Summary

Total Test Objects:	1
Successful:	0
Failed:	1
Not Executed:	0
Date:	2016-09-20
Time:	18:16:57+0530

Overall Test Object Results (including Coverage)



Selected Project Items

Test Object "CBD_UnitTest/SrlComInput/SrlComInput_Per1"

Used Test Environments

TI TMS 570 PLS UDE (Default)

Test Case Results for Each Test Object (without Coverage)



The table above shows each test object on the x axis and the number of test cases of the respective test object on the y axis. Each bar is divided into passed, not executed and failed test cases. The test case results do not take into account any coverage result (i.e. if all test cases of a test object are passed in this table but the coverage is failed, the overall test object result will be failed).

Statement (C0) Coverage: Total Statements for Each Test Object



The table above shows each test object on the x axis and the number of statements of the respective test object on the y axis. Each bar is divided into reached statements (i.e. statements that have been executed during the test) and unreached statements.

Branch (C1) Coverage: Total Branches for Each Test Object



The table above shows each test object on the x axis and the number of branches of the respective test object on the y axis. Each bar is divided into reached branches (i.e. branches that have been executed during the test) and unreached branches.

Decision Coverage: Total Decision Outcomes for Each Test Object



The table above shows test objects on the x axis and the number of possible outcomes of all decisions of the respective test object on the y axis. To achieve full DC coverage, each decision must evaluate to both true and false.

Each bar is divided into reached and unreached decision outcomes.

MC/DC Coverage: Total Condition Combinations for Each Test Object



The table above shows test objects on the x axis and the number of condition combinations of all decisions of the respective test object on the y axis. The number of condition combinations is based on the number of boolean conditions within each decision of the test object. To achieve full MC/DC coverage, each decision requires all contained atomic conditions to evaluate to both true and false independently of all other conditions. The cumulated number of rows within such tables of condition combinations is what is displayed in this table.

Each bar is divided into reached condition combinations (i.e. combinations of boolean condition values that have been executed during the test) and unreached condition combinations.

MCC Coverage: Total Condition Combinations for Each Test Object



The table above shows test objects on the x axis and the number of condition combinations of all decisions of the respective test object on the y axis. The number of condition combinations is based on the number of boolean conditions within each decision of the test object. To achieve full MCC coverage, each decision requires all contained atomic conditions to evaluate to all possible combinations of true and false values. The cumulated number of rows within such tables of condition combinations is what is displayed in this table.

Each bar is divided into reached condition combinations (i.e. combinations of boolean condition values that have been executed during the test) and unreached condition combinations.

Test Object List

The following table lists all test objects with their test case and coverage results. The cumulated results for modules, folders and test collections are also displayed, the indentation within the name column indicates the parent relationship of the elements.

Please note that only test objects are numbered within the first column. This number is referenced on the x axis within the overview charts for test case and coverage results available on previous pages (if included into the report).

No.	Name	C0	C1	DC	MC/DC	MCC	Test Cases	Result
	SrlComInput3	81.48 %	75.1 %	75.1 %	70.82 %	70.8 %	1 of 1 passed	
	CBD_UnitTest	81.48 %	75.1 %	75.1 %	70.82 %	70.8 %	1 of 1 passed	
	SrlComInput	81.48 %	75.1 %	75.1 %	70.82 %	70.8 %	1 of 1 passed	
1	SrlComInput_Per1	81.48 %	75.1 %	75.1 %	70.82 %	70.8 %	1 of 1 passed	

© Report created by TESSY V3.1.13, report template V2.0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Project	SrlComInput3
Module	SrlComInput
Test Object	SrlComInput_Per1

Instrumentation: Test Object Only

Statement (C0) Coverage	81.48 %
Decision Coverage	75.1 %
Branch (C1) Coverage	75.1 %
MCC Coverage	70.8 %
MC/DC Coverage	70.82 %

Statistics

Total Testcases	1
Successful	1
Failed	0
Not Executed	0

Module Properties

Project Root Directory	D:\Synergy_Work_Area\PSA_BMPV_SrlComInput_42
Configuration File	D:\Synergy_Work_Area\PSA_BMPV_SrlComInput_42\UnitTestEnv\config\TMS570_GCC_UDE_CCS4_Config.xml
Target Environment	TI TMS 570 PLS UDE (Default)
Kind of Test	Unit Test
Linker Options	
Source File(s)	
File	$(PROJECTROOT)\SrlComInput\src\Ap_SrlComInput.c
Compiler Options	-D_DATA_ACCESS= -Dconst= -Dstatic= -I$(PROJECTROOT)\SrlComInput\utp\contract\Ap_SrlComInput -I$(PROJECTROOT)\SrlComInput\utp\contract -I$(PROJECTROOT)\NxtrLib\include -I$(PROJECTROOT)\StdDef\include -I$(Compiler Install Path)\include

Comments/Description/Specification

Name	Text
Module 'SrlComInput'	**********Unit Test Information********** Name of Tester:Chandrakanth Sheegi Code File(s) Under Test:Ap_SrlComInput.c Code File(s) Version:42 Module Design Document:SrlComInput_MDD.docx Module Design Document Version:25 Data Dictionary Version:19 Unit Test Plan Version:4 Optimization Level:Level 2 Compiler (CodeGen) Version:TMS470_4.9.5 Model Type:Excel Macro Model Version:Nexteer EPS Unit Test Tool 2.7d/EPS Library 1.32 Total FLASH Used (Bytes):17220 Total RAM Used (Bytes):444 Total CALS Used (Bytes):310 Special Test Requirements:NA Test Date:9/20/2016 Comments: "Note 1: ""CBD_Sandbox_dbg.map"" file is embedded for reference. Note 2: In function 'SrlComInput_Per1', 100% MC/DC coverage can not be achieved at line no. 3812 and 3823, because the conditions """(SerialComAngleValid_Cnt_T_lgc == FALSE)==>False"" and """"(BusOffCh1_Cnt_T_lgc == TRUE)==>True"""" can not be satisfied at a time. Note 3: In function 'SrlComInput_Per1', Typecasting code is added for variable 'CONSANGLECPK_Cnt_T_u16' as it is mentioned in source code line no. 2836." **********

Attributes

Name	Value
Compiler Install Path	$(ProgramFiles)\Texas Instruments\ccsv4\tools\compiler\tms470_4.9.5
Float Precision	9
InitObjDir	$(PROJECTROOT)\UnitTestEnv\static_build_files\obj
InitSrcDir	$(PROJECTROOT)\UnitTestEnv\static_build_files\src
Linker File	$(PROJECTROOT)\UnitTestEnv\static_build_files\sys_link.cmd
Makefile Template	$(PROJECTROOT)\UnitTestEnv\config\Nexteer_ts_make_ude_ti_tms570_Ps.tpl
Target Install Path	$(ProgramFiles)\pls\UDE 4.4
Time Unit	cycles

© Report created by TESSY V3.1.13, report template V2.1

Attributes

Name	Value
Timer Enabled	false
Timer Prescale	0
Timer Resolution	1
UDE Config File	$(PROJECTROOT)\UnitTestEnv\config\TMS570_UDE_12PIN_JTAG.cfg
Workspace File	D:\Synergy_Work_Area\PSA_BMPV_SrlComInput_42\UnitTestEnv\config\UDE_TMS570_DEBUG.WSP

Test Case 1: Boundary Test ✔

Description

Vector Description:

TS 1.1ElecIntTimer_mS_M_u32[2]==>Pos
TS 1.2ElectronicIntegrationCmd_Cnt_M_lgc==>Min
TS 1.3ElectronicIntegrationCmd_Cnt_M_lgc==>Max
TS 1.4EffacDefaultDiagTimer_mS_M_u32[2]==>Min
TS 1.5EffacDefaultDiagTimer_mS_M_u32[2]==>Max
TS 1.6EffacDefaultDiagTimer_mS_M_u32[2]==>Pos
TS 1.7ClearDTCs_Cnt_M_lgc==>Min
TS 1.8ClearDTCs_Cnt_M_lgc==>Max
TS 1.9CMMNTCsEnabled_Cnt_M_lgc==>Min
TS 1.10CMMNTCsEnabled_Cnt_M_lgc==>Max
TS 1.11PrevISDYNCMM208MsgDLCError_Cnt_M_u08==>Min
TS 1.12PrevISDYNCMM208MsgDLCError_Cnt_M_u08==>Max
TS 1.13PrevISDYNCMM208MsgDLCError_Cnt_M_u08==>Pos
TS 1.14PrevISDYN2CMMMsgRxTime_MSec_M_u32==>Min
TS 1.15PrevISDYN2CMMMsgRxTime_MSec_M_u32==>Max
TS 1.16PrevISDYN2CMMMsgRxTime_MSec_M_u32==>Pos
TS 1.17ISDYN2CMMMsgTimeValidCount_Cnt_M_u16==>Min
TS 1.18ISDYN2CMMMsgTimeValidCount_Cnt_M_u16==>Max
TS 1.19ISDYN2CMMMsgTimeValidCount_Cnt_M_u16==>Pos
TS 1.20Msg348Valid_Cnt_M_lgc==>Min
TS 1.21Msg348Valid_Cnt_M_lgc==>Max
TS 1.22PrevISDYN2CMMMsgDLCError_Cnt_M_u08==>Min
TS 1.23PrevISDYN2CMMMsgDLCError_Cnt_M_u08==>Max
TS 1.24PrevISDYN2CMMMsgDLCError_Cnt_M_u08==>Pos
TS 1.25PrevEtatMT_Cnt_M_u08==>Min
TS 1.26PrevEtatMT_Cnt_M_u08==>Max
TS 1.27PrevEtatMT_Cnt_M_u08==>Pos
TS 1.28CountEtatMT_Cnt_M_u08==>Min
TS 1.29CountEtatMT_Cnt_M_u08==>Max
TS 1.30CountEtatMT_Cnt_M_u08==>Pos
TS 1.31k_EtatMTSigInvalidThresh_Cnt_u16==>Min
TS 1.32k_EtatMTSigInvalidThresh_Cnt_u16==>Max
TS 1.33k_EtatMTSigInvalidThresh_Cnt_u16==>Pos/Default
TS 1.34ValidEngineStatusCount_Cnt_M_u08==>Min
TS 1.35ValidEngineStatusCount_Cnt_M_u08==>Max
TS 1.36ValidEngineStatusCount_Cnt_M_u08==>Pos
TS 1.37EngOnDLCInvalidCount_Cnt_M_u08==>Min
TS 1.38EngOnDLCInvalidCount_Cnt_M_u08==>Max
TS 1.39EngOnDLCInvalidCount_Cnt_M_u08==>Pos
TS 1.40BSI3F2NTCsEnabled_Cnt_M_lgc==>Min
TS 1.41BSI3F2NTCsEnabled_Cnt_M_lgc==>Max
TS 1.42PrevISDATBSI3F2MsgRxTime_MSec_M_u32==>Min
TS 1.43PrevISDATBSI3F2MsgRxTime_MSec_M_u32==>Max
TS 1.44PrevISDATBSI3F2MsgRxTime_MSec_M_u32==>Pos
TS 1.45k_PowerCutVehSpdLowTimeout_mS_u16==>Min
TS 1.46k_PowerCutVehSpdLowTimeout_mS_u16==>Max
TS 1.47k_PowerCutVehSpdLowTimeout_mS_u16==>Pos/Default
TS 1.48k_PowerCutVehSpdHighThresh_Kph_f32==>Min
TS 1.49k_PowerCutVehSpdHighThresh_Kph_f32==>Max
TS 1.50k_PowerCutVehSpdHighThresh_Kph_f32==>Pos/Default
TS 1.51PrevISDATBSI3F2MsgDLCError_Cnt_M_u08==>Min
TS 1.52PrevISDATBSI3F2MsgDLCError_Cnt_M_u08==>Max
TS 1.53PrevISDATBSI3F2MsgDLCError_Cnt_M_u08==>Pos
TS 1.54k_JDD2010Selected_Cnt_lgc==>Min
TS 1.55k_JDD2010Selected_Cnt_lgc==>Max/Default
TS 1.56PrevISDATBSI412MsgRxTime_MSec_M_u32==>Min
TS 1.57PrevISDATBSI412MsgRxTime_MSec_M_u32==>Max
TS 1.58PrevISDATBSI412MsgRxTime_MSec_M_u32==>Pos
TS 1.59k_BSINodeTimeout_mS_u16==>Min
TS 1.60k_BSINodeTimeout_mS_u16==>Max
TS 1.61k_BSINodeTimeout_mS_u16==>Pos/Default
TS 1.62PrevISDATBSI412MsgDLCError_Cnt_M_u08==>Min
TS 1.63PrevISDATBSI412MsgDLCError_Cnt_M_u08==>Max
TS 1.64PrevISDATBSI412MsgDLCError_Cnt_M_u08==>Pos
TS 1.65k_ISDATBSI412MsgLenValidThresh_Cnt_u16==>Min
TS 1.66k_ISDATBSI412MsgLenValidThresh_Cnt_u16==>Max
TS 1.67k_ISDATBSI412MsgLenValidThresh_Cnt_u16==>Pos/Default
TS 1.68k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16==>Min
TS 1.69k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16==>Max
TS 1.70k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16==>Pos/Default
TS 1.71BSI432NTCsEnabled_Cnt_M_lgc==>Min
TS 1.72BSI432NTCsEnabled_Cnt_M_lgc==>Max
TS 1.73ISDATBSI432MsgTimeValidCount_Cnt_M_u16==>Min
TS 1.74ISDATBSI432MsgTimeValidCount_Cnt_M_u16==>Max
TS 1.75ISDATBSI432MsgTimeValidCount_Cnt_M_u16==>Pos
TS 1.76Msg432Valid_Cnt_M_lgc==>Min
TS 1.77Msg432Valid_Cnt_M_lgc==>Max
TS 1.78PrevISDATBSI432MsgDLCError_Cnt_M_u08==>Min
TS 1.79PrevISDATBSI432MsgDLCError_Cnt_M_u08==>Max
TS 1.80PrevISDATBSI432MsgDLCError_Cnt_M_u08==>Pos
TS 1.81k_ISDATBSI432MsgLenValidThresh_Cnt_u16==>Min
TS 1.82k_ISDATBSI432MsgLenValidThresh_Cnt_u16==>Max
TS 1.83k_ISDATBSI432MsgLenValidThresh_Cnt_u16==>Pos/Default
TS 1.84k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16==>Min
TS 1.85k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16==>Max
TS 1.86k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16==>Pos/default
TS 1.87PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32==>Min
TS 1.88PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32==>Max
TS 1.89PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32==>Pos
TS 1.90Msg552Valid_Cnt_M_lgc==>Min
TS 1.91Msg552Valid_Cnt_M_lgc==>Max
TS 1.92k_CptTemporelSigValidThresh_Cnt_u16==>Min
TS 1.93k_CptTemporelSigValidThresh_Cnt_u16==>Max
TS 1.94k_CptTemporelSigValidThresh_Cnt_u16==>Pos/default

TS 1.95k_ComputerRazGCTSigValidThresh_Cnt_u16==>Min
TS 1.96k_ComputerRazGCTSigValidThresh_Cnt_u16==>Max
TS 1.97k_ComputerRazGCTSigValidThresh_Cnt_u16==>Pos/Default
TS 1.98k_DefaultVehSpd_Kph_f32==>Min
TS 1.99k_DefaultVehSpd_Kph_f32==>Max
TS 1.100k_DefaultVehSpd_Kph_f32==>Pos/Default
TS 1.101VitesseVehiculeRoues_Kph_M_f32==>Min
TS 1.102VitesseVehiculeRoues_Kph_M_f32==>Max
TS 1.103VitesseVehiculeRoues_Kph_M_f32==>Pos
TS 1.104CPKOK_Cnt_M_lgc==>Min
TS 1.105CPKOK_Cnt_M_lgc==>Max
TS 1.106PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08==>Min
TS 1.107PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08==>Max
TS 1.108PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08==>Pos
TS 1.109PrevISDYNCMM388MsgDLCError_Cnt_M_u08==>Min
TS 1.110PrevISDYNCMM388MsgDLCError_Cnt_M_u08==>Max
TS 1.111PrevISDYNCMM388MsgDLCError_Cnt_M_u08==>Pos
TS 1.112k_PowerCutVehSpdLowThresh_Kph_f32==>Min
TS 1.113k_PowerCutVehSpdLowThresh_Kph_f32==>Max
TS 1.114k_PowerCutVehSpdLowThresh_Kph_f32==>Pos/Default
TS 1.115Rte_Pim_ElecIntData==>Min
TS 1.116Rte_Pim_ElecIntData==>Max
TS 1.117Rte_Pim_VVHTYPEData==>Min
TS 1.118Rte_Pim_VVHTYPEData==>Max
TS 1.119Rte_Pim_VVHTYPEData==>Pos
TS 1.120Rte_Call_NxtrDiagMgr_GetNTCFailed[48]==>Min
TS 1.121Rte_Call_NxtrDiagMgr_GetNTCFailed[48]==>Max
TS 1.122BSINodeAbsentTimer_mS_M_u32==>Min
TS 1.123BSINodeAbsentTimer_mS_M_u32==>Max
TS 1.124BSINodeAbsentTimer_mS_M_u32==>Pos
TS 1.125BSINodeAbsentFltAcc_Cnt_M_u16==>Min
TS 1.126BSINodeAbsentFltAcc_Cnt_M_u16==>Max
TS 1.127BSINodeAbsentFltAcc_Cnt_M_u16==>Pos
TS 1.128CAVNodeAbsentTimer_mS_M_u32==>Min
TS 1.129CAVNodeAbsentTimer_mS_M_u32==>Max
TS 1.130CAVNodeAbsentTimer_mS_M_u32==>Pos
TS 1.131CAVNodeAbsentFltAcc_Cnt_M_u16==>Min
TS 1.132CAVNodeAbsentFltAcc_Cnt_M_u16==>Max
TS 1.133CAVNodeAbsentFltAcc_Cnt_M_u16==>Pos
TS 1.134ESPNodeAbsentTimer_mS_M_u32==>Min
TS 1.135ESPNodeAbsentTimer_mS_M_u32==>Max
TS 1.136ESPNodeAbsentTimer_mS_M_u32==>Pos
TS 1.137ESPNodeAbsentFltAcc_Cnt_M_u16==>Min
TS 1.138ESPNodeAbsentFltAcc_Cnt_M_u16==>Max
TS 1.139ESPNodeAbsentFltAcc_Cnt_M_u16==>Pos
TS 1.140CMMNodeAbsentFltAcc_Cnt_M_u16==>Min
TS 1.141CMMNodeAbsentFltAcc_Cnt_M_u16==>Max
TS 1.142CMMNodeAbsentFltAcc_Cnt_M_u16==>Pos
TS 1.143CMMNodeAbsentTimer_mS_M_u32==>Min
TS 1.144CMMNodeAbsentTimer_mS_M_u32==>Max
TS 1.145CMMNodeAbsentTimer_mS_M_u32==>Pos
TS 1.146AASNodeAbsentTimer_mS_M_u32==>Min
TS 1.147AASNodeAbsentTimer_mS_M_u32==>Max
TS 1.148AASNodeAbsentTimer_mS_M_u32==>Pos
TS 1.149AASNodeAbsentFltAcc_Cnt_M_u16==>Min
TS 1.150AASNodeAbsentFltAcc_Cnt_M_u16==>Max
TS 1.151AASNodeAbsentFltAcc_Cnt_M_u16==>Pos
TS 1.152ISDYNVOLMsgTimer_mS_M_u32==>Min
TS 1.153ISDYNVOLMsgTimer_mS_M_u32==>Max
TS 1.154ISDYNVOLMsgTimer_mS_M_u32==>Pos
TS 1.155ISDYNVOLMsgTimeValidCount_Cnt_M_u16==>Min
TS 1.156ISDYNVOLMsgTimeValidCount_Cnt_M_u16==>Max
TS 1.157ISDYNVOLMsgTimeValidCount_Cnt_M_u16==>Pos
TS 1.158ISDYNVOLChkSumValidCount_Cnt_M_u16==>Min
TS 1.159ISDYNVOLChkSumValidCount_Cnt_M_u16==>Max
TS 1.160ISDYNVOLChkSumValidCount_Cnt_M_u16==>Pos
TS 1.161ISDYNVOLChkSumInvalidCount_Cnt_M_u16==>Min
TS 1.162ISDYNVOLChkSumInvalidCount_Cnt_M_u16==>Max
TS 1.163ISDYNVOLChkSumInvalidCount_Cnt_M_u16==>Pos
TS 1.164ISDYNVOLMsgCountValidCount_Cnt_M_u16==>Min
TS 1.165ISDYNVOLMsgCountValidCount_Cnt_M_u16==>Max
TS 1.166ISDYNVOLMsgCountValidCount_Cnt_M_u16==>Pos
TS 1.167ISDYNVOLMsgCountInvalidCount_Cnt_M_u16==>Min
TS 1.168ISDYNVOLMsgCountInvalidCount_Cnt_M_u16==>Max
TS 1.169ISDYNVOLMsgCountInvalidCount_Cnt_M_u16==>Pos
TS 1.170ANGLEVOLANTSigValidCount_Cnt_M_u16==>Min
TS 1.171ANGLEVOLANTSigValidCount_Cnt_M_u16==>Max
TS 1.172ANGLEVOLANTSigValidCount_Cnt_M_u16==>Pos
TS 1.173ANGLEVOLANTSigInvalidCount_Cnt_M_u16==>Min
TS 1.174ANGLEVOLANTSigInvalidCount_Cnt_M_u16==>Max
TS 1.175ANGLEVOLANTSigInvalidCount_Cnt_M_u16==>Pos
TS 1.176VITESSEROTVOLANTSigValidCount_Cnt_M_u16==>Min
TS 1.177VITESSEROTVOLANTSigValidCount_Cnt_M_u16==>Max
TS 1.178VITESSEROTVOLANTSigValidCount_Cnt_M_u16==>Pos
TS 1.179VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16==>Min
TS 1.180VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16==>Max
TS 1.181VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16==>Pos
TS 1.182ISDYNVOLMsgLenValidCount_Cnt_M_u16==>Min
TS 1.183ISDYNVOLMsgLenValidCount_Cnt_M_u16==>Max
TS 1.184ISDYNVOLMsgLenValidCount_Cnt_M_u16==>Pos
TS 1.185ISDYNVOLMsgLenInvalidCount_Cnt_M_u16==>Min
TS 1.186ISDYNVOLMsgLenInvalidCount_Cnt_M_u16==>Max
TS 1.187ISDYNVOLMsgLenInvalidCount_Cnt_M_u16==>Pos
TS 1.188ISDYNABRChkSumValidCount_Cnt_M_u16==>Min
TS 1.189ISDYNABRChkSumValidCount_Cnt_M_u16==>Max
TS 1.190ISDYNABRChkSumValidCount_Cnt_M_u16==>Pos

TS 1.191ISDYNABRChkSumInvalidCount_Cnt_M_u16==>Min
TS 1.192ISDYNABRChkSumInvalidCount_Cnt_M_u16==>Max
TS 1.193ISDYNABRChkSumInvalidCount_Cnt_M_u16==>Pos
TS 1.194ISDYNABRMsgCountValidCount_Cnt_M_u16==>Min
TS 1.195ISDYNABRMsgCountValidCount_Cnt_M_u16==>Max
TS 1.196ISDYNABRMsgCountValidCount_Cnt_M_u16==>Pos
TS 1.197ISDYNABRMsgCountInvalidCount_Cnt_M_u16==>Min
TS 1.198ISDYNABRMsgCountInvalidCount_Cnt_M_u16==>Max
TS 1.199ISDYNABRMsgCountInvalidCount_Cnt_M_u16==>Pos
TS 1.200VitesseVehiculeRouesSigValidCount_Cnt_M_u16==>Min
TS 1.201VitesseVehiculeRouesSigValidCount_Cnt_M_u16==>Max
TS 1.202VitesseVehiculeRouesSigValidCount_Cnt_M_u16==>Pos
TS 1.203VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16==>Min
TS 1.204VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16==>Max
TS 1.205VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16==>Pos
TS 1.206ISDYNABRMsgLenValidCount_Cnt_M_u16==>Min
TS 1.207ISDYNABRMsgLenValidCount_Cnt_M_u16==>Max
TS 1.208ISDYNABRMsgLenValidCount_Cnt_M_u16==>Pos
TS 1.209ISDYNABRMsgLenInvalidCount_Cnt_M_u16==>Min
TS 1.210ISDYNABRMsgLenInvalidCount_Cnt_M_u16==>Max
TS 1.211ISDYNABRMsgLenInvalidCount_Cnt_M_u16==>Pos
TS 1.212ISDYNCMM388MsgTimer_mS_M_u32==>Min
TS 1.213ISDYNCMM388MsgTimer_mS_M_u32==>Max
TS 1.214ISDYNCMM388MsgTimer_mS_M_u32==>Pos
TS 1.215ISDYNCMM388MsgTimeValidCount_Cnt_M_u16==>Min
TS 1.216ISDYNCMM388MsgTimeValidCount_Cnt_M_u16==>Max
TS 1.217ISDYNCMM388MsgTimeValidCount_Cnt_M_u16==>Pos
TS 1.218VitesseVehicleBVSigValidCount_Cnt_M_u16==>Min
TS 1.219VitesseVehicleBVSigValidCount_Cnt_M_u16==>Max
TS 1.220VitesseVehicleBVSigValidCount_Cnt_M_u16==>Pos
TS 1.221VitesseVehicleBVSigInvalidCount_Cnt_M_u16==>Min
TS 1.222VitesseVehicleBVSigInvalidCount_Cnt_M_u16==>Max
TS 1.223VitesseVehicleBVSigInvalidCount_Cnt_M_u16==>Pos
TS 1.224VitesseVehicleBVRampValidCount_Cnt_M_u16==>Min
TS 1.225VitesseVehicleBVRampValidCount_Cnt_M_u16==>Max
TS 1.226VitesseVehicleBVRampValidCount_Cnt_M_u16==>Pos
TS 1.227VitesseVehicleBVRampInvalidCount_Cnt_M_u16==>Min
TS 1.228VitesseVehicleBVRampInvalidCount_Cnt_M_u16==>Max
TS 1.229VitesseVehicleBVRampInvalidCount_Cnt_M_u16==>Pos
TS 1.230ISDYNCMM388MsgLenValidCount_Cnt_M_u16==>Min
TS 1.231ISDYNCMM388MsgLenValidCount_Cnt_M_u16==>Max
TS 1.232ISDYNCMM388MsgLenValidCount_Cnt_M_u16==>Pos
TS 1.233ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16==>Min
TS 1.234ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16==>Max
TS 1.235ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16==>Pos
TS 1.236ISDYNAASMsgTimer_mS_M_u32==>Min
TS 1.237ISDYNAASMsgTimer_mS_M_u32==>Max
TS 1.238ISDYNAASMsgTimer_mS_M_u32==>Pos
TS 1.239ISDYNAASMsgTimeValidCount_Cnt_M_u16==>Min
TS 1.240ISDYNAASMsgTimeValidCount_Cnt_M_u16==>Max
TS 1.241ISDYNAASMsgTimeValidCount_Cnt_M_u16==>Pos
TS 1.242ISDYNAASChkSumValidCount_Cnt_M_u16==>Min
TS 1.243ISDYNAASChkSumValidCount_Cnt_M_u16==>Max
TS 1.244ISDYNAASChkSumValidCount_Cnt_M_u16==>Pos
TS 1.245ISDYNAASChkSumInvalidCount_Cnt_M_u16==>Min
TS 1.246ISDYNAASChkSumInvalidCount_Cnt_M_u16==>Max
TS 1.247ISDYNAASChkSumInvalidCount_Cnt_M_u16==>Pos
TS 1.248ISDYNAASMsgCountValidCount_Cnt_M_u16==>Min
TS 1.249ISDYNAASMsgCountValidCount_Cnt_M_u16==>Max
TS 1.250ISDYNAASMsgCountValidCount_Cnt_M_u16==>Pos
TS 1.251ISDYNAASMsgCountInvalidCount_Cnt_M_u16==>Min
TS 1.252ISDYNAASMsgCountInvalidCount_Cnt_M_u16==>Max
TS 1.253ISDYNAASMsgCountInvalidCount_Cnt_M_u16==>Pos
TS 1.254CONSANGLECPKSigValidCount_Cnt_M_u16==>Min
TS 1.255CONSANGLECPKSigValidCount_Cnt_M_u16==>Max
TS 1.256CONSANGLECPKSigValidCount_Cnt_M_u16==>Pos
TS 1.257CONSANGLECPKSigInvalidCount_Cnt_M_u16==>Min
TS 1.258CONSANGLECPKSigInvalidCount_Cnt_M_u16==>Max
TS 1.259CONSANGLECPKSigInvalidCount_Cnt_M_u16==>Pos
TS 1.260DMDFCTCPKSigValidCount_Cnt_M_u16==>Min
TS 1.261DMDFCTCPKSigValidCount_Cnt_M_u16==>Max
TS 1.262DMDFCTCPKSigValidCount_Cnt_M_u16==>Pos
TS 1.263DMDFCTCPKSigInvalidCount_Cnt_M_u16==>Min
TS 1.264DMDFCTCPKSigInvalidCount_Cnt_M_u16==>Max
TS 1.265DMDFCTCPKSigInvalidCount_Cnt_M_u16==>Pos
TS 1.266DMDRELAXECPKSigValidCount_Cnt_M_u16==>Min
TS 1.267DMDRELAXECPKSigValidCount_Cnt_M_u16==>Max
TS 1.268DMDRELAXECPKSigValidCount_Cnt_M_u16==>Pos
TS 1.269DMDRELAXECPKSigInvalidCount_Cnt_M_u16==>Min
TS 1.270DMDRELAXECPKSigInvalidCount_Cnt_M_u16==>Max
TS 1.271DMDRELAXECPKSigInvalidCount_Cnt_M_u16==>Pos
TS 1.272ISDYNAASMsgLenValidCount_Cnt_M_u16==>Min
TS 1.273ISDYNAASMsgLenValidCount_Cnt_M_u16==>Max
TS 1.274ISDYNAASMsgLenValidCount_Cnt_M_u16==>Pos
TS 1.275ISDYNAASMsgLenInvalidCount_Cnt_M_u16==>Min
TS 1.276ISDYNAASMsgLenInvalidCount_Cnt_M_u16==>Max
TS 1.277ISDYNAASMsgLenInvalidCount_Cnt_M_u16==>Pos
TS 1.278ISDYNCMM208MsgTimer_mS_M_u32==>Min
TS 1.279ISDYNCMM208MsgTimer_mS_M_u32==>Max
TS 1.280ISDYNCMM208MsgTimer_mS_M_u32==>Pos
TS 1.281ISDYNCMM208MsgTimeValidCount_Cnt_M_u16==>Min
TS 1.282ISDYNCMM208MsgTimeValidCount_Cnt_M_u16==>Max
TS 1.283ISDYNCMM208MsgTimeValidCount_Cnt_M_u16==>Pos
TS 1.284ISDYNCMM208MsgLenValidCount_Cnt_M_u16==>Min
TS 1.285ISDYNCMM208MsgLenValidCount_Cnt_M_u16==>Max
TS 1.286ISDYNCMM208MsgLenValidCount_Cnt_M_u16==>Pos

TS 1.287ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16==>Min
TS 1.288ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16==>Max
TS 1.289ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16==>Pos
TS 1.290ISDYN2CMMMsgTimer_mS_M_u32==>Min
TS 1.291ISDYN2CMMMsgTimer_mS_M_u32==>Max
TS 1.292ISDYN2CMMMsgTimer_mS_M_u32==>Pos
TS 1.293EtatMTSigValidCount_Cnt_M_u16==>Min
TS 1.294EtatMTSigValidCount_Cnt_M_u16==>Max
TS 1.295EtatMTSigValidCount_Cnt_M_u16==>Pos
TS 1.296EtatMTSigInvalidCount_Cnt_M_u16==>Min
TS 1.297EtatMTSigInvalidCount_Cnt_M_u16==>Max
TS 1.298EtatMTSigInvalidCount_Cnt_M_u16==>Pos
TS 1.299ISDYN2CMMMsgLenValidCount_Cnt_M_u16==>Min
TS 1.300ISDYN2CMMMsgLenValidCount_Cnt_M_u16==>Max
TS 1.301ISDYN2CMMMsgLenValidCount_Cnt_M_u16==>Pos
TS 1.302ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16==>Min
TS 1.303ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16==>Max
TS 1.304ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16==>Pos
TS 1.305ISDATBSI3F2MsgTimer_mS_M_u32==>Min
TS 1.306ISDATBSI3F2MsgTimer_mS_M_u32==>Max
TS 1.307ISDATBSI3F2MsgTimer_mS_M_u32==>Pos
TS 1.308ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16==>Min
TS 1.309ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16==>Max
TS 1.310ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16==>Pos
TS 1.311ISDATBSI3F2MsgLenValidCount_Cnt_M_u16==>Min
TS 1.312ISDATBSI3F2MsgLenValidCount_Cnt_M_u16==>Max
TS 1.313ISDATBSI3F2MsgLenValidCount_Cnt_M_u16==>Pos
TS 1.314ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16==>Min
TS 1.315ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16==>Max
TS 1.316ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16==>Pos
TS 1.317ISDATBSI412MsgTimer_mS_M_u32==>Min
TS 1.318ISDATBSI412MsgTimer_mS_M_u32==>Max
TS 1.319ISDATBSI412MsgTimer_mS_M_u32==>Pos
TS 1.320ISDATBSI412MsgTimeValidCount_Cnt_M_u16==>Min
TS 1.321ISDATBSI412MsgTimeValidCount_Cnt_M_u16==>Max
TS 1.322ISDATBSI412MsgTimeValidCount_Cnt_M_u16==>Pos
TS 1.323ISDATBSI412MsgLenValidCount_Cnt_M_u16==>Min
TS 1.324ISDATBSI412MsgLenValidCount_Cnt_M_u16==>Max
TS 1.325ISDATBSI412MsgLenValidCount_Cnt_M_u16==>Pos
TS 1.326ISDATBSI412MsgLenInvalidCount_Cnt_M_u16==>Min
TS 1.327ISDATBSI412MsgLenInvalidCount_Cnt_M_u16==>Max
TS 1.328ISDATBSI412MsgLenInvalidCount_Cnt_M_u16==>Pos
TS 1.329ISDATBSI432MsgLenValidCount_Cnt_M_u16==>Min
TS 1.330ISDATBSI432MsgLenValidCount_Cnt_M_u16==>Max
TS 1.331ISDATBSI432MsgLenValidCount_Cnt_M_u16==>Pos
TS 1.332ISDATBSI432MsgLenInvalidCount_Cnt_M_u16==>Min
TS 1.333ISDATBSI432MsgLenInvalidCount_Cnt_M_u16==>Max
TS 1.334ISDATBSI432MsgLenInvalidCount_Cnt_M_u16==>Pos
TS 1.335ISDAT4V2BSI552MsgTimer_mS_M_u32==>Min
TS 1.336ISDAT4V2BSI552MsgTimer_mS_M_u32==>Max
TS 1.337ISDAT4V2BSI552MsgTimer_mS_M_u32==>Pos
TS 1.338CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32==>Min
TS 1.339CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32==>Max
TS 1.340CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32==>Pos
TS 1.341CompteurTemporelVehiculeSigValidCount_Cnt_M_u16==>Min
TS 1.342CompteurTemporelVehiculeSigValidCount_Cnt_M_u16==>Max
TS 1.343CompteurTemporelVehiculeSigValidCount_Cnt_M_u16==>Pos
TS 1.344ComputerRazGCTSigInvalidTimer_mS_M_u32==>Min
TS 1.345ComputerRazGCTSigInvalidTimer_mS_M_u32==>Max
TS 1.346ComputerRazGCTSigInvalidTimer_mS_M_u32==>Pos
TS 1.347ComputerRazGCTSigValidCount_Cnt_M_u16==>Min
TS 1.348ComputerRazGCTSigValidCount_Cnt_M_u16==>Max
TS 1.349ComputerRazGCTSigValidCount_Cnt_M_u16==>Pos
TS 1.350ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16==>Min
TS 1.351ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16==>Max
TS 1.352ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16==>Pos
TS 1.353ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16==>Min
TS 1.354ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16==>Max
TS 1.355ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16==>Pos
TS 1.356ISDYNABRMsgCount_Cnt_M_u08==>Min
TS 1.357ISDYNABRMsgCount_Cnt_M_u08==>Max
TS 1.358ISDYNABRMsgCount_Cnt_M_u08==>Pos
TS 1.359DMDFCTCPK_Cnt_M_u08==>Min
TS 1.360DMDFCTCPK_Cnt_M_u08==>Max
TS 1.361DMDFCTCPK_Cnt_M_u08==>Pos
TS 1.362ResetTimers_Cnt_M_lgc==>Min
TS 1.363ResetTimers_Cnt_M_lgc==>Max
TS 1.364ManVehSpd_Kph_M_f32==>Min
TS 1.365ManVehSpd_Kph_M_f32==>Max
TS 1.366ManVehSpd_Kph_M_f32==>Pos
TS 1.367k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16==>Min
TS 1.368k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16==>Max
TS 1.369k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16==>Pos/default
TS 1.370EngOn_Cnt_M_lgc==>Min
TS 1.371EngOn_Cnt_M_lgc==>Max
TS 1.372ISDYNABRMsgTimeValidCount_Cnt_M_u16==>Min
TS 1.373ISDYNABRMsgTimeValidCount_Cnt_M_u16==>Max
TS 1.374ISDYNABRMsgTimeValidCount_Cnt_M_u16==>Pos
TS 1.375AngleVolantInvalidCount_Cnt_M_u16==>Min
TS 1.376AngleVolantInvalidCount_Cnt_M_u16==>Max
TS 1.377AngleVolantInvalidCount_Cnt_M_u16==>Pos
TS 1.378k_AngleVolantInvalidThresh_Cnt_u16==>Min
TS 1.379k_AngleVolantInvalidThresh_Cnt_u16==>Max
TS 1.380k_AngleVolantInvalidThresh_Cnt_u16==>Pos/Default
TS 1.381DMDRELAXECPK_Cnt_M_u08==>Min
TS 1.382DMDRELAXECPK_Cnt_M_u08==>Max

TS 1.383DMDRELAXECPK_Cnt_M_u08==>Pos
TS 1.384AnneeEcoule_Cnt_u08==>Min
TS 1.385AnneeEcoule_Cnt_u08==>Max
TS 1.386AnneeEcoule_Cnt_u08==>Pos
TS 1.387BusOff_Cnt_lgc==>Min
TS 1.388BusOff_Cnt_lgc==>Max
TS 1.389JourEcoule_Cnt_u16==>Min
TS 1.390JourEcoule_Cnt_u16==>Max
TS 1.391JourEcoule_Cnt_u16==>Pos
TS 1.392LXASelected_Cnt_lgc==>Min
TS 1.393LXASelected_Cnt_lgc==>Max
TS 1.394SecondeEcoulee_Cnt_u32==>Min
TS 1.395SecondeEcoulee_Cnt_u32==>Max
TS 1.396SecondeEcoulee_Cnt_u32==>Pos
TS 1.397AngleVolantValidCount_Cnt_M_u16==>Min
TS 1.398AngleVolantValidCount_Cnt_M_u16==>Max
TS 1.399AngleVolantValidCount_Cnt_M_u16==>Pos
TS 1.400k_AngleVolantValidThresh_Cnt_u16==>Min
TS 1.401k_AngleVolantValidThresh_Cnt_u16==>Max
TS 1.402k_AngleVolantValidThresh_Cnt_u16==>Pos/Default
TS 1.403CPKVehicleSpeedInvalidCount_Cnt_M_u16==>Min
TS 1.404CPKVehicleSpeedInvalidCount_Cnt_M_u16==>Max
TS 1.405CPKVehicleSpeedInvalidCount_Cnt_M_u16==>Pos
TS 1.406k_CPKVehicleSpeedInvalidThresh_Cnt_u16==>Min
TS 1.407k_CPKVehicleSpeedInvalidThresh_Cnt_u16==>Max
TS 1.408k_CPKVehicleSpeedInvalidThresh_Cnt_u16==>Pos/Default
TS 1.409k_VitesseVehicleBVSpeedPassThresh_kph_f32==>Min
TS 1.410k_VitesseVehicleBVSpeedPassThresh_kph_f32==>Max
TS 1.411k_VitesseVehicleBVSpeedPassThresh_kph_f32==>Pos/default
TS 1.412k_CPKVehicleSpeedValidThresh_Cnt_u16==>Min
TS 1.413k_CPKVehicleSpeedValidThresh_Cnt_u16==>Max
TS 1.414k_CPKVehicleSpeedValidThresh_Cnt_u16==>Pos/Default
TS 1.415CityParkInputInvalidCount_Cnt_M_u16==>Min
TS 1.416CityParkInputInvalidCount_Cnt_M_u16==>Max
TS 1.417CityParkInputInvalidCount_Cnt_M_u16==>Pos
TS 1.418k_CityParkInputInvalidThresh_Cnt_u16==>Min
TS 1.419k_CityParkInputInvalidThresh_Cnt_u16==>Max
TS 1.420k_CityParkInputInvalidThresh_Cnt_u16==>Pos/Default
TS 1.421k_CONSANGLECPKMin_HwDeg_f32==>Min
TS 1.422k_CONSANGLECPKMin_HwDeg_f32==>Max
TS 1.423k_CONSANGLECPKMin_HwDeg_f32==>Pos
TS 1.424k_CONSANGLECPKMin_HwDeg_f32==>Zero
TS 1.425k_CONSANGLECPKMin_HwDeg_f32==>Neg/Default
TS 1.426k_CONSANGLECPKMax_HwDeg_f32==>Min
TS 1.427k_CONSANGLECPKMax_HwDeg_f32==>Max
TS 1.428k_CONSANGLECPKMax_HwDeg_f32==>Pos
TS 1.429PrevDMDRELAXECPK_Cnt_M_u08==>Min
TS 1.430PrevDMDRELAXECPK_Cnt_M_u08==>Max
TS 1.431PrevDMDRELAXECPK_Cnt_M_u08==>Pos
TS 1.432DMDRelaxeConsistentCount_Cnt_M_u16==>Min
TS 1.433DMDRelaxeConsistentCount_Cnt_M_u16==>Max
TS 1.434DMDRelaxeConsistentCount_Cnt_M_u16==>Pos
TS 1.435PrevDMDFCTCPK_Cnt_M_u08==>Min
TS 1.436PrevDMDFCTCPK_Cnt_M_u08==>Max
TS 1.437PrevDMDFCTCPK_Cnt_M_u08==>Pos
TS 1.438CityParkInputConsistentCount_Cnt_M_u16==>Min
TS 1.439CityParkInputConsistentCount_Cnt_M_u16==>Max
TS 1.440CityParkInputConsistentCount_Cnt_M_u16==>Pos
TS 1.441k_DMDFCTCPKValidCount_Cnt_u16==>Min
TS 1.442k_DMDFCTCPKValidCount_Cnt_u16==>Max
TS 1.443k_DMDFCTCPKValidCount_Cnt_u16==>Pos/Default
TS 1.444VehicleSpeedValid_Cnt_M_lgc==>Min
TS 1.445VehicleSpeedValid_Cnt_M_lgc==>Max
TS 1.446BSI412NTCsEnabled_Cnt_M_lgc==>Min
TS 1.447BSI412NTCsEnabled_Cnt_M_lgc==>Max
TS 1.448BSI552NTCsEnabled_Cnt_M_lgc==>Min
TS 1.449BSI552NTCsEnabled_Cnt_M_lgc==>Max
TS 1.450DateInvalidTimer_mS_M_u32==>Min
TS 1.451DateInvalidTimer_mS_M_u32==>Max
TS 1.452DateInvalidTimer_mS_M_u32==>Pos
TS 1.453DateValidCount_Cnt_M_u16==>Min
TS 1.454DateValidCount_Cnt_M_u16==>Max
TS 1.455DateValidCount_Cnt_M_u16==>Pos
TS 1.456StartupTimeCalculated_Cnt_M_lgc==>Min
TS 1.457StartupTimeCalculated_Cnt_M_lgc==>Max
TS 1.458Rte_Pim_ShutdownTimeData.Valid_Cnt_lgc==>Min
TS 1.459Rte_Pim_ShutdownTimeData.Valid_Cnt_lgc==>Max
TS 1.460Rte_Pim_ShutdownTimeData.Time_Sec_u32==>Min
TS 1.461Rte_Pim_ShutdownTimeData.Time_Sec_u32==>Max
TS 1.462Rte_Pim_ShutdownTimeData.Time_Sec_u32==>Pos
TS 1.463PrevSrlComVehSpd_Kph_M_f32==>Min
TS 1.464PrevSrlComVehSpd_Kph_M_f32==>Max
TS 1.465PrevSrlComVehSpd_Kph_M_f32==>Pos
TS 1.466VehSpdSync_Cnt_M_lgc==>Min
TS 1.467VehSpdSync_Cnt_M_lgc==>Max
TS 1.468APARequest_Cnt_M_lgc==>Min
TS 1.469APARequest_Cnt_M_lgc==>Max
TS 1.470ApaRelaxReq_Cnt_M_lgc==>Min
TS 1.471ApaRelaxReq_Cnt_M_lgc==>Max
TS 1.472VehTimeValid_Cnt_M_lgc==>Min
TS 1.473VehTimeValid_Cnt_M_lgc==>Max
TS 1.474AngleVolantValid_Cnt_M_lgc==>Min
TS 1.475AngleVolantValid_Cnt_M_lgc==>Max
TS 1.476ISDYNABRMsgTimer_mS_M_u32==>Min
TS 1.477ISDYNABRMsgTimer_mS_M_u32==>Max
TS 1.478ISDYNABRMsgTimer_mS_M_u32==>Pos

TS 1.479CityParkInputMsgTimer_mS_M_u32==>Min
TS 1.480CityParkInputMsgTimer_mS_M_u32==>Max
TS 1.481CityParkInputMsgTimer_mS_M_u32==>Pos
TS 1.482ISDATBSI432MsgTimer_mS_M_u32==>Min
TS 1.483ISDATBSI432MsgTimer_mS_M_u32==>Max
TS 1.484ISDATBSI432MsgTimer_mS_M_u32==>Pos
TS 1.485ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16==>Min
TS 1.486ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16==>Max
TS 1.487ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16==>Pos
TS 1.488IgnTimeOff_Sec_M_u32==>Min
TS 1.489IgnTimeOff_Sec_M_u32==>Max
TS 1.490IgnTimeOff_Sec_M_u32==>Pos
TS 1.491Rte_Mode_SystemState_Mode==>Min
TS 1.492Rte_Mode_SystemState_Mode==>Max
TS 1.493Rte_Mode_SystemState_Mode==>Pos
TS 1.494Rte_Call_EpsEn_OP_GET==>Min
TS 1.495Rte_Call_EpsEn_OP_GET==>Max
TS 1.496Rte_Call_SystemTime_GetSystemTime_mS_u32==>Min
TS 1.497Rte_Call_SystemTime_GetSystemTime_mS_u32==>Max
TS 1.498Rte_Call_SystemTime_GetSystemTime_mS_u32==>Pos
TS 1.499Rte_Call_SystemTime_DtrmnElapsedTime_mS_u16==>Min
TS 1.500Rte_Call_SystemTime_DtrmnElapsedTime_mS_u16==>Max
TS 1.501Rte_Call_SystemTime_DtrmnElapsedTime_mS_u16==>Pos
TS 1.502NtWrapC_Dem_ClearDTC==>Min
TS 1.503NtWrapC_Dem_ClearDTC==>Max
TS 1.504NtWrapC_Dem_ClearDTC==>Pos

Test Step 1.1 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2938399488
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	57740
AASNodeAbsentTimer_mS_M_u32	2625641216
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	34435
ANGLEVOLANTSigValidCount_Cnt_M_u16	34134
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	45
AngleVolantMsgTimer_mS_M_u32	2938399488
AngleVolantValidCount_Cnt_M_u16	12537
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	109239040
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1983077120
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3112667904
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	855984896
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	48534
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1124731648
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	3708
CAVNodeAbsentTimer_mS_M_u32	3297196800
CDD_SrlComVehSpd_Kph_G_f32	64.7340012
CMM388NTCEnableTimer_mS_M_u32	427850496
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3885316864
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	28786
CMMNodeAbsentTimer_mS_M_u32	4168567552
CONSANGLECPKSigInvalidCount_Cnt_M_u16	65474
CONSANGLECPKSigValidCount_Cnt_M_u16	5157
CONSANGLECPK_Cnt_M_u16	45868
CONSANGLECPK_HwDeg_M_f32	-663.656677
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	45868
CPKVehicleSpeedMsgTimer_mS_M_u32	2043636480
CPKVehicleSpeedValidCount_Cnt_M_u16	35918
CityParkInputConsistentCount_Cnt_M_u16	9901
CityParkInputInvalidCount_Cnt_M_u16	37819
CityParkInputMsgTimer_mS_M_u32	450598912
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4281604864
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	9536
ComputerRazGCTSigInvalidTimer_mS_M_u32	4048665344
ComputerRazGCTSigValidCount_Cnt_M_u16	26726

Name	Input Value
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	43527
DMDFCTCPKSigValidCount_Cnt_M_u16	34146
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	9309
DMDRELAXECPKSigValidCount_Cnt_M_u16	45744
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	19299
DateInvalidTimer_mS_M_u32	1983077120
DiagMuxOnAbsentTimer_mS_M_u32	2273913600
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	855984896
ESPNTCEnableTimer_mS_M_u32	3566541568
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	49009
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	3
EffacDefaultDiagTimer_mS_M_u32[1]	1145471744
ElecIntCount_Cnt_M_u08	2
ElecIntTimer_mS_M_u32[0]	180
ElecIntTimer_mS_M_u32[1]	1145471744
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3133410048
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	4644
EtatMTSigValidCount_Cnt_M_u16	20051
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	43932
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	53119
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	27248
ISDAT4V2BSI552MsgTimer_mS_M_u32	3123399424
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	20317
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	24180
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	20051
ISDATBSI3F2MsgTimer_mS_M_u32	3551472384
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	16168
ISDATBSI412MsgLenValidCount_Cnt_M_u16	52272
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	4644
ISDATBSI412MsgTimer_mS_M_u32	4182403840
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	53542
ISDATBSI432MsgLenValidCount_Cnt_M_u16	65317
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	33841
ISDATDIRASentFltAcc_Cnt_M_u16	10549
ISDATDIRASentTimer_mS_M_u32	2043636480
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	61394
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	12537
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	30874
ISDYN2CMMMsgTimer_mS_M_u32	3766950656
ISDYNAASChkSumInvalidCount_Cnt_M_u16	31590
ISDYNAASChkSumValidCount_Cnt_M_u16	50650
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	64908
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	38595
ISDYNAASMsgLenValidCount_Cnt_M_u16	50190
ISDYNAASMsgTimeValidCount_Cnt_M_u16	31590
ISDYNAASMsgTimer_mS_M_u32	2563537664
ISDYNABRChkSumInvalidCount_Cnt_M_u16	41700
ISDYNABRChkSumValidCount_Cnt_M_u16	671
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	44153
ISDYNABRMsgCountValidCount_Cnt_M_u16	44845
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	12245
ISDYNABRMsgLenValidCount_Cnt_M_u16	15480
ISDYNABRMsgTimeValidCount_Cnt_M_u16	45868
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	553
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	991
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	20051
ISDYNCMM208MsgTimer_mS_M_u32	3782990592
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2063
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1097
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	52767
ISDYNCMM388MsgTimer_mS_M_u32	1832254208
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	25576

Name	Input Value
ISDYNVOLChkSumValidCount_Cnt_M_u16	26827
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	19757
ISDYNVOLMsgCountValidCount_Cnt_M_u16	22792
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	35166
ISDYNVOLMsgLenValidCount_Cnt_M_u16	12833
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28786
ISDYNVOLMsgTimer_mS_M_u32	2359147264
IgnOnTimer_mS_M_u32	3857316608
IgnTimeOff_Sec_M_u32	1203662338
ManVehSpd_Kph_M_f32	538.958923
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	64
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	185
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2149395200
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	99
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	519736064
PrevISDATBSI412MsgDLCError_Cnt_M_u08	216
PrevISDATBSI412MsgRxTime_MSec_M_u32	2281454336
PrevISDATBSI432MsgDLCError_Cnt_M_u08	162
PrevISDATBSI432MsgRxTime_MSec_M_u32	3145276160
PrevISDATDIRAMsgTxTime_MSec_M_u32	2818587392
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	150
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3909667584
PrevISDYNAASMsgDLCError_Cnt_M_u08	182
PrevISDYNAASMsgRxTime_MSec_M_u32	2974006016
PrevISDYNABRMsgDLCError_Cnt_M_u08	7
PrevISDYNABRMsgRxTime_MSec_M_u32	4085381888
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	179
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1740421888
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	42
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3682605824
PrevISDYNVOLMsgDLCError_Cnt_M_u08	247
PrevISDYNVOLMsgRxTime_MSec_M_u32	3979164416
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1383099136
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	120.7826
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	14313
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	5556
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	25942
VitesseVehicleBVRampValidCount_Cnt_M_u16	27361
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	21360
VitesseVehicleBVSigValidCount_Cnt_M_u16	6659
VitesseVehicleBV_Kph_M_f32	61.6217995
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	52767
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	24522
VitesseVehiculeRoues_Kph_M_f32	528.377502
k_AASNTCEnableTimeout_mS_u16	33047
k_AASNodeAbsentDiag_Cnt_str.Threshold	40928
k_AASNodeAbsentDiag_Cnt_str.PStep	341
k_AASNodeAbsentDiag_Cnt_str.NStep	5981

Name	Input Value
k_AASNodeAbsentTimeout_mS_u16	55000
k_AASNodeTimeout_mS_u16	54452
k_ABSNodeTimeout_mS_u16	9152
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	41285
k_ANGLEVOLANTSigValidThresh_Cnt_u16	63620
k_AngleVolantInvalidThresh_Cnt_u16	46847
k_AngleVolantValidThresh_Cnt_u16	37819
k_BSI552MsgTimeout_mS_u16	38405
k_BSINTCEnableTimeout_mS_u16	3774
k_BSINodeAbsentDiag_Cnt_str.Threshold	19532
k_BSINodeAbsentDiag_Cnt_str.PStep	37239
k_BSINodeAbsentDiag_Cnt_str.NStep	11324
k_BSINodeAbsentTimeout_mS_u16	38853
k_BSINodeTimeout_mS_u16	33841
k_BattOvHi_Volt_f32	18.3533993
k_BattOvLo_Volt_f32	4.81430006
k_BattUvHi_Volt_f32	1.62870002
k_BattUvLo_Volt_f32	12.1033001
k_CAVNTCEnableTimeout_mS_u16	17017
k_CAVNodeAbsentDiag_Cnt_str.Threshold	30972
k_CAVNodeAbsentDiag_Cnt_str.PStep	28340
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	18082
k_CAVNodeTimeout_mS_u16	55054
k_CMM388MsgTimeout_mS_u16	57484
k_CMM388NTCEnableTimeout_mS_u16	56536
k_CMMNTCEnableTimeout_mS_u16	6389
k_CMMNodeAbsentDiag_Cnt_str.Threshold	53126
k_CMMNodeAbsentDiag_Cnt_str.PStep	17418
k_CMMNodeAbsentDiag_Cnt_str.NStep	35106
k_CMMNodeAbsentTimeout_mS_u16	59926
k_CONSANGLECPKMax_HwDeg_f32	591.945923
k_CONSANGLECPKMin_HwDeg_f32	-428.455811
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	19743
k_CONSANGLECPKSigValidThresh_Cnt_u16	7882
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	20674
k_CPKVehicleSpeedValidThresh_Cnt_u16	28719
k_CityParkInputInvalidThresh_Cnt_u16	62834
k_CityParkInputValidThresh_Cnt_u16	9901
k_ComputerRazGCTSigValidThresh_Cnt_u16	63563
k_CptTemporelSigValidThresh_Cnt_u16	32226
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	11989
k_DMDFCTCPKSigValidThresh_Cnt_u16	31608
k_DMDFCTCPKValidCount_Cnt_u16	29950
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	30874
k_DMDRELAXECPKSigValidThresh_Cnt_u16	11317
k_DMDRelaxeConsistentThresh_Cnt_u16	14915
k_DateValidThresh_Cnt_u16	27248
k_DefaultVehSpd_Kph_f32	81.6174011
k_DiagMuxOnAbsentTimeout_mS_u16	55514
k_EMNodeTimeout_mS_u16	44099
k_ESPNTCEnableTimeout_mS_u16	4040
k_ESPNodeAbsentDiag_Cnt_str.Threshold	37135
k_ESPNodeAbsentDiag_Cnt_str.PStep	31203
k_ESPNodeAbsentDiag_Cnt_str.NStep	32587
k_ESPNodeAbsentTimeout_mS_u16	54398
k_EtatMTSigInvalidThresh_Cnt_u16	3263
k_EtatMTSigValidThresh_Cnt_u16	43706
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	32041
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	3000
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	28186
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	50078
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	12661
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	56796
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	56551
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	2470
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	29146
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	45760
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	60007
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	41448
k_ISDATDIRASentDiag_Cnt_str.Threshold	13337
k_ISDATDIRASentDiag_Cnt_str.PStep	34961
k_ISDATDIRASentDiag_Cnt_str.NStep	18589

Name	Input Value
k_ISDATDIRASentTimeout_mS_u16	36912
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	8673
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	45
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	51684
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	8676
k_ISDYNAASChkSumValidThresh_Cnt_u16	49567
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	43897
k_ISDYNAASMsgCountValidThresh_Cnt_u16	60973
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	29848
k_ISDYNAASMsgLenValidThresh_Cnt_u16	33384
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39148
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	39675
k_ISDYNABRChkSumValidThresh_Cnt_u16	55326
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	48278
k_ISDYNABRMsgCountValidThresh_Cnt_u16	13225
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	12146
k_ISDYNABRMsgLenValidThresh_Cnt_u16	48753
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	15716
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	1437
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	41173
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	48623
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	34179
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	50262
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	32595
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	53703
k_ISDYNVOLChkSumValidThresh_Cnt_u16	26639
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	55570
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	29523
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	31856
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	6559
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	64430
k_IgnOnTimeout_mS_u16	49939
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	20.1882
k_PowerCutVehSpdLowThresh_Kph_f32	240.039703
k_PowerCutVehSpdLowTimeout_mS_u16	16147
k_VBattMaxAAS_Volt_f32	20.1086006
k_VBattMaxBSI_Volt_f32	24.5876999
k_VBattMaxCAV_Volt_f32	30.8514004
k_VBattMaxCMM388_Volt_f32	23.8215008
k_VBattMaxCMM_Volt_f32	21.9204998
k_VBattMaxESP_Volt_f32	13.2547998
k_VBattMinAAS_Volt_f32	5.01609993
k_VBattMinBSI_Volt_f32	13.2547998
k_VBattMinCAV_Volt_f32	11.7566996
k_VBattMinCMM388_Volt_f32	31.6804008
k_VBattMinCMM_Volt_f32	30.8286991
k_VBattMinESP_Volt_f32	21.9204998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	52435
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	53514
k_VitesseVehicleBVRampValidThresh_Cnt_u16	52269
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	42955
k_VitesseVehicleBVSigValidThresh_Cnt_u16	8626
k_VitesseVehicleBVSpeedPassThresh_kph_f32	339.617493
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	36220
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	33671
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1983077120
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	66
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	54721
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1145471744
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	42
target_SrlComInput_Per1_Batt_Volt_f32.value	3.36120009
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1671367424
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	65

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.264065921
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4285266688
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	322542336
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1259813632
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	201
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3473201920
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3338828544
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1527782144
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3006118656
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	24
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	25
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	48
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	75
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	211
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3578911488
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	48
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	49
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	122
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	167
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	193
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	62
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	538114816
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	160
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	90217216
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	211
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3468573440
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	57
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	80
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	221
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	235
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1898220288
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1277
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.912748635
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	502922
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	41.6492996
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	64091

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1145471744	1145471744	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1145471744	1145471744	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1145471744	1145471744	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1145471744	1145471744	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1145471744	1145471744	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1145471744	1145471744	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1145471744	1145471744	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1145471744	1145471744	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1145471744	1145471744	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	30972	30972	✔
CAVNodeAbsentTimer_mS_M_u32	1145471744	1145471744	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1145471744	1145471744	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1145471744	1145471744	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	53126	53126	✔
CMMNodeAbsentTimer_mS_M_u32	1145471744	1145471744	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	45868	45868	✔
CONSANGLECPK_HwDeg_M_f32	-663.656677	-663.656677 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1145471744	1145471744	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1145471744	1145471744	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1145471744	1145471744	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1145471744	1145471744	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1145471744	1145471744	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1145471744	1145471744	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1145471744	1145471744	✔
ESPNTCEnableTimer_mS_M_u32	1145471744	1145471744	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1145471744	1145471744	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3	3	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1145471744	1145471744	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1145471744	1145471744	✔
ElecIntTimer_mS_M_u32[1]	1145471744	1145471744	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1145471744	1145471744	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1145471744	1145471744	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1145471744	1145471744	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1145471744	1145471744	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1145471744	1145471744	✔
ISDATDIRASentFltAcc_Cnt_M_u16	13337	13337	✔
ISDATDIRASentTimer_mS_M_u32	1145471744	1145471744	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1145471744	1145471744	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1145471744	1145471744	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1145471744	1145471744	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1145471744	1145471744	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1145471744	1145471744	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1145471744	1145471744	✔
IgnOnTimer_mS_M_u32	1145471744	1145471744	✔
IgnTimeOff_Sec_M_u32	1203662338	1203662338	✔
Msg348Valid_Cnt_M_Igc	0	0	✔
Msg432Valid_Cnt_M_Igc	0	0	✔
Msg552Valid_Cnt_M_Igc	0	0	✔
NetOn_Cnt_M_Igc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	30	30	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4285266688	4285266688	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	143	143	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	322542336	322542336	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI412MsgDLCError_Cnt_M_u08	16	16	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1259813632	1259813632	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	201	201	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3473201920	3473201920	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2818587392	2818587392	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	131	131	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1527782144	1527782144	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	212	212	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3006118656	3006118656	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	223	223	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3578911488	3578911488	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	62	62	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	538114816	538114816	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	160	160	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	90217216	90217216	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	211	211	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3468573440	3468573440	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1898220288	1898220288	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	120.7826	120.7826	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	61.6217995	61.6217995	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	528.377502	528.377502	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	45868	45868	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1203662338	1203662338	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-663.656677	-663.656677 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.2 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	563970560
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	52324
AASNodeAbsentTimer_mS_M_u32	2756342272
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	55168
ANGLEVOLANTSigValidCount_Cnt_M_u16	25542
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	13441
AngleVolantMsgTimer_mS_M_u32	563970560
AngleVolantValidCount_Cnt_M_u16	55454
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3779211776
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	4096832000
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	4143194624
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2977620480
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	15943
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2221711872
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	27158
CAVNodeAbsentTimer_mS_M_u32	2964656640
CDD_SrlComVehSpd_Kph_G_f32	134.716904
CMM388NTCEnableTimer_mS_M_u32	650727936
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4287304192
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	27123
CMMNodeAbsentTimer_mS_M_u32	2837766656
CONSANGLECPKSigInvalidCount_Cnt_M_u16	54980
CONSANGLECPKSigValidCount_Cnt_M_u16	25178
CONSANGLECPK_Cnt_M_u16	24901
CONSANGLECPK_HwDeg_M_f32	61.7938004
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	24901
CPKVehicleSpeedMsgTimer_mS_M_u32	765231616
CPKVehicleSpeedValidCount_Cnt_M_u16	10598
CityParkInputConsistentCount_Cnt_M_u16	51074

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	35159
CityParkInputMsgTimer_mS_M_u32	4285266688
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1278112256
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	53576
ComputerRazGCTSigInvalidTimer_mS_M_u32	1951764992
ComputerRazGCTSigValidCount_Cnt_M_u16	9815
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	30323
DMDFCTCPKSigValidCount_Cnt_M_u16	36129
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	58866
DMDRELAXECPKSigValidCount_Cnt_M_u16	50104
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	47073
DateInvalidTimer_mS_M_u32	4096832000
DiagMuxOnAbsentTimer_mS_M_u32	460276224
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2977620480
ESPNTCEnableTimer_mS_M_u32	2416669184
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	46517
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	9
EffacDefaultDiagTimer_mS_M_u32[1]	680999424
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	20
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2235474432
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	7644
EtatMTSigValidCount_Cnt_M_u16	25103
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	47926
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	6220
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	38391
ISDAT4V2BSI552MsgTimer_mS_M_u32	872997376
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	57777
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	19756
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	25103
ISDATBSI3F2MsgTimer_mS_M_u32	1325220352
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	20304
ISDATBSI412MsgLenValidCount_Cnt_M_u16	250
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	7644
ISDATBSI412MsgTimer_mS_M_u32	1529577984
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	6103
ISDATBSI432MsgLenValidCount_Cnt_M_u16	50841
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	7415
ISDATDIRASentFltAcc_Cnt_M_u16	15851
ISDATDIRASentTimer_mS_M_u32	765231616
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	50003
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	55454
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	5818
ISDYN2CMMMsgTimer_mS_M_u32	3023401472
ISDYNAASChkSumInvalidCount_Cnt_M_u16	59094
ISDYNAASChkSumValidCount_Cnt_M_u16	4156
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	32485
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	44353
ISDYNAASMsgLenValidCount_Cnt_M_u16	36384
ISDYNAASMsgTimeValidCount_Cnt_M_u16	59094
ISDYNAASMsgTimer_mS_M_u32	3638907392
ISDYNABRChkSumInvalidCount_Cnt_M_u16	40413
ISDYNABRChkSumValidCount_Cnt_M_u16	42860
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	24477
ISDYNABRMsgCountValidCount_Cnt_M_u16	24643
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	21131
ISDYNABRMsgLenValidCount_Cnt_M_u16	62817
ISDYNABRMsgTimeValidCount_Cnt_M_u16	24901
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	554

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	993
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	25103
ISDYNCMM208MsgTimer_mS_M_u32	1951871488
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2067
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1099
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	6444
ISDYNCMM388MsgTimer_mS_M_u32	3785937408
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	49746
ISDYNVOLChkSumValidCount_Cnt_M_u16	31848
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	42241
ISDYNVOLMsgCountValidCount_Cnt_M_u16	10799
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	19438
ISDYNVOLMsgLenValidCount_Cnt_M_u16	39525
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	27123
ISDYNVOLMsgTimer_mS_M_u32	3530658304
IgnOnTimer_mS_M_u32	1200411136
IgnTimeOff_Sec_M_u32	3126845173
ManVehSpd_Kph_M_f32	503.516907
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	66
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	106
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2176008704
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	43
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1385898496
PrevISDATBSI412MsgDLCError_Cnt_M_u08	199
PrevISDATBSI412MsgRxTime_MSec_M_u32	2052461056
PrevISDATBSI432MsgDLCError_Cnt_M_u08	166
PrevISDATBSI432MsgRxTime_MSec_M_u32	1801417216
PrevISDATDIRAMsgTxTime_MSec_M_u32	709497344
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	89
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4252000768
PrevISDYNAASMsgDLCError_Cnt_M_u08	100
PrevISDYNAASMsgRxTime_MSec_M_u32	2088735232
PrevISDYNABRMsgDLCError_Cnt_M_u08	41
PrevISDYNABRMsgRxTime_MSec_M_u32	2126828032
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	71
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2098500096
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	63
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3880415744
PrevISDYNVOLMsgDLCError_Cnt_M_u08	156
PrevISDYNVOLMsgRxTime_MSec_M_u32	1321406976
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1740210688
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	12.7196999
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57807
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	45358
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	19848
VitesseVehicleBVRampValidCount_Cnt_M_u16	42407
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	25785
VitesseVehicleBVSigValidCount_Cnt_M_u16	39359

Name	Input Value
VitesseVehicleBV_Kph_M_f32	608.106201
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	6444
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	19690
VitesseVehiculeRoues_Kph_M_f32	560.258484
k_AASNTCEnableTimeout_mS_u16	25476
k_AASNodeAbsentDiag_Cnt_str.Threshold	6868
k_AASNodeAbsentDiag_Cnt_str.PStep	17207
k_AASNodeAbsentDiag_Cnt_str.NStep	40415
k_AASNodeAbsentTimeout_mS_u16	8961
k_AASNodeTimeout_mS_u16	29742
k_ABSNodeTimeout_mS_u16	11592
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	58234
k_ANGLEVOLANTSigValidThresh_Cnt_u16	5756
k_AngleVolantInvalidThresh_Cnt_u16	34571
k_AngleVolantValidThresh_Cnt_u16	35159
k_BSI552MsgTimeout_mS_u16	22073
k_BSINTCEnableTimeout_mS_u16	48911
k_BSINodeAbsentDiag_Cnt_str.Threshold	19572
k_BSINodeAbsentDiag_Cnt_str.PStep	37222
k_BSINodeAbsentDiag_Cnt_str.NStep	11347
k_BSINodeAbsentTimeout_mS_u16	52665
k_BSINodeTimeout_mS_u16	7415
k_BattOvHi_Volt_f32	8.83430004
k_BattOvLo_Volt_f32	7.52540016
k_BattUvHi_Volt_f32	17.1928997
k_BattUvLo_Volt_f32	22.4111004
k_CAVNTCEnableTimeout_mS_u16	62749
k_CAVNodeAbsentDiag_Cnt_str.Threshold	35137
k_CAVNodeAbsentDiag_Cnt_str.PStep	1241
k_CAVNodeAbsentDiag_Cnt_str.NStep	64948
k_CAVNodeAbsentTimeout_mS_u16	55716
k_CAVNodeTimeout_mS_u16	32992
k_CMM388MsgTimeout_mS_u16	53092
k_CMM388NTCEnableTimeout_mS_u16	2688
k_CMMNTCEnableTimeout_mS_u16	58601
k_CMMNodeAbsentDiag_Cnt_str.Threshold	21219
k_CMMNodeAbsentDiag_Cnt_str.PStep	33302
k_CMMNodeAbsentDiag_Cnt_str.NStep	36749
k_CMMNodeAbsentTimeout_mS_u16	56838
k_CONSANGLECPKMax_HwDeg_f32	655.763123
k_CONSANGLECPKMin_HwDeg_f32	-157.337402
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	39980
k_CONSANGLECPKSigValidThresh_Cnt_u16	4074
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	47108
k_CPKVehicleSpeedValidThresh_Cnt_u16	38971
k_CityParkInputInvalidThresh_Cnt_u16	24115
k_CityParkInputValidThresh_Cnt_u16	51074
k_ComputerRazGCTSigValidThresh_Cnt_u16	7911
k_CptTemporelSigValidThresh_Cnt_u16	9954
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	21899
k_DMDFCTCPKSigValidThresh_Cnt_u16	14433
k_DMDFCTCPKValidCount_Cnt_u16	47119
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	5818
k_DMDRELAXECPKSigValidThresh_Cnt_u16	42152
k_DMDRelaxeConsistentThresh_Cnt_u16	12926
k_DateValidThresh_Cnt_u16	38391
k_DefaultVehSpd_Kph_f32	168.690002
k_DiagMuxOnAbsentTimeout_mS_u16	44683
k_EMNodeTimeout_mS_u16	5441
k_ESPNTCEnableTimeout_mS_u16	38450
k_ESPNodeAbsentDiag_Cnt_str.Threshold	8520
k_ESPNodeAbsentDiag_Cnt_str.PStep	13196
k_ESPNodeAbsentDiag_Cnt_str.NStep	16403
k_ESPNodeAbsentTimeout_mS_u16	48846
k_EtatMTSigInvalidThresh_Cnt_u16	35916
k_EtatMTSigValidThresh_Cnt_u16	56091
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	36559
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	23521
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	58683
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	51438
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	6185
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	17204
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	14484

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	60182
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	1467
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	45705
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	58452
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	13330
k_ISDATDIRASentDiag_Cnt_str.Threshold	3050
k_ISDATDIRASentDiag_Cnt_str.PStep	27458
k_ISDATDIRASentDiag_Cnt_str.NStep	55261
k_ISDATDIRASentTimeout_mS_u16	1529
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	55335
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	13441
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	55262
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	8413
k_ISDYNAASChkSumValidThresh_Cnt_u16	27244
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	25245
k_ISDYNAASMsgCountValidThresh_Cnt_u16	41795
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	63681
k_ISDYNAASMsgLenValidThresh_Cnt_u16	15122
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	54596
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	10521
k_ISDYNABRChkSumValidThresh_Cnt_u16	14959
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	16711
k_ISDYNABRMsgCountValidThresh_Cnt_u16	25805
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	11507
k_ISDYNABRMsgLenValidThresh_Cnt_u16	47285
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	62364
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	18611
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7753
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	25725
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	55936
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	42694
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	9871
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	54131
k_ISDYNVOLChkSumValidThresh_Cnt_u16	26973
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	11474
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	9552
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	3832
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	12331
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	23101
k_IgnOnTimeout_mS_u16	12175
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	209.4776
k_PowerCutVehSpdLowThresh_Kph_f32	37.9229012
k_PowerCutVehSpdLowTimeout_mS_u16	6544
k_VBattMaxAAS_Volt_f32	30.3649998
k_VBattMaxBSI_Volt_f32	29.8829994
k_VBattMaxCAV_Volt_f32	19.5030003
k_VBattMaxCMM388_Volt_f32	16.4227009
k_VBattMaxCMM_Volt_f32	26.0895996
k_VBattMaxESP_Volt_f32	32
k_VBattMinAAS_Volt_f32	6.64550018
k_VBattMinBSI_Volt_f32	32
k_VBattMinCAV_Volt_f32	1.60239995
k_VBattMinCMM388_Volt_f32	29.0366001
k_VBattMinCMM_Volt_f32	21.1179008
k_VBattMinESP_Volt_f32	26.0895996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	8017
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	11115
k_VitesseVehicleBVRampValidThresh_Cnt_u16	10241
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	49000
k_VitesseVehicleBVSigValidThresh_Cnt_u16	10867
k_VitesseVehicleBVSpeedPassThresh_kph_f32	461.865997
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	60694
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	29621
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	4096832000
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	93
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	34479
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	680999424
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	63
target_SrlComInput_Per1_Batt_Volt_f32.value	28.4841003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3064832512
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	196
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.732914746
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2198262272
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	102625792
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1560613376
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	122
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	263991808
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2789429760
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2828694016
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	52
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2663485952
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	102
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	114
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	164
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	181
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	234
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	244
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	246
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1893020160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	97
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	107
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	202
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	220
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	232
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2098319872
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	82
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2343105024
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	772805120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	20
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	66
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	145
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	146
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2216501760
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3118
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.219837487
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	894367
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	189.343994

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	57977		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	680999424	680999424	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	680999424	680999424	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	680999424	680999424	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	680999424	680999424	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	680999424	680999424	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	680999424	680999424	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	680999424	680999424	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	680999424	680999424	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	680999424	680999424	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	35137	35137	✔
CAVNodeAbsentTimer_mS_M_u32	680999424	680999424	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	680999424	680999424	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	680999424	680999424	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	21219	21219	✔
CMMNodeAbsentTimer_mS_M_u32	680999424	680999424	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	24901	24901	✔
CONSANGLECPK_HwDeg_M_f32	61.7938004	61.7938004 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	680999424	680999424	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	680999424	680999424	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	680999424	680999424	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	680999424	680999424	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	680999424	680999424	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	680999424	680999424	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	680999424	680999424	✔
ESPNTCEnableTimer_mS_M_u32	680999424	680999424	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	680999424	680999424	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	9	9	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	680999424	680999424	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	680999424	680999424	✔
ElecIntTimer_mS_M_u32[1]	20	20	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	680999424	680999424	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	680999424	680999424	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	680999424	680999424	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	680999424	680999424	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	680999424	680999424	✔
ISDATDIRASentFltAcc_Cnt_M_u16	3050	3050	✔
ISDATDIRASentTimer_mS_M_u32	680999424	680999424	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	680999424	680999424	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	680999424	680999424	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	680999424	680999424	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	680999424	680999424	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	680999424	680999424	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	680999424	680999424	✔
IgnOnTimer_mS_M_u32	1200411136	1200411136	✔
IgnTimeOff_Sec_M_u32	3126845173	3126845173	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	222	222	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2198262272	2198262272	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	102625792	102625792	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	134	134	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1560613376	1560613376	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	122	122	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	263991808	263991808	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	709497344	709497344	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2828694016	2828694016	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	52	52	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2663485952	2663485952	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	172	172	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1893020160	1893020160	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2098319872	2098319872	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	82	82	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2343105024	2343105024	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	153	153	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	772805120	772805120	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2216501760	2216501760	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	12.7196999	12.7196999	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	608.106201	608.106201	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	560.258484	560.258484	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	24901	24901	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3126845173	3126845173	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	61.7938004	61.7938004 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	168.690002	168.690002	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.3 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2941140224
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	59642
AASNodeAbsentTimer_mS_M_u32	1191668992
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	55717
ANGLEVOLANTSigValidCount_Cnt_M_u16	39569
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	25763
AngleVolantMsgTimer_mS_M_u32	2941140224
AngleVolantValidCount_Cnt_M_u16	54476
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	522202368
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3226774784
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1372216576
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2906004736
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	33104
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	727768320
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	41570
CAVNodeAbsentTimer_mS_M_u32	2487717120
CDD_SrlComVehSpd_Kph_G_f32	335.261108
CMM388NTCEnableTimer_mS_M_u32	3540700416
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2143653120
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	12684
CMMNodeAbsentTimer_mS_M_u32	3996654848
CONSANGLECPKSigInvalidCount_Cnt_M_u16	39641
CONSANGLECPKSigValidCount_Cnt_M_u16	40406
CONSANGLECPK_Cnt_M_u16	3349
CONSANGLECPK_HwDeg_M_f32	349.562286
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	3349
CPKVehicleSpeedMsgTimer_mS_M_u32	1196506368
CPKVehicleSpeedValidCount_Cnt_M_u16	55833

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	38944
CityParkInputInvalidCount_Cnt_M_u16	14240
CityParkInputMsgTimer_mS_M_u32	2198262272
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3747310848
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	27214
ComputerRazGCTSigInvalidTimer_mS_M_u32	1801850112
ComputerRazGCTSigValidCount_Cnt_M_u16	4001
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	57420
DMDFCTCPKSigValidCount_Cnt_M_u16	41473
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	63055
DMDRELAXECPKSigValidCount_Cnt_M_u16	49851
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	43906
DateInvalidTimer_mS_M_u32	3226774784
DiagMuxOnAbsentTimer_mS_M_u32	953744640
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2906004736
ESPNTCEnableTimer_mS_M_u32	3351538944
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	41989
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	20
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	88
ElecIntTimer_mS_M_u32[1]	112
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4041923840
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	19153
EtatMTSigValidCount_Cnt_M_u16	37881
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	13699
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	50176
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	24447
ISDAT4V2BSI552MsgTimer_mS_M_u32	3716947200
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	36048
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	32801
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	37881
ISDATBSI3F2MsgTimer_mS_M_u32	1445920000
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	36086
ISDATBSI412MsgLenValidCount_Cnt_M_u16	28086
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	19153
ISDATBSI412MsgTimer_mS_M_u32	3131325696
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	47072
ISDATBSI432MsgLenValidCount_Cnt_M_u16	345
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	19903
ISDATDIRASentFltAcc_Cnt_M_u16	47843
ISDATDIRASentTimer_mS_M_u32	1196506368
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	40683
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	54476
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	56183
ISDYN2CMMMsgTimer_mS_M_u32	2202430720
ISDYNAASChkSumInvalidCount_Cnt_M_u16	57764
ISDYNAASChkSumValidCount_Cnt_M_u16	19249
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	48631
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	17633
ISDYNAASMsgLenValidCount_Cnt_M_u16	26630
ISDYNAASMsgTimeValidCount_Cnt_M_u16	57764
ISDYNAASMsgTimer_mS_M_u32	750177536
ISDYNABRChkSumInvalidCount_Cnt_M_u16	13325
ISDYNABRChkSumValidCount_Cnt_M_u16	40225
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	21327
ISDYNABRMsgCountValidCount_Cnt_M_u16	14108
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	900
ISDYNABRMsgLenValidCount_Cnt_M_u16	49345
ISDYNABRMsgTimeValidCount_Cnt_M_u16	3349

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	555
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	995
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	37881
ISDYNCMM208MsgTimer_mS_M_u32	4192283904
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2071
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1101
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	52002
ISDYNCMM388MsgTimer_mS_M_u32	2154581248
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	36911
ISDYNVOLChkSumValidCount_Cnt_M_u16	1964
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	3234
ISDYNVOLMsgCountValidCount_Cnt_M_u16	33495
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	1370
ISDYNVOLMsgLenValidCount_Cnt_M_u16	16311
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	12684
ISDYNVOLMsgTimer_mS_M_u32	3239185664
IgnOnTimer_mS_M_u32	3737144576
IgnTimeOff_Sec_M_u32	1078796818
ManVehSpd_Kph_M_f32	417.836304
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	68
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	156
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	369949952
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	31
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2597674240
PrevISDATBSI412MsgDLCError_Cnt_M_u08	88
PrevISDATBSI412MsgRxTime_MSec_M_u32	4217670912
PrevISDATBSI432MsgDLCError_Cnt_M_u08	10
PrevISDATBSI432MsgRxTime_MSec_M_u32	2244504832
PrevISDATDIRAMsgTxTime_MSec_M_u32	3146288384
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	56
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2136317184
PrevISDYNAASMsgDLCError_Cnt_M_u08	214
PrevISDYNAASMsgRxTime_MSec_M_u32	2062028032
PrevISDYNABRMsgDLCError_Cnt_M_u08	96
PrevISDYNABRMsgRxTime_MSec_M_u32	421022976
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	165
PrevISDYNCMM208MsgRxTime_MSec_M_u32	220794112
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	166
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2114415872
PrevISDYNVOLMsgDLCError_Cnt_M_u08	67
PrevISDYNVOLMsgRxTime_MSec_M_u32	1914539264
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1291468032
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	562.805786
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	24375
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	46812
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	16396
VitesseVehicleBVRampValidCount_Cnt_M_u16	64881
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	22010

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	7334
VitesseVehicleBV_Kph_M_f32	148.294403
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	52002
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	30119
VitesseVehiculeRoues_Kph_M_f32	172.619507
k_AASNTCEnableTimeout_mS_u16	49752
k_AASNodeAbsentDiag_Cnt_str.Threshold	4454
k_AASNodeAbsentDiag_Cnt_str.PStep	45563
k_AASNodeAbsentDiag_Cnt_str.NStep	52165
k_AASNodeAbsentTimeout_mS_u16	16803
k_AASNodeTimeout_mS_u16	28124
k_ABSNodeTimeout_mS_u16	20429
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	41207
k_ANGLEVOLANTSigValidThresh_Cnt_u16	23984
k_AngleVolantInvalidThresh_Cnt_u16	2051
k_AngleVolantValidThresh_Cnt_u16	14240
k_BSI552MsgTimeout_mS_u16	21946
k_BSINTCEnableTimeout_mS_u16	41528
k_BSINodeAbsentDiag_Cnt_str.Threshold	19612
k_BSINodeAbsentDiag_Cnt_str.PStep	37205
k_BSINodeAbsentDiag_Cnt_str.NStep	11370
k_BSINodeAbsentTimeout_mS_u16	30971
k_BSINodeTimeout_mS_u16	19903
k_BattOvHi_Volt_f32	29.7882996
k_BattOvLo_Volt_f32	29.4937
k_BattUvHi_Volt_f32	29.6585999
k_BattUvLo_Volt_f32	4.5777998
k_CAVNTCEnableTimeout_mS_u16	35918
k_CAVNodeAbsentDiag_Cnt_str.Threshold	55516
k_CAVNodeAbsentDiag_Cnt_str.PStep	20438
k_CAVNodeAbsentDiag_Cnt_str.NStep	24324
k_CAVNodeAbsentTimeout_mS_u16	3000
k_CAVNodeTimeout_mS_u16	3205
k_CMM388MsgTimeout_mS_u16	57338
k_CMM388NTCEnableTimeout_mS_u16	40614
k_CMMNTCEnableTimeout_mS_u16	25384
k_CMMNodeAbsentDiag_Cnt_str.Threshold	5177
k_CMMNodeAbsentDiag_Cnt_str.PStep	57439
k_CMMNodeAbsentDiag_Cnt_str.NStep	8633
k_CMMNodeAbsentTimeout_mS_u16	12883
k_CONSANGLECPKMax_HwDeg_f32	601.930298
k_CONSANGLECPKMin_HwDeg_f32	-158.851105
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	16930
k_CONSANGLECPKSigValidThresh_Cnt_u16	11431
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	31322
k_CPKVehicleSpeedValidThresh_Cnt_u16	7733
k_CityParkInputInvalidThresh_Cnt_u16	51979
k_CityParkInputValidThresh_Cnt_u16	38944
k_ComputerRazGCTSigValidThresh_Cnt_u16	11566
k_CptTemporelSigValidThresh_Cnt_u16	19199
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	64132
k_DMDFCTCPKSigValidThresh_Cnt_u16	63425
k_DMDFCTCPKValidCount_Cnt_u16	13304
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	56183
k_DMDRELAXECPKSigValidThresh_Cnt_u16	14188
k_DMDRelaxeConsistentThresh_Cnt_u16	26090
k_DateValidThresh_Cnt_u16	24447
k_DefaultVehSpd_Kph_f32	206.581497
k_DiagMuxOnAbsentTimeout_mS_u16	48451
k_EMNodeTimeout_mS_u16	4962
k_ESPNTCEnableTimeout_mS_u16	36366
k_ESPNodeAbsentDiag_Cnt_str.Threshold	28680
k_ESPNodeAbsentDiag_Cnt_str.PStep	54014
k_ESPNodeAbsentDiag_Cnt_str.NStep	22311
k_ESPNodeAbsentTimeout_mS_u16	45051
k_EtatMTSigInvalidThresh_Cnt_u16	58560
k_EtatMTSigValidThresh_Cnt_u16	32276
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	57849
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	4226
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	25333
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	2841
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	21290
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	16714

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	35241
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	51170
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	32308
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	10569
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	2474
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	47023
k_ISDATDIRASentDiag_Cnt_str.Threshold	13537
k_ISDATDIRASentDiag_Cnt_str.PStep	155
k_ISDATDIRASentDiag_Cnt_str.NStep	46217
k_ISDATDIRASentTimeout_mS_u16	27577
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	24432
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	25763
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	30986
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	43789
k_ISDYNAASChkSumValidThresh_Cnt_u16	21537
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	19023
k_ISDYNAASMsgCountValidThresh_Cnt_u16	28188
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	45921
k_ISDYNAASMsgLenValidThresh_Cnt_u16	43312
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	16728
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	14298
k_ISDYNABRChkSumValidThresh_Cnt_u16	43415
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	30800
k_ISDYNABRMsgCountValidThresh_Cnt_u16	29564
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	59532
k_ISDYNABRMsgLenValidThresh_Cnt_u16	39685
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	49935
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	47755
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	17419
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	39151
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	53413
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	53649
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	16376
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	19597
k_ISDYNVOLChkSumValidThresh_Cnt_u16	32909
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	62126
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	45941
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	59261
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	39333
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	43693
k_IgnOnTimeout_mS_u16	43065
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	2.71869993
k_PowerCutVehSpdLowThresh_Kph_f32	77.3827972
k_PowerCutVehSpdLowTimeout_mS_u16	53300
k_VBattMaxAAS_Volt_f32	20.6217003
k_VBattMaxBSI_Volt_f32	16.2026997
k_VBattMaxCAV_Volt_f32	22.1091003
k_VBattMaxCMM388_Volt_f32	4.8599
k_VBattMaxCMM_Volt_f32	29.9675007
k_VBattMaxESP_Volt_f32	5.27890015
k_VBattMinAAS_Volt_f32	1.77149999
k_VBattMinBSI_Volt_f32	5.27890015
k_VBattMinCAV_Volt_f32	4.36469984
k_VBattMinCMM388_Volt_f32	23.4468994
k_VBattMinCMM_Volt_f32	12.6239004
k_VBattMinESP_Volt_f32	29.9675007
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	45554
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	17251
k_VitesseVehicleBVRampValidThresh_Cnt_u16	33698
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	16044
k_VitesseVehicleBVSigValidThresh_Cnt_u16	29517
k_VitesseVehicleBVSpeedPassThresh_kph_f32	492.794403
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	6498
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	19271
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3226774784
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	189
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	10321
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3342931200
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	166
target_SrlComInput_Per1_Batt_Volt_f32.value	9.00419998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3634224384
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	184
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.501388729
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	87
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2488421632
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3482119424
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	232
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3478621440
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	177
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4222758144
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3164392704
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2048355584
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2619477248
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	159
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	180
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	229
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	236
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	191
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2087136512
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	68
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	111
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	192
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	79
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2452704512
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	720104704
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1211534592
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	12
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	83
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	107
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	124
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	212
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	213
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2387565824
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	4082
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.240117013
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	585917
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	186.369293
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	34105

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3342931200	3342931200	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3342931200	3342931200	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	25763	25763	✔
AngleVolantMsgTimer_mS_M_u32	3342931200	3342931200	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3342931200	3342931200	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3342931200	3342931200	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3342931200	3342931200	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3342931200	3342931200	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3342931200	3342931200	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3342931200	3342931200	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	55516	55516	✔
CAVNodeAbsentTimer_mS_M_u32	3342931200	3342931200	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3342931200	3342931200	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3342931200	3342931200	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	5177	5177	✔
CMMNodeAbsentTimer_mS_M_u32	3342931200	3342931200	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	3349	3349	✔
CONSANGLECPK_HwDeg_M_f32	349.562286	349.562286 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	3349	3349	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1196506368	1196506368	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	55833	55833	✔
CityParkInputConsistentCount_Cnt_M_u16	38944	38944	✔
CityParkInputInvalidCount_Cnt_M_u16	14242	14242	✔
CityParkInputMsgTimer_mS_M_u32	3342931200	3342931200	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3342931200	3342931200	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3342931200	3342931200	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3342931200	3342931200	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3342931200	3342931200	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3342931200	3342931200	✔
ESPNTCEnableTimer_mS_M_u32	3342931200	3342931200	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3342931200	3342931200	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	3342931200	3342931200	✔
EffacDefaultDiagTimer_mS_M_u32[1]	20	20	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3342931200	3342931200	✔
ElecIntTimer_mS_M_u32[1]	112	112	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3342931200	3342931200	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3342931200	3342931200	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3342931200	3342931200	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3342931200	3342931200	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3342931200	3342931200	✔
ISDATDIRASentFltAcc_Cnt_M_u16	13537	13537	✔
ISDATDIRASentTimer_mS_M_u32	3342931200	3342931200	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3342931200	3342931200	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3342931200	3342931200	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3342931200	3342931200	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3342931200	3342931200	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3342931200	3342931200	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3342931200	3342931200	✔
IgnOnTimer_mS_M_u32	3342931200	3342931200	✔
IgnTimeOff_Sec_M_u32	1078796818	1078796818	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	87	87	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2488421632	2488421632	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	151	151	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3482119424	3482119424	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	232	232	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3478621440	3478621440	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	177	177	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4222758144	4222758144	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3146288384	3146288384	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	77	77	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2048355584	2048355584	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	240	240	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2619477248	2619477248	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	191	191	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2087136512	2087136512	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	79	79	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2452704512	2452704512	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	12	12	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	720104704	720104704	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	154	154	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1211534592	1211534592	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2387565824	2387565824	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	562.805786	562.805786	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	148.294403	148.294403	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	172.619507	172.619507	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	3349	3349	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1078796818	1078796818	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	349.562286	349.562286 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	206.581497	206.581497	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.4 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3994459904
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	2343
AASNodeAbsentTimer_mS_M_u32	2132365056
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	49957
ANGLEVOLANTSigValidCount_Cnt_M_u16	45815
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	2584
AngleVolantMsgTimer_mS_M_u32	3994459904
AngleVolantValidCount_Cnt_M_u16	31877
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	637013760
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	617647872
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	292798208
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	238911232
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	8232
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3686678272
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	56016
CAVNodeAbsentTimer_mS_M_u32	1130000128
CDD_SrlComVehSpd_Kph_G_f32	148.0103
CMM388NTCEnableTimer_mS_M_u32	3392646912
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3133697792
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	60617
CMMNodeAbsentTimer_mS_M_u32	659521280
CONSANGLECPKSigInvalidCount_Cnt_M_u16	64512
CONSANGLECPKSigValidCount_Cnt_M_u16	48738
CONSANGLECPK_Cnt_M_u16	16281
CONSANGLECPK_HwDeg_M_f32	-767.526428
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	16281
CPKVehicleSpeedMsgTimer_mS_M_u32	2117181184
CPKVehicleSpeedValidCount_Cnt_M_u16	30224
CityParkInputConsistentCount_Cnt_M_u16	31353

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	12283
CityParkInputMsgTimer_mS_M_u32	4229684224
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4195176192
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	46363
ComputerRazGCTSigInvalidTimer_mS_M_u32	929885952
ComputerRazGCTSigValidCount_Cnt_M_u16	5634
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	65031
DMDFCTCPKSigValidCount_Cnt_M_u16	13538
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	54559
DMDRELAXECPKSigValidCount_Cnt_M_u16	11377
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	14833
DateInvalidTimer_mS_M_u32	617647872
DiagMuxOnAbsentTimer_mS_M_u32	569859840
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	238911232
ESPNTCEnableTimer_mS_M_u32	3451801344
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	64135
EffacDefaultDiagCount_Cnt_M_u08	2
EffacDefaultDiagTimer_mS_M_u32[0]	0
EffacDefaultDiagTimer_mS_M_u32[1]	2860779776
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	54
ElecIntTimer_mS_M_u32[1]	64
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3717742336
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	35375
EtatMTSigValidCount_Cnt_M_u16	42014
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	31738
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	9692
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	3664
ISDAT4V2BSI552MsgTimer_mS_M_u32	2973990656
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	53038
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	9348
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	42014
ISDATBSI3F2MsgTimer_mS_M_u32	436035328
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	62078
ISDATBSI412MsgLenValidCount_Cnt_M_u16	8388
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	35375
ISDATBSI412MsgTimer_mS_M_u32	1142726400
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	50621
ISDATBSI432MsgLenValidCount_Cnt_M_u16	25211
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	43285
ISDATDIRASentFltAcc_Cnt_M_u16	8025
ISDATDIRASentTimer_mS_M_u32	2117181184
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	20511
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	31877
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	19082
ISDYN2CMMMsgTimer_mS_M_u32	894455552
ISDYNAASChkSumInvalidCount_Cnt_M_u16	55073
ISDYNAASChkSumValidCount_Cnt_M_u16	46227
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	9992
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	10567
ISDYNAASMsgLenValidCount_Cnt_M_u16	19729
ISDYNAASMsgTimeValidCount_Cnt_M_u16	55073
ISDYNAASMsgTimer_mS_M_u32	3510873856
ISDYNABRChkSumInvalidCount_Cnt_M_u16	9164
ISDYNABRChkSumValidCount_Cnt_M_u16	15622
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	20004
ISDYNABRMsgCountValidCount_Cnt_M_u16	30678
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	8707
ISDYNABRMsgLenValidCount_Cnt_M_u16	28837
ISDYNABRMsgTimeValidCount_Cnt_M_u16	16281
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	557

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	999
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	42014
ISDYNCMM208MsgTimer_mS_M_u32	1052839680
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2079
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1105
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	5515
ISDYNCMM388MsgTimer_mS_M_u32	2124754688
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	35846
ISDYNVOLChkSumValidCount_Cnt_M_u16	26344
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	32013
ISDYNVOLMsgCountValidCount_Cnt_M_u16	3176
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	61060
ISDYNVOLMsgLenValidCount_Cnt_M_u16	41799
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	60617
ISDYNVOLMsgTimer_mS_M_u32	444133120
IgnOnTimer_mS_M_u32	4019793664
IgnTimeOff_Sec_M_u32	1613672932
ManVehSpd_Kph_M_f32	633.522095
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	72
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	57
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	147545856
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	205
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	450281216
PrevISDATBSI412MsgDLCError_Cnt_M_u08	192
PrevISDATBSI412MsgRxTime_MSec_M_u32	2875158272
PrevISDATBSI432MsgDLCError_Cnt_M_u08	116
PrevISDATBSI432MsgRxTime_MSec_M_u32	467816192
PrevISDATDIRAMsgTxTime_MSec_M_u32	212037376
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	76
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1029242624
PrevISDYNAASMsgDLCError_Cnt_M_u08	53
PrevISDYNAASMsgRxTime_MSec_M_u32	2466180864
PrevISDYNABRMsgDLCError_Cnt_M_u08	77
PrevISDYNABRMsgRxTime_MSec_M_u32	3165728512
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	254
PrevISDYNCMM208MsgRxTime_MSec_M_u32	524807936
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	75
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1847152384
PrevISDYNVOLMsgDLCError_Cnt_M_u08	112
PrevISDYNVOLMsgRxTime_MSec_M_u32	4292898560
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1495441152
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	360.212189
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	1613
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	663
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	30154
VitesseVehicleBVRampValidCount_Cnt_M_u16	1492
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	43554
VitesseVehicleBVSigValidCount_Cnt_M_u16	52660

Name	Input Value
VitesseVehicleBV_Kph_M_f32	316.394287
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	5515
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	64437
VitesseVehiculeRoues_Kph_M_f32	358.41571
k_AASNTCEnableTimeout_mS_u16	55028
k_AASNodeAbsentDiag_Cnt_str.Threshold	65114
k_AASNodeAbsentDiag_Cnt_str.PStep	18109
k_AASNodeAbsentDiag_Cnt_str.NStep	37278
k_AASNodeAbsentTimeout_mS_u16	43028
k_AASNodeTimeout_mS_u16	29079
k_ABSNodeTimeout_mS_u16	20880
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	20364
k_ANGLEVOLANTSigValidThresh_Cnt_u16	63882
k_AngleVolantInvalidThresh_Cnt_u16	44661
k_AngleVolantValidThresh_Cnt_u16	12283
k_BSI552MsgTimeout_mS_u16	37984
k_BSINTCEnableTimeout_mS_u16	49877
k_BSINodeAbsentDiag_Cnt_str.Threshold	19692
k_BSINodeAbsentDiag_Cnt_str.PStep	37171
k_BSINodeAbsentDiag_Cnt_str.NStep	11416
k_BSINodeAbsentTimeout_mS_u16	33072
k_BSINodeTimeout_mS_u16	43285
k_BattOvHi_Volt_f32	25.2124004
k_BattOvLo_Volt_f32	11.5796003
k_BattUvHi_Volt_f32	18.0790997
k_BattUvLo_Volt_f32	12.6787004
k_CAVNTCEnableTimeout_mS_u16	55833
k_CAVNodeAbsentDiag_Cnt_str.Threshold	36016
k_CAVNodeAbsentDiag_Cnt_str.PStep	61057
k_CAVNodeAbsentDiag_Cnt_str.NStep	48241
k_CAVNodeAbsentTimeout_mS_u16	32470
k_CAVNodeTimeout_mS_u16	56076
k_CMM388MsgTimeout_mS_u16	47143
k_CMM388NTCEnableTimeout_mS_u16	19507
k_CMMNTCEnableTimeout_mS_u16	6214
k_CMMNodeAbsentDiag_Cnt_str.Threshold	45882
k_CMMNodeAbsentDiag_Cnt_str.PStep	2553
k_CMMNodeAbsentDiag_Cnt_str.NStep	64915
k_CMMNodeAbsentTimeout_mS_u16	32193
k_CONSANGLECPKMax_HwDeg_f32	390.716003
k_CONSANGLECPKMin_HwDeg_f32	-95.810997
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	17547
k_CONSANGLECPKSigValidThresh_Cnt_u16	27317
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	4613
k_CPKVehicleSpeedValidThresh_Cnt_u16	42421
k_CityParkInputInvalidThresh_Cnt_u16	41658
k_CityParkInputValidThresh_Cnt_u16	31353
k_ComputerRazGCTSigValidThresh_Cnt_u16	41596
k_CptTemporelSigValidThresh_Cnt_u16	30290
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	53507
k_DMDFCTCPKSigValidThresh_Cnt_u16	24485
k_DMDFCTCPKValidCount_Cnt_u16	43024
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	19082
k_DMDRELAXECPKSigValidThresh_Cnt_u16	60837
k_DMDRelaxeConsistentThresh_Cnt_u16	49171
k_DateValidThresh_Cnt_u16	3664
k_DefaultVehSpd_Kph_f32	184.571304
k_DiagMuxOnAbsentTimeout_mS_u16	8503
k_EMNodeTimeout_mS_u16	57553
k_ESPNTCEnableTimeout_mS_u16	988
k_ESPNodeAbsentDiag_Cnt_str.Threshold	52988
k_ESPNodeAbsentDiag_Cnt_str.PStep	18660
k_ESPNodeAbsentDiag_Cnt_str.NStep	21662
k_ESPNodeAbsentTimeout_mS_u16	10409
k_EtatMTSigInvalidThresh_Cnt_u16	4631
k_EtatMTSigValidThresh_Cnt_u16	56721
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	20124
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	30954
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	9206
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	59327
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	14293
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	26994
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	52686

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	1356
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	57009
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	23917
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	34899
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	46337
k_ISDATDIRASentDiag_Cnt_str.Threshold	51526
k_ISDATDIRASentDiag_Cnt_str.PStep	21130
k_ISDATDIRASentDiag_Cnt_str.NStep	19284
k_ISDATDIRASentTimeout_mS_u16	63704
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	714
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	2584
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	42680
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	21196
k_ISDYNAASChkSumValidThresh_Cnt_u16	44038
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	64804
k_ISDYNAASMsgCountValidThresh_Cnt_u16	26326
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	48576
k_ISDYNAASMsgLenValidThresh_Cnt_u16	42891
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	14962
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	59657
k_ISDYNABRChkSumValidThresh_Cnt_u16	36907
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	53032
k_ISDYNABRMsgCountValidThresh_Cnt_u16	52026
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	23497
k_ISDYNABRMsgLenValidThresh_Cnt_u16	43399
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	20325
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	23617
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	59963
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	44354
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	29221
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	41463
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	15123
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	1741
k_ISDYNVOLChkSumValidThresh_Cnt_u16	8787
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	26232
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	9722
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	60475
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	46890
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	25326
k_IgnOnTimeout_mS_u16	8153
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	210.806107
k_PowerCutVehSpdLowThresh_Kph_f32	130.7827
k_PowerCutVehSpdLowTimeout_mS_u16	46000
k_VBattMaxAAS_Volt_f32	30.0485992
k_VBattMaxBSI_Volt_f32	16.7033997
k_VBattMaxCAV_Volt_f32	11.6601
k_VBattMaxCMM388_Volt_f32	6.59299994
k_VBattMaxCMM_Volt_f32	18.5125999
k_VBattMaxESP_Volt_f32	12.0398998
k_VBattMinAAS_Volt_f32	22.2388
k_VBattMinBSI_Volt_f32	12.0398998
k_VBattMinCAV_Volt_f32	17.9272003
k_VBattMinCMM388_Volt_f32	1.59290004
k_VBattMinCMM_Volt_f32	7.76219988
k_VBattMinESP_Volt_f32	18.5125999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	47452
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	40402
k_VitesseVehicleBVRampValidThresh_Cnt_u16	44045
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	21992
k_VitesseVehicleBVSigValidThresh_Cnt_u16	30478
k_VitesseVehicleBVSpeedPassThresh_kph_f32	408.242004
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	2512
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	45658
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	617647872
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	233
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	33856
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2860779776
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	75
target_SrlComInput_Per1_Batt_Volt_f32.value	0.4551
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3135454976
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	83
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.713493049
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2713399040
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2278215424
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3605688064
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	226
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	924454656
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1348054784
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	254
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3400093440
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1309208320
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	81
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	116
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	123
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	192
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	193
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	218
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	236
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1165430528
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	80
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	126
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	128
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	218
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	647114496
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	11
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1445056256
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2931912448
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	80
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	133
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	975224576
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3832
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.888203621
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	820784
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	242.161804

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	11359		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	2860779776	2860779776	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2860779776	2860779776	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2860779776	2860779776	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2860779776	2860779776	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2860779776	2860779776	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2860779776	2860779776	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2860779776	2860779776	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2860779776	2860779776	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2860779776	2860779776	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	36016	36016	✔
CAVNodeAbsentTimer_mS_M_u32	2860779776	2860779776	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2860779776	2860779776	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2860779776	2860779776	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	45882	45882	✔
CMMNodeAbsentTimer_mS_M_u32	2860779776	2860779776	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	16281	16281	✔
CONSANGLECPK_HwDeg_M_f32	-767.526428	-767.526428 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2860779776	2860779776	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2860779776	2860779776	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2860779776	2860779776	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2860779776	2860779776	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2860779776	2860779776	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2860779776	2860779776	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2860779776	2860779776	✔
ESPNTCEnableTimer_mS_M_u32	2860779776	2860779776	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2860779776	2860779776	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2860779776	2860779776	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	2860779776	2860779776	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2860779776	2860779776	✔
ElecIntTimer_mS_M_u32[1]	64	64	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2860779776	2860779776	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2860779776	2860779776	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2860779776	2860779776	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2860779776	2860779776	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2860779776	2860779776	✔
ISDATDIRASentFltAcc_Cnt_M_u16	51526	51526	✔
ISDATDIRASentTimer_mS_M_u32	2860779776	2860779776	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2860779776	2860779776	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2860779776	2860779776	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2860779776	2860779776	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2860779776	2860779776	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2860779776	2860779776	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2860779776	2860779776	✔
IgnOnTimer_mS_M_u32	2860779776	2860779776	✔
IgnTimeOff_Sec_M_u32	1613672932	1613672932	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	137	137	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2713399040	2713399040	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	90	90	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2278215424	2278215424	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	63	63	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3605688064	3605688064	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	226	226	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	924454656	924454656	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	212037376	212037376	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	254	254	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3400093440	3400093440	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	200	200	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1309208320	1309208320	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	236	236	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1165430528	1165430528	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	647114496	647114496	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	11	11	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1445056256	1445056256	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	26	26	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2931912448	2931912448	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	975224576	975224576	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	360.212189	360.212189	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	316.394287	316.394287	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	358.41571	358.41571	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	16281	16281	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1613672932	1613672932	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-767.526428	-767.526428 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	184.571304	184.571304	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.5 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	513205760
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	44901
AASNodeAbsentTimer_mS_M_u32	307156480
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	39785
ANGLEVOLANTSigValidCount_Cnt_M_u16	4275
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	45202
AngleVolantMsgTimer_mS_M_u32	513205760
AngleVolantValidCount_Cnt_M_u16	38857
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	145921536
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	237573632
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	285181440
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1906460160
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	20576
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4229957120
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	50922
CAVNodeAbsentTimer_mS_M_u32	2987095552
CDD_SrlComVehSpd_Kph_G_f32	617.661926
CMM388NTCEnableTimer_mS_M_u32	578008576
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2210493952
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	33469
CMMNodeAbsentTimer_mS_M_u32	4000073216
CONSANGLECPKSigInvalidCount_Cnt_M_u16	52185
CONSANGLECPKSigValidCount_Cnt_M_u16	2419
CONSANGLECPK_Cnt_M_u16	8654
CONSANGLECPK_HwDeg_M_f32	457.626801
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	8654
CPKVehicleSpeedMsgTimer_mS_M_u32	2588272128
CPKVehicleSpeedValidCount_Cnt_M_u16	27761

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	28141
CityParkInputInvalidCount_Cnt_M_u16	9830
CityParkInputMsgTimer_mS_M_u32	2713399040
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1903351296
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	31625
ComputerRazGCTSigInvalidTimer_mS_M_u32	1070855680
ComputerRazGCTSigValidCount_Cnt_M_u16	65362
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	60482
DMDFCTCPKSigValidCount_Cnt_M_u16	44148
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	52603
DMDRELAXECPKSigValidCount_Cnt_M_u16	3141
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	5638
DateInvalidTimer_mS_M_u32	237573632
DiagMuxOnAbsentTimer_mS_M_u32	4126451200
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1906460160
ESPNTCEnableTimer_mS_M_u32	4200584704
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	20035
EffacDefaultDiagCount_Cnt_M_u08	2
EffacDefaultDiagTimer_mS_M_u32[0]	4294967295
EffacDefaultDiagTimer_mS_M_u32[1]	3145115648
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	3145115648
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3734111744
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	5002
EtatMTSigValidCount_Cnt_M_u16	31360
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	46059
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	15109
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	22570
ISDAT4V2BSI552MsgTimer_mS_M_u32	546326016
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	22542
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	44235
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	31360
ISDATBSI3F2MsgTimer_mS_M_u32	2783094272
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	15136
ISDATBSI412MsgLenValidCount_Cnt_M_u16	50446
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	5002
ISDATBSI412MsgTimer_mS_M_u32	3028608512
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	51169
ISDATBSI432MsgLenValidCount_Cnt_M_u16	58983
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	45083
ISDATDIRASentFltAcc_Cnt_M_u16	23887
ISDATDIRASentTimer_mS_M_u32	2588272128
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	34876
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	38857
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	53945
ISDYN2CMMMsgTimer_mS_M_u32	2343163392
ISDYNAASChkSumInvalidCount_Cnt_M_u16	44407
ISDYNAASChkSumValidCount_Cnt_M_u16	55776
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	25664
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	30597
ISDYNAASMsgLenValidCount_Cnt_M_u16	12518
ISDYNAASMsgTimeValidCount_Cnt_M_u16	44407
ISDYNAASMsgTimer_mS_M_u32	1028634112
ISDYNABRChkSumInvalidCount_Cnt_M_u16	11509
ISDYNABRChkSumValidCount_Cnt_M_u16	50694
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	5230
ISDYNABRMsgCountValidCount_Cnt_M_u16	23575
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	9680
ISDYNABRMsgLenValidCount_Cnt_M_u16	48810
ISDYNABRMsgTimeValidCount_Cnt_M_u16	8654

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	558
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1001
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	31360
ISDYNCMM208MsgTimer_mS_M_u32	576165376
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2083
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1107
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	25783
ISDYNCMM388MsgTimer_mS_M_u32	2603300352
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	46023
ISDYNVOLChkSumValidCount_Cnt_M_u16	42977
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	1840
ISDYNVOLMsgCountValidCount_Cnt_M_u16	48610
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	42572
ISDYNVOLMsgLenValidCount_Cnt_M_u16	36037
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	33469
ISDYNVOLMsgTimer_mS_M_u32	3333420544
IgnOnTimer_mS_M_u32	407844352
IgnTimeOff_Sec_M_u32	2715648403
ManVehSpd_Kph_M_f32	532.133484
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	74
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	75
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2440603136
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	155
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1087800832
PrevISDATBSI412MsgDLCError_Cnt_M_u08	86
PrevISDATBSI412MsgRxTime_MSec_M_u32	3455874560
PrevISDATBSI432MsgDLCError_Cnt_M_u08	12
PrevISDATBSI432MsgRxTime_MSec_M_u32	2683557376
PrevISDATDIRAMsgTxTime_MSec_M_u32	3123738112
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	183
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2991572480
PrevISDYNAASMsgDLCError_Cnt_M_u08	235
PrevISDYNAASMsgRxTime_MSec_M_u32	4112381440
PrevISDYNABRMsgDLCError_Cnt_M_u08	199
PrevISDYNABRMsgRxTime_MSec_M_u32	285685248
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	210
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3024287232
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	131
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1162794496
PrevISDYNVOLMsgDLCError_Cnt_M_u08	44
PrevISDYNVOLMsgRxTime_MSec_M_u32	343504384
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	225633792
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	437.417694
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	30835
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	43092
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	24060
VitesseVehicleBVRampValidCount_Cnt_M_u16	53917
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	6770

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	62588
VitesseVehicleBV_Kph_M_f32	289.414215
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	25783
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	22264
VitesseVehiculeRoues_Kph_M_f32	100.536003
k_AASNTCEnableTimeout_mS_u16	34749
k_AASNodeAbsentDiag_Cnt_str.Threshold	49570
k_AASNodeAbsentDiag_Cnt_str.PStep	57969
k_AASNodeAbsentDiag_Cnt_str.NStep	1032
k_AASNodeAbsentTimeout_mS_u16	4380
k_AASNodeTimeout_mS_u16	23380
k_ABSNodeTimeout_mS_u16	21927
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	9844
k_ANGLEVOLANTSigValidThresh_Cnt_u16	7482
k_AngleVolantInvalidThresh_Cnt_u16	27257
k_AngleVolantValidThresh_Cnt_u16	9830
k_BSI552MsgTimeout_mS_u16	63735
k_BSINTCEnableTimeout_mS_u16	12441
k_BSINodeAbsentDiag_Cnt_str.Threshold	19732
k_BSINodeAbsentDiag_Cnt_str.PStep	37154
k_BSINodeAbsentDiag_Cnt_str.NStep	11439
k_BSINodeAbsentTimeout_mS_u16	43850
k_BSINodeTimeout_mS_u16	45083
k_BattOvHi_Volt_f32	30.6357002
k_BattOvLo_Volt_f32	23.0065002
k_BattUvHi_Volt_f32	28.4860001
k_BattUvLo_Volt_f32	6.69640017
k_CAVNTCEnableTimeout_mS_u16	8204
k_CAVNodeAbsentDiag_Cnt_str.Threshold	56888
k_CAVNodeAbsentDiag_Cnt_str.PStep	28157
k_CAVNodeAbsentDiag_Cnt_str.NStep	10151
k_CAVNodeAbsentTimeout_mS_u16	29400
k_CAVNodeTimeout_mS_u16	24245
k_CMM388MsgTimeout_mS_u16	41573
k_CMM388NTCEnableTimeout_mS_u16	5697
k_CMMNTCEnableTimeout_mS_u16	56518
k_CMMNodeAbsentDiag_Cnt_str.Threshold	38628
k_CMMNodeAbsentDiag_Cnt_str.PStep	19870
k_CMMNodeAbsentDiag_Cnt_str.NStep	11782
k_CMMNodeAbsentTimeout_mS_u16	212
k_CONSANGLECPKMax_HwDeg_f32	557.201294
k_CONSANGLECPKMin_HwDeg_f32	-502.976715
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	55223
k_CONSANGLECPKSigValidThresh_Cnt_u16	2552
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	45578
k_CPKVehicleSpeedValidThresh_Cnt_u16	48507
k_CityParkInputInvalidThresh_Cnt_u16	59435
k_CityParkInputValidThresh_Cnt_u16	28141
k_ComputerRazGCTSigValidThresh_Cnt_u16	38436
k_CptTemporelSigValidThresh_Cnt_u16	28513
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	6352
k_DMDFCTCPKSigValidThresh_Cnt_u16	61866
k_DMDFCTCPKValidCount_Cnt_u16	22696
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	53945
k_DMDRELAXECPKSigValidThresh_Cnt_u16	20011
k_DMDRelaxeConsistentThresh_Cnt_u16	3809
k_DateValidThresh_Cnt_u16	22570
k_DefaultVehSpd_Kph_f32	181.640701
k_DiagMuxOnAbsentTimeout_mS_u16	29940
k_EMNodeTimeout_mS_u16	41318
k_ESPNTCEnableTimeout_mS_u16	31686
k_ESPNodeAbsentDiag_Cnt_str.Threshold	14590
k_ESPNodeAbsentDiag_Cnt_str.PStep	47932
k_ESPNodeAbsentDiag_Cnt_str.NStep	57415
k_ESPNodeAbsentTimeout_mS_u16	40988
k_EtatMTSigInvalidThresh_Cnt_u16	19988
k_EtatMTSigValidThresh_Cnt_u16	53349
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	6213
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	52762
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	42358
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	37467
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	63192
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	42564

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	13230
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	33268
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	19717
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	6226
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	11359
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	4246
k_ISDATDIRASentDiag_Cnt_str.Threshold	1783
k_ISDATDIRASentDiag_Cnt_str.PStep	44131
k_ISDATDIRASentDiag_Cnt_str.NStep	4476
k_ISDATDIRASentTimeout_mS_u16	56785
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	35643
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	45202
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	818
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	40949
k_ISDYNAASChkSumValidThresh_Cnt_u16	30982
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	1902
k_ISDYNAASMsgCountValidThresh_Cnt_u16	36631
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	12057
k_ISDYNAASMsgLenValidThresh_Cnt_u16	35192
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	64130
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	26814
k_ISDYNABRChkSumValidThresh_Cnt_u16	63512
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	17248
k_ISDYNABRMsgCountValidThresh_Cnt_u16	37866
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	13757
k_ISDYNABRMsgLenValidThresh_Cnt_u16	16707
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	29545
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	18071
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	34793
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	5203
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	36457
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	17331
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	25886
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	64051
k_ISDYNVOLChkSumValidThresh_Cnt_u16	48225
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	3696
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	56106
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	7526
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	29020
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	21072
k_IgnOnTimeout_mS_u16	57103
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	255
k_PowerCutVehSpdLowThresh_Kph_f32	87.5064011
k_PowerCutVehSpdLowTimeout_mS_u16	57737
k_VBattMaxAAS_Volt_f32	29.6536999
k_VBattMaxBSI_Volt_f32	30.0508003
k_VBattMaxCAV_Volt_f32	0.482499987
k_VBattMaxCMM388_Volt_f32	4.92000008
k_VBattMaxCMM_Volt_f32	26.2343006
k_VBattMaxESP_Volt_f32	19.0657997
k_VBattMinAAS_Volt_f32	8.32050037
k_VBattMinBSI_Volt_f32	19.0657997
k_VBattMinCAV_Volt_f32	29.7308006
k_VBattMinCMM388_Volt_f32	14.3450003
k_VBattMinCMM_Volt_f32	5.47310019
k_VBattMinESP_Volt_f32	26.2343006
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	12165
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	22243
k_VitesseVehicleBVRampValidThresh_Cnt_u16	31280
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	56033
k_VitesseVehicleBVSigValidThresh_Cnt_u16	3118
k_VitesseVehicleBVSpeedPassThresh_kph_f32	588.809387
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	14826
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	25867
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	237573632
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	43
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	50617
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3145115648
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	131
target_SrlComInput_Per1_Batt_Volt_f32.value	9.42910004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	850462208
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	84
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.113422766
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	199
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	166278656
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2654623232
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	928740864
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3712783872
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2551035392
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1872680448
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	176
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1811936768
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	94
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	109
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	158
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	188
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1714787840
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	115
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	185
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	10
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2539927040
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1328895488
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	188
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3419829760
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	58
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	123
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	153
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	193
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2331543040
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1984
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.464687586
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	2937
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	161.619003
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	52797

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3145115648	3145115648	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3145115648	3145115648	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3145115648	3145115648	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3145115648	3145115648	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3145115648	3145115648	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3145115648	3145115648	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3145115648	3145115648	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3145115648	3145115648	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3145115648	3145115648	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	56888	56888	✔
CAVNodeAbsentTimer_mS_M_u32	3145115648	3145115648	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3145115648	3145115648	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3145115648	3145115648	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	38628	38628	✔
CMMNodeAbsentTimer_mS_M_u32	3145115648	3145115648	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	8654	8654	✔
CONSANGLECPK_HwDeg_M_f32	457.626801	457.626801 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3145115648	3145115648	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3145115648	3145115648	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3145115648	3145115648	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3145115648	3145115648	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3145115648	3145115648	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3145115648	3145115648	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3145115648	3145115648	✔
ESPNTCEnableTimer_mS_M_u32	3145115648	3145115648	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3145115648	3145115648	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	3145115648	3145115648	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3145115648	3145115648	✔
ElecIntCount_Cnt_M_u08	2	2	✔
ElecIntTimer_mS_M_u32[0]	10	10	✔
ElecIntTimer_mS_M_u32[1]	3145115648	3145115648	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3145115648	3145115648	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3145115648	3145115648	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3145115648	3145115648	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3145115648	3145115648	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3145115648	3145115648	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1783	1783	✔
ISDATDIRASentTimer_mS_M_u32	3145115648	3145115648	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3145115648	3145115648	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3145115648	3145115648	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3145115648	3145115648	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3145115648	3145115648	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3145115648	3145115648	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3145115648	3145115648	✔
IgnOnTimer_mS_M_u32	3145115648	3145115648	✔
IgnTimeOff_Sec_M_u32	2715648403	2715648403	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	199	199	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	166278656	166278656	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	123	123	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2654623232	2654623232	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	49	49	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	928740864	928740864	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	240	240	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3712783872	3712783872	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3123738112	3123738112	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	167	167	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1872680448	1872680448	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	176	176	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1811936768	1811936768	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	133	133	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1714787840	1714787840	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	10	10	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2539927040	2539927040	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	131	131	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1328895488	1328895488	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	188	188	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3419829760	3419829760	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2331543040	2331543040	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	437.417694	437.417694	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	527.969971	527.969971	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	100.536003	100.536003	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	8654	8654	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2715648403	2715648403	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	457.626801	457.626801 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	181.640701	181.640701	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.6 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3404861696
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	29318
AASNodeAbsentTimer_mS_M_u32	4220141824
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	24697
ANGLEVOLANTSigValidCount_Cnt_M_u16	12892
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	25343
AngleVolantMsgTimer_mS_M_u32	3404861696
AngleVolantValidCount_Cnt_M_u16	61914
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1465843968
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1090224384
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3728224512
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3075469568
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	56724
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1054257408
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	34424
CAVNodeAbsentTimer_mS_M_u32	1456759040
CDD_SrlComVehSpd_Kph_G_f32	133.888702
CMM388NTCEnableTimer_mS_M_u32	4137394432
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	967991552
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	32189
CMMNodeAbsentTimer_mS_M_u32	3908169984
CONSANGLECPKSigInvalidCount_Cnt_M_u16	15913
CONSANGLECPKSigValidCount_Cnt_M_u16	63261
CONSANGLECPK_Cnt_M_u16	55820
CONSANGLECPK_HwDeg_M_f32	-700.358215
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	55820
CPKVehicleSpeedMsgTimer_mS_M_u32	3555004672
CPKVehicleSpeedValidCount_Cnt_M_u16	20490
CityParkInputConsistentCount_Cnt_M_u16	65390
CityParkInputInvalidCount_Cnt_M_u16	19202

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	166278656
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1847476480
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	40474
ComputerRazGCTSigInvalidTimer_mS_M_u32	1870323968
ComputerRazGCTSigValidCount_Cnt_M_u16	7999
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	26990
DMDFCTCPKSigValidCount_Cnt_M_u16	64154
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	37443
DMDRELAXECPKSigValidCount_Cnt_M_u16	1958
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	21410
DateInvalidTimer_mS_M_u32	1090224384
DiagMuxOnAbsentTimer_mS_M_u32	3956855040
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3075469568
ESPNTCEnableTimer_mS_M_u32	3344384256
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	15597
EffacDefaultDiagCount_Cnt_M_u08	2
EffacDefaultDiagTimer_mS_M_u32[0]	180
EffacDefaultDiagTimer_mS_M_u32[1]	500878080
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	655
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3749753088
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	36949
EtatMTSigValidCount_Cnt_M_u16	15669
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	19955
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	10855
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20344
ISDAT4V2BSI552MsgTimer_mS_M_u32	3800428800
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	34891
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	35795
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	15669
ISDATBSI3F2MsgTimer_mS_M_u32	336515328
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	63509
ISDATBSI412MsgLenValidCount_Cnt_M_u16	7180
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	36949
ISDATBSI412MsgTimer_mS_M_u32	1093144832
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	15953
ISDATBSI432MsgLenValidCount_Cnt_M_u16	1153
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	52965
ISDATDIRASentFltAcc_Cnt_M_u16	38729
ISDATDIRASentTimer_mS_M_u32	3555004672
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	57026
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	61914
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	21001
ISDYN2CMMMsgTimer_mS_M_u32	3145285888
ISDYNAASChkSumInvalidCount_Cnt_M_u16	16464
ISDYNAASChkSumValidCount_Cnt_M_u16	27860
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	10357
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	41127
ISDYNAASMsgLenValidCount_Cnt_M_u16	1603
ISDYNAASMsgTimeValidCount_Cnt_M_u16	16464
ISDYNAASMsgTimer_mS_M_u32	369598720
ISDYNABRChkSumInvalidCount_Cnt_M_u16	37206
ISDYNABRChkSumValidCount_Cnt_M_u16	6114
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	42859
ISDYNABRMsgCountValidCount_Cnt_M_u16	33327
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	52292
ISDYNABRMsgLenValidCount_Cnt_M_u16	29560
ISDYNABRMsgTimeValidCount_Cnt_M_u16	55820
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	559
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1003

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	15669
ISDYNCMM208MsgTimer_mS_M_u32	3731882240
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2087
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1109
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	49936
ISDYNCMM388MsgTimer_mS_M_u32	3396673792
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	48735
ISDYNVOLChkSumValidCount_Cnt_M_u16	21459
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	20644
ISDYNVOLMsgCountValidCount_Cnt_M_u16	65104
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	39122
ISDYNVOLMsgLenValidCount_Cnt_M_u16	55078
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	32189
ISDYNVOLMsgTimer_mS_M_u32	1256644864
IgnOnTimer_mS_M_u32	3809026304
IgnTimeOff_Sec_M_u32	652166093
ManVehSpd_Kph_M_f32	215.492401
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	76
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	17
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	692900096
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	5
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1790128384
PrevISDATBSI412MsgDLCError_Cnt_M_u08	26
PrevISDATBSI412MsgRxTime_MSec_M_u32	117530880
PrevISDATBSI432MsgDLCError_Cnt_M_u08	125
PrevISDATBSI432MsgRxTime_MSec_M_u32	647708928
PrevISDATDIRAMsgTxTime_MSec_M_u32	308633856
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	229
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2336715008
PrevISDYNAASMsgDLCError_Cnt_M_u08	124
PrevISDYNAASMsgRxTime_MSec_M_u32	4154253568
PrevISDYNABRMsgDLCError_Cnt_M_u08	125
PrevISDYNABRMsgRxTime_MSec_M_u32	3638632704
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	253
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2385371392
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	42
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1653227776
PrevISDYNVOLMsgDLCError_Cnt_M_u08	229
PrevISDYNVOLMsgRxTime_MSec_M_u32	1737122048
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1851658496
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	618.216919
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	54749
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	55289
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	35138
VitesseVehicleBVRampValidCount_Cnt_M_u16	48414
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	18270
VitesseVehicleBVSigValidCount_Cnt_M_u16	60161
VitesseVehicleBV_Kph_M_f32	587.919128

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	49936
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	65035
VitesseVehiculeRoues_Kph_M_f32	30.3153
k_AASNTCEnableTimeout_mS_u16	9279
k_AASNodeAbsentDiag_Cnt_str.Threshold	50758
k_AASNodeAbsentDiag_Cnt_str.PStep	22002
k_AASNodeAbsentDiag_Cnt_str.NStep	51844
k_AASNodeAbsentTimeout_mS_u16	37345
k_AASNodeTimeout_mS_u16	48889
k_ABSNodeTimeout_mS_u16	319
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	11928
k_ANGLEVOLANTSigValidThresh_Cnt_u16	27656
k_AngleVolantInvalidThresh_Cnt_u16	16459
k_AngleVolantValidThresh_Cnt_u16	19202
k_BSI552MsgTimeout_mS_u16	54286
k_BSINTCEnableTimeout_mS_u16	58409
k_BSINodeAbsentDiag_Cnt_str.Threshold	19772
k_BSINodeAbsentDiag_Cnt_str.PStep	37137
k_BSINodeAbsentDiag_Cnt_str.NStep	11462
k_BSINodeAbsentTimeout_mS_u16	21207
k_BSINodeTimeout_mS_u16	52965
k_BattOvHi_Volt_f32	7.87340021
k_BattOvLo_Volt_f32	13.8445997
k_BattUvHi_Volt_f32	19.9719009
k_BattUvLo_Volt_f32	4.31290007
k_CAVNTCEnableTimeout_mS_u16	30224
k_CAVNodeAbsentDiag_Cnt_str.Threshold	31165
k_CAVNodeAbsentDiag_Cnt_str.PStep	35525
k_CAVNodeAbsentDiag_Cnt_str.NStep	54112
k_CAVNodeAbsentTimeout_mS_u16	47790
k_CAVNodeTimeout_mS_u16	62869
k_CMM388MsgTimeout_mS_u16	39302
k_CMM388NTCEnableTimeout_mS_u16	44530
k_CMMNTCEnableTimeout_mS_u16	55843
k_CMMNodeAbsentDiag_Cnt_str.Threshold	60130
k_CMMNodeAbsentDiag_Cnt_str.PStep	30156
k_CMMNodeAbsentDiag_Cnt_str.NStep	33514
k_CMMNodeAbsentTimeout_mS_u16	28791
k_CONSANGLECPKMax_HwDeg_f32	75.6207962
k_CONSANGLECPKMin_HwDeg_f32	-102.568604
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	27152
k_CONSANGLECPKSigValidThresh_Cnt_u16	58635
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	4823
k_CPKVehicleSpeedValidThresh_Cnt_u16	40196
k_CityParkInputInvalidThresh_Cnt_u16	47028
k_CityParkInputValidThresh_Cnt_u16	65390
k_ComputerRazGCTSigValidThresh_Cnt_u16	42505
k_CptTemporelSigValidThresh_Cnt_u16	7185
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	62276
k_DMDFCTCPKSigValidThresh_Cnt_u16	55928
k_DMDFCTCPKValidCount_Cnt_u16	58556
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	21001
k_DMDRELAXECPKSigValidThresh_Cnt_u16	45429
k_DMDRelaxeConsistentThresh_Cnt_u16	51027
k_DateValidThresh_Cnt_u16	20344
k_DefaultVehSpd_Kph_f32	34.2918015
k_DiagMuxOnAbsentTimeout_mS_u16	63642
k_EMNodeTimeout_mS_u16	12674
k_ESPNTCEnableTimeout_mS_u16	55268
k_ESPNodeAbsentDiag_Cnt_str.Threshold	42098
k_ESPNodeAbsentDiag_Cnt_str.PStep	11728
k_ESPNodeAbsentDiag_Cnt_str.NStep	50695
k_ESPNodeAbsentTimeout_mS_u16	45727
k_EtatMTSigInvalidThresh_Cnt_u16	27129
k_EtatMTSigValidThresh_Cnt_u16	13509
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	35878
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	52326
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	48339
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	19812
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	8620
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	18089
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	28394
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	42458

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	16101
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	1664
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	3096
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	8370
k_ISDATDIRASentDiag_Cnt_str.Threshold	25599
k_ISDATDIRASentDiag_Cnt_str.PStep	36883
k_ISDATDIRASentDiag_Cnt_str.NStep	21089
k_ISDATDIRASentTimeout_mS_u16	61122
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	33987
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	25343
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	61856
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	14422
k_ISDYNAASChkSumValidThresh_Cnt_u16	65250
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	52843
k_ISDYNAASMsgCountValidThresh_Cnt_u16	59695
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	6890
k_ISDYNAASMsgLenValidThresh_Cnt_u16	50317
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	62512
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	15226
k_ISDYNABRChkSumValidThresh_Cnt_u16	65326
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	1172
k_ISDYNABRMsgCountValidThresh_Cnt_u16	17591
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	25789
k_ISDYNABRMsgLenValidThresh_Cnt_u16	25581
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	25146
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	64369
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	30138
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	20476
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	34681
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	39260
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	28378
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	50908
k_ISDYNVOLChkSumValidThresh_Cnt_u16	16915
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	61542
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	26742
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	58049
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	51361
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	30982
k_IgnOnTimeout_mS_u16	34888
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	123.405502
k_PowerCutVehSpdLowThresh_Kph_f32	59.1945992
k_PowerCutVehSpdLowTimeout_mS_u16	18139
k_VBattMaxAAS_Volt_f32	9.67959976
k_VBattMaxBSI_Volt_f32	28.4043007
k_VBattMaxCAV_Volt_f32	20.2040997
k_VBattMaxCMM388_Volt_f32	6.18260002
k_VBattMaxCMM_Volt_f32	2.01990008
k_VBattMaxESP_Volt_f32	4.28630018
k_VBattMinAAS_Volt_f32	9.96749973
k_VBattMinBSI_Volt_f32	4.28630018
k_VBattMinCAV_Volt_f32	19.3097
k_VBattMinCMM388_Volt_f32	27.6331997
k_VBattMinCMM_Volt_f32	25.3416996
k_VBattMinESP_Volt_f32	2.01990008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	16357
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	19340
k_VitesseVehicleBVRampValidThresh_Cnt_u16	63396
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	47827
k_VitesseVehicleBVSigValidThresh_Cnt_u16	26795
k_VitesseVehicleBVSpeedPassThresh_kph_f32	590.27832
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	11640
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	15828
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1090224384
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	77
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16 Elaps	6315
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	500878080
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	42

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	31
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	522432768
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	247
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.408612341
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	96
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4131070208
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1707589888
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	115630336
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3247505664
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2110628096
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	597311744
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2599870720
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	47
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	72
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	148
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	212
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	220
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	254
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	181797120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	105
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	166
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	176
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	65
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4190773504
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4275486976
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4117979392
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	20
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	218
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	245
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2488086784
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3609
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.014880891
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1038021
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	148.106903
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	31871

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	500878080	500878080	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	500878080	500878080	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	25343	25343	✔
AngleVolantMsgTimer_mS_M_u32	500878080	500878080	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	500878080	500878080	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	500878080	500878080	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	500878080	500878080	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	500878080	500878080	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	500878080	500878080	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	500878080	500878080	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	31165	31165	✔
CAVNodeAbsentTimer_mS_M_u32	500878080	500878080	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	500878080	500878080	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	500878080	500878080	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	60130	60130	✔
CMMNodeAbsentTimer_mS_M_u32	500878080	500878080	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	55820	55820	✔
CONSANGLECPK_HwDeg_M_f32	-700.358215	-700.358215 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	55820	55820	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3555004672	3555004672	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	20490	20490	✔
CityParkInputConsistentCount_Cnt_M_u16	65390	65390	✔
CityParkInputInvalidCount_Cnt_M_u16	19204	19204	✔
CityParkInputMsgTimer_mS_M_u32	500878080	500878080	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	500878080	500878080	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	500878080	500878080	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	500878080	500878080	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	500878080	500878080	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	500878080	500878080	✔
ESPNTCEnableTimer_mS_M_u32	500878080	500878080	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	500878080	500878080	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	500878080	500878080	✔
EffacDefaultDiagTimer_mS_M_u32[1]	500878080	500878080	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	500878080	500878080	✔
ElecIntTimer_mS_M_u32[1]	655	655	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	500878080	500878080	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	500878080	500878080	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	500878080	500878080	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	500878080	500878080	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	500878080	500878080	✔
ISDATDIRASentFltAcc_Cnt_M_u16	25599	25599	✔
ISDATDIRASentTimer_mS_M_u32	500878080	500878080	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	500878080	500878080	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	500878080	500878080	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	500878080	500878080	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	500878080	500878080	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	500878080	500878080	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	500878080	500878080	✔
IgnOnTimer_mS_M_u32	500878080	500878080	✔
IgnTimeOff_Sec_M_u32	652166093	652166093	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	96	96	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4131070208	4131070208	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	206	206	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1707589888	1707589888	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	121	121	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	115630336	115630336	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	74	74	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3247505664	3247505664	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	308633856	308633856	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	253	253	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	597311744	597311744	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	174	174	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2599870720	2599870720	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	181797120	181797120	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	65	65	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4190773504	4190773504	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4275486976	4275486976	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	133	133	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4117979392	4117979392	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2488086784	2488086784	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	618.216919	618.216919	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	587.919128	587.919128	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	30.3153	30.3153	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	55820	55820	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	652166093	652166093	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-700.358215	-700.358215 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	34.2918015	34.2918015	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.7 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2085392384
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	30607
AASNodeAbsentTimer_mS_M_u32	3343122432
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	38839
ANGLEVOLANTSigValidCount_Cnt_M_u16	36044
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	51748
AngleVolantMsgTimer_mS_M_u32	2085392384
AngleVolantValidCount_Cnt_M_u16	20500
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	4140154880
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1274036224
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2197434368
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	112390144
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	19558
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	4213092352
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	11320
CAVNodeAbsentTimer_mS_M_u32	98934784
CDD_SrlComVehSpd_Kph_G_f32	409.492706
CMM388NTCEnableTimer_mS_M_u32	1401937920
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1431019520
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	50729
CMMNodeAbsentTimer_mS_M_u32	2043473920
CONSANGLECPKSigInvalidCount_Cnt_M_u16	45477
CONSANGLECPKSigValidCount_Cnt_M_u16	12682
CONSANGLECPK_Cnt_M_u16	1213
CONSANGLECPK_HwDeg_M_f32	587.110596
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	1213
CPKVehicleSpeedMsgTimer_mS_M_u32	3983773696
CPKVehicleSpeedValidCount_Cnt_M_u16	16651
CityParkInputConsistentCount_Cnt_M_u16	30552

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	13723
CityParkInputMsgTimer_mS_M_u32	4131070208
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3213361152
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	17619
ComputerRazGCTSigInvalidTimer_mS_M_u32	1978802176
ComputerRazGCTSigValidCount_Cnt_M_u16	39909
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	35415
DMDFCTCPKSigValidCount_Cnt_M_u16	24980
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	43609
DMDRELAXECPKSigValidCount_Cnt_M_u16	46318
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	38202
DateInvalidTimer_mS_M_u32	1274036224
DiagMuxOnAbsentTimer_mS_M_u32	613961728
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	112390144
ESPNTCEnableTimer_mS_M_u32	3621584896
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	9050
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	54
EffacDefaultDiagTimer_mS_M_u32[1]	64
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	653943296
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1092661248
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	16225
EtatMTSigValidCount_Cnt_M_u16	37762
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	10823
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	16300
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	23290
ISDAT4V2BSI552MsgTimer_mS_M_u32	3708874752
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1791
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	63272
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	37762
ISDATBSI3F2MsgTimer_mS_M_u32	66473984
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	27811
ISDATBSI412MsgLenValidCount_Cnt_M_u16	47996
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	16225
ISDATBSI412MsgTimer_mS_M_u32	1907003392
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	54381
ISDATBSI432MsgLenValidCount_Cnt_M_u16	7326
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	18161
ISDATDIRASentFltAcc_Cnt_M_u16	32197
ISDATDIRASentTimer_mS_M_u32	3983773696
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	20123
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	20500
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	64646
ISDYN2CMMMsgTimer_mS_M_u32	58130432
ISDYNAASChkSumInvalidCount_Cnt_M_u16	46641
ISDYNAASChkSumValidCount_Cnt_M_u16	7014
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	55363
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	22955
ISDYNAASMsgLenValidCount_Cnt_M_u16	29592
ISDYNAASMsgTimeValidCount_Cnt_M_u16	46641
ISDYNAASMsgTimer_mS_M_u32	2773213184
ISDYNABRChkSumInvalidCount_Cnt_M_u16	21661
ISDYNABRChkSumValidCount_Cnt_M_u16	52154
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	44256
ISDYNABRMsgCountValidCount_Cnt_M_u16	1877
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	13140
ISDYNABRMsgLenValidCount_Cnt_M_u16	59513
ISDYNABRMsgTimeValidCount_Cnt_M_u16	1213
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	560

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1005
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	37762
ISDYNCMM208MsgTimer_mS_M_u32	3851599872
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2091
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1111
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	13426
ISDYNCMM388MsgTimer_mS_M_u32	503537664
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	35075
ISDYNVOLChkSumValidCount_Cnt_M_u16	29544
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	11445
ISDYNVOLMsgCountValidCount_Cnt_M_u16	44658
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	58283
ISDYNVOLMsgLenValidCount_Cnt_M_u16	21360
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	50729
ISDYNVOLMsgTimer_mS_M_u32	2477662208
IgnOnTimer_mS_M_u32	608657408
IgnTimeOff_Sec_M_u32	1323641717
ManVehSpd_Kph_M_f32	33.2853012
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	78
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	61
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1010585600
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	185
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2307469312
PrevISDATBSI412MsgDLCError_Cnt_M_u08	170
PrevISDATBSI412MsgRxTime_MSec_M_u32	3915292672
PrevISDATBSI432MsgDLCError_Cnt_M_u08	241
PrevISDATBSI432MsgRxTime_MSec_M_u32	3390111744
PrevISDATDIRAMsgTxTime_MSec_M_u32	1462935552
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	120
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3368841216
PrevISDYNAASMsgDLCError_Cnt_M_u08	29
PrevISDYNAASMsgRxTime_MSec_M_u32	3851165696
PrevISDYNABRMsgDLCError_Cnt_M_u08	93
PrevISDYNABRMsgRxTime_MSec_M_u32	2730450944
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	253
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2782470144
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	184
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2453929984
PrevISDYNVOLMsgDLCError_Cnt_M_u08	96
PrevISDYNVOLMsgRxTime_MSec_M_u32	734240768
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1107857408
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	438.400787
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	4617
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	22134
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	52186
VitesseVehicleBVRampValidCount_Cnt_M_u16	31495
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	46856
VitesseVehicleBVSigValidCount_Cnt_M_u16	14045

Name	Input Value
VitesseVehicleBV_Kph_M_f32	639.538696
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	13426
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	20031
VitesseVehiculeRoues_Kph_M_f32	434.346008
k_AASNTCEnableTimeout_mS_u16	45604
k_AASNodeAbsentDiag_Cnt_str.Threshold	48358
k_AASNodeAbsentDiag_Cnt_str.PStep	38810
k_AASNodeAbsentDiag_Cnt_str.NStep	3549
k_AASNodeAbsentTimeout_mS_u16	19455
k_AASNodeTimeout_mS_u16	41334
k_ABSNodeTimeout_mS_u16	18148
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	57240
k_ANGLEVOLANTSigValidThresh_Cnt_u16	49673
k_AngleVolantInvalidThresh_Cnt_u16	4416
k_AngleVolantValidThresh_Cnt_u16	13723
k_BSI552MsgTimeout_mS_u16	38966
k_BSINTCEnableTimeout_mS_u16	17125
k_BSINodeAbsentDiag_Cnt_str.Threshold	19812
k_BSINodeAbsentDiag_Cnt_str.PStep	37120
k_BSINodeAbsentDiag_Cnt_str.NStep	11485
k_BSINodeAbsentTimeout_mS_u16	23196
k_BSINodeTimeout_mS_u16	18161
k_BattOvHi_Volt_f32	12.3564997
k_BattOvLo_Volt_f32	12.6924
k_BattUvHi_Volt_f32	24.1126995
k_BattUvLo_Volt_f32	21.6732006
k_CAVNTCEnableTimeout_mS_u16	27761
k_CAVNodeAbsentDiag_Cnt_str.Threshold	26331
k_CAVNodeAbsentDiag_Cnt_str.PStep	21178
k_CAVNodeAbsentDiag_Cnt_str.NStep	30752
k_CAVNodeAbsentTimeout_mS_u16	59286
k_CAVNodeTimeout_mS_u16	15201
k_CMM388MsgTimeout_mS_u16	655
k_CMM388NTCEnableTimeout_mS_u16	30027
k_CMMNTCEnableTimeout_mS_u16	29047
k_CMMNodeAbsentDiag_Cnt_str.Threshold	57844
k_CMMNodeAbsentDiag_Cnt_str.PStep	37869
k_CMMNodeAbsentDiag_Cnt_str.NStep	49548
k_CMMNodeAbsentTimeout_mS_u16	42747
k_CONSANGLECPKMax_HwDeg_f32	246.422806
k_CONSANGLECPKMin_HwDeg_f32	-60.8378983
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	16242
k_CONSANGLECPKSigValidThresh_Cnt_u16	39231
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	40412
k_CPKVehicleSpeedValidThresh_Cnt_u16	63958
k_CityParkInputInvalidThresh_Cnt_u16	55683
k_CityParkInputValidThresh_Cnt_u16	30552
k_ComputerRazGCTSigValidThresh_Cnt_u16	9669
k_CptTemporelSigValidThresh_Cnt_u16	48750
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	48724
k_DMDFCTCPKSigValidThresh_Cnt_u16	45945
k_DMDFCTCPKValidCount_Cnt_u16	55022
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	64646
k_DMDRELAXECPKSigValidThresh_Cnt_u16	26883
k_DMDRelaxeConsistentThresh_Cnt_u16	8041
k_DateValidThresh_Cnt_u16	23290
k_DefaultVehSpd_Kph_f32	32.7605019
k_DiagMuxOnAbsentTimeout_mS_u16	24851
k_EMNodeTimeout_mS_u16	31642
k_ESPNTCEnableTimeout_mS_u16	59380
k_ESPNodeAbsentDiag_Cnt_str.Threshold	21922
k_ESPNodeAbsentDiag_Cnt_str.PStep	59714
k_ESPNodeAbsentDiag_Cnt_str.NStep	27284
k_ESPNodeAbsentTimeout_mS_u16	32899
k_EtatMTSigInvalidThresh_Cnt_u16	5812
k_EtatMTSigValidThresh_Cnt_u16	49425
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	11759
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	18416
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	4905
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	23476
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	55709
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	53479
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	59042

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	56467
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	8881
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	20321
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	31066
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	63436
k_ISDATDIRASentDiag_Cnt_str.Threshold	31379
k_ISDATDIRASentDiag_Cnt_str.PStep	337
k_ISDATDIRASentDiag_Cnt_str.NStep	17822
k_ISDATDIRASentTimeout_mS_u16	60505
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	20377
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	51748
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	35520
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	24477
k_ISDYNAASChkSumValidThresh_Cnt_u16	5818
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	14304
k_ISDYNAASMsgCountValidThresh_Cnt_u16	53845
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	2017
k_ISDYNAASMsgLenValidThresh_Cnt_u16	57530
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	51601
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	15794
k_ISDYNABRChkSumValidThresh_Cnt_u16	40279
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	55142
k_ISDYNABRMsgCountValidThresh_Cnt_u16	33211
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	4393
k_ISDYNABRMsgLenValidThresh_Cnt_u16	44634
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	62770
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	61773
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	51124
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	47725
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	8887
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	22476
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	10771
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	56398
k_ISDYNVOLChkSumValidThresh_Cnt_u16	9575
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	11503
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	10750
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	63517
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	41278
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	38480
k_IgnOnTimeout_mS_u16	18442
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	113.919197
k_PowerCutVehSpdLowThresh_Kph_f32	218.552002
k_PowerCutVehSpdLowTimeout_mS_u16	47696
k_VBattMaxAAS_Volt_f32	15.5157003
k_VBattMaxBSI_Volt_f32	31.5935001
k_VBattMaxCAV_Volt_f32	16.9101009
k_VBattMaxCMM388_Volt_f32	28.1016006
k_VBattMaxCMM_Volt_f32	26.2488003
k_VBattMaxESP_Volt_f32	11.1673002
k_VBattMinAAS_Volt_f32	7.78779984
k_VBattMinBSI_Volt_f32	11.1673002
k_VBattMinCAV_Volt_f32	23.0415993
k_VBattMinCMM388_Volt_f32	12.5728998
k_VBattMinCMM_Volt_f32	7.16909981
k_VBattMinESP_Volt_f32	26.2488003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	9779
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	32251
k_VitesseVehicleBVRampValidThresh_Cnt_u16	14261
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	15976
k_VitesseVehicleBVSigValidThresh_Cnt_u16	28577
k_VitesseVehicleBVSpeedPassThresh_kph_f32	556.187317
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	14136
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	20709
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1274036224
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	30
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	18881
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	653943296
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	184
target_SrlComInput_Per1_Batt_Volt_f32.value	24.3610992
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3459756032
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	137
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.441135198
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	850485248
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1586200576
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	184
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	901095424
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	32
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3129344
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	100261888
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2400452608
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3816693760
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	32
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	50
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	64
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	10
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2019606528
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	46
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	235
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	604266496
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2405335040
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1711841280
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	241
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	243
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4105908224
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1995
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0285641793
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	810052
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	42.0648994

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	9763		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	653943296	653943296	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	653943296	653943296	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	51748	51748	✔
AngleVolantMsgTimer_mS_M_u32	653943296	653943296	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	653943296	653943296	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	653943296	653943296	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	653943296	653943296	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	653943296	653943296	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	653943296	653943296	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	653943296	653943296	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	26331	26331	✔
CAVNodeAbsentTimer_mS_M_u32	653943296	653943296	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	653943296	653943296	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	653943296	653943296	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	57844	57844	✔
CMMNodeAbsentTimer_mS_M_u32	653943296	653943296	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	1213	1213	✔
CONSANGLECPK_HwDeg_M_f32	587.110596	587.110596 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	1213	1213	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3983773696	3983773696	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	16651	16651	✔
CityParkInputConsistentCount_Cnt_M_u16	30552	30552	✔
CityParkInputInvalidCount_Cnt_M_u16	13725	13725	✔
CityParkInputMsgTimer_mS_M_u32	653943296	653943296	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	653943296	653943296	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	653943296	653943296	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	653943296	653943296	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	653943296	653943296	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	653943296	653943296	✔
ESPNTCEnableTimer_mS_M_u32	653943296	653943296	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	653943296	653943296	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	653943296	653943296	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	64	64	✔
ElecIntCount_Cnt_M_u08	2	2	✔
ElecIntTimer_mS_M_u32[0]	8	8	✔
ElecIntTimer_mS_M_u32[1]	653943296	653943296	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	653943296	653943296	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	653943296	653943296	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	653943296	653943296	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	653943296	653943296	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	653943296	653943296	✔
ISDATDIRASentFltAcc_Cnt_M_u16	31379	31379	✔
ISDATDIRASentTimer_mS_M_u32	653943296	653943296	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	653943296	653943296	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	653943296	653943296	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	653943296	653943296	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	653943296	653943296	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	653943296	653943296	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	653943296	653943296	✔
IgnOnTimer_mS_M_u32	608657408	608657408	✔
IgnTimeOff_Sec_M_u32	1323641717	1323641717	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	850485248	850485248	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	31	31	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1586200576	1586200576	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	184	184	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	901095424	901095424	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	32	32	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3129344	3129344	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1462935552	1462935552	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	125	125	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2400452608	2400452608	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	3	3	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3816693760	3816693760	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	10	10	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2019606528	2019606528	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	104	104	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	604266496	604266496	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	88	88	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2405335040	2405335040	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	144	144	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1711841280	1711841280	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4105908224	4105908224	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	438.400787	438.400787	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	639.538696	639.538696	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	434.346008	434.346008	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	1213	1213	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1323641717	1323641717	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	587.110596	587.110596 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	32.7605019	32.7605019	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.8 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4109964032
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	11569
AASNodeAbsentTimer_mS_M_u32	2110964480
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	3768
ANGLEVOLANTSigValidCount_Cnt_M_u16	61241
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	51570
AngleVolantMsgTimer_mS_M_u32	4109964032
AngleVolantValidCount_Cnt_M_u16	40994
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	642614016
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	4040033024
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	527446784
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1732637440
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	27819
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3909268224
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	15796
CAVNodeAbsentTimer_mS_M_u32	3496862464
CDD_SrlComVehSpd_Kph_G_f32	279.360992
CMM388NTCEnableTimer_mS_M_u32	1617896192
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	4198228736
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	61601
CMMNodeAbsentTimer_mS_M_u32	4126667520
CONSANGLECPKSigInvalidCount_Cnt_M_u16	42990
CONSANGLECPKSigValidCount_Cnt_M_u16	10240
CONSANGLECPK_Cnt_M_u16	14951
CONSANGLECPK_HwDeg_M_f32	-325.649902
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	14951
CPKVehicleSpeedMsgTimer_mS_M_u32	4253291264
CPKVehicleSpeedValidCount_Cnt_M_u16	51876
CityParkInputConsistentCount_Cnt_M_u16	14934
CityParkInputInvalidCount_Cnt_M_u16	7308
CityParkInputMsgTimer_mS_M_u32	850485248
CityParkInputValidCount_Cnt_M_u16	0

Name	Input Value
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2768683776
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	54629
ComputerRazGCTSigInvalidTimer_mS_M_u32	1380475648
ComputerRazGCTSigValidCount_Cnt_M_u16	16559
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	3672
DMDFCTCPKSigValidCount_Cnt_M_u16	59489
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	57042
DMDRELAXECPKSigValidCount_Cnt_M_u16	32467
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	37167
DateInvalidTimer_mS_M_u32	4040033024
DiagMuxOnAbsentTimer_mS_M_u32	3675640576
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1732637440
ESPNTCEnableTimer_mS_M_u32	4027040512
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	2254
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	79
ElecIntTimer_mS_M_u32[1]	699
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2667361024
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	29179
EtatMTSigValidCount_Cnt_M_u16	25944
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	17928
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1434
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	5167
ISDAT4V2BSI552MsgTimer_mS_M_u32	3693867776
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	3232
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	19429
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	25944
ISDATBSI3F2MsgTimer_mS_M_u32	888918784
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	48307
ISDATBSI412MsgLenValidCount_Cnt_M_u16	40936
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	29179
ISDATBSI412MsgTimer_mS_M_u32	215945984
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	54741
ISDATBSI432MsgLenValidCount_Cnt_M_u16	11522
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	4489
ISDATDIRASentFltAcc_Cnt_M_u16	48397
ISDATDIRASentTimer_mS_M_u32	4253291264
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	21709
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	40994
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	13259
ISDYN2CMMMsgTimer_mS_M_u32	1429848832
ISDYNAASChkSumInvalidCount_Cnt_M_u16	31051
ISDYNAASChkSumValidCount_Cnt_M_u16	35180
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	33685
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	16731
ISDYNAASMsgLenValidCount_Cnt_M_u16	4948
ISDYNAASMsgTimeValidCount_Cnt_M_u16	31051
ISDYNAASMsgTimer_mS_M_u32	1530602240
ISDYNABRChkSumInvalidCount_Cnt_M_u16	59780
ISDYNABRChkSumValidCount_Cnt_M_u16	25582
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	4414
ISDYNABRMsgCountValidCount_Cnt_M_u16	16799
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	40673
ISDYNABRMsgLenValidCount_Cnt_M_u16	32563
ISDYNABRMsgTimeValidCount_Cnt_M_u16	14951
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	561
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1007
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	25944
ISDYNCMM208MsgTimer_mS_M_u32	3454436096

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2095
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1113
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	60168
ISDYNCMM388MsgTimer_mS_M_u32	789881600
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	6612
ISDYNVOLChkSumValidCount_Cnt_M_u16	23142
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	7998
ISDYNVOLMsgCountValidCount_Cnt_M_u16	63943
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	19419
ISDYNVOLMsgLenValidCount_Cnt_M_u16	31820
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	61601
ISDYNVOLMsgTimer_mS_M_u32	3910427392
IgnOnTimer_mS_M_u32	742957824
IgnTimeOff_Sec_M_u32	2130229766
ManVehSpd_Kph_M_f32	489.491608
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	80
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	244
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	606720768
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	121
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	130233088
PrevISDATBSI412MsgDLCError_Cnt_M_u08	23
PrevISDATBSI412MsgRxTime_MSec_M_u32	1241703168
PrevISDATBSI432MsgDLCError_Cnt_M_u08	244
PrevISDATBSI432MsgRxTime_MSec_M_u32	3916153600
PrevISDATDIRAMsgTxTime_MSec_M_u32	1351017216
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	23
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1727623936
PrevISDYNAASMsgDLCError_Cnt_M_u08	239
PrevISDYNAASMsgRxTime_MSec_M_u32	3950666496
PrevISDYNABRMsgDLCError_Cnt_M_u08	103
PrevISDYNABRMsgRxTime_MSec_M_u32	2430640896
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	39
PrevISDYNCMM208MsgRxTime_MSec_M_u32	512975616
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	51
PrevISDYNCMM388MsgRxTime_MSec_M_u32	483574528
PrevISDYNVOLMsgDLCError_Cnt_M_u08	173
PrevISDYNVOLMsgRxTime_MSec_M_u32	1456726784
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2479166208
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	341.338501
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	4161
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	25274
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	26318
VitesseVehicleBVRampValidCount_Cnt_M_u16	30983
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	13509
VitesseVehicleBVSigValidCount_Cnt_M_u16	29958
VitesseVehicleBV_Kph_M_f32	63.5312004
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	60168
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	15713

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	406.061401
k_AASNTCEnableTimeout_mS_u16	36402
k_AASNodeAbsentDiag_Cnt_str.Threshold	64356
k_AASNodeAbsentDiag_Cnt_str.PStep	44576
k_AASNodeAbsentDiag_Cnt_str.NStep	44911
k_AASNodeAbsentTimeout_mS_u16	6241
k_AASNodeTimeout_mS_u16	33210
k_ABSNodeTimeout_mS_u16	19633
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	8276
k_ANGLEVOLANTSigValidThresh_Cnt_u16	43201
k_AngleVolantInvalidThresh_Cnt_u16	22300
k_AngleVolantValidThresh_Cnt_u16	7308
k_BSI552MsgTimeout_mS_u16	64380
k_BSINTCEnableTimeout_mS_u16	27245
k_BSINodeAbsentDiag_Cnt_str.Threshold	19852
k_BSINodeAbsentDiag_Cnt_str.PStep	37103
k_BSINodeAbsentDiag_Cnt_str.NStep	11508
k_BSINodeAbsentTimeout_mS_u16	63498
k_BSINodeTimeout_mS_u16	4489
k_BattOvHi_Volt_f32	17.6623993
k_BattOvLo_Volt_f32	26.9064007
k_BattUvHi_Volt_f32	0.738799989
k_BattUvLo_Volt_f32	26.3064995
k_CAVNTCEnableTimeout_mS_u16	20490
k_CAVNodeAbsentDiag_Cnt_str.Threshold	4219
k_CAVNodeAbsentDiag_Cnt_str.PStep	53239
k_CAVNodeAbsentDiag_Cnt_str.NStep	16926
k_CAVNodeAbsentTimeout_mS_u16	922
k_CAVNodeTimeout_mS_u16	64186
k_CMM388MsgTimeout_mS_u16	35889
k_CMM388NTCEnableTimeout_mS_u16	9213
k_CMMNTCEnableTimeout_mS_u16	44344
k_CMMNodeAbsentDiag_Cnt_str.Threshold	21401
k_CMMNodeAbsentDiag_Cnt_str.PStep	9605
k_CMMNodeAbsentDiag_Cnt_str.NStep	32194
k_CMMNodeAbsentTimeout_mS_u16	9005
k_CONSANGLECPKMax_HwDeg_f32	187.772903
k_CONSANGLECPKMin_HwDeg_f32	-253.957596
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	51720
k_CONSANGLECPKSigValidThresh_Cnt_u16	23649
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	42120
k_CPKVehicleSpeedValidThresh_Cnt_u16	41242
k_CityParkInputInvalidThresh_Cnt_u16	29394
k_CityParkInputValidThresh_Cnt_u16	14934
k_ComputerRazGCTSigValidThresh_Cnt_u16	18510
k_CptTemporelSigValidThresh_Cnt_u16	36371
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	64993
k_DMDFCTCPKSigValidThresh_Cnt_u16	7731
k_DMDFCTCPKValidCount_Cnt_u16	60691
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	13259
k_DMDRELAXECPKSigValidThresh_Cnt_u16	19988
k_DMDRelaxeConsistentThresh_Cnt_u16	17122
k_DateValidThresh_Cnt_u16	5167
k_DefaultVehSpd_Kph_f32	8.08870029
k_DiagMuxOnAbsentTimeout_mS_u16	64869
k_EMNodeTimeout_mS_u16	24079
k_ESPNTCEnableTimeout_mS_u16	64128
k_ESPNodeAbsentDiag_Cnt_str.Threshold	38766
k_ESPNodeAbsentDiag_Cnt_str.PStep	11624
k_ESPNodeAbsentDiag_Cnt_str.NStep	43912
k_ESPNodeAbsentTimeout_mS_u16	46741
k_EtatMTSigInvalidThresh_Cnt_u16	48959
k_EtatMTSigValidThresh_Cnt_u16	40937
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	79
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	8717
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	60131
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	8833
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	47238
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	40935
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	45878
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	291
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	64265
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	60027

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	48208
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	3130
k_ISDATDIRASentDiag_Cnt_str.Threshold	24019
k_ISDATDIRASentDiag_Cnt_str.PStep	34993
k_ISDATDIRASentDiag_Cnt_str.NStep	64035
k_ISDATDIRASentTimeout_mS_u16	4688
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	30931
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	51570
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	16924
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	51332
k_ISDYNAASChkSumValidThresh_Cnt_u16	33518
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	28734
k_ISDYNAASMsgCountValidThresh_Cnt_u16	57503
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	57272
k_ISDYNAASMsgLenValidThresh_Cnt_u16	54254
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	45609
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	30663
k_ISDYNABRChkSumValidThresh_Cnt_u16	22681
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	52139
k_ISDYNABRMsgCountValidThresh_Cnt_u16	35948
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	4001
k_ISDYNABRMsgLenValidThresh_Cnt_u16	26574
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	52743
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	33397
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	12160
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	53973
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	28088
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	36409
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	7972
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	55730
k_ISDYNVOLChkSumValidThresh_Cnt_u16	52775
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	32783
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	22818
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	14279
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	11300
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	14893
k_IgnOnTimeout_mS_u16	34430
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	255
k_PowerCutVehSpdLowThresh_Kph_f32	205.214203
k_PowerCutVehSpdLowTimeout_mS_u16	9646
k_VBattMaxAAS_Volt_f32	17.9538002
k_VBattMaxBSI_Volt_f32	16.9643993
k_VBattMaxCAV_Volt_f32	13.8673
k_VBattMaxCMM388_Volt_f32	6.91200018
k_VBattMaxCMM_Volt_f32	22.4929008
k_VBattMaxESP_Volt_f32	26.5837994
k_VBattMinAAS_Volt_f32	28.7301998
k_VBattMinBSI_Volt_f32	26.5837994
k_VBattMinCAV_Volt_f32	18.1278992
k_VBattMinCMM388_Volt_f32	6.02839994
k_VBattMinCMM_Volt_f32	26.0746002
k_VBattMinESP_Volt_f32	22.4929008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	56581
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	25962
k_VitesseVehicleBVRampValidThresh_Cnt_u16	65086
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	63846
k_VitesseVehicleBVSigValidThresh_Cnt_u16	46459
k_VitesseVehicleBVSpeedPassThresh_kph_f32	542.406921
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	7348
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	61293
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4040033024
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	53
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	59579
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2864160000
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	51
target_SrlComInput_Per1_Batt_Volt_f32.value	18.5881004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	330806016
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	19
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.626667857
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	688562944
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	905724672
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2164122368
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	839877376
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1899045632
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1717748480
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	201
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	967074560
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	17
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	28
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	36
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	106
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	129
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	156
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3447489280
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	38
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	130
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	155
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1628545792
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2944615168
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4228178688
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	49
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	93
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	138
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	237843200
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	539
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.659092784
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	12193
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	207.925293
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	48115

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2864160000	2864160000	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2864160000	2864160000	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	51570	51570	✔
AngleVolantMsgTimer_mS_M_u32	2864160000	2864160000	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2864160000	2864160000	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2864160000	2864160000	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2864160000	2864160000	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2864160000	2864160000	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2864160000	2864160000	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2864160000	2864160000	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	4219	4219	✔
CAVNodeAbsentTimer_mS_M_u32	2864160000	2864160000	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2864160000	2864160000	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2864160000	2864160000	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	21401	21401	✔
CMMNodeAbsentTimer_mS_M_u32	2864160000	2864160000	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	14951	14951	✔
CONSANGLECPK_HwDeg_M_f32	-325.649902	-325.649902 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	14951	14951	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4253291264	4253291264	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	51876	51876	✔
CityParkInputConsistentCount_Cnt_M_u16	14934	14934	✔
CityParkInputInvalidCount_Cnt_M_u16	7310	7310	✔
CityParkInputMsgTimer_mS_M_u32	2864160000	2864160000	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2864160000	2864160000	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2864160000	2864160000	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2864160000	2864160000	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2864160000	2864160000	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2864160000	2864160000	✔
ESPNTCEnableTimer_mS_M_u32	2864160000	2864160000	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2864160000	2864160000	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2864160000	2864160000	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	699	699	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2864160000	2864160000	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2864160000	2864160000	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2864160000	2864160000	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2864160000	2864160000	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2864160000	2864160000	✔
ISDATDIRASentFltAcc_Cnt_M_u16	24019	24019	✔
ISDATDIRASentTimer_mS_M_u32	2864160000	2864160000	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2864160000	2864160000	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2864160000	2864160000	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2864160000	2864160000	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2864160000	2864160000	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2864160000	2864160000	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2864160000	2864160000	✔
IgnOnTimer_mS_M_u32	2864160000	2864160000	✔
IgnTimeOff_Sec_M_u32	2130229766	2130229766	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	69	69	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	688562944	688562944	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	2	2	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	905724672	905724672	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	105	105	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2164122368	2164122368	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	162	162	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	839877376	839877376	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1351017216	1351017216	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1717748480	1717748480	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	201	201	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	967074560	967074560	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	229	229	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3447489280	3447489280	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	68	68	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1628545792	1628545792	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	99	99	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2944615168	2944615168	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	235	235	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4228178688	4228178688	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	237843200	237843200	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	341.338501	341.338501	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	63.5312004	63.5312004	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	406.061401	406.061401	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	14951	14951	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2130229766	2130229766	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-325.649902	-325.649902 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.9 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2282235136
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	30212
AASNodeAbsentTimer_mS_M_u32	3341767936
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	1983
ANGLEVOLANTSigValidCount_Cnt_M_u16	26569
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	23629
AngleVolantMsgTimer_mS_M_u32	2282235136
AngleVolantValidCount_Cnt_M_u16	16762
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2441090304
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3825505536
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1798849792
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3350988032
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	3402
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	90096896
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	20384
CAVNodeAbsentTimer_mS_M_u32	3013833984
CDD_SrlComVehSpd_Kph_G_f32	431.844391
CMM388NTCEnableTimer_mS_M_u32	1169077504
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3688985856
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	42864
CMMNodeAbsentTimer_mS_M_u32	469632256
CONSANGLECPKSigInvalidCount_Cnt_M_u16	43179
CONSANGLECPKSigValidCount_Cnt_M_u16	9414
CONSANGLECPK_Cnt_M_u16	41573
CONSANGLECPK_HwDeg_M_f32	197.976105
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	41573
CPKVehicleSpeedMsgTimer_mS_M_u32	1290478848
CPKVehicleSpeedValidCount_Cnt_M_u16	61791

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	52558
CityParkInputInvalidCount_Cnt_M_u16	52022
CityParkInputMsgTimer_mS_M_u32	852154880
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1208177920
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	32728
ComputerRazGCTSigInvalidTimer_mS_M_u32	139588864
ComputerRazGCTSigValidCount_Cnt_M_u16	11887
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	11106
DMDFCTCPKSigValidCount_Cnt_M_u16	37173
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	59561
DMDRELAXECPKSigValidCount_Cnt_M_u16	1075
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	17396
DateInvalidTimer_mS_M_u32	3825505536
DiagMuxOnAbsentTimer_mS_M_u32	1292559616
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3350988032
ESPNTCEnableTimer_mS_M_u32	1393317120
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	56455
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	2
ElecIntTimer_mS_M_u32[0]	5
ElecIntTimer_mS_M_u32[1]	155
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4213753088
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	56732
EtatMTSigValidCount_Cnt_M_u16	18275
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	51093
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	32560
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	52083
ISDAT4V2BSI552MsgTimer_mS_M_u32	1406272768
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	18536
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	40279
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	18275
ISDATBSI3F2MsgTimer_mS_M_u32	3860915456
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	19222
ISDATBSI412MsgLenValidCount_Cnt_M_u16	58228
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	56732
ISDATBSI412MsgTimer_mS_M_u32	3474859264
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	54852
ISDATBSI432MsgLenValidCount_Cnt_M_u16	16987
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	18973
ISDATDIRASentFltAcc_Cnt_M_u16	61889
ISDATDIRASentTimer_mS_M_u32	1290478848
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	65531
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	16762
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	13421
ISDYN2CMMMsgTimer_mS_M_u32	835605760
ISDYNAASChkSumInvalidCount_Cnt_M_u16	45806
ISDYNAASChkSumValidCount_Cnt_M_u16	49049
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	63621
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	18559
ISDYNAASMsgLenValidCount_Cnt_M_u16	58818
ISDYNAASMsgTimeValidCount_Cnt_M_u16	45806
ISDYNAASMsgTimer_mS_M_u32	4141528320
ISDYNABRChkSumInvalidCount_Cnt_M_u16	62451
ISDYNABRChkSumValidCount_Cnt_M_u16	64805
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	49785
ISDYNABRMsgCountValidCount_Cnt_M_u16	61796
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	3894
ISDYNABRMsgLenValidCount_Cnt_M_u16	60817
ISDYNABRMsgTimeValidCount_Cnt_M_u16	41573

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	563
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1011
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	18275
ISDYNCMM208MsgTimer_mS_M_u32	2648773888
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2103
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1117
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	21392
ISDYNCMM388MsgTimer_mS_M_u32	3313513728
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	6593
ISDYNVOLChkSumValidCount_Cnt_M_u16	23132
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	13176
ISDYNVOLMsgCountValidCount_Cnt_M_u16	40395
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	32764
ISDYNVOLMsgLenValidCount_Cnt_M_u16	12151
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	42864
ISDYNVOLMsgTimer_mS_M_u32	897447168
IgnOnTimer_mS_M_u32	3428070656
IgnTimeOff_Sec_M_u32	3100509903
ManVehSpd_Kph_M_f32	229.654297
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	84
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	52
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4273923328
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	87
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1310934272
PrevISDATBSI412MsgDLCError_Cnt_M_u08	228
PrevISDATBSI412MsgRxTime_MSec_M_u32	2178970880
PrevISDATBSI432MsgDLCError_Cnt_M_u08	37
PrevISDATBSI432MsgRxTime_MSec_M_u32	3079689472
PrevISDATDIRAMsgTxTime_MSec_M_u32	1552184576
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	117
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2970322176
PrevISDYNAASMsgDLCError_Cnt_M_u08	213
PrevISDYNAASMsgRxTime_MSec_M_u32	3138647296
PrevISDYNABRMsgDLCError_Cnt_M_u08	49
PrevISDYNABRMsgRxTime_MSec_M_u32	363607296
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	51
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2935289088
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	202
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1580160256
PrevISDYNVOLMsgDLCError_Cnt_M_u08	13
PrevISDYNVOLMsgRxTime_MSec_M_u32	3711530240
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4248052992
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	384.578796
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	65173
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	8280
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	20874
VitesseVehicleBVRampValidCount_Cnt_M_u16	12557
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	42548

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	25598
VitesseVehicleBV_Kph_M_f32	463.5242
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	21392
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	29746
VitesseVehiculeRoues_Kph_M_f32	600.457397
k_AASNTCEnableTimeout_mS_u16	3208
k_AASNodeAbsentDiag_Cnt_str.Threshold	62906
k_AASNodeAbsentDiag_Cnt_str.PStep	37259
k_AASNodeAbsentDiag_Cnt_str.NStep	18174
k_AASNodeAbsentTimeout_mS_u16	5041
k_AASNodeTimeout_mS_u16	14168
k_ABSNodeTimeout_mS_u16	33923
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	3259
k_ANGLEVOLANTSigValidThresh_Cnt_u16	13330
k_AngleVolantInvalidThresh_Cnt_u16	19781
k_AngleVolantValidThresh_Cnt_u16	52022
k_BSI552MsgTimeout_mS_u16	6949
k_BSINTCEnableTimeout_mS_u16	53148
k_BSINodeAbsentDiag_Cnt_str.Threshold	19932
k_BSINodeAbsentDiag_Cnt_str.PStep	37069
k_BSINodeAbsentDiag_Cnt_str.NStep	11554
k_BSINodeAbsentTimeout_mS_u16	49061
k_BSINodeTimeout_mS_u16	18973
k_BattOvHi_Volt_f32	22.0778008
k_BattOvLo_Volt_f32	29.8001003
k_BattUvHi_Volt_f32	4.97020006
k_BattUvLo_Volt_f32	11.0712004
k_CAVNTCEnableTimeout_mS_u16	51876
k_CAVNodeAbsentDiag_Cnt_str.Threshold	10497
k_CAVNodeAbsentDiag_Cnt_str.PStep	48135
k_CAVNodeAbsentDiag_Cnt_str.NStep	18837
k_CAVNodeAbsentTimeout_mS_u16	46262
k_CAVNodeTimeout_mS_u16	29143
k_CMM388MsgTimeout_mS_u16	52484
k_CMM388NTCEnableTimeout_mS_u16	816
k_CMMNTCEnableTimeout_mS_u16	44480
k_CMMNodeAbsentDiag_Cnt_str.Threshold	37975
k_CMMNodeAbsentDiag_Cnt_str.PStep	58074
k_CMMNodeAbsentDiag_Cnt_str.NStep	28845
k_CMMNodeAbsentTimeout_mS_u16	26718
k_CONSANGLECPKMax_HwDeg_f32	3.71390009
k_CONSANGLECPKMin_HwDeg_f32	-479.088898
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	10896
k_CONSANGLECPKSigValidThresh_Cnt_u16	35634
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	8342
k_CPKVehicleSpeedValidThresh_Cnt_u16	10933
k_CityParkInputInvalidThresh_Cnt_u16	30641
k_CityParkInputValidThresh_Cnt_u16	52558
k_ComputerRazGCTSigValidThresh_Cnt_u16	4486
k_CptTemporelSigValidThresh_Cnt_u16	41205
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	26166
k_DMDFCTCPKSigValidThresh_Cnt_u16	33937
k_DMDFCTCPKValidCount_Cnt_u16	53490
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	13421
k_DMDRELAXECPKSigValidThresh_Cnt_u16	56448
k_DMDRelaxeConsistentThresh_Cnt_u16	10174
k_DateValidThresh_Cnt_u16	52083
k_DefaultVehSpd_Kph_f32	61.0732994
k_DiagMuxOnAbsentTimeout_mS_u16	44371
k_EMNodeTimeout_mS_u16	30676
k_ESPNTCEnableTimeout_mS_u16	53964
k_ESPNodeAbsentDiag_Cnt_str.Threshold	41623
k_ESPNodeAbsentDiag_Cnt_str.PStep	14225
k_ESPNodeAbsentDiag_Cnt_str.NStep	27746
k_ESPNodeAbsentTimeout_mS_u16	55046
k_EtatMTSigInvalidThresh_Cnt_u16	28550
k_EtatMTSigValidThresh_Cnt_u16	4344
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	12949
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	15804
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	19011
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	30033
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	55040
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	26602

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	1709
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	8068
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	17688
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	62233
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	61208
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	2263
k_ISDATDIRASentDiag_Cnt_str.Threshold	31254
k_ISDATDIRASentDiag_Cnt_str.PStep	2967
k_ISDATDIRASentDiag_Cnt_str.NStep	2760
k_ISDATDIRASentTimeout_mS_u16	17183
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	568
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	23629
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	46920
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	51955
k_ISDYNAASChkSumValidThresh_Cnt_u16	5157
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	6521
k_ISDYNAASMsgCountValidThresh_Cnt_u16	34916
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	48071
k_ISDYNAASMsgLenValidThresh_Cnt_u16	15148
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	51386
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	8012
k_ISDYNABRChkSumValidThresh_Cnt_u16	551
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	25674
k_ISDYNABRMsgCountValidThresh_Cnt_u16	42644
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	48752
k_ISDYNABRMsgLenValidThresh_Cnt_u16	13191
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	60679
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	8809
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	40011
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	2379
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	24255
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	65225
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	41614
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	59405
k_ISDYNVOLChkSumValidThresh_Cnt_u16	7083
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	30160
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	48121
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	45512
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	9359
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	20833
k_IgnOnTimeout_mS_u16	56121
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	105.288696
k_PowerCutVehSpdLowThresh_Kph_f32	56.2027016
k_PowerCutVehSpdLowTimeout_mS_u16	49124
k_VBattMaxAAS_Volt_f32	18.2761002
k_VBattMaxBSI_Volt_f32	1.76610005
k_VBattMaxCAV_Volt_f32	16.2378006
k_VBattMaxCMM388_Volt_f32	3.78430009
k_VBattMaxCMM_Volt_f32	27.4165001
k_VBattMaxESP_Volt_f32	16.4755993
k_VBattMinAAS_Volt_f32	23.9332008
k_VBattMinBSI_Volt_f32	16.4755993
k_VBattMinCAV_Volt_f32	0.377600014
k_VBattMinCMM388_Volt_f32	32
k_VBattMinCMM_Volt_f32	17.8223991
k_VBattMinESP_Volt_f32	27.4165001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	55290
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	48905
k_VitesseVehicleBVRampValidThresh_Cnt_u16	2680
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	61788
k_VitesseVehicleBVSigValidThresh_Cnt_u16	10651
k_VitesseVehicleBVSpeedPassThresh_kph_f32	359.774902
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	9888
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	51875
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3825505536
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	87
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	5149
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2479554304
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	202
target_SrlComInput_Per1_Batt_Volt_f32.value	8.57740021
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	230409472
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	110
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.559739172
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	217
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2133210368
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	102
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	480564480
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1756591360
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3411154176
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2894116096
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1950307584
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2324559104
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	31
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	54
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	61
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	132
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	224
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2317817088
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	88
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	123
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	172
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	180
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	197
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1332032768
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	165
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	979621120
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2482140416
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	37
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	86
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	96
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	188
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2547860736
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1939
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.15397048
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	825782
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	71.103302
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	22487

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2479554304	2479554304	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	62906	62906	✔
AASNodeAbsentTimer_mS_M_u32	2479554304	2479554304	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	23629	23629	✔
AngleVolantMsgTimer_mS_M_u32	2479554304	2479554304	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2479554304	2479554304	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2479554304	2479554304	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2479554304	2479554304	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2479554304	2479554304	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2479554304	2479554304	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2479554304	2479554304	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2479554304	2479554304	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2479554304	2479554304	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2479554304	2479554304	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	14019	14019	✔
CMMNodeAbsentTimer_mS_M_u32	1950307584	1950307584	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	41573	41573	✔
CONSANGLECPK_HwDeg_M_f32	197.976105	197.976105 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	41573	41573	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1290478848	1290478848	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	61791	61791	✔
CityParkInputConsistentCount_Cnt_M_u16	52558	52558	✔
CityParkInputInvalidCount_Cnt_M_u16	52022	52022	✔
CityParkInputMsgTimer_mS_M_u32	2479554304	2479554304	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2479554304	2479554304	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2479554304	2479554304	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	1	1	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2479554304	2479554304	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2479554304	2479554304	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2479554304	2479554304	✔
ESPNTCEnableTimer_mS_M_u32	2479554304	2479554304	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	41623	41623	✔
ESPNodeAbsentTimer_mS_M_u32	2479554304	2479554304	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	2479554304	2479554304	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2479554304	2479554304	✔
ElecIntTimer_mS_M_u32[1]	155	155	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2479554304	2479554304	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2479554304	2479554304	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2479554304	2479554304	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2479554304	2479554304	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2479554304	2479554304	✔
ISDATDIRASentFltAcc_Cnt_M_u16	31254	31254	✔
ISDATDIRASentTimer_mS_M_u32	2479554304	2479554304	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2479554304	2479554304	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2479554304	2479554304	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2479554304	2479554304	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2479554304	2479554304	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2479554304	2479554304	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2479554304	2479554304	✔
IgnOnTimer_mS_M_u32	3428070656	3428070656	✔
IgnTimeOff_Sec_M_u32	3100509903	3100509903	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	217	217	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2133210368	2133210368	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	102	102	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	480564480	480564480	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	110	110	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1756591360	1756591360	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	88	88	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3411154176	3411154176	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1552184576	1552184576	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	117	117	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1950307584	1950307584	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	119	119	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2324559104	2324559104	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	253	253	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2317817088	2317817088	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	170	170	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1332032768	1332032768	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	165	165	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	979621120	979621120	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	218	218	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2482140416	2482140416	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2547860736	2547860736	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	384.578796	384.578796	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	463.5242	463.5242	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	600.457397	600.457397	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	41573	41573	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3100509903	3100509903	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	197.976105	197.976105 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	61.0732994	61.0732994	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.10 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3864679424
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	44644
AASNodeAbsentTimer_mS_M_u32	27575296
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	821
ANGLEVOLANTSigValidCount_Cnt_M_u16	43477
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	24457
AngleVolantMsgTimer_mS_M_u32	3864679424
AngleVolantValidCount_Cnt_M_u16	43651
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3585246208
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2418344960
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2773087232
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1321120768
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	56980
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2429973504
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	14864
CAVNodeAbsentTimer_mS_M_u32	3033031680
CDD_SrlComVehSpd_Kph_G_f32	431.713501
CMM388NTCEnableTimer_mS_M_u32	1000776704
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3020841984
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	40544
CMMNodeAbsentTimer_mS_M_u32	3656954880
CONSANGLECPKSigInvalidCount_Cnt_M_u16	50031
CONSANGLECPKSigValidCount_Cnt_M_u16	21983
CONSANGLECPK_Cnt_M_u16	6402
CONSANGLECPK_HwDeg_M_f32	753.814026
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	6402
CPKVehicleSpeedMsgTimer_mS_M_u32	3820049408
CPKVehicleSpeedValidCount_Cnt_M_u16	49373
CityParkInputConsistentCount_Cnt_M_u16	22279
CityParkInputInvalidCount_Cnt_M_u16	20047
CityParkInputMsgTimer_mS_M_u32	2133210368
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0

Name	Input Value
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3475555328
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	57576
ComputerRazGCTSigInvalidTimer_mS_M_u32	2428298240
ComputerRazGCTSigValidCount_Cnt_M_u16	63396
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	56779
DMDFCTCPKSigValidCount_Cnt_M_u16	37651
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	34935
DMDRELAXECPKSigValidCount_Cnt_M_u16	64663
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	21908
DateInvalidTimer_mS_M_u32	2418344960
DiagMuxOnAbsentTimer_mS_M_u32	307368960
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1321120768
ESPNTCEnableTimer_mS_M_u32	302892032
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	62940
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	79
EffacDefaultDiagTimer_mS_M_u32[1]	699
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1111
ElecIntTimer_mS_M_u32[1]	2222
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1467511808
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	64731
EtatMTSigValidCount_Cnt_M_u16	30279
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	36529
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	28321
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	23641
ISDAT4V2BSI552MsgTimer_mS_M_u32	2189210624
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	17400
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	39916
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	30279
ISDATBSI3F2MsgTimer_mS_M_u32	521147392
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	33008
ISDATBSI412MsgLenValidCount_Cnt_M_u16	52884
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	64731
ISDATBSI412MsgTimer_mS_M_u32	3910685696
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	25060
ISDATBSI432MsgLenValidCount_Cnt_M_u16	5216
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	32409
ISDATDIRASentFltAcc_Cnt_M_u16	6061
ISDATDIRASentTimer_mS_M_u32	3820049408
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	55360
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	43651
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	44714
ISDYN2CMMMsgTimer_mS_M_u32	4257727488
ISDYNAASChkSumInvalidCount_Cnt_M_u16	8102
ISDYNAASChkSumValidCount_Cnt_M_u16	16486
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	29026
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	35699
ISDYNAASMsgLenValidCount_Cnt_M_u16	23147
ISDYNAASMsgTimeValidCount_Cnt_M_u16	8102
ISDYNAASMsgTimer_mS_M_u32	3626148864
ISDYNABRChkSumInvalidCount_Cnt_M_u16	26137
ISDYNABRChkSumValidCount_Cnt_M_u16	45377
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	56581
ISDYNABRMsgCountValidCount_Cnt_M_u16	38661
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	31694
ISDYNABRMsgLenValidCount_Cnt_M_u16	59262
ISDYNABRMsgTimeValidCount_Cnt_M_u16	6402
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	564
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1013
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	30279
ISDYNCMM208MsgTimer_mS_M_u32	1955562496
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2107

Name	Input Value
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1119
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	19521
ISDYNCMM388MsgTimer_mS_M_u32	3794936832
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	18477
ISDYNVOLChkSumValidCount_Cnt_M_u16	36125
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	40329
ISDYNVOLMsgCountValidCount_Cnt_M_u16	17745
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	8061
ISDYNVOLMsgLenValidCount_Cnt_M_u16	38861
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	40544
ISDYNVOLMsgTimer_mS_M_u32	3107513344
IgnOnTimer_mS_M_u32	498476032
IgnTimeOff_Sec_M_u32	66605828
ManVehSpd_Kph_M_f32	240.292099
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	86
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	222
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3442873344
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	56
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1753805824
PrevISDATBSI412MsgDLCError_Cnt_M_u08	151
PrevISDATBSI412MsgRxTime_MSec_M_u32	2115068928
PrevISDATBSI432MsgDLCError_Cnt_M_u08	28
PrevISDATBSI432MsgRxTime_MSec_M_u32	4102145024
PrevISDATDIRAMsgTxTime_MSec_M_u32	2116379648
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	144
PrevISDYN2CMMMsgRxTime_MSec_M_u32	818951168
PrevISDYNAASMsgDLCError_Cnt_M_u08	188
PrevISDYNAASMsgRxTime_MSec_M_u32	7791616
PrevISDYNABRMsgDLCError_Cnt_M_u08	119
PrevISDYNABRMsgRxTime_MSec_M_u32	2712544256
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	143
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3906200576
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	133
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1017431040
PrevISDYNVOLMsgDLCError_Cnt_M_u08	200
PrevISDYNVOLMsgRxTime_MSec_M_u32	268854272
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	920015872
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	496.595398
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	16689
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	33449
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	23634
VitesseVehicleBVRampValidCount_Cnt_M_u16	25738
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	15318
VitesseVehicleBVSigValidCount_Cnt_M_u16	51510
VitesseVehicleBV_Kph_M_f32	0.812600017
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	19521
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	4377
VitesseVehiculeRoues_Kph_M_f32	398.900787

Name	Input Value
k_AASNTCEnableTimeout_mS_u16	9881
k_AASNodeAbsentDiag_Cnt_str.Threshold	8026
k_AASNodeAbsentDiag_Cnt_str.PStep	24353
k_AASNodeAbsentDiag_Cnt_str.NStep	53312
k_AASNodeAbsentTimeout_mS_u16	53214
k_AASNodeTimeout_mS_u16	15785
k_ABSNodeTimeout_mS_u16	38504
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	23167
k_ANGLEVOLANTSigValidThresh_Cnt_u16	56123
k_AngleVolantInvalidThresh_Cnt_u16	7074
k_AngleVolantValidThresh_Cnt_u16	20047
k_BSI552MsgTimeout_mS_u16	43072
k_BSINTCEnableTimeout_mS_u16	54748
k_BSINodeAbsentDiag_Cnt_str.Threshold	19972
k_BSINodeAbsentDiag_Cnt_str.PStep	37052
k_BSINodeAbsentDiag_Cnt_str.NStep	11577
k_BSINodeAbsentTimeout_mS_u16	38273
k_BSINodeTimeout_mS_u16	32409
k_BattOvHi_Volt_f32	4.94899988
k_BattOvLo_Volt_f32	29.9925995
k_BattUvHi_Volt_f32	15.9642
k_BattUvLo_Volt_f32	24.9242992
k_CAVNTCEnableTimeout_mS_u16	34821
k_CAVNodeAbsentDiag_Cnt_str.Threshold	9565
k_CAVNodeAbsentDiag_Cnt_str.PStep	47299
k_CAVNodeAbsentDiag_Cnt_str.NStep	20690
k_CAVNodeAbsentTimeout_mS_u16	58062
k_CAVNodeTimeout_mS_u16	6123
k_CMM388MsgTimeout_mS_u16	43364
k_CMM388NTCEnableTimeout_mS_u16	46816
k_CMMNTCEnableTimeout_mS_u16	29680
k_CMMNodeAbsentDiag_Cnt_str.Threshold	48228
k_CMMNodeAbsentDiag_Cnt_str.PStep	32020
k_CMMNodeAbsentDiag_Cnt_str.NStep	13842
k_CMMNodeAbsentTimeout_mS_u16	58517
k_CONSANGLECPKMax_HwDeg_f32	466.147797
k_CONSANGLECPKMin_HwDeg_f32	-208.600998
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	51009
k_CONSANGLECPKSigValidThresh_Cnt_u16	52249
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	63983
k_CPKVehicleSpeedValidThresh_Cnt_u16	7699
k_CityParkInputInvalidThresh_Cnt_u16	21215
k_CityParkInputValidThresh_Cnt_u16	22279
k_ComputerRazGCTSigValidThresh_Cnt_u16	57502
k_CptTemporelSigValidThresh_Cnt_u16	35090
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	30414
k_DMDFCTCPKSigValidThresh_Cnt_u16	8830
k_DMDFCTCPKValidCount_Cnt_u16	13212
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	44714
k_DMDRELAXECPKSigValidThresh_Cnt_u16	40242
k_DMDRelaxeConsistentThresh_Cnt_u16	13176
k_DateValidThresh_Cnt_u16	23641
k_DefaultVehSpd_Kph_f32	185.728302
k_DiagMuxOnAbsentTimeout_mS_u16	12344
k_EMNodeTimeout_mS_u16	14836
k_ESPNTCEnableTimeout_mS_u16	24716
k_ESPNodeAbsentDiag_Cnt_str.Threshold	20483
k_ESPNodeAbsentDiag_Cnt_str.PStep	10830
k_ESPNodeAbsentDiag_Cnt_str.NStep	29524
k_ESPNodeAbsentTimeout_mS_u16	14493
k_EtatMTSigInvalidThresh_Cnt_u16	65376
k_EtatMTSigValidThresh_Cnt_u16	33224
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	32754
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	38206
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	62504
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	41277
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	54001
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	31348
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	46249
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	24805
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	25960
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	63206
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	39337

Name	Input Value
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	56492
k_ISDATDIRASentDiag_Cnt_str.Threshold	52383
k_ISDATDIRASentDiag_Cnt_str.PStep	4245
k_ISDATDIRASentDiag_Cnt_str.NStep	40890
k_ISDATDIRASentTimeout_mS_u16	10389
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	46217
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	24457
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	41752
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	57625
k_ISDYNAASChkSumValidThresh_Cnt_u16	27713
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	55301
k_ISDYNAASMsgCountValidThresh_Cnt_u16	53765
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	24221
k_ISDYNAASMsgLenValidThresh_Cnt_u16	33325
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	48451
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	9100
k_ISDYNABRChkSumValidThresh_Cnt_u16	33212
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	55700
k_ISDYNABRMsgCountValidThresh_Cnt_u16	55668
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	22880
k_ISDYNABRMsgLenValidThresh_Cnt_u16	61660
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	37403
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	9653
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	41297
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	21456
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	65077
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	58581
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	10311
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	17931
k_ISDYNVOLChkSumValidThresh_Cnt_u16	49647
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	36353
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	50373
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	12375
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	36547
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	655
k_IgnOnTimeout_mS_u16	7303
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	121.582298
k_PowerCutVehSpdLowThresh_Kph_f32	52.8400993
k_PowerCutVehSpdLowTimeout_mS_u16	31877
k_VBattMaxAAS_Volt_f32	7.42670012
k_VBattMaxBSI_Volt_f32	2.36490011
k_VBattMaxCAV_Volt_f32	10.9314003
k_VBattMaxCMM388_Volt_f32	22.5750999
k_VBattMaxCMM_Volt_f32	11.0719004
k_VBattMaxESP_Volt_f32	0.0344000012
k_VBattMinAAS_Volt_f32	28.4505005
k_VBattMinBSI_Volt_f32	0.0344000012
k_VBattMinCAV_Volt_f32	7.81949997
k_VBattMinCMM388_Volt_f32	30.4806004
k_VBattMinCMM_Volt_f32	3.59940004
k_VBattMinESP_Volt_f32	11.0719004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	47939
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	56535
k_VitesseVehicleBVRampValidThresh_Cnt_u16	6281
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	51229
k_VitesseVehicleBVSigValidThresh_Cnt_u16	46624
k_VitesseVehicleBVSpeedPassThresh_kph_f32	40.9356995
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	46352
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	28616
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2418344960
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	212
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	2745
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	4143564288
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	133
target_SrlComInput_Per1_Batt_Volt_f32.value	16.2612991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0

Name	Input Value
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	733967360
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	243
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.244745269
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3443532800
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3074704384
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3583534080
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4030497792
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3476071424
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	980730880
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4194886656
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	70
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	106
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	121
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	191
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1203602432
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	175
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	189
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	124
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	411247616
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	47
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	436683776
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	266036224
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	71
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	85
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	155
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	183
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	223
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4082824192
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3537
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.879677773
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	890664
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	150.388199
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	48491

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4143564288	4143564288	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4143564288	4143564288	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	4143564288	4143564288	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	4143564288	4143564288	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4143564288	4143564288	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4143564288	4143564288	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4143564288	4143564288	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	4143564288	4143564288	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	4143564288	4143564288	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	9565	9565	✔
CAVNodeAbsentTimer_mS_M_u32	4143564288	4143564288	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4143564288	4143564288	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4143564288	4143564288	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	48228	48228	✔
CMMNodeAbsentTimer_mS_M_u32	4143564288	4143564288	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	6402	6402	✔
CONSANGLECPK_HwDeg_M_f32	753.814026	753.814026 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4143564288	4143564288	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	4143564288	4143564288	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4143564288	4143564288	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4143564288	4143564288	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4143564288	4143564288	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4143564288	4143564288	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4143564288	4143564288	✔
ESPNTCEnableTimer_mS_M_u32	4143564288	4143564288	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4143564288	4143564288	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	79	79	✔
EffacDefaultDiagTimer_mS_M_u32[1]	699	699	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4143564288	4143564288	✔
ElecIntTimer_mS_M_u32[1]	2222	2222	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4143564288	4143564288	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4143564288	4143564288	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4143564288	4143564288	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4143564288	4143564288	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4143564288	4143564288	✔
ISDATDIRASentFltAcc_Cnt_M_u16	52383	52383	✔
ISDATDIRASentTimer_mS_M_u32	4143564288	4143564288	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4143564288	4143564288	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4143564288	4143564288	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4143564288	4143564288	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4143564288	4143564288	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4143564288	4143564288	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4143564288	4143564288	✔
IgnOnTimer_mS_M_u32	498476032	498476032	✔
IgnTimeOff_Sec_M_u32	66605828	66605828	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	10	10	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	53	53	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3443532800	3443532800	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	48	48	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3074704384	3074704384	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	251	251	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3583534080	3583534080	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4030497792	4030497792	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2116379648	2116379648	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	14	14	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	980730880	980730880	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	235	235	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4194886656	4194886656	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	5	5	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1203602432	1203602432	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	124	124	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	411247616	411247616	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	47	47	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	436683776	436683776	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	113	113	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	266036224	266036224	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4082824192	4082824192	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	496.595398	496.595398	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	0.812600017	0.812600017	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	398.900787	398.900787	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	6402	6402	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	66605828	66605828	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	753.814026	753.814026 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	185.728302	185.728302	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.11 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2367601408
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	48423
AASNodeAbsentTimer_mS_M_u32	3996543744
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	50493
ANGLEVOLANTSigValidCount_Cnt_M_u16	21036
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	64264
AngleVolantMsgTimer_mS_M_u32	2367601408
AngleVolantValidCount_Cnt_M_u16	59931
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2552834816
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3480857344
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1479138048
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4250376960
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	30224
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	4224473856
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	57790
CAVNodeAbsentTimer_mS_M_u32	4226124544
CDD_SrlComVehSpd_Kph_G_f32	46.7703018
CMM388NTCEnableTimer_mS_M_u32	1945029376
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	611552000
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	17760
CMMNodeAbsentTimer_mS_M_u32	1565104896
CONSANGLECPKSigInvalidCount_Cnt_M_u16	45420
CONSANGLECPKSigValidCount_Cnt_M_u16	42987
CONSANGLECPK_Cnt_M_u16	43442
CONSANGLECPK_HwDeg_M_f32	-593.955017
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43442
CPKVehicleSpeedMsgTimer_mS_M_u32	1602861824
CPKVehicleSpeedValidCount_Cnt_M_u16	4947
CityParkInputConsistentCount_Cnt_M_u16	30927

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	61742
CityParkInputMsgTimer_mS_M_u32	2913740800
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	703228672
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	6619
ComputerRazGCTSigInvalidTimer_mS_M_u32	2362444544
ComputerRazGCTSigValidCount_Cnt_M_u16	51144
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	28282
DMDFCTCPKSigValidCount_Cnt_M_u16	12785
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	28567
DMDRELAXECPKSigValidCount_Cnt_M_u16	60422
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	23629
DateInvalidTimer_mS_M_u32	3480857344
DiagMuxOnAbsentTimer_mS_M_u32	200506112
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4250376960
ESPNTCEnableTimer_mS_M_u32	244017920
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	8571
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	579
EffacDefaultDiagTimer_mS_M_u32[1]	3417146624
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	979
ElecIntTimer_mS_M_u32[1]	1085
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	403069696
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	55139
EtatMTSigValidCount_Cnt_M_u16	15534
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	59846
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	20421
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	40063
ISDAT4V2BSI552MsgTimer_mS_M_u32	3086850816
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	16115
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	2343
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	15534
ISDATBSI3F2MsgTimer_mS_M_u32	3415833344
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	58447
ISDATBSI412MsgLenValidCount_Cnt_M_u16	14450
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	55139
ISDATBSI412MsgTimer_mS_M_u32	3401890560
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	65300
ISDATBSI432MsgLenValidCount_Cnt_M_u16	31279
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	1971
ISDATDIRASentFltAcc_Cnt_M_u16	18871
ISDATDIRASentTimer_mS_M_u32	1602861824
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	63960
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	59931
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	5837
ISDYN2CMMMsgTimer_mS_M_u32	3573377792
ISDYNAASChkSumInvalidCount_Cnt_M_u16	25473
ISDYNAASChkSumValidCount_Cnt_M_u16	33808
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	4206
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	56517
ISDYNAASMsgLenValidCount_Cnt_M_u16	65068
ISDYNAASMsgTimeValidCount_Cnt_M_u16	25473
ISDYNAASMsgTimer_mS_M_u32	2587544320
ISDYNABRChkSumInvalidCount_Cnt_M_u16	28150
ISDYNABRChkSumValidCount_Cnt_M_u16	28109
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	36436
ISDYNABRMsgCountValidCount_Cnt_M_u16	14115
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	39743
ISDYNABRMsgLenValidCount_Cnt_M_u16	23038
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43442
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	569

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1023
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	15534
ISDYNCMM208MsgTimer_mS_M_u32	2422352640
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2127
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1129
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	15041
ISDYNCMM388MsgTimer_mS_M_u32	59001600
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	35090
ISDYNVOLChkSumValidCount_Cnt_M_u16	4113
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	17696
ISDYNVOLMsgCountValidCount_Cnt_M_u16	55575
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	45480
ISDYNVOLMsgLenValidCount_Cnt_M_u16	62600
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	17760
ISDYNVOLMsgTimer_mS_M_u32	3474721536
IgnOnTimer_mS_M_u32	3577236224
IgnTimeOff_Sec_M_u32	2220903119
ManVehSpd_Kph_M_f32	107.537903
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	96
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	86
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1971813120
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	237
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1868356352
PrevISDATBSI412MsgDLCError_Cnt_M_u08	164
PrevISDATBSI412MsgRxTime_MSec_M_u32	530221824
PrevISDATBSI432MsgDLCError_Cnt_M_u08	196
PrevISDATBSI432MsgRxTime_MSec_M_u32	711944960
PrevISDATDIRAMsgTxTime_MSec_M_u32	2627635968
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	216
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2226854656
PrevISDYNAASMsgDLCError_Cnt_M_u08	112
PrevISDYNAASMsgRxTime_MSec_M_u32	121768704
PrevISDYNABRMsgDLCError_Cnt_M_u08	49
PrevISDYNABRMsgRxTime_MSec_M_u32	4040182528
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	0
PrevISDYNCMM208MsgRxTime_MSec_M_u32	989530880
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	200
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3979766528
PrevISDYNVOLMsgDLCError_Cnt_M_u08	233
PrevISDYNVOLMsgRxTime_MSec_M_u32	940280576
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3614096128
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	283.889313
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	12651
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	41810
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	34072
VitesseVehicleBVRampValidCount_Cnt_M_u16	20159
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	6250
VitesseVehicleBVSigValidCount_Cnt_M_u16	40217

Name	Input Value
VitesseVehicleBV_Kph_M_f32	225.850204
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	15041
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	30857
VitesseVehiculeRoues_Kph_M_f32	371.085785
k_AASNTCEnableTimeout_mS_u16	3933
k_AASNodeAbsentDiag_Cnt_str.Threshold	41513
k_AASNodeAbsentDiag_Cnt_str.PStep	450
k_AASNodeAbsentDiag_Cnt_str.NStep	22727
k_AASNodeAbsentTimeout_mS_u16	4282
k_AASNodeTimeout_mS_u16	8786
k_ABSNodeTimeout_mS_u16	62835
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	40947
k_ANGLEVOLANTSigValidThresh_Cnt_u16	21582
k_AngleVolantInvalidThresh_Cnt_u16	48777
k_AngleVolantValidThresh_Cnt_u16	61742
k_BSI552MsgTimeout_mS_u16	35460
k_BSINTCEnableTimeout_mS_u16	19116
k_BSINodeAbsentDiag_Cnt_str.Threshold	20172
k_BSINodeAbsentDiag_Cnt_str.PStep	36967
k_BSINodeAbsentDiag_Cnt_str.NStep	11692
k_BSINodeAbsentTimeout_mS_u16	8352
k_BSINodeTimeout_mS_u16	1971
k_BattOvHi_Volt_f32	6.88710022
k_BattOvLo_Volt_f32	20.6012001
k_BattUvHi_Volt_f32	23.9412994
k_BattUvLo_Volt_f32	16.8731995
k_CAVNTCEnableTimeout_mS_u16	24940
k_CAVNodeAbsentDiag_Cnt_str.Threshold	60263
k_CAVNodeAbsentDiag_Cnt_str.PStep	13137
k_CAVNodeAbsentDiag_Cnt_str.NStep	54320
k_CAVNodeAbsentTimeout_mS_u16	36196
k_CAVNodeTimeout_mS_u16	12216
k_CMM388MsgTimeout_mS_u16	31783
k_CMM388NTCEnableTimeout_mS_u16	24435
k_CMMNTCEnableTimeout_mS_u16	5771
k_CMMNodeAbsentDiag_Cnt_str.Threshold	25265
k_CMMNodeAbsentDiag_Cnt_str.PStep	15842
k_CMMNodeAbsentDiag_Cnt_str.NStep	27902
k_CMMNodeAbsentTimeout_mS_u16	27093
k_CONSANGLECPKMax_HwDeg_f32	614.377686
k_CONSANGLECPKMin_HwDeg_f32	-582.635681
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	31169
k_CONSANGLECPKSigValidThresh_Cnt_u16	63369
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	58336
k_CPKVehicleSpeedValidThresh_Cnt_u16	63510
k_CityParkInputInvalidThresh_Cnt_u16	9732
k_CityParkInputValidThresh_Cnt_u16	30927
k_ComputerRazGCTSigValidThresh_Cnt_u16	34145
k_CptTemporelSigValidThresh_Cnt_u16	58901
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	23103
k_DMDFCTCPKSigValidThresh_Cnt_u16	22782
k_DMDFCTCPKValidCount_Cnt_u16	24440
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	5837
k_DMDRELAXECPKSigValidThresh_Cnt_u16	33412
k_DMDRelaxeConsistentThresh_Cnt_u16	22034
k_DateValidThresh_Cnt_u16	40063
k_DefaultVehSpd_Kph_f32	251.376404
k_DiagMuxOnAbsentTimeout_mS_u16	55664
k_EMNodeTimeout_mS_u16	5421
k_ESPNTCEnableTimeout_mS_u16	2570
k_ESPNodeAbsentDiag_Cnt_str.Threshold	14453
k_ESPNodeAbsentDiag_Cnt_str.PStep	62268
k_ESPNodeAbsentDiag_Cnt_str.NStep	12163
k_ESPNodeAbsentTimeout_mS_u16	17981
k_EtatMTSigInvalidThresh_Cnt_u16	64401
k_EtatMTSigValidThresh_Cnt_u16	35240
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	27399
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	23218
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	26236
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	39540
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	45928
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	23555
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	21013

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	48112
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	63688
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	55878
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	57609
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	42398
k_ISDATDIRASentDiag_Cnt_str.Threshold	57890
k_ISDATDIRASentDiag_Cnt_str.PStep	15951
k_ISDATDIRASentDiag_Cnt_str.NStep	41050
k_ISDATDIRASentTimeout_mS_u16	33346
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	33495
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	64264
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	53030
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	44278
k_ISDYNAASChkSumValidThresh_Cnt_u16	60621
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	19796
k_ISDYNAASMsgCountValidThresh_Cnt_u16	13859
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	55466
k_ISDYNAASMsgLenValidThresh_Cnt_u16	26886
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	26294
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	14821
k_ISDYNABRChkSumValidThresh_Cnt_u16	51492
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	13584
k_ISDYNABRMsgCountValidThresh_Cnt_u16	2623
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	50272
k_ISDYNABRMsgLenValidThresh_Cnt_u16	57467
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	20410
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	38943
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	15420
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	42829
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	33853
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	20780
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	27334
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	26542
k_ISDYNVOLChkSumValidThresh_Cnt_u16	54545
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	6748
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	14209
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	43183
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	44794
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	3901
k_IgnOnTimeout_mS_u16	32762
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	195.353394
k_PowerCutVehSpdLowThresh_Kph_f32	43.7050018
k_PowerCutVehSpdLowTimeout_mS_u16	61529
k_VBattMaxAAS_Volt_f32	17.7089005
k_VBattMaxBSI_Volt_f32	25.7530003
k_VBattMaxCAV_Volt_f32	27.6359005
k_VBattMaxCMM388_Volt_f32	31.1320992
k_VBattMaxCMM_Volt_f32	29.2290001
k_VBattMaxESP_Volt_f32	0.669499993
k_VBattMinAAS_Volt_f32	26.8649006
k_VBattMinBSI_Volt_f32	0.669499993
k_VBattMinCAV_Volt_f32	5.07490015
k_VBattMinCMM388_Volt_f32	16.7042007
k_VBattMinCMM_Volt_f32	24.7451
k_VBattMinESP_Volt_f32	29.2290001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	43081
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	36764
k_VitesseVehicleBVRampValidThresh_Cnt_u16	33824
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	3857
k_VitesseVehicleBVSigValidThresh_Cnt_u16	43028
k_VitesseVehicleBVSpeedPassThresh_kph_f32	255.034393
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	8382
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	31461
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3480857344
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	215
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	22410
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3417146624
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	200
target_SrlComInput_Per1_Batt_Volt_f32.value	13.2919998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2762038016
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	171
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.135605231
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	145
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4248455936
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3184519936
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	376802048
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	791358208
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	804309760
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1086745344
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2309753600
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	95
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	98
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	109
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	186
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	187
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	244
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3015191296
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	142
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	216
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1218530048
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	225
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3132549888
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2229046016
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	82
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	130
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	150
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	151
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	201
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	302439168
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1086
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.743379831
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	862416
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	113.7677

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	52829		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	3417146624	3417146624	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3417146624	3417146624	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3417146624	3417146624	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3417146624	3417146624	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3417146624	3417146624	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3417146624	3417146624	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3417146624	3417146624	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3417146624	3417146624	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3417146624	3417146624	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	60263	60263	✔
CAVNodeAbsentTimer_mS_M_u32	3417146624	3417146624	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3417146624	3417146624	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3417146624	3417146624	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	25265	25265	✔
CMMNodeAbsentTimer_mS_M_u32	3417146624	3417146624	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	43442	43442	✔
CONSANGLECPK_HwDeg_M_f32	-593.955017	-593.955017 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3417146624	3417146624	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3417146624	3417146624	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3417146624	3417146624	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3417146624	3417146624	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3417146624	3417146624	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3417146624	3417146624	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3417146624	3417146624	✔
ESPNTCEnableTimer_mS_M_u32	3417146624	3417146624	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3417146624	3417146624	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	579	579	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	3417146624	3417146624	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3417146624	3417146624	✔
ElecIntTimer_mS_M_u32[1]	1085	1085	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3417146624	3417146624	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3417146624	3417146624	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3417146624	3417146624	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3417146624	3417146624	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3417146624	3417146624	✔
ISDATDIRASentFltAcc_Cnt_M_u16	57890	57890	✔
ISDATDIRASentTimer_mS_M_u32	3417146624	3417146624	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3417146624	3417146624	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3417146624	3417146624	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3417146624	3417146624	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3417146624	3417146624	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3417146624	3417146624	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3417146624	3417146624	✔
IgnOnTimer_mS_M_u32	3577236224	3577236224	✔
IgnTimeOff_Sec_M_u32	2220903119	2220903119	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	145	145	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4248455936	4248455936	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	53	53	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3184519936	3184519936	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	92	92	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	376802048	376802048	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	48	48	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	791358208	791358208	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2627635968	2627635968	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	123	123	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1086745344	1086745344	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	67	67	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2309753600	2309753600	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	244	244	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3015191296	3015191296	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	108	108	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1218530048	1218530048	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	225	225	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3132549888	3132549888	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	154	154	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2229046016	2229046016	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	302439168	302439168	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	283.889313	283.889313	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	225.850204	225.850204	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	371.085785	371.085785	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	43442	43442	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2220903119	2220903119	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-593.955017	-593.955017 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	251.376404	251.376404	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.12 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	351179264
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	18133
AASNodeAbsentTimer_mS_M_u32	744980992
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	43153
ANGLEVOLANTSigValidCount_Cnt_M_u16	64132
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	20786
AngleVolantMsgTimer_mS_M_u32	351179264
AngleVolantValidCount_Cnt_M_u16	55927
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1770996224
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2778579456
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1213018624
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1069806080
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	41496
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	124105216
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	40335
CAVNodeAbsentTimer_mS_M_u32	668606976
CDD_SrlComVehSpd_Kph_G_f32	591.769897
CMM388NTCEnableTimer_mS_M_u32	1958633984
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1714430464
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	18536
CMMNodeAbsentTimer_mS_M_u32	1743647232
CONSANGLECPKSigInvalidCount_Cnt_M_u16	3845
CONSANGLECPKSigValidCount_Cnt_M_u16	25671
CONSANGLECPK_Cnt_M_u16	15090
CONSANGLECPK_HwDeg_M_f32	421.295013
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	15090
CPKVehicleSpeedMsgTimer_mS_M_u32	162370048
CPKVehicleSpeedValidCount_Cnt_M_u16	27544
CityParkInputConsistentCount_Cnt_M_u16	65115

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	56896
CityParkInputMsgTimer_mS_M_u32	4248455936
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1229685248
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	185
ComputerRazGCTSigInvalidTimer_mS_M_u32	1058710016
ComputerRazGCTSigValidCount_Cnt_M_u16	13680
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	38492
DMDFCTCPKSigValidCount_Cnt_M_u16	25782
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	37251
DMDRELAXECPKSigValidCount_Cnt_M_u16	5366
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	53858
DateInvalidTimer_mS_M_u32	2778579456
DiagMuxOnAbsentTimer_mS_M_u32	3681571328
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1069806080
ESPNTCEnableTimer_mS_M_u32	1600684544
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	23766
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1000
EffacDefaultDiagTimer_mS_M_u32[1]	2000
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	16
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	448246272
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	27489
EtatMTSigValidCount_Cnt_M_u16	42048
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	19959
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	21689
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	56588
ISDAT4V2BSI552MsgTimer_mS_M_u32	668070400
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	4143
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	47701
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	42048
ISDATBSI3F2MsgTimer_mS_M_u32	3028177408
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	40221
ISDATBSI412MsgLenValidCount_Cnt_M_u16	26995
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	27489
ISDATBSI412MsgTimer_mS_M_u32	1945932288
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	60236
ISDATBSI432MsgLenValidCount_Cnt_M_u16	8890
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	16304
ISDATDIRASentFltAcc_Cnt_M_u16	35236
ISDATDIRASentTimer_mS_M_u32	162370048
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	25216
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	55927
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	43363
ISDYN2CMMMsgTimer_mS_M_u32	1410499072
ISDYNAASChkSumInvalidCount_Cnt_M_u16	15303
ISDYNAASChkSumValidCount_Cnt_M_u16	21209
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	29566
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	34938
ISDYNAASMsgLenValidCount_Cnt_M_u16	64773
ISDYNAASMsgTimeValidCount_Cnt_M_u16	15303
ISDYNAASMsgTimer_mS_M_u32	836395520
ISDYNABRChkSumInvalidCount_Cnt_M_u16	10726
ISDYNABRChkSumValidCount_Cnt_M_u16	49953
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	51022
ISDYNABRMsgCountValidCount_Cnt_M_u16	17824
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	23948
ISDYNABRMsgLenValidCount_Cnt_M_u16	23054
ISDYNABRMsgTimeValidCount_Cnt_M_u16	15090
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	570

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1025
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	42048
ISDYNCMM208MsgTimer_mS_M_u32	2766422528
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2131
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1131
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	133
ISDYNCMM388MsgTimer_mS_M_u32	4227719680
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	40979
ISDYNVOLChkSumValidCount_Cnt_M_u16	17365
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	10858
ISDYNVOLMsgCountValidCount_Cnt_M_u16	34628
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	41039
ISDYNVOLMsgLenValidCount_Cnt_M_u16	36978
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	18536
ISDYNVOLMsgTimer_mS_M_u32	2822152704
IgnOnTimer_mS_M_u32	1457644032
IgnTimeOff_Sec_M_u32	2230688501
ManVehSpd_Kph_M_f32	190.900696
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	98
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	192
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4004794880
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	106
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2394173952
PrevISDATBSI412MsgDLCError_Cnt_M_u08	159
PrevISDATBSI412MsgRxTime_MSec_M_u32	3501924864
PrevISDATBSI432MsgDLCError_Cnt_M_u08	219
PrevISDATBSI432MsgRxTime_MSec_M_u32	2612822528
PrevISDATDIRAMsgTxTime_MSec_M_u32	1773085184
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	179
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2543415808
PrevISDYNAASMsgDLCError_Cnt_M_u08	229
PrevISDYNAASMsgRxTime_MSec_M_u32	398762496
PrevISDYNABRMsgDLCError_Cnt_M_u08	137
PrevISDYNABRMsgRxTime_MSec_M_u32	1679417856
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	255
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2694423040
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	35
PrevISDYNCMM388MsgRxTime_MSec_M_u32	795312640
PrevISDYNVOLMsgDLCError_Cnt_M_u08	82
PrevISDYNVOLMsgRxTime_MSec_M_u32	2338857472
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1711968768
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	254.731705
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	41608
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	9619
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	39809
VitesseVehicleBVRampValidCount_Cnt_M_u16	5964
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	41738
VitesseVehicleBVSigValidCount_Cnt_M_u16	3517

Name	Input Value
VitesseVehicleBV_Kph_M_f32	26.3281002
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	133
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	40943
VitesseVehiculeRoues_Kph_M_f32	532.828186
k_AASNTCEnableTimeout_mS_u16	30193
k_AASNodeAbsentDiag_Cnt_str.Threshold	35878
k_AASNodeAbsentDiag_Cnt_str.PStep	26578
k_AASNodeAbsentDiag_Cnt_str.NStep	57722
k_AASNodeAbsentTimeout_mS_u16	41626
k_AASNodeTimeout_mS_u16	43155
k_ABSNodeTimeout_mS_u16	9585
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	17583
k_ANGLEVOLANTSigValidThresh_Cnt_u16	53341
k_AngleVolantInvalidThresh_Cnt_u16	15788
k_AngleVolantValidThresh_Cnt_u16	56896
k_BSI552MsgTimeout_mS_u16	5630
k_BSINTCEnableTimeout_mS_u16	26756
k_BSINodeAbsentDiag_Cnt_str.Threshold	20212
k_BSINodeAbsentDiag_Cnt_str.PStep	36950
k_BSINodeAbsentDiag_Cnt_str.NStep	11715
k_BSINodeAbsentTimeout_mS_u16	16490
k_BSINodeTimeout_mS_u16	16304
k_BattOvHi_Volt_f32	22.5716
k_BattOvLo_Volt_f32	26.8467007
k_BattUvHi_Volt_f32	31.5
k_BattUvLo_Volt_f32	5.72130013
k_CAVNTCEnableTimeout_mS_u16	1414
k_CAVNodeAbsentDiag_Cnt_str.Threshold	7813
k_CAVNodeAbsentDiag_Cnt_str.PStep	18559
k_CAVNodeAbsentDiag_Cnt_str.NStep	61912
k_CAVNodeAbsentTimeout_mS_u16	45725
k_CAVNodeTimeout_mS_u16	50209
k_CMM388MsgTimeout_mS_u16	2517
k_CMM388NTCEnableTimeout_mS_u16	36849
k_CMMNTCEnableTimeout_mS_u16	59751
k_CMMNodeAbsentDiag_Cnt_str.Threshold	32878
k_CMMNodeAbsentDiag_Cnt_str.PStep	39506
k_CMMNodeAbsentDiag_Cnt_str.NStep	46263
k_CMMNodeAbsentTimeout_mS_u16	64523
k_CONSANGLECPKMax_HwDeg_f32	628.890808
k_CONSANGLECPKMin_HwDeg_f32	-93.6873016
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	17285
k_CONSANGLECPKSigValidThresh_Cnt_u16	8943
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	7145
k_CPKVehicleSpeedValidThresh_Cnt_u16	15816
k_CityParkInputInvalidThresh_Cnt_u16	47548
k_CityParkInputValidThresh_Cnt_u16	65115
k_ComputerRazGCTSigValidThresh_Cnt_u16	29925
k_CptTemporelSigValidThresh_Cnt_u16	23435
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	8332
k_DMDFCTCPKSigValidThresh_Cnt_u16	23822
k_DMDFCTCPKValidCount_Cnt_u16	34272
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	43363
k_DMDRELAXECPKSigValidThresh_Cnt_u16	32509
k_DMDRelaxeConsistentThresh_Cnt_u16	48211
k_DateValidThresh_Cnt_u16	56588
k_DefaultVehSpd_Kph_f32	88.6629028
k_DiagMuxOnAbsentTimeout_mS_u16	9144
k_EMNodeTimeout_mS_u16	10178
k_ESPNTCEnableTimeout_mS_u16	21675
k_ESPNodeAbsentDiag_Cnt_str.Threshold	7809
k_ESPNodeAbsentDiag_Cnt_str.PStep	32421
k_ESPNodeAbsentDiag_Cnt_str.NStep	11912
k_ESPNodeAbsentTimeout_mS_u16	1747
k_EtatMTSigInvalidThresh_Cnt_u16	44309
k_EtatMTSigValidThresh_Cnt_u16	39824
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	57972
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	64562
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	10580
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	16812
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	65426
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	1537
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	13897

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	41335
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	52784
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	63798
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	11693
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	42543
k_ISDATDIRASentDiag_Cnt_str.Threshold	12498
k_ISDATDIRASentDiag_Cnt_str.PStep	59907
k_ISDATDIRASentDiag_Cnt_str.NStep	48091
k_ISDATDIRASentTimeout_mS_u16	7426
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	12932
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	20786
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	30039
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	27878
k_ISDYNAASChkSumValidThresh_Cnt_u16	17953
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	35406
k_ISDYNAASMsgCountValidThresh_Cnt_u16	18592
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	47562
k_ISDYNAASMsgLenValidThresh_Cnt_u16	42103
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	14629
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	39322
k_ISDYNABRChkSumValidThresh_Cnt_u16	9372
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	25880
k_ISDYNABRMsgCountValidThresh_Cnt_u16	56907
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	52072
k_ISDYNABRMsgLenValidThresh_Cnt_u16	8150
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	47578
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	15980
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	35158
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	50594
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	27537
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	64900
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	53624
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	20224
k_ISDYNVOLChkSumValidThresh_Cnt_u16	53142
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	13875
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	13829
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	10109
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	32092
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	64722
k_IgnOnTimeout_mS_u16	13852
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	17.2317009
k_PowerCutVehSpdLowThresh_Kph_f32	192.177002
k_PowerCutVehSpdLowTimeout_mS_u16	49917
k_VBattMaxAAS_Volt_f32	10.3971996
k_VBattMaxBSI_Volt_f32	19.8449001
k_VBattMaxCAV_Volt_f32	24.6699009
k_VBattMaxCMM388_Volt_f32	10.6365004
k_VBattMaxCMM_Volt_f32	18.2469997
k_VBattMaxESP_Volt_f32	7.72940016
k_VBattMinAAS_Volt_f32	27.3696995
k_VBattMinBSI_Volt_f32	7.72940016
k_VBattMinCAV_Volt_f32	31.6058998
k_VBattMinCMM388_Volt_f32	5.54799986
k_VBattMinCMM_Volt_f32	1.88919997
k_VBattMinESP_Volt_f32	18.2469997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	2606
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	56564
k_VitesseVehicleBVRampValidThresh_Cnt_u16	28010
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	18133
k_VitesseVehicleBVSigValidThresh_Cnt_u16	50316
k_VitesseVehicleBVSpeedPassThresh_kph_f32	503.45871
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	57487
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	43738
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2778579456
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	61
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	1356
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3907662848
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	35
target_SrlComInput_Per1_Batt_Volt_f32.value	2.34789991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2699473408
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	196
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.645456553
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1725686272
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	60490240
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	405414400
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	747192832
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3367526912
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	76
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1958183424
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	243
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3095831040
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	19
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	20
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	84
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	140
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	150
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	154
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	196
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	24
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	316817920
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	44
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	58
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	110
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3769033216
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	254
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1759904256
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	687153664
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	104
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	114
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	118
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	228
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3468046848
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	791
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.120372646
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	662657
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	2.23880005

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	5042		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	3907662848	3907662848	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3907662848	3907662848	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3907662848	3907662848	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3907662848	3907662848	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3907662848	3907662848	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3907662848	3907662848	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3907662848	3907662848	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3907662848	3907662848	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3907662848	3907662848	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	7813	7813	✔
CAVNodeAbsentTimer_mS_M_u32	3907662848	3907662848	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3907662848	3907662848	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3907662848	3907662848	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	32878	32878	✔
CMMNodeAbsentTimer_mS_M_u32	3907662848	3907662848	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	15090	15090	✔
CONSANGLECPK_HwDeg_M_f32	421.295013	421.295013 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3907662848	3907662848	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3907662848	3907662848	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3907662848	3907662848	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3907662848	3907662848	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3907662848	3907662848	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3907662848	3907662848	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3907662848	3907662848	✔
ESPNTCEnableTimer_mS_M_u32	3907662848	3907662848	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3907662848	3907662848	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1000	1000	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	2000	2000	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3907662848	3907662848	✔
ElecIntTimer_mS_M_u32[1]	16	16	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3907662848	3907662848	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3907662848	3907662848	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3907662848	3907662848	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3907662848	3907662848	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3907662848	3907662848	✔
ISDATDIRASentFltAcc_Cnt_M_u16	12498	12498	✔
ISDATDIRASentTimer_mS_M_u32	3907662848	3907662848	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3907662848	3907662848	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3907662848	3907662848	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3907662848	3907662848	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3907662848	3907662848	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3907662848	3907662848	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3907662848	3907662848	✔
IgnOnTimer_mS_M_u32	1457644032	1457644032	✔
IgnTimeOff_Sec_M_u32	2230688501	2230688501	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	210	210	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1725686272	1725686272	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	166	166	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	60490240	60490240	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	46	46	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	405414400	405414400	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	241	241	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	747192832	747192832	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1773085184	1773085184	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	76	76	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1958183424	1958183424	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	243	243	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3095831040	3095831040	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	24	24	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	316817920	316817920	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	158	158	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3769033216	3769033216	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	254	254	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1759904256	1759904256	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	209	209	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	687153664	687153664	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3468046848	3468046848	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	254.731705	254.731705	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	26.3281002	26.3281002	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	532.828186	532.828186	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	15090	15090	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2230688501	2230688501	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	421.295013	421.295013 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.13 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	765136128
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	20967
AASNodeAbsentTimer_mS_M_u32	921713920
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	48818
ANGLEVOLANTSigValidCount_Cnt_M_u16	56986
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	59088
AngleVolantMsgTimer_mS_M_u32	765136128
AngleVolantValidCount_Cnt_M_u16	18305
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3464035584
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1951235328
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3590270208
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	983231744
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	44573
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2595597568
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	55
CAVNodeAbsentTimer_mS_M_u32	3608698112
CDD_SrlComVehSpd_Kph_G_f32	379.976013
CMM388NTCEnableTimer_mS_M_u32	3513490688
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4095106304
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	32365
CMMNodeAbsentTimer_mS_M_u32	3927764224
CONSANGLECPKSigInvalidCount_Cnt_M_u16	2646
CONSANGLECPKSigValidCount_Cnt_M_u16	24655
CONSANGLECPK_Cnt_M_u16	18510
CONSANGLECPK_HwDeg_M_f32	687.239319
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	18510
CPKVehicleSpeedMsgTimer_mS_M_u32	190713088
CPKVehicleSpeedValidCount_Cnt_M_u16	36293

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	27605
CityParkInputInvalidCount_Cnt_M_u16	61733
CityParkInputMsgTimer_mS_M_u32	1725686272
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1883520256
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	46139
ComputerRazGCTSigInvalidTimer_mS_M_u32	861330688
ComputerRazGCTSigValidCount_Cnt_M_u16	23190
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	14545
DMDFCTCPKSigValidCount_Cnt_M_u16	33666
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	19420
DMDRELAXECPKSigValidCount_Cnt_M_u16	55108
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	29759
DateInvalidTimer_mS_M_u32	1951235328
DiagMuxOnAbsentTimer_mS_M_u32	286641408
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	983231744
ESPNTCEnableTimer_mS_M_u32	3790421248
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	18146
EffacDefaultDiagCount_Cnt_M_u08	2
EffacDefaultDiagTimer_mS_M_u32[0]	2500
EffacDefaultDiagTimer_mS_M_u32[1]	3500
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	54
ElecIntTimer_mS_M_u32[1]	65
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	683650304
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	35457
EtatMTSigValidCount_Cnt_M_u16	42406
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	38272
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	55033
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	62080
ISDAT4V2BSI552MsgTimer_mS_M_u32	980479232
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	2457
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	61670
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	42406
ISDATBSI3F2MsgTimer_mS_M_u32	1038863616
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	60366
ISDATBSI412MsgLenValidCount_Cnt_M_u16	11403
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	35457
ISDATBSI412MsgTimer_mS_M_u32	3362852096
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	9665
ISDATBSI432MsgLenValidCount_Cnt_M_u16	34102
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	56788
ISDATDIRASentFltAcc_Cnt_M_u16	53240
ISDATDIRASentTimer_mS_M_u32	190713088
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	35236
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	18305
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	56252
ISDYN2CMMMsgTimer_mS_M_u32	737099008
ISDYNAASChkSumInvalidCount_Cnt_M_u16	47889
ISDYNAASChkSumValidCount_Cnt_M_u16	2970
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	22636
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	43894
ISDYNAASMsgLenValidCount_Cnt_M_u16	50071
ISDYNAASMsgTimeValidCount_Cnt_M_u16	47889
ISDYNAASMsgTimer_mS_M_u32	169319680
ISDYNABRChkSumInvalidCount_Cnt_M_u16	51249
ISDYNABRChkSumValidCount_Cnt_M_u16	12866
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	62588
ISDYNABRMsgCountValidCount_Cnt_M_u16	3909
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	64193
ISDYNABRMsgLenValidCount_Cnt_M_u16	23290
ISDYNABRMsgTimeValidCount_Cnt_M_u16	18510

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	571
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1027
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	42406
ISDYNCMM208MsgTimer_mS_M_u32	2960784640
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2135
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1133
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	36183
ISDYNCMM388MsgTimer_mS_M_u32	2578259200
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	3884
ISDYNVOLChkSumValidCount_Cnt_M_u16	31141
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	13479
ISDYNVOLMsgCountValidCount_Cnt_M_u16	54232
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	41079
ISDYNVOLMsgLenValidCount_Cnt_M_u16	42447
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	32365
ISDYNVOLMsgTimer_mS_M_u32	1745018112
IgnOnTimer_mS_M_u32	419503360
IgnTimeOff_Sec_M_u32	485705818
ManVehSpd_Kph_M_f32	269.262604
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	100
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	16
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3880373504
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	202
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1590308096
PrevISDATBSI412MsgDLCError_Cnt_M_u08	24
PrevISDATBSI412MsgRxTime_MSec_M_u32	2692046080
PrevISDATBSI432MsgDLCError_Cnt_M_u08	147
PrevISDATBSI432MsgRxTime_MSec_M_u32	2096184576
PrevISDATDIRAMsgTxTime_MSec_M_u32	2778291456
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	213
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1763339520
PrevISDYNAASMsgDLCError_Cnt_M_u08	76
PrevISDYNAASMsgRxTime_MSec_M_u32	3512261888
PrevISDYNABRMsgDLCError_Cnt_M_u08	169
PrevISDYNABRMsgRxTime_MSec_M_u32	3512278272
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	62
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3403275520
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	194
PrevISDYNCMM388MsgRxTime_MSec_M_u32	770718976
PrevISDYNVOLMsgDLCError_Cnt_M_u08	120
PrevISDYNVOLMsgRxTime_MSec_M_u32	1684954368
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2856783104
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	268.134003
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	5452
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	493
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	20065
VitesseVehicleBVRampValidCount_Cnt_M_u16	20674
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	62279

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	51439
VitesseVehicleBV_Kph_M_f32	191.887604
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	36183
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	42199
VitesseVehiculeRoues_Kph_M_f32	440.147095
k_AASNTCEnableTimeout_mS_u16	21329
k_AASNodeAbsentDiag_Cnt_str.Threshold	1259
k_AASNodeAbsentDiag_Cnt_str.PStep	25214
k_AASNodeAbsentDiag_Cnt_str.NStep	22878
k_AASNodeAbsentTimeout_mS_u16	15128
k_AASNodeTimeout_mS_u16	30957
k_ABSNodeTimeout_mS_u16	8082
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	26008
k_ANGLEVOLANTSigValidThresh_Cnt_u16	51277
k_AngleVolantInvalidThresh_Cnt_u16	31840
k_AngleVolantValidThresh_Cnt_u16	61733
k_BSI552MsgTimeout_mS_u16	16042
k_BSINTCEnableTimeout_mS_u16	36377
k_BSINodeAbsentDiag_Cnt_str.Threshold	20252
k_BSINodeAbsentDiag_Cnt_str.PStep	36933
k_BSINodeAbsentDiag_Cnt_str.NStep	11738
k_BSINodeAbsentTimeout_mS_u16	63784
k_BSINodeTimeout_mS_u16	56788
k_BattOvHi_Volt_f32	18.0613995
k_BattOvLo_Volt_f32	31.4836998
k_BattUvHi_Volt_f32	2.06660008
k_BattUvLo_Volt_f32	29.2884007
k_CAVNTCEnableTimeout_mS_u16	4947
k_CAVNodeAbsentDiag_Cnt_str.Threshold	25478
k_CAVNodeAbsentDiag_Cnt_str.PStep	49264
k_CAVNodeAbsentDiag_Cnt_str.NStep	125
k_CAVNodeAbsentTimeout_mS_u16	30989
k_CAVNodeTimeout_mS_u16	23298
k_CMM388MsgTimeout_mS_u16	2279
k_CMM388NTCEnableTimeout_mS_u16	59027
k_CMMNTCEnableTimeout_mS_u16	24049
k_CMMNodeAbsentDiag_Cnt_str.Threshold	1651
k_CMMNodeAbsentDiag_Cnt_str.PStep	38496
k_CMMNodeAbsentDiag_Cnt_str.NStep	12296
k_CMMNodeAbsentTimeout_mS_u16	131
k_CONSANGLECPKMax_HwDeg_f32	561.278809
k_CONSANGLECPKMin_HwDeg_f32	-715.132324
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	50263
k_CONSANGLECPKSigValidThresh_Cnt_u16	7127
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	63211
k_CPKVehicleSpeedValidThresh_Cnt_u16	30157
k_CityParkInputInvalidThresh_Cnt_u16	61615
k_CityParkInputValidThresh_Cnt_u16	27605
k_ComputerRazGCTSigValidThresh_Cnt_u16	13175
k_CptTemporelSigValidThresh_Cnt_u16	25924
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	45505
k_DMDFCTCPKSigValidThresh_Cnt_u16	20986
k_DMDFCTCPKValidCount_Cnt_u16	8901
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	56252
k_DMDRELAXECPKSigValidThresh_Cnt_u16	4269
k_DMDRelaxeConsistentThresh_Cnt_u16	12459
k_DateValidThresh_Cnt_u16	62080
k_DefaultVehSpd_Kph_f32	182.912796
k_DiagMuxOnAbsentTimeout_mS_u16	9724
k_EMNodeTimeout_mS_u16	62495
k_ESPNTCEnableTimeout_mS_u16	19171
k_ESPNodeAbsentDiag_Cnt_str.Threshold	19994
k_ESPNodeAbsentDiag_Cnt_str.PStep	23622
k_ESPNodeAbsentDiag_Cnt_str.NStep	65140
k_ESPNodeAbsentTimeout_mS_u16	43
k_EtatMTSigInvalidThresh_Cnt_u16	47780
k_EtatMTSigValidThresh_Cnt_u16	9461
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	36682
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	34767
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	3818
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	43298
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	21807
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	16674

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	30922
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	15615
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	3349
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	7554
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	42463
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	59800
k_ISDATDIRASentDiag_Cnt_str.Threshold	18718
k_ISDATDIRASentDiag_Cnt_str.PStep	37988
k_ISDATDIRASentDiag_Cnt_str.NStep	5875
k_ISDATDIRASentTimeout_mS_u16	24285
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	55449
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	59088
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	39135
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	65329
k_ISDYNAASChkSumValidThresh_Cnt_u16	43330
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	43900
k_ISDYNAASMsgCountValidThresh_Cnt_u16	1605
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	43141
k_ISDYNAASMsgLenValidThresh_Cnt_u16	5441
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	44533
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	65175
k_ISDYNABRChkSumValidThresh_Cnt_u16	45904
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	25885
k_ISDYNABRMsgCountValidThresh_Cnt_u16	3909
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	62829
k_ISDYNABRMsgLenValidThresh_Cnt_u16	64994
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	30872
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	53664
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	19235
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	7616
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	30130
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	54682
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	63357
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	8741
k_ISDYNVOLChkSumValidThresh_Cnt_u16	17954
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	28363
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	27030
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	50733
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	35410
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	11054
k_IgnOnTimeout_mS_u16	56529
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	91.7062988
k_PowerCutVehSpdLowThresh_Kph_f32	150.8703
k_PowerCutVehSpdLowTimeout_mS_u16	39981
k_VBattMaxAAS_Volt_f32	30.0261993
k_VBattMaxBSI_Volt_f32	32
k_VBattMaxCAV_Volt_f32	20.0470009
k_VBattMaxCMM388_Volt_f32	6.78179979
k_VBattMaxCMM_Volt_f32	11.2462997
k_VBattMaxESP_Volt_f32	1.38789999
k_VBattMinAAS_Volt_f32	10.7873001
k_VBattMinBSI_Volt_f32	1.38789999
k_VBattMinCAV_Volt_f32	16.4803009
k_VBattMinCMM388_Volt_f32	2.1637001
k_VBattMinCMM_Volt_f32	17.7483006
k_VBattMinESP_Volt_f32	11.2462997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	31131
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	26375
k_VitesseVehicleBVRampValidThresh_Cnt_u16	27559
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	28837
k_VitesseVehicleBVSigValidThresh_Cnt_u16	7490
k_VitesseVehicleBVSpeedPassThresh_kph_f32	348.146606
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	14135
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	19992
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1951235328
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	64
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60833
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2729453312
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	194
target_SrlComInput_Per1_Batt_Volt_f32.value	14.4441004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	305310976
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	2
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.913552105
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	146
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1360207104
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3746938112
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1177050368
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3985308928
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1031642368
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2650815744
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	140
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1997724928
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	86
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	87
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	135
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	213
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	237
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3732929792
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	162
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3484556544
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	193
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2608119040
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	76
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4291255552
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	50
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	106
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	119
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	177
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	650390784
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	685
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.850280643
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	137013
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	147.934998
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	59854

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	765136128	765136128	✔
AASNTCsEnabled_Cnt_M_lgc	1	1	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1997724928	1997724928	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	59088	59088	✔
AngleVolantMsgTimer_mS_M_u32	2729453312	2729453312	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2729453312	2729453312	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2729453312	2729453312	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2729453312	2729453312	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2729453312	2729453312	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	32835	32835	✔
BSINodeAbsentTimer_mS_M_u32	3985308928	3985308928	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2729453312	2729453312	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4291255552	4291255552	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2729453312	2729453312	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2729453312	2729453312	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	20069	20069	✔
CMMNodeAbsentTimer_mS_M_u32	2650815744	2650815744	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	2646	2646	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	18510	18510	✔
CONSANGLECPK_HwDeg_M_f32	687.239319	687.239319 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	18510	18510	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	190713088	190713088	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	36293	36293	✔
CityParkInputConsistentCount_Cnt_M_u16	27605	27605	✔
CityParkInputInvalidCount_Cnt_M_u16	61733	61733	✔
CityParkInputMsgTimer_mS_M_u32	2729453312	2729453312	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2729453312	2729453312	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2729453312	2729453312	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	14545	14545	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	19420	19420	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2729453312	2729453312	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2729453312	2729453312	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2729453312	2729453312	✔
ESPNTCEnableTimer_mS_M_u32	2729453312	2729453312	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	19994	19994	✔
ESPNodeAbsentTimer_mS_M_u32	2729453312	2729453312	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	2500	2500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3500	3500	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	54	54	✔
ElecIntTimer_mS_M_u32[1]	65	65	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2729453312	2729453312	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2729453312	2729453312	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2729453312	2729453312	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2729453312	2729453312	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2729453312	2729453312	✔
ISDATDIRASentFltAcc_Cnt_M_u16	47365	47365	✔
ISDATDIRASentTimer_mS_M_u32	2729453312	2729453312	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2729453312	2729453312	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	47889	47889	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	22636	22636	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	43894	43894	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1997724928	1997724928	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2729453312	2729453312	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2729453312	2729453312	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2729453312	2729453312	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2729453312	2729453312	✔
IgnOnTimer_mS_M_u32	419503360	419503360	✔
IgnTimeOff_Sec_M_u32	485705818	485705818	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	146	146	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1360207104	1360207104	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3746938112	3746938112	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	73	73	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1177050368	1177050368	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	67	67	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3985308928	3985308928	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1031642368	1031642368	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	125	125	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2650815744	2650815744	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	140	140	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1997724928	1997724928	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	113	113	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3732929792	3732929792	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	26	26	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3484556544	3484556544	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	193	193	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2608119040	2608119040	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	76	76	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4291255552	4291255552	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	650390784	650390784	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	268.134003	268.134003	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	191.887604	191.887604	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	440.147095	440.147095	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	18510	18510	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	485705818	485705818	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	687.239319	687.239319 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	182.912796	182.912796	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.14 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1128373248
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	43100
AASNodeAbsentTimer_mS_M_u32	939658240
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	44028
ANGLEVOLANTSigValidCount_Cnt_M_u16	2818
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	52641
AngleVolantMsgTimer_mS_M_u32	1128373248
AngleVolantValidCount_Cnt_M_u16	46607
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2221394944
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2229947392
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2190818304
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1942092800
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	18875
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	779205632
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	34283
CAVNodeAbsentTimer_mS_M_u32	2684988416
CDD_SrlComVehSpd_Kph_G_f32	314.5914
CMM388NTCEnableTimer_mS_M_u32	235924480
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3239029760
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	36617
CMMNodeAbsentTimer_mS_M_u32	3980131328
CONSANGLECPKSigInvalidCount_Cnt_M_u16	19470
CONSANGLECPKSigValidCount_Cnt_M_u16	18660
CONSANGLECPK_Cnt_M_u16	19687
CONSANGLECPK_HwDeg_M_f32	3.26110005
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	19687
CPKVehicleSpeedMsgTimer_mS_M_u32	1979227136
CPKVehicleSpeedValidCount_Cnt_M_u16	38474
CityParkInputConsistentCount_Cnt_M_u16	39187
CityParkInputInvalidCount_Cnt_M_u16	39458
CityParkInputMsgTimer_mS_M_u32	1360207104

Name	Input Value
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3691383808
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	53600
ComputerRazGCTSigInvalidTimer_mS_M_u32	2773363712
ComputerRazGCTSigValidCount_Cnt_M_u16	4304
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	29470
DMDFCTCPKSigValidCount_Cnt_M_u16	29132
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	11390
DMDRELAXECPKSigValidCount_Cnt_M_u16	18692
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	62035
DateInvalidTimer_mS_M_u32	2229947392
DiagMuxOnAbsentTimer_mS_M_u32	4090584064
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1942092800
ESPNTCEnableTimer_mS_M_u32	1795886080
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	9323
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	979
EffacDefaultDiagTimer_mS_M_u32[1]	1085
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	101
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	743685120
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	3021
EtatMTSigValidCount_Cnt_M_u16	26911
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	53904
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	3302
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	40146
ISDAT4V2BSI552MsgTimer_mS_M_u32	1279261696
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	17925
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	57055
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	26911
ISDATBSI3F2MsgTimer_mS_M_u32	1162828800
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1125
ISDATBSI412MsgLenValidCount_Cnt_M_u16	20719
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	3021
ISDATBSI412MsgTimer_mS_M_u32	1254071296
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	59661
ISDATBSI432MsgLenValidCount_Cnt_M_u16	47471
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	41236
ISDATDIRASentFltAcc_Cnt_M_u16	23208
ISDATDIRASentTimer_mS_M_u32	1979227136
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	24805
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	46607
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	63069
ISDYN2CMMMsgTimer_mS_M_u32	352652288
ISDYNAASChkSumInvalidCount_Cnt_M_u16	38110
ISDYNAASChkSumValidCount_Cnt_M_u16	57860
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	61262
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	16430
ISDYNAASMsgLenValidCount_Cnt_M_u16	38540
ISDYNAASMsgTimeValidCount_Cnt_M_u16	38110
ISDYNAASMsgTimer_mS_M_u32	336325632
ISDYNABRChkSumInvalidCount_Cnt_M_u16	59132
ISDYNABRChkSumValidCount_Cnt_M_u16	1930
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	21661
ISDYNABRMsgCountValidCount_Cnt_M_u16	17155
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	59085
ISDYNABRMsgLenValidCount_Cnt_M_u16	50403
ISDYNABRMsgTimeValidCount_Cnt_M_u16	19687
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	572
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1029
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	26911

Name	Input Value
ISDYNCMM208MsgTimer_mS_M_u32	577031168
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2139
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1135
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	48269
ISDYNCMM388MsgTimer_mS_M_u32	2605411328
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	5516
ISDYNVOLChkSumValidCount_Cnt_M_u16	54498
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	22428
ISDYNVOLMsgCountValidCount_Cnt_M_u16	22730
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	43948
ISDYNVOLMsgLenValidCount_Cnt_M_u16	6754
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	36617
ISDYNVOLMsgTimer_mS_M_u32	3075091456
IgnOnTimer_mS_M_u32	1833921536
IgnTimeOff_Sec_M_u32	2705622483
ManVehSpd_Kph_M_f32	648.654602
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	102
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	229
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1094016000
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	149
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3560193024
PrevISDATBSI412MsgDLCError_Cnt_M_u08	226
PrevISDATBSI412MsgRxTime_MSec_M_u32	4159876096
PrevISDATBSI432MsgDLCError_Cnt_M_u08	233
PrevISDATBSI432MsgRxTime_MSec_M_u32	2852064256
PrevISDATDIRAMsgTxTime_MSec_M_u32	2022091776
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	196
PrevISDYN2CMMMsgRxTime_MSec_M_u32	0
PrevISDYNAASMsgDLCError_Cnt_M_u08	53
PrevISDYNAASMsgRxTime_MSec_M_u32	1397238784
PrevISDYNABRMsgDLCError_Cnt_M_u08	69
PrevISDYNABRMsgRxTime_MSec_M_u32	2756144128
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	198
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2865048576
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	65
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1392643072
PrevISDYNVOLMsgDLCError_Cnt_M_u08	86
PrevISDYNVOLMsgRxTime_MSec_M_u32	3490163712
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2101189632
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	80.9476013
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	55980
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	45962
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	50029
VitesseVehicleBVRampValidCount_Cnt_M_u16	23307
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	41533
VitesseVehicleBVSigValidCount_Cnt_M_u16	57347
VitesseVehicleBV_Kph_M_f32	625.037476
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	48269

Name	Input Value
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	38091
VitesseVehiculeRoues_Kph_M_f32	484.04071
k_AASNTCEnableTimeout_mS_u16	63454
k_AASNodeAbsentDiag_Cnt_str.Threshold	58984
k_AASNodeAbsentDiag_Cnt_str.PStep	23526
k_AASNodeAbsentDiag_Cnt_str.NStep	43967
k_AASNodeAbsentTimeout_mS_u16	63306
k_AASNodeTimeout_mS_u16	20106
k_ABSNodeTimeout_mS_u16	731
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	17800
k_ANGLEVOLANTSigValidThresh_Cnt_u16	3114
k_AngleVolantInvalidThresh_Cnt_u16	64497
k_AngleVolantValidThresh_Cnt_u16	39458
k_BSI552MsgTimeout_mS_u16	54098
k_BSINTCEnableTimeout_mS_u16	4101
k_BSINodeAbsentDiag_Cnt_str.Threshold	20292
k_BSINodeAbsentDiag_Cnt_str.PStep	36916
k_BSINodeAbsentDiag_Cnt_str.NStep	11761
k_BSINodeAbsentTimeout_mS_u16	63129
k_BSINodeTimeout_mS_u16	41236
k_BattOvHi_Volt_f32	15.6812
k_BattOvLo_Volt_f32	26.6716003
k_BattUvHi_Volt_f32	25.3892002
k_BattUvLo_Volt_f32	2.47110009
k_CAVNTCEnableTimeout_mS_u16	27544
k_CAVNodeAbsentDiag_Cnt_str.Threshold	26991
k_CAVNodeAbsentDiag_Cnt_str.PStep	8744
k_CAVNodeAbsentDiag_Cnt_str.NStep	3514
k_CAVNodeAbsentTimeout_mS_u16	62313
k_CAVNodeTimeout_mS_u16	2570
k_CMM388MsgTimeout_mS_u16	33628
k_CMM388NTCEnableTimeout_mS_u16	39512
k_CMMNTCEnableTimeout_mS_u16	43261
k_CMMNodeAbsentDiag_Cnt_str.Threshold	50865
k_CMMNodeAbsentDiag_Cnt_str.PStep	56864
k_CMMNodeAbsentDiag_Cnt_str.NStep	46752
k_CMMNodeAbsentTimeout_mS_u16	12743
k_CONSANGLECPKMax_HwDeg_f32	397.019989
k_CONSANGLECPKMin_HwDeg_f32	-264.310211
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	6029
k_CONSANGLECPKSigValidThresh_Cnt_u16	12235
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	19600
k_CPKVehicleSpeedValidThresh_Cnt_u16	8808
k_CityParkInputInvalidThresh_Cnt_u16	58754
k_CityParkInputValidThresh_Cnt_u16	39187
k_ComputerRazGCTSigValidThresh_Cnt_u16	49259
k_CptTemporelSigValidThresh_Cnt_u16	31173
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	49613
k_DMDFCTCPKSigValidThresh_Cnt_u16	57315
k_DMDFCTCPKValidCount_Cnt_u16	35779
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	63069
k_DMDRELAXECPKSigValidThresh_Cnt_u16	13899
k_DMDRelaxeConsistentThresh_Cnt_u16	20049
k_DateValidThresh_Cnt_u16	40146
k_DefaultVehSpd_Kph_f32	169.8349
k_DiagMuxOnAbsentTimeout_mS_u16	60381
k_EMNodeTimeout_mS_u16	62131
k_ESPNTCEnableTimeout_mS_u16	21991
k_ESPNodeAbsentDiag_Cnt_str.Threshold	2587
k_ESPNodeAbsentDiag_Cnt_str.PStep	46029
k_ESPNodeAbsentDiag_Cnt_str.NStep	6078
k_ESPNodeAbsentTimeout_mS_u16	53967
k_EtatMTSigInvalidThresh_Cnt_u16	39843
k_EtatMTSigValidThresh_Cnt_u16	47985
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	49011
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	1189
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	17364
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	52074
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	5636
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	21609
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	21490
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	62996
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	33553

Name	Input Value
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	40267
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	37621
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	49162
k_ISDATDIRASentDiag_Cnt_str.Threshold	25382
k_ISDATDIRASentDiag_Cnt_str.PStep	31949
k_ISDATDIRASentDiag_Cnt_str.NStep	27862
k_ISDATDIRASentTimeout_mS_u16	54008
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	14087
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	52641
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	23539
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	16892
k_ISDYNAASChkSumValidThresh_Cnt_u16	41610
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	12189
k_ISDYNAASMsgCountValidThresh_Cnt_u16	24067
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	38400
k_ISDYNAASMsgLenValidThresh_Cnt_u16	51598
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	64306
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	45899
k_ISDYNABRChkSumValidThresh_Cnt_u16	37857
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	9403
k_ISDYNABRMsgCountValidThresh_Cnt_u16	58625
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	10761
k_ISDYNABRMsgLenValidThresh_Cnt_u16	65387
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	46344
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	62896
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	31334
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	27665
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	34556
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	9730
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	59162
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	32096
k_ISDYNVOLChkSumValidThresh_Cnt_u16	8234
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	37040
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	45454
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	2249
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	27419
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	10952
k_IgnOnTimeout_mS_u16	64860
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	79.9544983
k_PowerCutVehSpdLowThresh_Kph_f32	198.462296
k_PowerCutVehSpdLowTimeout_mS_u16	36170
k_VBattMaxAAS_Volt_f32	25.4953995
k_VBattMaxBSI_Volt_f32	21.9664001
k_VBattMaxCAV_Volt_f32	22.9162998
k_VBattMaxCMM388_Volt_f32	30.8076
k_VBattMaxCMM_Volt_f32	1.52649999
k_VBattMaxESP_Volt_f32	23.3348999
k_VBattMinAAS_Volt_f32	21.1760006
k_VBattMinBSI_Volt_f32	23.3348999
k_VBattMinCAV_Volt_f32	14.8929005
k_VBattMinCMM388_Volt_f32	5.31330013
k_VBattMinCMM_Volt_f32	10.7341995
k_VBattMinESP_Volt_f32	1.52649999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	56321
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	57978
k_VitesseVehicleBVRampValidThresh_Cnt_u16	45724
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	61410
k_VitesseVehicleBVSigValidThresh_Cnt_u16	30924
k_VitesseVehicleBVSpeedPassThresh_kph_f32	644.028992
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	57579
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	15113
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2229947392
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	137
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	53197
target Rte Call Ap SrlComInput SystemTime GetSystemTime mS u32 CurrentT	820661760
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	65
target_SrlComInput_Per1_Batt_Volt_f32.value	22.3645

Name	Input Value
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4227513344
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	29
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.954068661
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2367253504
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3033631744
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	184
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2463738880
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	252
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4013018112
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2446978048
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	116
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1121061888
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3390712832
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	119
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	151
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	202
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	204
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	214
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	810732544
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	134
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	229
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1295805440
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3161754624
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2717690880
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	9
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	48
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	115
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	166
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	236
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3829808128
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1683
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.619152069
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	641362
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	133.518204
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	58662

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	820661760	820661760	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	820661760	820661760	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	820661760	820661760	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	820661760	820661760	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	820661760	820661760	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	820661760	820661760	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	820661760	820661760	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	820661760	820661760	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	820661760	820661760	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	26991	26991	✔
CAVNodeAbsentTimer_mS_M_u32	820661760	820661760	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	820661760	820661760	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	820661760	820661760	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	50865	50865	✔
CMMNodeAbsentTimer_mS_M_u32	820661760	820661760	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	19687	19687	✔
CONSANGLECPK_HwDeg_M_f32	3.26110005	3.26110005 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	820661760	820661760	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	820661760	820661760	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	820661760	820661760	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	820661760	820661760	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	820661760	820661760	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	820661760	820661760	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	820661760	820661760	✔
ESPNTCEnableTimer_mS_M_u32	820661760	820661760	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	820661760	820661760	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	979	979	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1085	1085	✔
ElecIntCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	820661760	820661760	✔
ElecIntTimer_mS_M_u32[1]	101	101	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	820661760	820661760	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	820661760	820661760	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	820661760	820661760	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	820661760	820661760	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	820661760	820661760	✔
ISDATDIRASentFltAcc_Cnt_M_u16	25382	25382	✔
ISDATDIRASentTimer_mS_M_u32	820661760	820661760	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	820661760	820661760	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	820661760	820661760	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	820661760	820661760	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	820661760	820661760	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	820661760	820661760	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	820661760	820661760	✔
IgnOnTimer_mS_M_u32	1833921536	1833921536	✔
IgnTimeOff_Sec_M_u32	2705622483	2705622483	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	55	55	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2367253504	2367253504	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	14	14	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3033631744	3033631744	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	184	184	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2463738880	2463738880	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	252	252	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4013018112	4013018112	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2022091776	2022091776	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	116	116	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1121061888	1121061888	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	55	55	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3390712832	3390712832	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	132	132	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	810732544	810732544	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1295805440	1295805440	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	154	154	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3161754624	3161754624	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	235	235	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2717690880	2717690880	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3829808128	3829808128	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	80.9476013	80.9476013	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	625.037476	625.037476	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	484.04071	484.04071	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	19687	19687	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2705622483	2705622483	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	3.26110005	3.26110005 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.15 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2471096064
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	60922
AASNodeAbsentTimer_mS_M_u32	2194185984
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	1304
ANGLEVOLANTSigValidCount_Cnt_M_u16	43975
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	53803
AngleVolantMsgTimer_mS_M_u32	2471096064
AngleVolantValidCount_Cnt_M_u16	63841
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1687641856
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2366627584
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	734990080
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4215852800
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	59355
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	976850688
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	39883
CAVNodeAbsentTimer_mS_M_u32	1899085568
CDD_SrlComVehSpd_Kph_G_f32	438.917786
CMM388NTCEnableTimer_mS_M_u32	270466816
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2787098368
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	62768
CMMNodeAbsentTimer_mS_M_u32	4141534976
CONSANGLECPKSigInvalidCount_Cnt_M_u16	39907
CONSANGLECPKSigValidCount_Cnt_M_u16	43297
CONSANGLECPK_Cnt_M_u16	26904
CONSANGLECPK_HwDeg_M_f32	-335.180786
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	26904
CPKVehicleSpeedMsgTimer_mS_M_u32	2535780096
CPKVehicleSpeedValidCount_Cnt_M_u16	24470
CityParkInputConsistentCount_Cnt_M_u16	24661
CityParkInputInvalidCount_Cnt_M_u16	43559

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	2367253504
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2797379328
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	33518
ComputerRazGCTSigInvalidTimer_mS_M_u32	325336832
ComputerRazGCTSigValidCount_Cnt_M_u16	11550
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	3891
DMDFCTCPKSigValidCount_Cnt_M_u16	30441
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	2962
DMDRELAXECPKSigValidCount_Cnt_M_u16	31169
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	64788
DateInvalidTimer_mS_M_u32	2366627584
DiagMuxOnAbsentTimer_mS_M_u32	1889185536
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4215852800
ESPNTCEnableTimer_mS_M_u32	1303224064
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	26827
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	6
EffacDefaultDiagTimer_mS_M_u32[1]	16
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	656
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1217629952
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	39911
EtatMTSigValidCount_Cnt_M_u16	30641
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	36957
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	58651
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	36311
ISDAT4V2BSI552MsgTimer_mS_M_u32	3922644736
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	50878
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	4080
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	30641
ISDATBSI3F2MsgTimer_mS_M_u32	4095782656
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	23709
ISDATBSI412MsgLenValidCount_Cnt_M_u16	19135
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	39911
ISDATBSI412MsgTimer_mS_M_u32	4107267840
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	63268
ISDATBSI432MsgLenValidCount_Cnt_M_u16	47551
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	11856
ISDATDIRASentFltAcc_Cnt_M_u16	20884
ISDATDIRASentTimer_mS_M_u32	2535780096
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	42270
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	63841
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	16758
ISDYN2CMMMsgTimer_mS_M_u32	3082788608
ISDYNAASChkSumInvalidCount_Cnt_M_u16	45172
ISDYNAASChkSumValidCount_Cnt_M_u16	3266
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	2468
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	14594
ISDYNAASMsgLenValidCount_Cnt_M_u16	22952
ISDYNAASMsgTimeValidCount_Cnt_M_u16	45172
ISDYNAASMsgTimer_mS_M_u32	3995795200
ISDYNABRChkSumInvalidCount_Cnt_M_u16	19863
ISDYNABRChkSumValidCount_Cnt_M_u16	53165
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	11575
ISDYNABRMsgCountValidCount_Cnt_M_u16	42437
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	34726
ISDYNABRMsgLenValidCount_Cnt_M_u16	61732
ISDYNABRMsgTimeValidCount_Cnt_M_u16	26904
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	573
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1031

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	30641
ISDYNCMM208MsgTimer_mS_M_u32	3198181120
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2143
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1137
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	24039
ISDYNCMM388MsgTimer_mS_M_u32	3060563712
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	46953
ISDYNVOLChkSumValidCount_Cnt_M_u16	32039
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	55737
ISDYNVOLMsgCountValidCount_Cnt_M_u16	14831
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	5896
ISDYNVOLMsgLenValidCount_Cnt_M_u16	20134
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	62768
ISDYNVOLMsgTimer_mS_M_u32	3446685440
IgnOnTimer_mS_M_u32	1348501248
IgnTimeOff_Sec_M_u32	910475645
ManVehSpd_Kph_M_f32	87.2996979
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	104
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	198
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	409906944
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	36
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1928466176
PrevISDATBSI412MsgDLCError_Cnt_M_u08	149
PrevISDATBSI412MsgRxTime_MSec_M_u32	1299627776
PrevISDATBSI432MsgDLCError_Cnt_M_u08	27
PrevISDATBSI432MsgRxTime_MSec_M_u32	1624350464
PrevISDATDIRAMsgTxTime_MSec_M_u32	465223424
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	163
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4294967295
PrevISDYNAASMsgDLCError_Cnt_M_u08	208
PrevISDYNAASMsgRxTime_MSec_M_u32	1903574784
PrevISDYNABRMsgDLCError_Cnt_M_u08	48
PrevISDYNABRMsgRxTime_MSec_M_u32	2339929856
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	76
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2667527936
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	95
PrevISDYNCMM388MsgRxTime_MSec_M_u32	835231488
PrevISDYNVOLMsgDLCError_Cnt_M_u08	125
PrevISDYNVOLMsgRxTime_MSec_M_u32	1496825600
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3579178752
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	221.998901
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57736
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	31406
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	27461
VitesseVehicleBVRampValidCount_Cnt_M_u16	51243
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	26197
VitesseVehicleBVSigValidCount_Cnt_M_u16	28868
VitesseVehicleBV_Kph_M_f32	269.036713

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	24039
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	30957
VitesseVehiculeRoues_Kph_M_f32	193.362396
k_AASNTCEnableTimeout_mS_u16	1075
k_AASNodeAbsentDiag_Cnt_str.Threshold	36493
k_AASNodeAbsentDiag_Cnt_str.PStep	25450
k_AASNodeAbsentDiag_Cnt_str.NStep	46711
k_AASNodeAbsentTimeout_mS_u16	57776
k_AASNodeTimeout_mS_u16	43438
k_ABSNodeTimeout_mS_u16	37884
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	36275
k_ANGLEVOLANTSigValidThresh_Cnt_u16	28046
k_AngleVolantInvalidThresh_Cnt_u16	31289
k_AngleVolantValidThresh_Cnt_u16	43559
k_BSI552MsgTimeout_mS_u16	39256
k_BSINTCEnableTimeout_mS_u16	25148
k_BSINodeAbsentDiag_Cnt_str.Threshold	20332
k_BSINodeAbsentDiag_Cnt_str.PStep	36899
k_BSINodeAbsentDiag_Cnt_str.NStep	11784
k_BSINodeAbsentTimeout_mS_u16	14147
k_BSINodeTimeout_mS_u16	11856
k_BattOvHi_Volt_f32	27.8978996
k_BattOvLo_Volt_f32	3.65459991
k_BattUvHi_Volt_f32	16.1030006
k_BattUvLo_Volt_f32	6.11450005
k_CAVNTCEnableTimeout_mS_u16	36293
k_CAVNodeAbsentDiag_Cnt_str.Threshold	35055
k_CAVNodeAbsentDiag_Cnt_str.PStep	53341
k_CAVNodeAbsentDiag_Cnt_str.NStep	60030
k_CAVNodeAbsentTimeout_mS_u16	52049
k_CAVNodeTimeout_mS_u16	20975
k_CMM388MsgTimeout_mS_u16	23802
k_CMM388NTCEnableTimeout_mS_u16	2054
k_CMMNTCEnableTimeout_mS_u16	32214
k_CMMNodeAbsentDiag_Cnt_str.Threshold	48914
k_CMMNodeAbsentDiag_Cnt_str.PStep	795
k_CMMNodeAbsentDiag_Cnt_str.NStep	26931
k_CMMNodeAbsentTimeout_mS_u16	37369
k_CONSANGLECPKMax_HwDeg_f32	185.018402
k_CONSANGLECPKMin_HwDeg_f32	-744.300781
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	19687
k_CONSANGLECPKSigValidThresh_Cnt_u16	42989
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	18332
k_CPKVehicleSpeedValidThresh_Cnt_u16	52884
k_CityParkInputInvalidThresh_Cnt_u16	59909
k_CityParkInputValidThresh_Cnt_u16	24661
k_ComputerRazGCTSigValidThresh_Cnt_u16	28556
k_CptTemporelSigValidThresh_Cnt_u16	22334
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	63142
k_DMDFCTCPKSigValidThresh_Cnt_u16	40996
k_DMDFCTCPKValidCount_Cnt_u16	16835
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	16758
k_DMDRELAXECPKSigValidThresh_Cnt_u16	58732
k_DMDRelaxeConsistentThresh_Cnt_u16	13658
k_DateValidThresh_Cnt_u16	36311
k_DefaultVehSpd_Kph_f32	88.0530014
k_DiagMuxOnAbsentTimeout_mS_u16	58422
k_EMNodeTimeout_mS_u16	31732
k_ESPNTCEnableTimeout_mS_u16	7127
k_ESPNodeAbsentDiag_Cnt_str.Threshold	9650
k_ESPNodeAbsentDiag_Cnt_str.PStep	35828
k_ESPNodeAbsentDiag_Cnt_str.NStep	24764
k_ESPNodeAbsentTimeout_mS_u16	52961
k_EtatMTSigInvalidThresh_Cnt_u16	35746
k_EtatMTSigValidThresh_Cnt_u16	4088
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	15091
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	57117
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	42002
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	2703
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	16001
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	31889
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	35445
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	55248

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	14616
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	2028
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	31407
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	2736
k_ISDATDIRASentDiag_Cnt_str.Threshold	40012
k_ISDATDIRASentDiag_Cnt_str.PStep	15598
k_ISDATDIRASentDiag_Cnt_str.NStep	58794
k_ISDATDIRASentTimeout_mS_u16	31139
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	55737
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	53803
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	14771
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	15511
k_ISDYNAASChkSumValidThresh_Cnt_u16	65197
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	39991
k_ISDYNAASMsgCountValidThresh_Cnt_u16	21701
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	20619
k_ISDYNAASMsgLenValidThresh_Cnt_u16	18594
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	49270
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	39468
k_ISDYNABRChkSumValidThresh_Cnt_u16	64554
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	22235
k_ISDYNABRMsgCountValidThresh_Cnt_u16	55754
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	9264
k_ISDYNABRMsgLenValidThresh_Cnt_u16	55243
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	17845
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	41084
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16026
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	11545
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	29720
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	23239
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	41791
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	40364
k_ISDYNVOLChkSumValidThresh_Cnt_u16	35086
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	30716
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	57761
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	38131
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	25021
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	15349
k_IgnOnTimeout_mS_u16	3512
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	168.194107
k_PowerCutVehSpdLowThresh_Kph_f32	204.670593
k_PowerCutVehSpdLowTimeout_mS_u16	62447
k_VBattMaxAAS_Volt_f32	30.7068996
k_VBattMaxBSI_Volt_f32	25.6317997
k_VBattMaxCAV_Volt_f32	3.99379992
k_VBattMaxCMM388_Volt_f32	10.0327997
k_VBattMaxCMM_Volt_f32	13.5393
k_VBattMaxESP_Volt_f32	4.4138999
k_VBattMinAAS_Volt_f32	31.7735004
k_VBattMinBSI_Volt_f32	4.4138999
k_VBattMinCAV_Volt_f32	18.2350006
k_VBattMinCMM388_Volt_f32	6.56150007
k_VBattMinCMM_Volt_f32	31.7745991
k_VBattMinESP_Volt_f32	13.5393
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	21195
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	54045
k_VitesseVehicleBVRampValidThresh_Cnt_u16	51385
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	11303
k_VitesseVehicleBVSigValidThresh_Cnt_u16	58666
k_VitesseVehicleBVSpeedPassThresh_kph_f32	61.4373016
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	35531
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	41009
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2366627584
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	230
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	1989
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2207766784
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	95

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	15.9762001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	899583744
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	254
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.624769032
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	78
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2567077632
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	176
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2858032896
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3636576000
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3426311936
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	750845696
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2723716864
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3573563136
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	98
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	124
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	172
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	163
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3436601088
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	55
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	106
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	220
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	234
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2761522944
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3748732672
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4149788416
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	63
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	88
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	207
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	242
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	180096768
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	614
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.226790622
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	683032
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	108.752899
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	10778

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2207766784	2207766784	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2207766784	2207766784	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	53803	53803	✔
AngleVolantMsgTimer_mS_M_u32	2207766784	2207766784	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1687641856	1687641856	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	2366627584	2366627584	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	734990080	734990080	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	4215852800	4215852800	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	20332	20332	✔
BSINodeAbsentTimer_mS_M_u32	2207766784	2207766784	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2207766784	2207766784	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	35055	35055	✔
CAVNodeAbsentTimer_mS_M_u32	2207766784	2207766784	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2207766784	2207766784	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2207766784	2207766784	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	35837	35837	✔
CMMNodeAbsentTimer_mS_M_u32	2723716864	2723716864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	26904	26904	✔
CONSANGLECPK_HwDeg_M_f32	-335.180786	-335.180786 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	26904	26904	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2535780096	2535780096	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	24470	24470	✔
CityParkInputConsistentCount_Cnt_M_u16	24661	24661	✔
CityParkInputInvalidCount_Cnt_M_u16	43561	43561	✔
CityParkInputMsgTimer_mS_M_u32	2207766784	2207766784	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2207766784	2207766784	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2207766784	2207766784	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2207766784	2207766784	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2207766784	2207766784	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4215852800	4215852800	✔
ESPNTCEnableTimer_mS_M_u32	2207766784	2207766784	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2207766784	2207766784	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	6	6	✔
EffacDefaultDiagTimer_mS_M_u32[1]	16	16	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	65	65	✔
ElecIntTimer_mS_M_u32[1]	656	656	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2207766784	2207766784	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2207766784	2207766784	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	50878	50878	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4095782656	4095782656	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2207766784	2207766784	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	63268	63268	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3426311936	3426311936	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2207766784	2207766784	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2207766784	2207766784	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2207766784	2207766784	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2207766784	2207766784	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2207766784	2207766784	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2207766784	2207766784	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2207766784	2207766784	✔
IgnOnTimer_mS_M_u32	1348501248	1348501248	✔
IgnTimeOff_Sec_M_u32	910475645	910475645	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	78	78	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2567077632	2567077632	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	176	176	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2858032896	2858032896	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3636576000	3636576000	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	119	119	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3426311936	3426311936	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	465223424	465223424	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2723716864	2723716864	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	129	129	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3573563136	3573563136	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	163	163	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3436601088	3436601088	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	173	173	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2761522944	2761522944	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	88	88	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3748732672	3748732672	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	141	141	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4149788416	4149788416	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	180096768	180096768	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	221.998901	221.998901	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	269.036713	269.036713	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	193.362396	193.362396	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	26904	26904	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	910475645	910475645	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-335.180786	-335.180786 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	88.0530014	88.0530014	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0139	0x0139	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0138	0x0138	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.16 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3762091520
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	12843
AASNodeAbsentTimer_mS_M_u32	2827019776
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	34511
ANGLEVOLANTSigValidCount_Cnt_M_u16	18309
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	35224
AngleVolantMsgTimer_mS_M_u32	3762091520
AngleVolantValidCount_Cnt_M_u16	29303
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2920588800
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3064669696
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	321754624
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3149944320
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	43654
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2985170432
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	21816
CAVNodeAbsentTimer_mS_M_u32	1774552576
CDD_SrlComVehSpd_Kph_G_f32	240.3992
CMM388NTCEnableTimer_mS_M_u32	3523069440
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	50038272
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	60103
CMMNodeAbsentTimer_mS_M_u32	2433373696
CONSANGLECPKSigInvalidCount_Cnt_M_u16	23919
CONSANGLECPKSigValidCount_Cnt_M_u16	10869
CONSANGLECPK_Cnt_M_u16	34448
CONSANGLECPK_HwDeg_M_f32	-51.2877998
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	34448

Name	Input Value
CPKVehicleSpeedMsgTimer_mS_M_u32	11269632
CPKVehicleSpeedValidCount_Cnt_M_u16	52000
CityParkInputConsistentCount_Cnt_M_u16	3483
CityParkInputInvalidCount_Cnt_M_u16	18724
CityParkInputMsgTimer_mS_M_u32	2567077632
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	212133376
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	17231
ComputerRazGCTSigInvalidTimer_mS_M_u32	1831732736
ComputerRazGCTSigValidCount_Cnt_M_u16	2880
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	18944
DMDFCTCPKSigValidCount_Cnt_M_u16	59294
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56161
DMDRELAXECPKSigValidCount_Cnt_M_u16	17815
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	15836
DateInvalidTimer_mS_M_u32	3064669696
DiagMuxOnAbsentTimer_mS_M_u32	2068493824
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3149944320
ESPNTCEnableTimer_mS_M_u32	466740736
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	62649
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	88
EffacDefaultDiagTimer_mS_M_u32[1]	108
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	89
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1860179456
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	40869
EtatMTSigValidCount_Cnt_M_u16	12550
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	59393
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	56967
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	56020
ISDAT4V2BSI552MsgTimer_mS_M_u32	2284738048
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	37536
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	31689
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	12550
ISDATBSI3F2MsgTimer_mS_M_u32	2293806592
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	24066
ISDATBSI412MsgLenValidCount_Cnt_M_u16	6236
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	40869
ISDATBSI412MsgTimer_mS_M_u32	1403713024
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	46315
ISDATBSI432MsgLenValidCount_Cnt_M_u16	53725
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	61865
ISDATDIRASentFltAcc_Cnt_M_u16	38877
ISDATDIRASentTimer_mS_M_u32	11269632
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	27262
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	29303
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	32567
ISDYN2CMMMsgTimer_mS_M_u32	2778457600
ISDYNAASChkSumInvalidCount_Cnt_M_u16	21181
ISDYNAASChkSumValidCount_Cnt_M_u16	29330
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	3502
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	6547
ISDYNAASMsgLenValidCount_Cnt_M_u16	19552
ISDYNAASMsgTimeValidCount_Cnt_M_u16	21181
ISDYNAASMsgTimer_mS_M_u32	1742325248
ISDYNABRChkSumInvalidCount_Cnt_M_u16	49363
ISDYNABRChkSumValidCount_Cnt_M_u16	36688
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	43124
ISDYNABRMsgCountValidCount_Cnt_M_u16	29577
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	26150

Name	Input Value
ISDYNABRMsgLenValidCount_Cnt_M_u16	7788
ISDYNABRMsgTimeValidCount_Cnt_M_u16	34448
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	574
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1033
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	12550
ISDYNCMM208MsgTimer_mS_M_u32	66692608
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2147
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1139
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	56549
ISDYNCMM388MsgTimer_mS_M_u32	4111812096
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	41693
ISDYNVOLChkSumValidCount_Cnt_M_u16	18019
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	33390
ISDYNVOLMsgCountValidCount_Cnt_M_u16	13964
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	7682
ISDYNVOLMsgLenValidCount_Cnt_M_u16	60391
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	60103
ISDYNVOLMsgTimer_mS_M_u32	1862927872
IgnOnTimer_mS_M_u32	4147725824
IgnTimeOff_Sec_M_u32	1058443687
ManVehSpd_Kph_M_f32	655.340027
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	106
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	247
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3553539584
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	150
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2311362048
PrevISDATBSI412MsgDLCError_Cnt_M_u08	55
PrevISDATBSI412MsgRxTime_MSec_M_u32	687244800
PrevISDATBSI432MsgDLCError_Cnt_M_u08	216
PrevISDATBSI432MsgRxTime_MSec_M_u32	1919280640
PrevISDATDIRAMsgTxTime_MSec_M_u32	3458893312
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	241
PrevISDYN2CMMMsgRxTime_MSec_M_u32	67772672
PrevISDYNAASMsgDLCError_Cnt_M_u08	235
PrevISDYNAASMsgRxTime_MSec_M_u32	452462080
PrevISDYNABRMsgDLCError_Cnt_M_u08	31
PrevISDYNABRMsgRxTime_MSec_M_u32	2784052736
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	235
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4133291520
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	38
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2608915968
PrevISDYNVOLMsgDLCError_Cnt_M_u08	181
PrevISDYNVOLMsgRxTime_MSec_M_u32	1236502016
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1243149824
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	363.007294
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	47105
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	33102
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	20170

Name	Input Value
VitesseVehicleBVRampValidCount_Cnt_M_u16	52439
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	38680
VitesseVehicleBVSigValidCount_Cnt_M_u16	11406
VitesseVehicleBV_Kph_M_f32	434.691803
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	56549
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	41107
VitesseVehiculeRoues_Kph_M_f32	188.688202
k_AASNTCEnableTimeout_mS_u16	57663
k_AASNodeAbsentDiag_Cnt_str.Threshold	8266
k_AASNodeAbsentDiag_Cnt_str.PStep	25004
k_AASNodeAbsentDiag_Cnt_str.NStep	187
k_AASNodeAbsentTimeout_mS_u16	46474
k_AASNodeTimeout_mS_u16	62542
k_ABSNodeTimeout_mS_u16	8101
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	60734
k_ANGLEVOLANTSigValidThresh_Cnt_u16	45680
k_AngleVolantInvalidThresh_Cnt_u16	63599
k_AngleVolantValidThresh_Cnt_u16	18724
k_BSI552MsgTimeout_mS_u16	43858
k_BSINTCEnableTimeout_mS_u16	54179
k_BSINodeAbsentDiag_Cnt_str.Threshold	20372
k_BSINodeAbsentDiag_Cnt_str.PStep	36882
k_BSINodeAbsentDiag_Cnt_str.NStep	11807
k_BSINodeAbsentTimeout_mS_u16	47696
k_BSINodeTimeout_mS_u16	61865
k_BattOvHi_Volt_f32	6.48789978
k_BattOvLo_Volt_f32	20.5338993
k_BattUvHi_Volt_f32	22.3854008
k_BattUvLo_Volt_f32	28.5790005
k_CAVNTCEnableTimeout_mS_u16	38474
k_CAVNodeAbsentDiag_Cnt_str.Threshold	34493
k_CAVNodeAbsentDiag_Cnt_str.PStep	48042
k_CAVNodeAbsentDiag_Cnt_str.NStep	14015
k_CAVNodeAbsentTimeout_mS_u16	24230
k_CAVNodeTimeout_mS_u16	27467
k_CMM388MsgTimeout_mS_u16	58667
k_CMM388NTCEnableTimeout_mS_u16	5127
k_CMMNTCEnableTimeout_mS_u16	52568
k_CMMNodeAbsentDiag_Cnt_str.Threshold	39577
k_CMMNodeAbsentDiag_Cnt_str.PStep	36727
k_CMMNodeAbsentDiag_Cnt_str.NStep	61031
k_CMMNodeAbsentTimeout_mS_u16	34159
k_CONSANGLECPKMax_HwDeg_f32	543.545105
k_CONSANGLECPKMin_HwDeg_f32	-408.568604
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	4069
k_CONSANGLECPKSigValidThresh_Cnt_u16	5011
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	21124
k_CPKVehicleSpeedValidThresh_Cnt_u16	42013
k_CityParkInputInvalidThresh_Cnt_u16	9097
k_CityParkInputValidThresh_Cnt_u16	3483
k_ComputerRazGCTSigValidThresh_Cnt_u16	20534
k_CptTemporelSigValidThresh_Cnt_u16	24031
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	6438
k_DMDFCTCPKSigValidThresh_Cnt_u16	4460
k_DMDFCTCPKValidCount_Cnt_u16	15566
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	32567
k_DMDRELAXECPKSigValidThresh_Cnt_u16	26645
k_DMDRelaxeConsistentThresh_Cnt_u16	45131
k_DateValidThresh_Cnt_u16	56020
k_DefaultVehSpd_Kph_f32	168.445602
k_DiagMuxOnAbsentTimeout_mS_u16	3382
k_EMNodeTimeout_mS_u16	16700
k_ESPNTCEnableTimeout_mS_u16	1300
k_ESPNodeAbsentDiag_Cnt_str.Threshold	21530
k_ESPNodeAbsentDiag_Cnt_str.PStep	22347
k_ESPNodeAbsentDiag_Cnt_str.NStep	14126
k_ESPNodeAbsentTimeout_mS_u16	28343
k_EtatMTSigInvalidThresh_Cnt_u16	62130
k_EtatMTSigValidThresh_Cnt_u16	47727
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	38015
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	19648
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	30308
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	19245

Name	Input Value
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	29718
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	52774
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	32504
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	64426
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	48911
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	64020
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	42637
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	45256
k_ISDATDIRASentDiag_Cnt_str.Threshold	19236
k_ISDATDIRASentDiag_Cnt_str.PStep	120
k_ISDATDIRASentDiag_Cnt_str.NStep	64444
k_ISDATDIRASentTimeout_mS_u16	27823
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	42925
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	35224
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	7040
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	62419
k_ISDYNAASChkSumValidThresh_Cnt_u16	592
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	23412
k_ISDYNAASMsgCountValidThresh_Cnt_u16	26249
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	34807
k_ISDYNAASMsgLenValidThresh_Cnt_u16	59250
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	22968
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	50836
k_ISDYNABRChkSumValidThresh_Cnt_u16	38234
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	23942
k_ISDYNABRMsgCountValidThresh_Cnt_u16	35196
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	24007
k_ISDYNABRMsgLenValidThresh_Cnt_u16	42937
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	45499
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	19237
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	60427
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	54797
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	14799
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	14981
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	48604
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	38613
k_ISDYNVOLChkSumValidThresh_Cnt_u16	22895
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	52006
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	10612
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	58497
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	41698
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	51322
k_IgnOnTimeout_mS_u16	30385
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	240.522293
k_PowerCutVehSpdLowThresh_Kph_f32	235.092606
k_PowerCutVehSpdLowTimeout_mS_u16	523
k_VBattMaxAAS_Volt_f32	5.15250015
k_VBattMaxBSI_Volt_f32	1.3642
k_VBattMaxCAV_Volt_f32	23.6422997
k_VBattMaxCMM388_Volt_f32	15.3865995
k_VBattMaxCMM_Volt_f32	26.8778992
k_VBattMaxESP_Volt_f32	17.3547993
k_VBattMinAAS_Volt_f32	4.62750006
k_VBattMinBSI_Volt_f32	17.3547993
k_VBattMinCAV_Volt_f32	10.4060001
k_VBattMinCMM388_Volt_f32	1.66289997
k_VBattMinCMM_Volt_f32	32
k_VBattMinESP_Volt_f32	26.8778992
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	1143
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	51265
k_VitesseVehicleBVRampValidThresh_Cnt_u16	46446
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	14691
k_VitesseVehicleBVSigValidThresh_Cnt_u16	4892
k_VitesseVehicleBVSpeedPassThresh_kph_f32	196.684494
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	34872
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	56517
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3064669696
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	150
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	46185

Name	Input Value
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	58406912
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	38
target_SrlComInput_Per1_Batt_Volt_f32.value	13.0219002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2478773760
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	181
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.340999156
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	232
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	626214400
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1473013248
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1930790400
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2133763584
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2216150528
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2312168960
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2556036608
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	26
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	147
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	170
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	188
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	827827712
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	23
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	127
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	133
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	212
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	232
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	512640512
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	44
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3565643264
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	22
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	860915200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	121
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	134
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	220
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1785107968
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2424
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.442019463
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1010652
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	115.095802
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	42571

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	58406912	58406912	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	8266	8266	✔
AASNodeAbsentTimer_mS_M_u32	58406912	58406912	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	35226	35226	✔
AngleVolantMsgTimer_mS_M_u32	58406912	58406912	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	58406912	58406912	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	58406912	58406912	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	58406912	58406912	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	58406912	58406912	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	20372	20372	✔
BSINodeAbsentTimer_mS_M_u32	58406912	58406912	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	58406912	58406912	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	58406912	58406912	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	58406912	58406912	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	58406912	58406912	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	58406912	58406912	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	34448	34448	✔
CONSANGLECPK_HwDeg_M_f32	-51.2877998	-51.2877998 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	34448	34448	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	11269632	11269632	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	52000	52000	✔
CityParkInputConsistentCount_Cnt_M_u16	3483	3483	✔
CityParkInputInvalidCount_Cnt_M_u16	18724	18724	✔
CityParkInputMsgTimer_mS_M_u32	58406912	58406912	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	58406912	58406912	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	58406912	58406912	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	58406912	58406912	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	58406912	58406912	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	58406912	58406912	✔
ESPNTCEnableTimer_mS_M_u32	58406912	58406912	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	21530	21530	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ESPNodeAbsentTimer_mS_M_u32	58406912	58406912	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	88	88	✔
EffacDefaultDiagTimer_mS_M_u32[1]	108	108	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	58406912	58406912	✔
ElecIntTimer_mS_M_u32[1]	89	89	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	58406912	58406912	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	58406912	58406912	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	58406912	58406912	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	58406912	58406912	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	58406912	58406912	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	58406912	58406912	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	58406912	58406912	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	58406912	58406912	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	58406912	58406912	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	58406912	58406912	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	58406912	58406912	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	58406912	58406912	✔
IgnOnTimer_mS_M_u32	4147725824	4147725824	✔
IgnTimeOff_Sec_M_u32	1058443687	1058443687	✔
Msg348Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	232	232	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	626214400	626214400	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	9	9	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1473013248	1473013248	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	15	15	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1930790400	1930790400	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	2	2	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2133763584	2133763584	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3458893312	3458893312	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	206	206	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2312168960	2312168960	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	183	183	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2556036608	2556036608	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	49	49	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	827827712	827827712	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	232	232	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	512640512	512640512	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	44	44	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3565643264	3565643264	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	22	22	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	860915200	860915200	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1785107968	1785107968	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	363.007294	363.007294	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	434.691803	434.691803	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	188.688202	188.688202	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	34448	34448	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1058443687	1058443687	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-51.2877998	-51.2877998 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.17 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1916788992
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	22132
AASNodeAbsentTimer_mS_M_u32	1429475584
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	35462
ANGLEVOLANTSigValidCount_Cnt_M_u16	10790
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	17453
AngleVolantMsgTimer_mS_M_u32	1916788992
AngleVolantValidCount_Cnt_M_u16	28176
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1131991296
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2746568960
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3824025856
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2771763456
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	47969
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2846654720
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	26574
CAVNodeAbsentTimer_mS_M_u32	1810247936
CDD_SrlComVehSpd_Kph_G_f32	435.63739
CMM388NTCEnableTimer_mS_M_u32	1681748224
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4165218560
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	49631
CMMNodeAbsentTimer_mS_M_u32	3445080320
CONSANGLECPKSigInvalidCount_Cnt_M_u16	13735
CONSANGLECPKSigValidCount_Cnt_M_u16	61527
CONSANGLECPK_Cnt_M_u16	2054
CONSANGLECPK_HwDeg_M_f32	23.0193996
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2054
CPKVehicleSpeedMsgTimer_mS_M_u32	2364727552
CPKVehicleSpeedValidCount_Cnt_M_u16	57918

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	11428
CityParkInputInvalidCount_Cnt_M_u16	12040
CityParkInputMsgTimer_mS_M_u32	626214400
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3100119296
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	45832
ComputerRazGCTSigInvalidTimer_mS_M_u32	2746003712
ComputerRazGCTSigValidCount_Cnt_M_u16	1973
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	40052
DMDFCTCPKSigValidCount_Cnt_M_u16	17755
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	21712
DMDRELAXECPKSigValidCount_Cnt_M_u16	63472
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	34912
DateInvalidTimer_mS_M_u32	2746568960
DiagMuxOnAbsentTimer_mS_M_u32	135700736
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2771763456
ESPNTCEnableTimer_mS_M_u32	2134970624
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	30155
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1
EffacDefaultDiagTimer_mS_M_u32[1]	11
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	79
ElecIntTimer_mS_M_u32[1]	700
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3134619904
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	43079
EtatMTSigValidCount_Cnt_M_u16	34275
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24049
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	39969
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	50105
ISDAT4V2BSI552MsgTimer_mS_M_u32	2011939072
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	29909
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	27417
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	34275
ISDATBSI3F2MsgTimer_mS_M_u32	399286528
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	27566
ISDATBSI412MsgLenValidCount_Cnt_M_u16	44642
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	43079
ISDATBSI412MsgTimer_mS_M_u32	1341513984
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	62323
ISDATBSI432MsgLenValidCount_Cnt_M_u16	28255
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	38523
ISDATDIRASentFltAcc_Cnt_M_u16	29663
ISDATDIRASentTimer_mS_M_u32	2364727552
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	37948
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	28176
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0
ISDYN2CMMMsgTimer_mS_M_u32	2313359616
ISDYNAASChkSumInvalidCount_Cnt_M_u16	48318
ISDYNAASChkSumValidCount_Cnt_M_u16	48894
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	14443
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	18109
ISDYNAASMsgLenValidCount_Cnt_M_u16	61461
ISDYNAASMsgTimeValidCount_Cnt_M_u16	48318
ISDYNAASMsgTimer_mS_M_u32	313094400
ISDYNABRChkSumInvalidCount_Cnt_M_u16	41468
ISDYNABRChkSumValidCount_Cnt_M_u16	14404
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	22425
ISDYNABRMsgCountValidCount_Cnt_M_u16	22553
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	46978
ISDYNABRMsgLenValidCount_Cnt_M_u16	45170
ISDYNABRMsgTimeValidCount_Cnt_M_u16	2054

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	575
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1035
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	34275
ISDYNCMM208MsgTimer_mS_M_u32	365547776
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2151
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1141
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	26310
ISDYNCMM388MsgTimer_mS_M_u32	3103191296
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	40285
ISDYNVOLChkSumValidCount_Cnt_M_u16	54413
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	11050
ISDYNVOLMsgCountValidCount_Cnt_M_u16	37009
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	24048
ISDYNVOLMsgLenValidCount_Cnt_M_u16	38399
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	49631
ISDYNVOLMsgTimer_mS_M_u32	236499200
IgnOnTimer_mS_M_u32	1116401920
IgnTimeOff_Sec_M_u32	998489974
ManVehSpd_Kph_M_f32	448.939087
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	108
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	27
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	243966208
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	17
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2619932928
PrevISDATBSI412MsgDLCError_Cnt_M_u08	83
PrevISDATBSI412MsgRxTime_MSec_M_u32	844312832
PrevISDATBSI432MsgDLCError_Cnt_M_u08	214
PrevISDATBSI432MsgRxTime_MSec_M_u32	3414495488
PrevISDATDIRAMsgTxTime_MSec_M_u32	313995520
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	116
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3012378880
PrevISDYNAASMsgDLCError_Cnt_M_u08	10
PrevISDYNAASMsgRxTime_MSec_M_u32	1112453376
PrevISDYNABRMsgDLCError_Cnt_M_u08	115
PrevISDYNABRMsgRxTime_MSec_M_u32	375582976
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	173
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2216669440
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	157
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2083787008
PrevISDYNVOLMsgDLCError_Cnt_M_u08	55
PrevISDYNVOLMsgRxTime_MSec_M_u32	68956416
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2762727680
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	339.578888
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	41843
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	35147
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	17176
VitesseVehicleBVRampValidCount_Cnt_M_u16	2736
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	48555

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	57099
VitesseVehicleBV_Kph_M_f32	142.472107
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	26310
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	56701
VitesseVehiculeRoues_Kph_M_f32	330.541687
k_AASNTCEnableTimeout_mS_u16	29689
k_AASNodeAbsentDiag_Cnt_str.Threshold	31888
k_AASNodeAbsentDiag_Cnt_str.PStep	22657
k_AASNodeAbsentDiag_Cnt_str.NStep	37548
k_AASNodeAbsentTimeout_mS_u16	45271
k_AASNodeTimeout_mS_u16	12363
k_ABSNodeTimeout_mS_u16	61317
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	22138
k_ANGLEVOLANTSigValidThresh_Cnt_u16	55462
k_AngleVolantInvalidThresh_Cnt_u16	49833
k_AngleVolantValidThresh_Cnt_u16	12040
k_BSI552MsgTimeout_mS_u16	31040
k_BSINTCEnableTimeout_mS_u16	30539
k_BSINodeAbsentDiag_Cnt_str.Threshold	20412
k_BSINodeAbsentDiag_Cnt_str.PStep	36865
k_BSINodeAbsentDiag_Cnt_str.NStep	11830
k_BSINodeAbsentTimeout_mS_u16	37381
k_BSINodeTimeout_mS_u16	38523
k_BattOvHi_Volt_f32	31.0907993
k_BattOvLo_Volt_f32	2.50500011
k_BattUvHi_Volt_f32	9.36030006
k_BattUvLo_Volt_f32	29.5953007
k_CAVNTCEnableTimeout_mS_u16	24470
k_CAVNodeAbsentDiag_Cnt_str.Threshold	43117
k_CAVNodeAbsentDiag_Cnt_str.PStep	51199
k_CAVNodeAbsentDiag_Cnt_str.NStep	55896
k_CAVNodeAbsentTimeout_mS_u16	33668
k_CAVNodeTimeout_mS_u16	31763
k_CMM388MsgTimeout_mS_u16	15732
k_CMM388NTCEnableTimeout_mS_u16	8416
k_CMMNTCEnableTimeout_mS_u16	42157
k_CMMNodeAbsentDiag_Cnt_str.Threshold	27137
k_CMMNodeAbsentDiag_Cnt_str.PStep	10369
k_CMMNodeAbsentDiag_Cnt_str.NStep	14344
k_CMMNodeAbsentTimeout_mS_u16	40681
k_CONSANGLECPKMax_HwDeg_f32	446.8367
k_CONSANGLECPKMin_HwDeg_f32	-299.608398
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	52678
k_CONSANGLECPKSigValidThresh_Cnt_u16	33917
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	28073
k_CPKVehicleSpeedValidThresh_Cnt_u16	50525
k_CityParkInputInvalidThresh_Cnt_u16	53722
k_CityParkInputValidThresh_Cnt_u16	11428
k_ComputerRazGCTSigValidThresh_Cnt_u16	5139
k_CptTemporelSigValidThresh_Cnt_u16	40151
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	40578
k_DMDFCTCPKSigValidThresh_Cnt_u16	55154
k_DMDFCTCPKValidCount_Cnt_u16	9353
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	39119
k_DMDRELAXECPKSigValidThresh_Cnt_u16	24566
k_DMDRelaxeConsistentThresh_Cnt_u16	57172
k_DateValidThresh_Cnt_u16	50105
k_DefaultVehSpd_Kph_f32	214.126999
k_DiagMuxOnAbsentTimeout_mS_u16	35860
k_EMNodeTimeout_mS_u16	65088
k_ESPNTCEnableTimeout_mS_u16	51258
k_ESPNodeAbsentDiag_Cnt_str.Threshold	62815
k_ESPNodeAbsentDiag_Cnt_str.PStep	10723
k_ESPNodeAbsentDiag_Cnt_str.NStep	20371
k_ESPNodeAbsentTimeout_mS_u16	785
k_EtatMTSigInvalidThresh_Cnt_u16	18527
k_EtatMTSigValidThresh_Cnt_u16	62183
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	21432
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	15539
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	22089
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	48942
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	63026
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	43842

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	2380
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	25848
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	25863
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	48506
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	43470
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	23644
k_ISDATDIRASentDiag_Cnt_str.Threshold	24504
k_ISDATDIRASentDiag_Cnt_str.PStep	23061
k_ISDATDIRASentDiag_Cnt_str.NStep	26593
k_ISDATDIRASentTimeout_mS_u16	3688
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	19373
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	17453
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	13558
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	2300
k_ISDYNAASChkSumValidThresh_Cnt_u16	57156
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	16025
k_ISDYNAASMsgCountValidThresh_Cnt_u16	32537
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	56464
k_ISDYNAASMsgLenValidThresh_Cnt_u16	59103
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	718
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	52792
k_ISDYNABRChkSumValidThresh_Cnt_u16	33704
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	41569
k_ISDYNABRMsgCountValidThresh_Cnt_u16	65
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	26847
k_ISDYNABRMsgLenValidThresh_Cnt_u16	23755
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	17284
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	31239
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	9619
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	18190
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	29062
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	20774
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	45280
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	52533
k_ISDYNVOLChkSumValidThresh_Cnt_u16	63273
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	59012
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	63960
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	18867
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	41039
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	4807
k_IgnOnTimeout_mS_u16	40353
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	84.3970032
k_PowerCutVehSpdLowThresh_Kph_f32	44.6861
k_PowerCutVehSpdLowTimeout_mS_u16	16789
k_VBattMaxAAS_Volt_f32	18.7623997
k_VBattMaxBSI_Volt_f32	21.1683998
k_VBattMaxCAV_Volt_f32	16.2411995
k_VBattMaxCMM388_Volt_f32	11.4243002
k_VBattMaxCMM_Volt_f32	31
k_VBattMaxESP_Volt_f32	17.1858997
k_VBattMinAAS_Volt_f32	12.3128996
k_VBattMinBSI_Volt_f32	17.1858997
k_VBattMinCAV_Volt_f32	0.488200009
k_VBattMinCMM388_Volt_f32	26.0086994
k_VBattMinCMM_Volt_f32	9.48719978
k_VBattMinESP_Volt_f32	9.91839981
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	56655
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	50098
k_VitesseVehicleBVRampValidThresh_Cnt_u16	37418
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	64397
k_VitesseVehicleBVSigValidThresh_Cnt_u16	24609
k_VitesseVehicleBVSpeedPassThresh_kph_f32	157.209793
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	52942
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	4838
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2746568960
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	224
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	57563
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3423410944
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	157
target_SrlComInput_Per1_Batt_Volt_f32.value	30.2423
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2285469952
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	178
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.023460336
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2688348416
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	112
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3578892544
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2415276288
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	159
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3089813760
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	904884480
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	85
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4047769856
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3525882112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	92
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	118
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	126
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	141
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	150
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	161
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	247
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2242892032
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	11
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	174
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1619783936
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	179
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	186683648
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4215615744
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	83
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	90
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	124
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	182
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	37945600
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1048
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.278018922
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	161377
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	91.9264984
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	32917

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3423410944	3423410944	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3525882112	3525882112	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	17455	17455	✔
AngleVolantMsgTimer_mS_M_u32	3423410944	3423410944	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3423410944	3423410944	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3423410944	3423410944	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3423410944	3423410944	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3423410944	3423410944	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	36139	36139	✔
BSINodeAbsentTimer_mS_M_u32	3089813760	3089813760	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3423410944	3423410944	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4215615744	4215615744	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3423410944	3423410944	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4165218560	4165218560	✔
CMMNTCsEnabled_Cnt_M_lgc	1	1	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	35287	35287	✔
CMMNodeAbsentTimer_mS_M_u32	4047769856	4047769856	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	2054	2054	✔
CONSANGLECPK_HwDeg_M_f32	23.0193996	23.0193996 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2054	2054	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2364727552	2364727552	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	57918	57918	✔
CityParkInputConsistentCount_Cnt_M_u16	11428	11428	✔
CityParkInputInvalidCount_Cnt_M_u16	12042	12042	✔
CityParkInputMsgTimer_mS_M_u32	3423410944	3423410944	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3423410944	3423410944	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3423410944	3423410944	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3423410944	3423410944	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3423410944	3423410944	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3423410944	3423410944	✔
ESPNTCEnableTimer_mS_M_u32	3423410944	3423410944	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3423410944	3423410944	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[1]	11	11	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	79	79	✔
ElecIntTimer_mS_M_u32[1]	700	700	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3423410944	3423410944	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	43079	43079	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3423410944	3423410944	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3423410944	3423410944	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3423410944	3423410944	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3423410944	3423410944	✔
ISDATDIRASentFltAcc_Cnt_M_u16	24504	24504	✔
ISDATDIRASentTimer_mS_M_u32	3423410944	3423410944	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	37948	37948	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4047769856	4047769856	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3423410944	3423410944	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3423410944	3423410944	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	576	576	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1619783936	1619783936	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3423410944	3423410944	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3423410944	3423410944	✔
IgnOnTimer_mS_M_u32	1116401920	1116401920	✔
IgnTimeOff_Sec_M_u32	998489974	998489974	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	167	167	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2688348416	2688348416	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	112	112	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3578892544	3578892544	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2415276288	2415276288	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	159	159	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3089813760	3089813760	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	313995520	313995520	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	85	85	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4047769856	4047769856	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3525882112	3525882112	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	247	247	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2242892032	2242892032	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	84	84	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1619783936	1619783936	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	179	179	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	186683648	186683648	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4215615744	4215615744	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	37945600	37945600	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	339.578888	339.578888	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	142.472107	142.472107	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	330.541687	330.541687	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	2054	2054	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	998489974	998489974	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	23.0193996	23.0193996 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	214.126999	214.126999	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.18 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3248693248
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	34565
AASNodeAbsentTimer_mS_M_u32	1703317504
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	21710
ANGLEVOLANTSigValidCount_Cnt_M_u16	53423
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	57818
AngleVolantMsgTimer_mS_M_u32	3248693248
AngleVolantValidCount_Cnt_M_u16	46770
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2646102016
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	251842560
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1293467648
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3628171264
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	60989
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	366821376
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	58231
CAVNodeAbsentTimer_mS_M_u32	300953600
CDD_SrlComVehSpd_Kph_G_f32	25.3446999
CMM388NTCEnableTimer_mS_M_u32	2515169280
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1691758592
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	34052
CMMNodeAbsentTimer_mS_M_u32	1742438400
CONSANGLECPKSigInvalidCount_Cnt_M_u16	50795
CONSANGLECPKSigValidCount_Cnt_M_u16	12572
CONSANGLECPK_Cnt_M_u16	26127
CONSANGLECPK_HwDeg_M_f32	-733.923706
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	26127

Name	Input Value
CPKVehicleSpeedMsgTimer_mS_M_u32	4253687808
CPKVehicleSpeedValidCount_Cnt_M_u16	32686
CityParkInputConsistentCount_Cnt_M_u16	51958
CityParkInputInvalidCount_Cnt_M_u16	42186
CityParkInputMsgTimer_mS_M_u32	2688348416
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2328530944
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	49481
ComputerRazGCTSigInvalidTimer_mS_M_u32	2761732096
ComputerRazGCTSigValidCount_Cnt_M_u16	48579
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	3206
DMDFCTCPKSigValidCount_Cnt_M_u16	35982
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	40432
DMDRELAXECPKSigValidCount_Cnt_M_u16	3921
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	62016
DateInvalidTimer_mS_M_u32	251842560
DiagMuxOnAbsentTimer_mS_M_u32	3407798272
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3628171264
ESPNTCEnableTimer_mS_M_u32	1532989440
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	62465
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	12
EffacDefaultDiagTimer_mS_M_u32[1]	16
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	37
ElecIntTimer_mS_M_u32[1]	87
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	174014464
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	49867
EtatMTSigValidCount_Cnt_M_u16	29880
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	62861
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	54718
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	2420
ISDAT4V2BSI552MsgTimer_mS_M_u32	3089072128
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	27810
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	29847
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	29880
ISDATBSI3F2MsgTimer_mS_M_u32	4093435904
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	32022
ISDATBSI412MsgLenValidCount_Cnt_M_u16	24507
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	49867
ISDATBSI412MsgTimer_mS_M_u32	2155945984
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	16456
ISDATBSI432MsgLenValidCount_Cnt_M_u16	23109
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	19312
ISDATDIRASentFltAcc_Cnt_M_u16	17220
ISDATDIRASentTimer_mS_M_u32	4253687808
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	6509
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	46770
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	65535
ISDYN2CMMMsgTimer_mS_M_u32	1132040192
ISDYNAASChkSumInvalidCount_Cnt_M_u16	64551
ISDYNAASChkSumValidCount_Cnt_M_u16	53288
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	33697
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	49834
ISDYNAASMsgLenValidCount_Cnt_M_u16	355
ISDYNAASMsgTimeValidCount_Cnt_M_u16	64551
ISDYNAASMsgTimer_mS_M_u32	983986176
ISDYNABRChkSumInvalidCount_Cnt_M_u16	48620
ISDYNABRChkSumValidCount_Cnt_M_u16	62933
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	22422
ISDYNABRMsgCountValidCount_Cnt_M_u16	12503
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	27866

Name	Input Value
ISDYNABRMsgLenValidCount_Cnt_M_u16	7371
ISDYNABRMsgTimeValidCount_Cnt_M_u16	26127
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	576
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1037
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	29880
ISDYNCMM208MsgTimer_mS_M_u32	2865057792
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2155
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1143
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	9360
ISDYNCMM388MsgTimer_mS_M_u32	1572728832
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	59209
ISDYNVOLChkSumValidCount_Cnt_M_u16	56442
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	47204
ISDYNVOLMsgCountValidCount_Cnt_M_u16	748
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	3986
ISDYNVOLMsgLenValidCount_Cnt_M_u16	33315
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	34052
ISDYNVOLMsgTimer_mS_M_u32	358133760
IgnOnTimer_mS_M_u32	285339648
IgnTimeOff_Sec_M_u32	1419996868
ManVehSpd_Kph_M_f32	141.192093
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	110
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	250
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2277695488
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	159
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3496460288
PrevISDATBSI412MsgDLCError_Cnt_M_u08	107
PrevISDATBSI412MsgRxTime_MSec_M_u32	2997432320
PrevISDATBSI432MsgDLCError_Cnt_M_u08	176
PrevISDATBSI432MsgRxTime_MSec_M_u32	2257817600
PrevISDATDIRAMsgTxTime_MSec_M_u32	2709336064
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	22
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1799028736
PrevISDYNAASMsgDLCError_Cnt_M_u08	207
PrevISDYNAASMsgRxTime_MSec_M_u32	3501633536
PrevISDYNABRMsgDLCError_Cnt_M_u08	135
PrevISDYNABRMsgRxTime_MSec_M_u32	4118409216
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	249
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2403577856
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	74
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4035350528
PrevISDYNVOLMsgDLCError_Cnt_M_u08	166
PrevISDYNVOLMsgRxTime_MSec_M_u32	2706255872
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3663667200
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	154.562698
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	1160
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	36289
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	63897

Name	Input Value
VitesseVehicleBVRampValidCount_Cnt_M_u16	56722
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	36703
VitesseVehicleBVSigValidCount_Cnt_M_u16	34304
VitesseVehicleBV_Kph_M_f32	35.7027016
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	9360
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	31529
VitesseVehiculeRoues_Kph_M_f32	464.977386
k_AASNTCEnableTimeout_mS_u16	44598
k_AASNodeAbsentDiag_Cnt_str.Threshold	9034
k_AASNodeAbsentDiag_Cnt_str.PStep	3885
k_AASNodeAbsentDiag_Cnt_str.NStep	31396
k_AASNodeAbsentTimeout_mS_u16	51805
k_AASNodeTimeout_mS_u16	39105
k_ABSNodeTimeout_mS_u16	38739
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	62259
k_ANGLEVOLANTSigValidThresh_Cnt_u16	63344
k_AngleVolantInvalidThresh_Cnt_u16	1383
k_AngleVolantValidThresh_Cnt_u16	42186
k_BSI552MsgTimeout_mS_u16	29664
k_BSINTCEnableTimeout_mS_u16	5312
k_BSINodeAbsentDiag_Cnt_str.Threshold	20452
k_BSINodeAbsentDiag_Cnt_str.PStep	36848
k_BSINodeAbsentDiag_Cnt_str.NStep	11853
k_BSINodeAbsentTimeout_mS_u16	22610
k_BSINodeTimeout_mS_u16	19312
k_BattOvHi_Volt_f32	25.3824005
k_BattOvLo_Volt_f32	5.48309994
k_BattUvHi_Volt_f32	12.6882
k_BattUvLo_Volt_f32	30.5354004
k_CAVNTCEnableTimeout_mS_u16	52000
k_CAVNodeAbsentDiag_Cnt_str.Threshold	25097
k_CAVNodeAbsentDiag_Cnt_str.PStep	10315
k_CAVNodeAbsentDiag_Cnt_str.NStep	50808
k_CAVNodeAbsentTimeout_mS_u16	59477
k_CAVNodeTimeout_mS_u16	41767
k_CMM388MsgTimeout_mS_u16	53765
k_CMM388NTCEnableTimeout_mS_u16	55233
k_CMMNTCEnableTimeout_mS_u16	15642
k_CMMNodeAbsentDiag_Cnt_str.Threshold	50646
k_CMMNodeAbsentDiag_Cnt_str.PStep	4879
k_CMMNodeAbsentDiag_Cnt_str.NStep	49009
k_CMMNodeAbsentTimeout_mS_u16	59109
k_CONSANGLECPKMax_HwDeg_f32	485.033997
k_CONSANGLECPKMin_HwDeg_f32	-509.272186
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	61328
k_CONSANGLECPKSigValidThresh_Cnt_u16	34345
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	55463
k_CPKVehicleSpeedValidThresh_Cnt_u16	60425
k_CityParkInputInvalidThresh_Cnt_u16	9810
k_CityParkInputValidThresh_Cnt_u16	51958
k_ComputerRazGCTSigValidThresh_Cnt_u16	1768
k_CptTemporelSigValidThresh_Cnt_u16	22365
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	47066
k_DMDFCTCPKSigValidThresh_Cnt_u16	42955
k_DMDFCTCPKValidCount_Cnt_u16	21189
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	17269
k_DMDRELAXECPKSigValidThresh_Cnt_u16	26813
k_DMDRelaxeConsistentThresh_Cnt_u16	58019
k_DateValidThresh_Cnt_u16	2420
k_DefaultVehSpd_Kph_f32	96.5048981
k_DiagMuxOnAbsentTimeout_mS_u16	37349
k_EMNodeTimeout_mS_u16	4256
k_ESPNTCEnableTimeout_mS_u16	29235
k_ESPNodeAbsentDiag_Cnt_str.Threshold	31770
k_ESPNodeAbsentDiag_Cnt_str.PStep	33865
k_ESPNodeAbsentDiag_Cnt_str.NStep	9007
k_ESPNodeAbsentTimeout_mS_u16	23149
k_EtatMTSigInvalidThresh_Cnt_u16	5827
k_EtatMTSigValidThresh_Cnt_u16	4588
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	8826
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	12871
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	8711
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	12695

Name	Input Value
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	30540
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	3674
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	41661
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	6778
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	15244
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	5555
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	31608
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	61454
k_ISDATDIRASentDiag_Cnt_str.Threshold	11945
k_ISDATDIRASentDiag_Cnt_str.PStep	20618
k_ISDATDIRASentDiag_Cnt_str.NStep	34910
k_ISDATDIRASentTimeout_mS_u16	10408
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	42523
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	57818
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	7167
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	35052
k_ISDYNAASChkSumValidThresh_Cnt_u16	213
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	41622
k_ISDYNAASMsgCountValidThresh_Cnt_u16	48087
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	24112
k_ISDYNAASMsgLenValidThresh_Cnt_u16	50437
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	6392
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	32952
k_ISDYNABRChkSumValidThresh_Cnt_u16	64297
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	14653
k_ISDYNABRMsgCountValidThresh_Cnt_u16	31326
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	36868
k_ISDYNABRMsgLenValidThresh_Cnt_u16	16129
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	31893
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	53452
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	9063
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	8312
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	40910
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	23471
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	32578
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	13441
k_ISDYNVOLChkSumValidThresh_Cnt_u16	24934
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	50646
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	281
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	36487
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	54644
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	54346
k_IgnOnTimeout_mS_u16	29501
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	226.194794
k_PowerCutVehSpdLowThresh_Kph_f32	1.3276
k_PowerCutVehSpdLowTimeout_mS_u16	46434
k_VBattMaxAAS_Volt_f32	16.5300999
k_VBattMaxBSI_Volt_f32	3.18910003
k_VBattMaxCAV_Volt_f32	30.2490997
k_VBattMaxCMM388_Volt_f32	1.45150006
k_VBattMaxCMM_Volt_f32	31.2399998
k_VBattMaxESP_Volt_f32	15.1687002
k_VBattMinAAS_Volt_f32	26.9517994
k_VBattMinBSI_Volt_f32	15.1687002
k_VBattMinCAV_Volt_f32	12.8936005
k_VBattMinCMM388_Volt_f32	4.45909977
k_VBattMinCMM_Volt_f32	23.1830006
k_VBattMinESP_Volt_f32	6.06610012
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	63797
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	45258
k_VitesseVehicleBVRampValidThresh_Cnt_u16	33636
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	26490
k_VitesseVehicleBVSigValidThresh_Cnt_u16	25727
k_VitesseVehicleBVSpeedPassThresh_kph_f32	120.322197
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	44663
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	7408
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	251842560
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	225
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	43425

Name	Input Value
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2309190144
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	74
target_SrlComInput_Per1_Batt_Volt_f32.value	31
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3996532736
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	197
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.635516584
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1072427008
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	992874496
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	254
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3854577664
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2275561472
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1758752768
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3512111104
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	182
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	153661440
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	22
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	115
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	117
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	194
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	201
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1930645504
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	71
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	140
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	141
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	168
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4211011584
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2512457728
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2681417728
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	91
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	149
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	176
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	190
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2249834496
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1225
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.565522075
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	736663
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	29.8561993
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	29986

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2309190144	2309190144	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2309190144	2309190144	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2309190144	2309190144	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2309190144	2309190144	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2309190144	2309190144	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2309190144	2309190144	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2309190144	2309190144	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	20452	20452	✔
BSINodeAbsentTimer_mS_M_u32	2309190144	2309190144	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2309190144	2309190144	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	25097	25097	✔
CAVNodeAbsentTimer_mS_M_u32	2309190144	2309190144	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2309190144	2309190144	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1691758592	1691758592	✔
CMMNTCsEnabled_Cnt_M_lgc	1	1	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3512111104	3512111104	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	26127	26127	✔
CONSANGLECPK_HwDeg_M_f32	-733.923706	-733.923706 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2309190144	2309190144	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2309190144	2309190144	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2309190144	2309190144	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2309190144	2309190144	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2309190144	2309190144	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2309190144	2309190144	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2309190144	2309190144	✔
ESPNTCEnableTimer_mS_M_u32	2309190144	2309190144	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ESPNodeAbsentTimer_mS_M_u32	2309190144	2309190144	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	12	12	✔
EffacDefaultDiagTimer_mS_M_u32[1]	16	16	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2309190144	2309190144	✔
ElecIntTimer_mS_M_u32[1]	87	87	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2309190144	2309190144	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2309190144	2309190144	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2309190144	2309190144	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2309190144	2309190144	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2309190144	2309190144	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2309190144	2309190144	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3512111104	3512111104	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2309190144	2309190144	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2309190144	2309190144	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4211011584	4211011584	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2309190144	2309190144	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2309190144	2309190144	✔
IgnOnTimer_mS_M_u32	285339648	285339648	✔
IgnTimeOff_Sec_M_u32	1419996868	1419996868	✔
Msg348Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	15	15	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	53	53	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1072427008	1072427008	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	84	84	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	992874496	992874496	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	254	254	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3854577664	3854577664	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	123	123	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2275561472	2275561472	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2709336064	2709336064	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	15	15	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3512111104	3512111104	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	182	182	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	153661440	153661440	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	201	201	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1930645504	1930645504	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4211011584	4211011584	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	134	134	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2512457728	2512457728	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	48	48	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2681417728	2681417728	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2249834496	2249834496	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	154.562698	154.562698	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	35.7027016	35.7027016	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	464.977386	464.977386	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	26127	26127	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1419996868	1419996868	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-733.923706	-733.923706 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	96.5048981	96.5048981	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0121	0x0121	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0129	0x0129	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.19 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1932878592
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	52493
AASNodeAbsentTimer_mS_M_u32	2706051840
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	9652
ANGLEVOLANTSigValidCount_Cnt_M_u16	41425
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	20622
AngleVolantMsgTimer_mS_M_u32	1932878592
AngleVolantValidCount_Cnt_M_u16	55942
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	4021670656
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3856028416
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	794067712
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	551174912
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	54631
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2265383680
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	1593
CAVNodeAbsentTimer_mS_M_u32	3398316800
CDD_SrlComVehSpd_Kph_G_f32	524.850708
CMM388NTCEnableTimer_mS_M_u32	4154422016
CMM388NTCsEnabled_Cnt_M_lgc	1

Name	Input Value
CMMNTCEnableTimer_mS_M_u32	3923522304
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	4689
CMMNodeAbsentTimer_mS_M_u32	1510753024
CONSANGLECPKSigInvalidCount_Cnt_M_u16	30683
CONSANGLECPKSigValidCount_Cnt_M_u16	26504
CONSANGLECPK_Cnt_M_u16	21679
CONSANGLECPK_HwDeg_M_f32	-470.842896
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21679
CPKVehicleSpeedMsgTimer_mS_M_u32	461398784
CPKVehicleSpeedValidCount_Cnt_M_u16	12027
CityParkInputConsistentCount_Cnt_M_u16	44474
CityParkInputInvalidCount_Cnt_M_u16	32064
CityParkInputMsgTimer_mS_M_u32	1072427008
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1098846976
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	11841
ComputerRazGCTSigInvalidTimer_mS_M_u32	1686680320
ComputerRazGCTSigValidCount_Cnt_M_u16	18771
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	13836
DMDFCTCPKSigValidCount_Cnt_M_u16	17841
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	21070
DMDRELAXECPKSigValidCount_Cnt_M_u16	60907
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	34908
DateInvalidTimer_mS_M_u32	3856028416
DiagMuxOnAbsentTimer_mS_M_u32	4123140864
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	551174912
ESPNTCEnableTimer_mS_M_u32	1673532160
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	9498
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	79
EffacDefaultDiagTimer_mS_M_u32[1]	99
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	5
ElecIntTimer_mS_M_u32[1]	156
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	830538496
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	34299
EtatMTSigValidCount_Cnt_M_u16	36852
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	62069
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	33186
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	59135
ISDAT4V2BSI552MsgTimer_mS_M_u32	2034254592
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	23032
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	33241
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	36852
ISDATBSI3F2MsgTimer_mS_M_u32	1932010240
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	18843
ISDATBSI412MsgLenValidCount_Cnt_M_u16	41325
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	34299
ISDATBSI412MsgTimer_mS_M_u32	781935360
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	61573
ISDATBSI432MsgLenValidCount_Cnt_M_u16	590
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	62030
ISDATDIRASentFltAcc_Cnt_M_u16	23250
ISDATDIRASentTimer_mS_M_u32	461398784
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	12949
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	55942
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	3391
ISDYN2CMMMsgTimer_mS_M_u32	2473726720
ISDYNAASChkSumInvalidCount_Cnt_M_u16	30119
ISDYNAASChkSumValidCount_Cnt_M_u16	26981
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	61369
ISDYNAASMsgCount_Cnt_M_u08	0

Name	Input Value
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	62624
ISDYNAASMsgLenValidCount_Cnt_M_u16	34869
ISDYNAASMsgTimeValidCount_Cnt_M_u16	30119
ISDYNAASMsgTimer_mS_M_u32	4184568576
ISDYNABRChkSumInvalidCount_Cnt_M_u16	56281
ISDYNABRChkSumValidCount_Cnt_M_u16	17374
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	57178
ISDYNABRMsgCountValidCount_Cnt_M_u16	50008
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	142
ISDYNABRMsgLenValidCount_Cnt_M_u16	8315
ISDYNABRMsgTimeValidCount_Cnt_M_u16	21679
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	577
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1039
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	36852
ISDYNCMM208MsgTimer_mS_M_u32	1015993088
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2159
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1145
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	35052
ISDYNCMM388MsgTimer_mS_M_u32	1311044352
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	3393
ISDYNVOLChkSumValidCount_Cnt_M_u16	23918
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	10866
ISDYNVOLMsgCountValidCount_Cnt_M_u16	55959
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	22119
ISDYNVOLMsgLenValidCount_Cnt_M_u16	44660
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	4689
ISDYNVOLMsgTimer_mS_M_u32	39105280
IgnOnTimer_mS_M_u32	1146680064
IgnTimeOff_Sec_M_u32	1620319922
ManVehSpd_Kph_M_f32	366.3909
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	112
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	43
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1339433728
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	163
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2707915520
PrevISDATBSI412MsgDLCError_Cnt_M_u08	147
PrevISDATBSI412MsgRxTime_MSec_M_u32	207827712
PrevISDATBSI432MsgDLCError_Cnt_M_u08	86
PrevISDATBSI432MsgRxTime_MSec_M_u32	2988708608
PrevISDATDIRAMsgTxTime_MSec_M_u32	2414293760
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	91
PrevISDYN2CMMMsgRxTime_MSec_M_u32	770556672
PrevISDYNAASMsgDLCError_Cnt_M_u08	198
PrevISDYNAASMsgRxTime_MSec_M_u32	3359290112
PrevISDYNABRMsgDLCError_Cnt_M_u08	202
PrevISDYNABRMsgRxTime_MSec_M_u32	1995502336
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	20
PrevISDYNCMM208MsgRxTime_MSec_M_u32	9679616
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	188
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4920064
PrevISDYNVOLMsgDLCError_Cnt_M_u08	40
PrevISDYNVOLMsgRxTime_MSec_M_u32	343159552
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	419521280
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	614.068909
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1

Name	Input Value
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	9990
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	56091
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	52179
VitesseVehicleBVRampValidCount_Cnt_M_u16	28584
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	64001
VitesseVehicleBVSigValidCount_Cnt_M_u16	1502
VitesseVehicleBV_Kph_M_f32	475.829987
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	35052
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	21729
VitesseVehiculeRoues_Kph_M_f32	145.595596
k_AASNTCEnableTimeout_mS_u16	55354
k_AASNodeAbsentDiag_Cnt_str.Threshold	35035
k_AASNodeAbsentDiag_Cnt_str.PStep	61129
k_AASNodeAbsentDiag_Cnt_str.NStep	43365
k_AASNodeAbsentTimeout_mS_u16	2949
k_AASNodeTimeout_mS_u16	47643
k_ABSNodeTimeout_mS_u16	2469
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	17348
k_ANGLEVOLANTSigValidThresh_Cnt_u16	38605
k_AngleVolantInvalidThresh_Cnt_u16	2280
k_AngleVolantValidThresh_Cnt_u16	32064
k_BSI552MsgTimeout_mS_u16	1724
k_BSINTCEnableTimeout_mS_u16	21277
k_BSINodeAbsentDiag_Cnt_str.Threshold	20492
k_BSINodeAbsentDiag_Cnt_str.PStep	36831
k_BSINodeAbsentDiag_Cnt_str.NStep	11876
k_BSINodeAbsentTimeout_mS_u16	52518
k_BSINodeTimeout_mS_u16	62030
k_BattOvHi_Volt_f32	23.0501003
k_BattOvLo_Volt_f32	9.71829987
k_BattUvHi_Volt_f32	2.2902
k_BattUvLo_Volt_f32	5.59149981
k_CAVNTCEnableTimeout_mS_u16	57918
k_CAVNodeAbsentDiag_Cnt_str.Threshold	1985
k_CAVNodeAbsentDiag_Cnt_str.PStep	47494
k_CAVNodeAbsentDiag_Cnt_str.NStep	26381
k_CAVNodeAbsentTimeout_mS_u16	61343
k_CAVNodeTimeout_mS_u16	53671
k_CMM388MsgTimeout_mS_u16	60429
k_CMM388NTCEnableTimeout_mS_u16	51929
k_CMMNTCEnableTimeout_mS_u16	51344
k_CMMNodeAbsentDiag_Cnt_str.Threshold	17290
k_CMMNodeAbsentDiag_Cnt_str.PStep	46967
k_CMMNodeAbsentDiag_Cnt_str.NStep	19544
k_CMMNodeAbsentTimeout_mS_u16	429
k_CONSANGLECPKMax_HwDeg_f32	101.163002
k_CONSANGLECPKMin_HwDeg_f32	-475.9935
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	10220
k_CONSANGLECPKSigValidThresh_Cnt_u16	13281
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	4713
k_CPKVehicleSpeedValidThresh_Cnt_u16	35010
k_CityParkInputInvalidThresh_Cnt_u16	47783
k_CityParkInputValidThresh_Cnt_u16	44474
k_ComputerRazGCTSigValidThresh_Cnt_u16	8998
k_CptTemporelSigValidThresh_Cnt_u16	29063
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	8078
k_DMDFCTCPKSigValidThresh_Cnt_u16	32635
k_DMDFCTCPKValidCount_Cnt_u16	51151
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	3391
k_DMDRELAXECPKSigValidThresh_Cnt_u16	11556
k_DMDRelaxeConsistentThresh_Cnt_u16	55154
k_DateValidThresh_Cnt_u16	59135
k_DefaultVehSpd_Kph_f32	55.1054993
k_DiagMuxOnAbsentTimeout_mS_u16	43309
k_EMNodeTimeout_mS_u16	44348
k_ESPNTCEnableTimeout_mS_u16	18949

Name	Input Value
k_ESPNodeAbsentDiag_Cnt_str.Threshold	25264
k_ESPNodeAbsentDiag_Cnt_str.PStep	29509
k_ESPNodeAbsentDiag_Cnt_str.NStep	18637
k_ESPNodeAbsentTimeout_mS_u16	50965
k_EtatMTSigInvalidThresh_Cnt_u16	60756
k_EtatMTSigValidThresh_Cnt_u16	2969
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	16624
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	45385
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	11399
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	7961
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	36282
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	42447
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	56614
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	54703
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	3769
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	54723
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	9268
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	8627
k_ISDATDIRASentDiag_Cnt_str.Threshold	18018
k_ISDATDIRASentDiag_Cnt_str.PStep	51390
k_ISDATDIRASentDiag_Cnt_str.NStep	46372
k_ISDATDIRASentTimeout_mS_u16	35749
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	29580
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	20622
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	31905
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	31449
k_ISDYNAASChkSumValidThresh_Cnt_u16	8926
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	65114
k_ISDYNAASMsgCountValidThresh_Cnt_u16	8792
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	2829
k_ISDYNAASMsgLenValidThresh_Cnt_u16	17743
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	21045
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	48372
k_ISDYNABRChkSumValidThresh_Cnt_u16	32097
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	62567
k_ISDYNABRMsgCountValidThresh_Cnt_u16	8388
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	61777
k_ISDYNABRMsgLenValidThresh_Cnt_u16	17434
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	46623
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	53818
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	55976
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	48886
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	17588
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	209
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	52696
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	36698
k_ISDYNVOLChkSumValidThresh_Cnt_u16	2156
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	17307
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	12818
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	4807
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	24000
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	24189
k_IgnOnTimeout_mS_u16	49958
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	188.535706
k_PowerCutVehSpdLowThresh_Kph_f32	103.137299
k_PowerCutVehSpdLowTimeout_mS_u16	29366
k_VBattMaxAAS_Volt_f32	29.1224995
k_VBattMaxBSI_Volt_f32	21.5146008
k_VBattMaxCAV_Volt_f32	2.49950004
k_VBattMaxCMM388_Volt_f32	20.6366005
k_VBattMaxCMM_Volt_f32	31.0100002
k_VBattMaxESP_Volt_f32	18.4790001
k_VBattMinAAS_Volt_f32	24.6375999
k_VBattMinBSI_Volt_f32	18.4790001
k_VBattMinCAV_Volt_f32	17.4090004
k_VBattMinCMM388_Volt_f32	3.33159995
k_VBattMinCMM_Volt_f32	6.68249989
k_VBattMinESP_Volt_f32	6.50260019
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	25150
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	64319
k_VitesseVehicleBVRampValidThresh_Cnt_u16	51570
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	48238

Name	Input Value
k_VitesseVehicleBVSigValidThresh_Cnt_u16	17695
k_VitesseVehicleBVSpeedPassThresh_kph_f32	491.814514
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	42297
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	43406
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3856028416
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	116
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	43525
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3634199552
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	188
target_SrlComInput_Per1_Batt_Volt_f32.value	18.9262009
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2717647616
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	28
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.027602246
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3751473920
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	19
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	508859136
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2401121024
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1509413632
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2799792896
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2648380160
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1726264064
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	146
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	192
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	239
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2611270400
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	41
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	86
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	147
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	223
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	224
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3126981376
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	446403328
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1826960128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	140
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	143
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	154
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	231

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3360785152
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	546
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.439542204
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	171094
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	18.8015995
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	48440

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3634199552	3634199552	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3634199552	3634199552	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	20622	20622	✔
AngleVolantMsgTimer_mS_M_u32	3634199552	3634199552	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4021670656	4021670656	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	3856028416	3856028416	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	3634199552	3634199552	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	551174912	551174912	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	20492	20492	✔
BSINodeAbsentTimer_mS_M_u32	3634199552	3634199552	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3634199552	3634199552	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	1985	1985	✔
CAVNodeAbsentTimer_mS_M_u32	3634199552	3634199552	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3634199552	3634199552	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3923522304	3923522304	✔
CMMNTCsEnabled_Cnt_M_lgc	1	1	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2648380160	2648380160	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	21679	21679	✔
CONSANGLECPK_HwDeg_M_f32	-470.842896	-470.842896 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21679	21679	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	461398784	461398784	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	12027	12027	✔
CityParkInputConsistentCount_Cnt_M_u16	44474	44474	✔
CityParkInputInvalidCount_Cnt_M_u16	32066	32066	✔
CityParkInputMsgTimer_mS_M_u32	3634199552	3634199552	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1098846976	1098846976	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1686680320	1686680320	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3634199552	3634199552	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3634199552	3634199552	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	551174912	551174912	✔
ESPNTCEnableTimer_mS_M_u32	3634199552	3634199552	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3634199552	3634199552	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	79	79	✔
EffacDefaultDiagTimer_mS_M_u32[1]	99	99	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3634199552	3634199552	✔
ElecIntTimer_mS_M_u32[1]	156	156	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3634199552	3634199552	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	34299	34299	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	62069	62069	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3751473920	3751473920	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	23032	23032	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1932010240	1932010240	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	18844	18844	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2401121024	2401121024	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3634199552	3634199552	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3634199552	3634199552	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	12950	12950	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2648380160	2648380160	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3634199552	3634199552	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3634199552	3634199552	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	578	578	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3126981376	3126981376	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3634199552	3634199552	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3634199552	3634199552	✔
IgnOnTimer_mS_M_u32	1146680064	1146680064	✔
IgnTimeOff_Sec_M_u32	1620319922	1620319922	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	222	222	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3751473920	3751473920	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	19	19	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	508859136	508859136	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	229	229	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2401121024	2401121024	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	126	126	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1509413632	1509413632	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2414293760	2414293760	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2648380160	2648380160	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	125	125	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1726264064	1726264064	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	152	152	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2611270400	2611270400	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	16	16	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3126981376	3126981376	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	134	134	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	446403328	446403328	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	90	90	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1826960128	1826960128	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3360785152	3360785152	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	614.068909	614.068909	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	475.829987	475.829987	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	145.595596	145.595596	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	21679	21679	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1620319922	1620319922	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-470.842896	-470.842896 ± 0.0125	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	55.1054993	55.1054993	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.20 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1867160064
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	25537
AASNodeAbsentTimer_mS_M_u32	2546567680
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	5069
ANGLEVOLANTSigValidCount_Cnt_M_u16	53302
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	7486
AngleVolantMsgTimer_mS_M_u32	1867160064
AngleVolantValidCount_Cnt_M_u16	26071
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3347663360
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	120048128
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	527251968

Name	Input Value
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2447112704
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	37044
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	39172608
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	52415
CAVNodeAbsentTimer_mS_M_u32	2424318464
CDD_SrlComVehSpd_Kph_G_f32	523.087708
CMM388NTCEnableTimer_mS_M_u32	3729549824
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3935709696
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	54838
CMMNodeAbsentTimer_mS_M_u32	776337920
CONSANGLECPKSigInvalidCount_Cnt_M_u16	10329
CONSANGLECPKSigValidCount_Cnt_M_u16	51729
CONSANGLECPK_Cnt_M_u16	24220
CONSANGLECPK_HwDeg_M_f32	-17.4020004
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	24220
CPKVehicleSpeedMsgTimer_mS_M_u32	1651087872
CPKVehicleSpeedValidCount_Cnt_M_u16	64064
CityParkInputConsistentCount_Cnt_M_u16	48187
CityParkInputInvalidCount_Cnt_M_u16	13992
CityParkInputMsgTimer_mS_M_u32	3751473920
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2267908608
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	4133
ComputerRazGCTSigInvalidTimer_mS_M_u32	3432032768
ComputerRazGCTSigValidCount_Cnt_M_u16	36208
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	15428
DMDFCTCPKSigValidCount_Cnt_M_u16	24084
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	30207
DMDRELAXECPKSigValidCount_Cnt_M_u16	54248
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	15062
DateInvalidTimer_mS_M_u32	120048128
DiagMuxOnAbsentTimer_mS_M_u32	178543104
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2447112704
ESPNTCEnableTimer_mS_M_u32	1684703744
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	32410
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	68
EffacDefaultDiagTimer_mS_M_u32[1]	2595639040
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	1111
ElecIntTimer_mS_M_u32[1]	2595639040
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1793571328
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	62519
EtatMTSigValidCount_Cnt_M_u16	30476
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	41099
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	25539
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	12842
ISDAT4V2BSI552MsgTimer_mS_M_u32	2695494144
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	961
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	52445
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	30476
ISDATBSI3F2MsgTimer_mS_M_u32	2859620864
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	53719
ISDATBSI412MsgLenValidCount_Cnt_M_u16	52003
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	62519
ISDATBSI412MsgTimer_mS_M_u32	1427675648
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	2970

Name	Input Value
ISDATBSI432MsgLenValidCount_Cnt_M_u16	46846
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	40064
ISDATDIRASentFltAcc_Cnt_M_u16	29428
ISDATDIRASentTimer_mS_M_u32	1651087872
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	56554
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	26071
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	17067
ISDYN2CMMMsgTimer_mS_M_u32	492079616
ISDYNAASChkSumInvalidCount_Cnt_M_u16	20979
ISDYNAASChkSumValidCount_Cnt_M_u16	10107
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	45630
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	23946
ISDYNAASMsgLenValidCount_Cnt_M_u16	45963
ISDYNAASMsgTimeValidCount_Cnt_M_u16	20979
ISDYNAASMsgTimer_mS_M_u32	149449216
ISDYNABRChkSumInvalidCount_Cnt_M_u16	7390
ISDYNABRChkSumValidCount_Cnt_M_u16	46479
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	41178
ISDYNABRMsgCountValidCount_Cnt_M_u16	42402
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	6720
ISDYNABRMsgLenValidCount_Cnt_M_u16	11064
ISDYNABRMsgTimeValidCount_Cnt_M_u16	24220
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	578
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1041
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	30476
ISDYNCMM208MsgTimer_mS_M_u32	2231257600
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2163
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1147
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	29349
ISDYNCMM388MsgTimer_mS_M_u32	3501976064
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	32807
ISDYNVOLChkSumValidCount_Cnt_M_u16	95
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	30482
ISDYNVOLMsgCountValidCount_Cnt_M_u16	46946
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	24243
ISDYNVOLMsgLenValidCount_Cnt_M_u16	18252
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	54838
ISDYNVOLMsgTimer_mS_M_u32	590129664
IgnOnTimer_mS_M_u32	3189762560
IgnTimeOff_Sec_M_u32	2796020555
ManVehSpd_Kph_M_f32	431.21991
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	114
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	32
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1281907200
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	123
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3576969728
PrevISDATBSI412MsgDLCError_Cnt_M_u08	183
PrevISDATBSI412MsgRxTime_MSec_M_u32	1593911808
PrevISDATBSI432MsgDLCError_Cnt_M_u08	187
PrevISDATBSI432MsgRxTime_MSec_M_u32	155093504
PrevISDATDIRAMsgTxTime_MSec_M_u32	3832883712
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	252
PrevISDYN2CMMMsgRxTime_MSec_M_u32	413235712
PrevISDYNAASMsgDLCError_Cnt_M_u08	1
PrevISDYNAASMsgRxTime_MSec_M_u32	3917130240
PrevISDYNABRMsgDLCError_Cnt_M_u08	117
PrevISDYNABRMsgRxTime_MSec_M_u32	2253908480
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	182
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3832523264
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	234
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2060028416
PrevISDYNVOLMsgDLCError_Cnt_M_u08	36

Name	Input Value
PrevISDYNVOLMsgRxTime_MSec_M_u32	3402508800
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2917571072
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	137.496902
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	56920
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	53977
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	25585
VitesseVehicleBVRampValidCount_Cnt_M_u16	35122
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	2790
VitesseVehicleBVSigValidCount_Cnt_M_u16	6159
VitesseVehicleBV_Kph_M_f32	67.6501999
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	29349
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	40837
VitesseVehiculeRoues_Kph_M_f32	154.603699
k_AASNTCEnableTimeout_mS_u16	49147
k_AASNodeAbsentDiag_Cnt_str.Threshold	48109
k_AASNodeAbsentDiag_Cnt_str.PStep	45499
k_AASNodeAbsentDiag_Cnt_str.NStep	25791
k_AASNodeAbsentTimeout_mS_u16	36570
k_AASNodeTimeout_mS_u16	13785
k_ABSNodeTimeout_mS_u16	25977
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	52701
k_ANGLEVOLANTSigValidThresh_Cnt_u16	46465
k_AngleVolantInvalidThresh_Cnt_u16	35632
k_AngleVolantValidThresh_Cnt_u16	13992
k_BSI552MsgTimeout_mS_u16	46580
k_BSINTCEnableTimeout_mS_u16	17362
k_BSINodeAbsentDiag_Cnt_str.Threshold	20532
k_BSINodeAbsentDiag_Cnt_str.PStep	36814
k_BSINodeAbsentDiag_Cnt_str.NStep	11899
k_BSINodeAbsentTimeout_mS_u16	1910
k_BSINodeTimeout_mS_u16	40064
k_BattOvHi_Volt_f32	21.3882999
k_BattOvLo_Volt_f32	20.4731998
k_BattUvHi_Volt_f32	0.196600005
k_BattUvLo_Volt_f32	14.7628002
k_CAVNTCEnableTimeout_mS_u16	32686
k_CAVNodeAbsentDiag_Cnt_str.Threshold	57331
k_CAVNodeAbsentDiag_Cnt_str.PStep	33914
k_CAVNodeAbsentDiag_Cnt_str.NStep	40702
k_CAVNodeAbsentTimeout_mS_u16	10381
k_CAVNodeTimeout_mS_u16	19189
k_CMM388MsgTimeout_mS_u16	1729
k_CMM388NTCEnableTimeout_mS_u16	39517
k_CMMNTCEnableTimeout_mS_u16	6137
k_CMMNodeAbsentDiag_Cnt_str.Threshold	50751
k_CMMNodeAbsentDiag_Cnt_str.PStep	40720
k_CMMNodeAbsentDiag_Cnt_str.NStep	26692
k_CMMNodeAbsentTimeout_mS_u16	51489
k_CONSANGLECPKMax_HwDeg_f32	449.800812
k_CONSANGLECPKMin_HwDeg_f32	-399.503998
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	38309
k_CONSANGLECPKSigValidThresh_Cnt_u16	645
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	58607
k_CPKVehicleSpeedValidThresh_Cnt_u16	28770
k_CityParkInputInvalidThresh_Cnt_u16	14452
k_CityParkInputValidThresh_Cnt_u16	48187
k_ComputerRazGCTSigValidThresh_Cnt_u16	57399

Name	Input Value
k_CptTemporelSigValidThresh_Cnt_u16	13779
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	48448
k_DMDFCTCPKSigValidThresh_Cnt_u16	3640
k_DMDFCTCPKValidCount_Cnt_u16	22908
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	17067
k_DMDRELAXECPKSigValidThresh_Cnt_u16	13243
k_DMDRelaxeConsistentThresh_Cnt_u16	60625
k_DateValidThresh_Cnt_u16	12842
k_DefaultVehSpd_Kph_f32	66.100502
k_DiagMuxOnAbsentTimeout_mS_u16	55586
k_EMNodeTimeout_mS_u16	19510
k_ESPNTCEnableTimeout_mS_u16	12635
k_ESPNodeAbsentDiag_Cnt_str.Threshold	38573
k_ESPNodeAbsentDiag_Cnt_str.PStep	35461
k_ESPNodeAbsentDiag_Cnt_str.NStep	64199
k_ESPNodeAbsentTimeout_mS_u16	6377
k_EtatMTSigInvalidThresh_Cnt_u16	37997
k_EtatMTSigValidThresh_Cnt_u16	2654
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	13658
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	1294
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	46036
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	30814
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	27962
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	36155
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	2487
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	219
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	33022
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	11104
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	49357
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	46737
k_ISDATDIRASentDiag_Cnt_str.Threshold	37008
k_ISDATDIRASentDiag_Cnt_str.PStep	57170
k_ISDATDIRASentDiag_Cnt_str.NStep	31032
k_ISDATDIRASentTimeout_mS_u16	15738
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	25862
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	7486
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	2439
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	16350
k_ISDYNAASChkSumValidThresh_Cnt_u16	6287
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	17370
k_ISDYNAASMsgCountValidThresh_Cnt_u16	34978
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	24386
k_ISDYNAASMsgLenValidThresh_Cnt_u16	25661
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	9033
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	64782
k_ISDYNABRChkSumValidThresh_Cnt_u16	11398
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	13236
k_ISDYNABRMsgCountValidThresh_Cnt_u16	57181
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	14646
k_ISDYNABRMsgLenValidThresh_Cnt_u16	8602
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	19276
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	44220
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	37552
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	21320
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	46797
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	45878
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	42208
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	48282
k_ISDYNVOLChkSumValidThresh_Cnt_u16	21030
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	26391
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	47859
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	32211
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	15784
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	17328
k_IgnOnTimeout_mS_u16	20790
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	146.309998
k_PowerCutVehSpdLowThresh_Kph_f32	122.505302
k_PowerCutVehSpdLowTimeout_mS_u16	57479
k_VBattMaxAAS_Volt_f32	4.59639978
k_VBattMaxBSI_Volt_f32	5.31279993
k_VBattMaxCAV_Volt_f32	7.86269999
k_VBattMaxCMM388_Volt_f32	26.219101

Name	Input Value
k_VBattMaxCMM_Volt_f32	3.49130011
k_VBattMaxESP_Volt_f32	14.7095003
k_VBattMinAAS_Volt_f32	3.7104001
k_VBattMinBSI_Volt_f32	14.7095003
k_VBattMinCAV_Volt_f32	8.60620022
k_VBattMinCMM388_Volt_f32	3.98099995
k_VBattMinCMM_Volt_f32	13.3608999
k_VBattMinESP_Volt_f32	3.49130011
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	57584
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	54956
k_VitesseVehicleBVRampValidThresh_Cnt_u16	39442
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	58207
k_VitesseVehicleBVSigValidThresh_Cnt_u16	51724
k_VitesseVehicleBVSpeedPassThresh_kph_f32	522.8479
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	61375
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	62336
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	120048128
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	105
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	3134
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2595639040
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	234
target_SrlComInput_Per1_Batt_Volt_f32.value	17.0237007
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3312892416
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	83
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.753126383
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1952049664
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	648874496
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	159
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2194680320
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	163
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	281233920
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1485203968
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3793324544
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	146
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	897362432
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	37
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	99
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	116
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	179
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	237
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1069304320
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	39
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	84
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	121
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	125
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	139
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	151
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	191

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3221547520
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	10
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	232262144
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	27
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3313183232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	47
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	129
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	132
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	185
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	195
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	199
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2289449472
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2316
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0862151682
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	230240
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	115.762398
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	25538

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2595639040	2595639040	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	48109	48109	✔
AASNodeAbsentTimer_mS_M_u32	2595639040	2595639040	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2595639040	2595639040	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2595639040	2595639040	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2595639040	2595639040	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2595639040	2595639040	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2595639040	2595639040	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	20532	20532	✔
BSINodeAbsentTimer_mS_M_u32	2595639040	2595639040	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2595639040	2595639040	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2595639040	2595639040	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2595639040	2595639040	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2595639040	2595639040	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2595639040	2595639040	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	24220	24220	✔
CONSANGLECPK_HwDeg_M_f32	-17.4020004	-17.4020004 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2595639040	2595639040	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2595639040	2595639040	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2595639040	2595639040	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2595639040	2595639040	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2595639040	2595639040	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2595639040	2595639040	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2595639040	2595639040	✔
ESPNTCEnableTimer_mS_M_u32	2595639040	2595639040	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	38573	38573	✔
ESPNodeAbsentTimer_mS_M_u32	2595639040	2595639040	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	68	68	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2595639040	2595639040	✔
ElecIntCount_Cnt_M_u08	2	2	✔
ElecIntTimer_mS_M_u32[0]	1111	1111	✔
ElecIntTimer_mS_M_u32[1]	2595639040	2595639040	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2595639040	2595639040	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2595639040	2595639040	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2595639040	2595639040	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2595639040	2595639040	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2595639040	2595639040	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2595639040	2595639040	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2595639040	2595639040	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2595639040	2595639040	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2595639040	2595639040	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2595639040	2595639040	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2595639040	2595639040	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2595639040	2595639040	✔
IgnOnTimer_mS_M_u32	3189762560	3189762560	✔
IgnTimeOff_Sec_M_u32	2796020555	2796020555	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	216	216	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1952049664	1952049664	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	136	136	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	648874496	648874496	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	159	159	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2194680320	2194680320	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	163	163	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	281233920	281233920	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3832883712	3832883712	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3793324544	3793324544	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	146	146	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	897362432	897362432	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	74	74	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1069304320	1069304320	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	30	30	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3221547520	3221547520	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	10	10	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	232262144	232262144	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	27	27	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3313183232	3313183232	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2289449472	2289449472	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	137.496902	137.496902	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	67.6501999	67.6501999	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	154.603699	154.603699	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	24220	24220	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2796020555	2796020555	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-17.4020004	-17.4020004 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.21 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2024207616
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	38211
AASNodeAbsentTimer_mS_M_u32	3874104576
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	22301
ANGLEVOLANTSigValidCount_Cnt_M_u16	36772
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	40140
AngleVolantMsgTimer_mS_M_u32	2024207616
AngleVolantValidCount_Cnt_M_u16	3969
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	111863040
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3788465408
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3133084928
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2389890304
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	15464
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1409651968
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	7367
CAVNodeAbsentTimer_mS_M_u32	2672182528

Name	Input Value
CDD_SrlComVehSpd_Kph_G_f32	99.2157974
CMM388NTCEnableTimer_mS_M_u32	920749312
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1761887488
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	30499
CMMNodeAbsentTimer_mS_M_u32	3778336000
CONSANGLECPKSigInvalidCount_Cnt_M_u16	63610
CONSANGLECPKSigValidCount_Cnt_M_u16	49425
CONSANGLECPK_Cnt_M_u16	61296
CONSANGLECPK_HwDeg_M_f32	-130.087006
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	61296
CPKVehicleSpeedMsgTimer_mS_M_u32	3679057152
CPKVehicleSpeedValidCount_Cnt_M_u16	48364
CityParkInputConsistentCount_Cnt_M_u16	40021
CityParkInputInvalidCount_Cnt_M_u16	29197
CityParkInputMsgTimer_mS_M_u32	1952049664
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2831033600
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	8215
ComputerRazGCTSigInvalidTimer_mS_M_u32	3440690432
ComputerRazGCTSigValidCount_Cnt_M_u16	15542
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	53561
DMDFCTCPKSigValidCount_Cnt_M_u16	31112
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	30855
DMDRELAXECPKSigValidCount_Cnt_M_u16	52366
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	62723
DateInvalidTimer_mS_M_u32	3788465408
DiagMuxOnAbsentTimer_mS_M_u32	1033483520
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2389890304
ESPNTCEnableTimer_mS_M_u32	1158096128
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	56246
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	117
EffacDefaultDiagTimer_mS_M_u32[1]	777
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65535
ElecIntTimer_mS_M_u32[1]	95536
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3796866304
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	45599
EtatMTSigValidCount_Cnt_M_u16	18274
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	55268
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	15355
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	54598
ISDAT4V2BSI552MsgTimer_mS_M_u32	436786432
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	57603
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	50030
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	18274
ISDATBSI3F2MsgTimer_mS_M_u32	372225280
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	40896
ISDATBSI412MsgLenValidCount_Cnt_M_u16	45467
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	45599
ISDATBSI412MsgTimer_mS_M_u32	2134701312
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	26359
ISDATBSI432MsgLenValidCount_Cnt_M_u16	49802
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	61828
ISDATDIRASentFltAcc_Cnt_M_u16	15912
ISDATDIRASentTimer_mS_M_u32	3679057152
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	11398
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	3969
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	6660
ISDYN2CMMMsgTimer_mS_M_u32	1112089856
ISDYNAASChkSumInvalidCount_Cnt_M_u16	4781

Name	Input Value
ISDYNAASChkSumValidCount_Cnt_M_u16	32724
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	34380
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	22118
ISDYNAASMsgLenValidCount_Cnt_M_u16	8741
ISDYNAASMsgTimeValidCount_Cnt_M_u16	4781
ISDYNAASMsgTimer_mS_M_u32	655197440
ISDYNABRChkSumInvalidCount_Cnt_M_u16	47465
ISDYNABRChkSumValidCount_Cnt_M_u16	32024
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	33272
ISDYNABRMsgCountValidCount_Cnt_M_u16	24927
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	32453
ISDYNABRMsgLenValidCount_Cnt_M_u16	63900
ISDYNABRMsgTimeValidCount_Cnt_M_u16	61296
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	579
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1043
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	18274
ISDYNCMM208MsgTimer_mS_M_u32	3796624640
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2167
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1149
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	41239
ISDYNCMM388MsgTimer_mS_M_u32	2106787072
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	43280
ISDYNVOLChkSumValidCount_Cnt_M_u16	54823
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	55503
ISDYNVOLMsgCountValidCount_Cnt_M_u16	9630
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	57195
ISDYNVOLMsgLenValidCount_Cnt_M_u16	21345
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	30499
ISDYNVOLMsgTimer_mS_M_u32	960546048
IgnOnTimer_mS_M_u32	1164379392
IgnTimeOff_Sec_M_u32	906394273
ManVehSpd_Kph_M_f32	107.5401
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	116
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	219
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2286793984
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	121
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1969886464
PrevISDATBSI412MsgDLCError_Cnt_M_u08	162
PrevISDATBSI412MsgRxTime_MSec_M_u32	2009285888
PrevISDATBSI432MsgDLCError_Cnt_M_u08	179
PrevISDATBSI432MsgRxTime_MSec_M_u32	2794136832
PrevISDATDIRAMsgTxTime_MSec_M_u32	3076998400
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	250
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4028781824
PrevISDYNAASMsgDLCError_Cnt_M_u08	34
PrevISDYNAASMsgRxTime_MSec_M_u32	2656486656
PrevISDYNABRMsgDLCError_Cnt_M_u08	72
PrevISDYNABRMsgRxTime_MSec_M_u32	3435070720
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	37
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3245851904
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	0
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1038755072
PrevISDYNVOLMsgDLCError_Cnt_M_u08	220
PrevISDYNVOLMsgRxTime_MSec_M_u32	2824619264
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	752022784
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	297.116302
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime

Name	Input Value
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	35836
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	31803
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	40753
VitesseVehicleBVRampValidCount_Cnt_M_u16	64816
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	5586
VitesseVehicleBVSigValidCount_Cnt_M_u16	23577
VitesseVehicleBV_Kph_M_f32	647.667175
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	41239
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	26677
VitesseVehiculeRoues_Kph_M_f32	472.694702
k_AASNTCEnableTimeout_mS_u16	1875
k_AASNodeAbsentDiag_Cnt_str.Threshold	14851
k_AASNodeAbsentDiag_Cnt_str.PStep	16849
k_AASNodeAbsentDiag_Cnt_str.NStep	57404
k_AASNodeAbsentTimeout_mS_u16	24696
k_AASNodeTimeout_mS_u16	21307
k_ABSNodeTimeout_mS_u16	27034
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	60462
k_ANGLEVOLANTSigValidThresh_Cnt_u16	37633
k_AngleVolantInvalidThresh_Cnt_u16	36340
k_AngleVolantValidThresh_Cnt_u16	29197
k_BSI552MsgTimeout_mS_u16	41192
k_BSINTCEnableTimeout_mS_u16	40527
k_BSINodeAbsentDiag_Cnt_str.Threshold	20572
k_BSINodeAbsentDiag_Cnt_str.PStep	36797
k_BSINodeAbsentDiag_Cnt_str.NStep	11922
k_BSINodeAbsentTimeout_mS_u16	48676
k_BSINodeTimeout_mS_u16	61828
k_BattOvHi_Volt_f32	25.9433002
k_BattOvLo_Volt_f32	21.4206009
k_BattUvHi_Volt_f32	14.9334002
k_BattUvLo_Volt_f32	27.8244991
k_CAVNTCEnableTimeout_mS_u16	12027
k_CAVNodeAbsentDiag_Cnt_str.Threshold	52167
k_CAVNodeAbsentDiag_Cnt_str.PStep	4265
k_CAVNodeAbsentDiag_Cnt_str.NStep	47064
k_CAVNodeAbsentTimeout_mS_u16	49501
k_CAVNodeTimeout_mS_u16	166
k_CMM388MsgTimeout_mS_u16	44099
k_CMM388NTCEnableTimeout_mS_u16	24943
k_CMMNTCEnableTimeout_mS_u16	33883
k_CMMNodeAbsentDiag_Cnt_str.Threshold	60395
k_CMMNodeAbsentDiag_Cnt_str.PStep	9138
k_CMMNodeAbsentDiag_Cnt_str.NStep	37004
k_CMMNodeAbsentTimeout_mS_u16	23393
k_CONSANGLECPKMax_HwDeg_f32	397.250488
k_CONSANGLECPKMin_HwDeg_f32	-230.5121
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	14359
k_CONSANGLECPKSigValidThresh_Cnt_u16	16181
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	7673
k_CPKVehicleSpeedValidThresh_Cnt_u16	45087
k_CityParkInputInvalidThresh_Cnt_u16	16039
k_CityParkInputValidThresh_Cnt_u16	40021
k_ComputerRazGCTSigValidThresh_Cnt_u16	41889
k_CptTemporelSigValidThresh_Cnt_u16	57484
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	38341
k_DMDFCTCPKSigValidThresh_Cnt_u16	20636
k_DMDFCTCPKValidCount_Cnt_u16	528
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	6660
k_DMDRELAXECPKSigValidThresh_Cnt_u16	21651
k_DMDRelaxeConsistentThresh_Cnt_u16	337
k_DateValidThresh_Cnt_u16	54598
k_DefaultVehSpd_Kph_f32	164.724899

Name	Input Value
k_DiagMuxOnAbsentTimeout_mS_u16	6110
k_EMNodeTimeout_mS_u16	16611
k_ESPNTCEnableTimeout_mS_u16	24307
k_ESPNodeAbsentDiag_Cnt_str.Threshold	28929
k_ESPNodeAbsentDiag_Cnt_str.PStep	33970
k_ESPNodeAbsentDiag_Cnt_str.NStep	49508
k_ESPNodeAbsentTimeout_mS_u16	35849
k_EtatMTSigInvalidThresh_Cnt_u16	20156
k_EtatMTSigValidThresh_Cnt_u16	31403
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	39096
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	51034
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	22922
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	14124
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	38487
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	64916
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	8352
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	39155
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	38603
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	39204
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	22175
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	43666
k_ISDATDIRASentDiag_Cnt_str.Threshold	29809
k_ISDATDIRASentDiag_Cnt_str.PStep	26275
k_ISDATDIRASentDiag_Cnt_str.NStep	56232
k_ISDATDIRASentTimeout_mS_u16	51093
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	45875
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	40140
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	34415
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	20585
k_ISDYNAASChkSumValidThresh_Cnt_u16	21528
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	39160
k_ISDYNAASMsgCountValidThresh_Cnt_u16	47199
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	33341
k_ISDYNAASMsgLenValidThresh_Cnt_u16	22543
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	27049
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	36443
k_ISDYNABRChkSumValidThresh_Cnt_u16	44466
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	21352
k_ISDYNABRMsgCountValidThresh_Cnt_u16	48687
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	20003
k_ISDYNABRMsgLenValidThresh_Cnt_u16	62134
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	63074
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	45264
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	309
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	30446
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	28189
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	59044
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	1893
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	43895
k_ISDYNVOLChkSumValidThresh_Cnt_u16	59538
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	22079
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	64748
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	34123
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	25486
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	14516
k_IgnOnTimeout_mS_u16	23971
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	18.5965004
k_PowerCutVehSpdLowThresh_Kph_f32	162.010605
k_PowerCutVehSpdLowTimeout_mS_u16	54703
k_VBattMaxAAS_Volt_f32	11.6086998
k_VBattMaxBSI_Volt_f32	9.78190041
k_VBattMaxCAV_Volt_f32	0.617299974
k_VBattMaxCMM388_Volt_f32	24.2455006
k_VBattMaxCMM_Volt_f32	23.8185997
k_VBattMaxESP_Volt_f32	13.7215996
k_VBattMinAAS_Volt_f32	24.2891006
k_VBattMinBSI_Volt_f32	13.7215996
k_VBattMinCAV_Volt_f32	26.9720001
k_VBattMinCMM388_Volt_f32	16.4199009
k_VBattMinCMM_Volt_f32	28.9822998
k_VBattMinESP_Volt_f32	23.8185997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	26485

Name	Input Value
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	17407
k_VitesseVehicleBVRampValidThresh_Cnt_u16	28623
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	11559
k_VitesseVehicleBVSigValidThresh_Cnt_u16	63202
k_VitesseVehicleBVSpeedPassThresh_kph_f32	397.980103
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	46023
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	30278
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3788465408
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	41
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	27030
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1937233408
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	0
target_SrlComInput_Per1_Batt_Volt_f32.value	19.6823006
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3466761472
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	37
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0500994623
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2327381248
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	675259648
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	139871488
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	217
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2466047232
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	808682752
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1207575808
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1112589568
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	78
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	94
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	141
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	171
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	183
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	705815808
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	30
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	243
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	214
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	330827008
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3737036032
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2891269376
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	94
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	111

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	131
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	132
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	157
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	187
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3819181312
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3002
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.937691689
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	2442
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	193.489304
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	9150

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1937233408	1937233408	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	14851	14851	✔
AASNodeAbsentTimer_mS_M_u32	1937233408	1937233408	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1937233408	1937233408	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1937233408	1937233408	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1937233408	1937233408	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1937233408	1937233408	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1937233408	1937233408	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	20572	20572	✔
BSINodeAbsentTimer_mS_M_u32	1937233408	1937233408	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1937233408	1937233408	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1937233408	1937233408	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1937233408	1937233408	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1937233408	1937233408	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1937233408	1937233408	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	61296	61296	✔
CONSANGLECPK_HwDeg_M_f32	-130.087006	-130.087006 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1937233408	1937233408	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1937233408	1937233408	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1937233408	1937233408	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1937233408	1937233408	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1937233408	1937233408	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1937233408	1937233408	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1937233408	1937233408	✔
ESPNTCEnableTimer_mS_M_u32	1937233408	1937233408	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	28929	28929	✔
ESPNodeAbsentTimer_mS_M_u32	1937233408	1937233408	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	117	117	✔
EffacDefaultDiagTimer_mS_M_u32[1]	777	777	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1937233408	1937233408	✔
ElecIntTimer_mS_M_u32[1]	95536	95536	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1937233408	1937233408	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1937233408	1937233408	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1937233408	1937233408	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1937233408	1937233408	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1937233408	1937233408	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1937233408	1937233408	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1937233408	1937233408	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1937233408	1937233408	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1937233408	1937233408	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1937233408	1937233408	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM388MsgTimer_mS_M_u32	1937233408	1937233408	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1937233408	1937233408	✔
IgnOnTimer_mS_M_u32	1164379392	1164379392	✔
IgnTimeOff_Sec_M_u32	906394273	906394273	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	60	60	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2327381248	2327381248	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	63	63	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	675259648	675259648	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	81	81	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	139871488	139871488	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	217	217	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2466047232	2466047232	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3076998400	3076998400	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	238	238	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1207575808	1207575808	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	74	74	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1112589568	1112589568	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	705815808	705815808	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	214	214	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	330827008	330827008	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	39	39	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3737036032	3737036032	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	70	70	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2891269376	2891269376	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3819181312	3819181312	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	297.116302	297.116302	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	647.667175	647.667175	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	472.694702	472.694702	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	61296	61296	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	906394273	906394273	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-130.087006	-130.087006 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	164.724899	164.724899	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.22 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	217388800
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	41589
AASNodeAbsentTimer_mS_M_u32	953272064
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	14116
ANGLEVOLANTSigValidCount_Cnt_M_u16	60256
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	36422
AngleVolantMsgTimer_mS_M_u32	217388800
AngleVolantValidCount_Cnt_M_u16	63392
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2761459456
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	752944896
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	751712000
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2753558272
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	48839
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	877180672
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	4890
CAVNodeAbsentTimer_mS_M_u32	554624768
CDD_SrlComVehSpd_Kph_G_f32	635.50293
CMM388NTCEnableTimer_mS_M_u32	2273584896
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1757210368
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	39382

Name	Input Value
CMMNodeAbsentTimer_mS_M_u32	1559361280
CONSANGLECPKSigInvalidCount_Cnt_M_u16	37222
CONSANGLECPKSigValidCount_Cnt_M_u16	54835
CONSANGLECPK_Cnt_M_u16	3978
CONSANGLECPK_HwDeg_M_f32	-43.1327019
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	3978
CPKVehicleSpeedMsgTimer_mS_M_u32	3165656832
CPKVehicleSpeedValidCount_Cnt_M_u16	61494
CityParkInputConsistentCount_Cnt_M_u16	2836
CityParkInputInvalidCount_Cnt_M_u16	26766
CityParkInputMsgTimer_mS_M_u32	969389056
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	692438784
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	41961
ComputerRazGCTSigInvalidTimer_mS_M_u32	2706466560
ComputerRazGCTSigValidCount_Cnt_M_u16	5757
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	41242
DMDFCTCPKSigValidCount_Cnt_M_u16	33630
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	29662
DMDRELAXECPKSigValidCount_Cnt_M_u16	8090
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	6711
DateInvalidTimer_mS_M_u32	752944896
DiagMuxOnAbsentTimer_mS_M_u32	2541606656
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2753558272
ESPNTCEnableTimer_mS_M_u32	1339475712
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	47742
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	963
EffacDefaultDiagTimer_mS_M_u32[1]	7852
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	1000
ElecIntTimer_mS_M_u32[1]	2001
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1155708672
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	9908
EtatMTSigValidCount_Cnt_M_u16	32140
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	31776
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	14445
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	60684
ISDAT4V2BSI552MsgTimer_mS_M_u32	2087057152
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	24503
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	44279
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	32140
ISDATBSI3F2MsgTimer_mS_M_u32	616814336
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	63070
ISDATBSI412MsgLenValidCount_Cnt_M_u16	28302
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	9908
ISDATBSI412MsgTimer_mS_M_u32	943396608
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	10314
ISDATBSI432MsgLenValidCount_Cnt_M_u16	63474
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	21951
ISDATDIRASentFltAcc_Cnt_M_u16	42883
ISDATDIRASentTimer_mS_M_u32	3165656832
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	9552
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	63392
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	43069
ISDYN2CMMMsgTimer_mS_M_u32	120112896
ISDYNAASChkSumInvalidCount_Cnt_M_u16	6959
ISDYNAASChkSumValidCount_Cnt_M_u16	43275
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	40131
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	45489
ISDYNAASMsgLenValidCount_Cnt_M_u16	21221
ISDYNAASMsgTimeValidCount_Cnt_M_u16	6959

Name	Input Value
ISDYNAASMsgTimer_mS_M_u32	3641714432
ISDYNABRChkSumInvalidCount_Cnt_M_u16	32462
ISDYNABRChkSumValidCount_Cnt_M_u16	22387
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	31954
ISDYNABRMsgCountValidCount_Cnt_M_u16	3822
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	49673
ISDYNABRMsgLenValidCount_Cnt_M_u16	19222
ISDYNABRMsgTimeValidCount_Cnt_M_u16	3978
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	581
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1047
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	32140
ISDYNCMM208MsgTimer_mS_M_u32	3309405952
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2175
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1153
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	1510
ISDYNCMM388MsgTimer_mS_M_u32	532784896
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	46764
ISDYNVOLChkSumValidCount_Cnt_M_u16	33785
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	54624
ISDYNVOLMsgCountValidCount_Cnt_M_u16	32804
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	25563
ISDYNVOLMsgLenValidCount_Cnt_M_u16	44807
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	39382
ISDYNVOLMsgTimer_mS_M_u32	1323132672
IgnOnTimer_mS_M_u32	1177921280
IgnTimeOff_Sec_M_u32	2982794852
ManVehSpd_Kph_M_f32	493.778198
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	120
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	222
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1473369856
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	175
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	886126336
PrevISDATBSI412MsgDLCError_Cnt_M_u08	186
PrevISDATBSI412MsgRxTime_MSec_M_u32	2238965504
PrevISDATBSI432MsgDLCError_Cnt_M_u08	101
PrevISDATBSI432MsgRxTime_MSec_M_u32	1568327424
PrevISDATDIRAMsgTxTime_MSec_M_u32	1647830784
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	0
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1598781184
PrevISDYNAASMsgDLCError_Cnt_M_u08	210
PrevISDYNAASMsgRxTime_MSec_M_u32	3433260800
PrevISDYNABRMsgDLCError_Cnt_M_u08	51
PrevISDYNABRMsgRxTime_MSec_M_u32	3360532224
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	52
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1892443904
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	81
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1204930304
PrevISDYNVOLMsgDLCError_Cnt_M_u08	217
PrevISDYNVOLMsgRxTime_MSec_M_u32	1658119936
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1115756288
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	252.736404
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	33783
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	28075
VVHTYPE1Count_Cnt_M_u08	9

Name	Input Value
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	47316
VitesseVehicleBVRampValidCount_Cnt_M_u16	32328
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	29569
VitesseVehicleBVSigValidCount_Cnt_M_u16	41853
VitesseVehicleBV_Kph_M_f32	38.824501
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	1510
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	32122
VitesseVehiculeRoues_Kph_M_f32	10.0602999
k_AASNTCEnableTimeout_mS_u16	7813
k_AASNodeAbsentDiag_Cnt_str.Threshold	3069
k_AASNodeAbsentDiag_Cnt_str.PStep	55341
k_AASNodeAbsentDiag_Cnt_str.NStep	28764
k_AASNodeAbsentTimeout_mS_u16	10319
k_AASNodeTimeout_mS_u16	64683
k_ABSNodeTimeout_mS_u16	25731
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	12089
k_ANGLEVOLANTSigValidThresh_Cnt_u16	42017
k_AngleVolantInvalidThresh_Cnt_u16	11948
k_AngleVolantValidThresh_Cnt_u16	26766
k_BSI552MsgTimeout_mS_u16	13253
k_BSINTCEnableTimeout_mS_u16	55906
k_BSINodeAbsentDiag_Cnt_str.Threshold	20652
k_BSINodeAbsentDiag_Cnt_str.PStep	36763
k_BSINodeAbsentDiag_Cnt_str.NStep	11968
k_BSINodeAbsentTimeout_mS_u16	31326
k_BSINodeTimeout_mS_u16	21951
k_BattOvHi_Volt_f32	30.5664997
k_BattOvLo_Volt_f32	21.5366993
k_BattUvHi_Volt_f32	18.9480991
k_BattUvLo_Volt_f32	16.0758991
k_CAVNTCEnableTimeout_mS_u16	48364
k_CAVNodeAbsentDiag_Cnt_str.Threshold	42259
k_CAVNodeAbsentDiag_Cnt_str.PStep	48504
k_CAVNodeAbsentDiag_Cnt_str.NStep	5894
k_CAVNodeAbsentTimeout_mS_u16	52320
k_CAVNodeTimeout_mS_u16	47858
k_CMM388MsgTimeout_mS_u16	29045
k_CMM388NTCEnableTimeout_mS_u16	45057
k_CMMNTCEnableTimeout_mS_u16	56783
k_CMMNodeAbsentDiag_Cnt_str.Threshold	31972
k_CMMNodeAbsentDiag_Cnt_str.PStep	15063
k_CMMNodeAbsentDiag_Cnt_str.NStep	18159
k_CMMNodeAbsentTimeout_mS_u16	59910
k_CONSANGLECPKMax_HwDeg_f32	533.893677
k_CONSANGLECPKMin_HwDeg_f32	-659.151184
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	21734
k_CONSANGLECPKSigValidThresh_Cnt_u16	3194
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	19801
k_CPKVehicleSpeedValidThresh_Cnt_u16	8629
k_CityParkInputInvalidThresh_Cnt_u16	24060
k_CityParkInputValidThresh_Cnt_u16	2836
k_ComputerRazGCTSigValidThresh_Cnt_u16	26437
k_CptTemporelSigValidThresh_Cnt_u16	58117
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	37129
k_DMDFCTCPKSigValidThresh_Cnt_u16	23062
k_DMDFCTCPKValidCount_Cnt_u16	61871
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	43069
k_DMDRELAXECPKSigValidThresh_Cnt_u16	44737
k_DMDRelaxeConsistentThresh_Cnt_u16	61807
k_DateValidThresh_Cnt_u16	60684
k_DefaultVehSpd_Kph_f32	42.6122017
k_DiagMuxOnAbsentTimeout_mS_u16	11112
k_EMNodeTimeout_mS_u16	50455
k_ESPNTCEnableTimeout_mS_u16	18086
k_ESPNodeAbsentDiag_Cnt_str.Threshold	64871
k_ESPNodeAbsentDiag_Cnt_str.PStep	41110
k_ESPNodeAbsentDiag_Cnt_str.NStep	54601

Name	Input Value
k_ESPNodeAbsentTimeout_mS_u16	57326
k_EtatMTSigInvalidThresh_Cnt_u16	30393
k_EtatMTSigValidThresh_Cnt_u16	63902
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	13840
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	61769
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	14833
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	3880
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	48936
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	25298
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	22331
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	10659
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	63166
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	9950
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	42926
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	22969
k_ISDATDIRASentDiag_Cnt_str.Threshold	45070
k_ISDATDIRASentDiag_Cnt_str.PStep	63546
k_ISDATDIRASentDiag_Cnt_str.NStep	58968
k_ISDATDIRASentTimeout_mS_u16	56922
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	3938
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	36422
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	2562
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	52686
k_ISDYNAASChkSumValidThresh_Cnt_u16	58995
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	19410
k_ISDYNAASMsgCountValidThresh_Cnt_u16	7662
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	44610
k_ISDYNAASMsgLenValidThresh_Cnt_u16	18463
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	28681
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	15951
k_ISDYNABRChkSumValidThresh_Cnt_u16	36828
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	36295
k_ISDYNABRMsgCountValidThresh_Cnt_u16	1603
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	10454
k_ISDYNABRMsgLenValidThresh_Cnt_u16	35198
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	47118
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	61291
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	60283
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	62966
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	1572
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	64096
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	26790
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	47053
k_ISDYNVOLChkSumValidThresh_Cnt_u16	46397
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	45391
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	62951
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	29504
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	23320
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	7146
k_IgnOnTimeout_mS_u16	56153
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	172.456406
k_PowerCutVehSpdLowThresh_Kph_f32	199.182999
k_PowerCutVehSpdLowTimeout_mS_u16	49089
k_VBattMaxAAS_Volt_f32	28.6923008
k_VBattMaxBSI_Volt_f32	18.0520992
k_VBattMaxCAV_Volt_f32	7.30770016
k_VBattMaxCMM388_Volt_f32	19.5121002
k_VBattMaxCMM_Volt_f32	1.68359995
k_VBattMaxESP_Volt_f32	4.84749985
k_VBattMinAAS_Volt_f32	26.2210007
k_VBattMinBSI_Volt_f32	4.84749985
k_VBattMinCAV_Volt_f32	0.0285999998
k_VBattMinCMM388_Volt_f32	26.3603001
k_VBattMinCMM_Volt_f32	14.0607004
k_VBattMinESP_Volt_f32	1.68359995
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	13748
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	19988
k_VitesseVehicleBVRampValidThresh_Cnt_u16	9312
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	37625
k_VitesseVehicleBVSigValidThresh_Cnt_u16	33289
k_VitesseVehicleBVSpeedPassThresh_kph_f32	156.771194
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	25114

Name	Input Value
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	45070
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	752944896
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	102
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	57788
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3652517888
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	81
target_SrlComInput_Per1_Batt_Volt_f32.value	5.90159988
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1271772928
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	130
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.847342432
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	102213376
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1087588096
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	252
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1386145536
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	56
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3816457984
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2607163136
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	82
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	576833280
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	128
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	544040704
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	58
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	104
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	196
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	201
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3140978432
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	45
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	47
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	160
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	225
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1863231232
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1128941312
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2929059584
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	32
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	52
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	169
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	217
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2765829888

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2743
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.566793978
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	432601
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	172.991806
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	43465

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3652517888	3652517888	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	3069	3069	✔
AASNodeAbsentTimer_mS_M_u32	3652517888	3652517888	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	36422	36422	✔
AngleVolantMsgTimer_mS_M_u32	3652517888	3652517888	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3652517888	3652517888	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3652517888	3652517888	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3652517888	3652517888	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3652517888	3652517888	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	20652	20652	✔
BSINodeAbsentTimer_mS_M_u32	3652517888	3652517888	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3652517888	3652517888	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3652517888	3652517888	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3652517888	3652517888	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3652517888	3652517888	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3652517888	3652517888	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	3978	3978	✔
CONSANGLECPK_HwDeg_M_f32	-43.1327019	-43.1327019 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	3978	3978	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3165656832	3165656832	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	61494	61494	✔
CityParkInputConsistentCount_Cnt_M_u16	2836	2836	✔
CityParkInputInvalidCount_Cnt_M_u16	26766	26766	✔
CityParkInputMsgTimer_mS_M_u32	3652517888	3652517888	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3652517888	3652517888	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3652517888	3652517888	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3652517888	3652517888	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3652517888	3652517888	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3652517888	3652517888	✔
ESPNTCEnableTimer_mS_M_u32	3652517888	3652517888	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	64871	64871	✔
ESPNodeAbsentTimer_mS_M_u32	3652517888	3652517888	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	963	963	✔
EffacDefaultDiagTimer_mS_M_u32[1]	7852	7852	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3652517888	3652517888	✔
ElecIntTimer_mS_M_u32[1]	2001	2001	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3652517888	3652517888	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3652517888	3652517888	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3652517888	3652517888	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3652517888	3652517888	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3652517888	3652517888	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3652517888	3652517888	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3652517888	3652517888	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3652517888	3652517888	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3652517888	3652517888	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3652517888	3652517888	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3652517888	3652517888	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3652517888	3652517888	✔
IgnOnTimer_mS_M_u32	3652517888	3652517888	✔
IgnTimeOff_Sec_M_u32	2982794852	2982794852	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	220	220	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	102213376	102213376	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	107	107	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1087588096	1087588096	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	252	252	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1386145536	1386145536	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	56	56	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3816457984	3816457984	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1647830784	1647830784	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	82	82	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	576833280	576833280	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	128	128	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	544040704	544040704	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	84	84	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3140978432	3140978432	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	225	225	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1863231232	1863231232	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1128941312	1128941312	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	51	51	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2929059584	2929059584	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2765829888	2765829888	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	252.736404	252.736404	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	38.824501	38.824501	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	10.0602999	10.0602999	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	3978	3978	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2982794852	2982794852	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-43.1327019	-43.1327019 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.23 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1910210048
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	21337
AASNodeAbsentTimer_mS_M_u32	2097507840
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	28494
ANGLEVOLANTSigValidCount_Cnt_M_u16	48985
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	5094
AngleVolantMsgTimer_mS_M_u32	1910210048
AngleVolantValidCount_Cnt_M_u16	50778
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3299945984
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3990334976
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1590697472
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1876614656
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	9317
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1382063616
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	32234
CAVNodeAbsentTimer_mS_M_u32	2697858560
CDD_SrlComVehSpd_Kph_G_f32	652.139282
CMM388NTCEnableTimer_mS_M_u32	3530444288
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	29625856
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	25464
CMMNodeAbsentTimer_mS_M_u32	224714240
CONSANGLECPKSigInvalidCount_Cnt_M_u16	56198
CONSANGLECPKSigValidCount_Cnt_M_u16	47585
CONSANGLECPK_Cnt_M_u16	10716
CONSANGLECPK_HwDeg_M_f32	-301.660187
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	10716

Name	Input Value
CPKVehicleSpeedMsgTimer_mS_M_u32	246054400
CPKVehicleSpeedValidCount_Cnt_M_u16	31966
CityParkInputConsistentCount_Cnt_M_u16	23550
CityParkInputInvalidCount_Cnt_M_u16	64655
CityParkInputMsgTimer_mS_M_u32	102213376
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2074701312
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	7933
ComputerRazGCTSigInvalidTimer_mS_M_u32	1241943552
ComputerRazGCTSigValidCount_Cnt_M_u16	7619
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	33515
DMDFCTCPKSigValidCount_Cnt_M_u16	26846
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	8480
DMDRELAXECPKSigValidCount_Cnt_M_u16	35499
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	50451
DateInvalidTimer_mS_M_u32	3990334976
DiagMuxOnAbsentTimer_mS_M_u32	3846258176
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1876614656
ESPNTCEnableTimer_mS_M_u32	2348183040
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	7743
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	200
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2500
ElecIntTimer_mS_M_u32[1]	3501
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	143826432
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	1501
EtatMTSigValidCount_Cnt_M_u16	56852
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	33624
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	64307
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	25556
ISDAT4V2BSI552MsgTimer_mS_M_u32	2131287552
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	32340
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	4948
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	56852
ISDATBSI3F2MsgTimer_mS_M_u32	3580837376
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	26463
ISDATBSI412MsgLenValidCount_Cnt_M_u16	15246
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	1501
ISDATBSI412MsgTimer_mS_M_u32	2282323456
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	34844
ISDATBSI432MsgLenValidCount_Cnt_M_u16	13795
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	35323
ISDATDIRASentFltAcc_Cnt_M_u16	42159
ISDATDIRASentTimer_mS_M_u32	246054400
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	32906
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	50778
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	47490
ISDYN2CMMMsgTimer_mS_M_u32	771780096
ISDYNAASChkSumInvalidCount_Cnt_M_u16	20779
ISDYNAASChkSumValidCount_Cnt_M_u16	37975
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	8945
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	48677
ISDYNAASMsgLenValidCount_Cnt_M_u16	10057
ISDYNAASMsgTimeValidCount_Cnt_M_u16	20779
ISDYNAASMsgTimer_mS_M_u32	231362048
ISDYNABRChkSumInvalidCount_Cnt_M_u16	23501
ISDYNABRChkSumValidCount_Cnt_M_u16	56993
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	30786
ISDYNABRMsgCountValidCount_Cnt_M_u16	44718
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	38301

Name	Input Value
ISDYNABRMsgLenValidCount_Cnt_M_u16	42808
ISDYNABRMsgTimeValidCount_Cnt_M_u16	10716
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	582
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1049
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	56852
ISDYNCMM208MsgTimer_mS_M_u32	1186344448
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2179
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1155
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	13192
ISDYNCMM388MsgTimer_mS_M_u32	3753233920
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	948
ISDYNVOLChkSumValidCount_Cnt_M_u16	18575
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	32281
ISDYNVOLMsgCountValidCount_Cnt_M_u16	2700
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	54824
ISDYNVOLMsgLenValidCount_Cnt_M_u16	8548
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	25464
ISDYNVOLMsgTimer_mS_M_u32	1902284288
IgnOnTimer_mS_M_u32	1012518400
IgnTimeOff_Sec_M_u32	2986289401
ManVehSpd_Kph_M_f32	417.768707
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	122
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	125
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4098178560
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	155
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	315039232
PrevISDATBSI412MsgDLCError_Cnt_M_u08	30
PrevISDATBSI412MsgRxTime_MSec_M_u32	1201606144
PrevISDATBSI432MsgDLCError_Cnt_M_u08	2
PrevISDATBSI432MsgRxTime_MSec_M_u32	4077547008
PrevISDATDIRAMsgTxTime_MSec_M_u32	3243445760
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	255
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1280859648
PrevISDYNAASMsgDLCError_Cnt_M_u08	242
PrevISDYNAASMsgRxTime_MSec_M_u32	2417004032
PrevISDYNABRMsgDLCError_Cnt_M_u08	60
PrevISDYNABRMsgRxTime_MSec_M_u32	370265600
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	90
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2274725376
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	102
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1342533120
PrevISDYNVOLMsgDLCError_Cnt_M_u08	32
PrevISDYNVOLMsgRxTime_MSec_M_u32	1937509888
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	20413952
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	123.695198
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57171
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	28407
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	62652

Name	Input Value
VitesseVehicleBVRampValidCount_Cnt_M_u16	61728
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	28215
VitesseVehicleBVSigValidCount_Cnt_M_u16	19202
VitesseVehicleBV_Kph_M_f32	239.846207
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	13192
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	39307
VitesseVehiculeRoues_Kph_M_f32	632.516174
k_AASNTCEnableTimeout_mS_u16	43243
k_AASNodeAbsentDiag_Cnt_str.Threshold	32918
k_AASNodeAbsentDiag_Cnt_str.PStep	8990
k_AASNodeAbsentDiag_Cnt_str.NStep	41194
k_AASNodeAbsentTimeout_mS_u16	45133
k_AASNodeTimeout_mS_u16	49655
k_ABSNodeTimeout_mS_u16	7344
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	61263
k_ANGLEVOLANTSigValidThresh_Cnt_u16	44374
k_AngleVolantInvalidThresh_Cnt_u16	63925
k_AngleVolantValidThresh_Cnt_u16	64655
k_BSI552MsgTimeout_mS_u16	25258
k_BSINTCEnableTimeout_mS_u16	53716
k_BSINodeAbsentDiag_Cnt_str.Threshold	20692
k_BSINodeAbsentDiag_Cnt_str.PStep	36746
k_BSINodeAbsentDiag_Cnt_str.NStep	11991
k_BSINodeAbsentTimeout_mS_u16	44958
k_BSINodeTimeout_mS_u16	35323
k_BattOvHi_Volt_f32	27.7607002
k_BattOvLo_Volt_f32	23.5879993
k_BattUvHi_Volt_f32	28.9097996
k_BattUvLo_Volt_f32	4.61390018
k_CAVNTCEnableTimeout_mS_u16	63349
k_CAVNodeAbsentDiag_Cnt_str.Threshold	3979
k_CAVNodeAbsentDiag_Cnt_str.PStep	5046
k_CAVNodeAbsentDiag_Cnt_str.NStep	41378
k_CAVNodeAbsentTimeout_mS_u16	59928
k_CAVNodeTimeout_mS_u16	36578
k_CMM388MsgTimeout_mS_u16	58969
k_CMM388NTCEnableTimeout_mS_u16	23221
k_CMMNTCEnableTimeout_mS_u16	25612
k_CMMNodeAbsentDiag_Cnt_str.Threshold	42562
k_CMMNodeAbsentDiag_Cnt_str.PStep	36993
k_CMMNodeAbsentDiag_Cnt_str.NStep	59281
k_CMMNodeAbsentTimeout_mS_u16	33767
k_CONSANGLECPKMax_HwDeg_f32	78.4740982
k_CONSANGLECPKMin_HwDeg_f32	-302.118591
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	18056
k_CONSANGLECPKSigValidThresh_Cnt_u16	60555
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	2029
k_CPKVehicleSpeedValidThresh_Cnt_u16	346
k_CityParkInputInvalidThresh_Cnt_u16	63043
k_CityParkInputValidThresh_Cnt_u16	23550
k_ComputerRazGCTSigValidThresh_Cnt_u16	8106
k_CptTemporelSigValidThresh_Cnt_u16	10538
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	10397
k_DMDFCTCPKSigValidThresh_Cnt_u16	31288
k_DMDFCTCPKValidCount_Cnt_u16	11181
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	47490
k_DMDRELAXECPKSigValidThresh_Cnt_u16	12981
k_DMDRelaxeConsistentThresh_Cnt_u16	41643
k_DateValidThresh_Cnt_u16	25556
k_DefaultVehSpd_Kph_f32	191.393005
k_DiagMuxOnAbsentTimeout_mS_u16	52802
k_EMNodeTimeout_mS_u16	17523
k_ESPNTCEnableTimeout_mS_u16	4934
k_ESPNodeAbsentDiag_Cnt_str.Threshold	43160
k_ESPNodeAbsentDiag_Cnt_str.PStep	9249
k_ESPNodeAbsentDiag_Cnt_str.NStep	14947
k_ESPNodeAbsentTimeout_mS_u16	16943
k_EtatMTSigInvalidThresh_Cnt_u16	57356
k_EtatMTSigValidThresh_Cnt_u16	25632
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	59848
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	5343
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	33639
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	29697

Name	Input Value
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	57537
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	61955
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	65353
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	42192
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	60608
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	13280
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	28208
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	47693
k_ISDATDIRASentDiag_Cnt_str.Threshold	17178
k_ISDATDIRASentDiag_Cnt_str.PStep	37872
k_ISDATDIRASentDiag_Cnt_str.NStep	24622
k_ISDATDIRASentTimeout_mS_u16	27945
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	32082
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	5094
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	14642
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	28365
k_ISDYNAASChkSumValidThresh_Cnt_u16	12705
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	2882
k_ISDYNAASMsgCountValidThresh_Cnt_u16	33198
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	40305
k_ISDYNAASMsgLenValidThresh_Cnt_u16	44955
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	59806
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	47307
k_ISDYNABRChkSumValidThresh_Cnt_u16	28902
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	46949
k_ISDYNABRMsgCountValidThresh_Cnt_u16	47792
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46712
k_ISDYNABRMsgLenValidThresh_Cnt_u16	45375
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	37199
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	27895
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	15368
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	49686
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	590
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	37465
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	23623
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	40722
k_ISDYNVOLChkSumValidThresh_Cnt_u16	58241
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	48588
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	54085
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	20537
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	30064
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	53050
k_IgnOnTimeout_mS_u16	25710
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	66.3602982
k_PowerCutVehSpdLowThresh_Kph_f32	90.180603
k_PowerCutVehSpdLowTimeout_mS_u16	46391
k_VBattMaxAAS_Volt_f32	4.83150005
k_VBattMaxBSI_Volt_f32	28.0510998
k_VBattMaxCAV_Volt_f32	2.1796999
k_VBattMaxCMM388_Volt_f32	18.7404995
k_VBattMaxCMM_Volt_f32	10.7054005
k_VBattMaxESP_Volt_f32	25.1578999
k_VBattMinAAS_Volt_f32	5.6388998
k_VBattMinBSI_Volt_f32	25.1578999
k_VBattMinCAV_Volt_f32	11.2229996
k_VBattMinCMM388_Volt_f32	30.7768002
k_VBattMinCMM_Volt_f32	24.7176991
k_VBattMinESP_Volt_f32	10.7054005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	53852
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	34299
k_VitesseVehicleBVRampValidThresh_Cnt_u16	37145
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	7055
k_VitesseVehicleBVSigValidThresh_Cnt_u16	2847
k_VitesseVehicleBVSpeedPassThresh_kph_f32	604.518799
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	37098
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	62414
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3990334976
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	221
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	61696

Name	Input Value
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1249886976
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	102
target_SrlComInput_Per1_Batt_Volt_f32.value	9.07390022
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1607572992
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	127
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.738350451
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	78892544
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1258352128
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	171
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1277038080
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	269168128
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2663927296
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	5598720
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	250
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1018334720
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	93
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	123
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	163
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	244
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3168022016
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	34
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	90
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	100
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	208
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	226
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1708051968
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	171
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3751538176
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3560508928
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	42
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	45
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	60
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	72
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	215
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1789468160
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2293
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.965996265
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	607641
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	121.004097
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	13789

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1249886976	1249886976	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	32918	32918	✔
AASNodeAbsentTimer_mS_M_u32	1249886976	1249886976	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	5096	5096	✔
AngleVolantMsgTimer_mS_M_u32	1249886976	1249886976	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1249886976	1249886976	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1249886976	1249886976	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1249886976	1249886976	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1249886976	1249886976	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	20692	20692	✔
BSINodeAbsentTimer_mS_M_u32	1249886976	1249886976	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1249886976	1249886976	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1249886976	1249886976	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1249886976	1249886976	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1249886976	1249886976	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1249886976	1249886976	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	10716	10716	✔
CONSANGLECPK_HwDeg_M_f32	-301.660187	-301.660187 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	10716	10716	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	246054400	246054400	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	31966	31966	✔
CityParkInputConsistentCount_Cnt_M_u16	23550	23550	✔
CityParkInputInvalidCount_Cnt_M_u16	64655	64655	✔
CityParkInputMsgTimer_mS_M_u32	1249886976	1249886976	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1249886976	1249886976	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1249886976	1249886976	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1249886976	1249886976	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1249886976	1249886976	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1249886976	1249886976	✔
ESPNTCEnableTimer_mS_M_u32	1249886976	1249886976	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	43160	43160	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ESPNodeAbsentTimer_mS_M_u32	1249886976	1249886976	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1249886976	1249886976	✔
EffacDefaultDiagTimer_mS_M_u32[1]	200	200	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	1249886976	1249886976	✔
ElecIntTimer_mS_M_u32[1]	3501	3501	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1249886976	1249886976	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1249886976	1249886976	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1249886976	1249886976	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1249886976	1249886976	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1249886976	1249886976	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1249886976	1249886976	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1249886976	1249886976	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1249886976	1249886976	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1249886976	1249886976	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1249886976	1249886976	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1249886976	1249886976	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1249886976	1249886976	✔
IgnOnTimer_mS_M_u32	1249886976	1249886976	✔
IgnTimeOff_Sec_M_u32	2986289401	2986289401	✔
Msg348Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	15	15	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	29	29	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	78892544	78892544	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	73	73	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1258352128	1258352128	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	171	171	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1277038080	1277038080	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	77	77	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	269168128	269168128	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3243445760	3243445760	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	108	108	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	5598720	5598720	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	250	250	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1018334720	1018334720	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	46	46	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3168022016	3168022016	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	172	172	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1708051968	1708051968	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	171	171	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3751538176	3751538176	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3560508928	3560508928	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1789468160	1789468160	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	123.695198	123.695198	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	239.846207	239.846207	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	632.516174	632.516174	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	10716	10716	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2986289401	2986289401	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-301.660187	-301.660187 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	191.393005	191.393005	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.24 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1099188480
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	46856
AASNodeAbsentTimer_mS_M_u32	1942386944
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	54571
ANGLEVOLANTSigValidCount_Cnt_M_u16	40648
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	59745
AngleVolantMsgTimer_mS_M_u32	1099188480
AngleVolantValidCount_Cnt_M_u16	1672
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	4223875328
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	978303232
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2502322432
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4245039360
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	53734
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2624907520
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	49622
CAVNodeAbsentTimer_mS_M_u32	1928108288
CDD_SrlComVehSpd_Kph_G_f32	462.140991
CMM388NTCEnableTimer_mS_M_u32	2936789248
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2819266816
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	41965
CMMNodeAbsentTimer_mS_M_u32	3429378304
CONSANGLECPKSigInvalidCount_Cnt_M_u16	8068
CONSANGLECPKSigValidCount_Cnt_M_u16	32305
CONSANGLECPK_Cnt_M_u16	55872
CONSANGLECPK_HwDeg_M_f32	-322.679413
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	55872
CPKVehicleSpeedMsgTimer_mS_M_u32	1729579264
CPKVehicleSpeedValidCount_Cnt_M_u16	8738
CityParkInputConsistentCount_Cnt_M_u16	54684
CityParkInputInvalidCount_Cnt_M_u16	51432
CityParkInputMsgTimer_mS_M_u32	78892544
CityParkInputValidCount_Cnt_M_u16	4

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	131758336
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	58396
ComputerRazGCTSigInvalidTimer_mS_M_u32	4181924096
ComputerRazGCTSigValidCount_Cnt_M_u16	58445
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	42452
DMDFCTCPKSigValidCount_Cnt_M_u16	19898
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	34741
DMDRELAXECPKSigValidCount_Cnt_M_u16	1234
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	55005
DateInvalidTimer_mS_M_u32	978303232
DiagMuxOnAbsentTimer_mS_M_u32	2924677376
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4245039360
ESPNTCEnableTimer_mS_M_u32	1257470208
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	7511
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	89
EffacDefaultDiagTimer_mS_M_u32[1]	898
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	979
ElecIntTimer_mS_M_u32[1]	1086
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3252611328
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	57790
EtatMTSigValidCount_Cnt_M_u16	49879
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	61454
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	33339
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	46296
ISDAT4V2BSI552MsgTimer_mS_M_u32	125577472
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	3543
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	55449
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	49879
ISDATBSI3F2MsgTimer_mS_M_u32	365496576
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	19385
ISDATBSI412MsgLenValidCount_Cnt_M_u16	6378
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	57790
ISDATBSI412MsgTimer_mS_M_u32	922372352
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	50689
ISDATBSI432MsgLenValidCount_Cnt_M_u16	26219
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	8611
ISDATDIRASentFltAcc_Cnt_M_u16	41351
ISDATDIRASentTimer_mS_M_u32	1729579264
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	3638
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	1672
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	7695
ISDYN2CMMMsgTimer_mS_M_u32	215316736
ISDYNAASChkSumInvalidCount_Cnt_M_u16	34194
ISDYNAASChkSumValidCount_Cnt_M_u16	62928
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	3267
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	44325
ISDYNAASMsgLenValidCount_Cnt_M_u16	35707
ISDYNAASMsgTimeValidCount_Cnt_M_u16	34194
ISDYNAASMsgTimer_mS_M_u32	1828182272
ISDYNABRChkSumInvalidCount_Cnt_M_u16	50477
ISDYNABRChkSumValidCount_Cnt_M_u16	5746
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	11341
ISDYNABRMsgCountValidCount_Cnt_M_u16	49867
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	3391
ISDYNABRMsgLenValidCount_Cnt_M_u16	53804
ISDYNABRMsgTimeValidCount_Cnt_M_u16	55872
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	583
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1051
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	49879
ISDYNCMM208MsgTimer_mS_M_u32	3384031488

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2183
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1157
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	63230
ISDYNCMM388MsgTimer_mS_M_u32	87382272
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	57082
ISDYNVOLChkSumValidCount_Cnt_M_u16	2599
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	60490
ISDYNVOLMsgCountValidCount_Cnt_M_u16	41136
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	55708
ISDYNVOLMsgLenValidCount_Cnt_M_u16	29098
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	41965
ISDYNVOLMsgTimer_mS_M_u32	4079950080
IgnOnTimer_mS_M_u32	2135513344
IgnTimeOff_Sec_M_u32	1039334826
ManVehSpd_Kph_M_f32	518.5271
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	124
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	156
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2437351680
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	142
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	356608256
PrevISDATBSI412MsgDLCError_Cnt_M_u08	27
PrevISDATBSI412MsgRxTime_MSec_M_u32	41523456
PrevISDATBSI432MsgDLCError_Cnt_M_u08	196
PrevISDATBSI432MsgRxTime_MSec_M_u32	1706522880
PrevISDATDIRAMsgTxTime_MSec_M_u32	1700632832
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	81
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1032694016
PrevISDYNAASMsgDLCError_Cnt_M_u08	72
PrevISDYNAASMsgRxTime_MSec_M_u32	3475314944
PrevISDYNABRMsgDLCError_Cnt_M_u08	39
PrevISDYNABRMsgRxTime_MSec_M_u32	3525400832
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	110
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1016469760
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	24
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4207311104
PrevISDYNVOLMsgDLCError_Cnt_M_u08	249
PrevISDYNVOLMsgRxTime_MSec_M_u32	853711104
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	57690368
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	514.303894
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	33179
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	60529
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	9568
VitesseVehicleBVRampValidCount_Cnt_M_u16	18934
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	48240
VitesseVehicleBVSigValidCount_Cnt_M_u16	57293
VitesseVehicleBV_Kph_M_f32	429.925415
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	63230
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	24244

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	301.802887
k_AASNTCEnableTimeout_mS_u16	22803
k_AASNodeAbsentDiag_Cnt_str.Threshold	16855
k_AASNodeAbsentDiag_Cnt_str.PStep	42230
k_AASNodeAbsentDiag_Cnt_str.NStep	47243
k_AASNodeAbsentTimeout_mS_u16	54447
k_AASNodeTimeout_mS_u16	62321
k_ABSNodeTimeout_mS_u16	11397
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	7272
k_ANGLEVOLANTSigValidThresh_Cnt_u16	35858
k_AngleVolantInvalidThresh_Cnt_u16	58101
k_AngleVolantValidThresh_Cnt_u16	51432
k_BSI552MsgTimeout_mS_u16	16215
k_BSINTCEnableTimeout_mS_u16	51417
k_BSINodeAbsentDiag_Cnt_str.Threshold	20732
k_BSINodeAbsentDiag_Cnt_str.PStep	36729
k_BSINodeAbsentDiag_Cnt_str.NStep	12014
k_BSINodeAbsentTimeout_mS_u16	63033
k_BSINodeTimeout_mS_u16	8611
k_BattOvHi_Volt_f32	25.6865997
k_BattOvLo_Volt_f32	1.99150002
k_BattUvHi_Volt_f32	25.8575001
k_BattUvLo_Volt_f32	2.48309994
k_CAVNTCEnableTimeout_mS_u16	61494
k_CAVNodeAbsentDiag_Cnt_str.Threshold	26191
k_CAVNodeAbsentDiag_Cnt_str.PStep	53703
k_CAVNodeAbsentDiag_Cnt_str.NStep	47164
k_CAVNodeAbsentTimeout_mS_u16	46412
k_CAVNodeTimeout_mS_u16	30064
k_CMM388MsgTimeout_mS_u16	65032
k_CMM388NTCEnableTimeout_mS_u16	4340
k_CMMNTCEnableTimeout_mS_u16	15535
k_CMMNodeAbsentDiag_Cnt_str.Threshold	59315
k_CMMNodeAbsentDiag_Cnt_str.PStep	7343
k_CMMNodeAbsentDiag_Cnt_str.NStep	1399
k_CMMNodeAbsentTimeout_mS_u16	4000
k_CONSANGLECPKMax_HwDeg_f32	487.884094
k_CONSANGLECPKMin_HwDeg_f32	-533.155212
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	48638
k_CONSANGLECPKSigValidThresh_Cnt_u16	26036
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	31119
k_CPKVehicleSpeedValidThresh_Cnt_u16	10696
k_CityParkInputInvalidThresh_Cnt_u16	19915
k_CityParkInputValidThresh_Cnt_u16	54684
k_ComputerRazGCTSigValidThresh_Cnt_u16	469
k_CptTemporelSigValidThresh_Cnt_u16	28439
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	21567
k_DMDFCTCPKSigValidThresh_Cnt_u16	22828
k_DMDFCTCPKValidCount_Cnt_u16	56334
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	7695
k_DMDRELAXECPKSigValidThresh_Cnt_u16	3125
k_DMDRelaxeConsistentThresh_Cnt_u16	5203
k_DateValidThresh_Cnt_u16	46296
k_DefaultVehSpd_Kph_f32	101.409798
k_DiagMuxOnAbsentTimeout_mS_u16	1294
k_EMNodeTimeout_mS_u16	55485
k_ESPNTCEnableTimeout_mS_u16	29122
k_ESPNodeAbsentDiag_Cnt_str.Threshold	54546
k_ESPNodeAbsentDiag_Cnt_str.PStep	37676
k_ESPNodeAbsentDiag_Cnt_str.NStep	37728
k_ESPNodeAbsentTimeout_mS_u16	62664
k_EtatMTSigInvalidThresh_Cnt_u16	62576
k_EtatMTSigValidThresh_Cnt_u16	16885
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	65534
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	26744
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	17249
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	8400
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	25682
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	15309
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	21626
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	3492
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	10261
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	52276

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	59142
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	56302
k_ISDATDIRASentDiag_Cnt_str.Threshold	52771
k_ISDATDIRASentDiag_Cnt_str.PStep	49050
k_ISDATDIRASentDiag_Cnt_str.NStep	63254
k_ISDATDIRASentTimeout_mS_u16	281
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	59103
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	59745
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	45054
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	35885
k_ISDYNAASChkSumValidThresh_Cnt_u16	7538
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	29517
k_ISDYNAASMsgCountValidThresh_Cnt_u16	18891
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	36929
k_ISDYNAASMsgLenValidThresh_Cnt_u16	47749
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	63290
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	56245
k_ISDYNABRChkSumValidThresh_Cnt_u16	44322
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	6374
k_ISDYNABRMsgCountValidThresh_Cnt_u16	51395
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	43757
k_ISDYNABRMsgLenValidThresh_Cnt_u16	25687
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	32998
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	26799
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	45502
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	12052
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	7211
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	9672
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	35264
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	12448
k_ISDYNVOLChkSumValidThresh_Cnt_u16	44305
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	45744
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	51334
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	29354
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	27843
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	35494
k_IgnOnTimeout_mS_u16	20620
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	195.007904
k_PowerCutVehSpdLowThresh_Kph_f32	67.5469971
k_PowerCutVehSpdLowTimeout_mS_u16	25647
k_VBattMaxAAS_Volt_f32	22.3195992
k_VBattMaxBSI_Volt_f32	11.7644997
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	21.4883003
k_VBattMaxCMM_Volt_f32	32
k_VBattMaxESP_Volt_f32	15.9645004
k_VBattMinAAS_Volt_f32	6.71680021
k_VBattMinBSI_Volt_f32	15.9645004
k_VBattMinCAV_Volt_f32	10.9440002
k_VBattMinCMM388_Volt_f32	19.6361008
k_VBattMinCMM_Volt_f32	1.6875
k_VBattMinESP_Volt_f32	32
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	36801
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	32419
k_VitesseVehicleBVRampValidThresh_Cnt_u16	45898
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	37159
k_VitesseVehicleBVSigValidThresh_Cnt_u16	35897
k_VitesseVehicleBVSpeedPassThresh_kph_f32	462.069
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	35030
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	31212
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	978303232
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	54
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	48033
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2330688000
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSe	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	24
target_SrlComInput_Per1_Batt_Volt_f32.value	0.601899981
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2015488256
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	207
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.938826025
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	238770432
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	231
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1473509632
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2969344256
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	147
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	28653824
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	838719744
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	701921536
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	1
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3510573312
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	83
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	155
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	189
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	190
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	238
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1599748352
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	35
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	37
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	62
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	85
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	92
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	163
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	187
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	203
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	384456960
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3322083584
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1152096512
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	137
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	164
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	206
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	362506496
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1389
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.697354555
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	175261
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	118.326599
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	9725

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2330688000	2330688000	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	16855	16855	✔
AASNodeAbsentTimer_mS_M_u32	2330688000	2330688000	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2330688000	2330688000	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2330688000	2330688000	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2330688000	2330688000	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2330688000	2330688000	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2330688000	2330688000	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	20732	20732	✔
BSINodeAbsentTimer_mS_M_u32	2330688000	2330688000	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2330688000	2330688000	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2330688000	2330688000	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2330688000	2330688000	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2330688000	2330688000	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2330688000	2330688000	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	55872	55872	✔
CONSANGLECPK_HwDeg_M_f32	-322.679413	-322.679413 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2330688000	2330688000	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2330688000	2330688000	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2330688000	2330688000	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2330688000	2330688000	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2330688000	2330688000	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2330688000	2330688000	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2330688000	2330688000	✔
ESPNTCEnableTimer_mS_M_u32	2330688000	2330688000	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	54546	54546	✔
ESPNodeAbsentTimer_mS_M_u32	2330688000	2330688000	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	89	89	✔
EffacDefaultDiagTimer_mS_M_u32[1]	898	898	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2330688000	2330688000	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	1086	1086	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2330688000	2330688000	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2330688000	2330688000	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2330688000	2330688000	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2330688000	2330688000	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2330688000	2330688000	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2330688000	2330688000	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2330688000	2330688000	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2330688000	2330688000	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2330688000	2330688000	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2330688000	2330688000	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2330688000	2330688000	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2330688000	2330688000	✔
IgnOnTimer_mS_M_u32	2135513344	2135513344	✔
IgnTimeOff_Sec_M_u32	1039334826	1039334826	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	238	238	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	238770432	238770432	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	231	231	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1473509632	1473509632	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	123	123	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2969344256	2969344256	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	147	147	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	28653824	28653824	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1700632832	1700632832	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	238	238	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	701921536	701921536	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	1	1	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3510573312	3510573312	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	83	83	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1599748352	1599748352	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	108	108	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	384456960	384456960	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	235	235	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3322083584	3322083584	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	196	196	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1152096512	1152096512	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	362506496	362506496	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	514.303894	514.303894	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	429.925415	429.925415	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	301.802887	301.802887	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	55872	55872	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1039334826	1039334826	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-322.679413	-322.679413 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.25 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1170988288
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	23736
AASNodeAbsentTimer_mS_M_u32	733809920
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	11682
ANGLEVOLANTSigValidCount_Cnt_M_u16	3975
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	6881
AngleVolantMsgTimer_mS_M_u32	1170988288
AngleVolantValidCount_Cnt_M_u16	50713
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1857408256
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2703904000
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1175977216
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1340325120
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	38093
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2649652480
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	4592
CAVNodeAbsentTimer_mS_M_u32	2966236416
CDD_SrlComVehSpd_Kph_G_f32	175.719101
CMM388NTCEnableTimer_mS_M_u32	984640768
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3746245888
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	22066
CMMNodeAbsentTimer_mS_M_u32	2380643584
CONSANGLECPKSigInvalidCount_Cnt_M_u16	44983
CONSANGLECPKSigValidCount_Cnt_M_u16	48044
CONSANGLECPK_Cnt_M_u16	35947
CONSANGLECPK_HwDeg_M_f32	505.9487
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	35947
CPKVehicleSpeedMsgTimer_mS_M_u32	424598784
CPKVehicleSpeedValidCount_Cnt_M_u16	45172
CityParkInputConsistentCount_Cnt_M_u16	35693

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	6798
CityParkInputMsgTimer_mS_M_u32	73724416
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1175522560
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	57356
ComputerRazGCTSigInvalidTimer_mS_M_u32	3123424512
ComputerRazGCTSigValidCount_Cnt_M_u16	33134
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	49466
DMDFCTCPKSigValidCount_Cnt_M_u16	30694
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	52044
DMDRELAXECPKSigValidCount_Cnt_M_u16	30897
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	33504
DateInvalidTimer_mS_M_u32	2703904000
DiagMuxOnAbsentTimer_mS_M_u32	2402721024
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1340325120
ESPNTCEnableTimer_mS_M_u32	1358564608
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	38819
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	101
EffacDefaultDiagTimer_mS_M_u32[1]	202
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	657
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2490924288
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	47382
EtatMTSigValidCount_Cnt_M_u16	51511
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	52065
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	8918
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	30820
ISDAT4V2BSI552MsgTimer_mS_M_u32	2134490368
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	58182
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	24975
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	51511
ISDATBSI3F2MsgTimer_mS_M_u32	730635520
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	39819
ISDATBSI412MsgLenValidCount_Cnt_M_u16	57156
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	47382
ISDATBSI412MsgTimer_mS_M_u32	3491880192
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	24198
ISDATBSI432MsgLenValidCount_Cnt_M_u16	63223
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	29133
ISDATDIRASentFltAcc_Cnt_M_u16	10481
ISDATDIRASentTimer_mS_M_u32	424598784
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	56641
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	50713
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	15333
ISDYN2CMMMsgTimer_mS_M_u32	1232866560
ISDYNAASChkSumInvalidCount_Cnt_M_u16	54882
ISDYNAASChkSumValidCount_Cnt_M_u16	28903
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	11972
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	13807
ISDYNAASMsgLenValidCount_Cnt_M_u16	9740
ISDYNAASMsgTimeValidCount_Cnt_M_u16	54882
ISDYNAASMsgTimer_mS_M_u32	308047104
ISDYNABRChkSumInvalidCount_Cnt_M_u16	54330
ISDYNABRChkSumValidCount_Cnt_M_u16	8775
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	1933
ISDYNABRMsgCountValidCount_Cnt_M_u16	48210
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	22498
ISDYNABRMsgLenValidCount_Cnt_M_u16	48663
ISDYNABRMsgTimeValidCount_Cnt_M_u16	35947
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	587

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1059
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	51511
ISDYNCMM208MsgTimer_mS_M_u32	3891711232
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2199
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1165
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	47983
ISDYNCMM388MsgTimer_mS_M_u32	4124175616
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	9229
ISDYNVOLChkSumValidCount_Cnt_M_u16	58498
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	60560
ISDYNVOLMsgCountValidCount_Cnt_M_u16	38844
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	47480
ISDYNVOLMsgLenValidCount_Cnt_M_u16	60620
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	22066
ISDYNVOLMsgTimer_mS_M_u32	2379721984
IgnOnTimer_mS_M_u32	3592809728
IgnTimeOff_Sec_M_u32	2528944730
ManVehSpd_Kph_M_f32	638.301697
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	132
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	65
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2657787136
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	104
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1050868992
PrevISDATBSI412MsgDLCError_Cnt_M_u08	57
PrevISDATBSI412MsgRxTime_MSec_M_u32	745155840
PrevISDATBSI432MsgDLCError_Cnt_M_u08	235
PrevISDATBSI432MsgRxTime_MSec_M_u32	150867200
PrevISDATDIRAMsgTxTime_MSec_M_u32	3062770944
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	84
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2462268672
PrevISDYNAASMsgDLCError_Cnt_M_u08	70
PrevISDYNAASMsgRxTime_MSec_M_u32	112045312
PrevISDYNABRMsgDLCError_Cnt_M_u08	148
PrevISDYNABRMsgRxTime_MSec_M_u32	2357062912
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	142
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4151225600
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	248
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3804040448
PrevISDYNVOLMsgDLCError_Cnt_M_u08	150
PrevISDYNVOLMsgRxTime_MSec_M_u32	1302539520
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1635245312
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	565.426025
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	20293
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	46050
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	45210
VitesseVehicleBVRampValidCount_Cnt_M_u16	56055
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	60023
VitesseVehicleBVSigValidCount_Cnt_M_u16	12828

Name	Input Value
VitesseVehicleBV_Kph_M_f32	530.04071
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	47983
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	8940
VitesseVehiculeRoues_Kph_M_f32	176.681793
k_AASNTCEnableTimeout_mS_u16	40238
k_AASNodeAbsentDiag_Cnt_str.Threshold	55115
k_AASNodeAbsentDiag_Cnt_str.PStep	34049
k_AASNodeAbsentDiag_Cnt_str.NStep	57557
k_AASNodeAbsentTimeout_mS_u16	12400
k_AASNodeTimeout_mS_u16	60130
k_ABSNodeTimeout_mS_u16	44859
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	58653
k_ANGLEVOLANTSigValidThresh_Cnt_u16	4302
k_AngleVolantInvalidThresh_Cnt_u16	32417
k_AngleVolantValidThresh_Cnt_u16	6798
k_BSI552MsgTimeout_mS_u16	9855
k_BSINTCEnableTimeout_mS_u16	50398
k_BSINodeAbsentDiag_Cnt_str.Threshold	20892
k_BSINodeAbsentDiag_Cnt_str.PStep	36661
k_BSINodeAbsentDiag_Cnt_str.NStep	12106
k_BSINodeAbsentTimeout_mS_u16	43833
k_BSINodeTimeout_mS_u16	29133
k_BattOvHi_Volt_f32	21.9358006
k_BattOvLo_Volt_f32	19.4948997
k_BattUvHi_Volt_f32	5.56409979
k_BattUvLo_Volt_f32	8.28209972
k_CAVNTCEnableTimeout_mS_u16	59964
k_CAVNodeAbsentDiag_Cnt_str.Threshold	5252
k_CAVNodeAbsentDiag_Cnt_str.PStep	43880
k_CAVNodeAbsentDiag_Cnt_str.NStep	56650
k_CAVNodeAbsentTimeout_mS_u16	64070
k_CAVNodeTimeout_mS_u16	40803
k_CMM388MsgTimeout_mS_u16	54200
k_CMM388NTCEnableTimeout_mS_u16	36964
k_CMMNTCEnableTimeout_mS_u16	13726
k_CMMNodeAbsentDiag_Cnt_str.Threshold	17714
k_CMMNodeAbsentDiag_Cnt_str.PStep	15849
k_CMMNodeAbsentDiag_Cnt_str.NStep	54005
k_CMMNodeAbsentTimeout_mS_u16	56728
k_CONSANGLECPKMax_HwDeg_f32	770.457703
k_CONSANGLECPKMin_HwDeg_f32	-719.555786
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	45679
k_CONSANGLECPKSigValidThresh_Cnt_u16	23020
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	47712
k_CPKVehicleSpeedValidThresh_Cnt_u16	36426
k_CityParkInputInvalidThresh_Cnt_u16	28216
k_CityParkInputValidThresh_Cnt_u16	35693
k_ComputerRazGCTSigValidThresh_Cnt_u16	30372
k_CptTemporelSigValidThresh_Cnt_u16	24429
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	52962
k_DMDFCTCPKSigValidThresh_Cnt_u16	29975
k_DMDFCTCPKValidCount_Cnt_u16	19317
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	15333
k_DMDRELAXECPKSigValidThresh_Cnt_u16	11473
k_DMDRelaxeConsistentThresh_Cnt_u16	7759
k_DateValidThresh_Cnt_u16	30820
k_DefaultVehSpd_Kph_f32	115.134697
k_DiagMuxOnAbsentTimeout_mS_u16	30617
k_EMNodeTimeout_mS_u16	6848
k_ESPNTCEnableTimeout_mS_u16	31644
k_ESPNodeAbsentDiag_Cnt_str.Threshold	43475
k_ESPNodeAbsentDiag_Cnt_str.PStep	14620
k_ESPNodeAbsentDiag_Cnt_str.NStep	52072
k_ESPNodeAbsentTimeout_mS_u16	57152
k_EtatMTSigInvalidThresh_Cnt_u16	47213
k_EtatMTSigValidThresh_Cnt_u16	54970
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	62335
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	55551
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	54978
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	46095
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	26392
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	53727
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	17103

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	45056
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	42714
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	23199
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	11767
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	41061
k_ISDATDIRASentDiag_Cnt_str.Threshold	6306
k_ISDATDIRASentDiag_Cnt_str.PStep	50485
k_ISDATDIRASentDiag_Cnt_str.NStep	51790
k_ISDATDIRASentTimeout_mS_u16	35302
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	26278
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	6881
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	60568
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	52026
k_ISDYNAASChkSumValidThresh_Cnt_u16	22855
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	32397
k_ISDYNAASMsgCountValidThresh_Cnt_u16	29522
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	21902
k_ISDYNAASMsgLenValidThresh_Cnt_u16	10294
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	30838
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	35640
k_ISDYNABRChkSumValidThresh_Cnt_u16	58861
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	3021
k_ISDYNABRMsgCountValidThresh_Cnt_u16	51186
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	36146
k_ISDYNABRMsgLenValidThresh_Cnt_u16	3747
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	64261
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	44185
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	29472
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	47477
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	42146
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	50823
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	40678
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	14498
k_ISDYNVOLChkSumValidThresh_Cnt_u16	61339
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	43212
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	47771
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	21442
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	19683
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	32402
k_IgnOnTimeout_mS_u16	4686
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	202.584396
k_PowerCutVehSpdLowThresh_Kph_f32	150.248505
k_PowerCutVehSpdLowTimeout_mS_u16	57610
k_VBattMaxAAS_Volt_f32	18.2759991
k_VBattMaxBSI_Volt_f32	30.8484001
k_VBattMaxCAV_Volt_f32	24.5450001
k_VBattMaxCMM388_Volt_f32	1.08410001
k_VBattMaxCMM_Volt_f32	9.01099968
k_VBattMaxESP_Volt_f32	8.69769955
k_VBattMinAAS_Volt_f32	27.9101009
k_VBattMinBSI_Volt_f32	8.69769955
k_VBattMinCAV_Volt_f32	6.66769981
k_VBattMinCMM388_Volt_f32	27.2726002
k_VBattMinCMM_Volt_f32	2.62039995
k_VBattMinESP_Volt_f32	9.01099968
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	30248
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	25232
k_VitesseVehicleBVRampValidThresh_Cnt_u16	58256
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	39810
k_VitesseVehicleBVSigValidThresh_Cnt_u16	25370
k_VitesseVehicleBVSpeedPassThresh_kph_f32	459.601105
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	2288
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	59341
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2703904000
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	104
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	38453
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2512543232
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	248
target_SrlComInput_Per1_Batt_Volt_f32.value	17.8701992
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	799767808
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	140
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.344762444
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	147
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2964843776
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	201493760
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1407003904
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4031237376
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1229090048
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3335326976
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3504844032
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	159
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	175
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	196
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	245
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	561827072
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	68
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	111
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	192
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	27
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	538373376
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	165
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2564918528
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3191614720
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	12
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	83
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	107
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	124
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	212
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	213
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2065497344
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3715
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.429326057
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	808884
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	244.391296

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	62023		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	2512543232	2512543232	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	55115	55115	✔
AASNodeAbsentTimer_mS_M_u32	2512543232	2512543232	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	6883	6883	✔
AngleVolantMsgTimer_mS_M_u32	2512543232	2512543232	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2512543232	2512543232	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2512543232	2512543232	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2512543232	2512543232	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2512543232	2512543232	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	20892	20892	✔
BSINodeAbsentTimer_mS_M_u32	2512543232	2512543232	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2512543232	2512543232	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2512543232	2512543232	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2512543232	2512543232	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2512543232	2512543232	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2512543232	2512543232	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	35947	35947	✔
CONSANGLECPK_HwDeg_M_f32	505.9487	505.9487 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	35947	35947	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	424598784	424598784	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	45172	45172	✔
CityParkInputConsistentCount_Cnt_M_u16	35693	35693	✔
CityParkInputInvalidCount_Cnt_M_u16	6800	6800	✔
CityParkInputMsgTimer_mS_M_u32	2512543232	2512543232	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2512543232	2512543232	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2512543232	2512543232	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	1	1	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2512543232	2512543232	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2512543232	2512543232	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2512543232	2512543232	✔
ESPNTCEnableTimer_mS_M_u32	2512543232	2512543232	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	43475	43475	✔
ESPNodeAbsentTimer_mS_M_u32	2512543232	2512543232	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	101	101	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	202	202	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	65	65	✔
ElecIntTimer_mS_M_u32[1]	657	657	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2512543232	2512543232	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2512543232	2512543232	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2512543232	2512543232	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2512543232	2512543232	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2512543232	2512543232	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2512543232	2512543232	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2512543232	2512543232	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2512543232	2512543232	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2512543232	2512543232	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2512543232	2512543232	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2512543232	2512543232	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2512543232	2512543232	✔
IgnOnTimer_mS_M_u32	2512543232	2512543232	✔
IgnTimeOff_Sec_M_u32	2528944730	2528944730	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	147	147	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2964843776	2964843776	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	223	223	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	201493760	201493760	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	99	99	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1407003904	1407003904	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	137	137	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4031237376	4031237376	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3062770944	3062770944	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	84	84	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3335326976	3335326976	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3504844032	3504844032	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	167	167	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	561827072	561827072	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	27	27	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	538373376	538373376	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	165	165	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2564918528	2564918528	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	39	39	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3191614720	3191614720	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2065497344	2065497344	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	565.426025	565.426025	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	530.04071	530.04071	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	176.681793	176.681793	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	35947	35947	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2528944730	2528944730	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	505.9487	505.9487 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.26 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2179935232
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	36649
AASNodeAbsentTimer_mS_M_u32	1356569600
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	58986
ANGLEVOLANTSigValidCount_Cnt_M_u16	61308
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	14510
AngleVolantMsgTimer_mS_M_u32	2179935232
AngleVolantValidCount_Cnt_M_u16	24964
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1525767168
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	898882560
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1502268416
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	455576576
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	7401
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3423030272
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	63489
CAVNodeAbsentTimer_mS_M_u32	2854960128
CDD_SrlComVehSpd_Kph_G_f32	330.631012
CMM388NTCEnableTimer_mS_M_u32	2843835392
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2528197632
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	57083
CMMNodeAbsentTimer_mS_M_u32	3911289856
CONSANGLECPKSigInvalidCount_Cnt_M_u16	41771
CONSANGLECPKSigValidCount_Cnt_M_u16	28173
CONSANGLECPK_Cnt_M_u16	47056
CONSANGLECPK_HwDeg_M_f32	298.653595
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	47056
CPKVehicleSpeedMsgTimer_mS_M_u32	3546688512
CPKVehicleSpeedValidCount_Cnt_M_u16	53116
CityParkInputConsistentCount_Cnt_M_u16	24968

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	34088
CityParkInputMsgTimer_mS_M_u32	2964843776
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1373608960
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	21805
ComputerRazGCTSigInvalidTimer_mS_M_u32	672119808
ComputerRazGCTSigValidCount_Cnt_M_u16	50053
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	16676
DMDFCTCPKSigValidCount_Cnt_M_u16	60381
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	13676
DMDRELAXECPKSigValidCount_Cnt_M_u16	56318
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	3504
DateInvalidTimer_mS_M_u32	898882560
DiagMuxOnAbsentTimer_mS_M_u32	3232689152
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	455576576
ESPNTCEnableTimer_mS_M_u32	354720768
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	63849
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	305
EffacDefaultDiagTimer_mS_M_u32[1]	706
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	54
ElecIntTimer_mS_M_u32[1]	67
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2422819840
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	38734
EtatMTSigValidCount_Cnt_M_u16	1452
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	30765
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	24719
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	25187
ISDAT4V2BSI552MsgTimer_mS_M_u32	1696959488
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	12351
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	62501
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	1452
ISDATBSI3F2MsgTimer_mS_M_u32	3282889728
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	44143
ISDATBSI412MsgLenValidCount_Cnt_M_u16	57349
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	38734
ISDATBSI412MsgTimer_mS_M_u32	3136105472
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	5631
ISDATBSI432MsgLenValidCount_Cnt_M_u16	11117
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	35946
ISDATDIRASentFltAcc_Cnt_M_u16	63230
ISDATDIRASentTimer_mS_M_u32	3546688512
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	40270
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	24964
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	15651
ISDYN2CMMMsgTimer_mS_M_u32	3013516288
ISDYNAASChkSumInvalidCount_Cnt_M_u16	18987
ISDYNAASChkSumValidCount_Cnt_M_u16	43357
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	37763
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	18436
ISDYNAASMsgLenValidCount_Cnt_M_u16	1646
ISDYNAASMsgTimeValidCount_Cnt_M_u16	18987
ISDYNAASMsgTimer_mS_M_u32	3531439104
ISDYNABRChkSumInvalidCount_Cnt_M_u16	43554
ISDYNABRChkSumValidCount_Cnt_M_u16	3772
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	8874
ISDYNABRMsgCountValidCount_Cnt_M_u16	13084
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	5802
ISDYNABRMsgLenValidCount_Cnt_M_u16	53964
ISDYNABRMsgTimeValidCount_Cnt_M_u16	47056
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	588

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1061
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	1452
ISDYNCMM208MsgTimer_mS_M_u32	858676224
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2203
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1167
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	22914
ISDYNCMM388MsgTimer_mS_M_u32	3726441472
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	7721
ISDYNVOLChkSumValidCount_Cnt_M_u16	52107
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	38690
ISDYNVOLMsgCountValidCount_Cnt_M_u16	25691
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	10218
ISDYNVOLMsgLenValidCount_Cnt_M_u16	64684
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	57083
ISDYNVOLMsgTimer_mS_M_u32	1561050112
IgnOnTimer_mS_M_u32	2367749120
IgnTimeOff_Sec_M_u32	1841955793
ManVehSpd_Kph_M_f32	544.634888
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	134
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	123
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1662184448
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	18
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1542048768
PrevISDATBSI412MsgDLCError_Cnt_M_u08	55
PrevISDATBSI412MsgRxTime_MSec_M_u32	3948166144
PrevISDATBSI432MsgDLCError_Cnt_M_u08	248
PrevISDATBSI432MsgRxTime_MSec_M_u32	4246248448
PrevISDATDIRAMsgTxTime_MSec_M_u32	3706207232
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	211
PrevISDYN2CMMMsgRxTime_MSec_M_u32	814287872
PrevISDYNAASMsgDLCError_Cnt_M_u08	239
PrevISDYNAASMsgRxTime_MSec_M_u32	3398024192
PrevISDYNABRMsgDLCError_Cnt_M_u08	217
PrevISDYNABRMsgRxTime_MSec_M_u32	3390635008
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	13
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1011268608
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	216
PrevISDYNCMM388MsgRxTime_MSec_M_u32	735812608
PrevISDYNVOLMsgDLCError_Cnt_M_u08	130
PrevISDYNVOLMsgRxTime_MSec_M_u32	2879994880
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3739954176
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	233.190506
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	54274
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	13548
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	17411
VitesseVehicleBVRampValidCount_Cnt_M_u16	21421
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	17387
VitesseVehicleBVSigValidCount_Cnt_M_u16	7101

Name	Input Value
VitesseVehicleBV_Kph_M_f32	490.612396
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	22914
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	12748
VitesseVehiculeRoues_Kph_M_f32	431.578003
k_AASNTCEnableTimeout_mS_u16	20871
k_AASNodeAbsentDiag_Cnt_str.Threshold	56356
k_AASNodeAbsentDiag_Cnt_str.PStep	18010
k_AASNodeAbsentDiag_Cnt_str.NStep	50037
k_AASNodeAbsentTimeout_mS_u16	15999
k_AASNodeTimeout_mS_u16	36844
k_ABSNodeTimeout_mS_u16	47905
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	40506
k_ANGLEVOLANTSigValidThresh_Cnt_u16	63976
k_AngleVolantInvalidThresh_Cnt_u16	48239
k_AngleVolantValidThresh_Cnt_u16	34088
k_BSI552MsgTimeout_mS_u16	13075
k_BSINTCEnableTimeout_mS_u16	17143
k_BSINodeAbsentDiag_Cnt_str.Threshold	20932
k_BSINodeAbsentDiag_Cnt_str.PStep	36644
k_BSINodeAbsentDiag_Cnt_str.NStep	12129
k_BSINodeAbsentTimeout_mS_u16	59302
k_BSINodeTimeout_mS_u16	35946
k_BattOvHi_Volt_f32	31.3843994
k_BattOvLo_Volt_f32	31.0582008
k_BattUvHi_Volt_f32	13.7855997
k_BattUvLo_Volt_f32	29.8481007
k_CAVNTCEnableTimeout_mS_u16	19998
k_CAVNodeAbsentDiag_Cnt_str.Threshold	19953
k_CAVNodeAbsentDiag_Cnt_str.PStep	2269
k_CAVNodeAbsentDiag_Cnt_str.NStep	60943
k_CAVNodeAbsentTimeout_mS_u16	5887
k_CAVNodeTimeout_mS_u16	33831
k_CMM388MsgTimeout_mS_u16	10793
k_CMM388NTCEnableTimeout_mS_u16	42021
k_CMMNTCEnableTimeout_mS_u16	39223
k_CMMNodeAbsentDiag_Cnt_str.Threshold	23503
k_CMMNodeAbsentDiag_Cnt_str.PStep	31234
k_CMMNodeAbsentDiag_Cnt_str.NStep	14455
k_CMMNodeAbsentTimeout_mS_u16	45512
k_CONSANGLECPKMax_HwDeg_f32	572.601501
k_CONSANGLECPKMin_HwDeg_f32	-277.734009
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	29826
k_CONSANGLECPKSigValidThresh_Cnt_u16	36044
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	39282
k_CPKVehicleSpeedValidThresh_Cnt_u16	36914
k_CityParkInputInvalidThresh_Cnt_u16	21544
k_CityParkInputValidThresh_Cnt_u16	24968
k_ComputerRazGCTSigValidThresh_Cnt_u16	28197
k_CptTemporelSigValidThresh_Cnt_u16	62091
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	45482
k_DMDFCTCPKSigValidThresh_Cnt_u16	44492
k_DMDFCTCPKValidCount_Cnt_u16	39153
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	15651
k_DMDRELAXECPKSigValidThresh_Cnt_u16	14620
k_DMDRelaxeConsistentThresh_Cnt_u16	56482
k_DateValidThresh_Cnt_u16	25187
k_DefaultVehSpd_Kph_f32	28.4190998
k_DiagMuxOnAbsentTimeout_mS_u16	11846
k_EMNodeTimeout_mS_u16	50704
k_ESPNTCEnableTimeout_mS_u16	27389
k_ESPNodeAbsentDiag_Cnt_str.Threshold	46797
k_ESPNodeAbsentDiag_Cnt_str.PStep	10825
k_ESPNodeAbsentDiag_Cnt_str.NStep	16893
k_ESPNodeAbsentTimeout_mS_u16	19664
k_EtatMTSigInvalidThresh_Cnt_u16	35209
k_EtatMTSigValidThresh_Cnt_u16	32099
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	10773
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	38995
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	5001
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	8676
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	18314
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	22899
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	52516

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	25682
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	36099
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	7476
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	8682
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	37603
k_ISDATDIRASentDiag_Cnt_str.Threshold	57878
k_ISDATDIRASentDiag_Cnt_str.PStep	55285
k_ISDATDIRASentDiag_Cnt_str.NStep	57219
k_ISDATDIRASentTimeout_mS_u16	14622
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	33824
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	14510
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	2057
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	50466
k_ISDYNAASChkSumValidThresh_Cnt_u16	27068
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	48554
k_ISDYNAASMsgCountValidThresh_Cnt_u16	3612
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	30246
k_ISDYNAASMsgLenValidThresh_Cnt_u16	10224
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	25328
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	21672
k_ISDYNABRChkSumValidThresh_Cnt_u16	13130
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	47081
k_ISDYNABRMsgCountValidThresh_Cnt_u16	12859
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	14843
k_ISDYNABRMsgLenValidThresh_Cnt_u16	37993
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	42242
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	3078
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	47536
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	12339
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	33130
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	51836
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	22560
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	61738
k_ISDYNVOLChkSumValidThresh_Cnt_u16	51968
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	43502
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	38336
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	30538
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	10920
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	34777
k_IgnOnTimeout_mS_u16	5158
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	74.5699997
k_PowerCutVehSpdLowThresh_Kph_f32	15.5777998
k_PowerCutVehSpdLowTimeout_mS_u16	62963
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	20.9339008
k_VBattMaxCAV_Volt_f32	20.6693001
k_VBattMaxCMM388_Volt_f32	13.7726002
k_VBattMaxCMM_Volt_f32	21.5419998
k_VBattMaxESP_Volt_f32	20.9025993
k_VBattMinAAS_Volt_f32	5.8046999
k_VBattMinBSI_Volt_f32	20.9025993
k_VBattMinCAV_Volt_f32	20.5151997
k_VBattMinCMM388_Volt_f32	25.7961006
k_VBattMinCMM_Volt_f32	1.36510003
k_VBattMinESP_Volt_f32	21.5419998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	56730
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	55072
k_VitesseVehicleBVRampValidThresh_Cnt_u16	45602
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	42635
k_VitesseVehicleBVSigValidThresh_Cnt_u16	52865
k_VitesseVehicleBVSpeedPassThresh_kph_f32	82.1256027
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	4865
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	1323
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	898882560
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	187
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	34511
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2303699200
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	216
target_SrlComInput_Per1_Batt_Volt_f32.value	24.9922009
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1255164928
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	52
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.547956049
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	124
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3312122880
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2785745920
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	16464896
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2654690304
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1170963456
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	211
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3215694848
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3554393088
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	56
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	136
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	155
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	193
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	513563648
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	65
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	77
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	94
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	144
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	228
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3008232448
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	997071872
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4259200000
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	72
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	84
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	142
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	242994176
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3814
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0106989853
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	196186
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	251.399399

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	29436		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	2303699200	2303699200	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	56356	56356	✔
AASNodeAbsentTimer_mS_M_u32	2303699200	2303699200	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	14512	14512	✔
AngleVolantMsgTimer_mS_M_u32	2303699200	2303699200	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2303699200	2303699200	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2303699200	2303699200	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2303699200	2303699200	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2303699200	2303699200	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	20932	20932	✔
BSINodeAbsentTimer_mS_M_u32	2303699200	2303699200	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2303699200	2303699200	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2303699200	2303699200	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2303699200	2303699200	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2303699200	2303699200	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2303699200	2303699200	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	47056	47056	✔
CONSANGLECPK_HwDeg_M_f32	298.653595	298.653595 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	47056	47056	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3546688512	3546688512	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	53116	53116	✔
CityParkInputConsistentCount_Cnt_M_u16	24968	24968	✔
CityParkInputInvalidCount_Cnt_M_u16	34088	34088	✔
CityParkInputMsgTimer_mS_M_u32	2303699200	2303699200	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2303699200	2303699200	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2303699200	2303699200	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	1	1	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2303699200	2303699200	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2303699200	2303699200	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2303699200	2303699200	✔
ESPNTCEnableTimer_mS_M_u32	2303699200	2303699200	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	46797	46797	✔
ESPNodeAbsentTimer_mS_M_u32	2303699200	2303699200	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	305	305	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	706	706	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2303699200	2303699200	✔
ElecIntTimer_mS_M_u32[1]	67	67	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2303699200	2303699200	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2303699200	2303699200	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2303699200	2303699200	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2303699200	2303699200	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2303699200	2303699200	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2303699200	2303699200	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2303699200	2303699200	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2303699200	2303699200	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2303699200	2303699200	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2303699200	2303699200	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2303699200	2303699200	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2303699200	2303699200	✔
IgnOnTimer_mS_M_u32	2367749120	2367749120	✔
IgnTimeOff_Sec_M_u32	1841955793	1841955793	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	124	124	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3312122880	3312122880	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	106	106	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2785745920	2785745920	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	239	239	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	16464896	16464896	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	210	210	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2654690304	2654690304	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3706207232	3706207232	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	211	211	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3215694848	3215694848	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	129	129	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3554393088	3554393088	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	137	137	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	513563648	513563648	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	30	30	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3008232448	3008232448	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	84	84	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	997071872	997071872	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4259200000	4259200000	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	242994176	242994176	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	233.190506	233.190506	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	490.612396	490.612396	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	431.578003	431.578003	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	47056	47056	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1841955793	1841955793	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	298.653595	298.653595 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.27 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1098989312
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	9169
AASNodeAbsentTimer_mS_M_u32	1383853824
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	49168
ANGLEVOLANTSigValidCount_Cnt_M_u16	39066
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	31554
AngleVolantMsgTimer_mS_M_u32	1098989312
AngleVolantValidCount_Cnt_M_u16	33088
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3141185280
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3578998528
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	825122560
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1331175168
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	55443
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1807277824
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	20426
CAVNodeAbsentTimer_mS_M_u32	2366443264
CDD_SrlComVehSpd_Kph_G_f32	211.972107
CMM388NTCEnableTimer_mS_M_u32	3087683328
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1601900288
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	32668
CMMNodeAbsentTimer_mS_M_u32	1298800384
CONSANGLECPKSigInvalidCount_Cnt_M_u16	49354
CONSANGLECPKSigValidCount_Cnt_M_u16	37861
CONSANGLECPK_Cnt_M_u16	33436
CONSANGLECPK_HwDeg_M_f32	-475.919708
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	33436
CPKVehicleSpeedMsgTimer_mS_M_u32	3910942464
CPKVehicleSpeedValidCount_Cnt_M_u16	53312
CityParkInputConsistentCount_Cnt_M_u16	37172

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	45910
CityParkInputMsgTimer_mS_M_u32	3312122880
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1601171200
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	57797
ComputerRazGCTSigInvalidTimer_mS_M_u32	1163890432
ComputerRazGCTSigValidCount_Cnt_M_u16	40765
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	28514
DMDFCTCPKSigValidCount_Cnt_M_u16	756
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	23306
DMDRELAXECPKSigValidCount_Cnt_M_u16	23316
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	54587
DateInvalidTimer_mS_M_u32	3578998528
DiagMuxOnAbsentTimer_mS_M_u32	876740352
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1331175168
ESPNTCEnableTimer_mS_M_u32	1772154624
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	37906
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	999
EffacDefaultDiagTimer_mS_M_u32[1]	1001
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	103
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	647159552
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	45986
EtatMTSigValidCount_Cnt_M_u16	35912
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	51652
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	17503
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	14178
ISDAT4V2BSI552MsgTimer_mS_M_u32	3915259648
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	41553
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	39519
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	35912
ISDATBSI3F2MsgTimer_mS_M_u32	2739404544
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	16064
ISDATBSI412MsgLenValidCount_Cnt_M_u16	42942
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	45986
ISDATBSI412MsgTimer_mS_M_u32	243744512
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	60048
ISDATBSI432MsgLenValidCount_Cnt_M_u16	3590
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	30351
ISDATDIRASentFltAcc_Cnt_M_u16	34515
ISDATDIRASentTimer_mS_M_u32	3910942464
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	18978
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	33088
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	14181
ISDYN2CMMMsgTimer_mS_M_u32	4130533120
ISDYNAASChkSumInvalidCount_Cnt_M_u16	31435
ISDYNAASChkSumValidCount_Cnt_M_u16	53493
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	42819
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	11201
ISDYNAASMsgLenValidCount_Cnt_M_u16	17476
ISDYNAASMsgTimeValidCount_Cnt_M_u16	31435
ISDYNAASMsgTimer_mS_M_u32	756436736
ISDYNABRChkSumInvalidCount_Cnt_M_u16	20071
ISDYNABRChkSumValidCount_Cnt_M_u16	13401
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	44366
ISDYNABRMsgCountValidCount_Cnt_M_u16	61368
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	8781
ISDYNABRMsgLenValidCount_Cnt_M_u16	8616
ISDYNABRMsgTimeValidCount_Cnt_M_u16	33436
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	589

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1063
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	35912
ISDYNCMM208MsgTimer_mS_M_u32	1719906048
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2207
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1169
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	4422
ISDYNCMM388MsgTimer_mS_M_u32	3895971584
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	51152
ISDYNVOLChkSumValidCount_Cnt_M_u16	62315
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	58728
ISDYNVOLMsgCountValidCount_Cnt_M_u16	4474
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	19599
ISDYNVOLMsgLenValidCount_Cnt_M_u16	33289
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	32668
ISDYNVOLMsgTimer_mS_M_u32	2523631360
IgnOnTimer_mS_M_u32	3945516800
IgnTimeOff_Sec_M_u32	443869575
ManVehSpd_Kph_M_f32	15.4254999
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	136
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	142
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3709206272
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	166
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1712414464
PrevISDATBSI412MsgDLCError_Cnt_M_u08	114
PrevISDATBSI412MsgRxTime_MSec_M_u32	2912030464
PrevISDATBSI432MsgDLCError_Cnt_M_u08	168
PrevISDATBSI432MsgRxTime_MSec_M_u32	2177167104
PrevISDATDIRAMsgTxTime_MSec_M_u32	685117184
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	204
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1966317312
PrevISDYNAASMsgDLCError_Cnt_M_u08	174
PrevISDYNAASMsgRxTime_MSec_M_u32	3320942336
PrevISDYNABRMsgDLCError_Cnt_M_u08	109
PrevISDYNABRMsgRxTime_MSec_M_u32	339988224
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	115
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2763689728
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	244
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3246124800
PrevISDYNVOLMsgDLCError_Cnt_M_u08	100
PrevISDYNVOLMsgRxTime_MSec_M_u32	9637632
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	445464320
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	570.953125
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	65479
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	12490
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	62404
VitesseVehicleBVRampValidCount_Cnt_M_u16	6279
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	60301
VitesseVehicleBVSigValidCount_Cnt_M_u16	22487

Name	Input Value
VitesseVehicleBV_Kph_M_f32	1.2299
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	4422
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	23592
VitesseVehiculeRoues_Kph_M_f32	253.966003
k_AASNTCEnableTimeout_mS_u16	20855
k_AASNodeAbsentDiag_Cnt_str.Threshold	54981
k_AASNodeAbsentDiag_Cnt_str.PStep	40475
k_AASNodeAbsentDiag_Cnt_str.NStep	54529
k_AASNodeAbsentTimeout_mS_u16	38479
k_AASNodeTimeout_mS_u16	8138
k_ABSNodeTimeout_mS_u16	13675
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	64991
k_ANGLEVOLANTSigValidThresh_Cnt_u16	20117
k_AngleVolantInvalidThresh_Cnt_u16	58112
k_AngleVolantValidThresh_Cnt_u16	45910
k_BSI552MsgTimeout_mS_u16	13395
k_BSINTCEnableTimeout_mS_u16	17320
k_BSINodeAbsentDiag_Cnt_str.Threshold	20972
k_BSINodeAbsentDiag_Cnt_str.PStep	36627
k_BSINodeAbsentDiag_Cnt_str.NStep	12152
k_BSINodeAbsentTimeout_mS_u16	20058
k_BSINodeTimeout_mS_u16	30351
k_BattOvHi_Volt_f32	28.8080997
k_BattOvLo_Volt_f32	20.2334995
k_BattUvHi_Volt_f32	21.7460995
k_BattUvLo_Volt_f32	30.9097004
k_CAVNTCEnableTimeout_mS_u16	45172
k_CAVNodeAbsentDiag_Cnt_str.Threshold	58614
k_CAVNodeAbsentDiag_Cnt_str.PStep	38250
k_CAVNodeAbsentDiag_Cnt_str.NStep	54603
k_CAVNodeAbsentTimeout_mS_u16	27344
k_CAVNodeTimeout_mS_u16	3542
k_CMM388MsgTimeout_mS_u16	21201
k_CMM388NTCEnableTimeout_mS_u16	54493
k_CMMNTCEnableTimeout_mS_u16	18281
k_CMMNodeAbsentDiag_Cnt_str.Threshold	31651
k_CMMNodeAbsentDiag_Cnt_str.PStep	26628
k_CMMNodeAbsentDiag_Cnt_str.NStep	5083
k_CMMNodeAbsentTimeout_mS_u16	52276
k_CONSANGLECPKMax_HwDeg_f32	372.919189
k_CONSANGLECPKMin_HwDeg_f32	-623.946228
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	49222
k_CONSANGLECPKSigValidThresh_Cnt_u16	19240
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	39736
k_CPKVehicleSpeedValidThresh_Cnt_u16	24439
k_CityParkInputInvalidThresh_Cnt_u16	59477
k_CityParkInputValidThresh_Cnt_u16	37172
k_ComputerRazGCTSigValidThresh_Cnt_u16	159
k_CptTemporelSigValidThresh_Cnt_u16	46893
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	20813
k_DMDFCTCPKSigValidThresh_Cnt_u16	37032
k_DMDFCTCPKValidCount_Cnt_u16	33915
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	14181
k_DMDRELAXECPKSigValidThresh_Cnt_u16	55095
k_DMDRelaxeConsistentThresh_Cnt_u16	33957
k_DateValidThresh_Cnt_u16	14178
k_DefaultVehSpd_Kph_f32	10.5502996
k_DiagMuxOnAbsentTimeout_mS_u16	30522
k_EMNodeTimeout_mS_u16	11291
k_ESPNTCEnableTimeout_mS_u16	59094
k_ESPNodeAbsentDiag_Cnt_str.Threshold	20489
k_ESPNodeAbsentDiag_Cnt_str.PStep	61838
k_ESPNodeAbsentDiag_Cnt_str.NStep	40616
k_ESPNodeAbsentTimeout_mS_u16	6940
k_EtatMTSigInvalidThresh_Cnt_u16	3122
k_EtatMTSigValidThresh_Cnt_u16	17508
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	13647
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	36437
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	48945
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	41314
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	29744
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	18356
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	39201

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	14167
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	38276
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	57968
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	22542
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	44131
k_ISDATDIRASentDiag_Cnt_str.Threshold	18181
k_ISDATDIRASentDiag_Cnt_str.PStep	53921
k_ISDATDIRASentDiag_Cnt_str.NStep	55152
k_ISDATDIRASentTimeout_mS_u16	37235
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	3244
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	31554
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	16306
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	64871
k_ISDYNAASChkSumValidThresh_Cnt_u16	9049
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	56398
k_ISDYNAASMsgCountValidThresh_Cnt_u16	24248
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	64091
k_ISDYNAASMsgLenValidThresh_Cnt_u16	26558
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	13181
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	57427
k_ISDYNABRChkSumValidThresh_Cnt_u16	30766
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	1939
k_ISDYNABRMsgCountValidThresh_Cnt_u16	35933
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	28316
k_ISDYNABRMsgLenValidThresh_Cnt_u16	49938
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	4104
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	26555
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	23293
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	6901
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	61200
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	1946
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	6766
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	7311
k_ISDYNVOLChkSumValidThresh_Cnt_u16	37581
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	54915
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	44877
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	942
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	3412
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	7936
k_IgnOnTimeout_mS_u16	41883
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	226.597595
k_PowerCutVehSpdLowThresh_Kph_f32	27.5741997
k_PowerCutVehSpdLowTimeout_mS_u16	5171
k_VBattMaxAAS_Volt_f32	26.5977001
k_VBattMaxBSI_Volt_f32	17.6755009
k_VBattMaxCAV_Volt_f32	9.99370003
k_VBattMaxCMM388_Volt_f32	31.5216007
k_VBattMaxCMM_Volt_f32	12.5641003
k_VBattMaxESP_Volt_f32	19.2196007
k_VBattMinAAS_Volt_f32	2.89610004
k_VBattMinBSI_Volt_f32	19.2196007
k_VBattMinCAV_Volt_f32	6.8144002
k_VBattMinCMM388_Volt_f32	20.6844997
k_VBattMinCMM_Volt_f32	26.1406994
k_VBattMinESP_Volt_f32	12.5641003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	26686
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	16237
k_VitesseVehicleBVRampValidThresh_Cnt_u16	37992
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	25195
k_VitesseVehicleBVSigValidThresh_Cnt_u16	28233
k_VitesseVehicleBVSpeedPassThresh_kph_f32	460.746704
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	65226
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	31757
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3578998528
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	85
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	49293
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1435748352
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	244
target_SrlComInput_Per1_Batt_Volt_f32.value	1.3743
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1398660864
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	145
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.00807677861
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3930967808
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	101
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1894608640
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	160
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3365736192
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	255
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2572988160
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2334936832
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	204
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1175187200
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	139
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1912311552
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	97
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	132
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	139
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	208
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	234
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	157
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3694767872
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	80
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	126
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	128
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	218
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1822740224
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4240731904
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	24
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	502533888
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	80
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	133
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	375086848
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2065
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.860307395
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	763897
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	69.3595963

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	35545		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1435748352	1435748352	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	54981	54981	✔
AASNodeAbsentTimer_mS_M_u32	1435748352	1435748352	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	31556	31556	✔
AngleVolantMsgTimer_mS_M_u32	1435748352	1435748352	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1435748352	1435748352	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1435748352	1435748352	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1435748352	1435748352	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1435748352	1435748352	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	20972	20972	✔
BSINodeAbsentTimer_mS_M_u32	1435748352	1435748352	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1435748352	1435748352	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1435748352	1435748352	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1435748352	1435748352	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1435748352	1435748352	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1435748352	1435748352	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	33436	33436	✔
CONSANGLECPK_HwDeg_M_f32	-475.919708	-475.919708 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	33436	33436	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3910942464	3910942464	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	53312	53312	✔
CityParkInputConsistentCount_Cnt_M_u16	37172	37172	✔
CityParkInputInvalidCount_Cnt_M_u16	45912	45912	✔
CityParkInputMsgTimer_mS_M_u32	1435748352	1435748352	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1435748352	1435748352	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1435748352	1435748352	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	1	1	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1435748352	1435748352	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1435748352	1435748352	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1435748352	1435748352	✔
ESPNTCEnableTimer_mS_M_u32	1435748352	1435748352	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	20489	20489	✔
ESPNodeAbsentTimer_mS_M_u32	1435748352	1435748352	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1435748352	1435748352	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	1001	1001	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1435748352	1435748352	✔
ElecIntTimer_mS_M_u32[1]	103	103	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1435748352	1435748352	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1435748352	1435748352	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1435748352	1435748352	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1435748352	1435748352	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1435748352	1435748352	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1435748352	1435748352	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1435748352	1435748352	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1435748352	1435748352	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1435748352	1435748352	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1435748352	1435748352	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1435748352	1435748352	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1435748352	1435748352	✔
IgnOnTimer_mS_M_u32	3945516800	3945516800	✔
IgnTimeOff_Sec_M_u32	443869575	443869575	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	168	168	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3930967808	3930967808	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	101	101	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1894608640	1894608640	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	160	160	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3365736192	3365736192	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	255	255	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2572988160	2572988160	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	685117184	685117184	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	204	204	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1175187200	1175187200	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	139	139	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1912311552	1912311552	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	157	157	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3694767872	3694767872	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	14	14	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1822740224	1822740224	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	245	245	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4240731904	4240731904	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	24	24	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	502533888	502533888	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	375086848	375086848	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	570.953125	570.953125	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	1.2299	1.2299	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	253.966003	253.966003	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	33436	33436	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	443869575	443869575	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-475.919708	-475.919708 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	10.5502996	10.5502996	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.28 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2530674176
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	53733
AASNodeAbsentTimer_mS_M_u32	3936810496
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	5930
ANGLEVOLANTSigValidCount_Cnt_M_u16	45643
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	53138
AngleVolantMsgTimer_mS_M_u32	2530674176
AngleVolantValidCount_Cnt_M_u16	15385
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	459978240
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3475060224
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1682941440
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3771885056
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	39329
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4272956928
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	6778
CAVNodeAbsentTimer_mS_M_u32	1735628288
CDD_SrlComVehSpd_Kph_G_f32	145.037399
CMM388NTCEnableTimer_mS_M_u32	1803277824
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	673814016
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	56517
CMMNodeAbsentTimer_mS_M_u32	2929485312
CONSANGLECPKSigInvalidCount_Cnt_M_u16	28665
CONSANGLECPKSigValidCount_Cnt_M_u16	23403
CONSANGLECPK_Cnt_M_u16	11078
CONSANGLECPK_HwDeg_M_f32	-304.386688
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	11078
CPKVehicleSpeedMsgTimer_mS_M_u32	3422946816
CPKVehicleSpeedValidCount_Cnt_M_u16	9314

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	56381
CityParkInputInvalidCount_Cnt_M_u16	52950
CityParkInputMsgTimer_mS_M_u32	3930967808
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2479552000
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	26633
ComputerRazGCTSigInvalidTimer_mS_M_u32	2826704384
ComputerRazGCTSigValidCount_Cnt_M_u16	5666
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	51890
DMDFCTCPKSigValidCount_Cnt_M_u16	21692
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	44604
DMDRELAXECPKSigValidCount_Cnt_M_u16	53981
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	13990
DateInvalidTimer_mS_M_u32	3475060224
DiagMuxOnAbsentTimer_mS_M_u32	2979317248
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3771885056
ESPNTCEnableTimer_mS_M_u32	2033710592
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	29731
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	252
EffacDefaultDiagTimer_mS_M_u32[1]	2885905152
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	658
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3055691264
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	10675
EtatMTSigValidCount_Cnt_M_u16	13440
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	48395
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	45565
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	61298
ISDAT4V2BSI552MsgTimer_mS_M_u32	2864735744
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	12582
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	32187
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13440
ISDATBSI3F2MsgTimer_mS_M_u32	4236428800
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	10456
ISDATBSI412MsgLenValidCount_Cnt_M_u16	58014
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	10675
ISDATBSI412MsgTimer_mS_M_u32	3351578112
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	27625
ISDATBSI432MsgLenValidCount_Cnt_M_u16	54855
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	64043
ISDATDIRASentFltAcc_Cnt_M_u16	55647
ISDATDIRASentTimer_mS_M_u32	3422946816
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	27828
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	15385
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	16041
ISDYN2CMMMsgTimer_mS_M_u32	2608985600
ISDYNAASChkSumInvalidCount_Cnt_M_u16	13559
ISDYNAASChkSumValidCount_Cnt_M_u16	55096
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	38416
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	8853
ISDYNAASMsgLenValidCount_Cnt_M_u16	56782
ISDYNAASMsgTimeValidCount_Cnt_M_u16	13559
ISDYNAASMsgTimer_mS_M_u32	1012389376
ISDYNABRChkSumInvalidCount_Cnt_M_u16	57253
ISDYNABRChkSumValidCount_Cnt_M_u16	62094
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	26990
ISDYNABRMsgCountValidCount_Cnt_M_u16	18159
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	6000
ISDYNABRMsgLenValidCount_Cnt_M_u16	32290
ISDYNABRMsgTimeValidCount_Cnt_M_u16	11078

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	590
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1065
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13440
ISDYNCMM208MsgTimer_mS_M_u32	2106570240
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2211
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1171
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	9223
ISDYNCMM388MsgTimer_mS_M_u32	1894995456
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	62183
ISDYNVOLChkSumValidCount_Cnt_M_u16	54489
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	160
ISDYNVOLMsgCountValidCount_Cnt_M_u16	49450
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	32428
ISDYNVOLMsgLenValidCount_Cnt_M_u16	49917
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	56517
ISDYNVOLMsgTimer_mS_M_u32	3847755264
IgnOnTimer_mS_M_u32	941053440
IgnTimeOff_Sec_M_u32	2075672318
ManVehSpd_Kph_M_f32	54.6217995
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	138
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	119064064
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	34
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	296134144
PrevISDATBSI412MsgDLCError_Cnt_M_u08	16
PrevISDATBSI412MsgRxTime_MSec_M_u32	1508152832
PrevISDATBSI432MsgDLCError_Cnt_M_u08	1
PrevISDATBSI432MsgRxTime_MSec_M_u32	3234592256
PrevISDATDIRAMsgTxTime_MSec_M_u32	4162360832
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	241
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1027597824
PrevISDYNAASMsgDLCError_Cnt_M_u08	49
PrevISDYNAASMsgRxTime_MSec_M_u32	4005959168
PrevISDYNABRMsgDLCError_Cnt_M_u08	120
PrevISDYNABRMsgRxTime_MSec_M_u32	483350016
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	135
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3060471296
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	89
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2644964864
PrevISDYNVOLMsgDLCError_Cnt_M_u08	195
PrevISDYNVOLMsgRxTime_MSec_M_u32	2766247424
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1001588224
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	180.795807
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	16003
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	45116
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	38540
VitesseVehicleBVRampValidCount_Cnt_M_u16	11525
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	51379

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	43156
VitesseVehicleBV_Kph_M_f32	625.998108
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	9223
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	51233
VitesseVehiculeRoues_Kph_M_f32	297.230896
k_AASNTCEnableTimeout_mS_u16	60085
k_AASNodeAbsentDiag_Cnt_str.Threshold	31581
k_AASNodeAbsentDiag_Cnt_str.PStep	62324
k_AASNodeAbsentDiag_Cnt_str.NStep	9241
k_AASNodeAbsentTimeout_mS_u16	63724
k_AASNodeTimeout_mS_u16	58172
k_ABSNodeTimeout_mS_u16	56471
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	11772
k_ANGLEVOLANTSigValidThresh_Cnt_u16	4250
k_AngleVolantInvalidThresh_Cnt_u16	48985
k_AngleVolantValidThresh_Cnt_u16	52950
k_BSI552MsgTimeout_mS_u16	43936
k_BSINTCEnableTimeout_mS_u16	49313
k_BSINodeAbsentDiag_Cnt_str.Threshold	21012
k_BSINodeAbsentDiag_Cnt_str.PStep	36610
k_BSINodeAbsentDiag_Cnt_str.NStep	12175
k_BSINodeAbsentTimeout_mS_u16	46666
k_BSINodeTimeout_mS_u16	64043
k_BattOvHi_Volt_f32	22.1973991
k_BattOvLo_Volt_f32	11.5808001
k_BattUvHi_Volt_f32	27.9584007
k_BattUvLo_Volt_f32	23.4146004
k_CAVNTCEnableTimeout_mS_u16	53116
k_CAVNodeAbsentDiag_Cnt_str.Threshold	34306
k_CAVNodeAbsentDiag_Cnt_str.PStep	45310
k_CAVNodeAbsentDiag_Cnt_str.NStep	756
k_CAVNodeAbsentTimeout_mS_u16	24936
k_CAVNodeTimeout_mS_u16	47317
k_CMM388MsgTimeout_mS_u16	17637
k_CMM388NTCEnableTimeout_mS_u16	61121
k_CMMNTCEnableTimeout_mS_u16	41438
k_CMMNodeAbsentDiag_Cnt_str.Threshold	41252
k_CMMNodeAbsentDiag_Cnt_str.PStep	59161
k_CMMNodeAbsentDiag_Cnt_str.NStep	3562
k_CMMNodeAbsentTimeout_mS_u16	43005
k_CONSANGLECPKMax_HwDeg_f32	178.906006
k_CONSANGLECPKMin_HwDeg_f32	-228.881607
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	5895
k_CONSANGLECPKSigValidThresh_Cnt_u16	64289
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	43250
k_CPKVehicleSpeedValidThresh_Cnt_u16	25267
k_CityParkInputInvalidThresh_Cnt_u16	18907
k_CityParkInputValidThresh_Cnt_u16	56381
k_ComputerRazGCTSigValidThresh_Cnt_u16	52796
k_CptTemporelSigValidThresh_Cnt_u16	57169
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	35440
k_DMDFCTCPKSigValidThresh_Cnt_u16	12578
k_DMDFCTCPKValidCount_Cnt_u16	13801
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	16041
k_DMDRELAXECPKSigValidThresh_Cnt_u16	41971
k_DMDRelaxeConsistentThresh_Cnt_u16	54185
k_DateValidThresh_Cnt_u16	61298
k_DefaultVehSpd_Kph_f32	114.203697
k_DiagMuxOnAbsentTimeout_mS_u16	17772
k_EMNodeTimeout_mS_u16	45574
k_ESPNTCEnableTimeout_mS_u16	34134
k_ESPNodeAbsentDiag_Cnt_str.Threshold	62417
k_ESPNodeAbsentDiag_Cnt_str.PStep	64345
k_ESPNodeAbsentDiag_Cnt_str.NStep	63331
k_ESPNodeAbsentTimeout_mS_u16	23365
k_EtatMTSigInvalidThresh_Cnt_u16	37444
k_EtatMTSigValidThresh_Cnt_u16	44653
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	63149
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	91
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	34374
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	47091
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	29768
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	56828

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	58422
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	56916
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	15117
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	23498
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	28591
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	31982
k_ISDATDIRASentDiag_Cnt_str.Threshold	1109
k_ISDATDIRASentDiag_Cnt_str.PStep	63963
k_ISDATDIRASentDiag_Cnt_str.NStep	30981
k_ISDATDIRASentTimeout_mS_u16	18049
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	49171
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	53138
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	60098
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	53925
k_ISDYNAASChkSumValidThresh_Cnt_u16	9614
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	56430
k_ISDYNAASMsgCountValidThresh_Cnt_u16	63983
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	43977
k_ISDYNAASMsgLenValidThresh_Cnt_u16	56160
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	482
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	30046
k_ISDYNABRChkSumValidThresh_Cnt_u16	4752
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	3233
k_ISDYNABRMsgCountValidThresh_Cnt_u16	41730
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	4037
k_ISDYNABRMsgLenValidThresh_Cnt_u16	59171
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	33793
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	54951
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	2081
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	23995
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	35370
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	25931
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	63886
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	35691
k_ISDYNVOLChkSumValidThresh_Cnt_u16	7537
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	45264
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	20914
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	27023
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	57692
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	12440
k_IgnOnTimeout_mS_u16	9799
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	194.5616
k_PowerCutVehSpdLowThresh_Kph_f32	127.631897
k_PowerCutVehSpdLowTimeout_mS_u16	37505
k_VBattMaxAAS_Volt_f32	30.0163002
k_VBattMaxBSI_Volt_f32	25.3941994
k_VBattMaxCAV_Volt_f32	7.8664999
k_VBattMaxCMM388_Volt_f32	6.76910019
k_VBattMaxCMM_Volt_f32	17.5895996
k_VBattMaxESP_Volt_f32	16.4111996
k_VBattMinAAS_Volt_f32	19.2332993
k_VBattMinBSI_Volt_f32	16.4111996
k_VBattMinCAV_Volt_f32	28.3290005
k_VBattMinCMM388_Volt_f32	29.5802002
k_VBattMinCMM_Volt_f32	18.7222996
k_VBattMinESP_Volt_f32	17.5895996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	30045
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	42131
k_VitesseVehicleBVRampValidThresh_Cnt_u16	62368
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	34777
k_VitesseVehicleBVSigValidThresh_Cnt_u16	55550
k_VitesseVehicleBVSpeedPassThresh_kph_f32	232.598801
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	3450
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	39539
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3475060224
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	61
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8366
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2885905152
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	89
target_SrlComInput_Per1_Batt_Volt_f32.value	12.9837999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	465643008
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	109
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.942946494
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1118918144
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	138
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	894596608
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	130
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4106458624
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2298787328
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4195735040
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1341584896
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2460489216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	69
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	124
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	176
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	204
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1953347072
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	115
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	185
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3618395648
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	249
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2915923456
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	280925696
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	58
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	123
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	153
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	193
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2831721984
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3978
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.648431003
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	377678
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	58.5256996
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	25933

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2885905152	2885905152	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	31581	31581	✔
AASNodeAbsentTimer_mS_M_u32	2885905152	2885905152	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2885905152	2885905152	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2885905152	2885905152	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2885905152	2885905152	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2885905152	2885905152	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2885905152	2885905152	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21012	21012	✔
BSINodeAbsentTimer_mS_M_u32	2885905152	2885905152	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2885905152	2885905152	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2885905152	2885905152	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2885905152	2885905152	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2885905152	2885905152	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2885905152	2885905152	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	11078	11078	✔
CONSANGLECPK_HwDeg_M_f32	-304.386688	-304.386688 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2885905152	2885905152	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2885905152	2885905152	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2885905152	2885905152	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2885905152	2885905152	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	1	1	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2885905152	2885905152	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2885905152	2885905152	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2885905152	2885905152	✔
ESPNTCEnableTimer_mS_M_u32	2885905152	2885905152	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	62417	62417	✔
ESPNodeAbsentTimer_mS_M_u32	2885905152	2885905152	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	252	252	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2885905152	2885905152	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2885905152	2885905152	✔
ElecIntTimer_mS_M_u32[1]	658	658	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2885905152	2885905152	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2885905152	2885905152	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2885905152	2885905152	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2885905152	2885905152	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2885905152	2885905152	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2885905152	2885905152	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2885905152	2885905152	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2885905152	2885905152	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2885905152	2885905152	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2885905152	2885905152	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2885905152	2885905152	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2885905152	2885905152	✔
IgnOnTimer_mS_M_u32	941053440	941053440	✔
IgnTimeOff_Sec_M_u32	2075672318	2075672318	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	91	91	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1118918144	1118918144	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	138	138	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	894596608	894596608	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	130	130	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4106458624	4106458624	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	75	75	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2298787328	2298787328	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4162360832	4162360832	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	241	241	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1341584896	1341584896	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	219	219	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2460489216	2460489216	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	35	35	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1953347072	1953347072	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3618395648	3618395648	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	249	249	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2915923456	2915923456	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	53	53	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	280925696	280925696	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2831721984	2831721984	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	180.795807	180.795807	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	625.998108	625.998108	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	297.230896	297.230896	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	11078	11078	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2075672318	2075672318	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-304.386688	-304.386688 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.29 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	179417344
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	45958
AASNodeAbsentTimer_mS_M_u32	2063720704
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	38328
ANGLEVOLANTSigValidCount_Cnt_M_u16	22036
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	44671
AngleVolantMsgTimer_mS_M_u32	179417344
AngleVolantValidCount_Cnt_M_u16	60777
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2813763840
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2257789184
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3435647232
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3527381248
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	43603
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	530993408
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	29768
CAVNodeAbsentTimer_mS_M_u32	2132541696
CDD_SrlComVehSpd_Kph_G_f32	424.959595
CMM388NTCEnableTimer_mS_M_u32	3825418496
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2499412224
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	14373
CMMNodeAbsentTimer_mS_M_u32	283218176
CONSANGLECPKSigInvalidCount_Cnt_M_u16	31305
CONSANGLECPKSigValidCount_Cnt_M_u16	35253
CONSANGLECPK_Cnt_M_u16	17956
CONSANGLECPK_HwDeg_M_f32	-313.73761
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17956
CPKVehicleSpeedMsgTimer_mS_M_u32	3877941504
CPKVehicleSpeedValidCount_Cnt_M_u16	54455
CityParkInputConsistentCount_Cnt_M_u16	40189
CityParkInputInvalidCount_Cnt_M_u16	47666

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	1118918144
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	261480704
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	33050
ComputerRazGCTSigInvalidTimer_mS_M_u32	2114093312
ComputerRazGCTSigValidCount_Cnt_M_u16	49998
CountEtatMT_Cnt_M_u08	3
DMDFCTCPKSigInvalidCount_Cnt_M_u16	13982
DMDFCTCPKSigValidCount_Cnt_M_u16	51777
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	39042
DMDRELAXECPKSigValidCount_Cnt_M_u16	48222
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	6722
DateInvalidTimer_mS_M_u32	2257789184
DiagMuxOnAbsentTimer_mS_M_u32	3782766848
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3527381248
ESPNTCEnableTimer_mS_M_u32	1397678336
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	62412
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	102
EffacDefaultDiagTimer_mS_M_u32[1]	106
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	54
ElecIntTimer_mS_M_u32[1]	68
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1095782656
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	38493
EtatMTSigValidCount_Cnt_M_u16	47029
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	23315
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	19967
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	21023
ISDAT4V2BSI552MsgTimer_mS_M_u32	2893385984
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1411
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	33155
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	47029
ISDATBSI3F2MsgTimer_mS_M_u32	950956288
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	46956
ISDATBSI412MsgLenValidCount_Cnt_M_u16	43996
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	38493
ISDATBSI412MsgTimer_mS_M_u32	2951196928
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	6841
ISDATBSI432MsgLenValidCount_Cnt_M_u16	23904
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	55605
ISDATDIRASentFltAcc_Cnt_M_u16	2969
ISDATDIRASentTimer_mS_M_u32	3877941504
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	47578
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	60777
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	30393
ISDYN2CMMMsgTimer_mS_M_u32	2490425600
ISDYNAASChkSumInvalidCount_Cnt_M_u16	21072
ISDYNAASChkSumValidCount_Cnt_M_u16	32075
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	31620
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	34807
ISDYNAASMsgLenValidCount_Cnt_M_u16	18443
ISDYNAASMsgTimeValidCount_Cnt_M_u16	21072
ISDYNAASMsgTimer_mS_M_u32	3782164736
ISDYNABRChkSumInvalidCount_Cnt_M_u16	57798
ISDYNABRChkSumValidCount_Cnt_M_u16	23242
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	20715
ISDYNABRMsgCountValidCount_Cnt_M_u16	51750
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	8164
ISDYNABRMsgLenValidCount_Cnt_M_u16	48528
ISDYNABRMsgTimeValidCount_Cnt_M_u16	17956
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	591
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1067

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	47029
ISDYNCMM208MsgTimer_mS_M_u32	1430757632
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2215
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1173
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	28063
ISDYNCMM388MsgTimer_mS_M_u32	295485696
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	10623
ISDYNVOLChkSumValidCount_Cnt_M_u16	21867
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	52436
ISDYNVOLMsgCountValidCount_Cnt_M_u16	48375
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	14385
ISDYNVOLMsgLenValidCount_Cnt_M_u16	48381
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	14373
ISDYNVOLMsgTimer_mS_M_u32	929988864
IgnOnTimer_mS_M_u32	1278263552
IgnTimeOff_Sec_M_u32	2279708816
ManVehSpd_Kph_M_f32	111.012703
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	140
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	216
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4042027264
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	55
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3770863872
PrevISDATBSI412MsgDLCError_Cnt_M_u08	116
PrevISDATBSI412MsgRxTime_MSec_M_u32	2882076928
PrevISDATBSI432MsgDLCError_Cnt_M_u08	230
PrevISDATBSI432MsgRxTime_MSec_M_u32	3432177920
PrevISDATDIRAMsgTxTime_MSec_M_u32	2704081152
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	130
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1391923456
PrevISDYNAASMsgDLCError_Cnt_M_u08	147
PrevISDYNAASMsgRxTime_MSec_M_u32	1394901248
PrevISDYNABRMsgDLCError_Cnt_M_u08	51
PrevISDYNABRMsgRxTime_MSec_M_u32	2114502912
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	167
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3493167360
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	48
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1644290304
PrevISDYNVOLMsgDLCError_Cnt_M_u08	201
PrevISDYNVOLMsgRxTime_MSec_M_u32	4275175680
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2350756096
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	261.280212
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	27693
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	2241
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	51218
VitesseVehicleBVRampValidCount_Cnt_M_u16	63078
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	58653
VitesseVehicleBVSigValidCount_Cnt_M_u16	55097
VitesseVehicleBV_Kph_M_f32	92.2152023

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	28063
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	62227
VitesseVehiculeRoues_Kph_M_f32	446.53299
k_AASNTCEnableTimeout_mS_u16	33751
k_AASNodeAbsentDiag_Cnt_str.Threshold	49186
k_AASNodeAbsentDiag_Cnt_str.PStep	19861
k_AASNodeAbsentDiag_Cnt_str.NStep	39839
k_AASNodeAbsentTimeout_mS_u16	49904
k_AASNodeTimeout_mS_u16	28609
k_ABSNodeTimeout_mS_u16	54511
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	57472
k_ANGLEVOLANTSigValidThresh_Cnt_u16	47719
k_AngleVolantInvalidThresh_Cnt_u16	27178
k_AngleVolantValidThresh_Cnt_u16	47666
k_BSI552MsgTimeout_mS_u16	1174
k_BSINTCEnableTimeout_mS_u16	64657
k_BSINodeAbsentDiag_Cnt_str.Threshold	21052
k_BSINodeAbsentDiag_Cnt_str.PStep	36593
k_BSINodeAbsentDiag_Cnt_str.NStep	12198
k_BSINodeAbsentTimeout_mS_u16	55895
k_BSINodeTimeout_mS_u16	55605
k_BattOvHi_Volt_f32	26.1425991
k_BattOvLo_Volt_f32	4.51340008
k_BattUvHi_Volt_f32	22.6338005
k_BattUvLo_Volt_f32	31.5
k_CAVNTCEnableTimeout_mS_u16	53312
k_CAVNodeAbsentDiag_Cnt_str.Threshold	57482
k_CAVNodeAbsentDiag_Cnt_str.PStep	2704
k_CAVNodeAbsentDiag_Cnt_str.NStep	16357
k_CAVNodeAbsentTimeout_mS_u16	55166
k_CAVNodeTimeout_mS_u16	4021
k_CMM388MsgTimeout_mS_u16	23174
k_CMM388NTCEnableTimeout_mS_u16	52466
k_CMMNTCEnableTimeout_mS_u16	37723
k_CMMNodeAbsentDiag_Cnt_str.Threshold	37292
k_CMMNodeAbsentDiag_Cnt_str.PStep	65156
k_CMMNodeAbsentDiag_Cnt_str.NStep	27402
k_CMMNodeAbsentTimeout_mS_u16	50047
k_CONSANGLECPKMax_HwDeg_f32	162.563599
k_CONSANGLECPKMin_HwDeg_f32	-117.922302
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	38047
k_CONSANGLECPKSigValidThresh_Cnt_u16	23059
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	30367
k_CPKVehicleSpeedValidThresh_Cnt_u16	13787
k_CityParkInputInvalidThresh_Cnt_u16	64292
k_CityParkInputValidThresh_Cnt_u16	40189
k_ComputerRazGCTSigValidThresh_Cnt_u16	1601
k_CptTemporelSigValidThresh_Cnt_u16	13505
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	50916
k_DMDFCTCPKSigValidThresh_Cnt_u16	42128
k_DMDFCTCPKValidCount_Cnt_u16	62843
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	30393
k_DMDRELAXECPKSigValidThresh_Cnt_u16	30876
k_DMDRelaxeConsistentThresh_Cnt_u16	16762
k_DateValidThresh_Cnt_u16	21023
k_DefaultVehSpd_Kph_f32	213.102798
k_DiagMuxOnAbsentTimeout_mS_u16	4018
k_EMNodeTimeout_mS_u16	10274
k_ESPNTCEnableTimeout_mS_u16	41908
k_ESPNodeAbsentDiag_Cnt_str.Threshold	43526
k_ESPNodeAbsentDiag_Cnt_str.PStep	12069
k_ESPNodeAbsentDiag_Cnt_str.NStep	37118
k_ESPNodeAbsentTimeout_mS_u16	51623
k_EtatMTSigInvalidThresh_Cnt_u16	1513
k_EtatMTSigValidThresh_Cnt_u16	25389
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	14702
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	56869
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	738
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	58652
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	4572
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	10240
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	9682
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	47417

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	15693
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	50328
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	10919
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	58409
k_ISDATDIRASentDiag_Cnt_str.Threshold	30738
k_ISDATDIRASentDiag_Cnt_str.PStep	11895
k_ISDATDIRASentDiag_Cnt_str.NStep	26675
k_ISDATDIRASentTimeout_mS_u16	7474
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	61114
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	44671
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	9072
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	2246
k_ISDYNAASChkSumValidThresh_Cnt_u16	49610
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	63467
k_ISDYNAASMsgCountValidThresh_Cnt_u16	45350
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	3418
k_ISDYNAASMsgLenValidThresh_Cnt_u16	5973
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	1679
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	15898
k_ISDYNABRChkSumValidThresh_Cnt_u16	14406
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	20819
k_ISDYNABRMsgCountValidThresh_Cnt_u16	8175
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	40741
k_ISDYNABRMsgLenValidThresh_Cnt_u16	39628
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	14578
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	13249
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	32145
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	48196
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	15544
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	15636
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	6666
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	39859
k_ISDYNVOLChkSumValidThresh_Cnt_u16	1891
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	12741
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	52574
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	18121
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	8481
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	42669
k_IgnOnTimeout_mS_u16	15135
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	90.5290985
k_PowerCutVehSpdLowThresh_Kph_f32	235.3181
k_PowerCutVehSpdLowTimeout_mS_u16	48243
k_VBattMaxAAS_Volt_f32	5.5625
k_VBattMaxBSI_Volt_f32	14.5951004
k_VBattMaxCAV_Volt_f32	23.8978996
k_VBattMaxCMM388_Volt_f32	1.73109996
k_VBattMaxCMM_Volt_f32	8.42479992
k_VBattMaxESP_Volt_f32	21.5958004
k_VBattMinAAS_Volt_f32	19.5748997
k_VBattMinBSI_Volt_f32	21.5958004
k_VBattMinCAV_Volt_f32	28.7357006
k_VBattMinCMM388_Volt_f32	28.3983994
k_VBattMinCMM_Volt_f32	11.4398003
k_VBattMinESP_Volt_f32	8.42479992
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	30428
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	51964
k_VitesseVehicleBVRampValidThresh_Cnt_u16	62420
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	15467
k_VitesseVehicleBVSigValidThresh_Cnt_u16	60090
k_VitesseVehicleBVSpeedPassThresh_kph_f32	285.980194
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	39752
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	58908
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2257789184
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	18
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	18486
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1728086528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	48

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	1.88769996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1282625792
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	52
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.474639237
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	342016256
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2835308800
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	388759808
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	32
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1189650688
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	540360960
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	130
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2333204736
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1870561536
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	63
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	71
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	88
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	164
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	228
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1756209408
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	105
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	166
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	176
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	24232192
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3951976704
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1866137856
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	20
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	218
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	245
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	593285376
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2157
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.652252555
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	938586
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	17.8866997
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	40911

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1728086528	1728086528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	49186	49186	✔
AASNodeAbsentTimer_mS_M_u32	1728086528	1728086528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1728086528	1728086528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1728086528	1728086528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1728086528	1728086528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1728086528	1728086528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1728086528	1728086528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21052	21052	✔
BSINodeAbsentTimer_mS_M_u32	1728086528	1728086528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1728086528	1728086528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1728086528	1728086528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1728086528	1728086528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1728086528	1728086528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1728086528	1728086528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	17956	17956	✔
CONSANGLECPK_HwDeg_M_f32	-313.73761	-313.73761 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1728086528	1728086528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1728086528	1728086528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1728086528	1728086528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1728086528	1728086528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	1	1	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1728086528	1728086528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1728086528	1728086528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1728086528	1728086528	✔
ESPNTCEnableTimer_mS_M_u32	1728086528	1728086528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	43526	43526	✔
ESPNodeAbsentTimer_mS_M_u32	1728086528	1728086528	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1728086528	1728086528	✔
EffacDefaultDiagTimer_mS_M_u32[1]	106	106	✔
ElecIntCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	1728086528	1728086528	✔
ElecIntTimer_mS_M_u32[1]	68	68	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1728086528	1728086528	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1728086528	1728086528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1728086528	1728086528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1728086528	1728086528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1728086528	1728086528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1728086528	1728086528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1728086528	1728086528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1728086528	1728086528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1728086528	1728086528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1728086528	1728086528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1728086528	1728086528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1728086528	1728086528	✔
IgnOnTimer_mS_M_u32	1728086528	1728086528	✔
IgnTimeOff_Sec_M_u32	2279708816	2279708816	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	342016256	342016256	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	9	9	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2835308800	2835308800	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	46	46	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	388759808	388759808	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	32	32	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1189650688	1189650688	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2704081152	2704081152	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	130	130	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2333204736	2333204736	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	215	215	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1870561536	1870561536	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	123	123	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1756209408	1756209408	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	181	181	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	24232192	24232192	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	105	105	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3951976704	3951976704	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	195	195	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1866137856	1866137856	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	593285376	593285376	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	261.280212	261.280212	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	92.2152023	92.2152023	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	446.53299	446.53299	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	17956	17956	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2279708816	2279708816	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-313.73761	-313.73761 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.30 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3280842752
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	47888
AASNodeAbsentTimer_mS_M_u32	794632192
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	65144
ANGLEVOLANTSigValidCount_Cnt_M_u16	2085
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	60965
AngleVolantMsgTimer_mS_M_u32	3280842752
AngleVolantValidCount_Cnt_M_u16	41957
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1816059904
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3785973760
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	4257959936
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2086932480
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	60583
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2670710784
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	43337
CAVNodeAbsentTimer_mS_M_u32	3012476928
CDD_SrlComVehSpd_Kph_G_f32	291.327515
CMM388NTCEnableTimer_mS_M_u32	836304896
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1777647616
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	15731
CMMNodeAbsentTimer_mS_M_u32	3363704832
CONSANGLECPKSigInvalidCount_Cnt_M_u16	33734
CONSANGLECPKSigValidCount_Cnt_M_u16	57411
CONSANGLECPK_Cnt_M_u16	9974
CONSANGLECPK_HwDeg_M_f32	442.508606
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	9974
CPKVehicleSpeedMsgTimer_mS_M_u32	3124015104
CPKVehicleSpeedValidCount_Cnt_M_u16	44421
CityParkInputConsistentCount_Cnt_M_u16	58665
CityParkInputInvalidCount_Cnt_M_u16	44684

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	342016256
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3248562176
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	41556
ComputerRazGCTSigInvalidTimer_mS_M_u32	1893416960
ComputerRazGCTSigValidCount_Cnt_M_u16	63030
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	59720
DMDFCTCPKSigValidCount_Cnt_M_u16	39197
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	40474
DMDRELAXECPKSigValidCount_Cnt_M_u16	32071
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	51163
DateInvalidTimer_mS_M_u32	3785973760
DiagMuxOnAbsentTimer_mS_M_u32	3392761856
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2086932480
ESPNTCEnableTimer_mS_M_u32	443949056
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	34107
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	89
EffacDefaultDiagTimer_mS_M_u32[1]	789
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	104
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1647431680
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	21450
EtatMTSigValidCount_Cnt_M_u16	10883
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	35176
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	15205
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	63875
ISDAT4V2BSI552MsgTimer_mS_M_u32	1170345984
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	30168
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	56473
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	10883
ISDATBSI3F2MsgTimer_mS_M_u32	479686656
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	38172
ISDATBSI412MsgLenValidCount_Cnt_M_u16	21133
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	21450
ISDATBSI412MsgTimer_mS_M_u32	736866304
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	58807
ISDATBSI432MsgLenValidCount_Cnt_M_u16	39039
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	28290
ISDATDIRASentFltAcc_Cnt_M_u16	26454
ISDATDIRASentTimer_mS_M_u32	3124015104
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	9172
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	41957
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	21751
ISDYN2CMMMsgTimer_mS_M_u32	1594892288
ISDYNAASChkSumInvalidCount_Cnt_M_u16	34482
ISDYNAASChkSumValidCount_Cnt_M_u16	53375
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	9620
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	59964
ISDYNAASMsgLenValidCount_Cnt_M_u16	54465
ISDYNAASMsgTimeValidCount_Cnt_M_u16	34482
ISDYNAASMsgTimer_mS_M_u32	3918856192
ISDYNABRChkSumInvalidCount_Cnt_M_u16	10703
ISDYNABRChkSumValidCount_Cnt_M_u16	43396
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	46817
ISDYNABRMsgCountValidCount_Cnt_M_u16	5614
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	48885
ISDYNABRMsgLenValidCount_Cnt_M_u16	28850
ISDYNABRMsgTimeValidCount_Cnt_M_u16	9974
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	592
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1069

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	10883
ISDYNCMM208MsgTimer_mS_M_u32	3884703744
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2219
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1175
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	31555
ISDYNCMM388MsgTimer_mS_M_u32	4010573824
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	52772
ISDYNVOLChkSumValidCount_Cnt_M_u16	54561
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	32422
ISDYNVOLMsgCountValidCount_Cnt_M_u16	6395
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	35852
ISDYNVOLMsgLenValidCount_Cnt_M_u16	2153
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	15731
ISDYNVOLMsgTimer_mS_M_u32	4103553024
IgnOnTimer_mS_M_u32	2404417536
IgnTimeOff_Sec_M_u32	503306140
ManVehSpd_Kph_M_f32	363.389496
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	142
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	46
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1809674240
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	199
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1843023872
PrevISDATBSI412MsgDLCError_Cnt_M_u08	3
PrevISDATBSI412MsgRxTime_MSec_M_u32	562544640
PrevISDATBSI432MsgDLCError_Cnt_M_u08	220
PrevISDATBSI432MsgRxTime_MSec_M_u32	3198820352
PrevISDATDIRAMsgTxTime_MSec_M_u32	3512451072
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	202
PrevISDYN2CMMMsgRxTime_MSec_M_u32	943558656
PrevISDYNAASMsgDLCError_Cnt_M_u08	32
PrevISDYNAASMsgRxTime_MSec_M_u32	4185210880
PrevISDYNABRMsgDLCError_Cnt_M_u08	225
PrevISDYNABRMsgRxTime_MSec_M_u32	1506312192
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	165
PrevISDYNCMM208MsgRxTime_MSec_M_u32	105005056
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	11
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2052923392
PrevISDYNVOLMsgDLCError_Cnt_M_u08	185
PrevISDYNVOLMsgRxTime_MSec_M_u32	2355937280
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4014583808
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	295.238312
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	38298
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	60063
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	21995
VitesseVehicleBVRampValidCount_Cnt_M_u16	62896
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	58441
VitesseVehicleBVSigValidCount_Cnt_M_u16	22710
VitesseVehicleBV_Kph_M_f32	584.50769

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	31555
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	38312
VitesseVehiculeRoues_Kph_M_f32	104.825302
k_AASNTCEnableTimeout_mS_u16	63965
k_AASNodeAbsentDiag_Cnt_str.Threshold	35375
k_AASNodeAbsentDiag_Cnt_str.PStep	57519
k_AASNodeAbsentDiag_Cnt_str.NStep	13992
k_AASNodeAbsentTimeout_mS_u16	65360
k_AASNodeTimeout_mS_u16	46495
k_ABSNodeTimeout_mS_u16	37461
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	28770
k_ANGLEVOLANTSigValidThresh_Cnt_u16	23914
k_AngleVolantInvalidThresh_Cnt_u16	6689
k_AngleVolantValidThresh_Cnt_u16	44684
k_BSI552MsgTimeout_mS_u16	11551
k_BSINTCEnableTimeout_mS_u16	41007
k_BSINodeAbsentDiag_Cnt_str.Threshold	21092
k_BSINodeAbsentDiag_Cnt_str.PStep	36576
k_BSINodeAbsentDiag_Cnt_str.NStep	12221
k_BSINodeAbsentTimeout_mS_u16	51869
k_BSINodeTimeout_mS_u16	28290
k_BattOvHi_Volt_f32	11.1868
k_BattOvLo_Volt_f32	9.01130009
k_BattUvHi_Volt_f32	12.8898001
k_BattUvLo_Volt_f32	27.5375004
k_CAVNTCEnableTimeout_mS_u16	9314
k_CAVNodeAbsentDiag_Cnt_str.Threshold	51182
k_CAVNodeAbsentDiag_Cnt_str.PStep	10484
k_CAVNodeAbsentDiag_Cnt_str.NStep	59214
k_CAVNodeAbsentTimeout_mS_u16	55207
k_CAVNodeTimeout_mS_u16	29570
k_CMM388MsgTimeout_mS_u16	50704
k_CMM388NTCEnableTimeout_mS_u16	7884
k_CMMNTCEnableTimeout_mS_u16	11344
k_CMMNodeAbsentDiag_Cnt_str.Threshold	52464
k_CMMNodeAbsentDiag_Cnt_str.PStep	43584
k_CMMNodeAbsentDiag_Cnt_str.NStep	41416
k_CMMNodeAbsentTimeout_mS_u16	54372
k_CONSANGLECPKMax_HwDeg_f32	5.42449999
k_CONSANGLECPKMin_HwDeg_f32	-92.571701
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	1603
k_CONSANGLECPKSigValidThresh_Cnt_u16	24744
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	39173
k_CPKVehicleSpeedValidThresh_Cnt_u16	38351
k_CityParkInputInvalidThresh_Cnt_u16	54709
k_CityParkInputValidThresh_Cnt_u16	58665
k_ComputerRazGCTSigValidThresh_Cnt_u16	60318
k_CptTemporelSigValidThresh_Cnt_u16	15071
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	51701
k_DMDFCTCPKSigValidThresh_Cnt_u16	48050
k_DMDFCTCPKValidCount_Cnt_u16	43823
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	21751
k_DMDRELAXECPKSigValidThresh_Cnt_u16	47628
k_DMDRelaxeConsistentThresh_Cnt_u16	22386
k_DateValidThresh_Cnt_u16	63875
k_DefaultVehSpd_Kph_f32	78.8274002
k_DiagMuxOnAbsentTimeout_mS_u16	33356
k_EMNodeTimeout_mS_u16	7739
k_ESPNTCEnableTimeout_mS_u16	51973
k_ESPNodeAbsentDiag_Cnt_str.Threshold	53953
k_ESPNodeAbsentDiag_Cnt_str.PStep	20542
k_ESPNodeAbsentDiag_Cnt_str.NStep	2250
k_ESPNodeAbsentTimeout_mS_u16	25068
k_EtatMTSigInvalidThresh_Cnt_u16	2406
k_EtatMTSigValidThresh_Cnt_u16	56411
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	19608
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	6449
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	34682
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	31501
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	53134
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	37728
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	26732
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	10484

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	52731
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	31642
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	25643
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	37861
k_ISDATDIRASentDiag_Cnt_str.Threshold	51670
k_ISDATDIRASentDiag_Cnt_str.PStep	49599
k_ISDATDIRASentDiag_Cnt_str.NStep	52964
k_ISDATDIRASentTimeout_mS_u16	10123
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	63538
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	60965
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	15313
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	46287
k_ISDYNAASChkSumValidThresh_Cnt_u16	29828
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	49633
k_ISDYNAASMsgCountValidThresh_Cnt_u16	24814
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	63251
k_ISDYNAASMsgLenValidThresh_Cnt_u16	3811
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	6386
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	48211
k_ISDYNABRChkSumValidThresh_Cnt_u16	22672
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	63399
k_ISDYNABRMsgCountValidThresh_Cnt_u16	54932
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	2163
k_ISDYNABRMsgLenValidThresh_Cnt_u16	36923
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	22411
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	36574
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	5805
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	39958
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	2424
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	21285
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	61188
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	50247
k_ISDYNVOLChkSumValidThresh_Cnt_u16	7160
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	61264
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	41416
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	62086
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	40511
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	46041
k_IgnOnTimeout_mS_u16	38403
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	91.0485992
k_PowerCutVehSpdLowThresh_Kph_f32	80.6813965
k_PowerCutVehSpdLowTimeout_mS_u16	49161
k_VBattMaxAAS_Volt_f32	3.95499992
k_VBattMaxBSI_Volt_f32	24.3591995
k_VBattMaxCAV_Volt_f32	27.2915993
k_VBattMaxCMM388_Volt_f32	5.16890001
k_VBattMaxCMM_Volt_f32	32
k_VBattMaxESP_Volt_f32	30.2017002
k_VBattMinAAS_Volt_f32	16.9286003
k_VBattMinBSI_Volt_f32	30.2017002
k_VBattMinCAV_Volt_f32	12.1013002
k_VBattMinCMM388_Volt_f32	2.86520004
k_VBattMinCMM_Volt_f32	4.33769989
k_VBattMinESP_Volt_f32	32
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	26572
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	50733
k_VitesseVehicleBVRampValidThresh_Cnt_u16	2470
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	8225
k_VitesseVehicleBVSigValidThresh_Cnt_u16	12274
k_VitesseVehicleBVSpeedPassThresh_kph_f32	337.151489
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	13385
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	32398
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3785973760
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	215
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16 Elaps	43484
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	723860736
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	11

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	9.97879982
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2361970688
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	57
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.966153979
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	85
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2126151680
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2070192128
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	160
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	727629824
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3601391616
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3309502464
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1059921920
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2355576832
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	48
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	80
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	200
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3311001600
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	46
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	235
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	146
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3012395008
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2948046848
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	523354112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	241
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	243
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2383171584
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2937
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.183862671
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	814687
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	215.225601
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	692

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	723860736	723860736	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	35375	35375	✔
AASNodeAbsentTimer_mS_M_u32	723860736	723860736	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	60965	60965	✔
AngleVolantMsgTimer_mS_M_u32	723860736	723860736	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	723860736	723860736	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	723860736	723860736	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	723860736	723860736	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	723860736	723860736	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21092	21092	✔
BSINodeAbsentTimer_mS_M_u32	723860736	723860736	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	723860736	723860736	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	723860736	723860736	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	723860736	723860736	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	723860736	723860736	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	723860736	723860736	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	9974	9974	✔
CONSANGLECPK_HwDeg_M_f32	442.508606	442.508606 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	9974	9974	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3124015104	3124015104	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	44421	44421	✔
CityParkInputConsistentCount_Cnt_M_u16	58665	58665	✔
CityParkInputInvalidCount_Cnt_M_u16	44686	44686	✔
CityParkInputMsgTimer_mS_M_u32	723860736	723860736	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	723860736	723860736	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	723860736	723860736	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	1	1	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	723860736	723860736	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	723860736	723860736	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	723860736	723860736	✔
ESPNTCEnableTimer_mS_M_u32	723860736	723860736	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	53953	53953	✔
ESPNodeAbsentTimer_mS_M_u32	723860736	723860736	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	89	89	✔
EffacDefaultDiagTimer_mS_M_u32[1]	789	789	✔
ElecIntCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	723860736	723860736	✔
ElecIntTimer_mS_M_u32[1]	104	104	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	723860736	723860736	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	723860736	723860736	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	723860736	723860736	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	723860736	723860736	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	723860736	723860736	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	723860736	723860736	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	723860736	723860736	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	723860736	723860736	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	723860736	723860736	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	723860736	723860736	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	723860736	723860736	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	723860736	723860736	✔
IgnOnTimer_mS_M_u32	723860736	723860736	✔
IgnTimeOff_Sec_M_u32	503306140	503306140	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	85	85	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2126151680	2126151680	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	51	51	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2070192128	2070192128	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	160	160	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	727629824	727629824	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	229	229	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3601391616	3601391616	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3512451072	3512451072	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	202	202	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1059921920	1059921920	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	142	142	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2355576832	2355576832	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	38	38	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3311001600	3311001600	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	146	146	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3012395008	3012395008	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	15	15	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2948046848	2948046848	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	220	220	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	523354112	523354112	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2383171584	2383171584	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	295.238312	295.238312	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	584.50769	584.50769	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	104.825302	104.825302	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	9974	9974	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	503306140	503306140	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	442.508606	442.508606 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.31 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2884989952
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	17471
AASNodeAbsentTimer_mS_M_u32	2878858240
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	49232
ANGLEVOLANTSigValidCount_Cnt_M_u16	27400
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	64996
AngleVolantMsgTimer_mS_M_u32	2884989952
AngleVolantValidCount_Cnt_M_u16	27055
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3137709056
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2847417344
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3145012224
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3318338560
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	52527
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3024196608
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	1659
CAVNodeAbsentTimer_mS_M_u32	1632338944
CDD_SrlComVehSpd_Kph_G_f32	525.965515
CMM388NTCEnableTimer_mS_M_u32	1254736896
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	4153508864
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	5763
CMMNodeAbsentTimer_mS_M_u32	4194554880
CONSANGLECPKSigInvalidCount_Cnt_M_u16	31210
CONSANGLECPKSigValidCount_Cnt_M_u16	22642
CONSANGLECPK_Cnt_M_u16	42773
CONSANGLECPK_HwDeg_M_f32	-458.78299
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	42773
CPKVehicleSpeedMsgTimer_mS_M_u32	3872158720
CPKVehicleSpeedValidCount_Cnt_M_u16	7553
CityParkInputConsistentCount_Cnt_M_u16	20531
CityParkInputInvalidCount_Cnt_M_u16	52378
CityParkInputMsgTimer_mS_M_u32	3417298176
CityParkInputValidCount_Cnt_M_u16	10

Name	Input Value
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	857465856
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	45251
ComputerRazGCTSigInvalidTimer_mS_M_u32	2927625216
ComputerRazGCTSigValidCount_Cnt_M_u16	50512
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	8726
DMDFCTCPKSigValidCount_Cnt_M_u16	57206
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	58002
DMDRELAXECPKSigValidCount_Cnt_M_u16	6858
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	38031
DateInvalidTimer_mS_M_u32	2847417344
DiagMuxOnAbsentTimer_mS_M_u32	3024958464
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3318338560
ESPNTCEnableTimer_mS_M_u32	3732988928
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	10263
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	41
EffacDefaultDiagTimer_mS_M_u32[1]	704188672
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	660
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	132355072
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	11295
EtatMTSigValidCount_Cnt_M_u16	30626
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	57900
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	52788
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	16316
ISDAT4V2BSI552MsgTimer_mS_M_u32	3699889152
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	4267
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	28343
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	30626
ISDATBSI3F2MsgTimer_mS_M_u32	604713984
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	2371
ISDATBSI412MsgLenValidCount_Cnt_M_u16	54527
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	11295
ISDATBSI412MsgTimer_mS_M_u32	296973312
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	37895
ISDATBSI432MsgLenValidCount_Cnt_M_u16	32923
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	15748
ISDATDIRASentFltAcc_Cnt_M_u16	14488
ISDATDIRASentTimer_mS_M_u32	3872158720
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	2387
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	27055
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	58485
ISDYN2CMMMsgTimer_mS_M_u32	3006981120
ISDYNAASChkSumInvalidCount_Cnt_M_u16	21121
ISDYNAASChkSumValidCount_Cnt_M_u16	18265
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	8718
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	33630
ISDYNAASMsgLenValidCount_Cnt_M_u16	53870
ISDYNAASMsgTimeValidCount_Cnt_M_u16	21121
ISDYNAASMsgTimer_mS_M_u32	759546880
ISDYNABRChkSumInvalidCount_Cnt_M_u16	5284
ISDYNABRChkSumValidCount_Cnt_M_u16	38884
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	16736
ISDYNABRMsgCountValidCount_Cnt_M_u16	61304
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	58313
ISDYNABRMsgLenValidCount_Cnt_M_u16	48017
ISDYNABRMsgTimeValidCount_Cnt_M_u16	42773
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	596
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1077
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	30626
ISDYNCMM208MsgTimer_mS_M_u32	3462571008

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2235
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1183
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	61037
ISDYNCMM388MsgTimer_mS_M_u32	3222619136
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	25000
ISDYNVOLChkSumValidCount_Cnt_M_u16	12976
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	50388
ISDYNVOLMsgCountValidCount_Cnt_M_u16	46260
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	41016
ISDYNVOLMsgLenValidCount_Cnt_M_u16	38048
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	5763
ISDYNVOLMsgTimer_mS_M_u32	486278144
IgnOnTimer_mS_M_u32	3046720512
IgnTimeOff_Sec_M_u32	1228912432
ManVehSpd_Kph_M_f32	217.489304
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	150
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	115
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	422654976
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	140
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3761509376
PrevISDATBSI412MsgDLCError_Cnt_M_u08	120
PrevISDATBSI412MsgRxTime_MSec_M_u32	4245980160
PrevISDATBSI432MsgDLCError_Cnt_M_u08	82
PrevISDATBSI432MsgRxTime_MSec_M_u32	318039040
PrevISDATDIRAMsgTxTime_MSec_M_u32	3743974400
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	32
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2912637952
PrevISDYNAASMsgDLCError_Cnt_M_u08	23
PrevISDYNAASMsgRxTime_MSec_M_u32	121242624
PrevISDYNABRMsgDLCError_Cnt_M_u08	248
PrevISDYNABRMsgRxTime_MSec_M_u32	1167148032
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	116
PrevISDYNCMM208MsgRxTime_MSec_M_u32	605488128
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	107
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1721230336
PrevISDYNVOLMsgDLCError_Cnt_M_u08	105
PrevISDYNVOLMsgRxTime_MSec_M_u32	1602847744
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1114731520
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	535.084106
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	7196
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	7596
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	17853
VitesseVehicleBVRampValidCount_Cnt_M_u16	60941
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	51057
VitesseVehicleBVSigValidCount_Cnt_M_u16	14569
VitesseVehicleBV_Kph_M_f32	614.560303
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	61037
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	25437

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	438.190704
k_AASNTCEnableTimeout_mS_u16	37420
k_AASNodeAbsentDiag_Cnt_str.Threshold	29189
k_AASNodeAbsentDiag_Cnt_str.PStep	6588
k_AASNodeAbsentDiag_Cnt_str.NStep	11282
k_AASNodeAbsentTimeout_mS_u16	50826
k_AASNodeTimeout_mS_u16	22700
k_ABSNodeTimeout_mS_u16	44851
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	58402
k_ANGLEVOLANTSigValidThresh_Cnt_u16	16118
k_AngleVolantInvalidThresh_Cnt_u16	9437
k_AngleVolantValidThresh_Cnt_u16	52378
k_BSI552MsgTimeout_mS_u16	32772
k_BSINTCEnableTimeout_mS_u16	5119
k_BSINodeAbsentDiag_Cnt_str.Threshold	21252
k_BSINodeAbsentDiag_Cnt_str.PStep	36508
k_BSINodeAbsentDiag_Cnt_str.NStep	12313
k_BSINodeAbsentTimeout_mS_u16	16348
k_BSINodeTimeout_mS_u16	15748
k_BattOvHi_Volt_f32	31.3092003
k_BattOvLo_Volt_f32	31.5
k_BattUvHi_Volt_f32	8.02330017
k_BattUvLo_Volt_f32	19.7882004
k_CAVNTCEnableTimeout_mS_u16	62800
k_CAVNodeAbsentDiag_Cnt_str.Threshold	60748
k_CAVNodeAbsentDiag_Cnt_str.PStep	47786
k_CAVNodeAbsentDiag_Cnt_str.NStep	7289
k_CAVNodeAbsentTimeout_mS_u16	4665
k_CAVNodeTimeout_mS_u16	5222
k_CMM388MsgTimeout_mS_u16	48959
k_CMM388NTCEnableTimeout_mS_u16	37563
k_CMMNTCEnableTimeout_mS_u16	19619
k_CMMNodeAbsentDiag_Cnt_str.Threshold	42643
k_CMMNodeAbsentDiag_Cnt_str.PStep	51758
k_CMMNodeAbsentDiag_Cnt_str.NStep	11911
k_CMMNodeAbsentTimeout_mS_u16	64729
k_CONSANGLECPKMax_HwDeg_f32	647.229797
k_CONSANGLECPKMin_HwDeg_f32	-649.592285
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	59757
k_CONSANGLECPKSigValidThresh_Cnt_u16	40541
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	11250
k_CPKVehicleSpeedValidThresh_Cnt_u16	12774
k_CityParkInputInvalidThresh_Cnt_u16	22634
k_CityParkInputValidThresh_Cnt_u16	20531
k_ComputerRazGCTSigValidThresh_Cnt_u16	13393
k_CptTemporelSigValidThresh_Cnt_u16	8925
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	24265
k_DMDFCTCPKSigValidThresh_Cnt_u16	30353
k_DMDFCTCPKValidCount_Cnt_u16	38455
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	58485
k_DMDRELAXECPKSigValidThresh_Cnt_u16	64277
k_DMDRelaxeConsistentThresh_Cnt_u16	43099
k_DateValidThresh_Cnt_u16	16316
k_DefaultVehSpd_Kph_f32	135.146805
k_DiagMuxOnAbsentTimeout_mS_u16	27979
k_EMNodeTimeout_mS_u16	59631
k_ESPNTCEnableTimeout_mS_u16	29431
k_ESPNodeAbsentDiag_Cnt_str.Threshold	20816
k_ESPNodeAbsentDiag_Cnt_str.PStep	1852
k_ESPNodeAbsentDiag_Cnt_str.NStep	16796
k_ESPNodeAbsentTimeout_mS_u16	17633
k_EtatMTSigInvalidThresh_Cnt_u16	0
k_EtatMTSigValidThresh_Cnt_u16	56811
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	60789
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	1241
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	64468
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	18032
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	56892
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	48327
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	32588
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	50592
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	20875
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	44793

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	8149
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	64159
k_ISDATDIRASentDiag_Cnt_str.Threshold	18837
k_ISDATDIRASentDiag_Cnt_str.PStep	50375
k_ISDATDIRASentDiag_Cnt_str.NStep	34001
k_ISDATDIRASentTimeout_mS_u16	7456
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	50940
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	64996
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	58243
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	4004
k_ISDYNAASChkSumValidThresh_Cnt_u16	53988
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	48224
k_ISDYNAASMsgCountValidThresh_Cnt_u16	43640
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	18216
k_ISDYNAASMsgLenValidThresh_Cnt_u16	55088
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	5374
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	28295
k_ISDYNABRChkSumValidThresh_Cnt_u16	30927
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	18479
k_ISDYNABRMsgCountValidThresh_Cnt_u16	27687
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	20867
k_ISDYNABRMsgLenValidThresh_Cnt_u16	41751
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	27214
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	15008
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	22564
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	29779
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	15184
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	9736
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	45714
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	26078
k_ISDYNVOLChkSumValidThresh_Cnt_u16	65498
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	18620
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	25960
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	9627
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	54814
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	5362
k_IgnOnTimeout_mS_u16	33370
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	119.063301
k_PowerCutVehSpdLowThresh_Kph_f32	207.321106
k_PowerCutVehSpdLowTimeout_mS_u16	1560
k_VBattMaxAAS_Volt_f32	2.4855001
k_VBattMaxBSI_Volt_f32	17.8633995
k_VBattMaxCAV_Volt_f32	17.8134003
k_VBattMaxCMM388_Volt_f32	4.00610018
k_VBattMaxCMM_Volt_f32	16.7914009
k_VBattMaxESP_Volt_f32	14.7958002
k_VBattMinAAS_Volt_f32	0.833899975
k_VBattMinBSI_Volt_f32	14.7958002
k_VBattMinCAV_Volt_f32	20.1275997
k_VBattMinCMM388_Volt_f32	10.6346998
k_VBattMinCMM_Volt_f32	5.23719978
k_VBattMinESP_Volt_f32	6.79139996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	14006
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	61026
k_VitesseVehicleBVRampValidThresh_Cnt_u16	49108
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	60848
k_VitesseVehicleBVSigValidThresh_Cnt_u16	51660
k_VitesseVehicleBVSpeedPassThresh_kph_f32	168.917999
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	379
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	40011
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2847417344
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	202
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	31029
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	704188672
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	107
target_SrlComInput_Per1_Batt_Volt_f32.value	10.5480003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2980746240
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	91
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.32914418
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2518893568
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	145
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2448909312
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	177
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1243317248
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	243
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2257560576
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	257147904
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	32
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2892489728
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	634127360
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	86
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	122
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	137
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	149
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	207
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	248
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1552983040
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	175
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	189
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	11
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1021723648
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	272262144
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1608418304
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	71
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	85
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	155
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	183
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	223
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2953188352
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1668
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.822472572
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	797522
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	26.4004993
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	49494

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	704188672	704188672	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	29189	29189	✔
AASNodeAbsentTimer_mS_M_u32	704188672	704188672	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	64996	64996	✔
AngleVolantMsgTimer_mS_M_u32	704188672	704188672	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	704188672	704188672	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	704188672	704188672	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	704188672	704188672	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	704188672	704188672	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21252	21252	✔
BSINodeAbsentTimer_mS_M_u32	704188672	704188672	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	704188672	704188672	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	704188672	704188672	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	704188672	704188672	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4153508864	4153508864	✔
CMMNTCsEnabled_Cnt_M_lgc	1	1	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	704188672	704188672	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	42773	42773	✔
CONSANGLECPK_HwDeg_M_f32	-458.78299	-458.78299 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	42773	42773	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3872158720	3872158720	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	7553	7553	✔
CityParkInputConsistentCount_Cnt_M_u16	20531	20531	✔
CityParkInputInvalidCount_Cnt_M_u16	52378	52378	✔
CityParkInputMsgTimer_mS_M_u32	704188672	704188672	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	704188672	704188672	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	704188672	704188672	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	1	1	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	704188672	704188672	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	704188672	704188672	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	704188672	704188672	✔
ESPNTCEnableTimer_mS_M_u32	704188672	704188672	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	20816	20816	✔
ESPNodeAbsentTimer_mS_M_u32	704188672	704188672	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	41	41	✔
EffacDefaultDiagTimer_mS_M_u32[1]	704188672	704188672	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	704188672	704188672	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	660	660	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	704188672	704188672	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	11295	11295	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	704188672	704188672	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	704188672	704188672	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	704188672	704188672	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	704188672	704188672	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	704188672	704188672	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2892489728	2892489728	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	704188672	704188672	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	704188672	704188672	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	597	597	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1021723648	1021723648	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	704188672	704188672	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	704188672	704188672	✔
IgnOnTimer_mS_M_u32	3046720512	3046720512	✔
IgnTimeOff_Sec_M_u32	1228912432	1228912432	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	200	200	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2518893568	2518893568	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	145	145	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2448909312	2448909312	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	177	177	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1243317248	1243317248	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	243	243	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2257560576	2257560576	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3743974400	3743974400	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	32	32	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2892489728	2892489728	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	634127360	634127360	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	248	248	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1552983040	1552983040	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	11	11	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1021723648	1021723648	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	75	75	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	272262144	272262144	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1608418304	1608418304	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2953188352	2953188352	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	535.084106	535.084106	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	614.560303	614.560303	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	438.190704	438.190704	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	42773	42773	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1228912432	1228912432	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-458.78299	-458.78299 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	135.146805	135.146805	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0121	0x0121	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0129	0x0129	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x012C	0x012C	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.32 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2525914880
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	6062
AASNodeAbsentTimer_mS_M_u32	1835472640
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	34173
ANGLEVOLANTSigValidCount_Cnt_M_u16	37141
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	48831
AngleVolantMsgTimer_mS_M_u32	2525914880
AngleVolantValidCount_Cnt_M_u16	52193
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	639489792
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1141266176
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1854899968
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2458994432
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	39648
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1445594880
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	51068
CAVNodeAbsentTimer_mS_M_u32	583808768
CDD_SrlComVehSpd_Kph_G_f32	269.809998
CMM388NTCEnableTimer_mS_M_u32	793868032
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4160370432
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	13347
CMMNodeAbsentTimer_mS_M_u32	1575175936

Name	Input Value
CONSANGLECPKSigInvalidCount_Cnt_M_u16	61360
CONSANGLECPKSigValidCount_Cnt_M_u16	40920
CONSANGLECPK_Cnt_M_u16	65519
CONSANGLECPK_HwDeg_M_f32	-769.961121
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	65519
CPKVehicleSpeedMsgTimer_mS_M_u32	34170624
CPKVehicleSpeedValidCount_Cnt_M_u16	33362
CityParkInputConsistentCount_Cnt_M_u16	10325
CityParkInputInvalidCount_Cnt_M_u16	24607
CityParkInputMsgTimer_mS_M_u32	2518893568
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3873117952
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	57890
ComputerRazGCTSigInvalidTimer_mS_M_u32	2905519872
ComputerRazGCTSigValidCount_Cnt_M_u16	31998
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	20395
DMDFCTCPKSigValidCount_Cnt_M_u16	49995
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	42679
DMDRELAXECPKSigValidCount_Cnt_M_u16	2511
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	29633
DateInvalidTimer_mS_M_u32	1141266176
DiagMuxOnAbsentTimer_mS_M_u32	2357667584
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2458994432
ESPNTCEnableTimer_mS_M_u32	3098285824
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	31527
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	3
EffacDefaultDiagTimer_mS_M_u32[1]	6
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1100
ElecIntTimer_mS_M_u32[1]	1150
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1665402624
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	28753
EtatMTSigValidCount_Cnt_M_u16	51589
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	16106
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	50834
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	14969
ISDAT4V2BSI552MsgTimer_mS_M_u32	3327608576
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	60460
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	11720
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	51589
ISDATBSI3F2MsgTimer_mS_M_u32	3041732352
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	45923
ISDATBSI412MsgLenValidCount_Cnt_M_u16	27632
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	28753
ISDATBSI412MsgTimer_mS_M_u32	3713296128
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	52119
ISDATBSI432MsgLenValidCount_Cnt_M_u16	33179
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	34401
ISDATDIRASentFltAcc_Cnt_M_u16	58661
ISDATDIRASentTimer_mS_M_u32	34170624
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	20789
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	52193
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	17550
ISDYN2CMMMsgTimer_mS_M_u32	2726172416
ISDYNAASChkSumInvalidCount_Cnt_M_u16	29928
ISDYNAASChkSumValidCount_Cnt_M_u16	8737
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	57028
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	40147
ISDYNAASMsgLenValidCount_Cnt_M_u16	7011
ISDYNAASMsgTimeValidCount_Cnt_M_u16	29928
ISDYNAASMsgTimer_mS_M_u32	2011002624

Name	Input Value
ISDYNABRChkSumInvalidCount_Cnt_M_u16	53760
ISDYNABRChkSumValidCount_Cnt_M_u16	29696
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	58443
ISDYNABRMsgCountValidCount_Cnt_M_u16	26052
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	60947
ISDYNABRMsgLenValidCount_Cnt_M_u16	45691
ISDYNABRMsgTimeValidCount_Cnt_M_u16	65519
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	597
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1079
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	51589
ISDYNCMM208MsgTimer_mS_M_u32	2684802816
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2239
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1185
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	46503
ISDYNCMM388MsgTimer_mS_M_u32	1567553280
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	45174
ISDYNVOLChkSumValidCount_Cnt_M_u16	35102
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	57201
ISDYNVOLMsgCountValidCount_Cnt_M_u16	48017
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	54980
ISDYNVOLMsgLenValidCount_Cnt_M_u16	50508
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	13347
ISDYNVOLMsgTimer_mS_M_u32	1371191040
IgnOnTimer_mS_M_u32	2363684608
IgnTimeOff_Sec_M_u32	1127454712
ManVehSpd_Kph_M_f32	553.640686
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	152
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	138
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3990562560
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	213
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3159525120
PrevISDATBSI412MsgDLCError_Cnt_M_u08	187
PrevISDATBSI412MsgRxTime_MSec_M_u32	3010541312
PrevISDATBSI432MsgDLCError_Cnt_M_u08	20
PrevISDATBSI432MsgRxTime_MSec_M_u32	3947894528
PrevISDATDIRAMsgTxTime_MSec_M_u32	1563768576
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	132
PrevISDYN2CMMMsgRxTime_MSec_M_u32	18663168
PrevISDYNAASMsgDLCError_Cnt_M_u08	89
PrevISDYNAASMsgRxTime_MSec_M_u32	184596224
PrevISDYNABRMsgDLCError_Cnt_M_u08	44
PrevISDYNABRMsgRxTime_MSec_M_u32	3170563840
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	87
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1751758592
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	5
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1013389056
PrevISDYNVOLMsgDLCError_Cnt_M_u08	3
PrevISDYNVOLMsgRxTime_MSec_M_u32	2685548288
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3273287424
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	473.1987
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	19097
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	45481
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	8

Name	Input Value
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	37302
VitesseVehicleBVRampValidCount_Cnt_M_u16	1158
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	13338
VitesseVehicleBVSigValidCount_Cnt_M_u16	60274
VitesseVehicleBV_Kph_M_f32	27.1000996
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	46503
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	17047
VitesseVehiculeRoues_Kph_M_f32	590.820618
k_AASNTCEnableTimeout_mS_u16	23210
k_AASNodeAbsentDiag_Cnt_str.Threshold	6851
k_AASNodeAbsentDiag_Cnt_str.PStep	7318
k_AASNodeAbsentDiag_Cnt_str.NStep	61132
k_AASNodeAbsentTimeout_mS_u16	57680
k_AASNodeTimeout_mS_u16	169
k_ABSNodeTimeout_mS_u16	23636
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	1862
k_ANGLEVOLANTSigValidThresh_Cnt_u16	29322
k_AngleVolantInvalidThresh_Cnt_u16	7381
k_AngleVolantValidThresh_Cnt_u16	24607
k_BSI552MsgTimeout_mS_u16	18594
k_BSINTCEnableTimeout_mS_u16	11183
k_BSINodeAbsentDiag_Cnt_str.Threshold	21292
k_BSINodeAbsentDiag_Cnt_str.PStep	36491
k_BSINodeAbsentDiag_Cnt_str.NStep	12336
k_BSINodeAbsentTimeout_mS_u16	55511
k_BSINodeTimeout_mS_u16	34401
k_BattOvHi_Volt_f32	24.3523998
k_BattOvLo_Volt_f32	4.52169991
k_BattUvHi_Volt_f32	28.2579994
k_BattUvLo_Volt_f32	20.8610992
k_CAVNTCEnableTimeout_mS_u16	15869
k_CAVNodeAbsentDiag_Cnt_str.Threshold	9094
k_CAVNodeAbsentDiag_Cnt_str.PStep	55202
k_CAVNodeAbsentDiag_Cnt_str.NStep	1196
k_CAVNodeAbsentTimeout_mS_u16	7234
k_CAVNodeTimeout_mS_u16	4156
k_CMM388MsgTimeout_mS_u16	42670
k_CMM388NTCEnableTimeout_mS_u16	7226
k_CMMNTCEnableTimeout_mS_u16	6212
k_CMMNodeAbsentDiag_Cnt_str.Threshold	60663
k_CMMNodeAbsentDiag_Cnt_str.PStep	23582
k_CMMNodeAbsentDiag_Cnt_str.NStep	4429
k_CMMNodeAbsentTimeout_mS_u16	26147
k_CONSANGLECPKMax_HwDeg_f32	597.880493
k_CONSANGLECPKMin_HwDeg_f32	-548.306396
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	50343
k_CONSANGLECPKSigValidThresh_Cnt_u16	37271
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	7895
k_CPKVehicleSpeedValidThresh_Cnt_u16	34170
k_CityParkInputInvalidThresh_Cnt_u16	40622
k_CityParkInputValidThresh_Cnt_u16	10325
k_ComputerRazGCTSigValidThresh_Cnt_u16	39226
k_CptTemporelSigValidThresh_Cnt_u16	10582
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	32019
k_DMDFCTCPKSigValidThresh_Cnt_u16	33147
k_DMDFCTCPKValidCount_Cnt_u16	24520
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	17550
k_DMDRELAXECPKSigValidThresh_Cnt_u16	44142
k_DMDRelaxeConsistentThresh_Cnt_u16	15516
k_DateValidThresh_Cnt_u16	14969
k_DefaultVehSpd_Kph_f32	109.492302
k_DiagMuxOnAbsentTimeout_mS_u16	1357
k_EMNodeTimeout_mS_u16	63137
k_ESPNTCEnableTimeout_mS_u16	29192
k_ESPNodeAbsentDiag_Cnt_str.Threshold	36385
k_ESPNodeAbsentDiag_Cnt_str.PStep	6996
k_ESPNodeAbsentDiag_Cnt_str.NStep	31597
k_ESPNodeAbsentTimeout_mS_u16	44555

Name	Input Value
k_EtatMTSigInvalidThresh_Cnt_u16	65535
k_EtatMTSigValidThresh_Cnt_u16	32235
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	42574
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	7138
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	59762
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	40669
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	13113
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	43223
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	24008
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	1676
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	41739
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	30787
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	49519
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	41039
k_ISDATDIRASentDiag_Cnt_str.Threshold	48425
k_ISDATDIRASentDiag_Cnt_str.PStep	29644
k_ISDATDIRASentDiag_Cnt_str.NStep	12838
k_ISDATDIRASentTimeout_mS_u16	43148
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	61240
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	48831
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	20580
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	57600
k_ISDYNAASChkSumValidThresh_Cnt_u16	49920
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	29515
k_ISDYNAASMsgCountValidThresh_Cnt_u16	13508
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	19060
k_ISDYNAASMsgLenValidThresh_Cnt_u16	38173
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	4210
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	50649
k_ISDYNABRChkSumValidThresh_Cnt_u16	62145
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	10720
k_ISDYNABRMsgCountValidThresh_Cnt_u16	51640
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	33571
k_ISDYNABRMsgLenValidThresh_Cnt_u16	2599
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	11075
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	65293
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	35520
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	2484
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	5245
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	24597
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	36407
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	51602
k_ISDYNVOLChkSumValidThresh_Cnt_u16	5983
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	60728
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	7028
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	29661
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	40465
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	4823
k_IgnOnTimeout_mS_u16	25630
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	16.2427998
k_PowerCutVehSpdLowThresh_Kph_f32	143.469299
k_PowerCutVehSpdLowTimeout_mS_u16	44774
k_VBattMaxAAS_Volt_f32	14.8355999
k_VBattMaxBSI_Volt_f32	8.72719955
k_VBattMaxCAV_Volt_f32	5.55810022
k_VBattMaxCMM388_Volt_f32	0.380199999
k_VBattMaxCMM_Volt_f32	24.2187004
k_VBattMaxESP_Volt_f32	28.6616001
k_VBattMinAAS_Volt_f32	17.1800995
k_VBattMinBSI_Volt_f32	28.6616001
k_VBattMinCAV_Volt_f32	31.0674992
k_VBattMinCMM388_Volt_f32	8.8217001
k_VBattMinCMM_Volt_f32	2.02099991
k_VBattMinESP_Volt_f32	24.2187004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	2058
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	48326
k_VitesseVehicleBVRampValidThresh_Cnt_u16	61041
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	22558
k_VitesseVehicleBVSigValidThresh_Cnt_u16	24458
k_VitesseVehicleBVSpeedPassThresh_kph_f32	290.423889
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	54908
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	29132

Name	Input Value
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1141266176
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	248
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	37882
target Rte Call Ap SrlComInput SystemTime GetSystemTime mS u32 CurrentT	993497088
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target Rte Inst Ap SrlComInput.SrlComInput Per1 ISDATBSI432MsgRxTime MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target Rte Inst Ap SrlComInput.SrlComInput Per1 ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target Rte Inst Ap SrlComInput.SrlComInput Per1 ISDYNABRMsgRxTime MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target Rte Inst Ap SrlComInput.SrlComInput Per1 ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target Rte Inst Ap SrlComInput.SrlComInput Per1 RxMsgsSrlComSvcDft Cnt lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	5
target_SrlComInput_Per1_Batt_Volt_f32.value	29.0974998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1106183936
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	40
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.682431698
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	248
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2470770432
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2554894080
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	44
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2824615680
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	65
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1803540224
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2310240000
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2868320000
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2001385216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	34
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	107
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	178
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	763156224
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	153
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	161
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	207
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	230
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1794897664
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	147
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3917453056
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	856897280
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	50
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	55
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	161
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	214
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	349996800
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3322

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.812502384
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	972190
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	35.4813004
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	49899

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	993497088	993497088	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	993497088	993497088	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	993497088	993497088	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	993497088	993497088	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	993497088	993497088	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	993497088	993497088	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	993497088	993497088	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21292	21292	✔
BSINodeAbsentTimer_mS_M_u32	993497088	993497088	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	993497088	993497088	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	9094	9094	✔
CAVNodeAbsentTimer_mS_M_u32	993497088	993497088	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	993497088	993497088	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	993497088	993497088	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	8918	8918	✔
CMMNodeAbsentTimer_mS_M_u32	2868320000	2868320000	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	65519	65519	✔
CONSANGLECPK_HwDeg_M_f32	-769.961121	-769.961121 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	993497088	993497088	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	993497088	993497088	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	993497088	993497088	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	993497088	993497088	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	1	1	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	993497088	993497088	✔
DateValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DiagMuxOnAbsentTimer_mS_M_u32	993497088	993497088	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	993497088	993497088	✔
ESPNTCEnableTimer_mS_M_u32	993497088	993497088	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	993497088	993497088	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3	3	✔
EffacDefaultDiagTimer_mS_M_u32[1]	6	6	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	993497088	993497088	✔
ElecIntTimer_mS_M_u32[1]	1150	1150	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	993497088	993497088	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	993497088	993497088	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	993497088	993497088	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	993497088	993497088	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	993497088	993497088	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	993497088	993497088	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	993497088	993497088	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	993497088	993497088	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	993497088	993497088	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	993497088	993497088	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	993497088	993497088	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	993497088	993497088	✔
IgnOnTimer_mS_M_u32	2363684608	2363684608	✔
IgnTimeOff_Sec_M_u32	1127454712	1127454712	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	248	248	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2470770432	2470770432	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	246	246	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2554894080	2554894080	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	44	44	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2824615680	2824615680	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	65	65	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1803540224	1803540224	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1563768576	1563768576	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	132	132	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2868320000	2868320000	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2001385216	2001385216	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	118	118	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	763156224	763156224	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	251	251	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1794897664	1794897664	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	147	147	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3917453056	3917453056	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	34	34	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	856897280	856897280	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	349996800	349996800	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	473.1987	473.1987	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	27.1000996	27.1000996	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	590.820618	590.820618	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	65519	65519	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1127454712	1127454712	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-769.961121	-769.961121 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	109.492302	109.492302	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.33 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2656013824
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	15598
AASNodeAbsentTimer_mS_M_u32	2558885376
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	19842
ANGLEVOLANTSigValidCount_Cnt_M_u16	1913
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	52155
AngleVolantMsgTimer_mS_M_u32	2656013824
AngleVolantValidCount_Cnt_M_u16	45782
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3110157824
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2712124928
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	46935552
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3452366336
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	22873
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3590106624
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	18950
CAVNodeAbsentTimer_mS_M_u32	4107673088
CDD_SrlComVehSpd_Kph_G_f32	337.189606
CMM388NTCEnableTimer_mS_M_u32	1950768640
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2907446784
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	11728
CMMNodeAbsentTimer_mS_M_u32	869330432
CONSANGLECPKSigInvalidCount_Cnt_M_u16	18922
CONSANGLECPKSigValidCount_Cnt_M_u16	22065
CONSANGLECPK_Cnt_M_u16	20972
CONSANGLECPK_HwDeg_M_f32	-308.709106
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	20972
CPKVehicleSpeedMsgTimer_mS_M_u32	132025856
CPKVehicleSpeedValidCount_Cnt_M_u16	47563
CityParkInputConsistentCount_Cnt_M_u16	28026
CityParkInputInvalidCount_Cnt_M_u16	48923

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	2470770432
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4230577664
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	44434
ComputerRazGCTSigInvalidTimer_mS_M_u32	4289633792
ComputerRazGCTSigValidCount_Cnt_M_u16	21375
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	8311
DMDFCTCPKSigValidCount_Cnt_M_u16	49750
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	20948
DMDRELAXECPKSigValidCount_Cnt_M_u16	1355
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	16823
DateInvalidTimer_mS_M_u32	2712124928
DiagMuxOnAbsentTimer_mS_M_u32	2405780992
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3452366336
ESPNTCEnableTimer_mS_M_u32	179731968
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	58755
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	9
EffacDefaultDiagTimer_mS_M_u32[1]	81
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2050
ElecIntTimer_mS_M_u32[1]	6070
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2528030208
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	581
EtatMTSigValidCount_Cnt_M_u16	17257
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	50236
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	18947
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	38092
ISDAT4V2BSI552MsgTimer_mS_M_u32	3396660736
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	4660
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	14880
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	17257
ISDATBSI3F2MsgTimer_mS_M_u32	2903723520
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	43407
ISDATBSI412MsgLenValidCount_Cnt_M_u16	11434
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	581
ISDATBSI412MsgTimer_mS_M_u32	1644006912
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	14196
ISDATBSI432MsgLenValidCount_Cnt_M_u16	41511
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	57687
ISDATDIRASentFltAcc_Cnt_M_u16	54539
ISDATDIRASentTimer_mS_M_u32	132025856
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	63002
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	45782
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36302
ISDYN2CMMMsgTimer_mS_M_u32	356548096
ISDYNAASChkSumInvalidCount_Cnt_M_u16	36160
ISDYNAASChkSumValidCount_Cnt_M_u16	57943
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	50733
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	58881
ISDYNAASMsgLenValidCount_Cnt_M_u16	10001
ISDYNAASMsgTimeValidCount_Cnt_M_u16	36160
ISDYNAASMsgTimer_mS_M_u32	3399638528
ISDYNABRChkSumInvalidCount_Cnt_M_u16	35705
ISDYNABRChkSumValidCount_Cnt_M_u16	8761
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	35607
ISDYNABRMsgCountValidCount_Cnt_M_u16	25454
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	39617
ISDYNABRMsgLenValidCount_Cnt_M_u16	27208
ISDYNABRMsgTimeValidCount_Cnt_M_u16	20972
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	598
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1081

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	17257
ISDYNCMM208MsgTimer_mS_M_u32	799424000
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2243
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1187
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	36228
ISDYNCMM388MsgTimer_mS_M_u32	1072553472
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	40856
ISDYNVOLChkSumValidCount_Cnt_M_u16	12895
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	2341
ISDYNVOLMsgCountValidCount_Cnt_M_u16	29060
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	34476
ISDYNVOLMsgLenValidCount_Cnt_M_u16	22484
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	11728
ISDYNVOLMsgTimer_mS_M_u32	1107992064
IgnOnTimer_mS_M_u32	2173820416
IgnTimeOff_Sec_M_u32	1898983744
ManVehSpd_Kph_M_f32	97.8115997
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	154
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	226
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3144240640
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	68
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3850579456
PrevISDATBSI412MsgDLCError_Cnt_M_u08	150
PrevISDATBSI412MsgRxTime_MSec_M_u32	384245248
PrevISDATBSI432MsgDLCError_Cnt_M_u08	206
PrevISDATBSI432MsgRxTime_MSec_M_u32	46824960
PrevISDATDIRAMsgTxTime_MSec_M_u32	698031616
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	239
PrevISDYN2CMMMsgRxTime_MSec_M_u32	270822912
PrevISDYNAASMsgDLCError_Cnt_M_u08	71
PrevISDYNAASMsgRxTime_MSec_M_u32	2922946048
PrevISDYNABRMsgDLCError_Cnt_M_u08	106
PrevISDYNABRMsgRxTime_MSec_M_u32	1363795456
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	9
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2046664192
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	68
PrevISDYNCMM388MsgRxTime_MSec_M_u32	730168832
PrevISDYNVOLMsgDLCError_Cnt_M_u08	108
PrevISDYNVOLMsgRxTime_MSec_M_u32	352591360
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1219202560
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	347.470001
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	29871
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	64575
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	21336
VitesseVehicleBVRampValidCount_Cnt_M_u16	47016
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	62891
VitesseVehicleBVSigValidCount_Cnt_M_u16	44130
VitesseVehicleBV_Kph_M_f32	339.756012

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	36228
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	9075
VitesseVehiculeRoues_Kph_M_f32	513.779602
k_AASNTCEnableTimeout_mS_u16	60859
k_AASNodeAbsentDiag_Cnt_str.Threshold	7813
k_AASNodeAbsentDiag_Cnt_str.PStep	3619
k_AASNodeAbsentDiag_Cnt_str.NStep	23512
k_AASNodeAbsentTimeout_mS_u16	61065
k_AASNodeTimeout_mS_u16	3903
k_ABSNodeTimeout_mS_u16	56956
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	103
k_ANGLEVOLANTSigValidThresh_Cnt_u16	19290
k_AngleVolantInvalidThresh_Cnt_u16	14457
k_AngleVolantValidThresh_Cnt_u16	48923
k_BSI552MsgTimeout_mS_u16	64850
k_BSINTCEnableTimeout_mS_u16	30508
k_BSINodeAbsentDiag_Cnt_str.Threshold	21332
k_BSINodeAbsentDiag_Cnt_str.PStep	36474
k_BSINodeAbsentDiag_Cnt_str.NStep	12359
k_BSINodeAbsentTimeout_mS_u16	56691
k_BSINodeTimeout_mS_u16	57687
k_BattOvHi_Volt_f32	0.85860002
k_BattOvLo_Volt_f32	18.9323997
k_BattUvHi_Volt_f32	24.4981995
k_BattUvLo_Volt_f32	27.9951
k_CAVNTCEnableTimeout_mS_u16	7553
k_CAVNodeAbsentDiag_Cnt_str.Threshold	62578
k_CAVNodeAbsentDiag_Cnt_str.PStep	25462
k_CAVNodeAbsentDiag_Cnt_str.NStep	50415
k_CAVNodeAbsentTimeout_mS_u16	58292
k_CAVNodeTimeout_mS_u16	6214
k_CMM388MsgTimeout_mS_u16	36846
k_CMM388NTCEnableTimeout_mS_u16	24394
k_CMMNTCEnableTimeout_mS_u16	6908
k_CMMNodeAbsentDiag_Cnt_str.Threshold	55367
k_CMMNodeAbsentDiag_Cnt_str.PStep	56555
k_CMMNodeAbsentDiag_Cnt_str.NStep	63157
k_CMMNodeAbsentTimeout_mS_u16	59599
k_CONSANGLECPKMax_HwDeg_f32	109.983704
k_CONSANGLECPKMin_HwDeg_f32	-69.4957962
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	24708
k_CONSANGLECPKSigValidThresh_Cnt_u16	13939
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	60597
k_CPKVehicleSpeedValidThresh_Cnt_u16	20298
k_CityParkInputInvalidThresh_Cnt_u16	23919
k_CityParkInputValidThresh_Cnt_u16	28026
k_ComputerRazGCTSigValidThresh_Cnt_u16	49930
k_CptTemporelSigValidThresh_Cnt_u16	65398
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	60865
k_DMDFCTCPKSigValidThresh_Cnt_u16	64840
k_DMDFCTCPKValidCount_Cnt_u16	43681
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	36302
k_DMDRELAXECPKSigValidThresh_Cnt_u16	21229
k_DMDRelaxeConsistentThresh_Cnt_u16	55907
k_DateValidThresh_Cnt_u16	38092
k_DefaultVehSpd_Kph_f32	224.002701
k_DiagMuxOnAbsentTimeout_mS_u16	14802
k_EMNodeTimeout_mS_u16	14615
k_ESPNTCEnableTimeout_mS_u16	31330
k_ESPNodeAbsentDiag_Cnt_str.Threshold	37035
k_ESPNodeAbsentDiag_Cnt_str.PStep	48170
k_ESPNodeAbsentDiag_Cnt_str.NStep	20021
k_ESPNodeAbsentTimeout_mS_u16	45335
k_EtatMTSigInvalidThresh_Cnt_u16	6646
k_EtatMTSigValidThresh_Cnt_u16	28792
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	62032
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	24147
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	56867
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	65057
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	11725
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	39219
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	34017
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	5972

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	33048
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	14576
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	35372
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	40909
k_ISDATDIRASentDiag_Cnt_str.Threshold	7177
k_ISDATDIRASentDiag_Cnt_str.PStep	24440
k_ISDATDIRASentDiag_Cnt_str.NStep	2308
k_ISDATDIRASentTimeout_mS_u16	14293
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	38674
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	52155
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	20302
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	24185
k_ISDYNAASChkSumValidThresh_Cnt_u16	13625
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	56855
k_ISDYNAASMsgCountValidThresh_Cnt_u16	63086
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	61981
k_ISDYNAASMsgLenValidThresh_Cnt_u16	8675
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	4514
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	43887
k_ISDYNABRChkSumValidThresh_Cnt_u16	16758
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	44121
k_ISDYNABRMsgCountValidThresh_Cnt_u16	43408
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	16592
k_ISDYNABRMsgLenValidThresh_Cnt_u16	14467
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	28911
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	10067
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	55160
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	57374
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	41090
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	39545
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	38099
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	58114
k_ISDYNVOLChkSumValidThresh_Cnt_u16	42589
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	4944
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	64477
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	10145
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	62917
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	946
k_IgnOnTimeout_mS_u16	17246
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	160.251205
k_PowerCutVehSpdLowThresh_Kph_f32	138.571503
k_PowerCutVehSpdLowTimeout_mS_u16	57607
k_VBattMaxAAS_Volt_f32	26.9692001
k_VBattMaxBSI_Volt_f32	24.2182007
k_VBattMaxCAV_Volt_f32	10.6835003
k_VBattMaxCMM388_Volt_f32	1.01590002
k_VBattMaxCMM_Volt_f32	30.9176006
k_VBattMaxESP_Volt_f32	31.2205009
k_VBattMinAAS_Volt_f32	27.7665005
k_VBattMinBSI_Volt_f32	31.2205009
k_VBattMinCAV_Volt_f32	1.79879999
k_VBattMinCMM388_Volt_f32	22.7101002
k_VBattMinCMM_Volt_f32	1.09159994
k_VBattMinESP_Volt_f32	30.9176006
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	5276
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	25383
k_VitesseVehicleBVRampValidThresh_Cnt_u16	56357
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	50527
k_VitesseVehicleBVSigValidThresh_Cnt_u16	56283
k_VitesseVehicleBVSpeedPassThresh_kph_f32	145.233597
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	7430
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	2006
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2712124928
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	99
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	9862
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	607654656
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	68

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	24.6422997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1722658304
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	7
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.895296574
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1986780672
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	78
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2111897088
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	228
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2753961472
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4047191552
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1830837760
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	534085120
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	232
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	291151360
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	92
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	105
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	187
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	191
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	217
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	176
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3745791488
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	64
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	114
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	131
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	184
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	196
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	230
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2336677376
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	641465856
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2684427776
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	38
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	118
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	242
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2212834816
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	321
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.114130713
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	825661
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	110.785599
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	54201

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	607654656	607654656	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	607654656	607654656	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	607654656	607654656	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	607654656	607654656	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	607654656	607654656	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	607654656	607654656	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	607654656	607654656	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21332	21332	✔
BSINodeAbsentTimer_mS_M_u32	607654656	607654656	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	607654656	607654656	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	62578	62578	✔
CAVNodeAbsentTimer_mS_M_u32	607654656	607654656	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	607654656	607654656	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2907446784	2907446784	✔
CMMNTCsEnabled_Cnt_M_lgc	1	1	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	534085120	534085120	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	20972	20972	✔
CONSANGLECPK_HwDeg_M_f32	-308.709106	-308.709106 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	607654656	607654656	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	607654656	607654656	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	607654656	607654656	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	607654656	607654656	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	1	1	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	607654656	607654656	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	607654656	607654656	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	607654656	607654656	✔
ESPNTCEnableTimer_mS_M_u32	607654656	607654656	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	607654656	607654656	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	9	9	✔
EffacDefaultDiagTimer_mS_M_u32[1]	81	81	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	2050	2050	✔
ElecIntTimer_mS_M_u32[1]	6070	6070	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	607654656	607654656	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	1	1	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	607654656	607654656	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	607654656	607654656	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	607654656	607654656	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	607654656	607654656	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	607654656	607654656	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	534085120	534085120	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	607654656	607654656	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	607654656	607654656	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2336677376	2336677376	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	607654656	607654656	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	607654656	607654656	✔
IgnOnTimer_mS_M_u32	2173820416	2173820416	✔
IgnTimeOff_Sec_M_u32	1898983744	1898983744	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	83	83	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1986780672	1986780672	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	78	78	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2111897088	2111897088	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	228	228	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2753961472	2753961472	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	29	29	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4047191552	4047191552	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	698031616	698031616	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	239	239	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	534085120	534085120	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	232	232	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	291151360	291151360	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	176	176	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3745791488	3745791488	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	230	230	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2336677376	2336677376	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	641465856	641465856	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	158	158	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2684427776	2684427776	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2212834816	2212834816	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	347.470001	347.470001	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	339.756012	339.756012	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	513.779602	513.779602	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	20972	20972	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1898983744	1898983744	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-308.709106	-308.709106 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	224.002701	224.002701	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0129	0x0129	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	2	ValidityNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.34 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1617434880
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	7820
AASNodeAbsentTimer_mS_M_u32	4119218432
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	57039
ANGLEVOLANTSigValidCount_Cnt_M_u16	6824
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	58917
AngleVolantMsgTimer_mS_M_u32	1617434880
AngleVolantValidCount_Cnt_M_u16	1364
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2985494784
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	857704704
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1836202240
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1736571136
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	55114
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1440790784
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	41410
CAVNodeAbsentTimer_mS_M_u32	1796499712
CDD_SrlComVehSpd_Kph_G_f32	392.354889
CMM388NTCEnableTimer_mS_M_u32	4257458432
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2578606336
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	31013
CMMNodeAbsentTimer_mS_M_u32	3714316544
CONSANGLECPKSigInvalidCount_Cnt_M_u16	14487
CONSANGLECPKSigValidCount_Cnt_M_u16	48513
CONSANGLECPK_Cnt_M_u16	30288

Name	Input Value
CONSANGLECPK_HwDeg_M_f32	17.0699005
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	30288
CPKVehicleSpeedMsgTimer_mS_M_u32	532355328
CPKVehicleSpeedValidCount_Cnt_M_u16	37276
CityParkInputConsistentCount_Cnt_M_u16	25960
CityParkInputInvalidCount_Cnt_M_u16	34180
CityParkInputMsgTimer_mS_M_u32	1986780672
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1520060672
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	23712
ComputerRazGCTSigInvalidTimer_mS_M_u32	1284172032
ComputerRazGCTSigValidCount_Cnt_M_u16	1881
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	53616
DMDFCTCPKSigValidCount_Cnt_M_u16	62866
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	39385
DMDRELAXECPKSigValidCount_Cnt_M_u16	59698
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	50480
DateInvalidTimer_mS_M_u32	857704704
DiagMuxOnAbsentTimer_mS_M_u32	338090240
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1736571136
ESPNTCEnableTimer_mS_M_u32	2733852928
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	43979
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	20
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	9900
ElecIntTimer_mS_M_u32[1]	11000
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1540012288
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	24773
EtatMTSigValidCount_Cnt_M_u16	46875
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	37281
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	43531
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	54832
ISDAT4V2BSI552MsgTimer_mS_M_u32	2843212032
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	42615
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	26741
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	46875
ISDATBSI3F2MsgTimer_mS_M_u32	4078754048
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	6505
ISDATBSI412MsgLenValidCount_Cnt_M_u16	35286
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	24773
ISDATBSI412MsgTimer_mS_M_u32	1298012416
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	60473
ISDATBSI432MsgLenValidCount_Cnt_M_u16	1503
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	24527
ISDATDIRASentFltAcc_Cnt_M_u16	21683
ISDATDIRASentTimer_mS_M_u32	532355328
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	49606
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	1364
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	42347
ISDYN2CMMMsgTimer_mS_M_u32	727009536
ISDYNAASChkSumInvalidCount_Cnt_M_u16	62870
ISDYNAASChkSumValidCount_Cnt_M_u16	57360
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	59215
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	31185
ISDYNAASMsgLenValidCount_Cnt_M_u16	32867
ISDYNAASMsgTimeValidCount_Cnt_M_u16	62870
ISDYNAASMsgTimer_mS_M_u32	1789896960
ISDYNABRChkSumInvalidCount_Cnt_M_u16	47720
ISDYNABRChkSumValidCount_Cnt_M_u16	32746
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	6161

Name	Input Value
ISDYNABRMsgCountValidCount_Cnt_M_u16	30923
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	25106
ISDYNABRMsgLenValidCount_Cnt_M_u16	40252
ISDYNABRMsgTimeValidCount_Cnt_M_u16	30288
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	599
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1083
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	46875
ISDYNCMM208MsgTimer_mS_M_u32	2737047808
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2247
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1189
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	44362
ISDYNCMM388MsgTimer_mS_M_u32	2563582208
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	28557
ISDYNVOLChkSumValidCount_Cnt_M_u16	24823
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	20326
ISDYNVOLMsgCountValidCount_Cnt_M_u16	8200
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	44112
ISDYNVOLMsgLenValidCount_Cnt_M_u16	25242
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	31013
ISDYNVOLMsgTimer_mS_M_u32	4118210816
IgnOnTimer_mS_M_u32	1675700480
IgnTimeOff_Sec_M_u32	1965278031
ManVehSpd_Kph_M_f32	586.827209
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	156
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	49
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2686114048
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	72
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1632450816
PrevISDATBSI412MsgDLCError_Cnt_M_u08	70
PrevISDATBSI412MsgRxTime_MSec_M_u32	2296473856
PrevISDATBSI432MsgDLCError_Cnt_M_u08	213
PrevISDATBSI432MsgRxTime_MSec_M_u32	179783936
PrevISDATDIRAMsgTxTime_MSec_M_u32	549808384
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	27
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4134107392
PrevISDYNAASMsgDLCError_Cnt_M_u08	140
PrevISDYNAASMsgRxTime_MSec_M_u32	3907840256
PrevISDYNABRMsgDLCError_Cnt_M_u08	82
PrevISDYNABRMsgRxTime_MSec_M_u32	3568904448
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	19
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3651004672
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	145
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1015433472
PrevISDYNVOLMsgDLCError_Cnt_M_u08	186
PrevISDYNVOLMsgRxTime_MSec_M_u32	1116367104
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3511949568
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	469.194702
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	1479
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	14553
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0

Name	Input Value
VehTimeValid_Cnt_M_Igc	1
VehicleSpeedValid_Cnt_M_Igc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	19916
VitesseVehicleBVRampValidCount_Cnt_M_u16	60062
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	51796
VitesseVehicleBVSigValidCount_Cnt_M_u16	4077
VitesseVehicleBV_Kph_M_f32	592.325989
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	44362
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	13627
VitesseVehiculeRoues_Kph_M_f32	381.760406
k_AASNTCEnableTimeout_mS_u16	40675
k_AASNodeAbsentDiag_Cnt_str.Threshold	2377
k_AASNodeAbsentDiag_Cnt_str.PStep	47912
k_AASNodeAbsentDiag_Cnt_str.NStep	58624
k_AASNodeAbsentTimeout_mS_u16	56891
k_AASNodeTimeout_mS_u16	65497
k_ABSNodeTimeout_mS_u16	60257
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	7520
k_ANGLEVOLANTSigValidThresh_Cnt_u16	38470
k_AngleVolantInvalidThresh_Cnt_u16	2793
k_AngleVolantValidThresh_Cnt_u16	34180
k_BSI552MsgTimeout_mS_u16	58270
k_BSINTCEnableTimeout_mS_u16	3345
k_BSINodeAbsentDiag_Cnt_str.Threshold	21372
k_BSINodeAbsentDiag_Cnt_str.PStep	36457
k_BSINodeAbsentDiag_Cnt_str.NStep	12382
k_BSINodeAbsentTimeout_mS_u16	37117
k_BSINodeTimeout_mS_u16	24527
k_BattOvHi_Volt_f32	15.5263004
k_BattOvLo_Volt_f32	20.5603008
k_BattUvHi_Volt_f32	1.0381
k_BattUvLo_Volt_f32	14.1289997
k_CAVNTCEnableTimeout_mS_u16	33362
k_CAVNodeAbsentDiag_Cnt_str.Threshold	38619
k_CAVNodeAbsentDiag_Cnt_str.PStep	1990
k_CAVNodeAbsentDiag_Cnt_str.NStep	35219
k_CAVNodeAbsentTimeout_mS_u16	3256
k_CAVNodeTimeout_mS_u16	15747
k_CMM388MsgTimeout_mS_u16	9612
k_CMM388NTCEnableTimeout_mS_u16	10104
k_CMMNTCEnableTimeout_mS_u16	62287
k_CMMNodeAbsentDiag_Cnt_str.Threshold	51939
k_CMMNodeAbsentDiag_Cnt_str.PStep	9903
k_CMMNodeAbsentDiag_Cnt_str.NStep	36170
k_CMMNodeAbsentTimeout_mS_u16	21799
k_CONSANGLECPKMax_HwDeg_f32	503.946106
k_CONSANGLECPKMin_HwDeg_f32	-583.4953
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	13386
k_CONSANGLECPKSigValidThresh_Cnt_u16	64571
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	49015
k_CPKVehicleSpeedValidThresh_Cnt_u16	54328
k_CityParkInputInvalidThresh_Cnt_u16	40070
k_CityParkInputValidThresh_Cnt_u16	25960
k_ComputerRazGCTSigValidThresh_Cnt_u16	27637
k_CptTemporelSigValidThresh_Cnt_u16	61555
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	26898
k_DMDFCTCPKSigValidThresh_Cnt_u16	58428
k_DMDFCTCPKValidCount_Cnt_u16	882
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	42347
k_DMDRELAXECPKSigValidThresh_Cnt_u16	24525
k_DMDRelaxeConsistentThresh_Cnt_u16	8555
k_DateValidThresh_Cnt_u16	54832
k_DefaultVehSpd_Kph_f32	71.8309021
k_DiagMuxOnAbsentTimeout_mS_u16	54942
k_EMNodeTimeout_mS_u16	24336
k_ESPNTCEnableTimeout_mS_u16	32942
k_ESPNodeAbsentDiag_Cnt_str.Threshold	19992
k_ESPNodeAbsentDiag_Cnt_str.PStep	45650
k_ESPNodeAbsentDiag_Cnt_str.NStep	17705
k_ESPNodeAbsentTimeout_mS_u16	7247
k_EtatMTSigInvalidThresh_Cnt_u16	49003
k_EtatMTSigValidThresh_Cnt_u16	20781
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	55974

Name	Input Value
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	12380
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	63341
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	54960
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	33134
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	55933
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	63474
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	39512
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	40781
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	53572
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	22354
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	65454
k_ISDATDIRASentDiag_Cnt_str.Threshold	17047
k_ISDATDIRASentDiag_Cnt_str.PStep	41537
k_ISDATDIRASentDiag_Cnt_str.NStep	22485
k_ISDATDIRASentTimeout_mS_u16	9556
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	28127
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58917
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	45546
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	16744
k_ISDYNAASChkSumValidThresh_Cnt_u16	18154
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	7953
k_ISDYNAASMsgCountValidThresh_Cnt_u16	49099
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	5756
k_ISDYNAASMsgLenValidThresh_Cnt_u16	22509
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	25454
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	26632
k_ISDYNABRChkSumValidThresh_Cnt_u16	20402
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	56906
k_ISDYNABRMsgCountValidThresh_Cnt_u16	20579
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	16421
k_ISDYNABRMsgLenValidThresh_Cnt_u16	45771
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	13894
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	32219
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	29614
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	51516
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	58831
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	25000
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	58460
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	63760
k_ISDYNVOLChkSumValidThresh_Cnt_u16	43197
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	38500
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	33534
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	24753
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	4103
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	41342
k_IgnOnTimeout_mS_u16	18428
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	13.5853004
k_PowerCutVehSpdLowThresh_Kph_f32	22.6243992
k_PowerCutVehSpdLowTimeout_mS_u16	62719
k_VBattMaxAAS_Volt_f32	14.2045002
k_VBattMaxBSI_Volt_f32	19.6861
k_VBattMaxCAV_Volt_f32	30.4158993
k_VBattMaxCMM388_Volt_f32	3.0223999
k_VBattMaxCMM_Volt_f32	5.06640005
k_VBattMaxESP_Volt_f32	29.2618999
k_VBattMinAAS_Volt_f32	21.3192997
k_VBattMinBSI_Volt_f32	29.2618999
k_VBattMinCAV_Volt_f32	19.1394997
k_VBattMinCMM388_Volt_f32	27.8840008
k_VBattMinCMM_Volt_f32	29.8010998
k_VBattMinESP_Volt_f32	5.06640005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	40257
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	27486
k_VitesseVehicleBVRampValidThresh_Cnt_u16	54886
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	42999
k_VitesseVehicleBVSigValidThresh_Cnt_u16	56901
k_VitesseVehicleBVSpeedPassThresh_kph_f32	45.8857002
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	10434
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	12820
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	857704704
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1

Name	Input Value
target_Pim_VVHTYPEData	241
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	13904
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	50498048
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	145
target_SrlComInput_Per1_Batt_Volt_f32.value	18.4279995
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2815277312
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	204
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.785079718
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	175
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1834166528
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	326355200
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2636409088
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	103
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4066707712
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4214597888
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	243
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2677426432
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3347507456
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	61
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	169
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	19
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2353662208
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	93
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	109
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	186
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	199
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1522673920
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1180879104
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	115
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3583207680
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	90
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	121
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	138
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2384935168
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1641
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.327734292
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	702624
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	137.232101
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	37033

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	50498048	50498048	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	2377	2377	✔
AASNodeAbsentTimer_mS_M_u32	50498048	50498048	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	58917	58917	✔
AngleVolantMsgTimer_mS_M_u32	50498048	50498048	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	50498048	50498048	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	50498048	50498048	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	50498048	50498048	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	50498048	50498048	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	42732	42732	✔
BSINodeAbsentTimer_mS_M_u32	4066707712	4066707712	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	50498048	50498048	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	6191	6191	✔
CAVNodeAbsentTimer_mS_M_u32	3583207680	3583207680	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	50498048	50498048	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	50498048	50498048	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2677426432	2677426432	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	30288	30288	✔
CONSANGLECPK_HwDeg_M_f32	17.0699005	17.0699005 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	30288	30288	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	532355328	532355328	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	37276	37276	✔
CityParkInputConsistentCount_Cnt_M_u16	25960	25960	✔
CityParkInputInvalidCount_Cnt_M_u16	34182	34182	✔
CityParkInputMsgTimer_mS_M_u32	50498048	50498048	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	50498048	50498048	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	50498048	50498048	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	50498048	50498048	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	50498048	50498048	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	50498048	50498048	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ESPNTCEnableTimer_mS_M_u32	50498048	50498048	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	50498048	50498048	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	20	20	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	9900	9900	✔
ElecIntTimer_mS_M_u32[1]	11000	11000	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	50498048	50498048	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	50498048	50498048	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	50498048	50498048	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	50498048	50498048	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	50498048	50498048	✔
ISDATDIRASentFltAcc_Cnt_M_u16	17047	17047	✔
ISDATDIRASentTimer_mS_M_u32	50498048	50498048	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	50498048	50498048	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	50498048	50498048	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	50498048	50498048	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	50498048	50498048	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	50498048	50498048	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	50498048	50498048	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
IgnOnTimer_mS_M_u32	1675700480	1675700480	✔
IgnTimeOff_Sec_M_u32	1965278031	1965278031	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	175	175	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1834166528	1834166528	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	326355200	326355200	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	117	117	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2636409088	2636409088	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	103	103	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4066707712	4066707712	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	549808384	549808384	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	243	243	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2677426432	2677426432	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	92	92	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3347507456	3347507456	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	19	19	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2353662208	2353662208	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1522673920	1522673920	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	178	178	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1180879104	1180879104	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	115	115	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3583207680	3583207680	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2384935168	2384935168	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	469.194702	469.194702	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	592.325989	592.325989	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	381.760406	381.760406	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	30288	30288	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1965278031	1965278031	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	17.0699005	17.0699005 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	71.8309021	71.8309021	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.35 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4262098944
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	62876
AASNodeAbsentTimer_mS_M_u32	3010455552
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	57045
ANGLEVOLANTSigValidCount_Cnt_M_u16	60936
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	17105
AngleVolantMsgTimer_mS_M_u32	4262098944
AngleVolantValidCount_Cnt_M_u16	26566
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	556378112
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4020512768
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	661395456
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	675076096
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	41316
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1210095616
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	27770
CAVNodeAbsentTimer_mS_M_u32	3007678464
CDD_SrlComVehSpd_Kph_G_f32	398.435211
CMM388NTCEnableTimer_mS_M_u32	3359098880
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	527140864
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	24081
CMMNodeAbsentTimer_mS_M_u32	3465992192
CONSANGLECPKSigInvalidCount_Cnt_M_u16	58491
CONSANGLECPKSigValidCount_Cnt_M_u16	22654
CONSANGLECPK_Cnt_M_u16	10769
CONSANGLECPK_HwDeg_M_f32	-722.934998
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	10769
CPKVehicleSpeedMsgTimer_mS_M_u32	3423696896
CPKVehicleSpeedValidCount_Cnt_M_u16	32628
CityParkInputConsistentCount_Cnt_M_u16	38794
CityParkInputInvalidCount_Cnt_M_u16	63541
CityParkInputMsgTimer_mS_M_u32	1834166528
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3560171520
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	35680
ComputerRazGCTSigInvalidTimer_mS_M_u32	149030912

Name	Input Value
ComputerRazGCTSigValidCount_Cnt_M_u16	46519
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	50289
DMDFCTCPKSigValidCount_Cnt_M_u16	15052
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	21943
DMDRELAXECPKSigValidCount_Cnt_M_u16	10858
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	58032
DateInvalidTimer_mS_M_u32	4020512768
DiagMuxOnAbsentTimer_mS_M_u32	1305360384
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	675076096
ESPNTCEnableTimer_mS_M_u32	2670258176
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	47328
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	80
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6454
ElecIntTimer_mS_M_u32[1]	8257
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1583519744
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	30769
EtatMTSigValidCount_Cnt_M_u16	10223
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	33117
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	15072
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	37106
ISDAT4V2BSI552MsgTimer_mS_M_u32	3126515712
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	18075
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	21346
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	10223
ISDATBSI3F2MsgTimer_mS_M_u32	149698560
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	17095
ISDATBSI412MsgLenValidCount_Cnt_M_u16	1086
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	30769
ISDATBSI412MsgTimer_mS_M_u32	2401794048
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	21717
ISDATBSI432MsgLenValidCount_Cnt_M_u16	64164
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	42579
ISDATDIRASentFltAcc_Cnt_M_u16	22439
ISDATDIRASentTimer_mS_M_u32	3423696896
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	40879
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	26566
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	62592
ISDYN2CMMMsgTimer_mS_M_u32	235071488
ISDYNAASChkSumInvalidCount_Cnt_M_u16	6270
ISDYNAASChkSumValidCount_Cnt_M_u16	39889
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	28117
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	57421
ISDYNAASMsgLenValidCount_Cnt_M_u16	28504
ISDYNAASMsgTimeValidCount_Cnt_M_u16	6270
ISDYNAASMsgTimer_mS_M_u32	829671424
ISDYNABRChkSumInvalidCount_Cnt_M_u16	35719
ISDYNABRChkSumValidCount_Cnt_M_u16	40386
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	23821
ISDYNABRMsgCountValidCount_Cnt_M_u16	32160
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	5130
ISDYNABRMsgLenValidCount_Cnt_M_u16	25933
ISDYNABRMsgTimeValidCount_Cnt_M_u16	10769
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	600
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1085
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	10223
ISDYNCMM208MsgTimer_mS_M_u32	1368827904
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2251
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1191
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	51172
ISDYNCMM388MsgTimer_mS_M_u32	4246423552

Name	Input Value
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	38809
ISDYNVOLChkSumValidCount_Cnt_M_u16	50716
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	41615
ISDYNVOLMsgCountValidCount_Cnt_M_u16	4970
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	2897
ISDYNVOLMsgLenValidCount_Cnt_M_u16	27444
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	24081
ISDYNVOLMsgTimer_mS_M_u32	3189639168
IgnOnTimer_mS_M_u32	3957278720
IgnTimeOff_Sec_M_u32	2387520020
ManVehSpd_Kph_M_f32	73.3242035
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	158
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	175
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2045917184
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	187
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2010847232
PrevISDATBSI412MsgDLCError_Cnt_M_u08	223
PrevISDATBSI412MsgRxTime_MSec_M_u32	3453913088
PrevISDATBSI432MsgDLCError_Cnt_M_u08	146
PrevISDATBSI432MsgRxTime_MSec_M_u32	2010966016
PrevISDATDIRAMsgTxTime_MSec_M_u32	2519894016
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	195
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2038847488
PrevISDYNAASMsgDLCError_Cnt_M_u08	255
PrevISDYNAASMsgRxTime_MSec_M_u32	1002178560
PrevISDYNABRMsgDLCError_Cnt_M_u08	40
PrevISDYNABRMsgRxTime_MSec_M_u32	4183246848
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	5
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1839794176
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	252
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3731875840
PrevISDYNVOLMsgDLCError_Cnt_M_u08	162
PrevISDYNVOLMsgRxTime_MSec_M_u32	2229504000
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1531344896
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	501.213715
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	37995
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	40438
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	4188
VitesseVehicleBVRampValidCount_Cnt_M_u16	56487
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	28742
VitesseVehicleBVSigValidCount_Cnt_M_u16	25145
VitesseVehicleBV_Kph_M_f32	488.191711
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	51172
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	21199
VitesseVehiculeRoues_Kph_M_f32	185.373306
k_AASNTCEnableTimeout_mS_u16	48216
k_AASNodeAbsentDiag_Cnt_str.Threshold	38617
k_AASNodeAbsentDiag_Cnt_str.PStep	57109

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.NStep	2213
k_AASNodeAbsentTimeout_mS_u16	14609
k_AASNodeTimeout_mS_u16	18678
k_ABSNodeTimeout_mS_u16	31390
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	7520
k_ANGLEVOLANTSigValidThresh_Cnt_u16	42351
k_AngleVolantInvalidThresh_Cnt_u16	37766
k_AngleVolantValidThresh_Cnt_u16	63541
k_BSI552MsgTimeout_mS_u16	37798
k_BSINTCEnableTimeout_mS_u16	21069
k_BSINodeAbsentDiag_Cnt_str.Threshold	21412
k_BSINodeAbsentDiag_Cnt_str.PStep	36440
k_BSINodeAbsentDiag_Cnt_str.NStep	12405
k_BSINodeAbsentTimeout_mS_u16	41545
k_BSINodeTimeout_mS_u16	42579
k_BattOvHi_Volt_f32	23.1832008
k_BattOvLo_Volt_f32	25.3152008
k_BattUvHi_Volt_f32	27.3558998
k_BattUvLo_Volt_f32	14.8386002
k_CAVNTCEnableTimeout_mS_u16	47563
k_CAVNodeAbsentDiag_Cnt_str.Threshold	8221
k_CAVNodeAbsentDiag_Cnt_str.PStep	29554
k_CAVNodeAbsentDiag_Cnt_str.NStep	56165
k_CAVNodeAbsentTimeout_mS_u16	33688
k_CAVNodeTimeout_mS_u16	34231
k_CMM388MsgTimeout_mS_u16	57500
k_CMM388NTCEnableTimeout_mS_u16	35544
k_CMMNTCEnableTimeout_mS_u16	49171
k_CMMNodeAbsentDiag_Cnt_str.Threshold	1389
k_CMMNodeAbsentDiag_Cnt_str.PStep	38113
k_CMMNodeAbsentDiag_Cnt_str.NStep	9512
k_CMMNodeAbsentTimeout_mS_u16	41739
k_CONSANGLECPKMax_HwDeg_f32	529.929871
k_CONSANGLECPKMin_HwDeg_f32	-686.106201
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	13028
k_CONSANGLECPKSigValidThresh_Cnt_u16	64975
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	540
k_CPKVehicleSpeedValidThresh_Cnt_u16	3674
k_CityParkInputInvalidThresh_Cnt_u16	56621
k_CityParkInputValidThresh_Cnt_u16	38794
k_ComputerRazGCTSigValidThresh_Cnt_u16	28193
k_CptTemporelSigValidThresh_Cnt_u16	13160
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	65290
k_DMDFCTCPKSigValidThresh_Cnt_u16	36941
k_DMDFCTCPKValidCount_Cnt_u16	48364
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	62592
k_DMDRELAXECPKSigValidThresh_Cnt_u16	43035
k_DMDRelaxeConsistentThresh_Cnt_u16	23361
k_DateValidThresh_Cnt_u16	37106
k_DefaultVehSpd_Kph_f32	66.2678986
k_DiagMuxOnAbsentTimeout_mS_u16	49447
k_EMNodeTimeout_mS_u16	38160
k_ESPNTCEnableTimeout_mS_u16	32694
k_ESPNodeAbsentDiag_Cnt_str.Threshold	63149
k_ESPNodeAbsentDiag_Cnt_str.PStep	62935
k_ESPNodeAbsentDiag_Cnt_str.NStep	17000
k_ESPNodeAbsentTimeout_mS_u16	60819
k_EtatMTSigInvalidThresh_Cnt_u16	18558
k_EtatMTSigValidThresh_Cnt_u16	62969
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	11407
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	24110
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	13691
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	55792
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	11383
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	20363
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	21930
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	24889
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	35737
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	59701
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	59852
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	13559
k_ISDATDIRASentDiag_Cnt_str.Threshold	46441
k_ISDATDIRASentDiag_Cnt_str.PStep	63617

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.NStep	41247
k_ISDATDIRASentTimeout_mS_u16	64195
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	61028
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	17105
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	56322
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	63111
k_ISDYNAASChkSumValidThresh_Cnt_u16	18626
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	18445
k_ISDYNAASMsgCountValidThresh_Cnt_u16	43168
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	51019
k_ISDYNAASMsgLenValidThresh_Cnt_u16	37050
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	56823
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	23080
k_ISDYNABRChkSumValidThresh_Cnt_u16	42475
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	35940
k_ISDYNABRMsgCountValidThresh_Cnt_u16	63703
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	2321
k_ISDYNABRMsgLenValidThresh_Cnt_u16	41952
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	37678
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	31791
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	34808
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	14541
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	51669
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	6408
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	15277
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	65490
k_ISDYNVOLChkSumValidThresh_Cnt_u16	905
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	40213
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	58502
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	10349
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	52523
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	59144
k_IgnOnTimeout_mS_u16	49934
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	221.504807
k_PowerCutVehSpdLowThresh_Kph_f32	106.387604
k_PowerCutVehSpdLowTimeout_mS_u16	10756
k_VBattMaxAAS_Volt_f32	29.0275993
k_VBattMaxBSI_Volt_f32	20.8973007
k_VBattMaxCAV_Volt_f32	12.3297997
k_VBattMaxCMM388_Volt_f32	32
k_VBattMaxCMM_Volt_f32	15.3209
k_VBattMaxESP_Volt_f32	32
k_VBattMinAAS_Volt_f32	12.1625004
k_VBattMinBSI_Volt_f32	32
k_VBattMinCAV_Volt_f32	27.9510994
k_VBattMinCMM388_Volt_f32	18.2819004
k_VBattMinCMM_Volt_f32	3.34619999
k_VBattMinESP_Volt_f32	15.3209
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	26686
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	53413
k_VitesseVehicleBVRampValidThresh_Cnt_u16	3471
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	61724
k_VitesseVehicleBVSigValidThresh_Cnt_u16	57587
k_VitesseVehicleBVSpeedPassThresh_kph_f32	266.814301
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	55162
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	24133
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4020512768
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	201
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	24750
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3376358656
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	252
target_SrlComInput_Per1_Batt_Volt_f32.value	13.8112001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1180276736

Name	Input Value
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	198
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.967301011
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	394872832
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	237
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4020725760
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	7
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1561692160
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2815666176
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	400672768
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	204
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4114606080
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2280523776
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	62
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	129
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	147
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	161
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2921637888
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	60
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	70
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	89
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	127
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	232
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3409725440
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3537528832
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	138
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	801671168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	88
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	129
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3645708288
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2039
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.6689533
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	106334
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	180.814606
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	64453

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3376358656	3376358656	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	38617	38617	✔
AASNodeAbsentTimer_mS_M_u32	3376358656	3376358656	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3376358656	3376358656	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3376358656	3376358656	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3376358656	3376358656	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3376358656	3376358656	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3376358656	3376358656	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21412	21412	✔
BSINodeAbsentTimer_mS_M_u32	3376358656	3376358656	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3376358656	3376358656	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3376358656	3376358656	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3376358656	3376358656	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3376358656	3376358656	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3376358656	3376358656	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	10769	10769	✔
CONSANGLECPK_HwDeg_M_f32	-722.934998	-722.934998 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3376358656	3376358656	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3376358656	3376358656	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3376358656	3376358656	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3376358656	3376358656	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3376358656	3376358656	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3376358656	3376358656	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3376358656	3376358656	✔
ESPNTCEnableTimer_mS_M_u32	3376358656	3376358656	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	63149	63149	✔
ESPNodeAbsentTimer_mS_M_u32	3376358656	3376358656	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	80	80	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3376358656	3376358656	✔
ElecIntTimer_mS_M_u32[1]	8257	8257	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3376358656	3376358656	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3376358656	3376358656	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3376358656	3376358656	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3376358656	3376358656	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3376358656	3376358656	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3376358656	3376358656	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3376358656	3376358656	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3376358656	3376358656	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3376358656	3376358656	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3376358656	3376358656	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3376358656	3376358656	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3376358656	3376358656	✔
IgnOnTimer_mS_M_u32	3376358656	3376358656	✔
IgnTimeOff_Sec_M_u32	2387520020	2387520020	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	394872832	394872832	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	237	237	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4020725760	4020725760	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	7	7	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1561692160	1561692160	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	90	90	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2815666176	2815666176	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2519894016	2519894016	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	204	204	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4114606080	4114606080	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	123	123	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2280523776	2280523776	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2921637888	2921637888	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	232	232	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3409725440	3409725440	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3537528832	3537528832	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	138	138	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	801671168	801671168	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3645708288	3645708288	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	501.213715	501.213715	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	488.191711	488.191711	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	185.373306	185.373306	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	10769	10769	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2387520020	2387520020	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-722.934998	-722.934998 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	66.2678986	66.2678986	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.36 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	694115072
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	44199
AASNodeAbsentTimer_mS_M_u32	2867792640
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	29438
ANGLEVOLANTSigValidCount_Cnt_M_u16	64805
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	55560
AngleVolantMsgTimer_mS_M_u32	694115072
AngleVolantValidCount_Cnt_M_u16	58028
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2025966336
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	391269120
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3149560576
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3964156672
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	10065
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3416062720
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	18062
CAVNodeAbsentTimer_mS_M_u32	2314087168
CDD_SrlComVehSpd_Kph_G_f32	316.699585
CMM388NTCEnableTimer_mS_M_u32	3826739968
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1568418560
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	2697
CMMNodeAbsentTimer_mS_M_u32	3778689792
CONSANGLECPKSigInvalidCount_Cnt_M_u16	10509
CONSANGLECPKSigValidCount_Cnt_M_u16	50372
CONSANGLECPK_Cnt_M_u16	23563
CONSANGLECPK_HwDeg_M_f32	297.270508
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	23563
CPKVehicleSpeedMsgTimer_mS_M_u32	2605341440
CPKVehicleSpeedValidCount_Cnt_M_u16	34313
CityParkInputConsistentCount_Cnt_M_u16	25440
CityParkInputInvalidCount_Cnt_M_u16	65118
CityParkInputMsgTimer_mS_M_u32	394872832
CityParkInputValidCount_Cnt_M_u16	1

Name	Input Value
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1487080192
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	64347
ComputerRazGCTSigInvalidTimer_mS_M_u32	2602085120
ComputerRazGCTSigValidCount_Cnt_M_u16	64729
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	35242
DMDFCTCPKSigValidCount_Cnt_M_u16	32345
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	5720
DMDRELAXECPKSigValidCount_Cnt_M_u16	20479
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	17006
DateInvalidTimer_mS_M_u32	391269120
DiagMuxOnAbsentTimer_mS_M_u32	4178844416
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3964156672
ESPNTCEnableTimer_mS_M_u32	197397248
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	8668
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	150
EffacDefaultDiagTimer_mS_M_u32[1]	1150
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	8976
ElecIntTimer_mS_M_u32[1]	15234
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	282524416
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	18731
EtatMTSigValidCount_Cnt_M_u16	8622
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	23143
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	9630
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	37863
ISDAT4V2BSI552MsgTimer_mS_M_u32	770587392
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	65388
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	57559
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	8622
ISDATBSI3F2MsgTimer_mS_M_u32	3216644864
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	3047
ISDATBSI412MsgLenValidCount_Cnt_M_u16	36674
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	18731
ISDATBSI412MsgTimer_mS_M_u32	1845844736
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	13885
ISDATBSI432MsgLenValidCount_Cnt_M_u16	27792
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	15619
ISDATDIRASentFltAcc_Cnt_M_u16	30983
ISDATDIRASentTimer_mS_M_u32	2605341440
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	62257
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	58028
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	62845
ISDYN2CMMMsgTimer_mS_M_u32	2805336832
ISDYNAASChkSumInvalidCount_Cnt_M_u16	19457
ISDYNAASChkSumValidCount_Cnt_M_u16	63945
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	52351
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	63253
ISDYNAASMsgLenValidCount_Cnt_M_u16	25013
ISDYNAASMsgTimeValidCount_Cnt_M_u16	19457
ISDYNAASMsgTimer_mS_M_u32	2556652288
ISDYNABRChkSumInvalidCount_Cnt_M_u16	44647
ISDYNABRChkSumValidCount_Cnt_M_u16	20342
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	31316
ISDYNABRMsgCountValidCount_Cnt_M_u16	20572
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	38496
ISDYNABRMsgLenValidCount_Cnt_M_u16	39511
ISDYNABRMsgTimeValidCount_Cnt_M_u16	23563
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	601
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1087
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	8622
ISDYNCMM208MsgTimer_mS_M_u32	3682257664

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2255
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1193
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	47698
ISDYNCMM388MsgTimer_mS_M_u32	862776064
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	1971
ISDYNVOLChkSumValidCount_Cnt_M_u16	29674
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	59216
ISDYNVOLMsgCountValidCount_Cnt_M_u16	60543
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	11913
ISDYNVOLMsgLenValidCount_Cnt_M_u16	34464
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	2697
ISDYNVOLMsgTimer_mS_M_u32	1801759488
IgnOnTimer_mS_M_u32	1998646016
IgnTimeOff_Sec_M_u32	1447200507
ManVehSpd_Kph_M_f32	517.115723
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	160
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	166
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	78125824
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	148
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1181580032
PrevISDATBSI412MsgDLCError_Cnt_M_u08	202
PrevISDATBSI412MsgRxTime_MSec_M_u32	3726846720
PrevISDATBSI432MsgDLCError_Cnt_M_u08	145
PrevISDATBSI432MsgRxTime_MSec_M_u32	1369967360
PrevISDATDIRAMsgTxTime_MSec_M_u32	3576113920
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	250
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4268473088
PrevISDYNAASMsgDLCError_Cnt_M_u08	145
PrevISDYNAASMsgRxTime_MSec_M_u32	3934956288
PrevISDYNABRMsgDLCError_Cnt_M_u08	168
PrevISDYNABRMsgRxTime_MSec_M_u32	783870720
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	177
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1220782848
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	121
PrevISDYNCMM388MsgRxTime_MSec_M_u32	703531776
PrevISDYNVOLMsgDLCError_Cnt_M_u08	30
PrevISDYNVOLMsgRxTime_MSec_M_u32	219425536
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	28007168
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	321.151215
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	53947
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	52699
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	25320
VitesseVehicleBVRampValidCount_Cnt_M_u16	5576
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	49835
VitesseVehicleBVSigValidCount_Cnt_M_u16	42130
VitesseVehicleBV_Kph_M_f32	603.780701
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	47698
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	45393

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	377.741913
k_AASNTCEnableTimeout_mS_u16	33078
k_AASNodeAbsentDiag_Cnt_str.Threshold	29847
k_AASNodeAbsentDiag_Cnt_str.PStep	57946
k_AASNodeAbsentDiag_Cnt_str.NStep	53345
k_AASNodeAbsentTimeout_mS_u16	23243
k_AASNodeTimeout_mS_u16	52443
k_ABSNodeTimeout_mS_u16	23331
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	51356
k_ANGLEVOLANTSigValidThresh_Cnt_u16	22575
k_AngleVolantInvalidThresh_Cnt_u16	43498
k_AngleVolantValidThresh_Cnt_u16	65118
k_BSI552MsgTimeout_mS_u16	2764
k_BSINTCEnableTimeout_mS_u16	7637
k_BSINodeAbsentDiag_Cnt_str.Threshold	21452
k_BSINodeAbsentDiag_Cnt_str.PStep	36423
k_BSINodeAbsentDiag_Cnt_str.NStep	12428
k_BSINodeAbsentTimeout_mS_u16	39584
k_BSINodeTimeout_mS_u16	15619
k_BattOvHi_Volt_f32	30.0762005
k_BattOvLo_Volt_f32	4.47849989
k_BattUvHi_Volt_f32	5.43419981
k_BattUvLo_Volt_f32	27.7199993
k_CAVNTCEnableTimeout_mS_u16	37276
k_CAVNodeAbsentDiag_Cnt_str.Threshold	8929
k_CAVNodeAbsentDiag_Cnt_str.PStep	38554
k_CAVNodeAbsentDiag_Cnt_str.NStep	63162
k_CAVNodeAbsentTimeout_mS_u16	63796
k_CAVNodeTimeout_mS_u16	13657
k_CMM388MsgTimeout_mS_u16	60327
k_CMM388NTCEnableTimeout_mS_u16	56563
k_CMMNTCEnableTimeout_mS_u16	29444
k_CMMNodeAbsentDiag_Cnt_str.Threshold	36539
k_CMMNodeAbsentDiag_Cnt_str.PStep	22486
k_CMMNodeAbsentDiag_Cnt_str.NStep	47802
k_CMMNodeAbsentTimeout_mS_u16	45213
k_CONSANGLECPKMax_HwDeg_f32	489.303101
k_CONSANGLECPKMin_HwDeg_f32	-374.507813
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	31058
k_CONSANGLECPKSigValidThresh_Cnt_u16	45137
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	47465
k_CPKVehicleSpeedValidThresh_Cnt_u16	46382
k_CityParkInputInvalidThresh_Cnt_u16	53621
k_CityParkInputValidThresh_Cnt_u16	25440
k_ComputerRazGCTSigValidThresh_Cnt_u16	8410
k_CptTemporelSigValidThresh_Cnt_u16	55493
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	54624
k_DMDFCTCPKSigValidThresh_Cnt_u16	6487
k_DMDFCTCPKValidCount_Cnt_u16	62649
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	62845
k_DMDRELAXECPKSigValidThresh_Cnt_u16	12908
k_DMDRelaxeConsistentThresh_Cnt_u16	12538
k_DateValidThresh_Cnt_u16	37863
k_DefaultVehSpd_Kph_f32	109.191299
k_DiagMuxOnAbsentTimeout_mS_u16	28361
k_EMNodeTimeout_mS_u16	43854
k_ESPNTCEnableTimeout_mS_u16	64730
k_ESPNodeAbsentDiag_Cnt_str.Threshold	51802
k_ESPNodeAbsentDiag_Cnt_str.PStep	43349
k_ESPNodeAbsentDiag_Cnt_str.NStep	5207
k_ESPNodeAbsentTimeout_mS_u16	61701
k_EtatMTSigInvalidThresh_Cnt_u16	4994
k_EtatMTSigValidThresh_Cnt_u16	58065
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	50704
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	39155
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	36237
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	55661
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	59800
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	62875
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	51134
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	52433
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	41457
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	44703

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	62618
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	18007
k_ISDATDIRASentDiag_Cnt_str.Threshold	39294
k_ISDATDIRASentDiag_Cnt_str.PStep	2542
k_ISDATDIRASentDiag_Cnt_str.NStep	5133
k_ISDATDIRASentTimeout_mS_u16	20659
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	3600
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	55560
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	6134
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	28007
k_ISDYNAASChkSumValidThresh_Cnt_u16	20086
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	47444
k_ISDYNAASMsgCountValidThresh_Cnt_u16	53084
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	2843
k_ISDYNAASMsgLenValidThresh_Cnt_u16	1423
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	52887
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	48134
k_ISDYNABRChkSumValidThresh_Cnt_u16	53373
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	26193
k_ISDYNABRMsgCountValidThresh_Cnt_u16	55480
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	2441
k_ISDYNABRMsgLenValidThresh_Cnt_u16	24796
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	9651
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	11119
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16468
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	6486
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	45566
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	31781
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	5110
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	49350
k_ISDYNVOLChkSumValidThresh_Cnt_u16	32097
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	35133
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	35626
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	10359
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	8698
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	27045
k_IgnOnTimeout_mS_u16	26386
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	213.980896
k_PowerCutVehSpdLowThresh_Kph_f32	55.3324013
k_PowerCutVehSpdLowTimeout_mS_u16	59442
k_VBattMaxAAS_Volt_f32	11.6587
k_VBattMaxBSI_Volt_f32	11.1063995
k_VBattMaxCAV_Volt_f32	31.9424992
k_VBattMaxCMM388_Volt_f32	24.2640991
k_VBattMaxCMM_Volt_f32	11.1422005
k_VBattMaxESP_Volt_f32	20.7831993
k_VBattMinAAS_Volt_f32	15.8155003
k_VBattMinBSI_Volt_f32	20.7831993
k_VBattMinCAV_Volt_f32	6.70270014
k_VBattMinCMM388_Volt_f32	19.0167999
k_VBattMinCMM_Volt_f32	25.3778992
k_VBattMinESP_Volt_f32	11.1422005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	34946
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	55053
k_VitesseVehicleBVRampValidThresh_Cnt_u16	42576
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	62186
k_VitesseVehicleBVSigValidThresh_Cnt_u16	27429
k_VitesseVehicleBVSpeedPassThresh_kph_f32	286.607697
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	1422
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	35054
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	391269120
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	237
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	50270
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3199554560
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSe	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	121
target_SrlComInput_Per1_Batt_Volt_f32.value	23.4407997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4109499136
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	172
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.840369582
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	187
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	472050432
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	877169408
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3430820608
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	189
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	214158080
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	488205056
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	629082880
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1307880192
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	111
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	114
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	202
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	226
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2110835456
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	142
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	216
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2366237440
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	244
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	380603136
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3764726528
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	94
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	170
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	195
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1779923712
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3400
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.915873528
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	632406
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	113.301399
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	33965

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3199554560	3199554560	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	29847	29847	✔
AASNodeAbsentTimer_mS_M_u32	3199554560	3199554560	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3199554560	3199554560	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3199554560	3199554560	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3199554560	3199554560	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3199554560	3199554560	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3199554560	3199554560	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21452	21452	✔
BSINodeAbsentTimer_mS_M_u32	3199554560	3199554560	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3199554560	3199554560	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3199554560	3199554560	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3199554560	3199554560	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3199554560	3199554560	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3199554560	3199554560	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	23563	23563	✔
CONSANGLECPK_HwDeg_M_f32	297.270508	297.270508 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3199554560	3199554560	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3199554560	3199554560	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3199554560	3199554560	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3199554560	3199554560	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3199554560	3199554560	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3199554560	3199554560	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3199554560	3199554560	✔
ESPNTCEnableTimer_mS_M_u32	3199554560	3199554560	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	51802	51802	✔
ESPNodeAbsentTimer_mS_M_u32	3199554560	3199554560	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3199554560	3199554560	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1150	1150	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3199554560	3199554560	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	15234	15234	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3199554560	3199554560	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3199554560	3199554560	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3199554560	3199554560	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3199554560	3199554560	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3199554560	3199554560	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3199554560	3199554560	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3199554560	3199554560	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3199554560	3199554560	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3199554560	3199554560	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3199554560	3199554560	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3199554560	3199554560	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3199554560	3199554560	✔
IgnOnTimer_mS_M_u32	1998646016	1998646016	✔
IgnTimeOff_Sec_M_u32	1447200507	1447200507	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	187	187	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	472050432	472050432	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	66	66	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	877169408	877169408	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	53	53	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3430820608	3430820608	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	189	189	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	214158080	214158080	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3576113920	3576113920	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	39	39	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	629082880	629082880	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	91	91	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1307880192	1307880192	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	205	205	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2110835456	2110835456	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2366237440	2366237440	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	244	244	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	380603136	380603136	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	57	57	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3764726528	3764726528	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1779923712	1779923712	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	321.151215	321.151215	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	603.780701	603.780701	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	377.741913	377.741913	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	23563	23563	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1447200507	1447200507	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	297.270508	297.270508 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.37 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2326573568
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	49875
AASNodeAbsentTimer_mS_M_u32	549298688
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	59855
ANGLEVOLANTSigValidCount_Cnt_M_u16	9242
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	432
AngleVolantMsgTimer_mS_M_u32	2326573568
AngleVolantValidCount_Cnt_M_u16	31557
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1917149696
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2022957568
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2820362752
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2104627712
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	55510
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	578015744
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	63901
CAVNodeAbsentTimer_mS_M_u32	3896525312
CDD_SrlComVehSpd_Kph_G_f32	55.0297012
CMM388NTCEnableTimer_mS_M_u32	247759360
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	630604288
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	58222
CMMNodeAbsentTimer_mS_M_u32	3868987904
CONSANGLECPKSigInvalidCount_Cnt_M_u16	29347
CONSANGLECPKSigValidCount_Cnt_M_u16	47165
CONSANGLECPK_Cnt_M_u16	52840
CONSANGLECPK_HwDeg_M_f32	738.519104
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	52840
CPKVehicleSpeedMsgTimer_mS_M_u32	2699801088
CPKVehicleSpeedValidCount_Cnt_M_u16	29175
CityParkInputConsistentCount_Cnt_M_u16	51497
CityParkInputInvalidCount_Cnt_M_u16	49454

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	472050432
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3886129664
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	42679
ComputerRazGCTSigInvalidTimer_mS_M_u32	2126561792
ComputerRazGCTSigValidCount_Cnt_M_u16	8382
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	20298
DMDFCTCPKSigValidCount_Cnt_M_u16	27133
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	59329
DMDRELAXECPKSigValidCount_Cnt_M_u16	5004
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	60032
DateInvalidTimer_mS_M_u32	2022957568
DiagMuxOnAbsentTimer_mS_M_u32	3733877248
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2104627712
ESPNTCEnableTimer_mS_M_u32	2453578240
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	9780
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	64
EffacDefaultDiagTimer_mS_M_u32[1]	894
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	5
ElecIntTimer_mS_M_u32[1]	55
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3133526528
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	32903
EtatMTSigValidCount_Cnt_M_u16	16318
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	50837
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	32175
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	57683
ISDAT4V2BSI552MsgTimer_mS_M_u32	3498054144
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	63813
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	15811
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	16318
ISDATBSI3F2MsgTimer_mS_M_u32	2728161792
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	53459
ISDATBSI412MsgLenValidCount_Cnt_M_u16	61313
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	32903
ISDATBSI412MsgTimer_mS_M_u32	3569005056
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	12370
ISDATBSI432MsgLenValidCount_Cnt_M_u16	5656
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	10814
ISDATDIRASentFltAcc_Cnt_M_u16	34354
ISDATDIRASentTimer_mS_M_u32	2699801088
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	8438
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	31557
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	6097
ISDYN2CMMMsgTimer_mS_M_u32	132686336
ISDYNAASChkSumInvalidCount_Cnt_M_u16	52421
ISDYNAASChkSumValidCount_Cnt_M_u16	7215
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	51660
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	50184
ISDYNAASMsgLenValidCount_Cnt_M_u16	15595
ISDYNAASMsgTimeValidCount_Cnt_M_u16	52421
ISDYNAASMsgTimer_mS_M_u32	568361472
ISDYNABRChkSumInvalidCount_Cnt_M_u16	29461
ISDYNABRChkSumValidCount_Cnt_M_u16	2215
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	19916
ISDYNABRMsgCountValidCount_Cnt_M_u16	9334
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	13994
ISDYNABRMsgLenValidCount_Cnt_M_u16	17284
ISDYNABRMsgTimeValidCount_Cnt_M_u16	52840
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	602
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1089

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	16318
ISDYNCMM208MsgTimer_mS_M_u32	1847222784
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2259
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1195
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	3155
ISDYNCMM388MsgTimer_mS_M_u32	1455686144
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	61105
ISDYNVOLChkSumValidCount_Cnt_M_u16	49867
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	20056
ISDYNVOLMsgCountValidCount_Cnt_M_u16	14219
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	62509
ISDYNVOLMsgLenValidCount_Cnt_M_u16	33960
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	58222
ISDYNVOLMsgTimer_mS_M_u32	1037877760
IgnOnTimer_mS_M_u32	1537737216
IgnTimeOff_Sec_M_u32	3089868682
ManVehSpd_Kph_M_f32	465.852509
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	162
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	90
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	198341120
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	94
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2483180032
PrevISDATBSI412MsgDLCError_Cnt_M_u08	215
PrevISDATBSI412MsgRxTime_MSec_M_u32	4288758272
PrevISDATBSI432MsgDLCError_Cnt_M_u08	223
PrevISDATBSI432MsgRxTime_MSec_M_u32	1351787008
PrevISDATDIRAMsgTxTime_MSec_M_u32	714424832
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	183
PrevISDYN2CMMMsgRxTime_MSec_M_u32	889688576
PrevISDYNAASMsgDLCError_Cnt_M_u08	12
PrevISDYNAASMsgRxTime_MSec_M_u32	3630875136
PrevISDYNABRMsgDLCError_Cnt_M_u08	15
PrevISDYNABRMsgRxTime_MSec_M_u32	2497708544
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	19
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3787440640
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	187
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2747113984
PrevISDYNVOLMsgDLCError_Cnt_M_u08	254
PrevISDYNVOLMsgRxTime_MSec_M_u32	1993228800
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	835236352
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	415.993713
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	18710
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	4217
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	35983
VitesseVehicleBVRampValidCount_Cnt_M_u16	11442
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	61128
VitesseVehicleBVSigValidCount_Cnt_M_u16	8659
VitesseVehicleBV_Kph_M_f32	150.094193

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	3155
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	24597
VitesseVehiculeRoues_Kph_M_f32	293.652313
k_AASNTCEnableTimeout_mS_u16	51943
k_AASNodeAbsentDiag_Cnt_str.Threshold	63512
k_AASNodeAbsentDiag_Cnt_str.PStep	47974
k_AASNodeAbsentDiag_Cnt_str.NStep	37160
k_AASNodeAbsentTimeout_mS_u16	20200
k_AASNodeTimeout_mS_u16	4985
k_ABSNodeTimeout_mS_u16	65247
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	46389
k_ANGLEVOLANTSigValidThresh_Cnt_u16	36667
k_AngleVolantInvalidThresh_Cnt_u16	17930
k_AngleVolantValidThresh_Cnt_u16	49454
k_BSI552MsgTimeout_mS_u16	65444
k_BSINTCEnableTimeout_mS_u16	55690
k_BSINodeAbsentDiag_Cnt_str.Threshold	21492
k_BSINodeAbsentDiag_Cnt_str.PStep	36406
k_BSINodeAbsentDiag_Cnt_str.NStep	12451
k_BSINodeAbsentTimeout_mS_u16	7400
k_BSINodeTimeout_mS_u16	10814
k_BattOvHi_Volt_f32	15.2748003
k_BattOvLo_Volt_f32	19.6728992
k_BattUvHi_Volt_f32	28.0727997
k_BattUvLo_Volt_f32	7.01370001
k_CAVNTCEnableTimeout_mS_u16	32628
k_CAVNodeAbsentDiag_Cnt_str.Threshold	28401
k_CAVNodeAbsentDiag_Cnt_str.PStep	43679
k_CAVNodeAbsentDiag_Cnt_str.NStep	41558
k_CAVNodeAbsentTimeout_mS_u16	63915
k_CAVNodeTimeout_mS_u16	32191
k_CMM388MsgTimeout_mS_u16	1491
k_CMM388NTCEnableTimeout_mS_u16	25071
k_CMMNTCEnableTimeout_mS_u16	65149
k_CMMNodeAbsentDiag_Cnt_str.Threshold	63499
k_CMMNodeAbsentDiag_Cnt_str.PStep	5716
k_CMMNodeAbsentDiag_Cnt_str.NStep	37503
k_CMMNodeAbsentTimeout_mS_u16	37425
k_CONSANGLECPKMax_HwDeg_f32	450.397705
k_CONSANGLECPKMin_HwDeg_f32	-588.412903
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	53075
k_CONSANGLECPKSigValidThresh_Cnt_u16	25365
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	1487
k_CPKVehicleSpeedValidThresh_Cnt_u16	45310
k_CityParkInputInvalidThresh_Cnt_u16	49643
k_CityParkInputValidThresh_Cnt_u16	51497
k_ComputerRazGCTSigValidThresh_Cnt_u16	52475
k_CptTemporelSigValidThresh_Cnt_u16	36345
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	31146
k_DMDFCTCPKSigValidThresh_Cnt_u16	50820
k_DMDFCTCPKValidCount_Cnt_u16	4254
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	6097
k_DMDRELAXECPKSigValidThresh_Cnt_u16	22980
k_DMDRelaxeConsistentThresh_Cnt_u16	5658
k_DateValidThresh_Cnt_u16	57683
k_DefaultVehSpd_Kph_f32	141.718002
k_DiagMuxOnAbsentTimeout_mS_u16	3630
k_EMNodeTimeout_mS_u16	12256
k_ESPNTCEnableTimeout_mS_u16	1721
k_ESPNodeAbsentDiag_Cnt_str.Threshold	38670
k_ESPNodeAbsentDiag_Cnt_str.PStep	17590
k_ESPNodeAbsentDiag_Cnt_str.NStep	61830
k_ESPNodeAbsentTimeout_mS_u16	28921
k_EtatMTSigInvalidThresh_Cnt_u16	28612
k_EtatMTSigValidThresh_Cnt_u16	31382
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	15322
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	35824
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	16034
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	44866
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	26496
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	58295
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	49103
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	14677

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	48438
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	9900
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	32123
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	61061
k_ISDATDIRASentDiag_Cnt_str.Threshold	26522
k_ISDATDIRASentDiag_Cnt_str.PStep	18723
k_ISDATDIRASentDiag_Cnt_str.NStep	65245
k_ISDATDIRASentTimeout_mS_u16	48177
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	47962
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	432
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	9573
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	13845
k_ISDYNAASChkSumValidThresh_Cnt_u16	2983
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	37068
k_ISDYNAASMsgCountValidThresh_Cnt_u16	42870
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	11513
k_ISDYNAASMsgLenValidThresh_Cnt_u16	14685
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	52227
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	56760
k_ISDYNABRChkSumValidThresh_Cnt_u16	47378
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	7126
k_ISDYNABRMsgCountValidThresh_Cnt_u16	40289
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	58990
k_ISDYNABRMsgLenValidThresh_Cnt_u16	26932
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	25200
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	3834
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	10124
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	55816
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	11471
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	42778
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	57446
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	60982
k_ISDYNVOLChkSumValidThresh_Cnt_u16	24868
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	46097
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	9611
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	4771
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	28378
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	55321
k_IgnOnTimeout_mS_u16	11090
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	163.849396
k_PowerCutVehSpdLowThresh_Kph_f32	103.794701
k_PowerCutVehSpdLowTimeout_mS_u16	34291
k_VBattMaxAAS_Volt_f32	13.4013996
k_VBattMaxBSI_Volt_f32	23.8883991
k_VBattMaxCAV_Volt_f32	8.97859955
k_VBattMaxCMM388_Volt_f32	3.7190001
k_VBattMaxCMM_Volt_f32	7.8611002
k_VBattMaxESP_Volt_f32	27.1168003
k_VBattMinAAS_Volt_f32	8.24639988
k_VBattMinBSI_Volt_f32	27.1168003
k_VBattMinCAV_Volt_f32	19.8260994
k_VBattMinCMM388_Volt_f32	32
k_VBattMinCMM_Volt_f32	30.2194996
k_VBattMinESP_Volt_f32	7.8611002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	37892
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	4387
k_VitesseVehicleBVRampValidThresh_Cnt_u16	4440
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	17867
k_VitesseVehicleBVSigValidThresh_Cnt_u16	1498
k_VitesseVehicleBVSpeedPassThresh_kph_f32	107.488701
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	48285
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	60224
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2022957568
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	232
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16 Elaps	8427
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3050227456
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	187

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	5.21409988
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	980734464
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	107
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.377612114
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4104258048
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3400606208
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	237
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1620066816
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	213
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1044341248
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3955130880
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	82
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4044202496
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	247
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3593257472
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	36
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	100
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	170
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	212
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	23
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1595433472
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	44
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	58
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	110
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4260168192
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	207
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2138841600
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2161852928
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	72
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1359237632
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	624
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0847431123
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	486417
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	110.137703
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	31552

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3050227456	3050227456	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	63512	63512	✔
AASNodeAbsentTimer_mS_M_u32	3050227456	3050227456	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3050227456	3050227456	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3050227456	3050227456	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3050227456	3050227456	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3050227456	3050227456	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3050227456	3050227456	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21492	21492	✔
BSINodeAbsentTimer_mS_M_u32	3050227456	3050227456	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3050227456	3050227456	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3050227456	3050227456	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3050227456	3050227456	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3050227456	3050227456	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3050227456	3050227456	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	52840	52840	✔
CONSANGLECPK_HwDeg_M_f32	738.519104	738.519104 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3050227456	3050227456	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3050227456	3050227456	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3050227456	3050227456	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3050227456	3050227456	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3050227456	3050227456	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3050227456	3050227456	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3050227456	3050227456	✔
ESPNTCEnableTimer_mS_M_u32	3050227456	3050227456	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	38670	38670	✔
ESPNodeAbsentTimer_mS_M_u32	3050227456	3050227456	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	64	64	✔
EffacDefaultDiagTimer_mS_M_u32[1]	894	894	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	5	5	✔
ElecIntTimer_mS_M_u32[1]	55	55	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3050227456	3050227456	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3050227456	3050227456	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3050227456	3050227456	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3050227456	3050227456	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3050227456	3050227456	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3050227456	3050227456	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3050227456	3050227456	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3050227456	3050227456	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3050227456	3050227456	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3050227456	3050227456	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3050227456	3050227456	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3050227456	3050227456	✔
IgnOnTimer_mS_M_u32	3050227456	3050227456	✔
IgnTimeOff_Sec_M_u32	3089868682	3089868682	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	31	31	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4104258048	4104258048	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	136	136	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3400606208	3400606208	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	237	237	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1620066816	1620066816	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	213	213	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1044341248	1044341248	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	714424832	714424832	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	82	82	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4044202496	4044202496	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	247	247	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3593257472	3593257472	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	23	23	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1595433472	1595433472	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	26	26	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4260168192	4260168192	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	207	207	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2138841600	2138841600	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	63	63	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2161852928	2161852928	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1359237632	1359237632	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	415.993713	415.993713	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	150.094193	150.094193	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	293.652313	293.652313	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	52840	52840	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3089868682	3089868682	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	738.519104	738.519104 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	141.718002	141.718002	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.38 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3974147328
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	65133
AASNodeAbsentTimer_mS_M_u32	3664633088
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	7031
ANGLEVOLANTSigValidCount_Cnt_M_u16	57944
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	62934
AngleVolantMsgTimer_mS_M_u32	3974147328
AngleVolantValidCount_Cnt_M_u16	50582
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3033963776
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4226489600
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	387239168
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1645251840
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	10850
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2852867328
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	19597
CAVNodeAbsentTimer_mS_M_u32	1449524480
CDD_SrlComVehSpd_Kph_G_f32	514.713379
CMM388NTCEnableTimer_mS_M_u32	1138310400
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1986264320
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	60891
CMMNodeAbsentTimer_mS_M_u32	1318227200
CONSANGLECPKSigInvalidCount_Cnt_M_u16	32764
CONSANGLECPKSigValidCount_Cnt_M_u16	25837
CONSANGLECPK_Cnt_M_u16	36460
CONSANGLECPK_HwDeg_M_f32	128.866104
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	36460
CPKVehicleSpeedMsgTimer_mS_M_u32	1713614080
CPKVehicleSpeedValidCount_Cnt_M_u16	24359
CityParkInputConsistentCount_Cnt_M_u16	27626
CityParkInputInvalidCount_Cnt_M_u16	10459

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	4104258048
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	365026560
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	58049
ComputerRazGCTSigInvalidTimer_mS_M_u32	887389440
ComputerRazGCTSigValidCount_Cnt_M_u16	63787
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	61063
DMDFCTCPKSigValidCount_Cnt_M_u16	46127
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	27041
DMDRELAXECPKSigValidCount_Cnt_M_u16	23554
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	52325
DateInvalidTimer_mS_M_u32	4226489600
DiagMuxOnAbsentTimer_mS_M_u32	2822466816
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1645251840
ESPNTCEnableTimer_mS_M_u32	3387612416
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	35655
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1123
EffacDefaultDiagTimer_mS_M_u32[1]	5523
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	977
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2836745472
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	2959
EtatMTSigValidCount_Cnt_M_u16	62380
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	52262
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	23703
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	9773
ISDAT4V2BSI552MsgTimer_mS_M_u32	551980288
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	52951
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	18204
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	62380
ISDATBSI3F2MsgTimer_mS_M_u32	336686336
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	20780
ISDATBSI412MsgLenValidCount_Cnt_M_u16	64225
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	2959
ISDATBSI412MsgTimer_mS_M_u32	3333860608
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	38703
ISDATBSI432MsgLenValidCount_Cnt_M_u16	19355
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	32426
ISDATDIRASentFltAcc_Cnt_M_u16	15054
ISDATDIRASentTimer_mS_M_u32	1713614080
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	20162
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	50582
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	28914
ISDYN2CMMMsgTimer_mS_M_u32	2431442176
ISDYNAASChkSumInvalidCount_Cnt_M_u16	10391
ISDYNAASChkSumValidCount_Cnt_M_u16	12311
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	46593
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	22860
ISDYNAASMsgLenValidCount_Cnt_M_u16	50276
ISDYNAASMsgTimeValidCount_Cnt_M_u16	10391
ISDYNAASMsgTimer_mS_M_u32	2055552256
ISDYNABRChkSumInvalidCount_Cnt_M_u16	52519
ISDYNABRChkSumValidCount_Cnt_M_u16	41520
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	33154
ISDYNABRMsgCountValidCount_Cnt_M_u16	62274
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	4071
ISDYNABRMsgLenValidCount_Cnt_M_u16	40728
ISDYNABRMsgTimeValidCount_Cnt_M_u16	36460
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	603
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1091

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	62380
ISDYNCMM208MsgTimer_mS_M_u32	1431805184
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2263
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1197
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	51820
ISDYNCMM388MsgTimer_mS_M_u32	3386555648
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	50130
ISDYNVOLChkSumValidCount_Cnt_M_u16	64835
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	43357
ISDYNVOLMsgCountValidCount_Cnt_M_u16	901
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	17756
ISDYNVOLMsgLenValidCount_Cnt_M_u16	51629
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	60891
ISDYNVOLMsgTimer_mS_M_u32	1737522432
IgnOnTimer_mS_M_u32	1261354240
IgnTimeOff_Sec_M_u32	2293948243
ManVehSpd_Kph_M_f32	184.071594
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	164
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	162
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	812608768
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	46
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2942291200
PrevISDATBSI412MsgDLCError_Cnt_M_u08	112
PrevISDATBSI412MsgRxTime_MSec_M_u32	3561159936
PrevISDATBSI432MsgDLCError_Cnt_M_u08	71
PrevISDATBSI432MsgRxTime_MSec_M_u32	3740196096
PrevISDATDIRAMsgTxTime_MSec_M_u32	593952000
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	136
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1901071616
PrevISDYNAASMsgDLCError_Cnt_M_u08	57
PrevISDYNAASMsgRxTime_MSec_M_u32	1340505344
PrevISDYNABRMsgDLCError_Cnt_M_u08	88
PrevISDYNABRMsgRxTime_MSec_M_u32	2139536640
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	235
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3353836800
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	251
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1366154496
PrevISDYNVOLMsgDLCError_Cnt_M_u08	148
PrevISDYNVOLMsgRxTime_MSec_M_u32	1656487168
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1737272576
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	277.884796
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	33314
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	442
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	56247
VitesseVehicleBVRampValidCount_Cnt_M_u16	53519
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	12428
VitesseVehicleBVSigValidCount_Cnt_M_u16	3373
VitesseVehicleBV_Kph_M_f32	642.296387

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	51820
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	9445
VitesseVehiculeRoues_Kph_M_f32	502.616608
k_AASNTCEnableTimeout_mS_u16	21743
k_AASNodeAbsentDiag_Cnt_str.Threshold	15391
k_AASNodeAbsentDiag_Cnt_str.PStep	40078
k_AASNodeAbsentDiag_Cnt_str.NStep	64919
k_AASNodeAbsentTimeout_mS_u16	38573
k_AASNodeTimeout_mS_u16	63674
k_ABSNodeTimeout_mS_u16	29640
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	21638
k_ANGLEVOLANTSigValidThresh_Cnt_u16	11314
k_AngleVolantInvalidThresh_Cnt_u16	965
k_AngleVolantValidThresh_Cnt_u16	10459
k_BSI552MsgTimeout_mS_u16	16952
k_BSINTCEnableTimeout_mS_u16	31623
k_BSINodeAbsentDiag_Cnt_str.Threshold	21532
k_BSINodeAbsentDiag_Cnt_str.PStep	36389
k_BSINodeAbsentDiag_Cnt_str.NStep	12474
k_BSINodeAbsentTimeout_mS_u16	33838
k_BSINodeTimeout_mS_u16	32426
k_BattOvHi_Volt_f32	15.6400995
k_BattOvLo_Volt_f32	24.6310005
k_BattUvHi_Volt_f32	30.6299
k_BattUvLo_Volt_f32	21.4122009
k_CAVNTCEnableTimeout_mS_u16	34313
k_CAVNodeAbsentDiag_Cnt_str.Threshold	43191
k_CAVNodeAbsentDiag_Cnt_str.PStep	64769
k_CAVNodeAbsentDiag_Cnt_str.NStep	1061
k_CAVNodeAbsentTimeout_mS_u16	1123
k_CAVNodeTimeout_mS_u16	52904
k_CMM388MsgTimeout_mS_u16	13677
k_CMM388NTCEnableTimeout_mS_u16	37145
k_CMMNTCEnableTimeout_mS_u16	40751
k_CMMNodeAbsentDiag_Cnt_str.Threshold	15984
k_CMMNodeAbsentDiag_Cnt_str.PStep	31660
k_CMMNodeAbsentDiag_Cnt_str.NStep	4191
k_CMMNodeAbsentTimeout_mS_u16	65169
k_CONSANGLECPKMax_HwDeg_f32	414.908295
k_CONSANGLECPKMin_HwDeg_f32	-400.930115
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	33132
k_CONSANGLECPKSigValidThresh_Cnt_u16	7141
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	63928
k_CPKVehicleSpeedValidThresh_Cnt_u16	7339
k_CityParkInputInvalidThresh_Cnt_u16	47269
k_CityParkInputValidThresh_Cnt_u16	27626
k_ComputerRazGCTSigValidThresh_Cnt_u16	43957
k_CptTemporelSigValidThresh_Cnt_u16	44666
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	18151
k_DMDFCTCPKSigValidThresh_Cnt_u16	5656
k_DMDFCTCPKValidCount_Cnt_u16	41738
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	28914
k_DMDRELAXECPKSigValidThresh_Cnt_u16	49370
k_DMDRelaxeConsistentThresh_Cnt_u16	25560
k_DateValidThresh_Cnt_u16	9773
k_DefaultVehSpd_Kph_f32	120.247299
k_DiagMuxOnAbsentTimeout_mS_u16	26394
k_EMNodeTimeout_mS_u16	31813
k_ESPNTCEnableTimeout_mS_u16	38201
k_ESPNodeAbsentDiag_Cnt_str.Threshold	5964
k_ESPNodeAbsentDiag_Cnt_str.PStep	4321
k_ESPNodeAbsentDiag_Cnt_str.NStep	32099
k_ESPNodeAbsentTimeout_mS_u16	33337
k_EtatMTSigInvalidThresh_Cnt_u16	21274
k_EtatMTSigValidThresh_Cnt_u16	51299
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	17303
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	63764
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	12159
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	57568
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	64997
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	43136
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	7352
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	5604

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	32899
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	38304
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	5876
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	37141
k_ISDATDIRASentDiag_Cnt_str.Threshold	59301
k_ISDATDIRASentDiag_Cnt_str.PStep	2209
k_ISDATDIRASentDiag_Cnt_str.NStep	62944
k_ISDATDIRASentTimeout_mS_u16	25043
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	48790
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	62934
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	59701
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	33831
k_ISDYNAASChkSumValidThresh_Cnt_u16	39216
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	47234
k_ISDYNAASMsgCountValidThresh_Cnt_u16	27202
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	12155
k_ISDYNAASMsgLenValidThresh_Cnt_u16	5902
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	38362
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	53949
k_ISDYNABRChkSumValidThresh_Cnt_u16	63086
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	24930
k_ISDYNABRMsgCountValidThresh_Cnt_u16	21123
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	58587
k_ISDYNABRMsgLenValidThresh_Cnt_u16	49735
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	65366
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	49270
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	28929
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	41229
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	21111
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	22872
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	43827
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	17667
k_ISDYNVOLChkSumValidThresh_Cnt_u16	61944
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	38320
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	56196
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	50491
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	54872
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	55771
k_IgnOnTimeout_mS_u16	64943
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	68.3532028
k_PowerCutVehSpdLowThresh_Kph_f32	64.5173035
k_PowerCutVehSpdLowTimeout_mS_u16	21451
k_VBattMaxAAS_Volt_f32	0.453099996
k_VBattMaxBSI_Volt_f32	8.5017004
k_VBattMaxCAV_Volt_f32	9.43519974
k_VBattMaxCMM388_Volt_f32	11.099
k_VBattMaxCMM_Volt_f32	5.3435998
k_VBattMaxESP_Volt_f32	1.04030001
k_VBattMinAAS_Volt_f32	26.9719009
k_VBattMinBSI_Volt_f32	1.04030001
k_VBattMinCAV_Volt_f32	6.50899982
k_VBattMinCMM388_Volt_f32	14.8556995
k_VBattMinCMM_Volt_f32	7.07210016
k_VBattMinESP_Volt_f32	5.3435998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	23704
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	43773
k_VitesseVehicleBVRampValidThresh_Cnt_u16	24669
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	29763
k_VitesseVehicleBVSigValidThresh_Cnt_u16	47575
k_VitesseVehicleBVSpeedPassThresh_kph_f32	470.786011
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	909
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	19813
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	4226489600
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	114
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	48732
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2695592192
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	251

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	1.90769994
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2785561856
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	13
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.9787063
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	78
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3896556800
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	23
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	177429760
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	762707200
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	247
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3102252288
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	350960896
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2843598080
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	161
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3735059712
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	102
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	103
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	151
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	229
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	214
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4200439040
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	162
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3093282048
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3627179264
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3096771840
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	119
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	5885184
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3620
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.336374134
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	785940
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	16.7381992
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	5028

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2695592192	2695592192	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	15391	15391	✔
AASNodeAbsentTimer_mS_M_u32	2695592192	2695592192	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	62934	62934	✔
AngleVolantMsgTimer_mS_M_u32	2695592192	2695592192	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2695592192	2695592192	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2695592192	2695592192	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2695592192	2695592192	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2695592192	2695592192	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21532	21532	✔
BSINodeAbsentTimer_mS_M_u32	2695592192	2695592192	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2695592192	2695592192	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2695592192	2695592192	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2695592192	2695592192	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2695592192	2695592192	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	15984	15984	✔
CMMNodeAbsentTimer_mS_M_u32	2695592192	2695592192	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	36460	36460	✔
CONSANGLECPK_HwDeg_M_f32	128.866104	128.866104 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	36460	36460	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1713614080	1713614080	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	24359	24359	✔
CityParkInputConsistentCount_Cnt_M_u16	27626	27626	✔
CityParkInputInvalidCount_Cnt_M_u16	10461	10461	✔
CityParkInputMsgTimer_mS_M_u32	2695592192	2695592192	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2695592192	2695592192	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2695592192	2695592192	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2695592192	2695592192	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2695592192	2695592192	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2695592192	2695592192	✔
ESPNTCEnableTimer_mS_M_u32	2695592192	2695592192	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2695592192	2695592192	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1123	1123	✔
EffacDefaultDiagTimer_mS_M_u32[1]	5523	5523	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	2695592192	2695592192	✔
ElecIntTimer_mS_M_u32[1]	977	977	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2695592192	2695592192	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2695592192	2695592192	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2695592192	2695592192	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2695592192	2695592192	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2695592192	2695592192	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2695592192	2695592192	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2695592192	2695592192	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2695592192	2695592192	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2695592192	2695592192	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2695592192	2695592192	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2695592192	2695592192	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2695592192	2695592192	✔
IgnOnTimer_mS_M_u32	1261354240	1261354240	✔
IgnTimeOff_Sec_M_u32	2293948243	2293948243	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	78	78	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3896556800	3896556800	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	23	23	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	177429760	177429760	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	45	45	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	762707200	762707200	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	247	247	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3102252288	3102252288	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	593952000	593952000	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2843598080	2843598080	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	161	161	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3735059712	3735059712	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	214	214	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4200439040	4200439040	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	72	72	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3093282048	3093282048	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	46	46	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3627179264	3627179264	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3096771840	3096771840	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	5885184	5885184	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	277.884796	277.884796	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	642.296387	642.296387	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	502.616608	502.616608	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	36460	36460	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2293948243	2293948243	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	128.866104	128.866104 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.39 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2750462976
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	16715
AASNodeAbsentTimer_mS_M_u32	3423153152
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	13355
ANGLEVOLANTSigValidCount_Cnt_M_u16	32329
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	16144
AngleVolantMsgTimer_mS_M_u32	2750462976
AngleVolantValidCount_Cnt_M_u16	6734
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3486444544
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3968953344
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2647940096
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1541479424
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	29546
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3740326912
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	32618
CAVNodeAbsentTimer_mS_M_u32	3768634368
CDD_SrlComVehSpd_Kph_G_f32	398.788391
CMM388NTCEnableTimer_mS_M_u32	4115074048
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	4171680768
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	32577
CMMNodeAbsentTimer_mS_M_u32	509287424
CONSANGLECPKSigInvalidCount_Cnt_M_u16	2461
CONSANGLECPKSigValidCount_Cnt_M_u16	14731
CONSANGLECPK_Cnt_M_u16	30990
CONSANGLECPK_HwDeg_M_f32	498.484314
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	30990
CPKVehicleSpeedMsgTimer_mS_M_u32	69712896
CPKVehicleSpeedValidCount_Cnt_M_u16	29858
CityParkInputConsistentCount_Cnt_M_u16	30546

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	20865
CityParkInputMsgTimer_mS_M_u32	3896556800
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1779248128
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	58447
ComputerRazGCTSigInvalidTimer_mS_M_u32	1596279808
ComputerRazGCTSigValidCount_Cnt_M_u16	5007
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	45181
DMDFCTCPKSigValidCount_Cnt_M_u16	7747
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	29101
DMDRELAXECPKSigValidCount_Cnt_M_u16	14667
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	2146
DateInvalidTimer_mS_M_u32	3968953344
DiagMuxOnAbsentTimer_mS_M_u32	1289780224
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1541479424
ESPNTCEnableTimer_mS_M_u32	831663104
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	30138
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	54
EffacDefaultDiagTimer_mS_M_u32[1]	64
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	6
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2312297472
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	18212
EtatMTSigValidCount_Cnt_M_u16	7566
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	19743
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	31373
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	16457
ISDAT4V2BSI552MsgTimer_mS_M_u32	4150205440
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	29900
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	15038
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	7566
ISDATBSI3F2MsgTimer_mS_M_u32	3781065728
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	53964
ISDATBSI412MsgLenValidCount_Cnt_M_u16	50286
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	18212
ISDATBSI412MsgTimer_mS_M_u32	4000234496
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	54085
ISDATBSI432MsgLenValidCount_Cnt_M_u16	33982
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	40211
ISDATDIRASentFltAcc_Cnt_M_u16	63655
ISDATDIRASentTimer_mS_M_u32	69712896
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	4108
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	6734
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	38204
ISDYN2CMMMsgTimer_mS_M_u32	1686907904
ISDYNAASChkSumInvalidCount_Cnt_M_u16	60109
ISDYNAASChkSumValidCount_Cnt_M_u16	62219
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	46349
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	5421
ISDYNAASMsgLenValidCount_Cnt_M_u16	21155
ISDYNAASMsgTimeValidCount_Cnt_M_u16	60109
ISDYNAASMsgTimer_mS_M_u32	21171200
ISDYNABRChkSumInvalidCount_Cnt_M_u16	13980
ISDYNABRChkSumValidCount_Cnt_M_u16	63042
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	19468
ISDYNABRMsgCountValidCount_Cnt_M_u16	5514
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	50652
ISDYNABRMsgLenValidCount_Cnt_M_u16	63242
ISDYNABRMsgTimeValidCount_Cnt_M_u16	30990
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	604

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1093
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	7566
ISDYNCMM208MsgTimer_mS_M_u32	843836416
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2267
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1199
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	58316
ISDYNCMM388MsgTimer_mS_M_u32	1229097984
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	5659
ISDYNVOLChkSumValidCount_Cnt_M_u16	18569
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	22523
ISDYNVOLMsgCountValidCount_Cnt_M_u16	2113
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	56187
ISDYNVOLMsgLenValidCount_Cnt_M_u16	44361
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	32577
ISDYNVOLMsgTimer_mS_M_u32	1998670848
IgnOnTimer_mS_M_u32	356944896
IgnTimeOff_Sec_M_u32	49226300
ManVehSpd_Kph_M_f32	654.254211
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	166
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2219080704
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	168
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3237174272
PrevISDATBSI412MsgDLCError_Cnt_M_u08	217
PrevISDATBSI412MsgRxTime_MSec_M_u32	453626880
PrevISDATBSI432MsgDLCError_Cnt_M_u08	139
PrevISDATBSI432MsgRxTime_MSec_M_u32	42347520
PrevISDATDIRAMsgTxTime_MSec_M_u32	3181235200
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	105
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2351078400
PrevISDYNAASMsgDLCError_Cnt_M_u08	77
PrevISDYNAASMsgRxTime_MSec_M_u32	2518633472
PrevISDYNABRMsgDLCError_Cnt_M_u08	118
PrevISDYNABRMsgRxTime_MSec_M_u32	3627977728
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	219
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1914457088
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	149
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1728654336
PrevISDYNVOLMsgDLCError_Cnt_M_u08	161
PrevISDYNVOLMsgRxTime_MSec_M_u32	2476657664
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3823942656
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	540.10437
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	29355
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	29345
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	63980
VitesseVehicleBVRampValidCount_Cnt_M_u16	39074
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	35052
VitesseVehicleBVSigValidCount_Cnt_M_u16	37322

Name	Input Value
VitesseVehicleBV_Kph_M_f32	90.3904037
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	58316
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	54050
VitesseVehiculeRoues_Kph_M_f32	292.786407
k_AASNTCEnableTimeout_mS_u16	61829
k_AASNodeAbsentDiag_Cnt_str.Threshold	58901
k_AASNodeAbsentDiag_Cnt_str.PStep	37054
k_AASNodeAbsentDiag_Cnt_str.NStep	45532
k_AASNodeAbsentTimeout_mS_u16	49929
k_AASNodeTimeout_mS_u16	36257
k_ABSNodeTimeout_mS_u16	25786
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	46912
k_ANGLEVOLANTSigValidThresh_Cnt_u16	65273
k_AngleVolantInvalidThresh_Cnt_u16	33856
k_AngleVolantValidThresh_Cnt_u16	20865
k_BSI552MsgTimeout_mS_u16	34601
k_BSINTCEnableTimeout_mS_u16	34365
k_BSINodeAbsentDiag_Cnt_str.Threshold	21572
k_BSINodeAbsentDiag_Cnt_str.PStep	36372
k_BSINodeAbsentDiag_Cnt_str.NStep	12497
k_BSINodeAbsentTimeout_mS_u16	62472
k_BSINodeTimeout_mS_u16	40211
k_BattOvHi_Volt_f32	30.8794003
k_BattOvLo_Volt_f32	2.35170007
k_BattUvHi_Volt_f32	20.7588997
k_BattUvLo_Volt_f32	5.59689999
k_CAVNTCEnableTimeout_mS_u16	29175
k_CAVNodeAbsentDiag_Cnt_str.Threshold	37347
k_CAVNodeAbsentDiag_Cnt_str.PStep	52287
k_CAVNodeAbsentDiag_Cnt_str.NStep	19531
k_CAVNodeAbsentTimeout_mS_u16	12264
k_CAVNodeTimeout_mS_u16	52633
k_CMM388MsgTimeout_mS_u16	40011
k_CMM388NTCEnableTimeout_mS_u16	14663
k_CMMNTCEnableTimeout_mS_u16	25540
k_CMMNodeAbsentDiag_Cnt_str.Threshold	6912
k_CMMNodeAbsentDiag_Cnt_str.PStep	45125
k_CMMNodeAbsentDiag_Cnt_str.NStep	44900
k_CMMNodeAbsentTimeout_mS_u16	63006
k_CONSANGLECPKMax_HwDeg_f32	538.680176
k_CONSANGLECPKMin_HwDeg_f32	-39.9928017
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	48844
k_CONSANGLECPKSigValidThresh_Cnt_u16	60962
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	679
k_CPKVehicleSpeedValidThresh_Cnt_u16	11343
k_CityParkInputInvalidThresh_Cnt_u16	60450
k_CityParkInputValidThresh_Cnt_u16	30546
k_ComputerRazGCTSigValidThresh_Cnt_u16	54834
k_CptTemporelSigValidThresh_Cnt_u16	64676
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	8412
k_DMDFCTCPKSigValidThresh_Cnt_u16	37386
k_DMDFCTCPKValidCount_Cnt_u16	43378
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	38204
k_DMDRELAXECPKSigValidThresh_Cnt_u16	25666
k_DMDRelaxeConsistentThresh_Cnt_u16	62280
k_DateValidThresh_Cnt_u16	16457
k_DefaultVehSpd_Kph_f32	68.3314972
k_DiagMuxOnAbsentTimeout_mS_u16	9988
k_EMNodeTimeout_mS_u16	30914
k_ESPNTCEnableTimeout_mS_u16	21862
k_ESPNodeAbsentDiag_Cnt_str.Threshold	28109
k_ESPNodeAbsentDiag_Cnt_str.PStep	49926
k_ESPNodeAbsentDiag_Cnt_str.NStep	34743
k_ESPNodeAbsentTimeout_mS_u16	2854
k_EtatMTSigInvalidThresh_Cnt_u16	12483
k_EtatMTSigValidThresh_Cnt_u16	4009
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	24842
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	20308
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	49299
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	41649
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	31331
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	7376
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	42666

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	35299
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	26441
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	13170
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	7732
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	18449
k_ISDATDIRASentDiag_Cnt_str.Threshold	5018
k_ISDATDIRASentDiag_Cnt_str.PStep	29661
k_ISDATDIRASentDiag_Cnt_str.NStep	28056
k_ISDATDIRASentTimeout_mS_u16	10392
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	910
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	16144
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	18802
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	4508
k_ISDYNAASChkSumValidThresh_Cnt_u16	4418
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	42764
k_ISDYNAASMsgCountValidThresh_Cnt_u16	45194
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	24480
k_ISDYNAASMsgLenValidThresh_Cnt_u16	33445
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	25089
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	21850
k_ISDYNABRChkSumValidThresh_Cnt_u16	51464
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	52842
k_ISDYNABRMsgCountValidThresh_Cnt_u16	39368
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	39489
k_ISDYNABRMsgLenValidThresh_Cnt_u16	53434
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	40783
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	1967
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	1869
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	41128
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	36651
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	6473
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	10873
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	4935
k_ISDYNVOLChkSumValidThresh_Cnt_u16	64297
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	14975
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	39494
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	51744
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	9610
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	23871
k_IgnOnTimeout_mS_u16	39235
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	180.513596
k_PowerCutVehSpdLowThresh_Kph_f32	232.021393
k_PowerCutVehSpdLowTimeout_mS_u16	25841
k_VBattMaxAAS_Volt_f32	10.8963003
k_VBattMaxBSI_Volt_f32	0.221000001
k_VBattMaxCAV_Volt_f32	29.8083
k_VBattMaxCMM388_Volt_f32	1.16279995
k_VBattMaxCMM_Volt_f32	31.4162006
k_VBattMaxESP_Volt_f32	15.9343996
k_VBattMinAAS_Volt_f32	30.1788006
k_VBattMinBSI_Volt_f32	15.9343996
k_VBattMinCAV_Volt_f32	15.7384005
k_VBattMinCMM388_Volt_f32	12.4188995
k_VBattMinCMM_Volt_f32	17.8195992
k_VBattMinESP_Volt_f32	31.4162006
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	45448
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	29978
k_VitesseVehicleBVRampValidThresh_Cnt_u16	13051
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	58249
k_VitesseVehicleBVSigValidThresh_Cnt_u16	33163
k_VitesseVehicleBVSpeedPassThresh_kph_f32	190.222595
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	23146
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	64416
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3968953344
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	85
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	45861
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	46159872
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	149
target_SrlComInput_Per1_Batt_Volt_f32.value	7.78590012
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	519691264
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	251
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0663513094
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	101747712
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	184
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2979572736
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2607860736
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2342054912
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1242631168
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2665032704
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1374768128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	135
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	167
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	218
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	220
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	230
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	248
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	52
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3678006272
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	134
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	229
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3518204928
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	175
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2226891776
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	907267072
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	11
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	28
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	30
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	68
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	172
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	187
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	906320896
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1517
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.23634693
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	588367
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	205.608597

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	17957		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	46159872	46159872	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	58901	58901	✔
AASNodeAbsentTimer_mS_M_u32	46159872	46159872	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	16146	16146	✔
AngleVolantMsgTimer_mS_M_u32	46159872	46159872	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	46159872	46159872	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	46159872	46159872	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	46159872	46159872	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	46159872	46159872	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21572	21572	✔
BSINodeAbsentTimer_mS_M_u32	46159872	46159872	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	46159872	46159872	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	46159872	46159872	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	46159872	46159872	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	46159872	46159872	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	6912	6912	✔
CMMNodeAbsentTimer_mS_M_u32	46159872	46159872	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	30990	30990	✔
CONSANGLECPK_HwDeg_M_f32	498.484314	498.484314 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	30990	30990	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	69712896	69712896	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	29858	29858	✔
CityParkInputConsistentCount_Cnt_M_u16	30546	30546	✔
CityParkInputInvalidCount_Cnt_M_u16	20867	20867	✔
CityParkInputMsgTimer_mS_M_u32	46159872	46159872	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	46159872	46159872	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	46159872	46159872	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	46159872	46159872	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	46159872	46159872	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	46159872	46159872	✔
ESPNTCEnableTimer_mS_M_u32	46159872	46159872	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	46159872	46159872	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	54	54	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	64	64	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	46159872	46159872	✔
ElecIntTimer_mS_M_u32[1]	6	6	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	46159872	46159872	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	46159872	46159872	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	46159872	46159872	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	46159872	46159872	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	46159872	46159872	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	46159872	46159872	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	46159872	46159872	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	46159872	46159872	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	46159872	46159872	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	46159872	46159872	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	46159872	46159872	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	46159872	46159872	✔
IgnOnTimer_mS_M_u32	356944896	356944896	✔
IgnTimeOff_Sec_M_u32	49226300	49226300	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	33	33	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	101747712	101747712	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	184	184	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2979572736	2979572736	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	170	170	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2607860736	2607860736	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	190	190	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2342054912	2342054912	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3181235200	3181235200	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2665032704	2665032704	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	152	152	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1374768128	1374768128	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	52	52	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3678006272	3678006272	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	113	113	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3518204928	3518204928	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	175	175	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2226891776	2226891776	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	9	9	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	907267072	907267072	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	906320896	906320896	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	540.10437	540.10437	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	90.3904037	90.3904037	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	292.786407	292.786407	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	30990	30990	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	49226300	49226300	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	498.484314	498.484314 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.40 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2512162560
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	18349
AASNodeAbsentTimer_mS_M_u32	1261649664
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	37131
ANGLEVOLANTSigValidCount_Cnt_M_u16	54897
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	41566
AngleVolantMsgTimer_mS_M_u32	2512162560
AngleVolantValidCount_Cnt_M_u16	12579
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2262957824
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1520074496
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1049734912
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	661352192
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	36686
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2369531648
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	5070
CAVNodeAbsentTimer_mS_M_u32	1944870656
CDD_SrlComVehSpd_Kph_G_f32	33.7790985
CMM388NTCEnableTimer_mS_M_u32	2667159296
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3285868288
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	26891
CMMNodeAbsentTimer_mS_M_u32	1207791360
CONSANGLECPKSigInvalidCount_Cnt_M_u16	1974
CONSANGLECPKSigValidCount_Cnt_M_u16	56236
CONSANGLECPK_Cnt_M_u16	59683
CONSANGLECPK_HwDeg_M_f32	157.839096
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	59683
CPKVehicleSpeedMsgTimer_mS_M_u32	286756608
CPKVehicleSpeedValidCount_Cnt_M_u16	52493
CityParkInputConsistentCount_Cnt_M_u16	10775
CityParkInputInvalidCount_Cnt_M_u16	26761

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	101747712
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2166832896
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	28321
ComputerRazGCTSigInvalidTimer_mS_M_u32	2858344192
ComputerRazGCTSigValidCount_Cnt_M_u16	35168
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	15253
DMDFCTCPKSigValidCount_Cnt_M_u16	46596
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	24709
DMDRELAXECPKSigValidCount_Cnt_M_u16	11627
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	24423
DateInvalidTimer_mS_M_u32	1520074496
DiagMuxOnAbsentTimer_mS_M_u32	166547200
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	661352192
ESPNTCEnableTimer_mS_M_u32	2123906816
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	6493
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	19
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2492870400
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	44641
EtatMTSigValidCount_Cnt_M_u16	32484
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	50480
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	41126
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	59378
ISDAT4V2BSI552MsgTimer_mS_M_u32	3438374656
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	48872
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	57554
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	32484
ISDATBSI3F2MsgTimer_mS_M_u32	3295891200
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	62951
ISDATBSI412MsgLenValidCount_Cnt_M_u16	21698
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	44641
ISDATBSI412MsgTimer_mS_M_u32	776113920
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	31999
ISDATBSI432MsgLenValidCount_Cnt_M_u16	64593
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	40659
ISDATDIRASentFltAcc_Cnt_M_u16	56343
ISDATDIRASentTimer_mS_M_u32	286756608
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	39977
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	12579
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	18776
ISDYN2CMMMsgTimer_mS_M_u32	1303002880
ISDYNAASChkSumInvalidCount_Cnt_M_u16	54055
ISDYNAASChkSumValidCount_Cnt_M_u16	24109
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	7398
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	7813
ISDYNAASMsgLenValidCount_Cnt_M_u16	59875
ISDYNAASMsgTimeValidCount_Cnt_M_u16	54055
ISDYNAASMsgTimer_mS_M_u32	1795530496
ISDYNABRChkSumInvalidCount_Cnt_M_u16	17210
ISDYNABRChkSumValidCount_Cnt_M_u16	18440
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	27498
ISDYNABRMsgCountValidCount_Cnt_M_u16	45744
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	36601
ISDYNABRMsgLenValidCount_Cnt_M_u16	24367
ISDYNABRMsgTimeValidCount_Cnt_M_u16	59683
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	605
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1095

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	32484
ISDYNCMM208MsgTimer_mS_M_u32	2473262848
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2271
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1201
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	19625
ISDYNCMM388MsgTimer_mS_M_u32	4043775744
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	23100
ISDYNVOLChkSumValidCount_Cnt_M_u16	9906
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	48411
ISDYNVOLMsgCountValidCount_Cnt_M_u16	28682
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	11290
ISDYNVOLMsgLenValidCount_Cnt_M_u16	39536
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	26891
ISDYNVOLMsgTimer_mS_M_u32	1382735616
IgnOnTimer_mS_M_u32	2633703168
IgnTimeOff_Sec_M_u32	574670911
ManVehSpd_Kph_M_f32	164.080597
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	168
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	173
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4089532160
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	46
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	288665344
PrevISDATBSI412MsgDLCError_Cnt_M_u08	181
PrevISDATBSI412MsgRxTime_MSec_M_u32	2830196480
PrevISDATBSI432MsgDLCError_Cnt_M_u08	249
PrevISDATBSI432MsgRxTime_MSec_M_u32	3686547200
PrevISDATDIRAMsgTxTime_MSec_M_u32	284516096
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	122
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2091314944
PrevISDYNAASMsgDLCError_Cnt_M_u08	237
PrevISDYNAASMsgRxTime_MSec_M_u32	1836113664
PrevISDYNABRMsgDLCError_Cnt_M_u08	226
PrevISDYNABRMsgRxTime_MSec_M_u32	873668352
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	81
PrevISDYNCMM208MsgRxTime_MSec_M_u32	226090752
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	102
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2050178816
PrevISDYNVOLMsgDLCError_Cnt_M_u08	192
PrevISDYNVOLMsgRxTime_MSec_M_u32	3539099392
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3318255360
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	4.66069984
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	32267
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	489
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	11336
VitesseVehicleBVRampValidCount_Cnt_M_u16	54246
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	54984
VitesseVehicleBVSigValidCount_Cnt_M_u16	57326
VitesseVehicleBV_Kph_M_f32	79.5800018

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	19625
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	33383
VitesseVehiculeRoues_Kph_M_f32	122.322601
k_AASNTCEnableTimeout_mS_u16	7102
k_AASNodeAbsentDiag_Cnt_str.Threshold	49070
k_AASNodeAbsentDiag_Cnt_str.PStep	15307
k_AASNodeAbsentDiag_Cnt_str.NStep	60361
k_AASNodeAbsentTimeout_mS_u16	58098
k_AASNodeTimeout_mS_u16	45289
k_ABSNodeTimeout_mS_u16	21214
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	32014
k_ANGLEVOLANTSigValidThresh_Cnt_u16	14752
k_AngleVolantInvalidThresh_Cnt_u16	34251
k_AngleVolantValidThresh_Cnt_u16	26761
k_BSI552MsgTimeout_mS_u16	16978
k_BSINTCEnableTimeout_mS_u16	17431
k_BSINodeAbsentDiag_Cnt_str.Threshold	21612
k_BSINodeAbsentDiag_Cnt_str.PStep	36355
k_BSINodeAbsentDiag_Cnt_str.NStep	12520
k_BSINodeAbsentTimeout_mS_u16	25462
k_BSINodeTimeout_mS_u16	40659
k_BattOvHi_Volt_f32	23.4995003
k_BattOvLo_Volt_f32	16.2479992
k_BattUvHi_Volt_f32	14.3150997
k_BattUvLo_Volt_f32	25.7458992
k_CAVNTCEnableTimeout_mS_u16	24359
k_CAVNodeAbsentDiag_Cnt_str.Threshold	18299
k_CAVNodeAbsentDiag_Cnt_str.PStep	53952
k_CAVNodeAbsentDiag_Cnt_str.NStep	29236
k_CAVNodeAbsentTimeout_mS_u16	31316
k_CAVNodeTimeout_mS_u16	43970
k_CMM388MsgTimeout_mS_u16	13997
k_CMM388NTCEnableTimeout_mS_u16	20409
k_CMMNTCEnableTimeout_mS_u16	53760
k_CMMNodeAbsentDiag_Cnt_str.Threshold	60747
k_CMMNodeAbsentDiag_Cnt_str.PStep	9878
k_CMMNodeAbsentDiag_Cnt_str.NStep	53649
k_CMMNodeAbsentTimeout_mS_u16	2419
k_CONSANGLECPKMax_HwDeg_f32	652.391174
k_CONSANGLECPKMin_HwDeg_f32	-232.024307
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	48041
k_CONSANGLECPKSigValidThresh_Cnt_u16	12647
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	59863
k_CPKVehicleSpeedValidThresh_Cnt_u16	46430
k_CityParkInputInvalidThresh_Cnt_u16	47784
k_CityParkInputValidThresh_Cnt_u16	10775
k_ComputerRazGCTSigValidThresh_Cnt_u16	45750
k_CptTemporelSigValidThresh_Cnt_u16	45856
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	32249
k_DMDFCTCPKSigValidThresh_Cnt_u16	36399
k_DMDFCTCPKValidCount_Cnt_u16	3382
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	18776
k_DMDRELAXECPKSigValidThresh_Cnt_u16	40967
k_DMDRelaxeConsistentThresh_Cnt_u16	35573
k_DateValidThresh_Cnt_u16	59378
k_DefaultVehSpd_Kph_f32	237.063202
k_DiagMuxOnAbsentTimeout_mS_u16	14145
k_EMNodeTimeout_mS_u16	36423
k_ESPNTCEnableTimeout_mS_u16	33242
k_ESPNodeAbsentDiag_Cnt_str.Threshold	56518
k_ESPNodeAbsentDiag_Cnt_str.PStep	63284
k_ESPNodeAbsentDiag_Cnt_str.NStep	27256
k_ESPNodeAbsentTimeout_mS_u16	59995
k_EtatMTSigInvalidThresh_Cnt_u16	45253
k_EtatMTSigValidThresh_Cnt_u16	22483
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	6830
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	9104
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	37460
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	2361
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	62947
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	10203
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	54992
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	49378

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	53491
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	18935
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	15729
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	63259
k_ISDATDIRASentDiag_Cnt_str.Threshold	1750
k_ISDATDIRASentDiag_Cnt_str.PStep	31845
k_ISDATDIRASentDiag_Cnt_str.NStep	10956
k_ISDATDIRASentTimeout_mS_u16	23878
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	63652
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	41566
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	54710
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	45626
k_ISDYNAASChkSumValidThresh_Cnt_u16	63240
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	23146
k_ISDYNAASMsgCountValidThresh_Cnt_u16	57776
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	55342
k_ISDYNAASMsgLenValidThresh_Cnt_u16	57821
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	12424
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	22655
k_ISDYNABRChkSumValidThresh_Cnt_u16	24885
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	32334
k_ISDYNABRMsgCountValidThresh_Cnt_u16	16372
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	6155
k_ISDYNABRMsgLenValidThresh_Cnt_u16	2141
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	2911
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	52991
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	40036
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	21460
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	32779
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	1393
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	48545
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	57462
k_ISDYNVOLChkSumValidThresh_Cnt_u16	23697
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	7950
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	27644
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	5485
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	22256
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	59664
k_IgnOnTimeout_mS_u16	16002
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	31.0167999
k_PowerCutVehSpdLowThresh_Kph_f32	12.4933996
k_PowerCutVehSpdLowTimeout_mS_u16	29050
k_VBattMaxAAS_Volt_f32	21.4591999
k_VBattMaxBSI_Volt_f32	13.0727997
k_VBattMaxCAV_Volt_f32	25.1478996
k_VBattMaxCMM388_Volt_f32	17.0475006
k_VBattMaxCMM_Volt_f32	19.3253002
k_VBattMaxESP_Volt_f32	18.9454002
k_VBattMinAAS_Volt_f32	30.0949993
k_VBattMinBSI_Volt_f32	18.9454002
k_VBattMinCAV_Volt_f32	3.90359998
k_VBattMinCMM388_Volt_f32	14.7000999
k_VBattMinCMM_Volt_f32	19.3486004
k_VBattMinESP_Volt_f32	19.3253002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	22198
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	65472
k_VitesseVehicleBVRampValidThresh_Cnt_u16	11291
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	21938
k_VitesseVehicleBVSigValidThresh_Cnt_u16	12140
k_VitesseVehicleBVSpeedPassThresh_kph_f32	367.841095
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	33486
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	8940
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1520074496
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	90
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16 Elaps	32038
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3401431808
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	102

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	24.2744007
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	824258304
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	105
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.575166821
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1922899712
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	948223744
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2205966080
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4219731712
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1218158336
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	155
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	314785536
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	33218304
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	114
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	115
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	140
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	188
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	226
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	248
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3500211968
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	55
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	106
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	220
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	234
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	145
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1538531072
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	186367744
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4287848192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	13
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	84
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	108
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	157
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	228
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2046734080
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2643
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.341897547
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	461153
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	88.9819031
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	27549

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3401431808	3401431808	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	49070	49070	✔
AASNodeAbsentTimer_mS_M_u32	3401431808	3401431808	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3401431808	3401431808	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3401431808	3401431808	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3401431808	3401431808	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3401431808	3401431808	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3401431808	3401431808	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21612	21612	✔
BSINodeAbsentTimer_mS_M_u32	3401431808	3401431808	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3401431808	3401431808	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3401431808	3401431808	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3401431808	3401431808	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3401431808	3401431808	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	60747	60747	✔
CMMNodeAbsentTimer_mS_M_u32	3401431808	3401431808	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	59683	59683	✔
CONSANGLECPK_HwDeg_M_f32	157.839096	157.839096 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3401431808	3401431808	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3401431808	3401431808	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3401431808	3401431808	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3401431808	3401431808	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3401431808	3401431808	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3401431808	3401431808	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3401431808	3401431808	✔
ESPNTCEnableTimer_mS_M_u32	3401431808	3401431808	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3401431808	3401431808	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	20	20	✔
ElecIntTimer_mS_M_u32[1]	19	19	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3401431808	3401431808	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3401431808	3401431808	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3401431808	3401431808	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3401431808	3401431808	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3401431808	3401431808	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3401431808	3401431808	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3401431808	3401431808	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3401431808	3401431808	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3401431808	3401431808	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3401431808	3401431808	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3401431808	3401431808	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3401431808	3401431808	✔
IgnOnTimer_mS_M_u32	2633703168	2633703168	✔
IgnTimeOff_Sec_M_u32	574670911	574670911	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	53	53	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1922899712	1922899712	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	151	151	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	948223744	948223744	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2205966080	2205966080	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	151	151	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4219731712	4219731712	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	284516096	284516096	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	155	155	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	314785536	314785536	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	131	131	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	33218304	33218304	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	248	248	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3500211968	3500211968	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	145	145	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1538531072	1538531072	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	253	253	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	186367744	186367744	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	90	90	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4287848192	4287848192	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2046734080	2046734080	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	4.66069984	4.66069984	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	79.5800018	79.5800018	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	122.322601	122.322601	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	59683	59683	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	574670911	574670911	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	157.839096	157.839096 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	237.063202	237.063202	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.41 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1801786880
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	46995
AASNodeAbsentTimer_mS_M_u32	3250652672
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	30072
ANGLEVOLANTSigValidCount_Cnt_M_u16	14853
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	43904
AngleVolantMsgTimer_mS_M_u32	1801786880
AngleVolantValidCount_Cnt_M_u16	40367
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	968148480
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1082869248
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2909124096
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2312664576
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	18095
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2338731520
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	49072
CAVNodeAbsentTimer_mS_M_u32	336963072
CDD_SrlComVehSpd_Kph_G_f32	600.778503
CMM388NTCEnableTimer_mS_M_u32	1475208704
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1548461568
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	49591
CMMNodeAbsentTimer_mS_M_u32	4028790272
CONSANGLECPKSigInvalidCount_Cnt_M_u16	11383
CONSANGLECPKSigValidCount_Cnt_M_u16	34133
CONSANGLECPK_Cnt_M_u16	63728
CONSANGLECPK_HwDeg_M_f32	338.584015
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	63728
CPKVehicleSpeedMsgTimer_mS_M_u32	626267648
CPKVehicleSpeedValidCount_Cnt_M_u16	26937
CityParkInputConsistentCount_Cnt_M_u16	33491
CityParkInputInvalidCount_Cnt_M_u16	24700
CityParkInputMsgTimer_mS_M_u32	1922899712
CityParkInputValidCount_Cnt_M_u16	8

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4024763904
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	4791
ComputerRazGCTSigInvalidTimer_mS_M_u32	1522411008
ComputerRazGCTSigValidCount_Cnt_M_u16	51448
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	5976
DMDFCTCPKSigValidCount_Cnt_M_u16	23758
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	28426
DMDRELAXECPKSigValidCount_Cnt_M_u16	40215
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	10596
DateInvalidTimer_mS_M_u32	1082869248
DiagMuxOnAbsentTimer_mS_M_u32	3251820032
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2312664576
ESPNTCEnableTimer_mS_M_u32	4220651008
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	62849
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	65
EffacDefaultDiagTimer_mS_M_u32[1]	655
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	555
ElecIntTimer_mS_M_u32[1]	5555
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1566062080
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	6837
EtatMTSigValidCount_Cnt_M_u16	44526
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	23561
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	40551
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	65284
ISDAT4V2BSI552MsgTimer_mS_M_u32	826701312
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	7328
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	23457
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	44526
ISDATBSI3F2MsgTimer_mS_M_u32	708892160
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	33954
ISDATBSI412MsgLenValidCount_Cnt_M_u16	52436
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	6837
ISDATBSI412MsgTimer_mS_M_u32	970135040
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	21979
ISDATBSI432MsgLenValidCount_Cnt_M_u16	7333
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	29345
ISDATDIRASentFltAcc_Cnt_M_u16	51925
ISDATDIRASentTimer_mS_M_u32	626267648
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	30686
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	40367
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	47631
ISDYN2CMMMsgTimer_mS_M_u32	1448871424
ISDYNAASChkSumInvalidCount_Cnt_M_u16	32037
ISDYNAASChkSumValidCount_Cnt_M_u16	61651
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	42598
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	15243
ISDYNAASMsgLenValidCount_Cnt_M_u16	20016
ISDYNAASMsgTimeValidCount_Cnt_M_u16	32037
ISDYNAASMsgTimer_mS_M_u32	600434176
ISDYNABRChkSumInvalidCount_Cnt_M_u16	12907
ISDYNABRChkSumValidCount_Cnt_M_u16	22720
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	32860
ISDYNABRMsgCountValidCount_Cnt_M_u16	48970
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	25262
ISDYNABRMsgLenValidCount_Cnt_M_u16	50892
ISDYNABRMsgTimeValidCount_Cnt_M_u16	63728
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	606
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1097
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	44526
ISDYNCMM208MsgTimer_mS_M_u32	2014955008

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2275
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1203
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	58141
ISDYNCMM388MsgTimer_mS_M_u32	2009425408
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	52453
ISDYNVOLChkSumValidCount_Cnt_M_u16	15427
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	10950
ISDYNVOLMsgCountValidCount_Cnt_M_u16	50876
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	61770
ISDYNVOLMsgLenValidCount_Cnt_M_u16	64263
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	49591
ISDYNVOLMsgTimer_mS_M_u32	2459575808
IgnOnTimer_mS_M_u32	1139369472
IgnTimeOff_Sec_M_u32	1499749733
ManVehSpd_Kph_M_f32	145.137604
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	170
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	20
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1414977024
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	170
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2172433920
PrevISDATBSI412MsgDLCError_Cnt_M_u08	202
PrevISDATBSI412MsgRxTime_MSec_M_u32	3385239040
PrevISDATBSI432MsgDLCError_Cnt_M_u08	242
PrevISDATBSI432MsgRxTime_MSec_M_u32	1948648960
PrevISDATDIRAMsgTxTime_MSec_M_u32	2700781056
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	31
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3626366464
PrevISDYNAASMsgDLCError_Cnt_M_u08	103
PrevISDYNAASMsgRxTime_MSec_M_u32	3649578496
PrevISDYNABRMsgDLCError_Cnt_M_u08	60
PrevISDYNABRMsgRxTime_MSec_M_u32	3735119360
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	13
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1567434240
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	4
PrevISDYNCMM388MsgRxTime_MSec_M_u32	885065216
PrevISDYNVOLMsgDLCError_Cnt_M_u08	126
PrevISDYNVOLMsgRxTime_MSec_M_u32	2399380992
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	188814848
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	159.985397
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	46329
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	40478
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	56898
VitesseVehicleBVRampValidCount_Cnt_M_u16	23591
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	55361
VitesseVehicleBVSigValidCount_Cnt_M_u16	20878
VitesseVehicleBV_Kph_M_f32	476.195007
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	58141
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	13987

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	367.196014
k_AASNTCEnableTimeout_mS_u16	36127
k_AASNodeAbsentDiag_Cnt_str.Threshold	40046
k_AASNodeAbsentDiag_Cnt_str.PStep	5072
k_AASNodeAbsentDiag_Cnt_str.NStep	10702
k_AASNodeAbsentTimeout_mS_u16	33858
k_AASNodeTimeout_mS_u16	37150
k_ABSNodeTimeout_mS_u16	13693
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	20910
k_ANGLEVOLANTSigValidThresh_Cnt_u16	24760
k_AngleVolantInvalidThresh_Cnt_u16	59447
k_AngleVolantValidThresh_Cnt_u16	24700
k_BSI552MsgTimeout_mS_u16	25314
k_BSINTCEnableTimeout_mS_u16	24723
k_BSINodeAbsentDiag_Cnt_str.Threshold	21652
k_BSINodeAbsentDiag_Cnt_str.PStep	36338
k_BSINodeAbsentDiag_Cnt_str.NStep	12543
k_BSINodeAbsentTimeout_mS_u16	51256
k_BSINodeTimeout_mS_u16	29345
k_BattOvHi_Volt_f32	26.0942993
k_BattOvLo_Volt_f32	1.35210001
k_BattUvHi_Volt_f32	9.78530025
k_BattUvLo_Volt_f32	12.6583004
k_CAVNTCEnableTimeout_mS_u16	29858
k_CAVNodeAbsentDiag_Cnt_str.Threshold	17248
k_CAVNodeAbsentDiag_Cnt_str.PStep	21129
k_CAVNodeAbsentDiag_Cnt_str.NStep	30053
k_CAVNodeAbsentTimeout_mS_u16	9246
k_CAVNodeTimeout_mS_u16	28755
k_CMM388MsgTimeout_mS_u16	60051
k_CMM388NTCEnableTimeout_mS_u16	53103
k_CMMNTCEnableTimeout_mS_u16	17240
k_CMMNodeAbsentDiag_Cnt_str.Threshold	11894
k_CMMNodeAbsentDiag_Cnt_str.PStep	63310
k_CMMNodeAbsentDiag_Cnt_str.NStep	23895
k_CMMNodeAbsentTimeout_mS_u16	53631
k_CONSANGLECPKMax_HwDeg_f32	369.365997
k_CONSANGLECPKMin_HwDeg_f32	-34.0836983
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	38429
k_CONSANGLECPKSigValidThresh_Cnt_u16	10659
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	7764
k_CPKVehicleSpeedValidThresh_Cnt_u16	57917
k_CityParkInputInvalidThresh_Cnt_u16	1057
k_CityParkInputValidThresh_Cnt_u16	33491
k_ComputerRazGCTSigValidThresh_Cnt_u16	63798
k_CptTemporelSigValidThresh_Cnt_u16	40119
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	38318
k_DMDFCTCPKSigValidThresh_Cnt_u16	14796
k_DMDFCTCPKValidCount_Cnt_u16	27895
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	47631
k_DMDRELAXECPKSigValidThresh_Cnt_u16	27333
k_DMDRelaxeConsistentThresh_Cnt_u16	57851
k_DateValidThresh_Cnt_u16	65284
k_DefaultVehSpd_Kph_f32	187.914902
k_DiagMuxOnAbsentTimeout_mS_u16	1686
k_EMNodeTimeout_mS_u16	7364
k_ESPNTCEnableTimeout_mS_u16	42380
k_ESPNodeAbsentDiag_Cnt_str.Threshold	10342
k_ESPNodeAbsentDiag_Cnt_str.PStep	60116
k_ESPNodeAbsentDiag_Cnt_str.NStep	44289
k_ESPNodeAbsentTimeout_mS_u16	52935
k_EtatMTSigInvalidThresh_Cnt_u16	54730
k_EtatMTSigValidThresh_Cnt_u16	5471
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	42959
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	4585
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	32284
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	49581
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	41070
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	48838
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	52328
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	21234
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	10751
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	9844

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	12485
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	24073
k_ISDATDIRASentDiag_Cnt_str.Threshold	14288
k_ISDATDIRASentDiag_Cnt_str.PStep	29720
k_ISDATDIRASentDiag_Cnt_str.NStep	63004
k_ISDATDIRASentTimeout_mS_u16	5191
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	48494
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	43904
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	6648
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	58731
k_ISDYNAASChkSumValidThresh_Cnt_u16	19392
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	45916
k_ISDYNAASMsgCountValidThresh_Cnt_u16	12874
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	17295
k_ISDYNAASMsgLenValidThresh_Cnt_u16	52802
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	7168
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	40476
k_ISDYNABRChkSumValidThresh_Cnt_u16	22714
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	31151
k_ISDYNABRMsgCountValidThresh_Cnt_u16	51580
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46263
k_ISDYNABRMsgLenValidThresh_Cnt_u16	10369
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	54075
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	37405
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	50475
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	5213
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	43128
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	44293
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	49460
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	49397
k_ISDYNVOLChkSumValidThresh_Cnt_u16	45415
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	59502
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	48356
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	5521
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	21962
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	62378
k_IgnOnTimeout_mS_u16	54993
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	158.554001
k_PowerCutVehSpdLowThresh_Kph_f32	62.1244011
k_PowerCutVehSpdLowTimeout_mS_u16	31723
k_VBattMaxAAS_Volt_f32	27.0303993
k_VBattMaxBSI_Volt_f32	8.42590046
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	9.10249996
k_VBattMaxCMM_Volt_f32	20.1546993
k_VBattMaxESP_Volt_f32	29.7700996
k_VBattMinAAS_Volt_f32	32
k_VBattMinBSI_Volt_f32	29.7700996
k_VBattMinCAV_Volt_f32	22.7851009
k_VBattMinCMM388_Volt_f32	20.882
k_VBattMinCMM_Volt_f32	10.3846998
k_VBattMinESP_Volt_f32	20.1546993
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	27448
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	38105
k_VitesseVehicleBVRampValidThresh_Cnt_u16	56774
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	44867
k_VitesseVehicleBVSigValidThresh_Cnt_u16	1748
k_VitesseVehicleBVSpeedPassThresh_kph_f32	473.499115
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	29360
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	1813
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1082869248
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	176
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	38414
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2551288320
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	4
target_SrlComInput_Per1_Batt_Volt_f32.value	30.4398994
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1941386752
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	103
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.987890422
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3405997568
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	533497344
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	179
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	627418624
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3821979136
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1661462016
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2870019584
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3286902272
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	42
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	82
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	163
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	186
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	204
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	410502656
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	23
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	127
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	133
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	212
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	79
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	733898240
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	146
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3288827392
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	65
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3441468928
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	155
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	240
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4011767296
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3314
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.345785081
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1008172
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	96.9087982
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	46147

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2551288320	2551288320	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	40046	40046	✔
AASNodeAbsentTimer_mS_M_u32	2551288320	2551288320	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2551288320	2551288320	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2551288320	2551288320	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2551288320	2551288320	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2551288320	2551288320	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2551288320	2551288320	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21652	21652	✔
BSINodeAbsentTimer_mS_M_u32	2551288320	2551288320	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2551288320	2551288320	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2551288320	2551288320	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2551288320	2551288320	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2551288320	2551288320	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	11894	11894	✔
CMMNodeAbsentTimer_mS_M_u32	2551288320	2551288320	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	63728	63728	✔
CONSANGLECPK_HwDeg_M_f32	338.584015	338.584015 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2551288320	2551288320	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2551288320	2551288320	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2551288320	2551288320	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2551288320	2551288320	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2551288320	2551288320	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2551288320	2551288320	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2551288320	2551288320	✔
ESPNTCEnableTimer_mS_M_u32	2551288320	2551288320	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2551288320	2551288320	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	65	65	✔
EffacDefaultDiagTimer_mS_M_u32[1]	655	655	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2551288320	2551288320	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	5555	5555	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2551288320	2551288320	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2551288320	2551288320	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2551288320	2551288320	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2551288320	2551288320	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2551288320	2551288320	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2551288320	2551288320	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2551288320	2551288320	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2551288320	2551288320	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2551288320	2551288320	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2551288320	2551288320	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2551288320	2551288320	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2551288320	2551288320	✔
IgnOnTimer_mS_M_u32	1139369472	1139369472	✔
IgnTimeOff_Sec_M_u32	1499749733	1499749733	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	72	72	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3405997568	3405997568	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	167	167	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	533497344	533497344	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	179	179	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	627418624	627418624	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	117	117	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3821979136	3821979136	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2700781056	2700781056	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	53	53	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2870019584	2870019584	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	68	68	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3286902272	3286902272	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	410502656	410502656	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	79	79	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	733898240	733898240	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	146	146	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3288827392	3288827392	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	65	65	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3441468928	3441468928	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4011767296	4011767296	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	159.985397	159.985397	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	476.195007	476.195007	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	367.196014	367.196014	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	63728	63728	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1499749733	1499749733	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	338.584015	338.584015 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	187.914902	187.914902	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.42 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4077666304
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	33966
AASNodeAbsentTimer_mS_M_u32	1439150080
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	1463
ANGLEVOLANTSigValidCount_Cnt_M_u16	25648
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	24579
AngleVolantMsgTimer_mS_M_u32	4077666304
AngleVolantValidCount_Cnt_M_u16	2219
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2472112128
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4108578816
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2249318400
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3826950144
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	47270
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2283167744
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	28336
CAVNodeAbsentTimer_mS_M_u32	2613137408
CDD_SrlComVehSpd_Kph_G_f32	348.558594
CMM388NTCEnableTimer_mS_M_u32	3629879296
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	363286528
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	41077
CMMNodeAbsentTimer_mS_M_u32	2360647680
CONSANGLECPKSigInvalidCount_Cnt_M_u16	23221
CONSANGLECPKSigValidCount_Cnt_M_u16	28669
CONSANGLECPK_Cnt_M_u16	30832
CONSANGLECPK_HwDeg_M_f32	512.692688
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	30832
CPKVehicleSpeedMsgTimer_mS_M_u32	2490580992
CPKVehicleSpeedValidCount_Cnt_M_u16	17296
CityParkInputConsistentCount_Cnt_M_u16	46831

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	17379
CityParkInputMsgTimer_mS_M_u32	397185280
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2500571136
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	22770
ComputerRazGCTSigInvalidTimer_mS_M_u32	2343424000
ComputerRazGCTSigValidCount_Cnt_M_u16	13884
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	4511
DMDFCTCPKSigValidCount_Cnt_M_u16	14400
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	7129
DMDRELAXECPKSigValidCount_Cnt_M_u16	12242
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	34570
DateInvalidTimer_mS_M_u32	4108578816
DiagMuxOnAbsentTimer_mS_M_u32	2464677888
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3826950144
ESPNTCEnableTimer_mS_M_u32	1176547328
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	18442
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	79
EffacDefaultDiagTimer_mS_M_u32[1]	699
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	200
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	966287360
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	41820
EtatMTSigValidCount_Cnt_M_u16	9697
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	22231
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	41375
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	56358
ISDAT4V2BSI552MsgTimer_mS_M_u32	1996005376
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	21411
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	8240
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	9697
ISDATBSI3F2MsgTimer_mS_M_u32	4005953536
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	58807
ISDATBSI412MsgLenValidCount_Cnt_M_u16	34036
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	41820
ISDATBSI412MsgTimer_mS_M_u32	3840557056
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	30137
ISDATBSI432MsgLenValidCount_Cnt_M_u16	18510
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	41257
ISDATDIRASentFltAcc_Cnt_M_u16	56061
ISDATDIRASentTimer_mS_M_u32	2490580992
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	40654
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	2219
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	8718
ISDYN2CMMMsgTimer_mS_M_u32	2268770304
ISDYNAASChkSumInvalidCount_Cnt_M_u16	50896
ISDYNAASChkSumValidCount_Cnt_M_u16	19817
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	44826
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	49507
ISDYNAASMsgLenValidCount_Cnt_M_u16	40628
ISDYNAASMsgTimeValidCount_Cnt_M_u16	50896
ISDYNAASMsgTimer_mS_M_u32	1662488576
ISDYNABRChkSumInvalidCount_Cnt_M_u16	35141
ISDYNABRChkSumValidCount_Cnt_M_u16	38854
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	15295
ISDYNABRMsgCountValidCount_Cnt_M_u16	59288
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	39588
ISDYNABRMsgLenValidCount_Cnt_M_u16	5420
ISDYNABRMsgTimeValidCount_Cnt_M_u16	30832
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	608

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1101
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	9697
ISDYNCMM208MsgTimer_mS_M_u32	3437654016
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2283
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1207
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	10633
ISDYNCMM388MsgTimer_mS_M_u32	2196705280
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	44691
ISDYNVOLChkSumValidCount_Cnt_M_u16	36443
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	28797
ISDYNVOLMsgCountValidCount_Cnt_M_u16	41374
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	51739
ISDYNVOLMsgLenValidCount_Cnt_M_u16	5956
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	41077
ISDYNVOLMsgTimer_mS_M_u32	3798585344
IgnOnTimer_mS_M_u32	1345523712
IgnTimeOff_Sec_M_u32	1572076469
ManVehSpd_Kph_M_f32	333.250092
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	174
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	202
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1502347264
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	226
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	0
PrevISDATBSI412MsgDLCError_Cnt_M_u08	164
PrevISDATBSI412MsgRxTime_MSec_M_u32	3875164160
PrevISDATBSI432MsgDLCError_Cnt_M_u08	39
PrevISDATBSI432MsgRxTime_MSec_M_u32	2740236288
PrevISDATDIRAMsgTxTime_MSec_M_u32	2546880512
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	68
PrevISDYN2CMMMsgRxTime_MSec_M_u32	550772736
PrevISDYNAASMsgDLCError_Cnt_M_u08	1
PrevISDYNAASMsgRxTime_MSec_M_u32	281530368
PrevISDYNABRMsgDLCError_Cnt_M_u08	31
PrevISDYNABRMsgRxTime_MSec_M_u32	2158694400
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	181
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3151286272
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	44
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1623699456
PrevISDYNVOLMsgDLCError_Cnt_M_u08	10
PrevISDYNVOLMsgRxTime_MSec_M_u32	2652852224
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4056432640
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	1.54540002
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	46657
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	7698
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	53714
VitesseVehicleBVRampValidCount_Cnt_M_u16	29795
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	9928
VitesseVehicleBVSigValidCount_Cnt_M_u16	57345

Name	Input Value
VitesseVehicleBV_Kph_M_f32	114.391403
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	10633
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	20154
VitesseVehiculeRoues_Kph_M_f32	135.857193
k_AASNTCEnableTimeout_mS_u16	50711
k_AASNodeAbsentDiag_Cnt_str.Threshold	30752
k_AASNodeAbsentDiag_Cnt_str.PStep	23941
k_AASNodeAbsentDiag_Cnt_str.NStep	61152
k_AASNodeAbsentTimeout_mS_u16	56278
k_AASNodeTimeout_mS_u16	43282
k_ABSNodeTimeout_mS_u16	10476
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	2084
k_ANGLEVOLANTSigValidThresh_Cnt_u16	25849
k_AngleVolantInvalidThresh_Cnt_u16	49264
k_AngleVolantValidThresh_Cnt_u16	17379
k_BSI552MsgTimeout_mS_u16	29937
k_BSINTCEnableTimeout_mS_u16	38449
k_BSINodeAbsentDiag_Cnt_str.Threshold	21732
k_BSINodeAbsentDiag_Cnt_str.PStep	36304
k_BSINodeAbsentDiag_Cnt_str.NStep	12589
k_BSINodeAbsentTimeout_mS_u16	8827
k_BSINodeTimeout_mS_u16	41257
k_BattOvHi_Volt_f32	24.7402992
k_BattOvLo_Volt_f32	5.12260008
k_BattUvHi_Volt_f32	30.9382
k_BattUvLo_Volt_f32	10.7749996
k_CAVNTCEnableTimeout_mS_u16	26937
k_CAVNodeAbsentDiag_Cnt_str.Threshold	22737
k_CAVNodeAbsentDiag_Cnt_str.PStep	29365
k_CAVNodeAbsentDiag_Cnt_str.NStep	57955
k_CAVNodeAbsentTimeout_mS_u16	42638
k_CAVNodeTimeout_mS_u16	7537
k_CMM388MsgTimeout_mS_u16	20398
k_CMM388NTCEnableTimeout_mS_u16	47978
k_CMMNTCEnableTimeout_mS_u16	28699
k_CMMNodeAbsentDiag_Cnt_str.Threshold	65067
k_CMMNodeAbsentDiag_Cnt_str.PStep	25263
k_CMMNodeAbsentDiag_Cnt_str.NStep	22127
k_CMMNodeAbsentTimeout_mS_u16	8310
k_CONSANGLECPKMax_HwDeg_f32	714.332703
k_CONSANGLECPKMin_HwDeg_f32	-223.248093
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	29833
k_CONSANGLECPKSigValidThresh_Cnt_u16	55738
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	36856
k_CPKVehicleSpeedValidThresh_Cnt_u16	10282
k_CityParkInputInvalidThresh_Cnt_u16	55467
k_CityParkInputValidThresh_Cnt_u16	46831
k_ComputerRazGCTSigValidThresh_Cnt_u16	1257
k_CptTemporelSigValidThresh_Cnt_u16	23030
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	26020
k_DMDFCTCPKSigValidThresh_Cnt_u16	8236
k_DMDFCTCPKValidCount_Cnt_u16	20782
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	8718
k_DMDRELAXECPKSigValidThresh_Cnt_u16	3567
k_DMDRelaxeConsistentThresh_Cnt_u16	11989
k_DateValidThresh_Cnt_u16	56358
k_DefaultVehSpd_Kph_f32	220.727997
k_DiagMuxOnAbsentTimeout_mS_u16	25414
k_EMNodeTimeout_mS_u16	5482
k_ESPNTCEnableTimeout_mS_u16	58220
k_ESPNodeAbsentDiag_Cnt_str.Threshold	24157
k_ESPNodeAbsentDiag_Cnt_str.PStep	37673
k_ESPNodeAbsentDiag_Cnt_str.NStep	32304
k_ESPNodeAbsentTimeout_mS_u16	18430
k_EtatMTSigInvalidThresh_Cnt_u16	57244
k_EtatMTSigValidThresh_Cnt_u16	53597
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	23883
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	28080
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	13440
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	26904
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	54117
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	37115
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	59566

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	30979
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	35581
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	45588
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	9329
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	5199
k_ISDATDIRASentDiag_Cnt_str.Threshold	32194
k_ISDATDIRASentDiag_Cnt_str.PStep	50621
k_ISDATDIRASentDiag_Cnt_str.NStep	26058
k_ISDATDIRASentTimeout_mS_u16	55809
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	30428
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	24579
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	56120
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	54341
k_ISDYNAASChkSumValidThresh_Cnt_u16	8902
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	1727
k_ISDYNAASMsgCountValidThresh_Cnt_u16	62104
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	50057
k_ISDYNAASMsgLenValidThresh_Cnt_u16	28502
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	14977
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	24962
k_ISDYNABRChkSumValidThresh_Cnt_u16	59018
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	33702
k_ISDYNABRMsgCountValidThresh_Cnt_u16	51039
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	11125
k_ISDYNABRMsgLenValidThresh_Cnt_u16	4874
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	46870
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	7301
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	53896
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	56905
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	53431
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	28464
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	27227
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	48290
k_ISDYNVOLChkSumValidThresh_Cnt_u16	17951
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	6751
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	48394
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	54552
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	27805
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	58876
k_IgnOnTimeout_mS_u16	57694
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	77.4804993
k_PowerCutVehSpdLowThresh_Kph_f32	57.6133003
k_PowerCutVehSpdLowTimeout_mS_u16	2883
k_VBattMaxAAS_Volt_f32	8.85669994
k_VBattMaxBSI_Volt_f32	10.6702995
k_VBattMaxCAV_Volt_f32	30.8539009
k_VBattMaxCMM388_Volt_f32	12.5702
k_VBattMaxCMM_Volt_f32	4.98309994
k_VBattMaxESP_Volt_f32	13.0825996
k_VBattMinAAS_Volt_f32	0.534699976
k_VBattMinBSI_Volt_f32	13.0825996
k_VBattMinCAV_Volt_f32	2.23119998
k_VBattMinCMM388_Volt_f32	5.85750008
k_VBattMinCMM_Volt_f32	6.44990015
k_VBattMinESP_Volt_f32	4.98309994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	41718
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	44835
k_VitesseVehicleBVRampValidThresh_Cnt_u16	47997
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	39259
k_VitesseVehicleBVSigValidThresh_Cnt_u16	49912
k_VitesseVehicleBVSpeedPassThresh_kph_f32	511.877991
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	47536
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	9921
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	4108578816
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	26
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	41811
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	394042368
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	44
target_SrlComInput_Per1_Batt_Volt_f32.value	21.8960991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2599378944
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	21
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.41735658
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2686259200
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1345269760
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3079753728
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	78
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	507736064
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3427110912
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	124
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	160935936
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	252
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	507105280
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	131
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	19
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2687791104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	71
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	140
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	141
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	168
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4272951296
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	228
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	239218688
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2502184960
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4254261248
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	244
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.414270252
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	163472
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	7.17309999

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	49115		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	394042368	394042368	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	30752	30752	✔
AASNodeAbsentTimer_mS_M_u32	394042368	394042368	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	24581	24581	✔
AngleVolantMsgTimer_mS_M_u32	394042368	394042368	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	394042368	394042368	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	394042368	394042368	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	394042368	394042368	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	394042368	394042368	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21732	21732	✔
BSINodeAbsentTimer_mS_M_u32	394042368	394042368	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	394042368	394042368	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	394042368	394042368	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	394042368	394042368	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	394042368	394042368	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	65067	65067	✔
CMMNodeAbsentTimer_mS_M_u32	394042368	394042368	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	30832	30832	✔
CONSANGLECPK_HwDeg_M_f32	512.692688	512.692688 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	30832	30832	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2490580992	2490580992	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	17296	17296	✔
CityParkInputConsistentCount_Cnt_M_u16	46831	46831	✔
CityParkInputInvalidCount_Cnt_M_u16	17381	17381	✔
CityParkInputMsgTimer_mS_M_u32	394042368	394042368	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	394042368	394042368	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	394042368	394042368	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	394042368	394042368	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	394042368	394042368	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	394042368	394042368	✔
ESPNTCEnableTimer_mS_M_u32	394042368	394042368	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	394042368	394042368	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	79	79	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	699	699	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	394042368	394042368	✔
ElecIntTimer_mS_M_u32[1]	200	200	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	394042368	394042368	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	394042368	394042368	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	394042368	394042368	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	394042368	394042368	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	394042368	394042368	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	394042368	394042368	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	394042368	394042368	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	394042368	394042368	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	394042368	394042368	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	394042368	394042368	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	394042368	394042368	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	394042368	394042368	✔
IgnOnTimer_mS_M_u32	394042368	394042368	✔
IgnTimeOff_Sec_M_u32	1572076469	1572076469	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	222	222	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2686259200	2686259200	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	173	173	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1345269760	1345269760	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	16	16	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3079753728	3079753728	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	78	78	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	507736064	507736064	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2546880512	2546880512	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	124	124	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	160935936	160935936	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	252	252	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	507105280	507105280	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	19	19	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2687791104	2687791104	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4272951296	4272951296	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	228	228	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	239218688	239218688	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2502184960	2502184960	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4254261248	4254261248	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	1.54540002	1.54540002	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	114.391403	114.391403	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	135.857193	135.857193	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	30832	30832	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1572076469	1572076469	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	512.692688	512.692688 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	220.727997	220.727997	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.43 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1803158272
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	24722
AASNodeAbsentTimer_mS_M_u32	3171398400
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	40825
ANGLEVOLANTSigValidCount_Cnt_M_u16	54222
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	25235
AngleVolantMsgTimer_mS_M_u32	1803158272
AngleVolantValidCount_Cnt_M_u16	45339
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2069000960
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2696082176
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1357456128
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1238295296
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	684
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4242252544
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	12557
CAVNodeAbsentTimer_mS_M_u32	1503318784
CDD_SrlComVehSpd_Kph_G_f32	325.639496
CMM388NTCEnableTimer_mS_M_u32	3704361728
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	65590016
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	27774
CMMNodeAbsentTimer_mS_M_u32	939582208
CONSANGLECPKSigInvalidCount_Cnt_M_u16	51071
CONSANGLECPKSigValidCount_Cnt_M_u16	5988
CONSANGLECPK_Cnt_M_u16	35339
CONSANGLECPK_HwDeg_M_f32	-36.8464012
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	35339
CPKVehicleSpeedMsgTimer_mS_M_u32	3812950784
CPKVehicleSpeedValidCount_Cnt_M_u16	37844
CityParkInputConsistentCount_Cnt_M_u16	46671

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	60533
CityParkInputMsgTimer_mS_M_u32	2686259200
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	255570688
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	62406
ComputerRazGCTSigInvalidTimer_mS_M_u32	3688190720
ComputerRazGCTSigValidCount_Cnt_M_u16	44136
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	29505
DMDFCTCPKSigValidCount_Cnt_M_u16	61214
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	25875
DMDRELAXECPKSigValidCount_Cnt_M_u16	30952
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	54912
DateInvalidTimer_mS_M_u32	2696082176
DiagMuxOnAbsentTimer_mS_M_u32	2867249920
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1238295296
ESPNTCEnableTimer_mS_M_u32	2415702784
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	13695
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	86
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	89
ElecIntTimer_mS_M_u32[1]	898
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1884660480
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	4296
EtatMTSigValidCount_Cnt_M_u16	2297
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	56089
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	35454
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	7020
ISDAT4V2BSI552MsgTimer_mS_M_u32	2301944576
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	37237
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	52110
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	2297
ISDATBSI3F2MsgTimer_mS_M_u32	2404172544
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	31800
ISDATBSI412MsgLenValidCount_Cnt_M_u16	65089
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	4296
ISDATBSI412MsgTimer_mS_M_u32	2380268288
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	64690
ISDATBSI432MsgLenValidCount_Cnt_M_u16	17587
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	48546
ISDATDIRASentFltAcc_Cnt_M_u16	24614
ISDATDIRASentTimer_mS_M_u32	3812950784
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	3825
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	45339
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	48628
ISDYN2CMMMsgTimer_mS_M_u32	3031347968
ISDYNAASChkSumInvalidCount_Cnt_M_u16	41516
ISDYNAASChkSumValidCount_Cnt_M_u16	56865
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	14798
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	50420
ISDYNAASMsgLenValidCount_Cnt_M_u16	56513
ISDYNAASMsgTimeValidCount_Cnt_M_u16	41516
ISDYNAASMsgTimer_mS_M_u32	748163840
ISDYNABRChkSumInvalidCount_Cnt_M_u16	50765
ISDYNABRChkSumValidCount_Cnt_M_u16	2699
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	48991
ISDYNABRMsgCountValidCount_Cnt_M_u16	35732
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	33714
ISDYNABRMsgLenValidCount_Cnt_M_u16	41943
ISDYNABRMsgTimeValidCount_Cnt_M_u16	35339
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	609

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1103
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	2297
ISDYNCMM208MsgTimer_mS_M_u32	1118532352
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2287
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1209
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	18049
ISDYNCMM388MsgTimer_mS_M_u32	2333184768
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	50149
ISDYNVOLChkSumValidCount_Cnt_M_u16	46154
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	20135
ISDYNVOLMsgCountValidCount_Cnt_M_u16	43780
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	13132
ISDYNVOLMsgLenValidCount_Cnt_M_u16	23441
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	27774
ISDYNVOLMsgTimer_mS_M_u32	3349238528
IgnOnTimer_mS_M_u32	860197632
IgnTimeOff_Sec_M_u32	523321340
ManVehSpd_Kph_M_f32	150.434692
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	176
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	137
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3875193600
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	136
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4294967295
PrevISDATBSI412MsgDLCError_Cnt_M_u08	84
PrevISDATBSI412MsgRxTime_MSec_M_u32	2616185600
PrevISDATBSI432MsgDLCError_Cnt_M_u08	27
PrevISDATBSI432MsgRxTime_MSec_M_u32	1214296832
PrevISDATDIRAMsgTxTime_MSec_M_u32	3648246528
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	254
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1503814400
PrevISDYNAASMsgDLCError_Cnt_M_u08	253
PrevISDYNAASMsgRxTime_MSec_M_u32	881283840
PrevISDYNABRMsgDLCError_Cnt_M_u08	173
PrevISDYNABRMsgRxTime_MSec_M_u32	2178781952
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	140
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2808107776
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	128
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2617750272
PrevISDYNVOLMsgDLCError_Cnt_M_u08	136
PrevISDYNVOLMsgRxTime_MSec_M_u32	1249956608
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1598423808
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	530.870911
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	56922
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	22183
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	4007
VitesseVehicleBVRampValidCount_Cnt_M_u16	55220
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	49222
VitesseVehicleBVSigValidCount_Cnt_M_u16	58459

Name	Input Value
VitesseVehicleBV_Kph_M_f32	25.6840992
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	18049
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1710
VitesseVehiculeRoues_Kph_M_f32	98.4514999
k_AASNTCEnableTimeout_mS_u16	64790
k_AASNodeAbsentDiag_Cnt_str.Threshold	60061
k_AASNodeAbsentDiag_Cnt_str.PStep	65030
k_AASNodeAbsentDiag_Cnt_str.NStep	59598
k_AASNodeAbsentTimeout_mS_u16	41882
k_AASNodeTimeout_mS_u16	46503
k_ABSNodeTimeout_mS_u16	41306
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	45425
k_ANGLEVOLANTSigValidThresh_Cnt_u16	23218
k_AngleVolantInvalidThresh_Cnt_u16	58445
k_AngleVolantValidThresh_Cnt_u16	60533
k_BSI552MsgTimeout_mS_u16	12297
k_BSINTCEnableTimeout_mS_u16	31562
k_BSINodeAbsentDiag_Cnt_str.Threshold	21772
k_BSINodeAbsentDiag_Cnt_str.PStep	36287
k_BSINodeAbsentDiag_Cnt_str.NStep	12612
k_BSINodeAbsentTimeout_mS_u16	64299
k_BSINodeTimeout_mS_u16	48546
k_BattOvHi_Volt_f32	14.3760004
k_BattOvLo_Volt_f32	28.6366005
k_BattUvHi_Volt_f32	10.0643997
k_BattUvLo_Volt_f32	9.5848999
k_CAVNTCEnableTimeout_mS_u16	21619
k_CAVNodeAbsentDiag_Cnt_str.Threshold	54595
k_CAVNodeAbsentDiag_Cnt_str.PStep	32109
k_CAVNodeAbsentDiag_Cnt_str.NStep	44411
k_CAVNodeAbsentTimeout_mS_u16	33139
k_CAVNodeTimeout_mS_u16	28491
k_CMM388MsgTimeout_mS_u16	65426
k_CMM388NTCEnableTimeout_mS_u16	44126
k_CMMNTCEnableTimeout_mS_u16	7181
k_CMMNodeAbsentDiag_Cnt_str.Threshold	732
k_CMMNodeAbsentDiag_Cnt_str.PStep	9703
k_CMMNodeAbsentDiag_Cnt_str.NStep	3711
k_CMMNodeAbsentTimeout_mS_u16	33146
k_CONSANGLECPKMax_HwDeg_f32	622.901672
k_CONSANGLECPKMin_HwDeg_f32	-612.556213
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	25985
k_CONSANGLECPKSigValidThresh_Cnt_u16	26030
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	6389
k_CPKVehicleSpeedValidThresh_Cnt_u16	16607
k_CityParkInputInvalidThresh_Cnt_u16	61467
k_CityParkInputValidThresh_Cnt_u16	46671
k_ComputerRazGCTSigValidThresh_Cnt_u16	5539
k_CptTemporelSigValidThresh_Cnt_u16	46652
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	8882
k_DMDFCTCPKSigValidThresh_Cnt_u16	33495
k_DMDFCTCPKValidCount_Cnt_u16	22804
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	48628
k_DMDRELAXECPKSigValidThresh_Cnt_u16	59921
k_DMDRelaxeConsistentThresh_Cnt_u16	40799
k_DateValidThresh_Cnt_u16	7020
k_DefaultVehSpd_Kph_f32	142.936096
k_DiagMuxOnAbsentTimeout_mS_u16	41353
k_EMNodeTimeout_mS_u16	43872
k_ESPNTCEnableTimeout_mS_u16	49881
k_ESPNodeAbsentDiag_Cnt_str.Threshold	16422
k_ESPNodeAbsentDiag_Cnt_str.PStep	25432
k_ESPNodeAbsentDiag_Cnt_str.NStep	20253
k_ESPNodeAbsentTimeout_mS_u16	10978
k_EtatMTSigInvalidThresh_Cnt_u16	57160
k_EtatMTSigValidThresh_Cnt_u16	31174
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	48380
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	35726
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	49564
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	25878
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	50671
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	35436
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	47059

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	50836
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	52454
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	27935
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	62921
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	41327
k_ISDATDIRASentDiag_Cnt_str.Threshold	4847
k_ISDATDIRASentDiag_Cnt_str.PStep	19669
k_ISDATDIRASentDiag_Cnt_str.NStep	10182
k_ISDATDIRASentTimeout_mS_u16	50201
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	60872
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	25235
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	2933
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	58701
k_ISDYNAASChkSumValidThresh_Cnt_u16	27019
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	24159
k_ISDYNAASMsgCountValidThresh_Cnt_u16	27284
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	10113
k_ISDYNAASMsgLenValidThresh_Cnt_u16	29403
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	64026
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	10008
k_ISDYNABRChkSumValidThresh_Cnt_u16	10173
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	41388
k_ISDYNABRMsgCountValidThresh_Cnt_u16	9793
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	52094
k_ISDYNABRMsgLenValidThresh_Cnt_u16	54399
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	62236
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	48014
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	14789
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	45570
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	15993
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	45774
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	22797
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	25463
k_ISDYNVOLChkSumValidThresh_Cnt_u16	9920
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	21120
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	43711
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	27540
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	9413
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	54762
k_IgnOnTimeout_mS_u16	58691
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	135.178802
k_PowerCutVehSpdLowThresh_Kph_f32	202.780304
k_PowerCutVehSpdLowTimeout_mS_u16	56722
k_VBattMaxAAS_Volt_f32	12.5039997
k_VBattMaxBSI_Volt_f32	0.682399988
k_VBattMaxCAV_Volt_f32	22.9214001
k_VBattMaxCMM388_Volt_f32	17.7667999
k_VBattMaxCMM_Volt_f32	19.6131001
k_VBattMaxESP_Volt_f32	30.4736996
k_VBattMinAAS_Volt_f32	10.6253996
k_VBattMinBSI_Volt_f32	30.4736996
k_VBattMinCAV_Volt_f32	18.0074997
k_VBattMinCMM388_Volt_f32	8.99769974
k_VBattMinCMM_Volt_f32	13.118
k_VBattMinESP_Volt_f32	19.6131001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	20858
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	19635
k_VitesseVehicleBVRampValidThresh_Cnt_u16	28071
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	37706
k_VitesseVehicleBVSigValidThresh_Cnt_u16	63028
k_VitesseVehicleBVSpeedPassThresh_kph_f32	497.789612
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	20493
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	47258
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2696082176
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	71
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	33324
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3264802560
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	128
target_SrlComInput_Per1_Batt_Volt_f32.value	25.3267994
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1750115072
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	153
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.276247233
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1804047104
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	82
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3419484928
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1177211648
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	43283200
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	688788224
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3784815360
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1412518656
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	146
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	192
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	239
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2160161536
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	41
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	86
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	147
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	223
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	224
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1540264704
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	187
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2643997440
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	101
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3111244544
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	175
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	183
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	251
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	778445568
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1369
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.841921926
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	333023
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	131.350906

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	43404		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	3264802560	3264802560	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	60061	60061	✔
AASNodeAbsentTimer_mS_M_u32	3264802560	3264802560	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	25237	25237	✔
AngleVolantMsgTimer_mS_M_u32	3264802560	3264802560	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3264802560	3264802560	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3264802560	3264802560	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3264802560	3264802560	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3264802560	3264802560	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21772	21772	✔
BSINodeAbsentTimer_mS_M_u32	3264802560	3264802560	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3264802560	3264802560	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3264802560	3264802560	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3264802560	3264802560	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3264802560	3264802560	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	732	732	✔
CMMNodeAbsentTimer_mS_M_u32	3264802560	3264802560	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	35339	35339	✔
CONSANGLECPK_HwDeg_M_f32	-36.8464012	-36.8464012 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	35339	35339	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3812950784	3812950784	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	37844	37844	✔
CityParkInputConsistentCount_Cnt_M_u16	46671	46671	✔
CityParkInputInvalidCount_Cnt_M_u16	60535	60535	✔
CityParkInputMsgTimer_mS_M_u32	3264802560	3264802560	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3264802560	3264802560	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3264802560	3264802560	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3264802560	3264802560	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3264802560	3264802560	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3264802560	3264802560	✔
ESPNTCEnableTimer_mS_M_u32	3264802560	3264802560	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3264802560	3264802560	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	86	86	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3264802560	3264802560	✔
ElecIntTimer_mS_M_u32[1]	898	898	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3264802560	3264802560	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3264802560	3264802560	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3264802560	3264802560	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3264802560	3264802560	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3264802560	3264802560	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3264802560	3264802560	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3264802560	3264802560	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3264802560	3264802560	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3264802560	3264802560	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3264802560	3264802560	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3264802560	3264802560	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3264802560	3264802560	✔
IgnOnTimer_mS_M_u32	860197632	860197632	✔
IgnTimeOff_Sec_M_u32	523321340	523321340	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	240	240	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1804047104	1804047104	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	82	82	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3419484928	3419484928	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	59	59	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1177211648	1177211648	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	43283200	43283200	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3648246528	3648246528	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	168	168	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3784815360	3784815360	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	57	57	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1412518656	1412518656	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	135	135	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2160161536	2160161536	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	88	88	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1540264704	1540264704	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	187	187	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2643997440	2643997440	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	101	101	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3111244544	3111244544	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	778445568	778445568	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	530.870911	530.870911	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	25.6840992	25.6840992	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	98.4514999	98.4514999	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	35339	35339	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	523321340	523321340	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-36.8464012	-36.8464012 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	142.936096	142.936096	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.44 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3774659072
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	947
AASNodeAbsentTimer_mS_M_u32	2131995136
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	255
ANGLEVOLANTSigValidCount_Cnt_M_u16	29888
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	16816
AngleVolantMsgTimer_mS_M_u32	3774659072
AngleVolantValidCount_Cnt_M_u16	31897
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3744688640
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2433870336
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1429166592
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	830347776
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	25446
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	995613184
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	59073
CAVNodeAbsentTimer_mS_M_u32	1574586880
CDD_SrlComVehSpd_Kph_G_f32	122.110199
CMM388NTCEnableTimer_mS_M_u32	692488704
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	384846336
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	49712
CMMNodeAbsentTimer_mS_M_u32	2934446592
CONSANGLECPKSigInvalidCount_Cnt_M_u16	5099
CONSANGLECPKSigValidCount_Cnt_M_u16	29947
CONSANGLECPK_Cnt_M_u16	30982
CONSANGLECPK_HwDeg_M_f32	208.071304
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	30982
CPKVehicleSpeedMsgTimer_mS_M_u32	1704704512
CPKVehicleSpeedValidCount_Cnt_M_u16	47667
CityParkInputConsistentCount_Cnt_M_u16	15613

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	906
CityParkInputMsgTimer_mS_M_u32	1804047104
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1484237312
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	6679
ComputerRazGCTSigInvalidTimer_mS_M_u32	3777677824
ComputerRazGCTSigValidCount_Cnt_M_u16	65202
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	40742
DMDFCTCPKSigValidCount_Cnt_M_u16	23631
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	38961
DMDRELAXECPKSigValidCount_Cnt_M_u16	28018
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	10984
DateInvalidTimer_mS_M_u32	2433870336
DiagMuxOnAbsentTimer_mS_M_u32	3317070336
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	830347776
ESPNTCEnableTimer_mS_M_u32	439659008
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	10220
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	5
EffacDefaultDiagTimer_mS_M_u32[1]	155
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	1313863168
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1223285248
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	52817
EtatMTSigValidCount_Cnt_M_u16	26238
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	49437
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	941
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	36709
ISDAT4V2BSI552MsgTimer_mS_M_u32	2337020416
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	38859
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	2623
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	26238
ISDATBSI3F2MsgTimer_mS_M_u32	813988352
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	62593
ISDATBSI412MsgLenValidCount_Cnt_M_u16	20261
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	52817
ISDATBSI412MsgTimer_mS_M_u32	2445982208
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	57748
ISDATBSI432MsgLenValidCount_Cnt_M_u16	51792
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	54530
ISDATDIRASentFltAcc_Cnt_M_u16	64886
ISDATDIRASentTimer_mS_M_u32	1704704512
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	596
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	31897
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	19213
ISDYN2CMMMsgTimer_mS_M_u32	4095650304
ISDYNAASChkSumInvalidCount_Cnt_M_u16	9957
ISDYNAASChkSumValidCount_Cnt_M_u16	965
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	28288
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	34572
ISDYNAASMsgLenValidCount_Cnt_M_u16	12389
ISDYNAASMsgTimeValidCount_Cnt_M_u16	9957
ISDYNAASMsgTimer_mS_M_u32	1776454144
ISDYNABRChkSumInvalidCount_Cnt_M_u16	30721
ISDYNABRChkSumValidCount_Cnt_M_u16	23561
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	23372
ISDYNABRMsgCountValidCount_Cnt_M_u16	34668
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	27474
ISDYNABRMsgLenValidCount_Cnt_M_u16	23458
ISDYNABRMsgTimeValidCount_Cnt_M_u16	30982
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	610

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1105
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	26238
ISDYNCMM208MsgTimer_mS_M_u32	757623296
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2291
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1211
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	54375
ISDYNCMM388MsgTimer_mS_M_u32	343280128
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	14009
ISDYNVOLChkSumValidCount_Cnt_M_u16	46665
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	9460
ISDYNVOLMsgCountValidCount_Cnt_M_u16	16541
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	41605
ISDYNVOLMsgLenValidCount_Cnt_M_u16	64118
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	49712
ISDYNVOLMsgTimer_mS_M_u32	1304873472
IgnOnTimer_mS_M_u32	3956935168
IgnTimeOff_Sec_M_u32	1639023646
ManVehSpd_Kph_M_f32	654.774902
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	178
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	160
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1635416576
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	200
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	905059584
PrevISDATBSI412MsgDLCError_Cnt_M_u08	46
PrevISDATBSI412MsgRxTime_MSec_M_u32	719014400
PrevISDATBSI432MsgDLCError_Cnt_M_u08	228
PrevISDATBSI432MsgRxTime_MSec_M_u32	2164828672
PrevISDATDIRAMsgTxTime_MSec_M_u32	2186234368
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	142
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2953026048
PrevISDYNAASMsgDLCError_Cnt_M_u08	245
PrevISDYNAASMsgRxTime_MSec_M_u32	521456128
PrevISDYNABRMsgDLCError_Cnt_M_u08	195
PrevISDYNABRMsgRxTime_MSec_M_u32	1611794944
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	72
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1787415040
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	89
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3792939520
PrevISDYNVOLMsgDLCError_Cnt_M_u08	92
PrevISDYNVOLMsgRxTime_MSec_M_u32	2737326592
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	899201536
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	44.8198013
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	21210
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	55987
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	13043
VitesseVehicleBVRampValidCount_Cnt_M_u16	52108
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	4760
VitesseVehicleBVSigValidCount_Cnt_M_u16	46873

Name	Input Value
VitesseVehicleBV_Kph_M_f32	91.3067017
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	54375
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1183
VitesseVehiculeRoues_Kph_M_f32	117.850098
k_AASNTCEnableTimeout_mS_u16	3045
k_AASNodeAbsentDiag_Cnt_str.Threshold	47217
k_AASNodeAbsentDiag_Cnt_str.PStep	37742
k_AASNodeAbsentDiag_Cnt_str.NStep	22160
k_AASNodeAbsentTimeout_mS_u16	24860
k_AASNodeTimeout_mS_u16	48563
k_ABSNodeTimeout_mS_u16	47323
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	32599
k_ANGLEVOLANTSigValidThresh_Cnt_u16	17491
k_AngleVolantInvalidThresh_Cnt_u16	54146
k_AngleVolantValidThresh_Cnt_u16	906
k_BSI552MsgTimeout_mS_u16	46222
k_BSINTCEnableTimeout_mS_u16	50636
k_BSINodeAbsentDiag_Cnt_str.Threshold	21812
k_BSINodeAbsentDiag_Cnt_str.PStep	36270
k_BSINodeAbsentDiag_Cnt_str.NStep	12635
k_BSINodeAbsentTimeout_mS_u16	55272
k_BSINodeTimeout_mS_u16	54530
k_BattOvHi_Volt_f32	14.2125998
k_BattOvLo_Volt_f32	7.70760012
k_BattUvHi_Volt_f32	16.8008003
k_BattUvLo_Volt_f32	6.14690018
k_CAVNTCEnableTimeout_mS_u16	17296
k_CAVNodeAbsentDiag_Cnt_str.Threshold	12888
k_CAVNodeAbsentDiag_Cnt_str.PStep	47186
k_CAVNodeAbsentDiag_Cnt_str.NStep	2783
k_CAVNodeAbsentTimeout_mS_u16	3471
k_CAVNodeTimeout_mS_u16	19591
k_CMM388MsgTimeout_mS_u16	9907
k_CMM388NTCEnableTimeout_mS_u16	20559
k_CMMNTCEnableTimeout_mS_u16	22531
k_CMMNodeAbsentDiag_Cnt_str.Threshold	61589
k_CMMNodeAbsentDiag_Cnt_str.PStep	62891
k_CMMNodeAbsentDiag_Cnt_str.NStep	20572
k_CMMNodeAbsentTimeout_mS_u16	50235
k_CONSANGLECPKMax_HwDeg_f32	722.680298
k_CONSANGLECPKMin_HwDeg_f32	-592.345215
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	30567
k_CONSANGLECPKSigValidThresh_Cnt_u16	59295
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	19401
k_CPKVehicleSpeedValidThresh_Cnt_u16	652
k_CityParkInputInvalidThresh_Cnt_u16	45719
k_CityParkInputValidThresh_Cnt_u16	15613
k_ComputerRazGCTSigValidThresh_Cnt_u16	17217
k_CptTemporelSigValidThresh_Cnt_u16	33333
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	36434
k_DMDFCTCPKSigValidThresh_Cnt_u16	48802
k_DMDFCTCPKValidCount_Cnt_u16	46
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	19213
k_DMDRELAXECPKSigValidThresh_Cnt_u16	63350
k_DMDRelaxeConsistentThresh_Cnt_u16	36748
k_DateValidThresh_Cnt_u16	36709
k_DefaultVehSpd_Kph_f32	213.108795
k_DiagMuxOnAbsentTimeout_mS_u16	43660
k_EMNodeTimeout_mS_u16	11336
k_ESPNTCEnableTimeout_mS_u16	24925
k_ESPNodeAbsentDiag_Cnt_str.Threshold	40727
k_ESPNodeAbsentDiag_Cnt_str.PStep	20663
k_ESPNodeAbsentDiag_Cnt_str.NStep	59104
k_ESPNodeAbsentTimeout_mS_u16	26627
k_EtatMTSigInvalidThresh_Cnt_u16	55568
k_EtatMTSigValidThresh_Cnt_u16	47704
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	15284
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	53440
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	36630
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	57576
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	57116
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	39397
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	29745

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	2221
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	16632
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	8138
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	59023
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	29147
k_ISDATDIRASentDiag_Cnt_str.Threshold	29650
k_ISDATDIRASentDiag_Cnt_str.PStep	61595
k_ISDATDIRASentDiag_Cnt_str.NStep	36479
k_ISDATDIRASentTimeout_mS_u16	44701
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	12496
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	16816
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	63369
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	6913
k_ISDYNAASChkSumValidThresh_Cnt_u16	16137
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	32332
k_ISDYNAASMsgCountValidThresh_Cnt_u16	60012
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	9317
k_ISDYNAASMsgLenValidThresh_Cnt_u16	22039
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	1563
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	39200
k_ISDYNABRChkSumValidThresh_Cnt_u16	59376
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	34406
k_ISDYNABRMsgCountValidThresh_Cnt_u16	2407
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	42288
k_ISDYNABRMsgLenValidThresh_Cnt_u16	19180
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	52950
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	35646
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	12250
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	62626
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	9215
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	55232
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	7618
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	64196
k_ISDYNVOLChkSumValidThresh_Cnt_u16	37288
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	5353
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	19309
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	60909
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	17178
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	55275
k_IgnOnTimeout_mS_u16	42336
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	12.8808002
k_PowerCutVehSpdLowThresh_Kph_f32	42.0760994
k_PowerCutVehSpdLowTimeout_mS_u16	23153
k_VBattMaxAAS_Volt_f32	8.36800003
k_VBattMaxBSI_Volt_f32	29.9752007
k_VBattMaxCAV_Volt_f32	11.8880997
k_VBattMaxCMM388_Volt_f32	9.36970043
k_VBattMaxCMM_Volt_f32	0.575800002
k_VBattMaxESP_Volt_f32	27.5165997
k_VBattMinAAS_Volt_f32	28.5380001
k_VBattMinBSI_Volt_f32	27.5165997
k_VBattMinCAV_Volt_f32	1.97660005
k_VBattMinCMM388_Volt_f32	23.3985004
k_VBattMinCMM_Volt_f32	26.3451996
k_VBattMinESP_Volt_f32	0.575800002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	19898
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	64719
k_VitesseVehicleBVRampValidThresh_Cnt_u16	51188
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	6473
k_VitesseVehicleBVSigValidThresh_Cnt_u16	20814
k_VitesseVehicleBVSpeedPassThresh_kph_f32	244.693893
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	35265
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	16602
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2433870336
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	111
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	17998
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1313863168
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	89
target_SrlComInput_Per1_Batt_Volt_f32.value	1.13409996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	217635328
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	154
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.316847444
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	124
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3407088128
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	228
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1488398848
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	249
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3626650112
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3513608704
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3430976000
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	157
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1365486080
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3893807616
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	37
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	99
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	116
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	179
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	237
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	23
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1256614400
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	39
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	84
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	121
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	125
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	139
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	151
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	191
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3594455552
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3210881536
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1515538944
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	67
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	74
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	149
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	153
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	216
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4038613504
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	856
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.988690138
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	492537
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	156.614395

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	14660		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1313863168	1313863168	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	47217	47217	✔
AASNodeAbsentTimer_mS_M_u32	1313863168	1313863168	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	16818	16818	✔
AngleVolantMsgTimer_mS_M_u32	1313863168	1313863168	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1313863168	1313863168	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1313863168	1313863168	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1313863168	1313863168	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1313863168	1313863168	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21812	21812	✔
BSINodeAbsentTimer_mS_M_u32	1313863168	1313863168	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1313863168	1313863168	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1313863168	1313863168	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1313863168	1313863168	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1313863168	1313863168	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	61589	61589	✔
CMMNodeAbsentTimer_mS_M_u32	1313863168	1313863168	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	30982	30982	✔
CONSANGLECPK_HwDeg_M_f32	208.071304	208.071304 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	30982	30982	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1704704512	1704704512	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	47667	47667	✔
CityParkInputConsistentCount_Cnt_M_u16	15613	15613	✔
CityParkInputInvalidCount_Cnt_M_u16	908	908	✔
CityParkInputMsgTimer_mS_M_u32	1313863168	1313863168	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1313863168	1313863168	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1313863168	1313863168	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1313863168	1313863168	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1313863168	1313863168	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1313863168	1313863168	✔
ESPNTCEnableTimer_mS_M_u32	1313863168	1313863168	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1313863168	1313863168	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	5	5	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	155	155	✔
ElecIntCount_Cnt_M_u08	2	2	✔
ElecIntTimer_mS_M_u32[0]	4	4	✔
ElecIntTimer_mS_M_u32[1]	1313863168	1313863168	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1313863168	1313863168	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1313863168	1313863168	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1313863168	1313863168	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1313863168	1313863168	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1313863168	1313863168	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1313863168	1313863168	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1313863168	1313863168	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1313863168	1313863168	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1313863168	1313863168	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1313863168	1313863168	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1313863168	1313863168	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1313863168	1313863168	✔
IgnOnTimer_mS_M_u32	1313863168	1313863168	✔
IgnTimeOff_Sec_M_u32	1639023646	1639023646	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	124	124	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3407088128	3407088128	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	228	228	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1488398848	1488398848	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	249	249	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3626650112	3626650112	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	69	69	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3513608704	3513608704	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2186234368	2186234368	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	157	157	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1365486080	1365486080	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	186	186	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3893807616	3893807616	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	23	23	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1256614400	1256614400	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3594455552	3594455552	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	133	133	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3210881536	3210881536	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	86	86	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1515538944	1515538944	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4038613504	4038613504	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	44.8198013	44.8198013	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	91.3067017	91.3067017	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	117.850098	117.850098	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	30982	30982	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1639023646	1639023646	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	208.071304	208.071304 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	213.108795	213.108795	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.45 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	336631040
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	42477
AASNodeAbsentTimer_mS_M_u32	2173420800
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	32775
ANGLEVOLANTSigValidCount_Cnt_M_u16	62086
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	8182
AngleVolantMsgTimer_mS_M_u32	336631040
AngleVolantValidCount_Cnt_M_u16	64442
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2418836736
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	345048320
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1241036032
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1611429120
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	46290
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3648992512
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	65345
CAVNodeAbsentTimer_mS_M_u32	3350717696
CDD_SrlComVehSpd_Kph_G_f32	359.941406
CMM388NTCEnableTimer_mS_M_u32	1718822144
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1953883392
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	50101
CMMNodeAbsentTimer_mS_M_u32	265188608
CONSANGLECPKSigInvalidCount_Cnt_M_u16	42564
CONSANGLECPKSigValidCount_Cnt_M_u16	37075
CONSANGLECPK_Cnt_M_u16	28850
CONSANGLECPK_HwDeg_M_f32	-705.895691
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	28850
CPKVehicleSpeedMsgTimer_mS_M_u32	3258160384
CPKVehicleSpeedValidCount_Cnt_M_u16	45459
CityParkInputConsistentCount_Cnt_M_u16	19086
CityParkInputInvalidCount_Cnt_M_u16	48102

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	3407088128
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2237646080
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	62145
ComputerRazGCTSigInvalidTimer_mS_M_u32	533095680
ComputerRazGCTSigValidCount_Cnt_M_u16	6511
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	22802
DMDFCTCPKSigValidCount_Cnt_M_u16	36697
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	625
DMDRELAXECPKSigValidCount_Cnt_M_u16	20592
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	38221
DateInvalidTimer_mS_M_u32	345048320
DiagMuxOnAbsentTimer_mS_M_u32	2095273216
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1611429120
ESPNTCEnableTimer_mS_M_u32	1948828928
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	20543
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	1111
EffacDefaultDiagTimer_mS_M_u32[1]	872866048
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	45
ElecIntTimer_mS_M_u32[1]	98
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2026452224
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	46161
EtatMTSigValidCount_Cnt_M_u16	27020
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	59054
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	11453
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	52759
ISDAT4V2BSI552MsgTimer_mS_M_u32	178418944
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	30053
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	48071
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	27020
ISDATBSI3F2MsgTimer_mS_M_u32	4101592320
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	2114
ISDATBSI412MsgLenValidCount_Cnt_M_u16	22037
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	46161
ISDATBSI412MsgTimer_mS_M_u32	3114702080
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	62857
ISDATBSI432MsgLenValidCount_Cnt_M_u16	63763
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	30846
ISDATDIRASentFltAcc_Cnt_M_u16	53026
ISDATDIRASentTimer_mS_M_u32	3258160384
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	36040
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	64442
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	45405
ISDYN2CMMMsgTimer_mS_M_u32	241878272
ISDYNAASChkSumInvalidCount_Cnt_M_u16	33879
ISDYNAASChkSumValidCount_Cnt_M_u16	15221
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	33285
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	2656
ISDYNAASMsgLenValidCount_Cnt_M_u16	15382
ISDYNAASMsgTimeValidCount_Cnt_M_u16	33879
ISDYNAASMsgTimer_mS_M_u32	345974016
ISDYNABRChkSumInvalidCount_Cnt_M_u16	22659
ISDYNABRChkSumValidCount_Cnt_M_u16	39466
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	17186
ISDYNABRMsgCountValidCount_Cnt_M_u16	3200
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	64527
ISDYNABRMsgLenValidCount_Cnt_M_u16	14558
ISDYNABRMsgTimeValidCount_Cnt_M_u16	28850
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	611
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1107

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	27020
ISDYNCMM208MsgTimer_mS_M_u32	3125642496
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2295
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1213
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	44112
ISDYNCMM388MsgTimer_mS_M_u32	3269764352
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	62938
ISDYNVOLChkSumValidCount_Cnt_M_u16	34025
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	32680
ISDYNVOLMsgCountValidCount_Cnt_M_u16	39535
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	33908
ISDYNVOLMsgLenValidCount_Cnt_M_u16	2659
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	50101
ISDYNVOLMsgTimer_mS_M_u32	1240622336
IgnOnTimer_mS_M_u32	3434652928
IgnTimeOff_Sec_M_u32	1795682971
ManVehSpd_Kph_M_f32	53.4757004
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	180
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	139
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3113702656
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	161
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1143190784
PrevISDATBSI412MsgDLCError_Cnt_M_u08	13
PrevISDATBSI412MsgRxTime_MSec_M_u32	2763318528
PrevISDATBSI432MsgDLCError_Cnt_M_u08	200
PrevISDATBSI432MsgRxTime_MSec_M_u32	2410464512
PrevISDATDIRAMsgTxTime_MSec_M_u32	1851319552
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	215
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3665556736
PrevISDYNAASMsgDLCError_Cnt_M_u08	117
PrevISDYNAASMsgRxTime_MSec_M_u32	2382914816
PrevISDYNABRMsgDLCError_Cnt_M_u08	108
PrevISDYNABRMsgRxTime_MSec_M_u32	1343268096
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	125
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3215549696
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	132
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1485554944
PrevISDYNVOLMsgDLCError_Cnt_M_u08	36
PrevISDYNVOLMsgRxTime_MSec_M_u32	2949506304
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2252117248
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	289.280914
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	24310
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	62764
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	25259
VitesseVehicleBVRampValidCount_Cnt_M_u16	50849
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	61244
VitesseVehicleBVSigValidCount_Cnt_M_u16	53115
VitesseVehicleBV_Kph_M_f32	619.000671

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	44112
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	51559
VitesseVehiculeRoues_Kph_M_f32	461.173798
k_AASNTCEnableTimeout_mS_u16	62485
k_AASNodeAbsentDiag_Cnt_str.Threshold	3858
k_AASNodeAbsentDiag_Cnt_str.PStep	7794
k_AASNodeAbsentDiag_Cnt_str.NStep	10917
k_AASNodeAbsentTimeout_mS_u16	6705
k_AASNodeTimeout_mS_u16	19500
k_ABSNodeTimeout_mS_u16	8179
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	59456
k_ANGLEVOLANTSigValidThresh_Cnt_u16	22282
k_AngleVolantInvalidThresh_Cnt_u16	9597
k_AngleVolantValidThresh_Cnt_u16	48102
k_BSI552MsgTimeout_mS_u16	13722
k_BSINTCEnableTimeout_mS_u16	10465
k_BSINodeAbsentDiag_Cnt_str.Threshold	21852
k_BSINodeAbsentDiag_Cnt_str.PStep	36253
k_BSINodeAbsentDiag_Cnt_str.NStep	12658
k_BSINodeAbsentTimeout_mS_u16	15694
k_BSINodeTimeout_mS_u16	30846
k_BattOvHi_Volt_f32	17.0653
k_BattOvLo_Volt_f32	25.2497997
k_BattUvHi_Volt_f32	7.84070015
k_BattUvLo_Volt_f32	11.0794001
k_CAVNTCEnableTimeout_mS_u16	37844
k_CAVNodeAbsentDiag_Cnt_str.Threshold	21460
k_CAVNodeAbsentDiag_Cnt_str.PStep	9856
k_CAVNodeAbsentDiag_Cnt_str.NStep	26289
k_CAVNodeAbsentTimeout_mS_u16	17111
k_CAVNodeTimeout_mS_u16	27760
k_CMM388MsgTimeout_mS_u16	15597
k_CMM388NTCEnableTimeout_mS_u16	12313
k_CMMNTCEnableTimeout_mS_u16	5309
k_CMMNodeAbsentDiag_Cnt_str.Threshold	25606
k_CMMNodeAbsentDiag_Cnt_str.PStep	59931
k_CMMNodeAbsentDiag_Cnt_str.NStep	31904
k_CMMNodeAbsentTimeout_mS_u16	64147
k_CONSANGLECPKMax_HwDeg_f32	312.324707
k_CONSANGLECPKMin_HwDeg_f32	-187.400406
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	50000
k_CONSANGLECPKSigValidThresh_Cnt_u16	8295
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	31210
k_CPKVehicleSpeedValidThresh_Cnt_u16	51745
k_CityParkInputInvalidThresh_Cnt_u16	32961
k_CityParkInputValidThresh_Cnt_u16	19086
k_ComputerRazGCTSigValidThresh_Cnt_u16	51971
k_CptTemporelSigValidThresh_Cnt_u16	44005
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	37647
k_DMDFCTCPKSigValidThresh_Cnt_u16	4062
k_DMDFCTCPKValidCount_Cnt_u16	65146
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	45405
k_DMDRELAXECPKSigValidThresh_Cnt_u16	6628
k_DMDRelaxeConsistentThresh_Cnt_u16	10658
k_DateValidThresh_Cnt_u16	52759
k_DefaultVehSpd_Kph_f32	28.2000008
k_DiagMuxOnAbsentTimeout_mS_u16	29728
k_EMNodeTimeout_mS_u16	4397
k_ESPNTCEnableTimeout_mS_u16	65389
k_ESPNodeAbsentDiag_Cnt_str.Threshold	42337
k_ESPNodeAbsentDiag_Cnt_str.PStep	7895
k_ESPNodeAbsentDiag_Cnt_str.NStep	12276
k_ESPNodeAbsentTimeout_mS_u16	12091
k_EtatMTSigInvalidThresh_Cnt_u16	12630
k_EtatMTSigValidThresh_Cnt_u16	31549
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	5673
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	21700
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	63555
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	19982
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	61744
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	43030
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	61874
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	61948

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	26461
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	35942
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	5592
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	51507
k_ISDATDIRASentDiag_Cnt_str.Threshold	40933
k_ISDATDIRASentDiag_Cnt_str.PStep	35365
k_ISDATDIRASentDiag_Cnt_str.NStep	1104
k_ISDATDIRASentTimeout_mS_u16	9391
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	41044
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	8182
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	60649
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	28547
k_ISDYNAASChkSumValidThresh_Cnt_u16	61738
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	55842
k_ISDYNAASMsgCountValidThresh_Cnt_u16	58240
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	58199
k_ISDYNAASMsgLenValidThresh_Cnt_u16	4864
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	12722
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	10917
k_ISDYNABRChkSumValidThresh_Cnt_u16	19444
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	19410
k_ISDYNABRMsgCountValidThresh_Cnt_u16	37009
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	6837
k_ISDYNABRMsgLenValidThresh_Cnt_u16	59199
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	48196
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	17866
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	64055
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	9055
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	5895
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	51590
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	19774
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	49529
k_ISDYNVOLChkSumValidThresh_Cnt_u16	23180
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	48456
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	23550
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	50557
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	17336
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	35973
k_IgnOnTimeout_mS_u16	12709
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	19.3841
k_PowerCutVehSpdLowThresh_Kph_f32	3.79819989
k_PowerCutVehSpdLowTimeout_mS_u16	0
k_VBattMaxAAS_Volt_f32	6.54589987
k_VBattMaxBSI_Volt_f32	16.2964993
k_VBattMaxCAV_Volt_f32	23.6681995
k_VBattMaxCMM388_Volt_f32	19.1707001
k_VBattMaxCMM_Volt_f32	25.3169003
k_VBattMaxESP_Volt_f32	26.9272995
k_VBattMinAAS_Volt_f32	1.43330002
k_VBattMinBSI_Volt_f32	6.92729998
k_VBattMinCAV_Volt_f32	28.3626003
k_VBattMinCMM388_Volt_f32	13.9190998
k_VBattMinCMM_Volt_f32	25.1562004
k_VBattMinESP_Volt_f32	22.3169003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	29078
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	33305
k_VitesseVehicleBVRampValidThresh_Cnt_u16	38568
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	23529
k_VitesseVehicleBVSigValidThresh_Cnt_u16	37275
k_VitesseVehicleBVSpeedPassThresh_kph_f32	44.1078987
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	5697
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	7863
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	345048320
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	157
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	34788
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	872866048
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	132

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	25.4136009
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	681325824
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	35
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.900653064
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2534057216
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3802219776
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2563237120
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	36
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	561939712
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3838125312
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1251722496
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3137496320
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	78
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	94
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	141
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	171
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	183
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3641935104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	30
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	243
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3783894272
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	103
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	446711040
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2118575360
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	23
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	115
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	131
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	151
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	177
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3680351488
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2990
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.761739194
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	637249
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	215.433197
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	54200

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	872866048	872866048	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	872866048	872866048	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	8184	8184	✔
AngleVolantMsgTimer_mS_M_u32	872866048	872866048	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	872866048	872866048	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	872866048	872866048	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	872866048	872866048	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	872866048	872866048	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21852	21852	✔
BSINodeAbsentTimer_mS_M_u32	872866048	872866048	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	872866048	872866048	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	872866048	872866048	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	872866048	872866048	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	872866048	872866048	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	18197	18197	✔
CMMNodeAbsentTimer_mS_M_u32	1251722496	1251722496	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	28850	28850	✔
CONSANGLECPK_HwDeg_M_f32	-705.895691	-705.895691 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	28850	28850	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3258160384	3258160384	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	45459	45459	✔
CityParkInputConsistentCount_Cnt_M_u16	19086	19086	✔
CityParkInputInvalidCount_Cnt_M_u16	48102	48102	✔
CityParkInputMsgTimer_mS_M_u32	872866048	872866048	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	872866048	872866048	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	872866048	872866048	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	872866048	872866048	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	872866048	872866048	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	872866048	872866048	✔
ESPNTCEnableTimer_mS_M_u32	872866048	872866048	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	42337	42337	✔
ESPNodeAbsentTimer_mS_M_u32	872866048	872866048	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1111	1111	✔
EffacDefaultDiagTimer_mS_M_u32[1]	872866048	872866048	✔
ElecIntCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	872866048	872866048	✔
ElecIntTimer_mS_M_u32[1]	98	98	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	872866048	872866048	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	872866048	872866048	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	872866048	872866048	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	872866048	872866048	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	872866048	872866048	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	872866048	872866048	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	872866048	872866048	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	872866048	872866048	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	872866048	872866048	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	872866048	872866048	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	872866048	872866048	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	872866048	872866048	✔
IgnOnTimer_mS_M_u32	3434652928	3434652928	✔
IgnTimeOff_Sec_M_u32	1795682971	1795682971	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	192	192	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2534057216	2534057216	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	222	222	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3802219776	3802219776	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	49	49	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2563237120	2563237120	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	36	36	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	561939712	561939712	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1851319552	1851319552	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	132	132	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1251722496	1251722496	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	194	194	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3137496320	3137496320	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	209	209	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3641935104	3641935104	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	60	60	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3783894272	3783894272	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	103	103	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	446711040	446711040	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	136	136	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2118575360	2118575360	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3680351488	3680351488	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	289.280914	289.280914	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	619.000671	619.000671	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	461.173798	461.173798	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	28850	28850	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1795682971	1795682971	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-705.895691	-705.895691 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	28.2000008	28.2000008	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.46 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	805372928
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	35947
AASNodeAbsentTimer_mS_M_u32	273642496
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	34844
ANGLEVOLANTSigValidCount_Cnt_M_u16	51039
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	33360
AngleVolantMsgTimer_mS_M_u32	805372928
AngleVolantValidCount_Cnt_M_u16	18818
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1466774528
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	4232033280
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3603473408
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2475516928
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	54715
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1647649792
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	30959
CAVNodeAbsentTimer_mS_M_u32	2521502720
CDD_SrlComVehSpd_Kph_G_f32	395.526398
CMM388NTCEnableTimer_mS_M_u32	3071890432
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	135336960
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	10067
CMMNodeAbsentTimer_mS_M_u32	206005248
CONSANGLECPKSigInvalidCount_Cnt_M_u16	63589
CONSANGLECPKSigValidCount_Cnt_M_u16	3961
CONSANGLECPK_Cnt_M_u16	43996
CONSANGLECPK_HwDeg_M_f32	134.584793
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43996
CPKVehicleSpeedMsgTimer_mS_M_u32	1905787904
CPKVehicleSpeedValidCount_Cnt_M_u16	31745
CityParkInputConsistentCount_Cnt_M_u16	44294
CityParkInputInvalidCount_Cnt_M_u16	2557
CityParkInputMsgTimer_mS_M_u32	2534057216
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1

Name	Input Value
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1423143936
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	62959
ComputerRazGCTSigInvalidTimer_mS_M_u32	3894383616
ComputerRazGCTSigValidCount_Cnt_M_u16	1123
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	57977
DMDFCTCPKSigValidCount_Cnt_M_u16	63077
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	10462
DMDRELAXECPKSigValidCount_Cnt_M_u16	54689
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	36682
DateInvalidTimer_mS_M_u32	4232033280
DiagMuxOnAbsentTimer_mS_M_u32	2961753088
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2475516928
ESPNTCEnableTimer_mS_M_u32	3967316992
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	18547
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	65535
EffacDefaultDiagTimer_mS_M_u32[1]	95535
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	66
ElecIntTimer_mS_M_u32[1]	78
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	743908352
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	5758
EtatMTSigValidCount_Cnt_M_u16	32142
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24359
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	25531
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	45611
ISDAT4V2BSI552MsgTimer_mS_M_u32	1808491520
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	31426
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	52826
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	32142
ISDATBSI3F2MsgTimer_mS_M_u32	566674432
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	50987
ISDATBSI412MsgLenValidCount_Cnt_M_u16	50291
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	5758
ISDATBSI412MsgTimer_mS_M_u32	390005760
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	57815
ISDATBSI432MsgLenValidCount_Cnt_M_u16	40439
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	16696
ISDATDIRASentFltAcc_Cnt_M_u16	52556
ISDATDIRASentTimer_mS_M_u32	1905787904
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	12186
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	18818
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	50584
ISDYN2CMMMsgTimer_mS_M_u32	2779935744
ISDYNAASChkSumInvalidCount_Cnt_M_u16	6445
ISDYNAASChkSumValidCount_Cnt_M_u16	2705
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	41633
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	37778
ISDYNAASMsgLenValidCount_Cnt_M_u16	29998
ISDYNAASMsgTimeValidCount_Cnt_M_u16	6445
ISDYNAASMsgTimer_mS_M_u32	1553290240
ISDYNABRChkSumInvalidCount_Cnt_M_u16	17960
ISDYNABRChkSumValidCount_Cnt_M_u16	47092
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	51404
ISDYNABRMsgCountValidCount_Cnt_M_u16	33648
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	58116
ISDYNABRMsgLenValidCount_Cnt_M_u16	856
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43996
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	612
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1109
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	32142
ISDYNCMM208MsgTimer_mS_M_u32	2634691584
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2299

Name	Input Value
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1215
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	4032
ISDYNCMM388MsgTimer_mS_M_u32	1204081664
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	57763
ISDYNVOLChkSumValidCount_Cnt_M_u16	2871
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	18103
ISDYNVOLMsgCountValidCount_Cnt_M_u16	44323
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	49108
ISDYNVOLMsgLenValidCount_Cnt_M_u16	33992
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	10067
ISDYNVOLMsgTimer_mS_M_u32	429626368
IgnOnTimer_mS_M_u32	2051593216
IgnTimeOff_Sec_M_u32	1763311265
ManVehSpd_Kph_M_f32	65.6983032
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	182
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	166
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3396125696
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	182
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1413981184
PrevISDATBSI412MsgDLCError_Cnt_M_u08	154
PrevISDATBSI412MsgRxTime_MSec_M_u32	861148160
PrevISDATBSI432MsgDLCError_Cnt_M_u08	208
PrevISDATBSI432MsgRxTime_MSec_M_u32	2850845696
PrevISDATDIRAMsgTxTime_MSec_M_u32	1718096896
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	135
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1111417856
PrevISDYNAASMsgDLCError_Cnt_M_u08	40
PrevISDYNAASMsgRxTime_MSec_M_u32	626627584
PrevISDYNABRMsgDLCError_Cnt_M_u08	33
PrevISDYNABRMsgRxTime_MSec_M_u32	1346425856
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	15
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1417057280
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	84
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2337240064
PrevISDYNVOLMsgDLCError_Cnt_M_u08	114
PrevISDYNVOLMsgRxTime_MSec_M_u32	3054048256
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2306671616
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	202.423004
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	28112
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	8684
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	30385
VitesseVehicleBVRampValidCount_Cnt_M_u16	49549
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	20093
VitesseVehicleBVSigValidCount_Cnt_M_u16	17536
VitesseVehicleBV_Kph_M_f32	431.081909
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	4032
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	44860
VitesseVehiculeRoues_Kph_M_f32	482.812897

Name	Input Value
k_AASNTCEnableTimeout_mS_u16	28083
k_AASNodeAbsentDiag_Cnt_str.Threshold	15068
k_AASNodeAbsentDiag_Cnt_str.PStep	35763
k_AASNodeAbsentDiag_Cnt_str.NStep	50769
k_AASNodeAbsentTimeout_mS_u16	35357
k_AASNodeTimeout_mS_u16	7404
k_ABSNodeTimeout_mS_u16	20950
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	42418
k_ANGLEVOLANTSigValidThresh_Cnt_u16	8210
k_AngleVolantInvalidThresh_Cnt_u16	16569
k_AngleVolantValidThresh_Cnt_u16	2557
k_BSI552MsgTimeout_mS_u16	63139
k_BSINTCEnableTimeout_mS_u16	42959
k_BSINodeAbsentDiag_Cnt_str.Threshold	21892
k_BSINodeAbsentDiag_Cnt_str.PStep	36236
k_BSINodeAbsentDiag_Cnt_str.NStep	12681
k_BSINodeAbsentTimeout_mS_u16	35400
k_BSINodeTimeout_mS_u16	16696
k_BattOvHi_Volt_f32	15.6381998
k_BattOvLo_Volt_f32	25.0764999
k_BattUvHi_Volt_f32	15.1920004
k_BattUvLo_Volt_f32	26.6455002
k_CAVNTCEnableTimeout_mS_u16	47667
k_CAVNodeAbsentDiag_Cnt_str.Threshold	13613
k_CAVNodeAbsentDiag_Cnt_str.PStep	61281
k_CAVNodeAbsentDiag_Cnt_str.NStep	59207
k_CAVNodeAbsentTimeout_mS_u16	34349
k_CAVNodeTimeout_mS_u16	21985
k_CMM388MsgTimeout_mS_u16	51051
k_CMM388NTCEnableTimeout_mS_u16	40423
k_CMMNTCEnableTimeout_mS_u16	64698
k_CMMNodeAbsentDiag_Cnt_str.Threshold	50143
k_CMMNodeAbsentDiag_Cnt_str.PStep	53657
k_CMMNodeAbsentDiag_Cnt_str.NStep	37440
k_CMMNodeAbsentTimeout_mS_u16	52152
k_CONSANGLECPKMax_HwDeg_f32	656.138611
k_CONSANGLECPKMin_HwDeg_f32	-114.2808
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	51904
k_CONSANGLECPKSigValidThresh_Cnt_u16	43580
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	2994
k_CPKVehicleSpeedValidThresh_Cnt_u16	48526
k_CityParkInputInvalidThresh_Cnt_u16	17774
k_CityParkInputValidThresh_Cnt_u16	44294
k_ComputerRazGCTSigValidThresh_Cnt_u16	29160
k_CptTemporelSigValidThresh_Cnt_u16	62976
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	7684
k_DMDFCTCPKSigValidThresh_Cnt_u16	32344
k_DMDFCTCPKValidCount_Cnt_u16	39107
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	50584
k_DMDRELAXECPKSigValidThresh_Cnt_u16	17092
k_DMDRelaxeConsistentThresh_Cnt_u16	35722
k_DateValidThresh_Cnt_u16	45611
k_DefaultVehSpd_Kph_f32	106.098198
k_DiagMuxOnAbsentTimeout_mS_u16	55698
k_EMNodeTimeout_mS_u16	39850
k_ESPNTCEnableTimeout_mS_u16	10347
k_ESPNodeAbsentDiag_Cnt_str.Threshold	39214
k_ESPNodeAbsentDiag_Cnt_str.PStep	57797
k_ESPNodeAbsentDiag_Cnt_str.NStep	37798
k_ESPNodeAbsentTimeout_mS_u16	52672
k_EtatMTSigInvalidThresh_Cnt_u16	51119
k_EtatMTSigValidThresh_Cnt_u16	8379
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	62197
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	15845
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	47079
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	54471
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	4639
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	14255
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	53596
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	38716
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	56411
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	10432
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	62248

Name	Input Value
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	55639
k_ISDATDIRASentDiag_Cnt_str.Threshold	8056
k_ISDATDIRASentDiag_Cnt_str.PStep	40691
k_ISDATDIRASentDiag_Cnt_str.NStep	38120
k_ISDATDIRASentTimeout_mS_u16	37284
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	6132
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	33360
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	20471
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	296
k_ISDYNAASChkSumValidThresh_Cnt_u16	45812
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	972
k_ISDYNAASMsgCountValidThresh_Cnt_u16	65136
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	62892
k_ISDYNAASMsgLenValidThresh_Cnt_u16	6256
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	12314
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	12098
k_ISDYNABRChkSumValidThresh_Cnt_u16	41494
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	4283
k_ISDYNABRMsgCountValidThresh_Cnt_u16	55614
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	8787
k_ISDYNABRMsgLenValidThresh_Cnt_u16	33651
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	57893
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	2388
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	1356
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	9043
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	49948
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	16991
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	46581
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	14214
k_ISDYNVOLChkSumValidThresh_Cnt_u16	21262
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	25944
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	49784
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	37626
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	40714
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	44769
k_IgnOnTimeout_mS_u16	38658
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	169.046005
k_PowerCutVehSpdLowThresh_Kph_f32	255
k_PowerCutVehSpdLowTimeout_mS_u16	65535
k_VBattMaxAAS_Volt_f32	3.13989997
k_VBattMaxBSI_Volt_f32	20.1713009
k_VBattMaxCAV_Volt_f32	0.725000024
k_VBattMaxCMM388_Volt_f32	17.3759003
k_VBattMaxCMM_Volt_f32	11.6433001
k_VBattMaxESP_Volt_f32	5.51429987
k_VBattMinAAS_Volt_f32	17.2852993
k_VBattMinBSI_Volt_f32	5.51429987
k_VBattMinCAV_Volt_f32	28.7621002
k_VBattMinCMM388_Volt_f32	21.6257
k_VBattMinCMM_Volt_f32	26.6830006
k_VBattMinESP_Volt_f32	11.6433001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	11310
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	41318
k_VitesseVehicleBVRampValidThresh_Cnt_u16	439
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	34359
k_VitesseVehicleBVSigValidThresh_Cnt_u16	19423
k_VitesseVehicleBVSpeedPassThresh_kph_f32	530.934204
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	13295
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	37195
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4232033280
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	24
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52348
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1481515008
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	84
target_SrlComInput_Per1_Batt_Volt_f32.value	15.4715996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1

Name	Input Value
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	685646848
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	81
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.45125863
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3813856256
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	87
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	588182528
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1662718976
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1802974208
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	69424128
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	237
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4112479232
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	107713536
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	45
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	55
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	213
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3635950592
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	54
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	81
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	177
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	215
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	240
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3218461696
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	923923456
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1855853568
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	43
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	82
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	109
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4137264128
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	957
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.093459852
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	298067
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	3.1487
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	38794

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1481515008	1481515008	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	107713536	107713536	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	33360	33360	✔
AngleVolantMsgTimer_mS_M_u32	1481515008	1481515008	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1466774528	1466774528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	4232033280	4232033280	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	1481515008	1481515008	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2475516928	2475516928	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	42034	42034	✔
BSINodeAbsentTimer_mS_M_u32	1802974208	1802974208	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1481515008	1481515008	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1855853568	1855853568	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1481515008	1481515008	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1481515008	1481515008	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4112479232	4112479232	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	43996	43996	✔
CONSANGLECPK_HwDeg_M_f32	134.584793	134.584793 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43996	43996	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1905787904	1905787904	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	31745	31745	✔
CityParkInputConsistentCount_Cnt_M_u16	44294	44294	✔
CityParkInputInvalidCount_Cnt_M_u16	2559	2559	✔
CityParkInputMsgTimer_mS_M_u32	1481515008	1481515008	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1423143936	1423143936	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3894383616	3894383616	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1481515008	1481515008	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1481515008	1481515008	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1481515008	1481515008	✔
ESPNTCEnableTimer_mS_M_u32	1481515008	1481515008	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1481515008	1481515008	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	65535	65535	✔
EffacDefaultDiagTimer_mS_M_u32[1]	95535	95535	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	66	66	✔
ElecIntTimer_mS_M_u32[1]	78	78	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1481515008	1481515008	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24360	24360	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3813856256	3813856256	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	31427	31427	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	588182528	588182528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	50988	50988	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1662718976	1662718976	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1481515008	1481515008	✔
ISDATDIRASentFltAcc_Cnt_M_u16	14436	14436	✔
ISDATDIRASentTimer_mS_M_u32	1481515008	1481515008	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1481515008	1481515008	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1481515008	1481515008	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1481515008	1481515008	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1481515008	1481515008	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1481515008	1481515008	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1481515008	1481515008	✔
IgnOnTimer_mS_M_u32	2051593216	2051593216	✔
IgnTimeOff_Sec_M_u32	1763311265	1763311265	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	8	8	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	173	173	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3813856256	3813856256	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	87	87	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	588182528	588182528	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	158	158	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1662718976	1662718976	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	73	73	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1802974208	1802974208	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	69424128	69424128	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	237	237	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4112479232	4112479232	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	117	117	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	107713536	107713536	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	213	213	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3635950592	3635950592	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	245	245	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3218461696	3218461696	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	119	119	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	923923456	923923456	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	86	86	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1855853568	1855853568	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4137264128	4137264128	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	202.423004	202.423004	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	431.081909	431.081909	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	482.812897	482.812897	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	43996	43996	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1763311265	1763311265	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	134.584793	134.584793 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	106.098198	106.098198	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.47 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1823192832
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	8556
AASNodeAbsentTimer_mS_M_u32	1367369472
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	36954
ANGLEVOLANTSigValidCount_Cnt_M_u16	3662
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	5053
AngleVolantMsgTimer_mS_M_u32	1823192832
AngleVolantValidCount_Cnt_M_u16	44710
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	589768448
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2662311680
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2664748800
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1803982592
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	58237
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1318016768
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	29281
CAVNodeAbsentTimer_mS_M_u32	3054339840
CDD_SrlComVehSpd_Kph_G_f32	461.789795
CMM388NTCEnableTimer_mS_M_u32	1554171648
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4173039360
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	29684
CMMNodeAbsentTimer_mS_M_u32	1767413504
CONSANGLECPKSigInvalidCount_Cnt_M_u16	38525

Name	Input Value
CONSANGLECPKSigValidCount_Cnt_M_u16	52481
CONSANGLECPK_Cnt_M_u16	17368
CONSANGLECPK_HwDeg_M_f32	-292.407196
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17368
CPKVehicleSpeedMsgTimer_mS_M_u32	3286677248
CPKVehicleSpeedValidCount_Cnt_M_u16	15122
CityParkInputConsistentCount_Cnt_M_u16	37914
CityParkInputInvalidCount_Cnt_M_u16	27189
CityParkInputMsgTimer_mS_M_u32	3813856256
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2482267904
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	62688
ComputerRazGCTSigInvalidTimer_mS_M_u32	2995783424
ComputerRazGCTSigValidCount_Cnt_M_u16	16899
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	53441
DMDFCTCPKSigValidCount_Cnt_M_u16	28861
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	13844
DMDRELAXECPKSigValidCount_Cnt_M_u16	27528
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	42446
DateInvalidTimer_mS_M_u32	2662311680
DiagMuxOnAbsentTimer_mS_M_u32	3121903360
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1803982592
ESPNTCEnableTimer_mS_M_u32	2701485824
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	48212
EffacDefaultDiagCount_Cnt_M_u08	2
EffacDefaultDiagTimer_mS_M_u32[0]	579
EffacDefaultDiagTimer_mS_M_u32[1]	989
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	101
ElecIntTimer_mS_M_u32[1]	105
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	4163458816
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	25459
EtatMTSigValidCount_Cnt_M_u16	39427
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	59959
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	22587
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	54635
ISDAT4V2BSI552MsgTimer_mS_M_u32	1523357440
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	16421
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	53534
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	39427
ISDATBSI3F2MsgTimer_mS_M_u32	3730470656
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	19437
ISDATBSI412MsgLenValidCount_Cnt_M_u16	40917
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	25459
ISDATBSI412MsgTimer_mS_M_u32	787592960
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	21608
ISDATBSI432MsgLenValidCount_Cnt_M_u16	52168
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	32134
ISDATDIRASentFltAcc_Cnt_M_u16	10570
ISDATDIRASentTimer_mS_M_u32	3286677248
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	12446
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	44710
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	25444
ISDYN2CMMMsgTimer_mS_M_u32	3713492736
ISDYNAASChkSumInvalidCount_Cnt_M_u16	806
ISDYNAASChkSumValidCount_Cnt_M_u16	60090
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	57161
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	28280
ISDYNAASMsgLenValidCount_Cnt_M_u16	25956
ISDYNAASMsgTimeValidCount_Cnt_M_u16	806
ISDYNAASMsgTimer_mS_M_u32	1546569472
ISDYNABRChkSumInvalidCount_Cnt_M_u16	32693

Name	Input Value
ISDYNABRChkSumValidCount_Cnt_M_u16	34321
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	12361
ISDYNABRMsgCountValidCount_Cnt_M_u16	48157
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	4768
ISDYNABRMsgLenValidCount_Cnt_M_u16	11620
ISDYNABRMsgTimeValidCount_Cnt_M_u16	17368
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	613
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1111
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	39427
ISDYNCMM208MsgTimer_mS_M_u32	105916160
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2303
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1217
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	54252
ISDYNCMM388MsgTimer_mS_M_u32	3097511680
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	21187
ISDYNVOLChkSumValidCount_Cnt_M_u16	20935
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	7175
ISDYNVOLMsgCountValidCount_Cnt_M_u16	50307
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	6705
ISDYNVOLMsgLenValidCount_Cnt_M_u16	50966
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	29684
ISDYNVOLMsgTimer_mS_M_u32	236717824
IgnOnTimer_mS_M_u32	823412480
IgnTimeOff_Sec_M_u32	2737388570
ManVehSpd_Kph_M_f32	604.569824
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	184
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	117
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4234704640
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	72
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3797407488
PrevISDATBSI412MsgDLCError_Cnt_M_u08	38
PrevISDATBSI412MsgRxTime_MSec_M_u32	1123190528
PrevISDATBSI432MsgDLCError_Cnt_M_u08	77
PrevISDATBSI432MsgRxTime_MSec_M_u32	950626048
PrevISDATDIRAMsgTxTime_MSec_M_u32	4189488896
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	129
PrevISDYN2CMMMsgRxTime_MSec_M_u32	91363072
PrevISDYNAASMsgDLCError_Cnt_M_u08	38
PrevISDYNAASMsgRxTime_MSec_M_u32	1658980096
PrevISDYNABRMsgDLCError_Cnt_M_u08	163
PrevISDYNABRMsgRxTime_MSec_M_u32	2402043648
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	120
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2307589888
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	156
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3766511360
PrevISDYNVOLMsgDLCError_Cnt_M_u08	73
PrevISDYNVOLMsgRxTime_MSec_M_u32	3469969152
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1345828608
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	287.33429
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	22462
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	55082
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	3

Name	Input Value
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	283
VitesseVehicleBVRampValidCount_Cnt_M_u16	48199
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	311
VitesseVehicleBVSigValidCount_Cnt_M_u16	23275
VitesseVehicleBV_Kph_M_f32	542.282471
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	54252
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	4409
VitesseVehiculeRoues_Kph_M_f32	339.658691
k_AASNTCEnableTimeout_mS_u16	6739
k_AASNodeAbsentDiag_Cnt_str.Threshold	55416
k_AASNodeAbsentDiag_Cnt_str.PStep	18700
k_AASNodeAbsentDiag_Cnt_str.NStep	23435
k_AASNodeAbsentTimeout_mS_u16	6357
k_AASNodeTimeout_mS_u16	58922
k_ABSNodeTimeout_mS_u16	13994
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	13527
k_ANGLEVOLANTSigValidThresh_Cnt_u16	29047
k_AngleVolantInvalidThresh_Cnt_u16	27522
k_AngleVolantValidThresh_Cnt_u16	27189
k_BSI552MsgTimeout_mS_u16	38660
k_BSINTCEnableTimeout_mS_u16	57984
k_BSINodeAbsentDiag_Cnt_str.Threshold	21932
k_BSINodeAbsentDiag_Cnt_str.PStep	36219
k_BSINodeAbsentDiag_Cnt_str.NStep	12704
k_BSINodeAbsentTimeout_mS_u16	56277
k_BSINodeTimeout_mS_u16	32134
k_BattOvHi_Volt_f32	20.8698006
k_BattOvLo_Volt_f32	20.5799007
k_BattUvHi_Volt_f32	9.06890011
k_BattUvLo_Volt_f32	8.70009995
k_CAVNTCEnableTimeout_mS_u16	45459
k_CAVNodeAbsentDiag_Cnt_str.Threshold	61373
k_CAVNodeAbsentDiag_Cnt_str.PStep	2683
k_CAVNodeAbsentDiag_Cnt_str.NStep	55649
k_CAVNodeAbsentTimeout_mS_u16	49831
k_CAVNodeTimeout_mS_u16	28169
k_CMM388MsgTimeout_mS_u16	28780
k_CMM388NTCEnableTimeout_mS_u16	56568
k_CMMNTCEnableTimeout_mS_u16	39485
k_CMMNodeAbsentDiag_Cnt_str.Threshold	9681
k_CMMNodeAbsentDiag_Cnt_str.PStep	64698
k_CMMNodeAbsentDiag_Cnt_str.NStep	12829
k_CMMNodeAbsentTimeout_mS_u16	43973
k_CONSANGLECPKMax_HwDeg_f32	480.393402
k_CONSANGLECPKMin_HwDeg_f32	-536.56427
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	41708
k_CONSANGLECPKSigValidThresh_Cnt_u16	8249
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	45528
k_CPKVehicleSpeedValidThresh_Cnt_u16	46276
k_CityParkInputInvalidThresh_Cnt_u16	6627
k_CityParkInputValidThresh_Cnt_u16	37914
k_ComputerRazGCTSigValidThresh_Cnt_u16	29363
k_CptTemporelSigValidThresh_Cnt_u16	29228
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	24992
k_DMDFCTCPKSigValidThresh_Cnt_u16	48228
k_DMDFCTCPKValidCount_Cnt_u16	47717
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	25444
k_DMDRELAXECPKSigValidThresh_Cnt_u16	51104
k_DMDRelaxeConsistentThresh_Cnt_u16	34126
k_DateValidThresh_Cnt_u16	54635
k_DefaultVehSpd_Kph_f32	198.888
k_DiagMuxOnAbsentTimeout_mS_u16	4790
k_EMNodeTimeout_mS_u16	174
k_ESPNTCEnableTimeout_mS_u16	21485
k_ESPNodeAbsentDiag_Cnt_str.Threshold	22978
k_ESPNodeAbsentDiag_Cnt_str.PStep	16663
k_ESPNodeAbsentDiag_Cnt_str.NStep	23499
k_ESPNodeAbsentTimeout_mS_u16	50605
k_EtatMTSigInvalidThresh_Cnt_u16	55072

Name	Input Value
k_EtatMTSigValidThresh_Cnt_u16	10172
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	51215
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	54015
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	14199
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	34326
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	22991
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	2657
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	55769
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	13305
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	29916
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	23852
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	51636
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	5736
k_ISDATDIRASentDiag_Cnt_str.Threshold	50524
k_ISDATDIRASentDiag_Cnt_str.PStep	27716
k_ISDATDIRASentDiag_Cnt_str.NStep	15614
k_ISDATDIRASentTimeout_mS_u16	36161
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	3729
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	5053
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	3401
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	20149
k_ISDYNAASChkSumValidThresh_Cnt_u16	38161
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	32585
k_ISDYNAASMsgCountValidThresh_Cnt_u16	19229
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	33065
k_ISDYNAASMsgLenValidThresh_Cnt_u16	926
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	24927
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	42470
k_ISDYNABRChkSumValidThresh_Cnt_u16	51498
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	12925
k_ISDYNABRMsgCountValidThresh_Cnt_u16	5297
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	33524
k_ISDYNABRMsgLenValidThresh_Cnt_u16	2900
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	22012
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	38194
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	21898
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	12021
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	57178
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	40270
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	17997
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	9948
k_ISDYNVOLChkSumValidThresh_Cnt_u16	8196
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	14757
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	30341
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	56831
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	9615
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	14153
k_IgnOnTimeout_mS_u16	63592
k_JDD2010Selected_Cnt_Igc	1
k_PowerCutVehSpdHighThresh_Kph_f32	156.5448
k_PowerCutVehSpdLowThresh_Kph_f32	32.2713013
k_PowerCutVehSpdLowTimeout_mS_u16	6780
k_VBattMaxAAS_Volt_f32	29.6625004
k_VBattMaxBSI_Volt_f32	27.7187004
k_VBattMaxCAV_Volt_f32	22.0506992
k_VBattMaxCMM388_Volt_f32	28.6233997
k_VBattMaxCMM_Volt_f32	1.70299995
k_VBattMaxESP_Volt_f32	29.9836006
k_VBattMinAAS_Volt_f32	23.8034
k_VBattMinBSI_Volt_f32	2.9835999
k_VBattMinCAV_Volt_f32	9.57909966
k_VBattMinCMM388_Volt_f32	17.3885002
k_VBattMinCMM_Volt_f32	17.9111004
k_VBattMinESP_Volt_f32	1.70299995
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	14819
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	58875
k_VitesseVehicleBVRampValidThresh_Cnt_u16	60167
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	57543
k_VitesseVehicleBVSigValidThresh_Cnt_u16	23439
k_VitesseVehicleBVSpeedPassThresh_kph_f32	522.823975
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	16737
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	50445
target_Pim_ElecIntData	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Pim_ShutdownTimeData.Time_Sec_u32	2662311680
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	202
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	58160
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	456418048
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	156
target_SrlComInput_Per1_Batt_Volt_f32.value	6.6079998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3734263552
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	25
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.36471352
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2650162944
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	101
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2000807680
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	201
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2409465600
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2399741696
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	495240960
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3809502976
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2276198144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	58
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	104
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	196
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	201
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2336630528
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	45
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	47
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	160
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3563931392
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	121169664
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	957646592
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	164
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	165
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	189
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3277969152
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1527
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.946470618
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	4962
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	155.486404
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	17040

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	456418048	456418048	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	55416	55416	✔
AASNodeAbsentTimer_mS_M_u32	456418048	456418048	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	456418048	456418048	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	589768448	589768448	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	2662311680	2662311680	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	2664748800	2664748800	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	1803982592	1803982592	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21932	21932	✔
BSINodeAbsentTimer_mS_M_u32	456418048	456418048	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	456418048	456418048	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	456418048	456418048	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	456418048	456418048	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	456418048	456418048	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	9681	9681	✔
CMMNodeAbsentTimer_mS_M_u32	456418048	456418048	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	17368	17368	✔
CONSANGLECPK_HwDeg_M_f32	-292.407196	-292.407196 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	456418048	456418048	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	456418048	456418048	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	456418048	456418048	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	456418048	456418048	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	456418048	456418048	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	456418048	456418048	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	456418048	456418048	✔
ESPNTCEnableTimer_mS_M_u32	456418048	456418048	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	456418048	456418048	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	579	579	✔
EffacDefaultDiagTimer_mS_M_u32[1]	989	989	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	456418048	456418048	✔
ElecIntTimer_mS_M_u32[1]	105	105	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	456418048	456418048	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2650162944	2650162944	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2000807680	2000807680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2409465600	2409465600	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2399741696	2399741696	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	456418048	456418048	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	456418048	456418048	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	456418048	456418048	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	456418048	456418048	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	456418048	456418048	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	456418048	456418048	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	456418048	456418048	✔
IgnOnTimer_mS_M_u32	823412480	823412480	✔
IgnTimeOff_Sec_M_u32	2737388570	2737388570	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	108	108	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2650162944	2650162944	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	101	101	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2000807680	2000807680	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	201	201	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2409465600	2409465600	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	63	63	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2399741696	2399741696	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4189488896	4189488896	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3809502976	3809502976	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	166	166	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2276198144	2276198144	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	223	223	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2336630528	2336630528	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3563931392	3563931392	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	208	208	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	121169664	121169664	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	957646592	957646592	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3277969152	3277969152	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	287.33429	287.33429	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	542.282471	542.282471	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	339.658691	339.658691	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	17368	17368	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2737388570	2737388570	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-292.407196	-292.407196 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	198.888	198.888	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.48 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	336631040
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	42477
AASNodeAbsentTimer_mS_M_u32	2173420800
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	32775
ANGLEVOLANTSigValidCount_Cnt_M_u16	62086
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	8182
AngleVolantMsgTimer_mS_M_u32	336631040
AngleVolantValidCount_Cnt_M_u16	64442
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2418836736
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	345048320
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1241036032
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1611429120
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	46290

Name	Input Value
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3648992512
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	65345
CAVNodeAbsentTimer_mS_M_u32	3350717696
CDD_SrlComVehSpd_Kph_G_f32	359.941406
CMM388NTCEnableTimer_mS_M_u32	1718822144
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1953883392
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	50101
CMMNodeAbsentTimer_mS_M_u32	265188608
CONSANGLECPKSigInvalidCount_Cnt_M_u16	42564
CONSANGLECPKSigValidCount_Cnt_M_u16	37075
CONSANGLECPK_Cnt_M_u16	28850
CONSANGLECPK_HwDeg_M_f32	-705.895691
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	28850
CPKVehicleSpeedMsgTimer_mS_M_u32	3258160384
CPKVehicleSpeedValidCount_Cnt_M_u16	45459
CityParkInputConsistentCount_Cnt_M_u16	19086
CityParkInputInvalidCount_Cnt_M_u16	48102
CityParkInputMsgTimer_mS_M_u32	3407088128
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2237646080
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	62145
ComputerRazGCTSigInvalidTimer_mS_M_u32	533095680
ComputerRazGCTSigValidCount_Cnt_M_u16	6511
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	22802
DMDFCTCPKSigValidCount_Cnt_M_u16	36697
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	625
DMDRELAXECPKSigValidCount_Cnt_M_u16	20592
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	38221
DateInvalidTimer_mS_M_u32	345048320
DiagMuxOnAbsentTimer_mS_M_u32	2095273216
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1611429120
ESPNTCEnableTimer_mS_M_u32	1948828928
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	20543
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	1111
EffacDefaultDiagTimer_mS_M_u32[1]	872866048
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	45
ElecIntTimer_mS_M_u32[1]	98
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2026452224
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	46161
EtatMTSigValidCount_Cnt_M_u16	27020
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	59054
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	11453
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	52759
ISDAT4V2BSI552MsgTimer_mS_M_u32	178418944
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	30053
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	48071
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	27020
ISDATBSI3F2MsgTimer_mS_M_u32	4101592320
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	2114
ISDATBSI412MsgLenValidCount_Cnt_M_u16	22037
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	46161
ISDATBSI412MsgTimer_mS_M_u32	3114702080
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	62857
ISDATBSI432MsgLenValidCount_Cnt_M_u16	63763
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	30846
ISDATDIRASentFltAcc_Cnt_M_u16	53026
ISDATDIRASentTimer_mS_M_u32	3258160384

Name	Input Value
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	36040
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	64442
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	45405
ISDYN2CMMMsgTimer_mS_M_u32	241878272
ISDYNAASChkSumInvalidCount_Cnt_M_u16	33879
ISDYNAASChkSumValidCount_Cnt_M_u16	15221
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	33285
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	2656
ISDYNAASMsgLenValidCount_Cnt_M_u16	15382
ISDYNAASMsgTimeValidCount_Cnt_M_u16	33879
ISDYNAASMsgTimer_mS_M_u32	345974016
ISDYNABRChkSumInvalidCount_Cnt_M_u16	22659
ISDYNABRChkSumValidCount_Cnt_M_u16	39466
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	17186
ISDYNABRMsgCountValidCount_Cnt_M_u16	3200
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	64527
ISDYNABRMsgLenValidCount_Cnt_M_u16	14558
ISDYNABRMsgTimeValidCount_Cnt_M_u16	28850
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	611
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1107
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	27020
ISDYNCMM208MsgTimer_mS_M_u32	3125642496
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2295
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1213
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	44112
ISDYNCMM388MsgTimer_mS_M_u32	3269764352
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	62938
ISDYNVOLChkSumValidCount_Cnt_M_u16	34025
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	32680
ISDYNVOLMsgCountValidCount_Cnt_M_u16	39535
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	33908
ISDYNVOLMsgLenValidCount_Cnt_M_u16	2659
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	50101
ISDYNVOLMsgTimer_mS_M_u32	1240622336
IgnOnTimer_mS_M_u32	3434652928
IgnTimeOff_Sec_M_u32	1795682971
ManVehSpd_Kph_M_f32	53.4757004
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	180
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	139
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3113702656
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	161
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1143190784
PrevISDATBSI412MsgDLCError_Cnt_M_u08	13
PrevISDATBSI412MsgRxTime_MSec_M_u32	2763318528
PrevISDATBSI432MsgDLCError_Cnt_M_u08	200
PrevISDATBSI432MsgRxTime_MSec_M_u32	2410464512
PrevISDATDIRAMsgTxTime_MSec_M_u32	1851319552
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	215
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3665556736
PrevISDYNAASMsgDLCError_Cnt_M_u08	117
PrevISDYNAASMsgRxTime_MSec_M_u32	2382914816
PrevISDYNABRMsgDLCError_Cnt_M_u08	108
PrevISDYNABRMsgRxTime_MSec_M_u32	1343268096
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	125
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3215549696
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	132
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1485554944
PrevISDYNVOLMsgDLCError_Cnt_M_u08	36
PrevISDYNVOLMsgRxTime_MSec_M_u32	2949506304
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2252117248
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	289.280914

Name	Input Value
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	24310
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	62764
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	25259
VitesseVehicleBVRampValidCount_Cnt_M_u16	50849
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	61244
VitesseVehicleBVSigValidCount_Cnt_M_u16	53115
VitesseVehicleBV_Kph_M_f32	619.000671
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	44112
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	51559
VitesseVehiculeRoues_Kph_M_f32	461.173798
k_AASNTCEnableTimeout_mS_u16	62485
k_AASNodeAbsentDiag_Cnt_str.Threshold	3858
k_AASNodeAbsentDiag_Cnt_str.PStep	7794
k_AASNodeAbsentDiag_Cnt_str.NStep	10917
k_AASNodeAbsentTimeout_mS_u16	6705
k_AASNodeTimeout_mS_u16	19500
k_ABSNodeTimeout_mS_u16	8179
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	59456
k_ANGLEVOLANTSigValidThresh_Cnt_u16	22282
k_AngleVolantInvalidThresh_Cnt_u16	9597
k_AngleVolantValidThresh_Cnt_u16	48102
k_BSI552MsgTimeout_mS_u16	13722
k_BSINTCEnableTimeout_mS_u16	10465
k_BSINodeAbsentDiag_Cnt_str.Threshold	21852
k_BSINodeAbsentDiag_Cnt_str.PStep	36253
k_BSINodeAbsentDiag_Cnt_str.NStep	12658
k_BSINodeAbsentTimeout_mS_u16	15694
k_BSINodeTimeout_mS_u16	30846
k_BattOvHi_Volt_f32	17.0653
k_BattOvLo_Volt_f32	25.2497997
k_BattUvHi_Volt_f32	7.84070015
k_BattUvLo_Volt_f32	11.0794001
k_CAVNTCEnableTimeout_mS_u16	37844
k_CAVNodeAbsentDiag_Cnt_str.Threshold	21460
k_CAVNodeAbsentDiag_Cnt_str.PStep	9856
k_CAVNodeAbsentDiag_Cnt_str.NStep	26289
k_CAVNodeAbsentTimeout_mS_u16	17111
k_CAVNodeTimeout_mS_u16	27760
k_CMM388MsgTimeout_mS_u16	15597
k_CMM388NTCEnableTimeout_mS_u16	12313
k_CMMNTCEnableTimeout_mS_u16	5309
k_CMMNodeAbsentDiag_Cnt_str.Threshold	25606
k_CMMNodeAbsentDiag_Cnt_str.PStep	59931
k_CMMNodeAbsentDiag_Cnt_str.NStep	31904
k_CMMNodeAbsentTimeout_mS_u16	64147
k_CONSANGLECPKMax_HwDeg_f32	312.324707
k_CONSANGLECPKMin_HwDeg_f32	-187.400406
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	50000
k_CONSANGLECPKSigValidThresh_Cnt_u16	8295
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	31210
k_CPKVehicleSpeedValidThresh_Cnt_u16	51745
k_CityParkInputInvalidThresh_Cnt_u16	32961
k_CityParkInputValidThresh_Cnt_u16	19086
k_ComputerRazGCTSigValidThresh_Cnt_u16	51971
k_CptTemporelSigValidThresh_Cnt_u16	44005
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	37647
k_DMDFCTCPKSigValidThresh_Cnt_u16	4062
k_DMDFCTCPKValidCount_Cnt_u16	65146

Name	Input Value
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	45405
k_DMDRELAXECPKSigValidThresh_Cnt_u16	6628
k_DMDRelaxeConsistentThresh_Cnt_u16	10658
k_DateValidThresh_Cnt_u16	52759
k_DefaultVehSpd_Kph_f32	28.2000008
k_DiagMuxOnAbsentTimeout_mS_u16	29728
k_EMNodeTimeout_mS_u16	4397
k_ESPNTCEnableTimeout_mS_u16	65389
k_ESPNodeAbsentDiag_Cnt_str.Threshold	42337
k_ESPNodeAbsentDiag_Cnt_str.PStep	7895
k_ESPNodeAbsentDiag_Cnt_str.NStep	12276
k_ESPNodeAbsentTimeout_mS_u16	12091
k_EtatMTSigInvalidThresh_Cnt_u16	12630
k_EtatMTSigValidThresh_Cnt_u16	31549
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	5673
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	21700
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	63555
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	19982
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	61744
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	43030
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	61874
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	61948
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	26461
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	35942
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	5592
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	51507
k_ISDATDIRASentDiag_Cnt_str.Threshold	40933
k_ISDATDIRASentDiag_Cnt_str.PStep	35365
k_ISDATDIRASentDiag_Cnt_str.NStep	1104
k_ISDATDIRASentTimeout_mS_u16	9391
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	41044
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	8182
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	60649
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	28547
k_ISDYNAASChkSumValidThresh_Cnt_u16	61738
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	55842
k_ISDYNAASMsgCountValidThresh_Cnt_u16	58240
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	58199
k_ISDYNAASMsgLenValidThresh_Cnt_u16	4864
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	12722
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	10917
k_ISDYNABRChkSumValidThresh_Cnt_u16	19444
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	19410
k_ISDYNABRMsgCountValidThresh_Cnt_u16	37009
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	6837
k_ISDYNABRMsgLenValidThresh_Cnt_u16	59199
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	48196
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	17866
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	64055
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	9055
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	5895
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	51590
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	19774
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	49529
k_ISDYNVOLChkSumValidThresh_Cnt_u16	23180
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	48456
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	23550
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	50557
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	17336
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	35973
k_IgnOnTimeout_mS_u16	12709
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	19.3841
k_PowerCutVehSpdLowThresh_Kph_f32	3.79819989
k_PowerCutVehSpdLowTimeout_mS_u16	0
k_VBattMaxAAS_Volt_f32	6.54589987
k_VBattMaxBSI_Volt_f32	16.2964993
k_VBattMaxCAV_Volt_f32	23.6681995
k_VBattMaxCMM388_Volt_f32	19.1707001
k_VBattMaxCMM_Volt_f32	25.3169003
k_VBattMaxESP_Volt_f32	26.9272995
k_VBattMinAAS_Volt_f32	1.43330002
k_VBattMinBSI_Volt_f32	6.92729998

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinCAV_Volt_f32	28.3626003
k_VBattMinCMM388_Volt_f32	13.9190998
k_VBattMinCMM_Volt_f32	25.1562004
k_VBattMinESP_Volt_f32	22.3169003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	29078
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	33305
k_VitesseVehicleBVRampValidThresh_Cnt_u16	38568
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	23529
k_VitesseVehicleBVSigValidThresh_Cnt_u16	37275
k_VitesseVehicleBVSpeedPassThresh_kph_f32	44.1078987
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	5697
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	7863
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	345048320
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	157
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	34788
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	872866048
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	132
target_SrlComInput_Per1_Batt_Volt_f32.value	25.4136009
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	681325824
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	35
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.900653064
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2534057216
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3802219776
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2563237120
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	36
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	561939712
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3838125312
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1251722496
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3137496320
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	78
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	94
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	141
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	171
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	183
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3641935104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	30
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	243
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3783894272
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	103
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	446711040

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2118575360
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	23
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	115
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	131
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	151
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	177
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3680351488
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1126
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.761739194
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	952093
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	215.433197
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	54200

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	872866048	872866048	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	872866048	872866048	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	8184	8184	✔
AngleVolantMsgTimer_mS_M_u32	872866048	872866048	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	872866048	872866048	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	872866048	872866048	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	872866048	872866048	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	872866048	872866048	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21852	21852	✔
BSINodeAbsentTimer_mS_M_u32	872866048	872866048	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	872866048	872866048	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	872866048	872866048	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	872866048	872866048	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	872866048	872866048	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	18197	18197	✔
CMMNodeAbsentTimer_mS_M_u32	1251722496	1251722496	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	28850	28850	✔
CONSANGLECPK_HwDeg_M_f32	-705.895691	-705.895691 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	28850	28850	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3258160384	3258160384	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	45459	45459	✔
CityParkInputConsistentCount_Cnt_M_u16	19086	19086	✔
CityParkInputInvalidCount_Cnt_M_u16	48102	48102	✔
CityParkInputMsgTimer_mS_M_u32	872866048	872866048	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	872866048	872866048	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ComputerRazGCTSigInvalidTimer_mS_M_u32	872866048	872866048	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	872866048	872866048	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	872866048	872866048	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	872866048	872866048	✔
ESPNTCEnableTimer_mS_M_u32	872866048	872866048	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	42337	42337	✔
ESPNodeAbsentTimer_mS_M_u32	872866048	872866048	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1111	1111	✔
EffacDefaultDiagTimer_mS_M_u32[1]	872866048	872866048	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	872866048	872866048	✔
ElecIntTimer_mS_M_u32[1]	98	98	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	872866048	872866048	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	872866048	872866048	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	872866048	872866048	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	872866048	872866048	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	872866048	872866048	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	872866048	872866048	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	872866048	872866048	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	872866048	872866048	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	872866048	872866048	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	872866048	872866048	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	872866048	872866048	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	872866048	872866048	✔
IgnOnTimer_mS_M_u32	3434652928	3434652928	✔
IgnTimeOff_Sec_M_u32	1795682971	1795682971	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	192	192	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2534057216	2534057216	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	222	222	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3802219776	3802219776	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	49	49	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2563237120	2563237120	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	36	36	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	561939712	561939712	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1851319552	1851319552	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	132	132	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1251722496	1251722496	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	194	194	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3137496320	3137496320	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	209	209	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3641935104	3641935104	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	60	60	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3783894272	3783894272	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	103	103	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	446711040	446711040	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	136	136	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2118575360	2118575360	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3680351488	3680351488	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	289.280914	289.280914	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	619.000671	619.000671	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	461.173798	461.173798	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	28850	28850	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1795682971	1795682971	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-705.895691	-705.895691 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	28.2000008	28.2000008	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.49 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	805372928
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	35947
AASNodeAbsentTimer_mS_M_u32	273642496
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	34844
ANGLEVOLANTSigValidCount_Cnt_M_u16	51039
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	33360
AngleVolantMsgTimer_mS_M_u32	805372928
AngleVolantValidCount_Cnt_M_u16	18818
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1466774528
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	4232033280
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3603473408
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2475516928
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	54715
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1647649792
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	30959
CAVNodeAbsentTimer_mS_M_u32	2521502720
CDD_SrlComVehSpd_Kph_G_f32	395.526398
CMM388NTCEnableTimer_mS_M_u32	3071890432
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	135336960
CMMNTCsEnabled_Cnt_M_lgc	0

Name	Input Value
CMMNodeAbsentFltAcc_Cnt_M_u16	10067
CMMNodeAbsentTimer_mS_M_u32	206005248
CONSANGLECPKSigInvalidCount_Cnt_M_u16	63589
CONSANGLECPKSigValidCount_Cnt_M_u16	3961
CONSANGLECPK_Cnt_M_u16	43996
CONSANGLECPK_HwDeg_M_f32	134.584793
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43996
CPKVehicleSpeedMsgTimer_mS_M_u32	1905787904
CPKVehicleSpeedValidCount_Cnt_M_u16	31745
CityParkInputConsistentCount_Cnt_M_u16	44294
CityParkInputInvalidCount_Cnt_M_u16	2557
CityParkInputMsgTimer_mS_M_u32	2534057216
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1423143936
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	62959
ComputerRazGCTSigInvalidTimer_mS_M_u32	3894383616
ComputerRazGCTSigValidCount_Cnt_M_u16	1123
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	57977
DMDFCTCPKSigValidCount_Cnt_M_u16	63077
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	10462
DMDRELAXECPKSigValidCount_Cnt_M_u16	54689
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	36682
DateInvalidTimer_mS_M_u32	4232033280
DiagMuxOnAbsentTimer_mS_M_u32	2961753088
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2475516928
ESPNTCEnableTimer_mS_M_u32	3967316992
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	18547
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	65535
EffacDefaultDiagTimer_mS_M_u32[1]	95535
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	66
ElecIntTimer_mS_M_u32[1]	78
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	743908352
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	5758
EtatMTSigValidCount_Cnt_M_u16	32142
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24359
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	25531
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	45611
ISDAT4V2BSI552MsgTimer_mS_M_u32	1808491520
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	31426
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	52826
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	32142
ISDATBSI3F2MsgTimer_mS_M_u32	566674432
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	50987
ISDATBSI412MsgLenValidCount_Cnt_M_u16	50291
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	5758
ISDATBSI412MsgTimer_mS_M_u32	390005760
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	57815
ISDATBSI432MsgLenValidCount_Cnt_M_u16	40439
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	16696
ISDATDIRASentFltAcc_Cnt_M_u16	52556
ISDATDIRASentTimer_mS_M_u32	1905787904
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	12186
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	18818
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	50584
ISDYN2CMMMsgTimer_mS_M_u32	2779935744
ISDYNAASChkSumInvalidCount_Cnt_M_u16	6445
ISDYNAASChkSumValidCount_Cnt_M_u16	2705
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	41633
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	37778
ISDYNAASMsgLenValidCount_Cnt_M_u16	29998

Name	Input Value
ISDYNAASMsgTimeValidCount_Cnt_M_u16	6445
ISDYNAASMsgTimer_mS_M_u32	1553290240
ISDYNABRChkSumInvalidCount_Cnt_M_u16	17960
ISDYNABRChkSumValidCount_Cnt_M_u16	47092
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	51404
ISDYNABRMsgCountValidCount_Cnt_M_u16	33648
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	58116
ISDYNABRMsgLenValidCount_Cnt_M_u16	856
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43996
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	612
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1109
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	32142
ISDYNCMM208MsgTimer_mS_M_u32	2634691584
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2299
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1215
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	4032
ISDYNCMM388MsgTimer_mS_M_u32	1204081664
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	57763
ISDYNVOLChkSumValidCount_Cnt_M_u16	2871
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	18103
ISDYNVOLMsgCountValidCount_Cnt_M_u16	44323
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	49108
ISDYNVOLMsgLenValidCount_Cnt_M_u16	33992
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	10067
ISDYNVOLMsgTimer_mS_M_u32	429626368
IgnOnTimer_mS_M_u32	2051593216
IgnTimeOff_Sec_M_u32	1763311265
ManVehSpd_Kph_M_f32	65.6983032
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	182
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	166
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3396125696
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	182
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1413981184
PrevISDATBSI412MsgDLCError_Cnt_M_u08	154
PrevISDATBSI412MsgRxTime_MSec_M_u32	861148160
PrevISDATBSI432MsgDLCError_Cnt_M_u08	208
PrevISDATBSI432MsgRxTime_MSec_M_u32	2850845696
PrevISDATDIRAMsgTxTime_MSec_M_u32	1718096896
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	135
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1111417856
PrevISDYNAASMsgDLCError_Cnt_M_u08	40
PrevISDYNAASMsgRxTime_MSec_M_u32	626627584
PrevISDYNABRMsgDLCError_Cnt_M_u08	33
PrevISDYNABRMsgRxTime_MSec_M_u32	1346425856
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	15
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1417057280
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	84
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2337240064
PrevISDYNVOLMsgDLCError_Cnt_M_u08	114
PrevISDYNVOLMsgRxTime_MSec_M_u32	3054048256
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2306671616
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	202.423004
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	28112
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	8684

Name	Input Value
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	30385
VitesseVehicleBVRampValidCount_Cnt_M_u16	49549
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	20093
VitesseVehicleBVSigValidCount_Cnt_M_u16	17536
VitesseVehicleBV_Kph_M_f32	431.081909
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	4032
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	44860
VitesseVehiculeRoues_Kph_M_f32	482.812897
k_AASNTCEnableTimeout_mS_u16	28083
k_AASNodeAbsentDiag_Cnt_str.Threshold	15068
k_AASNodeAbsentDiag_Cnt_str.PStep	35763
k_AASNodeAbsentDiag_Cnt_str.NStep	50769
k_AASNodeAbsentTimeout_mS_u16	35357
k_AASNodeTimeout_mS_u16	7404
k_ABSNodeTimeout_mS_u16	20950
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	42418
k_ANGLEVOLANTSigValidThresh_Cnt_u16	8210
k_AngleVolantInvalidThresh_Cnt_u16	16569
k_AngleVolantValidThresh_Cnt_u16	2557
k_BSI552MsgTimeout_mS_u16	63139
k_BSINTCEnableTimeout_mS_u16	42959
k_BSINodeAbsentDiag_Cnt_str.Threshold	21892
k_BSINodeAbsentDiag_Cnt_str.PStep	36236
k_BSINodeAbsentDiag_Cnt_str.NStep	12681
k_BSINodeAbsentTimeout_mS_u16	35400
k_BSINodeTimeout_mS_u16	16696
k_BattOvHi_Volt_f32	15.6381998
k_BattOvLo_Volt_f32	25.0764999
k_BattUvHi_Volt_f32	15.1920004
k_BattUvLo_Volt_f32	26.6455002
k_CAVNTCEnableTimeout_mS_u16	47667
k_CAVNodeAbsentDiag_Cnt_str.Threshold	13613
k_CAVNodeAbsentDiag_Cnt_str.PStep	61281
k_CAVNodeAbsentDiag_Cnt_str.NStep	59207
k_CAVNodeAbsentTimeout_mS_u16	34349
k_CAVNodeTimeout_mS_u16	21985
k_CMM388MsgTimeout_mS_u16	51051
k_CMM388NTCEnableTimeout_mS_u16	40423
k_CMMNTCEnableTimeout_mS_u16	64698
k_CMMNodeAbsentDiag_Cnt_str.Threshold	50143
k_CMMNodeAbsentDiag_Cnt_str.PStep	53657
k_CMMNodeAbsentDiag_Cnt_str.NStep	37440
k_CMMNodeAbsentTimeout_mS_u16	52152
k_CONSANGLECPKMax_HwDeg_f32	656.138611
k_CONSANGLECPKMin_HwDeg_f32	-114.2808
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	51904
k_CONSANGLECPKSigValidThresh_Cnt_u16	43580
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	2994
k_CPKVehicleSpeedValidThresh_Cnt_u16	48526
k_CityParkInputInvalidThresh_Cnt_u16	17774
k_CityParkInputValidThresh_Cnt_u16	44294
k_ComputerRazGCTSigValidThresh_Cnt_u16	29160
k_CptTemporelSigValidThresh_Cnt_u16	62976
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	7684
k_DMDFCTCPKSigValidThresh_Cnt_u16	32344
k_DMDFCTCPKValidCount_Cnt_u16	39107
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	50584
k_DMDRELAXECPKSigValidThresh_Cnt_u16	17092
k_DMDRelaxeConsistentThresh_Cnt_u16	35722
k_DateValidThresh_Cnt_u16	45611
k_DefaultVehSpd_Kph_f32	106.098198
k_DiagMuxOnAbsentTimeout_mS_u16	55698
k_EMNodeTimeout_mS_u16	39850
k_ESPNTCEnableTimeout_mS_u16	10347
k_ESPNodeAbsentDiag_Cnt_str.Threshold	39214
k_ESPNodeAbsentDiag_Cnt_str.PStep	57797

Name	Input Value
k_ESPNodeAbsentDiag_Cnt_str.NStep	37798
k_ESPNodeAbsentTimeout_mS_u16	52672
k_EtatMTSigInvalidThresh_Cnt_u16	51119
k_EtatMTSigValidThresh_Cnt_u16	8379
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	62197
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	15845
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	47079
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	54471
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	4639
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	14255
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	53596
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	38716
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	56411
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	10432
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	62248
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	55639
k_ISDATDIRASentDiag_Cnt_str.Threshold	8056
k_ISDATDIRASentDiag_Cnt_str.PStep	40691
k_ISDATDIRASentDiag_Cnt_str.NStep	38120
k_ISDATDIRASentTimeout_mS_u16	37284
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	6132
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	33360
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	20471
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	296
k_ISDYNAASChkSumValidThresh_Cnt_u16	45812
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	972
k_ISDYNAASMsgCountValidThresh_Cnt_u16	65136
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	62892
k_ISDYNAASMsgLenValidThresh_Cnt_u16	6256
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	12314
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	12098
k_ISDYNABRChkSumValidThresh_Cnt_u16	41494
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	4283
k_ISDYNABRMsgCountValidThresh_Cnt_u16	55614
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	8787
k_ISDYNABRMsgLenValidThresh_Cnt_u16	33651
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	57893
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	2388
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	1356
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	9043
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	49948
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	16991
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	46581
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	14214
k_ISDYNVOLChkSumValidThresh_Cnt_u16	21262
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	25944
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	49784
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	37626
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	40714
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	44769
k_IgnOnTimeout_mS_u16	38658
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	169.046005
k_PowerCutVehSpdLowThresh_Kph_f32	255
k_PowerCutVehSpdLowTimeout_mS_u16	65535
k_VBattMaxAAS_Volt_f32	3.13989997
k_VBattMaxBSI_Volt_f32	20.1713009
k_VBattMaxCAV_Volt_f32	0.725000024
k_VBattMaxCMM388_Volt_f32	17.3759003
k_VBattMaxCMM_Volt_f32	11.6433001
k_VBattMaxESP_Volt_f32	5.51429987
k_VBattMinAAS_Volt_f32	17.2852993
k_VBattMinBSI_Volt_f32	5.51429987
k_VBattMinCAV_Volt_f32	28.7621002
k_VBattMinCMM388_Volt_f32	21.6257
k_VBattMinCMM_Volt_f32	26.6830006
k_VBattMinESP_Volt_f32	11.6433001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	11310
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	41318
k_VitesseVehicleBVRampValidThresh_Cnt_u16	439
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	34359
k_VitesseVehicleBVSigValidThresh_Cnt_u16	19423
k_VitesseVehicleBVSpeedPassThresh_kph_f32	530.934204

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	13295
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	37195
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4232033280
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	24
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52348
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1481515008
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	84
target_SrlComInput_Per1_Batt_Volt_f32.value	15.4715996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	685646848
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	81
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.45125863
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3813856256
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	87
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	588182528
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1662718976
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1802974208
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	69424128
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	237
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4112479232
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	107713536
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	45
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	55
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	213
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3635950592
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	54
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	81
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	177
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	215
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	240
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3218461696
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	923923456
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1855853568
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	43
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	82
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	109
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	253

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4137264128
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3785
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.093459852
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	163948
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	3.1487
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	38794

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1481515008	1481515008	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	107713536	107713536	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	33360	33360	✔
AngleVolantMsgTimer_mS_M_u32	1481515008	1481515008	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1466774528	1466774528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	4232033280	4232033280	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	1481515008	1481515008	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2475516928	2475516928	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	42034	42034	✔
BSINodeAbsentTimer_mS_M_u32	1802974208	1802974208	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1481515008	1481515008	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1855853568	1855853568	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1481515008	1481515008	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1481515008	1481515008	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4112479232	4112479232	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	43996	43996	✔
CONSANGLECPK_HwDeg_M_f32	134.584793	134.584793 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43996	43996	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1905787904	1905787904	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	31745	31745	✔
CityParkInputConsistentCount_Cnt_M_u16	44294	44294	✔
CityParkInputInvalidCount_Cnt_M_u16	2559	2559	✔
CityParkInputMsgTimer_mS_M_u32	1481515008	1481515008	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1423143936	1423143936	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3894383616	3894383616	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DateInvalidTimer_mS_M_u32	1481515008	1481515008	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1481515008	1481515008	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1481515008	1481515008	✔
ESPNTCEnableTimer_mS_M_u32	1481515008	1481515008	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1481515008	1481515008	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	65535	65535	✔
EffacDefaultDiagTimer_mS_M_u32[1]	95535	95535	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	66	66	✔
ElecIntTimer_mS_M_u32[1]	78	78	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1481515008	1481515008	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24360	24360	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3813856256	3813856256	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	31427	31427	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	588182528	588182528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	50988	50988	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1662718976	1662718976	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1481515008	1481515008	✔
ISDATDIRASentFltAcc_Cnt_M_u16	14436	14436	✔
ISDATDIRASentTimer_mS_M_u32	1481515008	1481515008	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1481515008	1481515008	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1481515008	1481515008	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1481515008	1481515008	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1481515008	1481515008	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1481515008	1481515008	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1481515008	1481515008	✔
IgnOnTimer_mS_M_u32	2051593216	2051593216	✔
IgnTimeOff_Sec_M_u32	1763311265	1763311265	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	173	173	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3813856256	3813856256	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	87	87	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	588182528	588182528	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	158	158	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1662718976	1662718976	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	73	73	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1802974208	1802974208	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	69424128	69424128	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	237	237	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4112479232	4112479232	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	117	117	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	107713536	107713536	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	213	213	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3635950592	3635950592	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	245	245	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3218461696	3218461696	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	119	119	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	923923456	923923456	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	86	86	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1855853568	1855853568	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4137264128	4137264128	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	202.423004	202.423004	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	431.081909	431.081909	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	482.812897	482.812897	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	43996	43996	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1763311265	1763311265	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	134.584793	134.584793 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	106.098198	106.098198	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.50 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1823192832
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	8556
AASNodeAbsentTimer_mS_M_u32	1367369472
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	36954
ANGLEVOLANTSigValidCount_Cnt_M_u16	3662
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	5053
AngleVolantMsgTimer_mS_M_u32	1823192832
AngleVolantValidCount_Cnt_M_u16	44710
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	589768448
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2662311680
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2664748800
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1803982592
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	58237
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1318016768
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	29281
CAVNodeAbsentTimer_mS_M_u32	3054339840
CDD_SrlComVehSpd_Kph_G_f32	461.789795
CMM388NTCEnableTimer_mS_M_u32	1554171648
CMM388NTCsEnabled_Cnt_M_lgc	0

Name	Input Value
CMMNTCEnableTimer_mS_M_u32	4173039360
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	29684
CMMNodeAbsentTimer_mS_M_u32	1767413504
CONSANGLECPKSigInvalidCount_Cnt_M_u16	38525
CONSANGLECPKSigValidCount_Cnt_M_u16	52481
CONSANGLECPK_Cnt_M_u16	17368
CONSANGLECPK_HwDeg_M_f32	-292.407196
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17368
CPKVehicleSpeedMsgTimer_mS_M_u32	3286677248
CPKVehicleSpeedValidCount_Cnt_M_u16	15122
CityParkInputConsistentCount_Cnt_M_u16	37914
CityParkInputInvalidCount_Cnt_M_u16	27189
CityParkInputMsgTimer_mS_M_u32	3813856256
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2482267904
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	62688
ComputerRazGCTSigInvalidTimer_mS_M_u32	2995783424
ComputerRazGCTSigValidCount_Cnt_M_u16	16899
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	53441
DMDFCTCPKSigValidCount_Cnt_M_u16	28861
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	13844
DMDRELAXECPKSigValidCount_Cnt_M_u16	27528
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	42446
DateInvalidTimer_mS_M_u32	2662311680
DiagMuxOnAbsentTimer_mS_M_u32	3121903360
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1803982592
ESPNTCEnableTimer_mS_M_u32	2701485824
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	48212
EffacDefaultDiagCount_Cnt_M_u08	2
EffacDefaultDiagTimer_mS_M_u32[0]	579
EffacDefaultDiagTimer_mS_M_u32[1]	989
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	101
ElecIntTimer_mS_M_u32[1]	105
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	4163458816
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	25459
EtatMTSigValidCount_Cnt_M_u16	39427
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	59959
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	22587
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	54635
ISDAT4V2BSI552MsgTimer_mS_M_u32	1523357440
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	16421
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	53534
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	39427
ISDATBSI3F2MsgTimer_mS_M_u32	3730470656
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	19437
ISDATBSI412MsgLenValidCount_Cnt_M_u16	40917
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	25459
ISDATBSI412MsgTimer_mS_M_u32	787592960
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	21608
ISDATBSI432MsgLenValidCount_Cnt_M_u16	52168
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	32134
ISDATDIRASentFltAcc_Cnt_M_u16	10570
ISDATDIRASentTimer_mS_M_u32	3286677248
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	12446
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	44710
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	25444
ISDYN2CMMMsgTimer_mS_M_u32	3713492736
ISDYNAASChkSumInvalidCount_Cnt_M_u16	806
ISDYNAASChkSumValidCount_Cnt_M_u16	60090
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	57161
ISDYNAASMsgCount_Cnt_M_u08	5

Name	Input Value
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	28280
ISDYNAASMsgLenValidCount_Cnt_M_u16	25956
ISDYNAASMsgTimeValidCount_Cnt_M_u16	806
ISDYNAASMsgTimer_mS_M_u32	1546569472
ISDYNABRChkSumInvalidCount_Cnt_M_u16	32693
ISDYNABRChkSumValidCount_Cnt_M_u16	34321
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	12361
ISDYNABRMsgCountValidCount_Cnt_M_u16	48157
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	4768
ISDYNABRMsgLenValidCount_Cnt_M_u16	11620
ISDYNABRMsgTimeValidCount_Cnt_M_u16	17368
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	613
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1111
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	39427
ISDYNCMM208MsgTimer_mS_M_u32	105916160
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2303
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1217
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	54252
ISDYNCMM388MsgTimer_mS_M_u32	3097511680
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	21187
ISDYNVOLChkSumValidCount_Cnt_M_u16	20935
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	7175
ISDYNVOLMsgCountValidCount_Cnt_M_u16	50307
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	6705
ISDYNVOLMsgLenValidCount_Cnt_M_u16	50966
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	29684
ISDYNVOLMsgTimer_mS_M_u32	236717824
IgnOnTimer_mS_M_u32	823412480
IgnTimeOff_Sec_M_u32	2737388570
ManVehSpd_Kph_M_f32	604.569824
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	184
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	117
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4234704640
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	72
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3797407488
PrevISDATBSI412MsgDLCError_Cnt_M_u08	38
PrevISDATBSI412MsgRxTime_MSec_M_u32	1123190528
PrevISDATBSI432MsgDLCError_Cnt_M_u08	77
PrevISDATBSI432MsgRxTime_MSec_M_u32	950626048
PrevISDATDIRAMsgTxTime_MSec_M_u32	4189488896
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	129
PrevISDYN2CMMMsgRxTime_MSec_M_u32	91363072
PrevISDYNAASMsgDLCError_Cnt_M_u08	38
PrevISDYNAASMsgRxTime_MSec_M_u32	1658980096
PrevISDYNABRMsgDLCError_Cnt_M_u08	163
PrevISDYNABRMsgRxTime_MSec_M_u32	2402043648
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	120
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2307589888
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	156
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3766511360
PrevISDYNVOLMsgDLCError_Cnt_M_u08	73
PrevISDYNVOLMsgRxTime_MSec_M_u32	3469969152
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1345828608
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	287.33429
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0

Name	Input Value
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	22462
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	55082
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	283
VitesseVehicleBVRampValidCount_Cnt_M_u16	48199
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	311
VitesseVehicleBVSigValidCount_Cnt_M_u16	23275
VitesseVehicleBV_Kph_M_f32	542.282471
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	54252
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	4409
VitesseVehiculeRoues_Kph_M_f32	339.658691
k_AASNTCEnableTimeout_mS_u16	6739
k_AASNodeAbsentDiag_Cnt_str.Threshold	55416
k_AASNodeAbsentDiag_Cnt_str.PStep	18700
k_AASNodeAbsentDiag_Cnt_str.NStep	23435
k_AASNodeAbsentTimeout_mS_u16	6357
k_AASNodeTimeout_mS_u16	58922
k_ABSNodeTimeout_mS_u16	13994
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	13527
k_ANGLEVOLANTSigValidThresh_Cnt_u16	29047
k_AngleVolantInvalidThresh_Cnt_u16	27522
k_AngleVolantValidThresh_Cnt_u16	27189
k_BSI552MsgTimeout_mS_u16	38660
k_BSINTCEnableTimeout_mS_u16	57984
k_BSINodeAbsentDiag_Cnt_str.Threshold	21932
k_BSINodeAbsentDiag_Cnt_str.PStep	36219
k_BSINodeAbsentDiag_Cnt_str.NStep	12704
k_BSINodeAbsentTimeout_mS_u16	56277
k_BSINodeTimeout_mS_u16	32134
k_BattOvHi_Volt_f32	20.8698006
k_BattOvLo_Volt_f32	20.5799007
k_BattUvHi_Volt_f32	9.06890011
k_BattUvLo_Volt_f32	8.70009995
k_CAVNTCEnableTimeout_mS_u16	45459
k_CAVNodeAbsentDiag_Cnt_str.Threshold	61373
k_CAVNodeAbsentDiag_Cnt_str.PStep	2683
k_CAVNodeAbsentDiag_Cnt_str.NStep	55649
k_CAVNodeAbsentTimeout_mS_u16	49831
k_CAVNodeTimeout_mS_u16	28169
k_CMM388MsgTimeout_mS_u16	28780
k_CMM388NTCEnableTimeout_mS_u16	56568
k_CMMNTCEnableTimeout_mS_u16	39485
k_CMMNodeAbsentDiag_Cnt_str.Threshold	9681
k_CMMNodeAbsentDiag_Cnt_str.PStep	64698
k_CMMNodeAbsentDiag_Cnt_str.NStep	12829
k_CMMNodeAbsentTimeout_mS_u16	43973
k_CONSANGLECPKMax_HwDeg_f32	480.393402
k_CONSANGLECPKMin_HwDeg_f32	-536.56427
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	41708
k_CONSANGLECPKSigValidThresh_Cnt_u16	8249
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	45528
k_CPKVehicleSpeedValidThresh_Cnt_u16	46276
k_CityParkInputInvalidThresh_Cnt_u16	6627
k_CityParkInputValidThresh_Cnt_u16	37914
k_ComputerRazGCTSigValidThresh_Cnt_u16	29363
k_CptTemporelSigValidThresh_Cnt_u16	29228
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	24992
k_DMDFCTCPKSigValidThresh_Cnt_u16	48228
k_DMDFCTCPKValidCount_Cnt_u16	47717
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	25444
k_DMDRELAXECPKSigValidThresh_Cnt_u16	51104
k_DMDRelaxeConsistentThresh_Cnt_u16	34126
k_DateValidThresh_Cnt_u16	54635
k_DefaultVehSpd_Kph_f32	198.888
k_DiagMuxOnAbsentTimeout_mS_u16	4790
k_EMNodeTimeout_mS_u16	174
k_ESPNTCEnableTimeout_mS_u16	21485

Name	Input Value
k_ESPNodeAbsentDiag_Cnt_str.Threshold	22978
k_ESPNodeAbsentDiag_Cnt_str.PStep	16663
k_ESPNodeAbsentDiag_Cnt_str.NStep	23499
k_ESPNodeAbsentTimeout_mS_u16	50605
k_EtatMTSigInvalidThresh_Cnt_u16	55072
k_EtatMTSigValidThresh_Cnt_u16	10172
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	51215
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	54015
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	14199
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	34326
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	22991
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	2657
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	55769
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	13305
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	29916
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	23852
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	51636
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	5736
k_ISDATDIRASentDiag_Cnt_str.Threshold	50524
k_ISDATDIRASentDiag_Cnt_str.PStep	27716
k_ISDATDIRASentDiag_Cnt_str.NStep	15614
k_ISDATDIRASentTimeout_mS_u16	36161
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	3729
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	5053
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	3401
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	20149
k_ISDYNAASChkSumValidThresh_Cnt_u16	38161
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	32585
k_ISDYNAASMsgCountValidThresh_Cnt_u16	19229
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	33065
k_ISDYNAASMsgLenValidThresh_Cnt_u16	926
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	24927
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	42470
k_ISDYNABRChkSumValidThresh_Cnt_u16	51498
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	12925
k_ISDYNABRMsgCountValidThresh_Cnt_u16	5297
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	33524
k_ISDYNABRMsgLenValidThresh_Cnt_u16	2900
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	22012
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	38194
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	21898
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	12021
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	57178
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	40270
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	17997
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	9948
k_ISDYNVOLChkSumValidThresh_Cnt_u16	8196
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	14757
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	30341
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	56831
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	9615
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	14153
k_IgnOnTimeout_mS_u16	63592
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	156.5448
k_PowerCutVehSpdLowThresh_Kph_f32	32.2713013
k_PowerCutVehSpdLowTimeout_mS_u16	6780
k_VBattMaxAAS_Volt_f32	29.6625004
k_VBattMaxBSI_Volt_f32	27.7187004
k_VBattMaxCAV_Volt_f32	22.0506992
k_VBattMaxCMM388_Volt_f32	28.6233997
k_VBattMaxCMM_Volt_f32	1.70299995
k_VBattMaxESP_Volt_f32	29.9836006
k_VBattMinAAS_Volt_f32	23.8034
k_VBattMinBSI_Volt_f32	2.9835999
k_VBattMinCAV_Volt_f32	9.57909966
k_VBattMinCMM388_Volt_f32	17.3885002
k_VBattMinCMM_Volt_f32	17.9111004
k_VBattMinESP_Volt_f32	1.70299995
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	14819
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	58875
k_VitesseVehicleBVRampValidThresh_Cnt_u16	60167
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	57543

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VitesseVehicleBVSigValidThresh_Cnt_u16	23439
k_VitesseVehicleBVSpeedPassThresh_kph_f32	522.823975
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	16737
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	50445
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2662311680
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	202
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	58160
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	456418048
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	156
target_SrlComInput_Per1_Batt_Volt_f32.value	6.6079998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3734263552
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	25
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.36471352
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2650162944
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	101
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2000807680
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	201
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2409465600
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2399741696
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	495240960
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3809502976
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2276198144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	58
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	104
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	196
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	201
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2336630528
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	45
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	47
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	160
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3563931392
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	121169664
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	957646592
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	164
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	165

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	189
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3277969152
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3690
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.946470618
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	637473
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	155.486404
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	17040

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	456418048	456418048	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	55416	55416	✔
AASNodeAbsentTimer_mS_M_u32	456418048	456418048	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	456418048	456418048	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	589768448	589768448	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	2662311680	2662311680	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	2664748800	2664748800	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	1803982592	1803982592	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21932	21932	✔
BSINodeAbsentTimer_mS_M_u32	456418048	456418048	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	456418048	456418048	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	456418048	456418048	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	456418048	456418048	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	456418048	456418048	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	9681	9681	✔
CMMNodeAbsentTimer_mS_M_u32	456418048	456418048	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	17368	17368	✔
CONSANGLECPK_HwDeg_M_f32	-292.407196	-292.407196 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	456418048	456418048	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	456418048	456418048	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	456418048	456418048	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	456418048	456418048	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	456418048	456418048	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	456418048	456418048	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	456418048	456418048	✔
ESPNTCEnableTimer_mS_M_u32	456418048	456418048	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	456418048	456418048	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	579	579	✔
EffacDefaultDiagTimer_mS_M_u32[1]	989	989	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	456418048	456418048	✔
ElecIntTimer_mS_M_u32[1]	105	105	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	456418048	456418048	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2650162944	2650162944	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2000807680	2000807680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2409465600	2409465600	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2399741696	2399741696	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	456418048	456418048	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	456418048	456418048	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	456418048	456418048	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	456418048	456418048	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	456418048	456418048	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	456418048	456418048	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	456418048	456418048	✔
IgnOnTimer_mS_M_u32	823412480	823412480	✔
IgnTimeOff_Sec_M_u32	2737388570	2737388570	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	108	108	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2650162944	2650162944	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	101	101	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2000807680	2000807680	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	201	201	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2409465600	2409465600	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	63	63	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2399741696	2399741696	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4189488896	4189488896	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3809502976	3809502976	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	166	166	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2276198144	2276198144	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	223	223	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2336630528	2336630528	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3563931392	3563931392	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	208	208	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	121169664	121169664	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	957646592	957646592	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3277969152	3277969152	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	287.33429	287.33429	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	542.282471	542.282471	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	339.658691	339.658691	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	17368	17368	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2737388570	2737388570	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-292.407196	-292.407196 ± 0.0125	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	198.888	198.888	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.51 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1101376256
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	6798
AASNodeAbsentTimer_mS_M_u32	4025572096
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	15364
ANGLEVOLANTSigValidCount_Cnt_M_u16	46407
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	5679
AngleVolantMsgTimer_mS_M_u32	1101376256
AngleVolantValidCount_Cnt_M_u16	31770
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2712935168
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3756301056
BSI412NTCsEnabled_Cnt_M_lgc	1

Name	Input Value
BSI432NTCEnableTimer_mS_M_u32	3668495104
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1793493760
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	31255
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1017858816
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	12829
CAVNodeAbsentTimer_mS_M_u32	3130555136
CDD_SrlComVehSpd_Kph_G_f32	507.167114
CMM388NTCEnableTimer_mS_M_u32	3553737472
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	866548480
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	54467
CMMNodeAbsentTimer_mS_M_u32	1515752192
CONSANGLECPKSigInvalidCount_Cnt_M_u16	18691
CONSANGLECPKSigValidCount_Cnt_M_u16	10198
CONSANGLECPK_Cnt_M_u16	61917
CONSANGLECPK_HwDeg_M_f32	-673.916687
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	61917
CPKVehicleSpeedMsgTimer_mS_M_u32	1263577856
CPKVehicleSpeedValidCount_Cnt_M_u16	39865
CityParkInputConsistentCount_Cnt_M_u16	21966
CityParkInputInvalidCount_Cnt_M_u16	2077
CityParkInputMsgTimer_mS_M_u32	1351997440
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	916806400
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	16962
ComputerRazGCTSigInvalidTimer_mS_M_u32	3890412288
ComputerRazGCTSigValidCount_Cnt_M_u16	11399
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	14953
DMDFCTCPKSigValidCount_Cnt_M_u16	63540
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	52190
DMDRELAXECPKSigValidCount_Cnt_M_u16	21665
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	29092
DateInvalidTimer_mS_M_u32	3756301056
DiagMuxOnAbsentTimer_mS_M_u32	3150605056
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1793493760
ESPNTCEnableTimer_mS_M_u32	2835766016
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	6706
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	6
EffacDefaultDiagTimer_mS_M_u32[1]	16
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	1100
ElecIntTimer_mS_M_u32[1]	1151
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	107301632
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	53173
EtatMTSigValidCount_Cnt_M_u16	29269
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	59101
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	21808
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	13122
ISDAT4V2BSI552MsgTimer_mS_M_u32	822016
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	43598
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	26582
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	29269
ISDATBSI3F2MsgTimer_mS_M_u32	368077568
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	26714
ISDATBSI412MsgLenValidCount_Cnt_M_u16	54225
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	53173
ISDATBSI412MsgTimer_mS_M_u32	2580261632

Name	Input Value
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	6519
ISDATBSI432MsgLenValidCount_Cnt_M_u16	15846
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	18642
ISDATDIRASentFltAcc_Cnt_M_u16	57814
ISDATDIRASentTimer_mS_M_u32	1263577856
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	48259
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	31770
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36860
ISDYN2CMMMsgTimer_mS_M_u32	1593334528
ISDYNAASChkSumInvalidCount_Cnt_M_u16	42600
ISDYNAASChkSumValidCount_Cnt_M_u16	35659
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	53165
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	9572
ISDYNAASMsgLenValidCount_Cnt_M_u16	25887
ISDYNAASMsgTimeValidCount_Cnt_M_u16	42600
ISDYNAASMsgTimer_mS_M_u32	1864219392
ISDYNABRChkSumInvalidCount_Cnt_M_u16	32197
ISDYNABRChkSumValidCount_Cnt_M_u16	40944
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	56955
ISDYNABRMsgCountValidCount_Cnt_M_u16	48030
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	32790
ISDYNABRMsgLenValidCount_Cnt_M_u16	38697
ISDYNABRMsgTimeValidCount_Cnt_M_u16	61917
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	617
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1119
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	29269
ISDYNCMM208MsgTimer_mS_M_u32	1370299136
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2319
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1225
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	10048
ISDYNCMM388MsgTimer_mS_M_u32	2802268928
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	47913
ISDYNVOLChkSumValidCount_Cnt_M_u16	2684
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	60303
ISDYNVOLMsgCountValidCount_Cnt_M_u16	23002
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	56607
ISDYNVOLMsgLenValidCount_Cnt_M_u16	12371
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	54467
ISDYNVOLMsgTimer_mS_M_u32	2670656256
IgnOnTimer_mS_M_u32	62601984
IgnTimeOff_Sec_M_u32	776031488
ManVehSpd_Kph_M_f32	276.179108
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	192
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	179
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4166937344
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	0
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	656132864
PrevISDATBSI412MsgDLCError_Cnt_M_u08	254
PrevISDATBSI412MsgRxTime_MSec_M_u32	3742202624
PrevISDATBSI432MsgDLCError_Cnt_M_u08	21
PrevISDATBSI432MsgRxTime_MSec_M_u32	3823786752
PrevISDATDIRAMsgTxTime_MSec_M_u32	4078009088
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	180
PrevISDYN2CMMMsgRxTime_MSec_M_u32	912919296
PrevISDYNAASMsgDLCError_Cnt_M_u08	83
PrevISDYNAASMsgRxTime_MSec_M_u32	1372912384
PrevISDYNABRMsgDLCError_Cnt_M_u08	207
PrevISDYNABRMsgRxTime_MSec_M_u32	1230191360
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	162
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1565391616
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	102
PrevISDYNCMM388MsgRxTime_MSec_M_u32	787569408

Name	Input Value
PrevISDYNVOLMsgDLCError_Cnt_M_u08	187
PrevISDYNVOLMsgRxTime_MSec_M_u32	1899920128
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	15837952
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	97.8809967
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	54410
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	17605
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	31479
VitesseVehicleBVRampValidCount_Cnt_M_u16	54002
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	497
VitesseVehicleBVSigValidCount_Cnt_M_u16	756
VitesseVehicleBV_Kph_M_f32	63.7173996
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	10048
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	43867
VitesseVehiculeRoues_Kph_M_f32	444.264404
k_AASNTCEnableTimeout_mS_u16	16072
k_AASNodeAbsentDiag_Cnt_str.Threshold	1812
k_AASNodeAbsentDiag_Cnt_str.PStep	53264
k_AASNodeAbsentDiag_Cnt_str.NStep	24980
k_AASNodeAbsentTimeout_mS_u16	50425
k_AASNodeTimeout_mS_u16	965
k_ABSNodeTimeout_mS_u16	18722
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	52374
k_ANGLEVOLANTSigValidThresh_Cnt_u16	23109
k_AngleVolantInvalidThresh_Cnt_u16	59328
k_AngleVolantValidThresh_Cnt_u16	2077
k_BSI552MsgTimeout_mS_u16	28822
k_BSINTCEnableTimeout_mS_u16	36623
k_BSINodeAbsentDiag_Cnt_str.Threshold	22092
k_BSINodeAbsentDiag_Cnt_str.PStep	36151
k_BSINodeAbsentDiag_Cnt_str.NStep	12796
k_BSINodeAbsentTimeout_mS_u16	58823
k_BSINodeTimeout_mS_u16	18642
k_BattOvHi_Volt_f32	27.4074001
k_BattOvLo_Volt_f32	16.4946003
k_BattUvHi_Volt_f32	14.2903004
k_BattUvLo_Volt_f32	12.7229004
k_CAVNTCEnableTimeout_mS_u16	64731
k_CAVNodeAbsentDiag_Cnt_str.Threshold	669
k_CAVNodeAbsentDiag_Cnt_str.PStep	3068
k_CAVNodeAbsentDiag_Cnt_str.NStep	23385
k_CAVNodeAbsentTimeout_mS_u16	30787
k_CAVNodeTimeout_mS_u16	15439
k_CMM388MsgTimeout_mS_u16	6542
k_CMM388NTCEnableTimeout_mS_u16	12762
k_CMMNTCEnableTimeout_mS_u16	44006
k_CMMNodeAbsentDiag_Cnt_str.Threshold	39294
k_CMMNodeAbsentDiag_Cnt_str.PStep	30660
k_CMMNodeAbsentDiag_Cnt_str.NStep	10112
k_CMMNodeAbsentTimeout_mS_u16	20903
k_CONSANGLECPKMax_HwDeg_f32	616.367126
k_CONSANGLECPKMin_HwDeg_f32	-128.129593
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	42560
k_CONSANGLECPKSigValidThresh_Cnt_u16	27227
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	54739
k_CPKVehicleSpeedValidThresh_Cnt_u16	50273
k_CityParkInputInvalidThresh_Cnt_u16	42579
k_CityParkInputValidThresh_Cnt_u16	21966

Name	Input Value
k_ComputerRazGCTSigValidThresh_Cnt_u16	2364
k_CptTemporelSigValidThresh_Cnt_u16	48452
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	32534
k_DMDFCTCPKSigValidThresh_Cnt_u16	54825
k_DMDFCTCPKValidCount_Cnt_u16	63871
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	36860
k_DMDRELAXECPKSigValidThresh_Cnt_u16	26119
k_DMDRelaxeConsistentThresh_Cnt_u16	51733
k_DateValidThresh_Cnt_u16	13122
k_DefaultVehSpd_Kph_f32	143.247192
k_DiagMuxOnAbsentTimeout_mS_u16	50715
k_EMNodeTimeout_mS_u16	12932
k_ESPNTCEnableTimeout_mS_u16	20329
k_ESPNodeAbsentDiag_Cnt_str.Threshold	45167
k_ESPNodeAbsentDiag_Cnt_str.PStep	1188
k_ESPNodeAbsentDiag_Cnt_str.NStep	26390
k_ESPNodeAbsentTimeout_mS_u16	1039
k_EtatMTSigInvalidThresh_Cnt_u16	38560
k_EtatMTSigValidThresh_Cnt_u16	14091
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	3386
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	57913
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	5691
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	7055
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	63447
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	60174
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	41528
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	34151
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	40491
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	13681
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	27528
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	48473
k_ISDATDIRASentDiag_Cnt_str.Threshold	35790
k_ISDATDIRASentDiag_Cnt_str.PStep	24264
k_ISDATDIRASentDiag_Cnt_str.NStep	12776
k_ISDATDIRASentTimeout_mS_u16	34577
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	4690
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	5679
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	46469
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	64709
k_ISDYNAASChkSumValidThresh_Cnt_u16	24304
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	56699
k_ISDYNAASMsgCountValidThresh_Cnt_u16	64158
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	13177
k_ISDYNAASMsgLenValidThresh_Cnt_u16	38265
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	49837
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	63804
k_ISDYNABRChkSumValidThresh_Cnt_u16	49359
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	30999
k_ISDYNABRMsgCountValidThresh_Cnt_u16	43674
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	37827
k_ISDYNABRMsgLenValidThresh_Cnt_u16	6450
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	50005
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	34366
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	33543
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	31744
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	15108
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	62535
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	11189
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	24057
k_ISDYNVOLChkSumValidThresh_Cnt_u16	4784
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	4307
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	62628
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	22017
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	22945
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	35456
k_IgnOnTimeout_mS_u16	27461
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	147.442993
k_PowerCutVehSpdLowThresh_Kph_f32	97.2946014
k_PowerCutVehSpdLowTimeout_mS_u16	2244
k_VBattMaxAAS_Volt_f32	19.6098003
k_VBattMaxBSI_Volt_f32	6.89589977
k_VBattMaxCAV_Volt_f32	1.5661

Name	Input Value
k_VBattMaxCMM388_Volt_f32	5.18709993
k_VBattMaxCMM_Volt_f32	30.3484001
k_VBattMaxESP_Volt_f32	15.5838003
k_VBattMinAAS_Volt_f32	11.0190001
k_VBattMinBSI_Volt_f32	15.5838003
k_VBattMinCAV_Volt_f32	26.6138
k_VBattMinCMM388_Volt_f32	14.9070997
k_VBattMinCMM_Volt_f32	27.1958008
k_VBattMinESP_Volt_f32	30.3484001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	26436
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	47595
k_VitesseVehicleBVRampValidThresh_Cnt_u16	27279
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	18812
k_VitesseVehicleBVSigValidThresh_Cnt_u16	467
k_VitesseVehicleBVSpeedPassThresh_kph_f32	633.508789
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	45341
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	31128
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3756301056
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	37798
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3835959040
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	102
target_SrlComInput_Per1_Batt_Volt_f32.value	20.9087009
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1581271808
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	29
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.26312077
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	204
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	389888768
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	4
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3660241664
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	28
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2435349248
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1681267456
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2069084928
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	52
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4269890304
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	364837632
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	20
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	41
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	64
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	91
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1132665600
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	48
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	49
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	122
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	167
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	193

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2195995392
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2538724096
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1607432960
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	77
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	101
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2068171520
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2257
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.224137321
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	388681
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	2.71670008
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	49404

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3835959040	3835959040	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	1812	1812	✔
AASNodeAbsentTimer_mS_M_u32	3835959040	3835959040	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	5681	5681	✔
AngleVolantMsgTimer_mS_M_u32	3835959040	3835959040	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3835959040	3835959040	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3835959040	3835959040	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3835959040	3835959040	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3835959040	3835959040	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	22092	22092	✔
BSINodeAbsentTimer_mS_M_u32	3835959040	3835959040	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3835959040	3835959040	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3835959040	3835959040	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3835959040	3835959040	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3835959040	3835959040	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	39294	39294	✔
CMMNodeAbsentTimer_mS_M_u32	3835959040	3835959040	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	61917	61917	✔
CONSANGLECPK_HwDeg_M_f32	-673.916687	-673.916687 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	61917	61917	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3835959040	3835959040	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	21966	21966	✔
CityParkInputInvalidCount_Cnt_M_u16	2079	2079	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CityParkInputMsgTimer_mS_M_u32	3835959040	3835959040	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3835959040	3835959040	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3835959040	3835959040	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3835959040	3835959040	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3835959040	3835959040	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3835959040	3835959040	✔
ESPNTCEnableTimer_mS_M_u32	3835959040	3835959040	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3835959040	3835959040	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3835959040	3835959040	✔
EffacDefaultDiagTimer_mS_M_u32[1]	16	16	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3835959040	3835959040	✔
ElecIntTimer_mS_M_u32[1]	1151	1151	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3835959040	3835959040	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3835959040	3835959040	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3835959040	3835959040	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3835959040	3835959040	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3835959040	3835959040	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3835959040	3835959040	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3835959040	3835959040	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3835959040	3835959040	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3835959040	3835959040	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3835959040	3835959040	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3835959040	3835959040	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3835959040	3835959040	✔
IgnOnTimer_mS_M_u32	3835959040	3835959040	✔
IgnTimeOff_Sec_M_u32	776031488	776031488	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	204	204	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	389888768	389888768	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	4	4	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3660241664	3660241664	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	28	28	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2435349248	2435349248	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	60	60	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1681267456	1681267456	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4078009088	4078009088	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	52	52	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4269890304	4269890304	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	93	93	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	364837632	364837632	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	235	235	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1132665600	1132665600	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	119	119	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2195995392	2195995392	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2538724096	2538724096	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	106	106	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1607432960	1607432960	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2068171520	2068171520	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	97.8809967	97.8809967	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	63.7173996	63.7173996	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	444.264404	444.264404	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	61917	61917	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	776031488	776031488	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-673.916687	-673.916687 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	143.247192	143.247192	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.52 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4279878144
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	46688
AASNodeAbsentTimer_mS_M_u32	4277580288
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	19452
ANGLEVOLANTSigValidCount_Cnt_M_u16	10483
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	34685
AngleVolantMsgTimer_mS_M_u32	4279878144
AngleVolantValidCount_Cnt_M_u16	3130
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1689154048
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	203223552
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2828034560
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	517415424
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	40387

Name	Input Value
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2894651904
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	5170
CAVNodeAbsentTimer_mS_M_u32	2743161344
CDD_SrlComVehSpd_Kph_G_f32	9.85289955
CMM388NTCEnableTimer_mS_M_u32	3436548608
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4032254464
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	4607
CMMNodeAbsentTimer_mS_M_u32	2558599680
CONSANGLECPKSigInvalidCount_Cnt_M_u16	36864
CONSANGLECPKSigValidCount_Cnt_M_u16	31814
CONSANGLECPK_Cnt_M_u16	64049
CONSANGLECPK_HwDeg_M_f32	-169.625305
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	64049
CPKVehicleSpeedMsgTimer_mS_M_u32	1310245376
CPKVehicleSpeedValidCount_Cnt_M_u16	47141
CityParkInputConsistentCount_Cnt_M_u16	20254
CityParkInputInvalidCount_Cnt_M_u16	16691
CityParkInputMsgTimer_mS_M_u32	389888768
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4208636416
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	3908
ComputerRazGCTSigInvalidTimer_mS_M_u32	1705103872
ComputerRazGCTSigValidCount_Cnt_M_u16	61171
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	55887
DMDFCTCPKSigValidCount_Cnt_M_u16	2478
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	33902
DMDRELAXECPKSigValidCount_Cnt_M_u16	13029
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	55837
DateInvalidTimer_mS_M_u32	203223552
DiagMuxOnAbsentTimer_mS_M_u32	330007040
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	517415424
ESPNTCEnableTimer_mS_M_u32	1740091904
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	14962
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	88
EffacDefaultDiagTimer_mS_M_u32[1]	108
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2050
ElecIntTimer_mS_M_u32[1]	6071
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3076186624
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	47656
EtatMTSigValidCount_Cnt_M_u16	35595
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	40562
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	56376
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	4228
ISDAT4V2BSI552MsgTimer_mS_M_u32	2003116544
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	9694
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	17928
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	35595
ISDATBSI3F2MsgTimer_mS_M_u32	490308096
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	10428
ISDATBSI412MsgLenValidCount_Cnt_M_u16	65302
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	47656
ISDATBSI412MsgTimer_mS_M_u32	245875200
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	5091
ISDATBSI432MsgLenValidCount_Cnt_M_u16	40790
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	58387
ISDATDIRASentFltAcc_Cnt_M_u16	10503
ISDATDIRASentTimer_mS_M_u32	1310245376

Name	Input Value
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	45631
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	3130
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	58774
ISDYN2CMMMsgTimer_mS_M_u32	2380378624
ISDYNAASChkSumInvalidCount_Cnt_M_u16	64210
ISDYNAASChkSumValidCount_Cnt_M_u16	5352
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	7553
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	5725
ISDYNAASMsgLenValidCount_Cnt_M_u16	32748
ISDYNAASMsgTimeValidCount_Cnt_M_u16	64210
ISDYNAASMsgTimer_mS_M_u32	720474624
ISDYNABRChkSumInvalidCount_Cnt_M_u16	8762
ISDYNABRChkSumValidCount_Cnt_M_u16	42104
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	24217
ISDYNABRMsgCountValidCount_Cnt_M_u16	36847
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	63175
ISDYNABRMsgLenValidCount_Cnt_M_u16	14925
ISDYNABRMsgTimeValidCount_Cnt_M_u16	64049
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	618
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1121
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	35595
ISDYNCMM208MsgTimer_mS_M_u32	2026074624
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2323
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1227
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	8904
ISDYNCMM388MsgTimer_mS_M_u32	154472960
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	20878
ISDYNVOLChkSumValidCount_Cnt_M_u16	60500
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	57053
ISDYNVOLMsgCountValidCount_Cnt_M_u16	64700
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	58795
ISDYNVOLMsgLenValidCount_Cnt_M_u16	62673
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	4607
ISDYNVOLMsgTimer_mS_M_u32	1874711040
IgnOnTimer_mS_M_u32	3273200128
IgnTimeOff_Sec_M_u32	1485882410
ManVehSpd_Kph_M_f32	361.18689
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	194
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	144
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2918154752
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	255
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1329029632
PrevISDATBSI412MsgDLCError_Cnt_M_u08	169
PrevISDATBSI412MsgRxTime_MSec_M_u32	1243763200
PrevISDATBSI432MsgDLCError_Cnt_M_u08	32
PrevISDATBSI432MsgRxTime_MSec_M_u32	1191948800
PrevISDATDIRAMsgTxTime_MSec_M_u32	504779264
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	212
PrevISDYN2CMMMsgRxTime_MSec_M_u32	709665280
PrevISDYNAASMsgDLCError_Cnt_M_u08	163
PrevISDYNAASMsgRxTime_MSec_M_u32	1875628544
PrevISDYNABRMsgDLCError_Cnt_M_u08	167
PrevISDYNABRMsgRxTime_MSec_M_u32	1381044736
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	77
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1902170624
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	225
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1106686464
PrevISDYNVOLMsgDLCError_Cnt_M_u08	230
PrevISDYNVOLMsgRxTime_MSec_M_u32	2542752256
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4046832128
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	627.520203

Name	Input Value
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	8427
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	63738
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	8612
VitesseVehicleBVRampValidCount_Cnt_M_u16	17011
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	60981
VitesseVehicleBVSigValidCount_Cnt_M_u16	13292
VitesseVehicleBV_Kph_M_f32	491.574707
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	8904
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	16182
VitesseVehiculeRoues_Kph_M_f32	374.183197
k_AASNTCEnableTimeout_mS_u16	32624
k_AASNodeAbsentDiag_Cnt_str.Threshold	61357
k_AASNodeAbsentDiag_Cnt_str.PStep	25842
k_AASNodeAbsentDiag_Cnt_str.NStep	5853
k_AASNodeAbsentTimeout_mS_u16	28061
k_AASNodeTimeout_mS_u16	48122
k_ABSNodeTimeout_mS_u16	53796
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	13958
k_ANGLEVOLANTSigValidThresh_Cnt_u16	34361
k_AngleVolantInvalidThresh_Cnt_u16	35272
k_AngleVolantValidThresh_Cnt_u16	16691
k_BSI552MsgTimeout_mS_u16	39813
k_BSINTCEnableTimeout_mS_u16	4891
k_BSINodeAbsentDiag_Cnt_str.Threshold	22132
k_BSINodeAbsentDiag_Cnt_str.PStep	36134
k_BSINodeAbsentDiag_Cnt_str.NStep	12819
k_BSINodeAbsentTimeout_mS_u16	30901
k_BSINodeTimeout_mS_u16	58387
k_BattOvHi_Volt_f32	8.71339989
k_BattOvLo_Volt_f32	23.9004993
k_BattUvHi_Volt_f32	23.4990997
k_BattUvLo_Volt_f32	23.2185993
k_CAVNTCEnableTimeout_mS_u16	56057
k_CAVNodeAbsentDiag_Cnt_str.Threshold	30185
k_CAVNodeAbsentDiag_Cnt_str.PStep	39748
k_CAVNodeAbsentDiag_Cnt_str.NStep	15077
k_CAVNodeAbsentTimeout_mS_u16	22976
k_CAVNodeTimeout_mS_u16	58908
k_CMM388MsgTimeout_mS_u16	47456
k_CMM388NTCEnableTimeout_mS_u16	41084
k_CMMNTCEnableTimeout_mS_u16	33046
k_CMMNodeAbsentDiag_Cnt_str.Threshold	9552
k_CMMNodeAbsentDiag_Cnt_str.PStep	21430
k_CMMNodeAbsentDiag_Cnt_str.NStep	56313
k_CMMNodeAbsentTimeout_mS_u16	31826
k_CONSANGLECPKMax_HwDeg_f32	256.066101
k_CONSANGLECPKMin_HwDeg_f32	-17.9995003
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	42440
k_CONSANGLECPKSigValidThresh_Cnt_u16	566
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	64976
k_CPKVehicleSpeedValidThresh_Cnt_u16	61607
k_CityParkInputInvalidThresh_Cnt_u16	24720
k_CityParkInputValidThresh_Cnt_u16	20254
k_ComputerRazGCTSigValidThresh_Cnt_u16	16660
k_CptTemporelSigValidThresh_Cnt_u16	32190
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	63943
k_DMDFCTCPKSigValidThresh_Cnt_u16	32077
k_DMDFCTCPKValidCount_Cnt_u16	49035

Name	Input Value
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	58774
k_DMDRELAXECPKSigValidThresh_Cnt_u16	52277
k_DMDRelaxeConsistentThresh_Cnt_u16	22539
k_DateValidThresh_Cnt_u16	4228
k_DefaultVehSpd_Kph_f32	4.80030012
k_DiagMuxOnAbsentTimeout_mS_u16	62839
k_EMNodeTimeout_mS_u16	6013
k_ESPNTCEnableTimeout_mS_u16	60494
k_ESPNodeAbsentDiag_Cnt_str.Threshold	41693
k_ESPNodeAbsentDiag_Cnt_str.PStep	15477
k_ESPNodeAbsentDiag_Cnt_str.NStep	4504
k_ESPNodeAbsentTimeout_mS_u16	1306
k_EtatMTSigInvalidThresh_Cnt_u16	937
k_EtatMTSigValidThresh_Cnt_u16	2855
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	45979
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	27997
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	471
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	5659
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	55813
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	28832
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	48544
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	3283
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	21959
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	32629
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	30192
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	14014
k_ISDATDIRASentDiag_Cnt_str.Threshold	58583
k_ISDATDIRASentDiag_Cnt_str.PStep	55649
k_ISDATDIRASentDiag_Cnt_str.NStep	47545
k_ISDATDIRASentTimeout_mS_u16	13910
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	23507
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	34685
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10746
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	42298
k_ISDYNAASChkSumValidThresh_Cnt_u16	26488
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	24985
k_ISDYNAASMsgCountValidThresh_Cnt_u16	53999
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	53534
k_ISDYNAASMsgLenValidThresh_Cnt_u16	55006
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	60673
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	41813
k_ISDYNABRChkSumValidThresh_Cnt_u16	54619
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	41155
k_ISDYNABRMsgCountValidThresh_Cnt_u16	21754
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	54527
k_ISDYNABRMsgLenValidThresh_Cnt_u16	15730
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	46793
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	56271
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	52405
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	65353
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	20220
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	27635
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	13931
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	33759
k_ISDYNVOLChkSumValidThresh_Cnt_u16	32377
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	6799
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	30300
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	22340
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	1319
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	33482
k_IgnOnTimeout_mS_u16	35835
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	232.712906
k_PowerCutVehSpdLowThresh_Kph_f32	103.158203
k_PowerCutVehSpdLowTimeout_mS_u16	4476
k_VBattMaxAAS_Volt_f32	1.56869996
k_VBattMaxBSI_Volt_f32	3.16529989
k_VBattMaxCAV_Volt_f32	2.81579995
k_VBattMaxCMM388_Volt_f32	17.2828999
k_VBattMaxCMM_Volt_f32	3.51300001
k_VBattMaxESP_Volt_f32	19.6730003
k_VBattMinAAS_Volt_f32	16.094101
k_VBattMinBSI_Volt_f32	19.6730003

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinCAV_Volt_f32	9.23820019
k_VBattMinCMM388_Volt_f32	16.0634995
k_VBattMinCMM_Volt_f32	26.4736996
k_VBattMinESP_Volt_f32	3.51300001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	42237
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	34248
k_VitesseVehicleBVRampValidThresh_Cnt_u16	25053
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	12116
k_VitesseVehicleBVSigValidThresh_Cnt_u16	40719
k_VitesseVehicleBVSpeedPassThresh_kph_f32	290.372406
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	38706
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	26241
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	203223552
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	48
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	48000
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1724808704
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	225
target_SrlComInput_Per1_Batt_Volt_f32.value	0.466600001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3687440896
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	133
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.492813468
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	278073856
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	105525760
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1607553536
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	52
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2770891264
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1582273024
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	323400192
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1275974144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	8
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	118
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	130
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	155
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2067886592
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	97
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	107
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	202
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	220
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	232
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	698225152
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	230
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	718615040

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1339838976
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	45
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	166
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	167
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2058969600
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	420
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.341409594
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	336927
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	7.14190006
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	41877

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1724808704	1724808704	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	61357	61357	✔
AASNodeAbsentTimer_mS_M_u32	1724808704	1724808704	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	34687	34687	✔
AngleVolantMsgTimer_mS_M_u32	1724808704	1724808704	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1724808704	1724808704	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1724808704	1724808704	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1724808704	1724808704	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1724808704	1724808704	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	22132	22132	✔
BSINodeAbsentTimer_mS_M_u32	1724808704	1724808704	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1724808704	1724808704	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1724808704	1724808704	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1724808704	1724808704	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1724808704	1724808704	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	9552	9552	✔
CMMNodeAbsentTimer_mS_M_u32	1724808704	1724808704	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	64049	64049	✔
CONSANGLECPK_HwDeg_M_f32	-169.625305	-169.625305 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	64049	64049	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1310245376	1310245376	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	47141	47141	✔
CityParkInputConsistentCount_Cnt_M_u16	20254	20254	✔
CityParkInputInvalidCount_Cnt_M_u16	16693	16693	✔
CityParkInputMsgTimer_mS_M_u32	1724808704	1724808704	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1724808704	1724808704	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ComputerRazGCTSigInvalidTimer_mS_M_u32	1724808704	1724808704	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1724808704	1724808704	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1724808704	1724808704	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1724808704	1724808704	✔
ESPNTCEnableTimer_mS_M_u32	1724808704	1724808704	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1724808704	1724808704	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	88	88	✔
EffacDefaultDiagTimer_mS_M_u32[1]	108	108	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2050	2050	✔
ElecIntTimer_mS_M_u32[1]	6071	6071	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1724808704	1724808704	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1724808704	1724808704	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1724808704	1724808704	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1724808704	1724808704	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1724808704	1724808704	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1724808704	1724808704	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1724808704	1724808704	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1724808704	1724808704	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1724808704	1724808704	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1724808704	1724808704	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1724808704	1724808704	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1724808704	1724808704	✔
IgnOnTimer_mS_M_u32	3273200128	3273200128	✔
IgnTimeOff_Sec_M_u32	1485882410	1485882410	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	104	104	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	278073856	278073856	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	223	223	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	105525760	105525760	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	246	246	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1607553536	1607553536	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	52	52	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2770891264	2770891264	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	504779264	504779264	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	72	72	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	323400192	323400192	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	46	46	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1275974144	1275974144	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	155	155	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2067886592	2067886592	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	195	195	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	698225152	698225152	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	230	230	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	718615040	718615040	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	104	104	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1339838976	1339838976	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2058969600	2058969600	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	627.520203	627.520203	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	491.574707	491.574707	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	374.183197	374.183197	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	64049	64049	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1485882410	1485882410	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-169.625305	-169.625305 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	4.80030012	4.80030012	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.53 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1473871104
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	27653
AASNodeAbsentTimer_mS_M_u32	939699456
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	48432
ANGLEVOLANTSigValidCount_Cnt_M_u16	19469
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	44206
AngleVolantMsgTimer_mS_M_u32	1473871104
AngleVolantValidCount_Cnt_M_u16	64247
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2514185472
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2039475456
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	4260732160
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	639720704
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	41947
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1946950912
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	25870
CAVNodeAbsentTimer_mS_M_u32	1021496576
CDD_SrlComVehSpd_Kph_G_f32	384.246704

Name	Input Value
CMM388NTCEnableTimer_mS_M_u32	1642466560
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	778095872
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	47720
CMMNodeAbsentTimer_mS_M_u32	3777191168
CONSANGLECPKSigInvalidCount_Cnt_M_u16	45093
CONSANGLECPKSigValidCount_Cnt_M_u16	20753
CONSANGLECPK_Cnt_M_u16	17232
CONSANGLECPK_HwDeg_M_f32	269.417389
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17232
CPKVehicleSpeedMsgTimer_mS_M_u32	651984128
CPKVehicleSpeedValidCount_Cnt_M_u16	63199
CityParkInputConsistentCount_Cnt_M_u16	49739
CityParkInputInvalidCount_Cnt_M_u16	53515
CityParkInputMsgTimer_mS_M_u32	278073856
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3562450176
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	61785
ComputerRazGCTSigInvalidTimer_mS_M_u32	411127040
ComputerRazGCTSigValidCount_Cnt_M_u16	30412
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	30135
DMDFCTCPKSigValidCount_Cnt_M_u16	44380
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	23514
DMDRELAXECPKSigValidCount_Cnt_M_u16	30263
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	34254
DateInvalidTimer_mS_M_u32	2039475456
DiagMuxOnAbsentTimer_mS_M_u32	2435071232
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	639720704
ESPNTCEnableTimer_mS_M_u32	1103080704
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	22224
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	1
EffacDefaultDiagTimer_mS_M_u32[1]	11
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	9900
ElecIntTimer_mS_M_u32[1]	11001
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	462822656
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	63212
EtatMTSigValidCount_Cnt_M_u16	23044
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	52431
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	31035
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	28890
ISDAT4V2BSI552MsgTimer_mS_M_u32	3564592384
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	49484
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	22156
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	23044
ISDATBSI3F2MsgTimer_mS_M_u32	746208512
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	433
ISDATBSI412MsgLenValidCount_Cnt_M_u16	13410
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	63212
ISDATBSI412MsgTimer_mS_M_u32	3777985792
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	17596
ISDATBSI432MsgLenValidCount_Cnt_M_u16	47140
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	47467
ISDATDIRASentFltAcc_Cnt_M_u16	47759
ISDATDIRASentTimer_mS_M_u32	651984128
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	54054
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	64247
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	12258
ISDYN2CMMMsgTimer_mS_M_u32	4148276480
ISDYNAASChkSumInvalidCount_Cnt_M_u16	59055
ISDYNAASChkSumValidCount_Cnt_M_u16	15916

Name	Input Value
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	41762
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	51853
ISDYNAASMsgLenValidCount_Cnt_M_u16	5025
ISDYNAASMsgTimeValidCount_Cnt_M_u16	59055
ISDYNAASMsgTimer_mS_M_u32	3079802112
ISDYNABRChkSumInvalidCount_Cnt_M_u16	26616
ISDYNABRChkSumValidCount_Cnt_M_u16	9981
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	38746
ISDYNABRMsgCountValidCount_Cnt_M_u16	43287
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	22480
ISDYNABRMsgLenValidCount_Cnt_M_u16	62204
ISDYNABRMsgTimeValidCount_Cnt_M_u16	17232
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	619
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1123
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	23044
ISDYNCMM208MsgTimer_mS_M_u32	3986451712
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2327
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1229
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	28493
ISDYNCMM388MsgTimer_mS_M_u32	2328333568
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	9083
ISDYNVOLChkSumValidCount_Cnt_M_u16	47335
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	8205
ISDYNVOLMsgCountValidCount_Cnt_M_u16	35890
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	31013
ISDYNVOLMsgLenValidCount_Cnt_M_u16	12658
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	47720
ISDYNVOLMsgTimer_mS_M_u32	1781353728
IgnOnTimer_mS_M_u32	3978005760
IgnTimeOff_Sec_M_u32	2032707044
ManVehSpd_Kph_M_f32	355.135101
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	196
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	233
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3528998144
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	186
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1711316224
PrevISDATBSI412MsgDLCError_Cnt_M_u08	177
PrevISDATBSI412MsgRxTime_MSec_M_u32	218090752
PrevISDATBSI432MsgDLCError_Cnt_M_u08	28
PrevISDATBSI432MsgRxTime_MSec_M_u32	4089687296
PrevISDATDIRAMsgTxTime_MSec_M_u32	1629736192
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	73
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3116424448
PrevISDYNAASMsgDLCError_Cnt_M_u08	217
PrevISDYNAASMsgRxTime_MSec_M_u32	570641664
PrevISDYNABRMsgDLCError_Cnt_M_u08	104
PrevISDYNABRMsgRxTime_MSec_M_u32	527666432
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	22
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2974043392
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	193
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1862446336
PrevISDYNVOLMsgDLCError_Cnt_M_u08	165
PrevISDYNVOLMsgRxTime_MSec_M_u32	414764288
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4052057344
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	361.818207
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput

Name	Input Value
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	25315
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	24695
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	33976
VitesseVehicleBVRampValidCount_Cnt_M_u16	43020
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	64133
VitesseVehicleBVSigValidCount_Cnt_M_u16	20258
VitesseVehicleBV_Kph_M_f32	172.2827
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	28493
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	8130
VitesseVehiculeRoues_Kph_M_f32	77.0692978
k_AASNTCEnableTimeout_mS_u16	28563
k_AASNodeAbsentDiag_Cnt_str.Threshold	17277
k_AASNodeAbsentDiag_Cnt_str.PStep	21255
k_AASNodeAbsentDiag_Cnt_str.NStep	59869
k_AASNodeAbsentTimeout_mS_u16	8910
k_AASNodeTimeout_mS_u16	6007
k_ABSNodeTimeout_mS_u16	8760
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	10451
k_ANGLEVOLANTSigValidThresh_Cnt_u16	20347
k_AngleVolantInvalidThresh_Cnt_u16	16590
k_AngleVolantValidThresh_Cnt_u16	53515
k_BSI552MsgTimeout_mS_u16	1749
k_BSINTCEnableTimeout_mS_u16	10004
k_BSINodeAbsentDiag_Cnt_str.Threshold	22172
k_BSINodeAbsentDiag_Cnt_str.PStep	36117
k_BSINodeAbsentDiag_Cnt_str.NStep	12842
k_BSINodeAbsentTimeout_mS_u16	47366
k_BSINodeTimeout_mS_u16	47467
k_BattOvHi_Volt_f32	14.0277996
k_BattOvLo_Volt_f32	21.1203003
k_BattUvHi_Volt_f32	10.8671999
k_BattUvLo_Volt_f32	26.6574001
k_CAVNTCEnableTimeout_mS_u16	39865
k_CAVNodeAbsentDiag_Cnt_str.Threshold	42561
k_CAVNodeAbsentDiag_Cnt_str.PStep	20936
k_CAVNodeAbsentDiag_Cnt_str.NStep	43454
k_CAVNodeAbsentTimeout_mS_u16	19556
k_CAVNodeTimeout_mS_u16	7633
k_CMM388MsgTimeout_mS_u16	25349
k_CMM388NTCEnableTimeout_mS_u16	7601
k_CMMNTCEnableTimeout_mS_u16	36772
k_CMMNodeAbsentDiag_Cnt_str.Threshold	23541
k_CMMNodeAbsentDiag_Cnt_str.PStep	21786
k_CMMNodeAbsentDiag_Cnt_str.NStep	54763
k_CMMNodeAbsentTimeout_mS_u16	55406
k_CONSANGLECPKMax_HwDeg_f32	437.322205
k_CONSANGLECPKMin_HwDeg_f32	-573.814026
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	58957
k_CONSANGLECPKSigValidThresh_Cnt_u16	54978
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	10741
k_CPKVehicleSpeedValidThresh_Cnt_u16	5616
k_CityParkInputInvalidThresh_Cnt_u16	34038
k_CityParkInputValidThresh_Cnt_u16	49739
k_ComputerRazGCTSigValidThresh_Cnt_u16	51114
k_CptTemporelSigValidThresh_Cnt_u16	1898
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	20176
k_DMDFCTCPKSigValidThresh_Cnt_u16	10748
k_DMDFCTCPKValidCount_Cnt_u16	24195
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	12258
k_DMDRELAXECPKSigValidThresh_Cnt_u16	16839
k_DMDRelaxeConsistentThresh_Cnt_u16	30277
k_DateValidThresh_Cnt_u16	28890
k_DefaultVehSpd_Kph_f32	123.250397
k_DiagMuxOnAbsentTimeout_mS_u16	59774

Name	Input Value
k_EMNodeTimeout_mS_u16	19886
k_ESPNTCEnableTimeout_mS_u16	19642
k_ESPNodeAbsentDiag_Cnt_str.Threshold	7215
k_ESPNodeAbsentDiag_Cnt_str.PStep	27837
k_ESPNodeAbsentDiag_Cnt_str.NStep	55277
k_ESPNodeAbsentTimeout_mS_u16	24086
k_EtatMTSigInvalidThresh_Cnt_u16	16299
k_EtatMTSigValidThresh_Cnt_u16	28400
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	62612
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	7437
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	52768
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	9365
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	52885
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	47621
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	31621
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	41901
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	3856
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	50052
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	5589
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	45226
k_ISDATDIRASentDiag_Cnt_str.Threshold	14839
k_ISDATDIRASentDiag_Cnt_str.PStep	62449
k_ISDATDIRASentDiag_Cnt_str.NStep	9666
k_ISDATDIRASentTimeout_mS_u16	39844
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	54635
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	44206
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	17334
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	57080
k_ISDYNAASChkSumValidThresh_Cnt_u16	56829
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	36442
k_ISDYNAASMsgCountValidThresh_Cnt_u16	57367
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	60236
k_ISDYNAASMsgLenValidThresh_Cnt_u16	22219
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	15139
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	2598
k_ISDYNABRChkSumValidThresh_Cnt_u16	55762
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	39643
k_ISDYNABRMsgCountValidThresh_Cnt_u16	41976
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	29032
k_ISDYNABRMsgLenValidThresh_Cnt_u16	19920
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	31371
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	49719
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	14790
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	18826
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	46128
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	33549
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	53603
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	15432
k_ISDYNVOLChkSumValidThresh_Cnt_u16	569
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	27257
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	16721
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	36760
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	23472
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	45576
k_IgnOnTimeout_mS_u16	37876
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	254.012604
k_PowerCutVehSpdLowThresh_Kph_f32	202.676697
k_PowerCutVehSpdLowTimeout_mS_u16	59759
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	5.7347002
k_VBattMaxCAV_Volt_f32	22.7996006
k_VBattMaxCMM388_Volt_f32	2.40829992
k_VBattMaxCMM_Volt_f32	23.5762005
k_VBattMaxESP_Volt_f32	26.4976997
k_VBattMinAAS_Volt_f32	23.0547009
k_VBattMinBSI_Volt_f32	26.4976997
k_VBattMinCAV_Volt_f32	22.8362007
k_VBattMinCMM388_Volt_f32	21.2450008
k_VBattMinCMM_Volt_f32	13.1855001
k_VBattMinESP_Volt_f32	23.5762005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	8685
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	62798

Name	Input Value
k_VitesseVehicleBVRampValidThresh_Cnt_u16	38669
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	61415
k_VitesseVehicleBVSigValidThresh_Cnt_u16	54904
k_VitesseVehicleBVSpeedPassThresh_kph_f32	189.414001
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	56334
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	62434
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2039475456
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	36
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	43885
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	4004202752
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	193
target_SrlComInput_Per1_Batt_Volt_f32.value	21.1816006
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	709434624
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	120
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.100180529
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	250
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1823313152
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	58
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3490196736
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1207094528
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1013804288
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	360189184
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	991079680
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	356338944
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	159
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	175
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	196
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	245
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	179
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1579314432
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	68
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	111
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	192
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	227314944
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	17
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1315384576
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	112
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1674693888
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	25
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	33
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	104

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1803197696
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2067
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0455085076
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	377757
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	93.9757996
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	741

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4004202752	4004202752	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	17277	17277	✔
AASNodeAbsentTimer_mS_M_u32	4004202752	4004202752	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	44206	44206	✔
AngleVolantMsgTimer_mS_M_u32	4004202752	4004202752	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4004202752	4004202752	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4004202752	4004202752	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4004202752	4004202752	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4004202752	4004202752	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	22172	22172	✔
BSINodeAbsentTimer_mS_M_u32	4004202752	4004202752	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4004202752	4004202752	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4004202752	4004202752	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4004202752	4004202752	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4004202752	4004202752	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	23541	23541	✔
CMMNodeAbsentTimer_mS_M_u32	4004202752	4004202752	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	17232	17232	✔
CONSANGLECPK_HwDeg_M_f32	269.417389	269.417389 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17232	17232	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	651984128	651984128	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	63199	63199	✔
CityParkInputConsistentCount_Cnt_M_u16	49739	49739	✔
CityParkInputInvalidCount_Cnt_M_u16	53515	53515	✔
CityParkInputMsgTimer_mS_M_u32	4004202752	4004202752	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4004202752	4004202752	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4004202752	4004202752	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4004202752	4004202752	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4004202752	4004202752	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4004202752	4004202752	✔
ESPNTCEnableTimer_mS_M_u32	4004202752	4004202752	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4004202752	4004202752	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[1]	11	11	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4004202752	4004202752	✔
ElecIntTimer_mS_M_u32[1]	11001	11001	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4004202752	4004202752	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4004202752	4004202752	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4004202752	4004202752	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4004202752	4004202752	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4004202752	4004202752	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	4004202752	4004202752	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4004202752	4004202752	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4004202752	4004202752	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4004202752	4004202752	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4004202752	4004202752	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4004202752	4004202752	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4004202752	4004202752	✔
IgnOnTimer_mS_M_u32	3978005760	3978005760	✔
IgnTimeOff_Sec_M_u32	2032707044	2032707044	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	250	250	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1823313152	1823313152	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	58	58	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3490196736	3490196736	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1207094528	1207094528	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	68	68	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1013804288	1013804288	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1629736192	1629736192	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	16	16	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	991079680	991079680	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	67	67	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	356338944	356338944	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	179	179	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1579314432	1579314432	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	212	212	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	227314944	227314944	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	17	17	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1315384576	1315384576	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	112	112	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1674693888	1674693888	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1803197696	1803197696	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	361.818207	361.818207	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	172.2827	172.2827	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	77.0692978	77.0692978	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	17232	17232	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2032707044	2032707044	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	269.417389	269.417389 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	123.250397	123.250397	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.54 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3928214016
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	8186
AASNodeAbsentTimer_mS_M_u32	2105981440
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	20454
ANGLEVOLANTSigValidCount_Cnt_M_u16	24019
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	38967
AngleVolantMsgTimer_mS_M_u32	3928214016
AngleVolantValidCount_Cnt_M_u16	48968
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1071020544
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1725233664
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	928934400
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3130862080
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	36109
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1260841472
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	22288
CAVNodeAbsentTimer_mS_M_u32	643127808
CDD_SrlComVehSpd_Kph_G_f32	162.120605
CMM388NTCEnableTimer_mS_M_u32	110205440
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	518740480
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	57339

Name	Input Value
CMMNodeAbsentTimer_mS_M_u32	411511296
CONSANGLECPKSigInvalidCount_Cnt_M_u16	52226
CONSANGLECPKSigValidCount_Cnt_M_u16	19262
CONSANGLECPK_Cnt_M_u16	20233
CONSANGLECPK_HwDeg_M_f32	-314.539215
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	20233
CPKVehicleSpeedMsgTimer_mS_M_u32	3749890560
CPKVehicleSpeedValidCount_Cnt_M_u16	51691
CityParkInputConsistentCount_Cnt_M_u16	38060
CityParkInputInvalidCount_Cnt_M_u16	12105
CityParkInputMsgTimer_mS_M_u32	1524884224
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2884286976
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	52062
ComputerRazGCTSigInvalidTimer_mS_M_u32	3108362752
ComputerRazGCTSigValidCount_Cnt_M_u16	1697
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	46565
DMDFCTCPKSigValidCount_Cnt_M_u16	48954
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	12696
DMDRELAXECPKSigValidCount_Cnt_M_u16	33029
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	23871
DateInvalidTimer_mS_M_u32	1725233664
DiagMuxOnAbsentTimer_mS_M_u32	764250624
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3130862080
ESPNTCEnableTimer_mS_M_u32	3622287872
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	740
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	523809024
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	555
ElecIntTimer_mS_M_u32[1]	5556
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3677940224
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	28972
EtatMTSigValidCount_Cnt_M_u16	29317
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	17332
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	33904
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	45520
ISDAT4V2BSI552MsgTimer_mS_M_u32	166406656
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	16542
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	9790
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	29317
ISDATBSI3F2MsgTimer_mS_M_u32	3453716992
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	43684
ISDATBSI412MsgLenValidCount_Cnt_M_u16	54388
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	28972
ISDATBSI412MsgTimer_mS_M_u32	1349634560
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	54367
ISDATBSI432MsgLenValidCount_Cnt_M_u16	14920
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	44177
ISDATDIRASentFltAcc_Cnt_M_u16	24069
ISDATDIRASentTimer_mS_M_u32	3749890560
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	11735
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	48968
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	7308
ISDYN2CMMMsgTimer_mS_M_u32	844216832
ISDYNAASChkSumInvalidCount_Cnt_M_u16	36268
ISDYNAASChkSumValidCount_Cnt_M_u16	11448
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	60399
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	50971
ISDYNAASMsgLenValidCount_Cnt_M_u16	6304
ISDYNAASMsgTimeValidCount_Cnt_M_u16	36268

Name	Input Value
ISDYNAASMsgTimer_mS_M_u32	1915591168
ISDYNABRChkSumInvalidCount_Cnt_M_u16	26336
ISDYNABRChkSumValidCount_Cnt_M_u16	28436
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	7379
ISDYNABRMsgCountValidCount_Cnt_M_u16	39711
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	15913
ISDYNABRMsgLenValidCount_Cnt_M_u16	56485
ISDYNABRMsgTimeValidCount_Cnt_M_u16	20233
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	626
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1137
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	29317
ISDYNCMM208MsgTimer_mS_M_u32	235633152
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2355
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1243
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	35990
ISDYNCMM388MsgTimer_mS_M_u32	35723776
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	9296
ISDYNVOLChkSumValidCount_Cnt_M_u16	57868
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	12595
ISDYNVOLMsgCountValidCount_Cnt_M_u16	47368
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	58045
ISDYNVOLMsgLenValidCount_Cnt_M_u16	12505
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	57339
ISDYNVOLMsgTimer_mS_M_u32	1356978688
IgnOnTimer_mS_M_u32	2927958528
IgnTimeOff_Sec_M_u32	2096996906
ManVehSpd_Kph_M_f32	582.737976
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	210
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	64
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1448184320
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	227
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3043322368
PrevISDATBSI412MsgDLCError_Cnt_M_u08	7
PrevISDATBSI412MsgRxTime_MSec_M_u32	1251367424
PrevISDATBSI432MsgDLCError_Cnt_M_u08	191
PrevISDATBSI432MsgRxTime_MSec_M_u32	4290492928
PrevISDATDIRAMsgTxTime_MSec_M_u32	3943324160
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	248
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3640830464
PrevISDYNAASMsgDLCError_Cnt_M_u08	107
PrevISDYNAASMsgRxTime_MSec_M_u32	2008013312
PrevISDYNABRMsgDLCError_Cnt_M_u08	134
PrevISDYNABRMsgRxTime_MSec_M_u32	951917056
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	238
PrevISDYNCMM208MsgRxTime_MSec_M_u32	593811968
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	209
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2693184000
PrevISDYNVOLMsgDLCError_Cnt_M_u08	33
PrevISDYNVOLMsgRxTime_MSec_M_u32	3240319488
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1774176768
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	146.682495
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	2153
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	22638
VVHTYPE1Count_Cnt_M_u08	10

Name	Input Value
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	11714
VitesseVehicleBVRampValidCount_Cnt_M_u16	65159
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	34495
VitesseVehicleBVSigValidCount_Cnt_M_u16	13676
VitesseVehicleBV_Kph_M_f32	235.953293
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	35990
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	15610
VitesseVehiculeRoues_Kph_M_f32	563.025391
k_AASNTCEnableTimeout_mS_u16	41640
k_AASNodeAbsentDiag_Cnt_str.Threshold	13826
k_AASNodeAbsentDiag_Cnt_str.PStep	53740
k_AASNodeAbsentDiag_Cnt_str.NStep	13789
k_AASNodeAbsentTimeout_mS_u16	35211
k_AASNodeTimeout_mS_u16	64366
k_ABSNodeTimeout_mS_u16	32730
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	26594
k_ANGLEVOLANTSigValidThresh_Cnt_u16	31243
k_AngleVolantInvalidThresh_Cnt_u16	3578
k_AngleVolantValidThresh_Cnt_u16	12105
k_BSI552MsgTimeout_mS_u16	25001
k_BSINTCEnableTimeout_mS_u16	52887
k_BSINodeAbsentDiag_Cnt_str.Threshold	22452
k_BSINodeAbsentDiag_Cnt_str.PStep	35998
k_BSINodeAbsentDiag_Cnt_str.NStep	13003
k_BSINodeAbsentTimeout_mS_u16	50287
k_BSINodeTimeout_mS_u16	44177
k_BattOvHi_Volt_f32	16.6935997
k_BattOvLo_Volt_f32	28.2775002
k_BattUvHi_Volt_f32	27.4902
k_BattUvLo_Volt_f32	24.3483009
k_CAVNTCEnableTimeout_mS_u16	64207
k_CAVNodeAbsentDiag_Cnt_str.Threshold	48032
k_CAVNodeAbsentDiag_Cnt_str.PStep	56698
k_CAVNodeAbsentDiag_Cnt_str.NStep	22252
k_CAVNodeAbsentTimeout_mS_u16	45918
k_CAVNodeTimeout_mS_u16	12190
k_CMM388MsgTimeout_mS_u16	762
k_CMM388NTCEnableTimeout_mS_u16	38806
k_CMMNTCEnableTimeout_mS_u16	5846
k_CMMNodeAbsentDiag_Cnt_str.Threshold	61149
k_CMMNodeAbsentDiag_Cnt_str.PStep	24651
k_CMMNodeAbsentDiag_Cnt_str.NStep	49886
k_CMMNodeAbsentTimeout_mS_u16	59286
k_CONSANGLECPKMax_HwDeg_f32	432.940308
k_CONSANGLECPKMin_HwDeg_f32	-143.271805
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	61334
k_CONSANGLECPKSigValidThresh_Cnt_u16	57338
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	2308
k_CPKVehicleSpeedValidThresh_Cnt_u16	14447
k_CityParkInputInvalidThresh_Cnt_u16	49398
k_CityParkInputValidThresh_Cnt_u16	38060
k_ComputerRazGCTSigValidThresh_Cnt_u16	25492
k_CptTemporelSigValidThresh_Cnt_u16	46516
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	8489
k_DMDFCTCPKSigValidThresh_Cnt_u16	65445
k_DMDFCTCPKValidCount_Cnt_u16	21461
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	7308
k_DMDRELAXECPKSigValidThresh_Cnt_u16	42273
k_DMDRelaxeConsistentThresh_Cnt_u16	15543
k_DateValidThresh_Cnt_u16	45520
k_DefaultVehSpd_Kph_f32	241.917603
k_DiagMuxOnAbsentTimeout_mS_u16	60431
k_EMNodeTimeout_mS_u16	22175
k_ESPNTCEnableTimeout_mS_u16	31916
k_ESPNodeAbsentDiag_Cnt_str.Threshold	41046
k_ESPNodeAbsentDiag_Cnt_str.PStep	6709
k_ESPNodeAbsentDiag_Cnt_str.NStep	47087

Name	Input Value
k_ESPNodeAbsentTimeout_mS_u16	30046
k_EtatMTSigInvalidThresh_Cnt_u16	25775
k_EtatMTSigValidThresh_Cnt_u16	31267
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	4271
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	26343
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	44037
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	27643
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	3419
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	42248
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	10556
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	27365
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	2243
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	17101
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	49342
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	6734
k_ISDATDIRASentDiag_Cnt_str.Threshold	57722
k_ISDATDIRASentDiag_Cnt_str.PStep	13478
k_ISDATDIRASentDiag_Cnt_str.NStep	62420
k_ISDATDIRASentTimeout_mS_u16	18556
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	39299
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	38967
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	37336
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	51680
k_ISDYNAASChkSumValidThresh_Cnt_u16	4628
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	65491
k_ISDYNAASMsgCountValidThresh_Cnt_u16	48671
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	10308
k_ISDYNAASMsgLenValidThresh_Cnt_u16	43218
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	42451
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	24951
k_ISDYNABRChkSumValidThresh_Cnt_u16	32371
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	28685
k_ISDYNABRMsgCountValidThresh_Cnt_u16	7482
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	33531
k_ISDYNABRMsgLenValidThresh_Cnt_u16	58852
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	14185
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	21965
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	47933
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	26397
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	13030
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	32979
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	57217
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	18087
k_ISDYNVOLChkSumValidThresh_Cnt_u16	31927
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	59937
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	13176
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	31688
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	31265
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	9686
k_IgnOnTimeout_mS_u16	40003
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	28.4708996
k_PowerCutVehSpdLowThresh_Kph_f32	4.16620016
k_PowerCutVehSpdLowTimeout_mS_u16	10292
k_VBattMaxAAS_Volt_f32	28.7266998
k_VBattMaxBSI_Volt_f32	30.7441998
k_VBattMaxCAV_Volt_f32	24.7036991
k_VBattMaxCMM388_Volt_f32	22.9627991
k_VBattMaxCMM_Volt_f32	23.5207005
k_VBattMaxESP_Volt_f32	17.6527996
k_VBattMinAAS_Volt_f32	26.2313004
k_VBattMinBSI_Volt_f32	17.6527996
k_VBattMinCAV_Volt_f32	5.14650011
k_VBattMinCMM388_Volt_f32	26.0568008
k_VBattMinCMM_Volt_f32	24.0466003
k_VBattMinESP_Volt_f32	23.5207005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	63213
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	41262
k_VitesseVehicleBVRampValidThresh_Cnt_u16	37939
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	1292
k_VitesseVehicleBVSigValidThresh_Cnt_u16	1085
k_VitesseVehicleBVSpeedPassThresh_kph_f32	462.770111
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	47632

Name	Input Value
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	51541
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1725233664
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	183
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8855
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	523809024
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	209
target_SrlComInput_Per1_Batt_Volt_f32.value	25.8523998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4228377088
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	233
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.572890401
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2453608960
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	175
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1888107008
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	231
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1688558080
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4136663552
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2924190208
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	332839424
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2939279872
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	85
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	89
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	199
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	211
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	248
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2907273728
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	27
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	45
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	57
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	97
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	188
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1160387072
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3740613120
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1318083072
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	55
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	229
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	247
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	69691904

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	932
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.125765607
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	922010
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	154.845093
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	3923

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	523809024	523809024	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	13826	13826	✔
AASNodeAbsentTimer_mS_M_u32	523809024	523809024	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	38967	38967	✔
AngleVolantMsgTimer_mS_M_u32	523809024	523809024	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	523809024	523809024	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	523809024	523809024	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	523809024	523809024	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	523809024	523809024	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	22452	22452	✔
BSINodeAbsentTimer_mS_M_u32	523809024	523809024	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	523809024	523809024	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	523809024	523809024	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	523809024	523809024	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	523809024	523809024	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	61149	61149	✔
CMMNodeAbsentTimer_mS_M_u32	523809024	523809024	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	20233	20233	✔
CONSANGLECPK_HwDeg_M_f32	-314.539215	-314.539215 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	20233	20233	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3749890560	3749890560	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	51691	51691	✔
CityParkInputConsistentCount_Cnt_M_u16	38060	38060	✔
CityParkInputInvalidCount_Cnt_M_u16	12107	12107	✔
CityParkInputMsgTimer_mS_M_u32	523809024	523809024	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	523809024	523809024	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	523809024	523809024	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	523809024	523809024	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	523809024	523809024	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	523809024	523809024	✔
ESPNTCEnableTimer_mS_M_u32	523809024	523809024	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	523809024	523809024	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔
EffacDefaultDiagTimer_mS_M_u32[1]	523809024	523809024	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	523809024	523809024	✔
ElecIntTimer_mS_M_u32[1]	5556	5556	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	523809024	523809024	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	523809024	523809024	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	523809024	523809024	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	523809024	523809024	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	523809024	523809024	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	523809024	523809024	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	523809024	523809024	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	523809024	523809024	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	523809024	523809024	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	523809024	523809024	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	523809024	523809024	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	523809024	523809024	✔
IgnOnTimer_mS_M_u32	523809024	523809024	✔
IgnTimeOff_Sec_M_u32	2096996906	2096996906	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	72	72	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2453608960	2453608960	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	175	175	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1888107008	1888107008	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	231	231	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1688558080	1688558080	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	121	121	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4136663552	4136663552	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3943324160	3943324160	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	202	202	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	332839424	332839424	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	154	154	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2939279872	2939279872	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	248	248	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2907273728	2907273728	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	229	229	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1160387072	1160387072	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	167	167	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3740613120	3740613120	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	251	251	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1318083072	1318083072	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	69691904	69691904	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	146.682495	146.682495	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	235.953293	235.953293	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	563.025391	563.025391	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	20233	20233	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2096996906	2096996906	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-314.539215	-314.539215 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	241.917603	241.917603	✔

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.55 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	685466880
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	343
AASNodeAbsentTimer_mS_M_u32	3866268928
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	50066
ANGLEVOLANTSigValidCount_Cnt_M_u16	6029
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	52384
AngleVolantMsgTimer_mS_M_u32	685466880
AngleVolantValidCount_Cnt_M_u16	33773
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2390971648
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	864539904
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	4088104192
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3572450560
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	26653
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2052195584
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	32404
CAVNodeAbsentTimer_mS_M_u32	4001805568
CDD_SrlComVehSpd_Kph_G_f32	240.551193
CMM388NTCEnableTimer_mS_M_u32	2396124416
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3703878912
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	10899
CMMNodeAbsentTimer_mS_M_u32	3811656960
CONSANGLECPKSigInvalidCount_Cnt_M_u16	28223
CONSANGLECPKSigValidCount_Cnt_M_u16	44617
CONSANGLECPK_Cnt_M_u16	36584
CONSANGLECPK_HwDeg_M_f32	473.210205
CPKOK_Cnt_M_lgc	1

Name	Input Value
CPKVehicleSpeedInvalidCount_Cnt_M_u16	36584
CPKVehicleSpeedMsgTimer_mS_M_u32	2227070208
CPKVehicleSpeedValidCount_Cnt_M_u16	38060
CityParkInputConsistentCount_Cnt_M_u16	37825
CityParkInputInvalidCount_Cnt_M_u16	51433
CityParkInputMsgTimer_mS_M_u32	2453608960
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3947271424
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	36651
ComputerRazGCTSigInvalidTimer_mS_M_u32	2545235200
ComputerRazGCTSigValidCount_Cnt_M_u16	20962
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	42261
DMDFCTCPKSigValidCount_Cnt_M_u16	42712
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	26236
DMDRELAXECPKSigValidCount_Cnt_M_u16	62967
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	61064
DateInvalidTimer_mS_M_u32	864539904
DiagMuxOnAbsentTimer_mS_M_u32	899556608
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3572450560
ESPNTCEnableTimer_mS_M_u32	2605683968
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	12186
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	89
EffacDefaultDiagTimer_mS_M_u32[1]	1643687936
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	963
ElecIntTimer_mS_M_u32[1]	7853
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2451309824
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	52224
EtatMTSigValidCount_Cnt_M_u16	62902
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	20265
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	19123
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	42774
ISDAT4V2BSI552MsgTimer_mS_M_u32	2667922688
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	23340
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	63498
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	62902
ISDATBSI3F2MsgTimer_mS_M_u32	213132544
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1561
ISDATBSI412MsgLenValidCount_Cnt_M_u16	38504
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	52224
ISDATBSI412MsgTimer_mS_M_u32	2918278400
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	56679
ISDATBSI432MsgLenValidCount_Cnt_M_u16	6510
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	49681
ISDATDIRASentFltAcc_Cnt_M_u16	32181
ISDATDIRASentTimer_mS_M_u32	2227070208
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	43646
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	33773
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52512
ISDYN2CMMMsgTimer_mS_M_u32	3021051136
ISDYNAASChkSumInvalidCount_Cnt_M_u16	65
ISDYNAASChkSumValidCount_Cnt_M_u16	8412
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	23032
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	6771
ISDYNAASMsgLenValidCount_Cnt_M_u16	933
ISDYNAASMsgTimeValidCount_Cnt_M_u16	65
ISDYNAASMsgTimer_mS_M_u32	3153982720
ISDYNABRChkSumInvalidCount_Cnt_M_u16	39974
ISDYNABRChkSumValidCount_Cnt_M_u16	8520
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	44748
ISDYNABRMsgCountValidCount_Cnt_M_u16	12711
ISDYNABRMsgCount_Cnt_M_u08	6

Name	Input Value
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	29642
ISDYNABRMsgLenValidCount_Cnt_M_u16	22036
ISDYNABRMsgTimeValidCount_Cnt_M_u16	36584
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	627
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1139
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	62902
ISDYNCMM208MsgTimer_mS_M_u32	937710848
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2359
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1245
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	54275
ISDYNCMM388MsgTimer_mS_M_u32	975402240
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	7509
ISDYNVOLChkSumValidCount_Cnt_M_u16	41439
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	60203
ISDYNVOLMsgCountValidCount_Cnt_M_u16	29038
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	13327
ISDYNVOLMsgLenValidCount_Cnt_M_u16	34682
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	10899
ISDYNVOLMsgTimer_mS_M_u32	1088500992
IgnOnTimer_mS_M_u32	3304551680
IgnTimeOff_Sec_M_u32	3012796674
ManVehSpd_Kph_M_f32	393.291199
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	212
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	253
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3411158272
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	146
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1435927808
PrevISDATBSI412MsgDLCError_Cnt_M_u08	165
PrevISDATBSI412MsgRxTime_MSec_M_u32	3317937408
PrevISDATBSI432MsgDLCError_Cnt_M_u08	58
PrevISDATBSI432MsgRxTime_MSec_M_u32	1943246080
PrevISDATDIRAMsgTxTime_MSec_M_u32	3026695424
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	24
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4022256896
PrevISDYNAASMsgDLCError_Cnt_M_u08	229
PrevISDYNAASMsgRxTime_MSec_M_u32	2222404864
PrevISDYNABRMsgDLCError_Cnt_M_u08	99
PrevISDYNABRMsgRxTime_MSec_M_u32	105870592
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	206
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2505585920
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	187
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2104661248
PrevISDYNVOLMsgDLCError_Cnt_M_u08	7
PrevISDYNVOLMsgRxTime_MSec_M_u32	3592205568
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	436692224
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	312.503693
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	3721
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	64571
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0

Name	Input Value
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	17022
VitesseVehicleBVRampValidCount_Cnt_M_u16	44528
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	49927
VitesseVehicleBVSigValidCount_Cnt_M_u16	13506
VitesseVehicleBV_Kph_M_f32	349.786804
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	54275
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	8342
VitesseVehiculeRoues_Kph_M_f32	521.011292
k_AASNTCEnableTimeout_mS_u16	53259
k_AASNodeAbsentDiag_Cnt_str.Threshold	19786
k_AASNodeAbsentDiag_Cnt_str.PStep	65156
k_AASNodeAbsentDiag_Cnt_str.NStep	2025
k_AASNodeAbsentTimeout_mS_u16	61732
k_AASNodeTimeout_mS_u16	4923
k_ABSNodeTimeout_mS_u16	23350
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	61150
k_ANGLEVOLANTSigValidThresh_Cnt_u16	9765
k_AngleVolantInvalidThresh_Cnt_u16	58968
k_AngleVolantValidThresh_Cnt_u16	51433
k_BSI552MsgTimeout_mS_u16	11913
k_BSINTCEnableTimeout_mS_u16	52927
k_BSINodeAbsentDiag_Cnt_str.Threshold	22492
k_BSINodeAbsentDiag_Cnt_str.PStep	35981
k_BSINodeAbsentDiag_Cnt_str.NStep	13026
k_BSINodeAbsentTimeout_mS_u16	10232
k_BSINodeTimeout_mS_u16	49681
k_BattOvHi_Volt_f32	1.52890003
k_BattOvLo_Volt_f32	18.4155998
k_BattUvHi_Volt_f32	20.4918003
k_BattUvLo_Volt_f32	23.5380001
k_CAVNTCEnableTimeout_mS_u16	65111
k_CAVNodeAbsentDiag_Cnt_str.Threshold	21256
k_CAVNodeAbsentDiag_Cnt_str.PStep	46515
k_CAVNodeAbsentDiag_Cnt_str.NStep	59349
k_CAVNodeAbsentTimeout_mS_u16	8618
k_CAVNodeTimeout_mS_u16	45931
k_CMM388MsgTimeout_mS_u16	22615
k_CMM388NTCEnableTimeout_mS_u16	2691
k_CMMNTCEnableTimeout_mS_u16	47236
k_CMMNodeAbsentDiag_Cnt_str.Threshold	49818
k_CMMNodeAbsentDiag_Cnt_str.PStep	21576
k_CMMNodeAbsentDiag_Cnt_str.NStep	47814
k_CMMNodeAbsentTimeout_mS_u16	37058
k_CONSANGLECPKMax_HwDeg_f32	157.245102
k_CONSANGLECPKMin_HwDeg_f32	-459.982788
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	43779
k_CONSANGLECPKSigValidThresh_Cnt_u16	14230
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	49785
k_CPKVehicleSpeedValidThresh_Cnt_u16	18616
k_CityParkInputInvalidThresh_Cnt_u16	26084
k_CityParkInputValidThresh_Cnt_u16	37825
k_ComputerRazGCTSigValidThresh_Cnt_u16	19018
k_CptTemporelSigValidThresh_Cnt_u16	41384
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	51914
k_DMDFCTCPKSigValidThresh_Cnt_u16	60692
k_DMDFCTCPKValidCount_Cnt_u16	13253
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	52512
k_DMDRELAXECPKSigValidThresh_Cnt_u16	20771
k_DMDRelaxeConsistentThresh_Cnt_u16	25185
k_DateValidThresh_Cnt_u16	42774
k_DefaultVehSpd_Kph_f32	150.023499
k_DiagMuxOnAbsentTimeout_mS_u16	20438
k_EMNodeTimeout_mS_u16	33384
k_ESPNTCEnableTimeout_mS_u16	32192
k_ESPNodeAbsentDiag_Cnt_str.Threshold	16272
k_ESPNodeAbsentDiag_Cnt_str.PStep	3306
k_ESPNodeAbsentDiag_Cnt_str.NStep	28402
k_ESPNodeAbsentTimeout_mS_u16	1898
k_EtatMTSigInvalidThresh_Cnt_u16	40633
k_EtatMTSigValidThresh_Cnt_u16	64539
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	6008
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	49807
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	61878

Name	Input Value
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	36117
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	63155
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	42733
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	37584
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	15255
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	53307
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	50076
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	55179
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	12314
k_ISDATDIRASentDiag_Cnt_str.Threshold	53243
k_ISDATDIRASentDiag_Cnt_str.PStep	43693
k_ISDATDIRASentDiag_Cnt_str.NStep	47006
k_ISDATDIRASentTimeout_mS_u16	26450
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	50811
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	52384
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	60988
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	29478
k_ISDYNAASChkSumValidThresh_Cnt_u16	14408
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	1484
k_ISDYNAASMsgCountValidThresh_Cnt_u16	51367
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	59386
k_ISDYNAASMsgLenValidThresh_Cnt_u16	39695
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	49869
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	49632
k_ISDYNABRChkSumValidThresh_Cnt_u16	10410
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	48925
k_ISDYNABRMsgCountValidThresh_Cnt_u16	13656
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	16787
k_ISDYNABRMsgLenValidThresh_Cnt_u16	34458
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	25291
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	46685
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	30798
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	19502
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	6802
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	44685
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	38977
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	65040
k_ISDYNVOLChkSumValidThresh_Cnt_u16	27039
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	44515
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	25628
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	7212
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	20194
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	58116
k_IgnOnTimeout_mS_u16	27964
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	212.8638
k_PowerCutVehSpdLowThresh_Kph_f32	101.777901
k_PowerCutVehSpdLowTimeout_mS_u16	28519
k_VBattMaxAAS_Volt_f32	21.8146
k_VBattMaxBSI_Volt_f32	28.4594002
k_VBattMaxCAV_Volt_f32	26.5035992
k_VBattMaxCMM388_Volt_f32	23.7985992
k_VBattMaxCMM_Volt_f32	5.0770998
k_VBattMaxESP_Volt_f32	7.05089998
k_VBattMinAAS_Volt_f32	8.38560009
k_VBattMinBSI_Volt_f32	7.05089998
k_VBattMinCAV_Volt_f32	16.8227997
k_VBattMinCMM388_Volt_f32	8.03919983
k_VBattMinCMM_Volt_f32	7.33430004
k_VBattMinESP_Volt_f32	5.0770998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	54845
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	42300
k_VitesseVehicleBVRampValidThresh_Cnt_u16	49707
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	14559
k_VitesseVehicleBVSigValidThresh_Cnt_u16	51470
k_VitesseVehicleBVSpeedPassThresh_kph_f32	580.136414
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	21908
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	1414
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	864539904
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	209
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0

Name	Input Value
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	59986
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1643687936
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	187
target_SrlComInput_Per1_Batt_Volt_f32.value	1.28989995
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	732890368
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	84
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.641094625
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2177463552
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	13
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2070418688
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1939256576
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	87
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3528807680
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4288935168
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1669502208
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1710306560
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	22
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	47
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	70
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	77
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	148
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3525989632
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	88
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	123
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	172
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	180
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	197
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3574101248
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2619806976
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	567653632
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	57
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	58
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	106
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	117
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	225
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4048585984
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1411
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.652965486
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	924351
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	92.9909973
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	8651

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1643687936	1643687936	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	19786	19786	✔
AASNodeAbsentTimer_mS_M_u32	1643687936	1643687936	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	52386	52386	✔
AngleVolantMsgTimer_mS_M_u32	1643687936	1643687936	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1643687936	1643687936	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1643687936	1643687936	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1643687936	1643687936	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1643687936	1643687936	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	22492	22492	✔
BSINodeAbsentTimer_mS_M_u32	1643687936	1643687936	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1643687936	1643687936	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1643687936	1643687936	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1643687936	1643687936	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1643687936	1643687936	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	49818	49818	✔
CMMNodeAbsentTimer_mS_M_u32	1643687936	1643687936	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	36584	36584	✔
CONSANGLECPK_HwDeg_M_f32	473.210205	473.210205 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	36584	36584	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2227070208	2227070208	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	38060	38060	✔
CityParkInputConsistentCount_Cnt_M_u16	37825	37825	✔
CityParkInputInvalidCount_Cnt_M_u16	51433	51433	✔
CityParkInputMsgTimer_mS_M_u32	1643687936	1643687936	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1643687936	1643687936	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1643687936	1643687936	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1643687936	1643687936	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1643687936	1643687936	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1643687936	1643687936	✔
ESPNTCEnableTimer_mS_M_u32	1643687936	1643687936	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1643687936	1643687936	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	89	89	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1643687936	1643687936	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1643687936	1643687936	✔
ElecIntTimer_mS_M_u32[1]	7853	7853	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1643687936	1643687936	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1643687936	1643687936	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1643687936	1643687936	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1643687936	1643687936	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1643687936	1643687936	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1643687936	1643687936	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1643687936	1643687936	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1643687936	1643687936	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1643687936	1643687936	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1643687936	1643687936	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1643687936	1643687936	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1643687936	1643687936	✔
IgnOnTimer_mS_M_u32	1643687936	1643687936	✔
IgnTimeOff_Sec_M_u32	3012796674	3012796674	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	75	75	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2177463552	2177463552	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	13	13	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2070418688	2070418688	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	153	153	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1939256576	1939256576	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	87	87	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3528807680	3528807680	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3026695424	3026695424	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	12	12	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1669502208	1669502208	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	210	210	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1710306560	1710306560	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	253	253	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3525989632	3525989632	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3574101248	3574101248	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	143	143	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2619806976	2619806976	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	200	200	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	567653632	567653632	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4048585984	4048585984	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	312.503693	312.503693	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	349.786804	349.786804	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	521.011292	521.011292	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	36584	36584	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3012796674	3012796674	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	473.210205	473.210205 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	150.023499	150.023499	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.56 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2353858304
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	48301
AASNodeAbsentTimer_mS_M_u32	2719856384
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	21692
ANGLEVOLANTSigValidCount_Cnt_M_u16	8204
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	35390
AngleVolantMsgTimer_mS_M_u32	2353858304
AngleVolantValidCount_Cnt_M_u16	7408
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1488221952
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	4192007936
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	983443200
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2885674752
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	38303
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2591598336
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	37066
CAVNodeAbsentTimer_mS_M_u32	399693568
CDD_SrlComVehSpd_Kph_G_f32	55.1557999
CMM388NTCEnableTimer_mS_M_u32	1282938624
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2818627328
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	38474
CMMNodeAbsentTimer_mS_M_u32	4233225984
CONSANGLECPKSigInvalidCount_Cnt_M_u16	33486
CONSANGLECPKSigValidCount_Cnt_M_u16	6830
CONSANGLECPK_Cnt_M_u16	38981
CONSANGLECPK_HwDeg_M_f32	200.486206
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	38981
CPKVehicleSpeedMsgTimer_mS_M_u32	4282910464
CPKVehicleSpeedValidCount_Cnt_M_u16	32630
CityParkInputConsistentCount_Cnt_M_u16	52068

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	974
CityParkInputMsgTimer_mS_M_u32	1649828864
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3985749760
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	55585
ComputerRazGCTSigInvalidTimer_mS_M_u32	4000667392
ComputerRazGCTSigValidCount_Cnt_M_u16	57997
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	41306
DMDFCTCPKSigValidCount_Cnt_M_u16	51378
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	7926
DMDRELAXECPKSigValidCount_Cnt_M_u16	454
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	44383
DateInvalidTimer_mS_M_u32	4192007936
DiagMuxOnAbsentTimer_mS_M_u32	489015040
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2885674752
ESPNTCEnableTimer_mS_M_u32	3319969536
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	31494
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	45
EffacDefaultDiagTimer_mS_M_u32[1]	98
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	89
ElecIntTimer_mS_M_u32[1]	899
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2157094656
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	15640
EtatMTSigValidCount_Cnt_M_u16	60420
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	31496
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	43624
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	64224
ISDAT4V2BSI552MsgTimer_mS_M_u32	3066423040
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	6307
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	5111
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	60420
ISDATBSI3F2MsgTimer_mS_M_u32	2632697600
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	31994
ISDATBSI412MsgLenValidCount_Cnt_M_u16	34622
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	15640
ISDATBSI412MsgTimer_mS_M_u32	705890048
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	65470
ISDATBSI432MsgLenValidCount_Cnt_M_u16	54138
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	47151
ISDATDIRASentFltAcc_Cnt_M_u16	61683
ISDATDIRASentTimer_mS_M_u32	4282910464
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	32907
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	7408
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	33213
ISDYN2CMMMsgTimer_mS_M_u32	1958000384
ISDYNAASChkSumInvalidCount_Cnt_M_u16	49895
ISDYNAASChkSumValidCount_Cnt_M_u16	49111
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	6995
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	41889
ISDYNAASMsgLenValidCount_Cnt_M_u16	28137
ISDYNAASMsgTimeValidCount_Cnt_M_u16	49895
ISDYNAASMsgTimer_mS_M_u32	3271825152
ISDYNABRChkSumInvalidCount_Cnt_M_u16	1262
ISDYNABRChkSumValidCount_Cnt_M_u16	51879
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	24010
ISDYNABRMsgCountValidCount_Cnt_M_u16	52986
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	11441
ISDYNABRMsgLenValidCount_Cnt_M_u16	30929
ISDYNABRMsgTimeValidCount_Cnt_M_u16	38981
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	629

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1143
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	60420
ISDYNCMM208MsgTimer_mS_M_u32	3038607104
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2367
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1249
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	56758
ISDYNCMM388MsgTimer_mS_M_u32	1851102976
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	39572
ISDYNVOLChkSumValidCount_Cnt_M_u16	39668
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	2080
ISDYNVOLMsgCountValidCount_Cnt_M_u16	55288
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	11043
ISDYNVOLMsgLenValidCount_Cnt_M_u16	29027
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	38474
ISDYNVOLMsgTimer_mS_M_u32	3238090496
IgnOnTimer_mS_M_u32	1875482368
IgnTimeOff_Sec_M_u32	2997566615
ManVehSpd_Kph_M_f32	638.874207
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	216
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	27
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2155464448
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	69
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	601958144
PrevISDATBSI412MsgDLCError_Cnt_M_u08	187
PrevISDATBSI412MsgRxTime_MSec_M_u32	0
PrevISDATBSI432MsgDLCError_Cnt_M_u08	76
PrevISDATBSI432MsgRxTime_MSec_M_u32	42383104
PrevISDATDIRAMsgTxTime_MSec_M_u32	1958467328
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	205
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3914032896
PrevISDYNAASMsgDLCError_Cnt_M_u08	183
PrevISDYNAASMsgRxTime_MSec_M_u32	289888000
PrevISDYNABRMsgDLCError_Cnt_M_u08	212
PrevISDYNABRMsgRxTime_MSec_M_u32	2078381824
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	211
PrevISDYNCMM208MsgRxTime_MSec_M_u32	288380672
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	212
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4045256448
PrevISDYNVOLMsgDLCError_Cnt_M_u08	169
PrevISDYNVOLMsgRxTime_MSec_M_u32	739825408
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3872982784
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	507.876709
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	10343
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	6959
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	33796
VitesseVehicleBVRampValidCount_Cnt_M_u16	57996
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	55257
VitesseVehicleBVSigValidCount_Cnt_M_u16	44777

Name	Input Value
VitesseVehicleBV_Kph_M_f32	428.085114
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	56758
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	9822
VitesseVehiculeRoues_Kph_M_f32	397.478088
k_AASNTCEnableTimeout_mS_u16	6784
k_AASNodeAbsentDiag_Cnt_str.Threshold	46346
k_AASNodeAbsentDiag_Cnt_str.PStep	27015
k_AASNodeAbsentDiag_Cnt_str.NStep	39942
k_AASNodeAbsentTimeout_mS_u16	19423
k_AASNodeTimeout_mS_u16	59951
k_ABSNodeTimeout_mS_u16	28803
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	62701
k_ANGLEVOLANTSigValidThresh_Cnt_u16	40425
k_AngleVolantInvalidThresh_Cnt_u16	6068
k_AngleVolantValidThresh_Cnt_u16	974
k_BSI552MsgTimeout_mS_u16	23529
k_BSINTCEnableTimeout_mS_u16	15318
k_BSINodeAbsentDiag_Cnt_str.Threshold	22572
k_BSINodeAbsentDiag_Cnt_str.PStep	35947
k_BSINodeAbsentDiag_Cnt_str.NStep	13072
k_BSINodeAbsentTimeout_mS_u16	32854
k_BSINodeTimeout_mS_u16	47151
k_BattOvHi_Volt_f32	27.8628006
k_BattOvLo_Volt_f32	4.33059978
k_BattUvHi_Volt_f32	17.875
k_BattUvLo_Volt_f32	27.9619007
k_CAVNTCEnableTimeout_mS_u16	38060
k_CAVNodeAbsentDiag_Cnt_str.Threshold	8046
k_CAVNodeAbsentDiag_Cnt_str.PStep	52064
k_CAVNodeAbsentDiag_Cnt_str.NStep	54012
k_CAVNodeAbsentTimeout_mS_u16	15504
k_CAVNodeTimeout_mS_u16	53594
k_CMM388MsgTimeout_mS_u16	52141
k_CMM388NTCEnableTimeout_mS_u16	61241
k_CMMNTCEnableTimeout_mS_u16	8379
k_CMMNodeAbsentDiag_Cnt_str.Threshold	37535
k_CMMNodeAbsentDiag_Cnt_str.PStep	64810
k_CMMNodeAbsentDiag_Cnt_str.NStep	46988
k_CMMNodeAbsentTimeout_mS_u16	63466
k_CONSANGLECPKMax_HwDeg_f32	172.280106
k_CONSANGLECPKMin_HwDeg_f32	-47.327301
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	27830
k_CONSANGLECPKSigValidThresh_Cnt_u16	62814
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	17245
k_CPKVehicleSpeedValidThresh_Cnt_u16	27793
k_CityParkInputInvalidThresh_Cnt_u16	19612
k_CityParkInputValidThresh_Cnt_u16	52068
k_ComputerRazGCTSigValidThresh_Cnt_u16	45233
k_CptTemporelSigValidThresh_Cnt_u16	14981
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	15281
k_DMDFCTCPKSigValidThresh_Cnt_u16	51153
k_DMDFCTCPKValidCount_Cnt_u16	65159
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	33213
k_DMDRELAXECPKSigValidThresh_Cnt_u16	15701
k_DMDRelaxeConsistentThresh_Cnt_u16	2179
k_DateValidThresh_Cnt_u16	64224
k_DefaultVehSpd_Kph_f32	179.799393
k_DiagMuxOnAbsentTimeout_mS_u16	4259
k_EMNodeTimeout_mS_u16	57407
k_ESPNTCEnableTimeout_mS_u16	26966
k_ESPNodeAbsentDiag_Cnt_str.Threshold	45056
k_ESPNodeAbsentDiag_Cnt_str.PStep	11673
k_ESPNodeAbsentDiag_Cnt_str.NStep	59864
k_ESPNodeAbsentTimeout_mS_u16	25554
k_EtatMTSigInvalidThresh_Cnt_u16	54297
k_EtatMTSigValidThresh_Cnt_u16	13330
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	55380
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	5025
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	41217
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	33236
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	45032
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	17518
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	2159

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	44779
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	43314
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	37529
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	15742
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	30981
k_ISDATDIRASentDiag_Cnt_str.Threshold	18682
k_ISDATDIRASentDiag_Cnt_str.PStep	1323
k_ISDATDIRASentDiag_Cnt_str.NStep	54798
k_ISDATDIRASentTimeout_mS_u16	2426
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	10862
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	35390
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	48562
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	37870
k_ISDYNAASChkSumValidThresh_Cnt_u16	39335
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	27850
k_ISDYNAASMsgCountValidThresh_Cnt_u16	7674
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	53090
k_ISDYNAASMsgLenValidThresh_Cnt_u16	53411
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	24529
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	56183
k_ISDYNABRChkSumValidThresh_Cnt_u16	53271
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	42143
k_ISDYNABRMsgCountValidThresh_Cnt_u16	42031
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	25930
k_ISDYNABRMsgLenValidThresh_Cnt_u16	35334
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	62778
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	11995
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	2263
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	41658
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	25532
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	28428
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	3558
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	36009
k_ISDYNVOLChkSumValidThresh_Cnt_u16	19501
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	37783
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	17435
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	61092
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	61072
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	50750
k_IgnOnTimeout_mS_u16	21813
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	78.3623962
k_PowerCutVehSpdLowThresh_Kph_f32	118.588997
k_PowerCutVehSpdLowTimeout_mS_u16	5308
k_VBattMaxAAS_Volt_f32	23.2863007
k_VBattMaxBSI_Volt_f32	14.6400995
k_VBattMaxCAV_Volt_f32	31.6487999
k_VBattMaxCMM388_Volt_f32	29.6049995
k_VBattMaxCMM_Volt_f32	16.2499008
k_VBattMaxESP_Volt_f32	16.6767006
k_VBattMinAAS_Volt_f32	20.9540005
k_VBattMinBSI_Volt_f32	16.6767006
k_VBattMinCAV_Volt_f32	1.1767
k_VBattMinCMM388_Volt_f32	2.17420006
k_VBattMinCMM_Volt_f32	6.59420013
k_VBattMinESP_Volt_f32	16.2499008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	34880
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	18100
k_VitesseVehicleBVRampValidThresh_Cnt_u16	38688
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	59892
k_VitesseVehicleBVSigValidThresh_Cnt_u16	62233
k_VitesseVehicleBVSpeedPassThresh_kph_f32	518.110107
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	8138
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	59090
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	4192007936
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	250
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	3177
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3570182656
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	212
target_SrlComInput_Per1_Batt_Volt_f32.value	18.0578003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2663229184
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	19
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.06238636
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	54
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1663801088
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2596222720
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	207
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1164105472
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	186021632
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2480543488
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	237
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2276308736
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	150
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2391889664
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	34
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	107
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	178
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2442360576
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	153
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	161
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	207
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	230
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3898775296
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1500919552
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	18
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4254717696
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	71
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	188
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	761997056
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1122
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.798998892
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	722969
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	82.0072021

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	42425		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	3570182656	3570182656	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	46346	46346	✔
AASNodeAbsentTimer_mS_M_u32	3570182656	3570182656	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3570182656	3570182656	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3570182656	3570182656	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3570182656	3570182656	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3570182656	3570182656	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3570182656	3570182656	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	22572	22572	✔
BSINodeAbsentTimer_mS_M_u32	3570182656	3570182656	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3570182656	3570182656	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3570182656	3570182656	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3570182656	3570182656	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3570182656	3570182656	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	37535	37535	✔
CMMNodeAbsentTimer_mS_M_u32	3570182656	3570182656	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	38981	38981	✔
CONSANGLECPK_HwDeg_M_f32	200.486206	200.486206 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3570182656	3570182656	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3570182656	3570182656	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3570182656	3570182656	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3570182656	3570182656	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3570182656	3570182656	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3570182656	3570182656	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3570182656	3570182656	✔
ESPNTCEnableTimer_mS_M_u32	3570182656	3570182656	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3570182656	3570182656	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3570182656	3570182656	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	98	98	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3570182656	3570182656	✔
ElecIntTimer_mS_M_u32[1]	899	899	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3570182656	3570182656	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3570182656	3570182656	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3570182656	3570182656	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3570182656	3570182656	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3570182656	3570182656	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3570182656	3570182656	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3570182656	3570182656	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3570182656	3570182656	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3570182656	3570182656	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3570182656	3570182656	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3570182656	3570182656	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3570182656	3570182656	✔
IgnOnTimer_mS_M_u32	1875482368	1875482368	✔
IgnTimeOff_Sec_M_u32	2997566615	2997566615	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	54	54	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1663801088	1663801088	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	51	51	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2596222720	2596222720	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	207	207	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1164105472	1164105472	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	178	178	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	186021632	186021632	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1958467328	1958467328	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	237	237	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2276308736	2276308736	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	150	150	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2391889664	2391889664	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	12	12	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2442360576	2442360576	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3898775296	3898775296	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	93	93	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1500919552	1500919552	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	18	18	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4254717696	4254717696	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	761997056	761997056	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	507.876709	507.876709	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	428.085114	428.085114	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	397.478088	397.478088	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	38981	38981	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2997566615	2997566615	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	200.486206	200.486206 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	179.799393	179.799393	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.57 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2140384768
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	4210
AASNodeAbsentTimer_mS_M_u32	2632031744
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	41542
ANGLEVOLANTSigValidCount_Cnt_M_u16	64790
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	11199
AngleVolantMsgTimer_mS_M_u32	2140384768
AngleVolantValidCount_Cnt_M_u16	49706
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1142775296
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2728648192
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2703248896
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	66784768
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	11165
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	194039296
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	61594
CAVNodeAbsentTimer_mS_M_u32	4165090816
CDD_SrlComVehSpd_Kph_G_f32	249.179504
CMM388NTCEnableTimer_mS_M_u32	2136112640
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2142780928
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	27100
CMMNodeAbsentTimer_mS_M_u32	3674541568
CONSANGLECPKSigInvalidCount_Cnt_M_u16	54030
CONSANGLECPKSigValidCount_Cnt_M_u16	2093
CONSANGLECPK_Cnt_M_u16	43880
CONSANGLECPK_HwDeg_M_f32	502.567993
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43880
CPKVehicleSpeedMsgTimer_mS_M_u32	3533876736
CPKVehicleSpeedValidCount_Cnt_M_u16	22752

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	34510
CityParkInputInvalidCount_Cnt_M_u16	22159
CityParkInputMsgTimer_mS_M_u32	1663801088
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2324012544
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	35606
ComputerRazGCTSigInvalidTimer_mS_M_u32	509263360
ComputerRazGCTSigValidCount_Cnt_M_u16	9555
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	44523
DMDFCTCPKSigValidCount_Cnt_M_u16	5282
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	43928
DMDRELAXECPKSigValidCount_Cnt_M_u16	49128
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	55131
DateInvalidTimer_mS_M_u32	2728648192
DiagMuxOnAbsentTimer_mS_M_u32	537488896
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	66784768
ESPNTCEnableTimer_mS_M_u32	2240978432
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	10343
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	66
EffacDefaultDiagTimer_mS_M_u32[1]	78
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	749
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1094897152
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	32369
EtatMTSigValidCount_Cnt_M_u16	40557
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	21088
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	49407
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	46616
ISDAT4V2BSI552MsgTimer_mS_M_u32	2074676736
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	12113
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	2580
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	40557
ISDATBSI3F2MsgTimer_mS_M_u32	951545344
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	28491
ISDATBSI412MsgLenValidCount_Cnt_M_u16	56638
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	32369
ISDATBSI412MsgTimer_mS_M_u32	1044491776
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	64896
ISDATBSI432MsgLenValidCount_Cnt_M_u16	61195
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	20075
ISDATDIRASentFltAcc_Cnt_M_u16	46111
ISDATDIRASentTimer_mS_M_u32	3533876736
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	35478
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	49706
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	22722
ISDYN2CMMMsgTimer_mS_M_u32	1092394496
ISDYNAASChkSumInvalidCount_Cnt_M_u16	26052
ISDYNAASChkSumValidCount_Cnt_M_u16	43955
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	4865
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	54293
ISDYNAASMsgLenValidCount_Cnt_M_u16	4605
ISDYNAASMsgTimeValidCount_Cnt_M_u16	26052
ISDYNAASMsgTimer_mS_M_u32	1269726720
ISDYNABRChkSumInvalidCount_Cnt_M_u16	29998
ISDYNABRChkSumValidCount_Cnt_M_u16	32965
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	57627
ISDYNABRMsgCountValidCount_Cnt_M_u16	51786
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	8549
ISDYNABRMsgLenValidCount_Cnt_M_u16	14788
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43880

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	630
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1145
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	40557
ISDYNCMM208MsgTimer_mS_M_u32	316825088
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2371
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1251
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	6104
ISDYNCMM388MsgTimer_mS_M_u32	1874460160
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	9148
ISDYNVOLChkSumValidCount_Cnt_M_u16	8027
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	4505
ISDYNVOLMsgCountValidCount_Cnt_M_u16	32464
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	52240
ISDYNVOLMsgLenValidCount_Cnt_M_u16	30224
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	27100
ISDYNVOLMsgTimer_mS_M_u32	3602300416
IgnOnTimer_mS_M_u32	996015616
IgnTimeOff_Sec_M_u32	2690024877
ManVehSpd_Kph_M_f32	340.775604
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	218
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	51
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1175285248
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	85
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2975288832
PrevISDATBSI412MsgDLCError_Cnt_M_u08	184
PrevISDATBSI412MsgRxTime_MSec_M_u32	4294967295
PrevISDATBSI432MsgDLCError_Cnt_M_u08	9
PrevISDATBSI432MsgRxTime_MSec_M_u32	1604754944
PrevISDATDIRAMsgTxTime_MSec_M_u32	3313974784
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	246
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3659042304
PrevISDYNAASMsgDLCError_Cnt_M_u08	48
PrevISDYNAASMsgRxTime_MSec_M_u32	2112142848
PrevISDYNABRMsgDLCError_Cnt_M_u08	212
PrevISDYNABRMsgRxTime_MSec_M_u32	1997929984
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	248
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1646902784
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	250
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2950798848
PrevISDYNVOLMsgDLCError_Cnt_M_u08	59
PrevISDYNVOLMsgRxTime_MSec_M_u32	1399864832
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2683284992
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	167.802994
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	56771
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	41515
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	32492
VitesseVehicleBVRampValidCount_Cnt_M_u16	20
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	52463

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	1151
VitesseVehicleBV_Kph_M_f32	45.6781006
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	6104
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	23199
VitesseVehiculeRoues_Kph_M_f32	525.918884
k_AASNTCEnableTimeout_mS_u16	53431
k_AASNodeAbsentDiag_Cnt_str.Threshold	15384
k_AASNodeAbsentDiag_Cnt_str.PStep	47223
k_AASNodeAbsentDiag_Cnt_str.NStep	9235
k_AASNodeAbsentTimeout_mS_u16	45405
k_AASNodeTimeout_mS_u16	13611
k_ABSNodeTimeout_mS_u16	9328
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	39411
k_ANGLEVOLANTSigValidThresh_Cnt_u16	3006
k_AngleVolantInvalidThresh_Cnt_u16	35421
k_AngleVolantValidThresh_Cnt_u16	22159
k_BSI552MsgTimeout_mS_u16	42494
k_BSINTCEnableTimeout_mS_u16	43320
k_BSINodeAbsentDiag_Cnt_str.Threshold	22612
k_BSINodeAbsentDiag_Cnt_str.PStep	35930
k_BSINodeAbsentDiag_Cnt_str.NStep	13095
k_BSINodeAbsentTimeout_mS_u16	43383
k_BSINodeTimeout_mS_u16	20075
k_BattOvHi_Volt_f32	2.83240008
k_BattOvLo_Volt_f32	11.6981001
k_BattUvHi_Volt_f32	11.2772999
k_BattUvLo_Volt_f32	23.2602005
k_CAVNTCEnableTimeout_mS_u16	39925
k_CAVNodeAbsentDiag_Cnt_str.Threshold	15076
k_CAVNodeAbsentDiag_Cnt_str.PStep	47396
k_CAVNodeAbsentDiag_Cnt_str.NStep	35754
k_CAVNodeAbsentTimeout_mS_u16	34120
k_CAVNodeTimeout_mS_u16	5994
k_CMM388MsgTimeout_mS_u16	58226
k_CMM388NTCEnableTimeout_mS_u16	43214
k_CMMNTCEnableTimeout_mS_u16	30473
k_CMMNodeAbsentDiag_Cnt_str.Threshold	18104
k_CMMNodeAbsentDiag_Cnt_str.PStep	26096
k_CMMNodeAbsentDiag_Cnt_str.NStep	55009
k_CMMNodeAbsentTimeout_mS_u16	5627
k_CONSANGLECPKMax_HwDeg_f32	418.161804
k_CONSANGLECPKMin_HwDeg_f32	-295.681091
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	27352
k_CONSANGLECPKSigValidThresh_Cnt_u16	60831
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	24993
k_CPKVehicleSpeedValidThresh_Cnt_u16	48262
k_CityParkInputInvalidThresh_Cnt_u16	54820
k_CityParkInputValidThresh_Cnt_u16	34510
k_ComputerRazGCTSigValidThresh_Cnt_u16	7975
k_CptTemporelSigValidThresh_Cnt_u16	20074
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	62565
k_DMDFCTCPKSigValidThresh_Cnt_u16	19652
k_DMDFCTCPKValidCount_Cnt_u16	37093
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	22722
k_DMDRELAXECPKSigValidThresh_Cnt_u16	697
k_DMDRelaxeConsistentThresh_Cnt_u16	55599
k_DateValidThresh_Cnt_u16	46616
k_DefaultVehSpd_Kph_f32	15.5812998
k_DiagMuxOnAbsentTimeout_mS_u16	14926
k_EMNodeTimeout_mS_u16	48827
k_ESPNTCEnableTimeout_mS_u16	38646
k_ESPNodeAbsentDiag_Cnt_str.Threshold	6517
k_ESPNodeAbsentDiag_Cnt_str.PStep	2177
k_ESPNodeAbsentDiag_Cnt_str.NStep	13534
k_ESPNodeAbsentTimeout_mS_u16	29251
k_EtatMTSigInvalidThresh_Cnt_u16	29613
k_EtatMTSigValidThresh_Cnt_u16	45188
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	16060
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	14743
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	47607
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	63422
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	14913
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	59631

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	59245
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	24760
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	53540
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	3180
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	6272
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	47145
k_ISDATDIRASentDiag_Cnt_str.Threshold	38591
k_ISDATDIRASentDiag_Cnt_str.PStep	41027
k_ISDATDIRASentDiag_Cnt_str.NStep	62195
k_ISDATDIRASentTimeout_mS_u16	38794
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	34798
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	11199
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	2530
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	51246
k_ISDYNAASChkSumValidThresh_Cnt_u16	5061
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	46107
k_ISDYNAASMsgCountValidThresh_Cnt_u16	56650
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	58834
k_ISDYNAASMsgLenValidThresh_Cnt_u16	20943
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	26118
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	44307
k_ISDYNABRChkSumValidThresh_Cnt_u16	52210
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	65181
k_ISDYNABRMsgCountValidThresh_Cnt_u16	48301
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	64732
k_ISDYNABRMsgLenValidThresh_Cnt_u16	64359
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	46476
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	39527
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	32692
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	63370
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	30022
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	4118
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	38983
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	48190
k_ISDYNVOLChkSumValidThresh_Cnt_u16	2673
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	25268
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	58473
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	39373
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	50889
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	19454
k_IgnOnTimeout_mS_u16	37530
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	40.3922997
k_PowerCutVehSpdLowThresh_Kph_f32	23.7126007
k_PowerCutVehSpdLowTimeout_mS_u16	53763
k_VBattMaxAAS_Volt_f32	1.93929994
k_VBattMaxBSI_Volt_f32	15.0517998
k_VBattMaxCAV_Volt_f32	11.1085997
k_VBattMaxCMM388_Volt_f32	0.288800001
k_VBattMaxCMM_Volt_f32	5.64599991
k_VBattMaxESP_Volt_f32	30.3726997
k_VBattMinAAS_Volt_f32	12.6422005
k_VBattMinBSI_Volt_f32	30.3726997
k_VBattMinCAV_Volt_f32	1.04359996
k_VBattMinCMM388_Volt_f32	26.4747009
k_VBattMinCMM_Volt_f32	30.0694008
k_VBattMinESP_Volt_f32	5.64599991
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	13944
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	18396
k_VitesseVehicleBVRampValidThresh_Cnt_u16	25753
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	12891
k_VitesseVehicleBVSigValidThresh_Cnt_u16	9135
k_VitesseVehicleBVSpeedPassThresh_kph_f32	124.924599
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	17306
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	35650
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2728648192
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	151
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	10979
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2757805312
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	250
target_SrlComInput_Per1_Batt_Volt_f32.value	10.0740004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1388432896
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	104
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.971362293
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1765277184
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	28
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	419241472
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2945596928
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	888626688
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2972483072
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	741449216
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2919677440
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	92
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	105
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	187
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	191
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	217
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3581959680
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	64
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	114
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	131
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	184
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	196
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	7
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1972567552
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	58
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2027429376
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	585973248
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	38
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	118
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	242
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1018777088
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3214
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.564626932
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	318963
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	197.707993
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	11725

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2757805312	2757805312	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	15384	15384	✔
AASNodeAbsentTimer_mS_M_u32	2757805312	2757805312	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	11201	11201	✔
AngleVolantMsgTimer_mS_M_u32	2757805312	2757805312	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2757805312	2757805312	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2757805312	2757805312	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2757805312	2757805312	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2757805312	2757805312	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	22612	22612	✔
BSINodeAbsentTimer_mS_M_u32	2757805312	2757805312	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2757805312	2757805312	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2757805312	2757805312	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2757805312	2757805312	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2757805312	2757805312	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	18104	18104	✔
CMMNodeAbsentTimer_mS_M_u32	2757805312	2757805312	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	43880	43880	✔
CONSANGLECPK_HwDeg_M_f32	502.567993	502.567993 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43880	43880	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3533876736	3533876736	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	22752	22752	✔
CityParkInputConsistentCount_Cnt_M_u16	34510	34510	✔
CityParkInputInvalidCount_Cnt_M_u16	22161	22161	✔
CityParkInputMsgTimer_mS_M_u32	2757805312	2757805312	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2757805312	2757805312	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2757805312	2757805312	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2757805312	2757805312	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2757805312	2757805312	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2757805312	2757805312	✔
ESPNTCEnableTimer_mS_M_u32	2757805312	2757805312	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2757805312	2757805312	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	2757805312	2757805312	✔
EffacDefaultDiagTimer_mS_M_u32[1]	78	78	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2757805312	2757805312	✔
ElecIntTimer_mS_M_u32[1]	749	749	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2757805312	2757805312	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2757805312	2757805312	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2757805312	2757805312	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2757805312	2757805312	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2757805312	2757805312	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2757805312	2757805312	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2757805312	2757805312	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2757805312	2757805312	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2757805312	2757805312	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2757805312	2757805312	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2757805312	2757805312	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2757805312	2757805312	✔
IgnOnTimer_mS_M_u32	996015616	996015616	✔
IgnTimeOff_Sec_M_u32	2690024877	2690024877	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	221	221	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1765277184	1765277184	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	28	28	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	419241472	419241472	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	190	190	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2945596928	2945596928	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	888626688	888626688	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3313974784	3313974784	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	70	70	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	741449216	741449216	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	195	195	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2919677440	2919677440	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	241	241	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3581959680	3581959680	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	7	7	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1972567552	1972567552	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	58	58	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2027429376	2027429376	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	144	144	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	585973248	585973248	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1018777088	1018777088	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	167.802994	167.802994	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	45.6781006	45.6781006	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	525.918884	525.918884	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	43880	43880	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2690024877	2690024877	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	502.567993	502.567993 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.58 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1964751104
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	23680
AASNodeAbsentTimer_mS_M_u32	15853824
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	39170
ANGLEVOLANTSigValidCount_Cnt_M_u16	21076
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	32409
AngleVolantMsgTimer_mS_M_u32	1964751104
AngleVolantValidCount_Cnt_M_u16	53207
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2856233216
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3366660352
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2331367680
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1030068480
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	6397
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2913229056
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	42630
CAVNodeAbsentTimer_mS_M_u32	3109030144
CDD_SrlComVehSpd_Kph_G_f32	226.944199
CMM388NTCEnableTimer_mS_M_u32	3038726400
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2062420224
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	40321
CMMNodeAbsentTimer_mS_M_u32	1615304960
CONSANGLECPKSigInvalidCount_Cnt_M_u16	54699
CONSANGLECPKSigValidCount_Cnt_M_u16	16397
CONSANGLECPK_Cnt_M_u16	604
CONSANGLECPK_HwDeg_M_f32	464.381195
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	604
CPKVehicleSpeedMsgTimer_mS_M_u32	2012133632
CPKVehicleSpeedValidCount_Cnt_M_u16	61661

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	4587
CityParkInputInvalidCount_Cnt_M_u16	14248
CityParkInputMsgTimer_mS_M_u32	1765277184
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3355830528
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	31892
ComputerRazGCTSigInvalidTimer_mS_M_u32	1225165056
ComputerRazGCTSigValidCount_Cnt_M_u16	35420
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	41364
DMDFCTCPKSigValidCount_Cnt_M_u16	55085
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	17676
DMDRELAXECPKSigValidCount_Cnt_M_u16	53726
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	15556
DateInvalidTimer_mS_M_u32	3366660352
DiagMuxOnAbsentTimer_mS_M_u32	2595911936
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1030068480
ESPNTCEnableTimer_mS_M_u32	1256122624
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	7070
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	101
EffacDefaultDiagTimer_mS_M_u32[1]	1003516928
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	45
ElecIntTimer_mS_M_u32[1]	99
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1418615040
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	17601
EtatMTSigValidCount_Cnt_M_u16	24207
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	8117
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	56727
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	19147
ISDAT4V2BSI552MsgTimer_mS_M_u32	240883968
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	26531
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	28953
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	24207
ISDATBSI3F2MsgTimer_mS_M_u32	2293266688
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	24756
ISDATBSI412MsgLenValidCount_Cnt_M_u16	28826
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	17601
ISDATBSI412MsgTimer_mS_M_u32	1896986880
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	29333
ISDATBSI432MsgLenValidCount_Cnt_M_u16	22450
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	4371
ISDATDIRASentFltAcc_Cnt_M_u16	45047
ISDATDIRASentTimer_mS_M_u32	2012133632
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	40146
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	53207
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	48399
ISDYN2CMMMsgTimer_mS_M_u32	3225479424
ISDYNAASChkSumInvalidCount_Cnt_M_u16	9354
ISDYNAASChkSumValidCount_Cnt_M_u16	40059
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	63826
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	43029
ISDYNAASMsgLenValidCount_Cnt_M_u16	6175
ISDYNAASMsgTimeValidCount_Cnt_M_u16	9354
ISDYNAASMsgTimer_mS_M_u32	3221965056
ISDYNABRChkSumInvalidCount_Cnt_M_u16	30156
ISDYNABRChkSumValidCount_Cnt_M_u16	15558
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	52869
ISDYNABRMsgCountValidCount_Cnt_M_u16	23734
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	1702
ISDYNABRMsgLenValidCount_Cnt_M_u16	51016
ISDYNABRMsgTimeValidCount_Cnt_M_u16	604

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	631
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1147
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	24207
ISDYNCMM208MsgTimer_mS_M_u32	2448402688
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2375
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1253
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	1741
ISDYNCMM388MsgTimer_mS_M_u32	3790129408
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	7073
ISDYNVOLChkSumValidCount_Cnt_M_u16	12931
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	44682
ISDYNVOLMsgCountValidCount_Cnt_M_u16	53411
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	5283
ISDYNVOLMsgLenValidCount_Cnt_M_u16	41061
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	40321
ISDYNVOLMsgTimer_mS_M_u32	2415036672
IgnOnTimer_mS_M_u32	251447552
IgnTimeOff_Sec_M_u32	2683976101
ManVehSpd_Kph_M_f32	330.961395
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	220
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	55
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	950958336
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	236
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4132493568
PrevISDATBSI412MsgDLCError_Cnt_M_u08	120
PrevISDATBSI412MsgRxTime_MSec_M_u32	2717385984
PrevISDATBSI432MsgDLCError_Cnt_M_u08	124
PrevISDATBSI432MsgRxTime_MSec_M_u32	212003072
PrevISDATDIRAMsgTxTime_MSec_M_u32	2776697088
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	93
PrevISDYN2CMMMsgRxTime_MSec_M_u32	286071040
PrevISDYNAASMsgDLCError_Cnt_M_u08	202
PrevISDYNAASMsgRxTime_MSec_M_u32	3530066176
PrevISDYNABRMsgDLCError_Cnt_M_u08	234
PrevISDYNABRMsgRxTime_MSec_M_u32	1003800832
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	31
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2040105216
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	8
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3354519808
PrevISDYNVOLMsgDLCError_Cnt_M_u08	3
PrevISDYNVOLMsgRxTime_MSec_M_u32	3754297600
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2215098624
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	578.754517
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	49931
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	40853
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	50064
VitesseVehicleBVRampValidCount_Cnt_M_u16	27098
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	64775

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	8217
VitesseVehicleBV_Kph_M_f32	60.6082993
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	1741
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	59447
VitesseVehiculeRoues_Kph_M_f32	79.9860001
k_AASNTCEnableTimeout_mS_u16	36463
k_AASNodeAbsentDiag_Cnt_str.Threshold	35672
k_AASNodeAbsentDiag_Cnt_str.PStep	43186
k_AASNodeAbsentDiag_Cnt_str.NStep	48281
k_AASNodeAbsentTimeout_mS_u16	36414
k_AASNodeTimeout_mS_u16	59029
k_ABSNodeTimeout_mS_u16	37381
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	10556
k_ANGLEVOLANTSigValidThresh_Cnt_u16	36249
k_AngleVolantInvalidThresh_Cnt_u16	19900
k_AngleVolantValidThresh_Cnt_u16	14248
k_BSI552MsgTimeout_mS_u16	16922
k_BSINTCEnableTimeout_mS_u16	20333
k_BSINodeAbsentDiag_Cnt_str.Threshold	22652
k_BSINodeAbsentDiag_Cnt_str.PStep	35913
k_BSINodeAbsentDiag_Cnt_str.NStep	13118
k_BSINodeAbsentTimeout_mS_u16	58737
k_BSINodeTimeout_mS_u16	4371
k_BattOvHi_Volt_f32	4.59030008
k_BattOvLo_Volt_f32	0.68599999
k_BattUvHi_Volt_f32	11.3112001
k_BattUvLo_Volt_f32	11.1315002
k_CAVNTCEnableTimeout_mS_u16	32630
k_CAVNodeAbsentDiag_Cnt_str.Threshold	46349
k_CAVNodeAbsentDiag_Cnt_str.PStep	5125
k_CAVNodeAbsentDiag_Cnt_str.NStep	16492
k_CAVNodeAbsentTimeout_mS_u16	8316
k_CAVNodeTimeout_mS_u16	30871
k_CMM388MsgTimeout_mS_u16	58240
k_CMM388NTCEnableTimeout_mS_u16	876
k_CMMNTCEnableTimeout_mS_u16	28795
k_CMMNodeAbsentDiag_Cnt_str.Threshold	344
k_CMMNodeAbsentDiag_Cnt_str.PStep	59178
k_CMMNodeAbsentDiag_Cnt_str.NStep	5133
k_CMMNodeAbsentTimeout_mS_u16	9763
k_CONSANGLECPKMax_HwDeg_f32	142.281097
k_CONSANGLECPKMin_HwDeg_f32	-611.195129
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	3533
k_CONSANGLECPKSigValidThresh_Cnt_u16	12087
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	47411
k_CPKVehicleSpeedValidThresh_Cnt_u16	9475
k_CityParkInputInvalidThresh_Cnt_u16	43754
k_CityParkInputValidThresh_Cnt_u16	4587
k_ComputerRazGCTSigValidThresh_Cnt_u16	28705
k_CptTemporelSigValidThresh_Cnt_u16	31767
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	36262
k_DMDFCTCPKSigValidThresh_Cnt_u16	36424
k_DMDFCTCPKValidCount_Cnt_u16	2341
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	48399
k_DMDRELAXECPKSigValidThresh_Cnt_u16	10472
k_DMDRelaxeConsistentThresh_Cnt_u16	64902
k_DateValidThresh_Cnt_u16	19147
k_DefaultVehSpd_Kph_f32	177.595093
k_DiagMuxOnAbsentTimeout_mS_u16	28074
k_EMNodeTimeout_mS_u16	1700
k_ESPNTCEnableTimeout_mS_u16	9074
k_ESPNodeAbsentDiag_Cnt_str.Threshold	34947
k_ESPNodeAbsentDiag_Cnt_str.PStep	58325
k_ESPNodeAbsentDiag_Cnt_str.NStep	39799
k_ESPNodeAbsentTimeout_mS_u16	12619
k_EtatMTSigInvalidThresh_Cnt_u16	13903
k_EtatMTSigValidThresh_Cnt_u16	27017
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	19938
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	22287
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	23664
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	604
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	54418
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	33736

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	43214
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	63147
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	34729
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	61264
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	42197
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	53017
k_ISDATDIRASentDiag_Cnt_str.Threshold	6138
k_ISDATDIRASentDiag_Cnt_str.PStep	41257
k_ISDATDIRASentDiag_Cnt_str.NStep	47375
k_ISDATDIRASentTimeout_mS_u16	32440
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	46026
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	32409
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	31406
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	31948
k_ISDYNAASChkSumValidThresh_Cnt_u16	33734
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	21893
k_ISDYNAASMsgCountValidThresh_Cnt_u16	9142
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	46048
k_ISDYNAASMsgLenValidThresh_Cnt_u16	8361
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	40641
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	39836
k_ISDYNABRChkSumValidThresh_Cnt_u16	18622
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	40957
k_ISDYNABRMsgCountValidThresh_Cnt_u16	12175
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	58497
k_ISDYNABRMsgLenValidThresh_Cnt_u16	41630
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	33010
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	7455
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	4985
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	56184
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	8194
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	6484
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	21120
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	1499
k_ISDYNVOLChkSumValidThresh_Cnt_u16	29953
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	57527
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	41434
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	25261
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	21883
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	41241
k_IgnOnTimeout_mS_u16	62151
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	173.662003
k_PowerCutVehSpdLowThresh_Kph_f32	167.701096
k_PowerCutVehSpdLowTimeout_mS_u16	47755
k_VBattMaxAAS_Volt_f32	22.3274002
k_VBattMaxBSI_Volt_f32	21.468399
k_VBattMaxCAV_Volt_f32	24.0489998
k_VBattMaxCMM388_Volt_f32	8.36170006
k_VBattMaxCMM_Volt_f32	30.4144001
k_VBattMaxESP_Volt_f32	10.2138004
k_VBattMinAAS_Volt_f32	12.1002998
k_VBattMinBSI_Volt_f32	10.2138004
k_VBattMinCAV_Volt_f32	28.6884003
k_VBattMinCMM388_Volt_f32	32
k_VBattMinCMM_Volt_f32	3.77589989
k_VBattMinESP_Volt_f32	30.4144001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	20524
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	13762
k_VitesseVehicleBVRampValidThresh_Cnt_u16	46474
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	63875
k_VitesseVehicleBVSigValidThresh_Cnt_u16	65352
k_VitesseVehicleBVSpeedPassThresh_kph_f32	87.5842972
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	44422
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	80
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3366660352
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	198
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	32832
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1003516928
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	8
target_SrlComInput_Per1_Batt_Volt_f32.value	13.1954002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3692124416
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	64
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0869212598
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1835976960
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1520396544
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	159
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3546286336
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3216025856
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	126961920
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2466375936
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	130
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1241680128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	61
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	169
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1108715776
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	93
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	109
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	186
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	199
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1952303360
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1728997632
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2773420288
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	90
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	121
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	138
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1546311936
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	693
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0243442133
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	142809
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	220.964996
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	31469

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1003516928	1003516928	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	35672	35672	✔
AASNodeAbsentTimer_mS_M_u32	1003516928	1003516928	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1003516928	1003516928	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1003516928	1003516928	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1003516928	1003516928	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1003516928	1003516928	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1003516928	1003516928	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	22652	22652	✔
BSINodeAbsentTimer_mS_M_u32	1003516928	1003516928	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1003516928	1003516928	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1003516928	1003516928	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1003516928	1003516928	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1003516928	1003516928	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	344	344	✔
CMMNodeAbsentTimer_mS_M_u32	1003516928	1003516928	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	604	604	✔
CONSANGLECPK_HwDeg_M_f32	464.381195	464.381195 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1003516928	1003516928	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1003516928	1003516928	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1003516928	1003516928	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1003516928	1003516928	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1003516928	1003516928	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1003516928	1003516928	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1003516928	1003516928	✔
ESPNTCEnableTimer_mS_M_u32	1003516928	1003516928	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1003516928	1003516928	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	101	101	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1003516928	1003516928	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	1003516928	1003516928	✔
ElecIntTimer_mS_M_u32[1]	99	99	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1003516928	1003516928	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1003516928	1003516928	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1003516928	1003516928	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1003516928	1003516928	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1003516928	1003516928	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1003516928	1003516928	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1003516928	1003516928	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1003516928	1003516928	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1003516928	1003516928	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1003516928	1003516928	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1003516928	1003516928	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1003516928	1003516928	✔
IgnOnTimer_mS_M_u32	1003516928	1003516928	✔
IgnTimeOff_Sec_M_u32	2683976101	2683976101	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	74	74	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1835976960	1835976960	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	233	233	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1520396544	1520396544	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	159	159	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3546286336	3546286336	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	84	84	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3216025856	3216025856	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2776697088	2776697088	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	94	94	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2466375936	2466375936	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	130	130	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1241680128	1241680128	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	72	72	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1108715776	1108715776	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	246	246	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1952303360	1952303360	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	186	186	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1728997632	1728997632	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	86	86	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2773420288	2773420288	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1546311936	1546311936	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	578.754517	578.754517	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	60.6082993	60.6082993	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	79.9860001	79.9860001	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	604	604	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2683976101	2683976101	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	464.381195	464.381195 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	177.595093	177.595093	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.59 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2523895808
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	4674
AASNodeAbsentTimer_mS_M_u32	1202522112
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	34490
ANGLEVOLANTSigValidCount_Cnt_M_u16	64901
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	20471
AngleVolantMsgTimer_mS_M_u32	2523895808
AngleVolantValidCount_Cnt_M_u16	7867
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-110.614471
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1858521088
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1702971392
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3848353792
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1024587776
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	45769
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1465235456
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	29871
CAVNodeAbsentTimer_mS_M_u32	3205670912
CDD_SrlComVehSpd_Kph_G_f32	213.970993
CMM388NTCEnableTimer_mS_M_u32	413460480
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1916315648
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	26494
CMMNodeAbsentTimer_mS_M_u32	3698063360
CONSANGLECPKSigInvalidCount_Cnt_M_u16	25536
CONSANGLECPKSigValidCount_Cnt_M_u16	1883
CONSANGLECPK_Cnt_M_u16	48238
CONSANGLECPK_HwDeg_M_f32	218.703293
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	48238
CPKVehicleSpeedMsgTimer_mS_M_u32	2583074816
CPKVehicleSpeedValidCount_Cnt_M_u16	44082
CityParkInputConsistentCount_Cnt_M_u16	43135
CityParkInputInvalidCount_Cnt_M_u16	30794
CityParkInputMsgTimer_mS_M_u32	1835976960
CityParkInputValidCount_Cnt_M_u16	6

Name	Input Value
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1114703872
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	518
ComputerRazGCTSigInvalidTimer_mS_M_u32	166668288
ComputerRazGCTSigValidCount_Cnt_M_u16	17196
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	60038
DMDFCTCPKSigValidCount_Cnt_M_u16	3193
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	10908
DMDRELAXECPKSigValidCount_Cnt_M_u16	9959
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	53877
DateInvalidTimer_mS_M_u32	1702971392
DiagMuxOnAbsentTimer_mS_M_u32	278091776
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1024587776
ESPNTCEnableTimer_mS_M_u32	1575356416
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	49125
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	99
EffacDefaultDiagTimer_mS_M_u32[1]	999
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	66
ElecIntTimer_mS_M_u32[1]	79
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2325198848
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	49854
EtatMTSigValidCount_Cnt_M_u16	2069
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	11682
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	54973
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	43423
ISDAT4V2BSI552MsgTimer_mS_M_u32	573569024
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	47512
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	53239
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	2069
ISDATBSI3F2MsgTimer_mS_M_u32	2662422528
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	41828
ISDATBSI412MsgLenValidCount_Cnt_M_u16	26227
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	49854
ISDATBSI412MsgTimer_mS_M_u32	4203583488
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	14402
ISDATBSI432MsgLenValidCount_Cnt_M_u16	23465
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0
ISDATDIRASentFltAcc_Cnt_M_u16	23644
ISDATDIRASentTimer_mS_M_u32	2583074816
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	17676
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	7867
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	17429
ISDYN2CMMMsgTimer_mS_M_u32	96471040
ISDYNAASChkSumInvalidCount_Cnt_M_u16	25124
ISDYNAASChkSumValidCount_Cnt_M_u16	7439
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	20042
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	27650
ISDYNAASMsgLenValidCount_Cnt_M_u16	40613
ISDYNAASMsgTimeValidCount_Cnt_M_u16	25124
ISDYNAASMsgTimer_mS_M_u32	2816534528
ISDYNABRChkSumInvalidCount_Cnt_M_u16	61404
ISDYNABRChkSumValidCount_Cnt_M_u16	56751
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	4147
ISDYNABRMsgCountValidCount_Cnt_M_u16	34910
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	31951
ISDYNABRMsgLenValidCount_Cnt_M_u16	7594
ISDYNABRMsgTimeValidCount_Cnt_M_u16	48238
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	632
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1149
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	2069
ISDYNCMM208MsgTimer_mS_M_u32	3149121536

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2379
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1255
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	53721
ISDYNCMM388MsgTimer_mS_M_u32	2554882048
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	59870
ISDYNVOLChkSumValidCount_Cnt_M_u16	34809
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	7076
ISDYNVOLMsgCountValidCount_Cnt_M_u16	30743
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	10454
ISDYNVOLMsgLenValidCount_Cnt_M_u16	59473
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	26494
ISDYNVOLMsgTimer_mS_M_u32	3844810752
IgnOnTimer_mS_M_u32	1628203008
IgnTimeOff_Sec_M_u32	511369402
ManVehSpd_Kph_M_f32	78.1827011
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	222
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	180
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	112678912
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	67
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3478140928
PrevISDATBSI412MsgDLCError_Cnt_M_u08	128
PrevISDATBSI412MsgRxTime_MSec_M_u32	3022759936
PrevISDATBSI432MsgDLCError_Cnt_M_u08	148
PrevISDATBSI432MsgRxTime_MSec_M_u32	681183232
PrevISDATDIRAMsgTxTime_MSec_M_u32	4269778944
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	242
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3223025664
PrevISDYNAASMsgDLCError_Cnt_M_u08	94
PrevISDYNAASMsgRxTime_MSec_M_u32	1976117248
PrevISDYNABRMsgDLCError_Cnt_M_u08	214
PrevISDYNABRMsgRxTime_MSec_M_u32	981755904
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	87
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2218141696
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	207
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4071426048
PrevISDYNVOLMsgDLCError_Cnt_M_u08	157
PrevISDYNVOLMsgRxTime_MSec_M_u32	2746263552
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	430675968
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	148.177795
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	29472
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	24643
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	50577
VitesseVehicleBVRampValidCount_Cnt_M_u16	21876
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	44715
VitesseVehicleBVSigValidCount_Cnt_M_u16	59446
VitesseVehicleBV_Kph_M_f32	418.138397
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	53721
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	12380

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	574.085022
k_AASNTCEnableTimeout_mS_u16	9269
k_AASNodeAbsentDiag_Cnt_str.Threshold	41044
k_AASNodeAbsentDiag_Cnt_str.PStep	28893
k_AASNodeAbsentDiag_Cnt_str.NStep	4355
k_AASNodeAbsentTimeout_mS_u16	16262
k_AASNodeTimeout_mS_u16	35651
k_ABSNodeTimeout_mS_u16	7475
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	28749
k_ANGLEVOLANTSigValidThresh_Cnt_u16	5620
k_AngleVolantInvalidThresh_Cnt_u16	8587
k_AngleVolantValidThresh_Cnt_u16	30794
k_BSI552MsgTimeout_mS_u16	28339
k_BSINTCEnableTimeout_mS_u16	0
k_BSINodeAbsentDiag_Cnt_str.Threshold	22692
k_BSINodeAbsentDiag_Cnt_str.PStep	35896
k_BSINodeAbsentDiag_Cnt_str.NStep	13141
k_BSINodeAbsentTimeout_mS_u16	31599
k_BSINodeTimeout_mS_u16	0
k_BattOvHi_Volt_f32	6.03520012
k_BattOvLo_Volt_f32	14.6695995
k_BattUvHi_Volt_f32	19.7054996
k_BattUvLo_Volt_f32	10.4373999
k_CAVNTCEnableTimeout_mS_u16	22752
k_CAVNodeAbsentDiag_Cnt_str.Threshold	4333
k_CAVNodeAbsentDiag_Cnt_str.PStep	18142
k_CAVNodeAbsentDiag_Cnt_str.NStep	46528
k_CAVNodeAbsentTimeout_mS_u16	24269
k_CAVNodeTimeout_mS_u16	11004
k_CMM388MsgTimeout_mS_u16	32066
k_CMM388NTCEnableTimeout_mS_u16	52606
k_CMMNTCEnableTimeout_mS_u16	65296
k_CMMNodeAbsentDiag_Cnt_str.Threshold	64692
k_CMMNodeAbsentDiag_Cnt_str.PStep	24791
k_CMMNodeAbsentDiag_Cnt_str.NStep	15109
k_CMMNodeAbsentTimeout_mS_u16	9880
k_CONSANGLECPKMax_HwDeg_f32	707.317627
k_CONSANGLECPKMin_HwDeg_f32	-46.2391014
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	48345
k_CONSANGLECPKSigValidThresh_Cnt_u16	23388
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	2921
k_CPKVehicleSpeedValidThresh_Cnt_u16	21111
k_CityParkInputInvalidThresh_Cnt_u16	18562
k_CityParkInputValidThresh_Cnt_u16	43135
k_ComputerRazGCTSigValidThresh_Cnt_u16	6174
k_CptTemporelSigValidThresh_Cnt_u16	9981
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	59343
k_DMDFCTCPKSigValidThresh_Cnt_u16	51370
k_DMDFCTCPKValidCount_Cnt_u16	33361
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	17429
k_DMDRELAXECPKSigValidThresh_Cnt_u16	49992
k_DMDRelaxeConsistentThresh_Cnt_u16	15726
k_DateValidThresh_Cnt_u16	43423
k_DefaultVehSpd_Kph_f32	27.4755001
k_DiagMuxOnAbsentTimeout_mS_u16	12932
k_EMNodeTimeout_mS_u16	62677
k_ESPNTCEnableTimeout_mS_u16	44523
k_ESPNodeAbsentDiag_Cnt_str.Threshold	59667
k_ESPNodeAbsentDiag_Cnt_str.PStep	15798
k_ESPNodeAbsentDiag_Cnt_str.NStep	16553
k_ESPNodeAbsentTimeout_mS_u16	42272
k_EtatMTSigInvalidThresh_Cnt_u16	31315
k_EtatMTSigValidThresh_Cnt_u16	9062
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	51548
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	49299
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	7408
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	3437
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	51596
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	35368
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	47511
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	41662
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	18694
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	50578

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	6081
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	32053
k_ISDATDIRASentDiag_Cnt_str.Threshold	33958
k_ISDATDIRASentDiag_Cnt_str.PStep	55281
k_ISDATDIRASentDiag_Cnt_str.NStep	16471
k_ISDATDIRASentTimeout_mS_u16	34072
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	54050
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	20471
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	38967
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	56028
k_ISDYNAASChkSumValidThresh_Cnt_u16	2223
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	31539
k_ISDYNAASMsgCountValidThresh_Cnt_u16	13150
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	34208
k_ISDYNAASMsgLenValidThresh_Cnt_u16	11527
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	33404
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	5613
k_ISDYNABRChkSumValidThresh_Cnt_u16	61768
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	7625
k_ISDYNABRMsgCountValidThresh_Cnt_u16	4564
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	37502
k_ISDYNABRMsgLenValidThresh_Cnt_u16	10981
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	27051
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	46308
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	57109
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	63642
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	61882
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	43141
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	34754
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	4079
k_ISDYNVOLChkSumValidThresh_Cnt_u16	46398
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	5274
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	65139
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	6394
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	54097
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	24245
k_IgnOnTimeout_mS_u16	63787
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	83.7748032
k_PowerCutVehSpdLowThresh_Kph_f32	13.6576004
k_PowerCutVehSpdLowTimeout_mS_u16	4065
k_VBattMaxAAS_Volt_f32	7.55929995
k_VBattMaxBSI_Volt_f32	26.7005997
k_VBattMaxCAV_Volt_f32	13.7061005
k_VBattMaxCMM388_Volt_f32	7.20720005
k_VBattMaxCMM_Volt_f32	24.6772003
k_VBattMaxESP_Volt_f32	22.3404007
k_VBattMinAAS_Volt_f32	5.59490013
k_VBattMinBSI_Volt_f32	12.2563
k_VBattMinCAV_Volt_f32	10.4547005
k_VBattMinCMM388_Volt_f32	24.9634991
k_VBattMinCMM_Volt_f32	30.6970005
k_VBattMinESP_Volt_f32	24.6772003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	1532
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	2042
k_VitesseVehicleBVRampValidThresh_Cnt_u16	1700
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	13049
k_VitesseVehicleBVSigValidThresh_Cnt_u16	37992
k_VitesseVehicleBVSpeedPassThresh_kph_f32	199.404907
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	24495
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	59922
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1702971392
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	151
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	40388
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	318596864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	207
target_SrlComInput_Per1_Batt_Volt_f32.value	16.3215008
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3222190080
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	158
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.217341483
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2377541632
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3500443648
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	96
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2967644160
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1987102720
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1766778880
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3514632192
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4143654912
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	62
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	129
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	147
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	161
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3275868160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	60
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	70
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	89
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	127
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4108937216
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	660047872
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3071649792
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	88
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	129
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2244098048
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	921
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.889569521
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	144653
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	176.115799
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	21370

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	318596864	318596864	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	41044	41044	✔
AASNodeAbsentTimer_mS_M_u32	318596864	318596864	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	318596864	318596864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-110.614471	-110.614471	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1858521088	1858521088	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	318596864	318596864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	318596864	318596864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1024587776	1024587776	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	22692	22692	✔
BSINodeAbsentTimer_mS_M_u32	318596864	318596864	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	318596864	318596864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	318596864	318596864	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	318596864	318596864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	318596864	318596864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	64692	64692	✔
CMMNodeAbsentTimer_mS_M_u32	318596864	318596864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	48238	48238	✔
CONSANGLECPK_HwDeg_M_f32	218.703293	218.703293 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	318596864	318596864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	318596864	318596864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	318596864	318596864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	318596864	318596864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	318596864	318596864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	318596864	318596864	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	318596864	318596864	✔
ESPNTCEnableTimer_mS_M_u32	318596864	318596864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	318596864	318596864	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	318596864	318596864	✔
EffacDefaultDiagTimer_mS_M_u32[1]	999	999	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	318596864	318596864	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	79	79	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	318596864	318596864	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2377541632	2377541632	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3500443648	3500443648	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	318596864	318596864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	318596864	318596864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	318596864	318596864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	318596864	318596864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	318596864	318596864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	318596864	318596864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	318596864	318596864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	318596864	318596864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	318596864	318596864	✔
IgnOnTimer_mS_M_u32	318596864	318596864	✔
IgnTimeOff_Sec_M_u32	511369402	511369402	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	72	72	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2377541632	2377541632	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	88	88	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3500443648	3500443648	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	96	96	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2967644160	2967644160	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	170	170	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1987102720	1987102720	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4269778944	4269778944	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	34	34	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3514632192	3514632192	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4143654912	4143654912	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3275868160	3275868160	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	192	192	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4108937216	4108937216	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	660047872	660047872	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	183	183	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3071649792	3071649792	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2244098048	2244098048	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	148.177795	148.177795	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	418.138397	418.138397	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	574.085022	574.085022	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-110.614471	-110.614471	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	48238	48238	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	511369402	511369402	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	218.703293	218.703293 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	27.4755001	27.4755001	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.60 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3702520576
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	54072
AASNodeAbsentTimer_mS_M_u32	3401034496
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	63438
ANGLEVOLANTSigValidCount_Cnt_M_u16	43822
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	11801
AngleVolantMsgTimer_mS_M_u32	3702520576
AngleVolantValidCount_Cnt_M_u16	31309
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-718.72229
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3966397184
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	305851136
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1046158080
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3930643200
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	28577
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1518181120
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	60015
CAVNodeAbsentTimer_mS_M_u32	2198260480
CDD_SrlComVehSpd_Kph_G_f32	286.821198
CMM388NTCEnableTimer_mS_M_u32	2404387584
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2174012160
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	35522
CMMNodeAbsentTimer_mS_M_u32	4097497856

Name	Input Value
CONSANGLECPKSigInvalidCount_Cnt_M_u16	42941
CONSANGLECPKSigValidCount_Cnt_M_u16	5292
CONSANGLECPK_Cnt_M_u16	371
CONSANGLECPK_HwDeg_M_f32	-12.3612003
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	371
CPKVehicleSpeedMsgTimer_mS_M_u32	2921003776
CPKVehicleSpeedValidCount_Cnt_M_u16	8270
CityParkInputConsistentCount_Cnt_M_u16	60673
CityParkInputInvalidCount_Cnt_M_u16	47775
CityParkInputMsgTimer_mS_M_u32	2377541632
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3932924672
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	5100
ComputerRazGCTSigInvalidTimer_mS_M_u32	3027323648
ComputerRazGCTSigValidCount_Cnt_M_u16	4346
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	21483
DMDFCTCPKSigValidCount_Cnt_M_u16	42450
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	5160
DMDRELAXECPKSigValidCount_Cnt_M_u16	14088
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	28574
DateInvalidTimer_mS_M_u32	305851136
DiagMuxOnAbsentTimer_mS_M_u32	2906962688
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3930643200
ESPNTCEnableTimer_mS_M_u32	2886511360
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	2381
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	2768408064
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	101
ElecIntTimer_mS_M_u32[1]	2768408064
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1219992320
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	34308
EtatMTSigValidCount_Cnt_M_u16	64959
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	21015
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	44678
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	58976
ISDAT4V2BSI552MsgTimer_mS_M_u32	854514432
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	33525
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	42904
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	64959
ISDATBSI3F2MsgTimer_mS_M_u32	4209687296
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	18064
ISDATBSI412MsgLenValidCount_Cnt_M_u16	9507
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	34308
ISDATBSI412MsgTimer_mS_M_u32	2824207104
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	10358
ISDATBSI432MsgLenValidCount_Cnt_M_u16	17921
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	65535
ISDATDIRASentFltAcc_Cnt_M_u16	10088
ISDATDIRASentTimer_mS_M_u32	2921003776
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	24473
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	31309
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	17214
ISDYN2CMMMsgTimer_mS_M_u32	2625547008
ISDYNAASChkSumInvalidCount_Cnt_M_u16	60306
ISDYNAASChkSumValidCount_Cnt_M_u16	21137
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	59296
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	4214
ISDYNAASMsgLenValidCount_Cnt_M_u16	61517
ISDYNAASMsgTimeValidCount_Cnt_M_u16	60306
ISDYNAASMsgTimer_mS_M_u32	3516664576

Name	Input Value
ISDYNABRChkSumInvalidCount_Cnt_M_u16	48615
ISDYNABRChkSumValidCount_Cnt_M_u16	11311
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	56677
ISDYNABRMsgCountValidCount_Cnt_M_u16	3236
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	22672
ISDYNABRMsgLenValidCount_Cnt_M_u16	52671
ISDYNABRMsgTimeValidCount_Cnt_M_u16	371
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	633
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1151
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	64959
ISDYNCMM208MsgTimer_mS_M_u32	4188236544
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2383
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1257
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	22771
ISDYNCMM388MsgTimer_mS_M_u32	4268067584
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	3427
ISDYNVOLChkSumValidCount_Cnt_M_u16	35538
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	47249
ISDYNVOLMsgCountValidCount_Cnt_M_u16	23288
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	53882
ISDYNVOLMsgLenValidCount_Cnt_M_u16	27593
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	35522
ISDYNVOLMsgTimer_mS_M_u32	314395392
IgnOnTimer_mS_M_u32	3021572864
IgnTimeOff_Sec_M_u32	3050685578
ManVehSpd_Kph_M_f32	165.396805
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	224
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	85
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1524153088
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	151
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4237171456
PrevISDATBSI412MsgDLCError_Cnt_M_u08	68
PrevISDATBSI412MsgRxTime_MSec_M_u32	1203489536
PrevISDATBSI432MsgDLCError_Cnt_M_u08	169
PrevISDATBSI432MsgRxTime_MSec_M_u32	468757248
PrevISDATDIRAMsgTxTime_MSec_M_u32	3099577088
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	135
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1730960128
PrevISDYNAASMsgDLCError_Cnt_M_u08	50
PrevISDYNAASMsgRxTime_MSec_M_u32	1491290880
PrevISDYNABRMsgDLCError_Cnt_M_u08	58
PrevISDYNABRMsgRxTime_MSec_M_u32	129075968
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	87
PrevISDYNCMM208MsgRxTime_MSec_M_u32	563890944
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	92
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3384257280
PrevISDYNVOLMsgDLCError_Cnt_M_u08	170
PrevISDYNVOLMsgRxTime_MSec_M_u32	3442264832
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1123810048
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	140.647903
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	62236
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	41843
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	1

Name	Input Value
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	65481
VitesseVehicleBVRampValidCount_Cnt_M_u16	51168
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	33787
VitesseVehicleBVSigValidCount_Cnt_M_u16	61211
VitesseVehicleBV_Kph_M_f32	558.839783
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	22771
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	13610
VitesseVehiculeRoues_Kph_M_f32	105.101097
k_AASNTCEnableTimeout_mS_u16	42526
k_AASNodeAbsentDiag_Cnt_str.Threshold	18732
k_AASNodeAbsentDiag_Cnt_str.PStep	48585
k_AASNodeAbsentDiag_Cnt_str.NStep	43471
k_AASNodeAbsentTimeout_mS_u16	1004
k_AASNodeTimeout_mS_u16	8819
k_ABSNodeTimeout_mS_u16	45028
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	27733
k_ANGLEVOLANTSigValidThresh_Cnt_u16	800
k_AngleVolantInvalidThresh_Cnt_u16	64603
k_AngleVolantValidThresh_Cnt_u16	47775
k_BSI552MsgTimeout_mS_u16	38437
k_BSINTCEnableTimeout_mS_u16	1
k_BSINodeAbsentDiag_Cnt_str.Threshold	22732
k_BSINodeAbsentDiag_Cnt_str.PStep	35879
k_BSINodeAbsentDiag_Cnt_str.NStep	13164
k_BSINodeAbsentTimeout_mS_u16	35761
k_BSINodeTimeout_mS_u16	65535
k_BattOvHi_Volt_f32	3.88849998
k_BattOvLo_Volt_f32	19.7210999
k_BattUvHi_Volt_f32	23.8784008
k_BattUvLo_Volt_f32	16.1040993
k_CAVNTCEnableTimeout_mS_u16	61661
k_CAVNodeAbsentDiag_Cnt_str.Threshold	3642
k_CAVNodeAbsentDiag_Cnt_str.PStep	54240
k_CAVNodeAbsentDiag_Cnt_str.NStep	2801
k_CAVNodeAbsentTimeout_mS_u16	9237
k_CAVNodeTimeout_mS_u16	16905
k_CMM388MsgTimeout_mS_u16	37432
k_CMM388NTCEnableTimeout_mS_u16	37252
k_CMMNTCEnableTimeout_mS_u16	37517
k_CMMNodeAbsentDiag_Cnt_str.Threshold	30957
k_CMMNodeAbsentDiag_Cnt_str.PStep	27579
k_CMMNodeAbsentDiag_Cnt_str.NStep	6825
k_CMMNodeAbsentTimeout_mS_u16	17014
k_CONSANGLECPKMax_HwDeg_f32	336.962097
k_CONSANGLECPKMin_HwDeg_f32	-59.4118004
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	38899
k_CONSANGLECPKSigValidThresh_Cnt_u16	46122
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	47617
k_CPKVehicleSpeedValidThresh_Cnt_u16	17751
k_CityParkInputInvalidThresh_Cnt_u16	52213
k_CityParkInputValidThresh_Cnt_u16	60673
k_ComputerRazGCTSigValidThresh_Cnt_u16	65379
k_CptTemporelSigValidThresh_Cnt_u16	14982
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	6032
k_DMDFCTCPKSigValidThresh_Cnt_u16	52415
k_DMDFCTCPKValidCount_Cnt_u16	8457
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	17214
k_DMDRELAXECPKSigValidThresh_Cnt_u16	32101
k_DMDRelaxeConsistentThresh_Cnt_u16	9971
k_DateValidThresh_Cnt_u16	58976
k_DefaultVehSpd_Kph_f32	158.068802
k_DiagMuxOnAbsentTimeout_mS_u16	30513
k_EMNodeTimeout_mS_u16	34942
k_ESPNTCEnableTimeout_mS_u16	11963
k_ESPNodeAbsentDiag_Cnt_str.Threshold	44592
k_ESPNodeAbsentDiag_Cnt_str.PStep	56448
k_ESPNodeAbsentDiag_Cnt_str.NStep	46622
k_ESPNodeAbsentTimeout_mS_u16	59102

Name	Input Value
k_EtatMTSigInvalidThresh_Cnt_u16	47746
k_EtatMTSigValidThresh_Cnt_u16	63242
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	3112
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	60995
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	37806
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	7030
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	20185
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	41540
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	14455
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	1218
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	1578
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	30215
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	10043
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	18975
k_ISDATDIRASentDiag_Cnt_str.Threshold	56720
k_ISDATDIRASentDiag_Cnt_str.PStep	30501
k_ISDATDIRASentDiag_Cnt_str.NStep	36269
k_ISDATDIRASentTimeout_mS_u16	60979
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	15448
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	11801
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	40919
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	64743
k_ISDYNAASChkSumValidThresh_Cnt_u16	43823
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	40037
k_ISDYNAASMsgCountValidThresh_Cnt_u16	2980
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	3227
k_ISDYNAASMsgLenValidThresh_Cnt_u16	19751
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	56712
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	34102
k_ISDYNABRChkSumValidThresh_Cnt_u16	19173
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	11937
k_ISDYNABRMsgCountValidThresh_Cnt_u16	27201
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	2498
k_ISDYNABRMsgLenValidThresh_Cnt_u16	51277
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	32444
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	15824
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	38781
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	63086
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	46798
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	43566
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	27703
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	60655
k_ISDYNVOLChkSumValidThresh_Cnt_u16	9410
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	7982
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	55779
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	29520
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	35851
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	40734
k_IgnOnTimeout_mS_u16	8507
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	111.670799
k_PowerCutVehSpdLowThresh_Kph_f32	74.0223999
k_PowerCutVehSpdLowTimeout_mS_u16	37658
k_VBattMaxAAS_Volt_f32	1.36259997
k_VBattMaxBSI_Volt_f32	26.2451
k_VBattMaxCAV_Volt_f32	14.9876003
k_VBattMaxCMM388_Volt_f32	30.1658993
k_VBattMaxCMM_Volt_f32	23.8719997
k_VBattMaxESP_Volt_f32	21.6979008
k_VBattMinAAS_Volt_f32	6.19220018
k_VBattMinBSI_Volt_f32	1.23559999
k_VBattMinCAV_Volt_f32	25.7408009
k_VBattMinCMM388_Volt_f32	6.77099991
k_VBattMinCMM_Volt_f32	29.4992008
k_VBattMinESP_Volt_f32	23.8719997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	35786
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	28045
k_VitesseVehicleBVRampValidThresh_Cnt_u16	63377
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	35282
k_VitesseVehicleBVSigValidThresh_Cnt_u16	3398
k_VitesseVehicleBVSpeedPassThresh_kph_f32	315.777588
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	10607
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	518

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	305851136
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	183
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	23651
target Rte Call Ap SrlComInput SystemTime GetSystemTime mS u32 CurrentT	2768408064
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target Rte Inst Ap SrlComInput.SrlComInput Per1 ISDATBSI432MsgRxTime MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target Rte Inst Ap SrlComInput.SrlComInput Per1 ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target Rte Inst Ap SrlComInput.SrlComInput Per1 ISDYNABRMsgRxTime MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target Rte Inst Ap SrlComInput.SrlComInput Per1 ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target Rte Inst Ap SrlComInput.SrlComInput Per1 RxMsgsSrlComSvcDft Cnt lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	92
target_SrlComInput_Per1_Batt_Volt_f32.value	23.4722996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1146264320
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	128
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.34803915
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	44
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1444645632
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1842424576
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3986082560
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4251740928
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3310488320
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	98
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1833413376
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	491604736
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	111
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	114
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	202
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	226
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2600037120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	142
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	216
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	82
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2894236416
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	182
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4122487552
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1727908608
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	94
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	170
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	195
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	557325056
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1427

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0410742164
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	148679
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	155.897598
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	14862

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2768408064	2768408064	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	18732	18732	✔
AASNodeAbsentTimer_mS_M_u32	2768408064	2768408064	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2768408064	2768408064	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-718.72229	-718.72229	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3966397184	3966397184	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	2768408064	2768408064	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1046158080	1046158080	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	3930643200	3930643200	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2768408064	2768408064	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2768408064	2768408064	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	3642	3642	✔
CAVNodeAbsentTimer_mS_M_u32	2768408064	2768408064	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2768408064	2768408064	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2768408064	2768408064	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	28697	28697	✔
CMMNodeAbsentTimer_mS_M_u32	1833413376	1833413376	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	371	371	✔
CONSANGLECPK_HwDeg_M_f32	-12.3612003	-12.3612003 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2768408064	2768408064	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2768408064	2768408064	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2768408064	2768408064	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2768408064	2768408064	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2768408064	2768408064	✔
DateValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DiagMuxOnAbsentTimer_mS_M_u32	2768408064	2768408064	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2768408064	2768408064	✔
ESPNTCEnableTimer_mS_M_u32	2768408064	2768408064	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2768408064	2768408064	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	8	8	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2768408064	2768408064	✔
ElecIntCount_Cnt_M_u08	2	2	✔
ElecIntTimer_mS_M_u32[0]	101	101	✔
ElecIntTimer_mS_M_u32[1]	2768408064	2768408064	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2768408064	2768408064	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1444645632	1444645632	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1842424576	1842424576	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2768408064	2768408064	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4251740928	4251740928	✔
ISDATDIRASentFltAcc_Cnt_M_u16	56720	56720	✔
ISDATDIRASentTimer_mS_M_u32	2768408064	2768408064	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2768408064	2768408064	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2768408064	2768408064	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2768408064	2768408064	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2768408064	2768408064	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2768408064	2768408064	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2768408064	2768408064	✔
IgnOnTimer_mS_M_u32	3021572864	3021572864	✔
IgnTimeOff_Sec_M_u32	3050685578	3050685578	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	44	44	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1444645632	1444645632	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	63	63	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1842424576	1842424576	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	166	166	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3986082560	3986082560	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	136	136	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4251740928	4251740928	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3099577088	3099577088	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	98	98	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1833413376	1833413376	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	169	169	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	491604736	491604736	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	38	38	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2600037120	2600037120	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	82	82	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2894236416	2894236416	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	182	182	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4122487552	4122487552	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	46	46	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1727908608	1727908608	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	557325056	557325056	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	140.647903	140.647903	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	558.839783	558.839783	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	105.101097	105.101097	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-718.72229	-718.72229	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	371	371	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3050685578	3050685578	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-12.3612003	-12.3612003 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	158.068802	158.068802	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.61 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4214936064
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	55713
AASNodeAbsentTimer_mS_M_u32	736346624
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	58845
ANGLEVOLANTSigValidCount_Cnt_M_u16	33920
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	36094
AngleVolantMsgTimer_mS_M_u32	4214936064
AngleVolantValidCount_Cnt_M_u16	32483
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-399.783722
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	30114304
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1918501376
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3938021888
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3455070720
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	35428
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1079112192
CAVNTCsEnabled_Cnt_M_lgc	1

Name	Input Value
CAVNodeAbsentFltAcc_Cnt_M_u16	55419
CAVNodeAbsentTimer_mS_M_u32	2809553408
CDD_SrlComVehSpd_Kph_G_f32	581.797485
CMM388NTCEnableTimer_mS_M_u32	932880896
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1674338816
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	36164
CMMNodeAbsentTimer_mS_M_u32	4162466304
CONSANGLECPKSigInvalidCount_Cnt_M_u16	273
CONSANGLECPKSigValidCount_Cnt_M_u16	45828
CONSANGLECPK_Cnt_M_u16	51375
CONSANGLECPK_HwDeg_M_f32	365.564606
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	51375
CPKVehicleSpeedMsgTimer_mS_M_u32	4076458496
CPKVehicleSpeedValidCount_Cnt_M_u16	16806
CityParkInputConsistentCount_Cnt_M_u16	63175
CityParkInputInvalidCount_Cnt_M_u16	55020
CityParkInputMsgTimer_mS_M_u32	1444645632
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2630337024
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	59269
ComputerRazGCTSigInvalidTimer_mS_M_u32	3711361536
ComputerRazGCTSigValidCount_Cnt_M_u16	44764
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	15112
DMDFCTCPKSigValidCount_Cnt_M_u16	7699
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	30927
DMDRELAXECPKSigValidCount_Cnt_M_u16	51442
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	28014
DateInvalidTimer_mS_M_u32	1918501376
DiagMuxOnAbsentTimer_mS_M_u32	3430715904
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3455070720
ESPNTCEnableTimer_mS_M_u32	467976704
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	31331
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	4
EffacDefaultDiagTimer_mS_M_u32[1]	5
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	99
ElecIntTimer_mS_M_u32[1]	1000
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3718509056
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	29821
EtatMTSigValidCount_Cnt_M_u16	13836
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	59907
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	52598
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	5225
ISDAT4V2BSI552MsgTimer_mS_M_u32	201208320
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	55595
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	13313
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13836
ISDATBSI3F2MsgTimer_mS_M_u32	4220162560
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	2905
ISDATBSI412MsgLenValidCount_Cnt_M_u16	63583
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	29821
ISDATBSI412MsgTimer_mS_M_u32	2957562368
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	33832
ISDATBSI432MsgLenValidCount_Cnt_M_u16	37959
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	45066
ISDATDIRASentFltAcc_Cnt_M_u16	17808
ISDATDIRASentTimer_mS_M_u32	4076458496
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	50749
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	32483
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	30991

Name	Input Value
ISDYN2CMMMsgTimer_mS_M_u32	2458829312
ISDYNAASChkSumInvalidCount_Cnt_M_u16	30867
ISDYNAASChkSumValidCount_Cnt_M_u16	31829
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	17130
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	16998
ISDYNAASMsgLenValidCount_Cnt_M_u16	15265
ISDYNAASMsgTimeValidCount_Cnt_M_u16	30867
ISDYNAASMsgTimer_mS_M_u32	2696323584
ISDYNABRChkSumInvalidCount_Cnt_M_u16	36627
ISDYNABRChkSumValidCount_Cnt_M_u16	40189
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	44826
ISDYNABRMsgCountValidCount_Cnt_M_u16	23068
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	64152
ISDYNABRMsgLenValidCount_Cnt_M_u16	37835
ISDYNABRMsgTimeValidCount_Cnt_M_u16	51375
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	634
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1153
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13836
ISDYNCMM208MsgTimer_mS_M_u32	4263543296
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2387
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1259
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	64241
ISDYNCMM388MsgTimer_mS_M_u32	542777856
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	59423
ISDYNVOLChkSumValidCount_Cnt_M_u16	26770
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	9494
ISDYNVOLMsgCountValidCount_Cnt_M_u16	5793
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	4828
ISDYNVOLMsgLenValidCount_Cnt_M_u16	49070
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	36164
ISDYNVOLMsgTimer_mS_M_u32	4065518080
IgnOnTimer_mS_M_u32	3476955648
IgnTimeOff_Sec_M_u32	798905813
ManVehSpd_Kph_M_f32	563.419495
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	89
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	24
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	331387392
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	129
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1008759296
PrevISDATBSI412MsgDLCError_Cnt_M_u08	86
PrevISDATBSI412MsgRxTime_MSec_M_u32	1834443264
PrevISDATBSI432MsgDLCError_Cnt_M_u08	66
PrevISDATBSI432MsgRxTime_MSec_M_u32	1547223552
PrevISDATDIRAMsgTxTime_MSec_M_u32	709583360
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	186
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1162195456
PrevISDYNAASMsgDLCError_Cnt_M_u08	245
PrevISDYNAASMsgRxTime_MSec_M_u32	937484800
PrevISDYNABRMsgDLCError_Cnt_M_u08	131
PrevISDYNABRMsgRxTime_MSec_M_u32	880157184
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	76
PrevISDYNCMM208MsgRxTime_MSec_M_u32	28697088
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	250
PrevISDYNCMM388MsgRxTime_MSec_M_u32	786678272
PrevISDYNVOLMsgDLCError_Cnt_M_u08	229
PrevISDYNVOLMsgRxTime_MSec_M_u32	3775160832
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4166439424
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	81.9561996
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal

Name	Input Value
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	45684
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	14895
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	32877
VitesseVehicleBVRampValidCount_Cnt_M_u16	49384
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	13654
VitesseVehicleBVSigValidCount_Cnt_M_u16	44217
VitesseVehicleBV_Kph_M_f32	393.879395
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	64241
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	32523
VitesseVehiculeRoues_Kph_M_f32	400.112488
k_AASNTCEnableTimeout_mS_u16	18094
k_AASNodeAbsentDiag_Cnt_str.Threshold	51008
k_AASNodeAbsentDiag_Cnt_str.PStep	38595
k_AASNodeAbsentDiag_Cnt_str.NStep	19783
k_AASNodeAbsentTimeout_mS_u16	7686
k_AASNodeTimeout_mS_u16	48431
k_ABSNodeTimeout_mS_u16	19229
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	62603
k_ANGLEVOLANTSigValidThresh_Cnt_u16	39146
k_AngleVolantInvalidThresh_Cnt_u16	22841
k_AngleVolantValidThresh_Cnt_u16	55020
k_BSI552MsgTimeout_mS_u16	2074
k_BSINTCEnableTimeout_mS_u16	2
k_BSINodeAbsentDiag_Cnt_str.Threshold	22772
k_BSINodeAbsentDiag_Cnt_str.PStep	35862
k_BSINodeAbsentDiag_Cnt_str.NStep	13187
k_BSINodeAbsentTimeout_mS_u16	54326
k_BSINodeTimeout_mS_u16	45066
k_BattOvHi_Volt_f32	1.7335
k_BattOvLo_Volt_f32	24.0279999
k_BattUvHi_Volt_f32	18.7607002
k_BattUvLo_Volt_f32	18.8194008
k_CAVNTCEnableTimeout_mS_u16	44082
k_CAVNodeAbsentDiag_Cnt_str.Threshold	37776
k_CAVNodeAbsentDiag_Cnt_str.PStep	60468
k_CAVNodeAbsentDiag_Cnt_str.NStep	39899
k_CAVNodeAbsentTimeout_mS_u16	17289
k_CAVNodeTimeout_mS_u16	25133
k_CMM388MsgTimeout_mS_u16	40097
k_CMM388NTCEnableTimeout_mS_u16	52925
k_CMMNTCEnableTimeout_mS_u16	2659
k_CMMNodeAbsentDiag_Cnt_str.Threshold	59742
k_CMMNodeAbsentDiag_Cnt_str.PStep	37709
k_CMMNodeAbsentDiag_Cnt_str.NStep	44571
k_CMMNodeAbsentTimeout_mS_u16	34599
k_CONSANGLECPKMax_HwDeg_f32	548.953796
k_CONSANGLECPKMin_HwDeg_f32	-427.792603
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	15857
k_CONSANGLECPKSigValidThresh_Cnt_u16	523
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	44677
k_CPKVehicleSpeedValidThresh_Cnt_u16	60164
k_CityParkInputInvalidThresh_Cnt_u16	7401
k_CityParkInputValidThresh_Cnt_u16	63175
k_ComputerRazGCTSigValidThresh_Cnt_u16	39905
k_CptTemporelSigValidThresh_Cnt_u16	45879
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	48536
k_DMDFCTCPKSigValidThresh_Cnt_u16	38603
k_DMDFCTCPKValidCount_Cnt_u16	5676
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	30991
k_DMDRELAXECPKSigValidThresh_Cnt_u16	41818
k_DMDRelaxeConsistentThresh_Cnt_u16	24240

Name	Input Value
k_DateValidThresh_Cnt_u16	5225
k_DefaultVehSpd_Kph_f32	197.585693
k_DiagMuxOnAbsentTimeout_mS_u16	57205
k_EMNodeTimeout_mS_u16	41678
k_ESPNTCEnableTimeout_mS_u16	15255
k_ESPNodeAbsentDiag_Cnt_str.Threshold	55926
k_ESPNodeAbsentDiag_Cnt_str.PStep	43742
k_ESPNodeAbsentDiag_Cnt_str.NStep	22171
k_ESPNodeAbsentTimeout_mS_u16	14831
k_EtatMTSigInvalidThresh_Cnt_u16	50498
k_EtatMTSigValidThresh_Cnt_u16	26732
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	5136
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	5758
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	63168
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	21416
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	33342
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	51261
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	38949
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	39940
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	47884
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	47859
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	45081
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	19883
k_ISDATDIRASentDiag_Cnt_str.Threshold	42509
k_ISDATDIRASentDiag_Cnt_str.PStep	65253
k_ISDATDIRASentDiag_Cnt_str.NStep	44071
k_ISDATDIRASentTimeout_mS_u16	11823
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	39680
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	36094
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	22595
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	53779
k_ISDYNAASChkSumValidThresh_Cnt_u16	8189
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	29210
k_ISDYNAASMsgCountValidThresh_Cnt_u16	23836
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	29431
k_ISDYNAASMsgLenValidThresh_Cnt_u16	3347
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	43442
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	36006
k_ISDYNABRChkSumValidThresh_Cnt_u16	13401
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	19812
k_ISDYNABRMsgCountValidThresh_Cnt_u16	21319
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	4164
k_ISDYNABRMsgLenValidThresh_Cnt_u16	15715
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	49622
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	41560
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	3218
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	60734
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	43229
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	34688
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	8740
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	21564
k_ISDYNVOLChkSumValidThresh_Cnt_u16	13698
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	64704
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	25569
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	56473
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	47912
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	25135
k_IgnOnTimeout_mS_u16	59224
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	225.279602
k_PowerCutVehSpdLowThresh_Kph_f32	58.2248993
k_PowerCutVehSpdLowTimeout_mS_u16	28602
k_VBattMaxAAS_Volt_f32	4.39309978
k_VBattMaxBSI_Volt_f32	20.5622997
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	32
k_VBattMaxCMM_Volt_f32	12.2750998
k_VBattMaxESP_Volt_f32	13.3511
k_VBattMinAAS_Volt_f32	26.0949001
k_VBattMinBSI_Volt_f32	2.5631001
k_VBattMinCAV_Volt_f32	30.0652008
k_VBattMinCMM388_Volt_f32	13.3045998
k_VBattMinCMM_Volt_f32	23.3341007

Name	Input Value
k_VBattMinESP_Volt_f32	12.2750998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	62634
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	38945
k_VitesseVehicleBVRampValidThresh_Cnt_u16	26646
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	27538
k_VitesseVehicleBVSigValidThresh_Cnt_u16	59896
k_VitesseVehicleBVSpeedPassThresh_kph_f32	539.15448
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	7035
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	10870
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1918501376
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	143
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	35587
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3629062400
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	250
target_SrlComInput_Per1_Batt_Volt_f32.value	14.4320002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	382923264
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	217
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.435465544
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	213
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1899504128
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2291614208
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2814796288
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1455784448
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	496280064
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	236
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2217984512
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	149
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	312664576
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	36
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	100
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	170
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	212
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4062085632
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	44
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	58
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	110
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	193
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3389202944
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1289896448
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	232
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2542887424
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	72
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4129452544
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3316
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.361012906
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	416842
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	152.849197
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	9630

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3629062400	3629062400	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	51008	51008	✔
AASNodeAbsentTimer_mS_M_u32	3629062400	3629062400	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3629062400	3629062400	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-399.783722	-399.783722	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	30114304	30114304	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	3629062400	3629062400	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3938021888	3938021888	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	3455070720	3455070720	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3629062400	3629062400	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3629062400	3629062400	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	37776	37776	✔
CAVNodeAbsentTimer_mS_M_u32	3629062400	3629062400	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3629062400	3629062400	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3629062400	3629062400	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2217984512	2217984512	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	51375	51375	✔
CONSANGLECPK_HwDeg_M_f32	365.564606	365.564606 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3629062400	3629062400	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3629062400	3629062400	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3629062400	3629062400	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3629062400	3629062400	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3629062400	3629062400	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3629062400	3629062400	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3629062400	3629062400	✔
ESPNTCEnableTimer_mS_M_u32	3629062400	3629062400	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3629062400	3629062400	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4	4	✔
EffacDefaultDiagTimer_mS_M_u32[1]	5	5	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3629062400	3629062400	✔
ElecIntTimer_mS_M_u32[1]	1000	1000	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3629062400	3629062400	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1899504128	1899504128	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2291614208	2291614208	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3629062400	3629062400	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1455784448	1455784448	✔
ISDATDIRASentFltAcc_Cnt_M_u16	42509	42509	✔
ISDATDIRASentTimer_mS_M_u32	3629062400	3629062400	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3629062400	3629062400	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3629062400	3629062400	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3629062400	3629062400	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3629062400	3629062400	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3629062400	3629062400	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3629062400	3629062400	✔
IgnOnTimer_mS_M_u32	3476955648	3476955648	✔
IgnTimeOff_Sec_M_u32	798905813	798905813	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	213	213	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1899504128	1899504128	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	220	220	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2291614208	2291614208	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2814796288	2814796288	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	60	60	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1455784448	1455784448	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	709583360	709583360	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	236	236	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2217984512	2217984512	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	149	149	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	312664576	312664576	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	216	216	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4062085632	4062085632	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	193	193	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3389202944	3389202944	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	210	210	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1289896448	1289896448	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	232	232	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2542887424	2542887424	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4129452544	4129452544	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	81.9561996	81.9561996	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	393.879395	393.879395	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	400.112488	400.112488	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-399.783722	-399.783722	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	51375	51375	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	798905813	798905813	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	365.564606	365.564606 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	197.585693	197.585693	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.62 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4223028480
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	6786
AASNodeAbsentTimer_mS_M_u32	2038136064
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	34765
ANGLEVOLANTSigValidCount_Cnt_M_u16	33189
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	46187
AngleVolantMsgTimer_mS_M_u32	4223028480
AngleVolantValidCount_Cnt_M_u16	23356
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-391.523163
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1187265792
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1327021312
BSI412NTCsEnabled_Cnt_M_lgc	1

Name	Input Value
BSI432NTCEnableTimer_mS_M_u32	4021972224
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2434149632
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	30264
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	4042321152
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	20594
CAVNodeAbsentTimer_mS_M_u32	423861504
CDD_SrlComVehSpd_Kph_G_f32	248.371994
CMM388NTCEnableTimer_mS_M_u32	1238818048
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3158416640
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	28888
CMMNodeAbsentTimer_mS_M_u32	983051520
CONSANGLECPKSigInvalidCount_Cnt_M_u16	46386
CONSANGLECPKSigValidCount_Cnt_M_u16	46362
CONSANGLECPK_Cnt_M_u16	57369
CONSANGLECPK_HwDeg_M_f32	470.27829
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	57369
CPKVehicleSpeedMsgTimer_mS_M_u32	3497610496
CPKVehicleSpeedValidCount_Cnt_M_u16	5274
CityParkInputConsistentCount_Cnt_M_u16	33680
CityParkInputInvalidCount_Cnt_M_u16	2080
CityParkInputMsgTimer_mS_M_u32	1899504128
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3067051264
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	32982
ComputerRazGCTSigInvalidTimer_mS_M_u32	436346112
ComputerRazGCTSigValidCount_Cnt_M_u16	61265
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	19404
DMDFCTCPKSigValidCount_Cnt_M_u16	6253
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	5879
DMDRELAXECPKSigValidCount_Cnt_M_u16	64591
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	9243
DateInvalidTimer_mS_M_u32	1327021312
DiagMuxOnAbsentTimer_mS_M_u32	3203468544
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2434149632
ESPNTCEnableTimer_mS_M_u32	3984096512
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	28477
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	6
EffacDefaultDiagTimer_mS_M_u32[1]	7
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	10
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3774541056
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	12333
EtatMTSigValidCount_Cnt_M_u16	28993
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	16988
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	44484
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	3435
ISDAT4V2BSI552MsgTimer_mS_M_u32	2397842688
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	61348
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	34017
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	28993
ISDATBSI3F2MsgTimer_mS_M_u32	3922136320
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	57882
ISDATBSI412MsgLenValidCount_Cnt_M_u16	32966
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	12333
ISDATBSI412MsgTimer_mS_M_u32	2492222720

Name	Input Value
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	7212
ISDATBSI432MsgLenValidCount_Cnt_M_u16	45457
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	5903
ISDATDIRASentFltAcc_Cnt_M_u16	40243
ISDATDIRASentTimer_mS_M_u32	3497610496
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	40815
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	23356
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	28087
ISDYN2CMMMsgTimer_mS_M_u32	2977594624
ISDYNAASChkSumInvalidCount_Cnt_M_u16	34220
ISDYNAASChkSumValidCount_Cnt_M_u16	53285
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	60199
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	32433
ISDYNAASMsgLenValidCount_Cnt_M_u16	51394
ISDYNAASMsgTimeValidCount_Cnt_M_u16	34220
ISDYNAASMsgTimer_mS_M_u32	2122505472
ISDYNABRChkSumInvalidCount_Cnt_M_u16	39341
ISDYNABRChkSumValidCount_Cnt_M_u16	26029
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	48663
ISDYNABRMsgCountValidCount_Cnt_M_u16	4816
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	42141
ISDYNABRMsgLenValidCount_Cnt_M_u16	61125
ISDYNABRMsgTimeValidCount_Cnt_M_u16	57369
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	635
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1155
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	28993
ISDYNCMM208MsgTimer_mS_M_u32	3854908672
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2391
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1261
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	40722
ISDYNCMM388MsgTimer_mS_M_u32	3986185472
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	47112
ISDYNVOLChkSumValidCount_Cnt_M_u16	19568
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	17826
ISDYNVOLMsgCountValidCount_Cnt_M_u16	59075
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	51666
ISDYNVOLMsgLenValidCount_Cnt_M_u16	22811
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28888
ISDYNVOLMsgTimer_mS_M_u32	1252924672
IgnOnTimer_mS_M_u32	1894538496
IgnTimeOff_Sec_M_u32	1608359821
ManVehSpd_Kph_M_f32	138.780197
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	91
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4179954944
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	69
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1468361984
PrevISDATBSI412MsgDLCError_Cnt_M_u08	0
PrevISDATBSI412MsgRxTime_MSec_M_u32	2342558976
PrevISDATBSI432MsgDLCError_Cnt_M_u08	31
PrevISDATBSI432MsgRxTime_MSec_M_u32	2088533248
PrevISDATDIRAMsgTxTime_MSec_M_u32	616865024
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	127
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1628810496
PrevISDYNAASMsgDLCError_Cnt_M_u08	29
PrevISDYNAASMsgRxTime_MSec_M_u32	839130368
PrevISDYNABRMsgDLCError_Cnt_M_u08	122
PrevISDYNABRMsgRxTime_MSec_M_u32	558128384
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	194
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1753554176
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	127
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1887141120

Name	Input Value
PrevISDYNVOLMsgDLCError_Cnt_M_u08	63
PrevISDYNVOLMsgRxTime_MSec_M_u32	614046976
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1952599296
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	624.939209
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	59015
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	34072
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	41116
VitesseVehicleBVRampValidCount_Cnt_M_u16	5357
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	48482
VitesseVehicleBVSigValidCount_Cnt_M_u16	11514
VitesseVehicleBV_Kph_M_f32	240.392593
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	40722
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	51331
VitesseVehiculeRoues_Kph_M_f32	348.602905
k_AASNTCEnableTimeout_mS_u16	8732
k_AASNodeAbsentDiag_Cnt_str.Threshold	21296
k_AASNodeAbsentDiag_Cnt_str.PStep	48288
k_AASNodeAbsentDiag_Cnt_str.NStep	35149
k_AASNodeAbsentTimeout_mS_u16	51667
k_AASNodeTimeout_mS_u16	64536
k_ABSNodeTimeout_mS_u16	44941
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	5891
k_ANGLEVOLANTSigValidThresh_Cnt_u16	61352
k_AngleVolantInvalidThresh_Cnt_u16	43707
k_AngleVolantValidThresh_Cnt_u16	2080
k_BSI552MsgTimeout_mS_u16	10582
k_BSINTCEnableTimeout_mS_u16	31876
k_BSINodeAbsentDiag_Cnt_str.Threshold	22812
k_BSINodeAbsentDiag_Cnt_str.PStep	35845
k_BSINodeAbsentDiag_Cnt_str.NStep	13210
k_BSINodeAbsentTimeout_mS_u16	48835
k_BSINodeTimeout_mS_u16	5903
k_BattOvHi_Volt_f32	7.57740021
k_BattOvLo_Volt_f32	23.8164997
k_BattUvHi_Volt_f32	18.0048008
k_BattUvLo_Volt_f32	22.6210995
k_CAVNTCEnableTimeout_mS_u16	8270
k_CAVNodeAbsentDiag_Cnt_str.Threshold	31705
k_CAVNodeAbsentDiag_Cnt_str.PStep	54564
k_CAVNodeAbsentDiag_Cnt_str.NStep	10151
k_CAVNodeAbsentTimeout_mS_u16	51016
k_CAVNodeTimeout_mS_u16	478
k_CMM388MsgTimeout_mS_u16	53634
k_CMM388NTCEnableTimeout_mS_u16	43822
k_CMMNTCEnableTimeout_mS_u16	15356
k_CMMNodeAbsentDiag_Cnt_str.Threshold	22712
k_CMMNodeAbsentDiag_Cnt_str.PStep	13283
k_CMMNodeAbsentDiag_Cnt_str.NStep	52401
k_CMMNodeAbsentTimeout_mS_u16	8239
k_CONSANGLECPKMax_HwDeg_f32	413.640686
k_CONSANGLECPKMin_HwDeg_f32	-295.515808
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	54802
k_CONSANGLECPKSigValidThresh_Cnt_u16	16259
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	22
k_CPKVehicleSpeedValidThresh_Cnt_u16	44825
k_CityParkInputInvalidThresh_Cnt_u16	51243
k_CityParkInputValidThresh_Cnt_u16	33680

Name	Input Value
k_ComputerRazGCTSigValidThresh_Cnt_u16	65410
k_CptTemporelSigValidThresh_Cnt_u16	24383
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	23453
k_DMDFCTCPKSigValidThresh_Cnt_u16	58821
k_DMDFCTCPKValidCount_Cnt_u16	62176
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	28087
k_DMDRELAXECPKSigValidThresh_Cnt_u16	25752
k_DMDRelaxeConsistentThresh_Cnt_u16	2710
k_DateValidThresh_Cnt_u16	3435
k_DefaultVehSpd_Kph_f32	113.144203
k_DiagMuxOnAbsentTimeout_mS_u16	13255
k_EMNodeTimeout_mS_u16	1019
k_ESPNTCEnableTimeout_mS_u16	38686
k_ESPNodeAbsentDiag_Cnt_str.Threshold	21200
k_ESPNodeAbsentDiag_Cnt_str.PStep	12176
k_ESPNodeAbsentDiag_Cnt_str.NStep	58000
k_ESPNodeAbsentTimeout_mS_u16	10199
k_EtatMTSigInvalidThresh_Cnt_u16	29472
k_EtatMTSigValidThresh_Cnt_u16	32608
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	47989
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	47594
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	42917
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	46125
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	52778
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	15214
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	5173
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	52826
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	1920
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	6477
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	8090
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	13347
k_ISDATDIRASentDiag_Cnt_str.Threshold	49889
k_ISDATDIRASentDiag_Cnt_str.PStep	42898
k_ISDATDIRASentDiag_Cnt_str.NStep	11588
k_ISDATDIRASentTimeout_mS_u16	11353
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	57380
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	46187
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	61722
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	53421
k_ISDYNAASChkSumValidThresh_Cnt_u16	56493
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	29975
k_ISDYNAASMsgCountValidThresh_Cnt_u16	2512
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	32257
k_ISDYNAASMsgLenValidThresh_Cnt_u16	40044
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	56656
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	42611
k_ISDYNABRChkSumValidThresh_Cnt_u16	50459
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	11576
k_ISDYNABRMsgCountValidThresh_Cnt_u16	61776
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	59352
k_ISDYNABRMsgLenValidThresh_Cnt_u16	9789
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	41379
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	42715
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	623
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	26603
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	16077
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	30885
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	1656
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	21361
k_ISDYNVOLChkSumValidThresh_Cnt_u16	5469
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	39974
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	41217
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	26585
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	20973
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	48153
k_IgnOnTimeout_mS_u16	2589
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	108.562698
k_PowerCutVehSpdLowThresh_Kph_f32	169.726807
k_PowerCutVehSpdLowTimeout_mS_u16	55032
k_VBattMaxAAS_Volt_f32	15.1673002
k_VBattMaxBSI_Volt_f32	4.62930012
k_VBattMaxCAV_Volt_f32	21.9701004

Name	Input Value
k_VBattMaxCMM388_Volt_f32	14.8441
k_VBattMaxCMM_Volt_f32	29.2908001
k_VBattMaxESP_Volt_f32	9.40190029
k_VBattMinAAS_Volt_f32	6.49069977
k_VBattMinBSI_Volt_f32	9.40190029
k_VBattMinCAV_Volt_f32	4.73129988
k_VBattMinCMM388_Volt_f32	12.0226002
k_VBattMinCMM_Volt_f32	11.2925997
k_VBattMinESP_Volt_f32	29.2908001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	64294
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	13955
k_VitesseVehicleBVRampValidThresh_Cnt_u16	31906
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	17264
k_VitesseVehicleBVSigValidThresh_Cnt_u16	44541
k_VitesseVehicleBVSpeedPassThresh_kph_f32	243.623001
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	34674
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	36931
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1327021312
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	141
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	44977
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	4065687552
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	127
target_SrlComInput_Per1_Batt_Volt_f32.value	10.3167
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2976771328
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	3
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.550727665
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	10
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4076756224
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2439052544
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	225
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1481874688
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2950053120
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4293451008
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	157
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2961931520
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	700325120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	102
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	103
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	151
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	229
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2177580288
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	162
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	205

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3567082752
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	813694208
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1962056960
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	119
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2977918208
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1606
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.87578994
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	796429
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	145.104004
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	46345

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4065687552	4065687552	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4065687552	4065687552	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	46187	46187	✔
AngleVolantMsgTimer_mS_M_u32	4065687552	4065687552	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-391.523163	-391.523163	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4065687552	4065687552	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4065687552	4065687552	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4065687552	4065687552	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4065687552	4065687552	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	4065687552	4065687552	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4065687552	4065687552	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	31705	31705	✔
CAVNodeAbsentTimer_mS_M_u32	4065687552	4065687552	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4065687552	4065687552	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4065687552	4065687552	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4065687552	4065687552	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	57369	57369	✔
CONSANGLECPK_HwDeg_M_f32	470.27829	470.27829 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	57369	57369	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3497610496	3497610496	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	5274	5274	✔
CityParkInputConsistentCount_Cnt_M_u16	33680	33680	✔
CityParkInputInvalidCount_Cnt_M_u16	2082	2082	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CityParkInputMsgTimer_mS_M_u32	4065687552	4065687552	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4065687552	4065687552	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4065687552	4065687552	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4065687552	4065687552	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4065687552	4065687552	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4065687552	4065687552	✔
ESPNTCEnableTimer_mS_M_u32	4065687552	4065687552	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	21200	21200	✔
ESPNodeAbsentTimer_mS_M_u32	4065687552	4065687552	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4065687552	4065687552	✔
EffacDefaultDiagTimer_mS_M_u32[1]	7	7	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4065687552	4065687552	✔
ElecIntTimer_mS_M_u32[1]	10	10	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4065687552	4065687552	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4065687552	4065687552	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4065687552	4065687552	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4065687552	4065687552	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4065687552	4065687552	✔
ISDATDIRASentFltAcc_Cnt_M_u16	49889	49889	✔
ISDATDIRASentTimer_mS_M_u32	4065687552	4065687552	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4065687552	4065687552	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4065687552	4065687552	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4065687552	4065687552	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4065687552	4065687552	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4065687552	4065687552	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4065687552	4065687552	✔
IgnOnTimer_mS_M_u32	1894538496	1894538496	✔
IgnTimeOff_Sec_M_u32	1608359821	1608359821	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4076756224	4076756224	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	59	59	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2439052544	2439052544	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	225	225	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1481874688	1481874688	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	99	99	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2950053120	2950053120	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	616865024	616865024	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	157	157	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2961931520	2961931520	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	37	37	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	700325120	700325120	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	51	51	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2177580288	2177580288	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	53	53	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3567082752	3567082752	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	67	67	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	813694208	813694208	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	135	135	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1962056960	1962056960	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2977918208	2977918208	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	624.939209	624.939209	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	240.392593	240.392593	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	348.602905	348.602905	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-391.523163	-391.523163	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	57369	57369	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1608359821	1608359821	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	470.27829	470.27829 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.63 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1441782784
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	52106
AASNodeAbsentTimer_mS_M_u32	2908769280
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	52650
ANGLEVOLANTSigValidCount_Cnt_M_u16	24288
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	57807
AngleVolantMsgTimer_mS_M_u32	1441782784
AngleVolantValidCount_Cnt_M_u16	30685
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-146.011047
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1485179904
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	831032320
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	845380608
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1833974784
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	28265

Name	Input Value
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	683670528
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	37433
CAVNodeAbsentTimer_mS_M_u32	2525490176
CDD_SrlComVehSpd_Kph_G_f32	537.627014
CMM388NTCEnableTimer_mS_M_u32	1640901632
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	630057984
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	29896
CMMNodeAbsentTimer_mS_M_u32	4174003200
CONSANGLECPKSigInvalidCount_Cnt_M_u16	51324
CONSANGLECPKSigValidCount_Cnt_M_u16	34690
CONSANGLECPK_Cnt_M_u16	49797
CONSANGLECPK_HwDeg_M_f32	245.601303
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	49797
CPKVehicleSpeedMsgTimer_mS_M_u32	2745621504
CPKVehicleSpeedValidCount_Cnt_M_u16	59083
CityParkInputConsistentCount_Cnt_M_u16	20193
CityParkInputInvalidCount_Cnt_M_u16	21040
CityParkInputMsgTimer_mS_M_u32	4076756224
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1164200960
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	59534
ComputerRazGCTSigInvalidTimer_mS_M_u32	2924243968
ComputerRazGCTSigValidCount_Cnt_M_u16	20382
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	14124
DMDFCTCPKSigValidCount_Cnt_M_u16	28682
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	18476
DMDRELAXECPKSigValidCount_Cnt_M_u16	5858
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	24513
DateInvalidTimer_mS_M_u32	831032320
DiagMuxOnAbsentTimer_mS_M_u32	1732221952
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1833974784
ESPNTCEnableTimer_mS_M_u32	2238270464
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	10330
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	947804928
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	947804928
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	10615808
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	55243
EtatMTSigValidCount_Cnt_M_u16	33613
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	18686
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	50564
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	2320
ISDAT4V2BSI552MsgTimer_mS_M_u32	1271806976
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	53475
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	8173
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	33613
ISDATBSI3F2MsgTimer_mS_M_u32	3200097280
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	24196
ISDATBSI412MsgLenValidCount_Cnt_M_u16	20797
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	55243
ISDATBSI412MsgTimer_mS_M_u32	1668144128
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	49868
ISDATBSI432MsgLenValidCount_Cnt_M_u16	45406
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	62050
ISDATDIRASentFltAcc_Cnt_M_u16	61430
ISDATDIRASentTimer_mS_M_u32	2745621504

Name	Input Value
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	23683
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	30685
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	15723
ISDYN2CMMMsgTimer_mS_M_u32	3244510208
ISDYNAASChkSumInvalidCount_Cnt_M_u16	45580
ISDYNAASChkSumValidCount_Cnt_M_u16	53602
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	13340
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	50044
ISDYNAASMsgLenValidCount_Cnt_M_u16	17418
ISDYNAASMsgTimeValidCount_Cnt_M_u16	45580
ISDYNAASMsgTimer_mS_M_u32	1942629376
ISDYNABRChkSumInvalidCount_Cnt_M_u16	28555
ISDYNABRChkSumValidCount_Cnt_M_u16	10825
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	29899
ISDYNABRMsgCountValidCount_Cnt_M_u16	30049
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	26171
ISDYNABRMsgLenValidCount_Cnt_M_u16	18049
ISDYNABRMsgTimeValidCount_Cnt_M_u16	49797
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	636
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1157
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	33613
ISDYNCMM208MsgTimer_mS_M_u32	3213036544
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2395
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1263
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	33883
ISDYNCMM388MsgTimer_mS_M_u32	1552526336
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	38906
ISDYNVOLChkSumValidCount_Cnt_M_u16	39296
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	8618
ISDYNVOLMsgCountValidCount_Cnt_M_u16	56584
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	44187
ISDYNVOLMsgLenValidCount_Cnt_M_u16	15745
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	29896
ISDYNVOLMsgTimer_mS_M_u32	3427298304
IgnOnTimer_mS_M_u32	579709952
IgnTimeOff_Sec_M_u32	2485470661
ManVehSpd_Kph_M_f32	47.9001007
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	93
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	242
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2292423680
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	225
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3875699712
PrevISDATBSI412MsgDLCError_Cnt_M_u08	255
PrevISDATBSI412MsgRxTime_MSec_M_u32	4084263936
PrevISDATBSI432MsgDLCError_Cnt_M_u08	3
PrevISDATBSI432MsgRxTime_MSec_M_u32	3898428416
PrevISDATDIRAMsgTxTime_MSec_M_u32	3087330304
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	130
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1532083200
PrevISDYNAASMsgDLCError_Cnt_M_u08	190
PrevISDYNAASMsgRxTime_MSec_M_u32	3997592576
PrevISDYNABRMsgDLCError_Cnt_M_u08	140
PrevISDYNABRMsgRxTime_MSec_M_u32	1904585728
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	213
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2395171840
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	71
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3361754112
PrevISDYNVOLMsgDLCError_Cnt_M_u08	126
PrevISDYNVOLMsgRxTime_MSec_M_u32	1283845120
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2615925760
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	151.435303

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	25594
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	59144
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	51643
VitesseVehicleBVRampValidCount_Cnt_M_u16	52105
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	49387
VitesseVehicleBVSigValidCount_Cnt_M_u16	61665
VitesseVehicleBV_Kph_M_f32	307.746185
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	33883
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	59081
VitesseVehiculeRoues_Kph_M_f32	258.726807
k_AASNTCEnableTimeout_mS_u16	51324
k_AASNodeAbsentDiag_Cnt_str.Threshold	19677
k_AASNodeAbsentDiag_Cnt_str.PStep	26788
k_AASNodeAbsentDiag_Cnt_str.NStep	4598
k_AASNodeAbsentTimeout_mS_u16	18456
k_AASNodeTimeout_mS_u16	33288
k_ABSNodeTimeout_mS_u16	20457
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	60999
k_ANGLEVOLANTSigValidThresh_Cnt_u16	4889
k_AngleVolantInvalidThresh_Cnt_u16	60896
k_AngleVolantValidThresh_Cnt_u16	21040
k_BSI552MsgTimeout_mS_u16	53328
k_BSINTCEnableTimeout_mS_u16	452
k_BSINodeAbsentDiag_Cnt_str.Threshold	22852
k_BSINodeAbsentDiag_Cnt_str.PStep	35828
k_BSINodeAbsentDiag_Cnt_str.NStep	13233
k_BSINodeAbsentTimeout_mS_u16	8903
k_BSINodeTimeout_mS_u16	62050
k_BattOvHi_Volt_f32	6.12709999
k_BattOvLo_Volt_f32	0.542200029
k_BattUvHi_Volt_f32	17.8187008
k_BattUvLo_Volt_f32	22.0923996
k_CAVNTCEnableTimeout_mS_u16	16806
k_CAVNodeAbsentDiag_Cnt_str.Threshold	35353
k_CAVNodeAbsentDiag_Cnt_str.PStep	13456
k_CAVNodeAbsentDiag_Cnt_str.NStep	63647
k_CAVNodeAbsentTimeout_mS_u16	1463
k_CAVNodeTimeout_mS_u16	37496
k_CMM388MsgTimeout_mS_u16	42634
k_CMM388NTCEnableTimeout_mS_u16	51590
k_CMMNTCEnableTimeout_mS_u16	19419
k_CMMNodeAbsentDiag_Cnt_str.Threshold	30886
k_CMMNodeAbsentDiag_Cnt_str.PStep	15420
k_CMMNodeAbsentDiag_Cnt_str.NStep	38441
k_CMMNodeAbsentTimeout_mS_u16	36805
k_CONSANGLECPKMax_HwDeg_f32	440.282104
k_CONSANGLECPKMin_HwDeg_f32	-556.062012
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	57179
k_CONSANGLECPKSigValidThresh_Cnt_u16	33225
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	60942
k_CPKVehicleSpeedValidThresh_Cnt_u16	45959
k_CityParkInputInvalidThresh_Cnt_u16	23569
k_CityParkInputValidThresh_Cnt_u16	20193
k_ComputerRazGCTSigValidThresh_Cnt_u16	39241
k_CptTemporelSigValidThresh_Cnt_u16	35027
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	16699
k_DMDFCTCPKSigValidThresh_Cnt_u16	24961
k_DMDFCTCPKValidCount_Cnt_u16	39025

Name	Input Value
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	15723
k_DMDRELAXECPKSigValidThresh_Cnt_u16	63369
k_DMDRelaxeConsistentThresh_Cnt_u16	32143
k_DateValidThresh_Cnt_u16	2320
k_DefaultVehSpd_Kph_f32	120.140602
k_DiagMuxOnAbsentTimeout_mS_u16	65403
k_EMNodeTimeout_mS_u16	16417
k_ESPNTCEnableTimeout_mS_u16	28213
k_ESPNodeAbsentDiag_Cnt_str.Threshold	41533
k_ESPNodeAbsentDiag_Cnt_str.PStep	534
k_ESPNodeAbsentDiag_Cnt_str.NStep	42604
k_ESPNodeAbsentTimeout_mS_u16	6349
k_EtatMTSigInvalidThresh_Cnt_u16	28466
k_EtatMTSigValidThresh_Cnt_u16	26928
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	63473
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	60243
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	30370
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	59208
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	43026
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	41608
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	16049
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	48899
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	20688
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	59113
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	8899
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	7528
k_ISDATDIRASentDiag_Cnt_str.Threshold	14723
k_ISDATDIRASentDiag_Cnt_str.PStep	40390
k_ISDATDIRASentDiag_Cnt_str.NStep	17480
k_ISDATDIRASentTimeout_mS_u16	26503
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	23909
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	57807
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	20545
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	51851
k_ISDYNAASChkSumValidThresh_Cnt_u16	50505
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	20427
k_ISDYNAASMsgCountValidThresh_Cnt_u16	36961
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	4751
k_ISDYNAASMsgLenValidThresh_Cnt_u16	61708
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	59937
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	14521
k_ISDYNABRChkSumValidThresh_Cnt_u16	39807
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	18793
k_ISDYNABRMsgCountValidThresh_Cnt_u16	31711
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	4040
k_ISDYNABRMsgLenValidThresh_Cnt_u16	858
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	30438
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	29438
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	37253
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	19087
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	43178
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	31200
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	46888
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	9855
k_ISDYNVOLChkSumValidThresh_Cnt_u16	44920
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	34207
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	51277
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	57543
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	37193
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	13574
k_IgnOnTimeout_mS_u16	45691
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	154.385193
k_PowerCutVehSpdLowThresh_Kph_f32	10.8929996
k_PowerCutVehSpdLowTimeout_mS_u16	6632
k_VBattMaxAAS_Volt_f32	3.68510008
k_VBattMaxBSI_Volt_f32	24.0198994
k_VBattMaxCAV_Volt_f32	8.51019955
k_VBattMaxCMM388_Volt_f32	14.4840002
k_VBattMaxCMM_Volt_f32	13.0063
k_VBattMaxESP_Volt_f32	23.6562996
k_VBattMinAAS_Volt_f32	25.4290009
k_VBattMinBSI_Volt_f32	23.6562996

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinCAV_Volt_f32	0.253100008
k_VBattMinCMM388_Volt_f32	8.34980011
k_VBattMinCMM_Volt_f32	21.4647007
k_VBattMinESP_Volt_f32	13.0063
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	37983
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	28937
k_VitesseVehicleBVRampValidThresh_Cnt_u16	31914
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	46208
k_VitesseVehicleBVSigValidThresh_Cnt_u16	50074
k_VitesseVehicleBVSpeedPassThresh_kph_f32	293.568207
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	60729
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	12679
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	831032320
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	112
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	24578
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	947804928
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	71
target_SrlComInput_Per1_Batt_Volt_f32.value	2.37150002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	457767936
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	86
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.258604884
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	76
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1683467264
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3685731328
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	425192448
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3847228416
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	127413248
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1211124736
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	234
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1863871488
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	135
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	167
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	218
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	220
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	230
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	248
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	61
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2205223936
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	134
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	229
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	7
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4219120640
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	978504704

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4286245888
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	11
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	28
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	30
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	68
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	172
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	187
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1091861504
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3817
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.254699767
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	199967
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	75.0113983
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	32884

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	947804928	947804928	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	947804928	947804928	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	57809	57809	✔
AngleVolantMsgTimer_mS_M_u32	947804928	947804928	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-146.011047	-146.011047	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	947804928	947804928	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	947804928	947804928	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	947804928	947804928	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	947804928	947804928	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	947804928	947804928	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	947804928	947804928	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	35353	35353	✔
CAVNodeAbsentTimer_mS_M_u32	947804928	947804928	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	947804928	947804928	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	947804928	947804928	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	947804928	947804928	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	49797	49797	✔
CONSANGLECPK_HwDeg_M_f32	245.601303	245.601303 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	49797	49797	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2745621504	2745621504	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	59083	59083	✔
CityParkInputConsistentCount_Cnt_M_u16	20193	20193	✔
CityParkInputInvalidCount_Cnt_M_u16	21042	21042	✔
CityParkInputMsgTimer_mS_M_u32	947804928	947804928	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	947804928	947804928	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ComputerRazGCTSigInvalidTimer_mS_M_u32	947804928	947804928	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	947804928	947804928	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	947804928	947804928	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	947804928	947804928	✔
ESPNTCEnableTimer_mS_M_u32	947804928	947804928	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	41533	41533	✔
ESPNodeAbsentTimer_mS_M_u32	947804928	947804928	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	8	8	✔
EffacDefaultDiagTimer_mS_M_u32[1]	947804928	947804928	✔
ElecIntCount_Cnt_M_u08	2	2	✔
ElecIntTimer_mS_M_u32[0]	4	4	✔
ElecIntTimer_mS_M_u32[1]	947804928	947804928	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	947804928	947804928	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	947804928	947804928	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	947804928	947804928	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	947804928	947804928	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	947804928	947804928	✔
ISDATDIRASentFltAcc_Cnt_M_u16	14723	14723	✔
ISDATDIRASentTimer_mS_M_u32	947804928	947804928	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	947804928	947804928	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	947804928	947804928	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	947804928	947804928	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	947804928	947804928	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	947804928	947804928	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	947804928	947804928	✔
IgnOnTimer_mS_M_u32	579709952	579709952	✔
IgnTimeOff_Sec_M_u32	2485470661	2485470661	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	76	76	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1683467264	1683467264	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	235	235	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3685731328	3685731328	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	109	109	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	425192448	425192448	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	153	153	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3847228416	3847228416	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3087330304	3087330304	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	15	15	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1211124736	1211124736	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	234	234	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1863871488	1863871488	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	61	61	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2205223936	2205223936	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	7	7	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4219120640	4219120640	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	14	14	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	978504704	978504704	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	183	183	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4286245888	4286245888	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1091861504	1091861504	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	151.435303	151.435303	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	307.746185	307.746185	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	258.726807	258.726807	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-146.011047	-146.011047	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	49797	49797	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2485470661	2485470661	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	245.601303	245.601303 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	120.140602	120.140602	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.64 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3829346048
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	3439
AASNodeAbsentTimer_mS_M_u32	1806556928
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	10510
ANGLEVOLANTSigValidCount_Cnt_M_u16	63788
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	7840
AngleVolantMsgTimer_mS_M_u32	3829346048
AngleVolantValidCount_Cnt_M_u16	48374
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-553.340942
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	826056448
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3493142272
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	627330816
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	396234496
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	721
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1414450944
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	32736
CAVNodeAbsentTimer_mS_M_u32	1454833408
CDD_SrlComVehSpd_Kph_G_f32	285.140686
CMM388NTCEnableTimer_mS_M_u32	3722723072
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1101332224

Name	Input Value
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	3318
CMMNodeAbsentTimer_mS_M_u32	3710914304
CONSANGLECPKSigInvalidCount_Cnt_M_u16	44952
CONSANGLECPKSigValidCount_Cnt_M_u16	13895
CONSANGLECPK_Cnt_M_u16	20798
CONSANGLECPK_HwDeg_M_f32	163.427597
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	20798
CPKVehicleSpeedMsgTimer_mS_M_u32	2535075584
CPKVehicleSpeedValidCount_Cnt_M_u16	48917
CityParkInputConsistentCount_Cnt_M_u16	18410
CityParkInputInvalidCount_Cnt_M_u16	35580
CityParkInputMsgTimer_mS_M_u32	1683467264
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3013730048
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	50787
ComputerRazGCTSigInvalidTimer_mS_M_u32	3244916480
ComputerRazGCTSigValidCount_Cnt_M_u16	31155
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	52232
DMDFCTCPKSigValidCount_Cnt_M_u16	17710
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	16776
DMDRELAXECPKSigValidCount_Cnt_M_u16	22822
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	15817
DateInvalidTimer_mS_M_u32	3493142272
DiagMuxOnAbsentTimer_mS_M_u32	2672815872
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	396234496
ESPNTCEnableTimer_mS_M_u32	1200807680
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	58880
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	11
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1100
ElecIntTimer_mS_M_u32[1]	1152
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3567832832
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	236
EtatMTSigValidCount_Cnt_M_u16	45606
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	46610
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1089
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	4636
ISDAT4V2BSI552MsgTimer_mS_M_u32	4096003840
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	28451
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	21957
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	45606
ISDATBSI3F2MsgTimer_mS_M_u32	282455808
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	38722
ISDATBSI412MsgLenValidCount_Cnt_M_u16	21204
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	236
ISDATBSI412MsgTimer_mS_M_u32	868560640
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	13034
ISDATBSI432MsgLenValidCount_Cnt_M_u16	23284
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	17253
ISDATDIRASentFltAcc_Cnt_M_u16	39593
ISDATDIRASentTimer_mS_M_u32	2535075584
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	64324
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	48374
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	30027
ISDYN2CMMMsgTimer_mS_M_u32	4221886208
ISDYNAASChkSumInvalidCount_Cnt_M_u16	57833
ISDYNAASChkSumValidCount_Cnt_M_u16	34727
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	17465
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	47127

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNAASMsgLenValidCount_Cnt_M_u16	6701
ISDYNAASMsgTimeValidCount_Cnt_M_u16	57833
ISDYNAASMsgTimer_mS_M_u32	2549104384
ISDYNABRChkSumInvalidCount_Cnt_M_u16	48365
ISDYNABRChkSumValidCount_Cnt_M_u16	12403
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	21932
ISDYNABRMsgCountValidCount_Cnt_M_u16	22442
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	37467
ISDYNABRMsgLenValidCount_Cnt_M_u16	46410
ISDYNABRMsgTimeValidCount_Cnt_M_u16	20798
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	637
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1159
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	45606
ISDYNCMM208MsgTimer_mS_M_u32	809869056
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2399
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1265
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	3964
ISDYNCMM388MsgTimer_mS_M_u32	1001504512
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	47390
ISDYNVOLChkSumValidCount_Cnt_M_u16	30797
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	33934
ISDYNVOLMsgCountValidCount_Cnt_M_u16	30260
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	40253
ISDYNVOLMsgLenValidCount_Cnt_M_u16	11851
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	3318
ISDYNVOLMsgTimer_mS_M_u32	1467318016
IgnOnTimer_mS_M_u32	4188389120
IgnTimeOff_Sec_M_u32	1682908548
ManVehSpd_Kph_M_f32	271.787598
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	95
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	169
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3408129792
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	8
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1132941056
PrevISDATBSI412MsgDLCError_Cnt_M_u08	111
PrevISDATBSI412MsgRxTime_MSec_M_u32	603717376
PrevISDATBSI432MsgDLCError_Cnt_M_u08	150
PrevISDATBSI432MsgRxTime_MSec_M_u32	4004962048
PrevISDATDIRAMsgTxTime_MSec_M_u32	641728256
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	49
PrevISDYN2CMMMsgRxTime_MSec_M_u32	865701632
PrevISDYNAASMsgDLCError_Cnt_M_u08	61
PrevISDYNAASMsgRxTime_MSec_M_u32	1769701120
PrevISDYNABRMsgDLCError_Cnt_M_u08	35
PrevISDYNABRMsgRxTime_MSec_M_u32	3971858176
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	231
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3154411264
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	149
PrevISDYNCMM388MsgRxTime_MSec_M_u32	447602432
PrevISDYNVOLMsgDLCError_Cnt_M_u08	143
PrevISDYNVOLMsgRxTime_MSec_M_u32	2898067200
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	38481664
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	525.865112
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	20125

Name	Input Value
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	43315
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	24922
VitesseVehicleBVRampValidCount_Cnt_M_u16	16304
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	37707
VitesseVehicleBVSigValidCount_Cnt_M_u16	34601
VitesseVehicleBV_Kph_M_f32	423.559906
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	3964
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	19442
VitesseVehiculeRoues_Kph_M_f32	400.123596
k_AASNTCEnableTimeout_mS_u16	56153
k_AASNodeAbsentDiag_Cnt_str.Threshold	30562
k_AASNodeAbsentDiag_Cnt_str.PStep	31683
k_AASNodeAbsentDiag_Cnt_str.NStep	45512
k_AASNodeAbsentTimeout_mS_u16	63557
k_AASNodeTimeout_mS_u16	55347
k_ABSNodeTimeout_mS_u16	46545
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	23673
k_ANGLEVOLANTSigValidThresh_Cnt_u16	57795
k_AngleVolantInvalidThresh_Cnt_u16	11630
k_AngleVolantValidThresh_Cnt_u16	35580
k_BSI552MsgTimeout_mS_u16	27485
k_BSINTCEnableTimeout_mS_u16	22018
k_BSINodeAbsentDiag_Cnt_str.Threshold	22892
k_BSINodeAbsentDiag_Cnt_str.PStep	35811
k_BSINodeAbsentDiag_Cnt_str.NStep	13256
k_BSINodeAbsentTimeout_mS_u16	15288
k_BSINodeTimeout_mS_u16	17253
k_BattOvHi_Volt_f32	17.0778008
k_BattOvLo_Volt_f32	1.93540001
k_BattUvHi_Volt_f32	15.5818996
k_BattUvLo_Volt_f32	13.3930998
k_CAVNTCEnableTimeout_mS_u16	5274
k_CAVNodeAbsentDiag_Cnt_str.Threshold	31239
k_CAVNodeAbsentDiag_Cnt_str.PStep	46999
k_CAVNodeAbsentDiag_Cnt_str.NStep	39075
k_CAVNodeAbsentTimeout_mS_u16	40294
k_CAVNodeTimeout_mS_u16	16804
k_CMM388MsgTimeout_mS_u16	31855
k_CMM388NTCEnableTimeout_mS_u16	891
k_CMMNTCEnableTimeout_mS_u16	56891
k_CMMNodeAbsentDiag_Cnt_str.Threshold	48870
k_CMMNodeAbsentDiag_Cnt_str.PStep	54493
k_CMMNodeAbsentDiag_Cnt_str.NStep	47629
k_CMMNodeAbsentTimeout_mS_u16	16638
k_CONSANGLECPKMax_HwDeg_f32	473.189087
k_CONSANGLECPKMin_HwDeg_f32	-427.338409
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	65148
k_CONSANGLECPKSigValidThresh_Cnt_u16	31474
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	11297
k_CPKVehicleSpeedValidThresh_Cnt_u16	25657
k_CityParkInputInvalidThresh_Cnt_u16	36699
k_CityParkInputValidThresh_Cnt_u16	18410
k_ComputerRazGCTSigValidThresh_Cnt_u16	11761
k_CptTemporelSigValidThresh_Cnt_u16	13075
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	347
k_DMDFCTCPKSigValidThresh_Cnt_u16	25674
k_DMDFCTCPKValidCount_Cnt_u16	42169
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	30027
k_DMDRELAXECPKSigValidThresh_Cnt_u16	27313
k_DMDRelaxeConsistentThresh_Cnt_u16	28831
k_DateValidThresh_Cnt_u16	4636
k_DefaultVehSpd_Kph_f32	246.136002
k_DiagMuxOnAbsentTimeout_mS_u16	62044
k_EMNodeTimeout_mS_u16	7337
k_ESPNTCEnableTimeout_mS_u16	56300
k_ESPNodeAbsentDiag_Cnt_str.Threshold	31363

Name	Input Value
k_ESPNodeAbsentDiag_Cnt_str.PStep	55471
k_ESPNodeAbsentDiag_Cnt_str.NStep	5028
k_ESPNodeAbsentTimeout_mS_u16	50662
k_EtatMTSigInvalidThresh_Cnt_u16	6648
k_EtatMTSigValidThresh_Cnt_u16	53182
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	23160
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	46099
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	5287
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	65524
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	37206
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	56118
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	37691
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	1541
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	39134
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	29714
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	54340
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	15253
k_ISDATDIRASentDiag_Cnt_str.Threshold	56903
k_ISDATDIRASentDiag_Cnt_str.PStep	55926
k_ISDATDIRASentDiag_Cnt_str.NStep	41001
k_ISDATDIRASentTimeout_mS_u16	50425
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	44958
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	7840
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	26056
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	44013
k_ISDYNAASChkSumValidThresh_Cnt_u16	24435
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	50348
k_ISDYNAASMsgCountValidThresh_Cnt_u16	1706
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	58337
k_ISDYNAASMsgLenValidThresh_Cnt_u16	39719
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	31915
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	37601
k_ISDYNABRChkSumValidThresh_Cnt_u16	11856
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	29137
k_ISDYNABRMsgCountValidThresh_Cnt_u16	24111
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	15350
k_ISDYNABRMsgLenValidThresh_Cnt_u16	21760
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	18714
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	12689
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16959
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	23198
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	38926
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	43052
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	15380
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	60241
k_ISDYNVOLChkSumValidThresh_Cnt_u16	58403
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	8753
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	26215
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	54776
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	30770
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	58938
k_IgnOnTimeout_mS_u16	14173
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	81.9020996
k_PowerCutVehSpdLowThresh_Kph_f32	136.378601
k_PowerCutVehSpdLowTimeout_mS_u16	38677
k_VBattMaxAAS_Volt_f32	31.2977009
k_VBattMaxBSI_Volt_f32	4.13129997
k_VBattMaxCAV_Volt_f32	7.12239981
k_VBattMaxCMM388_Volt_f32	2.4138999
k_VBattMaxCMM_Volt_f32	13.2600002
k_VBattMaxESP_Volt_f32	29.3598995
k_VBattMinAAS_Volt_f32	11.9245996
k_VBattMinBSI_Volt_f32	29.3598995
k_VBattMinCAV_Volt_f32	13.8146
k_VBattMinCMM388_Volt_f32	31.6123009
k_VBattMinCMM_Volt_f32	25.4930992
k_VBattMinESP_Volt_f32	13.2600002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	29360
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	12403
k_VitesseVehicleBVRampValidThresh_Cnt_u16	29582
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	10061
k_VitesseVehicleBVSigValidThresh_Cnt_u16	3519

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VitesseVehicleBVSpeedPassThresh_kph_f32	479.554108
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	28384
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	34230
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3493142272
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	54
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	25595
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2572136960
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	149
target_SrlComInput_Per1_Batt_Volt_f32.value	13.0804005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3769880320
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	155
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.480567932
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3695689472
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2126470912
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	239533824
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	171
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	853450496
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2491825920
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3678265088
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2936372992
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	114
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	115
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	140
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	188
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	226
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	128
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	477863680
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	55
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	106
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	220
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	234
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	177
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1658765056
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2933284608
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	179
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2816343808
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	13
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	84
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	108
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	157

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	228
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4249964288
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3133
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.494502604
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	624236
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	229.273407
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	24879

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2572136960	2572136960	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2572136960	2572136960	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2572136960	2572136960	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-553.340942	-553.340942	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2572136960	2572136960	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2572136960	2572136960	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2572136960	2572136960	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2572136960	2572136960	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2572136960	2572136960	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2572136960	2572136960	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	31239	31239	✔
CAVNodeAbsentTimer_mS_M_u32	2572136960	2572136960	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2572136960	2572136960	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2572136960	2572136960	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2572136960	2572136960	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	20798	20798	✔
CONSANGLECPK_HwDeg_M_f32	163.427597	163.427597 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2572136960	2572136960	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2572136960	2572136960	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2572136960	2572136960	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2572136960	2572136960	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2572136960	2572136960	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2572136960	2572136960	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2572136960	2572136960	✔
ESPNTCEnableTimer_mS_M_u32	2572136960	2572136960	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	31363	31363	✔
ESPNodeAbsentTimer_mS_M_u32	2572136960	2572136960	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2572136960	2572136960	✔
EffacDefaultDiagTimer_mS_M_u32[1]	11	11	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2572136960	2572136960	✔
ElecIntTimer_mS_M_u32[1]	1152	1152	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2572136960	2572136960	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2572136960	2572136960	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2572136960	2572136960	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2572136960	2572136960	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2572136960	2572136960	✔
ISDATDIRASentFltAcc_Cnt_M_u16	56903	56903	✔
ISDATDIRASentTimer_mS_M_u32	2572136960	2572136960	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2572136960	2572136960	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2572136960	2572136960	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2572136960	2572136960	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2572136960	2572136960	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2572136960	2572136960	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2572136960	2572136960	✔
IgnOnTimer_mS_M_u32	2572136960	2572136960	✔
IgnTimeOff_Sec_M_u32	1682908548	1682908548	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	151	151	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3695689472	3695689472	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	34	34	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2126470912	2126470912	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	239533824	239533824	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	171	171	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	853450496	853450496	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	641728256	641728256	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	216	216	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3678265088	3678265088	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	240	240	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2936372992	2936372992	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	128	128	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	477863680	477863680	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	177	177	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1658765056	1658765056	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	5	5	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2933284608	2933284608	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	179	179	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2816343808	2816343808	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4249964288	4249964288	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	525.865112	525.865112	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	423.559906	423.559906	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	400.123596	400.123596	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-553.340942	-553.340942	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	20798	20798	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1682908548	1682908548	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	163.427597	163.427597 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.65 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1381840384
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	14539
AASNodeAbsentTimer_mS_M_u32	315696640
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	32752
ANGLEVOLANTSigValidCount_Cnt_M_u16	33877
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	2360
AngleVolantMsgTimer_mS_M_u32	1381840384
AngleVolantValidCount_Cnt_M_u16	3255
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-68.5143356
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1831134720
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	305882624
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	191747584
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1270912512
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	48807
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1219384832
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	36344
CAVNodeAbsentTimer_mS_M_u32	1580582400
CDD_SrlComVehSpd_Kph_G_f32	468.422089
CMM388NTCEnableTimer_mS_M_u32	229508608
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3580610048
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	18552
CMMNodeAbsentTimer_mS_M_u32	3272250880
CONSANGLECPKSigInvalidCount_Cnt_M_u16	34639
CONSANGLECPKSigValidCount_Cnt_M_u16	43013

Name	Input Value
CONSANGLECPK_Cnt_M_u16	62240
CONSANGLECPK_HwDeg_M_f32	-540.999878
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	62240
CPKVehicleSpeedMsgTimer_mS_M_u32	1707881984
CPKVehicleSpeedValidCount_Cnt_M_u16	47522
CityParkInputConsistentCount_Cnt_M_u16	15323
CityParkInputInvalidCount_Cnt_M_u16	35749
CityParkInputMsgTimer_mS_M_u32	3695689472
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	183838208
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	56815
ComputerRazGCTSigInvalidTimer_mS_M_u32	136201728
ComputerRazGCTSigValidCount_Cnt_M_u16	2688
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	63617
DMDFCTCPKSigValidCount_Cnt_M_u16	8654
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	40578
DMDRELAXECPKSigValidCount_Cnt_M_u16	52327
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	57532
DateInvalidTimer_mS_M_u32	305882624
DiagMuxOnAbsentTimer_mS_M_u32	1412101632
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1270912512
ESPNTCEnableTimer_mS_M_u32	1394746880
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	57881
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	21
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2050
ElecIntTimer_mS_M_u32[1]	6072
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2946520576
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	5525
EtatMTSigValidCount_Cnt_M_u16	59046
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	56289
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	42519
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	62212
ISDAT4V2BSI552MsgTimer_mS_M_u32	1311675904
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	48752
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	36682
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	59046
ISDATBSI3F2MsgTimer_mS_M_u32	2543384064
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	54034
ISDATBSI412MsgLenValidCount_Cnt_M_u16	58652
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	5525
ISDATBSI412MsgTimer_mS_M_u32	4224398848
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	42652
ISDATBSI432MsgLenValidCount_Cnt_M_u16	21309
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	38761
ISDATDIRASentFltAcc_Cnt_M_u16	41373
ISDATDIRASentTimer_mS_M_u32	1707881984
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	36110
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	3255
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	51384
ISDYN2CMMMsgTimer_mS_M_u32	4276889088
ISDYNAASChkSumInvalidCount_Cnt_M_u16	9053
ISDYNAASChkSumValidCount_Cnt_M_u16	9955
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	17134
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	33107
ISDYNAASMsgLenValidCount_Cnt_M_u16	45008
ISDYNAASMsgTimeValidCount_Cnt_M_u16	9053
ISDYNAASMsgTimer_mS_M_u32	260703744
ISDYNABRChkSumInvalidCount_Cnt_M_u16	22483
ISDYNABRChkSumValidCount_Cnt_M_u16	4609

Name	Input Value
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	37908
ISDYNABRMsgCountValidCount_Cnt_M_u16	33498
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	43782
ISDYNABRMsgLenValidCount_Cnt_M_u16	63228
ISDYNABRMsgTimeValidCount_Cnt_M_u16	62240
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	638
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1161
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	59046
ISDYNCMM208MsgTimer_mS_M_u32	3557418496
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2403
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1267
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	44325
ISDYNCMM388MsgTimer_mS_M_u32	172328448
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	701
ISDYNVOLChkSumValidCount_Cnt_M_u16	31219
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	26351
ISDYNVOLMsgCountValidCount_Cnt_M_u16	9916
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	61538
ISDYNVOLMsgLenValidCount_Cnt_M_u16	29175
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	18552
ISDYNVOLMsgTimer_mS_M_u32	1979336192
IgnOnTimer_mS_M_u32	2691270144
IgnTimeOff_Sec_M_u32	1590348666
ManVehSpd_Kph_M_f32	361.702209
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	97
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	52
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	548337152
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	142
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4244952576
PrevISDATBSI412MsgDLCError_Cnt_M_u08	197
PrevISDATBSI412MsgRxTime_MSec_M_u32	1248249344
PrevISDATBSI432MsgDLCError_Cnt_M_u08	12
PrevISDATBSI432MsgRxTime_MSec_M_u32	3988137472
PrevISDATDIRAMsgTxTime_MSec_M_u32	1402652160
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	237
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1171133952
PrevISDYNAASMsgDLCError_Cnt_M_u08	136
PrevISDYNAASMsgRxTime_MSec_M_u32	3622323712
PrevISDYNABRMsgDLCError_Cnt_M_u08	234
PrevISDYNABRMsgRxTime_MSec_M_u32	656508416
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	190
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1145914880
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	171
PrevISDYNCMM388MsgRxTime_MSec_M_u32	97592832
PrevISDYNVOLMsgDLCError_Cnt_M_u08	228
PrevISDYNVOLMsgRxTime_MSec_M_u32	4095985152
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	674838016
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	530.780273
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	21953
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	39614
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0

Name	Input Value
VehSpdSync_Cnt_M_Igc	1
VehTimeValid_Cnt_M_Igc	0
VehicleSpeedValid_Cnt_M_Igc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	20874
VitesseVehicleBVRampValidCount_Cnt_M_u16	2887
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	30009
VitesseVehicleBVSigValidCount_Cnt_M_u16	3678
VitesseVehicleBV_Kph_M_f32	394.153809
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	44325
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	52355
VitesseVehiculeRoues_Kph_M_f32	319.606201
k_AASNTCEnableTimeout_mS_u16	32975
k_AASNodeAbsentDiag_Cnt_str.Threshold	57647
k_AASNodeAbsentDiag_Cnt_str.PStep	44259
k_AASNodeAbsentDiag_Cnt_str.NStep	21741
k_AASNodeAbsentTimeout_mS_u16	22218
k_AASNodeTimeout_mS_u16	3518
k_ABSNodeTimeout_mS_u16	40742
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	9711
k_ANGLEVOLANTSigValidThresh_Cnt_u16	47824
k_AngleVolantInvalidThresh_Cnt_u16	17359
k_AngleVolantValidThresh_Cnt_u16	35749
k_BSI552MsgTimeout_mS_u16	55874
k_BSINTCEnableTimeout_mS_u16	40276
k_BSINodeAbsentDiag_Cnt_str.Threshold	22932
k_BSINodeAbsentDiag_Cnt_str.PStep	35794
k_BSINodeAbsentDiag_Cnt_str.NStep	13279
k_BSINodeAbsentTimeout_mS_u16	4592
k_BSINodeTimeout_mS_u16	38761
k_BattOvHi_Volt_f32	27.3955994
k_BattOvLo_Volt_f32	6.01380014
k_BattUvHi_Volt_f32	28.6459007
k_BattUvLo_Volt_f32	3.31550002
k_CAVNTCEnableTimeout_mS_u16	59083
k_CAVNodeAbsentDiag_Cnt_str.Threshold	2616
k_CAVNodeAbsentDiag_Cnt_str.PStep	31391
k_CAVNodeAbsentDiag_Cnt_str.NStep	12245
k_CAVNodeAbsentTimeout_mS_u16	52582
k_CAVNodeTimeout_mS_u16	299
k_CMM388MsgTimeout_mS_u16	60363
k_CMM388NTCEnableTimeout_mS_u16	34471
k_CMMNTCEnableTimeout_mS_u16	53544
k_CMMNodeAbsentDiag_Cnt_str.Threshold	10754
k_CMMNodeAbsentDiag_Cnt_str.PStep	42486
k_CMMNodeAbsentDiag_Cnt_str.NStep	64894
k_CMMNodeAbsentTimeout_mS_u16	7519
k_CONSANGLECPKMax_HwDeg_f32	768.161804
k_CONSANGLECPKMin_HwDeg_f32	-465.577087
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	57381
k_CONSANGLECPKSigValidThresh_Cnt_u16	16259
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	18932
k_CPKVehicleSpeedValidThresh_Cnt_u16	2093
k_CityParkInputInvalidThresh_Cnt_u16	6281
k_CityParkInputValidThresh_Cnt_u16	15323
k_ComputerRazGCTSigValidThresh_Cnt_u16	14854
k_CptTemporelSigValidThresh_Cnt_u16	44896
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	24070
k_DMDFCTCPKSigValidThresh_Cnt_u16	59900
k_DMDFCTCPKValidCount_Cnt_u16	30959
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	51384
k_DMDRELAXECPKSigValidThresh_Cnt_u16	32069
k_DMDRelaxeConsistentThresh_Cnt_u16	41851
k_DateValidThresh_Cnt_u16	62212
k_DefaultVehSpd_Kph_f32	179.196594
k_DiagMuxOnAbsentTimeout_mS_u16	1990
k_EMNodeTimeout_mS_u16	50204
k_ESPNTCEnableTimeout_mS_u16	43476
k_ESPNodeAbsentDiag_Cnt_str.Threshold	52749
k_ESPNodeAbsentDiag_Cnt_str.PStep	6750
k_ESPNodeAbsentDiag_Cnt_str.NStep	53658
k_ESPNodeAbsentTimeout_mS_u16	11943
k_EtatMTSigInvalidThresh_Cnt_u16	11442
k_EtatMTSigValidThresh_Cnt_u16	8224

Name	Input Value
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	56047
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	13025
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	2468
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	36861
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	24727
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	55094
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	2473
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	0
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	17600
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	55972
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	32461
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	17177
k_ISDATDIRASentDiag_Cnt_str.Threshold	34296
k_ISDATDIRASentDiag_Cnt_str.PStep	63105
k_ISDATDIRASentDiag_Cnt_str.NStep	22979
k_ISDATDIRASentTimeout_mS_u16	28591
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	19198
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	2360
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	31808
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	35539
k_ISDYNAASChkSumValidThresh_Cnt_u16	34049
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	18196
k_ISDYNAASMsgCountValidThresh_Cnt_u16	30170
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	45815
k_ISDYNAASMsgLenValidThresh_Cnt_u16	38114
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	35352
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	16756
k_ISDYNABRChkSumValidThresh_Cnt_u16	9194
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	29095
k_ISDYNABRMsgCountValidThresh_Cnt_u16	8524
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	47992
k_ISDYNABRMsgLenValidThresh_Cnt_u16	38169
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	52363
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	31973
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	1563
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	62077
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	13040
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	30549
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	55389
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	53989
k_ISDYNVOLChkSumValidThresh_Cnt_u16	11567
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	12678
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	16421
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	50801
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	50306
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	28330
k_IgnOnTimeout_mS_u16	7873
k_JDD2010Selected_Cnt_Igc	0
k_PowerCutVehSpdHighThresh_Kph_f32	88.3983002
k_PowerCutVehSpdLowThresh_Kph_f32	28.9685993
k_PowerCutVehSpdLowTimeout_mS_u16	15771
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	29.7863007
k_VBattMaxCAV_Volt_f32	2.52600002
k_VBattMaxCMM388_Volt_f32	10.0129995
k_VBattMaxCMM_Volt_f32	24.2353992
k_VBattMaxESP_Volt_f32	29.7863007
k_VBattMinAAS_Volt_f32	19.4438
k_VBattMinBSI_Volt_f32	12.5263004
k_VBattMinCAV_Volt_f32	3.6868999
k_VBattMinCMM388_Volt_f32	22.0301991
k_VBattMinCMM_Volt_f32	6.71089983
k_VBattMinESP_Volt_f32	24.2353992
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	51656
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	38209
k_VitesseVehicleBVRampValidThresh_Cnt_u16	39407
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	27891
k_VitesseVehicleBVSigValidThresh_Cnt_u16	32348
k_VitesseVehicleBVSpeedPassThresh_kph_f32	185.790802
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	49400
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	53557
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	305882624

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	119
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	51531
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	217558272
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	171
target_SrlComInput_Per1_Batt_Volt_f32.value	18.3344994
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2004833792
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	1
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.43777293
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	115
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	8619520
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4288456192
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2005255680
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1883170304
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4056417792
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	69281280
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2940880384
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	42
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	82
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	163
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	186
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	204
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	127
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1734862336
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	23
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	127
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	133
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	212
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2294187520
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	11
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2337777152
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3334522368
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	155
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	240
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2007422464
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3291
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.788051546
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	88077
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	174.534302
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	58891

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	217558272	217558272	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	217558272	217558272	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	217558272	217558272	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-68.5143356	-68.5143356	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1831134720	1831134720	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	305882624	305882624	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	217558272	217558272	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1270912512	1270912512	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	217558272	217558272	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	217558272	217558272	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	2616	2616	✔
CAVNodeAbsentTimer_mS_M_u32	217558272	217558272	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	217558272	217558272	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3580610048	3580610048	✔
CMMNTCsEnabled_Cnt_M_lgc	1	1	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	217558272	217558272	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	62240	62240	✔
CONSANGLECPK_HwDeg_M_f32	-540.999878	-540.999878 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	217558272	217558272	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	217558272	217558272	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	217558272	217558272	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	217558272	217558272	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	217558272	217558272	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	217558272	217558272	✔
DiagOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DmdDelestDATimer_mS_M_u32	217558272	217558272	✔
ESPNTCEnableTimer_mS_M_u32	217558272	217558272	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	52749	52749	✔
ESPNodeAbsentTimer_mS_M_u32	217558272	217558272	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔
EffacDefaultDiagTimer_mS_M_u32[1]	21	21	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	217558272	217558272	✔
ElecIntTimer_mS_M_u32[1]	6072	6072	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	217558272	217558272	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	8619520	8619520	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	217558272	217558272	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2005255680	2005255680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	217558272	217558272	✔
ISDATDIRASentFltAcc_Cnt_M_u16	34296	34296	✔
ISDATDIRASentTimer_mS_M_u32	217558272	217558272	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	69281280	69281280	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	217558272	217558272	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	217558272	217558272	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2294187520	2294187520	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	217558272	217558272	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgTimer_mS_M_u32	217558272	217558272	✔
IgnOnTimer_mS_M_u32	217558272	217558272	✔
IgnTimeOff_Sec_M_u32	1590348666	1590348666	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	115	115	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	8619520	8619520	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	153	153	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4288456192	4288456192	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	51	51	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2005255680	2005255680	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	75	75	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1883170304	1883170304	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1402652160	1402652160	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	16	16	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	69281280	69281280	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	206	206	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2940880384	2940880384	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	127	127	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1734862336	1734862336	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2294187520	2294187520	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	11	11	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2337777152	2337777152	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	9	9	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3334522368	3334522368	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2007422464	2007422464	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	530.780273	530.780273	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	394.153809	394.153809	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	319.606201	319.606201	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-68.5143356	-68.5143356	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	62240	62240	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1590348666	1590348666	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-540.999878	-540.999878 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	179.196594	179.196594	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NTC	0x0129	0x0129	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0161	0x0161	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.66 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3974045952
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	5011
AASNodeAbsentTimer_mS_M_u32	2806206720
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	28710
ANGLEVOLANTSigValidCount_Cnt_M_u16	1205
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	38476
AngleVolantMsgTimer_mS_M_u32	3974045952
AngleVolantValidCount_Cnt_M_u16	61519
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-326.618591
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2538082560
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	570724608
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1278034176
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1177878784
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	20481

Name	Input Value
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	913031424
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	3725
CAVNodeAbsentTimer_mS_M_u32	2677371136
CDD_SrlComVehSpd_Kph_G_f32	451.493591
CMM388NTCEnableTimer_mS_M_u32	3257708800
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2448650496
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	47566
CMMNodeAbsentTimer_mS_M_u32	2287403264
CONSANGLECPKSigInvalidCount_Cnt_M_u16	35078
CONSANGLECPKSigValidCount_Cnt_M_u16	2214
CONSANGLECPK_Cnt_M_u16	21333
CONSANGLECPK_HwDeg_M_f32	34.8157997
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21333
CPKVehicleSpeedMsgTimer_mS_M_u32	781328640
CPKVehicleSpeedValidCount_Cnt_M_u16	61368
CityParkInputConsistentCount_Cnt_M_u16	62179
CityParkInputInvalidCount_Cnt_M_u16	47239
CityParkInputMsgTimer_mS_M_u32	8619520
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1322733824
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	46119
ComputerRazGCTSigInvalidTimer_mS_M_u32	3822842112
ComputerRazGCTSigValidCount_Cnt_M_u16	23284
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	57843
DMDFCTCPKSigValidCount_Cnt_M_u16	42955
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56432
DMDRELAXECPKSigValidCount_Cnt_M_u16	62591
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	28863
DateInvalidTimer_mS_M_u32	570724608
DiagMuxOnAbsentTimer_mS_M_u32	1316348160
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1177878784
ESPNTCEnableTimer_mS_M_u32	1783648512
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	32426
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	22
EffacDefaultDiagTimer_mS_M_u32[1]	23
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	9900
ElecIntTimer_mS_M_u32[1]	11002
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1234551040
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	22390
EtatMTSigValidCount_Cnt_M_u16	13826
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	21328
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	54896
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	35881
ISDAT4V2BSI552MsgTimer_mS_M_u32	1995112704
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	33380
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	33176
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13826
ISDATBSI3F2MsgTimer_mS_M_u32	3156992256
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	40318
ISDATBSI412MsgLenValidCount_Cnt_M_u16	39201
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	22390
ISDATBSI412MsgTimer_mS_M_u32	680861952
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	12130
ISDATBSI432MsgLenValidCount_Cnt_M_u16	47934
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	63034
ISDATDIRASentFltAcc_Cnt_M_u16	42910
ISDATDIRASentTimer_mS_M_u32	781328640

Name	Input Value
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	48523
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	61519
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	3406
ISDYN2CMMMsgTimer_mS_M_u32	250761472
ISDYNAASChkSumInvalidCount_Cnt_M_u16	7133
ISDYNAASChkSumValidCount_Cnt_M_u16	13069
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	59818
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	24700
ISDYNAASMsgLenValidCount_Cnt_M_u16	54980
ISDYNAASMsgTimeValidCount_Cnt_M_u16	7133
ISDYNAASMsgTimer_mS_M_u32	748204288
ISDYNABRChkSumInvalidCount_Cnt_M_u16	11772
ISDYNABRChkSumValidCount_Cnt_M_u16	49459
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	26040
ISDYNABRMsgCountValidCount_Cnt_M_u16	47912
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	47585
ISDYNABRMsgLenValidCount_Cnt_M_u16	47041
ISDYNABRMsgTimeValidCount_Cnt_M_u16	21333
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	639
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1163
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13826
ISDYNCMM208MsgTimer_mS_M_u32	916001024
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2407
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1269
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	18181
ISDYNCMM388MsgTimer_mS_M_u32	2321953024
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	20156
ISDYNVOLChkSumValidCount_Cnt_M_u16	51932
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	52905
ISDYNVOLMsgCountValidCount_Cnt_M_u16	53505
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	47055
ISDYNVOLMsgLenValidCount_Cnt_M_u16	38095
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	47566
ISDYNVOLMsgTimer_mS_M_u32	172486912
IgnOnTimer_mS_M_u32	1476014336
IgnTimeOff_Sec_M_u32	410571977
ManVehSpd_Kph_M_f32	555.650879
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	99
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	180
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4176077056
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	58
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2473083136
PrevISDATBSI412MsgDLCError_Cnt_M_u08	57
PrevISDATBSI412MsgRxTime_MSec_M_u32	3741479168
PrevISDATBSI432MsgDLCError_Cnt_M_u08	75
PrevISDATBSI432MsgRxTime_MSec_M_u32	3935588608
PrevISDATDIRAMsgTxTime_MSec_M_u32	2472964352
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	144
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1846313216
PrevISDYNAASMsgDLCError_Cnt_M_u08	130
PrevISDYNAASMsgRxTime_MSec_M_u32	478015744
PrevISDYNABRMsgDLCError_Cnt_M_u08	34
PrevISDYNABRMsgRxTime_MSec_M_u32	2748461312
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	68
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2874077440
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	157
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3460518144
PrevISDYNVOLMsgDLCError_Cnt_M_u08	122
PrevISDYNVOLMsgRxTime_MSec_M_u32	365654272
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3679133952
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	536.184998

Name	Input Value
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	6962
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	19962
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	35799
VitesseVehicleBVRampValidCount_Cnt_M_u16	24671
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	62539
VitesseVehicleBVSigValidCount_Cnt_M_u16	51866
VitesseVehicleBV_Kph_M_f32	307.671295
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	18181
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	27308
VitesseVehiculeRoues_Kph_M_f32	309.542908
k_AASNTCEnableTimeout_mS_u16	9800
k_AASNodeAbsentDiag_Cnt_str.Threshold	22453
k_AASNodeAbsentDiag_Cnt_str.PStep	51729
k_AASNodeAbsentDiag_Cnt_str.NStep	21419
k_AASNodeAbsentTimeout_mS_u16	7702
k_AASNodeTimeout_mS_u16	62714
k_ABSNodeTimeout_mS_u16	49668
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	48489
k_ANGLEVOLANTSigValidThresh_Cnt_u16	36997
k_AngleVolantInvalidThresh_Cnt_u16	45448
k_AngleVolantValidThresh_Cnt_u16	47239
k_BSI552MsgTimeout_mS_u16	64879
k_BSINTCEnableTimeout_mS_u16	11066
k_BSINodeAbsentDiag_Cnt_str.Threshold	22972
k_BSINodeAbsentDiag_Cnt_str.PStep	35777
k_BSINodeAbsentDiag_Cnt_str.NStep	13302
k_BSINodeAbsentTimeout_mS_u16	23588
k_BSINodeTimeout_mS_u16	63034
k_BattOvHi_Volt_f32	3.02589989
k_BattOvLo_Volt_f32	7.59870005
k_BattUvHi_Volt_f32	8.98700047
k_BattUvLo_Volt_f32	18.1692009
k_CAVNTCEnableTimeout_mS_u16	48917
k_CAVNodeAbsentDiag_Cnt_str.Threshold	10673
k_CAVNodeAbsentDiag_Cnt_str.PStep	48436
k_CAVNodeAbsentDiag_Cnt_str.NStep	62601
k_CAVNodeAbsentTimeout_mS_u16	34883
k_CAVNodeTimeout_mS_u16	35698
k_CMM388MsgTimeout_mS_u16	64147
k_CMM388NTCEnableTimeout_mS_u16	39423
k_CMMNTCEnableTimeout_mS_u16	10812
k_CMMNodeAbsentDiag_Cnt_str.Threshold	40732
k_CMMNodeAbsentDiag_Cnt_str.PStep	20919
k_CMMNodeAbsentDiag_Cnt_str.NStep	38358
k_CMMNodeAbsentTimeout_mS_u16	59416
k_CONSANGLECPKMax_HwDeg_f32	410.599701
k_CONSANGLECPKMin_HwDeg_f32	-467.219604
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	44549
k_CONSANGLECPKSigValidThresh_Cnt_u16	4524
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	39000
k_CPKVehicleSpeedValidThresh_Cnt_u16	10797
k_CityParkInputInvalidThresh_Cnt_u16	17370
k_CityParkInputValidThresh_Cnt_u16	62179
k_ComputerRazGCTSigValidThresh_Cnt_u16	59298
k_CptTemporelSigValidThresh_Cnt_u16	63830
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	41185
k_DMDFCTCPKSigValidThresh_Cnt_u16	57025
k_DMDFCTCPKValidCount_Cnt_u16	16681

Name	Input Value
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	3406
k_DMDRELAXECPKSigValidThresh_Cnt_u16	12646
k_DMDRelaxeConsistentThresh_Cnt_u16	5828
k_DateValidThresh_Cnt_u16	35881
k_DefaultVehSpd_Kph_f32	6.87400007
k_DiagMuxOnAbsentTimeout_mS_u16	11619
k_EMNodeTimeout_mS_u16	18079
k_ESPNTCEnableTimeout_mS_u16	11001
k_ESPNodeAbsentDiag_Cnt_str.Threshold	44634
k_ESPNodeAbsentDiag_Cnt_str.PStep	62686
k_ESPNodeAbsentDiag_Cnt_str.NStep	63203
k_ESPNodeAbsentTimeout_mS_u16	54336
k_EtatMTSigInvalidThresh_Cnt_u16	60255
k_EtatMTSigValidThresh_Cnt_u16	53974
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	37223
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	23379
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	60808
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	33213
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	33201
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	8466
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	31291
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	65535
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	58614
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	44233
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	29197
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	13931
k_ISDATDIRASentDiag_Cnt_str.Threshold	48370
k_ISDATDIRASentDiag_Cnt_str.PStep	39948
k_ISDATDIRASentDiag_Cnt_str.NStep	46400
k_ISDATDIRASentTimeout_mS_u16	22120
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	62140
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	38476
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	25525
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	38140
k_ISDYNAASChkSumValidThresh_Cnt_u16	26675
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	19640
k_ISDYNAASMsgCountValidThresh_Cnt_u16	57896
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	44176
k_ISDYNAASMsgLenValidThresh_Cnt_u16	61326
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	17069
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	11927
k_ISDYNABRChkSumValidThresh_Cnt_u16	26871
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	14081
k_ISDYNABRMsgCountValidThresh_Cnt_u16	51664
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	24782
k_ISDYNABRMsgLenValidThresh_Cnt_u16	26026
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	33811
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	13766
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	26723
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	701
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	22310
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	11189
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	45663
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	43525
k_ISDYNVOLChkSumValidThresh_Cnt_u16	52456
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	33891
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	50887
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	46306
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	3182
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	12599
k_IgnOnTimeout_mS_u16	13937
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	237.769104
k_PowerCutVehSpdLowThresh_Kph_f32	104.058098
k_PowerCutVehSpdLowTimeout_mS_u16	8164
k_VBattMaxAAS_Volt_f32	11.9622002
k_VBattMaxBSI_Volt_f32	29.7863007
k_VBattMaxCAV_Volt_f32	15.7814999
k_VBattMaxCMM388_Volt_f32	13.2367001
k_VBattMaxCMM_Volt_f32	28.2870998
k_VBattMaxESP_Volt_f32	15.0827999
k_VBattMinAAS_Volt_f32	3.05550003
k_VBattMinBSI_Volt_f32	6.23559999

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinCAV_Volt_f32	14.5869999
k_VBattMinCMM388_Volt_f32	8.34819984
k_VBattMinCMM_Volt_f32	23.3362007
k_VBattMinESP_Volt_f32	28.2870998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	7774
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	44466
k_VitesseVehicleBVRampValidThresh_Cnt_u16	13737
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	61916
k_VitesseVehicleBVSigValidThresh_Cnt_u16	28512
k_VitesseVehicleBVSpeedPassThresh_kph_f32	397.561096
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	30093
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	18069
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	570724608
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	90
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	13737
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1605090304
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	157
target_SrlComInput_Per1_Batt_Volt_f32.value	24.4293995
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	771277056
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	95
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.478750199
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	531378432
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	19
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1860227328
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2477093120
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	22
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1979322624
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4259229952
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	324227328
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	147
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2656563456
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	108
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	134
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	177
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	182
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1954484480
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	11
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	174
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	24
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	855322880
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2008011008

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1374974208
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	145
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	729956608
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3488
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.548104882
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	245759
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	186.611099
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	4692

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1605090304	1605090304	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1605090304	1605090304	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	38478	38478	✔
AngleVolantMsgTimer_mS_M_u32	1605090304	1605090304	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-326.618591	-326.618591	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2538082560	2538082560	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	570724608	570724608	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	1605090304	1605090304	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1177878784	1177878784	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1605090304	1605090304	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1605090304	1605090304	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	10673	10673	✔
CAVNodeAbsentTimer_mS_M_u32	1605090304	1605090304	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1605090304	1605090304	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2448650496	2448650496	✔
CMMNTCsEnabled_Cnt_M_lgc	1	1	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1605090304	1605090304	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	21333	21333	✔
CONSANGLECPK_HwDeg_M_f32	34.8157997	34.8157997 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21333	21333	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	781328640	781328640	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	61368	61368	✔
CityParkInputConsistentCount_Cnt_M_u16	62179	62179	✔
CityParkInputInvalidCount_Cnt_M_u16	47239	47239	✔
CityParkInputMsgTimer_mS_M_u32	1605090304	1605090304	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1322733824	1322733824	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ComputerRazGCTSigInvalidTimer_mS_M_u32	3822842112	3822842112	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1605090304	1605090304	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1605090304	1605090304	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1605090304	1605090304	✔
ESPNTCEnableTimer_mS_M_u32	1605090304	1605090304	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	44634	44634	✔
ESPNodeAbsentTimer_mS_M_u32	1605090304	1605090304	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	22	22	✔
EffacDefaultDiagTimer_mS_M_u32[1]	23	23	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	1605090304	1605090304	✔
ElecIntTimer_mS_M_u32[1]	11002	11002	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1605090304	1605090304	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	22390	22390	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	21329	21329	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	531378432	531378432	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	33380	33380	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1860227328	1860227328	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	40318	40318	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2477093120	2477093120	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1605090304	1605090304	✔
ISDATDIRASentFltAcc_Cnt_M_u16	48370	48370	✔
ISDATDIRASentTimer_mS_M_u32	1605090304	1605090304	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	48524	48524	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	324227328	324227328	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1605090304	1605090304	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1605090304	1605090304	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	640	640	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	855322880	855322880	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1605090304	1605090304	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1605090304	1605090304	✔
IgnOnTimer_mS_M_u32	1605090304	1605090304	✔
IgnTimeOff_Sec_M_u32	410571977	410571977	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	215	215	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	531378432	531378432	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	19	19	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1860227328	1860227328	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	48	48	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2477093120	2477093120	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	22	22	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1979322624	1979322624	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2472964352	2472964352	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	324227328	324227328	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	147	147	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2656563456	2656563456	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	94	94	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1954484480	1954484480	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	24	24	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	855322880	855322880	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	105	105	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2008011008	2008011008	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	91	91	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1374974208	1374974208	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	729956608	729956608	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	536.184998	536.184998	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	307.671295	307.671295	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	309.542908	309.542908	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-326.618591	-326.618591	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	21333	21333	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	410571977	410571977	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	34.8157997	34.8157997 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	6.87400007	6.87400007	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.67 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3737477120
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	56487
AASNodeAbsentTimer_mS_M_u32	3159937024
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	12528
ANGLEVOLANTSigValidCount_Cnt_M_u16	36353
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	30844
AngleVolantMsgTimer_mS_M_u32	3737477120

Name	Input Value
AngleVolantValidCount_Cnt_M_u16	15605
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-756.037903
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	4014641152
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3776253952
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	559611904
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	37994496
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	48479
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2090827776
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	64569
CAVNodeAbsentTimer_mS_M_u32	1138913280
CDD_SrlComVehSpd_Kph_G_f32	503.360992
CMM388NTCEnableTimer_mS_M_u32	1226616832
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1690857472
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	27190
CMMNodeAbsentTimer_mS_M_u32	1138606080
CONSANGLECPKSigInvalidCount_Cnt_M_u16	22862
CONSANGLECPKSigValidCount_Cnt_M_u16	13615
CONSANGLECPK_Cnt_M_u16	53538
CONSANGLECPK_HwDeg_M_f32	480.706787
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	53538
CPKVehicleSpeedMsgTimer_mS_M_u32	2779537408
CPKVehicleSpeedValidCount_Cnt_M_u16	52290
CityParkInputConsistentCount_Cnt_M_u16	34105
CityParkInputInvalidCount_Cnt_M_u16	5452
CityParkInputMsgTimer_mS_M_u32	531378432
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	362598400
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	19179
ComputerRazGCTSigInvalidTimer_mS_M_u32	2970546176
ComputerRazGCTSigValidCount_Cnt_M_u16	53510
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	18696
DMDFCTCPKSigValidCount_Cnt_M_u16	12865
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	37906
DMDRELAXECPKSigValidCount_Cnt_M_u16	26275
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	50723
DateInvalidTimer_mS_M_u32	3776253952
DiagMuxOnAbsentTimer_mS_M_u32	2231443456
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	37994496
ESPNTCEnableTimer_mS_M_u32	3878801408
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	26211
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	28
EffacDefaultDiagTimer_mS_M_u32[1]	29
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	6454
ElecIntTimer_mS_M_u32[1]	8259
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1797357568
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	33341
EtatMTSigValidCount_Cnt_M_u16	61786
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	41584
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	29649
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	32039
ISDAT4V2BSI552MsgTimer_mS_M_u32	3357655040

Name	Input Value
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	37108
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	15897
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	61786
ISDATBSI3F2MsgTimer_mS_M_u32	2480873472
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	13480
ISDATBSI412MsgLenValidCount_Cnt_M_u16	44157
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	33341
ISDATBSI412MsgTimer_mS_M_u32	2208522240
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	22906
ISDATBSI432MsgLenValidCount_Cnt_M_u16	167
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	14642
ISDATDIRASentFltAcc_Cnt_M_u16	46342
ISDATDIRASentTimer_mS_M_u32	2779537408
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	60032
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	15605
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	62199
ISDYN2CMMMsgTimer_mS_M_u32	21745664
ISDYNAASChkSumInvalidCount_Cnt_M_u16	27593
ISDYNAASChkSumValidCount_Cnt_M_u16	49402
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	31972
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	33388
ISDYNAASMsgLenValidCount_Cnt_M_u16	6741
ISDYNAASMsgTimeValidCount_Cnt_M_u16	27593
ISDYNAASMsgTimer_mS_M_u32	3117985792
ISDYNABRChkSumInvalidCount_Cnt_M_u16	9966
ISDYNABRChkSumValidCount_Cnt_M_u16	10247
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	47672
ISDYNABRMsgCountValidCount_Cnt_M_u16	21673
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	62141
ISDYNABRMsgLenValidCount_Cnt_M_u16	21470
ISDYNABRMsgTimeValidCount_Cnt_M_u16	53538
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	640
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1165
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	61786
ISDYNCMM208MsgTimer_mS_M_u32	2505543680
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2411
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1271
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	37075
ISDYNCMM388MsgTimer_mS_M_u32	3060805632
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	24620
ISDYNVOLChkSumValidCount_Cnt_M_u16	18061
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	56038
ISDYNVOLMsgCountValidCount_Cnt_M_u16	3743
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	36596
ISDYNVOLMsgLenValidCount_Cnt_M_u16	53941
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	27190
ISDYNVOLMsgTimer_mS_M_u32	3989499904
IgnOnTimer_mS_M_u32	2645831680
IgnTimeOff_Sec_M_u32	160360049
ManVehSpd_Kph_M_f32	182.556305
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	101
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	59
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1436884992
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	243
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4155113472
PrevISDATBSI412MsgDLCError_Cnt_M_u08	3
PrevISDATBSI412MsgRxTime_MSec_M_u32	2040229888
PrevISDATBSI432MsgDLCError_Cnt_M_u08	29
PrevISDATBSI432MsgRxTime_MSec_M_u32	1986383872
PrevISDATDIRAMsgTxTime_MSec_M_u32	3966726144
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	144
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1220362240

Name	Input Value
PrevISDYNAASMsgDLCError_Cnt_M_u08	117
PrevISDYNAASMsgRxTime_MSec_M_u32	254341120
PrevISDYNABRMsgDLCError_Cnt_M_u08	69
PrevISDYNABRMsgRxTime_MSec_M_u32	439103488
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	255
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3870683136
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	150
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1197002752
PrevISDYNVOLMsgDLCError_Cnt_M_u08	104
PrevISDYNVOLMsgRxTime_MSec_M_u32	960524288
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3280035840
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	90.3292007
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	43594
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	3251
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	11355
VitesseVehicleBVRampValidCount_Cnt_M_u16	43396
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	30849
VitesseVehicleBVSigValidCount_Cnt_M_u16	4178
VitesseVehicleBV_Kph_M_f32	65.6900024
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	37075
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	41115
VitesseVehiculeRoues_Kph_M_f32	69.0486984
k_AASNTCEnableTimeout_mS_u16	58441
k_AASNodeAbsentDiag_Cnt_str.Threshold	10671
k_AASNodeAbsentDiag_Cnt_str.PStep	20827
k_AASNodeAbsentDiag_Cnt_str.NStep	26292
k_AASNodeAbsentTimeout_mS_u16	36768
k_AASNodeTimeout_mS_u16	6067
k_ABSNodeTimeout_mS_u16	11477
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	35685
k_ANGLEVOLANTSigValidThresh_Cnt_u16	23762
k_AngleVolantInvalidThresh_Cnt_u16	50633
k_AngleVolantValidThresh_Cnt_u16	5452
k_BSI552MsgTimeout_mS_u16	46162
k_BSINTCEnableTimeout_mS_u16	50674
k_BSINodeAbsentDiag_Cnt_str.Threshold	23012
k_BSINodeAbsentDiag_Cnt_str.PStep	35760
k_BSINodeAbsentDiag_Cnt_str.NStep	13325
k_BSINodeAbsentTimeout_mS_u16	34548
k_BSINodeTimeout_mS_u16	14642
k_BattOvHi_Volt_f32	5.6026001
k_BattOvLo_Volt_f32	8.1026001
k_BattUvHi_Volt_f32	23.5834007
k_BattUvLo_Volt_f32	1.46430004
k_CAVNTCEnableTimeout_mS_u16	47522
k_CAVNodeAbsentDiag_Cnt_str.Threshold	38713
k_CAVNodeAbsentDiag_Cnt_str.PStep	64458
k_CAVNodeAbsentDiag_Cnt_str.NStep	11062
k_CAVNodeAbsentTimeout_mS_u16	59159
k_CAVNodeTimeout_mS_u16	522
k_CMM388MsgTimeout_mS_u16	10151
k_CMM388NTCEnableTimeout_mS_u16	63843
k_CMMNTCEnableTimeout_mS_u16	63852
k_CMMNodeAbsentDiag_Cnt_str.Threshold	36367
k_CMMNodeAbsentDiag_Cnt_str.PStep	43509
k_CMMNodeAbsentDiag_Cnt_str.NStep	28668
k_CMMNodeAbsentTimeout_mS_u16	55383

Name	Input Value
k_CONSANGLECPKMax_HwDeg_f32	242.905106
k_CONSANGLECPKMin_HwDeg_f32	-552.528381
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	23507
k_CONSANGLECPKSigValidThresh_Cnt_u16	43931
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	9625
k_CPKVehicleSpeedValidThresh_Cnt_u16	2715
k_CityParkInputInvalidThresh_Cnt_u16	56660
k_CityParkInputValidThresh_Cnt_u16	34105
k_ComputerRazGCTSigValidThresh_Cnt_u16	55610
k_CptTemporelSigValidThresh_Cnt_u16	20191
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	15805
k_DMDFCTCPKSigValidThresh_Cnt_u16	57054
k_DMDFCTCPKValidCount_Cnt_u16	35303
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	62199
k_DMDRELAXECPKSigValidThresh_Cnt_u16	49520
k_DMDRelaxeConsistentThresh_Cnt_u16	2390
k_DateValidThresh_Cnt_u16	32039
k_DefaultVehSpd_Kph_f32	219.263702
k_DiagMuxOnAbsentTimeout_mS_u16	64248
k_EMNodeTimeout_mS_u16	50307
k_ESPNTCEnableTimeout_mS_u16	22261
k_ESPNodeAbsentDiag_Cnt_str.Threshold	17405
k_ESPNodeAbsentDiag_Cnt_str.PStep	60684
k_ESPNodeAbsentDiag_Cnt_str.NStep	59948
k_ESPNodeAbsentTimeout_mS_u16	46047
k_EtatMTSigInvalidThresh_Cnt_u16	15045
k_EtatMTSigValidThresh_Cnt_u16	16158
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	13932
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	25449
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	26954
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	14057
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	57806
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	63980
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	7407
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	25870
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	35006
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	38086
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	12219
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	44768
k_ISDATDIRASentDiag_Cnt_str.Threshold	14724
k_ISDATDIRASentDiag_Cnt_str.PStep	40547
k_ISDATDIRASentDiag_Cnt_str.NStep	22182
k_ISDATDIRASentTimeout_mS_u16	23978
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	65005
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	30844
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	40129
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	61934
k_ISDYNAASChkSumValidThresh_Cnt_u16	13063
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	1336
k_ISDYNAASMsgCountValidThresh_Cnt_u16	57257
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	64306
k_ISDYNAASMsgLenValidThresh_Cnt_u16	30711
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	58970
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	60571
k_ISDYNABRChkSumValidThresh_Cnt_u16	38972
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	2143
k_ISDYNABRMsgCountValidThresh_Cnt_u16	27312
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	30006
k_ISDYNABRMsgLenValidThresh_Cnt_u16	45411
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	2023
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	43662
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	43001
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	47722
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	31728
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	6401
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	34756
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	60179
k_ISDYNVOLChkSumValidThresh_Cnt_u16	60712
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	31032
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	26443
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	6649
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	7702
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	17917

Name	Input Value
k_IgnOnTimeout_mS_u16	62927
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	163.078598
k_PowerCutVehSpdLowThresh_Kph_f32	220.211395
k_PowerCutVehSpdLowTimeout_mS_u16	26485
k_VBattMaxAAS_Volt_f32	5.60640001
k_VBattMaxBSI_Volt_f32	29.7863007
k_VBattMaxCAV_Volt_f32	25.0536995
k_VBattMaxCMM388_Volt_f32	5.94019985
k_VBattMaxCMM_Volt_f32	18.6355991
k_VBattMaxESP_Volt_f32	14.9040003
k_VBattMinAAS_Volt_f32	15.1499996
k_VBattMinBSI_Volt_f32	2.12529993
k_VBattMinCAV_Volt_f32	21.7730999
k_VBattMinCMM388_Volt_f32	26.1165009
k_VBattMinCMM_Volt_f32	8.0618
k_VBattMinESP_Volt_f32	18.6355991
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	33543
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	65484
k_VitesseVehicleBVRampValidThresh_Cnt_u16	42470
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	53645
k_VitesseVehicleBVSigValidThresh_Cnt_u16	17346
k_VitesseVehicleBVSpeedPassThresh_kph_f32	88.9377975
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	51001
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	20194
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3776253952
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	109
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	26709
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	4244116992
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	150
target_SrlComInput_Per1_Batt_Volt_f32.value	18.5723991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	167280640
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	11
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.504543543
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2392731648
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3145748480
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2813489152
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	36
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2603913216
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3724980224
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3089682432
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	156
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1905979392
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	131
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	159

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4087713792
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	71
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	140
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	141
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	168
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1353789440
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	115
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2635288576
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	214
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1757769728
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	391905280
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3950
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.394198179
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	97373
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	206.802505
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	52452

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4244116992	4244116992	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4244116992	4244116992	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	4244116992	4244116992	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-756.037903	-756.037903	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	4014641152	4014641152	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3776253952	3776253952	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	559611904	559611904	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	37994496	37994496	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	4244116992	4244116992	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4244116992	4244116992	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	38713	38713	✔
CAVNodeAbsentTimer_mS_M_u32	4244116992	4244116992	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4244116992	4244116992	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1690857472	1690857472	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4244116992	4244116992	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CONSANGLECPK_Cnt_M_u16	53538	53538	✔
CONSANGLECPK_HwDeg_M_f32	480.706787	480.706787 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4244116992	4244116992	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	4244116992	4244116992	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4244116992	4244116992	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4244116992	4244116992	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4244116992	4244116992	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4244116992	4244116992	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4244116992	4244116992	✔
ESPNTCEnableTimer_mS_M_u32	4244116992	4244116992	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	17405	17405	✔
ESPNodeAbsentTimer_mS_M_u32	4244116992	4244116992	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	28	28	✔
EffacDefaultDiagTimer_mS_M_u32[1]	29	29	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	6454	6454	✔
ElecIntTimer_mS_M_u32[1]	8259	8259	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4244116992	4244116992	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4244116992	4244116992	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4244116992	4244116992	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2813489152	2813489152	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4244116992	4244116992	✔
ISDATDIRASentFltAcc_Cnt_M_u16	14724	14724	✔
ISDATDIRASentTimer_mS_M_u32	4244116992	4244116992	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4244116992	4244116992	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4244116992	4244116992	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4244116992	4244116992	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4244116992	4244116992	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4244116992	4244116992	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4244116992	4244116992	✔
IgnOnTimer_mS_M_u32	4244116992	4244116992	✔
IgnTimeOff_Sec_M_u32	160360049	160360049	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	49	49	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2392731648	2392731648	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	121	121	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3145748480	3145748480	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	93	93	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2813489152	2813489152	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	36	36	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2603913216	2603913216	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3966726144	3966726144	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	123	123	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3089682432	3089682432	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	156	156	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1905979392	1905979392	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	159	159	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4087713792	4087713792	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	107	107	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1353789440	1353789440	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	115	115	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2635288576	2635288576	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	214	214	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1757769728	1757769728	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	391905280	391905280	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	90.3292007	90.3292007	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	65.6900024	65.6900024	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	69.0486984	69.0486984	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-756.037903	-756.037903	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	53538	53538	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	160360049	160360049	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	480.706787	480.706787 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	219.263702	219.263702	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.68 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1959699200
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	9511
AASNodeAbsentTimer_mS_M_u32	3050590976
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	59981
ANGLEVOLANTSigValidCount_Cnt_M_u16	33498
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	58792
AngleVolantMsgTimer_mS_M_u32	1959699200
AngleVolantValidCount_Cnt_M_u16	8383
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-170.679962
ApaRelaxReq_Cnt_M_lgc	1

Name	Input Value
BSI3F2NTCEnableTimer_mS_M_u32	335483648
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2292159232
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2341323520
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2077459200
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	49408
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	734020352
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	38130
CAVNodeAbsentTimer_mS_M_u32	3451351808
CDD_SrlComVehSpd_Kph_G_f32	139.407593
CMM388NTCEnableTimer_mS_M_u32	1997058816
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2198172416
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	64442
CMMNodeAbsentTimer_mS_M_u32	2667938560
CONSANGLECPKSigInvalidCount_Cnt_M_u16	6196
CONSANGLECPKSigValidCount_Cnt_M_u16	29777
CONSANGLECPK_Cnt_M_u16	11384
CONSANGLECPK_HwDeg_M_f32	-59.7929993
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	11384
CPKVehicleSpeedMsgTimer_mS_M_u32	2082054912
CPKVehicleSpeedValidCount_Cnt_M_u16	59966
CityParkInputConsistentCount_Cnt_M_u16	22515
CityParkInputInvalidCount_Cnt_M_u16	1210
CityParkInputMsgTimer_mS_M_u32	2392731648
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3121107712
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	59995
ComputerRazGCTSigInvalidTimer_mS_M_u32	3627152128
ComputerRazGCTSigValidCount_Cnt_M_u16	59532
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	22918
DMDFCTCPKSigValidCount_Cnt_M_u16	60827
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	51431
DMDRELAXECPKSigValidCount_Cnt_M_u16	244
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	26037
DateInvalidTimer_mS_M_u32	2292159232
DiagMuxOnAbsentTimer_mS_M_u32	555442944
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2077459200
ESPNTCEnableTimer_mS_M_u32	3645461248
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	9971
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	200
EffacDefaultDiagTimer_mS_M_u32[1]	300
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	8976
ElecIntTimer_mS_M_u32[1]	15236
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3896132352
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	57508
EtatMTSigValidCount_Cnt_M_u16	29454
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	17614
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	49259
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	9449
ISDAT4V2BSI552MsgTimer_mS_M_u32	574194432
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1537
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	65107
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	29454
ISDATBSI3F2MsgTimer_mS_M_u32	3967902464

Name	Input Value
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	15333
ISDATBSI412MsgLenValidCount_Cnt_M_u16	37926
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	57508
ISDATBSI412MsgTimer_mS_M_u32	2117378816
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	15854
ISDATBSI432MsgLenValidCount_Cnt_M_u16	26663
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	519
ISDATDIRASentFltAcc_Cnt_M_u16	56971
ISDATDIRASentTimer_mS_M_u32	2082054912
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	55390
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	8383
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	55225
ISDYN2CMMMsgTimer_mS_M_u32	1929073408
ISDYNAASChkSumInvalidCount_Cnt_M_u16	32705
ISDYNAASChkSumValidCount_Cnt_M_u16	45038
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	56562
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	36441
ISDYNAASMsgLenValidCount_Cnt_M_u16	54878
ISDYNAASMsgTimeValidCount_Cnt_M_u16	32705
ISDYNAASMsgTimer_mS_M_u32	349483776
ISDYNABRChkSumInvalidCount_Cnt_M_u16	31186
ISDYNABRChkSumValidCount_Cnt_M_u16	17991
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	4212
ISDYNABRMsgCountValidCount_Cnt_M_u16	28897
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	51175
ISDYNABRMsgLenValidCount_Cnt_M_u16	37956
ISDYNABRMsgTimeValidCount_Cnt_M_u16	11384
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	641
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1167
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	29454
ISDYNCMM208MsgTimer_mS_M_u32	2513965824
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2415
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1273
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	7461
ISDYNCMM388MsgTimer_mS_M_u32	3708695296
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	64410
ISDYNVOLChkSumValidCount_Cnt_M_u16	14391
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	39916
ISDYNVOLMsgCountValidCount_Cnt_M_u16	20609
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	12608
ISDYNVOLMsgLenValidCount_Cnt_M_u16	54718
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	64442
ISDYNVOLMsgTimer_mS_M_u32	301855488
IgnOnTimer_mS_M_u32	927085312
IgnTimeOff_Sec_M_u32	1728858816
ManVehSpd_Kph_M_f32	470.478912
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	103
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	64
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1060070144
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	65
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	77644544
PrevISDATBSI412MsgDLCError_Cnt_M_u08	227
PrevISDATBSI412MsgRxTime_MSec_M_u32	1351381760
PrevISDATBSI432MsgDLCError_Cnt_M_u08	166
PrevISDATBSI432MsgRxTime_MSec_M_u32	4222440192
PrevISDATDIRAMsgTxTime_MSec_M_u32	1209037568
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	134
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1852244736
PrevISDYNAASMsgDLCError_Cnt_M_u08	173
PrevISDYNAASMsgRxTime_MSec_M_u32	2783179520
PrevISDYNABRMsgDLCError_Cnt_M_u08	38
PrevISDYNABRMsgRxTime_MSec_M_u32	2715431680

Name	Input Value
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	153
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2470245120
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	241
PrevISDYNCMM388MsgRxTime_MSec_M_u32	349459200
PrevISDYNVOLMsgDLCError_Cnt_M_u08	58
PrevISDYNVOLMsgRxTime_MSec_M_u32	3852301056
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3063587584
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	542.694824
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	3775
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	63300
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	3212
VitesseVehicleBVRampValidCount_Cnt_M_u16	42193
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	38810
VitesseVehicleBVSigValidCount_Cnt_M_u16	32743
VitesseVehicleBV_Kph_M_f32	121.7938
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	7461
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	32138
VitesseVehiculeRoues_Kph_M_f32	84.7974014
k_AASNTCEnableTimeout_mS_u16	20227
k_AASNodeAbsentDiag_Cnt_str.Threshold	56279
k_AASNodeAbsentDiag_Cnt_str.PStep	33067
k_AASNodeAbsentDiag_Cnt_str.NStep	12985
k_AASNodeAbsentTimeout_mS_u16	38078
k_AASNodeTimeout_mS_u16	54852
k_ABSNodeTimeout_mS_u16	8735
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	5165
k_ANGLEVOLANTSigValidThresh_Cnt_u16	49062
k_AngleVolantInvalidThresh_Cnt_u16	8385
k_AngleVolantValidThresh_Cnt_u16	1210
k_BSI552MsgTimeout_mS_u16	56933
k_BSINTCEnableTimeout_mS_u16	55430
k_BSINodeAbsentDiag_Cnt_str.Threshold	23052
k_BSINodeAbsentDiag_Cnt_str.PStep	35743
k_BSINodeAbsentDiag_Cnt_str.NStep	13348
k_BSINodeAbsentTimeout_mS_u16	39488
k_BSINodeTimeout_mS_u16	519
k_BattOvHi_Volt_f32	4.31330013
k_BattOvLo_Volt_f32	13.1585999
k_BattUvHi_Volt_f32	5.27810001
k_BattUvLo_Volt_f32	22.8537998
k_CAVNTCEnableTimeout_mS_u16	61368
k_CAVNodeAbsentDiag_Cnt_str.Threshold	37296
k_CAVNodeAbsentDiag_Cnt_str.PStep	58520
k_CAVNodeAbsentDiag_Cnt_str.NStep	51755
k_CAVNodeAbsentTimeout_mS_u16	52312
k_CAVNodeTimeout_mS_u16	3584
k_CMM388MsgTimeout_mS_u16	17447
k_CMM388NTCEnableTimeout_mS_u16	48883
k_CMMNTCEnableTimeout_mS_u16	44185
k_CMMNodeAbsentDiag_Cnt_str.Threshold	39960
k_CMMNodeAbsentDiag_Cnt_str.PStep	55743
k_CMMNodeAbsentDiag_Cnt_str.NStep	17984
k_CMMNodeAbsentTimeout_mS_u16	50774
k_CONSANGLECPKMax_HwDeg_f32	318.069397
k_CONSANGLECPKMin_HwDeg_f32	-269.955597
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	48165
k_CONSANGLECPKSigValidThresh_Cnt_u16	23690

Name	Input Value
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	50322
k_CPKVehicleSpeedValidThresh_Cnt_u16	17932
k_CityParkInputInvalidThresh_Cnt_u16	28320
k_CityParkInputValidThresh_Cnt_u16	22515
k_ComputerRazGCTSigValidThresh_Cnt_u16	50479
k_CptTemporelSigValidThresh_Cnt_u16	25601
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	59111
k_DMDFCTCPKSigValidThresh_Cnt_u16	62276
k_DMDFCTCPKValidCount_Cnt_u16	31592
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	55225
k_DMDRELAXECPKSigValidThresh_Cnt_u16	48142
k_DMDRelaxeConsistentThresh_Cnt_u16	64604
k_DateValidThresh_Cnt_u16	9449
k_DefaultVehSpd_Kph_f32	159.829102
k_DiagMuxOnAbsentTimeout_mS_u16	34550
k_EMNodeTimeout_mS_u16	60053
k_ESPNTCEnableTimeout_mS_u16	29886
k_ESPNodeAbsentDiag_Cnt_str.Threshold	30510
k_ESPNodeAbsentDiag_Cnt_str.PStep	34391
k_ESPNodeAbsentDiag_Cnt_str.NStep	65167
k_ESPNodeAbsentTimeout_mS_u16	21438
k_EtatMTSigInvalidThresh_Cnt_u16	23117
k_EtatMTSigValidThresh_Cnt_u16	7426
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	40473
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	30434
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	12224
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	10274
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	10036
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	64537
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	0
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	55432
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	49186
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	29068
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	57453
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	65084
k_ISDATDIRASentDiag_Cnt_str.Threshold	64338
k_ISDATDIRASentDiag_Cnt_str.PStep	18764
k_ISDATDIRASentDiag_Cnt_str.NStep	45147
k_ISDATDIRASentTimeout_mS_u16	50590
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	34069
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58792
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	54106
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	6354
k_ISDYNAASChkSumValidThresh_Cnt_u16	9543
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	12148
k_ISDYNAASMsgCountValidThresh_Cnt_u16	53217
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	3334
k_ISDYNAASMsgLenValidThresh_Cnt_u16	50552
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	17166
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	53837
k_ISDYNABRChkSumValidThresh_Cnt_u16	48938
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	57344
k_ISDYNABRMsgCountValidThresh_Cnt_u16	26829
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	55994
k_ISDYNABRMsgLenValidThresh_Cnt_u16	17907
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	11560
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	7667
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	26098
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	35359
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	2381
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	57818
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	36178
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	33956
k_ISDYNVOLChkSumValidThresh_Cnt_u16	15909
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	33396
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	39035
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	2416
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	56538
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	41575
k_IgnOnTimeout_mS_u16	21616
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	210.884293
k_PowerCutVehSpdLowThresh_Kph_f32	47.4859009

Name	Input Value
k_PowerCutVehSpdLowTimeout_mS_u16	30079
k_VBattMaxAAS_Volt_f32	23.8661995
k_VBattMaxBSI_Volt_f32	25.9909
k_VBattMaxCAV_Volt_f32	4.80840015
k_VBattMaxCMM388_Volt_f32	10.3931999
k_VBattMaxCMM_Volt_f32	29.7667999
k_VBattMaxESP_Volt_f32	5.99590015
k_VBattMinAAS_Volt_f32	13.7658005
k_VBattMinBSI_Volt_f32	5.99590015
k_VBattMinCAV_Volt_f32	2.24300003
k_VBattMinCMM388_Volt_f32	32
k_VBattMinCMM_Volt_f32	5.76870012
k_VBattMinESP_Volt_f32	29.7667999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	56775
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	59192
k_VitesseVehicleBVRampValidThresh_Cnt_u16	15084
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	38711
k_VitesseVehicleBVSigValidThresh_Cnt_u16	32856
k_VitesseVehicleBVSpeedPassThresh_kph_f32	485.97821
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	13298
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	44215
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2292159232
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	241
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	42575
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1888387328
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	241
target_SrlComInput_Per1_Batt_Volt_f32.value	20.8603992
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	666190592
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	98
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.25423342
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2357474048
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3059602176
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3796333312
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	943788800
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3762991872
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	40129280
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3331191552
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	146
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	192
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	239
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	854463232
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	41
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	86
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	112

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	147
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	223
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	224
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	160
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1380659968
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	497341184
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	193
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2869850880
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	175
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	183
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	251
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3985294080
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3710
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.386034817
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	946315
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	152.962708
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	36593

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1959699200	1959699200	✔
AASNTCsEnabled_Cnt_M_lgc	1	1	✔
AASNodeAbsentFltAcc_Cnt_M_u16	56279	56279	✔
AASNodeAbsentTimer_mS_M_u32	1888387328	1888387328	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1888387328	1888387328	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-170.679962	-170.679962	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	335483648	335483648	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	2292159232	2292159232	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	1888387328	1888387328	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2077459200	2077459200	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1888387328	1888387328	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1888387328	1888387328	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	37296	37296	✔
CAVNodeAbsentTimer_mS_M_u32	1888387328	1888387328	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1888387328	1888387328	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2198172416	2198172416	✔
CMMNTCsEnabled_Cnt_M_lgc	1	1	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	46458	46458	✔
CMMNodeAbsentTimer_mS_M_u32	40129280	40129280	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	11384	11384	✔
CONSANGLECPK_HwDeg_M_f32	-59.7929993	-59.7929993 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CPKVehicleSpeedMsgTimer_mS_M_u32	1888387328	1888387328	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1888387328	1888387328	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1888387328	1888387328	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1888387328	1888387328	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1888387328	1888387328	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1888387328	1888387328	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1888387328	1888387328	✔
ESPNTCEnableTimer_mS_M_u32	1888387328	1888387328	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1888387328	1888387328	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	200	200	✔
EffacDefaultDiagTimer_mS_M_u32[1]	300	300	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	8976	8976	✔
ElecIntTimer_mS_M_u32[1]	15236	15236	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1888387328	1888387328	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2357474048	2357474048	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3059602176	3059602176	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3796333312	3796333312	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1888387328	1888387328	✔
ISDATDIRASentFltAcc_Cnt_M_u16	64338	64338	✔
ISDATDIRASentTimer_mS_M_u32	1888387328	1888387328	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	40129280	40129280	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3331191552	3331191552	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1888387328	1888387328	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1380659968	1380659968	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1888387328	1888387328	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1888387328	1888387328	✔
IgnOnTimer_mS_M_u32	927085312	927085312	✔
IgnTimeOff_Sec_M_u32	1728858816	1728858816	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	67	67	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2357474048	2357474048	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	123	123	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3059602176	3059602176	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	33	33	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3796333312	3796333312	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	93	93	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	943788800	943788800	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1209037568	1209037568	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	55	55	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	40129280	40129280	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	37	37	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3331191552	3331191552	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	239	239	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	854463232	854463232	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	160	160	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1380659968	1380659968	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	154	154	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	497341184	497341184	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	193	193	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2869850880	2869850880	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3985294080	3985294080	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	542.694824	542.694824	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VitesseVehicleBV_Kph_M_f32	121.7938	121.7938	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	84.7974014	84.7974014	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-170.679962	-170.679962	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	11384	11384	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1728858816	1728858816	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-59.7929993	-59.7929993 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	159.829102	159.829102	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.69 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1602148864
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	20597
AASNodeAbsentTimer_mS_M_u32	254659072
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	47873
ANGLEVOLANTSigValidCount_Cnt_M_u16	57882
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	21234
AngleVolantMsgTimer_mS_M_u32	1602148864
AngleVolantValidCount_Cnt_M_u16	2091
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-240.223846
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	263031296
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3553364480
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2143386112
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4126161408
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	49896
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2301229568
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	38291
CAVNodeAbsentTimer_mS_M_u32	3154405888
CDD_SrlComVehSpd_Kph_G_f32	502.619598
CMM388NTCEnableTimer_mS_M_u32	2500897280
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1411017216
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	20218
CMMNodeAbsentTimer_mS_M_u32	3562682880
CONSANGLECPKSigInvalidCount_Cnt_M_u16	15437
CONSANGLECPKSigValidCount_Cnt_M_u16	22710
CONSANGLECPK_Cnt_M_u16	35905
CONSANGLECPK_HwDeg_M_f32	633.624023
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	35905
CPKVehicleSpeedMsgTimer_mS_M_u32	899537408
CPKVehicleSpeedValidCount_Cnt_M_u16	58743
CityParkInputConsistentCount_Cnt_M_u16	12943
CityParkInputInvalidCount_Cnt_M_u16	5436
CityParkInputMsgTimer_mS_M_u32	2357474048
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3532769792
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	53465
ComputerRazGCTSigInvalidTimer_mS_M_u32	2794777088
ComputerRazGCTSigValidCount_Cnt_M_u16	9412
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	18136
DMDFCTCPKSigValidCount_Cnt_M_u16	39769
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	1843
DMDRELAXECPKSigValidCount_Cnt_M_u16	20428
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	38858
DateInvalidTimer_mS_M_u32	3553364480
DiagMuxOnAbsentTimer_mS_M_u32	2107152896
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4126161408
ESPNTCEnableTimer_mS_M_u32	3100559872
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	28175
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	500
EffacDefaultDiagTimer_mS_M_u32[1]	600
ElecIntCount_Cnt_M_u08	1

Name	Input Value
ElecIntTimer_mS_M_u32[0]	1100
ElecIntTimer_mS_M_u32[1]	1151
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3149658624
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	6459
EtatMTSigValidCount_Cnt_M_u16	49856
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	40575
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	23656
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	44399
ISDAT4V2BSI552MsgTimer_mS_M_u32	448674304
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	46245
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	52337
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	49856
ISDATBSI3F2MsgTimer_mS_M_u32	862362112
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	45051
ISDATBSI412MsgLenValidCount_Cnt_M_u16	26615
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	6459
ISDATBSI412MsgTimer_mS_M_u32	1531763200
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	22622
ISDATBSI432MsgLenValidCount_Cnt_M_u16	31347
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	57940
ISDATDIRASentFltAcc_Cnt_M_u16	23752
ISDATDIRASentTimer_mS_M_u32	899537408
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	41103
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	2091
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	22591
ISDYN2CMMMsgTimer_mS_M_u32	867748352
ISDYNAASChkSumInvalidCount_Cnt_M_u16	10407
ISDYNAASChkSumValidCount_Cnt_M_u16	2271
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	24466
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	1374
ISDYNAASMsgLenValidCount_Cnt_M_u16	65039
ISDYNAASMsgTimeValidCount_Cnt_M_u16	10407
ISDYNAASMsgTimer_mS_M_u32	3953961472
ISDYNABRChkSumInvalidCount_Cnt_M_u16	47091
ISDYNABRChkSumValidCount_Cnt_M_u16	58195
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	654
ISDYNABRMsgCountValidCount_Cnt_M_u16	20998
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	47412
ISDYNABRMsgLenValidCount_Cnt_M_u16	34013
ISDYNABRMsgTimeValidCount_Cnt_M_u16	35905
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	642
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1169
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	49856
ISDYNCMM208MsgTimer_mS_M_u32	774015488
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2419
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1275
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	11001
ISDYNCMM388MsgTimer_mS_M_u32	1493182976
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	43547
ISDYNVOLChkSumValidCount_Cnt_M_u16	9476
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	38822
ISDYNVOLMsgCountValidCount_Cnt_M_u16	35495
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	49960
ISDYNVOLMsgLenValidCount_Cnt_M_u16	34416
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	20218
ISDYNVOLMsgTimer_mS_M_u32	691071488
IgnOnTimer_mS_M_u32	442771968
IgnTimeOff_Sec_M_u32	740974560
ManVehSpd_Kph_M_f32	90.7539978
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	105
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0

Name	Input Value
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	85
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1935448576
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	214
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	545815040
PrevISDATBSI412MsgDLCError_Cnt_M_u08	126
PrevISDATBSI412MsgRxTime_MSec_M_u32	3347409408
PrevISDATBSI432MsgDLCError_Cnt_M_u08	254
PrevISDATBSI432MsgRxTime_MSec_M_u32	3785542144
PrevISDATDIRAMsgTxTime_MSec_M_u32	4042877440
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	176
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3426073088
PrevISDYNAASMsgDLCError_Cnt_M_u08	191
PrevISDYNAASMsgRxTime_MSec_M_u32	2239687168
PrevISDYNABRMsgDLCError_Cnt_M_u08	147
PrevISDYNABRMsgRxTime_MSec_M_u32	983312896
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	92
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1634986496
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	0
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4063087104
PrevISDYNVOLMsgDLCError_Cnt_M_u08	225
PrevISDYNVOLMsgRxTime_MSec_M_u32	2354211328
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3390757376
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	487.502014
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	39980
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	45917
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	5829
VitesseVehicleBVRampValidCount_Cnt_M_u16	7862
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	10010
VitesseVehicleBVSigValidCount_Cnt_M_u16	24307
VitesseVehicleBV_Kph_M_f32	609.301392
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	11001
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	23177
VitesseVehiculeRoues_Kph_M_f32	144.711502
k_AASNTCEnableTimeout_mS_u16	4256
k_AASNodeAbsentDiag_Cnt_str.Threshold	29451
k_AASNodeAbsentDiag_Cnt_str.PStep	36361
k_AASNodeAbsentDiag_Cnt_str.NStep	1174
k_AASNodeAbsentTimeout_mS_u16	26670
k_AASNodeTimeout_mS_u16	5725
k_ABSNodeTimeout_mS_u16	37133
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	37281
k_ANGLEVOLANTSigValidThresh_Cnt_u16	12278
k_AngleVolantInvalidThresh_Cnt_u16	14501
k_AngleVolantValidThresh_Cnt_u16	5436
k_BSI552MsgTimeout_mS_u16	25592
k_BSINTCEnableTimeout_mS_u16	59542
k_BSINodeAbsentDiag_Cnt_str.Threshold	23092
k_BSINodeAbsentDiag_Cnt_str.PStep	35726
k_BSINodeAbsentDiag_Cnt_str.NStep	13371
k_BSINodeAbsentTimeout_mS_u16	38186
k_BSINodeTimeout_mS_u16	57940
k_BattOvHi_Volt_f32	19.3274994
k_BattOvLo_Volt_f32	8.75599957
k_BattUvHi_Volt_f32	14.2111998
k_BattUvLo_Volt_f32	10.3294001
k_CAVNTCEnableTimeout_mS_u16	52290

Name	Input Value
k_CAVNodeAbsentDiag_Cnt_str.Threshold	13847
k_CAVNodeAbsentDiag_Cnt_str.PStep	7066
k_CAVNodeAbsentDiag_Cnt_str.NStep	28503
k_CAVNodeAbsentTimeout_mS_u16	1889
k_CAVNodeTimeout_mS_u16	35561
k_CMM388MsgTimeout_mS_u16	62325
k_CMM388NTCEnableTimeout_mS_u16	45841
k_CMMNTCEnableTimeout_mS_u16	8413
k_CMMNodeAbsentDiag_Cnt_str.Threshold	59946
k_CMMNodeAbsentDiag_Cnt_str.PStep	56619
k_CMMNodeAbsentDiag_Cnt_str.NStep	48097
k_CMMNodeAbsentTimeout_mS_u16	45093
k_CONSANGLECPKMax_HwDeg_f32	546.52301
k_CONSANGLECPKMin_HwDeg_f32	-465.426392
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	19961
k_CONSANGLECPKSigValidThresh_Cnt_u16	48521
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	883
k_CPKVehicleSpeedValidThresh_Cnt_u16	60806
k_CityParkInputInvalidThresh_Cnt_u16	37257
k_CityParkInputValidThresh_Cnt_u16	12943
k_ComputerRazGCTSigValidThresh_Cnt_u16	44827
k_CptTemporelSigValidThresh_Cnt_u16	54119
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	23604
k_DMDFCTCPKSigValidThresh_Cnt_u16	26589
k_DMDFCTCPKValidCount_Cnt_u16	13232
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	22591
k_DMDRELAXECPKSigValidThresh_Cnt_u16	48128
k_DMDRelaxeConsistentThresh_Cnt_u16	45846
k_DateValidThresh_Cnt_u16	44399
k_DefaultVehSpd_Kph_f32	124.929604
k_DiagMuxOnAbsentTimeout_mS_u16	62663
k_EMNodeTimeout_mS_u16	35114
k_ESPNTCEnableTimeout_mS_u16	9775
k_ESPNodeAbsentDiag_Cnt_str.Threshold	57925
k_ESPNodeAbsentDiag_Cnt_str.PStep	62915
k_ESPNodeAbsentDiag_Cnt_str.NStep	40531
k_ESPNodeAbsentTimeout_mS_u16	42989
k_EtatMTSigInvalidThresh_Cnt_u16	49794
k_EtatMTSigValidThresh_Cnt_u16	2850
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	21214
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	43330
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	7976
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	4674
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	5582
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	16223
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	65535
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	60752
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	41410
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	3333
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	289
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	54773
k_ISDATDIRASentDiag_Cnt_str.Threshold	1971
k_ISDATDIRASentDiag_Cnt_str.PStep	2044
k_ISDATDIRASentDiag_Cnt_str.NStep	33608
k_ISDATDIRASentTimeout_mS_u16	1167
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	58730
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	21234
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	31323
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	56051
k_ISDYNAASChkSumValidThresh_Cnt_u16	18003
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	42382
k_ISDYNAASMsgCountValidThresh_Cnt_u16	13574
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	52823
k_ISDYNAASMsgLenValidThresh_Cnt_u16	6337
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	17854
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	45570
k_ISDYNABRChkSumValidThresh_Cnt_u16	7211
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	26088
k_ISDYNABRMsgCountValidThresh_Cnt_u16	48193
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	45562
k_ISDYNABRMsgLenValidThresh_Cnt_u16	4367
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	39728
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	16016

Name	Input Value
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	42452
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	9932
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	24065
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	50458
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	56180
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	37310
k_ISDYNVOLChkSumValidThresh_Cnt_u16	9722
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	40844
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	48311
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	52951
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	46428
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	44277
k_IgnOnTimeout_mS_u16	21082
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	68.2640991
k_PowerCutVehSpdLowThresh_Kph_f32	22.4594002
k_PowerCutVehSpdLowTimeout_mS_u16	36140
k_VBattMaxAAS_Volt_f32	2.44740009
k_VBattMaxBSI_Volt_f32	25.9909
k_VBattMaxCAV_Volt_f32	7.76819992
k_VBattMaxCMM388_Volt_f32	14.2812996
k_VBattMaxCMM_Volt_f32	14.7807999
k_VBattMaxESP_Volt_f32	25.9909
k_VBattMinAAS_Volt_f32	10.1578999
k_VBattMinBSI_Volt_f32	2.36500001
k_VBattMinCAV_Volt_f32	19.6861992
k_VBattMinCMM388_Volt_f32	31.0615005
k_VBattMinCMM_Volt_f32	22.9342995
k_VBattMinESP_Volt_f32	14.7807999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	9044
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	34753
k_VitesseVehicleBVRampValidThresh_Cnt_u16	47782
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	2052
k_VitesseVehicleBVSigValidThresh_Cnt_u16	36192
k_VitesseVehicleBVSpeedPassThresh_kph_f32	183.984497
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	47251
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	7940
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3553364480
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	97
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8301
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3375841280
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	0
target_SrlComInput_Per1_Batt_Volt_f32.value	25.8460999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2840263168
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	57
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.696213722
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	157
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2728274432
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	328288768
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	225
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3193203200
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	719817216
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3779766784
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	74

Name	Input Value
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1769851392
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1266739712
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	37
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	99
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	116
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	179
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	237
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	184
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	786467328
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	39
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	84
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	121
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	125
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	139
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	151
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	191
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	98
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	759769600
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3116124672
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1073703424
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	67
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	74
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	149
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	153
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	216
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2378856960
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3878
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0187988747
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	440133
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	22.2789993
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	25494

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3375841280	3375841280	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3375841280	3375841280	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3375841280	3375841280	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-240.223846	-240.223846	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	263031296	263031296	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	3553364480	3553364480	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	3375841280	3375841280	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4126161408	4126161408	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3375841280	3375841280	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3375841280	3375841280	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	13847	13847	✔
CAVNodeAbsentTimer_mS_M_u32	3375841280	3375841280	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3375841280	3375841280	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3375841280	3375841280	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3375841280	3375841280	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	35905	35905	✔
CONSANGLECPK_HwDeg_M_f32	633.624023	633.624023 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3375841280	3375841280	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3375841280	3375841280	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3375841280	3375841280	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3375841280	3375841280	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3375841280	3375841280	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3375841280	3375841280	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3375841280	3375841280	✔
ESPNTCEnableTimer_mS_M_u32	3375841280	3375841280	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	57925	57925	✔
ESPNodeAbsentTimer_mS_M_u32	3375841280	3375841280	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	500	500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	600	600	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3375841280	3375841280	✔
ElecIntTimer_mS_M_u32[1]	1151	1151	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3375841280	3375841280	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3375841280	3375841280	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3375841280	3375841280	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3193203200	3193203200	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3375841280	3375841280	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1971	1971	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDATDIRASentTimer_mS_M_u32	3375841280	3375841280	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3375841280	3375841280	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3375841280	3375841280	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3375841280	3375841280	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3375841280	3375841280	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3375841280	3375841280	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3375841280	3375841280	✔
IgnOnTimer_mS_M_u32	3375841280	3375841280	✔
IgnTimeOff_Sec_M_u32	740974560	740974560	✔
Msg348Valid_Cnt_M_Igc	0	0	✔
Msg432Valid_Cnt_M_Igc	0	0	✔
Msg552Valid_Cnt_M_Igc	0	0	✔
NetOn_Cnt_M_Igc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	157	157	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2728274432	2728274432	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	328288768	328288768	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	225	225	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3193203200	3193203200	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	123	123	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	719817216	719817216	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4042877440	4042877440	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	74	74	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1769851392	1769851392	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	142	142	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1266739712	1266739712	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	184	184	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	786467328	786467328	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	98	98	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	759769600	759769600	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	68	68	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3116124672	3116124672	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	221	221	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1073703424	1073703424	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2378856960	2378856960	✔
PrevModeDiag_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevSrlComVehSpd_Kph_M_f32	487.502014	487.502014	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	609.301392	609.301392	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	144.711502	144.711502	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-240.223846	-240.223846	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	35905	35905	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	740974560	740974560	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	633.624023	633.624023 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	124.929604	124.929604	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.70 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3372889344

Name	Input Value
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	61478
AASNodeAbsentTimer_mS_M_u32	1639802112
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	33409
ANGLEVOLANTSigValidCount_Cnt_M_u16	15095
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	7343
AngleVolantMsgTimer_mS_M_u32	3372889344
AngleVolantValidCount_Cnt_M_u16	51588
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-709.283936
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	255730944
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1558357248
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	985814272
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	53875968
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	50892
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1619580160
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	25418
CAVNodeAbsentTimer_mS_M_u32	2109310208
CDD_SrlComVehSpd_Kph_G_f32	409.31131
CMM388NTCEnableTimer_mS_M_u32	1939129600
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2373420288
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	28118
CMMNodeAbsentTimer_mS_M_u32	2415400192
CONSANGLECPKSigInvalidCount_Cnt_M_u16	56733
CONSANGLECPKSigValidCount_Cnt_M_u16	63012
CONSANGLECPK_Cnt_M_u16	18307
CONSANGLECPK_HwDeg_M_f32	69.3075027
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	18307
CPKVehicleSpeedMsgTimer_mS_M_u32	2192389376
CPKVehicleSpeedValidCount_Cnt_M_u16	42057
CityParkInputConsistentCount_Cnt_M_u16	55896
CityParkInputInvalidCount_Cnt_M_u16	30544
CityParkInputMsgTimer_mS_M_u32	2728274432
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2811323648
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	65274
ComputerRazGCTSigInvalidTimer_mS_M_u32	2684880128
ComputerRazGCTSigValidCount_Cnt_M_u16	6073
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	21116
DMDFCTCPKSigValidCount_Cnt_M_u16	8891
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	58859
DMDRELAXECPKSigValidCount_Cnt_M_u16	14817
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	65318
DateInvalidTimer_mS_M_u32	1558357248
DiagMuxOnAbsentTimer_mS_M_u32	96269568
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	53875968
ESPNTCEnableTimer_mS_M_u32	685401344
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	11865
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	850
EffacDefaultDiagTimer_mS_M_u32[1]	1050
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	2050
ElecIntTimer_mS_M_u32[1]	6071
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2429736192

Name	Input Value
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	42003
EtatMTSigValidCount_Cnt_M_u16	34117
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	65287
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	13070
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	50297
ISDAT4V2BSI552MsgTimer_mS_M_u32	1288443136
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	44886
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	26033
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	34117
ISDATBSI3F2MsgTimer_mS_M_u32	2622682368
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	58964
ISDATBSI412MsgLenValidCount_Cnt_M_u16	31774
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	42003
ISDATBSI412MsgTimer_mS_M_u32	2376086784
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	57770
ISDATBSI432MsgLenValidCount_Cnt_M_u16	39213
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	49415
ISDATDIRASentFltAcc_Cnt_M_u16	8619
ISDATDIRASentTimer_mS_M_u32	2192389376
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	49817
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	51588
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	31303
ISDYN2CMMMsgTimer_mS_M_u32	3759957248
ISDYNAASChkSumInvalidCount_Cnt_M_u16	44944
ISDYNAASChkSumValidCount_Cnt_M_u16	48295
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	8015
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	65513
ISDYNAASMsgLenValidCount_Cnt_M_u16	41880
ISDYNAASMsgTimeValidCount_Cnt_M_u16	44944
ISDYNAASMsgTimer_mS_M_u32	3753952512
ISDYNABRChkSumInvalidCount_Cnt_M_u16	35117
ISDYNABRChkSumValidCount_Cnt_M_u16	21707
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	32219
ISDYNABRMsgCountValidCount_Cnt_M_u16	15666
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	49896
ISDYNABRMsgLenValidCount_Cnt_M_u16	52655
ISDYNABRMsgTimeValidCount_Cnt_M_u16	18307
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	643
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1171
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	34117
ISDYNCMM208MsgTimer_mS_M_u32	3353289984
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2423
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1277
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	6426
ISDYNCMM388MsgTimer_mS_M_u32	1170621696
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	19507
ISDYNVOLChkSumValidCount_Cnt_M_u16	18746
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	6162
ISDYNVOLMsgCountValidCount_Cnt_M_u16	3281
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	54030
ISDYNVOLMsgLenValidCount_Cnt_M_u16	30453
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28118
ISDYNVOLMsgTimer_mS_M_u32	2285110528
IgnOnTimer_mS_M_u32	2442806528
IgnTimeOff_Sec_M_u32	2704412196
ManVehSpd_Kph_M_f32	557.203979
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	107
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	220
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	879817984
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	200

Name	Input Value
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	879580416
PrevISDATBSI412MsgDLCError_Cnt_M_u08	46
PrevISDATBSI412MsgRxTime_MSec_M_u32	2671150336
PrevISDATBSI432MsgDLCError_Cnt_M_u08	75
PrevISDATBSI432MsgRxTime_MSec_M_u32	4267599104
PrevISDATDIRAMsgTxTime_MSec_M_u32	4074407168
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	65
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1986368768
PrevISDYNAASMsgDLCError_Cnt_M_u08	138
PrevISDYNAASMsgRxTime_MSec_M_u32	726271232
PrevISDYNABRMsgDLCError_Cnt_M_u08	78
PrevISDYNABRMsgRxTime_MSec_M_u32	284312832
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	147
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2875917568
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	157
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3099419904
PrevISDYNVOLMsgDLCError_Cnt_M_u08	198
PrevISDYNVOLMsgRxTime_MSec_M_u32	3301934336
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4181079296
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	152.132294
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	62335
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	15278
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	10164
VitesseVehicleBVRampValidCount_Cnt_M_u16	40355
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	57910
VitesseVehicleBVSigValidCount_Cnt_M_u16	26732
VitesseVehicleBV_Kph_M_f32	584.084778
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	6426
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	38953
VitesseVehiculeRoues_Kph_M_f32	422.892914
k_AASNTCEnableTimeout_mS_u16	63078
k_AASNodeAbsentDiag_Cnt_str.Threshold	21611
k_AASNodeAbsentDiag_Cnt_str.PStep	49801
k_AASNodeAbsentDiag_Cnt_str.NStep	40251
k_AASNodeAbsentTimeout_mS_u16	30075
k_AASNodeTimeout_mS_u16	4782
k_ABSNodeTimeout_mS_u16	34781
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	481
k_ANGLEVOLANTSigValidThresh_Cnt_u16	17572
k_AngleVolantInvalidThresh_Cnt_u16	42647
k_AngleVolantValidThresh_Cnt_u16	30544
k_BSI552MsgTimeout_mS_u16	63452
k_BSINTCEnableTimeout_mS_u16	4354
k_BSINodeAbsentDiag_Cnt_str.Threshold	23132
k_BSINodeAbsentDiag_Cnt_str.PStep	35709
k_BSINodeAbsentDiag_Cnt_str.NStep	13394
k_BSINodeAbsentTimeout_mS_u16	13831
k_BSINodeTimeout_mS_u16	49415
k_BattOvHi_Volt_f32	11.9404001
k_BattOvLo_Volt_f32	28.2618008
k_BattUvHi_Volt_f32	1.45420003
k_BattUvLo_Volt_f32	29.0639
k_CAVNTCEnableTimeout_mS_u16	59966
k_CAVNodeAbsentDiag_Cnt_str.Threshold	48511
k_CAVNodeAbsentDiag_Cnt_str.PStep	21071
k_CAVNodeAbsentDiag_Cnt_str.NStep	10673
k_CAVNodeAbsentTimeout_mS_u16	50656

Name	Input Value
k_CAVNodeTimeout_mS_u16	25033
k_CMM388MsgTimeout_mS_u16	1830
k_CMM388NTCEnableTimeout_mS_u16	14418
k_CMMNTCEnableTimeout_mS_u16	19118
k_CMMNodeAbsentDiag_Cnt_str.Threshold	18287
k_CMMNodeAbsentDiag_Cnt_str.PStep	19076
k_CMMNodeAbsentDiag_Cnt_str.NStep	8634
k_CMMNodeAbsentTimeout_mS_u16	1877
k_CONSANGLECPKMax_HwDeg_f32	207.759506
k_CONSANGLECPKMin_HwDeg_f32	-127.318802
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	45082
k_CONSANGLECPKSigValidThresh_Cnt_u16	28457
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	9068
k_CPKVehicleSpeedValidThresh_Cnt_u16	6579
k_CityParkInputInvalidThresh_Cnt_u16	54379
k_CityParkInputValidThresh_Cnt_u16	55896
k_ComputerRazGCTSigValidThresh_Cnt_u16	6132
k_CptTemporelSigValidThresh_Cnt_u16	43215
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	55784
k_DMDFCTCPKSigValidThresh_Cnt_u16	9391
k_DMDFCTCPKValidCount_Cnt_u16	38004
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	31303
k_DMDRELAXECPKSigValidThresh_Cnt_u16	7366
k_DMDRelaxeConsistentThresh_Cnt_u16	3972
k_DateValidThresh_Cnt_u16	50297
k_DefaultVehSpd_Kph_f32	149.237595
k_DiagMuxOnAbsentTimeout_mS_u16	42481
k_EMNodeTimeout_mS_u16	43782
k_ESPNTCEnableTimeout_mS_u16	8566
k_ESPNodeAbsentDiag_Cnt_str.Threshold	17149
k_ESPNodeAbsentDiag_Cnt_str.PStep	9629
k_ESPNodeAbsentDiag_Cnt_str.NStep	55364
k_ESPNodeAbsentTimeout_mS_u16	16381
k_EtatMTSigInvalidThresh_Cnt_u16	25984
k_EtatMTSigValidThresh_Cnt_u16	55646
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	41259
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	64446
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	47245
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	19071
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	15770
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	51240
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	6442
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	62614
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	38270
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	54583
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	13986
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	11621
k_ISDATDIRASentDiag_Cnt_str.Threshold	7469
k_ISDATDIRASentDiag_Cnt_str.PStep	15785
k_ISDATDIRASentDiag_Cnt_str.NStep	39517
k_ISDATDIRASentTimeout_mS_u16	4953
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	4870
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	7343
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	54514
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	8237
k_ISDYNAASChkSumValidThresh_Cnt_u16	11211
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	38107
k_ISDYNAASMsgCountValidThresh_Cnt_u16	37938
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	54785
k_ISDYNAASMsgLenValidThresh_Cnt_u16	39810
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	9036
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	36990
k_ISDYNABRChkSumValidThresh_Cnt_u16	49093
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	56780
k_ISDYNABRMsgCountValidThresh_Cnt_u16	2178
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	17622
k_ISDYNABRMsgLenValidThresh_Cnt_u16	17753
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	59317
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	40019
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	43209
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	23905
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	39297
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	37367

Name	Input Value
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	1192
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	3339
k_ISDYNVOLChkSumValidThresh_Cnt_u16	3605
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	52706
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	22687
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	62271
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	7537
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	24039
k_IgnOnTimeout_mS_u16	15159
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	29.7341995
k_PowerCutVehSpdLowThresh_Kph_f32	239.1483
k_PowerCutVehSpdLowTimeout_mS_u16	45250
k_VBattMaxAAS_Volt_f32	5.80950022
k_VBattMaxBSI_Volt_f32	25.3812008
k_VBattMaxCAV_Volt_f32	13.4048996
k_VBattMaxCMM388_Volt_f32	23.0627995
k_VBattMaxCMM_Volt_f32	10.7040005
k_VBattMaxESP_Volt_f32	25.3812008
k_VBattMinAAS_Volt_f32	17.4507008
k_VBattMinBSI_Volt_f32	3.69230008
k_VBattMinCAV_Volt_f32	30.9857998
k_VBattMinCMM388_Volt_f32	21.9321995
k_VBattMinCMM_Volt_f32	12.7658997
k_VBattMinESP_Volt_f32	10.7040005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	33096
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	53699
k_VitesseVehicleBVRampValidThresh_Cnt_u16	44818
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	41018
k_VitesseVehicleBVSigValidThresh_Cnt_u16	19941
k_VitesseVehicleBVSpeedPassThresh_kph_f32	514.666809
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	64074
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	21689
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1558357248
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	140
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	17903
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1425605376
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	157
target_SrlComInput_Per1_Batt_Volt_f32.value	13.3401003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3290813696
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	87
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.503793895
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1626096896
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1116923136
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	171
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3066660096
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	630203648
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4142318848
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2462934272
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1631847680
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	78

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	94
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	141
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	171
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	183
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1034233088
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	30
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	243
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	753616128
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	24
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3155289344
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	36
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2647164160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	23
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	115
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	131
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	151
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	177
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1957123328
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1473
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.164469868
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	352015
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	58.9394989
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	50497

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1425605376	1425605376	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1425605376	1425605376	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1425605376	1425605376	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-709.283936	-709.283936	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	255730944	255730944	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	1558357248	1558357248	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	985814272	985814272	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	53875968	53875968	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1425605376	1425605376	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1425605376	1425605376	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	48511	48511	✔
CAVNodeAbsentTimer_mS_M_u32	1425605376	1425605376	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CMM388NTCEnableTimer_mS_M_u32	1425605376	1425605376	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1425605376	1425605376	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1425605376	1425605376	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	18307	18307	✔
CONSANGLECPK_HwDeg_M_f32	69.3075027	69.3075027 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1425605376	1425605376	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1425605376	1425605376	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1425605376	1425605376	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1425605376	1425605376	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1425605376	1425605376	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1425605376	1425605376	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1425605376	1425605376	✔
ESPNTCEnableTimer_mS_M_u32	1425605376	1425605376	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	17149	17149	✔
ESPNodeAbsentTimer_mS_M_u32	1425605376	1425605376	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	850	850	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1050	1050	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2050	2050	✔
ElecIntTimer_mS_M_u32[1]	6071	6071	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1425605376	1425605376	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1626096896	1626096896	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1116923136	1116923136	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3066660096	3066660096	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	630203648	630203648	✔
ISDATDIRASentFltAcc_Cnt_M_u16	7469	7469	✔
ISDATDIRASentTimer_mS_M_u32	1425605376	1425605376	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYN2CMMMsgTimer_mS_M_u32	1425605376	1425605376	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1425605376	1425605376	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1425605376	1425605376	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1425605376	1425605376	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1425605376	1425605376	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1425605376	1425605376	✔
IgnOnTimer_mS_M_u32	1425605376	1425605376	✔
IgnTimeOff_Sec_M_u32	2704412196	2704412196	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1626096896	1626096896	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	45	45	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1116923136	1116923136	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	171	171	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3066660096	3066660096	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	240	240	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	630203648	630203648	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4074407168	4074407168	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2462934272	2462934272	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	117	117	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1631847680	1631847680	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	94	94	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1034233088	1034233088	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	753616128	753616128	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	24	24	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3155289344	3155289344	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	36	36	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2647164160	2647164160	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1957123328	1957123328	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	152.132294	152.132294	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	584.084778	584.084778	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	422.892914	422.892914	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-709.283936	-709.283936	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	18307	18307	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2704412196	2704412196	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	69.3075027	69.3075027 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	149.237595	149.237595	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.71 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2140414976
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	7230
AASNodeAbsentTimer_mS_M_u32	3191510016
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	61231
ANGLEVOLANTSigValidCount_Cnt_M_u16	15499
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	64163
AngleVolantMsgTimer_mS_M_u32	2140414976
AngleVolantValidCount_Cnt_M_u16	36517
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-622.447083
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2830652416
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4056601600
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3001795584
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3633349632
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	3662
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2073576448

Name	Input Value
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	64338
CAVNodeAbsentTimer_mS_M_u32	46543872
CDD_SrlComVehSpd_Kph_G_f32	612.762024
CMM388NTCEnableTimer_mS_M_u32	2654237696
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1267479552
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	14190
CMMNodeAbsentTimer_mS_M_u32	3125445632
CONSANGLECPKSigInvalidCount_Cnt_M_u16	16600
CONSANGLECPKSigValidCount_Cnt_M_u16	44548
CONSANGLECPK_Cnt_M_u16	62951
CONSANGLECPK_HwDeg_M_f32	-541.609009
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	62951
CPKVehicleSpeedMsgTimer_mS_M_u32	2662016000
CPKVehicleSpeedValidCount_Cnt_M_u16	18013
CityParkInputConsistentCount_Cnt_M_u16	44073
CityParkInputInvalidCount_Cnt_M_u16	1601
CityParkInputMsgTimer_mS_M_u32	1626096896
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1019122688
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	16322
ComputerRazGCTSigInvalidTimer_mS_M_u32	4124750848
ComputerRazGCTSigValidCount_Cnt_M_u16	47110
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	9405
DMDFCTCPKSigValidCount_Cnt_M_u16	19136
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	60657
DMDRELAXECPKSigValidCount_Cnt_M_u16	26573
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	16445
DateInvalidTimer_mS_M_u32	4056601600
DiagMuxOnAbsentTimer_mS_M_u32	75228160
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3633349632
ESPNTCEnableTimer_mS_M_u32	484676608
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	40102
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	1100
EffacDefaultDiagTimer_mS_M_u32[1]	3766467072
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	9900
ElecIntTimer_mS_M_u32[1]	11001
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2461680640
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	54713
EtatMTSigValidCount_Cnt_M_u16	39137
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1178
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	8006
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	56710
ISDAT4V2BSI552MsgTimer_mS_M_u32	3553526784
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	7022
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	65310
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	39137
ISDATBSI3F2MsgTimer_mS_M_u32	414835712
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	64374
ISDATBSI412MsgLenValidCount_Cnt_M_u16	214
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	54713
ISDATBSI412MsgTimer_mS_M_u32	164766720
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	11250
ISDATBSI432MsgLenValidCount_Cnt_M_u16	44074
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	5659
ISDATDIRASentFltAcc_Cnt_M_u16	33839
ISDATDIRASentTimer_mS_M_u32	2662016000
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	23717
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	36517

Name	Input Value
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	39260
ISDYN2CMMMsgTimer_mS_M_u32	2132644864
ISDYNAASChkSumInvalidCount_Cnt_M_u16	1536
ISDYNAASChkSumValidCount_Cnt_M_u16	54652
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	31044
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	24949
ISDYNAASMsgLenValidCount_Cnt_M_u16	52521
ISDYNAASMsgTimeValidCount_Cnt_M_u16	1536
ISDYNAASMsgTimer_mS_M_u32	162558976
ISDYNABRChkSumInvalidCount_Cnt_M_u16	58027
ISDYNABRChkSumValidCount_Cnt_M_u16	38543
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	34591
ISDYNABRMsgCountValidCount_Cnt_M_u16	16347
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	31991
ISDYNABRMsgLenValidCount_Cnt_M_u16	4963
ISDYNABRMsgTimeValidCount_Cnt_M_u16	62951
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	644
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1173
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	39137
ISDYNCMM208MsgTimer_mS_M_u32	1121276928
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2427
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1279
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	30691
ISDYNCMM388MsgTimer_mS_M_u32	3449811968
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	52502
ISDYNVOLChkSumValidCount_Cnt_M_u16	36034
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	44027
ISDYNVOLMsgCountValidCount_Cnt_M_u16	25726
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	49799
ISDYNVOLMsgLenValidCount_Cnt_M_u16	3475
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	14190
ISDYNVOLMsgTimer_mS_M_u32	3981882368
IgnOnTimer_mS_M_u32	975434752
IgnTimeOff_Sec_M_u32	1208241684
ManVehSpd_Kph_M_f32	150.496094
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	109
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	96
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1214243840
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	81
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	837469184
PrevISDATBSI412MsgDLCError_Cnt_M_u08	6
PrevISDATBSI412MsgRxTime_MSec_M_u32	3528406016
PrevISDATBSI432MsgDLCError_Cnt_M_u08	214
PrevISDATBSI432MsgRxTime_MSec_M_u32	2891420672
PrevISDATDIRAMsgTxTime_MSec_M_u32	1734554624
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	216
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2634155008
PrevISDYNAASMsgDLCError_Cnt_M_u08	153
PrevISDYNAASMsgRxTime_MSec_M_u32	3692344320
PrevISDYNABRMsgDLCError_Cnt_M_u08	138
PrevISDYNABRMsgRxTime_MSec_M_u32	471593984
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	220
PrevISDYNCMM208MsgRxTime_MSec_M_u32	531739648
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	215
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3107623936
PrevISDYNVOLMsgDLCError_Cnt_M_u08	252
PrevISDYNVOLMsgRxTime_MSec_M_u32	92550144
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2668635136
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	322.874115
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	24243
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	56551
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	54804
VitesseVehicleBVRampValidCount_Cnt_M_u16	51976
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	58384
VitesseVehicleBVSigValidCount_Cnt_M_u16	51244
VitesseVehicleBV_Kph_M_f32	573.005127
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	30691
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	53623
VitesseVehiculeRoues_Kph_M_f32	470.746185
k_AASNTCEnableTimeout_mS_u16	13630
k_AASNodeAbsentDiag_Cnt_str.Threshold	43864
k_AASNodeAbsentDiag_Cnt_str.PStep	33717
k_AASNodeAbsentDiag_Cnt_str.NStep	39063
k_AASNodeAbsentTimeout_mS_u16	9920
k_AASNodeTimeout_mS_u16	22503
k_ABSNodeTimeout_mS_u16	18586
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	26445
k_ANGLEVOLANTSigValidThresh_Cnt_u16	17861
k_AngleVolantInvalidThresh_Cnt_u16	44012
k_AngleVolantValidThresh_Cnt_u16	1601
k_BSI552MsgTimeout_mS_u16	15966
k_BSINTCEnableTimeout_mS_u16	65002
k_BSINodeAbsentDiag_Cnt_str.Threshold	23172
k_BSINodeAbsentDiag_Cnt_str.PStep	35692
k_BSINodeAbsentDiag_Cnt_str.NStep	13417
k_BSINodeAbsentTimeout_mS_u16	3739
k_BSINodeTimeout_mS_u16	5659
k_BattOvHi_Volt_f32	0.353799999
k_BattOvLo_Volt_f32	30.0688992
k_BattUvHi_Volt_f32	11.8172998
k_BattUvLo_Volt_f32	11.0952997
k_CAVNTCEnableTimeout_mS_u16	58743
k_CAVNodeAbsentDiag_Cnt_str.Threshold	14709
k_CAVNodeAbsentDiag_Cnt_str.PStep	2811
k_CAVNodeAbsentDiag_Cnt_str.NStep	27918
k_CAVNodeAbsentTimeout_mS_u16	43920
k_CAVNodeTimeout_mS_u16	25684
k_CMM388MsgTimeout_mS_u16	55102
k_CMM388NTCEnableTimeout_mS_u16	62394
k_CMMNTCEnableTimeout_mS_u16	43366
k_CMMNodeAbsentDiag_Cnt_str.Threshold	18731
k_CMMNodeAbsentDiag_Cnt_str.PStep	2981
k_CMMNodeAbsentDiag_Cnt_str.NStep	35835
k_CMMNodeAbsentTimeout_mS_u16	13299
k_CONSANGLECPKMax_HwDeg_f32	525.945618
k_CONSANGLECPKMin_HwDeg_f32	-55.039299
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	45795
k_CONSANGLECPKSigValidThresh_Cnt_u16	19575
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	40365
k_CPKVehicleSpeedValidThresh_Cnt_u16	40281
k_CityParkInputInvalidThresh_Cnt_u16	30961
k_CityParkInputValidThresh_Cnt_u16	44073
k_ComputerRazGCTSigValidThresh_Cnt_u16	55700
k_CptTemporelSigValidThresh_Cnt_u16	11716
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	14327
k_DMDFCTCPKSigValidThresh_Cnt_u16	3683
k_DMDFCTCPKValidCount_Cnt_u16	17750
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	39260
k_DMDRELAXECPKSigValidThresh_Cnt_u16	18591

Name	Input Value
k_DMDRelaxeConsistentThresh_Cnt_u16	59493
k_DateValidThresh_Cnt_u16	56710
k_DefaultVehSpd_Kph_f32	173.485397
k_DiagMuxOnAbsentTimeout_mS_u16	4765
k_EMNodeTimeout_mS_u16	48285
k_ESPNTCEnableTimeout_mS_u16	28878
k_ESPNodeAbsentDiag_Cnt_str.Threshold	10978
k_ESPNodeAbsentDiag_Cnt_str.PStep	35771
k_ESPNodeAbsentDiag_Cnt_str.NStep	52925
k_ESPNodeAbsentTimeout_mS_u16	10747
k_EtatMTSigInvalidThresh_Cnt_u16	22962
k_EtatMTSigValidThresh_Cnt_u16	5334
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	57456
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	46968
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	9610
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	11763
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	23395
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	42490
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	37879
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	32239
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	24694
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	7371
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	16203
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	64322
k_ISDATDIRASentDiag_Cnt_str.Threshold	40169
k_ISDATDIRASentDiag_Cnt_str.PStep	14190
k_ISDATDIRASentDiag_Cnt_str.NStep	5512
k_ISDATDIRASentTimeout_mS_u16	62503
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	3679
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	64163
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	18010
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	7595
k_ISDYNAASChkSumValidThresh_Cnt_u16	4495
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	16927
k_ISDYNAASMsgCountValidThresh_Cnt_u16	15067
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	19503
k_ISDYNAASMsgLenValidThresh_Cnt_u16	3435
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	18893
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	60469
k_ISDYNABRChkSumValidThresh_Cnt_u16	5409
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	51534
k_ISDYNABRMsgCountValidThresh_Cnt_u16	49130
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	45678
k_ISDYNABRMsgLenValidThresh_Cnt_u16	22438
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	44625
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	46135
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	51223
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	974
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	43567
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	14219
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	48697
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	9041
k_ISDYNVOLChkSumValidThresh_Cnt_u16	59121
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	8715
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	56083
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	38965
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	32861
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	18748
k_IgnOnTimeout_mS_u16	18637
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	120.495697
k_PowerCutVehSpdLowThresh_Kph_f32	44.2535019
k_PowerCutVehSpdLowTimeout_mS_u16	30250
k_VBattMaxAAS_Volt_f32	27.8430996
k_VBattMaxBSI_Volt_f32	17.5485992
k_VBattMaxCAV_Volt_f32	0.384200007
k_VBattMaxCMM388_Volt_f32	15.8184996
k_VBattMaxCMM_Volt_f32	19.4759007
k_VBattMaxESP_Volt_f32	28.5216007
k_VBattMinAAS_Volt_f32	20.6021996
k_VBattMinBSI_Volt_f32	2.35599995
k_VBattMinCAV_Volt_f32	18.6364994
k_VBattMinCMM388_Volt_f32	3.58039999

Name	Input Value
k_VBattMinCMM_Volt_f32	32
k_VBattMinESP_Volt_f32	19.4759007
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	19353
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	57577
k_VitesseVehicleBVRampValidThresh_Cnt_u16	59131
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	34754
k_VitesseVehicleBVSigValidThresh_Cnt_u16	50562
k_VitesseVehicleBVSpeedPassThresh_kph_f32	222.985596
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	13906
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	32198
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4056601600
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	69
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	35283
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3766467072
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	215
target_SrlComInput_Per1_Batt_Volt_f32.value	25.5044003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	79774720
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	133
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.17213586
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2486039552
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	150
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1371149312
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	159
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2543203328
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	767710208
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3695080448
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1795855360
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2720445440
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	45
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	55
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2038649856
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	54
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	81
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	177
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	215
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	240
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	22
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3962631168
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	146
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2705134592
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2660840448

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	43
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	82
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	109
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3644638208
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	309
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0377896726
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	851650
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	103.1297
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	29037

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3766467072	3766467072	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	43864	43864	✔
AASNodeAbsentTimer_mS_M_u32	3766467072	3766467072	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3766467072	3766467072	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-622.447083	-622.447083	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3766467072	3766467072	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3766467072	3766467072	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3766467072	3766467072	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3766467072	3766467072	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3766467072	3766467072	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3766467072	3766467072	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	14709	14709	✔
CAVNodeAbsentTimer_mS_M_u32	3766467072	3766467072	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3766467072	3766467072	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3766467072	3766467072	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1795855360	1795855360	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	62951	62951	✔
CONSANGLECPK_HwDeg_M_f32	-541.609009	-541.609009 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3766467072	3766467072	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3766467072	3766467072	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3766467072	3766467072	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3766467072	3766467072	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3766467072	3766467072	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3766467072	3766467072	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3766467072	3766467072	✔
ESPNTCEnableTimer_mS_M_u32	3766467072	3766467072	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3766467072	3766467072	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1100	1100	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3766467072	3766467072	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3766467072	3766467072	✔
ElecIntTimer_mS_M_u32[1]	11001	11001	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3766467072	3766467072	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3766467072	3766467072	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3766467072	3766467072	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3766467072	3766467072	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3766467072	3766467072	✔
ISDATDIRASentFltAcc_Cnt_M_u16	40169	40169	✔
ISDATDIRASentTimer_mS_M_u32	3766467072	3766467072	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3766467072	3766467072	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3766467072	3766467072	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3766467072	3766467072	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3766467072	3766467072	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3766467072	3766467072	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3766467072	3766467072	✔
IgnOnTimer_mS_M_u32	975434752	975434752	✔
IgnTimeOff_Sec_M_u32	1208241684	1208241684	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	178	178	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2486039552	2486039552	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	150	150	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1371149312	1371149312	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	159	159	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2543203328	2543203328	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	148	148	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	767710208	767710208	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1734554624	1734554624	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	99	99	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1795855360	1795855360	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	205	205	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2720445440	2720445440	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	222	222	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2038649856	2038649856	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	22	22	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3962631168	3962631168	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	146	146	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2705134592	2705134592	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	242	242	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2660840448	2660840448	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3644638208	3644638208	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	322.874115	322.874115	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	573.005127	573.005127	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	470.746185	470.746185	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-622.447083	-622.447083	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	62951	62951	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1208241684	1208241684	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-541.609009	-541.609009 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	173.485397	173.485397	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.72 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	846354176
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	9842
AASNodeAbsentTimer_mS_M_u32	1547634432
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	4001
ANGLEVOLANTSigValidCount_Cnt_M_u16	49997
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	24387
AngleVolantMsgTimer_mS_M_u32	846354176
AngleVolantValidCount_Cnt_M_u16	54205
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-698.694763
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3284518656
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1385056000
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	4276844288
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	285030144
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	60996
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4142266112
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	57271
CAVNodeAbsentTimer_mS_M_u32	3306956544
CDD_SrlComVehSpd_Kph_G_f32	26.7264004
CMM388NTCEnableTimer_mS_M_u32	2077320960
CMM388NTCsEnabled_Cnt_M_lgc	0

Name	Input Value
CMMNTCEnableTimer_mS_M_u32	2194286336
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	6179
CMMNodeAbsentTimer_mS_M_u32	3553572608
CONSANGLECPKSigInvalidCount_Cnt_M_u16	61860
CONSANGLECPKSigValidCount_Cnt_M_u16	34272
CONSANGLECPK_Cnt_M_u16	64055
CONSANGLECPK_HwDeg_M_f32	-90.0739975
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	64055
CPKVehicleSpeedMsgTimer_mS_M_u32	4046280448
CPKVehicleSpeedValidCount_Cnt_M_u16	62589
CityParkInputConsistentCount_Cnt_M_u16	35633
CityParkInputInvalidCount_Cnt_M_u16	59883
CityParkInputMsgTimer_mS_M_u32	2486039552
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4038264576
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	52198
ComputerRazGCTSigInvalidTimer_mS_M_u32	3722356480
ComputerRazGCTSigValidCount_Cnt_M_u16	7066
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	32375
DMDFCTCPKSigValidCount_Cnt_M_u16	18475
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	40539
DMDRELAXECPKSigValidCount_Cnt_M_u16	51591
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	51061
DateInvalidTimer_mS_M_u32	1385056000
DiagMuxOnAbsentTimer_mS_M_u32	4072347392
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	285030144
ESPNTCEnableTimer_mS_M_u32	608438016
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	62523
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	2050
EffacDefaultDiagTimer_mS_M_u32[1]	6070
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	6454
ElecIntTimer_mS_M_u32[1]	8258
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3112171264
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	31297
EtatMTSigValidCount_Cnt_M_u16	64649
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	11870
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	47642
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	10201
ISDAT4V2BSI552MsgTimer_mS_M_u32	2537764608
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	29348
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	45908
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	64649
ISDATBSI3F2MsgTimer_mS_M_u32	771823360
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	17291
ISDATBSI412MsgLenValidCount_Cnt_M_u16	57131
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	31297
ISDATBSI412MsgTimer_mS_M_u32	196630272
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	19095
ISDATBSI432MsgLenValidCount_Cnt_M_u16	54703
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	62300
ISDATDIRASentFltAcc_Cnt_M_u16	63776
ISDATDIRASentTimer_mS_M_u32	4046280448
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	15869
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	54205
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	23706
ISDYN2CMMMsgTimer_mS_M_u32	1704331008
ISDYNAASChkSumInvalidCount_Cnt_M_u16	61740
ISDYNAASChkSumValidCount_Cnt_M_u16	40569
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	20448
ISDYNAASMsgCount_Cnt_M_u08	13

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	63822
ISDYNAASMsgLenValidCount_Cnt_M_u16	45555
ISDYNAASMsgTimeValidCount_Cnt_M_u16	61740
ISDYNAASMsgTimer_mS_M_u32	693987072
ISDYNABRChkSumInvalidCount_Cnt_M_u16	7852
ISDYNABRChkSumValidCount_Cnt_M_u16	48832
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	43471
ISDYNABRMsgCountValidCount_Cnt_M_u16	39772
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	31047
ISDYNABRMsgLenValidCount_Cnt_M_u16	37315
ISDYNABRMsgTimeValidCount_Cnt_M_u16	64055
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	645
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1175
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	64649
ISDYNCMM208MsgTimer_mS_M_u32	2842609408
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2431
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1281
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	36867
ISDYNCMM388MsgTimer_mS_M_u32	4220446464
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	50410
ISDYNVOLChkSumValidCount_Cnt_M_u16	24998
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	24765
ISDYNVOLMsgCountValidCount_Cnt_M_u16	29425
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	18072
ISDYNVOLMsgLenValidCount_Cnt_M_u16	49460
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	6179
ISDYNVOLMsgTimer_mS_M_u32	3882526464
IgnOnTimer_mS_M_u32	3322078976
IgnTimeOff_Sec_M_u32	1074379035
ManVehSpd_Kph_M_f32	156.607193
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	111
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	57
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3071219456
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	74
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1039038208
PrevISDATBSI412MsgDLCError_Cnt_M_u08	116
PrevISDATBSI412MsgRxTime_MSec_M_u32	3129026304
PrevISDATBSI432MsgDLCError_Cnt_M_u08	142
PrevISDATBSI432MsgRxTime_MSec_M_u32	1172834048
PrevISDATDIRAMsgTxTime_MSec_M_u32	1262823168
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	228
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1772664576
PrevISDYNAASMsgDLCError_Cnt_M_u08	200
PrevISDYNAASMsgRxTime_MSec_M_u32	2469439232
PrevISDYNABRMsgDLCError_Cnt_M_u08	61
PrevISDYNABRMsgRxTime_MSec_M_u32	1763072
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	230
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2086250240
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	169
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1799292672
PrevISDYNVOLMsgDLCError_Cnt_M_u08	95
PrevISDYNVOLMsgRxTime_MSec_M_u32	887236352
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3288225536
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	142.624496
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0

Name	Input Value
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	31124
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	64185
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	55153
VitesseVehicleBVRampValidCount_Cnt_M_u16	62550
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	62718
VitesseVehicleBVSigValidCount_Cnt_M_u16	58474
VitesseVehicleBV_Kph_M_f32	4.98649979
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	36867
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	65287
VitesseVehiculeRoues_Kph_M_f32	100.247498
k_AASNTCEnableTimeout_mS_u16	22578
k_AASNodeAbsentDiag_Cnt_str.Threshold	58734
k_AASNodeAbsentDiag_Cnt_str.PStep	54319
k_AASNodeAbsentDiag_Cnt_str.NStep	34464
k_AASNodeAbsentTimeout_mS_u16	14188
k_AASNodeTimeout_mS_u16	35257
k_ABSNodeTimeout_mS_u16	50912
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	50310
k_ANGLEVOLANTSigValidThresh_Cnt_u16	13534
k_AngleVolantInvalidThresh_Cnt_u16	24169
k_AngleVolantValidThresh_Cnt_u16	59883
k_BSI552MsgTimeout_mS_u16	5202
k_BSINTCEnableTimeout_mS_u16	46255
k_BSINodeAbsentDiag_Cnt_str.Threshold	23212
k_BSINodeAbsentDiag_Cnt_str.PStep	35675
k_BSINodeAbsentDiag_Cnt_str.NStep	13440
k_BSINodeAbsentTimeout_mS_u16	859
k_BSINodeTimeout_mS_u16	62300
k_BattOvHi_Volt_f32	28.7005005
k_BattOvLo_Volt_f32	28.5177994
k_BattUvHi_Volt_f32	21.7952995
k_BattUvLo_Volt_f32	5.14069986
k_CAVNTCEnableTimeout_mS_u16	42057
k_CAVNodeAbsentDiag_Cnt_str.Threshold	16141
k_CAVNodeAbsentDiag_Cnt_str.PStep	64147
k_CAVNodeAbsentDiag_Cnt_str.NStep	64434
k_CAVNodeAbsentTimeout_mS_u16	18173
k_CAVNodeTimeout_mS_u16	30512
k_CMM388MsgTimeout_mS_u16	62834
k_CMM388NTCEnableTimeout_mS_u16	36862
k_CMMNTCEnableTimeout_mS_u16	43196
k_CMMNodeAbsentDiag_Cnt_str.Threshold	10068
k_CMMNodeAbsentDiag_Cnt_str.PStep	23741
k_CMMNodeAbsentDiag_Cnt_str.NStep	43476
k_CMMNodeAbsentTimeout_mS_u16	51091
k_CONSANGLECPKMax_HwDeg_f32	640.638306
k_CONSANGLECPKMin_HwDeg_f32	-651.747681
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	57091
k_CONSANGLECPKSigValidThresh_Cnt_u16	36359
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	20583
k_CPKVehicleSpeedValidThresh_Cnt_u16	43490
k_CityParkInputInvalidThresh_Cnt_u16	62426
k_CityParkInputValidThresh_Cnt_u16	35633
k_ComputerRazGCTSigValidThresh_Cnt_u16	20530
k_CptTemporelSigValidThresh_Cnt_u16	16226
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	18503
k_DMDFCTCPKSigValidThresh_Cnt_u16	41155
k_DMDFCTCPKValidCount_Cnt_u16	26924
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	23706
k_DMDRELAXECPKSigValidThresh_Cnt_u16	35470
k_DMDRelaxeConsistentThresh_Cnt_u16	17212
k_DateValidThresh_Cnt_u16	10201
k_DefaultVehSpd_Kph_f32	241.226395
k_DiagMuxOnAbsentTimeout_mS_u16	64533
k_EMNodeTimeout_mS_u16	53845
k_ESPNTCEnableTimeout_mS_u16	28483

Name	Input Value
k_ESPNodeAbsentDiag_Cnt_str.Threshold	34062
k_ESPNodeAbsentDiag_Cnt_str.PStep	10333
k_ESPNodeAbsentDiag_Cnt_str.NStep	11887
k_ESPNodeAbsentTimeout_mS_u16	1403
k_EtatMTSigInvalidThresh_Cnt_u16	38295
k_EtatMTSigValidThresh_Cnt_u16	8171
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	21534
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	6854
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	58126
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	36629
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	62085
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	21503
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	26248
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	46176
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	48395
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	5515
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	55755
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	50471
k_ISDATDIRASentDiag_Cnt_str.Threshold	36145
k_ISDATDIRASentDiag_Cnt_str.PStep	43449
k_ISDATDIRASentDiag_Cnt_str.NStep	4803
k_ISDATDIRASentTimeout_mS_u16	55864
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	16336
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	24387
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	7839
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	28076
k_ISDYNAASChkSumValidThresh_Cnt_u16	19904
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	30927
k_ISDYNAASMsgCountValidThresh_Cnt_u16	43612
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	61984
k_ISDYNAASMsgLenValidThresh_Cnt_u16	31021
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	18630
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	41869
k_ISDYNABRChkSumValidThresh_Cnt_u16	1161
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	48452
k_ISDYNABRMsgCountValidThresh_Cnt_u16	30000
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	42787
k_ISDYNABRMsgLenValidThresh_Cnt_u16	49979
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	1531
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	35080
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	41384
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	57860
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	56993
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	53837
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	41475
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	63482
k_ISDYNVOLChkSumValidThresh_Cnt_u16	22746
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	14348
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	308
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	8909
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	13845
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	15543
k_IgnOnTimeout_mS_u16	30598
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	98.6957016
k_PowerCutVehSpdLowThresh_Kph_f32	207.422195
k_PowerCutVehSpdLowTimeout_mS_u16	17774
k_VBattMaxAAS_Volt_f32	20.0702991
k_VBattMaxBSI_Volt_f32	28.5216007
k_VBattMaxCAV_Volt_f32	17.4657001
k_VBattMaxCMM388_Volt_f32	2.9382
k_VBattMaxCMM_Volt_f32	26.2227001
k_VBattMaxESP_Volt_f32	4.85419989
k_VBattMinAAS_Volt_f32	24.7453003
k_VBattMinBSI_Volt_f32	4.85419989
k_VBattMinCAV_Volt_f32	13.7235003
k_VBattMinCMM388_Volt_f32	20.5419998
k_VBattMinCMM_Volt_f32	27.1835995
k_VBattMinESP_Volt_f32	26.2227001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	61474
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	39922
k_VitesseVehicleBVRampValidThresh_Cnt_u16	44989
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	28838

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VitesseVehicleBVSigValidThresh_Cnt_u16	58150
k_VitesseVehicleBVSpeedPassThresh_kph_f32	104.505699
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	11959
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	21532
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1385056000
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	91
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	20707
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3783759104
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	169
target_SrlComInput_Per1_Batt_Volt_f32.value	23.0720997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1063974656
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	18
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.770668864
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	146
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1608836864
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4290807552
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1185687296
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	85
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3701982976
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1773364992
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	25
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2513372928
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	150644480
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	58
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	104
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	196
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	201
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	185
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1030014720
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	45
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	47
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	160
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	601614080
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3711403776
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	78
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4255328000
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	164
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	165

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	189
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	267941632
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1704
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.203104377
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	772584
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	196.043594
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	43366

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3783759104	3783759104	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3783759104	3783759104	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3783759104	3783759104	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-698.694763	-698.694763	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3284518656	3284518656	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	1385056000	1385056000	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4276844288	4276844288	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	285030144	285030144	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3783759104	3783759104	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3783759104	3783759104	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	16141	16141	✔
CAVNodeAbsentTimer_mS_M_u32	3783759104	3783759104	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3783759104	3783759104	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3783759104	3783759104	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3783759104	3783759104	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	64055	64055	✔
CONSANGLECPK_HwDeg_M_f32	-90.0739975	-90.0739975 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3783759104	3783759104	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3783759104	3783759104	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3783759104	3783759104	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3783759104	3783759104	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3783759104	3783759104	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3783759104	3783759104	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3783759104	3783759104	✔
ESPNTCEnableTimer_mS_M_u32	3783759104	3783759104	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	34062	34062	✔
ESPNodeAbsentTimer_mS_M_u32	3783759104	3783759104	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2050	2050	✔
EffacDefaultDiagTimer_mS_M_u32[1]	6070	6070	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	6454	6454	✔
ElecIntTimer_mS_M_u32[1]	8258	8258	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3783759104	3783759104	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3783759104	3783759104	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3783759104	3783759104	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3783759104	3783759104	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3701982976	3701982976	✔
ISDATDIRASentFltAcc_Cnt_M_u16	36145	36145	✔
ISDATDIRASentTimer_mS_M_u32	3783759104	3783759104	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3783759104	3783759104	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3783759104	3783759104	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3783759104	3783759104	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3783759104	3783759104	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3783759104	3783759104	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3783759104	3783759104	✔
IgnOnTimer_mS_M_u32	3783759104	3783759104	✔
IgnTimeOff_Sec_M_u32	1074379035	1074379035	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	146	146	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1608836864	1608836864	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	29	29	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4290807552	4290807552	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	123	123	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1185687296	1185687296	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	85	85	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3701982976	3701982976	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1262823168	1262823168	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	25	25	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2513372928	2513372928	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	84	84	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	150644480	150644480	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	185	185	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1030014720	1030014720	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	49	49	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	601614080	601614080	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	246	246	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3711403776	3711403776	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	78	78	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4255328000	4255328000	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	267941632	267941632	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	142.624496	142.624496	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	4.98649979	4.98649979	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	100.247498	100.247498	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-698.694763	-698.694763	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	64055	64055	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1074379035	1074379035	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-90.0739975	-90.0739975 ± 0.0125	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	241.226395	241.226395	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0139	0x0139	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.73 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1961593088
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	15600
AASNodeAbsentTimer_mS_M_u32	345880832
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	21394
ANGLEVOLANTSigValidCount_Cnt_M_u16	38944
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	9289
AngleVolantMsgTimer_mS_M_u32	1961593088
AngleVolantValidCount_Cnt_M_u16	42383
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-650.06012
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1985640704
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	4016503040
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3660425472
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2999806208
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	24397
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1442588928
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	54622
CAVNodeAbsentTimer_mS_M_u32	2573457664
CDD_SrlComVehSpd_Kph_G_f32	485.127808
CMM388NTCEnableTimer_mS_M_u32	2814580992
CMM388NTCsEnabled_Cnt_M_lgc	1

Name	Input Value
CMMNTCEnableTimer_mS_M_u32	4102150400
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	30373
CMMNodeAbsentTimer_mS_M_u32	3694094592
CONSANGLECPKSigInvalidCount_Cnt_M_u16	25515
CONSANGLECPKSigValidCount_Cnt_M_u16	3400
CONSANGLECPK_Cnt_M_u16	31831
CONSANGLECPK_HwDeg_M_f32	-147.5802
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	31831
CPKVehicleSpeedMsgTimer_mS_M_u32	561940736
CPKVehicleSpeedValidCount_Cnt_M_u16	15011
CityParkInputConsistentCount_Cnt_M_u16	14499
CityParkInputInvalidCount_Cnt_M_u16	14127
CityParkInputMsgTimer_mS_M_u32	3159100928
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1823586560
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	11780
ComputerRazGCTSigInvalidTimer_mS_M_u32	2084198656
ComputerRazGCTSigValidCount_Cnt_M_u16	62548
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	20507
DMDFCTCPKSigValidCount_Cnt_M_u16	39665
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	59420
DMDRELAXECPKSigValidCount_Cnt_M_u16	24618
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	53252
DateInvalidTimer_mS_M_u32	4016503040
DiagMuxOnAbsentTimer_mS_M_u32	3313125632
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2999806208
ESPNTCEnableTimer_mS_M_u32	617265408
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	1790
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	6454
EffacDefaultDiagTimer_mS_M_u32[1]	8257
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	5
ElecIntTimer_mS_M_u32[1]	56
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3177588992
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	13237
EtatMTSigValidCount_Cnt_M_u16	7103
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	5685
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	29522
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	10255
ISDAT4V2BSI552MsgTimer_mS_M_u32	3678628096
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	6703
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	62432
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	7103
ISDATBSI3F2MsgTimer_mS_M_u32	1257261312
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	25680
ISDATBSI412MsgLenValidCount_Cnt_M_u16	61554
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	13237
ISDATBSI412MsgTimer_mS_M_u32	2288093440
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	23737
ISDATBSI432MsgLenValidCount_Cnt_M_u16	5138
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0
ISDATDIRASentFltAcc_Cnt_M_u16	25103
ISDATDIRASentTimer_mS_M_u32	561940736
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	20045
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	42383
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	22358
ISDYN2CMMMsgTimer_mS_M_u32	3232545024
ISDYNAASChkSumInvalidCount_Cnt_M_u16	60794
ISDYNAASChkSumValidCount_Cnt_M_u16	63655
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	15050
ISDYNAASMsgCount_Cnt_M_u08	15

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	5037
ISDYNAASMsgLenValidCount_Cnt_M_u16	17650
ISDYNAASMsgTimeValidCount_Cnt_M_u16	60794
ISDYNAASMsgTimer_mS_M_u32	2712606976
ISDYNABRChkSumInvalidCount_Cnt_M_u16	17908
ISDYNABRChkSumValidCount_Cnt_M_u16	6698
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	41781
ISDYNABRMsgCountValidCount_Cnt_M_u16	5282
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	24678
ISDYNABRMsgLenValidCount_Cnt_M_u16	45123
ISDYNABRMsgTimeValidCount_Cnt_M_u16	31831
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	647
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1179
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	7103
ISDYNCMM208MsgTimer_mS_M_u32	827029760
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2439
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1285
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	46085
ISDYNCMM388MsgTimer_mS_M_u32	560765184
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	16673
ISDYNVOLChkSumValidCount_Cnt_M_u16	14142
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	46225
ISDYNVOLMsgCountValidCount_Cnt_M_u16	35815
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	46147
ISDYNVOLMsgLenValidCount_Cnt_M_u16	30529
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	30373
ISDYNVOLMsgTimer_mS_M_u32	2988857600
IgnOnTimer_mS_M_u32	1602263296
IgnTimeOff_Sec_M_u32	2601150342
ManVehSpd_Kph_M_f32	32.4337997
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	115
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	178
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3429779712
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	97
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1229498624
PrevISDATBSI412MsgDLCError_Cnt_M_u08	9
PrevISDATBSI412MsgRxTime_MSec_M_u32	1106303232
PrevISDATBSI432MsgDLCError_Cnt_M_u08	156
PrevISDATBSI432MsgRxTime_MSec_M_u32	4086216960
PrevISDATDIRAMsgTxTime_MSec_M_u32	4174698752
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	247
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2094328064
PrevISDYNAASMsgDLCError_Cnt_M_u08	205
PrevISDYNAASMsgRxTime_MSec_M_u32	740055296
PrevISDYNABRMsgDLCError_Cnt_M_u08	225
PrevISDYNABRMsgRxTime_MSec_M_u32	710449408
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	16
PrevISDYNCMM208MsgRxTime_MSec_M_u32	109926656
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	143
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2610804992
PrevISDYNVOLMsgDLCError_Cnt_M_u08	150
PrevISDYNVOLMsgRxTime_MSec_M_u32	4149860608
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1926727936
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	430.891907
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1

Name	Input Value
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	1571
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	17384
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	6888
VitesseVehicleBVRampValidCount_Cnt_M_u16	53869
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	11223
VitesseVehicleBVSigValidCount_Cnt_M_u16	35365
VitesseVehicleBV_Kph_M_f32	376.638306
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	46085
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	20139
VitesseVehiculeRoues_Kph_M_f32	52.0625
k_AASNTCEnableTimeout_mS_u16	49706
k_AASNodeAbsentDiag_Cnt_str.Threshold	28889
k_AASNodeAbsentDiag_Cnt_str.PStep	58063
k_AASNodeAbsentDiag_Cnt_str.NStep	48246
k_AASNodeAbsentTimeout_mS_u16	16054
k_AASNodeTimeout_mS_u16	19176
k_ABSNodeTimeout_mS_u16	33740
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	48672
k_ANGLEVOLANTSigValidThresh_Cnt_u16	33977
k_AngleVolantInvalidThresh_Cnt_u16	29340
k_AngleVolantValidThresh_Cnt_u16	14127
k_BSI552MsgTimeout_mS_u16	34382
k_BSINTCEnableTimeout_mS_u16	55185
k_BSINodeAbsentDiag_Cnt_str.Threshold	23292
k_BSINodeAbsentDiag_Cnt_str.PStep	35641
k_BSINodeAbsentDiag_Cnt_str.NStep	13486
k_BSINodeAbsentTimeout_mS_u16	43297
k_BSINodeTimeout_mS_u16	36395
k_BattOvHi_Volt_f32	21.3341007
k_BattOvLo_Volt_f32	28.5123997
k_BattUvHi_Volt_f32	31.4232006
k_BattUvLo_Volt_f32	30.2577
k_CAVNTCEnableTimeout_mS_u16	62589
k_CAVNodeAbsentDiag_Cnt_str.Threshold	65249
k_CAVNodeAbsentDiag_Cnt_str.PStep	38979
k_CAVNodeAbsentDiag_Cnt_str.NStep	1675
k_CAVNodeAbsentTimeout_mS_u16	59092
k_CAVNodeTimeout_mS_u16	62871
k_CMM388MsgTimeout_mS_u16	33776
k_CMM388NTCEnableTimeout_mS_u16	53980
k_CMMNTCEnableTimeout_mS_u16	49415
k_CMMNodeAbsentDiag_Cnt_str.Threshold	11950
k_CMMNodeAbsentDiag_Cnt_str.PStep	30351
k_CMMNodeAbsentDiag_Cnt_str.NStep	18959
k_CMMNodeAbsentTimeout_mS_u16	15255
k_CONSANGLECPKMax_HwDeg_f32	576.061829
k_CONSANGLECPKMin_HwDeg_f32	-167.547104
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	31493
k_CONSANGLECPKSigValidThresh_Cnt_u16	21931
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	63238
k_CPKVehicleSpeedValidThresh_Cnt_u16	21855
k_CityParkInputInvalidThresh_Cnt_u16	29842
k_CityParkInputValidThresh_Cnt_u16	14499
k_ComputerRazGCTSigValidThresh_Cnt_u16	37933
k_CptTemporelSigValidThresh_Cnt_u16	36958
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	42854
k_DMDFCTCPKSigValidThresh_Cnt_u16	14147
k_DMDFCTCPKValidCount_Cnt_u16	61813
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	22358
k_DMDRELAXECPKSigValidThresh_Cnt_u16	10348
k_DMDRelaxeConsistentThresh_Cnt_u16	22154
k_DateValidThresh_Cnt_u16	10255
k_DefaultVehSpd_Kph_f32	66.9381027
k_DiagMuxOnAbsentTimeout_mS_u16	48421
k_EMNodeTimeout_mS_u16	12772
k_ESPNTCEnableTimeout_mS_u16	49482

Name	Input Value
k_ESPNodeAbsentDiag_Cnt_str.Threshold	11771
k_ESPNodeAbsentDiag_Cnt_str.PStep	29932
k_ESPNodeAbsentDiag_Cnt_str.NStep	56128
k_ESPNodeAbsentTimeout_mS_u16	43199
k_EtatMTSigInvalidThresh_Cnt_u16	60471
k_EtatMTSigValidThresh_Cnt_u16	64685
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	28789
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	49119
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	5992
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	552
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	5273
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	6244
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	16434
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	53323
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	33485
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	37451
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	35853
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	1221
k_ISDATDIRASentDiag_Cnt_str.Threshold	14113
k_ISDATDIRASentDiag_Cnt_str.PStep	29086
k_ISDATDIRASentDiag_Cnt_str.NStep	65322
k_ISDATDIRASentTimeout_mS_u16	48608
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	64694
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	9289
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	19334
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	3316
k_ISDYNAASChkSumValidThresh_Cnt_u16	8490
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	59957
k_ISDYNAASMsgCountValidThresh_Cnt_u16	39842
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	54536
k_ISDYNAASMsgLenValidThresh_Cnt_u16	54780
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	30689
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	19676
k_ISDYNABRChkSumValidThresh_Cnt_u16	10553
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	42573
k_ISDYNABRMsgCountValidThresh_Cnt_u16	4379
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	32165
k_ISDYNABRMsgLenValidThresh_Cnt_u16	19966
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	41022
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	45367
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	31573
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	56715
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	39570
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	7968
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	28679
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	54327
k_ISDYNVOLChkSumValidThresh_Cnt_u16	20377
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	20823
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	36926
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	161
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	427
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	5085
k_IgnOnTimeout_mS_u16	12323
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	13.1612997
k_PowerCutVehSpdLowThresh_Kph_f32	111.700302
k_PowerCutVehSpdLowTimeout_mS_u16	31046
k_VBattMaxAAS_Volt_f32	6.85449982
k_VBattMaxBSI_Volt_f32	28.6574001
k_VBattMaxCAV_Volt_f32	4.74720001
k_VBattMaxCMM388_Volt_f32	16.9561005
k_VBattMaxCMM_Volt_f32	18.1399994
k_VBattMaxESP_Volt_f32	28.6574001
k_VBattMinAAS_Volt_f32	6.06780005
k_VBattMinBSI_Volt_f32	2.56229997
k_VBattMinCAV_Volt_f32	31.3309002
k_VBattMinCMM388_Volt_f32	29.4043999
k_VBattMinCMM_Volt_f32	0.426299989
k_VBattMinESP_Volt_f32	18.1399994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	32664
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	7530
k_VitesseVehicleBVRampValidThresh_Cnt_u16	31633
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	48702

Name	Input Value
k_VitesseVehicleBVSigValidThresh_Cnt_u16	55360
k_VitesseVehicleBVSpeedPassThresh_kph_f32	571.104309
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	40030
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	41059
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4016503040
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	31
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	5191
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	4258969344
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	143
target_SrlComInput_Per1_Batt_Volt_f32.value	23.3866997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3936954624
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	67
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.62721765
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	47
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2557647104
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1881880832
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	217
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2809387264
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	642545920
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3568638208
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2595076352
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	87
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1614174464
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	83
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	155
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	189
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	190
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	238
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	199
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1425111296
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	35
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	37
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	62
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	85
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	92
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	163
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	187
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	203
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	32
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3558971648
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2438609152
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	149
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1847777536
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	184

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3147999488
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2735
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.967515051
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1002348
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	167.792404
target_SrlComInput_Per1_VitesseVehiculeBV_Cnt_u16.value	1157

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4258969344	4258969344	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4258969344	4258969344	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	4258969344	4258969344	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-650.06012	-650.06012	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1985640704	1985640704	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4016503040	4016503040	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	3660425472	3660425472	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	2999806208	2999806208	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	4258969344	4258969344	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4258969344	4258969344	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	65249	65249	✔
CAVNodeAbsentTimer_mS_M_u32	4258969344	4258969344	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4258969344	4258969344	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4258969344	4258969344	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4258969344	4258969344	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	31831	31831	✔
CONSANGLECPK_HwDeg_M_f32	-147.5802	-147.5802 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4258969344	4258969344	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	4258969344	4258969344	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4258969344	4258969344	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4258969344	4258969344	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4258969344	4258969344	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4258969344	4258969344	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4258969344	4258969344	✔
ESPNTCEnableTimer_mS_M_u32	4258969344	4258969344	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	11771	11771	✔
ESPNodeAbsentTimer_mS_M_u32	4258969344	4258969344	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	6454	6454	✔
EffacDefaultDiagTimer_mS_M_u32[1]	8257	8257	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	5	5	✔
ElecIntTimer_mS_M_u32[1]	56	56	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4258969344	4258969344	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2557647104	2557647104	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4258969344	4258969344	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2809387264	2809387264	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	642545920	642545920	✔
ISDATDIRASentFltAcc_Cnt_M_u16	14113	14113	✔
ISDATDIRASentTimer_mS_M_u32	4258969344	4258969344	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4258969344	4258969344	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4258969344	4258969344	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4258969344	4258969344	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4258969344	4258969344	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4258969344	4258969344	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4258969344	4258969344	✔
IgnOnTimer_mS_M_u32	1602263296	1602263296	✔
IgnTimeOff_Sec_M_u32	2601150342	2601150342	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	47	47	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2557647104	2557647104	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	14	14	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1881880832	1881880832	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	217	217	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2809387264	2809387264	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	119	119	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	642545920	642545920	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4174698752	4174698752	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	206	206	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2595076352	2595076352	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	87	87	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1614174464	1614174464	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	199	199	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1425111296	1425111296	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	32	32	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3558971648	3558971648	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	5	5	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2438609152	2438609152	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	149	149	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1847777536	1847777536	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3147999488	3147999488	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	430.891907	430.891907	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	376.638306	376.638306	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	52.0625	52.0625	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-650.06012	-650.06012	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	31831	31831	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2601150342	2601150342	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-147.5802	-147.5802 ± 0.0125	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	66.9381027	66.9381027	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0161	0x0161	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.74 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1514153984
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	46130
AASNodeAbsentTimer_mS_M_u32	1072273408
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	6731
ANGLEVOLANTSigValidCount_Cnt_M_u16	57186
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	41511
AngleVolantMsgTimer_mS_M_u32	1514153984
AngleVolantValidCount_Cnt_M_u16	211
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-381.109497
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	4256389120
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1687017472
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1526319104
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1738752
BSI552NTCsEnabled_Cnt_M_lgc	1

Name	Input Value
BSINodeAbsentFltAcc_Cnt_M_u16	41754
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1099843584
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	52072
CAVNodeAbsentTimer_mS_M_u32	4061607936
CDD_SrlComVehSpd_Kph_G_f32	309.198914
CMM388NTCEnableTimer_mS_M_u32	1408858112
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3636279296
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	61267
CMMNodeAbsentTimer_mS_M_u32	2348058624
CONSANGLECPKSigInvalidCount_Cnt_M_u16	15616
CONSANGLECPKSigValidCount_Cnt_M_u16	4839
CONSANGLECPK_Cnt_M_u16	49594
CONSANGLECPK_HwDeg_M_f32	610.967529
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	49594
CPKVehicleSpeedMsgTimer_mS_M_u32	1619470336
CPKVehicleSpeedValidCount_Cnt_M_u16	35871
CityParkInputConsistentCount_Cnt_M_u16	38807
CityParkInputInvalidCount_Cnt_M_u16	7411
CityParkInputMsgTimer_mS_M_u32	2557647104
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2276300800
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	12534
ComputerRazGCTSigInvalidTimer_mS_M_u32	3281238016
ComputerRazGCTSigValidCount_Cnt_M_u16	26756
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	33327
DMDFCTCPKSigValidCount_Cnt_M_u16	21613
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	1197
DMDRELAXECPKSigValidCount_Cnt_M_u16	12100
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	39925
DateInvalidTimer_mS_M_u32	1687017472
DiagMuxOnAbsentTimer_mS_M_u32	328460288
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1738752
ESPNTCEnableTimer_mS_M_u32	56793088
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	262
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	8976
EffacDefaultDiagTimer_mS_M_u32[1]	3182075392
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	978
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	860899328
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	18722
EtatMTSigValidCount_Cnt_M_u16	5061
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	52578
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	35017
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	42259
ISDAT4V2BSI552MsgTimer_mS_M_u32	3736635392
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	21813
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	60128
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	5061
ISDATBSI3F2MsgTimer_mS_M_u32	3677480960
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	35793
ISDATBSI412MsgLenValidCount_Cnt_M_u16	51756
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	18722
ISDATBSI412MsgTimer_mS_M_u32	2011047936
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	36119
ISDATBSI432MsgLenValidCount_Cnt_M_u16	10698
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	65535
ISDATDIRASentFltAcc_Cnt_M_u16	10581

Name	Input Value
ISDATDIRASentTimer_mS_M_u32	1619470336
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	41944
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	211
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	6270
ISDYN2CMMMsgTimer_mS_M_u32	935106560
ISDYNAASChkSumInvalidCount_Cnt_M_u16	19092
ISDYNAASChkSumValidCount_Cnt_M_u16	15307
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	60706
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	3195
ISDYNAASMsgLenValidCount_Cnt_M_u16	60266
ISDYNAASMsgTimeValidCount_Cnt_M_u16	19092
ISDYNAASMsgTimer_mS_M_u32	372602880
ISDYNABRChkSumInvalidCount_Cnt_M_u16	41637
ISDYNABRChkSumValidCount_Cnt_M_u16	22724
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	54627
ISDYNABRMsgCountValidCount_Cnt_M_u16	37850
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	62159
ISDYNABRMsgLenValidCount_Cnt_M_u16	54774
ISDYNABRMsgTimeValidCount_Cnt_M_u16	49594
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	648
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1181
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	5061
ISDYNCMM208MsgTimer_mS_M_u32	3504363520
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2443
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1287
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	11633
ISDYNCMM388MsgTimer_mS_M_u32	1828517888
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	64670
ISDYNVOLChkSumValidCount_Cnt_M_u16	60677
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	44237
ISDYNVOLMsgCountValidCount_Cnt_M_u16	55691
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	19767
ISDYNVOLMsgLenValidCount_Cnt_M_u16	22270
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	61267
ISDYNVOLMsgTimer_mS_M_u32	3520051200
IgnOnTimer_mS_M_u32	46200832
IgnTimeOff_Sec_M_u32	402140977
ManVehSpd_Kph_M_f32	161.673004
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	117
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	165
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3468158976
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	119
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	967362560
PrevISDATBSI412MsgDLCError_Cnt_M_u08	192
PrevISDATBSI412MsgRxTime_MSec_M_u32	1819293696
PrevISDATBSI432MsgDLCError_Cnt_M_u08	134
PrevISDATBSI432MsgRxTime_MSec_M_u32	2803275776
PrevISDATDIRAMsgTxTime_MSec_M_u32	3619960832
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	247
PrevISDYN2CMMMsgRxTime_MSec_M_u32	537135104
PrevISDYNAASMsgDLCError_Cnt_M_u08	56
PrevISDYNAASMsgRxTime_MSec_M_u32	3152918528
PrevISDYNABRMsgDLCError_Cnt_M_u08	133
PrevISDYNABRMsgRxTime_MSec_M_u32	37287936
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	24
PrevISDYNCMM208MsgRxTime_MSec_M_u32	815446016
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	172
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2867435520
PrevISDYNVOLMsgDLCError_Cnt_M_u08	170
PrevISDYNVOLMsgRxTime_MSec_M_u32	808794112
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	276572160
PrevModeDiag_Cnt_M_u08	0

Name	Input Value
PrevSrlComVehSpd_Kph_M_f32	477.034485
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	36121
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	18056
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	41674
VitesseVehicleBVRampValidCount_Cnt_M_u16	61177
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	58748
VitesseVehicleBVSigValidCount_Cnt_M_u16	23891
VitesseVehicleBV_Kph_M_f32	503.912109
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	11633
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	20544
VitesseVehiculeRoues_Kph_M_f32	625.16687
k_AASNTCEnableTimeout_mS_u16	64577
k_AASNodeAbsentDiag_Cnt_str.Threshold	3295
k_AASNodeAbsentDiag_Cnt_str.PStep	13107
k_AASNodeAbsentDiag_Cnt_str.NStep	22709
k_AASNodeAbsentTimeout_mS_u16	37214
k_AASNodeTimeout_mS_u16	12680
k_ABSNodeTimeout_mS_u16	60188
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	50402
k_ANGLEVOLANTSigValidThresh_Cnt_u16	13269
k_AngleVolantInvalidThresh_Cnt_u16	46636
k_AngleVolantValidThresh_Cnt_u16	7411
k_BSI552MsgTimeout_mS_u16	62807
k_BSINTCEnableTimeout_mS_u16	31887
k_BSINodeAbsentDiag_Cnt_str.Threshold	23332
k_BSINodeAbsentDiag_Cnt_str.PStep	35624
k_BSINodeAbsentDiag_Cnt_str.NStep	13509
k_BSINodeAbsentTimeout_mS_u16	29599
k_BSINodeTimeout_mS_u16	5377
k_BattOvHi_Volt_f32	23.2474995
k_BattOvLo_Volt_f32	4.72779989
k_BattUvHi_Volt_f32	30.8757
k_BattUvLo_Volt_f32	22.5338993
k_CAVNTCEnableTimeout_mS_u16	40201
k_CAVNodeAbsentDiag_Cnt_str.Threshold	38814
k_CAVNodeAbsentDiag_Cnt_str.PStep	55536
k_CAVNodeAbsentDiag_Cnt_str.NStep	34768
k_CAVNodeAbsentTimeout_mS_u16	61190
k_CAVNodeTimeout_mS_u16	14140
k_CMM388MsgTimeout_mS_u16	57138
k_CMM388NTCEnableTimeout_mS_u16	41582
k_CMMNTCEnableTimeout_mS_u16	49325
k_CMMNodeAbsentDiag_Cnt_str.Threshold	28734
k_CMMNodeAbsentDiag_Cnt_str.PStep	36307
k_CMMNodeAbsentDiag_Cnt_str.NStep	30413
k_CMMNodeAbsentTimeout_mS_u16	14716
k_CONSANGLECPKMax_HwDeg_f32	392.140503
k_CONSANGLECPKMin_HwDeg_f32	-439.830811
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	55409
k_CONSANGLECPKSigValidThresh_Cnt_u16	15168
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	9518
k_CPKVehicleSpeedValidThresh_Cnt_u16	46244
k_CityParkInputInvalidThresh_Cnt_u16	3787
k_CityParkInputValidThresh_Cnt_u16	38807
k_ComputerRazGCTSigValidThresh_Cnt_u16	24379
k_CptTemporelSigValidThresh_Cnt_u16	36198
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	7631
k_DMDFCTCPKSigValidThresh_Cnt_u16	16630

Name	Input Value
k_DMDFCTCPKValidCount_Cnt_u16	36002
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	6270
k_DMDRELAXECPKSigValidThresh_Cnt_u16	22524
k_DMDRelaxeConsistentThresh_Cnt_u16	50594
k_DateValidThresh_Cnt_u16	42259
k_DefaultVehSpd_Kph_f32	74.6964035
k_DiagMuxOnAbsentTimeout_mS_u16	46928
k_EMNodeTimeout_mS_u16	63061
k_ESPNTCEnableTimeout_mS_u16	47012
k_ESPNodeAbsentDiag_Cnt_str.Threshold	42167
k_ESPNodeAbsentDiag_Cnt_str.PStep	4638
k_ESPNodeAbsentDiag_Cnt_str.NStep	10136
k_ESPNodeAbsentTimeout_mS_u16	37380
k_EtatMTSigInvalidThresh_Cnt_u16	31708
k_EtatMTSigValidThresh_Cnt_u16	32059
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	13537
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	18788
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	20296
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	49482
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	44213
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	49045
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	1708
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	6431
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	27355
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	20446
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	50521
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	3953
k_ISDATDIRASentDiag_Cnt_str.Threshold	14684
k_ISDATDIRASentDiag_Cnt_str.PStep	50013
k_ISDATDIRASentDiag_Cnt_str.NStep	57460
k_ISDATDIRASentTimeout_mS_u16	60129
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	11166
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	41511
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	2288
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	19877
k_ISDYNAASChkSumValidThresh_Cnt_u16	17348
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	99
k_ISDYNAASMsgCountValidThresh_Cnt_u16	65242
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	17769
k_ISDYNAASMsgLenValidThresh_Cnt_u16	57420
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	64093
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	34157
k_ISDYNABRChkSumValidThresh_Cnt_u16	49940
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	52762
k_ISDYNABRMsgCountValidThresh_Cnt_u16	8305
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	55891
k_ISDYNABRMsgLenValidThresh_Cnt_u16	11270
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	48904
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	56285
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	39618
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	50591
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	17739
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	19042
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	53867
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	38940
k_ISDYNVOLChkSumValidThresh_Cnt_u16	2231
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	50683
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	18056
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	37470
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	4609
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	39337
k_IgnOnTimeout_mS_u16	13400
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	184.526993
k_PowerCutVehSpdLowThresh_Kph_f32	56.9098015
k_PowerCutVehSpdLowTimeout_mS_u16	18157
k_VBattMaxAAS_Volt_f32	0.771799982
k_VBattMaxBSI_Volt_f32	27.2411003
k_VBattMaxCAV_Volt_f32	24.5928993
k_VBattMaxCMM388_Volt_f32	21.0305996
k_VBattMaxCMM_Volt_f32	16.5443001
k_VBattMaxESP_Volt_f32	27.2411003
k_VBattMinAAS_Volt_f32	1.42390001

Name	Input Value
k_VBattMinBSI_Volt_f32	2.35439992
k_VBattMinCAV_Volt_f32	19.4461994
k_VBattMinCMM388_Volt_f32	4.6651001
k_VBattMinCMM_Volt_f32	26.7273998
k_VBattMinESP_Volt_f32	16.5443001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	43768
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	29763
k_VitesseVehicleBVRampValidThresh_Cnt_u16	22477
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	22533
k_VitesseVehicleBVSigValidThresh_Cnt_u16	27840
k_VitesseVehicleBVSpeedPassThresh_kph_f32	644.154602
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	30312
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	56599
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1687017472
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	177
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	18459
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3182075392
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	172
target_SrlComInput_Per1_Batt_Volt_f32.value	6.15380001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2005354496
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	138
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.927294552
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	28
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2682976256
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1128339456
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	116
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	132593664
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	903698432
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	354646016
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3988363264
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	127907840
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	81
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	119
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	214
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	223
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2112772096
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	69
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	152
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	164
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	183
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	197
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1759377408
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	34

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1538529280
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	189
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	802830336
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3399141376
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3076
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.763034463
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	210375
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	34.8837013
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	39411

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3182075392	3182075392	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3182075392	3182075392	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3182075392	3182075392	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-381.109497	-381.109497	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4256389120	4256389120	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	1687017472	1687017472	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	1526319104	1526319104	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	1738752	1738752	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3182075392	3182075392	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3182075392	3182075392	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	38814	38814	✔
CAVNodeAbsentTimer_mS_M_u32	3182075392	3182075392	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3182075392	3182075392	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3182075392	3182075392	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3182075392	3182075392	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	49594	49594	✔
CONSANGLECPK_HwDeg_M_f32	610.967529	610.967529 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3182075392	3182075392	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3182075392	3182075392	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3182075392	3182075392	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3182075392	3182075392	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3182075392	3182075392	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3182075392	3182075392	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3182075392	3182075392	✔
ESPNTCEnableTimer_mS_M_u32	3182075392	3182075392	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	42167	42167	✔
ESPNodeAbsentTimer_mS_M_u32	3182075392	3182075392	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	8976	8976	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3182075392	3182075392	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3182075392	3182075392	✔
ElecIntTimer_mS_M_u32[1]	978	978	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3182075392	3182075392	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2682976256	2682976256	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3182075392	3182075392	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	132593664	132593664	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	903698432	903698432	✔
ISDATDIRASentFltAcc_Cnt_M_u16	14684	14684	✔
ISDATDIRASentTimer_mS_M_u32	3182075392	3182075392	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3182075392	3182075392	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3182075392	3182075392	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3182075392	3182075392	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3182075392	3182075392	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3182075392	3182075392	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3182075392	3182075392	✔
IgnOnTimer_mS_M_u32	3182075392	3182075392	✔
IgnTimeOff_Sec_M_u32	402140977	402140977	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	28	28	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2682976256	2682976256	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	137	137	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1128339456	1128339456	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	116	116	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	132593664	132593664	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	37	37	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	903698432	903698432	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3619960832	3619960832	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	245	245	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3988363264	3988363264	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	166	166	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	127907840	127907840	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	8	8	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2112772096	2112772096	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	197	197	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1759377408	1759377408	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	34	34	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1538529280	1538529280	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	189	189	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	802830336	802830336	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3399141376	3399141376	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	477.034485	477.034485	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	503.912109	503.912109	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	625.16687	625.16687	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-381.109497	-381.109497	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	49594	49594	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	402140977	402140977	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	610.967529	610.967529 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	74.6964035	74.6964035	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0139	0x0139	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0161	0x0161	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	10	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	10	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.75 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1199459072
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	9126
AASNodeAbsentTimer_mS_M_u32	1212283648
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	62301
ANGLEVOLANTSigValidCount_Cnt_M_u16	60376
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	28103
AngleVolantMsgTimer_mS_M_u32	1199459072
AngleVolantValidCount_Cnt_M_u16	43587

Name	Input Value
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-578.619019
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1709488896
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3142925056
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3016846080
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	930032384
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	21744
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	4061391616
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	15493
CAVNodeAbsentTimer_mS_M_u32	1882790656
CDD_SrlComVehSpd_Kph_G_f32	17.1616993
CMM388NTCEnableTimer_mS_M_u32	2744277760
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3561429760
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	47492
CMMNodeAbsentTimer_mS_M_u32	2078354176
CONSANGLECPKSigInvalidCount_Cnt_M_u16	37436
CONSANGLECPKSigValidCount_Cnt_M_u16	38983
CONSANGLECPK_Cnt_M_u16	38862
CONSANGLECPK_HwDeg_M_f32	19.7066002
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	38862
CPKVehicleSpeedMsgTimer_mS_M_u32	279530240
CPKVehicleSpeedValidCount_Cnt_M_u16	18631
CityParkInputConsistentCount_Cnt_M_u16	62967
CityParkInputInvalidCount_Cnt_M_u16	58085
CityParkInputMsgTimer_mS_M_u32	2682976256
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2163604224
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	48474
ComputerRazGCTSigInvalidTimer_mS_M_u32	2378406656
ComputerRazGCTSigValidCount_Cnt_M_u16	30512
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	41777
DMDFCTCPKSigValidCount_Cnt_M_u16	5172
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	15415
DMDRELAXECPKSigValidCount_Cnt_M_u16	1074
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	35165
DateInvalidTimer_mS_M_u32	3142925056
DiagMuxOnAbsentTimer_mS_M_u32	444795648
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	930032384
ESPNTCEnableTimer_mS_M_u32	567737088
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	15403
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	5
EffacDefaultDiagTimer_mS_M_u32[1]	55
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	7
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2764958464
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	63766
EtatMTSigValidCount_Cnt_M_u16	4333
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	59670
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	16033
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	14914
ISDAT4V2BSI552MsgTimer_mS_M_u32	2476026624
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	38495

Name	Input Value
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	27934
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	4333
ISDATBSI3F2MsgTimer_mS_M_u32	3148417792
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	45962
ISDATBSI412MsgLenValidCount_Cnt_M_u16	20537
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	63766
ISDATBSI412MsgTimer_mS_M_u32	3869526784
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	61496
ISDATBSI432MsgLenValidCount_Cnt_M_u16	53727
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	954
ISDATDIRASentFltAcc_Cnt_M_u16	5822
ISDATDIRASentTimer_mS_M_u32	279530240
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	59764
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	43587
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	56388
ISDYN2CMMMsgTimer_mS_M_u32	1825110784
ISDYNAASChkSumInvalidCount_Cnt_M_u16	26752
ISDYNAASChkSumValidCount_Cnt_M_u16	23707
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	57686
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	34124
ISDYNAASMsgLenValidCount_Cnt_M_u16	36928
ISDYNAASMsgTimeValidCount_Cnt_M_u16	26752
ISDYNAASMsgTimer_mS_M_u32	1289640704
ISDYNABRChkSumInvalidCount_Cnt_M_u16	15310
ISDYNABRChkSumValidCount_Cnt_M_u16	33073
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	50195
ISDYNABRMsgCountValidCount_Cnt_M_u16	20590
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	27855
ISDYNABRMsgLenValidCount_Cnt_M_u16	19226
ISDYNABRMsgTimeValidCount_Cnt_M_u16	38862
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	649
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1183
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	4333
ISDYNCMM208MsgTimer_mS_M_u32	3764239104
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2447
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1289
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	7273
ISDYNCMM388MsgTimer_mS_M_u32	3330792192
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	19298
ISDYNVOLChkSumValidCount_Cnt_M_u16	493
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	6999
ISDYNVOLMsgCountValidCount_Cnt_M_u16	31962
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	23448
ISDYNVOLMsgLenValidCount_Cnt_M_u16	17923
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	47492
ISDYNVOLMsgTimer_mS_M_u32	1393531648
IgnOnTimer_mS_M_u32	356244224
IgnTimeOff_Sec_M_u32	1266351964
ManVehSpd_Kph_M_f32	382.183594
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	119
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	89
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2031553280
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	67
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2479123200
PrevISDATBSI412MsgDLCError_Cnt_M_u08	168
PrevISDATBSI412MsgRxTime_MSec_M_u32	2771262208
PrevISDATBSI432MsgDLCError_Cnt_M_u08	218
PrevISDATBSI432MsgRxTime_MSec_M_u32	112917248
PrevISDATDIRAMsgTxTime_MSec_M_u32	3006405376
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	254
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1571990272
PrevISDYNAASMsgDLCError_Cnt_M_u08	250

Name	Input Value
PrevISDYNAASMsgRxTime_MSec_M_u32	2360711936
PrevISDYNABRMsgDLCError_Cnt_M_u08	118
PrevISDYNABRMsgRxTime_MSec_M_u32	4141079296
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	93
PrevISDYNCMM208MsgRxTime_MSec_M_u32	581868288
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	106
PrevISDYNCMM388MsgRxTime_MSec_M_u32	121764608
PrevISDYNVOLMsgDLCError_Cnt_M_u08	57
PrevISDYNVOLMsgRxTime_MSec_M_u32	2917079808
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	348801792
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	154.611893
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	64370
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	30438
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	48735
VitesseVehicleBVRampValidCount_Cnt_M_u16	33171
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	38346
VitesseVehicleBVSigValidCount_Cnt_M_u16	30213
VitesseVehicleBV_Kph_M_f32	481.627686
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	7273
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	56252
VitesseVehiculeRoues_Kph_M_f32	49.9217987
k_AASNTCEnableTimeout_mS_u16	50233
k_AASNodeAbsentDiag_Cnt_str.Threshold	56423
k_AASNodeAbsentDiag_Cnt_str.PStep	54467
k_AASNodeAbsentDiag_Cnt_str.NStep	11476
k_AASNodeAbsentTimeout_mS_u16	58530
k_AASNodeTimeout_mS_u16	46566
k_ABSNodeTimeout_mS_u16	23658
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	13527
k_ANGLEVOLANTSigValidThresh_Cnt_u16	40894
k_AngleVolantInvalidThresh_Cnt_u16	13497
k_AngleVolantValidThresh_Cnt_u16	58085
k_BSI552MsgTimeout_mS_u16	2167
k_BSINTCEnableTimeout_mS_u16	464
k_BSINodeAbsentDiag_Cnt_str.Threshold	23372
k_BSINodeAbsentDiag_Cnt_str.PStep	35607
k_BSINodeAbsentDiag_Cnt_str.NStep	13532
k_BSINodeAbsentTimeout_mS_u16	55647
k_BSINodeTimeout_mS_u16	954
k_BattOvHi_Volt_f32	9.91989994
k_BattOvLo_Volt_f32	23.9335003
k_BattUvHi_Volt_f32	3.34890008
k_BattUvLo_Volt_f32	31.3892002
k_CAVNTCEnableTimeout_mS_u16	15011
k_CAVNodeAbsentDiag_Cnt_str.Threshold	64930
k_CAVNodeAbsentDiag_Cnt_str.PStep	61764
k_CAVNodeAbsentDiag_Cnt_str.NStep	55165
k_CAVNodeAbsentTimeout_mS_u16	51627
k_CAVNodeTimeout_mS_u16	37768
k_CMM388MsgTimeout_mS_u16	41638
k_CMM388NTCEnableTimeout_mS_u16	18674
k_CMMNTCEnableTimeout_mS_u16	13303
k_CMMNodeAbsentDiag_Cnt_str.Threshold	23467
k_CMMNodeAbsentDiag_Cnt_str.PStep	835
k_CMMNodeAbsentDiag_Cnt_str.NStep	65006
k_CMMNodeAbsentTimeout_mS_u16	4104
k_CONSANGLECPKMax_HwDeg_f32	666.998413

Name	Input Value
k_CONSANGLECPKMin_HwDeg_f32	-128.694199
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	7017
k_CONSANGLECPKSigValidThresh_Cnt_u16	6844
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	62196
k_CPKVehicleSpeedValidThresh_Cnt_u16	17681
k_CityParkInputInvalidThresh_Cnt_u16	3932
k_CityParkInputValidThresh_Cnt_u16	62967
k_ComputerRazGCTSigValidThresh_Cnt_u16	4173
k_CptTemporelSigValidThresh_Cnt_u16	7564
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	60367
k_DMDFCTCPKSigValidThresh_Cnt_u16	2586
k_DMDFCTCPKValidCount_Cnt_u16	47192
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	56388
k_DMDRELAXECPKSigValidThresh_Cnt_u16	1415
k_DMDRelaxeConsistentThresh_Cnt_u16	54421
k_DateValidThresh_Cnt_u16	14914
k_DefaultVehSpd_Kph_f32	102.655899
k_DiagMuxOnAbsentTimeout_mS_u16	36620
k_EMNodeTimeout_mS_u16	64061
k_ESPNTCEnableTimeout_mS_u16	26577
k_ESPNodeAbsentDiag_Cnt_str.Threshold	42784
k_ESPNodeAbsentDiag_Cnt_str.PStep	30786
k_ESPNodeAbsentDiag_Cnt_str.NStep	15981
k_ESPNodeAbsentTimeout_mS_u16	9840
k_EtatMTSigInvalidThresh_Cnt_u16	19497
k_EtatMTSigValidThresh_Cnt_u16	45004
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	20443
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	2578
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	53988
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	58912
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	48031
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	10302
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	6009
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	38880
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	26348
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	32098
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	62641
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	63913
k_ISDATDIRASentDiag_Cnt_str.Threshold	14568
k_ISDATDIRASentDiag_Cnt_str.PStep	52861
k_ISDATDIRASentDiag_Cnt_str.NStep	1552
k_ISDATDIRASentTimeout_mS_u16	21274
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	39202
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	28103
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	41965
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	15054
k_ISDYNAASChkSumValidThresh_Cnt_u16	49201
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	17171
k_ISDYNAASMsgCountValidThresh_Cnt_u16	3950
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	25474
k_ISDYNAASMsgLenValidThresh_Cnt_u16	47514
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	27686
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	44277
k_ISDYNABRChkSumValidThresh_Cnt_u16	31680
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	54256
k_ISDYNABRMsgCountValidThresh_Cnt_u16	9387
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	63620
k_ISDYNABRMsgLenValidThresh_Cnt_u16	47915
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	25830
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	7974
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	35511
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	5537
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	29277
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	43736
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	41597
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	31401
k_ISDYNVOLChkSumValidThresh_Cnt_u16	32920
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	332
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	51173
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	3426
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	1593
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	13440
k_IgnOnTimeout_mS_u16	38389

Name	Input Value
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	183.6642
k_PowerCutVehSpdLowThresh_Kph_f32	62.5158005
k_PowerCutVehSpdLowTimeout_mS_u16	37941
k_VBattMaxAAS_Volt_f32	16.3430996
k_VBattMaxBSI_Volt_f32	27.2411003
k_VBattMaxCAV_Volt_f32	24.3827991
k_VBattMaxCMM388_Volt_f32	1.87619996
k_VBattMaxCMM_Volt_f32	18.1389008
k_VBattMaxESP_Volt_f32	24.3013992
k_VBattMinAAS_Volt_f32	19.5109997
k_VBattMinBSI_Volt_f32	3.25629997
k_VBattMinCAV_Volt_f32	14.0094995
k_VBattMinCMM388_Volt_f32	21.0345001
k_VBattMinCMM_Volt_f32	17.4636993
k_VBattMinESP_Volt_f32	18.1389008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	788
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	48884
k_VitesseVehicleBVRampValidThresh_Cnt_u16	6743
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	49389
k_VitesseVehicleBVSigValidThresh_Cnt_u16	23164
k_VitesseVehicleBVSpeedPassThresh_kph_f32	515.338623
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	15237
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	44857
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3142925056
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	235
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	55836
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	43444480
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	106
target_SrlComInput_Per1_Batt_Volt_f32.value	24.7567005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1948838656
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	226
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.940737307
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1706941184
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	191
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4231756544
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1858673408
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	111
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3848715008
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2283035392
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2127690496
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4053768960
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	20
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	41
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	64
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	91
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2436086528

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	48
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	49
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	122
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	167
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	193
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	184
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2531580672
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1055030016
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2196773632
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	77
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	101
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	686713600
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	91
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.125774071
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	257295
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	201.844193
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	48356

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	43444480	43444480	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	56423	56423	✔
AASNodeAbsentTimer_mS_M_u32	43444480	43444480	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	28103	28103	✔
AngleVolantMsgTimer_mS_M_u32	43444480	43444480	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-578.619019	-578.619019	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1709488896	1709488896	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	43444480	43444480	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3016846080	3016846080	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	930032384	930032384	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	43444480	43444480	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	43444480	43444480	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	64930	64930	✔
CAVNodeAbsentTimer_mS_M_u32	43444480	43444480	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	43444480	43444480	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	43444480	43444480	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2127690496	2127690496	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	38862	38862	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CONSANGLECPK_HwDeg_M_f32	19.7066002	19.7066002 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	38862	38862	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	279530240	279530240	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	18631	18631	✔
CityParkInputConsistentCount_Cnt_M_u16	62967	62967	✔
CityParkInputInvalidCount_Cnt_M_u16	58085	58085	✔
CityParkInputMsgTimer_mS_M_u32	43444480	43444480	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	43444480	43444480	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	43444480	43444480	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3142925056	3142925056	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	43444480	43444480	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	930032384	930032384	✔
ESPNTCEnableTimer_mS_M_u32	43444480	43444480	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	43444480	43444480	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	5	5	✔
EffacDefaultDiagTimer_mS_M_u32[1]	55	55	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4	4	✔
ElecIntTimer_mS_M_u32[1]	7	7	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	43444480	43444480	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	59670	59670	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1706941184	1706941184	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	38496	38496	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4231756544	4231756544	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	43444480	43444480	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	61496	61496	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3848715008	3848715008	✔
ISDATDIRASentFltAcc_Cnt_M_u16	14568	14568	✔
ISDATDIRASentTimer_mS_M_u32	43444480	43444480	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	43444480	43444480	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASMsgTimer_mS_M_u32	43444480	43444480	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	43444480	43444480	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	43444480	43444480	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	43444480	43444480	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	43444480	43444480	✔
IgnOnTimer_mS_M_u32	356244224	356244224	✔
IgnTimeOff_Sec_M_u32	1266351964	1266351964	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1706941184	1706941184	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	191	191	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4231756544	4231756544	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	31	31	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1858673408	1858673408	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	111	111	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3848715008	3848715008	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3006405376	3006405376	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	126	126	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2127690496	2127690496	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	142	142	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4053768960	4053768960	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	74	74	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2436086528	2436086528	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	184	184	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2531580672	2531580672	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	129	129	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1055030016	1055030016	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	210	210	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2196773632	2196773632	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	686713600	686713600	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	154.611893	154.611893	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	481.627686	481.627686	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	49.9217987	49.9217987	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-578.619019	-578.619019	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	38862	38862	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1266351964	1266351964	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	19.7066002	19.7066002 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	102.655899	102.655899	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.76 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2551177728
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	17814

Name	Input Value
AASNodeAbsentTimer_mS_M_u32	2156188160
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	53362
ANGLEVOLANTSigValidCount_Cnt_M_u16	4033
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	11059
AngleVolantMsgTimer_mS_M_u32	2551177728
AngleVolantValidCount_Cnt_M_u16	27712
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-592.697021
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	580686336
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2219512320
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	127304192
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	599605760
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	47033
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1993277952
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	57209
CAVNodeAbsentTimer_mS_M_u32	1293906432
CDD_SrlComVehSpd_Kph_G_f32	30.0242996
CMM388NTCEnableTimer_mS_M_u32	2819863040
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3639964160
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	44605
CMMNodeAbsentTimer_mS_M_u32	2657567232
CONSANGLECPKSigInvalidCount_Cnt_M_u16	57046
CONSANGLECPKSigValidCount_Cnt_M_u16	13685
CONSANGLECPK_Cnt_M_u16	4832
CONSANGLECPK_HwDeg_M_f32	-235.219803
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	4832
CPKVehicleSpeedMsgTimer_mS_M_u32	2827936256
CPKVehicleSpeedValidCount_Cnt_M_u16	28540
CityParkInputConsistentCount_Cnt_M_u16	22820
CityParkInputInvalidCount_Cnt_M_u16	7001
CityParkInputMsgTimer_mS_M_u32	1706941184
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2791887360
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	18554
ComputerRazGCTSigInvalidTimer_mS_M_u32	1048572416
ComputerRazGCTSigValidCount_Cnt_M_u16	63865
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	2677
DMDFCTCPKSigValidCount_Cnt_M_u16	44
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56804
DMDRELAXECPKSigValidCount_Cnt_M_u16	44723
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	48499
DateInvalidTimer_mS_M_u32	2219512320
DiagMuxOnAbsentTimer_mS_M_u32	570532352
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	599605760
ESPNTCEnableTimer_mS_M_u32	2277888512
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	65288
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	97
EffacDefaultDiagTimer_mS_M_u32[1]	977
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	20
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3332440576
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0

Name	Input Value
EtatMTSigInvalidCount_Cnt_M_u16	2182
EtatMTSigValidCount_Cnt_M_u16	22977
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	49736
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	10855
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	17922
ISDAT4V2BSI552MsgTimer_mS_M_u32	659243520
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	60460
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	41134
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	22977
ISDATBSI3F2MsgTimer_mS_M_u32	1452253696
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	20906
ISDATBSI412MsgLenValidCount_Cnt_M_u16	29789
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	2182
ISDATBSI412MsgTimer_mS_M_u32	3533562368
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	55841
ISDATBSI432MsgLenValidCount_Cnt_M_u16	3564
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	40410
ISDATDIRASentFltAcc_Cnt_M_u16	29902
ISDATDIRASentTimer_mS_M_u32	2827936256
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	13806
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	27712
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	27452
ISDYN2CMMMsgTimer_mS_M_u32	4008694272
ISDYNAASChkSumInvalidCount_Cnt_M_u16	24328
ISDYNAASChkSumValidCount_Cnt_M_u16	11126
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	54023
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	57636
ISDYNAASMsgLenValidCount_Cnt_M_u16	51466
ISDYNAASMsgTimeValidCount_Cnt_M_u16	24328
ISDYNAASMsgTimer_mS_M_u32	3694113280
ISDYNABRChkSumInvalidCount_Cnt_M_u16	21152
ISDYNABRChkSumValidCount_Cnt_M_u16	19254
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	22607
ISDYNABRMsgCountValidCount_Cnt_M_u16	23549
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	23325
ISDYNABRMsgLenValidCount_Cnt_M_u16	10492
ISDYNABRMsgTimeValidCount_Cnt_M_u16	4832
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	650
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1185
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	22977
ISDYNCMM208MsgTimer_mS_M_u32	3610350080
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2451
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1291
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	11726
ISDYNCMM388MsgTimer_mS_M_u32	4113773056
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	52068
ISDYNVOLChkSumValidCount_Cnt_M_u16	4227
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	47619
ISDYNVOLMsgCountValidCount_Cnt_M_u16	56890
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	38081
ISDYNVOLMsgLenValidCount_Cnt_M_u16	48703
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	44605
ISDYNVOLMsgTimer_mS_M_u32	513536512
IgnOnTimer_mS_M_u32	3642176000
IgnTimeOff_Sec_M_u32	2932555328
ManVehSpd_Kph_M_f32	480.306
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	121
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	138
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1447404032
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	171
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4089283072
PrevISDATBSI412MsgDLCError_Cnt_M_u08	183

Name	Input Value
PrevISDATBSI412MsgRxTime_MSec_M_u32	3259003392
PrevISDATBSI432MsgDLCError_Cnt_M_u08	157
PrevISDATBSI432MsgRxTime_MSec_M_u32	1763299840
PrevISDATDIRAMsgTxTime_MSec_M_u32	2822009344
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	194
PrevISDYN2CMMMsgRxTime_MSec_M_u32	519225856
PrevISDYNAASMsgDLCError_Cnt_M_u08	153
PrevISDYNAASMsgRxTime_MSec_M_u32	2309616128
PrevISDYNABRMsgDLCError_Cnt_M_u08	254
PrevISDYNABRMsgRxTime_MSec_M_u32	2488218112
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	104
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3955159552
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	222
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1132777984
PrevISDYNVOLMsgDLCError_Cnt_M_u08	22
PrevISDYNVOLMsgRxTime_MSec_M_u32	2888659456
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1613488640
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	320.162506
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	38578
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	11544
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	16875
VitesseVehicleBVRampValidCount_Cnt_M_u16	273
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	56619
VitesseVehicleBVSigValidCount_Cnt_M_u16	25914
VitesseVehicleBV_Kph_M_f32	85.1892014
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	11726
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	30868
VitesseVehiculeRoues_Kph_M_f32	271.450989
k_AASNTCEnableTimeout_mS_u16	63903
k_AASNodeAbsentDiag_Cnt_str.Threshold	62204
k_AASNodeAbsentDiag_Cnt_str.PStep	10207
k_AASNodeAbsentDiag_Cnt_str.NStep	9700
k_AASNodeAbsentTimeout_mS_u16	63779
k_AASNodeTimeout_mS_u16	28696
k_ABSNodeTimeout_mS_u16	714
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	18500
k_ANGLEVOLANTSigValidThresh_Cnt_u16	57423
k_AngleVolantInvalidThresh_Cnt_u16	52574
k_AngleVolantValidThresh_Cnt_u16	7001
k_BSI552MsgTimeout_mS_u16	40547
k_BSINTCEnableTimeout_mS_u16	1369
k_BSINodeAbsentDiag_Cnt_str.Threshold	23412
k_BSINodeAbsentDiag_Cnt_str.PStep	35590
k_BSINodeAbsentDiag_Cnt_str.NStep	13555
k_BSINodeAbsentTimeout_mS_u16	18539
k_BSINodeTimeout_mS_u16	40410
k_BattOvHi_Volt_f32	5.63390017
k_BattOvLo_Volt_f32	23.2290993
k_BattUvHi_Volt_f32	8.90649986
k_BattUvLo_Volt_f32	13.2399998
k_CAVNTCEnableTimeout_mS_u16	35871
k_CAVNodeAbsentDiag_Cnt_str.Threshold	10978
k_CAVNodeAbsentDiag_Cnt_str.PStep	35125
k_CAVNodeAbsentDiag_Cnt_str.NStep	24067
k_CAVNodeAbsentTimeout_mS_u16	20487
k_CAVNodeTimeout_mS_u16	2802
k_CMM388MsgTimeout_mS_u16	51350

Name	Input Value
k_CMM388NTCEnableTimeout_mS_u16	1458
k_CMMNTCEnableTimeout_mS_u16	29540
k_CMMNodeAbsentDiag_Cnt_str.Threshold	63761
k_CMMNodeAbsentDiag_Cnt_str.PStep	24896
k_CMMNodeAbsentDiag_Cnt_str.NStep	45174
k_CMMNodeAbsentTimeout_mS_u16	2992
k_CONSANGLECPKMax_HwDeg_f32	624.330322
k_CONSANGLECPKMin_HwDeg_f32	-374.772614
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	12494
k_CONSANGLECPKSigValidThresh_Cnt_u16	48020
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	28910
k_CPKVehicleSpeedValidThresh_Cnt_u16	30997
k_CityParkInputInvalidThresh_Cnt_u16	36854
k_CityParkInputValidThresh_Cnt_u16	22820
k_ComputerRazGCTSigValidThresh_Cnt_u16	46690
k_CptTemporelSigValidThresh_Cnt_u16	51044
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	56861
k_DMDFCTCPKSigValidThresh_Cnt_u16	60412
k_DMDFCTCPKValidCount_Cnt_u16	11649
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	27452
k_DMDRELAXECPKSigValidThresh_Cnt_u16	14387
k_DMDRelaxeConsistentThresh_Cnt_u16	33545
k_DateValidThresh_Cnt_u16	17922
k_DefaultVehSpd_Kph_f32	105.074203
k_DiagMuxOnAbsentTimeout_mS_u16	42278
k_EMNodeTimeout_mS_u16	60115
k_ESPNTCEnableTimeout_mS_u16	36245
k_ESPNodeAbsentDiag_Cnt_str.Threshold	56336
k_ESPNodeAbsentDiag_Cnt_str.PStep	31907
k_ESPNodeAbsentDiag_Cnt_str.NStep	30299
k_ESPNodeAbsentTimeout_mS_u16	26744
k_EtatMTSigInvalidThresh_Cnt_u16	19855
k_EtatMTSigValidThresh_Cnt_u16	60261
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	46649
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	41043
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	46685
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	16617
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	63787
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	50062
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	43102
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	65513
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	17925
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	45604
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	50422
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	3148
k_ISDATDIRASentDiag_Cnt_str.Threshold	6034
k_ISDATDIRASentDiag_Cnt_str.PStep	7179
k_ISDATDIRASentDiag_Cnt_str.NStep	10440
k_ISDATDIRASentTimeout_mS_u16	15548
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	20961
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	11059
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	18753
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	21920
k_ISDYNAASChkSumValidThresh_Cnt_u16	36406
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	56143
k_ISDYNAASMsgCountValidThresh_Cnt_u16	7933
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	43908
k_ISDYNAASMsgLenValidThresh_Cnt_u16	13564
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	6935
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	45739
k_ISDYNABRChkSumValidThresh_Cnt_u16	44810
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	15033
k_ISDYNABRMsgCountValidThresh_Cnt_u16	29000
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	61757
k_ISDYNABRMsgLenValidThresh_Cnt_u16	33288
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	23703
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	64406
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	49187
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	64743
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	21362
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	53953
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	15505
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	14413

Name	Input Value
k_ISDYNVOLChkSumValidThresh_Cnt_u16	8000
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	29605
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	18202
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	64418
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	43485
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	53064
k_IgnOnTimeout_mS_u16	5737
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	166.549301
k_PowerCutVehSpdLowThresh_Kph_f32	249.994705
k_PowerCutVehSpdLowTimeout_mS_u16	31147
k_VBattMaxAAS_Volt_f32	8.59720039
k_VBattMaxBSI_Volt_f32	23.0923996
k_VBattMaxCAV_Volt_f32	9.96920013
k_VBattMaxCMM388_Volt_f32	12.0692997
k_VBattMaxCMM_Volt_f32	20.8701
k_VBattMaxESP_Volt_f32	19.6236992
k_VBattMinAAS_Volt_f32	16.7215004
k_VBattMinBSI_Volt_f32	19.6236992
k_VBattMinCAV_Volt_f32	19.5296001
k_VBattMinCMM388_Volt_f32	11.4097996
k_VBattMinCMM_Volt_f32	32
k_VBattMinESP_Volt_f32	20.8701
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	23563
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	57646
k_VitesseVehicleBVRampValidThresh_Cnt_u16	48387
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	54147
k_VitesseVehicleBVSigValidThresh_Cnt_u16	32661
k_VitesseVehicleBVSpeedPassThresh_kph_f32	589.760681
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	57977
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	36895
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2219512320
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	159
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	21
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	381552640
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	222
target_SrlComInput_Per1_Batt_Volt_f32.value	2.23519993
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2224030208
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	65
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.257314444
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	127
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1871786496
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	24
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	714625536
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2440000000
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	739676672
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2190324224
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	214
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	483709440
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2196500992
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	8

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	118
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	130
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2628751872
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	97
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	107
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	202
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	220
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	232
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	941371904
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3198374400
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	217
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2969203200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	45
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	166
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	167
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1547665920
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2028
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0997405574
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1032582
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	124.259598
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	39516

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	381552640	381552640	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	381552640	381552640	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	11061	11061	✔
AngleVolantMsgTimer_mS_M_u32	381552640	381552640	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-592.697021	-592.697021	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	381552640	381552640	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	381552640	381552640	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	381552640	381552640	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	381552640	381552640	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	381552640	381552640	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	381552640	381552640	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	10978	10978	✔
CAVNodeAbsentTimer_mS_M_u32	381552640	381552640	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	381552640	381552640	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CMMNTCEnableTimer_mS_M_u32	381552640	381552640	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	381552640	381552640	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	4832	4832	✔
CONSANGLECPK_HwDeg_M_f32	-235.219803	-235.219803 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	4832	4832	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2827936256	2827936256	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	28540	28540	✔
CityParkInputConsistentCount_Cnt_M_u16	22820	22820	✔
CityParkInputInvalidCount_Cnt_M_u16	7002	7002	✔
CityParkInputMsgTimer_mS_M_u32	2196500992	2196500992	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	381552640	381552640	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	381552640	381552640	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	381552640	381552640	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	381552640	381552640	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	381552640	381552640	✔
ESPNTCEnableTimer_mS_M_u32	381552640	381552640	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	56336	56336	✔
ESPNodeAbsentTimer_mS_M_u32	381552640	381552640	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	381552640	381552640	✔
EffacDefaultDiagTimer_mS_M_u32[1]	977	977	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	381552640	381552640	✔
ElecIntTimer_mS_M_u32[1]	20	20	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3332440576	3332440576	✔
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	381552640	381552640	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	381552640	381552640	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	381552640	381552640	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	381552640	381552640	✔
ISDATDIRASentFltAcc_Cnt_M_u16	6034	6034	✔
ISDATDIRASentTimer_mS_M_u32	381552640	381552640	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	381552640	381552640	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	381552640	381552640	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	381552640	381552640	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	381552640	381552640	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	381552640	381552640	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	381552640	381552640	✔
IgnOnTimer_mS_M_u32	381552640	381552640	✔
IgnTimeOff_Sec_M_u32	2932555328	2932555328	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	15	15	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	127	127	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1871786496	1871786496	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	24	24	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	714625536	714625536	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	152	152	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2440000000	2440000000	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	135	135	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	739676672	739676672	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2822009344	2822009344	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	214	214	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	483709440	483709440	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2196500992	2196500992	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	105	105	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2628751872	2628751872	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	941371904	941371904	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	46	46	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3198374400	3198374400	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	217	217	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2969203200	2969203200	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1547665920	1547665920	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	320.162506	320.162506	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	85.1892014	85.1892014	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	271.450989	271.450989	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-592.697021	-592.697021	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	4832	4832	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2932555328	2932555328	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-235.219803	-235.219803 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.77 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2373393664
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	48867
AASNodeAbsentTimer_mS_M_u32	332942592
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	12366
ANGLEVOLANTSigValidCount_Cnt_M_u16	63522
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	49676
AngleVolantMsgTimer_mS_M_u32	2373393664

Name	Input Value
AngleVolantValidCount_Cnt_M_u16	7013
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-180.787766
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1016139008
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4052061440
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	560151808
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3622763776
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	22137
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1438235904
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	17339
CAVNodeAbsentTimer_mS_M_u32	3767037184
CDD_SrlComVehSpd_Kph_G_f32	78.887001
CMM388NTCEnableTimer_mS_M_u32	4037782784
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	352742656
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	1581
CMMNodeAbsentTimer_mS_M_u32	2414935296
CONSANGLECPKSigInvalidCount_Cnt_M_u16	17442
CONSANGLECPKSigValidCount_Cnt_M_u16	1543
CONSANGLECPK_Cnt_M_u16	55750
CONSANGLECPK_HwDeg_M_f32	664.374573
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	55750
CPKVehicleSpeedMsgTimer_mS_M_u32	402267392
CPKVehicleSpeedValidCount_Cnt_M_u16	38233
CityParkInputConsistentCount_Cnt_M_u16	58553
CityParkInputInvalidCount_Cnt_M_u16	793
CityParkInputMsgTimer_mS_M_u32	1871786496
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	841764096
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	17975
ComputerRazGCTSigInvalidTimer_mS_M_u32	778497280
ComputerRazGCTSigValidCount_Cnt_M_u16	38842
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	42437
DMDFCTCPKSigValidCount_Cnt_M_u16	60002
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	20472
DMDRELAXECPKSigValidCount_Cnt_M_u16	25420
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	23627
DateInvalidTimer_mS_M_u32	4052061440
DiagMuxOnAbsentTimer_mS_M_u32	3869367552
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3622763776
ESPNTCEnableTimer_mS_M_u32	1108692224
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	35214
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	4
EffacDefaultDiagTimer_mS_M_u32[1]	3783568128
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	555
ElecIntTimer_mS_M_u32[1]	5556
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	776191232
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	44113
EtatMTSigValidCount_Cnt_M_u16	61026
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	57804
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	28465
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	61664
ISDAT4V2BSI552MsgTimer_mS_M_u32	2235890944

Name	Input Value
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	52961
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	1818
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	61026
ISDATBSI3F2MsgTimer_mS_M_u32	16243968
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	26471
ISDATBSI412MsgLenValidCount_Cnt_M_u16	5391
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	44113
ISDATBSI412MsgTimer_mS_M_u32	2513247488
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	4737
ISDATBSI432MsgLenValidCount_Cnt_M_u16	60642
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	52376
ISDATDIRASentFltAcc_Cnt_M_u16	6076
ISDATDIRASentTimer_mS_M_u32	402267392
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	10396
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	7013
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	24432
ISDYN2CMMMsgTimer_mS_M_u32	882330880
ISDYNAASChkSumInvalidCount_Cnt_M_u16	47757
ISDYNAASChkSumValidCount_Cnt_M_u16	23298
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	49936
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	43706
ISDYNAASMsgLenValidCount_Cnt_M_u16	55495
ISDYNAASMsgTimeValidCount_Cnt_M_u16	47757
ISDYNAASMsgTimer_mS_M_u32	3294080256
ISDYNABRChkSumInvalidCount_Cnt_M_u16	38725
ISDYNABRChkSumValidCount_Cnt_M_u16	21314
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	43704
ISDYNABRMsgCountValidCount_Cnt_M_u16	42349
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	43853
ISDYNABRMsgLenValidCount_Cnt_M_u16	1906
ISDYNABRMsgTimeValidCount_Cnt_M_u16	55750
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	651
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1187
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	61026
ISDYNCMM208MsgTimer_mS_M_u32	3000110336
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2455
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1293
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	36539
ISDYNCMM388MsgTimer_mS_M_u32	3880594688
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	13944
ISDYNVOLChkSumValidCount_Cnt_M_u16	11485
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	20251
ISDYNVOLMsgCountValidCount_Cnt_M_u16	2104
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	60515
ISDYNVOLMsgLenValidCount_Cnt_M_u16	46504
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	1581
ISDYNVOLMsgTimer_mS_M_u32	4262653184
IgnOnTimer_mS_M_u32	3416337664
IgnTimeOff_Sec_M_u32	1680329261
ManVehSpd_Kph_M_f32	655.340027
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	123
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	61
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1507187968
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	64
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3102620928
PrevISDATBSI412MsgDLCError_Cnt_M_u08	106
PrevISDATBSI412MsgRxTime_MSec_M_u32	1160080640
PrevISDATBSI432MsgDLCError_Cnt_M_u08	68
PrevISDATBSI432MsgRxTime_MSec_M_u32	3994635520
PrevISDATDIRAMsgTxTime_MSec_M_u32	1665756416
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	33
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2622389504

Name	Input Value
PrevISDYNAASMsgDLCError_Cnt_M_u08	57
PrevISDYNAASMsgRxTime_MSec_M_u32	1961422080
PrevISDYNABRMsgDLCError_Cnt_M_u08	132
PrevISDYNABRMsgRxTime_MSec_M_u32	2046373120
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	229
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3802787072
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	170
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3403173120
PrevISDYNVOLMsgDLCError_Cnt_M_u08	23
PrevISDYNVOLMsgRxTime_MSec_M_u32	2069785856
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2770541824
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	382.705688
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	16912
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	25757
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	25701
VitesseVehicleBVRampValidCount_Cnt_M_u16	3250
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	11811
VitesseVehicleBVSigValidCount_Cnt_M_u16	7095
VitesseVehicleBV_Kph_M_f32	162.083801
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	36539
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	5159
VitesseVehiculeRoues_Kph_M_f32	304.505188
k_AASNTCEnableTimeout_mS_u16	57737
k_AASNodeAbsentDiag_Cnt_str.Threshold	53178
k_AASNodeAbsentDiag_Cnt_str.PStep	46887
k_AASNodeAbsentDiag_Cnt_str.NStep	35442
k_AASNodeAbsentTimeout_mS_u16	49340
k_AASNodeTimeout_mS_u16	39837
k_ABSNodeTimeout_mS_u16	20678
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	5144
k_ANGLEVOLANTSigValidThresh_Cnt_u16	49593
k_AngleVolantInvalidThresh_Cnt_u16	63116
k_AngleVolantValidThresh_Cnt_u16	793
k_BSI552MsgTimeout_mS_u16	40634
k_BSINTCEnableTimeout_mS_u16	28889
k_BSINodeAbsentDiag_Cnt_str.Threshold	23452
k_BSINodeAbsentDiag_Cnt_str.PStep	35573
k_BSINodeAbsentDiag_Cnt_str.NStep	13578
k_BSINodeAbsentTimeout_mS_u16	19044
k_BSINodeTimeout_mS_u16	52376
k_BattOvHi_Volt_f32	27.3924999
k_BattOvLo_Volt_f32	23.198
k_BattUvHi_Volt_f32	1.89600003
k_BattUvLo_Volt_f32	16.0317993
k_CAVNTCEnableTimeout_mS_u16	18631
k_CAVNodeAbsentDiag_Cnt_str.Threshold	46397
k_CAVNodeAbsentDiag_Cnt_str.PStep	52895
k_CAVNodeAbsentDiag_Cnt_str.NStep	39371
k_CAVNodeAbsentTimeout_mS_u16	43537
k_CAVNodeTimeout_mS_u16	12238
k_CMM388MsgTimeout_mS_u16	13795
k_CMM388NTCEnableTimeout_mS_u16	61071
k_CMMNTCEnableTimeout_mS_u16	6457
k_CMMNodeAbsentDiag_Cnt_str.Threshold	45529
k_CMMNodeAbsentDiag_Cnt_str.PStep	15461
k_CMMNodeAbsentDiag_Cnt_str.NStep	28956
k_CMMNodeAbsentTimeout_mS_u16	51923

Name	Input Value
k_CONSANGLECPKMax_HwDeg_f32	115.055099
k_CONSANGLECPKMin_HwDeg_f32	-771.094299
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	34235
k_CONSANGLECPKSigValidThresh_Cnt_u16	19239
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	28955
k_CPKVehicleSpeedValidThresh_Cnt_u16	23846
k_CityParkInputInvalidThresh_Cnt_u16	46915
k_CityParkInputValidThresh_Cnt_u16	58553
k_ComputerRazGCTSigValidThresh_Cnt_u16	51263
k_CptTemporelSigValidThresh_Cnt_u16	60152
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	8781
k_DMDFCTCPKSigValidThresh_Cnt_u16	48754
k_DMDFCTCPKValidCount_Cnt_u16	5409
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	24432
k_DMDRELAXECPKSigValidThresh_Cnt_u16	7757
k_DMDRelaxeConsistentThresh_Cnt_u16	5579
k_DateValidThresh_Cnt_u16	61664
k_DefaultVehSpd_Kph_f32	142.928696
k_DiagMuxOnAbsentTimeout_mS_u16	47860
k_EMNodeTimeout_mS_u16	21547
k_ESPNTCEnableTimeout_mS_u16	43367
k_ESPNodeAbsentDiag_Cnt_str.Threshold	14526
k_ESPNodeAbsentDiag_Cnt_str.PStep	64285
k_ESPNodeAbsentDiag_Cnt_str.NStep	2381
k_ESPNodeAbsentTimeout_mS_u16	54395
k_EtatMTSigInvalidThresh_Cnt_u16	8824
k_EtatMTSigValidThresh_Cnt_u16	61109
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	36154
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	33963
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	61710
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	1194
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	12707
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	41403
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	56266
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	19179
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	24277
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	3066
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	26947
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	36992
k_ISDATDIRASentDiag_Cnt_str.Threshold	5040
k_ISDATDIRASentDiag_Cnt_str.PStep	38556
k_ISDATDIRASentDiag_Cnt_str.NStep	13820
k_ISDATDIRASentTimeout_mS_u16	18673
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	21441
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	49676
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	9827
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	36421
k_ISDYNAASChkSumValidThresh_Cnt_u16	35394
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	8632
k_ISDYNAASMsgCountValidThresh_Cnt_u16	23661
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	7321
k_ISDYNAASMsgLenValidThresh_Cnt_u16	56561
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	12641
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	23715
k_ISDYNABRChkSumValidThresh_Cnt_u16	11592
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	52601
k_ISDYNABRMsgCountValidThresh_Cnt_u16	44941
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	15661
k_ISDYNABRMsgLenValidThresh_Cnt_u16	142
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	59808
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	41828
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16380
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	61744
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	42830
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	44834
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	32625
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	65406
k_ISDYNVOLChkSumValidThresh_Cnt_u16	24678
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	57271
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	61334
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	17149
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	28174
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	60686

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_IgnOnTimeout_mS_u16	54570
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	69.0034027
k_PowerCutVehSpdLowThresh_Kph_f32	146.667404
k_PowerCutVehSpdLowTimeout_mS_u16	37221
k_VBattMaxAAS_Volt_f32	20.1186008
k_VBattMaxBSI_Volt_f32	28.5177002
k_VBattMaxCAV_Volt_f32	5.52899981
k_VBattMaxCMM388_Volt_f32	30.4885006
k_VBattMaxCMM_Volt_f32	29.3194008
k_VBattMaxESP_Volt_f32	14.335
k_VBattMinAAS_Volt_f32	8.86180019
k_VBattMinBSI_Volt_f32	14.335
k_VBattMinCAV_Volt_f32	8.52639961
k_VBattMinCMM388_Volt_f32	27.0205002
k_VBattMinCMM_Volt_f32	32
k_VBattMinESP_Volt_f32	29.3194008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	23875
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	41883
k_VitesseVehicleBVRampValidThresh_Cnt_u16	17947
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	58333
k_VitesseVehicleBVSigValidThresh_Cnt_u16	30054
k_VitesseVehicleBVSpeedPassThresh_kph_f32	112.956001
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	15035
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	6024
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4052061440
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	17
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	28
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3783568128
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	170
target_SrlComInput_Per1_Batt_Volt_f32.value	7.9382
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1886829824
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	35
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.371492177
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	52
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1882402048
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	80
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3281898752
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1402498304
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2283998464
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3376262400
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2129153280
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	287501568
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	159
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	175
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	196
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	245
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	138

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3663203584
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	68
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	111
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	192
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	32
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	43134208
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	249
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4085042432
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	28
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3774311680
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	25
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	33
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	104
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	124271872
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1943
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0749123096
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	724826
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	159.122803
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	24338

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3783568128	3783568128	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3783568128	3783568128	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	49678	49678	✔
AngleVolantMsgTimer_mS_M_u32	3783568128	3783568128	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-180.787766	-180.787766	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3783568128	3783568128	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3783568128	3783568128	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3783568128	3783568128	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3783568128	3783568128	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3783568128	3783568128	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3783568128	3783568128	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	46397	46397	✔
CAVNodeAbsentTimer_mS_M_u32	3783568128	3783568128	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3783568128	3783568128	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3783568128	3783568128	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3783568128	3783568128	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CONSANGLECPK_Cnt_M_u16	55750	55750	✔
CONSANGLECPK_HwDeg_M_f32	664.374573	664.374573 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	55750	55750	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	402267392	402267392	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	38233	38233	✔
CityParkInputConsistentCount_Cnt_M_u16	58553	58553	✔
CityParkInputInvalidCount_Cnt_M_u16	795	795	✔
CityParkInputMsgTimer_mS_M_u32	3783568128	3783568128	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3783568128	3783568128	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3783568128	3783568128	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3783568128	3783568128	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3783568128	3783568128	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3783568128	3783568128	✔
ESPNTCEnableTimer_mS_M_u32	3783568128	3783568128	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	14526	14526	✔
ESPNodeAbsentTimer_mS_M_u32	3783568128	3783568128	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4	4	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3783568128	3783568128	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3783568128	3783568128	✔
ElecIntTimer_mS_M_u32[1]	5556	5556	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	776191232	776191232	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3783568128	3783568128	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3783568128	3783568128	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3783568128	3783568128	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3783568128	3783568128	✔
ISDATDIRASentFltAcc_Cnt_M_u16	5040	5040	✔
ISDATDIRASentTimer_mS_M_u32	3783568128	3783568128	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3783568128	3783568128	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3783568128	3783568128	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3783568128	3783568128	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3783568128	3783568128	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3783568128	3783568128	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3783568128	3783568128	✔
IgnOnTimer_mS_M_u32	3416337664	3416337664	✔
IgnTimeOff_Sec_M_u32	1680329261	1680329261	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	52	52	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1882402048	1882402048	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	80	80	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3281898752	3281898752	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	245	245	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1402498304	1402498304	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	68	68	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2283998464	2283998464	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1665756416	1665756416	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	39	39	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2129153280	2129153280	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	253	253	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	287501568	287501568	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	138	138	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3663203584	3663203584	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	32	32	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	43134208	43134208	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	249	249	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4085042432	4085042432	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	28	28	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3774311680	3774311680	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	124271872	124271872	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	382.705688	382.705688	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	162.083801	162.083801	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	304.505188	304.505188	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-180.787766	-180.787766	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	55750	55750	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1680329261	1680329261	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	664.374573	664.374573 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.78 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1485209344
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	10582
AASNodeAbsentTimer_mS_M_u32	2373005056
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	27157
ANGLEVOLANTSigValidCount_Cnt_M_u16	55311
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	60871
AngleVolantMsgTimer_mS_M_u32	1485209344
AngleVolantValidCount_Cnt_M_u16	4837
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-384.970093
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	166719232
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3129503488
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2027134720

Name	Input Value
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2847760128
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	14744
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1943936768
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	41456
CAVNodeAbsentTimer_mS_M_u32	1285705472
CDD_SrlComVehSpd_Kph_G_f32	42.9721985
CMM388NTCEnableTimer_mS_M_u32	803180288
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1427132160
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	49521
CMMNodeAbsentTimer_mS_M_u32	4056899328
CONSANGLECPKSigInvalidCount_Cnt_M_u16	35472
CONSANGLECPKSigValidCount_Cnt_M_u16	17178
CONSANGLECPK_Cnt_M_u16	19665
CONSANGLECPK_HwDeg_M_f32	-501.328613
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	19665
CPKVehicleSpeedMsgTimer_mS_M_u32	1864466176
CPKVehicleSpeedValidCount_Cnt_M_u16	65103
CityParkInputConsistentCount_Cnt_M_u16	18137
CityParkInputInvalidCount_Cnt_M_u16	29243
CityParkInputMsgTimer_mS_M_u32	2214149120
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3194302208
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	2890
ComputerRazGCTSigInvalidTimer_mS_M_u32	1836371712
ComputerRazGCTSigValidCount_Cnt_M_u16	63970
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	2631
DMDFCTCPKSigValidCount_Cnt_M_u16	6986
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	38671
DMDRELAXECPKSigValidCount_Cnt_M_u16	44169
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	3073
DateInvalidTimer_mS_M_u32	3129503488
DiagMuxOnAbsentTimer_mS_M_u32	3641130752
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2847760128
ESPNTCEnableTimer_mS_M_u32	4120260352
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	42839
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	555
EffacDefaultDiagTimer_mS_M_u32[1]	5555
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	201
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	548937472
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	21175
EtatMTSigValidCount_Cnt_M_u16	27853
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	9610
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1428
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	34232
ISDAT4V2BSI552MsgTimer_mS_M_u32	2982371072
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	64710
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	65092
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	27853
ISDATBSI3F2MsgTimer_mS_M_u32	3054321408
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	31605
ISDATBSI412MsgLenValidCount_Cnt_M_u16	7652
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	21175
ISDATBSI412MsgTimer_mS_M_u32	2475458304
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	20581

Name	Input Value
ISDATBSI432MsgLenValidCount_Cnt_M_u16	17739
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	14773
ISDATDIRASentFltAcc_Cnt_M_u16	32249
ISDATDIRASentTimer_mS_M_u32	1864466176
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	599
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	4837
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	2378
ISDYN2CMMMsgTimer_mS_M_u32	1277701888
ISDYNAASChkSumInvalidCount_Cnt_M_u16	4688
ISDYNAASChkSumValidCount_Cnt_M_u16	7659
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	28648
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	55527
ISDYNAASMsgLenValidCount_Cnt_M_u16	40665
ISDYNAASMsgTimeValidCount_Cnt_M_u16	4688
ISDYNAASMsgTimer_mS_M_u32	2162921216
ISDYNABRChkSumInvalidCount_Cnt_M_u16	48076
ISDYNABRChkSumValidCount_Cnt_M_u16	65326
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	64467
ISDYNABRMsgCountValidCount_Cnt_M_u16	13230
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	41747
ISDYNABRMsgLenValidCount_Cnt_M_u16	51165
ISDYNABRMsgTimeValidCount_Cnt_M_u16	19665
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	653
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1191
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	27853
ISDYNCMM208MsgTimer_mS_M_u32	2587422464
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2463
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1297
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	4331
ISDYNCMM388MsgTimer_mS_M_u32	2005733120
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	65430
ISDYNVOLChkSumValidCount_Cnt_M_u16	37024
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	61005
ISDYNVOLMsgCountValidCount_Cnt_M_u16	6096
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	43220
ISDYNVOLMsgLenValidCount_Cnt_M_u16	41918
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	49521
ISDYNVOLMsgTimer_mS_M_u32	2592132864
IgnOnTimer_mS_M_u32	2659258112
IgnTimeOff_Sec_M_u32	993125224
ManVehSpd_Kph_M_f32	543.626709
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	127
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	254
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	98254592
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	84
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1152818944
PrevISDATBSI412MsgDLCError_Cnt_M_u08	60
PrevISDATBSI412MsgRxTime_MSec_M_u32	2653376256
PrevISDATBSI432MsgDLCError_Cnt_M_u08	0
PrevISDATBSI432MsgRxTime_MSec_M_u32	2713333504
PrevISDATDIRAMsgTxTime_MSec_M_u32	1298878208
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	209
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1561911040
PrevISDYNAASMsgDLCError_Cnt_M_u08	201
PrevISDYNAASMsgRxTime_MSec_M_u32	3087453952
PrevISDYNABRMsgDLCError_Cnt_M_u08	235
PrevISDYNABRMsgRxTime_MSec_M_u32	2140737280
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	152
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4224700160
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	75
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4235276032
PrevISDYNVOLMsgDLCError_Cnt_M_u08	124

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevISDYNVOLMsgRxTime_MSec_M_u32	2921877248
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	227704576
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	285.299103
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	6893
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	31071
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	55274
VitesseVehicleBVRampValidCount_Cnt_M_u16	59932
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	56978
VitesseVehicleBVSigValidCount_Cnt_M_u16	41036
VitesseVehicleBV_Kph_M_f32	17.4666996
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	4331
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	59709
VitesseVehiculeRoues_Kph_M_f32	137.8452
k_AASNTCEnableTimeout_mS_u16	51884
k_AASNodeAbsentDiag_Cnt_str.Threshold	25462
k_AASNodeAbsentDiag_Cnt_str.PStep	37884
k_AASNodeAbsentDiag_Cnt_str.NStep	4555
k_AASNodeAbsentTimeout_mS_u16	15092
k_AASNodeTimeout_mS_u16	26719
k_ABSNodeTimeout_mS_u16	30032
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	46772
k_ANGLEVOLANTSigValidThresh_Cnt_u16	6362
k_AngleVolantInvalidThresh_Cnt_u16	44101
k_AngleVolantValidThresh_Cnt_u16	29243
k_BSI552MsgTimeout_mS_u16	32872
k_BSINTCEnableTimeout_mS_u16	24957
k_BSINodeAbsentDiag_Cnt_str.Threshold	23532
k_BSINodeAbsentDiag_Cnt_str.PStep	35539
k_BSINodeAbsentDiag_Cnt_str.NStep	13624
k_BSINodeAbsentTimeout_mS_u16	30943
k_BSINodeTimeout_mS_u16	14773
k_BattOvHi_Volt_f32	15.2028999
k_BattOvLo_Volt_f32	7.09649992
k_BattUvHi_Volt_f32	23.5181999
k_BattUvLo_Volt_f32	21.6923008
k_CAVNTCEnableTimeout_mS_u16	38233
k_CAVNodeAbsentDiag_Cnt_str.Threshold	33539
k_CAVNodeAbsentDiag_Cnt_str.PStep	46496
k_CAVNodeAbsentDiag_Cnt_str.NStep	42719
k_CAVNodeAbsentTimeout_mS_u16	10998
k_CAVNodeTimeout_mS_u16	45980
k_CMM388MsgTimeout_mS_u16	22614
k_CMM388NTCEnableTimeout_mS_u16	46690
k_CMMNTCEnableTimeout_mS_u16	23006
k_CMMNodeAbsentDiag_Cnt_str.Threshold	1359
k_CMMNodeAbsentDiag_Cnt_str.PStep	15333
k_CMMNodeAbsentDiag_Cnt_str.NStep	8323
k_CMMNodeAbsentTimeout_mS_u16	13641
k_CONSANGLECPKMax_HwDeg_f32	386.710297
k_CONSANGLECPKMin_HwDeg_f32	-251.878998
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	49131
k_CONSANGLECPKSigValidThresh_Cnt_u16	55357
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	6605
k_CPKVehicleSpeedValidThresh_Cnt_u16	46892
k_CityParkInputInvalidThresh_Cnt_u16	3002
k_CityParkInputValidThresh_Cnt_u16	18137
k_ComputerRazGCTSigValidThresh_Cnt_u16	61716

Name	Input Value
k_CptTemporelSigValidThresh_Cnt_u16	12562
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	53779
k_DMDFCTCPKSigValidThresh_Cnt_u16	14045
k_DMDFCTCPKValidCount_Cnt_u16	11648
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	2378
k_DMDRELAXECPKSigValidThresh_Cnt_u16	26253
k_DMDRelaxeConsistentThresh_Cnt_u16	18939
k_DateValidThresh_Cnt_u16	34232
k_DefaultVehSpd_Kph_f32	150.695801
k_DiagMuxOnAbsentTimeout_mS_u16	59247
k_EMNodeTimeout_mS_u16	49889
k_ESPNTCEnableTimeout_mS_u16	5372
k_ESPNodeAbsentDiag_Cnt_str.Threshold	41241
k_ESPNodeAbsentDiag_Cnt_str.PStep	40988
k_ESPNodeAbsentDiag_Cnt_str.NStep	27645
k_ESPNodeAbsentTimeout_mS_u16	52273
k_EtatMTSigInvalidThresh_Cnt_u16	22679
k_EtatMTSigValidThresh_Cnt_u16	11833
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	44772
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	10586
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	15830
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	35031
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	9493
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	43113
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	3062
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	15260
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	8025
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	12453
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	65459
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	12121
k_ISDATDIRASentDiag_Cnt_str.Threshold	26123
k_ISDATDIRASentDiag_Cnt_str.PStep	50826
k_ISDATDIRASentDiag_Cnt_str.NStep	58773
k_ISDATDIRASentTimeout_mS_u16	56024
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	29858
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	60871
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	55768
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	27340
k_ISDYNAASChkSumValidThresh_Cnt_u16	60974
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	10963
k_ISDYNAASMsgCountValidThresh_Cnt_u16	41646
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	35776
k_ISDYNAASMsgLenValidThresh_Cnt_u16	54355
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	17858
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	53017
k_ISDYNABRChkSumValidThresh_Cnt_u16	3171
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	26776
k_ISDYNABRMsgCountValidThresh_Cnt_u16	49874
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	45169
k_ISDYNABRMsgLenValidThresh_Cnt_u16	54871
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	34173
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	42721
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	41138
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	8842
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	39189
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	18191
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	37203
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	11332
k_ISDYNVOLChkSumValidThresh_Cnt_u16	7155
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	22216
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	40482
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	32451
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	51673
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	4950
k_IgnOnTimeout_mS_u16	36688
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	194.368103
k_PowerCutVehSpdLowThresh_Kph_f32	141.344696
k_PowerCutVehSpdLowTimeout_mS_u16	22888
k_VBattMaxAAS_Volt_f32	29.0011997
k_VBattMaxBSI_Volt_f32	15.5190001
k_VBattMaxCAV_Volt_f32	6.16940022
k_VBattMaxCMM388_Volt_f32	1.48099995

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMaxCMM_Volt_f32	16.1599998
k_VBattMaxESP_Volt_f32	6.27530003
k_VBattMinAAS_Volt_f32	31.7817993
k_VBattMinBSI_Volt_f32	6.27530003
k_VBattMinCAV_Volt_f32	9.36289978
k_VBattMinCMM388_Volt_f32	4.23549986
k_VBattMinCMM_Volt_f32	4.65630007
k_VBattMinESP_Volt_f32	16.1599998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	39476
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	6866
k_VitesseVehicleBVRampValidThresh_Cnt_u16	40269
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	65440
k_VitesseVehicleBVSigValidThresh_Cnt_u16	42222
k_VitesseVehicleBVSpeedPassThresh_kph_f32	340.619812
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	20720
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	15266
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3129503488
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	32
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	59725
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2393931008
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	75
target_SrlComInput_Per1_Batt_Volt_f32.value	26.2362995
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	746790656
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	240
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.975073159
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	231
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3080916736
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4150439680
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3627175680
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	161
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	34729728
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	486641408
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	193
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3506515712
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3322990336
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	97
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	132
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	139
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	208
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	234
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	41
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1844375296
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	80
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	126
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	128
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	218

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1962544896
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	127
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1043967744
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1753829120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	107
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	134
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	245
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2533400320
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2862
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.368871123
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	220674
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	87.9425964
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	61439

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2393931008	2393931008	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2393931008	2393931008	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2393931008	2393931008	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-384.970093	-384.970093	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2393931008	2393931008	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2393931008	2393931008	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2393931008	2393931008	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2393931008	2393931008	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2393931008	2393931008	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2393931008	2393931008	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	33539	33539	✔
CAVNodeAbsentTimer_mS_M_u32	2393931008	2393931008	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2393931008	2393931008	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2393931008	2393931008	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2393931008	2393931008	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	19665	19665	✔
CONSANGLECPK_HwDeg_M_f32	-501.328613	-501.328613 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2393931008	2393931008	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2393931008	2393931008	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2393931008	2393931008	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2393931008	2393931008	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2393931008	2393931008	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2393931008	2393931008	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2393931008	2393931008	✔
ESPNTCEnableTimer_mS_M_u32	2393931008	2393931008	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	41241	41241	✔
ESPNodeAbsentTimer_mS_M_u32	2393931008	2393931008	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	555	555	✔
EffacDefaultDiagTimer_mS_M_u32[1]	5555	5555	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2393931008	2393931008	✔
ElecIntTimer_mS_M_u32[1]	201	201	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2393931008	2393931008	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2393931008	2393931008	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2393931008	2393931008	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2393931008	2393931008	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2393931008	2393931008	✔
ISDATDIRASentFltAcc_Cnt_M_u16	26123	26123	✔
ISDATDIRASentTimer_mS_M_u32	2393931008	2393931008	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2393931008	2393931008	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2393931008	2393931008	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2393931008	2393931008	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2393931008	2393931008	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2393931008	2393931008	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2393931008	2393931008	✔
IgnOnTimer_mS_M_u32	2659258112	2659258112	✔
IgnTimeOff_Sec_M_u32	993125224	993125224	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	231	231	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3080916736	3080916736	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	245	245	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4150439680	4150439680	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	81	81	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3627175680	3627175680	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	161	161	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	34729728	34729728	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1298878208	1298878208	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	193	193	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3506515712	3506515712	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3322990336	3322990336	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	41	41	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1844375296	1844375296	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	200	200	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1962544896	1962544896	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	127	127	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1043967744	1043967744	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	68	68	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1753829120	1753829120	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2533400320	2533400320	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	285.299103	285.299103	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	17.4666996	17.4666996	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	137.8452	137.8452	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-384.970093	-384.970093	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	19665	19665	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	993125224	993125224	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-501.328613	-501.328613 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.79 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4140254720
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	26197
AASNodeAbsentTimer_mS_M_u32	2663855616
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	48666
ANGLEVOLANTSigValidCount_Cnt_M_u16	22763
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	7426
AngleVolantMsgTimer_mS_M_u32	4140254720
AngleVolantValidCount_Cnt_M_u16	44073
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-458.452881
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2487940608
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2223076864
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2992629248
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4137854464
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	7057
BattOk_Cnt_M_lgc	0

Name	Input Value
CAVNTCEnableTimer_mS_M_u32	188769792
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	18698
CAVNodeAbsentTimer_mS_M_u32	229889536
CDD_SrlComVehSpd_Kph_G_f32	582.813599
CMM388NTCEnableTimer_mS_M_u32	3908834816
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	745133568
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	64582
CMMNodeAbsentTimer_mS_M_u32	3865880064
CONSANGLECPKSigInvalidCount_Cnt_M_u16	47018
CONSANGLECPKSigValidCount_Cnt_M_u16	45771
CONSANGLECPK_Cnt_M_u16	12710
CONSANGLECPK_HwDeg_M_f32	-392.796814
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	12710
CPKVehicleSpeedMsgTimer_mS_M_u32	3740681728
CPKVehicleSpeedValidCount_Cnt_M_u16	59188
CityParkInputConsistentCount_Cnt_M_u16	57421
CityParkInputInvalidCount_Cnt_M_u16	46887
CityParkInputMsgTimer_mS_M_u32	3080916736
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3689625088
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	36985
ComputerRazGCTSigInvalidTimer_mS_M_u32	356275712
ComputerRazGCTSigValidCount_Cnt_M_u16	11058
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	7939
DMDFCTCPKSigValidCount_Cnt_M_u16	61628
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	40748
DMDRELAXECPKSigValidCount_Cnt_M_u16	17277
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	14167
DateInvalidTimer_mS_M_u32	2223076864
DiagMuxOnAbsentTimer_mS_M_u32	1749353984
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4137854464
ESPNTCEnableTimer_mS_M_u32	978859520
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	57171
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	963
EffacDefaultDiagTimer_mS_M_u32[1]	7852
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	89
ElecIntTimer_mS_M_u32[1]	899
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3971114496
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	12659
EtatMTSigValidCount_Cnt_M_u16	14320
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	20156
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	54109
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	59762
ISDAT4V2BSI552MsgTimer_mS_M_u32	1989191168
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	34502
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	30476
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	14320
ISDATBSI3F2MsgTimer_mS_M_u32	1764951552
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	55224
ISDATBSI412MsgLenValidCount_Cnt_M_u16	42286
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	12659
ISDATBSI412MsgTimer_mS_M_u32	3719644672
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	8042
ISDATBSI432MsgLenValidCount_Cnt_M_u16	54647
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	54715
ISDATDIRASentFltAcc_Cnt_M_u16	6383
ISDATDIRASentTimer_mS_M_u32	3740681728
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	43284

Name	Input Value
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	44073
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	60922
ISDYN2CMMMsgTimer_mS_M_u32	4272043520
ISDYNAASChkSumInvalidCount_Cnt_M_u16	4967
ISDYNAASChkSumValidCount_Cnt_M_u16	21849
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	24864
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	16421
ISDYNAASMsgLenValidCount_Cnt_M_u16	45838
ISDYNAASMsgTimeValidCount_Cnt_M_u16	4967
ISDYNAASMsgTimer_mS_M_u32	634918400
ISDYNABRChkSumInvalidCount_Cnt_M_u16	48245
ISDYNABRChkSumValidCount_Cnt_M_u16	30479
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	8926
ISDYNABRMsgCountValidCount_Cnt_M_u16	57360
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	14881
ISDYNABRMsgLenValidCount_Cnt_M_u16	61570
ISDYNABRMsgTimeValidCount_Cnt_M_u16	12710
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	654
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1193
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	14320
ISDYNCMM208MsgTimer_mS_M_u32	1198519808
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2467
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1299
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	18967
ISDYNCMM388MsgTimer_mS_M_u32	2817758720
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	61592
ISDYNVOLChkSumValidCount_Cnt_M_u16	25145
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	2801
ISDYNVOLMsgCountValidCount_Cnt_M_u16	37674
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	3804
ISDYNVOLMsgLenValidCount_Cnt_M_u16	49885
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	64582
ISDYNVOLMsgTimer_mS_M_u32	3189265920
IgnOnTimer_mS_M_u32	51877376
IgnTimeOff_Sec_M_u32	888257058
ManVehSpd_Kph_M_f32	205.729904
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	129
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	212
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	835257856
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	252
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2595677696
PrevISDATBSI412MsgDLCError_Cnt_M_u08	24
PrevISDATBSI412MsgRxTime_MSec_M_u32	1831130624
PrevISDATBSI432MsgDLCError_Cnt_M_u08	255
PrevISDATBSI432MsgRxTime_MSec_M_u32	3320591872
PrevISDATDIRAMsgTxTime_MSec_M_u32	1868092928
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	159
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2861573632
PrevISDYNAASMsgDLCError_Cnt_M_u08	5
PrevISDYNAASMsgRxTime_MSec_M_u32	4253439488
PrevISDYNABRMsgDLCError_Cnt_M_u08	229
PrevISDYNABRMsgRxTime_MSec_M_u32	3218052608
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	252
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2519422464
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	184
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1372009984
PrevISDYNVOLMsgDLCError_Cnt_M_u08	32
PrevISDYNVOLMsgRxTime_MSec_M_u32	2166478336
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	128140800
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	312.194489
PrevVitesseVehicleBVValid_Cnt_M_lgc	0

Name	Input Value
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	4627
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	47996
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	3868
VitesseVehicleBVRampValidCount_Cnt_M_u16	40261
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	38051
VitesseVehicleBVSigValidCount_Cnt_M_u16	13364
VitesseVehicleBV_Kph_M_f32	508.064514
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	18967
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1505
VitesseVehiculeRoues_Kph_M_f32	248.200195
k_AASNTCEnableTimeout_mS_u16	58389
k_AASNodeAbsentDiag_Cnt_str.Threshold	18788
k_AASNodeAbsentDiag_Cnt_str.PStep	63814
k_AASNodeAbsentDiag_Cnt_str.NStep	30530
k_AASNodeAbsentTimeout_mS_u16	12284
k_AASNodeTimeout_mS_u16	61052
k_ABSNodeTimeout_mS_u16	16872
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	59517
k_ANGLEVOLANTSigValidThresh_Cnt_u16	22218
k_AngleVolantInvalidThresh_Cnt_u16	2185
k_AngleVolantValidThresh_Cnt_u16	46887
k_BSI552MsgTimeout_mS_u16	44128
k_BSINTCEnableTimeout_mS_u16	19490
k_BSINodeAbsentDiag_Cnt_str.Threshold	23572
k_BSINodeAbsentDiag_Cnt_str.PStep	35522
k_BSINodeAbsentDiag_Cnt_str.NStep	13647
k_BSINodeAbsentTimeout_mS_u16	56250
k_BSINodeTimeout_mS_u16	54715
k_BattOvHi_Volt_f32	27.0851994
k_BattOvLo_Volt_f32	6.93919992
k_BattUvHi_Volt_f32	2.96469998
k_BattUvLo_Volt_f32	23.2639999
k_CAVNTCEnableTimeout_mS_u16	17869
k_CAVNodeAbsentDiag_Cnt_str.Threshold	25288
k_CAVNodeAbsentDiag_Cnt_str.PStep	27127
k_CAVNodeAbsentDiag_Cnt_str.NStep	38758
k_CAVNodeAbsentTimeout_mS_u16	17912
k_CAVNodeTimeout_mS_u16	27782
k_CMM388MsgTimeout_mS_u16	55637
k_CMM388NTCEnableTimeout_mS_u16	61233
k_CMMNTCEnableTimeout_mS_u16	53118
k_CMMNodeAbsentDiag_Cnt_str.Threshold	7877
k_CMMNodeAbsentDiag_Cnt_str.PStep	40761
k_CMMNodeAbsentDiag_Cnt_str.NStep	33909
k_CMMNodeAbsentTimeout_mS_u16	20925
k_CONSANGLECPKMax_HwDeg_f32	640.911621
k_CONSANGLECPKMin_HwDeg_f32	-255.9543
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	15639
k_CONSANGLECPKSigValidThresh_Cnt_u16	14561
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	4658
k_CPKVehicleSpeedValidThresh_Cnt_u16	49299
k_CityParkInputInvalidThresh_Cnt_u16	1195
k_CityParkInputValidThresh_Cnt_u16	57421
k_ComputerRazGCTSigValidThresh_Cnt_u16	25052
k_CptTemporelSigValidThresh_Cnt_u16	38562
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	44321
k_DMDFCTCPKSigValidThresh_Cnt_u16	41858
k_DMDFCTCPKValidCount_Cnt_u16	57305
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	60922

Name	Input Value
k_DMDRELAXECPKSigValidThresh_Cnt_u16	56051
k_DMDRelaxeConsistentThresh_Cnt_u16	26793
k_DateValidThresh_Cnt_u16	59762
k_DefaultVehSpd_Kph_f32	242.767197
k_DiagMuxOnAbsentTimeout_mS_u16	22988
k_EMNodeTimeout_mS_u16	37559
k_ESPNTCEnableTimeout_mS_u16	8166
k_ESPNodeAbsentDiag_Cnt_str.Threshold	25753
k_ESPNodeAbsentDiag_Cnt_str.PStep	21220
k_ESPNodeAbsentDiag_Cnt_str.NStep	43901
k_ESPNodeAbsentTimeout_mS_u16	11525
k_EtatMTSigInvalidThresh_Cnt_u16	53780
k_EtatMTSigValidThresh_Cnt_u16	54766
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	28397
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	54347
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	12118
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	26259
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	34457
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	8412
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	28855
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	30340
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	33422
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	54826
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	40383
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	22799
k_ISDATDIRASentDiag_Cnt_str.Threshold	30477
k_ISDATDIRASentDiag_Cnt_str.PStep	21303
k_ISDATDIRASentDiag_Cnt_str.NStep	38088
k_ISDATDIRASentTimeout_mS_u16	36689
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	60724
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	7426
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	16722
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	44917
k_ISDYNAASChkSumValidThresh_Cnt_u16	43535
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	38366
k_ISDYNAASMsgCountValidThresh_Cnt_u16	37648
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	7321
k_ISDYNAASMsgLenValidThresh_Cnt_u16	31392
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	28690
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	19983
k_ISDYNABRChkSumValidThresh_Cnt_u16	47856
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	36497
k_ISDYNABRMsgCountValidThresh_Cnt_u16	25762
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	12102
k_ISDYNABRMsgLenValidThresh_Cnt_u16	21075
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	34977
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	15927
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	39937
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	11259
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	12570
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	3051
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	47583
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	49483
k_ISDYNVOLChkSumValidThresh_Cnt_u16	42753
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	54528
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	27187
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	56655
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	20684
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	14488
k_IgnOnTimeout_mS_u16	51239
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	200.250107
k_PowerCutVehSpdLowThresh_Kph_f32	207.320404
k_PowerCutVehSpdLowTimeout_mS_u16	10209
k_VBattMaxAAS_Volt_f32	27.5753002
k_VBattMaxBSI_Volt_f32	20.1333008
k_VBattMaxCAV_Volt_f32	15.8587999
k_VBattMaxCMM388_Volt_f32	10.9103003
k_VBattMaxCMM_Volt_f32	11.5713997
k_VBattMaxESP_Volt_f32	18.7637997
k_VBattMinAAS_Volt_f32	28.0956993
k_VBattMinBSI_Volt_f32	18.7637997
k_VBattMinCAV_Volt_f32	8.95300007

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinCMM388_Volt_f32	17.6966991
k_VBattMinCMM_Volt_f32	13.6950998
k_VBattMinESP_Volt_f32	11.5713997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	17534
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	14179
k_VitesseVehicleBVRampValidThresh_Cnt_u16	65009
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	5433
k_VitesseVehicleBVSigValidThresh_Cnt_u16	23054
k_VitesseVehicleBVSpeedPassThresh_kph_f32	31.5009995
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	15370
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	16563
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2223076864
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	248
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	23614
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2995445504
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	184
target_SrlComInput_Per1_Batt_Volt_f32.value	7.02299976
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3042010624
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	179
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.2754637
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3216086528
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	116569600
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2869155328
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	138
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3018126848
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	697701888
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	337065472
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	127
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2070435328
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	69
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	124
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	176
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	204
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	609089024
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	115
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	185
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2745996800
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1315812864
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	86

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	369022464
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	37
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	47
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	61
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	78
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	161
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	173
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1272505856
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3710
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0469047278
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	973755
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	231.776703
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	23261

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2995445504	2995445504	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2995445504	2995445504	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2995445504	2995445504	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-458.452881	-458.452881	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2995445504	2995445504	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2995445504	2995445504	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2995445504	2995445504	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2995445504	2995445504	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2995445504	2995445504	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2995445504	2995445504	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	25288	25288	✔
CAVNodeAbsentTimer_mS_M_u32	2995445504	2995445504	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2995445504	2995445504	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2995445504	2995445504	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2995445504	2995445504	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	12710	12710	✔
CONSANGLECPK_HwDeg_M_f32	-392.796814	-392.796814 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2995445504	2995445504	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2995445504	2995445504	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2995445504	2995445504	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2995445504	2995445504	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2995445504	2995445504	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2995445504	2995445504	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2995445504	2995445504	✔
ESPNTCEnableTimer_mS_M_u32	2995445504	2995445504	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	25753	25753	✔
ESPNodeAbsentTimer_mS_M_u32	2995445504	2995445504	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	963	963	✔
EffacDefaultDiagTimer_mS_M_u32[1]	7852	7852	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2995445504	2995445504	✔
ElecIntTimer_mS_M_u32[1]	899	899	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2995445504	2995445504	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2995445504	2995445504	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2995445504	2995445504	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2995445504	2995445504	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2995445504	2995445504	✔
ISDATDIRASentFltAcc_Cnt_M_u16	30477	30477	✔
ISDATDIRASentTimer_mS_M_u32	2995445504	2995445504	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2995445504	2995445504	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2995445504	2995445504	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2995445504	2995445504	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgTimer_mS_M_u32	2995445504	2995445504	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2995445504	2995445504	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2995445504	2995445504	✔
IgnOnTimer_mS_M_u32	51877376	51877376	✔
IgnTimeOff_Sec_M_u32	888257058	888257058	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	68	68	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3216086528	3216086528	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	0	0	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	116569600	116569600	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	20	20	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2869155328	2869155328	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	138	138	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3018126848	3018126848	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1868092928	1868092928	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	183	183	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	337065472	337065472	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	127	127	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2070435328	2070435328	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	167	167	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	609089024	609089024	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	190	190	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2745996800	2745996800	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	125	125	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1315812864	1315812864	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	86	86	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	369022464	369022464	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1272505856	1272505856	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	312.194489	312.194489	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	508.064514	508.064514	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	248.200195	248.200195	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-458.452881	-458.452881	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	12710	12710	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	888257058	888257058	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-392.796814	-392.796814 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.80 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4225822976
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	1845
AASNodeAbsentTimer_mS_M_u32	799088896
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	45543
ANGLEVOLANTSigValidCount_Cnt_M_u16	13107
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	55086
AngleVolantMsgTimer_mS_M_u32	4225822976
AngleVolantValidCount_Cnt_M_u16	11833
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-75.095047
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	236314880
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	930242816
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1939280128
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	567202048
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	13698
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2331349248
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	31127
CAVNodeAbsentTimer_mS_M_u32	3713745152
CDD_SrlComVehSpd_Kph_G_f32	631.981201
CMM388NTCEnableTimer_mS_M_u32	3162669312
CMM388NTCsEnabled_Cnt_M_lgc	0

Name	Input Value
CMMNTCEnableTimer_mS_M_u32	3644408064
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	10916
CMMNodeAbsentTimer_mS_M_u32	4201697536
CONSANGLECPKSigInvalidCount_Cnt_M_u16	46136
CONSANGLECPKSigValidCount_Cnt_M_u16	21652
CONSANGLECPK_Cnt_M_u16	1027
CONSANGLECPK_HwDeg_M_f32	445.40271
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	1027
CPKVehicleSpeedMsgTimer_mS_M_u32	3209949440
CPKVehicleSpeedValidCount_Cnt_M_u16	42304
CityParkInputConsistentCount_Cnt_M_u16	8653
CityParkInputInvalidCount_Cnt_M_u16	37441
CityParkInputMsgTimer_mS_M_u32	3216086528
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	137699584
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	6345
ComputerRazGCTSigInvalidTimer_mS_M_u32	2294399232
ComputerRazGCTSigValidCount_Cnt_M_u16	5406
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	51885
DMDFCTCPKSigValidCount_Cnt_M_u16	18241
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	54961
DMDRELAXECPKSigValidCount_Cnt_M_u16	15229
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	10545
DateInvalidTimer_mS_M_u32	930242816
DiagMuxOnAbsentTimer_mS_M_u32	3462902016
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	567202048
ESPNTCEnableTimer_mS_M_u32	3773702400
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	49980
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	4063897088
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	749
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	782209280
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	53276
EtatMTSigValidCount_Cnt_M_u16	48740
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	46850
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	47838
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	46367
ISDAT4V2BSI552MsgTimer_mS_M_u32	3657748736
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	54690
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	9874
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	48740
ISDATBSI3F2MsgTimer_mS_M_u32	60666112
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	31691
ISDATBSI412MsgLenValidCount_Cnt_M_u16	62763
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	53276
ISDATBSI412MsgTimer_mS_M_u32	2132209920
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	20792
ISDATBSI432MsgLenValidCount_Cnt_M_u16	28880
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	55172
ISDATDIRASentFltAcc_Cnt_M_u16	56808
ISDATDIRASentTimer_mS_M_u32	3209949440
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	54713
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	11833
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	63944
ISDYN2CMMMsgTimer_mS_M_u32	1007689984
ISDYNAASChkSumInvalidCount_Cnt_M_u16	51199
ISDYNAASChkSumValidCount_Cnt_M_u16	54251
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	43860
ISDYNAASMsgCount_Cnt_M_u08	7

Name	Input Value
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	49222
ISDYNAASMsgLenValidCount_Cnt_M_u16	6474
ISDYNAASMsgTimeValidCount_Cnt_M_u16	51199
ISDYNAASMsgTimer_mS_M_u32	1978564864
ISDYNABRChkSumInvalidCount_Cnt_M_u16	56405
ISDYNABRChkSumValidCount_Cnt_M_u16	7753
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	13722
ISDYNABRMsgCountValidCount_Cnt_M_u16	53190
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	51411
ISDYNABRMsgLenValidCount_Cnt_M_u16	14191
ISDYNABRMsgTimeValidCount_Cnt_M_u16	1027
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	655
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1195
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	48740
ISDYNCMM208MsgTimer_mS_M_u32	3366379776
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2471
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1301
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	35951
ISDYNCMM388MsgTimer_mS_M_u32	3181117696
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	16750
ISDYNVOLChkSumValidCount_Cnt_M_u16	32330
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	16099
ISDYNVOLMsgCountValidCount_Cnt_M_u16	38903
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	39073
ISDYNVOLMsgLenValidCount_Cnt_M_u16	36444
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	10916
ISDYNVOLMsgTimer_mS_M_u32	4264411392
IgnOnTimer_mS_M_u32	1009778944
IgnTimeOff_Sec_M_u32	1275763533
ManVehSpd_Kph_M_f32	357.613403
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	131
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	240
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2178658560
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	250
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3599896832
PrevISDATBSI412MsgDLCError_Cnt_M_u08	45
PrevISDATBSI412MsgRxTime_MSec_M_u32	3272098048
PrevISDATBSI432MsgDLCError_Cnt_M_u08	214
PrevISDATBSI432MsgRxTime_MSec_M_u32	2385649920
PrevISDATDIRAMsgTxTime_MSec_M_u32	2355904768
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	200
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2617659648
PrevISDYNAASMsgDLCError_Cnt_M_u08	169
PrevISDYNAASMsgRxTime_MSec_M_u32	2011414784
PrevISDYNABRMsgDLCError_Cnt_M_u08	61
PrevISDYNABRMsgRxTime_MSec_M_u32	3859284224
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	153
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2180301056
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	227
PrevISDYNCMM388MsgRxTime_MSec_M_u32	379658496
PrevISDYNVOLMsgDLCError_Cnt_M_u08	196
PrevISDYNVOLMsgRxTime_MSec_M_u32	3138470144
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	961343744
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	74.7542038
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1

Name	Input Value
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	33404
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	14336
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	61281
VitesseVehicleBVRampValidCount_Cnt_M_u16	63141
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	37452
VitesseVehicleBVSigValidCount_Cnt_M_u16	1368
VitesseVehicleBV_Kph_M_f32	653.686096
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	35951
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	35538
VitesseVehiculeRoues_Kph_M_f32	473.125214
k_AASNTCEnableTimeout_mS_u16	26806
k_AASNodeAbsentDiag_Cnt_str.Threshold	41948
k_AASNodeAbsentDiag_Cnt_str.PStep	11120
k_AASNodeAbsentDiag_Cnt_str.NStep	42740
k_AASNodeAbsentTimeout_mS_u16	44736
k_AASNodeTimeout_mS_u16	40704
k_ABSNodeTimeout_mS_u16	13822
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	511
k_ANGLEVOLANTSigValidThresh_Cnt_u16	63703
k_AngleVolantInvalidThresh_Cnt_u16	40858
k_AngleVolantValidThresh_Cnt_u16	37441
k_BSI552MsgTimeout_mS_u16	21333
k_BSINTCEnableTimeout_mS_u16	43792
k_BSINodeAbsentDiag_Cnt_str.Threshold	23612
k_BSINodeAbsentDiag_Cnt_str.PStep	35505
k_BSINodeAbsentDiag_Cnt_str.NStep	13670
k_BSINodeAbsentTimeout_mS_u16	31494
k_BSINodeTimeout_mS_u16	55172
k_BattOvHi_Volt_f32	21.7623005
k_BattOvLo_Volt_f32	20.5963993
k_BattUvHi_Volt_f32	26.6483002
k_BattUvLo_Volt_f32	18.7849998
k_CAVNTCEnableTimeout_mS_u16	65103
k_CAVNodeAbsentDiag_Cnt_str.Threshold	43912
k_CAVNodeAbsentDiag_Cnt_str.PStep	50804
k_CAVNodeAbsentDiag_Cnt_str.NStep	17119
k_CAVNodeAbsentTimeout_mS_u16	47821
k_CAVNodeTimeout_mS_u16	1444
k_CMM388MsgTimeout_mS_u16	44597
k_CMM388NTCEnableTimeout_mS_u16	56481
k_CMMNTCEnableTimeout_mS_u16	56186
k_CMMNodeAbsentDiag_Cnt_str.Threshold	44186
k_CMMNodeAbsentDiag_Cnt_str.PStep	56183
k_CMMNodeAbsentDiag_Cnt_str.NStep	29242
k_CMMNodeAbsentTimeout_mS_u16	5950
k_CONSANGLECPKMax_HwDeg_f32	390.409912
k_CONSANGLECPKMin_HwDeg_f32	-180.090897
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	45935
k_CONSANGLECPKSigValidThresh_Cnt_u16	61906
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	35806
k_CPKVehicleSpeedValidThresh_Cnt_u16	60730
k_CityParkInputInvalidThresh_Cnt_u16	23475
k_CityParkInputValidThresh_Cnt_u16	8653
k_ComputerRazGCTSigValidThresh_Cnt_u16	7264
k_CptTemporelSigValidThresh_Cnt_u16	40912
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	28627
k_DMDFCTCPKSigValidThresh_Cnt_u16	7791
k_DMDFCTCPKValidCount_Cnt_u16	2218
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	63944
k_DMDRELAXECPKSigValidThresh_Cnt_u16	9372
k_DMDRelaxeConsistentThresh_Cnt_u16	54138
k_DateValidThresh_Cnt_u16	46367
k_DefaultVehSpd_Kph_f32	228.412399
k_DiagMuxOnAbsentTimeout_mS_u16	41873
k_EMNodeTimeout_mS_u16	38673
k_ESPNTCEnableTimeout_mS_u16	25859

Name	Input Value
k_ESPNodeAbsentDiag_Cnt_str.Threshold	59774
k_ESPNodeAbsentDiag_Cnt_str.PStep	15317
k_ESPNodeAbsentDiag_Cnt_str.NStep	32129
k_ESPNodeAbsentTimeout_mS_u16	42342
k_EtatMTSigInvalidThresh_Cnt_u16	55160
k_EtatMTSigValidThresh_Cnt_u16	15788
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	8621
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	29524
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	39090
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	43579
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	27627
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	12383
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	53585
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	425
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	47052
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	9847
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	12663
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	8393
k_ISDATDIRASentDiag_Cnt_str.Threshold	51514
k_ISDATDIRASentDiag_Cnt_str.PStep	4405
k_ISDATDIRASentDiag_Cnt_str.NStep	40247
k_ISDATDIRASentTimeout_mS_u16	54209
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	14426
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	55086
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	45247
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	853
k_ISDYNAASChkSumValidThresh_Cnt_u16	34121
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	56474
k_ISDYNAASMsgCountValidThresh_Cnt_u16	46790
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	19433
k_ISDYNAASMsgLenValidThresh_Cnt_u16	35476
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	52479
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	50441
k_ISDYNABRChkSumValidThresh_Cnt_u16	4133
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	56450
k_ISDYNABRMsgCountValidThresh_Cnt_u16	44046
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	37284
k_ISDYNABRMsgLenValidThresh_Cnt_u16	27196
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	64529
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	36368
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	37616
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	41603
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	22759
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	6707
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	27161
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	51986
k_ISDYNVOLChkSumValidThresh_Cnt_u16	64434
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	54837
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	54493
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	15496
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	58320
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	57261
k_IgnOnTimeout_mS_u16	9854
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	90.4636002
k_PowerCutVehSpdLowThresh_Kph_f32	13.2526999
k_PowerCutVehSpdLowTimeout_mS_u16	52562
k_VBattMaxAAS_Volt_f32	31.5769997
k_VBattMaxBSI_Volt_f32	32
k_VBattMaxCAV_Volt_f32	10.3624001
k_VBattMaxCMM388_Volt_f32	16.2488003
k_VBattMaxCMM_Volt_f32	12.1707001
k_VBattMaxESP_Volt_f32	24.9792004
k_VBattMinAAS_Volt_f32	3.4289999
k_VBattMinBSI_Volt_f32	24.9792004
k_VBattMinCAV_Volt_f32	23.0554008
k_VBattMinCMM388_Volt_f32	16.7401009
k_VBattMinCMM_Volt_f32	3.96289992
k_VBattMinESP_Volt_f32	12.1707001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	55932
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	41867
k_VitesseVehicleBVRampValidThresh_Cnt_u16	26083
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	25930

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VitesseVehicleBVSigValidThresh_Cnt_u16	63626
k_VitesseVehicleBVSpeedPassThresh_kph_f32	604.688477
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	41111
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	17499
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	930242816
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	205
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	19926
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	4063897088
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	227
target_SrlComInput_Per1_Batt_Volt_f32.value	5.89519978
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	281186560
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	52
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.695663929
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3999400192
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	85893376
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1164656896
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2538070272
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3803480320
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	263266560
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	104710400
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	63
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	71
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	88
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	164
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	228
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	130
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	705487104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	105
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	166
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	176
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4000383232
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3668812032
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2960802048
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	16
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	32
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	52
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	57

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	133
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	239
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3408662784
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2060
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.165124923
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	370472
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	91.1337967
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	20510

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4063897088	4063897088	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4063897088	4063897088	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	4063897088	4063897088	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-75.095047	-75.095047	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4063897088	4063897088	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4063897088	4063897088	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4063897088	4063897088	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4063897088	4063897088	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	4063897088	4063897088	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4063897088	4063897088	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	43912	43912	✔
CAVNodeAbsentTimer_mS_M_u32	4063897088	4063897088	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4063897088	4063897088	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4063897088	4063897088	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4063897088	4063897088	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	1027	1027	✔
CONSANGLECPK_HwDeg_M_f32	445.40271	445.40271 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4063897088	4063897088	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	4063897088	4063897088	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4063897088	4063897088	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4063897088	4063897088	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4063897088	4063897088	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4063897088	4063897088	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4063897088	4063897088	✔
ESPNTCEnableTimer_mS_M_u32	4063897088	4063897088	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	59774	59774	✔
ESPNodeAbsentTimer_mS_M_u32	4063897088	4063897088	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔
EffacDefaultDiagTimer_mS_M_u32[1]	4063897088	4063897088	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4063897088	4063897088	✔
ElecIntTimer_mS_M_u32[1]	749	749	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4063897088	4063897088	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4063897088	4063897088	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4063897088	4063897088	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4063897088	4063897088	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4063897088	4063897088	✔
ISDATDIRASentFltAcc_Cnt_M_u16	51514	51514	✔
ISDATDIRASentTimer_mS_M_u32	4063897088	4063897088	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4063897088	4063897088	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4063897088	4063897088	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4063897088	4063897088	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4063897088	4063897088	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4063897088	4063897088	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4063897088	4063897088	✔
IgnOnTimer_mS_M_u32	1009778944	1009778944	✔
IgnTimeOff_Sec_M_u32	1275763533	1275763533	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	34	34	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3999400192	3999400192	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	59	59	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	85893376	85893376	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	137	137	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1164656896	1164656896	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	245	245	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2538070272	2538070272	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2355904768	2355904768	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	198	198	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	263266560	263266560	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	251	251	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	104710400	104710400	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	130	130	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	705487104	705487104	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	95	95	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4000383232	4000383232	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3668812032	3668812032	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	113	113	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2960802048	2960802048	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3408662784	3408662784	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	74.7542038	74.7542038	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	653.686096	653.686096	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	473.125214	473.125214	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-75.095047	-75.095047	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	1027	1027	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1275763533	1275763533	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	445.40271	445.40271 ± 0.0125	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	228.412399	228.412399	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.81 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3170889728
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	36098
AASNodeAbsentTimer_mS_M_u32	2659147776
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	30442
ANGLEVOLANTSigValidCount_Cnt_M_u16	64967
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	16663
AngleVolantMsgTimer_mS_M_u32	3170889728
AngleVolantValidCount_Cnt_M_u16	11895
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-114.104088
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3324059648
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1544265728
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1448972288
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3669381120
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	6169
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2856456192
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	58972
CAVNodeAbsentTimer_mS_M_u32	2781937664
CDD_SrlComVehSpd_Kph_G_f32	359.932404
CMM388NTCEnableTimer_mS_M_u32	3042656256
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2855731200
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	29429
CMMNodeAbsentTimer_mS_M_u32	1490046976
CONSANGLECPKSigInvalidCount_Cnt_M_u16	41720

Name	Input Value
CONSANGLECPKSigValidCount_Cnt_M_u16	3237
CONSANGLECPK_Cnt_M_u16	31320
CONSANGLECPK_HwDeg_M_f32	-194.642899
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	31320
CPKVehicleSpeedMsgTimer_mS_M_u32	4272353280
CPKVehicleSpeedValidCount_Cnt_M_u16	61673
CityParkInputConsistentCount_Cnt_M_u16	41915
CityParkInputInvalidCount_Cnt_M_u16	29534
CityParkInputMsgTimer_mS_M_u32	3999400192
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1690525696
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	43078
ComputerRazGCTSigInvalidTimer_mS_M_u32	1570603008
ComputerRazGCTSigValidCount_Cnt_M_u16	19912
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	31258
DMDFCTCPKSigValidCount_Cnt_M_u16	12063
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	45196
DMDRELAXECPKSigValidCount_Cnt_M_u16	36073
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	26637
DateInvalidTimer_mS_M_u32	1544265728
DiagMuxOnAbsentTimer_mS_M_u32	3496718336
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3669381120
ESPNTCEnableTimer_mS_M_u32	4271398912
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	58350
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	89
EffacDefaultDiagTimer_mS_M_u32[1]	898
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	45
ElecIntTimer_mS_M_u32[1]	3976745216
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3879997440
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	45964
EtatMTSigValidCount_Cnt_M_u16	58229
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	17050
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	33223
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	56709
ISDAT4V2BSI552MsgTimer_mS_M_u32	169103360
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	37498
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	14955
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	58229
ISDATBSI3F2MsgTimer_mS_M_u32	2294919168
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	54527
ISDATBSI412MsgLenValidCount_Cnt_M_u16	50080
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	45964
ISDATBSI412MsgTimer_mS_M_u32	2338189312
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	20281
ISDATBSI432MsgLenValidCount_Cnt_M_u16	11058
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	49301
ISDATDIRASentFltAcc_Cnt_M_u16	15721
ISDATDIRASentTimer_mS_M_u32	4272353280
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	23862
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	11895
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	6345
ISDYN2CMMMsgTimer_mS_M_u32	4113719296
ISDYNAASChkSumInvalidCount_Cnt_M_u16	62116
ISDYNAASChkSumValidCount_Cnt_M_u16	22945
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	58150
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	36431
ISDYNAASMsgLenValidCount_Cnt_M_u16	28164
ISDYNAASMsgTimeValidCount_Cnt_M_u16	62116
ISDYNAASMsgTimer_mS_M_u32	957825024
ISDYNABRChkSumInvalidCount_Cnt_M_u16	34593

Name	Input Value
ISDYNABRChkSumValidCount_Cnt_M_u16	27654
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	54739
ISDYNABRMsgCountValidCount_Cnt_M_u16	37392
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	37159
ISDYNABRMsgLenValidCount_Cnt_M_u16	36884
ISDYNABRMsgTimeValidCount_Cnt_M_u16	31320
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	656
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1197
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	58229
ISDYNCMM208MsgTimer_mS_M_u32	443424768
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2475
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1303
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	27605
ISDYNCMM388MsgTimer_mS_M_u32	4161716224
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	21334
ISDYNVOLChkSumValidCount_Cnt_M_u16	59267
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	30072
ISDYNVOLMsgCountValidCount_Cnt_M_u16	38141
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	14271
ISDYNVOLMsgLenValidCount_Cnt_M_u16	8524
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	29429
ISDYNVOLMsgTimer_mS_M_u32	2908323840
IgnOnTimer_mS_M_u32	3427975168
IgnTimeOff_Sec_M_u32	1288035176
ManVehSpd_Kph_M_f32	149.172104
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	133
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	52
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2249175040
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	139
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3647770624
PrevISDATBSI412MsgDLCError_Cnt_M_u08	100
PrevISDATBSI412MsgRxTime_MSec_M_u32	3905552384
PrevISDATBSI432MsgDLCError_Cnt_M_u08	106
PrevISDATBSI432MsgRxTime_MSec_M_u32	114057216
PrevISDATDIRAMsgTxTime_MSec_M_u32	480116736
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	4
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2853163008
PrevISDYNAASMsgDLCError_Cnt_M_u08	42
PrevISDYNAASMsgRxTime_MSec_M_u32	2553774080
PrevISDYNABRMsgDLCError_Cnt_M_u08	208
PrevISDYNABRMsgRxTime_MSec_M_u32	785039360
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	220
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4261707776
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	127
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3917438976
PrevISDYNVOLMsgDLCError_Cnt_M_u08	152
PrevISDYNVOLMsgRxTime_MSec_M_u32	1689190400
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3032215552
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	231.806107
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	40877
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	27106
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	1

Name	Input Value
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	11518
VitesseVehicleBVRampValidCount_Cnt_M_u16	499
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	43451
VitesseVehicleBVSigValidCount_Cnt_M_u16	23384
VitesseVehicleBV_Kph_M_f32	246.104996
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	27605
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	56170
VitesseVehiculeRoues_Kph_M_f32	386.548401
k_AASNTCEnableTimeout_mS_u16	55359
k_AASNodeAbsentDiag_Cnt_str.Threshold	13712
k_AASNodeAbsentDiag_Cnt_str.PStep	47405
k_AASNodeAbsentDiag_Cnt_str.NStep	17977
k_AASNodeAbsentTimeout_mS_u16	35042
k_AASNodeTimeout_mS_u16	13538
k_ABSNodeTimeout_mS_u16	48167
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	6372
k_ANGLEVOLANTSigValidThresh_Cnt_u16	28445
k_AngleVolantInvalidThresh_Cnt_u16	18132
k_AngleVolantValidThresh_Cnt_u16	29534
k_BSI552MsgTimeout_mS_u16	19937
k_BSINTCEnableTimeout_mS_u16	41393
k_BSINodeAbsentDiag_Cnt_str.Threshold	23652
k_BSINodeAbsentDiag_Cnt_str.PStep	35488
k_BSINodeAbsentDiag_Cnt_str.NStep	13693
k_BSINodeAbsentTimeout_mS_u16	46479
k_BSINodeTimeout_mS_u16	49301
k_BattOvHi_Volt_f32	25.9778996
k_BattOvLo_Volt_f32	19.2877007
k_BattUvHi_Volt_f32	18.7465992
k_BattUvLo_Volt_f32	13.2325001
k_CAVNTCEnableTimeout_mS_u16	59188
k_CAVNodeAbsentDiag_Cnt_str.Threshold	33541
k_CAVNodeAbsentDiag_Cnt_str.PStep	32985
k_CAVNodeAbsentDiag_Cnt_str.NStep	56687
k_CAVNodeAbsentTimeout_mS_u16	31418
k_CAVNodeTimeout_mS_u16	24244
k_CMM388MsgTimeout_mS_u16	38914
k_CMM388NTCEnableTimeout_mS_u16	48318
k_CMMNTCEnableTimeout_mS_u16	57586
k_CMMNodeAbsentDiag_Cnt_str.Threshold	182
k_CMMNodeAbsentDiag_Cnt_str.PStep	17272
k_CMMNodeAbsentDiag_Cnt_str.NStep	35782
k_CMMNodeAbsentTimeout_mS_u16	58918
k_CONSANGLECPKMax_HwDeg_f32	728.295776
k_CONSANGLECPKMin_HwDeg_f32	-256.905701
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	63189
k_CONSANGLECPKSigValidThresh_Cnt_u16	42602
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	26184
k_CPKVehicleSpeedValidThresh_Cnt_u16	64690
k_CityParkInputInvalidThresh_Cnt_u16	263
k_CityParkInputValidThresh_Cnt_u16	41915
k_ComputerRazGCTSigValidThresh_Cnt_u16	13888
k_CptTemporelSigValidThresh_Cnt_u16	18097
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	39975
k_DMDFCTCPKSigValidThresh_Cnt_u16	56084
k_DMDFCTCPKValidCount_Cnt_u16	16033
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	6345
k_DMDRELAXECPKSigValidThresh_Cnt_u16	49934
k_DMDRelaxeConsistentThresh_Cnt_u16	44660
k_DateValidThresh_Cnt_u16	56709
k_DefaultVehSpd_Kph_f32	109.898697
k_DiagMuxOnAbsentTimeout_mS_u16	21422
k_EMNodeTimeout_mS_u16	40557
k_ESPNTCEnableTimeout_mS_u16	54296
k_ESPNodeAbsentDiag_Cnt_str.Threshold	40683
k_ESPNodeAbsentDiag_Cnt_str.PStep	12350
k_ESPNodeAbsentDiag_Cnt_str.NStep	26835
k_ESPNodeAbsentTimeout_mS_u16	56238
k_EtatMTSigInvalidThresh_Cnt_u16	57784

Name	Input Value
k_EtatMTSigValidThresh_Cnt_u16	23005
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	41179
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	9891
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	4876
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	47279
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	3680
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	1859
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	29422
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	7335
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	27517
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	58108
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	0
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	27399
k_ISDATDIRASentDiag_Cnt_str.Threshold	6766
k_ISDATDIRASentDiag_Cnt_str.PStep	36118
k_ISDATDIRASentDiag_Cnt_str.NStep	55014
k_ISDATDIRASentTimeout_mS_u16	20701
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	43092
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	16663
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	57572
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	4641
k_ISDYNAASChkSumValidThresh_Cnt_u16	14086
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	57555
k_ISDYNAASMsgCountValidThresh_Cnt_u16	56592
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	34917
k_ISDYNAASMsgLenValidThresh_Cnt_u16	49702
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	37541
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	62597
k_ISDYNABRChkSumValidThresh_Cnt_u16	24050
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	8985
k_ISDYNABRMsgCountValidThresh_Cnt_u16	48950
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	15861
k_ISDYNABRMsgLenValidThresh_Cnt_u16	61166
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	39725
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	52465
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	25488
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	63065
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	33258
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	18631
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	19414
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	49962
k_ISDYNVOLChkSumValidThresh_Cnt_u16	35851
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	52995
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	38986
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	7752
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	9009
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	5595
k_IgnOnTimeout_mS_u16	24806
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	40.2448997
k_PowerCutVehSpdLowThresh_Kph_f32	183.877701
k_PowerCutVehSpdLowTimeout_mS_u16	6763
k_VBattMaxAAS_Volt_f32	1.83720005
k_VBattMaxBSI_Volt_f32	29.8630009
k_VBattMaxCAV_Volt_f32	3.57399988
k_VBattMaxCMM388_Volt_f32	12.7916002
k_VBattMaxCMM_Volt_f32	31.3099995
k_VBattMaxESP_Volt_f32	21.7271996
k_VBattMinAAS_Volt_f32	1.04209995
k_VBattMinBSI_Volt_f32	1.23650002
k_VBattMinCAV_Volt_f32	22.5680008
k_VBattMinCMM388_Volt_f32	14.7659998
k_VBattMinCMM_Volt_f32	28.4442997
k_VBattMinESP_Volt_f32	31.3099995
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	51694
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	35199
k_VitesseVehicleBVRampValidThresh_Cnt_u16	120
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	12931
k_VitesseVehicleBVSigValidThresh_Cnt_u16	21380
k_VitesseVehicleBVSpeedPassThresh_kph_f32	234.781204
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	29020
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	28881
target_Pim_ElecIntData	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Pim_ShutdownTimeData.Time_Sec_u32	1544265728
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	32
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	45066
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3976745216
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	127
target_SrlComInput_Per1_Batt_Volt_f32.value	7.58150005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2363166720
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	199
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.296056688
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4257005568
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	236
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4094091264
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2913009664
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1921720320
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2328182784
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	52
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1045389312
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3576266752
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	48
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	80
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	200
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	96
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	238821376
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	46
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	235
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	97
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4186947584
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	80
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1868161024
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1752432640
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	7
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	17
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	48
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	85
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	130
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	169
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3818819584
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	872
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.650778532
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	883862
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	8.4843998
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	16071

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3976745216	3976745216	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	13712	13712	✔
AASNodeAbsentTimer_mS_M_u32	3976745216	3976745216	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	16665	16665	✔
AngleVolantMsgTimer_mS_M_u32	3976745216	3976745216	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-114.104088	-114.104088	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3324059648	3324059648	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	3976745216	3976745216	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1448972288	1448972288	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	3669381120	3669381120	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3976745216	3976745216	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3976745216	3976745216	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	33541	33541	✔
CAVNodeAbsentTimer_mS_M_u32	3976745216	3976745216	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3976745216	3976745216	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3976745216	3976745216	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1045389312	1045389312	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	31320	31320	✔
CONSANGLECPK_HwDeg_M_f32	-194.642899	-194.642899 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	31320	31320	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4272353280	4272353280	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	61673	61673	✔
CityParkInputConsistentCount_Cnt_M_u16	41915	41915	✔
CityParkInputInvalidCount_Cnt_M_u16	29534	29534	✔
CityParkInputMsgTimer_mS_M_u32	3976745216	3976745216	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3976745216	3976745216	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3976745216	3976745216	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1544265728	1544265728	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3976745216	3976745216	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3669381120	3669381120	✔
ESPNTCEnableTimer_mS_M_u32	3976745216	3976745216	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3976745216	3976745216	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	89	89	✔
EffacDefaultDiagTimer_mS_M_u32[1]	898	898	✔
ElecIntCount_Cnt_M_u08	2	2	✔
ElecIntTimer_mS_M_u32[0]	45	45	✔
ElecIntTimer_mS_M_u32[1]	3976745216	3976745216	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3976745216	3976745216	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	17051	17051	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4257005568	4257005568	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	37498	37498	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2294919168	2294919168	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3976745216	3976745216	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	20282	20282	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1921720320	1921720320	✔
ISDATDIRASentFltAcc_Cnt_M_u16	6766	6766	✔
ISDATDIRASentTimer_mS_M_u32	3976745216	3976745216	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3976745216	3976745216	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3976745216	3976745216	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3976745216	3976745216	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3976745216	3976745216	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3976745216	3976745216	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3976745216	3976745216	✔
IgnOnTimer_mS_M_u32	3427975168	3427975168	✔
IgnTimeOff_Sec_M_u32	1288035176	1288035176	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	29	29	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4257005568	4257005568	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	236	236	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4094091264	4094091264	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	91	91	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2913009664	2913009664	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	178	178	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1921720320	1921720320	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	480116736	480116736	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	52	52	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1045389312	1045389312	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	240	240	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3576266752	3576266752	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	96	96	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	238821376	238821376	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	97	97	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4186947584	4186947584	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	80	80	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1868161024	1868161024	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	158	158	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1752432640	1752432640	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3818819584	3818819584	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	231.806107	231.806107	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	246.104996	246.104996	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	386.548401	386.548401	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-114.104088	-114.104088	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	31320	31320	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1288035176	1288035176	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-194.642899	-194.642899 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	109.898697	109.898697	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0139	0x0139	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0161	0x0161	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.82 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3093230336
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	29271
AASNodeAbsentTimer_mS_M_u32	2644550400
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	63133
ANGLEVOLANTSigValidCount_Cnt_M_u16	16839
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	59928
AngleVolantMsgTimer_mS_M_u32	3093230336
AngleVolantValidCount_Cnt_M_u16	19064
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-16.8014145
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3720045312
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3858490112
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3938849536
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2965099264
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	36624

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	555258624
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	21706
CAVNodeAbsentTimer_mS_M_u32	1445708544
CDD_SrlComVehSpd_Kph_G_f32	31.9302998
CMM388NTCEnableTimer_mS_M_u32	546112256
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1626981120
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	53183
CMMNodeAbsentTimer_mS_M_u32	510513920
CONSANGLECPKSigInvalidCount_Cnt_M_u16	55668
CONSANGLECPKSigValidCount_Cnt_M_u16	48173
CONSANGLECPK_Cnt_M_u16	65300
CONSANGLECPK_HwDeg_M_f32	297.022614
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	65300
CPKVehicleSpeedMsgTimer_mS_M_u32	1332343552
CPKVehicleSpeedValidCount_Cnt_M_u16	44169
CityParkInputConsistentCount_Cnt_M_u16	64172
CityParkInputInvalidCount_Cnt_M_u16	10434
CityParkInputMsgTimer_mS_M_u32	4257005568
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1523884800
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	12427
ComputerRazGCTSigInvalidTimer_mS_M_u32	12993280
ComputerRazGCTSigValidCount_Cnt_M_u16	28805
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	1166
DMDFCTCPKSigValidCount_Cnt_M_u16	25919
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	20919
DMDRELAXECPKSigValidCount_Cnt_M_u16	40033
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	7733
DateInvalidTimer_mS_M_u32	3858490112
DiagMuxOnAbsentTimer_mS_M_u32	3709580032
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2965099264
ESPNTCEnableTimer_mS_M_u32	559260416
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	52372
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	4
EffacDefaultDiagTimer_mS_M_u32[1]	748
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	66
ElecIntTimer_mS_M_u32[1]	79
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	4061303552
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	31481
EtatMTSigValidCount_Cnt_M_u16	64254
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	654
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	25799
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	29197
ISDAT4V2BSI552MsgTimer_mS_M_u32	446812928
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	4014
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	18331
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	64254
ISDATBSI3F2MsgTimer_mS_M_u32	2885792512
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	43297
ISDATBSI412MsgLenValidCount_Cnt_M_u16	52478
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	31481
ISDATBSI412MsgTimer_mS_M_u32	1162146560
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	19187
ISDATBSI432MsgLenValidCount_Cnt_M_u16	1736
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	59935
ISDATDIRASentFltAcc_Cnt_M_u16	50083
ISDATDIRASentTimer_mS_M_u32	1332343552

Name	Input Value
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	20090
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	19064
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	42113
ISDYN2CMMMsgTimer_mS_M_u32	629646080
ISDYNAASChkSumInvalidCount_Cnt_M_u16	18801
ISDYNAASChkSumValidCount_Cnt_M_u16	29754
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	43115
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	59633
ISDYNAASMsgLenValidCount_Cnt_M_u16	35218
ISDYNAASMsgTimeValidCount_Cnt_M_u16	18801
ISDYNAASMsgTimer_mS_M_u32	2237203200
ISDYNABRChkSumInvalidCount_Cnt_M_u16	6010
ISDYNABRChkSumValidCount_Cnt_M_u16	26764
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	7140
ISDYNABRMsgCountValidCount_Cnt_M_u16	18157
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	35559
ISDYNABRMsgLenValidCount_Cnt_M_u16	44512
ISDYNABRMsgTimeValidCount_Cnt_M_u16	65300
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	657
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1199
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	64254
ISDYNCMM208MsgTimer_mS_M_u32	1423205120
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2479
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1305
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	35422
ISDYNCMM388MsgTimer_mS_M_u32	2255651584
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	49242
ISDYNVOLChkSumValidCount_Cnt_M_u16	9107
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	2676
ISDYNVOLMsgCountValidCount_Cnt_M_u16	11173
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	21793
ISDYNVOLMsgLenValidCount_Cnt_M_u16	14394
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	53183
ISDYNVOLMsgTimer_mS_M_u32	26362624
IgnOnTimer_mS_M_u32	430342912
IgnTimeOff_Sec_M_u32	3101764045
ManVehSpd_Kph_M_f32	484.102295
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	135
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	85
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1278194432
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	230
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1570312960
PrevISDATBSI412MsgDLCError_Cnt_M_u08	15
PrevISDATBSI412MsgRxTime_MSec_M_u32	2973811456
PrevISDATBSI432MsgDLCError_Cnt_M_u08	238
PrevISDATBSI432MsgRxTime_MSec_M_u32	3636044544
PrevISDATDIRAMsgTxTime_MSec_M_u32	1707393792
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	217
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2293191424
PrevISDYNAASMsgDLCError_Cnt_M_u08	11
PrevISDYNAASMsgRxTime_MSec_M_u32	955794176
PrevISDYNABRMsgDLCError_Cnt_M_u08	243
PrevISDYNABRMsgRxTime_MSec_M_u32	3527312128
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	112
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2073117440
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	3
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3164644096
PrevISDYNVOLMsgDLCError_Cnt_M_u08	138
PrevISDYNVOLMsgRxTime_MSec_M_u32	294765312
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3240817408
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	565.011292

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	44247
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	36344
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	35044
VitesseVehicleBVRampValidCount_Cnt_M_u16	18885
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	57898
VitesseVehicleBVSigValidCount_Cnt_M_u16	44308
VitesseVehicleBV_Kph_M_f32	519.550903
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	35422
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	64351
VitesseVehiculeRoues_Kph_M_f32	645.597778
k_AASNTCEnableTimeout_mS_u16	16735
k_AASNodeAbsentDiag_Cnt_str.Threshold	3361
k_AASNodeAbsentDiag_Cnt_str.PStep	37698
k_AASNodeAbsentDiag_Cnt_str.NStep	19798
k_AASNodeAbsentTimeout_mS_u16	42807
k_AASNodeTimeout_mS_u16	11512
k_ABSNodeTimeout_mS_u16	45671
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	23026
k_ANGLEVOLANTSigValidThresh_Cnt_u16	42759
k_AngleVolantInvalidThresh_Cnt_u16	48098
k_AngleVolantValidThresh_Cnt_u16	10434
k_BSI552MsgTimeout_mS_u16	16378
k_BSINTCEnableTimeout_mS_u16	13195
k_BSINodeAbsentDiag_Cnt_str.Threshold	23692
k_BSINodeAbsentDiag_Cnt_str.PStep	35471
k_BSINodeAbsentDiag_Cnt_str.NStep	13716
k_BSINodeAbsentTimeout_mS_u16	27824
k_BSINodeTimeout_mS_u16	59935
k_BattOvHi_Volt_f32	5.93410015
k_BattOvLo_Volt_f32	24.0687008
k_BattUvHi_Volt_f32	5.34770012
k_BattUvLo_Volt_f32	11.7018995
k_CAVNTCEnableTimeout_mS_u16	42304
k_CAVNodeAbsentDiag_Cnt_str.Threshold	55130
k_CAVNodeAbsentDiag_Cnt_str.PStep	21012
k_CAVNodeAbsentDiag_Cnt_str.NStep	9933
k_CAVNodeAbsentTimeout_mS_u16	36784
k_CAVNodeTimeout_mS_u16	38464
k_CMM388MsgTimeout_mS_u16	20823
k_CMM388NTCEnableTimeout_mS_u16	54051
k_CMMNTCEnableTimeout_mS_u16	1094
k_CMMNodeAbsentDiag_Cnt_str.Threshold	31629
k_CMMNodeAbsentDiag_Cnt_str.PStep	42306
k_CMMNodeAbsentDiag_Cnt_str.NStep	1680
k_CMMNodeAbsentTimeout_mS_u16	52011
k_CONSANGLECPKMax_HwDeg_f32	711.433228
k_CONSANGLECPKMin_HwDeg_f32	-722.849792
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	59742
k_CONSANGLECPKSigValidThresh_Cnt_u16	39519
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	45254
k_CPKVehicleSpeedValidThresh_Cnt_u16	48648
k_CityParkInputInvalidThresh_Cnt_u16	49608
k_CityParkInputValidThresh_Cnt_u16	64172
k_ComputerRazGCTSigValidThresh_Cnt_u16	48220
k_CptTemporelSigValidThresh_Cnt_u16	47817
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	27111
k_DMDFCTCPKSigValidThresh_Cnt_u16	52448
k_DMDFCTCPKValidCount_Cnt_u16	15224

Name	Input Value
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	42113
k_DMDRELAXECPKSigValidThresh_Cnt_u16	9586
k_DMDRelaxeConsistentThresh_Cnt_u16	31552
k_DateValidThresh_Cnt_u16	29197
k_DefaultVehSpd_Kph_f32	102.174103
k_DiagMuxOnAbsentTimeout_mS_u16	19218
k_EMNodeTimeout_mS_u16	64277
k_ESPNTCEnableTimeout_mS_u16	31638
k_ESPNodeAbsentDiag_Cnt_str.Threshold	8783
k_ESPNodeAbsentDiag_Cnt_str.PStep	13648
k_ESPNodeAbsentDiag_Cnt_str.NStep	62151
k_ESPNodeAbsentTimeout_mS_u16	2707
k_EtatMTSigInvalidThresh_Cnt_u16	9141
k_EtatMTSigValidThresh_Cnt_u16	47879
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	3341
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	2930
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	12473
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	45327
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	57276
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	8789
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	62420
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	18025
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	1575
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	21800
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	65535
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	22536
k_ISDATDIRASentDiag_Cnt_str.Threshold	16286
k_ISDATDIRASentDiag_Cnt_str.PStep	26591
k_ISDATDIRASentDiag_Cnt_str.NStep	8422
k_ISDATDIRASentTimeout_mS_u16	43590
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	5153
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	59928
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	34098
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	30330
k_ISDYNAASChkSumValidThresh_Cnt_u16	1932
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	64228
k_ISDYNAASMsgCountValidThresh_Cnt_u16	26093
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	9134
k_ISDYNAASMsgLenValidThresh_Cnt_u16	38188
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	23663
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	22733
k_ISDYNABRChkSumValidThresh_Cnt_u16	15430
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	28176
k_ISDYNABRMsgCountValidThresh_Cnt_u16	31098
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	28351
k_ISDYNABRMsgLenValidThresh_Cnt_u16	43924
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	33173
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	13579
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	33134
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	33939
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	54685
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	24775
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	32602
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	19104
k_ISDYNVOLChkSumValidThresh_Cnt_u16	57277
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	40789
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	62400
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	10949
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	11210
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	41227
k_IgnOnTimeout_mS_u16	24940
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	225.635498
k_PowerCutVehSpdLowThresh_Kph_f32	58.7370987
k_PowerCutVehSpdLowTimeout_mS_u16	10971
k_VBattMaxAAS_Volt_f32	1.94819999
k_VBattMaxBSI_Volt_f32	29.8630009
k_VBattMaxCAV_Volt_f32	17.4594994
k_VBattMaxCMM388_Volt_f32	8.17580032
k_VBattMaxCMM_Volt_f32	32
k_VBattMaxESP_Volt_f32	7.98799992
k_VBattMinAAS_Volt_f32	29.0513992
k_VBattMinBSI_Volt_f32	7.98799992

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinCAV_Volt_f32	20.2577991
k_VBattMinCMM388_Volt_f32	24.9080009
k_VBattMinCMM_Volt_f32	24.8327999
k_VBattMinESP_Volt_f32	32
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	38739
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	2144
k_VitesseVehicleBVRampValidThresh_Cnt_u16	26996
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	17043
k_VitesseVehicleBVSigValidThresh_Cnt_u16	20305
k_VitesseVehicleBVSpeedPassThresh_kph_f32	372.131409
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	46026
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	62763
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3858490112
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	223
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	54395
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1057607680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	3
target_SrlComInput_Per1_Batt_Volt_f32.value	29.6144009
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	491623168
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	124
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.443245023
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2909307648
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	453649152
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2126234368
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	8217344
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3360621312
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4264600320
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3391243008
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	52
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	121
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	122
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	145
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	172
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	829055744
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	38
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	130
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	155
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3320808192
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	65
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3037799168

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1514324736
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	89
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	114
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	140
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	158
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2265125632
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1073
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.280810475
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	389365
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	154.167007
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	46985

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1057607680	1057607680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1057607680	1057607680	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	59928	59928	✔
AngleVolantMsgTimer_mS_M_u32	1057607680	1057607680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-16.8014145	-16.8014145	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3720045312	3720045312	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	3858490112	3858490112	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	3938849536	3938849536	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	2965099264	2965099264	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1057607680	1057607680	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1057607680	1057607680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	55130	55130	✔
CAVNodeAbsentTimer_mS_M_u32	1057607680	1057607680	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1057607680	1057607680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1626981120	1626981120	✔
CMMNTCsEnabled_Cnt_M_lgc	1	1	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1057607680	1057607680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	65300	65300	✔
CONSANGLECPK_HwDeg_M_f32	297.022614	297.022614 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	65300	65300	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1332343552	1332343552	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	44169	44169	✔
CityParkInputConsistentCount_Cnt_M_u16	64172	64172	✔
CityParkInputInvalidCount_Cnt_M_u16	10436	10436	✔
CityParkInputMsgTimer_mS_M_u32	1057607680	1057607680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1057607680	1057607680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ComputerRazGCTSigInvalidTimer_mS_M_u32	1057607680	1057607680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3858490112	3858490112	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1057607680	1057607680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1057607680	1057607680	✔
ESPNTCEnableTimer_mS_M_u32	1057607680	1057607680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	8783	8783	✔
ESPNodeAbsentTimer_mS_M_u32	1057607680	1057607680	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4	4	✔
EffacDefaultDiagTimer_mS_M_u32[1]	748	748	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	1057607680	1057607680	✔
ElecIntTimer_mS_M_u32[1]	79	79	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1057607680	1057607680	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	31481	31481	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	655	655	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2909307648	2909307648	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	4015	4015	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	453649152	453649152	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	43298	43298	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2126234368	2126234368	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	19188	19188	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	8217344	8217344	✔
ISDATDIRASentFltAcc_Cnt_M_u16	16286	16286	✔
ISDATDIRASentTimer_mS_M_u32	1057607680	1057607680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	20090	20090	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4264600320	4264600320	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1057607680	1057607680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1057607680	1057607680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	658	658	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3320808192	3320808192	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1057607680	1057607680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1057607680	1057607680	✔
IgnOnTimer_mS_M_u32	1057607680	1057607680	✔
IgnTimeOff_Sec_M_u32	3101764045	3101764045	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	30	30	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2909307648	2909307648	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	95	95	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	453649152	453649152	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	3	3	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2126234368	2126234368	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	49	49	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	8217344	8217344	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1707393792	1707393792	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	202	202	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4264600320	4264600320	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	134	134	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3391243008	3391243008	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	829055744	829055744	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3320808192	3320808192	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	65	65	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3037799168	3037799168	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	70	70	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1514324736	1514324736	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2265125632	2265125632	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	565.011292	565.011292	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	519.550903	519.550903	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	645.597778	645.597778	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-16.8014145	-16.8014145	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	65300	65300	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3101764045	3101764045	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	297.022614	297.022614 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	102.174103	102.174103	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.83 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4195215872
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	20004
AASNodeAbsentTimer_mS_M_u32	2903038464
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	64336
ANGLEVOLANTSigValidCount_Cnt_M_u16	31381
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	10977
AngleVolantMsgTimer_mS_M_u32	4195215872
AngleVolantValidCount_Cnt_M_u16	36930
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-310.890503
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3350764032
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1358371328
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1733855744
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	477579776
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	48631
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	778111488
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	56139
CAVNodeAbsentTimer_mS_M_u32	401046016
CDD_SrlComVehSpd_Kph_G_f32	469.320496
CMM388NTCEnableTimer_mS_M_u32	3452156416
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2944236032
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	2093
CMMNodeAbsentTimer_mS_M_u32	459360768
CONSANGLECPKSigInvalidCount_Cnt_M_u16	7628
CONSANGLECPKSigValidCount_Cnt_M_u16	5729
CONSANGLECPK_Cnt_M_u16	43436
CONSANGLECPK_HwDeg_M_f32	-112.122597
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43436
CPKVehicleSpeedMsgTimer_mS_M_u32	552397312
CPKVehicleSpeedValidCount_Cnt_M_u16	3542
CityParkInputConsistentCount_Cnt_M_u16	20390
CityParkInputInvalidCount_Cnt_M_u16	61027
CityParkInputMsgTimer_mS_M_u32	2909307648
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1164761600
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	58248
ComputerRazGCTSigInvalidTimer_mS_M_u32	2719480320
ComputerRazGCTSigValidCount_Cnt_M_u16	37403
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	35583
DMDFCTCPKSigValidCount_Cnt_M_u16	59820
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	53762
DMDRELAXECPKSigValidCount_Cnt_M_u16	21191
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	37769
DateInvalidTimer_mS_M_u32	1358371328
DiagMuxOnAbsentTimer_mS_M_u32	1859627520
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	477579776
ESPNTCEnableTimer_mS_M_u32	904518144
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	8814
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	45
EffacDefaultDiagTimer_mS_M_u32[1]	98
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	101

Name	Input Value
ElecIntTimer_mS_M_u32[1]	834753280
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	594741760
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	49022
EtatMTSigValidCount_Cnt_M_u16	4143
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	35454
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1171
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	31554
ISDAT4V2BSI552MsgTimer_mS_M_u32	4140124672
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	27872
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	13784
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	4143
ISDATBSI3F2MsgTimer_mS_M_u32	438675968
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	32134
ISDATBSI412MsgLenValidCount_Cnt_M_u16	17071
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	49022
ISDATBSI412MsgTimer_mS_M_u32	1801185792
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	26257
ISDATBSI432MsgLenValidCount_Cnt_M_u16	17362
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	44876
ISDATDIRASentFltAcc_Cnt_M_u16	12992
ISDATDIRASentTimer_mS_M_u32	552397312
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	54138
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	36930
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	14118
ISDYN2CMMMsgTimer_mS_M_u32	1901320704
ISDYNAASChkSumInvalidCount_Cnt_M_u16	45270
ISDYNAASChkSumValidCount_Cnt_M_u16	4410
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	617
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	31446
ISDYNAASMsgLenValidCount_Cnt_M_u16	55730
ISDYNAASMsgTimeValidCount_Cnt_M_u16	45270
ISDYNAASMsgTimer_mS_M_u32	3479157248
ISDYNABRChkSumInvalidCount_Cnt_M_u16	42042
ISDYNABRChkSumValidCount_Cnt_M_u16	45510
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	50557
ISDYNABRMsgCountValidCount_Cnt_M_u16	9505
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	38259
ISDYNABRMsgLenValidCount_Cnt_M_u16	52552
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43436
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	658
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1201
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	4143
ISDYNCMM208MsgTimer_mS_M_u32	107846144
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2483
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1307
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	59536
ISDYNCMM388MsgTimer_mS_M_u32	303249920
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	33050
ISDYNVOLChkSumValidCount_Cnt_M_u16	63535
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	37197
ISDYNVOLMsgCountValidCount_Cnt_M_u16	44666
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	64711
ISDYNVOLMsgLenValidCount_Cnt_M_u16	29755
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	2093
ISDYNVOLMsgTimer_mS_M_u32	3484678656
IgnOnTimer_mS_M_u32	678902272
IgnTimeOff_Sec_M_u32	1465283045
ManVehSpd_Kph_M_f32	309.471191
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	137
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	13

Name	Input Value
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	26
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1906027008
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	156
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	450857472
PrevISDATBSI412MsgDLCError_Cnt_M_u08	14
PrevISDATBSI412MsgRxTime_MSec_M_u32	2594732544
PrevISDATBSI432MsgDLCError_Cnt_M_u08	156
PrevISDATBSI432MsgRxTime_MSec_M_u32	2680019456
PrevISDATDIRAMsgTxTime_MSec_M_u32	2367453696
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	174
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3265055232
PrevISDYNAASMsgDLCError_Cnt_M_u08	42
PrevISDYNAASMsgRxTime_MSec_M_u32	1099037184
PrevISDYNABRMsgDLCError_Cnt_M_u08	225
PrevISDYNABRMsgRxTime_MSec_M_u32	1588541952
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	141
PrevISDYNCMM208MsgRxTime_MSec_M_u32	498530816
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	96
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1342757376
PrevISDYNVOLMsgDLCError_Cnt_M_u08	87
PrevISDYNVOLMsgRxTime_MSec_M_u32	4256528896
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	262793728
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	392.991608
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	18212
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	58496
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	9981
VitesseVehicleBVRampValidCount_Cnt_M_u16	9497
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	44201
VitesseVehicleBVSigValidCount_Cnt_M_u16	44206
VitesseVehicleBV_Kph_M_f32	537.064209
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	59536
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	22092
VitesseVehiculeRoues_Kph_M_f32	485.811401
k_AASNTCEnableTimeout_mS_u16	52939
k_AASNodeAbsentDiag_Cnt_str.Threshold	36970
k_AASNodeAbsentDiag_Cnt_str.PStep	43806
k_AASNodeAbsentDiag_Cnt_str.NStep	14650
k_AASNodeAbsentTimeout_mS_u16	13829
k_AASNodeTimeout_mS_u16	1920
k_ABSNodeTimeout_mS_u16	9588
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	62868
k_ANGLEVOLANTSigValidThresh_Cnt_u16	7957
k_AngleVolantInvalidThresh_Cnt_u16	3204
k_AngleVolantValidThresh_Cnt_u16	61027
k_BSI552MsgTimeout_mS_u16	46203
k_BSINTCEnableTimeout_mS_u16	3273
k_BSINodeAbsentDiag_Cnt_str.Threshold	23732
k_BSINodeAbsentDiag_Cnt_str.PStep	35454
k_BSINodeAbsentDiag_Cnt_str.NStep	13739
k_BSINodeAbsentTimeout_mS_u16	793
k_BSINodeTimeout_mS_u16	44876
k_BattOvHi_Volt_f32	21.2252998
k_BattOvLo_Volt_f32	5.12939978
k_BattUvHi_Volt_f32	24.8251991
k_BattUvLo_Volt_f32	3.82660007
k_CAVNTCEnableTimeout_mS_u16	61673
k_CAVNodeAbsentDiag_Cnt_str.Threshold	31221

Name	Input Value
k_CAVNodeAbsentDiag_Cnt_str.PStep	36127
k_CAVNodeAbsentDiag_Cnt_str.NStep	12175
k_CAVNodeAbsentTimeout_mS_u16	17049
k_CAVNodeTimeout_mS_u16	5992
k_CMM388MsgTimeout_mS_u16	45348
k_CMM388NTCEnableTimeout_mS_u16	23488
k_CMMNTCEnableTimeout_mS_u16	61208
k_CMMNodeAbsentDiag_Cnt_str.Threshold	21893
k_CMMNodeAbsentDiag_Cnt_str.PStep	57983
k_CMMNodeAbsentDiag_Cnt_str.NStep	61422
k_CMMNodeAbsentTimeout_mS_u16	5864
k_CONSANGLECPKMax_HwDeg_f32	65.8231964
k_CONSANGLECPKMin_HwDeg_f32	-408.66449
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	52112
k_CONSANGLECPKSigValidThresh_Cnt_u16	31052
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	13334
k_CPKVehicleSpeedValidThresh_Cnt_u16	39633
k_CityParkInputInvalidThresh_Cnt_u16	23888
k_CityParkInputValidThresh_Cnt_u16	20390
k_ComputerRazGCTSigValidThresh_Cnt_u16	40662
k_CptTemporelSigValidThresh_Cnt_u16	5198
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	63603
k_DMDFCTCPKSigValidThresh_Cnt_u16	28744
k_DMDFCTCPKValidCount_Cnt_u16	22719
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	14118
k_DMDRELAXECPKSigValidThresh_Cnt_u16	13587
k_DMDRelaxeConsistentThresh_Cnt_u16	60329
k_DateValidThresh_Cnt_u16	31554
k_DefaultVehSpd_Kph_f32	175.144699
k_DiagMuxOnAbsentTimeout_mS_u16	15794
k_EMNodeTimeout_mS_u16	31977
k_ESPNTCEnableTimeout_mS_u16	38631
k_ESPNodeAbsentDiag_Cnt_str.Threshold	23840
k_ESPNodeAbsentDiag_Cnt_str.PStep	44853
k_ESPNodeAbsentDiag_Cnt_str.NStep	8486
k_ESPNodeAbsentTimeout_mS_u16	63664
k_EtatMTSigInvalidThresh_Cnt_u16	11145
k_EtatMTSigValidThresh_Cnt_u16	26197
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	64321
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	20689
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	8575
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	19645
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	12661
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	57834
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	12270
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	18671
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	1269
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	63344
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	37005
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	7632
k_ISDATDIRASentDiag_Cnt_str.Threshold	46508
k_ISDATDIRASentDiag_Cnt_str.PStep	40001
k_ISDATDIRASentDiag_Cnt_str.NStep	36291
k_ISDATDIRASentTimeout_mS_u16	7126
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	36229
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	10977
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	59923
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	34618
k_ISDYNAASChkSumValidThresh_Cnt_u16	54470
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	10365
k_ISDYNAASMsgCountValidThresh_Cnt_u16	51233
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	20382
k_ISDYNAASMsgLenValidThresh_Cnt_u16	40676
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	40669
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	17345
k_ISDYNABRChkSumValidThresh_Cnt_u16	14870
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	8439
k_ISDYNABRMsgCountValidThresh_Cnt_u16	24444
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	11053
k_ISDYNABRMsgLenValidThresh_Cnt_u16	34158
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	29483
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	32392
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	26783

Name	Input Value
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	11439
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	24144
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	7573
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	19099
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	21769
k_ISDYNVOLChkSumValidThresh_Cnt_u16	50802
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	60971
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	57386
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	57370
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	44491
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	26184
k_IgnOnTimeout_mS_u16	16549
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	61.2603989
k_PowerCutVehSpdLowThresh_Kph_f32	25.9556999
k_PowerCutVehSpdLowTimeout_mS_u16	599
k_VBattMaxAAS_Volt_f32	2.87800002
k_VBattMaxBSI_Volt_f32	29.8630009
k_VBattMaxCAV_Volt_f32	26.1791992
k_VBattMaxCMM388_Volt_f32	31.9228992
k_VBattMaxCMM_Volt_f32	14.7038002
k_VBattMaxESP_Volt_f32	18.6287003
k_VBattMinAAS_Volt_f32	12.4153004
k_VBattMinBSI_Volt_f32	2.56229997
k_VBattMinCAV_Volt_f32	3.44350004
k_VBattMinCMM388_Volt_f32	12.7603998
k_VBattMinCMM_Volt_f32	22.1060009
k_VBattMinESP_Volt_f32	14.7038002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	19439
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	59784
k_VitesseVehicleBVRampValidThresh_Cnt_u16	29773
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	39727
k_VitesseVehicleBVSigValidThresh_Cnt_u16	9655
k_VitesseVehicleBVSpeedPassThresh_kph_f32	210.815201
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	48715
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	15079
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1358371328
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	238
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	46597
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	834753280
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	96
target_SrlComInput_Per1_Batt_Volt_f32.value	8.24009991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1304562176
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	0
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.938730538
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4113644032
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3133954560
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	160
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3728177664
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3883047424
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1585297920
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	85
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3411597824

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	80
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3053713920
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	85
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	89
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	199
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	211
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1219205632
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	27
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	45
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	57
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	97
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	188
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	79
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2275162624
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3367459328
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	179
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	664959488
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	55
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	229
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	247
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3332475392
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2666
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.147103027
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	393701
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	7.91590023
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	28430

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	834753280	834753280	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	834753280	834753280	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	834753280	834753280	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-310.890503	-310.890503	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3350764032	3350764032	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	834753280	834753280	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1733855744	1733855744	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	477579776	477579776	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	834753280	834753280	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	834753280	834753280	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CAVNodeAbsentFltAcc_Cnt_M_u16	31221	31221	✔
CAVNodeAbsentTimer_mS_M_u32	834753280	834753280	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	834753280	834753280	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	834753280	834753280	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	834753280	834753280	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	43436	43436	✔
CONSANGLECPK_HwDeg_M_f32	-112.122597	-112.122597 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	834753280	834753280	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	834753280	834753280	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	834753280	834753280	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	834753280	834753280	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	834753280	834753280	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	834753280	834753280	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	834753280	834753280	✔
ESPNTCEnableTimer_mS_M_u32	834753280	834753280	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	23840	23840	✔
ESPNodeAbsentTimer_mS_M_u32	834753280	834753280	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	45	45	✔
EffacDefaultDiagTimer_mS_M_u32[1]	98	98	✔
ElecIntCount_Cnt_M_u08	2	2	✔
ElecIntTimer_mS_M_u32[0]	101	101	✔
ElecIntTimer_mS_M_u32[1]	834753280	834753280	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	834753280	834753280	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4113644032	4113644032	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	834753280	834753280	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	834753280	834753280	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3883047424	3883047424	✔
ISDATDIRASentFltAcc_Cnt_M_u16	46508	46508	✔
ISDATDIRASentTimer_mS_M_u32	834753280	834753280	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	834753280	834753280	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	834753280	834753280	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	834753280	834753280	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	834753280	834753280	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	834753280	834753280	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	834753280	834753280	✔
IgnOnTimer_mS_M_u32	834753280	834753280	✔
IgnTimeOff_Sec_M_u32	1465283045	1465283045	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	51	51	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4113644032	4113644032	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	92	92	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3133954560	3133954560	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	160	160	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3728177664	3728177664	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	133	133	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3883047424	3883047424	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2367453696	2367453696	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	85	85	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3411597824	3411597824	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	80	80	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3053713920	3053713920	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	143	143	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1219205632	1219205632	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	79	79	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2275162624	2275162624	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3367459328	3367459328	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	179	179	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	664959488	664959488	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3332475392	3332475392	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	392.991608	392.991608	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	537.064209	537.064209	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	485.811401	485.811401	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-310.890503	-310.890503	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	43436	43436	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1465283045	1465283045	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-112.122597	-112.122597 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	175.144699	175.144699	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0139	0x0139	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0161	0x0161	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.84 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3382510848
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	18265
AASNodeAbsentTimer_mS_M_u32	2288792832
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	37332
ANGLEVOLANTSigValidCount_Cnt_M_u16	61894
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	58658
AngleVolantMsgTimer_mS_M_u32	3382510848
AngleVolantValidCount_Cnt_M_u16	8575
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-718.758362
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2807887104
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	631338240
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1950164224
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1071703296
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	42463
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3777209600
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	613
CAVNodeAbsentTimer_mS_M_u32	2320520448
CDD_SrlComVehSpd_Kph_G_f32	263.722107
CMM388NTCEnableTimer_mS_M_u32	700159232
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2609796352

Name	Input Value
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	41597
CMMNodeAbsentTimer_mS_M_u32	1797448960
CONSANGLECPKSigInvalidCount_Cnt_M_u16	51552
CONSANGLECPKSigValidCount_Cnt_M_u16	64867
CONSANGLECPK_Cnt_M_u16	12162
CONSANGLECPK_HwDeg_M_f32	-228.553207
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	12162
CPKVehicleSpeedMsgTimer_mS_M_u32	2432697600
CPKVehicleSpeedValidCount_Cnt_M_u16	56683
CityParkInputConsistentCount_Cnt_M_u16	29523
CityParkInputInvalidCount_Cnt_M_u16	7195
CityParkInputMsgTimer_mS_M_u32	4113644032
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1329607936
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	5933
ComputerRazGCTSigInvalidTimer_mS_M_u32	1304352000
ComputerRazGCTSigValidCount_Cnt_M_u16	49140
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	46663
DMDFCTCPKSigValidCount_Cnt_M_u16	6146
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	21950
DMDRELAXECPKSigValidCount_Cnt_M_u16	45360
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	39977
DateInvalidTimer_mS_M_u32	631338240
DiagMuxOnAbsentTimer_mS_M_u32	3258959104
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1071703296
ESPNTCEnableTimer_mS_M_u32	2982753536
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	8572
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	66
EffacDefaultDiagTimer_mS_M_u32[1]	78
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	99
ElecIntTimer_mS_M_u32[1]	1000
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3387794688
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	20873
EtatMTSigValidCount_Cnt_M_u16	60728
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	52042
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	31437
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	15168
ISDAT4V2BSI552MsgTimer_mS_M_u32	1761010944
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1765
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	22972
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	60728
ISDATBSI3F2MsgTimer_mS_M_u32	2018886912
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	15858
ISDATBSI412MsgLenValidCount_Cnt_M_u16	23609
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	20873
ISDATBSI412MsgTimer_mS_M_u32	766706944
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	5969
ISDATBSI432MsgLenValidCount_Cnt_M_u16	19792
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	51810
ISDATDIRASentFltAcc_Cnt_M_u16	4102
ISDATDIRASentTimer_mS_M_u32	2432697600
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	27160
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	8575
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	3538
ISDYN2CMMMsgTimer_mS_M_u32	663434496
ISDYNAASChkSumInvalidCount_Cnt_M_u16	26435
ISDYNAASChkSumValidCount_Cnt_M_u16	41942
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	9994
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	4036

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNAASMsgLenValidCount_Cnt_M_u16	12527
ISDYNAASMsgTimeValidCount_Cnt_M_u16	26435
ISDYNAASMsgTimer_mS_M_u32	2498204928
ISDYNABRChkSumInvalidCount_Cnt_M_u16	29847
ISDYNABRChkSumValidCount_Cnt_M_u16	18866
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	34126
ISDYNABRMsgCountValidCount_Cnt_M_u16	50209
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	48747
ISDYNABRMsgLenValidCount_Cnt_M_u16	13486
ISDYNABRMsgTimeValidCount_Cnt_M_u16	12162
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	659
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1203
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	60728
ISDYNCMM208MsgTimer_mS_M_u32	4282250496
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2487
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1309
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	53397
ISDYNCMM388MsgTimer_mS_M_u32	4207744256
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	22390
ISDYNVOLChkSumValidCount_Cnt_M_u16	4089
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	23389
ISDYNVOLMsgCountValidCount_Cnt_M_u16	33176
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	13937
ISDYNVOLMsgLenValidCount_Cnt_M_u16	28115
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	41597
ISDYNVOLMsgTimer_mS_M_u32	887805184
IgnOnTimer_mS_M_u32	1201739008
IgnTimeOff_Sec_M_u32	1928094225
ManVehSpd_Kph_M_f32	434.969696
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	139
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	126
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3388196096
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	87
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	900211968
PrevISDATBSI412MsgDLCError_Cnt_M_u08	63
PrevISDATBSI412MsgRxTime_MSec_M_u32	1175278848
PrevISDATBSI432MsgDLCError_Cnt_M_u08	18
PrevISDATBSI432MsgRxTime_MSec_M_u32	3293394176
PrevISDATDIRAMsgTxTime_MSec_M_u32	1051809024
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	103
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3278923008
PrevISDYNAASMsgDLCError_Cnt_M_u08	185
PrevISDYNAASMsgRxTime_MSec_M_u32	2541802752
PrevISDYNABRMsgDLCError_Cnt_M_u08	67
PrevISDYNABRMsgRxTime_MSec_M_u32	2230916352
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	225
PrevISDYNCMM208MsgRxTime_MSec_M_u32	383898880
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	190
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2674668800
PrevISDYNVOLMsgDLCError_Cnt_M_u08	52
PrevISDYNVOLMsgRxTime_MSec_M_u32	2431014144
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4173923584
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	518.34729
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	25306

Name	Input Value
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	51333
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	26447
VitesseVehicleBVRampValidCount_Cnt_M_u16	43706
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	8649
VitesseVehicleBVSigValidCount_Cnt_M_u16	65403
VitesseVehicleBV_Kph_M_f32	63.0550003
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	53397
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	17695
VitesseVehiculeRoues_Kph_M_f32	548.828979
k_AASNTCEnableTimeout_mS_u16	64549
k_AASNodeAbsentDiag_Cnt_str.Threshold	55450
k_AASNodeAbsentDiag_Cnt_str.PStep	57654
k_AASNodeAbsentDiag_Cnt_str.NStep	25052
k_AASNodeAbsentTimeout_mS_u16	64566
k_AASNodeTimeout_mS_u16	24453
k_ABSNodeTimeout_mS_u16	64232
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	13896
k_ANGLEVOLANTSigValidThresh_Cnt_u16	34695
k_AngleVolantInvalidThresh_Cnt_u16	15162
k_AngleVolantValidThresh_Cnt_u16	7195
k_BSI552MsgTimeout_mS_u16	42642
k_BSINTCEnableTimeout_mS_u16	1193
k_BSINodeAbsentDiag_Cnt_str.Threshold	23772
k_BSINodeAbsentDiag_Cnt_str.PStep	35437
k_BSINodeAbsentDiag_Cnt_str.NStep	13762
k_BSINodeAbsentTimeout_mS_u16	15482
k_BSINodeTimeout_mS_u16	51810
k_BattOvHi_Volt_f32	18.4659996
k_BattOvLo_Volt_f32	16.8295002
k_BattUvHi_Volt_f32	2.14389992
k_BattUvLo_Volt_f32	5.94789982
k_CAVNTCEnableTimeout_mS_u16	44169
k_CAVNodeAbsentDiag_Cnt_str.Threshold	9041
k_CAVNodeAbsentDiag_Cnt_str.PStep	49098
k_CAVNodeAbsentDiag_Cnt_str.NStep	54965
k_CAVNodeAbsentTimeout_mS_u16	33915
k_CAVNodeTimeout_mS_u16	19596
k_CMM388MsgTimeout_mS_u16	7769
k_CMM388NTCEnableTimeout_mS_u16	36485
k_CMMNTCEnableTimeout_mS_u16	24637
k_CMMNodeAbsentDiag_Cnt_str.Threshold	55339
k_CMMNodeAbsentDiag_Cnt_str.PStep	29429
k_CMMNodeAbsentDiag_Cnt_str.NStep	5790
k_CMMNodeAbsentTimeout_mS_u16	29515
k_CONSANGLECPKMax_HwDeg_f32	332.684387
k_CONSANGLECPKMin_HwDeg_f32	-296.84201
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	10133
k_CONSANGLECPKSigValidThresh_Cnt_u16	56351
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	45507
k_CPKVehicleSpeedValidThresh_Cnt_u16	53777
k_CityParkInputInvalidThresh_Cnt_u16	8533
k_CityParkInputValidThresh_Cnt_u16	29523
k_ComputerRazGCTSigValidThresh_Cnt_u16	51459
k_CptTemporelSigValidThresh_Cnt_u16	5722
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	38251
k_DMDFCTCPKSigValidThresh_Cnt_u16	19374
k_DMDFCTCPKValidCount_Cnt_u16	62855
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	3538
k_DMDRELAXECPKSigValidThresh_Cnt_u16	37325
k_DMDRelaxeConsistentThresh_Cnt_u16	17931
k_DateValidThresh_Cnt_u16	15168
k_DefaultVehSpd_Kph_f32	110.8424
k_DiagMuxOnAbsentTimeout_mS_u16	2928
k_EMNodeTimeout_mS_u16	24585
k_ESPNTCEnableTimeout_mS_u16	16273
k_ESPNodeAbsentDiag_Cnt_str.Threshold	19896

Name	Input Value
k_ESPNodeAbsentDiag_Cnt_str.PStep	5680
k_ESPNodeAbsentDiag_Cnt_str.NStep	8534
k_ESPNodeAbsentTimeout_mS_u16	60915
k_EtatMTSigInvalidThresh_Cnt_u16	55978
k_EtatMTSigValidThresh_Cnt_u16	10245
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	51266
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	54609
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	41416
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	6990
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	6885
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	41158
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	28474
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	61945
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	52261
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	0
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	34845
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	22036
k_ISDATDIRASentDiag_Cnt_str.Threshold	4781
k_ISDATDIRASentDiag_Cnt_str.PStep	41190
k_ISDATDIRASentDiag_Cnt_str.NStep	54935
k_ISDATDIRASentTimeout_mS_u16	32195
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	6901
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58658
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	62989
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	52119
k_ISDYNAASChkSumValidThresh_Cnt_u16	57522
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	23630
k_ISDYNAASMsgCountValidThresh_Cnt_u16	56097
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	619
k_ISDYNAASMsgLenValidThresh_Cnt_u16	10585
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	10287
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	27521
k_ISDYNABRChkSumValidThresh_Cnt_u16	42564
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	31967
k_ISDYNABRMsgCountValidThresh_Cnt_u16	40721
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	14717
k_ISDYNABRMsgLenValidThresh_Cnt_u16	63612
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	57348
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	19630
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	8359
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	27640
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	26836
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	2246
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	59251
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	33641
k_ISDYNVOLChkSumValidThresh_Cnt_u16	40176
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	62021
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	20102
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	24501
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	33892
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	4654
k_IgnOnTimeout_mS_u16	12437
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	194.995193
k_PowerCutVehSpdLowThresh_Kph_f32	116.909302
k_PowerCutVehSpdLowTimeout_mS_u16	37249
k_VBattMaxAAS_Volt_f32	2.48760009
k_VBattMaxBSI_Volt_f32	21.5629997
k_VBattMaxCAV_Volt_f32	20.0792007
k_VBattMaxCMM388_Volt_f32	3.1703999
k_VBattMaxCMM_Volt_f32	17.1548004
k_VBattMaxESP_Volt_f32	18.6250992
k_VBattMinAAS_Volt_f32	31.3356991
k_VBattMinBSI_Volt_f32	1.52629995
k_VBattMinCAV_Volt_f32	32
k_VBattMinCMM388_Volt_f32	0.555400014
k_VBattMinCMM_Volt_f32	11.158
k_VBattMinESP_Volt_f32	17.1548004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	1975
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	23725
k_VitesseVehicleBVRampValidThresh_Cnt_u16	45661
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	9977
k_VitesseVehicleBVSigValidThresh_Cnt_u16	29984

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VitesseVehicleBVSpeedPassThresh_kph_f32	65.6243973
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	22885
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	8528
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	631338240
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	143
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	38098
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2405878272
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	190
target_SrlComInput_Per1_Batt_Volt_f32.value	8.1892004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1191224576
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	193
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.926511347
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1232278784
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3441538304
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	62
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2002801920
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2955867392
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3750597888
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	252
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1836856576
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	128
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3254441216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	22
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	47
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	70
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	77
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	148
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2961437952
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	88
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	123
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	172
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	180
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	197
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	243
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4264695040
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	257996032
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	111
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	119493888
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	57
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	58
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	106
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	117
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	209

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	225
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3126994176
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1077
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.715224802
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	117989
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	134.278595
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	4892

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2405878272	2405878272	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	55450	55450	✔
AASNodeAbsentTimer_mS_M_u32	2405878272	2405878272	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	58658	58658	✔
AngleVolantMsgTimer_mS_M_u32	2405878272	2405878272	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-718.758362	-718.758362	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2807887104	2807887104	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	631338240	631338240	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	1950164224	1950164224	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	1071703296	1071703296	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2405878272	2405878272	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2405878272	2405878272	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	9041	9041	✔
CAVNodeAbsentTimer_mS_M_u32	2405878272	2405878272	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2405878272	2405878272	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2405878272	2405878272	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	35807	35807	✔
CMMNodeAbsentTimer_mS_M_u32	1836856576	1836856576	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	12162	12162	✔
CONSANGLECPK_HwDeg_M_f32	-228.553207	-228.553207 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	12162	12162	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2432697600	2432697600	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	56683	56683	✔
CityParkInputConsistentCount_Cnt_M_u16	29523	29523	✔
CityParkInputInvalidCount_Cnt_M_u16	7197	7197	✔
CityParkInputMsgTimer_mS_M_u32	2405878272	2405878272	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2405878272	2405878272	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2405878272	2405878272	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	631338240	631338240	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2405878272	2405878272	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1071703296	1071703296	✔
ESPNTCEnableTimer_mS_M_u32	2405878272	2405878272	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2405878272	2405878272	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	66	66	✔
EffacDefaultDiagTimer_mS_M_u32[1]	78	78	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	99	99	✔
ElecIntTimer_mS_M_u32[1]	1000	1000	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2405878272	2405878272	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	52042	52042	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1232278784	1232278784	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1766	1766	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2018886912	2018886912	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	15859	15859	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2002801920	2002801920	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	5969	5969	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2955867392	2955867392	✔
ISDATDIRASentFltAcc_Cnt_M_u16	4781	4781	✔
ISDATDIRASentTimer_mS_M_u32	2405878272	2405878272	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2405878272	2405878272	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2405878272	2405878272	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2405878272	2405878272	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2405878272	2405878272	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2405878272	2405878272	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2405878272	2405878272	✔
IgnOnTimer_mS_M_u32	1201739008	1201739008	✔
IgnTimeOff_Sec_M_u32	1928094225	1928094225	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	221	221	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1232278784	1232278784	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	148	148	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3441538304	3441538304	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	62	62	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2002801920	2002801920	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	67	67	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2955867392	2955867392	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1051809024	1051809024	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	252	252	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1836856576	1836856576	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	128	128	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3254441216	3254441216	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2961437952	2961437952	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	243	243	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4264695040	4264695040	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	88	88	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	257996032	257996032	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	111	111	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	119493888	119493888	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3126994176	3126994176	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	518.34729	518.34729	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	63.0550003	63.0550003	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	548.828979	548.828979	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-718.758362	-718.758362	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	12162	12162	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1928094225	1928094225	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-228.553207	-228.553207 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	110.8424	110.8424	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0139	0x0139	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0138	0x0138	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔
NTC	0x0160	0x0160	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.85 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	219919360
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	9702
AASNodeAbsentTimer_mS_M_u32	1231954944
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	20598
ANGLEVOLANTSigValidCount_Cnt_M_u16	38750
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	45195
AngleVolantMsgTimer_mS_M_u32	219919360
AngleVolantValidCount_Cnt_M_u16	46581
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-242.640671
ApaRelaxReq_Cnt_M_lgc	1

Name	Input Value
BSI3F2NTCEnableTimer_mS_M_u32	2677793792
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3603850240
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	901469184
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	298849280
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	85
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2835862528
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	52545
CAVNodeAbsentTimer_mS_M_u32	2084684800
CDD_SrlComVehSpd_Kph_G_f32	473.309387
CMM388NTCEnableTimer_mS_M_u32	1526727680
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3230123008
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	30906
CMMNodeAbsentTimer_mS_M_u32	403313664
CONSANGLECPKSigInvalidCount_Cnt_M_u16	52432
CONSANGLECPKSigValidCount_Cnt_M_u16	55176
CONSANGLECPK_Cnt_M_u16	32043
CONSANGLECPK_HwDeg_M_f32	152.274796
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	32043
CPKVehicleSpeedMsgTimer_mS_M_u32	49460224
CPKVehicleSpeedValidCount_Cnt_M_u16	33849
CityParkInputConsistentCount_Cnt_M_u16	4217
CityParkInputInvalidCount_Cnt_M_u16	34592
CityParkInputMsgTimer_mS_M_u32	1232278784
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1156719616
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	1642
ComputerRazGCTSigInvalidTimer_mS_M_u32	200688640
ComputerRazGCTSigValidCount_Cnt_M_u16	61078
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	26780
DMDFCTCPKSigValidCount_Cnt_M_u16	51756
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	11448
DMDRELAXECPKSigValidCount_Cnt_M_u16	33056
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	47221
DateInvalidTimer_mS_M_u32	3603850240
DiagMuxOnAbsentTimer_mS_M_u32	506688512
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	298849280
ESPNTCEnableTimer_mS_M_u32	2169971712
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	37501
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	101
EffacDefaultDiagTimer_mS_M_u32[1]	85091584
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	85091584
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2527712256
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	60565
EtatMTSigValidCount_Cnt_M_u16	28745
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	61202
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	34634
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	55410
ISDAT4V2BSI552MsgTimer_mS_M_u32	1854804992
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	37889
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	37437
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	28745
ISDATBSI3F2MsgTimer_mS_M_u32	3555816448

Name	Input Value
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	46041
ISDATBSI412MsgLenValidCount_Cnt_M_u16	4037
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	60565
ISDATBSI412MsgTimer_mS_M_u32	3101275136
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	27198
ISDATBSI432MsgLenValidCount_Cnt_M_u16	24321
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	43338
ISDATDIRASentFltAcc_Cnt_M_u16	26718
ISDATDIRASentTimer_mS_M_u32	49460224
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	42345
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	46581
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	19963
ISDYN2CMMMsgTimer_mS_M_u32	2819695616
ISDYNAASChkSumInvalidCount_Cnt_M_u16	60968
ISDYNAASChkSumValidCount_Cnt_M_u16	7984
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	37204
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	57636
ISDYNAASMsgLenValidCount_Cnt_M_u16	50276
ISDYNAASMsgTimeValidCount_Cnt_M_u16	60968
ISDYNAASMsgTimer_mS_M_u32	3380347904
ISDYNABRChkSumInvalidCount_Cnt_M_u16	4011
ISDYNABRChkSumValidCount_Cnt_M_u16	38683
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	32775
ISDYNABRMsgCountValidCount_Cnt_M_u16	43599
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	55727
ISDYNABRMsgLenValidCount_Cnt_M_u16	7591
ISDYNABRMsgTimeValidCount_Cnt_M_u16	32043
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	660
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1205
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	28745
ISDYNCMM208MsgTimer_mS_M_u32	1543037952
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2491
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1311
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	32947
ISDYNCMM388MsgTimer_mS_M_u32	231441408
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	64142
ISDYNVOLChkSumValidCount_Cnt_M_u16	30662
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	20826
ISDYNVOLMsgCountValidCount_Cnt_M_u16	25962
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	26526
ISDYNVOLMsgLenValidCount_Cnt_M_u16	59446
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	30906
ISDYNVOLMsgTimer_mS_M_u32	108151808
IgnOnTimer_mS_M_u32	2001699840
IgnTimeOff_Sec_M_u32	2532509143
ManVehSpd_Kph_M_f32	228.127701
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	141
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	170
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3608638464
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	4
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1568297984
PrevISDATBSI412MsgDLCError_Cnt_M_u08	147
PrevISDATBSI412MsgRxTime_MSec_M_u32	2097857536
PrevISDATBSI432MsgDLCError_Cnt_M_u08	161
PrevISDATBSI432MsgRxTime_MSec_M_u32	1506485248
PrevISDATDIRAMsgTxTime_MSec_M_u32	589218816
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	3
PrevISDYN2CMMMsgRxTime_MSec_M_u32	622957568
PrevISDYNAASMsgDLCError_Cnt_M_u08	186
PrevISDYNAASMsgRxTime_MSec_M_u32	3065005056
PrevISDYNABRMsgDLCError_Cnt_M_u08	12
PrevISDYNABRMsgRxTime_MSec_M_u32	524780544

Name	Input Value
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	80
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4237116416
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	178
PrevISDYNCMM388MsgRxTime_MSec_M_u32	74327040
PrevISDYNVOLMsgDLCError_Cnt_M_u08	63
PrevISDYNVOLMsgRxTime_MSec_M_u32	1082115072
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	798471168
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	288.859009
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	49122
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	54690
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	50819
VitesseVehicleBVRampValidCount_Cnt_M_u16	17155
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	46231
VitesseVehicleBVSigValidCount_Cnt_M_u16	33343
VitesseVehicleBV_Kph_M_f32	411.279205
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	32947
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	59859
VitesseVehiculeRoues_Kph_M_f32	583.269775
k_AASNTCEnableTimeout_mS_u16	25410
k_AASNodeAbsentDiag_Cnt_str.Threshold	47592
k_AASNodeAbsentDiag_Cnt_str.PStep	30186
k_AASNodeAbsentDiag_Cnt_str.NStep	21264
k_AASNodeAbsentTimeout_mS_u16	49616
k_AASNodeTimeout_mS_u16	4258
k_ABSNodeTimeout_mS_u16	24249
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	43353
k_ANGLEVOLANTSigValidThresh_Cnt_u16	19548
k_AngleVolantInvalidThresh_Cnt_u16	48451
k_AngleVolantValidThresh_Cnt_u16	34592
k_BSI552MsgTimeout_mS_u16	20858
k_BSINTCEnableTimeout_mS_u16	566
k_BSINodeAbsentDiag_Cnt_str.Threshold	23812
k_BSINodeAbsentDiag_Cnt_str.PStep	35420
k_BSINodeAbsentDiag_Cnt_str.NStep	13785
k_BSINodeAbsentTimeout_mS_u16	2691
k_BSINodeTimeout_mS_u16	43338
k_BattOvHi_Volt_f32	9.11929989
k_BattOvLo_Volt_f32	1.30190003
k_BattUvHi_Volt_f32	9.65299988
k_BattUvLo_Volt_f32	13.3167
k_CAVNTCEnableTimeout_mS_u16	3542
k_CAVNodeAbsentDiag_Cnt_str.Threshold	9146
k_CAVNodeAbsentDiag_Cnt_str.PStep	44134
k_CAVNodeAbsentDiag_Cnt_str.NStep	19710
k_CAVNodeAbsentTimeout_mS_u16	7935
k_CAVNodeTimeout_mS_u16	62284
k_CMM388MsgTimeout_mS_u16	41190
k_CMM388NTCEnableTimeout_mS_u16	98
k_CMMNTCEnableTimeout_mS_u16	59385
k_CMMNodeAbsentDiag_Cnt_str.Threshold	20116
k_CMMNodeAbsentDiag_Cnt_str.PStep	39182
k_CMMNodeAbsentDiag_Cnt_str.NStep	10795
k_CMMNodeAbsentTimeout_mS_u16	3919
k_CONSANGLECPKMax_HwDeg_f32	197.695404
k_CONSANGLECPKMin_HwDeg_f32	-329.757813
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	31667
k_CONSANGLECPKSigValidThresh_Cnt_u16	9427

Name	Input Value
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	37352
k_CPKVehicleSpeedValidThresh_Cnt_u16	13180
k_CityParkInputInvalidThresh_Cnt_u16	33137
k_CityParkInputValidThresh_Cnt_u16	4217
k_ComputerRazGCTSigValidThresh_Cnt_u16	17831
k_CptTemporelSigValidThresh_Cnt_u16	21603
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	21679
k_DMDFCTCPKSigValidThresh_Cnt_u16	55463
k_DMDFCTCPKValidCount_Cnt_u16	45405
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	19963
k_DMDRELAXECPKSigValidThresh_Cnt_u16	18635
k_DMDRelaxeConsistentThresh_Cnt_u16	42001
k_DateValidThresh_Cnt_u16	55410
k_DefaultVehSpd_Kph_f32	207.921204
k_DiagMuxOnAbsentTimeout_mS_u16	8545
k_EMNodeTimeout_mS_u16	60629
k_ESPNTCEnableTimeout_mS_u16	50621
k_ESPNodeAbsentDiag_Cnt_str.Threshold	51404
k_ESPNodeAbsentDiag_Cnt_str.PStep	4924
k_ESPNodeAbsentDiag_Cnt_str.NStep	44772
k_ESPNodeAbsentTimeout_mS_u16	16215
k_EtatMTSigInvalidThresh_Cnt_u16	59762
k_EtatMTSigValidThresh_Cnt_u16	2082
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	2667
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	47615
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	39194
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	15046
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	12994
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	56157
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	18051
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	21766
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	39874
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	65535
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	31259
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	32886
k_ISDATDIRASentDiag_Cnt_str.Threshold	28198
k_ISDATDIRASentDiag_Cnt_str.PStep	56724
k_ISDATDIRASentDiag_Cnt_str.NStep	64984
k_ISDATDIRASentTimeout_mS_u16	42023
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	62931
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	45195
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	37449
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	2731
k_ISDYNAASChkSumValidThresh_Cnt_u16	53787
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	64263
k_ISDYNAASMsgCountValidThresh_Cnt_u16	25935
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	46639
k_ISDYNAASMsgLenValidThresh_Cnt_u16	806
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	2660
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	43629
k_ISDYNABRChkSumValidThresh_Cnt_u16	41189
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	31573
k_ISDYNABRMsgCountValidThresh_Cnt_u16	31613
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46010
k_ISDYNABRMsgLenValidThresh_Cnt_u16	3453
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	17572
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	21094
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	8122
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	30537
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	52086
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	21086
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	34072
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	32628
k_ISDYNVOLChkSumValidThresh_Cnt_u16	59808
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	33826
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	55455
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	29201
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	23237
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	35752
k_IgnOnTimeout_mS_u16	10224
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	215.962708
k_PowerCutVehSpdLowThresh_Kph_f32	234.220505

Name	Input Value
k_PowerCutVehSpdLowTimeout_mS_u16	4910
k_VBattMaxAAS_Volt_f32	10.8998003
k_VBattMaxBSI_Volt_f32	25.632
k_VBattMaxCAV_Volt_f32	25.6394997
k_VBattMaxCMM388_Volt_f32	9.3991003
k_VBattMaxCMM_Volt_f32	14.4645004
k_VBattMaxESP_Volt_f32	3.31820011
k_VBattMinAAS_Volt_f32	15.9754
k_VBattMinBSI_Volt_f32	3.31820011
k_VBattMinCAV_Volt_f32	24.8841991
k_VBattMinCMM388_Volt_f32	32
k_VBattMinCMM_Volt_f32	16.8250008
k_VBattMinESP_Volt_f32	14.4645004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	46989
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	12137
k_VitesseVehicleBVRampValidThresh_Cnt_u16	19546
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	12998
k_VitesseVehicleBVSigValidThresh_Cnt_u16	32530
k_VitesseVehicleBVSpeedPassThresh_kph_f32	50.4034996
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	51265
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	46913
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3603850240
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	50
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	7720
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	85091584
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	178
target_SrlComInput_Per1_Batt_Volt_f32.value	22.8635998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	728814592
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	5
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.240291134
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	970556416
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	827171840
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4111582208
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1294328832
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	25822208
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3661505536
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2671920128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	86
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	122
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	137
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	149
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	207
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3760645120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	78

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	175
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	189
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3617358848
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	647013376
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	30721024
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	91
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	106
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	123
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	176
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	186
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	203
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	927749120
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2199
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.468594879
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	44800
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	36.3624001
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	14108

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	85091584	85091584	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	47592	47592	✔
AASNodeAbsentTimer_mS_M_u32	85091584	85091584	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	85091584	85091584	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-242.640671	-242.640671	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2677793792	2677793792	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	85091584	85091584	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	901469184	901469184	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	298849280	298849280	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	85091584	85091584	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	85091584	85091584	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	9146	9146	✔
CAVNodeAbsentTimer_mS_M_u32	85091584	85091584	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	85091584	85091584	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	85091584	85091584	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	20111	20111	✔
CMMNodeAbsentTimer_mS_M_u32	3661505536	3661505536	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	32043	32043	✔
CONSANGLECPK_HwDeg_M_f32	152.274796	152.274796 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CPKVehicleSpeedMsgTimer_mS_M_u32	85091584	85091584	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	85091584	85091584	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	85091584	85091584	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	85091584	85091584	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	85091584	85091584	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	85091584	85091584	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	85091584	85091584	✔
ESPNTCEnableTimer_mS_M_u32	85091584	85091584	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	85091584	85091584	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	101	101	✔
EffacDefaultDiagTimer_mS_M_u32[1]	85091584	85091584	✔
ElecIntCount_Cnt_M_u08	2	2	✔
ElecIntTimer_mS_M_u32[0]	8	8	✔
ElecIntTimer_mS_M_u32[1]	85091584	85091584	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	85091584	85091584	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	970556416	970556416	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	85091584	85091584	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	85091584	85091584	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1294328832	1294328832	✔
ISDATDIRASentFltAcc_Cnt_M_u16	28198	28198	✔
ISDATDIRASentTimer_mS_M_u32	85091584	85091584	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	85091584	85091584	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	85091584	85091584	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	85091584	85091584	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	85091584	85091584	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	85091584	85091584	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	85091584	85091584	✔
IgnOnTimer_mS_M_u32	2001699840	2001699840	✔
IgnTimeOff_Sec_M_u32	2532509143	2532509143	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	148	148	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	970556416	970556416	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	208	208	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	827171840	827171840	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	117	117	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4111582208	4111582208	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	74	74	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1294328832	1294328832	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	589218816	589218816	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3661505536	3661505536	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	186	186	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2671920128	2671920128	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3760645120	3760645120	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	14	14	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3617358848	3617358848	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	647013376	647013376	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	158	158	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	30721024	30721024	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	927749120	927749120	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	288.859009	288.859009	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VitesseVehicleBV_Kph_M_f32	411.279205	411.279205	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	583.269775	583.269775	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-242.640671	-242.640671	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	32043	32043	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2532509143	2532509143	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	152.274796	152.274796 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	207.921204	207.921204	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0139	0x0139	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0161	0x0161	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.86 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3692799744
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	56252
AASNodeAbsentTimer_mS_M_u32	3169081088

Name	Input Value
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	15882
ANGLEVOLANTSigValidCount_Cnt_M_u16	13586
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	4045
AngleVolantMsgTimer_mS_M_u32	3692799744
AngleVolantValidCount_Cnt_M_u16	53262
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-352.02475
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2707101440
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3854800640
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3904685824
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2541651712
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	27245
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1624721152
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	23593
CAVNodeAbsentTimer_mS_M_u32	2062120704
CDD_SrlComVehSpd_Kph_G_f32	204.725296
CMM388NTCEnableTimer_mS_M_u32	2813245184
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1175942912
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	46720
CMMNodeAbsentTimer_mS_M_u32	3973089024
CONSANGLECPKSigInvalidCount_Cnt_M_u16	24573
CONSANGLECPKSigValidCount_Cnt_M_u16	19349
CONSANGLECPK_Cnt_M_u16	42668
CONSANGLECPK_HwDeg_M_f32	-11.6306
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	42668
CPKVehicleSpeedMsgTimer_mS_M_u32	378971904
CPKVehicleSpeedValidCount_Cnt_M_u16	32553
CityParkInputConsistentCount_Cnt_M_u16	53378
CityParkInputInvalidCount_Cnt_M_u16	6541
CityParkInputMsgTimer_mS_M_u32	970556416
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3663222528
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	18992
ComputerRazGCTSigInvalidTimer_mS_M_u32	1036777216
ComputerRazGCTSigValidCount_Cnt_M_u16	59947
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	25881
DMDFCTCPKSigValidCount_Cnt_M_u16	44073
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	12612
DMDRELAXECPKSigValidCount_Cnt_M_u16	65484
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	28942
DateInvalidTimer_mS_M_u32	3854800640
DiagMuxOnAbsentTimer_mS_M_u32	3084150528
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2541651712
ESPNTCEnableTimer_mS_M_u32	4180236032
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	42228
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	99
EffacDefaultDiagTimer_mS_M_u32[1]	999
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	6
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2683389696
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	55278

Name	Input Value
EtatMTSigValidCount_Cnt_M_u16	18579
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	33079
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	50255
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	6487
ISDAT4V2BSI552MsgTimer_mS_M_u32	4182017792
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	35625
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	44086
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	18579
ISDATBSI3F2MsgTimer_mS_M_u32	244999936
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	56481
ISDATBSI412MsgLenValidCount_Cnt_M_u16	42141
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	55278
ISDATBSI412MsgTimer_mS_M_u32	1356965632
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	61940
ISDATBSI432MsgLenValidCount_Cnt_M_u16	20328
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	11278
ISDATDIRASentFltAcc_Cnt_M_u16	16082
ISDATDIRASentTimer_mS_M_u32	378971904
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	42482
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	53262
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	61692
ISDYN2CMMMsgTimer_mS_M_u32	3975894784
ISDYNAASChkSumInvalidCount_Cnt_M_u16	2806
ISDYNAASChkSumValidCount_Cnt_M_u16	50078
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	31217
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	27776
ISDYNAASMsgLenValidCount_Cnt_M_u16	61056
ISDYNAASMsgTimeValidCount_Cnt_M_u16	2806
ISDYNAASMsgTimer_mS_M_u32	1278916352
ISDYNABRChkSumInvalidCount_Cnt_M_u16	51693
ISDYNABRChkSumValidCount_Cnt_M_u16	8029
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	37209
ISDYNABRMsgCountValidCount_Cnt_M_u16	24129
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	30048
ISDYNABRMsgLenValidCount_Cnt_M_u16	46392
ISDYNABRMsgTimeValidCount_Cnt_M_u16	42668
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	661
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1207
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	18579
ISDYNCMM208MsgTimer_mS_M_u32	541333248
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2495
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1313
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	59348
ISDYNCMM388MsgTimer_mS_M_u32	491534080
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	20163
ISDYNVOLChkSumValidCount_Cnt_M_u16	58075
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	8927
ISDYNVOLMsgCountValidCount_Cnt_M_u16	21103
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	59793
ISDYNVOLMsgLenValidCount_Cnt_M_u16	62346
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	46720
ISDYNVOLMsgTimer_mS_M_u32	1045952256
IgnOnTimer_mS_M_u32	4039128832
IgnTimeOff_Sec_M_u32	115636015
ManVehSpd_Kph_M_f32	134.587494
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	143
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	205
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	489187072
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	20
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	763348736
PrevISDATBSI412MsgDLCError_Cnt_M_u08	145
PrevISDATBSI412MsgRxTime_MSec_M_u32	3700324096

Name	Input Value
PrevISDATBSI432MsgDLCError_Cnt_M_u08	209
PrevISDATBSI432MsgRxTime_MSec_M_u32	1070421760
PrevISDATDIRAMsgTxTime_MSec_M_u32	978482944
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	132
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2206861056
PrevISDYNAASMsgDLCError_Cnt_M_u08	87
PrevISDYNAASMsgRxTime_MSec_M_u32	2778593024
PrevISDYNABRMsgDLCError_Cnt_M_u08	154
PrevISDYNABRMsgRxTime_MSec_M_u32	3638048512
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	109
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2282157824
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	89
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2346997504
PrevISDYNVOLMsgDLCError_Cnt_M_u08	233
PrevISDYNVOLMsgRxTime_MSec_M_u32	2788128512
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1688708864
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	332.48111
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	18502
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	12998
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	63587
VitesseVehicleBVRampValidCount_Cnt_M_u16	44707
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	54695
VitesseVehicleBVSigValidCount_Cnt_M_u16	14447
VitesseVehicleBV_Kph_M_f32	413.890106
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	59348
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	22580
VitesseVehiculeRoues_Kph_M_f32	260.700195
k_AASNTCEnableTimeout_mS_u16	4199
k_AASNodeAbsentDiag_Cnt_str.Threshold	22633
k_AASNodeAbsentDiag_Cnt_str.PStep	731
k_AASNodeAbsentDiag_Cnt_str.NStep	44576
k_AASNodeAbsentTimeout_mS_u16	55421
k_AASNodeTimeout_mS_u16	33222
k_ABSNodeTimeout_mS_u16	14018
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	24739
k_ANGLEVOLANTSigValidThresh_Cnt_u16	45911
k_AngleVolantInvalidThresh_Cnt_u16	48290
k_AngleVolantValidThresh_Cnt_u16	6541
k_BSI552MsgTimeout_mS_u16	32063
k_BSINTCEnableTimeout_mS_u16	2572
k_BSINodeAbsentDiag_Cnt_str.Threshold	23852
k_BSINodeAbsentDiag_Cnt_str.PStep	35403
k_BSINodeAbsentDiag_Cnt_str.NStep	13808
k_BSINodeAbsentTimeout_mS_u16	57829
k_BSINodeTimeout_mS_u16	11278
k_BattOvHi_Volt_f32	14.8772001
k_BattOvLo_Volt_f32	11.5107002
k_BattUvHi_Volt_f32	28.5739994
k_BattUvLo_Volt_f32	4.85570002
k_CAVNTCEnableTimeout_mS_u16	56683
k_CAVNodeAbsentDiag_Cnt_str.Threshold	7433
k_CAVNodeAbsentDiag_Cnt_str.PStep	51392
k_CAVNodeAbsentDiag_Cnt_str.NStep	38638
k_CAVNodeAbsentTimeout_mS_u16	57071
k_CAVNodeTimeout_mS_u16	56457
k_CMM388MsgTimeout_mS_u16	27324
k_CMM388NTCEnableTimeout_mS_u16	15432

Name	Input Value
k_CMMNTCEnableTimeout_mS_u16	28481
k_CMMNodeAbsentDiag_Cnt_str.Threshold	24645
k_CMMNodeAbsentDiag_Cnt_str.PStep	36942
k_CMMNodeAbsentDiag_Cnt_str.NStep	51376
k_CMMNodeAbsentTimeout_mS_u16	55232
k_CONSANGLECPKMax_HwDeg_f32	704.815674
k_CONSANGLECPKMin_HwDeg_f32	-601.727783
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	63188
k_CONSANGLECPKSigValidThresh_Cnt_u16	42804
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	38388
k_CPKVehicleSpeedValidThresh_Cnt_u16	43448
k_CityParkInputInvalidThresh_Cnt_u16	3227
k_CityParkInputValidThresh_Cnt_u16	53378
k_ComputerRazGCTSigValidThresh_Cnt_u16	36407
k_CptTemporelSigValidThresh_Cnt_u16	32196
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	1120
k_DMDFCTCPKSigValidThresh_Cnt_u16	33848
k_DMDFCTCPKValidCount_Cnt_u16	30549
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	61692
k_DMDRELAXECPKSigValidThresh_Cnt_u16	27724
k_DMDRelaxeConsistentThresh_Cnt_u16	62074
k_DateValidThresh_Cnt_u16	6487
k_DefaultVehSpd_Kph_f32	124.169098
k_DiagMuxOnAbsentTimeout_mS_u16	4618
k_EMNodeTimeout_mS_u16	21486
k_ESPNTCEnableTimeout_mS_u16	25269
k_ESPNodeAbsentDiag_Cnt_str.Threshold	57596
k_ESPNodeAbsentDiag_Cnt_str.PStep	30245
k_ESPNodeAbsentDiag_Cnt_str.NStep	52198
k_ESPNodeAbsentTimeout_mS_u16	26536
k_EtatMTSigInvalidThresh_Cnt_u16	6296
k_EtatMTSigValidThresh_Cnt_u16	43080
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	63595
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	25967
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	64159
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	60122
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	7847
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	30229
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	45349
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	49497
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	28008
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	54500
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	39836
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	14284
k_ISDATDIRASentDiag_Cnt_str.Threshold	62534
k_ISDATDIRASentDiag_Cnt_str.PStep	47028
k_ISDATDIRASentDiag_Cnt_str.NStep	29409
k_ISDATDIRASentTimeout_mS_u16	64633
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	35765
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	4045
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	11537
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	55533
k_ISDYNAASChkSumValidThresh_Cnt_u16	28253
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	8281
k_ISDYNAASMsgCountValidThresh_Cnt_u16	11585
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	58977
k_ISDYNAASMsgLenValidThresh_Cnt_u16	47674
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39231
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	31526
k_ISDYNABRChkSumValidThresh_Cnt_u16	41854
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	63853
k_ISDYNABRMsgCountValidThresh_Cnt_u16	50357
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	1408
k_ISDYNABRMsgLenValidThresh_Cnt_u16	13300
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	50496
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	41146
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	23806
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	43473
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	52490
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	1042
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	65445
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	42448
k_ISDYNVOLChkSumValidThresh_Cnt_u16	17164

Name	Input Value
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	41989
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	27345
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	14202
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	31007
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	22453
k_IgnOnTimeout_mS_u16	40028
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	86.5445023
k_PowerCutVehSpdLowThresh_Kph_f32	167.771103
k_PowerCutVehSpdLowTimeout_mS_u16	45219
k_VBattMaxAAS_Volt_f32	19.6278992
k_VBattMaxBSI_Volt_f32	25.9750996
k_VBattMaxCAV_Volt_f32	3.86479998
k_VBattMaxCMM388_Volt_f32	22.4862995
k_VBattMaxCMM_Volt_f32	31.2346001
k_VBattMaxESP_Volt_f32	18.8794994
k_VBattMinAAS_Volt_f32	26.5405998
k_VBattMinBSI_Volt_f32	1.25629997
k_VBattMinCAV_Volt_f32	30.3330002
k_VBattMinCMM388_Volt_f32	6.10519981
k_VBattMinCMM_Volt_f32	5.04260015
k_VBattMinESP_Volt_f32	31.2346001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	44679
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	58035
k_VitesseVehicleBVRampValidThresh_Cnt_u16	12767
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	45531
k_VitesseVehicleBVSigValidThresh_Cnt_u16	10423
k_VitesseVehicleBVSpeedPassThresh_kph_f32	586.999207
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	27433
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	51689
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3854800640
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	228
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	242
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1748734976
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	89
target_SrlComInput_Per1_Batt_Volt_f32.value	21.2758999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3181135616
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	84
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.351968139
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1361196800
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3813005056
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1350137600
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1086134016
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1544599296
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1249138432
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3018323712
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	34
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	107

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	178
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	228
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3417970432
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	153
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	161
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	207
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	230
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1138308864
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3481065216
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	156
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4130371328
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	71
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	188
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1745471232
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	148
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0381127037
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	179200
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	174.595596
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	19096

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1748734976	1748734976	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1748734976	1748734976	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1748734976	1748734976	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-352.02475	-352.02475	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2707101440	2707101440	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1748734976	1748734976	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3904685824	3904685824	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	2541651712	2541651712	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1748734976	1748734976	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1748734976	1748734976	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	7433	7433	✔
CAVNodeAbsentTimer_mS_M_u32	1748734976	1748734976	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1748734976	1748734976	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1175942912	1175942912	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1748734976	1748734976	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	42668	42668	✔
CONSANGLECPK_HwDeg_M_f32	-11.6306	-11.6306 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1748734976	1748734976	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1748734976	1748734976	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1748734976	1748734976	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1748734976	1748734976	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1748734976	1748734976	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1748734976	1748734976	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1748734976	1748734976	✔
ESPNTCEnableTimer_mS_M_u32	1748734976	1748734976	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	57596	57596	✔
ESPNodeAbsentTimer_mS_M_u32	1748734976	1748734976	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	99	99	✔
EffacDefaultDiagTimer_mS_M_u32[1]	999	999	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4	4	✔
ElecIntTimer_mS_M_u32[1]	6	6	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1748734976	1748734976	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1361196800	1361196800	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1748734976	1748734976	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1748734976	1748734976	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1086134016	1086134016	✔
ISDATDIRASentFltAcc_Cnt_M_u16	62534	62534	✔
ISDATDIRASentTimer_mS_M_u32	1748734976	1748734976	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1748734976	1748734976	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1748734976	1748734976	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1748734976	1748734976	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1748734976	1748734976	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1748734976	1748734976	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1748734976	1748734976	✔
IgnOnTimer_mS_M_u32	1748734976	1748734976	✔
IgnTimeOff_Sec_M_u32	115636015	115636015	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	253	253	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1361196800	1361196800	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	33	33	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3813005056	3813005056	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	75	75	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1350137600	1350137600	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	37	37	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1086134016	1086134016	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	978482944	978482944	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	134	134	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1249138432	1249138432	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	93	93	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3018323712	3018323712	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	228	228	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3417970432	3417970432	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	91	91	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1138308864	1138308864	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	152	152	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3481065216	3481065216	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	156	156	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4130371328	4130371328	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1745471232	1745471232	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	332.48111	332.48111	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	413.890106	413.890106	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	260.700195	260.700195	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-352.02475	-352.02475	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	42668	42668	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	115636015	115636015	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-11.6306	-11.6306 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	124.169098	124.169098	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.87 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2460470784
AASNTCsEnabled_Cnt_M_lgc	0

Name	Input Value
AASNodeAbsentFltAcc_Cnt_M_u16	46534
AASNodeAbsentTimer_mS_M_u32	789429760
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	59610
ANGLEVOLANTSigValidCount_Cnt_M_u16	41090
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	40339
AngleVolantMsgTimer_mS_M_u32	2460470784
AngleVolantValidCount_Cnt_M_u16	60238
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-659.30304
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3433659904
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1097858560
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3645140480
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	67055104
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	44977
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4210355712
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	53502
CAVNodeAbsentTimer_mS_M_u32	4051590656
CDD_SrlComVehSpd_Kph_G_f32	545.262817
CMM388NTCEnableTimer_mS_M_u32	271490560
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3354680832
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	43960
CMMNodeAbsentTimer_mS_M_u32	3423153664
CONSANGLECPKSigInvalidCount_Cnt_M_u16	48642
CONSANGLECPKSigValidCount_Cnt_M_u16	55289
CONSANGLECPK_Cnt_M_u16	58036
CONSANGLECPK_HwDeg_M_f32	568.78772
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	58036
CPKVehicleSpeedMsgTimer_mS_M_u32	2402733568
CPKVehicleSpeedValidCount_Cnt_M_u16	12357
CityParkInputConsistentCount_Cnt_M_u16	47602
CityParkInputInvalidCount_Cnt_M_u16	55251
CityParkInputMsgTimer_mS_M_u32	1361196800
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2796666368
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	14954
ComputerRazGCTSigInvalidTimer_mS_M_u32	1389813248
ComputerRazGCTSigValidCount_Cnt_M_u16	20727
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	9519
DMDFCTCPKSigValidCount_Cnt_M_u16	3263
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	30508
DMDRELAXECPKSigValidCount_Cnt_M_u16	43092
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	3791
DateInvalidTimer_mS_M_u32	1097858560
DiagMuxOnAbsentTimer_mS_M_u32	3531443712
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	67055104
ESPNTCEnableTimer_mS_M_u32	3460218368
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	11548
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	9
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1100
ElecIntTimer_mS_M_u32[1]	1152
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	631696896
EngOnDLCInvalidCount_Cnt_M_u08	1

Name	Input Value
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	53357
EtatMTSigValidCount_Cnt_M_u16	35649
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	49748
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	54731
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	64821
ISDAT4V2BSI552MsgTimer_mS_M_u32	1991060992
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	47677
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	984
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	35649
ISDATBSI3F2MsgTimer_mS_M_u32	1714130432
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	45783
ISDATBSI412MsgLenValidCount_Cnt_M_u16	51106
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	53357
ISDATBSI412MsgTimer_mS_M_u32	3428175360
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	51548
ISDATBSI432MsgLenValidCount_Cnt_M_u16	64960
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	13647
ISDATDIRASentFltAcc_Cnt_M_u16	3331
ISDATDIRASentTimer_mS_M_u32	2402733568
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	31970
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	60238
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52614
ISDYN2CMMMsgTimer_mS_M_u32	3133718016
ISDYNAASChkSumInvalidCount_Cnt_M_u16	36888
ISDYNAASChkSumValidCount_Cnt_M_u16	33503
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	14757
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	48121
ISDYNAASMsgLenValidCount_Cnt_M_u16	45753
ISDYNAASMsgTimeValidCount_Cnt_M_u16	36888
ISDYNAASMsgTimer_mS_M_u32	1384816128
ISDYNABRChkSumInvalidCount_Cnt_M_u16	59570
ISDYNABRChkSumValidCount_Cnt_M_u16	9505
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	18671
ISDYNABRMsgCountValidCount_Cnt_M_u16	65270
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	51673
ISDYNABRMsgLenValidCount_Cnt_M_u16	59152
ISDYNABRMsgTimeValidCount_Cnt_M_u16	58036
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	662
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1209
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	35649
ISDYNCMM208MsgTimer_mS_M_u32	871267840
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2499
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1315
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	15356
ISDYNCMM388MsgTimer_mS_M_u32	89529856
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	35248
ISDYNVOLChkSumValidCount_Cnt_M_u16	43559
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	33757
ISDYNVOLMsgCountValidCount_Cnt_M_u16	45549
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	4933
ISDYNVOLMsgLenValidCount_Cnt_M_u16	21020
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	43960
ISDYNVOLMsgTimer_mS_M_u32	2167594496
IgnOnTimer_mS_M_u32	1526341120
IgnTimeOff_Sec_M_u32	2607797521
ManVehSpd_Kph_M_f32	547.365295
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	145
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	94
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	0
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	140
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3606801920

Name	Input Value
PrevISDATBSI412MsgDLCError_Cnt_M_u08	152
PrevISDATBSI412MsgRxTime_MSec_M_u32	2693750272
PrevISDATBSI432MsgDLCError_Cnt_M_u08	154
PrevISDATBSI432MsgRxTime_MSec_M_u32	2320678400
PrevISDATDIRAMsgTxTime_MSec_M_u32	2537774592
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	244
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3453791744
PrevISDYNAASMsgDLCError_Cnt_M_u08	147
PrevISDYNAASMsgRxTime_MSec_M_u32	3814776320
PrevISDYNABRMsgDLCError_Cnt_M_u08	37
PrevISDYNABRMsgRxTime_MSec_M_u32	45227520
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	205
PrevISDYNCMM208MsgRxTime_MSec_M_u32	539352576
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	206
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3255680512
PrevISDYNVOLMsgDLCError_Cnt_M_u08	125
PrevISDYNVOLMsgRxTime_MSec_M_u32	128736768
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	688115200
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	126.101997
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	49319
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	32231
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	25680
VitesseVehicleBVRampValidCount_Cnt_M_u16	48720
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	54787
VitesseVehicleBVSigValidCount_Cnt_M_u16	19051
VitesseVehicleBV_Kph_M_f32	504.88501
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	15356
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	59291
VitesseVehiculeRoues_Kph_M_f32	532.44989
k_AASNTCEnableTimeout_mS_u16	20867
k_AASNodeAbsentDiag_Cnt_str.Threshold	26017
k_AASNodeAbsentDiag_Cnt_str.PStep	43749
k_AASNodeAbsentDiag_Cnt_str.NStep	49390
k_AASNodeAbsentTimeout_mS_u16	19969
k_AASNodeTimeout_mS_u16	37095
k_ABSNodeTimeout_mS_u16	37940
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	63823
k_ANGLEVOLANTSigValidThresh_Cnt_u16	19955
k_AngleVolantInvalidThresh_Cnt_u16	7698
k_AngleVolantValidThresh_Cnt_u16	55251
k_BSI552MsgTimeout_mS_u16	25722
k_BSINTCEnableTimeout_mS_u16	57620
k_BSINodeAbsentDiag_Cnt_str.Threshold	23892
k_BSINodeAbsentDiag_Cnt_str.PStep	35386
k_BSINodeAbsentDiag_Cnt_str.NStep	13831
k_BSINodeAbsentTimeout_mS_u16	34635
k_BSINodeTimeout_mS_u16	13647
k_BattOvHi_Volt_f32	29.9190998
k_BattOvLo_Volt_f32	22.9752007
k_BattUvHi_Volt_f32	7.93489981
k_BattUvLo_Volt_f32	19.7710991
k_CAVNTCEnableTimeout_mS_u16	33849
k_CAVNodeAbsentDiag_Cnt_str.Threshold	29049
k_CAVNodeAbsentDiag_Cnt_str.PStep	32044
k_CAVNodeAbsentDiag_Cnt_str.NStep	58042
k_CAVNodeAbsentTimeout_mS_u16	57516
k_CAVNodeTimeout_mS_u16	30814

Name	Input Value
k_CMM388MsgTimeout_mS_u16	2246
k_CMM388NTCEnableTimeout_mS_u16	50210
k_CMMNTCEnableTimeout_mS_u16	28149
k_CMMNodeAbsentDiag_Cnt_str.Threshold	31853
k_CMMNodeAbsentDiag_Cnt_str.PStep	40427
k_CMMNodeAbsentDiag_Cnt_str.NStep	4508
k_CMMNodeAbsentTimeout_mS_u16	39159
k_CONSANGLECPKMax_HwDeg_f32	390.181885
k_CONSANGLECPKMin_HwDeg_f32	-284.477509
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	3836
k_CONSANGLECPKSigValidThresh_Cnt_u16	64155
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	35933
k_CPKVehicleSpeedValidThresh_Cnt_u16	26514
k_CityParkInputInvalidThresh_Cnt_u16	22696
k_CityParkInputValidThresh_Cnt_u16	47602
k_ComputerRazGCTSigValidThresh_Cnt_u16	26899
k_CptTemporelSigValidThresh_Cnt_u16	18222
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	7385
k_DMDFCTCPKSigValidThresh_Cnt_u16	31248
k_DMDFCTCPKValidCount_Cnt_u16	10489
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	52614
k_DMDRELAXECPKSigValidThresh_Cnt_u16	6230
k_DMDRelaxeConsistentThresh_Cnt_u16	48588
k_DateValidThresh_Cnt_u16	64821
k_DefaultVehSpd_Kph_f32	248.972397
k_DiagMuxOnAbsentTimeout_mS_u16	39066
k_EMNodeTimeout_mS_u16	58927
k_ESPNTCEnableTimeout_mS_u16	60762
k_ESPNodeAbsentDiag_Cnt_str.Threshold	44072
k_ESPNodeAbsentDiag_Cnt_str.PStep	28485
k_ESPNodeAbsentDiag_Cnt_str.NStep	54236
k_ESPNodeAbsentTimeout_mS_u16	35135
k_EtatMTSigInvalidThresh_Cnt_u16	26801
k_EtatMTSigValidThresh_Cnt_u16	63072
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	248
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	18091
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	61339
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	40746
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	45189
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	46715
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	36809
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	44013
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	9984
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	48568
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	16548
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	24149
k_ISDATDIRASentDiag_Cnt_str.Threshold	51265
k_ISDATDIRASentDiag_Cnt_str.PStep	10448
k_ISDATDIRASentDiag_Cnt_str.NStep	33632
k_ISDATDIRASentTimeout_mS_u16	33038
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	18074
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	40339
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	65094
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	48050
k_ISDYNAASChkSumValidThresh_Cnt_u16	14369
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	39919
k_ISDYNAASMsgCountValidThresh_Cnt_u16	37366
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	25430
k_ISDYNAASMsgLenValidThresh_Cnt_u16	46987
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	15419
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	20615
k_ISDYNABRChkSumValidThresh_Cnt_u16	46142
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	689
k_ISDYNABRMsgCountValidThresh_Cnt_u16	15769
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	48824
k_ISDYNABRMsgLenValidThresh_Cnt_u16	32796
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	10232
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	34635
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	58816
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	1222
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	15322
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	13186
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	34187

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	54090
k_ISDYNVOLChkSumValidThresh_Cnt_u16	26709
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	46057
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	4805
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	57801
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	10653
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	14875
k_IgnOnTimeout_mS_u16	8102
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	146.345901
k_PowerCutVehSpdLowThresh_Kph_f32	6.66620016
k_PowerCutVehSpdLowTimeout_mS_u16	24783
k_VBattMaxAAS_Volt_f32	21.4867992
k_VBattMaxBSI_Volt_f32	30.8689995
k_VBattMaxCAV_Volt_f32	16.4078999
k_VBattMaxCMM388_Volt_f32	17.8423004
k_VBattMaxCMM_Volt_f32	18.7642994
k_VBattMaxESP_Volt_f32	28.2115002
k_VBattMinAAS_Volt_f32	0.32980001
k_VBattMinBSI_Volt_f32	28.2115002
k_VBattMinCAV_Volt_f32	29.3969002
k_VBattMinCMM388_Volt_f32	6.75409985
k_VBattMinCMM_Volt_f32	22.6714001
k_VBattMinESP_Volt_f32	18.7642994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	42532
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	13920
k_VitesseVehicleBVRampValidThresh_Cnt_u16	22237
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	15655
k_VitesseVehicleBVSigValidThresh_Cnt_u16	50515
k_VitesseVehicleBVSpeedPassThresh_kph_f32	88.7518005
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	41982
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	1150
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1097858560
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	107
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	3118
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2721842944
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	206
target_SrlComInput_Per1_Batt_Volt_f32.value	24.7322998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	950398464
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	7
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.687158644
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1104420352
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	568933888
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2966314496
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4135812608
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4211645952
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3328032256
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1619189248
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	92

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	105
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	187
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	191
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	217
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2307685888
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	64
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	114
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	131
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	184
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	196
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	138
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	95362560
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4181999104
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	244
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1537826304
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	38
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	118
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	242
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3479006720
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2255
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.191026971
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	70477
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	210.442795
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	33201

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2721842944	2721842944	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2721842944	2721842944	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2721842944	2721842944	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-659.30304	-659.30304	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2721842944	2721842944	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2721842944	2721842944	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2721842944	2721842944	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2721842944	2721842944	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2721842944	2721842944	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2721842944	2721842944	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	29049	29049	✔
CAVNodeAbsentTimer_mS_M_u32	2721842944	2721842944	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2721842944	2721842944	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2721842944	2721842944	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2721842944	2721842944	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	58036	58036	✔
CONSANGLECPK_HwDeg_M_f32	568.78772	568.78772 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2721842944	2721842944	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2721842944	2721842944	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2721842944	2721842944	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2721842944	2721842944	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2721842944	2721842944	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2721842944	2721842944	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2721842944	2721842944	✔
ESPNTCEnableTimer_mS_M_u32	2721842944	2721842944	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	44072	44072	✔
ESPNodeAbsentTimer_mS_M_u32	2721842944	2721842944	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	8	8	✔
EffacDefaultDiagTimer_mS_M_u32[1]	9	9	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2721842944	2721842944	✔
ElecIntTimer_mS_M_u32[1]	1152	1152	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2721842944	2721842944	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2721842944	2721842944	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2721842944	2721842944	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2721842944	2721842944	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2721842944	2721842944	✔
ISDATDIRASentFltAcc_Cnt_M_u16	51265	51265	✔
ISDATDIRASentTimer_mS_M_u32	2721842944	2721842944	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2721842944	2721842944	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2721842944	2721842944	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2721842944	2721842944	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2721842944	2721842944	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2721842944	2721842944	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2721842944	2721842944	✔
IgnOnTimer_mS_M_u32	2721842944	2721842944	✔
IgnTimeOff_Sec_M_u32	2607797521	2607797521	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1104420352	1104420352	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	20	20	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	568933888	568933888	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	75	75	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2966314496	2966314496	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	180	180	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4135812608	4135812608	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2537774592	2537774592	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	63	63	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3328032256	3328032256	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	113	113	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1619189248	1619189248	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	172	172	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2307685888	2307685888	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	138	138	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	95362560	95362560	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	74	74	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4181999104	4181999104	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	244	244	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1537826304	1537826304	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3479006720	3479006720	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	126.101997	126.101997	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	504.88501	504.88501	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	532.44989	532.44989	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-659.30304	-659.30304	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	58036	58036	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2607797521	2607797521	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	568.78772	568.78772 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	248.972397	248.972397	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.88 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	878663936
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	25859
AASNodeAbsentTimer_mS_M_u32	2733476096
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	48582
ANGLEVOLANTSigValidCount_Cnt_M_u16	49296
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	8604
AngleVolantMsgTimer_mS_M_u32	878663936
AngleVolantValidCount_Cnt_M_u16	36075
AngleVolantValid_Cnt_M_lgc	0

Name	Input Value
AngleVolant_HwDeg_M_f32	-626.824951
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3910813952
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3301361920
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	453605632
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	4124653824
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	34113
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	402127104
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	15833
CAVNodeAbsentTimer_mS_M_u32	1713088768
CDD_SrlComVehSpd_Kph_G_f32	386.018005
CMM388NTCEnableTimer_mS_M_u32	453699840
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	985245952
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	61548
CMMNodeAbsentTimer_mS_M_u32	1169897728
CONSANGLECPKSigInvalidCount_Cnt_M_u16	36175
CONSANGLECPKSigValidCount_Cnt_M_u16	43304
CONSANGLECPK_Cnt_M_u16	13559
CONSANGLECPK_HwDeg_M_f32	415.114685
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	13559
CPKVehicleSpeedMsgTimer_mS_M_u32	984766720
CPKVehicleSpeedValidCount_Cnt_M_u16	59181
CityParkInputConsistentCount_Cnt_M_u16	45311
CityParkInputInvalidCount_Cnt_M_u16	27739
CityParkInputMsgTimer_mS_M_u32	1104420352
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3422652672
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	26391
ComputerRazGCTSigInvalidTimer_mS_M_u32	1142040832
ComputerRazGCTSigValidCount_Cnt_M_u16	16368
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	62535
DMDFCTCPKSigValidCount_Cnt_M_u16	1881
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56016
DMDRELAXECPKSigValidCount_Cnt_M_u16	28954
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	3816
DateInvalidTimer_mS_M_u32	3301361920
DiagMuxOnAbsentTimer_mS_M_u32	4225636608
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4124653824
ESPNTCEnableTimer_mS_M_u32	3378153728
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	34306
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	4
EffacDefaultDiagTimer_mS_M_u32[1]	3116805632
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2050
ElecIntTimer_mS_M_u32[1]	6072
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3756128512
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	59213
EtatMTSigValidCount_Cnt_M_u16	37010
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	18521
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	30642
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	36343
ISDAT4V2BSI552MsgTimer_mS_M_u32	3587127552
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	8031
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	15436

Name	Input Value
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	37010
ISDATBSI3F2MsgTimer_mS_M_u32	2027165952
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	28304
ISDATBSI412MsgLenValidCount_Cnt_M_u16	59885
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	59213
ISDATBSI412MsgTimer_mS_M_u32	3210041600
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	10112
ISDATBSI432MsgLenValidCount_Cnt_M_u16	42006
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	38118
ISDATDIRASentFltAcc_Cnt_M_u16	56778
ISDATDIRASentTimer_mS_M_u32	984766720
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	40557
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	36075
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	5954
ISDYN2CMMMsgTimer_mS_M_u32	2881259776
ISDYNAASChkSumInvalidCount_Cnt_M_u16	40461
ISDYNAASChkSumValidCount_Cnt_M_u16	28535
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	48614
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	10472
ISDYNAASMsgLenValidCount_Cnt_M_u16	52842
ISDYNAASMsgTimeValidCount_Cnt_M_u16	40461
ISDYNAASMsgTimer_mS_M_u32	3287738624
ISDYNABRChkSumInvalidCount_Cnt_M_u16	54208
ISDYNABRChkSumValidCount_Cnt_M_u16	26673
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	36744
ISDYNABRMsgCountValidCount_Cnt_M_u16	5938
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	34250
ISDYNABRMsgLenValidCount_Cnt_M_u16	38883
ISDYNABRMsgTimeValidCount_Cnt_M_u16	13559
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	663
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1211
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	37010
ISDYNCMM208MsgTimer_mS_M_u32	122374400
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2503
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1317
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	53985
ISDYNCMM388MsgTimer_mS_M_u32	966027520
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	25157
ISDYNVOLChkSumValidCount_Cnt_M_u16	27294
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	4157
ISDYNVOLMsgCountValidCount_Cnt_M_u16	20431
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	46983
ISDYNVOLMsgLenValidCount_Cnt_M_u16	58561
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	61548
ISDYNVOLMsgTimer_mS_M_u32	687745280
IgnOnTimer_mS_M_u32	3366480128
IgnTimeOff_Sec_M_u32	448491636
ManVehSpd_Kph_M_f32	348.303497
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	147
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	239
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4294967295
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	95
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3185867008
PrevISDATBSI412MsgDLCError_Cnt_M_u08	176
PrevISDATBSI412MsgRxTime_MSec_M_u32	3706235136
PrevISDATBSI432MsgDLCError_Cnt_M_u08	97
PrevISDATBSI432MsgRxTime_MSec_M_u32	3843983616
PrevISDATDIRAMsgTxTime_MSec_M_u32	3368855808
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	254
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3997219072
PrevISDYNAASMsgDLCError_Cnt_M_u08	217
PrevISDYNAASMsgRxTime_MSec_M_u32	980691200

Name	Input Value
PrevISDYNABRMsgDLCError_Cnt_M_u08	17
PrevISDYNABRMsgRxTime_MSec_M_u32	2977982720
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	186
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3626313984
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	101
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3924658432
PrevISDYNVOLMsgDLCError_Cnt_M_u08	55
PrevISDYNVOLMsgRxTime_MSec_M_u32	1536272640
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3779811584
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	438.501312
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	21214
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	42208
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	19427
VitesseVehicleBVRampValidCount_Cnt_M_u16	51109
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	55883
VitesseVehicleBVSigValidCount_Cnt_M_u16	42709
VitesseVehicleBV_Kph_M_f32	58.4813995
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	53985
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	55747
VitesseVehiculeRoues_Kph_M_f32	615.461792
k_AASNTCEnableTimeout_mS_u16	58506
k_AASNodeAbsentDiag_Cnt_str.Threshold	29638
k_AASNodeAbsentDiag_Cnt_str.PStep	13874
k_AASNodeAbsentDiag_Cnt_str.NStep	3216
k_AASNodeAbsentTimeout_mS_u16	61650
k_AASNodeTimeout_mS_u16	27616
k_ABSNodeTimeout_mS_u16	64312
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	9127
k_ANGLEVOLANTSigValidThresh_Cnt_u16	16253
k_AngleVolantInvalidThresh_Cnt_u16	2848
k_AngleVolantValidThresh_Cnt_u16	27739
k_BSI552MsgTimeout_mS_u16	40742
k_BSINTCEnableTimeout_mS_u16	49240
k_BSINodeAbsentDiag_Cnt_str.Threshold	23932
k_BSINodeAbsentDiag_Cnt_str.PStep	35369
k_BSINodeAbsentDiag_Cnt_str.NStep	13854
k_BSINodeAbsentTimeout_mS_u16	17524
k_BSINodeTimeout_mS_u16	38118
k_BattOvHi_Volt_f32	23.9405003
k_BattOvLo_Volt_f32	30.9025993
k_BattUvHi_Volt_f32	0.0737000033
k_BattUvLo_Volt_f32	12.5219002
k_CAVNTCEnableTimeout_mS_u16	32553
k_CAVNodeAbsentDiag_Cnt_str.Threshold	8983
k_CAVNodeAbsentDiag_Cnt_str.PStep	13172
k_CAVNodeAbsentDiag_Cnt_str.NStep	62084
k_CAVNodeAbsentTimeout_mS_u16	18127
k_CAVNodeTimeout_mS_u16	52795
k_CMM388MsgTimeout_mS_u16	27651
k_CMM388NTCEnableTimeout_mS_u16	43503
k_CMMNTCEnableTimeout_mS_u16	58423
k_CMMNodeAbsentDiag_Cnt_str.Threshold	9283
k_CMMNodeAbsentDiag_Cnt_str.PStep	2816
k_CMMNodeAbsentDiag_Cnt_str.NStep	47461
k_CMMNodeAbsentTimeout_mS_u16	13743
k_CONSANGLECPKMax_HwDeg_f32	203.339905
k_CONSANGLECPKMin_HwDeg_f32	-374.811707

Name	Input Value
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	23009
k_CONSANGLECPKSigValidThresh_Cnt_u16	41155
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	53630
k_CPKVehicleSpeedValidThresh_Cnt_u16	64607
k_CityParkInputInvalidThresh_Cnt_u16	56286
k_CityParkInputValidThresh_Cnt_u16	45311
k_ComputerRazGCTSigValidThresh_Cnt_u16	60125
k_CptTemporelSigValidThresh_Cnt_u16	19018
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	36042
k_DMDFCTCPKSigValidThresh_Cnt_u16	57059
k_DMDFCTCPKValidCount_Cnt_u16	14697
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	5954
k_DMDRELAXECPKSigValidThresh_Cnt_u16	148
k_DMDRelaxeConsistentThresh_Cnt_u16	26674
k_DateValidThresh_Cnt_u16	36343
k_DefaultVehSpd_Kph_f32	45.9217987
k_DiagMuxOnAbsentTimeout_mS_u16	11077
k_EMNodeTimeout_mS_u16	2248
k_ESPNTCEnableTimeout_mS_u16	22725
k_ESPNodeAbsentDiag_Cnt_str.Threshold	65394
k_ESPNodeAbsentDiag_Cnt_str.PStep	36433
k_ESPNodeAbsentDiag_Cnt_str.NStep	36614
k_ESPNodeAbsentTimeout_mS_u16	34007
k_EtatMTSigInvalidThresh_Cnt_u16	4035
k_EtatMTSigValidThresh_Cnt_u16	45172
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	40877
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	10323
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	62468
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	25752
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	10821
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	62372
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	51257
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	36239
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	40596
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	46059
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	25833
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	13589
k_ISDATDIRASentDiag_Cnt_str.Threshold	35133
k_ISDATDIRASentDiag_Cnt_str.PStep	50953
k_ISDATDIRASentDiag_Cnt_str.NStep	29456
k_ISDATDIRASentTimeout_mS_u16	31404
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	53318
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	8604
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	54785
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	23232
k_ISDYNAASChkSumValidThresh_Cnt_u16	12081
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	38536
k_ISDYNAASMsgCountValidThresh_Cnt_u16	24114
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	62420
k_ISDYNAASMsgLenValidThresh_Cnt_u16	34804
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	38053
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	10688
k_ISDYNABRChkSumValidThresh_Cnt_u16	26713
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	35905
k_ISDYNABRMsgCountValidThresh_Cnt_u16	1355
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46956
k_ISDYNABRMsgLenValidThresh_Cnt_u16	36098
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	33326
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	36594
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	47573
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	19523
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	50374
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	1936
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	17203
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	39223
k_ISDYNVOLChkSumValidThresh_Cnt_u16	37844
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	26011
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	12101
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	9017
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	9598
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	61253
k_IgnOnTimeout_mS_u16	9251
k_JDD2010Selected_Cnt_Igc	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_PowerCutVehSpdHighThresh_Kph_f32	232.301193
k_PowerCutVehSpdLowThresh_Kph_f32	83.3402023
k_PowerCutVehSpdLowTimeout_mS_u16	59046
k_VBattMaxAAS_Volt_f32	3.96810007
k_VBattMaxBSI_Volt_f32	22.5498009
k_VBattMaxCAV_Volt_f32	11.3092003
k_VBattMaxCMM388_Volt_f32	0.109499998
k_VBattMaxCMM_Volt_f32	14.8427
k_VBattMaxESP_Volt_f32	3.35540009
k_VBattMinAAS_Volt_f32	2.6960001
k_VBattMinBSI_Volt_f32	3.35540009
k_VBattMinCAV_Volt_f32	25.1613998
k_VBattMinCMM388_Volt_f32	16.0685997
k_VBattMinCMM_Volt_f32	29.1280003
k_VBattMinESP_Volt_f32	14.8427
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	22952
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	8886
k_VitesseVehicleBVRampValidThresh_Cnt_u16	38717
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	45470
k_VitesseVehicleBVSigValidThresh_Cnt_u16	21212
k_VitesseVehicleBVSpeedPassThresh_kph_f32	340.958801
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	50393
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	11547
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3301361920
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	176
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	16295
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3116805632
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	101
target_SrlComInput_Per1_Batt_Volt_f32.value	24.2831001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1659173120
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	60
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.369177431
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4229589248
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2556102912
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	243
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1747691776
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	211
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1401702656
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1115482368
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	486377728
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	115
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3406702848
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	61
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	169
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	80
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4268837120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	93
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	109
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	186
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	199
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	230
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3699992832
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1045039360
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	36
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2476386560
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	90
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	121
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	138
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3703470336
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1635
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.746192455
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	378642
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	79.2603989
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	47040

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3116805632	3116805632	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3116805632	3116805632	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3116805632	3116805632	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-626.824951	-626.824951	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3116805632	3116805632	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3116805632	3116805632	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3116805632	3116805632	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3116805632	3116805632	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3116805632	3116805632	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3116805632	3116805632	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	8983	8983	✔
CAVNodeAbsentTimer_mS_M_u32	3116805632	3116805632	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3116805632	3116805632	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3116805632	3116805632	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	9283	9283	✔
CMMNodeAbsentTimer_mS_M_u32	3116805632	3116805632	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	13559	13559	✔
CONSANGLECPK_HwDeg_M_f32	415.114685	415.114685 ± 0.0125	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3116805632	3116805632	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3116805632	3116805632	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3116805632	3116805632	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3116805632	3116805632	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3116805632	3116805632	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3116805632	3116805632	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3116805632	3116805632	✔
ESPNTCEnableTimer_mS_M_u32	3116805632	3116805632	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3116805632	3116805632	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4	4	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3116805632	3116805632	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3116805632	3116805632	✔
ElecIntTimer_mS_M_u32[1]	6072	6072	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3116805632	3116805632	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3116805632	3116805632	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3116805632	3116805632	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3116805632	3116805632	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3116805632	3116805632	✔
ISDATDIRASentFltAcc_Cnt_M_u16	35133	35133	✔
ISDATDIRASentTimer_mS_M_u32	3116805632	3116805632	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3116805632	3116805632	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3116805632	3116805632	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3116805632	3116805632	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3116805632	3116805632	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3116805632	3116805632	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3116805632	3116805632	✔
IgnOnTimer_mS_M_u32	3116805632	3116805632	✔
IgnTimeOff_Sec_M_u32	448491636	448491636	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	64	64	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4229589248	4229589248	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	186	186	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2556102912	2556102912	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	243	243	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1747691776	1747691776	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	211	211	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1401702656	1401702656	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3368855808	3368855808	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	486377728	486377728	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	115	115	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3406702848	3406702848	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	80	80	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4268837120	4268837120	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	230	230	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3699992832	3699992832	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1045039360	1045039360	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	36	36	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2476386560	2476386560	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3703470336	3703470336	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	438.501312	438.501312	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	58.4813995	58.4813995	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	615.461792	615.461792	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-626.824951	-626.824951	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	13559	13559	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	448491636	448491636	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	415.114685	415.114685 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	45.9217987	45.9217987	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.89 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1864677376
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	3895
AASNodeAbsentTimer_mS_M_u32	1480206336
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	12015
ANGLEVOLANTSigValidCount_Cnt_M_u16	43346
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	32108
AngleVolantMsgTimer_mS_M_u32	1864677376
AngleVolantValidCount_Cnt_M_u16	15872
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-60.285923
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	682878976
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3886966784
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2342934528

Name	Input Value
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3929479168
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	33918
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1859835904
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	1332
CAVNodeAbsentTimer_mS_M_u32	4012886016
CDD_SrlComVehSpd_Kph_G_f32	532.81842
CMM388NTCEnableTimer_mS_M_u32	2640447488
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1767229440
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	9532
CMMNodeAbsentTimer_mS_M_u32	43063296
CONSANGLECPKSigInvalidCount_Cnt_M_u16	54101
CONSANGLECPKSigValidCount_Cnt_M_u16	17032
CONSANGLECPK_Cnt_M_u16	39707
CONSANGLECPK_HwDeg_M_f32	-81.6746979
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	39707
CPKVehicleSpeedMsgTimer_mS_M_u32	1747695616
CPKVehicleSpeedValidCount_Cnt_M_u16	21440
CityParkInputConsistentCount_Cnt_M_u16	8644
CityParkInputInvalidCount_Cnt_M_u16	45231
CityParkInputMsgTimer_mS_M_u32	4229589248
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	754853888
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	22779
ComputerRazGCTSigInvalidTimer_mS_M_u32	1330399232
ComputerRazGCTSigValidCount_Cnt_M_u16	30961
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	51435
DMDFCTCPKSigValidCount_Cnt_M_u16	12918
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	32721
DMDRELAXECPKSigValidCount_Cnt_M_u16	16308
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	62090
DateInvalidTimer_mS_M_u32	3886966784
DiagMuxOnAbsentTimer_mS_M_u32	2208856064
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3929479168
ESPNTCEnableTimer_mS_M_u32	3639814144
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	5946
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	6
EffacDefaultDiagTimer_mS_M_u32[1]	7
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	9900
ElecIntTimer_mS_M_u32[1]	11002
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1058854912
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	4507
EtatMTSigValidCount_Cnt_M_u16	34954
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	18999
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	32490
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	38556
ISDAT4V2BSI552MsgTimer_mS_M_u32	2723485696
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	35045
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	17628
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	34954
ISDATBSI3F2MsgTimer_mS_M_u32	1690728448
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	61521
ISDATBSI412MsgLenValidCount_Cnt_M_u16	20728
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	4507
ISDATBSI412MsgTimer_mS_M_u32	641906688
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	53248

Name	Input Value
ISDATBSI432MsgLenValidCount_Cnt_M_u16	3326
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	29709
ISDATDIRASentFltAcc_Cnt_M_u16	10593
ISDATDIRASentTimer_mS_M_u32	1747695616
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	46777
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	15872
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	3066
ISDYN2CMMMsgTimer_mS_M_u32	969746432
ISDYNAASChkSumInvalidCount_Cnt_M_u16	3097
ISDYNAASChkSumValidCount_Cnt_M_u16	39580
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	22287
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	16391
ISDYNAASMsgLenValidCount_Cnt_M_u16	45634
ISDYNAASMsgTimeValidCount_Cnt_M_u16	3097
ISDYNAASMsgTimer_mS_M_u32	1386088448
ISDYNABRChkSumInvalidCount_Cnt_M_u16	44162
ISDYNABRChkSumValidCount_Cnt_M_u16	4589
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	58280
ISDYNABRMsgCountValidCount_Cnt_M_u16	20331
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	38372
ISDYNABRMsgLenValidCount_Cnt_M_u16	8791
ISDYNABRMsgTimeValidCount_Cnt_M_u16	39707
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	664
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1213
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	34954
ISDYNCMM208MsgTimer_mS_M_u32	3525371904
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2507
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1319
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	50206
ISDYNCMM388MsgTimer_mS_M_u32	1204127744
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	44147
ISDYNVOLChkSumValidCount_Cnt_M_u16	22054
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	52489
ISDYNVOLMsgCountValidCount_Cnt_M_u16	45332
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	54955
ISDYNVOLMsgLenValidCount_Cnt_M_u16	37310
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	9532
ISDYNVOLMsgTimer_mS_M_u32	1351108608
IgnOnTimer_mS_M_u32	3934881792
IgnTimeOff_Sec_M_u32	1923778390
ManVehSpd_Kph_M_f32	83.8423996
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	149
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	224
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2666288640
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	160
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3474282496
PrevISDATBSI412MsgDLCError_Cnt_M_u08	77
PrevISDATBSI412MsgRxTime_MSec_M_u32	4274571264
PrevISDATBSI432MsgDLCError_Cnt_M_u08	26
PrevISDATBSI432MsgRxTime_MSec_M_u32	2510759936
PrevISDATDIRAMsgTxTime_MSec_M_u32	3407661056
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	71
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4278228992
PrevISDYNAASMsgDLCError_Cnt_M_u08	133
PrevISDYNAASMsgRxTime_MSec_M_u32	1948665856
PrevISDYNABRMsgDLCError_Cnt_M_u08	25
PrevISDYNABRMsgRxTime_MSec_M_u32	2416019456
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	62
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2668840960
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	46
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2201626624
PrevISDYNVOLMsgDLCError_Cnt_M_u08	25

Name	Input Value
PrevISDYNVOLMsgRxTime_MSec_M_u32	1724762112
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	408991744
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	52.325901
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	6693
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	34528
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	33558
VitesseVehicleBVRampValidCount_Cnt_M_u16	29329
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	11616
VitesseVehicleBVSigValidCount_Cnt_M_u16	19075
VitesseVehicleBV_Kph_M_f32	236.077805
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	50206
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	37433
VitesseVehiculeRoues_Kph_M_f32	584.151306
k_AASNTCEnableTimeout_mS_u16	39010
k_AASNodeAbsentDiag_Cnt_str.Threshold	55282
k_AASNodeAbsentDiag_Cnt_str.PStep	47624
k_AASNodeAbsentDiag_Cnt_str.NStep	52614
k_AASNodeAbsentTimeout_mS_u16	28235
k_AASNodeTimeout_mS_u16	12768
k_ABSNodeTimeout_mS_u16	47128
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	14219
k_ANGLEVOLANTSigValidThresh_Cnt_u16	38601
k_AngleVolantInvalidThresh_Cnt_u16	32736
k_AngleVolantValidThresh_Cnt_u16	45231
k_BSI552MsgTimeout_mS_u16	36368
k_BSINTCEnableTimeout_mS_u16	25976
k_BSINodeAbsentDiag_Cnt_str.Threshold	23972
k_BSINodeAbsentDiag_Cnt_str.PStep	35352
k_BSINodeAbsentDiag_Cnt_str.NStep	13877
k_BSINodeAbsentTimeout_mS_u16	29924
k_BSINodeTimeout_mS_u16	29709
k_BattOvHi_Volt_f32	3.65339994
k_BattOvLo_Volt_f32	24.3761005
k_BattUvHi_Volt_f32	19.7119999
k_BattUvLo_Volt_f32	0.997799993
k_CAVNTCEnableTimeout_mS_u16	12357
k_CAVNodeAbsentDiag_Cnt_str.Threshold	45432
k_CAVNodeAbsentDiag_Cnt_str.PStep	50680
k_CAVNodeAbsentDiag_Cnt_str.NStep	39330
k_CAVNodeAbsentTimeout_mS_u16	16978
k_CAVNodeTimeout_mS_u16	49297
k_CMM388MsgTimeout_mS_u16	64055
k_CMM388NTCEnableTimeout_mS_u16	61555
k_CMMNTCEnableTimeout_mS_u16	39517
k_CMMNodeAbsentDiag_Cnt_str.Threshold	26587
k_CMMNodeAbsentDiag_Cnt_str.PStep	45565
k_CMMNodeAbsentDiag_Cnt_str.NStep	27238
k_CMMNodeAbsentTimeout_mS_u16	11893
k_CONSANGLECPKMax_HwDeg_f32	592.783691
k_CONSANGLECPKMin_HwDeg_f32	-3.37170005
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	12062
k_CONSANGLECPKSigValidThresh_Cnt_u16	15673
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	63750
k_CPKVehicleSpeedValidThresh_Cnt_u16	17124
k_CityParkInputInvalidThresh_Cnt_u16	35880
k_CityParkInputValidThresh_Cnt_u16	8644
k_ComputerRazGCTSigValidThresh_Cnt_u16	40555

Name	Input Value
k_CptTemporelSigValidThresh_Cnt_u16	37602
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	32996
k_DMDFCTCPKSigValidThresh_Cnt_u16	19799
k_DMDFCTCPKValidCount_Cnt_u16	2054
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	3066
k_DMDRELAXECPKSigValidThresh_Cnt_u16	62149
k_DMDRelaxeConsistentThresh_Cnt_u16	46059
k_DateValidThresh_Cnt_u16	38556
k_DefaultVehSpd_Kph_f32	252.995499
k_DiagMuxOnAbsentTimeout_mS_u16	28721
k_EMNodeTimeout_mS_u16	34026
k_ESPNTCEnableTimeout_mS_u16	25712
k_ESPNodeAbsentDiag_Cnt_str.Threshold	5935
k_ESPNodeAbsentDiag_Cnt_str.PStep	49642
k_ESPNodeAbsentDiag_Cnt_str.NStep	5219
k_ESPNodeAbsentTimeout_mS_u16	57597
k_EtatMTSigInvalidThresh_Cnt_u16	50297
k_EtatMTSigValidThresh_Cnt_u16	1316
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	2681
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	25416
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	44213
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	56634
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	40689
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	45333
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	4565
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	29843
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	47812
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	60991
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	11782
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	16834
k_ISDATDIRASentDiag_Cnt_str.Threshold	16262
k_ISDATDIRASentDiag_Cnt_str.PStep	18360
k_ISDATDIRASentDiag_Cnt_str.NStep	61565
k_ISDATDIRASentTimeout_mS_u16	26558
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	29743
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	32108
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	56508
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	6018
k_ISDYNAASChkSumValidThresh_Cnt_u16	48365
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	52904
k_ISDYNAASMsgCountValidThresh_Cnt_u16	31339
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	40006
k_ISDYNAASMsgLenValidThresh_Cnt_u16	11684
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	14161
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	514
k_ISDYNABRChkSumValidThresh_Cnt_u16	2293
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	28542
k_ISDYNABRMsgCountValidThresh_Cnt_u16	34593
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	53308
k_ISDYNABRMsgLenValidThresh_Cnt_u16	570
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	23672
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	46569
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	25218
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	56503
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	6639
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	54354
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	35879
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	52316
k_ISDYNVOLChkSumValidThresh_Cnt_u16	44867
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	7279
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	3249
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	3543
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	31174
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	10930
k_IgnOnTimeout_mS_u16	56216
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	58.3572998
k_PowerCutVehSpdLowThresh_Kph_f32	161.240097
k_PowerCutVehSpdLowTimeout_mS_u16	526
k_VBattMaxAAS_Volt_f32	7.78739977
k_VBattMaxBSI_Volt_f32	9.85680008
k_VBattMaxCAV_Volt_f32	9.45069981
k_VBattMaxCMM388_Volt_f32	30.7392006

Name	Input Value
k_VBattMaxCMM_Volt_f32	0.0425999984
k_VBattMaxESP_Volt_f32	16.941
k_VBattMinAAS_Volt_f32	7.83319998
k_VBattMinBSI_Volt_f32	16.941
k_VBattMinCAV_Volt_f32	7.43599987
k_VBattMinCMM388_Volt_f32	1.77909994
k_VBattMinCMM_Volt_f32	11.1662998
k_VBattMinESP_Volt_f32	0.0425999984
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	57353
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	6048
k_VitesseVehicleBVRampValidThresh_Cnt_u16	14345
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	33062
k_VitesseVehicleBVSigValidThresh_Cnt_u16	61485
k_VitesseVehicleBVSpeedPassThresh_kph_f32	317.392303
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	28724
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	39471
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3886966784
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	72
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	21945
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1384298752
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	46
target_SrlComInput_Per1_Batt_Volt_f32.value	9.87090015
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2182338560
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	35
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.994023204
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	252
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2553513984
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	233940992
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	122
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	687851520
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	828237824
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1863059456
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	705308672
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2857912320
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	62
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	129
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	147
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	161
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	225
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	78571520
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	60
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	70
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	89
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	127
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	246

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1927710720
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	149
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2552539136
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	582141952
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	88
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	129
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1518819328
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	344
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.535287678
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	547387
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	143.729599
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	62335

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1384298752	1384298752	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1384298752	1384298752	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	32110	32110	✔
AngleVolantMsgTimer_mS_M_u32	1384298752	1384298752	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-60.285923	-60.285923	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1384298752	1384298752	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1384298752	1384298752	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1384298752	1384298752	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1384298752	1384298752	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1384298752	1384298752	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1384298752	1384298752	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	45432	45432	✔
CAVNodeAbsentTimer_mS_M_u32	1384298752	1384298752	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1384298752	1384298752	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1384298752	1384298752	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	26587	26587	✔
CMMNodeAbsentTimer_mS_M_u32	1384298752	1384298752	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	39707	39707	✔
CONSANGLECPK_HwDeg_M_f32	-81.6746979	-81.6746979 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	39707	39707	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1747695616	1747695616	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	21440	21440	✔
CityParkInputConsistentCount_Cnt_M_u16	8644	8644	✔
CityParkInputInvalidCount_Cnt_M_u16	45231	45231	✔
CityParkInputMsgTimer_mS_M_u32	1384298752	1384298752	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1384298752	1384298752	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1384298752	1384298752	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1384298752	1384298752	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1384298752	1384298752	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1384298752	1384298752	✔
ESPNTCEnableTimer_mS_M_u32	1384298752	1384298752	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1384298752	1384298752	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	6	6	✔
EffacDefaultDiagTimer_mS_M_u32[1]	7	7	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	9900	9900	✔
ElecIntTimer_mS_M_u32[1]	11002	11002	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1384298752	1384298752	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1384298752	1384298752	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1384298752	1384298752	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1384298752	1384298752	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1384298752	1384298752	✔
ISDATDIRASentFltAcc_Cnt_M_u16	16262	16262	✔
ISDATDIRASentTimer_mS_M_u32	1384298752	1384298752	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1384298752	1384298752	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1384298752	1384298752	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1384298752	1384298752	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1384298752	1384298752	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1384298752	1384298752	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1384298752	1384298752	✔
IgnOnTimer_mS_M_u32	3934881792	3934881792	✔
IgnTimeOff_Sec_M_u32	1923778390	1923778390	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	252	252	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2553513984	2553513984	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	186	186	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	233940992	233940992	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	122	122	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	687851520	687851520	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	131	131	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	828237824	828237824	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3407661056	3407661056	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	144	144	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	705308672	705308672	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	37	37	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2857912320	2857912320	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	225	225	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	78571520	78571520	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	135	135	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1927710720	1927710720	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	149	149	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2552539136	2552539136	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	582141952	582141952	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1518819328	1518819328	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	52.325901	52.325901	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	236.077805	236.077805	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	584.151306	584.151306	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-60.285923	-60.285923	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	39707	39707	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1923778390	1923778390	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-81.6746979	-81.6746979 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.90 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	252746496
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	39129
AASNodeAbsentTimer_mS_M_u32	3046132480
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	48047
ANGLEVOLANTSigValidCount_Cnt_M_u16	50246
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	25146
AngleVolantMsgTimer_mS_M_u32	252746496
AngleVolantValidCount_Cnt_M_u16	6397
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-677.362732
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1529023232
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	674466560
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1208728320
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1599699712
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	46850
BattOk_Cnt_M_lgc	1

Name	Input Value
CAVNTCEnableTimer_mS_M_u32	275659520
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	13664
CAVNodeAbsentTimer_mS_M_u32	1328507648
CDD_SrlComVehSpd_Kph_G_f32	223.7733
CMM388NTCEnableTimer_mS_M_u32	3717769984
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	4173163264
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	11786
CMMNodeAbsentTimer_mS_M_u32	4266359552
CONSANGLECPKSigInvalidCount_Cnt_M_u16	38270
CONSANGLECPKSigValidCount_Cnt_M_u16	65445
CONSANGLECPK_Cnt_M_u16	492
CONSANGLECPK_HwDeg_M_f32	672.306091
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	492
CPKVehicleSpeedMsgTimer_mS_M_u32	4294679296
CPKVehicleSpeedValidCount_Cnt_M_u16	35364
CityParkInputConsistentCount_Cnt_M_u16	32177
CityParkInputInvalidCount_Cnt_M_u16	36335
CityParkInputMsgTimer_mS_M_u32	2553513984
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1195657984
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	52109
ComputerRazGCTSigInvalidTimer_mS_M_u32	1088023296
ComputerRazGCTSigValidCount_Cnt_M_u16	27690
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	13627
DMDFCTCPKSigValidCount_Cnt_M_u16	4187
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	53513
DMDRELAXECPKSigValidCount_Cnt_M_u16	2336
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	19423
DateInvalidTimer_mS_M_u32	674466560
DiagMuxOnAbsentTimer_mS_M_u32	2424658688
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1599699712
ESPNTCEnableTimer_mS_M_u32	1466256128
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	16333
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	1513789440
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	6454
ElecIntTimer_mS_M_u32[1]	8259
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	665336576
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	62956
EtatMTSigValidCount_Cnt_M_u16	14560
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	14552
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	21119
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	64489
ISDAT4V2BSI552MsgTimer_mS_M_u32	788495104
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	12685
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	50536
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	14560
ISDATBSI3F2MsgTimer_mS_M_u32	3844823808
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	64585
ISDATBSI412MsgLenValidCount_Cnt_M_u16	25108
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	62956
ISDATBSI412MsgTimer_mS_M_u32	3786840832
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	15806
ISDATBSI432MsgLenValidCount_Cnt_M_u16	28289
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	36053
ISDATDIRASentFltAcc_Cnt_M_u16	48345
ISDATDIRASentTimer_mS_M_u32	4294679296
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	42770

Name	Input Value
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	6397
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	26638
ISDYN2CMMMsgTimer_mS_M_u32	483871488
ISDYNAASChkSumInvalidCount_Cnt_M_u16	43571
ISDYNAASChkSumValidCount_Cnt_M_u16	63082
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	51664
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	37095
ISDYNAASMsgLenValidCount_Cnt_M_u16	4598
ISDYNAASMsgTimeValidCount_Cnt_M_u16	43571
ISDYNAASMsgTimer_mS_M_u32	2917444352
ISDYNABRChkSumInvalidCount_Cnt_M_u16	1144
ISDYNABRChkSumValidCount_Cnt_M_u16	27639
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	8070
ISDYNABRMsgCountValidCount_Cnt_M_u16	54269
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	18897
ISDYNABRMsgLenValidCount_Cnt_M_u16	23608
ISDYNABRMsgTimeValidCount_Cnt_M_u16	492
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	665
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1215
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	14560
ISDYNCMM208MsgTimer_mS_M_u32	1390152448
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2511
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1321
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	32419
ISDYNCMM388MsgTimer_mS_M_u32	3429772032
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	548
ISDYNVOLChkSumValidCount_Cnt_M_u16	48331
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	8417
ISDYNVOLMsgCountValidCount_Cnt_M_u16	35969
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	1402
ISDYNVOLMsgLenValidCount_Cnt_M_u16	3074
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	11786
ISDYNVOLMsgTimer_mS_M_u32	757459712
IgnOnTimer_mS_M_u32	4095879936
IgnTimeOff_Sec_M_u32	1955047833
ManVehSpd_Kph_M_f32	631.69928
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	151
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	204
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3759758080
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	92
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4190026496
PrevISDATBSI412MsgDLCError_Cnt_M_u08	120
PrevISDATBSI412MsgRxTime_MSec_M_u32	3294915328
PrevISDATBSI432MsgDLCError_Cnt_M_u08	116
PrevISDATBSI432MsgRxTime_MSec_M_u32	4048112384
PrevISDATDIRAMsgTxTime_MSec_M_u32	2942855936
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	231
PrevISDYN2CMMMsgRxTime_MSec_M_u32	654113536
PrevISDYNAASMsgDLCError_Cnt_M_u08	185
PrevISDYNAASMsgRxTime_MSec_M_u32	3125537536
PrevISDYNABRMsgDLCError_Cnt_M_u08	79
PrevISDYNABRMsgRxTime_MSec_M_u32	3820628736
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	128
PrevISDYNCMM208MsgRxTime_MSec_M_u32	763685632
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	219
PrevISDYNCMM388MsgRxTime_MSec_M_u32	881871616
PrevISDYNVOLMsgDLCError_Cnt_M_u08	245
PrevISDYNVOLMsgRxTime_MSec_M_u32	3763694336
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	56400640
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	9.01760006
PrevVitesseVehicleBVValid_Cnt_M_lgc	0

Name	Input Value
ResetTimers_Cnt_M_Igc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_Igc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	64141
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	35868
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_Igc	0
VehSpdSync_Cnt_M_Igc	1
VehTimeValid_Cnt_M_Igc	1
VehicleSpeedValid_Cnt_M_Igc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	50106
VitesseVehicleBVRampValidCount_Cnt_M_u16	52489
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	50268
VitesseVehicleBVSigValidCount_Cnt_M_u16	58547
VitesseVehicleBV_Kph_M_f32	357.66571
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	32419
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	27666
VitesseVehiculeRoues_Kph_M_f32	476.141388
k_AASNTCEnableTimeout_mS_u16	58903
k_AASNodeAbsentDiag_Cnt_str.Threshold	28571
k_AASNodeAbsentDiag_Cnt_str.PStep	44370
k_AASNodeAbsentDiag_Cnt_str.NStep	3854
k_AASNodeAbsentTimeout_mS_u16	29724
k_AASNodeTimeout_mS_u16	35612
k_ABSNodeTimeout_mS_u16	23476
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	62237
k_ANGLEVOLANTSigValidThresh_Cnt_u16	48416
k_AngleVolantInvalidThresh_Cnt_u16	7643
k_AngleVolantValidThresh_Cnt_u16	36335
k_BSI552MsgTimeout_mS_u16	38029
k_BSINTCEnableTimeout_mS_u16	23894
k_BSINodeAbsentDiag_Cnt_str.Threshold	24012
k_BSINodeAbsentDiag_Cnt_str.PStep	35335
k_BSINodeAbsentDiag_Cnt_str.NStep	13900
k_BSINodeAbsentTimeout_mS_u16	23506
k_BSINodeTimeout_mS_u16	36053
k_BattOvHi_Volt_f32	6.52699995
k_BattOvLo_Volt_f32	14.5321999
k_BattUvHi_Volt_f32	27.4771004
k_BattUvLo_Volt_f32	27.7285995
k_CAVNTCEnableTimeout_mS_u16	59181
k_CAVNodeAbsentDiag_Cnt_str.Threshold	3232
k_CAVNodeAbsentDiag_Cnt_str.PStep	24153
k_CAVNodeAbsentDiag_Cnt_str.NStep	4307
k_CAVNodeAbsentTimeout_mS_u16	30214
k_CAVNodeTimeout_mS_u16	48586
k_CMM388MsgTimeout_mS_u16	55257
k_CMM388NTCEnableTimeout_mS_u16	58661
k_CMMNTCEnableTimeout_mS_u16	56613
k_CMMNodeAbsentDiag_Cnt_str.Threshold	23487
k_CMMNodeAbsentDiag_Cnt_str.PStep	57937
k_CMMNodeAbsentDiag_Cnt_str.NStep	52814
k_CMMNodeAbsentTimeout_mS_u16	34654
k_CONSANGLECPKMax_HwDeg_f32	474.636108
k_CONSANGLECPKMin_HwDeg_f32	-101.066597
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	15779
k_CONSANGLECPKSigValidThresh_Cnt_u16	27410
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	19882
k_CPKVehicleSpeedValidThresh_Cnt_u16	4240
k_CityParkInputInvalidThresh_Cnt_u16	32134
k_CityParkInputValidThresh_Cnt_u16	32177
k_ComputerRazGCTSigValidThresh_Cnt_u16	35067
k_CptTemporelSigValidThresh_Cnt_u16	29526
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	35025
k_DMDFCTCPKSigValidThresh_Cnt_u16	56120
k_DMDFCTCPKValidCount_Cnt_u16	19562
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	26638

Name	Input Value
k_DMDRELAXECPKSigValidThresh_Cnt_u16	52078
k_DMDRelaxeConsistentThresh_Cnt_u16	40956
k_DateValidThresh_Cnt_u16	64489
k_DefaultVehSpd_Kph_f32	246.008698
k_DiagMuxOnAbsentTimeout_mS_u16	23210
k_EMNodeTimeout_mS_u16	5311
k_ESPNTCEnableTimeout_mS_u16	1964
k_ESPNodeAbsentDiag_Cnt_str.Threshold	2851
k_ESPNodeAbsentDiag_Cnt_str.PStep	25834
k_ESPNodeAbsentDiag_Cnt_str.NStep	53177
k_ESPNodeAbsentTimeout_mS_u16	36806
k_EtatMTSigInvalidThresh_Cnt_u16	22675
k_EtatMTSigValidThresh_Cnt_u16	11858
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	42321
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	49828
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	57566
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	51342
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	19241
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	51709
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	3135
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	52162
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	36210
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	39040
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	57579
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	6392
k_ISDATDIRASentDiag_Cnt_str.Threshold	8439
k_ISDATDIRASentDiag_Cnt_str.PStep	9111
k_ISDATDIRASentDiag_Cnt_str.NStep	33472
k_ISDATDIRASentTimeout_mS_u16	49860
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	30129
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	25146
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	52936
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	50040
k_ISDYNAASChkSumValidThresh_Cnt_u16	27383
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	24198
k_ISDYNAASMsgCountValidThresh_Cnt_u16	21245
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	17708
k_ISDYNAASMsgLenValidThresh_Cnt_u16	42960
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	64392
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	64887
k_ISDYNABRChkSumValidThresh_Cnt_u16	41054
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	62978
k_ISDYNABRMsgCountValidThresh_Cnt_u16	9945
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	11530
k_ISDYNABRMsgLenValidThresh_Cnt_u16	32461
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	49876
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	14145
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	43446
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	42647
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	64175
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	17222
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	56199
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	21544
k_ISDYNVOLChkSumValidThresh_Cnt_u16	13107
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	17454
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	35755
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	61752
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	21804
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	6055
k_IgnOnTimeout_mS_u16	5748
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	248.423294
k_PowerCutVehSpdLowThresh_Kph_f32	203.774796
k_PowerCutVehSpdLowTimeout_mS_u16	22803
k_VBattMaxAAS_Volt_f32	0.226999998
k_VBattMaxBSI_Volt_f32	18.5755005
k_VBattMaxCAV_Volt_f32	23.1774998
k_VBattMaxCMM388_Volt_f32	29.2437
k_VBattMaxCMM_Volt_f32	14.8247004
k_VBattMaxESP_Volt_f32	16.8199997
k_VBattMinAAS_Volt_f32	11.4011002
k_VBattMinBSI_Volt_f32	16.8199997
k_VBattMinCAV_Volt_f32	9.59560013

Name	Input Value
k_VBattMinCMM388_Volt_f32	26.3731995
k_VBattMinCMM_Volt_f32	17.5151997
k_VBattMinESP_Volt_f32	14.8247004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	6691
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	47902
k_VitesseVehicleBVRampValidThresh_Cnt_u16	57313
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	15307
k_VitesseVehicleBVSigValidThresh_Cnt_u16	63094
k_VitesseVehicleBVSpeedPassThresh_kph_f32	609.181885
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	62560
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	20015
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	674466560
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	122
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	61965
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1513789440
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	219
target_SrlComInput_Per1_Batt_Volt_f32.value	26.3866997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4207098624
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	143
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.105235264
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	321137408
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	147
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3530148608
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3787418368
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1764035328
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2426055424
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2149600000
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1605757696
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	111
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	114
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	202
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	226
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	101
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1932659456
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	142
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	216
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	56
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	252390144
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3218131712
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	227

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2158390016
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	94
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	170
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	195
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2674440960
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	263
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.200450614
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	706440
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	89.5562973
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	22143

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1513789440	1513789440	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1513789440	1513789440	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	25146	25146	✔
AngleVolantMsgTimer_mS_M_u32	1513789440	1513789440	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-677.362732	-677.362732	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1513789440	1513789440	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1513789440	1513789440	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1513789440	1513789440	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1513789440	1513789440	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1513789440	1513789440	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1513789440	1513789440	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	3232	3232	✔
CAVNodeAbsentTimer_mS_M_u32	1513789440	1513789440	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1513789440	1513789440	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1513789440	1513789440	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	23487	23487	✔
CMMNodeAbsentTimer_mS_M_u32	1513789440	1513789440	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	492	492	✔
CONSANGLECPK_HwDeg_M_f32	672.306091	672.306091 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	492	492	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4294679296	4294679296	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	35364	35364	✔
CityParkInputConsistentCount_Cnt_M_u16	32177	32177	✔
CityParkInputInvalidCount_Cnt_M_u16	36335	36335	✔
CityParkInputMsgTimer_mS_M_u32	1513789440	1513789440	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1513789440	1513789440	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1513789440	1513789440	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1513789440	1513789440	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1513789440	1513789440	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1513789440	1513789440	✔
ESPNTCEnableTimer_mS_M_u32	1513789440	1513789440	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1513789440	1513789440	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	8	8	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1513789440	1513789440	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	1513789440	1513789440	✔
ElecIntTimer_mS_M_u32[1]	8259	8259	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1513789440	1513789440	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1513789440	1513789440	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1513789440	1513789440	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1513789440	1513789440	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1513789440	1513789440	✔
ISDATDIRASentFltAcc_Cnt_M_u16	8439	8439	✔
ISDATDIRASentTimer_mS_M_u32	1513789440	1513789440	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1513789440	1513789440	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1513789440	1513789440	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1513789440	1513789440	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgTimer_mS_M_u32	1513789440	1513789440	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1513789440	1513789440	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1513789440	1513789440	✔
IgnOnTimer_mS_M_u32	4095879936	4095879936	✔
IgnTimeOff_Sec_M_u32	1955047833	1955047833	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	77	77	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	321137408	321137408	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	147	147	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3530148608	3530148608	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	21	21	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3787418368	3787418368	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	251	251	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1764035328	1764035328	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2942855936	2942855936	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2149600000	2149600000	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	151	151	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1605757696	1605757696	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	101	101	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1932659456	1932659456	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	56	56	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	252390144	252390144	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	143	143	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3218131712	3218131712	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2158390016	2158390016	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2674440960	2674440960	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	9.01760006	9.01760006	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	357.66571	357.66571	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	476.141388	476.141388	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-677.362732	-677.362732	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	492	492	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1955047833	1955047833	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	672.306091	672.306091 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	246.008698	246.008698	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.91 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	781775360
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	21311
AASNodeAbsentTimer_mS_M_u32	366600704
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	25787
ANGLEVOLANTSigValidCount_Cnt_M_u16	58294
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	47900
AngleVolantMsgTimer_mS_M_u32	781775360
AngleVolantValidCount_Cnt_M_u16	44369
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-223.69635
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3760300544
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1525686784
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3626471936
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	4181611008
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	32450
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	687870464
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	554
CAVNodeAbsentTimer_mS_M_u32	763134464
CDD_SrlComVehSpd_Kph_G_f32	59.4789009
CMM388NTCEnableTimer_mS_M_u32	3074474496
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3906109952
CMMNTCsEnabled_Cnt_M_lgc	0

© Report created by TESSY V3.1.13, report template V2.1

Name	Input Value
CMMNodeAbsentFltAcc_Cnt_M_u16	3562
CMMNodeAbsentTimer_mS_M_u32	1684558336
CONSANGLECPKSigInvalidCount_Cnt_M_u16	33359
CONSANGLECPKSigValidCount_Cnt_M_u16	7322
CONSANGLECPK_Cnt_M_u16	61893
CONSANGLECPK_HwDeg_M_f32	521.962891
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	61893
CPKVehicleSpeedMsgTimer_mS_M_u32	3352818176
CPKVehicleSpeedValidCount_Cnt_M_u16	58021
CityParkInputConsistentCount_Cnt_M_u16	20277
CityParkInputInvalidCount_Cnt_M_u16	59258
CityParkInputMsgTimer_mS_M_u32	321137408
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	817750528
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	35619
ComputerRazGCTSigInvalidTimer_mS_M_u32	578617856
ComputerRazGCTSigValidCount_Cnt_M_u16	42954
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	8598
DMDFCTCPKSigValidCount_Cnt_M_u16	18681
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	3245
DMDRELAXECPKSigValidCount_Cnt_M_u16	64808
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	9004
DateInvalidTimer_mS_M_u32	1525686784
DiagMuxOnAbsentTimer_mS_M_u32	1832563200
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4181611008
ESPNTCEnableTimer_mS_M_u32	3294290432
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	8545
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	11
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8976
ElecIntTimer_mS_M_u32[1]	15236
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1263669760
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	3908
EtatMTSigValidCount_Cnt_M_u16	20266
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	32833
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	3084
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	15951
ISDAT4V2BSI552MsgTimer_mS_M_u32	2722910720
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	30689
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	25871
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	20266
ISDATBSI3F2MsgTimer_mS_M_u32	2269688320
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	5295
ISDATBSI412MsgLenValidCount_Cnt_M_u16	19470
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	3908
ISDATBSI412MsgTimer_mS_M_u32	3467047424
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	44750
ISDATBSI432MsgLenValidCount_Cnt_M_u16	25925
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	4043
ISDATDIRASentFltAcc_Cnt_M_u16	36799
ISDATDIRASentTimer_mS_M_u32	3352818176
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	6739
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	44369
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	38173
ISDYN2CMMMsgTimer_mS_M_u32	3154436608
ISDYNAASChkSumInvalidCount_Cnt_M_u16	1841
ISDYNAASChkSumValidCount_Cnt_M_u16	15179
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	42712
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	52117
ISDYNAASMsgLenValidCount_Cnt_M_u16	49447

Name	Input Value
ISDYNAASMsgTimeValidCount_Cnt_M_u16	1841
ISDYNAASMsgTimer_mS_M_u32	1985790464
ISDYNABRChkSumInvalidCount_Cnt_M_u16	17889
ISDYNABRChkSumValidCount_Cnt_M_u16	18467
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	45880
ISDYNABRMsgCountValidCount_Cnt_M_u16	44690
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	29014
ISDYNABRMsgLenValidCount_Cnt_M_u16	4833
ISDYNABRMsgTimeValidCount_Cnt_M_u16	61893
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	666
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1217
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	20266
ISDYNCMM208MsgTimer_mS_M_u32	485925376
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2515
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1323
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	37983
ISDYNCMM388MsgTimer_mS_M_u32	549470720
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	21597
ISDYNVOLChkSumValidCount_Cnt_M_u16	64808
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	30372
ISDYNVOLMsgCountValidCount_Cnt_M_u16	60551
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	50266
ISDYNVOLMsgLenValidCount_Cnt_M_u16	2436
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	3562
ISDYNVOLMsgTimer_mS_M_u32	2375614976
IgnOnTimer_mS_M_u32	2040807936
IgnTimeOff_Sec_M_u32	1031323392
ManVehSpd_Kph_M_f32	340.027191
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	153
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	192
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3464409600
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	155
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1326354944
PrevISDATBSI412MsgDLCError_Cnt_M_u08	228
PrevISDATBSI412MsgRxTime_MSec_M_u32	3789390336
PrevISDATBSI432MsgDLCError_Cnt_M_u08	203
PrevISDATBSI432MsgRxTime_MSec_M_u32	2259608064
PrevISDATDIRAMsgTxTime_MSec_M_u32	819036672
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	132
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2421412352
PrevISDYNAASMsgDLCError_Cnt_M_u08	105
PrevISDYNAASMsgRxTime_MSec_M_u32	4263969280
PrevISDYNABRMsgDLCError_Cnt_M_u08	175
PrevISDYNABRMsgRxTime_MSec_M_u32	182206976
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	59
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3363570176
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	167
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2564416000
PrevISDYNVOLMsgDLCError_Cnt_M_u08	207
PrevISDYNVOLMsgRxTime_MSec_M_u32	2450162176
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2176119296
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	421.724792
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	42659
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	27317

Name	Input Value
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	16156
VitesseVehicleBVRampValidCount_Cnt_M_u16	39918
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	16052
VitesseVehicleBVSigValidCount_Cnt_M_u16	30319
VitesseVehicleBV_Kph_M_f32	614.109497
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	37983
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	50386
VitesseVehiculeRoues_Kph_M_f32	52.2943993
k_AASNTCEnableTimeout_mS_u16	45380
k_AASNodeAbsentDiag_Cnt_str.Threshold	3100
k_AASNodeAbsentDiag_Cnt_str.PStep	34574
k_AASNodeAbsentDiag_Cnt_str.NStep	27954
k_AASNodeAbsentTimeout_mS_u16	55284
k_AASNodeTimeout_mS_u16	28085
k_ABSNodeTimeout_mS_u16	53803
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	51889
k_ANGLEVOLANTSigValidThresh_Cnt_u16	46440
k_AngleVolantInvalidThresh_Cnt_u16	16183
k_AngleVolantValidThresh_Cnt_u16	59258
k_BSI552MsgTimeout_mS_u16	63329
k_BSINTCEnableTimeout_mS_u16	45062
k_BSINodeAbsentDiag_Cnt_str.Threshold	24052
k_BSINodeAbsentDiag_Cnt_str.PStep	35318
k_BSINodeAbsentDiag_Cnt_str.NStep	13923
k_BSINodeAbsentTimeout_mS_u16	11860
k_BSINodeTimeout_mS_u16	4043
k_BattOvHi_Volt_f32	7.33839989
k_BattOvLo_Volt_f32	0.302700013
k_BattUvHi_Volt_f32	29.6103001
k_BattUvLo_Volt_f32	1.52909994
k_CAVNTCEnableTimeout_mS_u16	21440
k_CAVNodeAbsentDiag_Cnt_str.Threshold	6214
k_CAVNodeAbsentDiag_Cnt_str.PStep	21873
k_CAVNodeAbsentDiag_Cnt_str.NStep	38299
k_CAVNodeAbsentTimeout_mS_u16	22584
k_CAVNodeTimeout_mS_u16	14699
k_CMM388MsgTimeout_mS_u16	38463
k_CMM388NTCEnableTimeout_mS_u16	40539
k_CMMNTCEnableTimeout_mS_u16	54553
k_CMMNodeAbsentDiag_Cnt_str.Threshold	62481
k_CMMNodeAbsentDiag_Cnt_str.PStep	4466
k_CMMNodeAbsentDiag_Cnt_str.NStep	60882
k_CMMNodeAbsentTimeout_mS_u16	41710
k_CONSANGLECPKMax_HwDeg_f32	753.715088
k_CONSANGLECPKMin_HwDeg_f32	-563.669983
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	22367
k_CONSANGLECPKSigValidThresh_Cnt_u16	51154
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	56843
k_CPKVehicleSpeedValidThresh_Cnt_u16	46042
k_CityParkInputInvalidThresh_Cnt_u16	37559
k_CityParkInputValidThresh_Cnt_u16	20277
k_ComputerRazGCTSigValidThresh_Cnt_u16	43415
k_CptTemporelSigValidThresh_Cnt_u16	37701
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	46166
k_DMDFCTCPKSigValidThresh_Cnt_u16	38369
k_DMDFCTCPKValidCount_Cnt_u16	24202
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	38173
k_DMDRELAXECPKSigValidThresh_Cnt_u16	9152
k_DMDRelaxeConsistentThresh_Cnt_u16	24086
k_DateValidThresh_Cnt_u16	15951
k_DefaultVehSpd_Kph_f32	200.2659
k_DiagMuxOnAbsentTimeout_mS_u16	24459
k_EMNodeTimeout_mS_u16	18572
k_ESPNTCEnableTimeout_mS_u16	47942
k_ESPNodeAbsentDiag_Cnt_str.Threshold	11715
k_ESPNodeAbsentDiag_Cnt_str.PStep	62087

Name	Input Value
k_ESPNodeAbsentDiag_Cnt_str.NStep	27505
k_ESPNodeAbsentTimeout_mS_u16	10678
k_EtatMTSigInvalidThresh_Cnt_u16	30096
k_EtatMTSigValidThresh_Cnt_u16	11538
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	13078
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	25564
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	6574
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	63198
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	6092
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	31635
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	34635
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	37250
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	36786
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	32265
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	36231
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	35745
k_ISDATDIRASentDiag_Cnt_str.Threshold	40897
k_ISDATDIRASentDiag_Cnt_str.PStep	9783
k_ISDATDIRASentDiag_Cnt_str.NStep	56404
k_ISDATDIRASentTimeout_mS_u16	15101
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	39286
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	47900
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	54770
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	2273
k_ISDYNAASChkSumValidThresh_Cnt_u16	19235
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	63032
k_ISDYNAASMsgCountValidThresh_Cnt_u16	12690
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	21445
k_ISDYNAASMsgLenValidThresh_Cnt_u16	59289
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39472
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	28260
k_ISDYNABRChkSumValidThresh_Cnt_u16	24175
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	49602
k_ISDYNABRMsgCountValidThresh_Cnt_u16	51197
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	4330
k_ISDYNABRMsgLenValidThresh_Cnt_u16	25697
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	40972
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	49287
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	104
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	51012
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	42939
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	26294
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	24242
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	18706
k_ISDYNVOLChkSumValidThresh_Cnt_u16	5297
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	55358
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	47367
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	19808
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	10822
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	25365
k_IgnOnTimeout_mS_u16	12846
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	145.522202
k_PowerCutVehSpdLowThresh_Kph_f32	255
k_PowerCutVehSpdLowTimeout_mS_u16	18512
k_VBattMaxAAS_Volt_f32	9.15359974
k_VBattMaxBSI_Volt_f32	12.4379997
k_VBattMaxCAV_Volt_f32	21.4806004
k_VBattMaxCMM388_Volt_f32	24.4871006
k_VBattMaxCMM_Volt_f32	24.2705002
k_VBattMaxESP_Volt_f32	25.2134991
k_VBattMinAAS_Volt_f32	7.69659996
k_VBattMinBSI_Volt_f32	25.2134991
k_VBattMinCAV_Volt_f32	22.1042004
k_VBattMinCMM388_Volt_f32	5.35179996
k_VBattMinCMM_Volt_f32	7.01440001
k_VBattMinESP_Volt_f32	24.2705002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	62496
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	14831
k_VitesseVehicleBVRampValidThresh_Cnt_u16	14756
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	32808
k_VitesseVehicleBVSigValidThresh_Cnt_u16	14566
k_VitesseVehicleBVSpeedPassThresh_kph_f32	342.201691

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	50474
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	12412
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1525686784
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	95
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	45
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2102328064
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	167
target_SrlComInput_Per1_Batt_Volt_f32.value	23.0014
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4261483008
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	214
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.127329618
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2761835008
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	88957440
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	163
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3050078720
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1041998336
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	641384960
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4129939968
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	904462848
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	36
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	100
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	170
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	212
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2482283008
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	44
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	58
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	110
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	216613376
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2568512000
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	890733056
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	72
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	249

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2249232896
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1816
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.342172503
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	127954
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	74.3731003
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	56013

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2102328064	2102328064	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2102328064	2102328064	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2102328064	2102328064	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-223.69635	-223.69635	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2102328064	2102328064	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2102328064	2102328064	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2102328064	2102328064	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2102328064	2102328064	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2102328064	2102328064	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2102328064	2102328064	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	6214	6214	✔
CAVNodeAbsentTimer_mS_M_u32	2102328064	2102328064	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2102328064	2102328064	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2102328064	2102328064	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	62481	62481	✔
CMMNodeAbsentTimer_mS_M_u32	2102328064	2102328064	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	61893	61893	✔
CONSANGLECPK_HwDeg_M_f32	521.962891	521.962891 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2102328064	2102328064	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2102328064	2102328064	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2102328064	2102328064	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2102328064	2102328064	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DateInvalidTimer_mS_M_u32	2102328064	2102328064	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2102328064	2102328064	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2102328064	2102328064	✔
ESPNTCEnableTimer_mS_M_u32	2102328064	2102328064	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2102328064	2102328064	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2102328064	2102328064	✔
EffacDefaultDiagTimer_mS_M_u32[1]	11	11	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2102328064	2102328064	✔
ElecIntTimer_mS_M_u32[1]	15236	15236	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1263669760	1263669760	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2102328064	2102328064	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2102328064	2102328064	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2102328064	2102328064	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2102328064	2102328064	✔
ISDATDIRASentFltAcc_Cnt_M_u16	40897	40897	✔
ISDATDIRASentTimer_mS_M_u32	2102328064	2102328064	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2102328064	2102328064	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2102328064	2102328064	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2102328064	2102328064	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2102328064	2102328064	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2102328064	2102328064	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2102328064	2102328064	✔
IgnOnTimer_mS_M_u32	2040807936	2040807936	✔
IgnTimeOff_Sec_M_u32	1031323392	1031323392	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	192	192	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2761835008	2761835008	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	107	107	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	88957440	88957440	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	163	163	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3050078720	3050078720	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	238	238	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1041998336	1041998336	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	819036672	819036672	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4129939968	4129939968	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	151	151	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	904462848	904462848	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	37	37	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2482283008	2482283008	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	90	90	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	216613376	216613376	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2568512000	2568512000	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	890733056	890733056	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2249232896	2249232896	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	421.724792	421.724792	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	614.109497	614.109497	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	52.2943993	52.2943993	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-223.69635	-223.69635	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	61893	61893	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1031323392	1031323392	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	521.962891	521.962891 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	200.2659	200.2659	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.92 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1631517696
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	20249
AASNodeAbsentTimer_mS_M_u32	3825691648
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	32889
ANGLEVOLANTSigValidCount_Cnt_M_u16	46279
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	48606
AngleVolantMsgTimer_mS_M_u32	1631517696
AngleVolantValidCount_Cnt_M_u16	54972
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-698.740417
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	646786048
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1540336640
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1212324864
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2953796608
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	17080
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	333388800
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	50777
CAVNodeAbsentTimer_mS_M_u32	3384740864
CDD_SrlComVehSpd_Kph_G_f32	95.2777023
CMM388NTCEnableTimer_mS_M_u32	1537559552
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1338313728
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	30623
CMMNodeAbsentTimer_mS_M_u32	2223594496
CONSANGLECPKSigInvalidCount_Cnt_M_u16	37035
CONSANGLECPKSigValidCount_Cnt_M_u16	15049
CONSANGLECPK_Cnt_M_u16	12620
CONSANGLECPK_HwDeg_M_f32	-706.606689

Name	Input Value
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	12620
CPKVehicleSpeedMsgTimer_mS_M_u32	1551236096
CPKVehicleSpeedValidCount_Cnt_M_u16	13507
CityParkInputConsistentCount_Cnt_M_u16	10176
CityParkInputInvalidCount_Cnt_M_u16	42031
CityParkInputMsgTimer_mS_M_u32	424410368
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1980460032
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	58909
ComputerRazGCTSigInvalidTimer_mS_M_u32	2596506624
ComputerRazGCTSigValidCount_Cnt_M_u16	52477
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	3883
DMDFCTCPKSigValidCount_Cnt_M_u16	28449
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	47099
DMDRELAXECPKSigValidCount_Cnt_M_u16	59849
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	112
DateInvalidTimer_mS_M_u32	1540336640
DiagMuxOnAbsentTimer_mS_M_u32	1257159680
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2953796608
ESPNTCEnableTimer_mS_M_u32	1854958592
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	17481
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	22
EffacDefaultDiagTimer_mS_M_u32[1]	23
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	979
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2562792448
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	50626
EtatMTSigValidCount_Cnt_M_u16	41564
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	52781
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	62923
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	65319
ISDAT4V2BSI552MsgTimer_mS_M_u32	1368218624
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	25162
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	38508
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	41564
ISDATBSI3F2MsgTimer_mS_M_u32	3849108480
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	44939
ISDATBSI412MsgLenValidCount_Cnt_M_u16	65373
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	50626
ISDATBSI412MsgTimer_mS_M_u32	2981952512
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	49059
ISDATBSI432MsgLenValidCount_Cnt_M_u16	18253
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	43266
ISDATDIRASentFltAcc_Cnt_M_u16	18582
ISDATDIRASentTimer_mS_M_u32	1551236096
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	20042
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	54972
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	63210
ISDYN2CMMMsgTimer_mS_M_u32	864709632
ISDYNAASChkSumInvalidCount_Cnt_M_u16	62107
ISDYNAASChkSumValidCount_Cnt_M_u16	34057
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	29819
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	21276
ISDYNAASMsgLenValidCount_Cnt_M_u16	29378
ISDYNAASMsgTimeValidCount_Cnt_M_u16	62107
ISDYNAASMsgTimer_mS_M_u32	1939950592
ISDYNABRChkSumInvalidCount_Cnt_M_u16	39370
ISDYNABRChkSumValidCount_Cnt_M_u16	43936
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	55002
ISDYNABRMsgCountValidCount_Cnt_M_u16	27272

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	53226
ISDYNABRMsgLenValidCount_Cnt_M_u16	47944
ISDYNABRMsgTimeValidCount_Cnt_M_u16	12620
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	668
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1221
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	41564
ISDYNCMM208MsgTimer_mS_M_u32	3523881984
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2523
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1327
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	42554
ISDYNCMM388MsgTimer_mS_M_u32	3709914112
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	41769
ISDYNVOLChkSumValidCount_Cnt_M_u16	53191
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	48297
ISDYNVOLMsgCountValidCount_Cnt_M_u16	57119
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	9994
ISDYNVOLMsgLenValidCount_Cnt_M_u16	54024
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	30623
ISDYNVOLMsgTimer_mS_M_u32	3200224256
IgnOnTimer_mS_M_u32	2636434432
IgnTimeOff_Sec_M_u32	558483065
ManVehSpd_Kph_M_f32	162.782898
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	157
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	150
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1448262656
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	71
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1315019776
PrevISDATBSI412MsgDLCError_Cnt_M_u08	199
PrevISDATBSI412MsgRxTime_MSec_M_u32	2301103104
PrevISDATBSI432MsgDLCError_Cnt_M_u08	88
PrevISDATBSI432MsgRxTime_MSec_M_u32	1669622784
PrevISDATDIRAMsgTxTime_MSec_M_u32	1874594816
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	26
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3151027200
PrevISDYNAASMsgDLCError_Cnt_M_u08	145
PrevISDYNAASMsgRxTime_MSec_M_u32	1673366528
PrevISDYNABRMsgDLCError_Cnt_M_u08	144
PrevISDYNABRMsgRxTime_MSec_M_u32	2015153152
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	189
PrevISDYNCMM208MsgRxTime_MSec_M_u32	146443264
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	95
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2131192832
PrevISDYNVOLMsgDLCError_Cnt_M_u08	243
PrevISDYNVOLMsgRxTime_MSec_M_u32	45943808
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2906323968
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	248.130997
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	46746
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	6336
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0

Name	Input Value
VehicleSpeedValid_Cnt_M_Igc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	15067
VitesseVehicleBVRampValidCount_Cnt_M_u16	64449
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	21050
VitesseVehicleBVSigValidCount_Cnt_M_u16	1352
VitesseVehicleBV_Kph_M_f32	641.275513
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	42554
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	55232
VitesseVehiculeRoues_Kph_M_f32	402.372498
k_AASNTCEnableTimeout_mS_u16	33987
k_AASNodeAbsentDiag_Cnt_str.Threshold	2914
k_AASNodeAbsentDiag_Cnt_str.PStep	42905
k_AASNodeAbsentDiag_Cnt_str.NStep	11022
k_AASNodeAbsentTimeout_mS_u16	36471
k_AASNodeTimeout_mS_u16	13248
k_ABSNodeTimeout_mS_u16	52328
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	62110
k_ANGLEVOLANTSigValidThresh_Cnt_u16	20616
k_AngleVolantInvalidThresh_Cnt_u16	16591
k_AngleVolantValidThresh_Cnt_u16	42031
k_BSI552MsgTimeout_mS_u16	46791
k_BSINTCEnableTimeout_mS_u16	35483
k_BSINodeAbsentDiag_Cnt_str.Threshold	24132
k_BSINodeAbsentDiag_Cnt_str.PStep	35284
k_BSINodeAbsentDiag_Cnt_str.NStep	13969
k_BSINodeAbsentTimeout_mS_u16	35542
k_BSINodeTimeout_mS_u16	43266
k_BattOvHi_Volt_f32	7.43979979
k_BattOvLo_Volt_f32	22.2586994
k_BattUvHi_Volt_f32	17.5841999
k_BattUvLo_Volt_f32	20.4734001
k_CAVNTCEnableTimeout_mS_u16	58021
k_CAVNodeAbsentDiag_Cnt_str.Threshold	37587
k_CAVNodeAbsentDiag_Cnt_str.PStep	58244
k_CAVNodeAbsentDiag_Cnt_str.NStep	60846
k_CAVNodeAbsentTimeout_mS_u16	31959
k_CAVNodeTimeout_mS_u16	24743
k_CMM388MsgTimeout_mS_u16	43545
k_CMM388NTCEnableTimeout_mS_u16	21269
k_CMMNTCEnableTimeout_mS_u16	26946
k_CMMNodeAbsentDiag_Cnt_str.Threshold	53697
k_CMMNodeAbsentDiag_Cnt_str.PStep	60888
k_CMMNodeAbsentDiag_Cnt_str.NStep	37740
k_CMMNodeAbsentTimeout_mS_u16	1724
k_CONSANGLECPKMax_HwDeg_f32	126.231796
k_CONSANGLECPKMin_HwDeg_f32	-226.111298
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	33082
k_CONSANGLECPKSigValidThresh_Cnt_u16	62144
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	5830
k_CPKVehicleSpeedValidThresh_Cnt_u16	49166
k_CityParkInputInvalidThresh_Cnt_u16	15696
k_CityParkInputValidThresh_Cnt_u16	10176
k_ComputerRazGCTSigValidThresh_Cnt_u16	4528
k_CptTemporelSigValidThresh_Cnt_u16	0
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	10986
k_DMDFCTCPKSigValidThresh_Cnt_u16	22088
k_DMDFCTCPKValidCount_Cnt_u16	24768
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	63210
k_DMDRELAXECPKSigValidThresh_Cnt_u16	63520
k_DMDRelaxeConsistentThresh_Cnt_u16	62758
k_DateValidThresh_Cnt_u16	65319
k_DefaultVehSpd_Kph_f32	77.2621002
k_DiagMuxOnAbsentTimeout_mS_u16	32066
k_EMNodeTimeout_mS_u16	20688
k_ESPNTCEnableTimeout_mS_u16	43093
k_ESPNodeAbsentDiag_Cnt_str.Threshold	26313
k_ESPNodeAbsentDiag_Cnt_str.PStep	46941
k_ESPNodeAbsentDiag_Cnt_str.NStep	40900
k_ESPNodeAbsentTimeout_mS_u16	964
k_EtatMTSigInvalidThresh_Cnt_u16	24305
k_EtatMTSigValidThresh_Cnt_u16	53255
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	35881
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	57506

Name	Input Value
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	28161
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	41263
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	42769
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	60815
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	9224
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	40306
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	18343
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	49072
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	43170
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	18447
k_ISDATDIRASentDiag_Cnt_str.Threshold	10018
k_ISDATDIRASentDiag_Cnt_str.PStep	33655
k_ISDATDIRASentDiag_Cnt_str.NStep	27435
k_ISDATDIRASentTimeout_mS_u16	38854
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	19596
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	48606
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	30817
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	29898
k_ISDYNAASChkSumValidThresh_Cnt_u16	50848
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	12762
k_ISDYNAASMsgCountValidThresh_Cnt_u16	1416
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	46798
k_ISDYNAASMsgLenValidThresh_Cnt_u16	7364
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39824
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	25960
k_ISDYNABRChkSumValidThresh_Cnt_u16	4934
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	40376
k_ISDYNABRMsgCountValidThresh_Cnt_u16	37702
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	37535
k_ISDYNABRMsgLenValidThresh_Cnt_u16	40777
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	17357
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	16286
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	8460
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	29127
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	56185
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	20423
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	38183
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	48902
k_ISDYNVOLChkSumValidThresh_Cnt_u16	17688
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	31246
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	17316
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	21694
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	46680
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	47645
k_IgnOnTimeout_mS_u16	20738
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	9.5692997
k_PowerCutVehSpdLowThresh_Kph_f32	55.0770988
k_PowerCutVehSpdLowTimeout_mS_u16	46127
k_VBattMaxAAS_Volt_f32	4.89319992
k_VBattMaxBSI_Volt_f32	28.3941994
k_VBattMaxCAV_Volt_f32	26.0531006
k_VBattMaxCMM388_Volt_f32	5.80249977
k_VBattMaxCMM_Volt_f32	13.3281002
k_VBattMaxESP_Volt_f32	14.5317001
k_VBattMinAAS_Volt_f32	7.95769978
k_VBattMinBSI_Volt_f32	4.12349987
k_VBattMinCAV_Volt_f32	2.46819997
k_VBattMinCMM388_Volt_f32	27.1375008
k_VBattMinCMM_Volt_f32	22.7010002
k_VBattMinESP_Volt_f32	13.3281002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	35974
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	56904
k_VitesseVehicleBVRampValidThresh_Cnt_u16	38825
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	27335
k_VitesseVehicleBVSigValidThresh_Cnt_u16	18169
k_VitesseVehicleBVSpeedPassThresh_kph_f32	318.236298
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	41305
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	58559
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1540336640
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	114

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	24339
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	961367296
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	95
target_SrlComInput_Per1_Batt_Volt_f32.value	7.12099981
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4175961088
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	54
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.54763031
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	193
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2951662592
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	176
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	991357952
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	344919040
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	149
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	72821760
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3530509312
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1188523008
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	697273344
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	135
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	167
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	218
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	220
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	230
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	248
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	821570560
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	134
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	229
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3532770304
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3845778432
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	255
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	103943168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	11
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	28
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	30
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	68
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	172
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	187
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	225680384
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2803
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.977086008

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	672624
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	5.72669983
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	39956

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	961367296	961367296	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	961367296	961367296	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	48606	48606	✔
AngleVolantMsgTimer_mS_M_u32	961367296	961367296	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-698.740417	-698.740417	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	646786048	646786048	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	961367296	961367296	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1212324864	1212324864	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	2953796608	2953796608	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	961367296	961367296	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	961367296	961367296	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	37587	37587	✔
CAVNodeAbsentTimer_mS_M_u32	961367296	961367296	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	961367296	961367296	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	961367296	961367296	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	53697	53697	✔
CMMNodeAbsentTimer_mS_M_u32	961367296	961367296	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	12620	12620	✔
CONSANGLECPK_HwDeg_M_f32	-706.606689	-706.606689 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	12620	12620	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1551236096	1551236096	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	13507	13507	✔
CityParkInputConsistentCount_Cnt_M_u16	10176	10176	✔
CityParkInputInvalidCount_Cnt_M_u16	42031	42031	✔
CityParkInputMsgTimer_mS_M_u32	961367296	961367296	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	961367296	961367296	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	961367296	961367296	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1540336640	1540336640	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	961367296	961367296	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	961367296	961367296	✔
ESPNTCEnableTimer_mS_M_u32	961367296	961367296	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	961367296	961367296	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	22	22	✔
EffacDefaultDiagTimer_mS_M_u32[1]	23	23	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	97	97	✔
ElecIntTimer_mS_M_u32[1]	979	979	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	961367296	961367296	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	52781	52781	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2951662592	2951662592	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	961367296	961367296	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	961367296	961367296	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	49060	49060	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	72821760	72821760	✔
ISDATDIRASentFltAcc_Cnt_M_u16	10018	10018	✔
ISDATDIRASentTimer_mS_M_u32	961367296	961367296	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	961367296	961367296	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	961367296	961367296	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	961367296	961367296	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	961367296	961367296	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	961367296	961367296	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	961367296	961367296	✔
IgnOnTimer_mS_M_u32	961367296	961367296	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
IgnTimeOff_Sec_M_u32	558483065	558483065	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	193	193	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2951662592	2951662592	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	176	176	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	991357952	991357952	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	9	9	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	344919040	344919040	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	149	149	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	72821760	72821760	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1874594816	1874594816	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	99	99	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1188523008	1188523008	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	53	53	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	697273344	697273344	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	168	168	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	821570560	821570560	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	168	168	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3532770304	3532770304	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	190	190	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3845778432	3845778432	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	255	255	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	103943168	103943168	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	225680384	225680384	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	248.130997	248.130997	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	641.275513	641.275513	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	402.372498	402.372498	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-698.740417	-698.740417	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	12620	12620	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	558483065	558483065	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-706.606689	-706.606689 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	77.2621002	77.2621002	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0139	0x0139	✔
Param	0x00	0x00	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
Status	0x00	0x00	✔
NTC	0x0161	0x0161	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0164	0x0164	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0160	0x0160	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.93 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1725026048
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	10050
AASNodeAbsentTimer_mS_M_u32	3426254592
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	46368
ANGLEVOLANTSigValidCount_Cnt_M_u16	64502
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	12019
AngleVolantMsgTimer_mS_M_u32	1725026048
AngleVolantValidCount_Cnt_M_u16	34008
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-455.91922
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1269251840
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3588210432
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3360091904
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3017846528

Name	Input Value
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	10851
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2003922688
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	51203
CAVNodeAbsentTimer_mS_M_u32	26320640
CDD_SrlComVehSpd_Kph_G_f32	475.130615
CMM388NTCEnableTimer_mS_M_u32	3034504960
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	125804288
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	51440
CMMNodeAbsentTimer_mS_M_u32	2658316032
CONSANGLECPKSigInvalidCount_Cnt_M_u16	31627
CONSANGLECPKSigValidCount_Cnt_M_u16	41201
CONSANGLECPK_Cnt_M_u16	35176
CONSANGLECPK_HwDeg_M_f32	-464.759003
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	35176
CPKVehicleSpeedMsgTimer_mS_M_u32	288149248
CPKVehicleSpeedValidCount_Cnt_M_u16	23981
CityParkInputConsistentCount_Cnt_M_u16	41420
CityParkInputInvalidCount_Cnt_M_u16	63871
CityParkInputMsgTimer_mS_M_u32	2951662592
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	640450304
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	29238
ComputerRazGCTSigInvalidTimer_mS_M_u32	1082400512
ComputerRazGCTSigValidCount_Cnt_M_u16	58901
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	43147
DMDFCTCPKSigValidCount_Cnt_M_u16	3177
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	38554
DMDRELAXECPKSigValidCount_Cnt_M_u16	58608
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	32828
DateInvalidTimer_mS_M_u32	3588210432
DiagMuxOnAbsentTimer_mS_M_u32	415403776
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3017846528
ESPNTCEnableTimer_mS_M_u32	2426240768
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	46771
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	28
EffacDefaultDiagTimer_mS_M_u32[1]	29
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	8
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	4039864064
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	31623
EtatMTSigValidCount_Cnt_M_u16	63865
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	19205
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	63467
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	62551
ISDAT4V2BSI552MsgTimer_mS_M_u32	1197911808
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	49005
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	22216
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	63865
ISDATBSI3F2MsgTimer_mS_M_u32	3242757888
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	10413
ISDATBSI412MsgLenValidCount_Cnt_M_u16	11511
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	31623
ISDATBSI412MsgTimer_mS_M_u32	3981954816
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	228
ISDATBSI432MsgLenValidCount_Cnt_M_u16	48551
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	1032

Name	Input Value
ISDATDIRASentFltAcc_Cnt_M_u16	30028
ISDATDIRASentTimer_mS_M_u32	288149248
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	43630
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	34008
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	44366
ISDYN2CMMMsgTimer_mS_M_u32	2846850816
ISDYNAASChkSumInvalidCount_Cnt_M_u16	50364
ISDYNAASChkSumValidCount_Cnt_M_u16	28978
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	26523
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	60858
ISDYNAASMsgLenValidCount_Cnt_M_u16	53896
ISDYNAASMsgTimeValidCount_Cnt_M_u16	50364
ISDYNAASMsgTimer_mS_M_u32	1558896384
ISDYNABRChkSumInvalidCount_Cnt_M_u16	41647
ISDYNABRChkSumValidCount_Cnt_M_u16	28909
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	54271
ISDYNABRMsgCountValidCount_Cnt_M_u16	31925
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	31182
ISDYNABRMsgLenValidCount_Cnt_M_u16	56180
ISDYNABRMsgTimeValidCount_Cnt_M_u16	35176
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	669
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1223
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	63865
ISDYNCMM208MsgTimer_mS_M_u32	2100313856
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2527
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1329
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	36446
ISDYNCMM388MsgTimer_mS_M_u32	2121031424
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	48145
ISDYNVOLChkSumValidCount_Cnt_M_u16	23031
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	6161
ISDYNVOLMsgCountValidCount_Cnt_M_u16	13423
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	21104
ISDYNVOLMsgLenValidCount_Cnt_M_u16	62006
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	51440
ISDYNVOLMsgTimer_mS_M_u32	3297779456
IgnOnTimer_mS_M_u32	1314938624
IgnTimeOff_Sec_M_u32	751446056
ManVehSpd_Kph_M_f32	348.889008
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	159
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	160
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2258013952
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	155
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4058640128
PrevISDATBSI412MsgDLCError_Cnt_M_u08	180
PrevISDATBSI412MsgRxTime_MSec_M_u32	2807471872
PrevISDATBSI432MsgDLCError_Cnt_M_u08	220
PrevISDATBSI432MsgRxTime_MSec_M_u32	2176941824
PrevISDATDIRAMsgTxTime_MSec_M_u32	1134206720
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	176
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1989947136
PrevISDYNAASMsgDLCError_Cnt_M_u08	170
PrevISDYNAASMsgRxTime_MSec_M_u32	1301683968
PrevISDYNABRMsgDLCError_Cnt_M_u08	221
PrevISDYNABRMsgRxTime_MSec_M_u32	2641911552
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	245
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2459901696
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	211
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4214783744
PrevISDYNVOLMsgDLCError_Cnt_M_u08	210
PrevISDYNVOLMsgRxTime_MSec_M_u32	3466043136
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1927139072

Name	Input Value
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	411.400513
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	15168
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	22670
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	62077
VitesseVehicleBVRampValidCount_Cnt_M_u16	62347
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	33757
VitesseVehicleBVSigValidCount_Cnt_M_u16	20083
VitesseVehicleBV_Kph_M_f32	583.10437
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	36446
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	48525
VitesseVehiculeRoues_Kph_M_f32	308.893707
k_AASNTCEnableTimeout_mS_u16	11011
k_AASNodeAbsentDiag_Cnt_str.Threshold	44954
k_AASNodeAbsentDiag_Cnt_str.PStep	31853
k_AASNodeAbsentDiag_Cnt_str.NStep	57286
k_AASNodeAbsentTimeout_mS_u16	2471
k_AASNodeTimeout_mS_u16	1934
k_ABSNodeTimeout_mS_u16	42196
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	5107
k_ANGLEVOLANTSigValidThresh_Cnt_u16	19958
k_AngleVolantInvalidThresh_Cnt_u16	22817
k_AngleVolantValidThresh_Cnt_u16	63871
k_BSI552MsgTimeout_mS_u16	64632
k_BSINTCEnableTimeout_mS_u16	32764
k_BSINodeAbsentDiag_Cnt_str.Threshold	24172
k_BSINodeAbsentDiag_Cnt_str.PStep	35267
k_BSINodeAbsentDiag_Cnt_str.NStep	13992
k_BSINodeAbsentTimeout_mS_u16	43019
k_BSINodeTimeout_mS_u16	1032
k_BattOvHi_Volt_f32	5.58589983
k_BattOvLo_Volt_f32	22.6697006
k_BattUvHi_Volt_f32	16.8567009
k_BattUvLo_Volt_f32	31.0091
k_CAVNTCEnableTimeout_mS_u16	38429
k_CAVNodeAbsentDiag_Cnt_str.Threshold	49761
k_CAVNodeAbsentDiag_Cnt_str.PStep	41219
k_CAVNodeAbsentDiag_Cnt_str.NStep	25983
k_CAVNodeAbsentTimeout_mS_u16	7305
k_CAVNodeTimeout_mS_u16	64407
k_CMM388MsgTimeout_mS_u16	5698
k_CMM388NTCEnableTimeout_mS_u16	2894
k_CMMNTCEnableTimeout_mS_u16	35461
k_CMMNodeAbsentDiag_Cnt_str.Threshold	44637
k_CMMNodeAbsentDiag_Cnt_str.PStep	52367
k_CMMNodeAbsentDiag_Cnt_str.NStep	4750
k_CMMNodeAbsentTimeout_mS_u16	8345
k_CONSANGLECPKMax_HwDeg_f32	355.193298
k_CONSANGLECPKMin_HwDeg_f32	-622.461792
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	64862
k_CONSANGLECPKSigValidThresh_Cnt_u16	27789
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	63100
k_CPKVehicleSpeedValidThresh_Cnt_u16	49956
k_CityParkInputInvalidThresh_Cnt_u16	20509
k_CityParkInputValidThresh_Cnt_u16	41420
k_ComputerRazGCTSigValidThresh_Cnt_u16	51515
k_CptTemporelSigValidThresh_Cnt_u16	65535
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	26830

Name	Input Value
k_DMDFCTCPKSigValidThresh_Cnt_u16	2676
k_DMDFCTCPKValidCount_Cnt_u16	61515
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	44366
k_DMDRELAXECPKSigValidThresh_Cnt_u16	11628
k_DMDRelaxeConsistentThresh_Cnt_u16	52826
k_DateValidThresh_Cnt_u16	62551
k_DefaultVehSpd_Kph_f32	91.2712021
k_DiagMuxOnAbsentTimeout_mS_u16	64902
k_EMNodeTimeout_mS_u16	3868
k_ESPNTCEnableTimeout_mS_u16	4623
k_ESPNodeAbsentDiag_Cnt_str.Threshold	55975
k_ESPNodeAbsentDiag_Cnt_str.PStep	57442
k_ESPNodeAbsentDiag_Cnt_str.NStep	47846
k_ESPNodeAbsentTimeout_mS_u16	18817
k_EtatMTSigInvalidThresh_Cnt_u16	44858
k_EtatMTSigValidThresh_Cnt_u16	24504
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	57939
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	30885
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	4873
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	54974
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	63705
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	32417
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	42933
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	36664
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	30936
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	28220
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	10022
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	49184
k_ISDATDIRASentDiag_Cnt_str.Threshold	19442
k_ISDATDIRASentDiag_Cnt_str.PStep	21420
k_ISDATDIRASentDiag_Cnt_str.NStep	27527
k_ISDATDIRASentTimeout_mS_u16	39099
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	59049
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	12019
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	53739
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	4527
k_ISDYNAASChkSumValidThresh_Cnt_u16	8173
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	49919
k_ISDYNAASMsgCountValidThresh_Cnt_u16	43957
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	23459
k_ISDYNAASMsgLenValidThresh_Cnt_u16	23682
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	36062
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	12628
k_ISDYNABRChkSumValidThresh_Cnt_u16	19322
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	6499
k_ISDYNABRMsgCountValidThresh_Cnt_u16	7289
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	30704
k_ISDYNABRMsgLenValidThresh_Cnt_u16	42419
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	59108
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	45108
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	6186
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	10617
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	42016
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	10998
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	1687
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	42556
k_ISDYNVOLChkSumValidThresh_Cnt_u16	1990
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	26980
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	47329
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	48787
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	44421
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	7029
k_IgnOnTimeout_mS_u16	57416
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	40.8498001
k_PowerCutVehSpdLowThresh_Kph_f32	40.3264008
k_PowerCutVehSpdLowTimeout_mS_u16	19647
k_VBattMaxAAS_Volt_f32	24.1285992
k_VBattMaxBSI_Volt_f32	28.7133999
k_VBattMaxCAV_Volt_f32	12.8238001
k_VBattMaxCMM388_Volt_f32	29.0384007
k_VBattMaxCMM_Volt_f32	25.2495995
k_VBattMaxESP_Volt_f32	32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinAAS_Volt_f32	7.16849995
k_VBattMinBSI_Volt_f32	2.35599995
k_VBattMinCAV_Volt_f32	11.8743
k_VBattMinCMM388_Volt_f32	21.2043991
k_VBattMinCMM_Volt_f32	14.1143999
k_VBattMinESP_Volt_f32	25.2495995
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	36539
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	19765
k_VitesseVehicleBVRampValidThresh_Cnt_u16	34577
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	35063
k_VitesseVehicleBVSigValidThresh_Cnt_u16	26657
k_VitesseVehicleBVSpeedPassThresh_kph_f32	335.044586
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	14083
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	45201
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3588210432
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	132
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	57039
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3106593792
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	211
target_SrlComInput_Per1_Batt_Volt_f32.value	11.3941002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	743862016
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	126
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.524267733
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3187826432
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1695153920
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1629593344
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	155
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1514749696
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4169195264
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3821567744
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3290439424
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	114
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	115
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	140
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	188
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	226
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2556837632
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	55
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	106
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	220
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	234
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2719571712

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2996895488
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	128
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3627589376
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	13
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	84
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	108
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	157
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	228
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2092166912
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	101
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0882499367
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	291358
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	249.627396
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	62162

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3106593792	3106593792	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3106593792	3106593792	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3106593792	3106593792	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-455.91922	-455.91922	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1269251840	1269251840	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	3106593792	3106593792	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3360091904	3360091904	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	3017846528	3017846528	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3106593792	3106593792	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3106593792	3106593792	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	49761	49761	✔
CAVNodeAbsentTimer_mS_M_u32	3106593792	3106593792	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3106593792	3106593792	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3106593792	3106593792	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	44637	44637	✔
CMMNodeAbsentTimer_mS_M_u32	3106593792	3106593792	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	35176	35176	✔
CONSANGLECPK_HwDeg_M_f32	-464.759003	-464.759003 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3106593792	3106593792	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3106593792	3106593792	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3106593792	3106593792	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3106593792	3106593792	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3106593792	3106593792	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3106593792	3106593792	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3106593792	3106593792	✔
ESPNTCEnableTimer_mS_M_u32	3106593792	3106593792	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3106593792	3106593792	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3106593792	3106593792	✔
EffacDefaultDiagTimer_mS_M_u32[1]	29	29	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3106593792	3106593792	✔
ElecIntTimer_mS_M_u32[1]	8	8	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3106593792	3106593792	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3187826432	3187826432	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1695153920	1695153920	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3106593792	3106593792	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1514749696	1514749696	✔
ISDATDIRASentFltAcc_Cnt_M_u16	19442	19442	✔
ISDATDIRASentTimer_mS_M_u32	3106593792	3106593792	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3106593792	3106593792	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3106593792	3106593792	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3106593792	3106593792	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3106593792	3106593792	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3106593792	3106593792	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3106593792	3106593792	✔
IgnOnTimer_mS_M_u32	3106593792	3106593792	✔
IgnTimeOff_Sec_M_u32	751446056	751446056	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	93	93	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3187826432	3187826432	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	57	57	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1695153920	1695153920	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	21	21	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1629593344	1629593344	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	155	155	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1514749696	1514749696	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1134206720	1134206720	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3821567744	3821567744	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	178	178	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3290439424	3290439424	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	37	37	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2556837632	2556837632	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	245	245	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2719571712	2719571712	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	90	90	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2996895488	2996895488	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	128	128	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3627589376	3627589376	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2092166912	2092166912	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	411.400513	411.400513	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	583.10437	583.10437	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	308.893707	308.893707	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-455.91922	-455.91922	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	35176	35176	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	751446056	751446056	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-464.759003	-464.759003 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	91.2712021	91.2712021	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.94 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3710211584
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	64979
AASNodeAbsentTimer_mS_M_u32	3820045824
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	60984
ANGLEVOLANTSigValidCount_Cnt_M_u16	28277
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	60096
AngleVolantMsgTimer_mS_M_u32	3710211584
AngleVolantValidCount_Cnt_M_u16	1935
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-214.379898
ApaRelaxReq_Cnt_M_lgc	0

Name	Input Value
BSI3F2NTCEnableTimer_mS_M_u32	2422539776
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1941669376
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1967519232
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1232647680
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	23151
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	835089920
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	2064
CAVNodeAbsentTimer_mS_M_u32	2418402816
CDD_SrlComVehSpd_Kph_G_f32	27.9256992
CMM388NTCEnableTimer_mS_M_u32	993928704
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3059475968
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	50952
CMMNodeAbsentTimer_mS_M_u32	1371715072
CONSANGLECPKSigInvalidCount_Cnt_M_u16	46584
CONSANGLECPKSigValidCount_Cnt_M_u16	55941
CONSANGLECPK_Cnt_M_u16	48416
CONSANGLECPK_HwDeg_M_f32	-690.008423
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	48416
CPKVehicleSpeedMsgTimer_mS_M_u32	169104896
CPKVehicleSpeedValidCount_Cnt_M_u16	17499
CityParkInputConsistentCount_Cnt_M_u16	32947
CityParkInputInvalidCount_Cnt_M_u16	4765
CityParkInputMsgTimer_mS_M_u32	3187826432
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2782217728
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	60663
ComputerRazGCTSigInvalidTimer_mS_M_u32	3176031744
ComputerRazGCTSigValidCount_Cnt_M_u16	6104
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	13689
DMDFCTCPKSigValidCount_Cnt_M_u16	32414
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	45514
DMDRELAXECPKSigValidCount_Cnt_M_u16	7047
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	44005
DateInvalidTimer_mS_M_u32	1941669376
DiagMuxOnAbsentTimer_mS_M_u32	2052265472
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1232647680
ESPNTCEnableTimer_mS_M_u32	1786922496
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	641
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	200
EffacDefaultDiagTimer_mS_M_u32[1]	300
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	21
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2914547200
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	55365
EtatMTSigValidCount_Cnt_M_u16	9006
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	44938
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	15767
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	65236
ISDAT4V2BSI552MsgTimer_mS_M_u32	652654080
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	49168
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	24258
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	9006
ISDATBSI3F2MsgTimer_mS_M_u32	415307264

Name	Input Value
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	37203
ISDATBSI412MsgLenValidCount_Cnt_M_u16	43316
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	55365
ISDATBSI412MsgTimer_mS_M_u32	3784529408
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	61228
ISDATBSI432MsgLenValidCount_Cnt_M_u16	48549
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	43009
ISDATDIRASentFltAcc_Cnt_M_u16	25653
ISDATDIRASentTimer_mS_M_u32	169104896
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	61966
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	1935
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	62256
ISDYN2CMMMsgTimer_mS_M_u32	3880535552
ISDYNAASChkSumInvalidCount_Cnt_M_u16	36197
ISDYNAASChkSumValidCount_Cnt_M_u16	23747
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	11078
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	13035
ISDYNAASMsgLenValidCount_Cnt_M_u16	47424
ISDYNAASMsgTimeValidCount_Cnt_M_u16	36197
ISDYNAASMsgTimer_mS_M_u32	1931093504
ISDYNABRChkSumInvalidCount_Cnt_M_u16	30987
ISDYNABRChkSumValidCount_Cnt_M_u16	785
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	11164
ISDYNABRMsgCountValidCount_Cnt_M_u16	1594
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	34607
ISDYNABRMsgLenValidCount_Cnt_M_u16	63228
ISDYNABRMsgTimeValidCount_Cnt_M_u16	48416
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	670
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1225
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	9006
ISDYNCMM208MsgTimer_mS_M_u32	1607075328
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2531
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1331
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	33533
ISDYNCMM388MsgTimer_mS_M_u32	4103448064
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	35942
ISDYNVOLChkSumValidCount_Cnt_M_u16	18291
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	32487
ISDYNVOLMsgCountValidCount_Cnt_M_u16	40588
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	25418
ISDYNVOLMsgLenValidCount_Cnt_M_u16	39096
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	50952
ISDYNVOLMsgTimer_mS_M_u32	1630168576
IgnOnTimer_mS_M_u32	1421452800
IgnTimeOff_Sec_M_u32	2226059985
ManVehSpd_Kph_M_f32	177.828903
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	161
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	160
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2161579520
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	138
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1146942976
PrevISDATBSI412MsgDLCError_Cnt_M_u08	112
PrevISDATBSI412MsgRxTime_MSec_M_u32	4074169856
PrevISDATBSI432MsgDLCError_Cnt_M_u08	109
PrevISDATBSI432MsgRxTime_MSec_M_u32	655771136
PrevISDATDIRAMsgTxTime_MSec_M_u32	772466176
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	163
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1330001408
PrevISDYNAASMsgDLCError_Cnt_M_u08	149
PrevISDYNAASMsgRxTime_MSec_M_u32	1578657280
PrevISDYNABRMsgDLCError_Cnt_M_u08	111
PrevISDYNABRMsgRxTime_MSec_M_u32	3346114048

Name	Input Value
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	72
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4076692992
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	98
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1454458368
PrevISDYNVOLMsgDLCError_Cnt_M_u08	45
PrevISDYNVOLMsgRxTime_MSec_M_u32	3239306752
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3909178880
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	347.307587
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57945
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	48942
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	61602
VitesseVehicleBVRampValidCount_Cnt_M_u16	8759
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	46593
VitesseVehicleBVSigValidCount_Cnt_M_u16	43774
VitesseVehicleBV_Kph_M_f32	373.163696
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	33533
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	43571
VitesseVehiculeRoues_Kph_M_f32	230.514404
k_AASNTCEnableTimeout_mS_u16	1103
k_AASNodeAbsentDiag_Cnt_str.Threshold	64814
k_AASNodeAbsentDiag_Cnt_str.PStep	37453
k_AASNodeAbsentDiag_Cnt_str.NStep	32539
k_AASNodeAbsentTimeout_mS_u16	29986
k_AASNodeTimeout_mS_u16	45614
k_ABSNodeTimeout_mS_u16	42142
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	45567
k_ANGLEVOLANTSigValidThresh_Cnt_u16	2232
k_AngleVolantInvalidThresh_Cnt_u16	21303
k_AngleVolantValidThresh_Cnt_u16	4765
k_BSI552MsgTimeout_mS_u16	22898
k_BSINTCEnableTimeout_mS_u16	53732
k_BSINodeAbsentDiag_Cnt_str.Threshold	24212
k_BSINodeAbsentDiag_Cnt_str.PStep	35250
k_BSINodeAbsentDiag_Cnt_str.NStep	14015
k_BSINodeAbsentTimeout_mS_u16	57208
k_BSINodeTimeout_mS_u16	43009
k_BattOvHi_Volt_f32	19.5324993
k_BattOvLo_Volt_f32	11.1594
k_BattUvHi_Volt_f32	23.1075993
k_BattUvLo_Volt_f32	9.69089985
k_CAVNTCEnableTimeout_mS_u16	13507
k_CAVNodeAbsentDiag_Cnt_str.Threshold	10642
k_CAVNodeAbsentDiag_Cnt_str.PStep	64386
k_CAVNodeAbsentDiag_Cnt_str.NStep	58663
k_CAVNodeAbsentTimeout_mS_u16	41598
k_CAVNodeTimeout_mS_u16	26068
k_CMM388MsgTimeout_mS_u16	12499
k_CMM388NTCEnableTimeout_mS_u16	33199
k_CMMNTCEnableTimeout_mS_u16	48840
k_CMMNodeAbsentDiag_Cnt_str.Threshold	35653
k_CMMNodeAbsentDiag_Cnt_str.PStep	47430
k_CMMNodeAbsentDiag_Cnt_str.NStep	8996
k_CMMNodeAbsentTimeout_mS_u16	45327
k_CONSANGLECPKMax_HwDeg_f32	397.588715
k_CONSANGLECPKMin_HwDeg_f32	-702.392517
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	13821
k_CONSANGLECPKSigValidThresh_Cnt_u16	40243

Name	Input Value
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	7524
k_CPKVehicleSpeedValidThresh_Cnt_u16	24046
k_CityParkInputInvalidThresh_Cnt_u16	43201
k_CityParkInputValidThresh_Cnt_u16	32947
k_ComputerRazGCTSigValidThresh_Cnt_u16	23206
k_CptTemporelSigValidThresh_Cnt_u16	46285
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	47663
k_DMDFCTCPKSigValidThresh_Cnt_u16	27132
k_DMDFCTCPKValidCount_Cnt_u16	43191
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	62256
k_DMDRELAXECPKSigValidThresh_Cnt_u16	59285
k_DMDRelaxeConsistentThresh_Cnt_u16	15563
k_DateValidThresh_Cnt_u16	65236
k_DefaultVehSpd_Kph_f32	214.290894
k_DiagMuxOnAbsentTimeout_mS_u16	22726
k_EMNodeTimeout_mS_u16	32581
k_ESPNTCEnableTimeout_mS_u16	23020
k_ESPNodeAbsentDiag_Cnt_str.Threshold	50247
k_ESPNodeAbsentDiag_Cnt_str.PStep	44208
k_ESPNodeAbsentDiag_Cnt_str.NStep	16891
k_ESPNodeAbsentTimeout_mS_u16	54871
k_EtatMTSigInvalidThresh_Cnt_u16	16234
k_EtatMTSigValidThresh_Cnt_u16	8880
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	30175
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	63401
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	24828
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	65053
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	64655
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	24439
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	32441
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	52466
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	22352
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	24228
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	55461
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	43001
k_ISDATDIRASentDiag_Cnt_str.Threshold	47455
k_ISDATDIRASentDiag_Cnt_str.PStep	11274
k_ISDATDIRASentDiag_Cnt_str.NStep	22417
k_ISDATDIRASentTimeout_mS_u16	50919
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	39006
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	60096
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	35416
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	11275
k_ISDYNAASChkSumValidThresh_Cnt_u16	62993
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	24220
k_ISDYNAASMsgCountValidThresh_Cnt_u16	31034
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	7727
k_ISDYNAASMsgLenValidThresh_Cnt_u16	33618
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	60416
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	63645
k_ISDYNABRChkSumValidThresh_Cnt_u16	16106
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	36207
k_ISDYNABRMsgCountValidThresh_Cnt_u16	55532
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	47624
k_ISDYNABRMsgLenValidThresh_Cnt_u16	13697
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	58795
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	21373
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	63196
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	47213
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	8504
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	57717
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	19285
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	5286
k_ISDYNVOLChkSumValidThresh_Cnt_u16	5319
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	61038
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	64309
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	16161
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	14090
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	33146
k_IgnOnTimeout_mS_u16	38530
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	102.055
k_PowerCutVehSpdLowThresh_Kph_f32	207.625305

Name	Input Value
k_PowerCutVehSpdLowTimeout_mS_u16	36635
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	24.0237007
k_VBattMaxCAV_Volt_f32	8.43159962
k_VBattMaxCMM388_Volt_f32	27.3992996
k_VBattMaxCMM_Volt_f32	15.4013996
k_VBattMaxESP_Volt_f32	26.6844997
k_VBattMinAAS_Volt_f32	7.22200012
k_VBattMinBSI_Volt_f32	2.56220007
k_VBattMinCAV_Volt_f32	28.3927002
k_VBattMinCMM388_Volt_f32	14.3885002
k_VBattMinCMM_Volt_f32	30.8568001
k_VBattMinESP_Volt_f32	15.4013996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	26664
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	4473
k_VitesseVehicleBVRampValidThresh_Cnt_u16	12775
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	47731
k_VitesseVehicleBVSigValidThresh_Cnt_u16	49588
k_VitesseVehicleBVSpeedPassThresh_kph_f32	174.495193
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	47888
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	33573
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1941669376
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	242
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	4279
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1720594176
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	98
target_SrlComInput_Per1_Batt_Volt_f32.value	17.7056999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3877074432
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	202
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.645101011
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	231974400
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1060947456
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2977293824
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1820263936
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2019042816
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3707848192
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	155
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2725930496
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	42
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	82
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	163
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	186
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	204
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1713899008
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	23

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	127
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	133
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	212
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2106500608
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1920452096
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1748035072
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	155
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	240
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1275000320
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	661
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.243160039
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	747134
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	163.972305
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	33699

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1720594176	1720594176	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1720594176	1720594176	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1720594176	1720594176	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-214.379898	-214.379898	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2422539776	2422539776	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1720594176	1720594176	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1967519232	1967519232	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	1232647680	1232647680	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1720594176	1720594176	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1720594176	1720594176	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	10642	10642	✔
CAVNodeAbsentTimer_mS_M_u32	1720594176	1720594176	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1720594176	1720594176	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1720594176	1720594176	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	35653	35653	✔
CMMNodeAbsentTimer_mS_M_u32	1720594176	1720594176	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	48416	48416	✔
CONSANGLECPK_HwDeg_M_f32	-690.008423	-690.008423 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CPKVehicleSpeedMsgTimer_mS_M_u32	1720594176	1720594176	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1720594176	1720594176	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1720594176	1720594176	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1720594176	1720594176	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1720594176	1720594176	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1720594176	1720594176	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1720594176	1720594176	✔
ESPNTCEnableTimer_mS_M_u32	1720594176	1720594176	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1720594176	1720594176	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	200	200	✔
EffacDefaultDiagTimer_mS_M_u32[1]	300	300	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	20	20	✔
ElecIntTimer_mS_M_u32[1]	21	21	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1720594176	1720594176	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	231974400	231974400	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1720594176	1720594176	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1720594176	1720594176	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1820263936	1820263936	✔
ISDATDIRASentFltAcc_Cnt_M_u16	47455	47455	✔
ISDATDIRASentTimer_mS_M_u32	1720594176	1720594176	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1720594176	1720594176	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1720594176	1720594176	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1720594176	1720594176	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1720594176	1720594176	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1720594176	1720594176	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1720594176	1720594176	✔
IgnOnTimer_mS_M_u32	1720594176	1720594176	✔
IgnTimeOff_Sec_M_u32	2226059985	2226059985	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	178	178	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	231974400	231974400	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1060947456	1060947456	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	215	215	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2977293824	2977293824	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	205	205	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1820263936	1820263936	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	772466176	772466176	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	167	167	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3707848192	3707848192	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	155	155	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2725930496	2725930496	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1713899008	1713899008	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	8	8	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2106500608	2106500608	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1920452096	1920452096	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	180	180	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1748035072	1748035072	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1275000320	1275000320	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	347.307587	347.307587	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VitesseVehicleBV_Kph_M_f32	373.163696	373.163696	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	230.514404	230.514404	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-214.379898	-214.379898	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	48416	48416	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2226059985	2226059985	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-690.008423	-690.008423 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	214.290894	214.290894	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0139	0x0139	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0161	0x0161	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.95 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	352764160
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	36091

Name	Input Value
AASNodeAbsentTimer_mS_M_u32	1562571008
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	60877
ANGLEVOLANTSigValidCount_Cnt_M_u16	28373
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	47668
AngleVolantMsgTimer_mS_M_u32	352764160
AngleVolantValidCount_Cnt_M_u16	2118
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-186.673508
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3590828288
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2785292544
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	388292864
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3582763264
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	17704
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2208522496
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	43205
CAVNodeAbsentTimer_mS_M_u32	1917128960
CDD_SrlComVehSpd_Kph_G_f32	71.8830032
CMM388NTCEnableTimer_mS_M_u32	570183936
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1470304512
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	9886
CMMNodeAbsentTimer_mS_M_u32	1689166080
CONSANGLECPKSigInvalidCount_Cnt_M_u16	17806
CONSANGLECPKSigValidCount_Cnt_M_u16	6566
CONSANGLECPK_Cnt_M_u16	40405
CONSANGLECPK_HwDeg_M_f32	338.546387
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	40405
CPKVehicleSpeedMsgTimer_mS_M_u32	171557120
CPKVehicleSpeedValidCount_Cnt_M_u16	7180
CityParkInputConsistentCount_Cnt_M_u16	11482
CityParkInputInvalidCount_Cnt_M_u16	44063
CityParkInputMsgTimer_mS_M_u32	231974400
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2797007104
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	20367
ComputerRazGCTSigInvalidTimer_mS_M_u32	751538432
ComputerRazGCTSigValidCount_Cnt_M_u16	15211
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	45963
DMDFCTCPKSigValidCount_Cnt_M_u16	31194
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	27415
DMDRELAXECPKSigValidCount_Cnt_M_u16	12191
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	22471
DateInvalidTimer_mS_M_u32	2785292544
DiagMuxOnAbsentTimer_mS_M_u32	612204800
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3582763264
ESPNTCEnableTimer_mS_M_u32	1286598912
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	26098
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	500
EffacDefaultDiagTimer_mS_M_u32[1]	600
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	555
ElecIntTimer_mS_M_u32[1]	5557
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1473077504
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1

Name	Input Value
EtatMTSigInvalidCount_Cnt_M_u16	30694
EtatMTSigValidCount_Cnt_M_u16	18666
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	8408
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	47216
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20792
ISDAT4V2BSI552MsgTimer_mS_M_u32	1967300864
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	42500
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	39856
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	18666
ISDATBSI3F2MsgTimer_mS_M_u32	2167636224
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	2877
ISDATBSI412MsgLenValidCount_Cnt_M_u16	21849
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	30694
ISDATBSI412MsgTimer_mS_M_u32	1069334784
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	15922
ISDATBSI432MsgLenValidCount_Cnt_M_u16	50310
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	52466
ISDATDIRASentFltAcc_Cnt_M_u16	26710
ISDATDIRASentTimer_mS_M_u32	171557120
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	14091
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	2118
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	5734
ISDYN2CMMMsgTimer_mS_M_u32	2119299328
ISDYNAASChkSumInvalidCount_Cnt_M_u16	42565
ISDYNAASChkSumValidCount_Cnt_M_u16	47596
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	14625
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	21556
ISDYNAASMsgLenValidCount_Cnt_M_u16	8948
ISDYNAASMsgTimeValidCount_Cnt_M_u16	42565
ISDYNAASMsgTimer_mS_M_u32	3932705024
ISDYNABRChkSumInvalidCount_Cnt_M_u16	21203
ISDYNABRChkSumValidCount_Cnt_M_u16	54915
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	26528
ISDYNABRMsgCountValidCount_Cnt_M_u16	22919
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	28137
ISDYNABRMsgLenValidCount_Cnt_M_u16	24641
ISDYNABRMsgTimeValidCount_Cnt_M_u16	40405
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	671
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1227
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	18666
ISDYNCMM208MsgTimer_mS_M_u32	1004056832
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2535
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1333
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	52732
ISDYNCMM388MsgTimer_mS_M_u32	3019231488
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	64068
ISDYNVOLChkSumValidCount_Cnt_M_u16	2780
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	3905
ISDYNVOLMsgCountValidCount_Cnt_M_u16	21008
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	42903
ISDYNVOLMsgLenValidCount_Cnt_M_u16	51470
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	9886
ISDYNVOLMsgTimer_mS_M_u32	2973208832
IgnOnTimer_mS_M_u32	596234496
IgnTimeOff_Sec_M_u32	1794330487
ManVehSpd_Kph_M_f32	308.638397
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	163
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	120
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	552698112
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	47
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3319783680
PrevISDATBSI412MsgDLCError_Cnt_M_u08	226

Name	Input Value
PrevISDATBSI412MsgRxTime_MSec_M_u32	1311904000
PrevISDATBSI432MsgDLCError_Cnt_M_u08	143
PrevISDATBSI432MsgRxTime_MSec_M_u32	1727262976
PrevISDATDIRAMsgTxTime_MSec_M_u32	1821774080
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	215
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3659800832
PrevISDYNAASMsgDLCError_Cnt_M_u08	100
PrevISDYNAASMsgRxTime_MSec_M_u32	4067266816
PrevISDYNABRMsgDLCError_Cnt_M_u08	123
PrevISDYNABRMsgRxTime_MSec_M_u32	2875314432
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	145
PrevISDYNCMM208MsgRxTime_MSec_M_u32	129929472
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	34
PrevISDYNCMM388MsgRxTime_MSec_M_u32	69398784
PrevISDYNVOLMsgDLCError_Cnt_M_u08	103
PrevISDYNVOLMsgRxTime_MSec_M_u32	393941248
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1634910464
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	41.8431015
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	32234
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	18730
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	46863
VitesseVehicleBVRampValidCount_Cnt_M_u16	33807
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	64114
VitesseVehicleBVSigValidCount_Cnt_M_u16	7482
VitesseVehicleBV_Kph_M_f32	310.391602
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	52732
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	14876
VitesseVehiculeRoues_Kph_M_f32	352.483185
k_AASNTCEnableTimeout_mS_u16	17480
k_AASNodeAbsentDiag_Cnt_str.Threshold	21949
k_AASNodeAbsentDiag_Cnt_str.PStep	921
k_AASNodeAbsentDiag_Cnt_str.NStep	22696
k_AASNodeAbsentTimeout_mS_u16	52109
k_AASNodeTimeout_mS_u16	28714
k_ABSNodeTimeout_mS_u16	14876
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	441
k_ANGLEVOLANTSigValidThresh_Cnt_u16	61261
k_AngleVolantInvalidThresh_Cnt_u16	52176
k_AngleVolantValidThresh_Cnt_u16	44063
k_BSI552MsgTimeout_mS_u16	59487
k_BSINTCEnableTimeout_mS_u16	30218
k_BSINodeAbsentDiag_Cnt_str.Threshold	24252
k_BSINodeAbsentDiag_Cnt_str.PStep	35233
k_BSINodeAbsentDiag_Cnt_str.NStep	14038
k_BSINodeAbsentTimeout_mS_u16	48140
k_BSINodeTimeout_mS_u16	52466
k_BattOvHi_Volt_f32	23.6317997
k_BattOvLo_Volt_f32	17.6159
k_BattUvHi_Volt_f32	30.7434998
k_BattUvLo_Volt_f32	16.3717995
k_CAVNTCEnableTimeout_mS_u16	23981
k_CAVNodeAbsentDiag_Cnt_str.Threshold	33387
k_CAVNodeAbsentDiag_Cnt_str.PStep	8978
k_CAVNodeAbsentDiag_Cnt_str.NStep	8413
k_CAVNodeAbsentTimeout_mS_u16	4475
k_CAVNodeTimeout_mS_u16	42490
k_CMM388MsgTimeout_mS_u16	62459

Name	Input Value
k_CMM388NTCEnableTimeout_mS_u16	29031
k_CMMNTCEnableTimeout_mS_u16	35292
k_CMMNodeAbsentDiag_Cnt_str.Threshold	35929
k_CMMNodeAbsentDiag_Cnt_str.PStep	51342
k_CMMNodeAbsentDiag_Cnt_str.NStep	14188
k_CMMNodeAbsentTimeout_mS_u16	38280
k_CONSANGLECPKMax_HwDeg_f32	572.000671
k_CONSANGLECPKMin_HwDeg_f32	-414.216797
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	46332
k_CONSANGLECPKSigValidThresh_Cnt_u16	24860
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	34440
k_CPKVehicleSpeedValidThresh_Cnt_u16	53612
k_CityParkInputInvalidThresh_Cnt_u16	7089
k_CityParkInputValidThresh_Cnt_u16	11482
k_ComputerRazGCTSigValidThresh_Cnt_u16	0
k_CptTemporelSigValidThresh_Cnt_u16	63086
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	54505
k_DMDFCTCPKSigValidThresh_Cnt_u16	1857
k_DMDFCTCPKValidCount_Cnt_u16	31312
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	5734
k_DMDRELAXECPKSigValidThresh_Cnt_u16	56053
k_DMDRelaxeConsistentThresh_Cnt_u16	13139
k_DateValidThresh_Cnt_u16	20792
k_DefaultVehSpd_Kph_f32	166.091293
k_DiagMuxOnAbsentTimeout_mS_u16	58083
k_EMNodeTimeout_mS_u16	23975
k_ESPNTCEnableTimeout_mS_u16	9009
k_ESPNodeAbsentDiag_Cnt_str.Threshold	10163
k_ESPNodeAbsentDiag_Cnt_str.PStep	57778
k_ESPNodeAbsentDiag_Cnt_str.NStep	4937
k_ESPNodeAbsentTimeout_mS_u16	17840
k_EtatMTSigInvalidThresh_Cnt_u16	15286
k_EtatMTSigValidThresh_Cnt_u16	45990
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	10519
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	54650
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	61439
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	24541
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	13897
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	12497
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	907
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	2719
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	38342
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	51529
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	27908
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	12362
k_ISDATDIRASentDiag_Cnt_str.Threshold	19845
k_ISDATDIRASentDiag_Cnt_str.PStep	47099
k_ISDATDIRASentDiag_Cnt_str.NStep	15389
k_ISDATDIRASentTimeout_mS_u16	55615
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	13083
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	47668
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	16877
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	14803
k_ISDYNAASChkSumValidThresh_Cnt_u16	64899
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	52896
k_ISDYNAASMsgCountValidThresh_Cnt_u16	135
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	62311
k_ISDYNAASMsgLenValidThresh_Cnt_u16	36030
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	25973
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	20895
k_ISDYNABRChkSumValidThresh_Cnt_u16	49271
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	44072
k_ISDYNABRMsgCountValidThresh_Cnt_u16	52080
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	19870
k_ISDYNABRMsgLenValidThresh_Cnt_u16	52466
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	24883
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	47742
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16034
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	6509
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	21709
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	5589
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	57847
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	36164

Name	Input Value
k_ISDYNVOLChkSumValidThresh_Cnt_u16	7840
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	38443
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	32279
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	45906
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	32086
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	57670
k_IgnOnTimeout_mS_u16	30640
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	13.2988005
k_PowerCutVehSpdLowThresh_Kph_f32	152.587906
k_PowerCutVehSpdLowTimeout_mS_u16	54244
k_VBattMaxAAS_Volt_f32	15.6317997
k_VBattMaxBSI_Volt_f32	22.4769993
k_VBattMaxCAV_Volt_f32	28.0354996
k_VBattMaxCMM388_Volt_f32	32
k_VBattMaxCMM_Volt_f32	6.38500023
k_VBattMaxESP_Volt_f32	4.8586998
k_VBattMinAAS_Volt_f32	20.1917
k_VBattMinBSI_Volt_f32	4.8586998
k_VBattMinCAV_Volt_f32	15.8154001
k_VBattMinCMM388_Volt_f32	15.8689003
k_VBattMinCMM_Volt_f32	13.8694
k_VBattMinESP_Volt_f32	6.38500023
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	27581
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	49545
k_VitesseVehicleBVRampValidThresh_Cnt_u16	63041
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	45532
k_VitesseVehicleBVSigValidThresh_Cnt_u16	44503
k_VitesseVehicleBVSpeedPassThresh_kph_f32	453.240509
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	36805
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	39237
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2785292544
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	105
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	55212
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3346019840
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	34
target_SrlComInput_Per1_Batt_Volt_f32.value	11.3785
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3887096064
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	170
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.999626935
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	98
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3762016512
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	243
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3632296192
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	13
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1314197760
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	700035328
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1387155712
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2972905728
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	759664896
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	108
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	134

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	177
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	182
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	549368064
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	11
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	174
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1024119040
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	114
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3939463424
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3592687872
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	145
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3069829376
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	317
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.722154558
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	507698
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	66.7970963
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	16908

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3346019840	3346019840	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	21949	21949	✔
AASNodeAbsentTimer_mS_M_u32	3346019840	3346019840	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3346019840	3346019840	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-186.673508	-186.673508	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3590828288	3590828288	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	2785292544	2785292544	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	388292864	388292864	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	3582763264	3582763264	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3346019840	3346019840	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3346019840	3346019840	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3346019840	3346019840	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3346019840	3346019840	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CMMNTCEnableTimer_mS_M_u32	3346019840	3346019840	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2972905728	2972905728	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	40405	40405	✔
CONSANGLECPK_HwDeg_M_f32	338.546387	338.546387 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3346019840	3346019840	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3346019840	3346019840	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3346019840	3346019840	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3346019840	3346019840	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3346019840	3346019840	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3346019840	3346019840	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3346019840	3346019840	✔
ESPNTCEnableTimer_mS_M_u32	3346019840	3346019840	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	10163	10163	✔
ESPNodeAbsentTimer_mS_M_u32	3346019840	3346019840	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	500	500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	600	600	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	555	555	✔
ElecIntTimer_mS_M_u32[1]	5557	5557	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3346019840	3346019840	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3762016512	3762016512	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3346019840	3346019840	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1314197760	1314197760	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	700035328	700035328	✔
ISDATDIRASentFltAcc_Cnt_M_u16	19845	19845	✔
ISDATDIRASentTimer_mS_M_u32	3346019840	3346019840	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3346019840	3346019840	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3346019840	3346019840	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3346019840	3346019840	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3346019840	3346019840	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3346019840	3346019840	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3346019840	3346019840	✔
IgnOnTimer_mS_M_u32	596234496	596234496	✔
IgnTimeOff_Sec_M_u32	1794330487	1794330487	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	98	98	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3762016512	3762016512	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	243	243	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3632296192	3632296192	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	13	13	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1314197760	1314197760	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	152	152	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	700035328	700035328	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1821774080	1821774080	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2972905728	2972905728	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	245	245	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	759664896	759664896	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	57	57	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	549368064	549368064	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	12	12	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1024119040	1024119040	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	114	114	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3939463424	3939463424	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	34	34	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3592687872	3592687872	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3069829376	3069829376	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	41.8431015	41.8431015	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	310.391602	310.391602	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	352.483185	352.483185	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-186.673508	-186.673508	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	40405	40405	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1794330487	1794330487	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	338.546387	338.546387 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	166.091293	166.091293	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0139	0x0139	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0165	0x0165	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.96 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	214859776
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	5873
AASNodeAbsentTimer_mS_M_u32	557445120
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	24185
ANGLEVOLANTSigValidCount_Cnt_M_u16	54818
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	45894
AngleVolantMsgTimer_mS_M_u32	214859776
AngleVolantValidCount_Cnt_M_u16	56206
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-482.872772
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	965455872
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1536569344
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2801016832
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3132940288
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	33896
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2071502848
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	5138
CAVNodeAbsentTimer_mS_M_u32	2454949888
CDD_SrlComVehSpd_Kph_G_f32	182.092499

Name	Input Value
CMM388NTCEnableTimer_mS_M_u32	1882050560
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3661205504
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	27207
CMMNodeAbsentTimer_mS_M_u32	358014976
CONSANGLECPKSigInvalidCount_Cnt_M_u16	18999
CONSANGLECPKSigValidCount_Cnt_M_u16	2224
CONSANGLECPK_Cnt_M_u16	63523
CONSANGLECPK_HwDeg_M_f32	-0.600099981
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	63523
CPKVehicleSpeedMsgTimer_mS_M_u32	3107291136
CPKVehicleSpeedValidCount_Cnt_M_u16	57796
CityParkInputConsistentCount_Cnt_M_u16	48594
CityParkInputInvalidCount_Cnt_M_u16	41221
CityParkInputMsgTimer_mS_M_u32	3762016512
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2491281408
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	7989
ComputerRazGCTSigInvalidTimer_mS_M_u32	2629832704
ComputerRazGCTSigValidCount_Cnt_M_u16	5663
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	15041
DMDFCTCPKSigValidCount_Cnt_M_u16	658
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	36507
DMDRELAXECPKSigValidCount_Cnt_M_u16	15300
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	14220
DateInvalidTimer_mS_M_u32	1536569344
DiagMuxOnAbsentTimer_mS_M_u32	694829056
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3132940288
ESPNTCEnableTimer_mS_M_u32	3331518464
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	55052
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	850
EffacDefaultDiagTimer_mS_M_u32[1]	2577801472
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	963
ElecIntTimer_mS_M_u32[1]	7854
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	653959168
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	59247
EtatMTSigValidCount_Cnt_M_u16	24356
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24665
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	54354
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	29816
ISDAT4V2BSI552MsgTimer_mS_M_u32	865787904
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	44181
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	22098
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	24356
ISDATBSI3F2MsgTimer_mS_M_u32	1799897088
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	61929
ISDATBSI412MsgLenValidCount_Cnt_M_u16	24150
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	59247
ISDATBSI412MsgTimer_mS_M_u32	3836510208
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	29579
ISDATBSI432MsgLenValidCount_Cnt_M_u16	2896
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	39819
ISDATDIRASentFltAcc_Cnt_M_u16	22879
ISDATDIRASentTimer_mS_M_u32	3107291136
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	33921
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	56206
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	15920
ISDYN2CMMMsgTimer_mS_M_u32	967634944
ISDYNAASChkSumInvalidCount_Cnt_M_u16	29459
ISDYNAASChkSumValidCount_Cnt_M_u16	45787

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	29949
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	36293
ISDYNAASMsgLenValidCount_Cnt_M_u16	64582
ISDYNAASMsgTimeValidCount_Cnt_M_u16	29459
ISDYNAASMsgTimer_mS_M_u32	3337211904
ISDYNABRChkSumInvalidCount_Cnt_M_u16	7911
ISDYNABRChkSumValidCount_Cnt_M_u16	11928
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	23298
ISDYNABRMsgCountValidCount_Cnt_M_u16	10
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	64806
ISDYNABRMsgLenValidCount_Cnt_M_u16	24799
ISDYNABRMsgTimeValidCount_Cnt_M_u16	63523
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	672
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1229
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	24356
ISDYNCMM208MsgTimer_mS_M_u32	2350428160
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2539
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1335
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	57964
ISDYNCMM388MsgTimer_mS_M_u32	2151763968
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	33813
ISDYNVOLChkSumValidCount_Cnt_M_u16	36110
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	32671
ISDYNVOLMsgCountValidCount_Cnt_M_u16	53744
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	58909
ISDYNVOLMsgLenValidCount_Cnt_M_u16	15478
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	27207
ISDYNVOLMsgTimer_mS_M_u32	3212578816
IgnOnTimer_mS_M_u32	2172997632
IgnTimeOff_Sec_M_u32	2062087111
ManVehSpd_Kph_M_f32	37.7914009
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	165
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	215
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	68042752
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	90
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1187192832
PrevISDATBSI412MsgDLCError_Cnt_M_u08	17
PrevISDATBSI412MsgRxTime_MSec_M_u32	4069298176
PrevISDATBSI432MsgDLCError_Cnt_M_u08	25
PrevISDATBSI432MsgRxTime_MSec_M_u32	2277961728
PrevISDATDIRAMsgTxTime_MSec_M_u32	660639744
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	131
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1794531328
PrevISDYNAASMsgDLCError_Cnt_M_u08	179
PrevISDYNAASMsgRxTime_MSec_M_u32	1406799872
PrevISDYNABRMsgDLCError_Cnt_M_u08	130
PrevISDYNABRMsgRxTime_MSec_M_u32	1241337856
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	96
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2548502528
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	13
PrevISDYNCMM388MsgRxTime_MSec_M_u32	741994496
PrevISDYNVOLMsgDLCError_Cnt_M_u08	73
PrevISDYNVOLMsgRxTime_MSec_M_u32	4205940736
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3616178176
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	113.2547
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput

Name	Input Value
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	26787
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	57764
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	37172
VitesseVehicleBVRampValidCount_Cnt_M_u16	1269
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	3210
VitesseVehicleBVSigValidCount_Cnt_M_u16	40691
VitesseVehicleBV_Kph_M_f32	238.2789
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	57964
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	63693
VitesseVehiculeRoues_Kph_M_f32	613.232483
k_AASNTCEnableTimeout_mS_u16	37066
k_AASNodeAbsentDiag_Cnt_str.Threshold	47149
k_AASNodeAbsentDiag_Cnt_str.PStep	18163
k_AASNodeAbsentDiag_Cnt_str.NStep	54621
k_AASNodeAbsentTimeout_mS_u16	28089
k_AASNodeTimeout_mS_u16	27812
k_ABSNodeTimeout_mS_u16	11022
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	1270
k_ANGLEVOLANTSigValidThresh_Cnt_u16	26363
k_AngleVolantInvalidThresh_Cnt_u16	40306
k_AngleVolantValidThresh_Cnt_u16	41221
k_BSI552MsgTimeout_mS_u16	47620
k_BSINTCEnableTimeout_mS_u16	11267
k_BSINodeAbsentDiag_Cnt_str.Threshold	24292
k_BSINodeAbsentDiag_Cnt_str.PStep	35216
k_BSINodeAbsentDiag_Cnt_str.NStep	14061
k_BSINodeAbsentTimeout_mS_u16	3518
k_BSINodeTimeout_mS_u16	39819
k_BattOvHi_Volt_f32	17.7352009
k_BattOvLo_Volt_f32	31.5
k_BattUvHi_Volt_f32	7.88940001
k_BattUvLo_Volt_f32	19.8691006
k_CAVNTCEnableTimeout_mS_u16	17499
k_CAVNodeAbsentDiag_Cnt_str.Threshold	31901
k_CAVNodeAbsentDiag_Cnt_str.PStep	14143
k_CAVNodeAbsentDiag_Cnt_str.NStep	60854
k_CAVNodeAbsentTimeout_mS_u16	12784
k_CAVNodeTimeout_mS_u16	55539
k_CMM388MsgTimeout_mS_u16	57841
k_CMM388NTCEnableTimeout_mS_u16	6573
k_CMMNTCEnableTimeout_mS_u16	24845
k_CMMNodeAbsentDiag_Cnt_str.Threshold	61881
k_CMMNodeAbsentDiag_Cnt_str.PStep	51828
k_CMMNodeAbsentDiag_Cnt_str.NStep	22640
k_CMMNodeAbsentTimeout_mS_u16	38537
k_CONSANGLECPKMax_HwDeg_f32	266.657288
k_CONSANGLECPKMin_HwDeg_f32	-301.206787
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	11628
k_CONSANGLECPKSigValidThresh_Cnt_u16	33741
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	8586
k_CPKVehicleSpeedValidThresh_Cnt_u16	7004
k_CityParkInputInvalidThresh_Cnt_u16	48205
k_CityParkInputValidThresh_Cnt_u16	48594
k_ComputerRazGCTSigValidThresh_Cnt_u16	65535
k_CptTemporelSigValidThresh_Cnt_u16	48664
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	51238
k_DMDFCTCPKSigValidThresh_Cnt_u16	27615
k_DMDFCTCPKValidCount_Cnt_u16	34032
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	15920
k_DMDRELAXECPKSigValidThresh_Cnt_u16	2881
k_DMDRelaxeConsistentThresh_Cnt_u16	64039
k_DateValidThresh_Cnt_u16	29816
k_DefaultVehSpd_Kph_f32	228.111801
k_DiagMuxOnAbsentTimeout_mS_u16	57593

Name	Input Value
k_EMNodeTimeout_mS_u16	42476
k_ESPNTCEnableTimeout_mS_u16	21710
k_ESPNodeAbsentDiag_Cnt_str.Threshold	52364
k_ESPNodeAbsentDiag_Cnt_str.PStep	9448
k_ESPNodeAbsentDiag_Cnt_str.NStep	39867
k_ESPNodeAbsentTimeout_mS_u16	9745
k_EtatMTSigInvalidThresh_Cnt_u16	45118
k_EtatMTSigValidThresh_Cnt_u16	58159
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	13789
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	39794
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	18531
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	8970
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	10887
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	53549
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	51072
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	56581
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	48335
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	17863
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	9556
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	18369
k_ISDATDIRASentDiag_Cnt_str.Threshold	43983
k_ISDATDIRASentDiag_Cnt_str.PStep	1284
k_ISDATDIRASentDiag_Cnt_str.NStep	17526
k_ISDATDIRASentTimeout_mS_u16	15267
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	49998
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	45894
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	59546
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	27111
k_ISDYNAASChkSumValidThresh_Cnt_u16	47512
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	9730
k_ISDYNAASMsgCountValidThresh_Cnt_u16	2826
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	36139
k_ISDYNAASMsgLenValidThresh_Cnt_u16	26344
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	42115
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	43524
k_ISDYNABRChkSumValidThresh_Cnt_u16	38973
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	20328
k_ISDYNABRMsgCountValidThresh_Cnt_u16	60497
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	62791
k_ISDYNABRMsgLenValidThresh_Cnt_u16	41484
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	63240
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	743
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	11194
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	15579
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	10617
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	57634
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	24445
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	18388
k_ISDYNVOLChkSumValidThresh_Cnt_u16	56961
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	27233
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	34780
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	58667
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	29152
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	31822
k_IgnOnTimeout_mS_u16	14480
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	106.989304
k_PowerCutVehSpdLowThresh_Kph_f32	113.122101
k_PowerCutVehSpdLowTimeout_mS_u16	20982
k_VBattMaxAAS_Volt_f32	24.3104992
k_VBattMaxBSI_Volt_f32	22.4018993
k_VBattMaxCAV_Volt_f32	30.3796997
k_VBattMaxCMM388_Volt_f32	32
k_VBattMaxCMM_Volt_f32	31.5550003
k_VBattMaxESP_Volt_f32	5.16410017
k_VBattMinAAS_Volt_f32	22.3290005
k_VBattMinBSI_Volt_f32	5.16410017
k_VBattMinCAV_Volt_f32	23.0506992
k_VBattMinCMM388_Volt_f32	16.7672997
k_VBattMinCMM_Volt_f32	12.5499001
k_VBattMinESP_Volt_f32	31.5550003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	8552
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	10949

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VitesseVehicleBVRampValidThresh_Cnt_u16	51871
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	38926
k_VitesseVehicleBVSigValidThresh_Cnt_u16	28379
k_VitesseVehicleBVSpeedPassThresh_kph_f32	512.862
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	24338
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	7507
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1536569344
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	175
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	7369
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2577801472
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	13
target_SrlComInput_Per1_Batt_Volt_f32.value	6.53779984
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3276906496
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	48
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.649085999
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	182
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2473545728
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	86077440
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1042518016
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2255859712
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	639094784
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	149
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1695150080
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2337017856
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	131
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4117147648
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	71
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	140
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	141
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	168
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2030194688
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	189
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3392434176
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	41
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2729873408
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1534402560
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	379
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.29598394
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	681532
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	252.7444
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	9277

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2577801472	2577801472	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2577801472	2577801472	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2577801472	2577801472	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-482.872772	-482.872772	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	965455872	965455872	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	1536569344	1536569344	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2801016832	2801016832	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	3132940288	3132940288	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2577801472	2577801472	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2577801472	2577801472	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	31901	31901	✔
CAVNodeAbsentTimer_mS_M_u32	2577801472	2577801472	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2577801472	2577801472	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2577801472	2577801472	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	61881	61881	✔
CMMNodeAbsentTimer_mS_M_u32	2577801472	2577801472	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	63523	63523	✔
CONSANGLECPK_HwDeg_M_f32	-0.600099981	-0.600099981 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2577801472	2577801472	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2577801472	2577801472	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2577801472	2577801472	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2577801472	2577801472	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2577801472	2577801472	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2577801472	2577801472	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2577801472	2577801472	✔
ESPNTCEnableTimer_mS_M_u32	2577801472	2577801472	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2577801472	2577801472	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	850	850	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2577801472	2577801472	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2577801472	2577801472	✔
ElecIntTimer_mS_M_u32[1]	7854	7854	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2577801472	2577801472	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2473545728	2473545728	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	86077440	86077440	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2577801472	2577801472	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2255859712	2255859712	✔
ISDATDIRASentFltAcc_Cnt_M_u16	43983	43983	✔
ISDATDIRASentTimer_mS_M_u32	2577801472	2577801472	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2577801472	2577801472	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2577801472	2577801472	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2577801472	2577801472	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2577801472	2577801472	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2577801472	2577801472	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2577801472	2577801472	✔
IgnOnTimer_mS_M_u32	2577801472	2577801472	✔
IgnTimeOff_Sec_M_u32	2062087111	2062087111	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	182	182	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2473545728	2473545728	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	63	63	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	86077440	86077440	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	108	108	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1042518016	1042518016	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	131	131	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2255859712	2255859712	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	660639744	660639744	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	149	149	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1695150080	1695150080	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	30	30	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2337017856	2337017856	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	245	245	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4117147648	4117147648	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	180	180	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2030194688	2030194688	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	189	189	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3392434176	3392434176	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	41	41	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2729873408	2729873408	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1534402560	1534402560	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	113.2547	113.2547	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	238.2789	238.2789	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	613.232483	613.232483	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-482.872772	-482.872772	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	63523	63523	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2062087111	2062087111	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-0.600099981	-0.600099981 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	228.111801	228.111801	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.97 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4147331840
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	33483
AASNodeAbsentTimer_mS_M_u32	4088460032
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	28210
ANGLEVOLANTSigValidCount_Cnt_M_u16	5879
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	16844
AngleVolantMsgTimer_mS_M_u32	4147331840
AngleVolantValidCount_Cnt_M_u16	37236
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-393.882324
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	565949184
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	94122752
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1195533056

Name	Input Value
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	518529792
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	30821
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2075452160
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	39398
CAVNodeAbsentTimer_mS_M_u32	2397311744
CDD_SrlComVehSpd_Kph_G_f32	232.793304
CMM388NTCEnableTimer_mS_M_u32	777343744
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3476165376
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	10247
CMMNodeAbsentTimer_mS_M_u32	4145685248
CONSANGLECPKSigInvalidCount_Cnt_M_u16	53753
CONSANGLECPKSigValidCount_Cnt_M_u16	58958
CONSANGLECPK_Cnt_M_u16	41973
CONSANGLECPK_HwDeg_M_f32	94.4736023
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	41973
CPKVehicleSpeedMsgTimer_mS_M_u32	1308508928
CPKVehicleSpeedValidCount_Cnt_M_u16	55864
CityParkInputConsistentCount_Cnt_M_u16	64168
CityParkInputInvalidCount_Cnt_M_u16	11790
CityParkInputMsgTimer_mS_M_u32	2473545728
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2850353920
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	31231
ComputerRazGCTSigInvalidTimer_mS_M_u32	3248395008
ComputerRazGCTSigValidCount_Cnt_M_u16	26049
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	20698
DMDFCTCPKSigValidCount_Cnt_M_u16	43303
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	58828
DMDRELAXECPKSigValidCount_Cnt_M_u16	60945
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	40442
DateInvalidTimer_mS_M_u32	94122752
DiagMuxOnAbsentTimer_mS_M_u32	3227517696
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	518529792
ESPNTCEnableTimer_mS_M_u32	2812670720
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	24952
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1100
EffacDefaultDiagTimer_mS_M_u32[1]	1150
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	202
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	19849984
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	23953
EtatMTSigValidCount_Cnt_M_u16	13874
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	38803
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	35688
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	27509
ISDAT4V2BSI552MsgTimer_mS_M_u32	2890801920
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	8094
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	33319
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13874
ISDATBSI3F2MsgTimer_mS_M_u32	4073063168
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	61601
ISDATBSI412MsgLenValidCount_Cnt_M_u16	51994
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	23953
ISDATBSI412MsgTimer_mS_M_u32	1738097408
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	7227

Name	Input Value
ISDATBSI432MsgLenValidCount_Cnt_M_u16	54444
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	10107
ISDATDIRASentFltAcc_Cnt_M_u16	15871
ISDATDIRASentTimer_mS_M_u32	1308508928
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	63195
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	37236
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	49805
ISDYN2CMMMsgTimer_mS_M_u32	911733504
ISDYNAASChkSumInvalidCount_Cnt_M_u16	30309
ISDYNAASChkSumValidCount_Cnt_M_u16	18122
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	16679
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	47309
ISDYNAASMsgLenValidCount_Cnt_M_u16	56587
ISDYNAASMsgTimeValidCount_Cnt_M_u16	30309
ISDYNAASMsgTimer_mS_M_u32	438391552
ISDYNABRChkSumInvalidCount_Cnt_M_u16	24167
ISDYNABRChkSumValidCount_Cnt_M_u16	24340
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	15000
ISDYNABRMsgCountValidCount_Cnt_M_u16	56125
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	13612
ISDYNABRMsgLenValidCount_Cnt_M_u16	22977
ISDYNABRMsgTimeValidCount_Cnt_M_u16	41973
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	673
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1231
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13874
ISDYNCMM208MsgTimer_mS_M_u32	2652156672
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2543
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1337
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	29914
ISDYNCMM388MsgTimer_mS_M_u32	2887439104
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	7263
ISDYNVOLChkSumValidCount_Cnt_M_u16	20788
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	31296
ISDYNVOLMsgCountValidCount_Cnt_M_u16	13069
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	47173
ISDYNVOLMsgLenValidCount_Cnt_M_u16	34042
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	10247
ISDYNVOLMsgTimer_mS_M_u32	1231721216
IgnOnTimer_mS_M_u32	3092173568
IgnTimeOff_Sec_M_u32	160621851
ManVehSpd_Kph_M_f32	280.481415
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	167
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	184
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3228828416
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	56
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1674928896
PrevISDATBSI412MsgDLCError_Cnt_M_u08	166
PrevISDATBSI412MsgRxTime_MSec_M_u32	2453213952
PrevISDATBSI432MsgDLCError_Cnt_M_u08	94
PrevISDATBSI432MsgRxTime_MSec_M_u32	873067264
PrevISDATDIRAMsgTxTime_MSec_M_u32	1136464640
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	92
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3560678144
PrevISDYNAASMsgDLCError_Cnt_M_u08	63
PrevISDYNAASMsgRxTime_MSec_M_u32	2219873024
PrevISDYNABRMsgDLCError_Cnt_M_u08	157
PrevISDYNABRMsgRxTime_MSec_M_u32	1055314688
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	163
PrevISDYNCMM208MsgRxTime_MSec_M_u32	740922112
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	119
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3534811904
PrevISDYNVOLMsgDLCError_Cnt_M_u08	165

Name	Input Value
PrevISDYNVOLMsgRxTime_MSec_M_u32	1305088768
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2264875776
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	259.838715
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	8243
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	9457
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	10880
VitesseVehicleBVRampValidCount_Cnt_M_u16	16126
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	59391
VitesseVehicleBVSigValidCount_Cnt_M_u16	16516
VitesseVehicleBV_Kph_M_f32	374.457397
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	29914
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	8567
VitesseVehiculeRoues_Kph_M_f32	371.271301
k_AASNTCEnableTimeout_mS_u16	13824
k_AASNodeAbsentDiag_Cnt_str.Threshold	48266
k_AASNodeAbsentDiag_Cnt_str.PStep	42799
k_AASNodeAbsentDiag_Cnt_str.NStep	45867
k_AASNodeAbsentTimeout_mS_u16	18163
k_AASNodeTimeout_mS_u16	33777
k_ABSNodeTimeout_mS_u16	62451
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	54266
k_ANGLEVOLANTSigValidThresh_Cnt_u16	11691
k_AngleVolantInvalidThresh_Cnt_u16	9798
k_AngleVolantValidThresh_Cnt_u16	11790
k_BSI552MsgTimeout_mS_u16	31186
k_BSINTCEnableTimeout_mS_u16	53971
k_BSINodeAbsentDiag_Cnt_str.Threshold	24332
k_BSINodeAbsentDiag_Cnt_str.PStep	35199
k_BSINodeAbsentDiag_Cnt_str.NStep	14084
k_BSINodeAbsentTimeout_mS_u16	4708
k_BSINodeTimeout_mS_u16	10107
k_BattOvHi_Volt_f32	6.06510019
k_BattOvLo_Volt_f32	8.98729992
k_BattUvHi_Volt_f32	1.13460004
k_BattUvLo_Volt_f32	26.1012993
k_CAVNTCEnableTimeout_mS_u16	7180
k_CAVNodeAbsentDiag_Cnt_str.Threshold	28626
k_CAVNodeAbsentDiag_Cnt_str.PStep	51747
k_CAVNodeAbsentDiag_Cnt_str.NStep	63287
k_CAVNodeAbsentTimeout_mS_u16	14412
k_CAVNodeTimeout_mS_u16	5573
k_CMM388MsgTimeout_mS_u16	8651
k_CMM388NTCEnableTimeout_mS_u16	27287
k_CMMNTCEnableTimeout_mS_u16	57910
k_CMMNodeAbsentDiag_Cnt_str.Threshold	63429
k_CMMNodeAbsentDiag_Cnt_str.PStep	9613
k_CMMNodeAbsentDiag_Cnt_str.NStep	19410
k_CMMNodeAbsentTimeout_mS_u16	14403
k_CONSANGLECPKMax_HwDeg_f32	284.947296
k_CONSANGLECPKMin_HwDeg_f32	-692.910278
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	37850
k_CONSANGLECPKSigValidThresh_Cnt_u16	32887
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	32063
k_CPKVehicleSpeedValidThresh_Cnt_u16	72
k_CityParkInputInvalidThresh_Cnt_u16	40501
k_CityParkInputValidThresh_Cnt_u16	64168
k_ComputerRazGCTSigValidThresh_Cnt_u16	47926

Name	Input Value
k_CptTemporelSigValidThresh_Cnt_u16	58069
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	54316
k_DMDFCTCPKSigValidThresh_Cnt_u16	14529
k_DMDFCTCPKValidCount_Cnt_u16	38605
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	49805
k_DMDRELAXECPKSigValidThresh_Cnt_u16	2842
k_DMDRelaxeConsistentThresh_Cnt_u16	22120
k_DateValidThresh_Cnt_u16	27509
k_DefaultVehSpd_Kph_f32	209.784698
k_DiagMuxOnAbsentTimeout_mS_u16	49523
k_EMNodeTimeout_mS_u16	53978
k_ESPNTCEnableTimeout_mS_u16	51122
k_ESPNodeAbsentDiag_Cnt_str.Threshold	57516
k_ESPNodeAbsentDiag_Cnt_str.PStep	42129
k_ESPNodeAbsentDiag_Cnt_str.NStep	32080
k_ESPNodeAbsentTimeout_mS_u16	43435
k_EtatMTSigInvalidThresh_Cnt_u16	50786
k_EtatMTSigValidThresh_Cnt_u16	23887
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	19526
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	56135
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	57077
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	53311
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	6536
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	25301
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	13404
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	29581
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	20591
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	19209
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	19490
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	40984
k_ISDATDIRASentDiag_Cnt_str.Threshold	12477
k_ISDATDIRASentDiag_Cnt_str.PStep	47957
k_ISDATDIRASentDiag_Cnt_str.NStep	63864
k_ISDATDIRASentTimeout_mS_u16	63539
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	41329
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	16844
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	15438
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	32103
k_ISDYNAASChkSumValidThresh_Cnt_u16	48660
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	55704
k_ISDYNAASMsgCountValidThresh_Cnt_u16	47677
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	9115
k_ISDYNAASMsgLenValidThresh_Cnt_u16	42277
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	38163
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	9874
k_ISDYNABRChkSumValidThresh_Cnt_u16	43943
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	5989
k_ISDYNABRMsgCountValidThresh_Cnt_u16	20586
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	34567
k_ISDYNABRMsgLenValidThresh_Cnt_u16	120
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	52293
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	24935
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	50990
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	44876
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	3378
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	62967
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	53926
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	23264
k_ISDYNVOLChkSumValidThresh_Cnt_u16	46745
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	15225
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	25416
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	21597
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	60926
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	11251
k_IgnOnTimeout_mS_u16	30892
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	7.65240002
k_PowerCutVehSpdLowThresh_Kph_f32	253.253998
k_PowerCutVehSpdLowTimeout_mS_u16	41596
k_VBattMaxAAS_Volt_f32	10.6153002
k_VBattMaxBSI_Volt_f32	26.4603004
k_VBattMaxCAV_Volt_f32	27.5667
k_VBattMaxCMM388_Volt_f32	11.9223003

Name	Input Value
k_VBattMaxCMM_Volt_f32	17.3698997
k_VBattMaxESP_Volt_f32	24.4519005
k_VBattMinAAS_Volt_f32	14.4650002
k_VBattMinBSI_Volt_f32	6.5236001
k_VBattMinCAV_Volt_f32	16.5216999
k_VBattMinCMM388_Volt_f32	20.7409
k_VBattMinCMM_Volt_f32	31.0405998
k_VBattMinESP_Volt_f32	17.3698997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	28451
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	13005
k_VitesseVehicleBVRampValidThresh_Cnt_u16	39232
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	12340
k_VitesseVehicleBVSigValidThresh_Cnt_u16	19341
k_VitesseVehicleBVSpeedPassThresh_kph_f32	66.6783981
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	47334
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	60900
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	94122752
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	16
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	28541
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3027263488
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	119
target_SrlComInput_Per1_Batt_Volt_f32.value	18.5266991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1210704640
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	224
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.607326746
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2861617920
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1174041344
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3413381888
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	138
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1660793600
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	882332416
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1749086976
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	171
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	637178624
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	146
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	192
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	239
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	439005952
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	41
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	86
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	147
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	223
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	224
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	249

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	82
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	98030336
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	46232320
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	214
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2847609600
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	175
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	183
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	251
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1841259264
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	4076
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.240563735
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	881895
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	187.636993
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	54629

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3027263488	3027263488	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3027263488	3027263488	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3027263488	3027263488	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-393.882324	-393.882324	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	565949184	565949184	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	3027263488	3027263488	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1195533056	1195533056	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	518529792	518529792	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3027263488	3027263488	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3027263488	3027263488	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	28626	28626	✔
CAVNodeAbsentTimer_mS_M_u32	3027263488	3027263488	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3027263488	3027263488	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3027263488	3027263488	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	63429	63429	✔
CMMNodeAbsentTimer_mS_M_u32	3027263488	3027263488	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	41973	41973	✔
CONSANGLECPK_HwDeg_M_f32	94.4736023	94.4736023 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3027263488	3027263488	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3027263488	3027263488	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3027263488	3027263488	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3027263488	3027263488	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3027263488	3027263488	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3027263488	3027263488	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3027263488	3027263488	✔
ESPNTCEnableTimer_mS_M_u32	3027263488	3027263488	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3027263488	3027263488	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1100	1100	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1150	1150	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	20	20	✔
ElecIntTimer_mS_M_u32[1]	202	202	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3027263488	3027263488	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2861617920	2861617920	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1174041344	1174041344	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3027263488	3027263488	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1660793600	1660793600	✔
ISDATDIRASentFltAcc_Cnt_M_u16	12477	12477	✔
ISDATDIRASentTimer_mS_M_u32	3027263488	3027263488	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3027263488	3027263488	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3027263488	3027263488	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3027263488	3027263488	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3027263488	3027263488	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3027263488	3027263488	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3027263488	3027263488	✔
IgnOnTimer_mS_M_u32	3027263488	3027263488	✔
IgnTimeOff_Sec_M_u32	160621851	160621851	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	64	64	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2861617920	2861617920	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	245	245	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1174041344	1174041344	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	0	0	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3413381888	3413381888	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	138	138	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1660793600	1660793600	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1136464640	1136464640	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	183	183	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1749086976	1749086976	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	171	171	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	637178624	637178624	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	57	57	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	439005952	439005952	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	82	82	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	98030336	98030336	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	137	137	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	46232320	46232320	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	214	214	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2847609600	2847609600	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1841259264	1841259264	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	259.838715	259.838715	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	374.457397	374.457397	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	371.271301	371.271301	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-393.882324	-393.882324	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	41973	41973	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	160621851	160621851	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	94.4736023	94.4736023 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	209.784698	209.784698	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0146	0x0146	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.98 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3860678656
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	13391
AASNodeAbsentTimer_mS_M_u32	1637791744
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	54696
ANGLEVOLANTSigValidCount_Cnt_M_u16	11351
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	62148

© Report created by TESSY V3.1.13, report template V2.1

Name	Input Value
AngleVolantMsgTimer_mS_M_u32	3860678656
AngleVolantValidCount_Cnt_M_u16	26432
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-195.563004
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3234363392
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3219322880
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	140961792
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2355603456
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	26615
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1882941440
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	45845
CAVNodeAbsentTimer_mS_M_u32	123492352
CDD_SrlComVehSpd_Kph_G_f32	436.159698
CMM388NTCEnableTimer_mS_M_u32	1172215808
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1963087872
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	23096
CMMNodeAbsentTimer_mS_M_u32	3510740992
CONSANGLECPKSigInvalidCount_Cnt_M_u16	14270
CONSANGLECPKSigValidCount_Cnt_M_u16	26428
CONSANGLECPK_Cnt_M_u16	6543
CONSANGLECPK_HwDeg_M_f32	195.686798
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	6543
CPKVehicleSpeedMsgTimer_mS_M_u32	3252963328
CPKVehicleSpeedValidCount_Cnt_M_u16	7189
CityParkInputConsistentCount_Cnt_M_u16	55300
CityParkInputInvalidCount_Cnt_M_u16	50304
CityParkInputMsgTimer_mS_M_u32	2103851264
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	56801280
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	35603
ComputerRazGCTSigInvalidTimer_mS_M_u32	4263041024
ComputerRazGCTSigValidCount_Cnt_M_u16	1393
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	20412
DMDFCTCPKSigValidCount_Cnt_M_u16	63379
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	44298
DMDRELAXECPKSigValidCount_Cnt_M_u16	10553
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	59187
DateInvalidTimer_mS_M_u32	3219322880
DiagMuxOnAbsentTimer_mS_M_u32	1909524480
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2355603456
ESPNTCEnableTimer_mS_M_u32	2945955840
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	4995
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	4
EffacDefaultDiagTimer_mS_M_u32[1]	1305159680
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	11
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1056794624
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	27943
EtatMTSigValidCount_Cnt_M_u16	30562
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	46368
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	35358
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	53049

Name	Input Value
ISDAT4V2BSI552MsgTimer_mS_M_u32	4261783552
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	9642
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	28397
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	30562
ISDATBSI3F2MsgTimer_mS_M_u32	1282344960
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	41446
ISDATBSI412MsgLenValidCount_Cnt_M_u16	35801
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	27943
ISDATBSI412MsgTimer_mS_M_u32	381372416
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	20988
ISDATBSI432MsgLenValidCount_Cnt_M_u16	5703
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	22318
ISDATDIRASentFltAcc_Cnt_M_u16	60802
ISDATDIRASentTimer_mS_M_u32	3252963328
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	20141
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	26432
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	44939
ISDYN2CMMMsgTimer_mS_M_u32	3706828800
ISDYNAASChkSumInvalidCount_Cnt_M_u16	47025
ISDYNAASChkSumValidCount_Cnt_M_u16	2688
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	7439
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	38824
ISDYNAASMsgLenValidCount_Cnt_M_u16	17455
ISDYNAASMsgTimeValidCount_Cnt_M_u16	47025
ISDYNAASMsgTimer_mS_M_u32	2920978432
ISDYNABRChkSumInvalidCount_Cnt_M_u16	40562
ISDYNABRChkSumValidCount_Cnt_M_u16	23081
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	19456
ISDYNABRMsgCountValidCount_Cnt_M_u16	35855
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	30477
ISDYNABRMsgLenValidCount_Cnt_M_u16	54219
ISDYNABRMsgTimeValidCount_Cnt_M_u16	6543
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	680
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1245
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	30562
ISDYNCMM208MsgTimer_mS_M_u32	2423617536
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2571
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1351
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	9950
ISDYNCMM388MsgTimer_mS_M_u32	2040666112
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	2652
ISDYNVOLChkSumValidCount_Cnt_M_u16	37978
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	3418
ISDYNVOLMsgCountValidCount_Cnt_M_u16	20401
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	54836
ISDYNVOLMsgLenValidCount_Cnt_M_u16	27027
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	23096
ISDYNVOLMsgTimer_mS_M_u32	2991904768
IgnOnTimer_mS_M_u32	1768298496
IgnTimeOff_Sec_M_u32	510090580
ManVehSpd_Kph_M_f32	544.616028
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	181
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	248
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1995769856
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	17
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	546695168
PrevISDATBSI412MsgDLCError_Cnt_M_u08	247
PrevISDATBSI412MsgRxTime_MSec_M_u32	3157612544
PrevISDATBSI432MsgDLCError_Cnt_M_u08	161
PrevISDATBSI432MsgRxTime_MSec_M_u32	3310073856
PrevISDATDIRAMsgTxTime_MSec_M_u32	696866816
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	49

Name	Input Value
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3994101760
PrevISDYNAASMsgDLCError_Cnt_M_u08	214
PrevISDYNAASMsgRxTime_MSec_M_u32	4017281024
PrevISDYNABRMsgDLCError_Cnt_M_u08	228
PrevISDYNABRMsgRxTime_MSec_M_u32	886970368
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	27
PrevISDYNCMM208MsgRxTime_MSec_M_u32	547346432
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	37
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1285470208
PrevISDYNVOLMsgDLCError_Cnt_M_u08	249
PrevISDYNVOLMsgRxTime_MSec_M_u32	2558154752
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1113147392
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	394.402313
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	43846
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	29261
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	63351
VitesseVehicleBVRampValidCount_Cnt_M_u16	12606
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	38745
VitesseVehicleBVSigValidCount_Cnt_M_u16	32968
VitesseVehicleBV_Kph_M_f32	478.645599
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	9950
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	18245
VitesseVehiculeRoues_Kph_M_f32	330.538208
k_AASNTCEnableTimeout_mS_u16	51606
k_AASNodeAbsentDiag_Cnt_str.Threshold	2575
k_AASNodeAbsentDiag_Cnt_str.PStep	34297
k_AASNodeAbsentDiag_Cnt_str.NStep	46541
k_AASNodeAbsentTimeout_mS_u16	26443
k_AASNodeTimeout_mS_u16	56653
k_ABSNodeTimeout_mS_u16	5417
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	6471
k_ANGLEVOLANTSigValidThresh_Cnt_u16	20434
k_AngleVolantInvalidThresh_Cnt_u16	36777
k_AngleVolantValidThresh_Cnt_u16	50304
k_BSI552MsgTimeout_mS_u16	35292
k_BSINTCEnableTimeout_mS_u16	3444
k_BSINodeAbsentDiag_Cnt_str.Threshold	24612
k_BSINodeAbsentDiag_Cnt_str.PStep	35080
k_BSINodeAbsentDiag_Cnt_str.NStep	14245
k_BSINodeAbsentTimeout_mS_u16	36924
k_BSINodeTimeout_mS_u16	22318
k_BattOvHi_Volt_f32	22.5359993
k_BattOvLo_Volt_f32	10.7726002
k_BattUvHi_Volt_f32	12.7476997
k_BattUvLo_Volt_f32	29.2371998
k_CAVNTCEnableTimeout_mS_u16	41878
k_CAVNodeAbsentDiag_Cnt_str.Threshold	64017
k_CAVNodeAbsentDiag_Cnt_str.PStep	26002
k_CAVNodeAbsentDiag_Cnt_str.NStep	51479
k_CAVNodeAbsentTimeout_mS_u16	59827
k_CAVNodeTimeout_mS_u16	55290
k_CMM388MsgTimeout_mS_u16	57167
k_CMM388NTCEnableTimeout_mS_u16	51339
k_CMMNTCEnableTimeout_mS_u16	23842
k_CMMNodeAbsentDiag_Cnt_str.Threshold	41408
k_CMMNodeAbsentDiag_Cnt_str.PStep	53270
k_CMMNodeAbsentDiag_Cnt_str.NStep	30523

Name	Input Value
k_CMMNodeAbsentTimeout_mS_u16	22145
k_CONSANGLECPKMax_HwDeg_f32	580.110596
k_CONSANGLECPKMin_HwDeg_f32	-442.248505
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	20958
k_CONSANGLECPKSigValidThresh_Cnt_u16	45637
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	55283
k_CPKVehicleSpeedValidThresh_Cnt_u16	52793
k_CityParkInputInvalidThresh_Cnt_u16	20888
k_CityParkInputValidThresh_Cnt_u16	55300
k_ComputerRazGCTSigValidThresh_Cnt_u16	42672
k_CptTemporelSigValidThresh_Cnt_u16	51315
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	8717
k_DMDFCTCPKSigValidThresh_Cnt_u16	48843
k_DMDFCTCPKValidCount_Cnt_u16	1407
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	44939
k_DMDRELAXECPKSigValidThresh_Cnt_u16	58530
k_DMDRelaxeConsistentThresh_Cnt_u16	22856
k_DateValidThresh_Cnt_u16	53049
k_DefaultVehSpd_Kph_f32	0
k_DiagMuxOnAbsentTimeout_mS_u16	11813
k_EMNodeTimeout_mS_u16	45459
k_ESPNTCEnableTimeout_mS_u16	17745
k_ESPNodeAbsentDiag_Cnt_str.Threshold	24843
k_ESPNodeAbsentDiag_Cnt_str.PStep	24933
k_ESPNodeAbsentDiag_Cnt_str.NStep	40876
k_ESPNodeAbsentTimeout_mS_u16	58121
k_EtatMTSigInvalidThresh_Cnt_u16	58665
k_EtatMTSigValidThresh_Cnt_u16	3104
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	39718
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	8001
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	50741
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	12863
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	12610
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	12202
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	11281
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	50716
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	35264
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	29107
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	58054
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	58662
k_ISDATDIRASentDiag_Cnt_str.Threshold	14352
k_ISDATDIRASentDiag_Cnt_str.PStep	20280
k_ISDATDIRASentDiag_Cnt_str.NStep	17452
k_ISDATDIRASentTimeout_mS_u16	36014
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	32211
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	62148
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	42141
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	51570
k_ISDYNAASChkSumValidThresh_Cnt_u16	50473
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	63232
k_ISDYNAASMsgCountValidThresh_Cnt_u16	30479
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	6966
k_ISDYNAASMsgLenValidThresh_Cnt_u16	26129
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	19034
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	40107
k_ISDYNABRChkSumValidThresh_Cnt_u16	37865
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	4855
k_ISDYNABRMsgCountValidThresh_Cnt_u16	5862
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	50488
k_ISDYNABRMsgLenValidThresh_Cnt_u16	48771
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	4861
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	54282
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	1879
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	36580
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	32936
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	5975
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	17912
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	32177
k_ISDYNVOLChkSumValidThresh_Cnt_u16	14820
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	10488
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	41453
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	56419
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	7070

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	25295
k_IgnOnTimeout_mS_u16	49133
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	234.265701
k_PowerCutVehSpdLowThresh_Kph_f32	87.6485977
k_PowerCutVehSpdLowTimeout_mS_u16	4674
k_VBattMaxAAS_Volt_f32	14.2974997
k_VBattMaxBSI_Volt_f32	32
k_VBattMaxCAV_Volt_f32	11.7208996
k_VBattMaxCMM388_Volt_f32	30.2742004
k_VBattMaxCMM_Volt_f32	26.8633995
k_VBattMaxESP_Volt_f32	1.88139999
k_VBattMinAAS_Volt_f32	2.26430011
k_VBattMinBSI_Volt_f32	1.88139999
k_VBattMinCAV_Volt_f32	9.61559963
k_VBattMinCMM388_Volt_f32	1.99689996
k_VBattMinCMM_Volt_f32	27.4550991
k_VBattMinESP_Volt_f32	26.8633995
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	30253
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	33552
k_VitesseVehicleBVRampValidThresh_Cnt_u16	14426
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	32602
k_VitesseVehicleBVSigValidThresh_Cnt_u16	44973
k_VitesseVehicleBVSpeedPassThresh_kph_f32	247.213196
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	56853
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	29276
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3219322880
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	3
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60393
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1305159680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	37
target_SrlComInput_Per1_Batt_Volt_f32.value	13.5977001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1890871296
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	56
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.694746017
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3348109312
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	28719104
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1697404928
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	972191744
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3356006400
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1466873856
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	807720960
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	81
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	119
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	214
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	223
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	255

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	679704576
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	69
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	152
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	164
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	183
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	24
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1677924352
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2913548288
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	189
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3768539136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3330795520
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1829
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.862331986
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	220616
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	71.6537018
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	61728

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	62148	62148	✔
AngleVolantMsgTimer_mS_M_u32	1305159680	1305159680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-195.563004	-195.563004	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	64017	64017	✔
CAVNodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	41408	41408	✔
CMMNodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	6543	6543	✔
CONSANGLECPK_HwDeg_M_f32	195.686798	195.686798 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	6543	6543	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3252963328	3252963328	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	7189	7189	✔
CityParkInputConsistentCount_Cnt_M_u16	55300	55300	✔
CityParkInputInvalidCount_Cnt_M_u16	50304	50304	✔
CityParkInputMsgTimer_mS_M_u32	1305159680	1305159680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1305159680	1305159680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1305159680	1305159680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1305159680	1305159680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1305159680	1305159680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1305159680	1305159680	✔
ESPNTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4	4	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1305159680	1305159680	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1305159680	1305159680	✔
ElecIntTimer_mS_M_u32[1]	11	11	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1305159680	1305159680	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	14352	14352	✔
ISDATDIRASentTimer_mS_M_u32	1305159680	1305159680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1305159680	1305159680	✔
IgnOnTimer_mS_M_u32	1768298496	1768298496	✔
IgnTimeOff_Sec_M_u32	510090580	510090580	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	251	251	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3348109312	3348109312	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	123	123	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	28719104	28719104	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	129	129	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1697404928	1697404928	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	84	84	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	972191744	972191744	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	696866816	696866816	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	131	131	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1466873856	1466873856	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	110	110	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	807720960	807720960	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	190	190	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	679704576	679704576	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	24	24	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1677924352	1677924352	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	72	72	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2913548288	2913548288	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	189	189	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3768539136	3768539136	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3330795520	3330795520	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	394.402313	394.402313	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	478.645599	478.645599	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	330.538208	330.538208	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-195.563004	-195.563004	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	6543	6543	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	510090580	510090580	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	195.686798	195.686798 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.99 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	6744832
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	65487
AASNodeAbsentTimer_mS_M_u32	2678233856
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	7621
ANGLEVOLANTSigValidCount_Cnt_M_u16	49529
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	55408
AngleVolantMsgTimer_mS_M_u32	6744832
AngleVolantValidCount_Cnt_M_u16	4988
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-658.175537
ApaRelaxReq_Cnt_M_lgc	0

Name	Input Value
BSI3F2NTCEnableTimer_mS_M_u32	1495620352
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3855997696
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1208617728
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2936523520
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	25304
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	42765056
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	8702
CAVNodeAbsentTimer_mS_M_u32	753515264
CDD_SrlComVehSpd_Kph_G_f32	283.645813
CMM388NTCEnableTimer_mS_M_u32	1248000768
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4227316480
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	62804
CMMNodeAbsentTimer_mS_M_u32	3363425024
CONSANGLECPKSigInvalidCount_Cnt_M_u16	32388
CONSANGLECPKSigValidCount_Cnt_M_u16	55239
CONSANGLECPK_Cnt_M_u16	52430
CONSANGLECPK_HwDeg_M_f32	463.707001
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	52430
CPKVehicleSpeedMsgTimer_mS_M_u32	1225911040
CPKVehicleSpeedValidCount_Cnt_M_u16	39269
CityParkInputConsistentCount_Cnt_M_u16	53552
CityParkInputInvalidCount_Cnt_M_u16	2238
CityParkInputMsgTimer_mS_M_u32	3348109312
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3394673408
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	2947
ComputerRazGCTSigInvalidTimer_mS_M_u32	3669244672
ComputerRazGCTSigValidCount_Cnt_M_u16	15593
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	22282
DMDFCTCPKSigValidCount_Cnt_M_u16	42821
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	40863
DMDRELAXECPKSigValidCount_Cnt_M_u16	53971
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	33829
DateInvalidTimer_mS_M_u32	3855997696
DiagMuxOnAbsentTimer_mS_M_u32	3695946496
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2936523520
ESPNTCEnableTimer_mS_M_u32	3652688640
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	57652
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	19
ElecIntCount_Cnt_M_u08	2
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	7
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	507939584
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	35207
EtatMTSigValidCount_Cnt_M_u16	17046
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	3678
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	30497
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	14419
ISDAT4V2BSI552MsgTimer_mS_M_u32	1378732800
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	57728
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	64887
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	17046
ISDATBSI3F2MsgTimer_mS_M_u32	1148300032

Name	Input Value
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	44491
ISDATBSI412MsgLenValidCount_Cnt_M_u16	42930
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	35207
ISDATBSI412MsgTimer_mS_M_u32	1720511232
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	7688
ISDATBSI432MsgLenValidCount_Cnt_M_u16	59624
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	55731
ISDATDIRASentFltAcc_Cnt_M_u16	26295
ISDATDIRASentTimer_mS_M_u32	1225911040
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	9588
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	4988
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	13213
ISDYN2CMMMsgTimer_mS_M_u32	967416576
ISDYNAASChkSumInvalidCount_Cnt_M_u16	32169
ISDYNAASChkSumValidCount_Cnt_M_u16	44284
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	60943
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	32837
ISDYNAASMsgLenValidCount_Cnt_M_u16	33392
ISDYNAASMsgTimeValidCount_Cnt_M_u16	32169
ISDYNAASMsgTimer_mS_M_u32	28244736
ISDYNABRChkSumInvalidCount_Cnt_M_u16	25830
ISDYNABRChkSumValidCount_Cnt_M_u16	63873
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	48316
ISDYNABRMsgCountValidCount_Cnt_M_u16	9295
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	48279
ISDYNABRMsgLenValidCount_Cnt_M_u16	36378
ISDYNABRMsgTimeValidCount_Cnt_M_u16	52430
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	681
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1247
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	17046
ISDYNCMM208MsgTimer_mS_M_u32	3726531328
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2575
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1353
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	52386
ISDYNCMM388MsgTimer_mS_M_u32	488143616
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	65194
ISDYNVOLChkSumValidCount_Cnt_M_u16	18541
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	5680
ISDYNVOLMsgCountValidCount_Cnt_M_u16	38635
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	40225
ISDYNVOLMsgLenValidCount_Cnt_M_u16	19140
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	62804
ISDYNVOLMsgTimer_mS_M_u32	2919250688
IgnOnTimer_mS_M_u32	1573681920
IgnTimeOff_Sec_M_u32	2889666373
ManVehSpd_Kph_M_f32	126.848602
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	183
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	250
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1558162176
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	241
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2071792384
PrevISDATBSI412MsgDLCError_Cnt_M_u08	65
PrevISDATBSI412MsgRxTime_MSec_M_u32	2992552704
PrevISDATBSI432MsgDLCError_Cnt_M_u08	133
PrevISDATBSI432MsgRxTime_MSec_M_u32	1755028224
PrevISDATDIRAMsgTxTime_MSec_M_u32	3127032576
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	79
PrevISDYN2CMMMsgRxTime_MSec_M_u32	269175552
PrevISDYNAASMsgDLCError_Cnt_M_u08	188
PrevISDYNAASMsgRxTime_MSec_M_u32	4003871488
PrevISDYNABRMsgDLCError_Cnt_M_u08	211
PrevISDYNABRMsgRxTime_MSec_M_u32	3680795392

Name	Input Value
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	207
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1327446784
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	62
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3735198464
PrevISDYNVOLMsgDLCError_Cnt_M_u08	170
PrevISDYNVOLMsgRxTime_MSec_M_u32	1905244928
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3685935872
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	393.534912
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	15723
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	61462
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	23768
VitesseVehicleBVRampValidCount_Cnt_M_u16	46915
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	56498
VitesseVehicleBVSigValidCount_Cnt_M_u16	51238
VitesseVehicleBV_Kph_M_f32	220.283707
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	52386
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	62253
VitesseVehiculeRoues_Kph_M_f32	432.579498
k_AASNTCEnableTimeout_mS_u16	39097
k_AASNodeAbsentDiag_Cnt_str.Threshold	16129
k_AASNodeAbsentDiag_Cnt_str.PStep	11609
k_AASNodeAbsentDiag_Cnt_str.NStep	26423
k_AASNodeAbsentTimeout_mS_u16	65371
k_AASNodeTimeout_mS_u16	44822
k_ABSNodeTimeout_mS_u16	64195
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	46119
k_ANGLEVOLANTSigValidThresh_Cnt_u16	10311
k_AngleVolantInvalidThresh_Cnt_u16	33986
k_AngleVolantValidThresh_Cnt_u16	2238
k_BSI552MsgTimeout_mS_u16	18280
k_BSINTCEnableTimeout_mS_u16	52128
k_BSINodeAbsentDiag_Cnt_str.Threshold	24652
k_BSINodeAbsentDiag_Cnt_str.PStep	35063
k_BSINodeAbsentDiag_Cnt_str.NStep	14268
k_BSINodeAbsentTimeout_mS_u16	57352
k_BSINodeTimeout_mS_u16	55731
k_BattOvHi_Volt_f32	27.8603001
k_BattOvLo_Volt_f32	17.5426006
k_BattUvHi_Volt_f32	16.6634007
k_BattUvLo_Volt_f32	14.8975
k_CAVNTCEnableTimeout_mS_u16	17276
k_CAVNodeAbsentDiag_Cnt_str.Threshold	10291
k_CAVNodeAbsentDiag_Cnt_str.PStep	38407
k_CAVNodeAbsentDiag_Cnt_str.NStep	20751
k_CAVNodeAbsentTimeout_mS_u16	30244
k_CAVNodeTimeout_mS_u16	36304
k_CMM388MsgTimeout_mS_u16	65231
k_CMM388NTCEnableTimeout_mS_u16	13083
k_CMMNTCEnableTimeout_mS_u16	6936
k_CMMNodeAbsentDiag_Cnt_str.Threshold	56396
k_CMMNodeAbsentDiag_Cnt_str.PStep	28770
k_CMMNodeAbsentDiag_Cnt_str.NStep	6476
k_CMMNodeAbsentTimeout_mS_u16	46457
k_CONSANGLECPKMax_HwDeg_f32	385.285309
k_CONSANGLECPKMin_HwDeg_f32	-327.368896
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	19362
k_CONSANGLECPKSigValidThresh_Cnt_u16	45613

Name	Input Value
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	55076
k_CPKVehicleSpeedValidThresh_Cnt_u16	13522
k_CityParkInputInvalidThresh_Cnt_u16	25460
k_CityParkInputValidThresh_Cnt_u16	53552
k_ComputerRazGCTSigValidThresh_Cnt_u16	63086
k_CptTemporelSigValidThresh_Cnt_u16	35045
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	48023
k_DMDFCTCPKSigValidThresh_Cnt_u16	52506
k_DMDFCTCPKValidCount_Cnt_u16	43584
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	13213
k_DMDRELAXECPKSigValidThresh_Cnt_u16	56344
k_DMDRelaxeConsistentThresh_Cnt_u16	38438
k_DateValidThresh_Cnt_u16	14419
k_DefaultVehSpd_Kph_f32	255
k_DiagMuxOnAbsentTimeout_mS_u16	26380
k_EMNodeTimeout_mS_u16	42245
k_ESPNTCEnableTimeout_mS_u16	23370
k_ESPNodeAbsentDiag_Cnt_str.Threshold	65101
k_ESPNodeAbsentDiag_Cnt_str.PStep	32086
k_ESPNodeAbsentDiag_Cnt_str.NStep	47577
k_ESPNodeAbsentTimeout_mS_u16	12257
k_EtatMTSigInvalidThresh_Cnt_u16	11457
k_EtatMTSigValidThresh_Cnt_u16	32668
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	6539
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	58618
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	2717
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	20417
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	19064
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	5247
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	9161
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	28009
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	34492
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	21602
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	14570
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	13578
k_ISDATDIRASentDiag_Cnt_str.Threshold	53942
k_ISDATDIRASentDiag_Cnt_str.PStep	39317
k_ISDATDIRASentDiag_Cnt_str.NStep	7247
k_ISDATDIRASentTimeout_mS_u16	35378
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	24323
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	55408
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	28006
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	58342
k_ISDYNAASChkSumValidThresh_Cnt_u16	47233
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	48060
k_ISDYNAASMsgCountValidThresh_Cnt_u16	25423
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	65178
k_ISDYNAASMsgLenValidThresh_Cnt_u16	9418
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	22703
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	17341
k_ISDYNABRChkSumValidThresh_Cnt_u16	17856
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	25048
k_ISDYNABRMsgCountValidThresh_Cnt_u16	64972
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46164
k_ISDYNABRMsgLenValidThresh_Cnt_u16	57396
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	9607
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	54047
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	33144
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	46673
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	7365
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	121
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	25686
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	1642
k_ISDYNVOLChkSumValidThresh_Cnt_u16	35217
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	46293
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	12853
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	11219
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	17890
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	21905
k_IgnOnTimeout_mS_u16	12214
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	254.947906
k_PowerCutVehSpdLowThresh_Kph_f32	190.7995

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_PowerCutVehSpdLowTimeout_mS_u16	28341
k_VBattMaxAAS_Volt_f32	28.9400005
k_VBattMaxBSI_Volt_f32	3.15829992
k_VBattMaxCAV_Volt_f32	13.0474997
k_VBattMaxCMM388_Volt_f32	31.4444008
k_VBattMaxCMM_Volt_f32	23.8554001
k_VBattMaxESP_Volt_f32	0.929400027
k_VBattMinAAS_Volt_f32	16.5384007
k_VBattMinBSI_Volt_f32	0.929400027
k_VBattMinCAV_Volt_f32	5.92500019
k_VBattMinCMM388_Volt_f32	32
k_VBattMinCMM_Volt_f32	31.3295002
k_VBattMinESP_Volt_f32	23.8554001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	24053
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	44812
k_VitesseVehicleBVRampValidThresh_Cnt_u16	38192
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	34669
k_VitesseVehicleBVSigValidThresh_Cnt_u16	11829
k_VitesseVehicleBVSpeedPassThresh_kph_f32	138.382095
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	41214
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	60393
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3855997696
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	121
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	2073
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1490897664
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	62
target_SrlComInput_Per1_Batt_Volt_f32.value	5.98740005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	622955264
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	21
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.802492142
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	103
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1800305408
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2103188224
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	85
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1400486656
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	124
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	363289344
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3957652224
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	243
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4264729344
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	146
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1955609344
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	20
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	41
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	64
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	91
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3455343360
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	48
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	49
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	74

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	122
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	167
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	193
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	157
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	569735936
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	92478208
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1830861568
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	77
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	101
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3517385472
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	790
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.352136403
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	797901
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	88.0341034
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	21469

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1490897664	1490897664	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1490897664	1490897664	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-658.175537	-658.175537	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1490897664	1490897664	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	10291	10291	✔
CAVNodeAbsentTimer_mS_M_u32	1490897664	1490897664	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	56396	56396	✔
CMMNodeAbsentTimer_mS_M_u32	1490897664	1490897664	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	52430	52430	✔
CONSANGLECPK_HwDeg_M_f32	463.707001	463.707001 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CPKVehicleSpeedMsgTimer_mS_M_u32	1490897664	1490897664	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1490897664	1490897664	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1490897664	1490897664	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1490897664	1490897664	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1490897664	1490897664	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1490897664	1490897664	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1490897664	1490897664	✔
ESPNTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1490897664	1490897664	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔
EffacDefaultDiagTimer_mS_M_u32[1]	19	19	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4	4	✔
ElecIntTimer_mS_M_u32[1]	7	7	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1490897664	1490897664	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDATDIRASentFltAcc_Cnt_M_u16	53942	53942	✔
ISDATDIRASentTimer_mS_M_u32	1490897664	1490897664	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1490897664	1490897664	✔
IgnOnTimer_mS_M_u32	1573681920	1573681920	✔
IgnTimeOff_Sec_M_u32	2889666373	2889666373	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	103	103	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1800305408	1800305408	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2103188224	2103188224	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	85	85	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1400486656	1400486656	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	124	124	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	363289344	363289344	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3127032576	3127032576	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	243	243	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4264729344	4264729344	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	146	146	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1955609344	1955609344	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	196	196	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3455343360	3455343360	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	157	157	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	569735936	569735936	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	45	45	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	92478208	92478208	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	46	46	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1830861568	1830861568	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3517385472	3517385472	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	393.534912	393.534912	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VitesseVehicleBV_Kph_M_f32	220.283707	220.283707	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	432.579498	432.579498	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-658.175537	-658.175537	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	52430	52430	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2889666373	2889666373	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	463.707001	463.707001 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.100 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1473643008
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	39836
AASNodeAbsentTimer_mS_M_u32	1155723776
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	15289
ANGLEVOLANTSigValidCount_Cnt_M_u16	22879
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	54713
AngleVolantMsgTimer_mS_M_u32	1473643008
AngleVolantValidCount_Cnt_M_u16	23318
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-680.051636
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2472194560
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1330196992
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1970053632

Name	Input Value
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1735614976
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	30848
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1877287424
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	22927
CAVNodeAbsentTimer_mS_M_u32	562926080
CDD_SrlComVehSpd_Kph_G_f32	570.171997
CMM388NTCEnableTimer_mS_M_u32	1042403840
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1818464768
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	34123
CMMNodeAbsentTimer_mS_M_u32	1662870016
CONSANGLECPKSigInvalidCount_Cnt_M_u16	33916
CONSANGLECPKSigValidCount_Cnt_M_u16	49523
CONSANGLECPK_Cnt_M_u16	48734
CONSANGLECPK_HwDeg_M_f32	-722.695801
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	48734
CPKVehicleSpeedMsgTimer_mS_M_u32	3923051008
CPKVehicleSpeedValidCount_Cnt_M_u16	31779
CityParkInputConsistentCount_Cnt_M_u16	61946
CityParkInputInvalidCount_Cnt_M_u16	21583
CityParkInputMsgTimer_mS_M_u32	1800305408
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2496066048
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	18560
ComputerRazGCTSigInvalidTimer_mS_M_u32	1647186432
ComputerRazGCTSigValidCount_Cnt_M_u16	53967
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	39275
DMDFCTCPKSigValidCount_Cnt_M_u16	53626
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	40491
DMDRELAXECPKSigValidCount_Cnt_M_u16	3409
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	14233
DateInvalidTimer_mS_M_u32	1330196992
DiagMuxOnAbsentTimer_mS_M_u32	1193787904
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1735614976
ESPNTCEnableTimer_mS_M_u32	715387392
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	31342
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	555
EffacDefaultDiagTimer_mS_M_u32[1]	2683494912
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	1100
ElecIntTimer_mS_M_u32[1]	2683494912
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2226594304
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	25013
EtatMTSigValidCount_Cnt_M_u16	44871
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	48366
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	52069
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	54864
ISDAT4V2BSI552MsgTimer_mS_M_u32	2516673024
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	54602
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	39460
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	44871
ISDATBSI3F2MsgTimer_mS_M_u32	649445888
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	44392
ISDATBSI412MsgLenValidCount_Cnt_M_u16	39027
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	25013
ISDATBSI412MsgTimer_mS_M_u32	1029964288
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	56111

Name	Input Value
ISDATBSI432MsgLenValidCount_Cnt_M_u16	13138
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	18032
ISDATDIRASentFltAcc_Cnt_M_u16	44900
ISDATDIRASentTimer_mS_M_u32	3923051008
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	52332
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	23318
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	4018
ISDYN2CMMMsgTimer_mS_M_u32	1389228544
ISDYNAASChkSumInvalidCount_Cnt_M_u16	2574
ISDYNAASChkSumValidCount_Cnt_M_u16	1236
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	55133
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	6842
ISDYNAASMsgLenValidCount_Cnt_M_u16	64760
ISDYNAASMsgTimeValidCount_Cnt_M_u16	2574
ISDYNAASMsgTimer_mS_M_u32	1212011008
ISDYNABRChkSumInvalidCount_Cnt_M_u16	33238
ISDYNABRChkSumValidCount_Cnt_M_u16	27844
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	22741
ISDYNABRMsgCountValidCount_Cnt_M_u16	43739
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	54851
ISDYNABRMsgLenValidCount_Cnt_M_u16	43642
ISDYNABRMsgTimeValidCount_Cnt_M_u16	48734
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	682
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1249
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	44871
ISDYNCMM208MsgTimer_mS_M_u32	678408704
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2579
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1355
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	18340
ISDYNCMM388MsgTimer_mS_M_u32	2080461312
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	7178
ISDYNVOLChkSumValidCount_Cnt_M_u16	34689
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	29689
ISDYNVOLMsgCountValidCount_Cnt_M_u16	6792
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	15015
ISDYNVOLMsgLenValidCount_Cnt_M_u16	64125
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	34123
ISDYNVOLMsgTimer_mS_M_u32	407507456
IgnOnTimer_mS_M_u32	2313507328
IgnTimeOff_Sec_M_u32	1776530444
ManVehSpd_Kph_M_f32	534.848694
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	185
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	210
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	359383552
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	43
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1729339904
PrevISDATBSI412MsgDLCError_Cnt_M_u08	55
PrevISDATBSI412MsgRxTime_MSec_M_u32	2771292672
PrevISDATBSI432MsgDLCError_Cnt_M_u08	165
PrevISDATBSI432MsgRxTime_MSec_M_u32	234353152
PrevISDATDIRAMsgTxTime_MSec_M_u32	2636288512
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	218
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2993218048
PrevISDYNAASMsgDLCError_Cnt_M_u08	126
PrevISDYNAASMsgRxTime_MSec_M_u32	1851265536
PrevISDYNABRMsgDLCError_Cnt_M_u08	112
PrevISDYNABRMsgRxTime_MSec_M_u32	1897746944
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	158
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1894584832
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	174
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2279797248
PrevISDYNVOLMsgDLCError_Cnt_M_u08	172

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevISDYNVOLMsgRxTime_MSec_M_u32	1805357568
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4126278144
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	286.653687
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	64328
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	52230
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	37121
VitesseVehicleBVRampValidCount_Cnt_M_u16	27263
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	62194
VitesseVehicleBVSigValidCount_Cnt_M_u16	14680
VitesseVehicleBV_Kph_M_f32	567.971313
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	18340
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	15555
VitesseVehiculeRoues_Kph_M_f32	627.163391
k_AASNTCEnableTimeout_mS_u16	50845
k_AASNodeAbsentDiag_Cnt_str.Threshold	23734
k_AASNodeAbsentDiag_Cnt_str.PStep	52070
k_AASNodeAbsentDiag_Cnt_str.NStep	8645
k_AASNodeAbsentTimeout_mS_u16	54137
k_AASNodeTimeout_mS_u16	36614
k_ABSNodeTimeout_mS_u16	53824
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	21714
k_ANGLEVOLANTSigValidThresh_Cnt_u16	45365
k_AngleVolantInvalidThresh_Cnt_u16	18372
k_AngleVolantValidThresh_Cnt_u16	21583
k_BSI552MsgTimeout_mS_u16	60434
k_BSINTCEnableTimeout_mS_u16	12903
k_BSINodeAbsentDiag_Cnt_str.Threshold	24692
k_BSINodeAbsentDiag_Cnt_str.PStep	35046
k_BSINodeAbsentDiag_Cnt_str.NStep	14291
k_BSINodeAbsentTimeout_mS_u16	7921
k_BSINodeTimeout_mS_u16	18032
k_BattOvHi_Volt_f32	1.89579999
k_BattOvLo_Volt_f32	7.17259979
k_BattUvHi_Volt_f32	27.1709003
k_BattUvLo_Volt_f32	19.3605003
k_CAVNTCEnableTimeout_mS_u16	7189
k_CAVNodeAbsentDiag_Cnt_str.Threshold	21880
k_CAVNodeAbsentDiag_Cnt_str.PStep	23283
k_CAVNodeAbsentDiag_Cnt_str.NStep	55572
k_CAVNodeAbsentTimeout_mS_u16	29981
k_CAVNodeTimeout_mS_u16	34456
k_CMM388MsgTimeout_mS_u16	40604
k_CMM388NTCEnableTimeout_mS_u16	12728
k_CMMNTCEnableTimeout_mS_u16	34946
k_CMMNodeAbsentDiag_Cnt_str.Threshold	55221
k_CMMNodeAbsentDiag_Cnt_str.PStep	7722
k_CMMNodeAbsentDiag_Cnt_str.NStep	43108
k_CMMNodeAbsentTimeout_mS_u16	9695
k_CONSANGLECPKMax_HwDeg_f32	622.87793
k_CONSANGLECPKMin_HwDeg_f32	-722.965271
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	51876
k_CONSANGLECPKSigValidThresh_Cnt_u16	65475
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	52956
k_CPKVehicleSpeedValidThresh_Cnt_u16	62547
k_CityParkInputInvalidThresh_Cnt_u16	15916
k_CityParkInputValidThresh_Cnt_u16	61946
k_ComputerRazGCTSigValidThresh_Cnt_u16	52864

Name	Input Value
k_CptTemporelSigValidThresh_Cnt_u16	12250
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	55619
k_DMDFCTCPKSigValidThresh_Cnt_u16	60794
k_DMDFCTCPKValidCount_Cnt_u16	16968
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	4018
k_DMDRELAXECPKSigValidThresh_Cnt_u16	16129
k_DMDRelaxeConsistentThresh_Cnt_u16	51415
k_DateValidThresh_Cnt_u16	54864
k_DefaultVehSpd_Kph_f32	151.866394
k_DiagMuxOnAbsentTimeout_mS_u16	26532
k_EMNodeTimeout_mS_u16	21753
k_ESPNTCEnableTimeout_mS_u16	56747
k_ESPNodeAbsentDiag_Cnt_str.Threshold	53779
k_ESPNodeAbsentDiag_Cnt_str.PStep	13486
k_ESPNodeAbsentDiag_Cnt_str.NStep	63773
k_ESPNodeAbsentTimeout_mS_u16	22183
k_EtatMTSigInvalidThresh_Cnt_u16	22085
k_EtatMTSigValidThresh_Cnt_u16	1651
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	25511
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	64026
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	14771
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	52871
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	63265
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	18764
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	3564
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	59855
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	28947
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	30626
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	8908
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	9386
k_ISDATDIRASentDiag_Cnt_str.Threshold	10352
k_ISDATDIRASentDiag_Cnt_str.PStep	3786
k_ISDATDIRASentDiag_Cnt_str.NStep	49618
k_ISDATDIRASentTimeout_mS_u16	16882
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	51903
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	54713
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	5975
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	1238
k_ISDYNAASChkSumValidThresh_Cnt_u16	12228
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	23509
k_ISDYNAASMsgCountValidThresh_Cnt_u16	60891
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	33978
k_ISDYNAASMsgLenValidThresh_Cnt_u16	65002
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	49149
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	22737
k_ISDYNABRChkSumValidThresh_Cnt_u16	39816
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	31616
k_ISDYNABRMsgCountValidThresh_Cnt_u16	45158
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	18507
k_ISDYNABRMsgLenValidThresh_Cnt_u16	32110
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	58677
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	2604
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	9825
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	9557
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	16057
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	40031
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	41351
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	57227
k_ISDYNVOLChkSumValidThresh_Cnt_u16	11990
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	50059
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	37544
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	43729
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	54627
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	63126
k_IgnOnTimeout_mS_u16	37799
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	59.1982994
k_PowerCutVehSpdLowThresh_Kph_f32	227.6436
k_PowerCutVehSpdLowTimeout_mS_u16	13481
k_VBattMaxAAS_Volt_f32	9.28509998
k_VBattMaxBSI_Volt_f32	0.585200012
k_VBattMaxCAV_Volt_f32	28.8288002
k_VBattMaxCMM388_Volt_f32	15.4681997

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMaxCMM_Volt_f32	25.6991005
k_VBattMaxESP_Volt_f32	25.0932007
k_VBattMinAAS_Volt_f32	26.9927998
k_VBattMinBSI_Volt_f32	25.0932007
k_VBattMinCAV_Volt_f32	24.5116997
k_VBattMinCMM388_Volt_f32	31.3530998
k_VBattMinCMM_Volt_f32	8.52960014
k_VBattMinESP_Volt_f32	25.6991005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	5609
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	47972
k_VitesseVehicleBVRampValidThresh_Cnt_u16	63225
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	51841
k_VitesseVehicleBVSigValidThresh_Cnt_u16	12011
k_VitesseVehicleBVSpeedPassThresh_kph_f32	516.913086
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	56463
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	58509
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1330196992
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	137
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	21877
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2683494912
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	174
target_SrlComInput_Per1_Batt_Volt_f32.value	15.8554001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2619744768
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	240
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.323594302
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3915338240
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1907782144
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3990721024
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3855921664
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3785085440
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1764946432
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	77206016
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	8
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	118
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	130
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	820883968
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	123
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	218
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	236
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	248

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	232
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	560615936
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	213
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	893481472
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4243100160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	45
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	166
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	167
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2358616576
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	328
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.297140688
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	648010
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	220.189697
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	65522

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2683494912	2683494912	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-680.051636	-680.051636	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	21880	21880	✔
CAVNodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	55221	55221	✔
CMMNodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	48734	48734	✔
CONSANGLECPK_HwDeg_M_f32	-722.695801	-722.695801 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2683494912	2683494912	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2683494912	2683494912	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2683494912	2683494912	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2683494912	2683494912	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2683494912	2683494912	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2683494912	2683494912	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2683494912	2683494912	✔
ESPNTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	555	555	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2683494912	2683494912	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1100	1100	✔
ElecIntTimer_mS_M_u32[1]	2683494912	2683494912	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2683494912	2683494912	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDATDIRASentFltAcc_Cnt_M_u16	10352	10352	✔
ISDATDIRASentTimer_mS_M_u32	2683494912	2683494912	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2683494912	2683494912	✔
IgnOnTimer_mS_M_u32	2313507328	2313507328	✔
IgnTimeOff_Sec_M_u32	1776530444	1776530444	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	46	46	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3915338240	3915338240	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	239	239	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1907782144	1907782144	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	224	224	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3990721024	3990721024	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	137	137	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3855921664	3855921664	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2636288512	2636288512	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	35	35	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1764946432	1764946432	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	35	35	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	77206016	77206016	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	37	37	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	820883968	820883968	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	232	232	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	560615936	560615936	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	213	213	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	893481472	893481472	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	178	178	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4243100160	4243100160	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2358616576	2358616576	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	286.653687	286.653687	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	567.971313	567.971313	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	627.163391	627.163391	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-680.051636	-680.051636	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	48734	48734	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1776530444	1776530444	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-722.695801	-722.695801 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.101 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2393160960
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	64849
AASNodeAbsentTimer_mS_M_u32	1732111616
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	12027
ANGLEVOLANTSigValidCount_Cnt_M_u16	48072
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	762
AngleVolantMsgTimer_mS_M_u32	2393160960
AngleVolantValidCount_Cnt_M_u16	53090
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-351.4841
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	181841152
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2970299648
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1482743040
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	223124736
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	21670
BattOk_Cnt_M_lgc	0

Name	Input Value
CAVNTCEnableTimer_mS_M_u32	3942079744
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	22009
CAVNodeAbsentTimer_mS_M_u32	1136528640
CDD_SrlComVehSpd_Kph_G_f32	346.703186
CMM388NTCEnableTimer_mS_M_u32	2399227136
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	993791232
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	57731
CMMNodeAbsentTimer_mS_M_u32	1112448256
CONSANGLECPKSigInvalidCount_Cnt_M_u16	5040
CONSANGLECPKSigValidCount_Cnt_M_u16	33421
CONSANGLECPK_Cnt_M_u16	63436
CONSANGLECPK_HwDeg_M_f32	-406.773407
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	63436
CPKVehicleSpeedMsgTimer_mS_M_u32	2494020864
CPKVehicleSpeedValidCount_Cnt_M_u16	29668
CityParkInputConsistentCount_Cnt_M_u16	39606
CityParkInputInvalidCount_Cnt_M_u16	22711
CityParkInputMsgTimer_mS_M_u32	3915338240
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	127003904
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	34469
ComputerRazGCTSigInvalidTimer_mS_M_u32	2749140224
ComputerRazGCTSigValidCount_Cnt_M_u16	35895
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	63843
DMDFCTCPKSigValidCount_Cnt_M_u16	55031
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	20389
DMDRELAXECPKSigValidCount_Cnt_M_u16	59378
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	44633
DateInvalidTimer_mS_M_u32	2970299648
DiagMuxOnAbsentTimer_mS_M_u32	934247680
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	223124736
ESPNTCEnableTimer_mS_M_u32	4193971456
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	55259
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	963
EffacDefaultDiagTimer_mS_M_u32[1]	7852
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	977
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1954635008
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	33095
EtatMTSigValidCount_Cnt_M_u16	11856
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	45658
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	44215
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	41077
ISDAT4V2BSI552MsgTimer_mS_M_u32	966958336
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	46087
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	6968
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	11856
ISDATBSI3F2MsgTimer_mS_M_u32	1359314176
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	29868
ISDATBSI412MsgLenValidCount_Cnt_M_u16	10573
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	33095
ISDATBSI412MsgTimer_mS_M_u32	2516237568
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	28631
ISDATBSI432MsgLenValidCount_Cnt_M_u16	15663
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	21334
ISDATDIRASentFltAcc_Cnt_M_u16	59514
ISDATDIRASentTimer_mS_M_u32	2494020864
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	34210

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	53090
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	29326
ISDYN2CMMMsgTimer_mS_M_u32	2843536640
ISDYNAASChkSumInvalidCount_Cnt_M_u16	63995
ISDYNAASChkSumValidCount_Cnt_M_u16	28519
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	13965
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	32376
ISDYNAASMsgLenValidCount_Cnt_M_u16	7549
ISDYNAASMsgTimeValidCount_Cnt_M_u16	63995
ISDYNAASMsgTimer_mS_M_u32	3769453824
ISDYNABRChkSumInvalidCount_Cnt_M_u16	2595
ISDYNABRChkSumValidCount_Cnt_M_u16	20248
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	59814
ISDYNABRMsgCountValidCount_Cnt_M_u16	22866
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	64091
ISDYNABRMsgLenValidCount_Cnt_M_u16	41848
ISDYNABRMsgTimeValidCount_Cnt_M_u16	63436
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	683
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1251
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	11856
ISDYNCMM208MsgTimer_mS_M_u32	3751259392
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2583
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1357
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	49592
ISDYNCMM388MsgTimer_mS_M_u32	3009596672
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	1286
ISDYNVOLChkSumValidCount_Cnt_M_u16	59491
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	8633
ISDYNVOLMsgCountValidCount_Cnt_M_u16	46029
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	47920
ISDYNVOLMsgLenValidCount_Cnt_M_u16	8557
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	57731
ISDYNVOLMsgTimer_mS_M_u32	4052258048
IgnOnTimer_mS_M_u32	431410432
IgnTimeOff_Sec_M_u32	376920879
ManVehSpd_Kph_M_f32	0.798600018
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	187
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	229
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3705896192
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	32
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3748388096
PrevISDATBSI412MsgDLCError_Cnt_M_u08	9
PrevISDATBSI412MsgRxTime_MSec_M_u32	2094730496
PrevISDATBSI432MsgDLCError_Cnt_M_u08	12
PrevISDATBSI432MsgRxTime_MSec_M_u32	2684284160
PrevISDATDIRAMsgTxTime_MSec_M_u32	1694436608
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	184
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3798736128
PrevISDYNAASMsgDLCError_Cnt_M_u08	11
PrevISDYNAASMsgRxTime_MSec_M_u32	2807991552
PrevISDYNABRMsgDLCError_Cnt_M_u08	143
PrevISDYNABRMsgRxTime_MSec_M_u32	1141820672
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	164
PrevISDYNCMM208MsgRxTime_MSec_M_u32	866094336
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	91
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2654858496
PrevISDYNVOLMsgDLCError_Cnt_M_u08	149
PrevISDYNVOLMsgRxTime_MSec_M_u32	496241920
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	609271040
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	402.471405
PrevVitesseVehicleBVValid_Cnt_M_lgc	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	38094
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	26707
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	63395
VitesseVehicleBVRampValidCount_Cnt_M_u16	45288
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	11600
VitesseVehicleBVSigValidCount_Cnt_M_u16	16349
VitesseVehicleBV_Kph_M_f32	273.826904
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	49592
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	43037
VitesseVehiculeRoues_Kph_M_f32	0
k_AASNTCEnableTimeout_mS_u16	39695
k_AASNodeAbsentDiag_Cnt_str.Threshold	65010
k_AASNodeAbsentDiag_Cnt_str.PStep	58555
k_AASNodeAbsentDiag_Cnt_str.NStep	46517
k_AASNodeAbsentTimeout_mS_u16	45625
k_AASNodeTimeout_mS_u16	8019
k_ABSNodeTimeout_mS_u16	58084
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	20206
k_ANGLEVOLANTSigValidThresh_Cnt_u16	3974
k_AngleVolantInvalidThresh_Cnt_u16	18393
k_AngleVolantValidThresh_Cnt_u16	22711
k_BSI552MsgTimeout_mS_u16	38448
k_BSINTCEnableTimeout_mS_u16	18991
k_BSINodeAbsentDiag_Cnt_str.Threshold	24732
k_BSINodeAbsentDiag_Cnt_str.PStep	35029
k_BSINodeAbsentDiag_Cnt_str.NStep	14314
k_BSINodeAbsentTimeout_mS_u16	1874
k_BSINodeTimeout_mS_u16	21334
k_BattOvHi_Volt_f32	18.3577995
k_BattOvLo_Volt_f32	14.5560999
k_BattUvHi_Volt_f32	31.5
k_BattUvLo_Volt_f32	30.2334995
k_CAVNTCEnableTimeout_mS_u16	39269
k_CAVNodeAbsentDiag_Cnt_str.Threshold	22182
k_CAVNodeAbsentDiag_Cnt_str.PStep	14669
k_CAVNodeAbsentDiag_Cnt_str.NStep	37184
k_CAVNodeAbsentTimeout_mS_u16	47951
k_CAVNodeTimeout_mS_u16	32092
k_CMM388MsgTimeout_mS_u16	62545
k_CMM388NTCEnableTimeout_mS_u16	43773
k_CMMNTCEnableTimeout_mS_u16	31327
k_CMMNodeAbsentDiag_Cnt_str.Threshold	5207
k_CMMNodeAbsentDiag_Cnt_str.PStep	6352
k_CMMNodeAbsentDiag_Cnt_str.NStep	52025
k_CMMNodeAbsentTimeout_mS_u16	23753
k_CONSANGLECPKMax_HwDeg_f32	316.187714
k_CONSANGLECPKMin_HwDeg_f32	-17.8656998
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	14520
k_CONSANGLECPKSigValidThresh_Cnt_u16	24349
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	14289
k_CPKVehicleSpeedValidThresh_Cnt_u16	3051
k_CityParkInputInvalidThresh_Cnt_u16	44321
k_CityParkInputValidThresh_Cnt_u16	39606
k_ComputerRazGCTSigValidThresh_Cnt_u16	8293
k_CptTemporelSigValidThresh_Cnt_u16	45590
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	61787
k_DMDFCTCPKSigValidThresh_Cnt_u16	55928
k_DMDFCTCPKValidCount_Cnt_u16	5966
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	29326

Name	Input Value
k_DMDRELAXECPKSigValidThresh_Cnt_u16	27234
k_DMDRelaxeConsistentThresh_Cnt_u16	42208
k_DateValidThresh_Cnt_u16	41077
k_DefaultVehSpd_Kph_f32	86.1694031
k_DiagMuxOnAbsentTimeout_mS_u16	37882
k_EMNodeTimeout_mS_u16	54841
k_ESPNTCEnableTimeout_mS_u16	14757
k_ESPNodeAbsentDiag_Cnt_str.Threshold	33820
k_ESPNodeAbsentDiag_Cnt_str.PStep	40226
k_ESPNodeAbsentDiag_Cnt_str.NStep	49646
k_ESPNodeAbsentTimeout_mS_u16	60017
k_EtatMTSigInvalidThresh_Cnt_u16	2262
k_EtatMTSigValidThresh_Cnt_u16	65035
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	25968
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	47064
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	59275
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	64592
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	14401
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	12544
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	2976
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	19896
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	15915
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	56320
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	53312
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	59365
k_ISDATDIRASentDiag_Cnt_str.Threshold	26174
k_ISDATDIRASentDiag_Cnt_str.PStep	57928
k_ISDATDIRASentDiag_Cnt_str.NStep	63366
k_ISDATDIRASentTimeout_mS_u16	14799
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	35238
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	762
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	15521
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	33059
k_ISDYNAASChkSumValidThresh_Cnt_u16	1560
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	57510
k_ISDYNAASMsgCountValidThresh_Cnt_u16	36946
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	37239
k_ISDYNAASMsgLenValidThresh_Cnt_u16	25255
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	814
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	10929
k_ISDYNABRChkSumValidThresh_Cnt_u16	34894
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	19366
k_ISDYNABRMsgCountValidThresh_Cnt_u16	37555
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	39043
k_ISDYNABRMsgLenValidThresh_Cnt_u16	52955
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	61510
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	63522
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	11713
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	22630
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	9723
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	62152
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	20751
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	10819
k_ISDYNVOLChkSumValidThresh_Cnt_u16	45604
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	45188
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	28012
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	5619
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	11260
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	55203
k_IgnOnTimeout_mS_u16	32239
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	71.5566025
k_PowerCutVehSpdLowThresh_Kph_f32	150.220703
k_PowerCutVehSpdLowTimeout_mS_u16	33003
k_VBattMaxAAS_Volt_f32	1.61930001
k_VBattMaxBSI_Volt_f32	21.8535995
k_VBattMaxCAV_Volt_f32	27.3894997
k_VBattMaxCMM388_Volt_f32	7.98110008
k_VBattMaxCMM_Volt_f32	14.8968
k_VBattMaxESP_Volt_f32	26.8659
k_VBattMinAAS_Volt_f32	6.98740005
k_VBattMinBSI_Volt_f32	26.8659
k_VBattMinCAV_Volt_f32	18.3945999

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinCMM388_Volt_f32	0.255100012
k_VBattMinCMM_Volt_f32	17.6464996
k_VBattMinESP_Volt_f32	14.8968
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	53288
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	5497
k_VitesseVehicleBVRampValidThresh_Cnt_u16	39097
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	8035
k_VitesseVehicleBVSigValidThresh_Cnt_u16	59363
k_VitesseVehicleBVSpeedPassThresh_kph_f32	4.61049986
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	52473
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	64190
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2970299648
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	91
target_SrlComInput_Per1_Batt_Volt_f32.value	31
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2855558400
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	54
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.190636054
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	234
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1665715456
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2395172096
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	516820224
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2070457600
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	210980096
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	65
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	978185472
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1821936896
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	159
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	175
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	196
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	245
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	213
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1042132224
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	58
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	84
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	107
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	115
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2804403456
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	807562496
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	211

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3719105792
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	25
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	33
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	104
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4142259456
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1330
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.728816092
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	887274
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	95.8321991
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	44752

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-351.4841	-351.4841	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	63436	63436	✔
CONSANGLECPK_HwDeg_M_f32	-406.773407	-406.773407 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2	2	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3251510528	3251510528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	963	963	✔
EffacDefaultDiagTimer_mS_M_u32[1]	7852	7852	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	97	97	✔
ElecIntTimer_mS_M_u32[1]	977	977	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	3251510528	3251510528	✔
IgnTimeOff_Sec_M_u32	376920879	376920879	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	234	234	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1665715456	1665715456	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	202	202	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2395172096	2395172096	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	91	91	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	516820224	516820224	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	5	5	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2070457600	2070457600	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1694436608	1694436608	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	65	65	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	978185472	978185472	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1821936896	1821936896	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	213	213	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1042132224	1042132224	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	167	167	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2804403456	2804403456	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	5	5	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	807562496	807562496	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	211	211	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3719105792	3719105792	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4142259456	4142259456	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	0	0	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	273.826904	273.826904	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	0	0	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-351.4841	-351.4841	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	63436	63436	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	376920879	376920879	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-406.773407	-406.773407 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.102 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2732887040
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	43231
AASNodeAbsentTimer_mS_M_u32	970521600
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	56799
ANGLEVOLANTSigValidCount_Cnt_M_u16	34361
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	31716
AngleVolantMsgTimer_mS_M_u32	2732887040
AngleVolantValidCount_Cnt_M_u16	298
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	-372.846741
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2718874624
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	561069056
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3727698944
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	510454784
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	55518
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2691476480
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	59238
CAVNodeAbsentTimer_mS_M_u32	1289264128
CDD_SrlComVehSpd_Kph_G_f32	52.2691002
CMM388NTCEnableTimer_mS_M_u32	2282675200

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3730742272
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	6280
CMMNodeAbsentTimer_mS_M_u32	124185600
CONSANGLECPKSigInvalidCount_Cnt_M_u16	62145
CONSANGLECPKSigValidCount_Cnt_M_u16	13547
CONSANGLECPK_Cnt_M_u16	37166
CONSANGLECPK_HwDeg_M_f32	-307.744598
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37166
CPKVehicleSpeedMsgTimer_mS_M_u32	1557892096
CPKVehicleSpeedValidCount_Cnt_M_u16	40109
CityParkInputConsistentCount_Cnt_M_u16	61230
CityParkInputInvalidCount_Cnt_M_u16	1581
CityParkInputMsgTimer_mS_M_u32	1665715456
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2833054720
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	23779
ComputerRazGCTSigInvalidTimer_mS_M_u32	3330087936
ComputerRazGCTSigValidCount_Cnt_M_u16	24235
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	54313
DMDFCTCPKSigValidCount_Cnt_M_u16	43563
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	41953
DMDRELAXECPKSigValidCount_Cnt_M_u16	10683
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	1734
DateInvalidTimer_mS_M_u32	561069056
DiagMuxOnAbsentTimer_mS_M_u32	1120160768
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	510454784
ESPNTCEnableTimer_mS_M_u32	3047291904
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	46142
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	200
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	6
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2882448384
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	39484
EtatMTSigValidCount_Cnt_M_u16	53730
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	16067
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	56941
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	50609
ISDAT4V2BSI552MsgTimer_mS_M_u32	1902832640
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	22908
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	682
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	53730
ISDATBSI3F2MsgTimer_mS_M_u32	3468839936
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	15500
ISDATBSI412MsgLenValidCount_Cnt_M_u16	48490
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	39484
ISDATBSI412MsgTimer_mS_M_u32	1692568576
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	48524
ISDATBSI432MsgLenValidCount_Cnt_M_u16	54338
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	41807
ISDATDIRASentFltAcc_Cnt_M_u16	29667
ISDATDIRASentTimer_mS_M_u32	1557892096
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	49068
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	298
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	54440
ISDYN2CMMMsgTimer_mS_M_u32	790363136
ISDYNAASChkSumInvalidCount_Cnt_M_u16	56033
ISDYNAASChkSumValidCount_Cnt_M_u16	18778
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	14249

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	10729
ISDYNAASMsgLenValidCount_Cnt_M_u16	31643
ISDYNAASMsgTimeValidCount_Cnt_M_u16	56033
ISDYNAASMsgTimer_mS_M_u32	1124785152
ISDYNABRChkSumInvalidCount_Cnt_M_u16	17383
ISDYNABRChkSumValidCount_Cnt_M_u16	25545
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	30688
ISDYNABRMsgCountValidCount_Cnt_M_u16	63385
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	43712
ISDYNABRMsgLenValidCount_Cnt_M_u16	15914
ISDYNABRMsgTimeValidCount_Cnt_M_u16	37166
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	684
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1253
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	53730
ISDYNCMM208MsgTimer_mS_M_u32	1741405184
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2587
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1359
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	552
ISDYNCMM388MsgTimer_mS_M_u32	2162842624
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	63167
ISDYNVOLChkSumValidCount_Cnt_M_u16	56169
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	13095
ISDYNVOLMsgCountValidCount_Cnt_M_u16	60329
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	40511
ISDYNVOLMsgLenValidCount_Cnt_M_u16	31305
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	6280
ISDYNVOLMsgTimer_mS_M_u32	2373524480
IgnOnTimer_mS_M_u32	2649644032
IgnTimeOff_Sec_M_u32	1075482626
ManVehSpd_Kph_M_f32	476.587097
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	189
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	76
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	589843456
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	198
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	890186752
PrevISDATBSI412MsgDLCError_Cnt_M_u08	224
PrevISDATBSI412MsgRxTime_MSec_M_u32	1434557440
PrevISDATBSI432MsgDLCError_Cnt_M_u08	240
PrevISDATBSI432MsgRxTime_MSec_M_u32	3549821952
PrevISDATDIRAMsgTxTime_MSec_M_u32	756390912
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	15
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2098097152
PrevISDYNAASMsgDLCError_Cnt_M_u08	89
PrevISDYNAASMsgRxTime_MSec_M_u32	1140268032
PrevISDYNABRMsgDLCError_Cnt_M_u08	197
PrevISDYNABRMsgRxTime_MSec_M_u32	2129026048
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	164
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3811843072
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	203
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2497248256
PrevISDYNVOLMsgDLCError_Cnt_M_u08	130
PrevISDYNVOLMsgRxTime_MSec_M_u32	2539035648
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2447412224
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	300.304504
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1

Name	Input Value
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	48871
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	29465
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	10856
VitesseVehicleBVRampValidCount_Cnt_M_u16	11610
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	30432
VitesseVehicleBVSigValidCount_Cnt_M_u16	36346
VitesseVehicleBV_Kph_M_f32	509.334106
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	552
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	64954
VitesseVehiculeRoues_Kph_M_f32	655.340027
k_AASNTCEnableTimeout_mS_u16	29541
k_AASNodeAbsentDiag_Cnt_str.Threshold	39723
k_AASNodeAbsentDiag_Cnt_str.PStep	44617
k_AASNodeAbsentDiag_Cnt_str.NStep	7954
k_AASNodeAbsentTimeout_mS_u16	29861
k_AASNodeTimeout_mS_u16	19993
k_ABSNodeTimeout_mS_u16	23462
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	15431
k_ANGLEVOLANTSigValidThresh_Cnt_u16	31037
k_AngleVolantInvalidThresh_Cnt_u16	56388
k_AngleVolantValidThresh_Cnt_u16	1581
k_BSI552MsgTimeout_mS_u16	16257
k_BSINTCEnableTimeout_mS_u16	36484
k_BSINodeAbsentDiag_Cnt_str.Threshold	24772
k_BSINodeAbsentDiag_Cnt_str.PStep	35012
k_BSINodeAbsentDiag_Cnt_str.NStep	14337
k_BSINodeAbsentTimeout_mS_u16	52956
k_BSINodeTimeout_mS_u16	41807
k_BattOvHi_Volt_f32	4.98479986
k_BattOvLo_Volt_f32	12.8034
k_BattUvHi_Volt_f32	17.7833004
k_BattUvLo_Volt_f32	4.04759979
k_CAVNTCEnableTimeout_mS_u16	31779
k_CAVNodeAbsentDiag_Cnt_str.Threshold	43047
k_CAVNodeAbsentDiag_Cnt_str.PStep	34537
k_CAVNodeAbsentDiag_Cnt_str.NStep	26632
k_CAVNodeAbsentTimeout_mS_u16	36708
k_CAVNodeTimeout_mS_u16	26045
k_CMM388MsgTimeout_mS_u16	50143
k_CMM388NTCEnableTimeout_mS_u16	20443
k_CMMNTCEnableTimeout_mS_u16	26228
k_CMMNodeAbsentDiag_Cnt_str.Threshold	16860
k_CMMNodeAbsentDiag_Cnt_str.PStep	3306
k_CMMNodeAbsentDiag_Cnt_str.NStep	25191
k_CMMNodeAbsentTimeout_mS_u16	36790
k_CONSANGLECPKMax_HwDeg_f32	359.682892
k_CONSANGLECPKMin_HwDeg_f32	-346.407898
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	40232
k_CONSANGLECPKSigValidThresh_Cnt_u16	55482
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	31903
k_CPKVehicleSpeedValidThresh_Cnt_u16	13007
k_CityParkInputInvalidThresh_Cnt_u16	53997
k_CityParkInputValidThresh_Cnt_u16	61230
k_ComputerRazGCTSigValidThresh_Cnt_u16	3170
k_CptTemporelSigValidThresh_Cnt_u16	13840
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	50624
k_DMDFCTCPKSigValidThresh_Cnt_u16	39210
k_DMDFCTCPKValidCount_Cnt_u16	12518
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	54440
k_DMDRELAXECPKSigValidThresh_Cnt_u16	23530
k_DMDRelaxeConsistentThresh_Cnt_u16	9328
k_DateValidThresh_Cnt_u16	50609
k_DefaultVehSpd_Kph_f32	46.8151016
k_DiagMuxOnAbsentTimeout_mS_u16	62628
k_EMNodeTimeout_mS_u16	3878

Name	Input Value
k_ESPNTCEnableTimeout_mS_u16	60514
k_ESPNodeAbsentDiag_Cnt_str.Threshold	21996
k_ESPNodeAbsentDiag_Cnt_str.PStep	43090
k_ESPNodeAbsentDiag_Cnt_str.NStep	17318
k_ESPNodeAbsentTimeout_mS_u16	34494
k_EtatMTSigInvalidThresh_Cnt_u16	54222
k_EtatMTSigValidThresh_Cnt_u16	58096
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	12226
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	63304
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	40111
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	58529
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	3983
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	22416
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	20017
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	1703
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	41616
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	46226
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	63120
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	22496
k_ISDATDIRASentDiag_Cnt_str.Threshold	57312
k_ISDATDIRASentDiag_Cnt_str.PStep	15993
k_ISDATDIRASentDiag_Cnt_str.NStep	54200
k_ISDATDIRASentTimeout_mS_u16	25827
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	46749
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	31716
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	54126
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	57063
k_ISDYNAASChkSumValidThresh_Cnt_u16	16073
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	37600
k_ISDYNAASMsgCountValidThresh_Cnt_u16	21145
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	65003
k_ISDYNAASMsgLenValidThresh_Cnt_u16	54301
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	15941
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	61886
k_ISDYNABRChkSumValidThresh_Cnt_u16	26536
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	62430
k_ISDYNABRMsgCountValidThresh_Cnt_u16	28024
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	62344
k_ISDYNABRMsgLenValidThresh_Cnt_u16	53054
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	24767
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	58603
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	42317
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	44768
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	63711
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	57657
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	32037
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	14279
k_ISDYNVOLChkSumValidThresh_Cnt_u16	16101
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	3651
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	22733
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	35896
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	35038
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	22567
k_IgnOnTimeout_mS_u16	60611
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	79.1535034
k_PowerCutVehSpdLowThresh_Kph_f32	139.161301
k_PowerCutVehSpdLowTimeout_mS_u16	12753
k_VBattMaxAAS_Volt_f32	7.94540024
k_VBattMaxBSI_Volt_f32	30.8381996
k_VBattMaxCAV_Volt_f32	7.4309001
k_VBattMaxCMM388_Volt_f32	13.1267996
k_VBattMaxCMM_Volt_f32	11.5544004
k_VBattMaxESP_Volt_f32	11.1929998
k_VBattMinAAS_Volt_f32	14.3676004
k_VBattMinBSI_Volt_f32	11.1929998
k_VBattMinCAV_Volt_f32	1.25450003
k_VBattMinCMM388_Volt_f32	15.5186005
k_VBattMinCMM_Volt_f32	17.5818005
k_VBattMinESP_Volt_f32	11.5544004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	27415
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	63973
k_VitesseVehicleBVRampValidThresh_Cnt_u16	52775

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	13929
k_VitesseVehicleBVSigValidThresh_Cnt_u16	64423
k_VitesseVehicleBVSpeedPassThresh_kph_f32	615.135193
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	33382
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	10200
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	561069056
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8816
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3873991680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	203
target_SrlComInput_Per1_Batt_Volt_f32.value	24.6198006
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2528488448
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	83
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.885017574
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2302172160
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3108535296
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4222131200
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	408468480
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3612924928
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	11074560
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	243
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1548295168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	56
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	136
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	155
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	193
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	188
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3828988928
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	80
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	92
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4187708416
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	111
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	288062464
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4211842048
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	42
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	93
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	105

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	122
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	124
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	162
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1453403136
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3695
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.746199608
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	384351
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	20.5765991
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	63713

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	31718	31718	✔
AngleVolantMsgTimer_mS_M_u32	3873991680	3873991680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	-372.846741	-372.846741	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	37166	37166	✔
CONSANGLECPK_HwDeg_M_f32	-307.744598	-307.744598 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37166	37166	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3873991680	3873991680	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	61230	61230	✔
CityParkInputInvalidCount_Cnt_M_u16	1583	1583	✔
CityParkInputMsgTimer_mS_M_u32	3873991680	3873991680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3873991680	3873991680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3873991680	3873991680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3873991680	3873991680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3873991680	3873991680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3873991680	3873991680	✔
ESPNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔
EffacDefaultDiagTimer_mS_M_u32[1]	200	200	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3873991680	3873991680	✔
ElecIntTimer_mS_M_u32[1]	6	6	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3873991680	3873991680	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3873991680	3873991680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3873991680	3873991680	✔
IgnOnTimer_mS_M_u32	2649644032	2649644032	✔
IgnTimeOff_Sec_M_u32	1075482626	1075482626	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	241	241	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2302172160	2302172160	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	227	227	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3108535296	3108535296	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	3	3	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4222131200	4222131200	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	26	26	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	408468480	408468480	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	756390912	756390912	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	74	74	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	11074560	11074560	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	243	243	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1548295168	1548295168	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	188	188	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3828988928	3828988928	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	246	246	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4187708416	4187708416	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	111	111	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	288062464	288062464	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	215	215	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4211842048	4211842048	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1453403136	1453403136	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	655.340027	655.340027	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	509.334106	509.334106	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	655.340027	655.340027	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-372.846741	-372.846741	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	37166	37166	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1075482626	1075482626	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-307.744598	-307.744598 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	655.340027	655.340027	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	13	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	13	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.103 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3961593600
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	58417
AASNodeAbsentTimer_mS_M_u32	3305361152
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	59184
ANGLEVOLANTSigValidCount_Cnt_M_u16	482
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	48930
AngleVolantMsgTimer_mS_M_u32	3961593600
AngleVolantValidCount_Cnt_M_u16	28624
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-506.577087
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2472709888
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3208318720
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1891516160
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2466774784
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	45619
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3154689792
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	20250
CAVNodeAbsentTimer_mS_M_u32	2458185472
CDD_SrlComVehSpd_Kph_G_f32	343.286896
CMM388NTCEnableTimer_mS_M_u32	2313301760
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1978855168
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	16500
CMMNodeAbsentTimer_mS_M_u32	1075445504
CONSANGLECPKSigInvalidCount_Cnt_M_u16	24458
CONSANGLECPKSigValidCount_Cnt_M_u16	60621
CONSANGLECPK_Cnt_M_u16	41988
CONSANGLECPK_HwDeg_M_f32	449.968292

Name	Input Value
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	41988
CPKVehicleSpeedMsgTimer_mS_M_u32	1513889536
CPKVehicleSpeedValidCount_Cnt_M_u16	8750
CityParkInputConsistentCount_Cnt_M_u16	46532
CityParkInputInvalidCount_Cnt_M_u16	32198
CityParkInputMsgTimer_mS_M_u32	2302172160
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2281164544
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	55333
ComputerRazGCTSigInvalidTimer_mS_M_u32	1469542144
ComputerRazGCTSigValidCount_Cnt_M_u16	39757
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	978
DMDFCTCPKSigValidCount_Cnt_M_u16	13708
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	7466
DMDRELAXECPKSigValidCount_Cnt_M_u16	40796
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	30587
DateInvalidTimer_mS_M_u32	3208318720
DiagMuxOnAbsentTimer_mS_M_u32	998366976
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2466774784
ESPNTCEnableTimer_mS_M_u32	3047739136
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	61714
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	89
EffacDefaultDiagTimer_mS_M_u32[1]	2274721536
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	19
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2715991808
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	39002
EtatMTSigValidCount_Cnt_M_u16	13608
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	900
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	30791
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	31482
ISDAT4V2BSI552MsgTimer_mS_M_u32	302907136
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	21529
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	48207
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13608
ISDATBSI3F2MsgTimer_mS_M_u32	260562688
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	15336
ISDATBSI412MsgLenValidCount_Cnt_M_u16	56590
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	39002
ISDATBSI412MsgTimer_mS_M_u32	505880320
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	24936
ISDATBSI432MsgLenValidCount_Cnt_M_u16	41222
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	65375
ISDATDIRASentFltAcc_Cnt_M_u16	56739
ISDATDIRASentTimer_mS_M_u32	1513889536
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	37002
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	28624
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	48725
ISDYN2CMMMsgTimer_mS_M_u32	2973421312
ISDYNAASChkSumInvalidCount_Cnt_M_u16	54827
ISDYNAASChkSumValidCount_Cnt_M_u16	7805
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	34899
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	21393
ISDYNAASMsgLenValidCount_Cnt_M_u16	53819
ISDYNAASMsgTimeValidCount_Cnt_M_u16	54827
ISDYNAASMsgTimer_mS_M_u32	1223569152
ISDYNABRChkSumInvalidCount_Cnt_M_u16	52886
ISDYNABRChkSumValidCount_Cnt_M_u16	41649
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	47918
ISDYNABRMsgCountValidCount_Cnt_M_u16	53184

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	62349
ISDYNABRMsgLenValidCount_Cnt_M_u16	36112
ISDYNABRMsgTimeValidCount_Cnt_M_u16	41988
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	685
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1255
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13608
ISDYNCMM208MsgTimer_mS_M_u32	1982566144
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2591
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1361
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	58582
ISDYNCMM388MsgTimer_mS_M_u32	1833938688
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	52112
ISDYNVOLChkSumValidCount_Cnt_M_u16	29011
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	24280
ISDYNVOLMsgCountValidCount_Cnt_M_u16	59666
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	30479
ISDYNVOLMsgLenValidCount_Cnt_M_u16	46769
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	16500
ISDYNVOLMsgTimer_mS_M_u32	4070797056
IgnOnTimer_mS_M_u32	641969920
IgnTimeOff_Sec_M_u32	2114971230
ManVehSpd_Kph_M_f32	254.180695
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	191
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	235
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	710270720
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	249
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2820751104
PrevISDATBSI412MsgDLCError_Cnt_M_u08	35
PrevISDATBSI412MsgRxTime_MSec_M_u32	1552543488
PrevISDATBSI432MsgDLCError_Cnt_M_u08	174
PrevISDATBSI432MsgRxTime_MSec_M_u32	734842624
PrevISDATDIRAMsgTxTime_MSec_M_u32	634253056
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	235
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3710091008
PrevISDYNAASMsgDLCError_Cnt_M_u08	59
PrevISDYNAASMsgRxTime_MSec_M_u32	1193897728
PrevISDYNABRMsgDLCError_Cnt_M_u08	23
PrevISDYNABRMsgRxTime_MSec_M_u32	1666952960
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	25
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2641522432
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	201
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3020148480
PrevISDYNVOLMsgDLCError_Cnt_M_u08	112
PrevISDYNVOLMsgRxTime_MSec_M_u32	722136832
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	254615296
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	322.180389
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	3223
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	25537
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1

Name	Input Value
VehicleSpeedValid_Cnt_M_Igc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	3604
VitesseVehicleBVRampValidCount_Cnt_M_u16	30974
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	24621
VitesseVehicleBVSigValidCount_Cnt_M_u16	11935
VitesseVehicleBV_Kph_M_f32	225.804001
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	58582
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	58848
VitesseVehiculeRoues_Kph_M_f32	1.35160005
k_AASNTCEnableTimeout_mS_u16	39263
k_AASNodeAbsentDiag_Cnt_str.Threshold	61629
k_AASNodeAbsentDiag_Cnt_str.PStep	16633
k_AASNodeAbsentDiag_Cnt_str.NStep	9080
k_AASNodeAbsentTimeout_mS_u16	49503
k_AASNodeTimeout_mS_u16	53953
k_ABSNodeTimeout_mS_u16	41307
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	37175
k_ANGLEVOLANTSigValidThresh_Cnt_u16	24085
k_AngleVolantInvalidThresh_Cnt_u16	4352
k_AngleVolantValidThresh_Cnt_u16	32198
k_BSI552MsgTimeout_mS_u16	64651
k_BSINTCEnableTimeout_mS_u16	52864
k_BSINodeAbsentDiag_Cnt_str.Threshold	24812
k_BSINodeAbsentDiag_Cnt_str.PStep	34995
k_BSINodeAbsentDiag_Cnt_str.NStep	14360
k_BSINodeAbsentTimeout_mS_u16	42554
k_BSINodeTimeout_mS_u16	65375
k_BattOvHi_Volt_f32	24.4083004
k_BattOvLo_Volt_f32	11.7117004
k_BattUvHi_Volt_f32	15.5292997
k_BattUvLo_Volt_f32	20.6501999
k_CAVNTCEnableTimeout_mS_u16	29668
k_CAVNodeAbsentDiag_Cnt_str.Threshold	58496
k_CAVNodeAbsentDiag_Cnt_str.PStep	37906
k_CAVNodeAbsentDiag_Cnt_str.NStep	5579
k_CAVNodeAbsentTimeout_mS_u16	53024
k_CAVNodeTimeout_mS_u16	63126
k_CMM388MsgTimeout_mS_u16	37681
k_CMM388NTCEnableTimeout_mS_u16	57149
k_CMMNTCEnableTimeout_mS_u16	3377
k_CMMNodeAbsentDiag_Cnt_str.Threshold	48906
k_CMMNodeAbsentDiag_Cnt_str.PStep	46200
k_CMMNodeAbsentDiag_Cnt_str.NStep	19927
k_CMMNodeAbsentTimeout_mS_u16	8172
k_CONSANGLECPKMax_HwDeg_f32	271.860596
k_CONSANGLECPKMin_HwDeg_f32	-279.114105
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	5078
k_CONSANGLECPKSigValidThresh_Cnt_u16	21728
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	57135
k_CPKVehicleSpeedValidThresh_Cnt_u16	9503
k_CityParkInputInvalidThresh_Cnt_u16	47492
k_CityParkInputValidThresh_Cnt_u16	46532
k_ComputerRazGCTSigValidThresh_Cnt_u16	21351
k_CptTemporelSigValidThresh_Cnt_u16	14877
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	41613
k_DMDFCTCPKSigValidThresh_Cnt_u16	31760
k_DMDFCTCPKValidCount_Cnt_u16	51739
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	48725
k_DMDRELAXECPKSigValidThresh_Cnt_u16	56399
k_DMDRelaxeConsistentThresh_Cnt_u16	6845
k_DateValidThresh_Cnt_u16	31482
k_DefaultVehSpd_Kph_f32	160.862305
k_DiagMuxOnAbsentTimeout_mS_u16	53666
k_EMNodeTimeout_mS_u16	56923
k_ESPNTCEnableTimeout_mS_u16	12326
k_ESPNodeAbsentDiag_Cnt_str.Threshold	55482
k_ESPNodeAbsentDiag_Cnt_str.PStep	59680
k_ESPNodeAbsentDiag_Cnt_str.NStep	55804
k_ESPNodeAbsentTimeout_mS_u16	23252
k_EtatMTSigInvalidThresh_Cnt_u16	31457
k_EtatMTSigValidThresh_Cnt_u16	33084
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	4550
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	32501

Name	Input Value
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	61761
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	34474
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	27040
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	64220
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	33657
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	56791
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	49756
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	51672
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	42910
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	35563
k_ISDATDIRASentDiag_Cnt_str.Threshold	2517
k_ISDATDIRASentDiag_Cnt_str.PStep	21985
k_ISDATDIRASentDiag_Cnt_str.NStep	63294
k_ISDATDIRASentTimeout_mS_u16	23458
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	41652
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	48930
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	43778
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	64918
k_ISDYNAASChkSumValidThresh_Cnt_u16	4529
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	27182
k_ISDYNAASMsgCountValidThresh_Cnt_u16	48832
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	45194
k_ISDYNAASMsgLenValidThresh_Cnt_u16	20661
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	12029
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	38547
k_ISDYNABRChkSumValidThresh_Cnt_u16	34966
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	24883
k_ISDYNABRMsgCountValidThresh_Cnt_u16	2085
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	44916
k_ISDYNABRMsgLenValidThresh_Cnt_u16	40978
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	2640
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	43659
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	17829
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	35948
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	38448
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	61666
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	63710
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	63031
k_ISDYNVOLChkSumValidThresh_Cnt_u16	1181
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	14083
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	54181
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	45670
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	52
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	7064
k_IgnOnTimeout_mS_u16	51011
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	98.3471985
k_PowerCutVehSpdLowThresh_Kph_f32	54.3237
k_PowerCutVehSpdLowTimeout_mS_u16	3611
k_VBattMaxAAS_Volt_f32	28.6681995
k_VBattMaxBSI_Volt_f32	6.2027998
k_VBattMaxCAV_Volt_f32	30.8239994
k_VBattMaxCMM388_Volt_f32	6.32439995
k_VBattMaxCMM_Volt_f32	19.5170002
k_VBattMaxESP_Volt_f32	12.9636002
k_VBattMinAAS_Volt_f32	7.82270002
k_VBattMinBSI_Volt_f32	12.9636002
k_VBattMinCAV_Volt_f32	16.8367996
k_VBattMinCMM388_Volt_f32	28.5074005
k_VBattMinCMM_Volt_f32	24.6058006
k_VBattMinESP_Volt_f32	19.5170002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	60742
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	9372
k_VitesseVehicleBVRampValidThresh_Cnt_u16	36312
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	24659
k_VitesseVehicleBVSigValidThresh_Cnt_u16	46169
k_VitesseVehicleBVSpeedPassThresh_kph_f32	44.9244995
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	32282
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	388
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3208318720
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	56852
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2274721536
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	201
target_SrlComInput_Per1_Batt_Volt_f32.value	12.1789999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1026408192
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	226
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.243530303
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	207990528
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1689603840
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3323260672
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3632566016
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1141124864
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2962476800
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3325259520
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	97
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	132
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	139
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	208
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	234
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	954306304
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	88
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	142
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	144
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	189
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	216
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	234
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	121417472
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2836156160
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	334229248
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	107
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	134
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	245
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	191577856
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	863
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0662784353

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	182758
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	231.327896
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	50857

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	48930	48930	✔
AngleVolantMsgTimer_mS_M_u32	2274721536	2274721536	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-506.577087	-506.577087	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
CDD_SrlComVehSpd_Kph_G_f32	1.35160005	1.35160005	✔
CMM388NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	41988	41988	✔
CONSANGLECPK_HwDeg_M_f32	449.968292	449.968292 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	41990	41990	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2274721536	2274721536	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	46532	46532	✔
CityParkInputInvalidCount_Cnt_M_u16	32200	32200	✔
CityParkInputMsgTimer_mS_M_u32	2274721536	2274721536	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2274721536	2274721536	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2274721536	2274721536	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2274721536	2274721536	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2274721536	2274721536	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2274721536	2274721536	✔
ESPNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	89	89	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2274721536	2274721536	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2274721536	2274721536	✔
ElecIntTimer_mS_M_u32[1]	19	19	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2274721536	2274721536	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2274721536	2274721536	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2274721536	2274721536	✔
IgnOnTimer_mS_M_u32	641969920	641969920	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
IgnTimeOff_Sec_M_u32	2114971230	2114971230	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	215	215	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	207990528	207990528	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	73	73	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1689603840	1689603840	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	113	113	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3323260672	3323260672	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	246	246	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3632566016	3632566016	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	634253056	634253056	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	183	183	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2962476800	2962476800	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	67	67	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3325259520	3325259520	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	210	210	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	954306304	954306304	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	121417472	121417472	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	241	241	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2836156160	2836156160	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	334229248	334229248	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	191577856	191577856	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	1.35160005	1.35160005	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	225.804001	225.804001	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	1.35160005	1.35160005	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-506.577087	-506.577087	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	41988	41988	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2114971230	2114971230	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	449.968292	449.968292 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.104 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1853318656
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	26693
AASNodeAbsentTimer_mS_M_u32	177165824
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	31050
ANGLEVOLANTSigValidCount_Cnt_M_u16	60915
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	56178
AngleVolantMsgTimer_mS_M_u32	1853318656
AngleVolantValidCount_Cnt_M_u16	2026
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-100.305496
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2322798080
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	149526016
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1025508864
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	759350784
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	58433
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2772469248
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	46090
CAVNodeAbsentTimer_mS_M_u32	2391537152
CDD_SrlComVehSpd_Kph_G_f32	549.725403
CMM388NTCEnableTimer_mS_M_u32	2910074368
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	474084864
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	20926
CMMNodeAbsentTimer_mS_M_u32	3993814528
CONSANGLECPKSigInvalidCount_Cnt_M_u16	60218
CONSANGLECPKSigValidCount_Cnt_M_u16	18483
CONSANGLECPK_Cnt_M_u16	48782
CONSANGLECPK_HwDeg_M_f32	-402.130798
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	48782
CPKVehicleSpeedMsgTimer_mS_M_u32	1344693760
CPKVehicleSpeedValidCount_Cnt_M_u16	533

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	1550
CityParkInputInvalidCount_Cnt_M_u16	34567
CityParkInputMsgTimer_mS_M_u32	207990528
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2444449280
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	23657
ComputerRazGCTSigInvalidTimer_mS_M_u32	2840884736
ComputerRazGCTSigValidCount_Cnt_M_u16	47475
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	9443
DMDFCTCPKSigValidCount_Cnt_M_u16	29812
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	16220
DMDRELAXECPKSigValidCount_Cnt_M_u16	32133
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	42855
DateInvalidTimer_mS_M_u32	149526016
DiagMuxOnAbsentTimer_mS_M_u32	4082443776
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	759350784
ESPNTCEnableTimer_mS_M_u32	211834368
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	46243
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	4
EffacDefaultDiagTimer_mS_M_u32[1]	748
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	102
ElecIntTimer_mS_M_u32[1]	106
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3685910016
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	45835
EtatMTSigValidCount_Cnt_M_u16	4448
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	26444
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	3525
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	56362
ISDAT4V2BSI552MsgTimer_mS_M_u32	1211155968
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	37710
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	12140
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	4448
ISDATBSI3F2MsgTimer_mS_M_u32	256058880
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	10465
ISDATBSI412MsgLenValidCount_Cnt_M_u16	55854
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	45835
ISDATBSI412MsgTimer_mS_M_u32	1885693440
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	48866
ISDATBSI432MsgLenValidCount_Cnt_M_u16	29895
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	63291
ISDATDIRASentFltAcc_Cnt_M_u16	27759
ISDATDIRASentTimer_mS_M_u32	1344693760
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	37116
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	2026
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	49498
ISDYN2CMMMsgTimer_mS_M_u32	3790231040
ISDYNAASChkSumInvalidCount_Cnt_M_u16	64087
ISDYNAASChkSumValidCount_Cnt_M_u16	26145
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	35425
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	17061
ISDYNAASMsgLenValidCount_Cnt_M_u16	27494
ISDYNAASMsgTimeValidCount_Cnt_M_u16	64087
ISDYNAASMsgTimer_mS_M_u32	2689611264
ISDYNABRChkSumInvalidCount_Cnt_M_u16	30357
ISDYNABRChkSumValidCount_Cnt_M_u16	24327
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	5966
ISDYNABRMsgCountValidCount_Cnt_M_u16	7768
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	64305
ISDYNABRMsgLenValidCount_Cnt_M_u16	13162
ISDYNABRMsgTimeValidCount_Cnt_M_u16	48782

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	686
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1257
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	4448
ISDYNCMM208MsgTimer_mS_M_u32	1175983616
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2595
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1363
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	16600
ISDYNCMM388MsgTimer_mS_M_u32	2569778688
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	16168
ISDYNVOLChkSumValidCount_Cnt_M_u16	21153
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	43985
ISDYNVOLMsgCountValidCount_Cnt_M_u16	61922
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	22188
ISDYNVOLMsgLenValidCount_Cnt_M_u16	7302
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	20926
ISDYNVOLMsgTimer_mS_M_u32	137393664
IgnOnTimer_mS_M_u32	1045411328
IgnTimeOff_Sec_M_u32	2132456884
ManVehSpd_Kph_M_f32	547.200989
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	193
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	130
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1993942528
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	223
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3807839744
PrevISDATBSI412MsgDLCError_Cnt_M_u08	246
PrevISDATBSI412MsgRxTime_MSec_M_u32	2222781952
PrevISDATBSI432MsgDLCError_Cnt_M_u08	40
PrevISDATBSI432MsgRxTime_MSec_M_u32	976508416
PrevISDATDIRAMsgTxTime_MSec_M_u32	951121408
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	164
PrevISDYN2CMMMsgRxTime_MSec_M_u32	485508608
PrevISDYNAASMsgDLCError_Cnt_M_u08	34
PrevISDYNAASMsgRxTime_MSec_M_u32	2728293888
PrevISDYNABRMsgDLCError_Cnt_M_u08	49
PrevISDYNABRMsgRxTime_MSec_M_u32	3876042240
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	76
PrevISDYNCMM208MsgRxTime_MSec_M_u32	63141376
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	209
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1032803840
PrevISDYNVOLMsgDLCError_Cnt_M_u08	118
PrevISDYNVOLMsgRxTime_MSec_M_u32	1559885312
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	894658048
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	413.066406
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	44947
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	20180
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	57116
VitesseVehicleBVRampValidCount_Cnt_M_u16	17181
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	16979

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	39868
VitesseVehicleBV_Kph_M_f32	422.738312
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	16600
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	25209
VitesseVehiculeRoues_Kph_M_f32	371.665802
k_AASNTCEnableTimeout_mS_u16	2685
k_AASNodeAbsentDiag_Cnt_str.Threshold	22610
k_AASNodeAbsentDiag_Cnt_str.PStep	10965
k_AASNodeAbsentDiag_Cnt_str.NStep	17616
k_AASNodeAbsentTimeout_mS_u16	3901
k_AASNodeTimeout_mS_u16	468
k_ABSNodeTimeout_mS_u16	45128
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	11125
k_ANGLEVOLANTSigValidThresh_Cnt_u16	14746
k_AngleVolantInvalidThresh_Cnt_u16	36057
k_AngleVolantValidThresh_Cnt_u16	34567
k_BSI552MsgTimeout_mS_u16	35448
k_BSINTCEnableTimeout_mS_u16	55194
k_BSINodeAbsentDiag_Cnt_str.Threshold	24852
k_BSINodeAbsentDiag_Cnt_str.PStep	34978
k_BSINodeAbsentDiag_Cnt_str.NStep	14383
k_BSINodeAbsentTimeout_mS_u16	34346
k_BSINodeTimeout_mS_u16	63291
k_BattOvHi_Volt_f32	26.1926003
k_BattOvLo_Volt_f32	31.5
k_BattUvHi_Volt_f32	29.2796993
k_BattUvLo_Volt_f32	24.6763992
k_CAVNTCEnableTimeout_mS_u16	40109
k_CAVNodeAbsentDiag_Cnt_str.Threshold	3297
k_CAVNodeAbsentDiag_Cnt_str.PStep	31396
k_CAVNodeAbsentDiag_Cnt_str.NStep	58926
k_CAVNodeAbsentTimeout_mS_u16	52216
k_CAVNodeTimeout_mS_u16	22038
k_CMM388MsgTimeout_mS_u16	23365
k_CMM388NTCEnableTimeout_mS_u16	42785
k_CMMNTCEnableTimeout_mS_u16	51206
k_CMMNodeAbsentDiag_Cnt_str.Threshold	9804
k_CMMNodeAbsentDiag_Cnt_str.PStep	41528
k_CMMNodeAbsentDiag_Cnt_str.NStep	26770
k_CMMNodeAbsentTimeout_mS_u16	58453
k_CONSANGLECPKMax_HwDeg_f32	358.525208
k_CONSANGLECPKMin_HwDeg_f32	-117.809601
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	46040
k_CONSANGLECPKSigValidThresh_Cnt_u16	5497
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	5258
k_CPKVehicleSpeedValidThresh_Cnt_u16	2364
k_CityParkInputInvalidThresh_Cnt_u16	60875
k_CityParkInputValidThresh_Cnt_u16	1550
k_ComputerRazGCTSigValidThresh_Cnt_u16	19812
k_CptTemporelSigValidThresh_Cnt_u16	28162
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	60977
k_DMDFCTCPKSigValidThresh_Cnt_u16	26218
k_DMDFCTCPKValidCount_Cnt_u16	15497
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	49498
k_DMDRELAXECPKSigValidThresh_Cnt_u16	19499
k_DMDRelaxeConsistentThresh_Cnt_u16	51425
k_DateValidThresh_Cnt_u16	56362
k_DefaultVehSpd_Kph_f32	70.7677002
k_DiagMuxOnAbsentTimeout_mS_u16	11700
k_EMNodeTimeout_mS_u16	62151
k_ESPNTCEnableTimeout_mS_u16	16614
k_ESPNodeAbsentDiag_Cnt_str.Threshold	22428
k_ESPNodeAbsentDiag_Cnt_str.PStep	28578
k_ESPNodeAbsentDiag_Cnt_str.NStep	46213
k_ESPNodeAbsentTimeout_mS_u16	54173
k_EtatMTSigInvalidThresh_Cnt_u16	23988
k_EtatMTSigValidThresh_Cnt_u16	44902
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	39109
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	1531
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	34711
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	32667
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	43897
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	48133

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	56495
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	16980
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	27654
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	40210
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	6272
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	22743
k_ISDATDIRASentDiag_Cnt_str.Threshold	14179
k_ISDATDIRASentDiag_Cnt_str.PStep	31669
k_ISDATDIRASentDiag_Cnt_str.NStep	54359
k_ISDATDIRASentTimeout_mS_u16	65393
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	30076
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	56178
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	16466
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	59797
k_ISDYNAASChkSumValidThresh_Cnt_u16	4615
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	2638
k_ISDYNAASMsgCountValidThresh_Cnt_u16	20824
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	41145
k_ISDYNAASMsgLenValidThresh_Cnt_u16	22520
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	26338
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	43551
k_ISDYNABRChkSumValidThresh_Cnt_u16	55512
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	55105
k_ISDYNABRMsgCountValidThresh_Cnt_u16	42794
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	1214
k_ISDYNABRMsgLenValidThresh_Cnt_u16	42915
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	3241
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	42423
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16298
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	16595
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	27722
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	8435
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	30143
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	62964
k_ISDYNVOLChkSumValidThresh_Cnt_u16	24449
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	59088
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	39979
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	38119
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	57404
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	62032
k_IgnOnTimeout_mS_u16	45776
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	154.813095
k_PowerCutVehSpdLowThresh_Kph_f32	134.883408
k_PowerCutVehSpdLowTimeout_mS_u16	40009
k_VBattMaxAAS_Volt_f32	10.3341999
k_VBattMaxBSI_Volt_f32	5.09159994
k_VBattMaxCAV_Volt_f32	2.02959991
k_VBattMaxCMM388_Volt_f32	31.7649994
k_VBattMaxCMM_Volt_f32	32
k_VBattMaxESP_Volt_f32	9.33360004
k_VBattMinAAS_Volt_f32	11.6077995
k_VBattMinBSI_Volt_f32	9.33360004
k_VBattMinCAV_Volt_f32	9.54119968
k_VBattMinCMM388_Volt_f32	9.1406002
k_VBattMinCMM_Volt_f32	13.9811001
k_VBattMinESP_Volt_f32	32
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	24006
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	3203
k_VitesseVehicleBVRampValidThresh_Cnt_u16	7889
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	34209
k_VitesseVehicleBVSigValidThresh_Cnt_u16	40527
k_VitesseVehicleBVSpeedPassThresh_kph_f32	555.805115
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	9994
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	16779
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	149526016
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	93
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	42709
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1704609280
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	209
target_SrlComInput_Per1_Batt_Volt_f32.value	15.5074997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4124149248
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	112
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.888953924
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2481567232
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3514488320
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	870053376
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3272414720
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2265855488
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	199
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2279560704
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3447748096
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	69
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	124
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	176
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	204
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1442190848
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	67
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	131
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	187
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	138
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3211048448
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	27
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	544593408
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1716975104
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	37
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	47
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	61
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	78
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	161
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	173
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1629029888
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1553
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.776588142
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	652796
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	140.120895
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	18781

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1704609280	1704609280	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-100.305496	-100.305496	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	3297	3297	✔
CAVNodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	9804	9804	✔
CMMNodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	48782	48782	✔
CONSANGLECPK_HwDeg_M_f32	-402.130798	-402.130798 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1704609280	1704609280	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1704609280	1704609280	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1704609280	1704609280	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1704609280	1704609280	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1704609280	1704609280	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1704609280	1704609280	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1704609280	1704609280	✔
ESPNTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	4	4	✔
EffacDefaultDiagTimer_mS_M_u32[1]	748	748	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	1704609280	1704609280	✔
ElecIntTimer_mS_M_u32[1]	106	106	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1704609280	1704609280	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDATDIRASentFltAcc_Cnt_M_u16	14179	14179	✔
ISDATDIRASentTimer_mS_M_u32	1704609280	1704609280	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1704609280	1704609280	✔
IgnOnTimer_mS_M_u32	1704609280	1704609280	✔
IgnTimeOff_Sec_M_u32	2132456884	2132456884	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2481567232	2481567232	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	246	246	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3514488320	3514488320	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	229	229	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	870053376	870053376	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	253	253	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3272414720	3272414720	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	951121408	951121408	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	199	199	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2279560704	2279560704	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	137	137	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3447748096	3447748096	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	29	29	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1442190848	1442190848	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	138	138	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3211048448	3211048448	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	27	27	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	544593408	544593408	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	142	142	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1716975104	1716975104	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1629029888	1629029888	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	413.066406	413.066406	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	422.738312	422.738312	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	371.665802	371.665802	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-100.305496	-100.305496	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	48782	48782	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2132456884	2132456884	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-402.130798	-402.130798 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.105 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4249915648
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	27109
AASNodeAbsentTimer_mS_M_u32	3033055488
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	59607
ANGLEVOLANTSigValidCount_Cnt_M_u16	15515
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	1118
AngleVolantMsgTimer_mS_M_u32	4249915648
AngleVolantValidCount_Cnt_M_u16	50040
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-451.541687
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1948090624
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4072276224
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2077667584
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2792255744
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	17394
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1702179072
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	57623
CAVNodeAbsentTimer_mS_M_u32	1666375936
CDD_SrlComVehSpd_Kph_G_f32	96.6981964
CMM388NTCEnableTimer_mS_M_u32	4154073344
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	305193216
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	45756
CMMNodeAbsentTimer_mS_M_u32	202404096
CONSANGLECPKSigInvalidCount_Cnt_M_u16	520
CONSANGLECPKSigValidCount_Cnt_M_u16	56540
CONSANGLECPK_Cnt_M_u16	42443
CONSANGLECPK_HwDeg_M_f32	-255.264999
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	42443
CPKVehicleSpeedMsgTimer_mS_M_u32	3561197824
CPKVehicleSpeedValidCount_Cnt_M_u16	49436
CityParkInputConsistentCount_Cnt_M_u16	22796
CityParkInputInvalidCount_Cnt_M_u16	19232

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	2481567232
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2942091520
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	7545
ComputerRazGCTSigInvalidTimer_mS_M_u32	3573113088
ComputerRazGCTSigValidCount_Cnt_M_u16	4829
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	57740
DMDFCTCPKSigValidCount_Cnt_M_u16	17560
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	24225
DMDRELAXECPKSigValidCount_Cnt_M_u16	21989
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	49537
DateInvalidTimer_mS_M_u32	4072276224
DiagMuxOnAbsentTimer_mS_M_u32	364335360
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2792255744
ESPNTCEnableTimer_mS_M_u32	848675072
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	11211
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	45
EffacDefaultDiagTimer_mS_M_u32[1]	98
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	89
ElecIntTimer_mS_M_u32[1]	789
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	169816320
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	21460
EtatMTSigValidCount_Cnt_M_u16	39572
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	21970
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	21542
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	25974
ISDAT4V2BSI552MsgTimer_mS_M_u32	2376364288
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	30858
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	9713
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	39572
ISDATBSI3F2MsgTimer_mS_M_u32	4193079552
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	53459
ISDATBSI412MsgLenValidCount_Cnt_M_u16	65195
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	21460
ISDATBSI412MsgTimer_mS_M_u32	797348096
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	64336
ISDATBSI432MsgLenValidCount_Cnt_M_u16	31583
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	7044
ISDATDIRASentFltAcc_Cnt_M_u16	35816
ISDATDIRASentTimer_mS_M_u32	3561197824
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	26241
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	50040
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	43047
ISDYN2CMMMsgTimer_mS_M_u32	1521991936
ISDYNAASChkSumInvalidCount_Cnt_M_u16	31663
ISDYNAASChkSumValidCount_Cnt_M_u16	27154
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	55315
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	24902
ISDYNAASMsgLenValidCount_Cnt_M_u16	63681
ISDYNAASMsgTimeValidCount_Cnt_M_u16	31663
ISDYNAASMsgTimer_mS_M_u32	2399543552
ISDYNABRChkSumInvalidCount_Cnt_M_u16	54901
ISDYNABRChkSumValidCount_Cnt_M_u16	61153
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	49354
ISDYNABRMsgCountValidCount_Cnt_M_u16	56685
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	28195
ISDYNABRMsgLenValidCount_Cnt_M_u16	46903
ISDYNABRMsgTimeValidCount_Cnt_M_u16	42443
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	687
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1259

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	39572
ISDYNCMM208MsgTimer_mS_M_u32	355369216
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2599
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1365
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	20654
ISDYNCMM388MsgTimer_mS_M_u32	1920180480
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	15934
ISDYNVOLChkSumValidCount_Cnt_M_u16	62866
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	33986
ISDYNVOLMsgCountValidCount_Cnt_M_u16	1102
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	43440
ISDYNVOLMsgLenValidCount_Cnt_M_u16	51684
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	45756
ISDYNVOLMsgTimer_mS_M_u32	677732608
IgnOnTimer_mS_M_u32	319267072
IgnTimeOff_Sec_M_u32	2824766526
ManVehSpd_Kph_M_f32	257.460114
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	195
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	145
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2603307264
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	219
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2790371584
PrevISDATBSI412MsgDLCError_Cnt_M_u08	220
PrevISDATBSI412MsgRxTime_MSec_M_u32	2239750400
PrevISDATBSI432MsgDLCError_Cnt_M_u08	204
PrevISDATBSI432MsgRxTime_MSec_M_u32	4191797504
PrevISDATDIRAMsgTxTime_MSec_M_u32	954458368
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	194
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1835397376
PrevISDYNAASMsgDLCError_Cnt_M_u08	249
PrevISDYNAASMsgRxTime_MSec_M_u32	2434490624
PrevISDYNABRMsgDLCError_Cnt_M_u08	225
PrevISDYNABRMsgRxTime_MSec_M_u32	4175405312
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	49
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1101816064
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	223
PrevISDYNCMM388MsgRxTime_MSec_M_u32	466141440
PrevISDYNVOLMsgDLCError_Cnt_M_u08	42
PrevISDYNVOLMsgRxTime_MSec_M_u32	805888256
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	415011072
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	450.271088
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	21116
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	34423
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	10209
VitesseVehicleBVRampValidCount_Cnt_M_u16	3484
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	61884
VitesseVehicleBVSigValidCount_Cnt_M_u16	38720
VitesseVehicleBV_Kph_M_f32	603.287109

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	20654
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	32138
VitesseVehiculeRoues_Kph_M_f32	288.605988
k_AASNTCEnableTimeout_mS_u16	15870
k_AASNodeAbsentDiag_Cnt_str.Threshold	6318
k_AASNodeAbsentDiag_Cnt_str.PStep	14205
k_AASNodeAbsentDiag_Cnt_str.NStep	34084
k_AASNodeAbsentTimeout_mS_u16	47487
k_AASNodeTimeout_mS_u16	28023
k_ABSNodeTimeout_mS_u16	4957
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	49559
k_ANGLEVOLANTSigValidThresh_Cnt_u16	14566
k_AngleVolantInvalidThresh_Cnt_u16	64297
k_AngleVolantValidThresh_Cnt_u16	19232
k_BSI552MsgTimeout_mS_u16	49549
k_BSINTCEnableTimeout_mS_u16	37160
k_BSINodeAbsentDiag_Cnt_str.Threshold	24892
k_BSINodeAbsentDiag_Cnt_str.PStep	34961
k_BSINodeAbsentDiag_Cnt_str.NStep	14406
k_BSINodeAbsentTimeout_mS_u16	58422
k_BSINodeTimeout_mS_u16	7044
k_BattOvHi_Volt_f32	9.26910019
k_BattOvLo_Volt_f32	23.6669006
k_BattUvHi_Volt_f32	5.65719986
k_BattUvLo_Volt_f32	19.6893997
k_CAVNTCEnableTimeout_mS_u16	8750
k_CAVNodeAbsentDiag_Cnt_str.Threshold	43897
k_CAVNodeAbsentDiag_Cnt_str.PStep	52425
k_CAVNodeAbsentDiag_Cnt_str.NStep	38913
k_CAVNodeAbsentTimeout_mS_u16	53581
k_CAVNodeTimeout_mS_u16	12660
k_CMM388MsgTimeout_mS_u16	37093
k_CMM388NTCEnableTimeout_mS_u16	7505
k_CMMNTCEnableTimeout_mS_u16	47714
k_CMMNodeAbsentDiag_Cnt_str.Threshold	33824
k_CMMNodeAbsentDiag_Cnt_str.PStep	56244
k_CMMNodeAbsentDiag_Cnt_str.NStep	45373
k_CMMNodeAbsentTimeout_mS_u16	26614
k_CONSANGLECPKMax_HwDeg_f32	775.375916
k_CONSANGLECPKMin_HwDeg_f32	-763.843323
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	63406
k_CONSANGLECPKSigValidThresh_Cnt_u16	25738
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	36181
k_CPKVehicleSpeedValidThresh_Cnt_u16	23490
k_CityParkInputInvalidThresh_Cnt_u16	51411
k_CityParkInputValidThresh_Cnt_u16	22796
k_ComputerRazGCTSigValidThresh_Cnt_u16	8776
k_CptTemporelSigValidThresh_Cnt_u16	16943
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	38179
k_DMDFCTCPKSigValidThresh_Cnt_u16	7735
k_DMDFCTCPKValidCount_Cnt_u16	23322
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	43047
k_DMDRELAXECPKSigValidThresh_Cnt_u16	22899
k_DMDRelaxeConsistentThresh_Cnt_u16	15185
k_DateValidThresh_Cnt_u16	25974
k_DefaultVehSpd_Kph_f32	144.910904
k_DiagMuxOnAbsentTimeout_mS_u16	28761
k_EMNodeTimeout_mS_u16	24417
k_ESPNTCEnableTimeout_mS_u16	43651
k_ESPNodeAbsentDiag_Cnt_str.Threshold	62737
k_ESPNodeAbsentDiag_Cnt_str.PStep	45398
k_ESPNodeAbsentDiag_Cnt_str.NStep	31815
k_ESPNodeAbsentTimeout_mS_u16	47646
k_EtatMTSigInvalidThresh_Cnt_u16	23832
k_EtatMTSigValidThresh_Cnt_u16	14788
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	44196
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	18116
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	14449
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	10147
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	9674
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	42855
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	5609
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	34488

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	33764
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	6719
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	27062
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	59888
k_ISDATDIRASentDiag_Cnt_str.Threshold	23667
k_ISDATDIRASentDiag_Cnt_str.PStep	62998
k_ISDATDIRASentDiag_Cnt_str.NStep	5641
k_ISDATDIRASentTimeout_mS_u16	44001
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	26625
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	1118
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	23615
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	32117
k_ISDYNAASChkSumValidThresh_Cnt_u16	54753
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	59338
k_ISDYNAASMsgCountValidThresh_Cnt_u16	17517
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	59401
k_ISDYNAASMsgLenValidThresh_Cnt_u16	64267
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	53518
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	39257
k_ISDYNABRChkSumValidThresh_Cnt_u16	65261
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	27378
k_ISDYNABRMsgCountValidThresh_Cnt_u16	44278
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	39356
k_ISDYNABRMsgLenValidThresh_Cnt_u16	21195
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	14457
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	16
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	61560
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	27770
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	4055
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	41883
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	24312
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	30106
k_ISDYNVOLChkSumValidThresh_Cnt_u16	31410
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	35140
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	51061
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	7744
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	40448
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	15108
k_IgnOnTimeout_mS_u16	44806
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	203.274704
k_PowerCutVehSpdLowThresh_Kph_f32	207.063705
k_PowerCutVehSpdLowTimeout_mS_u16	47258
k_VBattMaxAAS_Volt_f32	6.02120018
k_VBattMaxBSI_Volt_f32	8.66479969
k_VBattMaxCAV_Volt_f32	3.4454999
k_VBattMaxCMM388_Volt_f32	12.5305004
k_VBattMaxCMM_Volt_f32	19.8243008
k_VBattMaxESP_Volt_f32	21.3656006
k_VBattMinAAS_Volt_f32	20.9881992
k_VBattMinBSI_Volt_f32	21.3656006
k_VBattMinCAV_Volt_f32	18.2614994
k_VBattMinCMM388_Volt_f32	14.6290998
k_VBattMinCMM_Volt_f32	20.7003002
k_VBattMinESP_Volt_f32	19.8243008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	22307
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	19627
k_VitesseVehicleBVRampValidThresh_Cnt_u16	11202
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	23698
k_VitesseVehicleBVSigValidThresh_Cnt_u16	54345
k_VitesseVehicleBVSpeedPassThresh_kph_f32	120.1213
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	34839
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	19026
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	4072276224
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	69
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16 Elaps	2445
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3144151296
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	223

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	17.5044003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4156698880
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	70
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.912512958
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4198080768
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	128
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1845903616
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	128
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3009601792
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2991554816
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1389109504
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2094579968
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	410345728
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	63
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	71
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	88
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	164
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	228
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3717497088
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	28
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	44
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	121
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	133
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	182
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	192
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	600350976
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	188
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	756367616
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3354517760
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	16
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	32
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	52
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	57
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	133
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	239
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	871084288
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	61
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.708277285
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	508931
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	118.601097
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	11550

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3144151296	3144151296	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-451.541687	-451.541687	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	43897	43897	✔
CAVNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	33824	33824	✔
CMMNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	42443	42443	✔
CONSANGLECPK_HwDeg_M_f32	-255.264999	-255.264999 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3144151296	3144151296	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3144151296	3144151296	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3144151296	3144151296	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3144151296	3144151296	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3144151296	3144151296	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3144151296	3144151296	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3144151296	3144151296	✔
ESPNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3144151296	3144151296	✔
EffacDefaultDiagTimer_mS_M_u32[1]	98	98	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	3144151296	3144151296	✔
ElecIntTimer_mS_M_u32[1]	789	789	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3144151296	3144151296	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATDIRASentFltAcc_Cnt_M_u16	23667	23667	✔
ISDATDIRASentTimer_mS_M_u32	3144151296	3144151296	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3144151296	3144151296	✔
IgnOnTimer_mS_M_u32	3144151296	3144151296	✔
IgnTimeOff_Sec_M_u32	2824766526	2824766526	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4198080768	4198080768	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	128	128	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1845903616	1845903616	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	128	128	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3009601792	3009601792	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	69	69	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2991554816	2991554816	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	954458368	954458368	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	192	192	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2094579968	2094579968	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	410345728	410345728	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	202	202	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3717497088	3717497088	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	229	229	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	600350976	600350976	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	188	188	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	756367616	756367616	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	49	49	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3354517760	3354517760	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	871084288	871084288	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	450.271088	450.271088	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	603.287109	603.287109	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	288.605988	288.605988	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-451.541687	-451.541687	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	42443	42443	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2824766526	2824766526	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-255.264999	-255.264999 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	144.910904	144.910904	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.106 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2733840896
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	4201
AASNodeAbsentTimer_mS_M_u32	1238501888
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	46454
ANGLEVOLANTSigValidCount_Cnt_M_u16	14142
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	23526
AngleVolantMsgTimer_mS_M_u32	2733840896
AngleVolantValidCount_Cnt_M_u16	40383
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-413.451202
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3675376128
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2746239488
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3545610752
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	222591488
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	18525
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2201893376
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	53672
CAVNodeAbsentTimer_mS_M_u32	1254664704
CDD_SrlComVehSpd_Kph_G_f32	408.441498
CMM388NTCEnableTimer_mS_M_u32	4011125248
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	551463424
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	27390
CMMNodeAbsentTimer_mS_M_u32	766409216
CONSANGLECPKSigInvalidCount_Cnt_M_u16	25473
CONSANGLECPKSigValidCount_Cnt_M_u16	60058
CONSANGLECPK_Cnt_M_u16	48421
CONSANGLECPK_HwDeg_M_f32	719.092529
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	48421
CPKVehicleSpeedMsgTimer_mS_M_u32	1544690176
CPKVehicleSpeedValidCount_Cnt_M_u16	40429
CityParkInputConsistentCount_Cnt_M_u16	39971

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	10000
CityParkInputMsgTimer_mS_M_u32	766341888
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3778415104
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	25805
ComputerRazGCTSigInvalidTimer_mS_M_u32	1675176448
ComputerRazGCTSigValidCount_Cnt_M_u16	44888
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	33964
DMDFCTCPKSigValidCount_Cnt_M_u16	64477
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	60328
DMDRELAXECPKSigValidCount_Cnt_M_u16	3824
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	2046
DateInvalidTimer_mS_M_u32	2746239488
DiagMuxOnAbsentTimer_mS_M_u32	63756800
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	222591488
ESPNTCEnableTimer_mS_M_u32	3497200128
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	61635
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	8976
EffacDefaultDiagTimer_mS_M_u32[1]	3893024000
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	41
ElecIntTimer_mS_M_u32[1]	47
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2144352768
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	8576
EtatMTSigValidCount_Cnt_M_u16	57780
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	44979
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	22604
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	19443
ISDAT4V2BSI552MsgTimer_mS_M_u32	1209170432
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	43209
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	65349
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	57780
ISDATBSI3F2MsgTimer_mS_M_u32	3483032064
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	4447
ISDATBSI412MsgLenValidCount_Cnt_M_u16	30732
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	8576
ISDATBSI412MsgTimer_mS_M_u32	3032553984
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	18530
ISDATBSI432MsgLenValidCount_Cnt_M_u16	53543
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	39785
ISDATDIRASentFltAcc_Cnt_M_u16	47581
ISDATDIRASentTimer_mS_M_u32	1544690176
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	26483
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	40383
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	41235
ISDYN2CMMMsgTimer_mS_M_u32	224201216
ISDYNAASChkSumInvalidCount_Cnt_M_u16	53915
ISDYNAASChkSumValidCount_Cnt_M_u16	44420
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	38
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	8307
ISDYNAASMsgLenValidCount_Cnt_M_u16	43987
ISDYNAASMsgTimeValidCount_Cnt_M_u16	53915
ISDYNAASMsgTimer_mS_M_u32	1907419648
ISDYNABRChkSumInvalidCount_Cnt_M_u16	1607
ISDYNABRChkSumValidCount_Cnt_M_u16	46167
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	14210
ISDYNABRMsgCountValidCount_Cnt_M_u16	49579
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	27496
ISDYNABRMsgLenValidCount_Cnt_M_u16	57793
ISDYNABRMsgTimeValidCount_Cnt_M_u16	48421
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	706

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1297
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	57780
ISDYNCMM208MsgTimer_mS_M_u32	1518782976
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2675
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1403
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	54925
ISDYNCMM388MsgTimer_mS_M_u32	75786752
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	59215
ISDYNVOLChkSumValidCount_Cnt_M_u16	19688
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	60282
ISDYNVOLMsgCountValidCount_Cnt_M_u16	33067
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	47836
ISDYNVOLMsgLenValidCount_Cnt_M_u16	18644
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	27390
ISDYNVOLMsgTimer_mS_M_u32	309668352
IgnOnTimer_mS_M_u32	2582145536
IgnTimeOff_Sec_M_u32	119861862
ManVehSpd_Kph_M_f32	620.066895
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	33
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2911951360
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	85
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1595718144
PrevISDATBSI412MsgDLCError_Cnt_M_u08	200
PrevISDATBSI412MsgRxTime_MSec_M_u32	2471078400
PrevISDATBSI432MsgDLCError_Cnt_M_u08	36
PrevISDATBSI432MsgRxTime_MSec_M_u32	2101807616
PrevISDATDIRAMsgTxTime_MSec_M_u32	1623042560
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	198
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3003775488
PrevISDYNAASMsgDLCError_Cnt_M_u08	240
PrevISDYNAASMsgRxTime_MSec_M_u32	79899136
PrevISDYNABRMsgDLCError_Cnt_M_u08	212
PrevISDYNABRMsgRxTime_MSec_M_u32	304114176
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	37
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3250072064
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	26
PrevISDYNCMM388MsgRxTime_MSec_M_u32	751962624
PrevISDYNVOLMsgDLCError_Cnt_M_u08	242
PrevISDYNVOLMsgRxTime_MSec_M_u32	2971052544
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	965679616
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	435.627106
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	52545
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	63265
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	15578
VitesseVehicleBVRampValidCount_Cnt_M_u16	6010
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	38543
VitesseVehicleBVSigValidCount_Cnt_M_u16	59671

Name	Input Value
VitesseVehicleBV_Kph_M_f32	584.98761
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	54925
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	63694
VitesseVehiculeRoues_Kph_M_f32	471.321594
k_AASNTCEnableTimeout_mS_u16	25732
k_AASNodeAbsentDiag_Cnt_str.Threshold	44077
k_AASNodeAbsentDiag_Cnt_str.PStep	24884
k_AASNodeAbsentDiag_Cnt_str.NStep	1467
k_AASNodeAbsentTimeout_mS_u16	13506
k_AASNodeTimeout_mS_u16	23073
k_ABSNodeTimeout_mS_u16	61409
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	63653
k_ANGLEVOLANTSigValidThresh_Cnt_u16	15786
k_AngleVolantInvalidThresh_Cnt_u16	31065
k_AngleVolantValidThresh_Cnt_u16	10000
k_BSI552MsgTimeout_mS_u16	62781
k_BSINTCEnableTimeout_mS_u16	12442
k_BSINodeAbsentDiag_Cnt_str.Threshold	25652
k_BSINodeAbsentDiag_Cnt_str.PStep	34638
k_BSINodeAbsentDiag_Cnt_str.NStep	14843
k_BSINodeAbsentTimeout_mS_u16	63006
k_BSINodeTimeout_mS_u16	39785
k_BattOvHi_Volt_f32	5.49170017
k_BattOvLo_Volt_f32	23.8575993
k_BattUvHi_Volt_f32	20.5133991
k_BattUvLo_Volt_f32	28.6525002
k_CAVNTCEnableTimeout_mS_u16	19478
k_CAVNodeAbsentDiag_Cnt_str.Threshold	14042
k_CAVNodeAbsentDiag_Cnt_str.PStep	30262
k_CAVNodeAbsentDiag_Cnt_str.NStep	2683
k_CAVNodeAbsentTimeout_mS_u16	22902
k_CAVNodeTimeout_mS_u16	56861
k_CMM388MsgTimeout_mS_u16	45929
k_CMM388NTCEnableTimeout_mS_u16	40709
k_CMMNTCEnableTimeout_mS_u16	27905
k_CMMNodeAbsentDiag_Cnt_str.Threshold	40491
k_CMMNodeAbsentDiag_Cnt_str.PStep	37146
k_CMMNodeAbsentDiag_Cnt_str.NStep	19847
k_CMMNodeAbsentTimeout_mS_u16	31338
k_CONSANGLECPKMax_HwDeg_f32	506.7229
k_CONSANGLECPKMin_HwDeg_f32	-716.683899
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	63885
k_CONSANGLECPKSigValidThresh_Cnt_u16	23502
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	34103
k_CPKVehicleSpeedValidThresh_Cnt_u16	60906
k_CityParkInputInvalidThresh_Cnt_u16	40413
k_CityParkInputValidThresh_Cnt_u16	39971
k_ComputerRazGCTSigValidThresh_Cnt_u16	49471
k_CptTemporelSigValidThresh_Cnt_u16	42043
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	3688
k_DMDFCTCPKSigValidThresh_Cnt_u16	50369
k_DMDFCTCPKValidCount_Cnt_u16	24869
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	41235
k_DMDRELAXECPKSigValidThresh_Cnt_u16	26500
k_DMDRelaxeConsistentThresh_Cnt_u16	40090
k_DateValidThresh_Cnt_u16	19443
k_DefaultVehSpd_Kph_f32	43.0087013
k_DiagMuxOnAbsentTimeout_mS_u16	5035
k_EMNodeTimeout_mS_u16	55646
k_ESPNTCEnableTimeout_mS_u16	36420
k_ESPNodeAbsentDiag_Cnt_str.Threshold	38622
k_ESPNodeAbsentDiag_Cnt_str.PStep	63474
k_ESPNodeAbsentDiag_Cnt_str.NStep	43930
k_ESPNodeAbsentTimeout_mS_u16	6706
k_EtatMTSigInvalidThresh_Cnt_u16	41942
k_EtatMTSigValidThresh_Cnt_u16	44838
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	54178
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	41143
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	32188
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	61286
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	61858
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	29891
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	6271

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	27908
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	26054
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	61929
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	13493
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	47258
k_ISDATDIRASentDiag_Cnt_str.Threshold	45598
k_ISDATDIRASentDiag_Cnt_str.PStep	35197
k_ISDATDIRASentDiag_Cnt_str.NStep	1197
k_ISDATDIRASentTimeout_mS_u16	32483
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	10511
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	23526
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	24176
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	10567
k_ISDYNAASChkSumValidThresh_Cnt_u16	5975
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	55938
k_ISDYNAASMsgCountValidThresh_Cnt_u16	42155
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	61611
k_ISDYNAASMsgLenValidThresh_Cnt_u16	12421
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	64370
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	31286
k_ISDYNABRChkSumValidThresh_Cnt_u16	3855
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	60253
k_ISDYNABRMsgCountValidThresh_Cnt_u16	56421
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	52734
k_ISDYNABRMsgLenValidThresh_Cnt_u16	37827
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	11860
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	17317
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	15416
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	23952
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	22646
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	6718
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	17736
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	59938
k_ISDYNVOLChkSumValidThresh_Cnt_u16	27919
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	27456
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	25019
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	796
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	80
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	14713
k_IgnOnTimeout_mS_u16	54974
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	9.46819973
k_PowerCutVehSpdLowThresh_Kph_f32	197.663498
k_PowerCutVehSpdLowTimeout_mS_u16	15632
k_VBattMaxAAS_Volt_f32	31.6548996
k_VBattMaxBSI_Volt_f32	31.3722
k_VBattMaxCAV_Volt_f32	12.2175999
k_VBattMaxCMM388_Volt_f32	27.5123997
k_VBattMaxCMM_Volt_f32	32
k_VBattMaxESP_Volt_f32	17.0662994
k_VBattMinAAS_Volt_f32	12.8992996
k_VBattMinBSI_Volt_f32	17.0662994
k_VBattMinCAV_Volt_f32	0.247700006
k_VBattMinCMM388_Volt_f32	15.2483997
k_VBattMinCMM_Volt_f32	4.05170012
k_VBattMinESP_Volt_f32	32
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	10489
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	60437
k_VitesseVehicleBVRampValidThresh_Cnt_u16	3706
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	12264
k_VitesseVehicleBVSigValidThresh_Cnt_u16	17396
k_VitesseVehicleBVSpeedPassThresh_kph_f32	140.602203
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	62632
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	44488
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2746239488
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	34
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	62348
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3893024000
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	26
target_SrlComInput_Per1_Batt_Volt_f32.value	9.07470036
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	6240768
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	161
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.493888438
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4095896064
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1135970816
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1561897472
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	199
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3360410112
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	223275520
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	179
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3022129664
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1153772032
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	37
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	99
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	116
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	179
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	237
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2705639936
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	55
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	100
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	141
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	155
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	167
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	207
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	185
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3184355840
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2833287680
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	499362304
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	67
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	74
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	149
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	153
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	216
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2254354944
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2660
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0377656966
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	224888
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	28.0456009

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	54955		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	3893024000	3893024000	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	44077	44077	✔
AASNodeAbsentTimer_mS_M_u32	3893024000	3893024000	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3893024000	3893024000	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-413.451202	-413.451202	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3893024000	3893024000	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3893024000	3893024000	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3893024000	3893024000	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3893024000	3893024000	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	25652	25652	✔
BSINodeAbsentTimer_mS_M_u32	3893024000	3893024000	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3893024000	3893024000	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3893024000	3893024000	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3893024000	3893024000	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3893024000	3893024000	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3893024000	3893024000	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	48421	48421	✔
CONSANGLECPK_HwDeg_M_f32	719.092529	719.092529 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3893024000	3893024000	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3893024000	3893024000	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3893024000	3893024000	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3893024000	3893024000	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3893024000	3893024000	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3893024000	3893024000	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3893024000	3893024000	✔
ESPNTCEnableTimer_mS_M_u32	3893024000	3893024000	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	38622	38622	✔
ESPNodeAbsentTimer_mS_M_u32	3893024000	3893024000	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	8976	8976	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	3893024000	3893024000	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3893024000	3893024000	✔
ElecIntTimer_mS_M_u32[1]	47	47	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3893024000	3893024000	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3893024000	3893024000	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3893024000	3893024000	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3893024000	3893024000	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3893024000	3893024000	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3893024000	3893024000	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3893024000	3893024000	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3893024000	3893024000	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3893024000	3893024000	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3893024000	3893024000	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3893024000	3893024000	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3893024000	3893024000	✔
IgnOnTimer_mS_M_u32	3893024000	3893024000	✔
IgnTimeOff_Sec_M_u32	119861862	119861862	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	117	117	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4095896064	4095896064	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	51	51	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1135970816	1135970816	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	118	118	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1561897472	1561897472	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	199	199	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3360410112	3360410112	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1623042560	1623042560	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	179	179	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3022129664	3022129664	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	94	94	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1153772032	1153772032	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	153	153	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2705639936	2705639936	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	185	185	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3184355840	3184355840	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	178	178	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2833287680	2833287680	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	241	241	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	499362304	499362304	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2254354944	2254354944	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	435.627106	435.627106	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	584.98761	584.98761	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	471.321594	471.321594	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-413.451202	-413.451202	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	48421	48421	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	119861862	119861862	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	719.092529	719.092529 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.107 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	531461376
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	53577
AASNodeAbsentTimer_mS_M_u32	2463147264
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	46116
ANGLEVOLANTSigValidCount_Cnt_M_u16	7307
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	8914
AngleVolantMsgTimer_mS_M_u32	531461376
AngleVolantValidCount_Cnt_M_u16	43463
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	-714.473877
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2383504640
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3459638528
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3775239424
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1580815616
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	22383
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	323753216
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	20494
CAVNodeAbsentTimer_mS_M_u32	845989120
CDD_SrlComVehSpd_Kph_G_f32	284.196991
CMM388NTCEnableTimer_mS_M_u32	3330802944
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2284504320
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	31434
CMMNodeAbsentTimer_mS_M_u32	620451072
CONSANGLECPKSigInvalidCount_Cnt_M_u16	35073
CONSANGLECPKSigValidCount_Cnt_M_u16	8567
CONSANGLECPK_Cnt_M_u16	38358
CONSANGLECPK_HwDeg_M_f32	404.374908
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	38358
CPKVehicleSpeedMsgTimer_mS_M_u32	810579200
CPKVehicleSpeedValidCount_Cnt_M_u16	9190

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	16027
CityParkInputInvalidCount_Cnt_M_u16	58067
CityParkInputMsgTimer_mS_M_u32	4095896064
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1554294016
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	25629
ComputerRazGCTSigInvalidTimer_mS_M_u32	3376104704
ComputerRazGCTSigValidCount_Cnt_M_u16	6396
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	14847
DMDFCTCPKSigValidCount_Cnt_M_u16	25134
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	22926
DMDRELAXECPKSigValidCount_Cnt_M_u16	56693
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	53130
DateInvalidTimer_mS_M_u32	3459638528
DiagMuxOnAbsentTimer_mS_M_u32	2485138688
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1580815616
ESPNTCEnableTimer_mS_M_u32	3270354176
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	51004
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	5
EffacDefaultDiagTimer_mS_M_u32[1]	55
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	3
ElecIntTimer_mS_M_u32[1]	7
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3851818240
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	60486
EtatMTSigValidCount_Cnt_M_u16	18792
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	60523
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	8289
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	18924
ISDAT4V2BSI552MsgTimer_mS_M_u32	1708086528
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	46058
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	28212
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	18792
ISDATBSI3F2MsgTimer_mS_M_u32	3904255232
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	41767
ISDATBSI412MsgLenValidCount_Cnt_M_u16	60642
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	60486
ISDATBSI412MsgTimer_mS_M_u32	2722329856
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	29342
ISDATBSI432MsgLenValidCount_Cnt_M_u16	46608
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	14027
ISDATDIRASentFltAcc_Cnt_M_u16	43887
ISDATDIRASentTimer_mS_M_u32	810579200
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	20204
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	43463
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	16586
ISDYN2CMMMsgTimer_mS_M_u32	875537664
ISDYNAASChkSumInvalidCount_Cnt_M_u16	53939
ISDYNAASChkSumValidCount_Cnt_M_u16	44986
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	56978
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	20397
ISDYNAASMsgLenValidCount_Cnt_M_u16	64331
ISDYNAASMsgTimeValidCount_Cnt_M_u16	53939
ISDYNAASMsgTimer_mS_M_u32	2931033344
ISDYNABRChkSumInvalidCount_Cnt_M_u16	16176
ISDYNABRChkSumValidCount_Cnt_M_u16	17087
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	65534
ISDYNABRMsgCountValidCount_Cnt_M_u16	53061
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	52556
ISDYNABRMsgLenValidCount_Cnt_M_u16	38914
ISDYNABRMsgTimeValidCount_Cnt_M_u16	38358

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	707
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1299
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	18792
ISDYNCMM208MsgTimer_mS_M_u32	598893824
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2679
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1405
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	46941
ISDYNCMM388MsgTimer_mS_M_u32	2755233024
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	46487
ISDYNVOLChkSumValidCount_Cnt_M_u16	45709
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	48533
ISDYNVOLMsgCountValidCount_Cnt_M_u16	35396
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	3313
ISDYNVOLMsgLenValidCount_Cnt_M_u16	4296
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	31434
ISDYNVOLMsgTimer_mS_M_u32	761742592
IgnOnTimer_mS_M_u32	1947043072
IgnTimeOff_Sec_M_u32	200630229
ManVehSpd_Kph_M_f32	366.55191
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	35
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	255
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2798925056
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	173
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	431002880
PrevISDATBSI412MsgDLCError_Cnt_M_u08	48
PrevISDATBSI412MsgRxTime_MSec_M_u32	2632566016
PrevISDATBSI432MsgDLCError_Cnt_M_u08	57
PrevISDATBSI432MsgRxTime_MSec_M_u32	208774400
PrevISDATDIRAMsgTxTime_MSec_M_u32	76399872
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	93
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1659426048
PrevISDYNAASMsgDLCError_Cnt_M_u08	152
PrevISDYNAASMsgRxTime_MSec_M_u32	243090688
PrevISDYNABRMsgDLCError_Cnt_M_u08	235
PrevISDYNABRMsgRxTime_MSec_M_u32	3949298944
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	151
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3953018112
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	48
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3922765056
PrevISDYNVOLMsgDLCError_Cnt_M_u08	181
PrevISDYNVOLMsgRxTime_MSec_M_u32	3078800640
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3420026112
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	556.448486
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	323
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	53601
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	22136
VitesseVehicleBVRampValidCount_Cnt_M_u16	5206
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	46297

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	43776
VitesseVehicleBV_Kph_M_f32	249.377502
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	46941
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	7772
VitesseVehiculeRoues_Kph_M_f32	19.9237003
k_AASNTCEnableTimeout_mS_u16	56249
k_AASNodeAbsentDiag_Cnt_str.Threshold	8082
k_AASNodeAbsentDiag_Cnt_str.PStep	63998
k_AASNodeAbsentDiag_Cnt_str.NStep	18028
k_AASNodeAbsentTimeout_mS_u16	45246
k_AASNodeTimeout_mS_u16	43105
k_ABSNodeTimeout_mS_u16	3168
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	11733
k_ANGLEVOLANTSigValidThresh_Cnt_u16	15495
k_AngleVolantInvalidThresh_Cnt_u16	1402
k_AngleVolantValidThresh_Cnt_u16	58067
k_BSI552MsgTimeout_mS_u16	42255
k_BSINTCEnableTimeout_mS_u16	39414
k_BSINodeAbsentDiag_Cnt_str.Threshold	25692
k_BSINodeAbsentDiag_Cnt_str.PStep	34621
k_BSINodeAbsentDiag_Cnt_str.NStep	14866
k_BSINodeAbsentTimeout_mS_u16	13354
k_BSINodeTimeout_mS_u16	14027
k_BattOvHi_Volt_f32	0.762199998
k_BattOvLo_Volt_f32	19.6464996
k_BattUvHi_Volt_f32	11.1121998
k_BattUvLo_Volt_f32	27.0342007
k_CAVNTCEnableTimeout_mS_u16	3009
k_CAVNodeAbsentDiag_Cnt_str.Threshold	5912
k_CAVNodeAbsentDiag_Cnt_str.PStep	17152
k_CAVNodeAbsentDiag_Cnt_str.NStep	19870
k_CAVNodeAbsentTimeout_mS_u16	28836
k_CAVNodeTimeout_mS_u16	35117
k_CMM388MsgTimeout_mS_u16	59465
k_CMM388NTCEnableTimeout_mS_u16	38261
k_CMMNTCEnableTimeout_mS_u16	18242
k_CMMNodeAbsentDiag_Cnt_str.Threshold	52799
k_CMMNodeAbsentDiag_Cnt_str.PStep	12246
k_CMMNodeAbsentDiag_Cnt_str.NStep	56668
k_CMMNodeAbsentTimeout_mS_u16	2440
k_CONSANGLECPKMax_HwDeg_f32	427.835785
k_CONSANGLECPKMin_HwDeg_f32	-249.120605
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	20061
k_CONSANGLECPKSigValidThresh_Cnt_u16	62812
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	65311
k_CPKVehicleSpeedValidThresh_Cnt_u16	63878
k_CityParkInputInvalidThresh_Cnt_u16	20590
k_CityParkInputValidThresh_Cnt_u16	16027
k_ComputerRazGCTSigValidThresh_Cnt_u16	49800
k_CptTemporelSigValidThresh_Cnt_u16	55122
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	58444
k_DMDFCTCPKSigValidThresh_Cnt_u16	61186
k_DMDFCTCPKValidCount_Cnt_u16	11543
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	16586
k_DMDRELAXECPKSigValidThresh_Cnt_u16	31545
k_DMDRelaxeConsistentThresh_Cnt_u16	46071
k_DateValidThresh_Cnt_u16	18924
k_DefaultVehSpd_Kph_f32	44.0003014
k_DiagMuxOnAbsentTimeout_mS_u16	10820
k_EMNodeTimeout_mS_u16	56170
k_ESPNTCEnableTimeout_mS_u16	35386
k_ESPNodeAbsentDiag_Cnt_str.Threshold	69
k_ESPNodeAbsentDiag_Cnt_str.PStep	25387
k_ESPNodeAbsentDiag_Cnt_str.NStep	54213
k_ESPNodeAbsentTimeout_mS_u16	18992
k_EtatMTSigInvalidThresh_Cnt_u16	25219
k_EtatMTSigValidThresh_Cnt_u16	20050
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	32734
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	13921
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	15824
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	37907
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	19229
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	2299

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	46663
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	38521
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	43634
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	1930
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	15589
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	26232
k_ISDATDIRASentDiag_Cnt_str.Threshold	58745
k_ISDATDIRASentDiag_Cnt_str.PStep	41340
k_ISDATDIRASentDiag_Cnt_str.NStep	16989
k_ISDATDIRASentTimeout_mS_u16	17756
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	10521
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	8914
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	51638
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	54832
k_ISDYNAASChkSumValidThresh_Cnt_u16	6591
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	5886
k_ISDYNAASMsgCountValidThresh_Cnt_u16	9797
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	4100
k_ISDYNAASMsgLenValidThresh_Cnt_u16	46389
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	9007
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	22754
k_ISDYNABRChkSumValidThresh_Cnt_u16	51224
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	28271
k_ISDYNABRMsgCountValidThresh_Cnt_u16	35094
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	20938
k_ISDYNABRMsgLenValidThresh_Cnt_u16	56892
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	3913
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	11799
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	50844
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	6676
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	52004
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	29579
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	26667
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	58590
k_ISDYNVOLChkSumValidThresh_Cnt_u16	55769
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	35781
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	51859
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	46962
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	23956
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	6490
k_IgnOnTimeout_mS_u16	36618
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	239.121902
k_PowerCutVehSpdLowThresh_Kph_f32	2.53600001
k_PowerCutVehSpdLowTimeout_mS_u16	33301
k_VBattMaxAAS_Volt_f32	4.94099998
k_VBattMaxBSI_Volt_f32	6.11129999
k_VBattMaxCAV_Volt_f32	12.5606003
k_VBattMaxCMM388_Volt_f32	12.3732996
k_VBattMaxCMM_Volt_f32	10.7700996
k_VBattMaxESP_Volt_f32	31.6590004
k_VBattMinAAS_Volt_f32	21.7304001
k_VBattMinBSI_Volt_f32	31.6590004
k_VBattMinCAV_Volt_f32	27.5552998
k_VBattMinCMM388_Volt_f32	24.1252995
k_VBattMinCMM_Volt_f32	15.9176998
k_VBattMinESP_Volt_f32	10.7700996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	20827
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	17862
k_VitesseVehicleBVRampValidThresh_Cnt_u16	21653
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	2445
k_VitesseVehicleBVSigValidThresh_Cnt_u16	52008
k_VitesseVehicleBVSpeedPassThresh_kph_f32	401.249908
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	59150
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	2412
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3459638528
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	48
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	36411
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2323117824
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	48
target_SrlComInput_Per1_Batt_Volt_f32.value	19.7791996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1609110784
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	254
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0452038832
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3445589248
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	130
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2468750592
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	998032640
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	778265856
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3554280704
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2480973056
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3598140672
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	78
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	94
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	141
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	171
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	183
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3346556160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	10
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	46
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	94
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	195
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	71
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3697181952
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	112
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3483706624
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	7
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1702610176
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	23
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	115
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	131
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	151
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	177
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	736793856
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3876
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.18091321
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	779651
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	138.639694
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	3333

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2323117824	2323117824	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	8082	8082	✔
AASNodeAbsentTimer_mS_M_u32	2323117824	2323117824	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	8914	8914	✔
AngleVolantMsgTimer_mS_M_u32	2323117824	2323117824	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	-714.473877	-714.473877	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2323117824	2323117824	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2323117824	2323117824	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2323117824	2323117824	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2323117824	2323117824	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	25692	25692	✔
BSINodeAbsentTimer_mS_M_u32	2323117824	2323117824	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2323117824	2323117824	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2323117824	2323117824	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2323117824	2323117824	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2323117824	2323117824	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2323117824	2323117824	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	38358	38358	✔
CONSANGLECPK_HwDeg_M_f32	404.374908	404.374908 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	38358	38358	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	810579200	810579200	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	9190	9190	✔
CityParkInputConsistentCount_Cnt_M_u16	16027	16027	✔
CityParkInputInvalidCount_Cnt_M_u16	58067	58067	✔
CityParkInputMsgTimer_mS_M_u32	2323117824	2323117824	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2323117824	2323117824	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2323117824	2323117824	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2323117824	2323117824	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2323117824	2323117824	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2323117824	2323117824	✔
ESPNTCEnableTimer_mS_M_u32	2323117824	2323117824	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	69	69	✔
ESPNodeAbsentTimer_mS_M_u32	2323117824	2323117824	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	5	5	✔
EffacDefaultDiagTimer_mS_M_u32[1]	55	55	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3	3	✔
ElecIntTimer_mS_M_u32[1]	7	7	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2323117824	2323117824	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2323117824	2323117824	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2323117824	2323117824	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2323117824	2323117824	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2323117824	2323117824	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2323117824	2323117824	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2323117824	2323117824	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2323117824	2323117824	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2323117824	2323117824	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2323117824	2323117824	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2323117824	2323117824	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2323117824	2323117824	✔
IgnOnTimer_mS_M_u32	2323117824	2323117824	✔
IgnTimeOff_Sec_M_u32	200630229	200630229	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	15	15	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	166	166	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3445589248	3445589248	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	130	130	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2468750592	2468750592	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	12	12	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	998032640	998032640	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	173	173	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	778265856	778265856	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	76399872	76399872	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	210	210	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2480973056	2480973056	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	38	38	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3598140672	3598140672	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	91	91	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3346556160	3346556160	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	71	71	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3697181952	3697181952	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	112	112	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3483706624	3483706624	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	7	7	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1702610176	1702610176	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	736793856	736793856	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	556.448486	556.448486	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	249.377502	249.377502	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	19.9237003	19.9237003	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	-714.473877	-714.473877	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	38358	38358	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	200630229	200630229	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	404.374908	404.374908 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.108 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	413819904
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	5588
AASNodeAbsentTimer_mS_M_u32	2281755648
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	63301
ANGLEVOLANTSigValidCount_Cnt_M_u16	62673
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	34105
AngleVolantMsgTimer_mS_M_u32	413819904
AngleVolantValidCount_Cnt_M_u16	2780
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	628.498474
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2302579712
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4208006144
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3709993984
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3834037248
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	63844
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2152629248
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	21000
CAVNodeAbsentTimer_mS_M_u32	3249304576
CDD_SrlComVehSpd_Kph_G_f32	242.030899
CMM388NTCEnableTimer_mS_M_u32	2186982400
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	947024896
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	60820
CMMNodeAbsentTimer_mS_M_u32	406897664
CONSANGLECPKSigInvalidCount_Cnt_M_u16	56239
CONSANGLECPKSigValidCount_Cnt_M_u16	35083
CONSANGLECPK_Cnt_M_u16	26606
CONSANGLECPK_HwDeg_M_f32	-199.229095
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	26606
CPKVehicleSpeedMsgTimer_mS_M_u32	851534848
CPKVehicleSpeedValidCount_Cnt_M_u16	52357
CityParkInputConsistentCount_Cnt_M_u16	40032
CityParkInputInvalidCount_Cnt_M_u16	57527

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	3445589248
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2055525376
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	44376
ComputerRazGCTSigInvalidTimer_mS_M_u32	1463874560
ComputerRazGCTSigValidCount_Cnt_M_u16	53565
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	35635
DMDFCTCPKSigValidCount_Cnt_M_u16	26983
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	12039
DMDRELAXECPKSigValidCount_Cnt_M_u16	55827
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	27668
DateInvalidTimer_mS_M_u32	4208006144
DiagMuxOnAbsentTimer_mS_M_u32	4132578304
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3834037248
ESPNTCEnableTimer_mS_M_u32	2880033792
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	28412
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	97
EffacDefaultDiagTimer_mS_M_u32[1]	977
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	9
ElecIntTimer_mS_M_u32[1]	483581440
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2976941056
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	55839
EtatMTSigValidCount_Cnt_M_u16	59767
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	55665
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	46157
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	10797
ISDAT4V2BSI552MsgTimer_mS_M_u32	2781135872
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	27316
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	660
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	59767
ISDATBSI3F2MsgTimer_mS_M_u32	3499107328
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	8700
ISDATBSI412MsgLenValidCount_Cnt_M_u16	52108
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	55839
ISDATBSI412MsgTimer_mS_M_u32	1760060416
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	22040
ISDATBSI432MsgLenValidCount_Cnt_M_u16	62080
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	53713
ISDATDIRASentFltAcc_Cnt_M_u16	997
ISDATDIRASentTimer_mS_M_u32	851534848
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	5292
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	2780
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	25298
ISDYN2CMMMsgTimer_mS_M_u32	3756250112
ISDYNAASChkSumInvalidCount_Cnt_M_u16	14742
ISDYNAASChkSumValidCount_Cnt_M_u16	22850
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	22651
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	36651
ISDYNAASMsgLenValidCount_Cnt_M_u16	41743
ISDYNAASMsgTimeValidCount_Cnt_M_u16	14742
ISDYNAASMsgTimer_mS_M_u32	2044113920
ISDYNABRChkSumInvalidCount_Cnt_M_u16	56737
ISDYNABRChkSumValidCount_Cnt_M_u16	43445
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	40373
ISDYNABRMsgCountValidCount_Cnt_M_u16	59041
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	64206
ISDYNABRMsgLenValidCount_Cnt_M_u16	4458
ISDYNABRMsgTimeValidCount_Cnt_M_u16	26606
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	708
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1301

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	59767
ISDYNCMM208MsgTimer_mS_M_u32	2354811904
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2683
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1407
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	47642
ISDYNCMM388MsgTimer_mS_M_u32	2403742720
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	11757
ISDYNVOLChkSumValidCount_Cnt_M_u16	44489
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	55409
ISDYNVOLMsgCountValidCount_Cnt_M_u16	51493
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	45533
ISDYNVOLMsgLenValidCount_Cnt_M_u16	40217
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	60820
ISDYNVOLMsgTimer_mS_M_u32	3669816320
IgnOnTimer_mS_M_u32	1875522560
IgnTimeOff_Sec_M_u32	2710131774
ManVehSpd_Kph_M_f32	468.633606
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	37
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2385912832
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	126
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2669741056
PrevISDATBSI412MsgDLCError_Cnt_M_u08	94
PrevISDATBSI412MsgRxTime_MSec_M_u32	3056956416
PrevISDATBSI432MsgDLCError_Cnt_M_u08	233
PrevISDATBSI432MsgRxTime_MSec_M_u32	3743273984
PrevISDATDIRAMsgTxTime_MSec_M_u32	256472064
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	95
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4101522432
PrevISDYNAASMsgDLCError_Cnt_M_u08	141
PrevISDYNAASMsgRxTime_MSec_M_u32	259716096
PrevISDYNABRMsgDLCError_Cnt_M_u08	146
PrevISDYNABRMsgRxTime_MSec_M_u32	1774334976
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	172
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1008202752
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	122
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2197869568
PrevISDYNVOLMsgDLCError_Cnt_M_u08	202
PrevISDYNVOLMsgRxTime_MSec_M_u32	174748672
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3290850304
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	332.871613
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	21097
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	63693
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	26314
VitesseVehicleBVRampValidCount_Cnt_M_u16	17390
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	2342
VitesseVehicleBVSigValidCount_Cnt_M_u16	23922
VitesseVehicleBV_Kph_M_f32	174.712906

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	47642
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	7133
VitesseVehiculeRoues_Kph_M_f32	605.409729
k_AASNTCEnableTimeout_mS_u16	57925
k_AASNodeAbsentDiag_Cnt_str.Threshold	30131
k_AASNodeAbsentDiag_Cnt_str.PStep	47781
k_AASNodeAbsentDiag_Cnt_str.NStep	8150
k_AASNodeAbsentTimeout_mS_u16	37367
k_AASNodeTimeout_mS_u16	29645
k_ABSNodeTimeout_mS_u16	55312
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	49267
k_ANGLEVOLANTSigValidThresh_Cnt_u16	64283
k_AngleVolantInvalidThresh_Cnt_u16	11330
k_AngleVolantValidThresh_Cnt_u16	57527
k_BSI552MsgTimeout_mS_u16	5060
k_BSINTCEnableTimeout_mS_u16	16400
k_BSINodeAbsentDiag_Cnt_str.Threshold	25732
k_BSINodeAbsentDiag_Cnt_str.PStep	34604
k_BSINodeAbsentDiag_Cnt_str.NStep	14889
k_BSINodeAbsentTimeout_mS_u16	45361
k_BSINodeTimeout_mS_u16	53713
k_BattOvHi_Volt_f32	29.4449997
k_BattOvLo_Volt_f32	10.8465004
k_BattUvHi_Volt_f32	27.1499996
k_BattUvLo_Volt_f32	20.8658009
k_CAVNTCEnableTimeout_mS_u16	40429
k_CAVNodeAbsentDiag_Cnt_str.Threshold	15352
k_CAVNodeAbsentDiag_Cnt_str.PStep	23992
k_CAVNodeAbsentDiag_Cnt_str.NStep	3990
k_CAVNodeAbsentTimeout_mS_u16	51270
k_CAVNodeTimeout_mS_u16	35627
k_CMM388MsgTimeout_mS_u16	53460
k_CMM388NTCEnableTimeout_mS_u16	31056
k_CMMNTCEnableTimeout_mS_u16	4268
k_CMMNodeAbsentDiag_Cnt_str.Threshold	26250
k_CMMNodeAbsentDiag_Cnt_str.PStep	36606
k_CMMNodeAbsentDiag_Cnt_str.NStep	33253
k_CMMNodeAbsentTimeout_mS_u16	2649
k_CONSANGLECPKMax_HwDeg_f32	344.689301
k_CONSANGLECPKMin_HwDeg_f32	-186.911102
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	62746
k_CONSANGLECPKSigValidThresh_Cnt_u16	38621
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	59283
k_CPKVehicleSpeedValidThresh_Cnt_u16	23263
k_CityParkInputInvalidThresh_Cnt_u16	8679
k_CityParkInputValidThresh_Cnt_u16	40032
k_ComputerRazGCTSigValidThresh_Cnt_u16	14042
k_CptTemporelSigValidThresh_Cnt_u16	48954
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	46542
k_DMDFCTCPKSigValidThresh_Cnt_u16	3178
k_DMDFCTCPKValidCount_Cnt_u16	6252
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	25298
k_DMDRELAXECPKSigValidThresh_Cnt_u16	2630
k_DMDRelaxeConsistentThresh_Cnt_u16	55308
k_DateValidThresh_Cnt_u16	10797
k_DefaultVehSpd_Kph_f32	6.19729996
k_DiagMuxOnAbsentTimeout_mS_u16	58020
k_EMNodeTimeout_mS_u16	51316
k_ESPNTCEnableTimeout_mS_u16	21380
k_ESPNodeAbsentDiag_Cnt_str.Threshold	58075
k_ESPNodeAbsentDiag_Cnt_str.PStep	21601
k_ESPNodeAbsentDiag_Cnt_str.NStep	58120
k_ESPNodeAbsentTimeout_mS_u16	59489
k_EtatMTSigInvalidThresh_Cnt_u16	32680
k_EtatMTSigValidThresh_Cnt_u16	37628
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	8534
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	42126
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	45761
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	44601
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	20441
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	16512
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	28445
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	13637

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	65180
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	58066
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	18818
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	44296
k_ISDATDIRASentDiag_Cnt_str.Threshold	39767
k_ISDATDIRASentDiag_Cnt_str.PStep	14534
k_ISDATDIRASentDiag_Cnt_str.NStep	62426
k_ISDATDIRASentTimeout_mS_u16	31517
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	10533
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	34105
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	34064
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	6305
k_ISDYNAASChkSumValidThresh_Cnt_u16	9397
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	22709
k_ISDYNAASMsgCountValidThresh_Cnt_u16	57761
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	47909
k_ISDYNAASMsgLenValidThresh_Cnt_u16	40273
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	59171
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	12300
k_ISDYNABRChkSumValidThresh_Cnt_u16	22824
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	46180
k_ISDYNABRMsgCountValidThresh_Cnt_u16	39728
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	26772
k_ISDYNABRMsgLenValidThresh_Cnt_u16	10748
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	38039
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	7149
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	52125
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	43700
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	45637
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	61393
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	45231
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	63703
k_ISDYNVOLChkSumValidThresh_Cnt_u16	41127
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	34145
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	25145
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	10395
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	23795
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	62435
k_IgnOnTimeout_mS_u16	43603
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	161.332596
k_PowerCutVehSpdLowThresh_Kph_f32	143.090393
k_PowerCutVehSpdLowTimeout_mS_u16	24369
k_VBattMaxAAS_Volt_f32	1.18690002
k_VBattMaxBSI_Volt_f32	29.7091999
k_VBattMaxCAV_Volt_f32	31.4053993
k_VBattMaxCMM388_Volt_f32	26.8754005
k_VBattMaxCMM_Volt_f32	23.0158997
k_VBattMaxESP_Volt_f32	5.17659998
k_VBattMinAAS_Volt_f32	3.2513001
k_VBattMinBSI_Volt_f32	5.17659998
k_VBattMinCAV_Volt_f32	16.1662006
k_VBattMinCMM388_Volt_f32	0.739600003
k_VBattMinCMM_Volt_f32	18.7560005
k_VBattMinESP_Volt_f32	23.0158997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	14431
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	41439
k_VitesseVehicleBVRampValidThresh_Cnt_u16	4977
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	43209
k_VitesseVehicleBVSigValidThresh_Cnt_u16	27321
k_VitesseVehicleBVSpeedPassThresh_kph_f32	637.587219
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	36104
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	15532
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	4208006144
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	232
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	46913
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	483581440
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	122

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	9.81210041
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1316455424
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	234
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.805034876
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	735327232
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3170915328
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3866915840
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	122
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1883804672
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	577025024
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3302020096
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	529331200
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	45
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	55
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	956929024
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	70
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	97
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	111
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	97
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3134665728
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3280163840
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	228
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	612332544
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	43
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	82
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	109
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3497198592
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3855
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.282161981
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	318691
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	85.0290985
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	46883

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	483581440	483581440	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	30131	30131	✔
AASNodeAbsentTimer_mS_M_u32	483581440	483581440	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	34105	34105	✔
AngleVolantMsgTimer_mS_M_u32	483581440	483581440	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	628.498474	628.498474	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	483581440	483581440	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	483581440	483581440	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	483581440	483581440	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	483581440	483581440	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	25732	25732	✔
BSINodeAbsentTimer_mS_M_u32	483581440	483581440	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	483581440	483581440	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	483581440	483581440	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	483581440	483581440	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	483581440	483581440	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	483581440	483581440	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	26606	26606	✔
CONSANGLECPK_HwDeg_M_f32	-199.229095	-199.229095 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	26606	26606	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	851534848	851534848	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	52357	52357	✔
CityParkInputConsistentCount_Cnt_M_u16	40032	40032	✔
CityParkInputInvalidCount_Cnt_M_u16	57527	57527	✔
CityParkInputMsgTimer_mS_M_u32	483581440	483581440	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	483581440	483581440	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	483581440	483581440	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	483581440	483581440	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	483581440	483581440	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	483581440	483581440	✔
ESPNTCEnableTimer_mS_M_u32	483581440	483581440	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	58075	58075	✔
ESPNodeAbsentTimer_mS_M_u32	483581440	483581440	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	483581440	483581440	✔
EffacDefaultDiagTimer_mS_M_u32[1]	977	977	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	9	9	✔
ElecIntTimer_mS_M_u32[1]	483581440	483581440	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	483581440	483581440	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	483581440	483581440	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	483581440	483581440	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	483581440	483581440	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	483581440	483581440	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	483581440	483581440	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	483581440	483581440	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	483581440	483581440	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	483581440	483581440	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	483581440	483581440	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	483581440	483581440	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	483581440	483581440	✔
IgnOnTimer_mS_M_u32	1875522560	1875522560	✔
IgnTimeOff_Sec_M_u32	2710131774	2710131774	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	133	133	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	735327232	735327232	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	181	181	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3170915328	3170915328	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	26	26	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3866915840	3866915840	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	122	122	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1883804672	1883804672	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	256472064	256472064	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	81	81	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3302020096	3302020096	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	86	86	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	529331200	529331200	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	2	2	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	956929024	956929024	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	97	97	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3134665728	3134665728	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	168	168	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3280163840	3280163840	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	228	228	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	612332544	612332544	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3497198592	3497198592	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	332.871613	332.871613	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	174.712906	174.712906	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	605.409729	605.409729	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	628.498474	628.498474	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	26606	26606	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2710131774	2710131774	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-199.229095	-199.229095 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	6.19729996	6.19729996	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.109 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2419037952
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	25264
AASNodeAbsentTimer_mS_M_u32	3891021568
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	8286
ANGLEVOLANTSigValidCount_Cnt_M_u16	33658
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	59521
AngleVolantMsgTimer_mS_M_u32	2419037952
AngleVolantValidCount_Cnt_M_u16	2074
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	384.845215
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	187893504
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	544966400
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	692631296
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2518316800
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	22017
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2445489920
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	33941
CAVNodeAbsentTimer_mS_M_u32	4050216704
CDD_SrlComVehSpd_Kph_G_f32	95.4414978
CMM388NTCEnableTimer_mS_M_u32	945727232
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	622290688
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	24240
CMMNodeAbsentTimer_mS_M_u32	1659664128
CONSANGLECPKSigInvalidCount_Cnt_M_u16	18977
CONSANGLECPKSigValidCount_Cnt_M_u16	56781
CONSANGLECPK_Cnt_M_u16	36132
CONSANGLECPK_HwDeg_M_f32	-476.959503
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	36132
CPKVehicleSpeedMsgTimer_mS_M_u32	1575655168
CPKVehicleSpeedValidCount_Cnt_M_u16	21253
CityParkInputConsistentCount_Cnt_M_u16	25486

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	904
CityParkInputMsgTimer_mS_M_u32	735327232
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	543180544
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	44068
ComputerRazGCTSigInvalidTimer_mS_M_u32	581691136
ComputerRazGCTSigValidCount_Cnt_M_u16	30967
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	62484
DMDFCTCPKSigValidCount_Cnt_M_u16	21817
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	280
DMDRELAXECPKSigValidCount_Cnt_M_u16	23476
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	27890
DateInvalidTimer_mS_M_u32	544966400
DiagMuxOnAbsentTimer_mS_M_u32	1178097408
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2518316800
ESPNTCEnableTimer_mS_M_u32	1626425088
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	42552
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	4
EffacDefaultDiagTimer_mS_M_u32[1]	6
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	3592300800
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	106772224
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	54798
EtatMTSigValidCount_Cnt_M_u16	13255
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	55515
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	58375
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	43751
ISDAT4V2BSI552MsgTimer_mS_M_u32	3395319552
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	28113
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	20977
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13255
ISDATBSI3F2MsgTimer_mS_M_u32	796808960
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	47353
ISDATBSI412MsgLenValidCount_Cnt_M_u16	10249
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	54798
ISDATBSI412MsgTimer_mS_M_u32	393582336
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	13604
ISDATBSI432MsgLenValidCount_Cnt_M_u16	11180
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	26938
ISDATDIRASentFltAcc_Cnt_M_u16	8958
ISDATDIRASentTimer_mS_M_u32	1575655168
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	65258
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	2074
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	43319
ISDYN2CMMMsgTimer_mS_M_u32	742606592
ISDYNAASChkSumInvalidCount_Cnt_M_u16	32618
ISDYNAASChkSumValidCount_Cnt_M_u16	64550
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	23357
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	6444
ISDYNAASMsgLenValidCount_Cnt_M_u16	39232
ISDYNAASMsgTimeValidCount_Cnt_M_u16	32618
ISDYNAASMsgTimer_mS_M_u32	1105897216
ISDYNABRChkSumInvalidCount_Cnt_M_u16	54985
ISDYNABRChkSumValidCount_Cnt_M_u16	61005
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	36621
ISDYNABRMsgCountValidCount_Cnt_M_u16	36873
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	10436
ISDYNABRMsgLenValidCount_Cnt_M_u16	32944
ISDYNABRMsgTimeValidCount_Cnt_M_u16	36132
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	709

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1303
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13255
ISDYNCMM208MsgTimer_mS_M_u32	3051095808
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2687
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1409
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	29280
ISDYNCMM388MsgTimer_mS_M_u32	530327296
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	52071
ISDYNVOLChkSumValidCount_Cnt_M_u16	59283
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	33882
ISDYNVOLMsgCountValidCount_Cnt_M_u16	44543
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	41365
ISDYNVOLMsgLenValidCount_Cnt_M_u16	64418
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	24240
ISDYNVOLMsgTimer_mS_M_u32	2285364992
IgnOnTimer_mS_M_u32	2383423232
IgnTimeOff_Sec_M_u32	1856532201
ManVehSpd_Kph_M_f32	619.991577
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	39
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	237
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	244078336
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	45
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2672539392
PrevISDATBSI412MsgDLCError_Cnt_M_u08	87
PrevISDATBSI412MsgRxTime_MSec_M_u32	2010015488
PrevISDATBSI432MsgDLCError_Cnt_M_u08	192
PrevISDATBSI432MsgRxTime_MSec_M_u32	2526365440
PrevISDATDIRAMsgTxTime_MSec_M_u32	3163711232
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	185
PrevISDYN2CMMMsgRxTime_MSec_M_u32	205911808
PrevISDYNAASMsgDLCError_Cnt_M_u08	150
PrevISDYNAASMsgRxTime_MSec_M_u32	1644029696
PrevISDYNABRMsgDLCError_Cnt_M_u08	143
PrevISDYNABRMsgRxTime_MSec_M_u32	2150115072
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	224
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2418468608
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	0
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4142679808
PrevISDYNVOLMsgDLCError_Cnt_M_u08	30
PrevISDYNVOLMsgRxTime_MSec_M_u32	2402248448
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2109445888
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	381.834198
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	18290
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	4102
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	52815
VitesseVehicleBVRampValidCount_Cnt_M_u16	62115
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	44731
VitesseVehicleBVSigValidCount_Cnt_M_u16	3479

Name	Input Value
VitesseVehicleBV_Kph_M_f32	156.384995
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	29280
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	35028
VitesseVehiculeRoues_Kph_M_f32	293.628693
k_AASNTCEnableTimeout_mS_u16	14879
k_AASNodeAbsentDiag_Cnt_str.Threshold	17130
k_AASNodeAbsentDiag_Cnt_str.PStep	55148
k_AASNodeAbsentDiag_Cnt_str.NStep	43124
k_AASNodeAbsentTimeout_mS_u16	40649
k_AASNodeTimeout_mS_u16	40710
k_ABSNodeTimeout_mS_u16	49533
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	8723
k_ANGLEVOLANTSigValidThresh_Cnt_u16	15835
k_AngleVolantInvalidThresh_Cnt_u16	1638
k_AngleVolantValidThresh_Cnt_u16	904
k_BSI552MsgTimeout_mS_u16	64799
k_BSINTCEnableTimeout_mS_u16	22332
k_BSINodeAbsentDiag_Cnt_str.Threshold	25772
k_BSINodeAbsentDiag_Cnt_str.PStep	34587
k_BSINodeAbsentDiag_Cnt_str.NStep	14912
k_BSINodeAbsentTimeout_mS_u16	17561
k_BSINodeTimeout_mS_u16	26938
k_BattOvHi_Volt_f32	19.7569008
k_BattOvLo_Volt_f32	26.3899002
k_BattUvHi_Volt_f32	5.37729979
k_BattUvLo_Volt_f32	29.7840996
k_CAVNTCEnableTimeout_mS_u16	9190
k_CAVNodeAbsentDiag_Cnt_str.Threshold	18835
k_CAVNodeAbsentDiag_Cnt_str.PStep	54251
k_CAVNodeAbsentDiag_Cnt_str.NStep	10538
k_CAVNodeAbsentTimeout_mS_u16	39387
k_CAVNodeTimeout_mS_u16	11181
k_CMM388MsgTimeout_mS_u16	12720
k_CMM388NTCEnableTimeout_mS_u16	10300
k_CMMNTCEnableTimeout_mS_u16	23529
k_CMMNodeAbsentDiag_Cnt_str.Threshold	63942
k_CMMNodeAbsentDiag_Cnt_str.PStep	30916
k_CMMNodeAbsentDiag_Cnt_str.NStep	36262
k_CMMNodeAbsentTimeout_mS_u16	44384
k_CONSANGLECPKMax_HwDeg_f32	528.489319
k_CONSANGLECPKMin_HwDeg_f32	-326.300201
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	49504
k_CONSANGLECPKSigValidThresh_Cnt_u16	6100
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	56244
k_CPKVehicleSpeedValidThresh_Cnt_u16	23120
k_CityParkInputInvalidThresh_Cnt_u16	41463
k_CityParkInputValidThresh_Cnt_u16	25486
k_ComputerRazGCTSigValidThresh_Cnt_u16	8543
k_CptTemporelSigValidThresh_Cnt_u16	13311
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	63428
k_DMDFCTCPKSigValidThresh_Cnt_u16	36784
k_DMDFCTCPKValidCount_Cnt_u16	6377
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	43319
k_DMDRELAXECPKSigValidThresh_Cnt_u16	44700
k_DMDRelaxeConsistentThresh_Cnt_u16	56650
k_DateValidThresh_Cnt_u16	43751
k_DefaultVehSpd_Kph_f32	144.090698
k_DiagMuxOnAbsentTimeout_mS_u16	29954
k_EMNodeTimeout_mS_u16	55250
k_ESPNTCEnableTimeout_mS_u16	28705
k_ESPNodeAbsentDiag_Cnt_str.Threshold	52660
k_ESPNodeAbsentDiag_Cnt_str.PStep	35451
k_ESPNodeAbsentDiag_Cnt_str.NStep	7452
k_ESPNodeAbsentTimeout_mS_u16	13128
k_EtatMTSigInvalidThresh_Cnt_u16	52404
k_EtatMTSigValidThresh_Cnt_u16	3704
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	64107
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	31875
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	58475
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	63298
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	48674
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	28013
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	15893

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	46941
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	19352
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	44152
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	25640
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	39124
k_ISDATDIRASentDiag_Cnt_str.Threshold	52217
k_ISDATDIRASentDiag_Cnt_str.PStep	24388
k_ISDATDIRASentDiag_Cnt_str.NStep	13533
k_ISDATDIRASentTimeout_mS_u16	61013
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	55421
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	59521
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	2941
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	9673
k_ISDYNAASChkSumValidThresh_Cnt_u16	32077
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	24077
k_ISDYNAASMsgCountValidThresh_Cnt_u16	40713
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	20029
k_ISDYNAASMsgLenValidThresh_Cnt_u16	12922
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39363
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	266
k_ISDYNABRChkSumValidThresh_Cnt_u16	8566
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	9473
k_ISDYNABRMsgCountValidThresh_Cnt_u16	52317
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	60848
k_ISDYNABRMsgLenValidThresh_Cnt_u16	30008
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	15400
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	64230
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	32790
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	22097
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	61278
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	37498
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	29600
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	24680
k_ISDYNVOLChkSumValidThresh_Cnt_u16	54456
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	14089
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	54465
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	55962
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	51539
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	42437
k_IgnOnTimeout_mS_u16	15348
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	17.1849003
k_PowerCutVehSpdLowThresh_Kph_f32	207.911499
k_PowerCutVehSpdLowTimeout_mS_u16	29531
k_VBattMaxAAS_Volt_f32	22.8243008
k_VBattMaxBSI_Volt_f32	6.15770006
k_VBattMaxCAV_Volt_f32	3.93729997
k_VBattMaxCMM388_Volt_f32	32
k_VBattMaxCMM_Volt_f32	4.38780022
k_VBattMaxESP_Volt_f32	22.4244003
k_VBattMinAAS_Volt_f32	24.3330002
k_VBattMinBSI_Volt_f32	22.4244003
k_VBattMinCAV_Volt_f32	26.4193993
k_VBattMinCMM388_Volt_f32	17.8497009
k_VBattMinCMM_Volt_f32	16.6198997
k_VBattMinESP_Volt_f32	4.38780022
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	4815
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	527
k_VitesseVehicleBVRampValidThresh_Cnt_u16	54106
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	63123
k_VitesseVehicleBVSigValidThresh_Cnt_u16	40067
k_VitesseVehicleBVSpeedPassThresh_kph_f32	606.66803
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	54165
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	32873
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	544966400
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	10
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	62889
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3592300800
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	0
target_SrlComInput_Per1_Batt_Volt_f32.value	27.2738991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	189282048
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	202
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.787436545
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	32646912
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2800600832
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3271124736
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4262790912
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4237056
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	248
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1903970048
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4190627584
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	58
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	104
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	196
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	201
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	247
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3889301248
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	153
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	176
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	552150784
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1600440064
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	160
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3572524800
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	164
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	165
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	189
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3545609984
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1593
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.215849012
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	887890
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	99.3452988

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	33092		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	3592300800	3592300800	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	17130	17130	✔
AASNodeAbsentTimer_mS_M_u32	3592300800	3592300800	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	59521	59521	✔
AngleVolantMsgTimer_mS_M_u32	3592300800	3592300800	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	384.845215	384.845215	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3592300800	3592300800	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3592300800	3592300800	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3592300800	3592300800	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3592300800	3592300800	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	25772	25772	✔
BSINodeAbsentTimer_mS_M_u32	3592300800	3592300800	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3592300800	3592300800	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3592300800	3592300800	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3592300800	3592300800	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3592300800	3592300800	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3592300800	3592300800	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	36132	36132	✔
CONSANGLECPK_HwDeg_M_f32	-476.959503	-476.959503 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	36132	36132	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1575655168	1575655168	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	21253	21253	✔
CityParkInputConsistentCount_Cnt_M_u16	25486	25486	✔
CityParkInputInvalidCount_Cnt_M_u16	906	906	✔
CityParkInputMsgTimer_mS_M_u32	3592300800	3592300800	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3592300800	3592300800	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3592300800	3592300800	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3592300800	3592300800	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3592300800	3592300800	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3592300800	3592300800	✔
ESPNTCEnableTimer_mS_M_u32	3592300800	3592300800	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	52660	52660	✔
ESPNodeAbsentTimer_mS_M_u32	3592300800	3592300800	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4	4	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	6	6	✔
ElecIntCount_Cnt_M_u08	2	2	✔
ElecIntTimer_mS_M_u32[0]	10	10	✔
ElecIntTimer_mS_M_u32[1]	3592300800	3592300800	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3592300800	3592300800	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3592300800	3592300800	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3592300800	3592300800	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3592300800	3592300800	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3592300800	3592300800	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3592300800	3592300800	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3592300800	3592300800	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3592300800	3592300800	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3592300800	3592300800	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3592300800	3592300800	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3592300800	3592300800	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3592300800	3592300800	✔
IgnOnTimer_mS_M_u32	3592300800	3592300800	✔
IgnTimeOff_Sec_M_u32	1856532201	1856532201	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	63	63	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	32646912	32646912	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	104	104	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2800600832	2800600832	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	51	51	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3271124736	3271124736	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	74	74	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4262790912	4262790912	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3163711232	3163711232	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	248	248	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1903970048	1903970048	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4190627584	4190627584	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	247	247	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3889301248	3889301248	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	121	121	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	552150784	552150784	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	91	91	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1600440064	1600440064	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	160	160	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3572524800	3572524800	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3545609984	3545609984	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	381.834198	381.834198	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	156.384995	156.384995	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	293.628693	293.628693	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	384.845215	384.845215	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	36132	36132	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1856532201	1856532201	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-476.959503	-476.959503 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	144.090698	144.090698	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.110 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4062969344
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	7338
AASNodeAbsentTimer_mS_M_u32	4189449728
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	48542
ANGLEVOLANTSigValidCount_Cnt_M_u16	33034
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	3895
AngleVolantMsgTimer_mS_M_u32	4062969344
AngleVolantValidCount_Cnt_M_u16	40682
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	516.570984
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	450997760
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2634558976
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1935711744
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2750111232
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	26805
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1139875328
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	13179
CAVNodeAbsentTimer_mS_M_u32	3116273152
CDD_SrlComVehSpd_Kph_G_f32	0.771700025
CMM388NTCEnableTimer_mS_M_u32	1239338496
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1454673408
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	40680
CMMNodeAbsentTimer_mS_M_u32	91577856
CONSANGLECPKSigInvalidCount_Cnt_M_u16	47958
CONSANGLECPKSigValidCount_Cnt_M_u16	11538
CONSANGLECPK_Cnt_M_u16	15117
CONSANGLECPK_HwDeg_M_f32	280.296814
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	15117
CPKVehicleSpeedMsgTimer_mS_M_u32	888864256
CPKVehicleSpeedValidCount_Cnt_M_u16	44659
CityParkInputConsistentCount_Cnt_M_u16	23694
CityParkInputInvalidCount_Cnt_M_u16	13727

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	32646912
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	542764544
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	4174
ComputerRazGCTSigInvalidTimer_mS_M_u32	1341591040
ComputerRazGCTSigValidCount_Cnt_M_u16	83
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	37883
DMDFCTCPKSigValidCount_Cnt_M_u16	32079
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	33648
DMDRELAXECPKSigValidCount_Cnt_M_u16	24668
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	55011
DateInvalidTimer_mS_M_u32	2634558976
DiagMuxOnAbsentTimer_mS_M_u32	3809590784
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2750111232
ESPNTCEnableTimer_mS_M_u32	3802590720
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	25872
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	3374860288
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	80
ElecIntTimer_mS_M_u32[1]	101
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3458407936
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	33230
EtatMTSigValidCount_Cnt_M_u16	50533
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	30504
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	33380
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	46149
ISDAT4V2BSI552MsgTimer_mS_M_u32	2669239808
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	56837
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	11876
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	50533
ISDATBSI3F2MsgTimer_mS_M_u32	3208625664
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	43407
ISDATBSI412MsgLenValidCount_Cnt_M_u16	6431
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	33230
ISDATBSI412MsgTimer_mS_M_u32	4099538432
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	60300
ISDATBSI432MsgLenValidCount_Cnt_M_u16	42164
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	22924
ISDATDIRASentFltAcc_Cnt_M_u16	15424
ISDATDIRASentTimer_mS_M_u32	888864256
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	32187
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	40682
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	49298
ISDYN2CMMMsgTimer_mS_M_u32	1219554816
ISDYNAASChkSumInvalidCount_Cnt_M_u16	11900
ISDYNAASChkSumValidCount_Cnt_M_u16	9479
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	61825
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	37302
ISDYNAASMsgLenValidCount_Cnt_M_u16	56889
ISDYNAASMsgTimeValidCount_Cnt_M_u16	11900
ISDYNAASMsgTimer_mS_M_u32	1564134912
ISDYNABRChkSumInvalidCount_Cnt_M_u16	24030
ISDYNABRChkSumValidCount_Cnt_M_u16	42001
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	19347
ISDYNABRMsgCountValidCount_Cnt_M_u16	46430
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	27501
ISDYNABRMsgLenValidCount_Cnt_M_u16	36969
ISDYNABRMsgTimeValidCount_Cnt_M_u16	15117
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	710
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1305

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	50533
ISDYNCMM208MsgTimer_mS_M_u32	4276530688
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2691
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1411
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	63512
ISDYNCMM388MsgTimer_mS_M_u32	1780895232
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	53124
ISDYNVOLChkSumValidCount_Cnt_M_u16	42944
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	31529
ISDYNVOLMsgCountValidCount_Cnt_M_u16	2813
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	9977
ISDYNVOLMsgLenValidCount_Cnt_M_u16	50580
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	40680
ISDYNVOLMsgTimer_mS_M_u32	1330843136
IgnOnTimer_mS_M_u32	4006235648
IgnTimeOff_Sec_M_u32	119224729
ManVehSpd_Kph_M_f32	64.7666016
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	41
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	92
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3658857984
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	171
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3713506816
PrevISDATBSI412MsgDLCError_Cnt_M_u08	210
PrevISDATBSI412MsgRxTime_MSec_M_u32	4203712000
PrevISDATBSI432MsgDLCError_Cnt_M_u08	122
PrevISDATBSI432MsgRxTime_MSec_M_u32	3518688768
PrevISDATDIRAMsgTxTime_MSec_M_u32	1011060224
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	130
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1332272640
PrevISDYNAASMsgDLCError_Cnt_M_u08	177
PrevISDYNAASMsgRxTime_MSec_M_u32	1510018560
PrevISDYNABRMsgDLCError_Cnt_M_u08	178
PrevISDYNABRMsgRxTime_MSec_M_u32	2021805568
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	224
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3011907072
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	255
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3434475008
PrevISDYNVOLMsgDLCError_Cnt_M_u08	90
PrevISDYNVOLMsgRxTime_MSec_M_u32	2020380160
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1502084608
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	90.2101974
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	40676
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	4583
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	48717
VitesseVehicleBVRampValidCount_Cnt_M_u16	7696
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	50823
VitesseVehicleBVSigValidCount_Cnt_M_u16	38579
VitesseVehicleBV_Kph_M_f32	240.9729

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	63512
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	380
VitesseVehiculeRoues_Kph_M_f32	135.619293
k_AASNTCEnableTimeout_mS_u16	57372
k_AASNodeAbsentDiag_Cnt_str.Threshold	56434
k_AASNodeAbsentDiag_Cnt_str.PStep	21731
k_AASNodeAbsentDiag_Cnt_str.NStep	16390
k_AASNodeAbsentTimeout_mS_u16	22237
k_AASNodeTimeout_mS_u16	25831
k_ABSNodeTimeout_mS_u16	4032
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	41151
k_ANGLEVOLANTSigValidThresh_Cnt_u16	59943
k_AngleVolantInvalidThresh_Cnt_u16	31878
k_AngleVolantValidThresh_Cnt_u16	13727
k_BSI552MsgTimeout_mS_u16	37019
k_BSINTCEnableTimeout_mS_u16	58692
k_BSINodeAbsentDiag_Cnt_str.Threshold	25812
k_BSINodeAbsentDiag_Cnt_str.PStep	34570
k_BSINodeAbsentDiag_Cnt_str.NStep	14935
k_BSINodeAbsentTimeout_mS_u16	23279
k_BSINodeTimeout_mS_u16	22924
k_BattOvHi_Volt_f32	12.7090998
k_BattOvLo_Volt_f32	10.2978001
k_BattUvHi_Volt_f32	22.1418991
k_BattUvLo_Volt_f32	29.7588005
k_CAVNTCEnableTimeout_mS_u16	52357
k_CAVNodeAbsentDiag_Cnt_str.Threshold	39951
k_CAVNodeAbsentDiag_Cnt_str.PStep	36415
k_CAVNodeAbsentDiag_Cnt_str.NStep	44539
k_CAVNodeAbsentTimeout_mS_u16	35753
k_CAVNodeTimeout_mS_u16	18098
k_CMM388MsgTimeout_mS_u16	44970
k_CMM388NTCEnableTimeout_mS_u16	64518
k_CMMNTCEnableTimeout_mS_u16	29629
k_CMMNodeAbsentDiag_Cnt_str.Threshold	39871
k_CMMNodeAbsentDiag_Cnt_str.PStep	38332
k_CMMNodeAbsentDiag_Cnt_str.NStep	61008
k_CMMNodeAbsentTimeout_mS_u16	50136
k_CONSANGLECPKMax_HwDeg_f32	125.195198
k_CONSANGLECPKMin_HwDeg_f32	-98.6636963
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	2840
k_CONSANGLECPKSigValidThresh_Cnt_u16	21628
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	59101
k_CPKVehicleSpeedValidThresh_Cnt_u16	57738
k_CityParkInputInvalidThresh_Cnt_u16	13396
k_CityParkInputValidThresh_Cnt_u16	23694
k_ComputerRazGCTSigValidThresh_Cnt_u16	31579
k_CptTemporelSigValidThresh_Cnt_u16	16442
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	65133
k_DMDFCTCPKSigValidThresh_Cnt_u16	25449
k_DMDFCTCPKValidCount_Cnt_u16	49149
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	49298
k_DMDRELAXECPKSigValidThresh_Cnt_u16	48422
k_DMDRelaxeConsistentThresh_Cnt_u16	26908
k_DateValidThresh_Cnt_u16	46149
k_DefaultVehSpd_Kph_f32	152.957504
k_DiagMuxOnAbsentTimeout_mS_u16	31603
k_EMNodeTimeout_mS_u16	5699
k_ESPNTCEnableTimeout_mS_u16	41175
k_ESPNodeAbsentDiag_Cnt_str.Threshold	50518
k_ESPNodeAbsentDiag_Cnt_str.PStep	47863
k_ESPNodeAbsentDiag_Cnt_str.NStep	42829
k_ESPNodeAbsentTimeout_mS_u16	53792
k_EtatMTSigInvalidThresh_Cnt_u16	59421
k_EtatMTSigValidThresh_Cnt_u16	44944
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	9912
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	32047
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	36343
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	17842
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	60881
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	23603
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	54457
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	1441

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	30768
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	11537
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	17088
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	34557
k_ISDATDIRASentDiag_Cnt_str.Threshold	13150
k_ISDATDIRASentDiag_Cnt_str.PStep	38581
k_ISDATDIRASentDiag_Cnt_str.NStep	24929
k_ISDATDIRASentTimeout_mS_u16	18234
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	44034
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	3895
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	16067
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	28894
k_ISDYNAASChkSumValidThresh_Cnt_u16	63249
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	56979
k_ISDYNAASMsgCountValidThresh_Cnt_u16	34910
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	51074
k_ISDYNAASMsgLenValidThresh_Cnt_u16	31371
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	30319
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	31387
k_ISDYNABRChkSumValidThresh_Cnt_u16	17943
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	64437
k_ISDYNABRMsgCountValidThresh_Cnt_u16	62049
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	61928
k_ISDYNABRMsgLenValidThresh_Cnt_u16	63504
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	36608
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	21640
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	2104
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	11014
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	20638
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	21514
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	17751
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	12098
k_ISDYNVOLChkSumValidThresh_Cnt_u16	36626
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	13981
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	49333
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	42026
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	13505
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	48043
k_IgnOnTimeout_mS_u16	52382
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	30.1748009
k_PowerCutVehSpdLowThresh_Kph_f32	73.9951019
k_PowerCutVehSpdLowTimeout_mS_u16	9320
k_VBattMaxAAS_Volt_f32	23.7245998
k_VBattMaxBSI_Volt_f32	32
k_VBattMaxCAV_Volt_f32	30.0800991
k_VBattMaxCMM388_Volt_f32	29.6574993
k_VBattMaxCMM_Volt_f32	3.88170004
k_VBattMaxESP_Volt_f32	23.2164993
k_VBattMinAAS_Volt_f32	29.0921001
k_VBattMinBSI_Volt_f32	23.2164993
k_VBattMinCAV_Volt_f32	32
k_VBattMinCMM388_Volt_f32	24.5976009
k_VBattMinCMM_Volt_f32	1.829
k_VBattMinESP_Volt_f32	3.88170004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	50444
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	29708
k_VitesseVehicleBVRampValidThresh_Cnt_u16	36393
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	31424
k_VitesseVehicleBVSigValidThresh_Cnt_u16	50607
k_VitesseVehicleBVSpeedPassThresh_kph_f32	593.14679
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	18043
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	3262
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2634558976
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	241
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65021
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3374860288
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	255

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	10.2069998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	727850496
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	47
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.572942615
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	254
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2602847744
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2729537024
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2232323584
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1245425152
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4198026752
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2634411520
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	983764480
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	93
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	123
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	163
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	244
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	78
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3238309376
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	50
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	106
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	236
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3661581824
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	28
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	357330432
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3945369088
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	80
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	132
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	222
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3912867328
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3964
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.775911629
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	184177
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	223.943604
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	47470

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3374860288	3374860288	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	56434	56434	✔
AASNodeAbsentTimer_mS_M_u32	3374860288	3374860288	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	3897	3897	✔
AngleVolantMsgTimer_mS_M_u32	3374860288	3374860288	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	516.570984	516.570984	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3374860288	3374860288	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3374860288	3374860288	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3374860288	3374860288	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3374860288	3374860288	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	25812	25812	✔
BSINodeAbsentTimer_mS_M_u32	3374860288	3374860288	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3374860288	3374860288	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3374860288	3374860288	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3374860288	3374860288	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3374860288	3374860288	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3374860288	3374860288	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	15117	15117	✔
CONSANGLECPK_HwDeg_M_f32	280.296814	280.296814 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	15117	15117	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	888864256	888864256	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	44659	44659	✔
CityParkInputConsistentCount_Cnt_M_u16	23694	23694	✔
CityParkInputInvalidCount_Cnt_M_u16	13727	13727	✔
CityParkInputMsgTimer_mS_M_u32	3374860288	3374860288	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3374860288	3374860288	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3374860288	3374860288	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3374860288	3374860288	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3374860288	3374860288	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3374860288	3374860288	✔
ESPNTCEnableTimer_mS_M_u32	3374860288	3374860288	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	50518	50518	✔
ESPNodeAbsentTimer_mS_M_u32	3374860288	3374860288	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3374860288	3374860288	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	3374860288	3374860288	✔
ElecIntTimer_mS_M_u32[1]	101	101	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3374860288	3374860288	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3374860288	3374860288	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3374860288	3374860288	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3374860288	3374860288	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3374860288	3374860288	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3374860288	3374860288	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3374860288	3374860288	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3374860288	3374860288	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3374860288	3374860288	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3374860288	3374860288	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3374860288	3374860288	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3374860288	3374860288	✔
IgnOnTimer_mS_M_u32	3374860288	3374860288	✔
IgnTimeOff_Sec_M_u32	119224729	119224729	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	254	254	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2602847744	2602847744	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	92	92	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2729537024	2729537024	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	16	16	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2232323584	2232323584	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	34	34	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1245425152	1245425152	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1011060224	1011060224	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	132	132	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2634411520	2634411520	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	983764480	983764480	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	78	78	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3238309376	3238309376	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	236	236	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3661581824	3661581824	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	28	28	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	357330432	357330432	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3945369088	3945369088	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3912867328	3912867328	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	90.2101974	90.2101974	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	240.9729	240.9729	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	135.619293	135.619293	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	516.570984	516.570984	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	15117	15117	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	119224729	119224729	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	280.296814	280.296814 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.111 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2727528704
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	15639
AASNodeAbsentTimer_mS_M_u32	1605695744
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	52281
ANGLEVOLANTSigValidCount_Cnt_M_u16	48055
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	55664
AngleVolantMsgTimer_mS_M_u32	2727528704
AngleVolantValidCount_Cnt_M_u16	24278
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	270.146301
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1529985280
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2394831104
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	963963136
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1121233152
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	59124
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2848155904
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	33573
CAVNodeAbsentTimer_mS_M_u32	2317031680
CDD_SrlComVehSpd_Kph_G_f32	42.1389008
CMM388NTCEnableTimer_mS_M_u32	2864339200
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	188291328
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	21404
CMMNodeAbsentTimer_mS_M_u32	3325470976
CONSANGLECPKSigInvalidCount_Cnt_M_u16	25106
CONSANGLECPKSigValidCount_Cnt_M_u16	34464
CONSANGLECPK_Cnt_M_u16	2223
CONSANGLECPK_HwDeg_M_f32	90.0199966
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2223
CPKVehicleSpeedMsgTimer_mS_M_u32	3592800512
CPKVehicleSpeedValidCount_Cnt_M_u16	32612
CityParkInputConsistentCount_Cnt_M_u16	46570

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	65463
CityParkInputMsgTimer_mS_M_u32	2602847744
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2076768512
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	61995
ComputerRazGCTSigInvalidTimer_mS_M_u32	1232181504
ComputerRazGCTSigValidCount_Cnt_M_u16	7835
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	21667
DMDFCTCPKSigValidCount_Cnt_M_u16	29288
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	17091
DMDRELAXECPKSigValidCount_Cnt_M_u16	58817
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	33643
DateInvalidTimer_mS_M_u32	2394831104
DiagMuxOnAbsentTimer_mS_M_u32	2531363072
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1121233152
ESPNTCEnableTimer_mS_M_u32	2833381632
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	10982
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	102
EffacDefaultDiagTimer_mS_M_u32[1]	106
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	150
ElecIntTimer_mS_M_u32[1]	1151
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1395484928
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	53228
EtatMTSigValidCount_Cnt_M_u16	61158
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	63132
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	20138
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	9606
ISDAT4V2BSI552MsgTimer_mS_M_u32	2303371520
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	20678
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	26984
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	61158
ISDATBSI3F2MsgTimer_mS_M_u32	978815232
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	59175
ISDATBSI412MsgLenValidCount_Cnt_M_u16	25145
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	53228
ISDATBSI412MsgTimer_mS_M_u32	3557345536
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	64944
ISDATBSI432MsgLenValidCount_Cnt_M_u16	64506
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	38130
ISDATDIRASentFltAcc_Cnt_M_u16	48342
ISDATDIRASentTimer_mS_M_u32	3592800512
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	30885
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	24278
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	60126
ISDYN2CMMMsgTimer_mS_M_u32	516159744
ISDYNAASChkSumInvalidCount_Cnt_M_u16	53153
ISDYNAASChkSumValidCount_Cnt_M_u16	42430
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	33553
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	5236
ISDYNAASMsgLenValidCount_Cnt_M_u16	51370
ISDYNAASMsgTimeValidCount_Cnt_M_u16	53153
ISDYNAASMsgTimer_mS_M_u32	3768998144
ISDYNABRChkSumInvalidCount_Cnt_M_u16	41211
ISDYNABRChkSumValidCount_Cnt_M_u16	10273
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	37980
ISDYNABRMsgCountValidCount_Cnt_M_u16	4281
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	28109
ISDYNABRMsgLenValidCount_Cnt_M_u16	30875
ISDYNABRMsgTimeValidCount_Cnt_M_u16	2223
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	711

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1307
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	61158
ISDYNCMM208MsgTimer_mS_M_u32	52607232
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2695
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1413
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	35660
ISDYNCMM388MsgTimer_mS_M_u32	3353598208
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	23944
ISDYNVOLChkSumValidCount_Cnt_M_u16	20118
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	55065
ISDYNVOLMsgCountValidCount_Cnt_M_u16	350
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	51499
ISDYNVOLMsgLenValidCount_Cnt_M_u16	59160
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	21404
ISDYNVOLMsgTimer_mS_M_u32	3143473408
IgnOnTimer_mS_M_u32	3388463360
IgnTimeOff_Sec_M_u32	2896998717
ManVehSpd_Kph_M_f32	187.938507
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	43
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	227
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3251996928
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	191
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2542790912
PrevISDATBSI412MsgDLCError_Cnt_M_u08	97
PrevISDATBSI412MsgRxTime_MSec_M_u32	1269307648
PrevISDATBSI432MsgDLCError_Cnt_M_u08	190
PrevISDATBSI432MsgRxTime_MSec_M_u32	732297472
PrevISDATDIRAMsgTxTime_MSec_M_u32	1452022016
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	208
PrevISDYN2CMMMsgRxTime_MSec_M_u32	375138560
PrevISDYNAASMsgDLCError_Cnt_M_u08	235
PrevISDYNAASMsgRxTime_MSec_M_u32	3545471232
PrevISDYNABRMsgDLCError_Cnt_M_u08	37
PrevISDYNABRMsgRxTime_MSec_M_u32	214948096
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	60
PrevISDYNCMM208MsgRxTime_MSec_M_u32	449091840
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	40
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3870619904
PrevISDYNVOLMsgDLCError_Cnt_M_u08	44
PrevISDYNVOLMsgRxTime_MSec_M_u32	2249267456
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3699296512
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	209.673996
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	9450
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	26016
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	43695
VitesseVehicleBVRampValidCount_Cnt_M_u16	9509
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	38270
VitesseVehicleBVSigValidCount_Cnt_M_u16	24252

Name	Input Value
VitesseVehicleBV_Kph_M_f32	21.4605007
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	35660
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	35042
VitesseVehiculeRoues_Kph_M_f32	74.7287979
k_AASNTCEnableTimeout_mS_u16	5506
k_AASNodeAbsentDiag_Cnt_str.Threshold	48215
k_AASNodeAbsentDiag_Cnt_str.PStep	37147
k_AASNodeAbsentDiag_Cnt_str.NStep	38155
k_AASNodeAbsentTimeout_mS_u16	49917
k_AASNodeTimeout_mS_u16	27808
k_ABSNodeTimeout_mS_u16	13652
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	27159
k_ANGLEVOLANTSigValidThresh_Cnt_u16	47009
k_AngleVolantInvalidThresh_Cnt_u16	15492
k_AngleVolantValidThresh_Cnt_u16	65463
k_BSI552MsgTimeout_mS_u16	6021
k_BSINTCEnableTimeout_mS_u16	61576
k_BSINodeAbsentDiag_Cnt_str.Threshold	25852
k_BSINodeAbsentDiag_Cnt_str.PStep	34553
k_BSINodeAbsentDiag_Cnt_str.NStep	14958
k_BSINodeAbsentTimeout_mS_u16	54856
k_BSINodeTimeout_mS_u16	38130
k_BattOvHi_Volt_f32	18.2828999
k_BattOvLo_Volt_f32	5.5532999
k_BattUvHi_Volt_f32	26.1026993
k_BattUvLo_Volt_f32	20.7397995
k_CAVNTCEnableTimeout_mS_u16	21253
k_CAVNodeAbsentDiag_Cnt_str.Threshold	25273
k_CAVNodeAbsentDiag_Cnt_str.PStep	47232
k_CAVNodeAbsentDiag_Cnt_str.NStep	56034
k_CAVNodeAbsentTimeout_mS_u16	45723
k_CAVNodeTimeout_mS_u16	12286
k_CMM388MsgTimeout_mS_u16	33815
k_CMM388NTCEnableTimeout_mS_u16	3843
k_CMMNTCEnableTimeout_mS_u16	28574
k_CMMNodeAbsentDiag_Cnt_str.Threshold	21199
k_CMMNodeAbsentDiag_Cnt_str.PStep	57328
k_CMMNodeAbsentDiag_Cnt_str.NStep	61581
k_CMMNodeAbsentTimeout_mS_u16	45518
k_CONSANGLECPKMax_HwDeg_f32	256.19751
k_CONSANGLECPKMin_HwDeg_f32	-63.5433998
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	21068
k_CONSANGLECPKSigValidThresh_Cnt_u16	36834
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	16062
k_CPKVehicleSpeedValidThresh_Cnt_u16	60214
k_CityParkInputInvalidThresh_Cnt_u16	30105
k_CityParkInputValidThresh_Cnt_u16	46570
k_ComputerRazGCTSigValidThresh_Cnt_u16	20676
k_CptTemporelSigValidThresh_Cnt_u16	3046
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	46285
k_DMDFCTCPKSigValidThresh_Cnt_u16	65435
k_DMDFCTCPKValidCount_Cnt_u16	284
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	60126
k_DMDRELAXECPKSigValidThresh_Cnt_u16	52963
k_DMDRelaxeConsistentThresh_Cnt_u16	8961
k_DateValidThresh_Cnt_u16	9606
k_DefaultVehSpd_Kph_f32	186.7164
k_DiagMuxOnAbsentTimeout_mS_u16	24445
k_EMNodeTimeout_mS_u16	17739
k_ESPNTCEnableTimeout_mS_u16	43793
k_ESPNodeAbsentDiag_Cnt_str.Threshold	26091
k_ESPNodeAbsentDiag_Cnt_str.PStep	57632
k_ESPNodeAbsentDiag_Cnt_str.NStep	3958
k_ESPNodeAbsentTimeout_mS_u16	42742
k_EtatMTSigInvalidThresh_Cnt_u16	48702
k_EtatMTSigValidThresh_Cnt_u16	49572
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	43821
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	4486
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	1455
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	3519
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	7969
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	24379
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	13865

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	52531
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	59332
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	17059
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	19284
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	55260
k_ISDATDIRASentDiag_Cnt_str.Threshold	16715
k_ISDATDIRASentDiag_Cnt_str.PStep	40862
k_ISDATDIRASentDiag_Cnt_str.NStep	15667
k_ISDATDIRASentTimeout_mS_u16	21735
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	48333
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	55664
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	33101
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	26619
k_ISDYNAASChkSumValidThresh_Cnt_u16	12065
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	56156
k_ISDYNAASMsgCountValidThresh_Cnt_u16	38841
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	62479
k_ISDYNAASMsgLenValidThresh_Cnt_u16	48052
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	13001
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	30787
k_ISDYNABRChkSumValidThresh_Cnt_u16	36753
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	11764
k_ISDYNABRMsgCountValidThresh_Cnt_u16	33714
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	23196
k_ISDYNABRMsgLenValidThresh_Cnt_u16	29158
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	59861
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	37886
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	44844
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	22083
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	4921
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	17079
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	45199
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	57870
k_ISDYNVOLChkSumValidThresh_Cnt_u16	35936
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	10815
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	25141
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	55512
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	4306
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	10068
k_IgnOnTimeout_mS_u16	31226
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	17.5646
k_PowerCutVehSpdLowThresh_Kph_f32	86.1036987
k_PowerCutVehSpdLowTimeout_mS_u16	30878
k_VBattMaxAAS_Volt_f32	27.7731991
k_VBattMaxBSI_Volt_f32	28.9808006
k_VBattMaxCAV_Volt_f32	27.6236
k_VBattMaxCMM388_Volt_f32	1.37010002
k_VBattMaxCMM_Volt_f32	15.7588997
k_VBattMaxESP_Volt_f32	1.42149997
k_VBattMinAAS_Volt_f32	14.9902
k_VBattMinBSI_Volt_f32	1.42149997
k_VBattMinCAV_Volt_f32	9.72659969
k_VBattMinCMM388_Volt_f32	1.30649996
k_VBattMinCMM_Volt_f32	16.9862995
k_VBattMinESP_Volt_f32	15.7588997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	6575
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	38513
k_VitesseVehicleBVRampValidThresh_Cnt_u16	40473
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	54678
k_VitesseVehicleBVSigValidThresh_Cnt_u16	16007
k_VitesseVehicleBVSpeedPassThresh_kph_f32	419.270111
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	18981
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	37147
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2394831104
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	198
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	51805
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1128655616
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	40
target_SrlComInput_Per1_Batt_Volt_f32.value	25.4526997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4151339264
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	33
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.115927912
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2901006592
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2999089408
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1747654912
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3039017216
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2175555840
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3049584896
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	963483904
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	83
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	155
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	189
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	190
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	238
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	214
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3033053440
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	463001856
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2263972096
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1641683200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2078927104
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1800
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.358858287
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	463508
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	163.508194

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	32076		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	48215	48215	✔
AASNodeAbsentTimer_mS_M_u32	1128655616	1128655616	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1128655616	1128655616	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	270.146301	270.146301	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	25852	25852	✔
BSINodeAbsentTimer_mS_M_u32	1128655616	1128655616	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1128655616	1128655616	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1128655616	1128655616	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	2223	2223	✔
CONSANGLECPK_HwDeg_M_f32	90.0199966	90.0199966 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1128655616	1128655616	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1128655616	1128655616	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1128655616	1128655616	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1128655616	1128655616	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1128655616	1128655616	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1128655616	1128655616	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1128655616	1128655616	✔
ESPNTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	26091	26091	✔
ESPNodeAbsentTimer_mS_M_u32	1128655616	1128655616	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	102	102	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	106	106	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1128655616	1128655616	✔
ElecIntTimer_mS_M_u32[1]	1151	1151	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1128655616	1128655616	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1128655616	1128655616	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1128655616	1128655616	✔
IgnOnTimer_mS_M_u32	3388463360	3388463360	✔
IgnTimeOff_Sec_M_u32	2896998717	2896998717	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	43	43	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2901006592	2901006592	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	144	144	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2999089408	2999089408	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	49	49	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1747654912	1747654912	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	245	245	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3039017216	3039017216	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1452022016	1452022016	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	136	136	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3049584896	3049584896	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	39	39	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	963483904	963483904	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	214	214	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3033053440	3033053440	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	143	143	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	463001856	463001856	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	121	121	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2263972096	2263972096	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	95	95	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1641683200	1641683200	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2078927104	2078927104	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	209.673996	209.673996	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	21.4605007	21.4605007	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	74.7287979	74.7287979	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	270.146301	270.146301	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	2223	2223	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2896998717	2896998717	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	90.0199966	90.0199966 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.112 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2118805504
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	24764
AASNodeAbsentTimer_mS_M_u32	3416512512
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	23893
ANGLEVOLANTSigValidCount_Cnt_M_u16	57756
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	12209
AngleVolantMsgTimer_mS_M_u32	2118805504
AngleVolantValidCount_Cnt_M_u16	510
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	738.388
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3157104640
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4085782528
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1780746240
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2097465344
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	47396
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1933084672
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	61202
CAVNodeAbsentTimer_mS_M_u32	217151488
CDD_SrlComVehSpd_Kph_G_f32	276.772888
CMM388NTCEnableTimer_mS_M_u32	940816384
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2174187520
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	17773
CMMNodeAbsentTimer_mS_M_u32	4208904192
CONSANGLECPKSigInvalidCount_Cnt_M_u16	61131
CONSANGLECPKSigValidCount_Cnt_M_u16	5090
CONSANGLECPK_Cnt_M_u16	35253
CONSANGLECPK_HwDeg_M_f32	-217.688507
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	35253
CPKVehicleSpeedMsgTimer_mS_M_u32	4019283968
CPKVehicleSpeedValidCount_Cnt_M_u16	21212

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	19650
CityParkInputInvalidCount_Cnt_M_u16	61533
CityParkInputMsgTimer_mS_M_u32	2901006592
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3345471488
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	37248
ComputerRazGCTSigInvalidTimer_mS_M_u32	1223555072
ComputerRazGCTSigValidCount_Cnt_M_u16	5807
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	41369
DMDFCTCPKSigValidCount_Cnt_M_u16	47880
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	41399
DMDRELAXECPKSigValidCount_Cnt_M_u16	2942
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	11968
DateInvalidTimer_mS_M_u32	4085782528
DiagMuxOnAbsentTimer_mS_M_u32	1281239040
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2097465344
ESPNTCEnableTimer_mS_M_u32	3827095552
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	16976
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	89
EffacDefaultDiagTimer_mS_M_u32[1]	3409510912
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	64
ElecIntTimer_mS_M_u32[1]	895
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2667218944
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	24956
EtatMTSigValidCount_Cnt_M_u16	18255
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	55597
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	25540
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	39342
ISDAT4V2BSI552MsgTimer_mS_M_u32	27445248
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	7791
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	46922
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	18255
ISDATBSI3F2MsgTimer_mS_M_u32	3120310272
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	28747
ISDATBSI412MsgLenValidCount_Cnt_M_u16	41430
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	24956
ISDATBSI412MsgTimer_mS_M_u32	1105750016
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	38705
ISDATBSI432MsgLenValidCount_Cnt_M_u16	7956
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	11691
ISDATDIRASentFltAcc_Cnt_M_u16	17919
ISDATDIRASentTimer_mS_M_u32	4019283968
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	37331
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	510
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	35560
ISDYN2CMMMsgTimer_mS_M_u32	2323044352
ISDYNAASChkSumInvalidCount_Cnt_M_u16	20766
ISDYNAASChkSumValidCount_Cnt_M_u16	41349
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	16717
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	14117
ISDYNAASMsgLenValidCount_Cnt_M_u16	19780
ISDYNAASMsgTimeValidCount_Cnt_M_u16	20766
ISDYNAASMsgTimer_mS_M_u32	1179629568
ISDYNABRChkSumInvalidCount_Cnt_M_u16	48783
ISDYNABRChkSumValidCount_Cnt_M_u16	7134
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	44781
ISDYNABRMsgCountValidCount_Cnt_M_u16	3220
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	30618
ISDYNABRMsgLenValidCount_Cnt_M_u16	59889
ISDYNABRMsgTimeValidCount_Cnt_M_u16	35253

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	712
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1309
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	18255
ISDYNCMM208MsgTimer_mS_M_u32	3361380352
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2699
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1415
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	54428
ISDYNCMM388MsgTimer_mS_M_u32	1721186304
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	21609
ISDYNVOLChkSumValidCount_Cnt_M_u16	5120
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	29239
ISDYNVOLMsgCountValidCount_Cnt_M_u16	26150
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	48001
ISDYNVOLMsgLenValidCount_Cnt_M_u16	29816
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	17773
ISDYNVOLMsgTimer_mS_M_u32	2737436672
IgnOnTimer_mS_M_u32	2958768128
IgnTimeOff_Sec_M_u32	74483039
ManVehSpd_Kph_M_f32	138.701202
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	45
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	65
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2608998400
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	76
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2077427712
PrevISDATBSI412MsgDLCError_Cnt_M_u08	38
PrevISDATBSI412MsgRxTime_MSec_M_u32	1011513344
PrevISDATBSI432MsgDLCError_Cnt_M_u08	12
PrevISDATBSI432MsgRxTime_MSec_M_u32	1808848896
PrevISDATDIRAMsgTxTime_MSec_M_u32	2879289344
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	90
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2154711040
PrevISDYNAASMsgDLCError_Cnt_M_u08	8
PrevISDYNAASMsgRxTime_MSec_M_u32	3007838208
PrevISDYNABRMsgDLCError_Cnt_M_u08	164
PrevISDYNABRMsgRxTime_MSec_M_u32	1205024768
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	127
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3774150656
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	245
PrevISDYNCMM388MsgRxTime_MSec_M_u32	916707328
PrevISDYNVOLMsgDLCError_Cnt_M_u08	147
PrevISDYNVOLMsgRxTime_MSec_M_u32	1896839168
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2156292096
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	435.635101
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	24003
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	52834
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	8308
VitesseVehicleBVRampValidCount_Cnt_M_u16	58323
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	21894

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	19597
VitesseVehicleBV_Kph_M_f32	208.052795
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	54428
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	36506
VitesseVehiculeRoues_Kph_M_f32	180.285095
k_AASNTCEnableTimeout_mS_u16	28476
k_AASNodeAbsentDiag_Cnt_str.Threshold	1842
k_AASNodeAbsentDiag_Cnt_str.PStep	11937
k_AASNodeAbsentDiag_Cnt_str.NStep	12999
k_AASNodeAbsentTimeout_mS_u16	12681
k_AASNodeTimeout_mS_u16	47458
k_ABSNodeTimeout_mS_u16	902
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	44540
k_ANGLEVOLANTSigValidThresh_Cnt_u16	18463
k_AngleVolantInvalidThresh_Cnt_u16	1398
k_AngleVolantValidThresh_Cnt_u16	61533
k_BSI552MsgTimeout_mS_u16	11953
k_BSINTCEnableTimeout_mS_u16	7849
k_BSINodeAbsentDiag_Cnt_str.Threshold	25892
k_BSINodeAbsentDiag_Cnt_str.PStep	34536
k_BSINodeAbsentDiag_Cnt_str.NStep	14981
k_BSINodeAbsentTimeout_mS_u16	39209
k_BSINodeTimeout_mS_u16	11691
k_BattOvHi_Volt_f32	29.9890995
k_BattOvLo_Volt_f32	30.5678997
k_BattUvHi_Volt_f32	28.1751003
k_BattUvLo_Volt_f32	24.3005009
k_CAVNTCEnableTimeout_mS_u16	44659
k_CAVNodeAbsentDiag_Cnt_str.Threshold	17511
k_CAVNodeAbsentDiag_Cnt_str.PStep	7689
k_CAVNodeAbsentDiag_Cnt_str.NStep	37401
k_CAVNodeAbsentTimeout_mS_u16	47280
k_CAVNodeTimeout_mS_u16	13575
k_CMM388MsgTimeout_mS_u16	35772
k_CMM388NTCEnableTimeout_mS_u16	39672
k_CMMNTCEnableTimeout_mS_u16	8679
k_CMMNodeAbsentDiag_Cnt_str.Threshold	18093
k_CMMNodeAbsentDiag_Cnt_str.PStep	36353
k_CMMNodeAbsentDiag_Cnt_str.NStep	27938
k_CMMNodeAbsentTimeout_mS_u16	50134
k_CONSANGLECPKMax_HwDeg_f32	317.518494
k_CONSANGLECPKMin_HwDeg_f32	-419.30661
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	32668
k_CONSANGLECPKSigValidThresh_Cnt_u16	31130
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	15112
k_CPKVehicleSpeedValidThresh_Cnt_u16	24606
k_CityParkInputInvalidThresh_Cnt_u16	14517
k_CityParkInputValidThresh_Cnt_u16	19650
k_ComputerRazGCTSigValidThresh_Cnt_u16	38517
k_CptTemporelSigValidThresh_Cnt_u16	18384
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	41626
k_DMDFCTCPKSigValidThresh_Cnt_u16	21745
k_DMDFCTCPKValidCount_Cnt_u16	2732
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	35560
k_DMDRELAXECPKSigValidThresh_Cnt_u16	20887
k_DMDRelaxeConsistentThresh_Cnt_u16	19773
k_DateValidThresh_Cnt_u16	39342
k_DefaultVehSpd_Kph_f32	16.3614998
k_DiagMuxOnAbsentTimeout_mS_u16	15691
k_EMNodeTimeout_mS_u16	26912
k_ESPNTCEnableTimeout_mS_u16	10062
k_ESPNodeAbsentDiag_Cnt_str.Threshold	56759
k_ESPNodeAbsentDiag_Cnt_str.PStep	47057
k_ESPNodeAbsentDiag_Cnt_str.NStep	45767
k_ESPNodeAbsentTimeout_mS_u16	33886
k_EtatMTSigInvalidThresh_Cnt_u16	12998
k_EtatMTSigValidThresh_Cnt_u16	6997
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	29115
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	366
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	45427
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	2948
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	47647
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	22543

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	4550
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	53097
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	10485
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	43993
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	46212
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	811
k_ISDATDIRASentDiag_Cnt_str.Threshold	47919
k_ISDATDIRASentDiag_Cnt_str.PStep	26416
k_ISDATDIRASentDiag_Cnt_str.NStep	62887
k_ISDATDIRASentTimeout_mS_u16	21195
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	22616
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	12209
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	38042
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	27023
k_ISDYNAASChkSumValidThresh_Cnt_u16	1758
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	55789
k_ISDYNAASMsgCountValidThresh_Cnt_u16	30612
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	5459
k_ISDYNAASMsgLenValidThresh_Cnt_u16	7206
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	30375
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	45112
k_ISDYNABRChkSumValidThresh_Cnt_u16	64783
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	58404
k_ISDYNABRMsgCountValidThresh_Cnt_u16	13739
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	12397
k_ISDYNABRMsgLenValidThresh_Cnt_u16	27984
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	20290
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	24711
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	27708
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	18553
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	34901
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	19612
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	15829
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	56214
k_ISDYNVOLChkSumValidThresh_Cnt_u16	32609
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	59461
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	48546
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	63160
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	37259
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	19524
k_IgnOnTimeout_mS_u16	50130
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	88.3170013
k_PowerCutVehSpdLowThresh_Kph_f32	0
k_PowerCutVehSpdLowTimeout_mS_u16	46568
k_VBattMaxAAS_Volt_f32	9.81649971
k_VBattMaxBSI_Volt_f32	26.8833008
k_VBattMaxCAV_Volt_f32	19.5142994
k_VBattMaxCMM388_Volt_f32	15.8393002
k_VBattMaxCMM_Volt_f32	29.4885006
k_VBattMaxESP_Volt_f32	7.4994998
k_VBattMinAAS_Volt_f32	5.20760012
k_VBattMinBSI_Volt_f32	1.23559999
k_VBattMinCAV_Volt_f32	7.55970001
k_VBattMinCMM388_Volt_f32	28.7595997
k_VBattMinCMM_Volt_f32	7.59800005
k_VBattMinESP_Volt_f32	29.4885006
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	18866
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	13869
k_VitesseVehicleBVRampValidThresh_Cnt_u16	7479
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	32512
k_VitesseVehicleBVSigValidThresh_Cnt_u16	26347
k_VitesseVehicleBVSpeedPassThresh_kph_f32	558.689514
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	39442
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	63473
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4085782528
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	96
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	9514
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3409510912
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	245
target_SrlComInput_Per1_Batt_Volt_f32.value	5.58069992
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2117175296
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	94
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.802472651
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1334130688
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	50
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3900397568
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2999023616
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4132935680
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4215126016
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	244
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	158586880
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	226
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1761212416
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	81
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	119
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	214
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	223
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3412629504
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	85
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	117
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	180
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	197
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	199
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2138585088
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3891156992
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	10
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1102346240
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3066365952
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3447
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.114501536
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	593864
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	28.7362003
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	23709

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3409510912	3409510912	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3409510912	3409510912	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	738.388	738.388	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3157104640	3157104640	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1780746240	1780746240	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	2097465344	2097465344	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	25892	25892	✔
BSINodeAbsentTimer_mS_M_u32	3409510912	3409510912	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	17511	17511	✔
CAVNodeAbsentTimer_mS_M_u32	3409510912	3409510912	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	158586880	158586880	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	35253	35253	✔
CONSANGLECPK_HwDeg_M_f32	-217.688507	-217.688507 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3409510912	3409510912	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3409510912	3409510912	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3409510912	3409510912	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3409510912	3409510912	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3409510912	3409510912	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3409510912	3409510912	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3409510912	3409510912	✔
ESPNTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3409510912	3409510912	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	89	89	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3409510912	3409510912	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3409510912	3409510912	✔
ElecIntTimer_mS_M_u32[1]	895	895	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3409510912	3409510912	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1334130688	1334130688	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3900397568	3900397568	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4132935680	4132935680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3409510912	3409510912	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3409510912	3409510912	✔
IgnOnTimer_mS_M_u32	2958768128	2958768128	✔
IgnTimeOff_Sec_M_u32	74483039	74483039	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	215	215	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1334130688	1334130688	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	50	50	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3900397568	3900397568	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	26	26	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2999023616	2999023616	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	216	216	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4132935680	4132935680	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2879289344	2879289344	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	244	244	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	158586880	158586880	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	226	226	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1761212416	1761212416	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	8	8	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3412629504	3412629504	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	39	39	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2138585088	2138585088	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	242	242	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3891156992	3891156992	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	10	10	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1102346240	1102346240	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3066365952	3066365952	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	435.635101	435.635101	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	208.052795	208.052795	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	180.285095	180.285095	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	738.388	738.388	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	35253	35253	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	74483039	74483039	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-217.688507	-217.688507 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	16.3614998	16.3614998	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.113 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3563031296
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	5896
AASNodeAbsentTimer_mS_M_u32	1578318592
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	9022
ANGLEVOLANTSigValidCount_Cnt_M_u16	40489
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	48681
AngleVolantMsgTimer_mS_M_u32	3563031296
AngleVolantValidCount_Cnt_M_u16	8132
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	241.590576
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3816160000
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3345382144
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	4283607808
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	967863040
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	3025
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3591711488
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	19079
CAVNodeAbsentTimer_mS_M_u32	1487559424
CDD_SrlComVehSpd_Kph_G_f32	260.577606
CMM388NTCEnableTimer_mS_M_u32	809736960

Name	Input Value
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	314071808
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	61493
CMMNodeAbsentTimer_mS_M_u32	2820827904
CONSANGLECPKSigInvalidCount_Cnt_M_u16	30173
CONSANGLECPKSigValidCount_Cnt_M_u16	20056
CONSANGLECPK_Cnt_M_u16	63711
CONSANGLECPK_HwDeg_M_f32	-268.759003
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	63711
CPKVehicleSpeedMsgTimer_mS_M_u32	1552583424
CPKVehicleSpeedValidCount_Cnt_M_u16	13714
CityParkInputConsistentCount_Cnt_M_u16	20344
CityParkInputInvalidCount_Cnt_M_u16	57766
CityParkInputMsgTimer_mS_M_u32	1334130688
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2059877120
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	38076
ComputerRazGCTSigInvalidTimer_mS_M_u32	917822208
ComputerRazGCTSigValidCount_Cnt_M_u16	58801
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	48626
DMDFCTCPKSigValidCount_Cnt_M_u16	6502
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	24088
DMDRELAXECPKSigValidCount_Cnt_M_u16	10371
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	51710
DateInvalidTimer_mS_M_u32	3345382144
DiagMuxOnAbsentTimer_mS_M_u32	1763986176
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	967863040
ESPNTCEnableTimer_mS_M_u32	950549248
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	29004
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	56
EffacDefaultDiagTimer_mS_M_u32[1]	456
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	2155592960
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3671010048
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	59655
EtatMTSigValidCount_Cnt_M_u16	28495
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	48823
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	26290
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	38260
ISDAT4V2BSI552MsgTimer_mS_M_u32	2748738304
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	62384
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	32991
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	28495
ISDATBSI3F2MsgTimer_mS_M_u32	407522048
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	48923
ISDATBSI412MsgLenValidCount_Cnt_M_u16	16955
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	59655
ISDATBSI412MsgTimer_mS_M_u32	2173012736
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	2793
ISDATBSI432MsgLenValidCount_Cnt_M_u16	60160
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	12988
ISDATDIRASentFltAcc_Cnt_M_u16	14784
ISDATDIRASentTimer_mS_M_u32	1552583424
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	55429
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	8132
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	65029
ISDYN2CMMMsgTimer_mS_M_u32	765082368
ISDYNAASChkSumInvalidCount_Cnt_M_u16	19938
ISDYNAASChkSumValidCount_Cnt_M_u16	58477
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	24023

Name	Input Value
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	32334
ISDYNAASMsgLenValidCount_Cnt_M_u16	41905
ISDYNAASMsgTimeValidCount_Cnt_M_u16	19938
ISDYNAASMsgTimer_mS_M_u32	4119829248
ISDYNABRChkSumInvalidCount_Cnt_M_u16	24847
ISDYNABRChkSumValidCount_Cnt_M_u16	28898
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	12405
ISDYNABRMsgCountValidCount_Cnt_M_u16	40768
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	55152
ISDYNABRMsgLenValidCount_Cnt_M_u16	51243
ISDYNABRMsgTimeValidCount_Cnt_M_u16	63711
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	713
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1311
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	28495
ISDYNCMM208MsgTimer_mS_M_u32	3002006272
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2703
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1417
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	40938
ISDYNCMM388MsgTimer_mS_M_u32	314120960
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	15619
ISDYNVOLChkSumValidCount_Cnt_M_u16	17918
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	17432
ISDYNVOLMsgCountValidCount_Cnt_M_u16	4108
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	2489
ISDYNVOLMsgLenValidCount_Cnt_M_u16	42644
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	61493
ISDYNVOLMsgTimer_mS_M_u32	402709248
IgnOnTimer_mS_M_u32	1164778240
IgnTimeOff_Sec_M_u32	569664215
ManVehSpd_Kph_M_f32	433.152191
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	47
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	254
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	196627200
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	254
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1178970880
PrevISDATBSI412MsgDLCError_Cnt_M_u08	48
PrevISDATBSI412MsgRxTime_MSec_M_u32	1855937280
PrevISDATBSI432MsgDLCError_Cnt_M_u08	127
PrevISDATBSI432MsgRxTime_MSec_M_u32	1905015552
PrevISDATDIRAMsgTxTime_MSec_M_u32	1889753856
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	14
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3044272896
PrevISDYNAASMsgDLCError_Cnt_M_u08	1
PrevISDYNAASMsgRxTime_MSec_M_u32	3752254208
PrevISDYNABRMsgDLCError_Cnt_M_u08	80
PrevISDYNABRMsgRxTime_MSec_M_u32	1594170112
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	95
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1251990272
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	72
PrevISDYNCMM388MsgRxTime_MSec_M_u32	487799552
PrevISDYNVOLMsgDLCError_Cnt_M_u08	119
PrevISDYNVOLMsgRxTime_MSec_M_u32	609245952
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3182136064
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	424.94809
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0

Name	Input Value
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	628
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	6231
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	48737
VitesseVehicleBVRampValidCount_Cnt_M_u16	56324
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	16043
VitesseVehicleBVSigValidCount_Cnt_M_u16	24918
VitesseVehicleBV_Kph_M_f32	202.663696
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	40938
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	22957
VitesseVehiculeRoues_Kph_M_f32	546.195313
k_AASNTCEnableTimeout_mS_u16	9290
k_AASNodeAbsentDiag_Cnt_str.Threshold	38654
k_AASNodeAbsentDiag_Cnt_str.PStep	3977
k_AASNodeAbsentDiag_Cnt_str.NStep	45871
k_AASNodeAbsentTimeout_mS_u16	32035
k_AASNodeTimeout_mS_u16	22359
k_ABSNodeTimeout_mS_u16	35883
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	45704
k_ANGLEVOLANTSigValidThresh_Cnt_u16	23519
k_AngleVolantInvalidThresh_Cnt_u16	16346
k_AngleVolantValidThresh_Cnt_u16	57766
k_BSI552MsgTimeout_mS_u16	38248
k_BSINTCEnableTimeout_mS_u16	21633
k_BSINodeAbsentDiag_Cnt_str.Threshold	25932
k_BSINodeAbsentDiag_Cnt_str.PStep	34519
k_BSINodeAbsentDiag_Cnt_str.NStep	15004
k_BSINodeAbsentTimeout_mS_u16	25025
k_BSINodeTimeout_mS_u16	12988
k_BattOvHi_Volt_f32	29.4316006
k_BattOvLo_Volt_f32	10.5247002
k_BattUvHi_Volt_f32	2.43700004
k_BattUvLo_Volt_f32	8.95090008
k_CAVNTCEnableTimeout_mS_u16	32612
k_CAVNodeAbsentDiag_Cnt_str.Threshold	44633
k_CAVNodeAbsentDiag_Cnt_str.PStep	28811
k_CAVNodeAbsentDiag_Cnt_str.NStep	25265
k_CAVNodeAbsentTimeout_mS_u16	58797
k_CAVNodeTimeout_mS_u16	37673
k_CMM388MsgTimeout_mS_u16	38408
k_CMM388NTCEnableTimeout_mS_u16	22612
k_CMMNTCEnableTimeout_mS_u16	51528
k_CMMNodeAbsentDiag_Cnt_str.Threshold	20463
k_CMMNodeAbsentDiag_Cnt_str.PStep	36298
k_CMMNodeAbsentDiag_Cnt_str.NStep	40318
k_CMMNodeAbsentTimeout_mS_u16	43513
k_CONSANGLECPKMax_HwDeg_f32	88.5089035
k_CONSANGLECPKMin_HwDeg_f32	-406.872406
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	40682
k_CONSANGLECPKSigValidThresh_Cnt_u16	39085
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	60005
k_CPKVehicleSpeedValidThresh_Cnt_u16	64418
k_CityParkInputInvalidThresh_Cnt_u16	2717
k_CityParkInputValidThresh_Cnt_u16	20344
k_ComputerRazGCTSigValidThresh_Cnt_u16	9118
k_CptTemporelSigValidThresh_Cnt_u16	26445
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	22128
k_DMDFCTCPKSigValidThresh_Cnt_u16	34603
k_DMDFCTCPKValidCount_Cnt_u16	14137
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	65029
k_DMDRELAXECPKSigValidThresh_Cnt_u16	20921
k_DMDRelaxeConsistentThresh_Cnt_u16	30407
k_DateValidThresh_Cnt_u16	38260
k_DefaultVehSpd_Kph_f32	142.660797
k_DiagMuxOnAbsentTimeout_mS_u16	46621
k_EMNodeTimeout_mS_u16	39646

Name	Input Value
k_ESPNTCEnableTimeout_mS_u16	37331
k_ESPNodeAbsentDiag_Cnt_str.Threshold	39344
k_ESPNodeAbsentDiag_Cnt_str.PStep	2105
k_ESPNodeAbsentDiag_Cnt_str.NStep	25968
k_ESPNodeAbsentTimeout_mS_u16	34913
k_EtatMTSigInvalidThresh_Cnt_u16	41066
k_EtatMTSigValidThresh_Cnt_u16	3709
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	53836
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	56051
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	9573
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	49265
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	3168
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	6095
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	12074
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	28161
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	26013
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	8819
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	41010
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	55163
k_ISDATDIRASentDiag_Cnt_str.Threshold	4736
k_ISDATDIRASentDiag_Cnt_str.PStep	39317
k_ISDATDIRASentDiag_Cnt_str.NStep	39046
k_ISDATDIRASentTimeout_mS_u16	37979
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	52212
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	48681
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	31215
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	24591
k_ISDYNAASChkSumValidThresh_Cnt_u16	45026
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	44917
k_ISDYNAASMsgCountValidThresh_Cnt_u16	24128
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	27843
k_ISDYNAASMsgLenValidThresh_Cnt_u16	16139
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	61511
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	9622
k_ISDYNABRChkSumValidThresh_Cnt_u16	34513
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	35537
k_ISDYNABRMsgCountValidThresh_Cnt_u16	40444
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	12085
k_ISDYNABRMsgLenValidThresh_Cnt_u16	61516
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	27959
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	2600
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	53064
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	50706
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	41534
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	23849
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	55614
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	26938
k_ISDYNVOLChkSumValidThresh_Cnt_u16	38298
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	37741
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	39830
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	6483
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	32923
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	21938
k_IgnOnTimeout_mS_u16	41094
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	209.294098
k_PowerCutVehSpdLowThresh_Kph_f32	255
k_PowerCutVehSpdLowTimeout_mS_u16	70
k_VBattMaxAAS_Volt_f32	4.80660009
k_VBattMaxBSI_Volt_f32	23.5379009
k_VBattMaxCAV_Volt_f32	13.9661999
k_VBattMaxCMM388_Volt_f32	8.29800034
k_VBattMaxCMM_Volt_f32	27.9041004
k_VBattMaxESP_Volt_f32	24.8740005
k_VBattMinAAS_Volt_f32	15.5073996
k_VBattMinBSI_Volt_f32	1.23559999
k_VBattMinCAV_Volt_f32	15.7665005
k_VBattMinCMM388_Volt_f32	30.3486004
k_VBattMinCMM_Volt_f32	16.1993999
k_VBattMinESP_Volt_f32	27.9041004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	57318
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	62005
k_VitesseVehicleBVRampValidThresh_Cnt_u16	17176

Name	Input Value
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	1278
k_VitesseVehicleBVSigValidThresh_Cnt_u16	58621
k_VitesseVehicleBVSpeedPassThresh_kph_f32	425.617188
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	18823
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	38826
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3345382144
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	56
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	34046
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2155592960
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	72
target_SrlComInput_Per1_Batt_Volt_f32.value	9.60099983
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3643419392
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	32
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.73825866
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2414811904
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3314334464
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2805619456
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1559755520
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	247831296
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	250
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3835902720
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	110156544
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	20
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	41
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	64
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	91
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	193
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1640299264
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	64
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	65
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	90
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	176
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	183
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	140
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2350258944
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	140
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1395899136
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	228
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2254527232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	77

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	101
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3715083008
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3051
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.138628677
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	560882
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	21.2865009
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	60902

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	38654	38654	✔
AASNodeAbsentTimer_mS_M_u32	2155592960	2155592960	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2155592960	2155592960	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	241.590576	241.590576	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3816160000	3816160000	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	3345382144	3345382144	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	967863040	967863040	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	25932	25932	✔
BSINodeAbsentTimer_mS_M_u32	2155592960	2155592960	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2155592960	2155592960	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2155592960	2155592960	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	63711	63711	✔
CONSANGLECPK_HwDeg_M_f32	-268.759003	-268.759003 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2155592960	2155592960	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2155592960	2155592960	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2155592960	2155592960	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2155592960	2155592960	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2155592960	2155592960	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2155592960	2155592960	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2155592960	2155592960	✔
ESPNTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	39344	39344	✔
ESPNodeAbsentTimer_mS_M_u32	2155592960	2155592960	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2155592960	2155592960	✔
EffacDefaultDiagTimer_mS_M_u32[1]	456	456	✔
ElecIntCount_Cnt_M_u08	2	2	✔
ElecIntTimer_mS_M_u32[0]	97	97	✔
ElecIntTimer_mS_M_u32[1]	2155592960	2155592960	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2155592960	2155592960	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2414811904	2414811904	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3314334464	3314334464	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2805619456	2805619456	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2155592960	2155592960	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2155592960	2155592960	✔
IgnOnTimer_mS_M_u32	1164778240	1164778240	✔
IgnTimeOff_Sec_M_u32	569664215	569664215	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	241	241	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2414811904	2414811904	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	63	63	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3314334464	3314334464	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2805619456	2805619456	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	205	205	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1559755520	1559755520	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1889753856	1889753856	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	250	250	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3835902720	3835902720	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	209	209	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	110156544	110156544	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	193	193	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1640299264	1640299264	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	140	140	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2350258944	2350258944	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	140	140	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1395899136	1395899136	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	228	228	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2254527232	2254527232	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3715083008	3715083008	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	424.94809	424.94809	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	202.663696	202.663696	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	546.195313	546.195313	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	241.590576	241.590576	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	63711	63711	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	569664215	569664215	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-268.759003	-268.759003 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	142.660797	142.660797	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.114 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	107749888
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	32882
AASNodeAbsentTimer_mS_M_u32	336663040
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	21967
ANGLEVOLANTSigValidCount_Cnt_M_u16	52685
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	20239
AngleVolantMsgTimer_mS_M_u32	107749888
AngleVolantValidCount_Cnt_M_u16	41148
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	64.5234146
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2129187328
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	890720768
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3121791488
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2985918976
BSI552NTCsEnabled_Cnt_M_lgc	1

Name	Input Value
BSINodeAbsentFltAcc_Cnt_M_u16	43030
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1607156224
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	19061
CAVNodeAbsentTimer_mS_M_u32	3905663488
CDD_SrlComVehSpd_Kph_G_f32	174.041794
CMM388NTCEnableTimer_mS_M_u32	1459614208
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1923199488
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	24361
CMMNodeAbsentTimer_mS_M_u32	2929951232
CONSANGLECPKSigInvalidCount_Cnt_M_u16	18674
CONSANGLECPKSigValidCount_Cnt_M_u16	59457
CONSANGLECPK_Cnt_M_u16	50348
CONSANGLECPK_HwDeg_M_f32	-412.522186
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	50348
CPKVehicleSpeedMsgTimer_mS_M_u32	3656065536
CPKVehicleSpeedValidCount_Cnt_M_u16	58906
CityParkInputConsistentCount_Cnt_M_u16	57760
CityParkInputInvalidCount_Cnt_M_u16	46102
CityParkInputMsgTimer_mS_M_u32	2414811904
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2381648384
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	55126
ComputerRazGCTSigInvalidTimer_mS_M_u32	2561421824
ComputerRazGCTSigValidCount_Cnt_M_u16	17141
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	20274
DMDFCTCPKSigValidCount_Cnt_M_u16	17816
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	36161
DMDRELAXECPKSigValidCount_Cnt_M_u16	5823
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	4239
DateInvalidTimer_mS_M_u32	890720768
DiagMuxOnAbsentTimer_mS_M_u32	1260249600
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2985918976
ESPNTCEnableTimer_mS_M_u32	408031744
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	29860
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	99
EffacDefaultDiagTimer_mS_M_u32[1]	759
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	8
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3114091008
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	36275
EtatMTSigValidCount_Cnt_M_u16	21405
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	22116
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	34611
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	35182
ISDAT4V2BSI552MsgTimer_mS_M_u32	2340913664
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	43320
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	64107
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	21405
ISDATBSI3F2MsgTimer_mS_M_u32	1437327872
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1014
ISDATBSI412MsgLenValidCount_Cnt_M_u16	13145
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	36275
ISDATBSI412MsgTimer_mS_M_u32	385491456
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	57101
ISDATBSI432MsgLenValidCount_Cnt_M_u16	55176
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	42454
ISDATDIRASentFltAcc_Cnt_M_u16	41162

Name	Input Value
ISDATDIRASentTimer_mS_M_u32	3656065536
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	15802
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	41148
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	39673
ISDYN2CMMMsgTimer_mS_M_u32	2172391936
ISDYNAASChkSumInvalidCount_Cnt_M_u16	50148
ISDYNAASChkSumValidCount_Cnt_M_u16	26883
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	62083
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	35616
ISDYNAASMsgLenValidCount_Cnt_M_u16	58294
ISDYNAASMsgTimeValidCount_Cnt_M_u16	50148
ISDYNAASMsgTimer_mS_M_u32	924578304
ISDYNABRChkSumInvalidCount_Cnt_M_u16	30684
ISDYNABRChkSumValidCount_Cnt_M_u16	53538
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	10283
ISDYNABRMsgCountValidCount_Cnt_M_u16	17546
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	12345
ISDYNABRMsgLenValidCount_Cnt_M_u16	34504
ISDYNABRMsgTimeValidCount_Cnt_M_u16	50348
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	714
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1313
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	21405
ISDYNCMM208MsgTimer_mS_M_u32	880660992
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2707
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1419
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	14410
ISDYNCMM388MsgTimer_mS_M_u32	1704948224
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	2944
ISDYNVOLChkSumValidCount_Cnt_M_u16	6479
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	54464
ISDYNVOLMsgCountValidCount_Cnt_M_u16	31142
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	40797
ISDYNVOLMsgLenValidCount_Cnt_M_u16	29067
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	24361
ISDYNVOLMsgTimer_mS_M_u32	617099776
IgnOnTimer_mS_M_u32	2642637312
IgnTimeOff_Sec_M_u32	506195260
ManVehSpd_Kph_M_f32	381.240601
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	49
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	49
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3009536512
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	206
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1899610624
PrevISDATBSI412MsgDLCError_Cnt_M_u08	242
PrevISDATBSI412MsgRxTime_MSec_M_u32	3136074240
PrevISDATBSI432MsgDLCError_Cnt_M_u08	0
PrevISDATBSI432MsgRxTime_MSec_M_u32	4255519232
PrevISDATDIRAMsgTxTime_MSec_M_u32	3303059968
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	229
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2897150464
PrevISDYNAASMsgDLCError_Cnt_M_u08	25
PrevISDYNAASMsgRxTime_MSec_M_u32	3856019968
PrevISDYNABRMsgDLCError_Cnt_M_u08	196
PrevISDYNABRMsgRxTime_MSec_M_u32	2965074432
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	182
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3370856960
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	25
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3608220160
PrevISDYNVOLMsgDLCError_Cnt_M_u08	113
PrevISDYNVOLMsgRxTime_MSec_M_u32	2648289792
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2055741952
PrevModeDiag_Cnt_M_u08	0

Name	Input Value
PrevSrlComVehSpd_Kph_M_f32	383.419403
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	5806
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	40388
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	55015
VitesseVehicleBVRampValidCount_Cnt_M_u16	18109
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	63368
VitesseVehicleBVSigValidCount_Cnt_M_u16	30790
VitesseVehicleBV_Kph_M_f32	483.666595
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	14410
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	21441
VitesseVehiculeRoues_Kph_M_f32	641.405884
k_AASNTCEnableTimeout_mS_u16	44651
k_AASNodeAbsentDiag_Cnt_str.Threshold	1672
k_AASNodeAbsentDiag_Cnt_str.PStep	12381
k_AASNodeAbsentDiag_Cnt_str.NStep	38181
k_AASNodeAbsentTimeout_mS_u16	50335
k_AASNodeTimeout_mS_u16	57540
k_ABSNodeTimeout_mS_u16	2183
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	9264
k_ANGLEVOLANTSigValidThresh_Cnt_u16	49387
k_AngleVolantInvalidThresh_Cnt_u16	49402
k_AngleVolantValidThresh_Cnt_u16	46102
k_BSI552MsgTimeout_mS_u16	19600
k_BSINTCEnableTimeout_mS_u16	25157
k_BSINodeAbsentDiag_Cnt_str.Threshold	25972
k_BSINodeAbsentDiag_Cnt_str.PStep	34502
k_BSINodeAbsentDiag_Cnt_str.NStep	15027
k_BSINodeAbsentTimeout_mS_u16	50247
k_BSINodeTimeout_mS_u16	42454
k_BattOvHi_Volt_f32	22.8896999
k_BattOvLo_Volt_f32	1.12160003
k_BattUvHi_Volt_f32	6.18300009
k_BattUvLo_Volt_f32	1.97099996
k_CAVNTCEnableTimeout_mS_u16	21212
k_CAVNodeAbsentDiag_Cnt_str.Threshold	13199
k_CAVNodeAbsentDiag_Cnt_str.PStep	24496
k_CAVNodeAbsentDiag_Cnt_str.NStep	65079
k_CAVNodeAbsentTimeout_mS_u16	37123
k_CAVNodeTimeout_mS_u16	8462
k_CMM388MsgTimeout_mS_u16	882
k_CMM388NTCEnableTimeout_mS_u16	60558
k_CMMNTCEnableTimeout_mS_u16	34928
k_CMMNodeAbsentDiag_Cnt_str.Threshold	62869
k_CMMNodeAbsentDiag_Cnt_str.PStep	24698
k_CMMNodeAbsentDiag_Cnt_str.NStep	35350
k_CMMNodeAbsentTimeout_mS_u16	37597
k_CONSANGLECPKMax_HwDeg_f32	80.8651962
k_CONSANGLECPKMin_HwDeg_f32	-452.421509
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	15178
k_CONSANGLECPKSigValidThresh_Cnt_u16	38593
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	57242
k_CPKVehicleSpeedValidThresh_Cnt_u16	10849
k_CityParkInputInvalidThresh_Cnt_u16	13106
k_CityParkInputValidThresh_Cnt_u16	57760
k_ComputerRazGCTSigValidThresh_Cnt_u16	20846
k_CptTemporelSigValidThresh_Cnt_u16	32545
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	45881
k_DMDFCTCPKSigValidThresh_Cnt_u16	18888

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_DMDFCTCPKValidCount_Cnt_u16	50654
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	39673
k_DMDRELAXECPKSigValidThresh_Cnt_u16	43167
k_DMDRelaxeConsistentThresh_Cnt_u16	61813
k_DateValidThresh_Cnt_u16	35182
k_DefaultVehSpd_Kph_f32	134.059601
k_DiagMuxOnAbsentTimeout_mS_u16	1266
k_EMNodeTimeout_mS_u16	7663
k_ESPNTCEnableTimeout_mS_u16	42129
k_ESPNodeAbsentDiag_Cnt_str.Threshold	27569
k_ESPNodeAbsentDiag_Cnt_str.PStep	35214
k_ESPNodeAbsentDiag_Cnt_str.NStep	59297
k_ESPNodeAbsentTimeout_mS_u16	38821
k_EtatMTSigInvalidThresh_Cnt_u16	58827
k_EtatMTSigValidThresh_Cnt_u16	9297
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	33765
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	17072
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	21465
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	34549
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	39912
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	51674
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	46666
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	37509
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	40689
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	38896
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	22386
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	18393
k_ISDATDIRASentDiag_Cnt_str.Threshold	44440
k_ISDATDIRASentDiag_Cnt_str.PStep	55056
k_ISDATDIRASentDiag_Cnt_str.NStep	15158
k_ISDATDIRASentTimeout_mS_u16	3576
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	36462
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	20239
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	23613
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	31452
k_ISDYNAASChkSumValidThresh_Cnt_u16	5154
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	43819
k_ISDYNAASMsgCountValidThresh_Cnt_u16	1930
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	9408
k_ISDYNAASMsgLenValidThresh_Cnt_u16	63912
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	41907
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	24007
k_ISDYNABRChkSumValidThresh_Cnt_u16	25302
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	11030
k_ISDYNABRMsgCountValidThresh_Cnt_u16	55892
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	41513
k_ISDYNABRMsgLenValidThresh_Cnt_u16	63396
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	6307
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	53138
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	51055
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	16531
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	55503
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	37069
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	11598
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	16793
k_ISDYNVOLChkSumValidThresh_Cnt_u16	30012
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	53825
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	8454
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	11471
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	20409
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	49332
k_IgnOnTimeout_mS_u16	52149
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	110.659698
k_PowerCutVehSpdLowThresh_Kph_f32	0.0617000014
k_PowerCutVehSpdLowTimeout_mS_u16	2679
k_VBattMaxAAS_Volt_f32	29.4137001
k_VBattMaxBSI_Volt_f32	27.4249992
k_VBattMaxCAV_Volt_f32	19.1760006
k_VBattMaxCMM388_Volt_f32	20.2609997
k_VBattMaxCMM_Volt_f32	10.7812996
k_VBattMaxESP_Volt_f32	28.8628006
k_VBattMinAAS_Volt_f32	6.68909979

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinBSI_Volt_f32	2.36500001
k_VBattMinCAV_Volt_f32	16.9657001
k_VBattMinCMM388_Volt_f32	2.67459989
k_VBattMinCMM_Volt_f32	14.0233002
k_VBattMinESP_Volt_f32	10.7812996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	39576
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	56426
k_VitesseVehicleBVRampValidThresh_Cnt_u16	55232
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	56399
k_VitesseVehicleBVSigValidThresh_Cnt_u16	29969
k_VitesseVehicleBVSpeedPassThresh_kph_f32	584.59552
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	19829
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	11211
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	890720768
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	226
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	1230
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3915353088
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	25
target_SrlComInput_Per1_Batt_Volt_f32.value	2.32719994
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3935060480
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	90
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.302186847
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1174237696
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2745471488
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1025225216
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2590167552
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1132065280
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3227587072
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2568499712
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	8
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	118
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	130
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4294693376
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	123
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	218
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	236
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2911400448
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	163

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1454346752
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	185
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4222005760
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	45
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	166
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	167
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3552297472
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3777
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.154389754
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	312296
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	238.932404
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	40024

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3915353088	3915353088	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	20241	20241	✔
AngleVolantMsgTimer_mS_M_u32	3915353088	3915353088	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	64.5234146	64.5234146	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	25972	25972	✔
BSINodeAbsentTimer_mS_M_u32	3915353088	3915353088	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	13199	13199	✔
CAVNodeAbsentTimer_mS_M_u32	3915353088	3915353088	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3227587072	3227587072	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	50348	50348	✔
CONSANGLECPK_HwDeg_M_f32	-412.522186	-412.522186 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	50348	50348	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3656065536	3656065536	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	58906	58906	✔
CityParkInputConsistentCount_Cnt_M_u16	57760	57760	✔
CityParkInputInvalidCount_Cnt_M_u16	46102	46102	✔
CityParkInputMsgTimer_mS_M_u32	3915353088	3915353088	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3915353088	3915353088	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3915353088	3915353088	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3915353088	3915353088	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3915353088	3915353088	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3915353088	3915353088	✔
ESPNTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3915353088	3915353088	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	99	99	✔
EffacDefaultDiagTimer_mS_M_u32[1]	759	759	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3915353088	3915353088	✔
ElecIntTimer_mS_M_u32[1]	8	8	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3915353088	3915353088	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3915353088	3915353088	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3915353088	3915353088	✔
IgnOnTimer_mS_M_u32	2642637312	2642637312	✔
IgnTimeOff_Sec_M_u32	506195260	506195260	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	59	59	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1174237696	1174237696	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	45	45	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2745471488	2745471488	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	152	152	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1025225216	1025225216	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	2	2	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2590167552	2590167552	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3303059968	3303059968	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	246	246	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3227587072	3227587072	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	144	144	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2568499712	2568499712	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	153	153	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4294693376	4294693376	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2911400448	2911400448	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	163	163	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1454346752	1454346752	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	185	185	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4222005760	4222005760	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3552297472	3552297472	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	383.419403	383.419403	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	483.666595	483.666595	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	641.405884	641.405884	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	64.5234146	64.5234146	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	50348	50348	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	506195260	506195260	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-412.522186	-412.522186 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	134.059601	134.059601	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.115 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	56777984
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	53070
AASNodeAbsentTimer_mS_M_u32	3660811520
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	24889
ANGLEVOLANTSigValidCount_Cnt_M_u16	16126
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	6007
AngleVolantMsgTimer_mS_M_u32	56777984
AngleVolantValidCount_Cnt_M_u16	48880
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	569.464844
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2829864192
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1612762368
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1257143552
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1849310464
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	18020
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3687120128
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	17350
CAVNodeAbsentTimer_mS_M_u32	243510528

Name	Input Value
CDD_SrlComVehSpd_Kph_G_f32	305.738312
CMM388NTCEnableTimer_mS_M_u32	3840339200
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1224846592
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	62568
CMMNodeAbsentTimer_mS_M_u32	2688302336
CONSANGLECPKSigInvalidCount_Cnt_M_u16	50894
CONSANGLECPKSigValidCount_Cnt_M_u16	28322
CONSANGLECPK_Cnt_M_u16	17761
CONSANGLECPK_HwDeg_M_f32	-358.620392
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17761
CPKVehicleSpeedMsgTimer_mS_M_u32	1155882240
CPKVehicleSpeedValidCount_Cnt_M_u16	31359
CityParkInputConsistentCount_Cnt_M_u16	35908
CityParkInputInvalidCount_Cnt_M_u16	31204
CityParkInputMsgTimer_mS_M_u32	1174237696
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4236741888
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	23202
ComputerRazGCTSigInvalidTimer_mS_M_u32	551693568
ComputerRazGCTSigValidCount_Cnt_M_u16	64581
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	6288
DMDFCTCPKSigValidCount_Cnt_M_u16	6941
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	739
DMDRELAXECPKSigValidCount_Cnt_M_u16	44072
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	9207
DateInvalidTimer_mS_M_u32	1612762368
DiagMuxOnAbsentTimer_mS_M_u32	743251200
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1849310464
ESPNTCEnableTimer_mS_M_u32	292588800
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	59833
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1121
EffacDefaultDiagTimer_mS_M_u32[1]	2235
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	21
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2521758976
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	7629
EtatMTSigValidCount_Cnt_M_u16	49613
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	59000
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	55756
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	10139
ISDAT4V2BSI552MsgTimer_mS_M_u32	2576366848
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	6333
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	15077
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	49613
ISDATBSI3F2MsgTimer_mS_M_u32	3299024128
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	53634
ISDATBSI412MsgLenValidCount_Cnt_M_u16	6426
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	7629
ISDATBSI412MsgTimer_mS_M_u32	2310561024
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1212
ISDATBSI432MsgLenValidCount_Cnt_M_u16	20749
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	62883
ISDATDIRASentFltAcc_Cnt_M_u16	54471
ISDATDIRASentTimer_mS_M_u32	1155882240
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	37431
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	48880
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	4411
ISDYN2CMMMsgTimer_mS_M_u32	4260531456
ISDYNAASChkSumInvalidCount_Cnt_M_u16	19704

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNAASChkSumValidCount_Cnt_M_u16	9053
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	42395
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	60869
ISDYNAASMsgLenValidCount_Cnt_M_u16	35266
ISDYNAASMsgTimeValidCount_Cnt_M_u16	19704
ISDYNAASMsgTimer_mS_M_u32	3029527808
ISDYNABRChkSumInvalidCount_Cnt_M_u16	26769
ISDYNABRChkSumValidCount_Cnt_M_u16	49789
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	64547
ISDYNABRMsgCountValidCount_Cnt_M_u16	27848
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	60665
ISDYNABRMsgLenValidCount_Cnt_M_u16	28429
ISDYNABRMsgTimeValidCount_Cnt_M_u16	17761
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	715
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1315
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	49613
ISDYNCMM208MsgTimer_mS_M_u32	468536576
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2711
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1421
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	45126
ISDYNCMM388MsgTimer_mS_M_u32	2533911808
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	14116
ISDYNVOLChkSumValidCount_Cnt_M_u16	37752
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	16358
ISDYNVOLMsgCountValidCount_Cnt_M_u16	14067
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	36238
ISDYNVOLMsgLenValidCount_Cnt_M_u16	7363
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	62568
ISDYNVOLMsgTimer_mS_M_u32	3968740608
IgnOnTimer_mS_M_u32	2136763648
IgnTimeOff_Sec_M_u32	212727400
ManVehSpd_Kph_M_f32	134.734802
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	51
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	136
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	58793216
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	215
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2172222720
PrevISDATBSI412MsgDLCError_Cnt_M_u08	57
PrevISDATBSI412MsgRxTime_MSec_M_u32	1545645312
PrevISDATBSI432MsgDLCError_Cnt_M_u08	28
PrevISDATBSI432MsgRxTime_MSec_M_u32	2977205504
PrevISDATDIRAMsgTxTime_MSec_M_u32	239381760
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	183
PrevISDYN2CMMMsgRxTime_MSec_M_u32	874102016
PrevISDYNAASMsgDLCError_Cnt_M_u08	250
PrevISDYNAASMsgRxTime_MSec_M_u32	1633955072
PrevISDYNABRMsgDLCError_Cnt_M_u08	49
PrevISDYNABRMsgRxTime_MSec_M_u32	632581376
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	251
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1277504768
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	123
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2436074752
PrevISDYNVOLMsgDLCError_Cnt_M_u08	198
PrevISDYNVOLMsgRxTime_MSec_M_u32	2807672064
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	386817280
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	195.498703
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime

Name	Input Value
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	795
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	5016
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	58992
VitesseVehicleBVRampValidCount_Cnt_M_u16	15533
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	40974
VitesseVehicleBVSigValidCount_Cnt_M_u16	25491
VitesseVehicleBV_Kph_M_f32	281.895203
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	45126
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	33699
VitesseVehiculeRoues_Kph_M_f32	181.714294
k_AASNTCEnableTimeout_mS_u16	17444
k_AASNodeAbsentDiag_Cnt_str.Threshold	2853
k_AASNodeAbsentDiag_Cnt_str.PStep	45885
k_AASNodeAbsentDiag_Cnt_str.NStep	30143
k_AASNodeAbsentTimeout_mS_u16	40775
k_AASNodeTimeout_mS_u16	19096
k_ABSNodeTimeout_mS_u16	32913
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	33107
k_ANGLEVOLANTSigValidThresh_Cnt_u16	57572
k_AngleVolantInvalidThresh_Cnt_u16	56503
k_AngleVolantValidThresh_Cnt_u16	31204
k_BSI552MsgTimeout_mS_u16	38198
k_BSINTCEnableTimeout_mS_u16	23316
k_BSINodeAbsentDiag_Cnt_str.Threshold	26012
k_BSINodeAbsentDiag_Cnt_str.PStep	34485
k_BSINodeAbsentDiag_Cnt_str.NStep	15050
k_BSINodeAbsentTimeout_mS_u16	38863
k_BSINodeTimeout_mS_u16	62883
k_BattOvHi_Volt_f32	8.25189972
k_BattOvLo_Volt_f32	16.5226994
k_BattUvHi_Volt_f32	26.4431992
k_BattUvLo_Volt_f32	25.5905991
k_CAVNTCEnableTimeout_mS_u16	13714
k_CAVNodeAbsentDiag_Cnt_str.Threshold	35528
k_CAVNodeAbsentDiag_Cnt_str.PStep	36412
k_CAVNodeAbsentDiag_Cnt_str.NStep	13249
k_CAVNodeAbsentTimeout_mS_u16	10268
k_CAVNodeTimeout_mS_u16	44666
k_CMM388MsgTimeout_mS_u16	17998
k_CMM388NTCEnableTimeout_mS_u16	64250
k_CMMNTCEnableTimeout_mS_u16	23317
k_CMMNodeAbsentDiag_Cnt_str.Threshold	28766
k_CMMNodeAbsentDiag_Cnt_str.PStep	41544
k_CMMNodeAbsentDiag_Cnt_str.NStep	64330
k_CMMNodeAbsentTimeout_mS_u16	13903
k_CONSANGLECPKMax_HwDeg_f32	772.251221
k_CONSANGLECPKMin_HwDeg_f32	-144.596695
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	42822
k_CONSANGLECPKSigValidThresh_Cnt_u16	47779
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	9750
k_CPKVehicleSpeedValidThresh_Cnt_u16	51777
k_CityParkInputInvalidThresh_Cnt_u16	3727
k_CityParkInputValidThresh_Cnt_u16	35908
k_ComputerRazGCTSigValidThresh_Cnt_u16	30747
k_CptTemporelSigValidThresh_Cnt_u16	1219
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	25593
k_DMDFCTCPKSigValidThresh_Cnt_u16	9741
k_DMDFCTCPKValidCount_Cnt_u16	3340
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	4411
k_DMDRELAXECPKSigValidThresh_Cnt_u16	52744
k_DMDRelaxeConsistentThresh_Cnt_u16	52102
k_DateValidThresh_Cnt_u16	10139
k_DefaultVehSpd_Kph_f32	120.972603

Name	Input Value
k_DiagMuxOnAbsentTimeout_mS_u16	7311
k_EMNodeTimeout_mS_u16	31703
k_ESPNTCEnableTimeout_mS_u16	42354
k_ESPNodeAbsentDiag_Cnt_str.Threshold	37866
k_ESPNodeAbsentDiag_Cnt_str.PStep	56811
k_ESPNodeAbsentDiag_Cnt_str.NStep	17035
k_ESPNodeAbsentTimeout_mS_u16	18423
k_EtatMTSigInvalidThresh_Cnt_u16	39620
k_EtatMTSigValidThresh_Cnt_u16	17648
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	9525
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	24214
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	22937
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	45958
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	35438
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	4054
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	45829
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	21526
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	21776
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	56213
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	62158
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	24283
k_ISDATDIRASentDiag_Cnt_str.Threshold	10540
k_ISDATDIRASentDiag_Cnt_str.PStep	20636
k_ISDATDIRASentDiag_Cnt_str.NStep	57668
k_ISDATDIRASentTimeout_mS_u16	5693
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	7964
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	6007
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	11886
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	24465
k_ISDYNAASChkSumValidThresh_Cnt_u16	63869
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	29475
k_ISDYNAASMsgCountValidThresh_Cnt_u16	9160
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	61925
k_ISDYNAASMsgLenValidThresh_Cnt_u16	36844
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	22668
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	7247
k_ISDYNABRChkSumValidThresh_Cnt_u16	37603
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	48484
k_ISDYNABRMsgCountValidThresh_Cnt_u16	62825
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	11112
k_ISDYNABRMsgLenValidThresh_Cnt_u16	24761
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	13948
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	26735
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	43799
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	10027
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	55353
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	62974
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	60988
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	25753
k_ISDYNVOLChkSumValidThresh_Cnt_u16	40817
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	34018
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	25297
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	45177
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	15737
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	6601
k_IgnOnTimeout_mS_u16	13893
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	173.672302
k_PowerCutVehSpdLowThresh_Kph_f32	125.336403
k_PowerCutVehSpdLowTimeout_mS_u16	24576
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	7.3987999
k_VBattMaxCAV_Volt_f32	11.0373001
k_VBattMaxCMM388_Volt_f32	22.5422993
k_VBattMaxCMM_Volt_f32	1.96469998
k_VBattMaxESP_Volt_f32	19.7467003
k_VBattMinAAS_Volt_f32	6.08790016
k_VBattMinBSI_Volt_f32	19.7467003
k_VBattMinCAV_Volt_f32	8.09700012
k_VBattMinCMM388_Volt_f32	28.6051998
k_VBattMinCMM_Volt_f32	21.8549004
k_VBattMinESP_Volt_f32	1.96469998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	8862

Name	Input Value
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	62183
k_VitesseVehicleBVRampValidThresh_Cnt_u16	14054
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	19064
k_VitesseVehicleBVSigValidThresh_Cnt_u16	54769
k_VitesseVehicleBVSpeedPassThresh_kph_f32	295.100494
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	15046
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	17795
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1612762368
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	105
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	55161
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3299876608
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	123
target_SrlComInput_Per1_Batt_Volt_f32.value	15.7875004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2139225344
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	88
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.000386777014
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3991825664
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	80
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3648589056
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1368632576
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3191753984
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2272849152
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	7
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	356748544
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3483249920
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	159
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	175
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	196
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	245
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	829639936
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	58
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	84
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	107
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	115
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	18
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2739760384
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2891451648
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	32681216
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	25
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	33

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	104
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3790830848
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1951
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.356844783
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	888902
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	72.1042023
target_SrlComInput_Per1_VitesseVehiculeBV_Cnt_u16.value	39453

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3299876608	3299876608	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3299876608	3299876608	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	569.464844	569.464844	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26012	26012	✔
BSINodeAbsentTimer_mS_M_u32	3299876608	3299876608	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	35528	35528	✔
CAVNodeAbsentTimer_mS_M_u32	3299876608	3299876608	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	356748544	356748544	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	17761	17761	✔
CONSANGLECPK_HwDeg_M_f32	-358.620392	-358.620392 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3299876608	3299876608	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3299876608	3299876608	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3299876608	3299876608	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3299876608	3299876608	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3299876608	3299876608	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3299876608	3299876608	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3299876608	3299876608	✔
ESPNTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3299876608	3299876608	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1121	1121	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2235	2235	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3299876608	3299876608	✔
ElecIntTimer_mS_M_u32[1]	21	21	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3299876608	3299876608	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3299876608	3299876608	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM388MsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3299876608	3299876608	✔
IgnOnTimer_mS_M_u32	2136763648	2136763648	✔
IgnTimeOff_Sec_M_u32	212727400	212727400	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3991825664	3991825664	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	80	80	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3648589056	3648589056	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	181	181	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1368632576	1368632576	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	90	90	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3191753984	3191753984	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	239381760	239381760	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	7	7	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	356748544	356748544	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	222	222	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3483249920	3483249920	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	59	59	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	829639936	829639936	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	18	18	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2739760384	2739760384	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	220	220	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2891451648	2891451648	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	63	63	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	32681216	32681216	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3790830848	3790830848	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	195.498703	195.498703	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	281.895203	281.895203	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	181.714294	181.714294	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	569.464844	569.464844	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	17761	17761	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	212727400	212727400	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-358.620392	-358.620392 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	120.972603	120.972603	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.116 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3274419200
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	45414
AASNodeAbsentTimer_mS_M_u32	1064836096
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	50598
ANGLEVOLANTSigValidCount_Cnt_M_u16	23320
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	48363
AngleVolantMsgTimer_mS_M_u32	3274419200
AngleVolantValidCount_Cnt_M_u16	61697
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	117.366737
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2802703360
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	4071644160
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3305589760
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	975440896
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	33317
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2357447680
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	56445
CAVNodeAbsentTimer_mS_M_u32	2332539904
CDD_SrlComVehSpd_Kph_G_f32	581.530579
CMM388NTCEnableTimer_mS_M_u32	2766011392
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1401797632
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	65111

Name	Input Value
CMMNodeAbsentTimer_mS_M_u32	740166656
CONSANGLECPKSigInvalidCount_Cnt_M_u16	55272
CONSANGLECPKSigValidCount_Cnt_M_u16	20266
CONSANGLECPK_Cnt_M_u16	34541
CONSANGLECPK_HwDeg_M_f32	-266.225189
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	34541
CPKVehicleSpeedMsgTimer_mS_M_u32	3399658496
CPKVehicleSpeedValidCount_Cnt_M_u16	47965
CityParkInputConsistentCount_Cnt_M_u16	55557
CityParkInputInvalidCount_Cnt_M_u16	57636
CityParkInputMsgTimer_mS_M_u32	3991825664
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	679222272
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	24426
ComputerRazGCTSigInvalidTimer_mS_M_u32	3991682048
ComputerRazGCTSigValidCount_Cnt_M_u16	52482
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	46368
DMDFCTCPKSigValidCount_Cnt_M_u16	64570
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	2216
DMDRELAXECPKSigValidCount_Cnt_M_u16	15258
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	42093
DateInvalidTimer_mS_M_u32	4071644160
DiagMuxOnAbsentTimer_mS_M_u32	1667984384
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	975440896
ESPNTCEnableTimer_mS_M_u32	3451984896
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	32037
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	41
EffacDefaultDiagTimer_mS_M_u32[1]	46
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	102
ElecIntTimer_mS_M_u32[1]	108
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	82168832
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	25387
EtatMTSigValidCount_Cnt_M_u16	38377
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	41194
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	13740
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20160
ISDAT4V2BSI552MsgTimer_mS_M_u32	2418150400
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	35291
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	57889
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	38377
ISDATBSI3F2MsgTimer_mS_M_u32	1919511552
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1163
ISDATBSI412MsgLenValidCount_Cnt_M_u16	44161
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	25387
ISDATBSI412MsgTimer_mS_M_u32	136948736
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	7515
ISDATBSI432MsgLenValidCount_Cnt_M_u16	38697
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	31462
ISDATDIRASentFltAcc_Cnt_M_u16	28026
ISDATDIRASentTimer_mS_M_u32	3399658496
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	30827
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	61697
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	14111
ISDYN2CMMMsgTimer_mS_M_u32	2419792896
ISDYNAASChkSumInvalidCount_Cnt_M_u16	24680
ISDYNAASChkSumValidCount_Cnt_M_u16	35834
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	43264
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	39552
ISDYNAASMsgLenValidCount_Cnt_M_u16	54602
ISDYNAASMsgTimeValidCount_Cnt_M_u16	24680

Name	Input Value
ISDYNAASMsgTimer_mS_M_u32	3856268288
ISDYNABRChkSumInvalidCount_Cnt_M_u16	26399
ISDYNABRChkSumValidCount_Cnt_M_u16	10264
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	48871
ISDYNABRMsgCountValidCount_Cnt_M_u16	7097
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	53607
ISDYNABRMsgLenValidCount_Cnt_M_u16	47593
ISDYNABRMsgTimeValidCount_Cnt_M_u16	34541
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	716
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1317
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	38377
ISDYNCMM208MsgTimer_mS_M_u32	2437602304
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2715
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1423
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	62719
ISDYNCMM388MsgTimer_mS_M_u32	4101602304
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	24294
ISDYNVOLChkSumValidCount_Cnt_M_u16	47272
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	5918
ISDYNVOLMsgCountValidCount_Cnt_M_u16	32952
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	9638
ISDYNVOLMsgLenValidCount_Cnt_M_u16	26312
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	65111
ISDYNVOLMsgTimer_mS_M_u32	988298240
IgnOnTimer_mS_M_u32	2340256768
IgnTimeOff_Sec_M_u32	753116157
ManVehSpd_Kph_M_f32	399.1026
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	53
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	33
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2916051968
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	191
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	224807936
PrevISDATBSI412MsgDLCError_Cnt_M_u08	49
PrevISDATBSI412MsgRxTime_MSec_M_u32	1446034432
PrevISDATBSI432MsgDLCError_Cnt_M_u08	96
PrevISDATBSI432MsgRxTime_MSec_M_u32	4256504832
PrevISDATDIRAMsgTxTime_MSec_M_u32	3485776896
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	177
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3330640896
PrevISDYNAASMsgDLCError_Cnt_M_u08	77
PrevISDYNAASMsgRxTime_MSec_M_u32	3026598912
PrevISDYNABRMsgDLCError_Cnt_M_u08	251
PrevISDYNABRMsgRxTime_MSec_M_u32	4168449024
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	191
PrevISDYNCMM208MsgRxTime_MSec_M_u32	941833216
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	73
PrevISDYNCMM388MsgRxTime_MSec_M_u32	444079104
PrevISDYNVOLMsgDLCError_Cnt_M_u08	109
PrevISDYNVOLMsgRxTime_MSec_M_u32	2558901248
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	942124032
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	14.9096003
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	12926
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	4040
VVHTYPE1Count_Cnt_M_u08	6

Name	Input Value
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	7295
VitesseVehicleBVRampValidCount_Cnt_M_u16	10377
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	40231
VitesseVehicleBVSigValidCount_Cnt_M_u16	33113
VitesseVehicleBV_Kph_M_f32	563.325989
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	62719
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	2473
VitesseVehiculeRoues_Kph_M_f32	401.097504
k_AASNTCEnableTimeout_mS_u16	22180
k_AASNodeAbsentDiag_Cnt_str.Threshold	62361
k_AASNodeAbsentDiag_Cnt_str.PStep	60042
k_AASNodeAbsentDiag_Cnt_str.NStep	12412
k_AASNodeAbsentTimeout_mS_u16	27644
k_AASNodeTimeout_mS_u16	27336
k_ABSNodeTimeout_mS_u16	49437
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	50070
k_ANGLEVOLANTSigValidThresh_Cnt_u16	932
k_AngleVolantInvalidThresh_Cnt_u16	7211
k_AngleVolantValidThresh_Cnt_u16	57636
k_BSI552MsgTimeout_mS_u16	57584
k_BSINTCEnableTimeout_mS_u16	31315
k_BSINodeAbsentDiag_Cnt_str.Threshold	26052
k_BSINodeAbsentDiag_Cnt_str.PStep	34468
k_BSINodeAbsentDiag_Cnt_str.NStep	15073
k_BSINodeAbsentTimeout_mS_u16	39907
k_BSINodeTimeout_mS_u16	31462
k_BattOvHi_Volt_f32	6.67449999
k_BattOvLo_Volt_f32	22.9631996
k_BattUvHi_Volt_f32	15.3866997
k_BattUvLo_Volt_f32	25.9109001
k_CAVNTCEnableTimeout_mS_u16	58906
k_CAVNodeAbsentDiag_Cnt_str.Threshold	16522
k_CAVNodeAbsentDiag_Cnt_str.PStep	65188
k_CAVNodeAbsentDiag_Cnt_str.NStep	60110
k_CAVNodeAbsentTimeout_mS_u16	1915
k_CAVNodeTimeout_mS_u16	53476
k_CMM388MsgTimeout_mS_u16	19558
k_CMM388NTCEnableTimeout_mS_u16	56930
k_CMMNTCEnableTimeout_mS_u16	8915
k_CMMNodeAbsentDiag_Cnt_str.Threshold	44238
k_CMMNodeAbsentDiag_Cnt_str.PStep	8009
k_CMMNodeAbsentDiag_Cnt_str.NStep	62139
k_CMMNodeAbsentTimeout_mS_u16	41381
k_CONSANGLECPKMax_HwDeg_f32	158.416199
k_CONSANGLECPKMin_HwDeg_f32	-458.915894
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	4095
k_CONSANGLECPKSigValidThresh_Cnt_u16	25769
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	20558
k_CPKVehicleSpeedValidThresh_Cnt_u16	54862
k_CityParkInputInvalidThresh_Cnt_u16	60709
k_CityParkInputValidThresh_Cnt_u16	55557
k_ComputerRazGCTSigValidThresh_Cnt_u16	25537
k_CptTemporelSigValidThresh_Cnt_u16	31879
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	27751
k_DMDFCTCPKSigValidThresh_Cnt_u16	38121
k_DMDFCTCPKValidCount_Cnt_u16	52781
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	14111
k_DMDRELAXECPKSigValidThresh_Cnt_u16	20345
k_DMDRelaxeConsistentThresh_Cnt_u16	52991
k_DateValidThresh_Cnt_u16	20160
k_DefaultVehSpd_Kph_f32	132.905502
k_DiagMuxOnAbsentTimeout_mS_u16	14691
k_EMNodeTimeout_mS_u16	7373
k_ESPNTCEnableTimeout_mS_u16	26489
k_ESPNodeAbsentDiag_Cnt_str.Threshold	12426
k_ESPNodeAbsentDiag_Cnt_str.PStep	51135
k_ESPNodeAbsentDiag_Cnt_str.NStep	32089

Name	Input Value
k_ESPNodeAbsentTimeout_mS_u16	3245
k_EtatMTSigInvalidThresh_Cnt_u16	23686
k_EtatMTSigValidThresh_Cnt_u16	11455
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	36593
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	33167
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	1286
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	7552
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	22406
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	39311
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	30336
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	61966
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	31839
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	37969
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	19815
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	20864
k_ISDATDIRASentDiag_Cnt_str.Threshold	16348
k_ISDATDIRASentDiag_Cnt_str.PStep	15877
k_ISDATDIRASentDiag_Cnt_str.NStep	46278
k_ISDATDIRASentTimeout_mS_u16	3611
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	21693
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	48363
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	48261
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	33311
k_ISDYNAASChkSumValidThresh_Cnt_u16	33560
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	23015
k_ISDYNAASMsgCountValidThresh_Cnt_u16	63161
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	6947
k_ISDYNAASMsgLenValidThresh_Cnt_u16	60108
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	15532
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	7013
k_ISDYNABRChkSumValidThresh_Cnt_u16	9831
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	7461
k_ISDYNABRMsgCountValidThresh_Cnt_u16	41943
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	22871
k_ISDYNABRMsgLenValidThresh_Cnt_u16	6181
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	60574
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	21122
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	3020
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	57615
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	24742
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	13848
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	58396
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	26438
k_ISDYNVOLChkSumValidThresh_Cnt_u16	13692
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	36778
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	38684
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	23335
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	53989
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	45110
k_IgnOnTimeout_mS_u16	41538
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	27.3062992
k_PowerCutVehSpdLowThresh_Kph_f32	212.314102
k_PowerCutVehSpdLowTimeout_mS_u16	29456
k_VBattMaxAAS_Volt_f32	7.21589994
k_VBattMaxBSI_Volt_f32	8.00930023
k_VBattMaxCAV_Volt_f32	27.4190006
k_VBattMaxCMM388_Volt_f32	14.6248999
k_VBattMaxCMM_Volt_f32	25.4074001
k_VBattMaxESP_Volt_f32	19.9822998
k_VBattMinAAS_Volt_f32	4.49770021
k_VBattMinBSI_Volt_f32	19.9822998
k_VBattMinCAV_Volt_f32	31.9538994
k_VBattMinCMM388_Volt_f32	4.52479982
k_VBattMinCMM_Volt_f32	8.88819981
k_VBattMinESP_Volt_f32	25.4074001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	53815
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	40989
k_VitesseVehicleBVRampValidThresh_Cnt_u16	12830
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	37800
k_VitesseVehicleBVSigValidThresh_Cnt_u16	61438
k_VitesseVehicleBVSpeedPassThresh_kph_f32	232.074493
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	63357

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	58887
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	4071644160
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	163
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	55588
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3771360768
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	73
target_SrlComInput_Per1_Batt_Volt_f32.value	14.4905005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3578579968
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	203
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.602993071
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	130513920
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	933731328
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	116
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	30915584
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	777509888
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2233990144
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	54
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3460832256
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3518512128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	56
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	136
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	155
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	193
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3904429056
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	80
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	92
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	179
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	598375424
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4211776512
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	750435328
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	42
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	93
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	122
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	124
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	162
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1408781312

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3320
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.136914864
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	360495
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	250.260696
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	62840

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3771360768	3771360768	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	62361	62361	✔
AASNodeAbsentTimer_mS_M_u32	3771360768	3771360768	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	48363	48363	✔
AngleVolantMsgTimer_mS_M_u32	3771360768	3771360768	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	117.366737	117.366737	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3771360768	3771360768	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3771360768	3771360768	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3771360768	3771360768	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3771360768	3771360768	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26052	26052	✔
BSINodeAbsentTimer_mS_M_u32	3771360768	3771360768	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3771360768	3771360768	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3771360768	3771360768	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3771360768	3771360768	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3771360768	3771360768	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3771360768	3771360768	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	34541	34541	✔
CONSANGLECPK_HwDeg_M_f32	-266.225189	-266.225189 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	34541	34541	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3399658496	3399658496	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	47965	47965	✔
CityParkInputConsistentCount_Cnt_M_u16	55557	55557	✔
CityParkInputInvalidCount_Cnt_M_u16	57638	57638	✔
CityParkInputMsgTimer_mS_M_u32	3771360768	3771360768	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3771360768	3771360768	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3771360768	3771360768	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3771360768	3771360768	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3771360768	3771360768	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3771360768	3771360768	✔
ESPNTCEnableTimer_mS_M_u32	3771360768	3771360768	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	12426	12426	✔
ESPNodeAbsentTimer_mS_M_u32	3771360768	3771360768	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	41	41	✔
EffacDefaultDiagTimer_mS_M_u32[1]	46	46	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3771360768	3771360768	✔
ElecIntTimer_mS_M_u32[1]	108	108	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3771360768	3771360768	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3771360768	3771360768	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3771360768	3771360768	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3771360768	3771360768	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3771360768	3771360768	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3771360768	3771360768	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3771360768	3771360768	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3771360768	3771360768	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3771360768	3771360768	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3771360768	3771360768	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3771360768	3771360768	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3771360768	3771360768	✔
IgnOnTimer_mS_M_u32	3771360768	3771360768	✔
IgnTimeOff_Sec_M_u32	753116157	753116157	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	99	99	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	130513920	130513920	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	144	144	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	933731328	933731328	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	116	116	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	30915584	30915584	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	215	215	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	777509888	777509888	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3485776896	3485776896	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	54	54	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3460832256	3460832256	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	196	196	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3518512128	3518512128	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	72	72	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3904429056	3904429056	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	179	179	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	598375424	598375424	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4211776512	4211776512	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	750435328	750435328	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1408781312	1408781312	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	14.9096003	14.9096003	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	563.325989	563.325989	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	401.097504	401.097504	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	117.366737	117.366737	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	34541	34541	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	753116157	753116157	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-266.225189	-266.225189 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	132.905502	132.905502	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.117 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1979155968
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	39430
AASNodeAbsentTimer_mS_M_u32	3794236928
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	33866
ANGLEVOLANTSigValidCount_Cnt_M_u16	3787
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	2483
AngleVolantMsgTimer_mS_M_u32	1979155968
AngleVolantValidCount_Cnt_M_u16	56186
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	272.389801
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1550530048
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	153204224
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3215992320
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2343757312
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	48321
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1460708864
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	46810
CAVNodeAbsentTimer_mS_M_u32	3811841536
CDD_SrlComVehSpd_Kph_G_f32	157.220596
CMM388NTCEnableTimer_mS_M_u32	3585889792
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1609176576
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	35590
CMMNodeAbsentTimer_mS_M_u32	2642208256
CONSANGLECPKSigInvalidCount_Cnt_M_u16	56986
CONSANGLECPKSigValidCount_Cnt_M_u16	55659
CONSANGLECPK_Cnt_M_u16	1862
CONSANGLECPK_HwDeg_M_f32	197.157394
CPKOK_Cnt_M_lgc	0

Name	Input Value
CPKVehicleSpeedInvalidCount_Cnt_M_u16	1862
CPKVehicleSpeedMsgTimer_mS_M_u32	287737344
CPKVehicleSpeedValidCount_Cnt_M_u16	41799
CityParkInputConsistentCount_Cnt_M_u16	41886
CityParkInputInvalidCount_Cnt_M_u16	40631
CityParkInputMsgTimer_mS_M_u32	892882688
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3008067072
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	22570
ComputerRazGCTSigInvalidTimer_mS_M_u32	826054144
ComputerRazGCTSigValidCount_Cnt_M_u16	65411
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	29331
DMDFCTCPKSigValidCount_Cnt_M_u16	31740
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	44892
DMDRELAXECPKSigValidCount_Cnt_M_u16	50013
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	5959
DateInvalidTimer_mS_M_u32	153204224
DiagMuxOnAbsentTimer_mS_M_u32	4264904192
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2343757312
ESPNTCEnableTimer_mS_M_u32	2327344640
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	43459
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	9
EffacDefaultDiagTimer_mS_M_u32[1]	81
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	56
ElecIntTimer_mS_M_u32[1]	458
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1652729344
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	59507
EtatMTSigValidCount_Cnt_M_u16	55969
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	49068
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	50173
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	53938
ISDAT4V2BSI552MsgTimer_mS_M_u32	3248547328
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	60326
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	28572
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	55969
ISDATBSI3F2MsgTimer_mS_M_u32	3038987776
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	54745
ISDATBSI412MsgLenValidCount_Cnt_M_u16	42750
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	59507
ISDATBSI412MsgTimer_mS_M_u32	317031936
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	16938
ISDATBSI432MsgLenValidCount_Cnt_M_u16	13287
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	61579
ISDATDIRASentFltAcc_Cnt_M_u16	38847
ISDATDIRASentTimer_mS_M_u32	287737344
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	46260
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	56186
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	40074
ISDYN2CMMMsgTimer_mS_M_u32	4043470336
ISDYNAASChkSumInvalidCount_Cnt_M_u16	37144
ISDYNAASChkSumValidCount_Cnt_M_u16	25273
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	60273
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	40181
ISDYNAASMsgLenValidCount_Cnt_M_u16	46991
ISDYNAASMsgTimeValidCount_Cnt_M_u16	37144
ISDYNAASMsgTimer_mS_M_u32	2123912704
ISDYNABRChkSumInvalidCount_Cnt_M_u16	6277
ISDYNABRChkSumValidCount_Cnt_M_u16	27343
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	31631
ISDYNABRMsgCountValidCount_Cnt_M_u16	2160
ISDYNABRMsgCount_Cnt_M_u08	7

Name	Input Value
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	15377
ISDYNABRMsgLenValidCount_Cnt_M_u16	12834
ISDYNABRMsgTimeValidCount_Cnt_M_u16	1862
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	718
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1321
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	55969
ISDYNCMM208MsgTimer_mS_M_u32	1620063744
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2723
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1427
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	12136
ISDYNCMM388MsgTimer_mS_M_u32	3459503616
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	52616
ISDYNVOLChkSumValidCount_Cnt_M_u16	48857
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	5249
ISDYNVOLMsgCountValidCount_Cnt_M_u16	21610
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	65100
ISDYNVOLMsgLenValidCount_Cnt_M_u16	4606
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	35590
ISDYNVOLMsgTimer_mS_M_u32	1176016384
IgnOnTimer_mS_M_u32	3176650240
IgnTimeOff_Sec_M_u32	487794345
ManVehSpd_Kph_M_f32	436.957703
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	57
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	103
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1001997824
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	198
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3808896512
PrevISDATBSI412MsgDLCError_Cnt_M_u08	111
PrevISDATBSI412MsgRxTime_MSec_M_u32	2946831872
PrevISDATBSI432MsgDLCError_Cnt_M_u08	60
PrevISDATBSI432MsgRxTime_MSec_M_u32	1514960384
PrevISDATDIRAMsgTxTime_MSec_M_u32	366548480
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	124
PrevISDYN2CMMMsgRxTime_MSec_M_u32	387999232
PrevISDYNAASMsgDLCError_Cnt_M_u08	23
PrevISDYNAASMsgRxTime_MSec_M_u32	3146159616
PrevISDYNABRMsgDLCError_Cnt_M_u08	65
PrevISDYNABRMsgRxTime_MSec_M_u32	1376769536
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	96
PrevISDYNCMM208MsgRxTime_MSec_M_u32	623613440
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	231
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2502391296
PrevISDYNVOLMsgDLCError_Cnt_M_u08	156
PrevISDYNVOLMsgRxTime_MSec_M_u32	2359432704
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4073948672
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	564.73407
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	9443
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	62973
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0

Name	Input Value
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	50924
VitesseVehicleBVRampValidCount_Cnt_M_u16	15558
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	32723
VitesseVehicleBVSigValidCount_Cnt_M_u16	53012
VitesseVehicleBV_Kph_M_f32	347.186798
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	12136
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	62177
VitesseVehiculeRoues_Kph_M_f32	402.352905
k_AASNTCEnableTimeout_mS_u16	44213
k_AASNodeAbsentDiag_Cnt_str.Threshold	21695
k_AASNodeAbsentDiag_Cnt_str.PStep	62766
k_AASNodeAbsentDiag_Cnt_str.NStep	32033
k_AASNodeAbsentTimeout_mS_u16	9805
k_AASNodeTimeout_mS_u16	10493
k_ABSNodeTimeout_mS_u16	42616
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	4669
k_ANGLEVOLANTSigValidThresh_Cnt_u16	64570
k_AngleVolantInvalidThresh_Cnt_u16	45305
k_AngleVolantValidThresh_Cnt_u16	40631
k_BSI552MsgTimeout_mS_u16	23648
k_BSINTCEnableTimeout_mS_u16	18146
k_BSINodeAbsentDiag_Cnt_str.Threshold	26132
k_BSINodeAbsentDiag_Cnt_str.PStep	34434
k_BSINodeAbsentDiag_Cnt_str.NStep	15119
k_BSINodeAbsentTimeout_mS_u16	41067
k_BSINodeTimeout_mS_u16	61579
k_BattOvHi_Volt_f32	13.5965004
k_BattOvLo_Volt_f32	22.5149002
k_BattUvHi_Volt_f32	28.6569004
k_BattUvLo_Volt_f32	6.76809978
k_CAVNTCEnableTimeout_mS_u16	47965
k_CAVNodeAbsentDiag_Cnt_str.Threshold	65135
k_CAVNodeAbsentDiag_Cnt_str.PStep	58823
k_CAVNodeAbsentDiag_Cnt_str.NStep	55341
k_CAVNodeAbsentTimeout_mS_u16	27080
k_CAVNodeTimeout_mS_u16	65398
k_CMM388MsgTimeout_mS_u16	3334
k_CMM388NTCEnableTimeout_mS_u16	36578
k_CMMNTCEnableTimeout_mS_u16	3166
k_CMMNodeAbsentDiag_Cnt_str.Threshold	46948
k_CMMNodeAbsentDiag_Cnt_str.PStep	29094
k_CMMNodeAbsentDiag_Cnt_str.NStep	42258
k_CMMNodeAbsentTimeout_mS_u16	43709
k_CONSANGLECPKMax_HwDeg_f32	26.7542
k_CONSANGLECPKMin_HwDeg_f32	-627.002625
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	8808
k_CONSANGLECPKSigValidThresh_Cnt_u16	9697
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	43699
k_CPKVehicleSpeedValidThresh_Cnt_u16	28084
k_CityParkInputInvalidThresh_Cnt_u16	16059
k_CityParkInputValidThresh_Cnt_u16	41886
k_ComputerRazGCTSigValidThresh_Cnt_u16	1212
k_CptTemporelSigValidThresh_Cnt_u16	19762
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	44817
k_DMDFCTCPKSigValidThresh_Cnt_u16	58658
k_DMDFCTCPKValidCount_Cnt_u16	43273
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	40074
k_DMDRELAXECPKSigValidThresh_Cnt_u16	307
k_DMDRelaxeConsistentThresh_Cnt_u16	60649
k_DateValidThresh_Cnt_u16	53938
k_DefaultVehSpd_Kph_f32	178.580704
k_DiagMuxOnAbsentTimeout_mS_u16	15724
k_EMNodeTimeout_mS_u16	21159
k_ESPNTCEnableTimeout_mS_u16	63926
k_ESPNodeAbsentDiag_Cnt_str.Threshold	39869
k_ESPNodeAbsentDiag_Cnt_str.PStep	19084
k_ESPNodeAbsentDiag_Cnt_str.NStep	52066
k_ESPNodeAbsentTimeout_mS_u16	44549
k_EtatMTSigInvalidThresh_Cnt_u16	37156
k_EtatMTSigValidThresh_Cnt_u16	27822
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	5742
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	51067
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	38823

Name	Input Value
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	9331
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	38953
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	45821
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	27767
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	28148
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	14670
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	8138
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	35600
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	50287
k_ISDATDIRASentDiag_Cnt_str.Threshold	21842
k_ISDATDIRASentDiag_Cnt_str.PStep	38193
k_ISDATDIRASentDiag_Cnt_str.NStep	48870
k_ISDATDIRASentTimeout_mS_u16	22369
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	43412
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	2483
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	55074
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	2949
k_ISDYNAASChkSumValidThresh_Cnt_u16	40399
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	61071
k_ISDYNAASMsgCountValidThresh_Cnt_u16	47984
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	3241
k_ISDYNAASMsgLenValidThresh_Cnt_u16	18721
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	15746
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	1535
k_ISDYNABRChkSumValidThresh_Cnt_u16	12944
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	12225
k_ISDYNABRMsgCountValidThresh_Cnt_u16	13698
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	48646
k_ISDYNABRMsgLenValidThresh_Cnt_u16	7363
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	40065
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	58631
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	32546
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	10620
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	63306
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	49611
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	31087
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	18028
k_ISDYNVOLChkSumValidThresh_Cnt_u16	28625
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	22640
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	61939
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	79
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	24445
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	12248
k_IgnOnTimeout_mS_u16	47432
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	173.188599
k_PowerCutVehSpdLowThresh_Kph_f32	254.258896
k_PowerCutVehSpdLowTimeout_mS_u16	35969
k_VBattMaxAAS_Volt_f32	16.7875996
k_VBattMaxBSI_Volt_f32	27.1508007
k_VBattMaxCAV_Volt_f32	21.6919003
k_VBattMaxCMM388_Volt_f32	0.517400026
k_VBattMaxCMM_Volt_f32	5.45660019
k_VBattMaxESP_Volt_f32	27.2073002
k_VBattMinAAS_Volt_f32	26.5489006
k_VBattMinBSI_Volt_f32	27.2073002
k_VBattMinCAV_Volt_f32	18.3551998
k_VBattMinCMM388_Volt_f32	22.2166004
k_VBattMinCMM_Volt_f32	6.50869989
k_VBattMinESP_Volt_f32	5.45660019
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	41694
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	18803
k_VitesseVehicleBVRampValidThresh_Cnt_u16	1921
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	29145
k_VitesseVehicleBVSigValidThresh_Cnt_u16	39519
k_VitesseVehicleBVSpeedPassThresh_kph_f32	648.905396
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	43482
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	5684
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	153204224
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0

Name	Input Value
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	33851
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1008472064
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	231
target_SrlComInput_Per1_Batt_Volt_f32.value	0.968500018
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2384569856
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	72
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.378504604
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	737269248
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	116
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3889362432
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2424575488
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	772093440
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3361101312
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1735882240
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	325621248
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	69
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	124
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	176
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	204
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	594425344
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	67
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	131
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	187
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1592579584
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	1
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4266522112
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	150
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1249842688
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	37
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	47
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	61
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	78
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	161
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	173
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2921932288
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3860
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.490363985
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1009090
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	196.277695
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	36781

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	21695	21695	✔
AASNodeAbsentTimer_mS_M_u32	1008472064	1008472064	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2485	2485	✔
AngleVolantMsgTimer_mS_M_u32	1008472064	1008472064	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	272.389801	272.389801	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26132	26132	✔
BSINodeAbsentTimer_mS_M_u32	1008472064	1008472064	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1008472064	1008472064	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1008472064	1008472064	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	1862	1862	✔
CONSANGLECPK_HwDeg_M_f32	197.157394	197.157394 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	1862	1862	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	287737344	287737344	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	41799	41799	✔
CityParkInputConsistentCount_Cnt_M_u16	41886	41886	✔
CityParkInputInvalidCount_Cnt_M_u16	40631	40631	✔
CityParkInputMsgTimer_mS_M_u32	1008472064	1008472064	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1008472064	1008472064	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1008472064	1008472064	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1008472064	1008472064	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1008472064	1008472064	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1008472064	1008472064	✔
ESPNTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ESPNodeAbsentFltAcc_Cnt_M_u16	39869	39869	✔
ESPNodeAbsentTimer_mS_M_u32	1008472064	1008472064	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	9	9	✔
EffacDefaultDiagTimer_mS_M_u32[1]	81	81	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	1008472064	1008472064	✔
ElecIntTimer_mS_M_u32[1]	458	458	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1008472064	1008472064	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1008472064	1008472064	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1008472064	1008472064	✔
IgnOnTimer_mS_M_u32	1008472064	1008472064	✔
IgnTimeOff_Sec_M_u32	487794345	487794345	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	737269248	737269248	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	116	116	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3889362432	3889362432	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	198	198	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2424575488	2424575488	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	8	8	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	772093440	772093440	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	366548480	366548480	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	126	126	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1735882240	1735882240	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	195	195	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	325621248	325621248	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	106	106	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	594425344	594425344	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1592579584	1592579584	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	1	1	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4266522112	4266522112	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	150	150	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1249842688	1249842688	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2921932288	2921932288	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	564.73407	564.73407	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	347.186798	347.186798	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	402.352905	402.352905	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	272.389801	272.389801	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	1862	1862	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	487794345	487794345	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	197.157394	197.157394 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	178.580704	178.580704	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.118 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2404397312
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	32036
AASNodeAbsentTimer_mS_M_u32	914383104
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	28759
ANGLEVOLANTSigValidCount_Cnt_M_u16	58002
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	8733
AngleVolantMsgTimer_mS_M_u32	2404397312
AngleVolantValidCount_Cnt_M_u16	12616
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	192.075455
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2260017408
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2056364288
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3701887232
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4087222528
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	25330
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	948228352
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	49446
CAVNodeAbsentTimer_mS_M_u32	2916778240
CDD_SrlComVehSpd_Kph_G_f32	147.410095
CMM388NTCEnableTimer_mS_M_u32	1195491584
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2411233536
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	53091
CMMNodeAbsentTimer_mS_M_u32	1715474688
CONSANGLECPKSigInvalidCount_Cnt_M_u16	20583
CONSANGLECPKSigValidCount_Cnt_M_u16	45491
CONSANGLECPK_Cnt_M_u16	21538
CONSANGLECPK_HwDeg_M_f32	730.450317
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21538
CPKVehicleSpeedMsgTimer_mS_M_u32	969093376
CPKVehicleSpeedValidCount_Cnt_M_u16	35337
CityParkInputConsistentCount_Cnt_M_u16	26844
CityParkInputInvalidCount_Cnt_M_u16	27792
CityParkInputMsgTimer_mS_M_u32	737269248
CityParkInputValidCount_Cnt_M_u16	10

Name	Input Value
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1393844480
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	53944
ComputerRazGCTSigInvalidTimer_mS_M_u32	2244018432
ComputerRazGCTSigValidCount_Cnt_M_u16	10541
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	24828
DMDFCTCPKSigValidCount_Cnt_M_u16	63104
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	46881
DMDRELAXECPKSigValidCount_Cnt_M_u16	36060
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	39520
DateInvalidTimer_mS_M_u32	2056364288
DiagMuxOnAbsentTimer_mS_M_u32	496431360
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4087222528
ESPNTCEnableTimer_mS_M_u32	3234685184
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	29931
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	20
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	99
ElecIntTimer_mS_M_u32[1]	761
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1580126464
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	64540
EtatMTSigValidCount_Cnt_M_u16	59219
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	30001
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	47613
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	19038
ISDAT4V2BSI552MsgTimer_mS_M_u32	2312376576
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	30721
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	52705
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	59219
ISDATBSI3F2MsgTimer_mS_M_u32	818737408
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	21099
ISDATBSI412MsgLenValidCount_Cnt_M_u16	32954
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	64540
ISDATBSI412MsgTimer_mS_M_u32	4035326208
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	14839
ISDATBSI432MsgLenValidCount_Cnt_M_u16	26239
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	6163
ISDATDIRASentFltAcc_Cnt_M_u16	62071
ISDATDIRASentTimer_mS_M_u32	969093376
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	33752
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	12616
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	32535
ISDYN2CMMMsgTimer_mS_M_u32	904880384
ISDYNAASChkSumInvalidCount_Cnt_M_u16	24558
ISDYNAASChkSumValidCount_Cnt_M_u16	31946
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	40291
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	15061
ISDYNAASMsgLenValidCount_Cnt_M_u16	23753
ISDYNAASMsgTimeValidCount_Cnt_M_u16	24558
ISDYNAASMsgTimer_mS_M_u32	3165503744
ISDYNABRChkSumInvalidCount_Cnt_M_u16	22821
ISDYNABRChkSumValidCount_Cnt_M_u16	37896
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	15497
ISDYNABRMsgCountValidCount_Cnt_M_u16	10149
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	54274
ISDYNABRMsgLenValidCount_Cnt_M_u16	17294
ISDYNABRMsgTimeValidCount_Cnt_M_u16	21538
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	719
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1323
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	59219
ISDYNCMM208MsgTimer_mS_M_u32	1313218816

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2727
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1429
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	28030
ISDYNCMM388MsgTimer_mS_M_u32	2614837504
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	48029
ISDYNVOLChkSumValidCount_Cnt_M_u16	14697
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	45874
ISDYNVOLMsgCountValidCount_Cnt_M_u16	42294
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	56144
ISDYNVOLMsgLenValidCount_Cnt_M_u16	29180
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	53091
ISDYNVOLMsgTimer_mS_M_u32	3073179904
IgnOnTimer_mS_M_u32	1584349440
IgnTimeOff_Sec_M_u32	1096096610
ManVehSpd_Kph_M_f32	363.855194
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	59
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	202
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1963651328
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	240
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2392936704
PrevISDATBSI412MsgDLCError_Cnt_M_u08	249
PrevISDATBSI412MsgRxTime_MSec_M_u32	1283948800
PrevISDATBSI432MsgDLCError_Cnt_M_u08	215
PrevISDATBSI432MsgRxTime_MSec_M_u32	2719047936
PrevISDATDIRAMsgTxTime_MSec_M_u32	3924525312
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	128
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3881144576
PrevISDYNAASMsgDLCError_Cnt_M_u08	2
PrevISDYNAASMsgRxTime_MSec_M_u32	2397241600
PrevISDYNABRMsgDLCError_Cnt_M_u08	121
PrevISDYNABRMsgRxTime_MSec_M_u32	2152153344
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	189
PrevISDYNCMM208MsgRxTime_MSec_M_u32	636748032
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	40
PrevISDYNCMM388MsgRxTime_MSec_M_u32	494952704
PrevISDYNVOLMsgDLCError_Cnt_M_u08	96
PrevISDYNVOLMsgRxTime_MSec_M_u32	3918561536
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2294034688
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	181.145493
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	56075
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	55679
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	22768
VitesseVehicleBVRampValidCount_Cnt_M_u16	26916
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	57788
VitesseVehicleBVSigValidCount_Cnt_M_u16	1463
VitesseVehicleBV_Kph_M_f32	31.3092995
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	28030
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	5330

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	546.507324
k_AASNTCEnableTimeout_mS_u16	57301
k_AASNodeAbsentDiag_Cnt_str.Threshold	656
k_AASNodeAbsentDiag_Cnt_str.PStep	34393
k_AASNodeAbsentDiag_Cnt_str.NStep	41691
k_AASNodeAbsentTimeout_mS_u16	23759
k_AASNodeTimeout_mS_u16	16511
k_ABSNodeTimeout_mS_u16	39245
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	54718
k_ANGLEVOLANTSigValidThresh_Cnt_u16	6534
k_AngleVolantInvalidThresh_Cnt_u16	46921
k_AngleVolantValidThresh_Cnt_u16	27792
k_BSI552MsgTimeout_mS_u16	37973
k_BSINTCEnableTimeout_mS_u16	3023
k_BSINodeAbsentDiag_Cnt_str.Threshold	26172
k_BSINodeAbsentDiag_Cnt_str.PStep	34417
k_BSINodeAbsentDiag_Cnt_str.NStep	15142
k_BSINodeAbsentTimeout_mS_u16	15861
k_BSINodeTimeout_mS_u16	6163
k_BattOvHi_Volt_f32	7.51140022
k_BattOvLo_Volt_f32	8.52750015
k_BattUvHi_Volt_f32	8.60470009
k_BattUvLo_Volt_f32	21.6807995
k_CAVNTCEnableTimeout_mS_u16	11934
k_CAVNodeAbsentDiag_Cnt_str.Threshold	42425
k_CAVNodeAbsentDiag_Cnt_str.PStep	27401
k_CAVNodeAbsentDiag_Cnt_str.NStep	60526
k_CAVNodeAbsentTimeout_mS_u16	57436
k_CAVNodeTimeout_mS_u16	24019
k_CMM388MsgTimeout_mS_u16	9252
k_CMM388NTCEnableTimeout_mS_u16	3728
k_CMMNTCEnableTimeout_mS_u16	62937
k_CMMNodeAbsentDiag_Cnt_str.Threshold	51970
k_CMMNodeAbsentDiag_Cnt_str.PStep	24146
k_CMMNodeAbsentDiag_Cnt_str.NStep	60776
k_CMMNodeAbsentTimeout_mS_u16	23870
k_CONSANGLECPKMax_HwDeg_f32	722.745483
k_CONSANGLECPKMin_HwDeg_f32	-772.332825
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	38014
k_CONSANGLECPKSigValidThresh_Cnt_u16	31698
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	4957
k_CPKVehicleSpeedValidThresh_Cnt_u16	46810
k_CityParkInputInvalidThresh_Cnt_u16	16003
k_CityParkInputValidThresh_Cnt_u16	26844
k_ComputerRazGCTSigValidThresh_Cnt_u16	1215
k_CptTemporelSigValidThresh_Cnt_u16	3359
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	31490
k_DMDFCTCPKSigValidThresh_Cnt_u16	10894
k_DMDFCTCPKValidCount_Cnt_u16	48666
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	32535
k_DMDRELAXECPKSigValidThresh_Cnt_u16	731
k_DMDRelaxeConsistentThresh_Cnt_u16	38841
k_DateValidThresh_Cnt_u16	19038
k_DefaultVehSpd_Kph_f32	53.9719009
k_DiagMuxOnAbsentTimeout_mS_u16	51632
k_EMNodeTimeout_mS_u16	26688
k_ESPNTCEnableTimeout_mS_u16	26770
k_ESPNodeAbsentDiag_Cnt_str.Threshold	31189
k_ESPNodeAbsentDiag_Cnt_str.PStep	45185
k_ESPNodeAbsentDiag_Cnt_str.NStep	53336
k_ESPNodeAbsentTimeout_mS_u16	29542
k_EtatMTSigInvalidThresh_Cnt_u16	11080
k_EtatMTSigValidThresh_Cnt_u16	51819
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	31788
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	43716
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	61633
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	16794
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	51258
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	19199
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	12048
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	11352
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	58507
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	6806

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	64134
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	44968
k_ISDATDIRASentDiag_Cnt_str.Threshold	38287
k_ISDATDIRASentDiag_Cnt_str.PStep	11594
k_ISDATDIRASentDiag_Cnt_str.NStep	1219
k_ISDATDIRASentTimeout_mS_u16	3217
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	54329
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	8733
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	32846
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	32805
k_ISDYNAASChkSumValidThresh_Cnt_u16	64264
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	58249
k_ISDYNAASMsgCountValidThresh_Cnt_u16	3749
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	3257
k_ISDYNAASMsgLenValidThresh_Cnt_u16	28691
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	30126
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	44600
k_ISDYNABRChkSumValidThresh_Cnt_u16	31300
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	2546
k_ISDYNABRMsgCountValidThresh_Cnt_u16	2669
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	13923
k_ISDYNABRMsgLenValidThresh_Cnt_u16	7147
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	37232
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	10911
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	47760
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	64258
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	5975
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	51602
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	48232
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	3250
k_ISDYNVOLChkSumValidThresh_Cnt_u16	12865
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	23780
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	36508
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	9352
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	51391
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	19180
k_IgnOnTimeout_mS_u16	9246
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	188.648193
k_PowerCutVehSpdLowThresh_Kph_f32	145.437302
k_PowerCutVehSpdLowTimeout_mS_u16	28785
k_VBattMaxAAS_Volt_f32	16.6315994
k_VBattMaxBSI_Volt_f32	13.7081003
k_VBattMaxCAV_Volt_f32	3.30439997
k_VBattMaxCMM388_Volt_f32	8.36900043
k_VBattMaxCMM_Volt_f32	16.2066994
k_VBattMaxESP_Volt_f32	10.0902004
k_VBattMinAAS_Volt_f32	18.5105991
k_VBattMinBSI_Volt_f32	10.0902004
k_VBattMinCAV_Volt_f32	30.0401993
k_VBattMinCMM388_Volt_f32	21.8717995
k_VBattMinCMM_Volt_f32	2.96350002
k_VBattMinESP_Volt_f32	16.2066994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	36955
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	65115
k_VitesseVehicleBVRampValidThresh_Cnt_u16	55858
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	8297
k_VitesseVehicleBVSigValidThresh_Cnt_u16	51353
k_VitesseVehicleBVSpeedPassThresh_kph_f32	436.910492
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	59430
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	5338
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2056364288
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	255
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	63428
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1401590528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSe	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	40
target_SrlComInput_Per1_Batt_Volt_f32.value	10.1838999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	391237888
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	69
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.289241791
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4204871936
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	863887616
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3857350912
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	13
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4192674048
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1467203840
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3868221696
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	65
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2403139840
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	63
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	71
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	88
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	164
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	228
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4255916288
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	28
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	44
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	121
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	133
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	182
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	192
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	229654784
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	116
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2618089728
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1677295872
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	16
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	32
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	52
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	57
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	133
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	239
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	893079808
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1096
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.998711824
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	644483
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	22.6308994
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	17069

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1401590528	1401590528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	656	656	✔
AASNodeAbsentTimer_mS_M_u32	1401590528	1401590528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1401590528	1401590528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	192.075455	192.075455	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1401590528	1401590528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1401590528	1401590528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1401590528	1401590528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1401590528	1401590528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26172	26172	✔
BSINodeAbsentTimer_mS_M_u32	1401590528	1401590528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1401590528	1401590528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1401590528	1401590528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1401590528	1401590528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1401590528	1401590528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1401590528	1401590528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	21538	21538	✔
CONSANGLECPK_HwDeg_M_f32	730.450317	730.450317 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1401590528	1401590528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1401590528	1401590528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1401590528	1401590528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1401590528	1401590528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1401590528	1401590528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1401590528	1401590528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1401590528	1401590528	✔
ESPNTCEnableTimer_mS_M_u32	1401590528	1401590528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	31189	31189	✔
ESPNodeAbsentTimer_mS_M_u32	1401590528	1401590528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	20	20	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	99	99	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	761	761	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1401590528	1401590528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1401590528	1401590528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1401590528	1401590528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1401590528	1401590528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1401590528	1401590528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1401590528	1401590528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1401590528	1401590528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1401590528	1401590528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1401590528	1401590528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1401590528	1401590528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1401590528	1401590528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1401590528	1401590528	✔
IgnOnTimer_mS_M_u32	1401590528	1401590528	✔
IgnTimeOff_Sec_M_u32	1096096610	1096096610	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4204871936	4204871936	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	110	110	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	863887616	863887616	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	135	135	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3857350912	3857350912	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	13	13	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4192674048	4192674048	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3924525312	3924525312	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	2	2	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3868221696	3868221696	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	65	65	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2403139840	2403139840	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	202	202	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4255916288	4255916288	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	107	107	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	229654784	229654784	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	116	116	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2618089728	2618089728	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	194	194	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1677295872	1677295872	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	893079808	893079808	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	181.145493	181.145493	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	31.3092995	31.3092995	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	546.507324	546.507324	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	192.075455	192.075455	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	21538	21538	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1096096610	1096096610	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	730.450317	730.450317 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.119 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3484561408
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	63540
AASNodeAbsentTimer_mS_M_u32	383885312
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	2205
ANGLEVOLANTSigValidCount_Cnt_M_u16	31914
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	11593
AngleVolantMsgTimer_mS_M_u32	3484561408
AngleVolantValidCount_Cnt_M_u16	29257
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	293.817444
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3913506816
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	531488768
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1747963904
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2991099904
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	23756
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4002697216
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	23726
CAVNodeAbsentTimer_mS_M_u32	1095974912
CDD_SrlComVehSpd_Kph_G_f32	534.295288
CMM388NTCEnableTimer_mS_M_u32	572358656
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2478391296
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	37303
CMMNodeAbsentTimer_mS_M_u32	1650626560
CONSANGLECPKSigInvalidCount_Cnt_M_u16	39786
CONSANGLECPKSigValidCount_Cnt_M_u16	33351
CONSANGLECPK_Cnt_M_u16	5882
CONSANGLECPK_HwDeg_M_f32	590.484009
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	5882
CPKVehicleSpeedMsgTimer_mS_M_u32	1549348864
CPKVehicleSpeedValidCount_Cnt_M_u16	63374

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	7053
CityParkInputInvalidCount_Cnt_M_u16	12657
CityParkInputMsgTimer_mS_M_u32	4204871936
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	287678464
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	18296
ComputerRazGCTSigInvalidTimer_mS_M_u32	1939849216
ComputerRazGCTSigValidCount_Cnt_M_u16	24218
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	1069
DMDFCTCPKSigValidCount_Cnt_M_u16	11874
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56383
DMDRELAXECPKSigValidCount_Cnt_M_u16	9676
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	57727
DateInvalidTimer_mS_M_u32	531488768
DiagMuxOnAbsentTimer_mS_M_u32	2950557696
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2991099904
ESPNTCEnableTimer_mS_M_u32	3959070720
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	39904
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	80
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1121
ElecIntTimer_mS_M_u32[1]	2237
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2778091520
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	15502
EtatMTSigValidCount_Cnt_M_u16	13735
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	54540
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	4457
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	10952
ISDAT4V2BSI552MsgTimer_mS_M_u32	1202098176
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	14429
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	37246
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13735
ISDATBSI3F2MsgTimer_mS_M_u32	3460034560
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	56865
ISDATBSI412MsgLenValidCount_Cnt_M_u16	28146
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	15502
ISDATBSI412MsgTimer_mS_M_u32	68169728
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	41467
ISDATBSI432MsgLenValidCount_Cnt_M_u16	5924
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	19431
ISDATDIRASentFltAcc_Cnt_M_u16	19643
ISDATDIRASentTimer_mS_M_u32	1549348864
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	57304
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	29257
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	54748
ISDYN2CMMMsgTimer_mS_M_u32	2492768256
ISDYNAASChkSumInvalidCount_Cnt_M_u16	63446
ISDYNAASChkSumValidCount_Cnt_M_u16	60419
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	23032
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	27553
ISDYNAASMsgLenValidCount_Cnt_M_u16	45190
ISDYNAASMsgTimeValidCount_Cnt_M_u16	63446
ISDYNAASMsgTimer_mS_M_u32	1910079488
ISDYNABRChkSumInvalidCount_Cnt_M_u16	23987
ISDYNABRChkSumValidCount_Cnt_M_u16	6088
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	36357
ISDYNABRMsgCountValidCount_Cnt_M_u16	6002
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	15513
ISDYNABRMsgLenValidCount_Cnt_M_u16	63670
ISDYNABRMsgTimeValidCount_Cnt_M_u16	5882

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	720
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1325
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13735
ISDYNCMM208MsgTimer_mS_M_u32	378560512
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2731
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1431
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	5543
ISDYNCMM388MsgTimer_mS_M_u32	1783693312
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	45512
ISDYNVOLChkSumValidCount_Cnt_M_u16	17189
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	25995
ISDYNVOLMsgCountValidCount_Cnt_M_u16	31296
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	15537
ISDYNVOLMsgLenValidCount_Cnt_M_u16	878
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	37303
ISDYNVOLMsgTimer_mS_M_u32	2405154816
IgnOnTimer_mS_M_u32	1922367488
IgnTimeOff_Sec_M_u32	2785065135
ManVehSpd_Kph_M_f32	655.340027
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	61
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	242
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2038558720
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	185
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4265529344
PrevISDATBSI412MsgDLCError_Cnt_M_u08	142
PrevISDATBSI412MsgRxTime_MSec_M_u32	1498169344
PrevISDATBSI432MsgDLCError_Cnt_M_u08	33
PrevISDATBSI432MsgRxTime_MSec_M_u32	1479450624
PrevISDATDIRAMsgTxTime_MSec_M_u32	287326208
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	232
PrevISDYN2CMMMsgRxTime_MSec_M_u32	354553856
PrevISDYNAASMsgDLCError_Cnt_M_u08	109
PrevISDYNAASMsgRxTime_MSec_M_u32	1614397440
PrevISDYNABRMsgDLCError_Cnt_M_u08	41
PrevISDYNABRMsgRxTime_MSec_M_u32	1829568512
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	125
PrevISDYNCMM208MsgRxTime_MSec_M_u32	520536064
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	61
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1642176512
PrevISDYNVOLMsgDLCError_Cnt_M_u08	143
PrevISDYNVOLMsgRxTime_MSec_M_u32	3861987328
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2473472000
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	602.301819
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	58111
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	37476
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	15696
VitesseVehicleBVRampValidCount_Cnt_M_u16	46965
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	34926

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	59195
VitesseVehicleBV_Kph_M_f32	177.545105
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	5543
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	19052
VitesseVehiculeRoues_Kph_M_f32	527.901978
k_AASNTCEnableTimeout_mS_u16	65505
k_AASNodeAbsentDiag_Cnt_str.Threshold	42794
k_AASNodeAbsentDiag_Cnt_str.PStep	19588
k_AASNodeAbsentDiag_Cnt_str.NStep	14840
k_AASNodeAbsentTimeout_mS_u16	52148
k_AASNodeTimeout_mS_u16	23908
k_ABSNodeTimeout_mS_u16	57146
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	43686
k_ANGLEVOLANTSigValidThresh_Cnt_u16	55823
k_AngleVolantInvalidThresh_Cnt_u16	52422
k_AngleVolantValidThresh_Cnt_u16	12657
k_BSI552MsgTimeout_mS_u16	38883
k_BSINTCEnableTimeout_mS_u16	35955
k_BSINodeAbsentDiag_Cnt_str.Threshold	26212
k_BSINodeAbsentDiag_Cnt_str.PStep	34400
k_BSINodeAbsentDiag_Cnt_str.NStep	15165
k_BSINodeAbsentTimeout_mS_u16	14785
k_BSINodeTimeout_mS_u16	19431
k_BattOvHi_Volt_f32	5.38089991
k_BattOvLo_Volt_f32	16.5195999
k_BattUvHi_Volt_f32	25.7777004
k_BattUvLo_Volt_f32	14.3206997
k_CAVNTCEnableTimeout_mS_u16	41799
k_CAVNodeAbsentDiag_Cnt_str.Threshold	48391
k_CAVNodeAbsentDiag_Cnt_str.PStep	23311
k_CAVNodeAbsentDiag_Cnt_str.NStep	11543
k_CAVNodeAbsentTimeout_mS_u16	22284
k_CAVNodeTimeout_mS_u16	8998
k_CMM388MsgTimeout_mS_u16	820
k_CMM388NTCEnableTimeout_mS_u16	62448
k_CMMNTCEnableTimeout_mS_u16	7893
k_CMMNodeAbsentDiag_Cnt_str.Threshold	64691
k_CMMNodeAbsentDiag_Cnt_str.PStep	23675
k_CMMNodeAbsentDiag_Cnt_str.NStep	37682
k_CMMNodeAbsentTimeout_mS_u16	8488
k_CONSANGLECPKMax_HwDeg_f32	356.69931
k_CONSANGLECPKMin_HwDeg_f32	-393.019989
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	41127
k_CONSANGLECPKSigValidThresh_Cnt_u16	5484
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	56522
k_CPKVehicleSpeedValidThresh_Cnt_u16	11476
k_CityParkInputInvalidThresh_Cnt_u16	42393
k_CityParkInputValidThresh_Cnt_u16	7053
k_ComputerRazGCTSigValidThresh_Cnt_u16	2595
k_CptTemporelSigValidThresh_Cnt_u16	19396
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	18329
k_DMDFCTCPKSigValidThresh_Cnt_u16	17334
k_DMDFCTCPKValidCount_Cnt_u16	60244
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	54748
k_DMDRELAXECPKSigValidThresh_Cnt_u16	13649
k_DMDRelaxeConsistentThresh_Cnt_u16	28343
k_DateValidThresh_Cnt_u16	10952
k_DefaultVehSpd_Kph_f32	198.220001
k_DiagMuxOnAbsentTimeout_mS_u16	28240
k_EMNodeTimeout_mS_u16	63455
k_ESPNTCEnableTimeout_mS_u16	5738
k_ESPNodeAbsentDiag_Cnt_str.Threshold	23704
k_ESPNodeAbsentDiag_Cnt_str.PStep	20303
k_ESPNodeAbsentDiag_Cnt_str.NStep	26818
k_ESPNodeAbsentTimeout_mS_u16	32432
k_EtatMTSigInvalidThresh_Cnt_u16	13130
k_EtatMTSigValidThresh_Cnt_u16	49311
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	40541
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	19798
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	22494
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	32658
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	18035
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	17509

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	26288
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	27033
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	62015
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	37790
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	36495
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	19305
k_ISDATDIRASentDiag_Cnt_str.Threshold	4099
k_ISDATDIRASentDiag_Cnt_str.PStep	41674
k_ISDATDIRASentDiag_Cnt_str.NStep	32409
k_ISDATDIRASentTimeout_mS_u16	62319
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	25014
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	11593
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	48950
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	59571
k_ISDYNAASChkSumValidThresh_Cnt_u16	58056
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	39173
k_ISDYNAASMsgCountValidThresh_Cnt_u16	25202
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	37623
k_ISDYNAASMsgLenValidThresh_Cnt_u16	7848
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	26007
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	1527
k_ISDYNABRChkSumValidThresh_Cnt_u16	44180
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	26572
k_ISDYNABRMsgCountValidThresh_Cnt_u16	12569
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	23735
k_ISDYNABRMsgLenValidThresh_Cnt_u16	42720
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	26640
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	17475
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	31154
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	63963
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	5021
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	51114
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	41449
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	35660
k_ISDYNVOLChkSumValidThresh_Cnt_u16	13661
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	2037
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	30732
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	29514
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	16739
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	57630
k_IgnOnTimeout_mS_u16	62728
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	206.691193
k_PowerCutVehSpdLowThresh_Kph_f32	248.324005
k_PowerCutVehSpdLowTimeout_mS_u16	48653
k_VBattMaxAAS_Volt_f32	23.5993004
k_VBattMaxBSI_Volt_f32	13.8717003
k_VBattMaxCAV_Volt_f32	26.4237995
k_VBattMaxCMM388_Volt_f32	21.6067009
k_VBattMaxCMM_Volt_f32	29.1278
k_VBattMaxESP_Volt_f32	2.07019997
k_VBattMinAAS_Volt_f32	23.4729004
k_VBattMinBSI_Volt_f32	2.07019997
k_VBattMinCAV_Volt_f32	28.0396004
k_VBattMinCMM388_Volt_f32	9.29660034
k_VBattMinCMM_Volt_f32	0.118299998
k_VBattMinESP_Volt_f32	29.1278
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	13648
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	50705
k_VitesseVehicleBVRampValidThresh_Cnt_u16	61579
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	36389
k_VitesseVehicleBVSigValidThresh_Cnt_u16	12374
k_VitesseVehicleBVSpeedPassThresh_kph_f32	279.190002
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	59310
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	3155
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	531488768
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	155
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	56468
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3742042624
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	61
target_SrlComInput_Per1_Batt_Volt_f32.value	4.34040022
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3324858368
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	32
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.968864739
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3858694144
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	160
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4125696000
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3642966016
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	184
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3618463744
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	965181440
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1186045952
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	236
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1194049536
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	48
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	80
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	200
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	211
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	543055872
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	24
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	62
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	166
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2832334848
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	138
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3090948096
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	122
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1526087680
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	7
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	17
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	48
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	85
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	130
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	169
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4067479552
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3607
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.00300238305
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	771925
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	226.993195
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	46105

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3742042624	3742042624	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	42794	42794	✔
AASNodeAbsentTimer_mS_M_u32	3742042624	3742042624	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	11595	11595	✔
AngleVolantMsgTimer_mS_M_u32	3742042624	3742042624	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	293.817444	293.817444	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3742042624	3742042624	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3742042624	3742042624	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3742042624	3742042624	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3742042624	3742042624	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26212	26212	✔
BSINodeAbsentTimer_mS_M_u32	3742042624	3742042624	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3742042624	3742042624	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3742042624	3742042624	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3742042624	3742042624	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3742042624	3742042624	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3742042624	3742042624	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	5882	5882	✔
CONSANGLECPK_HwDeg_M_f32	590.484009	590.484009 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	5882	5882	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1549348864	1549348864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	63374	63374	✔
CityParkInputConsistentCount_Cnt_M_u16	7053	7053	✔
CityParkInputInvalidCount_Cnt_M_u16	12659	12659	✔
CityParkInputMsgTimer_mS_M_u32	3742042624	3742042624	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3742042624	3742042624	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3742042624	3742042624	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3742042624	3742042624	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3742042624	3742042624	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3742042624	3742042624	✔
ESPNTCEnableTimer_mS_M_u32	3742042624	3742042624	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	23704	23704	✔
ESPNodeAbsentTimer_mS_M_u32	3742042624	3742042624	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	80	80	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3742042624	3742042624	✔
ElecIntTimer_mS_M_u32[1]	2237	2237	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3742042624	3742042624	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3742042624	3742042624	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3742042624	3742042624	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3742042624	3742042624	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3742042624	3742042624	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3742042624	3742042624	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3742042624	3742042624	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3742042624	3742042624	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3742042624	3742042624	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3742042624	3742042624	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3742042624	3742042624	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3742042624	3742042624	✔
IgnOnTimer_mS_M_u32	3742042624	3742042624	✔
IgnTimeOff_Sec_M_u32	2785065135	2785065135	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	190	190	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3858694144	3858694144	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	160	160	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4125696000	4125696000	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	48	48	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3642966016	3642966016	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	184	184	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3618463744	3618463744	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	287326208	287326208	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	206	206	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1186045952	1186045952	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	236	236	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1194049536	1194049536	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	211	211	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	543055872	543055872	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	9	9	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2832334848	2832334848	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	138	138	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3090948096	3090948096	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	122	122	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1526087680	1526087680	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4067479552	4067479552	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	602.301819	602.301819	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	177.545105	177.545105	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	527.901978	527.901978	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	293.817444	293.817444	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	5882	5882	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2785065135	2785065135	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	590.484009	590.484009 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	198.220001	198.220001	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.120 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	424162048
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	51648
AASNodeAbsentTimer_mS_M_u32	2373575424
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	55943
ANGLEVOLANTSigValidCount_Cnt_M_u16	7712
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	48769
AngleVolantMsgTimer_mS_M_u32	424162048
AngleVolantValidCount_Cnt_M_u16	38913
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	297.385468
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3444876032
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4095025920
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3461305088
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1124406016
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	23034
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1830933248
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	2771
CAVNodeAbsentTimer_mS_M_u32	1554318080
CDD_SrlComVehSpd_Kph_G_f32	65.1924973
CMM388NTCEnableTimer_mS_M_u32	3007726336
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2104689408
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	19576
CMMNodeAbsentTimer_mS_M_u32	448205568
CONSANGLECPKSigInvalidCount_Cnt_M_u16	35101
CONSANGLECPKSigValidCount_Cnt_M_u16	46151
CONSANGLECPK_Cnt_M_u16	33326
CONSANGLECPK_HwDeg_M_f32	-735.166504
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	33326
CPKVehicleSpeedMsgTimer_mS_M_u32	3478336256
CPKVehicleSpeedValidCount_Cnt_M_u16	31132
CityParkInputConsistentCount_Cnt_M_u16	44085

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	1931
CityParkInputMsgTimer_mS_M_u32	3858694144
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2930631424
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	60404
ComputerRazGCTSigInvalidTimer_mS_M_u32	2545910528
ComputerRazGCTSigValidCount_Cnt_M_u16	22286
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	32599
DMDFCTCPKSigValidCount_Cnt_M_u16	16504
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	26529
DMDRELAXECPKSigValidCount_Cnt_M_u16	10938
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	19166
DateInvalidTimer_mS_M_u32	4095025920
DiagMuxOnAbsentTimer_mS_M_u32	3620008704
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1124406016
ESPNTCEnableTimer_mS_M_u32	2989417216
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	15805
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	150
EffacDefaultDiagTimer_mS_M_u32[1]	1150
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	41
ElecIntTimer_mS_M_u32[1]	48
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3491484416
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	47346
EtatMTSigValidCount_Cnt_M_u16	40295
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	58423
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	3809
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	25414
ISDAT4V2BSI552MsgTimer_mS_M_u32	2062226176
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	30471
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	23396
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	40295
ISDATBSI3F2MsgTimer_mS_M_u32	1957360384
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	59066
ISDATBSI412MsgLenValidCount_Cnt_M_u16	59143
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	47346
ISDATBSI412MsgTimer_mS_M_u32	1949184768
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	11180
ISDATBSI432MsgLenValidCount_Cnt_M_u16	56305
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	24872
ISDATDIRASentFltAcc_Cnt_M_u16	44716
ISDATDIRASentTimer_mS_M_u32	3478336256
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	8084
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	38913
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	34378
ISDYN2CMMMsgTimer_mS_M_u32	2690704128
ISDYNAASChkSumInvalidCount_Cnt_M_u16	53978
ISDYNAASChkSumValidCount_Cnt_M_u16	5651
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	23796
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	27130
ISDYNAASMsgLenValidCount_Cnt_M_u16	39692
ISDYNAASMsgTimeValidCount_Cnt_M_u16	53978
ISDYNAASMsgTimer_mS_M_u32	3021095680
ISDYNABRChkSumInvalidCount_Cnt_M_u16	44228
ISDYNABRChkSumValidCount_Cnt_M_u16	15941
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	35917
ISDYNABRMsgCountValidCount_Cnt_M_u16	4038
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	8592
ISDYNABRMsgLenValidCount_Cnt_M_u16	52474
ISDYNABRMsgTimeValidCount_Cnt_M_u16	33326
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	721

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1327
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	40295
ISDYNCMM208MsgTimer_mS_M_u32	3110970112
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2735
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1433
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	42471
ISDYNCMM388MsgTimer_mS_M_u32	145474304
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	15875
ISDYNVOLChkSumValidCount_Cnt_M_u16	27053
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	21309
ISDYNVOLMsgCountValidCount_Cnt_M_u16	21726
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	57162
ISDYNVOLMsgLenValidCount_Cnt_M_u16	60115
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	19576
ISDYNVOLMsgTimer_mS_M_u32	881558272
IgnOnTimer_mS_M_u32	4292854528
IgnTimeOff_Sec_M_u32	2106858607
ManVehSpd_Kph_M_f32	12.1301003
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	63
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	50
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	181990144
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	56
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	136467200
PrevISDATBSI412MsgDLCError_Cnt_M_u08	234
PrevISDATBSI412MsgRxTime_MSec_M_u32	951714560
PrevISDATBSI432MsgDLCError_Cnt_M_u08	162
PrevISDATBSI432MsgRxTime_MSec_M_u32	1033036544
PrevISDATDIRAMsgTxTime_MSec_M_u32	1631453952
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	7
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1618514688
PrevISDYNAASMsgDLCError_Cnt_M_u08	90
PrevISDYNAASMsgRxTime_MSec_M_u32	3119612672
PrevISDYNABRMsgDLCError_Cnt_M_u08	196
PrevISDYNABRMsgRxTime_MSec_M_u32	4034380544
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	104
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4052386560
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	35
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2893669120
PrevISDYNVOLMsgDLCError_Cnt_M_u08	60
PrevISDYNVOLMsgRxTime_MSec_M_u32	1711997696
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3188994816
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	9.87489986
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	64480
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	60786
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	28909
VitesseVehicleBVRampValidCount_Cnt_M_u16	575
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	57108
VitesseVehicleBVSigValidCount_Cnt_M_u16	25197

Name	Input Value
VitesseVehicleBV_Kph_M_f32	625.241211
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	42471
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	34648
VitesseVehiculeRoues_Kph_M_f32	449.717896
k_AASNTCEnableTimeout_mS_u16	9081
k_AASNodeAbsentDiag_Cnt_str.Threshold	57143
k_AASNodeAbsentDiag_Cnt_str.PStep	15615
k_AASNodeAbsentDiag_Cnt_str.NStep	35772
k_AASNodeAbsentTimeout_mS_u16	63424
k_AASNodeTimeout_mS_u16	35954
k_ABSNodeTimeout_mS_u16	25136
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	32171
k_ANGLEVOLANTSigValidThresh_Cnt_u16	65328
k_AngleVolantInvalidThresh_Cnt_u16	49931
k_AngleVolantValidThresh_Cnt_u16	1931
k_BSI552MsgTimeout_mS_u16	15091
k_BSINTCEnableTimeout_mS_u16	19524
k_BSINodeAbsentDiag_Cnt_str.Threshold	26252
k_BSINodeAbsentDiag_Cnt_str.PStep	34383
k_BSINodeAbsentDiag_Cnt_str.NStep	15188
k_BSINodeAbsentTimeout_mS_u16	31001
k_BSINodeTimeout_mS_u16	24872
k_BattOvHi_Volt_f32	30.2740002
k_BattOvLo_Volt_f32	19.2966995
k_BattUvHi_Volt_f32	28.0531006
k_BattUvLo_Volt_f32	11.6113005
k_CAVNTCEnableTimeout_mS_u16	35337
k_CAVNodeAbsentDiag_Cnt_str.Threshold	65432
k_CAVNodeAbsentDiag_Cnt_str.PStep	15257
k_CAVNodeAbsentDiag_Cnt_str.NStep	41687
k_CAVNodeAbsentTimeout_mS_u16	5049
k_CAVNodeTimeout_mS_u16	57833
k_CMM388MsgTimeout_mS_u16	43200
k_CMM388NTCEnableTimeout_mS_u16	50828
k_CMMNTCEnableTimeout_mS_u16	41887
k_CMMNodeAbsentDiag_Cnt_str.Threshold	20987
k_CMMNodeAbsentDiag_Cnt_str.PStep	50556
k_CMMNodeAbsentDiag_Cnt_str.NStep	21870
k_CMMNodeAbsentTimeout_mS_u16	62244
k_CONSANGLECPKMax_HwDeg_f32	730.992188
k_CONSANGLECPKMin_HwDeg_f32	-42.9874001
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	1255
k_CONSANGLECPKSigValidThresh_Cnt_u16	9816
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	9792
k_CPKVehicleSpeedValidThresh_Cnt_u16	34465
k_CityParkInputInvalidThresh_Cnt_u16	60690
k_CityParkInputValidThresh_Cnt_u16	44085
k_ComputerRazGCTSigValidThresh_Cnt_u16	39349
k_CptTemporelSigValidThresh_Cnt_u16	50322
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	144
k_DMDFCTCPKSigValidThresh_Cnt_u16	60410
k_DMDFCTCPKValidCount_Cnt_u16	52834
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	34378
k_DMDRELAXECPKSigValidThresh_Cnt_u16	42923
k_DMDRelaxeConsistentThresh_Cnt_u16	4985
k_DateValidThresh_Cnt_u16	25414
k_DefaultVehSpd_Kph_f32	118.210297
k_DiagMuxOnAbsentTimeout_mS_u16	21548
k_EMNodeTimeout_mS_u16	34750
k_ESPNTCEnableTimeout_mS_u16	52639
k_ESPNodeAbsentDiag_Cnt_str.Threshold	27947
k_ESPNodeAbsentDiag_Cnt_str.PStep	45281
k_ESPNodeAbsentDiag_Cnt_str.NStep	55711
k_ESPNodeAbsentTimeout_mS_u16	64140
k_EtatMTSigInvalidThresh_Cnt_u16	18431
k_EtatMTSigValidThresh_Cnt_u16	24512
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	60807
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	12380
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	31554
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	46440
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	20613
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	50158
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	61837

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	63634
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	19168
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	40002
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	56111
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	4065
k_ISDATDIRASentDiag_Cnt_str.Threshold	40739
k_ISDATDIRASentDiag_Cnt_str.PStep	47335
k_ISDATDIRASentDiag_Cnt_str.NStep	57041
k_ISDATDIRASentTimeout_mS_u16	56208
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	16634
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	48769
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	827
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	3012
k_ISDYNAASChkSumValidThresh_Cnt_u16	56645
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	27469
k_ISDYNAASMsgCountValidThresh_Cnt_u16	11974
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	7416
k_ISDYNAASMsgLenValidThresh_Cnt_u16	22694
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	31896
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	48502
k_ISDYNABRChkSumValidThresh_Cnt_u16	43360
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	14586
k_ISDYNABRMsgCountValidThresh_Cnt_u16	31955
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	60280
k_ISDYNABRMsgLenValidThresh_Cnt_u16	7357
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	29678
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	59412
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	38919
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	21261
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	47495
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	15648
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	38435
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	19257
k_ISDYNVOLChkSumValidThresh_Cnt_u16	64710
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	36222
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	11641
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	1214
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	27187
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	6212
k_IgnOnTimeout_mS_u16	65029
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	135.296707
k_PowerCutVehSpdLowThresh_Kph_f32	18.3981991
k_PowerCutVehSpdLowTimeout_mS_u16	39157
k_VBattMaxAAS_Volt_f32	5.88450003
k_VBattMaxBSI_Volt_f32	24.5613995
k_VBattMaxCAV_Volt_f32	9.88290024
k_VBattMaxCMM388_Volt_f32	26.2031994
k_VBattMaxCMM_Volt_f32	9.53730011
k_VBattMaxESP_Volt_f32	28.9319
k_VBattMinAAS_Volt_f32	22.7315998
k_VBattMinBSI_Volt_f32	28.9319
k_VBattMinCAV_Volt_f32	23.5655994
k_VBattMinCMM388_Volt_f32	11.5387001
k_VBattMinCMM_Volt_f32	5.78350019
k_VBattMinESP_Volt_f32	9.53730011
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	44588
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	27562
k_VitesseVehicleBVRampValidThresh_Cnt_u16	45629
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	34989
k_VitesseVehicleBVSigValidThresh_Cnt_u16	53722
k_VitesseVehicleBVSpeedPassThresh_kph_f32	303.000702
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	27091
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	64421
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	4095025920
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	51
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8161
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	4146439424
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	35
target_SrlComInput_Per1_Batt_Volt_f32.value	10.4626999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2320945920
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	204
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.762989938
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	211
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3449930496
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1852007168
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3577021184
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	706126592
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2500346624
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	23
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1040835328
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1293648640
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	52
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	121
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	122
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	145
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	172
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1409524480
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	77
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	151
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	222
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2435367680
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	862610176
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	76
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1539048192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	89
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	114
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	140
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	158
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1938576128
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1388
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.547174871
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	854078
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	227.640701

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	28818		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	4146439424	4146439424	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4146439424	4146439424	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	48771	48771	✔
AngleVolantMsgTimer_mS_M_u32	4146439424	4146439424	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	297.385468	297.385468	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	4146439424	4146439424	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4146439424	4146439424	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4146439424	4146439424	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4146439424	4146439424	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	4146439424	4146439424	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4146439424	4146439424	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4146439424	4146439424	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4146439424	4146439424	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4146439424	4146439424	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4146439424	4146439424	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	33326	33326	✔
CONSANGLECPK_HwDeg_M_f32	-735.166504	-735.166504 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	33326	33326	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3478336256	3478336256	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	31132	31132	✔
CityParkInputConsistentCount_Cnt_M_u16	44085	44085	✔
CityParkInputInvalidCount_Cnt_M_u16	1933	1933	✔
CityParkInputMsgTimer_mS_M_u32	4146439424	4146439424	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4146439424	4146439424	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4146439424	4146439424	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4146439424	4146439424	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4146439424	4146439424	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4146439424	4146439424	✔
ESPNTCEnableTimer_mS_M_u32	4146439424	4146439424	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4146439424	4146439424	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	150	150	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	1150	1150	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	41	41	✔
ElecIntTimer_mS_M_u32[1]	48	48	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4146439424	4146439424	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4146439424	4146439424	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4146439424	4146439424	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4146439424	4146439424	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4146439424	4146439424	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	4146439424	4146439424	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4146439424	4146439424	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4146439424	4146439424	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4146439424	4146439424	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4146439424	4146439424	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4146439424	4146439424	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4146439424	4146439424	✔
IgnOnTimer_mS_M_u32	4292854528	4292854528	✔
IgnTimeOff_Sec_M_u32	2106858607	2106858607	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	211	211	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3449930496	3449930496	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	95	95	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1852007168	1852007168	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	30	30	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3577021184	3577021184	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	55	55	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	706126592	706126592	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1631453952	1631453952	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	23	23	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1040835328	1040835328	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	46	46	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1293648640	1293648640	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	233	233	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1409524480	1409524480	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	253	253	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2435367680	2435367680	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	172	172	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	862610176	862610176	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	76	76	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1539048192	1539048192	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1938576128	1938576128	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	9.87489986	9.87489986	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	625.241211	625.241211	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	449.717896	449.717896	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	297.385468	297.385468	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	33326	33326	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2106858607	2106858607	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-735.166504	-735.166504 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	118.210297	118.210297	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.121 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	206711296
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	31976
AASNodeAbsentTimer_mS_M_u32	3531414016
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	33941
ANGLEVOLANTSigValidCount_Cnt_M_u16	55945
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	58021
AngleVolantMsgTimer_mS_M_u32	206711296
AngleVolantValidCount_Cnt_M_u16	23718
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	500.96286
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3991722496
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	464214528
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1908197888
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	446401024
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	37436
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	4282731008
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	28207
CAVNodeAbsentTimer_mS_M_u32	2038151680
CDD_SrlComVehSpd_Kph_G_f32	13.1618996
CMM388NTCEnableTimer_mS_M_u32	2325215744
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3474045440
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	1793
CMMNodeAbsentTimer_mS_M_u32	3682961920
CONSANGLECPKSigInvalidCount_Cnt_M_u16	17360
CONSANGLECPKSigValidCount_Cnt_M_u16	8981
CONSANGLECPK_Cnt_M_u16	5472
CONSANGLECPK_HwDeg_M_f32	575.870483
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	5472
CPKVehicleSpeedMsgTimer_mS_M_u32	3593546240
CPKVehicleSpeedValidCount_Cnt_M_u16	924

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	61450
CityParkInputInvalidCount_Cnt_M_u16	1800
CityParkInputMsgTimer_mS_M_u32	3449930496
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1054939648
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	58956
ComputerRazGCTSigInvalidTimer_mS_M_u32	1378630144
ComputerRazGCTSigValidCount_Cnt_M_u16	37759
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	53156
DMDFCTCPKSigValidCount_Cnt_M_u16	52480
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	50503
DMDRELAXECPKSigValidCount_Cnt_M_u16	40123
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	17037
DateInvalidTimer_mS_M_u32	464214528
DiagMuxOnAbsentTimer_mS_M_u32	3017533952
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	446401024
ESPNTCEnableTimer_mS_M_u32	2019432960
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	1010
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	64
EffacDefaultDiagTimer_mS_M_u32[1]	894
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	3
ElecIntTimer_mS_M_u32[1]	8
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1045907968
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	31379
EtatMTSigValidCount_Cnt_M_u16	24051
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	6786
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	64327
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	7318
ISDAT4V2BSI552MsgTimer_mS_M_u32	2330561024
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	11220
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	44925
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	24051
ISDATBSI3F2MsgTimer_mS_M_u32	4113164800
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	47546
ISDATBSI412MsgLenValidCount_Cnt_M_u16	43411
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	31379
ISDATBSI412MsgTimer_mS_M_u32	329263616
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	14693
ISDATBSI432MsgLenValidCount_Cnt_M_u16	63830
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	65328
ISDATDIRASentFltAcc_Cnt_M_u16	9892
ISDATDIRASentTimer_mS_M_u32	3593546240
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	21806
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	23718
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	18123
ISDYN2CMMMsgTimer_mS_M_u32	4123531776
ISDYNAASChkSumInvalidCount_Cnt_M_u16	18842
ISDYNAASChkSumValidCount_Cnt_M_u16	8367
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	39373
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	44218
ISDYNAASMsgLenValidCount_Cnt_M_u16	6726
ISDYNAASMsgTimeValidCount_Cnt_M_u16	18842
ISDYNAASMsgTimer_mS_M_u32	3090414080
ISDYNABRChkSumInvalidCount_Cnt_M_u16	39262
ISDYNABRChkSumValidCount_Cnt_M_u16	42394
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	43329
ISDYNABRMsgCountValidCount_Cnt_M_u16	49046
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	1655
ISDYNABRMsgLenValidCount_Cnt_M_u16	25852
ISDYNABRMsgTimeValidCount_Cnt_M_u16	5472

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	722
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1329
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	24051
ISDYNCMM208MsgTimer_mS_M_u32	3449936384
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2739
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1435
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	19188
ISDYNCMM388MsgTimer_mS_M_u32	6781440
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	15646
ISDYNVOLChkSumValidCount_Cnt_M_u16	6883
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	27634
ISDYNVOLMsgCountValidCount_Cnt_M_u16	42958
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	37707
ISDYNVOLMsgLenValidCount_Cnt_M_u16	20847
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	1793
ISDYNVOLMsgTimer_mS_M_u32	2882025984
IgnOnTimer_mS_M_u32	3939203584
IgnTimeOff_Sec_M_u32	331718046
ManVehSpd_Kph_M_f32	548.59082
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	65
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	57
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1788865024
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	29
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3494103552
PrevISDATBSI412MsgDLCError_Cnt_M_u08	115
PrevISDATBSI412MsgRxTime_MSec_M_u32	2034022912
PrevISDATBSI432MsgDLCError_Cnt_M_u08	245
PrevISDATBSI432MsgRxTime_MSec_M_u32	1714559488
PrevISDATDIRAMsgTxTime_MSec_M_u32	263240192
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	151
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4030794240
PrevISDYNAASMsgDLCError_Cnt_M_u08	242
PrevISDYNAASMsgRxTime_MSec_M_u32	865483264
PrevISDYNABRMsgDLCError_Cnt_M_u08	230
PrevISDYNABRMsgRxTime_MSec_M_u32	2030270976
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	25
PrevISDYNCMM208MsgRxTime_MSec_M_u32	818625024
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	245
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1971132928
PrevISDYNVOLMsgDLCError_Cnt_M_u08	118
PrevISDYNVOLMsgRxTime_MSec_M_u32	1967766016
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1307453952
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	389.348602
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	3848
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	15124
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	9185
VitesseVehicleBVRampValidCount_Cnt_M_u16	28845
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	60142

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	33186
VitesseVehicleBV_Kph_M_f32	519.961121
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	19188
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	10081
VitesseVehiculeRoues_Kph_M_f32	388.90921
k_AASNTCEnableTimeout_mS_u16	7551
k_AASNodeAbsentDiag_Cnt_str.Threshold	13692
k_AASNodeAbsentDiag_Cnt_str.PStep	37531
k_AASNodeAbsentDiag_Cnt_str.NStep	49438
k_AASNodeAbsentTimeout_mS_u16	63849
k_AASNodeTimeout_mS_u16	24084
k_ABSNodeTimeout_mS_u16	51993
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	65384
k_ANGLEVOLANTSigValidThresh_Cnt_u16	19353
k_AngleVolantInvalidThresh_Cnt_u16	11272
k_AngleVolantValidThresh_Cnt_u16	1800
k_BSI552MsgTimeout_mS_u16	14480
k_BSINTCEnableTimeout_mS_u16	14237
k_BSINodeAbsentDiag_Cnt_str.Threshold	26292
k_BSINodeAbsentDiag_Cnt_str.PStep	34366
k_BSINodeAbsentDiag_Cnt_str.NStep	15211
k_BSINodeAbsentTimeout_mS_u16	4829
k_BSINodeTimeout_mS_u16	65328
k_BattOvHi_Volt_f32	28.0590992
k_BattOvLo_Volt_f32	26.1739998
k_BattUvHi_Volt_f32	20.3125992
k_BattUvLo_Volt_f32	27.0769997
k_CAVNTCEnableTimeout_mS_u16	63374
k_CAVNodeAbsentDiag_Cnt_str.Threshold	36466
k_CAVNodeAbsentDiag_Cnt_str.PStep	63526
k_CAVNodeAbsentDiag_Cnt_str.NStep	35427
k_CAVNodeAbsentTimeout_mS_u16	27517
k_CAVNodeTimeout_mS_u16	26988
k_CMM388MsgTimeout_mS_u16	57320
k_CMM388NTCEnableTimeout_mS_u16	46724
k_CMMNTCEnableTimeout_mS_u16	1548
k_CMMNodeAbsentDiag_Cnt_str.Threshold	784
k_CMMNodeAbsentDiag_Cnt_str.PStep	20486
k_CMMNodeAbsentDiag_Cnt_str.NStep	25575
k_CMMNodeAbsentTimeout_mS_u16	5117
k_CONSANGLECPKMax_HwDeg_f32	168.837708
k_CONSANGLECPKMin_HwDeg_f32	-138.810394
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	11764
k_CONSANGLECPKSigValidThresh_Cnt_u16	19041
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	18602
k_CPKVehicleSpeedValidThresh_Cnt_u16	13829
k_CityParkInputInvalidThresh_Cnt_u16	36980
k_CityParkInputValidThresh_Cnt_u16	61450
k_ComputerRazGCTSigValidThresh_Cnt_u16	64458
k_CptTemporelSigValidThresh_Cnt_u16	44019
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	26999
k_DMDFCTCPKSigValidThresh_Cnt_u16	2044
k_DMDFCTCPKValidCount_Cnt_u16	54532
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	18123
k_DMDRELAXECPKSigValidThresh_Cnt_u16	9063
k_DMDRelaxeConsistentThresh_Cnt_u16	38909
k_DateValidThresh_Cnt_u16	7318
k_DefaultVehSpd_Kph_f32	52.0363007
k_DiagMuxOnAbsentTimeout_mS_u16	5990
k_EMNodeTimeout_mS_u16	3053
k_ESPNTCEnableTimeout_mS_u16	21963
k_ESPNodeAbsentDiag_Cnt_str.Threshold	32991
k_ESPNodeAbsentDiag_Cnt_str.PStep	49717
k_ESPNodeAbsentDiag_Cnt_str.NStep	18612
k_ESPNodeAbsentTimeout_mS_u16	40389
k_EtatMTSigInvalidThresh_Cnt_u16	29613
k_EtatMTSigValidThresh_Cnt_u16	60713
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	52949
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	5910
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	63203
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	13489
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	37914
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	61982

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	43970
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	26483
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	43977
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	5924
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	51996
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	60229
k_ISDATDIRASentDiag_Cnt_str.Threshold	58959
k_ISDATDIRASentDiag_Cnt_str.PStep	33467
k_ISDATDIRASentDiag_Cnt_str.NStep	17654
k_ISDATDIRASentTimeout_mS_u16	15610
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	64506
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58021
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	9463
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	31838
k_ISDYNAASChkSumValidThresh_Cnt_u16	51354
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	3137
k_ISDYNAASMsgCountValidThresh_Cnt_u16	25238
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	6338
k_ISDYNAASMsgLenValidThresh_Cnt_u16	51576
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	29537
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	19141
k_ISDYNABRChkSumValidThresh_Cnt_u16	59338
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	62780
k_ISDYNABRMsgCountValidThresh_Cnt_u16	19056
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	10753
k_ISDYNABRMsgLenValidThresh_Cnt_u16	26354
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	37151
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	6764
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	6611
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	13891
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	59285
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	32137
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	47936
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	18493
k_ISDYNVOLChkSumValidThresh_Cnt_u16	9302
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	22703
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	43006
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	50991
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	10127
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	30108
k_IgnOnTimeout_mS_u16	24537
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	129.276993
k_PowerCutVehSpdLowThresh_Kph_f32	199.972305
k_PowerCutVehSpdLowTimeout_mS_u16	44299
k_VBattMaxAAS_Volt_f32	14.4011002
k_VBattMaxBSI_Volt_f32	22.8880997
k_VBattMaxCAV_Volt_f32	30.9911003
k_VBattMaxCMM388_Volt_f32	9.42280006
k_VBattMaxCMM_Volt_f32	8.72789955
k_VBattMaxESP_Volt_f32	3.87910008
k_VBattMinAAS_Volt_f32	13.4567003
k_VBattMinBSI_Volt_f32	3.87910008
k_VBattMinCAV_Volt_f32	0.351900011
k_VBattMinCMM388_Volt_f32	10.2004995
k_VBattMinCMM_Volt_f32	28.3358994
k_VBattMinESP_Volt_f32	8.72789955
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	64612
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	29868
k_VitesseVehicleBVRampValidThresh_Cnt_u16	20210
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	48611
k_VitesseVehicleBVSigValidThresh_Cnt_u16	21275
k_VitesseVehicleBVSpeedPassThresh_kph_f32	225.920197
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	20783
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	40059
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	464214528
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	69
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	28870
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	4009874432
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	245
target_SrlComInput_Per1_Batt_Volt_f32.value	24.3202991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3148237312
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	3
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.268873721
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	159742464
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	18
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3049298432
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1338751488
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1604770304
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1834088960
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	13441536
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2719496704
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	85
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	89
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	199
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	211
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	7
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3588217344
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	43
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	194
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	165
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2599451136
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1118542336
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2553723392
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	55
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	229
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	247
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3053832704
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2176
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.482140392
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	136434
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	160.494995
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	63730

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	13692	13692	✔
AASNodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	58021	58021	✔
AngleVolantMsgTimer_mS_M_u32	4009874432	4009874432	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	500.96286	500.96286	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26292	26292	✔
BSINodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	36466	36466	✔
CAVNodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	784	784	✔
CMMNodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	5472	5472	✔
CONSANGLECPK_HwDeg_M_f32	575.870483	575.870483 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	5472	5472	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3593546240	3593546240	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	924	924	✔
CityParkInputConsistentCount_Cnt_M_u16	61450	61450	✔
CityParkInputInvalidCount_Cnt_M_u16	1802	1802	✔
CityParkInputMsgTimer_mS_M_u32	4009874432	4009874432	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4009874432	4009874432	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4009874432	4009874432	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4009874432	4009874432	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4009874432	4009874432	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	4009874432	4009874432	✔
ESPNTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	32991	32991	✔
ESPNodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	64	64	✔
EffacDefaultDiagTimer_mS_M_u32[1]	894	894	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3	3	✔
ElecIntTimer_mS_M_u32[1]	8	8	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4009874432	4009874432	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDATDIRASentFltAcc_Cnt_M_u16	58959	58959	✔
ISDATDIRASentTimer_mS_M_u32	4009874432	4009874432	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4009874432	4009874432	✔
IgnOnTimer_mS_M_u32	3939203584	3939203584	✔
IgnTimeOff_Sec_M_u32	331718046	331718046	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	74	74	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	159742464	159742464	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	18	18	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3049298432	3049298432	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	132	132	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1338751488	1338751488	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1604770304	1604770304	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	263240192	263240192	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	37	37	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	13441536	13441536	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	143	143	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2719496704	2719496704	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	7	7	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3588217344	3588217344	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	165	165	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2599451136	2599451136	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	9	9	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1118542336	1118542336	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	215	215	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2553723392	2553723392	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3053832704	3053832704	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	389.348602	389.348602	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	519.961121	519.961121	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	388.90921	388.90921	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	500.96286	500.96286	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	5472	5472	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	331718046	331718046	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	575.870483	575.870483 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	52.0363007	52.0363007	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.122 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1803678720
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	33996
AASNodeAbsentTimer_mS_M_u32	3565446144
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	56796
ANGLEVOLANTSigValidCount_Cnt_M_u16	12532
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	57457
AngleVolantMsgTimer_mS_M_u32	1803678720
AngleVolantValidCount_Cnt_M_u16	40827
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	348.540436
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	829563904
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	824484864
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1296143360
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3138802688
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	12475
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3138262016
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	45384
CAVNodeAbsentTimer_mS_M_u32	611845120
CDD_SrlComVehSpd_Kph_G_f32	454.623993
CMM388NTCEnableTimer_mS_M_u32	947274752
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	381551616
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	43056
CMMNodeAbsentTimer_mS_M_u32	2471515136
CONSANGLECPKSigInvalidCount_Cnt_M_u16	56566
CONSANGLECPKSigValidCount_Cnt_M_u16	33758
CONSANGLECPK_Cnt_M_u16	32897
CONSANGLECPK_HwDeg_M_f32	453.876587
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	32897
CPKVehicleSpeedMsgTimer_mS_M_u32	475591680
CPKVehicleSpeedValidCount_Cnt_M_u16	45617
CityParkInputConsistentCount_Cnt_M_u16	28159

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	7910
CityParkInputMsgTimer_mS_M_u32	2910213376
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1141400576
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	55632
ComputerRazGCTSigInvalidTimer_mS_M_u32	1991017472
ComputerRazGCTSigValidCount_Cnt_M_u16	46364
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	35938
DMDFCTCPKSigValidCount_Cnt_M_u16	546
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	29726
DMDRELAXECPKSigValidCount_Cnt_M_u16	21686
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	39323
DateInvalidTimer_mS_M_u32	824484864
DiagMuxOnAbsentTimer_mS_M_u32	1163506688
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3138802688
ESPNTCEnableTimer_mS_M_u32	292381696
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	14884
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	54
EffacDefaultDiagTimer_mS_M_u32[1]	64
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	22
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1118835712
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	47691
EtatMTSigValidCount_Cnt_M_u16	58927
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	47416
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	28064
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	48744
ISDAT4V2BSI552MsgTimer_mS_M_u32	1574196224
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	33943
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	37635
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	58927
ISDATBSI3F2MsgTimer_mS_M_u32	1092072448
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	2992
ISDATBSI412MsgLenValidCount_Cnt_M_u16	26572
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	47691
ISDATBSI412MsgTimer_mS_M_u32	1564472320
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	3508
ISDATBSI432MsgLenValidCount_Cnt_M_u16	31400
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	12881
ISDATDIRASentFltAcc_Cnt_M_u16	46437
ISDATDIRASentTimer_mS_M_u32	475591680
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	28351
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	40827
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	38081
ISDYN2CMMMsgTimer_mS_M_u32	2317837312
ISDYNAASChkSumInvalidCount_Cnt_M_u16	1806
ISDYNAASChkSumValidCount_Cnt_M_u16	58438
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	40410
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	23595
ISDYNAASMsgLenValidCount_Cnt_M_u16	17307
ISDYNAASMsgTimeValidCount_Cnt_M_u16	1806
ISDYNAASMsgTimer_mS_M_u32	854737920
ISDYNABRChkSumInvalidCount_Cnt_M_u16	26609
ISDYNABRChkSumValidCount_Cnt_M_u16	25489
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	15341
ISDYNABRMsgCountValidCount_Cnt_M_u16	21093
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	36053
ISDYNABRMsgLenValidCount_Cnt_M_u16	44285
ISDYNABRMsgTimeValidCount_Cnt_M_u16	32897
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	724

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1333
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	58927
ISDYNCMM208MsgTimer_mS_M_u32	2530157568
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2747
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1439
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	45113
ISDYNCMM388MsgTimer_mS_M_u32	2831270912
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	20660
ISDYNVOLChkSumValidCount_Cnt_M_u16	59932
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	47904
ISDYNVOLMsgCountValidCount_Cnt_M_u16	25440
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	27717
ISDYNVOLMsgLenValidCount_Cnt_M_u16	59661
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	43056
ISDYNVOLMsgTimer_mS_M_u32	4247290880
IgnOnTimer_mS_M_u32	2252719104
IgnTimeOff_Sec_M_u32	1014896526
ManVehSpd_Kph_M_f32	231.7155
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	69
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	127
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1379775488
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	202
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2013303808
PrevISDATBSI412MsgDLCError_Cnt_M_u08	92
PrevISDATBSI412MsgRxTime_MSec_M_u32	2319516672
PrevISDATBSI432MsgDLCError_Cnt_M_u08	252
PrevISDATBSI432MsgRxTime_MSec_M_u32	2380358656
PrevISDATDIRAMsgTxTime_MSec_M_u32	4099212288
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	115
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2045236224
PrevISDYNAASMsgDLCError_Cnt_M_u08	123
PrevISDYNAASMsgRxTime_MSec_M_u32	1936098304
PrevISDYNABRMsgDLCError_Cnt_M_u08	108
PrevISDYNABRMsgRxTime_MSec_M_u32	1178452992
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	121
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3796075520
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	39
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2407818240
PrevISDYNVOLMsgDLCError_Cnt_M_u08	18
PrevISDYNVOLMsgRxTime_MSec_M_u32	2931164160
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	436073472
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	404.774506
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	33001
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	6873
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	25738
VitesseVehicleBVRampValidCount_Cnt_M_u16	9530
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	40701
VitesseVehicleBVSigValidCount_Cnt_M_u16	14549

Name	Input Value
VitesseVehicleBV_Kph_M_f32	406.053894
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	45113
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	32137
VitesseVehiculeRoues_Kph_M_f32	516.192078
k_AASNTCEnableTimeout_mS_u16	24984
k_AASNodeAbsentDiag_Cnt_str.Threshold	41835
k_AASNodeAbsentDiag_Cnt_str.PStep	24052
k_AASNodeAbsentDiag_Cnt_str.NStep	384
k_AASNodeAbsentTimeout_mS_u16	23126
k_AASNodeTimeout_mS_u16	21977
k_ABSNodeTimeout_mS_u16	60287
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	15311
k_ANGLEVOLANTSigValidThresh_Cnt_u16	38659
k_AngleVolantInvalidThresh_Cnt_u16	37610
k_AngleVolantValidThresh_Cnt_u16	7910
k_BSI552MsgTimeout_mS_u16	12336
k_BSINTCEnableTimeout_mS_u16	48556
k_BSINodeAbsentDiag_Cnt_str.Threshold	26372
k_BSINodeAbsentDiag_Cnt_str.PStep	34332
k_BSINodeAbsentDiag_Cnt_str.NStep	15257
k_BSINodeAbsentTimeout_mS_u16	21097
k_BSINodeTimeout_mS_u16	12881
k_BattOvHi_Volt_f32	2
k_BattOvLo_Volt_f32	19.3164005
k_BattUvHi_Volt_f32	8.90229988
k_BattUvLo_Volt_f32	0
k_CAVNTCEnableTimeout_mS_u16	924
k_CAVNodeAbsentDiag_Cnt_str.Threshold	31169
k_CAVNodeAbsentDiag_Cnt_str.PStep	26637
k_CAVNodeAbsentDiag_Cnt_str.NStep	48026
k_CAVNodeAbsentTimeout_mS_u16	18694
k_CAVNodeTimeout_mS_u16	36722
k_CMM388MsgTimeout_mS_u16	65484
k_CMM388NTCEnableTimeout_mS_u16	60232
k_CMMNTCEnableTimeout_mS_u16	61583
k_CMMNodeAbsentDiag_Cnt_str.Threshold	1887
k_CMMNodeAbsentDiag_Cnt_str.PStep	41594
k_CMMNodeAbsentDiag_Cnt_str.NStep	14413
k_CMMNodeAbsentTimeout_mS_u16	12037
k_CONSANGLECPKMax_HwDeg_f32	130.271393
k_CONSANGLECPKMin_HwDeg_f32	-67.1255035
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	43833
k_CONSANGLECPKSigValidThresh_Cnt_u16	47241
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	34079
k_CPKVehicleSpeedValidThresh_Cnt_u16	57939
k_CityParkInputInvalidThresh_Cnt_u16	1975
k_CityParkInputValidThresh_Cnt_u16	28159
k_ComputerRazGCTSigValidThresh_Cnt_u16	50237
k_CptTemporelSigValidThresh_Cnt_u16	25385
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	2005
k_DMDFCTCPKSigValidThresh_Cnt_u16	26621
k_DMDFCTCPKValidCount_Cnt_u16	51651
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	38081
k_DMDRELAXECPKSigValidThresh_Cnt_u16	58305
k_DMDRelaxeConsistentThresh_Cnt_u16	60679
k_DateValidThresh_Cnt_u16	48744
k_DefaultVehSpd_Kph_f32	53.9455986
k_DiagMuxOnAbsentTimeout_mS_u16	0
k_EMNodeTimeout_mS_u16	44539
k_ESPNTCEnableTimeout_mS_u16	13764
k_ESPNodeAbsentDiag_Cnt_str.Threshold	34918
k_ESPNodeAbsentDiag_Cnt_str.PStep	54499
k_ESPNodeAbsentDiag_Cnt_str.NStep	48198
k_ESPNodeAbsentTimeout_mS_u16	18189
k_EtatMTSigInvalidThresh_Cnt_u16	11448
k_EtatMTSigValidThresh_Cnt_u16	65432
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	46242
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	27749
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	54176
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	40028
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	25736
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	42804
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	56057

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	8621
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	45880
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	12389
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	29089
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	62348
k_ISDATDIRASentDiag_Cnt_str.Threshold	25991
k_ISDATDIRASentDiag_Cnt_str.PStep	29762
k_ISDATDIRASentDiag_Cnt_str.NStep	4038
k_ISDATDIRASentTimeout_mS_u16	34925
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	4585
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	57457
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	24144
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	25329
k_ISDYNAASChkSumValidThresh_Cnt_u16	40593
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	46829
k_ISDYNAASMsgCountValidThresh_Cnt_u16	3429
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	33397
k_ISDYNAASMsgLenValidThresh_Cnt_u16	48221
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	15627
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	41875
k_ISDYNABRChkSumValidThresh_Cnt_u16	63035
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	43963
k_ISDYNABRMsgCountValidThresh_Cnt_u16	63507
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	58160
k_ISDYNABRMsgLenValidThresh_Cnt_u16	46372
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	35898
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	34669
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	38033
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	1920
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	22748
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	60404
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	13534
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	17995
k_ISDYNVOLChkSumValidThresh_Cnt_u16	61607
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	64713
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	6421
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	52167
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	23723
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	20382
k_IgnOnTimeout_mS_u16	31431
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	246.112106
k_PowerCutVehSpdLowThresh_Kph_f32	194.369904
k_PowerCutVehSpdLowTimeout_mS_u16	19844
k_VBattMaxAAS_Volt_f32	6.58459997
k_VBattMaxBSI_Volt_f32	23.2838001
k_VBattMaxCAV_Volt_f32	10.4237003
k_VBattMaxCMM388_Volt_f32	12.3752003
k_VBattMaxCMM_Volt_f32	17.6581001
k_VBattMaxESP_Volt_f32	10.0487003
k_VBattMinAAS_Volt_f32	32
k_VBattMinBSI_Volt_f32	10.0487003
k_VBattMinCAV_Volt_f32	21.0361996
k_VBattMinCMM388_Volt_f32	0.489600003
k_VBattMinCMM_Volt_f32	14.3709002
k_VBattMinESP_Volt_f32	17.6581001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	9635
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	52655
k_VitesseVehicleBVRampValidThresh_Cnt_u16	46624
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	42268
k_VitesseVehicleBVSigValidThresh_Cnt_u16	53656
k_VitesseVehicleBVSpeedPassThresh_kph_f32	6.88110018
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	44104
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	24440
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	824484864
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	246
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	0
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	12512768
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	39
target_SrlComInput_Per1_Batt_Volt_f32.value	1
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3262583808
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	92
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.966671765
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	718259200
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	237
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1038345216
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	759694336
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3237749760
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3238020096
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	176
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4115948544
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	637043712
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	86
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	122
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	137
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	149
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	207
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	188
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	285025280
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	69
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	93
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	164
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	173
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	205
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3214066688
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2854675456
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	149
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	822805504
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	91
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	106
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	123
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	176
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	186
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	203
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1540527104
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1245
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.808031857
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	796176
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	187.574295

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	51747		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	12512768	12512768	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	41835	41835	✔
AASNodeAbsentTimer_mS_M_u32	12512768	12512768	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	57457	57457	✔
AngleVolantMsgTimer_mS_M_u32	822805504	822805504	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	348.540436	348.540436	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	12512768	12512768	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	12512768	12512768	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	12512768	12512768	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	12512768	12512768	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3237749760	3237749760	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	12512768	12512768	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	31169	31169	✔
CAVNodeAbsentTimer_mS_M_u32	12512768	12512768	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	12512768	12512768	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	12512768	12512768	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	28643	28643	✔
CMMNodeAbsentTimer_mS_M_u32	4115948544	4115948544	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	32897	32897	✔
CONSANGLECPK_HwDeg_M_f32	453.876587	453.876587 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	32897	32897	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	475591680	475591680	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	45617	45617	✔
CityParkInputConsistentCount_Cnt_M_u16	28159	28159	✔
CityParkInputInvalidCount_Cnt_M_u16	7910	7910	✔
CityParkInputMsgTimer_mS_M_u32	637043712	637043712	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	12512768	12512768	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	12512768	12512768	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	12512768	12512768	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	12512768	12512768	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	12512768	12512768	✔
ESPNTCEnableTimer_mS_M_u32	12512768	12512768	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	12512768	12512768	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	54	54	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	64	64	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	10	10	✔
ElecIntTimer_mS_M_u32[1]	22	22	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1118835712	1118835712	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	12512768	12512768	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	12512768	12512768	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	12512768	12512768	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	12512768	12512768	✔
ISDATDIRASentFltAcc_Cnt_M_u16	42399	42399	✔
ISDATDIRASentTimer_mS_M_u32	12512768	12512768	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	12512768	12512768	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	12512768	12512768	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	12512768	12512768	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	12512768	12512768	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	12512768	12512768	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	12512768	12512768	✔
IgnOnTimer_mS_M_u32	2252719104	2252719104	✔
IgnTimeOff_Sec_M_u32	1014896526	1014896526	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	29	29	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	718259200	718259200	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	237	237	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1038345216	1038345216	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	53	53	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	759694336	759694336	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	190	190	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3237749760	3237749760	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3238020096	3238020096	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	176	176	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4115948544	4115948544	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	169	169	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	637043712	637043712	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	188	188	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	285025280	285025280	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	206	206	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3214066688	3214066688	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2854675456	2854675456	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	149	149	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	822805504	822805504	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1540527104	1540527104	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	404.774506	404.774506	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	406.053894	406.053894	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	516.192078	516.192078	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	348.540436	348.540436	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	32897	32897	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1014896526	1014896526	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	453.876587	453.876587 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	53.9455986	53.9455986	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0106	0x0106	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.123 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	703129344
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	10249
AASNodeAbsentTimer_mS_M_u32	1151440640
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	65239
ANGLEVOLANTSigValidCount_Cnt_M_u16	37200
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	59674
AngleVolantMsgTimer_mS_M_u32	703129344
AngleVolantValidCount_Cnt_M_u16	64636
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	422.302429
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	349722368
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4290828032
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2334787328
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2225850112
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	16954
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	331646720
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	39190
CAVNodeAbsentTimer_mS_M_u32	726054656
CDD_SrlComVehSpd_Kph_G_f32	37.7285004
CMM388NTCEnableTimer_mS_M_u32	3091986176
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3967072000
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	53533
CMMNodeAbsentTimer_mS_M_u32	1677575936
CONSANGLECPKSigInvalidCount_Cnt_M_u16	39050
CONSANGLECPKSigValidCount_Cnt_M_u16	28562
CONSANGLECPK_Cnt_M_u16	50601
CONSANGLECPK_HwDeg_M_f32	114.068001
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	50601
CPKVehicleSpeedMsgTimer_mS_M_u32	862185216
CPKVehicleSpeedValidCount_Cnt_M_u16	9792
CityParkInputConsistentCount_Cnt_M_u16	41200
CityParkInputInvalidCount_Cnt_M_u16	15162
CityParkInputMsgTimer_mS_M_u32	718259200
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1

Name	Input Value
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	102078208
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	14973
ComputerRazGCTSigInvalidTimer_mS_M_u32	2796107520
ComputerRazGCTSigValidCount_Cnt_M_u16	32665
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	58054
DMDFCTCPKSigValidCount_Cnt_M_u16	44358
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	50193
DMDRELAXECPKSigValidCount_Cnt_M_u16	44554
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	13979
DateInvalidTimer_mS_M_u32	4290828032
DiagMuxOnAbsentTimer_mS_M_u32	2875303680
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2225850112
ESPNTCEnableTimer_mS_M_u32	1910937344
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	5890
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	80
ElecIntTimer_mS_M_u32[1]	2929326336
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2229176064
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	6092
EtatMTSigValidCount_Cnt_M_u16	20448
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	35780
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	14924
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	4212
ISDAT4V2BSI552MsgTimer_mS_M_u32	343000832
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	57959
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	37603
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	20448
ISDATBSI3F2MsgTimer_mS_M_u32	807905024
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	65054
ISDATBSI412MsgLenValidCount_Cnt_M_u16	34186
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	6092
ISDATBSI412MsgTimer_mS_M_u32	3434014464
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	45201
ISDATBSI432MsgLenValidCount_Cnt_M_u16	25974
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	31227
ISDATDIRASentFltAcc_Cnt_M_u16	16575
ISDATDIRASentTimer_mS_M_u32	862185216
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	29423
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	64636
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	1449
ISDYN2CMMMsgTimer_mS_M_u32	1874368256
ISDYNAASChkSumInvalidCount_Cnt_M_u16	10563
ISDYNAASChkSumValidCount_Cnt_M_u16	40283
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	15711
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	58477
ISDYNAASMsgLenValidCount_Cnt_M_u16	6621
ISDYNAASMsgTimeValidCount_Cnt_M_u16	10563
ISDYNAASMsgTimer_mS_M_u32	3101161216
ISDYNABRChkSumInvalidCount_Cnt_M_u16	43546
ISDYNABRChkSumValidCount_Cnt_M_u16	25338
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	50854
ISDYNABRMsgCountValidCount_Cnt_M_u16	36606
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	50413
ISDYNABRMsgLenValidCount_Cnt_M_u16	12341
ISDYNABRMsgTimeValidCount_Cnt_M_u16	50601
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	725
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1335
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	20448
ISDYNCMM208MsgTimer_mS_M_u32	2562807552
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2751

Name	Input Value
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1441
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	16962
ISDYNCMM388MsgTimer_mS_M_u32	4117329664
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	46416
ISDYNVOLChkSumValidCount_Cnt_M_u16	46296
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	52876
ISDYNVOLMsgCountValidCount_Cnt_M_u16	396
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	17567
ISDYNVOLMsgLenValidCount_Cnt_M_u16	6663
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	53533
ISDYNVOLMsgTimer_mS_M_u32	53819136
IgnOnTimer_mS_M_u32	1826453248
IgnTimeOff_Sec_M_u32	1197173303
ManVehSpd_Kph_M_f32	393.025909
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	71
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	57
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	347449088
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	107
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3337422592
PrevISDATBSI412MsgDLCError_Cnt_M_u08	95
PrevISDATBSI412MsgRxTime_MSec_M_u32	1575728896
PrevISDATBSI432MsgDLCError_Cnt_M_u08	103
PrevISDATBSI432MsgRxTime_MSec_M_u32	3431634688
PrevISDATDIRAMsgTxTime_MSec_M_u32	1873786624
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	221
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1849116416
PrevISDYNAASMsgDLCError_Cnt_M_u08	253
PrevISDYNAASMsgRxTime_MSec_M_u32	410728192
PrevISDYNABRMsgDLCError_Cnt_M_u08	32
PrevISDYNABRMsgRxTime_MSec_M_u32	217413376
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	155
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2145662720
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	37
PrevISDYNCMM388MsgRxTime_MSec_M_u32	329357056
PrevISDYNVOLMsgDLCError_Cnt_M_u08	216
PrevISDYNVOLMsgRxTime_MSec_M_u32	76330752
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	242542336
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	418.021301
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	60979
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	3107
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	1872
VitesseVehicleBVRampValidCount_Cnt_M_u16	45312
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	32628
VitesseVehicleBVSigValidCount_Cnt_M_u16	15789
VitesseVehicleBV_Kph_M_f32	206.513
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	16962
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	17938
VitesseVehiculeRoues_Kph_M_f32	567.05011

Name	Input Value
k_AASNTCEnableTimeout_mS_u16	15972
k_AASNodeAbsentDiag_Cnt_str.Threshold	10757
k_AASNodeAbsentDiag_Cnt_str.PStep	7105
k_AASNodeAbsentDiag_Cnt_str.NStep	65461
k_AASNodeAbsentTimeout_mS_u16	63467
k_AASNodeTimeout_mS_u16	23331
k_ABSNodeTimeout_mS_u16	31087
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	21056
k_ANGLEVOLANTSigValidThresh_Cnt_u16	15461
k_AngleVolantInvalidThresh_Cnt_u16	42160
k_AngleVolantValidThresh_Cnt_u16	15162
k_BSI552MsgTimeout_mS_u16	35357
k_BSINTCEnableTimeout_mS_u16	32937
k_BSINodeAbsentDiag_Cnt_str.Threshold	26412
k_BSINodeAbsentDiag_Cnt_str.PStep	34315
k_BSINodeAbsentDiag_Cnt_str.NStep	15280
k_BSINodeAbsentTimeout_mS_u16	29490
k_BSINodeTimeout_mS_u16	31227
k_BattOvHi_Volt_f32	2
k_BattOvLo_Volt_f32	3.29699993
k_BattUvHi_Volt_f32	3.53119993
k_BattUvLo_Volt_f32	0
k_CAVNTCEnableTimeout_mS_u16	58648
k_CAVNodeAbsentDiag_Cnt_str.Threshold	9850
k_CAVNodeAbsentDiag_Cnt_str.PStep	55599
k_CAVNodeAbsentDiag_Cnt_str.NStep	26463
k_CAVNodeAbsentTimeout_mS_u16	18908
k_CAVNodeTimeout_mS_u16	28950
k_CMM388MsgTimeout_mS_u16	46857
k_CMM388NTCEnableTimeout_mS_u16	58517
k_CMMNTCEnableTimeout_mS_u16	32383
k_CMMNodeAbsentDiag_Cnt_str.Threshold	32647
k_CMMNodeAbsentDiag_Cnt_str.PStep	42126
k_CMMNodeAbsentDiag_Cnt_str.NStep	57005
k_CMMNodeAbsentTimeout_mS_u16	8606
k_CONSANGLECPKMax_HwDeg_f32	446.419891
k_CONSANGLECPKMin_HwDeg_f32	-483.542786
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	20802
k_CONSANGLECPKSigValidThresh_Cnt_u16	38162
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	25937
k_CPKVehicleSpeedValidThresh_Cnt_u16	50741
k_CityParkInputInvalidThresh_Cnt_u16	25288
k_CityParkInputValidThresh_Cnt_u16	41200
k_ComputerRazGCTSigValidThresh_Cnt_u16	15221
k_CptTemporelSigValidThresh_Cnt_u16	14961
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	21485
k_DMDFCTCPKSigValidThresh_Cnt_u16	65333
k_DMDFCTCPKValidCount_Cnt_u16	38690
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	1449
k_DMDRELAXECPKSigValidThresh_Cnt_u16	17513
k_DMDRelaxeConsistentThresh_Cnt_u16	49303
k_DateValidThresh_Cnt_u16	4212
k_DefaultVehSpd_Kph_f32	51.0957985
k_DiagMuxOnAbsentTimeout_mS_u16	38663
k_EMNodeTimeout_mS_u16	31099
k_ESPNTCEnableTimeout_mS_u16	64418
k_ESPNodeAbsentDiag_Cnt_str.Threshold	40274
k_ESPNodeAbsentDiag_Cnt_str.PStep	1844
k_ESPNodeAbsentDiag_Cnt_str.NStep	56738
k_ESPNodeAbsentTimeout_mS_u16	63878
k_EtatMTSigInvalidThresh_Cnt_u16	14277
k_EtatMTSigValidThresh_Cnt_u16	27365
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	41672
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	46908
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	13325
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	61208
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	29268
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	15250
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	40130
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	50279
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	53253
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	17917
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	40458

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	1929
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	14502
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	24690
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	59674
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	45566
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	47386
k_ISDYNAASChkSumValidThresh_Cnt_u16	45562
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	21926
k_ISDYNAASMsgCountValidThresh_Cnt_u16	24062
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	27278
k_ISDYNAASMsgLenValidThresh_Cnt_u16	14231
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	27213
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	63667
k_ISDYNABRChkSumValidThresh_Cnt_u16	52347
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	53562
k_ISDYNABRMsgCountValidThresh_Cnt_u16	30707
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	8221
k_ISDYNABRMsgLenValidThresh_Cnt_u16	42498
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	6014
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	60071
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	10107
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	41518
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	36311
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	24656
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	55634
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	31309
k_ISDYNVOLChkSumValidThresh_Cnt_u16	5881
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	41747
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	21102
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	54104
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	56428
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	46290
k_IgnOnTimeout_mS_u16	52441
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	101.096298
k_PowerCutVehSpdLowThresh_Kph_f32	136.322906
k_PowerCutVehSpdLowTimeout_mS_u16	10912
k_VBattMaxAAS_Volt_f32	29.6086998
k_VBattMaxBSI_Volt_f32	19.5363998
k_VBattMaxCAV_Volt_f32	5.29750013
k_VBattMaxCMM388_Volt_f32	18.8432999
k_VBattMaxCMM_Volt_f32	18.6889992
k_VBattMaxESP_Volt_f32	20.4733009
k_VBattMinAAS_Volt_f32	30.7770004
k_VBattMinBSI_Volt_f32	20.4733009
k_VBattMinCAV_Volt_f32	22.4118996
k_VBattMinCMM388_Volt_f32	0.327199996
k_VBattMinCMM_Volt_f32	1.19009995
k_VBattMinESP_Volt_f32	18.6889992
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	36164
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	61664
k_VitesseVehicleBVRampValidThresh_Cnt_u16	56716
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	33752
k_VitesseVehicleBVSigValidThresh_Cnt_u16	6693
k_VitesseVehicleBVSpeedPassThresh_kph_f32	2.2586
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	43030
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	31302
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4290828032
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	61
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	38663
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2929326336
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	37
target_SrlComInput_Per1_Batt_Volt_f32.value	1
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3783886592
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	120
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0163409021
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	658470656
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	179
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3867350784
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	115
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1356248832
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	238704384
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3333289728
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	573675264
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	249
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3368367872
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	34
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	107
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	178
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	250
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1647793920
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	169
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	177
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	223
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	225
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	246
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	888567552
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1840912128
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	294500096
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	71
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	188
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3816228608
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2128
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0629952177
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	937032
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	145.959793
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	31365

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2929326336	2929326336	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNodeAbsentFltAcc_Cnt_M_u16	10757	10757	✔
AASNodeAbsentTimer_mS_M_u32	2929326336	2929326336	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	59674	59674	✔
AngleVolantMsgTimer_mS_M_u32	2929326336	2929326336	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	422.302429	422.302429	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2929326336	2929326336	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2929326336	2929326336	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2929326336	2929326336	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2929326336	2929326336	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26412	26412	✔
BSINodeAbsentTimer_mS_M_u32	2929326336	2929326336	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2929326336	2929326336	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2929326336	2929326336	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2929326336	2929326336	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2929326336	2929326336	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	32647	32647	✔
CMMNodeAbsentTimer_mS_M_u32	2929326336	2929326336	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	50601	50601	✔
CONSANGLECPK_HwDeg_M_f32	114.068001	114.068001 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	50601	50601	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	862185216	862185216	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	9792	9792	✔
CityParkInputConsistentCount_Cnt_M_u16	41200	41200	✔
CityParkInputInvalidCount_Cnt_M_u16	15164	15164	✔
CityParkInputMsgTimer_mS_M_u32	2929326336	2929326336	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2929326336	2929326336	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2929326336	2929326336	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2929326336	2929326336	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2929326336	2929326336	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2929326336	2929326336	✔
ESPNTCEnableTimer_mS_M_u32	2929326336	2929326336	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2929326336	2929326336	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	2	2	✔
ElecIntTimer_mS_M_u32[0]	80	80	✔
ElecIntTimer_mS_M_u32[1]	2929326336	2929326336	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2929326336	2929326336	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2929326336	2929326336	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2929326336	2929326336	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2929326336	2929326336	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2929326336	2929326336	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2929326336	2929326336	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2929326336	2929326336	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2929326336	2929326336	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2929326336	2929326336	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2929326336	2929326336	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2929326336	2929326336	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2929326336	2929326336	✔
IgnOnTimer_mS_M_u32	2929326336	2929326336	✔
IgnTimeOff_Sec_M_u32	1197173303	1197173303	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	10	10	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	658470656	658470656	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	179	179	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3867350784	3867350784	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	115	115	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1356248832	1356248832	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	178	178	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	238704384	238704384	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1873786624	1873786624	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	77	77	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	573675264	573675264	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	249	249	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3368367872	3368367872	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	250	250	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1647793920	1647793920	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	132	132	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	888567552	888567552	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1840912128	1840912128	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	31	31	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	294500096	294500096	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3816228608	3816228608	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	418.021301	418.021301	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	206.513	206.513	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	567.05011	567.05011	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	422.302429	422.302429	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	50601	50601	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1197173303	1197173303	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	114.068001	114.068001 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	51.0957985	51.0957985	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.124 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1849691648
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	38366
AASNodeAbsentTimer_mS_M_u32	483786240
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	27507
ANGLEVOLANTSigValidCount_Cnt_M_u16	4298
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	54955
AngleVolantMsgTimer_mS_M_u32	1849691648
AngleVolantValidCount_Cnt_M_u16	43782
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	336.964386
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	4147232256
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2021146112
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	922529280
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2172087808
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	60746
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	657272320
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	24375
CAVNodeAbsentTimer_mS_M_u32	3848707584
CDD_SrlComVehSpd_Kph_G_f32	402.732513
CMM388NTCEnableTimer_mS_M_u32	3814120960
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3655114240
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	24800
CMMNodeAbsentTimer_mS_M_u32	2877386240
CONSANGLECPKSigInvalidCount_Cnt_M_u16	55642
CONSANGLECPKSigValidCount_Cnt_M_u16	61698
CONSANGLECPK_Cnt_M_u16	2749
CONSANGLECPK_HwDeg_M_f32	222.179993
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2749
CPKVehicleSpeedMsgTimer_mS_M_u32	4258205184
CPKVehicleSpeedValidCount_Cnt_M_u16	43007
CityParkInputConsistentCount_Cnt_M_u16	36266
CityParkInputInvalidCount_Cnt_M_u16	47051

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	658470656
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2826567168
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	11906
ComputerRazGCTSigInvalidTimer_mS_M_u32	490675712
ComputerRazGCTSigValidCount_Cnt_M_u16	54703
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	61735
DMDFCTCPKSigValidCount_Cnt_M_u16	3687
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	33733
DMDRELAXECPKSigValidCount_Cnt_M_u16	8860
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	33575
DateInvalidTimer_mS_M_u32	2021146112
DiagMuxOnAbsentTimer_mS_M_u32	3168128512
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2172087808
ESPNTCEnableTimer_mS_M_u32	3909549568
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	39924
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	65
EffacDefaultDiagTimer_mS_M_u32[1]	655
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	56565
ElecIntTimer_mS_M_u32[1]	787878
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3151965696
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	5590
EtatMTSigValidCount_Cnt_M_u16	14937
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	26540
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	63700
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	7389
ISDAT4V2BSI552MsgTimer_mS_M_u32	1780837888
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	14725
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	38096
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	14937
ISDATBSI3F2MsgTimer_mS_M_u32	3330526720
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	54111
ISDATBSI412MsgLenValidCount_Cnt_M_u16	27099
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	5590
ISDATBSI412MsgTimer_mS_M_u32	502140416
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	37508
ISDATBSI432MsgLenValidCount_Cnt_M_u16	32920
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	37000
ISDATDIRASentFltAcc_Cnt_M_u16	19516
ISDATDIRASentTimer_mS_M_u32	4258205184
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	39659
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	43782
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	54398
ISDYN2CMMMsgTimer_mS_M_u32	3079732736
ISDYNAASChkSumInvalidCount_Cnt_M_u16	64048
ISDYNAASChkSumValidCount_Cnt_M_u16	31399
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	13405
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	39218
ISDYNAASMsgLenValidCount_Cnt_M_u16	13729
ISDYNAASMsgTimeValidCount_Cnt_M_u16	64048
ISDYNAASMsgTimer_mS_M_u32	296934912
ISDYNABRChkSumInvalidCount_Cnt_M_u16	36138
ISDYNABRChkSumValidCount_Cnt_M_u16	24393
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	28167
ISDYNABRMsgCountValidCount_Cnt_M_u16	61886
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	41009
ISDYNABRMsgLenValidCount_Cnt_M_u16	64281
ISDYNABRMsgTimeValidCount_Cnt_M_u16	2749
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	726
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1337

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	14937
ISDYNCMM208MsgTimer_mS_M_u32	1333181952
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2755
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1443
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	29108
ISDYNCMM388MsgTimer_mS_M_u32	2180931072
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	6920
ISDYNVOLChkSumValidCount_Cnt_M_u16	47408
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	50645
ISDYNVOLMsgCountValidCount_Cnt_M_u16	43413
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	50973
ISDYNVOLMsgLenValidCount_Cnt_M_u16	25508
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	24800
ISDYNVOLMsgTimer_mS_M_u32	932912640
IgnOnTimer_mS_M_u32	3953286656
IgnTimeOff_Sec_M_u32	221679346
ManVehSpd_Kph_M_f32	277.124298
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	73
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	97
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3503934976
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	140
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1337175552
PrevISDATBSI412MsgDLCError_Cnt_M_u08	178
PrevISDATBSI412MsgRxTime_MSec_M_u32	561487360
PrevISDATBSI432MsgDLCError_Cnt_M_u08	221
PrevISDATBSI432MsgRxTime_MSec_M_u32	1763376640
PrevISDATDIRAMsgTxTime_MSec_M_u32	4230716928
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	240
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1389686272
PrevISDYNAASMsgDLCError_Cnt_M_u08	230
PrevISDYNAASMsgRxTime_MSec_M_u32	2412322304
PrevISDYNABRMsgDLCError_Cnt_M_u08	152
PrevISDYNABRMsgRxTime_MSec_M_u32	1801084416
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	71
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1032723968
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	239
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2950036992
PrevISDYNVOLMsgDLCError_Cnt_M_u08	118
PrevISDYNVOLMsgRxTime_MSec_M_u32	4053048832
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4036759040
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	538.640381
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	5088
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	63183
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	31881
VitesseVehicleBVRampValidCount_Cnt_M_u16	48184
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	40348
VitesseVehicleBVSigValidCount_Cnt_M_u16	49075
VitesseVehicleBV_Kph_M_f32	483.495605

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	29108
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	8964
VitesseVehiculeRoues_Kph_M_f32	610.729309
k_AASNTCEnableTimeout_mS_u16	19596
k_AASNodeAbsentDiag_Cnt_str.Threshold	54881
k_AASNodeAbsentDiag_Cnt_str.PStep	64806
k_AASNodeAbsentDiag_Cnt_str.NStep	17792
k_AASNodeAbsentTimeout_mS_u16	13497
k_AASNodeTimeout_mS_u16	2511
k_ABSNodeTimeout_mS_u16	4396
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	10615
k_ANGLEVOLANTSigValidThresh_Cnt_u16	30667
k_AngleVolantInvalidThresh_Cnt_u16	10986
k_AngleVolantValidThresh_Cnt_u16	47051
k_BSI552MsgTimeout_mS_u16	17123
k_BSINTCEnableTimeout_mS_u16	33340
k_BSINodeAbsentDiag_Cnt_str.Threshold	26452
k_BSINodeAbsentDiag_Cnt_str.PStep	34298
k_BSINodeAbsentDiag_Cnt_str.NStep	15303
k_BSINodeAbsentTimeout_mS_u16	39011
k_BSINodeTimeout_mS_u16	37000
k_BattOvHi_Volt_f32	2
k_BattOvLo_Volt_f32	7.62589979
k_BattUvHi_Volt_f32	2.44829988
k_BattUvLo_Volt_f32	0
k_CAVNTCEnableTimeout_mS_u16	45617
k_CAVNodeAbsentDiag_Cnt_str.Threshold	17052
k_CAVNodeAbsentDiag_Cnt_str.PStep	4531
k_CAVNodeAbsentDiag_Cnt_str.NStep	11419
k_CAVNodeAbsentTimeout_mS_u16	58597
k_CAVNodeTimeout_mS_u16	32694
k_CMM388MsgTimeout_mS_u16	59614
k_CMM388NTCEnableTimeout_mS_u16	36922
k_CMMNTCEnableTimeout_mS_u16	50493
k_CMMNodeAbsentDiag_Cnt_str.Threshold	53693
k_CMMNodeAbsentDiag_Cnt_str.PStep	57245
k_CMMNodeAbsentDiag_Cnt_str.NStep	40569
k_CMMNodeAbsentTimeout_mS_u16	49248
k_CONSANGLECPKMax_HwDeg_f32	204.373199
k_CONSANGLECPKMin_HwDeg_f32	-233.278595
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	17588
k_CONSANGLECPKSigValidThresh_Cnt_u16	13828
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	9029
k_CPKVehicleSpeedValidThresh_Cnt_u16	38682
k_CityParkInputInvalidThresh_Cnt_u16	39712
k_CityParkInputValidThresh_Cnt_u16	36266
k_ComputerRazGCTSigValidThresh_Cnt_u16	58971
k_CptTemporelSigValidThresh_Cnt_u16	22054
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	62257
k_DMDFCTCPKSigValidThresh_Cnt_u16	36377
k_DMDFCTCPKValidCount_Cnt_u16	36498
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	54398
k_DMDRELAXECPKSigValidThresh_Cnt_u16	38142
k_DMDRelaxeConsistentThresh_Cnt_u16	22644
k_DateValidThresh_Cnt_u16	7389
k_DefaultVehSpd_Kph_f32	25.1921005
k_DiagMuxOnAbsentTimeout_mS_u16	36515
k_EMNodeTimeout_mS_u16	14983
k_ESPNTCEnableTimeout_mS_u16	26515
k_ESPNodeAbsentDiag_Cnt_str.Threshold	5561
k_ESPNodeAbsentDiag_Cnt_str.PStep	18958
k_ESPNodeAbsentDiag_Cnt_str.NStep	33020
k_ESPNodeAbsentTimeout_mS_u16	55464
k_EtatMTSigInvalidThresh_Cnt_u16	20521
k_EtatMTSigValidThresh_Cnt_u16	45960
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	1760
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	5700
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	34899
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	6002
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	64125
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	60163
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	53745
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	26565

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	1064
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	55745
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	32348
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	29725
k_ISDATDIRASentDiag_Cnt_str.Threshold	2451
k_ISDATDIRASentDiag_Cnt_str.PStep	5266
k_ISDATDIRASentDiag_Cnt_str.NStep	3881
k_ISDATDIRASentTimeout_mS_u16	4486
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	19810
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	54955
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	46207
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	24618
k_ISDYNAASChkSumValidThresh_Cnt_u16	29257
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	49415
k_ISDYNAASMsgCountValidThresh_Cnt_u16	33982
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	7118
k_ISDYNAASMsgLenValidThresh_Cnt_u16	17523
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	36371
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	40159
k_ISDYNABRChkSumValidThresh_Cnt_u16	48711
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	16458
k_ISDYNABRMsgCountValidThresh_Cnt_u16	43233
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	29664
k_ISDYNABRMsgLenValidThresh_Cnt_u16	61172
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	46656
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	61060
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	2888
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	8366
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	48755
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	41930
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	15747
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	56018
k_ISDYNVOLChkSumValidThresh_Cnt_u16	12686
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	31681
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	24813
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	4914
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	50357
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	10179
k_IgnOnTimeout_mS_u16	4910
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	43.6906013
k_PowerCutVehSpdLowThresh_Kph_f32	42.0110016
k_PowerCutVehSpdLowTimeout_mS_u16	30680
k_VBattMaxAAS_Volt_f32	0.438899994
k_VBattMaxBSI_Volt_f32	9.5795002
k_VBattMaxCAV_Volt_f32	12.7544003
k_VBattMaxCMM388_Volt_f32	12.9158001
k_VBattMaxCMM_Volt_f32	32
k_VBattMaxESP_Volt_f32	24.0746002
k_VBattMinAAS_Volt_f32	21.2651005
k_VBattMinBSI_Volt_f32	24.0746002
k_VBattMinCAV_Volt_f32	12.5546999
k_VBattMinCMM388_Volt_f32	32
k_VBattMinCMM_Volt_f32	1.87339997
k_VBattMinESP_Volt_f32	32
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	36588
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	20696
k_VitesseVehicleBVRampValidThresh_Cnt_u16	39125
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	19504
k_VitesseVehicleBVSigValidThresh_Cnt_u16	13835
k_VitesseVehicleBVSpeedPassThresh_kph_f32	50.8577003
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	12855
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	63590
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2021146112
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	18
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	36515
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3002390528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	239

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	1
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	299773440
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	31
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.413689941
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	101
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3296484864
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	161
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2637266432
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3031866880
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	82
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	319536640
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3224428032
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3290824192
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	97
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	652942848
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	92
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	105
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	187
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	191
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	217
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	175
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1259650560
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	68
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	80
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	130
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	147
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	214
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	928472576
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2743893504
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	244424192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	38
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	118
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	242
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2719329792
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	4085
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.663345397
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	398295
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	45.3501015
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	14058

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3002390528	3002390528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	54881	54881	✔
AASNodeAbsentTimer_mS_M_u32	3002390528	3002390528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	54955	54955	✔
AngleVolantMsgTimer_mS_M_u32	3002390528	3002390528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	336.964386	336.964386	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3002390528	3002390528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3002390528	3002390528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3002390528	3002390528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3002390528	3002390528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	45443	45443	✔
BSINodeAbsentTimer_mS_M_u32	319536640	319536640	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3002390528	3002390528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	17052	17052	✔
CAVNodeAbsentTimer_mS_M_u32	3002390528	3002390528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3002390528	3002390528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3002390528	3002390528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3290824192	3290824192	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	2749	2749	✔
CONSANGLECPK_HwDeg_M_f32	222.179993	222.179993 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2749	2749	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4258205184	4258205184	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	43007	43007	✔
CityParkInputConsistentCount_Cnt_M_u16	36266	36266	✔
CityParkInputInvalidCount_Cnt_M_u16	47051	47051	✔
CityParkInputMsgTimer_mS_M_u32	3002390528	3002390528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3002390528	3002390528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3002390528	3002390528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3002390528	3002390528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3002390528	3002390528	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3002390528	3002390528	✔
ESPNTCEnableTimer_mS_M_u32	3002390528	3002390528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3002390528	3002390528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	65	65	✔
EffacDefaultDiagTimer_mS_M_u32[1]	655	655	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	56565	56565	✔
ElecIntTimer_mS_M_u32[1]	787878	787878	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3002390528	3002390528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3002390528	3002390528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3002390528	3002390528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3002390528	3002390528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3002390528	3002390528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	2451	2451	✔
ISDATDIRASentTimer_mS_M_u32	3002390528	3002390528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3002390528	3002390528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3002390528	3002390528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3002390528	3002390528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3002390528	3002390528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3002390528	3002390528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3002390528	3002390528	✔
IgnOnTimer_mS_M_u32	3953286656	3953286656	✔
IgnTimeOff_Sec_M_u32	221679346	221679346	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	101	101	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3296484864	3296484864	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	161	161	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2637266432	2637266432	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	152	152	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3031866880	3031866880	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	82	82	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	319536640	319536640	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4230716928	4230716928	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	46	46	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3290824192	3290824192	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	97	97	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	652942848	652942848	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	175	175	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1259650560	1259650560	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	214	214	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	928472576	928472576	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2743893504	2743893504	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	48	48	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	244424192	244424192	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2719329792	2719329792	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	538.640381	538.640381	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	483.495605	483.495605	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	610.729309	610.729309	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	336.964386	336.964386	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	2749	2749	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	221679346	221679346	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	222.179993	222.179993 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	25.1921005	25.1921005	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.125 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1385601280
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	30139
AASNodeAbsentTimer_mS_M_u32	1251264768
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	59133
ANGLEVOLANTSigValidCount_Cnt_M_u16	57527
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	10068
AngleVolantMsgTimer_mS_M_u32	1385601280
AngleVolantValidCount_Cnt_M_u16	32450
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	224.502121
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3665922304
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2427324672
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	853588224
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2926606592
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	0
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3293526272
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	50225
CAVNodeAbsentTimer_mS_M_u32	2070079744
CDD_SrlComVehSpd_Kph_G_f32	118.811501
CMM388NTCEnableTimer_mS_M_u32	2459052288
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4127254784
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	49652
CMMNodeAbsentTimer_mS_M_u32	3629283584
CONSANGLECPKSigInvalidCount_Cnt_M_u16	60486
CONSANGLECPKSigValidCount_Cnt_M_u16	53008
CONSANGLECPK_Cnt_M_u16	11743
CONSANGLECPK_HwDeg_M_f32	-197.5271
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	11743
CPKVehicleSpeedMsgTimer_mS_M_u32	2682886400
CPKVehicleSpeedValidCount_Cnt_M_u16	14591
CityParkInputConsistentCount_Cnt_M_u16	26326
CityParkInputInvalidCount_Cnt_M_u16	64882
CityParkInputMsgTimer_mS_M_u32	3296484864
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0

Name	Input Value
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	933808384
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	15311
ComputerRazGCTSigInvalidTimer_mS_M_u32	3587795200
ComputerRazGCTSigValidCount_Cnt_M_u16	58055
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	49502
DMDFCTCPKSigValidCount_Cnt_M_u16	62304
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	26119
DMDRELAXECPKSigValidCount_Cnt_M_u16	29505
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	25311
DateInvalidTimer_mS_M_u32	2427324672
DiagMuxOnAbsentTimer_mS_M_u32	3990182144
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2926606592
ESPNTCEnableTimer_mS_M_u32	3925985536
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	60025
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	55656
ElecIntTimer_mS_M_u32[1]	87787
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1312372992
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	2068
EtatMTSigValidCount_Cnt_M_u16	13386
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	2384
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	32666
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	8190
ISDAT4V2BSI552MsgTimer_mS_M_u32	744913152
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	4742
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	47715
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13386
ISDATBSI3F2MsgTimer_mS_M_u32	147544320
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	32247
ISDATBSI412MsgLenValidCount_Cnt_M_u16	13381
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	2068
ISDATBSI412MsgTimer_mS_M_u32	2072811776
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	48392
ISDATBSI432MsgLenValidCount_Cnt_M_u16	52365
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	46142
ISDATDIRASentFltAcc_Cnt_M_u16	20770
ISDATDIRASentTimer_mS_M_u32	2682886400
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	46421
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	32450
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	13145
ISDYN2CMMMsgTimer_mS_M_u32	644073728
ISDYNAASChkSumInvalidCount_Cnt_M_u16	4293
ISDYNAASChkSumValidCount_Cnt_M_u16	63774
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	65213
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	49728
ISDYNAASMsgLenValidCount_Cnt_M_u16	14001
ISDYNAASMsgTimeValidCount_Cnt_M_u16	4293
ISDYNAASMsgTimer_mS_M_u32	2004756736
ISDYNABRChkSumInvalidCount_Cnt_M_u16	5975
ISDYNABRChkSumValidCount_Cnt_M_u16	43705
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	53568
ISDYNABRMsgCountValidCount_Cnt_M_u16	45017
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	46017
ISDYNABRMsgLenValidCount_Cnt_M_u16	52427
ISDYNABRMsgTimeValidCount_Cnt_M_u16	11743
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	727
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1339
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13386
ISDYNCMM208MsgTimer_mS_M_u32	632457472
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2759

Name	Input Value
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1445
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	25272
ISDYNCMM388MsgTimer_mS_M_u32	3030100224
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	24380
ISDYNVOLChkSumValidCount_Cnt_M_u16	44678
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	31572
ISDYNVOLMsgCountValidCount_Cnt_M_u16	22998
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	19710
ISDYNVOLMsgLenValidCount_Cnt_M_u16	8488
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	49652
ISDYNVOLMsgTimer_mS_M_u32	4140132608
IgnOnTimer_mS_M_u32	128952576
IgnTimeOff_Sec_M_u32	1846229101
ManVehSpd_Kph_M_f32	300.144104
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	75
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	24
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3251198208
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	81
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2226895104
PrevISDATBSI412MsgDLCError_Cnt_M_u08	213
PrevISDATBSI412MsgRxTime_MSec_M_u32	1261431040
PrevISDATBSI432MsgDLCError_Cnt_M_u08	136
PrevISDATBSI432MsgRxTime_MSec_M_u32	3116747008
PrevISDATDIRAMsgTxTime_MSec_M_u32	2333337856
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	251
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2421684480
PrevISDYNAASMsgDLCError_Cnt_M_u08	17
PrevISDYNAASMsgRxTime_MSec_M_u32	641427712
PrevISDYNABRMsgDLCError_Cnt_M_u08	170
PrevISDYNABRMsgRxTime_MSec_M_u32	1753721088
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	59
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1894541568
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	115
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2442447104
PrevISDYNVOLMsgDLCError_Cnt_M_u08	254
PrevISDYNVOLMsgRxTime_MSec_M_u32	2396580096
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	998414592
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	475.10849
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	35382
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	11047
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	13371
VitesseVehicleBVRampValidCount_Cnt_M_u16	48876
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	13442
VitesseVehicleBVSigValidCount_Cnt_M_u16	47100
VitesseVehicleBV_Kph_M_f32	84.1922989
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	25272
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	6282
VitesseVehiculeRoues_Kph_M_f32	13.9961996

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNTCEnableTimeout_mS_u16	25714
k_AASNodeAbsentDiag_Cnt_str.Threshold	49353
k_AASNodeAbsentDiag_Cnt_str.PStep	14481
k_AASNodeAbsentDiag_Cnt_str.NStep	25307
k_AASNodeAbsentTimeout_mS_u16	28073
k_AASNodeTimeout_mS_u16	61991
k_ABSNodeTimeout_mS_u16	46415
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	33839
k_ANGLEVOLANTSigValidThresh_Cnt_u16	29428
k_AngleVolantInvalidThresh_Cnt_u16	38295
k_AngleVolantValidThresh_Cnt_u16	64882
k_BSI552MsgTimeout_mS_u16	62701
k_BSINTCEnableTimeout_mS_u16	52704
k_BSINodeAbsentDiag_Cnt_str.Threshold	26492
k_BSINodeAbsentDiag_Cnt_str.PStep	34281
k_BSINodeAbsentDiag_Cnt_str.NStep	15326
k_BSINodeAbsentTimeout_mS_u16	49708
k_BSINodeTimeout_mS_u16	46142
k_BattOvHi_Volt_f32	11.3122997
k_BattOvLo_Volt_f32	1.92120004
k_BattUvHi_Volt_f32	30.8792992
k_BattUvLo_Volt_f32	16.2784996
k_CAVNTCEnableTimeout_mS_u16	9792
k_CAVNodeAbsentDiag_Cnt_str.Threshold	46929
k_CAVNodeAbsentDiag_Cnt_str.PStep	29794
k_CAVNodeAbsentDiag_Cnt_str.NStep	45890
k_CAVNodeAbsentTimeout_mS_u16	27431
k_CAVNodeTimeout_mS_u16	26930
k_CMM388MsgTimeout_mS_u16	31931
k_CMM388NTCEnableTimeout_mS_u16	63143
k_CMMNTCEnableTimeout_mS_u16	20318
k_CMMNodeAbsentDiag_Cnt_str.Threshold	23318
k_CMMNodeAbsentDiag_Cnt_str.PStep	39565
k_CMMNodeAbsentDiag_Cnt_str.NStep	63059
k_CMMNodeAbsentTimeout_mS_u16	45174
k_CONSANGLECPKMax_HwDeg_f32	519.754211
k_CONSANGLECPKMin_HwDeg_f32	-183.670197
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	59832
k_CONSANGLECPKSigValidThresh_Cnt_u16	57226
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	64965
k_CPKVehicleSpeedValidThresh_Cnt_u16	57030
k_CityParkInputInvalidThresh_Cnt_u16	17781
k_CityParkInputValidThresh_Cnt_u16	26326
k_ComputerRazGCTSigValidThresh_Cnt_u16	58372
k_CptTemporelSigValidThresh_Cnt_u16	20065
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	47809
k_DMDFCTCPKSigValidThresh_Cnt_u16	5067
k_DMDFCTCPKValidCount_Cnt_u16	47520
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	13145
k_DMDRELAXECPKSigValidThresh_Cnt_u16	31643
k_DMDRelaxeConsistentThresh_Cnt_u16	35129
k_DateValidThresh_Cnt_u16	8190
k_DefaultVehSpd_Kph_f32	254.262604
k_DiagMuxOnAbsentTimeout_mS_u16	47661
k_EMNodeTimeout_mS_u16	48319
k_ESPNTCEnableTimeout_mS_u16	6941
k_ESPNodeAbsentDiag_Cnt_str.Threshold	14081
k_ESPNodeAbsentDiag_Cnt_str.PStep	9243
k_ESPNodeAbsentDiag_Cnt_str.NStep	12458
k_ESPNodeAbsentTimeout_mS_u16	34718
k_EtatMTSigInvalidThresh_Cnt_u16	35418
k_EtatMTSigValidThresh_Cnt_u16	27132
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	32500
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	27274
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	23259
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	27839
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	32092
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	50955
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	62145
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	2822
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	63516
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	53459
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	56512

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	25788
k_ISDATDIRASentDiag_Cnt_str.Threshold	42732
k_ISDATDIRASentDiag_Cnt_str.PStep	3144
k_ISDATDIRASentDiag_Cnt_str.NStep	10267
k_ISDATDIRASentTimeout_mS_u16	64067
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	11501
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	10068
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	58457
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	40535
k_ISDYNAASChkSumValidThresh_Cnt_u16	29113
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	55360
k_ISDYNAASMsgCountValidThresh_Cnt_u16	63193
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	64363
k_ISDYNAASMsgLenValidThresh_Cnt_u16	53819
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	20508
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	62903
k_ISDYNABRChkSumValidThresh_Cnt_u16	47937
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	33912
k_ISDYNABRMsgCountValidThresh_Cnt_u16	13426
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	35060
k_ISDYNABRMsgLenValidThresh_Cnt_u16	61817
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	18517
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	35402
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	47676
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	59786
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	60925
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	10167
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	19530
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	62366
k_ISDYNVOLChkSumValidThresh_Cnt_u16	26924
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	48914
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	13773
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	32768
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	1334
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	5964
k_IgnOnTimeout_mS_u16	47754
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	205.266998
k_PowerCutVehSpdLowThresh_Kph_f32	154.306
k_PowerCutVehSpdLowTimeout_mS_u16	4750
k_VBattMaxAAS_Volt_f32	7.42810011
k_VBattMaxBSI_Volt_f32	10.2349005
k_VBattMaxCAV_Volt_f32	20.3362999
k_VBattMaxCMM388_Volt_f32	29.4554996
k_VBattMaxCMM_Volt_f32	13.5654001
k_VBattMaxESP_Volt_f32	13.8326998
k_VBattMinAAS_Volt_f32	3.95650005
k_VBattMinBSI_Volt_f32	13.8326998
k_VBattMinCAV_Volt_f32	32
k_VBattMinCMM388_Volt_f32	9.69939995
k_VBattMinCMM_Volt_f32	23.5886993
k_VBattMinESP_Volt_f32	13.5654001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	4175
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	1101
k_VitesseVehicleBVRampValidThresh_Cnt_u16	596
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	62854
k_VitesseVehicleBVSigValidThresh_Cnt_u16	12723
k_VitesseVehicleBVSpeedPassThresh_kph_f32	580.268616
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	19249
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	16994
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2427324672
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	199
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	16373
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	740309760
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	115
target_SrlComInput_Per1_Batt_Volt_f32.value	19.4193993
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	138164480
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	102
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.845675468
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1696704768
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2541897984
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	187
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1299376384
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1861454080
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3825477888
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2493827328
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1758816512
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	61
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	169
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	718833920
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	109
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	172
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	949004544
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	130
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2960214272
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1809967360
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	90
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	121
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	138
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2509617408
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2400
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.438268512
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	734171
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	47.5387001
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	51480

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	740309760	740309760	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNodeAbsentFltAcc_Cnt_M_u16	49353	49353	✔
AASNodeAbsentTimer_mS_M_u32	740309760	740309760	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	740309760	740309760	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	224.502121	224.502121	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	740309760	740309760	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	740309760	740309760	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	740309760	740309760	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	740309760	740309760	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	740309760	740309760	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	740309760	740309760	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	740309760	740309760	✔
CDD_SrlComVehSpd_Kph_G_f32	300.144104	300.144104	✔
CMM388NTCEnableTimer_mS_M_u32	740309760	740309760	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	740309760	740309760	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	23318	23318	✔
CMMNodeAbsentTimer_mS_M_u32	740309760	740309760	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	11743	11743	✔
CONSANGLECPK_HwDeg_M_f32	-197.5271	-197.5271 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	740309760	740309760	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	740309760	740309760	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	740309760	740309760	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	740309760	740309760	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	740309760	740309760	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	740309760	740309760	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	740309760	740309760	✔
ESPNTCEnableTimer_mS_M_u32	740309760	740309760	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	14081	14081	✔
ESPNodeAbsentTimer_mS_M_u32	740309760	740309760	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	8	8	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	55656	55656	✔
ElecIntTimer_mS_M_u32[1]	87787	87787	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	740309760	740309760	✔
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	8190	8190	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	740309760	740309760	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13386	13386	✔
ISDATBSI3F2MsgTimer_mS_M_u32	740309760	740309760	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	2068	2068	✔
ISDATBSI412MsgTimer_mS_M_u32	740309760	740309760	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	46142	46142	✔
ISDATBSI432MsgTimer_mS_M_u32	740309760	740309760	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	740309760	740309760	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	13145	13145	✔
ISDYN2CMMMsgTimer_mS_M_u32	740309760	740309760	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	4293	4293	✔
ISDYNAASMsgTimer_mS_M_u32	740309760	740309760	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	11743	11743	✔
ISDYNABRMsgTimer_mS_M_u32	740309760	740309760	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13386	13386	✔
ISDYNCMM208MsgTimer_mS_M_u32	740309760	740309760	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	25272	25272	✔
ISDYNCMM388MsgTimer_mS_M_u32	740309760	740309760	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	49652	49652	✔
ISDYNVOLMsgTimer_mS_M_u32	740309760	740309760	✔
IgnOnTimer_mS_M_u32	128952576	128952576	✔
IgnTimeOff_Sec_M_u32	1846229101	1846229101	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	220	220	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1696704768	1696704768	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	68	68	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2541897984	2541897984	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	187	187	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1299376384	1299376384	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1861454080	1861454080	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2333337856	2333337856	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	142	142	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2493827328	2493827328	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	83	83	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1758816512	1758816512	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	119	119	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	718833920	718833920	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	181	181	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	949004544	949004544	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	130	130	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2960214272	2960214272	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	31	31	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1809967360	1809967360	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2509617408	2509617408	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	475.10849	475.10849	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	84.1922989	84.1922989	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	13.9961996	13.9961996	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	224.502121	224.502121	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	11743	11743	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1846229101	1846229101	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-197.5271	-197.5271 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	300.144104	300.144104	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.126 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	25098240
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	51729
AASNodeAbsentTimer_mS_M_u32	239364096
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	41033
ANGLEVOLANTSigValidCount_Cnt_M_u16	62940
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	22854
AngleVolantMsgTimer_mS_M_u32	25098240
AngleVolantValidCount_Cnt_M_u16	54650
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	40.3436356
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	25044992
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	821602304
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2971703296
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	762402816
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	65535
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3604289536
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	57135
CAVNodeAbsentTimer_mS_M_u32	3696887808
CDD_SrlComVehSpd_Kph_G_f32	137.130096
CMM388NTCEnableTimer_mS_M_u32	1674332160
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1686112256
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	56742
CMMNodeAbsentTimer_mS_M_u32	3083556864
CONSANGLECPKSigInvalidCount_Cnt_M_u16	41839
CONSANGLECPKSigValidCount_Cnt_M_u16	32210
CONSANGLECPK_Cnt_M_u16	23909
CONSANGLECPK_HwDeg_M_f32	469.645111
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	23909
CPKVehicleSpeedMsgTimer_mS_M_u32	629536768
CPKVehicleSpeedValidCount_Cnt_M_u16	13133
CityParkInputConsistentCount_Cnt_M_u16	27966
CityParkInputInvalidCount_Cnt_M_u16	27241
CityParkInputMsgTimer_mS_M_u32	1696704768
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2533910528
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	51157

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3338045440
ComputerRazGCTSigValidCount_Cnt_M_u16	64875
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	52901
DMDFCTCPKSigValidCount_Cnt_M_u16	39776
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	52011
DMDRELAXECPKSigValidCount_Cnt_M_u16	58942
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	58276
DateInvalidTimer_mS_M_u32	821602304
DiagMuxOnAbsentTimer_mS_M_u32	2596452352
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	762402816
ESPNTCEnableTimer_mS_M_u32	603809792
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	54997
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	79
EffacDefaultDiagTimer_mS_M_u32[1]	699
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	2323
ElecIntTimer_mS_M_u32[1]	454646
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1628903424
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	56389
EtatMTSigValidCount_Cnt_M_u16	35428
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	62545
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	5172
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	3462
ISDAT4V2BSI552MsgTimer_mS_M_u32	193943552
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	23663
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	14230
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	35428
ISDATBSI3F2MsgTimer_mS_M_u32	2715858944
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	28444
ISDATBSI412MsgLenValidCount_Cnt_M_u16	57075
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	56389
ISDATBSI412MsgTimer_mS_M_u32	3734829056
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	15466
ISDATBSI432MsgLenValidCount_Cnt_M_u16	32921
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	33544
ISDATDIRASentFltAcc_Cnt_M_u16	15452
ISDATDIRASentTimer_mS_M_u32	629536768
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	7939
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	54650
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	9396
ISDYN2CMMMsgTimer_mS_M_u32	1993828352
ISDYNAASChkSumInvalidCount_Cnt_M_u16	41203
ISDYNAASChkSumValidCount_Cnt_M_u16	43686
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	393
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	57602
ISDYNAASMsgLenValidCount_Cnt_M_u16	42605
ISDYNAASMsgTimeValidCount_Cnt_M_u16	41203
ISDYNAASMsgTimer_mS_M_u32	1695041536
ISDYNABRChkSumInvalidCount_Cnt_M_u16	20156
ISDYNABRChkSumValidCount_Cnt_M_u16	30551
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	2946
ISDYNABRMsgCountValidCount_Cnt_M_u16	12917
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	63742
ISDYNABRMsgLenValidCount_Cnt_M_u16	12449
ISDYNABRMsgTimeValidCount_Cnt_M_u16	23909
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	728
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1341
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	35428
ISDYNCMM208MsgTimer_mS_M_u32	602613760
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2763
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1447
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	33176

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	61851648
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	41613
ISDYNVOLChkSumValidCount_Cnt_M_u16	14192
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	63683
ISDYNVOLMsgCountValidCount_Cnt_M_u16	49150
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	838
ISDYNVOLMsgLenValidCount_Cnt_M_u16	35209
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	56742
ISDYNVOLMsgTimer_mS_M_u32	338855936
IgnOnTimer_mS_M_u32	1517537280
IgnTimeOff_Sec_M_u32	2271873183
ManVehSpd_Kph_M_f32	179.607895
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	77
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	211
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4008097792
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	247
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3884947456
PrevISDATBSI412MsgDLCError_Cnt_M_u08	141
PrevISDATBSI412MsgRxTime_MSec_M_u32	3774023680
PrevISDATBSI432MsgDLCError_Cnt_M_u08	210
PrevISDATBSI432MsgRxTime_MSec_M_u32	3299960832
PrevISDATDIRAMsgTxTime_MSec_M_u32	2974222336
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	124
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2243614720
PrevISDYNAASMsgDLCError_Cnt_M_u08	76
PrevISDYNAASMsgRxTime_MSec_M_u32	3721431040
PrevISDYNABRMsgDLCError_Cnt_M_u08	123
PrevISDYNABRMsgRxTime_MSec_M_u32	2548811776
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	232
PrevISDYNCMM208MsgRxTime_MSec_M_u32	29198336
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	177
PrevISDYNCMM388MsgRxTime_MSec_M_u32	960784384
PrevISDYNVOLMsgDLCError_Cnt_M_u08	176
PrevISDYNVOLMsgRxTime_MSec_M_u32	4193781760
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4139448320
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	57.8767014
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57632
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	8459
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	14097
VitesseVehicleBVRampValidCount_Cnt_M_u16	47548
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	3002
VitesseVehicleBVSigValidCount_Cnt_M_u16	50189
VitesseVehicleBV_Kph_M_f32	274.317413
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	33176
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	739
VitesseVehiculeRoues_Kph_M_f32	206.730194
k_AASNTCEnableTimeout_mS_u16	50604
k_AASNodeAbsentDiag_Cnt_str.Threshold	8990

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	22397
k_AASNodeAbsentDiag_Cnt_str.NStep	11926
k_AASNodeAbsentTimeout_mS_u16	25797
k_AASNodeTimeout_mS_u16	52235
k_ABSNodeTimeout_mS_u16	63186
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	17141
k_ANGLEVOLANTSigValidThresh_Cnt_u16	59748
k_AngleVolantInvalidThresh_Cnt_u16	52603
k_AngleVolantValidThresh_Cnt_u16	27241
k_BSI552MsgTimeout_mS_u16	47546
k_BSINTCEnableTimeout_mS_u16	27106
k_BSINodeAbsentDiag_Cnt_str.Threshold	0
k_BSINodeAbsentDiag_Cnt_str.PStep	34264
k_BSINodeAbsentDiag_Cnt_str.NStep	15349
k_BSINodeAbsentTimeout_mS_u16	59582
k_BSINodeTimeout_mS_u16	33544
k_BattOvHi_Volt_f32	14.7510004
k_BattOvLo_Volt_f32	11.4082003
k_BattUvHi_Volt_f32	14.2580996
k_BattUvLo_Volt_f32	3.56579995
k_CAVNTCEnableTimeout_mS_u16	43007
k_CAVNodeAbsentDiag_Cnt_str.Threshold	28124
k_CAVNodeAbsentDiag_Cnt_str.PStep	6050
k_CAVNodeAbsentDiag_Cnt_str.NStep	3130
k_CAVNodeAbsentTimeout_mS_u16	16973
k_CAVNodeTimeout_mS_u16	56491
k_CMM388MsgTimeout_mS_u16	46353
k_CMM388NTCEnableTimeout_mS_u16	63309
k_CMMNTCEnableTimeout_mS_u16	1511
k_CMMNodeAbsentDiag_Cnt_str.Threshold	12055
k_CMMNodeAbsentDiag_Cnt_str.PStep	38250
k_CMMNodeAbsentDiag_Cnt_str.NStep	6415
k_CMMNodeAbsentTimeout_mS_u16	60191
k_CONSANGLECPKMax_HwDeg_f32	366.575989
k_CONSANGLECPKMin_HwDeg_f32	-49.0112991
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	60568
k_CONSANGLECPKSigValidThresh_Cnt_u16	44515
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	41265
k_CPKVehicleSpeedValidThresh_Cnt_u16	18607
k_CityParkInputInvalidThresh_Cnt_u16	48226
k_CityParkInputValidThresh_Cnt_u16	27966
k_ComputerRazGCTSigValidThresh_Cnt_u16	24565
k_CptTemporelSigValidThresh_Cnt_u16	62364
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	58366
k_DMDFCTCPKSigValidThresh_Cnt_u16	23457
k_DMDFCTCPKValidCount_Cnt_u16	29792
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	9396
k_DMDRELAXECPKSigValidThresh_Cnt_u16	44719
k_DMDRelaxeConsistentThresh_Cnt_u16	32213
k_DateValidThresh_Cnt_u16	3462
k_DefaultVehSpd_Kph_f32	248.973007
k_DiagMuxOnAbsentTimeout_mS_u16	28795
k_EMNodeTimeout_mS_u16	22020
k_ESPNTCEnableTimeout_mS_u16	35435
k_ESPNodeAbsentDiag_Cnt_str.Threshold	9143
k_ESPNodeAbsentDiag_Cnt_str.PStep	7713
k_ESPNodeAbsentDiag_Cnt_str.NStep	17514
k_ESPNodeAbsentTimeout_mS_u16	1447
k_EtatMTSigInvalidThresh_Cnt_u16	49587
k_EtatMTSigValidThresh_Cnt_u16	1422
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	39332
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	35234
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	58671
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	29124
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	4779
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	58336
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	48959
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	59694
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	56110
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	17545
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	13184
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	24524
k_ISDATDIRASentDiag_Cnt_str.Threshold	53644

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	28273
k_ISDATDIRASentDiag_Cnt_str.NStep	22576
k_ISDATDIRASentTimeout_mS_u16	22008
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	2873
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	22854
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	7863
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	47548
k_ISDYNAASChkSumValidThresh_Cnt_u16	8791
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	63106
k_ISDYNAASMsgCountValidThresh_Cnt_u16	23925
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	62080
k_ISDYNAASMsgLenValidThresh_Cnt_u16	31695
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	61932
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	35612
k_ISDYNABRChkSumValidThresh_Cnt_u16	48447
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	29656
k_ISDYNABRMsgCountValidThresh_Cnt_u16	42667
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	34982
k_ISDYNABRMsgLenValidThresh_Cnt_u16	49621
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	46850
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	12516
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	3661
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	12770
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	35657
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	8412
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	56801
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	27175
k_ISDYNVOLChkSumValidThresh_Cnt_u16	39998
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	64778
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	9755
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	9345
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	51104
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	57244
k_IgnOnTimeout_mS_u16	50531
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	120.459801
k_PowerCutVehSpdLowThresh_Kph_f32	185.342697
k_PowerCutVehSpdLowTimeout_mS_u16	11096
k_VBattMaxAAS_Volt_f32	11.4583998
k_VBattMaxBSI_Volt_f32	11.3523998
k_VBattMaxCAV_Volt_f32	21.1702003
k_VBattMaxCMM388_Volt_f32	31.0021992
k_VBattMaxCMM_Volt_f32	17.9253998
k_VBattMaxESP_Volt_f32	24.3099003
k_VBattMinAAS_Volt_f32	9.85249996
k_VBattMinBSI_Volt_f32	24.3099003
k_VBattMinCAV_Volt_f32	15.9569998
k_VBattMinCMM388_Volt_f32	1.93729997
k_VBattMinCMM_Volt_f32	0.584999979
k_VBattMinESP_Volt_f32	17.9253998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	26899
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	57306
k_VitesseVehicleBVRampValidThresh_Cnt_u16	25539
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	25200
k_VitesseVehicleBVSigValidThresh_Cnt_u16	49319
k_VitesseVehicleBVSpeedPassThresh_kph_f32	535.260071
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	18991
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	34650
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	821602304
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	126
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	42915
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	501879296
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	177
target_SrlComInput_Per1_Batt_Volt_f32.value	6.0868001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4279113728
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	80
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.633640051
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2317207552
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3179014144
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2787772416
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	236
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2351441920
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3077982208
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	213
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1880385536
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	111
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4261578752
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	62
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	129
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	147
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	161
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	746137600
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	76
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	7
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2345715712
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4004440064
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3336374272
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	88
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	129
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2634127360
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1647
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.697272003
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	517672
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	27.8946991
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	11386

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	501879296	501879296	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	8990	8990	✔
AASNodeAbsentTimer_mS_M_u32	501879296	501879296	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	501879296	501879296	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	40.3436356	40.3436356	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	501879296	501879296	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	501879296	501879296	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	501879296	501879296	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	501879296	501879296	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	501879296	501879296	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	501879296	501879296	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	501879296	501879296	✔
CDD_SrlComVehSpd_Kph_G_f32	179.607895	179.607895	✔
CMM388NTCEnableTimer_mS_M_u32	501879296	501879296	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	501879296	501879296	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	12055	12055	✔
CMMNodeAbsentTimer_mS_M_u32	501879296	501879296	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	23909	23909	✔
CONSANGLECPK_HwDeg_M_f32	469.645111	469.645111 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	501879296	501879296	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	501879296	501879296	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	501879296	501879296	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	501879296	501879296	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	501879296	501879296	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	501879296	501879296	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	501879296	501879296	✔
ESPNTCEnableTimer_mS_M_u32	501879296	501879296	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	9143	9143	✔
ESPNodeAbsentTimer_mS_M_u32	501879296	501879296	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	79	79	✔
EffacDefaultDiagTimer_mS_M_u32[1]	699	699	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2323	2323	✔
ElecIntTimer_mS_M_u32[1]	454646	454646	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	501879296	501879296	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	3462	3462	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	501879296	501879296	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	35428	35428	✔
ISDATBSI3F2MsgTimer_mS_M_u32	501879296	501879296	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	56389	56389	✔
ISDATBSI412MsgTimer_mS_M_u32	501879296	501879296	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	33544	33544	✔
ISDATBSI432MsgTimer_mS_M_u32	501879296	501879296	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	501879296	501879296	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	9396	9396	✔
ISDYN2CMMMsgTimer_mS_M_u32	501879296	501879296	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	41203	41203	✔
ISDYNAASMsgTimer_mS_M_u32	501879296	501879296	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	23909	23909	✔
ISDYNABRMsgTimer_mS_M_u32	501879296	501879296	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	35428	35428	✔
ISDYNCMM208MsgTimer_mS_M_u32	501879296	501879296	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	33176	33176	✔
ISDYNCMM388MsgTimer_mS_M_u32	501879296	501879296	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	56742	56742	✔
ISDYNVOLMsgTimer_mS_M_u32	501879296	501879296	✔
IgnOnTimer_mS_M_u32	1517537280	1517537280	✔
IgnTimeOff_Sec_M_u32	2271873183	2271873183	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	21	21	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2317207552	2317207552	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	137	137	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3179014144	3179014144	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	14	14	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2787772416	2787772416	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	236	236	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2351441920	2351441920	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2974222336	2974222336	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	213	213	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1880385536	1880385536	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	111	111	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4261578752	4261578752	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	216	216	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	746137600	746137600	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	7	7	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2345715712	2345715712	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	75	75	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4004440064	4004440064	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	95	95	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3336374272	3336374272	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2634127360	2634127360	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	57.8767014	57.8767014	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	274.317413	274.317413	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	206.730194	206.730194	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	40.3436356	40.3436356	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	23909	23909	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2271873183	2271873183	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	469.645111	469.645111 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.127 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2432817920
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	41290
AASNodeAbsentTimer_mS_M_u32	2356251392
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	41120
ANGLEVOLANTSigValidCount_Cnt_M_u16	55208
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	1963
AngleVolantMsgTimer_mS_M_u32	2432817920
AngleVolantValidCount_Cnt_M_u16	2958
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	245.264801
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3385084672
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1163184896
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2426206976
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1319811840
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	8008
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2441050880
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	24689
CAVNodeAbsentTimer_mS_M_u32	11578112
CDD_SrlComVehSpd_Kph_G_f32	408.381409
CMM388NTCEnableTimer_mS_M_u32	56224512
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2151590656
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	32203
CMMNodeAbsentTimer_mS_M_u32	2543631104
CONSANGLECPKSigInvalidCount_Cnt_M_u16	24111
CONSANGLECPKSigValidCount_Cnt_M_u16	18118
CONSANGLECPK_Cnt_M_u16	46093
CONSANGLECPK_HwDeg_M_f32	-243.836899
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	46093
CPKVehicleSpeedMsgTimer_mS_M_u32	15522560
CPKVehicleSpeedValidCount_Cnt_M_u16	27775
CityParkInputConsistentCount_Cnt_M_u16	21570
CityParkInputInvalidCount_Cnt_M_u16	6593
CityParkInputMsgTimer_mS_M_u32	2317207552
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	36014848
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	47102

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1390095104
ComputerRazGCTSigValidCount_Cnt_M_u16	38843
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	56589
DMDFCTCPKSigValidCount_Cnt_M_u16	20124
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	10234
DMDRELAXECPKSigValidCount_Cnt_M_u16	3714
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	45456
DateInvalidTimer_mS_M_u32	1163184896
DiagMuxOnAbsentTimer_mS_M_u32	2218171136
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1319811840
ESPNTCEnableTimer_mS_M_u32	1866894080
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	14847
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	86
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	56565
ElecIntTimer_mS_M_u32[1]	787879
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2058976000
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	3822
EtatMTSigValidCount_Cnt_M_u16	27729
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	29577
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	35744
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	4138
ISDAT4V2BSI552MsgTimer_mS_M_u32	2890971904
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	45039
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	42554
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	27729
ISDATBSI3F2MsgTimer_mS_M_u32	1725733632
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	30954
ISDATBSI412MsgLenValidCount_Cnt_M_u16	28965
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	3822
ISDATBSI412MsgTimer_mS_M_u32	4054309632
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	29055
ISDATBSI432MsgLenValidCount_Cnt_M_u16	19635
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	6374
ISDATDIRASentFltAcc_Cnt_M_u16	15594
ISDATDIRASentTimer_mS_M_u32	15522560
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	26419
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	2958
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	55008
ISDYN2CMMMsgTimer_mS_M_u32	1589152512
ISDYNAASChkSumInvalidCount_Cnt_M_u16	9380
ISDYNAASChkSumValidCount_Cnt_M_u16	48971
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	33633
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	26360
ISDYNAASMsgLenValidCount_Cnt_M_u16	44663
ISDYNAASMsgTimeValidCount_Cnt_M_u16	9380
ISDYNAASMsgTimer_mS_M_u32	4020628224
ISDYNABRChkSumInvalidCount_Cnt_M_u16	54985
ISDYNABRChkSumValidCount_Cnt_M_u16	46264
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	57591
ISDYNABRMsgCountValidCount_Cnt_M_u16	9182
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	22914
ISDYNABRMsgLenValidCount_Cnt_M_u16	10841
ISDYNABRMsgTimeValidCount_Cnt_M_u16	46093
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	729
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1343
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	27729
ISDYNCMM208MsgTimer_mS_M_u32	1451051776
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2767
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1449
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	65332

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	296708864
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	22741
ISDYNVOLChkSumValidCount_Cnt_M_u16	4588
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	22195
ISDYNVOLMsgCountValidCount_Cnt_M_u16	55490
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	47276
ISDYNVOLMsgLenValidCount_Cnt_M_u16	7587
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	32203
ISDYNVOLMsgTimer_mS_M_u32	1529293568
IgnOnTimer_mS_M_u32	493054720
IgnTimeOff_Sec_M_u32	27385893
ManVehSpd_Kph_M_f32	490.540985
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	79
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	173
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	399153920
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	209
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1766849280
PrevISDATBSI412MsgDLCError_Cnt_M_u08	177
PrevISDATBSI412MsgRxTime_MSec_M_u32	2531633920
PrevISDATBSI432MsgDLCError_Cnt_M_u08	195
PrevISDATBSI432MsgRxTime_MSec_M_u32	1563069184
PrevISDATDIRAMsgTxTime_MSec_M_u32	1978247936
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	192
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1271806720
PrevISDYNAASMsgDLCError_Cnt_M_u08	29
PrevISDYNAASMsgRxTime_MSec_M_u32	4132252416
PrevISDYNABRMsgDLCError_Cnt_M_u08	162
PrevISDYNABRMsgRxTime_MSec_M_u32	1157327616
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	252
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2122722048
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	75
PrevISDYNCMM388MsgRxTime_MSec_M_u32	191990528
PrevISDYNVOLMsgDLCError_Cnt_M_u08	104
PrevISDYNVOLMsgRxTime_MSec_M_u32	2681645824
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2706234112
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	302.588501
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	24222
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	13981
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	24779
VitesseVehicleBVRampValidCount_Cnt_M_u16	28810
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	25165
VitesseVehicleBVSigValidCount_Cnt_M_u16	28949
VitesseVehicleBV_Kph_M_f32	553.170105
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	65332
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	37652
VitesseVehiculeRoues_Kph_M_f32	277.77771
k_AASNTCEnableTimeout_mS_u16	22328
k_AASNodeAbsentDiag_Cnt_str.Threshold	51065

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	14134
k_AASNodeAbsentDiag_Cnt_str.NStep	36866
k_AASNodeAbsentTimeout_mS_u16	18861
k_AASNodeTimeout_mS_u16	13725
k_ABSNodeTimeout_mS_u16	22662
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	18910
k_ANGLEVOLANTSigValidThresh_Cnt_u16	65106
k_AngleVolantInvalidThresh_Cnt_u16	28173
k_AngleVolantValidThresh_Cnt_u16	6593
k_BSI552MsgTimeout_mS_u16	35471
k_BSINTCEnableTimeout_mS_u16	51479
k_BSINodeAbsentDiag_Cnt_str.Threshold	65535
k_BSINodeAbsentDiag_Cnt_str.PStep	34247
k_BSINodeAbsentDiag_Cnt_str.NStep	15372
k_BSINodeAbsentTimeout_mS_u16	14659
k_BSINodeTimeout_mS_u16	6374
k_BattOvHi_Volt_f32	21.0955009
k_BattOvLo_Volt_f32	28.1723995
k_BattUvHi_Volt_f32	10.4500999
k_BattUvLo_Volt_f32	11.0110998
k_CAVNTCEnableTimeout_mS_u16	14591
k_CAVNodeAbsentDiag_Cnt_str.Threshold	48184
k_CAVNodeAbsentDiag_Cnt_str.PStep	64512
k_CAVNodeAbsentDiag_Cnt_str.NStep	60047
k_CAVNodeAbsentTimeout_mS_u16	12055
k_CAVNodeTimeout_mS_u16	41595
k_CMM388MsgTimeout_mS_u16	57418
k_CMM388NTCEnableTimeout_mS_u16	2454
k_CMMNTCEnableTimeout_mS_u16	37767
k_CMMNodeAbsentDiag_Cnt_str.Threshold	37616
k_CMMNodeAbsentDiag_Cnt_str.PStep	53710
k_CMMNodeAbsentDiag_Cnt_str.NStep	25079
k_CMMNodeAbsentTimeout_mS_u16	51808
k_CONSANGLECPKMax_HwDeg_f32	546.153687
k_CONSANGLECPKMin_HwDeg_f32	-766.503418
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	48692
k_CONSANGLECPKSigValidThresh_Cnt_u16	37396
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	52779
k_CPKVehicleSpeedValidThresh_Cnt_u16	63537
k_CityParkInputInvalidThresh_Cnt_u16	42455
k_CityParkInputValidThresh_Cnt_u16	21570
k_ComputerRazGCTSigValidThresh_Cnt_u16	15709
k_CptTemporelSigValidThresh_Cnt_u16	2600
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	39042
k_DMDFCTCPKSigValidThresh_Cnt_u16	43353
k_DMDFCTCPKValidCount_Cnt_u16	16475
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	55008
k_DMDRELAXECPKSigValidThresh_Cnt_u16	4271
k_DMDRelaxeConsistentThresh_Cnt_u16	47933
k_DateValidThresh_Cnt_u16	4138
k_DefaultVehSpd_Kph_f32	187.076096
k_DiagMuxOnAbsentTimeout_mS_u16	21195
k_EMNodeTimeout_mS_u16	55920
k_ESPNTCEnableTimeout_mS_u16	20157
k_ESPNodeAbsentDiag_Cnt_str.Threshold	39920
k_ESPNodeAbsentDiag_Cnt_str.PStep	18314
k_ESPNodeAbsentDiag_Cnt_str.NStep	53447
k_ESPNodeAbsentTimeout_mS_u16	39624
k_EtatMTSigInvalidThresh_Cnt_u16	6628
k_EtatMTSigValidThresh_Cnt_u16	42515
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	28882
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	34965
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	61551
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	1008
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	43259
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	10910
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	32000
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	42740
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	42291
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	36513
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	35196
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	47065
k_ISDATDIRASentDiag_Cnt_str.Threshold	63911

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	39954
k_ISDATDIRASentDiag_Cnt_str.NStep	1837
k_ISDATDIRASentTimeout_mS_u16	45333
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	43410
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	1963
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	49625
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	38345
k_ISDYNAASChkSumValidThresh_Cnt_u16	46008
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	8183
k_ISDYNAASMsgCountValidThresh_Cnt_u16	41694
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	64381
k_ISDYNAASMsgLenValidThresh_Cnt_u16	13905
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	1210
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	39720
k_ISDYNABRChkSumValidThresh_Cnt_u16	31871
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	8691
k_ISDYNABRMsgCountValidThresh_Cnt_u16	49467
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	31947
k_ISDYNABRMsgLenValidThresh_Cnt_u16	30975
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	44086
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	32594
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	40791
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	8216
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	57248
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	22184
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	40793
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	29641
k_ISDYNVOLChkSumValidThresh_Cnt_u16	9540
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	56160
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	47212
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	9786
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	42141
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	29160
k_IgnOnTimeout_mS_u16	21013
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	119.115601
k_PowerCutVehSpdLowThresh_Kph_f32	188.467194
k_PowerCutVehSpdLowTimeout_mS_u16	54836
k_VBattMaxAAS_Volt_f32	13.0618
k_VBattMaxBSI_Volt_f32	21.4363003
k_VBattMaxCAV_Volt_f32	3.61660004
k_VBattMaxCMM388_Volt_f32	27.5524998
k_VBattMaxCMM_Volt_f32	18.0237999
k_VBattMaxESP_Volt_f32	10.3107996
k_VBattMinAAS_Volt_f32	20.9407997
k_VBattMinBSI_Volt_f32	10.3107996
k_VBattMinCAV_Volt_f32	24.3801994
k_VBattMinCMM388_Volt_f32	16.7460995
k_VBattMinCMM_Volt_f32	31.8567009
k_VBattMinESP_Volt_f32	18.0237999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	30724
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	7023
k_VitesseVehicleBVRampValidThresh_Cnt_u16	5555
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	37100
k_VitesseVehicleBVSigValidThresh_Cnt_u16	15879
k_VitesseVehicleBVSpeedPassThresh_kph_f32	429.886688
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	8049
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	65456
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1163184896
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	135
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	21460
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1621658880
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	75
target_SrlComInput_Per1_Batt_Volt_f32.value	28.8638992
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1020558080
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	255
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.175782219
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	58
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3060099840
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3167423232
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	145
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3812666112
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1371949824
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	811330304
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2801896192
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3719768832
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	111
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	114
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	202
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	226
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4107488000
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	47
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	82
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	158
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	232
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1028418304
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3039955712
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	220703488
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	94
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	170
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	195
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2432301824
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3603
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.352446973
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	780424
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	46.0611992
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	25744

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1621658880	1621658880	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	51065	51065	✔
AASNodeAbsentTimer_mS_M_u32	1621658880	1621658880	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1621658880	1621658880	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	245.264801	245.264801	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1621658880	1621658880	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1621658880	1621658880	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1621658880	1621658880	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1621658880	1621658880	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1621658880	1621658880	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1621658880	1621658880	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1621658880	1621658880	✔
CDD_SrlComVehSpd_Kph_G_f32	490.540985	490.540985	✔
CMM388NTCEnableTimer_mS_M_u32	1621658880	1621658880	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1621658880	1621658880	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	37616	37616	✔
CMMNodeAbsentTimer_mS_M_u32	1621658880	1621658880	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	46093	46093	✔
CONSANGLECPK_HwDeg_M_f32	-243.836899	-243.836899 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1621658880	1621658880	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1621658880	1621658880	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1621658880	1621658880	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1621658880	1621658880	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1621658880	1621658880	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1621658880	1621658880	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1621658880	1621658880	✔
ESPNTCEnableTimer_mS_M_u32	1621658880	1621658880	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	39920	39920	✔
ESPNodeAbsentTimer_mS_M_u32	1621658880	1621658880	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔
EffacDefaultDiagTimer_mS_M_u32[1]	86	86	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	56565	56565	✔
ElecIntTimer_mS_M_u32[1]	787879	787879	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1621658880	1621658880	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	4138	4138	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1621658880	1621658880	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	27729	27729	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1621658880	1621658880	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	3822	3822	✔
ISDATBSI412MsgTimer_mS_M_u32	1621658880	1621658880	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	6374	6374	✔
ISDATBSI432MsgTimer_mS_M_u32	1621658880	1621658880	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1621658880	1621658880	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	55008	55008	✔
ISDYN2CMMMsgTimer_mS_M_u32	1621658880	1621658880	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	9380	9380	✔
ISDYNAASMsgTimer_mS_M_u32	1621658880	1621658880	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	46093	46093	✔
ISDYNABRMsgTimer_mS_M_u32	1621658880	1621658880	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	27729	27729	✔
ISDYNCMM208MsgTimer_mS_M_u32	1621658880	1621658880	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	65332	65332	✔
ISDYNCMM388MsgTimer_mS_M_u32	1621658880	1621658880	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	32203	32203	✔
ISDYNVOLMsgTimer_mS_M_u32	1621658880	1621658880	✔
IgnOnTimer_mS_M_u32	493054720	493054720	✔
IgnTimeOff_Sec_M_u32	27385893	27385893	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	58	58	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3060099840	3060099840	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	224	224	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3167423232	3167423232	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	145	145	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3812666112	3812666112	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	119	119	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1371949824	1371949824	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1978247936	1978247936	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	126	126	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2801896192	2801896192	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	239	239	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3719768832	3719768832	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	57	57	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4107488000	4107488000	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	240	240	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1028418304	1028418304	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	39	39	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3039955712	3039955712	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	220703488	220703488	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2432301824	2432301824	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	302.588501	302.588501	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	553.170105	553.170105	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	277.77771	277.77771	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	245.264801	245.264801	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	46093	46093	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	27385893	27385893	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-243.836899	-243.836899 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.128 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4257559040
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	36587
AASNodeAbsentTimer_mS_M_u32	2788565504
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	2792
ANGLEVOLANTSigValidCount_Cnt_M_u16	48786
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	8136
AngleVolantMsgTimer_mS_M_u32	4257559040
AngleVolantValidCount_Cnt_M_u16	43677
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	595.264771
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2839405056
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	411853312
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3547582976
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	4887040
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	20463
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2060210688
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	22006
CAVNodeAbsentTimer_mS_M_u32	0
CDD_SrlComVehSpd_Kph_G_f32	544.004822
CMM388NTCEnableTimer_mS_M_u32	3674014208
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3880698368
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	45991
CMMNodeAbsentTimer_mS_M_u32	1836356096
CONSANGLECPKSigInvalidCount_Cnt_M_u16	32059
CONSANGLECPKSigValidCount_Cnt_M_u16	23606
CONSANGLECPK_Cnt_M_u16	61537
CONSANGLECPK_HwDeg_M_f32	-504.057007
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	61537
CPKVehicleSpeedMsgTimer_mS_M_u32	436482560
CPKVehicleSpeedValidCount_Cnt_M_u16	47252
CityParkInputConsistentCount_Cnt_M_u16	41089
CityParkInputInvalidCount_Cnt_M_u16	6407
CityParkInputMsgTimer_mS_M_u32	3060099840
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	354034176
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	6863

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2172207616
ComputerRazGCTSigValidCount_Cnt_M_u16	64022
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	65315
DMDFCTCPKSigValidCount_Cnt_M_u16	9013
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	23770
DMDRELAXECPKSigValidCount_Cnt_M_u16	516
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	18200
DateInvalidTimer_mS_M_u32	411853312
DiagMuxOnAbsentTimer_mS_M_u32	3878089216
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4887040
ESPNTCEnableTimer_mS_M_u32	2444698112
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	34765
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	5
EffacDefaultDiagTimer_mS_M_u32[1]	155
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	556
ElecIntTimer_mS_M_u32[1]	877877
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	656298496
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	22848
EtatMTSigValidCount_Cnt_M_u16	2518
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	9517
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	30120
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	38539
ISDAT4V2BSI552MsgTimer_mS_M_u32	4283994624
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	4541
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	38812
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	2518
ISDATBSI3F2MsgTimer_mS_M_u32	1463087616
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	46027
ISDATBSI412MsgLenValidCount_Cnt_M_u16	62426
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	22848
ISDATBSI412MsgTimer_mS_M_u32	4090704384
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	43147
ISDATBSI432MsgLenValidCount_Cnt_M_u16	8113
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	16535
ISDATDIRASentFltAcc_Cnt_M_u16	58507
ISDATDIRASentTimer_mS_M_u32	436482560
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	61167
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	43677
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	7594
ISDYN2CMMMsgTimer_mS_M_u32	190915072
ISDYNAASChkSumInvalidCount_Cnt_M_u16	60637
ISDYNAASChkSumValidCount_Cnt_M_u16	62888
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	20260
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	7777
ISDYNAASMsgLenValidCount_Cnt_M_u16	32931
ISDYNAASMsgTimeValidCount_Cnt_M_u16	60637
ISDYNAASMsgTimer_mS_M_u32	1176044032
ISDYNABRChkSumInvalidCount_Cnt_M_u16	41965
ISDYNABRChkSumValidCount_Cnt_M_u16	736
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	50148
ISDYNABRMsgCountValidCount_Cnt_M_u16	54255
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	38722
ISDYNABRMsgLenValidCount_Cnt_M_u16	48509
ISDYNABRMsgTimeValidCount_Cnt_M_u16	61537
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	730
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1345
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	2518
ISDYNCMM208MsgTimer_mS_M_u32	655548928
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2771
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1451
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	59307

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3858530816
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	42313
ISDYNVOLChkSumValidCount_Cnt_M_u16	4804
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	43569
ISDYNVOLMsgCountValidCount_Cnt_M_u16	40131
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	65478
ISDYNVOLMsgLenValidCount_Cnt_M_u16	59808
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	45991
ISDYNVOLMsgTimer_mS_M_u32	2559918592
IgnOnTimer_mS_M_u32	2464186880
IgnTimeOff_Sec_M_u32	3094169899
ManVehSpd_Kph_M_f32	325.087402
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	81
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	240
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2087383552
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	211
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3579499008
PrevISDATBSI412MsgDLCError_Cnt_M_u08	76
PrevISDATBSI412MsgRxTime_MSec_M_u32	4284072448
PrevISDATBSI432MsgDLCError_Cnt_M_u08	115
PrevISDATBSI432MsgRxTime_MSec_M_u32	1477124608
PrevISDATDIRAMsgTxTime_MSec_M_u32	1917698560
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	141
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4141879808
PrevISDYNAASMsgDLCError_Cnt_M_u08	18
PrevISDYNAASMsgRxTime_MSec_M_u32	3743629824
PrevISDYNABRMsgDLCError_Cnt_M_u08	74
PrevISDYNABRMsgRxTime_MSec_M_u32	2081980928
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	94
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1786266112
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	111
PrevISDYNCMM388MsgRxTime_MSec_M_u32	691413504
PrevISDYNVOLMsgDLCError_Cnt_M_u08	203
PrevISDYNVOLMsgRxTime_MSec_M_u32	3901145600
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4242616832
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	579.36261
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	20335
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	49
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	15592
VitesseVehicleBVRampValidCount_Cnt_M_u16	18026
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	47585
VitesseVehicleBVSigValidCount_Cnt_M_u16	58955
VitesseVehicleBV_Kph_M_f32	409.606689
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	59307
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	58574
VitesseVehiculeRoues_Kph_M_f32	44.8857994
k_AASNTCEnableTimeout_mS_u16	29408
k_AASNodeAbsentDiag_Cnt_str.Threshold	59476

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	53909
k_AASNodeAbsentDiag_Cnt_str.NStep	36332
k_AASNodeAbsentTimeout_mS_u16	11328
k_AASNodeTimeout_mS_u16	817
k_ABSNodeTimeout_mS_u16	45240
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	23406
k_ANGLEVOLANTSigValidThresh_Cnt_u16	18132
k_AngleVolantInvalidThresh_Cnt_u16	41891
k_AngleVolantValidThresh_Cnt_u16	6407
k_BSI552MsgTimeout_mS_u16	43613
k_BSINTCEnableTimeout_mS_u16	451
k_BSINodeAbsentDiag_Cnt_str.Threshold	4189
k_BSINodeAbsentDiag_Cnt_str.PStep	34230
k_BSINodeAbsentDiag_Cnt_str.NStep	15395
k_BSINodeAbsentTimeout_mS_u16	60160
k_BSINodeTimeout_mS_u16	16535
k_BattOvHi_Volt_f32	2
k_BattOvLo_Volt_f32	2.67330003
k_BattUvHi_Volt_f32	18.3572006
k_BattUvLo_Volt_f32	0
k_CAVNTCEnableTimeout_mS_u16	13133
k_CAVNodeAbsentDiag_Cnt_str.Threshold	27441
k_CAVNodeAbsentDiag_Cnt_str.PStep	21650
k_CAVNodeAbsentDiag_Cnt_str.NStep	33756
k_CAVNodeAbsentTimeout_mS_u16	516
k_CAVNodeTimeout_mS_u16	57431
k_CMM388MsgTimeout_mS_u16	53739
k_CMM388NTCEnableTimeout_mS_u16	34311
k_CMMNTCEnableTimeout_mS_u16	50933
k_CMMNodeAbsentDiag_Cnt_str.Threshold	14287
k_CMMNodeAbsentDiag_Cnt_str.PStep	34224
k_CMMNodeAbsentDiag_Cnt_str.NStep	58348
k_CMMNodeAbsentTimeout_mS_u16	28394
k_CONSANGLECPKMax_HwDeg_f32	17.4787998
k_CONSANGLECPKMin_HwDeg_f32	-65.2932968
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	43691
k_CONSANGLECPKSigValidThresh_Cnt_u16	59342
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	61831
k_CPKVehicleSpeedValidThresh_Cnt_u16	4598
k_CityParkInputInvalidThresh_Cnt_u16	61123
k_CityParkInputValidThresh_Cnt_u16	41089
k_ComputerRazGCTSigValidThresh_Cnt_u16	41331
k_CptTemporelSigValidThresh_Cnt_u16	41938
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	55874
k_DMDFCTCPKSigValidThresh_Cnt_u16	16509
k_DMDFCTCPKValidCount_Cnt_u16	55223
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	7594
k_DMDRELAXECPKSigValidThresh_Cnt_u16	59644
k_DMDRelaxeConsistentThresh_Cnt_u16	41298
k_DateValidThresh_Cnt_u16	38539
k_DefaultVehSpd_Kph_f32	78.063797
k_DiagMuxOnAbsentTimeout_mS_u16	0
k_EMNodeTimeout_mS_u16	19576
k_ESPNTCEnableTimeout_mS_u16	47890
k_ESPNodeAbsentDiag_Cnt_str.Threshold	59441
k_ESPNodeAbsentDiag_Cnt_str.PStep	29914
k_ESPNodeAbsentDiag_Cnt_str.NStep	17628
k_ESPNodeAbsentTimeout_mS_u16	40370
k_EtatMTSigInvalidThresh_Cnt_u16	1692
k_EtatMTSigValidThresh_Cnt_u16	23247
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	26002
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	26377
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	49146
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	22970
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	54105
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	28335
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	51720
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	21742
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	56687
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	45221
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	26835
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	50174
k_ISDATDIRASentDiag_Cnt_str.Threshold	31074

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	34522
k_ISDATDIRASentDiag_Cnt_str.NStep	11395
k_ISDATDIRASentTimeout_mS_u16	17673
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	4819
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	8136
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	53694
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	26349
k_ISDYNAASChkSumValidThresh_Cnt_u16	1504
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	1764
k_ISDYNAASMsgCountValidThresh_Cnt_u16	22255
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	1489
k_ISDYNAASMsgLenValidThresh_Cnt_u16	53525
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	54172
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	59984
k_ISDYNABRChkSumValidThresh_Cnt_u16	57099
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	37615
k_ISDYNABRMsgCountValidThresh_Cnt_u16	3545
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46759
k_ISDYNABRMsgLenValidThresh_Cnt_u16	51917
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	63720
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	48467
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	13444
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	61376
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	19944
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	16786
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	59455
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	65326
k_ISDYNVOLChkSumValidThresh_Cnt_u16	4989
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	26538
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	51140
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	17244
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	37106
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	59729
k_IgnOnTimeout_mS_u16	37962
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	106.445099
k_PowerCutVehSpdLowThresh_Kph_f32	130.390396
k_PowerCutVehSpdLowTimeout_mS_u16	58860
k_VBattMaxAAS_Volt_f32	31.1061001
k_VBattMaxBSI_Volt_f32	14.8128996
k_VBattMaxCAV_Volt_f32	0.370400012
k_VBattMaxCMM388_Volt_f32	32
k_VBattMaxCMM_Volt_f32	9.13020039
k_VBattMaxESP_Volt_f32	30.948
k_VBattMinAAS_Volt_f32	31.2845993
k_VBattMinBSI_Volt_f32	30.948
k_VBattMinCAV_Volt_f32	21.7075996
k_VBattMinCMM388_Volt_f32	28.6900005
k_VBattMinCMM_Volt_f32	16.1970997
k_VBattMinESP_Volt_f32	9.13020039
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	61309
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	60923
k_VitesseVehicleBVRampValidThresh_Cnt_u16	27953
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	38340
k_VitesseVehicleBVSigValidThresh_Cnt_u16	14130
k_VitesseVehicleBVSpeedPassThresh_kph_f32	113.502701
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	6390
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	45304
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	411853312
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	210
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	38284
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3222871040
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	111
target_SrlComInput_Per1_Batt_Volt_f32.value	1
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	214782464
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	156
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.53801614
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1339720192
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1529455104
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1179173376
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	82
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2570576384
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3690398208
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	249
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2525372928
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1357201920
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	36
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	100
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	170
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	212
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	605086208
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	60
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	126
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	388334080
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3455361536
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	613663232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	72
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2254230016
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	4093
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.654631913
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	105949
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	97.8583984
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	34201

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3222871040	3222871040	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	255	255	✔
AASNodeAbsentTimer_mS_M_u32	1357201920	1357201920	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	8138	8138	✔
AngleVolantMsgTimer_mS_M_u32	3222871040	3222871040	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	595.264771	595.264771	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3222871040	3222871040	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3222871040	3222871040	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3222871040	3222871040	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3222871040	3222871040	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	5068	5068	✔
BSINodeAbsentTimer_mS_M_u32	2570576384	2570576384	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3222871040	3222871040	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	613663232	613663232	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3222871040	3222871040	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3222871040	3222871040	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2525372928	2525372928	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	61537	61537	✔
CONSANGLECPK_HwDeg_M_f32	-504.057007	-504.057007 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	61537	61537	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	436482560	436482560	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	47252	47252	✔
CityParkInputConsistentCount_Cnt_M_u16	41089	41089	✔
CityParkInputInvalidCount_Cnt_M_u16	6409	6409	✔
CityParkInputMsgTimer_mS_M_u32	3222871040	3222871040	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3222871040	3222871040	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3222871040	3222871040	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3222871040	3222871040	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3222871040	3222871040	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3222871040	3222871040	✔
ESPNTCEnableTimer_mS_M_u32	3222871040	3222871040	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3222871040	3222871040	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	5	5	✔
EffacDefaultDiagTimer_mS_M_u32[1]	155	155	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	556	556	✔
ElecIntTimer_mS_M_u32[1]	877877	877877	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3222871040	3222871040	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3222871040	3222871040	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3222871040	3222871040	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3222871040	3222871040	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3222871040	3222871040	✔
ISDATDIRASentFltAcc_Cnt_M_u16	47112	47112	✔
ISDATDIRASentTimer_mS_M_u32	3222871040	3222871040	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3222871040	3222871040	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3222871040	3222871040	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3222871040	3222871040	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3222871040	3222871040	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3222871040	3222871040	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3222871040	3222871040	✔
IgnOnTimer_mS_M_u32	2464186880	2464186880	✔
IgnTimeOff_Sec_M_u32	3094169899	3094169899	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	75	75	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1339720192	1339720192	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	90	90	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1529455104	1529455104	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	132	132	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1179173376	1179173376	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	82	82	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2570576384	2570576384	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3690398208	3690398208	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	249	249	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2525372928	2525372928	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1357201920	1357201920	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	125	125	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	605086208	605086208	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	133	133	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	388334080	388334080	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	223	223	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3455361536	3455361536	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	613663232	613663232	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2254230016	2254230016	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	579.36261	579.36261	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	409.606689	409.606689	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	44.8857994	44.8857994	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	595.264771	595.264771	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	61537	61537	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3094169899	3094169899	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-504.057007	-504.057007 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	78.063797	78.063797	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0108	0x0108	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.129 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2509712640
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	39971
AASNodeAbsentTimer_mS_M_u32	3422838016
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	47662
ANGLEVOLANTSigValidCount_Cnt_M_u16	38126
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	40332
AngleVolantMsgTimer_mS_M_u32	2509712640
AngleVolantValidCount_Cnt_M_u16	14733
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	285.72757
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2448235776
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2650905856
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2534100224
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3683060992
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	50969
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2734804224
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	14723
CAVNodeAbsentTimer_mS_M_u32	4294967295
CDD_SrlComVehSpd_Kph_G_f32	37.4258003
CMM388NTCEnableTimer_mS_M_u32	1630518528
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3006954752
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	65329
CMMNodeAbsentTimer_mS_M_u32	3154709760
CONSANGLECPKSigInvalidCount_Cnt_M_u16	25138
CONSANGLECPKSigValidCount_Cnt_M_u16	64259
CONSANGLECPK_Cnt_M_u16	43650
CONSANGLECPK_HwDeg_M_f32	-33.7103004
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43650
CPKVehicleSpeedMsgTimer_mS_M_u32	4242156800
CPKVehicleSpeedValidCount_Cnt_M_u16	40274
CityParkInputConsistentCount_Cnt_M_u16	59361
CityParkInputInvalidCount_Cnt_M_u16	9041
CityParkInputMsgTimer_mS_M_u32	1339720192
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	257449216
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	34935
ComputerRazGCTSigInvalidTimer_mS_M_u32	2931490048
ComputerRazGCTSigValidCount_Cnt_M_u16	28450

Name	Input Value
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	57597
DMDFCTCPKSigValidCount_Cnt_M_u16	2694
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	3160
DMDRELAXECPKSigValidCount_Cnt_M_u16	4760
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	47259
DateInvalidTimer_mS_M_u32	2650905856
DiagMuxOnAbsentTimer_mS_M_u32	2423385344
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3683060992
ESPNTCEnableTimer_mS_M_u32	1300323584
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	26750
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1111
EffacDefaultDiagTimer_mS_M_u32[1]	2222
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	2323
ElecIntTimer_mS_M_u32[1]	45464
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1712049408
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	869
EtatMTSigValidCount_Cnt_M_u16	38754
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	45660
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	63149
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	34948
ISDAT4V2BSI552MsgTimer_mS_M_u32	2522680576
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1901
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	15250
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	38754
ISDATBSI3F2MsgTimer_mS_M_u32	4165463296
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	10819
ISDATBSI412MsgLenValidCount_Cnt_M_u16	61399
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	869
ISDATBSI412MsgTimer_mS_M_u32	1802317056
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	45189
ISDATBSI432MsgLenValidCount_Cnt_M_u16	12498
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	15776
ISDATDIRASentFltAcc_Cnt_M_u16	8644
ISDATDIRASentTimer_mS_M_u32	4242156800
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	26328
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	14733
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	24936
ISDYN2CMMMsgTimer_mS_M_u32	142826752
ISDYNAASChkSumInvalidCount_Cnt_M_u16	51789
ISDYNAASChkSumValidCount_Cnt_M_u16	9646
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	10232
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	19522
ISDYNAASMsgLenValidCount_Cnt_M_u16	31547
ISDYNAASMsgTimeValidCount_Cnt_M_u16	51789
ISDYNAASMsgTimer_mS_M_u32	2413542656
ISDYNABRChkSumInvalidCount_Cnt_M_u16	15518
ISDYNABRChkSumValidCount_Cnt_M_u16	13702
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	8504
ISDYNABRMsgCountValidCount_Cnt_M_u16	26329
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	61469
ISDYNABRMsgLenValidCount_Cnt_M_u16	45870
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43650
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	731
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1347
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	38754
ISDYNCMM208MsgTimer_mS_M_u32	2892897536
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2775
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1453
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	14947
ISDYNCMM388MsgTimer_mS_M_u32	2654027008
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	41480

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNVOLChkSumValidCount_Cnt_M_u16	36697
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	38867
ISDYNVOLMsgCountValidCount_Cnt_M_u16	21980
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	9363
ISDYNVOLMsgLenValidCount_Cnt_M_u16	7364
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	65329
ISDYNVOLMsgTimer_mS_M_u32	3647405312
IgnOnTimer_mS_M_u32	663043328
IgnTimeOff_Sec_M_u32	2305928468
ManVehSpd_Kph_M_f32	611.494812
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	83
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	228
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3768970496
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	80
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3981856000
PrevISDATBSI412MsgDLCError_Cnt_M_u08	147
PrevISDATBSI412MsgRxTime_MSec_M_u32	1461288192
PrevISDATBSI432MsgDLCError_Cnt_M_u08	11
PrevISDATBSI432MsgRxTime_MSec_M_u32	1250254080
PrevISDATDIRAMsgTxTime_MSec_M_u32	3460136192
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	137
PrevISDYN2CMMMsgRxTime_MSec_M_u32	767986944
PrevISDYNAASMsgDLCError_Cnt_M_u08	40
PrevISDYNAASMsgRxTime_MSec_M_u32	3183279360
PrevISDYNABRMsgDLCError_Cnt_M_u08	40
PrevISDYNABRMsgRxTime_MSec_M_u32	1272790272
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	140
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2948463872
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	97
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1124359424
PrevISDYNVOLMsgDLCError_Cnt_M_u08	47
PrevISDYNVOLMsgRxTime_MSec_M_u32	2408742144
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	138620160
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	121.075699
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	28952
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	46225
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	52397
VitesseVehicleBVRampValidCount_Cnt_M_u16	1510
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	53571
VitesseVehicleBVSigValidCount_Cnt_M_u16	16835
VitesseVehicleBV_Kph_M_f32	197.056595
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	14947
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	6331
VitesseVehiculeRoues_Kph_M_f32	269.5336
k_AASNTCEnableTimeout_mS_u16	57093
k_AASNodeAbsentDiag_Cnt_str.Threshold	3072
k_AASNodeAbsentDiag_Cnt_str.PStep	32981
k_AASNodeAbsentDiag_Cnt_str.NStep	56744

Name	Input Value
k_AASNodeAbsentTimeout_mS_u16	164
k_AASNodeTimeout_mS_u16	43921
k_ABSNodeTimeout_mS_u16	24638
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	58332
k_ANGLEVOLANTSigValidThresh_Cnt_u16	1897
k_AngleVolantInvalidThresh_Cnt_u16	60668
k_AngleVolantValidThresh_Cnt_u16	9041
k_BSI552MsgTimeout_mS_u16	50190
k_BSINTCEnableTimeout_mS_u16	34013
k_BSINodeAbsentDiag_Cnt_str.Threshold	10
k_BSINodeAbsentDiag_Cnt_str.PStep	0
k_BSINodeAbsentDiag_Cnt_str.NStep	15418
k_BSINodeAbsentTimeout_mS_u16	7140
k_BSINodeTimeout_mS_u16	15776
k_BattOvHi_Volt_f32	2
k_BattOvLo_Volt_f32	10.8836002
k_BattUvHi_Volt_f32	11.2806997
k_BattUvLo_Volt_f32	0
k_CAVNTCEnableTimeout_mS_u16	27775
k_CAVNodeAbsentDiag_Cnt_str.Threshold	49185
k_CAVNodeAbsentDiag_Cnt_str.PStep	59864
k_CAVNodeAbsentDiag_Cnt_str.NStep	19218
k_CAVNodeAbsentTimeout_mS_u16	60761
k_CAVNodeTimeout_mS_u16	43230
k_CMM388MsgTimeout_mS_u16	54051
k_CMM388NTCEnableTimeout_mS_u16	9935
k_CMMNTCEnableTimeout_mS_u16	51141
k_CMMNodeAbsentDiag_Cnt_str.Threshold	34798
k_CMMNodeAbsentDiag_Cnt_str.PStep	24294
k_CMMNodeAbsentDiag_Cnt_str.NStep	63497
k_CMMNodeAbsentTimeout_mS_u16	60007
k_CONSANGLECPKMax_HwDeg_f32	157.7668
k_CONSANGLECPKMin_HwDeg_f32	-11.6873999
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	61795
k_CONSANGLECPKSigValidThresh_Cnt_u16	4027
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	47247
k_CPKVehicleSpeedValidThresh_Cnt_u16	31682
k_CityParkInputInvalidThresh_Cnt_u16	13340
k_CityParkInputValidThresh_Cnt_u16	59361
k_ComputerRazGCTSigValidThresh_Cnt_u16	45131
k_CptTemporelSigValidThresh_Cnt_u16	28400
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	10013
k_DMDFCTCPKSigValidThresh_Cnt_u16	10798
k_DMDFCTCPKValidCount_Cnt_u16	20417
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	24936
k_DMDRELAXECPKSigValidThresh_Cnt_u16	38193
k_DMDRelaxeConsistentThresh_Cnt_u16	17455
k_DateValidThresh_Cnt_u16	34948
k_DefaultVehSpd_Kph_f32	57.2102013
k_DiagMuxOnAbsentTimeout_mS_u16	0
k_EMNodeTimeout_mS_u16	10363
k_ESPNTCEnableTimeout_mS_u16	31279
k_ESPNodeAbsentDiag_Cnt_str.Threshold	38057
k_ESPNodeAbsentDiag_Cnt_str.PStep	8263
k_ESPNodeAbsentDiag_Cnt_str.NStep	19736
k_ESPNodeAbsentTimeout_mS_u16	32271
k_EtatMTSigInvalidThresh_Cnt_u16	37009
k_EtatMTSigValidThresh_Cnt_u16	43449
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	18542
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	27083
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	44406
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	25462
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	48219
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	35223
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	32782
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	50459
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	41433
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	31158
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	22251
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	37548
k_ISDATDIRASentDiag_Cnt_str.Threshold	16910
k_ISDATDIRASentDiag_Cnt_str.PStep	7039
k_ISDATDIRASentDiag_Cnt_str.NStep	21916

Name	Input Value
k_ISDATDIRASentTimeout_mS_u16	51530
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	14893
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	40332
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	58923
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	62366
k_ISDYNAASChkSumValidThresh_Cnt_u16	11398
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	22584
k_ISDYNAASMsgCountValidThresh_Cnt_u16	56793
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	42738
k_ISDYNAASMsgLenValidThresh_Cnt_u16	53733
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	33041
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	44787
k_ISDYNABRChkSumValidThresh_Cnt_u16	1668
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	65049
k_ISDYNABRMsgCountValidThresh_Cnt_u16	33561
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	63025
k_ISDYNABRMsgLenValidThresh_Cnt_u16	40830
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	48620
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	46956
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	52248
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	57828
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	61742
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	3054
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	38313
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	37914
k_ISDYNVOLChkSumValidThresh_Cnt_u16	56558
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	31975
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	30426
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	46353
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	29198
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	10290
k_IgnOnTimeout_mS_u16	17606
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	242.566101
k_PowerCutVehSpdLowThresh_Kph_f32	242.730194
k_PowerCutVehSpdLowTimeout_mS_u16	46561
k_VBattMaxAAS_Volt_f32	13.5966997
k_VBattMaxBSI_Volt_f32	2.98620009
k_VBattMaxCAV_Volt_f32	19.0177994
k_VBattMaxCMM388_Volt_f32	8.2098999
k_VBattMaxCMM_Volt_f32	1.79390001
k_VBattMaxESP_Volt_f32	6.30459976
k_VBattMinAAS_Volt_f32	7.61499977
k_VBattMinBSI_Volt_f32	6.30459976
k_VBattMinCAV_Volt_f32	1.12240005
k_VBattMinCMM388_Volt_f32	27.9349003
k_VBattMinCMM_Volt_f32	32
k_VBattMinESP_Volt_f32	1.79390001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	52271
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	5748
k_VitesseVehicleBVRampValidThresh_Cnt_u16	20179
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	1625
k_VitesseVehicleBVSigValidThresh_Cnt_u16	10190
k_VitesseVehicleBVSpeedPassThresh_kph_f32	457.871704
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	61571
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	32316
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2650905856
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	241
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	11650
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3670241024
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	97
target_SrlComInput_Per1_Batt_Volt_f32.value	1
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	822004992
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	252

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.12215846
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1486306560
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3676953856
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4266425600
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	704584960
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3326196992
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	87
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	991190272
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4034329856
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	102
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	103
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	151
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	229
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	165
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	762584320
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	114
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	185
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	220
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	10
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4004920576
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	1
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1858657536
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1332444416
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	119
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1649429760
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2135
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.595567286
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	189222
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	183.576096
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	63130

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3670241024	3670241024	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4034329856	4034329856	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	40334	40334	✔
AngleVolantMsgTimer_mS_M_u32	3670241024	3670241024	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	285.72757	285.72757	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3670241024	3670241024	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3670241024	3670241024	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3670241024	3670241024	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3670241024	3670241024	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	35551	35551	✔
BSINodeAbsentTimer_mS_M_u32	704584960	704584960	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3670241024	3670241024	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1332444416	1332444416	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3670241024	3670241024	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3670241024	3670241024	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	1832	1832	✔
CMMNodeAbsentTimer_mS_M_u32	991190272	991190272	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	43650	43650	✔
CONSANGLECPK_HwDeg_M_f32	-33.7103004	-33.7103004 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43650	43650	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4242156800	4242156800	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	40274	40274	✔
CityParkInputConsistentCount_Cnt_M_u16	59361	59361	✔
CityParkInputInvalidCount_Cnt_M_u16	9043	9043	✔
CityParkInputMsgTimer_mS_M_u32	3670241024	3670241024	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3670241024	3670241024	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3670241024	3670241024	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3670241024	3670241024	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3670241024	3670241024	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3670241024	3670241024	✔
ESPNTCEnableTimer_mS_M_u32	3670241024	3670241024	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3670241024	3670241024	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1111	1111	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2222	2222	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2323	2323	✔
ElecIntTimer_mS_M_u32[1]	45464	45464	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3670241024	3670241024	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3670241024	3670241024	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3670241024	3670241024	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3670241024	3670241024	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3670241024	3670241024	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3670241024	3670241024	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3670241024	3670241024	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3670241024	3670241024	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3670241024	3670241024	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3670241024	3670241024	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3670241024	3670241024	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3670241024	3670241024	✔
IgnOnTimer_mS_M_u32	663043328	663043328	✔
IgnTimeOff_Sec_M_u32	2305928468	2305928468	✔
Msg348Valid_Cnt_M_Igc	0	0	✔
Msg432Valid_Cnt_M_Igc	0	0	✔
Msg552Valid_Cnt_M_Igc	0	0	✔
NetOn_Cnt_M_Igc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1486306560	1486306560	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	164	164	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3676953856	3676953856	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI412MsgDLCError_Cnt_M_u08	106	106	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4266425600	4266425600	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	132	132	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	704584960	704584960	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3326196992	3326196992	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	87	87	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	991190272	991190272	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	223	223	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4034329856	4034329856	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	165	165	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	762584320	762584320	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	10	10	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4004920576	4004920576	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	1	1	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1858657536	1858657536	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1332444416	1332444416	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1649429760	1649429760	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	121.075699	121.075699	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	197.056595	197.056595	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	269.5336	269.5336	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	285.72757	285.72757	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	43650	43650	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2305928468	2305928468	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-33.7103004	-33.7103004 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	57.2102013	57.2102013	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.130 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2748136448
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	25127
AASNodeAbsentTimer_mS_M_u32	1900391424
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	21000
ANGLEVOLANTSigValidCount_Cnt_M_u16	57478
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	16876
AngleVolantMsgTimer_mS_M_u32	2748136448
AngleVolantValidCount_Cnt_M_u16	47210
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	145.193726
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2995481600
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2152590336
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	401660928
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3917323264
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	38727
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3993852928
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	45703
CAVNodeAbsentTimer_mS_M_u32	925121280
CDD_SrlComVehSpd_Kph_G_f32	174.418396
CMM388NTCEnableTimer_mS_M_u32	390302720
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3156429824
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	50493
CMMNodeAbsentTimer_mS_M_u32	3489111040
CONSANGLECPKSigInvalidCount_Cnt_M_u16	23801
CONSANGLECPKSigValidCount_Cnt_M_u16	61767
CONSANGLECPK_Cnt_M_u16	40650
CONSANGLECPK_HwDeg_M_f32	169.127502
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	40650
CPKVehicleSpeedMsgTimer_mS_M_u32	973356032
CPKVehicleSpeedValidCount_Cnt_M_u16	33827
CityParkInputConsistentCount_Cnt_M_u16	64878
CityParkInputInvalidCount_Cnt_M_u16	23582
CityParkInputMsgTimer_mS_M_u32	1486306560
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4148800512

Name	Input Value
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	60715
ComputerRazGCTSigInvalidTimer_mS_M_u32	1805765632
ComputerRazGCTSigValidCount_Cnt_M_u16	43947
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	54042
DMDFCTCPKSigValidCount_Cnt_M_u16	38208
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	33674
DMDRELAXECPKSigValidCount_Cnt_M_u16	36744
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	15806
DateInvalidTimer_mS_M_u32	2152590336
DiagMuxOnAbsentTimer_mS_M_u32	2386361344
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3917323264
ESPNTCEnableTimer_mS_M_u32	550415360
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	55319
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	65535
EffacDefaultDiagTimer_mS_M_u32[1]	95535
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	5656
ElecIntTimer_mS_M_u32[1]	78788
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1290755072
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	55712
EtatMTSigValidCount_Cnt_M_u16	11370
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	38011
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	9801
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	37702
ISDAT4V2BSI552MsgTimer_mS_M_u32	2432408576
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	17673
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	22363
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	11370
ISDATBSI3F2MsgTimer_mS_M_u32	784006144
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	49545
ISDATBSI412MsgLenValidCount_Cnt_M_u16	57227
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	55712
ISDATBSI412MsgTimer_mS_M_u32	4199234560
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	321
ISDATBSI432MsgLenValidCount_Cnt_M_u16	53019
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	23088
ISDATDIRASentFltAcc_Cnt_M_u16	15812
ISDATDIRASentTimer_mS_M_u32	973356032
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	16840
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	47210
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	48601
ISDYN2CMMMsgTimer_mS_M_u32	2009639936
ISDYNAASChkSumInvalidCount_Cnt_M_u16	65449
ISDYNAASChkSumValidCount_Cnt_M_u16	35911
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	22825
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	13898
ISDYNAASMsgLenValidCount_Cnt_M_u16	43040
ISDYNAASMsgTimeValidCount_Cnt_M_u16	65449
ISDYNAASMsgTimer_mS_M_u32	994020352
ISDYNABRChkSumInvalidCount_Cnt_M_u16	57912
ISDYNABRChkSumValidCount_Cnt_M_u16	46654
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	26344
ISDYNABRMsgCountValidCount_Cnt_M_u16	13510
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	7992
ISDYNABRMsgLenValidCount_Cnt_M_u16	13510
ISDYNABRMsgTimeValidCount_Cnt_M_u16	40650
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	732
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1349
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	11370
ISDYNCMM208MsgTimer_mS_M_u32	2802347008
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2779
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1455

Name	Input Value
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	36328
ISDYNCMM388MsgTimer_mS_M_u32	1178536960
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	30071
ISDYNVOLChkSumValidCount_Cnt_M_u16	3141
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	34456
ISDYNVOLMsgCountValidCount_Cnt_M_u16	35646
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	14296
ISDYNVOLMsgLenValidCount_Cnt_M_u16	11782
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	50493
ISDYNVOLMsgTimer_mS_M_u32	2610809856
IgnOnTimer_mS_M_u32	4198697984
IgnTimeOff_Sec_M_u32	3123770001
ManVehSpd_Kph_M_f32	12.9417
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	85
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	67
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1839266816
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	187
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	17816576
PrevISDATBSI412MsgDLCError_Cnt_M_u08	234
PrevISDATBSI412MsgRxTime_MSec_M_u32	210127872
PrevISDATBSI432MsgDLCError_Cnt_M_u08	186
PrevISDATBSI432MsgRxTime_MSec_M_u32	969059328
PrevISDATDIRAMsgTxTime_MSec_M_u32	924470272
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	224
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1354701824
PrevISDYNAASMsgDLCError_Cnt_M_u08	122
PrevISDYNAASMsgRxTime_MSec_M_u32	3332099072
PrevISDYNABRMsgDLCError_Cnt_M_u08	127
PrevISDYNABRMsgRxTime_MSec_M_u32	3980069888
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	116
PrevISDYNCMM208MsgRxTime_MSec_M_u32	882428928
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	221
PrevISDYNCMM388MsgRxTime_MSec_M_u32	205892608
PrevISDYNVOLMsgDLCError_Cnt_M_u08	203
PrevISDYNVOLMsgRxTime_MSec_M_u32	2266713088
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4224269312
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	10.6388998
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	40904
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	54302
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	8457
VitesseVehicleBVRampValidCount_Cnt_M_u16	29727
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	41161
VitesseVehicleBVSigValidCount_Cnt_M_u16	28167
VitesseVehicleBV_Kph_M_f32	426.216888
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	36328
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	29086
VitesseVehiculeRoues_Kph_M_f32	648.482483
k_AASNTCEnableTimeout_mS_u16	52545

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.Threshold	65098
k_AASNodeAbsentDiag_Cnt_str.PStep	25859
k_AASNodeAbsentDiag_Cnt_str.NStep	512
k_AASNodeAbsentTimeout_mS_u16	32549
k_AASNodeTimeout_mS_u16	61214
k_ABSNodeTimeout_mS_u16	39255
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	33596
k_ANGLEVOLANTSigValidThresh_Cnt_u16	26454
k_AngleVolantInvalidThresh_Cnt_u16	49821
k_AngleVolantValidThresh_Cnt_u16	23582
k_BSI552MsgTimeout_mS_u16	31653
k_BSINTCEnableTimeout_mS_u16	58425
k_BSINodeAbsentDiag_Cnt_str.Threshold	123
k_BSINodeAbsentDiag_Cnt_str.PStep	65535
k_BSINodeAbsentDiag_Cnt_str.NStep	15441
k_BSINodeAbsentTimeout_mS_u16	9956
k_BSINodeTimeout_mS_u16	23088
k_BattOvHi_Volt_f32	2
k_BattOvLo_Volt_f32	10.3322001
k_BattUvHi_Volt_f32	29.2947998
k_BattUvLo_Volt_f32	0
k_CAVNTCEnableTimeout_mS_u16	47252
k_CAVNodeAbsentDiag_Cnt_str.Threshold	3005
k_CAVNodeAbsentDiag_Cnt_str.PStep	15634
k_CAVNodeAbsentDiag_Cnt_str.NStep	44059
k_CAVNodeAbsentTimeout_mS_u16	28421
k_CAVNodeTimeout_mS_u16	14581
k_CMM388MsgTimeout_mS_u16	48423
k_CMM388NTCEnableTimeout_mS_u16	29219
k_CMMNTCEnableTimeout_mS_u16	25601
k_CMMNodeAbsentDiag_Cnt_str.Threshold	52061
k_CMMNodeAbsentDiag_Cnt_str.PStep	25776
k_CMMNodeAbsentDiag_Cnt_str.NStep	56765
k_CMMNodeAbsentTimeout_mS_u16	44186
k_CONSANGLECPKMax_HwDeg_f32	510.80011
k_CONSANGLECPKMin_HwDeg_f32	-54.5256996
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	26856
k_CONSANGLECPKSigValidThresh_Cnt_u16	35998
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	16420
k_CPKVehicleSpeedValidThresh_Cnt_u16	35084
k_CityParkInputInvalidThresh_Cnt_u16	29630
k_CityParkInputValidThresh_Cnt_u16	64878
k_ComputerRazGCTSigValidThresh_Cnt_u16	17007
k_CptTemporelSigValidThresh_Cnt_u16	46401
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	31288
k_DMDFCTCPKSigValidThresh_Cnt_u16	53190
k_DMDFCTCPKValidCount_Cnt_u16	40271
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	48601
k_DMDRELAXECPKSigValidThresh_Cnt_u16	24895
k_DMDRelaxeConsistentThresh_Cnt_u16	52293
k_DateValidThresh_Cnt_u16	37702
k_DefaultVehSpd_Kph_f32	251.442795
k_DiagMuxOnAbsentTimeout_mS_u16	0
k_EMNodeTimeout_mS_u16	28190
k_ESPNTCEnableTimeout_mS_u16	41091
k_ESPNodeAbsentDiag_Cnt_str.Threshold	52111
k_ESPNodeAbsentDiag_Cnt_str.PStep	62444
k_ESPNodeAbsentDiag_Cnt_str.NStep	63217
k_ESPNodeAbsentTimeout_mS_u16	37282
k_EtatMTSigInvalidThresh_Cnt_u16	29279
k_EtatMTSigValidThresh_Cnt_u16	58789
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	52359
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	63281
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	16559
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	38126
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	14592
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	62349
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	63142
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	30272
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	32069
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	302
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	22608
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	48461

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.Threshold	32887
k_ISDATDIRASentDiag_Cnt_str.PStep	20123
k_ISDATDIRASentDiag_Cnt_str.NStep	32507
k_ISDATDIRASentTimeout_mS_u16	60468
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	2762
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	16876
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	19599
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	48440
k_ISDYNAASChkSumValidThresh_Cnt_u16	53566
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	49640
k_ISDYNAASMsgCountValidThresh_Cnt_u16	53190
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	62268
k_ISDYNAASMsgLenValidThresh_Cnt_u16	52258
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39518
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	47798
k_ISDYNABRChkSumValidThresh_Cnt_u16	4804
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	62023
k_ISDYNABRMsgCountValidThresh_Cnt_u16	33285
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	57405
k_ISDYNABRMsgLenValidThresh_Cnt_u16	13079
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	56716
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	7372
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	28682
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	22565
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	44296
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	31622
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	25878
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	40964
k_ISDYNVOLChkSumValidThresh_Cnt_u16	13382
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	32476
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	16962
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	29852
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	19558
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	60476
k_IgnOnTimeout_mS_u16	15872
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	163.874893
k_PowerCutVehSpdLowThresh_Kph_f32	203.382797
k_PowerCutVehSpdLowTimeout_mS_u16	47277
k_VBattMaxAAS_Volt_f32	3.69190001
k_VBattMaxBSI_Volt_f32	15.9941998
k_VBattMaxCAV_Volt_f32	16.7870007
k_VBattMaxCMM388_Volt_f32	25.5564995
k_VBattMaxCMM_Volt_f32	8.29179955
k_VBattMaxESP_Volt_f32	15.8682003
k_VBattMinAAS_Volt_f32	4.97590017
k_VBattMinBSI_Volt_f32	15.8682003
k_VBattMinCAV_Volt_f32	31.1247997
k_VBattMinCMM388_Volt_f32	5.4078002
k_VBattMinCMM_Volt_f32	22.0716991
k_VBattMinESP_Volt_f32	8.29179955
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	56516
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	11446
k_VitesseVehicleBVRampValidThresh_Cnt_u16	24984
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	42821
k_VitesseVehicleBVSigValidThresh_Cnt_u16	12711
k_VitesseVehicleBVSpeedPassThresh_kph_f32	213.582504
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	36231
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	58141
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2152590336
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	3
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	48714
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3486545408
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	221
target_SrlComInput_Per1_Batt_Volt_f32.value	1
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2014731264
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	167
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.866407871
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	789384192
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	13
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3117755392
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2733460480
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	17
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2991942656
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2953677824
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	62
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1679141888
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2523778048
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	135
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	167
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	218
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	220
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	230
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	248
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	193
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3153488896
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	174
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	186
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	245
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	36
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2830109696
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	50
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	989342720
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	122
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3952102400
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	11
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	28
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	30
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	68
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	172
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	187
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	169991168
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2918
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.546724796
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	787576
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	83.094902
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	38722

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	24615	24615	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNodeAbsentTimer_mS_M_u32	2523778048	2523778048	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3486545408	3486545408	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	145.193726	145.193726	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	23286	23286	✔
BSINodeAbsentTimer_mS_M_u32	2991942656	2991942656	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	1644	1644	✔
CAVNodeAbsentTimer_mS_M_u32	3952102400	3952102400	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1679141888	1679141888	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	40650	40650	✔
CONSANGLECPK_HwDeg_M_f32	169.127502	169.127502 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3486545408	3486545408	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3486545408	3486545408	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3486545408	3486545408	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3486545408	3486545408	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3486545408	3486545408	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3486545408	3486545408	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3486545408	3486545408	✔
ESPNTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3486545408	3486545408	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	65535	65535	✔
EffacDefaultDiagTimer_mS_M_u32[1]	95535	95535	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	5656	5656	✔
ElecIntTimer_mS_M_u32[1]	78788	78788	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnAbsentTimer_mS_M_u32	3486545408	3486545408	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3486545408	3486545408	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3486545408	3486545408	✔
IgnOnTimer_mS_M_u32	4198697984	4198697984	✔
IgnTimeOff_Sec_M_u32	3123770001	3123770001	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	166	166	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	789384192	789384192	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	13	13	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3117755392	3117755392	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	238	238	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2733460480	2733460480	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	17	17	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2991942656	2991942656	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2953677824	2953677824	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	62	62	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1679141888	1679141888	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	216	216	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2523778048	2523778048	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	193	193	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3153488896	3153488896	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	36	36	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2830109696	2830109696	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	50	50	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	989342720	989342720	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	122	122	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3952102400	3952102400	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	169991168	169991168	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	10.6388998	10.6388998	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	426.216888	426.216888	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	648.482483	648.482483	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	145.193726	145.193726	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	40650	40650	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3123770001	3123770001	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	169.127502	169.127502 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	251.442795	251.442795	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.131 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2821132032
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	63255
AASNodeAbsentTimer_mS_M_u32	3984441088
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	18806
ANGLEVOLANTSigValidCount_Cnt_M_u16	16828
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	43976
AngleVolantMsgTimer_mS_M_u32	2821132032
AngleVolantValidCount_Cnt_M_u16	26830
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	434.756836
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1890352896
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	828702464
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3795595008
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2425745152
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	13753
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1910943488
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	0
CAVNodeAbsentTimer_mS_M_u32	1333190400
CDD_SrlComVehSpd_Kph_G_f32	424.868103
CMM388NTCEnableTimer_mS_M_u32	3406044928
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	191160064
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	10518
CMMNodeAbsentTimer_mS_M_u32	1160244992
CONSANGLECPKSigInvalidCount_Cnt_M_u16	8096
CONSANGLECPKSigValidCount_Cnt_M_u16	18038
CONSANGLECPK_Cnt_M_u16	2541
CONSANGLECPK_HwDeg_M_f32	475.167297
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2541
CPKVehicleSpeedMsgTimer_mS_M_u32	2172784384
CPKVehicleSpeedValidCount_Cnt_M_u16	16524
CityParkInputConsistentCount_Cnt_M_u16	43458
CityParkInputInvalidCount_Cnt_M_u16	23220
CityParkInputMsgTimer_mS_M_u32	789384192
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1802616576
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	26123
ComputerRazGCTSigInvalidTimer_mS_M_u32	384392960
ComputerRazGCTSigValidCount_Cnt_M_u16	54027
CountEtatMT_Cnt_M_u08	0

Name	Input Value
DMDFCTCPKSigInvalidCount_Cnt_M_u16	58816
DMDFCTCPKSigValidCount_Cnt_M_u16	58126
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	15600
DMDRELAXECPKSigValidCount_Cnt_M_u16	48310
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	53585
DateInvalidTimer_mS_M_u32	828702464
DiagMuxOnAbsentTimer_mS_M_u32	1473761024
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2425745152
ESPNTCEnableTimer_mS_M_u32	1122156288
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	1096
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	579
EffacDefaultDiagTimer_mS_M_u32[1]	989
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	5
ElecIntTimer_mS_M_u32[1]	87787
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1564520192
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	35052
EtatMTSigValidCount_Cnt_M_u16	25678
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	282
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	12144
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	33020
ISDAT4V2BSI552MsgTimer_mS_M_u32	303820544
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	57395
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	40189
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	25678
ISDATBSI3F2MsgTimer_mS_M_u32	3999125248
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	48050
ISDATBSI412MsgLenValidCount_Cnt_M_u16	5484
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	35052
ISDATBSI412MsgTimer_mS_M_u32	481103616
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	34058
ISDATBSI432MsgLenValidCount_Cnt_M_u16	12092
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	31101
ISDATDIRASentFltAcc_Cnt_M_u16	7873
ISDATDIRASentTimer_mS_M_u32	2172784384
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	39155
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	26830
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	57731
ISDYN2CMMMsgTimer_mS_M_u32	2784280320
ISDYNAASChkSumInvalidCount_Cnt_M_u16	42641
ISDYNAASChkSumValidCount_Cnt_M_u16	9335
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	17041
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	52527
ISDYNAASMsgLenValidCount_Cnt_M_u16	31597
ISDYNAASMsgTimeValidCount_Cnt_M_u16	42641
ISDYNAASMsgTimer_mS_M_u32	1326456576
ISDYNABRChkSumInvalidCount_Cnt_M_u16	21092
ISDYNABRChkSumValidCount_Cnt_M_u16	39443
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	11476
ISDYNABRMsgCountValidCount_Cnt_M_u16	59130
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	38115
ISDYNABRMsgLenValidCount_Cnt_M_u16	14329
ISDYNABRMsgTimeValidCount_Cnt_M_u16	2541
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	733
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1351
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	25678
ISDYNCMM208MsgTimer_mS_M_u32	3342171904
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2783
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1457
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	24660
ISDYNCMM388MsgTimer_mS_M_u32	2349965056
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	20006
ISDYNVOLChkSumValidCount_Cnt_M_u16	28028

Name	Input Value
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	17222
ISDYNVOLMsgCountValidCount_Cnt_M_u16	30996
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	10501
ISDYNVOLMsgLenValidCount_Cnt_M_u16	43579
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	10518
ISDYNVOLMsgTimer_mS_M_u32	1995792128
IgnOnTimer_mS_M_u32	2147852032
IgnTimeOff_Sec_M_u32	1130402685
ManVehSpd_Kph_M_f32	165.147202
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	87
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	35
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1235996416
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	135
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1658793728
PrevISDATBSI412MsgDLCError_Cnt_M_u08	21
PrevISDATBSI412MsgRxTime_MSec_M_u32	1715199744
PrevISDATBSI432MsgDLCError_Cnt_M_u08	255
PrevISDATBSI432MsgRxTime_MSec_M_u32	3355885312
PrevISDATDIRAMsgTxTime_MSec_M_u32	914349824
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	166
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1087467264
PrevISDYNAASMsgDLCError_Cnt_M_u08	119
PrevISDYNAASMsgRxTime_MSec_M_u32	1845190400
PrevISDYNABRMsgDLCError_Cnt_M_u08	89
PrevISDYNABRMsgRxTime_MSec_M_u32	2266865408
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	24
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1476681472
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	33
PrevISDYNCMM388MsgRxTime_MSec_M_u32	478002944
PrevISDYNVOLMsgDLCError_Cnt_M_u08	84
PrevISDYNVOLMsgRxTime_MSec_M_u32	2323439360
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2419265280
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	654.696289
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	2229
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	28531
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	51442
VitesseVehicleBVRampValidCount_Cnt_M_u16	54128
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	41267
VitesseVehicleBVSigValidCount_Cnt_M_u16	56633
VitesseVehicleBV_Kph_M_f32	102.759598
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	24660
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	14578
VitesseVehiculeRoues_Kph_M_f32	85.8932037
k_AASNTCEnableTimeout_mS_u16	6792
k_AASNodeAbsentDiag_Cnt_str.Threshold	16264
k_AASNodeAbsentDiag_Cnt_str.PStep	39860
k_AASNodeAbsentDiag_Cnt_str.NStep	35412
k_AASNodeAbsentTimeout_mS_u16	49309

Name	Input Value
k_AASNodeTimeout_mS_u16	7795
k_ABSNodeTimeout_mS_u16	50953
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	43801
k_ANGLEVOLANTSigValidThresh_Cnt_u16	4747
k_AngleVolantInvalidThresh_Cnt_u16	56502
k_AngleVolantValidThresh_Cnt_u16	23220
k_BSI552MsgTimeout_mS_u16	63197
k_BSINTCEnableTimeout_mS_u16	48162
k_BSINodeAbsentDiag_Cnt_str.Threshold	236
k_BSINodeAbsentDiag_Cnt_str.PStep	1216
k_BSINodeAbsentDiag_Cnt_str.NStep	15464
k_BSINodeAbsentTimeout_mS_u16	56544
k_BSINodeTimeout_mS_u16	31101
k_BattOvHi_Volt_f32	20.2040005
k_BattOvLo_Volt_f32	27.0918999
k_BattUvHi_Volt_f32	7.24259996
k_BattUvLo_Volt_f32	13.9603004
k_CAVNTCEnableTimeout_mS_u16	40274
k_CAVNodeAbsentDiag_Cnt_str.Threshold	63910
k_CAVNodeAbsentDiag_Cnt_str.PStep	14911
k_CAVNodeAbsentDiag_Cnt_str.NStep	5371
k_CAVNodeAbsentTimeout_mS_u16	52990
k_CAVNodeTimeout_mS_u16	31660
k_CMM388MsgTimeout_mS_u16	58903
k_CMM388NTCEnableTimeout_mS_u16	46883
k_CMMNTCEnableTimeout_mS_u16	25419
k_CMMNodeAbsentDiag_Cnt_str.Threshold	38317
k_CMMNodeAbsentDiag_Cnt_str.PStep	20237
k_CMMNodeAbsentDiag_Cnt_str.NStep	63103
k_CMMNodeAbsentTimeout_mS_u16	30718
k_CONSANGLECPKMax_HwDeg_f32	9.94550037
k_CONSANGLECPKMin_HwDeg_f32	-524.011475
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	53076
k_CONSANGLECPKSigValidThresh_Cnt_u16	59378
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	50017
k_CPKVehicleSpeedValidThresh_Cnt_u16	12585
k_CityParkInputInvalidThresh_Cnt_u16	13778
k_CityParkInputValidThresh_Cnt_u16	43458
k_ComputerRazGCTSigValidThresh_Cnt_u16	1
k_CptTemporelSigValidThresh_Cnt_u16	39755
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	33763
k_DMDFCTCPKSigValidThresh_Cnt_u16	26361
k_DMDFCTCPKValidCount_Cnt_u16	17313
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	57731
k_DMDRELAXECPKSigValidThresh_Cnt_u16	15121
k_DMDRelaxeConsistentThresh_Cnt_u16	37375
k_DateValidThresh_Cnt_u16	33020
k_DefaultVehSpd_Kph_f32	217.729202
k_DiagMuxOnAbsentTimeout_mS_u16	41995
k_EMNodeTimeout_mS_u16	49201
k_ESPNTCEnableTimeout_mS_u16	45700
k_ESPNodeAbsentDiag_Cnt_str.Threshold	41463
k_ESPNodeAbsentDiag_Cnt_str.PStep	42809
k_ESPNodeAbsentDiag_Cnt_str.NStep	57794
k_ESPNodeAbsentTimeout_mS_u16	59622
k_EtatMTSigInvalidThresh_Cnt_u16	65007
k_EtatMTSigValidThresh_Cnt_u16	26590
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	27192
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	15867
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	9215
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	50308
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	52238
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	13734
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	30939
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	3533
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	8446
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	29377
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	41244
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	10597
k_ISDATDIRASentDiag_Cnt_str.Threshold	44024
k_ISDATDIRASentDiag_Cnt_str.PStep	4643
k_ISDATDIRASentDiag_Cnt_str.NStep	50395
k_ISDATDIRASentTimeout_mS_u16	9328

Name	Input Value
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	29934
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	43976
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	56928
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	49508
k_ISDYNAASChkSumValidThresh_Cnt_u16	18707
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	7124
k_ISDYNAASMsgCountValidThresh_Cnt_u16	5626
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	12120
k_ISDYNAASMsgLenValidThresh_Cnt_u16	38759
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39283
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	14953
k_ISDYNABRChkSumValidThresh_Cnt_u16	5631
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	9401
k_ISDYNABRMsgCountValidThresh_Cnt_u16	6463
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	55318
k_ISDYNABRMsgLenValidThresh_Cnt_u16	62280
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	58026
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	41385
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	62511
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	48990
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	14454
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	28860
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	8140
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	52289
k_ISDYNVOLChkSumValidThresh_Cnt_u16	49979
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	25593
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	1543
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	43000
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	62554
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	52762
k_IgnOnTimeout_mS_u16	57933
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	98.9328003
k_PowerCutVehSpdLowThresh_Kph_f32	116.409401
k_PowerCutVehSpdLowTimeout_mS_u16	2116
k_VBattMaxAAS_Volt_f32	12.3927002
k_VBattMaxBSI_Volt_f32	1.07369995
k_VBattMaxCAV_Volt_f32	17.0321007
k_VBattMaxCMM388_Volt_f32	28.6865005
k_VBattMaxCMM_Volt_f32	25.0186005
k_VBattMaxESP_Volt_f32	4.96430016
k_VBattMinAAS_Volt_f32	25.5240993
k_VBattMinBSI_Volt_f32	4.96430016
k_VBattMinCAV_Volt_f32	26.0646
k_VBattMinCMM388_Volt_f32	5.05350018
k_VBattMinCMM_Volt_f32	25.4125004
k_VBattMinESP_Volt_f32	25.0186005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	26368
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	60138
k_VitesseVehicleBVRampValidThresh_Cnt_u16	45638
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	40060
k_VitesseVehicleBVSigValidThresh_Cnt_u16	12567
k_VitesseVehicleBVSpeedPassThresh_kph_f32	343.910309
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	64376
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	65142
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	828702464
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	47
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	45551
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1367695616
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	33
target_SrlComInput_Per1_Batt_Volt_f32.value	24.5450993
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	936095488
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	244
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.919998407
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	182
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2309463808
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	171
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2983149312
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4278640384
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	176
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	424574720
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2829459200
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	56
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1426964224
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3330629376
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	114
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	115
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	140
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	188
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	226
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	98
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3228270336
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	71
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	122
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	236
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	238
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1757323008
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2053521152
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	22
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1897783040
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	13
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	84
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	108
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	157
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	228
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	262745856
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	249
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.693050802
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	504511
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	90.5229034
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	35399

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	16264	16264	✔
AASNodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1367695616	1367695616	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	434.756836	434.756836	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
CDD_SrlComVehSpd_Kph_G_f32	165.147202	165.147202	✔
CMM388NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	38317	38317	✔
CMMNodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	2541	2541	✔
CONSANGLECPK_HwDeg_M_f32	475.167297	475.167297 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1367695616	1367695616	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1367695616	1367695616	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1367695616	1367695616	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1367695616	1367695616	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1367695616	1367695616	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1367695616	1367695616	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1367695616	1367695616	✔
ESPNTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	41463	41463	✔
ESPNodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	579	579	✔
EffacDefaultDiagTimer_mS_M_u32[1]	989	989	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	5	5	✔
ElecIntTimer_mS_M_u32[1]	87787	87787	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1367695616	1367695616	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	33020	33020	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	25678	25678	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	35052	35052	✔
ISDATBSI412MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	31101	31101	✔
ISDATBSI432MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1367695616	1367695616	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	57731	57731	✔
ISDYN2CMMMsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	42641	42641	✔
ISDYNAASMsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	2541	2541	✔
ISDYNABRMsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	25678	25678	✔
ISDYNCMM208MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	24660	24660	✔
ISDYNCMM388MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	10518	10518	✔
ISDYNVOLMsgTimer_mS_M_u32	1367695616	1367695616	✔
IgnOnTimer_mS_M_u32	2147852032	2147852032	✔
IgnTimeOff_Sec_M_u32	1130402685	1130402685	✔
Msg348Valid_Cnt_M_Igc	1	1	✔
Msg432Valid_Cnt_M_Igc	1	1	✔
Msg552Valid_Cnt_M_Igc	0	0	✔
NetOn_Cnt_M_Igc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	182	182	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2309463808	2309463808	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	171	171	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2983149312	2983149312	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	113	113	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI412MsgRxTime_MSec_M_u32	4278640384	4278640384	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	176	176	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	424574720	424574720	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	914349824	914349824	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	56	56	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1426964224	1426964224	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	210	210	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3330629376	3330629376	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	98	98	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3228270336	3228270336	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	137	137	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1757323008	1757323008	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	135	135	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2053521152	2053521152	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	22	22	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1897783040	1897783040	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	262745856	262745856	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	654.696289	654.696289	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	102.759598	102.759598	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	85.8932037	85.8932037	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	434.756836	434.756836	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	2541	2541	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1130402685	1130402685	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	475.167297	475.167297 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.132 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4263876096
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	29524
AASNodeAbsentTimer_mS_M_u32	618759680
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	5688
ANGLEVOLANTSigValidCount_Cnt_M_u16	16934
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	22849
AngleVolantMsgTimer_mS_M_u32	4263876096
AngleVolantValidCount_Cnt_M_u16	49328
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	128.421692
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3327477248
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	103532032
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2355508736
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	408483328
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	7535
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2808526336
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	65535
CAVNodeAbsentTimer_mS_M_u32	3413517824
CDD_SrlComVehSpd_Kph_G_f32	273.575012
CMM388NTCEnableTimer_mS_M_u32	500065792
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3484165632
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	52120
CMMNodeAbsentTimer_mS_M_u32	3265459712
CONSANGLECPKSigInvalidCount_Cnt_M_u16	44728
CONSANGLECPKSigValidCount_Cnt_M_u16	36597
CONSANGLECPK_Cnt_M_u16	57488
CONSANGLECPK_HwDeg_M_f32	-162.174103
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	57488
CPKVehicleSpeedMsgTimer_mS_M_u32	2652149248
CPKVehicleSpeedValidCount_Cnt_M_u16	10429
CityParkInputConsistentCount_Cnt_M_u16	52692
CityParkInputInvalidCount_Cnt_M_u16	21501
CityParkInputMsgTimer_mS_M_u32	2309463808
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2063959552
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	63096

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1595844096
ComputerRazGCTSigValidCount_Cnt_M_u16	46585
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	58073
DMDFCTCPKSigValidCount_Cnt_M_u16	8110
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	41930
DMDRELAXECPKSigValidCount_Cnt_M_u16	14648
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	40357
DateInvalidTimer_mS_M_u32	103532032
DiagMuxOnAbsentTimer_mS_M_u32	2719176192
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	408483328
ESPNTCEnableTimer_mS_M_u32	4172449280
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	65217
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1000
EffacDefaultDiagTimer_mS_M_u32[1]	2000
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	2324
ElecIntTimer_mS_M_u32[1]	45464
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3445143040
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	54549
EtatMTSigValidCount_Cnt_M_u16	51119
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	29258
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	15367
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	32228
ISDAT4V2BSI552MsgTimer_mS_M_u32	734459392
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	705
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	61730
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	51119
ISDATBSI3F2MsgTimer_mS_M_u32	1988187648
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	32067
ISDATBSI412MsgLenValidCount_Cnt_M_u16	21716
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	54549
ISDATBSI412MsgTimer_mS_M_u32	949196288
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	34748
ISDATBSI432MsgLenValidCount_Cnt_M_u16	19941
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	44193
ISDATDIRASentFltAcc_Cnt_M_u16	52437
ISDATDIRASentTimer_mS_M_u32	2652149248
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	52094
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	49328
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	48016
ISDYN2CMMMsgTimer_mS_M_u32	2541520384
ISDYNAASChkSumInvalidCount_Cnt_M_u16	52454
ISDYNAASChkSumValidCount_Cnt_M_u16	59379
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	65383
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	63883
ISDYNAASMsgLenValidCount_Cnt_M_u16	58257
ISDYNAASMsgTimeValidCount_Cnt_M_u16	52454
ISDYNAASMsgTimer_mS_M_u32	3249169920
ISDYNABRChkSumInvalidCount_Cnt_M_u16	52971
ISDYNABRChkSumValidCount_Cnt_M_u16	44193
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	1565
ISDYNABRMsgCountValidCount_Cnt_M_u16	27754
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	6895
ISDYNABRMsgLenValidCount_Cnt_M_u16	34412
ISDYNABRMsgTimeValidCount_Cnt_M_u16	57488
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	734
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1353
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	51119
ISDYNCMM208MsgTimer_mS_M_u32	649741824
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2787
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1459
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	29214

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	4037404160
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	47910
ISDYNVOLChkSumValidCount_Cnt_M_u16	45539
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	25159
ISDYNVOLMsgCountValidCount_Cnt_M_u16	62876
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	50314
ISDYNVOLMsgLenValidCount_Cnt_M_u16	5544
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	52120
ISDYNVOLMsgTimer_mS_M_u32	1861920256
IgnOnTimer_mS_M_u32	3838436864
IgnTimeOff_Sec_M_u32	2345825784
ManVehSpd_Kph_M_f32	3.49110007
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	89
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	125
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	479680000
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	233
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1451046400
PrevISDATBSI412MsgDLCError_Cnt_M_u08	245
PrevISDATBSI412MsgRxTime_MSec_M_u32	3676775936
PrevISDATBSI432MsgDLCError_Cnt_M_u08	40
PrevISDATBSI432MsgRxTime_MSec_M_u32	4182148608
PrevISDATDIRAMsgTxTime_MSec_M_u32	2052793856
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	231
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1436972544
PrevISDYNAASMsgDLCError_Cnt_M_u08	145
PrevISDYNAASMsgRxTime_MSec_M_u32	568894976
PrevISDYNABRMsgDLCError_Cnt_M_u08	33
PrevISDYNABRMsgRxTime_MSec_M_u32	797042176
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	2
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3352143360
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	30
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2548139520
PrevISDYNVOLMsgDLCError_Cnt_M_u08	139
PrevISDYNVOLMsgRxTime_MSec_M_u32	2992907776
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1979815424
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	368.621887
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57081
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	40831
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	53826
VitesseVehicleBVRampValidCount_Cnt_M_u16	42888
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	17153
VitesseVehicleBVSigValidCount_Cnt_M_u16	41903
VitesseVehicleBV_Kph_M_f32	596.379517
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	29214
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	23811
VitesseVehiculeRoues_Kph_M_f32	9.86750031
k_AASNTCEnableTimeout_mS_u16	55999
k_AASNodeAbsentDiag_Cnt_str.Threshold	41849

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	15852
k_AASNodeAbsentDiag_Cnt_str.NStep	33093
k_AASNodeAbsentTimeout_mS_u16	46403
k_AASNodeTimeout_mS_u16	37503
k_ABSNodeTimeout_mS_u16	41726
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	4495
k_ANGLEVOLANTSigValidThresh_Cnt_u16	40952
k_AngleVolantInvalidThresh_Cnt_u16	44407
k_AngleVolantValidThresh_Cnt_u16	21501
k_BSI552MsgTimeout_mS_u16	36674
k_BSINTCEnableTimeout_mS_u16	17012
k_BSINodeAbsentDiag_Cnt_str.Threshold	349
k_BSINodeAbsentDiag_Cnt_str.PStep	412
k_BSINodeAbsentDiag_Cnt_str.NStep	0
k_BSINodeAbsentTimeout_mS_u16	9721
k_BSINodeTimeout_mS_u16	44193
k_BattOvHi_Volt_f32	12.8754997
k_BattOvLo_Volt_f32	26.9652004
k_BattUvHi_Volt_f32	7.89709997
k_BattUvLo_Volt_f32	8.65960026
k_CAVNTCEnableTimeout_mS_u16	33827
k_CAVNodeAbsentDiag_Cnt_str.Threshold	44470
k_CAVNodeAbsentDiag_Cnt_str.PStep	52773
k_CAVNodeAbsentDiag_Cnt_str.NStep	9831
k_CAVNodeAbsentTimeout_mS_u16	61470
k_CAVNodeTimeout_mS_u16	51860
k_CMM388MsgTimeout_mS_u16	42580
k_CMM388NTCEnableTimeout_mS_u16	25392
k_CMMNTCEnableTimeout_mS_u16	55673
k_CMMNodeAbsentDiag_Cnt_str.Threshold	59627
k_CMMNodeAbsentDiag_Cnt_str.PStep	36033
k_CMMNodeAbsentDiag_Cnt_str.NStep	48804
k_CMMNodeAbsentTimeout_mS_u16	53215
k_CONSANGLECPKMax_HwDeg_f32	569.960815
k_CONSANGLECPKMin_HwDeg_f32	-494.36441
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	9502
k_CONSANGLECPKSigValidThresh_Cnt_u16	20483
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	56245
k_CPKVehicleSpeedValidThresh_Cnt_u16	47326
k_CityParkInputInvalidThresh_Cnt_u16	23713
k_CityParkInputValidThresh_Cnt_u16	52692
k_ComputerRazGCTSigValidThresh_Cnt_u16	23383
k_CptTemporelSigValidThresh_Cnt_u16	44600
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	19951
k_DMDFCTCPKSigValidThresh_Cnt_u16	63852
k_DMDFCTCPKValidCount_Cnt_u16	37815
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	48016
k_DMDRELAXECPKSigValidThresh_Cnt_u16	58277
k_DMDRelaxeConsistentThresh_Cnt_u16	5851
k_DateValidThresh_Cnt_u16	32228
k_DefaultVehSpd_Kph_f32	191.916794
k_DiagMuxOnAbsentTimeout_mS_u16	2614
k_EMNodeTimeout_mS_u16	20741
k_ESPNTCEnableTimeout_mS_u16	56716
k_ESPNodeAbsentDiag_Cnt_str.Threshold	7531
k_ESPNodeAbsentDiag_Cnt_str.PStep	62109
k_ESPNodeAbsentDiag_Cnt_str.NStep	55354
k_ESPNodeAbsentTimeout_mS_u16	7463
k_EtatMTSigInvalidThresh_Cnt_u16	47178
k_EtatMTSigValidThresh_Cnt_u16	12096
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	816
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	36009
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	37661
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	55758
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	59375
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	57191
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	12361
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	13874
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	33760
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	62996
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	53190
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	4393
k_ISDATDIRASentDiag_Cnt_str.Threshold	25921

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	8439
k_ISDATDIRASentDiag_Cnt_str.NStep	40264
k_ISDATDIRASentTimeout_mS_u16	35015
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	37518
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	22849
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	51704
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	33259
k_ISDYNAASChkSumValidThresh_Cnt_u16	40865
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	14621
k_ISDYNAASMsgCountValidThresh_Cnt_u16	57194
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	2063
k_ISDYNAASMsgLenValidThresh_Cnt_u16	63395
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	43840
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	49757
k_ISDYNABRChkSumValidThresh_Cnt_u16	33882
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	20591
k_ISDYNABRMsgCountValidThresh_Cnt_u16	34717
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	48792
k_ISDYNABRMsgLenValidThresh_Cnt_u16	12737
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	38748
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	58397
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	1996
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	7102
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	18744
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	46374
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	25781
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	18326
k_ISDYNVOLChkSumValidThresh_Cnt_u16	18279
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	58286
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	14533
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	42993
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	18315
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	36490
k_IgnOnTimeout_mS_u16	13682
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	156.806
k_PowerCutVehSpdLowThresh_Kph_f32	208.376297
k_PowerCutVehSpdLowTimeout_mS_u16	395
k_VBattMaxAAS_Volt_f32	14.2688999
k_VBattMaxBSI_Volt_f32	4.46229982
k_VBattMaxCAV_Volt_f32	0.576499999
k_VBattMaxCMM388_Volt_f32	16.7243004
k_VBattMaxCMM_Volt_f32	29.1138992
k_VBattMaxESP_Volt_f32	15.2523003
k_VBattMinAAS_Volt_f32	22.9244995
k_VBattMinBSI_Volt_f32	15.2523003
k_VBattMinCAV_Volt_f32	15.3409996
k_VBattMinCMM388_Volt_f32	9.86079979
k_VBattMinCMM_Volt_f32	1.73210001
k_VBattMinESP_Volt_f32	29.1138992
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	33880
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	40281
k_VitesseVehicleBVRampValidThresh_Cnt_u16	5447
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	9443
k_VitesseVehicleBVSigValidThresh_Cnt_u16	52181
k_VitesseVehicleBVSpeedPassThresh_kph_f32	406.844604
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	53936
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	48758
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	103532032
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	118
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	54541
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	433233920
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	30
target_SrlComInput_Per1_Batt_Volt_f32.value	22.8777008
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	699905536
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	13
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.41472736
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	140
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3487819264
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4260169216
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4240844288
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3564062208
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2364040704
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	774997504
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	32
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3226117632
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	42
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	82
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	163
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	186
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	204
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2467841536
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	39
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	161
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	228
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1319036416
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	189
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3223848448
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	214
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3263243776
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	155
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	240
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4162795008
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.21369414
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	973241
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	166.285706
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	8771

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	433233920	433233920	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	41849	41849	✔
AASNodeAbsentTimer_mS_M_u32	433233920	433233920	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	433233920	433233920	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	128.421692	128.421692	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	433233920	433233920	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	433233920	433233920	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	433233920	433233920	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	433233920	433233920	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	433233920	433233920	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	433233920	433233920	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	433233920	433233920	✔
CDD_SrlComVehSpd_Kph_G_f32	3.49110007	3.49110007	✔
CMM388NTCEnableTimer_mS_M_u32	433233920	433233920	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	433233920	433233920	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	59627	59627	✔
CMMNodeAbsentTimer_mS_M_u32	433233920	433233920	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	57488	57488	✔
CONSANGLECPK_HwDeg_M_f32	-162.174103	-162.174103 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	433233920	433233920	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	433233920	433233920	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	433233920	433233920	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	433233920	433233920	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	433233920	433233920	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	433233920	433233920	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	433233920	433233920	✔
ESPNTCEnableTimer_mS_M_u32	433233920	433233920	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	7531	7531	✔
ESPNodeAbsentTimer_mS_M_u32	433233920	433233920	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1000	1000	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2000	2000	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2324	2324	✔
ElecIntTimer_mS_M_u32[1]	45464	45464	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	433233920	433233920	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	32228	32228	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	433233920	433233920	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	51119	51119	✔
ISDATBSI3F2MsgTimer_mS_M_u32	433233920	433233920	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	54549	54549	✔
ISDATBSI412MsgTimer_mS_M_u32	433233920	433233920	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	44193	44193	✔
ISDATBSI432MsgTimer_mS_M_u32	433233920	433233920	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	433233920	433233920	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	48016	48016	✔
ISDYN2CMMMsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	52454	52454	✔
ISDYNAASMsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	57488	57488	✔
ISDYNABRMsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	51119	51119	✔
ISDYNCMM208MsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	29214	29214	✔
ISDYNCMM388MsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	52120	52120	✔
ISDYNVOLMsgTimer_mS_M_u32	433233920	433233920	✔
IgnOnTimer_mS_M_u32	3838436864	3838436864	✔
IgnTimeOff_Sec_M_u32	2345825784	2345825784	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	140	140	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3487819264	3487819264	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	53	53	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4260169216	4260169216	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	170	170	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4240844288	4240844288	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	245	245	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3564062208	3564062208	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2052793856	2052793856	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	39	39	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	774997504	774997504	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	32	32	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3226117632	3226117632	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	144	144	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2467841536	2467841536	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	49	49	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1319036416	1319036416	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	189	189	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3223848448	3223848448	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	214	214	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3263243776	3263243776	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4162795008	4162795008	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	368.621887	368.621887	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	596.379517	596.379517	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	9.86750031	9.86750031	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	128.421692	128.421692	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	57488	57488	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2345825784	2345825784	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-162.174103	-162.174103 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	3.49110007	3.49110007	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.133 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	50725120
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	32122
AASNodeAbsentTimer_mS_M_u32	2861707520
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	50893
ANGLEVOLANTSigValidCount_Cnt_M_u16	1220
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	49075
AngleVolantMsgTimer_mS_M_u32	50725120
AngleVolantValidCount_Cnt_M_u16	44518
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	346.903595
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1161228544
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4289949952
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2730762496
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	971759872
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	19752
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4089618688
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	3294
CAVNodeAbsentTimer_mS_M_u32	1364480256
CDD_SrlComVehSpd_Kph_G_f32	363.030212
CMM388NTCEnableTimer_mS_M_u32	189501696
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2628931840
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	43501
CMMNodeAbsentTimer_mS_M_u32	3809337600
CONSANGLECPKSigInvalidCount_Cnt_M_u16	44109
CONSANGLECPKSigValidCount_Cnt_M_u16	3413
CONSANGLECPK_Cnt_M_u16	17540
CONSANGLECPK_HwDeg_M_f32	-360.796509
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17540
CPKVehicleSpeedMsgTimer_mS_M_u32	2671313152
CPKVehicleSpeedValidCount_Cnt_M_u16	51173
CityParkInputConsistentCount_Cnt_M_u16	5754
CityParkInputInvalidCount_Cnt_M_u16	47358
CityParkInputMsgTimer_mS_M_u32	3487819264
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	942027008
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	33806

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3629830400
ComputerRazGCTSigValidCount_Cnt_M_u16	12811
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	31850
DMDFCTCPKSigValidCount_Cnt_M_u16	10154
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	58903
DMDRELAXECPKSigValidCount_Cnt_M_u16	59278
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	54150
DateInvalidTimer_mS_M_u32	4289949952
DiagMuxOnAbsentTimer_mS_M_u32	4265394432
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	971759872
ESPNTCEnableTimer_mS_M_u32	3005165824
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	49713
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	2500
EffacDefaultDiagTimer_mS_M_u32[1]	3500
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	565
ElecIntTimer_mS_M_u32[1]	78788
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3387728128
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	4725
EtatMTSigValidCount_Cnt_M_u16	44137
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	10647
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	52767
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	25864
ISDAT4V2BSI552MsgTimer_mS_M_u32	933355776
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	61171
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	46479
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	44137
ISDATBSI3F2MsgTimer_mS_M_u32	3102916864
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	22636
ISDATBSI412MsgLenValidCount_Cnt_M_u16	9080
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	4725
ISDATBSI412MsgTimer_mS_M_u32	2344354048
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1409
ISDATBSI432MsgLenValidCount_Cnt_M_u16	25797
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	36881
ISDATDIRASentFltAcc_Cnt_M_u16	65397
ISDATDIRASentTimer_mS_M_u32	2671313152
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	48058
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	44518
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36421
ISDYN2CMMMsgTimer_mS_M_u32	2126590208
ISDYNAASChkSumInvalidCount_Cnt_M_u16	14532
ISDYNAASChkSumValidCount_Cnt_M_u16	10588
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	36289
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	53587
ISDYNAASMsgLenValidCount_Cnt_M_u16	13571
ISDYNAASMsgTimeValidCount_Cnt_M_u16	14532
ISDYNAASMsgTimer_mS_M_u32	2411172096
ISDYNABRChkSumInvalidCount_Cnt_M_u16	8754
ISDYNABRChkSumValidCount_Cnt_M_u16	27346
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	10527
ISDYNABRMsgCountValidCount_Cnt_M_u16	14327
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	936
ISDYNABRMsgLenValidCount_Cnt_M_u16	49904
ISDYNABRMsgTimeValidCount_Cnt_M_u16	17540
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	735
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1355
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	44137
ISDYNCMM208MsgTimer_mS_M_u32	4161270016
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2791
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1461
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	53660

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1355092224
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	48899
ISDYNVOLChkSumValidCount_Cnt_M_u16	56459
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	13856
ISDYNVOLMsgCountValidCount_Cnt_M_u16	56800
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	54486
ISDYNVOLMsgLenValidCount_Cnt_M_u16	25405
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	43501
ISDYNVOLMsgTimer_mS_M_u32	415682816
IgnOnTimer_mS_M_u32	72945920
IgnTimeOff_Sec_M_u32	850262029
ManVehSpd_Kph_M_f32	382.981903
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	91
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	180
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2662383872
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	162
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1618944256
PrevISDATBSI412MsgDLCError_Cnt_M_u08	100
PrevISDATBSI412MsgRxTime_MSec_M_u32	641814784
PrevISDATBSI432MsgDLCError_Cnt_M_u08	239
PrevISDATBSI432MsgRxTime_MSec_M_u32	23277824
PrevISDATDIRAMsgTxTime_MSec_M_u32	413487360
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	158
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2550358272
PrevISDYNAASMsgDLCError_Cnt_M_u08	64
PrevISDYNAASMsgRxTime_MSec_M_u32	939315456
PrevISDYNABRMsgDLCError_Cnt_M_u08	245
PrevISDYNABRMsgRxTime_MSec_M_u32	70324480
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	244
PrevISDYNCMM208MsgRxTime_MSec_M_u32	441307392
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	254
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1368535296
PrevISDYNVOLMsgDLCError_Cnt_M_u08	158
PrevISDYNVOLMsgRxTime_MSec_M_u32	3565834496
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	192020736
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	349.655212
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	22793
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	14649
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	58158
VitesseVehicleBVRampValidCount_Cnt_M_u16	34078
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	42098
VitesseVehicleBVSigValidCount_Cnt_M_u16	17449
VitesseVehicleBV_Kph_M_f32	12.4993
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	53660
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	45739
VitesseVehiculeRoues_Kph_M_f32	401.669189
k_AASNTCEnableTimeout_mS_u16	53751
k_AASNodeAbsentDiag_Cnt_str.Threshold	45219

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	46178
k_AASNodeAbsentDiag_Cnt_str.NStep	40109
k_AASNodeAbsentTimeout_mS_u16	56365
k_AASNodeTimeout_mS_u16	24633
k_ABSNodeTimeout_mS_u16	4091
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	29704
k_ANGLEVOLANTSigValidThresh_Cnt_u16	31372
k_AngleVolantInvalidThresh_Cnt_u16	3599
k_AngleVolantValidThresh_Cnt_u16	47358
k_BSI552MsgTimeout_mS_u16	55278
k_BSINTCEnableTimeout_mS_u16	46425
k_BSINodeAbsentDiag_Cnt_str.Threshold	462
k_BSINodeAbsentDiag_Cnt_str.PStep	518
k_BSINodeAbsentDiag_Cnt_str.NStep	65535
k_BSINodeAbsentTimeout_mS_u16	14731
k_BSINodeTimeout_mS_u16	36881
k_BattOvHi_Volt_f32	29.5109005
k_BattOvLo_Volt_f32	12.9816999
k_BattUvHi_Volt_f32	13.533
k_BattUvLo_Volt_f32	13.4990997
k_CAVNTCEnableTimeout_mS_u16	16524
k_CAVNodeAbsentDiag_Cnt_str.Threshold	18467
k_CAVNodeAbsentDiag_Cnt_str.PStep	8237
k_CAVNodeAbsentDiag_Cnt_str.NStep	15872
k_CAVNodeAbsentTimeout_mS_u16	63898
k_CAVNodeTimeout_mS_u16	51385
k_CMM388MsgTimeout_mS_u16	58490
k_CMM388NTCEnableTimeout_mS_u16	7654
k_CMMNTCEnableTimeout_mS_u16	19147
k_CMMNodeAbsentDiag_Cnt_str.Threshold	34987
k_CMMNodeAbsentDiag_Cnt_str.PStep	3393
k_CMMNodeAbsentDiag_Cnt_str.NStep	57072
k_CMMNodeAbsentTimeout_mS_u16	51735
k_CONSANGLECPKMax_HwDeg_f32	301.997589
k_CONSANGLECPKMin_HwDeg_f32	-205.437897
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	47260
k_CONSANGLECPKSigValidThresh_Cnt_u16	55723
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	56471
k_CPKVehicleSpeedValidThresh_Cnt_u16	53659
k_CityParkInputInvalidThresh_Cnt_u16	53520
k_CityParkInputValidThresh_Cnt_u16	5754
k_ComputerRazGCTSigValidThresh_Cnt_u16	48433
k_CptTemporelSigValidThresh_Cnt_u16	22093
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	27304
k_DMDFCTCPKSigValidThresh_Cnt_u16	27120
k_DMDFCTCPKValidCount_Cnt_u16	2640
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	36421
k_DMDRELAXECPKSigValidThresh_Cnt_u16	30661
k_DMDRelaxeConsistentThresh_Cnt_u16	13859
k_DateValidThresh_Cnt_u16	25864
k_DefaultVehSpd_Kph_f32	186.213394
k_DiagMuxOnAbsentTimeout_mS_u16	57234
k_EMNodeTimeout_mS_u16	14694
k_ESPNTCEnableTimeout_mS_u16	26960
k_ESPNodeAbsentDiag_Cnt_str.Threshold	24333
k_ESPNodeAbsentDiag_Cnt_str.PStep	4238
k_ESPNodeAbsentDiag_Cnt_str.NStep	32782
k_ESPNodeAbsentTimeout_mS_u16	575
k_EtatMTSigInvalidThresh_Cnt_u16	41493
k_EtatMTSigValidThresh_Cnt_u16	7925
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	4646
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	26490
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	10911
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	56780
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	17704
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	49664
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	32730
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	8158
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	41237
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	5112
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	22692
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	1466
k_ISDATDIRASentDiag_Cnt_str.Threshold	46594

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	38967
k_ISDATDIRASentDiag_Cnt_str.NStep	17884
k_ISDATDIRASentTimeout_mS_u16	25758
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	21899
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	49075
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	21516
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	2354
k_ISDYNAASChkSumValidThresh_Cnt_u16	37330
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	36895
k_ISDYNAASMsgCountValidThresh_Cnt_u16	57079
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	1734
k_ISDYNAASMsgLenValidThresh_Cnt_u16	49357
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	30900
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	17758
k_ISDYNABRChkSumValidThresh_Cnt_u16	294
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	46120
k_ISDYNABRMsgCountValidThresh_Cnt_u16	53343
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	53485
k_ISDYNABRMsgLenValidThresh_Cnt_u16	10545
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	23842
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	55709
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7377
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	32892
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	11725
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	43972
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	26326
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	1395
k_ISDYNVOLChkSumValidThresh_Cnt_u16	22463
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	1898
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	22118
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	2529
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	40149
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	19222
k_IgnOnTimeout_mS_u16	43999
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	186.045898
k_PowerCutVehSpdLowThresh_Kph_f32	231.335007
k_PowerCutVehSpdLowTimeout_mS_u16	36243
k_VBattMaxAAS_Volt_f32	29.8917007
k_VBattMaxBSI_Volt_f32	25.6026001
k_VBattMaxCAV_Volt_f32	4.29220009
k_VBattMaxCMM388_Volt_f32	0.514699996
k_VBattMaxCMM_Volt_f32	25.1888008
k_VBattMaxESP_Volt_f32	24.8467999
k_VBattMinAAS_Volt_f32	24.7756004
k_VBattMinBSI_Volt_f32	24.8467999
k_VBattMinCAV_Volt_f32	32
k_VBattMinCMM388_Volt_f32	23.3934002
k_VBattMinCMM_Volt_f32	20.9347
k_VBattMinESP_Volt_f32	25.1888008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	10285
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	61160
k_VitesseVehicleBVRampValidThresh_Cnt_u16	7456
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	33675
k_VitesseVehicleBVSigValidThresh_Cnt_u16	24695
k_VitesseVehicleBVSpeedPassThresh_kph_f32	292.032288
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	6628
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	30804
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4289949952
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	108
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	41358
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2292638464
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	254
target_SrlComInput_Per1_Batt_Volt_f32.value	21.9874992
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4040139008
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	242
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.880068421
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	722145536
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2909778176
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4251209984
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	48820480
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2784858368
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	243
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3466735872
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1691799808
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	108
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	134
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	177
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	182
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	4
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2867720448
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	227
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1524240640
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	171
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	314487040
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	13
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1479758080
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	145
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2207850752
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3633
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0387445651
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	724683
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	204.856705
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	14123

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	45219	45219	✔
AASNodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2292638464	2292638464	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	346.903595	346.903595	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
CDD_SrlComVehSpd_Kph_G_f32	382.981903	382.981903	✔
CMM388NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	34987	34987	✔
CMMNodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	17540	17540	✔
CONSANGLECPK_HwDeg_M_f32	-360.796509	-360.796509 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2292638464	2292638464	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2292638464	2292638464	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2292638464	2292638464	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2292638464	2292638464	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2292638464	2292638464	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2292638464	2292638464	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2292638464	2292638464	✔
ESPNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	24333	24333	✔
ESPNodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2500	2500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3500	3500	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	565	565	✔
ElecIntTimer_mS_M_u32[1]	78788	78788	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2292638464	2292638464	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	25864	25864	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	44137	44137	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	4725	4725	✔
ISDATBSI412MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	36881	36881	✔
ISDATBSI432MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2292638464	2292638464	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36421	36421	✔
ISDYN2CMMMsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	14532	14532	✔
ISDYNAASMsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	17540	17540	✔
ISDYNABRMsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	44137	44137	✔
ISDYNCMM208MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	53660	53660	✔
ISDYNCMM388MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	43501	43501	✔
ISDYNVOLMsgTimer_mS_M_u32	2292638464	2292638464	✔
IgnOnTimer_mS_M_u32	72945920	72945920	✔
IgnTimeOff_Sec_M_u32	850262029	850262029	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	722145536	722145536	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	153	153	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2909778176	2909778176	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	229	229	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4251209984	4251209984	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	242	242	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	48820480	48820480	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	413487360	413487360	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	243	243	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3466735872	3466735872	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	181	181	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1691799808	1691799808	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	4	4	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2867720448	2867720448	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1524240640	1524240640	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	171	171	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	314487040	314487040	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	13	13	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1479758080	1479758080	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2207850752	2207850752	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	349.655212	349.655212	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	12.4993	12.4993	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	401.669189	401.669189	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	346.903595	346.903595	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	17540	17540	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	850262029	850262029	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-360.796509	-360.796509 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.134 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1339080704
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	21107
AASNodeAbsentTimer_mS_M_u32	99364864
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	57467
ANGLEVOLANTSigValidCount_Cnt_M_u16	57684
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	45000
AngleVolantMsgTimer_mS_M_u32	1339080704
AngleVolantValidCount_Cnt_M_u16	30640
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	547.365173
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3103649792
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	461926400
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2434162688
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	446636032
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	31082
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3088769024
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	692
CAVNodeAbsentTimer_mS_M_u32	1109774336
CDD_SrlComVehSpd_Kph_G_f32	162.405594
CMM388NTCEnableTimer_mS_M_u32	20975616
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1477169152
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	11610
CMMNodeAbsentTimer_mS_M_u32	658055168
CONSANGLECPKSigInvalidCount_Cnt_M_u16	8953
CONSANGLECPKSigValidCount_Cnt_M_u16	64162
CONSANGLECPK_Cnt_M_u16	53525
CONSANGLECPK_HwDeg_M_f32	-555.052185
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	53525
CPKVehicleSpeedMsgTimer_mS_M_u32	121094144
CPKVehicleSpeedValidCount_Cnt_M_u16	54073
CityParkInputConsistentCount_Cnt_M_u16	36340
CityParkInputInvalidCount_Cnt_M_u16	1895
CityParkInputMsgTimer_mS_M_u32	722145536
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2905616384
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	36535

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3876737024
ComputerRazGCTSigValidCount_Cnt_M_u16	48961
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	27939
DMDFCTCPKSigValidCount_Cnt_M_u16	17956
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	10909
DMDRELAXECPKSigValidCount_Cnt_M_u16	57590
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	53582
DateInvalidTimer_mS_M_u32	461926400
DiagMuxOnAbsentTimer_mS_M_u32	2838265856
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	446636032
ESPNTCEnableTimer_mS_M_u32	1615147008
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	53071
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	102
EffacDefaultDiagTimer_mS_M_u32[1]	106
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	1234
ElecIntTimer_mS_M_u32[1]	23645
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1570562048
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	25793
EtatMTSigValidCount_Cnt_M_u16	16806
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	21275
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	24644
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	34314
ISDAT4V2BSI552MsgTimer_mS_M_u32	2038243328
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	40647
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	38324
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	16806
ISDATBSI3F2MsgTimer_mS_M_u32	3507126272
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	55131
ISDATBSI412MsgLenValidCount_Cnt_M_u16	33016
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	25793
ISDATBSI412MsgTimer_mS_M_u32	229556224
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	27294
ISDATBSI432MsgLenValidCount_Cnt_M_u16	14227
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	57133
ISDATDIRASentFltAcc_Cnt_M_u16	8449
ISDATDIRASentTimer_mS_M_u32	121094144
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	50035
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	30640
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	25490
ISDYN2CMMMsgTimer_mS_M_u32	90124288
ISDYNAASChkSumInvalidCount_Cnt_M_u16	51349
ISDYNAASChkSumValidCount_Cnt_M_u16	12686
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	1055
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	41831
ISDYNAASMsgLenValidCount_Cnt_M_u16	4888
ISDYNAASMsgTimeValidCount_Cnt_M_u16	51349
ISDYNAASMsgTimer_mS_M_u32	603721728
ISDYNABRChkSumInvalidCount_Cnt_M_u16	15818
ISDYNABRChkSumValidCount_Cnt_M_u16	48811
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	9092
ISDYNABRMsgCountValidCount_Cnt_M_u16	12733
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	18664
ISDYNABRMsgLenValidCount_Cnt_M_u16	1489
ISDYNABRMsgTimeValidCount_Cnt_M_u16	53525
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	736
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1357
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	16806
ISDYNCMM208MsgTimer_mS_M_u32	613085184
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2795
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1463
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	25742

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	4141060096
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	17111
ISDYNVOLChkSumValidCount_Cnt_M_u16	58624
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	38913
ISDYNVOLMsgCountValidCount_Cnt_M_u16	31618
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	27488
ISDYNVOLMsgLenValidCount_Cnt_M_u16	15080
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	11610
ISDYNVOLMsgTimer_mS_M_u32	3587067904
IgnOnTimer_mS_M_u32	739741696
IgnTimeOff_Sec_M_u32	278333675
ManVehSpd_Kph_M_f32	504.430695
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	93
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	175
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2547023872
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	76
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	65363968
PrevISDATBSI412MsgDLCError_Cnt_M_u08	87
PrevISDATBSI412MsgRxTime_MSec_M_u32	3076444160
PrevISDATBSI432MsgDLCError_Cnt_M_u08	69
PrevISDATBSI432MsgRxTime_MSec_M_u32	2239311872
PrevISDATDIRAMsgTxTime_MSec_M_u32	1882378240
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	123
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3193479168
PrevISDYNAASMsgDLCError_Cnt_M_u08	175
PrevISDYNAASMsgRxTime_MSec_M_u32	3492564992
PrevISDYNABRMsgDLCError_Cnt_M_u08	95
PrevISDYNABRMsgRxTime_MSec_M_u32	2358218752
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	133
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2906214400
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	71
PrevISDYNCMM388MsgRxTime_MSec_M_u32	283914240
PrevISDYNVOLMsgDLCError_Cnt_M_u08	177
PrevISDYNVOLMsgRxTime_MSec_M_u32	277073920
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3867983872
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	43.5732002
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	25669
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	24182
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	39382
VitesseVehicleBVRampValidCount_Cnt_M_u16	20167
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	7052
VitesseVehicleBVSigValidCount_Cnt_M_u16	63269
VitesseVehicleBV_Kph_M_f32	16.6905003
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	25742
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	56351
VitesseVehiculeRoues_Kph_M_f32	334.919495
k_AASNTCEnableTimeout_mS_u16	46268
k_AASNodeAbsentDiag_Cnt_str.Threshold	52784

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	43434
k_AASNodeAbsentDiag_Cnt_str.NStep	14785
k_AASNodeAbsentTimeout_mS_u16	51419
k_AASNodeTimeout_mS_u16	59766
k_ABSNodeTimeout_mS_u16	13936
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	64265
k_ANGLEVOLANTSigValidThresh_Cnt_u16	53822
k_AngleVolantInvalidThresh_Cnt_u16	58293
k_AngleVolantValidThresh_Cnt_u16	1895
k_BSI552MsgTimeout_mS_u16	14422
k_BSINTCEnableTimeout_mS_u16	47894
k_BSINodeAbsentDiag_Cnt_str.Threshold	575
k_BSINodeAbsentDiag_Cnt_str.PStep	624
k_BSINodeAbsentDiag_Cnt_str.NStep	4536
k_BSINodeAbsentTimeout_mS_u16	41536
k_BSINodeTimeout_mS_u16	57133
k_BattOvHi_Volt_f32	2
k_BattOvLo_Volt_f32	14.7416
k_BattUvHi_Volt_f32	20.5461998
k_BattUvLo_Volt_f32	0
k_CAVNTCEnableTimeout_mS_u16	10429
k_CAVNodeAbsentDiag_Cnt_str.Threshold	50439
k_CAVNodeAbsentDiag_Cnt_str.PStep	61666
k_CAVNodeAbsentDiag_Cnt_str.NStep	33698
k_CAVNodeAbsentTimeout_mS_u16	1682
k_CAVNodeTimeout_mS_u16	32181
k_CMM388MsgTimeout_mS_u16	7539
k_CMM388NTCEnableTimeout_mS_u16	8495
k_CMMNTCEnableTimeout_mS_u16	60223
k_CMMNodeAbsentDiag_Cnt_str.Threshold	52471
k_CMMNodeAbsentDiag_Cnt_str.PStep	20207
k_CMMNodeAbsentDiag_Cnt_str.NStep	985
k_CMMNodeAbsentTimeout_mS_u16	17883
k_CONSANGLECPKMax_HwDeg_f32	335.326691
k_CONSANGLECPKMin_HwDeg_f32	-302.133392
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	44942
k_CONSANGLECPKSigValidThresh_Cnt_u16	26399
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	27740
k_CPKVehicleSpeedValidThresh_Cnt_u16	59342
k_CityParkInputInvalidThresh_Cnt_u16	10544
k_CityParkInputValidThresh_Cnt_u16	36340
k_ComputerRazGCTSigValidThresh_Cnt_u16	44045
k_CptTemporelSigValidThresh_Cnt_u16	11130
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	5096
k_DMDFCTCPKSigValidThresh_Cnt_u16	4305
k_DMDFCTCPKValidCount_Cnt_u16	57842
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	25490
k_DMDRELAXECPKSigValidThresh_Cnt_u16	33235
k_DMDRelaxeConsistentThresh_Cnt_u16	16057
k_DateValidThresh_Cnt_u16	34314
k_DefaultVehSpd_Kph_f32	52.7456017
k_DiagMuxOnAbsentTimeout_mS_u16	0
k_EMNodeTimeout_mS_u16	8110
k_ESPNTCEnableTimeout_mS_u16	3952
k_ESPNodeAbsentDiag_Cnt_str.Threshold	28211
k_ESPNodeAbsentDiag_Cnt_str.PStep	9832
k_ESPNodeAbsentDiag_Cnt_str.NStep	55007
k_ESPNodeAbsentTimeout_mS_u16	15715
k_EtatMTSigInvalidThresh_Cnt_u16	2593
k_EtatMTSigValidThresh_Cnt_u16	60994
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	51119
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	62068
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	9605
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	30268
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	35561
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	60063
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	40851
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	43592
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	59362
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	12985
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	61302
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	38004
k_ISDATDIRASentDiag_Cnt_str.Threshold	48619

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	14149
k_ISDATDIRASentDiag_Cnt_str.NStep	9868
k_ISDATDIRASentTimeout_mS_u16	9862
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	10497
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	45000
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	16188
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	35018
k_ISDYNAASChkSumValidThresh_Cnt_u16	18859
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	61060
k_ISDYNAASMsgCountValidThresh_Cnt_u16	15549
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	57358
k_ISDYNAASMsgLenValidThresh_Cnt_u16	6074
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	30662
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	56262
k_ISDYNABRChkSumValidThresh_Cnt_u16	41775
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	17514
k_ISDYNABRMsgCountValidThresh_Cnt_u16	43651
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	47194
k_ISDYNABRMsgLenValidThresh_Cnt_u16	39503
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	53306
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	12937
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	24108
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	21677
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	43899
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	60500
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	24031
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	44102
k_ISDYNVOLChkSumValidThresh_Cnt_u16	49187
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	9124
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	19439
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	11901
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	8290
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	35808
k_IgnOnTimeout_mS_u16	26882
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	113.748001
k_PowerCutVehSpdLowThresh_Kph_f32	145.880905
k_PowerCutVehSpdLowTimeout_mS_u16	61928
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	14.7009001
k_VBattMaxCAV_Volt_f32	12.5354004
k_VBattMaxCMM388_Volt_f32	21.8698006
k_VBattMaxCMM_Volt_f32	26.3192997
k_VBattMaxESP_Volt_f32	21.1254005
k_VBattMinAAS_Volt_f32	18.5032005
k_VBattMinBSI_Volt_f32	21.1254005
k_VBattMinCAV_Volt_f32	7.93760014
k_VBattMinCMM388_Volt_f32	12.3695002
k_VBattMinCMM_Volt_f32	1.27980006
k_VBattMinESP_Volt_f32	26.3192997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	47387
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	12200
k_VitesseVehicleBVRampValidThresh_Cnt_u16	58113
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	61440
k_VitesseVehicleBVSigValidThresh_Cnt_u16	58365
k_VitesseVehicleBVSpeedPassThresh_kph_f32	45.3064003
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	19892
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	52517
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	461926400
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	0
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3572898304
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	71
target_SrlComInput_Per1_Batt_Volt_f32.value	1
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	888397824
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	37
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.99324888
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	120
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	102400
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1397993472
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2113261568
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3353866240
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2032799744
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3652988928
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	234
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	832458752
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	131
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	601419776
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	36
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	156
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	157
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	184
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	61
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1821675520
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	159
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	526823424
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1770573824
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2190958592
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2153
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.893223941
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	295147
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	171.565704
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	53727

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	6322	6322	✔
AASNodeAbsentTimer_mS_M_u32	832458752	832458752	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	45001	45001	✔
AngleVolantMsgTimer_mS_M_u32	1770573824	1770573824	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	547.365173	547.365173	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26546	26546	✔
BSINodeAbsentTimer_mS_M_u32	3353866240	3353866240	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1770573824	1770573824	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	10625	10625	✔
CMMNodeAbsentTimer_mS_M_u32	3652988928	3652988928	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	53525	53525	✔
CONSANGLECPK_HwDeg_M_f32	-555.052185	-555.052185 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	53525	53525	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	601419776	601419776	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	36340	36340	✔
CityParkInputInvalidCount_Cnt_M_u16	1896	1896	✔
CityParkInputMsgTimer_mS_M_u32	832458752	832458752	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3572898304	3572898304	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3572898304	3572898304	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3572898304	3572898304	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3572898304	3572898304	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3572898304	3572898304	✔
ESPNTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	601419776	601419776	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	102	102	✔
EffacDefaultDiagTimer_mS_M_u32[1]	106	106	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1234	1234	✔
ElecIntTimer_mS_M_u32[1]	23645	23645	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1570562048	1570562048	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3572898304	3572898304	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3572898304	3572898304	✔
IgnOnTimer_mS_M_u32	739741696	739741696	✔
IgnTimeOff_Sec_M_u32	278333675	278333675	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	120	120	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	102400	102400	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1397993472	1397993472	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	241	241	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2113261568	2113261568	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	2	2	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3353866240	3353866240	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2032799744	2032799744	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	55	55	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3652988928	3652988928	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	234	234	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	832458752	832458752	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	601419776	601419776	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	61	61	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1821675520	1821675520	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	159	159	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	526823424	526823424	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	117	117	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1770573824	1770573824	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2190958592	2190958592	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	43.5732002	43.5732002	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	16.6905003	16.6905003	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	334.919495	334.919495	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	547.365173	547.365173	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	53525	53525	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	278333675	278333675	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-555.052185	-555.052185 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	52.7456017	52.7456017	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	3	NodeAbsentNTCProcessing	3	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.135 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	120357632
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	43333
AASNodeAbsentTimer_mS_M_u32	3734647552
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	49451
ANGLEVOLANTSigValidCount_Cnt_M_u16	36448
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	9542
AngleVolantMsgTimer_mS_M_u32	120357632
AngleVolantValidCount_Cnt_M_u16	5645
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	586.687683
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1013248768
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1589998336
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3789267712
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1480680192
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	29278
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	516825856
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	9984
CAVNodeAbsentTimer_mS_M_u32	2557301504
CDD_SrlComVehSpd_Kph_G_f32	355.949707
CMM388NTCEnableTimer_mS_M_u32	2485031680
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1857770240
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	63440
CMMNodeAbsentTimer_mS_M_u32	443769600
CONSANGLECPKSigInvalidCount_Cnt_M_u16	8370
CONSANGLECPKSigValidCount_Cnt_M_u16	43383
CONSANGLECPK_Cnt_M_u16	45598
CONSANGLECPK_HwDeg_M_f32	349.270996
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	45598
CPKVehicleSpeedMsgTimer_mS_M_u32	1022853888
CPKVehicleSpeedValidCount_Cnt_M_u16	9947
CityParkInputConsistentCount_Cnt_M_u16	58177
CityParkInputInvalidCount_Cnt_M_u16	21479
CityParkInputMsgTimer_mS_M_u32	102400
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4174263040
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	1145
ComputerRazGCTSigInvalidTimer_mS_M_u32	4222079744

Name	Input Value
ComputerRazGCTSigValidCount_Cnt_M_u16	50010
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	4787
DMDFCTCPKSigValidCount_Cnt_M_u16	63345
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	60101
DMDRELAXECPKSigValidCount_Cnt_M_u16	38778
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	43443
DateInvalidTimer_mS_M_u32	1589998336
DiagMuxOnAbsentTimer_mS_M_u32	437863168
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1480680192
ESPNTCEnableTimer_mS_M_u32	1938764544
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	20913
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	89
EffacDefaultDiagTimer_mS_M_u32[1]	789
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	6446
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3058180864
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	65178
EtatMTSigValidCount_Cnt_M_u16	26540
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	38988
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	32913
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20415
ISDAT4V2BSI552MsgTimer_mS_M_u32	866607872
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	57863
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	7424
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	26540
ISDATBSI3F2MsgTimer_mS_M_u32	2592031488
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	55626
ISDATBSI412MsgLenValidCount_Cnt_M_u16	48180
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	65178
ISDATBSI412MsgTimer_mS_M_u32	3314713344
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	20484
ISDATBSI432MsgLenValidCount_Cnt_M_u16	10469
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	46485
ISDATDIRASentFltAcc_Cnt_M_u16	16409
ISDATDIRASentTimer_mS_M_u32	1022853888
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	54020
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	5645
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	43878
ISDYN2CMMMsgTimer_mS_M_u32	1816212224
ISDYNAASChkSumInvalidCount_Cnt_M_u16	20191
ISDYNAASChkSumValidCount_Cnt_M_u16	25524
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	60608
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	53479
ISDYNAASMsgLenValidCount_Cnt_M_u16	45460
ISDYNAASMsgTimeValidCount_Cnt_M_u16	20191
ISDYNAASMsgTimer_mS_M_u32	468357888
ISDYNABRChkSumInvalidCount_Cnt_M_u16	23232
ISDYNABRChkSumValidCount_Cnt_M_u16	51165
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	47634
ISDYNABRMsgCountValidCount_Cnt_M_u16	57127
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	10981
ISDYNABRMsgLenValidCount_Cnt_M_u16	1002
ISDYNABRMsgTimeValidCount_Cnt_M_u16	45598
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	737
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1359
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	26540
ISDYNCMM208MsgTimer_mS_M_u32	1841165056
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2799
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1465
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	18291
ISDYNCMM388MsgTimer_mS_M_u32	1633948416

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	47384
ISDYNVOLChkSumValidCount_Cnt_M_u16	57949
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	35353
ISDYNVOLMsgCountValidCount_Cnt_M_u16	20311
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	382
ISDYNVOLMsgLenValidCount_Cnt_M_u16	8867
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	63440
ISDYNVOLMsgTimer_mS_M_u32	527684352
IgnOnTimer_mS_M_u32	3516404480
IgnTimeOff_Sec_M_u32	248942597
ManVehSpd_Kph_M_f32	93.2544022
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	95
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	140
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3727508224
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	124
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2238620416
PrevISDATBSI412MsgDLCError_Cnt_M_u08	107
PrevISDATBSI412MsgRxTime_MSec_M_u32	1556239104
PrevISDATBSI432MsgDLCError_Cnt_M_u08	245
PrevISDATBSI432MsgRxTime_MSec_M_u32	3555930880
PrevISDATDIRAMsgTxTime_MSec_M_u32	2185646848
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	141
PrevISDYN2CMMMsgRxTime_MSec_M_u32	857006848
PrevISDYNAASMsgDLCError_Cnt_M_u08	165
PrevISDYNAASMsgRxTime_MSec_M_u32	676975360
PrevISDYNABRMsgDLCError_Cnt_M_u08	32
PrevISDYNABRMsgRxTime_MSec_M_u32	2419069696
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	78
PrevISDYNCMM208MsgRxTime_MSec_M_u32	87216896
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	98
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3180999424
PrevISDYNVOLMsgDLCError_Cnt_M_u08	70
PrevISDYNVOLMsgRxTime_MSec_M_u32	626217728
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	855147264
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	532.979004
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	34381
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	51066
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	27034
VitesseVehicleBVRampValidCount_Cnt_M_u16	31367
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	37880
VitesseVehicleBVSigValidCount_Cnt_M_u16	53485
VitesseVehicleBV_Kph_M_f32	446.978088
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	18291
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	36992
VitesseVehiculeRoues_Kph_M_f32	285.796204
k_AASNTCEnableTimeout_mS_u16	25385
k_AASNodeAbsentDiag_Cnt_str.Threshold	54885
k_AASNodeAbsentDiag_Cnt_str.PStep	28623

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.NStep	50336
k_AASNodeAbsentTimeout_mS_u16	36492
k_AASNodeTimeout_mS_u16	9850
k_ABSNodeTimeout_mS_u16	10956
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	2755
k_ANGLEVOLANTSigValidThresh_Cnt_u16	50404
k_AngleVolantInvalidThresh_Cnt_u16	11391
k_AngleVolantValidThresh_Cnt_u16	21479
k_BSI552MsgTimeout_mS_u16	6107
k_BSINTCEnableTimeout_mS_u16	16028
k_BSINodeAbsentDiag_Cnt_str.Threshold	688
k_BSINodeAbsentDiag_Cnt_str.PStep	730
k_BSINodeAbsentDiag_Cnt_str.NStep	56
k_BSINodeAbsentTimeout_mS_u16	11742
k_BSINodeTimeout_mS_u16	46485
k_BattOvHi_Volt_f32	2
k_BattOvLo_Volt_f32	22.3775005
k_BattUvHi_Volt_f32	15.0881996
k_BattUvLo_Volt_f32	0
k_CAVNTCEnableTimeout_mS_u16	51173
k_CAVNodeAbsentDiag_Cnt_str.Threshold	6617
k_CAVNodeAbsentDiag_Cnt_str.PStep	23136
k_CAVNodeAbsentDiag_Cnt_str.NStep	48504
k_CAVNodeAbsentTimeout_mS_u16	4966
k_CAVNodeTimeout_mS_u16	126
k_CMM388MsgTimeout_mS_u16	18501
k_CMM388NTCEnableTimeout_mS_u16	11537
k_CMMNTCEnableTimeout_mS_u16	56479
k_CMMNodeAbsentDiag_Cnt_str.Threshold	50543
k_CMMNodeAbsentDiag_Cnt_str.PStep	61537
k_CMMNodeAbsentDiag_Cnt_str.NStep	13241
k_CMMNodeAbsentTimeout_mS_u16	17228
k_CONSANGLECPKMax_HwDeg_f32	740.958618
k_CONSANGLECPKMin_HwDeg_f32	-223.361099
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	26227
k_CONSANGLECPKSigValidThresh_Cnt_u16	61312
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	46536
k_CPKVehicleSpeedValidThresh_Cnt_u16	13297
k_CityParkInputInvalidThresh_Cnt_u16	45198
k_CityParkInputValidThresh_Cnt_u16	58177
k_ComputerRazGCTSigValidThresh_Cnt_u16	21045
k_CptTemporelSigValidThresh_Cnt_u16	62382
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	51685
k_DMDFCTCPKSigValidThresh_Cnt_u16	58090
k_DMDFCTCPKValidCount_Cnt_u16	22726
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	43878
k_DMDRELAXECPKSigValidThresh_Cnt_u16	49252
k_DMDRelaxeConsistentThresh_Cnt_u16	41394
k_DateValidThresh_Cnt_u16	20415
k_DefaultVehSpd_Kph_f32	56.8833008
k_DiagMuxOnAbsentTimeout_mS_u16	0
k_EMNodeTimeout_mS_u16	16019
k_ESPNTCEnableTimeout_mS_u16	61644
k_ESPNodeAbsentDiag_Cnt_str.Threshold	62621
k_ESPNodeAbsentDiag_Cnt_str.PStep	17876
k_ESPNodeAbsentDiag_Cnt_str.NStep	6024
k_ESPNodeAbsentTimeout_mS_u16	31924
k_EtatMTSigInvalidThresh_Cnt_u16	4539
k_EtatMTSigValidThresh_Cnt_u16	21784
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	45007
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	44864
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	41102
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	28584
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	20833
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	44926
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	50469
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	58566
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	59448
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	7474
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	18107
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	21250
k_ISDATDIRASentDiag_Cnt_str.Threshold	26541
k_ISDATDIRASentDiag_Cnt_str.PStep	31670

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.NStep	42297
k_ISDATDIRASentTimeout_mS_u16	37004
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	2395
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	9542
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	37224
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	31168
k_ISDYNAASChkSumValidThresh_Cnt_u16	9949
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	22802
k_ISDYNAASMsgCountValidThresh_Cnt_u16	48679
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	33780
k_ISDYNAASMsgLenValidThresh_Cnt_u16	43950
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	62540
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	27211
k_ISDYNABRChkSumValidThresh_Cnt_u16	9168
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	4446
k_ISDYNABRMsgCountValidThresh_Cnt_u16	44755
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	22224
k_ISDYNABRMsgLenValidThresh_Cnt_u16	61617
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	55726
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	11137
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	51415
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	32981
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	24619
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	28000
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	12415
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	50825
k_ISDYNVOLChkSumValidThresh_Cnt_u16	27315
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	59570
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	12305
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	37222
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	47992
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	5693
k_IgnOnTimeout_mS_u16	32853
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	204.376007
k_PowerCutVehSpdLowThresh_Kph_f32	115.9776
k_PowerCutVehSpdLowTimeout_mS_u16	23461
k_VBattMaxAAS_Volt_f32	29.8994999
k_VBattMaxBSI_Volt_f32	11.5360003
k_VBattMaxCAV_Volt_f32	18.3223
k_VBattMaxCMM388_Volt_f32	29.3132
k_VBattMaxCMM_Volt_f32	11.5495996
k_VBattMaxESP_Volt_f32	12.7905998
k_VBattMinAAS_Volt_f32	29.1650009
k_VBattMinBSI_Volt_f32	12.7905998
k_VBattMinCAV_Volt_f32	23.8337002
k_VBattMinCMM388_Volt_f32	12.4069004
k_VBattMinCMM_Volt_f32	2.07360005
k_VBattMinESP_Volt_f32	11.5495996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	16653
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	32038
k_VitesseVehicleBVRampValidThresh_Cnt_u16	43289
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	49501
k_VitesseVehicleBVSigValidThresh_Cnt_u16	17702
k_VitesseVehicleBVSpeedPassThresh_kph_f32	384.846008
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	17920
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	63341
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1589998336
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	0
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1436841216
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	98
target_SrlComInput_Per1_Batt_Volt_f32.value	1
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1279468288

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	156
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.951274991
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	211
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2111443712
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	124
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4100174592
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	620581632
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	103
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	933688064
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1415615232
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2737451776
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1275319040
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	146
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	192
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	239
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	668201728
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	57
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	128
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	163
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	239
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	145
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1143018240
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2620044032
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1849971456
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	175
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	183
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	251
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1364763392
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2398
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.3052724
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	836324
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	200.173096
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	9599

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	54885	54885	✔
AASNodeAbsentTimer_mS_M_u32	1436841216	1436841216	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	9543	9543	✔
AngleVolantMsgTimer_mS_M_u32	1849971456	1849971456	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	586.687683	586.687683	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	29222	29222	✔
BSINodeAbsentTimer_mS_M_u32	933688064	933688064	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1436841216	1436841216	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	50199	50199	✔
CMMNodeAbsentTimer_mS_M_u32	2737451776	2737451776	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	45598	45598	✔
CONSANGLECPK_HwDeg_M_f32	349.270996	349.270996 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	45599	45599	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	668201728	668201728	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	58177	58177	✔
CityParkInputInvalidCount_Cnt_M_u16	21480	21480	✔
CityParkInputMsgTimer_mS_M_u32	1275319040	1275319040	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1436841216	1436841216	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1436841216	1436841216	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1436841216	1436841216	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1436841216	1436841216	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1436841216	1436841216	✔
ESPNTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	14889	14889	✔
ESPNodeAbsentTimer_mS_M_u32	668201728	668201728	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	89	89	✔
EffacDefaultDiagTimer_mS_M_u32[1]	789	789	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	65	65	✔
ElecIntTimer_mS_M_u32[1]	6446	6446	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3058180864	3058180864	✔
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDATDIRASentFltAcc_Cnt_M_u16	16409	16409	✔
ISDATDIRASentTimer_mS_M_u32	1022853888	1022853888	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1436841216	1436841216	✔
IgnOnTimer_mS_M_u32	3516404480	3516404480	✔
IgnTimeOff_Sec_M_u32	248942597	248942597	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	211	211	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2111443712	2111443712	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	124	124	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4100174592	4100174592	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	74	74	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	620581632	620581632	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	103	103	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	933688064	933688064	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2185646848	2185646848	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2737451776	2737451776	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1275319040	1275319040	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	15	15	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	668201728	668201728	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	145	145	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1143018240	1143018240	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	59	59	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2620044032	2620044032	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1849971456	1849971456	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1364763392	1364763392	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	532.979004	532.979004	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	446.978088	446.978088	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	285.796204	285.796204	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	586.687683	586.687683	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	45598	45598	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	248942597	248942597	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	349.270996	349.270996 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	56.8833008	56.8833008	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
NodeAbsentNTCProcessing	3	NodeAbsentNTCProcessing	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	13	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	13	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.136 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4158994944
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	5019
AASNodeAbsentTimer_mS_M_u32	2220632576
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	34280
ANGLEVOLANTSigValidCount_Cnt_M_u16	44808
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	58264
AngleVolantMsgTimer_mS_M_u32	4158994944
AngleVolantValidCount_Cnt_M_u16	14273
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	584.426819
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	100395520
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3235539456
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2354567680
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4029061632
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	65103
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3212859904
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	61162
CAVNodeAbsentTimer_mS_M_u32	191023616
CDD_SrlComVehSpd_Kph_G_f32	302.94519
CMM388NTCEnableTimer_mS_M_u32	1833896448
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1081657856
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	35385
CMMNodeAbsentTimer_mS_M_u32	4052785664
CONSANGLECPKSigInvalidCount_Cnt_M_u16	62035
CONSANGLECPKSigValidCount_Cnt_M_u16	10436
CONSANGLECPK_Cnt_M_u16	27343
CONSANGLECPK_HwDeg_M_f32	-303.929291
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	27343
CPKVehicleSpeedMsgTimer_mS_M_u32	1115961856
CPKVehicleSpeedValidCount_Cnt_M_u16	15136
CityParkInputConsistentCount_Cnt_M_u16	40997
CityParkInputInvalidCount_Cnt_M_u16	46899
CityParkInputMsgTimer_mS_M_u32	2111443712
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	96479744
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	53759
ComputerRazGCTSigInvalidTimer_mS_M_u32	3954395648
ComputerRazGCTSigValidCount_Cnt_M_u16	41946
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	43727

Name	Input Value
DMDFCTCPKSigValidCount_Cnt_M_u16	44375
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	61722
DMDRELAXECPKSigValidCount_Cnt_M_u16	31674
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	39760
DateInvalidTimer_mS_M_u32	3235539456
DiagMuxOnAbsentTimer_mS_M_u32	1646197248
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4029061632
ESPNTCEnableTimer_mS_M_u32	3648858624
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	48469
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	56
EffacDefaultDiagTimer_mS_M_u32[1]	456
ElecIntCount_Cnt_M_u08	2
ElecIntTimer_mS_M_u32[0]	56565
ElecIntTimer_mS_M_u32[1]	787879
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1628592640
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	28378
EtatMTSigValidCount_Cnt_M_u16	13414
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	29573
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	35702
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	23661
ISDAT4V2BSI552MsgTimer_mS_M_u32	1978964480
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	4115
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	65512
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13414
ISDATBSI3F2MsgTimer_mS_M_u32	4176280064
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	18249
ISDATBSI412MsgLenValidCount_Cnt_M_u16	65358
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	28378
ISDATBSI412MsgTimer_mS_M_u32	3568515584
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	20893
ISDATBSI432MsgLenValidCount_Cnt_M_u16	1977
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	55083
ISDATDIRASentFltAcc_Cnt_M_u16	18335
ISDATDIRASentTimer_mS_M_u32	1115961856
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	8221
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	14273
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	27830
ISDYN2CMMMsgTimer_mS_M_u32	929507840
ISDYNAASChkSumInvalidCount_Cnt_M_u16	2765
ISDYNAASChkSumValidCount_Cnt_M_u16	56590
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	16296
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	19765
ISDYNAASMsgLenValidCount_Cnt_M_u16	7149
ISDYNAASMsgTimeValidCount_Cnt_M_u16	2765
ISDYNAASMsgTimer_mS_M_u32	99289600
ISDYNABRChkSumInvalidCount_Cnt_M_u16	42153
ISDYNABRChkSumValidCount_Cnt_M_u16	36370
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	21812
ISDYNABRMsgCountValidCount_Cnt_M_u16	63157
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	24506
ISDYNABRMsgLenValidCount_Cnt_M_u16	42347
ISDYNABRMsgTimeValidCount_Cnt_M_u16	27343
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	738
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1361
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13414
ISDYNCMM208MsgTimer_mS_M_u32	368110080
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2803
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1467
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	48015
ISDYNCMM388MsgTimer_mS_M_u32	4219374080
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	16673
ISDYNVOLChkSumValidCount_Cnt_M_u16	38418
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	23709

Name	Input Value
ISDYNVOLMsgCountValidCount_Cnt_M_u16	48549
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	8686
ISDYNVOLMsgLenValidCount_Cnt_M_u16	3902
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	35385
ISDYNVOLMsgTimer_mS_M_u32	2957986304
IgnOnTimer_mS_M_u32	2061666816
IgnTimeOff_Sec_M_u32	2188437249
ManVehSpd_Kph_M_f32	113.5718
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	97
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	129
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1709373952
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	85
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2912868864
PrevISDATBSI412MsgDLCError_Cnt_M_u08	83
PrevISDATBSI412MsgRxTime_MSec_M_u32	1382271488
PrevISDATBSI432MsgDLCError_Cnt_M_u08	193
PrevISDATBSI432MsgRxTime_MSec_M_u32	1213278720
PrevISDATDIRAMsgTxTime_MSec_M_u32	4057451008
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	75
PrevISDYN2CMMMsgRxTime_MSec_M_u32	229382656
PrevISDYNAASMsgDLCError_Cnt_M_u08	232
PrevISDYNAASMsgRxTime_MSec_M_u32	2912766464
PrevISDYNABRMsgDLCError_Cnt_M_u08	214
PrevISDYNABRMsgRxTime_MSec_M_u32	2669316608
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	107
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3138537984
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	28
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3881576960
PrevISDYNVOLMsgDLCError_Cnt_M_u08	13
PrevISDYNVOLMsgRxTime_MSec_M_u32	2091960832
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2759932416
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	310.2612
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	17667
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	62011
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	3868
VitesseVehicleBVRampValidCount_Cnt_M_u16	19732
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	33153
VitesseVehicleBVSigValidCount_Cnt_M_u16	23393
VitesseVehicleBV_Kph_M_f32	411.870392
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	48015
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	53544
VitesseVehiculeRoues_Kph_M_f32	483.921692
k_AASNTCEnableTimeout_mS_u16	17326
k_AASNodeAbsentDiag_Cnt_str.Threshold	2866
k_AASNodeAbsentDiag_Cnt_str.PStep	7021
k_AASNodeAbsentDiag_Cnt_str.NStep	28079
k_AASNodeAbsentTimeout_mS_u16	35396
k_AASNodeTimeout_mS_u16	54587

Name	Input Value
k_ABSNodeTimeout_mS_u16	1668
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	56672
k_ANGLEVOLANTSigValidThresh_Cnt_u16	61372
k_AngleVolantInvalidThresh_Cnt_u16	58603
k_AngleVolantValidThresh_Cnt_u16	46899
k_BSI552MsgTimeout_mS_u16	26391
k_BSINTCEnableTimeout_mS_u16	58837
k_BSINodeAbsentDiag_Cnt_str.Threshold	801
k_BSINodeAbsentDiag_Cnt_str.PStep	836
k_BSINodeAbsentDiag_Cnt_str.NStep	898
k_BSINodeAbsentTimeout_mS_u16	10704
k_BSINodeTimeout_mS_u16	55083
k_BattOvHi_Volt_f32	2
k_BattOvLo_Volt_f32	23.6919994
k_BattUvHi_Volt_f32	15.1864004
k_BattUvLo_Volt_f32	0
k_CAVNTCEnableTimeout_mS_u16	54073
k_CAVNodeAbsentDiag_Cnt_str.Threshold	43246
k_CAVNodeAbsentDiag_Cnt_str.PStep	64274
k_CAVNodeAbsentDiag_Cnt_str.NStep	57282
k_CAVNodeAbsentTimeout_mS_u16	16824
k_CAVNodeTimeout_mS_u16	33519
k_CMM388MsgTimeout_mS_u16	13979
k_CMM388NTCEnableTimeout_mS_u16	47159
k_CMMNTCEnableTimeout_mS_u16	32843
k_CMMNodeAbsentDiag_Cnt_str.Threshold	64500
k_CMMNodeAbsentDiag_Cnt_str.PStep	51350
k_CMMNodeAbsentDiag_Cnt_str.NStep	14406
k_CMMNodeAbsentTimeout_mS_u16	59588
k_CONSANGLECPKMax_HwDeg_f32	301.392487
k_CONSANGLECPKMin_HwDeg_f32	-655.547607
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	24207
k_CONSANGLECPKSigValidThresh_Cnt_u16	46120
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	57169
k_CPKVehicleSpeedValidThresh_Cnt_u16	37716
k_CityParkInputInvalidThresh_Cnt_u16	23359
k_CityParkInputValidThresh_Cnt_u16	40997
k_ComputerRazGCTSigValidThresh_Cnt_u16	63369
k_CptTemporelSigValidThresh_Cnt_u16	46046
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	33466
k_DMDFCTCPKSigValidThresh_Cnt_u16	2155
k_DMDFCTCPKValidCount_Cnt_u16	60183
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	27830
k_DMDRELAXECPKSigValidThresh_Cnt_u16	56958
k_DMDRelaxeConsistentThresh_Cnt_u16	62100
k_DateValidThresh_Cnt_u16	23661
k_DefaultVehSpd_Kph_f32	193.266998
k_DiagMuxOnAbsentTimeout_mS_u16	0
k_EMNodeTimeout_mS_u16	23728
k_ESPNTCEnableTimeout_mS_u16	49542
k_ESPNodeAbsentDiag_Cnt_str.Threshold	46537
k_ESPNodeAbsentDiag_Cnt_str.PStep	46235
k_ESPNodeAbsentDiag_Cnt_str.NStep	63034
k_ESPNodeAbsentTimeout_mS_u16	56460
k_EtatMTSigInvalidThresh_Cnt_u16	11192
k_EtatMTSigValidThresh_Cnt_u16	37473
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	52540
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	20393
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	56382
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	11056
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	9925
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	38061
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	46650
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	38934
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	22785
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	31123
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	56759
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	50980
k_ISDATDIRASentDiag_Cnt_str.Threshold	5619
k_ISDATDIRASentDiag_Cnt_str.PStep	47502
k_ISDATDIRASentDiag_Cnt_str.NStep	46845
k_ISDATDIRASentTimeout_mS_u16	13125
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	18457

Name	Input Value
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58264
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	20402
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	18345
k_ISDYNAASChkSumValidThresh_Cnt_u16	28946
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	30772
k_ISDYNAASMsgCountValidThresh_Cnt_u16	22965
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	63757
k_ISDYNAASMsgLenValidThresh_Cnt_u16	5535
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	388
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	47496
k_ISDYNABRChkSumValidThresh_Cnt_u16	23993
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	8527
k_ISDYNABRMsgCountValidThresh_Cnt_u16	55727
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	27961
k_ISDYNABRMsgLenValidThresh_Cnt_u16	57429
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	34078
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	9575
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	60578
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	61994
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	43240
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	4616
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	33131
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	15244
k_ISDYNVOLChkSumValidThresh_Cnt_u16	45009
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	15442
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	9590
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	58998
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	26882
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	33011
k_IgnOnTimeout_mS_u16	15912
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	39.2890015
k_PowerCutVehSpdLowThresh_Kph_f32	24.4843006
k_PowerCutVehSpdLowTimeout_mS_u16	19002
k_VBattMaxAAS_Volt_f32	19.3453999
k_VBattMaxBSI_Volt_f32	27.5785999
k_VBattMaxCAV_Volt_f32	6.34940004
k_VBattMaxCMM388_Volt_f32	21.3945007
k_VBattMaxCMM_Volt_f32	21.9302006
k_VBattMaxESP_Volt_f32	28.2299004
k_VBattMinAAS_Volt_f32	19.5832996
k_VBattMinBSI_Volt_f32	28.2299004
k_VBattMinCAV_Volt_f32	14.6620998
k_VBattMinCMM388_Volt_f32	10.335
k_VBattMinCMM_Volt_f32	7.14249992
k_VBattMinESP_Volt_f32	21.9302006
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	59651
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	21879
k_VitesseVehicleBVRampValidThresh_Cnt_u16	65437
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	63762
k_VitesseVehicleBVSigValidThresh_Cnt_u16	20086
k_VitesseVehicleBVSpeedPassThresh_kph_f32	527.120605
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	37354
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	61026
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3235539456
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	0
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	314926080
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	28
target_SrlComInput_Per1_Batt_Volt_f32.value	1
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1260476928
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	250
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.804778218
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	188
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4263283200
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1224714752
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2779957760
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2620779008
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3028879872
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	255
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1990994432
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1788824064
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	37
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	99
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	116
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	179
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	237
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3215911424
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	55
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	100
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	141
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	155
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	167
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	207
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	96
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2269612544
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	766159360
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2782775808
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	67
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	74
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	149
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	153
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	216
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1910561280
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1466
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.464262754
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	677125
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	56.1475983
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	44909

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	314926080	314926080	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1788824064	1788824064	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	58265	58265	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AngleVolantMsgTimer_mS_M_u32	2782775808	2782775808	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	584.426819	584.426819	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	314926080	314926080	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	314926080	314926080	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	314926080	314926080	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	314926080	314926080	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	64205	64205	✔
BSINodeAbsentTimer_mS_M_u32	2620779008	2620779008	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	314926080	314926080	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	314926080	314926080	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	314926080	314926080	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	314926080	314926080	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	20979	20979	✔
CMMNodeAbsentTimer_mS_M_u32	1990994432	1990994432	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	27343	27343	✔
CONSANGLECPK_HwDeg_M_f32	-303.929291	-303.929291 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	27344	27344	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3215911424	3215911424	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	40997	40997	✔
CityParkInputInvalidCount_Cnt_M_u16	46899	46899	✔
CityParkInputMsgTimer_mS_M_u32	1788824064	1788824064	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	314926080	314926080	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	314926080	314926080	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	314926080	314926080	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	314926080	314926080	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	314926080	314926080	✔
ESPNTCEnableTimer_mS_M_u32	314926080	314926080	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3215911424	3215911424	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	56	56	✔
EffacDefaultDiagTimer_mS_M_u32[1]	456	456	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	56565	56565	✔
ElecIntTimer_mS_M_u32[1]	787879	787879	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1628592640	1628592640	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	314926080	314926080	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	314926080	314926080	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	314926080	314926080	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	314926080	314926080	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	314926080	314926080	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	314926080	314926080	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	314926080	314926080	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	314926080	314926080	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	314926080	314926080	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	314926080	314926080	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	314926080	314926080	✔
IgnOnTimer_mS_M_u32	2061666816	2061666816	✔
IgnTimeOff_Sec_M_u32	2188437249	2188437249	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	188	188	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4263283200	4263283200	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	81	81	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1224714752	1224714752	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	180	180	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2779957760	2779957760	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI432MsgDLCError_Cnt_M_u08	109	109	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2620779008	2620779008	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3028879872	3028879872	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	255	255	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1990994432	1990994432	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	233	233	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1788824064	1788824064	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	105	105	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3215911424	3215911424	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	96	96	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2269612544	2269612544	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	240	240	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	766159360	766159360	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	15	15	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2782775808	2782775808	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1910561280	1910561280	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	310.2612	310.2612	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	411.870392	411.870392	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	483.921692	483.921692	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	584.426819	584.426819	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	27343	27343	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2188437249	2188437249	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-303.929291	-303.929291 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	193.266998	193.266998	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	3	NodeAbsentNTCProcessing	3	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.137 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	290919680
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	47155
AASNodeAbsentTimer_mS_M_u32	867321088
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	13134
ANGLEVOLANTSigValidCount_Cnt_M_u16	1452
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	31804
AngleVolantMsgTimer_mS_M_u32	290919680
AngleVolantValidCount_Cnt_M_u16	3137
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	686.151367
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3721594112
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1194820864
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3867096320
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1712518400
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	9753
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2399515904
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	10439
CAVNodeAbsentTimer_mS_M_u32	2166252800
CDD_SrlComVehSpd_Kph_G_f32	314.819
CMM388NTCEnableTimer_mS_M_u32	1549378816
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3118228736
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	11675
CMMNodeAbsentTimer_mS_M_u32	2312434944
CONSANGLECPKSigInvalidCount_Cnt_M_u16	19722
CONSANGLECPKSigValidCount_Cnt_M_u16	14201
CONSANGLECPK_Cnt_M_u16	23896
CONSANGLECPK_HwDeg_M_f32	452.051605
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	23896
CPKVehicleSpeedMsgTimer_mS_M_u32	1836717312
CPKVehicleSpeedValidCount_Cnt_M_u16	32973
CityParkInputConsistentCount_Cnt_M_u16	25365
CityParkInputInvalidCount_Cnt_M_u16	58093
CityParkInputMsgTimer_mS_M_u32	4263283200
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1065764096
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	3335

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3257722112
ComputerRazGCTSigValidCount_Cnt_M_u16	27638
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	30745
DMDFCTCPKSigValidCount_Cnt_M_u16	24128
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	14776
DMDRELAXECPKSigValidCount_Cnt_M_u16	59286
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	34323
DateInvalidTimer_mS_M_u32	1194820864
DiagMuxOnAbsentTimer_mS_M_u32	3920221440
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1712518400
ESPNTCEnableTimer_mS_M_u32	4165944576
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	0
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	99
EffacDefaultDiagTimer_mS_M_u32[1]	759
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	55656
ElecIntTimer_mS_M_u32[1]	87788
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1917826304
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	38071
EtatMTSigValidCount_Cnt_M_u16	16850
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	4468
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	22371
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	10494
ISDAT4V2BSI552MsgTimer_mS_M_u32	2359883008
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	52875
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	7374
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	16850
ISDATBSI3F2MsgTimer_mS_M_u32	3711948032
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	53737
ISDATBSI412MsgLenValidCount_Cnt_M_u16	34715
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	38071
ISDATBSI412MsgTimer_mS_M_u32	854398208
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	26479
ISDATBSI432MsgLenValidCount_Cnt_M_u16	33498
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	46084
ISDATDIRASentFltAcc_Cnt_M_u16	12968
ISDATDIRASentTimer_mS_M_u32	1836717312
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	62830
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	3137
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36452
ISDYN2CMMMsgTimer_mS_M_u32	110183680
ISDYNAASChkSumInvalidCount_Cnt_M_u16	6813
ISDYNAASChkSumValidCount_Cnt_M_u16	29084
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	20620
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	63974
ISDYNAASMsgLenValidCount_Cnt_M_u16	15229
ISDYNAASMsgTimeValidCount_Cnt_M_u16	6813
ISDYNAASMsgTimer_mS_M_u32	42312960
ISDYNABRChkSumInvalidCount_Cnt_M_u16	5257
ISDYNABRChkSumValidCount_Cnt_M_u16	50704
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	38760
ISDYNABRMsgCountValidCount_Cnt_M_u16	32935
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	24789
ISDYNABRMsgLenValidCount_Cnt_M_u16	7556
ISDYNABRMsgTimeValidCount_Cnt_M_u16	23896
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	739
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1363
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	16850
ISDYNCMM208MsgTimer_mS_M_u32	3253994752
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2807
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1469
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	14551

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3486196992
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	6304
ISDYNVOLChkSumValidCount_Cnt_M_u16	42895
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	6831
ISDYNVOLMsgCountValidCount_Cnt_M_u16	58710
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	18491
ISDYNVOLMsgLenValidCount_Cnt_M_u16	36362
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	11675
ISDYNVOLMsgTimer_mS_M_u32	3831031040
IgnOnTimer_mS_M_u32	3785303296
IgnTimeOff_Sec_M_u32	968610036
ManVehSpd_Kph_M_f32	533.617615
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	99
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	42
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3999126784
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	188
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1588212992
PrevISDATBSI412MsgDLCError_Cnt_M_u08	97
PrevISDATBSI412MsgRxTime_MSec_M_u32	4028327168
PrevISDATBSI432MsgDLCError_Cnt_M_u08	245
PrevISDATBSI432MsgRxTime_MSec_M_u32	4224926976
PrevISDATDIRAMsgTxTime_MSec_M_u32	3787416832
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	96
PrevISDYN2CMMMsgRxTime_MSec_M_u32	58881280
PrevISDYNAASMsgDLCError_Cnt_M_u08	225
PrevISDYNAASMsgRxTime_MSec_M_u32	2758731008
PrevISDYNABRMsgDLCError_Cnt_M_u08	245
PrevISDYNABRMsgRxTime_MSec_M_u32	1425483008
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	214
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2416960768
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	251
PrevISDYNCMM388MsgRxTime_MSec_M_u32	179455232
PrevISDYNVOLMsgDLCError_Cnt_M_u08	83
PrevISDYNVOLMsgRxTime_MSec_M_u32	3845416192
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2072188160
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	646.679504
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	51836
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	28819
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	4145
VitesseVehicleBVRampValidCount_Cnt_M_u16	1032
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	58499
VitesseVehicleBVSigValidCount_Cnt_M_u16	42145
VitesseVehicleBV_Kph_M_f32	154.692398
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	14551
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	9677
VitesseVehiculeRoues_Kph_M_f32	516.681702
k_AASNTCEnableTimeout_mS_u16	3771
k_AASNodeAbsentDiag_Cnt_str.Threshold	13446

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	20078
k_AASNodeAbsentDiag_Cnt_str.NStep	17790
k_AASNodeAbsentTimeout_mS_u16	57528
k_AASNodeTimeout_mS_u16	51091
k_ABSNodeTimeout_mS_u16	30970
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	36902
k_ANGLEVOLANTSigValidThresh_Cnt_u16	38609
k_AngleVolantInvalidThresh_Cnt_u16	13124
k_AngleVolantValidThresh_Cnt_u16	58093
k_BSI552MsgTimeout_mS_u16	57344
k_BSINTCEnableTimeout_mS_u16	35527
k_BSINodeAbsentDiag_Cnt_str.Threshold	914
k_BSINodeAbsentDiag_Cnt_str.PStep	942
k_BSINodeAbsentDiag_Cnt_str.NStep	1740
k_BSINodeAbsentTimeout_mS_u16	35220
k_BSINodeTimeout_mS_u16	46084
k_BattOvHi_Volt_f32	4.86520004
k_BattOvLo_Volt_f32	18.1753998
k_BattUvHi_Volt_f32	4.81290007
k_BattUvLo_Volt_f32	17.1763
k_CAVNTCEnableTimeout_mS_u16	9947
k_CAVNodeAbsentDiag_Cnt_str.Threshold	33548
k_CAVNodeAbsentDiag_Cnt_str.PStep	12663
k_CAVNodeAbsentDiag_Cnt_str.NStep	14720
k_CAVNodeAbsentTimeout_mS_u16	59485
k_CAVNodeTimeout_mS_u16	2870
k_CMM388MsgTimeout_mS_u16	20275
k_CMM388NTCEnableTimeout_mS_u16	14943
k_CMMNTCEnableTimeout_mS_u16	24035
k_CMMNodeAbsentDiag_Cnt_str.Threshold	43168
k_CMMNodeAbsentDiag_Cnt_str.PStep	14930
k_CMMNodeAbsentDiag_Cnt_str.NStep	7707
k_CMMNodeAbsentTimeout_mS_u16	20217
k_CONSANGLECPKMax_HwDeg_f32	215.539902
k_CONSANGLECPKMin_HwDeg_f32	-186.941605
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	20439
k_CONSANGLECPKSigValidThresh_Cnt_u16	31949
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	33105
k_CPKVehicleSpeedValidThresh_Cnt_u16	55752
k_CityParkInputInvalidThresh_Cnt_u16	51399
k_CityParkInputValidThresh_Cnt_u16	25365
k_ComputerRazGCTSigValidThresh_Cnt_u16	28713
k_CptTemporelSigValidThresh_Cnt_u16	22764
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	63445
k_DMDFCTCPKSigValidThresh_Cnt_u16	62596
k_DMDFCTCPKValidCount_Cnt_u16	32705
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	36452
k_DMDRELAXECPKSigValidThresh_Cnt_u16	9931
k_DMDRelaxeConsistentThresh_Cnt_u16	49801
k_DateValidThresh_Cnt_u16	10494
k_DefaultVehSpd_Kph_f32	153.725403
k_DiagMuxOnAbsentTimeout_mS_u16	52422
k_EMNodeTimeout_mS_u16	49651
k_ESPNTCEnableTimeout_mS_u16	8435
k_ESPNodeAbsentDiag_Cnt_str.Threshold	9473
k_ESPNodeAbsentDiag_Cnt_str.PStep	12578
k_ESPNodeAbsentDiag_Cnt_str.NStep	10272
k_ESPNodeAbsentTimeout_mS_u16	37793
k_EtatMTSigInvalidThresh_Cnt_u16	31580
k_EtatMTSigValidThresh_Cnt_u16	46371
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	9104
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	6667
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	21194
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	12596
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	23607
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	31165
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	60824
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	34243
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	57667
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	16652
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	29279
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	35674
k_ISDATDIRASentDiag_Cnt_str.Threshold	14460

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	36482
k_ISDATDIRASentDiag_Cnt_str.NStep	2126
k_ISDATDIRASentTimeout_mS_u16	55477
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	7291
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	31804
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	9839
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	11145
k_ISDYNAASChkSumValidThresh_Cnt_u16	7440
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	11880
k_ISDYNAASMsgCountValidThresh_Cnt_u16	22439
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	42845
k_ISDYNAASMsgLenValidThresh_Cnt_u16	38503
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	33145
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	2923
k_ISDYNABRChkSumValidThresh_Cnt_u16	44186
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	48409
k_ISDYNABRMsgCountValidThresh_Cnt_u16	57783
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	33947
k_ISDYNABRMsgLenValidThresh_Cnt_u16	26886
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	23402
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	47440
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	34270
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	60614
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	51790
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	56492
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	25669
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	49440
k_ISDYNVOLChkSumValidThresh_Cnt_u16	16914
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	35087
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	36836
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	40419
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	5118
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	21356
k_IgnOnTimeout_mS_u16	10572
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	6.15950012
k_PowerCutVehSpdLowThresh_Kph_f32	122.573601
k_PowerCutVehSpdLowTimeout_mS_u16	11031
k_VBattMaxAAS_Volt_f32	15.1213999
k_VBattMaxBSI_Volt_f32	31.9941006
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	8.10410023
k_VBattMaxCMM_Volt_f32	32
k_VBattMaxESP_Volt_f32	16.7952995
k_VBattMinAAS_Volt_f32	20.3052006
k_VBattMinBSI_Volt_f32	16.7952995
k_VBattMinCAV_Volt_f32	31.8141003
k_VBattMinCMM388_Volt_f32	28.6177006
k_VBattMinCMM_Volt_f32	8.77219963
k_VBattMinESP_Volt_f32	32
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	25021
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	47647
k_VitesseVehicleBVRampValidThresh_Cnt_u16	12719
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	32399
k_VitesseVehicleBVSigValidThresh_Cnt_u16	56354
k_VitesseVehicleBVSpeedPassThresh_kph_f32	22.3805008
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	16327
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	55326
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1194820864
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	131
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	55180
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3453916928
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	251
target_SrlComInput_Per1_Batt_Volt_f32.value	16.2917004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2955064576
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	195
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.847126365
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	65
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3220251904
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3553084672
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4063126784
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	237
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2200241408
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4004226304
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2629977344
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4117292288
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	78
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	94
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	141
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	171
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	183
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1018823936
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	10
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	46
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	94
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	195
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2423268608
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	102
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2445722880
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	159
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1571644672
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	23
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	115
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	131
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	151
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	177
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2581869824
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3018
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.121336579
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	620227
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	198.833603
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	45886

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	13446	13446	✔
AASNodeAbsentTimer_mS_M_u32	3453916928	3453916928	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	31804	31804	✔
AngleVolantMsgTimer_mS_M_u32	3453916928	3453916928	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	686.151367	686.151367	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	914	914	✔
BSINodeAbsentTimer_mS_M_u32	3453916928	3453916928	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3453916928	3453916928	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	43168	43168	✔
CMMNodeAbsentTimer_mS_M_u32	3453916928	3453916928	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	23896	23896	✔
CONSANGLECPK_HwDeg_M_f32	452.051605	452.051605 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	23896	23896	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1836717312	1836717312	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	32973	32973	✔
CityParkInputConsistentCount_Cnt_M_u16	25365	25365	✔
CityParkInputInvalidCount_Cnt_M_u16	58093	58093	✔
CityParkInputMsgTimer_mS_M_u32	3453916928	3453916928	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3453916928	3453916928	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3453916928	3453916928	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3453916928	3453916928	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3453916928	3453916928	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3453916928	3453916928	✔
ESPNTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3453916928	3453916928	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	99	99	✔
EffacDefaultDiagTimer_mS_M_u32[1]	759	759	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	55656	55656	✔
ElecIntTimer_mS_M_u32[1]	87788	87788	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3453916928	3453916928	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3453916928	3453916928	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3453916928	3453916928	✔
IgnOnTimer_mS_M_u32	3453916928	3453916928	✔
IgnTimeOff_Sec_M_u32	968610036	968610036	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	65	65	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3220251904	3220251904	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	215	215	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3553084672	3553084672	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	67	67	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4063126784	4063126784	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	237	237	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2200241408	2200241408	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3787416832	3787416832	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	158	158	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2629977344	2629977344	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	117	117	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4117292288	4117292288	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	29	29	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1018823936	1018823936	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	195	195	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2423268608	2423268608	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	102	102	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2445722880	2445722880	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	159	159	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1571644672	1571644672	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2581869824	2581869824	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	646.679504	646.679504	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	154.692398	154.692398	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	516.681702	516.681702	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	686.151367	686.151367	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	23896	23896	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	968610036	968610036	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	452.051605	452.051605 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.138 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1915585536
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	36760
AASNodeAbsentTimer_mS_M_u32	3017536512
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	43080
ANGLEVOLANTSigValidCount_Cnt_M_u16	18412
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	42877
AngleVolantMsgTimer_mS_M_u32	1915585536
AngleVolantValidCount_Cnt_M_u16	20975
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	465.397247
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	679064576
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	508310528
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	993338368
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3145327616
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	48103
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2074190848
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	13915
CAVNodeAbsentTimer_mS_M_u32	605524992
CDD_SrlComVehSpd_Kph_G_f32	351.425507
CMM388NTCEnableTimer_mS_M_u32	2405815296
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	4057830400
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	41887
CMMNodeAbsentTimer_mS_M_u32	3627279360
CONSANGLECPKSigInvalidCount_Cnt_M_u16	15890
CONSANGLECPKSigValidCount_Cnt_M_u16	54662
CONSANGLECPK_Cnt_M_u16	40937
CONSANGLECPK_HwDeg_M_f32	-644.093079
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	40937
CPKVehicleSpeedMsgTimer_mS_M_u32	2848228352
CPKVehicleSpeedValidCount_Cnt_M_u16	6225
CityParkInputConsistentCount_Cnt_M_u16	40307
CityParkInputInvalidCount_Cnt_M_u16	52970

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	3220251904
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3764384768
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	57628
ComputerRazGCTSigInvalidTimer_mS_M_u32	3136033792
ComputerRazGCTSigValidCount_Cnt_M_u16	18128
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	48998
DMDFCTCPKSigValidCount_Cnt_M_u16	17330
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	48394
DMDRELAXECPKSigValidCount_Cnt_M_u16	51758
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	63223
DateInvalidTimer_mS_M_u32	508310528
DiagMuxOnAbsentTimer_mS_M_u32	2754954240
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3145327616
ESPNTCEnableTimer_mS_M_u32	436532224
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	65535
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	1121
EffacDefaultDiagTimer_mS_M_u32[1]	3038707200
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	2323
ElecIntTimer_mS_M_u32[1]	454647
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2042864640
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	12107
EtatMTSigValidCount_Cnt_M_u16	11963
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	6356
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	40392
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	23416
ISDAT4V2BSI552MsgTimer_mS_M_u32	532145152
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	10575
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	58695
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	11963
ISDATBSI3F2MsgTimer_mS_M_u32	2708685824
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	9271
ISDATBSI412MsgLenValidCount_Cnt_M_u16	27103
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	12107
ISDATBSI412MsgTimer_mS_M_u32	3849028608
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	17955
ISDATBSI432MsgLenValidCount_Cnt_M_u16	15011
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	51364
ISDATDIRASentFltAcc_Cnt_M_u16	56504
ISDATDIRASentTimer_mS_M_u32	2848228352
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	44967
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	20975
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	26757
ISDYN2CMMMsgTimer_mS_M_u32	2000614400
ISDYNAASChkSumInvalidCount_Cnt_M_u16	36954
ISDYNAASChkSumValidCount_Cnt_M_u16	8733
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	28942
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	65278
ISDYNAASMsgLenValidCount_Cnt_M_u16	12538
ISDYNAASMsgTimeValidCount_Cnt_M_u16	36954
ISDYNAASMsgTimer_mS_M_u32	1289868288
ISDYNABRChkSumInvalidCount_Cnt_M_u16	19476
ISDYNABRChkSumValidCount_Cnt_M_u16	60992
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	1529
ISDYNABRMsgCountValidCount_Cnt_M_u16	57596
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	61105
ISDYNABRMsgLenValidCount_Cnt_M_u16	3941
ISDYNABRMsgTimeValidCount_Cnt_M_u16	40937
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	740
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1365

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	11963
ISDYNCMM208MsgTimer_mS_M_u32	1075229696
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2811
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1471
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	42029
ISDYNCMM388MsgTimer_mS_M_u32	3675345920
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	45904
ISDYNVOLChkSumValidCount_Cnt_M_u16	23876
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	44964
ISDYNVOLMsgCountValidCount_Cnt_M_u16	34416
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	44672
ISDYNVOLMsgLenValidCount_Cnt_M_u16	46036
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	41887
ISDYNVOLMsgTimer_mS_M_u32	73929728
IgnOnTimer_mS_M_u32	4120204288
IgnTimeOff_Sec_M_u32	1781026446
ManVehSpd_Kph_M_f32	86.6545029
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	101
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1712931840
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	31
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1051993088
PrevISDATBSI412MsgDLCError_Cnt_M_u08	89
PrevISDATBSI412MsgRxTime_MSec_M_u32	186684416
PrevISDATBSI432MsgDLCError_Cnt_M_u08	5
PrevISDATBSI432MsgRxTime_MSec_M_u32	528020480
PrevISDATDIRAMsgTxTime_MSec_M_u32	3325334528
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	165
PrevISDYN2CMMMsgRxTime_MSec_M_u32	19620864
PrevISDYNAASMsgDLCError_Cnt_M_u08	32
PrevISDYNAASMsgRxTime_MSec_M_u32	2619741184
PrevISDYNABRMsgDLCError_Cnt_M_u08	64
PrevISDYNABRMsgRxTime_MSec_M_u32	4220343296
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	191
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2638418944
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	170
PrevISDYNCMM388MsgRxTime_MSec_M_u32	786166784
PrevISDYNVOLMsgDLCError_Cnt_M_u08	30
PrevISDYNVOLMsgRxTime_MSec_M_u32	3486880768
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3819537408
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	263.439087
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	25916
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	27064
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	43037
VitesseVehicleBVRampValidCount_Cnt_M_u16	50009
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	43177
VitesseVehicleBVSigValidCount_Cnt_M_u16	32525
VitesseVehicleBV_Kph_M_f32	331.858795

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	42029
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	21513
VitesseVehiculeRoues_Kph_M_f32	136.821304
k_AASNTCEnableTimeout_mS_u16	55232
k_AASNodeAbsentDiag_Cnt_str.Threshold	20822
k_AASNodeAbsentDiag_Cnt_str.PStep	33751
k_AASNodeAbsentDiag_Cnt_str.NStep	13598
k_AASNodeAbsentTimeout_mS_u16	28810
k_AASNodeTimeout_mS_u16	25784
k_ABSNodeTimeout_mS_u16	32963
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	26622
k_ANGLEVOLANTSigValidThresh_Cnt_u16	39614
k_AngleVolantInvalidThresh_Cnt_u16	20837
k_AngleVolantValidThresh_Cnt_u16	52970
k_BSI552MsgTimeout_mS_u16	45424
k_BSINTCEnableTimeout_mS_u16	15387
k_BSINodeAbsentDiag_Cnt_str.Threshold	1027
k_BSINodeAbsentDiag_Cnt_str.PStep	1048
k_BSINodeAbsentDiag_Cnt_str.NStep	2582
k_BSINodeAbsentTimeout_mS_u16	57205
k_BSINodeTimeout_mS_u16	51364
k_BattOvHi_Volt_f32	10.8519001
k_BattOvLo_Volt_f32	21.1630001
k_BattUvHi_Volt_f32	15.3886003
k_BattUvLo_Volt_f32	15.7178001
k_CAVNTCEnableTimeout_mS_u16	15136
k_CAVNodeAbsentDiag_Cnt_str.Threshold	52894
k_CAVNodeAbsentDiag_Cnt_str.PStep	13525
k_CAVNodeAbsentDiag_Cnt_str.NStep	23153
k_CAVNodeAbsentTimeout_mS_u16	53145
k_CAVNodeTimeout_mS_u16	45966
k_CMM388MsgTimeout_mS_u16	51864
k_CMM388NTCEnableTimeout_mS_u16	47380
k_CMMNTCEnableTimeout_mS_u16	56135
k_CMMNodeAbsentDiag_Cnt_str.Threshold	41448
k_CMMNodeAbsentDiag_Cnt_str.PStep	26123
k_CMMNodeAbsentDiag_Cnt_str.NStep	33321
k_CMMNodeAbsentTimeout_mS_u16	34949
k_CONSANGLECPKMax_HwDeg_f32	342.438507
k_CONSANGLECPKMin_HwDeg_f32	-329.211914
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	24365
k_CONSANGLECPKSigValidThresh_Cnt_u16	20233
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	44926
k_CPKVehicleSpeedValidThresh_Cnt_u16	18586
k_CityParkInputInvalidThresh_Cnt_u16	42842
k_CityParkInputValidThresh_Cnt_u16	40307
k_ComputerRazGCTSigValidThresh_Cnt_u16	15477
k_CptTemporelSigValidThresh_Cnt_u16	10477
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	10673
k_DMDFCTCPKSigValidThresh_Cnt_u16	35429
k_DMDFCTCPKValidCount_Cnt_u16	20207
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	26757
k_DMDRELAXECPKSigValidThresh_Cnt_u16	54801
k_DMDRelaxeConsistentThresh_Cnt_u16	31447
k_DateValidThresh_Cnt_u16	23416
k_DefaultVehSpd_Kph_f32	43.5219994
k_DiagMuxOnAbsentTimeout_mS_u16	35231
k_EMNodeTimeout_mS_u16	50007
k_ESPNTCEnableTimeout_mS_u16	64983
k_ESPNodeAbsentDiag_Cnt_str.Threshold	44837
k_ESPNodeAbsentDiag_Cnt_str.PStep	53498
k_ESPNodeAbsentDiag_Cnt_str.NStep	6264
k_ESPNodeAbsentTimeout_mS_u16	23181
k_EtatMTSigInvalidThresh_Cnt_u16	9115
k_EtatMTSigValidThresh_Cnt_u16	11527
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	33985
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	10257
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	57940
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	58708
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	2828
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	31931
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	38824
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	5608

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	10407
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	50381
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	6037
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	19683
k_ISDATDIRASentDiag_Cnt_str.Threshold	47308
k_ISDATDIRASentDiag_Cnt_str.PStep	21554
k_ISDATDIRASentDiag_Cnt_str.NStep	61574
k_ISDATDIRASentTimeout_mS_u16	44944
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	23936
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	42877
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	56675
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	1812
k_ISDYNAASChkSumValidThresh_Cnt_u16	59712
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	16633
k_ISDYNAASMsgCountValidThresh_Cnt_u16	23548
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	58264
k_ISDYNAASMsgLenValidThresh_Cnt_u16	18492
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	31430
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	50927
k_ISDYNABRChkSumValidThresh_Cnt_u16	14883
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	63207
k_ISDYNABRMsgCountValidThresh_Cnt_u16	40907
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	40607
k_ISDYNABRMsgLenValidThresh_Cnt_u16	14367
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	48818
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	59584
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7256
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	33055
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	58184
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	49900
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	43746
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	62098
k_ISDYNVOLChkSumValidThresh_Cnt_u16	54906
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	15364
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	57540
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	50119
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	26679
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	5166
k_IgnOnTimeout_mS_u16	27150
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	10.7198
k_PowerCutVehSpdLowThresh_Kph_f32	213.4776
k_PowerCutVehSpdLowTimeout_mS_u16	62124
k_VBattMaxAAS_Volt_f32	17.8897991
k_VBattMaxBSI_Volt_f32	7.55499983
k_VBattMaxCAV_Volt_f32	31.8299007
k_VBattMaxCMM388_Volt_f32	8.55210018
k_VBattMaxCMM_Volt_f32	20.7858009
k_VBattMaxESP_Volt_f32	26.8868008
k_VBattMinAAS_Volt_f32	17.6460991
k_VBattMinBSI_Volt_f32	26.8868008
k_VBattMinCAV_Volt_f32	25.8841
k_VBattMinCMM388_Volt_f32	18.0065002
k_VBattMinCMM_Volt_f32	0.811399996
k_VBattMinESP_Volt_f32	20.7858009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	5562
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	13138
k_VitesseVehicleBVRampValidThresh_Cnt_u16	27300
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	55364
k_VitesseVehicleBVSigValidThresh_Cnt_u16	42572
k_VitesseVehicleBVSpeedPassThresh_kph_f32	88.4785004
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	61787
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	7959
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	508310528
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	210
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	43468
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3038707200
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	170

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	18.0870991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3427443712
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	44
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.672848463
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	580867072
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	161182720
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	283612160
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	8631296
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2691683328
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	217
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3098276864
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	288887808
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	45
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	55
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1740944384
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	70
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	97
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	111
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	155
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1830966272
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2342417408
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2322240512
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	43
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	82
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	109
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4110820352
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	4020
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0752352402
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	52861
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	238.947601
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	13046

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	20822	20822	✔
AASNodeAbsentTimer_mS_M_u32	3038707200	3038707200	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3038707200	3038707200	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	465.397247	465.397247	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	1027	1027	✔
BSINodeAbsentTimer_mS_M_u32	3038707200	3038707200	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3038707200	3038707200	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	41448	41448	✔
CMMNodeAbsentTimer_mS_M_u32	3038707200	3038707200	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	40937	40937	✔
CONSANGLECPK_HwDeg_M_f32	-644.093079	-644.093079 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3038707200	3038707200	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3038707200	3038707200	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3038707200	3038707200	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3038707200	3038707200	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3038707200	3038707200	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3038707200	3038707200	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3038707200	3038707200	✔
ESPNTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3038707200	3038707200	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1121	1121	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3038707200	3038707200	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	3038707200	3038707200	✔
ElecIntTimer_mS_M_u32[1]	454647	454647	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3038707200	3038707200	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3038707200	3038707200	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3038707200	3038707200	✔
IgnOnTimer_mS_M_u32	4120204288	4120204288	✔
IgnTimeOff_Sec_M_u32	1781026446	1781026446	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	100	100	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	580867072	580867072	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	166	166	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	161182720	161182720	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	164	164	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	283612160	283612160	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	39	39	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	8631296	8631296	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3325334528	3325334528	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	217	217	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3098276864	3098276864	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	152	152	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	288887808	288887808	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	45	45	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1740944384	1740944384	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	155	155	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1830966272	1830966272	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	180	180	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2342417408	2342417408	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	74	74	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2322240512	2322240512	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4110820352	4110820352	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	263.439087	263.439087	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	331.858795	331.858795	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	136.821304	136.821304	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	465.397247	465.397247	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	40937	40937	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1781026446	1781026446	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-644.093079	-644.093079 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.139 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4163254016
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	27110
AASNodeAbsentTimer_mS_M_u32	953870080
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	33237
ANGLEVOLANTSigValidCount_Cnt_M_u16	24233
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	63031
AngleVolantMsgTimer_mS_M_u32	4163254016
AngleVolantValidCount_Cnt_M_u16	59233
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	304.220123
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2181146368
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	176826112
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3280951040
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1170282240
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	33528
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1414125312
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	35867
CAVNodeAbsentTimer_mS_M_u32	3735553792
CDD_SrlComVehSpd_Kph_G_f32	476.156189
CMM388NTCEnableTimer_mS_M_u32	2780645120
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	223741696
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	53519
CMMNodeAbsentTimer_mS_M_u32	1469257472
CONSANGLECPKSigInvalidCount_Cnt_M_u16	6007
CONSANGLECPKSigValidCount_Cnt_M_u16	19676
CONSANGLECPK_Cnt_M_u16	14771
CONSANGLECPK_HwDeg_M_f32	202.134201
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	14771
CPKVehicleSpeedMsgTimer_mS_M_u32	1835087616
CPKVehicleSpeedValidCount_Cnt_M_u16	18464
CityParkInputConsistentCount_Cnt_M_u16	5333

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	28015
CityParkInputMsgTimer_mS_M_u32	580867072
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3276728064
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	34138
ComputerRazGCTSigInvalidTimer_mS_M_u32	204113664
ComputerRazGCTSigValidCount_Cnt_M_u16	52414
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	35835
DMDFCTCPKSigValidCount_Cnt_M_u16	23255
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	52111
DMDRELAXECPKSigValidCount_Cnt_M_u16	24547
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	49352
DateInvalidTimer_mS_M_u32	176826112
DiagMuxOnAbsentTimer_mS_M_u32	823064320
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1170282240
ESPNTCEnableTimer_mS_M_u32	3932153600
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	18093
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	41
EffacDefaultDiagTimer_mS_M_u32[1]	46
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	56565
ElecIntTimer_mS_M_u32[1]	787880
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1642321664
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	60173
EtatMTSigValidCount_Cnt_M_u16	55421
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	3889
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	31766
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	43909
ISDAT4V2BSI552MsgTimer_mS_M_u32	2433160960
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1664
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	56920
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	55421
ISDATBSI3F2MsgTimer_mS_M_u32	2975135488
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1735
ISDATBSI412MsgLenValidCount_Cnt_M_u16	399
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	60173
ISDATBSI412MsgTimer_mS_M_u32	376190720
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	63875
ISDATBSI432MsgLenValidCount_Cnt_M_u16	18371
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	14656
ISDATDIRASentFltAcc_Cnt_M_u16	19716
ISDATDIRASentTimer_mS_M_u32	1835087616
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	33401
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	59233
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52382
ISDYN2CMMMsgTimer_mS_M_u32	984737536
ISDYNAASChkSumInvalidCount_Cnt_M_u16	61344
ISDYNAASChkSumValidCount_Cnt_M_u16	30228
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	50692
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	32306
ISDYNAASMsgLenValidCount_Cnt_M_u16	1023
ISDYNAASMsgTimeValidCount_Cnt_M_u16	61344
ISDYNAASMsgTimer_mS_M_u32	1565083392
ISDYNABRChkSumInvalidCount_Cnt_M_u16	49136
ISDYNABRChkSumValidCount_Cnt_M_u16	46380
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	51907
ISDYNABRMsgCountValidCount_Cnt_M_u16	30071
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	16794
ISDYNABRMsgLenValidCount_Cnt_M_u16	56127
ISDYNABRMsgTimeValidCount_Cnt_M_u16	14771
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	741

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1367
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	55421
ISDYNCMM208MsgTimer_mS_M_u32	4012549888
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2815
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1473
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	26791
ISDYNCMM388MsgTimer_mS_M_u32	3501901568
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	12221
ISDYNVOLChkSumValidCount_Cnt_M_u16	11682
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	13121
ISDYNVOLMsgCountValidCount_Cnt_M_u16	2717
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	41004
ISDYNVOLMsgLenValidCount_Cnt_M_u16	3056
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	53519
ISDYNVOLMsgTimer_mS_M_u32	532055808
IgnOnTimer_mS_M_u32	2435761920
IgnTimeOff_Sec_M_u32	519345904
ManVehSpd_Kph_M_f32	95.594902
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	103
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	171
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2070083328
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	222
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1964136192
PrevISDATBSI412MsgDLCError_Cnt_M_u08	187
PrevISDATBSI412MsgRxTime_MSec_M_u32	2374829824
PrevISDATBSI432MsgDLCError_Cnt_M_u08	128
PrevISDATBSI432MsgRxTime_MSec_M_u32	2852382464
PrevISDATDIRAMsgTxTime_MSec_M_u32	2890991360
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	250
PrevISDYN2CMMMsgRxTime_MSec_M_u32	447518464
PrevISDYNAASMsgDLCError_Cnt_M_u08	146
PrevISDYNAASMsgRxTime_MSec_M_u32	3497821952
PrevISDYNABRMsgDLCError_Cnt_M_u08	23
PrevISDYNABRMsgRxTime_MSec_M_u32	1598473984
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	60
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2166720256
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	108
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3353011968
PrevISDYNVOLMsgDLCError_Cnt_M_u08	151
PrevISDYNVOLMsgRxTime_MSec_M_u32	1399719680
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2477930240
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	642.68988
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	50040
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	53701
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	48853
VitesseVehicleBVRampValidCount_Cnt_M_u16	35042
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	17586
VitesseVehicleBVSigValidCount_Cnt_M_u16	32070

Name	Input Value
VitesseVehicleBV_Kph_M_f32	65.6757965
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	26791
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	62675
VitesseVehiculeRoues_Kph_M_f32	603.357422
k_AASNTCEnableTimeout_mS_u16	44590
k_AASNodeAbsentDiag_Cnt_str.Threshold	24708
k_AASNodeAbsentDiag_Cnt_str.PStep	10329
k_AASNodeAbsentDiag_Cnt_str.NStep	12571
k_AASNodeAbsentTimeout_mS_u16	46992
k_AASNodeTimeout_mS_u16	57541
k_ABSNodeTimeout_mS_u16	64484
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	49138
k_ANGLEVOLANTSigValidThresh_Cnt_u16	21362
k_AngleVolantInvalidThresh_Cnt_u16	35709
k_AngleVolantValidThresh_Cnt_u16	28015
k_BSI552MsgTimeout_mS_u16	14494
k_BSINTCEnableTimeout_mS_u16	63387
k_BSINodeAbsentDiag_Cnt_str.Threshold	1140
k_BSINodeAbsentDiag_Cnt_str.PStep	1154
k_BSINodeAbsentDiag_Cnt_str.NStep	3424
k_BSINodeAbsentTimeout_mS_u16	11855
k_BSINodeTimeout_mS_u16	14656
k_BattOvHi_Volt_f32	29.3887997
k_BattOvLo_Volt_f32	10.2305002
k_BattUvHi_Volt_f32	2.63919997
k_BattUvLo_Volt_f32	19.3931007
k_CAVNTCEnableTimeout_mS_u16	32973
k_CAVNodeAbsentDiag_Cnt_str.Threshold	3620
k_CAVNodeAbsentDiag_Cnt_str.PStep	26391
k_CAVNodeAbsentDiag_Cnt_str.NStep	7448
k_CAVNodeAbsentTimeout_mS_u16	14433
k_CAVNodeTimeout_mS_u16	42755
k_CMM388MsgTimeout_mS_u16	47334
k_CMM388NTCEnableTimeout_mS_u16	56690
k_CMMNTCEnableTimeout_mS_u16	53400
k_CMMNodeAbsentDiag_Cnt_str.Threshold	59435
k_CMMNodeAbsentDiag_Cnt_str.PStep	4125
k_CMMNodeAbsentDiag_Cnt_str.NStep	17753
k_CMMNodeAbsentTimeout_mS_u16	18271
k_CONSANGLECPKMax_HwDeg_f32	109.657898
k_CONSANGLECPKMin_HwDeg_f32	-32.1068993
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	14247
k_CONSANGLECPKSigValidThresh_Cnt_u16	979
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	39027
k_CPKVehicleSpeedValidThresh_Cnt_u16	58782
k_CityParkInputInvalidThresh_Cnt_u16	17950
k_CityParkInputValidThresh_Cnt_u16	5333
k_ComputerRazGCTSigValidThresh_Cnt_u16	58638
k_CptTemporelSigValidThresh_Cnt_u16	11110
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	37018
k_DMDFCTCPKSigValidThresh_Cnt_u16	27199
k_DMDFCTCPKValidCount_Cnt_u16	59872
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	52382
k_DMDRELAXECPKSigValidThresh_Cnt_u16	57274
k_DMDRelaxeConsistentThresh_Cnt_u16	35176
k_DateValidThresh_Cnt_u16	43909
k_DefaultVehSpd_Kph_f32	212.616592
k_DiagMuxOnAbsentTimeout_mS_u16	54417
k_EMNodeTimeout_mS_u16	56232
k_ESPNTCEnableTimeout_mS_u16	9639
k_ESPNodeAbsentDiag_Cnt_str.Threshold	47445
k_ESPNodeAbsentDiag_Cnt_str.PStep	24880
k_ESPNodeAbsentDiag_Cnt_str.NStep	58700
k_ESPNodeAbsentTimeout_mS_u16	61767
k_EtatMTSigInvalidThresh_Cnt_u16	5467
k_EtatMTSigValidThresh_Cnt_u16	54487
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	58538
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	26234
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	2610
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	9841
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	49417
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	3387
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	22772

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	2548
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	25079
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	23303
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	44655
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	36290
k_ISDATDIRASentDiag_Cnt_str.Threshold	12314
k_ISDATDIRASentDiag_Cnt_str.PStep	25984
k_ISDATDIRASentDiag_Cnt_str.NStep	21340
k_ISDATDIRASentTimeout_mS_u16	34172
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	4075
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	63031
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	46851
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	36592
k_ISDYNAASChkSumValidThresh_Cnt_u16	50220
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	6595
k_ISDYNAASMsgCountValidThresh_Cnt_u16	1143
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	2404
k_ISDYNAASMsgLenValidThresh_Cnt_u16	17977
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	54106
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	12512
k_ISDYNABRChkSumValidThresh_Cnt_u16	54021
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	53752
k_ISDYNABRMsgCountValidThresh_Cnt_u16	37644
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	57359
k_ISDYNABRMsgLenValidThresh_Cnt_u16	16207
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	37463
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	18668
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	57956
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	59280
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	53461
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	60841
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	47495
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	51126
k_ISDYNVOLChkSumValidThresh_Cnt_u16	59326
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	1952
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	60832
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	7577
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	7177
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	55651
k_IgnOnTimeout_mS_u16	20802
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	201.5233
k_PowerCutVehSpdLowThresh_Kph_f32	241.249893
k_PowerCutVehSpdLowTimeout_mS_u16	3434
k_VBattMaxAAS_Volt_f32	28.9829006
k_VBattMaxBSI_Volt_f32	5.13789988
k_VBattMaxCAV_Volt_f32	21.8062
k_VBattMaxCMM388_Volt_f32	16.1651001
k_VBattMaxCMM_Volt_f32	17.8458004
k_VBattMaxESP_Volt_f32	25.9363995
k_VBattMinAAS_Volt_f32	16.7912998
k_VBattMinBSI_Volt_f32	25.9363995
k_VBattMinCAV_Volt_f32	28.7833004
k_VBattMinCMM388_Volt_f32	5.81640005
k_VBattMinCMM_Volt_f32	23.5963001
k_VBattMinESP_Volt_f32	17.8458004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	20285
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	33334
k_VitesseVehicleBVRampValidThresh_Cnt_u16	577
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	48290
k_VitesseVehicleBVSigValidThresh_Cnt_u16	40522
k_VitesseVehicleBVSpeedPassThresh_kph_f32	91.4048996
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	23323
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	60840
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	176826112
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	241
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	45704
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3854158080
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	108
target_SrlComInput_Per1_Batt_Volt_f32.value	9.01150036
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1179571968
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	90
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.577964842
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2987443968
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2510055168
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1480066816
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	249
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2716051200
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	446646016
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	149
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1785390848
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	960923392
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	58
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	104
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	196
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	201
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2954929920
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	153
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	176
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	191
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2659698432
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3683870464
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3081701120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	164
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	165
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	189
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	438064896
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1702
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.402213842
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	642220
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	170.089996

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	49738		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	24708	24708	✔
AASNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	63031	63031	✔
AngleVolantMsgTimer_mS_M_u32	3854158080	3854158080	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	304.220123	304.220123	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	1140	1140	✔
BSINodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	59435	59435	✔
CMMNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	14771	14771	✔
CONSANGLECPK_HwDeg_M_f32	202.134201	202.134201 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	14771	14771	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1835087616	1835087616	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	18464	18464	✔
CityParkInputConsistentCount_Cnt_M_u16	5333	5333	✔
CityParkInputInvalidCount_Cnt_M_u16	28015	28015	✔
CityParkInputMsgTimer_mS_M_u32	3854158080	3854158080	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3854158080	3854158080	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3854158080	3854158080	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3854158080	3854158080	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3854158080	3854158080	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3854158080	3854158080	✔
ESPNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	41	41	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	46	46	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	56565	56565	✔
ElecIntTimer_mS_M_u32[1]	787880	787880	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3854158080	3854158080	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3854158080	3854158080	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3854158080	3854158080	✔
IgnOnTimer_mS_M_u32	2435761920	2435761920	✔
IgnTimeOff_Sec_M_u32	519345904	519345904	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	151	151	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2987443968	2987443968	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	202	202	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2510055168	2510055168	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	8	8	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1480066816	1480066816	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	249	249	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2716051200	2716051200	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2890991360	2890991360	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	149	149	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1785390848	1785390848	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	143	143	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	960923392	960923392	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2954929920	2954929920	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	191	191	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2659698432	2659698432	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	107	107	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3683870464	3683870464	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3081701120	3081701120	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	438064896	438064896	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	642.68988	642.68988	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	65.6757965	65.6757965	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	603.357422	603.357422	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	304.220123	304.220123	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	14771	14771	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	519345904	519345904	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	202.134201	202.134201 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.140 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1556618752
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	43398
AASNodeAbsentTimer_mS_M_u32	2305428992
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	15291
ANGLEVOLANTSigValidCount_Cnt_M_u16	29182
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	34963
AngleVolantMsgTimer_mS_M_u32	1556618752
AngleVolantValidCount_Cnt_M_u16	58262
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	598.99585
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3103116800
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3780922880
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2265759232
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	4151803392
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	33874
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3739041280
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	65383
CAVNodeAbsentTimer_mS_M_u32	3028463104
CDD_SrlComVehSpd_Kph_G_f32	13.6322002
CMM388NTCEnableTimer_mS_M_u32	1145236992
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1618521600
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	0
CMMNodeAbsentTimer_mS_M_u32	2315353600
CONSANGLECPKSigInvalidCount_Cnt_M_u16	30162
CONSANGLECPKSigValidCount_Cnt_M_u16	57958
CONSANGLECPK_Cnt_M_u16	14305
CONSANGLECPK_HwDeg_M_f32	209.509796
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	14305
CPKVehicleSpeedMsgTimer_mS_M_u32	2836864512
CPKVehicleSpeedValidCount_Cnt_M_u16	17824
CityParkInputConsistentCount_Cnt_M_u16	11066
CityParkInputInvalidCount_Cnt_M_u16	23147

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	2987443968
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3121483264
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	10026
ComputerRazGCTSigInvalidTimer_mS_M_u32	1442524672
ComputerRazGCTSigValidCount_Cnt_M_u16	59263
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	11975
DMDFCTCPKSigValidCount_Cnt_M_u16	44787
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	50829
DMDRELAXECPKSigValidCount_Cnt_M_u16	54864
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	64991
DateInvalidTimer_mS_M_u32	3780922880
DiagMuxOnAbsentTimer_mS_M_u32	1158536704
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4151803392
ESPNTCEnableTimer_mS_M_u32	3369799168
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	43340
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	3
EffacDefaultDiagTimer_mS_M_u32[1]	6
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	556
ElecIntTimer_mS_M_u32[1]	877878
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2651799040
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	1362
EtatMTSigValidCount_Cnt_M_u16	31169
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	63140
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	48312
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	62697
ISDAT4V2BSI552MsgTimer_mS_M_u32	2913304064
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	38521
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	60336
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	31169
ISDATBSI3F2MsgTimer_mS_M_u32	1547427328
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	49827
ISDATBSI412MsgLenValidCount_Cnt_M_u16	28427
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	1362
ISDATBSI412MsgTimer_mS_M_u32	2583043584
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	57584
ISDATBSI432MsgLenValidCount_Cnt_M_u16	29424
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	52216
ISDATDIRASentFltAcc_Cnt_M_u16	41132
ISDATDIRASentTimer_mS_M_u32	2836864512
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	62863
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	58262
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	47326
ISDYN2CMMMsgTimer_mS_M_u32	2682588672
ISDYNAASChkSumInvalidCount_Cnt_M_u16	32856
ISDYNAASChkSumValidCount_Cnt_M_u16	14780
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	37805
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	17698
ISDYNAASMsgLenValidCount_Cnt_M_u16	24701
ISDYNAASMsgTimeValidCount_Cnt_M_u16	32856
ISDYNAASMsgTimer_mS_M_u32	1302261248
ISDYNABRChkSumInvalidCount_Cnt_M_u16	1258
ISDYNABRChkSumValidCount_Cnt_M_u16	37365
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	15087
ISDYNABRMsgCountValidCount_Cnt_M_u16	34707
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	17257
ISDYNABRMsgLenValidCount_Cnt_M_u16	33597
ISDYNABRMsgTimeValidCount_Cnt_M_u16	14305
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	742
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1369

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	31169
ISDYNCMM208MsgTimer_mS_M_u32	1434111488
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2819
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1475
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	63428
ISDYNCMM388MsgTimer_mS_M_u32	2571791872
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	50432
ISDYNVOLChkSumValidCount_Cnt_M_u16	55316
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	53493
ISDYNVOLMsgCountValidCount_Cnt_M_u16	14241
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	19893
ISDYNVOLMsgLenValidCount_Cnt_M_u16	38696
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0
ISDYNVOLMsgTimer_mS_M_u32	1264004608
IgnOnTimer_mS_M_u32	669937152
IgnTimeOff_Sec_M_u32	578610465
ManVehSpd_Kph_M_f32	85.5588989
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	105
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3054624256
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	220
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1048821248
PrevISDATBSI412MsgDLCError_Cnt_M_u08	167
PrevISDATBSI412MsgRxTime_MSec_M_u32	2077470208
PrevISDATBSI432MsgDLCError_Cnt_M_u08	252
PrevISDATBSI432MsgRxTime_MSec_M_u32	435097088
PrevISDATDIRAMsgTxTime_MSec_M_u32	797421056
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	129
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2260008448
PrevISDYNAASMsgDLCError_Cnt_M_u08	160
PrevISDYNAASMsgRxTime_MSec_M_u32	3506777600
PrevISDYNABRMsgDLCError_Cnt_M_u08	92
PrevISDYNABRMsgRxTime_MSec_M_u32	497446400
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	14
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2735353344
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	163
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3697937920
PrevISDYNVOLMsgDLCError_Cnt_M_u08	147
PrevISDYNVOLMsgRxTime_MSec_M_u32	3996167680
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3122929152
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	462.647614
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	3408
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	36651
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	53049
VitesseVehicleBVRampValidCount_Cnt_M_u16	7636
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	42788
VitesseVehicleBVSigValidCount_Cnt_M_u16	51751
VitesseVehicleBV_Kph_M_f32	27.2549992

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	63428
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	32768
VitesseVehiculeRoues_Kph_M_f32	525.522705
k_AASNTCEnableTimeout_mS_u16	34416
k_AASNodeAbsentDiag_Cnt_str.Threshold	29221
k_AASNodeAbsentDiag_Cnt_str.PStep	23710
k_AASNodeAbsentDiag_Cnt_str.NStep	19599
k_AASNodeAbsentTimeout_mS_u16	61193
k_AASNodeTimeout_mS_u16	25131
k_ABSNodeTimeout_mS_u16	49932
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	2467
k_ANGLEVOLANTSigValidThresh_Cnt_u16	52195
k_AngleVolantInvalidThresh_Cnt_u16	4034
k_AngleVolantValidThresh_Cnt_u16	23147
k_BSI552MsgTimeout_mS_u16	41119
k_BSINTCEnableTimeout_mS_u16	18088
k_BSINodeAbsentDiag_Cnt_str.Threshold	1253
k_BSINodeAbsentDiag_Cnt_str.PStep	1260
k_BSINodeAbsentDiag_Cnt_str.NStep	4266
k_BSINodeAbsentTimeout_mS_u16	16459
k_BSINodeTimeout_mS_u16	52216
k_BattOvHi_Volt_f32	24.7558002
k_BattOvLo_Volt_f32	14.4060001
k_BattUvHi_Volt_f32	14.4236002
k_BattUvLo_Volt_f32	8.43669987
k_CAVNTCEnableTimeout_mS_u16	6225
k_CAVNodeAbsentDiag_Cnt_str.Threshold	55517
k_CAVNodeAbsentDiag_Cnt_str.PStep	35644
k_CAVNodeAbsentDiag_Cnt_str.NStep	21680
k_CAVNodeAbsentTimeout_mS_u16	37525
k_CAVNodeTimeout_mS_u16	63278
k_CMM388MsgTimeout_mS_u16	48262
k_CMM388NTCEnableTimeout_mS_u16	32482
k_CMMNTCEnableTimeout_mS_u16	38961
k_CMMNodeAbsentDiag_Cnt_str.Threshold	61198
k_CMMNodeAbsentDiag_Cnt_str.PStep	31282
k_CMMNodeAbsentDiag_Cnt_str.NStep	40373
k_CMMNodeAbsentTimeout_mS_u16	47196
k_CONSANGLECPKMax_HwDeg_f32	315.441498
k_CONSANGLECPKMin_HwDeg_f32	-583.116699
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	35524
k_CONSANGLECPKSigValidThresh_Cnt_u16	21248
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	29473
k_CPKVehicleSpeedValidThresh_Cnt_u16	16926
k_CityParkInputInvalidThresh_Cnt_u16	43616
k_CityParkInputValidThresh_Cnt_u16	11066
k_ComputerRazGCTSigValidThresh_Cnt_u16	45775
k_CptTemporelSigValidThresh_Cnt_u16	48262
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	22121
k_DMDFCTCPKSigValidThresh_Cnt_u16	54845
k_DMDFCTCPKValidCount_Cnt_u16	61338
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	47326
k_DMDRELAXECPKSigValidThresh_Cnt_u16	27722
k_DMDRelaxeConsistentThresh_Cnt_u16	42816
k_DateValidThresh_Cnt_u16	62697
k_DefaultVehSpd_Kph_f32	173.879898
k_DiagMuxOnAbsentTimeout_mS_u16	24391
k_EMNodeTimeout_mS_u16	11583
k_ESPNTCEnableTimeout_mS_u16	25283
k_ESPNodeAbsentDiag_Cnt_str.Threshold	4337
k_ESPNodeAbsentDiag_Cnt_str.PStep	20825
k_ESPNodeAbsentDiag_Cnt_str.NStep	5438
k_ESPNodeAbsentTimeout_mS_u16	23204
k_EtatMTSigInvalidThresh_Cnt_u16	28841
k_EtatMTSigValidThresh_Cnt_u16	40692
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	10876
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	25036
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	65315
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	15014
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	18333
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	32583
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	50845
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	12381

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	30612
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	9189
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	18028
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	10930
k_ISDATDIRASentDiag_Cnt_str.Threshold	53628
k_ISDATDIRASentDiag_Cnt_str.PStep	31362
k_ISDATDIRASentDiag_Cnt_str.NStep	51301
k_ISDATDIRASentTimeout_mS_u16	58438
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	34871
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	34963
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	7855
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	38890
k_ISDYNAASChkSumValidThresh_Cnt_u16	25845
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	19951
k_ISDYNAASMsgCountValidThresh_Cnt_u16	55955
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	63630
k_ISDYNAASMsgLenValidThresh_Cnt_u16	463
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	60459
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	3479
k_ISDYNABRChkSumValidThresh_Cnt_u16	13291
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	38738
k_ISDYNABRMsgCountValidThresh_Cnt_u16	8405
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	23884
k_ISDYNABRMsgLenValidThresh_Cnt_u16	48204
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	3828
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	19700
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	58316
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	14794
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	20155
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	50430
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	54819
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	64470
k_ISDYNVOLChkSumValidThresh_Cnt_u16	14462
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	59225
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	47257
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	40366
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	57117
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	25423
k_IgnOnTimeout_mS_u16	36658
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	23.6595993
k_PowerCutVehSpdLowThresh_Kph_f32	8.47990036
k_PowerCutVehSpdLowTimeout_mS_u16	22716
k_VBattMaxAAS_Volt_f32	1.44599998
k_VBattMaxBSI_Volt_f32	6.53009987
k_VBattMaxCAV_Volt_f32	18.0456009
k_VBattMaxCMM388_Volt_f32	30.3927002
k_VBattMaxCMM_Volt_f32	9.2052002
k_VBattMaxESP_Volt_f32	4.75279999
k_VBattMinAAS_Volt_f32	10.7894001
k_VBattMinBSI_Volt_f32	4.75279999
k_VBattMinCAV_Volt_f32	29.6952
k_VBattMinCMM388_Volt_f32	7.39470005
k_VBattMinCMM_Volt_f32	22.4722004
k_VBattMinESP_Volt_f32	9.2052002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	37441
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	22040
k_VitesseVehicleBVRampValidThresh_Cnt_u16	25589
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	11028
k_VitesseVehicleBVSigValidThresh_Cnt_u16	41691
k_VitesseVehicleBVSpeedPassThresh_kph_f32	94.2832031
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	37479
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	34690
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3780922880
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	3
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	2529
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	282421248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	163

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	13.3065996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1557020160
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	132
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.384398401
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	25
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3444076032
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1495633408
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2278731264
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1632620032
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3986484736
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	17
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	884608512
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	120
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1051143680
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	93
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	123
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	163
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	244
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1788399104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	50
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	106
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	62
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2749591040
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	79
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	591433216
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	91074048
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	80
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	132
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	222
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4150640128
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1983
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.829629719
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	827379
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	206.209702
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	55514

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	282421248	282421248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	29221	29221	✔
AASNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	34963	34963	✔
AngleVolantMsgTimer_mS_M_u32	282421248	282421248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	598.99585	598.99585	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	1253	1253	✔
BSINodeAbsentTimer_mS_M_u32	282421248	282421248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	282421248	282421248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	282421248	282421248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	282421248	282421248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	61198	61198	✔
CMMNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	14305	14305	✔
CONSANGLECPK_HwDeg_M_f32	209.509796	209.509796 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	14305	14305	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2836864512	2836864512	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	17824	17824	✔
CityParkInputConsistentCount_Cnt_M_u16	11066	11066	✔
CityParkInputInvalidCount_Cnt_M_u16	23149	23149	✔
CityParkInputMsgTimer_mS_M_u32	282421248	282421248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	282421248	282421248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	282421248	282421248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	282421248	282421248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	282421248	282421248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	282421248	282421248	✔
ESPNTCEnableTimer_mS_M_u32	282421248	282421248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3	3	✔
EffacDefaultDiagTimer_mS_M_u32[1]	6	6	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	282421248	282421248	✔
ElecIntTimer_mS_M_u32[1]	877878	877878	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	282421248	282421248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	282421248	282421248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	282421248	282421248	✔
IgnOnTimer_mS_M_u32	282421248	282421248	✔
IgnTimeOff_Sec_M_u32	578610465	578610465	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	25	25	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3444076032	3444076032	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	151	151	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1495633408	1495633408	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	51	51	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2278731264	2278731264	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	246	246	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1632620032	1632620032	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	797421056	797421056	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	17	17	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	884608512	884608512	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	120	120	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1051143680	1051143680	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1788399104	1788399104	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	62	62	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2749591040	2749591040	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	79	79	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	591433216	591433216	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	63	63	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	91074048	91074048	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4150640128	4150640128	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	462.647614	462.647614	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	27.2549992	27.2549992	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	525.522705	525.522705	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	598.99585	598.99585	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	14305	14305	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	578610465	578610465	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	209.509796	209.509796 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.141 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2067687680
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	44802
AASNodeAbsentTimer_mS_M_u32	689477888
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	27237
ANGLEVOLANTSigValidCount_Cnt_M_u16	24923
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	34267
AngleVolantMsgTimer_mS_M_u32	2067687680
AngleVolantValidCount_Cnt_M_u16	59730
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	51.4752731
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2037733632
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3124877568
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1458604288
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	548423936
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	44192
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	830408960
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	30689
CAVNodeAbsentTimer_mS_M_u32	1380890880
CDD_SrlComVehSpd_Kph_G_f32	476.583801
CMM388NTCEnableTimer_mS_M_u32	4094556416
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2792143104
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	65535
CMMNodeAbsentTimer_mS_M_u32	286411008
CONSANGLECPKSigInvalidCount_Cnt_M_u16	51998
CONSANGLECPKSigValidCount_Cnt_M_u16	24355
CONSANGLECPK_Cnt_M_u16	2738
CONSANGLECPK_HwDeg_M_f32	646.898499
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2738
CPKVehicleSpeedMsgTimer_mS_M_u32	2454808832
CPKVehicleSpeedValidCount_Cnt_M_u16	22109

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	41574
CityParkInputInvalidCount_Cnt_M_u16	27090
CityParkInputMsgTimer_mS_M_u32	3444076032
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	657234176
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	50710
ComputerRazGCTSigInvalidTimer_mS_M_u32	4024776960
ComputerRazGCTSigValidCount_Cnt_M_u16	49559
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	23742
DMDFCTCPKSigValidCount_Cnt_M_u16	5628
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	37359
DMDRELAXECPKSigValidCount_Cnt_M_u16	64613
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	42743
DateInvalidTimer_mS_M_u32	3124877568
DiagMuxOnAbsentTimer_mS_M_u32	158148864
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	548423936
ESPNTCEnableTimer_mS_M_u32	1858443520
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	63153
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	9
EffacDefaultDiagTimer_mS_M_u32[1]	81
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	2323
ElecIntTimer_mS_M_u32[1]	45465
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1005127936
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	64992
EtatMTSigValidCount_Cnt_M_u16	59985
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	4264
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	38957
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	39962
ISDAT4V2BSI552MsgTimer_mS_M_u32	908478720
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	40938
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	2563
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	59985
ISDATBSI3F2MsgTimer_mS_M_u32	4225968384
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	37995
ISDATBSI412MsgLenValidCount_Cnt_M_u16	47349
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	64992
ISDATBSI412MsgTimer_mS_M_u32	4222904576
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	22019
ISDATBSI432MsgLenValidCount_Cnt_M_u16	10693
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	38446
ISDATDIRASentFltAcc_Cnt_M_u16	59410
ISDATDIRASentTimer_mS_M_u32	2454808832
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	2472
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	59730
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	55929
ISDYN2CMMMsgTimer_mS_M_u32	2443680000
ISDYNAASChkSumInvalidCount_Cnt_M_u16	62092
ISDYNAASChkSumValidCount_Cnt_M_u16	57378
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	62733
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	21168
ISDYNAASMsgLenValidCount_Cnt_M_u16	64093
ISDYNAASMsgTimeValidCount_Cnt_M_u16	62092
ISDYNAASMsgTimer_mS_M_u32	1207564544
ISDYNABRChkSumInvalidCount_Cnt_M_u16	33879
ISDYNABRChkSumValidCount_Cnt_M_u16	38644
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	57031
ISDYNABRMsgCountValidCount_Cnt_M_u16	4765
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	32345
ISDYNABRMsgLenValidCount_Cnt_M_u16	39070
ISDYNABRMsgTimeValidCount_Cnt_M_u16	2738

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	743
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1371
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	59985
ISDYNCMM208MsgTimer_mS_M_u32	4159068416
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2823
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1477
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	58568
ISDYNCMM388MsgTimer_mS_M_u32	1928820992
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	5524
ISDYNVOLChkSumValidCount_Cnt_M_u16	46617
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	44596
ISDYNVOLMsgCountValidCount_Cnt_M_u16	46066
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	60790
ISDYNVOLMsgLenValidCount_Cnt_M_u16	27356
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	65535
ISDYNVOLMsgTimer_mS_M_u32	2144418048
IgnOnTimer_mS_M_u32	1460369664
IgnTimeOff_Sec_M_u32	2619952977
ManVehSpd_Kph_M_f32	188.375397
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	107
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	73
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3328256256
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	101
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3431696640
PrevISDATBSI412MsgDLCError_Cnt_M_u08	216
PrevISDATBSI412MsgRxTime_MSec_M_u32	2153494784
PrevISDATBSI432MsgDLCError_Cnt_M_u08	239
PrevISDATBSI432MsgRxTime_MSec_M_u32	3414792448
PrevISDATDIRAMsgTxTime_MSec_M_u32	893368576
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	140
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1224198400
PrevISDYNAASMsgDLCError_Cnt_M_u08	121
PrevISDYNAASMsgRxTime_MSec_M_u32	650590464
PrevISDYNABRMsgDLCError_Cnt_M_u08	95
PrevISDYNABRMsgRxTime_MSec_M_u32	1440971008
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	234
PrevISDYNCMM208MsgRxTime_MSec_M_u32	79182080
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	189
PrevISDYNCMM388MsgRxTime_MSec_M_u32	806918400
PrevISDYNVOLMsgDLCError_Cnt_M_u08	153
PrevISDYNVOLMsgRxTime_MSec_M_u32	3712268544
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3542771968
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	221.728302
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	12838
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	42579
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	53355
VitesseVehicleBVRampValidCount_Cnt_M_u16	56920
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	3114

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	15584
VitesseVehicleBV_Kph_M_f32	151.130402
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	58568
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	50646
VitesseVehiculeRoues_Kph_M_f32	198.469803
k_AASNTCEnableTimeout_mS_u16	6917
k_AASNodeAbsentDiag_Cnt_str.Threshold	12222
k_AASNodeAbsentDiag_Cnt_str.PStep	35436
k_AASNodeAbsentDiag_Cnt_str.NStep	31728
k_AASNodeAbsentTimeout_mS_u16	21241
k_AASNodeTimeout_mS_u16	11603
k_ABSNodeTimeout_mS_u16	62447
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	26602
k_ANGLEVOLANTSigValidThresh_Cnt_u16	43756
k_AngleVolantInvalidThresh_Cnt_u16	6991
k_AngleVolantValidThresh_Cnt_u16	27090
k_BSI552MsgTimeout_mS_u16	40953
k_BSINTCEnableTimeout_mS_u16	1243
k_BSINodeAbsentDiag_Cnt_str.Threshold	1366
k_BSINodeAbsentDiag_Cnt_str.PStep	1366
k_BSINodeAbsentDiag_Cnt_str.NStep	5108
k_BSINodeAbsentTimeout_mS_u16	16051
k_BSINodeTimeout_mS_u16	38446
k_BattOvHi_Volt_f32	21.8155994
k_BattOvLo_Volt_f32	28.8390999
k_BattUvHi_Volt_f32	31.5
k_BattUvLo_Volt_f32	14.6914997
k_CAVNTCEnableTimeout_mS_u16	18464
k_CAVNodeAbsentDiag_Cnt_str.Threshold	3278
k_CAVNodeAbsentDiag_Cnt_str.PStep	40457
k_CAVNodeAbsentDiag_Cnt_str.NStep	24390
k_CAVNodeAbsentTimeout_mS_u16	63063
k_CAVNodeTimeout_mS_u16	46858
k_CMM388MsgTimeout_mS_u16	30210
k_CMM388NTCEnableTimeout_mS_u16	40686
k_CMMNTCEnableTimeout_mS_u16	31426
k_CMMNodeAbsentDiag_Cnt_str.Threshold	64865
k_CMMNodeAbsentDiag_Cnt_str.PStep	13070
k_CMMNodeAbsentDiag_Cnt_str.NStep	24285
k_CMMNodeAbsentTimeout_mS_u16	36034
k_CONSANGLECPKMax_HwDeg_f32	541.20282
k_CONSANGLECPKMin_HwDeg_f32	-585.565186
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	11208
k_CONSANGLECPKSigValidThresh_Cnt_u16	19670
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	21105
k_CPKVehicleSpeedValidThresh_Cnt_u16	49658
k_CityParkInputInvalidThresh_Cnt_u16	60405
k_CityParkInputValidThresh_Cnt_u16	41574
k_ComputerRazGCTSigValidThresh_Cnt_u16	8936
k_CptTemporelSigValidThresh_Cnt_u16	28545
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	17753
k_DMDFCTCPKSigValidThresh_Cnt_u16	40862
k_DMDFCTCPKValidCount_Cnt_u16	35528
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	55929
k_DMDRELAXECPKSigValidThresh_Cnt_u16	63991
k_DMDRelaxeConsistentThresh_Cnt_u16	41237
k_DateValidThresh_Cnt_u16	39962
k_DefaultVehSpd_Kph_f32	212.449402
k_DiagMuxOnAbsentTimeout_mS_u16	44160
k_EMNodeTimeout_mS_u16	39127
k_ESPNTCEnableTimeout_mS_u16	48589
k_ESPNodeAbsentDiag_Cnt_str.Threshold	22426
k_ESPNodeAbsentDiag_Cnt_str.PStep	52857
k_ESPNodeAbsentDiag_Cnt_str.NStep	29219
k_ESPNodeAbsentTimeout_mS_u16	50666
k_EtatMTSigInvalidThresh_Cnt_u16	64794
k_EtatMTSigValidThresh_Cnt_u16	11255
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	22624
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	31794
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	2731
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	42851
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	59964
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	61055

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	39164
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	58750
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	8727
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	22182
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	39120
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	25920
k_ISDATDIRASentDiag_Cnt_str.Threshold	1905
k_ISDATDIRASentDiag_Cnt_str.PStep	4278
k_ISDATDIRASentDiag_Cnt_str.NStep	49319
k_ISDATDIRASentTimeout_mS_u16	22083
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	41137
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	34267
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	14857
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	52055
k_ISDYNAASChkSumValidThresh_Cnt_u16	7668
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	42439
k_ISDYNAASMsgCountValidThresh_Cnt_u16	6557
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	14699
k_ISDYNAASMsgLenValidThresh_Cnt_u16	56935
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	27156
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	22479
k_ISDYNABRChkSumValidThresh_Cnt_u16	48788
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	29600
k_ISDYNABRMsgCountValidThresh_Cnt_u16	28886
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	20719
k_ISDYNABRMsgLenValidThresh_Cnt_u16	48561
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	57977
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	826
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	5360
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	57974
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	12645
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	26715
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	54954
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	29906
k_ISDYNVOLChkSumValidThresh_Cnt_u16	59548
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	45194
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	45832
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	42188
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	10813
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	26856
k_IgnOnTimeout_mS_u16	10942
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	189.610001
k_PowerCutVehSpdLowThresh_Kph_f32	179.149094
k_PowerCutVehSpdLowTimeout_mS_u16	54305
k_VBattMaxAAS_Volt_f32	7.01709986
k_VBattMaxBSI_Volt_f32	26.1184998
k_VBattMaxCAV_Volt_f32	5.01049995
k_VBattMaxCMM388_Volt_f32	14.6976004
k_VBattMaxCMM_Volt_f32	27.6966
k_VBattMaxESP_Volt_f32	14.5959997
k_VBattMinAAS_Volt_f32	27.6812
k_VBattMinBSI_Volt_f32	14.5959997
k_VBattMinCAV_Volt_f32	4.31839991
k_VBattMinCMM388_Volt_f32	14.8233995
k_VBattMinCMM_Volt_f32	28.3400002
k_VBattMinESP_Volt_f32	27.6966
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	10899
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	51405
k_VitesseVehicleBVRampValidThresh_Cnt_u16	62772
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	48409
k_VitesseVehicleBVSigValidThresh_Cnt_u16	65411
k_VitesseVehicleBVSpeedPassThresh_kph_f32	173.739807
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	48865
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	55630
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3124877568
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	57136
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	146705152
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	189
target_SrlComInput_Per1_Batt_Volt_f32.value	11.2161999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3148613888
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	27
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.232283816
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	114
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1325234432
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	182
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	132520192
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	408860928
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1751603456
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3758094592
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	187
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1730713856
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3856742656
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	83
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	155
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	189
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	190
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	238
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2961987840
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4146886912
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	185
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3583318272
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	231
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3415062784
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2850392320
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1831
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.290927917
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	540655
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	145.2099
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	30600

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	146705152	146705152	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	12222	12222	✔
AASNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	34267	34267	✔
AngleVolantMsgTimer_mS_M_u32	146705152	146705152	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	51.4752731	51.4752731	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	1366	1366	✔
BSINodeAbsentTimer_mS_M_u32	146705152	146705152	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	146705152	146705152	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	146705152	146705152	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	146705152	146705152	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	64865	64865	✔
CMMNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	2738	2738	✔
CONSANGLECPK_HwDeg_M_f32	646.898499	646.898499 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2738	2738	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2454808832	2454808832	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	22109	22109	✔
CityParkInputConsistentCount_Cnt_M_u16	41574	41574	✔
CityParkInputInvalidCount_Cnt_M_u16	27092	27092	✔
CityParkInputMsgTimer_mS_M_u32	146705152	146705152	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	146705152	146705152	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	146705152	146705152	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	146705152	146705152	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	146705152	146705152	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	146705152	146705152	✔
ESPNTCEnableTimer_mS_M_u32	146705152	146705152	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	9	9	✔
EffacDefaultDiagTimer_mS_M_u32[1]	81	81	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	146705152	146705152	✔
ElecIntTimer_mS_M_u32[1]	45465	45465	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	146705152	146705152	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	146705152	146705152	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	146705152	146705152	✔
IgnOnTimer_mS_M_u32	146705152	146705152	✔
IgnTimeOff_Sec_M_u32	2619952977	2619952977	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	114	114	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1325234432	1325234432	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	182	182	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	132520192	132520192	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	222	222	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	408860928	408860928	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1751603456	1751603456	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	893368576	893368576	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	187	187	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1730713856	1730713856	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	129	129	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3856742656	3856742656	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	91	91	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2961987840	2961987840	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	48	48	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4146886912	4146886912	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	185	185	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3583318272	3583318272	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	231	231	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3415062784	3415062784	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2850392320	2850392320	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	221.728302	221.728302	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	151.130402	151.130402	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	198.469803	198.469803	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	51.4752731	51.4752731	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	2738	2738	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2619952977	2619952977	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	646.898499	646.898499 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	212.449402	212.449402	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.142 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2865203200
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	49530
AASNodeAbsentTimer_mS_M_u32	100202496
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	14674
ANGLEVOLANTSigValidCount_Cnt_M_u16	34609
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	57583
AngleVolantMsgTimer_mS_M_u32	2865203200
AngleVolantValidCount_Cnt_M_u16	22795
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	340.879272
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2011346944
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2273130496
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	137439232
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1509025792
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	7841
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3531974656
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	1887
CAVNodeAbsentTimer_mS_M_u32	2329319424
CDD_SrlComVehSpd_Kph_G_f32	179.719299
CMM388NTCEnableTimer_mS_M_u32	2996361216
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2256312320
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	38663
CMMNodeAbsentTimer_mS_M_u32	2429282304
CONSANGLECPKSigInvalidCount_Cnt_M_u16	59944
CONSANGLECPKSigValidCount_Cnt_M_u16	41175
CONSANGLECPK_Cnt_M_u16	39466
CONSANGLECPK_HwDeg_M_f32	200.123093
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	39466
CPKVehicleSpeedMsgTimer_mS_M_u32	1905166336
CPKVehicleSpeedValidCount_Cnt_M_u16	63602
CityParkInputConsistentCount_Cnt_M_u16	32207
CityParkInputInvalidCount_Cnt_M_u16	10378

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	1325234432
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1539110912
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	52286
ComputerRazGCTSigInvalidTimer_mS_M_u32	739448832
ComputerRazGCTSigValidCount_Cnt_M_u16	9276
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	65478
DMDFCTCPKSigValidCount_Cnt_M_u16	9933
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	27316
DMDRELAXECPKSigValidCount_Cnt_M_u16	24083
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	64157
DateInvalidTimer_mS_M_u32	2273130496
DiagMuxOnAbsentTimer_mS_M_u32	725305344
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1509025792
ESPNTCEnableTimer_mS_M_u32	686946304
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	5485
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	20
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	5656
ElecIntTimer_mS_M_u32[1]	78789
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3678906368
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	44578
EtatMTSigValidCount_Cnt_M_u16	2957
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	49546
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	40377
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	35955
ISDAT4V2BSI552MsgTimer_mS_M_u32	1905256448
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	51076
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	19447
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	2957
ISDATBSI3F2MsgTimer_mS_M_u32	2883143680
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	32512
ISDATBSI412MsgLenValidCount_Cnt_M_u16	37923
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	44578
ISDATBSI412MsgTimer_mS_M_u32	2170914816
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	58550
ISDATBSI432MsgLenValidCount_Cnt_M_u16	52273
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	8312
ISDATDIRASentFltAcc_Cnt_M_u16	47820
ISDATDIRASentTimer_mS_M_u32	1905166336
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	62792
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	22795
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	12949
ISDYN2CMMMsgTimer_mS_M_u32	3360421888
ISDYNAASChkSumInvalidCount_Cnt_M_u16	40668
ISDYNAASChkSumValidCount_Cnt_M_u16	35034
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	57818
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	29426
ISDYNAASMsgLenValidCount_Cnt_M_u16	36521
ISDYNAASMsgTimeValidCount_Cnt_M_u16	40668
ISDYNAASMsgTimer_mS_M_u32	1725224960
ISDYNABRChkSumInvalidCount_Cnt_M_u16	35580
ISDYNABRChkSumValidCount_Cnt_M_u16	9699
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	34347
ISDYNABRMsgCountValidCount_Cnt_M_u16	40297
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	31863
ISDYNABRMsgLenValidCount_Cnt_M_u16	41062
ISDYNABRMsgTimeValidCount_Cnt_M_u16	39466
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	744
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1373

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	2957
ISDYNCMM208MsgTimer_mS_M_u32	9418752
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2827
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1479
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	48809
ISDYNCMM388MsgTimer_mS_M_u32	3151779840
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	25286
ISDYNVOLChkSumValidCount_Cnt_M_u16	62453
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	25444
ISDYNVOLMsgCountValidCount_Cnt_M_u16	42219
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	34078
ISDYNVOLMsgLenValidCount_Cnt_M_u16	65453
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	38663
ISDYNVOLMsgTimer_mS_M_u32	743380992
IgnOnTimer_mS_M_u32	1604343808
IgnTimeOff_Sec_M_u32	787421853
ManVehSpd_Kph_M_f32	605.289124
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	109
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3294578688
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	174
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3546294272
PrevISDATBSI412MsgDLCError_Cnt_M_u08	213
PrevISDATBSI412MsgRxTime_MSec_M_u32	1957664768
PrevISDATBSI432MsgDLCError_Cnt_M_u08	80
PrevISDATBSI432MsgRxTime_MSec_M_u32	581302272
PrevISDATDIRAMsgTxTime_MSec_M_u32	3858995200
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	252
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1595631616
PrevISDYNAASMsgDLCError_Cnt_M_u08	87
PrevISDYNAASMsgRxTime_MSec_M_u32	2406291456
PrevISDYNABRMsgDLCError_Cnt_M_u08	76
PrevISDYNABRMsgRxTime_MSec_M_u32	3273152512
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	203
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4187625472
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	166
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4042848256
PrevISDYNVOLMsgDLCError_Cnt_M_u08	2
PrevISDYNVOLMsgRxTime_MSec_M_u32	1106548736
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1392740352
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	293.073486
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	11408
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	58055
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	42433
VitesseVehicleBVRampValidCount_Cnt_M_u16	36536
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	43011
VitesseVehicleBVSigValidCount_Cnt_M_u16	18594
VitesseVehicleBV_Kph_M_f32	40.8143997

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	48809
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	44608
VitesseVehiculeRoues_Kph_M_f32	523.088196
k_AASNTCEnableTimeout_mS_u16	30001
k_AASNodeAbsentDiag_Cnt_str.Threshold	3966
k_AASNodeAbsentDiag_Cnt_str.PStep	4396
k_AASNodeAbsentDiag_Cnt_str.NStep	22681
k_AASNodeAbsentTimeout_mS_u16	30742
k_AASNodeTimeout_mS_u16	19911
k_ABSNodeTimeout_mS_u16	15923
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	2817
k_ANGLEVOLANTSigValidThresh_Cnt_u16	42172
k_AngleVolantInvalidThresh_Cnt_u16	40851
k_AngleVolantValidThresh_Cnt_u16	10378
k_BSI552MsgTimeout_mS_u16	27607
k_BSINTCEnableTimeout_mS_u16	14382
k_BSINodeAbsentDiag_Cnt_str.Threshold	1479
k_BSINodeAbsentDiag_Cnt_str.PStep	1472
k_BSINodeAbsentDiag_Cnt_str.NStep	5950
k_BSINodeAbsentTimeout_mS_u16	5735
k_BSINodeTimeout_mS_u16	8312
k_BattOvHi_Volt_f32	30.3724995
k_BattOvLo_Volt_f32	16.3794003
k_BattUvHi_Volt_f32	29.4234009
k_BattUvLo_Volt_f32	24.9894009
k_CAVNTCEnableTimeout_mS_u16	17824
k_CAVNodeAbsentDiag_Cnt_str.Threshold	9382
k_CAVNodeAbsentDiag_Cnt_str.PStep	55279
k_CAVNodeAbsentDiag_Cnt_str.NStep	39790
k_CAVNodeAbsentTimeout_mS_u16	58365
k_CAVNodeTimeout_mS_u16	54884
k_CMM388MsgTimeout_mS_u16	27770
k_CMM388NTCEnableTimeout_mS_u16	41398
k_CMMNTCEnableTimeout_mS_u16	38652
k_CMMNodeAbsentDiag_Cnt_str.Threshold	22901
k_CMMNodeAbsentDiag_Cnt_str.PStep	37672
k_CMMNodeAbsentDiag_Cnt_str.NStep	44208
k_CMMNodeAbsentTimeout_mS_u16	2428
k_CONSANGLECPKMax_HwDeg_f32	19.2702999
k_CONSANGLECPKMin_HwDeg_f32	-737.098816
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	59817
k_CONSANGLECPKSigValidThresh_Cnt_u16	6464
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	54893
k_CPKVehicleSpeedValidThresh_Cnt_u16	62035
k_CityParkInputInvalidThresh_Cnt_u16	19490
k_CityParkInputValidThresh_Cnt_u16	32207
k_ComputerRazGCTSigValidThresh_Cnt_u16	46730
k_CptTemporelSigValidThresh_Cnt_u16	37757
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	10103
k_DMDFCTCPKSigValidThresh_Cnt_u16	35686
k_DMDFCTCPKValidCount_Cnt_u16	9257
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	12949
k_DMDRELAXECPKSigValidThresh_Cnt_u16	9948
k_DMDRelaxeConsistentThresh_Cnt_u16	10626
k_DateValidThresh_Cnt_u16	35955
k_DefaultVehSpd_Kph_f32	185.662704
k_DiagMuxOnAbsentTimeout_mS_u16	27840
k_EMNodeTimeout_mS_u16	42237
k_ESPNTCEnableTimeout_mS_u16	58779
k_ESPNodeAbsentDiag_Cnt_str.Threshold	35627
k_ESPNodeAbsentDiag_Cnt_str.PStep	56900
k_ESPNodeAbsentDiag_Cnt_str.NStep	34113
k_ESPNodeAbsentTimeout_mS_u16	65028
k_EtatMTSigInvalidThresh_Cnt_u16	60595
k_EtatMTSigValidThresh_Cnt_u16	13018
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	16544
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	30699
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	39168
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	54553
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	53068
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	49348
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	16331
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	48390

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	53370
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	34382
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	49809
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	61824
k_ISDATDIRASentDiag_Cnt_str.Threshold	34622
k_ISDATDIRASentDiag_Cnt_str.PStep	48742
k_ISDATDIRASentDiag_Cnt_str.NStep	16845
k_ISDATDIRASentTimeout_mS_u16	50488
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	17197
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	57583
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	24807
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	46588
k_ISDYNAASChkSumValidThresh_Cnt_u16	37091
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	12587
k_ISDYNAASMsgCountValidThresh_Cnt_u16	34921
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	48064
k_ISDYNAASMsgLenValidThresh_Cnt_u16	35467
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	1860
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	18453
k_ISDYNABRChkSumValidThresh_Cnt_u16	34436
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	51617
k_ISDYNABRMsgCountValidThresh_Cnt_u16	1216
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	41970
k_ISDYNABRMsgLenValidThresh_Cnt_u16	49261
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	64471
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	2388
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	20849
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	31326
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	58450
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	29233
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	16898
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	14795
k_ISDYNVOLChkSumValidThresh_Cnt_u16	24878
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	35810
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	8615
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	26974
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	64457
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	56841
k_IgnOnTimeout_mS_u16	51207
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	138.680801
k_PowerCutVehSpdLowThresh_Kph_f32	82.0635986
k_PowerCutVehSpdLowTimeout_mS_u16	47581
k_VBattMaxAAS_Volt_f32	4.86019993
k_VBattMaxBSI_Volt_f32	9.49559975
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	28.2570992
k_VBattMaxCMM_Volt_f32	8.95059967
k_VBattMaxESP_Volt_f32	28.6266003
k_VBattMinAAS_Volt_f32	27.7849007
k_VBattMinBSI_Volt_f32	28.6266003
k_VBattMinCAV_Volt_f32	30.8097
k_VBattMinCMM388_Volt_f32	3.48440003
k_VBattMinCMM_Volt_f32	17.6875
k_VBattMinESP_Volt_f32	8.95059967
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	44423
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	5530
k_VitesseVehicleBVRampValidThresh_Cnt_u16	36452
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	57077
k_VitesseVehicleBVSigValidThresh_Cnt_u16	6776
k_VitesseVehicleBVSpeedPassThresh_kph_f32	614.584229
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	12895
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	62934
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2273130496
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	11
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	15663
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2773426688
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	166

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	31
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	671000576
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	132
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0668352544
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	54
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3217709056
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2140174336
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2024183808
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4077697024
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	918738944
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2345203712
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	139
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	975116288
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	81
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	119
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	214
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	223
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	111
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4003313664
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	85
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	117
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	180
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	197
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	199
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	122
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1128093696
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2458089472
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3675887616
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	592586752
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	531
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.587683499
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	965787
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	42.1311989
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	25706

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	3966	3966	✔
AASNodeAbsentTimer_mS_M_u32	2773426688	2773426688	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2773426688	2773426688	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	340.879272	340.879272	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2773426688	2773426688	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2773426688	2773426688	✔
CDD_SrlComVehSpd_Kph_G_f32	605.289124	605.289124	✔
CMM388NTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	22901	22901	✔
CMMNodeAbsentTimer_mS_M_u32	2773426688	2773426688	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	39466	39466	✔
CONSANGLECPK_HwDeg_M_f32	200.123093	200.123093 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2773426688	2773426688	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2773426688	2773426688	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2773426688	2773426688	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2773426688	2773426688	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2773426688	2773426688	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2773426688	2773426688	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2773426688	2773426688	✔
ESPNTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	35627	35627	✔
ESPNodeAbsentTimer_mS_M_u32	2773426688	2773426688	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	20	20	✔
ElecIntCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	5656	5656	✔
ElecIntTimer_mS_M_u32[1]	78789	78789	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2773426688	2773426688	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	35955	35955	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	2957	2957	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	44578	44578	✔
ISDATBSI412MsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	8312	8312	✔
ISDATBSI432MsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2773426688	2773426688	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	12949	12949	✔
ISDYN2CMMMsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	40668	40668	✔
ISDYNAASMsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	39466	39466	✔
ISDYNABRMsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	2957	2957	✔
ISDYNCMM208MsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	48809	48809	✔
ISDYNCMM388MsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	38663	38663	✔
ISDYNVOLMsgTimer_mS_M_u32	2773426688	2773426688	✔
IgnOnTimer_mS_M_u32	1604343808	1604343808	✔
IgnTimeOff_Sec_M_u32	787421853	787421853	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	54	54	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3217709056	3217709056	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	53	53	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2140174336	2140174336	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	200	200	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2024183808	2024183808	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	57	57	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4077697024	4077697024	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3858995200	3858995200	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	210	210	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2345203712	2345203712	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	139	139	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	975116288	975116288	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	111	111	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4003313664	4003313664	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	122	122	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1128093696	1128093696	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	168	168	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2458089472	2458089472	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3675887616	3675887616	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	592586752	592586752	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	293.073486	293.073486	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	40.8143997	40.8143997	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	523.088196	523.088196	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	340.879272	340.879272	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	39466	39466	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	787421853	787421853	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	200.123093	200.123093 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	605.289124	605.289124	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.143 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	728247040
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	53584
AASNodeAbsentTimer_mS_M_u32	3952335616
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	27591
ANGLEVOLANTSigValidCount_Cnt_M_u16	59882
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	34545
AngleVolantMsgTimer_mS_M_u32	728247040
AngleVolantValidCount_Cnt_M_u16	14109
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	409.650574
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1826003712
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3355908864
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1101744896
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1063848704
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	47066
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3568159488
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	7711
CAVNodeAbsentTimer_mS_M_u32	1534786304
CDD_SrlComVehSpd_Kph_G_f32	214.5952
CMM388NTCEnableTimer_mS_M_u32	3174316800
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2156460800
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	4646
CMMNodeAbsentTimer_mS_M_u32	0
CONSANGLECPKSigInvalidCount_Cnt_M_u16	57413
CONSANGLECPKSigValidCount_Cnt_M_u16	25593
CONSANGLECPK_Cnt_M_u16	33792
CONSANGLECPK_HwDeg_M_f32	17.4645996
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	33792
CPKVehicleSpeedMsgTimer_mS_M_u32	3004377856
CPKVehicleSpeedValidCount_Cnt_M_u16	50512
CityParkInputConsistentCount_Cnt_M_u16	55505
CityParkInputInvalidCount_Cnt_M_u16	54687
CityParkInputMsgTimer_mS_M_u32	3217709056
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4199013120
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	49412

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	163937024
ComputerRazGCTSigValidCount_Cnt_M_u16	55690
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	16363
DMDFCTCPKSigValidCount_Cnt_M_u16	53910
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	57249
DMDRELAXECPKSigValidCount_Cnt_M_u16	27972
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	49894
DateInvalidTimer_mS_M_u32	3355908864
DiagMuxOnAbsentTimer_mS_M_u32	688712448
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1063848704
ESPNTCEnableTimer_mS_M_u32	2796083968
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	21621
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	80
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	5
ElecIntTimer_mS_M_u32[1]	87788
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1114098432
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	32664
EtatMTSigValidCount_Cnt_M_u16	65303
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	25119
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	30035
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	47524
ISDAT4V2BSI552MsgTimer_mS_M_u32	4035906304
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	13553
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	24408
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	65303
ISDATBSI3F2MsgTimer_mS_M_u32	2670914304
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	20348
ISDATBSI412MsgLenValidCount_Cnt_M_u16	34771
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	32664
ISDATBSI412MsgTimer_mS_M_u32	2676894464
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	7898
ISDATBSI432MsgLenValidCount_Cnt_M_u16	16425
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	30420
ISDATDIRASentFltAcc_Cnt_M_u16	63448
ISDATDIRASentTimer_mS_M_u32	3004377856
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	27302
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	14109
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	41854
ISDYN2CMMMsgTimer_mS_M_u32	2962938624
ISDYNAASChkSumInvalidCount_Cnt_M_u16	16682
ISDYNAASChkSumValidCount_Cnt_M_u16	27373
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	39088
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	59238
ISDYNAASMsgLenValidCount_Cnt_M_u16	23553
ISDYNAASMsgTimeValidCount_Cnt_M_u16	16682
ISDYNAASMsgTimer_mS_M_u32	2424322816
ISDYNABRChkSumInvalidCount_Cnt_M_u16	38984
ISDYNABRChkSumValidCount_Cnt_M_u16	20307
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	34621
ISDYNABRMsgCountValidCount_Cnt_M_u16	10560
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	9560
ISDYNABRMsgLenValidCount_Cnt_M_u16	24908
ISDYNABRMsgTimeValidCount_Cnt_M_u16	33792
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	745
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1375
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	65303
ISDYNCMM208MsgTimer_mS_M_u32	3335494400
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2831
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1481
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	65091

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	258587392
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	28267
ISDYNVOLChkSumValidCount_Cnt_M_u16	25247
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	3345
ISDYNVOLMsgCountValidCount_Cnt_M_u16	20540
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	2402
ISDYNVOLMsgLenValidCount_Cnt_M_u16	49525
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	4646
ISDYNVOLMsgTimer_mS_M_u32	4178672384
IgnOnTimer_mS_M_u32	874363648
IgnTimeOff_Sec_M_u32	1970578992
ManVehSpd_Kph_M_f32	255.052505
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	111
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	204
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3986746112
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	210
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1545489152
PrevISDATBSI412MsgDLCError_Cnt_M_u08	223
PrevISDATBSI412MsgRxTime_MSec_M_u32	1106246400
PrevISDATBSI432MsgDLCError_Cnt_M_u08	49
PrevISDATBSI432MsgRxTime_MSec_M_u32	2307709696
PrevISDATDIRAMsgTxTime_MSec_M_u32	1039399680
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	165
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3052178176
PrevISDYNAASMsgDLCError_Cnt_M_u08	49
PrevISDYNAASMsgRxTime_MSec_M_u32	3350690560
PrevISDYNABRMsgDLCError_Cnt_M_u08	84
PrevISDYNABRMsgRxTime_MSec_M_u32	3921001216
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	119
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2100329216
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	242
PrevISDYNCMM388MsgRxTime_MSec_M_u32	714332928
PrevISDYNVOLMsgDLCError_Cnt_M_u08	6
PrevISDYNVOLMsgRxTime_MSec_M_u32	773913344
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	582232832
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	515.489502
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	45708
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	22439
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	19193
VitesseVehicleBVRampValidCount_Cnt_M_u16	22484
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	9140
VitesseVehicleBVSigValidCount_Cnt_M_u16	43415
VitesseVehicleBV_Kph_M_f32	39.0656013
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	65091
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	30526
VitesseVehiculeRoues_Kph_M_f32	1.06760001
k_AASNTCEnableTimeout_mS_u16	52971
k_AASNodeAbsentDiag_Cnt_str.Threshold	22169

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	64616
k_AASNodeAbsentDiag_Cnt_str.NStep	45624
k_AASNodeAbsentTimeout_mS_u16	50684
k_AASNodeTimeout_mS_u16	5799
k_ABSNodeTimeout_mS_u16	30884
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	38905
k_ANGLEVOLANTSigValidThresh_Cnt_u16	41608
k_AngleVolantInvalidThresh_Cnt_u16	52739
k_AngleVolantValidThresh_Cnt_u16	54687
k_BSI552MsgTimeout_mS_u16	23161
k_BSINTCEnableTimeout_mS_u16	1138
k_BSINodeAbsentDiag_Cnt_str.Threshold	1592
k_BSINodeAbsentDiag_Cnt_str.PStep	1578
k_BSINodeAbsentDiag_Cnt_str.NStep	6792
k_BSINodeAbsentTimeout_mS_u16	50825
k_BSINodeTimeout_mS_u16	30420
k_BattOvHi_Volt_f32	27.8370991
k_BattOvLo_Volt_f32	16.0832005
k_BattUvHi_Volt_f32	6.37290001
k_BattUvLo_Volt_f32	26.7523994
k_CAVNTCEnableTimeout_mS_u16	22109
k_CAVNodeAbsentDiag_Cnt_str.Threshold	29211
k_CAVNodeAbsentDiag_Cnt_str.PStep	856
k_CAVNodeAbsentDiag_Cnt_str.NStep	33585
k_CAVNodeAbsentTimeout_mS_u16	32837
k_CAVNodeTimeout_mS_u16	2961
k_CMM388MsgTimeout_mS_u16	53328
k_CMM388NTCEnableTimeout_mS_u16	8348
k_CMMNTCEnableTimeout_mS_u16	42633
k_CMMNodeAbsentDiag_Cnt_str.Threshold	57366
k_CMMNodeAbsentDiag_Cnt_str.PStep	33493
k_CMMNodeAbsentDiag_Cnt_str.NStep	16212
k_CMMNodeAbsentTimeout_mS_u16	21898
k_CONSANGLECPKMax_HwDeg_f32	93.9505997
k_CONSANGLECPKMin_HwDeg_f32	-49.9235992
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	32067
k_CONSANGLECPKSigValidThresh_Cnt_u16	13886
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	38069
k_CPKVehicleSpeedValidThresh_Cnt_u16	387
k_CityParkInputInvalidThresh_Cnt_u16	27862
k_CityParkInputValidThresh_Cnt_u16	55505
k_ComputerRazGCTSigValidThresh_Cnt_u16	65503
k_CptTemporelSigValidThresh_Cnt_u16	8390
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	9304
k_DMDFCTCPKSigValidThresh_Cnt_u16	41036
k_DMDFCTCPKValidCount_Cnt_u16	51010
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	41854
k_DMDRELAXECPKSigValidThresh_Cnt_u16	52841
k_DMDRelaxeConsistentThresh_Cnt_u16	56951
k_DateValidThresh_Cnt_u16	47524
k_DefaultVehSpd_Kph_f32	175.257004
k_DiagMuxOnAbsentTimeout_mS_u16	58430
k_EMNodeTimeout_mS_u16	17350
k_ESPNTCEnableTimeout_mS_u16	29547
k_ESPNodeAbsentDiag_Cnt_str.Threshold	2516
k_ESPNodeAbsentDiag_Cnt_str.PStep	51552
k_ESPNodeAbsentDiag_Cnt_str.NStep	65154
k_ESPNodeAbsentTimeout_mS_u16	38898
k_EtatMTSigInvalidThresh_Cnt_u16	3875
k_EtatMTSigValidThresh_Cnt_u16	50286
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	57884
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	21500
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	35646
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	41010
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	26969
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	39472
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	41371
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	426
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	27534
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	20372
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	37515
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	18683
k_ISDATDIRASentDiag_Cnt_str.Threshold	21203

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	38003
k_ISDATDIRASentDiag_Cnt_str.NStep	12439
k_ISDATDIRASentTimeout_mS_u16	55700
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	18420
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	34545
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	12679
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	5960
k_ISDYNAASChkSumValidThresh_Cnt_u16	3667
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	34365
k_ISDYNAASMsgCountValidThresh_Cnt_u16	26688
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	5628
k_ISDYNAASMsgLenValidThresh_Cnt_u16	28763
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39664
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	47742
k_ISDYNABRChkSumValidThresh_Cnt_u16	42738
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	46810
k_ISDYNABRMsgCountValidThresh_Cnt_u16	27965
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	53542
k_ISDYNABRMsgLenValidThresh_Cnt_u16	21365
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	41976
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	11328
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	56361
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	44258
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	27335
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	10474
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	26935
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	2843
k_ISDYNVOLChkSumValidThresh_Cnt_u16	3250
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	1302
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	27655
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	15844
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	7779
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	40162
k_IgnOnTimeout_mS_u16	20583
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	150.702805
k_PowerCutVehSpdLowThresh_Kph_f32	72.5543976
k_PowerCutVehSpdLowTimeout_mS_u16	45287
k_VBattMaxAAS_Volt_f32	23.3493004
k_VBattMaxBSI_Volt_f32	21.6247005
k_VBattMaxCAV_Volt_f32	7.54540014
k_VBattMaxCMM388_Volt_f32	11.8431997
k_VBattMaxCMM_Volt_f32	10.6913996
k_VBattMaxESP_Volt_f32	10.5416002
k_VBattMinAAS_Volt_f32	29.8243999
k_VBattMinBSI_Volt_f32	10.5416002
k_VBattMinCAV_Volt_f32	23.9403
k_VBattMinCMM388_Volt_f32	27.3477993
k_VBattMinCMM_Volt_f32	18.4797993
k_VBattMinESP_Volt_f32	10.6913996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	61670
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	61550
k_VitesseVehicleBVRampValidThresh_Cnt_u16	35857
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	41375
k_VitesseVehicleBVSigValidThresh_Cnt_u16	59094
k_VitesseVehicleBVSpeedPassThresh_kph_f32	331.002197
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	40223
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	6778
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3355908864
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	67
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14703
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1924750592
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	242
target_SrlComInput_Per1_Batt_Volt_f32.value	16.5974007
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4165126912
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	106
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.653045833
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1000323840
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1020091136
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	250
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3523934976
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	593009408
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1488337664
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2586041088
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	179
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	262241024
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	20
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	41
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	64
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	91
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3030752000
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	64
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	65
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	90
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	176
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	183
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1028045568
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2415155968
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	917633792
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	77
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	101
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3024636672
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2214
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.460754216
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	682356
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	105.601501
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	62206

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1924750592	1924750592	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	34547	34547	✔
AngleVolantMsgTimer_mS_M_u32	1924750592	1924750592	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	409.650574	409.650574	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1826003712	1826003712	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	3355908864	3355908864	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	1101744896	1101744896	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	1063848704	1063848704	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	1592	1592	✔
BSINodeAbsentTimer_mS_M_u32	1924750592	1924750592	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1924750592	1924750592	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2586041088	2586041088	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	33792	33792	✔
CONSANGLECPK_HwDeg_M_f32	17.4645996	17.4645996 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	33792	33792	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3004377856	3004377856	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	50512	50512	✔
CityParkInputConsistentCount_Cnt_M_u16	55505	55505	✔
CityParkInputInvalidCount_Cnt_M_u16	54687	54687	✔
CityParkInputMsgTimer_mS_M_u32	1924750592	1924750592	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1924750592	1924750592	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1924750592	1924750592	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3355908864	3355908864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1924750592	1924750592	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1924750592	1924750592	✔
ESPNTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	2516	2516	✔
ESPNodeAbsentTimer_mS_M_u32	1924750592	1924750592	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	80	80	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1924750592	1924750592	✔
ElecIntTimer_mS_M_u32[1]	87788	87788	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1924750592	1924750592	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	25120	25120	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1000323840	1000323840	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	13554	13554	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1020091136	1020091136	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	20349	20349	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3523934976	3523934976	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	7899	7899	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	593009408	593009408	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1924750592	1924750592	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1924750592	1924750592	✔
IgnOnTimer_mS_M_u32	874363648	874363648	✔
IgnTimeOff_Sec_M_u32	1970578992	1970578992	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	46	46	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1000323840	1000323840	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	212	212	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1020091136	1020091136	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	250	250	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3523934976	3523934976	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	200	200	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	593009408	593009408	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1039399680	1039399680	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	253	253	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2586041088	2586041088	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	179	179	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	262241024	262241024	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	169	169	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3030752000	3030752000	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	238	238	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1028045568	1028045568	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2415155968	2415155968	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	94	94	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	917633792	917633792	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3024636672	3024636672	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	515.489502	515.489502	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	39.0656013	39.0656013	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	1.06760001	1.06760001	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	409.650574	409.650574	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	33792	33792	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1970578992	1970578992	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	17.4645996	17.4645996 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	175.257004	175.257004	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.144 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1808941568
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	48152
AASNodeAbsentTimer_mS_M_u32	3054449152
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	59061
ANGLEVOLANTSigValidCount_Cnt_M_u16	13579
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	24373
AngleVolantMsgTimer_mS_M_u32	1808941568
AngleVolantValidCount_Cnt_M_u16	1330
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	583.609863
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2907107840
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4256526848
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2642993664
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3410993664
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	3708

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	243360256
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	31275
CAVNodeAbsentTimer_mS_M_u32	1792659968
CDD_SrlComVehSpd_Kph_G_f32	10.7391996
CMM388NTCEnableTimer_mS_M_u32	3131970048
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3014644224
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	984
CMMNodeAbsentTimer_mS_M_u32	4294967295
CONSANGLECPKSigInvalidCount_Cnt_M_u16	62521
CONSANGLECPKSigValidCount_Cnt_M_u16	29151
CONSANGLECPK_Cnt_M_u16	60874
CONSANGLECPK_HwDeg_M_f32	353.832306
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	60874
CPKVehicleSpeedMsgTimer_mS_M_u32	1087455744
CPKVehicleSpeedValidCount_Cnt_M_u16	46433
CityParkInputConsistentCount_Cnt_M_u16	61462
CityParkInputInvalidCount_Cnt_M_u16	684
CityParkInputMsgTimer_mS_M_u32	1000323840
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1509110272
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	48380
ComputerRazGCTSigInvalidTimer_mS_M_u32	2851754496
ComputerRazGCTSigValidCount_Cnt_M_u16	4587
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	62408
DMDFCTCPKSigValidCount_Cnt_M_u16	9350
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	29479
DMDRELAXECPKSigValidCount_Cnt_M_u16	37629
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	4182
DateInvalidTimer_mS_M_u32	4256526848
DiagMuxOnAbsentTimer_mS_M_u32	4125360640
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3410993664
ESPNTCEnableTimer_mS_M_u32	416297472
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	46506
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	150
EffacDefaultDiagTimer_mS_M_u32[1]	1150
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	2324
ElecIntTimer_mS_M_u32[1]	45465
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	760439296
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	21633
EtatMTSigValidCount_Cnt_M_u16	3779
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	22187
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	9681
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	10076
ISDAT4V2BSI552MsgTimer_mS_M_u32	3487408640
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	12278
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	35201
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	3779
ISDATBSI3F2MsgTimer_mS_M_u32	2876375552
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	7508
ISDATBSI412MsgLenValidCount_Cnt_M_u16	3343
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	21633
ISDATBSI412MsgTimer_mS_M_u32	660619776
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	44476
ISDATBSI432MsgLenValidCount_Cnt_M_u16	49806
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	33804
ISDATDIRASentFltAcc_Cnt_M_u16	4352
ISDATDIRASentTimer_mS_M_u32	1087455744

Name	Input Value
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	20952
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	1330
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	54543
ISDYN2CMMMsgTimer_mS_M_u32	1123693056
ISDYNAASChkSumInvalidCount_Cnt_M_u16	21642
ISDYNAASChkSumValidCount_Cnt_M_u16	8193
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	60537
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	64086
ISDYNAASMsgLenValidCount_Cnt_M_u16	17732
ISDYNAASMsgTimeValidCount_Cnt_M_u16	21642
ISDYNAASMsgTimer_mS_M_u32	1892291072
ISDYNABRChkSumInvalidCount_Cnt_M_u16	64690
ISDYNABRChkSumValidCount_Cnt_M_u16	16465
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	36433
ISDYNABRMsgCountValidCount_Cnt_M_u16	61704
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	12544
ISDYNABRMsgLenValidCount_Cnt_M_u16	34278
ISDYNABRMsgTimeValidCount_Cnt_M_u16	60874
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	746
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1377
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	3779
ISDYNCMM208MsgTimer_mS_M_u32	3277582848
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2835
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1483
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	51136
ISDYNCMM388MsgTimer_mS_M_u32	2047709696
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	25031
ISDYNVOLChkSumValidCount_Cnt_M_u16	36333
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	42070
ISDYNVOLMsgCountValidCount_Cnt_M_u16	50068
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	35555
ISDYNVOLMsgLenValidCount_Cnt_M_u16	60265
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	984
ISDYNVOLMsgTimer_mS_M_u32	202789376
IgnOnTimer_mS_M_u32	3690041856
IgnTimeOff_Sec_M_u32	1609937275
ManVehSpd_Kph_M_f32	532.247314
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	113
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	111
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4163371520
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	92
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3660571136
PrevISDATBSI412MsgDLCError_Cnt_M_u08	176
PrevISDATBSI412MsgRxTime_MSec_M_u32	3413824000
PrevISDATBSI432MsgDLCError_Cnt_M_u08	118
PrevISDATBSI432MsgRxTime_MSec_M_u32	2372096
PrevISDATDIRAMsgTxTime_MSec_M_u32	3882799616
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	172
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3586466304
PrevISDYNAASMsgDLCError_Cnt_M_u08	51
PrevISDYNAASMsgRxTime_MSec_M_u32	3089388032
PrevISDYNABRMsgDLCError_Cnt_M_u08	196
PrevISDYNABRMsgRxTime_MSec_M_u32	455709184
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	122
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3149484544
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	231
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4178522624
PrevISDYNVOLMsgDLCError_Cnt_M_u08	45
PrevISDYNVOLMsgRxTime_MSec_M_u32	182964736
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3052290560
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	466.885315

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	45284
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	27218
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	56221
VitesseVehicleBVRampValidCount_Cnt_M_u16	24011
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	45806
VitesseVehicleBVSigValidCount_Cnt_M_u16	59908
VitesseVehicleBV_Kph_M_f32	345.040894
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	51136
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	34191
VitesseVehiculeRoues_Kph_M_f32	170.604202
k_AASNTCEnableTimeout_mS_u16	30985
k_AASNodeAbsentDiag_Cnt_str.Threshold	26660
k_AASNodeAbsentDiag_Cnt_str.PStep	56551
k_AASNodeAbsentDiag_Cnt_str.NStep	46206
k_AASNodeAbsentTimeout_mS_u16	38037
k_AASNodeTimeout_mS_u16	11602
k_ABSNodeTimeout_mS_u16	28061
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	32351
k_ANGLEVOLANTSigValidThresh_Cnt_u16	55153
k_AngleVolantInvalidThresh_Cnt_u16	256
k_AngleVolantValidThresh_Cnt_u16	684
k_BSI552MsgTimeout_mS_u16	34782
k_BSINTCEnableTimeout_mS_u16	23796
k_BSINodeAbsentDiag_Cnt_str.Threshold	1705
k_BSINodeAbsentDiag_Cnt_str.PStep	1684
k_BSINodeAbsentDiag_Cnt_str.NStep	7634
k_BSINodeAbsentTimeout_mS_u16	109
k_BSINodeTimeout_mS_u16	33804
k_BattOvHi_Volt_f32	29.0063
k_BattOvLo_Volt_f32	30.4666004
k_BattUvHi_Volt_f32	3.83349991
k_BattUvLo_Volt_f32	18.9619999
k_CAVNTCEnableTimeout_mS_u16	63602
k_CAVNodeAbsentDiag_Cnt_str.Threshold	48338
k_CAVNodeAbsentDiag_Cnt_str.PStep	23322
k_CAVNodeAbsentDiag_Cnt_str.NStep	29493
k_CAVNodeAbsentTimeout_mS_u16	27577
k_CAVNodeTimeout_mS_u16	41557
k_CMM388MsgTimeout_mS_u16	48920
k_CMM388NTCEnableTimeout_mS_u16	65076
k_CMMNTCEnableTimeout_mS_u16	15150
k_CMMNodeAbsentDiag_Cnt_str.Threshold	34710
k_CMMNodeAbsentDiag_Cnt_str.PStep	1129
k_CMMNodeAbsentDiag_Cnt_str.NStep	49168
k_CMMNodeAbsentTimeout_mS_u16	6827
k_CONSANGLECPKMax_HwDeg_f32	389.448395
k_CONSANGLECPKMin_HwDeg_f32	-514.984924
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	19136
k_CONSANGLECPKSigValidThresh_Cnt_u16	18575
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	27432
k_CPKVehicleSpeedValidThresh_Cnt_u16	58175
k_CityParkInputInvalidThresh_Cnt_u16	14088
k_CityParkInputValidThresh_Cnt_u16	61462
k_ComputerRazGCTSigValidThresh_Cnt_u16	1836
k_CptTemporelSigValidThresh_Cnt_u16	32055
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	13312
k_DMDFCTCPKSigValidThresh_Cnt_u16	51430
k_DMDFCTCPKValidCount_Cnt_u16	32836

Name	Input Value
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	54543
k_DMDRELAXECPKSigValidThresh_Cnt_u16	15629
k_DMDRelaxeConsistentThresh_Cnt_u16	50403
k_DateValidThresh_Cnt_u16	10076
k_DefaultVehSpd_Kph_f32	206.770996
k_DiagMuxOnAbsentTimeout_mS_u16	17680
k_EMNodeTimeout_mS_u16	3510
k_ESPNTCEnableTimeout_mS_u16	43591
k_ESPNodeAbsentDiag_Cnt_str.Threshold	49114
k_ESPNodeAbsentDiag_Cnt_str.PStep	2558
k_ESPNodeAbsentDiag_Cnt_str.NStep	40693
k_ESPNodeAbsentTimeout_mS_u16	62323
k_EtatMTSigInvalidThresh_Cnt_u16	50209
k_EtatMTSigValidThresh_Cnt_u16	3328
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	57075
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	16918
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	52431
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	12851
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	44926
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	3384
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	27001
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	49675
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	38816
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	56078
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	10984
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	15831
k_ISDATDIRASentDiag_Cnt_str.Threshold	255
k_ISDATDIRASentDiag_Cnt_str.PStep	39431
k_ISDATDIRASentDiag_Cnt_str.NStep	31970
k_ISDATDIRASentTimeout_mS_u16	26830
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	25836
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	24373
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	57331
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	32690
k_ISDYNAASChkSumValidThresh_Cnt_u16	849
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	37201
k_ISDYNAASMsgCountValidThresh_Cnt_u16	13320
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	21398
k_ISDYNAASMsgLenValidThresh_Cnt_u16	61494
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	36409
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	35214
k_ISDYNABRChkSumValidThresh_Cnt_u16	52468
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	4476
k_ISDYNABRMsgCountValidThresh_Cnt_u16	46866
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	50904
k_ISDYNABRMsgLenValidThresh_Cnt_u16	47274
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	48865
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	5064
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	27469
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	5793
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	59829
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	30731
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	42980
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	9847
k_ISDYNVOLChkSumValidThresh_Cnt_u16	47730
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	26567
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	47669
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	18845
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	57567
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	62882
k_IgnOnTimeout_mS_u16	34451
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	8.93360043
k_PowerCutVehSpdLowThresh_Kph_f32	219.378906
k_PowerCutVehSpdLowTimeout_mS_u16	49941
k_VBattMaxAAS_Volt_f32	28.7642002
k_VBattMaxBSI_Volt_f32	30.3929005
k_VBattMaxCAV_Volt_f32	6.79199982
k_VBattMaxCMM388_Volt_f32	19.2287998
k_VBattMaxCMM_Volt_f32	1.89789999
k_VBattMaxESP_Volt_f32	23.7136002
k_VBattMinAAS_Volt_f32	14.5916996
k_VBattMinBSI_Volt_f32	23.7136002

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinCAV_Volt_f32	22.6728992
k_VBattMinCMM388_Volt_f32	17.1553993
k_VBattMinCMM_Volt_f32	8.53579998
k_VBattMinESP_Volt_f32	1.89789999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	45590
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	3136
k_VitesseVehicleBVRampValidThresh_Cnt_u16	10070
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	53485
k_VitesseVehicleBVSigValidThresh_Cnt_u16	6663
k_VitesseVehicleBVSpeedPassThresh_kph_f32	649.233215
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	64811
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	11737
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4256526848
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	239
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	61949
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2435230720
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	231
target_SrlComInput_Per1_Batt_Volt_f32.value	18.6504993
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	935485952
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	71
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.436452806
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1298895360
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2288169472
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1193923072
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	297857536
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1881674240
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	25
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3932107264
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	140923392
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	8
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	118
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	130
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	139
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3520721408
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	123
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	218
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	236
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2759234048
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3941446144

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1966395904
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	45
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	166
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	167
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4189184512
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	656
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.821625054
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	895166
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	124.487602
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	14222

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1808941568	1808941568	✔
AASNTCsEnabled_Cnt_M_lgc	1	1	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2435230720	2435230720	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	24373	24373	✔
AngleVolantMsgTimer_mS_M_u32	2435230720	2435230720	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	583.609863	583.609863	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	1705	1705	✔
BSINodeAbsentTimer_mS_M_u32	2435230720	2435230720	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2435230720	2435230720	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3932107264	3932107264	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	62521	62521	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	60874	60874	✔
CONSANGLECPK_HwDeg_M_f32	353.832306	353.832306 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	60874	60874	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1087455744	1087455744	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	46433	46433	✔
CityParkInputConsistentCount_Cnt_M_u16	61462	61462	✔
CityParkInputInvalidCount_Cnt_M_u16	686	686	✔
CityParkInputMsgTimer_mS_M_u32	2435230720	2435230720	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2435230720	2435230720	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ComputerRazGCTSigInvalidTimer_mS_M_u32	2435230720	2435230720	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	62408	62408	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	29479	29479	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2435230720	2435230720	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2435230720	2435230720	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2435230720	2435230720	✔
ESPNTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	49114	49114	✔
ESPNodeAbsentTimer_mS_M_u32	2435230720	2435230720	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	150	150	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1150	1150	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2435230720	2435230720	✔
ElecIntTimer_mS_M_u32[1]	45465	45465	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2435230720	2435230720	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2435230720	2435230720	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	21642	21642	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	60537	60537	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	64086	64086	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	140923392	140923392	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2435230720	2435230720	✔
IgnOnTimer_mS_M_u32	3690041856	3690041856	✔
IgnTimeOff_Sec_M_u32	1609937275	1609937275	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	110	110	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1298895360	1298895360	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	154	154	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2288169472	2288169472	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	134	134	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1193923072	1193923072	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	186	186	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	297857536	297857536	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3882799616	3882799616	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	25	25	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3932107264	3932107264	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	84	84	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	140923392	140923392	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	139	139	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3520721408	3520721408	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	136	136	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2759234048	2759234048	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	95	95	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3941446144	3941446144	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	183	183	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1966395904	1966395904	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4189184512	4189184512	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	466.885315	466.885315	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	345.040894	345.040894	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	170.604202	170.604202	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	583.609863	583.609863	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	60874	60874	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1609937275	1609937275	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	353.832306	353.832306 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	206.770996	206.770996	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0148	0x0148	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.145 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2477784320
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	56540
AASNodeAbsentTimer_mS_M_u32	347680000
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	28422
ANGLEVOLANTSigValidCount_Cnt_M_u16	10691
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	42885
AngleVolantMsgTimer_mS_M_u32	2477784320
AngleVolantValidCount_Cnt_M_u16	37390
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	347.261261
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3188845824
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2798021888
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2701925632
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2729958656

Name	Input Value
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	54193
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3491929344
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	46372
CAVNodeAbsentTimer_mS_M_u32	3906555136
CDD_SrlComVehSpd_Kph_G_f32	386.715393
CMM388NTCEnableTimer_mS_M_u32	2589756672
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3864481024
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	59102
CMMNodeAbsentTimer_mS_M_u32	2869196288
CONSANGLECPKSigInvalidCount_Cnt_M_u16	1403
CONSANGLECPKSigValidCount_Cnt_M_u16	29256
CONSANGLECPK_Cnt_M_u16	27271
CONSANGLECPK_HwDeg_M_f32	272.239899
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	27271
CPKVehicleSpeedMsgTimer_mS_M_u32	3501391104
CPKVehicleSpeedValidCount_Cnt_M_u16	37161
CityParkInputConsistentCount_Cnt_M_u16	24930
CityParkInputInvalidCount_Cnt_M_u16	3746
CityParkInputMsgTimer_mS_M_u32	1298895360
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3104648448
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	27184
ComputerRazGCTSigInvalidTimer_mS_M_u32	1299696896
ComputerRazGCTSigValidCount_Cnt_M_u16	36835
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	43854
DMDFCTCPKSigValidCount_Cnt_M_u16	24275
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	4528
DMDRELAXECPKSigValidCount_Cnt_M_u16	22509
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	25892
DateInvalidTimer_mS_M_u32	2798021888
DiagMuxOnAbsentTimer_mS_M_u32	1819983104
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2729958656
ESPNTCEnableTimer_mS_M_u32	813051136
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	26407
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	64
EffacDefaultDiagTimer_mS_M_u32[1]	894
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	565
ElecIntTimer_mS_M_u32[1]	78789
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1001168128
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	10722
EtatMTSigValidCount_Cnt_M_u16	20699
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	9765
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	40562
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	11857
ISDAT4V2BSI552MsgTimer_mS_M_u32	1292754176
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	42242
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	3619
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	20699
ISDATBSI3F2MsgTimer_mS_M_u32	64011520
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	9703
ISDATBSI412MsgLenValidCount_Cnt_M_u16	35960
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	10722
ISDATBSI412MsgTimer_mS_M_u32	419822848
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	31026
ISDATBSI432MsgLenValidCount_Cnt_M_u16	53371
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	23425

Name	Input Value
ISDATDIRASentFltAcc_Cnt_M_u16	33957
ISDATDIRASentTimer_mS_M_u32	3501391104
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	63069
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	37390
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	58233
ISDYN2CMMMsgTimer_mS_M_u32	3656920320
ISDYNAASChkSumInvalidCount_Cnt_M_u16	23430
ISDYNAASChkSumValidCount_Cnt_M_u16	7907
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	47161
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	41123
ISDYNAASMsgLenValidCount_Cnt_M_u16	50584
ISDYNAASMsgTimeValidCount_Cnt_M_u16	23430
ISDYNAASMsgTimer_mS_M_u32	3892874496
ISDYNABRChkSumInvalidCount_Cnt_M_u16	23182
ISDYNABRChkSumValidCount_Cnt_M_u16	21875
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	35377
ISDYNABRMsgCountValidCount_Cnt_M_u16	34766
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	11046
ISDYNABRMsgLenValidCount_Cnt_M_u16	4659
ISDYNABRMsgTimeValidCount_Cnt_M_u16	27271
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	747
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1379
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	20699
ISDYNCMM208MsgTimer_mS_M_u32	265481472
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2839
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1485
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	612
ISDYNCMM388MsgTimer_mS_M_u32	977145088
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	29905
ISDYNVOLChkSumValidCount_Cnt_M_u16	54814
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	20900
ISDYNVOLMsgCountValidCount_Cnt_M_u16	14761
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	2940
ISDYNVOLMsgLenValidCount_Cnt_M_u16	20392
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	59102
ISDYNVOLMsgTimer_mS_M_u32	2535705856
IgnOnTimer_mS_M_u32	2761035008
IgnTimeOff_Sec_M_u32	92858324
ManVehSpd_Kph_M_f32	175.251602
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	115
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	206
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1974385920
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	14
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1192697088
PrevISDATBSI412MsgDLCError_Cnt_M_u08	160
PrevISDATBSI412MsgRxTime_MSec_M_u32	2331397376
PrevISDATBSI432MsgDLCError_Cnt_M_u08	27
PrevISDATBSI432MsgRxTime_MSec_M_u32	3397004544
PrevISDATDIRAMsgTxTime_MSec_M_u32	119164160
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	197
PrevISDYN2CMMMsgRxTime_MSec_M_u32	962026752
PrevISDYNAASMsgDLCError_Cnt_M_u08	171
PrevISDYNAASMsgRxTime_MSec_M_u32	1257884928
PrevISDYNABRMsgDLCError_Cnt_M_u08	20
PrevISDYNABRMsgRxTime_MSec_M_u32	3337227520
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	145
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3560623360
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	178
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1270426880
PrevISDYNVOLMsgDLCError_Cnt_M_u08	83
PrevISDYNVOLMsgRxTime_MSec_M_u32	3232713984
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	626785536

Name	Input Value
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	192.510498
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	13561
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	3694
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	55502
VitesseVehicleBVRampValidCount_Cnt_M_u16	22531
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	11867
VitesseVehicleBVSigValidCount_Cnt_M_u16	11992
VitesseVehicleBV_Kph_M_f32	617.01178
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	612
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	20152
VitesseVehiculeRoues_Kph_M_f32	36.5938988
k_AASNTCEnableTimeout_mS_u16	33994
k_AASNodeAbsentDiag_Cnt_str.Threshold	52633
k_AASNodeAbsentDiag_Cnt_str.PStep	47119
k_AASNodeAbsentDiag_Cnt_str.NStep	51722
k_AASNodeAbsentTimeout_mS_u16	12261
k_AASNodeTimeout_mS_u16	50542
k_ABSNodeTimeout_mS_u16	53711
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	21321
k_ANGLEVOLANTSigValidThresh_Cnt_u16	56786
k_AngleVolantInvalidThresh_Cnt_u16	23845
k_AngleVolantValidThresh_Cnt_u16	3746
k_BSI552MsgTimeout_mS_u16	17355
k_BSINTCEnableTimeout_mS_u16	19338
k_BSINodeAbsentDiag_Cnt_str.Threshold	1818
k_BSINodeAbsentDiag_Cnt_str.PStep	1790
k_BSINodeAbsentDiag_Cnt_str.NStep	8476
k_BSINodeAbsentTimeout_mS_u16	41949
k_BSINodeTimeout_mS_u16	23425
k_BattOvHi_Volt_f32	18.4029999
k_BattOvLo_Volt_f32	17.9258995
k_BattUvHi_Volt_f32	5.11789989
k_BattUvLo_Volt_f32	23.4312
k_CAVNTCEnableTimeout_mS_u16	50512
k_CAVNodeAbsentDiag_Cnt_str.Threshold	54606
k_CAVNodeAbsentDiag_Cnt_str.PStep	21304
k_CAVNodeAbsentDiag_Cnt_str.NStep	45990
k_CAVNodeAbsentTimeout_mS_u16	39034
k_CAVNodeTimeout_mS_u16	27431
k_CMM388MsgTimeout_mS_u16	54236
k_CMM388NTCEnableTimeout_mS_u16	34440
k_CMMNTCEnableTimeout_mS_u16	25434
k_CMMNodeAbsentDiag_Cnt_str.Threshold	26180
k_CMMNodeAbsentDiag_Cnt_str.PStep	30858
k_CMMNodeAbsentDiag_Cnt_str.NStep	7764
k_CMMNodeAbsentTimeout_mS_u16	65380
k_CONSANGLECPKMax_HwDeg_f32	433.776886
k_CONSANGLECPKMin_HwDeg_f32	-638.756287
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	31076
k_CONSANGLECPKSigValidThresh_Cnt_u16	1464
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	58348
k_CPKVehicleSpeedValidThresh_Cnt_u16	16422
k_CityParkInputInvalidThresh_Cnt_u16	33676
k_CityParkInputValidThresh_Cnt_u16	24930
k_ComputerRazGCTSigValidThresh_Cnt_u16	30560
k_CptTemporelSigValidThresh_Cnt_u16	35585
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	8742

Name	Input Value
k_DMDFCTCPKSigValidThresh_Cnt_u16	18739
k_DMDFCTCPKValidCount_Cnt_u16	40537
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	58233
k_DMDRELAXECPKSigValidThresh_Cnt_u16	61758
k_DMDRelaxeConsistentThresh_Cnt_u16	12732
k_DateValidThresh_Cnt_u16	11857
k_DefaultVehSpd_Kph_f32	159.338303
k_DiagMuxOnAbsentTimeout_mS_u16	64693
k_EMNodeTimeout_mS_u16	60676
k_ESPNTCEnableTimeout_mS_u16	38096
k_ESPNodeAbsentDiag_Cnt_str.Threshold	49269
k_ESPNodeAbsentDiag_Cnt_str.PStep	43724
k_ESPNodeAbsentDiag_Cnt_str.NStep	1190
k_ESPNodeAbsentTimeout_mS_u16	38156
k_EtatMTSigInvalidThresh_Cnt_u16	32833
k_EtatMTSigValidThresh_Cnt_u16	27494
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	29835
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	8419
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	61239
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	53835
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	53292
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	58939
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	31227
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	1540
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	19334
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	45755
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	30956
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	40289
k_ISDATDIRASentDiag_Cnt_str.Threshold	64711
k_ISDATDIRASentDiag_Cnt_str.PStep	35441
k_ISDATDIRASentDiag_Cnt_str.NStep	35487
k_ISDATDIRASentTimeout_mS_u16	34362
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	48162
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	42885
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	41932
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	53646
k_ISDYNAASChkSumValidThresh_Cnt_u16	3187
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	33073
k_ISDYNAASMsgCountValidThresh_Cnt_u16	48846
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	58850
k_ISDYNAASMsgLenValidThresh_Cnt_u16	3266
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	55674
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	55676
k_ISDYNABRChkSumValidThresh_Cnt_u16	62729
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	51889
k_ISDYNABRMsgCountValidThresh_Cnt_u16	32686
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	40414
k_ISDYNABRMsgLenValidThresh_Cnt_u16	24103
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	25665
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	40013
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	24572
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	1409
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	26118
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	24771
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	65274
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	22142
k_ISDYNVOLChkSumValidThresh_Cnt_u16	53327
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	1232
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	30663
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	47758
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	19079
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	23423
k_IgnOnTimeout_mS_u16	42538
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	31.3505001
k_PowerCutVehSpdLowThresh_Kph_f32	240.014603
k_PowerCutVehSpdLowTimeout_mS_u16	54950
k_VBattMaxAAS_Volt_f32	1.06099999
k_VBattMaxBSI_Volt_f32	6.80950022
k_VBattMaxCAV_Volt_f32	11.1288004
k_VBattMaxCMM388_Volt_f32	29.8283005
k_VBattMaxCMM_Volt_f32	12.1793003
k_VBattMaxESP_Volt_f32	14.6335001

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinAAS_Volt_f32	27.8195
k_VBattMinBSI_Volt_f32	14.6335001
k_VBattMinCAV_Volt_f32	32
k_VBattMinCMM388_Volt_f32	1.72710001
k_VBattMinCMM_Volt_f32	1.25689995
k_VBattMinESP_Volt_f32	12.1793003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	64676
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	58340
k_VitesseVehicleBVRampValidThresh_Cnt_u16	51364
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	3358
k_VitesseVehicleBVSigValidThresh_Cnt_u16	59279
k_VitesseVehicleBVSpeedPassThresh_kph_f32	102.469101
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	11300
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	40921
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2798021888
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	195
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	61551
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1373290240
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	178
target_SrlComInput_Per1_Batt_Volt_f32.value	14.8801003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2556402944
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	50
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.402386338
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3089370368
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1270787328
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2481540352
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	52
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4171492608
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3790507264
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	32
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3083414784
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3795045632
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	159
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	175
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	196
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	245
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	101
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1549331712
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	58
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	84
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	107
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	115
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2667777280

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	270380288
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4123544832
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	25
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	33
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	104
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1888558336
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2484
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.138284594
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	251398
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	255
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	51451

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	52633	52633	✔
AASNodeAbsentTimer_mS_M_u32	1373290240	1373290240	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	42885	42885	✔
AngleVolantMsgTimer_mS_M_u32	1373290240	1373290240	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	347.261261	347.261261	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	45717	45717	✔
BSINodeAbsentTimer_mS_M_u32	4171492608	4171492608	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	54606	54606	✔
CAVNodeAbsentTimer_mS_M_u32	1373290240	1373290240	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	51338	51338	✔
CMMNodeAbsentTimer_mS_M_u32	3083414784	3083414784	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	27271	27271	✔
CONSANGLECPK_HwDeg_M_f32	272.239899	272.239899 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	27271	27271	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3501391104	3501391104	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	37161	37161	✔
CityParkInputConsistentCount_Cnt_M_u16	24930	24930	✔
CityParkInputInvalidCount_Cnt_M_u16	3748	3748	✔
CityParkInputMsgTimer_mS_M_u32	1373290240	1373290240	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1373290240	1373290240	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1373290240	1373290240	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1373290240	1373290240	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1373290240	1373290240	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1373290240	1373290240	✔
ESPNTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1373290240	1373290240	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	64	64	✔
EffacDefaultDiagTimer_mS_M_u32[1]	894	894	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	565	565	✔
ElecIntTimer_mS_M_u32[1]	78789	78789	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1373290240	1373290240	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDATDIRASentFltAcc_Cnt_M_u16	64711	64711	✔
ISDATDIRASentTimer_mS_M_u32	1373290240	1373290240	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1373290240	1373290240	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1373290240	1373290240	✔
IgnOnTimer_mS_M_u32	2761035008	2761035008	✔
IgnTimeOff_Sec_M_u32	92858324	92858324	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	105	105	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3089370368	3089370368	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	137	137	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1270787328	1270787328	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	170	170	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2481540352	2481540352	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	52	52	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4171492608	4171492608	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	119164160	119164160	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	32	32	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3083414784	3083414784	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	83	83	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3795045632	3795045632	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	101	101	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1549331712	1549331712	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	9	9	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2667777280	2667777280	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	39	39	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	270380288	270380288	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	5	5	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4123544832	4123544832	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1888558336	1888558336	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	192.510498	192.510498	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	617.01178	617.01178	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	36.5938988	36.5938988	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	347.261261	347.261261	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	27271	27271	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	92858324	92858324	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	272.239899	272.239899 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	159.338303	159.338303	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0101	0x0101	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.146 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3502427136
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	18237
AASNodeAbsentTimer_mS_M_u32	0
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	23229
ANGLEVOLANTSigValidCount_Cnt_M_u16	14663
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	52034
AngleVolantMsgTimer_mS_M_u32	3502427136
AngleVolantValidCount_Cnt_M_u16	30248
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	632.796387
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2237463552
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1027570688
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3241044992
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	455814144
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	39100
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2917854208
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	34532
CAVNodeAbsentTimer_mS_M_u32	3666271232
CDD_SrlComVehSpd_Kph_G_f32	252.710907
CMM388NTCEnableTimer_mS_M_u32	3808238592
CMM388NTCsEnabled_Cnt_M_lgc	0

Name	Input Value
CMMNTCEnableTimer_mS_M_u32	1510792192
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	34167
CMMNodeAbsentTimer_mS_M_u32	2519018496
CONSANGLECPKSigInvalidCount_Cnt_M_u16	23135
CONSANGLECPKSigValidCount_Cnt_M_u16	25273
CONSANGLECPK_Cnt_M_u16	13820
CONSANGLECPK_HwDeg_M_f32	-21.5776005
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	13820
CPKVehicleSpeedMsgTimer_mS_M_u32	3854158848
CPKVehicleSpeedValidCount_Cnt_M_u16	59869
CityParkInputConsistentCount_Cnt_M_u16	22572
CityParkInputInvalidCount_Cnt_M_u16	41323
CityParkInputMsgTimer_mS_M_u32	3089370368
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2439724032
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	61249
ComputerRazGCTSigInvalidTimer_mS_M_u32	1185635328
ComputerRazGCTSigValidCount_Cnt_M_u16	4265
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	31591
DMDFCTCPKSigValidCount_Cnt_M_u16	36761
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	39615
DMDRELAXECPKSigValidCount_Cnt_M_u16	54985
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	8036
DateInvalidTimer_mS_M_u32	1027570688
DiagMuxOnAbsentTimer_mS_M_u32	3781331968
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	455814144
ESPNTCEnableTimer_mS_M_u32	254819328
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	17245
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1123
EffacDefaultDiagTimer_mS_M_u32[1]	5523
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	1234
ElecIntTimer_mS_M_u32[1]	23646
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	323808256
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	7530
EtatMTSigValidCount_Cnt_M_u16	42816
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	8289
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1595
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	39199
ISDAT4V2BSI552MsgTimer_mS_M_u32	4096338944
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	33674
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	59112
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	42816
ISDATBSI3F2MsgTimer_mS_M_u32	4083190784
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	9690
ISDATBSI412MsgLenValidCount_Cnt_M_u16	20712
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	7530
ISDATBSI412MsgTimer_mS_M_u32	415288320
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	7803
ISDATBSI432MsgLenValidCount_Cnt_M_u16	22369
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	18381
ISDATDIRASentFltAcc_Cnt_M_u16	23649
ISDATDIRASentTimer_mS_M_u32	3854158848
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	27258
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	30248
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	16102
ISDYN2CMMMsgTimer_mS_M_u32	2594847744
ISDYNAASChkSumInvalidCount_Cnt_M_u16	62271
ISDYNAASChkSumValidCount_Cnt_M_u16	14313
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	28583
ISDYNAASMsgCount_Cnt_M_u08	4

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	32871
ISDYNAASMsgLenValidCount_Cnt_M_u16	73
ISDYNAASMsgTimeValidCount_Cnt_M_u16	62271
ISDYNAASMsgTimer_mS_M_u32	2851675136
ISDYNABRChkSumInvalidCount_Cnt_M_u16	4006
ISDYNABRChkSumValidCount_Cnt_M_u16	52664
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	54078
ISDYNABRMsgCountValidCount_Cnt_M_u16	26920
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	21854
ISDYNABRMsgLenValidCount_Cnt_M_u16	61176
ISDYNABRMsgTimeValidCount_Cnt_M_u16	13820
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	748
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1381
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	42816
ISDYNCMM208MsgTimer_mS_M_u32	3558472704
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2843
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1487
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	64806
ISDYNCMM388MsgTimer_mS_M_u32	1767414784
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	58461
ISDYNVOLChkSumValidCount_Cnt_M_u16	3895
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	24677
ISDYNVOLMsgCountValidCount_Cnt_M_u16	55063
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	59998
ISDYNVOLMsgLenValidCount_Cnt_M_u16	60567
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	34167
ISDYNVOLMsgTimer_mS_M_u32	430398464
IgnOnTimer_mS_M_u32	2052889600
IgnTimeOff_Sec_M_u32	1094060480
ManVehSpd_Kph_M_f32	109.621597
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	117
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	76
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2512817152
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	121
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3138219008
PrevISDATBSI412MsgDLCError_Cnt_M_u08	26
PrevISDATBSI412MsgRxTime_MSec_M_u32	2821708800
PrevISDATBSI432MsgDLCError_Cnt_M_u08	65
PrevISDATBSI432MsgRxTime_MSec_M_u32	1361329152
PrevISDATDIRAMsgTxTime_MSec_M_u32	3284392960
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	100
PrevISDYN2CMMMsgRxTime_MSec_M_u32	894217216
PrevISDYNAASMsgDLCError_Cnt_M_u08	54
PrevISDYNAASMsgRxTime_MSec_M_u32	3592772608
PrevISDYNABRMsgDLCError_Cnt_M_u08	179
PrevISDYNABRMsgRxTime_MSec_M_u32	1934924800
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	91
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2120375296
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	193
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2305244160
PrevISDYNVOLMsgDLCError_Cnt_M_u08	133
PrevISDYNVOLMsgRxTime_MSec_M_u32	721738752
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3418278912
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	594.325989
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1

Name	Input Value
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	39781
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	64967
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	17382
VitesseVehicleBVRampValidCount_Cnt_M_u16	46344
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	45246
VitesseVehicleBVSigValidCount_Cnt_M_u16	48648
VitesseVehicleBV_Kph_M_f32	456.5979
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	64806
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	34536
VitesseVehiculeRoues_Kph_M_f32	258.315491
k_AASNTCEnableTimeout_mS_u16	45875
k_AASNodeAbsentDiag_Cnt_str.Threshold	5734
k_AASNodeAbsentDiag_Cnt_str.PStep	31939
k_AASNodeAbsentDiag_Cnt_str.NStep	31892
k_AASNodeAbsentTimeout_mS_u16	47267
k_AASNodeTimeout_mS_u16	55495
k_ABSNodeTimeout_mS_u16	19428
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	44086
k_ANGLEVOLANTSigValidThresh_Cnt_u16	19292
k_AngleVolantInvalidThresh_Cnt_u16	55651
k_AngleVolantValidThresh_Cnt_u16	41323
k_BSI552MsgTimeout_mS_u16	45999
k_BSINTCEnableTimeout_mS_u16	1907
k_BSINodeAbsentDiag_Cnt_str.Threshold	1931
k_BSINodeAbsentDiag_Cnt_str.PStep	1896
k_BSINodeAbsentDiag_Cnt_str.NStep	9318
k_BSINodeAbsentTimeout_mS_u16	13882
k_BSINodeTimeout_mS_u16	18381
k_BattOvHi_Volt_f32	2
k_BattOvLo_Volt_f32	10.4380999
k_BattUvHi_Volt_f32	1.98479998
k_BattUvLo_Volt_f32	0
k_CAVNTCEnableTimeout_mS_u16	46433
k_CAVNodeAbsentDiag_Cnt_str.Threshold	60936
k_CAVNodeAbsentDiag_Cnt_str.PStep	27145
k_CAVNodeAbsentDiag_Cnt_str.NStep	20094
k_CAVNodeAbsentTimeout_mS_u16	46306
k_CAVNodeTimeout_mS_u16	55643
k_CMM388MsgTimeout_mS_u16	25149
k_CMM388NTCEnableTimeout_mS_u16	64057
k_CMMNTCEnableTimeout_mS_u16	43138
k_CMMNodeAbsentDiag_Cnt_str.Threshold	26470
k_CMMNodeAbsentDiag_Cnt_str.PStep	38483
k_CMMNodeAbsentDiag_Cnt_str.NStep	6835
k_CMMNodeAbsentTimeout_mS_u16	9444
k_CONSANGLECPKMax_HwDeg_f32	193.013107
k_CONSANGLECPKMin_HwDeg_f32	-54.8885002
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	38950
k_CONSANGLECPKSigValidThresh_Cnt_u16	25064
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	62797
k_CPKVehicleSpeedValidThresh_Cnt_u16	37661
k_CityParkInputInvalidThresh_Cnt_u16	3244
k_CityParkInputValidThresh_Cnt_u16	22572
k_ComputerRazGCTSigValidThresh_Cnt_u16	1136
k_CptTemporelSigValidThresh_Cnt_u16	26702
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	28766
k_DMDFCTCPKSigValidThresh_Cnt_u16	18936
k_DMDFCTCPKValidCount_Cnt_u16	55492
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	16102
k_DMDRELAXECPKSigValidThresh_Cnt_u16	17496
k_DMDRelaxeConsistentThresh_Cnt_u16	64222
k_DateValidThresh_Cnt_u16	39199
k_DefaultVehSpd_Kph_f32	16.3083
k_DiagMuxOnAbsentTimeout_mS_u16	0
k_EMNodeTimeout_mS_u16	1988
k_ESPNTCEnableTimeout_mS_u16	38880

Name	Input Value
k_ESPNodeAbsentDiag_Cnt_str.Threshold	20433
k_ESPNodeAbsentDiag_Cnt_str.PStep	13965
k_ESPNodeAbsentDiag_Cnt_str.NStep	57022
k_ESPNodeAbsentTimeout_mS_u16	1004
k_EtatMTSigInvalidThresh_Cnt_u16	10893
k_EtatMTSigValidThresh_Cnt_u16	6111
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	32624
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	63782
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	17069
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	24495
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	1229
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	13534
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	32800
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	6854
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	63359
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	11616
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	47502
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	13423
k_ISDATDIRASentDiag_Cnt_str.Threshold	39837
k_ISDATDIRASentDiag_Cnt_str.PStep	59486
k_ISDATDIRASentDiag_Cnt_str.NStep	60819
k_ISDATDIRASentTimeout_mS_u16	15522
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	7212
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	52034
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	23276
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	43686
k_ISDYNAASChkSumValidThresh_Cnt_u16	43192
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	60990
k_ISDYNAASMsgCountValidThresh_Cnt_u16	50216
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	48554
k_ISDYNAASMsgLenValidThresh_Cnt_u16	21195
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	63588
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	8796
k_ISDYNABRChkSumValidThresh_Cnt_u16	7798
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	46012
k_ISDYNABRMsgCountValidThresh_Cnt_u16	41862
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	24695
k_ISDYNABRMsgLenValidThresh_Cnt_u16	24157
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	461
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	46441
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	2971
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	9358
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	30141
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	37959
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	12387
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	45077
k_ISDYNVOLChkSumValidThresh_Cnt_u16	41315
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	20066
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	46780
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	7014
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	27196
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	18837
k_IgnOnTimeout_mS_u16	28945
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	4.77169991
k_PowerCutVehSpdLowThresh_Kph_f32	186.779495
k_PowerCutVehSpdLowTimeout_mS_u16	11679
k_VBattMaxAAS_Volt_f32	0.98360002
k_VBattMaxBSI_Volt_f32	17.8339005
k_VBattMaxCAV_Volt_f32	6.32630014
k_VBattMaxCMM388_Volt_f32	13.1983995
k_VBattMaxCMM_Volt_f32	11.0702
k_VBattMaxESP_Volt_f32	31.0034008
k_VBattMinAAS_Volt_f32	0.984600008
k_VBattMinBSI_Volt_f32	31.0034008
k_VBattMinCAV_Volt_f32	0.431800008
k_VBattMinCMM388_Volt_f32	2.46589994
k_VBattMinCMM_Volt_f32	16.8638992
k_VBattMinESP_Volt_f32	11.0702
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	58022
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	19364
k_VitesseVehicleBVRampValidThresh_Cnt_u16	64357
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	27191

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VitesseVehicleBVSigValidThresh_Cnt_u16	47525
k_VitesseVehicleBVSpeedPassThresh_kph_f32	149.782898
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	8676
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	46470
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1027570688
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	20
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60612
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2882176512
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	193
target_SrlComInput_Per1_Batt_Volt_f32.value	1.02520001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2301881344
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	91
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.74433887
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	128359424
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2136390656
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	425122816
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2644966400
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3561430016
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2234989568
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2021088256
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	56
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	136
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	155
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	193
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	201
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2257058816
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	80
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	92
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	13
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2399771648
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1849277440
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	800709632
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	42
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	93
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	122

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	124
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	162
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2795465728
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1985
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.776606083
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	896211
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	177.257294
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	26463

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2021088256	2021088256	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	23229	23229	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	52036	52036	✔
AngleVolantMsgTimer_mS_M_u32	2882176512	2882176512	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	632.796387	632.796387	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	29782	29782	✔
BSINodeAbsentTimer_mS_M_u32	2644966400	2644966400	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2917854208	2917854208	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	14438	14438	✔
CAVNodeAbsentTimer_mS_M_u32	800709632	800709632	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	27332	27332	✔
CMMNodeAbsentTimer_mS_M_u32	2234989568	2234989568	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	13820	13820	✔
CONSANGLECPK_HwDeg_M_f32	-21.5776005	-21.5776005 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	13820	13820	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3854158848	3854158848	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	59869	59869	✔
CityParkInputConsistentCount_Cnt_M_u16	22572	22572	✔
CityParkInputInvalidCount_Cnt_M_u16	41323	41323	✔
CityParkInputMsgTimer_mS_M_u32	2882176512	2882176512	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2882176512	2882176512	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2882176512	2882176512	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2882176512	2882176512	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2882176512	2882176512	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2882176512	2882176512	✔
ESPNTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2882176512	2882176512	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1123	1123	✔
EffacDefaultDiagTimer_mS_M_u32[1]	5523	5523	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1234	1234	✔
ElecIntTimer_mS_M_u32[1]	23646	23646	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2882176512	2882176512	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2882176512	2882176512	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	58461	58461	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	24677	24677	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	59998	59998	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	800709632	800709632	✔
IgnOnTimer_mS_M_u32	2052889600	2052889600	✔
IgnTimeOff_Sec_M_u32	1094060480	1094060480	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	178	178	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	128359424	128359424	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	99	99	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2136390656	2136390656	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	83	83	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	425122816	425122816	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	73	73	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2644966400	2644966400	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3561430016	3561430016	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	104	104	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2234989568	2234989568	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	34	34	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2021088256	2021088256	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	201	201	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2257058816	2257058816	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	13	13	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2399771648	2399771648	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	198	198	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1849277440	1849277440	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	126	126	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	800709632	800709632	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2795465728	2795465728	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	594.325989	594.325989	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	39781	39781	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	456.5979	456.5979	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	258.315491	258.315491	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	632.796387	632.796387	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	13820	13820	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1094060480	1094060480	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-21.5776005	-21.5776005 ± 0.0125	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	16.3083	16.3083	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	10	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	10	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.147 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2877710080
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	21014
AASNodeAbsentTimer_mS_M_u32	4294967295
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	47509
ANGLEVOLANTSigValidCount_Cnt_M_u16	61879
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	6663
AngleVolantMsgTimer_mS_M_u32	2877710080
AngleVolantValidCount_Cnt_M_u16	55765
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	381.880432
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	4067938048
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1959808768
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2428731136
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1707949824
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	48024
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1552809728
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	14751
CAVNodeAbsentTimer_mS_M_u32	1920610048
CDD_SrlComVehSpd_Kph_G_f32	93.2060013
CMM388NTCEnableTimer_mS_M_u32	35090176
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2347249408
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	33449
CMMNodeAbsentTimer_mS_M_u32	1558134528
CONSANGLECPKSigInvalidCount_Cnt_M_u16	29104
CONSANGLECPKSigValidCount_Cnt_M_u16	27746
CONSANGLECPK_Cnt_M_u16	48793
CONSANGLECPK_HwDeg_M_f32	426.8461
CPKOK_Cnt_M_lgc	0

Name	Input Value
CPKVehicleSpeedInvalidCount_Cnt_M_u16	48793
CPKVehicleSpeedMsgTimer_mS_M_u32	144793344
CPKVehicleSpeedValidCount_Cnt_M_u16	19358
CityParkInputConsistentCount_Cnt_M_u16	17353
CityParkInputInvalidCount_Cnt_M_u16	29963
CityParkInputMsgTimer_mS_M_u32	128359424
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3612151552
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	27146
ComputerRazGCTSigInvalidTimer_mS_M_u32	1611443968
ComputerRazGCTSigValidCount_Cnt_M_u16	20050
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	55063
DMDFCTCPKSigValidCount_Cnt_M_u16	3649
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	33167
DMDRELAXECPKSigValidCount_Cnt_M_u16	41265
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	30369
DateInvalidTimer_mS_M_u32	1959808768
DiagMuxOnAbsentTimer_mS_M_u32	2829524736
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1707949824
ESPNTCEnableTimer_mS_M_u32	2986217216
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	36023
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	54
EffacDefaultDiagTimer_mS_M_u32[1]	64
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	6447
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	879230720
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	38863
EtatMTSigValidCount_Cnt_M_u16	65037
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	42922
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	2524
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	35247
ISDAT4V2BSI552MsgTimer_mS_M_u32	1389575936
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	57070
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	55444
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	65037
ISDATBSI3F2MsgTimer_mS_M_u32	3937214208
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	35069
ISDATBSI412MsgLenValidCount_Cnt_M_u16	60307
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	38863
ISDATBSI412MsgTimer_mS_M_u32	1267490560
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	51101
ISDATBSI432MsgLenValidCount_Cnt_M_u16	24747
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	56036
ISDATDIRASentFltAcc_Cnt_M_u16	60712
ISDATDIRASentTimer_mS_M_u32	144793344
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	39199
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	55765
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	18586
ISDYN2CMMMsgTimer_mS_M_u32	2005929728
ISDYNAASChkSumInvalidCount_Cnt_M_u16	54800
ISDYNAASChkSumValidCount_Cnt_M_u16	23507
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	43352
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	6422
ISDYNAASMsgLenValidCount_Cnt_M_u16	52529
ISDYNAASMsgTimeValidCount_Cnt_M_u16	54800
ISDYNAASMsgTimer_mS_M_u32	2636345088
ISDYNABRChkSumInvalidCount_Cnt_M_u16	13404
ISDYNABRChkSumValidCount_Cnt_M_u16	60902
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	61971
ISDYNABRMsgCountValidCount_Cnt_M_u16	33814
ISDYNABRMsgCount_Cnt_M_u08	7

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	15539
ISDYNABRMsgLenValidCount_Cnt_M_u16	33701
ISDYNABRMsgTimeValidCount_Cnt_M_u16	48793
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	749
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1383
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	65037
ISDYNCMM208MsgTimer_mS_M_u32	977325824
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2847
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1489
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	48347
ISDYNCMM388MsgTimer_mS_M_u32	1023733504
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	19382
ISDYNVOLChkSumValidCount_Cnt_M_u16	57064
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	40989
ISDYNVOLMsgCountValidCount_Cnt_M_u16	44999
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	56244
ISDYNVOLMsgLenValidCount_Cnt_M_u16	26822
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	33449
ISDYNVOLMsgTimer_mS_M_u32	3608719104
IgnOnTimer_mS_M_u32	435744512
IgnTimeOff_Sec_M_u32	1374931106
ManVehSpd_Kph_M_f32	229.556503
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	119
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	180
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	461053696
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	104
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3743842048
PrevISDATBSI412MsgDLCError_Cnt_M_u08	125
PrevISDATBSI412MsgRxTime_MSec_M_u32	3984535296
PrevISDATBSI432MsgDLCError_Cnt_M_u08	68
PrevISDATBSI432MsgRxTime_MSec_M_u32	3156348672
PrevISDATDIRAMsgTxTime_MSec_M_u32	3938660096
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	115
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2104016640
PrevISDYNAASMsgDLCError_Cnt_M_u08	111
PrevISDYNAASMsgRxTime_MSec_M_u32	429829888
PrevISDYNABRMsgDLCError_Cnt_M_u08	213
PrevISDYNABRMsgRxTime_MSec_M_u32	252768000
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	127
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1424469760
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	241
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3747155712
PrevISDYNVOLMsgDLCError_Cnt_M_u08	176
PrevISDYNVOLMsgRxTime_MSec_M_u32	4177538816
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2861719296
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	447.700287
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	16412
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	19639
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1

Name	Input Value
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	35481
VitesseVehicleBVRampValidCount_Cnt_M_u16	27380
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	64402
VitesseVehicleBVSigValidCount_Cnt_M_u16	42868
VitesseVehicleBV_Kph_M_f32	78.9171982
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	48347
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	54101
VitesseVehiculeRoues_Kph_M_f32	585.312012
k_AASNTCEnableTimeout_mS_u16	58100
k_AASNodeAbsentDiag_Cnt_str.Threshold	32890
k_AASNodeAbsentDiag_Cnt_str.PStep	56356
k_AASNodeAbsentDiag_Cnt_str.NStep	15218
k_AASNodeAbsentTimeout_mS_u16	48740
k_AASNodeTimeout_mS_u16	48055
k_ABSNodeTimeout_mS_u16	39328
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	51820
k_ANGLEVOLANTSigValidThresh_Cnt_u16	12474
k_AngleVolantInvalidThresh_Cnt_u16	25253
k_AngleVolantValidThresh_Cnt_u16	29963
k_BSI552MsgTimeout_mS_u16	10496
k_BSINTCEnableTimeout_mS_u16	60597
k_BSINodeAbsentDiag_Cnt_str.Threshold	2044
k_BSINodeAbsentDiag_Cnt_str.PStep	2002
k_BSINodeAbsentDiag_Cnt_str.NStep	10160
k_BSINodeAbsentTimeout_mS_u16	47391
k_BSINodeTimeout_mS_u16	56036
k_BattOvHi_Volt_f32	2
k_BattOvLo_Volt_f32	28.0753994
k_BattUvHi_Volt_f32	31.5
k_BattUvLo_Volt_f32	0
k_CAVNTCEnableTimeout_mS_u16	37161
k_CAVNodeAbsentDiag_Cnt_str.Threshold	11604
k_CAVNodeAbsentDiag_Cnt_str.PStep	55314
k_CAVNodeAbsentDiag_Cnt_str.NStep	6516
k_CAVNodeAbsentTimeout_mS_u16	10149
k_CAVNodeTimeout_mS_u16	58556
k_CMM388MsgTimeout_mS_u16	278
k_CMM388NTCEnableTimeout_mS_u16	10530
k_CMMNTCEnableTimeout_mS_u16	20486
k_CMMNodeAbsentDiag_Cnt_str.Threshold	15483
k_CMMNodeAbsentDiag_Cnt_str.PStep	32373
k_CMMNodeAbsentDiag_Cnt_str.NStep	36883
k_CMMNodeAbsentTimeout_mS_u16	59745
k_CONSANGLECPKMax_HwDeg_f32	213.576996
k_CONSANGLECPKMin_HwDeg_f32	-345.215302
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	60379
k_CONSANGLECPKSigValidThresh_Cnt_u16	16981
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	65061
k_CPKVehicleSpeedValidThresh_Cnt_u16	3380
k_CityParkInputInvalidThresh_Cnt_u16	54602
k_CityParkInputValidThresh_Cnt_u16	17353
k_ComputerRazGCTSigValidThresh_Cnt_u16	29756
k_CptTemporelSigValidThresh_Cnt_u16	27746
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	60339
k_DMDFCTCPKSigValidThresh_Cnt_u16	29349
k_DMDFCTCPKValidCount_Cnt_u16	7040
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	18586
k_DMDRELAXECPKSigValidThresh_Cnt_u16	44036
k_DMDRelaxeConsistentThresh_Cnt_u16	8306
k_DateValidThresh_Cnt_u16	35247
k_DefaultVehSpd_Kph_f32	197.382797
k_DiagMuxOnAbsentTimeout_mS_u16	0
k_EMNodeTimeout_mS_u16	15745
k_ESPNTCEnableTimeout_mS_u16	63147
k_ESPNodeAbsentDiag_Cnt_str.Threshold	40506
k_ESPNodeAbsentDiag_Cnt_str.PStep	63684
k_ESPNodeAbsentDiag_Cnt_str.NStep	57074
k_ESPNodeAbsentTimeout_mS_u16	27721
k_EtatMTSigInvalidThresh_Cnt_u16	16295
k_EtatMTSigValidThresh_Cnt_u16	27505
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	43964
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	49754
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	51270

Name	Input Value
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	7807
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	21221
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	27633
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	30382
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	60028
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	19601
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	26733
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	10147
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	65089
k_ISDATDIRASentDiag_Cnt_str.Threshold	47253
k_ISDATDIRASentDiag_Cnt_str.PStep	61715
k_ISDATDIRASentDiag_Cnt_str.NStep	53301
k_ISDATDIRASentTimeout_mS_u16	40296
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	31498
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	6663
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	56711
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	25436
k_ISDYNAASChkSumValidThresh_Cnt_u16	23782
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	41235
k_ISDYNAASMsgCountValidThresh_Cnt_u16	29462
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	14928
k_ISDYNAASMsgLenValidThresh_Cnt_u16	23979
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	18850
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	19897
k_ISDYNABRChkSumValidThresh_Cnt_u16	27947
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	27288
k_ISDYNABRMsgCountValidThresh_Cnt_u16	28410
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	61865
k_ISDYNABRMsgLenValidThresh_Cnt_u16	15287
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	12325
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	528
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7098
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	46178
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	26773
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	57527
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	43043
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	38476
k_ISDYNVOLChkSumValidThresh_Cnt_u16	42530
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	49064
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	17114
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	36315
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	42265
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	53325
k_IgnOnTimeout_mS_u16	17240
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	138.492706
k_PowerCutVehSpdLowThresh_Kph_f32	240.469193
k_PowerCutVehSpdLowTimeout_mS_u16	9136
k_VBattMaxAAS_Volt_f32	9.46380043
k_VBattMaxBSI_Volt_f32	21.6257992
k_VBattMaxCAV_Volt_f32	18.7980995
k_VBattMaxCMM388_Volt_f32	7.26959991
k_VBattMaxCMM_Volt_f32	13.8800001
k_VBattMaxESP_Volt_f32	4.19259977
k_VBattMinAAS_Volt_f32	32
k_VBattMinBSI_Volt_f32	4.19259977
k_VBattMinCAV_Volt_f32	28.7148991
k_VBattMinCMM388_Volt_f32	27.5755005
k_VBattMinCMM_Volt_f32	11.4197998
k_VBattMinESP_Volt_f32	13.8800001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	36764
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	63586
k_VitesseVehicleBVRampValidThresh_Cnt_u16	53021
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	52712
k_VitesseVehicleBVSigValidThresh_Cnt_u16	17246
k_VitesseVehicleBVSpeedPassThresh_kph_f32	643.630981
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	26783
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	57722
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1959808768
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	101
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	49346
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	4191629568
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	241
target_SrlComInput_Per1_Batt_Volt_f32.value	1
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	783482624
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	210
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.698678434
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	437972736
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	146
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	462065408
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4127862528
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1369034496
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3594088192
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	36
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	736694016
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	1
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4205358848
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	97
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	132
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	139
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	208
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	234
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1526124288
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	88
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	142
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	144
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	189
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	216
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	234
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	23
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3488739072
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2598473472
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4276170496
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	107
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	134
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	245
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3832577792
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	89
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.844046414
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	15495
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	154.285904
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	17454

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	5796	5796	✔
AASNodeAbsentTimer_mS_M_u32	4205358848	4205358848	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	6665	6665	✔
AngleVolantMsgTimer_mS_M_u32	4191629568	4191629568	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	381.880432	381.880432	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	37864	37864	✔
BSINodeAbsentTimer_mS_M_u32	1369034496	1369034496	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	8235	8235	✔
CAVNodeAbsentTimer_mS_M_u32	4276170496	4276170496	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	736694016	736694016	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	48793	48793	✔
CONSANGLECPK_HwDeg_M_f32	426.8461	426.8461 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	48793	48793	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	144793344	144793344	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	19358	19358	✔
CityParkInputConsistentCount_Cnt_M_u16	17353	17353	✔
CityParkInputInvalidCount_Cnt_M_u16	29965	29965	✔
CityParkInputMsgTimer_mS_M_u32	4191629568	4191629568	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4191629568	4191629568	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4191629568	4191629568	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4191629568	4191629568	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4191629568	4191629568	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	4191629568	4191629568	✔
ESPNTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4191629568	4191629568	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	54	54	✔
EffacDefaultDiagTimer_mS_M_u32[1]	64	64	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	65	65	✔
ElecIntTimer_mS_M_u32[1]	6447	6447	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	4191629568	4191629568	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDATDIRASentFltAcc_Cnt_M_u16	7411	7411	✔
ISDATDIRASentTimer_mS_M_u32	4191629568	4191629568	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4191629568	4191629568	✔
IgnOnTimer_mS_M_u32	435744512	435744512	✔
IgnTimeOff_Sec_M_u32	1374931106	1374931106	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	222	222	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	437972736	437972736	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	146	146	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	462065408	462065408	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4127862528	4127862528	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	49	49	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1369034496	1369034496	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3594088192	3594088192	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	36	36	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	736694016	736694016	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	1	1	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4205358848	4205358848	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	118	118	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1526124288	1526124288	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	23	23	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3488739072	3488739072	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	180	180	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2598473472	2598473472	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	151	151	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4276170496	4276170496	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3832577792	3832577792	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	447.700287	447.700287	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	78.9171982	78.9171982	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	585.312012	585.312012	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	381.880432	381.880432	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	48793	48793	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1374931106	1374931106	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	426.8461	426.8461 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	197.382797	197.382797	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.148 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1430758912
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	17302
AASNodeAbsentTimer_mS_M_u32	2414436608
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	10010
ANGLEVOLANTSigValidCount_Cnt_M_u16	884
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	61379
AngleVolantMsgTimer_mS_M_u32	1430758912
AngleVolantValidCount_Cnt_M_u16	28378
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	751.954224
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1379096064
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3442071040
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2182104576
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1509099008
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	60689
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1756415488
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	39290
CAVNodeAbsentTimer_mS_M_u32	1403794944
CDD_SrlComVehSpd_Kph_G_f32	246.234802
CMM388NTCEnableTimer_mS_M_u32	2849273344
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1063400960
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	61470
CMMNodeAbsentTimer_mS_M_u32	1019020800
CONSANGLECPKSigInvalidCount_Cnt_M_u16	55754
CONSANGLECPKSigValidCount_Cnt_M_u16	44659
CONSANGLECPK_Cnt_M_u16	21454
CONSANGLECPK_HwDeg_M_f32	283.099213
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21454
CPKVehicleSpeedMsgTimer_mS_M_u32	1777772032
CPKVehicleSpeedValidCount_Cnt_M_u16	21192
CityParkInputConsistentCount_Cnt_M_u16	254
CityParkInputInvalidCount_Cnt_M_u16	17975
CityParkInputMsgTimer_mS_M_u32	437972736
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2293470720
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	52154
ComputerRazGCTSigInvalidTimer_mS_M_u32	4109678080
ComputerRazGCTSigValidCount_Cnt_M_u16	17763

Name	Input Value
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	20499
DMDFCTCPKSigValidCount_Cnt_M_u16	20308
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	14124
DMDRELAXECPKSigValidCount_Cnt_M_u16	23814
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	52983
DateInvalidTimer_mS_M_u32	3442071040
DiagMuxOnAbsentTimer_mS_M_u32	3504694784
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1509099008
ESPNTCEnableTimer_mS_M_u32	4238382592
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	1715
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	56565
ElecIntTimer_mS_M_u32[1]	787880
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3374499328
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	6571
EtatMTSigValidCount_Cnt_M_u16	56241
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	40924
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	15877
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	5386
ISDAT4V2BSI552MsgTimer_mS_M_u32	719390208
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	55247
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	32668
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	56241
ISDATBSI3F2MsgTimer_mS_M_u32	2731763200
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	9889
ISDATBSI412MsgLenValidCount_Cnt_M_u16	21406
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	6571
ISDATBSI412MsgTimer_mS_M_u32	221619712
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	61762
ISDATBSI432MsgLenValidCount_Cnt_M_u16	23255
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	2475
ISDATDIRASentFltAcc_Cnt_M_u16	58079
ISDATDIRASentTimer_mS_M_u32	1777772032
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	23612
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	28378
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	51082
ISDYN2CMMMsgTimer_mS_M_u32	1944753664
ISDYNAASChkSumInvalidCount_Cnt_M_u16	8104
ISDYNAASChkSumValidCount_Cnt_M_u16	37665
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	52305
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	38677
ISDYNAASMsgLenValidCount_Cnt_M_u16	57223
ISDYNAASMsgTimeValidCount_Cnt_M_u16	8104
ISDYNAASMsgTimer_mS_M_u32	145782272
ISDYNABRChkSumInvalidCount_Cnt_M_u16	59974
ISDYNABRChkSumValidCount_Cnt_M_u16	57959
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	38815
ISDYNABRMsgCountValidCount_Cnt_M_u16	58968
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	17601
ISDYNABRMsgLenValidCount_Cnt_M_u16	13482
ISDYNABRMsgTimeValidCount_Cnt_M_u16	21454
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	750
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1385
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	56241
ISDYNCMM208MsgTimer_mS_M_u32	3738719744
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2851
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1491
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	24008
ISDYNCMM388MsgTimer_mS_M_u32	2399925760
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	58296

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNVOLChkSumValidCount_Cnt_M_u16	61153
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	36097
ISDYNVOLMsgCountValidCount_Cnt_M_u16	706
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	19900
ISDYNVOLMsgLenValidCount_Cnt_M_u16	60230
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	61470
ISDYNVOLMsgTimer_mS_M_u32	3218126336
IgnOnTimer_mS_M_u32	3358586368
IgnTimeOff_Sec_M_u32	35224944
ManVehSpd_Kph_M_f32	59.5955009
Msg348Valid_Cnt_M_Igc	0
Msg432Valid_Cnt_M_Igc	1
Msg552Valid_Cnt_M_Igc	1
NetOn_Cnt_M_Igc	0
NtWrapC_Dem_ClearDTC()	121
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	203
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3362350592
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	248
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3806807552
PrevISDATBSI412MsgDLCError_Cnt_M_u08	204
PrevISDATBSI412MsgRxTime_MSec_M_u32	916272640
PrevISDATBSI432MsgDLCError_Cnt_M_u08	204
PrevISDATBSI432MsgRxTime_MSec_M_u32	1848940032
PrevISDATDIRAMsgTxTime_MSec_M_u32	1322333696
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	113
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3777005056
PrevISDYNAASMsgDLCError_Cnt_M_u08	45
PrevISDYNAASMsgRxTime_MSec_M_u32	2420028928
PrevISDYNABRMsgDLCError_Cnt_M_u08	93
PrevISDYNABRMsgRxTime_MSec_M_u32	1223161344
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	128
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1113830912
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	64
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2693764608
PrevISDYNVOLMsgDLCError_Cnt_M_u08	218
PrevISDYNVOLMsgRxTime_MSec_M_u32	1478112768
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2284037632
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	295.453308
PrevVitesseVehicleBVValid_Cnt_M_Igc	1
ResetTimers_Cnt_M_Igc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_Igc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	47619
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	63733
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_Igc	0
VehSpdSync_Cnt_M_Igc	0
VehTimeValid_Cnt_M_Igc	1
VehicleSpeedValid_Cnt_M_Igc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	3724
VitesseVehicleBVRampValidCount_Cnt_M_u16	53822
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	38179
VitesseVehicleBVSigValidCount_Cnt_M_u16	5693
VitesseVehicleBV_Kph_M_f32	466.005402
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	24008
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	65305
VitesseVehiculeRoues_Kph_M_f32	524.856995
k_AASNTCEnableTimeout_mS_u16	4797
k_AASNodeAbsentDiag_Cnt_str.Threshold	25803
k_AASNodeAbsentDiag_Cnt_str.PStep	42381
k_AASNodeAbsentDiag_Cnt_str.NStep	27491

Name	Input Value
k_AASNodeAbsentTimeout_mS_u16	48429
k_AASNodeTimeout_mS_u16	44021
k_ABSNodeTimeout_mS_u16	27768
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	58581
k_ANGLEVOLANTSigValidThresh_Cnt_u16	59050
k_AngleVolantInvalidThresh_Cnt_u16	48361
k_AngleVolantValidThresh_Cnt_u16	17975
k_BSI552MsgTimeout_mS_u16	27160
k_BSINTCEnableTimeout_mS_u16	57850
k_BSINodeAbsentDiag_Cnt_str.Threshold	2157
k_BSINodeAbsentDiag_Cnt_str.PStep	2108
k_BSINodeAbsentDiag_Cnt_str.NStep	11002
k_BSINodeAbsentTimeout_mS_u16	29307
k_BSINodeTimeout_mS_u16	2475
k_BattOvHi_Volt_f32	2
k_BattOvLo_Volt_f32	20.1107006
k_BattUvHi_Volt_f32	10.2369003
k_BattUvLo_Volt_f32	0
k_CAVNTCEnableTimeout_mS_u16	59869
k_CAVNodeAbsentDiag_Cnt_str.Threshold	49916
k_CAVNodeAbsentDiag_Cnt_str.PStep	26242
k_CAVNodeAbsentDiag_Cnt_str.NStep	54813
k_CAVNodeAbsentTimeout_mS_u16	26472
k_CAVNodeTimeout_mS_u16	45222
k_CMM388MsgTimeout_mS_u16	13974
k_CMM388NTCEnableTimeout_mS_u16	61042
k_CMMNTCEnableTimeout_mS_u16	58503
k_CMMNodeAbsentDiag_Cnt_str.Threshold	9161
k_CMMNodeAbsentDiag_Cnt_str.PStep	61851
k_CMMNodeAbsentDiag_Cnt_str.NStep	57473
k_CMMNodeAbsentTimeout_mS_u16	60661
k_CONSANGLECPKMax_HwDeg_f32	646.255005
k_CONSANGLECPKMin_HwDeg_f32	-1.87699997
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	53448
k_CONSANGLECPKSigValidThresh_Cnt_u16	45593
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	7339
k_CPKVehicleSpeedValidThresh_Cnt_u16	13820
k_CityParkInputInvalidThresh_Cnt_u16	16252
k_CityParkInputValidThresh_Cnt_u16	254
k_ComputerRazGCTSigValidThresh_Cnt_u16	53221
k_CptTemporelSigValidThresh_Cnt_u16	31794
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	14273
k_DMDFCTCPKSigValidThresh_Cnt_u16	26538
k_DMDFCTCPKValidCount_Cnt_u16	27993
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	51082
k_DMDRELAXECPKSigValidThresh_Cnt_u16	16907
k_DMDRelaxeConsistentThresh_Cnt_u16	7361
k_DateValidThresh_Cnt_u16	5386
k_DefaultVehSpd_Kph_f32	126.2061
k_DiagMuxOnAbsentTimeout_mS_u16	0
k_EMNodeTimeout_mS_u16	64087
k_ESPNTCEnableTimeout_mS_u16	37462
k_ESPNodeAbsentDiag_Cnt_str.Threshold	44425
k_ESPNodeAbsentDiag_Cnt_str.PStep	29100
k_ESPNodeAbsentDiag_Cnt_str.NStep	8930
k_ESPNodeAbsentTimeout_mS_u16	1085
k_EtatMTSigInvalidThresh_Cnt_u16	46181
k_EtatMTSigValidThresh_Cnt_u16	21958
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	12262
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	24779
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	42887
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	40220
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	38057
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	19909
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	26639
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	16740
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	12902
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	42578
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	15728
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	58327
k_ISDATDIRASentDiag_Cnt_str.Threshold	25913
k_ISDATDIRASentDiag_Cnt_str.PStep	24447
k_ISDATDIRASentDiag_Cnt_str.NStep	62938

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentTimeout_mS_u16	57122
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	53628
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	61379
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	19906
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	23878
k_ISDYNAASChkSumValidThresh_Cnt_u16	38247
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	35487
k_ISDYNAASMsgCountValidThresh_Cnt_u16	6488
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	43114
k_ISDYNAASMsgLenValidThresh_Cnt_u16	38425
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	15346
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	43439
k_ISDYNABRChkSumValidThresh_Cnt_u16	4120
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	57361
k_ISDYNABRMsgCountValidThresh_Cnt_u16	22443
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	41758
k_ISDYNABRMsgLenValidThresh_Cnt_u16	63923
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	32810
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	17447
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	41578
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	11764
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	6682
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	13940
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	3311
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	64180
k_ISDYNVOLChkSumValidThresh_Cnt_u16	8177
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	29152
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	45963
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	26503
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	5773
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	14640
k_IgnOnTimeout_mS_u16	9104
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	71.3766022
k_PowerCutVehSpdLowThresh_Kph_f32	125.446899
k_PowerCutVehSpdLowTimeout_mS_u16	16521
k_VBattMaxAAS_Volt_f32	23.2168999
k_VBattMaxBSI_Volt_f32	29.5919991
k_VBattMaxCAV_Volt_f32	18.1268997
k_VBattMaxCMM388_Volt_f32	25.4487
k_VBattMaxCMM_Volt_f32	4.94099998
k_VBattMaxESP_Volt_f32	15.6661997
k_VBattMinAAS_Volt_f32	16.2001991
k_VBattMinBSI_Volt_f32	15.6661997
k_VBattMinCAV_Volt_f32	11.6763
k_VBattMinCMM388_Volt_f32	0.206
k_VBattMinCMM_Volt_f32	0.558899999
k_VBattMinESP_Volt_f32	4.94099998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	23494
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	13876
k_VitesseVehicleBVRampValidThresh_Cnt_u16	1
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	8673
k_VitesseVehicleBVSigValidThresh_Cnt_u16	38463
k_VitesseVehicleBVSpeedPassThresh_kph_f32	495.3974
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	3194
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	1708
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3442071040
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	149
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	55763
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1813852160
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	64
target_SrlComInput_Per1_Batt_Volt_f32.value	1
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3326199296
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	133

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.467175454
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3486119424
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2449151488
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	254
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	150746624
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1020089856
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	896431616
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4208956928
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	116
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2501948928
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	69
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	124
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	176
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	204
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3568719360
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	67
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	131
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	187
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3393517056
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	804656640
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	182
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	175584768
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	37
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	47
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	61
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	78
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	161
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	173
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2064205312
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	576
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.750332594
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	816891
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	216.246902
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	30157

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2501948928	2501948928	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	61379	61379	✔
AngleVolantMsgTimer_mS_M_u32	1813852160	1813852160	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	751.954224	751.954224	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	49687	49687	✔
BSINodeAbsentTimer_mS_M_u32	1020089856	1020089856	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	175584768	175584768	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	3997	3997	✔
CMMNodeAbsentTimer_mS_M_u32	4208956928	4208956928	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	21454	21454	✔
CONSANGLECPK_HwDeg_M_f32	283.099213	283.099213 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21454	21454	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1777772032	1777772032	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	21192	21192	✔
CityParkInputConsistentCount_Cnt_M_u16	254	254	✔
CityParkInputInvalidCount_Cnt_M_u16	17975	17975	✔
CityParkInputMsgTimer_mS_M_u32	1813852160	1813852160	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1813852160	1813852160	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1813852160	1813852160	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1813852160	1813852160	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1813852160	1813852160	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1813852160	1813852160	✔
ESPNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	56565	56565	✔
ElecIntTimer_mS_M_u32[1]	787880	787880	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1813852160	1813852160	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATDIRASentFltAcc_Cnt_M_u16	58079	58079	✔
ISDATDIRASentTimer_mS_M_u32	1777772032	1777772032	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1813852160	1813852160	✔
IgnOnTimer_mS_M_u32	3358586368	3358586368	✔
IgnTimeOff_Sec_M_u32	35224944	35224944	✔
Msg348Valid_Cnt_M_Igc	0	0	✔
Msg432Valid_Cnt_M_Igc	0	0	✔
Msg552Valid_Cnt_M_Igc	0	0	✔
NetOn_Cnt_M_Igc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	55	55	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3486119424	3486119424	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	194	194	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2449151488	2449151488	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI412MsgDLCError_Cnt_M_u08	254	254	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	150746624	150746624	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	242	242	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1020089856	1020089856	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1322333696	1322333696	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	38	38	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4208956928	4208956928	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	116	116	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2501948928	2501948928	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	215	215	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3568719360	3568719360	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	168	168	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3393517056	3393517056	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	119	119	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	804656640	804656640	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	182	182	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	175584768	175584768	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2064205312	2064205312	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	295.453308	295.453308	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	466.005402	466.005402	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	524.856995	524.856995	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	751.954224	751.954224	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	21454	21454	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	35224944	35224944	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	283.099213	283.099213 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	126.2061	126.2061	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0108	0x0108	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x010A	0x010A	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.149 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3655323904
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	0
AASNodeAbsentTimer_mS_M_u32	3704094976
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	28774
ANGLEVOLANTSigValidCount_Cnt_M_u16	19738
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	22637
AngleVolantMsgTimer_mS_M_u32	3655323904
AngleVolantValidCount_Cnt_M_u16	40871
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	468.925323
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1843183872
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	4143530240
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3188060416
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	828223744
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	47745
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	740585728
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	16838
CAVNodeAbsentTimer_mS_M_u32	3841073408
CDD_SrlComVehSpd_Kph_G_f32	230.3302
CMM388NTCEnableTimer_mS_M_u32	3547947264
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2043683072
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	43163
CMMNodeAbsentTimer_mS_M_u32	822063360
CONSANGLECPKSigInvalidCount_Cnt_M_u16	51031
CONSANGLECPKSigValidCount_Cnt_M_u16	64283
CONSANGLECPK_Cnt_M_u16	14090
CONSANGLECPK_HwDeg_M_f32	524.454895
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	14090
CPKVehicleSpeedMsgTimer_mS_M_u32	399692032
CPKVehicleSpeedValidCount_Cnt_M_u16	26630
CityParkInputConsistentCount_Cnt_M_u16	31035
CityParkInputInvalidCount_Cnt_M_u16	7824
CityParkInputMsgTimer_mS_M_u32	3486119424
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	459014400
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	24712

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3273171200
ComputerRazGCTSigValidCount_Cnt_M_u16	32780
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	28924
DMDFCTCPKSigValidCount_Cnt_M_u16	34039
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	2096
DMDRELAXECPKSigValidCount_Cnt_M_u16	2148
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	56272
DateInvalidTimer_mS_M_u32	4143530240
DiagMuxOnAbsentTimer_mS_M_u32	235311360
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	828223744
ESPNTCEnableTimer_mS_M_u32	3012886784
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	50843
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	65
EffacDefaultDiagTimer_mS_M_u32[1]	655
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	55656
ElecIntTimer_mS_M_u32[1]	87789
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1389261056
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	61683
EtatMTSigValidCount_Cnt_M_u16	52387
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	15649
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	5221
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	35797
ISDAT4V2BSI552MsgTimer_mS_M_u32	4136874240
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	64521
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	18017
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	52387
ISDATBSI3F2MsgTimer_mS_M_u32	3493630208
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	10386
ISDATBSI412MsgLenValidCount_Cnt_M_u16	41818
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	61683
ISDATBSI412MsgTimer_mS_M_u32	3927298304
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	13615
ISDATBSI432MsgLenValidCount_Cnt_M_u16	23087
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	62771
ISDATDIRASentFltAcc_Cnt_M_u16	14743
ISDATDIRASentTimer_mS_M_u32	399692032
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	21952
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	40871
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	42647
ISDYN2CMMMsgTimer_mS_M_u32	4122411264
ISDYNAASChkSumInvalidCount_Cnt_M_u16	40126
ISDYNAASChkSumValidCount_Cnt_M_u16	13330
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	9026
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	29941
ISDYNAASMsgLenValidCount_Cnt_M_u16	28001
ISDYNAASMsgTimeValidCount_Cnt_M_u16	40126
ISDYNAASMsgTimer_mS_M_u32	652566784
ISDYNABRChkSumInvalidCount_Cnt_M_u16	35940
ISDYNABRChkSumValidCount_Cnt_M_u16	13760
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	53465
ISDYNABRMsgCountValidCount_Cnt_M_u16	54893
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	8818
ISDYNABRMsgLenValidCount_Cnt_M_u16	1142
ISDYNABRMsgTimeValidCount_Cnt_M_u16	14090
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	751
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1387
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	52387
ISDYNCMM208MsgTimer_mS_M_u32	2616049920
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2855
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1493
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	2781

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1641210112
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	57741
ISDYNVOLChkSumValidCount_Cnt_M_u16	29137
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	62002
ISDYNVOLMsgCountValidCount_Cnt_M_u16	41645
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	21888
ISDYNVOLMsgLenValidCount_Cnt_M_u16	44707
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	43163
ISDYNVOLMsgTimer_mS_M_u32	3531907328
IgnOnTimer_mS_M_u32	1181147392
IgnTimeOff_Sec_M_u32	2957703283
ManVehSpd_Kph_M_f32	123.011803
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	123
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	196
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	930779392
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	97
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3078680832
PrevISDATBSI412MsgDLCError_Cnt_M_u08	169
PrevISDATBSI412MsgRxTime_MSec_M_u32	1075781888
PrevISDATBSI432MsgDLCError_Cnt_M_u08	175
PrevISDATBSI432MsgRxTime_MSec_M_u32	2933457152
PrevISDATDIRAMsgTxTime_MSec_M_u32	3347259648
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	43
PrevISDYN2CMMMsgRxTime_MSec_M_u32	836055296
PrevISDYNAASMsgDLCError_Cnt_M_u08	235
PrevISDYNAASMsgRxTime_MSec_M_u32	2570756352
PrevISDYNABRMsgDLCError_Cnt_M_u08	46
PrevISDYNABRMsgRxTime_MSec_M_u32	2755584256
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	102
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1456185600
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	230
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1137180928
PrevISDYNVOLMsgDLCError_Cnt_M_u08	143
PrevISDYNVOLMsgRxTime_MSec_M_u32	262676736
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2974535936
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	26.2705002
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	17451
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	22807
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	43664
VitesseVehicleBVRampValidCount_Cnt_M_u16	12604
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	35403
VitesseVehicleBVSigValidCount_Cnt_M_u16	30911
VitesseVehicleBV_Kph_M_f32	352.985809
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	2781
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	30889
VitesseVehiculeRoues_Kph_M_f32	36.702301
k_AASNTCEnableTimeout_mS_u16	30269
k_AASNodeAbsentDiag_Cnt_str.Threshold	17636

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	28472
k_AASNodeAbsentDiag_Cnt_str.NStep	26432
k_AASNodeAbsentTimeout_mS_u16	49326
k_AASNodeTimeout_mS_u16	16407
k_ABSNodeTimeout_mS_u16	61389
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	26230
k_ANGLEVOLANTSigValidThresh_Cnt_u16	49846
k_AngleVolantInvalidThresh_Cnt_u16	64505
k_AngleVolantValidThresh_Cnt_u16	7824
k_BSI552MsgTimeout_mS_u16	62380
k_BSINTCEnableTimeout_mS_u16	17159
k_BSINodeAbsentDiag_Cnt_str.Threshold	2270
k_BSINodeAbsentDiag_Cnt_str.PStep	2214
k_BSINodeAbsentDiag_Cnt_str.NStep	11844
k_BSINodeAbsentTimeout_mS_u16	45125
k_BSINodeTimeout_mS_u16	62771
k_BattOvHi_Volt_f32	21.5673008
k_BattOvLo_Volt_f32	12.7565002
k_BattUvHi_Volt_f32	8.06900024
k_BattUvLo_Volt_f32	29.8372993
k_CAVNTCEnableTimeout_mS_u16	19358
k_CAVNodeAbsentDiag_Cnt_str.Threshold	43553
k_CAVNodeAbsentDiag_Cnt_str.PStep	60761
k_CAVNodeAbsentDiag_Cnt_str.NStep	32069
k_CAVNodeAbsentTimeout_mS_u16	4092
k_CAVNodeTimeout_mS_u16	45763
k_CMM388MsgTimeout_mS_u16	36852
k_CMM388NTCEnableTimeout_mS_u16	55392
k_CMMNTCEnableTimeout_mS_u16	46561
k_CMMNodeAbsentDiag_Cnt_str.Threshold	4560
k_CMMNodeAbsentDiag_Cnt_str.PStep	45492
k_CMMNodeAbsentDiag_Cnt_str.NStep	39755
k_CMMNodeAbsentTimeout_mS_u16	7957
k_CONSANGLECPKMax_HwDeg_f32	354.549805
k_CONSANGLECPKMin_HwDeg_f32	-83.5279999
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	45533
k_CONSANGLECPKSigValidThresh_Cnt_u16	24489
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	17909
k_CPKVehicleSpeedValidThresh_Cnt_u16	9857
k_CityParkInputInvalidThresh_Cnt_u16	58562
k_CityParkInputValidThresh_Cnt_u16	31035
k_ComputerRazGCTSigValidThresh_Cnt_u16	60359
k_CptTemporelSigValidThresh_Cnt_u16	10399
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	18802
k_DMDFCTCPKSigValidThresh_Cnt_u16	27510
k_DMDFCTCPKValidCount_Cnt_u16	22953
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	42647
k_DMDRELAXECPKSigValidThresh_Cnt_u16	18642
k_DMDRelaxeConsistentThresh_Cnt_u16	4272
k_DateValidThresh_Cnt_u16	35797
k_DefaultVehSpd_Kph_f32	251.595505
k_DiagMuxOnAbsentTimeout_mS_u16	55192
k_EMNodeTimeout_mS_u16	55728
k_ESPNTCEnableTimeout_mS_u16	50994
k_ESPNodeAbsentDiag_Cnt_str.Threshold	14231
k_ESPNodeAbsentDiag_Cnt_str.PStep	74
k_ESPNodeAbsentDiag_Cnt_str.NStep	16050
k_ESPNodeAbsentTimeout_mS_u16	63805
k_EtatMTSigInvalidThresh_Cnt_u16	27143
k_EtatMTSigValidThresh_Cnt_u16	6051
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	47172
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	51027
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	59808
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	8226
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	31546
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	17190
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	17608
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	6792
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	451
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	20350
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	3045
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	39408
k_ISDATDIRASentDiag_Cnt_str.Threshold	9798

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	30270
k_ISDATDIRASentDiag_Cnt_str.NStep	25322
k_ISDATDIRASentTimeout_mS_u16	7632
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	42241
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	22637
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	17646
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	13156
k_ISDYNAASChkSumValidThresh_Cnt_u16	7360
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	63449
k_ISDYNAASMsgCountValidThresh_Cnt_u16	15725
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	57848
k_ISDYNAASMsgLenValidThresh_Cnt_u16	4523
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	58078
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	11176
k_ISDYNABRChkSumValidThresh_Cnt_u16	43564
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	57729
k_ISDYNABRMsgCountValidThresh_Cnt_u16	60533
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	36763
k_ISDYNABRMsgLenValidThresh_Cnt_u16	60827
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	12024
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	13759
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	6455
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	30234
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	38758
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	46106
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	43624
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	47193
k_ISDYNVOLChkSumValidThresh_Cnt_u16	19041
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	30996
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	21076
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	30559
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	35855
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	14179
k_IgnOnTimeout_mS_u16	44485
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	86.584198
k_PowerCutVehSpdLowThresh_Kph_f32	124.373299
k_PowerCutVehSpdLowTimeout_mS_u16	7385
k_VBattMaxAAS_Volt_f32	2.56450009
k_VBattMaxBSI_Volt_f32	19.8551006
k_VBattMaxCAV_Volt_f32	15.0951004
k_VBattMaxCMM388_Volt_f32	8.92070007
k_VBattMaxCMM_Volt_f32	6.47410011
k_VBattMaxESP_Volt_f32	29.3090992
k_VBattMinAAS_Volt_f32	1.15240002
k_VBattMinBSI_Volt_f32	29.3090992
k_VBattMinCAV_Volt_f32	30.5475006
k_VBattMinCMM388_Volt_f32	10.6245003
k_VBattMinCMM_Volt_f32	21.9085007
k_VBattMinESP_Volt_f32	6.47410011
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	44579
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	57498
k_VitesseVehicleBVRampValidThresh_Cnt_u16	39218
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	55505
k_VitesseVehicleBVSigValidThresh_Cnt_u16	64888
k_VitesseVehicleBVSpeedPassThresh_kph_f32	344.929413
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	59590
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	52210
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	4143530240
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	44013
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	68495872
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	230
target_SrlComInput_Per1_Batt_Volt_f32.value	20.9337006
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2540794112
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	89
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.987422049
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	395895040
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	44
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2105901312
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	84025600
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2517549312
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	413884672
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1960313088
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2459214080
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	63
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	71
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	88
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	164
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	228
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	171
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2991833344
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	28
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	44
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	121
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	133
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	182
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	192
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3559383296
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	188
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1335132416
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2895192320
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	16
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	32
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	52
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	57
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	133
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	239
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4145737984
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	232
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.91230166
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	237304
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	99.2231979
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	47309

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	68495872	68495872	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	17636	17636	✔
AASNodeAbsentTimer_mS_M_u32	68495872	68495872	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	22639	22639	✔
AngleVolantMsgTimer_mS_M_u32	68495872	68495872	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	468.925323	468.925323	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	2270	2270	✔
BSINodeAbsentTimer_mS_M_u32	68495872	68495872	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	68495872	68495872	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	68495872	68495872	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	68495872	68495872	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	4560	4560	✔
CMMNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	14090	14090	✔
CONSANGLECPK_HwDeg_M_f32	524.454895	524.454895 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	14090	14090	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	399692032	399692032	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	26630	26630	✔
CityParkInputConsistentCount_Cnt_M_u16	31035	31035	✔
CityParkInputInvalidCount_Cnt_M_u16	7826	7826	✔
CityParkInputMsgTimer_mS_M_u32	68495872	68495872	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	68495872	68495872	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	68495872	68495872	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	68495872	68495872	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	68495872	68495872	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	68495872	68495872	✔
ESPNTCEnableTimer_mS_M_u32	68495872	68495872	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	65	65	✔
EffacDefaultDiagTimer_mS_M_u32[1]	655	655	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	68495872	68495872	✔
ElecIntTimer_mS_M_u32[1]	87789	87789	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	68495872	68495872	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	68495872	68495872	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	68495872	68495872	✔
IgnOnTimer_mS_M_u32	68495872	68495872	✔
IgnTimeOff_Sec_M_u32	2957703283	2957703283	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	192	192	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	395895040	395895040	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	44	44	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2105901312	2105901312	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	198	198	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	84025600	84025600	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	117	117	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2517549312	2517549312	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3347259648	3347259648	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	181	181	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1960313088	1960313088	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2459214080	2459214080	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	171	171	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2991833344	2991833344	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	26	26	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3559383296	3559383296	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	188	188	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1335132416	1335132416	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	75	75	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2895192320	2895192320	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4145737984	4145737984	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	26.2705002	26.2705002	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	352.985809	352.985809	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	36.702301	36.702301	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	468.925323	468.925323	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	14090	14090	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2957703283	2957703283	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	524.454895	524.454895 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.150 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	914575360
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	65535
AASNodeAbsentTimer_mS_M_u32	1250607104
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	20206
ANGLEVOLANTSigValidCount_Cnt_M_u16	25491
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	53466
AngleVolantMsgTimer_mS_M_u32	914575360
AngleVolantValidCount_Cnt_M_u16	44458
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	311.337067
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3662446592
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1358364672
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1251012608
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	4287213568
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	40093
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2587193344
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	24911
CAVNodeAbsentTimer_mS_M_u32	42754048
CDD_SrlComVehSpd_Kph_G_f32	548.327515
CMM388NTCEnableTimer_mS_M_u32	1677107200
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1005740032
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	60560
CMMNodeAbsentTimer_mS_M_u32	144945152
CONSANGLECPKSigInvalidCount_Cnt_M_u16	64796
CONSANGLECPKSigValidCount_Cnt_M_u16	19601
CONSANGLECPK_Cnt_M_u16	5316
CONSANGLECPK_HwDeg_M_f32	-508.020111
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	5316
CPKVehicleSpeedMsgTimer_mS_M_u32	145379328
CPKVehicleSpeedValidCount_Cnt_M_u16	38936

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	28910
CityParkInputInvalidCount_Cnt_M_u16	8690
CityParkInputMsgTimer_mS_M_u32	395895040
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3738091520
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	58505
ComputerRazGCTSigInvalidTimer_mS_M_u32	572055552
ComputerRazGCTSigValidCount_Cnt_M_u16	57467
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	55982
DMDFCTCPKSigValidCount_Cnt_M_u16	27003
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	12176
DMDRELAXECPKSigValidCount_Cnt_M_u16	55733
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	58289
DateInvalidTimer_mS_M_u32	1358364672
DiagMuxOnAbsentTimer_mS_M_u32	2769227776
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4287213568
ESPNTCEnableTimer_mS_M_u32	975421440
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	27985
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	2323
ElecIntTimer_mS_M_u32[1]	454648
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1312256000
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	50311
EtatMTSigValidCount_Cnt_M_u16	52280
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	17342
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	43187
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	19681
ISDAT4V2BSI552MsgTimer_mS_M_u32	132624384
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	53958
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	11903
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	52280
ISDATBSI3F2MsgTimer_mS_M_u32	3060600832
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	554
ISDATBSI412MsgLenValidCount_Cnt_M_u16	35987
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	50311
ISDATBSI412MsgTimer_mS_M_u32	1575047168
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	38612
ISDATBSI432MsgLenValidCount_Cnt_M_u16	661
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	15112
ISDATDIRASentFltAcc_Cnt_M_u16	64988
ISDATDIRASentTimer_mS_M_u32	145379328
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	4258
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	44458
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	26077
ISDYN2CMMMsgTimer_mS_M_u32	2076033024
ISDYNAASChkSumInvalidCount_Cnt_M_u16	34791
ISDYNAASChkSumValidCount_Cnt_M_u16	60588
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	20185
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	17346
ISDYNAASMsgLenValidCount_Cnt_M_u16	58687
ISDYNAASMsgTimeValidCount_Cnt_M_u16	34791
ISDYNAASMsgTimer_mS_M_u32	431136768
ISDYNABRChkSumInvalidCount_Cnt_M_u16	51828
ISDYNABRChkSumValidCount_Cnt_M_u16	6433
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	6038
ISDYNABRMsgCountValidCount_Cnt_M_u16	12699
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	6091
ISDYNABRMsgLenValidCount_Cnt_M_u16	23680
ISDYNABRMsgTimeValidCount_Cnt_M_u16	5316

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	752
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1389
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	52280
ISDYNCMM208MsgTimer_mS_M_u32	3558440960
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2859
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1495
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	50184
ISDYNCMM388MsgTimer_mS_M_u32	4276756480
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	1658
ISDYNVOLChkSumValidCount_Cnt_M_u16	16495
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	44812
ISDYNVOLMsgCountValidCount_Cnt_M_u16	26713
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	38050
ISDYNVOLMsgLenValidCount_Cnt_M_u16	62455
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	60560
ISDYNVOLMsgTimer_mS_M_u32	2748637184
IgnOnTimer_mS_M_u32	2704154624
IgnTimeOff_Sec_M_u32	2058821710
ManVehSpd_Kph_M_f32	246.631393
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	125
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	139
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4172484608
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	75
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	169865216
PrevISDATBSI412MsgDLCError_Cnt_M_u08	34
PrevISDATBSI412MsgRxTime_MSec_M_u32	3842334720
PrevISDATBSI432MsgDLCError_Cnt_M_u08	0
PrevISDATBSI432MsgRxTime_MSec_M_u32	1482145792
PrevISDATDIRAMsgTxTime_MSec_M_u32	3738787840
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	77
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1008939008
PrevISDYNAASMsgDLCError_Cnt_M_u08	57
PrevISDYNAASMsgRxTime_MSec_M_u32	2813517824
PrevISDYNABRMsgDLCError_Cnt_M_u08	240
PrevISDYNABRMsgRxTime_MSec_M_u32	3886424064
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	104
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4076855296
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	171
PrevISDYNCMM388MsgRxTime_MSec_M_u32	361414656
PrevISDYNVOLMsgDLCError_Cnt_M_u08	73
PrevISDYNVOLMsgRxTime_MSec_M_u32	3664404480
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1614761984
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	17.0391998
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	11808
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	31261
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	52977
VitesseVehicleBVRampValidCount_Cnt_M_u16	50606
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	54591

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	46244
VitesseVehicleBV_Kph_M_f32	459.81781
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	50184
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	34149
VitesseVehiculeRoues_Kph_M_f32	515.174194
k_AASNTCEnableTimeout_mS_u16	58155
k_AASNodeAbsentDiag_Cnt_str.Threshold	25104
k_AASNodeAbsentDiag_Cnt_str.PStep	3541
k_AASNodeAbsentDiag_Cnt_str.NStep	8318
k_AASNodeAbsentTimeout_mS_u16	9877
k_AASNodeTimeout_mS_u16	50461
k_ABSNodeTimeout_mS_u16	57915
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	57087
k_ANGLEVOLANTSigValidThresh_Cnt_u16	42240
k_AngleVolantInvalidThresh_Cnt_u16	50487
k_AngleVolantValidThresh_Cnt_u16	8690
k_BSI552MsgTimeout_mS_u16	57436
k_BSINTCEnableTimeout_mS_u16	52556
k_BSINodeAbsentDiag_Cnt_str.Threshold	2383
k_BSINodeAbsentDiag_Cnt_str.PStep	2320
k_BSINodeAbsentDiag_Cnt_str.NStep	12686
k_BSINodeAbsentTimeout_mS_u16	10578
k_BSINodeTimeout_mS_u16	15112
k_BattOvHi_Volt_f32	24.9759007
k_BattOvLo_Volt_f32	12.783
k_BattUvHi_Volt_f32	31.5
k_BattUvLo_Volt_f32	23.1762009
k_CAVNTCEnableTimeout_mS_u16	21192
k_CAVNodeAbsentDiag_Cnt_str.Threshold	37401
k_CAVNodeAbsentDiag_Cnt_str.PStep	33586
k_CAVNodeAbsentDiag_Cnt_str.NStep	24111
k_CAVNodeAbsentTimeout_mS_u16	20141
k_CAVNodeTimeout_mS_u16	60120
k_CMM388MsgTimeout_mS_u16	1605
k_CMM388NTCEnableTimeout_mS_u16	56577
k_CMMNTCEnableTimeout_mS_u16	1342
k_CMMNodeAbsentDiag_Cnt_str.Threshold	23117
k_CMMNodeAbsentDiag_Cnt_str.PStep	58722
k_CMMNodeAbsentDiag_Cnt_str.NStep	25435
k_CMMNodeAbsentTimeout_mS_u16	16929
k_CONSANGLECPKMax_HwDeg_f32	114.366302
k_CONSANGLECPKMin_HwDeg_f32	-779.979126
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	53000
k_CONSANGLECPKSigValidThresh_Cnt_u16	53349
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	43907
k_CPKVehicleSpeedValidThresh_Cnt_u16	33885
k_CityParkInputInvalidThresh_Cnt_u16	47450
k_CityParkInputValidThresh_Cnt_u16	28910
k_ComputerRazGCTSigValidThresh_Cnt_u16	31628
k_CptTemporelSigValidThresh_Cnt_u16	65477
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	41675
k_DMDFCTCPKSigValidThresh_Cnt_u16	10112
k_DMDFCTCPKValidCount_Cnt_u16	24357
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	26077
k_DMDRELAXECPKSigValidThresh_Cnt_u16	18922
k_DMDRelaxeConsistentThresh_Cnt_u16	59984
k_DateValidThresh_Cnt_u16	19681
k_DefaultVehSpd_Kph_f32	251.849396
k_DiagMuxOnAbsentTimeout_mS_u16	60186
k_EMNodeTimeout_mS_u16	27153
k_ESPNTCEnableTimeout_mS_u16	33035
k_ESPNodeAbsentDiag_Cnt_str.Threshold	29688
k_ESPNodeAbsentDiag_Cnt_str.PStep	50333
k_ESPNodeAbsentDiag_Cnt_str.NStep	33830
k_ESPNodeAbsentTimeout_mS_u16	21417
k_EtatMTSigInvalidThresh_Cnt_u16	32139
k_EtatMTSigValidThresh_Cnt_u16	49016
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	20630
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	15911
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	62399
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	2683
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	13300
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	622

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	3081
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	25994
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	33048
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	39784
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	57584
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	45842
k_ISDATDIRASentDiag_Cnt_str.Threshold	61866
k_ISDATDIRASentDiag_Cnt_str.PStep	48259
k_ISDATDIRASentDiag_Cnt_str.NStep	33088
k_ISDATDIRASentTimeout_mS_u16	50736
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	5599
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	53466
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	63447
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	54644
k_ISDYNAASChkSumValidThresh_Cnt_u16	25633
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	41622
k_ISDYNAASMsgCountValidThresh_Cnt_u16	64667
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	6584
k_ISDYNAASMsgLenValidThresh_Cnt_u16	41057
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	58504
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	21545
k_ISDYNABRChkSumValidThresh_Cnt_u16	50014
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	10141
k_ISDYNABRMsgCountValidThresh_Cnt_u16	45442
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	14224
k_ISDYNABRMsgLenValidThresh_Cnt_u16	63569
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	46585
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	43364
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	1083
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	61204
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	55790
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	11923
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	56938
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	11989
k_ISDYNVOLChkSumValidThresh_Cnt_u16	29566
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	31206
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	4965
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	57667
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	15860
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	567
k_IgnOnTimeout_mS_u16	65169
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	199.383102
k_PowerCutVehSpdLowThresh_Kph_f32	254.0159
k_PowerCutVehSpdLowTimeout_mS_u16	24407
k_VBattMaxAAS_Volt_f32	17.1385002
k_VBattMaxBSI_Volt_f32	21.0184994
k_VBattMaxCAV_Volt_f32	20.7644997
k_VBattMaxCMM388_Volt_f32	24.9144993
k_VBattMaxCMM_Volt_f32	26.1634998
k_VBattMaxESP_Volt_f32	23.6263008
k_VBattMinAAS_Volt_f32	22.7605
k_VBattMinBSI_Volt_f32	23.6263008
k_VBattMinCAV_Volt_f32	19.1053009
k_VBattMinCMM388_Volt_f32	10.8762999
k_VBattMinCMM_Volt_f32	5.99620008
k_VBattMinESP_Volt_f32	26.1634998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	633
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	9682
k_VitesseVehicleBVRampValidThresh_Cnt_u16	47628
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	2927
k_VitesseVehicleBVSigValidThresh_Cnt_u16	6199
k_VitesseVehicleBVSpeedPassThresh_kph_f32	243.628098
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	27727
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	19852
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1358364672
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	255
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65109
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3632743680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	171
target_SrlComInput_Per1_Batt_Volt_f32.value	4.90339994
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3427692544
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	139
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.355942249
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1972903936
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1045577728
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	184
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3797704704
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2847309824
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3697319936
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	188
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3260727296
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2745491456
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	48
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	80
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	200
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2833743872
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	24
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	62
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	166
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1005264896
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	185
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3290775552
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3887030272
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	7
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	17
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	48
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	85
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	130
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	169
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	861007872
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1275
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.955509961
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	11466
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	99.716301
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	55354

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	25104	25104	✔
AASNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3632743680	3632743680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	311.337067	311.337067	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	2383	2383	✔
BSINodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	23117	23117	✔
CMMNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	5316	5316	✔
CONSANGLECPK_HwDeg_M_f32	-508.020111	-508.020111 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3632743680	3632743680	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3632743680	3632743680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3632743680	3632743680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3632743680	3632743680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3632743680	3632743680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3632743680	3632743680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3632743680	3632743680	✔
ESPNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	8	8	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3632743680	3632743680	✔
ElecIntTimer_mS_M_u32[1]	454648	454648	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3632743680	3632743680	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3632743680	3632743680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3632743680	3632743680	✔
IgnOnTimer_mS_M_u32	2704154624	2704154624	✔
IgnTimeOff_Sec_M_u32	2058821710	2058821710	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	212	212	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1972903936	1972903936	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	107	107	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1045577728	1045577728	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	184	184	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3797704704	3797704704	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	5	5	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2847309824	2847309824	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3738787840	3738787840	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	188	188	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3260727296	3260727296	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	183	183	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2745491456	2745491456	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	183	183	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2833743872	2833743872	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	195	195	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1005264896	1005264896	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	185	185	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3290775552	3290775552	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	38	38	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3887030272	3887030272	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	861007872	861007872	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	17.0391998	17.0391998	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	459.81781	459.81781	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	515.174194	515.174194	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	311.337067	311.337067	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	5316	5316	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2058821710	2058821710	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-508.020111	-508.020111 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.151 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	290771712
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	61094
AASNodeAbsentTimer_mS_M_u32	2130608896
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	13331
ANGLEVOLANTSigValidCount_Cnt_M_u16	62949
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	78
AngleVolantMsgTimer_mS_M_u32	290771712
AngleVolantValidCount_Cnt_M_u16	21085
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	124.514343
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	112804608
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1824113408
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2477519616
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1203876608
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	50950
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3602805504
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	26992
CAVNodeAbsentTimer_mS_M_u32	3849954048
CDD_SrlComVehSpd_Kph_G_f32	547.398682
CMM388NTCEnableTimer_mS_M_u32	976937728
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1363649280
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	34924
CMMNodeAbsentTimer_mS_M_u32	343126784
CONSANGLECPKSigInvalidCount_Cnt_M_u16	4234
CONSANGLECPKSigValidCount_Cnt_M_u16	25067
CONSANGLECPK_Cnt_M_u16	38226
CONSANGLECPK_HwDeg_M_f32	-95.1835022
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	38226
CPKVehicleSpeedMsgTimer_mS_M_u32	4141863680
CPKVehicleSpeedValidCount_Cnt_M_u16	59518
CityParkInputConsistentCount_Cnt_M_u16	6289

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	8840
CityParkInputMsgTimer_mS_M_u32	1972903936
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3526525696
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	16705
ComputerRazGCTSigInvalidTimer_mS_M_u32	1490297600
ComputerRazGCTSigValidCount_Cnt_M_u16	15850
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	59476
DMDFCTCPKSigValidCount_Cnt_M_u16	56237
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	39469
DMDRELAXECPKSigValidCount_Cnt_M_u16	39807
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	61643
DateInvalidTimer_mS_M_u32	1824113408
DiagMuxOnAbsentTimer_mS_M_u32	2763100928
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1203876608
ESPNTCEnableTimer_mS_M_u32	1412662016
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	30186
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	79
EffacDefaultDiagTimer_mS_M_u32[1]	699
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	56565
ElecIntTimer_mS_M_u32[1]	787881
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1119384320
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	60807
EtatMTSigValidCount_Cnt_M_u16	1588
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	17572
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	21893
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	18811
ISDAT4V2BSI552MsgTimer_mS_M_u32	648524544
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	13388
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	28897
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	1588
ISDATBSI3F2MsgTimer_mS_M_u32	1754764032
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	34591
ISDATBSI412MsgLenValidCount_Cnt_M_u16	63396
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	60807
ISDATBSI412MsgTimer_mS_M_u32	2470105856
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	39328
ISDATBSI432MsgLenValidCount_Cnt_M_u16	50718
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	69
ISDATDIRASentFltAcc_Cnt_M_u16	1993
ISDATDIRASentTimer_mS_M_u32	4141863680
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	39352
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	21085
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	49863
ISDYN2CMMMsgTimer_mS_M_u32	2003141376
ISDYNAASChkSumInvalidCount_Cnt_M_u16	20263
ISDYNAASChkSumValidCount_Cnt_M_u16	41112
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	60112
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	19991
ISDYNAASMsgLenValidCount_Cnt_M_u16	51552
ISDYNAASMsgTimeValidCount_Cnt_M_u16	20263
ISDYNAASMsgTimer_mS_M_u32	151446272
ISDYNABRChkSumInvalidCount_Cnt_M_u16	21248
ISDYNABRChkSumValidCount_Cnt_M_u16	34489
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	7194
ISDYNABRMsgCountValidCount_Cnt_M_u16	19915
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	15485
ISDYNABRMsgLenValidCount_Cnt_M_u16	44574
ISDYNABRMsgTimeValidCount_Cnt_M_u16	38226
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	753

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1391
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	1588
ISDYNCMM208MsgTimer_mS_M_u32	2370978560
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2863
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1497
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	1859
ISDYNCMM388MsgTimer_mS_M_u32	2539676416
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	60528
ISDYNVOLChkSumValidCount_Cnt_M_u16	32337
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	25402
ISDYNVOLMsgCountValidCount_Cnt_M_u16	55059
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	33783
ISDYNVOLMsgLenValidCount_Cnt_M_u16	9656
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	34924
ISDYNVOLMsgTimer_mS_M_u32	3282051840
IgnOnTimer_mS_M_u32	3230950144
IgnTimeOff_Sec_M_u32	2450403101
ManVehSpd_Kph_M_f32	41.7406006
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	127
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	212
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	969249536
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	206
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1358885632
PrevISDATBSI412MsgDLCError_Cnt_M_u08	57
PrevISDATBSI412MsgRxTime_MSec_M_u32	1645126400
PrevISDATBSI432MsgDLCError_Cnt_M_u08	210
PrevISDATBSI432MsgRxTime_MSec_M_u32	3382149888
PrevISDATDIRAMsgTxTime_MSec_M_u32	3297944320
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	164
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3623170816
PrevISDYNAASMsgDLCError_Cnt_M_u08	101
PrevISDYNAASMsgRxTime_MSec_M_u32	2953192192
PrevISDYNABRMsgDLCError_Cnt_M_u08	185
PrevISDYNABRMsgRxTime_MSec_M_u32	3442238208
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	242
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1109336832
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	229
PrevISDYNCMM388MsgRxTime_MSec_M_u32	503218944
PrevISDYNVOLMsgDLCError_Cnt_M_u08	60
PrevISDYNVOLMsgRxTime_MSec_M_u32	1440719616
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2216743680
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	320.945587
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	34557
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	710
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	10378
VitesseVehicleBVRampValidCount_Cnt_M_u16	42003
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	9504
VitesseVehicleBVSigValidCount_Cnt_M_u16	34482

Name	Input Value
VitesseVehicleBV_Kph_M_f32	630.895874
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	1859
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	41709
VitesseVehiculeRoues_Kph_M_f32	519.948975
k_AASNTCEnableTimeout_mS_u16	34333
k_AASNodeAbsentDiag_Cnt_str.Threshold	47321
k_AASNodeAbsentDiag_Cnt_str.PStep	13642
k_AASNodeAbsentDiag_Cnt_str.NStep	3343
k_AASNodeAbsentTimeout_mS_u16	21404
k_AASNodeTimeout_mS_u16	8646
k_ABSNodeTimeout_mS_u16	17837
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	11551
k_ANGLEVOLANTSigValidThresh_Cnt_u16	19165
k_AngleVolantInvalidThresh_Cnt_u16	34360
k_AngleVolantValidThresh_Cnt_u16	8840
k_BSI552MsgTimeout_mS_u16	11784
k_BSINTCEnableTimeout_mS_u16	54840
k_BSINodeAbsentDiag_Cnt_str.Threshold	2496
k_BSINodeAbsentDiag_Cnt_str.PStep	2426
k_BSINodeAbsentDiag_Cnt_str.NStep	13528
k_BSINodeAbsentTimeout_mS_u16	55014
k_BSINodeTimeout_mS_u16	69
k_BattOvHi_Volt_f32	13.7010002
k_BattOvLo_Volt_f32	3.6559999
k_BattUvHi_Volt_f32	26.4050007
k_BattUvLo_Volt_f32	15.0691004
k_CAVNTCEnableTimeout_mS_u16	26630
k_CAVNodeAbsentDiag_Cnt_str.Threshold	2429
k_CAVNodeAbsentDiag_Cnt_str.PStep	1523
k_CAVNodeAbsentDiag_Cnt_str.NStep	54460
k_CAVNodeAbsentTimeout_mS_u16	39254
k_CAVNodeTimeout_mS_u16	14166
k_CMM388MsgTimeout_mS_u16	52237
k_CMM388NTCEnableTimeout_mS_u16	14297
k_CMMNTCEnableTimeout_mS_u16	31972
k_CMMNodeAbsentDiag_Cnt_str.Threshold	45859
k_CMMNodeAbsentDiag_Cnt_str.PStep	53668
k_CMMNodeAbsentDiag_Cnt_str.NStep	42873
k_CMMNodeAbsentTimeout_mS_u16	23737
k_CONSANGLECPKMax_HwDeg_f32	31.7511005
k_CONSANGLECPKMin_HwDeg_f32	-15.4752998
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	58947
k_CONSANGLECPKSigValidThresh_Cnt_u16	49645
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	34452
k_CPKVehicleSpeedValidThresh_Cnt_u16	35974
k_CityParkInputInvalidThresh_Cnt_u16	40526
k_CityParkInputValidThresh_Cnt_u16	6289
k_ComputerRazGCTSigValidThresh_Cnt_u16	53754
k_CptTemporelSigValidThresh_Cnt_u16	38159
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	39805
k_DMDFCTCPKSigValidThresh_Cnt_u16	19742
k_DMDFCTCPKValidCount_Cnt_u16	40814
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	49863
k_DMDRELAXECPKSigValidThresh_Cnt_u16	46688
k_DMDRelaxeConsistentThresh_Cnt_u16	60718
k_DateValidThresh_Cnt_u16	18811
k_DefaultVehSpd_Kph_f32	65.8220978
k_DiagMuxOnAbsentTimeout_mS_u16	59984
k_EMNodeTimeout_mS_u16	56747
k_ESPNTCEnableTimeout_mS_u16	64060
k_ESPNodeAbsentDiag_Cnt_str.Threshold	50464
k_ESPNodeAbsentDiag_Cnt_str.PStep	54001
k_ESPNodeAbsentDiag_Cnt_str.NStep	9238
k_ESPNodeAbsentTimeout_mS_u16	18465
k_EtatMTSigInvalidThresh_Cnt_u16	21947
k_EtatMTSigValidThresh_Cnt_u16	44980
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	41819
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	35432
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	5150
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	41261
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	29826
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	38483
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	19969

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	45375
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	60116
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	37222
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	20619
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	25958
k_ISDATDIRASentDiag_Cnt_str.Threshold	28362
k_ISDATDIRASentDiag_Cnt_str.PStep	56832
k_ISDATDIRASentDiag_Cnt_str.NStep	61321
k_ISDATDIRASentTimeout_mS_u16	20428
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	45311
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	78
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	50648
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	12800
k_ISDYNAASChkSumValidThresh_Cnt_u16	42425
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	31514
k_ISDYNAASMsgCountValidThresh_Cnt_u16	60619
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	30004
k_ISDYNAASMsgLenValidThresh_Cnt_u16	40954
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	44101
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	32611
k_ISDYNABRChkSumValidThresh_Cnt_u16	29060
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	9734
k_ISDYNABRMsgCountValidThresh_Cnt_u16	34840
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	42860
k_ISDYNABRMsgLenValidThresh_Cnt_u16	54506
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	5811
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	9521
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	1260
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	16353
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	37651
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	38117
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	52512
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	27934
k_ISDYNVOLChkSumValidThresh_Cnt_u16	44771
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	58411
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	42989
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	34643
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	41216
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	377
k_IgnOnTimeout_mS_u16	60906
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	73.7210007
k_PowerCutVehSpdLowThresh_Kph_f32	173.822601
k_PowerCutVehSpdLowTimeout_mS_u16	49561
k_VBattMaxAAS_Volt_f32	6.25339985
k_VBattMaxBSI_Volt_f32	25.3572998
k_VBattMaxCAV_Volt_f32	3.72189999
k_VBattMaxCMM388_Volt_f32	1.39100003
k_VBattMaxCMM_Volt_f32	15.9165001
k_VBattMaxESP_Volt_f32	23.6249008
k_VBattMinAAS_Volt_f32	18.2301998
k_VBattMinBSI_Volt_f32	23.6249008
k_VBattMinCAV_Volt_f32	6.60470009
k_VBattMinCMM388_Volt_f32	4.28599977
k_VBattMinCMM_Volt_f32	31.0112
k_VBattMinESP_Volt_f32	15.9165001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	54065
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	14566
k_VitesseVehicleBVRampValidThresh_Cnt_u16	16954
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	7505
k_VitesseVehicleBVSigValidThresh_Cnt_u16	34486
k_VitesseVehicleBVSpeedPassThresh_kph_f32	31.5216007
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	18544
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	1145
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1824113408
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	124
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	61417
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1499264000
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	229
target_SrlComInput_Per1_Batt_Volt_f32.value	6.33599997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3832771328
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	150
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.547434032
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1800823552
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	564658944
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	179
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2248778496
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3229303552
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4177322752
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1468957440
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	249
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	70263552
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	52
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	121
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	122
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	145
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	172
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3337110272
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	77
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	151
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	222
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	610099968
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	13
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2620326656
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2182128384
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	89
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	114
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	140
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	158
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	493417216
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1410
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.683568895
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	5360
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	45.971199

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	28847		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	80	80	✔
AngleVolantMsgTimer_mS_M_u32	1499264000	1499264000	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	124.514343	124.514343	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	2429	2429	✔
CAVNodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	38226	38226	✔
CONSANGLECPK_HwDeg_M_f32	-95.1835022	-95.1835022 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	38226	38226	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4141863680	4141863680	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	59518	59518	✔
CityParkInputConsistentCount_Cnt_M_u16	6289	6289	✔
CityParkInputInvalidCount_Cnt_M_u16	8842	8842	✔
CityParkInputMsgTimer_mS_M_u32	1499264000	1499264000	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1499264000	1499264000	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1499264000	1499264000	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1499264000	1499264000	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1499264000	1499264000	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1499264000	1499264000	✔
ESPNTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	50464	50464	✔
ESPNodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	79	79	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	699	699	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1499264000	1499264000	✔
ElecIntTimer_mS_M_u32[1]	787881	787881	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1499264000	1499264000	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDATDIRASentFltAcc_Cnt_M_u16	28362	28362	✔
ISDATDIRASentTimer_mS_M_u32	1499264000	1499264000	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1499264000	1499264000	✔
IgnOnTimer_mS_M_u32	3230950144	3230950144	✔
IgnTimeOff_Sec_M_u32	2450403101	2450403101	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	60	60	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1800823552	1800823552	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	235	235	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	564658944	564658944	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	179	179	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2248778496	2248778496	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	190	190	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3229303552	3229303552	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3297944320	3297944320	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	57	57	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1468957440	1468957440	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	249	249	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	70263552	70263552	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	172	172	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3337110272	3337110272	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	125	125	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	610099968	610099968	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	13	13	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2620326656	2620326656	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	118	118	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2182128384	2182128384	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	493417216	493417216	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	320.945587	320.945587	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	630.895874	630.895874	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	519.948975	519.948975	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	124.514343	124.514343	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	38226	38226	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2450403101	2450403101	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-95.1835022	-95.1835022 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	65.8220978	65.8220978	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.152 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2662091264
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	3458
AASNodeAbsentTimer_mS_M_u32	1483684352
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	62063
ANGLEVOLANTSigValidCount_Cnt_M_u16	44475
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	38847
AngleVolantMsgTimer_mS_M_u32	2662091264
AngleVolantValidCount_Cnt_M_u16	59408
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	760.74646
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	473889280
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2352839168
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3693537792
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1189456384
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	50582
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2096065024
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	3289
CAVNodeAbsentTimer_mS_M_u32	2038290944
CDD_SrlComVehSpd_Kph_G_f32	275.334595
CMM388NTCEnableTimer_mS_M_u32	272243200
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3994278400
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	28068
CMMNodeAbsentTimer_mS_M_u32	684698112
CONSANGLECPKSigInvalidCount_Cnt_M_u16	43019
CONSANGLECPKSigValidCount_Cnt_M_u16	62631
CONSANGLECPK_Cnt_M_u16	46706
CONSANGLECPK_HwDeg_M_f32	378.509491
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	46706
CPKVehicleSpeedMsgTimer_mS_M_u32	3658172928
CPKVehicleSpeedValidCount_Cnt_M_u16	50551

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	25972
CityParkInputInvalidCount_Cnt_M_u16	61586
CityParkInputMsgTimer_mS_M_u32	1800823552
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	785594880
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	24806
ComputerRazGCTSigInvalidTimer_mS_M_u32	2842581504
ComputerRazGCTSigValidCount_Cnt_M_u16	39273
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	53038
DMDFCTCPKSigValidCount_Cnt_M_u16	5602
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	43041
DMDRELAXECPKSigValidCount_Cnt_M_u16	42221
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	19272
DateInvalidTimer_mS_M_u32	2352839168
DiagMuxOnAbsentTimer_mS_M_u32	1201015296
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1189456384
ESPNTCEnableTimer_mS_M_u32	3973069312
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	21996
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	86
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	556
ElecIntTimer_mS_M_u32[1]	877879
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2701224448
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	30549
EtatMTSigValidCount_Cnt_M_u16	40461
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	62397
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	473
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	33912
ISDAT4V2BSI552MsgTimer_mS_M_u32	3258165760
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	20102
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	43399
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	40461
ISDATBSI3F2MsgTimer_mS_M_u32	333711872
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	45836
ISDATBSI412MsgLenValidCount_Cnt_M_u16	12861
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	30549
ISDATBSI412MsgTimer_mS_M_u32	821709312
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	2568
ISDATBSI432MsgLenValidCount_Cnt_M_u16	13648
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	56410
ISDATDIRASentFltAcc_Cnt_M_u16	54734
ISDATDIRASentTimer_mS_M_u32	3658172928
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	49472
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	59408
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52181
ISDYN2CMMMsgTimer_mS_M_u32	3409590784
ISDYNAASChkSumInvalidCount_Cnt_M_u16	20276
ISDYNAASChkSumValidCount_Cnt_M_u16	56225
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	43703
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	47844
ISDYNAASMsgLenValidCount_Cnt_M_u16	10696
ISDYNAASMsgTimeValidCount_Cnt_M_u16	20276
ISDYNAASMsgTimer_mS_M_u32	3554023936
ISDYNABRChkSumInvalidCount_Cnt_M_u16	57640
ISDYNABRChkSumValidCount_Cnt_M_u16	59069
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	29787
ISDYNABRMsgCountValidCount_Cnt_M_u16	24584
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	45106
ISDYNABRMsgLenValidCount_Cnt_M_u16	39950
ISDYNABRMsgTimeValidCount_Cnt_M_u16	46706

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	754
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1393
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	40461
ISDYNCMM208MsgTimer_mS_M_u32	745798144
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2867
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1499
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	57694
ISDYNCMM388MsgTimer_mS_M_u32	1858705920
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	11353
ISDYNVOLChkSumValidCount_Cnt_M_u16	46965
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	30332
ISDYNVOLMsgCountValidCount_Cnt_M_u16	15280
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	40901
ISDYNVOLMsgLenValidCount_Cnt_M_u16	31553
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28068
ISDYNVOLMsgTimer_mS_M_u32	0
IgnOnTimer_mS_M_u32	3274545664
IgnTimeOff_Sec_M_u32	1621505908
ManVehSpd_Kph_M_f32	117.488297
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	129
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3629779456
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	117
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2955799040
PrevISDATBSI412MsgDLCError_Cnt_M_u08	97
PrevISDATBSI412MsgRxTime_MSec_M_u32	2545867264
PrevISDATBSI432MsgDLCError_Cnt_M_u08	1
PrevISDATBSI432MsgRxTime_MSec_M_u32	480524800
PrevISDATDIRAMsgTxTime_MSec_M_u32	2150816256
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	91
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3293260288
PrevISDYNAASMsgDLCError_Cnt_M_u08	139
PrevISDYNAASMsgRxTime_MSec_M_u32	3956824576
PrevISDYNABRMsgDLCError_Cnt_M_u08	31
PrevISDYNABRMsgRxTime_MSec_M_u32	4251294208
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	150
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3649919488
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	138
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2070886912
PrevISDYNVOLMsgDLCError_Cnt_M_u08	239
PrevISDYNVOLMsgRxTime_MSec_M_u32	1078712832
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1984449024
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	508.587891
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	10290
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	38294
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	46987
VitesseVehicleBVRampValidCount_Cnt_M_u16	9647
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	37704

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	28500
VitesseVehicleBV_Kph_M_f32	570.938477
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	57694
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	28451
VitesseVehiculeRoues_Kph_M_f32	82.0723038
k_AASNTCEnableTimeout_mS_u16	53265
k_AASNodeAbsentDiag_Cnt_str.Threshold	55706
k_AASNodeAbsentDiag_Cnt_str.PStep	58630
k_AASNodeAbsentDiag_Cnt_str.NStep	11895
k_AASNodeAbsentTimeout_mS_u16	41043
k_AASNodeTimeout_mS_u16	14486
k_ABSNodeTimeout_mS_u16	23331
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	2955
k_ANGLEVOLANTSigValidThresh_Cnt_u16	25363
k_AngleVolantInvalidThresh_Cnt_u16	56578
k_AngleVolantValidThresh_Cnt_u16	61586
k_BSI552MsgTimeout_mS_u16	63954
k_BSINTCEnableTimeout_mS_u16	46144
k_BSINodeAbsentDiag_Cnt_str.Threshold	2609
k_BSINodeAbsentDiag_Cnt_str.PStep	2532
k_BSINodeAbsentDiag_Cnt_str.NStep	14370
k_BSINodeAbsentTimeout_mS_u16	29687
k_BSINodeTimeout_mS_u16	56410
k_BattOvHi_Volt_f32	16.1424007
k_BattOvLo_Volt_f32	23.6478996
k_BattUvHi_Volt_f32	4.24609995
k_BattUvLo_Volt_f32	24.1303005
k_CAVNTCEnableTimeout_mS_u16	38936
k_CAVNodeAbsentDiag_Cnt_str.Threshold	17772
k_CAVNodeAbsentDiag_Cnt_str.PStep	57549
k_CAVNodeAbsentDiag_Cnt_str.NStep	21809
k_CAVNodeAbsentTimeout_mS_u16	38183
k_CAVNodeTimeout_mS_u16	25511
k_CMM388MsgTimeout_mS_u16	61570
k_CMM388NTCEnableTimeout_mS_u16	56606
k_CMMNTCEnableTimeout_mS_u16	54462
k_CMMNodeAbsentDiag_Cnt_str.Threshold	16828
k_CMMNodeAbsentDiag_Cnt_str.PStep	42745
k_CMMNodeAbsentDiag_Cnt_str.NStep	13881
k_CMMNodeAbsentTimeout_mS_u16	29119
k_CONSANGLECPKMax_HwDeg_f32	297.281799
k_CONSANGLECPKMin_HwDeg_f32	-726.251099
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	17502
k_CONSANGLECPKSigValidThresh_Cnt_u16	4643
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	49708
k_CPKVehicleSpeedValidThresh_Cnt_u16	65239
k_CityParkInputInvalidThresh_Cnt_u16	46910
k_CityParkInputValidThresh_Cnt_u16	25972
k_ComputerRazGCTSigValidThresh_Cnt_u16	44412
k_CptTemporelSigValidThresh_Cnt_u16	29949
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	37682
k_DMDFCTCPKSigValidThresh_Cnt_u16	48910
k_DMDFCTCPKValidCount_Cnt_u16	56414
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	52181
k_DMDRELAXECPKSigValidThresh_Cnt_u16	4553
k_DMDRelaxeConsistentThresh_Cnt_u16	9567
k_DateValidThresh_Cnt_u16	33912
k_DefaultVehSpd_Kph_f32	139.700806
k_DiagMuxOnAbsentTimeout_mS_u16	12152
k_EMNodeTimeout_mS_u16	1192
k_ESPNTCEnableTimeout_mS_u16	35445
k_ESPNodeAbsentDiag_Cnt_str.Threshold	61126
k_ESPNodeAbsentDiag_Cnt_str.PStep	50707
k_ESPNodeAbsentDiag_Cnt_str.NStep	9059
k_ESPNodeAbsentTimeout_mS_u16	20359
k_EtatMTSigInvalidThresh_Cnt_u16	34039
k_EtatMTSigValidThresh_Cnt_u16	6092
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	18391
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	33648
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	59085
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	52195
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	25252
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	21872

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	45285
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	14317
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	58988
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	4662
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	9606
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	17719
k_ISDATDIRASentDiag_Cnt_str.Threshold	35205
k_ISDATDIRASentDiag_Cnt_str.PStep	52390
k_ISDATDIRASentDiag_Cnt_str.NStep	30922
k_ISDATDIRASentTimeout_mS_u16	6852
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	1644
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	38847
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	38817
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	17448
k_ISDYNAASChkSumValidThresh_Cnt_u16	35261
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	22363
k_ISDYNAASMsgCountValidThresh_Cnt_u16	33544
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	19084
k_ISDYNAASMsgLenValidThresh_Cnt_u16	36346
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	57051
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	65408
k_ISDYNABRChkSumValidThresh_Cnt_u16	27100
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	43158
k_ISDYNABRMsgCountValidThresh_Cnt_u16	33570
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	4260
k_ISDYNABRMsgLenValidThresh_Cnt_u16	14572
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	849
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	7574
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	44453
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	2629
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	54639
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	53435
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	20682
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	48399
k_ISDYNVOLChkSumValidThresh_Cnt_u16	51328
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	20265
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	21281
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	55793
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	64937
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	54398
k_IgnOnTimeout_mS_u16	27307
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	52.5041008
k_PowerCutVehSpdLowThresh_Kph_f32	240.199402
k_PowerCutVehSpdLowTimeout_mS_u16	3485
k_VBattMaxAAS_Volt_f32	4.3354001
k_VBattMaxBSI_Volt_f32	19.7914009
k_VBattMaxCAV_Volt_f32	19.8901005
k_VBattMaxCMM388_Volt_f32	29.5251999
k_VBattMaxCMM_Volt_f32	30.1313992
k_VBattMaxESP_Volt_f32	6.71610022
k_VBattMinAAS_Volt_f32	13.8767004
k_VBattMinBSI_Volt_f32	6.71610022
k_VBattMinCAV_Volt_f32	7.45230007
k_VBattMinCMM388_Volt_f32	6.4994998
k_VBattMinCMM_Volt_f32	22.0690002
k_VBattMinESP_Volt_f32	30.1313992
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	59350
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	18294
k_VitesseVehicleBVRampValidThresh_Cnt_u16	55676
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	55925
k_VitesseVehicleBVSigValidThresh_Cnt_u16	61189
k_VitesseVehicleBVSpeedPassThresh_kph_f32	205.831497
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	28633
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	7293
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2352839168
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	97
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	37067
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2354571008
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	138
target_SrlComInput_Per1_Batt_Volt_f32.value	12.0128002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1741711872
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	128
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.250189036
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1256692224
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4134713856
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3620592128
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	79
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1996028416
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1542724096
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	247413248
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	391797248
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	85
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	89
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	199
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	211
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	120
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1471281664
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	43
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	194
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4224883200
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1658698240
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3216562688
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	55
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	229
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	247
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1928325632
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3306
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.949299276
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	657667
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	92.0033035
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	45852

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	55706	55706	✔
AASNodeAbsentTimer_mS_M_u32	2354571008	2354571008	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	62063	62063	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	38849	38849	✔
AngleVolantMsgTimer_mS_M_u32	2354571008	2354571008	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	760.74646	760.74646	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	473889280	473889280	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2352839168	2352839168	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	3693537792	3693537792	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1189456384	1189456384	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2354571008	2354571008	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2096065024	2096065024	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	17772	17772	✔
CAVNodeAbsentTimer_mS_M_u32	2354571008	2354571008	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	14187	14187	✔
CMMNodeAbsentTimer_mS_M_u32	247413248	247413248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	46706	46706	✔
CONSANGLECPK_HwDeg_M_f32	378.509491	378.509491 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	46706	46706	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3658172928	3658172928	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	50551	50551	✔
CityParkInputConsistentCount_Cnt_M_u16	25972	25972	✔
CityParkInputInvalidCount_Cnt_M_u16	61586	61586	✔
CityParkInputMsgTimer_mS_M_u32	2354571008	2354571008	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2354571008	2354571008	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2354571008	2354571008	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2352839168	2352839168	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2354571008	2354571008	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2354571008	2354571008	✔
ESPNTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2354571008	2354571008	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔
EffacDefaultDiagTimer_mS_M_u32[1]	86	86	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	556	556	✔
ElecIntTimer_mS_M_u32[1]	877879	877879	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2354571008	2354571008	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	62397	62397	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1256692224	1256692224	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	45836	45836	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3620592128	3620592128	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDATDIRASentFltAcc_Cnt_M_u16	35205	35205	✔
ISDATDIRASentTimer_mS_M_u32	2354571008	2354571008	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	11353	11353	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	30332	30332	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	40902	40902	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3216562688	3216562688	✔
IgnOnTimer_mS_M_u32	3274545664	3274545664	✔
IgnTimeOff_Sec_M_u32	1621505908	1621505908	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1256692224	1256692224	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	170	170	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4134713856	4134713856	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	63	63	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3620592128	3620592128	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	79	79	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1996028416	1996028416	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2150816256	2150816256	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	251	251	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	247413248	247413248	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	167	167	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	391797248	391797248	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	120	120	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1471281664	1471281664	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4224883200	4224883200	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1658698240	1658698240	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	210	210	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3216562688	3216562688	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1928325632	1928325632	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	508.587891	508.587891	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	10290	10290	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	570.938477	570.938477	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	82.0723038	82.0723038	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	760.74646	760.74646	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	46706	46706	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1621505908	1621505908	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	378.509491	378.509491 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	139.700806	139.700806	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0158	0x0158	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔
NTC	0x0160	0x0160	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.153 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3443647744
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	64190
AASNodeAbsentTimer_mS_M_u32	2545489152
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	40440
ANGLEVOLANTSigValidCount_Cnt_M_u16	27091
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	36871
AngleVolantMsgTimer_mS_M_u32	3443647744
AngleVolantValidCount_Cnt_M_u16	52116
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	56.6359177
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	994694400
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	89019648
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3344041216
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	4061512960
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	32899
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2801304832
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	7994
CAVNodeAbsentTimer_mS_M_u32	923612416
CDD_SrlComVehSpd_Kph_G_f32	70.1218033
CMM388NTCEnableTimer_mS_M_u32	3017307392
CMM388NTCsEnabled_Cnt_M_lgc	0

Name	Input Value
CMMNTCEnableTimer_mS_M_u32	2974496000
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	50074
CMMNodeAbsentTimer_mS_M_u32	1951909120
CONSANGLECPKSigInvalidCount_Cnt_M_u16	39973
CONSANGLECPKSigValidCount_Cnt_M_u16	62480
CONSANGLECPK_Cnt_M_u16	39599
CONSANGLECPK_HwDeg_M_f32	357.509613
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	39599
CPKVehicleSpeedMsgTimer_mS_M_u32	1462035712
CPKVehicleSpeedValidCount_Cnt_M_u16	29702
CityParkInputConsistentCount_Cnt_M_u16	58216
CityParkInputInvalidCount_Cnt_M_u16	18192
CityParkInputMsgTimer_mS_M_u32	1256692224
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2760709376
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	37010
ComputerRazGCTSigInvalidTimer_mS_M_u32	154907904
ComputerRazGCTSigValidCount_Cnt_M_u16	23433
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	6972
DMDFCTCPKSigValidCount_Cnt_M_u16	58590
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	50402
DMDRELAXECPKSigValidCount_Cnt_M_u16	52285
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	58990
DateInvalidTimer_mS_M_u32	89019648
DiagMuxOnAbsentTimer_mS_M_u32	2844042496
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4061512960
ESPNTCEnableTimer_mS_M_u32	2660635904
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	63617
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	5
EffacDefaultDiagTimer_mS_M_u32[1]	3270708736
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2323
ElecIntTimer_mS_M_u32[1]	45466
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	46302464
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	64390
EtatMTSigValidCount_Cnt_M_u16	13597
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	271
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	5242
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	28956
ISDAT4V2BSI552MsgTimer_mS_M_u32	942392576
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	29554
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	12337
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13597
ISDATBSI3F2MsgTimer_mS_M_u32	4237993216
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	11999
ISDATBSI412MsgLenValidCount_Cnt_M_u16	16142
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	64390
ISDATBSI412MsgTimer_mS_M_u32	3461866752
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	32366
ISDATBSI432MsgLenValidCount_Cnt_M_u16	59989
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	62647
ISDATDIRASentFltAcc_Cnt_M_u16	55387
ISDATDIRASentTimer_mS_M_u32	1462035712
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	12869
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	52116
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	33095
ISDYN2CMMMsgTimer_mS_M_u32	727192832
ISDYNAASChkSumInvalidCount_Cnt_M_u16	32168
ISDYNAASChkSumValidCount_Cnt_M_u16	22051
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	57247
ISDYNAASMsgCount_Cnt_M_u08	8

Name	Input Value
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	281
ISDYNAASMsgLenValidCount_Cnt_M_u16	4652
ISDYNAASMsgTimeValidCount_Cnt_M_u16	32168
ISDYNAASMsgTimer_mS_M_u32	3640947968
ISDYNABRChkSumInvalidCount_Cnt_M_u16	61260
ISDYNABRChkSumValidCount_Cnt_M_u16	64591
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	27187
ISDYNABRMsgCountValidCount_Cnt_M_u16	9454
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	57264
ISDYNABRMsgLenValidCount_Cnt_M_u16	23003
ISDYNABRMsgTimeValidCount_Cnt_M_u16	39599
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	755
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1395
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13597
ISDYNCMM208MsgTimer_mS_M_u32	514512128
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2871
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1501
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	38826
ISDYNCMM388MsgTimer_mS_M_u32	908719360
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	51003
ISDYNVOLChkSumValidCount_Cnt_M_u16	25510
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	56658
ISDYNVOLMsgCountValidCount_Cnt_M_u16	11124
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	48886
ISDYNVOLMsgLenValidCount_Cnt_M_u16	59968
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	50074
ISDYNVOLMsgTimer_mS_M_u32	4294967295
IgnOnTimer_mS_M_u32	3372086528
IgnTimeOff_Sec_M_u32	482733543
ManVehSpd_Kph_M_f32	317.402893
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	131
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	83
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	121152768
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	28
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	658310400
PrevISDATBSI412MsgDLCError_Cnt_M_u08	215
PrevISDATBSI412MsgRxTime_MSec_M_u32	541734144
PrevISDATBSI432MsgDLCError_Cnt_M_u08	181
PrevISDATBSI432MsgRxTime_MSec_M_u32	1595544832
PrevISDATDIRAMsgTxTime_MSec_M_u32	921580800
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	48
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4024780032
PrevISDYNAASMsgDLCError_Cnt_M_u08	72
PrevISDYNAASMsgRxTime_MSec_M_u32	1778234624
PrevISDYNABRMsgDLCError_Cnt_M_u08	219
PrevISDYNABRMsgRxTime_MSec_M_u32	4199937280
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	22
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3034494208
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	209
PrevISDYNCMM388MsgRxTime_MSec_M_u32	783881472
PrevISDYNVOLMsgDLCError_Cnt_M_u08	94
PrevISDYNVOLMsgRxTime_MSec_M_u32	2594387200
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3060655360
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	52.3401985
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0

Name	Input Value
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	28975
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	34498
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	26404
VitesseVehicleBVRampValidCount_Cnt_M_u16	31351
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	24429
VitesseVehicleBVSigValidCount_Cnt_M_u16	51464
VitesseVehicleBV_Kph_M_f32	170.384003
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	38826
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	52252
VitesseVehiculeRoues_Kph_M_f32	164.063293
k_AASNTCEnableTimeout_mS_u16	35282
k_AASNodeAbsentDiag_Cnt_str.Threshold	30724
k_AASNodeAbsentDiag_Cnt_str.PStep	54142
k_AASNodeAbsentDiag_Cnt_str.NStep	34029
k_AASNodeAbsentTimeout_mS_u16	28363
k_AASNodeTimeout_mS_u16	40386
k_ABSNodeTimeout_mS_u16	35677
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	17893
k_ANGLEVOLANTSigValidThresh_Cnt_u16	11532
k_AngleVolantInvalidThresh_Cnt_u16	15167
k_AngleVolantValidThresh_Cnt_u16	18192
k_BSI552MsgTimeout_mS_u16	43023
k_BSINTCEnableTimeout_mS_u16	24518
k_BSINodeAbsentDiag_Cnt_str.Threshold	2722
k_BSINodeAbsentDiag_Cnt_str.PStep	2638
k_BSINodeAbsentDiag_Cnt_str.NStep	15212
k_BSINodeAbsentTimeout_mS_u16	56159
k_BSINodeTimeout_mS_u16	62647
k_BattOvHi_Volt_f32	11.5614004
k_BattOvLo_Volt_f32	24.4332008
k_BattUvHi_Volt_f32	1.10290003
k_BattUvLo_Volt_f32	16.3208008
k_CAVNTCEnableTimeout_mS_u16	59518
k_CAVNodeAbsentDiag_Cnt_str.Threshold	6987
k_CAVNodeAbsentDiag_Cnt_str.PStep	38634
k_CAVNodeAbsentDiag_Cnt_str.NStep	38781
k_CAVNodeAbsentTimeout_mS_u16	15952
k_CAVNodeTimeout_mS_u16	55633
k_CMM388MsgTimeout_mS_u16	20926
k_CMM388NTCEnableTimeout_mS_u16	64490
k_CMMNTCEnableTimeout_mS_u16	49354
k_CMMNodeAbsentDiag_Cnt_str.Threshold	15003
k_CMMNodeAbsentDiag_Cnt_str.PStep	51366
k_CMMNodeAbsentDiag_Cnt_str.NStep	59557
k_CMMNodeAbsentTimeout_mS_u16	13384
k_CONSANGLECPKMax_HwDeg_f32	375.071991
k_CONSANGLECPKMin_HwDeg_f32	-71.6933975
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	28330
k_CONSANGLECPKSigValidThresh_Cnt_u16	58140
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	55552
k_CPKVehicleSpeedValidThresh_Cnt_u16	14206
k_CityParkInputInvalidThresh_Cnt_u16	17674
k_CityParkInputValidThresh_Cnt_u16	58216
k_ComputerRazGCTSigValidThresh_Cnt_u16	44688
k_CptTemporelSigValidThresh_Cnt_u16	9679
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	14000
k_DMDFCTCPKSigValidThresh_Cnt_u16	61659
k_DMDFCTCPKValidCount_Cnt_u16	23595
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	33095
k_DMDRELAXECPKSigValidThresh_Cnt_u16	19753
k_DMDRelaxeConsistentThresh_Cnt_u16	60007
k_DateValidThresh_Cnt_u16	28956
k_DefaultVehSpd_Kph_f32	138.673904
k_DiagMuxOnAbsentTimeout_mS_u16	51101
k_EMNodeTimeout_mS_u16	14926
k_ESPNTCEnableTimeout_mS_u16	5734

Name	Input Value
k_ESPNodeAbsentDiag_Cnt_str.Threshold	35454
k_ESPNodeAbsentDiag_Cnt_str.PStep	601
k_ESPNodeAbsentDiag_Cnt_str.NStep	63527
k_ESPNodeAbsentTimeout_mS_u16	47856
k_EtatMTSigInvalidThresh_Cnt_u16	65503
k_EtatMTSigValidThresh_Cnt_u16	25890
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	46079
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	12021
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	861
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	44891
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	47322
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	55219
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	15831
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	38526
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	31042
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	38755
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	27442
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	61793
k_ISDATDIRASentDiag_Cnt_str.Threshold	62208
k_ISDATDIRASentDiag_Cnt_str.PStep	30559
k_ISDATDIRASentDiag_Cnt_str.NStep	53426
k_ISDATDIRASentTimeout_mS_u16	45688
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	49602
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	36871
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	40674
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	50764
k_ISDYNAASChkSumValidThresh_Cnt_u16	4943
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	49459
k_ISDYNAASMsgCountValidThresh_Cnt_u16	48110
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	17184
k_ISDYNAASMsgLenValidThresh_Cnt_u16	11670
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	55732
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	43462
k_ISDYNABRChkSumValidThresh_Cnt_u16	43121
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	55171
k_ISDYNABRMsgCountValidThresh_Cnt_u16	17822
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	55962
k_ISDYNABRMsgLenValidThresh_Cnt_u16	20353
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	16657
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	8451
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	58132
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	42165
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	62712
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	211
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	1640
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	56534
k_ISDYNVOLChkSumValidThresh_Cnt_u16	18501
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	16586
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	18211
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	17330
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	34377
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	6410
k_IgnOnTimeout_mS_u16	17410
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	78.7641983
k_PowerCutVehSpdLowThresh_Kph_f32	99.678299
k_PowerCutVehSpdLowTimeout_mS_u16	302
k_VBattMaxAAS_Volt_f32	20.9960995
k_VBattMaxBSI_Volt_f32	20.3255005
k_VBattMaxCAV_Volt_f32	16.4521008
k_VBattMaxCMM388_Volt_f32	12.6192999
k_VBattMaxCMM_Volt_f32	10.2526999
k_VBattMaxESP_Volt_f32	15.3685999
k_VBattMinAAS_Volt_f32	20.9571991
k_VBattMinBSI_Volt_f32	15.3685999
k_VBattMinCAV_Volt_f32	4.69280005
k_VBattMinCMM388_Volt_f32	25.7187004
k_VBattMinCMM_Volt_f32	21.7751007
k_VBattMinESP_Volt_f32	10.2526999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	17796
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	29794
k_VitesseVehicleBVRampValidThresh_Cnt_u16	46162
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	64166

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VitesseVehicleBVSigValidThresh_Cnt_u16	51893
k_VitesseVehicleBVSpeedPassThresh_kph_f32	535.655029
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	63034
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	19981
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	89019648
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	219
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	48464
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3270708736
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	209
target_SrlComInput_Per1_Batt_Volt_f32.value	10.2356005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2857731328
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	210
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0824365094
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	211
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2580542720
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	732861696
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1545417984
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2468074752
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	950695168
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	61
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3033076992
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1870116096
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	22
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	47
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	70
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	77
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	148
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	351327488
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	139
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	140
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	188
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	196
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4077843712
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1382913280
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	7
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	274478336
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	57
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	58
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	106
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	117

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	225
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1727464704
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2797
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.246870384
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	355419
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	91.5164032
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	63601

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3270708736	3270708736	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	30724	30724	✔
AASNodeAbsentTimer_mS_M_u32	3270708736	3270708736	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	40440	40440	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	36871	36871	✔
AngleVolantMsgTimer_mS_M_u32	3270708736	3270708736	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	56.6359177	56.6359177	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3270708736	3270708736	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3270708736	3270708736	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3270708736	3270708736	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3270708736	3270708736	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3270708736	3270708736	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2801304832	2801304832	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	6987	6987	✔
CAVNodeAbsentTimer_mS_M_u32	3270708736	3270708736	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3270708736	3270708736	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3270708736	3270708736	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3033076992	3033076992	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	39599	39599	✔
CONSANGLECPK_HwDeg_M_f32	357.509613	357.509613 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	39599	39599	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1462035712	1462035712	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	29702	29702	✔
CityParkInputConsistentCount_Cnt_M_u16	58216	58216	✔
CityParkInputInvalidCount_Cnt_M_u16	18192	18192	✔
CityParkInputMsgTimer_mS_M_u32	3270708736	3270708736	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3270708736	3270708736	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3270708736	3270708736	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3270708736	3270708736	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3270708736	3270708736	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3270708736	3270708736	✔
ESPNTCEnableTimer_mS_M_u32	3270708736	3270708736	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3270708736	3270708736	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	5	5	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3270708736	3270708736	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3270708736	3270708736	✔
ElecIntTimer_mS_M_u32[1]	45466	45466	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3270708736	3270708736	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3270708736	3270708736	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3270708736	3270708736	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3270708736	3270708736	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3270708736	3270708736	✔
ISDATDIRASentFltAcc_Cnt_M_u16	62208	62208	✔
ISDATDIRASentTimer_mS_M_u32	3270708736	3270708736	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3270708736	3270708736	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3270708736	3270708736	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3270708736	3270708736	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3270708736	3270708736	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3270708736	3270708736	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	51003	51003	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	56658	56658	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	48886	48886	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	274478336	274478336	✔
IgnOnTimer_mS_M_u32	3372086528	3372086528	✔
IgnTimeOff_Sec_M_u32	482733543	482733543	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	211	211	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2580542720	2580542720	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	221	221	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	732861696	732861696	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	81	81	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1545417984	1545417984	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	152	152	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2468074752	2468074752	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	921580800	921580800	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	61	61	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3033076992	3033076992	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	107	107	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1870116096	1870116096	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	63	63	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	351327488	351327488	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	238	238	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4077843712	4077843712	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	229	229	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1382913280	1382913280	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	7	7	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	274478336	274478336	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1727464704	1727464704	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	52.3401985	52.3401985	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	28975	28975	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	170.384003	170.384003	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	164.063293	164.063293	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	56.6359177	56.6359177	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	39599	39599	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	482733543	482733543	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	357.509613	357.509613 ± 0.0125	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	138.673904	138.673904	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0151	0x0151	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0150	0x0150	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.154 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	766317568
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	14135
AASNodeAbsentTimer_mS_M_u32	3876029440
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	22408
ANGLEVOLANTSigValidCount_Cnt_M_u16	64184
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	56156
AngleVolantMsgTimer_mS_M_u32	766317568
AngleVolantValidCount_Cnt_M_u16	41782
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	610.952942
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	794117120
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2202518528
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	670872576
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1722905600
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	39911

Name	Input Value
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1124676608
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	25155
CAVNodeAbsentTimer_mS_M_u32	25895936
CDD_SrlComVehSpd_Kph_G_f32	99.0843964
CMM388NTCEnableTimer_mS_M_u32	3358155776
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	181478400
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	8419
CMMNodeAbsentTimer_mS_M_u32	1743483904
CONSANGLECPKSigInvalidCount_Cnt_M_u16	1
CONSANGLECPKSigValidCount_Cnt_M_u16	16129
CONSANGLECPK_Cnt_M_u16	34596
CONSANGLECPK_HwDeg_M_f32	25.2096004
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	34596
CPKVehicleSpeedMsgTimer_mS_M_u32	3691254784
CPKVehicleSpeedValidCount_Cnt_M_u16	34790
CityParkInputConsistentCount_Cnt_M_u16	43962
CityParkInputInvalidCount_Cnt_M_u16	29121
CityParkInputMsgTimer_mS_M_u32	2580542720
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	277578752
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	50619
ComputerRazGCTSigInvalidTimer_mS_M_u32	1694475264
ComputerRazGCTSigValidCount_Cnt_M_u16	1879
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	42301
DMDFCTCPKSigValidCount_Cnt_M_u16	28437
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	2762
DMDRELAXECPKSigValidCount_Cnt_M_u16	64378
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	34086
DateInvalidTimer_mS_M_u32	2202518528
DiagMuxOnAbsentTimer_mS_M_u32	333763584
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1722905600
ESPNTCEnableTimer_mS_M_u32	2255520768
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	47343
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1111
EffacDefaultDiagTimer_mS_M_u32[1]	2222
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	5656
ElecIntTimer_mS_M_u32[1]	78790
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3618321408
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	31262
EtatMTSigValidCount_Cnt_M_u16	50202
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	63811
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1475
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	16987
ISDAT4V2BSI552MsgTimer_mS_M_u32	1819243520
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	6619
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	31326
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	50202
ISDATBSI3F2MsgTimer_mS_M_u32	4070757376
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	11411
ISDATBSI412MsgLenValidCount_Cnt_M_u16	21191
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	31262
ISDATBSI412MsgTimer_mS_M_u32	40571904
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	16487
ISDATBSI432MsgLenValidCount_Cnt_M_u16	13171
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	5580
ISDATDIRASentFltAcc_Cnt_M_u16	64224
ISDATDIRASentTimer_mS_M_u32	3691254784

Name	Input Value
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	39010
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	41782
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	24348
ISDYN2CMMMsgTimer_mS_M_u32	1747616768
ISDYNAASChkSumInvalidCount_Cnt_M_u16	54905
ISDYNAASChkSumValidCount_Cnt_M_u16	54217
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	21269
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	63654
ISDYNAASMsgLenValidCount_Cnt_M_u16	44078
ISDYNAASMsgTimeValidCount_Cnt_M_u16	54905
ISDYNAASMsgTimer_mS_M_u32	145056768
ISDYNABRChkSumInvalidCount_Cnt_M_u16	2828
ISDYNABRChkSumValidCount_Cnt_M_u16	35524
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	64728
ISDYNABRMsgCountValidCount_Cnt_M_u16	21352
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	8544
ISDYNABRMsgLenValidCount_Cnt_M_u16	63904
ISDYNABRMsgTimeValidCount_Cnt_M_u16	34596
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	756
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1397
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	50202
ISDYNCMM208MsgTimer_mS_M_u32	1228030976
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2875
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1503
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	5876
ISDYNCMM388MsgTimer_mS_M_u32	1731519488
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	22207
ISDYNVOLChkSumValidCount_Cnt_M_u16	51263
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	14075
ISDYNVOLMsgCountValidCount_Cnt_M_u16	29523
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	31120
ISDYNVOLMsgLenValidCount_Cnt_M_u16	48752
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	8419
ISDYNVOLMsgTimer_mS_M_u32	1512760064
IgnOnTimer_mS_M_u32	4273529856
IgnTimeOff_Sec_M_u32	243259470
ManVehSpd_Kph_M_f32	36.0145988
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	0
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	24
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3402159104
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	190
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1950069760
PrevISDATBSI412MsgDLCError_Cnt_M_u08	21
PrevISDATBSI412MsgRxTime_MSec_M_u32	2043945984
PrevISDATBSI432MsgDLCError_Cnt_M_u08	67
PrevISDATBSI432MsgRxTime_MSec_M_u32	1424262144
PrevISDATDIRAMsgTxTime_MSec_M_u32	3320325120
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	52
PrevISDYN2CMMMsgRxTime_MSec_M_u32	188937216
PrevISDYNAASMsgDLCError_Cnt_M_u08	251
PrevISDYNAASMsgRxTime_MSec_M_u32	3401163776
PrevISDYNABRMsgDLCError_Cnt_M_u08	78
PrevISDYNABRMsgRxTime_MSec_M_u32	3400590336
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	190
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2920719360
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	198
PrevISDYNCMM388MsgRxTime_MSec_M_u32	570917888
PrevISDYNVOLMsgDLCError_Cnt_M_u08	239
PrevISDYNVOLMsgRxTime_MSec_M_u32	2932417536
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	573117440
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	75.5141983

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	32868
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	9836
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	45701
VitesseVehicleBVRampValidCount_Cnt_M_u16	24397
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	10025
VitesseVehicleBVSigValidCount_Cnt_M_u16	61721
VitesseVehicleBV_Kph_M_f32	118.776299
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	5876
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	57436
VitesseVehiculeRoues_Kph_M_f32	618.456116
k_AASNTCEnableTimeout_mS_u16	1467
k_AASNodeAbsentDiag_Cnt_str.Threshold	47250
k_AASNodeAbsentDiag_Cnt_str.PStep	51043
k_AASNodeAbsentDiag_Cnt_str.NStep	64455
k_AASNodeAbsentTimeout_mS_u16	21905
k_AASNodeTimeout_mS_u16	57708
k_ABSNodeTimeout_mS_u16	6362
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	34306
k_ANGLEVOLANTSigValidThresh_Cnt_u16	1870
k_AngleVolantInvalidThresh_Cnt_u16	26805
k_AngleVolantValidThresh_Cnt_u16	29121
k_BSI552MsgTimeout_mS_u16	55427
k_BSINTCEnableTimeout_mS_u16	64607
k_BSINodeAbsentDiag_Cnt_str.Threshold	2835
k_BSINodeAbsentDiag_Cnt_str.PStep	2744
k_BSINodeAbsentDiag_Cnt_str.NStep	16054
k_BSINodeAbsentTimeout_mS_u16	22868
k_BSINodeTimeout_mS_u16	5580
k_BattOvHi_Volt_f32	31.2931004
k_BattOvLo_Volt_f32	16.5130997
k_BattUvHi_Volt_f32	6.11089993
k_BattUvLo_Volt_f32	28.3455009
k_CAVNTCEnableTimeout_mS_u16	50551
k_CAVNodeAbsentDiag_Cnt_str.Threshold	44954
k_CAVNodeAbsentDiag_Cnt_str.PStep	32686
k_CAVNodeAbsentDiag_Cnt_str.NStep	7254
k_CAVNodeAbsentTimeout_mS_u16	56577
k_CAVNodeTimeout_mS_u16	63613
k_CMM388MsgTimeout_mS_u16	12855
k_CMM388NTCEnableTimeout_mS_u16	58291
k_CMMNTCEnableTimeout_mS_u16	37331
k_CMMNodeAbsentDiag_Cnt_str.Threshold	13800
k_CMMNodeAbsentDiag_Cnt_str.PStep	35784
k_CMMNodeAbsentDiag_Cnt_str.NStep	9021
k_CMMNodeAbsentTimeout_mS_u16	22488
k_CONSANGLECPKMax_HwDeg_f32	203.241394
k_CONSANGLECPKMin_HwDeg_f32	-384.369507
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	37364
k_CONSANGLECPKSigValidThresh_Cnt_u16	39772
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	42930
k_CPKVehicleSpeedValidThresh_Cnt_u16	20150
k_CityParkInputInvalidThresh_Cnt_u16	33234
k_CityParkInputValidThresh_Cnt_u16	43962
k_ComputerRazGCTSigValidThresh_Cnt_u16	24705
k_CptTemporelSigValidThresh_Cnt_u16	37252
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	7264
k_DMDFCTCPKSigValidThresh_Cnt_u16	13472
k_DMDFCTCPKValidCount_Cnt_u16	43247

Name	Input Value
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	24348
k_DMDRELAXECPKSigValidThresh_Cnt_u16	8756
k_DMDRelaxeConsistentThresh_Cnt_u16	49786
k_DateValidThresh_Cnt_u16	16987
k_DefaultVehSpd_Kph_f32	103.926598
k_DiagMuxOnAbsentTimeout_mS_u16	14426
k_EMNodeTimeout_mS_u16	2438
k_ESPNTCEnableTimeout_mS_u16	11455
k_ESPNodeAbsentDiag_Cnt_str.Threshold	8929
k_ESPNodeAbsentDiag_Cnt_str.PStep	12561
k_ESPNodeAbsentDiag_Cnt_str.NStep	52437
k_ESPNodeAbsentTimeout_mS_u16	25568
k_EtatMTSigInvalidThresh_Cnt_u16	58707
k_EtatMTSigValidThresh_Cnt_u16	23627
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	53941
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	55441
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	24539
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	18976
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	50275
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	33303
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	58924
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	4856
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	40939
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	24840
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	48220
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	31247
k_ISDATDIRASentDiag_Cnt_str.Threshold	52471
k_ISDATDIRASentDiag_Cnt_str.PStep	60363
k_ISDATDIRASentDiag_Cnt_str.NStep	42803
k_ISDATDIRASentTimeout_mS_u16	29064
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	52460
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	56156
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	33611
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	34316
k_ISDYNAASChkSumValidThresh_Cnt_u16	17860
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	63448
k_ISDYNAASMsgCountValidThresh_Cnt_u16	36456
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	24464
k_ISDYNAASMsgLenValidThresh_Cnt_u16	33264
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	41302
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	39710
k_ISDYNABRChkSumValidThresh_Cnt_u16	58846
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	38631
k_ISDYNABRMsgCountValidThresh_Cnt_u16	21335
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	56291
k_ISDYNABRMsgLenValidThresh_Cnt_u16	46063
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	60670
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	49384
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	9204
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	22675
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	21128
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	13752
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	37817
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	48814
k_ISDYNVOLChkSumValidThresh_Cnt_u16	54050
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	17428
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	64072
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	20890
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	32918
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	33425
k_IgnOnTimeout_mS_u16	14634
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	224.155594
k_PowerCutVehSpdLowThresh_Kph_f32	201.413406
k_PowerCutVehSpdLowTimeout_mS_u16	4007
k_VBattMaxAAS_Volt_f32	18.7315006
k_VBattMaxBSI_Volt_f32	15.6517
k_VBattMaxCAV_Volt_f32	5.00309992
k_VBattMaxCMM388_Volt_f32	7.28499985
k_VBattMaxCMM_Volt_f32	16.0282001
k_VBattMaxESP_Volt_f32	31.0699997
k_VBattMinAAS_Volt_f32	32
k_VBattMinBSI_Volt_f32	31.0699997

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinCAV_Volt_f32	3.25629997
k_VBattMinCMM388_Volt_f32	3.91930008
k_VBattMinCMM_Volt_f32	19.4561996
k_VBattMinESP_Volt_f32	16.0282001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	51622
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	21450
k_VitesseVehicleBVRampValidThresh_Cnt_u16	45563
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	831
k_VitesseVehicleBVSigValidThresh_Cnt_u16	27091
k_VitesseVehicleBVSpeedPassThresh_kph_f32	556.773376
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	56643
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	48267
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2202518528
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	229
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	11265
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3016357888
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	198
target_SrlComInput_Per1_Batt_Volt_f32.value	4.23559999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3975296000
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	28
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.601677418
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1413669888
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	98
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3777430528
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3529188352
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4024386560
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	28533760
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	76
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3487007744
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	36
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	575382528
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	86
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	122
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	137
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	149
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	207
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4267721728
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	69
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	93
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	164
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	173
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	205
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	201
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	75883520
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	686425088

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	4
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1906189312
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	91
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	106
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	123
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	176
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	186
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	203
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	487437312
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1412
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.825222611
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	501182
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	48.1489983
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	29342

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3016357888	3016357888	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	47250	47250	✔
AASNodeAbsentTimer_mS_M_u32	3016357888	3016357888	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	22408	22408	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	56156	56156	✔
AngleVolantMsgTimer_mS_M_u32	3016357888	3016357888	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	610.952942	610.952942	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3016357888	3016357888	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3016357888	3016357888	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3016357888	3016357888	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3016357888	3016357888	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3016357888	3016357888	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1124676608	1124676608	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	44954	44954	✔
CAVNodeAbsentTimer_mS_M_u32	3016357888	3016357888	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3016357888	3016357888	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3016357888	3016357888	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3487007744	3487007744	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	34596	34596	✔
CONSANGLECPK_HwDeg_M_f32	25.2096004	25.2096004 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	34596	34596	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3691254784	3691254784	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	34790	34790	✔
CityParkInputConsistentCount_Cnt_M_u16	43962	43962	✔
CityParkInputInvalidCount_Cnt_M_u16	29123	29123	✔
CityParkInputMsgTimer_mS_M_u32	3016357888	3016357888	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3016357888	3016357888	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ComputerRazGCTSigInvalidTimer_mS_M_u32	3016357888	3016357888	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3016357888	3016357888	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3016357888	3016357888	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3016357888	3016357888	✔
ESPNTCEnableTimer_mS_M_u32	3016357888	3016357888	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3016357888	3016357888	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1111	1111	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2222	2222	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	5656	5656	✔
ElecIntTimer_mS_M_u32[1]	78790	78790	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3016357888	3016357888	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3016357888	3016357888	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3016357888	3016357888	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3016357888	3016357888	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3016357888	3016357888	✔
ISDATDIRASentFltAcc_Cnt_M_u16	52471	52471	✔
ISDATDIRASentTimer_mS_M_u32	3016357888	3016357888	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3016357888	3016357888	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3016357888	3016357888	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3016357888	3016357888	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3016357888	3016357888	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3016357888	3016357888	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	22207	22207	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	14075	14075	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	31120	31120	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1906189312	1906189312	✔
IgnOnTimer_mS_M_u32	4273529856	4273529856	✔
IgnTimeOff_Sec_M_u32	243259470	243259470	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	92	92	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1413669888	1413669888	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	98	98	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3777430528	3777430528	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	104	104	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3529188352	3529188352	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	55	55	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4024386560	4024386560	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3320325120	3320325120	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	76	76	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3487007744	3487007744	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	36	36	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	575382528	575382528	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	212	212	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4267721728	4267721728	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	201	201	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	75883520	75883520	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	686425088	686425088	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	4	4	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1906189312	1906189312	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	487437312	487437312	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	75.5141983	75.5141983	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	32868	32868	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	118.776299	118.776299	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	618.456116	618.456116	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	610.952942	610.952942	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	34596	34596	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	243259470	243259470	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	25.2096004	25.2096004 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	103.926598	103.926598	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0150	0x0150	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	10	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	10	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.155 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4159145728
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	9544
AASNodeAbsentTimer_mS_M_u32	2174236416
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	42582
ANGLEVOLANTSigValidCount_Cnt_M_u16	43142
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	3289
AngleVolantMsgTimer_mS_M_u32	4159145728
AngleVolantValidCount_Cnt_M_u16	17866
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	519.401611
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	263124736
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4258756352
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1333307136
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1448765184

Name	Input Value
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	5433
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3495110400
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	55973
CAVNodeAbsentTimer_mS_M_u32	1217222400
CDD_SrlComVehSpd_Kph_G_f32	254.438293
CMM388NTCEnableTimer_mS_M_u32	1035114240
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3300611840
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	39812
CMMNodeAbsentTimer_mS_M_u32	3131860736
CONSANGLECPKSigInvalidCount_Cnt_M_u16	50153
CONSANGLECPKSigValidCount_Cnt_M_u16	12969
CONSANGLECPK_Cnt_M_u16	42560
CONSANGLECPK_HwDeg_M_f32	159.195999
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	42560
CPKVehicleSpeedMsgTimer_mS_M_u32	149063424
CPKVehicleSpeedValidCount_Cnt_M_u16	7588
CityParkInputConsistentCount_Cnt_M_u16	15422
CityParkInputInvalidCount_Cnt_M_u16	5928
CityParkInputMsgTimer_mS_M_u32	1413669888
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	353122048
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	35260
ComputerRazGCTSigInvalidTimer_mS_M_u32	2419054336
ComputerRazGCTSigValidCount_Cnt_M_u16	56679
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	27828
DMDFCTCPKSigValidCount_Cnt_M_u16	39661
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	5264
DMDRELAXECPKSigValidCount_Cnt_M_u16	11840
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	2170
DateInvalidTimer_mS_M_u32	4258756352
DiagMuxOnAbsentTimer_mS_M_u32	3560982272
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1448765184
ESPNTCEnableTimer_mS_M_u32	2271033088
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	12064
EffacDefaultDiagCount_Cnt_M_u08	2
EffacDefaultDiagTimer_mS_M_u32[0]	65535
EffacDefaultDiagTimer_mS_M_u32[1]	95535
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	5
ElecIntTimer_mS_M_u32[1]	87789
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	443361024
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	36050
EtatMTSigValidCount_Cnt_M_u16	51871
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24611
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	26211
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	47387
ISDAT4V2BSI552MsgTimer_mS_M_u32	3173017344
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	38685
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	45393
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	51871
ISDATBSI3F2MsgTimer_mS_M_u32	2953201408
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	36852
ISDATBSI412MsgLenValidCount_Cnt_M_u16	6425
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	36050
ISDATBSI412MsgTimer_mS_M_u32	4054681344
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	19704
ISDATBSI432MsgLenValidCount_Cnt_M_u16	53140
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	9226

Name	Input Value
ISDATDIRASentFltAcc_Cnt_M_u16	50382
ISDATDIRASentTimer_mS_M_u32	149063424
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	60038
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	17866
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	31511
ISDYN2CMMMsgTimer_mS_M_u32	1244608256
ISDYNAASChkSumInvalidCount_Cnt_M_u16	53122
ISDYNAASChkSumValidCount_Cnt_M_u16	17234
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	29229
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	25468
ISDYNAASMsgLenValidCount_Cnt_M_u16	38052
ISDYNAASMsgTimeValidCount_Cnt_M_u16	53122
ISDYNAASMsgTimer_mS_M_u32	1816041216
ISDYNABRChkSumInvalidCount_Cnt_M_u16	38217
ISDYNABRChkSumValidCount_Cnt_M_u16	8673
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	39013
ISDYNABRMsgCountValidCount_Cnt_M_u16	117
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	39884
ISDYNABRMsgLenValidCount_Cnt_M_u16	16076
ISDYNABRMsgTimeValidCount_Cnt_M_u16	42560
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	757
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1399
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	51871
ISDYNCMM208MsgTimer_mS_M_u32	1981282048
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2879
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1505
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	25232
ISDYNCMM388MsgTimer_mS_M_u32	4002420480
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	14255
ISDYNVOLChkSumValidCount_Cnt_M_u16	3823
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	12154
ISDYNVOLMsgCountValidCount_Cnt_M_u16	1587
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	45373
ISDYNVOLMsgLenValidCount_Cnt_M_u16	36445
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0
ISDYNVOLMsgTimer_mS_M_u32	448517888
IgnOnTimer_mS_M_u32	939792128
IgnTimeOff_Sec_M_u32	1378292191
ManVehSpd_Kph_M_f32	376.347198
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	255
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	193
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1066682112
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	195
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	649832192
PrevISDATBSI412MsgDLCError_Cnt_M_u08	40
PrevISDATBSI412MsgRxTime_MSec_M_u32	1135761152
PrevISDATBSI432MsgDLCError_Cnt_M_u08	71
PrevISDATBSI432MsgRxTime_MSec_M_u32	3959502592
PrevISDATDIRAMsgTxTime_MSec_M_u32	2943768320
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	78
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2393237248
PrevISDYNAASMsgDLCError_Cnt_M_u08	211
PrevISDYNAASMsgRxTime_MSec_M_u32	3338786560
PrevISDYNABRMsgDLCError_Cnt_M_u08	176
PrevISDYNABRMsgRxTime_MSec_M_u32	3021739776
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	255
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3505051392
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	60
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3499636480
PrevISDYNVOLMsgDLCError_Cnt_M_u08	87
PrevISDYNVOLMsgRxTime_MSec_M_u32	3100858112
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	175343360

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	555.893372
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	17474
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	40426
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	29151
VitesseVehicleBVRampValidCount_Cnt_M_u16	46919
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	64371
VitesseVehicleBVSigValidCount_Cnt_M_u16	35171
VitesseVehicleBV_Kph_M_f32	546.607117
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	25232
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	53784
VitesseVehiculeRoues_Kph_M_f32	230.7742
k_AASNTCEnableTimeout_mS_u16	18043
k_AASNodeAbsentDiag_Cnt_str.Threshold	60670
k_AASNodeAbsentDiag_Cnt_str.PStep	32077
k_AASNodeAbsentDiag_Cnt_str.NStep	60640
k_AASNodeAbsentTimeout_mS_u16	23225
k_AASNodeTimeout_mS_u16	27882
k_ABSNodeTimeout_mS_u16	50653
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	43047
k_ANGLEVOLANTSigValidThresh_Cnt_u16	32771
k_AngleVolantInvalidThresh_Cnt_u16	47054
k_AngleVolantValidThresh_Cnt_u16	5928
k_BSI552MsgTimeout_mS_u16	17827
k_BSINTCEnableTimeout_mS_u16	63760
k_BSINodeAbsentDiag_Cnt_str.Threshold	2948
k_BSINodeAbsentDiag_Cnt_str.PStep	2850
k_BSINodeAbsentDiag_Cnt_str.NStep	16896
k_BSINodeAbsentTimeout_mS_u16	29425
k_BSINodeTimeout_mS_u16	9226
k_BattOvHi_Volt_f32	8.97579956
k_BattOvLo_Volt_f32	14.3094997
k_BattUvHi_Volt_f32	26.6954994
k_BattUvLo_Volt_f32	16.3271008
k_CAVNTCEnableTimeout_mS_u16	29702
k_CAVNodeAbsentDiag_Cnt_str.Threshold	45479
k_CAVNodeAbsentDiag_Cnt_str.PStep	3627
k_CAVNodeAbsentDiag_Cnt_str.NStep	21746
k_CAVNodeAbsentTimeout_mS_u16	57963
k_CAVNodeTimeout_mS_u16	51829
k_CMM388MsgTimeout_mS_u16	13384
k_CMM388NTCEnableTimeout_mS_u16	4052
k_CMMNTCEnableTimeout_mS_u16	3893
k_CMMNodeAbsentDiag_Cnt_str.Threshold	64508
k_CMMNodeAbsentDiag_Cnt_str.PStep	63260
k_CMMNodeAbsentDiag_Cnt_str.NStep	32127
k_CMMNodeAbsentTimeout_mS_u16	23460
k_CONSANGLECPKMax_HwDeg_f32	290.050995
k_CONSANGLECPKMin_HwDeg_f32	-738.394775
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	61840
k_CONSANGLECPKSigValidThresh_Cnt_u16	41240
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	45592
k_CPKVehicleSpeedValidThresh_Cnt_u16	30091
k_CityParkInputInvalidThresh_Cnt_u16	51447
k_CityParkInputValidThresh_Cnt_u16	15422
k_ComputerRazGCTSigValidThresh_Cnt_u16	56107
k_CptTemporelSigValidThresh_Cnt_u16	33759
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	43724

Name	Input Value
k_DMDFCTCPKSigValidThresh_Cnt_u16	36300
k_DMDFCTCPKValidCount_Cnt_u16	3617
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	31511
k_DMDRELAXECPKSigValidThresh_Cnt_u16	48528
k_DMDRelaxeConsistentThresh_Cnt_u16	29886
k_DateValidThresh_Cnt_u16	47387
k_DefaultVehSpd_Kph_f32	241.652893
k_DiagMuxOnAbsentTimeout_mS_u16	60062
k_EMNodeTimeout_mS_u16	64346
k_ESPNTCEnableTimeout_mS_u16	27441
k_ESPNodeAbsentDiag_Cnt_str.Threshold	2066
k_ESPNodeAbsentDiag_Cnt_str.PStep	6722
k_ESPNodeAbsentDiag_Cnt_str.NStep	54197
k_ESPNodeAbsentTimeout_mS_u16	22412
k_EtatMTSigInvalidThresh_Cnt_u16	57972
k_EtatMTSigValidThresh_Cnt_u16	35148
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	64783
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	34619
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	58331
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	23118
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	10050
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	40808
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	44969
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	34053
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	15980
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	43156
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	4696
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	59520
k_ISDATDIRASentDiag_Cnt_str.Threshold	3472
k_ISDATDIRASentDiag_Cnt_str.PStep	32212
k_ISDATDIRASentDiag_Cnt_str.NStep	26715
k_ISDATDIRASentTimeout_mS_u16	20949
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	41961
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	3289
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	38797
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	9289
k_ISDYNAASChkSumValidThresh_Cnt_u16	61665
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	42853
k_ISDYNAASMsgCountValidThresh_Cnt_u16	20341
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	42941
k_ISDYNAASMsgLenValidThresh_Cnt_u16	39774
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	53739
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	42642
k_ISDYNABRChkSumValidThresh_Cnt_u16	61970
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	9273
k_ISDYNABRMsgCountValidThresh_Cnt_u16	55977
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	27268
k_ISDYNABRMsgLenValidThresh_Cnt_u16	15904
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	27060
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	37558
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	28113
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	25461
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	46422
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	63366
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	37184
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	1443
k_ISDYNVOLChkSumValidThresh_Cnt_u16	50184
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	25009
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	58197
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	63070
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	34091
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	20601
k_IgnOnTimeout_mS_u16	34351
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	59.4659004
k_PowerCutVehSpdLowThresh_Kph_f32	7.69250011
k_PowerCutVehSpdLowTimeout_mS_u16	55479
k_VBattMaxAAS_Volt_f32	4.06040001
k_VBattMaxBSI_Volt_f32	28.5753002
k_VBattMaxCAV_Volt_f32	28.3267002
k_VBattMaxCMM388_Volt_f32	16.1315002
k_VBattMaxCMM_Volt_f32	17.9713001
k_VBattMaxESP_Volt_f32	13.6767998

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinAAS_Volt_f32	23.2392998
k_VBattMinBSI_Volt_f32	13.6767998
k_VBattMinCAV_Volt_f32	12.1470003
k_VBattMinCMM388_Volt_f32	17.4307003
k_VBattMinCMM_Volt_f32	25.7017002
k_VBattMinESP_Volt_f32	17.9713001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	5563
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	13071
k_VitesseVehicleBVRampValidThresh_Cnt_u16	48762
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	24047
k_VitesseVehicleBVSigValidThresh_Cnt_u16	42483
k_VitesseVehicleBVSpeedPassThresh_kph_f32	538.245178
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	27045
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	6029
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4258756352
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	1
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	60
target_SrlComInput_Per1_Batt_Volt_f32.value	22.4769993
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3063424768
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	44
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.802533805
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	161
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3748009728
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1899607808
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	371021568
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	156
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1980823296
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	957650688
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	76
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	120076032
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2286671616
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	34
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	107
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	178
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2391668480
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	169
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	177
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	223
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	225
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	246
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2593986304

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1710274304
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	232
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	72636160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	71
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	188
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4098205440
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	4054
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.534247875
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	390517
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	232.735703
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	54676

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	60670	60670	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	42582	42582	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	3291	3291	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	519.401611	519.401611	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3495110400	3495110400	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	45479	45479	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	7685	7685	✔
CMMNodeAbsentTimer_mS_M_u32	120076032	120076032	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	42560	42560	✔
CONSANGLECPK_HwDeg_M_f32	159.195999	159.195999 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	42562	42562	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1713429248	1713429248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	15422	15422	✔
CityParkInputInvalidCount_Cnt_M_u16	5930	5930	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	65535	65535	✔
EffacDefaultDiagTimer_mS_M_u32[1]	95535	95535	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	1713429248	1713429248	✔
ElecIntTimer_mS_M_u32[1]	87789	87789	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	3472	3472	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	14255	14255	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	12154	12154	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	45374	45374	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	72636160	72636160	✔
IgnOnTimer_mS_M_u32	939792128	939792128	✔
IgnTimeOff_Sec_M_u32	1378292191	1378292191	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	161	161	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3748009728	3748009728	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1899607808	1899607808	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	238	238	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	371021568	371021568	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	156	156	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1980823296	1980823296	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2943768320	2943768320	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	76	76	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	120076032	120076032	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	158	158	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2286671616	2286671616	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	8	8	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2391668480	2391668480	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	39	39	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2593986304	2593986304	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	8	8	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1710274304	1710274304	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	232	232	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	72636160	72636160	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4098205440	4098205440	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	555.893372	555.893372	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	17474	17474	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	546.607117	546.607117	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	230.7742	230.7742	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	519.401611	519.401611	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	42560	42560	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1378292191	1378292191	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	159.195999	159.195999 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	241.652893	241.652893	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.156 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3334745600
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	24738
AASNodeAbsentTimer_mS_M_u32	141696512
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	14199
ANGLEVOLANTSigValidCount_Cnt_M_u16	28070
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	11759
AngleVolantMsgTimer_mS_M_u32	3334745600
AngleVolantValidCount_Cnt_M_u16	53658
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	69.8200378
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	690871808
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2696175104
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3968912896
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2397801984
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	14030
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	4093726208

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	40203
CAVNodeAbsentTimer_mS_M_u32	1880276480
CDD_SrlComVehSpd_Kph_G_f32	333.310089
CMM388NTCEnableTimer_mS_M_u32	3047357952
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	864599552
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	25644
CMMNodeAbsentTimer_mS_M_u32	703958528
CONSANGLECPKSigInvalidCount_Cnt_M_u16	39358
CONSANGLECPKSigValidCount_Cnt_M_u16	51774
CONSANGLECPK_Cnt_M_u16	35705
CONSANGLECPK_HwDeg_M_f32	687.4151
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	35705
CPKVehicleSpeedMsgTimer_mS_M_u32	1070804480
CPKVehicleSpeedValidCount_Cnt_M_u16	22612
CityParkInputConsistentCount_Cnt_M_u16	48702
CityParkInputInvalidCount_Cnt_M_u16	42624
CityParkInputMsgTimer_mS_M_u32	3748009728
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	504765952
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	838
ComputerRazGCTSigInvalidTimer_mS_M_u32	1126907392
ComputerRazGCTSigValidCount_Cnt_M_u16	48835
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	54748
DMDFCTCPKSigValidCount_Cnt_M_u16	42995
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	21705
DMDRELAXECPKSigValidCount_Cnt_M_u16	17528
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	20491
DateInvalidTimer_mS_M_u32	2696175104
DiagMuxOnAbsentTimer_mS_M_u32	2226777600
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2397801984
ESPNTCEnableTimer_mS_M_u32	1260592640
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	38424
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	79
EffacDefaultDiagTimer_mS_M_u32[1]	1236548
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2323
ElecIntTimer_mS_M_u32[1]	454648
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4256386560
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	39234
EtatMTSigValidCount_Cnt_M_u16	35997
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	11536
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	38672
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	34153
ISDAT4V2BSI552MsgTimer_mS_M_u32	4070149632
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	48609
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	48133
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	35997
ISDATBSI3F2MsgTimer_mS_M_u32	2305289728
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	16475
ISDATBSI412MsgLenValidCount_Cnt_M_u16	45487
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	39234
ISDATBSI412MsgTimer_mS_M_u32	1903308288
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	8144
ISDATBSI432MsgLenValidCount_Cnt_M_u16	33980
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	38108
ISDATDIRASentFltAcc_Cnt_M_u16	49808
ISDATDIRASentTimer_mS_M_u32	1070804480
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	22183
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	53658

Name	Input Value
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	63155
ISDYN2CMMMsgTimer_mS_M_u32	3400343040
ISDYNAASChkSumInvalidCount_Cnt_M_u16	51700
ISDYNAASChkSumValidCount_Cnt_M_u16	11076
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	39025
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	7814
ISDYNAASMsgLenValidCount_Cnt_M_u16	42957
ISDYNAASMsgTimeValidCount_Cnt_M_u16	51700
ISDYNAASMsgTimer_mS_M_u32	1509883392
ISDYNABRChkSumInvalidCount_Cnt_M_u16	19998
ISDYNABRChkSumValidCount_Cnt_M_u16	34069
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	47947
ISDYNABRMsgCountValidCount_Cnt_M_u16	16347
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	24085
ISDYNABRMsgLenValidCount_Cnt_M_u16	61909
ISDYNABRMsgTimeValidCount_Cnt_M_u16	35705
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	758
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1401
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	35997
ISDYNCMM208MsgTimer_mS_M_u32	3656572416
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2883
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1507
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	4936
ISDYNCMM388MsgTimer_mS_M_u32	4178214400
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	54892
ISDYNVOLChkSumValidCount_Cnt_M_u16	52588
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	9610
ISDYNVOLMsgCountValidCount_Cnt_M_u16	65057
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	50113
ISDYNVOLMsgLenValidCount_Cnt_M_u16	10528
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	65535
ISDYNVOLMsgTimer_mS_M_u32	3548855808
IgnOnTimer_mS_M_u32	3970858496
IgnTimeOff_Sec_M_u32	2894563525
ManVehSpd_Kph_M_f32	169.484894
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	137
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	201
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2461920768
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	228
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	851955200
PrevISDATBSI412MsgDLCError_Cnt_M_u08	123
PrevISDATBSI412MsgRxTime_MSec_M_u32	1386462720
PrevISDATBSI432MsgDLCError_Cnt_M_u08	32
PrevISDATBSI432MsgRxTime_MSec_M_u32	2906070528
PrevISDATDIRAMsgTxTime_MSec_M_u32	525843968
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	126
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1946750464
PrevISDYNAASMsgDLCError_Cnt_M_u08	103
PrevISDYNAASMsgRxTime_MSec_M_u32	1723153920
PrevISDYNABRMsgDLCError_Cnt_M_u08	74
PrevISDYNABRMsgRxTime_MSec_M_u32	3630595584
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	125
PrevISDYNCMM208MsgRxTime_MSec_M_u32	754597376
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	204
PrevISDYNCMM388MsgRxTime_MSec_M_u32	460463616
PrevISDYNVOLMsgDLCError_Cnt_M_u08	189
PrevISDYNVOLMsgRxTime_MSec_M_u32	3074473472
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3206557184
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	49.391201
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	5172
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	9211
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	16221
VitesseVehicleBVRampValidCount_Cnt_M_u16	35812
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	60448
VitesseVehicleBVSigValidCount_Cnt_M_u16	32527
VitesseVehicleBV_Kph_M_f32	372.090515
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	4936
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	24944
VitesseVehiculeRoues_Kph_M_f32	395.328888
k_AASNTCEnableTimeout_mS_u16	22216
k_AASNodeAbsentDiag_Cnt_str.Threshold	9638
k_AASNodeAbsentDiag_Cnt_str.PStep	52346
k_AASNodeAbsentDiag_Cnt_str.NStep	9652
k_AASNodeAbsentTimeout_mS_u16	3789
k_AASNodeTimeout_mS_u16	46843
k_ABSNodeTimeout_mS_u16	44641
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	35395
k_ANGLEVOLANTSigValidThresh_Cnt_u16	61295
k_AngleVolantInvalidThresh_Cnt_u16	13326
k_AngleVolantValidThresh_Cnt_u16	42624
k_BSI552MsgTimeout_mS_u16	62159
k_BSINTCEnableTimeout_mS_u16	31624
k_BSINodeAbsentDiag_Cnt_str.Threshold	2609
k_BSINodeAbsentDiag_Cnt_str.PStep	2532
k_BSINodeAbsentDiag_Cnt_str.NStep	14370
k_BSINodeAbsentTimeout_mS_u16	23463
k_BSINodeTimeout_mS_u16	38108
k_BattOvHi_Volt_f32	28.2628994
k_BattOvLo_Volt_f32	31.5
k_BattUvHi_Volt_f32	18.5853004
k_BattUvLo_Volt_f32	10.6842003
k_CAVNTCEnableTimeout_mS_u16	34790
k_CAVNodeAbsentDiag_Cnt_str.Threshold	4965
k_CAVNodeAbsentDiag_Cnt_str.PStep	7532
k_CAVNodeAbsentDiag_Cnt_str.NStep	12568
k_CAVNodeAbsentTimeout_mS_u16	7609
k_CAVNodeTimeout_mS_u16	46618
k_CMM388MsgTimeout_mS_u16	13218
k_CMM388NTCEnableTimeout_mS_u16	53502
k_CMMNTCEnableTimeout_mS_u16	46489
k_CMMNodeAbsentDiag_Cnt_str.Threshold	8523
k_CMMNodeAbsentDiag_Cnt_str.PStep	45632
k_CMMNodeAbsentDiag_Cnt_str.NStep	8523
k_CMMNodeAbsentTimeout_mS_u16	62668
k_CONSANGLECPKMax_HwDeg_f32	485.856903
k_CONSANGLECPKMin_HwDeg_f32	-534.970825
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	26184
k_CONSANGLECPKSigValidThresh_Cnt_u16	62576
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	8049
k_CPKVehicleSpeedValidThresh_Cnt_u16	43926
k_CityParkInputInvalidThresh_Cnt_u16	60180
k_CityParkInputValidThresh_Cnt_u16	48702
k_ComputerRazGCTSigValidThresh_Cnt_u16	43447
k_CptTemporelSigValidThresh_Cnt_u16	64603
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	12565
k_DMDFCTCPKSigValidThresh_Cnt_u16	1237
k_DMDFCTCPKValidCount_Cnt_u16	60438
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	63155
k_DMDRELAXECPKSigValidThresh_Cnt_u16	35850

Name	Input Value
k_DMDRelaxeConsistentThresh_Cnt_u16	40576
k_DateValidThresh_Cnt_u16	34153
k_DefaultVehSpd_Kph_f32	224.020706
k_DiagMuxOnAbsentTimeout_mS_u16	46687
k_EMNodeTimeout_mS_u16	63339
k_ESPNTCEnableTimeout_mS_u16	7015
k_ESPNodeAbsentDiag_Cnt_str.Threshold	525
k_ESPNodeAbsentDiag_Cnt_str.PStep	434
k_ESPNodeAbsentDiag_Cnt_str.NStep	5268
k_ESPNodeAbsentTimeout_mS_u16	41236
k_EtatMTSigInvalidThresh_Cnt_u16	53917
k_EtatMTSigValidThresh_Cnt_u16	47828
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	55948
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	26824
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	31591
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	30798
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	24114
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	57855
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	64445
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	26729
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	7028
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	54397
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	9200
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	29626
k_ISDATDIRASentDiag_Cnt_str.Threshold	2435
k_ISDATDIRASentDiag_Cnt_str.PStep	9638
k_ISDATDIRASentDiag_Cnt_str.NStep	54621
k_ISDATDIRASentTimeout_mS_u16	18554
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	9599
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	11759
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	1619
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	41246
k_ISDYNAASChkSumValidThresh_Cnt_u16	6165
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	36427
k_ISDYNAASMsgCountValidThresh_Cnt_u16	21211
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	59074
k_ISDYNAASMsgLenValidThresh_Cnt_u16	64415
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39351
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	54723
k_ISDYNABRChkSumValidThresh_Cnt_u16	28675
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	2510
k_ISDYNABRMsgCountValidThresh_Cnt_u16	9021
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	63276
k_ISDYNABRMsgLenValidThresh_Cnt_u16	26904
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	25116
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	63704
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	23236
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	48986
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	2679
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	32934
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	38968
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	23374
k_ISDYNVOLChkSumValidThresh_Cnt_u16	11490
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	33381
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	4281
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	35998
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	36089
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	46927
k_IgnOnTimeout_mS_u16	2474
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	235.081802
k_PowerCutVehSpdLowThresh_Kph_f32	238.4021
k_PowerCutVehSpdLowTimeout_mS_u16	36884
k_VBattMaxAAS_Volt_f32	11.4061003
k_VBattMaxBSI_Volt_f32	24.0352001
k_VBattMaxCAV_Volt_f32	22.3640003
k_VBattMaxCMM388_Volt_f32	8.9982996
k_VBattMaxCMM_Volt_f32	18.2709999
k_VBattMaxESP_Volt_f32	7.66120005
k_VBattMinAAS_Volt_f32	7.07539988
k_VBattMinBSI_Volt_f32	7.66120005
k_VBattMinCAV_Volt_f32	18.9214993
k_VBattMinCMM388_Volt_f32	31.4941998

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinCMM_Volt_f32	7.03569984
k_VBattMinESP_Volt_f32	18.2709999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	38921
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	3276
k_VitesseVehicleBVRampValidThresh_Cnt_u16	30858
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	57452
k_VitesseVehicleBVSigValidThresh_Cnt_u16	38175
k_VitesseVehicleBVSpeedPassThresh_kph_f32	418.327698
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	61451
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	786
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2696175104
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	11
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8524
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1236548
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	204
target_SrlComInput_Per1_Batt_Volt_f32.value	21.2360001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2503101952
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	39
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.657322705
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4270358016
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2676858368
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	234
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1197653504
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4261928448
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3413966336
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3082952192
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3403103744
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	92
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	105
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	187
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	191
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	217
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3901808128
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	68
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	80
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	130
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	147
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1759739392
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1567137280
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	415088128

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	38
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	118
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	242
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1915342336
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	900
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0923708305
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	67388
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	11.5223999
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	10302

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1236548	1236548	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	9638	9638	✔
AASNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	14199	14199	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	11761	11761	✔
AngleVolantMsgTimer_mS_M_u32	1236548	1236548	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	69.8200378	69.8200378	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	690871808	690871808	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3968912896	3968912896	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2397801984	2397801984	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1236548	1236548	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	4093726208	4093726208	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	4965	4965	✔
CAVNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	17121	17121	✔
CMMNodeAbsentTimer_mS_M_u32	3082952192	3082952192	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	35705	35705	✔
CONSANGLECPK_HwDeg_M_f32	687.4151	687.4151 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	35705	35705	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1070804480	1070804480	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	22612	22612	✔
CityParkInputConsistentCount_Cnt_M_u16	48702	48702	✔
CityParkInputInvalidCount_Cnt_M_u16	42626	42626	✔
CityParkInputMsgTimer_mS_M_u32	1236548	1236548	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1236548	1236548	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1236548	1236548	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2696175104	2696175104	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1236548	1236548	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1236548	1236548	✔
ESPNTCEnableTimer_mS_M_u32	1236548	1236548	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	79	79	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1236548	1236548	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1236548	1236548	✔
ElecIntTimer_mS_M_u32[1]	454648	454648	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1236548	1236548	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	11537	11537	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4270358016	4270358016	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATDIRASentFltAcc_Cnt_M_u16	2435	2435	✔
ISDATDIRASentTimer_mS_M_u32	1236548	1236548	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1236548	1236548	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	54892	54892	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	9610	9610	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	50113	50113	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	415088128	415088128	✔
IgnOnTimer_mS_M_u32	3970858496	3970858496	✔
IgnTimeOff_Sec_M_u32	2894563525	2894563525	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4270358016	4270358016	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	198	198	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2676858368	2676858368	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	234	234	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1197653504	1197653504	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	152	152	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4261928448	4261928448	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	525843968	525843968	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	181	181	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3082952192	3082952192	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	51	51	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3403103744	3403103744	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	135	135	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3901808128	3901808128	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	46	46	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1759739392	1759739392	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	194	194	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1567137280	1567137280	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	153	153	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	415088128	415088128	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1915342336	1915342336	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	49.391201	49.391201	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	5172	5172	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	372.090515	372.090515	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	395.328888	395.328888	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	69.8200378	69.8200378	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	35705	35705	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2894563525	2894563525	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	687.4151	687.4151 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	224.020706	224.020706	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0151	0x0151	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0150	0x0150	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔
NTC	0x0161	0x0161	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.157 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	25835776
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	52718
AASNodeAbsentTimer_mS_M_u32	2688575744
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	15217
ANGLEVOLANTSigValidCount_Cnt_M_u16	58018
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	55815

Name	Input Value
AngleVolantMsgTimer_mS_M_u32	25835776
AngleVolantValidCount_Cnt_M_u16	902
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	373.022186
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3708627200
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2960763136
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	178542848
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4271118592
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	22892
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1448270080
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	820
CAVNodeAbsentTimer_mS_M_u32	870222080
CDD_SrlComVehSpd_Kph_G_f32	553.977478
CMM388NTCEnableTimer_mS_M_u32	4096641280
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1098680576
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	37007
CMMNodeAbsentTimer_mS_M_u32	3581286656
CONSANGLECPKSigInvalidCount_Cnt_M_u16	58265
CONSANGLECPKSigValidCount_Cnt_M_u16	56283
CONSANGLECPK_Cnt_M_u16	17450
CONSANGLECPK_HwDeg_M_f32	-273.089813
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17450
CPKVehicleSpeedMsgTimer_mS_M_u32	2455582976
CPKVehicleSpeedValidCount_Cnt_M_u16	25727
CityParkInputConsistentCount_Cnt_M_u16	52634
CityParkInputInvalidCount_Cnt_M_u16	43478
CityParkInputMsgTimer_mS_M_u32	4270358016
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4015286528
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	30210
ComputerRazGCTSigInvalidTimer_mS_M_u32	3163883776
ComputerRazGCTSigValidCount_Cnt_M_u16	8203
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	35778
DMDFCTCPKSigValidCount_Cnt_M_u16	65340
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	43899
DMDRELAXECPKSigValidCount_Cnt_M_u16	9772
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	13490
DateInvalidTimer_mS_M_u32	2960763136
DiagMuxOnAbsentTimer_mS_M_u32	3467180288
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4271118592
ESPNTCEnableTimer_mS_M_u32	3693963520
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	13453
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	579
EffacDefaultDiagTimer_mS_M_u32[1]	989
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	2324
ElecIntTimer_mS_M_u32[1]	45466
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2168248576
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	54864
EtatMTSigValidCount_Cnt_M_u16	62973
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	61859
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	15717
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	48858

Name	Input Value
ISDAT4V2BSI552MsgTimer_mS_M_u32	193599744
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	40433
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	48455
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	62973
ISDATBSI3F2MsgTimer_mS_M_u32	4171168000
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	53123
ISDATBSI412MsgLenValidCount_Cnt_M_u16	21832
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	54864
ISDATBSI412MsgTimer_mS_M_u32	964704512
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	60835
ISDATBSI432MsgLenValidCount_Cnt_M_u16	63649
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	40897
ISDATDIRASentFltAcc_Cnt_M_u16	59045
ISDATDIRASentTimer_mS_M_u32	2455582976
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	6816
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	902
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	17725
ISDYN2CMMMsgTimer_mS_M_u32	93284608
ISDYNAASChkSumInvalidCount_Cnt_M_u16	23032
ISDYNAASChkSumValidCount_Cnt_M_u16	65482
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	51969
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	10947
ISDYNAASMsgLenValidCount_Cnt_M_u16	14509
ISDYNAASMsgTimeValidCount_Cnt_M_u16	23032
ISDYNAASMsgTimer_mS_M_u32	1998178560
ISDYNABRChkSumInvalidCount_Cnt_M_u16	19707
ISDYNABRChkSumValidCount_Cnt_M_u16	4564
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	41459
ISDYNABRMsgCountValidCount_Cnt_M_u16	56837
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	45716
ISDYNABRMsgLenValidCount_Cnt_M_u16	33046
ISDYNABRMsgTimeValidCount_Cnt_M_u16	17450
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	759
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1403
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	62973
ISDYNCMM208MsgTimer_mS_M_u32	515778816
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2887
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1509
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	30332
ISDYNCMM388MsgTimer_mS_M_u32	670517504
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	25999
ISDYNVOLChkSumValidCount_Cnt_M_u16	2641
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	54456
ISDYNVOLMsgCountValidCount_Cnt_M_u16	13490
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	36754
ISDYNVOLMsgLenValidCount_Cnt_M_u16	26932
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	37007
ISDYNVOLMsgTimer_mS_M_u32	2072054016
IgnOnTimer_mS_M_u32	3708504320
IgnTimeOff_Sec_M_u32	104534031
ManVehSpd_Kph_M_f32	439.74881
Msg348Valid_Cnt_M_Igc	0
Msg432Valid_Cnt_M_Igc	0
Msg552Valid_Cnt_M_Igc	1
NetOn_Cnt_M_Igc	0
NtWrapC_Dem_ClearDTC()	137
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	217
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3030186240
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	32
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3556727040
PrevISDATBSI412MsgDLCError_Cnt_M_u08	17
PrevISDATBSI412MsgRxTime_MSec_M_u32	271288576
PrevISDATBSI432MsgDLCError_Cnt_M_u08	25
PrevISDATBSI432MsgRxTime_MSec_M_u32	99707136
PrevISDATDIRAMsgTxTime_MSec_M_u32	2047838464
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	167

Name	Input Value
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2772146432
PrevISDYNAASMsgDLCError_Cnt_M_u08	136
PrevISDYNAASMsgRxTime_MSec_M_u32	4193716480
PrevISDYNABRMsgDLCError_Cnt_M_u08	108
PrevISDYNABRMsgRxTime_MSec_M_u32	4192422144
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	113
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4213704960
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	115
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1732274432
PrevISDYNVOLMsgDLCError_Cnt_M_u08	226
PrevISDYNVOLMsgRxTime_MSec_M_u32	2522122496
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2289449216
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	200.735107
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	33209
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	64547
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	58430
VitesseVehicleBVRampValidCount_Cnt_M_u16	43112
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	374
VitesseVehicleBVSigValidCount_Cnt_M_u16	37479
VitesseVehicleBV_Kph_M_f32	317.136414
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	30332
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	46534
VitesseVehiculeRoues_Kph_M_f32	394.841187
k_AASNTCEnableTimeout_mS_u16	56893
k_AASNodeAbsentDiag_Cnt_str.Threshold	1893
k_AASNodeAbsentDiag_Cnt_str.PStep	24496
k_AASNodeAbsentDiag_Cnt_str.NStep	12638
k_AASNodeAbsentTimeout_mS_u16	55277
k_AASNodeTimeout_mS_u16	17187
k_ABSNodeTimeout_mS_u16	22067
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	14922
k_ANGLEVOLANTSigValidThresh_Cnt_u16	17544
k_AngleVolantInvalidThresh_Cnt_u16	45739
k_AngleVolantValidThresh_Cnt_u16	43478
k_BSI552MsgTimeout_mS_u16	15785
k_BSINTCEnableTimeout_mS_u16	47739
k_BSINodeAbsentDiag_Cnt_str.Threshold	3061
k_BSINodeAbsentDiag_Cnt_str.PStep	2956
k_BSINodeAbsentDiag_Cnt_str.NStep	17738
k_BSINodeAbsentTimeout_mS_u16	12511
k_BSINodeTimeout_mS_u16	40897
k_BattOvHi_Volt_f32	21.9901009
k_BattOvLo_Volt_f32	17.8794003
k_BattUvHi_Volt_f32	18.0785999
k_BattUvLo_Volt_f32	28.8010998
k_CAVNTCEnableTimeout_mS_u16	7588
k_CAVNodeAbsentDiag_Cnt_str.Threshold	57564
k_CAVNodeAbsentDiag_Cnt_str.PStep	34555
k_CAVNodeAbsentDiag_Cnt_str.NStep	2430
k_CAVNodeAbsentTimeout_mS_u16	47402
k_CAVNodeTimeout_mS_u16	65157
k_CMM388MsgTimeout_mS_u16	21742
k_CMM388NTCEnableTimeout_mS_u16	60634
k_CMMNTCEnableTimeout_mS_u16	38601
k_CMMNodeAbsentDiag_Cnt_str.Threshold	3161
k_CMMNodeAbsentDiag_Cnt_str.PStep	42484
k_CMMNodeAbsentDiag_Cnt_str.NStep	50419

Name	Input Value
k_CMMNodeAbsentTimeout_mS_u16	27570
k_CONSANGLECPKMax_HwDeg_f32	238.172104
k_CONSANGLECPKMin_HwDeg_f32	-765.849487
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	32124
k_CONSANGLECPKSigValidThresh_Cnt_u16	64710
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	25025
k_CPKVehicleSpeedValidThresh_Cnt_u16	14802
k_CityParkInputInvalidThresh_Cnt_u16	52761
k_CityParkInputValidThresh_Cnt_u16	52634
k_ComputerRazGCTSigValidThresh_Cnt_u16	45679
k_CptTemporelSigValidThresh_Cnt_u16	54341
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	14740
k_DMDFCTCPKSigValidThresh_Cnt_u16	18454
k_DMDFCTCPKValidCount_Cnt_u16	22932
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	17725
k_DMDRELAXECPKSigValidThresh_Cnt_u16	28407
k_DMDRelaxeConsistentThresh_Cnt_u16	36757
k_DateValidThresh_Cnt_u16	48858
k_DefaultVehSpd_Kph_f32	162.276703
k_DiagMuxOnAbsentTimeout_mS_u16	56184
k_EMNodeTimeout_mS_u16	48786
k_ESPNTCEnableTimeout_mS_u16	63520
k_ESPNodeAbsentDiag_Cnt_str.Threshold	20253
k_ESPNodeAbsentDiag_Cnt_str.PStep	14408
k_ESPNodeAbsentDiag_Cnt_str.NStep	41687
k_ESPNodeAbsentTimeout_mS_u16	34522
k_EtatMTSigInvalidThresh_Cnt_u16	31614
k_EtatMTSigValidThresh_Cnt_u16	11415
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	23664
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	11134
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	31263
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	25258
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	51904
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	31383
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	19932
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	16794
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	35511
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	31006
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	58500
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	32360
k_ISDATDIRASentDiag_Cnt_str.Threshold	50189
k_ISDATDIRASentDiag_Cnt_str.PStep	7148
k_ISDATDIRASentDiag_Cnt_str.NStep	24623
k_ISDATDIRASentTimeout_mS_u16	52711
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	48409
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	55815
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	59228
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	21499
k_ISDYNAASChkSumValidThresh_Cnt_u16	22740
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	10483
k_ISDYNAASMsgCountValidThresh_Cnt_u16	42245
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	4879
k_ISDYNAASMsgLenValidThresh_Cnt_u16	1335
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	26032
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	33674
k_ISDYNABRChkSumValidThresh_Cnt_u16	16012
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	57452
k_ISDYNABRMsgCountValidThresh_Cnt_u16	56797
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	55183
k_ISDYNABRMsgLenValidThresh_Cnt_u16	48013
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	23872
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	25549
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	25672
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	26118
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	49777
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	43426
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	46254
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	2730
k_ISDYNVOLChkSumValidThresh_Cnt_u16	28591
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	58278
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	65256
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	27708
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	25833

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	16680
k_IgnOnTimeout_mS_u16	28566
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	199.593597
k_PowerCutVehSpdLowThresh_Kph_f32	133.632706
k_PowerCutVehSpdLowTimeout_mS_u16	25177
k_VBattMaxAAS_Volt_f32	6.55980015
k_VBattMaxBSI_Volt_f32	7.15100002
k_VBattMaxCAV_Volt_f32	19.4155998
k_VBattMaxCMM388_Volt_f32	11.3661003
k_VBattMaxCMM_Volt_f32	5.1722002
k_VBattMaxESP_Volt_f32	8.48089981
k_VBattMinAAS_Volt_f32	24.9337997
k_VBattMinBSI_Volt_f32	8.48089981
k_VBattMinCAV_Volt_f32	2.64849997
k_VBattMinCMM388_Volt_f32	29.6977997
k_VBattMinCMM_Volt_f32	3.00979996
k_VBattMinESP_Volt_f32	5.1722002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	3451
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	18673
k_VitesseVehicleBVRampValidThresh_Cnt_u16	56248
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	53585
k_VitesseVehicleBVSigValidThresh_Cnt_u16	3319
k_VitesseVehicleBVSpeedPassThresh_kph_f32	114.9701
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	2612
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	31454
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2960763136
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	145
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	33485
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	0
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	115
target_SrlComInput_Per1_Batt_Volt_f32.value	13.4680996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1992284416
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	229
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.719168186
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2407352576
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2834163968
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	127
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3991832832
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1182738688
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2594162944
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	115
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3528485120
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	147
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3583052032
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	61
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	169
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	245

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	231
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3940821248
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	109
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	172
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	228
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2087471360
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2606557440
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	156
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2782759168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	90
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	121
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	138
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	500783360
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1584
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.662293553
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	295400
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	237.521606
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	60827

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	0	0	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	1893	1893	✔
AASNodeAbsentTimer_mS_M_u32	0	0	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	15217	15217	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	55815	55815	✔
AngleVolantMsgTimer_mS_M_u32	0	0	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	373.022186	373.022186	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	0	0	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	0	0	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	0	0	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	0	0	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	0	0	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1448270080	1448270080	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	57564	57564	✔
CAVNodeAbsentTimer_mS_M_u32	0	0	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	0	0	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	0	0	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3528485120	3528485120	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	17450	17450	✔
CONSANGLECPK_HwDeg_M_f32	-273.089813	-273.089813 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17450	17450	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2455582976	2455582976	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	25727	25727	✔
CityParkInputConsistentCount_Cnt_M_u16	52634	52634	✔
CityParkInputInvalidCount_Cnt_M_u16	43480	43480	✔
CityParkInputMsgTimer_mS_M_u32	0	0	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	0	0	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	0	0	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	0	0	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	0	0	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	0	0	✔
ESPNTCEnableTimer_mS_M_u32	0	0	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	0	0	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	579	579	✔
EffacDefaultDiagTimer_mS_M_u32[1]	989	989	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	0	0	✔
ElecIntTimer_mS_M_u32[1]	45466	45466	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	0	0	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	0	0	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	0	0	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	0	0	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	0	0	✔
ISDATDIRASentFltAcc_Cnt_M_u16	50189	50189	✔
ISDATDIRASentTimer_mS_M_u32	0	0	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	0	0	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	0	0	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	0	0	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	0	0	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	0	0	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	25999	25999	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	54456	54456	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	36754	36754	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2782759168	2782759168	✔
IgnOnTimer_mS_M_u32	3708504320	3708504320	✔
IgnTimeOff_Sec_M_u32	104534031	104534031	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	210	210	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2407352576	2407352576	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	77	77	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2834163968	2834163968	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	127	127	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3991832832	3991832832	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	81	81	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1182738688	1182738688	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2047838464	2047838464	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	115	115	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3528485120	3528485120	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	147	147	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3583052032	3583052032	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	231	231	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3940821248	3940821248	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	228	228	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2087471360	2087471360	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	132	132	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2606557440	2606557440	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	156	156	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2782759168	2782759168	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	500783360	500783360	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	200.735107	200.735107	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	33209	33209	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	317.136414	317.136414	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	394.841187	394.841187	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	373.022186	373.022186	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	17450	17450	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	104534031	104534031	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-273.089813	-273.089813 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	162.276703	162.276703	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0151	0x0151	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0150	0x0150	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.158 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3408140288
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	38902
AASNodeAbsentTimer_mS_M_u32	3284240384
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	31087
ANGLEVOLANTSigValidCount_Cnt_M_u16	42650
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	6059
AngleVolantMsgTimer_mS_M_u32	3408140288
AngleVolantValidCount_Cnt_M_u16	23983
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	702.129333
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	811288576
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	135645184
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1079359488
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3548805120
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	52094
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	927610880
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	14500
CAVNodeAbsentTimer_mS_M_u32	2842109952
CDD_SrlComVehSpd_Kph_G_f32	119.955704
CMM388NTCEnableTimer_mS_M_u32	3044632576
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2022516736
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	59475
CMMNodeAbsentTimer_mS_M_u32	1457551360
CONSANGLECPKSigInvalidCount_Cnt_M_u16	5108
CONSANGLECPKSigValidCount_Cnt_M_u16	36335
CONSANGLECPK_Cnt_M_u16	20738
CONSANGLECPK_HwDeg_M_f32	-142.094498
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	20738
CPKVehicleSpeedMsgTimer_mS_M_u32	615192576
CPKVehicleSpeedValidCount_Cnt_M_u16	64331
CityParkInputConsistentCount_Cnt_M_u16	20339
CityParkInputInvalidCount_Cnt_M_u16	64446
CityParkInputMsgTimer_mS_M_u32	2407352576
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	646285312
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	61370
ComputerRazGCTSigInvalidTimer_mS_M_u32	155428864
ComputerRazGCTSigValidCount_Cnt_M_u16	23584
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	1530
DMDFCTCPKSigValidCount_Cnt_M_u16	61005
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	53585
DMDRELAXECPKSigValidCount_Cnt_M_u16	33788
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	50345
DateInvalidTimer_mS_M_u32	135645184
DiagMuxOnAbsentTimer_mS_M_u32	1321719808
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3548805120
ESPNTCEnableTimer_mS_M_u32	66750464
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	20250
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	1000
EffacDefaultDiagTimer_mS_M_u32[1]	2000
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	565

Name	Input Value
ElecIntTimer_mS_M_u32[1]	78790
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3733731328
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	26642
EtatMTSigValidCount_Cnt_M_u16	7113
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	37334
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	4433
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	42867
ISDAT4V2BSI552MsgTimer_mS_M_u32	77887488
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	28845
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	50539
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	7113
ISDATBSI3F2MsgTimer_mS_M_u32	686151680
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	45305
ISDATBSI412MsgLenValidCount_Cnt_M_u16	37480
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	26642
ISDATBSI412MsgTimer_mS_M_u32	2067929088
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	8471
ISDATBSI432MsgLenValidCount_Cnt_M_u16	21214
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	55037
ISDATDIRASentFltAcc_Cnt_M_u16	37457
ISDATDIRASentTimer_mS_M_u32	615192576
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	9632
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	23983
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	34185
ISDYN2CMMMsgTimer_mS_M_u32	2413070336
ISDYNAASChkSumInvalidCount_Cnt_M_u16	39896
ISDYNAASChkSumValidCount_Cnt_M_u16	19747
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	45886
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	48631
ISDYNAASMsgLenValidCount_Cnt_M_u16	38650
ISDYNAASMsgTimeValidCount_Cnt_M_u16	39896
ISDYNAASMsgTimer_mS_M_u32	3702876160
ISDYNABRChkSumInvalidCount_Cnt_M_u16	17489
ISDYNABRChkSumValidCount_Cnt_M_u16	47236
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	28647
ISDYNABRMsgCountValidCount_Cnt_M_u16	24178
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	21251
ISDYNABRMsgLenValidCount_Cnt_M_u16	19006
ISDYNABRMsgTimeValidCount_Cnt_M_u16	20738
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	760
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1405
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	7113
ISDYNCMM208MsgTimer_mS_M_u32	1867008000
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2891
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1511
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	23757
ISDYNCMM388MsgTimer_mS_M_u32	538765312
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	58898
ISDYNVOLChkSumValidCount_Cnt_M_u16	0
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	33560
ISDYNVOLMsgCountValidCount_Cnt_M_u16	42475
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	37387
ISDYNVOLMsgLenValidCount_Cnt_M_u16	59366
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	59475
ISDYNVOLMsgTimer_mS_M_u32	2088740864
IgnOnTimer_mS_M_u32	1356916736
IgnTimeOff_Sec_M_u32	1406629987
ManVehSpd_Kph_M_f32	310.734894
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	139
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	10

Name	Input Value
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	169
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1827395584
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	1
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	272939008
PrevISDATBSI412MsgDLCError_Cnt_M_u08	15
PrevISDATBSI412MsgRxTime_MSec_M_u32	2290100224
PrevISDATBSI432MsgDLCError_Cnt_M_u08	21
PrevISDATBSI432MsgRxTime_MSec_M_u32	2528020480
PrevISDATDIRAMsgTxTime_MSec_M_u32	3671336960
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	109
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3717199872
PrevISDYNAASMsgDLCError_Cnt_M_u08	252
PrevISDYNAASMsgRxTime_MSec_M_u32	1495115776
PrevISDYNABRMsgDLCError_Cnt_M_u08	170
PrevISDYNABRMsgRxTime_MSec_M_u32	1515776000
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	187
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1502259200
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	229
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1858177024
PrevISDYNVOLMsgDLCError_Cnt_M_u08	220
PrevISDYNVOLMsgRxTime_MSec_M_u32	3657771008
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3865057280
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	200.300598
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	4373
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	42136
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	15750
VitesseVehicleBVRampValidCount_Cnt_M_u16	62409
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	31584
VitesseVehicleBVSigValidCount_Cnt_M_u16	60235
VitesseVehicleBV_Kph_M_f32	535.638794
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	23757
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	8624
VitesseVehiculeRoues_Kph_M_f32	516.604187
k_AASNTCEnableTimeout_mS_u16	36553
k_AASNodeAbsentDiag_Cnt_str.Threshold	19835
k_AASNodeAbsentDiag_Cnt_str.PStep	23642
k_AASNodeAbsentDiag_Cnt_str.NStep	36621
k_AASNodeAbsentTimeout_mS_u16	15482
k_AASNodeTimeout_mS_u16	53144
k_ABSNodeTimeout_mS_u16	43687
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	38690
k_ANGLEVOLANTSigValidThresh_Cnt_u16	52009
k_AngleVolantInvalidThresh_Cnt_u16	52416
k_AngleVolantValidThresh_Cnt_u16	64446
k_BSI552MsgTimeout_mS_u16	54791
k_BSINTCEnableTimeout_mS_u16	6799
k_BSINodeAbsentDiag_Cnt_str.Threshold	3174
k_BSINodeAbsentDiag_Cnt_str.PStep	3062
k_BSINodeAbsentDiag_Cnt_str.NStep	18580
k_BSINodeAbsentTimeout_mS_u16	29475
k_BSINodeTimeout_mS_u16	55037
k_BattOvHi_Volt_f32	30.2616997
k_BattOvLo_Volt_f32	23.2649994
k_BattUvHi_Volt_f32	10.8290005
k_BattUvLo_Volt_f32	17.6046009
k_CAVNTCEnableTimeout_mS_u16	22612
k_CAVNodeAbsentDiag_Cnt_str.Threshold	55765

Name	Input Value
k_CAVNodeAbsentDiag_Cnt_str.PStep	20281
k_CAVNodeAbsentDiag_Cnt_str.NStep	49008
k_CAVNodeAbsentTimeout_mS_u16	28354
k_CAVNodeTimeout_mS_u16	29488
k_CMM388MsgTimeout_mS_u16	758
k_CMM388NTCEnableTimeout_mS_u16	60210
k_CMMNTCEnableTimeout_mS_u16	58917
k_CMMNodeAbsentDiag_Cnt_str.Threshold	413
k_CMMNodeAbsentDiag_Cnt_str.PStep	35980
k_CMMNodeAbsentDiag_Cnt_str.NStep	5967
k_CMMNodeAbsentTimeout_mS_u16	45036
k_CONSANGLECPKMax_HwDeg_f32	303.714691
k_CONSANGLECPKMin_HwDeg_f32	-88.7057037
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	18381
k_CONSANGLECPKSigValidThresh_Cnt_u16	19632
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	27582
k_CPKVehicleSpeedValidThresh_Cnt_u16	28172
k_CityParkInputInvalidThresh_Cnt_u16	47351
k_CityParkInputValidThresh_Cnt_u16	20339
k_ComputerRazGCTSigValidThresh_Cnt_u16	43827
k_CptTemporelSigValidThresh_Cnt_u16	63601
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	48643
k_DMDFCTCPKSigValidThresh_Cnt_u16	62782
k_DMDFCTCPKValidCount_Cnt_u16	27398
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	34185
k_DMDRELAXECPKSigValidThresh_Cnt_u16	19228
k_DMDRelaxeConsistentThresh_Cnt_u16	57666
k_DateValidThresh_Cnt_u16	42867
k_DefaultVehSpd_Kph_f32	35.4305
k_DiagMuxOnAbsentTimeout_mS_u16	17176
k_EMNodeTimeout_mS_u16	42761
k_ESPNTCEnableTimeout_mS_u16	2528
k_ESPNodeAbsentDiag_Cnt_str.Threshold	63570
k_ESPNodeAbsentDiag_Cnt_str.PStep	54417
k_ESPNodeAbsentDiag_Cnt_str.NStep	48292
k_ESPNodeAbsentTimeout_mS_u16	65140
k_EtatMTSigInvalidThresh_Cnt_u16	33992
k_EtatMTSigValidThresh_Cnt_u16	13371
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	63409
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	7496
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	40420
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	18050
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	49408
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	65469
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	9324
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	39923
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	39387
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	33318
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	12981
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	51529
k_ISDATDIRASentDiag_Cnt_str.Threshold	13378
k_ISDATDIRASentDiag_Cnt_str.PStep	37990
k_ISDATDIRASentDiag_Cnt_str.NStep	48989
k_ISDATDIRASentTimeout_mS_u16	29069
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	4406
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	6059
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	11308
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	12113
k_ISDYNAASChkSumValidThresh_Cnt_u16	58244
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	56039
k_ISDYNAASMsgCountValidThresh_Cnt_u16	2418
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	16917
k_ISDYNAASMsgLenValidThresh_Cnt_u16	55644
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	1969
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	14369
k_ISDYNABRChkSumValidThresh_Cnt_u16	27100
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	13950
k_ISDYNABRMsgCountValidThresh_Cnt_u16	24809
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	4947
k_ISDYNABRMsgLenValidThresh_Cnt_u16	47642
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	11968
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	47833
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	18090

Name	Input Value
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	45807
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	58479
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	20890
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	15158
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	23428
k_ISDYNVOLChkSumValidThresh_Cnt_u16	40755
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	58831
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	16712
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	22094
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	32517
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	55433
k_IgnOnTimeout_mS_u16	56512
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	223.979904
k_PowerCutVehSpdLowThresh_Kph_f32	77.8627014
k_PowerCutVehSpdLowTimeout_mS_u16	29301
k_VBattMaxAAS_Volt_f32	16.9636002
k_VBattMaxBSI_Volt_f32	31.7544003
k_VBattMaxCAV_Volt_f32	25.6324997
k_VBattMaxCMM388_Volt_f32	9.79559994
k_VBattMaxCMM_Volt_f32	29.5053997
k_VBattMaxESP_Volt_f32	6.14069986
k_VBattMinAAS_Volt_f32	11.6961002
k_VBattMinBSI_Volt_f32	6.14069986
k_VBattMinCAV_Volt_f32	9.55259991
k_VBattMinCMM388_Volt_f32	27.3425007
k_VBattMinCMM_Volt_f32	11.5970001
k_VBattMinESP_Volt_f32	29.5053997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	10256
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	43119
k_VitesseVehicleBVRampValidThresh_Cnt_u16	28184
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	1421
k_VitesseVehicleBVSigValidThresh_Cnt_u16	17756
k_VitesseVehicleBVSpeedPassThresh_kph_f32	19.8218002
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	9124
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	54375
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	135645184
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	212
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	13090
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	4294967295
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	229
target_SrlComInput_Per1_Batt_Volt_f32.value	10.7533998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3389208576
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	10
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.991452932
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	138
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2173364224
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1069090816
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3140954112
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1006979072
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	170092544
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	188
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1838254080

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2924455936
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	62
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	129
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	147
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	161
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	160
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	584468480
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	76
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	918415360
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3832285184
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	189
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	258615296
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	88
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	129
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	448182272
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	777
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.231509939
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	698024
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	216.445908
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	54639

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4294967295	4294967295	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	4294967295	4294967295	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	702.129333	702.129333	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	811288576	811288576	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	135645184	135645184	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	1079359488	1079359488	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	3548805120	3548805120	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	4294967295	4294967295	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	927610880	927610880	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CAVNodeAbsentFltAcc_Cnt_M_u16	55765	55765	✔
CAVNodeAbsentTimer_mS_M_u32	4294967295	4294967295	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4294967295	4294967295	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	20738	20738	✔
CONSANGLECPK_HwDeg_M_f32	-142.094498	-142.094498 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4294967295	4294967295	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	4294967295	4294967295	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4294967295	4294967295	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4294967295	4294967295	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4294967295	4294967295	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4294967295	4294967295	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4294967295	4294967295	✔
ESPNTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	63570	63570	✔
ESPNodeAbsentTimer_mS_M_u32	4294967295	4294967295	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1000	1000	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2000	2000	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	565	565	✔
ElecIntTimer_mS_M_u32[1]	78790	78790	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	4294967295	4294967295	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2173364224	2173364224	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1069090816	1069090816	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3140954112	3140954112	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1006979072	1006979072	✔
ISDATDIRASentFltAcc_Cnt_M_u16	13378	13378	✔
ISDATDIRASentTimer_mS_M_u32	4294967295	4294967295	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	258615296	258615296	✔
IgnOnTimer_mS_M_u32	1356916736	1356916736	✔
IgnTimeOff_Sec_M_u32	1406629987	1406629987	✔
Msg348Valid_Cnt_M_Igc	0	0	✔
Msg432Valid_Cnt_M_Igc	0	0	✔
Msg552Valid_Cnt_M_Igc	0	0	✔
NetOn_Cnt_M_Igc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	138	138	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2173364224	2173364224	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	5	5	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1069090816	1069090816	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	153	153	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3140954112	3140954112	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	142	142	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1006979072	1006979072	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3671336960	3671336960	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	188	188	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1838254080	1838254080	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	133	133	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2924455936	2924455936	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	160	160	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	584468480	584468480	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	208	208	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	918415360	918415360	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3832285184	3832285184	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	189	189	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	258615296	258615296	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	448182272	448182272	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	200.300598	200.300598	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	535.638794	535.638794	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	516.604187	516.604187	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	702.129333	702.129333	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	20738	20738	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1406629987	1406629987	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-142.094498	-142.094498 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	35.4305	35.4305	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.159 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2962389760
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	46106
AASNodeAbsentTimer_mS_M_u32	1215965952
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	37297
ANGLEVOLANTSigValidCount_Cnt_M_u16	41456
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	18683
AngleVolantMsgTimer_mS_M_u32	2962389760
AngleVolantValidCount_Cnt_M_u16	12143
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	402.936249
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2578246400
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	477981440
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2675809024
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2565561088
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	38788

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	748690176
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	4242
CAVNodeAbsentTimer_mS_M_u32	3054062336
CDD_SrlComVehSpd_Kph_G_f32	532.973694
CMM388NTCEnableTimer_mS_M_u32	2865924864
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1620527872
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	64068
CMMNodeAbsentTimer_mS_M_u32	4141701888
CONSANGLECPKSigInvalidCount_Cnt_M_u16	2336
CONSANGLECPKSigValidCount_Cnt_M_u16	29423
CONSANGLECPK_Cnt_M_u16	13750
CONSANGLECPK_HwDeg_M_f32	-576.3349
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	13750
CPKVehicleSpeedMsgTimer_mS_M_u32	2147318528
CPKVehicleSpeedValidCount_Cnt_M_u16	13573
CityParkInputConsistentCount_Cnt_M_u16	27171
CityParkInputInvalidCount_Cnt_M_u16	41537
CityParkInputMsgTimer_mS_M_u32	2173364224
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	808332032
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	48334
ComputerRazGCTSigInvalidTimer_mS_M_u32	2826160896
ComputerRazGCTSigValidCount_Cnt_M_u16	14364
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	29581
DMDFCTCPKSigValidCount_Cnt_M_u16	62037
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	37387
DMDRELAXECPKSigValidCount_Cnt_M_u16	4554
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	2817
DateInvalidTimer_mS_M_u32	477981440
DiagMuxOnAbsentTimer_mS_M_u32	1688681216
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2565561088
ESPNTCEnableTimer_mS_M_u32	2882480896
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	52655
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	2500
EffacDefaultDiagTimer_mS_M_u32[1]	3500
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	1234
ElecIntTimer_mS_M_u32[1]	23647
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3201964800
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	34822
EtatMTSigValidCount_Cnt_M_u16	13473
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	38778
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	61641
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	57059
ISDAT4V2BSI552MsgTimer_mS_M_u32	4254161664
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	20407
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	14650
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13473
ISDATBSI3F2MsgTimer_mS_M_u32	3461167872
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	4050
ISDATBSI412MsgLenValidCount_Cnt_M_u16	4934
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	34822
ISDATBSI412MsgTimer_mS_M_u32	2553838336
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	24568
ISDATBSI432MsgLenValidCount_Cnt_M_u16	53859
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	55687
ISDATDIRASentFltAcc_Cnt_M_u16	63371
ISDATDIRASentTimer_mS_M_u32	2147318528

Name	Input Value
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	45020
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	12143
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	61664
ISDYN2CMMMsgTimer_mS_M_u32	4030802688
ISDYNAASChkSumInvalidCount_Cnt_M_u16	45172
ISDYNAASChkSumValidCount_Cnt_M_u16	46164
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	10946
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	35993
ISDYNAASMsgLenValidCount_Cnt_M_u16	63824
ISDYNAASMsgTimeValidCount_Cnt_M_u16	45172
ISDYNAASMsgTimer_mS_M_u32	622758656
ISDYNABRChkSumInvalidCount_Cnt_M_u16	12938
ISDYNABRChkSumValidCount_Cnt_M_u16	36273
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	12359
ISDYNABRMsgCountValidCount_Cnt_M_u16	31847
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	18419
ISDYNABRMsgLenValidCount_Cnt_M_u16	14850
ISDYNABRMsgTimeValidCount_Cnt_M_u16	13750
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	761
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1407
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13473
ISDYNCMM208MsgTimer_mS_M_u32	3504728832
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2895
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1513
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	10773
ISDYNCMM388MsgTimer_mS_M_u32	1491602176
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	35526
ISDYNVOLChkSumValidCount_Cnt_M_u16	65535
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	62515
ISDYNVOLMsgCountValidCount_Cnt_M_u16	50043
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	2268
ISDYNVOLMsgLenValidCount_Cnt_M_u16	24331
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	64068
ISDYNVOLMsgTimer_mS_M_u32	1052756736
IgnOnTimer_mS_M_u32	3600550656
IgnTimeOff_Sec_M_u32	1783284699
ManVehSpd_Kph_M_f32	416.356506
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	141
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	233
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2587572992
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	79
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2880477952
PrevISDATBSI412MsgDLCError_Cnt_M_u08	135
PrevISDATBSI412MsgRxTime_MSec_M_u32	3166587648
PrevISDATBSI432MsgDLCError_Cnt_M_u08	23
PrevISDATBSI432MsgRxTime_MSec_M_u32	3283299072
PrevISDATDIRAMsgTxTime_MSec_M_u32	365054720
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	10
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2161040128
PrevISDYNAASMsgDLCError_Cnt_M_u08	202
PrevISDYNAASMsgRxTime_MSec_M_u32	2699414272
PrevISDYNABRMsgDLCError_Cnt_M_u08	177
PrevISDYNABRMsgRxTime_MSec_M_u32	2587101952
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	30
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2476657408
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	11
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1199188736
PrevISDYNVOLMsgDLCError_Cnt_M_u08	96
PrevISDYNVOLMsgRxTime_MSec_M_u32	472861440
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1323203328
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	604.725891

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	35647
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	51318
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	2540
VitesseVehicleBVRampValidCount_Cnt_M_u16	57059
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	36830
VitesseVehicleBVSigValidCount_Cnt_M_u16	55261
VitesseVehicleBV_Kph_M_f32	170.444901
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	10773
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	21292
VitesseVehiculeRoues_Kph_M_f32	241.649994
k_AASNTCEnableTimeout_mS_u16	22625
k_AASNodeAbsentDiag_Cnt_str.Threshold	3540
k_AASNodeAbsentDiag_Cnt_str.PStep	39414
k_AASNodeAbsentDiag_Cnt_str.NStep	2717
k_AASNodeAbsentTimeout_mS_u16	32526
k_AASNodeTimeout_mS_u16	18294
k_ABSNodeTimeout_mS_u16	31110
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	59863
k_ANGLEVOLANTSigValidThresh_Cnt_u16	21890
k_AngleVolantInvalidThresh_Cnt_u16	27837
k_AngleVolantValidThresh_Cnt_u16	41537
k_BSI552MsgTimeout_mS_u16	21031
k_BSINTCEnableTimeout_mS_u16	21392
k_BSINodeAbsentDiag_Cnt_str.Threshold	3287
k_BSINodeAbsentDiag_Cnt_str.PStep	3168
k_BSINodeAbsentDiag_Cnt_str.NStep	19422
k_BSINodeAbsentTimeout_mS_u16	5779
k_BSINodeTimeout_mS_u16	55687
k_BattOvHi_Volt_f32	26.9316998
k_BattOvLo_Volt_f32	8.40769958
k_BattUvHi_Volt_f32	16.2306995
k_BattUvLo_Volt_f32	9.07530022
k_CAVNTCEnableTimeout_mS_u16	25727
k_CAVNodeAbsentDiag_Cnt_str.Threshold	7812
k_CAVNodeAbsentDiag_Cnt_str.PStep	34587
k_CAVNodeAbsentDiag_Cnt_str.NStep	20277
k_CAVNodeAbsentTimeout_mS_u16	26168
k_CAVNodeTimeout_mS_u16	56172
k_CMM388MsgTimeout_mS_u16	29466
k_CMM388NTCEnableTimeout_mS_u16	43622
k_CMMNTCEnableTimeout_mS_u16	53071
k_CMMNodeAbsentDiag_Cnt_str.Threshold	43118
k_CMMNodeAbsentDiag_Cnt_str.PStep	97
k_CMMNodeAbsentDiag_Cnt_str.NStep	43223
k_CMMNodeAbsentTimeout_mS_u16	39032
k_CONSANGLECPKMax_HwDeg_f32	333.559814
k_CONSANGLECPKMin_HwDeg_f32	-755.722778
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	26901
k_CONSANGLECPKSigValidThresh_Cnt_u16	53804
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	35588
k_CPKVehicleSpeedValidThresh_Cnt_u16	58521
k_CityParkInputInvalidThresh_Cnt_u16	60568
k_CityParkInputValidThresh_Cnt_u16	27171
k_ComputerRazGCTSigValidThresh_Cnt_u16	14373
k_CptTemporelSigValidThresh_Cnt_u16	14376
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	1779
k_DMDFCTCPKSigValidThresh_Cnt_u16	14594
k_DMDFCTCPKValidCount_Cnt_u16	55532

Name	Input Value
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	61664
k_DMDRELAXECPKSigValidThresh_Cnt_u16	55272
k_DMDRelaxeConsistentThresh_Cnt_u16	11638
k_DateValidThresh_Cnt_u16	57059
k_DefaultVehSpd_Kph_f32	248.203506
k_DiagMuxOnAbsentTimeout_mS_u16	14196
k_EMNodeTimeout_mS_u16	58337
k_ESPNTCEnableTimeout_mS_u16	36062
k_ESPNodeAbsentDiag_Cnt_str.Threshold	34640
k_ESPNodeAbsentDiag_Cnt_str.PStep	11091
k_ESPNodeAbsentDiag_Cnt_str.NStep	64473
k_ESPNodeAbsentTimeout_mS_u16	52448
k_EtatMTSigInvalidThresh_Cnt_u16	3365
k_EtatMTSigValidThresh_Cnt_u16	46732
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	29483
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	18982
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	33488
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	25144
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	55931
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	13190
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	59897
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	35620
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	1452
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	12874
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	18525
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	22498
k_ISDATDIRASentDiag_Cnt_str.Threshold	829
k_ISDATDIRASentDiag_Cnt_str.PStep	43924
k_ISDATDIRASentDiag_Cnt_str.NStep	17262
k_ISDATDIRASentTimeout_mS_u16	39638
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	29723
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	18683
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	22010
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	29066
k_ISDYNAASChkSumValidThresh_Cnt_u16	3249
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	61255
k_ISDYNAASMsgCountValidThresh_Cnt_u16	31591
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	18750
k_ISDYNAASMsgLenValidThresh_Cnt_u16	14890
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	49130
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	37017
k_ISDYNABRChkSumValidThresh_Cnt_u16	54056
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	22148
k_ISDYNABRMsgCountValidThresh_Cnt_u16	28419
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	31044
k_ISDYNABRMsgLenValidThresh_Cnt_u16	36015
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	8574
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	40435
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	21183
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	47473
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	20657
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	41200
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	50137
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	64561
k_ISDYNVOLChkSumValidThresh_Cnt_u16	55525
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	7568
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	869
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	44370
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	64237
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	9121
k_IgnOnTimeout_mS_u16	26749
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	61.0555992
k_PowerCutVehSpdLowThresh_Kph_f32	251.407196
k_PowerCutVehSpdLowTimeout_mS_u16	23901
k_VBattMaxAAS_Volt_f32	20.8448009
k_VBattMaxBSI_Volt_f32	25.7791004
k_VBattMaxCAV_Volt_f32	25.6299992
k_VBattMaxCMM388_Volt_f32	20.5958996
k_VBattMaxCMM_Volt_f32	24.0827007
k_VBattMaxESP_Volt_f32	2.4921999
k_VBattMinAAS_Volt_f32	19.0841007
k_VBattMinBSI_Volt_f32	2.4921999

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinCAV_Volt_f32	16.1224995
k_VBattMinCMM388_Volt_f32	14.3294001
k_VBattMinCMM_Volt_f32	18.9946003
k_VBattMinESP_Volt_f32	24.0827007
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	6029
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	65072
k_VitesseVehicleBVRampValidThresh_Cnt_u16	13107
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	1045
k_VitesseVehicleBVSigValidThresh_Cnt_u16	27752
k_VitesseVehicleBVSpeedPassThresh_kph_f32	490.463409
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	20370
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	13577
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	477981440
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	249
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	54592
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	21324
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	11
target_SrlComInput_Per1_Batt_Volt_f32.value	22.4267006
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2557811456
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	47
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.494465679
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1822296832
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	311667456
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3231271680
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	79
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2662263552
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3570699008
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2332699392
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3914320640
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	111
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	114
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	202
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	226
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1849420544
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	47
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	82
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	158
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	232
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	147
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3640986368
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	182
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2960829184

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	140
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1342196480
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	94
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	170
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	195
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3562707712
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	668
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.532882392
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	24660
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	20.9074001
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	9777

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	21324	21324	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	21324	21324	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	21324	21324	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	402.936249	402.936249	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2578246400	2578246400	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	21324	21324	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2675809024	2675809024	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	2565561088	2565561088	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	19366	19366	✔
BSINodeAbsentTimer_mS_M_u32	2662263552	2662263552	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	748690176	748690176	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1342196480	1342196480	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	21324	21324	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1620527872	1620527872	✔
CMMNTCsEnabled_Cnt_M_lgc	1	1	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	20845	20845	✔
CMMNodeAbsentTimer_mS_M_u32	2332699392	2332699392	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	13750	13750	✔
CONSANGLECPK_HwDeg_M_f32	-576.3349	-576.3349 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	21324	21324	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	21324	21324	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	21324	21324	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ComputerRazGCTSigInvalidTimer_mS_M_u32	21324	21324	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	21324	21324	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	21324	21324	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	21324	21324	✔
ESPNTCEnableTimer_mS_M_u32	21324	21324	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	34640	34640	✔
ESPNodeAbsentTimer_mS_M_u32	21324	21324	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2500	2500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3500	3500	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1234	1234	✔
ElecIntTimer_mS_M_u32[1]	23647	23647	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	21324	21324	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1822296832	1822296832	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	311667456	311667456	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	21324	21324	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2662263552	2662263552	✔
ISDATDIRASentFltAcc_Cnt_M_u16	46109	46109	✔
ISDATDIRASentTimer_mS_M_u32	21324	21324	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2332699392	2332699392	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	21324	21324	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	21324	21324	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3640986368	3640986368	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	21324	21324	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1342196480	1342196480	✔
IgnOnTimer_mS_M_u32	3600550656	3600550656	✔
IgnTimeOff_Sec_M_u32	1783284699	1783284699	✔
Msg348Valid_Cnt_M_Igc	0	0	✔
Msg432Valid_Cnt_M_Igc	0	0	✔
Msg552Valid_Cnt_M_Igc	0	0	✔
NetOn_Cnt_M_Igc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	216	216	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1822296832	1822296832	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	169	169	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	311667456	311667456	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	110	110	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3231271680	3231271680	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	79	79	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2662263552	2662263552	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3570699008	3570699008	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	5	5	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2332699392	2332699392	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3914320640	3914320640	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	158	158	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1849420544	1849420544	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	147	147	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3640986368	3640986368	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	182	182	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2960829184	2960829184	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	140	140	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1342196480	1342196480	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3562707712	3562707712	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	604.725891	604.725891	✔
PrevVitesseVehicleBVValid_Cnt_M_Igc	0	0	✔
ResetTimers_Cnt_M_Igc	0	0	✔
StartupTimeCalculated_Cnt_M_Igc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_Igc	0	0	✔
VehTimeValid_Cnt_M_Igc	1	1	✔
VehicleSpeedValid_Cnt_M_Igc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	170.444901	170.444901	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	241.649994	241.649994	✔
target_SrlComInput_Per1_APAAuthn_Cnt_Igc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_Igc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	402.936249	402.936249	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_Igc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_Igc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	13750	13750	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1783284699	1783284699	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-576.3349	-576.3349 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	248.203506	248.203506	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.160 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	697520640
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	57593
AASNodeAbsentTimer_mS_M_u32	3701228032
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	49718
ANGLEVOLANTSigValidCount_Cnt_M_u16	51768
APARequest_Cnt_M_lgc	1

Name	Input Value
AngleVolantInvalidCount_Cnt_M_u16	58966
AngleVolantMsgTimer_mS_M_u32	697520640
AngleVolantValidCount_Cnt_M_u16	2427
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	380.572174
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	604242432
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2106753536
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1901195776
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1812509184
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	48317
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1944744448
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	4116
CAVNodeAbsentTimer_mS_M_u32	946790912
CDD_SrlComVehSpd_Kph_G_f32	607.360718
CMM388NTCEnableTimer_mS_M_u32	252912128
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	4039434752
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	26813
CMMNodeAbsentTimer_mS_M_u32	2587013632
CONSANGLECPKSigInvalidCount_Cnt_M_u16	34538
CONSANGLECPKSigValidCount_Cnt_M_u16	49724
CONSANGLECPK_Cnt_M_u16	21991
CONSANGLECPK_HwDeg_M_f32	752.587097
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21991
CPKVehicleSpeedMsgTimer_mS_M_u32	659706368
CPKVehicleSpeedValidCount_Cnt_M_u16	64899
CityParkInputConsistentCount_Cnt_M_u16	10591
CityParkInputInvalidCount_Cnt_M_u16	51717
CityParkInputMsgTimer_mS_M_u32	1822296832
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4118823424
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	38621
ComputerRazGCTSigInvalidTimer_mS_M_u32	724525568
ComputerRazGCTSigValidCount_Cnt_M_u16	58228
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	34337
DMDFCTCPKSigValidCount_Cnt_M_u16	25227
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	43304
DMDRELAXECPKSigValidCount_Cnt_M_u16	25258
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	17735
DateInvalidTimer_mS_M_u32	2106753536
DiagMuxOnAbsentTimer_mS_M_u32	1347752448
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1812509184
ESPNTCEnableTimer_mS_M_u32	1184711168
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	55099
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	102
EffacDefaultDiagTimer_mS_M_u32[1]	2646119936
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	6448
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	624718336
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	39030
EtatMTSigValidCount_Cnt_M_u16	15204
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	50140
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	12462

Name	Input Value
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	21729
ISDAT4V2BSI552MsgTimer_mS_M_u32	1444327936
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	40163
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	10522
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	15204
ISDATBSI3F2MsgTimer_mS_M_u32	727912960
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	55698
ISDATBSI412MsgLenValidCount_Cnt_M_u16	55288
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	39030
ISDATBSI412MsgTimer_mS_M_u32	2325828096
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1953
ISDATBSI432MsgLenValidCount_Cnt_M_u16	39199
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	51509
ISDATDIRASentFltAcc_Cnt_M_u16	32553
ISDATDIRASentTimer_mS_M_u32	659706368
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	65397
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	2427
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	6696
ISDYN2CMMMsgTimer_mS_M_u32	3242672640
ISDYNAASChkSumInvalidCount_Cnt_M_u16	54251
ISDYNAASChkSumValidCount_Cnt_M_u16	33038
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	9090
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	30719
ISDYNAASMsgLenValidCount_Cnt_M_u16	19097
ISDYNAASMsgTimeValidCount_Cnt_M_u16	54251
ISDYNAASMsgTimer_mS_M_u32	3492749824
ISDYNABRChkSumInvalidCount_Cnt_M_u16	56107
ISDYNABRChkSumValidCount_Cnt_M_u16	41590
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	24690
ISDYNABRMsgCountValidCount_Cnt_M_u16	13525
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	54897
ISDYNABRMsgLenValidCount_Cnt_M_u16	30979
ISDYNABRMsgTimeValidCount_Cnt_M_u16	21991
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	762
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1409
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	15204
ISDYNCMM208MsgTimer_mS_M_u32	2723742208
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2899
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1515
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	12681
ISDYNCMM388MsgTimer_mS_M_u32	986882560
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	6648
ISDYNVOLChkSumValidCount_Cnt_M_u16	21320
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	7215
ISDYNVOLMsgCountValidCount_Cnt_M_u16	1817
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	6580
ISDYNVOLMsgLenValidCount_Cnt_M_u16	4071
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	26813
ISDYNVOLMsgTimer_mS_M_u32	2555077120
IgnOnTimer_mS_M_u32	2444665344
IgnTimeOff_Sec_M_u32	345965826
ManVehSpd_Kph_M_f32	246.391098
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	143
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4288221696
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	130
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3635999232
PrevISDATBSI412MsgDLCError_Cnt_M_u08	183
PrevISDATBSI412MsgRxTime_MSec_M_u32	944759296
PrevISDATBSI432MsgDLCError_Cnt_M_u08	34
PrevISDATBSI432MsgRxTime_MSec_M_u32	2398175744
PrevISDATDIRAMsgTxTime_MSec_M_u32	1027858944

Name	Input Value
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	91
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2724082176
PrevISDYNAASMsgDLCError_Cnt_M_u08	215
PrevISDYNAASMsgRxTime_MSec_M_u32	2312724992
PrevISDYNABRMsgDLCError_Cnt_M_u08	74
PrevISDYNABRMsgRxTime_MSec_M_u32	2800656896
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	34
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3584975360
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	25
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3751559680
PrevISDYNVOLMsgDLCError_Cnt_M_u08	110
PrevISDYNVOLMsgRxTime_MSec_M_u32	503112192
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2125419008
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	110.083199
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	37901
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	62759
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	3078
VitesseVehicleBVRampValidCount_Cnt_M_u16	42464
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	48047
VitesseVehicleBVSigValidCount_Cnt_M_u16	7281
VitesseVehicleBV_Kph_M_f32	354.065002
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	12681
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	20228
VitesseVehiculeRoues_Kph_M_f32	98.1465988
k_AASNTCEnableTimeout_mS_u16	23014
k_AASNodeAbsentDiag_Cnt_str.Threshold	34038
k_AASNodeAbsentDiag_Cnt_str.PStep	46671
k_AASNodeAbsentDiag_Cnt_str.NStep	18971
k_AASNodeAbsentTimeout_mS_u16	22174
k_AASNodeTimeout_mS_u16	30759
k_ABSNodeTimeout_mS_u16	38966
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	42500
k_ANGLEVOLANTSigValidThresh_Cnt_u16	19394
k_AngleVolantInvalidThresh_Cnt_u16	45585
k_AngleVolantValidThresh_Cnt_u16	51717
k_BSI552MsgTimeout_mS_u16	65043
k_BSINTCEnableTimeout_mS_u16	36057
k_BSINodeAbsentDiag_Cnt_str.Threshold	3400
k_BSINodeAbsentDiag_Cnt_str.PStep	3274
k_BSINodeAbsentDiag_Cnt_str.NStep	20264
k_BSINodeAbsentTimeout_mS_u16	56718
k_BSINodeTimeout_mS_u16	51509
k_BattOvHi_Volt_f32	2.93589997
k_BattOvLo_Volt_f32	14.5503998
k_BattUvHi_Volt_f32	14.5358
k_BattUvLo_Volt_f32	28.9878006
k_CAVNTCEnableTimeout_mS_u16	64331
k_CAVNodeAbsentDiag_Cnt_str.Threshold	12708
k_CAVNodeAbsentDiag_Cnt_str.PStep	40352
k_CAVNodeAbsentDiag_Cnt_str.NStep	64273
k_CAVNodeAbsentTimeout_mS_u16	10018
k_CAVNodeTimeout_mS_u16	16390
k_CMM388MsgTimeout_mS_u16	41977
k_CMM388NTCEnableTimeout_mS_u16	11797
k_CMMNTCEnableTimeout_mS_u16	32283
k_CMMNodeAbsentDiag_Cnt_str.Threshold	36902
k_CMMNodeAbsentDiag_Cnt_str.PStep	40462

Name	Input Value
k_CMMNodeAbsentDiag_Cnt_str.NStep	51819
k_CMMNodeAbsentTimeout_mS_u16	44832
k_CONSANGLECPKMax_HwDeg_f32	296.79361
k_CONSANGLECPKMin_HwDeg_f32	-553.726685
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	29833
k_CONSANGLECPKSigValidThresh_Cnt_u16	53764
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	25981
k_CPKVehicleSpeedValidThresh_Cnt_u16	14141
k_CityParkInputInvalidThresh_Cnt_u16	25857
k_CityParkInputValidThresh_Cnt_u16	10591
k_ComputerRazGCTSigValidThresh_Cnt_u16	7065
k_CptTemporelSigValidThresh_Cnt_u16	25680
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	39281
k_DMDFCTCPKSigValidThresh_Cnt_u16	31747
k_DMDFCTCPKValidCount_Cnt_u16	39045
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	6696
k_DMDRELAXECPKSigValidThresh_Cnt_u16	48594
k_DMDRelaxeConsistentThresh_Cnt_u16	29992
k_DateValidThresh_Cnt_u16	21729
k_DefaultVehSpd_Kph_f32	97.1813965
k_DiagMuxOnAbsentTimeout_mS_u16	51373
k_EMNodeTimeout_mS_u16	15015
k_ESPNTCEnableTimeout_mS_u16	52016
k_ESPNodeAbsentDiag_Cnt_str.Threshold	43648
k_ESPNodeAbsentDiag_Cnt_str.PStep	5177
k_ESPNodeAbsentDiag_Cnt_str.NStep	2150
k_ESPNodeAbsentTimeout_mS_u16	45544
k_EtatMTSigInvalidThresh_Cnt_u16	30554
k_EtatMTSigValidThresh_Cnt_u16	21477
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	2312
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	44247
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	54104
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	43360
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	35159
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	15990
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	44446
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	45788
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	59013
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	45099
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	63153
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	20068
k_ISDATDIRASentDiag_Cnt_str.Threshold	42873
k_ISDATDIRASentDiag_Cnt_str.PStep	21557
k_ISDATDIRASentDiag_Cnt_str.NStep	16998
k_ISDATDIRASentTimeout_mS_u16	53831
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	7609
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58966
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	57308
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	7723
k_ISDYNAASChkSumValidThresh_Cnt_u16	9590
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	9074
k_ISDYNAASMsgCountValidThresh_Cnt_u16	14293
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	26383
k_ISDYNAASMsgLenValidThresh_Cnt_u16	28683
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	44170
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	5247
k_ISDYNABRChkSumValidThresh_Cnt_u16	50577
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	32701
k_ISDYNABRMsgCountValidThresh_Cnt_u16	28415
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	60349
k_ISDYNABRMsgLenValidThresh_Cnt_u16	39483
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	910
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	11249
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	1227
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	52790
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	34102
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	52536
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	50493
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	20597
k_ISDYNVOLChkSumValidThresh_Cnt_u16	49947
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	43928
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	4442
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	22674

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	6272
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	65191
k_IgnOnTimeout_mS_u16	15249
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	35.1253014
k_PowerCutVehSpdLowThresh_Kph_f32	208.070602
k_PowerCutVehSpdLowTimeout_mS_u16	15090
k_VBattMaxAAS_Volt_f32	0.860499978
k_VBattMaxBSI_Volt_f32	3.13779998
k_VBattMaxCAV_Volt_f32	8.6637001
k_VBattMaxCMM388_Volt_f32	0.86619997
k_VBattMaxCMM_Volt_f32	0.556999981
k_VBattMaxESP_Volt_f32	10.3823996
k_VBattMinAAS_Volt_f32	25.8332996
k_VBattMinBSI_Volt_f32	10.3823996
k_VBattMinCAV_Volt_f32	4.23559999
k_VBattMinCMM388_Volt_f32	12.5434999
k_VBattMinCMM_Volt_f32	27.2619991
k_VBattMinESP_Volt_f32	0.556999981
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	31587
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	36921
k_VitesseVehicleBVRampValidThresh_Cnt_u16	24367
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	9930
k_VitesseVehicleBVSigValidThresh_Cnt_u16	30352
k_VitesseVehicleBVSpeedPassThresh_kph_f32	450.947815
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	21268
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	47982
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2106753536
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	113
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	0
target Rte Call Ap SrlComInput SystemTime GetSystemTime mS u32 CurrentT	2646119936
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target Rte Inst Ap SrlComInput.SrlComInput Per1 ISDATBSI432MsgRxTime MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	25
target_SrlComInput_Per1_Batt_Volt_f32.value	6.81890011
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3295375872
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	245
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.102368861
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1471193600
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3293561344
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1488904704
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2633892352
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	420291072
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1424769536
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	189
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3634061824
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	36
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	100
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	170

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	212
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2723611136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	60
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	126
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1853596160
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1184547328
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	109699584
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	72
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2260398592
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	514
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.804085612
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1042733
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	87.8199005
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	2871

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2646119936	2646119936	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	34038	34038	✔
AASNodeAbsentTimer_mS_M_u32	2646119936	2646119936	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	1	1	✔
AngleVolantMsgTimer_mS_M_u32	109699584	109699584	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	380.572174	380.572174	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2646119936	2646119936	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2646119936	2646119936	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2646119936	2646119936	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2646119936	2646119936	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2646119936	2646119936	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1944744448	1944744448	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	12708	12708	✔
CAVNodeAbsentTimer_mS_M_u32	2646119936	2646119936	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2646119936	2646119936	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2646119936	2646119936	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1424769536	1424769536	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	21991	21991	✔
CONSANGLECPK_HwDeg_M_f32	752.587097	752.587097 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2646119936	2646119936	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	1	1	✔
CityParkInputMsgTimer_mS_M_u32	3634061824	3634061824	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2646119936	2646119936	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2646119936	2646119936	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2646119936	2646119936	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2646119936	2646119936	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2646119936	2646119936	✔
ESPNTCEnableTimer_mS_M_u32	2646119936	2646119936	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2646119936	2646119936	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	102	102	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2646119936	2646119936	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2646119936	2646119936	✔
ElecIntTimer_mS_M_u32[1]	6448	6448	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	624718336	624718336	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2646119936	2646119936	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2646119936	2646119936	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2646119936	2646119936	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2646119936	2646119936	✔
ISDATDIRASentFltAcc_Cnt_M_u16	42873	42873	✔
ISDATDIRASentTimer_mS_M_u32	2646119936	2646119936	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2646119936	2646119936	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2646119936	2646119936	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2646119936	2646119936	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2646119936	2646119936	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2646119936	2646119936	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	109699584	109699584	✔
IgnOnTimer_mS_M_u32	2444665344	2444665344	✔
IgnTimeOff_Sec_M_u32	345965826	345965826	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	125	125	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1471193600	1471193600	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	73	73	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3293561344	3293561344	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	121	121	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1488904704	1488904704	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	148	148	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2633892352	2633892352	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1027858944	1027858944	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	174	174	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1424769536	1424769536	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	189	189	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3634061824	3634061824	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	26	26	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2723611136	2723611136	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	166	166	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1853596160	1853596160	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	126	126	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1184547328	1184547328	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	121	121	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	109699584	109699584	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2260398592	2260398592	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	110.083199	110.083199	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	354.065002	354.065002	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	98.1465988	98.1465988	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	380.572174	380.572174	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	21991	21991	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	345965826	345965826	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	752.587097	752.587097 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	97.1813965	97.1813965	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.161 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1923927296
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	1657
AASNodeAbsentTimer_mS_M_u32	3914464512
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	62659
ANGLEVOLANTSigValidCount_Cnt_M_u16	12924
APARequest_Cnt_M_lgc	1

Name	Input Value
AngleVolantInvalidCount_Cnt_M_u16	43618
AngleVolantMsgTimer_mS_M_u32	1923927296
AngleVolantValidCount_Cnt_M_u16	48498
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	737.649292
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1645919488
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2943302912
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1576070400
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3100421376
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	57646
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1478978816
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	43945
CAVNodeAbsentTimer_mS_M_u32	3898219776
CDD_SrlComVehSpd_Kph_G_f32	504.980103
CMM388NTCEnableTimer_mS_M_u32	1164795136
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2539134208
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	24687
CMMNodeAbsentTimer_mS_M_u32	1447996672
CONSANGLECPKSigInvalidCount_Cnt_M_u16	9640
CONSANGLECPKSigValidCount_Cnt_M_u16	2417
CONSANGLECPK_Cnt_M_u16	47728
CONSANGLECPK_HwDeg_M_f32	101.905998
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	47728
CPKVehicleSpeedMsgTimer_mS_M_u32	896519424
CPKVehicleSpeedValidCount_Cnt_M_u16	62213
CityParkInputConsistentCount_Cnt_M_u16	60870
CityParkInputInvalidCount_Cnt_M_u16	12503
CityParkInputMsgTimer_mS_M_u32	1471193600
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	782630144
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	29901
ComputerRazGCTSigInvalidTimer_mS_M_u32	2987957504
ComputerRazGCTSigValidCount_Cnt_M_u16	21383
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	27779
DMDFCTCPKSigValidCount_Cnt_M_u16	52483
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	34797
DMDRELAXECPKSigValidCount_Cnt_M_u16	45350
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	40593
DateInvalidTimer_mS_M_u32	2943302912
DiagMuxOnAbsentTimer_mS_M_u32	895978752
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3100421376
ESPNTCEnableTimer_mS_M_u32	4014931200
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	23220
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	89
EffacDefaultDiagTimer_mS_M_u32[1]	789
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	56565
ElecIntTimer_mS_M_u32[1]	787881
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	204565760
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	17987
EtatMTSigValidCount_Cnt_M_u16	25400
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	46802
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1563

Name	Input Value
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	52737
ISDAT4V2BSI552MsgTimer_mS_M_u32	2997005568
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	9851
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	42904
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	25400
ISDATBSI3F2MsgTimer_mS_M_u32	1547537664
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	63856
ISDATBSI412MsgLenValidCount_Cnt_M_u16	58365
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	17987
ISDATBSI412MsgTimer_mS_M_u32	126012672
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	5059
ISDATBSI432MsgLenValidCount_Cnt_M_u16	42248
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	17478
ISDATDIRASentFltAcc_Cnt_M_u16	62058
ISDATDIRASentTimer_mS_M_u32	896519424
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	30150
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	48498
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	35950
ISDYN2CMMMsgTimer_mS_M_u32	2807102720
ISDYNAASChkSumInvalidCount_Cnt_M_u16	30115
ISDYNAASChkSumValidCount_Cnt_M_u16	17403
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	19293
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	57320
ISDYNAASMsgLenValidCount_Cnt_M_u16	7641
ISDYNAASMsgTimeValidCount_Cnt_M_u16	30115
ISDYNAASMsgTimer_mS_M_u32	1914264832
ISDYNABRChkSumInvalidCount_Cnt_M_u16	46947
ISDYNABRChkSumValidCount_Cnt_M_u16	55108
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	44046
ISDYNABRMsgCountValidCount_Cnt_M_u16	1190
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	4883
ISDYNABRMsgLenValidCount_Cnt_M_u16	49436
ISDYNABRMsgTimeValidCount_Cnt_M_u16	47728
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	763
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1411
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	25400
ISDYNCMM208MsgTimer_mS_M_u32	2065415424
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2903
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1517
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	64840
ISDYNCMM388MsgTimer_mS_M_u32	539942144
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0
ISDYNVOLChkSumValidCount_Cnt_M_u16	40135
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	25177
ISDYNVOLMsgCountValidCount_Cnt_M_u16	38745
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	46921
ISDYNVOLMsgLenValidCount_Cnt_M_u16	60017
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	24687
ISDYNVOLMsgTimer_mS_M_u32	3670318336
IgnOnTimer_mS_M_u32	2877480192
IgnTimeOff_Sec_M_u32	2992063655
ManVehSpd_Kph_M_f32	438.653015
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	145
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	59
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	932941056
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	197
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2210131200
PrevISDATBSI412MsgDLCError_Cnt_M_u08	148
PrevISDATBSI412MsgRxTime_MSec_M_u32	2897681664
PrevISDATBSI432MsgDLCError_Cnt_M_u08	1
PrevISDATBSI432MsgRxTime_MSec_M_u32	1716714752
PrevISDATDIRAMsgTxTime_MSec_M_u32	1843076352

Name	Input Value
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	30
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1271672064
PrevISDYNAASMsgDLCError_Cnt_M_u08	122
PrevISDYNAASMsgRxTime_MSec_M_u32	3189415168
PrevISDYNABRMsgDLCError_Cnt_M_u08	169
PrevISDYNABRMsgRxTime_MSec_M_u32	1272634624
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	193
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1855692032
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	163
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3763469568
PrevISDYNVOLMsgDLCError_Cnt_M_u08	216
PrevISDYNVOLMsgRxTime_MSec_M_u32	4021296384
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3814247680
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	217.5159
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	17342
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	54831
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	65491
VitesseVehicleBVRampValidCount_Cnt_M_u16	59396
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	11352
VitesseVehicleBVSigValidCount_Cnt_M_u16	24529
VitesseVehicleBV_Kph_M_f32	36.7935982
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	64840
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	55961
VitesseVehiculeRoues_Kph_M_f32	275.118195
k_AASNTCEnableTimeout_mS_u16	27251
k_AASNodeAbsentDiag_Cnt_str.Threshold	42763
k_AASNodeAbsentDiag_Cnt_str.PStep	37313
k_AASNodeAbsentDiag_Cnt_str.NStep	9499
k_AASNodeAbsentTimeout_mS_u16	8713
k_AASNodeTimeout_mS_u16	19759
k_ABSNodeTimeout_mS_u16	51780
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	33946
k_ANGLEVOLANTSigValidThresh_Cnt_u16	55583
k_AngleVolantInvalidThresh_Cnt_u16	41522
k_AngleVolantValidThresh_Cnt_u16	12503
k_BSI552MsgTimeout_mS_u16	51564
k_BSINTCEnableTimeout_mS_u16	25627
k_BSINodeAbsentDiag_Cnt_str.Threshold	3513
k_BSINodeAbsentDiag_Cnt_str.PStep	3380
k_BSINodeAbsentDiag_Cnt_str.NStep	21106
k_BSINodeAbsentTimeout_mS_u16	42170
k_BSINodeTimeout_mS_u16	17478
k_BattOvHi_Volt_f32	20.4743004
k_BattOvLo_Volt_f32	20.0032005
k_BattUvHi_Volt_f32	14.6834002
k_BattUvLo_Volt_f32	24.8698006
k_CAVNTCEnableTimeout_mS_u16	13573
k_CAVNodeAbsentDiag_Cnt_str.Threshold	1217
k_CAVNodeAbsentDiag_Cnt_str.PStep	53131
k_CAVNodeAbsentDiag_Cnt_str.NStep	38393
k_CAVNodeAbsentTimeout_mS_u16	7807
k_CAVNodeTimeout_mS_u16	27220
k_CMM388MsgTimeout_mS_u16	48505
k_CMM388NTCEnableTimeout_mS_u16	36645
k_CMMNTCEnableTimeout_mS_u16	25299
k_CMMNodeAbsentDiag_Cnt_str.Threshold	62588
k_CMMNodeAbsentDiag_Cnt_str.PStep	35202

Name	Input Value
k_CMMNodeAbsentDiag_Cnt_str.NStep	37676
k_CMMNodeAbsentTimeout_mS_u16	10821
k_CONSANGLECPKMax_HwDeg_f32	395.222809
k_CONSANGLECPKMin_HwDeg_f32	-302.111908
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	13384
k_CONSANGLECPKSigValidThresh_Cnt_u16	20889
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	23853
k_CPKVehicleSpeedValidThresh_Cnt_u16	19567
k_CityParkInputInvalidThresh_Cnt_u16	61921
k_CityParkInputValidThresh_Cnt_u16	60870
k_ComputerRazGCTSigValidThresh_Cnt_u16	601
k_CptTemporelSigValidThresh_Cnt_u16	19958
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	51731
k_DMDFCTCPKSigValidThresh_Cnt_u16	47132
k_DMDFCTCPKValidCount_Cnt_u16	28118
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	35950
k_DMDRELAXECPKSigValidThresh_Cnt_u16	38702
k_DMDRelaxeConsistentThresh_Cnt_u16	18732
k_DateValidThresh_Cnt_u16	52737
k_DefaultVehSpd_Kph_f32	160.357101
k_DiagMuxOnAbsentTimeout_mS_u16	64030
k_EMNodeTimeout_mS_u16	15985
k_ESPNTCEnableTimeout_mS_u16	59989
k_ESPNodeAbsentDiag_Cnt_str.Threshold	32876
k_ESPNodeAbsentDiag_Cnt_str.PStep	16898
k_ESPNodeAbsentDiag_Cnt_str.NStep	13372
k_ESPNodeAbsentTimeout_mS_u16	16877
k_EtatMTSigInvalidThresh_Cnt_u16	24278
k_EtatMTSigValidThresh_Cnt_u16	16119
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	24204
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	63712
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	5083
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	13572
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	47841
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	23236
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	21964
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	35793
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	1815
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	48036
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	19920
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	46073
k_ISDATDIRASentDiag_Cnt_str.Threshold	14146
k_ISDATDIRASentDiag_Cnt_str.PStep	16332
k_ISDATDIRASentDiag_Cnt_str.NStep	21498
k_ISDATDIRASentTimeout_mS_u16	16911
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	55802
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	43618
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	23633
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	61027
k_ISDYNAASChkSumValidThresh_Cnt_u16	20036
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	25358
k_ISDYNAASMsgCountValidThresh_Cnt_u16	64422
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	41911
k_ISDYNAASMsgLenValidThresh_Cnt_u16	62851
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	54983
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	4329
k_ISDYNABRChkSumValidThresh_Cnt_u16	37746
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	38958
k_ISDYNABRMsgCountValidThresh_Cnt_u16	8231
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	55151
k_ISDYNABRMsgLenValidThresh_Cnt_u16	4532
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	24186
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	3090
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	39877
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	18178
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	43971
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	10620
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	7983
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	57543
k_ISDYNVOLChkSumValidThresh_Cnt_u16	28308
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	37277
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	6808
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	30191

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	15332
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	26799
k_IgnOnTimeout_mS_u16	36723
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	169.025604
k_PowerCutVehSpdLowThresh_Kph_f32	234.189697
k_PowerCutVehSpdLowTimeout_mS_u16	63311
k_VBattMaxAAS_Volt_f32	26.0228996
k_VBattMaxBSI_Volt_f32	0.950699985
k_VBattMaxCAV_Volt_f32	10.7021999
k_VBattMaxCMM388_Volt_f32	28.2294998
k_VBattMaxCMM_Volt_f32	31.7029991
k_VBattMaxESP_Volt_f32	2.06559992
k_VBattMinAAS_Volt_f32	24.0333004
k_VBattMinBSI_Volt_f32	2.06559992
k_VBattMinCAV_Volt_f32	1.02559996
k_VBattMinCMM388_Volt_f32	14.5636997
k_VBattMinCMM_Volt_f32	16.2667999
k_VBattMinESP_Volt_f32	31.7029991
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	59644
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	20537
k_VitesseVehicleBVRampValidThresh_Cnt_u16	39257
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	37831
k_VitesseVehicleBVSigValidThresh_Cnt_u16	2611
k_VitesseVehicleBVSpeedPassThresh_kph_f32	513.370789
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	58025
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	24410
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2943302912
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	66
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65535
target Rte Call Ap SrlComInput SystemTime GetSystemTime mS u32 CurrentT	810352896
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target Rte Inst Ap SrlComInput.SrlComInput Per1 ISDATBSI432MsgRxTime MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	163
target_SrlComInput_Per1_Batt_Volt_f32.value	1.40579998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2862902528
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	48
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.66439718
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3247758592
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1614249216
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	236
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3345620224
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1596767488
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2407488768
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	89
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3227647232
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	177
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1507106048
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	102
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	103
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	151
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	229

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	112
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4079074560
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	114
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	185
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	220
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1765006592
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3310779648
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2852723968
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	119
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	28699904
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1144
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0249582306
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	794422
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	214.191803
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	1600

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	810352896	810352896	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	42763	42763	✔
AASNodeAbsentTimer_mS_M_u32	810352896	810352896	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	1	1	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	810352896	810352896	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	737.649292	737.649292	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	810352896	810352896	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	810352896	810352896	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	810352896	810352896	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	810352896	810352896	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	810352896	810352896	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1478978816	1478978816	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	1217	1217	✔
CAVNodeAbsentTimer_mS_M_u32	810352896	810352896	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	810352896	810352896	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	810352896	810352896	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3227647232	3227647232	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	47728	47728	✔
CONSANGLECPK_HwDeg_M_f32	101.905998	101.905998 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	810352896	810352896	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	810352896	810352896	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	810352896	810352896	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	810352896	810352896	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	810352896	810352896	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	810352896	810352896	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	810352896	810352896	✔
ESPNTCEnableTimer_mS_M_u32	810352896	810352896	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	810352896	810352896	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	89	89	✔
EffacDefaultDiagTimer_mS_M_u32[1]	789	789	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	810352896	810352896	✔
ElecIntTimer_mS_M_u32[1]	787881	787881	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	810352896	810352896	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	810352896	810352896	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	810352896	810352896	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	810352896	810352896	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	810352896	810352896	✔
ISDATDIRASentFltAcc_Cnt_M_u16	14146	14146	✔
ISDATDIRASentTimer_mS_M_u32	810352896	810352896	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2852723968	2852723968	✔
IgnOnTimer_mS_M_u32	2877480192	2877480192	✔
IgnTimeOff_Sec_M_u32	2992063655	2992063655	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	20	20	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3247758592	3247758592	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	246	246	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1614249216	1614249216	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	236	236	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3345620224	3345620224	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1596767488	1596767488	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1843076352	1843076352	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	89	89	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3227647232	3227647232	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	177	177	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1507106048	1507106048	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	112	112	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4079074560	4079074560	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	133	133	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1765006592	1765006592	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	68	68	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3310779648	3310779648	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	216	216	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2852723968	2852723968	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	28699904	28699904	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	217.5159	217.5159	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	36.7935982	36.7935982	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	275.118195	275.118195	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	737.649292	737.649292	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	47728	47728	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2992063655	2992063655	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	101.905998	101.905998 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	160.357101	160.357101	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	5	ValidityNTCProcessing	5	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.162 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3943455744
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	422
AASNodeAbsentTimer_mS_M_u32	3621571584
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	32967
ANGLEVOLANTSigValidCount_Cnt_M_u16	50781
APARequest_Cnt_M_lgc	1

Name	Input Value
AngleVolantInvalidCount_Cnt_M_u16	63979
AngleVolantMsgTimer_mS_M_u32	3943455744
AngleVolantValidCount_Cnt_M_u16	19257
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	692.465881
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2156039168
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2323975168
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3787455488
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	4029463552
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	10118
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3978066944
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	31382
CAVNodeAbsentTimer_mS_M_u32	2739170304
CDD_SrlComVehSpd_Kph_G_f32	80.5895004
CMM388NTCEnableTimer_mS_M_u32	3909790720
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	239758336
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	8196
CMMNodeAbsentTimer_mS_M_u32	2678504448
CONSANGLECPKSigInvalidCount_Cnt_M_u16	28953
CONSANGLECPKSigValidCount_Cnt_M_u16	1151
CONSANGLECPK_Cnt_M_u16	44418
CONSANGLECPK_HwDeg_M_f32	533.632202
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	44418
CPKVehicleSpeedMsgTimer_mS_M_u32	1858296832
CPKVehicleSpeedValidCount_Cnt_M_u16	5515
CityParkInputConsistentCount_Cnt_M_u16	2621
CityParkInputInvalidCount_Cnt_M_u16	53773
CityParkInputMsgTimer_mS_M_u32	3247758592
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1474350080
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	1706
ComputerRazGCTSigInvalidTimer_mS_M_u32	1611197440
ComputerRazGCTSigValidCount_Cnt_M_u16	7418
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	53001
DMDFCTCPKSigValidCount_Cnt_M_u16	52295
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	61257
DMDRELAXECPKSigValidCount_Cnt_M_u16	29279
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	59998
DateInvalidTimer_mS_M_u32	2323975168
DiagMuxOnAbsentTimer_mS_M_u32	4259060736
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4029463552
ESPNTCEnableTimer_mS_M_u32	4192586752
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	24566
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	56
EffacDefaultDiagTimer_mS_M_u32[1]	456
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	55656
ElecIntTimer_mS_M_u32[1]	87790
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2029943808
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	3975
EtatMTSigValidCount_Cnt_M_u16	42857
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	58779
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	13953

Name	Input Value
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	16717
ISDAT4V2BSI552MsgTimer_mS_M_u32	3668622336
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	42592
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	45514
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	42857
ISDATBSI3F2MsgTimer_mS_M_u32	1633295360
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	37504
ISDATBSI412MsgLenValidCount_Cnt_M_u16	8602
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	3975
ISDATBSI412MsgTimer_mS_M_u32	76176384
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	22024
ISDATBSI432MsgLenValidCount_Cnt_M_u16	53498
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	25791
ISDATDIRASentFltAcc_Cnt_M_u16	59987
ISDATDIRASentTimer_mS_M_u32	1858296832
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	21376
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	19257
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	56136
ISDYN2CMMMsgTimer_mS_M_u32	1507838976
ISDYNAASChkSumInvalidCount_Cnt_M_u16	56360
ISDYNAASChkSumValidCount_Cnt_M_u16	61406
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	3448
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	39385
ISDYNAASMsgLenValidCount_Cnt_M_u16	48839
ISDYNAASMsgTimeValidCount_Cnt_M_u16	56360
ISDYNAASMsgTimer_mS_M_u32	319204352
ISDYNABRChkSumInvalidCount_Cnt_M_u16	4199
ISDYNABRChkSumValidCount_Cnt_M_u16	20357
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	42215
ISDYNABRMsgCountValidCount_Cnt_M_u16	6621
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	5336
ISDYNABRMsgLenValidCount_Cnt_M_u16	18814
ISDYNABRMsgTimeValidCount_Cnt_M_u16	44418
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	764
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1413
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	42857
ISDYNCMM208MsgTimer_mS_M_u32	2038402048
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2907
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1519
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	25527
ISDYNCMM388MsgTimer_mS_M_u32	1053174784
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	65535
ISDYNVOLChkSumValidCount_Cnt_M_u16	8829
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	50567
ISDYNVOLMsgCountValidCount_Cnt_M_u16	17733
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	56887
ISDYNVOLMsgLenValidCount_Cnt_M_u16	893
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	8196
ISDYNVOLMsgTimer_mS_M_u32	2516904960
IgnOnTimer_mS_M_u32	3972672512
IgnTimeOff_Sec_M_u32	1444843533
ManVehSpd_Kph_M_f32	445.578888
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	147
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	91
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3342867456
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	217
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1549728768
PrevISDATBSI412MsgDLCError_Cnt_M_u08	35
PrevISDATBSI412MsgRxTime_MSec_M_u32	170748928
PrevISDATBSI432MsgDLCError_Cnt_M_u08	214
PrevISDATBSI432MsgRxTime_MSec_M_u32	2765736960
PrevISDATDIRAMsgTxTime_MSec_M_u32	1455516672

Name	Input Value
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	31
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2502835200
PrevISDYNAASMsgDLCError_Cnt_M_u08	161
PrevISDYNAASMsgRxTime_MSec_M_u32	3288525824
PrevISDYNABRMsgDLCError_Cnt_M_u08	122
PrevISDYNABRMsgRxTime_MSec_M_u32	1807887360
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	84
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4135578624
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	84
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4074556416
PrevISDYNVOLMsgDLCError_Cnt_M_u08	190
PrevISDYNVOLMsgRxTime_MSec_M_u32	1698851840
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1225284608
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	373.812408
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	18007
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	28101
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	42520
VitesseVehicleBVRampValidCount_Cnt_M_u16	52294
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	28168
VitesseVehicleBVSigValidCount_Cnt_M_u16	53854
VitesseVehicleBV_Kph_M_f32	574.990295
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	25527
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	10885
VitesseVehiculeRoues_Kph_M_f32	135.628006
k_AASNTCEnableTimeout_mS_u16	27001
k_AASNodeAbsentDiag_Cnt_str.Threshold	39511
k_AASNodeAbsentDiag_Cnt_str.PStep	24053
k_AASNodeAbsentDiag_Cnt_str.NStep	47015
k_AASNodeAbsentTimeout_mS_u16	14708
k_AASNodeTimeout_mS_u16	2245
k_ABSNodeTimeout_mS_u16	63942
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	8067
k_ANGLEVOLANTSigValidThresh_Cnt_u16	20661
k_AngleVolantInvalidThresh_Cnt_u16	380
k_AngleVolantValidThresh_Cnt_u16	53773
k_BSI552MsgTimeout_mS_u16	27148
k_BSINTCEnableTimeout_mS_u16	50432
k_BSINodeAbsentDiag_Cnt_str.Threshold	3626
k_BSINodeAbsentDiag_Cnt_str.PStep	3486
k_BSINodeAbsentDiag_Cnt_str.NStep	21948
k_BSINodeAbsentTimeout_mS_u16	27363
k_BSINodeTimeout_mS_u16	25791
k_BattOvHi_Volt_f32	15.4245996
k_BattOvLo_Volt_f32	11.2203999
k_BattUvHi_Volt_f32	10.7711
k_BattUvLo_Volt_f32	14.5846004
k_CAVNTCEnableTimeout_mS_u16	64899
k_CAVNodeAbsentDiag_Cnt_str.Threshold	22004
k_CAVNodeAbsentDiag_Cnt_str.PStep	51543
k_CAVNodeAbsentDiag_Cnt_str.NStep	55757
k_CAVNodeAbsentTimeout_mS_u16	64020
k_CAVNodeTimeout_mS_u16	21269
k_CMM388MsgTimeout_mS_u16	56486
k_CMM388NTCEnableTimeout_mS_u16	6050
k_CMMNTCEnableTimeout_mS_u16	20824
k_CMMNodeAbsentDiag_Cnt_str.Threshold	25861
k_CMMNodeAbsentDiag_Cnt_str.PStep	27059

Name	Input Value
k_CMMNodeAbsentDiag_Cnt_str.NStep	41077
k_CMMNodeAbsentTimeout_mS_u16	60289
k_CONSANGLECPKMax_HwDeg_f32	477.23111
k_CONSANGLECPKMin_HwDeg_f32	-164.078293
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	48823
k_CONSANGLECPKSigValidThresh_Cnt_u16	50565
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	20683
k_CPKVehicleSpeedValidThresh_Cnt_u16	21891
k_CityParkInputInvalidThresh_Cnt_u16	55533
k_CityParkInputValidThresh_Cnt_u16	2621
k_ComputerRazGCTSigValidThresh_Cnt_u16	2758
k_CptTemporelSigValidThresh_Cnt_u16	46768
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	61400
k_DMDFCTCPKSigValidThresh_Cnt_u16	25726
k_DMDFCTCPKValidCount_Cnt_u16	8590
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	56136
k_DMDRELAXECPKSigValidThresh_Cnt_u16	55750
k_DMDRelaxeConsistentThresh_Cnt_u16	15308
k_DateValidThresh_Cnt_u16	16717
k_DefaultVehSpd_Kph_f32	228.501907
k_DiagMuxOnAbsentTimeout_mS_u16	9848
k_EMNodeTimeout_mS_u16	35518
k_ESPNTCEnableTimeout_mS_u16	28306
k_ESPNodeAbsentDiag_Cnt_str.Threshold	12341
k_ESPNodeAbsentDiag_Cnt_str.PStep	61236
k_ESPNodeAbsentDiag_Cnt_str.NStep	44102
k_ESPNodeAbsentTimeout_mS_u16	17545
k_EtatMTSigInvalidThresh_Cnt_u16	42510
k_EtatMTSigValidThresh_Cnt_u16	42092
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	34990
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	10352
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	11262
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	57029
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	56303
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	48772
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	62445
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	32927
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	52236
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	31206
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	37407
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	6116
k_ISDATDIRASentDiag_Cnt_str.Threshold	625
k_ISDATDIRASentDiag_Cnt_str.PStep	48276
k_ISDATDIRASentDiag_Cnt_str.NStep	58314
k_ISDATDIRASentTimeout_mS_u16	8291
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	59873
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	63979
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	2206
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	27495
k_ISDYNAASChkSumValidThresh_Cnt_u16	60037
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	32743
k_ISDYNAASMsgCountValidThresh_Cnt_u16	13533
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	39787
k_ISDYNAASMsgLenValidThresh_Cnt_u16	24521
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	63421
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	62294
k_ISDYNABRChkSumValidThresh_Cnt_u16	43644
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	646
k_ISDYNABRMsgCountValidThresh_Cnt_u16	26972
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	47876
k_ISDYNABRMsgLenValidThresh_Cnt_u16	15094
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	47715
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	15707
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16257
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	10060
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	23495
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	57693
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	26373
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	63611
k_ISDYNVOLChkSumValidThresh_Cnt_u16	40405
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	40763
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	54665
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	12419

Name	Input Value
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	52581
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	43331
k_IgnOnTimeout_mS_u16	40055
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	222.996506
k_PowerCutVehSpdLowThresh_Kph_f32	67.504303
k_PowerCutVehSpdLowTimeout_mS_u16	13029
k_VBattMaxAAS_Volt_f32	3.34500003
k_VBattMaxBSI_Volt_f32	1.2823
k_VBattMaxCAV_Volt_f32	29.8563004
k_VBattMaxCMM388_Volt_f32	23.0545006
k_VBattMaxCMM_Volt_f32	4.99620008
k_VBattMaxESP_Volt_f32	28.3917999
k_VBattMinAAS_Volt_f32	21.5277996
k_VBattMinBSI_Volt_f32	28.3917999
k_VBattMinCAV_Volt_f32	26.6287994
k_VBattMinCMM388_Volt_f32	32
k_VBattMinCMM_Volt_f32	22.2686005
k_VBattMinESP_Volt_f32	4.99620008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	17627
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	7653
k_VitesseVehicleBVRampValidThresh_Cnt_u16	8327
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	15741
k_VitesseVehicleBVSigValidThresh_Cnt_u16	43254
k_VitesseVehicleBVSpeedPassThresh_kph_f32	125.281898
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	54678
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	15940
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2323975168
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	212
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	6190
target Rte Call Ap SrlComInput SystemTime GetSystemTime mS u32 CurrentT	2751184896
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target Rte Inst Ap SrlComInput.SrlComInput Per1 ISDATBSI432MsgRxTime MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	84
target_SrlComInput_Per1_Batt_Volt_f32.value	28.3540993
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	698711040
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	72
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.55881089
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1922313216
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3911994368
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1175743488
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	161
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1363971072
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3537153024
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	214
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2460797952
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1490349056
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	135
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	167
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	218
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	220
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	230
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	248

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	128
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2842528768
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	174
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	186
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	245
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3082234880
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4124003328
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3661065216
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	11
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	28
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	30
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	68
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	172
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	187
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1248918528
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	304
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0672205836
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1010421
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	245.747696
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	34513

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	39511	39511	✔
AASNodeAbsentTimer_mS_M_u32	2751184896	2751184896	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	1	1	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	63979	63979	✔
AngleVolantMsgTimer_mS_M_u32	2751184896	2751184896	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	692.465881	692.465881	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2751184896	2751184896	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3978066944	3978066944	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	22004	22004	✔
CAVNodeAbsentTimer_mS_M_u32	2751184896	2751184896	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2460797952	2460797952	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	44418	44418	✔
CONSANGLECPK_HwDeg_M_f32	533.632202	533.632202 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	44418	44418	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1858296832	1858296832	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	5515	5515	✔
CityParkInputConsistentCount_Cnt_M_u16	2621	2621	✔
CityParkInputInvalidCount_Cnt_M_u16	53775	53775	✔
CityParkInputMsgTimer_mS_M_u32	2751184896	2751184896	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2751184896	2751184896	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2751184896	2751184896	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2751184896	2751184896	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2751184896	2751184896	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2751184896	2751184896	✔
ESPNTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2751184896	2751184896	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	56	56	✔
EffacDefaultDiagTimer_mS_M_u32[1]	456	456	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2751184896	2751184896	✔
ElecIntTimer_mS_M_u32[1]	87790	87790	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2751184896	2751184896	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDATDIRASentFltAcc_Cnt_M_u16	625	625	✔
ISDATDIRASentTimer_mS_M_u32	2751184896	2751184896	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	65535	65535	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	50567	50567	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3661065216	3661065216	✔
IgnOnTimer_mS_M_u32	3972672512	3972672512	✔
IgnTimeOff_Sec_M_u32	1444843533	1444843533	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	39	39	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1922313216	1922313216	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	181	181	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3911994368	3911994368	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1175743488	1175743488	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	161	161	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1363971072	1363971072	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1455516672	1455516672	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	214	214	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2460797952	2460797952	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	64	64	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1490349056	1490349056	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	128	128	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2842528768	2842528768	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	16	16	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3082234880	3082234880	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4124003328	4124003328	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	190	190	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3661065216	3661065216	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1248918528	1248918528	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	373.812408	373.812408	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VehTimeValid_Cnt_M_Igc	0	0	✔
VehicleSpeedValid_Cnt_M_Igc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	574.990295	574.990295	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	135.628006	135.628006	✔
target_SrlComInput_Per1_APAAuthn_Cnt_Igc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_Igc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	692.465881	692.465881	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_Igc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_Igc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_Igc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	44418	44418	✔
target_SrlComInput_Per1_CPKOK_Cnt_Igc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_Igc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_Igc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1444843533	1444843533	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	533.632202	533.632202 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_Igc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_Igc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	228.501907	228.501907	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_Igc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_Igc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_Igc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0152	0x0152	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔
NTC	0x0153	0x0153	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	3	ValidityNTCProcessing	3	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.163 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	921284352
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	32026
AASNodeAbsentTimer_mS_M_u32	2117623552
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	8632
ANGLEVOLANTSigValidCount_Cnt_M_u16	21686
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	59467
AngleVolantMsgTimer_mS_M_u32	921284352
AngleVolantValidCount_Cnt_M_u16	21728
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	471.270996
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1262952192
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1463787264
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	693030656
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2701692672
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	59771
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	423186176
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	55499
CAVNodeAbsentTimer_mS_M_u32	3263266560
CDD_SrlComVehSpd_Kph_G_f32	61.551899
CMM388NTCEnableTimer_mS_M_u32	3660496640
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	426737408
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	40256
CMMNodeAbsentTimer_mS_M_u32	4204433152
CONSANGLECPKSigInvalidCount_Cnt_M_u16	51139
CONSANGLECPKSigValidCount_Cnt_M_u16	20817
CONSANGLECPK_Cnt_M_u16	8776
CONSANGLECPK_HwDeg_M_f32	189.592804
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	8776
CPKVehicleSpeedMsgTimer_mS_M_u32	1204072192
CPKVehicleSpeedValidCount_Cnt_M_u16	54484
CityParkInputConsistentCount_Cnt_M_u16	10196
CityParkInputInvalidCount_Cnt_M_u16	7527
CityParkInputMsgTimer_mS_M_u32	1922313216
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	237788928
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	32270
ComputerRazGCTSigInvalidTimer_mS_M_u32	1043595008
ComputerRazGCTSigValidCount_Cnt_M_u16	9117
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	5747
DMDFCTCPKSigValidCount_Cnt_M_u16	49785
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	24114
DMDRELAXECPKSigValidCount_Cnt_M_u16	55472
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	45044
DateInvalidTimer_mS_M_u32	1463787264
DiagMuxOnAbsentTimer_mS_M_u32	3984224000
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2701692672
ESPNTCEnableTimer_mS_M_u32	2082299648
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	20778
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	2323

Name	Input Value
ElecIntTimer_mS_M_u32[1]	454648
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2106806016
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	60342
EtatMTSigValidCount_Cnt_M_u16	22481
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	62013
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	17227
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	64359
ISDAT4V2BSI552MsgTimer_mS_M_u32	1502514944
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	32941
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	45616
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	22481
ISDATBSI3F2MsgTimer_mS_M_u32	989884160
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	36173
ISDATBSI412MsgLenValidCount_Cnt_M_u16	62399
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	60342
ISDATBSI412MsgTimer_mS_M_u32	1651486464
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	2868
ISDATBSI432MsgLenValidCount_Cnt_M_u16	3614
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	65104
ISDATDIRASentFltAcc_Cnt_M_u16	48532
ISDATDIRASentTimer_mS_M_u32	1204072192
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	43086
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	21728
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	44470
ISDYN2CMMMsgTimer_mS_M_u32	3291438848
ISDYNAASChkSumInvalidCount_Cnt_M_u16	30100
ISDYNAASChkSumValidCount_Cnt_M_u16	48690
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	51747
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	18178
ISDYNAASMsgLenValidCount_Cnt_M_u16	15352
ISDYNAASMsgTimeValidCount_Cnt_M_u16	30100
ISDYNAASMsgTimer_mS_M_u32	1278918400
ISDYNABRChkSumInvalidCount_Cnt_M_u16	60503
ISDYNABRChkSumValidCount_Cnt_M_u16	21181
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	55127
ISDYNABRMsgCountValidCount_Cnt_M_u16	64565
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	39046
ISDYNABRMsgLenValidCount_Cnt_M_u16	15956
ISDYNABRMsgTimeValidCount_Cnt_M_u16	8776
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	765
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1415
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	22481
ISDYNCMM208MsgTimer_mS_M_u32	2488278784
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2911
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1521
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	33638
ISDYNCMM388MsgTimer_mS_M_u32	654065408
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	43481
ISDYNVOLChkSumValidCount_Cnt_M_u16	28503
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	43769
ISDYNVOLMsgCountValidCount_Cnt_M_u16	53119
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	6759
ISDYNVOLMsgLenValidCount_Cnt_M_u16	28246
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	40256
ISDYNVOLMsgTimer_mS_M_u32	2353004288
IgnOnTimer_mS_M_u32	753942272
IgnTimeOff_Sec_M_u32	1843608807
ManVehSpd_Kph_M_f32	437.5802
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	85
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	14

Name	Input Value
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	126
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	558788352
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	178
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4117876480
PrevISDATBSI412MsgDLCError_Cnt_M_u08	173
PrevISDATBSI412MsgRxTime_MSec_M_u32	1908834048
PrevISDATBSI432MsgDLCError_Cnt_M_u08	173
PrevISDATBSI432MsgRxTime_MSec_M_u32	1262575360
PrevISDATDIRAMsgTxTime_MSec_M_u32	3691675392
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	237
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2550402816
PrevISDYNAASMsgDLCError_Cnt_M_u08	168
PrevISDYNAASMsgRxTime_MSec_M_u32	2051407616
PrevISDYNABRMsgDLCError_Cnt_M_u08	235
PrevISDYNABRMsgRxTime_MSec_M_u32	2416459520
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	254
PrevISDYNCMM208MsgRxTime_MSec_M_u32	382664448
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	0
PrevISDYNCMM388MsgRxTime_MSec_M_u32	758669056
PrevISDYNVOLMsgDLCError_Cnt_M_u08	175
PrevISDYNVOLMsgRxTime_MSec_M_u32	4102520576
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	217427712
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	233.052902
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	47496
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	42750
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	56901
VitesseVehicleBVRampValidCount_Cnt_M_u16	53115
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	40437
VitesseVehicleBVSigValidCount_Cnt_M_u16	29875
VitesseVehicleBV_Kph_M_f32	652.486694
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	33638
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	4796
VitesseVehiculeRoues_Kph_M_f32	487.398987
k_AASNTCEnableTimeout_mS_u16	35427
k_AASNodeAbsentDiag_Cnt_str.Threshold	5734
k_AASNodeAbsentDiag_Cnt_str.PStep	31939
k_AASNodeAbsentDiag_Cnt_str.NStep	31892
k_AASNodeAbsentTimeout_mS_u16	13871
k_AASNodeTimeout_mS_u16	54782
k_ABSNodeTimeout_mS_u16	51772
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	23235
k_ANGLEVOLANTSigValidThresh_Cnt_u16	15085
k_AngleVolantInvalidThresh_Cnt_u16	1176
k_AngleVolantValidThresh_Cnt_u16	7527
k_BSI552MsgTimeout_mS_u16	12327
k_BSINTCEnableTimeout_mS_u16	40524
k_BSINodeAbsentDiag_Cnt_str.Threshold	2835
k_BSINodeAbsentDiag_Cnt_str.PStep	2744
k_BSINodeAbsentDiag_Cnt_str.NStep	16054
k_BSINodeAbsentTimeout_mS_u16	30051
k_BSINodeTimeout_mS_u16	65104
k_BattOvHi_Volt_f32	7.72020006
k_BattOvLo_Volt_f32	4.68599987
k_BattUvHi_Volt_f32	22.7600002
k_BattUvLo_Volt_f32	5.70179987
k_CAVNTCEnableTimeout_mS_u16	62213
k_CAVNodeAbsentDiag_Cnt_str.Threshold	60936

Name	Input Value
k_CAVNodeAbsentDiag_Cnt_str.PStep	27145
k_CAVNodeAbsentDiag_Cnt_str.NStep	20094
k_CAVNodeAbsentTimeout_mS_u16	53841
k_CAVNodeTimeout_mS_u16	4559
k_CMM388MsgTimeout_mS_u16	60442
k_CMM388NTCEnableTimeout_mS_u16	11046
k_CMMNTCEnableTimeout_mS_u16	24517
k_CMMNodeAbsentDiag_Cnt_str.Threshold	26470
k_CMMNodeAbsentDiag_Cnt_str.PStep	38483
k_CMMNodeAbsentDiag_Cnt_str.NStep	6835
k_CMMNodeAbsentTimeout_mS_u16	49096
k_CONSANGLECPKMax_HwDeg_f32	417.256104
k_CONSANGLECPKMin_HwDeg_f32	-376.875397
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	29286
k_CONSANGLECPKSigValidThresh_Cnt_u16	16828
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	38380
k_CPKVehicleSpeedValidThresh_Cnt_u16	4164
k_CityParkInputInvalidThresh_Cnt_u16	10949
k_CityParkInputValidThresh_Cnt_u16	10196
k_ComputerRazGCTSigValidThresh_Cnt_u16	27515
k_CptTemporelSigValidThresh_Cnt_u16	47998
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	1926
k_DMDFCTCPKSigValidThresh_Cnt_u16	60756
k_DMDFCTCPKValidCount_Cnt_u16	7011
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	44470
k_DMDRELAXECPKSigValidThresh_Cnt_u16	22012
k_DMDRelaxeConsistentThresh_Cnt_u16	51178
k_DateValidThresh_Cnt_u16	64359
k_DefaultVehSpd_Kph_f32	195.052002
k_DiagMuxOnAbsentTimeout_mS_u16	3942
k_EMNodeTimeout_mS_u16	20180
k_ESPNTCEnableTimeout_mS_u16	60631
k_ESPNodeAbsentDiag_Cnt_str.Threshold	20433
k_ESPNodeAbsentDiag_Cnt_str.PStep	13965
k_ESPNodeAbsentDiag_Cnt_str.NStep	57022
k_ESPNodeAbsentTimeout_mS_u16	54448
k_EtatMTSigInvalidThresh_Cnt_u16	34658
k_EtatMTSigValidThresh_Cnt_u16	45064
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	14915
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	3773
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	1681
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	43902
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	1985
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	6465
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	1413
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	54063
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	47400
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	19740
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	38958
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	56864
k_ISDATDIRASentDiag_Cnt_str.Threshold	64711
k_ISDATDIRASentDiag_Cnt_str.PStep	35441
k_ISDATDIRASentDiag_Cnt_str.NStep	35487
k_ISDATDIRASentTimeout_mS_u16	44131
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	39977
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	59467
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	20147
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	56151
k_ISDYNAASChkSumValidThresh_Cnt_u16	33213
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	18007
k_ISDYNAASMsgCountValidThresh_Cnt_u16	43829
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	23371
k_ISDYNAASMsgLenValidThresh_Cnt_u16	57586
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	26069
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	29964
k_ISDYNABRChkSumValidThresh_Cnt_u16	37722
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	22651
k_ISDYNABRMsgCountValidThresh_Cnt_u16	10169
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	52288
k_ISDYNABRMsgLenValidThresh_Cnt_u16	49194
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	4260
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	58492
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	51786

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	22121
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	37048
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	950
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	15999
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	1884
k_ISDYNVOLChkSumValidThresh_Cnt_u16	11022
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	59227
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	53425
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	30914
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	54749
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	7045
k_IgnOnTimeout_mS_u16	2920
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	150.0681
k_PowerCutVehSpdLowThresh_Kph_f32	240.544693
k_PowerCutVehSpdLowTimeout_mS_u16	56863
k_VBattMaxAAS_Volt_f32	1.63839996
k_VBattMaxBSI_Volt_f32	8.6644001
k_VBattMaxCAV_Volt_f32	9.35140038
k_VBattMaxCMM388_Volt_f32	28.5226994
k_VBattMaxCMM_Volt_f32	6.61049986
k_VBattMaxESP_Volt_f32	0.97359997
k_VBattMinAAS_Volt_f32	9.44839954
k_VBattMinBSI_Volt_f32	0.97359997
k_VBattMinCAV_Volt_f32	3.0079
k_VBattMinCMM388_Volt_f32	26.1229
k_VBattMinCMM_Volt_f32	8.90170002
k_VBattMinESP_Volt_f32	6.61049986
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	62267
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	15325
k_VitesseVehicleBVRampValidThresh_Cnt_u16	39417
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	7767
k_VitesseVehicleBVSigValidThresh_Cnt_u16	28585
k_VitesseVehicleBVSpeedPassThresh_kph_f32	374.221802
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	51147
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	61825
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1463787264
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	229
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	0
target_SrlComInput_Per1_Batt_Volt_f32.value	6.52299976
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3349040896
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	87
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.556488514
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	25
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1133657856
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	214
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3897155328
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	437354240
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2162761472
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3302014720
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	150
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2378718976

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2211446528
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	114
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	115
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	140
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	188
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	226
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1015422720
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	71
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	122
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	236
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	238
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3223928576
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	241229568
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	175
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2846392064
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	13
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	84
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	108
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	157
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	228
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4080783104
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3057
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.363339663
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	22338
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	119.0644
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	24602

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	1	1	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	59467	59467	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	471.270996	471.270996	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	43717	43717	✔
BSINodeAbsentTimer_mS_M_u32	2162761472	2162761472	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	423186176	423186176	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CAVNodeAbsentFltAcc_Cnt_M_u16	35405	35405	✔
CAVNodeAbsentTimer_mS_M_u32	2846392064	2846392064	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	33421	33421	✔
CMMNodeAbsentTimer_mS_M_u32	2378718976	2378718976	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	8776	8776	✔
CONSANGLECPK_HwDeg_M_f32	189.592804	189.592804 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	8776	8776	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1204072192	1204072192	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	54484	54484	✔
CityParkInputConsistentCount_Cnt_M_u16	10196	10196	✔
CityParkInputInvalidCount_Cnt_M_u16	7529	7529	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	8	8	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2323	2323	✔
ElecIntTimer_mS_M_u32[1]	454648	454648	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	13045	13045	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	43481	43481	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	43770	43770	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2846392064	2846392064	✔
IgnOnTimer_mS_M_u32	753942272	753942272	✔
IgnTimeOff_Sec_M_u32	1843608807	1843608807	✔
Msg348Valid_Cnt_M_Igc	0	0	✔
Msg432Valid_Cnt_M_Igc	0	0	✔
Msg552Valid_Cnt_M_Igc	0	0	✔
NetOn_Cnt_M_Igc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	25	25	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1133657856	1133657856	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	214	214	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3897155328	3897155328	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	205	205	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	437354240	437354240	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	164	164	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2162761472	2162761472	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3302014720	3302014720	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	150	150	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2378718976	2378718976	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	0	0	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2211446528	2211446528	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1015422720	1015422720	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	169	169	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3223928576	3223928576	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	48	48	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	241229568	241229568	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	175	175	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2846392064	2846392064	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4080783104	4080783104	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	233.052902	233.052902	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	652.486694	652.486694	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	487.398987	487.398987	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	471.270996	471.270996	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	8776	8776	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1843608807	1843608807	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	189.592804	189.592804 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	195.052002	195.052002	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0151	0x0151	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0152	0x0152	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	4	ValidityNTCProcessing	4	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.164 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	610121216
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	46028
AASNodeAbsentTimer_mS_M_u32	624010752
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	24560
ANGLEVOLANTSigValidCount_Cnt_M_u16	48054
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	30265
AngleVolantMsgTimer_mS_M_u32	610121216
AngleVolantValidCount_Cnt_M_u16	3832
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	80.8309708
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1761961472
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3340494336
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3383645696
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2038502912
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	54439
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3287209472
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	19768
CAVNodeAbsentTimer_mS_M_u32	1691764224
CDD_SrlComVehSpd_Kph_G_f32	16.2320004
CMM388NTCEnableTimer_mS_M_u32	1657701888
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2550941184
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	57752
CMMNodeAbsentTimer_mS_M_u32	885724672
CONSANGLECPKSigInvalidCount_Cnt_M_u16	2256
CONSANGLECPKSigValidCount_Cnt_M_u16	41189
CONSANGLECPK_Cnt_M_u16	51712
CONSANGLECPK_HwDeg_M_f32	-168.268799
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	51712
CPKVehicleSpeedMsgTimer_mS_M_u32	499955200
CPKVehicleSpeedValidCount_Cnt_M_u16	37478
CityParkInputConsistentCount_Cnt_M_u16	26140
CityParkInputInvalidCount_Cnt_M_u16	40549
CityParkInputMsgTimer_mS_M_u32	1133657856
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1163240960
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	33008
ComputerRazGCTSigInvalidTimer_mS_M_u32	3686712832
ComputerRazGCTSigValidCount_Cnt_M_u16	54977
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	58177
DMDFCTCPKSigValidCount_Cnt_M_u16	62447
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	4738
DMDRELAXECPKSigValidCount_Cnt_M_u16	38856
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	21565
DateInvalidTimer_mS_M_u32	3340494336
DiagMuxOnAbsentTimer_mS_M_u32	866874880
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2038502912
ESPNTCEnableTimer_mS_M_u32	4286752256
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	27289
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	2323

Name	Input Value
ElecIntTimer_mS_M_u32[1]	1713429248
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2128664064
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	40757
EtatMTSigValidCount_Cnt_M_u16	49063
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	61794
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	13047
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	33061
ISDAT4V2BSI552MsgTimer_mS_M_u32	3891205632
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	54225
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	17418
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	49063
ISDATBSI3F2MsgTimer_mS_M_u32	3810096640
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	15091
ISDATBSI412MsgLenValidCount_Cnt_M_u16	52316
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	40757
ISDATBSI412MsgTimer_mS_M_u32	969651712
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	26556
ISDATBSI432MsgLenValidCount_Cnt_M_u16	957
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	12457
ISDATDIRASentFltAcc_Cnt_M_u16	733
ISDATDIRASentTimer_mS_M_u32	499955200
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	53230
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	3832
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	59768
ISDYN2CMMMsgTimer_mS_M_u32	4014777856
ISDYNAASChkSumInvalidCount_Cnt_M_u16	12894
ISDYNAASChkSumValidCount_Cnt_M_u16	52547
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	31535
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	40595
ISDYNAASMsgLenValidCount_Cnt_M_u16	38001
ISDYNAASMsgTimeValidCount_Cnt_M_u16	12894
ISDYNAASMsgTimer_mS_M_u32	1017808384
ISDYNABRChkSumInvalidCount_Cnt_M_u16	37780
ISDYNABRChkSumValidCount_Cnt_M_u16	62753
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	55573
ISDYNABRMsgCountValidCount_Cnt_M_u16	57146
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	25223
ISDYNABRMsgLenValidCount_Cnt_M_u16	42460
ISDYNABRMsgTimeValidCount_Cnt_M_u16	51712
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	856
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1489
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	49063
ISDYNCMM208MsgTimer_mS_M_u32	4058670592
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2911
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1521
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	7014
ISDYNCMM388MsgTimer_mS_M_u32	2456159744
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	61502
ISDYNVOLChkSumValidCount_Cnt_M_u16	57043
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	48559
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	17122
ISDYNVOLMsgLenValidCount_Cnt_M_u16	64472
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	57752
ISDYNVOLMsgTimer_mS_M_u32	563791360
IgnOnTimer_mS_M_u32	1351222784
IgnTimeOff_Sec_M_u32	436383263
ManVehSpd_Kph_M_f32	382.217804
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	85
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	9

Name	Input Value
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	124
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3895424512
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	220
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2974111232
PrevISDATBSI412MsgDLCError_Cnt_M_u08	95
PrevISDATBSI412MsgRxTime_MSec_M_u32	2869380608
PrevISDATBSI432MsgDLCError_Cnt_M_u08	17
PrevISDATBSI432MsgRxTime_MSec_M_u32	571909632
PrevISDATDIRAMsgTxTime_MSec_M_u32	2084259328
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	4
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3800995328
PrevISDYNAASMsgDLCError_Cnt_M_u08	18
PrevISDYNAASMsgRxTime_MSec_M_u32	4018718208
PrevISDYNABRMsgDLCError_Cnt_M_u08	222
PrevISDYNABRMsgRxTime_MSec_M_u32	2269251072
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	194
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2112734720
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	180
PrevISDYNCMM388MsgRxTime_MSec_M_u32	405906944
PrevISDYNVOLMsgDLCError_Cnt_M_u08	221
PrevISDYNVOLMsgRxTime_MSec_M_u32	1724139008
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3526997504
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	286.260193
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57089
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	60255
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	42186
VitesseVehicleBVRampValidCount_Cnt_M_u16	42472
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	7993
VitesseVehicleBVSigValidCount_Cnt_M_u16	36799
VitesseVehicleBV_Kph_M_f32	553.436584
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	7014
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	49699
VitesseVehiculeRoues_Kph_M_f32	247.503494
k_AASNTCEnableTimeout_mS_u16	48559
k_AASNodeAbsentDiag_Cnt_str.Threshold	5734
k_AASNodeAbsentDiag_Cnt_str.PStep	31939
k_AASNodeAbsentDiag_Cnt_str.NStep	31892
k_AASNodeAbsentTimeout_mS_u16	26379
k_AASNodeTimeout_mS_u16	24159
k_ABSNodeTimeout_mS_u16	11238
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	29967
k_ANGLEVOLANTSigValidThresh_Cnt_u16	31056
k_AngleVolantInvalidThresh_Cnt_u16	34895
k_AngleVolantValidThresh_Cnt_u16	40549
k_BSI552MsgTimeout_mS_u16	54754
k_BSINTCEnableTimeout_mS_u16	3700
k_BSINodeAbsentDiag_Cnt_str.Threshold	3287
k_BSINodeAbsentDiag_Cnt_str.PStep	3168
k_BSINodeAbsentDiag_Cnt_str.NStep	19422
k_BSINodeAbsentTimeout_mS_u16	12017
k_BSINodeTimeout_mS_u16	12457
k_BattOvHi_Volt_f32	31.5
k_BattOvLo_Volt_f32	23.406601
k_BattUvHi_Volt_f32	16.5062008
k_BattUvLo_Volt_f32	19.5340004
k_CAVNTCEnableTimeout_mS_u16	5515
k_CAVNodeAbsentDiag_Cnt_str.Threshold	60936

Name	Input Value
k_CAVNodeAbsentDiag_Cnt_str.PStep	27145
k_CAVNodeAbsentDiag_Cnt_str.NStep	20094
k_CAVNodeAbsentTimeout_mS_u16	63654
k_CAVNodeTimeout_mS_u16	23212
k_CMM388MsgTimeout_mS_u16	26316
k_CMM388NTCEnableTimeout_mS_u16	55720
k_CMMNTCEnableTimeout_mS_u16	38537
k_CMMNodeAbsentDiag_Cnt_str.Threshold	26470
k_CMMNodeAbsentDiag_Cnt_str.PStep	38483
k_CMMNodeAbsentDiag_Cnt_str.NStep	6835
k_CMMNodeAbsentTimeout_mS_u16	60159
k_CONSANGLECPKMax_HwDeg_f32	771.218628
k_CONSANGLECPKMin_HwDeg_f32	-391.208313
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	20070
k_CONSANGLECPKSigValidThresh_Cnt_u16	13603
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	22165
k_CPKVehicleSpeedValidThresh_Cnt_u16	19982
k_CityParkInputInvalidThresh_Cnt_u16	4170
k_CityParkInputValidThresh_Cnt_u16	26140
k_ComputerRazGCTSigValidThresh_Cnt_u16	52071
k_CptTemporelSigValidThresh_Cnt_u16	57376
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	5511
k_DMDFCTCPKSigValidThresh_Cnt_u16	39132
k_DMDFCTCPKValidCount_Cnt_u16	57071
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	59768
k_DMDRELAXECPKSigValidThresh_Cnt_u16	1382
k_DMDRelaxeConsistentThresh_Cnt_u16	59292
k_DateValidThresh_Cnt_u16	33061
k_DefaultVehSpd_Kph_f32	22.4486008
k_DiagMuxOnAbsentTimeout_mS_u16	64166
k_EMNodeTimeout_mS_u16	63389
k_ESPNTCEnableTimeout_mS_u16	16660
k_ESPNodeAbsentDiag_Cnt_str.Threshold	20433
k_ESPNodeAbsentDiag_Cnt_str.PStep	13965
k_ESPNodeAbsentDiag_Cnt_str.NStep	57022
k_ESPNodeAbsentTimeout_mS_u16	19527
k_EtatMTSigInvalidThresh_Cnt_u16	44659
k_EtatMTSigValidThresh_Cnt_u16	51520
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	34192
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	60641
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	64997
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	55134
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	51031
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	26391
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	64713
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	14474
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	11744
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	39300
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	64782
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	42361
k_ISDATDIRASentDiag_Cnt_str.Threshold	64711
k_ISDATDIRASentDiag_Cnt_str.PStep	35441
k_ISDATDIRASentDiag_Cnt_str.NStep	35487
k_ISDATDIRASentTimeout_mS_u16	33648
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	53086
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	30265
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	35712
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	50836
k_ISDYNAASChkSumValidThresh_Cnt_u16	26657
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	35861
k_ISDYNAASMsgCountValidThresh_Cnt_u16	53818
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	5816
k_ISDYNAASMsgLenValidThresh_Cnt_u16	3459
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39064
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	25845
k_ISDYNABRChkSumValidThresh_Cnt_u16	16074
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	34727
k_ISDYNABRMsgCountValidThresh_Cnt_u16	3757
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	21656
k_ISDYNABRMsgLenValidThresh_Cnt_u16	7577
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	49132
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	11813
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	47100

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	18718
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	4848
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	44726
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	39709
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	51398
k_ISDYNVOLChkSumValidThresh_Cnt_u16	8815
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	44038
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	19269
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	10257
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	30083
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	6347
k_IgnOnTimeout_mS_u16	60578
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	85.9001999
k_PowerCutVehSpdLowThresh_Kph_f32	174.470596
k_PowerCutVehSpdLowTimeout_mS_u16	45691
k_VBattMaxAAS_Volt_f32	15.9166002
k_VBattMaxBSI_Volt_f32	25.3250008
k_VBattMaxCAV_Volt_f32	5.37830019
k_VBattMaxCMM388_Volt_f32	7.22559977
k_VBattMaxCMM_Volt_f32	4.22300005
k_VBattMaxESP_Volt_f32	25.4843006
k_VBattMinAAS_Volt_f32	3.41140008
k_VBattMinBSI_Volt_f32	25.4843006
k_VBattMinCAV_Volt_f32	2.59629989
k_VBattMinCMM388_Volt_f32	31.5373001
k_VBattMinCMM_Volt_f32	0.0241999999
k_VBattMinESP_Volt_f32	4.22300005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	37416
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	15618
k_VitesseVehicleBVRampValidThresh_Cnt_u16	61615
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	53715
k_VitesseVehicleBVSigValidThresh_Cnt_u16	8861
k_VitesseVehicleBVSpeedPassThresh_kph_f32	363.340912
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	32824
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	55254
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3340494336
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	145
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	180
target_SrlComInput_Per1_Batt_Volt_f32.value	3.25600004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2361382400
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	23
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0361702926
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	346293760
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	217916928
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2653308416
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3491718656
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2867365376
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	914466304

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2062206464
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	42
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	82
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	163
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	186
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	204
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1363699200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	39
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	161
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	228
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3135178240
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3065521664
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	190924288
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	155
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	240
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1608996352
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	978
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.592304766
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	64595
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	67.1612015
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	45899

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	5734	5734	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	24561	24561	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	30267	30267	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	80.8309708	80.8309708	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	3287	3287	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3287209472	3287209472	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CAVNodeAbsentFltAcc_Cnt_M_u16	60936	60936	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	26470	26470	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	51712	51712	✔
CONSANGLECPK_HwDeg_M_f32	-168.268799	-168.268799 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	51712	51712	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	499955200	499955200	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	37478	37478	✔
CityParkInputConsistentCount_Cnt_M_u16	26140	26140	✔
CityParkInputInvalidCount_Cnt_M_u16	40549	40549	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	20433	20433	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1713429248	1713429248	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	2	2	✔
ElecIntTimer_mS_M_u32[0]	2323	2323	✔
ElecIntTimer_mS_M_u32[1]	1713429248	1713429248	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	64711	64711	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	61502	61502	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	48559	48559	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	190924288	190924288	✔
IgnOnTimer_mS_M_u32	1351222784	1351222784	✔
IgnTimeOff_Sec_M_u32	436383263	436383263	✔
Msg348Valid_Cnt_M_Igc	0	0	✔
Msg432Valid_Cnt_M_Igc	0	0	✔
Msg552Valid_Cnt_M_Igc	0	0	✔
NetOn_Cnt_M_Igc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	183	183	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	346293760	346293760	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	217916928	217916928	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	105	105	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2653308416	2653308416	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3491718656	3491718656	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2084259328	2084259328	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	914466304	914466304	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	105	105	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2062206464	2062206464	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	104	104	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1363699200	1363699200	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	35	35	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3135178240	3135178240	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	86	86	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3065521664	3065521664	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	221	221	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	190924288	190924288	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1608996352	1608996352	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	286.260193	286.260193	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	553.436584	553.436584	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	247.503494	247.503494	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	80.8309708	80.8309708	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	51712	51712	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	436383263	436383263	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-168.268799	-168.268799 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	22.4486008	22.4486008	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0151	0x0151	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0152	0x0152	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔
NTC	0x0153	0x0153	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	3	ValidityNTCProcessing	3	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.165 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	417177856
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	17554
AASNodeAbsentTimer_mS_M_u32	2451689728
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	29220
ANGLEVOLANTSigValidCount_Cnt_M_u16	32916
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	61771
AngleVolantMsgTimer_mS_M_u32	417177856
AngleVolantValidCount_Cnt_M_u16	35725
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	484.285126
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3316027648
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	627249408
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3010183424
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1593016576
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	45055
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1722433792
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	29388
CAVNodeAbsentTimer_mS_M_u32	2914251008
CDD_SrlComVehSpd_Kph_G_f32	582.554199
CMM388NTCEnableTimer_mS_M_u32	3838521600
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1813115136
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	4205
CMMNodeAbsentTimer_mS_M_u32	3574956288
CONSANGLECPKSigInvalidCount_Cnt_M_u16	42629

Name	Input Value
CONSANGLECPKSigValidCount_Cnt_M_u16	16389
CONSANGLECPK_Cnt_M_u16	61620
CONSANGLECPK_HwDeg_M_f32	684.942688
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	61620
CPKVehicleSpeedMsgTimer_mS_M_u32	2828050688
CPKVehicleSpeedValidCount_Cnt_M_u16	5994
CityParkInputConsistentCount_Cnt_M_u16	5665
CityParkInputInvalidCount_Cnt_M_u16	8774
CityParkInputMsgTimer_mS_M_u32	346293760
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3249918208
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	27942
ComputerRazGCTSigInvalidTimer_mS_M_u32	2331668736
ComputerRazGCTSigValidCount_Cnt_M_u16	38962
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	50098
DMDFCTCPKSigValidCount_Cnt_M_u16	21353
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	8814
DMDRELAXECPKSigValidCount_Cnt_M_u16	46174
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	47166
DateInvalidTimer_mS_M_u32	627249408
DiagMuxOnAbsentTimer_mS_M_u32	1374970112
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1593016576
ESPNTCEnableTimer_mS_M_u32	2267992320
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	34600
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	5
EffacDefaultDiagTimer_mS_M_u32[1]	155
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2323
ElecIntTimer_mS_M_u32[1]	45466
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2111062272
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	56469
EtatMTSigValidCount_Cnt_M_u16	19713
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	46287
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	20943
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	967
ISDAT4V2BSI552MsgTimer_mS_M_u32	1269399808
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	25667
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	1367
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	19713
ISDATBSI3F2MsgTimer_mS_M_u32	2074763520
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	34780
ISDATBSI412MsgLenValidCount_Cnt_M_u16	34144
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	56469
ISDATBSI412MsgTimer_mS_M_u32	278110464
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	3585
ISDATBSI432MsgLenValidCount_Cnt_M_u16	19388
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	52345
ISDATDIRASentFltAcc_Cnt_M_u16	9693
ISDATDIRASentTimer_mS_M_u32	2828050688
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	5866
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	35725
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	19725
ISDYN2CMMMsgTimer_mS_M_u32	1607520512
ISDYNAASChkSumInvalidCount_Cnt_M_u16	37084
ISDYNAASChkSumValidCount_Cnt_M_u16	25067
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	58088
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	43707
ISDYNAASMsgLenValidCount_Cnt_M_u16	19170
ISDYNAASMsgTimeValidCount_Cnt_M_u16	37084
ISDYNAASMsgTimer_mS_M_u32	3342283008
ISDYNABRChkSumInvalidCount_Cnt_M_u16	7354

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNABRChkSumValidCount_Cnt_M_u16	14802
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	14519
ISDYNABRMsgCountValidCount_Cnt_M_u16	51206
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	13664
ISDYNABRMsgLenValidCount_Cnt_M_u16	52512
ISDYNABRMsgTimeValidCount_Cnt_M_u16	61620
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	755
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1395
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	19713
ISDYNCMM208MsgTimer_mS_M_u32	4277637376
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2871
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1501
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	40515
ISDYNCMM388MsgTimer_mS_M_u32	335851776
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	10299
ISDYNVOLChkSumValidCount_Cnt_M_u16	48699
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	27752
ISDYNVOLMsgCountValidCount_Cnt_M_u16	65535
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	25165
ISDYNVOLMsgLenValidCount_Cnt_M_u16	6445
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	4205
ISDYNVOLMsgTimer_mS_M_u32	694579456
IgnOnTimer_mS_M_u32	1771614464
IgnTimeOff_Sec_M_u32	2702926059
ManVehSpd_Kph_M_f32	253.104202
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	121
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	125
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1147691264
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	113
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	413581568
PrevISDATBSI412MsgDLCError_Cnt_M_u08	142
PrevISDATBSI412MsgRxTime_MSec_M_u32	3743478016
PrevISDATBSI432MsgDLCError_Cnt_M_u08	92
PrevISDATBSI432MsgRxTime_MSec_M_u32	1869795584
PrevISDATDIRAMsgTxTime_MSec_M_u32	998568192
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	110
PrevISDYN2CMMMsgRxTime_MSec_M_u32	969605376
PrevISDYNAASMsgDLCError_Cnt_M_u08	136
PrevISDYNAASMsgRxTime_MSec_M_u32	4154224896
PrevISDYNABRMsgDLCError_Cnt_M_u08	104
PrevISDYNABRMsgRxTime_MSec_M_u32	2775625984
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	90
PrevISDYNCMM208MsgRxTime_MSec_M_u32	544043264
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	165
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3106001152
PrevISDYNVOLMsgDLCError_Cnt_M_u08	129
PrevISDYNVOLMsgRxTime_MSec_M_u32	3756650752
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2135531776
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	44.2355003
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	8561
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	32280
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	2

Name	Input Value
VehSpdControl_Cnt_M_Igc	0
VehSpdSync_Cnt_M_Igc	1
VehTimeValid_Cnt_M_Igc	0
VehicleSpeedValid_Cnt_M_Igc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	13334
VitesseVehicleBVRampValidCount_Cnt_M_u16	45693
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	38985
VitesseVehicleBVSigValidCount_Cnt_M_u16	26745
VitesseVehicleBV_Kph_M_f32	573.333008
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	40515
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	43979
VitesseVehiculeRoues_Kph_M_f32	613.020996
k_AASNTCEnableTimeout_mS_u16	37287
k_AASNodeAbsentDiag_Cnt_str.Threshold	30724
k_AASNodeAbsentDiag_Cnt_str.PStep	54142
k_AASNodeAbsentDiag_Cnt_str.NStep	34029
k_AASNodeAbsentTimeout_mS_u16	36692
k_AASNodeTimeout_mS_u16	9496
k_ABSNodeTimeout_mS_u16	48579
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	61960
k_ANGLEVOLANTSigValidThresh_Cnt_u16	63235
k_AngleVolantInvalidThresh_Cnt_u16	34310
k_AngleVolantValidThresh_Cnt_u16	8774
k_BSI552MsgTimeout_mS_u16	11406
k_BSINTCEnableTimeout_mS_u16	63961
k_BSINodeAbsentDiag_Cnt_str.Threshold	2722
k_BSINodeAbsentDiag_Cnt_str.PStep	2638
k_BSINodeAbsentDiag_Cnt_str.NStep	15212
k_BSINodeAbsentTimeout_mS_u16	42787
k_BSINodeTimeout_mS_u16	52345
k_BattOvHi_Volt_f32	24.9403992
k_BattOvLo_Volt_f32	8.48659992
k_BattUvHi_Volt_f32	17.2224007
k_BattUvLo_Volt_f32	22.5800991
k_CAVNTCEnableTimeout_mS_u16	54484
k_CAVNodeAbsentDiag_Cnt_str.Threshold	6987
k_CAVNodeAbsentDiag_Cnt_str.PStep	38634
k_CAVNodeAbsentDiag_Cnt_str.NStep	38781
k_CAVNodeAbsentTimeout_mS_u16	43138
k_CAVNodeTimeout_mS_u16	8433
k_CMM388MsgTimeout_mS_u16	11154
k_CMM388NTCEnableTimeout_mS_u16	17150
k_CMMNTCEnableTimeout_mS_u16	64539
k_CMMNodeAbsentDiag_Cnt_str.Threshold	15003
k_CMMNodeAbsentDiag_Cnt_str.PStep	51366
k_CMMNodeAbsentDiag_Cnt_str.NStep	59557
k_CMMNodeAbsentTimeout_mS_u16	41271
k_CONSANGLECPKMax_HwDeg_f32	114.656097
k_CONSANGLECPKMin_HwDeg_f32	-586.599304
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	1347
k_CONSANGLECPKSigValidThresh_Cnt_u16	21195
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	38006
k_CPKVehicleSpeedValidThresh_Cnt_u16	31371
k_CityParkInputInvalidThresh_Cnt_u16	65176
k_CityParkInputValidThresh_Cnt_u16	5665
k_ComputerRazGCTSigValidThresh_Cnt_u16	21889
k_CptTemporelSigValidThresh_Cnt_u16	2325
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	7264
k_DMDFCTCPKSigValidThresh_Cnt_u16	62496
k_DMDFCTCPKValidCount_Cnt_u16	45351
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	19725
k_DMDRELAXECPKSigValidThresh_Cnt_u16	47876
k_DMDRelaxeConsistentThresh_Cnt_u16	27746
k_DateValidThresh_Cnt_u16	967
k_DefaultVehSpd_Kph_f32	127.118202
k_DiagMuxOnAbsentTimeout_mS_u16	30402
k_EMNodeTimeout_mS_u16	19998
k_ESPNTCEnableTimeout_mS_u16	1848
k_ESPNodeAbsentDiag_Cnt_str.Threshold	35454
k_ESPNodeAbsentDiag_Cnt_str.PStep	601
k_ESPNodeAbsentDiag_Cnt_str.NStep	63527
k_ESPNodeAbsentTimeout_mS_u16	40287
k_EtatMTSigInvalidThresh_Cnt_u16	2077

Name	Input Value
k_EtatMTSigValidThresh_Cnt_u16	63861
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	45957
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	53073
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	45766
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	52636
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	61296
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	37744
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	49882
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	8533
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	19349
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	37416
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	39243
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	12617
k_ISDATDIRASentDiag_Cnt_str.Threshold	62208
k_ISDATDIRASentDiag_Cnt_str.PStep	30559
k_ISDATDIRASentDiag_Cnt_str.NStep	53426
k_ISDATDIRASentTimeout_mS_u16	48422
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	34714
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	61771
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	55284
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	33722
k_ISDYNAASChkSumValidThresh_Cnt_u16	57554
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	8119
k_ISDYNAASMsgCountValidThresh_Cnt_u16	61190
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	9038
k_ISDYNAASMsgLenValidThresh_Cnt_u16	42924
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	47403
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	26134
k_ISDYNABRChkSumValidThresh_Cnt_u16	14934
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	38655
k_ISDYNABRMsgCountValidThresh_Cnt_u16	9135
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46957
k_ISDYNABRMsgLenValidThresh_Cnt_u16	28200
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	52210
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	50181
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	29889
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	8411
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	22820
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	42900
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	3102
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	60003
k_ISDYNVOLChkSumValidThresh_Cnt_u16	36647
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	46817
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	51046
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	45569
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	39789
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	21717
k_IgnOnTimeout_mS_u16	61135
k_JDD2010Selected_Cnt_Igc	0
k_PowerCutVehSpdHighThresh_Kph_f32	151.263199
k_PowerCutVehSpdLowThresh_Kph_f32	85.5522995
k_PowerCutVehSpdLowTimeout_mS_u16	58179
k_VBattMaxAAS_Volt_f32	17.7945004
k_VBattMaxBSI_Volt_f32	30.1100998
k_VBattMaxCAV_Volt_f32	25.6394997
k_VBattMaxCMM388_Volt_f32	25.9815998
k_VBattMaxCMM_Volt_f32	10.2073002
k_VBattMaxESP_Volt_f32	32
k_VBattMinAAS_Volt_f32	22.5356998
k_VBattMinBSI_Volt_f32	32
k_VBattMinCAV_Volt_f32	11.2563
k_VBattMinCMM388_Volt_f32	0.709699988
k_VBattMinCMM_Volt_f32	14.7791996
k_VBattMinESP_Volt_f32	10.2073002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	59196
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	22640
k_VitesseVehicleBVRampValidThresh_Cnt_u16	54120
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	58683
k_VitesseVehicleBVSigValidThresh_Cnt_u16	9374
k_VitesseVehicleBVSpeedPassThresh_kph_f32	280.251007
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	55756
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	21683
target_Pim_ElecIntData	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Pim_ShutdownTimeData.Time_Sec_u32	627249408
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	219
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	165
target_SrlComInput_Per1_Batt_Volt_f32.value	12.5622997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2419540224
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	63
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.781401634
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	175
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	88781056
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1757368576
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1103360256
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2019070208
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4101845248
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2654064896
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1568043264
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	108
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	134
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	177
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	182
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3638399232
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	227
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3197743360
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	395202816
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2786259200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	145
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	348176640
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	713
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.839858115
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	345729
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	30.7301998
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	19603

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	30724	30724	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	29221	29221	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	61771	61771	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	484.285126	484.285126	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1722433792	1722433792	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	6987	6987	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2654064896	2654064896	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	61620	61620	✔
CONSANGLECPK_HwDeg_M_f32	684.942688	684.942688 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	61620	61620	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2828050688	2828050688	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	5994	5994	✔
CityParkInputConsistentCount_Cnt_M_u16	5665	5665	✔
CityParkInputInvalidCount_Cnt_M_u16	8776	8776	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	5	5	✔
EffacDefaultDiagTimer_mS_M_u32[1]	155	155	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2323	2323	✔
ElecIntTimer_mS_M_u32[1]	45466	45466	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	62208	62208	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	10300	10300	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	27753	27753	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2786259200	2786259200	✔
IgnOnTimer_mS_M_u32	1771614464	1771614464	✔
IgnTimeOff_Sec_M_u32	2702926059	2702926059	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	175	175	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	88781056	88781056	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	174	174	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1757368576	1757368576	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	48	48	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1103360256	1103360256	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	26	26	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2019070208	2019070208	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	998568192	998568192	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	205	205	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2654064896	2654064896	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1568043264	1568043264	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3638399232	3638399232	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3197743360	3197743360	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	395202816	395202816	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	129	129	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2786259200	2786259200	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	348176640	348176640	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	44.2355003	44.2355003	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	573.333008	573.333008	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	613.020996	613.020996	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	484.285126	484.285126	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	61620	61620	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2702926059	2702926059	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	684.942688	684.942688 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	127.118202	127.118202	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	5	ValidityNTCProcessing	5	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.166 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1959387136
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	25516
AASNodeAbsentTimer_mS_M_u32	2512211968
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	17652
ANGLEVOLANTSigValidCount_Cnt_M_u16	46181
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	33153
AngleVolantMsgTimer_mS_M_u32	1959387136
AngleVolantValidCount_Cnt_M_u16	34105
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	214.580902
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	4264497152
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1895403520
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	94339072
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3523756032
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	46947
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	98828288
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	59774
CAVNodeAbsentTimer_mS_M_u32	3011964928
CDD_SrlComVehSpd_Kph_G_f32	505.008392
CMM388NTCEnableTimer_mS_M_u32	2067869696
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1886187520
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	91
CMMNodeAbsentTimer_mS_M_u32	2007121920
CONSANGLECPKSigInvalidCount_Cnt_M_u16	6866

Name	Input Value
CONSANGLECPKSigValidCount_Cnt_M_u16	10515
CONSANGLECPK_Cnt_M_u16	37638
CONSANGLECPK_HwDeg_M_f32	-530.634705
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37638
CPKVehicleSpeedMsgTimer_mS_M_u32	1370546176
CPKVehicleSpeedValidCount_Cnt_M_u16	16171
CityParkInputConsistentCount_Cnt_M_u16	13693
CityParkInputInvalidCount_Cnt_M_u16	61968
CityParkInputMsgTimer_mS_M_u32	88781056
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1459703808
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	14832
ComputerRazGCTSigInvalidTimer_mS_M_u32	1437822976
ComputerRazGCTSigValidCount_Cnt_M_u16	13130
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	48588
DMDFCTCPKSigValidCount_Cnt_M_u16	51557
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56342
DMDRELAXECPKSigValidCount_Cnt_M_u16	49415
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	2471
DateInvalidTimer_mS_M_u32	1895403520
DiagMuxOnAbsentTimer_mS_M_u32	2491785216
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3523756032
ESPNTCEnableTimer_mS_M_u32	714493952
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	26344
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1111
EffacDefaultDiagTimer_mS_M_u32[1]	2222
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	5656
ElecIntTimer_mS_M_u32[1]	78790
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3898998784
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	36066
EtatMTSigValidCount_Cnt_M_u16	50783
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	38900
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	39861
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	45131
ISDAT4V2BSI552MsgTimer_mS_M_u32	1676034048
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	34136
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	52445
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	50783
ISDATBSI3F2MsgTimer_mS_M_u32	1868800000
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	3981
ISDATBSI412MsgLenValidCount_Cnt_M_u16	450
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	36066
ISDATBSI412MsgTimer_mS_M_u32	3852984320
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	22431
ISDATBSI432MsgLenValidCount_Cnt_M_u16	26924
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	53367
ISDATDIRASentFltAcc_Cnt_M_u16	21579
ISDATDIRASentTimer_mS_M_u32	1370546176
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	30820
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	34105
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	19899
ISDYN2CMMMsgTimer_mS_M_u32	2830127104
ISDYNAASChkSumInvalidCount_Cnt_M_u16	9934
ISDYNAASChkSumValidCount_Cnt_M_u16	52831
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	43816
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	48561
ISDYNAASMsgLenValidCount_Cnt_M_u16	22521
ISDYNAASMsgTimeValidCount_Cnt_M_u16	9934
ISDYNAASMsgTimer_mS_M_u32	2214408192
ISDYNABRChkSumInvalidCount_Cnt_M_u16	29875

Name	Input Value
ISDYNABRChkSumValidCount_Cnt_M_u16	22572
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	23357
ISDYNABRMsgCountValidCount_Cnt_M_u16	51214
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	39489
ISDYNABRMsgLenValidCount_Cnt_M_u16	44482
ISDYNABRMsgTimeValidCount_Cnt_M_u16	37638
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	756
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1397
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	50783
ISDYNCMM208MsgTimer_mS_M_u32	3594260480
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2875
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1503
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	42263
ISDYNCMM388MsgTimer_mS_M_u32	3012866048
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	60848
ISDYNVOLChkSumValidCount_Cnt_M_u16	1649
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	7082
ISDYNVOLMsgCountValidCount_Cnt_M_u16	22690
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	43385
ISDYNVOLMsgLenValidCount_Cnt_M_u16	57242
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	91
ISDYNVOLMsgTimer_mS_M_u32	711946240
IgnOnTimer_mS_M_u32	47755264
IgnTimeOff_Sec_M_u32	3162196177
ManVehSpd_Kph_M_f32	500.516113
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	123
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	250
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2368315392
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	230
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2179891200
PrevISDATBSI412MsgDLCError_Cnt_M_u08	160
PrevISDATBSI412MsgRxTime_MSec_M_u32	322957312
PrevISDATBSI432MsgDLCError_Cnt_M_u08	132
PrevISDATBSI432MsgRxTime_MSec_M_u32	2177519616
PrevISDATDIRAMsgTxTime_MSec_M_u32	2383671296
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	144
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4286693376
PrevISDYNAASMsgDLCError_Cnt_M_u08	124
PrevISDYNAASMsgRxTime_MSec_M_u32	399339520
PrevISDYNABRMsgDLCError_Cnt_M_u08	14
PrevISDYNABRMsgRxTime_MSec_M_u32	2941300736
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	88
PrevISDYNCMM208MsgRxTime_MSec_M_u32	559575040
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	25
PrevISDYNCMM388MsgRxTime_MSec_M_u32	549277696
PrevISDYNVOLMsgDLCError_Cnt_M_u08	126
PrevISDYNVOLMsgRxTime_MSec_M_u32	1961160704
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4052082688
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	648.327393
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	45455
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	5719
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	2

Name	Input Value
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	19872
VitesseVehicleBVRampValidCount_Cnt_M_u16	19752
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	42629
VitesseVehicleBVSigValidCount_Cnt_M_u16	53430
VitesseVehicleBV_Kph_M_f32	319.874512
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	42263
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	30528
VitesseVehiculeRoues_Kph_M_f32	209.783905
k_AASNTCEnableTimeout_mS_u16	15405
k_AASNodeAbsentDiag_Cnt_str.Threshold	47250
k_AASNodeAbsentDiag_Cnt_str.PStep	51043
k_AASNodeAbsentDiag_Cnt_str.NStep	64455
k_AASNodeAbsentTimeout_mS_u16	21988
k_AASNodeTimeout_mS_u16	8535
k_ABSNodeTimeout_mS_u16	21401
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	34698
k_ANGLEVOLANTSigValidThresh_Cnt_u16	17239
k_AngleVolantInvalidThresh_Cnt_u16	25166
k_AngleVolantValidThresh_Cnt_u16	61968
k_BSI552MsgTimeout_mS_u16	49399
k_BSINTCEnableTimeout_mS_u16	62487
k_BSINodeAbsentDiag_Cnt_str.Threshold	2835
k_BSINodeAbsentDiag_Cnt_str.PStep	2744
k_BSINodeAbsentDiag_Cnt_str.NStep	16054
k_BSINodeAbsentTimeout_mS_u16	49145
k_BSINodeTimeout_mS_u16	53367
k_BattOvHi_Volt_f32	24.4097996
k_BattOvLo_Volt_f32	8.73960018
k_BattUvHi_Volt_f32	18.4281998
k_BattUvLo_Volt_f32	24.0324001
k_CAVNTCEnableTimeout_mS_u16	37478
k_CAVNodeAbsentDiag_Cnt_str.Threshold	44954
k_CAVNodeAbsentDiag_Cnt_str.PStep	32686
k_CAVNodeAbsentDiag_Cnt_str.NStep	7254
k_CAVNodeAbsentTimeout_mS_u16	41052
k_CAVNodeTimeout_mS_u16	23438
k_CMM388MsgTimeout_mS_u16	44716
k_CMM388NTCEnableTimeout_mS_u16	6248
k_CMMNTCEnableTimeout_mS_u16	7632
k_CMMNodeAbsentDiag_Cnt_str.Threshold	13800
k_CMMNodeAbsentDiag_Cnt_str.PStep	35784
k_CMMNodeAbsentDiag_Cnt_str.NStep	9021
k_CMMNodeAbsentTimeout_mS_u16	18172
k_CONSANGLECPKMax_HwDeg_f32	429.056305
k_CONSANGLECPKMin_HwDeg_f32	-505.569
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	28695
k_CONSANGLECPKSigValidThresh_Cnt_u16	33344
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	52029
k_CPKVehicleSpeedValidThresh_Cnt_u16	45952
k_CityParkInputInvalidThresh_Cnt_u16	50969
k_CityParkInputValidThresh_Cnt_u16	13693
k_ComputerRazGCTSigValidThresh_Cnt_u16	10654
k_CptTemporelSigValidThresh_Cnt_u16	14755
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	58689
k_DMDFCTCPKSigValidThresh_Cnt_u16	14530
k_DMDFCTCPKValidCount_Cnt_u16	21483
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	19899
k_DMDRELAXECPKSigValidThresh_Cnt_u16	48788
k_DMDRelaxeConsistentThresh_Cnt_u16	41594
k_DateValidThresh_Cnt_u16	45131
k_DefaultVehSpd_Kph_f32	140.531204
k_DiagMuxOnAbsentTimeout_mS_u16	47324
k_EMNodeTimeout_mS_u16	51207
k_ESPNTCEnableTimeout_mS_u16	56378
k_ESPNodeAbsentDiag_Cnt_str.Threshold	8929
k_ESPNodeAbsentDiag_Cnt_str.PStep	12561
k_ESPNodeAbsentDiag_Cnt_str.NStep	52437
k_ESPNodeAbsentTimeout_mS_u16	62084
k_EtatMTSigInvalidThresh_Cnt_u16	65162

Name	Input Value
k_EtatMTSigValidThresh_Cnt_u16	25923
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	27152
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	8557
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	13198
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	60749
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	45714
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	15569
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	56596
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	35937
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	61155
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	32426
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	54271
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	22597
k_ISDATDIRASentDiag_Cnt_str.Threshold	52471
k_ISDATDIRASentDiag_Cnt_str.PStep	60363
k_ISDATDIRASentDiag_Cnt_str.NStep	42803
k_ISDATDIRASentTimeout_mS_u16	17263
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	55634
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	33153
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	23046
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	16307
k_ISDYNAASChkSumValidThresh_Cnt_u16	25388
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	42557
k_ISDYNAASMsgCountValidThresh_Cnt_u16	21262
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	45303
k_ISDYNAASMsgLenValidThresh_Cnt_u16	59803
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	40159
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	24607
k_ISDYNABRChkSumValidThresh_Cnt_u16	48672
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	611
k_ISDYNABRMsgCountValidThresh_Cnt_u16	63252
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	2907
k_ISDYNABRMsgLenValidThresh_Cnt_u16	45544
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	51787
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	6611
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7390
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	64014
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	36852
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	16229
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	38024
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	50168
k_ISDYNVOLChkSumValidThresh_Cnt_u16	49261
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	64445
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	65392
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	48286
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	35611
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	29985
k_IgnOnTimeout_mS_u16	26292
k_JDD2010Selected_Cnt_Igc	1
k_PowerCutVehSpdHighThresh_Kph_f32	192.596207
k_PowerCutVehSpdLowThresh_Kph_f32	45.7290001
k_PowerCutVehSpdLowTimeout_mS_u16	46937
k_VBattMaxAAS_Volt_f32	24.4612007
k_VBattMaxBSI_Volt_f32	30.8911991
k_VBattMaxCAV_Volt_f32	24.4276009
k_VBattMaxCMM388_Volt_f32	20.5571995
k_VBattMaxCMM_Volt_f32	10.2268
k_VBattMaxESP_Volt_f32	15.8892002
k_VBattMinAAS_Volt_f32	9.56089973
k_VBattMinBSI_Volt_f32	15.8892002
k_VBattMinCAV_Volt_f32	2.55629992
k_VBattMinCMM388_Volt_f32	19.3834
k_VBattMinCMM_Volt_f32	20.5841007
k_VBattMinESP_Volt_f32	10.2268
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	49772
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	6545
k_VitesseVehicleBVRampValidThresh_Cnt_u16	59050
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	37233
k_VitesseVehicleBVSigValidThresh_Cnt_u16	15878
k_VitesseVehicleBVSpeedPassThresh_kph_f32	507.527802
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	46206
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	48774
target_Pim_ElecIntData	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Pim_ShutdownTimeData.Time_Sec_u32	1895403520
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	229
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8524
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1236548
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	25
target_SrlComInput_Per1_Batt_Volt_f32.value	10.2563
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4248633344
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	4
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0454229452
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2009247744
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1743048704
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	928444416
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	773394432
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2485858304
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	207
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2978828288
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3460263936
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	131
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1619660800
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	36
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	156
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	157
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	184
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1205186560
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1467469824
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	107606016
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1973452800
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2472
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.57820338
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	345243
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	60.4450989
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	14377

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1236548	1236548	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	47250	47250	✔
AASNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	17653	17653	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	33153	33153	✔
AngleVolantMsgTimer_mS_M_u32	1236548	1236548	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	214.580902	214.580902	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1236548	1236548	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	98828288	98828288	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	44954	44954	✔
CAVNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2978828288	2978828288	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	37638	37638	✔
CONSANGLECPK_HwDeg_M_f32	-530.634705	-530.634705 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37638	37638	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1370546176	1370546176	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	16171	16171	✔
CityParkInputConsistentCount_Cnt_M_u16	13693	13693	✔
CityParkInputInvalidCount_Cnt_M_u16	61968	61968	✔
CityParkInputMsgTimer_mS_M_u32	1236548	1236548	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1236548	1236548	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1236548	1236548	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1236548	1236548	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1236548	1236548	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1236548	1236548	✔
ESPNTCEnableTimer_mS_M_u32	1236548	1236548	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1111	1111	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2222	2222	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1236548	1236548	✔
ElecIntTimer_mS_M_u32[1]	78790	78790	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1236548	1236548	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATDIRASentFltAcc_Cnt_M_u16	52471	52471	✔
ISDATDIRASentTimer_mS_M_u32	1236548	1236548	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	60848	60848	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	7083	7083	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	107606016	107606016	✔
IgnOnTimer_mS_M_u32	47755264	47755264	✔
IgnTimeOff_Sec_M_u32	3162196177	3162196177	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2009247744	2009247744	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	192	192	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1743048704	1743048704	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	119	119	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	928444416	928444416	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	49	49	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	773394432	773394432	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2383671296	2383671296	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	207	207	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2978828288	2978828288	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	67	67	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3460263936	3460263936	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1619660800	1619660800	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	141	141	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1205186560	1205186560	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	72	72	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1467469824	1467469824	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	126	126	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	107606016	107606016	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1973452800	1973452800	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	648.327393	648.327393	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	319.874512	319.874512	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	209.783905	209.783905	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	214.580902	214.580902	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	37638	37638	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3162196177	3162196177	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-530.634705	-530.634705 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	140.531204	140.531204	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0152	0x0152	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	4	ValidityNTCProcessing	4	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.167 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	610121216
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	46028
AASNodeAbsentTimer_mS_M_u32	624010752
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	24560
ANGLEVOLANTSigValidCount_Cnt_M_u16	48054
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	30265
AngleVolantMsgTimer_mS_M_u32	610121216
AngleVolantValidCount_Cnt_M_u16	3832
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	613.599121
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1761961472
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3340494336
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3383645696
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2038502912
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	54439
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3287209472
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	19768
CAVNodeAbsentTimer_mS_M_u32	1691764224
CDD_SrlComVehSpd_Kph_G_f32	16.2320004
CMM388NTCEnableTimer_mS_M_u32	1657701888

Name	Input Value
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2550941184
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	57752
CMMNodeAbsentTimer_mS_M_u32	885724672
CONSANGLECPKSigInvalidCount_Cnt_M_u16	2256
CONSANGLECPKSigValidCount_Cnt_M_u16	41189
CONSANGLECPK_Cnt_M_u16	51712
CONSANGLECPK_HwDeg_M_f32	-168.268799
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	51712
CPKVehicleSpeedMsgTimer_mS_M_u32	499955200
CPKVehicleSpeedValidCount_Cnt_M_u16	37478
CityParkInputConsistentCount_Cnt_M_u16	26140
CityParkInputInvalidCount_Cnt_M_u16	40549
CityParkInputMsgTimer_mS_M_u32	1133657856
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1163240960
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	33008
ComputerRazGCTSigInvalidTimer_mS_M_u32	3686712832
ComputerRazGCTSigValidCount_Cnt_M_u16	54977
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	58177
DMDFCTCPKSigValidCount_Cnt_M_u16	62447
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	4738
DMDRELAXECPKSigValidCount_Cnt_M_u16	38856
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	21565
DateInvalidTimer_mS_M_u32	3340494336
DiagMuxOnAbsentTimer_mS_M_u32	866874880
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2038502912
ESPNTCEnableTimer_mS_M_u32	4286752256
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	27289
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	2323
ElecIntTimer_mS_M_u32[1]	1713429248
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2128664064
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	40757
EtatMTSigValidCount_Cnt_M_u16	49063
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	61794
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	13047
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	33061
ISDAT4V2BSI552MsgTimer_mS_M_u32	3891205632
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	54225
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	17418
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	49063
ISDATBSI3F2MsgTimer_mS_M_u32	3810096640
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	15091
ISDATBSI412MsgLenValidCount_Cnt_M_u16	52316
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	40757
ISDATBSI412MsgTimer_mS_M_u32	969651712
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	26556
ISDATBSI432MsgLenValidCount_Cnt_M_u16	957
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	12457
ISDATDIRASentFltAcc_Cnt_M_u16	733
ISDATDIRASentTimer_mS_M_u32	499955200
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	53230
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	3832
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	59768
ISDYN2CMMMsgTimer_mS_M_u32	4014777856
ISDYNAASChkSumInvalidCount_Cnt_M_u16	12894
ISDYNAASChkSumValidCount_Cnt_M_u16	52547
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	31535

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	40595
ISDYNAASMsgLenValidCount_Cnt_M_u16	38001
ISDYNAASMsgTimeValidCount_Cnt_M_u16	12894
ISDYNAASMsgTimer_mS_M_u32	1017808384
ISDYNABRChkSumInvalidCount_Cnt_M_u16	37780
ISDYNABRChkSumValidCount_Cnt_M_u16	62753
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	55573
ISDYNABRMsgCountValidCount_Cnt_M_u16	57146
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	25223
ISDYNABRMsgLenValidCount_Cnt_M_u16	42460
ISDYNABRMsgTimeValidCount_Cnt_M_u16	51712
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	856
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1489
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	49063
ISDYNCMM208MsgTimer_mS_M_u32	4058670592
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2911
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1521
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	7014
ISDYNCMM388MsgTimer_mS_M_u32	2456159744
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	61502
ISDYNVOLChkSumValidCount_Cnt_M_u16	57043
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0
ISDYNVOLMsgCountValidCount_Cnt_M_u16	5354
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	17122
ISDYNVOLMsgLenValidCount_Cnt_M_u16	64472
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	57752
ISDYNVOLMsgTimer_mS_M_u32	563791360
IgnOnTimer_mS_M_u32	1351222784
IgnTimeOff_Sec_M_u32	436383263
ManVehSpd_Kph_M_f32	382.217804
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	85
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	124
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3895424512
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	220
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2974111232
PrevISDATBSI412MsgDLCError_Cnt_M_u08	95
PrevISDATBSI412MsgRxTime_MSec_M_u32	2869380608
PrevISDATBSI432MsgDLCError_Cnt_M_u08	17
PrevISDATBSI432MsgRxTime_MSec_M_u32	571909632
PrevISDATDIRAMsgTxTime_MSec_M_u32	2084259328
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	4
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3800995328
PrevISDYNAASMsgDLCError_Cnt_M_u08	18
PrevISDYNAASMsgRxTime_MSec_M_u32	4018718208
PrevISDYNABRMsgDLCError_Cnt_M_u08	222
PrevISDYNABRMsgRxTime_MSec_M_u32	2269251072
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	194
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2112734720
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	180
PrevISDYNCMM388MsgRxTime_MSec_M_u32	405906944
PrevISDYNVOLMsgDLCError_Cnt_M_u08	221
PrevISDYNVOLMsgRxTime_MSec_M_u32	1724139008
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3526997504
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	286.260193
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4

Name	Input Value
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57089
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	60255
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	42186
VitesseVehicleBVRampValidCount_Cnt_M_u16	42472
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	7993
VitesseVehicleBVSigValidCount_Cnt_M_u16	36799
VitesseVehicleBV_Kph_M_f32	553.436584
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	7014
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	49699
VitesseVehiculeRoues_Kph_M_f32	247.503494
k_AASNTCEnableTimeout_mS_u16	48559
k_AASNodeAbsentDiag_Cnt_str.Threshold	5734
k_AASNodeAbsentDiag_Cnt_str.PStep	31939
k_AASNodeAbsentDiag_Cnt_str.NStep	31892
k_AASNodeAbsentTimeout_mS_u16	26379
k_AASNodeTimeout_mS_u16	24159
k_ABSNodeTimeout_mS_u16	11238
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	29967
k_ANGLEVOLANTSigValidThresh_Cnt_u16	31056
k_AngleVolantInvalidThresh_Cnt_u16	34895
k_AngleVolantValidThresh_Cnt_u16	40549
k_BSI552MsgTimeout_mS_u16	54754
k_BSINTCEnableTimeout_mS_u16	3700
k_BSINodeAbsentDiag_Cnt_str.Threshold	3287
k_BSINodeAbsentDiag_Cnt_str.PStep	3168
k_BSINodeAbsentDiag_Cnt_str.NStep	19422
k_BSINodeAbsentTimeout_mS_u16	12017
k_BSINodeTimeout_mS_u16	12457
k_BattOvHi_Volt_f32	31.5
k_BattOvLo_Volt_f32	23.406601
k_BattUvHi_Volt_f32	16.5062008
k_BattUvLo_Volt_f32	19.5340004
k_CAVNTCEnableTimeout_mS_u16	5515
k_CAVNodeAbsentDiag_Cnt_str.Threshold	60936
k_CAVNodeAbsentDiag_Cnt_str.PStep	27145
k_CAVNodeAbsentDiag_Cnt_str.NStep	20094
k_CAVNodeAbsentTimeout_mS_u16	63654
k_CAVNodeTimeout_mS_u16	23212
k_CMM388MsgTimeout_mS_u16	26316
k_CMM388NTCEnableTimeout_mS_u16	55720
k_CMMNTCEnableTimeout_mS_u16	38537
k_CMMNodeAbsentDiag_Cnt_str.Threshold	26470
k_CMMNodeAbsentDiag_Cnt_str.PStep	38483
k_CMMNodeAbsentDiag_Cnt_str.NStep	6835
k_CMMNodeAbsentTimeout_mS_u16	60159
k_CONSANGLECPKMax_HwDeg_f32	771.218628
k_CONSANGLECPKMin_HwDeg_f32	-391.208313
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	20070
k_CONSANGLECPKSigValidThresh_Cnt_u16	13603
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	22165
k_CPKVehicleSpeedValidThresh_Cnt_u16	19982
k_CityParkInputInvalidThresh_Cnt_u16	4170
k_CityParkInputValidThresh_Cnt_u16	26140
k_ComputerRazGCTSigValidThresh_Cnt_u16	52071
k_CptTemporelSigValidThresh_Cnt_u16	57376
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	5511
k_DMDFCTCPKSigValidThresh_Cnt_u16	39132
k_DMDFCTCPKValidCount_Cnt_u16	57071
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	59768
k_DMDRELAXECPKSigValidThresh_Cnt_u16	1382
k_DMDRelaxeConsistentThresh_Cnt_u16	59292
k_DateValidThresh_Cnt_u16	33061
k_DefaultVehSpd_Kph_f32	22.4486008
k_DiagMuxOnAbsentTimeout_mS_u16	64166
k_EMNodeTimeout_mS_u16	63389

Name	Input Value
k_ESPNTCEnableTimeout_mS_u16	16660
k_ESPNodeAbsentDiag_Cnt_str.Threshold	20433
k_ESPNodeAbsentDiag_Cnt_str.PStep	13965
k_ESPNodeAbsentDiag_Cnt_str.NStep	57022
k_ESPNodeAbsentTimeout_mS_u16	19527
k_EtatMTSigInvalidThresh_Cnt_u16	44659
k_EtatMTSigValidThresh_Cnt_u16	51520
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	34192
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	60641
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	64997
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	55134
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	51031
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	26391
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	64713
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	14474
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	11744
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	39300
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	64782
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	42361
k_ISDATDIRASentDiag_Cnt_str.Threshold	64711
k_ISDATDIRASentDiag_Cnt_str.PStep	35441
k_ISDATDIRASentDiag_Cnt_str.NStep	35487
k_ISDATDIRASentTimeout_mS_u16	33648
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	53086
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	30265
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	35712
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	50836
k_ISDYNAASChkSumValidThresh_Cnt_u16	26657
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	35861
k_ISDYNAASMsgCountValidThresh_Cnt_u16	53818
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	5816
k_ISDYNAASMsgLenValidThresh_Cnt_u16	3459
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39064
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	25845
k_ISDYNABRChkSumValidThresh_Cnt_u16	16074
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	34727
k_ISDYNABRMsgCountValidThresh_Cnt_u16	3757
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	21656
k_ISDYNABRMsgLenValidThresh_Cnt_u16	7577
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	49132
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	11813
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	47100
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	18718
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	4848
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	44726
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	39709
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	51398
k_ISDYNVOLChkSumValidThresh_Cnt_u16	8815
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	44038
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	19269
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	10257
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	30083
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	6347
k_IgnOnTimeout_mS_u16	60578
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	85.9001999
k_PowerCutVehSpdLowThresh_Kph_f32	174.470596
k_PowerCutVehSpdLowTimeout_mS_u16	45691
k_VBattMaxAAS_Volt_f32	15.9166002
k_VBattMaxBSI_Volt_f32	25.3250008
k_VBattMaxCAV_Volt_f32	5.37830019
k_VBattMaxCMM388_Volt_f32	7.22559977
k_VBattMaxCMM_Volt_f32	4.22300005
k_VBattMaxESP_Volt_f32	25.4843006
k_VBattMinAAS_Volt_f32	3.41140008
k_VBattMinBSI_Volt_f32	25.4843006
k_VBattMinCAV_Volt_f32	2.59629989
k_VBattMinCMM388_Volt_f32	31.5373001
k_VBattMinCMM_Volt_f32	0.0241999999
k_VBattMinESP_Volt_f32	4.22300005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	37416
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	15618
k_VitesseVehicleBVRampValidThresh_Cnt_u16	61615

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	53715
k_VitesseVehicleBVSigValidThresh_Cnt_u16	8861
k_VitesseVehicleBVSpeedPassThresh_kph_f32	363.340912
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	32824
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	55254
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3340494336
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	145
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	180
target_SrlComInput_Per1_Batt_Volt_f32.value	3.25600004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2361382400
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	23
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0361702926
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	346293760
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	217916928
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2653308416
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3491718656
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2867365376
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	914466304
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2062206464
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	42
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	82
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	163
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	186
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	204
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1363699200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	39
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	161
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	228
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3135178240
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3065521664
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	190924288
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	155

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	240
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1608996352
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	811
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.592304766
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	937042
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	67.1612015
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	45899

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	5734	5734	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	24561	24561	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	30267	30267	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	613.599121	613.599121	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	3287	3287	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3287209472	3287209472	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	60936	60936	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	26470	26470	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	51712	51712	✔
CONSANGLECPK_HwDeg_M_f32	-168.268799	-168.268799 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	51712	51712	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	499955200	499955200	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	37478	37478	✔
CityParkInputConsistentCount_Cnt_M_u16	26140	26140	✔
CityParkInputInvalidCount_Cnt_M_u16	40549	40549	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	20433	20433	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1713429248	1713429248	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	2	2	✔
ElecIntTimer_mS_M_u32[0]	2323	2323	✔
ElecIntTimer_mS_M_u32[1]	1713429248	1713429248	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	64711	64711	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	61502	61502	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	190924288	190924288	✔
IgnOnTimer_mS_M_u32	1351222784	1351222784	✔
IgnTimeOff_Sec_M_u32	436383263	436383263	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	183	183	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	346293760	346293760	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	217916928	217916928	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	105	105	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2653308416	2653308416	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3491718656	3491718656	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2084259328	2084259328	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	914466304	914466304	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	105	105	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2062206464	2062206464	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	104	104	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1363699200	1363699200	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	35	35	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3135178240	3135178240	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	86	86	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3065521664	3065521664	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	221	221	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	190924288	190924288	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1608996352	1608996352	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	286.260193	286.260193	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	553.436584	553.436584	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	247.503494	247.503494	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	613.599121	613.599121	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	51712	51712	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	436383263	436383263	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-168.268799	-168.268799 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	22.4486008	22.4486008	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0151	0x0151	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0152	0x0152	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	4	ValidityNTCProcessing	4	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.168 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	417177856
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	17554
AASNodeAbsentTimer_mS_M_u32	2451689728
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	29220
ANGLEVOLANTSigValidCount_Cnt_M_u16	32916
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	61771
AngleVolantMsgTimer_mS_M_u32	417177856
AngleVolantValidCount_Cnt_M_u16	35725
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	652.893188
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3316027648
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	627249408
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3010183424
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1593016576
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	45055
BattOk_Cnt_M_lgc	0

Name	Input Value
CAVNTCEnableTimer_mS_M_u32	1722433792
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	29388
CAVNodeAbsentTimer_mS_M_u32	2914251008
CDD_SrlComVehSpd_Kph_G_f32	582.554199
CMM388NTCEnableTimer_mS_M_u32	3838521600
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1813115136
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	4205
CMMNodeAbsentTimer_mS_M_u32	3574956288
CONSANGLECPKSigInvalidCount_Cnt_M_u16	42629
CONSANGLECPKSigValidCount_Cnt_M_u16	16389
CONSANGLECPK_Cnt_M_u16	61620
CONSANGLECPK_HwDeg_M_f32	684.942688
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	61620
CPKVehicleSpeedMsgTimer_mS_M_u32	2828050688
CPKVehicleSpeedValidCount_Cnt_M_u16	5994
CityParkInputConsistentCount_Cnt_M_u16	5665
CityParkInputInvalidCount_Cnt_M_u16	8774
CityParkInputMsgTimer_mS_M_u32	346293760
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3249918208
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	27942
ComputerRazGCTSigInvalidTimer_mS_M_u32	2331668736
ComputerRazGCTSigValidCount_Cnt_M_u16	38962
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	50098
DMDFCTCPKSigValidCount_Cnt_M_u16	21353
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	8814
DMDRELAXECPKSigValidCount_Cnt_M_u16	46174
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	47166
DateInvalidTimer_mS_M_u32	627249408
DiagMuxOnAbsentTimer_mS_M_u32	1374970112
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1593016576
ESPNTCEnableTimer_mS_M_u32	2267992320
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	34600
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	5
EffacDefaultDiagTimer_mS_M_u32[1]	155
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2323
ElecIntTimer_mS_M_u32[1]	45466
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2111062272
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	56469
EtatMTSigValidCount_Cnt_M_u16	19713
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	46287
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	20943
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	967
ISDAT4V2BSI552MsgTimer_mS_M_u32	1269399808
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	25667
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	1367
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	19713
ISDATBSI3F2MsgTimer_mS_M_u32	2074763520
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	34780
ISDATBSI412MsgLenValidCount_Cnt_M_u16	34144
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	56469
ISDATBSI412MsgTimer_mS_M_u32	278110464
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	3585
ISDATBSI432MsgLenValidCount_Cnt_M_u16	19388
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	52345
ISDATDIRASentFltAcc_Cnt_M_u16	9693
ISDATDIRASentTimer_mS_M_u32	2828050688
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	5866

Name	Input Value
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	35725
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	19725
ISDYN2CMMMsgTimer_mS_M_u32	1607520512
ISDYNAASChkSumInvalidCount_Cnt_M_u16	37084
ISDYNAASChkSumValidCount_Cnt_M_u16	25067
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	58088
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	43707
ISDYNAASMsgLenValidCount_Cnt_M_u16	19170
ISDYNAASMsgTimeValidCount_Cnt_M_u16	37084
ISDYNAASMsgTimer_mS_M_u32	3342283008
ISDYNABRChkSumInvalidCount_Cnt_M_u16	7354
ISDYNABRChkSumValidCount_Cnt_M_u16	14802
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	14519
ISDYNABRMsgCountValidCount_Cnt_M_u16	51206
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	13664
ISDYNABRMsgLenValidCount_Cnt_M_u16	52512
ISDYNABRMsgTimeValidCount_Cnt_M_u16	61620
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	755
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1395
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	19713
ISDYNCMM208MsgTimer_mS_M_u32	4277637376
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2871
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1501
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	40515
ISDYNCMM388MsgTimer_mS_M_u32	335851776
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	10299
ISDYNVOLChkSumValidCount_Cnt_M_u16	48699
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	65535
ISDYNVOLMsgCountValidCount_Cnt_M_u16	435
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	25165
ISDYNVOLMsgLenValidCount_Cnt_M_u16	6445
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	4205
ISDYNVOLMsgTimer_mS_M_u32	694579456
IgnOnTimer_mS_M_u32	1771614464
IgnTimeOff_Sec_M_u32	2702926059
ManVehSpd_Kph_M_f32	253.104202
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	121
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	125
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1147691264
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	113
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	413581568
PrevISDATBSI412MsgDLCError_Cnt_M_u08	142
PrevISDATBSI412MsgRxTime_MSec_M_u32	3743478016
PrevISDATBSI432MsgDLCError_Cnt_M_u08	92
PrevISDATBSI432MsgRxTime_MSec_M_u32	1869795584
PrevISDATDIRAMsgTxTime_MSec_M_u32	998568192
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	110
PrevISDYN2CMMMsgRxTime_MSec_M_u32	969605376
PrevISDYNAASMsgDLCError_Cnt_M_u08	136
PrevISDYNAASMsgRxTime_MSec_M_u32	4154224896
PrevISDYNABRMsgDLCError_Cnt_M_u08	104
PrevISDYNABRMsgRxTime_MSec_M_u32	2775625984
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	90
PrevISDYNCMM208MsgRxTime_MSec_M_u32	544043264
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	165
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3106001152
PrevISDYNVOLMsgDLCError_Cnt_M_u08	129
PrevISDYNVOLMsgRxTime_MSec_M_u32	3756650752
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2135531776
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	44.2355003
PrevVitesseVehicleBVValid_Cnt_M_lgc	0

Name	Input Value
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	8561
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	32280
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	13334
VitesseVehicleBVRampValidCount_Cnt_M_u16	45693
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	38985
VitesseVehicleBVSigValidCount_Cnt_M_u16	26745
VitesseVehicleBV_Kph_M_f32	573.333008
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	40515
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	43979
VitesseVehiculeRoues_Kph_M_f32	613.020996
k_AASNTCEnableTimeout_mS_u16	37287
k_AASNodeAbsentDiag_Cnt_str.Threshold	30724
k_AASNodeAbsentDiag_Cnt_str.PStep	54142
k_AASNodeAbsentDiag_Cnt_str.NStep	34029
k_AASNodeAbsentTimeout_mS_u16	36692
k_AASNodeTimeout_mS_u16	9496
k_ABSNodeTimeout_mS_u16	48579
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	61960
k_ANGLEVOLANTSigValidThresh_Cnt_u16	63235
k_AngleVolantInvalidThresh_Cnt_u16	34310
k_AngleVolantValidThresh_Cnt_u16	8774
k_BSI552MsgTimeout_mS_u16	11406
k_BSINTCEnableTimeout_mS_u16	63961
k_BSINodeAbsentDiag_Cnt_str.Threshold	2722
k_BSINodeAbsentDiag_Cnt_str.PStep	2638
k_BSINodeAbsentDiag_Cnt_str.NStep	15212
k_BSINodeAbsentTimeout_mS_u16	42787
k_BSINodeTimeout_mS_u16	52345
k_BattOvHi_Volt_f32	24.9403992
k_BattOvLo_Volt_f32	8.48659992
k_BattUvHi_Volt_f32	17.2224007
k_BattUvLo_Volt_f32	22.5800991
k_CAVNTCEnableTimeout_mS_u16	54484
k_CAVNodeAbsentDiag_Cnt_str.Threshold	6987
k_CAVNodeAbsentDiag_Cnt_str.PStep	38634
k_CAVNodeAbsentDiag_Cnt_str.NStep	38781
k_CAVNodeAbsentTimeout_mS_u16	43138
k_CAVNodeTimeout_mS_u16	8433
k_CMM388MsgTimeout_mS_u16	11154
k_CMM388NTCEnableTimeout_mS_u16	17150
k_CMMNTCEnableTimeout_mS_u16	64539
k_CMMNodeAbsentDiag_Cnt_str.Threshold	15003
k_CMMNodeAbsentDiag_Cnt_str.PStep	51366
k_CMMNodeAbsentDiag_Cnt_str.NStep	59557
k_CMMNodeAbsentTimeout_mS_u16	41271
k_CONSANGLECPKMax_HwDeg_f32	114.656097
k_CONSANGLECPKMin_HwDeg_f32	-586.599304
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	1347
k_CONSANGLECPKSigValidThresh_Cnt_u16	21195
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	38006
k_CPKVehicleSpeedValidThresh_Cnt_u16	31371
k_CityParkInputInvalidThresh_Cnt_u16	65176
k_CityParkInputValidThresh_Cnt_u16	5665
k_ComputerRazGCTSigValidThresh_Cnt_u16	21889
k_CptTemporelSigValidThresh_Cnt_u16	2325
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	7264
k_DMDFCTCPKSigValidThresh_Cnt_u16	62496
k_DMDFCTCPKValidCount_Cnt_u16	45351
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	19725

Name	Input Value
k_DMDRELAXECPKSigValidThresh_Cnt_u16	47876
k_DMDRelaxeConsistentThresh_Cnt_u16	27746
k_DateValidThresh_Cnt_u16	967
k_DefaultVehSpd_Kph_f32	127.118202
k_DiagMuxOnAbsentTimeout_mS_u16	30402
k_EMNodeTimeout_mS_u16	19998
k_ESPNTCEnableTimeout_mS_u16	1848
k_ESPNodeAbsentDiag_Cnt_str.Threshold	35454
k_ESPNodeAbsentDiag_Cnt_str.PStep	601
k_ESPNodeAbsentDiag_Cnt_str.NStep	63527
k_ESPNodeAbsentTimeout_mS_u16	40287
k_EtatMTSigInvalidThresh_Cnt_u16	2077
k_EtatMTSigValidThresh_Cnt_u16	63861
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	45957
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	53073
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	45766
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	52636
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	61296
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	37744
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	49882
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	8533
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	19349
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	37416
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	39243
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	12617
k_ISDATDIRASentDiag_Cnt_str.Threshold	62208
k_ISDATDIRASentDiag_Cnt_str.PStep	30559
k_ISDATDIRASentDiag_Cnt_str.NStep	53426
k_ISDATDIRASentTimeout_mS_u16	48422
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	34714
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	61771
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	55284
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	33722
k_ISDYNAASChkSumValidThresh_Cnt_u16	57554
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	8119
k_ISDYNAASMsgCountValidThresh_Cnt_u16	61190
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	9038
k_ISDYNAASMsgLenValidThresh_Cnt_u16	42924
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	47403
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	26134
k_ISDYNABRChkSumValidThresh_Cnt_u16	14934
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	38655
k_ISDYNABRMsgCountValidThresh_Cnt_u16	9135
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46957
k_ISDYNABRMsgLenValidThresh_Cnt_u16	28200
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	52210
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	50181
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	29889
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	8411
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	22820
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	42900
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	3102
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	60003
k_ISDYNVOLChkSumValidThresh_Cnt_u16	36647
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	46817
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	51046
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	45569
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	39789
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	21717
k_IgnOnTimeout_mS_u16	61135
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	151.263199
k_PowerCutVehSpdLowThresh_Kph_f32	85.5522995
k_PowerCutVehSpdLowTimeout_mS_u16	58179
k_VBattMaxAAS_Volt_f32	17.7945004
k_VBattMaxBSI_Volt_f32	30.1100998
k_VBattMaxCAV_Volt_f32	25.6394997
k_VBattMaxCMM388_Volt_f32	25.9815998
k_VBattMaxCMM_Volt_f32	10.2073002
k_VBattMaxESP_Volt_f32	32
k_VBattMinAAS_Volt_f32	22.5356998
k_VBattMinBSI_Volt_f32	32
k_VBattMinCAV_Volt_f32	11.2563

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinCMM388_Volt_f32	0.709699988
k_VBattMinCMM_Volt_f32	14.7791996
k_VBattMinESP_Volt_f32	10.2073002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	59196
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	22640
k_VitesseVehicleBVRampValidThresh_Cnt_u16	54120
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	58683
k_VitesseVehicleBVSigValidThresh_Cnt_u16	9374
k_VitesseVehicleBVSpeedPassThresh_kph_f32	280.251007
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	55756
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	21683
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	627249408
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	219
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	165
target_SrlComInput_Per1_Batt_Volt_f32.value	12.5622997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2419540224
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	63
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.781401634
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	175
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	88781056
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1757368576
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1103360256
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2019070208
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4101845248
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2654064896
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1568043264
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	108
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	134
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	177
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	182
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3638399232
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	227
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3197743360
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	395202816
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	129

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2786259200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	145
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	348176640
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2846
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.839858115
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	521657
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	30.7301998
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	19603

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	30724	30724	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	29221	29221	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	61771	61771	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	652.893188	652.893188	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1722433792	1722433792	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	6987	6987	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2654064896	2654064896	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	61620	61620	✔
CONSANGLECPK_HwDeg_M_f32	684.942688	684.942688 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	61620	61620	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2828050688	2828050688	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	5994	5994	✔
CityParkInputConsistentCount_Cnt_M_u16	5665	5665	✔
CityParkInputInvalidCount_Cnt_M_u16	8776	8776	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	5	5	✔
EffacDefaultDiagTimer_mS_M_u32[1]	155	155	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2323	2323	✔
ElecIntTimer_mS_M_u32[1]	45466	45466	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	62208	62208	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	10300	10300	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	65535	65535	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2786259200	2786259200	✔
IgnOnTimer_mS_M_u32	1771614464	1771614464	✔
IgnTimeOff_Sec_M_u32	2702926059	2702926059	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	175	175	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	88781056	88781056	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	174	174	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1757368576	1757368576	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	48	48	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1103360256	1103360256	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	26	26	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2019070208	2019070208	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	998568192	998568192	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	205	205	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2654064896	2654064896	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1568043264	1568043264	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3638399232	3638399232	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3197743360	3197743360	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	395202816	395202816	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	129	129	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2786259200	2786259200	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	348176640	348176640	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	44.2355003	44.2355003	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	573.333008	573.333008	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	613.020996	613.020996	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	652.893188	652.893188	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	61620	61620	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2702926059	2702926059	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	684.942688	684.942688 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	127.118202	127.118202	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0153	0x0153	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	2	ValidityNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	3	ValidityNTCProcessing	3	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.169 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1959387136
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	25516
AASNodeAbsentTimer_mS_M_u32	2512211968
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	17652
ANGLEVOLANTSigValidCount_Cnt_M_u16	46181
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	33153
AngleVolantMsgTimer_mS_M_u32	1959387136
AngleVolantValidCount_Cnt_M_u16	34105
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	524.141663
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	4264497152
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1895403520
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	94339072

Name	Input Value
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3523756032
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	46947
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	98828288
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	59774
CAVNodeAbsentTimer_mS_M_u32	3011964928
CDD_SrlComVehSpd_Kph_G_f32	505.008392
CMM388NTCEnableTimer_mS_M_u32	2067869696
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1886187520
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	91
CMMNodeAbsentTimer_mS_M_u32	2007121920
CONSANGLECPKSigInvalidCount_Cnt_M_u16	6866
CONSANGLECPKSigValidCount_Cnt_M_u16	10515
CONSANGLECPK_Cnt_M_u16	37638
CONSANGLECPK_HwDeg_M_f32	-530.634705
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37638
CPKVehicleSpeedMsgTimer_mS_M_u32	1370546176
CPKVehicleSpeedValidCount_Cnt_M_u16	16171
CityParkInputConsistentCount_Cnt_M_u16	13693
CityParkInputInvalidCount_Cnt_M_u16	61968
CityParkInputMsgTimer_mS_M_u32	88781056
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1459703808
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	14832
ComputerRazGCTSigInvalidTimer_mS_M_u32	1437822976
ComputerRazGCTSigValidCount_Cnt_M_u16	13130
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	48588
DMDFCTCPKSigValidCount_Cnt_M_u16	51557
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56342
DMDRELAXECPKSigValidCount_Cnt_M_u16	49415
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	2471
DateInvalidTimer_mS_M_u32	1895403520
DiagMuxOnAbsentTimer_mS_M_u32	2491785216
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3523756032
ESPNTCEnableTimer_mS_M_u32	714493952
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	26344
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1111
EffacDefaultDiagTimer_mS_M_u32[1]	2222
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	5656
ElecIntTimer_mS_M_u32[1]	78790
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3898998784
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	36066
EtatMTSigValidCount_Cnt_M_u16	50783
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	38900
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	39861
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	45131
ISDAT4V2BSI552MsgTimer_mS_M_u32	1676034048
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	34136
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	52445
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	50783
ISDATBSI3F2MsgTimer_mS_M_u32	1868800000
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	3981
ISDATBSI412MsgLenValidCount_Cnt_M_u16	450
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	36066
ISDATBSI412MsgTimer_mS_M_u32	3852984320
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	22431

Name	Input Value
ISDATBSI432MsgLenValidCount_Cnt_M_u16	26924
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	53367
ISDATDIRASentFltAcc_Cnt_M_u16	21579
ISDATDIRASentTimer_mS_M_u32	1370546176
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	30820
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	34105
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	19899
ISDYN2CMMMsgTimer_mS_M_u32	2830127104
ISDYNAASChkSumInvalidCount_Cnt_M_u16	9934
ISDYNAASChkSumValidCount_Cnt_M_u16	52831
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	43816
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	48561
ISDYNAASMsgLenValidCount_Cnt_M_u16	22521
ISDYNAASMsgTimeValidCount_Cnt_M_u16	9934
ISDYNAASMsgTimer_mS_M_u32	2214408192
ISDYNABRChkSumInvalidCount_Cnt_M_u16	29875
ISDYNABRChkSumValidCount_Cnt_M_u16	22572
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	23357
ISDYNABRMsgCountValidCount_Cnt_M_u16	51214
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	39489
ISDYNABRMsgLenValidCount_Cnt_M_u16	44482
ISDYNABRMsgTimeValidCount_Cnt_M_u16	37638
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	756
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1397
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	50783
ISDYNCMM208MsgTimer_mS_M_u32	3594260480
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2875
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1503
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	42263
ISDYNCMM388MsgTimer_mS_M_u32	3012866048
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	60848
ISDYNVOLChkSumValidCount_Cnt_M_u16	1649
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	7082
ISDYNVOLMsgCountValidCount_Cnt_M_u16	22690
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	43385
ISDYNVOLMsgLenValidCount_Cnt_M_u16	57242
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	91
ISDYNVOLMsgTimer_mS_M_u32	711946240
IgnOnTimer_mS_M_u32	47755264
IgnTimeOff_Sec_M_u32	3162196177
ManVehSpd_Kph_M_f32	500.516113
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	123
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	250
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2368315392
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	230
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2179891200
PrevISDATBSI412MsgDLCError_Cnt_M_u08	160
PrevISDATBSI412MsgRxTime_MSec_M_u32	322957312
PrevISDATBSI432MsgDLCError_Cnt_M_u08	132
PrevISDATBSI432MsgRxTime_MSec_M_u32	2177519616
PrevISDATDIRAMsgTxTime_MSec_M_u32	2383671296
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	144
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4286693376
PrevISDYNAASMsgDLCError_Cnt_M_u08	124
PrevISDYNAASMsgRxTime_MSec_M_u32	399339520
PrevISDYNABRMsgDLCError_Cnt_M_u08	14
PrevISDYNABRMsgRxTime_MSec_M_u32	2941300736
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	88
PrevISDYNCMM208MsgRxTime_MSec_M_u32	559575040
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	25
PrevISDYNCMM388MsgRxTime_MSec_M_u32	549277696
PrevISDYNVOLMsgDLCError_Cnt_M_u08	126

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevISDYNVOLMsgRxTime_MSec_M_u32	1961160704
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4052082688
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	648.327393
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	45455
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	5719
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	19872
VitesseVehicleBVRampValidCount_Cnt_M_u16	19752
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	42629
VitesseVehicleBVSigValidCount_Cnt_M_u16	53430
VitesseVehicleBV_Kph_M_f32	319.874512
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	42263
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	30528
VitesseVehiculeRoues_Kph_M_f32	209.783905
k_AASNTCEnableTimeout_mS_u16	15405
k_AASNodeAbsentDiag_Cnt_str.Threshold	47250
k_AASNodeAbsentDiag_Cnt_str.PStep	51043
k_AASNodeAbsentDiag_Cnt_str.NStep	64455
k_AASNodeAbsentTimeout_mS_u16	21988
k_AASNodeTimeout_mS_u16	8535
k_ABSNodeTimeout_mS_u16	21401
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	34698
k_ANGLEVOLANTSigValidThresh_Cnt_u16	17239
k_AngleVolantInvalidThresh_Cnt_u16	25166
k_AngleVolantValidThresh_Cnt_u16	61968
k_BSI552MsgTimeout_mS_u16	49399
k_BSINTCEnableTimeout_mS_u16	62487
k_BSINodeAbsentDiag_Cnt_str.Threshold	2835
k_BSINodeAbsentDiag_Cnt_str.PStep	2744
k_BSINodeAbsentDiag_Cnt_str.NStep	16054
k_BSINodeAbsentTimeout_mS_u16	49145
k_BSINodeTimeout_mS_u16	53367
k_BattOvHi_Volt_f32	24.4097996
k_BattOvLo_Volt_f32	8.73960018
k_BattUvHi_Volt_f32	18.4281998
k_BattUvLo_Volt_f32	24.0324001
k_CAVNTCEnableTimeout_mS_u16	37478
k_CAVNodeAbsentDiag_Cnt_str.Threshold	44954
k_CAVNodeAbsentDiag_Cnt_str.PStep	32686
k_CAVNodeAbsentDiag_Cnt_str.NStep	7254
k_CAVNodeAbsentTimeout_mS_u16	41052
k_CAVNodeTimeout_mS_u16	23438
k_CMM388MsgTimeout_mS_u16	44716
k_CMM388NTCEnableTimeout_mS_u16	6248
k_CMMNTCEnableTimeout_mS_u16	7632
k_CMMNodeAbsentDiag_Cnt_str.Threshold	13800
k_CMMNodeAbsentDiag_Cnt_str.PStep	35784
k_CMMNodeAbsentDiag_Cnt_str.NStep	9021
k_CMMNodeAbsentTimeout_mS_u16	18172
k_CONSANGLECPKMax_HwDeg_f32	429.056305
k_CONSANGLECPKMin_HwDeg_f32	-505.569
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	28695
k_CONSANGLECPKSigValidThresh_Cnt_u16	33344
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	52029
k_CPKVehicleSpeedValidThresh_Cnt_u16	45952
k_CityParkInputInvalidThresh_Cnt_u16	50969
k_CityParkInputValidThresh_Cnt_u16	13693
k_ComputerRazGCTSigValidThresh_Cnt_u16	10654

Name	Input Value
k_CptTemporelSigValidThresh_Cnt_u16	14755
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	58689
k_DMDFCTCPKSigValidThresh_Cnt_u16	14530
k_DMDFCTCPKValidCount_Cnt_u16	21483
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	19899
k_DMDRELAXECPKSigValidThresh_Cnt_u16	48788
k_DMDRelaxeConsistentThresh_Cnt_u16	41594
k_DateValidThresh_Cnt_u16	45131
k_DefaultVehSpd_Kph_f32	140.531204
k_DiagMuxOnAbsentTimeout_mS_u16	47324
k_EMNodeTimeout_mS_u16	51207
k_ESPNTCEnableTimeout_mS_u16	56378
k_ESPNodeAbsentDiag_Cnt_str.Threshold	8929
k_ESPNodeAbsentDiag_Cnt_str.PStep	12561
k_ESPNodeAbsentDiag_Cnt_str.NStep	52437
k_ESPNodeAbsentTimeout_mS_u16	62084
k_EtatMTSigInvalidThresh_Cnt_u16	65162
k_EtatMTSigValidThresh_Cnt_u16	25923
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	27152
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	8557
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	13198
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	60749
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	45714
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	15569
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	56596
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	35937
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	61155
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	32426
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	54271
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	22597
k_ISDATDIRASentDiag_Cnt_str.Threshold	52471
k_ISDATDIRASentDiag_Cnt_str.PStep	60363
k_ISDATDIRASentDiag_Cnt_str.NStep	42803
k_ISDATDIRASentTimeout_mS_u16	17263
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	55634
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	33153
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	23046
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	16307
k_ISDYNAASChkSumValidThresh_Cnt_u16	25388
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	42557
k_ISDYNAASMsgCountValidThresh_Cnt_u16	21262
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	45303
k_ISDYNAASMsgLenValidThresh_Cnt_u16	59803
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	40159
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	24607
k_ISDYNABRChkSumValidThresh_Cnt_u16	48672
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	611
k_ISDYNABRMsgCountValidThresh_Cnt_u16	63252
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	2907
k_ISDYNABRMsgLenValidThresh_Cnt_u16	45544
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	51787
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	6611
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7390
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	64014
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	36852
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	16229
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	38024
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	50168
k_ISDYNVOLChkSumValidThresh_Cnt_u16	49261
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	64445
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	65392
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	48286
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	35611
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	29985
k_IgnOnTimeout_mS_u16	26292
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	192.596207
k_PowerCutVehSpdLowThresh_Kph_f32	45.7290001
k_PowerCutVehSpdLowTimeout_mS_u16	46937
k_VBattMaxAAS_Volt_f32	24.4612007
k_VBattMaxBSI_Volt_f32	30.8911991
k_VBattMaxCAV_Volt_f32	24.4276009
k_VBattMaxCMM388_Volt_f32	20.5571995

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMaxCMM_Volt_f32	10.2268
k_VBattMaxESP_Volt_f32	15.8892002
k_VBattMinAAS_Volt_f32	9.56089973
k_VBattMinBSI_Volt_f32	15.8892002
k_VBattMinCAV_Volt_f32	2.55629992
k_VBattMinCMM388_Volt_f32	19.3834
k_VBattMinCMM_Volt_f32	20.5841007
k_VBattMinESP_Volt_f32	10.2268
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	49772
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	6545
k_VitesseVehicleBVRampValidThresh_Cnt_u16	59050
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	37233
k_VitesseVehicleBVSigValidThresh_Cnt_u16	15878
k_VitesseVehicleBVSpeedPassThresh_kph_f32	507.527802
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	46206
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	48774
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1895403520
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	229
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8524
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1236548
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	25
target_SrlComInput_Per1_Batt_Volt_f32.value	10.2563
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4248633344
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	4
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0454229452
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2009247744
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1743048704
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	928444416
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	773394432
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2485858304
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	207
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2978828288
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3460263936
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	131
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1619660800
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	36
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	156
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	157
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	184

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1205186560
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1467469824
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	107606016
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1973452800
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2067
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.57820338
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	707305
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	60.4450989
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	14377

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1236548	1236548	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	47250	47250	✔
AASNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	17653	17653	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	33153	33153	✔
AngleVolantMsgTimer_mS_M_u32	1236548	1236548	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	524.141663	524.141663	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1236548	1236548	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	98828288	98828288	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	44954	44954	✔
CAVNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2978828288	2978828288	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	37638	37638	✔
CONSANGLECPK_HwDeg_M_f32	-530.634705	-530.634705 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37638	37638	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1370546176	1370546176	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	16171	16171	✔
CityParkInputConsistentCount_Cnt_M_u16	13693	13693	✔
CityParkInputInvalidCount_Cnt_M_u16	61968	61968	✔
CityParkInputMsgTimer_mS_M_u32	1236548	1236548	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1236548	1236548	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1236548	1236548	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1236548	1236548	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1236548	1236548	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1236548	1236548	✔
ESPNTCEnableTimer_mS_M_u32	1236548	1236548	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1111	1111	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2222	2222	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1236548	1236548	✔
ElecIntTimer_mS_M_u32[1]	78790	78790	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1236548	1236548	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATDIRASentFltAcc_Cnt_M_u16	52471	52471	✔
ISDATDIRASentTimer_mS_M_u32	1236548	1236548	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	60848	60848	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	7083	7083	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	107606016	107606016	✔
IgnOnTimer_mS_M_u32	47755264	47755264	✔
IgnTimeOff_Sec_M_u32	3162196177	3162196177	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2009247744	2009247744	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	192	192	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1743048704	1743048704	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	119	119	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	928444416	928444416	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	49	49	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	773394432	773394432	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2383671296	2383671296	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	207	207	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2978828288	2978828288	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	67	67	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3460263936	3460263936	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1619660800	1619660800	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	141	141	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1205186560	1205186560	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	72	72	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1467469824	1467469824	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	126	126	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	107606016	107606016	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1973452800	1973452800	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	648.327393	648.327393	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	319.874512	319.874512	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	209.783905	209.783905	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	524.141663	524.141663	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	37638	37638	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3162196177	3162196177	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-530.634705	-530.634705 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	140.531204	140.531204	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0152	0x0152	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	4	ValidityNTCProcessing	4	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.170 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	610121216
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	46028
AASNodeAbsentTimer_mS_M_u32	624010752
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	24560
ANGLEVOLANTSigValidCount_Cnt_M_u16	0
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	30265
AngleVolantMsgTimer_mS_M_u32	610121216
AngleVolantValidCount_Cnt_M_u16	3832
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	496.947052

Name	Input Value
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1761961472
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3340494336
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3383645696
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2038502912
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	54439
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3287209472
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	19768
CAVNodeAbsentTimer_mS_M_u32	1691764224
CDD_SrlComVehSpd_Kph_G_f32	16.2320004
CMM388NTCEnableTimer_mS_M_u32	1657701888
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2550941184
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	57752
CMMNodeAbsentTimer_mS_M_u32	885724672
CONSANGLECPKSigInvalidCount_Cnt_M_u16	2256
CONSANGLECPKSigValidCount_Cnt_M_u16	41189
CONSANGLECPK_Cnt_M_u16	51712
CONSANGLECPK_HwDeg_M_f32	-168.268799
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	51712
CPKVehicleSpeedMsgTimer_mS_M_u32	499955200
CPKVehicleSpeedValidCount_Cnt_M_u16	37478
CityParkInputConsistentCount_Cnt_M_u16	26140
CityParkInputInvalidCount_Cnt_M_u16	40549
CityParkInputMsgTimer_mS_M_u32	1133657856
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1163240960
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	33008
ComputerRazGCTSigInvalidTimer_mS_M_u32	3686712832
ComputerRazGCTSigValidCount_Cnt_M_u16	54977
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	58177
DMDFCTCPKSigValidCount_Cnt_M_u16	62447
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	4738
DMDRELAXECPKSigValidCount_Cnt_M_u16	38856
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	21565
DateInvalidTimer_mS_M_u32	3340494336
DiagMuxOnAbsentTimer_mS_M_u32	866874880
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2038502912
ESPNTCEnableTimer_mS_M_u32	4286752256
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	27289
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	2323
ElecIntTimer_mS_M_u32[1]	1713429248
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2128664064
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	40757
EtatMTSigValidCount_Cnt_M_u16	49063
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	61794
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	13047
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	33061
ISDAT4V2BSI552MsgTimer_mS_M_u32	3891205632
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	54225
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	17418
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	49063

Name	Input Value
ISDATBSI3F2MsgTimer_mS_M_u32	3810096640
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	15091
ISDATBSI412MsgLenValidCount_Cnt_M_u16	52316
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	40757
ISDATBSI412MsgTimer_mS_M_u32	969651712
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	26556
ISDATBSI432MsgLenValidCount_Cnt_M_u16	957
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	12457
ISDATDIRASentFltAcc_Cnt_M_u16	733
ISDATDIRASentTimer_mS_M_u32	499955200
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	53230
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	3832
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	59768
ISDYN2CMMMsgTimer_mS_M_u32	4014777856
ISDYNAASChkSumInvalidCount_Cnt_M_u16	12894
ISDYNAASChkSumValidCount_Cnt_M_u16	52547
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	31535
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	40595
ISDYNAASMsgLenValidCount_Cnt_M_u16	38001
ISDYNAASMsgTimeValidCount_Cnt_M_u16	12894
ISDYNAASMsgTimer_mS_M_u32	1017808384
ISDYNABRChkSumInvalidCount_Cnt_M_u16	37780
ISDYNABRChkSumValidCount_Cnt_M_u16	62753
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	55573
ISDYNABRMsgCountValidCount_Cnt_M_u16	57146
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	25223
ISDYNABRMsgLenValidCount_Cnt_M_u16	42460
ISDYNABRMsgTimeValidCount_Cnt_M_u16	51712
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	856
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1489
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	49063
ISDYNCMM208MsgTimer_mS_M_u32	4058670592
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2911
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1521
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	7014
ISDYNCMM388MsgTimer_mS_M_u32	2456159744
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	61502
ISDYNVOLChkSumValidCount_Cnt_M_u16	57043
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	154
ISDYNVOLMsgCountValidCount_Cnt_M_u16	5354
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	17122
ISDYNVOLMsgLenValidCount_Cnt_M_u16	64472
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	57752
ISDYNVOLMsgTimer_mS_M_u32	563791360
IgnOnTimer_mS_M_u32	1351222784
IgnTimeOff_Sec_M_u32	436383263
ManVehSpd_Kph_M_f32	382.217804
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	85
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	124
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3895424512
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	220
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2974111232
PrevISDATBSI412MsgDLCError_Cnt_M_u08	95
PrevISDATBSI412MsgRxTime_MSec_M_u32	2869380608
PrevISDATBSI432MsgDLCError_Cnt_M_u08	17
PrevISDATBSI432MsgRxTime_MSec_M_u32	571909632
PrevISDATDIRAMsgTxTime_MSec_M_u32	2084259328
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	4
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3800995328
PrevISDYNAASMsgDLCError_Cnt_M_u08	18
PrevISDYNAASMsgRxTime_MSec_M_u32	4018718208
PrevISDYNABRMsgDLCError_Cnt_M_u08	222

Name	Input Value
PrevISDYNABRMsgRxTime_MSec_M_u32	2269251072
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	194
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2112734720
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	180
PrevISDYNCMM388MsgRxTime_MSec_M_u32	405906944
PrevISDYNVOLMsgDLCError_Cnt_M_u08	221
PrevISDYNVOLMsgRxTime_MSec_M_u32	1724139008
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3526997504
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	286.260193
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57089
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	60255
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	42186
VitesseVehicleBVRampValidCount_Cnt_M_u16	42472
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	7993
VitesseVehicleBVSigValidCount_Cnt_M_u16	36799
VitesseVehicleBV_Kph_M_f32	553.436584
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	7014
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	49699
VitesseVehiculeRoues_Kph_M_f32	247.503494
k_AASNTCEnableTimeout_mS_u16	48559
k_AASNodeAbsentDiag_Cnt_str.Threshold	5734
k_AASNodeAbsentDiag_Cnt_str.PStep	31939
k_AASNodeAbsentDiag_Cnt_str.NStep	31892
k_AASNodeAbsentTimeout_mS_u16	26379
k_AASNodeTimeout_mS_u16	24159
k_ABSNodeTimeout_mS_u16	11238
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	29967
k_ANGLEVOLANTSigValidThresh_Cnt_u16	31056
k_AngleVolantInvalidThresh_Cnt_u16	34895
k_AngleVolantValidThresh_Cnt_u16	40549
k_BSI552MsgTimeout_mS_u16	54754
k_BSINTCEnableTimeout_mS_u16	3700
k_BSINodeAbsentDiag_Cnt_str.Threshold	3287
k_BSINodeAbsentDiag_Cnt_str.PStep	3168
k_BSINodeAbsentDiag_Cnt_str.NStep	19422
k_BSINodeAbsentTimeout_mS_u16	12017
k_BSINodeTimeout_mS_u16	12457
k_BattOvHi_Volt_f32	31.5
k_BattOvLo_Volt_f32	23.406601
k_BattUvHi_Volt_f32	16.5062008
k_BattUvLo_Volt_f32	19.5340004
k_CAVNTCEnableTimeout_mS_u16	5515
k_CAVNodeAbsentDiag_Cnt_str.Threshold	60936
k_CAVNodeAbsentDiag_Cnt_str.PStep	27145
k_CAVNodeAbsentDiag_Cnt_str.NStep	20094
k_CAVNodeAbsentTimeout_mS_u16	63654
k_CAVNodeTimeout_mS_u16	23212
k_CMM388MsgTimeout_mS_u16	26316
k_CMM388NTCEnableTimeout_mS_u16	55720
k_CMMNTCEnableTimeout_mS_u16	38537
k_CMMNodeAbsentDiag_Cnt_str.Threshold	26470
k_CMMNodeAbsentDiag_Cnt_str.PStep	38483
k_CMMNodeAbsentDiag_Cnt_str.NStep	6835
k_CMMNodeAbsentTimeout_mS_u16	60159
k_CONSANGLECPKMax_HwDeg_f32	771.218628
k_CONSANGLECPKMin_HwDeg_f32	-391.208313
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	20070

Name	Input Value
k_CONSANGLECPKSigValidThresh_Cnt_u16	13603
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	22165
k_CPKVehicleSpeedValidThresh_Cnt_u16	19982
k_CityParkInputInvalidThresh_Cnt_u16	4170
k_CityParkInputValidThresh_Cnt_u16	26140
k_ComputerRazGCTSigValidThresh_Cnt_u16	52071
k_CptTemporelSigValidThresh_Cnt_u16	57376
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	5511
k_DMDFCTCPKSigValidThresh_Cnt_u16	39132
k_DMDFCTCPKValidCount_Cnt_u16	57071
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	59768
k_DMDRELAXECPKSigValidThresh_Cnt_u16	1382
k_DMDRelaxeConsistentThresh_Cnt_u16	59292
k_DateValidThresh_Cnt_u16	33061
k_DefaultVehSpd_Kph_f32	22.4486008
k_DiagMuxOnAbsentTimeout_mS_u16	64166
k_EMNodeTimeout_mS_u16	63389
k_ESPNTCEnableTimeout_mS_u16	16660
k_ESPNodeAbsentDiag_Cnt_str.Threshold	20433
k_ESPNodeAbsentDiag_Cnt_str.PStep	13965
k_ESPNodeAbsentDiag_Cnt_str.NStep	57022
k_ESPNodeAbsentTimeout_mS_u16	19527
k_EtatMTSigInvalidThresh_Cnt_u16	44659
k_EtatMTSigValidThresh_Cnt_u16	51520
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	34192
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	60641
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	64997
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	55134
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	51031
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	26391
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	64713
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	14474
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	11744
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	39300
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	64782
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	42361
k_ISDATDIRASentDiag_Cnt_str.Threshold	64711
k_ISDATDIRASentDiag_Cnt_str.PStep	35441
k_ISDATDIRASentDiag_Cnt_str.NStep	35487
k_ISDATDIRASentTimeout_mS_u16	33648
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	53086
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	30265
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	35712
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	50836
k_ISDYNAASChkSumValidThresh_Cnt_u16	26657
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	35861
k_ISDYNAASMsgCountValidThresh_Cnt_u16	53818
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	5816
k_ISDYNAASMsgLenValidThresh_Cnt_u16	3459
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39064
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	25845
k_ISDYNABRChkSumValidThresh_Cnt_u16	16074
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	34727
k_ISDYNABRMsgCountValidThresh_Cnt_u16	3757
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	21656
k_ISDYNABRMsgLenValidThresh_Cnt_u16	7577
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	49132
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	11813
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	47100
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	18718
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	4848
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	44726
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	39709
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	51398
k_ISDYNVOLChkSumValidThresh_Cnt_u16	8815
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	44038
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	19269
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	10257
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	30083
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	6347
k_IgnOnTimeout_mS_u16	60578
k_JDD2010Selected_Cnt_Igc	0
k_PowerCutVehSpdHighThresh_Kph_f32	85.9001999

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_PowerCutVehSpdLowThresh_Kph_f32	174.470596
k_PowerCutVehSpdLowTimeout_mS_u16	45691
k_VBattMaxAAS_Volt_f32	15.9166002
k_VBattMaxBSI_Volt_f32	25.3250008
k_VBattMaxCAV_Volt_f32	5.37830019
k_VBattMaxCMM388_Volt_f32	7.22559977
k_VBattMaxCMM_Volt_f32	4.22300005
k_VBattMaxESP_Volt_f32	25.4843006
k_VBattMinAAS_Volt_f32	3.41140008
k_VBattMinBSI_Volt_f32	25.4843006
k_VBattMinCAV_Volt_f32	2.59629989
k_VBattMinCMM388_Volt_f32	31.5373001
k_VBattMinCMM_Volt_f32	0.0241999999
k_VBattMinESP_Volt_f32	4.22300005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	37416
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	15618
k_VitesseVehicleBVRampValidThresh_Cnt_u16	61615
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	53715
k_VitesseVehicleBVSigValidThresh_Cnt_u16	8861
k_VitesseVehicleBVSpeedPassThresh_kph_f32	363.340912
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	32824
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	55254
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3340494336
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	145
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	180
target_SrlComInput_Per1_Batt_Volt_f32.value	3.25600004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2361382400
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	23
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0361702926
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	346293760
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	217916928
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2653308416
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3491718656
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2867365376
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	914466304
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2062206464
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	42
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	82
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	163
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	186
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	204
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1363699200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	35

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	39
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	161
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	228
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3135178240
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3065521664
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	190924288
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	155
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	240
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1608996352
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2946
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.592304766
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	819942
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	67.1612015
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	45899

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	5734	5734	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	24561	24561	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	30267	30267	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	496.947052	496.947052	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	3287	3287	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3287209472	3287209472	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	60936	60936	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	26470	26470	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	51712	51712	✔
CONSANGLECPK_HwDeg_M_f32	-168.268799	-168.268799 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CPKVehicleSpeedInvalidCount_Cnt_M_u16	51712	51712	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	499955200	499955200	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	37478	37478	✔
CityParkInputConsistentCount_Cnt_M_u16	26140	26140	✔
CityParkInputInvalidCount_Cnt_M_u16	40549	40549	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	20433	20433	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1713429248	1713429248	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	2	2	✔
ElecIntTimer_mS_M_u32[0]	2323	2323	✔
ElecIntTimer_mS_M_u32[1]	1713429248	1713429248	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	64711	64711	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	61502	61502	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	155	155	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	190924288	190924288	✔
IgnOnTimer_mS_M_u32	1351222784	1351222784	✔
IgnTimeOff_Sec_M_u32	436383263	436383263	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	183	183	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	346293760	346293760	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	217916928	217916928	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	105	105	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2653308416	2653308416	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3491718656	3491718656	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2084259328	2084259328	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	914466304	914466304	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	105	105	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2062206464	2062206464	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	104	104	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1363699200	1363699200	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	35	35	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3135178240	3135178240	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	86	86	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3065521664	3065521664	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	221	221	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	190924288	190924288	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1608996352	1608996352	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	286.260193	286.260193	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	553.436584	553.436584	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	247.503494	247.503494	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	496.947052	496.947052	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	51712	51712	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	436383263	436383263	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-168.268799	-168.268799 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	22.4486008	22.4486008	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0151	0x0151	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0152	0x0152	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	4	ValidityNTCProcessing	4	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.171 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	417177856
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	17554
AASNodeAbsentTimer_mS_M_u32	2451689728
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	29220
ANGLEVOLANTSigValidCount_Cnt_M_u16	65535

Name	Input Value
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	61771
AngleVolantMsgTimer_mS_M_u32	417177856
AngleVolantValidCount_Cnt_M_u16	35725
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	741.504028
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3316027648
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	627249408
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3010183424
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1593016576
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	45055
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1722433792
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	29388
CAVNodeAbsentTimer_mS_M_u32	2914251008
CDD_SrlComVehSpd_Kph_G_f32	582.554199
CMM388NTCEnableTimer_mS_M_u32	3838521600
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1813115136
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	4205
CMMNodeAbsentTimer_mS_M_u32	3574956288
CONSANGLECPKSigInvalidCount_Cnt_M_u16	42629
CONSANGLECPKSigValidCount_Cnt_M_u16	16389
CONSANGLECPK_Cnt_M_u16	61620
CONSANGLECPK_HwDeg_M_f32	684.942688
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	61620
CPKVehicleSpeedMsgTimer_mS_M_u32	2828050688
CPKVehicleSpeedValidCount_Cnt_M_u16	5994
CityParkInputConsistentCount_Cnt_M_u16	5665
CityParkInputInvalidCount_Cnt_M_u16	8774
CityParkInputMsgTimer_mS_M_u32	346293760
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3249918208
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	27942
ComputerRazGCTSigInvalidTimer_mS_M_u32	2331668736
ComputerRazGCTSigValidCount_Cnt_M_u16	38962
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	50098
DMDFCTCPKSigValidCount_Cnt_M_u16	21353
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	8814
DMDRELAXECPKSigValidCount_Cnt_M_u16	46174
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	47166
DateInvalidTimer_mS_M_u32	627249408
DiagMuxOnAbsentTimer_mS_M_u32	1374970112
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1593016576
ESPNTCEnableTimer_mS_M_u32	2267992320
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	34600
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	5
EffacDefaultDiagTimer_mS_M_u32[1]	155
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2323
ElecIntTimer_mS_M_u32[1]	45466
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2111062272
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	56469
EtatMTSigValidCount_Cnt_M_u16	19713
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	46287

Name	Input Value
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	20943
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	967
ISDAT4V2BSI552MsgTimer_mS_M_u32	1269399808
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	25667
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	1367
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	19713
ISDATBSI3F2MsgTimer_mS_M_u32	2074763520
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	34780
ISDATBSI412MsgLenValidCount_Cnt_M_u16	34144
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	56469
ISDATBSI412MsgTimer_mS_M_u32	278110464
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	3585
ISDATBSI432MsgLenValidCount_Cnt_M_u16	19388
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	52345
ISDATDIRASentFltAcc_Cnt_M_u16	9693
ISDATDIRASentTimer_mS_M_u32	2828050688
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	5866
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	35725
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	19725
ISDYN2CMMMsgTimer_mS_M_u32	1607520512
ISDYNAASChkSumInvalidCount_Cnt_M_u16	37084
ISDYNAASChkSumValidCount_Cnt_M_u16	25067
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	58088
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	43707
ISDYNAASMsgLenValidCount_Cnt_M_u16	19170
ISDYNAASMsgTimeValidCount_Cnt_M_u16	37084
ISDYNAASMsgTimer_mS_M_u32	3342283008
ISDYNABRChkSumInvalidCount_Cnt_M_u16	7354
ISDYNABRChkSumValidCount_Cnt_M_u16	14802
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	14519
ISDYNABRMsgCountValidCount_Cnt_M_u16	51206
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	13664
ISDYNABRMsgLenValidCount_Cnt_M_u16	52512
ISDYNABRMsgTimeValidCount_Cnt_M_u16	61620
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	755
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1395
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	19713
ISDYNCMM208MsgTimer_mS_M_u32	4277637376
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2871
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1501
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	40515
ISDYNCMM388MsgTimer_mS_M_u32	335851776
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	10299
ISDYNVOLChkSumValidCount_Cnt_M_u16	48699
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	4436
ISDYNVOLMsgCountValidCount_Cnt_M_u16	435
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	25165
ISDYNVOLMsgLenValidCount_Cnt_M_u16	6445
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	4205
ISDYNVOLMsgTimer_mS_M_u32	694579456
IgnOnTimer_mS_M_u32	1771614464
IgnTimeOff_Sec_M_u32	2702926059
ManVehSpd_Kph_M_f32	253.104202
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	121
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	125
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1147691264
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	113
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	413581568
PrevISDATBSI412MsgDLCError_Cnt_M_u08	142
PrevISDATBSI412MsgRxTime_MSec_M_u32	3743478016
PrevISDATBSI432MsgDLCError_Cnt_M_u08	92
PrevISDATBSI432MsgRxTime_MSec_M_u32	1869795584

Name	Input Value
PrevISDATDIRAMsgTxTime_MSec_M_u32	998568192
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	110
PrevISDYN2CMMMsgRxTime_MSec_M_u32	969605376
PrevISDYNAASMsgDLCError_Cnt_M_u08	136
PrevISDYNAASMsgRxTime_MSec_M_u32	4154224896
PrevISDYNABRMsgDLCError_Cnt_M_u08	104
PrevISDYNABRMsgRxTime_MSec_M_u32	2775625984
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	90
PrevISDYNCMM208MsgRxTime_MSec_M_u32	544043264
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	165
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3106001152
PrevISDYNVOLMsgDLCError_Cnt_M_u08	129
PrevISDYNVOLMsgRxTime_MSec_M_u32	3756650752
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2135531776
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	44.2355003
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	8561
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	32280
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	13334
VitesseVehicleBVRampValidCount_Cnt_M_u16	45693
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	38985
VitesseVehicleBVSigValidCount_Cnt_M_u16	26745
VitesseVehicleBV_Kph_M_f32	573.333008
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	40515
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	43979
VitesseVehiculeRoues_Kph_M_f32	613.020996
k_AASNTCEnableTimeout_mS_u16	37287
k_AASNodeAbsentDiag_Cnt_str.Threshold	30724
k_AASNodeAbsentDiag_Cnt_str.PStep	54142
k_AASNodeAbsentDiag_Cnt_str.NStep	34029
k_AASNodeAbsentTimeout_mS_u16	36692
k_AASNodeTimeout_mS_u16	9496
k_ABSNodeTimeout_mS_u16	48579
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	61960
k_ANGLEVOLANTSigValidThresh_Cnt_u16	63235
k_AngleVolantInvalidThresh_Cnt_u16	34310
k_AngleVolantValidThresh_Cnt_u16	8774
k_BSI552MsgTimeout_mS_u16	11406
k_BSINTCEnableTimeout_mS_u16	63961
k_BSINodeAbsentDiag_Cnt_str.Threshold	2722
k_BSINodeAbsentDiag_Cnt_str.PStep	2638
k_BSINodeAbsentDiag_Cnt_str.NStep	15212
k_BSINodeAbsentTimeout_mS_u16	42787
k_BSINodeTimeout_mS_u16	52345
k_BattOvHi_Volt_f32	24.9403992
k_BattOvLo_Volt_f32	8.48659992
k_BattUvHi_Volt_f32	17.2224007
k_BattUvLo_Volt_f32	22.5800991
k_CAVNTCEnableTimeout_mS_u16	54484
k_CAVNodeAbsentDiag_Cnt_str.Threshold	6987
k_CAVNodeAbsentDiag_Cnt_str.PStep	38634
k_CAVNodeAbsentDiag_Cnt_str.NStep	38781
k_CAVNodeAbsentTimeout_mS_u16	43138
k_CAVNodeTimeout_mS_u16	8433
k_CMM388MsgTimeout_mS_u16	11154
k_CMM388NTCEnableTimeout_mS_u16	17150
k_CMMNTCEnableTimeout_mS_u16	64539
k_CMMNodeAbsentDiag_Cnt_str.Threshold	15003

Name	Input Value
k_CMMNodeAbsentDiag_Cnt_str.PStep	51366
k_CMMNodeAbsentDiag_Cnt_str.NStep	59557
k_CMMNodeAbsentTimeout_mS_u16	41271
k_CONSANGLECPKMax_HwDeg_f32	114.656097
k_CONSANGLECPKMin_HwDeg_f32	-586.599304
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	1347
k_CONSANGLECPKSigValidThresh_Cnt_u16	21195
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	38006
k_CPKVehicleSpeedValidThresh_Cnt_u16	31371
k_CityParkInputInvalidThresh_Cnt_u16	65176
k_CityParkInputValidThresh_Cnt_u16	5665
k_ComputerRazGCTSigValidThresh_Cnt_u16	21889
k_CptTemporelSigValidThresh_Cnt_u16	2325
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	7264
k_DMDFCTCPKSigValidThresh_Cnt_u16	62496
k_DMDFCTCPKValidCount_Cnt_u16	45351
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	19725
k_DMDRELAXECPKSigValidThresh_Cnt_u16	47876
k_DMDRelaxeConsistentThresh_Cnt_u16	27746
k_DateValidThresh_Cnt_u16	967
k_DefaultVehSpd_Kph_f32	127.118202
k_DiagMuxOnAbsentTimeout_mS_u16	30402
k_EMNodeTimeout_mS_u16	19998
k_ESPNTCEnableTimeout_mS_u16	1848
k_ESPNodeAbsentDiag_Cnt_str.Threshold	35454
k_ESPNodeAbsentDiag_Cnt_str.PStep	601
k_ESPNodeAbsentDiag_Cnt_str.NStep	63527
k_ESPNodeAbsentTimeout_mS_u16	40287
k_EtatMTSigInvalidThresh_Cnt_u16	2077
k_EtatMTSigValidThresh_Cnt_u16	63861
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	45957
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	53073
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	45766
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	52636
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	61296
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	37744
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	49882
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	8533
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	19349
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	37416
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	39243
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	12617
k_ISDATDIRASentDiag_Cnt_str.Threshold	62208
k_ISDATDIRASentDiag_Cnt_str.PStep	30559
k_ISDATDIRASentDiag_Cnt_str.NStep	53426
k_ISDATDIRASentTimeout_mS_u16	48422
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	34714
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	61771
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	55284
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	33722
k_ISDYNAASChkSumValidThresh_Cnt_u16	57554
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	8119
k_ISDYNAASMsgCountValidThresh_Cnt_u16	61190
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	9038
k_ISDYNAASMsgLenValidThresh_Cnt_u16	42924
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	47403
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	26134
k_ISDYNABRChkSumValidThresh_Cnt_u16	14934
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	38655
k_ISDYNABRMsgCountValidThresh_Cnt_u16	9135
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46957
k_ISDYNABRMsgLenValidThresh_Cnt_u16	28200
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	52210
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	50181
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	29889
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	8411
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	22820
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	42900
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	3102
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	60003
k_ISDYNVOLChkSumValidThresh_Cnt_u16	36647
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	46817
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	51046

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	45569
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	39789
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	21717
k_IgnOnTimeout_mS_u16	61135
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	151.263199
k_PowerCutVehSpdLowThresh_Kph_f32	85.5522995
k_PowerCutVehSpdLowTimeout_mS_u16	58179
k_VBattMaxAAS_Volt_f32	17.7945004
k_VBattMaxBSI_Volt_f32	30.1100998
k_VBattMaxCAV_Volt_f32	25.6394997
k_VBattMaxCMM388_Volt_f32	25.9815998
k_VBattMaxCMM_Volt_f32	10.2073002
k_VBattMaxESP_Volt_f32	32
k_VBattMinAAS_Volt_f32	22.5356998
k_VBattMinBSI_Volt_f32	32
k_VBattMinCAV_Volt_f32	11.2563
k_VBattMinCMM388_Volt_f32	0.709699988
k_VBattMinCMM_Volt_f32	14.7791996
k_VBattMinESP_Volt_f32	10.2073002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	59196
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	22640
k_VitesseVehicleBVRampValidThresh_Cnt_u16	54120
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	58683
k_VitesseVehicleBVSigValidThresh_Cnt_u16	9374
k_VitesseVehicleBVSpeedPassThresh_kph_f32	280.251007
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	55756
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	21683
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	627249408
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	219
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16 Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target Rte Inst Ap SrlComInput.SrlComInput Per1 ISDATBSI432MsgDLCError C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	165
target_SrlComInput_Per1_Batt_Volt_f32.value	12.5622997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2419540224
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	63
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.781401634
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	175
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	88781056
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1757368576
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1103360256
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2019070208
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4101845248
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2654064896
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1568043264
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	108
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	134
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	165

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	177
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	182
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3638399232
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	227
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3197743360
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	395202816
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2786259200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	145
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	348176640
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	741
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.839858115
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	267401
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	30.7301998
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	19603

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	30724	30724	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	29221	29221	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	61771	61771	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	741.504028	741.504028	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1722433792	1722433792	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	6987	6987	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CMMNodeAbsentTimer_mS_M_u32	2654064896	2654064896	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	61620	61620	✔
CONSANGLECPK_HwDeg_M_f32	684.942688	684.942688 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	61620	61620	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2828050688	2828050688	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	5994	5994	✔
CityParkInputConsistentCount_Cnt_M_u16	5665	5665	✔
CityParkInputInvalidCount_Cnt_M_u16	8776	8776	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	5	5	✔
EffacDefaultDiagTimer_mS_M_u32[1]	155	155	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2323	2323	✔
ElecIntTimer_mS_M_u32[1]	45466	45466	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	62208	62208	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	10300	10300	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	4437	4437	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2786259200	2786259200	✔
IgnOnTimer_mS_M_u32	1771614464	1771614464	✔
IgnTimeOff_Sec_M_u32	2702926059	2702926059	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	175	175	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	88781056	88781056	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	174	174	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1757368576	1757368576	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	48	48	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1103360256	1103360256	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	26	26	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2019070208	2019070208	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	998568192	998568192	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	205	205	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2654064896	2654064896	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1568043264	1568043264	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3638399232	3638399232	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3197743360	3197743360	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	395202816	395202816	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	129	129	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2786259200	2786259200	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	348176640	348176640	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	44.2355003	44.2355003	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	573.333008	573.333008	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	613.020996	613.020996	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	741.504028	741.504028	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	61620	61620	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2702926059	2702926059	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	684.942688	684.942688 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	127.118202	127.118202	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	5	ValidityNTCProcessing	5	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.172 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1959387136
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	25516
AASNodeAbsentTimer_mS_M_u32	2512211968
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	17652
ANGLEVOLANTSigValidCount_Cnt_M_u16	46181

Name	Input Value
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	33153
AngleVolantMsgTimer_mS_M_u32	1959387136
AngleVolantValidCount_Cnt_M_u16	34105
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	674.683228
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	4264497152
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1895403520
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	94339072
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3523756032
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	46947
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	98828288
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	59774
CAVNodeAbsentTimer_mS_M_u32	3011964928
CDD_SrlComVehSpd_Kph_G_f32	505.008392
CMM388NTCEnableTimer_mS_M_u32	2067869696
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1886187520
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	91
CMMNodeAbsentTimer_mS_M_u32	2007121920
CONSANGLECPKSigInvalidCount_Cnt_M_u16	6866
CONSANGLECPKSigValidCount_Cnt_M_u16	10515
CONSANGLECPK_Cnt_M_u16	37638
CONSANGLECPK_HwDeg_M_f32	-530.634705
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37638
CPKVehicleSpeedMsgTimer_mS_M_u32	1370546176
CPKVehicleSpeedValidCount_Cnt_M_u16	16171
CityParkInputConsistentCount_Cnt_M_u16	13693
CityParkInputInvalidCount_Cnt_M_u16	61968
CityParkInputMsgTimer_mS_M_u32	88781056
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1459703808
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	14832
ComputerRazGCTSigInvalidTimer_mS_M_u32	1437822976
ComputerRazGCTSigValidCount_Cnt_M_u16	13130
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	48588
DMDFCTCPKSigValidCount_Cnt_M_u16	51557
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56342
DMDRELAXECPKSigValidCount_Cnt_M_u16	49415
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	2471
DateInvalidTimer_mS_M_u32	1895403520
DiagMuxOnAbsentTimer_mS_M_u32	2491785216
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3523756032
ESPNTCEnableTimer_mS_M_u32	714493952
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	26344
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1111
EffacDefaultDiagTimer_mS_M_u32[1]	2222
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	5656
ElecIntTimer_mS_M_u32[1]	78790
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3898998784
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	36066
EtatMTSigValidCount_Cnt_M_u16	50783
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	38900

Name	Input Value
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	39861
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	45131
ISDAT4V2BSI552MsgTimer_mS_M_u32	1676034048
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	34136
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	52445
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	50783
ISDATBSI3F2MsgTimer_mS_M_u32	1868800000
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	3981
ISDATBSI412MsgLenValidCount_Cnt_M_u16	450
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	36066
ISDATBSI412MsgTimer_mS_M_u32	3852984320
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	22431
ISDATBSI432MsgLenValidCount_Cnt_M_u16	26924
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	53367
ISDATDIRASentFltAcc_Cnt_M_u16	21579
ISDATDIRASentTimer_mS_M_u32	1370546176
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	30820
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	34105
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	19899
ISDYN2CMMMsgTimer_mS_M_u32	2830127104
ISDYNAASChkSumInvalidCount_Cnt_M_u16	9934
ISDYNAASChkSumValidCount_Cnt_M_u16	52831
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	43816
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	48561
ISDYNAASMsgLenValidCount_Cnt_M_u16	22521
ISDYNAASMsgTimeValidCount_Cnt_M_u16	9934
ISDYNAASMsgTimer_mS_M_u32	2214408192
ISDYNABRChkSumInvalidCount_Cnt_M_u16	29875
ISDYNABRChkSumValidCount_Cnt_M_u16	22572
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	23357
ISDYNABRMsgCountValidCount_Cnt_M_u16	51214
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	39489
ISDYNABRMsgLenValidCount_Cnt_M_u16	44482
ISDYNABRMsgTimeValidCount_Cnt_M_u16	37638
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	756
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1397
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	50783
ISDYNCMM208MsgTimer_mS_M_u32	3594260480
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2875
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1503
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	42263
ISDYNCMM388MsgTimer_mS_M_u32	3012866048
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	60848
ISDYNVOLChkSumValidCount_Cnt_M_u16	1649
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	7082
ISDYNVOLMsgCountValidCount_Cnt_M_u16	22690
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	43385
ISDYNVOLMsgLenValidCount_Cnt_M_u16	57242
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	91
ISDYNVOLMsgTimer_mS_M_u32	711946240
IgnOnTimer_mS_M_u32	47755264
IgnTimeOff_Sec_M_u32	3162196177
ManVehSpd_Kph_M_f32	500.516113
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	123
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	250
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2368315392
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	230
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2179891200
PrevISDATBSI412MsgDLCError_Cnt_M_u08	160
PrevISDATBSI412MsgRxTime_MSec_M_u32	322957312
PrevISDATBSI432MsgDLCError_Cnt_M_u08	132
PrevISDATBSI432MsgRxTime_MSec_M_u32	2177519616

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevISDATDIRAMsgTxTime_MSec_M_u32	2383671296
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	144
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4286693376
PrevISDYNAASMsgDLCError_Cnt_M_u08	124
PrevISDYNAASMsgRxTime_MSec_M_u32	399339520
PrevISDYNABRMsgDLCError_Cnt_M_u08	14
PrevISDYNABRMsgRxTime_MSec_M_u32	2941300736
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	88
PrevISDYNCMM208MsgRxTime_MSec_M_u32	559575040
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	25
PrevISDYNCMM388MsgRxTime_MSec_M_u32	549277696
PrevISDYNVOLMsgDLCError_Cnt_M_u08	126
PrevISDYNVOLMsgRxTime_MSec_M_u32	1961160704
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4052082688
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	648.327393
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	45455
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	5719
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	19872
VitesseVehicleBVRampValidCount_Cnt_M_u16	19752
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	42629
VitesseVehicleBVSigValidCount_Cnt_M_u16	53430
VitesseVehicleBV_Kph_M_f32	319.874512
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	42263
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	30528
VitesseVehiculeRoues_Kph_M_f32	209.783905
k_AASNTCEnableTimeout_mS_u16	15405
k_AASNodeAbsentDiag_Cnt_str.Threshold	47250
k_AASNodeAbsentDiag_Cnt_str.PStep	51043
k_AASNodeAbsentDiag_Cnt_str.NStep	64455
k_AASNodeAbsentTimeout_mS_u16	21988
k_AASNodeTimeout_mS_u16	8535
k_ABSNodeTimeout_mS_u16	21401
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	34698
k_ANGLEVOLANTSigValidThresh_Cnt_u16	17239
k_AngleVolantInvalidThresh_Cnt_u16	25166
k_AngleVolantValidThresh_Cnt_u16	61968
k_BSI552MsgTimeout_mS_u16	49399
k_BSINTCEnableTimeout_mS_u16	62487
k_BSINodeAbsentDiag_Cnt_str.Threshold	2835
k_BSINodeAbsentDiag_Cnt_str.PStep	2744
k_BSINodeAbsentDiag_Cnt_str.NStep	16054
k_BSINodeAbsentTimeout_mS_u16	49145
k_BSINodeTimeout_mS_u16	53367
k_BattOvHi_Volt_f32	24.4097996
k_BattOvLo_Volt_f32	8.73960018
k_BattUvHi_Volt_f32	18.4281998
k_BattUvLo_Volt_f32	24.0324001
k_CAVNTCEnableTimeout_mS_u16	37478
k_CAVNodeAbsentDiag_Cnt_str.Threshold	44954
k_CAVNodeAbsentDiag_Cnt_str.PStep	32686
k_CAVNodeAbsentDiag_Cnt_str.NStep	7254
k_CAVNodeAbsentTimeout_mS_u16	41052
k_CAVNodeTimeout_mS_u16	23438
k_CMM388MsgTimeout_mS_u16	44716
k_CMM388NTCEnableTimeout_mS_u16	6248
k_CMMNTCEnableTimeout_mS_u16	7632
k_CMMNodeAbsentDiag_Cnt_str.Threshold	13800

Name	Input Value
k_CMMNodeAbsentDiag_Cnt_str.PStep	35784
k_CMMNodeAbsentDiag_Cnt_str.NStep	9021
k_CMMNodeAbsentTimeout_mS_u16	18172
k_CONSANGLECPKMax_HwDeg_f32	429.056305
k_CONSANGLECPKMin_HwDeg_f32	-505.569
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	28695
k_CONSANGLECPKSigValidThresh_Cnt_u16	33344
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	52029
k_CPKVehicleSpeedValidThresh_Cnt_u16	45952
k_CityParkInputInvalidThresh_Cnt_u16	50969
k_CityParkInputValidThresh_Cnt_u16	13693
k_ComputerRazGCTSigValidThresh_Cnt_u16	10654
k_CptTemporelSigValidThresh_Cnt_u16	14755
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	58689
k_DMDFCTCPKSigValidThresh_Cnt_u16	14530
k_DMDFCTCPKValidCount_Cnt_u16	21483
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	19899
k_DMDRELAXECPKSigValidThresh_Cnt_u16	48788
k_DMDRelaxeConsistentThresh_Cnt_u16	41594
k_DateValidThresh_Cnt_u16	45131
k_DefaultVehSpd_Kph_f32	140.531204
k_DiagMuxOnAbsentTimeout_mS_u16	47324
k_EMNodeTimeout_mS_u16	51207
k_ESPNTCEnableTimeout_mS_u16	56378
k_ESPNodeAbsentDiag_Cnt_str.Threshold	8929
k_ESPNodeAbsentDiag_Cnt_str.PStep	12561
k_ESPNodeAbsentDiag_Cnt_str.NStep	52437
k_ESPNodeAbsentTimeout_mS_u16	62084
k_EtatMTSigInvalidThresh_Cnt_u16	65162
k_EtatMTSigValidThresh_Cnt_u16	25923
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	27152
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	8557
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	13198
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	60749
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	45714
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	15569
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	56596
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	35937
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	61155
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	32426
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	54271
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	22597
k_ISDATDIRASentDiag_Cnt_str.Threshold	52471
k_ISDATDIRASentDiag_Cnt_str.PStep	60363
k_ISDATDIRASentDiag_Cnt_str.NStep	42803
k_ISDATDIRASentTimeout_mS_u16	17263
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	55634
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	33153
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	23046
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	16307
k_ISDYNAASChkSumValidThresh_Cnt_u16	25388
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	42557
k_ISDYNAASMsgCountValidThresh_Cnt_u16	21262
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	45303
k_ISDYNAASMsgLenValidThresh_Cnt_u16	59803
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	40159
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	24607
k_ISDYNABRChkSumValidThresh_Cnt_u16	48672
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	611
k_ISDYNABRMsgCountValidThresh_Cnt_u16	63252
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	2907
k_ISDYNABRMsgLenValidThresh_Cnt_u16	45544
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	51787
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	6611
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7390
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	64014
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	36852
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	16229
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	38024
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	50168
k_ISDYNVOLChkSumValidThresh_Cnt_u16	49261
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	64445
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	65392

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	48286
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	35611
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	29985
k_IgnOnTimeout_mS_u16	26292
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	192.596207
k_PowerCutVehSpdLowThresh_Kph_f32	45.7290001
k_PowerCutVehSpdLowTimeout_mS_u16	46937
k_VBattMaxAAS_Volt_f32	24.4612007
k_VBattMaxBSI_Volt_f32	30.8911991
k_VBattMaxCAV_Volt_f32	24.4276009
k_VBattMaxCMM388_Volt_f32	20.5571995
k_VBattMaxCMM_Volt_f32	10.2268
k_VBattMaxESP_Volt_f32	15.8892002
k_VBattMinAAS_Volt_f32	9.56089973
k_VBattMinBSI_Volt_f32	15.8892002
k_VBattMinCAV_Volt_f32	2.55629992
k_VBattMinCMM388_Volt_f32	19.3834
k_VBattMinCMM_Volt_f32	20.5841007
k_VBattMinESP_Volt_f32	10.2268
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	49772
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	6545
k_VitesseVehicleBVRampValidThresh_Cnt_u16	59050
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	37233
k_VitesseVehicleBVSigValidThresh_Cnt_u16	15878
k_VitesseVehicleBVSpeedPassThresh_kph_f32	507.527802
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	46206
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	48774
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1895403520
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	229
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16 Elaps	8524
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1236548
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target Rte Inst Ap SrlComInput.SrlComInput Per1 ISDATBSI432MsgDLCError C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	25
target_SrlComInput_Per1_Batt_Volt_f32.value	10.2563
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4248633344
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	4
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0454229452
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2009247744
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1743048704
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	928444416
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	773394432
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2485858304
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	207
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2978828288
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3460263936
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	131
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1619660800
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	36
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	156
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	157
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	184
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1205186560
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1467469824
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	107606016
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1973452800
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3197
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.57820338
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	35672
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	60.4450989
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	14377

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1236548	1236548	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	47250	47250	✔
AASNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	17653	17653	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	33153	33153	✔
AngleVolantMsgTimer_mS_M_u32	1236548	1236548	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	674.683228	674.683228	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1236548	1236548	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	98828288	98828288	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	44954	44954	✔
CAVNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CMMNodeAbsentTimer_mS_M_u32	2978828288	2978828288	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	37638	37638	✔
CONSANGLECPK_HwDeg_M_f32	-530.634705	-530.634705 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37638	37638	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1370546176	1370546176	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	16171	16171	✔
CityParkInputConsistentCount_Cnt_M_u16	13693	13693	✔
CityParkInputInvalidCount_Cnt_M_u16	61968	61968	✔
CityParkInputMsgTimer_mS_M_u32	1236548	1236548	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1236548	1236548	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1236548	1236548	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1236548	1236548	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1236548	1236548	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1236548	1236548	✔
ESPNTCEnableTimer_mS_M_u32	1236548	1236548	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1111	1111	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2222	2222	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1236548	1236548	✔
ElecIntTimer_mS_M_u32[1]	78790	78790	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1236548	1236548	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATDIRASentFltAcc_Cnt_M_u16	52471	52471	✔
ISDATDIRASentTimer_mS_M_u32	1236548	1236548	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	60848	60848	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	7083	7083	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	107606016	107606016	✔
IgnOnTimer_mS_M_u32	47755264	47755264	✔
IgnTimeOff_Sec_M_u32	3162196177	3162196177	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2009247744	2009247744	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	192	192	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1743048704	1743048704	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	119	119	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	928444416	928444416	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	49	49	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	773394432	773394432	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2383671296	2383671296	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	207	207	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2978828288	2978828288	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	67	67	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3460263936	3460263936	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1619660800	1619660800	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	141	141	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1205186560	1205186560	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	72	72	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1467469824	1467469824	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	126	126	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	107606016	107606016	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1973452800	1973452800	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	648.327393	648.327393	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VehSpdSync_Cnt_M_Igc	0	0	✔
VehTimeValid_Cnt_M_Igc	0	0	✔
VehicleSpeedValid_Cnt_M_Igc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	319.874512	319.874512	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	209.783905	209.783905	✔
target_SrlComInput_Per1_APAAuthn_Cnt_Igc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_Igc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	674.683228	674.683228	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_Igc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_Igc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_Igc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	37638	37638	✔
target_SrlComInput_Per1_CPKOK_Cnt_Igc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_Igc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_Igc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3162196177	3162196177	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-530.634705	-530.634705 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_Igc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_Igc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	140.531204	140.531204	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_Igc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_Igc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_Igc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0152	0x0152	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	4	ValidityNTCProcessing	4	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.173 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	175769856
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	63358
AASNodeAbsentTimer_mS_M_u32	2500606208
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0
ANGLEVOLANTSigValidCount_Cnt_M_u16	18830
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	18647
AngleVolantMsgTimer_mS_M_u32	175769856
AngleVolantValidCount_Cnt_M_u16	29278
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	701.579895
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3930650880
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1481996544
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	4076611840
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3978029312
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	43228
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3620382976
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	2860
CAVNodeAbsentTimer_mS_M_u32	2232572160
CDD_SrlComVehSpd_Kph_G_f32	609.939209
CMM388NTCEnableTimer_mS_M_u32	4159805696
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	741366016
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	31443
CMMNodeAbsentTimer_mS_M_u32	3397249280
CONSANGLECPKSigInvalidCount_Cnt_M_u16	23225
CONSANGLECPKSigValidCount_Cnt_M_u16	10807
CONSANGLECPK_Cnt_M_u16	48966
CONSANGLECPK_HwDeg_M_f32	780
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	48966
CPKVehicleSpeedMsgTimer_mS_M_u32	3305965824
CPKVehicleSpeedValidCount_Cnt_M_u16	12390
CityParkInputConsistentCount_Cnt_M_u16	36210
CityParkInputInvalidCount_Cnt_M_u16	25214
CityParkInputMsgTimer_mS_M_u32	3778842112
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1965046016
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	28818
ComputerRazGCTSigInvalidTimer_mS_M_u32	2699614464
ComputerRazGCTSigValidCount_Cnt_M_u16	41763
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	62314
DMDFCTCPKSigValidCount_Cnt_M_u16	5152
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	55211
DMDRELAXECPKSigValidCount_Cnt_M_u16	54680
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	12562
DateInvalidTimer_mS_M_u32	1481996544
DiagMuxOnAbsentTimer_mS_M_u32	1653131520
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3978029312
ESPNTCEnableTimer_mS_M_u32	389626112
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	51469
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	80

Name	Input Value
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3275008256
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	63075
EtatMTSigValidCount_Cnt_M_u16	31821
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	53571
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	21569
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	60734
ISDAT4V2BSI552MsgTimer_mS_M_u32	1368516864
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	61853
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	31023
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	31821
ISDATBSI3F2MsgTimer_mS_M_u32	603900160
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	5182
ISDATBSI412MsgLenValidCount_Cnt_M_u16	44608
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	63075
ISDATBSI412MsgTimer_mS_M_u32	1508903168
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	59623
ISDATBSI432MsgLenValidCount_Cnt_M_u16	24097
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	30201
ISDATDIRASentFltAcc_Cnt_M_u16	61917
ISDATDIRASentTimer_mS_M_u32	3305965824
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	52540
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	29278
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	6309
ISDYN2CMMMsgTimer_mS_M_u32	1729837312
ISDYNAASChkSumInvalidCount_Cnt_M_u16	27656
ISDYNAASChkSumValidCount_Cnt_M_u16	15638
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	9625
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	61307
ISDYNAASMsgLenValidCount_Cnt_M_u16	22177
ISDYNAASMsgTimeValidCount_Cnt_M_u16	27656
ISDYNAASMsgTimer_mS_M_u32	1776130304
ISDYNABRChkSumInvalidCount_Cnt_M_u16	5698
ISDYNABRChkSumValidCount_Cnt_M_u16	32856
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	16323
ISDYNABRMsgCountValidCount_Cnt_M_u16	63249
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	30068
ISDYNABRMsgLenValidCount_Cnt_M_u16	27442
ISDYNABRMsgTimeValidCount_Cnt_M_u16	48966
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	725
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1335
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	31821
ISDYNCMM208MsgTimer_mS_M_u32	2134505728
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2751
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1441
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	48340
ISDYNCMM388MsgTimer_mS_M_u32	949688576
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	29743
ISDYNVOLChkSumValidCount_Cnt_M_u16	36909
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	37856
ISDYNVOLMsgCountValidCount_Cnt_M_u16	16662
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	22610
ISDYNVOLMsgLenValidCount_Cnt_M_u16	303
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	31443
ISDYNVOLMsgTimer_mS_M_u32	1322572032
IgnOnTimer_mS_M_u32	4272888064
IgnTimeOff_Sec_M_u32	2723163952
ManVehSpd_Kph_M_f32	492.786102
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	187
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	13

Name	Input Value
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	109
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2977745152
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	231
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1075259648
PrevISDATBSI412MsgDLCError_Cnt_M_u08	99
PrevISDATBSI412MsgRxTime_MSec_M_u32	1604278528
PrevISDATBSI432MsgDLCError_Cnt_M_u08	107
PrevISDATBSI432MsgRxTime_MSec_M_u32	1308440832
PrevISDATDIRAMsgTxTime_MSec_M_u32	3196279040
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	179
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1243834624
PrevISDYNAASMsgDLCError_Cnt_M_u08	228
PrevISDYNAASMsgRxTime_MSec_M_u32	80402688
PrevISDYNABRMsgDLCError_Cnt_M_u08	52
PrevISDYNABRMsgRxTime_MSec_M_u32	3112638720
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	51
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3107707136
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	124
PrevISDYNCMM388MsgRxTime_MSec_M_u32	470563072
PrevISDYNVOLMsgDLCError_Cnt_M_u08	100
PrevISDYNVOLMsgRxTime_MSec_M_u32	520640768
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2154170624
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	14.7355003
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	7665
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	37271
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	5302
VitesseVehicleBVRampValidCount_Cnt_M_u16	33308
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	14694
VitesseVehicleBVSigValidCount_Cnt_M_u16	40339
VitesseVehicleBV_Kph_M_f32	184.816895
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	48340
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	19801
VitesseVehiculeRoues_Kph_M_f32	533.886902
k_AASNTCEnableTimeout_mS_u16	37657
k_AASNodeAbsentDiag_Cnt_str.Threshold	10757
k_AASNodeAbsentDiag_Cnt_str.PStep	7105
k_AASNodeAbsentDiag_Cnt_str.NStep	65461
k_AASNodeAbsentTimeout_mS_u16	41349
k_AASNodeTimeout_mS_u16	39063
k_ABSNodeTimeout_mS_u16	33051
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	24654
k_ANGLEVOLANTSigValidThresh_Cnt_u16	25800
k_AngleVolantInvalidThresh_Cnt_u16	32939
k_AngleVolantValidThresh_Cnt_u16	25214
k_BSI552MsgTimeout_mS_u16	13052
k_BSINTCEnableTimeout_mS_u16	21439
k_BSINodeAbsentDiag_Cnt_str.Threshold	26412
k_BSINodeAbsentDiag_Cnt_str.PStep	34315
k_BSINodeAbsentDiag_Cnt_str.NStep	15280
k_BSINodeAbsentTimeout_mS_u16	48559
k_BSINodeTimeout_mS_u16	30201
k_BattOvHi_Volt_f32	24.6580009
k_BattOvLo_Volt_f32	6.23929977
k_BattUvHi_Volt_f32	18.0209999
k_BattUvLo_Volt_f32	14.5544004
k_CAVNTCEnableTimeout_mS_u16	1404
k_CAVNodeAbsentDiag_Cnt_str.Threshold	9850

Name	Input Value
k_CAVNodeAbsentDiag_Cnt_str.PStep	55599
k_CAVNodeAbsentDiag_Cnt_str.NStep	26463
k_CAVNodeAbsentTimeout_mS_u16	22690
k_CAVNodeTimeout_mS_u16	25765
k_CMM388MsgTimeout_mS_u16	15998
k_CMM388NTCEnableTimeout_mS_u16	1386
k_CMMNTCEnableTimeout_mS_u16	34933
k_CMMNodeAbsentDiag_Cnt_str.Threshold	32647
k_CMMNodeAbsentDiag_Cnt_str.PStep	42126
k_CMMNodeAbsentDiag_Cnt_str.NStep	57005
k_CMMNodeAbsentTimeout_mS_u16	45637
k_CONSANGLECPKMax_HwDeg_f32	504.541199
k_CONSANGLECPKMin_HwDeg_f32	-25.8943005
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	33748
k_CONSANGLECPKSigValidThresh_Cnt_u16	21593
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	37045
k_CPKVehicleSpeedValidThresh_Cnt_u16	11085
k_CityParkInputInvalidThresh_Cnt_u16	37088
k_CityParkInputValidThresh_Cnt_u16	36210
k_ComputerRazGCTSigValidThresh_Cnt_u16	30619
k_CptTemporelSigValidThresh_Cnt_u16	8621
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	48244
k_DMDFCTCPKSigValidThresh_Cnt_u16	62002
k_DMDFCTCPKValidCount_Cnt_u16	19204
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	6309
k_DMDRELAXECPKSigValidThresh_Cnt_u16	16283
k_DMDRelaxeConsistentThresh_Cnt_u16	47545
k_DateValidThresh_Cnt_u16	60734
k_DefaultVehSpd_Kph_f32	12.7447996
k_DiagMuxOnAbsentTimeout_mS_u16	11284
k_EMNodeTimeout_mS_u16	21234
k_ESPNTCEnableTimeout_mS_u16	28440
k_ESPNodeAbsentDiag_Cnt_str.Threshold	40274
k_ESPNodeAbsentDiag_Cnt_str.PStep	1844
k_ESPNodeAbsentDiag_Cnt_str.NStep	56738
k_ESPNodeAbsentTimeout_mS_u16	12141
k_EtatMTSigInvalidThresh_Cnt_u16	43653
k_EtatMTSigValidThresh_Cnt_u16	53467
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	61476
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	40302
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	20023
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	33686
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	50152
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	20562
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	30304
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	17498
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	38651
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	7482
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	25820
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	38196
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	1582
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	26405
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	18647
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	37204
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	56642
k_ISDYNAASChkSumValidThresh_Cnt_u16	34648
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	34499
k_ISDYNAASMsgCountValidThresh_Cnt_u16	32273
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	11606
k_ISDYNAASMsgLenValidThresh_Cnt_u16	43947
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	26608
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	40426
k_ISDYNABRChkSumValidThresh_Cnt_u16	8232
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	61404
k_ISDYNABRMsgCountValidThresh_Cnt_u16	24713
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	33235
k_ISDYNABRMsgLenValidThresh_Cnt_u16	4109
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	40364
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	20741
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	36163

Name	Input Value
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	55610
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	50721
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	53390
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	35670
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	39461
k_ISDYNVOLChkSumValidThresh_Cnt_u16	41831
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	32102
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	32364
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	15183
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	55865
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	1292
k_IgnOnTimeout_mS_u16	28177
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	16.2178993
k_PowerCutVehSpdLowThresh_Kph_f32	54.757
k_PowerCutVehSpdLowTimeout_mS_u16	41525
k_VBattMaxAAS_Volt_f32	27.3257008
k_VBattMaxBSI_Volt_f32	24.1021004
k_VBattMaxCAV_Volt_f32	20.5713997
k_VBattMaxCMM388_Volt_f32	15.9805002
k_VBattMaxCMM_Volt_f32	0.261500001
k_VBattMaxESP_Volt_f32	8.50699997
k_VBattMinAAS_Volt_f32	8.73379993
k_VBattMinBSI_Volt_f32	8.50699997
k_VBattMinCAV_Volt_f32	2.38120008
k_VBattMinCMM388_Volt_f32	9.5923996
k_VBattMinCMM_Volt_f32	26.6177006
k_VBattMinESP_Volt_f32	0.261500001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	40455
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	10680
k_VitesseVehicleBVRampValidThresh_Cnt_u16	23264
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	5933
k_VitesseVehicleBVSigValidThresh_Cnt_u16	65295
k_VitesseVehicleBVSpeedPassThresh_kph_f32	170.651398
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	53804
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	35858
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1481996544
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	61
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	124
target_SrlComInput_Per1_Batt_Volt_f32.value	14.8000002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3732384000
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	169
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.549080729
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	32
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2342590720
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1603909888
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	857889024
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3996842240
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2028181760
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3139188992

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	177
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2632243456
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	83
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	155
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	189
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	190
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	238
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	191
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3202349312
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	247
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	760224000
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3871914240
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1607555328
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2523998464
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3441
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0929407626
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	272568
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	169.473999
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	53331

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	175769856	175769856	✔
AASNTCsEnabled_Cnt_M_lgc	1	1	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2632243456	2632243456	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	1	1	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	701.579895	701.579895	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3930650880	3930650880	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	1481996544	1481996544	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3978029312	3978029312	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	27948	27948	✔
BSINodeAbsentTimer_mS_M_u32	3996842240	3996842240	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3620382976	3620382976	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1607555328	1607555328	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3139188992	3139188992	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	48966	48966	✔
CONSANGLECPK_HwDeg_M_f32	780	780 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3251510528	3251510528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	80	80	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1603909888	1603909888	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11906	11906	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2632243456	2632243456	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1607555328	1607555328	✔
IgnOnTimer_mS_M_u32	4272888064	4272888064	✔
IgnTimeOff_Sec_M_u32	2723163952	2723163952	✔
Msg348Valid_Cnt_M_Igc	0	0	✔
Msg432Valid_Cnt_M_Igc	0	0	✔
Msg552Valid_Cnt_M_Igc	0	0	✔
NetOn_Cnt_M_Igc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	32	32	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2342590720	2342590720	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	172	172	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1603909888	1603909888	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	194	194	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	857889024	857889024	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	77	77	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3996842240	3996842240	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2028181760	2028181760	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	92	92	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3139188992	3139188992	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	177	177	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2632243456	2632243456	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	191	191	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3202349312	3202349312	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	247	247	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	760224000	760224000	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	136	136	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3871914240	3871914240	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1607555328	1607555328	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2523998464	2523998464	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	14.7355003	14.7355003	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	184.816895	184.816895	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	533.886902	533.886902	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	701.579895	701.579895	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	48966	48966	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2723163952	2723163952	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	780	780 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	12.7447996	12.7447996	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	5	ValidityNTCProcessing	5	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.174 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4086605824
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	56967
AASNodeAbsentTimer_mS_M_u32	2560497664
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	65535
ANGLEVOLANTSigValidCount_Cnt_M_u16	42262
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	36476
AngleVolantMsgTimer_mS_M_u32	4086605824
AngleVolantValidCount_Cnt_M_u16	62568
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	344.168396
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2078791680
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	63068160
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1787709440
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2871986176
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	8302
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	371378176
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	33788
CAVNodeAbsentTimer_mS_M_u32	151762944
CDD_SrlComVehSpd_Kph_G_f32	493.679291
CMM388NTCEnableTimer_mS_M_u32	1030617088
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	196196352
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	48327

Name	Input Value
CMMNodeAbsentTimer_mS_M_u32	453576704
CONSANGLECPKSigInvalidCount_Cnt_M_u16	45525
CONSANGLECPKSigValidCount_Cnt_M_u16	38428
CONSANGLECPK_Cnt_M_u16	53999
CONSANGLECPK_HwDeg_M_f32	717.402588
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	53999
CPKVehicleSpeedMsgTimer_mS_M_u32	3487279104
CPKVehicleSpeedValidCount_Cnt_M_u16	54488
CityParkInputConsistentCount_Cnt_M_u16	62252
CityParkInputInvalidCount_Cnt_M_u16	62727
CityParkInputMsgTimer_mS_M_u32	2342590720
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1214388224
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	49995
ComputerRazGCTSigInvalidTimer_mS_M_u32	797456384
ComputerRazGCTSigValidCount_Cnt_M_u16	46617
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	62019
DMDFCTCPKSigValidCount_Cnt_M_u16	49890
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	36865
DMDRELAXECPKSigValidCount_Cnt_M_u16	43256
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	53962
DateInvalidTimer_mS_M_u32	63068160
DiagMuxOnAbsentTimer_mS_M_u32	2523424768
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2871986176
ESPNTCEnableTimer_mS_M_u32	102176768
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	5338
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	65
EffacDefaultDiagTimer_mS_M_u32[1]	3873991680
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	56565
ElecIntTimer_mS_M_u32[1]	3873991680
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2078590976
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	56087
EtatMTSigValidCount_Cnt_M_u16	19482
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	63031
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	49150
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	12168
ISDAT4V2BSI552MsgTimer_mS_M_u32	3586983936
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	43241
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	46324
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	19482
ISDATBSI3F2MsgTimer_mS_M_u32	2852546560
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	22021
ISDATBSI412MsgLenValidCount_Cnt_M_u16	60096
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	56087
ISDATBSI412MsgTimer_mS_M_u32	1563600896
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	49803
ISDATBSI432MsgLenValidCount_Cnt_M_u16	42398
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	46997
ISDATDIRASentFltAcc_Cnt_M_u16	54249
ISDATDIRASentTimer_mS_M_u32	3487279104
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	269
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	62568
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	11922
ISDYN2CMMMsgTimer_mS_M_u32	510728192
ISDYNAASChkSumInvalidCount_Cnt_M_u16	10473
ISDYNAASChkSumValidCount_Cnt_M_u16	18560
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	34487
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	54031
ISDYNAASMsgLenValidCount_Cnt_M_u16	36958
ISDYNAASMsgTimeValidCount_Cnt_M_u16	10473

Name	Input Value
ISDYNAASMsgTimer_mS_M_u32	2544498688
ISDYNABRChkSumInvalidCount_Cnt_M_u16	35770
ISDYNABRChkSumValidCount_Cnt_M_u16	56
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	22968
ISDYNABRMsgCountValidCount_Cnt_M_u16	50831
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	3492
ISDYNABRMsgLenValidCount_Cnt_M_u16	32555
ISDYNABRMsgTimeValidCount_Cnt_M_u16	53999
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	726
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1337
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	19482
ISDYNCMM208MsgTimer_mS_M_u32	3239368704
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2755
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1443
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	27910
ISDYNCMM388MsgTimer_mS_M_u32	24213504
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	48499
ISDYNVOLChkSumValidCount_Cnt_M_u16	48186
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	26849
ISDYNVOLMsgCountValidCount_Cnt_M_u16	37888
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	47883
ISDYNVOLMsgLenValidCount_Cnt_M_u16	37682
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	48327
ISDYNVOLMsgTimer_mS_M_u32	3586406400
IgnOnTimer_mS_M_u32	4281694208
IgnTimeOff_Sec_M_u32	1155874523
ManVehSpd_Kph_M_f32	324.040405
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	189
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	206
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2039244800
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	193
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2940028928
PrevISDATBSI412MsgDLCError_Cnt_M_u08	141
PrevISDATBSI412MsgRxTime_MSec_M_u32	3982800896
PrevISDATBSI432MsgDLCError_Cnt_M_u08	244
PrevISDATBSI432MsgRxTime_MSec_M_u32	1909135360
PrevISDATDIRAMsgTxTime_MSec_M_u32	1622718464
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	158
PrevISDYN2CMMMsgRxTime_MSec_M_u32	303597568
PrevISDYNAASMsgDLCError_Cnt_M_u08	74
PrevISDYNAASMsgRxTime_MSec_M_u32	199374848
PrevISDYNABRMsgDLCError_Cnt_M_u08	101
PrevISDYNABRMsgRxTime_MSec_M_u32	783120384
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	136
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4069472256
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	192
PrevISDYNCMM388MsgRxTime_MSec_M_u32	60692480
PrevISDYNVOLMsgDLCError_Cnt_M_u08	168
PrevISDYNVOLMsgRxTime_MSec_M_u32	2468984832
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1104193536
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	315.398102
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	40877
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	14204
VVHTYPE1Count_Cnt_M_u08	8

Name	Input Value
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	3934
VitesseVehicleBVRampValidCount_Cnt_M_u16	47597
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	5840
VitesseVehicleBVSigValidCount_Cnt_M_u16	64775
VitesseVehicleBV_Kph_M_f32	325.610901
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	27910
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	11829
VitesseVehiculeRoues_Kph_M_f32	394.94809
k_AASNTCEnableTimeout_mS_u16	25462
k_AASNodeAbsentDiag_Cnt_str.Threshold	54881
k_AASNodeAbsentDiag_Cnt_str.PStep	64806
k_AASNodeAbsentDiag_Cnt_str.NStep	17792
k_AASNodeAbsentTimeout_mS_u16	49907
k_AASNodeTimeout_mS_u16	8828
k_ABSNodeTimeout_mS_u16	19760
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	47190
k_ANGLEVOLANTSigValidThresh_Cnt_u16	60841
k_AngleVolantInvalidThresh_Cnt_u16	58880
k_AngleVolantValidThresh_Cnt_u16	62727
k_BSI552MsgTimeout_mS_u16	51532
k_BSINTCEnableTimeout_mS_u16	57859
k_BSINodeAbsentDiag_Cnt_str.Threshold	26452
k_BSINodeAbsentDiag_Cnt_str.PStep	34298
k_BSINodeAbsentDiag_Cnt_str.NStep	15303
k_BSINodeAbsentTimeout_mS_u16	36852
k_BSINodeTimeout_mS_u16	46997
k_BattOvHi_Volt_f32	8.45180035
k_BattOvLo_Volt_f32	17.9729004
k_BattUvHi_Volt_f32	1.25820005
k_BattUvLo_Volt_f32	16.0695
k_CAVNTCEnableTimeout_mS_u16	1725
k_CAVNodeAbsentDiag_Cnt_str.Threshold	17052
k_CAVNodeAbsentDiag_Cnt_str.PStep	4531
k_CAVNodeAbsentDiag_Cnt_str.NStep	11419
k_CAVNodeAbsentTimeout_mS_u16	62362
k_CAVNodeTimeout_mS_u16	17425
k_CMM388MsgTimeout_mS_u16	2439
k_CMM388NTCEnableTimeout_mS_u16	25795
k_CMMNTCEnableTimeout_mS_u16	17505
k_CMMNodeAbsentDiag_Cnt_str.Threshold	53693
k_CMMNodeAbsentDiag_Cnt_str.PStep	57245
k_CMMNodeAbsentDiag_Cnt_str.NStep	40569
k_CMMNodeAbsentTimeout_mS_u16	44913
k_CONSANGLECPKMax_HwDeg_f32	100.272499
k_CONSANGLECPKMin_HwDeg_f32	-199.718796
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	6150
k_CONSANGLECPKSigValidThresh_Cnt_u16	6453
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	12834
k_CPKVehicleSpeedValidThresh_Cnt_u16	3288
k_CityParkInputInvalidThresh_Cnt_u16	5088
k_CityParkInputValidThresh_Cnt_u16	62252
k_ComputerRazGCTSigValidThresh_Cnt_u16	36591
k_CptTemporelSigValidThresh_Cnt_u16	13178
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	14500
k_DMDFCTCPKSigValidThresh_Cnt_u16	59947
k_DMDFCTCPKValidCount_Cnt_u16	55798
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	11922
k_DMDRELAXECPKSigValidThresh_Cnt_u16	60529
k_DMDRelaxeConsistentThresh_Cnt_u16	30231
k_DateValidThresh_Cnt_u16	12168
k_DefaultVehSpd_Kph_f32	71.2764969
k_DiagMuxOnAbsentTimeout_mS_u16	17541
k_EMNodeTimeout_mS_u16	60714
k_ESPNTCEnableTimeout_mS_u16	2104
k_ESPNodeAbsentDiag_Cnt_str.Threshold	5561
k_ESPNodeAbsentDiag_Cnt_str.PStep	18958
k_ESPNodeAbsentDiag_Cnt_str.NStep	33020

Name	Input Value
k_ESPNodeAbsentTimeout_mS_u16	55289
k_EtatMTSigInvalidThresh_Cnt_u16	39665
k_EtatMTSigValidThresh_Cnt_u16	55983
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	36821
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	2744
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	1245
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	5886
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	63689
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	61897
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	15904
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	5875
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	2127
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	35091
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	38126
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	14374
k_ISDATDIRASentDiag_Cnt_str.Threshold	2451
k_ISDATDIRASentDiag_Cnt_str.PStep	5266
k_ISDATDIRASentDiag_Cnt_str.NStep	3881
k_ISDATDIRASentTimeout_mS_u16	27638
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	50771
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	36476
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	37252
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	14010
k_ISDYNAASChkSumValidThresh_Cnt_u16	60216
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	33976
k_ISDYNAASMsgCountValidThresh_Cnt_u16	12687
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	38526
k_ISDYNAASMsgLenValidThresh_Cnt_u16	14656
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	33841
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	60482
k_ISDYNABRChkSumValidThresh_Cnt_u16	47177
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	19310
k_ISDYNABRMsgCountValidThresh_Cnt_u16	3109
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	42951
k_ISDYNABRMsgLenValidThresh_Cnt_u16	16346
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	41148
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	22129
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16118
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	44179
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	7327
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	4118
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	55935
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	8272
k_ISDYNVOLChkSumValidThresh_Cnt_u16	26443
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	39887
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	22012
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	48211
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	57942
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	40990
k_IgnOnTimeout_mS_u16	21644
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	9.35709953
k_PowerCutVehSpdLowThresh_Kph_f32	61.7398987
k_PowerCutVehSpdLowTimeout_mS_u16	42530
k_VBattMaxAAS_Volt_f32	16.9598999
k_VBattMaxBSI_Volt_f32	30.8201008
k_VBattMaxCAV_Volt_f32	22.2219009
k_VBattMaxCMM388_Volt_f32	19.059
k_VBattMaxCMM_Volt_f32	15.7812004
k_VBattMaxESP_Volt_f32	16.7938995
k_VBattMinAAS_Volt_f32	21.5275002
k_VBattMinBSI_Volt_f32	16.7938995
k_VBattMinCAV_Volt_f32	3.89689994
k_VBattMinCMM388_Volt_f32	9.70269966
k_VBattMinCMM_Volt_f32	9.25479984
k_VBattMinESP_Volt_f32	15.7812004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	10669
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	43352
k_VitesseVehicleBVRampValidThresh_Cnt_u16	5089
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	10042
k_VitesseVehicleBVSigValidThresh_Cnt_u16	21077
k_VitesseVehicleBVSpeedPassThresh_kph_f32	107.2379
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	12028

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	62475
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	63068160
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	18
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	18816
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3873991680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	192
target_SrlComInput_Per1_Batt_Volt_f32.value	11.1638002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4129015808
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	51
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.296008527
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	163
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2690611200
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1324718080
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	18
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1054586880
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3088177152
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	43513856
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1718491136
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	731133952
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	81
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	119
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	214
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	223
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	122
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	438491136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	85
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	117
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	180
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	197
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	199
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	928151552
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	896047104
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	885962752
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2486126592

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1371
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.480671316
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	718634
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	247.838699
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	36999

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	54881	54881	✔
AASNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	1	1	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3873991680	3873991680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	344.168396	344.168396	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26452	26452	✔
BSINodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	371378176	371378176	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	53693	53693	✔
CMMNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	53999	53999	✔
CONSANGLECPK_HwDeg_M_f32	717.402588	717.402588 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3873991680	3873991680	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3873991680	3873991680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3873991680	3873991680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3873991680	3873991680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3873991680	3873991680	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3873991680	3873991680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3873991680	3873991680	✔
ESPNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	65	65	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3873991680	3873991680	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	56565	56565	✔
ElecIntTimer_mS_M_u32[1]	3873991680	3873991680	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3873991680	3873991680	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3873991680	3873991680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	885962752	885962752	✔
IgnOnTimer_mS_M_u32	4281694208	4281694208	✔
IgnTimeOff_Sec_M_u32	1155874523	1155874523	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	163	163	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2690611200	2690611200	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	12	12	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1324718080	1324718080	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	18	18	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1054586880	1054586880	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	253	253	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3088177152	3088177152	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1622718464	1622718464	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1718491136	1718491136	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	240	240	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	731133952	731133952	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	122	122	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	438491136	438491136	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	154	154	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	928151552	928151552	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	242	242	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	896047104	896047104	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	168	168	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	885962752	885962752	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2486126592	2486126592	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	315.398102	315.398102	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	325.610901	325.610901	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	394.94809	394.94809	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	344.168396	344.168396	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	53999	53999	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1155874523	1155874523	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	717.402588	717.402588 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	71.2764969	71.2764969	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0151	0x0151	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	5	ValidityNTCProcessing	5	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.175 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1837157120
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	38569
AASNodeAbsentTimer_mS_M_u32	2955180800
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	7721
ANGLEVOLANTSigValidCount_Cnt_M_u16	3258
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	39626
AngleVolantMsgTimer_mS_M_u32	1837157120
AngleVolantValidCount_Cnt_M_u16	49541
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	390.974396
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1564949248
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1337441024
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1997794048
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	674343680
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	52978
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1716939520
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	1224
CAVNodeAbsentTimer_mS_M_u32	2640026368
CDD_SrlComVehSpd_Kph_G_f32	412.3367
CMM388NTCEnableTimer_mS_M_u32	1496636160
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2909379328

Name	Input Value
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	49958
CMMNodeAbsentTimer_mS_M_u32	3231951616
CONSANGLECPKSigInvalidCount_Cnt_M_u16	9662
CONSANGLECPKSigValidCount_Cnt_M_u16	32937
CONSANGLECPK_Cnt_M_u16	54832
CONSANGLECPK_HwDeg_M_f32	395.53421
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	54832
CPKVehicleSpeedMsgTimer_mS_M_u32	3031157504
CPKVehicleSpeedValidCount_Cnt_M_u16	61597
CityParkInputConsistentCount_Cnt_M_u16	54585
CityParkInputInvalidCount_Cnt_M_u16	19624
CityParkInputMsgTimer_mS_M_u32	2690611200
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2966977280
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	63581
ComputerRazGCTSigInvalidTimer_mS_M_u32	3152419584
ComputerRazGCTSigValidCount_Cnt_M_u16	32882
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	17652
DMDFCTCPKSigValidCount_Cnt_M_u16	15063
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	35897
DMDRELAXECPKSigValidCount_Cnt_M_u16	2324
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	55007
DateInvalidTimer_mS_M_u32	1337441024
DiagMuxOnAbsentTimer_mS_M_u32	2214955776
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	674343680
ESPNTCEnableTimer_mS_M_u32	2344188672
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	62126
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	55656
ElecIntTimer_mS_M_u32[1]	87787
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3171969792
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	46393
EtatMTSigValidCount_Cnt_M_u16	23024
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24728
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	2819
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	3301
ISDAT4V2BSI552MsgTimer_mS_M_u32	2690099968
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	3393
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	225
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	23024
ISDATBSI3F2MsgTimer_mS_M_u32	1093372672
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	50925
ISDATBSI412MsgLenValidCount_Cnt_M_u16	57468
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	46393
ISDATBSI412MsgTimer_mS_M_u32	682019584
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	49626
ISDATBSI432MsgLenValidCount_Cnt_M_u16	20578
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	3581
ISDATDIRASentFltAcc_Cnt_M_u16	2305
ISDATDIRASentTimer_mS_M_u32	3031157504
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	17366
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	49541
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	35847
ISDYN2CMMMsgTimer_mS_M_u32	715881216
ISDYNAASChkSumInvalidCount_Cnt_M_u16	49027
ISDYNAASChkSumValidCount_Cnt_M_u16	43134
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	1688
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	9103

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNAASMsgLenValidCount_Cnt_M_u16	4962
ISDYNAASMsgTimeValidCount_Cnt_M_u16	49027
ISDYNAASMsgTimer_mS_M_u32	981523200
ISDYNABRChkSumInvalidCount_Cnt_M_u16	29328
ISDYNABRChkSumValidCount_Cnt_M_u16	64723
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	10518
ISDYNABRMsgCountValidCount_Cnt_M_u16	10833
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	3665
ISDYNABRMsgLenValidCount_Cnt_M_u16	49532
ISDYNABRMsgTimeValidCount_Cnt_M_u16	54832
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	727
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1339
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	23024
ISDYNCMM208MsgTimer_mS_M_u32	2176858880
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2759
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1445
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	20395
ISDYNCMM388MsgTimer_mS_M_u32	2066373376
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	64228
ISDYNVOLChkSumValidCount_Cnt_M_u16	1615
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	55578
ISDYNVOLMsgCountValidCount_Cnt_M_u16	49021
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	1051
ISDYNVOLMsgLenValidCount_Cnt_M_u16	870
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	49958
ISDYNVOLMsgTimer_mS_M_u32	3107068672
IgnOnTimer_mS_M_u32	2447268608
IgnTimeOff_Sec_M_u32	2016100202
ManVehSpd_Kph_M_f32	515.52771
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	191
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	206
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1788447488
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	213
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	621210368
PrevISDATBSI412MsgDLCError_Cnt_M_u08	181
PrevISDATBSI412MsgRxTime_MSec_M_u32	2488310528
PrevISDATBSI432MsgDLCError_Cnt_M_u08	2
PrevISDATBSI432MsgRxTime_MSec_M_u32	412973824
PrevISDATDIRAMsgTxTime_MSec_M_u32	2320800512
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	123
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2037721856
PrevISDYNAASMsgDLCError_Cnt_M_u08	180
PrevISDYNAASMsgRxTime_MSec_M_u32	249043712
PrevISDYNABRMsgDLCError_Cnt_M_u08	70
PrevISDYNABRMsgRxTime_MSec_M_u32	3816184576
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	126
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1322326784
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	162
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1864661760
PrevISDYNVOLMsgDLCError_Cnt_M_u08	2
PrevISDYNVOLMsgRxTime_MSec_M_u32	4144077568
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1926023936
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	275.457306
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	46517

Name	Input Value
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	5640
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	27298
VitesseVehicleBVRampValidCount_Cnt_M_u16	37557
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	62412
VitesseVehicleBVSigValidCount_Cnt_M_u16	2279
VitesseVehicleBV_Kph_M_f32	652.467773
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	20395
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	46047
VitesseVehiculeRoues_Kph_M_f32	376.514496
k_AASNTCEnableTimeout_mS_u16	155
k_AASNodeAbsentDiag_Cnt_str.Threshold	49353
k_AASNodeAbsentDiag_Cnt_str.PStep	14481
k_AASNodeAbsentDiag_Cnt_str.NStep	25307
k_AASNodeAbsentTimeout_mS_u16	16868
k_AASNodeTimeout_mS_u16	21768
k_ABSNodeTimeout_mS_u16	10285
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	52345
k_ANGLEVOLANTSigValidThresh_Cnt_u16	25665
k_AngleVolantInvalidThresh_Cnt_u16	38716
k_AngleVolantValidThresh_Cnt_u16	19624
k_BSI552MsgTimeout_mS_u16	65178
k_BSINTCEnableTimeout_mS_u16	17266
k_BSINodeAbsentDiag_Cnt_str.Threshold	26492
k_BSINodeAbsentDiag_Cnt_str.PStep	34281
k_BSINodeAbsentDiag_Cnt_str.NStep	15326
k_BSINodeAbsentTimeout_mS_u16	30306
k_BSINodeTimeout_mS_u16	3581
k_BattOvHi_Volt_f32	3.77979994
k_BattOvLo_Volt_f32	14.9210997
k_BattUvHi_Volt_f32	9.17409992
k_BattUvLo_Volt_f32	16.5051994
k_CAVNTCEnableTimeout_mS_u16	1390
k_CAVNodeAbsentDiag_Cnt_str.Threshold	46929
k_CAVNodeAbsentDiag_Cnt_str.PStep	29794
k_CAVNodeAbsentDiag_Cnt_str.NStep	45890
k_CAVNodeAbsentTimeout_mS_u16	44526
k_CAVNodeTimeout_mS_u16	24330
k_CMM388MsgTimeout_mS_u16	5545
k_CMM388NTCEnableTimeout_mS_u16	62453
k_CMMNTCEnableTimeout_mS_u16	6873
k_CMMNodeAbsentDiag_Cnt_str.Threshold	23318
k_CMMNodeAbsentDiag_Cnt_str.PStep	39565
k_CMMNodeAbsentDiag_Cnt_str.NStep	63059
k_CMMNodeAbsentTimeout_mS_u16	8235
k_CONSANGLECPKMax_HwDeg_f32	718.891479
k_CONSANGLECPKMin_HwDeg_f32	-501.241089
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	20139
k_CONSANGLECPKSigValidThresh_Cnt_u16	62175
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	15894
k_CPKVehicleSpeedValidThresh_Cnt_u16	44660
k_CityParkInputInvalidThresh_Cnt_u16	61982
k_CityParkInputValidThresh_Cnt_u16	54585
k_ComputerRazGCTSigValidThresh_Cnt_u16	62255
k_CptTemporelSigValidThresh_Cnt_u16	7503
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	36177
k_DMDFCTCPKSigValidThresh_Cnt_u16	32892
k_DMDFCTCPKValidCount_Cnt_u16	49754
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	35847
k_DMDRELAXECPKSigValidThresh_Cnt_u16	47658
k_DMDRelaxeConsistentThresh_Cnt_u16	13624
k_DateValidThresh_Cnt_u16	3301
k_DefaultVehSpd_Kph_f32	98.9157028
k_DiagMuxOnAbsentTimeout_mS_u16	22894
k_EMNodeTimeout_mS_u16	1983
k_ESPNTCEnableTimeout_mS_u16	26644
k_ESPNodeAbsentDiag_Cnt_str.Threshold	14081

Name	Input Value
k_ESPNodeAbsentDiag_Cnt_str.PStep	9243
k_ESPNodeAbsentDiag_Cnt_str.NStep	12458
k_ESPNodeAbsentTimeout_mS_u16	50835
k_EtatMTSigInvalidThresh_Cnt_u16	57579
k_EtatMTSigValidThresh_Cnt_u16	2414
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	45309
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	47124
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	42022
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	22274
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	51554
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	929
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	58139
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	36963
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	142
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	17348
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	30707
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	61836
k_ISDATDIRASentDiag_Cnt_str.Threshold	42732
k_ISDATDIRASentDiag_Cnt_str.PStep	3144
k_ISDATDIRASentDiag_Cnt_str.NStep	10267
k_ISDATDIRASentTimeout_mS_u16	49628
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	15109
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	39626
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	64560
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	29072
k_ISDYNAASChkSumValidThresh_Cnt_u16	15315
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	43030
k_ISDYNAASMsgCountValidThresh_Cnt_u16	59729
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	25156
k_ISDYNAASMsgLenValidThresh_Cnt_u16	8380
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	49321
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	27255
k_ISDYNABRChkSumValidThresh_Cnt_u16	3618
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	19954
k_ISDYNABRMsgCountValidThresh_Cnt_u16	54157
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	550
k_ISDYNABRMsgLenValidThresh_Cnt_u16	29102
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	12744
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	41321
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	4122
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	53955
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	56927
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	52154
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	31808
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	21516
k_ISDYNVOLChkSumValidThresh_Cnt_u16	22235
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	29135
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	2951
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	389
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	34620
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	37667
k_IgnOnTimeout_mS_u16	42840
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	183.173996
k_PowerCutVehSpdLowThresh_Kph_f32	34.0256004
k_PowerCutVehSpdLowTimeout_mS_u16	59543
k_VBattMaxAAS_Volt_f32	31.9741993
k_VBattMaxBSI_Volt_f32	10.8250999
k_VBattMaxCAV_Volt_f32	27.1912003
k_VBattMaxCMM388_Volt_f32	22.4862995
k_VBattMaxCMM_Volt_f32	18.6235008
k_VBattMaxESP_Volt_f32	4.33830023
k_VBattMinAAS_Volt_f32	6.89550018
k_VBattMinBSI_Volt_f32	4.33830023
k_VBattMinCAV_Volt_f32	1.85259998
k_VBattMinCMM388_Volt_f32	4.11679983
k_VBattMinCMM_Volt_f32	18.5767994
k_VBattMinESP_Volt_f32	18.6235008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	63735
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	4534
k_VitesseVehicleBVRampValidThresh_Cnt_u16	55322
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	50511
k_VitesseVehicleBVSigValidThresh_Cnt_u16	39870

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VitesseVehicleBVSpeedPassThresh_kph_f32	121.175102
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	968
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	56411
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1337441024
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	199
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	56852
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2274721536
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	162
target_SrlComInput_Per1_Batt_Volt_f32.value	7.97660017
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3932908288
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	91
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.353503138
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3596638976
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1260256000
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1005296384
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3502848768
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	834067200
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2259974912
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	161
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4156693248
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	20
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	41
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	64
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	91
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	228
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	781597440
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	64
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	65
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	90
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	176
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	183
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	44
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2642893568
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	600111872
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3859979008
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	77
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	101
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	241

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3190876928
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	290
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.528777897
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1912
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	188.978897
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	52007

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	39626	39626	✔
AngleVolantMsgTimer_mS_M_u32	2274721536	2274721536	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	390.974396	390.974396	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1564949248	1564949248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	1337441024	1337441024	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	1997794048	1997794048	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	674343680	674343680	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26492	26492	✔
BSINodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2259974912	2259974912	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	54832	54832	✔
CONSANGLECPK_HwDeg_M_f32	395.53421	395.53421 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	54832	54832	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3031157504	3031157504	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	61597	61597	✔
CityParkInputConsistentCount_Cnt_M_u16	54585	54585	✔
CityParkInputInvalidCount_Cnt_M_u16	19626	19626	✔
CityParkInputMsgTimer_mS_M_u32	2274721536	2274721536	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2274721536	2274721536	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2274721536	2274721536	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1337441024	1337441024	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2274721536	2274721536	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	674343680	674343680	✔
ESPNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	14081	14081	✔
ESPNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2274721536	2274721536	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2274721536	2274721536	✔
ElecIntTimer_mS_M_u32[1]	87787	87787	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2274721536	2274721536	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24729	24729	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3596638976	3596638976	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	3394	3394	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1093372672	1093372672	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	50926	50926	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1005296384	1005296384	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	49626	49626	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3502848768	3502848768	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2274721536	2274721536	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2274721536	2274721536	✔
IgnOnTimer_mS_M_u32	2447268608	2447268608	✔
IgnTimeOff_Sec_M_u32	2016100202	2016100202	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	134	134	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3596638976	3596638976	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	43	43	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1260256000	1260256000	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	57	57	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1005296384	1005296384	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	215	215	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3502848768	3502848768	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2320800512	2320800512	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	99	99	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2259974912	2259974912	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	161	161	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4156693248	4156693248	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	228	228	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	781597440	781597440	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	44	44	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2642893568	2642893568	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	3	3	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	600111872	600111872	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	2	2	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3859979008	3859979008	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3190876928	3190876928	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	275.457306	275.457306	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	652.467773	652.467773	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	376.514496	376.514496	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	390.974396	390.974396	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	54832	54832	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2016100202	2016100202	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	395.53421	395.53421 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	98.9157028	98.9157028	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.176 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	175769856
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	63358
AASNodeAbsentTimer_mS_M_u32	2500606208
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0
ANGLEVOLANTSigValidCount_Cnt_M_u16	18830
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	18647
AngleVolantMsgTimer_mS_M_u32	175769856
AngleVolantValidCount_Cnt_M_u16	29278
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0.4135966
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3930650880
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1481996544
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	4076611840
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3978029312

Name	Input Value
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	43228
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3620382976
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	2860
CAVNodeAbsentTimer_mS_M_u32	2232572160
CDD_SrlComVehSpd_Kph_G_f32	609.939209
CMM388NTCEnableTimer_mS_M_u32	4159805696
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	741366016
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	31443
CMMNodeAbsentTimer_mS_M_u32	3397249280
CONSANGLECPKSigInvalidCount_Cnt_M_u16	23225
CONSANGLECPKSigValidCount_Cnt_M_u16	10807
CONSANGLECPK_Cnt_M_u16	48966
CONSANGLECPK_HwDeg_M_f32	780
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	48966
CPKVehicleSpeedMsgTimer_mS_M_u32	3305965824
CPKVehicleSpeedValidCount_Cnt_M_u16	12390
CityParkInputConsistentCount_Cnt_M_u16	36210
CityParkInputInvalidCount_Cnt_M_u16	25214
CityParkInputMsgTimer_mS_M_u32	3778842112
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1965046016
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	28818
ComputerRazGCTSigInvalidTimer_mS_M_u32	2699614464
ComputerRazGCTSigValidCount_Cnt_M_u16	41763
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	62314
DMDFCTCPKSigValidCount_Cnt_M_u16	5152
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	55211
DMDRELAXECPKSigValidCount_Cnt_M_u16	54680
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	12562
DateInvalidTimer_mS_M_u32	1481996544
DiagMuxOnAbsentTimer_mS_M_u32	1653131520
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3978029312
ESPNTCEnableTimer_mS_M_u32	389626112
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	51469
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	80
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3275008256
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	63075
EtatMTSigValidCount_Cnt_M_u16	31821
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	53571
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	21569
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	60734
ISDAT4V2BSI552MsgTimer_mS_M_u32	1368516864
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	61853
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	31023
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	31821
ISDATBSI3F2MsgTimer_mS_M_u32	603900160
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	5182
ISDATBSI412MsgLenValidCount_Cnt_M_u16	44608
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	63075
ISDATBSI412MsgTimer_mS_M_u32	1508903168
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	59623
ISDATBSI432MsgLenValidCount_Cnt_M_u16	24097
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	30201

Name	Input Value
ISDATDIRASentFltAcc_Cnt_M_u16	61917
ISDATDIRASentTimer_mS_M_u32	3305965824
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	52540
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	29278
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	6309
ISDYN2CMMMsgTimer_mS_M_u32	1729837312
ISDYNAASChkSumInvalidCount_Cnt_M_u16	27656
ISDYNAASChkSumValidCount_Cnt_M_u16	15638
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	9625
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	61307
ISDYNAASMsgLenValidCount_Cnt_M_u16	22177
ISDYNAASMsgTimeValidCount_Cnt_M_u16	27656
ISDYNAASMsgTimer_mS_M_u32	1776130304
ISDYNABRChkSumInvalidCount_Cnt_M_u16	5698
ISDYNABRChkSumValidCount_Cnt_M_u16	32856
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	16323
ISDYNABRMsgCountValidCount_Cnt_M_u16	63249
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	30068
ISDYNABRMsgLenValidCount_Cnt_M_u16	27442
ISDYNABRMsgTimeValidCount_Cnt_M_u16	48966
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	725
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1335
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	31821
ISDYNCMM208MsgTimer_mS_M_u32	2134505728
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2751
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1441
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	48340
ISDYNCMM388MsgTimer_mS_M_u32	949688576
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	29743
ISDYNVOLChkSumValidCount_Cnt_M_u16	36909
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	37856
ISDYNVOLMsgCountValidCount_Cnt_M_u16	16662
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	22610
ISDYNVOLMsgLenValidCount_Cnt_M_u16	303
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	31443
ISDYNVOLMsgTimer_mS_M_u32	1322572032
IgnOnTimer_mS_M_u32	4272888064
IgnTimeOff_Sec_M_u32	2723163952
ManVehSpd_Kph_M_f32	492.786102
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	187
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	109
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2977745152
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	231
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1075259648
PrevISDATBSI412MsgDLCError_Cnt_M_u08	99
PrevISDATBSI412MsgRxTime_MSec_M_u32	1604278528
PrevISDATBSI432MsgDLCError_Cnt_M_u08	107
PrevISDATBSI432MsgRxTime_MSec_M_u32	1308440832
PrevISDATDIRAMsgTxTime_MSec_M_u32	3196279040
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	179
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1243834624
PrevISDYNAASMsgDLCError_Cnt_M_u08	228
PrevISDYNAASMsgRxTime_MSec_M_u32	80402688
PrevISDYNABRMsgDLCError_Cnt_M_u08	52
PrevISDYNABRMsgRxTime_MSec_M_u32	3112638720
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	51
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3107707136
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	124
PrevISDYNCMM388MsgRxTime_MSec_M_u32	470563072
PrevISDYNVOLMsgDLCError_Cnt_M_u08	100
PrevISDYNVOLMsgRxTime_MSec_M_u32	520640768
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2154170624

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	14.7355003
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	7665
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	37271
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	5302
VitesseVehicleBVRampValidCount_Cnt_M_u16	33308
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	14694
VitesseVehicleBVSigValidCount_Cnt_M_u16	40339
VitesseVehicleBV_Kph_M_f32	184.816895
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	48340
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	19801
VitesseVehiculeRoues_Kph_M_f32	533.886902
k_AASNTCEnableTimeout_mS_u16	37657
k_AASNodeAbsentDiag_Cnt_str.Threshold	10757
k_AASNodeAbsentDiag_Cnt_str.PStep	7105
k_AASNodeAbsentDiag_Cnt_str.NStep	65461
k_AASNodeAbsentTimeout_mS_u16	41349
k_AASNodeTimeout_mS_u16	39063
k_ABSNodeTimeout_mS_u16	33051
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	24654
k_ANGLEVOLANTSigValidThresh_Cnt_u16	25800
k_AngleVolantInvalidThresh_Cnt_u16	32939
k_AngleVolantValidThresh_Cnt_u16	25214
k_BSI552MsgTimeout_mS_u16	13052
k_BSINTCEnableTimeout_mS_u16	21439
k_BSINodeAbsentDiag_Cnt_str.Threshold	26412
k_BSINodeAbsentDiag_Cnt_str.PStep	34315
k_BSINodeAbsentDiag_Cnt_str.NStep	15280
k_BSINodeAbsentTimeout_mS_u16	48559
k_BSINodeTimeout_mS_u16	30201
k_BattOvHi_Volt_f32	24.6580009
k_BattOvLo_Volt_f32	6.23929977
k_BattUvHi_Volt_f32	18.0209999
k_BattUvLo_Volt_f32	14.5544004
k_CAVNTCEnableTimeout_mS_u16	1404
k_CAVNodeAbsentDiag_Cnt_str.Threshold	9850
k_CAVNodeAbsentDiag_Cnt_str.PStep	55599
k_CAVNodeAbsentDiag_Cnt_str.NStep	26463
k_CAVNodeAbsentTimeout_mS_u16	22690
k_CAVNodeTimeout_mS_u16	25765
k_CMM388MsgTimeout_mS_u16	15998
k_CMM388NTCEnableTimeout_mS_u16	1386
k_CMMNTCEnableTimeout_mS_u16	34933
k_CMMNodeAbsentDiag_Cnt_str.Threshold	32647
k_CMMNodeAbsentDiag_Cnt_str.PStep	42126
k_CMMNodeAbsentDiag_Cnt_str.NStep	57005
k_CMMNodeAbsentTimeout_mS_u16	45637
k_CONSANGLECPKMax_HwDeg_f32	504.541199
k_CONSANGLECPKMin_HwDeg_f32	-25.8943005
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	33748
k_CONSANGLECPKSigValidThresh_Cnt_u16	21593
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	37045
k_CPKVehicleSpeedValidThresh_Cnt_u16	11085
k_CityParkInputInvalidThresh_Cnt_u16	37088
k_CityParkInputValidThresh_Cnt_u16	36210
k_ComputerRazGCTSigValidThresh_Cnt_u16	30619
k_CptTemporelSigValidThresh_Cnt_u16	8621
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	48244

Name	Input Value
k_DMDFCTCPKSigValidThresh_Cnt_u16	62002
k_DMDFCTCPKValidCount_Cnt_u16	19204
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	6309
k_DMDRELAXECPKSigValidThresh_Cnt_u16	16283
k_DMDRelaxeConsistentThresh_Cnt_u16	47545
k_DateValidThresh_Cnt_u16	60734
k_DefaultVehSpd_Kph_f32	12.7447996
k_DiagMuxOnAbsentTimeout_mS_u16	11284
k_EMNodeTimeout_mS_u16	21234
k_ESPNTCEnableTimeout_mS_u16	28440
k_ESPNodeAbsentDiag_Cnt_str.Threshold	40274
k_ESPNodeAbsentDiag_Cnt_str.PStep	1844
k_ESPNodeAbsentDiag_Cnt_str.NStep	56738
k_ESPNodeAbsentTimeout_mS_u16	12141
k_EtatMTSigInvalidThresh_Cnt_u16	43653
k_EtatMTSigValidThresh_Cnt_u16	53467
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	61476
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	40302
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	20023
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	33686
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	50152
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	20562
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	30304
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	17498
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	38651
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	7482
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	25820
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	38196
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	1582
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	26405
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	18647
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	37204
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	56642
k_ISDYNAASChkSumValidThresh_Cnt_u16	34648
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	34499
k_ISDYNAASMsgCountValidThresh_Cnt_u16	32273
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	11606
k_ISDYNAASMsgLenValidThresh_Cnt_u16	43947
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	26608
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	40426
k_ISDYNABRChkSumValidThresh_Cnt_u16	8232
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	61404
k_ISDYNABRMsgCountValidThresh_Cnt_u16	24713
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	33235
k_ISDYNABRMsgLenValidThresh_Cnt_u16	4109
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	40364
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	20741
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	36163
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	55610
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	50721
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	53390
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	35670
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	39461
k_ISDYNVOLChkSumValidThresh_Cnt_u16	41831
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	32102
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	32364
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	15183
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	55865
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	1292
k_IgnOnTimeout_mS_u16	28177
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	16.2178993
k_PowerCutVehSpdLowThresh_Kph_f32	54.757
k_PowerCutVehSpdLowTimeout_mS_u16	41525
k_VBattMaxAAS_Volt_f32	27.3257008
k_VBattMaxBSI_Volt_f32	24.1021004
k_VBattMaxCAV_Volt_f32	20.5713997
k_VBattMaxCMM388_Volt_f32	15.9805002
k_VBattMaxCMM_Volt_f32	0.261500001
k_VBattMaxESP_Volt_f32	8.50699997

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinAAS_Volt_f32	8.73379993
k_VBattMinBSI_Volt_f32	8.50699997
k_VBattMinCAV_Volt_f32	2.38120008
k_VBattMinCMM388_Volt_f32	9.5923996
k_VBattMinCMM_Volt_f32	26.6177006
k_VBattMinESP_Volt_f32	0.261500001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	40455
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	10680
k_VitesseVehicleBVRampValidThresh_Cnt_u16	23264
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	5933
k_VitesseVehicleBVSigValidThresh_Cnt_u16	65295
k_VitesseVehicleBVSpeedPassThresh_kph_f32	170.651398
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	53804
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	35858
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1481996544
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	61
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	124
target_SrlComInput_Per1_Batt_Volt_f32.value	14.8000002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3732384000
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	169
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.549080729
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	32
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2342590720
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1603909888
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	857889024
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3996842240
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2028181760
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3139188992
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	177
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2632243456
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	83
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	155
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	189
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	190
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	238
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	191
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3202349312
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	247
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	760224000

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3871914240
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1607555328
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2523998464
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2521
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0929407626
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	135634
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	169.473999
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	53331

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	175769856	175769856	✔
AASNTCsEnabled_Cnt_M_lgc	1	1	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2632243456	2632243456	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	1	1	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0.4135966	0.4135966	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3930650880	3930650880	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	1481996544	1481996544	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3978029312	3978029312	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	27948	27948	✔
BSINodeAbsentTimer_mS_M_u32	3996842240	3996842240	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3620382976	3620382976	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1607555328	1607555328	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3139188992	3139188992	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	48966	48966	✔
CONSANGLECPK_HwDeg_M_f32	780	780 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3251510528	3251510528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	80	80	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1603909888	1603909888	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11906	11906	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2632243456	2632243456	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1607555328	1607555328	✔
IgnOnTimer_mS_M_u32	4272888064	4272888064	✔
IgnTimeOff_Sec_M_u32	2723163952	2723163952	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	32	32	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2342590720	2342590720	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	172	172	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1603909888	1603909888	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	194	194	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	857889024	857889024	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	77	77	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3996842240	3996842240	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2028181760	2028181760	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	92	92	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3139188992	3139188992	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	177	177	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2632243456	2632243456	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	191	191	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3202349312	3202349312	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	247	247	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	760224000	760224000	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	136	136	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3871914240	3871914240	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1607555328	1607555328	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2523998464	2523998464	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	14.7355003	14.7355003	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	184.816895	184.816895	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	533.886902	533.886902	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0.4135966	0.4135966	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	48966	48966	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2723163952	2723163952	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	780	780 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	12.7447996	12.7447996	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	5	ValidityNTCProcessing	5	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.177 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4086605824
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	56967
AASNodeAbsentTimer_mS_M_u32	2560497664
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	65535
ANGLEVOLANTSigValidCount_Cnt_M_u16	42262
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	36476
AngleVolantMsgTimer_mS_M_u32	4086605824
AngleVolantValidCount_Cnt_M_u16	62568
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	566.845093
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2078791680
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	63068160

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1787709440
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2871986176
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	8302
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	371378176
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	33788
CAVNodeAbsentTimer_mS_M_u32	151762944
CDD_SrlComVehSpd_Kph_G_f32	493.679291
CMM388NTCEnableTimer_mS_M_u32	1030617088
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	196196352
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	48327
CMMNodeAbsentTimer_mS_M_u32	453576704
CONSANGLECPKSigInvalidCount_Cnt_M_u16	45525
CONSANGLECPKSigValidCount_Cnt_M_u16	38428
CONSANGLECPK_Cnt_M_u16	53999
CONSANGLECPK_HwDeg_M_f32	717.402588
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	53999
CPKVehicleSpeedMsgTimer_mS_M_u32	3487279104
CPKVehicleSpeedValidCount_Cnt_M_u16	54488
CityParkInputConsistentCount_Cnt_M_u16	62252
CityParkInputInvalidCount_Cnt_M_u16	62727
CityParkInputMsgTimer_mS_M_u32	2342590720
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1214388224
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	49995
ComputerRazGCTSigInvalidTimer_mS_M_u32	797456384
ComputerRazGCTSigValidCount_Cnt_M_u16	46617
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	62019
DMDFCTCPKSigValidCount_Cnt_M_u16	49890
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	36865
DMDRELAXECPKSigValidCount_Cnt_M_u16	43256
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	53962
DateInvalidTimer_mS_M_u32	63068160
DiagMuxOnAbsentTimer_mS_M_u32	2523424768
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2871986176
ESPNTCEnableTimer_mS_M_u32	102176768
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	5338
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	65
EffacDefaultDiagTimer_mS_M_u32[1]	3873991680
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	56565
ElecIntTimer_mS_M_u32[1]	3873991680
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2078590976
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	56087
EtatMTSigValidCount_Cnt_M_u16	19482
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	63031
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	49150
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	12168
ISDAT4V2BSI552MsgTimer_mS_M_u32	3586983936
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	43241
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	46324
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	19482
ISDATBSI3F2MsgTimer_mS_M_u32	2852546560
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	22021
ISDATBSI412MsgLenValidCount_Cnt_M_u16	60096
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	56087

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDATBSI412MsgTimer_mS_M_u32	1563600896
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	49803
ISDATBSI432MsgLenValidCount_Cnt_M_u16	42398
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	46997
ISDATDIRASentFltAcc_Cnt_M_u16	54249
ISDATDIRASentTimer_mS_M_u32	3487279104
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	269
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	62568
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	11922
ISDYN2CMMMsgTimer_mS_M_u32	510728192
ISDYNAASChkSumInvalidCount_Cnt_M_u16	10473
ISDYNAASChkSumValidCount_Cnt_M_u16	18560
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	34487
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	54031
ISDYNAASMsgLenValidCount_Cnt_M_u16	36958
ISDYNAASMsgTimeValidCount_Cnt_M_u16	10473
ISDYNAASMsgTimer_mS_M_u32	2544498688
ISDYNABRChkSumInvalidCount_Cnt_M_u16	35770
ISDYNABRChkSumValidCount_Cnt_M_u16	56
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	22968
ISDYNABRMsgCountValidCount_Cnt_M_u16	50831
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	3492
ISDYNABRMsgLenValidCount_Cnt_M_u16	32555
ISDYNABRMsgTimeValidCount_Cnt_M_u16	53999
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	726
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1337
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	19482
ISDYNCMM208MsgTimer_mS_M_u32	3239368704
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2755
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1443
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	27910
ISDYNCMM388MsgTimer_mS_M_u32	24213504
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	48499
ISDYNVOLChkSumValidCount_Cnt_M_u16	48186
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	26849
ISDYNVOLMsgCountValidCount_Cnt_M_u16	37888
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	47883
ISDYNVOLMsgLenValidCount_Cnt_M_u16	37682
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	48327
ISDYNVOLMsgTimer_mS_M_u32	3586406400
IgnOnTimer_mS_M_u32	4281694208
IgnTimeOff_Sec_M_u32	1155874523
ManVehSpd_Kph_M_f32	324.040405
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	189
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	206
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2039244800
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	193
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2940028928
PrevISDATBSI412MsgDLCError_Cnt_M_u08	141
PrevISDATBSI412MsgRxTime_MSec_M_u32	3982800896
PrevISDATBSI432MsgDLCError_Cnt_M_u08	244
PrevISDATBSI432MsgRxTime_MSec_M_u32	1909135360
PrevISDATDIRAMsgTxTime_MSec_M_u32	1622718464
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	158
PrevISDYN2CMMMsgRxTime_MSec_M_u32	303597568
PrevISDYNAASMsgDLCError_Cnt_M_u08	74
PrevISDYNAASMsgRxTime_MSec_M_u32	199374848
PrevISDYNABRMsgDLCError_Cnt_M_u08	101
PrevISDYNABRMsgRxTime_MSec_M_u32	783120384
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	136
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4069472256
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	192

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevISDYNCMM388MsgRxTime_MSec_M_u32	60692480
PrevISDYNVOLMsgDLCError_Cnt_M_u08	168
PrevISDYNVOLMsgRxTime_MSec_M_u32	2468984832
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1104193536
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	315.398102
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	40877
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	14204
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	3934
VitesseVehicleBVRampValidCount_Cnt_M_u16	47597
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	5840
VitesseVehicleBVSigValidCount_Cnt_M_u16	64775
VitesseVehicleBV_Kph_M_f32	325.610901
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	27910
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	11829
VitesseVehiculeRoues_Kph_M_f32	394.94809
k_AASNTCEnableTimeout_mS_u16	25462
k_AASNodeAbsentDiag_Cnt_str.Threshold	54881
k_AASNodeAbsentDiag_Cnt_str.PStep	64806
k_AASNodeAbsentDiag_Cnt_str.NStep	17792
k_AASNodeAbsentTimeout_mS_u16	49907
k_AASNodeTimeout_mS_u16	8828
k_ABSNodeTimeout_mS_u16	19760
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	47190
k_ANGLEVOLANTSigValidThresh_Cnt_u16	60841
k_AngleVolantInvalidThresh_Cnt_u16	58880
k_AngleVolantValidThresh_Cnt_u16	62727
k_BSI552MsgTimeout_mS_u16	51532
k_BSINTCEnableTimeout_mS_u16	57859
k_BSINodeAbsentDiag_Cnt_str.Threshold	26452
k_BSINodeAbsentDiag_Cnt_str.PStep	34298
k_BSINodeAbsentDiag_Cnt_str.NStep	15303
k_BSINodeAbsentTimeout_mS_u16	36852
k_BSINodeTimeout_mS_u16	46997
k_BattOvHi_Volt_f32	8.45180035
k_BattOvLo_Volt_f32	17.9729004
k_BattUvHi_Volt_f32	1.25820005
k_BattUvLo_Volt_f32	16.0695
k_CAVNTCEnableTimeout_mS_u16	1725
k_CAVNodeAbsentDiag_Cnt_str.Threshold	17052
k_CAVNodeAbsentDiag_Cnt_str.PStep	4531
k_CAVNodeAbsentDiag_Cnt_str.NStep	11419
k_CAVNodeAbsentTimeout_mS_u16	62362
k_CAVNodeTimeout_mS_u16	17425
k_CMM388MsgTimeout_mS_u16	2439
k_CMM388NTCEnableTimeout_mS_u16	25795
k_CMMNTCEnableTimeout_mS_u16	17505
k_CMMNodeAbsentDiag_Cnt_str.Threshold	53693
k_CMMNodeAbsentDiag_Cnt_str.PStep	57245
k_CMMNodeAbsentDiag_Cnt_str.NStep	40569
k_CMMNodeAbsentTimeout_mS_u16	44913
k_CONSANGLECPKMax_HwDeg_f32	100.272499
k_CONSANGLECPKMin_HwDeg_f32	-199.718796
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	6150
k_CONSANGLECPKSigValidThresh_Cnt_u16	6453
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	12834
k_CPKVehicleSpeedValidThresh_Cnt_u16	3288
k_CityParkInputInvalidThresh_Cnt_u16	5088

Name	Input Value
k_CityParkInputValidThresh_Cnt_u16	62252
k_ComputerRazGCTSigValidThresh_Cnt_u16	36591
k_CptTemporelSigValidThresh_Cnt_u16	13178
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	14500
k_DMDFCTCPKSigValidThresh_Cnt_u16	59947
k_DMDFCTCPKValidCount_Cnt_u16	55798
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	11922
k_DMDRELAXECPKSigValidThresh_Cnt_u16	60529
k_DMDRelaxeConsistentThresh_Cnt_u16	30231
k_DateValidThresh_Cnt_u16	12168
k_DefaultVehSpd_Kph_f32	71.2764969
k_DiagMuxOnAbsentTimeout_mS_u16	17541
k_EMNodeTimeout_mS_u16	60714
k_ESPNTCEnableTimeout_mS_u16	2104
k_ESPNodeAbsentDiag_Cnt_str.Threshold	5561
k_ESPNodeAbsentDiag_Cnt_str.PStep	18958
k_ESPNodeAbsentDiag_Cnt_str.NStep	33020
k_ESPNodeAbsentTimeout_mS_u16	55289
k_EtatMTSigInvalidThresh_Cnt_u16	39665
k_EtatMTSigValidThresh_Cnt_u16	55983
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	36821
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	2744
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	1245
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	5886
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	63689
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	61897
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	15904
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	5875
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	2127
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	35091
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	38126
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	14374
k_ISDATDIRASentDiag_Cnt_str.Threshold	2451
k_ISDATDIRASentDiag_Cnt_str.PStep	5266
k_ISDATDIRASentDiag_Cnt_str.NStep	3881
k_ISDATDIRASentTimeout_mS_u16	27638
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	50771
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	36476
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	37252
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	14010
k_ISDYNAASChkSumValidThresh_Cnt_u16	60216
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	33976
k_ISDYNAASMsgCountValidThresh_Cnt_u16	12687
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	38526
k_ISDYNAASMsgLenValidThresh_Cnt_u16	14656
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	33841
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	60482
k_ISDYNABRChkSumValidThresh_Cnt_u16	47177
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	19310
k_ISDYNABRMsgCountValidThresh_Cnt_u16	3109
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	42951
k_ISDYNABRMsgLenValidThresh_Cnt_u16	16346
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	41148
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	22129
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16118
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	44179
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	7327
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	4118
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	55935
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	8272
k_ISDYNVOLChkSumValidThresh_Cnt_u16	26443
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	39887
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	22012
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	48211
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	57942
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	40990
k_IgnOnTimeout_mS_u16	21644
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	9.35709953
k_PowerCutVehSpdLowThresh_Kph_f32	61.7398987
k_PowerCutVehSpdLowTimeout_mS_u16	42530
k_VBattMaxAAS_Volt_f32	16.9598999
k_VBattMaxBSI_Volt_f32	30.8201008

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMaxCAV_Volt_f32	22.2219009
k_VBattMaxCMM388_Volt_f32	19.059
k_VBattMaxCMM_Volt_f32	15.7812004
k_VBattMaxESP_Volt_f32	16.7938995
k_VBattMinAAS_Volt_f32	21.5275002
k_VBattMinBSI_Volt_f32	16.7938995
k_VBattMinCAV_Volt_f32	3.89689994
k_VBattMinCMM388_Volt_f32	9.70269966
k_VBattMinCMM_Volt_f32	9.25479984
k_VBattMinESP_Volt_f32	15.7812004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	10669
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	43352
k_VitesseVehicleBVRampValidThresh_Cnt_u16	5089
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	10042
k_VitesseVehicleBVSigValidThresh_Cnt_u16	21077
k_VitesseVehicleBVSpeedPassThresh_kph_f32	107.2379
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	12028
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	62475
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	63068160
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	18
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	18816
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3873991680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	192
target_SrlComInput_Per1_Batt_Volt_f32.value	11.1638002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4129015808
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	51
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.296008527
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	163
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2690611200
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1324718080
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	18
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1054586880
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3088177152
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	43513856
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1718491136
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	731133952
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	81
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	119
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	214
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	223
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	122
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	438491136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	85
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	117
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	180
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	197

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	199
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	928151552
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	896047104
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	885962752
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2486126592
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3019
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.480671316
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	364826
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	247.838699
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	36999

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	54881	54881	✔
AASNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	1	1	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3873991680	3873991680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	566.845093	566.845093	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26452	26452	✔
BSINodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	371378176	371378176	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	53693	53693	✔
CMMNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	53999	53999	✔
CONSANGLECPK_HwDeg_M_f32	717.402588	717.402588 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3873991680	3873991680	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3873991680	3873991680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3873991680	3873991680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3873991680	3873991680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3873991680	3873991680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3873991680	3873991680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3873991680	3873991680	✔
ESPNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	65	65	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3873991680	3873991680	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	56565	56565	✔
ElecIntTimer_mS_M_u32[1]	3873991680	3873991680	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3873991680	3873991680	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3873991680	3873991680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	885962752	885962752	✔
IgnOnTimer_mS_M_u32	4281694208	4281694208	✔
IgnTimeOff_Sec_M_u32	1155874523	1155874523	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	163	163	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2690611200	2690611200	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	12	12	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1324718080	1324718080	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	18	18	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1054586880	1054586880	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	253	253	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3088177152	3088177152	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1622718464	1622718464	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1718491136	1718491136	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	240	240	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	731133952	731133952	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	122	122	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	438491136	438491136	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	154	154	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	928151552	928151552	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	242	242	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	896047104	896047104	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	168	168	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	885962752	885962752	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2486126592	2486126592	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	315.398102	315.398102	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	325.610901	325.610901	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VitesseVehiculeRoues_Kph_M_f32	394.94809	394.94809	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	566.845093	566.845093	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	53999	53999	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1155874523	1155874523	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	717.402588	717.402588 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	71.2764969	71.2764969	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0151	0x0151	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	5	ValidityNTCProcessing	5	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.178 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1837157120
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	38569
AASNodeAbsentTimer_mS_M_u32	2955180800
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	7721
ANGLEVOLANTSigValidCount_Cnt_M_u16	3258
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	39626
AngleVolantMsgTimer_mS_M_u32	1837157120
AngleVolantValidCount_Cnt_M_u16	49541
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	363.643646
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1564949248

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1337441024
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1997794048
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	674343680
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	52978
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1716939520
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	1224
CAVNodeAbsentTimer_mS_M_u32	2640026368
CDD_SrlComVehSpd_Kph_G_f32	412.3367
CMM388NTCEnableTimer_mS_M_u32	1496636160
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2909379328
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	49958
CMMNodeAbsentTimer_mS_M_u32	3231951616
CONSANGLECPKSigInvalidCount_Cnt_M_u16	9662
CONSANGLECPKSigValidCount_Cnt_M_u16	32937
CONSANGLECPK_Cnt_M_u16	54832
CONSANGLECPK_HwDeg_M_f32	395.53421
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	54832
CPKVehicleSpeedMsgTimer_mS_M_u32	3031157504
CPKVehicleSpeedValidCount_Cnt_M_u16	61597
CityParkInputConsistentCount_Cnt_M_u16	54585
CityParkInputInvalidCount_Cnt_M_u16	19624
CityParkInputMsgTimer_mS_M_u32	2690611200
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2966977280
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	63581
ComputerRazGCTSigInvalidTimer_mS_M_u32	3152419584
ComputerRazGCTSigValidCount_Cnt_M_u16	32882
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	17652
DMDFCTCPKSigValidCount_Cnt_M_u16	15063
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	35897
DMDRELAXECPKSigValidCount_Cnt_M_u16	2324
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	55007
DateInvalidTimer_mS_M_u32	1337441024
DiagMuxOnAbsentTimer_mS_M_u32	2214955776
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	674343680
ESPNTCEnableTimer_mS_M_u32	2344188672
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	62126
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	55656
ElecIntTimer_mS_M_u32[1]	87787
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3171969792
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	46393
EtatMTSigValidCount_Cnt_M_u16	23024
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24728
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	2819
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	3301
ISDAT4V2BSI552MsgTimer_mS_M_u32	2690099968
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	3393
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	225
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	23024
ISDATBSI3F2MsgTimer_mS_M_u32	1093372672
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	50925

Name	Input Value
ISDATBSI412MsgLenValidCount_Cnt_M_u16	57468
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	46393
ISDATBSI412MsgTimer_mS_M_u32	682019584
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	49626
ISDATBSI432MsgLenValidCount_Cnt_M_u16	20578
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	3581
ISDATDIRASentFltAcc_Cnt_M_u16	2305
ISDATDIRASentTimer_mS_M_u32	3031157504
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	17366
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	49541
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	35847
ISDYN2CMMMsgTimer_mS_M_u32	715881216
ISDYNAASChkSumInvalidCount_Cnt_M_u16	49027
ISDYNAASChkSumValidCount_Cnt_M_u16	43134
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	1688
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	9103
ISDYNAASMsgLenValidCount_Cnt_M_u16	4962
ISDYNAASMsgTimeValidCount_Cnt_M_u16	49027
ISDYNAASMsgTimer_mS_M_u32	981523200
ISDYNABRChkSumInvalidCount_Cnt_M_u16	29328
ISDYNABRChkSumValidCount_Cnt_M_u16	64723
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	10518
ISDYNABRMsgCountValidCount_Cnt_M_u16	10833
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	3665
ISDYNABRMsgLenValidCount_Cnt_M_u16	49532
ISDYNABRMsgTimeValidCount_Cnt_M_u16	54832
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	727
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1339
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	23024
ISDYNCMM208MsgTimer_mS_M_u32	2176858880
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2759
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1445
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	20395
ISDYNCMM388MsgTimer_mS_M_u32	2066373376
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	64228
ISDYNVOLChkSumValidCount_Cnt_M_u16	1615
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	55578
ISDYNVOLMsgCountValidCount_Cnt_M_u16	49021
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	1051
ISDYNVOLMsgLenValidCount_Cnt_M_u16	870
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	49958
ISDYNVOLMsgTimer_mS_M_u32	3107068672
IgnOnTimer_mS_M_u32	2447268608
IgnTimeOff_Sec_M_u32	2016100202
ManVehSpd_Kph_M_f32	515.52771
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	191
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	206
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1788447488
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	213
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	621210368
PrevISDATBSI412MsgDLCError_Cnt_M_u08	181
PrevISDATBSI412MsgRxTime_MSec_M_u32	2488310528
PrevISDATBSI432MsgDLCError_Cnt_M_u08	2
PrevISDATBSI432MsgRxTime_MSec_M_u32	412973824
PrevISDATDIRAMsgTxTime_MSec_M_u32	2320800512
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	123
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2037721856
PrevISDYNAASMsgDLCError_Cnt_M_u08	180
PrevISDYNAASMsgRxTime_MSec_M_u32	249043712
PrevISDYNABRMsgDLCError_Cnt_M_u08	70
PrevISDYNABRMsgRxTime_MSec_M_u32	3816184576
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	126

Name	Input Value
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1322326784
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	162
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1864661760
PrevISDYNVOLMsgDLCError_Cnt_M_u08	2
PrevISDYNVOLMsgRxTime_MSec_M_u32	4144077568
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1926023936
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	275.457306
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	46517
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	5640
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	27298
VitesseVehicleBVRampValidCount_Cnt_M_u16	37557
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	62412
VitesseVehicleBVSigValidCount_Cnt_M_u16	2279
VitesseVehicleBV_Kph_M_f32	652.467773
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	20395
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	46047
VitesseVehiculeRoues_Kph_M_f32	376.514496
k_AASNTCEnableTimeout_mS_u16	155
k_AASNodeAbsentDiag_Cnt_str.Threshold	49353
k_AASNodeAbsentDiag_Cnt_str.PStep	14481
k_AASNodeAbsentDiag_Cnt_str.NStep	25307
k_AASNodeAbsentTimeout_mS_u16	16868
k_AASNodeTimeout_mS_u16	21768
k_ABSNodeTimeout_mS_u16	10285
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	52345
k_ANGLEVOLANTSigValidThresh_Cnt_u16	25665
k_AngleVolantInvalidThresh_Cnt_u16	38716
k_AngleVolantValidThresh_Cnt_u16	19624
k_BSI552MsgTimeout_mS_u16	65178
k_BSINTCEnableTimeout_mS_u16	17266
k_BSINodeAbsentDiag_Cnt_str.Threshold	26492
k_BSINodeAbsentDiag_Cnt_str.PStep	34281
k_BSINodeAbsentDiag_Cnt_str.NStep	15326
k_BSINodeAbsentTimeout_mS_u16	30306
k_BSINodeTimeout_mS_u16	3581
k_BattOvHi_Volt_f32	3.77979994
k_BattOvLo_Volt_f32	14.9210997
k_BattUvHi_Volt_f32	9.17409992
k_BattUvLo_Volt_f32	16.5051994
k_CAVNTCEnableTimeout_mS_u16	1390
k_CAVNodeAbsentDiag_Cnt_str.Threshold	46929
k_CAVNodeAbsentDiag_Cnt_str.PStep	29794
k_CAVNodeAbsentDiag_Cnt_str.NStep	45890
k_CAVNodeAbsentTimeout_mS_u16	44526
k_CAVNodeTimeout_mS_u16	24330
k_CMM388MsgTimeout_mS_u16	5545
k_CMM388NTCEnableTimeout_mS_u16	62453
k_CMMNTCEnableTimeout_mS_u16	6873
k_CMMNodeAbsentDiag_Cnt_str.Threshold	23318
k_CMMNodeAbsentDiag_Cnt_str.PStep	39565
k_CMMNodeAbsentDiag_Cnt_str.NStep	63059
k_CMMNodeAbsentTimeout_mS_u16	8235
k_CONSANGLECPKMax_HwDeg_f32	718.891479
k_CONSANGLECPKMin_HwDeg_f32	-501.241089
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	20139
k_CONSANGLECPKSigValidThresh_Cnt_u16	62175
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	15894

Name	Input Value
k_CPKVehicleSpeedValidThresh_Cnt_u16	44660
k_CityParkInputInvalidThresh_Cnt_u16	61982
k_CityParkInputValidThresh_Cnt_u16	54585
k_ComputerRazGCTSigValidThresh_Cnt_u16	62255
k_CptTemporelSigValidThresh_Cnt_u16	7503
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	36177
k_DMDFCTCPKSigValidThresh_Cnt_u16	32892
k_DMDFCTCPKValidCount_Cnt_u16	49754
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	35847
k_DMDRELAXECPKSigValidThresh_Cnt_u16	47658
k_DMDRelaxeConsistentThresh_Cnt_u16	13624
k_DateValidThresh_Cnt_u16	3301
k_DefaultVehSpd_Kph_f32	98.9157028
k_DiagMuxOnAbsentTimeout_mS_u16	22894
k_EMNodeTimeout_mS_u16	1983
k_ESPNTCEnableTimeout_mS_u16	26644
k_ESPNodeAbsentDiag_Cnt_str.Threshold	14081
k_ESPNodeAbsentDiag_Cnt_str.PStep	9243
k_ESPNodeAbsentDiag_Cnt_str.NStep	12458
k_ESPNodeAbsentTimeout_mS_u16	50835
k_EtatMTSigInvalidThresh_Cnt_u16	57579
k_EtatMTSigValidThresh_Cnt_u16	2414
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	45309
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	47124
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	42022
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	22274
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	51554
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	929
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	58139
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	36963
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	142
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	17348
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	30707
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	61836
k_ISDATDIRASentDiag_Cnt_str.Threshold	42732
k_ISDATDIRASentDiag_Cnt_str.PStep	3144
k_ISDATDIRASentDiag_Cnt_str.NStep	10267
k_ISDATDIRASentTimeout_mS_u16	49628
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	15109
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	39626
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	64560
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	29072
k_ISDYNAASChkSumValidThresh_Cnt_u16	15315
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	43030
k_ISDYNAASMsgCountValidThresh_Cnt_u16	59729
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	25156
k_ISDYNAASMsgLenValidThresh_Cnt_u16	8380
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	49321
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	27255
k_ISDYNABRChkSumValidThresh_Cnt_u16	3618
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	19954
k_ISDYNABRMsgCountValidThresh_Cnt_u16	54157
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	550
k_ISDYNABRMsgLenValidThresh_Cnt_u16	29102
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	12744
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	41321
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	4122
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	53955
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	56927
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	52154
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	31808
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	21516
k_ISDYNVOLChkSumValidThresh_Cnt_u16	22235
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	29135
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	2951
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	389
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	34620
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	37667
k_IgnOnTimeout_mS_u16	42840
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	183.173996
k_PowerCutVehSpdLowThresh_Kph_f32	34.0256004
k_PowerCutVehSpdLowTimeout_mS_u16	59543

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMaxAAS_Volt_f32	31.9741993
k_VBattMaxBSI_Volt_f32	10.8250999
k_VBattMaxCAV_Volt_f32	27.1912003
k_VBattMaxCMM388_Volt_f32	22.4862995
k_VBattMaxCMM_Volt_f32	18.6235008
k_VBattMaxESP_Volt_f32	4.33830023
k_VBattMinAAS_Volt_f32	6.89550018
k_VBattMinBSI_Volt_f32	4.33830023
k_VBattMinCAV_Volt_f32	1.85259998
k_VBattMinCMM388_Volt_f32	4.11679983
k_VBattMinCMM_Volt_f32	18.5767994
k_VBattMinESP_Volt_f32	18.6235008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	63735
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	4534
k_VitesseVehicleBVRampValidThresh_Cnt_u16	55322
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	50511
k_VitesseVehicleBVSigValidThresh_Cnt_u16	39870
k_VitesseVehicleBVSpeedPassThresh_kph_f32	121.175102
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	968
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	56411
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1337441024
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	199
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	56852
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2274721536
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	162
target_SrlComInput_Per1_Batt_Volt_f32.value	7.97660017
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3932908288
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	91
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.353503138
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3596638976
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1260256000
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1005296384
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3502848768
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	834067200
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2259974912
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	161
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4156693248
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	20
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	41
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	64
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	91
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	228
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	781597440
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	64
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	65
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	90
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	138

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	176
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	183
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	44
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2642893568
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	600111872
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3859979008
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	77
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	101
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3190876928
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3263
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.528777897
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	264607
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	188.978897
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	52007

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	39626	39626	✔
AngleVolantMsgTimer_mS_M_u32	2274721536	2274721536	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	363.643646	363.643646	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1564949248	1564949248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	1337441024	1337441024	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	1997794048	1997794048	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	674343680	674343680	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26492	26492	✔
BSINodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2259974912	2259974912	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	54832	54832	✔
CONSANGLECPK_HwDeg_M_f32	395.53421	395.53421 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	54832	54832	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3031157504	3031157504	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CPKVehicleSpeedValidCount_Cnt_M_u16	61597	61597	✔
CityParkInputConsistentCount_Cnt_M_u16	54585	54585	✔
CityParkInputInvalidCount_Cnt_M_u16	19626	19626	✔
CityParkInputMsgTimer_mS_M_u32	2274721536	2274721536	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2274721536	2274721536	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2274721536	2274721536	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1337441024	1337441024	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2274721536	2274721536	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	674343680	674343680	✔
ESPNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	14081	14081	✔
ESPNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2274721536	2274721536	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2274721536	2274721536	✔
ElecIntTimer_mS_M_u32[1]	87787	87787	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2274721536	2274721536	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24729	24729	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3596638976	3596638976	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	3394	3394	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1093372672	1093372672	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	50926	50926	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1005296384	1005296384	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	49626	49626	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3502848768	3502848768	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2274721536	2274721536	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2274721536	2274721536	✔
IgnOnTimer_mS_M_u32	2447268608	2447268608	✔
IgnTimeOff_Sec_M_u32	2016100202	2016100202	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	134	134	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3596638976	3596638976	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	43	43	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1260256000	1260256000	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	57	57	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1005296384	1005296384	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	215	215	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3502848768	3502848768	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2320800512	2320800512	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	99	99	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2259974912	2259974912	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	161	161	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4156693248	4156693248	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	228	228	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	781597440	781597440	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	44	44	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2642893568	2642893568	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	3	3	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	600111872	600111872	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	2	2	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3859979008	3859979008	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3190876928	3190876928	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	275.457306	275.457306	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	652.467773	652.467773	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	376.514496	376.514496	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	363.643646	363.643646	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	54832	54832	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2016100202	2016100202	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	395.53421	395.53421 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	98.9157028	98.9157028	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.179 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	175769856
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	63358

Name	Input Value
AASNodeAbsentTimer_mS_M_u32	2500606208
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0
ANGLEVOLANTSigValidCount_Cnt_M_u16	18830
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	18647
AngleVolantMsgTimer_mS_M_u32	175769856
AngleVolantValidCount_Cnt_M_u16	29278
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	371.888062
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3930650880
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1481996544
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	4076611840
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3978029312
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	43228
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3620382976
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	2860
CAVNodeAbsentTimer_mS_M_u32	2232572160
CDD_SrlComVehSpd_Kph_G_f32	609.939209
CMM388NTCEnableTimer_mS_M_u32	4159805696
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	741366016
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	31443
CMMNodeAbsentTimer_mS_M_u32	3397249280
CONSANGLECPKSigInvalidCount_Cnt_M_u16	23225
CONSANGLECPKSigValidCount_Cnt_M_u16	10807
CONSANGLECPK_Cnt_M_u16	48966
CONSANGLECPK_HwDeg_M_f32	780
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	48966
CPKVehicleSpeedMsgTimer_mS_M_u32	3305965824
CPKVehicleSpeedValidCount_Cnt_M_u16	12390
CityParkInputConsistentCount_Cnt_M_u16	36210
CityParkInputInvalidCount_Cnt_M_u16	25214
CityParkInputMsgTimer_mS_M_u32	3778842112
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1965046016
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	28818
ComputerRazGCTSigInvalidTimer_mS_M_u32	2699614464
ComputerRazGCTSigValidCount_Cnt_M_u16	41763
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	62314
DMDFCTCPKSigValidCount_Cnt_M_u16	5152
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	55211
DMDRELAXECPKSigValidCount_Cnt_M_u16	54680
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	12562
DateInvalidTimer_mS_M_u32	1481996544
DiagMuxOnAbsentTimer_mS_M_u32	1653131520
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3978029312
ESPNTCEnableTimer_mS_M_u32	389626112
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	51469
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	80
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3275008256
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1

Name	Input Value
EtatMTSigInvalidCount_Cnt_M_u16	63075
EtatMTSigValidCount_Cnt_M_u16	31821
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	53571
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	21569
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	60734
ISDAT4V2BSI552MsgTimer_mS_M_u32	1368516864
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	61853
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	31023
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	31821
ISDATBSI3F2MsgTimer_mS_M_u32	603900160
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	5182
ISDATBSI412MsgLenValidCount_Cnt_M_u16	44608
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	63075
ISDATBSI412MsgTimer_mS_M_u32	1508903168
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	59623
ISDATBSI432MsgLenValidCount_Cnt_M_u16	24097
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	30201
ISDATDIRASentFltAcc_Cnt_M_u16	61917
ISDATDIRASentTimer_mS_M_u32	3305965824
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	52540
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	29278
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	6309
ISDYN2CMMMsgTimer_mS_M_u32	1729837312
ISDYNAASChkSumInvalidCount_Cnt_M_u16	27656
ISDYNAASChkSumValidCount_Cnt_M_u16	15638
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	9625
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	61307
ISDYNAASMsgLenValidCount_Cnt_M_u16	22177
ISDYNAASMsgTimeValidCount_Cnt_M_u16	27656
ISDYNAASMsgTimer_mS_M_u32	1776130304
ISDYNABRChkSumInvalidCount_Cnt_M_u16	5698
ISDYNABRChkSumValidCount_Cnt_M_u16	32856
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	16323
ISDYNABRMsgCountValidCount_Cnt_M_u16	63249
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	30068
ISDYNABRMsgLenValidCount_Cnt_M_u16	27442
ISDYNABRMsgTimeValidCount_Cnt_M_u16	48966
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	725
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1335
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	31821
ISDYNCMM208MsgTimer_mS_M_u32	2134505728
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2751
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1441
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	48340
ISDYNCMM388MsgTimer_mS_M_u32	949688576
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	29743
ISDYNVOLChkSumValidCount_Cnt_M_u16	36909
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	37856
ISDYNVOLMsgCountValidCount_Cnt_M_u16	16662
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	22610
ISDYNVOLMsgLenValidCount_Cnt_M_u16	303
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	31443
ISDYNVOLMsgTimer_mS_M_u32	1322572032
IgnOnTimer_mS_M_u32	4272888064
IgnTimeOff_Sec_M_u32	2723163952
ManVehSpd_Kph_M_f32	492.786102
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	187
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	109
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2977745152
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	231
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1075259648
PrevISDATBSI412MsgDLCError_Cnt_M_u08	99

Name	Input Value
PrevISDATBSI412MsgRxTime_MSec_M_u32	1604278528
PrevISDATBSI432MsgDLCError_Cnt_M_u08	107
PrevISDATBSI432MsgRxTime_MSec_M_u32	1308440832
PrevISDATDIRAMsgTxTime_MSec_M_u32	3196279040
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	179
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1243834624
PrevISDYNAASMsgDLCError_Cnt_M_u08	228
PrevISDYNAASMsgRxTime_MSec_M_u32	80402688
PrevISDYNABRMsgDLCError_Cnt_M_u08	52
PrevISDYNABRMsgRxTime_MSec_M_u32	3112638720
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	51
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3107707136
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	124
PrevISDYNCMM388MsgRxTime_MSec_M_u32	470563072
PrevISDYNVOLMsgDLCError_Cnt_M_u08	100
PrevISDYNVOLMsgRxTime_MSec_M_u32	520640768
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2154170624
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	14.7355003
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	7665
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	37271
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	5302
VitesseVehicleBVRampValidCount_Cnt_M_u16	33308
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	14694
VitesseVehicleBVSigValidCount_Cnt_M_u16	40339
VitesseVehicleBV_Kph_M_f32	184.816895
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	48340
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	19801
VitesseVehiculeRoues_Kph_M_f32	533.886902
k_AASNTCEnableTimeout_mS_u16	37657
k_AASNodeAbsentDiag_Cnt_str.Threshold	10757
k_AASNodeAbsentDiag_Cnt_str.PStep	7105
k_AASNodeAbsentDiag_Cnt_str.NStep	65461
k_AASNodeAbsentTimeout_mS_u16	41349
k_AASNodeTimeout_mS_u16	39063
k_ABSNodeTimeout_mS_u16	33051
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	24654
k_ANGLEVOLANTSigValidThresh_Cnt_u16	25800
k_AngleVolantInvalidThresh_Cnt_u16	32939
k_AngleVolantValidThresh_Cnt_u16	25214
k_BSI552MsgTimeout_mS_u16	13052
k_BSINTCEnableTimeout_mS_u16	21439
k_BSINodeAbsentDiag_Cnt_str.Threshold	26412
k_BSINodeAbsentDiag_Cnt_str.PStep	34315
k_BSINodeAbsentDiag_Cnt_str.NStep	15280
k_BSINodeAbsentTimeout_mS_u16	48559
k_BSINodeTimeout_mS_u16	30201
k_BattOvHi_Volt_f32	24.6580009
k_BattOvLo_Volt_f32	6.23929977
k_BattUvHi_Volt_f32	18.0209999
k_BattUvLo_Volt_f32	14.5544004
k_CAVNTCEnableTimeout_mS_u16	1404
k_CAVNodeAbsentDiag_Cnt_str.Threshold	9850
k_CAVNodeAbsentDiag_Cnt_str.PStep	55599
k_CAVNodeAbsentDiag_Cnt_str.NStep	26463
k_CAVNodeAbsentTimeout_mS_u16	22690
k_CAVNodeTimeout_mS_u16	25765
k_CMM388MsgTimeout_mS_u16	15998

Name	Input Value
k_CMM388NTCEnableTimeout_mS_u16	1386
k_CMMNTCEnableTimeout_mS_u16	34933
k_CMMNodeAbsentDiag_Cnt_str.Threshold	32647
k_CMMNodeAbsentDiag_Cnt_str.PStep	42126
k_CMMNodeAbsentDiag_Cnt_str.NStep	57005
k_CMMNodeAbsentTimeout_mS_u16	45637
k_CONSANGLECPKMax_HwDeg_f32	504.541199
k_CONSANGLECPKMin_HwDeg_f32	-25.8943005
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	33748
k_CONSANGLECPKSigValidThresh_Cnt_u16	21593
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	37045
k_CPKVehicleSpeedValidThresh_Cnt_u16	11085
k_CityParkInputInvalidThresh_Cnt_u16	37088
k_CityParkInputValidThresh_Cnt_u16	36210
k_ComputerRazGCTSigValidThresh_Cnt_u16	30619
k_CptTemporelSigValidThresh_Cnt_u16	8621
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	48244
k_DMDFCTCPKSigValidThresh_Cnt_u16	62002
k_DMDFCTCPKValidCount_Cnt_u16	19204
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	6309
k_DMDRELAXECPKSigValidThresh_Cnt_u16	16283
k_DMDRelaxeConsistentThresh_Cnt_u16	47545
k_DateValidThresh_Cnt_u16	60734
k_DefaultVehSpd_Kph_f32	12.7447996
k_DiagMuxOnAbsentTimeout_mS_u16	11284
k_EMNodeTimeout_mS_u16	21234
k_ESPNTCEnableTimeout_mS_u16	28440
k_ESPNodeAbsentDiag_Cnt_str.Threshold	40274
k_ESPNodeAbsentDiag_Cnt_str.PStep	1844
k_ESPNodeAbsentDiag_Cnt_str.NStep	56738
k_ESPNodeAbsentTimeout_mS_u16	12141
k_EtatMTSigInvalidThresh_Cnt_u16	43653
k_EtatMTSigValidThresh_Cnt_u16	53467
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	61476
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	40302
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	20023
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	33686
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	50152
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	20562
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	30304
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	17498
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	38651
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	7482
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	25820
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	38196
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	1582
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	26405
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	18647
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	37204
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	56642
k_ISDYNAASChkSumValidThresh_Cnt_u16	34648
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	34499
k_ISDYNAASMsgCountValidThresh_Cnt_u16	32273
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	11606
k_ISDYNAASMsgLenValidThresh_Cnt_u16	43947
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	26608
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	40426
k_ISDYNABRChkSumValidThresh_Cnt_u16	8232
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	61404
k_ISDYNABRMsgCountValidThresh_Cnt_u16	24713
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	33235
k_ISDYNABRMsgLenValidThresh_Cnt_u16	4109
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	40364
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	20741
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	36163
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	55610
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	50721
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	53390
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	35670
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	39461

Name	Input Value
k_ISDYNVOLChkSumValidThresh_Cnt_u16	41831
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	32102
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	32364
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	15183
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	55865
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	1292
k_IgnOnTimeout_mS_u16	28177
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	16.2178993
k_PowerCutVehSpdLowThresh_Kph_f32	54.757
k_PowerCutVehSpdLowTimeout_mS_u16	41525
k_VBattMaxAAS_Volt_f32	27.3257008
k_VBattMaxBSI_Volt_f32	24.1021004
k_VBattMaxCAV_Volt_f32	20.5713997
k_VBattMaxCMM388_Volt_f32	15.9805002
k_VBattMaxCMM_Volt_f32	0.261500001
k_VBattMaxESP_Volt_f32	8.50699997
k_VBattMinAAS_Volt_f32	8.73379993
k_VBattMinBSI_Volt_f32	8.50699997
k_VBattMinCAV_Volt_f32	2.38120008
k_VBattMinCMM388_Volt_f32	9.5923996
k_VBattMinCMM_Volt_f32	26.6177006
k_VBattMinESP_Volt_f32	0.261500001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	40455
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	10680
k_VitesseVehicleBVRampValidThresh_Cnt_u16	23264
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	5933
k_VitesseVehicleBVSigValidThresh_Cnt_u16	65295
k_VitesseVehicleBVSpeedPassThresh_kph_f32	170.651398
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	53804
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	35858
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1481996544
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	61
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	124
target_SrlComInput_Per1_Batt_Volt_f32.value	14.8000002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3732384000
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	169
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.549080729
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	32
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2342590720
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1603909888
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	857889024
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3996842240
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2028181760
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3139188992
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	177
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2632243456
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	83
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	155

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	189
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	190
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	238
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	191
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3202349312
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	247
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	760224000
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3871914240
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1607555328
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2523998464
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3198
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0929407626
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	294557
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	169.473999
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	53331

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	175769856	175769856	✔
AASNTCsEnabled_Cnt_M_lgc	1	1	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2632243456	2632243456	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	1	1	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	371.888062	371.888062	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3930650880	3930650880	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	1481996544	1481996544	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3978029312	3978029312	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	27948	27948	✔
BSINodeAbsentTimer_mS_M_u32	3996842240	3996842240	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3620382976	3620382976	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1607555328	1607555328	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3139188992	3139188992	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	48966	48966	✔
CONSANGLECPK_HwDeg_M_f32	780	780 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3251510528	3251510528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	80	80	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1603909888	1603909888	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11906	11906	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2632243456	2632243456	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1607555328	1607555328	✔
IgnOnTimer_mS_M_u32	4272888064	4272888064	✔
IgnTimeOff_Sec_M_u32	2723163952	2723163952	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	32	32	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2342590720	2342590720	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	172	172	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1603909888	1603909888	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	194	194	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	857889024	857889024	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	77	77	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3996842240	3996842240	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2028181760	2028181760	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	92	92	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3139188992	3139188992	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	177	177	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2632243456	2632243456	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	191	191	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3202349312	3202349312	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	247	247	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	760224000	760224000	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	136	136	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3871914240	3871914240	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1607555328	1607555328	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2523998464	2523998464	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	14.7355003	14.7355003	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	184.816895	184.816895	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	533.886902	533.886902	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	371.888062	371.888062	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	48966	48966	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2723163952	2723163952	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	780	780 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	12.7447996	12.7447996	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	5	ValidityNTCProcessing	5	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.180 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4086605824
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	56967
AASNodeAbsentTimer_mS_M_u32	2560497664
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	65535
ANGLEVOLANTSigValidCount_Cnt_M_u16	42262
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	36476
AngleVolantMsgTimer_mS_M_u32	4086605824
AngleVolantValidCount_Cnt_M_u16	62568
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	618.410889
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2078791680
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	63068160
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1787709440
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2871986176
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	8302
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	371378176
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	33788
CAVNodeAbsentTimer_mS_M_u32	151762944
CDD_SrlComVehSpd_Kph_G_f32	493.679291
CMM388NTCEnableTimer_mS_M_u32	1030617088
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	196196352
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	48327
CMMNodeAbsentTimer_mS_M_u32	453576704
CONSANGLECPKSigInvalidCount_Cnt_M_u16	45525
CONSANGLECPKSigValidCount_Cnt_M_u16	38428
CONSANGLECPK_Cnt_M_u16	53999
CONSANGLECPK_HwDeg_M_f32	717.402588
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	53999
CPKVehicleSpeedMsgTimer_mS_M_u32	3487279104
CPKVehicleSpeedValidCount_Cnt_M_u16	54488
CityParkInputConsistentCount_Cnt_M_u16	62252
CityParkInputInvalidCount_Cnt_M_u16	62727
CityParkInputMsgTimer_mS_M_u32	2342590720
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1214388224
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	49995
ComputerRazGCTSigInvalidTimer_mS_M_u32	797456384
ComputerRazGCTSigValidCount_Cnt_M_u16	46617
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	62019
DMDFCTCPKSigValidCount_Cnt_M_u16	49890
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	36865
DMDRELAXECPKSigValidCount_Cnt_M_u16	43256
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	53962
DateInvalidTimer_mS_M_u32	63068160
DiagMuxOnAbsentTimer_mS_M_u32	2523424768
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2871986176
ESPNTCEnableTimer_mS_M_u32	102176768
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	5338
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	65
EffacDefaultDiagTimer_mS_M_u32[1]	3873991680
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	56565

Name	Input Value
ElecIntTimer_mS_M_u32[1]	3873991680
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2078590976
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	56087
EtatMTSigValidCount_Cnt_M_u16	19482
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	63031
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	49150
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	12168
ISDAT4V2BSI552MsgTimer_mS_M_u32	3586983936
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	43241
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	46324
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	19482
ISDATBSI3F2MsgTimer_mS_M_u32	2852546560
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	22021
ISDATBSI412MsgLenValidCount_Cnt_M_u16	60096
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	56087
ISDATBSI412MsgTimer_mS_M_u32	1563600896
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	49803
ISDATBSI432MsgLenValidCount_Cnt_M_u16	42398
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	46997
ISDATDIRASentFltAcc_Cnt_M_u16	54249
ISDATDIRASentTimer_mS_M_u32	3487279104
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	269
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	62568
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	11922
ISDYN2CMMMsgTimer_mS_M_u32	510728192
ISDYNAASChkSumInvalidCount_Cnt_M_u16	10473
ISDYNAASChkSumValidCount_Cnt_M_u16	18560
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	34487
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	54031
ISDYNAASMsgLenValidCount_Cnt_M_u16	36958
ISDYNAASMsgTimeValidCount_Cnt_M_u16	10473
ISDYNAASMsgTimer_mS_M_u32	2544498688
ISDYNABRChkSumInvalidCount_Cnt_M_u16	35770
ISDYNABRChkSumValidCount_Cnt_M_u16	56
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	22968
ISDYNABRMsgCountValidCount_Cnt_M_u16	50831
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	3492
ISDYNABRMsgLenValidCount_Cnt_M_u16	32555
ISDYNABRMsgTimeValidCount_Cnt_M_u16	53999
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	726
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1337
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	19482
ISDYNCMM208MsgTimer_mS_M_u32	3239368704
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2755
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1443
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	27910
ISDYNCMM388MsgTimer_mS_M_u32	24213504
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	48499
ISDYNVOLChkSumValidCount_Cnt_M_u16	48186
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	26849
ISDYNVOLMsgCountValidCount_Cnt_M_u16	37888
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	47883
ISDYNVOLMsgLenValidCount_Cnt_M_u16	37682
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	48327
ISDYNVOLMsgTimer_mS_M_u32	3586406400
IgnOnTimer_mS_M_u32	4281694208
IgnTimeOff_Sec_M_u32	1155874523
ManVehSpd_Kph_M_f32	324.040405
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	189
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	13

Name	Input Value
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	206
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2039244800
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	193
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2940028928
PrevISDATBSI412MsgDLCError_Cnt_M_u08	141
PrevISDATBSI412MsgRxTime_MSec_M_u32	3982800896
PrevISDATBSI432MsgDLCError_Cnt_M_u08	244
PrevISDATBSI432MsgRxTime_MSec_M_u32	1909135360
PrevISDATDIRAMsgTxTime_MSec_M_u32	1622718464
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	158
PrevISDYN2CMMMsgRxTime_MSec_M_u32	303597568
PrevISDYNAASMsgDLCError_Cnt_M_u08	74
PrevISDYNAASMsgRxTime_MSec_M_u32	199374848
PrevISDYNABRMsgDLCError_Cnt_M_u08	101
PrevISDYNABRMsgRxTime_MSec_M_u32	783120384
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	136
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4069472256
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	192
PrevISDYNCMM388MsgRxTime_MSec_M_u32	60692480
PrevISDYNVOLMsgDLCError_Cnt_M_u08	168
PrevISDYNVOLMsgRxTime_MSec_M_u32	2468984832
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1104193536
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	315.398102
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	40877
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	14204
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	3934
VitesseVehicleBVRampValidCount_Cnt_M_u16	47597
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	5840
VitesseVehicleBVSigValidCount_Cnt_M_u16	64775
VitesseVehicleBV_Kph_M_f32	325.610901
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	27910
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	11829
VitesseVehiculeRoues_Kph_M_f32	394.94809
k_AASNTCEnableTimeout_mS_u16	25462
k_AASNodeAbsentDiag_Cnt_str.Threshold	54881
k_AASNodeAbsentDiag_Cnt_str.PStep	64806
k_AASNodeAbsentDiag_Cnt_str.NStep	17792
k_AASNodeAbsentTimeout_mS_u16	49907
k_AASNodeTimeout_mS_u16	8828
k_ABSNodeTimeout_mS_u16	19760
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	47190
k_ANGLEVOLANTSigValidThresh_Cnt_u16	60841
k_AngleVolantInvalidThresh_Cnt_u16	58880
k_AngleVolantValidThresh_Cnt_u16	62727
k_BSI552MsgTimeout_mS_u16	51532
k_BSINTCEnableTimeout_mS_u16	57859
k_BSINodeAbsentDiag_Cnt_str.Threshold	26452
k_BSINodeAbsentDiag_Cnt_str.PStep	34298
k_BSINodeAbsentDiag_Cnt_str.NStep	15303
k_BSINodeAbsentTimeout_mS_u16	36852
k_BSINodeTimeout_mS_u16	46997
k_BattOvHi_Volt_f32	8.45180035
k_BattOvLo_Volt_f32	17.9729004
k_BattUvHi_Volt_f32	1.25820005
k_BattUvLo_Volt_f32	16.0695
k_CAVNTCEnableTimeout_mS_u16	1725
k_CAVNodeAbsentDiag_Cnt_str.Threshold	17052

Name	Input Value
k_CAVNodeAbsentDiag_Cnt_str.PStep	4531
k_CAVNodeAbsentDiag_Cnt_str.NStep	11419
k_CAVNodeAbsentTimeout_mS_u16	62362
k_CAVNodeTimeout_mS_u16	17425
k_CMM388MsgTimeout_mS_u16	2439
k_CMM388NTCEnableTimeout_mS_u16	25795
k_CMMNTCEnableTimeout_mS_u16	17505
k_CMMNodeAbsentDiag_Cnt_str.Threshold	53693
k_CMMNodeAbsentDiag_Cnt_str.PStep	57245
k_CMMNodeAbsentDiag_Cnt_str.NStep	40569
k_CMMNodeAbsentTimeout_mS_u16	44913
k_CONSANGLECPKMax_HwDeg_f32	100.272499
k_CONSANGLECPKMin_HwDeg_f32	-199.718796
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	6150
k_CONSANGLECPKSigValidThresh_Cnt_u16	6453
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	12834
k_CPKVehicleSpeedValidThresh_Cnt_u16	3288
k_CityParkInputInvalidThresh_Cnt_u16	5088
k_CityParkInputValidThresh_Cnt_u16	62252
k_ComputerRazGCTSigValidThresh_Cnt_u16	36591
k_CptTemporelSigValidThresh_Cnt_u16	13178
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	14500
k_DMDFCTCPKSigValidThresh_Cnt_u16	59947
k_DMDFCTCPKValidCount_Cnt_u16	55798
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	11922
k_DMDRELAXECPKSigValidThresh_Cnt_u16	60529
k_DMDRelaxeConsistentThresh_Cnt_u16	30231
k_DateValidThresh_Cnt_u16	12168
k_DefaultVehSpd_Kph_f32	71.2764969
k_DiagMuxOnAbsentTimeout_mS_u16	17541
k_EMNodeTimeout_mS_u16	60714
k_ESPNTCEnableTimeout_mS_u16	2104
k_ESPNodeAbsentDiag_Cnt_str.Threshold	5561
k_ESPNodeAbsentDiag_Cnt_str.PStep	18958
k_ESPNodeAbsentDiag_Cnt_str.NStep	33020
k_ESPNodeAbsentTimeout_mS_u16	55289
k_EtatMTSigInvalidThresh_Cnt_u16	39665
k_EtatMTSigValidThresh_Cnt_u16	55983
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	36821
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	2744
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	1245
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	5886
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	63689
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	61897
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	15904
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	5875
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	2127
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	35091
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	38126
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	14374
k_ISDATDIRASentDiag_Cnt_str.Threshold	2451
k_ISDATDIRASentDiag_Cnt_str.PStep	5266
k_ISDATDIRASentDiag_Cnt_str.NStep	3881
k_ISDATDIRASentTimeout_mS_u16	27638
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	50771
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	36476
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	37252
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	14010
k_ISDYNAASChkSumValidThresh_Cnt_u16	60216
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	33976
k_ISDYNAASMsgCountValidThresh_Cnt_u16	12687
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	38526
k_ISDYNAASMsgLenValidThresh_Cnt_u16	14656
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	33841
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	60482
k_ISDYNABRChkSumValidThresh_Cnt_u16	47177
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	19310
k_ISDYNABRMsgCountValidThresh_Cnt_u16	3109
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	42951
k_ISDYNABRMsgLenValidThresh_Cnt_u16	16346
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	41148
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	22129
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16118

Name	Input Value
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	44179
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	7327
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	4118
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	55935
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	8272
k_ISDYNVOLChkSumValidThresh_Cnt_u16	26443
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	39887
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	22012
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	48211
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	57942
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	40990
k_IgnOnTimeout_mS_u16	21644
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	9.35709953
k_PowerCutVehSpdLowThresh_Kph_f32	61.7398987
k_PowerCutVehSpdLowTimeout_mS_u16	42530
k_VBattMaxAAS_Volt_f32	16.9598999
k_VBattMaxBSI_Volt_f32	30.8201008
k_VBattMaxCAV_Volt_f32	22.2219009
k_VBattMaxCMM388_Volt_f32	19.059
k_VBattMaxCMM_Volt_f32	15.7812004
k_VBattMaxESP_Volt_f32	16.7938995
k_VBattMinAAS_Volt_f32	21.5275002
k_VBattMinBSI_Volt_f32	16.7938995
k_VBattMinCAV_Volt_f32	3.89689994
k_VBattMinCMM388_Volt_f32	9.70269966
k_VBattMinCMM_Volt_f32	9.25479984
k_VBattMinESP_Volt_f32	15.7812004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	10669
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	43352
k_VitesseVehicleBVRampValidThresh_Cnt_u16	5089
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	10042
k_VitesseVehicleBVSigValidThresh_Cnt_u16	21077
k_VitesseVehicleBVSpeedPassThresh_kph_f32	107.2379
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	12028
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	62475
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	63068160
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	18
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	18816
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3873991680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	192
target_SrlComInput_Per1_Batt_Volt_f32.value	11.1638002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4129015808
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	51
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.296008527
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	163
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2690611200
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1324718080
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	18
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1054586880
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3088177152
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	43513856
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1718491136

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	731133952
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	81
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	119
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	214
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	223
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	122
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	438491136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	85
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	117
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	180
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	197
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	199
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	928151552
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	896047104
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	885962752
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2486126592
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2425
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.480671316
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1044669
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	247.838699
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	36999

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	54881	54881	✔
AASNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	1	1	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3873991680	3873991680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	618.410889	618.410889	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26452	26452	✔
BSINodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	371378176	371378176	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	53693	53693	✔
CMMNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	53999	53999	✔
CONSANGLECPK_HwDeg_M_f32	717.402588	717.402588 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3873991680	3873991680	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3873991680	3873991680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3873991680	3873991680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3873991680	3873991680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3873991680	3873991680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3873991680	3873991680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3873991680	3873991680	✔
ESPNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	65	65	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3873991680	3873991680	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	56565	56565	✔
ElecIntTimer_mS_M_u32[1]	3873991680	3873991680	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3873991680	3873991680	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3873991680	3873991680	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	885962752	885962752	✔
IgnOnTimer_mS_M_u32	4281694208	4281694208	✔
IgnTimeOff_Sec_M_u32	1155874523	1155874523	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	163	163	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2690611200	2690611200	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	12	12	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1324718080	1324718080	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	18	18	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1054586880	1054586880	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	253	253	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3088177152	3088177152	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1622718464	1622718464	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1718491136	1718491136	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	240	240	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	731133952	731133952	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	122	122	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	438491136	438491136	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	154	154	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	928151552	928151552	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	242	242	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	896047104	896047104	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	168	168	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	885962752	885962752	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2486126592	2486126592	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	315.398102	315.398102	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	325.610901	325.610901	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	394.94809	394.94809	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	618.410889	618.410889	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	53999	53999	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1155874523	1155874523	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	717.402588	717.402588 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	71.2764969	71.2764969	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0151	0x0151	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	5	ValidityNTCProcessing	5	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.181 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1837157120
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	38569
AASNodeAbsentTimer_mS_M_u32	2955180800
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	7721
ANGLEVOLANTSigValidCount_Cnt_M_u16	3258
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	39626
AngleVolantMsgTimer_mS_M_u32	1837157120
AngleVolantValidCount_Cnt_M_u16	49541
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	38.6192627
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1564949248
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1337441024
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1997794048
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	674343680
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	52978
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1716939520
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	1224
CAVNodeAbsentTimer_mS_M_u32	2640026368
CDD_SrlComVehSpd_Kph_G_f32	412.3367
CMM388NTCEnableTimer_mS_M_u32	1496636160
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2909379328
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	49958
CMMNodeAbsentTimer_mS_M_u32	3231951616
CONSANGLECPKSigInvalidCount_Cnt_M_u16	9662
CONSANGLECPKSigValidCount_Cnt_M_u16	32937
CONSANGLECPK_Cnt_M_u16	54832
CONSANGLECPK_HwDeg_M_f32	395.53421
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	54832
CPKVehicleSpeedMsgTimer_mS_M_u32	3031157504
CPKVehicleSpeedValidCount_Cnt_M_u16	61597
CityParkInputConsistentCount_Cnt_M_u16	54585
CityParkInputInvalidCount_Cnt_M_u16	19624
CityParkInputMsgTimer_mS_M_u32	2690611200
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2966977280
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	63581
ComputerRazGCTSigInvalidTimer_mS_M_u32	3152419584
ComputerRazGCTSigValidCount_Cnt_M_u16	32882
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	17652
DMDFCTCPKSigValidCount_Cnt_M_u16	15063
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	35897
DMDRELAXECPKSigValidCount_Cnt_M_u16	2324
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	55007
DateInvalidTimer_mS_M_u32	1337441024
DiagMuxOnAbsentTimer_mS_M_u32	2214955776
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	674343680
ESPNTCEnableTimer_mS_M_u32	2344188672
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	62126
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0

Name	Input Value
ElecIntTimer_mS_M_u32[0]	55656
ElecIntTimer_mS_M_u32[1]	87787
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3171969792
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	46393
EtatMTSigValidCount_Cnt_M_u16	23024
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24728
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	2819
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	3301
ISDAT4V2BSI552MsgTimer_mS_M_u32	2690099968
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	3393
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	225
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	23024
ISDATBSI3F2MsgTimer_mS_M_u32	1093372672
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	50925
ISDATBSI412MsgLenValidCount_Cnt_M_u16	57468
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	46393
ISDATBSI412MsgTimer_mS_M_u32	682019584
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	49626
ISDATBSI432MsgLenValidCount_Cnt_M_u16	20578
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	3581
ISDATDIRASentFltAcc_Cnt_M_u16	2305
ISDATDIRASentTimer_mS_M_u32	3031157504
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	17366
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	49541
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	35847
ISDYN2CMMMsgTimer_mS_M_u32	715881216
ISDYNAASChkSumInvalidCount_Cnt_M_u16	49027
ISDYNAASChkSumValidCount_Cnt_M_u16	43134
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	1688
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	9103
ISDYNAASMsgLenValidCount_Cnt_M_u16	4962
ISDYNAASMsgTimeValidCount_Cnt_M_u16	49027
ISDYNAASMsgTimer_mS_M_u32	981523200
ISDYNABRChkSumInvalidCount_Cnt_M_u16	29328
ISDYNABRChkSumValidCount_Cnt_M_u16	64723
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	10518
ISDYNABRMsgCountValidCount_Cnt_M_u16	10833
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	3665
ISDYNABRMsgLenValidCount_Cnt_M_u16	49532
ISDYNABRMsgTimeValidCount_Cnt_M_u16	54832
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	727
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1339
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	23024
ISDYNCMM208MsgTimer_mS_M_u32	2176858880
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2759
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1445
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	20395
ISDYNCMM388MsgTimer_mS_M_u32	2066373376
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	64228
ISDYNVOLChkSumValidCount_Cnt_M_u16	1615
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	55578
ISDYNVOLMsgCountValidCount_Cnt_M_u16	49021
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	1051
ISDYNVOLMsgLenValidCount_Cnt_M_u16	870
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	49958
ISDYNVOLMsgTimer_mS_M_u32	3107068672
IgnOnTimer_mS_M_u32	2447268608
IgnTimeOff_Sec_M_u32	2016100202
ManVehSpd_Kph_M_f32	515.52771
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	191
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1

Name	Input Value
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	206
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1788447488
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	213
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	621210368
PrevISDATBSI412MsgDLCError_Cnt_M_u08	181
PrevISDATBSI412MsgRxTime_MSec_M_u32	2488310528
PrevISDATBSI432MsgDLCError_Cnt_M_u08	2
PrevISDATBSI432MsgRxTime_MSec_M_u32	412973824
PrevISDATDIRAMsgTxTime_MSec_M_u32	2320800512
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	123
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2037721856
PrevISDYNAASMsgDLCError_Cnt_M_u08	180
PrevISDYNAASMsgRxTime_MSec_M_u32	249043712
PrevISDYNABRMsgDLCError_Cnt_M_u08	70
PrevISDYNABRMsgRxTime_MSec_M_u32	3816184576
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	126
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1322326784
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	162
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1864661760
PrevISDYNVOLMsgDLCError_Cnt_M_u08	2
PrevISDYNVOLMsgRxTime_MSec_M_u32	4144077568
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1926023936
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	275.457306
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	46517
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	5640
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	27298
VitesseVehicleBVRampValidCount_Cnt_M_u16	37557
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	62412
VitesseVehicleBVSigValidCount_Cnt_M_u16	2279
VitesseVehicleBV_Kph_M_f32	652.467773
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	20395
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	46047
VitesseVehiculeRoues_Kph_M_f32	376.514496
k_AASNTCEnableTimeout_mS_u16	155
k_AASNodeAbsentDiag_Cnt_str.Threshold	49353
k_AASNodeAbsentDiag_Cnt_str.PStep	14481
k_AASNodeAbsentDiag_Cnt_str.NStep	25307
k_AASNodeAbsentTimeout_mS_u16	16868
k_AASNodeTimeout_mS_u16	21768
k_ABSNodeTimeout_mS_u16	10285
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	52345
k_ANGLEVOLANTSigValidThresh_Cnt_u16	25665
k_AngleVolantInvalidThresh_Cnt_u16	38716
k_AngleVolantValidThresh_Cnt_u16	19624
k_BSI552MsgTimeout_mS_u16	65178
k_BSINTCEnableTimeout_mS_u16	17266
k_BSINodeAbsentDiag_Cnt_str.Threshold	26492
k_BSINodeAbsentDiag_Cnt_str.PStep	34281
k_BSINodeAbsentDiag_Cnt_str.NStep	15326
k_BSINodeAbsentTimeout_mS_u16	30306
k_BSINodeTimeout_mS_u16	3581
k_BattOvHi_Volt_f32	3.77979994
k_BattOvLo_Volt_f32	14.9210997
k_BattUvHi_Volt_f32	9.17409992
k_BattUvLo_Volt_f32	16.5051994
k_CAVNTCEnableTimeout_mS_u16	1390

Name	Input Value
k_CAVNodeAbsentDiag_Cnt_str.Threshold	46929
k_CAVNodeAbsentDiag_Cnt_str.PStep	29794
k_CAVNodeAbsentDiag_Cnt_str.NStep	45890
k_CAVNodeAbsentTimeout_mS_u16	44526
k_CAVNodeTimeout_mS_u16	24330
k_CMM388MsgTimeout_mS_u16	5545
k_CMM388NTCEnableTimeout_mS_u16	62453
k_CMMNTCEnableTimeout_mS_u16	6873
k_CMMNodeAbsentDiag_Cnt_str.Threshold	23318
k_CMMNodeAbsentDiag_Cnt_str.PStep	39565
k_CMMNodeAbsentDiag_Cnt_str.NStep	63059
k_CMMNodeAbsentTimeout_mS_u16	8235
k_CONSANGLECPKMax_HwDeg_f32	718.891479
k_CONSANGLECPKMin_HwDeg_f32	-501.241089
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	20139
k_CONSANGLECPKSigValidThresh_Cnt_u16	62175
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	15894
k_CPKVehicleSpeedValidThresh_Cnt_u16	44660
k_CityParkInputInvalidThresh_Cnt_u16	61982
k_CityParkInputValidThresh_Cnt_u16	54585
k_ComputerRazGCTSigValidThresh_Cnt_u16	62255
k_CptTemporelSigValidThresh_Cnt_u16	7503
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	36177
k_DMDFCTCPKSigValidThresh_Cnt_u16	32892
k_DMDFCTCPKValidCount_Cnt_u16	49754
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	35847
k_DMDRELAXECPKSigValidThresh_Cnt_u16	47658
k_DMDRelaxeConsistentThresh_Cnt_u16	13624
k_DateValidThresh_Cnt_u16	3301
k_DefaultVehSpd_Kph_f32	98.9157028
k_DiagMuxOnAbsentTimeout_mS_u16	22894
k_EMNodeTimeout_mS_u16	1983
k_ESPNTCEnableTimeout_mS_u16	26644
k_ESPNodeAbsentDiag_Cnt_str.Threshold	14081
k_ESPNodeAbsentDiag_Cnt_str.PStep	9243
k_ESPNodeAbsentDiag_Cnt_str.NStep	12458
k_ESPNodeAbsentTimeout_mS_u16	50835
k_EtatMTSigInvalidThresh_Cnt_u16	57579
k_EtatMTSigValidThresh_Cnt_u16	2414
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	45309
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	47124
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	42022
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	22274
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	51554
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	929
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	58139
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	36963
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	142
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	17348
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	30707
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	61836
k_ISDATDIRASentDiag_Cnt_str.Threshold	42732
k_ISDATDIRASentDiag_Cnt_str.PStep	3144
k_ISDATDIRASentDiag_Cnt_str.NStep	10267
k_ISDATDIRASentTimeout_mS_u16	49628
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	15109
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	39626
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	64560
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	29072
k_ISDYNAASChkSumValidThresh_Cnt_u16	15315
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	43030
k_ISDYNAASMsgCountValidThresh_Cnt_u16	59729
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	25156
k_ISDYNAASMsgLenValidThresh_Cnt_u16	8380
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	49321
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	27255
k_ISDYNABRChkSumValidThresh_Cnt_u16	3618
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	19954
k_ISDYNABRMsgCountValidThresh_Cnt_u16	54157
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	550
k_ISDYNABRMsgLenValidThresh_Cnt_u16	29102
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	12744
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	41321

Name	Input Value
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	4122
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	53955
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	56927
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	52154
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	31808
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	21516
k_ISDYNVOLChkSumValidThresh_Cnt_u16	22235
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	29135
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	2951
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	389
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	34620
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	37667
k_IgnOnTimeout_mS_u16	42840
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	183.173996
k_PowerCutVehSpdLowThresh_Kph_f32	34.0256004
k_PowerCutVehSpdLowTimeout_mS_u16	59543
k_VBattMaxAAS_Volt_f32	31.9741993
k_VBattMaxBSI_Volt_f32	10.8250999
k_VBattMaxCAV_Volt_f32	27.1912003
k_VBattMaxCMM388_Volt_f32	22.4862995
k_VBattMaxCMM_Volt_f32	18.6235008
k_VBattMaxESP_Volt_f32	4.33830023
k_VBattMinAAS_Volt_f32	6.89550018
k_VBattMinBSI_Volt_f32	4.33830023
k_VBattMinCAV_Volt_f32	1.85259998
k_VBattMinCMM388_Volt_f32	4.11679983
k_VBattMinCMM_Volt_f32	18.5767994
k_VBattMinESP_Volt_f32	18.6235008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	63735
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	4534
k_VitesseVehicleBVRampValidThresh_Cnt_u16	55322
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	50511
k_VitesseVehicleBVSigValidThresh_Cnt_u16	39870
k_VitesseVehicleBVSpeedPassThresh_kph_f32	121.175102
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	968
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	56411
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1337441024
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	199
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	56852
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2274721536
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	162
target_SrlComInput_Per1_Batt_Volt_f32.value	7.97660017
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3932908288
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	91
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.353503138
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3596638976
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1260256000
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1005296384
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3502848768
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	834067200
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	99

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2259974912
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	161
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4156693248
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	20
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	41
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	64
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	91
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	228
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	781597440
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	64
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	65
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	90
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	176
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	183
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	44
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2642893568
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	600111872
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3859979008
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	77
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	101
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3190876928
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3040
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.528777897
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	115575
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	188.978897
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	52007

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	39626	39626	✔
AngleVolantMsgTimer_mS_M_u32	2274721536	2274721536	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	38.6192627	38.6192627	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1564949248	1564949248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	1337441024	1337441024	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	1997794048	1997794048	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	674343680	674343680	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26492	26492	✔
BSINodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2259974912	2259974912	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	54832	54832	✔
CONSANGLECPK_HwDeg_M_f32	395.53421	395.53421 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	54832	54832	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3031157504	3031157504	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	61597	61597	✔
CityParkInputConsistentCount_Cnt_M_u16	54585	54585	✔
CityParkInputInvalidCount_Cnt_M_u16	19626	19626	✔
CityParkInputMsgTimer_mS_M_u32	2274721536	2274721536	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2274721536	2274721536	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2274721536	2274721536	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1337441024	1337441024	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2274721536	2274721536	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	674343680	674343680	✔
ESPNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	14081	14081	✔
ESPNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2274721536	2274721536	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2274721536	2274721536	✔
ElecIntTimer_mS_M_u32[1]	87787	87787	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2274721536	2274721536	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24729	24729	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3596638976	3596638976	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	3394	3394	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1093372672	1093372672	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	50926	50926	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1005296384	1005296384	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	49626	49626	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3502848768	3502848768	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDATDIRASentTimer_mS_M_u32	2274721536	2274721536	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2274721536	2274721536	✔
IgnOnTimer_mS_M_u32	2447268608	2447268608	✔
IgnTimeOff_Sec_M_u32	2016100202	2016100202	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	134	134	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3596638976	3596638976	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	43	43	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1260256000	1260256000	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	57	57	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1005296384	1005296384	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	215	215	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3502848768	3502848768	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2320800512	2320800512	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	99	99	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2259974912	2259974912	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	161	161	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4156693248	4156693248	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	228	228	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	781597440	781597440	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	44	44	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2642893568	2642893568	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	3	3	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	600111872	600111872	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	2	2	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3859979008	3859979008	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3190876928	3190876928	✔
PrevModeDiag_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevSrlComVehSpd_Kph_M_f32	275.457306	275.457306	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	652.467773	652.467773	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	376.514496	376.514496	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	38.6192627	38.6192627	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	54832	54832	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2016100202	2016100202	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	395.53421	395.53421 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	98.9157028	98.9157028	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.182 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1000632320
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	15526
AASNodeAbsentTimer_mS_M_u32	3632521216
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	62351
ANGLEVOLANTSigValidCount_Cnt_M_u16	50380
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	62139
AngleVolantMsgTimer_mS_M_u32	1000632320
AngleVolantValidCount_Cnt_M_u16	44892
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	407.96637
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	363175936
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1821384704
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1933709312
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1125830656
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	64190
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2888208384
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	19520

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CAVNodeAbsentTimer_mS_M_u32	3323297792
CDD_SrlComVehSpd_Kph_G_f32	322.161011
CMM388NTCEnableTimer_mS_M_u32	3089088512
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1719369728
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	55737
CMMNodeAbsentTimer_mS_M_u32	624218112
CONSANGLECPKSigInvalidCount_Cnt_M_u16	44317
CONSANGLECPKSigValidCount_Cnt_M_u16	33066
CONSANGLECPK_Cnt_M_u16	15581
CONSANGLECPK_HwDeg_M_f32	66.1390991
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	15581
CPKVehicleSpeedMsgTimer_mS_M_u32	323710976
CPKVehicleSpeedValidCount_Cnt_M_u16	370
CityParkInputConsistentCount_Cnt_M_u16	36000
CityParkInputInvalidCount_Cnt_M_u16	10435
CityParkInputMsgTimer_mS_M_u32	2032173312
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	113762304
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	49130
ComputerRazGCTSigInvalidTimer_mS_M_u32	4074897408
ComputerRazGCTSigValidCount_Cnt_M_u16	26797
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	51071
DMDFCTCPKSigValidCount_Cnt_M_u16	55012
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	24881
DMDRELAXECPKSigValidCount_Cnt_M_u16	34798
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	29746
DateInvalidTimer_mS_M_u32	1821384704
DiagMuxOnAbsentTimer_mS_M_u32	2828021760
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1125830656
ESPNTCEnableTimer_mS_M_u32	580706304
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	60690
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	201
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	9
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3710423040
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	11985
EtatMTSigValidCount_Cnt_M_u16	24857
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	32959
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	10828
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	8522
ISDAT4V2BSI552MsgTimer_mS_M_u32	1048104960
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	42879
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	8656
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	24857
ISDATBSI3F2MsgTimer_mS_M_u32	753807360
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	61571
ISDATBSI412MsgLenValidCount_Cnt_M_u16	37252
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	11985
ISDATBSI412MsgTimer_mS_M_u32	3590483968
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	7677
ISDATBSI432MsgLenValidCount_Cnt_M_u16	40022
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	20601
ISDATDIRASentFltAcc_Cnt_M_u16	54605
ISDATDIRASentTimer_mS_M_u32	323710976
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	60347
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	44892
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52270
ISDYN2CMMMsgTimer_mS_M_u32	2100748288

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNAASChkSumInvalidCount_Cnt_M_u16	54856
ISDYNAASChkSumValidCount_Cnt_M_u16	51109
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	51723
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	49715
ISDYNAASMsgLenValidCount_Cnt_M_u16	56392
ISDYNAASMsgTimeValidCount_Cnt_M_u16	54856
ISDYNAASMsgTimer_mS_M_u32	3554394112
ISDYNABRChkSumInvalidCount_Cnt_M_u16	60805
ISDYNABRChkSumValidCount_Cnt_M_u16	60618
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	8055
ISDYNABRMsgCountValidCount_Cnt_M_u16	58900
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	332
ISDYNABRMsgLenValidCount_Cnt_M_u16	60057
ISDYNABRMsgTimeValidCount_Cnt_M_u16	15581
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	157
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	199
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	24857
ISDYNCMM208MsgTimer_mS_M_u32	468885504
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	479
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	305
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	47290
ISDYNCMM388MsgTimer_mS_M_u32	2245214208
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	10619
ISDYNVOLChkSumValidCount_Cnt_M_u16	10248
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	36573
ISDYNVOLMsgCountValidCount_Cnt_M_u16	2242
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	56035
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	55737
ISDYNVOLMsgTimer_mS_M_u32	3667787776
IgnOnTimer_mS_M_u32	3256303616
IgnTimeOff_Sec_M_u32	2605544015
ManVehSpd_Kph_M_f32	79.032402
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	93
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	170
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2251567104
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	143
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	475074560
PrevISDATBSI412MsgDLCError_Cnt_M_u08	193
PrevISDATBSI412MsgRxTime_MSec_M_u32	3004071936
PrevISDATBSI432MsgDLCError_Cnt_M_u08	65
PrevISDATBSI432MsgRxTime_MSec_M_u32	4073775104
PrevISDATDIRAMsgTxTime_MSec_M_u32	4007821312
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	180
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3111407616
PrevISDYNAASMsgDLCError_Cnt_M_u08	42
PrevISDYNAASMsgRxTime_MSec_M_u32	2440822784
PrevISDYNABRMsgDLCError_Cnt_M_u08	42
PrevISDYNABRMsgRxTime_MSec_M_u32	1418674176
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	198
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2840133632
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	132
PrevISDYNCMM388MsgRxTime_MSec_M_u32	595845120
PrevISDYNVOLMsgDLCError_Cnt_M_u08	224
PrevISDYNVOLMsgRxTime_MSec_M_u32	1358135296
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3412094976
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	258.130402
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime

Name	Input Value
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	40849
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	42022
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	50914
VitesseVehicleBVRampValidCount_Cnt_M_u16	22071
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	49248
VitesseVehicleBVSigValidCount_Cnt_M_u16	15453
VitesseVehicleBV_Kph_M_f32	542.913086
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	47290
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	8879
VitesseVehiculeRoues_Kph_M_f32	36.6309013
k_AASNTCEnableTimeout_mS_u16	45252
k_AASNodeAbsentDiag_Cnt_str.Threshold	47636
k_AASNodeAbsentDiag_Cnt_str.PStep	34578
k_AASNodeAbsentDiag_Cnt_str.NStep	62563
k_AASNodeAbsentTimeout_mS_u16	1991
k_AASNodeTimeout_mS_u16	28454
k_ABSNodeTimeout_mS_u16	15244
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	26024
k_ANGLEVOLANTSigValidThresh_Cnt_u16	56897
k_AngleVolantInvalidThresh_Cnt_u16	60408
k_AngleVolantValidThresh_Cnt_u16	10435
k_BSI552MsgTimeout_mS_u16	19238
k_BSINTCEnableTimeout_mS_u16	41077
k_BSINodeAbsentDiag_Cnt_str.Threshold	3692
k_BSINodeAbsentDiag_Cnt_str.PStep	43971
k_BSINodeAbsentDiag_Cnt_str.NStep	2216
k_BSINodeAbsentTimeout_mS_u16	38707
k_BSINodeTimeout_mS_u16	20601
k_BattOvHi_Volt_f32	22.5207005
k_BattOvLo_Volt_f32	8.83209991
k_BattUvHi_Volt_f32	9.60820007
k_BattUvLo_Volt_f32	6.42689991
k_CAVNTCEnableTimeout_mS_u16	3065
k_CAVNodeAbsentDiag_Cnt_str.Threshold	14101
k_CAVNodeAbsentDiag_Cnt_str.PStep	13590
k_CAVNodeAbsentDiag_Cnt_str.NStep	2667
k_CAVNodeAbsentTimeout_mS_u16	44190
k_CAVNodeTimeout_mS_u16	217
k_CMM388MsgTimeout_mS_u16	18342
k_CMM388NTCEnableTimeout_mS_u16	1122
k_CMMNTCEnableTimeout_mS_u16	9719
k_CMMNodeAbsentDiag_Cnt_str.Threshold	62414
k_CMMNodeAbsentDiag_Cnt_str.PStep	42715
k_CMMNodeAbsentDiag_Cnt_str.NStep	22076
k_CMMNodeAbsentTimeout_mS_u16	50539
k_CONSANGLECPKMax_HwDeg_f32	647.885071
k_CONSANGLECPKMin_HwDeg_f32	-305.664612
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	17338
k_CONSANGLECPKSigValidThresh_Cnt_u16	60847
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	15500
k_CPKVehicleSpeedValidThresh_Cnt_u16	26166
k_CityParkInputInvalidThresh_Cnt_u16	875
k_CityParkInputValidThresh_Cnt_u16	36000
k_ComputerRazGCTSigValidThresh_Cnt_u16	42821
k_CptTemporelSigValidThresh_Cnt_u16	35350
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	3148
k_DMDFCTCPKSigValidThresh_Cnt_u16	13721
k_DMDFCTCPKValidCount_Cnt_u16	61766
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	52270
k_DMDRELAXECPKSigValidThresh_Cnt_u16	20691
k_DMDRelaxeConsistentThresh_Cnt_u16	55353
k_DateValidThresh_Cnt_u16	8522

Name	Input Value
k_DefaultVehSpd_Kph_f32	151.791306
k_DiagMuxOnAbsentTimeout_mS_u16	4659
k_EMNodeTimeout_mS_u16	27282
k_ESPNTCEnableTimeout_mS_u16	53756
k_ESPNodeAbsentDiag_Cnt_str.Threshold	62971
k_ESPNodeAbsentDiag_Cnt_str.PStep	11352
k_ESPNodeAbsentDiag_Cnt_str.NStep	60169
k_ESPNodeAbsentTimeout_mS_u16	35571
k_EtatMTSigInvalidThresh_Cnt_u16	15900
k_EtatMTSigValidThresh_Cnt_u16	20641
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	34079
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	52552
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	38385
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	4020
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	47045
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	35527
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	33714
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	20427
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	41537
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	52609
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	31138
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	29963
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	20289
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	25688
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	62139
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	5832
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	30853
k_ISDYNAASChkSumValidThresh_Cnt_u16	47050
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	10871
k_ISDYNAASMsgCountValidThresh_Cnt_u16	12564
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	22217
k_ISDYNAASMsgLenValidThresh_Cnt_u16	25706
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	53705
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	12458
k_ISDYNABRChkSumValidThresh_Cnt_u16	33911
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	1470
k_ISDYNABRMsgCountValidThresh_Cnt_u16	27707
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	42169
k_ISDYNABRMsgLenValidThresh_Cnt_u16	63506
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	65074
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	13525
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	39188
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	59037
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	65167
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	4044
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	12603
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	23726
k_ISDYNVOLChkSumValidThresh_Cnt_u16	22511
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	55847
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	33038
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	12685
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	14549
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	21920
k_IgnOnTimeout_mS_u16	37482
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	142.387497
k_PowerCutVehSpdLowThresh_Kph_f32	82.0203018
k_PowerCutVehSpdLowTimeout_mS_u16	60144
k_VBattMaxAAS_Volt_f32	11.4912996
k_VBattMaxBSI_Volt_f32	17.6352997
k_VBattMaxCAV_Volt_f32	15.0909004
k_VBattMaxCMM388_Volt_f32	6.86420012
k_VBattMaxCMM_Volt_f32	1.32550001
k_VBattMaxESP_Volt_f32	12.4805002
k_VBattMinAAS_Volt_f32	26.4710999
k_VBattMinBSI_Volt_f32	12.4805002
k_VBattMinCAV_Volt_f32	3.76609993
k_VBattMinCMM388_Volt_f32	27.7071991
k_VBattMinCMM_Volt_f32	26.6096992
k_VBattMinESP_Volt_f32	1.32550001

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	59890
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	48099
k_VitesseVehicleBVRampValidThresh_Cnt_u16	6621
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	29448
k_VitesseVehicleBVSigValidThresh_Cnt_u16	1641
k_VitesseVehicleBVSpeedPassThresh_kph_f32	634.463013
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	55104
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	37141
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1821384704
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	58
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	132
target_SrlComInput_Per1_Batt_Volt_f32.value	8.25549984
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2025820160
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	129
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.902174652
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2004959232
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	140
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3238748160
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3991240704
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	56
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1175429120
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	294240256
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2555633664
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	577634304
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	48
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	80
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	200
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1002479616
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	24
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	62
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	166
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	22298624
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3395182592
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	918061056
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	7

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	17
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	48
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	85
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	130
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	169
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4202893312
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3670
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.697941124
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	993682
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	166.751999
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	41643

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	577634304	577634304	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	1	1	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	407.96637	407.96637	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	61974	61974	✔
BSINodeAbsentTimer_mS_M_u32	1175429120	1175429120	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2888208384	2888208384	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	16853	16853	✔
CAVNodeAbsentTimer_mS_M_u32	918061056	918061056	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	33661	33661	✔
CMMNodeAbsentTimer_mS_M_u32	2555633664	2555633664	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	15581	15581	✔
CONSANGLECPK_HwDeg_M_f32	66.1390991	66.1390991 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2006148864	2006148864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	62971	62971	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔
EffacDefaultDiagTimer_mS_M_u32[1]	201	201	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	8	8	✔
ElecIntTimer_mS_M_u32[1]	9	9	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	49365	49365	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	918061056	918061056	✔
IgnOnTimer_mS_M_u32	3256303616	3256303616	✔
IgnTimeOff_Sec_M_u32	2605544015	2605544015	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	121	121	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2004959232	2004959232	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	140	140	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3238748160	3238748160	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3991240704	3991240704	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	56	56	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1175429120	1175429120	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	294240256	294240256	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2555633664	2555633664	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	192	192	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	577634304	577634304	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	192	192	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1002479616	1002479616	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	22298624	22298624	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	253	253	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3395182592	3395182592	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	918061056	918061056	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4202893312	4202893312	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	258.130402	258.130402	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	542.913086	542.913086	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	36.6309013	36.6309013	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	407.96637	407.96637	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	15581	15581	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2605544015	2605544015	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	66.1390991	66.1390991 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	151.791306	151.791306	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x010A	0x010A	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0151	0x0151	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	5	ValidityNTCProcessing	5	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.183 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1852928768
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	38249
AASNodeAbsentTimer_mS_M_u32	2710774528
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	45744
ANGLEVOLANTSigValidCount_Cnt_M_u16	40633
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	1834
AngleVolantMsgTimer_mS_M_u32	1852928768
AngleVolantValidCount_Cnt_M_u16	63946
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	564.94812
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2704139008
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1718510336
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3323499264
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2844676864
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	6435
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1298862848
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	21789
CAVNodeAbsentTimer_mS_M_u32	2807972608
CDD_SrlComVehSpd_Kph_G_f32	601.605896
CMM388NTCEnableTimer_mS_M_u32	3393159936

Name	Input Value
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3727442688
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	19825
CMMNodeAbsentTimer_mS_M_u32	3946861312
CONSANGLECPKSigInvalidCount_Cnt_M_u16	60679
CONSANGLECPKSigValidCount_Cnt_M_u16	4256
CONSANGLECPK_Cnt_M_u16	27015
CONSANGLECPK_HwDeg_M_f32	600.059509
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	27015
CPKVehicleSpeedMsgTimer_mS_M_u32	1132229376
CPKVehicleSpeedValidCount_Cnt_M_u16	15599
CityParkInputConsistentCount_Cnt_M_u16	29182
CityParkInputInvalidCount_Cnt_M_u16	14996
CityParkInputMsgTimer_mS_M_u32	2004959232
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	650584832
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	7069
ComputerRazGCTSigInvalidTimer_mS_M_u32	4076389120
ComputerRazGCTSigValidCount_Cnt_M_u16	20951
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	20064
DMDFCTCPKSigValidCount_Cnt_M_u16	8178
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	29130
DMDRELAXECPKSigValidCount_Cnt_M_u16	23891
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	11208
DateInvalidTimer_mS_M_u32	1718510336
DiagMuxOnAbsentTimer_mS_M_u32	2259563264
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2844676864
ESPNTCEnableTimer_mS_M_u32	1732780800
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	58150
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	66
EffacDefaultDiagTimer_mS_M_u32[1]	78
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	16
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1113920256
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	47915
EtatMTSigValidCount_Cnt_M_u16	46096
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	31265
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	7482
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	22720
ISDAT4V2BSI552MsgTimer_mS_M_u32	2943636224
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	33440
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	50029
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	46096
ISDATBSI3F2MsgTimer_mS_M_u32	4053021440
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	2195
ISDATBSI412MsgLenValidCount_Cnt_M_u16	38225
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	47915
ISDATBSI412MsgTimer_mS_M_u32	2539090688
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	37029
ISDATBSI432MsgLenValidCount_Cnt_M_u16	58714
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	27762
ISDATDIRASentFltAcc_Cnt_M_u16	11766
ISDATDIRASentTimer_mS_M_u32	1132229376
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	21741
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	63946
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	48211
ISDYN2CMMMsgTimer_mS_M_u32	1064968960
ISDYNAASChkSumInvalidCount_Cnt_M_u16	53379
ISDYNAASChkSumValidCount_Cnt_M_u16	56365
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	9661

Name	Input Value
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	32580
ISDYNAASMsgLenValidCount_Cnt_M_u16	61637
ISDYNAASMsgTimeValidCount_Cnt_M_u16	53379
ISDYNAASMsgTimer_mS_M_u32	1728807680
ISDYNABRChkSumInvalidCount_Cnt_M_u16	5709
ISDYNABRChkSumValidCount_Cnt_M_u16	38974
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	28918
ISDYNABRMsgCountValidCount_Cnt_M_u16	64736
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	27770
ISDYNABRMsgLenValidCount_Cnt_M_u16	20563
ISDYNABRMsgTimeValidCount_Cnt_M_u16	27015
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	141
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	167
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	46096
ISDYNCMM208MsgTimer_mS_M_u32	38200064
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	415
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	273
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	54704
ISDYNCMM388MsgTimer_mS_M_u32	2401567488
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	28653
ISDYNVOLChkSumValidCount_Cnt_M_u16	5126
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	61510
ISDYNVOLMsgCountValidCount_Cnt_M_u16	33368
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	40371
ISDYNVOLMsgLenValidCount_Cnt_M_u16	65535
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	19825
ISDYNVOLMsgTimer_mS_M_u32	734315264
IgnOnTimer_mS_M_u32	3931702016
IgnTimeOff_Sec_M_u32	2956470404
ManVehSpd_Kph_M_f32	166.372894
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	77
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	35
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2109879040
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	141
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3337327360
PrevISDATBSI412MsgDLCError_Cnt_M_u08	168
PrevISDATBSI412MsgRxTime_MSec_M_u32	74662656
PrevISDATBSI432MsgDLCError_Cnt_M_u08	26
PrevISDATBSI432MsgRxTime_MSec_M_u32	3333169920
PrevISDATDIRAMsgTxTime_MSec_M_u32	2700559104
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	122
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2357318400
PrevISDYNAASMsgDLCError_Cnt_M_u08	62
PrevISDYNAASMsgRxTime_MSec_M_u32	4280992512
PrevISDYNABRMsgDLCError_Cnt_M_u08	152
PrevISDYNABRMsgRxTime_MSec_M_u32	317784832
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	100
PrevISDYNCMM208MsgRxTime_MSec_M_u32	734249728
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	167
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3230868224
PrevISDYNVOLMsgDLCError_Cnt_M_u08	226
PrevISDYNVOLMsgRxTime_MSec_M_u32	4274275072
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2940039936
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	286.059692
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3

Name	Input Value
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57130
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	37163
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	60727
VitesseVehicleBVRampValidCount_Cnt_M_u16	65272
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	53309
VitesseVehicleBVSigValidCount_Cnt_M_u16	48134
VitesseVehicleBV_Kph_M_f32	85.4878006
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	54704
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	55185
VitesseVehiculeRoues_Kph_M_f32	182.691605
k_AASNTCEnableTimeout_mS_u16	27090
k_AASNodeAbsentDiag_Cnt_str.Threshold	4467
k_AASNodeAbsentDiag_Cnt_str.PStep	60116
k_AASNodeAbsentDiag_Cnt_str.NStep	906
k_AASNodeAbsentTimeout_mS_u16	23689
k_AASNodeTimeout_mS_u16	12331
k_ABSNodeTimeout_mS_u16	26169
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	9636
k_ANGLEVOLANTSigValidThresh_Cnt_u16	35737
k_AngleVolantInvalidThresh_Cnt_u16	65140
k_AngleVolantValidThresh_Cnt_u16	14996
k_BSI552MsgTimeout_mS_u16	64044
k_BSINTCEnableTimeout_mS_u16	59709
k_BSINodeAbsentDiag_Cnt_str.Threshold	3052
k_BSINodeAbsentDiag_Cnt_str.PStep	44243
k_BSINodeAbsentDiag_Cnt_str.NStep	1848
k_BSINodeAbsentTimeout_mS_u16	63938
k_BSINodeTimeout_mS_u16	27762
k_BattOvHi_Volt_f32	6.40350008
k_BattOvLo_Volt_f32	29.2830009
k_BattUvHi_Volt_f32	22.8605995
k_BattUvLo_Volt_f32	5.96649981
k_CAVNTCEnableTimeout_mS_u16	9938
k_CAVNodeAbsentDiag_Cnt_str.Threshold	41800
k_CAVNodeAbsentDiag_Cnt_str.PStep	20653
k_CAVNodeAbsentDiag_Cnt_str.NStep	46182
k_CAVNodeAbsentTimeout_mS_u16	11267
k_CAVNodeTimeout_mS_u16	57811
k_CMM388MsgTimeout_mS_u16	29801
k_CMM388NTCEnableTimeout_mS_u16	11829
k_CMMNTCEnableTimeout_mS_u16	59192
k_CMMNodeAbsentDiag_Cnt_str.Threshold	10365
k_CMMNodeAbsentDiag_Cnt_str.PStep	62446
k_CMMNodeAbsentDiag_Cnt_str.NStep	23219
k_CMMNodeAbsentTimeout_mS_u16	57181
k_CONSANGLECPKMax_HwDeg_f32	324.204498
k_CONSANGLECPKMin_HwDeg_f32	-33.5341988
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	13488
k_CONSANGLECPKSigValidThresh_Cnt_u16	30353
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	57337
k_CPKVehicleSpeedValidThresh_Cnt_u16	13178
k_CityParkInputInvalidThresh_Cnt_u16	60571
k_CityParkInputValidThresh_Cnt_u16	29182
k_ComputerRazGCTSigValidThresh_Cnt_u16	6990
k_CptTemporelSigValidThresh_Cnt_u16	8859
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	19322
k_DMDFCTCPKSigValidThresh_Cnt_u16	28499
k_DMDFCTCPKValidCount_Cnt_u16	21899
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	48211
k_DMDRELAXECPKSigValidThresh_Cnt_u16	11813
k_DMDRelaxeConsistentThresh_Cnt_u16	45043
k_DateValidThresh_Cnt_u16	22720
k_DefaultVehSpd_Kph_f32	26.4964008
k_DiagMuxOnAbsentTimeout_mS_u16	49541
k_EMNodeTimeout_mS_u16	51368

Name	Input Value
k_ESPNTCEnableTimeout_mS_u16	46057
k_ESPNodeAbsentDiag_Cnt_str.Threshold	17978
k_ESPNodeAbsentDiag_Cnt_str.PStep	37115
k_ESPNodeAbsentDiag_Cnt_str.NStep	784
k_ESPNodeAbsentTimeout_mS_u16	44741
k_EtatMTSigInvalidThresh_Cnt_u16	16520
k_EtatMTSigValidThresh_Cnt_u16	35001
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	4672
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	18821
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	55819
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	24065
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	5518
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	18887
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	29574
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	57083
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	5081
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	18331
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	13048
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	60411
k_ISDATDIRASentDiag_Cnt_str.Threshold	6549
k_ISDATDIRASentDiag_Cnt_str.PStep	63930
k_ISDATDIRASentDiag_Cnt_str.NStep	24627
k_ISDATDIRASentTimeout_mS_u16	57625
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	37396
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	1834
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	5509
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	30029
k_ISDYNAASChkSumValidThresh_Cnt_u16	14142
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	20470
k_ISDYNAASMsgCountValidThresh_Cnt_u16	7136
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	60033
k_ISDYNAASMsgLenValidThresh_Cnt_u16	24671
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	53505
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	54880
k_ISDYNABRChkSumValidThresh_Cnt_u16	31417
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	63523
k_ISDYNABRMsgCountValidThresh_Cnt_u16	9324
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	60529
k_ISDYNABRMsgLenValidThresh_Cnt_u16	49702
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	2695
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	12126
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	37600
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	26054
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	37296
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	48569
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	300
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	12306
k_ISDYNVOLChkSumValidThresh_Cnt_u16	44560
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	45031
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	60274
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	41719
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	7388
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	37822
k_IgnOnTimeout_mS_u16	32478
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	225.207794
k_PowerCutVehSpdLowThresh_Kph_f32	158.309402
k_PowerCutVehSpdLowTimeout_mS_u16	27470
k_VBattMaxAAS_Volt_f32	12.4312
k_VBattMaxBSI_Volt_f32	32
k_VBattMaxCAV_Volt_f32	12.8541002
k_VBattMaxCMM388_Volt_f32	15.9034004
k_VBattMaxCMM_Volt_f32	30.1669998
k_VBattMaxESP_Volt_f32	25.6735992
k_VBattMinAAS_Volt_f32	8.70960045
k_VBattMinBSI_Volt_f32	25.6735992
k_VBattMinCAV_Volt_f32	1.10889995
k_VBattMinCMM388_Volt_f32	25.5296001
k_VBattMinCMM_Volt_f32	20.2821007
k_VBattMinESP_Volt_f32	30.1669998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	59718
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	41779
k_VitesseVehicleBVRampValidThresh_Cnt_u16	20294

Name	Input Value
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	13062
k_VitesseVehicleBVSigValidThresh_Cnt_u16	26787
k_VitesseVehicleBVSpeedPassThresh_kph_f32	613.95752
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	46109
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	18014
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1718510336
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	186
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65036
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	163190528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	167
target_SrlComInput_Per1_Batt_Volt_f32.value	1.84220004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2342523648
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	1
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.322624534
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4061856512
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	179
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1711055616
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1877885696
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	938468096
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3858858752
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2720211712
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2488582912
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	52
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	121
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	122
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	145
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	172
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1524425472
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	77
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	151
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	222
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1621230336
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1443078912
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	226
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2708816640
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	89

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	114
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	140
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	158
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1951765248
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2676
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.367320895
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	570724
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	113.364304
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	48604

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	163190528	163190528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	1	1	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	1836	1836	✔
AngleVolantMsgTimer_mS_M_u32	163190528	163190528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	564.94812	564.94812	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	3052	3052	✔
BSINodeAbsentTimer_mS_M_u32	163190528	163190528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1298862848	1298862848	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2720211712	2720211712	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	27015	27015	✔
CONSANGLECPK_HwDeg_M_f32	600.059509	600.059509 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	27015	27015	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1132229376	1132229376	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	15599	15599	✔
CityParkInputConsistentCount_Cnt_M_u16	29182	29182	✔
CityParkInputInvalidCount_Cnt_M_u16	14998	14998	✔
CityParkInputMsgTimer_mS_M_u32	163190528	163190528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	163190528	163190528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	163190528	163190528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	163190528	163190528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	163190528	163190528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	163190528	163190528	✔
ESPNTCEnableTimer_mS_M_u32	163190528	163190528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	17978	17978	✔
ESPNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	66	66	✔
EffacDefaultDiagTimer_mS_M_u32[1]	78	78	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	163190528	163190528	✔
ElecIntTimer_mS_M_u32[1]	16	16	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	163190528	163190528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	163190528	163190528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	28653	28653	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	61510	61510	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2708816640	2708816640	✔
IgnOnTimer_mS_M_u32	3931702016	3931702016	✔
IgnTimeOff_Sec_M_u32	2956470404	2956470404	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	59	59	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4061856512	4061856512	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	179	179	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1711055616	1711055616	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	45	45	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1877885696	1877885696	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	938468096	938468096	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2700559104	2700559104	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	55	55	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2720211712	2720211712	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2488582912	2488582912	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	60	60	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1524425472	1524425472	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	81	81	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1621230336	1621230336	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	107	107	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1443078912	1443078912	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	226	226	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2708816640	2708816640	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1951765248	1951765248	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	286.059692	286.059692	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	85.4878006	85.4878006	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	182.691605	182.691605	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	564.94812	564.94812	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	27015	27015	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2956470404	2956470404	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	600.059509	600.059509 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	26.4964008	26.4964008	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	3	ValidityNTCProcessing	3	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.184 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1104570880
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	20204
AASNodeAbsentTimer_mS_M_u32	2335267328
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	12569
ANGLEVOLANTSigValidCount_Cnt_M_u16	19901
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	15785
AngleVolantMsgTimer_mS_M_u32	1104570880
AngleVolantValidCount_Cnt_M_u16	60491
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	534.028259
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1734416896
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3114244608
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1063324160
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2617231872
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	35264
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	325683712
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	17491
CAVNodeAbsentTimer_mS_M_u32	240122368
CDD_SrlComVehSpd_Kph_G_f32	16.5695

Name	Input Value
CMM388NTCEnableTimer_mS_M_u32	3131849216
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	568719872
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	30998
CMMNodeAbsentTimer_mS_M_u32	518638080
CONSANGLECPKSigInvalidCount_Cnt_M_u16	19733
CONSANGLECPKSigValidCount_Cnt_M_u16	777
CONSANGLECPK_Cnt_M_u16	21588
CONSANGLECPK_HwDeg_M_f32	405.618408
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21588
CPKVehicleSpeedMsgTimer_mS_M_u32	2931124736
CPKVehicleSpeedValidCount_Cnt_M_u16	5795
CityParkInputConsistentCount_Cnt_M_u16	21423
CityParkInputInvalidCount_Cnt_M_u16	8940
CityParkInputMsgTimer_mS_M_u32	4061856512
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3415562752
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	35920
ComputerRazGCTSigInvalidTimer_mS_M_u32	3045095936
ComputerRazGCTSigValidCount_Cnt_M_u16	22564
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	6024
DMDFCTCPKSigValidCount_Cnt_M_u16	41876
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56267
DMDRELAXECPKSigValidCount_Cnt_M_u16	63983
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	54482
DateInvalidTimer_mS_M_u32	3114244608
DiagMuxOnAbsentTimer_mS_M_u32	3693095424
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2617231872
ESPNTCEnableTimer_mS_M_u32	1309825536
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	18614
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	80
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2625341952
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	59623
EtatMTSigValidCount_Cnt_M_u16	20215
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	36295
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	50491
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	45354
ISDAT4V2BSI552MsgTimer_mS_M_u32	2723006976
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	65032
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	11361
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	20215
ISDATBSI3F2MsgTimer_mS_M_u32	3010341376
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	18735
ISDATBSI412MsgLenValidCount_Cnt_M_u16	21431
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	59623
ISDATBSI412MsgTimer_mS_M_u32	3743705600
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	32634
ISDATBSI432MsgLenValidCount_Cnt_M_u16	4634
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	37460
ISDATDIRASentFltAcc_Cnt_M_u16	24008
ISDATDIRASentTimer_mS_M_u32	2931124736
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	43554
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	60491
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	22959
ISDYN2CMMMsgTimer_mS_M_u32	226253312
ISDYNAASChkSumInvalidCount_Cnt_M_u16	34206
ISDYNAASChkSumValidCount_Cnt_M_u16	50019

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	62578
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	8670
ISDYNAASMsgLenValidCount_Cnt_M_u16	36378
ISDYNAASMsgTimeValidCount_Cnt_M_u16	34206
ISDYNAASMsgTimer_mS_M_u32	340277760
ISDYNABRChkSumInvalidCount_Cnt_M_u16	4546
ISDYNABRChkSumValidCount_Cnt_M_u16	3247
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	12357
ISDYNABRMsgCountValidCount_Cnt_M_u16	60746
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	23228
ISDYNABRMsgLenValidCount_Cnt_M_u16	53232
ISDYNABRMsgTimeValidCount_Cnt_M_u16	21588
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	725
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1335
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	20215
ISDYNCMM208MsgTimer_mS_M_u32	3893762560
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2751
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1441
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	28825
ISDYNCMM388MsgTimer_mS_M_u32	3791370752
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	56419
ISDYNVOLChkSumValidCount_Cnt_M_u16	4311
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	18902
ISDYNVOLMsgCountValidCount_Cnt_M_u16	37986
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	36111
ISDYNVOLMsgLenValidCount_Cnt_M_u16	31453
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	30998
ISDYNVOLMsgTimer_mS_M_u32	991721984
IgnOnTimer_mS_M_u32	2690628096
IgnTimeOff_Sec_M_u32	34873344
ManVehSpd_Kph_M_f32	221.745193
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	187
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	28
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1189358080
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	146
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1223166464
PrevISDATBSI412MsgDLCError_Cnt_M_u08	44
PrevISDATBSI412MsgRxTime_MSec_M_u32	2333145600
PrevISDATBSI432MsgDLCError_Cnt_M_u08	1
PrevISDATBSI432MsgRxTime_MSec_M_u32	3219544576
PrevISDATDIRAMsgTxTime_MSec_M_u32	3313826304
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	180
PrevISDYN2CMMMsgRxTime_MSec_M_u32	556091904
PrevISDYNAASMsgDLCError_Cnt_M_u08	253
PrevISDYNAASMsgRxTime_MSec_M_u32	3639245312
PrevISDYNABRMsgDLCError_Cnt_M_u08	221
PrevISDYNABRMsgRxTime_MSec_M_u32	2258090496
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	152
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4146035200
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	93
PrevISDYNCMM388MsgRxTime_MSec_M_u32	774986240
PrevISDYNVOLMsgDLCError_Cnt_M_u08	185
PrevISDYNVOLMsgRxTime_MSec_M_u32	538835456
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2943511040
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	517.101929
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput

Name	Input Value
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	6700
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	50408
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	25605
VitesseVehicleBVRampValidCount_Cnt_M_u16	61313
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	19570
VitesseVehicleBVSigValidCount_Cnt_M_u16	27094
VitesseVehicleBV_Kph_M_f32	470.169312
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	28825
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	43957
VitesseVehiculeRoues_Kph_M_f32	505.445709
k_AASNTCEnableTimeout_mS_u16	16243
k_AASNodeAbsentDiag_Cnt_str.Threshold	10757
k_AASNodeAbsentDiag_Cnt_str.PStep	7105
k_AASNodeAbsentDiag_Cnt_str.NStep	65461
k_AASNodeAbsentTimeout_mS_u16	32782
k_AASNodeTimeout_mS_u16	59368
k_ABSNodeTimeout_mS_u16	29693
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	31869
k_ANGLEVOLANTSigValidThresh_Cnt_u16	56157
k_AngleVolantInvalidThresh_Cnt_u16	44748
k_AngleVolantValidThresh_Cnt_u16	8940
k_BSI552MsgTimeout_mS_u16	28644
k_BSINTCEnableTimeout_mS_u16	54706
k_BSINodeAbsentDiag_Cnt_str.Threshold	26412
k_BSINodeAbsentDiag_Cnt_str.PStep	34315
k_BSINodeAbsentDiag_Cnt_str.NStep	15280
k_BSINodeAbsentTimeout_mS_u16	50657
k_BSINodeTimeout_mS_u16	37460
k_BattOvHi_Volt_f32	17.0242004
k_BattOvLo_Volt_f32	2.94370008
k_BattUvHi_Volt_f32	1.99370003
k_BattUvLo_Volt_f32	1.99000001
k_CAVNTCEnableTimeout_mS_u16	370
k_CAVNodeAbsentDiag_Cnt_str.Threshold	9850
k_CAVNodeAbsentDiag_Cnt_str.PStep	55599
k_CAVNodeAbsentDiag_Cnt_str.NStep	26463
k_CAVNodeAbsentTimeout_mS_u16	55201
k_CAVNodeTimeout_mS_u16	40625
k_CMM388MsgTimeout_mS_u16	45548
k_CMM388NTCEnableTimeout_mS_u16	46216
k_CMMNTCEnableTimeout_mS_u16	12352
k_CMMNodeAbsentDiag_Cnt_str.Threshold	32647
k_CMMNodeAbsentDiag_Cnt_str.PStep	42126
k_CMMNodeAbsentDiag_Cnt_str.NStep	57005
k_CMMNodeAbsentTimeout_mS_u16	50257
k_CONSANGLECPKMax_HwDeg_f32	769.892212
k_CONSANGLECPKMin_HwDeg_f32	-200.728699
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	21401
k_CONSANGLECPKSigValidThresh_Cnt_u16	52917
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	36990
k_CPKVehicleSpeedValidThresh_Cnt_u16	9338
k_CityParkInputInvalidThresh_Cnt_u16	18136
k_CityParkInputValidThresh_Cnt_u16	21423
k_ComputerRazGCTSigValidThresh_Cnt_u16	27646
k_CptTemporelSigValidThresh_Cnt_u16	18135
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	48572
k_DMDFCTCPKSigValidThresh_Cnt_u16	29424
k_DMDFCTCPKValidCount_Cnt_u16	29832
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	22959
k_DMDRELAXECPKSigValidThresh_Cnt_u16	1275
k_DMDRelaxeConsistentThresh_Cnt_u16	14225
k_DateValidThresh_Cnt_u16	45354
k_DefaultVehSpd_Kph_f32	252.177902
k_DiagMuxOnAbsentTimeout_mS_u16	50266

Name	Input Value
k_EMNodeTimeout_mS_u16	32306
k_ESPNTCEnableTimeout_mS_u16	22511
k_ESPNodeAbsentDiag_Cnt_str.Threshold	40274
k_ESPNodeAbsentDiag_Cnt_str.PStep	1844
k_ESPNodeAbsentDiag_Cnt_str.NStep	56738
k_ESPNodeAbsentTimeout_mS_u16	63001
k_EtatMTSigInvalidThresh_Cnt_u16	16145
k_EtatMTSigValidThresh_Cnt_u16	59198
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	54697
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	154
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	36744
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	12261
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	63998
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	21907
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	39639
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	59703
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	50654
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	2584
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	30913
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	19449
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	57694
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	64942
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	15785
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	41755
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	62658
k_ISDYNAASChkSumValidThresh_Cnt_u16	12207
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	37701
k_ISDYNAASMsgCountValidThresh_Cnt_u16	36938
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	25894
k_ISDYNAASMsgLenValidThresh_Cnt_u16	10060
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	43813
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	13578
k_ISDYNABRChkSumValidThresh_Cnt_u16	26814
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	60608
k_ISDYNABRMsgCountValidThresh_Cnt_u16	18596
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	39958
k_ISDYNABRMsgLenValidThresh_Cnt_u16	43958
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	49747
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	63888
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7752
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	29463
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	37913
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	61629
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	12068
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	36530
k_ISDYNVOLChkSumValidThresh_Cnt_u16	50554
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	9843
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	58131
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	24963
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	17555
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	30768
k_IgnOnTimeout_mS_u16	53838
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	168.543594
k_PowerCutVehSpdLowThresh_Kph_f32	89.2388992
k_PowerCutVehSpdLowTimeout_mS_u16	11007
k_VBattMaxAAS_Volt_f32	18.0932007
k_VBattMaxBSI_Volt_f32	4.42439985
k_VBattMaxCAV_Volt_f32	11.1595001
k_VBattMaxCMM388_Volt_f32	5.90420008
k_VBattMaxCMM_Volt_f32	3.17090011
k_VBattMaxESP_Volt_f32	28.7360001
k_VBattMinAAS_Volt_f32	4.60459995
k_VBattMinBSI_Volt_f32	28.7360001
k_VBattMinCAV_Volt_f32	2.55430007
k_VBattMinCMM388_Volt_f32	24.5596008
k_VBattMinCMM_Volt_f32	32
k_VBattMinESP_Volt_f32	3.17090011
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	16408
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	33552

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VitesseVehicleBVRampValidThresh_Cnt_u16	11478
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	46039
k_VitesseVehicleBVSigValidThresh_Cnt_u16	17344
k_VitesseVehicleBVSpeedPassThresh_kph_f32	413.442688
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	10067
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	12623
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3114244608
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	61
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	93
target_SrlComInput_Per1_Batt_Volt_f32.value	8.80679989
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1825212928
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	90
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.809025943
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	286898688
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3287603712
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	140
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4104124928
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	723196416
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4016454144
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3380697600
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1097628160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	85
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	89
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	199
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	211
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3058964992
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	43
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	194
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2709830144
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3487554048
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	185
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1007352320
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	55
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	126

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	229
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	247
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1755974144
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2808
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.864297211
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	788563
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	108.324097
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	50710

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	12570	12570	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	15787	15787	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	534.028259	534.028259	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26412	26412	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	325683712	325683712	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3380697600	3380697600	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	21588	21588	✔
CONSANGLECPK_HwDeg_M_f32	405.618408	405.618408 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21588	21588	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2931124736	2931124736	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	5795	5795	✔
CityParkInputConsistentCount_Cnt_M_u16	21423	21423	✔
CityParkInputInvalidCount_Cnt_M_u16	8942	8942	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	40274	40274	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	80	80	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	56419	56419	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	18902	18902	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1007352320	1007352320	✔
IgnOnTimer_mS_M_u32	2690628096	2690628096	✔
IgnTimeOff_Sec_M_u32	34873344	34873344	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	68	68	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	286898688	286898688	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3287603712	3287603712	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	140	140	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4104124928	4104124928	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	14	14	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	723196416	723196416	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3313826304	3313826304	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	121	121	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3380697600	3380697600	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	113	113	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1097628160	1097628160	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	194	194	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3058964992	3058964992	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	223	223	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2709830144	2709830144	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	129	129	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3487554048	3487554048	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	185	185	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1007352320	1007352320	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1755974144	1755974144	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	517.101929	517.101929	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	470.169312	470.169312	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	505.445709	505.445709	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	534.028259	534.028259	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	21588	21588	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	34873344	34873344	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	405.618408	405.618408 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	252.177902	252.177902	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0151	0x0151	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0152	0x0152	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔
NTC	0x0153	0x0153	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	3	ValidityNTCProcessing	3	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.185 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1000632320
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	15526
AASNodeAbsentTimer_mS_M_u32	3632521216
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	62351
ANGLEVOLANTSigValidCount_Cnt_M_u16	50380
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	62139
AngleVolantMsgTimer_mS_M_u32	1000632320
AngleVolantValidCount_Cnt_M_u16	44892
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	411.883301
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	363175936

Name	Input Value
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1821384704
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1933709312
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1125830656
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	64190
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2888208384
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	19520
CAVNodeAbsentTimer_mS_M_u32	3323297792
CDD_SrlComVehSpd_Kph_G_f32	322.161011
CMM388NTCEnableTimer_mS_M_u32	3089088512
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1719369728
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	55737
CMMNodeAbsentTimer_mS_M_u32	624218112
CONSANGLECPKSigInvalidCount_Cnt_M_u16	44317
CONSANGLECPKSigValidCount_Cnt_M_u16	33066
CONSANGLECPK_Cnt_M_u16	15581
CONSANGLECPK_HwDeg_M_f32	66.1390991
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	15581
CPKVehicleSpeedMsgTimer_mS_M_u32	323710976
CPKVehicleSpeedValidCount_Cnt_M_u16	370
CityParkInputConsistentCount_Cnt_M_u16	36000
CityParkInputInvalidCount_Cnt_M_u16	10435
CityParkInputMsgTimer_mS_M_u32	2032173312
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	113762304
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	49130
ComputerRazGCTSigInvalidTimer_mS_M_u32	4074897408
ComputerRazGCTSigValidCount_Cnt_M_u16	26797
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	51071
DMDFCTCPKSigValidCount_Cnt_M_u16	55012
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	24881
DMDRELAXECPKSigValidCount_Cnt_M_u16	34798
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	29746
DateInvalidTimer_mS_M_u32	1821384704
DiagMuxOnAbsentTimer_mS_M_u32	2828021760
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1125830656
ESPNTCEnableTimer_mS_M_u32	580706304
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	60690
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	201
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	9
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3710423040
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	11985
EtatMTSigValidCount_Cnt_M_u16	24857
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	32959
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	10828
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	8522
ISDAT4V2BSI552MsgTimer_mS_M_u32	1048104960
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	42879
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	8656
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	24857
ISDATBSI3F2MsgTimer_mS_M_u32	753807360
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	61571

Name	Input Value
ISDATBSI412MsgLenValidCount_Cnt_M_u16	37252
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	11985
ISDATBSI412MsgTimer_mS_M_u32	3590483968
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	7677
ISDATBSI432MsgLenValidCount_Cnt_M_u16	40022
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	20601
ISDATDIRASentFltAcc_Cnt_M_u16	54605
ISDATDIRASentTimer_mS_M_u32	323710976
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	60347
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	44892
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52270
ISDYN2CMMMsgTimer_mS_M_u32	2100748288
ISDYNAASChkSumInvalidCount_Cnt_M_u16	54856
ISDYNAASChkSumValidCount_Cnt_M_u16	51109
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	51723
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	49715
ISDYNAASMsgLenValidCount_Cnt_M_u16	56392
ISDYNAASMsgTimeValidCount_Cnt_M_u16	54856
ISDYNAASMsgTimer_mS_M_u32	3554394112
ISDYNABRChkSumInvalidCount_Cnt_M_u16	60805
ISDYNABRChkSumValidCount_Cnt_M_u16	60618
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	8055
ISDYNABRMsgCountValidCount_Cnt_M_u16	58900
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	332
ISDYNABRMsgLenValidCount_Cnt_M_u16	60057
ISDYNABRMsgTimeValidCount_Cnt_M_u16	15581
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	157
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	199
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	24857
ISDYNCMM208MsgTimer_mS_M_u32	468885504
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	479
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	305
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	47290
ISDYNCMM388MsgTimer_mS_M_u32	2245214208
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	10619
ISDYNVOLChkSumValidCount_Cnt_M_u16	10248
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	36573
ISDYNVOLMsgCountValidCount_Cnt_M_u16	2242
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	56035
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	55737
ISDYNVOLMsgTimer_mS_M_u32	3667787776
IgnOnTimer_mS_M_u32	3256303616
IgnTimeOff_Sec_M_u32	2605544015
ManVehSpd_Kph_M_f32	79.032402
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	93
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	170
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2251567104
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	143
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	475074560
PrevISDATBSI412MsgDLCError_Cnt_M_u08	193
PrevISDATBSI412MsgRxTime_MSec_M_u32	3004071936
PrevISDATBSI432MsgDLCError_Cnt_M_u08	65
PrevISDATBSI432MsgRxTime_MSec_M_u32	4073775104
PrevISDATDIRAMsgTxTime_MSec_M_u32	4007821312
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	180
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3111407616
PrevISDYNAASMsgDLCError_Cnt_M_u08	42
PrevISDYNAASMsgRxTime_MSec_M_u32	2440822784
PrevISDYNABRMsgDLCError_Cnt_M_u08	42
PrevISDYNABRMsgRxTime_MSec_M_u32	1418674176
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	198

Name	Input Value
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2840133632
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	132
PrevISDYNCMM388MsgRxTime_MSec_M_u32	595845120
PrevISDYNVOLMsgDLCError_Cnt_M_u08	224
PrevISDYNVOLMsgRxTime_MSec_M_u32	1358135296
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3412094976
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	258.130402
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	40849
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	42022
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	50914
VitesseVehicleBVRampValidCount_Cnt_M_u16	22071
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	49248
VitesseVehicleBVSigValidCount_Cnt_M_u16	15453
VitesseVehicleBV_Kph_M_f32	542.913086
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	47290
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	8879
VitesseVehiculeRoues_Kph_M_f32	36.6309013
k_AASNTCEnableTimeout_mS_u16	45252
k_AASNodeAbsentDiag_Cnt_str.Threshold	47636
k_AASNodeAbsentDiag_Cnt_str.PStep	34578
k_AASNodeAbsentDiag_Cnt_str.NStep	62563
k_AASNodeAbsentTimeout_mS_u16	1991
k_AASNodeTimeout_mS_u16	28454
k_ABSNodeTimeout_mS_u16	15244
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	26024
k_ANGLEVOLANTSigValidThresh_Cnt_u16	56897
k_AngleVolantInvalidThresh_Cnt_u16	60408
k_AngleVolantValidThresh_Cnt_u16	10435
k_BSI552MsgTimeout_mS_u16	19238
k_BSINTCEnableTimeout_mS_u16	41077
k_BSINodeAbsentDiag_Cnt_str.Threshold	3692
k_BSINodeAbsentDiag_Cnt_str.PStep	43971
k_BSINodeAbsentDiag_Cnt_str.NStep	2216
k_BSINodeAbsentTimeout_mS_u16	38707
k_BSINodeTimeout_mS_u16	20601
k_BattOvHi_Volt_f32	22.5207005
k_BattOvLo_Volt_f32	8.83209991
k_BattUvHi_Volt_f32	9.60820007
k_BattUvLo_Volt_f32	6.42689991
k_CAVNTCEnableTimeout_mS_u16	3065
k_CAVNodeAbsentDiag_Cnt_str.Threshold	14101
k_CAVNodeAbsentDiag_Cnt_str.PStep	13590
k_CAVNodeAbsentDiag_Cnt_str.NStep	2667
k_CAVNodeAbsentTimeout_mS_u16	44190
k_CAVNodeTimeout_mS_u16	217
k_CMM388MsgTimeout_mS_u16	18342
k_CMM388NTCEnableTimeout_mS_u16	1122
k_CMMNTCEnableTimeout_mS_u16	9719
k_CMMNodeAbsentDiag_Cnt_str.Threshold	62414
k_CMMNodeAbsentDiag_Cnt_str.PStep	42715
k_CMMNodeAbsentDiag_Cnt_str.NStep	22076
k_CMMNodeAbsentTimeout_mS_u16	50539
k_CONSANGLECPKMax_HwDeg_f32	647.885071
k_CONSANGLECPKMin_HwDeg_f32	-305.664612
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	17338
k_CONSANGLECPKSigValidThresh_Cnt_u16	60847
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	15500

Name	Input Value
k_CPKVehicleSpeedValidThresh_Cnt_u16	26166
k_CityParkInputInvalidThresh_Cnt_u16	875
k_CityParkInputValidThresh_Cnt_u16	36000
k_ComputerRazGCTSigValidThresh_Cnt_u16	42821
k_CptTemporelSigValidThresh_Cnt_u16	35350
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	3148
k_DMDFCTCPKSigValidThresh_Cnt_u16	13721
k_DMDFCTCPKValidCount_Cnt_u16	61766
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	52270
k_DMDRELAXECPKSigValidThresh_Cnt_u16	20691
k_DMDRelaxeConsistentThresh_Cnt_u16	55353
k_DateValidThresh_Cnt_u16	8522
k_DefaultVehSpd_Kph_f32	151.791306
k_DiagMuxOnAbsentTimeout_mS_u16	4659
k_EMNodeTimeout_mS_u16	27282
k_ESPNTCEnableTimeout_mS_u16	53756
k_ESPNodeAbsentDiag_Cnt_str.Threshold	62971
k_ESPNodeAbsentDiag_Cnt_str.PStep	11352
k_ESPNodeAbsentDiag_Cnt_str.NStep	60169
k_ESPNodeAbsentTimeout_mS_u16	35571
k_EtatMTSigInvalidThresh_Cnt_u16	15900
k_EtatMTSigValidThresh_Cnt_u16	20641
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	34079
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	52552
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	38385
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	4020
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	47045
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	35527
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	33714
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	20427
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	41537
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	52609
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	31138
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	29963
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	20289
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	25688
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	62139
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	5832
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	30853
k_ISDYNAASChkSumValidThresh_Cnt_u16	47050
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	10871
k_ISDYNAASMsgCountValidThresh_Cnt_u16	12564
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	22217
k_ISDYNAASMsgLenValidThresh_Cnt_u16	25706
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	53705
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	12458
k_ISDYNABRChkSumValidThresh_Cnt_u16	33911
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	1470
k_ISDYNABRMsgCountValidThresh_Cnt_u16	27707
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	42169
k_ISDYNABRMsgLenValidThresh_Cnt_u16	63506
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	65074
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	13525
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	39188
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	59037
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	65167
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	4044
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	12603
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	23726
k_ISDYNVOLChkSumValidThresh_Cnt_u16	22511
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	55847
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	33038
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	12685
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	14549
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	21920
k_IgnOnTimeout_mS_u16	37482
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	142.387497
k_PowerCutVehSpdLowThresh_Kph_f32	82.0203018
k_PowerCutVehSpdLowTimeout_mS_u16	60144

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMaxAAS_Volt_f32	11.4912996
k_VBattMaxBSI_Volt_f32	17.6352997
k_VBattMaxCAV_Volt_f32	15.0909004
k_VBattMaxCMM388_Volt_f32	6.86420012
k_VBattMaxCMM_Volt_f32	1.32550001
k_VBattMaxESP_Volt_f32	12.4805002
k_VBattMinAAS_Volt_f32	26.4710999
k_VBattMinBSI_Volt_f32	12.4805002
k_VBattMinCAV_Volt_f32	3.76609993
k_VBattMinCMM388_Volt_f32	27.7071991
k_VBattMinCMM_Volt_f32	26.6096992
k_VBattMinESP_Volt_f32	1.32550001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	59890
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	48099
k_VitesseVehicleBVRampValidThresh_Cnt_u16	6621
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	29448
k_VitesseVehicleBVSigValidThresh_Cnt_u16	1641
k_VitesseVehicleBVSpeedPassThresh_kph_f32	634.463013
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	55104
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	37141
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1821384704
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	58
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	132
target_SrlComInput_Per1_Batt_Volt_f32.value	8.25549984
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2025820160
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	129
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.902174652
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2004959232
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	140
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3238748160
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3991240704
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	56
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1175429120
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	294240256
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2555633664
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	577634304
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	48
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	80
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	200
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1002479616
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	24
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	62

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	166
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	22298624
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3395182592
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	918061056
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	7
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	17
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	48
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	85
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	130
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	169
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4202893312
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1210
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.697941124
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	253594
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	166.751999
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	41643

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	577634304	577634304	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	1	1	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	411.883301	411.883301	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	61974	61974	✔
BSINodeAbsentTimer_mS_M_u32	1175429120	1175429120	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2888208384	2888208384	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	16853	16853	✔
CAVNodeAbsentTimer_mS_M_u32	918061056	918061056	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	33661	33661	✔
CMMNodeAbsentTimer_mS_M_u32	2555633664	2555633664	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	15581	15581	✔
CONSANGLECPK_HwDeg_M_f32	66.1390991	66.1390991 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2006148864	2006148864	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	62971	62971	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔
EffacDefaultDiagTimer_mS_M_u32[1]	201	201	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	8	8	✔
ElecIntTimer_mS_M_u32[1]	9	9	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	49365	49365	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	918061056	918061056	✔
IgnOnTimer_mS_M_u32	3256303616	3256303616	✔
IgnTimeOff_Sec_M_u32	2605544015	2605544015	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	121	121	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2004959232	2004959232	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	140	140	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3238748160	3238748160	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3991240704	3991240704	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	56	56	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1175429120	1175429120	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	294240256	294240256	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2555633664	2555633664	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	192	192	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	577634304	577634304	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	192	192	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1002479616	1002479616	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	22298624	22298624	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	253	253	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3395182592	3395182592	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	918061056	918061056	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4202893312	4202893312	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	258.130402	258.130402	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	542.913086	542.913086	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	36.6309013	36.6309013	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	411.883301	411.883301	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	15581	15581	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2605544015	2605544015	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	66.1390991	66.1390991 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	151.791306	151.791306	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x010A	0x010A	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0151	0x0151	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	5	ValidityNTCProcessing	5	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.186 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1852928768
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	38249
AASNodeAbsentTimer_mS_M_u32	2710774528
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	45744
ANGLEVOLANTSigValidCount_Cnt_M_u16	40633
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	1834
AngleVolantMsgTimer_mS_M_u32	1852928768
AngleVolantValidCount_Cnt_M_u16	63946
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	655.057373
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2704139008
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1718510336
BSI412NTCsEnabled_Cnt_M_lgc	1

Name	Input Value
BSI432NTCEnableTimer_mS_M_u32	3323499264
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2844676864
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	6435
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1298862848
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	21789
CAVNodeAbsentTimer_mS_M_u32	2807972608
CDD_SrlComVehSpd_Kph_G_f32	601.605896
CMM388NTCEnableTimer_mS_M_u32	3393159936
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3727442688
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	19825
CMMNodeAbsentTimer_mS_M_u32	3946861312
CONSANGLECPKSigInvalidCount_Cnt_M_u16	60679
CONSANGLECPKSigValidCount_Cnt_M_u16	4256
CONSANGLECPK_Cnt_M_u16	27015
CONSANGLECPK_HwDeg_M_f32	600.059509
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	27015
CPKVehicleSpeedMsgTimer_mS_M_u32	1132229376
CPKVehicleSpeedValidCount_Cnt_M_u16	15599
CityParkInputConsistentCount_Cnt_M_u16	29182
CityParkInputInvalidCount_Cnt_M_u16	14996
CityParkInputMsgTimer_mS_M_u32	2004959232
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	650584832
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	7069
ComputerRazGCTSigInvalidTimer_mS_M_u32	4076389120
ComputerRazGCTSigValidCount_Cnt_M_u16	20951
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	20064
DMDFCTCPKSigValidCount_Cnt_M_u16	8178
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	29130
DMDRELAXECPKSigValidCount_Cnt_M_u16	23891
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	11208
DateInvalidTimer_mS_M_u32	1718510336
DiagMuxOnAbsentTimer_mS_M_u32	2259563264
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2844676864
ESPNTCEnableTimer_mS_M_u32	1732780800
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	58150
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	66
EffacDefaultDiagTimer_mS_M_u32[1]	78
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	16
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1113920256
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	47915
EtatMTSigValidCount_Cnt_M_u16	46096
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	31265
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	7482
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	22720
ISDAT4V2BSI552MsgTimer_mS_M_u32	2943636224
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	33440
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	50029
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	46096
ISDATBSI3F2MsgTimer_mS_M_u32	4053021440
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	2195
ISDATBSI412MsgLenValidCount_Cnt_M_u16	38225
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	47915
ISDATBSI412MsgTimer_mS_M_u32	2539090688

Name	Input Value
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	37029
ISDATBSI432MsgLenValidCount_Cnt_M_u16	58714
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	27762
ISDATDIRASentFltAcc_Cnt_M_u16	11766
ISDATDIRASentTimer_mS_M_u32	1132229376
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	21741
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	63946
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	48211
ISDYN2CMMMsgTimer_mS_M_u32	1064968960
ISDYNAASChkSumInvalidCount_Cnt_M_u16	53379
ISDYNAASChkSumValidCount_Cnt_M_u16	56365
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	9661
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	32580
ISDYNAASMsgLenValidCount_Cnt_M_u16	61637
ISDYNAASMsgTimeValidCount_Cnt_M_u16	53379
ISDYNAASMsgTimer_mS_M_u32	1728807680
ISDYNABRChkSumInvalidCount_Cnt_M_u16	5709
ISDYNABRChkSumValidCount_Cnt_M_u16	38974
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	28918
ISDYNABRMsgCountValidCount_Cnt_M_u16	64736
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	27770
ISDYNABRMsgLenValidCount_Cnt_M_u16	20563
ISDYNABRMsgTimeValidCount_Cnt_M_u16	27015
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	141
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	167
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	46096
ISDYNCMM208MsgTimer_mS_M_u32	38200064
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	415
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	273
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	54704
ISDYNCMM388MsgTimer_mS_M_u32	2401567488
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	28653
ISDYNVOLChkSumValidCount_Cnt_M_u16	5126
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	61510
ISDYNVOLMsgCountValidCount_Cnt_M_u16	33368
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	40371
ISDYNVOLMsgLenValidCount_Cnt_M_u16	65535
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	19825
ISDYNVOLMsgTimer_mS_M_u32	734315264
IgnOnTimer_mS_M_u32	3931702016
IgnTimeOff_Sec_M_u32	2956470404
ManVehSpd_Kph_M_f32	166.372894
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	77
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	35
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2109879040
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	141
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3337327360
PrevISDATBSI412MsgDLCError_Cnt_M_u08	168
PrevISDATBSI412MsgRxTime_MSec_M_u32	74662656
PrevISDATBSI432MsgDLCError_Cnt_M_u08	26
PrevISDATBSI432MsgRxTime_MSec_M_u32	3333169920
PrevISDATDIRAMsgTxTime_MSec_M_u32	2700559104
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	122
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2357318400
PrevISDYNAASMsgDLCError_Cnt_M_u08	62
PrevISDYNAASMsgRxTime_MSec_M_u32	4280992512
PrevISDYNABRMsgDLCError_Cnt_M_u08	152
PrevISDYNABRMsgRxTime_MSec_M_u32	317784832
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	100
PrevISDYNCMM208MsgRxTime_MSec_M_u32	734249728
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	167
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3230868224

Name	Input Value
PrevISDYNVOLMsgDLCError_Cnt_M_u08	226
PrevISDYNVOLMsgRxTime_MSec_M_u32	4274275072
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2940039936
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	286.059692
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57130
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	37163
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	60727
VitesseVehicleBVRampValidCount_Cnt_M_u16	65272
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	53309
VitesseVehicleBVSigValidCount_Cnt_M_u16	48134
VitesseVehicleBV_Kph_M_f32	85.4878006
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	54704
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	55185
VitesseVehiculeRoues_Kph_M_f32	182.691605
k_AASNTCEnableTimeout_mS_u16	27090
k_AASNodeAbsentDiag_Cnt_str.Threshold	4467
k_AASNodeAbsentDiag_Cnt_str.PStep	60116
k_AASNodeAbsentDiag_Cnt_str.NStep	906
k_AASNodeAbsentTimeout_mS_u16	23689
k_AASNodeTimeout_mS_u16	12331
k_ABSNodeTimeout_mS_u16	26169
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	9636
k_ANGLEVOLANTSigValidThresh_Cnt_u16	35737
k_AngleVolantInvalidThresh_Cnt_u16	65140
k_AngleVolantValidThresh_Cnt_u16	14996
k_BSI552MsgTimeout_mS_u16	64044
k_BSINTCEnableTimeout_mS_u16	59709
k_BSINodeAbsentDiag_Cnt_str.Threshold	3052
k_BSINodeAbsentDiag_Cnt_str.PStep	44243
k_BSINodeAbsentDiag_Cnt_str.NStep	1848
k_BSINodeAbsentTimeout_mS_u16	63938
k_BSINodeTimeout_mS_u16	27762
k_BattOvHi_Volt_f32	6.40350008
k_BattOvLo_Volt_f32	29.2830009
k_BattUvHi_Volt_f32	22.8605995
k_BattUvLo_Volt_f32	5.96649981
k_CAVNTCEnableTimeout_mS_u16	9938
k_CAVNodeAbsentDiag_Cnt_str.Threshold	41800
k_CAVNodeAbsentDiag_Cnt_str.PStep	20653
k_CAVNodeAbsentDiag_Cnt_str.NStep	46182
k_CAVNodeAbsentTimeout_mS_u16	11267
k_CAVNodeTimeout_mS_u16	57811
k_CMM388MsgTimeout_mS_u16	29801
k_CMM388NTCEnableTimeout_mS_u16	11829
k_CMMNTCEnableTimeout_mS_u16	59192
k_CMMNodeAbsentDiag_Cnt_str.Threshold	10365
k_CMMNodeAbsentDiag_Cnt_str.PStep	62446
k_CMMNodeAbsentDiag_Cnt_str.NStep	23219
k_CMMNodeAbsentTimeout_mS_u16	57181
k_CONSANGLECPKMax_HwDeg_f32	324.204498
k_CONSANGLECPKMin_HwDeg_f32	-33.5341988
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	13488
k_CONSANGLECPKSigValidThresh_Cnt_u16	30353
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	57337
k_CPKVehicleSpeedValidThresh_Cnt_u16	13178
k_CityParkInputInvalidThresh_Cnt_u16	60571
k_CityParkInputValidThresh_Cnt_u16	29182

Name	Input Value
k_ComputerRazGCTSigValidThresh_Cnt_u16	6990
k_CptTemporelSigValidThresh_Cnt_u16	8859
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	19322
k_DMDFCTCPKSigValidThresh_Cnt_u16	28499
k_DMDFCTCPKValidCount_Cnt_u16	21899
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	48211
k_DMDRELAXECPKSigValidThresh_Cnt_u16	11813
k_DMDRelaxeConsistentThresh_Cnt_u16	45043
k_DateValidThresh_Cnt_u16	22720
k_DefaultVehSpd_Kph_f32	26.4964008
k_DiagMuxOnAbsentTimeout_mS_u16	49541
k_EMNodeTimeout_mS_u16	51368
k_ESPNTCEnableTimeout_mS_u16	46057
k_ESPNodeAbsentDiag_Cnt_str.Threshold	17978
k_ESPNodeAbsentDiag_Cnt_str.PStep	37115
k_ESPNodeAbsentDiag_Cnt_str.NStep	784
k_ESPNodeAbsentTimeout_mS_u16	44741
k_EtatMTSigInvalidThresh_Cnt_u16	16520
k_EtatMTSigValidThresh_Cnt_u16	35001
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	4672
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	18821
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	55819
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	24065
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	5518
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	18887
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	29574
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	57083
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	5081
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	18331
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	13048
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	60411
k_ISDATDIRASentDiag_Cnt_str.Threshold	6549
k_ISDATDIRASentDiag_Cnt_str.PStep	63930
k_ISDATDIRASentDiag_Cnt_str.NStep	24627
k_ISDATDIRASentTimeout_mS_u16	57625
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	37396
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	1834
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	5509
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	30029
k_ISDYNAASChkSumValidThresh_Cnt_u16	14142
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	20470
k_ISDYNAASMsgCountValidThresh_Cnt_u16	7136
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	60033
k_ISDYNAASMsgLenValidThresh_Cnt_u16	24671
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	53505
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	54880
k_ISDYNABRChkSumValidThresh_Cnt_u16	31417
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	63523
k_ISDYNABRMsgCountValidThresh_Cnt_u16	9324
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	60529
k_ISDYNABRMsgLenValidThresh_Cnt_u16	49702
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	2695
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	12126
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	37600
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	26054
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	37296
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	48569
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	300
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	12306
k_ISDYNVOLChkSumValidThresh_Cnt_u16	44560
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	45031
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	60274
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	41719
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	7388
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	37822
k_IgnOnTimeout_mS_u16	32478
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	225.207794
k_PowerCutVehSpdLowThresh_Kph_f32	158.309402
k_PowerCutVehSpdLowTimeout_mS_u16	27470
k_VBattMaxAAS_Volt_f32	12.4312
k_VBattMaxBSI_Volt_f32	32
k_VBattMaxCAV_Volt_f32	12.8541002

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMaxCMM388_Volt_f32	15.9034004
k_VBattMaxCMM_Volt_f32	30.1669998
k_VBattMaxESP_Volt_f32	25.6735992
k_VBattMinAAS_Volt_f32	8.70960045
k_VBattMinBSI_Volt_f32	25.6735992
k_VBattMinCAV_Volt_f32	1.10889995
k_VBattMinCMM388_Volt_f32	25.5296001
k_VBattMinCMM_Volt_f32	20.2821007
k_VBattMinESP_Volt_f32	30.1669998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	59718
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	41779
k_VitesseVehicleBVRampValidThresh_Cnt_u16	20294
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	13062
k_VitesseVehicleBVSigValidThresh_Cnt_u16	26787
k_VitesseVehicleBVSpeedPassThresh_kph_f32	613.95752
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	46109
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	18014
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1718510336
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	186
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65036
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	163190528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	167
target_SrlComInput_Per1_Batt_Volt_f32.value	1.84220004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2342523648
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	1
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.322624534
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4061856512
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	179
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1711055616
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1877885696
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	938468096
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3858858752
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2720211712
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2488582912
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	52
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	121
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	122
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	145
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	172
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1524425472
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	77
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	151
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	171

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	222
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1621230336
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1443078912
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	226
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2708816640
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	89
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	114
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	140
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	158
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1951765248
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2514
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.367320895
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	140566
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	113.364304
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	48604

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	163190528	163190528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	1	1	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	1836	1836	✔
AngleVolantMsgTimer_mS_M_u32	163190528	163190528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	655.057373	655.057373	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	3052	3052	✔
BSINodeAbsentTimer_mS_M_u32	163190528	163190528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1298862848	1298862848	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2720211712	2720211712	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	27015	27015	✔
CONSANGLECPK_HwDeg_M_f32	600.059509	600.059509 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	27015	27015	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1132229376	1132229376	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	15599	15599	✔
CityParkInputConsistentCount_Cnt_M_u16	29182	29182	✔
CityParkInputInvalidCount_Cnt_M_u16	14998	14998	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CityParkInputMsgTimer_mS_M_u32	163190528	163190528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	163190528	163190528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	163190528	163190528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	163190528	163190528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	163190528	163190528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	163190528	163190528	✔
ESPNTCEnableTimer_mS_M_u32	163190528	163190528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	17978	17978	✔
ESPNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	66	66	✔
EffacDefaultDiagTimer_mS_M_u32[1]	78	78	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	163190528	163190528	✔
ElecIntTimer_mS_M_u32[1]	16	16	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	163190528	163190528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	163190528	163190528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	28653	28653	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	61510	61510	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2708816640	2708816640	✔
IgnOnTimer_mS_M_u32	3931702016	3931702016	✔
IgnTimeOff_Sec_M_u32	2956470404	2956470404	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	59	59	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4061856512	4061856512	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	179	179	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1711055616	1711055616	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	45	45	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1877885696	1877885696	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	938468096	938468096	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2700559104	2700559104	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	55	55	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2720211712	2720211712	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2488582912	2488582912	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	60	60	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1524425472	1524425472	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	81	81	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1621230336	1621230336	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	107	107	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1443078912	1443078912	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	226	226	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2708816640	2708816640	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1951765248	1951765248	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	286.059692	286.059692	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	85.4878006	85.4878006	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	182.691605	182.691605	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	655.057373	655.057373	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	27015	27015	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2956470404	2956470404	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	600.059509	600.059509 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	26.4964008	26.4964008	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	3	ValidityNTCProcessing	3	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.187 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1104570880
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	20204
AASNodeAbsentTimer_mS_M_u32	2335267328
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	12569
ANGLEVOLANTSigValidCount_Cnt_M_u16	19901
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	15785
AngleVolantMsgTimer_mS_M_u32	1104570880
AngleVolantValidCount_Cnt_M_u16	60491
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	83.6250153
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1734416896
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3114244608

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1063324160
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2617231872
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	35264
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	325683712
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	17491
CAVNodeAbsentTimer_mS_M_u32	240122368
CDD_SrlComVehSpd_Kph_G_f32	16.5695
CMM388NTCEnableTimer_mS_M_u32	3131849216
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	568719872
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	30998
CMMNodeAbsentTimer_mS_M_u32	518638080
CONSANGLECPKSigInvalidCount_Cnt_M_u16	19733
CONSANGLECPKSigValidCount_Cnt_M_u16	777
CONSANGLECPK_Cnt_M_u16	21588
CONSANGLECPK_HwDeg_M_f32	405.618408
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21588
CPKVehicleSpeedMsgTimer_mS_M_u32	2931124736
CPKVehicleSpeedValidCount_Cnt_M_u16	5795
CityParkInputConsistentCount_Cnt_M_u16	21423
CityParkInputInvalidCount_Cnt_M_u16	8940
CityParkInputMsgTimer_mS_M_u32	4061856512
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3415562752
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	35920
ComputerRazGCTSigInvalidTimer_mS_M_u32	3045095936
ComputerRazGCTSigValidCount_Cnt_M_u16	22564
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	6024
DMDFCTCPKSigValidCount_Cnt_M_u16	41876
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56267
DMDRELAXECPKSigValidCount_Cnt_M_u16	63983
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	54482
DateInvalidTimer_mS_M_u32	3114244608
DiagMuxOnAbsentTimer_mS_M_u32	3693095424
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2617231872
ESPNTCEnableTimer_mS_M_u32	1309825536
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	18614
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	80
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2625341952
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	59623
EtatMTSigValidCount_Cnt_M_u16	20215
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	36295
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	50491
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	45354
ISDAT4V2BSI552MsgTimer_mS_M_u32	2723006976
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	65032
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	11361
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	20215
ISDATBSI3F2MsgTimer_mS_M_u32	3010341376
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	18735
ISDATBSI412MsgLenValidCount_Cnt_M_u16	21431
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	59623

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDATBSI412MsgTimer_mS_M_u32	3743705600
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	32634
ISDATBSI432MsgLenValidCount_Cnt_M_u16	4634
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	37460
ISDATDIRASentFltAcc_Cnt_M_u16	24008
ISDATDIRASentTimer_mS_M_u32	2931124736
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	43554
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	60491
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	22959
ISDYN2CMMMsgTimer_mS_M_u32	226253312
ISDYNAASChkSumInvalidCount_Cnt_M_u16	34206
ISDYNAASChkSumValidCount_Cnt_M_u16	50019
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	62578
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	8670
ISDYNAASMsgLenValidCount_Cnt_M_u16	36378
ISDYNAASMsgTimeValidCount_Cnt_M_u16	34206
ISDYNAASMsgTimer_mS_M_u32	340277760
ISDYNABRChkSumInvalidCount_Cnt_M_u16	4546
ISDYNABRChkSumValidCount_Cnt_M_u16	3247
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	12357
ISDYNABRMsgCountValidCount_Cnt_M_u16	60746
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	23228
ISDYNABRMsgLenValidCount_Cnt_M_u16	53232
ISDYNABRMsgTimeValidCount_Cnt_M_u16	21588
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	725
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1335
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	20215
ISDYNCMM208MsgTimer_mS_M_u32	3893762560
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2751
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1441
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	28825
ISDYNCMM388MsgTimer_mS_M_u32	3791370752
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	56419
ISDYNVOLChkSumValidCount_Cnt_M_u16	4311
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	18902
ISDYNVOLMsgCountValidCount_Cnt_M_u16	37986
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	36111
ISDYNVOLMsgLenValidCount_Cnt_M_u16	31453
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	30998
ISDYNVOLMsgTimer_mS_M_u32	991721984
IgnOnTimer_mS_M_u32	2690628096
IgnTimeOff_Sec_M_u32	34873344
ManVehSpd_Kph_M_f32	221.745193
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	187
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	28
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1189358080
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	146
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1223166464
PrevISDATBSI412MsgDLCError_Cnt_M_u08	44
PrevISDATBSI412MsgRxTime_MSec_M_u32	2333145600
PrevISDATBSI432MsgDLCError_Cnt_M_u08	1
PrevISDATBSI432MsgRxTime_MSec_M_u32	3219544576
PrevISDATDIRAMsgTxTime_MSec_M_u32	3313826304
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	180
PrevISDYN2CMMMsgRxTime_MSec_M_u32	556091904
PrevISDYNAASMsgDLCError_Cnt_M_u08	253
PrevISDYNAASMsgRxTime_MSec_M_u32	3639245312
PrevISDYNABRMsgDLCError_Cnt_M_u08	221
PrevISDYNABRMsgRxTime_MSec_M_u32	2258090496
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	152
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4146035200
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	93

Name	Input Value
PrevISDYNCMM388MsgRxTime_MSec_M_u32	774986240
PrevISDYNVOLMsgDLCError_Cnt_M_u08	185
PrevISDYNVOLMsgRxTime_MSec_M_u32	538835456
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2943511040
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	517.101929
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	6700
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	50408
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	25605
VitesseVehicleBVRampValidCount_Cnt_M_u16	61313
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	19570
VitesseVehicleBVSigValidCount_Cnt_M_u16	27094
VitesseVehicleBV_Kph_M_f32	470.169312
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	28825
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	43957
VitesseVehiculeRoues_Kph_M_f32	505.445709
k_AASNTCEnableTimeout_mS_u16	16243
k_AASNodeAbsentDiag_Cnt_str.Threshold	10757
k_AASNodeAbsentDiag_Cnt_str.PStep	7105
k_AASNodeAbsentDiag_Cnt_str.NStep	65461
k_AASNodeAbsentTimeout_mS_u16	32782
k_AASNodeTimeout_mS_u16	59368
k_ABSNodeTimeout_mS_u16	29693
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	31869
k_ANGLEVOLANTSigValidThresh_Cnt_u16	56157
k_AngleVolantInvalidThresh_Cnt_u16	44748
k_AngleVolantValidThresh_Cnt_u16	8940
k_BSI552MsgTimeout_mS_u16	28644
k_BSINTCEnableTimeout_mS_u16	54706
k_BSINodeAbsentDiag_Cnt_str.Threshold	26412
k_BSINodeAbsentDiag_Cnt_str.PStep	34315
k_BSINodeAbsentDiag_Cnt_str.NStep	15280
k_BSINodeAbsentTimeout_mS_u16	50657
k_BSINodeTimeout_mS_u16	37460
k_BattOvHi_Volt_f32	17.0242004
k_BattOvLo_Volt_f32	2.94370008
k_BattUvHi_Volt_f32	1.99370003
k_BattUvLo_Volt_f32	1.99000001
k_CAVNTCEnableTimeout_mS_u16	370
k_CAVNodeAbsentDiag_Cnt_str.Threshold	9850
k_CAVNodeAbsentDiag_Cnt_str.PStep	55599
k_CAVNodeAbsentDiag_Cnt_str.NStep	26463
k_CAVNodeAbsentTimeout_mS_u16	55201
k_CAVNodeTimeout_mS_u16	40625
k_CMM388MsgTimeout_mS_u16	45548
k_CMM388NTCEnableTimeout_mS_u16	46216
k_CMMNTCEnableTimeout_mS_u16	12352
k_CMMNodeAbsentDiag_Cnt_str.Threshold	32647
k_CMMNodeAbsentDiag_Cnt_str.PStep	42126
k_CMMNodeAbsentDiag_Cnt_str.NStep	57005
k_CMMNodeAbsentTimeout_mS_u16	50257
k_CONSANGLECPKMax_HwDeg_f32	769.892212
k_CONSANGLECPKMin_HwDeg_f32	-200.728699
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	21401
k_CONSANGLECPKSigValidThresh_Cnt_u16	52917
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	36990
k_CPKVehicleSpeedValidThresh_Cnt_u16	9338
k_CityParkInputInvalidThresh_Cnt_u16	18136

Name	Input Value
k_CityParkInputValidThresh_Cnt_u16	21423
k_ComputerRazGCTSigValidThresh_Cnt_u16	27646
k_CptTemporelSigValidThresh_Cnt_u16	18135
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	48572
k_DMDFCTCPKSigValidThresh_Cnt_u16	29424
k_DMDFCTCPKValidCount_Cnt_u16	29832
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	22959
k_DMDRELAXECPKSigValidThresh_Cnt_u16	1275
k_DMDRelaxeConsistentThresh_Cnt_u16	14225
k_DateValidThresh_Cnt_u16	45354
k_DefaultVehSpd_Kph_f32	252.177902
k_DiagMuxOnAbsentTimeout_mS_u16	50266
k_EMNodeTimeout_mS_u16	32306
k_ESPNTCEnableTimeout_mS_u16	22511
k_ESPNodeAbsentDiag_Cnt_str.Threshold	40274
k_ESPNodeAbsentDiag_Cnt_str.PStep	1844
k_ESPNodeAbsentDiag_Cnt_str.NStep	56738
k_ESPNodeAbsentTimeout_mS_u16	63001
k_EtatMTSigInvalidThresh_Cnt_u16	16145
k_EtatMTSigValidThresh_Cnt_u16	59198
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	54697
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	154
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	36744
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	12261
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	63998
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	21907
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	39639
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	59703
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	50654
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	2584
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	30913
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	19449
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	57694
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	64942
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	15785
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	41755
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	62658
k_ISDYNAASChkSumValidThresh_Cnt_u16	12207
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	37701
k_ISDYNAASMsgCountValidThresh_Cnt_u16	36938
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	25894
k_ISDYNAASMsgLenValidThresh_Cnt_u16	10060
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	43813
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	13578
k_ISDYNABRChkSumValidThresh_Cnt_u16	26814
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	60608
k_ISDYNABRMsgCountValidThresh_Cnt_u16	18596
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	39958
k_ISDYNABRMsgLenValidThresh_Cnt_u16	43958
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	49747
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	63888
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7752
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	29463
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	37913
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	61629
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	12068
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	36530
k_ISDYNVOLChkSumValidThresh_Cnt_u16	50554
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	9843
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	58131
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	24963
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	17555
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	30768
k_IgnOnTimeout_mS_u16	53838
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	168.543594
k_PowerCutVehSpdLowThresh_Kph_f32	89.2388992
k_PowerCutVehSpdLowTimeout_mS_u16	11007
k_VBattMaxAAS_Volt_f32	18.0932007
k_VBattMaxBSI_Volt_f32	4.42439985

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMaxCAV_Volt_f32	11.1595001
k_VBattMaxCMM388_Volt_f32	5.90420008
k_VBattMaxCMM_Volt_f32	3.17090011
k_VBattMaxESP_Volt_f32	28.7360001
k_VBattMinAAS_Volt_f32	4.60459995
k_VBattMinBSI_Volt_f32	28.7360001
k_VBattMinCAV_Volt_f32	2.55430007
k_VBattMinCMM388_Volt_f32	24.5596008
k_VBattMinCMM_Volt_f32	32
k_VBattMinESP_Volt_f32	3.17090011
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	16408
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	33552
k_VitesseVehicleBVRampValidThresh_Cnt_u16	11478
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	46039
k_VitesseVehicleBVSigValidThresh_Cnt_u16	17344
k_VitesseVehicleBVSpeedPassThresh_kph_f32	413.442688
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	10067
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	12623
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3114244608
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	61
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	93
target_SrlComInput_Per1_Batt_Volt_f32.value	8.80679989
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1825212928
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	90
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.809025943
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	286898688
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3287603712
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	140
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4104124928
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	723196416
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4016454144
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3380697600
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1097628160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	85
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	89
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	199
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	211
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3058964992
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	43
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	194
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	204

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2709830144
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3487554048
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	185
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1007352320
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	55
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	229
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	247
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1755974144
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3473
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.864297211
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	992726
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	108.324097
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	50710

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	12570	12570	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	15787	15787	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	83.6250153	83.6250153	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26412	26412	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	325683712	325683712	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3380697600	3380697600	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	21588	21588	✔
CONSANGLECPK_HwDeg_M_f32	405.618408	405.618408 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21588	21588	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2931124736	2931124736	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	5795	5795	✔
CityParkInputConsistentCount_Cnt_M_u16	21423	21423	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CityParkInputInvalidCount_Cnt_M_u16	8942	8942	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	40274	40274	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	80	80	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	56419	56419	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	18902	18902	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1007352320	1007352320	✔
IgnOnTimer_mS_M_u32	2690628096	2690628096	✔
IgnTimeOff_Sec_M_u32	34873344	34873344	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	68	68	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	286898688	286898688	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3287603712	3287603712	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	140	140	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4104124928	4104124928	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	14	14	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	723196416	723196416	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3313826304	3313826304	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	121	121	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3380697600	3380697600	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	113	113	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1097628160	1097628160	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	194	194	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3058964992	3058964992	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	223	223	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2709830144	2709830144	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	129	129	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3487554048	3487554048	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	185	185	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1007352320	1007352320	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1755974144	1755974144	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	517.101929	517.101929	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1	1	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	470.169312	470.169312	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VitesseVehiculeRoues_Kph_M_f32	505.445709	505.445709	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	83.6250153	83.6250153	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	21588	21588	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	34873344	34873344	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	405.618408	405.618408 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	252.177902	252.177902	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0151	0x0151	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0152	0x0152	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔
NTC	0x0153	0x0153	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	3	ValidityNTCProcessing	3	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.188 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1897418240
AASNTCsEnabled_Cnt_M_lgc	0

Name	Input Value
AASNodeAbsentFltAcc_Cnt_M_u16	7478
AASNodeAbsentTimer_mS_M_u32	2715696640
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	5451
ANGLEVOLANTSigValidCount_Cnt_M_u16	38994
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	46851
AngleVolantMsgTimer_mS_M_u32	1897418240
AngleVolantValidCount_Cnt_M_u16	12798
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	208.824875
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2029649408
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2260762112
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1542778368
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2251271680
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	21026
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2594532864
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	13487
CAVNodeAbsentTimer_mS_M_u32	277798400
CDD_SrlComVehSpd_Kph_G_f32	73.6837006
CMM388NTCEnableTimer_mS_M_u32	767499776
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	587521536
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	36169
CMMNodeAbsentTimer_mS_M_u32	305769984
CONSANGLECPKSigInvalidCount_Cnt_M_u16	56307
CONSANGLECPKSigValidCount_Cnt_M_u16	57674
CONSANGLECPK_Cnt_M_u16	2565
CONSANGLECPK_HwDeg_M_f32	602.717773
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2565
CPKVehicleSpeedMsgTimer_mS_M_u32	2477215232
CPKVehicleSpeedValidCount_Cnt_M_u16	24826
CityParkInputConsistentCount_Cnt_M_u16	10402
CityParkInputInvalidCount_Cnt_M_u16	40708
CityParkInputMsgTimer_mS_M_u32	1436333824
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1099054592
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	51674
ComputerRazGCTSigInvalidTimer_mS_M_u32	2665963008
ComputerRazGCTSigValidCount_Cnt_M_u16	8615
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	50272
DMDFCTCPKSigValidCount_Cnt_M_u16	1871
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	47005
DMDRELAXECPKSigValidCount_Cnt_M_u16	46116
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	57024
DateInvalidTimer_mS_M_u32	2260762112
DiagMuxOnAbsentTimer_mS_M_u32	2389577216
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2251271680
ESPNTCEnableTimer_mS_M_u32	2601467392
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	29196
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	1000
EffacDefaultDiagTimer_mS_M_u32[1]	4294967295
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	565
ElecIntTimer_mS_M_u32[1]	78790
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2572643840
EngOnDLCInvalidCount_Cnt_M_u08	3

Name	Input Value
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	4734
EtatMTSigValidCount_Cnt_M_u16	37041
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	62533
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	62236
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	13253
ISDAT4V2BSI552MsgTimer_mS_M_u32	3839733248
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	53261
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	11529
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	37041
ISDATBSI3F2MsgTimer_mS_M_u32	236719616
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	19239
ISDATBSI412MsgLenValidCount_Cnt_M_u16	21331
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	4734
ISDATBSI412MsgTimer_mS_M_u32	2529578496
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	53997
ISDATBSI432MsgLenValidCount_Cnt_M_u16	27312
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	13056
ISDATDIRASentFltAcc_Cnt_M_u16	53940
ISDATDIRASentTimer_mS_M_u32	2477215232
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	36915
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	12798
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	58039
ISDYN2CMMMsgTimer_mS_M_u32	1268334080
ISDYNAASChkSumInvalidCount_Cnt_M_u16	2952
ISDYNAASChkSumValidCount_Cnt_M_u16	2480
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	63061
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	48554
ISDYNAASMsgLenValidCount_Cnt_M_u16	61385
ISDYNAASMsgTimeValidCount_Cnt_M_u16	2952
ISDYNAASMsgTimer_mS_M_u32	1209736704
ISDYNABRChkSumInvalidCount_Cnt_M_u16	47330
ISDYNABRChkSumValidCount_Cnt_M_u16	0
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	14943
ISDYNABRMsgCountValidCount_Cnt_M_u16	31687
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	24010
ISDYNABRMsgLenValidCount_Cnt_M_u16	58977
ISDYNABRMsgTimeValidCount_Cnt_M_u16	2565
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	760
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1405
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	37041
ISDYNCMM208MsgTimer_mS_M_u32	3258908160
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2891
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1511
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	28332
ISDYNCMM388MsgTimer_mS_M_u32	4125531648
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	37793
ISDYNVOLChkSumValidCount_Cnt_M_u16	40824
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	3854
ISDYNVOLMsgCountValidCount_Cnt_M_u16	39037
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	57909
ISDYNVOLMsgLenValidCount_Cnt_M_u16	52332
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	36169
ISDYNVOLMsgTimer_mS_M_u32	2772655616
IgnOnTimer_mS_M_u32	1938464256
IgnTimeOff_Sec_M_u32	1907185217
ManVehSpd_Kph_M_f32	107.513603
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	139
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	42
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2524057088
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	131
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2410409472

Name	Input Value
PrevISDATBSI412MsgDLCError_Cnt_M_u08	35
PrevISDATBSI412MsgRxTime_MSec_M_u32	3651132928
PrevISDATBSI432MsgDLCError_Cnt_M_u08	216
PrevISDATBSI432MsgRxTime_MSec_M_u32	3743628800
PrevISDATDIRAMsgTxTime_MSec_M_u32	2555633152
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	35
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3742182912
PrevISDYNAASMsgDLCError_Cnt_M_u08	129
PrevISDYNAASMsgRxTime_MSec_M_u32	4084293120
PrevISDYNABRMsgDLCError_Cnt_M_u08	2
PrevISDYNABRMsgRxTime_MSec_M_u32	3410140672
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	185
PrevISDYNCMM208MsgRxTime_MSec_M_u32	305552896
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	231
PrevISDYNCMM388MsgRxTime_MSec_M_u32	886980096
PrevISDYNVOLMsgDLCError_Cnt_M_u08	149
PrevISDYNVOLMsgRxTime_MSec_M_u32	314367488
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3748941312
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	436.490387
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	44632
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	42743
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	56321
VitesseVehicleBVRampValidCount_Cnt_M_u16	61792
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	35956
VitesseVehicleBVSigValidCount_Cnt_M_u16	19515
VitesseVehicleBV_Kph_M_f32	439.672699
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	28332
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	5548
VitesseVehiculeRoues_Kph_M_f32	256.362701
k_AASNTCEnableTimeout_mS_u16	7892
k_AASNodeAbsentDiag_Cnt_str.Threshold	19835
k_AASNodeAbsentDiag_Cnt_str.PStep	23642
k_AASNodeAbsentDiag_Cnt_str.NStep	36621
k_AASNodeAbsentTimeout_mS_u16	58033
k_AASNodeTimeout_mS_u16	47607
k_ABSNodeTimeout_mS_u16	38245
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	53472
k_ANGLEVOLANTSigValidThresh_Cnt_u16	2275
k_AngleVolantInvalidThresh_Cnt_u16	40706
k_AngleVolantValidThresh_Cnt_u16	40708
k_BSI552MsgTimeout_mS_u16	55435
k_BSINTCEnableTimeout_mS_u16	39589
k_BSINodeAbsentDiag_Cnt_str.Threshold	3174
k_BSINodeAbsentDiag_Cnt_str.PStep	3062
k_BSINodeAbsentDiag_Cnt_str.NStep	18580
k_BSINodeAbsentTimeout_mS_u16	20667
k_BSINodeTimeout_mS_u16	13056
k_BattOvHi_Volt_f32	19.7075005
k_BattOvLo_Volt_f32	13.5094995
k_BattUvHi_Volt_f32	16.1632996
k_BattUvLo_Volt_f32	6.08419991
k_CAVNTCEnableTimeout_mS_u16	59242
k_CAVNodeAbsentDiag_Cnt_str.Threshold	55765
k_CAVNodeAbsentDiag_Cnt_str.PStep	20281
k_CAVNodeAbsentDiag_Cnt_str.NStep	49008
k_CAVNodeAbsentTimeout_mS_u16	12381
k_CAVNodeTimeout_mS_u16	28239

Name	Input Value
k_CMM388MsgTimeout_mS_u16	28726
k_CMM388NTCEnableTimeout_mS_u16	914
k_CMMNTCEnableTimeout_mS_u16	13253
k_CMMNodeAbsentDiag_Cnt_str.Threshold	413
k_CMMNodeAbsentDiag_Cnt_str.PStep	35980
k_CMMNodeAbsentDiag_Cnt_str.NStep	5967
k_CMMNodeAbsentTimeout_mS_u16	40712
k_CONSANGLECPKMax_HwDeg_f32	528.807678
k_CONSANGLECPKMin_HwDeg_f32	-501.649109
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	16812
k_CONSANGLECPKSigValidThresh_Cnt_u16	10412
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	61805
k_CPKVehicleSpeedValidThresh_Cnt_u16	7650
k_CityParkInputInvalidThresh_Cnt_u16	25816
k_CityParkInputValidThresh_Cnt_u16	10402
k_ComputerRazGCTSigValidThresh_Cnt_u16	31459
k_CptTemporelSigValidThresh_Cnt_u16	27743
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	45258
k_DMDFCTCPKSigValidThresh_Cnt_u16	31073
k_DMDFCTCPKValidCount_Cnt_u16	7018
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	58039
k_DMDRELAXECPKSigValidThresh_Cnt_u16	2278
k_DMDRelaxeConsistentThresh_Cnt_u16	59996
k_DateValidThresh_Cnt_u16	13253
k_DefaultVehSpd_Kph_f32	128.661804
k_DiagMuxOnAbsentTimeout_mS_u16	23531
k_EMNodeTimeout_mS_u16	30240
k_ESPNTCEnableTimeout_mS_u16	10507
k_ESPNodeAbsentDiag_Cnt_str.Threshold	63570
k_ESPNodeAbsentDiag_Cnt_str.PStep	54417
k_ESPNodeAbsentDiag_Cnt_str.NStep	48292
k_ESPNodeAbsentTimeout_mS_u16	57168
k_EtatMTSigInvalidThresh_Cnt_u16	48865
k_EtatMTSigValidThresh_Cnt_u16	59377
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	17416
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	3356
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	59467
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	42746
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	19382
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	30411
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	35674
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	35549
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	22673
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	52489
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	33620
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	8486
k_ISDATDIRASentDiag_Cnt_str.Threshold	13378
k_ISDATDIRASentDiag_Cnt_str.PStep	37990
k_ISDATDIRASentDiag_Cnt_str.NStep	48989
k_ISDATDIRASentTimeout_mS_u16	10558
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	60267
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	46851
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	45559
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	35810
k_ISDYNAASChkSumValidThresh_Cnt_u16	9138
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	36191
k_ISDYNAASMsgCountValidThresh_Cnt_u16	3783
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	23430
k_ISDYNAASMsgLenValidThresh_Cnt_u16	2203
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	18219
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	53368
k_ISDYNABRChkSumValidThresh_Cnt_u16	40847
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	42274
k_ISDYNABRMsgCountValidThresh_Cnt_u16	11113
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	41033
k_ISDYNABRMsgLenValidThresh_Cnt_u16	50444
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	23496
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	40188
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	34832
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	29654
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	26699
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	11090
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	64700

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	14746
k_ISDYNVOLChkSumValidThresh_Cnt_u16	16902
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	43737
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	9814
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	64474
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	1805
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	3243
k_IgnOnTimeout_mS_u16	24054
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	172.2854
k_PowerCutVehSpdLowThresh_Kph_f32	52.6057014
k_PowerCutVehSpdLowTimeout_mS_u16	26144
k_VBattMaxAAS_Volt_f32	5.07560015
k_VBattMaxBSI_Volt_f32	1.59949994
k_VBattMaxCAV_Volt_f32	7.97289991
k_VBattMaxCMM388_Volt_f32	27.4864006
k_VBattMaxCMM_Volt_f32	13.7613001
k_VBattMaxESP_Volt_f32	27.0597
k_VBattMinAAS_Volt_f32	32
k_VBattMinBSI_Volt_f32	27.0597
k_VBattMinCAV_Volt_f32	25.5219994
k_VBattMinCMM388_Volt_f32	10.6457005
k_VBattMinCMM_Volt_f32	12.9473
k_VBattMinESP_Volt_f32	1.76129997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	3829
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	62096
k_VitesseVehicleBVRampValidThresh_Cnt_u16	57870
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	12920
k_VitesseVehicleBVSigValidThresh_Cnt_u16	28163
k_VitesseVehicleBVSpeedPassThresh_kph_f32	195.636398
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	1967
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	9102
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2260762112
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	13090
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	4294967295
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	231
target_SrlComInput_Per1_Batt_Volt_f32.value	11.6309004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	844525056
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	141
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.733558714
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1046781440
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	800701952
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	13
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4024360448
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2262040064
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4237893120
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	165
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1496202752
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	248
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2761121280
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	92

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	105
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	187
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	191
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	217
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1675427328
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	68
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	80
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	130
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	147
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1614781952
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1695858176
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4172930560
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	38
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	118
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	242
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1007545856
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3370
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.386255831
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	26008
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	191.507294
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	13154

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	19835	19835	✔
AASNodeAbsentTimer_mS_M_u32	4294967295	4294967295	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	4294967295	4294967295	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	208.824875	208.824875	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	4294967295	4294967295	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	55765	55765	✔
CAVNodeAbsentTimer_mS_M_u32	4294967295	4294967295	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4294967295	4294967295	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	30202	30202	✔
CMMNodeAbsentTimer_mS_M_u32	1496202752	1496202752	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	2565	2565	✔
CONSANGLECPK_HwDeg_M_f32	602.717773	602.717773 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2	2	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4294967295	4294967295	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	4294967295	4294967295	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4294967295	4294967295	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4294967295	4294967295	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4294967295	4294967295	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4294967295	4294967295	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4294967295	4294967295	✔
ESPNTCEnableTimer_mS_M_u32	2601467392	2601467392	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4294967295	4294967295	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1000	1000	✔
EffacDefaultDiagTimer_mS_M_u32[1]	4294967295	4294967295	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	4294967295	4294967295	✔
ElecIntTimer_mS_M_u32[1]	78790	78790	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4294967295	4294967295	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDATDIRASentFltAcc_Cnt_M_u16	13378	13378	✔
ISDATDIRASentTimer_mS_M_u32	4294967295	4294967295	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4294967295	4294967295	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	1	1	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1675427328	1675427328	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4294967295	4294967295	✔
IgnOnTimer_mS_M_u32	1938464256	1938464256	✔
IgnTimeOff_Sec_M_u32	1907185217	1907185217	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	168	168	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1046781440	1046781440	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	53	53	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	800701952	800701952	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	13	13	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4024360448	4024360448	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	55	55	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2262040064	2262040064	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2555633152	2555633152	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	165	165	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1496202752	1496202752	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	248	248	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2761121280	2761121280	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	2	2	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1675427328	1675427328	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	8	8	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1614781952	1614781952	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1695858176	1695858176	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4172930560	4172930560	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1007545856	1007545856	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	436.490387	436.490387	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	439.672699	439.672699	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	256.362701	256.362701	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	208.824875	208.824875	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	2565	2565	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1907185217	1907185217	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	602.717773	602.717773 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	128.661804	128.661804	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	4	ValidityNTCProcessing	4	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.189 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4211988736
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	37042
AASNodeAbsentTimer_mS_M_u32	746326272
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	39540
ANGLEVOLANTSigValidCount_Cnt_M_u16	47902
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	14155

Name	Input Value
AngleVolantMsgTimer_mS_M_u32	4211988736
AngleVolantValidCount_Cnt_M_u16	6873
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	68.6426468
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3324561664
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3604302080
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	4109891840
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3511138560
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	65519
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2598795520
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	29896
CAVNodeAbsentTimer_mS_M_u32	3941214464
CDD_SrlComVehSpd_Kph_G_f32	411.160492
CMM388NTCEnableTimer_mS_M_u32	2757323008
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	193472768
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	11707
CMMNodeAbsentTimer_mS_M_u32	3576281344
CONSANGLECPKSigInvalidCount_Cnt_M_u16	38269
CONSANGLECPKSigValidCount_Cnt_M_u16	28471
CONSANGLECPK_Cnt_M_u16	41222
CONSANGLECPK_HwDeg_M_f32	130.394608
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	41222
CPKVehicleSpeedMsgTimer_mS_M_u32	2405488896
CPKVehicleSpeedValidCount_Cnt_M_u16	50960
CityParkInputConsistentCount_Cnt_M_u16	50925
CityParkInputInvalidCount_Cnt_M_u16	30922
CityParkInputMsgTimer_mS_M_u32	1046781440
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3717204224
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	6854
ComputerRazGCTSigInvalidTimer_mS_M_u32	1105242368
ComputerRazGCTSigValidCount_Cnt_M_u16	12254
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	30902
DMDFCTCPKSigValidCount_Cnt_M_u16	63911
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	31614
DMDRELAXECPKSigValidCount_Cnt_M_u16	12200
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	278
DateInvalidTimer_mS_M_u32	3604302080
DiagMuxOnAbsentTimer_mS_M_u32	705468672
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3511138560
ESPNTCEnableTimer_mS_M_u32	1156122880
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	6449
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	80
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3872422144
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	795
EtatMTSigValidCount_Cnt_M_u16	57921
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	5255
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	449
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	52293

Name	Input Value
ISDAT4V2BSI552MsgTimer_mS_M_u32	3980245248
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	49133
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	8891
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	57921
ISDATBSI3F2MsgTimer_mS_M_u32	3808598272
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	34718
ISDATBSI412MsgLenValidCount_Cnt_M_u16	43228
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	795
ISDATBSI412MsgTimer_mS_M_u32	3255032064
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	60623
ISDATBSI432MsgLenValidCount_Cnt_M_u16	48965
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	64981
ISDATDIRASentFltAcc_Cnt_M_u16	61113
ISDATDIRASentTimer_mS_M_u32	2405488896
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	18044
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	6873
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	14769
ISDYN2CMMMsgTimer_mS_M_u32	3679127808
ISDYNAASChkSumInvalidCount_Cnt_M_u16	36284
ISDYNAASChkSumValidCount_Cnt_M_u16	48390
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	59860
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	34263
ISDYNAASMsgLenValidCount_Cnt_M_u16	63801
ISDYNAASMsgTimeValidCount_Cnt_M_u16	36284
ISDYNAASMsgTimer_mS_M_u32	3309660416
ISDYNABRChkSumInvalidCount_Cnt_M_u16	50478
ISDYNABRChkSumValidCount_Cnt_M_u16	65535
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	7479
ISDYNABRMsgCountValidCount_Cnt_M_u16	33473
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	11256
ISDYNABRMsgLenValidCount_Cnt_M_u16	31730
ISDYNABRMsgTimeValidCount_Cnt_M_u16	41222
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	725
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1335
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	57921
ISDYNCMM208MsgTimer_mS_M_u32	1046071552
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2751
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1441
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	40143
ISDYNCMM388MsgTimer_mS_M_u32	1239607552
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	42611
ISDYNVOLChkSumValidCount_Cnt_M_u16	27821
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	53420
ISDYNVOLMsgCountValidCount_Cnt_M_u16	32285
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	44214
ISDYNVOLMsgLenValidCount_Cnt_M_u16	22479
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	11707
ISDYNVOLMsgTimer_mS_M_u32	2664212736
IgnOnTimer_mS_M_u32	1626794240
IgnTimeOff_Sec_M_u32	584502426
ManVehSpd_Kph_M_f32	606.434021
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	187
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	235
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	570464512
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	94
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4124244224
PrevISDATBSI412MsgDLCError_Cnt_M_u08	243
PrevISDATBSI412MsgRxTime_MSec_M_u32	330770688
PrevISDATBSI432MsgDLCError_Cnt_M_u08	137
PrevISDATBSI432MsgRxTime_MSec_M_u32	3366783232
PrevISDATDIRAMsgTxTime_MSec_M_u32	2811963648
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	82

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevISDYN2CMMMsgRxTime_MSec_M_u32	481245440
PrevISDYNAASMsgDLCError_Cnt_M_u08	114
PrevISDYNAASMsgRxTime_MSec_M_u32	3963791616
PrevISDYNABRMsgDLCError_Cnt_M_u08	93
PrevISDYNABRMsgRxTime_MSec_M_u32	969861376
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	214
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3824396544
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	251
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1937508608
PrevISDYNVOLMsgDLCError_Cnt_M_u08	80
PrevISDYNVOLMsgRxTime_MSec_M_u32	476064000
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	536467712
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	86.7611008
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	60365
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	2991
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	18130
VitesseVehicleBVRampValidCount_Cnt_M_u16	4212
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	6393
VitesseVehicleBVSigValidCount_Cnt_M_u16	33635
VitesseVehicleBV_Kph_M_f32	177.203705
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	40143
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	12689
VitesseVehiculeRoues_Kph_M_f32	54.1287003
k_AASNTCEnableTimeout_mS_u16	24217
k_AASNodeAbsentDiag_Cnt_str.Threshold	10757
k_AASNodeAbsentDiag_Cnt_str.PStep	7105
k_AASNodeAbsentDiag_Cnt_str.NStep	65461
k_AASNodeAbsentTimeout_mS_u16	38080
k_AASNodeTimeout_mS_u16	53935
k_ABSNodeTimeout_mS_u16	22951
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	32502
k_ANGLEVOLANTSigValidThresh_Cnt_u16	28844
k_AngleVolantInvalidThresh_Cnt_u16	59983
k_AngleVolantValidThresh_Cnt_u16	30922
k_BSI552MsgTimeout_mS_u16	9460
k_BSINTCEnableTimeout_mS_u16	30119
k_BSINodeAbsentDiag_Cnt_str.Threshold	26412
k_BSINodeAbsentDiag_Cnt_str.PStep	34315
k_BSINodeAbsentDiag_Cnt_str.NStep	15280
k_BSINodeAbsentTimeout_mS_u16	18979
k_BSINodeTimeout_mS_u16	64981
k_BattOvHi_Volt_f32	18.2665997
k_BattOvLo_Volt_f32	6.74109983
k_BattUvHi_Volt_f32	4.07989979
k_BattUvLo_Volt_f32	1.02390003
k_CAVNTCEnableTimeout_mS_u16	47000
k_CAVNodeAbsentDiag_Cnt_str.Threshold	9850
k_CAVNodeAbsentDiag_Cnt_str.PStep	55599
k_CAVNodeAbsentDiag_Cnt_str.NStep	26463
k_CAVNodeAbsentTimeout_mS_u16	47550
k_CAVNodeTimeout_mS_u16	20073
k_CMM388MsgTimeout_mS_u16	38834
k_CMM388NTCEnableTimeout_mS_u16	19870
k_CMMNTCEnableTimeout_mS_u16	29893
k_CMMNodeAbsentDiag_Cnt_str.Threshold	32647
k_CMMNodeAbsentDiag_Cnt_str.PStep	42126
k_CMMNodeAbsentDiag_Cnt_str.NStep	57005

Name	Input Value
k_CMMNodeAbsentTimeout_mS_u16	1405
k_CONSANGLECPKMax_HwDeg_f32	86.439003
k_CONSANGLECPKMin_HwDeg_f32	-595.820618
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	9167
k_CONSANGLECPKSigValidThresh_Cnt_u16	63633
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	33869
k_CPKVehicleSpeedValidThresh_Cnt_u16	47981
k_CityParkInputInvalidThresh_Cnt_u16	6476
k_CityParkInputValidThresh_Cnt_u16	50925
k_ComputerRazGCTSigValidThresh_Cnt_u16	38763
k_CptTemporelSigValidThresh_Cnt_u16	15545
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	13048
k_DMDFCTCPKSigValidThresh_Cnt_u16	49906
k_DMDFCTCPKValidCount_Cnt_u16	50199
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	14769
k_DMDRELAXECPKSigValidThresh_Cnt_u16	4322
k_DMDRelaxeConsistentThresh_Cnt_u16	50304
k_DateValidThresh_Cnt_u16	52293
k_DefaultVehSpd_Kph_f32	248.853394
k_DiagMuxOnAbsentTimeout_mS_u16	50004
k_EMNodeTimeout_mS_u16	47862
k_ESPNTCEnableTimeout_mS_u16	1972
k_ESPNodeAbsentDiag_Cnt_str.Threshold	40274
k_ESPNodeAbsentDiag_Cnt_str.PStep	1844
k_ESPNodeAbsentDiag_Cnt_str.NStep	56738
k_ESPNodeAbsentTimeout_mS_u16	25765
k_EtatMTSigInvalidThresh_Cnt_u16	28465
k_EtatMTSigValidThresh_Cnt_u16	48579
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	47228
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	14081
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	27634
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	12070
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	47796
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	38066
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	46984
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	21182
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	60387
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	26618
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	65239
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	52900
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	58394
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	50133
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	14155
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	7408
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	19502
k_ISDYNAASChkSumValidThresh_Cnt_u16	20096
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	9271
k_ISDYNAASMsgCountValidThresh_Cnt_u16	51649
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	27970
k_ISDYNAASMsgLenValidThresh_Cnt_u16	30403
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	54740
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	3054
k_ISDYNABRChkSumValidThresh_Cnt_u16	34920
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	1775
k_ISDYNABRMsgCountValidThresh_Cnt_u16	7641
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	62651
k_ISDYNABRMsgLenValidThresh_Cnt_u16	8241
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	51388
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	45025
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	46307
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	57618
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	41332
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	542
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	16290
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	18501
k_ISDYNVOLChkSumValidThresh_Cnt_u16	26819
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	58058
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	54932
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	46855
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	61229

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	22931
k_IgnOnTimeout_mS_u16	19249
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	252.482803
k_PowerCutVehSpdLowThresh_Kph_f32	43.5219002
k_PowerCutVehSpdLowTimeout_mS_u16	47285
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	23.9911995
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	0.310200006
k_VBattMaxCMM_Volt_f32	9.48429966
k_VBattMaxESP_Volt_f32	12.9438
k_VBattMinAAS_Volt_f32	0.350800008
k_VBattMinBSI_Volt_f32	2.94379997
k_VBattMinCAV_Volt_f32	16.4192009
k_VBattMinCMM388_Volt_f32	17.0265999
k_VBattMinCMM_Volt_f32	21.4330997
k_VBattMinESP_Volt_f32	9.48429966
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	311
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	20516
k_VitesseVehicleBVRampValidThresh_Cnt_u16	22444
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	45997
k_VitesseVehicleBVSigValidThresh_Cnt_u16	47818
k_VitesseVehicleBVSpeedPassThresh_kph_f32	271.560211
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	64456
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	45546
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3604302080
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	251
target_SrlComInput_Per1_Batt_Volt_f32.value	11.8369999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3620960512
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	139
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.556387663
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3899189504
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	184
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1357482240
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	13
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2365204736
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2224736512
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	533424384
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1183582464
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	62
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3772557568
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	61
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	169
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	245

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1367329024
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	109
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	172
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2933385472
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3705178368
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2657691904
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	90
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	121
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	138
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4172085504
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	789
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.325458407
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	908600
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	106.067001
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	1199

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	10757	10757	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	14157	14157	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	68.6426468	68.6426468	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3324561664	3324561664	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3511138560	3511138560	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26412	26412	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	32647	32647	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	41222	41222	✔
CONSANGLECPK_HwDeg_M_f32	130.394608	130.394608 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	41222	41222	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3251510528	3251510528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	50925	50925	✔
CityParkInputInvalidCount_Cnt_M_u16	30922	30922	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3717204224	3717204224	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1105242368	1105242368	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	1156122880	1156122880	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	80	80	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	5256	5256	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3899189504	3899189504	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	50478	50478	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	7479	7479	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1367329024	1367329024	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	1626794240	1626794240	✔
IgnTimeOff_Sec_M_u32	584502426	584502426	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	194	194	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3899189504	3899189504	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	184	184	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1357482240	1357482240	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	13	13	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2365204736	2365204736	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	170	170	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2224736512	2224736512	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2811963648	2811963648	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	91	91	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1183582464	1183582464	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	62	62	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3772557568	3772557568	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	93	93	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1367329024	1367329024	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	206	206	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2933385472	2933385472	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	169	169	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3705178368	3705178368	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2657691904	2657691904	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4172085504	4172085504	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	86.7611008	86.7611008	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	177.203705	177.203705	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	54.1287003	54.1287003	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	68.6426468	68.6426468	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	41222	41222	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	584502426	584502426	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	130.394608	130.394608 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	248.853394	248.853394	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0132	0x0132	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔
NTC	0x0133	0x0133	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔
NTC	0x0161	0x0161	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	2	ValidityNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.190 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4112070656
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	26155
AASNodeAbsentTimer_mS_M_u32	361670656
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	29412
ANGLEVOLANTSigValidCount_Cnt_M_u16	5031
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	5728
AngleVolantMsgTimer_mS_M_u32	4112070656
AngleVolantValidCount_Cnt_M_u16	28212
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	47.1257095
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3951585280
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	193128448
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3621443584
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	837523456
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	61043
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3222231040
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	14953
CAVNodeAbsentTimer_mS_M_u32	3133425664
CDD_SrlComVehSpd_Kph_G_f32	31.7952995
CMM388NTCEnableTimer_mS_M_u32	1534494720
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1357531136

Name	Input Value
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	51024
CMMNodeAbsentTimer_mS_M_u32	776312832
CONSANGLECPKSigInvalidCount_Cnt_M_u16	38089
CONSANGLECPKSigValidCount_Cnt_M_u16	19036
CONSANGLECPK_Cnt_M_u16	45295
CONSANGLECPK_HwDeg_M_f32	-239.725494
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	45295
CPKVehicleSpeedMsgTimer_mS_M_u32	1142962176
CPKVehicleSpeedValidCount_Cnt_M_u16	24089
CityParkInputConsistentCount_Cnt_M_u16	47608
CityParkInputInvalidCount_Cnt_M_u16	25956
CityParkInputMsgTimer_mS_M_u32	3899189504
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1381148672
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	6127
ComputerRazGCTSigInvalidTimer_mS_M_u32	2950744064
ComputerRazGCTSigValidCount_Cnt_M_u16	33573
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	5536
DMDFCTCPKSigValidCount_Cnt_M_u16	46475
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	30662
DMDRELAXECPKSigValidCount_Cnt_M_u16	24073
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	62974
DateInvalidTimer_mS_M_u32	193128448
DiagMuxOnAbsentTimer_mS_M_u32	3541891072
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	837523456
ESPNTCEnableTimer_mS_M_u32	3225921536
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	14255
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	41
EffacDefaultDiagTimer_mS_M_u32[1]	46
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	56565
ElecIntTimer_mS_M_u32[1]	787880
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	72439808
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	6191
EtatMTSigValidCount_Cnt_M_u16	28030
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	49067
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	15038
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	13745
ISDAT4V2BSI552MsgTimer_mS_M_u32	906598400
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	314
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	27537
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	28030
ISDATBSI3F2MsgTimer_mS_M_u32	3864576
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	65318
ISDATBSI412MsgLenValidCount_Cnt_M_u16	60973
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	6191
ISDATBSI412MsgTimer_mS_M_u32	4164368384
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	55828
ISDATBSI432MsgLenValidCount_Cnt_M_u16	38259
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	4930
ISDATDIRASentFltAcc_Cnt_M_u16	53398
ISDATDIRASentTimer_mS_M_u32	1142962176
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	6285
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	28212
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	32431
ISDYN2CMMMsgTimer_mS_M_u32	86091776
ISDYNAASChkSumInvalidCount_Cnt_M_u16	5901
ISDYNAASChkSumValidCount_Cnt_M_u16	3056
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	44355
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	828

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNAASMsgLenValidCount_Cnt_M_u16	35799
ISDYNAASMsgTimeValidCount_Cnt_M_u16	5901
ISDYNAASMsgTimer_mS_M_u32	2830272512
ISDYNABRChkSumInvalidCount_Cnt_M_u16	45622
ISDYNABRChkSumValidCount_Cnt_M_u16	15134
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	5276
ISDYNABRMsgCountValidCount_Cnt_M_u16	26303
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	32088
ISDYNABRMsgLenValidCount_Cnt_M_u16	53291
ISDYNABRMsgTimeValidCount_Cnt_M_u16	45295
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	741
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1367
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	28030
ISDYNCMM208MsgTimer_mS_M_u32	2264229888
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2815
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1473
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	16466
ISDYNCMM388MsgTimer_mS_M_u32	1893337088
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	47591
ISDYNVOLChkSumValidCount_Cnt_M_u16	43514
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	26046
ISDYNVOLMsgCountValidCount_Cnt_M_u16	32809
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	53536
ISDYNVOLMsgLenValidCount_Cnt_M_u16	37523
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	51024
ISDYNVOLMsgTimer_mS_M_u32	1226622976
IgnOnTimer_mS_M_u32	2073954304
IgnTimeOff_Sec_M_u32	1042952397
ManVehSpd_Kph_M_f32	524.705627
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	103
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	199
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3141597184
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	0
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	21616640
PrevISDATBSI412MsgDLCError_Cnt_M_u08	222
PrevISDATBSI412MsgRxTime_MSec_M_u32	3026012160
PrevISDATBSI432MsgDLCError_Cnt_M_u08	252
PrevISDATBSI432MsgRxTime_MSec_M_u32	1157343232
PrevISDATDIRAMsgTxTime_MSec_M_u32	2293319680
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	162
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1303713792
PrevISDYNAASMsgDLCError_Cnt_M_u08	148
PrevISDYNAASMsgRxTime_MSec_M_u32	3099248640
PrevISDYNABRMsgDLCError_Cnt_M_u08	142
PrevISDYNABRMsgRxTime_MSec_M_u32	1360398336
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	67
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3584542720
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	198
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1083090944
PrevISDYNVOLMsgDLCError_Cnt_M_u08	169
PrevISDYNVOLMsgRxTime_MSec_M_u32	2120370176
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	911554560
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	25.6110992
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	10586

Name	Input Value
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	44149
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	27723
VitesseVehicleBVRampValidCount_Cnt_M_u16	61990
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	19285
VitesseVehicleBVSigValidCount_Cnt_M_u16	3800
VitesseVehicleBV_Kph_M_f32	110.655502
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	16466
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	58573
VitesseVehiculeRoues_Kph_M_f32	529.875183
k_AASNTCEnableTimeout_mS_u16	33846
k_AASNodeAbsentDiag_Cnt_str.Threshold	24708
k_AASNodeAbsentDiag_Cnt_str.PStep	10329
k_AASNodeAbsentDiag_Cnt_str.NStep	12571
k_AASNodeAbsentTimeout_mS_u16	23679
k_AASNodeTimeout_mS_u16	22389
k_ABSNodeTimeout_mS_u16	30413
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	32671
k_ANGLEVOLANTSigValidThresh_Cnt_u16	56638
k_AngleVolantInvalidThresh_Cnt_u16	48213
k_AngleVolantValidThresh_Cnt_u16	25956
k_BSI552MsgTimeout_mS_u16	22180
k_BSINTCEnableTimeout_mS_u16	40844
k_BSINodeAbsentDiag_Cnt_str.Threshold	1140
k_BSINodeAbsentDiag_Cnt_str.PStep	1154
k_BSINodeAbsentDiag_Cnt_str.NStep	3424
k_BSINodeAbsentTimeout_mS_u16	15832
k_BSINodeTimeout_mS_u16	4930
k_BattOvHi_Volt_f32	31.5
k_BattOvLo_Volt_f32	27.0363998
k_BattUvHi_Volt_f32	19.1191998
k_BattUvLo_Volt_f32	30.6674004
k_CAVNTCEnableTimeout_mS_u16	24826
k_CAVNodeAbsentDiag_Cnt_str.Threshold	3620
k_CAVNodeAbsentDiag_Cnt_str.PStep	26391
k_CAVNodeAbsentDiag_Cnt_str.NStep	7448
k_CAVNodeAbsentTimeout_mS_u16	50055
k_CAVNodeTimeout_mS_u16	6661
k_CMM388MsgTimeout_mS_u16	20779
k_CMM388NTCEnableTimeout_mS_u16	57191
k_CMMNTCEnableTimeout_mS_u16	17074
k_CMMNodeAbsentDiag_Cnt_str.Threshold	59435
k_CMMNodeAbsentDiag_Cnt_str.PStep	4125
k_CMMNodeAbsentDiag_Cnt_str.NStep	17753
k_CMMNodeAbsentTimeout_mS_u16	6409
k_CONSANGLECPKMax_HwDeg_f32	46.5568008
k_CONSANGLECPKMin_HwDeg_f32	-627.774902
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	43858
k_CONSANGLECPKSigValidThresh_Cnt_u16	36813
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	15003
k_CPKVehicleSpeedValidThresh_Cnt_u16	24505
k_CityParkInputInvalidThresh_Cnt_u16	44508
k_CityParkInputValidThresh_Cnt_u16	47608
k_ComputerRazGCTSigValidThresh_Cnt_u16	62144
k_CptTemporelSigValidThresh_Cnt_u16	38295
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	26712
k_DMDFCTCPKSigValidThresh_Cnt_u16	64299
k_DMDFCTCPKValidCount_Cnt_u16	16891
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	32431
k_DMDRELAXECPKSigValidThresh_Cnt_u16	7130
k_DMDRelaxeConsistentThresh_Cnt_u16	63744
k_DateValidThresh_Cnt_u16	13745
k_DefaultVehSpd_Kph_f32	118.2006
k_DiagMuxOnAbsentTimeout_mS_u16	517
k_EMNodeTimeout_mS_u16	18526
k_ESPNTCEnableTimeout_mS_u16	12709
k_ESPNodeAbsentDiag_Cnt_str.Threshold	47445

Name	Input Value
k_ESPNodeAbsentDiag_Cnt_str.PStep	24880
k_ESPNodeAbsentDiag_Cnt_str.NStep	58700
k_ESPNodeAbsentTimeout_mS_u16	39825
k_EtatMTSigInvalidThresh_Cnt_u16	32813
k_EtatMTSigValidThresh_Cnt_u16	14136
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	6670
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	4413
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	7913
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	55183
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	51110
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	10218
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	40425
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	65288
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	11480
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	11283
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	14906
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	53014
k_ISDATDIRASentDiag_Cnt_str.Threshold	12314
k_ISDATDIRASentDiag_Cnt_str.PStep	25984
k_ISDATDIRASentDiag_Cnt_str.NStep	21340
k_ISDATDIRASentTimeout_mS_u16	1394
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	62339
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	5728
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	57841
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	7478
k_ISDYNAASChkSumValidThresh_Cnt_u16	47361
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	65436
k_ISDYNAASMsgCountValidThresh_Cnt_u16	37311
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	2554
k_ISDYNAASMsgLenValidThresh_Cnt_u16	47929
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	19910
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	13686
k_ISDYNABRChkSumValidThresh_Cnt_u16	713
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	55667
k_ISDYNABRMsgCountValidThresh_Cnt_u16	38774
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	29264
k_ISDYNABRMsgLenValidThresh_Cnt_u16	8879
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	58061
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	11550
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	52055
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	30796
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	24036
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	16039
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	28892
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	6449
k_ISDYNVOLChkSumValidThresh_Cnt_u16	2680
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	32484
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	28869
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	44139
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	63162
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	17863
k_IgnOnTimeout_mS_u16	49261
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	215.812393
k_PowerCutVehSpdLowThresh_Kph_f32	242.695206
k_PowerCutVehSpdLowTimeout_mS_u16	58850
k_VBattMaxAAS_Volt_f32	15.2903996
k_VBattMaxBSI_Volt_f32	0.634199977
k_VBattMaxCAV_Volt_f32	22.7383995
k_VBattMaxCMM388_Volt_f32	8.73880005
k_VBattMaxCMM_Volt_f32	11.2194004
k_VBattMaxESP_Volt_f32	29.7775002
k_VBattMinAAS_Volt_f32	26.4705009
k_VBattMinBSI_Volt_f32	29.7775002
k_VBattMinCAV_Volt_f32	28.7642002
k_VBattMinCMM388_Volt_f32	27.0067005
k_VBattMinCMM_Volt_f32	12.8523998
k_VBattMinESP_Volt_f32	1.21940005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	17245
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	26964
k_VitesseVehicleBVRampValidThresh_Cnt_u16	53438
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	54522
k_VitesseVehicleBVSigValidThresh_Cnt_u16	37473

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VitesseVehicleBVSpeedPassThresh_kph_f32	428.162689
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	42345
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	26052
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	193128448
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	45704
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3854158080
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	198
target_SrlComInput_Per1_Batt_Volt_f32.value	10.4589996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4249376768
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	144
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.530090451
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	80
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	759695360
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1044785152
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	4
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	345262080
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4164052992
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	824215552
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	123643904
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	155
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3270297600
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	62
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	129
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	147
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	161
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1703110656
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	76
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1442514944
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	377038848
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	188
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1548175360
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	88
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	129
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	211

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3770406912
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2306
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.616339922
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	975336
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	153.309692
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	59060

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	24708	24708	✔
AASNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3854158080	3854158080	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	47.1257095	47.1257095	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	1140	1140	✔
BSINodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	59435	59435	✔
CMMNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	45295	45295	✔
CONSANGLECPK_HwDeg_M_f32	-239.725494	-239.725494 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2	2	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3854158080	3854158080	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3854158080	3854158080	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3854158080	3854158080	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3854158080	3854158080	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3854158080	3854158080	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3854158080	3854158080	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3854158080	3854158080	✔
ESPNTCEnableTimer_mS_M_u32	3225921536	3225921536	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	41	41	✔
EffacDefaultDiagTimer_mS_M_u32[1]	46	46	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	56565	56565	✔
ElecIntTimer_mS_M_u32[1]	787880	787880	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3854158080	3854158080	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3854158080	3854158080	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	1	1	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1703110656	1703110656	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3854158080	3854158080	✔
IgnOnTimer_mS_M_u32	2073954304	2073954304	✔
IgnTimeOff_Sec_M_u32	1042952397	1042952397	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	80	80	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	759695360	759695360	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	153	153	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1044785152	1044785152	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	4	4	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	345262080	345262080	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	216	216	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4164052992	4164052992	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2293319680	2293319680	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	220	220	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	123643904	123643904	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	155	155	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3270297600	3270297600	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	142	142	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1703110656	1703110656	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	169	169	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1442514944	1442514944	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	377038848	377038848	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	188	188	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1548175360	1548175360	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3770406912	3770406912	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	25.6110992	25.6110992	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	110.655502	110.655502	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	529.875183	529.875183	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	47.1257095	47.1257095	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	45295	45295	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1042952397	1042952397	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-239.725494	-239.725494 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	118.2006	118.2006	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	4	ValidityNTCProcessing	4	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.191 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4013103872
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	1531
AASNodeAbsentTimer_mS_M_u32	1871891200
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	25042
ANGLEVOLANTSigValidCount_Cnt_M_u16	30537
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	2396
AngleVolantMsgTimer_mS_M_u32	4013103872
AngleVolantValidCount_Cnt_M_u16	64096
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	150.644135
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	77957888
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2931165952
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3580771072
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4198234880
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	60197
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2396044032
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	1986
CAVNodeAbsentTimer_mS_M_u32	3732007680
CDD_SrlComVehSpd_Kph_G_f32	378.269012
CMM388NTCEnableTimer_mS_M_u32	2505779968
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	872409856
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	14797
CMMNodeAbsentTimer_mS_M_u32	3979213568
CONSANGLECPKSigInvalidCount_Cnt_M_u16	49952
CONSANGLECPKSigValidCount_Cnt_M_u16	55848

Name	Input Value
CONSANGLECPK_Cnt_M_u16	45679
CONSANGLECPK_HwDeg_M_f32	-499.908691
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	45679
CPKVehicleSpeedMsgTimer_mS_M_u32	3726514944
CPKVehicleSpeedValidCount_Cnt_M_u16	27930
CityParkInputConsistentCount_Cnt_M_u16	10004
CityParkInputInvalidCount_Cnt_M_u16	57810
CityParkInputMsgTimer_mS_M_u32	759695360
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3376859904
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	175
ComputerRazGCTSigInvalidTimer_mS_M_u32	287075072
ComputerRazGCTSigValidCount_Cnt_M_u16	49037
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	49438
DMDFCTCPKSigValidCount_Cnt_M_u16	31005
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	23340
DMDRELAXECPKSigValidCount_Cnt_M_u16	40995
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	45953
DateInvalidTimer_mS_M_u32	2931165952
DiagMuxOnAbsentTimer_mS_M_u32	338156288
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4198234880
ESPNTCEnableTimer_mS_M_u32	2473052928
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	20592
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	3
EffacDefaultDiagTimer_mS_M_u32[1]	6
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	556
ElecIntTimer_mS_M_u32[1]	877878
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1242217216
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	54319
EtatMTSigValidCount_Cnt_M_u16	64514
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	19066
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	4354
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	4267
ISDAT4V2BSI552MsgTimer_mS_M_u32	3856792320
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	47760
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	49995
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	64514
ISDATBSI3F2MsgTimer_mS_M_u32	2228083456
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	49611
ISDATBSI412MsgLenValidCount_Cnt_M_u16	64630
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	54319
ISDATBSI412MsgTimer_mS_M_u32	3721992960
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	4481
ISDATBSI432MsgLenValidCount_Cnt_M_u16	18212
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	8503
ISDATDIRASentFltAcc_Cnt_M_u16	14651
ISDATDIRASentTimer_mS_M_u32	3726514944
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	29589
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	64096
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	33265
ISDYN2CMMMsgTimer_mS_M_u32	2899954432
ISDYNAASChkSumInvalidCount_Cnt_M_u16	64341
ISDYNAASChkSumValidCount_Cnt_M_u16	37996
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	14643
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	47433
ISDYNAASMsgLenValidCount_Cnt_M_u16	30520
ISDYNAASMsgTimeValidCount_Cnt_M_u16	64341
ISDYNAASMsgTimer_mS_M_u32	2644978432
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0
ISDYNABRChkSumValidCount_Cnt_M_u16	27066

Name	Input Value
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	65192
ISDYNABRMsgCountValidCount_Cnt_M_u16	32767
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	1395
ISDYNABRMsgLenValidCount_Cnt_M_u16	17595
ISDYNABRMsgTimeValidCount_Cnt_M_u16	45679
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	742
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1369
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	64514
ISDYNCMM208MsgTimer_mS_M_u32	643730176
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2819
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1475
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	31750
ISDYNCMM388MsgTimer_mS_M_u32	1127262976
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	19398
ISDYNVOLChkSumValidCount_Cnt_M_u16	45902
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	51396
ISDYNVOLMsgCountValidCount_Cnt_M_u16	4419
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	34845
ISDYNVOLMsgLenValidCount_Cnt_M_u16	64388
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	14797
ISDYNVOLMsgTimer_mS_M_u32	896035584
IgnOnTimer_mS_M_u32	853846784
IgnTimeOff_Sec_M_u32	2830770688
ManVehSpd_Kph_M_f32	257.725891
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	105
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	139
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3954957056
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	49
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3575724800
PrevISDATBSI412MsgDLCError_Cnt_M_u08	183
PrevISDATBSI412MsgRxTime_MSec_M_u32	2510744320
PrevISDATBSI432MsgDLCError_Cnt_M_u08	190
PrevISDATBSI432MsgRxTime_MSec_M_u32	3578514176
PrevISDATDIRAMsgTxTime_MSec_M_u32	1756031744
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	198
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2900327168
PrevISDYNAASMsgDLCError_Cnt_M_u08	253
PrevISDYNAASMsgRxTime_MSec_M_u32	3733875456
PrevISDYNABRMsgDLCError_Cnt_M_u08	226
PrevISDYNABRMsgRxTime_MSec_M_u32	2457643776
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	99
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2076666624
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	6
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4002597632
PrevISDYNVOLMsgDLCError_Cnt_M_u08	183
PrevISDYNVOLMsgRxTime_MSec_M_u32	2341989120
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	461314816
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	53.2686996
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	16111
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	3422
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VehSpdSync_Cnt_M_Igc	1
VehTimeValid_Cnt_M_Igc	1
VehicleSpeedValid_Cnt_M_Igc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	31260
VitesseVehicleBVRampValidCount_Cnt_M_u16	16459
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	56447
VitesseVehicleBVSigValidCount_Cnt_M_u16	35254
VitesseVehicleBV_Kph_M_f32	41.6988983
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	31750
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	26197
VitesseVehiculeRoues_Kph_M_f32	603.075928
k_AASNTCEnableTimeout_mS_u16	5274
k_AASNodeAbsentDiag_Cnt_str.Threshold	29221
k_AASNodeAbsentDiag_Cnt_str.PStep	23710
k_AASNodeAbsentDiag_Cnt_str.NStep	19599
k_AASNodeAbsentTimeout_mS_u16	7039
k_AASNodeTimeout_mS_u16	3166
k_ABSNodeTimeout_mS_u16	37271
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	3296
k_ANGLEVOLANTSigValidThresh_Cnt_u16	23491
k_AngleVolantInvalidThresh_Cnt_u16	55934
k_AngleVolantValidThresh_Cnt_u16	57810
k_BSI552MsgTimeout_mS_u16	11472
k_BSINTCEnableTimeout_mS_u16	41241
k_BSINodeAbsentDiag_Cnt_str.Threshold	1253
k_BSINodeAbsentDiag_Cnt_str.PStep	1260
k_BSINodeAbsentDiag_Cnt_str.NStep	4266
k_BSINodeAbsentTimeout_mS_u16	29428
k_BSINodeTimeout_mS_u16	8503
k_BattOvHi_Volt_f32	16.9067001
k_BattOvLo_Volt_f32	21.0238991
k_BattUvHi_Volt_f32	27.4783001
k_BattUvLo_Volt_f32	18.1924992
k_CAVNTCEnableTimeout_mS_u16	50960
k_CAVNodeAbsentDiag_Cnt_str.Threshold	55517
k_CAVNodeAbsentDiag_Cnt_str.PStep	35644
k_CAVNodeAbsentDiag_Cnt_str.NStep	21680
k_CAVNodeAbsentTimeout_mS_u16	25704
k_CAVNodeTimeout_mS_u16	9068
k_CMM388MsgTimeout_mS_u16	17659
k_CMM388NTCEnableTimeout_mS_u16	35399
k_CMMNTCEnableTimeout_mS_u16	54824
k_CMMNodeAbsentDiag_Cnt_str.Threshold	61198
k_CMMNodeAbsentDiag_Cnt_str.PStep	31282
k_CMMNodeAbsentDiag_Cnt_str.NStep	40373
k_CMMNodeAbsentTimeout_mS_u16	47521
k_CONSANGLECPKMax_HwDeg_f32	118.105797
k_CONSANGLECPKMin_HwDeg_f32	-613.567993
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	15110
k_CONSANGLECPKSigValidThresh_Cnt_u16	25941
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	31468
k_CPKVehicleSpeedValidThresh_Cnt_u16	44050
k_CityParkInputInvalidThresh_Cnt_u16	35432
k_CityParkInputValidThresh_Cnt_u16	10004
k_ComputerRazGCTSigValidThresh_Cnt_u16	32254
k_CptTemporelSigValidThresh_Cnt_u16	56633
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	17523
k_DMDFCTCPKSigValidThresh_Cnt_u16	50107
k_DMDFCTCPKValidCount_Cnt_u16	4237
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	33265
k_DMDRELAXECPKSigValidThresh_Cnt_u16	16944
k_DMDRelaxeConsistentThresh_Cnt_u16	49854
k_DateValidThresh_Cnt_u16	4267
k_DefaultVehSpd_Kph_f32	252.393494
k_DiagMuxOnAbsentTimeout_mS_u16	38701
k_EMNodeTimeout_mS_u16	15457
k_ESPNTCEnableTimeout_mS_u16	4622
k_ESPNodeAbsentDiag_Cnt_str.Threshold	4337
k_ESPNodeAbsentDiag_Cnt_str.PStep	20825
k_ESPNodeAbsentDiag_Cnt_str.NStep	5438
k_ESPNodeAbsentTimeout_mS_u16	21001
k_EtatMTSigInvalidThresh_Cnt_u16	38773
k_EtatMTSigValidThresh_Cnt_u16	35349

Name	Input Value
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	26771
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	10951
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	64577
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	52113
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	17164
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	22399
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	23042
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	40549
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	10549
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	53507
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	11854
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	25338
k_ISDATDIRASentDiag_Cnt_str.Threshold	53628
k_ISDATDIRASentDiag_Cnt_str.PStep	31362
k_ISDATDIRASentDiag_Cnt_str.NStep	51301
k_ISDATDIRASentTimeout_mS_u16	23462
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	59827
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	2396
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	12586
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	9306
k_ISDYNAASChkSumValidThresh_Cnt_u16	26810
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	15784
k_ISDYNAASMsgCountValidThresh_Cnt_u16	65279
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	28174
k_ISDYNAASMsgLenValidThresh_Cnt_u16	61714
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	10795
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	54553
k_ISDYNABRChkSumValidThresh_Cnt_u16	42209
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	10789
k_ISDYNABRMsgCountValidThresh_Cnt_u16	59356
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	14541
k_ISDYNABRMsgLenValidThresh_Cnt_u16	36720
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	8663
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	17315
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	24888
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	50649
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	41170
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	63049
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	40810
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	24490
k_ISDYNVOLChkSumValidThresh_Cnt_u16	37781
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	36561
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	20846
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	1915
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	20558
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	47209
k_IgnOnTimeout_mS_u16	23030
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	146.057999
k_PowerCutVehSpdLowThresh_Kph_f32	73.4095993
k_PowerCutVehSpdLowTimeout_mS_u16	40854
k_VBattMaxAAS_Volt_f32	25.4132996
k_VBattMaxBSI_Volt_f32	27.9386005
k_VBattMaxCAV_Volt_f32	14.5098
k_VBattMaxCMM388_Volt_f32	27.4403
k_VBattMaxCMM_Volt_f32	28.9895
k_VBattMaxESP_Volt_f32	9.50580025
k_VBattMinAAS_Volt_f32	19.6846008
k_VBattMinBSI_Volt_f32	9.50580025
k_VBattMinCAV_Volt_f32	26.3064003
k_VBattMinCMM388_Volt_f32	31.3855991
k_VBattMinCMM_Volt_f32	10.6521997
k_VBattMinESP_Volt_f32	2.98950005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	57893
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	14336
k_VitesseVehicleBVRampValidThresh_Cnt_u16	34756
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	12878
k_VitesseVehicleBVSigValidThresh_Cnt_u16	33241
k_VitesseVehicleBVSpeedPassThresh_kph_f32	569.147095
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	50882
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	56689
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2931165952

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	25029
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	282421248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	6
target_SrlComInput_Per1_Batt_Volt_f32.value	6.87230015
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4213553920
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	59
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0351573601
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1172744960
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	862735104
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	285338368
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	111643392
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1012738816
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3659713280
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	133720832
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	111
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	114
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	202
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	226
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	226
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1119128320
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	47
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	82
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	158
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	232
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1473096448
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	919816960
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3320376064
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	94
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	170
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	195
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2127248128
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	642
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.818900585
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	872397
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	46.8161011
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	61153

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	282421248	282421248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	282421248	282421248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	150.644135	150.644135	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	1253	1253	✔
BSINodeAbsentTimer_mS_M_u32	282421248	282421248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	282421248	282421248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	282421248	282421248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	282421248	282421248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3659713280	3659713280	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	45679	45679	✔
CONSANGLECPK_HwDeg_M_f32	-499.908691	-499.908691 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2	2	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	282421248	282421248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	282421248	282421248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	282421248	282421248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	282421248	282421248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	282421248	282421248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	282421248	282421248	✔
DiagOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DmdDelestDATimer_mS_M_u32	282421248	282421248	✔
ESPNTCEnableTimer_mS_M_u32	282421248	282421248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	4337	4337	✔
ESPNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	282421248	282421248	✔
EffacDefaultDiagTimer_mS_M_u32[1]	6	6	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	282421248	282421248	✔
ElecIntTimer_mS_M_u32[1]	877878	877878	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	282421248	282421248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	282421248	282421248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgTimer_mS_M_u32	282421248	282421248	✔
IgnOnTimer_mS_M_u32	853846784	853846784	✔
IgnTimeOff_Sec_M_u32	2830770688	2830770688	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1172744960	1172744960	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	105	105	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	862735104	862735104	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	233	233	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	285338368	285338368	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	110	110	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	111643392	111643392	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1756031744	1756031744	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	35	35	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3659713280	3659713280	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	133720832	133720832	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	226	226	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1119128320	1119128320	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1473096448	1473096448	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	251	251	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	919816960	919816960	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	77	77	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3320376064	3320376064	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2127248128	2127248128	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	53.2686996	53.2686996	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	41.6988983	41.6988983	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	603.075928	603.075928	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	150.644135	150.644135	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	45679	45679	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2830770688	2830770688	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-499.908691	-499.908691 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	252.393494	252.393494	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	13	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	13	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.192 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	942764544
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	46551
AASNodeAbsentTimer_mS_M_u32	299000320
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	7252
ANGLEVOLANTSigValidCount_Cnt_M_u16	62638
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	28596
AngleVolantMsgTimer_mS_M_u32	942764544
AngleVolantValidCount_Cnt_M_u16	45866
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	144.902618
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	228205056
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4050166272
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3657437696
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3533099520
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	35931
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1473810944
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	13570
CAVNodeAbsentTimer_mS_M_u32	2847212032
CDD_SrlComVehSpd_Kph_G_f32	360.012604
CMM388NTCEnableTimer_mS_M_u32	3120120320
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1628111360
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	5283
CMMNodeAbsentTimer_mS_M_u32	1103155712
CONSANGLECPKSigInvalidCount_Cnt_M_u16	41832
CONSANGLECPKSigValidCount_Cnt_M_u16	46866
CONSANGLECPK_Cnt_M_u16	2621
CONSANGLECPK_HwDeg_M_f32	-388.290894
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2621
CPKVehicleSpeedMsgTimer_mS_M_u32	3614470656
CPKVehicleSpeedValidCount_Cnt_M_u16	13250

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	64782
CityParkInputInvalidCount_Cnt_M_u16	38355
CityParkInputMsgTimer_mS_M_u32	1172744960
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3568722432
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	38331
ComputerRazGCTSigInvalidTimer_mS_M_u32	3686105600
ComputerRazGCTSigValidCount_Cnt_M_u16	22435
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	10223
DMDFCTCPKSigValidCount_Cnt_M_u16	14513
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	6214
DMDRELAXECPKSigValidCount_Cnt_M_u16	25120
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	38469
DateInvalidTimer_mS_M_u32	4050166272
DiagMuxOnAbsentTimer_mS_M_u32	2354262528
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3533099520
ESPNTCEnableTimer_mS_M_u32	978543104
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	39289
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	9
EffacDefaultDiagTimer_mS_M_u32[1]	81
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	2323
ElecIntTimer_mS_M_u32[1]	45465
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2385154560
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	40572
EtatMTSigValidCount_Cnt_M_u16	44994
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	62810
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	64132
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	10759
ISDAT4V2BSI552MsgTimer_mS_M_u32	665113088
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1753
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	5480
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	44994
ISDATBSI3F2MsgTimer_mS_M_u32	1382101504
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	60968
ISDATBSI412MsgLenValidCount_Cnt_M_u16	9958
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	40572
ISDATBSI412MsgTimer_mS_M_u32	2218750464
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	23943
ISDATBSI432MsgLenValidCount_Cnt_M_u16	34141
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	64675
ISDATDIRASentFltAcc_Cnt_M_u16	50327
ISDATDIRASentTimer_mS_M_u32	3614470656
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	57035
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	45866
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	61814
ISDYN2CMMMsgTimer_mS_M_u32	905798144
ISDYNAASChkSumInvalidCount_Cnt_M_u16	48585
ISDYNAASChkSumValidCount_Cnt_M_u16	35652
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	689
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	64621
ISDYNAASMsgLenValidCount_Cnt_M_u16	47968
ISDYNAASMsgTimeValidCount_Cnt_M_u16	48585
ISDYNAASMsgTimer_mS_M_u32	3507831296
ISDYNABRChkSumInvalidCount_Cnt_M_u16	65535
ISDYNABRChkSumValidCount_Cnt_M_u16	30940
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	49104
ISDYNABRMsgCountValidCount_Cnt_M_u16	54411
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	59503
ISDYNABRMsgLenValidCount_Cnt_M_u16	33625
ISDYNABRMsgTimeValidCount_Cnt_M_u16	2621

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	743
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1371
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	44994
ISDYNCMM208MsgTimer_mS_M_u32	3429835264
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2823
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1477
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	17976
ISDYNCMM388MsgTimer_mS_M_u32	3866673664
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	8566
ISDYNVOLChkSumValidCount_Cnt_M_u16	17312
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	10493
ISDYNVOLMsgCountValidCount_Cnt_M_u16	34879
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	58994
ISDYNVOLMsgLenValidCount_Cnt_M_u16	25853
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	5283
ISDYNVOLMsgTimer_mS_M_u32	2664530432
IgnOnTimer_mS_M_u32	3881615872
IgnTimeOff_Sec_M_u32	519284203
ManVehSpd_Kph_M_f32	585.118103
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	107
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	43
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1435972096
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	71
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1726419456
PrevISDATBSI412MsgDLCError_Cnt_M_u08	80
PrevISDATBSI412MsgRxTime_MSec_M_u32	2551579136
PrevISDATBSI432MsgDLCError_Cnt_M_u08	23
PrevISDATBSI432MsgRxTime_MSec_M_u32	78078464
PrevISDATDIRAMsgTxTime_MSec_M_u32	789185024
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	16
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2829865472
PrevISDYNAASMsgDLCError_Cnt_M_u08	70
PrevISDYNAASMsgRxTime_MSec_M_u32	3143598592
PrevISDYNABRMsgDLCError_Cnt_M_u08	33
PrevISDYNABRMsgRxTime_MSec_M_u32	680837632
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	189
PrevISDYNCMM208MsgRxTime_MSec_M_u32	129270272
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	82
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2496815616
PrevISDYNVOLMsgDLCError_Cnt_M_u08	51
PrevISDYNVOLMsgRxTime_MSec_M_u32	3124953600
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3813503488
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	396.652313
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	33659
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	4334
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	50676
VitesseVehicleBVRampValidCount_Cnt_M_u16	27687
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	41037

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	45415
VitesseVehicleBV_Kph_M_f32	357.01059
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	17976
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	10
VitesseVehiculeRoues_Kph_M_f32	435.511597
k_AASNTCEnableTimeout_mS_u16	20412
k_AASNodeAbsentDiag_Cnt_str.Threshold	12222
k_AASNodeAbsentDiag_Cnt_str.PStep	35436
k_AASNodeAbsentDiag_Cnt_str.NStep	31728
k_AASNodeAbsentTimeout_mS_u16	35789
k_AASNodeTimeout_mS_u16	5102
k_ABSNodeTimeout_mS_u16	55940
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	42858
k_ANGLEVOLANTSigValidThresh_Cnt_u16	33664
k_AngleVolantInvalidThresh_Cnt_u16	45903
k_AngleVolantValidThresh_Cnt_u16	38355
k_BSI552MsgTimeout_mS_u16	22681
k_BSINTCEnableTimeout_mS_u16	3775
k_BSINodeAbsentDiag_Cnt_str.Threshold	1366
k_BSINodeAbsentDiag_Cnt_str.PStep	1366
k_BSINodeAbsentDiag_Cnt_str.NStep	5108
k_BSINodeAbsentTimeout_mS_u16	37612
k_BSINodeTimeout_mS_u16	64675
k_BattOvHi_Volt_f32	14.0313997
k_BattOvLo_Volt_f32	2.40960002
k_BattUvHi_Volt_f32	2.43860006
k_BattUvLo_Volt_f32	19.2194004
k_CAVNTCEnableTimeout_mS_u16	24089
k_CAVNodeAbsentDiag_Cnt_str.Threshold	3278
k_CAVNodeAbsentDiag_Cnt_str.PStep	40457
k_CAVNodeAbsentDiag_Cnt_str.NStep	24390
k_CAVNodeAbsentTimeout_mS_u16	14096
k_CAVNodeTimeout_mS_u16	45700
k_CMM388MsgTimeout_mS_u16	63703
k_CMM388NTCEnableTimeout_mS_u16	22771
k_CMMNTCEnableTimeout_mS_u16	5137
k_CMMNodeAbsentDiag_Cnt_str.Threshold	64865
k_CMMNodeAbsentDiag_Cnt_str.PStep	13070
k_CMMNodeAbsentDiag_Cnt_str.NStep	24285
k_CMMNodeAbsentTimeout_mS_u16	13862
k_CONSANGLECPKMax_HwDeg_f32	779.938721
k_CONSANGLECPKMin_HwDeg_f32	-460.032806
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	2360
k_CONSANGLECPKSigValidThresh_Cnt_u16	778
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	32836
k_CPKVehicleSpeedValidThresh_Cnt_u16	2899
k_CityParkInputInvalidThresh_Cnt_u16	5647
k_CityParkInputValidThresh_Cnt_u16	64782
k_ComputerRazGCTSigValidThresh_Cnt_u16	62607
k_CptTemporelSigValidThresh_Cnt_u16	65438
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	11119
k_DMDFCTCPKSigValidThresh_Cnt_u16	1625
k_DMDFCTCPKValidCount_Cnt_u16	48163
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	61814
k_DMDRELAXECPKSigValidThresh_Cnt_u16	59768
k_DMDRelaxeConsistentThresh_Cnt_u16	8142
k_DateValidThresh_Cnt_u16	10759
k_DefaultVehSpd_Kph_f32	95.1116028
k_DiagMuxOnAbsentTimeout_mS_u16	54275
k_EMNodeTimeout_mS_u16	31653
k_ESPNTCEnableTimeout_mS_u16	17950
k_ESPNodeAbsentDiag_Cnt_str.Threshold	22426
k_ESPNodeAbsentDiag_Cnt_str.PStep	52857
k_ESPNodeAbsentDiag_Cnt_str.NStep	29219
k_ESPNodeAbsentTimeout_mS_u16	3310
k_EtatMTSigInvalidThresh_Cnt_u16	25320
k_EtatMTSigValidThresh_Cnt_u16	17355
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	4943
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	54645
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	29063
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	6102
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	55845
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	64780

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	51204
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	50074
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	58987
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	65153
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	20320
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	55194
k_ISDATDIRASentDiag_Cnt_str.Threshold	1905
k_ISDATDIRASentDiag_Cnt_str.PStep	4278
k_ISDATDIRASentDiag_Cnt_str.NStep	49319
k_ISDATDIRASentTimeout_mS_u16	6741
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	26479
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	28596
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	22730
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	36921
k_ISDYNAASChkSumValidThresh_Cnt_u16	31708
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	720
k_ISDYNAASMsgCountValidThresh_Cnt_u16	22411
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	33565
k_ISDYNAASMsgLenValidThresh_Cnt_u16	13778
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	47176
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	37245
k_ISDYNABRChkSumValidThresh_Cnt_u16	31463
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	53083
k_ISDYNABRMsgCountValidThresh_Cnt_u16	44789
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	6051
k_ISDYNABRMsgLenValidThresh_Cnt_u16	56441
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	44292
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	17759
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	993
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	37757
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	24404
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	30638
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	48395
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	20619
k_ISDYNVOLChkSumValidThresh_Cnt_u16	40329
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	41558
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	37312
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	13464
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	58078
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	43725
k_IgnOnTimeout_mS_u16	37287
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	110.617996
k_PowerCutVehSpdLowThresh_Kph_f32	48.5633011
k_PowerCutVehSpdLowTimeout_mS_u16	40648
k_VBattMaxAAS_Volt_f32	21.5086994
k_VBattMaxBSI_Volt_f32	6.26289988
k_VBattMaxCAV_Volt_f32	19.8978004
k_VBattMaxCMM388_Volt_f32	2.31139994
k_VBattMaxCMM_Volt_f32	3.69009995
k_VBattMaxESP_Volt_f32	19.5701008
k_VBattMinAAS_Volt_f32	21.2602005
k_VBattMinBSI_Volt_f32	19.5701008
k_VBattMinCAV_Volt_f32	26.8861008
k_VBattMinCMM388_Volt_f32	12.2284002
k_VBattMinCMM_Volt_f32	0.0175000001
k_VBattMinESP_Volt_f32	3.69009995
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	50713
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	27975
k_VitesseVehicleBVRampValidThresh_Cnt_u16	60413
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	50848
k_VitesseVehicleBVSigValidThresh_Cnt_u16	16575
k_VitesseVehicleBVSpeedPassThresh_kph_f32	241.816803
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	63490
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	44213
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4050166272
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	57136
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	146705152
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	82
target_SrlComInput_Per1_Batt_Volt_f32.value	6.79460001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2799276544
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	253
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.358024985
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	911655424
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	147
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	205906432
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1376059904
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	65
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2408849920
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1291010560
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	304243200
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1730249216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	36
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	100
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	170
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	212
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1332552192
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	60
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	126
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1554104832
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1578164736
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2404385280
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	72
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2447970816
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1340
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.330557376
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	815273
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	244.593796
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	48037

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	146705152	146705152	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	146705152	146705152	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	144.902618	144.902618	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	1366	1366	✔
BSINodeAbsentTimer_mS_M_u32	146705152	146705152	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	146705152	146705152	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	146705152	146705152	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	146705152	146705152	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	304243200	304243200	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	2621	2621	✔
CONSANGLECPK_HwDeg_M_f32	-388.290894	-388.290894 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2	2	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	146705152	146705152	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	146705152	146705152	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	146705152	146705152	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	146705152	146705152	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	146705152	146705152	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	146705152	146705152	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	146705152	146705152	✔
ESPNTCEnableTimer_mS_M_u32	978543104	978543104	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	22426	22426	✔
ESPNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	146705152	146705152	✔
EffacDefaultDiagTimer_mS_M_u32[1]	81	81	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	146705152	146705152	✔
ElecIntTimer_mS_M_u32[1]	45465	45465	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	146705152	146705152	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	146705152	146705152	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	1	1	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1332552192	1332552192	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	146705152	146705152	✔
IgnOnTimer_mS_M_u32	3881615872	3881615872	✔
IgnTimeOff_Sec_M_u32	519284203	519284203	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	911655424	911655424	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	147	147	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	205906432	205906432	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	208	208	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1376059904	1376059904	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	65	65	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2408849920	2408849920	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	789185024	789185024	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	222	222	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	304243200	304243200	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	26	26	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1730249216	1730249216	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1332552192	1332552192	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1554104832	1554104832	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	55	55	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1578164736	1578164736	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	0	0	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2404385280	2404385280	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2447970816	2447970816	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	396.652313	396.652313	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	357.01059	357.01059	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	435.511597	435.511597	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	144.902618	144.902618	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	2621	2621	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	519284203	519284203	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-388.290894	-388.290894 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	95.1116028	95.1116028	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	4	ValidityNTCProcessing	4	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.193 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3880938752
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	10334
AASNodeAbsentTimer_mS_M_u32	1244634368
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	34537
ANGLEVOLANTSigValidCount_Cnt_M_u16	45978
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	44743
AngleVolantMsgTimer_mS_M_u32	3880938752
AngleVolantValidCount_Cnt_M_u16	41192
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	304.634033
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	634936576
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3563904256
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	73829632
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3852619008
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	4820
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2363297024
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	7519
CAVNodeAbsentTimer_mS_M_u32	3574054144
CDD_SrlComVehSpd_Kph_G_f32	99.7113037
CMM388NTCEnableTimer_mS_M_u32	87751936
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2265300224
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	7484
CMMNodeAbsentTimer_mS_M_u32	3223604480
CONSANGLECPKSigInvalidCount_Cnt_M_u16	61614
CONSANGLECPKSigValidCount_Cnt_M_u16	43886
CONSANGLECPK_Cnt_M_u16	7661
CONSANGLECPK_HwDeg_M_f32	15.3388996
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	7661
CPKVehicleSpeedMsgTimer_mS_M_u32	3314904320
CPKVehicleSpeedValidCount_Cnt_M_u16	46279

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	21308
CityParkInputInvalidCount_Cnt_M_u16	11756
CityParkInputMsgTimer_mS_M_u32	911655424
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2441321728
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	6322
ComputerRazGCTSigInvalidTimer_mS_M_u32	3775282432
ComputerRazGCTSigValidCount_Cnt_M_u16	55165
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	59288
DMDFCTCPKSigValidCount_Cnt_M_u16	2833
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56083
DMDRELAXECPKSigValidCount_Cnt_M_u16	45892
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	52247
DateInvalidTimer_mS_M_u32	3563904256
DiagMuxOnAbsentTimer_mS_M_u32	2716675328
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3852619008
ESPNTCEnableTimer_mS_M_u32	346856704
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	13433
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	66
EffacDefaultDiagTimer_mS_M_u32[1]	163190528
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	16
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2984709376
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	29873
EtatMTSigValidCount_Cnt_M_u16	42653
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	17112
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	10520
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	3855
ISDAT4V2BSI552MsgTimer_mS_M_u32	2658684160
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	59673
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	17197
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	42653
ISDATBSI3F2MsgTimer_mS_M_u32	130231552
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	15406
ISDATBSI412MsgLenValidCount_Cnt_M_u16	55219
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	29873
ISDATBSI412MsgTimer_mS_M_u32	3139988736
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	53904
ISDATBSI432MsgLenValidCount_Cnt_M_u16	205
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	35452
ISDATDIRASentFltAcc_Cnt_M_u16	672
ISDATDIRASentTimer_mS_M_u32	3314904320
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	22595
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	41192
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	26371
ISDYN2CMMMsgTimer_mS_M_u32	1236180224
ISDYNAASChkSumInvalidCount_Cnt_M_u16	22664
ISDYNAASChkSumValidCount_Cnt_M_u16	9689
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	36435
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	13086
ISDYNAASMsgLenValidCount_Cnt_M_u16	3078
ISDYNAASMsgTimeValidCount_Cnt_M_u16	22664
ISDYNAASMsgTimer_mS_M_u32	803667200
ISDYNABRChkSumInvalidCount_Cnt_M_u16	65534
ISDYNABRChkSumValidCount_Cnt_M_u16	5265
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	11891
ISDYNABRMsgCountValidCount_Cnt_M_u16	9732
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	64921
ISDYNABRMsgLenValidCount_Cnt_M_u16	8857
ISDYNABRMsgTimeValidCount_Cnt_M_u16	7661

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	141
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	167
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	42653
ISDYNCMM208MsgTimer_mS_M_u32	2103008512
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	415
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	273
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	40894
ISDYNCMM388MsgTimer_mS_M_u32	3720117504
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	11908
ISDYNVOLChkSumValidCount_Cnt_M_u16	48580
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	40046
ISDYNVOLMsgCountValidCount_Cnt_M_u16	54375
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	29070
ISDYNVOLMsgLenValidCount_Cnt_M_u16	27567
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	7484
ISDYNVOLMsgTimer_mS_M_u32	129121536
IgnOnTimer_mS_M_u32	1796242688
IgnTimeOff_Sec_M_u32	2080187495
ManVehSpd_Kph_M_f32	490.306305
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	77
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	178
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1445014784
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	54
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3115420928
PrevISDATBSI412MsgDLCError_Cnt_M_u08	74
PrevISDATBSI412MsgRxTime_MSec_M_u32	3454319872
PrevISDATBSI432MsgDLCError_Cnt_M_u08	98
PrevISDATBSI432MsgRxTime_MSec_M_u32	95460608
PrevISDATDIRAMsgTxTime_MSec_M_u32	3641228544
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	63
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2573323520
PrevISDYNAASMsgDLCError_Cnt_M_u08	12
PrevISDYNAASMsgRxTime_MSec_M_u32	1778924800
PrevISDYNABRMsgDLCError_Cnt_M_u08	230
PrevISDYNABRMsgRxTime_MSec_M_u32	2271771904
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	177
PrevISDYNCMM208MsgRxTime_MSec_M_u32	420035840
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	121
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3241123072
PrevISDYNVOLMsgDLCError_Cnt_M_u08	249
PrevISDYNVOLMsgRxTime_MSec_M_u32	1532869888
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1442737408
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	179.515396
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	22004
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	50012
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	45705
VitesseVehicleBVRampValidCount_Cnt_M_u16	54705
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	7934

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	41327
VitesseVehicleBV_Kph_M_f32	521.49353
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	40894
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	2055
VitesseVehiculeRoues_Kph_M_f32	248.815094
k_AASNTCEnableTimeout_mS_u16	2416
k_AASNodeAbsentDiag_Cnt_str.Threshold	4467
k_AASNodeAbsentDiag_Cnt_str.PStep	60116
k_AASNodeAbsentDiag_Cnt_str.NStep	906
k_AASNodeAbsentTimeout_mS_u16	25343
k_AASNodeTimeout_mS_u16	47708
k_ABSNodeTimeout_mS_u16	25561
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	16615
k_ANGLEVOLANTSigValidThresh_Cnt_u16	21092
k_AngleVolantInvalidThresh_Cnt_u16	48887
k_AngleVolantValidThresh_Cnt_u16	11756
k_BSI552MsgTimeout_mS_u16	64090
k_BSINTCEnableTimeout_mS_u16	40680
k_BSINodeAbsentDiag_Cnt_str.Threshold	3052
k_BSINodeAbsentDiag_Cnt_str.PStep	44243
k_BSINodeAbsentDiag_Cnt_str.NStep	1848
k_BSINodeAbsentTimeout_mS_u16	9503
k_BSINodeTimeout_mS_u16	35452
k_BattOvHi_Volt_f32	11.6260996
k_BattOvLo_Volt_f32	11.8016005
k_BattUvHi_Volt_f32	18.5384007
k_BattUvLo_Volt_f32	1.42589998
k_CAVNTCEnableTimeout_mS_u16	27930
k_CAVNodeAbsentDiag_Cnt_str.Threshold	41800
k_CAVNodeAbsentDiag_Cnt_str.PStep	20653
k_CAVNodeAbsentDiag_Cnt_str.NStep	46182
k_CAVNodeAbsentTimeout_mS_u16	53045
k_CAVNodeTimeout_mS_u16	13146
k_CMM388MsgTimeout_mS_u16	24414
k_CMM388NTCEnableTimeout_mS_u16	44810
k_CMMNTCEnableTimeout_mS_u16	41329
k_CMMNodeAbsentDiag_Cnt_str.Threshold	10365
k_CMMNodeAbsentDiag_Cnt_str.PStep	62446
k_CMMNodeAbsentDiag_Cnt_str.NStep	23219
k_CMMNodeAbsentTimeout_mS_u16	54707
k_CONSANGLECPKMax_HwDeg_f32	216.437698
k_CONSANGLECPKMin_HwDeg_f32	-581.668091
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	22206
k_CONSANGLECPKSigValidThresh_Cnt_u16	65287
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	19802
k_CPKVehicleSpeedValidThresh_Cnt_u16	20653
k_CityParkInputInvalidThresh_Cnt_u16	16183
k_CityParkInputValidThresh_Cnt_u16	21308
k_ComputerRazGCTSigValidThresh_Cnt_u16	30711
k_CptTemporelSigValidThresh_Cnt_u16	56459
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	13465
k_DMDFCTCPKSigValidThresh_Cnt_u16	39321
k_DMDFCTCPKValidCount_Cnt_u16	41852
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	26371
k_DMDRELAXECPKSigValidThresh_Cnt_u16	54460
k_DMDRelaxeConsistentThresh_Cnt_u16	2490
k_DateValidThresh_Cnt_u16	3855
k_DefaultVehSpd_Kph_f32	135.066605
k_DiagMuxOnAbsentTimeout_mS_u16	22683
k_EMNodeTimeout_mS_u16	39927
k_ESPNTCEnableTimeout_mS_u16	23051
k_ESPNodeAbsentDiag_Cnt_str.Threshold	17978
k_ESPNodeAbsentDiag_Cnt_str.PStep	37115
k_ESPNodeAbsentDiag_Cnt_str.NStep	784
k_ESPNodeAbsentTimeout_mS_u16	29019
k_EtatMTSigInvalidThresh_Cnt_u16	64684
k_EtatMTSigValidThresh_Cnt_u16	12228
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	32825
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	8070
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	6609
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	59938
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	10486
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	40834

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	50969
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	31254
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	51172
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	20769
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	9286
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	6359
k_ISDATDIRASentDiag_Cnt_str.Threshold	6549
k_ISDATDIRASentDiag_Cnt_str.PStep	63930
k_ISDATDIRASentDiag_Cnt_str.NStep	24627
k_ISDATDIRASentTimeout_mS_u16	51813
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	64856
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	44743
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	53767
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	63673
k_ISDYNAASChkSumValidThresh_Cnt_u16	2961
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	25971
k_ISDYNAASMsgCountValidThresh_Cnt_u16	40196
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	45069
k_ISDYNAASMsgLenValidThresh_Cnt_u16	58544
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	54284
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	47727
k_ISDYNABRChkSumValidThresh_Cnt_u16	62447
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	18900
k_ISDYNABRMsgCountValidThresh_Cnt_u16	24773
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	5180
k_ISDYNABRMsgLenValidThresh_Cnt_u16	27513
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	25240
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	41032
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7939
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	14255
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	48617
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	10906
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	38980
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	24837
k_ISDYNVOLChkSumValidThresh_Cnt_u16	49098
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	52706
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	23013
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	8797
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	32073
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	9405
k_IgnOnTimeout_mS_u16	3505
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	231.047607
k_PowerCutVehSpdLowThresh_Kph_f32	233.211594
k_PowerCutVehSpdLowTimeout_mS_u16	19532
k_VBattMaxAAS_Volt_f32	26.0177002
k_VBattMaxBSI_Volt_f32	28.7651005
k_VBattMaxCAV_Volt_f32	1.81449997
k_VBattMaxCMM388_Volt_f32	23.9582005
k_VBattMaxCMM_Volt_f32	1.74319994
k_VBattMaxESP_Volt_f32	15.8170996
k_VBattMinAAS_Volt_f32	13.0670004
k_VBattMinBSI_Volt_f32	15.8170996
k_VBattMinCAV_Volt_f32	18.7157001
k_VBattMinCMM388_Volt_f32	27.9486008
k_VBattMinCMM_Volt_f32	23.8146992
k_VBattMinESP_Volt_f32	1.74319994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	2394
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	6543
k_VitesseVehicleBVRampValidThresh_Cnt_u16	21358
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	13508
k_VitesseVehicleBVSigValidThresh_Cnt_u16	35881
k_VitesseVehicleBVSpeedPassThresh_kph_f32	403.663208
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	54367
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	52231
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3563904256
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65036
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	163190528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	121
target_SrlComInput_Per1_Batt_Volt_f32.value	13.5414
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3822718208
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	153
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.627984166
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3861019904
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2295667968
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	471317760
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	56
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	132799744
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3024944384
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2302647552
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4005707008
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	102
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	103
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	151
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	229
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	230
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1818189056
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	114
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	185
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	220
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1598127360
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2138316032
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1345764608
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	119
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3232468224
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3093
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.964761078
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	713410
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	64.3701019
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	54646

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	163190528	163190528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	44745	44745	✔
AngleVolantMsgTimer_mS_M_u32	163190528	163190528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	304.634033	304.634033	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	3052	3052	✔
BSINodeAbsentTimer_mS_M_u32	163190528	163190528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2302647552	2302647552	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	7661	7661	✔
CONSANGLECPK_HwDeg_M_f32	15.3388996	15.3388996 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	7663	7663	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	163190528	163190528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	21308	21308	✔
CityParkInputInvalidCount_Cnt_M_u16	11758	11758	✔
CityParkInputMsgTimer_mS_M_u32	163190528	163190528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	163190528	163190528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	163190528	163190528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	163190528	163190528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	163190528	163190528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	163190528	163190528	✔
ESPNTCEnableTimer_mS_M_u32	346856704	346856704	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	17978	17978	✔
ESPNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	66	66	✔
EffacDefaultDiagTimer_mS_M_u32[1]	163190528	163190528	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	163190528	163190528	✔
ElecIntTimer_mS_M_u32[1]	16	16	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	163190528	163190528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	163190528	163190528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	65534	65534	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	11892	11892	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1818189056	1818189056	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	163190528	163190528	✔
IgnOnTimer_mS_M_u32	1796242688	1796242688	✔
IgnTimeOff_Sec_M_u32	2080187495	2080187495	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	166	166	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3861019904	3861019904	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	119	119	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2295667968	2295667968	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	133	133	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	471317760	471317760	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	56	56	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	132799744	132799744	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3641228544	3641228544	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2302647552	2302647552	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	59	59	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4005707008	4005707008	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	230	230	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1818189056	1818189056	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	8	8	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1598127360	1598127360	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	119	119	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2138316032	2138316032	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1345764608	1345764608	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3232468224	3232468224	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	179.515396	179.515396	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	521.49353	521.49353	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	248.815094	248.815094	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	304.634033	304.634033	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	7661	7661	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2080187495	2080187495	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	15.3388996	15.3388996 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	135.066605	135.066605	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0132	0x0132	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	3	ValidityNTCProcessing	3	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.194 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4013103872
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	1531
AASNodeAbsentTimer_mS_M_u32	1871891200
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	25042
ANGLEVOLANTSigValidCount_Cnt_M_u16	30537
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	2396
AngleVolantMsgTimer_mS_M_u32	4013103872
AngleVolantValidCount_Cnt_M_u16	64096
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	618.090576
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	77957888
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2931165952
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3580771072
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4198234880
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	60197
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2396044032
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	1986
CAVNodeAbsentTimer_mS_M_u32	3732007680
CDD_SrlComVehSpd_Kph_G_f32	378.269012
CMM388NTCEnableTimer_mS_M_u32	2505779968
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	872409856
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	14797
CMMNodeAbsentTimer_mS_M_u32	3979213568
CONSANGLECPKSigInvalidCount_Cnt_M_u16	49952
CONSANGLECPKSigValidCount_Cnt_M_u16	55848
CONSANGLECPK_Cnt_M_u16	45679
CONSANGLECPK_HwDeg_M_f32	-499.908691
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	45679

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CPKVehicleSpeedMsgTimer_mS_M_u32	3726514944
CPKVehicleSpeedValidCount_Cnt_M_u16	27930
CityParkInputConsistentCount_Cnt_M_u16	10004
CityParkInputInvalidCount_Cnt_M_u16	57810
CityParkInputMsgTimer_mS_M_u32	759695360
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3376859904
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	175
ComputerRazGCTSigInvalidTimer_mS_M_u32	287075072
ComputerRazGCTSigValidCount_Cnt_M_u16	49037
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	49438
DMDFCTCPKSigValidCount_Cnt_M_u16	31005
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	23340
DMDRELAXECPKSigValidCount_Cnt_M_u16	40995
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	45953
DateInvalidTimer_mS_M_u32	2931165952
DiagMuxOnAbsentTimer_mS_M_u32	338156288
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4198234880
ESPNTCEnableTimer_mS_M_u32	2473052928
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	20592
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	3
EffacDefaultDiagTimer_mS_M_u32[1]	6
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	556
ElecIntTimer_mS_M_u32[1]	877878
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1242217216
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	54319
EtatMTSigValidCount_Cnt_M_u16	64514
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	19066
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	4354
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	4267
ISDAT4V2BSI552MsgTimer_mS_M_u32	3856792320
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	47760
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	49995
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	64514
ISDATBSI3F2MsgTimer_mS_M_u32	2228083456
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	49611
ISDATBSI412MsgLenValidCount_Cnt_M_u16	64630
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	54319
ISDATBSI412MsgTimer_mS_M_u32	3721992960
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	4481
ISDATBSI432MsgLenValidCount_Cnt_M_u16	18212
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	8503
ISDATDIRASentFltAcc_Cnt_M_u16	14651
ISDATDIRASentTimer_mS_M_u32	3726514944
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	29589
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	64096
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	33265
ISDYN2CMMMsgTimer_mS_M_u32	2899954432
ISDYNAASChkSumInvalidCount_Cnt_M_u16	64341
ISDYNAASChkSumValidCount_Cnt_M_u16	37996
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	14643
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	47433
ISDYNAASMsgLenValidCount_Cnt_M_u16	30520
ISDYNAASMsgTimeValidCount_Cnt_M_u16	64341
ISDYNAASMsgTimer_mS_M_u32	2644978432
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0
ISDYNABRChkSumValidCount_Cnt_M_u16	27066
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	65192
ISDYNABRMsgCountValidCount_Cnt_M_u16	32767
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	1395

Name	Input Value
ISDYNABRMsgLenValidCount_Cnt_M_u16	17595
ISDYNABRMsgTimeValidCount_Cnt_M_u16	45679
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	742
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1369
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	64514
ISDYNCMM208MsgTimer_mS_M_u32	643730176
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2819
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1475
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	31750
ISDYNCMM388MsgTimer_mS_M_u32	1127262976
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	19398
ISDYNVOLChkSumValidCount_Cnt_M_u16	45902
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	51396
ISDYNVOLMsgCountValidCount_Cnt_M_u16	4419
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	34845
ISDYNVOLMsgLenValidCount_Cnt_M_u16	64388
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	14797
ISDYNVOLMsgTimer_mS_M_u32	896035584
IgnOnTimer_mS_M_u32	853846784
IgnTimeOff_Sec_M_u32	2830770688
ManVehSpd_Kph_M_f32	257.725891
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	105
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	139
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3954957056
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	49
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3575724800
PrevISDATBSI412MsgDLCError_Cnt_M_u08	183
PrevISDATBSI412MsgRxTime_MSec_M_u32	2510744320
PrevISDATBSI432MsgDLCError_Cnt_M_u08	190
PrevISDATBSI432MsgRxTime_MSec_M_u32	3578514176
PrevISDATDIRAMsgTxTime_MSec_M_u32	1756031744
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	198
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2900327168
PrevISDYNAASMsgDLCError_Cnt_M_u08	253
PrevISDYNAASMsgRxTime_MSec_M_u32	3733875456
PrevISDYNABRMsgDLCError_Cnt_M_u08	226
PrevISDYNABRMsgRxTime_MSec_M_u32	2457643776
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	99
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2076666624
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	6
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4002597632
PrevISDYNVOLMsgDLCError_Cnt_M_u08	183
PrevISDYNVOLMsgRxTime_MSec_M_u32	2341989120
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	461314816
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	53.2686996
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	16111
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	3422
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	31260

Name	Input Value
VitesseVehicleBVRampValidCount_Cnt_M_u16	16459
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	56447
VitesseVehicleBVSigValidCount_Cnt_M_u16	35254
VitesseVehicleBV_Kph_M_f32	41.6988983
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	31750
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	26197
VitesseVehiculeRoues_Kph_M_f32	603.075928
k_AASNTCEnableTimeout_mS_u16	5274
k_AASNodeAbsentDiag_Cnt_str.Threshold	29221
k_AASNodeAbsentDiag_Cnt_str.PStep	23710
k_AASNodeAbsentDiag_Cnt_str.NStep	19599
k_AASNodeAbsentTimeout_mS_u16	7039
k_AASNodeTimeout_mS_u16	3166
k_ABSNodeTimeout_mS_u16	37271
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	3296
k_ANGLEVOLANTSigValidThresh_Cnt_u16	23491
k_AngleVolantInvalidThresh_Cnt_u16	55934
k_AngleVolantValidThresh_Cnt_u16	57810
k_BSI552MsgTimeout_mS_u16	11472
k_BSINTCEnableTimeout_mS_u16	41241
k_BSINodeAbsentDiag_Cnt_str.Threshold	1253
k_BSINodeAbsentDiag_Cnt_str.PStep	1260
k_BSINodeAbsentDiag_Cnt_str.NStep	4266
k_BSINodeAbsentTimeout_mS_u16	29428
k_BSINodeTimeout_mS_u16	8503
k_BattOvHi_Volt_f32	16.9067001
k_BattOvLo_Volt_f32	21.0238991
k_BattUvHi_Volt_f32	27.4783001
k_BattUvLo_Volt_f32	18.1924992
k_CAVNTCEnableTimeout_mS_u16	50960
k_CAVNodeAbsentDiag_Cnt_str.Threshold	55517
k_CAVNodeAbsentDiag_Cnt_str.PStep	35644
k_CAVNodeAbsentDiag_Cnt_str.NStep	21680
k_CAVNodeAbsentTimeout_mS_u16	25704
k_CAVNodeTimeout_mS_u16	9068
k_CMM388MsgTimeout_mS_u16	17659
k_CMM388NTCEnableTimeout_mS_u16	35399
k_CMMNTCEnableTimeout_mS_u16	54824
k_CMMNodeAbsentDiag_Cnt_str.Threshold	61198
k_CMMNodeAbsentDiag_Cnt_str.PStep	31282
k_CMMNodeAbsentDiag_Cnt_str.NStep	40373
k_CMMNodeAbsentTimeout_mS_u16	47521
k_CONSANGLECPKMax_HwDeg_f32	118.105797
k_CONSANGLECPKMin_HwDeg_f32	-613.567993
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	15110
k_CONSANGLECPKSigValidThresh_Cnt_u16	25941
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	31468
k_CPKVehicleSpeedValidThresh_Cnt_u16	44050
k_CityParkInputInvalidThresh_Cnt_u16	35432
k_CityParkInputValidThresh_Cnt_u16	10004
k_ComputerRazGCTSigValidThresh_Cnt_u16	32254
k_CptTemporelSigValidThresh_Cnt_u16	56633
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	17523
k_DMDFCTCPKSigValidThresh_Cnt_u16	50107
k_DMDFCTCPKValidCount_Cnt_u16	4237
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	33265
k_DMDRELAXECPKSigValidThresh_Cnt_u16	16944
k_DMDRelaxeConsistentThresh_Cnt_u16	49854
k_DateValidThresh_Cnt_u16	4267
k_DefaultVehSpd_Kph_f32	252.393494
k_DiagMuxOnAbsentTimeout_mS_u16	38701
k_EMNodeTimeout_mS_u16	15457
k_ESPNTCEnableTimeout_mS_u16	4622
k_ESPNodeAbsentDiag_Cnt_str.Threshold	4337
k_ESPNodeAbsentDiag_Cnt_str.PStep	20825
k_ESPNodeAbsentDiag_Cnt_str.NStep	5438
k_ESPNodeAbsentTimeout_mS_u16	21001
k_EtatMTSigInvalidThresh_Cnt_u16	38773
k_EtatMTSigValidThresh_Cnt_u16	35349
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	26771
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	10951
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	64577
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	52113

Name	Input Value
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	17164
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	22399
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	23042
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	40549
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	10549
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	53507
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	11854
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	25338
k_ISDATDIRASentDiag_Cnt_str.Threshold	53628
k_ISDATDIRASentDiag_Cnt_str.PStep	31362
k_ISDATDIRASentDiag_Cnt_str.NStep	51301
k_ISDATDIRASentTimeout_mS_u16	23462
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	59827
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	2396
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	12586
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	9306
k_ISDYNAASChkSumValidThresh_Cnt_u16	26810
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	15784
k_ISDYNAASMsgCountValidThresh_Cnt_u16	65279
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	28174
k_ISDYNAASMsgLenValidThresh_Cnt_u16	61714
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	10795
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	54553
k_ISDYNABRChkSumValidThresh_Cnt_u16	42209
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	10789
k_ISDYNABRMsgCountValidThresh_Cnt_u16	59356
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	14541
k_ISDYNABRMsgLenValidThresh_Cnt_u16	36720
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	8663
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	17315
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	24888
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	50649
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	41170
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	63049
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	40810
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	24490
k_ISDYNVOLChkSumValidThresh_Cnt_u16	37781
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	36561
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	20846
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	1915
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	20558
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	47209
k_IgnOnTimeout_mS_u16	23030
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	146.057999
k_PowerCutVehSpdLowThresh_Kph_f32	73.4095993
k_PowerCutVehSpdLowTimeout_mS_u16	40854
k_VBattMaxAAS_Volt_f32	25.4132996
k_VBattMaxBSI_Volt_f32	27.9386005
k_VBattMaxCAV_Volt_f32	14.5098
k_VBattMaxCMM388_Volt_f32	27.4403
k_VBattMaxCMM_Volt_f32	28.9895
k_VBattMaxESP_Volt_f32	9.50580025
k_VBattMinAAS_Volt_f32	19.6846008
k_VBattMinBSI_Volt_f32	9.50580025
k_VBattMinCAV_Volt_f32	26.3064003
k_VBattMinCMM388_Volt_f32	31.3855991
k_VBattMinCMM_Volt_f32	10.6521997
k_VBattMinESP_Volt_f32	2.98950005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	57893
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	14336
k_VitesseVehicleBVRampValidThresh_Cnt_u16	34756
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	12878
k_VitesseVehicleBVSigValidThresh_Cnt_u16	33241
k_VitesseVehicleBVSpeedPassThresh_kph_f32	569.147095
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	50882
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	56689
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2931165952
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	25029

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	282421248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	6
target_SrlComInput_Per1_Batt_Volt_f32.value	6.87230015
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4213553920
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	59
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0351573601
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1172744960
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	862735104
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	285338368
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	111643392
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1012738816
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3659713280
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	133720832
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	111
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	114
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	202
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	226
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	226
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1119128320
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	47
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	82
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	158
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	232
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1473096448
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	919816960
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3320376064
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	94
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	170
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	195
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2127248128
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	444
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.818900585
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	621662
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	46.8161011
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	61153

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	282421248	282421248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	282421248	282421248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	618.090576	618.090576	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	1253	1253	✔
BSINodeAbsentTimer_mS_M_u32	282421248	282421248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	282421248	282421248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	282421248	282421248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	282421248	282421248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3659713280	3659713280	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	45679	45679	✔
CONSANGLECPK_HwDeg_M_f32	-499.908691	-499.908691 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2	2	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	282421248	282421248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	282421248	282421248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	282421248	282421248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	282421248	282421248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	282421248	282421248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	282421248	282421248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	282421248	282421248	✔
ESPNTCEnableTimer_mS_M_u32	282421248	282421248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	4337	4337	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ESPNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	282421248	282421248	✔
EffacDefaultDiagTimer_mS_M_u32[1]	6	6	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	282421248	282421248	✔
ElecIntTimer_mS_M_u32[1]	877878	877878	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	282421248	282421248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	282421248	282421248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	282421248	282421248	✔
IgnOnTimer_mS_M_u32	853846784	853846784	✔
IgnTimeOff_Sec_M_u32	2830770688	2830770688	✔
Msg348Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1172744960	1172744960	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	105	105	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	862735104	862735104	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	233	233	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	285338368	285338368	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	110	110	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	111643392	111643392	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1756031744	1756031744	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	35	35	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3659713280	3659713280	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	133720832	133720832	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	226	226	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1119128320	1119128320	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1473096448	1473096448	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	251	251	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	919816960	919816960	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	77	77	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3320376064	3320376064	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2127248128	2127248128	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	53.2686996	53.2686996	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	41.6988983	41.6988983	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	603.075928	603.075928	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	618.090576	618.090576	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	45679	45679	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2830770688	2830770688	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-499.908691	-499.908691 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	252.393494	252.393494	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	13	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	13	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.195 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	942764544
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	46551
AASNodeAbsentTimer_mS_M_u32	299000320
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	7252
ANGLEVOLANTSigValidCount_Cnt_M_u16	62638
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	28596
AngleVolantMsgTimer_mS_M_u32	942764544
AngleVolantValidCount_Cnt_M_u16	45866
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	205.943832
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	228205056
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4050166272
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3657437696
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3533099520
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	35931
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1473810944
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	13570
CAVNodeAbsentTimer_mS_M_u32	2847212032
CDD_SrlComVehSpd_Kph_G_f32	360.012604
CMM388NTCEnableTimer_mS_M_u32	3120120320
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1628111360
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	5283
CMMNodeAbsentTimer_mS_M_u32	1103155712
CONSANGLECPKSigInvalidCount_Cnt_M_u16	41832
CONSANGLECPKSigValidCount_Cnt_M_u16	46866
CONSANGLECPK_Cnt_M_u16	2621
CONSANGLECPK_HwDeg_M_f32	-388.290894
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2621
CPKVehicleSpeedMsgTimer_mS_M_u32	3614470656
CPKVehicleSpeedValidCount_Cnt_M_u16	13250
CityParkInputConsistentCount_Cnt_M_u16	64782
CityParkInputInvalidCount_Cnt_M_u16	38355
CityParkInputMsgTimer_mS_M_u32	1172744960
CityParkInputValidCount_Cnt_M_u16	2

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3568722432
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	38331
ComputerRazGCTSigInvalidTimer_mS_M_u32	3686105600
ComputerRazGCTSigValidCount_Cnt_M_u16	22435
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	10223
DMDFCTCPKSigValidCount_Cnt_M_u16	14513
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	6214
DMDRELAXECPKSigValidCount_Cnt_M_u16	25120
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	38469
DateInvalidTimer_mS_M_u32	4050166272
DiagMuxOnAbsentTimer_mS_M_u32	2354262528
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3533099520
ESPNTCEnableTimer_mS_M_u32	978543104
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	39289
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	9
EffacDefaultDiagTimer_mS_M_u32[1]	81
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	2323
ElecIntTimer_mS_M_u32[1]	45465
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2385154560
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	40572
EtatMTSigValidCount_Cnt_M_u16	44994
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	62810
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	64132
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	10759
ISDAT4V2BSI552MsgTimer_mS_M_u32	665113088
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1753
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	5480
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	44994
ISDATBSI3F2MsgTimer_mS_M_u32	1382101504
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	60968
ISDATBSI412MsgLenValidCount_Cnt_M_u16	9958
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	40572
ISDATBSI412MsgTimer_mS_M_u32	2218750464
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	23943
ISDATBSI432MsgLenValidCount_Cnt_M_u16	34141
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	64675
ISDATDIRASentFltAcc_Cnt_M_u16	50327
ISDATDIRASentTimer_mS_M_u32	3614470656
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	57035
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	45866
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	61814
ISDYN2CMMMsgTimer_mS_M_u32	905798144
ISDYNAASChkSumInvalidCount_Cnt_M_u16	48585
ISDYNAASChkSumValidCount_Cnt_M_u16	35652
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	689
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	64621
ISDYNAASMsgLenValidCount_Cnt_M_u16	47968
ISDYNAASMsgTimeValidCount_Cnt_M_u16	48585
ISDYNAASMsgTimer_mS_M_u32	3507831296
ISDYNABRChkSumInvalidCount_Cnt_M_u16	65535
ISDYNABRChkSumValidCount_Cnt_M_u16	30940
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	49104
ISDYNABRMsgCountValidCount_Cnt_M_u16	54411
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	59503
ISDYNABRMsgLenValidCount_Cnt_M_u16	33625
ISDYNABRMsgTimeValidCount_Cnt_M_u16	2621
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	743
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1371
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	44994
ISDYNCMM208MsgTimer_mS_M_u32	3429835264

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2823
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1477
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	17976
ISDYNCMM388MsgTimer_mS_M_u32	3866673664
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	8566
ISDYNVOLChkSumValidCount_Cnt_M_u16	17312
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	10493
ISDYNVOLMsgCountValidCount_Cnt_M_u16	34879
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	58994
ISDYNVOLMsgLenValidCount_Cnt_M_u16	25853
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	5283
ISDYNVOLMsgTimer_mS_M_u32	2664530432
IgnOnTimer_mS_M_u32	3881615872
IgnTimeOff_Sec_M_u32	519284203
ManVehSpd_Kph_M_f32	585.118103
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	107
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	43
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1435972096
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	71
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1726419456
PrevISDATBSI412MsgDLCError_Cnt_M_u08	80
PrevISDATBSI412MsgRxTime_MSec_M_u32	2551579136
PrevISDATBSI432MsgDLCError_Cnt_M_u08	23
PrevISDATBSI432MsgRxTime_MSec_M_u32	78078464
PrevISDATDIRAMsgTxTime_MSec_M_u32	789185024
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	16
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2829865472
PrevISDYNAASMsgDLCError_Cnt_M_u08	70
PrevISDYNAASMsgRxTime_MSec_M_u32	3143598592
PrevISDYNABRMsgDLCError_Cnt_M_u08	33
PrevISDYNABRMsgRxTime_MSec_M_u32	680837632
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	189
PrevISDYNCMM208MsgRxTime_MSec_M_u32	129270272
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	82
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2496815616
PrevISDYNVOLMsgDLCError_Cnt_M_u08	51
PrevISDYNVOLMsgRxTime_MSec_M_u32	3124953600
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3813503488
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	396.652313
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	33659
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	4334
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	50676
VitesseVehicleBVRampValidCount_Cnt_M_u16	27687
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	41037
VitesseVehicleBVSigValidCount_Cnt_M_u16	45415
VitesseVehicleBV_Kph_M_f32	357.01059
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	17976
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	10

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	435.511597
k_AASNTCEnableTimeout_mS_u16	20412
k_AASNodeAbsentDiag_Cnt_str.Threshold	12222
k_AASNodeAbsentDiag_Cnt_str.PStep	35436
k_AASNodeAbsentDiag_Cnt_str.NStep	31728
k_AASNodeAbsentTimeout_mS_u16	35789
k_AASNodeTimeout_mS_u16	5102
k_ABSNodeTimeout_mS_u16	55940
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	42858
k_ANGLEVOLANTSigValidThresh_Cnt_u16	33664
k_AngleVolantInvalidThresh_Cnt_u16	45903
k_AngleVolantValidThresh_Cnt_u16	38355
k_BSI552MsgTimeout_mS_u16	22681
k_BSINTCEnableTimeout_mS_u16	3775
k_BSINodeAbsentDiag_Cnt_str.Threshold	1366
k_BSINodeAbsentDiag_Cnt_str.PStep	1366
k_BSINodeAbsentDiag_Cnt_str.NStep	5108
k_BSINodeAbsentTimeout_mS_u16	37612
k_BSINodeTimeout_mS_u16	64675
k_BattOvHi_Volt_f32	14.0313997
k_BattOvLo_Volt_f32	2.40960002
k_BattUvHi_Volt_f32	2.43860006
k_BattUvLo_Volt_f32	19.2194004
k_CAVNTCEnableTimeout_mS_u16	24089
k_CAVNodeAbsentDiag_Cnt_str.Threshold	3278
k_CAVNodeAbsentDiag_Cnt_str.PStep	40457
k_CAVNodeAbsentDiag_Cnt_str.NStep	24390
k_CAVNodeAbsentTimeout_mS_u16	14096
k_CAVNodeTimeout_mS_u16	45700
k_CMM388MsgTimeout_mS_u16	63703
k_CMM388NTCEnableTimeout_mS_u16	22771
k_CMMNTCEnableTimeout_mS_u16	5137
k_CMMNodeAbsentDiag_Cnt_str.Threshold	64865
k_CMMNodeAbsentDiag_Cnt_str.PStep	13070
k_CMMNodeAbsentDiag_Cnt_str.NStep	24285
k_CMMNodeAbsentTimeout_mS_u16	13862
k_CONSANGLECPKMax_HwDeg_f32	779.938721
k_CONSANGLECPKMin_HwDeg_f32	-460.032806
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	2360
k_CONSANGLECPKSigValidThresh_Cnt_u16	778
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	32836
k_CPKVehicleSpeedValidThresh_Cnt_u16	2899
k_CityParkInputInvalidThresh_Cnt_u16	5647
k_CityParkInputValidThresh_Cnt_u16	64782
k_ComputerRazGCTSigValidThresh_Cnt_u16	62607
k_CptTemporelSigValidThresh_Cnt_u16	65438
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	11119
k_DMDFCTCPKSigValidThresh_Cnt_u16	1625
k_DMDFCTCPKValidCount_Cnt_u16	48163
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	61814
k_DMDRELAXECPKSigValidThresh_Cnt_u16	59768
k_DMDRelaxeConsistentThresh_Cnt_u16	8142
k_DateValidThresh_Cnt_u16	10759
k_DefaultVehSpd_Kph_f32	95.1116028
k_DiagMuxOnAbsentTimeout_mS_u16	54275
k_EMNodeTimeout_mS_u16	31653
k_ESPNTCEnableTimeout_mS_u16	17950
k_ESPNodeAbsentDiag_Cnt_str.Threshold	22426
k_ESPNodeAbsentDiag_Cnt_str.PStep	52857
k_ESPNodeAbsentDiag_Cnt_str.NStep	29219
k_ESPNodeAbsentTimeout_mS_u16	3310
k_EtatMTSigInvalidThresh_Cnt_u16	25320
k_EtatMTSigValidThresh_Cnt_u16	17355
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	4943
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	54645
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	29063
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	6102
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	55845
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	64780
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	51204
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	50074
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	58987
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	65153

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	20320
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	55194
k_ISDATDIRASentDiag_Cnt_str.Threshold	1905
k_ISDATDIRASentDiag_Cnt_str.PStep	4278
k_ISDATDIRASentDiag_Cnt_str.NStep	49319
k_ISDATDIRASentTimeout_mS_u16	6741
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	26479
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	28596
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	22730
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	36921
k_ISDYNAASChkSumValidThresh_Cnt_u16	31708
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	720
k_ISDYNAASMsgCountValidThresh_Cnt_u16	22411
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	33565
k_ISDYNAASMsgLenValidThresh_Cnt_u16	13778
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	47176
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	37245
k_ISDYNABRChkSumValidThresh_Cnt_u16	31463
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	53083
k_ISDYNABRMsgCountValidThresh_Cnt_u16	44789
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	6051
k_ISDYNABRMsgLenValidThresh_Cnt_u16	56441
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	44292
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	17759
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	993
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	37757
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	24404
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	30638
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	48395
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	20619
k_ISDYNVOLChkSumValidThresh_Cnt_u16	40329
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	41558
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	37312
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	13464
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	58078
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	43725
k_IgnOnTimeout_mS_u16	37287
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	110.617996
k_PowerCutVehSpdLowThresh_Kph_f32	48.5633011
k_PowerCutVehSpdLowTimeout_mS_u16	40648
k_VBattMaxAAS_Volt_f32	21.5086994
k_VBattMaxBSI_Volt_f32	6.26289988
k_VBattMaxCAV_Volt_f32	19.8978004
k_VBattMaxCMM388_Volt_f32	2.31139994
k_VBattMaxCMM_Volt_f32	3.69009995
k_VBattMaxESP_Volt_f32	19.5701008
k_VBattMinAAS_Volt_f32	21.2602005
k_VBattMinBSI_Volt_f32	19.5701008
k_VBattMinCAV_Volt_f32	26.8861008
k_VBattMinCMM388_Volt_f32	12.2284002
k_VBattMinCMM_Volt_f32	0.0175000001
k_VBattMinESP_Volt_f32	3.69009995
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	50713
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	27975
k_VitesseVehicleBVRampValidThresh_Cnt_u16	60413
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	50848
k_VitesseVehicleBVSigValidThresh_Cnt_u16	16575
k_VitesseVehicleBVSpeedPassThresh_kph_f32	241.816803
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	63490
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	44213
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4050166272
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	57136
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	146705152
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSe	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	82
target_SrlComInput_Per1_Batt_Volt_f32.value	6.79460001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2799276544
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	253
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.358024985
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	911655424
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	147
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	205906432
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1376059904
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	65
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2408849920
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1291010560
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	304243200
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1730249216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	36
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	100
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	170
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	212
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1332552192
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	60
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	126
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1554104832
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1578164736
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2404385280
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	72
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2447970816
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1267
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.330557376
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	709682
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	244.593796
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	48037

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	146705152	146705152	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	146705152	146705152	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	205.943832	205.943832	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	1366	1366	✔
BSINodeAbsentTimer_mS_M_u32	146705152	146705152	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	146705152	146705152	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	146705152	146705152	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	146705152	146705152	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	304243200	304243200	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	2621	2621	✔
CONSANGLECPK_HwDeg_M_f32	-388.290894	-388.290894 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2	2	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	146705152	146705152	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	146705152	146705152	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	146705152	146705152	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	146705152	146705152	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	146705152	146705152	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	146705152	146705152	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	146705152	146705152	✔
ESPNTCEnableTimer_mS_M_u32	978543104	978543104	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	22426	22426	✔
ESPNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	146705152	146705152	✔
EffacDefaultDiagTimer_mS_M_u32[1]	81	81	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	146705152	146705152	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	45465	45465	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	146705152	146705152	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	146705152	146705152	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	1	1	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1332552192	1332552192	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	146705152	146705152	✔
IgnOnTimer_mS_M_u32	3881615872	3881615872	✔
IgnTimeOff_Sec_M_u32	519284203	519284203	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	911655424	911655424	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	147	147	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	205906432	205906432	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	208	208	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1376059904	1376059904	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	65	65	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2408849920	2408849920	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	789185024	789185024	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	222	222	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	304243200	304243200	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	26	26	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1730249216	1730249216	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1332552192	1332552192	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1554104832	1554104832	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	55	55	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1578164736	1578164736	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	0	0	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2404385280	2404385280	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2447970816	2447970816	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	396.652313	396.652313	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	357.01059	357.01059	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	435.511597	435.511597	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	205.943832	205.943832	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	2621	2621	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	519284203	519284203	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-388.290894	-388.290894 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	95.1116028	95.1116028	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	4	ValidityNTCProcessing	4	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.196 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3880938752
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	10334
AASNodeAbsentTimer_mS_M_u32	1244634368
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	34537
ANGLEVOLANTSigValidCount_Cnt_M_u16	45978
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	44743
AngleVolantMsgTimer_mS_M_u32	3880938752
AngleVolantValidCount_Cnt_M_u16	41192
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	744.691345
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	634936576
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3563904256
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	73829632
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3852619008
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	4820
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2363297024
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	7519
CAVNodeAbsentTimer_mS_M_u32	3574054144
CDD_SrlComVehSpd_Kph_G_f32	99.7113037
CMM388NTCEnableTimer_mS_M_u32	87751936
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2265300224
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	7484
CMMNodeAbsentTimer_mS_M_u32	3223604480
CONSANGLECPKSigInvalidCount_Cnt_M_u16	61614
CONSANGLECPKSigValidCount_Cnt_M_u16	43886
CONSANGLECPK_Cnt_M_u16	7661
CONSANGLECPK_HwDeg_M_f32	15.3388996
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	7661
CPKVehicleSpeedMsgTimer_mS_M_u32	3314904320
CPKVehicleSpeedValidCount_Cnt_M_u16	46279

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	21308
CityParkInputInvalidCount_Cnt_M_u16	11756
CityParkInputMsgTimer_mS_M_u32	911655424
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2441321728
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	6322
ComputerRazGCTSigInvalidTimer_mS_M_u32	3775282432
ComputerRazGCTSigValidCount_Cnt_M_u16	55165
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	59288
DMDFCTCPKSigValidCount_Cnt_M_u16	2833
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56083
DMDRELAXECPKSigValidCount_Cnt_M_u16	45892
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	52247
DateInvalidTimer_mS_M_u32	3563904256
DiagMuxOnAbsentTimer_mS_M_u32	2716675328
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3852619008
ESPNTCEnableTimer_mS_M_u32	346856704
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	13433
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	66
EffacDefaultDiagTimer_mS_M_u32[1]	163190528
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	16
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2984709376
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	29873
EtatMTSigValidCount_Cnt_M_u16	42653
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	17112
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	10520
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	3855
ISDAT4V2BSI552MsgTimer_mS_M_u32	2658684160
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	59673
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	17197
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	42653
ISDATBSI3F2MsgTimer_mS_M_u32	130231552
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	15406
ISDATBSI412MsgLenValidCount_Cnt_M_u16	55219
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	29873
ISDATBSI412MsgTimer_mS_M_u32	3139988736
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	53904
ISDATBSI432MsgLenValidCount_Cnt_M_u16	205
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	35452
ISDATDIRASentFltAcc_Cnt_M_u16	672
ISDATDIRASentTimer_mS_M_u32	3314904320
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	22595
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	41192
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	26371
ISDYN2CMMMsgTimer_mS_M_u32	1236180224
ISDYNAASChkSumInvalidCount_Cnt_M_u16	22664
ISDYNAASChkSumValidCount_Cnt_M_u16	9689
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	36435
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	13086
ISDYNAASMsgLenValidCount_Cnt_M_u16	3078
ISDYNAASMsgTimeValidCount_Cnt_M_u16	22664
ISDYNAASMsgTimer_mS_M_u32	803667200
ISDYNABRChkSumInvalidCount_Cnt_M_u16	65534
ISDYNABRChkSumValidCount_Cnt_M_u16	5265
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	11891
ISDYNABRMsgCountValidCount_Cnt_M_u16	9732
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	64921
ISDYNABRMsgLenValidCount_Cnt_M_u16	8857
ISDYNABRMsgTimeValidCount_Cnt_M_u16	7661

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	141
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	167
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	42653
ISDYNCMM208MsgTimer_mS_M_u32	2103008512
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	415
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	273
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	40894
ISDYNCMM388MsgTimer_mS_M_u32	3720117504
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	11908
ISDYNVOLChkSumValidCount_Cnt_M_u16	48580
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	40046
ISDYNVOLMsgCountValidCount_Cnt_M_u16	54375
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	29070
ISDYNVOLMsgLenValidCount_Cnt_M_u16	27567
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	7484
ISDYNVOLMsgTimer_mS_M_u32	129121536
IgnOnTimer_mS_M_u32	1796242688
IgnTimeOff_Sec_M_u32	2080187495
ManVehSpd_Kph_M_f32	490.306305
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	77
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	178
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1445014784
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	54
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3115420928
PrevISDATBSI412MsgDLCError_Cnt_M_u08	74
PrevISDATBSI412MsgRxTime_MSec_M_u32	3454319872
PrevISDATBSI432MsgDLCError_Cnt_M_u08	98
PrevISDATBSI432MsgRxTime_MSec_M_u32	95460608
PrevISDATDIRAMsgTxTime_MSec_M_u32	3641228544
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	63
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2573323520
PrevISDYNAASMsgDLCError_Cnt_M_u08	12
PrevISDYNAASMsgRxTime_MSec_M_u32	1778924800
PrevISDYNABRMsgDLCError_Cnt_M_u08	230
PrevISDYNABRMsgRxTime_MSec_M_u32	2271771904
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	177
PrevISDYNCMM208MsgRxTime_MSec_M_u32	420035840
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	121
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3241123072
PrevISDYNVOLMsgDLCError_Cnt_M_u08	249
PrevISDYNVOLMsgRxTime_MSec_M_u32	1532869888
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1442737408
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	179.515396
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	22004
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	50012
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	45705
VitesseVehicleBVRampValidCount_Cnt_M_u16	54705
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	7934

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	41327
VitesseVehicleBV_Kph_M_f32	521.49353
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	40894
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	2055
VitesseVehiculeRoues_Kph_M_f32	248.815094
k_AASNTCEnableTimeout_mS_u16	2416
k_AASNodeAbsentDiag_Cnt_str.Threshold	4467
k_AASNodeAbsentDiag_Cnt_str.PStep	60116
k_AASNodeAbsentDiag_Cnt_str.NStep	906
k_AASNodeAbsentTimeout_mS_u16	25343
k_AASNodeTimeout_mS_u16	47708
k_ABSNodeTimeout_mS_u16	25561
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	16615
k_ANGLEVOLANTSigValidThresh_Cnt_u16	21092
k_AngleVolantInvalidThresh_Cnt_u16	48887
k_AngleVolantValidThresh_Cnt_u16	11756
k_BSI552MsgTimeout_mS_u16	64090
k_BSINTCEnableTimeout_mS_u16	40680
k_BSINodeAbsentDiag_Cnt_str.Threshold	3052
k_BSINodeAbsentDiag_Cnt_str.PStep	44243
k_BSINodeAbsentDiag_Cnt_str.NStep	1848
k_BSINodeAbsentTimeout_mS_u16	9503
k_BSINodeTimeout_mS_u16	35452
k_BattOvHi_Volt_f32	11.6260996
k_BattOvLo_Volt_f32	11.8016005
k_BattUvHi_Volt_f32	18.5384007
k_BattUvLo_Volt_f32	1.42589998
k_CAVNTCEnableTimeout_mS_u16	27930
k_CAVNodeAbsentDiag_Cnt_str.Threshold	41800
k_CAVNodeAbsentDiag_Cnt_str.PStep	20653
k_CAVNodeAbsentDiag_Cnt_str.NStep	46182
k_CAVNodeAbsentTimeout_mS_u16	53045
k_CAVNodeTimeout_mS_u16	13146
k_CMM388MsgTimeout_mS_u16	24414
k_CMM388NTCEnableTimeout_mS_u16	44810
k_CMMNTCEnableTimeout_mS_u16	41329
k_CMMNodeAbsentDiag_Cnt_str.Threshold	10365
k_CMMNodeAbsentDiag_Cnt_str.PStep	62446
k_CMMNodeAbsentDiag_Cnt_str.NStep	23219
k_CMMNodeAbsentTimeout_mS_u16	54707
k_CONSANGLECPKMax_HwDeg_f32	216.437698
k_CONSANGLECPKMin_HwDeg_f32	-581.668091
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	22206
k_CONSANGLECPKSigValidThresh_Cnt_u16	65287
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	19802
k_CPKVehicleSpeedValidThresh_Cnt_u16	20653
k_CityParkInputInvalidThresh_Cnt_u16	16183
k_CityParkInputValidThresh_Cnt_u16	21308
k_ComputerRazGCTSigValidThresh_Cnt_u16	30711
k_CptTemporelSigValidThresh_Cnt_u16	56459
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	13465
k_DMDFCTCPKSigValidThresh_Cnt_u16	39321
k_DMDFCTCPKValidCount_Cnt_u16	41852
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	26371
k_DMDRELAXECPKSigValidThresh_Cnt_u16	54460
k_DMDRelaxeConsistentThresh_Cnt_u16	2490
k_DateValidThresh_Cnt_u16	3855
k_DefaultVehSpd_Kph_f32	135.066605
k_DiagMuxOnAbsentTimeout_mS_u16	22683
k_EMNodeTimeout_mS_u16	39927
k_ESPNTCEnableTimeout_mS_u16	23051
k_ESPNodeAbsentDiag_Cnt_str.Threshold	17978
k_ESPNodeAbsentDiag_Cnt_str.PStep	37115
k_ESPNodeAbsentDiag_Cnt_str.NStep	784
k_ESPNodeAbsentTimeout_mS_u16	29019
k_EtatMTSigInvalidThresh_Cnt_u16	64684
k_EtatMTSigValidThresh_Cnt_u16	12228
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	32825
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	8070
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	6609
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	59938
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	10486
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	40834

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	50969
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	31254
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	51172
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	20769
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	9286
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	6359
k_ISDATDIRASentDiag_Cnt_str.Threshold	6549
k_ISDATDIRASentDiag_Cnt_str.PStep	63930
k_ISDATDIRASentDiag_Cnt_str.NStep	24627
k_ISDATDIRASentTimeout_mS_u16	51813
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	64856
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	44743
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	53767
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	63673
k_ISDYNAASChkSumValidThresh_Cnt_u16	2961
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	25971
k_ISDYNAASMsgCountValidThresh_Cnt_u16	40196
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	45069
k_ISDYNAASMsgLenValidThresh_Cnt_u16	58544
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	54284
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	47727
k_ISDYNABRChkSumValidThresh_Cnt_u16	62447
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	18900
k_ISDYNABRMsgCountValidThresh_Cnt_u16	24773
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	5180
k_ISDYNABRMsgLenValidThresh_Cnt_u16	27513
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	25240
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	41032
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7939
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	14255
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	48617
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	10906
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	38980
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	24837
k_ISDYNVOLChkSumValidThresh_Cnt_u16	49098
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	52706
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	23013
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	8797
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	32073
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	9405
k_IgnOnTimeout_mS_u16	3505
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	231.047607
k_PowerCutVehSpdLowThresh_Kph_f32	233.211594
k_PowerCutVehSpdLowTimeout_mS_u16	19532
k_VBattMaxAAS_Volt_f32	26.0177002
k_VBattMaxBSI_Volt_f32	28.7651005
k_VBattMaxCAV_Volt_f32	1.81449997
k_VBattMaxCMM388_Volt_f32	23.9582005
k_VBattMaxCMM_Volt_f32	1.74319994
k_VBattMaxESP_Volt_f32	15.8170996
k_VBattMinAAS_Volt_f32	13.0670004
k_VBattMinBSI_Volt_f32	15.8170996
k_VBattMinCAV_Volt_f32	18.7157001
k_VBattMinCMM388_Volt_f32	27.9486008
k_VBattMinCMM_Volt_f32	23.8146992
k_VBattMinESP_Volt_f32	1.74319994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	2394
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	6543
k_VitesseVehicleBVRampValidThresh_Cnt_u16	21358
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	13508
k_VitesseVehicleBVSigValidThresh_Cnt_u16	35881
k_VitesseVehicleBVSpeedPassThresh_kph_f32	403.663208
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	54367
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	52231
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3563904256
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65036
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	163190528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	121
target_SrlComInput_Per1_Batt_Volt_f32.value	13.5414
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3822718208
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	153
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.627984166
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3861019904
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2295667968
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	471317760
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	56
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	132799744
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3024944384
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2302647552
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4005707008
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	102
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	103
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	151
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	229
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	230
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1818189056
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	114
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	185
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	220
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1598127360
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2138316032
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1345764608
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	119
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3232468224
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	808
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.964761078
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	201304
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	64.3701019
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	54646

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	163190528	163190528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	44745	44745	✔
AngleVolantMsgTimer_mS_M_u32	163190528	163190528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	744.691345	744.691345	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	3052	3052	✔
BSINodeAbsentTimer_mS_M_u32	163190528	163190528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2302647552	2302647552	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	7661	7661	✔
CONSANGLECPK_HwDeg_M_f32	15.3388996	15.3388996 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	7663	7663	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	163190528	163190528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	21308	21308	✔
CityParkInputInvalidCount_Cnt_M_u16	11758	11758	✔
CityParkInputMsgTimer_mS_M_u32	163190528	163190528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	163190528	163190528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	163190528	163190528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	163190528	163190528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	163190528	163190528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	163190528	163190528	✔
ESPNTCEnableTimer_mS_M_u32	346856704	346856704	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	17978	17978	✔
ESPNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	66	66	✔
EffacDefaultDiagTimer_mS_M_u32[1]	163190528	163190528	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	163190528	163190528	✔
ElecIntTimer_mS_M_u32[1]	16	16	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	163190528	163190528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	163190528	163190528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	65534	65534	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	11892	11892	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1818189056	1818189056	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	163190528	163190528	✔
IgnOnTimer_mS_M_u32	1796242688	1796242688	✔
IgnTimeOff_Sec_M_u32	2080187495	2080187495	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	166	166	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3861019904	3861019904	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	119	119	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2295667968	2295667968	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	133	133	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	471317760	471317760	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	56	56	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	132799744	132799744	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3641228544	3641228544	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2302647552	2302647552	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	59	59	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4005707008	4005707008	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	230	230	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1818189056	1818189056	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	8	8	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1598127360	1598127360	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	119	119	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2138316032	2138316032	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1345764608	1345764608	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3232468224	3232468224	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	179.515396	179.515396	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	521.49353	521.49353	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	248.815094	248.815094	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	744.691345	744.691345	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	7661	7661	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2080187495	2080187495	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	15.3388996	15.3388996 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	135.066605	135.066605	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0132	0x0132	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	3	ValidityNTCProcessing	3	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.197 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	591741184
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	8249
AASNodeAbsentTimer_mS_M_u32	3661721856
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	53772
ANGLEVOLANTSigValidCount_Cnt_M_u16	64755
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	30578
AngleVolantMsgTimer_mS_M_u32	591741184
AngleVolantValidCount_Cnt_M_u16	42437
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	496.791016
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1453732096
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2074259712
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2158190848
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2961907968
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	34663
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	908189952
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	36675
CAVNodeAbsentTimer_mS_M_u32	849580288
CDD_SrlComVehSpd_Kph_G_f32	331.776001
CMM388NTCEnableTimer_mS_M_u32	920310016
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3825307904
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	28540
CMMNodeAbsentTimer_mS_M_u32	1940726016
CONSANGLECPKSigInvalidCount_Cnt_M_u16	1357
CONSANGLECPKSigValidCount_Cnt_M_u16	9028
CONSANGLECPK_Cnt_M_u16	3443
CONSANGLECPK_HwDeg_M_f32	-656.169495
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	3443

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CPKVehicleSpeedMsgTimer_mS_M_u32	1719156992
CPKVehicleSpeedValidCount_Cnt_M_u16	38911
CityParkInputConsistentCount_Cnt_M_u16	21081
CityParkInputInvalidCount_Cnt_M_u16	22557
CityParkInputMsgTimer_mS_M_u32	1362372096
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2882892032
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	27341
ComputerRazGCTSigInvalidTimer_mS_M_u32	103420160
ComputerRazGCTSigValidCount_Cnt_M_u16	31466
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	55177
DMDFCTCPKSigValidCount_Cnt_M_u16	38841
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	37718
DMDRELAXECPKSigValidCount_Cnt_M_u16	445
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	16774
DateInvalidTimer_mS_M_u32	2074259712
DiagMuxOnAbsentTimer_mS_M_u32	3392930048
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2961907968
ESPNTCEnableTimer_mS_M_u32	4224610560
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	37040
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	66
EffacDefaultDiagTimer_mS_M_u32[1]	163190528
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	16
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	239853824
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	12101
EtatMTSigValidCount_Cnt_M_u16	49704
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	9367
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1550
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	15127
ISDAT4V2BSI552MsgTimer_mS_M_u32	205594880
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	39458
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	25006
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	49704
ISDATBSI3F2MsgTimer_mS_M_u32	3807510784
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	18396
ISDATBSI412MsgLenValidCount_Cnt_M_u16	50135
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	12101
ISDATBSI412MsgTimer_mS_M_u32	167461120
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	3856
ISDATBSI432MsgLenValidCount_Cnt_M_u16	30532
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	9584
ISDATDIRASentFltAcc_Cnt_M_u16	26836
ISDATDIRASentTimer_mS_M_u32	1719156992
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	25257
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	42437
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	39012
ISDYN2CMMMsgTimer_mS_M_u32	1634758912
ISDYNAASChkSumInvalidCount_Cnt_M_u16	32131
ISDYNAASChkSumValidCount_Cnt_M_u16	31499
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	13472
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	8370
ISDYNAASMsgLenValidCount_Cnt_M_u16	18770
ISDYNAASMsgTimeValidCount_Cnt_M_u16	32131
ISDYNAASMsgTimer_mS_M_u32	2001129728
ISDYNABRChkSumInvalidCount_Cnt_M_u16	978
ISDYNABRChkSumValidCount_Cnt_M_u16	16737
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0
ISDYNABRMsgCountValidCount_Cnt_M_u16	63654
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	35752

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNABRMsgLenValidCount_Cnt_M_u16	18399
ISDYNABRMsgTimeValidCount_Cnt_M_u16	3443
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	141
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	167
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	49704
ISDYNCMM208MsgTimer_mS_M_u32	1450651904
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	415
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	273
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	10107
ISDYNCMM388MsgTimer_mS_M_u32	2949927168
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	30211
ISDYNVOLChkSumValidCount_Cnt_M_u16	53370
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	61247
ISDYNVOLMsgCountValidCount_Cnt_M_u16	11247
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	29781
ISDYNVOLMsgLenValidCount_Cnt_M_u16	40877
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28540
ISDYNVOLMsgTimer_mS_M_u32	43389184
IgnOnTimer_mS_M_u32	2808631552
IgnTimeOff_Sec_M_u32	2522110929
ManVehSpd_Kph_M_f32	586.157715
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	77
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	67
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	246415616
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	216
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1298030848
PrevISDATBSI412MsgDLCError_Cnt_M_u08	136
PrevISDATBSI412MsgRxTime_MSec_M_u32	9474304
PrevISDATBSI432MsgDLCError_Cnt_M_u08	210
PrevISDATBSI432MsgRxTime_MSec_M_u32	2115137792
PrevISDATDIRAMsgTxTime_MSec_M_u32	3337916672
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	103
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3894583552
PrevISDYNAASMsgDLCError_Cnt_M_u08	237
PrevISDYNAASMsgRxTime_MSec_M_u32	4291563776
PrevISDYNABRMsgDLCError_Cnt_M_u08	162
PrevISDYNABRMsgRxTime_MSec_M_u32	524308736
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	25
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2937917696
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	252
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2168549632
PrevISDYNVOLMsgDLCError_Cnt_M_u08	7
PrevISDYNVOLMsgRxTime_MSec_M_u32	2480509184
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3887153408
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	6.89599991
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	1640
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	11144
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	57741

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBVRampValidCount_Cnt_M_u16	34925
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	32945
VitesseVehicleBVSigValidCount_Cnt_M_u16	52568
VitesseVehicleBV_Kph_M_f32	212.6306
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	10107
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	44411
VitesseVehiculeRoues_Kph_M_f32	210.496201
k_AASNTCEnableTimeout_mS_u16	33254
k_AASNodeAbsentDiag_Cnt_str.Threshold	4467
k_AASNodeAbsentDiag_Cnt_str.PStep	60116
k_AASNodeAbsentDiag_Cnt_str.NStep	906
k_AASNodeAbsentTimeout_mS_u16	16140
k_AASNodeTimeout_mS_u16	21128
k_ABSNodeTimeout_mS_u16	30746
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	10391
k_ANGLEVOLANTSigValidThresh_Cnt_u16	30731
k_AngleVolantInvalidThresh_Cnt_u16	49806
k_AngleVolantValidThresh_Cnt_u16	22557
k_BSI552MsgTimeout_mS_u16	18878
k_BSINTCEnableTimeout_mS_u16	14056
k_BSINodeAbsentDiag_Cnt_str.Threshold	3052
k_BSINodeAbsentDiag_Cnt_str.PStep	44243
k_BSINodeAbsentDiag_Cnt_str.NStep	1848
k_BSINodeAbsentTimeout_mS_u16	26954
k_BSINodeTimeout_mS_u16	9584
k_BattOvHi_Volt_f32	11.3007002
k_BattOvLo_Volt_f32	30.9769001
k_BattUvHi_Volt_f32	25.0457001
k_BattUvLo_Volt_f32	12.9433002
k_CAVNTCEnableTimeout_mS_u16	46507
k_CAVNodeAbsentDiag_Cnt_str.Threshold	41800
k_CAVNodeAbsentDiag_Cnt_str.PStep	20653
k_CAVNodeAbsentDiag_Cnt_str.NStep	46182
k_CAVNodeAbsentTimeout_mS_u16	46073
k_CAVNodeTimeout_mS_u16	56761
k_CMM388MsgTimeout_mS_u16	34617
k_CMM388NTCEnableTimeout_mS_u16	31909
k_CMMNTCEnableTimeout_mS_u16	28154
k_CMMNodeAbsentDiag_Cnt_str.Threshold	10365
k_CMMNodeAbsentDiag_Cnt_str.PStep	62446
k_CMMNodeAbsentDiag_Cnt_str.NStep	23219
k_CMMNodeAbsentTimeout_mS_u16	32999
k_CONSANGLECPKMax_HwDeg_f32	575.796326
k_CONSANGLECPKMin_HwDeg_f32	-87.4197006
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	3707
k_CONSANGLECPKSigValidThresh_Cnt_u16	54395
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	13542
k_CPKVehicleSpeedValidThresh_Cnt_u16	29707
k_CityParkInputInvalidThresh_Cnt_u16	39088
k_CityParkInputValidThresh_Cnt_u16	21081
k_ComputerRazGCTSigValidThresh_Cnt_u16	11872
k_CptTemporelSigValidThresh_Cnt_u16	18540
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	62120
k_DMDFCTCPKSigValidThresh_Cnt_u16	61151
k_DMDFCTCPKValidCount_Cnt_u16	52367
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	39012
k_DMDRELAXECPKSigValidThresh_Cnt_u16	54996
k_DMDRelaxeConsistentThresh_Cnt_u16	64306
k_DateValidThresh_Cnt_u16	15127
k_DefaultVehSpd_Kph_f32	160.585495
k_DiagMuxOnAbsentTimeout_mS_u16	65153
k_EMNodeTimeout_mS_u16	1894
k_ESPNTCEnableTimeout_mS_u16	33199
k_ESPNodeAbsentDiag_Cnt_str.Threshold	17978
k_ESPNodeAbsentDiag_Cnt_str.PStep	37115
k_ESPNodeAbsentDiag_Cnt_str.NStep	784
k_ESPNodeAbsentTimeout_mS_u16	16655
k_EtatMTSigInvalidThresh_Cnt_u16	6837
k_EtatMTSigValidThresh_Cnt_u16	52356
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	64885
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	11193
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	46974
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	48635

Name	Input Value
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	58951
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	62832
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	15977
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	42845
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	61092
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	32999
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	38531
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	48489
k_ISDATDIRASentDiag_Cnt_str.Threshold	6549
k_ISDATDIRASentDiag_Cnt_str.PStep	63930
k_ISDATDIRASentDiag_Cnt_str.NStep	24627
k_ISDATDIRASentTimeout_mS_u16	574
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	23098
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	30578
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	14443
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	60114
k_ISDYNAASChkSumValidThresh_Cnt_u16	26721
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	990
k_ISDYNAASMsgCountValidThresh_Cnt_u16	40870
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	11366
k_ISDYNAASMsgLenValidThresh_Cnt_u16	63260
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	65075
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	11102
k_ISDYNABRChkSumValidThresh_Cnt_u16	25621
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	61031
k_ISDYNABRMsgCountValidThresh_Cnt_u16	14222
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	38524
k_ISDYNABRMsgLenValidThresh_Cnt_u16	63408
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	47953
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	51964
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	40257
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	59851
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	14604
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	41971
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	32245
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	8163
k_ISDYNVOLChkSumValidThresh_Cnt_u16	25374
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	60137
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	28917
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	58033
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	28308
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	30501
k_IgnOnTimeout_mS_u16	33359
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	89.0429993
k_PowerCutVehSpdLowThresh_Kph_f32	40.3320007
k_PowerCutVehSpdLowTimeout_mS_u16	27010
k_VBattMaxAAS_Volt_f32	21.7541008
k_VBattMaxBSI_Volt_f32	10.4558001
k_VBattMaxCAV_Volt_f32	5.58900023
k_VBattMaxCMM388_Volt_f32	30.8959007
k_VBattMaxCMM_Volt_f32	29.8451004
k_VBattMaxESP_Volt_f32	29.5552998
k_VBattMinAAS_Volt_f32	13.1494999
k_VBattMinBSI_Volt_f32	12.125
k_VBattMinCAV_Volt_f32	14.2356005
k_VBattMinCMM388_Volt_f32	0.270500004
k_VBattMinCMM_Volt_f32	20.0400009
k_VBattMinESP_Volt_f32	12.125
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	50908
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	11912
k_VitesseVehicleBVRampValidThresh_Cnt_u16	54847
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	30586
k_VitesseVehicleBVSigValidThresh_Cnt_u16	25942
k_VitesseVehicleBVSpeedPassThresh_kph_f32	13.5290003
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	30275
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	22947
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2074259712
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65036

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	163190528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	252
target_SrlComInput_Per1_Batt_Volt_f32.value	18.8777008
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3425624320
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	220
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.108573854
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	941248768
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3835621632
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2931003648
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2119708928
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	999084288
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3461443840
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	514199808
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	108
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	134
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	177
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	182
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3613208832
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	227
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	988369152
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2632839424
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3699544320
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	145
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2725798144
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	794
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.239259362
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	887142
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	89.1662979
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	65162

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	591741184	591741184	✔
AASNTCsEnabled_Cnt_M_lgc	1	1	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	163190528	163190528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	496.791016	496.791016	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	3052	3052	✔
BSINodeAbsentTimer_mS_M_u32	163190528	163190528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	5321	5321	✔
CMMNodeAbsentTimer_mS_M_u32	3461443840	3461443840	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	3443	3443	✔
CONSANGLECPK_HwDeg_M_f32	-656.169495	-656.169495 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2	2	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	163190528	163190528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	163190528	163190528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	163190528	163190528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	163190528	163190528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	163190528	163190528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	163190528	163190528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	163190528	163190528	✔
ESPNTCEnableTimer_mS_M_u32	4224610560	4224610560	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	17978	17978	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ESPNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	66	66	✔
EffacDefaultDiagTimer_mS_M_u32[1]	163190528	163190528	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	163190528	163190528	✔
ElecIntTimer_mS_M_u32[1]	16	16	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	163190528	163190528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	163190528	163190528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	514199808	514199808	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	1	1	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3613208832	3613208832	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	163190528	163190528	✔
IgnOnTimer_mS_M_u32	2808631552	2808631552	✔
IgnTimeOff_Sec_M_u32	2522110929	2522110929	✔
Msg348Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	220	220	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	941248768	941248768	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3835621632	3835621632	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	239	239	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2931003648	2931003648	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	31	31	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2119708928	2119708928	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3337916672	3337916672	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	83	83	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3461443840	3461443840	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	40	40	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	514199808	514199808	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3613208832	3613208832	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	172	172	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	988369152	988369152	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	118	118	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2632839424	2632839424	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3699544320	3699544320	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2725798144	2725798144	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	6.89599991	6.89599991	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	212.6306	212.6306	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	210.496201	210.496201	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	496.791016	496.791016	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	3443	3443	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2522110929	2522110929	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-656.169495	-656.169495 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	160.585495	160.585495	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	4	ValidityNTCProcessing	4	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.198 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4229103616
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	30517
AASNodeAbsentTimer_mS_M_u32	1138651136
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	52158
ANGLEVOLANTSigValidCount_Cnt_M_u16	50630
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	38282
AngleVolantMsgTimer_mS_M_u32	4229103616
AngleVolantValidCount_Cnt_M_u16	7442
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	599.595703
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1370501120
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1958391808
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2222497792
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1136746496
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	55213
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2113740800
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	31383
CAVNodeAbsentTimer_mS_M_u32	3946319872
CDD_SrlComVehSpd_Kph_G_f32	453.582886
CMM388NTCEnableTimer_mS_M_u32	3415363584
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3474853888
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	10668
CMMNodeAbsentTimer_mS_M_u32	39542784
CONSANGLECPKSigInvalidCount_Cnt_M_u16	9467
CONSANGLECPKSigValidCount_Cnt_M_u16	34260
CONSANGLECPK_Cnt_M_u16	17223
CONSANGLECPK_HwDeg_M_f32	-760.413391
CPKOK_Cnt_M_lgc	0

Name	Input Value
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17223
CPKVehicleSpeedMsgTimer_mS_M_u32	3195666432
CPKVehicleSpeedValidCount_Cnt_M_u16	22509
CityParkInputConsistentCount_Cnt_M_u16	26454
CityParkInputInvalidCount_Cnt_M_u16	46857
CityParkInputMsgTimer_mS_M_u32	941248768
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	522350592
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	59257
ComputerRazGCTSigInvalidTimer_mS_M_u32	2862911488
ComputerRazGCTSigValidCount_Cnt_M_u16	29091
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	59589
DMDFCTCPKSigValidCount_Cnt_M_u16	17142
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	12256
DMDRELAXECPKSigValidCount_Cnt_M_u16	24424
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	37968
DateInvalidTimer_mS_M_u32	1958391808
DiagMuxOnAbsentTimer_mS_M_u32	1378795520
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1136746496
ESPNTCEnableTimer_mS_M_u32	1396142080
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	28881
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	201
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	9
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	494870528
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	23379
EtatMTSigValidCount_Cnt_M_u16	3432
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	28445
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	34166
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20700
ISDAT4V2BSI552MsgTimer_mS_M_u32	2292146176
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	27193
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	7766
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	3432
ISDATBSI3F2MsgTimer_mS_M_u32	1611448320
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	54798
ISDATBSI412MsgLenValidCount_Cnt_M_u16	11483
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	23379
ISDATBSI412MsgTimer_mS_M_u32	2683371520
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	39664
ISDATBSI432MsgLenValidCount_Cnt_M_u16	3349
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	44048
ISDATDIRASentFltAcc_Cnt_M_u16	29156
ISDATDIRASentTimer_mS_M_u32	3195666432
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	39845
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	7442
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	53812
ISDYN2CMMMsgTimer_mS_M_u32	709980160
ISDYNAASChkSumInvalidCount_Cnt_M_u16	1879
ISDYNAASChkSumValidCount_Cnt_M_u16	2432
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	40065
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	16970
ISDYNAASMsgLenValidCount_Cnt_M_u16	9003
ISDYNAASMsgTimeValidCount_Cnt_M_u16	1879
ISDYNAASMsgTimer_mS_M_u32	3125694464
ISDYNABRChkSumInvalidCount_Cnt_M_u16	9708
ISDYNABRChkSumValidCount_Cnt_M_u16	34813
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	65535
ISDYNABRMsgCountValidCount_Cnt_M_u16	48303
ISDYNABRMsgCount_Cnt_M_u08	15

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	48618
ISDYNABRMsgLenValidCount_Cnt_M_u16	17411
ISDYNABRMsgTimeValidCount_Cnt_M_u16	17223
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	157
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	199
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	3432
ISDYNCMM208MsgTimer_mS_M_u32	3594334208
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	479
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	305
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	61424
ISDYNCMM388MsgTimer_mS_M_u32	648400896
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	10969
ISDYNVOLChkSumValidCount_Cnt_M_u16	54834
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	63907
ISDYNVOLMsgCountValidCount_Cnt_M_u16	56916
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	39394
ISDYNVOLMsgLenValidCount_Cnt_M_u16	21147
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	10668
ISDYNVOLMsgTimer_mS_M_u32	1700827136
IgnOnTimer_mS_M_u32	2414465024
IgnTimeOff_Sec_M_u32	202236160
ManVehSpd_Kph_M_f32	584.572815
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	93
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	143
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1423097856
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	247
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3393691648
PrevISDATBSI412MsgDLCError_Cnt_M_u08	183
PrevISDATBSI412MsgRxTime_MSec_M_u32	1970343936
PrevISDATBSI432MsgDLCError_Cnt_M_u08	233
PrevISDATBSI432MsgRxTime_MSec_M_u32	3698028544
PrevISDATDIRAMsgTxTime_MSec_M_u32	2990870528
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	108
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1526390784
PrevISDYNAASMsgDLCError_Cnt_M_u08	52
PrevISDYNAASMsgRxTime_MSec_M_u32	3317600256
PrevISDYNABRMsgDLCError_Cnt_M_u08	214
PrevISDYNABRMsgRxTime_MSec_M_u32	2288111616
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	98
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1003196416
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	26
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1323200512
PrevISDYNVOLMsgDLCError_Cnt_M_u08	130
PrevISDYNVOLMsgRxTime_MSec_M_u32	529928192
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1590624256
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	612.925781
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	59688
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	54409
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1

Name	Input Value
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	11193
VitesseVehicleBVRampValidCount_Cnt_M_u16	37338
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	37839
VitesseVehicleBVSigValidCount_Cnt_M_u16	10391
VitesseVehicleBV_Kph_M_f32	270.0513
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	61424
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	14513
VitesseVehiculeRoues_Kph_M_f32	121.343102
k_AASNTCEnableTimeout_mS_u16	29166
k_AASNodeAbsentDiag_Cnt_str.Threshold	47636
k_AASNodeAbsentDiag_Cnt_str.PStep	34578
k_AASNodeAbsentDiag_Cnt_str.NStep	62563
k_AASNodeAbsentTimeout_mS_u16	11581
k_AASNodeTimeout_mS_u16	24457
k_ABSNodeTimeout_mS_u16	35602
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	10843
k_ANGLEVOLANTSigValidThresh_Cnt_u16	59072
k_AngleVolantInvalidThresh_Cnt_u16	54071
k_AngleVolantValidThresh_Cnt_u16	46857
k_BSI552MsgTimeout_mS_u16	12264
k_BSINTCEnableTimeout_mS_u16	33640
k_BSINodeAbsentDiag_Cnt_str.Threshold	3692
k_BSINodeAbsentDiag_Cnt_str.PStep	43971
k_BSINodeAbsentDiag_Cnt_str.NStep	2216
k_BSINodeAbsentTimeout_mS_u16	8194
k_BSINodeTimeout_mS_u16	44048
k_BattOvHi_Volt_f32	9.27910042
k_BattOvLo_Volt_f32	27.4062996
k_BattUvHi_Volt_f32	12.0334997
k_BattUvLo_Volt_f32	0.955299973
k_CAVNTCEnableTimeout_mS_u16	22111
k_CAVNodeAbsentDiag_Cnt_str.Threshold	14101
k_CAVNodeAbsentDiag_Cnt_str.PStep	13590
k_CAVNodeAbsentDiag_Cnt_str.NStep	2667
k_CAVNodeAbsentTimeout_mS_u16	25717
k_CAVNodeTimeout_mS_u16	19383
k_CMM388MsgTimeout_mS_u16	16949
k_CMM388NTCEnableTimeout_mS_u16	4593
k_CMMNTCEnableTimeout_mS_u16	20145
k_CMMNodeAbsentDiag_Cnt_str.Threshold	62414
k_CMMNodeAbsentDiag_Cnt_str.PStep	42715
k_CMMNodeAbsentDiag_Cnt_str.NStep	22076
k_CMMNodeAbsentTimeout_mS_u16	28269
k_CONSANGLECPKMax_HwDeg_f32	334.590912
k_CONSANGLECPKMin_HwDeg_f32	-30.7777004
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	15088
k_CONSANGLECPKSigValidThresh_Cnt_u16	50097
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	45167
k_CPKVehicleSpeedValidThresh_Cnt_u16	52609
k_CityParkInputInvalidThresh_Cnt_u16	24402
k_CityParkInputValidThresh_Cnt_u16	26454
k_ComputerRazGCTSigValidThresh_Cnt_u16	9599
k_CptTemporelSigValidThresh_Cnt_u16	57884
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	35050
k_DMDFCTCPKSigValidThresh_Cnt_u16	20227
k_DMDFCTCPKValidCount_Cnt_u16	43061
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	53812
k_DMDRELAXECPKSigValidThresh_Cnt_u16	45477
k_DMDRelaxeConsistentThresh_Cnt_u16	15499
k_DateValidThresh_Cnt_u16	20700
k_DefaultVehSpd_Kph_f32	14.6294003
k_DiagMuxOnAbsentTimeout_mS_u16	10269
k_EMNodeTimeout_mS_u16	49840
k_ESPNTCEnableTimeout_mS_u16	21331
k_ESPNodeAbsentDiag_Cnt_str.Threshold	62971
k_ESPNodeAbsentDiag_Cnt_str.PStep	11352
k_ESPNodeAbsentDiag_Cnt_str.NStep	60169
k_ESPNodeAbsentTimeout_mS_u16	52725
k_EtatMTSigInvalidThresh_Cnt_u16	11587
k_EtatMTSigValidThresh_Cnt_u16	12948
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	21186
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	45751
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	3047

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	41646
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	13451
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	7506
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	45285
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	8394
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	19508
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	47339
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	49880
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	14950
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	55976
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	59379
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	38282
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	7967
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	28908
k_ISDYNAASChkSumValidThresh_Cnt_u16	4861
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	41030
k_ISDYNAASMsgCountValidThresh_Cnt_u16	51119
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	64560
k_ISDYNAASMsgLenValidThresh_Cnt_u16	49613
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	62536
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	14024
k_ISDYNABRChkSumValidThresh_Cnt_u16	18273
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	41645
k_ISDYNABRMsgCountValidThresh_Cnt_u16	16885
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46252
k_ISDYNABRMsgLenValidThresh_Cnt_u16	15313
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	33452
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	60268
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	43487
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	26048
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	38590
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	53446
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	42369
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	10745
k_ISDYNVOLChkSumValidThresh_Cnt_u16	11014
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	34342
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	18753
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	61711
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	47140
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	21682
k_IgnOnTimeout_mS_u16	45749
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	161.756805
k_PowerCutVehSpdLowThresh_Kph_f32	219.889603
k_PowerCutVehSpdLowTimeout_mS_u16	11034
k_VBattMaxAAS_Volt_f32	9.29520035
k_VBattMaxBSI_Volt_f32	28.8171997
k_VBattMaxCAV_Volt_f32	18.5709991
k_VBattMaxCMM388_Volt_f32	23.1520004
k_VBattMaxCMM_Volt_f32	30.5259991
k_VBattMaxESP_Volt_f32	25.6320992
k_VBattMinAAS_Volt_f32	30.3073997
k_VBattMinBSI_Volt_f32	3.21659994
k_VBattMinCAV_Volt_f32	31.1417999
k_VBattMinCMM388_Volt_f32	0.914099991
k_VBattMinCMM_Volt_f32	13.8895998
k_VBattMinESP_Volt_f32	3.21659994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	43533
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	64970
k_VitesseVehicleBVRampValidThresh_Cnt_u16	17571
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	57650
k_VitesseVehicleBVSigValidThresh_Cnt_u16	25183
k_VitesseVehicleBVSpeedPassThresh_kph_f32	585.976196
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	50583
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	30264
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1958391808
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	26
target_SrlComInput_Per1_Batt_Volt_f32.value	19.2900009
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	802562048
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	50
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.797768593
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	634638336
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	191
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2059792384
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3070758912
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	10
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	580530176
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	92033024
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2813227008
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	159
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1362137088
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	131
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	214
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1804283904
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	36
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	156
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	157
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	184
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	426168320
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1306062848
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	698028032
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3002703872
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	419
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.606383681
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	958917
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	83.637001
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	2242

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	38284	38284	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	599.595703	599.595703	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1370501120	1370501120	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2222497792	2222497792	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	1136746496	1136746496	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	14101	14101	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3474853888	3474853888	✔
CMMNTCsEnabled_Cnt_M_lgc	1	1	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	17223	17223	✔
CONSANGLECPK_HwDeg_M_f32	-760.413391	-760.413391 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17225	17225	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2006148864	2006148864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	26454	26454	✔
CityParkInputInvalidCount_Cnt_M_u16	46857	46857	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1958391808	1958391808	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	1396142080	1396142080	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ESPNodeAbsentFltAcc_Cnt_M_u16	62971	62971	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔
EffacDefaultDiagTimer_mS_M_u32[1]	201	201	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	8	8	✔
ElecIntTimer_mS_M_u32[1]	9	9	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	23379	23379	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	28445	28445	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	634638336	634638336	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	27194	27194	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2059792384	2059792384	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	39665	39665	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	580530176	580530176	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11170	11170	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	39846	39846	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2813227008	2813227008	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	9709	9709	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	65535	65535	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1804283904	1804283904	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	158	158	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	426168320	426168320	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	2006148864	2006148864	✔
IgnTimeOff_Sec_M_u32	202236160	202236160	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	99	99	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	634638336	634638336	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	191	191	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2059792384	2059792384	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	223	223	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3070758912	3070758912	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	10	10	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	580530176	580530176	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2990870528	2990870528	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2813227008	2813227008	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	159	159	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1362137088	1362137088	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	214	214	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1804283904	1804283904	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	239	239	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	426168320	426168320	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1306062848	1306062848	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	698028032	698028032	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3002703872	3002703872	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	612.925781	612.925781	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	270.0513	270.0513	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	121.343102	121.343102	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	599.595703	599.595703	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	17223	17223	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	202236160	202236160	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-760.413391	-760.413391 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	14.6294003	14.6294003	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	2	ValidityNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	2	ValidityNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.199 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3680879360
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	5118
AASNodeAbsentTimer_mS_M_u32	3183702784
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	55396
ANGLEVOLANTSigValidCount_Cnt_M_u16	31241
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	19711
AngleVolantMsgTimer_mS_M_u32	3680879360
AngleVolantValidCount_Cnt_M_u16	32486
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	323.885498
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	189674240

Name	Input Value
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3962483456
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1622467328
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	903521024
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	12439
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	640115456
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	6233
CAVNodeAbsentTimer_mS_M_u32	3057029888
CDD_SrlComVehSpd_Kph_G_f32	202.853607
CMM388NTCEnableTimer_mS_M_u32	1311232768
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	579113728
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	7129
CMMNodeAbsentTimer_mS_M_u32	3792478976
CONSANGLECPKSigInvalidCount_Cnt_M_u16	62379
CONSANGLECPKSigValidCount_Cnt_M_u16	41184
CONSANGLECPK_Cnt_M_u16	62599
CONSANGLECPK_HwDeg_M_f32	-443.20401
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	62599
CPKVehicleSpeedMsgTimer_mS_M_u32	4029727488
CPKVehicleSpeedValidCount_Cnt_M_u16	47550
CityParkInputConsistentCount_Cnt_M_u16	45082
CityParkInputInvalidCount_Cnt_M_u16	40449
CityParkInputMsgTimer_mS_M_u32	634638336
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1006072576
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	54066
ComputerRazGCTSigInvalidTimer_mS_M_u32	3388019456
ComputerRazGCTSigValidCount_Cnt_M_u16	1331
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	63693
DMDFCTCPKSigValidCount_Cnt_M_u16	6650
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	46078
DMDRELAXECPKSigValidCount_Cnt_M_u16	46371
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	14764
DateInvalidTimer_mS_M_u32	3962483456
DiagMuxOnAbsentTimer_mS_M_u32	4161962752
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	903521024
ESPNTCEnableTimer_mS_M_u32	867726080
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	17963
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	2050
EffacDefaultDiagTimer_mS_M_u32[1]	6070
ElecIntCount_Cnt_M_u08	2
ElecIntTimer_mS_M_u32[0]	56
ElecIntTimer_mS_M_u32[1]	457
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3483460352
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	13284
EtatMTSigValidCount_Cnt_M_u16	56677
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	7493
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	43514
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	2120
ISDAT4V2BSI552MsgTimer_mS_M_u32	1598071552
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	6320
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	56346
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	56677
ISDATBSI3F2MsgTimer_mS_M_u32	3329786624
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	30260

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDATBSI412MsgLenValidCount_Cnt_M_u16	4493
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	13284
ISDATBSI412MsgTimer_mS_M_u32	3888890624
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	55309
ISDATBSI432MsgLenValidCount_Cnt_M_u16	33119
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	42990
ISDATDIRASentFltAcc_Cnt_M_u16	42610
ISDATDIRASentTimer_mS_M_u32	4029727488
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	58221
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	32486
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	47232
ISDYN2CMMMsgTimer_mS_M_u32	2523558656
ISDYNAASChkSumInvalidCount_Cnt_M_u16	27544
ISDYNAASChkSumValidCount_Cnt_M_u16	29917
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	31897
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	19776
ISDYNAASMsgLenValidCount_Cnt_M_u16	39517
ISDYNAASMsgTimeValidCount_Cnt_M_u16	27544
ISDYNAASMsgTimer_mS_M_u32	1911804672
ISDYNABRChkSumInvalidCount_Cnt_M_u16	64345
ISDYNABRChkSumValidCount_Cnt_M_u16	34022
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	33265
ISDYNABRMsgCountValidCount_Cnt_M_u16	55120
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	42206
ISDYNABRMsgLenValidCount_Cnt_M_u16	57939
ISDYNABRMsgTimeValidCount_Cnt_M_u16	62599
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	703
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1291
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	56677
ISDYNCMM208MsgTimer_mS_M_u32	4054266624
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2663
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1397
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	65100
ISDYNCMM388MsgTimer_mS_M_u32	3941421824
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	55825
ISDYNVOLChkSumValidCount_Cnt_M_u16	42950
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	48691
ISDYNVOLMsgCountValidCount_Cnt_M_u16	16352
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	20216
ISDYNVOLMsgLenValidCount_Cnt_M_u16	29837
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	7129
ISDYNVOLMsgTimer_mS_M_u32	2310869760
IgnOnTimer_mS_M_u32	3206632192
IgnTimeOff_Sec_M_u32	1584567577
ManVehSpd_Kph_M_f32	409.178589
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	227
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	67
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2150007552
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	149
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2336744192
PrevISDATBSI412MsgDLCError_Cnt_M_u08	229
PrevISDATBSI412MsgRxTime_MSec_M_u32	999002880
PrevISDATBSI432MsgDLCError_Cnt_M_u08	33
PrevISDATBSI432MsgRxTime_MSec_M_u32	1746694912
PrevISDATDIRAMsgTxTime_MSec_M_u32	3574567680
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	211
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3056476928
PrevISDYNAASMsgDLCError_Cnt_M_u08	111
PrevISDYNAASMsgRxTime_MSec_M_u32	1621299968
PrevISDYNABRMsgDLCError_Cnt_M_u08	73
PrevISDYNABRMsgRxTime_MSec_M_u32	3048821504
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	206

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1920733952
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	130
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2630054656
PrevISDYNVOLMsgDLCError_Cnt_M_u08	171
PrevISDYNVOLMsgRxTime_MSec_M_u32	287085312
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2737947392
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	201.696899
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	20646
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	32323
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	3315
VitesseVehicleBVRampValidCount_Cnt_M_u16	51792
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	1073
VitesseVehicleBVSigValidCount_Cnt_M_u16	54678
VitesseVehicleBV_Kph_M_f32	407.33139
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	65100
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	37834
VitesseVehiculeRoues_Kph_M_f32	6.1111002
k_AASNTCEnableTimeout_mS_u16	50322
k_AASNodeAbsentDiag_Cnt_str.Threshold	8025
k_AASNodeAbsentDiag_Cnt_str.PStep	40741
k_AASNodeAbsentDiag_Cnt_str.NStep	23056
k_AASNodeAbsentTimeout_mS_u16	47717
k_AASNodeTimeout_mS_u16	56643
k_ABSNodeTimeout_mS_u16	34278
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	38348
k_ANGLEVOLANTSigValidThresh_Cnt_u16	24670
k_AngleVolantInvalidThresh_Cnt_u16	14073
k_AngleVolantValidThresh_Cnt_u16	40449
k_BSI552MsgTimeout_mS_u16	18981
k_BSINTCEnableTimeout_mS_u16	65189
k_BSINodeAbsentDiag_Cnt_str.Threshold	25532
k_BSINodeAbsentDiag_Cnt_str.PStep	34689
k_BSINodeAbsentDiag_Cnt_str.NStep	14774
k_BSINodeAbsentTimeout_mS_u16	36247
k_BSINodeTimeout_mS_u16	42990
k_BattOvHi_Volt_f32	5.2809
k_BattOvLo_Volt_f32	11.9322004
k_BattUvHi_Volt_f32	27.5499992
k_BattUvLo_Volt_f32	7.94029999
k_CAVNTCEnableTimeout_mS_u16	38911
k_CAVNodeAbsentDiag_Cnt_str.Threshold	43612
k_CAVNodeAbsentDiag_Cnt_str.PStep	33532
k_CAVNodeAbsentDiag_Cnt_str.NStep	50919
k_CAVNodeAbsentTimeout_mS_u16	21183
k_CAVNodeTimeout_mS_u16	28535
k_CMM388MsgTimeout_mS_u16	45822
k_CMM388NTCEnableTimeout_mS_u16	13258
k_CMMNTCEnableTimeout_mS_u16	19272
k_CMMNodeAbsentDiag_Cnt_str.Threshold	62640
k_CMMNodeAbsentDiag_Cnt_str.PStep	29375
k_CMMNodeAbsentDiag_Cnt_str.NStep	51731
k_CMMNodeAbsentTimeout_mS_u16	58006
k_CONSANGLECPKMax_HwDeg_f32	624.185791
k_CONSANGLECPKMin_HwDeg_f32	-570.65863
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	7500
k_CONSANGLECPKSigValidThresh_Cnt_u16	62154
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	657

Name	Input Value
k_CPKVehicleSpeedValidThresh_Cnt_u16	7131
k_CityParkInputInvalidThresh_Cnt_u16	26407
k_CityParkInputValidThresh_Cnt_u16	45082
k_ComputerRazGCTSigValidThresh_Cnt_u16	32478
k_CptTemporelSigValidThresh_Cnt_u16	10440
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	17374
k_DMDFCTCPKSigValidThresh_Cnt_u16	49491
k_DMDFCTCPKValidCount_Cnt_u16	57087
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	47232
k_DMDRELAXECPKSigValidThresh_Cnt_u16	18925
k_DMDRelaxeConsistentThresh_Cnt_u16	49467
k_DateValidThresh_Cnt_u16	2120
k_DefaultVehSpd_Kph_f32	4.23199987
k_DiagMuxOnAbsentTimeout_mS_u16	7685
k_EMNodeTimeout_mS_u16	11916
k_ESPNTCEnableTimeout_mS_u16	32293
k_ESPNodeAbsentDiag_Cnt_str.Threshold	40036
k_ESPNodeAbsentDiag_Cnt_str.PStep	46639
k_ESPNodeAbsentDiag_Cnt_str.NStep	47261
k_ESPNodeAbsentTimeout_mS_u16	58366
k_EtatMTSigInvalidThresh_Cnt_u16	340
k_EtatMTSigValidThresh_Cnt_u16	41249
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	10136
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	18297
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	18023
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	33617
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	44411
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	45160
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	43566
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	23104
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	54337
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	9115
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	9620
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	64043
k_ISDATDIRASentDiag_Cnt_str.Threshold	25239
k_ISDATDIRASentDiag_Cnt_str.PStep	16638
k_ISDATDIRASentDiag_Cnt_str.NStep	16248
k_ISDATDIRASentTimeout_mS_u16	52517
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	25988
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	19711
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	19137
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	6745
k_ISDYNAASChkSumValidThresh_Cnt_u16	58342
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	7371
k_ISDYNAASMsgCountValidThresh_Cnt_u16	46672
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	34957
k_ISDYNAASMsgLenValidThresh_Cnt_u16	50807
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	22470
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	12868
k_ISDYNABRChkSumValidThresh_Cnt_u16	53305
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	53143
k_ISDYNABRMsgCountValidThresh_Cnt_u16	33148
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	31449
k_ISDYNABRMsgLenValidThresh_Cnt_u16	58667
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	23383
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	23002
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	32449
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	26270
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	30564
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	22793
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	45721
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	58995
k_ISDYNVOLChkSumValidThresh_Cnt_u16	33548
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	39468
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	20762
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	25264
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	52529
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	54470
k_IgnOnTimeout_mS_u16	15423
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	21.3497009
k_PowerCutVehSpdLowThresh_Kph_f32	110.951202
k_PowerCutVehSpdLowTimeout_mS_u16	18702

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMaxAAS_Volt_f32	12.6065998
k_VBattMaxBSI_Volt_f32	30.1595001
k_VBattMaxCAV_Volt_f32	3.43829989
k_VBattMaxCMM388_Volt_f32	12.1893997
k_VBattMaxCMM_Volt_f32	10.4021997
k_VBattMaxESP_Volt_f32	24.1553001
k_VBattMinAAS_Volt_f32	29.9752998
k_VBattMinBSI_Volt_f32	3.73959994
k_VBattMinCAV_Volt_f32	15.1935997
k_VBattMinCMM388_Volt_f32	25.2458
k_VBattMinCMM_Volt_f32	0.466899991
k_VBattMinESP_Volt_f32	3.73959994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	1846
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	27583
k_VitesseVehicleBVRampValidThresh_Cnt_u16	56627
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	34502
k_VitesseVehicleBVSigValidThresh_Cnt_u16	8959
k_VitesseVehicleBVSpeedPassThresh_kph_f32	303.697296
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	14169
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	5430
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3962483456
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	15965
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2717483008
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	130
target_SrlComInput_Per1_Batt_Volt_f32.value	20.5263004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3030147840
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	12
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0678651333
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	627266304
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	386724608
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	89
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2462487296
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3230675712
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3362378496
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3528684288
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	105714432
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	146
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	192
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	239
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3921490688
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	57
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	128

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	163
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	239
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1454002944
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	17
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2849239808
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1192071936
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	175
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	183
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	251
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	422699776
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1032
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.340427816
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	851298
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	232.959305
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	55768

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	8025	8025	✔
AASNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	19711	19711	✔
AngleVolantMsgTimer_mS_M_u32	2717483008	2717483008	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	323.885498	323.885498	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	189674240	189674240	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	903521024	903521024	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	25532	25532	✔
BSINodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	62599	62599	✔
CONSANGLECPK_HwDeg_M_f32	-443.20401	-443.20401 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	62599	62599	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2717483008	2717483008	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	45082	45082	✔
CityParkInputInvalidCount_Cnt_M_u16	40449	40449	✔
CityParkInputMsgTimer_mS_M_u32	2717483008	2717483008	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2717483008	2717483008	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2717483008	2717483008	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2717483008	2717483008	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2717483008	2717483008	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2717483008	2717483008	✔
ESPNTCEnableTimer_mS_M_u32	867726080	867726080	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	40036	40036	✔
ESPNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2050	2050	✔
EffacDefaultDiagTimer_mS_M_u32[1]	6070	6070	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2717483008	2717483008	✔
ElecIntTimer_mS_M_u32[1]	457	457	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2717483008	2717483008	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2717483008	2717483008	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	64345	64345	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	33266	33266	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3921490688	3921490688	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2717483008	2717483008	✔
IgnOnTimer_mS_M_u32	2717483008	2717483008	✔
IgnTimeOff_Sec_M_u32	1584567577	1584567577	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	235	235	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	627266304	627266304	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	39	39	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	386724608	386724608	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	89	89	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2462487296	2462487296	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	168	168	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3230675712	3230675712	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3574567680	3574567680	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3528684288	3528684288	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	220	220	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	105714432	105714432	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3921490688	3921490688	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	84	84	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1454002944	1454002944	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	17	17	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2849239808	2849239808	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	132	132	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1192071936	1192071936	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	422699776	422699776	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	201.696899	201.696899	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	407.33139	407.33139	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	6.1111002	6.1111002	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	323.885498	323.885498	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	62599	62599	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1584567577	1584567577	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-443.20401	-443.20401 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	4.23199987	4.23199987	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	3	ValidityNTCProcessing	3	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.200 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	591741184
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	8249
AASNodeAbsentTimer_mS_M_u32	3661721856
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	53772
ANGLEVOLANTSigValidCount_Cnt_M_u16	64755
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	30578
AngleVolantMsgTimer_mS_M_u32	591741184
AngleVolantValidCount_Cnt_M_u16	42437
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	511.776031
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1453732096
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2074259712

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2158190848
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2961907968
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	34663
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	908189952
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	36675
CAVNodeAbsentTimer_mS_M_u32	849580288
CDD_SrlComVehSpd_Kph_G_f32	331.776001
CMM388NTCEnableTimer_mS_M_u32	920310016
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3825307904
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	28540
CMMNodeAbsentTimer_mS_M_u32	1940726016
CONSANGLECPKSigInvalidCount_Cnt_M_u16	1357
CONSANGLECPKSigValidCount_Cnt_M_u16	9028
CONSANGLECPK_Cnt_M_u16	3443
CONSANGLECPK_HwDeg_M_f32	-656.169495
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	3443
CPKVehicleSpeedMsgTimer_mS_M_u32	1719156992
CPKVehicleSpeedValidCount_Cnt_M_u16	38911
CityParkInputConsistentCount_Cnt_M_u16	21081
CityParkInputInvalidCount_Cnt_M_u16	22557
CityParkInputMsgTimer_mS_M_u32	1362372096
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2882892032
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	27341
ComputerRazGCTSigInvalidTimer_mS_M_u32	103420160
ComputerRazGCTSigValidCount_Cnt_M_u16	31466
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	55177
DMDFCTCPKSigValidCount_Cnt_M_u16	38841
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	37718
DMDRELAXECPKSigValidCount_Cnt_M_u16	445
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	16774
DateInvalidTimer_mS_M_u32	2074259712
DiagMuxOnAbsentTimer_mS_M_u32	3392930048
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2961907968
ESPNTCEnableTimer_mS_M_u32	4224610560
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	37040
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	66
EffacDefaultDiagTimer_mS_M_u32[1]	163190528
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	16
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	239853824
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	12101
EtatMTSigValidCount_Cnt_M_u16	49704
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	9367
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1550
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	15127
ISDAT4V2BSI552MsgTimer_mS_M_u32	205594880
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	39458
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	25006
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	49704
ISDATBSI3F2MsgTimer_mS_M_u32	3807510784
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	18396
ISDATBSI412MsgLenValidCount_Cnt_M_u16	50135
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	12101

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDATBSI412MsgTimer_mS_M_u32	167461120
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	3856
ISDATBSI432MsgLenValidCount_Cnt_M_u16	30532
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	9584
ISDATDIRASentFltAcc_Cnt_M_u16	26836
ISDATDIRASentTimer_mS_M_u32	1719156992
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	25257
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	42437
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	39012
ISDYN2CMMMsgTimer_mS_M_u32	1634758912
ISDYNAASChkSumInvalidCount_Cnt_M_u16	32131
ISDYNAASChkSumValidCount_Cnt_M_u16	31499
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	13472
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	8370
ISDYNAASMsgLenValidCount_Cnt_M_u16	18770
ISDYNAASMsgTimeValidCount_Cnt_M_u16	32131
ISDYNAASMsgTimer_mS_M_u32	2001129728
ISDYNABRChkSumInvalidCount_Cnt_M_u16	978
ISDYNABRChkSumValidCount_Cnt_M_u16	16737
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	44411
ISDYNABRMsgCountValidCount_Cnt_M_u16	63654
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	35752
ISDYNABRMsgLenValidCount_Cnt_M_u16	18399
ISDYNABRMsgTimeValidCount_Cnt_M_u16	3443
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	141
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	167
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	49704
ISDYNCMM208MsgTimer_mS_M_u32	1450651904
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	415
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	273
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	10107
ISDYNCMM388MsgTimer_mS_M_u32	2949927168
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	30211
ISDYNVOLChkSumValidCount_Cnt_M_u16	53370
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	61247
ISDYNVOLMsgCountValidCount_Cnt_M_u16	11247
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	29781
ISDYNVOLMsgLenValidCount_Cnt_M_u16	40877
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28540
ISDYNVOLMsgTimer_mS_M_u32	43389184
IgnOnTimer_mS_M_u32	2808631552
IgnTimeOff_Sec_M_u32	2522110929
ManVehSpd_Kph_M_f32	586.157715
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	77
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	67
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	246415616
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	216
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1298030848
PrevISDATBSI412MsgDLCError_Cnt_M_u08	136
PrevISDATBSI412MsgRxTime_MSec_M_u32	9474304
PrevISDATBSI432MsgDLCError_Cnt_M_u08	210
PrevISDATBSI432MsgRxTime_MSec_M_u32	2115137792
PrevISDATDIRAMsgTxTime_MSec_M_u32	3337916672
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	103
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3894583552
PrevISDYNAASMsgDLCError_Cnt_M_u08	237
PrevISDYNAASMsgRxTime_MSec_M_u32	4291563776
PrevISDYNABRMsgDLCError_Cnt_M_u08	162
PrevISDYNABRMsgRxTime_MSec_M_u32	524308736
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	25
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2937917696
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	252

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2168549632
PrevISDYNVOLMsgDLCError_Cnt_M_u08	7
PrevISDYNVOLMsgRxTime_MSec_M_u32	2480509184
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3887153408
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	6.89599991
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	1640
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	11144
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	57741
VitesseVehicleBVRampValidCount_Cnt_M_u16	34925
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	32945
VitesseVehicleBVSigValidCount_Cnt_M_u16	52568
VitesseVehicleBV_Kph_M_f32	212.6306
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	10107
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0
VitesseVehiculeRoues_Kph_M_f32	210.496201
k_AASNTCEnableTimeout_mS_u16	33254
k_AASNodeAbsentDiag_Cnt_str.Threshold	4467
k_AASNodeAbsentDiag_Cnt_str.PStep	60116
k_AASNodeAbsentDiag_Cnt_str.NStep	906
k_AASNodeAbsentTimeout_mS_u16	16140
k_AASNodeTimeout_mS_u16	21128
k_ABSNodeTimeout_mS_u16	30746
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	10391
k_ANGLEVOLANTSigValidThresh_Cnt_u16	30731
k_AngleVolantInvalidThresh_Cnt_u16	49806
k_AngleVolantValidThresh_Cnt_u16	22557
k_BSI552MsgTimeout_mS_u16	18878
k_BSINTCEnableTimeout_mS_u16	14056
k_BSINodeAbsentDiag_Cnt_str.Threshold	3052
k_BSINodeAbsentDiag_Cnt_str.PStep	44243
k_BSINodeAbsentDiag_Cnt_str.NStep	1848
k_BSINodeAbsentTimeout_mS_u16	26954
k_BSINodeTimeout_mS_u16	9584
k_BattOvHi_Volt_f32	11.3007002
k_BattOvLo_Volt_f32	30.9769001
k_BattUvHi_Volt_f32	25.0457001
k_BattUvLo_Volt_f32	12.9433002
k_CAVNTCEnableTimeout_mS_u16	46507
k_CAVNodeAbsentDiag_Cnt_str.Threshold	41800
k_CAVNodeAbsentDiag_Cnt_str.PStep	20653
k_CAVNodeAbsentDiag_Cnt_str.NStep	46182
k_CAVNodeAbsentTimeout_mS_u16	46073
k_CAVNodeTimeout_mS_u16	56761
k_CMM388MsgTimeout_mS_u16	34617
k_CMM388NTCEnableTimeout_mS_u16	31909
k_CMMNTCEnableTimeout_mS_u16	28154
k_CMMNodeAbsentDiag_Cnt_str.Threshold	10365
k_CMMNodeAbsentDiag_Cnt_str.PStep	62446
k_CMMNodeAbsentDiag_Cnt_str.NStep	23219
k_CMMNodeAbsentTimeout_mS_u16	32999
k_CONSANGLECPKMax_HwDeg_f32	575.796326
k_CONSANGLECPKMin_HwDeg_f32	-87.4197006
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	3707
k_CONSANGLECPKSigValidThresh_Cnt_u16	54395
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	13542
k_CPKVehicleSpeedValidThresh_Cnt_u16	29707
k_CityParkInputInvalidThresh_Cnt_u16	39088

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_CityParkInputValidThresh_Cnt_u16	21081
k_ComputerRazGCTSigValidThresh_Cnt_u16	11872
k_CptTemporelSigValidThresh_Cnt_u16	18540
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	62120
k_DMDFCTCPKSigValidThresh_Cnt_u16	61151
k_DMDFCTCPKValidCount_Cnt_u16	52367
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	39012
k_DMDRELAXECPKSigValidThresh_Cnt_u16	54996
k_DMDRelaxeConsistentThresh_Cnt_u16	64306
k_DateValidThresh_Cnt_u16	15127
k_DefaultVehSpd_Kph_f32	160.585495
k_DiagMuxOnAbsentTimeout_mS_u16	65153
k_EMNodeTimeout_mS_u16	1894
k_ESPNTCEnableTimeout_mS_u16	33199
k_ESPNodeAbsentDiag_Cnt_str.Threshold	17978
k_ESPNodeAbsentDiag_Cnt_str.PStep	37115
k_ESPNodeAbsentDiag_Cnt_str.NStep	784
k_ESPNodeAbsentTimeout_mS_u16	16655
k_EtatMTSigInvalidThresh_Cnt_u16	6837
k_EtatMTSigValidThresh_Cnt_u16	52356
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	64885
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	11193
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	46974
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	48635
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	58951
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	62832
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	15977
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	42845
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	61092
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	32999
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	38531
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	48489
k_ISDATDIRASentDiag_Cnt_str.Threshold	6549
k_ISDATDIRASentDiag_Cnt_str.PStep	63930
k_ISDATDIRASentDiag_Cnt_str.NStep	24627
k_ISDATDIRASentTimeout_mS_u16	574
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	23098
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	30578
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	14443
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	60114
k_ISDYNAASChkSumValidThresh_Cnt_u16	26721
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	990
k_ISDYNAASMsgCountValidThresh_Cnt_u16	40870
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	11366
k_ISDYNAASMsgLenValidThresh_Cnt_u16	63260
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	65075
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	11102
k_ISDYNABRChkSumValidThresh_Cnt_u16	25621
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	61031
k_ISDYNABRMsgCountValidThresh_Cnt_u16	14222
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	38524
k_ISDYNABRMsgLenValidThresh_Cnt_u16	63408
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	47953
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	51964
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	40257
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	59851
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	14604
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	41971
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	32245
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	8163
k_ISDYNVOLChkSumValidThresh_Cnt_u16	25374
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	60137
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	28917
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	58033
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	28308
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	30501
k_IgnOnTimeout_mS_u16	33359
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	89.0429993
k_PowerCutVehSpdLowThresh_Kph_f32	40.3320007
k_PowerCutVehSpdLowTimeout_mS_u16	27010
k_VBattMaxAAS_Volt_f32	21.7541008
k_VBattMaxBSI_Volt_f32	10.4558001

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMaxCAV_Volt_f32	5.58900023
k_VBattMaxCMM388_Volt_f32	30.8959007
k_VBattMaxCMM_Volt_f32	29.8451004
k_VBattMaxESP_Volt_f32	29.5552998
k_VBattMinAAS_Volt_f32	13.1494999
k_VBattMinBSI_Volt_f32	12.125
k_VBattMinCAV_Volt_f32	14.2356005
k_VBattMinCMM388_Volt_f32	0.270500004
k_VBattMinCMM_Volt_f32	20.0400009
k_VBattMinESP_Volt_f32	12.125
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	50908
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	11912
k_VitesseVehicleBVRampValidThresh_Cnt_u16	54847
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	30586
k_VitesseVehicleBVSigValidThresh_Cnt_u16	25942
k_VitesseVehicleBVSpeedPassThresh_kph_f32	13.5290003
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	30275
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	22947
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2074259712
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65036
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	163190528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	252
target_SrlComInput_Per1_Batt_Volt_f32.value	18.8777008
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3425624320
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	220
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.108573854
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	941248768
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3835621632
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2931003648
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2119708928
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	999084288
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3461443840
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	514199808
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	108
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	134
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	177
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	182
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3613208832
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	226

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	227
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	988369152
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2632839424
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3699544320
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	145
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2725798144
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3499
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.239259362
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	78841
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	89.1662979
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	65162

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	591741184	591741184	✔
AASNTCsEnabled_Cnt_M_lgc	1	1	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	163190528	163190528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	511.776031	511.776031	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	3052	3052	✔
BSINodeAbsentTimer_mS_M_u32	163190528	163190528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	5321	5321	✔
CMMNodeAbsentTimer_mS_M_u32	3461443840	3461443840	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	3443	3443	✔
CONSANGLECPK_HwDeg_M_f32	-656.169495	-656.169495 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2	2	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	163190528	163190528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	163190528	163190528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	163190528	163190528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	163190528	163190528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	163190528	163190528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	163190528	163190528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	163190528	163190528	✔
ESPNTCEnableTimer_mS_M_u32	4224610560	4224610560	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	17978	17978	✔
ESPNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	66	66	✔
EffacDefaultDiagTimer_mS_M_u32[1]	163190528	163190528	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	163190528	163190528	✔
ElecIntTimer_mS_M_u32[1]	16	16	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	163190528	163190528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	163190528	163190528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	514199808	514199808	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	1	1	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3613208832	3613208832	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	163190528	163190528	✔
IgnOnTimer_mS_M_u32	2808631552	2808631552	✔
IgnTimeOff_Sec_M_u32	2522110929	2522110929	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	220	220	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	941248768	941248768	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3835621632	3835621632	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	239	239	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2931003648	2931003648	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	31	31	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2119708928	2119708928	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3337916672	3337916672	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	83	83	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3461443840	3461443840	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	40	40	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	514199808	514199808	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3613208832	3613208832	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	172	172	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	988369152	988369152	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	118	118	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2632839424	2632839424	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3699544320	3699544320	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2725798144	2725798144	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	6.89599991	6.89599991	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	212.6306	212.6306	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VitesseVehiculeRoues_Kph_M_f32	210.496201	210.496201	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	511.776031	511.776031	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	3443	3443	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2522110929	2522110929	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-656.169495	-656.169495 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	160.585495	160.585495	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	4	ValidityNTCProcessing	4	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.201 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4229103616
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	30517
AASNodeAbsentTimer_mS_M_u32	1138651136
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	52158
ANGLEVOLANTSigValidCount_Cnt_M_u16	50630
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	38282
AngleVolantMsgTimer_mS_M_u32	4229103616
AngleVolantValidCount_Cnt_M_u16	7442
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	746.018555
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1370501120
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1958391808
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2222497792

© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1136746496
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	55213
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2113740800
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	31383
CAVNodeAbsentTimer_mS_M_u32	3946319872
CDD_SrlComVehSpd_Kph_G_f32	453.582886
CMM388NTCEnableTimer_mS_M_u32	3415363584
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3474853888
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	10668
CMMNodeAbsentTimer_mS_M_u32	39542784
CONSANGLECPKSigInvalidCount_Cnt_M_u16	9467
CONSANGLECPKSigValidCount_Cnt_M_u16	34260
CONSANGLECPK_Cnt_M_u16	17223
CONSANGLECPK_HwDeg_M_f32	-760.413391
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17223
CPKVehicleSpeedMsgTimer_mS_M_u32	3195666432
CPKVehicleSpeedValidCount_Cnt_M_u16	22509
CityParkInputConsistentCount_Cnt_M_u16	26454
CityParkInputInvalidCount_Cnt_M_u16	46857
CityParkInputMsgTimer_mS_M_u32	941248768
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	522350592
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	59257
ComputerRazGCTSigInvalidTimer_mS_M_u32	2862911488
ComputerRazGCTSigValidCount_Cnt_M_u16	29091
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	59589
DMDFCTCPKSigValidCount_Cnt_M_u16	17142
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	12256
DMDRELAXECPKSigValidCount_Cnt_M_u16	24424
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	37968
DateInvalidTimer_mS_M_u32	1958391808
DiagMuxOnAbsentTimer_mS_M_u32	1378795520
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1136746496
ESPNTCEnableTimer_mS_M_u32	1396142080
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	28881
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	201
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	9
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	494870528
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	23379
EtatMTSigValidCount_Cnt_M_u16	3432
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	28445
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	34166
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20700
ISDAT4V2BSI552MsgTimer_mS_M_u32	2292146176
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	27193
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	7766
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	3432
ISDATBSI3F2MsgTimer_mS_M_u32	1611448320
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	54798
ISDATBSI412MsgLenValidCount_Cnt_M_u16	11483
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	23379
ISDATBSI412MsgTimer_mS_M_u32	2683371520
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	39664

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDATBSI432MsgLenValidCount_Cnt_M_u16	3349
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	44048
ISDATDIRASentFltAcc_Cnt_M_u16	29156
ISDATDIRASentTimer_mS_M_u32	3195666432
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	39845
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	7442
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	53812
ISDYN2CMMMsgTimer_mS_M_u32	709980160
ISDYNAASChkSumInvalidCount_Cnt_M_u16	1879
ISDYNAASChkSumValidCount_Cnt_M_u16	2432
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	40065
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	16970
ISDYNAASMsgLenValidCount_Cnt_M_u16	9003
ISDYNAASMsgTimeValidCount_Cnt_M_u16	1879
ISDYNAASMsgTimer_mS_M_u32	3125694464
ISDYNABRChkSumInvalidCount_Cnt_M_u16	9708
ISDYNABRChkSumValidCount_Cnt_M_u16	34813
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	14513
ISDYNABRMsgCountValidCount_Cnt_M_u16	48303
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	48618
ISDYNABRMsgLenValidCount_Cnt_M_u16	17411
ISDYNABRMsgTimeValidCount_Cnt_M_u16	17223
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	157
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	199
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	3432
ISDYNCMM208MsgTimer_mS_M_u32	3594334208
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	479
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	305
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	61424
ISDYNCMM388MsgTimer_mS_M_u32	648400896
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	10969
ISDYNVOLChkSumValidCount_Cnt_M_u16	54834
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	63907
ISDYNVOLMsgCountValidCount_Cnt_M_u16	56916
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	39394
ISDYNVOLMsgLenValidCount_Cnt_M_u16	21147
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	10668
ISDYNVOLMsgTimer_mS_M_u32	1700827136
IgnOnTimer_mS_M_u32	2414465024
IgnTimeOff_Sec_M_u32	202236160
ManVehSpd_Kph_M_f32	584.572815
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	93
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	143
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1423097856
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	247
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3393691648
PrevISDATBSI412MsgDLCError_Cnt_M_u08	183
PrevISDATBSI412MsgRxTime_MSec_M_u32	1970343936
PrevISDATBSI432MsgDLCError_Cnt_M_u08	233
PrevISDATBSI432MsgRxTime_MSec_M_u32	3698028544
PrevISDATDIRAMsgTxTime_MSec_M_u32	2990870528
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	108
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1526390784
PrevISDYNAASMsgDLCError_Cnt_M_u08	52
PrevISDYNAASMsgRxTime_MSec_M_u32	3317600256
PrevISDYNABRMsgDLCError_Cnt_M_u08	214
PrevISDYNABRMsgRxTime_MSec_M_u32	2288111616
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	98
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1003196416
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	26
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1323200512
PrevISDYNVOLMsgDLCError_Cnt_M_u08	130

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevISDYNVOLMsgRxTime_MSec_M_u32	529928192
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1590624256
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	612.925781
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	59688
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	54409
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	11193
VitesseVehicleBVRampValidCount_Cnt_M_u16	37338
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	37839
VitesseVehicleBVSigValidCount_Cnt_M_u16	10391
VitesseVehicleBV_Kph_M_f32	270.0513
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	61424
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	65535
VitesseVehiculeRoues_Kph_M_f32	121.343102
k_AASNTCEnableTimeout_mS_u16	29166
k_AASNodeAbsentDiag_Cnt_str.Threshold	47636
k_AASNodeAbsentDiag_Cnt_str.PStep	34578
k_AASNodeAbsentDiag_Cnt_str.NStep	62563
k_AASNodeAbsentTimeout_mS_u16	11581
k_AASNodeTimeout_mS_u16	24457
k_ABSNodeTimeout_mS_u16	35602
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	10843
k_ANGLEVOLANTSigValidThresh_Cnt_u16	59072
k_AngleVolantInvalidThresh_Cnt_u16	54071
k_AngleVolantValidThresh_Cnt_u16	46857
k_BSI552MsgTimeout_mS_u16	12264
k_BSINTCEnableTimeout_mS_u16	33640
k_BSINodeAbsentDiag_Cnt_str.Threshold	3692
k_BSINodeAbsentDiag_Cnt_str.PStep	43971
k_BSINodeAbsentDiag_Cnt_str.NStep	2216
k_BSINodeAbsentTimeout_mS_u16	8194
k_BSINodeTimeout_mS_u16	44048
k_BattOvHi_Volt_f32	9.27910042
k_BattOvLo_Volt_f32	27.4062996
k_BattUvHi_Volt_f32	12.0334997
k_BattUvLo_Volt_f32	0.955299973
k_CAVNTCEnableTimeout_mS_u16	22111
k_CAVNodeAbsentDiag_Cnt_str.Threshold	14101
k_CAVNodeAbsentDiag_Cnt_str.PStep	13590
k_CAVNodeAbsentDiag_Cnt_str.NStep	2667
k_CAVNodeAbsentTimeout_mS_u16	25717
k_CAVNodeTimeout_mS_u16	19383
k_CMM388MsgTimeout_mS_u16	16949
k_CMM388NTCEnableTimeout_mS_u16	4593
k_CMMNTCEnableTimeout_mS_u16	20145
k_CMMNodeAbsentDiag_Cnt_str.Threshold	62414
k_CMMNodeAbsentDiag_Cnt_str.PStep	42715
k_CMMNodeAbsentDiag_Cnt_str.NStep	22076
k_CMMNodeAbsentTimeout_mS_u16	28269
k_CONSANGLECPKMax_HwDeg_f32	334.590912
k_CONSANGLECPKMin_HwDeg_f32	-30.7777004
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	15088
k_CONSANGLECPKSigValidThresh_Cnt_u16	50097
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	45167
k_CPKVehicleSpeedValidThresh_Cnt_u16	52609
k_CityParkInputInvalidThresh_Cnt_u16	24402
k_CityParkInputValidThresh_Cnt_u16	26454
k_ComputerRazGCTSigValidThresh_Cnt_u16	9599

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_CptTemporelSigValidThresh_Cnt_u16	57884
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	35050
k_DMDFCTCPKSigValidThresh_Cnt_u16	20227
k_DMDFCTCPKValidCount_Cnt_u16	43061
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	53812
k_DMDRELAXECPKSigValidThresh_Cnt_u16	45477
k_DMDRelaxeConsistentThresh_Cnt_u16	15499
k_DateValidThresh_Cnt_u16	20700
k_DefaultVehSpd_Kph_f32	14.6294003
k_DiagMuxOnAbsentTimeout_mS_u16	10269
k_EMNodeTimeout_mS_u16	49840
k_ESPNTCEnableTimeout_mS_u16	21331
k_ESPNodeAbsentDiag_Cnt_str.Threshold	62971
k_ESPNodeAbsentDiag_Cnt_str.PStep	11352
k_ESPNodeAbsentDiag_Cnt_str.NStep	60169
k_ESPNodeAbsentTimeout_mS_u16	52725
k_EtatMTSigInvalidThresh_Cnt_u16	11587
k_EtatMTSigValidThresh_Cnt_u16	12948
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	21186
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	45751
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	3047
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	41646
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	13451
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	7506
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	45285
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	8394
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	19508
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	47339
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	49880
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	14950
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	55976
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	59379
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	38282
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	7967
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	28908
k_ISDYNAASChkSumValidThresh_Cnt_u16	4861
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	41030
k_ISDYNAASMsgCountValidThresh_Cnt_u16	51119
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	64560
k_ISDYNAASMsgLenValidThresh_Cnt_u16	49613
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	62536
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	14024
k_ISDYNABRChkSumValidThresh_Cnt_u16	18273
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	41645
k_ISDYNABRMsgCountValidThresh_Cnt_u16	16885
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46252
k_ISDYNABRMsgLenValidThresh_Cnt_u16	15313
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	33452
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	60268
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	43487
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	26048
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	38590
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	53446
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	42369
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	10745
k_ISDYNVOLChkSumValidThresh_Cnt_u16	11014
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	34342
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	18753
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	61711
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	47140
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	21682
k_IgnOnTimeout_mS_u16	45749
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	161.756805
k_PowerCutVehSpdLowThresh_Kph_f32	219.889603
k_PowerCutVehSpdLowTimeout_mS_u16	11034
k_VBattMaxAAS_Volt_f32	9.29520035
k_VBattMaxBSI_Volt_f32	28.8171997
k_VBattMaxCAV_Volt_f32	18.5709991
k_VBattMaxCMM388_Volt_f32	23.1520004

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMaxCMM_Volt_f32	30.5259991
k_VBattMaxESP_Volt_f32	25.6320992
k_VBattMinAAS_Volt_f32	30.3073997
k_VBattMinBSI_Volt_f32	3.21659994
k_VBattMinCAV_Volt_f32	31.1417999
k_VBattMinCMM388_Volt_f32	0.914099991
k_VBattMinCMM_Volt_f32	13.8895998
k_VBattMinESP_Volt_f32	3.21659994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	43533
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	64970
k_VitesseVehicleBVRampValidThresh_Cnt_u16	17571
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	57650
k_VitesseVehicleBVSigValidThresh_Cnt_u16	25183
k_VitesseVehicleBVSpeedPassThresh_kph_f32	585.976196
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	50583
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	30264
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1958391808
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	26
target_SrlComInput_Per1_Batt_Volt_f32.value	19.2900009
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	802562048
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	50
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.797768593
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	634638336
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	191
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2059792384
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3070758912
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	10
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	580530176
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	92033024
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2813227008
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	159
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1362137088
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	131
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	214
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1804283904
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	36
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	156
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	157
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	184

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	426168320
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1306062848
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	698028032
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	210
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3002703872
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3708
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.606383681
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	390948
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	83.637001
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	2242

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	38284	38284	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	746.018555	746.018555	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1370501120	1370501120	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2222497792	2222497792	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	1136746496	1136746496	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	14101	14101	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3474853888	3474853888	✔
CMMNTCsEnabled_Cnt_M_lgc	1	1	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	17223	17223	✔
CONSANGLECPK_HwDeg_M_f32	-760.413391	-760.413391 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17225	17225	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2006148864	2006148864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	26454	26454	✔
CityParkInputInvalidCount_Cnt_M_u16	46857	46857	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1958391808	1958391808	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	1396142080	1396142080	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	62971	62971	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔
EffacDefaultDiagTimer_mS_M_u32[1]	201	201	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	8	8	✔
ElecIntTimer_mS_M_u32[1]	9	9	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	23379	23379	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	28445	28445	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	634638336	634638336	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	27194	27194	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2059792384	2059792384	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	39665	39665	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	580530176	580530176	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11170	11170	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	39846	39846	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2813227008	2813227008	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	9709	9709	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	14514	14514	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1804283904	1804283904	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	158	158	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	426168320	426168320	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	2006148864	2006148864	✔
IgnTimeOff_Sec_M_u32	202236160	202236160	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	99	99	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	634638336	634638336	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	191	191	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2059792384	2059792384	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	223	223	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3070758912	3070758912	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	10	10	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	580530176	580530176	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2990870528	2990870528	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2813227008	2813227008	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	159	159	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1362137088	1362137088	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	214	214	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1804283904	1804283904	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	239	239	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	426168320	426168320	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1306062848	1306062848	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	698028032	698028032	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3002703872	3002703872	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	612.925781	612.925781	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	270.0513	270.0513	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	121.343102	121.343102	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	746.018555	746.018555	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	17223	17223	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	202236160	202236160	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-760.413391	-760.413391 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	14.6294003	14.6294003	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	4	ValidityNTCProcessing	4	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.202 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3680879360
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	5118
AASNodeAbsentTimer_mS_M_u32	3183702784
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	55396
ANGLEVOLANTSigValidCount_Cnt_M_u16	31241
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	19711
AngleVolantMsgTimer_mS_M_u32	3680879360
AngleVolantValidCount_Cnt_M_u16	32486
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	675.756958
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	189674240
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3962483456
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1622467328
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	903521024
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	12439
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	640115456
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	6233
CAVNodeAbsentTimer_mS_M_u32	3057029888
CDD_SrlComVehSpd_Kph_G_f32	202.853607
CMM388NTCEnableTimer_mS_M_u32	1311232768
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	579113728
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	7129
CMMNodeAbsentTimer_mS_M_u32	3792478976
CONSANGLECPKSigInvalidCount_Cnt_M_u16	62379
CONSANGLECPKSigValidCount_Cnt_M_u16	41184
CONSANGLECPK_Cnt_M_u16	62599
CONSANGLECPK_HwDeg_M_f32	-443.20401
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	62599
CPKVehicleSpeedMsgTimer_mS_M_u32	4029727488
CPKVehicleSpeedValidCount_Cnt_M_u16	47550
CityParkInputConsistentCount_Cnt_M_u16	45082
CityParkInputInvalidCount_Cnt_M_u16	40449
CityParkInputMsgTimer_mS_M_u32	634638336
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1006072576
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	54066
ComputerRazGCTSigInvalidTimer_mS_M_u32	3388019456
ComputerRazGCTSigValidCount_Cnt_M_u16	1331
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	63693
DMDFCTCPKSigValidCount_Cnt_M_u16	6650
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	46078
DMDRELAXECPKSigValidCount_Cnt_M_u16	46371
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	14764
DateInvalidTimer_mS_M_u32	3962483456
DiagMuxOnAbsentTimer_mS_M_u32	4161962752
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	903521024
ESPNTCEnableTimer_mS_M_u32	867726080
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	17963
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	2050
EffacDefaultDiagTimer_mS_M_u32[1]	6070
ElecIntCount_Cnt_M_u08	2
ElecIntTimer_mS_M_u32[0]	56

Name	Input Value
ElecIntTimer_mS_M_u32[1]	457
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3483460352
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	13284
EtatMTSigValidCount_Cnt_M_u16	56677
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	7493
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	43514
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	2120
ISDAT4V2BSI552MsgTimer_mS_M_u32	1598071552
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	6320
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	56346
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	56677
ISDATBSI3F2MsgTimer_mS_M_u32	3329786624
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	30260
ISDATBSI412MsgLenValidCount_Cnt_M_u16	4493
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	13284
ISDATBSI412MsgTimer_mS_M_u32	3888890624
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	55309
ISDATBSI432MsgLenValidCount_Cnt_M_u16	33119
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	42990
ISDATDIRASentFltAcc_Cnt_M_u16	42610
ISDATDIRASentTimer_mS_M_u32	4029727488
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	58221
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	32486
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	47232
ISDYN2CMMMsgTimer_mS_M_u32	2523558656
ISDYNAASChkSumInvalidCount_Cnt_M_u16	27544
ISDYNAASChkSumValidCount_Cnt_M_u16	29917
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	31897
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	19776
ISDYNAASMsgLenValidCount_Cnt_M_u16	39517
ISDYNAASMsgTimeValidCount_Cnt_M_u16	27544
ISDYNAASMsgTimer_mS_M_u32	1911804672
ISDYNABRChkSumInvalidCount_Cnt_M_u16	64345
ISDYNABRChkSumValidCount_Cnt_M_u16	34022
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	37834
ISDYNABRMsgCountValidCount_Cnt_M_u16	55120
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	42206
ISDYNABRMsgLenValidCount_Cnt_M_u16	57939
ISDYNABRMsgTimeValidCount_Cnt_M_u16	62599
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	703
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1291
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	56677
ISDYNCMM208MsgTimer_mS_M_u32	4054266624
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2663
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1397
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	65100
ISDYNCMM388MsgTimer_mS_M_u32	3941421824
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	55825
ISDYNVOLChkSumValidCount_Cnt_M_u16	42950
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	48691
ISDYNVOLMsgCountValidCount_Cnt_M_u16	16352
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	20216
ISDYNVOLMsgLenValidCount_Cnt_M_u16	29837
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	7129
ISDYNVOLMsgTimer_mS_M_u32	2310869760
IgnOnTimer_mS_M_u32	3206632192
IgnTimeOff_Sec_M_u32	1584567577
ManVehSpd_Kph_M_f32	409.178589
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	227
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	4

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	67
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2150007552
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	149
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2336744192
PrevISDATBSI412MsgDLCError_Cnt_M_u08	229
PrevISDATBSI412MsgRxTime_MSec_M_u32	999002880
PrevISDATBSI432MsgDLCError_Cnt_M_u08	33
PrevISDATBSI432MsgRxTime_MSec_M_u32	1746694912
PrevISDATDIRAMsgTxTime_MSec_M_u32	3574567680
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	211
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3056476928
PrevISDYNAASMsgDLCError_Cnt_M_u08	111
PrevISDYNAASMsgRxTime_MSec_M_u32	1621299968
PrevISDYNABRMsgDLCError_Cnt_M_u08	73
PrevISDYNABRMsgRxTime_MSec_M_u32	3048821504
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	206
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1920733952
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	130
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2630054656
PrevISDYNVOLMsgDLCError_Cnt_M_u08	171
PrevISDYNVOLMsgRxTime_MSec_M_u32	287085312
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2737947392
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	201.696899
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	20646
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	32323
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	3315
VitesseVehicleBVRampValidCount_Cnt_M_u16	51792
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	1073
VitesseVehicleBVSigValidCount_Cnt_M_u16	54678
VitesseVehicleBV_Kph_M_f32	407.33139
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	65100
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	5462
VitesseVehiculeRoues_Kph_M_f32	6.1111002
k_AASNTCEnableTimeout_mS_u16	50322
k_AASNodeAbsentDiag_Cnt_str.Threshold	8025
k_AASNodeAbsentDiag_Cnt_str.PStep	40741
k_AASNodeAbsentDiag_Cnt_str.NStep	23056
k_AASNodeAbsentTimeout_mS_u16	47717
k_AASNodeTimeout_mS_u16	56643
k_ABSNodeTimeout_mS_u16	34278
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	38348
k_ANGLEVOLANTSigValidThresh_Cnt_u16	24670
k_AngleVolantInvalidThresh_Cnt_u16	14073
k_AngleVolantValidThresh_Cnt_u16	40449
k_BSI552MsgTimeout_mS_u16	18981
k_BSINTCEnableTimeout_mS_u16	65189
k_BSINodeAbsentDiag_Cnt_str.Threshold	25532
k_BSINodeAbsentDiag_Cnt_str.PStep	34689
k_BSINodeAbsentDiag_Cnt_str.NStep	14774
k_BSINodeAbsentTimeout_mS_u16	36247
k_BSINodeTimeout_mS_u16	42990
k_BattOvHi_Volt_f32	5.2809
k_BattOvLo_Volt_f32	11.9322004
k_BattUvHi_Volt_f32	27.5499992
k_BattUvLo_Volt_f32	7.94029999
k_CAVNTCEnableTimeout_mS_u16	38911
k_CAVNodeAbsentDiag_Cnt_str.Threshold	43612

Name	Input Value
k_CAVNodeAbsentDiag_Cnt_str.PStep	33532
k_CAVNodeAbsentDiag_Cnt_str.NStep	50919
k_CAVNodeAbsentTimeout_mS_u16	21183
k_CAVNodeTimeout_mS_u16	28535
k_CMM388MsgTimeout_mS_u16	45822
k_CMM388NTCEnableTimeout_mS_u16	13258
k_CMMNTCEnableTimeout_mS_u16	19272
k_CMMNodeAbsentDiag_Cnt_str.Threshold	62640
k_CMMNodeAbsentDiag_Cnt_str.PStep	29375
k_CMMNodeAbsentDiag_Cnt_str.NStep	51731
k_CMMNodeAbsentTimeout_mS_u16	58006
k_CONSANGLECPKMax_HwDeg_f32	624.185791
k_CONSANGLECPKMin_HwDeg_f32	-570.65863
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	7500
k_CONSANGLECPKSigValidThresh_Cnt_u16	62154
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	657
k_CPKVehicleSpeedValidThresh_Cnt_u16	7131
k_CityParkInputInvalidThresh_Cnt_u16	26407
k_CityParkInputValidThresh_Cnt_u16	45082
k_ComputerRazGCTSigValidThresh_Cnt_u16	32478
k_CptTemporelSigValidThresh_Cnt_u16	10440
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	17374
k_DMDFCTCPKSigValidThresh_Cnt_u16	49491
k_DMDFCTCPKValidCount_Cnt_u16	57087
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	47232
k_DMDRELAXECPKSigValidThresh_Cnt_u16	18925
k_DMDRelaxeConsistentThresh_Cnt_u16	49467
k_DateValidThresh_Cnt_u16	2120
k_DefaultVehSpd_Kph_f32	4.23199987
k_DiagMuxOnAbsentTimeout_mS_u16	7685
k_EMNodeTimeout_mS_u16	11916
k_ESPNTCEnableTimeout_mS_u16	32293
k_ESPNodeAbsentDiag_Cnt_str.Threshold	40036
k_ESPNodeAbsentDiag_Cnt_str.PStep	46639
k_ESPNodeAbsentDiag_Cnt_str.NStep	47261
k_ESPNodeAbsentTimeout_mS_u16	58366
k_EtatMTSigInvalidThresh_Cnt_u16	340
k_EtatMTSigValidThresh_Cnt_u16	41249
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	10136
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	18297
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	18023
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	33617
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	44411
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	45160
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	43566
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	23104
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	54337
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	9115
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	9620
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	64043
k_ISDATDIRASentDiag_Cnt_str.Threshold	25239
k_ISDATDIRASentDiag_Cnt_str.PStep	16638
k_ISDATDIRASentDiag_Cnt_str.NStep	16248
k_ISDATDIRASentTimeout_mS_u16	52517
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	25988
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	19711
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	19137
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	6745
k_ISDYNAASChkSumValidThresh_Cnt_u16	58342
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	7371
k_ISDYNAASMsgCountValidThresh_Cnt_u16	46672
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	34957
k_ISDYNAASMsgLenValidThresh_Cnt_u16	50807
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	22470
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	12868
k_ISDYNABRChkSumValidThresh_Cnt_u16	53305
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	53143
k_ISDYNABRMsgCountValidThresh_Cnt_u16	33148
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	31449
k_ISDYNABRMsgLenValidThresh_Cnt_u16	58667
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	23383
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	23002
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	32449

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	26270
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	30564
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	22793
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	45721
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	58995
k_ISDYNVOLChkSumValidThresh_Cnt_u16	33548
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	39468
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	20762
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	25264
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	52529
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	54470
k_IgnOnTimeout_mS_u16	15423
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	21.3497009
k_PowerCutVehSpdLowThresh_Kph_f32	110.951202
k_PowerCutVehSpdLowTimeout_mS_u16	18702
k_VBattMaxAAS_Volt_f32	12.6065998
k_VBattMaxBSI_Volt_f32	30.1595001
k_VBattMaxCAV_Volt_f32	3.43829989
k_VBattMaxCMM388_Volt_f32	12.1893997
k_VBattMaxCMM_Volt_f32	10.4021997
k_VBattMaxESP_Volt_f32	24.1553001
k_VBattMinAAS_Volt_f32	29.9752998
k_VBattMinBSI_Volt_f32	3.73959994
k_VBattMinCAV_Volt_f32	15.1935997
k_VBattMinCMM388_Volt_f32	25.2458
k_VBattMinCMM_Volt_f32	0.466899991
k_VBattMinESP_Volt_f32	3.73959994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	1846
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	27583
k_VitesseVehicleBVRampValidThresh_Cnt_u16	56627
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	34502
k_VitesseVehicleBVSigValidThresh_Cnt_u16	8959
k_VitesseVehicleBVSpeedPassThresh_kph_f32	303.697296
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	14169
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	5430
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3962483456
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	15965
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2717483008
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	130
target_SrlComInput_Per1_Batt_Volt_f32.value	20.5263004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3030147840
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	12
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0678651333
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	627266304
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	386724608
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	89
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2462487296
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3230675712
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3362378496
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3528684288

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	105714432
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	146
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	192
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	239
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3921490688
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	57
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	128
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	163
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	239
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1454002944
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	17
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2849239808
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1192071936
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	175
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	183
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	251
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	422699776
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2030
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.340427816
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	901649
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	232.959305
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	55768

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	8025	8025	✔
AASNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	19711	19711	✔
AngleVolantMsgTimer_mS_M_u32	2717483008	2717483008	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	675.756958	675.756958	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	189674240	189674240	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	903521024	903521024	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	25532	25532	✔
BSINodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	62599	62599	✔
CONSANGLECPK_HwDeg_M_f32	-443.20401	-443.20401 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	62599	62599	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2717483008	2717483008	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	45082	45082	✔
CityParkInputInvalidCount_Cnt_M_u16	40449	40449	✔
CityParkInputMsgTimer_mS_M_u32	2717483008	2717483008	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2717483008	2717483008	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2717483008	2717483008	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2717483008	2717483008	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2717483008	2717483008	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2717483008	2717483008	✔
ESPNTCEnableTimer_mS_M_u32	867726080	867726080	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	40036	40036	✔
ESPNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2050	2050	✔
EffacDefaultDiagTimer_mS_M_u32[1]	6070	6070	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2717483008	2717483008	✔
ElecIntTimer_mS_M_u32[1]	457	457	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2717483008	2717483008	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2717483008	2717483008	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	64345	64345	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	37835	37835	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3921490688	3921490688	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2717483008	2717483008	✔
IgnOnTimer_mS_M_u32	2717483008	2717483008	✔
IgnTimeOff_Sec_M_u32	1584567577	1584567577	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	235	235	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	627266304	627266304	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	39	39	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	386724608	386724608	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	89	89	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2462487296	2462487296	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	168	168	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3230675712	3230675712	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3574567680	3574567680	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3528684288	3528684288	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	220	220	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	105714432	105714432	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3921490688	3921490688	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	84	84	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1454002944	1454002944	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	17	17	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2849239808	2849239808	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	132	132	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1192071936	1192071936	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	422699776	422699776	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	201.696899	201.696899	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	407.33139	407.33139	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	6.1111002	6.1111002	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	675.756958	675.756958	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	62599	62599	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1584567577	1584567577	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-443.20401	-443.20401 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	4.23199987	4.23199987	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	3	ValidityNTCProcessing	3	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.203 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3259201280
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	53891
AASNodeAbsentTimer_mS_M_u32	2028480256
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	32498
ANGLEVOLANTSigValidCount_Cnt_M_u16	37686
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	11220
AngleVolantMsgTimer_mS_M_u32	3259201280
AngleVolantValidCount_Cnt_M_u16	47134
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	642.178711
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2647582464
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1826055936
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2320275200
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	121526016
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	22293
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1267144448
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	36185
CAVNodeAbsentTimer_mS_M_u32	4015343360
CDD_SrlComVehSpd_Kph_G_f32	309.960602
CMM388NTCEnableTimer_mS_M_u32	648709888
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2483242752
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	56316
CMMNodeAbsentTimer_mS_M_u32	588273408
CONSANGLECPKSigInvalidCount_Cnt_M_u16	31829
CONSANGLECPKSigValidCount_Cnt_M_u16	14633
CONSANGLECPK_Cnt_M_u16	57600
CONSANGLECPK_HwDeg_M_f32	-548.324097
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	57600
CPKVehicleSpeedMsgTimer_mS_M_u32	3330176768
CPKVehicleSpeedValidCount_Cnt_M_u16	34312
CityParkInputConsistentCount_Cnt_M_u16	35218
CityParkInputInvalidCount_Cnt_M_u16	33644
CityParkInputMsgTimer_mS_M_u32	2384827392
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2807834368
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	37367
ComputerRazGCTSigInvalidTimer_mS_M_u32	4116170496
ComputerRazGCTSigValidCount_Cnt_M_u16	18043
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	65016
DMDFCTCPKSigValidCount_Cnt_M_u16	60485
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	6828
DMDRELAXECPKSigValidCount_Cnt_M_u16	26224
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	62118
DateInvalidTimer_mS_M_u32	1826055936
DiagMuxOnAbsentTimer_mS_M_u32	283916032
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	121526016
ESPNTCEnableTimer_mS_M_u32	1533880064
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	61100
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	1
EffacDefaultDiagTimer_mS_M_u32[1]	15
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	10

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ElecIntTimer_mS_M_u32[1]	100
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	186717952
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	27450
EtatMTSigValidCount_Cnt_M_u16	48154
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	50703
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	14947
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	45811
ISDAT4V2BSI552MsgTimer_mS_M_u32	8673024
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	62989
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	63829
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	48154
ISDATBSI3F2MsgTimer_mS_M_u32	1060255488
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	20628
ISDATBSI412MsgLenValidCount_Cnt_M_u16	42701
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	27450
ISDATBSI412MsgTimer_mS_M_u32	2391373568
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	43120
ISDATBSI432MsgLenValidCount_Cnt_M_u16	59936
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	35710
ISDATDIRASentFltAcc_Cnt_M_u16	21314
ISDATDIRASentTimer_mS_M_u32	3330176768
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	22470
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	47134
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	38299
ISDYN2CMMMsgTimer_mS_M_u32	901719808
ISDYNAASChkSumInvalidCount_Cnt_M_u16	43581
ISDYNAASChkSumValidCount_Cnt_M_u16	34850
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	60865
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	31344
ISDYNAASMsgLenValidCount_Cnt_M_u16	20396
ISDYNAASMsgTimeValidCount_Cnt_M_u16	43581
ISDYNAASMsgTimer_mS_M_u32	976652032
ISDYNABRChkSumInvalidCount_Cnt_M_u16	13421
ISDYNABRChkSumValidCount_Cnt_M_u16	10521
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	23648
ISDYNABRMsgCountValidCount_Cnt_M_u16	40581
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	32120
ISDYNABRMsgLenValidCount_Cnt_M_u16	56972
ISDYNABRMsgTimeValidCount_Cnt_M_u16	57600
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	85
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	55
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	48154
ISDYNCMM208MsgTimer_mS_M_u32	1341646592
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	191
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	161
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0
ISDYNCMM388MsgTimer_mS_M_u32	4180150016
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	17051
ISDYNVOLChkSumValidCount_Cnt_M_u16	18415
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	21310
ISDYNVOLMsgCountValidCount_Cnt_M_u16	51723
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	51081
ISDYNVOLMsgLenValidCount_Cnt_M_u16	39613
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	56316
ISDYNVOLMsgTimer_mS_M_u32	1692649216
IgnOnTimer_mS_M_u32	1570506496
IgnTimeOff_Sec_M_u32	2450823047
ManVehSpd_Kph_M_f32	508.664093
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	21
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	9

Name	Input Value
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	123
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1598043904
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	69
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4073690880
PrevISDATBSI412MsgDLCError_Cnt_M_u08	242
PrevISDATBSI412MsgRxTime_MSec_M_u32	2939832064
PrevISDATBSI432MsgDLCError_Cnt_M_u08	214
PrevISDATBSI432MsgRxTime_MSec_M_u32	789653248
PrevISDATDIRAMsgTxTime_MSec_M_u32	2180925184
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	179
PrevISDYN2CMMMsgRxTime_MSec_M_u32	967431936
PrevISDYNAASMsgDLCError_Cnt_M_u08	60
PrevISDYNAASMsgRxTime_MSec_M_u32	1135200000
PrevISDYNABRMsgDLCError_Cnt_M_u08	109
PrevISDYNABRMsgRxTime_MSec_M_u32	3820226304
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	58
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3109209856
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	0
PrevISDYNCMM388MsgRxTime_MSec_M_u32	132654848
PrevISDYNVOLMsgDLCError_Cnt_M_u08	66
PrevISDYNVOLMsgRxTime_MSec_M_u32	2451261184
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3117381376
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	482.903809
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	28086
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	19314
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	4627
VitesseVehicleBVRampValidCount_Cnt_M_u16	27535
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	27343
VitesseVehicleBVSigValidCount_Cnt_M_u16	39635
VitesseVehicleBV_Kph_M_f32	556.461121
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	41728
VitesseVehiculeRoues_Kph_M_f32	28.5517006
k_AASNTCEnableTimeout_mS_u16	9339
k_AASNodeAbsentDiag_Cnt_str.Threshold	31896
k_AASNodeAbsentDiag_Cnt_str.PStep	3944
k_AASNodeAbsentDiag_Cnt_str.NStep	53340
k_AASNodeAbsentTimeout_mS_u16	15181
k_AASNodeTimeout_mS_u16	23154
k_ABSNodeTimeout_mS_u16	29409
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	25055
k_ANGLEVOLANTSigValidThresh_Cnt_u16	10447
k_AngleVolantInvalidThresh_Cnt_u16	32730
k_AngleVolantValidThresh_Cnt_u16	33644
k_BSI552MsgTimeout_mS_u16	50635
k_BSINTCEnableTimeout_mS_u16	24200
k_BSINodeAbsentDiag_Cnt_str.Threshold	812
k_BSINodeAbsentDiag_Cnt_str.PStep	45195
k_BSINodeAbsentDiag_Cnt_str.NStep	560
k_BSINodeAbsentTimeout_mS_u16	7148
k_BSINodeTimeout_mS_u16	35710
k_BattOvHi_Volt_f32	29.1256008
k_BattOvLo_Volt_f32	29.9862003
k_BattUvHi_Volt_f32	25.3703995
k_BattUvLo_Volt_f32	2.95129991
k_CAVNTCEnableTimeout_mS_u16	64714
k_CAVNodeAbsentDiag_Cnt_str.Threshold	49920

Name	Input Value
k_CAVNodeAbsentDiag_Cnt_str.PStep	25956
k_CAVNodeAbsentDiag_Cnt_str.NStep	43244
k_CAVNodeAbsentTimeout_mS_u16	59295
k_CAVNodeTimeout_mS_u16	26593
k_CMM388MsgTimeout_mS_u16	8579
k_CMM388NTCEnableTimeout_mS_u16	41487
k_CMMNTCEnableTimeout_mS_u16	30757
k_CMMNodeAbsentDiag_Cnt_str.Threshold	5585
k_CMMNodeAbsentDiag_Cnt_str.PStep	53489
k_CMMNodeAbsentDiag_Cnt_str.NStep	1589
k_CMMNodeAbsentTimeout_mS_u16	20876
k_CONSANGLECPKMax_HwDeg_f32	523.387329
k_CONSANGLECPKMin_HwDeg_f32	-327.874786
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	46692
k_CONSANGLECPKSigValidThresh_Cnt_u16	45568
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	34848
k_CPKVehicleSpeedValidThresh_Cnt_u16	60011
k_CityParkInputInvalidThresh_Cnt_u16	45211
k_CityParkInputValidThresh_Cnt_u16	35218
k_ComputerRazGCTSigValidThresh_Cnt_u16	43675
k_CptTemporelSigValidThresh_Cnt_u16	40035
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	52344
k_DMDFCTCPKSigValidThresh_Cnt_u16	28044
k_DMDFCTCPKValidCount_Cnt_u16	1533
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	38299
k_DMDRELAXECPKSigValidThresh_Cnt_u16	2088
k_DMDRelaxeConsistentThresh_Cnt_u16	10198
k_DateValidThresh_Cnt_u16	45811
k_DefaultVehSpd_Kph_f32	207.855804
k_DiagMuxOnAbsentTimeout_mS_u16	25054
k_EMNodeTimeout_mS_u16	28038
k_ESPNTCEnableTimeout_mS_u16	33509
k_ESPNodeAbsentDiag_Cnt_str.Threshold	56105
k_ESPNodeAbsentDiag_Cnt_str.PStep	39129
k_ESPNodeAbsentDiag_Cnt_str.NStep	3244
k_ESPNodeAbsentTimeout_mS_u16	17268
k_EtatMTSigInvalidThresh_Cnt_u16	35032
k_EtatMTSigValidThresh_Cnt_u16	34756
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	28503
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	13463
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	10223
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	766
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	35078
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	64264
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	29921
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	55633
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	46308
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	1620
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	54572
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	5584
k_ISDATDIRASentDiag_Cnt_str.Threshold	26593
k_ISDATDIRASentDiag_Cnt_str.PStep	61445
k_ISDATDIRASentDiag_Cnt_str.NStep	10573
k_ISDATDIRASentTimeout_mS_u16	22009
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	56569
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	11220
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	65
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	877
k_ISDYNAASChkSumValidThresh_Cnt_u16	14361
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	43872
k_ISDYNAASMsgCountValidThresh_Cnt_u16	11653
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	8673
k_ISDYNAASMsgLenValidThresh_Cnt_u16	25574
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	61623
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	6846
k_ISDYNABRChkSumValidThresh_Cnt_u16	1106
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	42517
k_ISDYNABRMsgCountValidThresh_Cnt_u16	56985
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	60156
k_ISDYNABRMsgLenValidThresh_Cnt_u16	15788
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	15588
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	38698
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	5425

Name	Input Value
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	16445
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	52722
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	8758
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	34692
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	33923
k_ISDYNVOLChkSumValidThresh_Cnt_u16	16380
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	54013
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	1421
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	63942
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	23462
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	50897
k_IgnOnTimeout_mS_u16	27151
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	132.387604
k_PowerCutVehSpdLowThresh_Kph_f32	254.114105
k_PowerCutVehSpdLowTimeout_mS_u16	53175
k_VBattMaxAAS_Volt_f32	2.39459991
k_VBattMaxBSI_Volt_f32	16.7863998
k_VBattMaxCAV_Volt_f32	25.3416996
k_VBattMaxCMM388_Volt_f32	3.28110003
k_VBattMaxCMM_Volt_f32	12.0436001
k_VBattMaxESP_Volt_f32	16.9454994
k_VBattMinAAS_Volt_f32	4.56799984
k_VBattMinBSI_Volt_f32	6.9454999
k_VBattMinCAV_Volt_f32	10.0743999
k_VBattMinCMM388_Volt_f32	10.9068003
k_VBattMinCMM_Volt_f32	13.5965996
k_VBattMinESP_Volt_f32	1.04359996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	42571
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	42163
k_VitesseVehicleBVRampValidThresh_Cnt_u16	8766
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	55023
k_VitesseVehicleBVSigValidThresh_Cnt_u16	29703
k_VitesseVehicleBVSpeedPassThresh_kph_f32	502.230804
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	23641
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	65109
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1826055936
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	42563
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3466657536
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	0
target_SrlComInput_Per1_Batt_Volt_f32.value	12.7601995
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4002158336
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	103
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.589274943
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1484654336
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	145
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	824813312
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	44
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3102033664
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2544953088
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1972143872
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	176
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4202178304

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3463694080
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	212
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2934826752
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	153
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	176
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	536151808
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3525355264
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4082910976
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	164
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	165
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	189
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4191786752
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2914
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.118247561
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	977676
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	173.766693
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	30344

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	31896	31896	✔
AASNodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	11222	11222	✔
AngleVolantMsgTimer_mS_M_u32	3466657536	3466657536	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	642.178711	642.178711	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2647582464	2647582464	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	1826055936	1826055936	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	2320275200	2320275200	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	121526016	121526016	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	54727	54727	✔
CMMNodeAbsentTimer_mS_M_u32	4202178304	4202178304	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	57600	57600	✔
CONSANGLECPK_HwDeg_M_f32	-548.324097	-548.324097 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	57600	57600	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3466657536	3466657536	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	35218	35218	✔
CityParkInputInvalidCount_Cnt_M_u16	33646	33646	✔
CityParkInputMsgTimer_mS_M_u32	3466657536	3466657536	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3466657536	3466657536	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3466657536	3466657536	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1826055936	1826055936	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3466657536	3466657536	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	121526016	121526016	✔
ESPNTCEnableTimer_mS_M_u32	1533880064	1533880064	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	56105	56105	✔
ESPNodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[1]	15	15	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3466657536	3466657536	✔
ElecIntTimer_mS_M_u32[1]	100	100	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3466657536	3466657536	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	50703	50703	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1484654336	1484654336	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	62989	62989	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1060255488	1060255488	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	20629	20629	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3102033664	3102033664	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	43120	43120	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2544953088	2544953088	✔
ISDATDIRASentFltAcc_Cnt_M_u16	26593	26593	✔
ISDATDIRASentTimer_mS_M_u32	3466657536	3466657536	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	13421	13421	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	23649	23649	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2934826752	2934826752	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3466657536	3466657536	✔
IgnOnTimer_mS_M_u32	1570506496	1570506496	✔
IgnTimeOff_Sec_M_u32	2450823047	2450823047	✔
Msg348Valid_Cnt_M_Igc	0	0	✔
Msg432Valid_Cnt_M_Igc	0	0	✔
Msg552Valid_Cnt_M_Igc	0	0	✔
NetOn_Cnt_M_Igc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1484654336	1484654336	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	145	145	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	824813312	824813312	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	44	44	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3102033664	3102033664	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	74	74	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2544953088	2544953088	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2180925184	2180925184	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	176	176	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4202178304	4202178304	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	72	72	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3463694080	3463694080	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2934826752	2934826752	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	536151808	536151808	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	205	205	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3525355264	3525355264	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	34	34	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4082910976	4082910976	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4191786752	4191786752	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	482.903809	482.903809	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	556.461121	556.461121	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	28.5517006	28.5517006	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	642.178711	642.178711	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	57600	57600	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2450823047	2450823047	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-548.324097	-548.324097 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	207.855804	207.855804	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	3	ValidityNTCProcessing	3	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.204 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	57695744
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	29870
AASNodeAbsentTimer_mS_M_u32	2386710016
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	18787
ANGLEVOLANTSigValidCount_Cnt_M_u16	39254
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	60603
AngleVolantMsgTimer_mS_M_u32	57695744
AngleVolantValidCount_Cnt_M_u16	63070
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	712.476074
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	713952768
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2138344960
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3084189184
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	939507200
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	3322

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2116386304
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	32943
CAVNodeAbsentTimer_mS_M_u32	3346722304
CDD_SrlComVehSpd_Kph_G_f32	32.7831993
CMM388NTCEnableTimer_mS_M_u32	108736000
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	292613632
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	44677
CMMNodeAbsentTimer_mS_M_u32	2894708224
CONSANGLECPKSigInvalidCount_Cnt_M_u16	19515
CONSANGLECPKSigValidCount_Cnt_M_u16	57982
CONSANGLECPK_Cnt_M_u16	1785
CONSANGLECPK_HwDeg_M_f32	-240.376999
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	1785
CPKVehicleSpeedMsgTimer_mS_M_u32	2730450432
CPKVehicleSpeedValidCount_Cnt_M_u16	14570
CityParkInputConsistentCount_Cnt_M_u16	20994
CityParkInputInvalidCount_Cnt_M_u16	40308
CityParkInputMsgTimer_mS_M_u32	1484654336
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3538308608
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	1618
ComputerRazGCTSigInvalidTimer_mS_M_u32	3748883968
ComputerRazGCTSigValidCount_Cnt_M_u16	65351
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	24016
DMDFCTCPKSigValidCount_Cnt_M_u16	16299
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56885
DMDRELAXECPKSigValidCount_Cnt_M_u16	34728
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	27976
DateInvalidTimer_mS_M_u32	2138344960
DiagMuxOnAbsentTimer_mS_M_u32	2859867648
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	939507200
ESPNTCEnableTimer_mS_M_u32	984829440
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	45876
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	54
EffacDefaultDiagTimer_mS_M_u32[1]	64
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	655
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	660045312
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	51658
EtatMTSigValidCount_Cnt_M_u16	54249
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	55053
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	18128
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	9121
ISDAT4V2BSI552MsgTimer_mS_M_u32	3828203008
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	36049
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	8121
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	54249
ISDATBSI3F2MsgTimer_mS_M_u32	3080986112
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	43580
ISDATBSI412MsgLenValidCount_Cnt_M_u16	1107
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	51658
ISDATBSI412MsgTimer_mS_M_u32	916348416
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	6441
ISDATBSI432MsgLenValidCount_Cnt_M_u16	37080
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	23104
ISDATDIRASentFltAcc_Cnt_M_u16	4852
ISDATDIRASentTimer_mS_M_u32	2730450432

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	15015
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	63070
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	58087
ISDYN2CMMMsgTimer_mS_M_u32	1941786112
ISDYNAASChkSumInvalidCount_Cnt_M_u16	21888
ISDYNAASChkSumValidCount_Cnt_M_u16	51348
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	41333
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	54634
ISDYNAASMsgLenValidCount_Cnt_M_u16	49781
ISDYNAASMsgTimeValidCount_Cnt_M_u16	21888
ISDYNAASMsgTimer_mS_M_u32	4225183232
ISDYNABRChkSumInvalidCount_Cnt_M_u16	11378
ISDYNABRChkSumValidCount_Cnt_M_u16	31534
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	35607
ISDYNABRMsgCountValidCount_Cnt_M_u16	53611
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	38098
ISDYNABRMsgLenValidCount_Cnt_M_u16	15957
ISDYNABRMsgTimeValidCount_Cnt_M_u16	1785
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	86
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	57
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	54249
ISDYNCMM208MsgTimer_mS_M_u32	4161998336
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	195
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	163
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	65535
ISDYNCMM388MsgTimer_mS_M_u32	1694674432
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	37225
ISDYNVOLChkSumValidCount_Cnt_M_u16	20012
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	62974
ISDYNVOLMsgCountValidCount_Cnt_M_u16	15961
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	56477
ISDYNVOLMsgLenValidCount_Cnt_M_u16	44993
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	44677
ISDYNVOLMsgTimer_mS_M_u32	3234819584
IgnOnTimer_mS_M_u32	128364032
IgnTimeOff_Sec_M_u32	2809228723
ManVehSpd_Kph_M_f32	171.850296
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	22
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	24
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	259661312
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	235
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1246494208
PrevISDATBSI412MsgDLCError_Cnt_M_u08	200
PrevISDATBSI412MsgRxTime_MSec_M_u32	1540091392
PrevISDATBSI432MsgDLCError_Cnt_M_u08	63
PrevISDATBSI432MsgRxTime_MSec_M_u32	1338461696
PrevISDATDIRAMsgTxTime_MSec_M_u32	4085247488
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	156
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2931637760
PrevISDYNAASMsgDLCError_Cnt_M_u08	38
PrevISDYNAASMsgRxTime_MSec_M_u32	3162336768
PrevISDYNABRMsgDLCError_Cnt_M_u08	158
PrevISDYNABRMsgRxTime_MSec_M_u32	3579751936
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	88
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1065512448
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	171
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3779218944
PrevISDYNVOLMsgDLCError_Cnt_M_u08	151
PrevISDYNVOLMsgRxTime_MSec_M_u32	1999171072
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1288461824
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	462.570007

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	37784
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	26403
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	23169
VitesseVehicleBVRampValidCount_Cnt_M_u16	47820
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	14796
VitesseVehicleBVSigValidCount_Cnt_M_u16	13951
VitesseVehicleBV_Kph_M_f32	44.4832001
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	65535
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	47736
VitesseVehiculeRoues_Kph_M_f32	129.654099
k_AASNTCEnableTimeout_mS_u16	59528
k_AASNodeAbsentDiag_Cnt_str.Threshold	40324
k_AASNodeAbsentDiag_Cnt_str.PStep	16467
k_AASNodeAbsentDiag_Cnt_str.NStep	8806
k_AASNodeAbsentTimeout_mS_u16	59601
k_AASNodeTimeout_mS_u16	14883
k_ABSNodeTimeout_mS_u16	58133
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	26844
k_ANGLEVOLANTSigValidThresh_Cnt_u16	20683
k_AngleVolantInvalidThresh_Cnt_u16	14250
k_AngleVolantValidThresh_Cnt_u16	40308
k_BSI552MsgTimeout_mS_u16	15895
k_BSINTCEnableTimeout_mS_u16	22241
k_BSINodeAbsentDiag_Cnt_str.Threshold	852
k_BSINodeAbsentDiag_Cnt_str.PStep	45178
k_BSINodeAbsentDiag_Cnt_str.NStep	583
k_BSINodeAbsentTimeout_mS_u16	31859
k_BSINodeTimeout_mS_u16	23104
k_BattOvHi_Volt_f32	1.80519998
k_BattOvLo_Volt_f32	20.7735996
k_BattUvHi_Volt_f32	3.73979998
k_BattUvLo_Volt_f32	9.64680004
k_CAVNTCEnableTimeout_mS_u16	10586
k_CAVNodeAbsentDiag_Cnt_str.Threshold	27309
k_CAVNodeAbsentDiag_Cnt_str.PStep	47537
k_CAVNodeAbsentDiag_Cnt_str.NStep	21240
k_CAVNodeAbsentTimeout_mS_u16	2525
k_CAVNodeTimeout_mS_u16	47511
k_CMM388MsgTimeout_mS_u16	34734
k_CMM388NTCEnableTimeout_mS_u16	13834
k_CMMNTCEnableTimeout_mS_u16	26249
k_CMMNodeAbsentDiag_Cnt_str.Threshold	3714
k_CMMNodeAbsentDiag_Cnt_str.PStep	39970
k_CMMNodeAbsentDiag_Cnt_str.NStep	5381
k_CMMNodeAbsentTimeout_mS_u16	57044
k_CONSANGLECPKMax_HwDeg_f32	651.50708
k_CONSANGLECPKMin_HwDeg_f32	-656.809204
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	37772
k_CONSANGLECPKSigValidThresh_Cnt_u16	36216
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	59673
k_CPKVehicleSpeedValidThresh_Cnt_u16	63671
k_CityParkInputInvalidThresh_Cnt_u16	61416
k_CityParkInputValidThresh_Cnt_u16	20994
k_ComputerRazGCTSigValidThresh_Cnt_u16	10023
k_CptTemporelSigValidThresh_Cnt_u16	61071
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	42962
k_DMDFCTCPKSigValidThresh_Cnt_u16	37205
k_DMDFCTCPKValidCount_Cnt_u16	41026

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	58087
k_DMDRELAXECPKSigValidThresh_Cnt_u16	14338
k_DMDRelaxeConsistentThresh_Cnt_u16	4344
k_DateValidThresh_Cnt_u16	9121
k_DefaultVehSpd_Kph_f32	65.1621017
k_DiagMuxOnAbsentTimeout_mS_u16	31839
k_EMNodeTimeout_mS_u16	31912
k_ESPNTCEnableTimeout_mS_u16	53259
k_ESPNodeAbsentDiag_Cnt_str.Threshold	42136
k_ESPNodeAbsentDiag_Cnt_str.PStep	51528
k_ESPNodeAbsentDiag_Cnt_str.NStep	62779
k_ESPNodeAbsentTimeout_mS_u16	43292
k_EtatMTSigInvalidThresh_Cnt_u16	39729
k_EtatMTSigValidThresh_Cnt_u16	52013
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	53108
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	64628
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	10987
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	27134
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	29862
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	31456
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	47062
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	51013
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	50125
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	59133
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	22324
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	22410
k_ISDATDIRASentDiag_Cnt_str.Threshold	40598
k_ISDATDIRASentDiag_Cnt_str.PStep	346
k_ISDATDIRASentDiag_Cnt_str.NStep	15969
k_ISDATDIRASentTimeout_mS_u16	63438
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	58895
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	60603
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	51191
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	49010
k_ISDYNAASChkSumValidThresh_Cnt_u16	20014
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	40471
k_ISDYNAASMsgCountValidThresh_Cnt_u16	9323
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	13334
k_ISDYNAASMsgLenValidThresh_Cnt_u16	60871
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39187
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	21760
k_ISDYNABRChkSumValidThresh_Cnt_u16	25859
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	8186
k_ISDYNABRMsgCountValidThresh_Cnt_u16	813
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	33157
k_ISDYNABRMsgLenValidThresh_Cnt_u16	50740
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	54348
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	59196
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	4197
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	29890
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	23651
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	60502
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	61740
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	35439
k_ISDYNVOLChkSumValidThresh_Cnt_u16	46278
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	35393
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	46546
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	20006
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	9541
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	57351
k_IgnOnTimeout_mS_u16	2507
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	236.066895
k_PowerCutVehSpdLowThresh_Kph_f32	230.887207
k_PowerCutVehSpdLowTimeout_mS_u16	54996
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	5.22910023
k_VBattMaxCAV_Volt_f32	16.3337002
k_VBattMaxCMM388_Volt_f32	28.4391003
k_VBattMaxCMM_Volt_f32	10.7561998
k_VBattMaxESP_Volt_f32	20.6198997
k_VBattMinAAS_Volt_f32	23.3539009
k_VBattMinBSI_Volt_f32	4.61990023

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinCAV_Volt_f32	20.4664001
k_VBattMinCMM388_Volt_f32	9.26799965
k_VBattMinCMM_Volt_f32	28.3658009
k_VBattMinESP_Volt_f32	10.7561998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	21017
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	29600
k_VitesseVehicleBVRampValidThresh_Cnt_u16	35070
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	41260
k_VitesseVehicleBVSigValidThresh_Cnt_u16	42659
k_VitesseVehicleBVSpeedPassThresh_kph_f32	515.474609
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	5039
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	39546
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2138344960
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	57719
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	511165952
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	171
target_SrlComInput_Per1_Batt_Volt_f32.value	18.6856995
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3910565376
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	34
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.779292524
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	520138240
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	199
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1266535936
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	204
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2865425920
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1156058624
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	567619072
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1234324992
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3290394112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	45
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	109
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	179
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	858852864
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	50
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	106
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1687924224
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	77123072

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2540039680
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	80
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	132
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	222
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3710778880
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	16
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.738414943
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	172221
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	8.17940044
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	16674

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	511165952	511165952	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	40324	40324	✔
AASNodeAbsentTimer_mS_M_u32	511165952	511165952	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	60603	60603	✔
AngleVolantMsgTimer_mS_M_u32	511165952	511165952	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	712.476074	712.476074	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	511165952	511165952	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	511165952	511165952	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	511165952	511165952	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	511165952	511165952	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	511165952	511165952	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	39296	39296	✔
CMMNodeAbsentTimer_mS_M_u32	1234324992	1234324992	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	1785	1785	✔
CONSANGLECPK_HwDeg_M_f32	-240.376999	-240.376999 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	1787	1787	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	511165952	511165952	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	20994	20994	✔
CityParkInputInvalidCount_Cnt_M_u16	40310	40310	✔
CityParkInputMsgTimer_mS_M_u32	511165952	511165952	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	511165952	511165952	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ComputerRazGCTSigInvalidTimer_mS_M_u32	511165952	511165952	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	511165952	511165952	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	511165952	511165952	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	511165952	511165952	✔
ESPNTCEnableTimer_mS_M_u32	984829440	984829440	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	42136	42136	✔
ESPNodeAbsentTimer_mS_M_u32	511165952	511165952	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	54	54	✔
EffacDefaultDiagTimer_mS_M_u32[1]	64	64	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	65	65	✔
ElecIntTimer_mS_M_u32[1]	655	655	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	511165952	511165952	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATDIRASentFltAcc_Cnt_M_u16	40598	40598	✔
ISDATDIRASentTimer_mS_M_u32	511165952	511165952	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	11379	11379	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	35607	35607	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	858852864	858852864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	511165952	511165952	✔
IgnOnTimer_mS_M_u32	128364032	128364032	✔
IgnTimeOff_Sec_M_u32	2809228723	2809228723	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	113	113	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	520138240	520138240	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	199	199	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1266535936	1266535936	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	204	204	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2865425920	2865425920	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	135	135	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1156058624	1156058624	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4085247488	4085247488	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	67	67	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1234324992	1234324992	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	83	83	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3290394112	3290394112	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	158	158	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	858852864	858852864	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1687924224	1687924224	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	174	174	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	77123072	77123072	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	135	135	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2540039680	2540039680	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3710778880	3710778880	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	462.570007	462.570007	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	44.4832001	44.4832001	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	129.654099	129.654099	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	712.476074	712.476074	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	1785	1785	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2809228723	2809228723	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-240.376999	-240.376999 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	65.1621017	65.1621017	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0133	0x0133	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	2	ValidityNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	2	ValidityNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.205 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2017831168
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	16010
AASNodeAbsentTimer_mS_M_u32	3415202048
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	12908
ANGLEVOLANTSigValidCount_Cnt_M_u16	40018
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	19043
AngleVolantMsgTimer_mS_M_u32	2017831168
AngleVolantValidCount_Cnt_M_u16	8697
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	161.260681
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3584858368
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2432243968
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	899139840
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3491203328
BSI552NTCsEnabled_Cnt_M_lgc	0

Name	Input Value
BSINodeAbsentFltAcc_Cnt_M_u16	935
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3299232000
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	25864
CAVNodeAbsentTimer_mS_M_u32	1248196864
CDD_SrlComVehSpd_Kph_G_f32	544.758118
CMM388NTCEnableTimer_mS_M_u32	3731175680
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3296983296
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	36423
CMMNodeAbsentTimer_mS_M_u32	444172544
CONSANGLECPKSigInvalidCount_Cnt_M_u16	14565
CONSANGLECPKSigValidCount_Cnt_M_u16	4059
CONSANGLECPK_Cnt_M_u16	20074
CONSANGLECPK_HwDeg_M_f32	734.343872
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	20074
CPKVehicleSpeedMsgTimer_mS_M_u32	2522392832
CPKVehicleSpeedValidCount_Cnt_M_u16	30078
CityParkInputConsistentCount_Cnt_M_u16	40717
CityParkInputInvalidCount_Cnt_M_u16	4538
CityParkInputMsgTimer_mS_M_u32	520138240
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2376325376
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	6558
ComputerRazGCTSigInvalidTimer_mS_M_u32	2222749952
ComputerRazGCTSigValidCount_Cnt_M_u16	60222
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	16550
DMDFCTCPKSigValidCount_Cnt_M_u16	38099
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	15350
DMDRELAXECPKSigValidCount_Cnt_M_u16	39260
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	18878
DateInvalidTimer_mS_M_u32	2432243968
DiagMuxOnAbsentTimer_mS_M_u32	3392432384
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3491203328
ESPNTCEnableTimer_mS_M_u32	3392985344
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	51704
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	80
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	286279936
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	57719
EtatMTSigValidCount_Cnt_M_u16	52441
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24687
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	43749
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	16625
ISDAT4V2BSI552MsgTimer_mS_M_u32	59607296
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	28129
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	57067
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	52441
ISDATBSI3F2MsgTimer_mS_M_u32	3668601088
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	36514
ISDATBSI412MsgLenValidCount_Cnt_M_u16	27164
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	57719
ISDATBSI412MsgTimer_mS_M_u32	381397248
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	56923
ISDATBSI432MsgLenValidCount_Cnt_M_u16	49420
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	23637
ISDATDIRASentFltAcc_Cnt_M_u16	569

Name	Input Value
ISDATDIRASentTimer_mS_M_u32	2522392832
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	60256
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	8697
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52577
ISDYN2CMMMsgTimer_mS_M_u32	3340687616
ISDYNAASChkSumInvalidCount_Cnt_M_u16	25620
ISDYNAASChkSumValidCount_Cnt_M_u16	58521
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	15540
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	4823
ISDYNAASMsgLenValidCount_Cnt_M_u16	1396
ISDYNAASMsgTimeValidCount_Cnt_M_u16	25620
ISDYNAASMsgTimer_mS_M_u32	1850816768
ISDYNABRChkSumInvalidCount_Cnt_M_u16	32446
ISDYNABRChkSumValidCount_Cnt_M_u16	3148
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	57167
ISDYNABRMsgCountValidCount_Cnt_M_u16	58900
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	31520
ISDYNABRMsgLenValidCount_Cnt_M_u16	6230
ISDYNABRMsgTimeValidCount_Cnt_M_u16	20074
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	725
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1335
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	52441
ISDYNCMM208MsgTimer_mS_M_u32	3239942400
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2751
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1441
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	59529
ISDYNCMM388MsgTimer_mS_M_u32	1087289600
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	41307
ISDYNVOLChkSumValidCount_Cnt_M_u16	1233
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	45084
ISDYNVOLMsgCountValidCount_Cnt_M_u16	53449
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	12733
ISDYNVOLMsgLenValidCount_Cnt_M_u16	53779
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	36423
ISDYNVOLMsgTimer_mS_M_u32	1349024000
IgnOnTimer_mS_M_u32	3907172608
IgnTimeOff_Sec_M_u32	519173141
ManVehSpd_Kph_M_f32	547.383911
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	187
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	120
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2871552256
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	106
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	439535872
PrevISDATBSI412MsgDLCError_Cnt_M_u08	40
PrevISDATBSI412MsgRxTime_MSec_M_u32	292747520
PrevISDATBSI432MsgDLCError_Cnt_M_u08	89
PrevISDATBSI432MsgRxTime_MSec_M_u32	3674265856
PrevISDATDIRAMsgTxTime_MSec_M_u32	441907456
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	108
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1105135872
PrevISDYNAASMsgDLCError_Cnt_M_u08	87
PrevISDYNAASMsgRxTime_MSec_M_u32	2505996544
PrevISDYNABRMsgDLCError_Cnt_M_u08	203
PrevISDYNABRMsgRxTime_MSec_M_u32	1606072576
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	62
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1615821056
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	85
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3532642560
PrevISDYNVOLMsgDLCError_Cnt_M_u08	127
PrevISDYNVOLMsgRxTime_MSec_M_u32	1935407360
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	204581120
PrevModeDiag_Cnt_M_u08	0

Name	Input Value
PrevSrlComVehSpd_Kph_M_f32	347.588715
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	4173
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	20330
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	40850
VitesseVehicleBVRampValidCount_Cnt_M_u16	14447
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	17713
VitesseVehicleBVSigValidCount_Cnt_M_u16	43223
VitesseVehicleBV_Kph_M_f32	225.073303
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	59529
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	18285
VitesseVehiculeRoues_Kph_M_f32	527.193115
k_AASNTCEnableTimeout_mS_u16	42429
k_AASNodeAbsentDiag_Cnt_str.Threshold	10757
k_AASNodeAbsentDiag_Cnt_str.PStep	7105
k_AASNodeAbsentDiag_Cnt_str.NStep	65461
k_AASNodeAbsentTimeout_mS_u16	54944
k_AASNodeTimeout_mS_u16	54890
k_ABSNodeTimeout_mS_u16	1239
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	31554
k_ANGLEVOLANTSigValidThresh_Cnt_u16	3379
k_AngleVolantInvalidThresh_Cnt_u16	38038
k_AngleVolantValidThresh_Cnt_u16	4538
k_BSI552MsgTimeout_mS_u16	63632
k_BSINTCEnableTimeout_mS_u16	1331
k_BSINodeAbsentDiag_Cnt_str.Threshold	26412
k_BSINodeAbsentDiag_Cnt_str.PStep	34315
k_BSINodeAbsentDiag_Cnt_str.NStep	15280
k_BSINodeAbsentTimeout_mS_u16	31547
k_BSINodeTimeout_mS_u16	23637
k_BattOvHi_Volt_f32	31.5
k_BattOvLo_Volt_f32	7.83199978
k_BattUvHi_Volt_f32	21.5774994
k_BattUvLo_Volt_f32	25.4067993
k_CAVNTCEnableTimeout_mS_u16	34312
k_CAVNodeAbsentDiag_Cnt_str.Threshold	9850
k_CAVNodeAbsentDiag_Cnt_str.PStep	55599
k_CAVNodeAbsentDiag_Cnt_str.NStep	26463
k_CAVNodeAbsentTimeout_mS_u16	382
k_CAVNodeTimeout_mS_u16	24785
k_CMM388MsgTimeout_mS_u16	1418
k_CMM388NTCEnableTimeout_mS_u16	27254
k_CMMNTCEnableTimeout_mS_u16	49337
k_CMMNodeAbsentDiag_Cnt_str.Threshold	32647
k_CMMNodeAbsentDiag_Cnt_str.PStep	42126
k_CMMNodeAbsentDiag_Cnt_str.NStep	57005
k_CMMNodeAbsentTimeout_mS_u16	19033
k_CONSANGLECPKMax_HwDeg_f32	268.244202
k_CONSANGLECPKMin_HwDeg_f32	-605.499512
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	33391
k_CONSANGLECPKSigValidThresh_Cnt_u16	52845
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	8584
k_CPKVehicleSpeedValidThresh_Cnt_u16	20273
k_CityParkInputInvalidThresh_Cnt_u16	35932
k_CityParkInputValidThresh_Cnt_u16	40717
k_ComputerRazGCTSigValidThresh_Cnt_u16	30431
k_CptTemporelSigValidThresh_Cnt_u16	19049
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	16928
k_DMDFCTCPKSigValidThresh_Cnt_u16	8022

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_DMDFCTCPKValidCount_Cnt_u16	27087
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	52577
k_DMDRELAXECPKSigValidThresh_Cnt_u16	51150
k_DMDRelaxeConsistentThresh_Cnt_u16	38124
k_DateValidThresh_Cnt_u16	16625
k_DefaultVehSpd_Kph_f32	139.602707
k_DiagMuxOnAbsentTimeout_mS_u16	1592
k_EMNodeTimeout_mS_u16	39838
k_ESPNTCEnableTimeout_mS_u16	59124
k_ESPNodeAbsentDiag_Cnt_str.Threshold	40274
k_ESPNodeAbsentDiag_Cnt_str.PStep	1844
k_ESPNodeAbsentDiag_Cnt_str.NStep	56738
k_ESPNodeAbsentTimeout_mS_u16	2945
k_EtatMTSigInvalidThresh_Cnt_u16	61057
k_EtatMTSigValidThresh_Cnt_u16	55375
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	39543
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	40249
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	63570
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	51802
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	54308
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	44214
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	63060
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	4549
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	28271
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	48734
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	55159
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	36791
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	36010
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	14376
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	19043
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	44848
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	50622
k_ISDYNAASChkSumValidThresh_Cnt_u16	37708
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	42575
k_ISDYNAASMsgCountValidThresh_Cnt_u16	60692
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	63442
k_ISDYNAASMsgLenValidThresh_Cnt_u16	19326
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	21595
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	29334
k_ISDYNABRChkSumValidThresh_Cnt_u16	56396
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	51879
k_ISDYNABRMsgCountValidThresh_Cnt_u16	31437
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	5447
k_ISDYNABRMsgLenValidThresh_Cnt_u16	37112
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	17264
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	42337
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16423
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	25229
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	63852
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	41810
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	63122
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	31241
k_ISDYNVOLChkSumValidThresh_Cnt_u16	58563
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	47313
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	60512
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	50275
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	18629
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	9151
k_IgnOnTimeout_mS_u16	27637
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	49.3883018
k_PowerCutVehSpdLowThresh_Kph_f32	8.92739964
k_PowerCutVehSpdLowTimeout_mS_u16	2777
k_VBattMaxAAS_Volt_f32	27.8551998
k_VBattMaxBSI_Volt_f32	28.0879002
k_VBattMaxCAV_Volt_f32	16.4626007
k_VBattMaxCMM388_Volt_f32	10.3748999
k_VBattMaxCMM_Volt_f32	4.6099
k_VBattMaxESP_Volt_f32	21.3108006
k_VBattMinAAS_Volt_f32	29.3043003

Name	Input Value
k_VBattMinBSI_Volt_f32	21.3108006
k_VBattMinCAV_Volt_f32	30.0711002
k_VBattMinCMM388_Volt_f32	23.7698994
k_VBattMinCMM_Volt_f32	16.9757004
k_VBattMinESP_Volt_f32	4.6099
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	39946
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	57652
k_VitesseVehicleBVRampValidThresh_Cnt_u16	63260
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	3025
k_VitesseVehicleBVSigValidThresh_Cnt_u16	25898
k_VitesseVehicleBVSpeedPassThresh_kph_f32	512.558228
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	44040
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	53605
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2432243968
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	85
target_SrlComInput_Per1_Batt_Volt_f32.value	9.20409966
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2278770944
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	241
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.445504785
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2329196800
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3789379840
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3765827840
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1855887616
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1951873280
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3651131648
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2256042240
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	205
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	130259200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3859003648
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	13

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3800848640
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	1
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1185216768
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1770834176
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1270
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0876433849
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	2365
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	20.3006992
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	44975

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	19045	19045	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	161.260681	161.260681	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26412	26412	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3651131648	3651131648	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	20074	20074	✔
CONSANGLECPK_HwDeg_M_f32	734.343872	734.343872 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	20074	20074	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3251510528	3251510528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	40717	40717	✔
CityParkInputInvalidCount_Cnt_M_u16	4540	4540	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3392985344	3392985344	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	40274	40274	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	80	80	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	32446	32446	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	57167	57167	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	130259200	130259200	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	3907172608	3907172608	✔
IgnTimeOff_Sec_M_u32	519173141	519173141	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	93	93	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2329196800	2329196800	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	151	151	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3789379840	3789379840	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	5	5	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3765827840	3765827840	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	143	143	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1855887616	1855887616	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	441907456	441907456	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3651131648	3651131648	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2256042240	2256042240	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	130259200	130259200	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	14	14	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3859003648	3859003648	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	13	13	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3800848640	3800848640	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	1	1	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1185216768	1185216768	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1770834176	1770834176	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	347.588715	347.588715	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	225.073303	225.073303	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	527.193115	527.193115	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	161.260681	161.260681	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	20074	20074	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	519173141	519173141	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	734.343872	734.343872 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	139.602707	139.602707	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	2	ValidityNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.206 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3259201280
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	53891
AASNodeAbsentTimer_mS_M_u32	2028480256
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	32498
ANGLEVOLANTSigValidCount_Cnt_M_u16	37686
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	11220
AngleVolantMsgTimer_mS_M_u32	3259201280
AngleVolantValidCount_Cnt_M_u16	47134
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	618.215149
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2647582464
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1826055936
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2320275200
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	121526016
BSI552NTCsEnabled_Cnt_M_lgc	0

Name	Input Value
BSINodeAbsentFltAcc_Cnt_M_u16	22293
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1267144448
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	36185
CAVNodeAbsentTimer_mS_M_u32	4015343360
CDD_SrlComVehSpd_Kph_G_f32	309.960602
CMM388NTCEnableTimer_mS_M_u32	648709888
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2483242752
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	56316
CMMNodeAbsentTimer_mS_M_u32	588273408
CONSANGLECPKSigInvalidCount_Cnt_M_u16	31829
CONSANGLECPKSigValidCount_Cnt_M_u16	14633
CONSANGLECPK_Cnt_M_u16	57600
CONSANGLECPK_HwDeg_M_f32	-548.324097
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	57600
CPKVehicleSpeedMsgTimer_mS_M_u32	3330176768
CPKVehicleSpeedValidCount_Cnt_M_u16	34312
CityParkInputConsistentCount_Cnt_M_u16	35218
CityParkInputInvalidCount_Cnt_M_u16	33644
CityParkInputMsgTimer_mS_M_u32	2384827392
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2807834368
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	37367
ComputerRazGCTSigInvalidTimer_mS_M_u32	4116170496
ComputerRazGCTSigValidCount_Cnt_M_u16	18043
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	65016
DMDFCTCPKSigValidCount_Cnt_M_u16	60485
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	6828
DMDRELAXECPKSigValidCount_Cnt_M_u16	26224
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	62118
DateInvalidTimer_mS_M_u32	1826055936
DiagMuxOnAbsentTimer_mS_M_u32	283916032
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	121526016
ESPNTCEnableTimer_mS_M_u32	1533880064
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	61100
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	1
EffacDefaultDiagTimer_mS_M_u32[1]	15
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	100
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	186717952
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	27450
EtatMTSigValidCount_Cnt_M_u16	48154
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	50703
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	14947
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	45811
ISDAT4V2BSI552MsgTimer_mS_M_u32	8673024
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	62989
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	63829
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	48154
ISDATBSI3F2MsgTimer_mS_M_u32	1060255488
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	20628
ISDATBSI412MsgLenValidCount_Cnt_M_u16	42701
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	27450
ISDATBSI412MsgTimer_mS_M_u32	2391373568
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	43120
ISDATBSI432MsgLenValidCount_Cnt_M_u16	59936
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	35710
ISDATDIRASentFltAcc_Cnt_M_u16	21314

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDATDIRASentTimer_mS_M_u32	3330176768
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	22470
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	47134
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	38299
ISDYN2CMMMsgTimer_mS_M_u32	901719808
ISDYNAASChkSumInvalidCount_Cnt_M_u16	43581
ISDYNAASChkSumValidCount_Cnt_M_u16	34850
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	60865
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	31344
ISDYNAASMsgLenValidCount_Cnt_M_u16	20396
ISDYNAASMsgTimeValidCount_Cnt_M_u16	43581
ISDYNAASMsgTimer_mS_M_u32	976652032
ISDYNABRChkSumInvalidCount_Cnt_M_u16	13421
ISDYNABRChkSumValidCount_Cnt_M_u16	10521
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	23648
ISDYNABRMsgCountValidCount_Cnt_M_u16	40581
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	32120
ISDYNABRMsgLenValidCount_Cnt_M_u16	56972
ISDYNABRMsgTimeValidCount_Cnt_M_u16	57600
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	85
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	55
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	48154
ISDYNCMM208MsgTimer_mS_M_u32	1341646592
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	191
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	161
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0
ISDYNCMM388MsgTimer_mS_M_u32	4180150016
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	17051
ISDYNVOLChkSumValidCount_Cnt_M_u16	18415
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	21310
ISDYNVOLMsgCountValidCount_Cnt_M_u16	51723
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	51081
ISDYNVOLMsgLenValidCount_Cnt_M_u16	39613
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	56316
ISDYNVOLMsgTimer_mS_M_u32	1692649216
IgnOnTimer_mS_M_u32	1570506496
IgnTimeOff_Sec_M_u32	2450823047
ManVehSpd_Kph_M_f32	508.664093
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	21
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	123
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1598043904
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	69
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4073690880
PrevISDATBSI412MsgDLCError_Cnt_M_u08	242
PrevISDATBSI412MsgRxTime_MSec_M_u32	2939832064
PrevISDATBSI432MsgDLCError_Cnt_M_u08	214
PrevISDATBSI432MsgRxTime_MSec_M_u32	789653248
PrevISDATDIRAMsgTxTime_MSec_M_u32	2180925184
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	179
PrevISDYN2CMMMsgRxTime_MSec_M_u32	967431936
PrevISDYNAASMsgDLCError_Cnt_M_u08	60
PrevISDYNAASMsgRxTime_MSec_M_u32	1135200000
PrevISDYNABRMsgDLCError_Cnt_M_u08	109
PrevISDYNABRMsgRxTime_MSec_M_u32	3820226304
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	58
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3109209856
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	0
PrevISDYNCMM388MsgRxTime_MSec_M_u32	132654848
PrevISDYNVOLMsgDLCError_Cnt_M_u08	66
PrevISDYNVOLMsgRxTime_MSec_M_u32	2451261184
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3117381376
PrevModeDiag_Cnt_M_u08	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevSrlComVehSpd_Kph_M_f32	482.903809
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	28086
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	19314
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	4627
VitesseVehicleBVRampValidCount_Cnt_M_u16	27535
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	27343
VitesseVehicleBVSigValidCount_Cnt_M_u16	39635
VitesseVehicleBV_Kph_M_f32	556.461121
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	41728
VitesseVehiculeRoues_Kph_M_f32	28.5517006
k_AASNTCEnableTimeout_mS_u16	9339
k_AASNodeAbsentDiag_Cnt_str.Threshold	31896
k_AASNodeAbsentDiag_Cnt_str.PStep	3944
k_AASNodeAbsentDiag_Cnt_str.NStep	53340
k_AASNodeAbsentTimeout_mS_u16	15181
k_AASNodeTimeout_mS_u16	23154
k_ABSNodeTimeout_mS_u16	29409
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	25055
k_ANGLEVOLANTSigValidThresh_Cnt_u16	10447
k_AngleVolantInvalidThresh_Cnt_u16	32730
k_AngleVolantValidThresh_Cnt_u16	33644
k_BSI552MsgTimeout_mS_u16	50635
k_BSINTCEnableTimeout_mS_u16	24200
k_BSINodeAbsentDiag_Cnt_str.Threshold	812
k_BSINodeAbsentDiag_Cnt_str.PStep	45195
k_BSINodeAbsentDiag_Cnt_str.NStep	560
k_BSINodeAbsentTimeout_mS_u16	7148
k_BSINodeTimeout_mS_u16	35710
k_BattOvHi_Volt_f32	29.1256008
k_BattOvLo_Volt_f32	29.9862003
k_BattUvHi_Volt_f32	25.3703995
k_BattUvLo_Volt_f32	2.95129991
k_CAVNTCEnableTimeout_mS_u16	64714
k_CAVNodeAbsentDiag_Cnt_str.Threshold	49920
k_CAVNodeAbsentDiag_Cnt_str.PStep	25956
k_CAVNodeAbsentDiag_Cnt_str.NStep	43244
k_CAVNodeAbsentTimeout_mS_u16	59295
k_CAVNodeTimeout_mS_u16	26593
k_CMM388MsgTimeout_mS_u16	8579
k_CMM388NTCEnableTimeout_mS_u16	41487
k_CMMNTCEnableTimeout_mS_u16	30757
k_CMMNodeAbsentDiag_Cnt_str.Threshold	5585
k_CMMNodeAbsentDiag_Cnt_str.PStep	53489
k_CMMNodeAbsentDiag_Cnt_str.NStep	1589
k_CMMNodeAbsentTimeout_mS_u16	20876
k_CONSANGLECPKMax_HwDeg_f32	523.387329
k_CONSANGLECPKMin_HwDeg_f32	-327.874786
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	46692
k_CONSANGLECPKSigValidThresh_Cnt_u16	45568
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	34848
k_CPKVehicleSpeedValidThresh_Cnt_u16	60011
k_CityParkInputInvalidThresh_Cnt_u16	45211
k_CityParkInputValidThresh_Cnt_u16	35218
k_ComputerRazGCTSigValidThresh_Cnt_u16	43675
k_CptTemporelSigValidThresh_Cnt_u16	40035
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	52344
k_DMDFCTCPKSigValidThresh_Cnt_u16	28044

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_DMDFCTCPKValidCount_Cnt_u16	1533
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	38299
k_DMDRELAXECPKSigValidThresh_Cnt_u16	2088
k_DMDRelaxeConsistentThresh_Cnt_u16	10198
k_DateValidThresh_Cnt_u16	45811
k_DefaultVehSpd_Kph_f32	207.855804
k_DiagMuxOnAbsentTimeout_mS_u16	25054
k_EMNodeTimeout_mS_u16	28038
k_ESPNTCEnableTimeout_mS_u16	33509
k_ESPNodeAbsentDiag_Cnt_str.Threshold	56105
k_ESPNodeAbsentDiag_Cnt_str.PStep	39129
k_ESPNodeAbsentDiag_Cnt_str.NStep	3244
k_ESPNodeAbsentTimeout_mS_u16	17268
k_EtatMTSigInvalidThresh_Cnt_u16	35032
k_EtatMTSigValidThresh_Cnt_u16	34756
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	28503
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	13463
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	10223
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	766
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	35078
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	64264
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	29921
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	55633
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	46308
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	1620
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	54572
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	5584
k_ISDATDIRASentDiag_Cnt_str.Threshold	26593
k_ISDATDIRASentDiag_Cnt_str.PStep	61445
k_ISDATDIRASentDiag_Cnt_str.NStep	10573
k_ISDATDIRASentTimeout_mS_u16	22009
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	56569
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	11220
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	65
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	877
k_ISDYNAASChkSumValidThresh_Cnt_u16	14361
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	43872
k_ISDYNAASMsgCountValidThresh_Cnt_u16	11653
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	8673
k_ISDYNAASMsgLenValidThresh_Cnt_u16	25574
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	61623
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	6846
k_ISDYNABRChkSumValidThresh_Cnt_u16	1106
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	42517
k_ISDYNABRMsgCountValidThresh_Cnt_u16	56985
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	60156
k_ISDYNABRMsgLenValidThresh_Cnt_u16	15788
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	15588
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	38698
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	5425
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	16445
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	52722
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	8758
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	34692
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	33923
k_ISDYNVOLChkSumValidThresh_Cnt_u16	16380
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	54013
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	1421
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	63942
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	23462
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	50897
k_IgnOnTimeout_mS_u16	27151
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	132.387604
k_PowerCutVehSpdLowThresh_Kph_f32	254.114105
k_PowerCutVehSpdLowTimeout_mS_u16	53175
k_VBattMaxAAS_Volt_f32	2.39459991
k_VBattMaxBSI_Volt_f32	16.7863998
k_VBattMaxCAV_Volt_f32	25.3416996
k_VBattMaxCMM388_Volt_f32	3.28110003
k_VBattMaxCMM_Volt_f32	12.0436001
k_VBattMaxESP_Volt_f32	16.9454994
k_VBattMinAAS_Volt_f32	4.56799984

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinBSI_Volt_f32	6.9454999
k_VBattMinCAV_Volt_f32	10.0743999
k_VBattMinCMM388_Volt_f32	10.9068003
k_VBattMinCMM_Volt_f32	13.5965996
k_VBattMinESP_Volt_f32	1.04359996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	42571
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	42163
k_VitesseVehicleBVRampValidThresh_Cnt_u16	8766
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	55023
k_VitesseVehicleBVSigValidThresh_Cnt_u16	29703
k_VitesseVehicleBVSpeedPassThresh_kph_f32	502.230804
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	23641
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	65109
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1826055936
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	42563
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3466657536
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	0
target_SrlComInput_Per1_Batt_Volt_f32.value	12.7601995
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4002158336
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	103
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.589274943
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1484654336
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	145
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	824813312
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	44
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3102033664
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2544953088
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1972143872
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	176
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4202178304
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3463694080
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	212
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2934826752
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	153
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	176
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	536151808
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	205

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3525355264
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4082910976
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	164
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	165
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	189
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4191786752
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	42
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.118247561
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	691673
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	173.766693
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	30344

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	31896	31896	✔
AASNodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	11222	11222	✔
AngleVolantMsgTimer_mS_M_u32	3466657536	3466657536	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	618.215149	618.215149	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2647582464	2647582464	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	1826055936	1826055936	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	2320275200	2320275200	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	121526016	121526016	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	54727	54727	✔
CMMNodeAbsentTimer_mS_M_u32	4202178304	4202178304	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	57600	57600	✔
CONSANGLECPK_HwDeg_M_f32	-548.324097	-548.324097 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	57600	57600	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3466657536	3466657536	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	35218	35218	✔
CityParkInputInvalidCount_Cnt_M_u16	33646	33646	✔
CityParkInputMsgTimer_mS_M_u32	3466657536	3466657536	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3466657536	3466657536	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3466657536	3466657536	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1826055936	1826055936	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3466657536	3466657536	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	121526016	121526016	✔
ESPNTCEnableTimer_mS_M_u32	1533880064	1533880064	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	56105	56105	✔
ESPNodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[1]	15	15	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3466657536	3466657536	✔
ElecIntTimer_mS_M_u32[1]	100	100	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3466657536	3466657536	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	50703	50703	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1484654336	1484654336	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	62989	62989	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1060255488	1060255488	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	20629	20629	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3102033664	3102033664	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	43120	43120	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2544953088	2544953088	✔
ISDATDIRASentFltAcc_Cnt_M_u16	26593	26593	✔
ISDATDIRASentTimer_mS_M_u32	3466657536	3466657536	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	13421	13421	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	23649	23649	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2934826752	2934826752	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3466657536	3466657536	✔
IgnOnTimer_mS_M_u32	1570506496	1570506496	✔
IgnTimeOff_Sec_M_u32	2450823047	2450823047	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1484654336	1484654336	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	145	145	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	824813312	824813312	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	44	44	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3102033664	3102033664	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	74	74	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2544953088	2544953088	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2180925184	2180925184	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	176	176	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4202178304	4202178304	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	72	72	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3463694080	3463694080	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2934826752	2934826752	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	536151808	536151808	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	205	205	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3525355264	3525355264	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	34	34	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4082910976	4082910976	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4191786752	4191786752	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	482.903809	482.903809	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	556.461121	556.461121	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	28.5517006	28.5517006	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	618.215149	618.215149	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	57600	57600	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2450823047	2450823047	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-548.324097	-548.324097 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	207.855804	207.855804	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	3	ValidityNTCProcessing	3	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.207 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	57695744
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	29870
AASNodeAbsentTimer_mS_M_u32	2386710016
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	18787
ANGLEVOLANTSigValidCount_Cnt_M_u16	39254

Name	Input Value
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	60603
AngleVolantMsgTimer_mS_M_u32	57695744
AngleVolantValidCount_Cnt_M_u16	63070
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	253.778473
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	713952768
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2138344960
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3084189184
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	939507200
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	3322
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2116386304
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	32943
CAVNodeAbsentTimer_mS_M_u32	3346722304
CDD_SrlComVehSpd_Kph_G_f32	32.7831993
CMM388NTCEnableTimer_mS_M_u32	108736000
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	292613632
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	44677
CMMNodeAbsentTimer_mS_M_u32	2894708224
CONSANGLECPKSigInvalidCount_Cnt_M_u16	19515
CONSANGLECPKSigValidCount_Cnt_M_u16	57982
CONSANGLECPK_Cnt_M_u16	1785
CONSANGLECPK_HwDeg_M_f32	-240.376999
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	1785
CPKVehicleSpeedMsgTimer_mS_M_u32	2730450432
CPKVehicleSpeedValidCount_Cnt_M_u16	14570
CityParkInputConsistentCount_Cnt_M_u16	20994
CityParkInputInvalidCount_Cnt_M_u16	40308
CityParkInputMsgTimer_mS_M_u32	1484654336
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3538308608
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	1618
ComputerRazGCTSigInvalidTimer_mS_M_u32	3748883968
ComputerRazGCTSigValidCount_Cnt_M_u16	65351
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	24016
DMDFCTCPKSigValidCount_Cnt_M_u16	16299
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56885
DMDRELAXECPKSigValidCount_Cnt_M_u16	34728
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	27976
DateInvalidTimer_mS_M_u32	2138344960
DiagMuxOnAbsentTimer_mS_M_u32	2859867648
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	939507200
ESPNTCEnableTimer_mS_M_u32	984829440
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	45876
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	54
EffacDefaultDiagTimer_mS_M_u32[1]	64
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	655
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	660045312
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	51658
EtatMTSigValidCount_Cnt_M_u16	54249
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	55053

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	18128
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	9121
ISDAT4V2BSI552MsgTimer_mS_M_u32	3828203008
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	36049
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	8121
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	54249
ISDATBSI3F2MsgTimer_mS_M_u32	3080986112
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	43580
ISDATBSI412MsgLenValidCount_Cnt_M_u16	1107
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	51658
ISDATBSI412MsgTimer_mS_M_u32	916348416
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	6441
ISDATBSI432MsgLenValidCount_Cnt_M_u16	37080
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	23104
ISDATDIRASentFltAcc_Cnt_M_u16	4852
ISDATDIRASentTimer_mS_M_u32	2730450432
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	15015
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	63070
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	58087
ISDYN2CMMMsgTimer_mS_M_u32	1941786112
ISDYNAASChkSumInvalidCount_Cnt_M_u16	21888
ISDYNAASChkSumValidCount_Cnt_M_u16	51348
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	41333
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	54634
ISDYNAASMsgLenValidCount_Cnt_M_u16	49781
ISDYNAASMsgTimeValidCount_Cnt_M_u16	21888
ISDYNAASMsgTimer_mS_M_u32	4225183232
ISDYNABRChkSumInvalidCount_Cnt_M_u16	11378
ISDYNABRChkSumValidCount_Cnt_M_u16	31534
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	35607
ISDYNABRMsgCountValidCount_Cnt_M_u16	53611
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	38098
ISDYNABRMsgLenValidCount_Cnt_M_u16	15957
ISDYNABRMsgTimeValidCount_Cnt_M_u16	1785
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	86
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	57
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	54249
ISDYNCMM208MsgTimer_mS_M_u32	4161998336
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	195
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	163
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	65535
ISDYNCMM388MsgTimer_mS_M_u32	1694674432
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	37225
ISDYNVOLChkSumValidCount_Cnt_M_u16	20012
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	62974
ISDYNVOLMsgCountValidCount_Cnt_M_u16	15961
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	56477
ISDYNVOLMsgLenValidCount_Cnt_M_u16	44993
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	44677
ISDYNVOLMsgTimer_mS_M_u32	3234819584
IgnOnTimer_mS_M_u32	128364032
IgnTimeOff_Sec_M_u32	2809228723
ManVehSpd_Kph_M_f32	171.850296
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	22
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	24
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	259661312
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	235
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1246494208
PrevISDATBSI412MsgDLCError_Cnt_M_u08	200
PrevISDATBSI412MsgRxTime_MSec_M_u32	1540091392
PrevISDATBSI432MsgDLCError_Cnt_M_u08	63
PrevISDATBSI432MsgRxTime_MSec_M_u32	1338461696

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
PrevISDATDIRAMsgTxTime_MSec_M_u32	4085247488
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	156
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2931637760
PrevISDYNAASMsgDLCError_Cnt_M_u08	38
PrevISDYNAASMsgRxTime_MSec_M_u32	3162336768
PrevISDYNABRMsgDLCError_Cnt_M_u08	158
PrevISDYNABRMsgRxTime_MSec_M_u32	3579751936
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	88
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1065512448
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	171
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3779218944
PrevISDYNVOLMsgDLCError_Cnt_M_u08	151
PrevISDYNVOLMsgRxTime_MSec_M_u32	1999171072
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1288461824
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	462.570007
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	37784
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	26403
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	23169
VitesseVehicleBVRampValidCount_Cnt_M_u16	47820
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	14796
VitesseVehicleBVSigValidCount_Cnt_M_u16	13951
VitesseVehicleBV_Kph_M_f32	44.4832001
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	65535
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	47736
VitesseVehiculeRoues_Kph_M_f32	129.654099
k_AASNTCEnableTimeout_mS_u16	59528
k_AASNodeAbsentDiag_Cnt_str.Threshold	40324
k_AASNodeAbsentDiag_Cnt_str.PStep	16467
k_AASNodeAbsentDiag_Cnt_str.NStep	8806
k_AASNodeAbsentTimeout_mS_u16	59601
k_AASNodeTimeout_mS_u16	14883
k_ABSNodeTimeout_mS_u16	58133
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	26844
k_ANGLEVOLANTSigValidThresh_Cnt_u16	20683
k_AngleVolantInvalidThresh_Cnt_u16	14250
k_AngleVolantValidThresh_Cnt_u16	40308
k_BSI552MsgTimeout_mS_u16	15895
k_BSINTCEnableTimeout_mS_u16	22241
k_BSINodeAbsentDiag_Cnt_str.Threshold	852
k_BSINodeAbsentDiag_Cnt_str.PStep	45178
k_BSINodeAbsentDiag_Cnt_str.NStep	583
k_BSINodeAbsentTimeout_mS_u16	31859
k_BSINodeTimeout_mS_u16	23104
k_BattOvHi_Volt_f32	1.80519998
k_BattOvLo_Volt_f32	20.7735996
k_BattUvHi_Volt_f32	3.73979998
k_BattUvLo_Volt_f32	9.64680004
k_CAVNTCEnableTimeout_mS_u16	10586
k_CAVNodeAbsentDiag_Cnt_str.Threshold	27309
k_CAVNodeAbsentDiag_Cnt_str.PStep	47537
k_CAVNodeAbsentDiag_Cnt_str.NStep	21240
k_CAVNodeAbsentTimeout_mS_u16	2525
k_CAVNodeTimeout_mS_u16	47511
k_CMM388MsgTimeout_mS_u16	34734
k_CMM388NTCEnableTimeout_mS_u16	13834
k_CMMNTCEnableTimeout_mS_u16	26249
k_CMMNodeAbsentDiag_Cnt_str.Threshold	3714

Name	Input Value
k_CMMNodeAbsentDiag_Cnt_str.PStep	39970
k_CMMNodeAbsentDiag_Cnt_str.NStep	5381
k_CMMNodeAbsentTimeout_mS_u16	57044
k_CONSANGLECPKMax_HwDeg_f32	651.50708
k_CONSANGLECPKMin_HwDeg_f32	-656.809204
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	37772
k_CONSANGLECPKSigValidThresh_Cnt_u16	36216
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	59673
k_CPKVehicleSpeedValidThresh_Cnt_u16	63671
k_CityParkInputInvalidThresh_Cnt_u16	61416
k_CityParkInputValidThresh_Cnt_u16	20994
k_ComputerRazGCTSigValidThresh_Cnt_u16	10023
k_CptTemporelSigValidThresh_Cnt_u16	61071
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	42962
k_DMDFCTCPKSigValidThresh_Cnt_u16	37205
k_DMDFCTCPKValidCount_Cnt_u16	41026
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	58087
k_DMDRELAXECPKSigValidThresh_Cnt_u16	14338
k_DMDRelaxeConsistentThresh_Cnt_u16	4344
k_DateValidThresh_Cnt_u16	9121
k_DefaultVehSpd_Kph_f32	65.1621017
k_DiagMuxOnAbsentTimeout_mS_u16	31839
k_EMNodeTimeout_mS_u16	31912
k_ESPNTCEnableTimeout_mS_u16	53259
k_ESPNodeAbsentDiag_Cnt_str.Threshold	42136
k_ESPNodeAbsentDiag_Cnt_str.PStep	51528
k_ESPNodeAbsentDiag_Cnt_str.NStep	62779
k_ESPNodeAbsentTimeout_mS_u16	43292
k_EtatMTSigInvalidThresh_Cnt_u16	39729
k_EtatMTSigValidThresh_Cnt_u16	52013
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	53108
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	64628
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	10987
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	27134
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	29862
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	31456
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	47062
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	51013
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	50125
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	59133
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	22324
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	22410
k_ISDATDIRASentDiag_Cnt_str.Threshold	40598
k_ISDATDIRASentDiag_Cnt_str.PStep	346
k_ISDATDIRASentDiag_Cnt_str.NStep	15969
k_ISDATDIRASentTimeout_mS_u16	63438
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	58895
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	60603
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	51191
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	49010
k_ISDYNAASChkSumValidThresh_Cnt_u16	20014
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	40471
k_ISDYNAASMsgCountValidThresh_Cnt_u16	9323
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	13334
k_ISDYNAASMsgLenValidThresh_Cnt_u16	60871
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39187
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	21760
k_ISDYNABRChkSumValidThresh_Cnt_u16	25859
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	8186
k_ISDYNABRMsgCountValidThresh_Cnt_u16	813
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	33157
k_ISDYNABRMsgLenValidThresh_Cnt_u16	50740
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	54348
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	59196
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	4197
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	29890
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	23651
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	60502
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	61740
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	35439
k_ISDYNVOLChkSumValidThresh_Cnt_u16	46278
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	35393
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	46546

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	20006
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	9541
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	57351
k_IgnOnTimeout_mS_u16	2507
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	236.066895
k_PowerCutVehSpdLowThresh_Kph_f32	230.887207
k_PowerCutVehSpdLowTimeout_mS_u16	54996
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	5.22910023
k_VBattMaxCAV_Volt_f32	16.3337002
k_VBattMaxCMM388_Volt_f32	28.4391003
k_VBattMaxCMM_Volt_f32	10.7561998
k_VBattMaxESP_Volt_f32	20.6198997
k_VBattMinAAS_Volt_f32	23.3539009
k_VBattMinBSI_Volt_f32	4.61990023
k_VBattMinCAV_Volt_f32	20.4664001
k_VBattMinCMM388_Volt_f32	9.26799965
k_VBattMinCMM_Volt_f32	28.3658009
k_VBattMinESP_Volt_f32	10.7561998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	21017
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	29600
k_VitesseVehicleBVRampValidThresh_Cnt_u16	35070
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	41260
k_VitesseVehicleBVSigValidThresh_Cnt_u16	42659
k_VitesseVehicleBVSpeedPassThresh_kph_f32	515.474609
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	5039
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	39546
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2138344960
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16 Elaps	57719
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	511165952
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target Rte Inst Ap SrlComInput.SrlComInput Per1 ISDATBSI432MsgDLCError C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	171
target_SrlComInput_Per1_Batt_Volt_f32.value	18.6856995
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3910565376
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	34
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.779292524
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	520138240
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	199
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1266535936
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	204
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2865425920
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1156058624
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	567619072
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1234324992
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3290394112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	45
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	109
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	127

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	179
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	858852864
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	50
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	106
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1687924224
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	77123072
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2540039680
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	80
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	132
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	222
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3710778880
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	4051
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.738414943
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	986834
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	8.17940044
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	16674

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	511165952	511165952	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	40324	40324	✔
AASNodeAbsentTimer_mS_M_u32	511165952	511165952	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	60603	60603	✔
AngleVolantMsgTimer_mS_M_u32	511165952	511165952	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	253.778473	253.778473	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	511165952	511165952	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	511165952	511165952	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	511165952	511165952	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	511165952	511165952	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	511165952	511165952	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	39296	39296	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CMMNodeAbsentTimer_mS_M_u32	1234324992	1234324992	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	1785	1785	✔
CONSANGLECPK_HwDeg_M_f32	-240.376999	-240.376999 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	1787	1787	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	511165952	511165952	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	20994	20994	✔
CityParkInputInvalidCount_Cnt_M_u16	40310	40310	✔
CityParkInputMsgTimer_mS_M_u32	511165952	511165952	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	511165952	511165952	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	511165952	511165952	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	511165952	511165952	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	511165952	511165952	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	511165952	511165952	✔
ESPNTCEnableTimer_mS_M_u32	984829440	984829440	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	42136	42136	✔
ESPNodeAbsentTimer_mS_M_u32	511165952	511165952	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	54	54	✔
EffacDefaultDiagTimer_mS_M_u32[1]	64	64	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	65	65	✔
ElecIntTimer_mS_M_u32[1]	655	655	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	511165952	511165952	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATDIRASentFltAcc_Cnt_M_u16	40598	40598	✔
ISDATDIRASentTimer_mS_M_u32	511165952	511165952	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	11379	11379	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	35607	35607	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	858852864	858852864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	511165952	511165952	✔
IgnOnTimer_mS_M_u32	128364032	128364032	✔
IgnTimeOff_Sec_M_u32	2809228723	2809228723	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	113	113	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	520138240	520138240	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	199	199	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1266535936	1266535936	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	204	204	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2865425920	2865425920	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	135	135	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1156058624	1156058624	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4085247488	4085247488	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	67	67	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1234324992	1234324992	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	83	83	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3290394112	3290394112	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	158	158	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	858852864	858852864	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1687924224	1687924224	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	174	174	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	77123072	77123072	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	135	135	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2540039680	2540039680	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3710778880	3710778880	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	462.570007	462.570007	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	44.4832001	44.4832001	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	129.654099	129.654099	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	253.778473	253.778473	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	1785	1785	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2809228723	2809228723	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-240.376999	-240.376999 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	65.1621017	65.1621017	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0133	0x0133	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	2	ValidityNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	2	ValidityNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.208 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2017831168
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	16010
AASNodeAbsentTimer_mS_M_u32	3415202048
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	12908

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ANGLEVOLANTSigValidCount_Cnt_M_u16	40018
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	19043
AngleVolantMsgTimer_mS_M_u32	2017831168
AngleVolantValidCount_Cnt_M_u16	8697
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	661.883484
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3584858368
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2432243968
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	899139840
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3491203328
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	935
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3299232000
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	25864
CAVNodeAbsentTimer_mS_M_u32	1248196864
CDD_SrlComVehSpd_Kph_G_f32	544.758118
CMM388NTCEnableTimer_mS_M_u32	3731175680
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3296983296
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	36423
CMMNodeAbsentTimer_mS_M_u32	444172544
CONSANGLECPKSigInvalidCount_Cnt_M_u16	14565
CONSANGLECPKSigValidCount_Cnt_M_u16	4059
CONSANGLECPK_Cnt_M_u16	20074
CONSANGLECPK_HwDeg_M_f32	734.343872
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	20074
CPKVehicleSpeedMsgTimer_mS_M_u32	2522392832
CPKVehicleSpeedValidCount_Cnt_M_u16	30078
CityParkInputConsistentCount_Cnt_M_u16	40717
CityParkInputInvalidCount_Cnt_M_u16	4538
CityParkInputMsgTimer_mS_M_u32	520138240
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2376325376
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	6558
ComputerRazGCTSigInvalidTimer_mS_M_u32	2222749952
ComputerRazGCTSigValidCount_Cnt_M_u16	60222
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	16550
DMDFCTCPKSigValidCount_Cnt_M_u16	38099
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	15350
DMDRELAXECPKSigValidCount_Cnt_M_u16	39260
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	18878
DateInvalidTimer_mS_M_u32	2432243968
DiagMuxOnAbsentTimer_mS_M_u32	3392432384
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3491203328
ESPNTCEnableTimer_mS_M_u32	3392985344
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	51704
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	80
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	286279936
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	57719
EtatMTSigValidCount_Cnt_M_u16	52441

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24687
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	43749
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	16625
ISDAT4V2BSI552MsgTimer_mS_M_u32	59607296
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	28129
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	57067
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	52441
ISDATBSI3F2MsgTimer_mS_M_u32	3668601088
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	36514
ISDATBSI412MsgLenValidCount_Cnt_M_u16	27164
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	57719
ISDATBSI412MsgTimer_mS_M_u32	381397248
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	56923
ISDATBSI432MsgLenValidCount_Cnt_M_u16	49420
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	23637
ISDATDIRASentFltAcc_Cnt_M_u16	569
ISDATDIRASentTimer_mS_M_u32	2522392832
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	60256
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	8697
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52577
ISDYN2CMMMsgTimer_mS_M_u32	3340687616
ISDYNAASChkSumInvalidCount_Cnt_M_u16	25620
ISDYNAASChkSumValidCount_Cnt_M_u16	58521
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	15540
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	4823
ISDYNAASMsgLenValidCount_Cnt_M_u16	1396
ISDYNAASMsgTimeValidCount_Cnt_M_u16	25620
ISDYNAASMsgTimer_mS_M_u32	1850816768
ISDYNABRChkSumInvalidCount_Cnt_M_u16	32446
ISDYNABRChkSumValidCount_Cnt_M_u16	3148
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	57167
ISDYNABRMsgCountValidCount_Cnt_M_u16	58900
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	31520
ISDYNABRMsgLenValidCount_Cnt_M_u16	6230
ISDYNABRMsgTimeValidCount_Cnt_M_u16	20074
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	725
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1335
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	52441
ISDYNCMM208MsgTimer_mS_M_u32	3239942400
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2751
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1441
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	59529
ISDYNCMM388MsgTimer_mS_M_u32	1087289600
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	41307
ISDYNVOLChkSumValidCount_Cnt_M_u16	1233
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	45084
ISDYNVOLMsgCountValidCount_Cnt_M_u16	53449
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	12733
ISDYNVOLMsgLenValidCount_Cnt_M_u16	53779
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	36423
ISDYNVOLMsgTimer_mS_M_u32	1349024000
IgnOnTimer_mS_M_u32	3907172608
IgnTimeOff_Sec_M_u32	519173141
ManVehSpd_Kph_M_f32	547.383911
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	187
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	120
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2871552256
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	106
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	439535872
PrevISDATBSI412MsgDLCError_Cnt_M_u08	40
PrevISDATBSI412MsgRxTime_MSec_M_u32	292747520
PrevISDATBSI432MsgDLCError_Cnt_M_u08	89

Name	Input Value
PrevISDATBSI432MsgRxTime_MSec_M_u32	3674265856
PrevISDATDIRAMsgTxTime_MSec_M_u32	441907456
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	108
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1105135872
PrevISDYNAASMsgDLCError_Cnt_M_u08	87
PrevISDYNAASMsgRxTime_MSec_M_u32	2505996544
PrevISDYNABRMsgDLCError_Cnt_M_u08	203
PrevISDYNABRMsgRxTime_MSec_M_u32	1606072576
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	62
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1615821056
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	85
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3532642560
PrevISDYNVOLMsgDLCError_Cnt_M_u08	127
PrevISDYNVOLMsgRxTime_MSec_M_u32	1935407360
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	204581120
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	347.588715
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	4173
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	20330
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	40850
VitesseVehicleBVRampValidCount_Cnt_M_u16	14447
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	17713
VitesseVehicleBVSigValidCount_Cnt_M_u16	43223
VitesseVehicleBV_Kph_M_f32	225.073303
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	59529
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	18285
VitesseVehiculeRoues_Kph_M_f32	527.193115
k_AASNTCEnableTimeout_mS_u16	42429
k_AASNodeAbsentDiag_Cnt_str.Threshold	10757
k_AASNodeAbsentDiag_Cnt_str.PStep	7105
k_AASNodeAbsentDiag_Cnt_str.NStep	65461
k_AASNodeAbsentTimeout_mS_u16	54944
k_AASNodeTimeout_mS_u16	54890
k_ABSNodeTimeout_mS_u16	1239
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	31554
k_ANGLEVOLANTSigValidThresh_Cnt_u16	3379
k_AngleVolantInvalidThresh_Cnt_u16	38038
k_AngleVolantValidThresh_Cnt_u16	4538
k_BSI552MsgTimeout_mS_u16	63632
k_BSINTCEnableTimeout_mS_u16	1331
k_BSINodeAbsentDiag_Cnt_str.Threshold	26412
k_BSINodeAbsentDiag_Cnt_str.PStep	34315
k_BSINodeAbsentDiag_Cnt_str.NStep	15280
k_BSINodeAbsentTimeout_mS_u16	31547
k_BSINodeTimeout_mS_u16	23637
k_BattOvHi_Volt_f32	31.5
k_BattOvLo_Volt_f32	7.83199978
k_BattUvHi_Volt_f32	21.5774994
k_BattUvLo_Volt_f32	25.4067993
k_CAVNTCEnableTimeout_mS_u16	34312
k_CAVNodeAbsentDiag_Cnt_str.Threshold	9850
k_CAVNodeAbsentDiag_Cnt_str.PStep	55599
k_CAVNodeAbsentDiag_Cnt_str.NStep	26463
k_CAVNodeAbsentTimeout_mS_u16	382
k_CAVNodeTimeout_mS_u16	24785
k_CMM388MsgTimeout_mS_u16	1418
k_CMM388NTCEnableTimeout_mS_u16	27254
k_CMMNTCEnableTimeout_mS_u16	49337

Name	Input Value
k_CMMNodeAbsentDiag_Cnt_str.Threshold	32647
k_CMMNodeAbsentDiag_Cnt_str.PStep	42126
k_CMMNodeAbsentDiag_Cnt_str.NStep	57005
k_CMMNodeAbsentTimeout_mS_u16	19033
k_CONSANGLECPKMax_HwDeg_f32	268.244202
k_CONSANGLECPKMin_HwDeg_f32	-605.499512
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	33391
k_CONSANGLECPKSigValidThresh_Cnt_u16	52845
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	8584
k_CPKVehicleSpeedValidThresh_Cnt_u16	20273
k_CityParkInputInvalidThresh_Cnt_u16	35932
k_CityParkInputValidThresh_Cnt_u16	40717
k_ComputerRazGCTSigValidThresh_Cnt_u16	30431
k_CptTemporelSigValidThresh_Cnt_u16	19049
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	16928
k_DMDFCTCPKSigValidThresh_Cnt_u16	8022
k_DMDFCTCPKValidCount_Cnt_u16	27087
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	52577
k_DMDRELAXECPKSigValidThresh_Cnt_u16	51150
k_DMDRelaxeConsistentThresh_Cnt_u16	38124
k_DateValidThresh_Cnt_u16	16625
k_DefaultVehSpd_Kph_f32	139.602707
k_DiagMuxOnAbsentTimeout_mS_u16	1592
k_EMNodeTimeout_mS_u16	39838
k_ESPNTCEnableTimeout_mS_u16	59124
k_ESPNodeAbsentDiag_Cnt_str.Threshold	40274
k_ESPNodeAbsentDiag_Cnt_str.PStep	1844
k_ESPNodeAbsentDiag_Cnt_str.NStep	56738
k_ESPNodeAbsentTimeout_mS_u16	2945
k_EtatMTSigInvalidThresh_Cnt_u16	61057
k_EtatMTSigValidThresh_Cnt_u16	55375
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	39543
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	40249
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	63570
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	51802
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	54308
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	44214
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	63060
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	4549
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	28271
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	48734
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	55159
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	36791
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	36010
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	14376
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	19043
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	44848
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	50622
k_ISDYNAASChkSumValidThresh_Cnt_u16	37708
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	42575
k_ISDYNAASMsgCountValidThresh_Cnt_u16	60692
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	63442
k_ISDYNAASMsgLenValidThresh_Cnt_u16	19326
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	21595
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	29334
k_ISDYNABRChkSumValidThresh_Cnt_u16	56396
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	51879
k_ISDYNABRMsgCountValidThresh_Cnt_u16	31437
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	5447
k_ISDYNABRMsgLenValidThresh_Cnt_u16	37112
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	17264
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	42337
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16423
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	25229
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	63852
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	41810
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	63122
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	31241
k_ISDYNVOLChkSumValidThresh_Cnt_u16	58563
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	47313

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	60512
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	50275
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	18629
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	9151
k_IgnOnTimeout_mS_u16	27637
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	49.3883018
k_PowerCutVehSpdLowThresh_Kph_f32	8.92739964
k_PowerCutVehSpdLowTimeout_mS_u16	2777
k_VBattMaxAAS_Volt_f32	27.8551998
k_VBattMaxBSI_Volt_f32	28.0879002
k_VBattMaxCAV_Volt_f32	16.4626007
k_VBattMaxCMM388_Volt_f32	10.3748999
k_VBattMaxCMM_Volt_f32	4.6099
k_VBattMaxESP_Volt_f32	21.3108006
k_VBattMinAAS_Volt_f32	29.3043003
k_VBattMinBSI_Volt_f32	21.3108006
k_VBattMinCAV_Volt_f32	30.0711002
k_VBattMinCMM388_Volt_f32	23.7698994
k_VBattMinCMM_Volt_f32	16.9757004
k_VBattMinESP_Volt_f32	4.6099
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	39946
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	57652
k_VitesseVehicleBVRampValidThresh_Cnt_u16	63260
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	3025
k_VitesseVehicleBVSigValidThresh_Cnt_u16	25898
k_VitesseVehicleBVSpeedPassThresh_kph_f32	512.558228
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	44040
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	53605
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2432243968
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	85
target_SrlComInput_Per1_Batt_Volt_f32.value	9.20409966
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2278770944
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	241
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.445504785
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2329196800
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3789379840
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3765827840
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1855887616
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1951873280
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3651131648
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2256042240
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	205

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	130259200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3859003648
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	13
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3800848640
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	1
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1185216768
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1770834176
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3265
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0876433849
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	219172
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	20.3006992
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	44975

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	19045	19045	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	661.883484	661.883484	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26412	26412	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3651131648	3651131648	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	20074	20074	✔
CONSANGLECPK_HwDeg_M_f32	734.343872	734.343872 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	20074	20074	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3251510528	3251510528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	40717	40717	✔
CityParkInputInvalidCount_Cnt_M_u16	4540	4540	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3392985344	3392985344	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	40274	40274	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	80	80	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	32446	32446	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	57167	57167	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	130259200	130259200	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	3907172608	3907172608	✔
IgnTimeOff_Sec_M_u32	519173141	519173141	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	93	93	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2329196800	2329196800	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	151	151	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3789379840	3789379840	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	5	5	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3765827840	3765827840	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	143	143	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1855887616	1855887616	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	441907456	441907456	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3651131648	3651131648	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2256042240	2256042240	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	130259200	130259200	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	14	14	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3859003648	3859003648	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	13	13	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3800848640	3800848640	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	1	1	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1185216768	1185216768	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1770834176	1770834176	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	347.588715	347.588715	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	225.073303	225.073303	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	527.193115	527.193115	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	661.883484	661.883484	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	20074	20074	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	519173141	519173141	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	734.343872	734.343872 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	139.602707	139.602707	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0131	0x0131	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0132	0x0132	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔
NTC	0x0133	0x0133	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	2	ValidityNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.209 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3259201280
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	53891
AASNodeAbsentTimer_mS_M_u32	2028480256
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	32498
ANGLEVOLANTSigValidCount_Cnt_M_u16	37686
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	11220
AngleVolantMsgTimer_mS_M_u32	3259201280
AngleVolantValidCount_Cnt_M_u16	47134
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	312.092712
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2647582464
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1826055936
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2320275200
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	121526016
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	22293
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1267144448
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	36185
CAVNodeAbsentTimer_mS_M_u32	4015343360
CDD_SrlComVehSpd_Kph_G_f32	309.960602
CMM388NTCEnableTimer_mS_M_u32	648709888
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2483242752
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	56316
CMMNodeAbsentTimer_mS_M_u32	588273408
CONSANGLECPKSigInvalidCount_Cnt_M_u16	31829
CONSANGLECPKSigValidCount_Cnt_M_u16	14633
CONSANGLECPK_Cnt_M_u16	57600

Name	Input Value
CONSANGLECPK_HwDeg_M_f32	-548.324097
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	57600
CPKVehicleSpeedMsgTimer_mS_M_u32	3330176768
CPKVehicleSpeedValidCount_Cnt_M_u16	34312
CityParkInputConsistentCount_Cnt_M_u16	35218
CityParkInputInvalidCount_Cnt_M_u16	33644
CityParkInputMsgTimer_mS_M_u32	2384827392
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2807834368
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	37367
ComputerRazGCTSigInvalidTimer_mS_M_u32	4116170496
ComputerRazGCTSigValidCount_Cnt_M_u16	18043
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	65016
DMDFCTCPKSigValidCount_Cnt_M_u16	60485
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	6828
DMDRELAXECPKSigValidCount_Cnt_M_u16	26224
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	62118
DateInvalidTimer_mS_M_u32	1826055936
DiagMuxOnAbsentTimer_mS_M_u32	283916032
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	121526016
ESPNTCEnableTimer_mS_M_u32	1533880064
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	61100
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	1
EffacDefaultDiagTimer_mS_M_u32[1]	15
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	100
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	186717952
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	27450
EtatMTSigValidCount_Cnt_M_u16	48154
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	50703
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	14947
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	45811
ISDAT4V2BSI552MsgTimer_mS_M_u32	8673024
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	62989
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	63829
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	48154
ISDATBSI3F2MsgTimer_mS_M_u32	1060255488
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	20628
ISDATBSI412MsgLenValidCount_Cnt_M_u16	42701
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	27450
ISDATBSI412MsgTimer_mS_M_u32	2391373568
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	43120
ISDATBSI432MsgLenValidCount_Cnt_M_u16	59936
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	35710
ISDATDIRASentFltAcc_Cnt_M_u16	21314
ISDATDIRASentTimer_mS_M_u32	3330176768
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	22470
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	47134
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	38299
ISDYN2CMMMsgTimer_mS_M_u32	901719808
ISDYNAASChkSumInvalidCount_Cnt_M_u16	43581
ISDYNAASChkSumValidCount_Cnt_M_u16	34850
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	60865
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	31344
ISDYNAASMsgLenValidCount_Cnt_M_u16	20396
ISDYNAASMsgTimeValidCount_Cnt_M_u16	43581
ISDYNAASMsgTimer_mS_M_u32	976652032
ISDYNABRChkSumInvalidCount_Cnt_M_u16	13421
ISDYNABRChkSumValidCount_Cnt_M_u16	10521
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	23648

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNABRMsgCountValidCount_Cnt_M_u16	40581
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	32120
ISDYNABRMsgLenValidCount_Cnt_M_u16	56972
ISDYNABRMsgTimeValidCount_Cnt_M_u16	57600
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	85
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	55
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	48154
ISDYNCMM208MsgTimer_mS_M_u32	1341646592
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	191
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	161
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0
ISDYNCMM388MsgTimer_mS_M_u32	4180150016
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	17051
ISDYNVOLChkSumValidCount_Cnt_M_u16	18415
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	21310
ISDYNVOLMsgCountValidCount_Cnt_M_u16	51723
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	51081
ISDYNVOLMsgLenValidCount_Cnt_M_u16	39613
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	56316
ISDYNVOLMsgTimer_mS_M_u32	1692649216
IgnOnTimer_mS_M_u32	1570506496
IgnTimeOff_Sec_M_u32	2450823047
ManVehSpd_Kph_M_f32	508.664093
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	21
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	123
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1598043904
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	69
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4073690880
PrevISDATBSI412MsgDLCError_Cnt_M_u08	242
PrevISDATBSI412MsgRxTime_MSec_M_u32	2939832064
PrevISDATBSI432MsgDLCError_Cnt_M_u08	214
PrevISDATBSI432MsgRxTime_MSec_M_u32	789653248
PrevISDATDIRAMsgTxTime_MSec_M_u32	2180925184
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	179
PrevISDYN2CMMMsgRxTime_MSec_M_u32	967431936
PrevISDYNAASMsgDLCError_Cnt_M_u08	60
PrevISDYNAASMsgRxTime_MSec_M_u32	1135200000
PrevISDYNABRMsgDLCError_Cnt_M_u08	109
PrevISDYNABRMsgRxTime_MSec_M_u32	3820226304
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	58
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3109209856
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	0
PrevISDYNCMM388MsgRxTime_MSec_M_u32	132654848
PrevISDYNVOLMsgDLCError_Cnt_M_u08	66
PrevISDYNVOLMsgRxTime_MSec_M_u32	2451261184
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3117381376
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	482.903809
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	28086
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	19314
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0

Name	Input Value
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	4627
VitesseVehicleBVRampValidCount_Cnt_M_u16	27535
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	27343
VitesseVehicleBVSigValidCount_Cnt_M_u16	39635
VitesseVehicleBV_Kph_M_f32	556.461121
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	41728
VitesseVehiculeRoues_Kph_M_f32	28.5517006
k_AASNTCEnableTimeout_mS_u16	9339
k_AASNodeAbsentDiag_Cnt_str.Threshold	31896
k_AASNodeAbsentDiag_Cnt_str.PStep	3944
k_AASNodeAbsentDiag_Cnt_str.NStep	53340
k_AASNodeAbsentTimeout_mS_u16	15181
k_AASNodeTimeout_mS_u16	23154
k_ABSNodeTimeout_mS_u16	29409
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	25055
k_ANGLEVOLANTSigValidThresh_Cnt_u16	10447
k_AngleVolantInvalidThresh_Cnt_u16	32730
k_AngleVolantValidThresh_Cnt_u16	33644
k_BSI552MsgTimeout_mS_u16	50635
k_BSINTCEnableTimeout_mS_u16	24200
k_BSINodeAbsentDiag_Cnt_str.Threshold	812
k_BSINodeAbsentDiag_Cnt_str.PStep	45195
k_BSINodeAbsentDiag_Cnt_str.NStep	560
k_BSINodeAbsentTimeout_mS_u16	7148
k_BSINodeTimeout_mS_u16	35710
k_BattOvHi_Volt_f32	29.1256008
k_BattOvLo_Volt_f32	29.9862003
k_BattUvHi_Volt_f32	25.3703995
k_BattUvLo_Volt_f32	2.95129991
k_CAVNTCEnableTimeout_mS_u16	64714
k_CAVNodeAbsentDiag_Cnt_str.Threshold	49920
k_CAVNodeAbsentDiag_Cnt_str.PStep	25956
k_CAVNodeAbsentDiag_Cnt_str.NStep	43244
k_CAVNodeAbsentTimeout_mS_u16	59295
k_CAVNodeTimeout_mS_u16	26593
k_CMM388MsgTimeout_mS_u16	8579
k_CMM388NTCEnableTimeout_mS_u16	41487
k_CMMNTCEnableTimeout_mS_u16	30757
k_CMMNodeAbsentDiag_Cnt_str.Threshold	5585
k_CMMNodeAbsentDiag_Cnt_str.PStep	53489
k_CMMNodeAbsentDiag_Cnt_str.NStep	1589
k_CMMNodeAbsentTimeout_mS_u16	20876
k_CONSANGLECPKMax_HwDeg_f32	523.387329
k_CONSANGLECPKMin_HwDeg_f32	-327.874786
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	46692
k_CONSANGLECPKSigValidThresh_Cnt_u16	45568
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	34848
k_CPKVehicleSpeedValidThresh_Cnt_u16	60011
k_CityParkInputInvalidThresh_Cnt_u16	45211
k_CityParkInputValidThresh_Cnt_u16	35218
k_ComputerRazGCTSigValidThresh_Cnt_u16	43675
k_CptTemporelSigValidThresh_Cnt_u16	40035
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	52344
k_DMDFCTCPKSigValidThresh_Cnt_u16	28044
k_DMDFCTCPKValidCount_Cnt_u16	1533
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	38299
k_DMDRELAXECPKSigValidThresh_Cnt_u16	2088
k_DMDRelaxeConsistentThresh_Cnt_u16	10198
k_DateValidThresh_Cnt_u16	45811
k_DefaultVehSpd_Kph_f32	207.855804
k_DiagMuxOnAbsentTimeout_mS_u16	25054
k_EMNodeTimeout_mS_u16	28038
k_ESPNTCEnableTimeout_mS_u16	33509
k_ESPNodeAbsentDiag_Cnt_str.Threshold	56105
k_ESPNodeAbsentDiag_Cnt_str.PStep	39129
k_ESPNodeAbsentDiag_Cnt_str.NStep	3244
k_ESPNodeAbsentTimeout_mS_u16	17268
k_EtatMTSigInvalidThresh_Cnt_u16	35032
k_EtatMTSigValidThresh_Cnt_u16	34756
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	28503

Name	Input Value
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	13463
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	10223
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	766
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	35078
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	64264
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	29921
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	55633
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	46308
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	1620
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	54572
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	5584
k_ISDATDIRASentDiag_Cnt_str.Threshold	26593
k_ISDATDIRASentDiag_Cnt_str.PStep	61445
k_ISDATDIRASentDiag_Cnt_str.NStep	10573
k_ISDATDIRASentTimeout_mS_u16	22009
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	56569
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	11220
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	65
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	877
k_ISDYNAASChkSumValidThresh_Cnt_u16	14361
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	43872
k_ISDYNAASMsgCountValidThresh_Cnt_u16	11653
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	8673
k_ISDYNAASMsgLenValidThresh_Cnt_u16	25574
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	61623
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	6846
k_ISDYNABRChkSumValidThresh_Cnt_u16	1106
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	42517
k_ISDYNABRMsgCountValidThresh_Cnt_u16	56985
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	60156
k_ISDYNABRMsgLenValidThresh_Cnt_u16	15788
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	15588
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	38698
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	5425
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	16445
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	52722
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	8758
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	34692
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	33923
k_ISDYNVOLChkSumValidThresh_Cnt_u16	16380
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	54013
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	1421
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	63942
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	23462
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	50897
k_IgnOnTimeout_mS_u16	27151
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	132.387604
k_PowerCutVehSpdLowThresh_Kph_f32	254.114105
k_PowerCutVehSpdLowTimeout_mS_u16	53175
k_VBattMaxAAS_Volt_f32	2.39459991
k_VBattMaxBSI_Volt_f32	16.7863998
k_VBattMaxCAV_Volt_f32	25.3416996
k_VBattMaxCMM388_Volt_f32	3.28110003
k_VBattMaxCMM_Volt_f32	12.0436001
k_VBattMaxESP_Volt_f32	16.9454994
k_VBattMinAAS_Volt_f32	4.56799984
k_VBattMinBSI_Volt_f32	6.9454999
k_VBattMinCAV_Volt_f32	10.0743999
k_VBattMinCMM388_Volt_f32	10.9068003
k_VBattMinCMM_Volt_f32	13.5965996
k_VBattMinESP_Volt_f32	1.04359996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	42571
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	42163
k_VitesseVehicleBVRampValidThresh_Cnt_u16	8766
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	55023
k_VitesseVehicleBVSigValidThresh_Cnt_u16	29703
k_VitesseVehicleBVSpeedPassThresh_kph_f32	502.230804
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	23641
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	65109
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1826055936
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	42563
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3466657536
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	0
target_SrlComInput_Per1_Batt_Volt_f32.value	12.7601995
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4002158336
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	103
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.589274943
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1484654336
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	145
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	824813312
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	44
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3102033664
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2544953088
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1972143872
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	176
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4202178304
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3463694080
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	212
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2934826752
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	153
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	176
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	536151808
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3525355264
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4082910976
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	164
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	165
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	189
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4191786752
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	4031
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.118247561
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	191038
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	173.766693
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	30344

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	31896	31896	✔
AASNodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	11222	11222	✔
AngleVolantMsgTimer_mS_M_u32	3466657536	3466657536	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	312.092712	312.092712	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2647582464	2647582464	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	1826055936	1826055936	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	2320275200	2320275200	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	121526016	121526016	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	54727	54727	✔
CMMNodeAbsentTimer_mS_M_u32	4202178304	4202178304	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	57600	57600	✔
CONSANGLECPK_HwDeg_M_f32	-548.324097	-548.324097 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	57600	57600	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3466657536	3466657536	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	35218	35218	✔
CityParkInputInvalidCount_Cnt_M_u16	33646	33646	✔
CityParkInputMsgTimer_mS_M_u32	3466657536	3466657536	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3466657536	3466657536	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3466657536	3466657536	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1826055936	1826055936	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3466657536	3466657536	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	121526016	121526016	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ESPNTCEnableTimer_mS_M_u32	1533880064	1533880064	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	56105	56105	✔
ESPNodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[1]	15	15	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3466657536	3466657536	✔
ElecIntTimer_mS_M_u32[1]	100	100	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3466657536	3466657536	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	50703	50703	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1484654336	1484654336	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	62989	62989	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1060255488	1060255488	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	20629	20629	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3102033664	3102033664	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	43120	43120	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2544953088	2544953088	✔
ISDATDIRASentFltAcc_Cnt_M_u16	26593	26593	✔
ISDATDIRASentTimer_mS_M_u32	3466657536	3466657536	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	13421	13421	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	23649	23649	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2934826752	2934826752	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3466657536	3466657536	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
IgnOnTimer_mS_M_u32	1570506496	1570506496	✔
IgnTimeOff_Sec_M_u32	2450823047	2450823047	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1484654336	1484654336	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	145	145	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	824813312	824813312	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	44	44	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3102033664	3102033664	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	74	74	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2544953088	2544953088	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2180925184	2180925184	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	176	176	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4202178304	4202178304	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	72	72	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3463694080	3463694080	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2934826752	2934826752	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	536151808	536151808	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	205	205	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3525355264	3525355264	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	34	34	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4082910976	4082910976	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4191786752	4191786752	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	482.903809	482.903809	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	556.461121	556.461121	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	28.5517006	28.5517006	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	312.092712	312.092712	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	57600	57600	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2450823047	2450823047	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-548.324097	-548.324097 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	207.855804	207.855804	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	3	ValidityNTCProcessing	3	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.210 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	57695744
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	29870
AASNodeAbsentTimer_mS_M_u32	2386710016
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	18787
ANGLEVOLANTSigValidCount_Cnt_M_u16	39254
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	60603
AngleVolantMsgTimer_mS_M_u32	57695744
AngleVolantValidCount_Cnt_M_u16	63070
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	386.469269
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	713952768
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2138344960
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3084189184
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	939507200
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	3322

Name	Input Value
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2116386304
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	32943
CAVNodeAbsentTimer_mS_M_u32	3346722304
CDD_SrlComVehSpd_Kph_G_f32	32.7831993
CMM388NTCEnableTimer_mS_M_u32	108736000
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	292613632
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	44677
CMMNodeAbsentTimer_mS_M_u32	2894708224
CONSANGLECPKSigInvalidCount_Cnt_M_u16	19515
CONSANGLECPKSigValidCount_Cnt_M_u16	57982
CONSANGLECPK_Cnt_M_u16	1785
CONSANGLECPK_HwDeg_M_f32	-240.376999
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	1785
CPKVehicleSpeedMsgTimer_mS_M_u32	2730450432
CPKVehicleSpeedValidCount_Cnt_M_u16	14570
CityParkInputConsistentCount_Cnt_M_u16	20994
CityParkInputInvalidCount_Cnt_M_u16	40308
CityParkInputMsgTimer_mS_M_u32	1484654336
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3538308608
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	1618
ComputerRazGCTSigInvalidTimer_mS_M_u32	3748883968
ComputerRazGCTSigValidCount_Cnt_M_u16	65351
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	24016
DMDFCTCPKSigValidCount_Cnt_M_u16	16299
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56885
DMDRELAXECPKSigValidCount_Cnt_M_u16	34728
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	27976
DateInvalidTimer_mS_M_u32	2138344960
DiagMuxOnAbsentTimer_mS_M_u32	2859867648
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	939507200
ESPNTCEnableTimer_mS_M_u32	984829440
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	45876
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	54
EffacDefaultDiagTimer_mS_M_u32[1]	64
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	655
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	660045312
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	51658
EtatMTSigValidCount_Cnt_M_u16	54249
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	55053
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	18128
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	9121
ISDAT4V2BSI552MsgTimer_mS_M_u32	3828203008
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	36049
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	8121
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	54249
ISDATBSI3F2MsgTimer_mS_M_u32	3080986112
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	43580
ISDATBSI412MsgLenValidCount_Cnt_M_u16	1107
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	51658
ISDATBSI412MsgTimer_mS_M_u32	916348416
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	6441
ISDATBSI432MsgLenValidCount_Cnt_M_u16	37080
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	23104
ISDATDIRASentFltAcc_Cnt_M_u16	4852
ISDATDIRASentTimer_mS_M_u32	2730450432

Name	Input Value
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	15015
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	63070
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	58087
ISDYN2CMMMsgTimer_mS_M_u32	1941786112
ISDYNAASChkSumInvalidCount_Cnt_M_u16	21888
ISDYNAASChkSumValidCount_Cnt_M_u16	51348
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	41333
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	54634
ISDYNAASMsgLenValidCount_Cnt_M_u16	49781
ISDYNAASMsgTimeValidCount_Cnt_M_u16	21888
ISDYNAASMsgTimer_mS_M_u32	4225183232
ISDYNABRChkSumInvalidCount_Cnt_M_u16	11378
ISDYNABRChkSumValidCount_Cnt_M_u16	31534
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	35607
ISDYNABRMsgCountValidCount_Cnt_M_u16	53611
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	38098
ISDYNABRMsgLenValidCount_Cnt_M_u16	15957
ISDYNABRMsgTimeValidCount_Cnt_M_u16	1785
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	86
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	57
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	54249
ISDYNCMM208MsgTimer_mS_M_u32	4161998336
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	195
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	163
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	65535
ISDYNCMM388MsgTimer_mS_M_u32	1694674432
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	37225
ISDYNVOLChkSumValidCount_Cnt_M_u16	20012
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	62974
ISDYNVOLMsgCountValidCount_Cnt_M_u16	15961
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	56477
ISDYNVOLMsgLenValidCount_Cnt_M_u16	44993
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	44677
ISDYNVOLMsgTimer_mS_M_u32	3234819584
IgnOnTimer_mS_M_u32	128364032
IgnTimeOff_Sec_M_u32	2809228723
ManVehSpd_Kph_M_f32	171.850296
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	22
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	24
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	259661312
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	235
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1246494208
PrevISDATBSI412MsgDLCError_Cnt_M_u08	200
PrevISDATBSI412MsgRxTime_MSec_M_u32	1540091392
PrevISDATBSI432MsgDLCError_Cnt_M_u08	63
PrevISDATBSI432MsgRxTime_MSec_M_u32	1338461696
PrevISDATDIRAMsgTxTime_MSec_M_u32	4085247488
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	156
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2931637760
PrevISDYNAASMsgDLCError_Cnt_M_u08	38
PrevISDYNAASMsgRxTime_MSec_M_u32	3162336768
PrevISDYNABRMsgDLCError_Cnt_M_u08	158
PrevISDYNABRMsgRxTime_MSec_M_u32	3579751936
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	88
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1065512448
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	171
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3779218944
PrevISDYNVOLMsgDLCError_Cnt_M_u08	151
PrevISDYNVOLMsgRxTime_MSec_M_u32	1999171072
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1288461824
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	462.570007

Name	Input Value
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	37784
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	26403
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	23169
VitesseVehicleBVRampValidCount_Cnt_M_u16	47820
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	14796
VitesseVehicleBVSigValidCount_Cnt_M_u16	13951
VitesseVehicleBV_Kph_M_f32	44.4832001
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	65535
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	47736
VitesseVehiculeRoues_Kph_M_f32	129.654099
k_AASNTCEnableTimeout_mS_u16	59528
k_AASNodeAbsentDiag_Cnt_str.Threshold	40324
k_AASNodeAbsentDiag_Cnt_str.PStep	16467
k_AASNodeAbsentDiag_Cnt_str.NStep	8806
k_AASNodeAbsentTimeout_mS_u16	59601
k_AASNodeTimeout_mS_u16	14883
k_ABSNodeTimeout_mS_u16	58133
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	26844
k_ANGLEVOLANTSigValidThresh_Cnt_u16	20683
k_AngleVolantInvalidThresh_Cnt_u16	14250
k_AngleVolantValidThresh_Cnt_u16	40308
k_BSI552MsgTimeout_mS_u16	15895
k_BSINTCEnableTimeout_mS_u16	22241
k_BSINodeAbsentDiag_Cnt_str.Threshold	852
k_BSINodeAbsentDiag_Cnt_str.PStep	45178
k_BSINodeAbsentDiag_Cnt_str.NStep	583
k_BSINodeAbsentTimeout_mS_u16	31859
k_BSINodeTimeout_mS_u16	23104
k_BattOvHi_Volt_f32	1.80519998
k_BattOvLo_Volt_f32	20.7735996
k_BattUvHi_Volt_f32	3.73979998
k_BattUvLo_Volt_f32	9.64680004
k_CAVNTCEnableTimeout_mS_u16	10586
k_CAVNodeAbsentDiag_Cnt_str.Threshold	27309
k_CAVNodeAbsentDiag_Cnt_str.PStep	47537
k_CAVNodeAbsentDiag_Cnt_str.NStep	21240
k_CAVNodeAbsentTimeout_mS_u16	2525
k_CAVNodeTimeout_mS_u16	47511
k_CMM388MsgTimeout_mS_u16	34734
k_CMM388NTCEnableTimeout_mS_u16	13834
k_CMMNTCEnableTimeout_mS_u16	26249
k_CMMNodeAbsentDiag_Cnt_str.Threshold	3714
k_CMMNodeAbsentDiag_Cnt_str.PStep	39970
k_CMMNodeAbsentDiag_Cnt_str.NStep	5381
k_CMMNodeAbsentTimeout_mS_u16	57044
k_CONSANGLECPKMax_HwDeg_f32	651.50708
k_CONSANGLECPKMin_HwDeg_f32	-656.809204
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	37772
k_CONSANGLECPKSigValidThresh_Cnt_u16	36216
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	59673
k_CPKVehicleSpeedValidThresh_Cnt_u16	63671
k_CityParkInputInvalidThresh_Cnt_u16	61416
k_CityParkInputValidThresh_Cnt_u16	20994
k_ComputerRazGCTSigValidThresh_Cnt_u16	10023
k_CptTemporelSigValidThresh_Cnt_u16	61071
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	42962
k_DMDFCTCPKSigValidThresh_Cnt_u16	37205
k_DMDFCTCPKValidCount_Cnt_u16	41026

Name	Input Value
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	58087
k_DMDRELAXECPKSigValidThresh_Cnt_u16	14338
k_DMDRelaxeConsistentThresh_Cnt_u16	4344
k_DateValidThresh_Cnt_u16	9121
k_DefaultVehSpd_Kph_f32	65.1621017
k_DiagMuxOnAbsentTimeout_mS_u16	31839
k_EMNodeTimeout_mS_u16	31912
k_ESPNTCEnableTimeout_mS_u16	53259
k_ESPNodeAbsentDiag_Cnt_str.Threshold	42136
k_ESPNodeAbsentDiag_Cnt_str.PStep	51528
k_ESPNodeAbsentDiag_Cnt_str.NStep	62779
k_ESPNodeAbsentTimeout_mS_u16	43292
k_EtatMTSigInvalidThresh_Cnt_u16	39729
k_EtatMTSigValidThresh_Cnt_u16	52013
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	53108
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	64628
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	10987
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	27134
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	29862
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	31456
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	47062
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	51013
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	50125
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	59133
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	22324
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	22410
k_ISDATDIRASentDiag_Cnt_str.Threshold	40598
k_ISDATDIRASentDiag_Cnt_str.PStep	346
k_ISDATDIRASentDiag_Cnt_str.NStep	15969
k_ISDATDIRASentTimeout_mS_u16	63438
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	58895
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	60603
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	51191
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	49010
k_ISDYNAASChkSumValidThresh_Cnt_u16	20014
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	40471
k_ISDYNAASMsgCountValidThresh_Cnt_u16	9323
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	13334
k_ISDYNAASMsgLenValidThresh_Cnt_u16	60871
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39187
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	21760
k_ISDYNABRChkSumValidThresh_Cnt_u16	25859
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	8186
k_ISDYNABRMsgCountValidThresh_Cnt_u16	813
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	33157
k_ISDYNABRMsgLenValidThresh_Cnt_u16	50740
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	54348
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	59196
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	4197
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	29890
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	23651
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	60502
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	61740
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	35439
k_ISDYNVOLChkSumValidThresh_Cnt_u16	46278
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	35393
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	46546
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	20006
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	9541
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	57351
k_IgnOnTimeout_mS_u16	2507
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	236.066895
k_PowerCutVehSpdLowThresh_Kph_f32	230.887207
k_PowerCutVehSpdLowTimeout_mS_u16	54996
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	5.22910023
k_VBattMaxCAV_Volt_f32	16.3337002
k_VBattMaxCMM388_Volt_f32	28.4391003
k_VBattMaxCMM_Volt_f32	10.7561998
k_VBattMaxESP_Volt_f32	20.6198997
k_VBattMinAAS_Volt_f32	23.3539009
k_VBattMinBSI_Volt_f32	4.61990023

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinCAV_Volt_f32	20.4664001
k_VBattMinCMM388_Volt_f32	9.26799965
k_VBattMinCMM_Volt_f32	28.3658009
k_VBattMinESP_Volt_f32	10.7561998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	21017
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	29600
k_VitesseVehicleBVRampValidThresh_Cnt_u16	35070
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	41260
k_VitesseVehicleBVSigValidThresh_Cnt_u16	42659
k_VitesseVehicleBVSpeedPassThresh_kph_f32	515.474609
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	5039
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	39546
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2138344960
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	57719
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	511165952
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	171
target_SrlComInput_Per1_Batt_Volt_f32.value	18.6856995
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3910565376
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	34
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.779292524
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	520138240
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	199
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1266535936
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	204
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2865425920
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1156058624
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	567619072
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1234324992
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3290394112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	45
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	109
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	179
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	858852864
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	50
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	106
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1687924224
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	77123072

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2540039680
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	80
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	132
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	222
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3710778880
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2992
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.738414943
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	582133
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	8.17940044
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	16674

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	511165952	511165952	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	40324	40324	✔
AASNodeAbsentTimer_mS_M_u32	511165952	511165952	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	60603	60603	✔
AngleVolantMsgTimer_mS_M_u32	511165952	511165952	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	386.469269	386.469269	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	511165952	511165952	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	511165952	511165952	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	511165952	511165952	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	511165952	511165952	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	511165952	511165952	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	39296	39296	✔
CMMNodeAbsentTimer_mS_M_u32	1234324992	1234324992	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	1785	1785	✔
CONSANGLECPK_HwDeg_M_f32	-240.376999	-240.376999 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	1787	1787	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	511165952	511165952	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	20994	20994	✔
CityParkInputInvalidCount_Cnt_M_u16	40310	40310	✔
CityParkInputMsgTimer_mS_M_u32	511165952	511165952	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	511165952	511165952	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ComputerRazGCTSigInvalidTimer_mS_M_u32	511165952	511165952	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	511165952	511165952	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	511165952	511165952	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	511165952	511165952	✔
ESPNTCEnableTimer_mS_M_u32	984829440	984829440	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	42136	42136	✔
ESPNodeAbsentTimer_mS_M_u32	511165952	511165952	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	54	54	✔
EffacDefaultDiagTimer_mS_M_u32[1]	64	64	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	65	65	✔
ElecIntTimer_mS_M_u32[1]	655	655	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	511165952	511165952	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATDIRASentFltAcc_Cnt_M_u16	40598	40598	✔
ISDATDIRASentTimer_mS_M_u32	511165952	511165952	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	11379	11379	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	35607	35607	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	858852864	858852864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	511165952	511165952	✔
IgnOnTimer_mS_M_u32	128364032	128364032	✔
IgnTimeOff_Sec_M_u32	2809228723	2809228723	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	113	113	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	520138240	520138240	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	199	199	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1266535936	1266535936	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	204	204	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2865425920	2865425920	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	135	135	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1156058624	1156058624	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4085247488	4085247488	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	67	67	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1234324992	1234324992	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	83	83	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3290394112	3290394112	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	158	158	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	858852864	858852864	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1687924224	1687924224	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	174	174	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	77123072	77123072	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	135	135	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2540039680	2540039680	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3710778880	3710778880	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	462.570007	462.570007	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	44.4832001	44.4832001	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	129.654099	129.654099	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	386.469269	386.469269	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	1785	1785	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2809228723	2809228723	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-240.376999	-240.376999 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	65.1621017	65.1621017	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0133	0x0133	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	2	ValidityNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	2	ValidityNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.211 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2017831168
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	16010
AASNodeAbsentTimer_mS_M_u32	3415202048
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	12908
ANGLEVOLANTSigValidCount_Cnt_M_u16	40018
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	19043
AngleVolantMsgTimer_mS_M_u32	2017831168
AngleVolantValidCount_Cnt_M_u16	8697
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	564.331299
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3584858368
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2432243968
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	899139840
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3491203328
BSI552NTCsEnabled_Cnt_M_lgc	0

Name	Input Value
BSINodeAbsentFltAcc_Cnt_M_u16	935
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3299232000
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	25864
CAVNodeAbsentTimer_mS_M_u32	1248196864
CDD_SrlComVehSpd_Kph_G_f32	544.758118
CMM388NTCEnableTimer_mS_M_u32	3731175680
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3296983296
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	36423
CMMNodeAbsentTimer_mS_M_u32	444172544
CONSANGLECPKSigInvalidCount_Cnt_M_u16	14565
CONSANGLECPKSigValidCount_Cnt_M_u16	4059
CONSANGLECPK_Cnt_M_u16	20074
CONSANGLECPK_HwDeg_M_f32	734.343872
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	20074
CPKVehicleSpeedMsgTimer_mS_M_u32	2522392832
CPKVehicleSpeedValidCount_Cnt_M_u16	30078
CityParkInputConsistentCount_Cnt_M_u16	40717
CityParkInputInvalidCount_Cnt_M_u16	4538
CityParkInputMsgTimer_mS_M_u32	520138240
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2376325376
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	6558
ComputerRazGCTSigInvalidTimer_mS_M_u32	2222749952
ComputerRazGCTSigValidCount_Cnt_M_u16	60222
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	16550
DMDFCTCPKSigValidCount_Cnt_M_u16	38099
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	15350
DMDRELAXECPKSigValidCount_Cnt_M_u16	39260
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	18878
DateInvalidTimer_mS_M_u32	2432243968
DiagMuxOnAbsentTimer_mS_M_u32	3392432384
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3491203328
ESPNTCEnableTimer_mS_M_u32	3392985344
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	51704
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	80
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	286279936
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	57719
EtatMTSigValidCount_Cnt_M_u16	52441
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24687
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	43749
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	16625
ISDAT4V2BSI552MsgTimer_mS_M_u32	59607296
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	28129
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	57067
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	52441
ISDATBSI3F2MsgTimer_mS_M_u32	3668601088
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	36514
ISDATBSI412MsgLenValidCount_Cnt_M_u16	27164
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	57719
ISDATBSI412MsgTimer_mS_M_u32	381397248
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	56923
ISDATBSI432MsgLenValidCount_Cnt_M_u16	49420
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	23637
ISDATDIRASentFltAcc_Cnt_M_u16	569

Name	Input Value
ISDATDIRASentTimer_mS_M_u32	2522392832
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	60256
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	8697
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52577
ISDYN2CMMMsgTimer_mS_M_u32	3340687616
ISDYNAASChkSumInvalidCount_Cnt_M_u16	25620
ISDYNAASChkSumValidCount_Cnt_M_u16	58521
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	15540
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	4823
ISDYNAASMsgLenValidCount_Cnt_M_u16	1396
ISDYNAASMsgTimeValidCount_Cnt_M_u16	25620
ISDYNAASMsgTimer_mS_M_u32	1850816768
ISDYNABRChkSumInvalidCount_Cnt_M_u16	32446
ISDYNABRChkSumValidCount_Cnt_M_u16	3148
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	57167
ISDYNABRMsgCountValidCount_Cnt_M_u16	58900
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	31520
ISDYNABRMsgLenValidCount_Cnt_M_u16	6230
ISDYNABRMsgTimeValidCount_Cnt_M_u16	20074
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	725
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1335
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	52441
ISDYNCMM208MsgTimer_mS_M_u32	3239942400
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2751
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1441
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	59529
ISDYNCMM388MsgTimer_mS_M_u32	1087289600
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	41307
ISDYNVOLChkSumValidCount_Cnt_M_u16	1233
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	45084
ISDYNVOLMsgCountValidCount_Cnt_M_u16	53449
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	12733
ISDYNVOLMsgLenValidCount_Cnt_M_u16	53779
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	36423
ISDYNVOLMsgTimer_mS_M_u32	1349024000
IgnOnTimer_mS_M_u32	3907172608
IgnTimeOff_Sec_M_u32	519173141
ManVehSpd_Kph_M_f32	547.383911
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	187
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	120
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2871552256
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	106
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	439535872
PrevISDATBSI412MsgDLCError_Cnt_M_u08	40
PrevISDATBSI412MsgRxTime_MSec_M_u32	292747520
PrevISDATBSI432MsgDLCError_Cnt_M_u08	89
PrevISDATBSI432MsgRxTime_MSec_M_u32	3674265856
PrevISDATDIRAMsgTxTime_MSec_M_u32	441907456
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	108
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1105135872
PrevISDYNAASMsgDLCError_Cnt_M_u08	87
PrevISDYNAASMsgRxTime_MSec_M_u32	2505996544
PrevISDYNABRMsgDLCError_Cnt_M_u08	203
PrevISDYNABRMsgRxTime_MSec_M_u32	1606072576
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	62
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1615821056
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	85
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3532642560
PrevISDYNVOLMsgDLCError_Cnt_M_u08	127
PrevISDYNVOLMsgRxTime_MSec_M_u32	1935407360
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	204581120
PrevModeDiag_Cnt_M_u08	0

Name	Input Value
PrevSrlComVehSpd_Kph_M_f32	347.588715
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	4173
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	20330
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	40850
VitesseVehicleBVRampValidCount_Cnt_M_u16	14447
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	17713
VitesseVehicleBVSigValidCount_Cnt_M_u16	43223
VitesseVehicleBV_Kph_M_f32	225.073303
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	59529
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	18285
VitesseVehiculeRoues_Kph_M_f32	527.193115
k_AASNTCEnableTimeout_mS_u16	42429
k_AASNodeAbsentDiag_Cnt_str.Threshold	10757
k_AASNodeAbsentDiag_Cnt_str.PStep	7105
k_AASNodeAbsentDiag_Cnt_str.NStep	65461
k_AASNodeAbsentTimeout_mS_u16	54944
k_AASNodeTimeout_mS_u16	54890
k_ABSNodeTimeout_mS_u16	1239
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	31554
k_ANGLEVOLANTSigValidThresh_Cnt_u16	3379
k_AngleVolantInvalidThresh_Cnt_u16	38038
k_AngleVolantValidThresh_Cnt_u16	4538
k_BSI552MsgTimeout_mS_u16	63632
k_BSINTCEnableTimeout_mS_u16	1331
k_BSINodeAbsentDiag_Cnt_str.Threshold	26412
k_BSINodeAbsentDiag_Cnt_str.PStep	34315
k_BSINodeAbsentDiag_Cnt_str.NStep	15280
k_BSINodeAbsentTimeout_mS_u16	31547
k_BSINodeTimeout_mS_u16	23637
k_BattOvHi_Volt_f32	31.5
k_BattOvLo_Volt_f32	7.83199978
k_BattUvHi_Volt_f32	21.5774994
k_BattUvLo_Volt_f32	25.4067993
k_CAVNTCEnableTimeout_mS_u16	34312
k_CAVNodeAbsentDiag_Cnt_str.Threshold	9850
k_CAVNodeAbsentDiag_Cnt_str.PStep	55599
k_CAVNodeAbsentDiag_Cnt_str.NStep	26463
k_CAVNodeAbsentTimeout_mS_u16	382
k_CAVNodeTimeout_mS_u16	24785
k_CMM388MsgTimeout_mS_u16	1418
k_CMM388NTCEnableTimeout_mS_u16	27254
k_CMMNTCEnableTimeout_mS_u16	49337
k_CMMNodeAbsentDiag_Cnt_str.Threshold	32647
k_CMMNodeAbsentDiag_Cnt_str.PStep	42126
k_CMMNodeAbsentDiag_Cnt_str.NStep	57005
k_CMMNodeAbsentTimeout_mS_u16	19033
k_CONSANGLECPKMax_HwDeg_f32	268.244202
k_CONSANGLECPKMin_HwDeg_f32	-605.499512
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	33391
k_CONSANGLECPKSigValidThresh_Cnt_u16	52845
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	8584
k_CPKVehicleSpeedValidThresh_Cnt_u16	20273
k_CityParkInputInvalidThresh_Cnt_u16	35932
k_CityParkInputValidThresh_Cnt_u16	40717
k_ComputerRazGCTSigValidThresh_Cnt_u16	30431
k_CptTemporelSigValidThresh_Cnt_u16	19049
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	16928
k_DMDFCTCPKSigValidThresh_Cnt_u16	8022

Name	Input Value
k_DMDFCTCPKValidCount_Cnt_u16	27087
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	52577
k_DMDRELAXECPKSigValidThresh_Cnt_u16	51150
k_DMDRelaxeConsistentThresh_Cnt_u16	38124
k_DateValidThresh_Cnt_u16	16625
k_DefaultVehSpd_Kph_f32	139.602707
k_DiagMuxOnAbsentTimeout_mS_u16	1592
k_EMNodeTimeout_mS_u16	39838
k_ESPNTCEnableTimeout_mS_u16	59124
k_ESPNodeAbsentDiag_Cnt_str.Threshold	40274
k_ESPNodeAbsentDiag_Cnt_str.PStep	1844
k_ESPNodeAbsentDiag_Cnt_str.NStep	56738
k_ESPNodeAbsentTimeout_mS_u16	2945
k_EtatMTSigInvalidThresh_Cnt_u16	61057
k_EtatMTSigValidThresh_Cnt_u16	55375
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	39543
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	40249
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	63570
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	51802
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	54308
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	44214
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	63060
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	4549
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	28271
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	48734
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	55159
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	36791
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	36010
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	14376
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	19043
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	44848
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	50622
k_ISDYNAASChkSumValidThresh_Cnt_u16	37708
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	42575
k_ISDYNAASMsgCountValidThresh_Cnt_u16	60692
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	63442
k_ISDYNAASMsgLenValidThresh_Cnt_u16	19326
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	21595
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	29334
k_ISDYNABRChkSumValidThresh_Cnt_u16	56396
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	51879
k_ISDYNABRMsgCountValidThresh_Cnt_u16	31437
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	5447
k_ISDYNABRMsgLenValidThresh_Cnt_u16	37112
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	17264
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	42337
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16423
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	25229
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	63852
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	41810
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	63122
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	31241
k_ISDYNVOLChkSumValidThresh_Cnt_u16	58563
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	47313
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	60512
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	50275
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	18629
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	9151
k_IgnOnTimeout_mS_u16	27637
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	49.3883018
k_PowerCutVehSpdLowThresh_Kph_f32	8.92739964
k_PowerCutVehSpdLowTimeout_mS_u16	2777
k_VBattMaxAAS_Volt_f32	27.8551998
k_VBattMaxBSI_Volt_f32	28.0879002
k_VBattMaxCAV_Volt_f32	16.4626007
k_VBattMaxCMM388_Volt_f32	10.3748999
k_VBattMaxCMM_Volt_f32	4.6099
k_VBattMaxESP_Volt_f32	21.3108006
k_VBattMinAAS_Volt_f32	29.3043003

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinBSI_Volt_f32	21.3108006
k_VBattMinCAV_Volt_f32	30.0711002
k_VBattMinCMM388_Volt_f32	23.7698994
k_VBattMinCMM_Volt_f32	16.9757004
k_VBattMinESP_Volt_f32	4.6099
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	39946
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	57652
k_VitesseVehicleBVRampValidThresh_Cnt_u16	63260
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	3025
k_VitesseVehicleBVSigValidThresh_Cnt_u16	25898
k_VitesseVehicleBVSpeedPassThresh_kph_f32	512.558228
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	44040
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	53605
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2432243968
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	85
target_SrlComInput_Per1_Batt_Volt_f32.value	9.20409966
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2278770944
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	241
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.445504785
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2329196800
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3789379840
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3765827840
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1855887616
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1951873280
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3651131648
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2256042240
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	205
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	130259200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3859003648
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	13

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3800848640
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	1
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1185216768
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1770834176
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3997
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0876433849
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	388587
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	20.3006992
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	44975

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	19045	19045	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	564.331299	564.331299	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26412	26412	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3651131648	3651131648	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	20074	20074	✔
CONSANGLECPK_HwDeg_M_f32	734.343872	734.343872 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	20074	20074	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3251510528	3251510528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	40717	40717	✔
CityParkInputInvalidCount_Cnt_M_u16	4540	4540	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3392985344	3392985344	✔
ESPNTCsEnabled_Cnt_M_lgc	1	1	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	40274	40274	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	80	80	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	32446	32446	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	57167	57167	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	1	1	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	130259200	130259200	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	3907172608	3907172608	✔
IgnTimeOff_Sec_M_u32	519173141	519173141	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	93	93	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2329196800	2329196800	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	151	151	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3789379840	3789379840	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	5	5	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3765827840	3765827840	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	143	143	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1855887616	1855887616	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	441907456	441907456	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3651131648	3651131648	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2256042240	2256042240	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	130259200	130259200	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	14	14	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3859003648	3859003648	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	13	13	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3800848640	3800848640	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	1	1	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1185216768	1185216768	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1770834176	1770834176	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	347.588715	347.588715	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	225.073303	225.073303	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1	1	✔
VitesseVehiculeRoues_Kph_M_f32	527.193115	527.193115	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	564.331299	564.331299	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	20074	20074	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	519173141	519173141	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	734.343872	734.343872 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	139.602707	139.602707	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	2	ValidityNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.212 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3143099904
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	7718
AASNodeAbsentTimer_mS_M_u32	3218068992
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	21546
ANGLEVOLANTSigValidCount_Cnt_M_u16	34868
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	851
AngleVolantMsgTimer_mS_M_u32	3143099904
AngleVolantValidCount_Cnt_M_u16	62730
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	394.921295
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3375601152
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3232372224
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3862988288
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1709393408
BSI552NTCsEnabled_Cnt_M_lgc	1

Name	Input Value
BSINodeAbsentFltAcc_Cnt_M_u16	29985
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3412133376
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	7723
CAVNodeAbsentTimer_mS_M_u32	2819388928
CDD_SrlComVehSpd_Kph_G_f32	638.182495
CMM388NTCEnableTimer_mS_M_u32	1970583040
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	4056053248
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	23998
CMMNodeAbsentTimer_mS_M_u32	1789740544
CONSANGLECPKSigInvalidCount_Cnt_M_u16	1946
CONSANGLECPKSigValidCount_Cnt_M_u16	17396
CONSANGLECPK_Cnt_M_u16	6223
CONSANGLECPK_HwDeg_M_f32	671.068604
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	6223
CPKVehicleSpeedMsgTimer_mS_M_u32	50783744
CPKVehicleSpeedValidCount_Cnt_M_u16	64698
CityParkInputConsistentCount_Cnt_M_u16	6958
CityParkInputInvalidCount_Cnt_M_u16	25767
CityParkInputMsgTimer_mS_M_u32	3088068352
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1861473792
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	14922
ComputerRazGCTSigInvalidTimer_mS_M_u32	1339356672
ComputerRazGCTSigValidCount_Cnt_M_u16	61587
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	55939
DMDFCTCPKSigValidCount_Cnt_M_u16	31093
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	44604
DMDRELAXECPKSigValidCount_Cnt_M_u16	43974
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	13767
DateInvalidTimer_mS_M_u32	3232372224
DiagMuxOnAbsentTimer_mS_M_u32	3988104704
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1709393408
ESPNTCEnableTimer_mS_M_u32	3688945152
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	6148
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	80
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1439892992
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	36747
EtatMTSigValidCount_Cnt_M_u16	42305
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	6060
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	40326
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	40235
ISDAT4V2BSI552MsgTimer_mS_M_u32	3973137920
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	35727
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	12044
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	42305
ISDATBSI3F2MsgTimer_mS_M_u32	1973659136
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	54177
ISDATBSI412MsgLenValidCount_Cnt_M_u16	27727
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	36747
ISDATBSI412MsgTimer_mS_M_u32	692446720
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	62178
ISDATBSI432MsgLenValidCount_Cnt_M_u16	40
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	47964
ISDATDIRASentFltAcc_Cnt_M_u16	63632

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDATDIRASentTimer_mS_M_u32	50783744
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	22205
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	62730
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	11514
ISDYN2CMMMsgTimer_mS_M_u32	4113225216
ISDYNAASChkSumInvalidCount_Cnt_M_u16	17464
ISDYNAASChkSumValidCount_Cnt_M_u16	44897
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	11649
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	35526
ISDYNAASMsgLenValidCount_Cnt_M_u16	58087
ISDYNAASMsgTimeValidCount_Cnt_M_u16	17464
ISDYNAASMsgTimer_mS_M_u32	1079031296
ISDYNABRChkSumInvalidCount_Cnt_M_u16	15670
ISDYNABRChkSumValidCount_Cnt_M_u16	13575
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	5935
ISDYNABRMsgCountValidCount_Cnt_M_u16	40344
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	52625
ISDYNABRMsgLenValidCount_Cnt_M_u16	25899
ISDYNABRMsgTimeValidCount_Cnt_M_u16	6223
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	725
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1335
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	42305
ISDYNCMM208MsgTimer_mS_M_u32	651728384
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2751
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1441
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	39416
ISDYNCMM388MsgTimer_mS_M_u32	0
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	51080
ISDYNVOLChkSumValidCount_Cnt_M_u16	47714
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	52593
ISDYNVOLMsgCountValidCount_Cnt_M_u16	25315
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	1037
ISDYNVOLMsgLenValidCount_Cnt_M_u16	26950
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	23998
ISDYNVOLMsgTimer_mS_M_u32	2259744256
IgnOnTimer_mS_M_u32	2706388480
IgnTimeOff_Sec_M_u32	3104507551
ManVehSpd_Kph_M_f32	554.577026
Msg348Valid_Cnt_M_Igc	0
Msg432Valid_Cnt_M_Igc	0
Msg552Valid_Cnt_M_Igc	1
NetOn_Cnt_M_Igc	1
NtWrapC_Dem_ClearDTC()	187
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	53
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1496950272
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	96
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	35096064
PrevISDATBSI412MsgDLCError_Cnt_M_u08	82
PrevISDATBSI412MsgRxTime_MSec_M_u32	2013099520
PrevISDATBSI432MsgDLCError_Cnt_M_u08	128
PrevISDATBSI432MsgRxTime_MSec_M_u32	2440353280
PrevISDATDIRAMsgTxTime_MSec_M_u32	4096882176
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	205
PrevISDYN2CMMMsgRxTime_MSec_M_u32	76596736
PrevISDYNAASMsgDLCError_Cnt_M_u08	214
PrevISDYNAASMsgRxTime_MSec_M_u32	2367616512
PrevISDYNABRMsgDLCError_Cnt_M_u08	216
PrevISDYNABRMsgRxTime_MSec_M_u32	4194842112
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	3
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2420372992
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	221
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4073707008
PrevISDYNVOLMsgDLCError_Cnt_M_u08	189
PrevISDYNVOLMsgRxTime_MSec_M_u32	3799676416
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1513350656
PrevModeDiag_Cnt_M_u08	0

Name	Input Value
PrevSrlComVehSpd_Kph_M_f32	545.108521
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	25524
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	12885
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	56637
VitesseVehicleBVRampValidCount_Cnt_M_u16	61598
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	26419
VitesseVehicleBVSigValidCount_Cnt_M_u16	65533
VitesseVehicleBV_Kph_M_f32	56.1158981
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	39416
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	43769
VitesseVehiculeRoues_Kph_M_f32	471.019196
k_AASNTCEnableTimeout_mS_u16	19006
k_AASNodeAbsentDiag_Cnt_str.Threshold	10757
k_AASNodeAbsentDiag_Cnt_str.PStep	7105
k_AASNodeAbsentDiag_Cnt_str.NStep	65461
k_AASNodeAbsentTimeout_mS_u16	35421
k_AASNodeTimeout_mS_u16	58709
k_ABSNodeTimeout_mS_u16	34792
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	28021
k_ANGLEVOLANTSigValidThresh_Cnt_u16	21243
k_AngleVolantInvalidThresh_Cnt_u16	44090
k_AngleVolantValidThresh_Cnt_u16	25767
k_BSI552MsgTimeout_mS_u16	22776
k_BSINTCEnableTimeout_mS_u16	48026
k_BSINodeAbsentDiag_Cnt_str.Threshold	26412
k_BSINodeAbsentDiag_Cnt_str.PStep	34315
k_BSINodeAbsentDiag_Cnt_str.NStep	15280
k_BSINodeAbsentTimeout_mS_u16	24075
k_BSINodeTimeout_mS_u16	47964
k_BattOvHi_Volt_f32	29.4936008
k_BattOvLo_Volt_f32	8.12170029
k_BattUvHi_Volt_f32	21.5676003
k_BattUvLo_Volt_f32	26.0254993
k_CAVNTCEnableTimeout_mS_u16	38477
k_CAVNodeAbsentDiag_Cnt_str.Threshold	9850
k_CAVNodeAbsentDiag_Cnt_str.PStep	55599
k_CAVNodeAbsentDiag_Cnt_str.NStep	26463
k_CAVNodeAbsentTimeout_mS_u16	41497
k_CAVNodeTimeout_mS_u16	19062
k_CMM388MsgTimeout_mS_u16	4390
k_CMM388NTCEnableTimeout_mS_u16	13570
k_CMMNTCEnableTimeout_mS_u16	28743
k_CMMNodeAbsentDiag_Cnt_str.Threshold	32647
k_CMMNodeAbsentDiag_Cnt_str.PStep	42126
k_CMMNodeAbsentDiag_Cnt_str.NStep	57005
k_CMMNodeAbsentTimeout_mS_u16	1237
k_CONSANGLECPKMax_HwDeg_f32	150.696701
k_CONSANGLECPKMin_HwDeg_f32	-718.044922
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	3320
k_CONSANGLECPKSigValidThresh_Cnt_u16	24057
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	46091
k_CPKVehicleSpeedValidThresh_Cnt_u16	4604
k_CityParkInputInvalidThresh_Cnt_u16	28780
k_CityParkInputValidThresh_Cnt_u16	6958
k_ComputerRazGCTSigValidThresh_Cnt_u16	49573
k_CptTemporelSigValidThresh_Cnt_u16	59810
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	49297
k_DMDFCTCPKSigValidThresh_Cnt_u16	38955

Name	Input Value
k_DMDFCTCPKValidCount_Cnt_u16	7529
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	11514
k_DMDRELAXECPKSigValidThresh_Cnt_u16	34604
k_DMDRelaxeConsistentThresh_Cnt_u16	49122
k_DateValidThresh_Cnt_u16	40235
k_DefaultVehSpd_Kph_f32	84.8945999
k_DiagMuxOnAbsentTimeout_mS_u16	41845
k_EMNodeTimeout_mS_u16	16679
k_ESPNTCEnableTimeout_mS_u16	33543
k_ESPNodeAbsentDiag_Cnt_str.Threshold	40274
k_ESPNodeAbsentDiag_Cnt_str.PStep	1844
k_ESPNodeAbsentDiag_Cnt_str.NStep	56738
k_ESPNodeAbsentTimeout_mS_u16	17437
k_EtatMTSigInvalidThresh_Cnt_u16	59989
k_EtatMTSigValidThresh_Cnt_u16	52070
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	22086
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	15067
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	59063
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	10716
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	56601
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	36549
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	49839
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	65461
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	51206
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	57043
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	33184
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	24087
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	40466
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	7356
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	851
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	64115
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	45110
k_ISDYNAASChkSumValidThresh_Cnt_u16	59399
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	2607
k_ISDYNAASMsgCountValidThresh_Cnt_u16	53400
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	36698
k_ISDYNAASMsgLenValidThresh_Cnt_u16	25465
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	53315
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	59519
k_ISDYNABRChkSumValidThresh_Cnt_u16	30361
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	26657
k_ISDYNABRMsgCountValidThresh_Cnt_u16	30571
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	4286
k_ISDYNABRMsgLenValidThresh_Cnt_u16	2820
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	25322
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	33240
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	46186
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	43604
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	18218
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	47924
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	863
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	44724
k_ISDYNVOLChkSumValidThresh_Cnt_u16	32674
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	48177
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	39467
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	18791
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	19485
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	53073
k_IgnOnTimeout_mS_u16	17296
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	51.1899986
k_PowerCutVehSpdLowThresh_Kph_f32	179.2603
k_PowerCutVehSpdLowTimeout_mS_u16	5130
k_VBattMaxAAS_Volt_f32	7.12790012
k_VBattMaxBSI_Volt_f32	12.7456999
k_VBattMaxCAV_Volt_f32	11.4399996
k_VBattMaxCMM388_Volt_f32	16.9731998
k_VBattMaxCMM_Volt_f32	22.3999004
k_VBattMaxESP_Volt_f32	7.46470022
k_VBattMinAAS_Volt_f32	22.7584991

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinBSI_Volt_f32	7.46470022
k_VBattMinCAV_Volt_f32	21.9647007
k_VBattMinCMM388_Volt_f32	2.04959989
k_VBattMinCMM_Volt_f32	30.3525009
k_VBattMinESP_Volt_f32	2.39989996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	18694
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	16164
k_VitesseVehicleBVRampValidThresh_Cnt_u16	16497
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	60770
k_VitesseVehicleBVSigValidThresh_Cnt_u16	44399
k_VitesseVehicleBVSpeedPassThresh_kph_f32	186.939407
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	37163
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	23308
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3232372224
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	1
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	221
target_SrlComInput_Per1_Batt_Volt_f32.value	5.21080017
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	905053696
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	73
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.503290474
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1525298688
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3250279936
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	150
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1834776064
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1707972096
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3004085760
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1562367488
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1812002304
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	85
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	140
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	190
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	192
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	45520384
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	67
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	131
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	187
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	610612736
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	49

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2931185152
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1037530624
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	37
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	47
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	61
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	78
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	161
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	173
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3023668736
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3478
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.974099159
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	259244
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	179.622894
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	16766

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	394.921295	394.921295	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26412	26412	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1970583040	1970583040	✔
CMM388NTCsEnabled_Cnt_M_lgc	1	1	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1562367488	1562367488	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	6223	6223	✔
CONSANGLECPK_HwDeg_M_f32	671.068604	671.068604 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2	2	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3251510528	3251510528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	40274	40274	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	80	80	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2931185152	2931185152	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	2706388480	2706388480	✔
IgnTimeOff_Sec_M_u32	3104507551	3104507551	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	134	134	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1525298688	1525298688	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	238	238	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3250279936	3250279936	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	150	150	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1834776064	1834776064	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	135	135	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1707972096	1707972096	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4096882176	4096882176	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	99	99	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1562367488	1562367488	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	95	95	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1812002304	1812002304	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	49	49	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	45520384	45520384	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	610612736	610612736	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	49	49	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2931185152	2931185152	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	93	93	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1037530624	1037530624	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3023668736	3023668736	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	545.108521	545.108521	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	56.1158981	56.1158981	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	471.019196	471.019196	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	394.921295	394.921295	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	6223	6223	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3104507551	3104507551	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	671.068604	671.068604 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	84.8945999	84.8945999	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔
NTC	0x0169	0x0169	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.213 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	950997248
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	27203
AASNodeAbsentTimer_mS_M_u32	923222272
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	31286
ANGLEVOLANTSigValidCount_Cnt_M_u16	4057
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	44732
AngleVolantMsgTimer_mS_M_u32	950997248
AngleVolantValidCount_Cnt_M_u16	7703
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	700.624451
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1507590400
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1836613888
BSI412NTCsEnabled_Cnt_M_lgc	0

Name	Input Value
BSI432NTCEnableTimer_mS_M_u32	2725589248
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	512553216
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	45905
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	353612032
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	50357
CAVNodeAbsentTimer_mS_M_u32	3100729600
CDD_SrlComVehSpd_Kph_G_f32	246.667099
CMM388NTCEnableTimer_mS_M_u32	1100521728
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	867131648
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	12474
CMMNodeAbsentTimer_mS_M_u32	3090084096
CONSANGLECPKSigInvalidCount_Cnt_M_u16	52966
CONSANGLECPKSigValidCount_Cnt_M_u16	35738
CONSANGLECPK_Cnt_M_u16	14985
CONSANGLECPK_HwDeg_M_f32	634.957092
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	14985
CPKVehicleSpeedMsgTimer_mS_M_u32	3718385920
CPKVehicleSpeedValidCount_Cnt_M_u16	815
CityParkInputConsistentCount_Cnt_M_u16	15275
CityParkInputInvalidCount_Cnt_M_u16	54335
CityParkInputMsgTimer_mS_M_u32	1525298688
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3113959680
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	42455
ComputerRazGCTSigInvalidTimer_mS_M_u32	2205671680
ComputerRazGCTSigValidCount_Cnt_M_u16	36732
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	58027
DMDFCTCPKSigValidCount_Cnt_M_u16	55191
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	13312
DMDRELAXECPKSigValidCount_Cnt_M_u16	27939
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	14431
DateInvalidTimer_mS_M_u32	1836613888
DiagMuxOnAbsentTimer_mS_M_u32	1217777920
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	512553216
ESPNTCEnableTimer_mS_M_u32	1725186304
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	9130
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	201
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	9
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3183325440
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	24658
EtatMTSigValidCount_Cnt_M_u16	242
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	26288
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	18148
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	50293
ISDAT4V2BSI552MsgTimer_mS_M_u32	3250778368
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	12744
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	18704
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	242
ISDATBSI3F2MsgTimer_mS_M_u32	3905671424
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	29330
ISDATBSI412MsgLenValidCount_Cnt_M_u16	27209
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	24658
ISDATBSI412MsgTimer_mS_M_u32	652546304

Name	Input Value
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	334
ISDATBSI432MsgLenValidCount_Cnt_M_u16	64318
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	61730
ISDATDIRASentFltAcc_Cnt_M_u16	2438
ISDATDIRASentTimer_mS_M_u32	3718385920
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	46911
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	7703
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	34630
ISDYN2CMMMsgTimer_mS_M_u32	3270918400
ISDYNAASChkSumInvalidCount_Cnt_M_u16	49165
ISDYNAASChkSumValidCount_Cnt_M_u16	12369
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	4274
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	43748
ISDYNAASMsgLenValidCount_Cnt_M_u16	13376
ISDYNAASMsgTimeValidCount_Cnt_M_u16	49165
ISDYNAASMsgTimer_mS_M_u32	1359257856
ISDYNABRChkSumInvalidCount_Cnt_M_u16	42131
ISDYNABRChkSumValidCount_Cnt_M_u16	3807
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	58152
ISDYNABRMsgCountValidCount_Cnt_M_u16	428
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	6401
ISDYNABRMsgLenValidCount_Cnt_M_u16	50165
ISDYNABRMsgTimeValidCount_Cnt_M_u16	14985
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	157
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	199
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	242
ISDYNCMM208MsgTimer_mS_M_u32	351076608
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	479
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	305
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	26445
ISDYNCMM388MsgTimer_mS_M_u32	4294967295
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	50972
ISDYNVOLChkSumValidCount_Cnt_M_u16	24656
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	16865
ISDYNVOLMsgCountValidCount_Cnt_M_u16	21325
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	50063
ISDYNVOLMsgLenValidCount_Cnt_M_u16	34211
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	12474
ISDYNVOLMsgTimer_mS_M_u32	1323557120
IgnOnTimer_mS_M_u32	2349211904
IgnTimeOff_Sec_M_u32	331640398
ManVehSpd_Kph_M_f32	322.502197
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	93
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	153
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	369742080
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	250
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1794126080
PrevISDATBSI412MsgDLCError_Cnt_M_u08	104
PrevISDATBSI412MsgRxTime_MSec_M_u32	1291739392
PrevISDATBSI432MsgDLCError_Cnt_M_u08	101
PrevISDATBSI432MsgRxTime_MSec_M_u32	2518171904
PrevISDATDIRAMsgTxTime_MSec_M_u32	2825019648
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	231
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3632558336
PrevISDYNAASMsgDLCError_Cnt_M_u08	255
PrevISDYNAASMsgRxTime_MSec_M_u32	1939464448
PrevISDYNABRMsgDLCError_Cnt_M_u08	142
PrevISDYNABRMsgRxTime_MSec_M_u32	1641947392
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	174
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1042997504
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	94
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2651275520

Name	Input Value
PrevISDYNVOLMsgDLCError_Cnt_M_u08	119
PrevISDYNVOLMsgRxTime_MSec_M_u32	1099391232
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3424325888
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	469.484802
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	22554
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	32246
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	20351
VitesseVehicleBVRampValidCount_Cnt_M_u16	42779
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	42267
VitesseVehicleBVSigValidCount_Cnt_M_u16	3198
VitesseVehicleBV_Kph_M_f32	149.474503
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	26445
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	17928
VitesseVehiculeRoues_Kph_M_f32	405.886108
k_AASNTCEnableTimeout_mS_u16	8380
k_AASNodeAbsentDiag_Cnt_str.Threshold	47636
k_AASNodeAbsentDiag_Cnt_str.PStep	34578
k_AASNodeAbsentDiag_Cnt_str.NStep	62563
k_AASNodeAbsentTimeout_mS_u16	27166
k_AASNodeTimeout_mS_u16	25846
k_ABSNodeTimeout_mS_u16	44668
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	40341
k_ANGLEVOLANTSigValidThresh_Cnt_u16	3781
k_AngleVolantInvalidThresh_Cnt_u16	48904
k_AngleVolantValidThresh_Cnt_u16	54335
k_BSI552MsgTimeout_mS_u16	63499
k_BSINTCEnableTimeout_mS_u16	34598
k_BSINodeAbsentDiag_Cnt_str.Threshold	3692
k_BSINodeAbsentDiag_Cnt_str.PStep	43971
k_BSINodeAbsentDiag_Cnt_str.NStep	2216
k_BSINodeAbsentTimeout_mS_u16	32404
k_BSINodeTimeout_mS_u16	61730
k_BattOvHi_Volt_f32	19.9323997
k_BattOvLo_Volt_f32	2.13170004
k_BattUvHi_Volt_f32	16.8600998
k_BattUvLo_Volt_f32	19.9584007
k_CAVNTCEnableTimeout_mS_u16	22349
k_CAVNodeAbsentDiag_Cnt_str.Threshold	14101
k_CAVNodeAbsentDiag_Cnt_str.PStep	13590
k_CAVNodeAbsentDiag_Cnt_str.NStep	2667
k_CAVNodeAbsentTimeout_mS_u16	28907
k_CAVNodeTimeout_mS_u16	30290
k_CMM388MsgTimeout_mS_u16	37187
k_CMM388NTCEnableTimeout_mS_u16	38319
k_CMMNTCEnableTimeout_mS_u16	25504
k_CMMNodeAbsentDiag_Cnt_str.Threshold	62414
k_CMMNodeAbsentDiag_Cnt_str.PStep	42715
k_CMMNodeAbsentDiag_Cnt_str.NStep	22076
k_CMMNodeAbsentTimeout_mS_u16	43124
k_CONSANGLECPKMax_HwDeg_f32	721.588013
k_CONSANGLECPKMin_HwDeg_f32	-30.9109993
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	3661
k_CONSANGLECPKSigValidThresh_Cnt_u16	11528
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	20692
k_CPKVehicleSpeedValidThresh_Cnt_u16	58241
k_CityParkInputInvalidThresh_Cnt_u16	25329
k_CityParkInputValidThresh_Cnt_u16	15275

Name	Input Value
k_ComputerRazGCTSigValidThresh_Cnt_u16	26502
k_CptTemporelSigValidThresh_Cnt_u16	61774
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	16385
k_DMDFCTCPKSigValidThresh_Cnt_u16	10997
k_DMDFCTCPKValidCount_Cnt_u16	55929
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	34630
k_DMDRELAXECPKSigValidThresh_Cnt_u16	19058
k_DMDRelaxeConsistentThresh_Cnt_u16	63568
k_DateValidThresh_Cnt_u16	50293
k_DefaultVehSpd_Kph_f32	136.529999
k_DiagMuxOnAbsentTimeout_mS_u16	45335
k_EMNodeTimeout_mS_u16	38463
k_ESPNTCEnableTimeout_mS_u16	1569
k_ESPNodeAbsentDiag_Cnt_str.Threshold	62971
k_ESPNodeAbsentDiag_Cnt_str.PStep	11352
k_ESPNodeAbsentDiag_Cnt_str.NStep	60169
k_ESPNodeAbsentTimeout_mS_u16	2716
k_EtatMTSigInvalidThresh_Cnt_u16	55606
k_EtatMTSigValidThresh_Cnt_u16	34754
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	5667
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	51747
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	15632
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	51937
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	45801
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	53542
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	1511
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	28823
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	4578
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	63229
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	20565
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	31791
k_ISDATDIRASentDiag_Cnt_str.Threshold	1170
k_ISDATDIRASentDiag_Cnt_str.PStep	4955
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	61951
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	5184
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	44732
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	20445
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	19347
k_ISDYNAASChkSumValidThresh_Cnt_u16	62943
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	2600
k_ISDYNAASMsgCountValidThresh_Cnt_u16	26796
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	15911
k_ISDYNAASMsgLenValidThresh_Cnt_u16	31370
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	46829
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	55
k_ISDYNABRChkSumValidThresh_Cnt_u16	51115
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	55889
k_ISDYNABRMsgCountValidThresh_Cnt_u16	56884
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	6074
k_ISDYNABRMsgLenValidThresh_Cnt_u16	19114
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	55223
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	36270
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	13367
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	53753
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	41270
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	30425
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	55319
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	60761
k_ISDYNVOLChkSumValidThresh_Cnt_u16	15440
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	11043
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	28531
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	41662
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	31838
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	17923
k_IgnOnTimeout_mS_u16	40645
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	36.1437988
k_PowerCutVehSpdLowThresh_Kph_f32	107.932899
k_PowerCutVehSpdLowTimeout_mS_u16	62296
k_VBattMaxAAS_Volt_f32	20.0228996
k_VBattMaxBSI_Volt_f32	23.0855007
k_VBattMaxCAV_Volt_f32	29.0970993

Name	Input Value
k_VBattMaxCMM388_Volt_f32	21.7884998
k_VBattMaxCMM_Volt_f32	22.2889004
k_VBattMaxESP_Volt_f32	14.8550997
k_VBattMinAAS_Volt_f32	8.41909981
k_VBattMinBSI_Volt_f32	14.8550997
k_VBattMinCAV_Volt_f32	18.3736
k_VBattMinCMM388_Volt_f32	19.2851009
k_VBattMinCMM_Volt_f32	25.469101
k_VBattMinESP_Volt_f32	2.2888999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	14178
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	54985
k_VitesseVehicleBVRampValidThresh_Cnt_u16	59617
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	51024
k_VitesseVehicleBVSigValidThresh_Cnt_u16	51432
k_VitesseVehicleBVSpeedPassThresh_kph_f32	1.20869994
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	27573
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	40913
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1836613888
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	1
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	94
target_SrlComInput_Per1_Batt_Volt_f32.value	20.6443005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1499508992
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	94
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.459792793
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	101
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1194860800
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	187
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1061470464
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2833342720
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1812857088
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1892327680
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2669101312
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	230
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3740524800
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	31
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	104
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	244
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	175
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2035482880
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	28
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	44
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	121
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	133
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	182

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	192
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	146
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2529632512
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	157
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	609468672
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	231
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3815792896
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	16
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	32
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	52
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	57
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	133
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	239
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1552560384
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3844
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.949364603
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	663096
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	162.0952
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	26300

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	47636	47636	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	44734	44734	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	700.624451	700.624451	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1507590400	1507590400	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2725589248	2725589248	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	512553216	512553216	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	14101	14101	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1100521728	1100521728	✔
CMM388NTCsEnabled_Cnt_M_lgc	1	1	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2669101312	2669101312	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	14985	14985	✔
CONSANGLECPK_HwDeg_M_f32	634.957092	634.957092 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	14987	14987	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2006148864	2006148864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	15275	15275	✔
CityParkInputInvalidCount_Cnt_M_u16	54335	54335	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1836613888	1836613888	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔
EffacDefaultDiagTimer_mS_M_u32[1]	201	201	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2006148864	2006148864	✔
ElecIntTimer_mS_M_u32[1]	9	9	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	26288	26288	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1194860800	1194860800	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	12745	12745	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1061470464	1061470464	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	335	335	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1812857088	1812857088	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1170	1170	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	480	480	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	609468672	609468672	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	2349211904	2349211904	✔
IgnTimeOff_Sec_M_u32	331640398	331640398	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	101	101	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1194860800	1194860800	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	187	187	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1061470464	1061470464	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	143	143	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2833342720	2833342720	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	200	200	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1812857088	1812857088	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2825019648	2825019648	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	12	12	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2669101312	2669101312	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	230	230	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3740524800	3740524800	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	175	175	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2035482880	2035482880	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	146	146	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2529632512	2529632512	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	157	157	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	609468672	609468672	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	231	231	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3815792896	3815792896	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1552560384	1552560384	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	469.484802	469.484802	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	20351	20351	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	42267	42267	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	149.474503	149.474503	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	405.886108	405.886108	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	700.624451	700.624451	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	14985	14985	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	331640398	331640398	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	634.957092	634.957092 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	136.529999	136.529999	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.214 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1729466368
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	50264

Name	Input Value
AASNodeAbsentTimer_mS_M_u32	1221394432
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	32384
ANGLEVOLANTSigValidCount_Cnt_M_u16	10325
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	6893
AngleVolantMsgTimer_mS_M_u32	1729466368
AngleVolantValidCount_Cnt_M_u16	65373
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	384.069611
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	592363520
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	4202250240
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1782788096
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	83619840
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	65327
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2892476416
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	42369
CAVNodeAbsentTimer_mS_M_u32	334405632
CDD_SrlComVehSpd_Kph_G_f32	204.476593
CMM388NTCEnableTimer_mS_M_u32	2795036672
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2606014464
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	57650
CMMNodeAbsentTimer_mS_M_u32	1075179520
CONSANGLECPKSigInvalidCount_Cnt_M_u16	13166
CONSANGLECPKSigValidCount_Cnt_M_u16	43027
CONSANGLECPK_Cnt_M_u16	5958
CONSANGLECPK_HwDeg_M_f32	20.2429008
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	5958
CPKVehicleSpeedMsgTimer_mS_M_u32	71077888
CPKVehicleSpeedValidCount_Cnt_M_u16	64412
CityParkInputConsistentCount_Cnt_M_u16	63137
CityParkInputInvalidCount_Cnt_M_u16	52708
CityParkInputMsgTimer_mS_M_u32	1194860800
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	286326784
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	24988
ComputerRazGCTSigInvalidTimer_mS_M_u32	1845174272
ComputerRazGCTSigValidCount_Cnt_M_u16	32558
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	21152
DMDFCTCPKSigValidCount_Cnt_M_u16	65181
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	63778
DMDRELAXECPKSigValidCount_Cnt_M_u16	47223
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	6915
DateInvalidTimer_mS_M_u32	4202250240
DiagMuxOnAbsentTimer_mS_M_u32	1113673728
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	83619840
ESPNTCEnableTimer_mS_M_u32	761659392
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	41763
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	201
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	9
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3664359424
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1

Name	Input Value
EtatMTSigInvalidCount_Cnt_M_u16	874
EtatMTSigValidCount_Cnt_M_u16	31819
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	5136
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	7733
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	12291
ISDAT4V2BSI552MsgTimer_mS_M_u32	1935273984
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	16008
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	62321
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	31819
ISDATBSI3F2MsgTimer_mS_M_u32	3116322816
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	12588
ISDATBSI412MsgLenValidCount_Cnt_M_u16	1221
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	874
ISDATBSI412MsgTimer_mS_M_u32	4101214208
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	49014
ISDATBSI432MsgLenValidCount_Cnt_M_u16	27751
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	5178
ISDATDIRASentFltAcc_Cnt_M_u16	23310
ISDATDIRASentTimer_mS_M_u32	71077888
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	63780
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	65373
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	37071
ISDYN2CMMMsgTimer_mS_M_u32	553648128
ISDYNAASChkSumInvalidCount_Cnt_M_u16	27386
ISDYNAASChkSumValidCount_Cnt_M_u16	1263
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	21388
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	28404
ISDYNAASMsgLenValidCount_Cnt_M_u16	7585
ISDYNAASMsgTimeValidCount_Cnt_M_u16	27386
ISDYNAASMsgTimer_mS_M_u32	676651008
ISDYNABRChkSumInvalidCount_Cnt_M_u16	20198
ISDYNABRChkSumValidCount_Cnt_M_u16	6851
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	11689
ISDYNABRMsgCountValidCount_Cnt_M_u16	48350
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	33053
ISDYNABRMsgLenValidCount_Cnt_M_u16	11010
ISDYNABRMsgTimeValidCount_Cnt_M_u16	5958
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	157
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	199
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	31819
ISDYNCMM208MsgTimer_mS_M_u32	1981530112
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	479
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	305
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	31675
ISDYNCMM388MsgTimer_mS_M_u32	1679550208
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	41676
ISDYNVOLChkSumValidCount_Cnt_M_u16	33265
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	36094
ISDYNVOLMsgCountValidCount_Cnt_M_u16	58235
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	38772
ISDYNVOLMsgLenValidCount_Cnt_M_u16	31737
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	57650
ISDYNVOLMsgTimer_mS_M_u32	3149340672
IgnOnTimer_mS_M_u32	1565548544
IgnTimeOff_Sec_M_u32	2932199551
ManVehSpd_Kph_M_f32	501.915009
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	93
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	216
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2852474880
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	14
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3167891456
PrevISDATBSI412MsgDLCError_Cnt_M_u08	242

Name	Input Value
PrevISDATBSI412MsgRxTime_MSec_M_u32	1265082368
PrevISDATBSI432MsgDLCError_Cnt_M_u08	109
PrevISDATBSI432MsgRxTime_MSec_M_u32	2946105344
PrevISDATDIRAMsgTxTime_MSec_M_u32	3376128000
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	166
PrevISDYN2CMMMsgRxTime_MSec_M_u32	353726464
PrevISDYNAASMsgDLCError_Cnt_M_u08	202
PrevISDYNAASMsgRxTime_MSec_M_u32	2778013696
PrevISDYNABRMsgDLCError_Cnt_M_u08	94
PrevISDYNABRMsgRxTime_MSec_M_u32	1002987520
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	30
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3387039744
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	78
PrevISDYNCMM388MsgRxTime_MSec_M_u32	332201984
PrevISDYNVOLMsgDLCError_Cnt_M_u08	222
PrevISDYNVOLMsgRxTime_MSec_M_u32	3519848448
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1557237760
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	361.576111
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	48978
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	39039
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	44323
VitesseVehicleBVRampValidCount_Cnt_M_u16	61712
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	53713
VitesseVehicleBVSigValidCount_Cnt_M_u16	1638
VitesseVehicleBV_Kph_M_f32	119.1717
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	31675
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	43592
VitesseVehiculeRoues_Kph_M_f32	97.2928009
k_AASNTCEnableTimeout_mS_u16	61613
k_AASNodeAbsentDiag_Cnt_str.Threshold	47636
k_AASNodeAbsentDiag_Cnt_str.PStep	34578
k_AASNodeAbsentDiag_Cnt_str.NStep	62563
k_AASNodeAbsentTimeout_mS_u16	63304
k_AASNodeTimeout_mS_u16	58239
k_ABSNodeTimeout_mS_u16	29485
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	50849
k_ANGLEVOLANTSigValidThresh_Cnt_u16	3538
k_AngleVolantInvalidThresh_Cnt_u16	51465
k_AngleVolantValidThresh_Cnt_u16	52708
k_BSI552MsgTimeout_mS_u16	24639
k_BSINTCEnableTimeout_mS_u16	36334
k_BSINodeAbsentDiag_Cnt_str.Threshold	3692
k_BSINodeAbsentDiag_Cnt_str.PStep	43971
k_BSINodeAbsentDiag_Cnt_str.NStep	2216
k_BSINodeAbsentTimeout_mS_u16	2917
k_BSINodeTimeout_mS_u16	5178
k_BattOvHi_Volt_f32	15.2809
k_BattOvLo_Volt_f32	21.9326992
k_BattUvHi_Volt_f32	7.54969978
k_BattUvLo_Volt_f32	13.8383999
k_CAVNTCEnableTimeout_mS_u16	64698
k_CAVNodeAbsentDiag_Cnt_str.Threshold	14101
k_CAVNodeAbsentDiag_Cnt_str.PStep	13590
k_CAVNodeAbsentDiag_Cnt_str.NStep	2667
k_CAVNodeAbsentTimeout_mS_u16	63711
k_CAVNodeTimeout_mS_u16	60714
k_CMM388MsgTimeout_mS_u16	20312

Name	Input Value
k_CMM388NTCEnableTimeout_mS_u16	61972
k_CMMNTCEnableTimeout_mS_u16	2304
k_CMMNodeAbsentDiag_Cnt_str.Threshold	62414
k_CMMNodeAbsentDiag_Cnt_str.PStep	42715
k_CMMNodeAbsentDiag_Cnt_str.NStep	22076
k_CMMNodeAbsentTimeout_mS_u16	13060
k_CONSANGLECPKMax_HwDeg_f32	29.1618996
k_CONSANGLECPKMin_HwDeg_f32	-117.170097
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	34491
k_CONSANGLECPKSigValidThresh_Cnt_u16	62792
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	6117
k_CPKVehicleSpeedValidThresh_Cnt_u16	23135
k_CityParkInputInvalidThresh_Cnt_u16	3020
k_CityParkInputValidThresh_Cnt_u16	63137
k_ComputerRazGCTSigValidThresh_Cnt_u16	5454
k_CptTemporelSigValidThresh_Cnt_u16	29367
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	3101
k_DMDFCTCPKSigValidThresh_Cnt_u16	62978
k_DMDFCTCPKValidCount_Cnt_u16	10679
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	37071
k_DMDRELAXECPKSigValidThresh_Cnt_u16	53772
k_DMDRelaxeConsistentThresh_Cnt_u16	49266
k_DateValidThresh_Cnt_u16	12291
k_DefaultVehSpd_Kph_f32	34.0457001
k_DiagMuxOnAbsentTimeout_mS_u16	27548
k_EMNodeTimeout_mS_u16	33123
k_ESPNTCEnableTimeout_mS_u16	37181
k_ESPNodeAbsentDiag_Cnt_str.Threshold	62971
k_ESPNodeAbsentDiag_Cnt_str.PStep	11352
k_ESPNodeAbsentDiag_Cnt_str.NStep	60169
k_ESPNodeAbsentTimeout_mS_u16	44172
k_EtatMTSigInvalidThresh_Cnt_u16	64765
k_EtatMTSigValidThresh_Cnt_u16	64538
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	50168
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	33465
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	50802
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	5949
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	23014
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	25968
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	21931
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	45148
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	56762
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	45546
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	57507
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	6485
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	5794
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	54562
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	6893
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	41993
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	23014
k_ISDYNAASChkSumValidThresh_Cnt_u16	26051
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	47273
k_ISDYNAASMsgCountValidThresh_Cnt_u16	34782
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	53802
k_ISDYNAASMsgLenValidThresh_Cnt_u16	62147
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	46426
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	9083
k_ISDYNABRChkSumValidThresh_Cnt_u16	30688
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	35375
k_ISDYNABRMsgCountValidThresh_Cnt_u16	59716
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	11314
k_ISDYNABRMsgLenValidThresh_Cnt_u16	11811
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	51387
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	28310
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	49213
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	26742
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	2432
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	62293
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	8796
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	40151

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDYNVOLChkSumValidThresh_Cnt_u16	27312
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	45240
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	18695
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	60454
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	47623
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	25433
k_IgnOnTimeout_mS_u16	14483
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	171.7043
k_PowerCutVehSpdLowThresh_Kph_f32	124.337196
k_PowerCutVehSpdLowTimeout_mS_u16	59609
k_VBattMaxAAS_Volt_f32	24.1891994
k_VBattMaxBSI_Volt_f32	21.2532997
k_VBattMaxCAV_Volt_f32	29.9340992
k_VBattMaxCMM388_Volt_f32	31.9869995
k_VBattMaxCMM_Volt_f32	5.14489985
k_VBattMaxESP_Volt_f32	19.1639996
k_VBattMinAAS_Volt_f32	19.1361008
k_VBattMinBSI_Volt_f32	19.1639996
k_VBattMinCAV_Volt_f32	32
k_VBattMinCMM388_Volt_f32	11.3205996
k_VBattMinCMM_Volt_f32	13.4899998
k_VBattMinESP_Volt_f32	5.14489985
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	29628
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	4164
k_VitesseVehicleBVRampValidThresh_Cnt_u16	38910
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	19697
k_VitesseVehicleBVSigValidThresh_Cnt_u16	33514
k_VitesseVehicleBVSpeedPassThresh_kph_f32	487.695099
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	45185
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	24302
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4202250240
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	1
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	78
target_SrlComInput_Per1_Batt_Volt_f32.value	31
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1400942592
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	137
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.525010407
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	52
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1941594112
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	139
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	102006784
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2210308096
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	217
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	884523008
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1627578368
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1352466432
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1267146752
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	55
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	64
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	82

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	120
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1625931776
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	24
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	62
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	166
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2165137408
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	225
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1390903296
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	159
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3490816000
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	7
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	17
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	48
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	85
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	130
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	169
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3489935360
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	157
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.167137519
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	646917
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	52.1001015
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	39788

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	47636	47636	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	384.069611	384.069611	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	14101	14101	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2795036672	2795036672	✔
CMM388NTCsEnabled_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	35574	35574	✔
CMMNodeAbsentTimer_mS_M_u32	1352466432	1352466432	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	5958	5958	✔
CONSANGLECPK_HwDeg_M_f32	20.2429008	20.2429008 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2	2	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2006148864	2006148864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔
EffacDefaultDiagTimer_mS_M_u32[1]	201	201	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	8	8	✔
ElecIntTimer_mS_M_u32[1]	9	9	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11170	11170	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1390903296	1390903296	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	1565548544	1565548544	✔
IgnTimeOff_Sec_M_u32	2932199551	2932199551	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	52	52	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1941594112	1941594112	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	139	139	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	102006784	102006784	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	170	170	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2210308096	2210308096	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	217	217	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	884523008	884523008	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3376128000	3376128000	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	131	131	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1352466432	1352466432	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	144	144	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1267146752	1267146752	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	120	120	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1625931776	1625931776	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	169	169	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2165137408	2165137408	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	225	225	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1390903296	1390903296	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	159	159	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3490816000	3490816000	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3489935360	3489935360	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	361.576111	361.576111	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	119.1717	119.1717	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	97.2928009	97.2928009	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	384.069611	384.069611	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	5958	5958	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2932199551	2932199551	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	20.2429008	20.2429008 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	34.0457001	34.0457001	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0169	0x0169	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	8	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	8	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.215 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2560496384
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	43734
AASNodeAbsentTimer_mS_M_u32	1563935488
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	48733

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ANGLEVOLANTSigValidCount_Cnt_M_u16	32926
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	15127
AngleVolantMsgTimer_mS_M_u32	2560496384
AngleVolantValidCount_Cnt_M_u16	63047
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	488.315613
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	78807808
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1228079872
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3449107200
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3496669952
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	47184
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	958903040
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	13785
CAVNodeAbsentTimer_mS_M_u32	173204224
CDD_SrlComVehSpd_Kph_G_f32	494.452087
CMM388NTCEnableTimer_mS_M_u32	3411288832
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2350965504
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	902
CMMNodeAbsentTimer_mS_M_u32	119337728
CONSANGLECPKSigInvalidCount_Cnt_M_u16	34451
CONSANGLECPKSigValidCount_Cnt_M_u16	10341
CONSANGLECPK_Cnt_M_u16	26316
CONSANGLECPK_HwDeg_M_f32	423.718689
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	26316
CPKVehicleSpeedMsgTimer_mS_M_u32	489231104
CPKVehicleSpeedValidCount_Cnt_M_u16	7921
CityParkInputConsistentCount_Cnt_M_u16	8315
CityParkInputInvalidCount_Cnt_M_u16	47025
CityParkInputMsgTimer_mS_M_u32	1941594112
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	342606592
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	58122
ComputerRazGCTSigInvalidTimer_mS_M_u32	3459080960
ComputerRazGCTSigValidCount_Cnt_M_u16	64212
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	6525
DMDFCTCPKSigValidCount_Cnt_M_u16	30022
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	22135
DMDRELAXECPKSigValidCount_Cnt_M_u16	55352
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	25556
DateInvalidTimer_mS_M_u32	1228079872
DiagMuxOnAbsentTimer_mS_M_u32	3854226176
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3496669952
ESPNTCEnableTimer_mS_M_u32	1399636736
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	60787
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	89
EffacDefaultDiagTimer_mS_M_u32[1]	899
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	5
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	924955392
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	35296
EtatMTSigValidCount_Cnt_M_u16	3837

Name	Input Value
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	60589
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	52735
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	63764
ISDAT4V2BSI552MsgTimer_mS_M_u32	2102457088
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	51717
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	47882
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	3837
ISDATBSI3F2MsgTimer_mS_M_u32	2007028480
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	54040
ISDATBSI412MsgLenValidCount_Cnt_M_u16	10253
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	35296
ISDATBSI412MsgTimer_mS_M_u32	3900969728
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	30906
ISDATBSI432MsgLenValidCount_Cnt_M_u16	41383
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	3502
ISDATDIRASentFltAcc_Cnt_M_u16	35122
ISDATDIRASentTimer_mS_M_u32	489231104
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	47410
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	63047
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	56048
ISDYN2CMMMsgTimer_mS_M_u32	1621017344
ISDYNAASChkSumInvalidCount_Cnt_M_u16	48880
ISDYNAASChkSumValidCount_Cnt_M_u16	12497
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	30138
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	25984
ISDYNAASMsgLenValidCount_Cnt_M_u16	31033
ISDYNAASMsgTimeValidCount_Cnt_M_u16	48880
ISDYNAASMsgTimer_mS_M_u32	908075776
ISDYNABRChkSumInvalidCount_Cnt_M_u16	24233
ISDYNABRChkSumValidCount_Cnt_M_u16	56019
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	62179
ISDYNABRMsgCountValidCount_Cnt_M_u16	34052
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	6534
ISDYNABRMsgLenValidCount_Cnt_M_u16	7064
ISDYNABRMsgTimeValidCount_Cnt_M_u16	26316
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	158
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	201
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	3837
ISDYNCMM208MsgTimer_mS_M_u32	2152432384
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	483
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	307
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0
ISDYNCMM388MsgTimer_mS_M_u32	1475977984
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	12409
ISDYNVOLChkSumValidCount_Cnt_M_u16	37579
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	25187
ISDYNVOLMsgCountValidCount_Cnt_M_u16	48812
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	38016
ISDYNVOLMsgLenValidCount_Cnt_M_u16	26289
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	902
ISDYNVOLMsgTimer_mS_M_u32	3573113600
IgnOnTimer_mS_M_u32	3844973312
IgnTimeOff_Sec_M_u32	1733886015
ManVehSpd_Kph_M_f32	652.665283
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	94
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	135
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1053741824
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	221
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3521655552
PrevISDATBSI412MsgDLCError_Cnt_M_u08	161
PrevISDATBSI412MsgRxTime_MSec_M_u32	2280121088
PrevISDATBSI432MsgDLCError_Cnt_M_u08	228

Name	Input Value
PrevISDATBSI432MsgRxTime_MSec_M_u32	2630927104
PrevISDATDIRAMsgTxTime_MSec_M_u32	1584128768
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	241
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3860755200
PrevISDYNAASMsgDLCError_Cnt_M_u08	75
PrevISDYNAASMsgRxTime_MSec_M_u32	257909504
PrevISDYNABRMsgDLCError_Cnt_M_u08	200
PrevISDYNABRMsgRxTime_MSec_M_u32	700818176
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	40
PrevISDYNCMM208MsgRxTime_MSec_M_u32	376988416
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	211
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4231512832
PrevISDYNVOLMsgDLCError_Cnt_M_u08	149
PrevISDYNVOLMsgRxTime_MSec_M_u32	3367559936
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2808746752
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	171.855499
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	27750
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	159
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	9971
VitesseVehicleBVRampValidCount_Cnt_M_u16	31468
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	18538
VitesseVehicleBVSigValidCount_Cnt_M_u16	27243
VitesseVehicleBV_Kph_M_f32	568.335022
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	31021
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	36166
VitesseVehiculeRoues_Kph_M_f32	360.924011
k_AASNTCEnableTimeout_mS_u16	13975
k_AASNodeAbsentDiag_Cnt_str.Threshold	42792
k_AASNodeAbsentDiag_Cnt_str.PStep	61680
k_AASNodeAbsentDiag_Cnt_str.NStep	43453
k_AASNodeAbsentTimeout_mS_u16	31366
k_AASNodeTimeout_mS_u16	8095
k_ABSNodeTimeout_mS_u16	11222
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	53049
k_ANGLEVOLANTSigValidThresh_Cnt_u16	10598
k_AngleVolantInvalidThresh_Cnt_u16	37825
k_AngleVolantValidThresh_Cnt_u16	47025
k_BSI552MsgTimeout_mS_u16	1889
k_BSINTCEnableTimeout_mS_u16	60754
k_BSINodeAbsentDiag_Cnt_str.Threshold	3732
k_BSINodeAbsentDiag_Cnt_str.PStep	43954
k_BSINodeAbsentDiag_Cnt_str.NStep	2239
k_BSINodeAbsentTimeout_mS_u16	18863
k_BSINodeTimeout_mS_u16	3502
k_BattOvHi_Volt_f32	21.5846004
k_BattOvLo_Volt_f32	11.8808002
k_BattUvHi_Volt_f32	30.6229
k_BattUvLo_Volt_f32	30.0065002
k_CAVNTCEnableTimeout_mS_u16	815
k_CAVNodeAbsentDiag_Cnt_str.Threshold	64998
k_CAVNodeAbsentDiag_Cnt_str.PStep	50339
k_CAVNodeAbsentDiag_Cnt_str.NStep	21859
k_CAVNodeAbsentTimeout_mS_u16	13247
k_CAVNodeTimeout_mS_u16	18783
k_CMM388MsgTimeout_mS_u16	2518
k_CMM388NTCEnableTimeout_mS_u16	4514
k_CMMNTCEnableTimeout_mS_u16	19101

Name	Input Value
k_CMMNodeAbsentDiag_Cnt_str.Threshold	4347
k_CMMNodeAbsentDiag_Cnt_str.PStep	59539
k_CMMNodeAbsentDiag_Cnt_str.NStep	6959
k_CMMNodeAbsentTimeout_mS_u16	58130
k_CONSANGLECPKMax_HwDeg_f32	363.633789
k_CONSANGLECPKMin_HwDeg_f32	-560.882874
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	22573
k_CONSANGLECPKSigValidThresh_Cnt_u16	44102
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	39533
k_CPKVehicleSpeedValidThresh_Cnt_u16	58239
k_CityParkInputInvalidThresh_Cnt_u16	16375
k_CityParkInputValidThresh_Cnt_u16	8315
k_ComputerRazGCTSigValidThresh_Cnt_u16	56755
k_CptTemporelSigValidThresh_Cnt_u16	54584
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	30854
k_DMDFCTCPKSigValidThresh_Cnt_u16	47768
k_DMDFCTCPKValidCount_Cnt_u16	22712
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	56048
k_DMDRELAXECPKSigValidThresh_Cnt_u16	30457
k_DMDRelaxeConsistentThresh_Cnt_u16	50119
k_DateValidThresh_Cnt_u16	63764
k_DefaultVehSpd_Kph_f32	104.2332
k_DiagMuxOnAbsentTimeout_mS_u16	16842
k_EMNodeTimeout_mS_u16	45236
k_ESPNTCEnableTimeout_mS_u16	25253
k_ESPNodeAbsentDiag_Cnt_str.Threshold	44404
k_ESPNodeAbsentDiag_Cnt_str.PStep	15133
k_ESPNodeAbsentDiag_Cnt_str.NStep	32713
k_ESPNodeAbsentTimeout_mS_u16	38522
k_EtatMTSigInvalidThresh_Cnt_u16	28772
k_EtatMTSigValidThresh_Cnt_u16	21198
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	41524
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	54706
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	13576
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	21478
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	39851
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	17996
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	51739
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	59848
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	11758
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	9952
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	60021
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	2975
k_ISDATDIRASentDiag_Cnt_str.Threshold	37951
k_ISDATDIRASentDiag_Cnt_str.PStep	62140
k_ISDATDIRASentDiag_Cnt_str.NStep	43836
k_ISDATDIRASentTimeout_mS_u16	63349
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	19512
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	15127
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	23105
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	15785
k_ISDYNAASChkSumValidThresh_Cnt_u16	63955
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	20963
k_ISDYNAASMsgCountValidThresh_Cnt_u16	9220
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	58589
k_ISDYNAASMsgLenValidThresh_Cnt_u16	467
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	21198
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	10860
k_ISDYNABRChkSumValidThresh_Cnt_u16	11518
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	5968
k_ISDYNABRMsgCountValidThresh_Cnt_u16	47569
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	8838
k_ISDYNABRMsgLenValidThresh_Cnt_u16	19571
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	46956
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	28314
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	43493
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	11450
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	7517
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	8094
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	39497
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	64535
k_ISDYNVOLChkSumValidThresh_Cnt_u16	25164
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	22708

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	24583
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	49068
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	17865
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	14098
k_IgnOnTimeout_mS_u16	6371
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	181.757095
k_PowerCutVehSpdLowThresh_Kph_f32	75.8587036
k_PowerCutVehSpdLowTimeout_mS_u16	65043
k_VBattMaxAAS_Volt_f32	4.82399988
k_VBattMaxBSI_Volt_f32	27.8756008
k_VBattMaxCAV_Volt_f32	20.6856995
k_VBattMaxCMM388_Volt_f32	17.1464005
k_VBattMaxCMM_Volt_f32	32
k_VBattMaxESP_Volt_f32	15.4842997
k_VBattMinAAS_Volt_f32	7.57600021
k_VBattMinBSI_Volt_f32	15.4842997
k_VBattMinCAV_Volt_f32	2.48440003
k_VBattMinCMM388_Volt_f32	2.67589998
k_VBattMinCMM_Volt_f32	20.0023994
k_VBattMinESP_Volt_f32	32
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	22634
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	4751
k_VitesseVehicleBVRampValidThresh_Cnt_u16	16739
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	12747
k_VitesseVehicleBVSigValidThresh_Cnt_u16	57248
k_VitesseVehicleBVSpeedPassThresh_kph_f32	347.926514
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	5337
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	10578
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1228079872
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	1
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60081
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1329630720
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	211
target_SrlComInput_Per1_Batt_Volt_f32.value	9.98120022
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3890000640
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	117
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.89126575
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3387925248
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2741060352
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	244
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4209173248
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4168385280
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3289785088
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2244461312
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1703502592
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	46
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	48
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	68
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	137

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	161
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	188
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	1
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2011267840
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	77
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	151
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	222
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2918621952
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3370664704
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	568976128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	89
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	114
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	140
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	158
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3763483392
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2756
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.347861528
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	162821
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	21.8199005
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	49176

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1329630720	1329630720	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	42792	42792	✔
AASNodeAbsentTimer_mS_M_u32	1329630720	1329630720	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	48733	48733	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	15129	15129	✔
AngleVolantMsgTimer_mS_M_u32	1329630720	1329630720	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	488.315613	488.315613	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1329630720	1329630720	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1329630720	1329630720	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1329630720	1329630720	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1329630720	1329630720	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1329630720	1329630720	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	958903040	958903040	✔
CAVNTCsEnabled_Cnt_M_lgc	1	1	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	64998	64998	✔
CAVNodeAbsentTimer_mS_M_u32	1329630720	1329630720	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3411288832	3411288832	✔
CMM388NTCsEnabled_Cnt_M_lgc	1	1	✔
CMMNTCEnableTimer_mS_M_u32	1329630720	1329630720	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2244461312	2244461312	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	26316	26316	✔
CONSANGLECPK_HwDeg_M_f32	423.718689	423.718689 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	26318	26318	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1329630720	1329630720	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	8315	8315	✔
CityParkInputInvalidCount_Cnt_M_u16	47025	47025	✔
CityParkInputMsgTimer_mS_M_u32	1329630720	1329630720	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1329630720	1329630720	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1329630720	1329630720	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1329630720	1329630720	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1329630720	1329630720	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1329630720	1329630720	✔
ESPNTCEnableTimer_mS_M_u32	1329630720	1329630720	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1329630720	1329630720	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1329630720	1329630720	✔
EffacDefaultDiagTimer_mS_M_u32[1]	899	899	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	1329630720	1329630720	✔
ElecIntTimer_mS_M_u32[1]	5	5	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1329630720	1329630720	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1329630720	1329630720	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1329630720	1329630720	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1329630720	1329630720	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1329630720	1329630720	✔
ISDATDIRASentFltAcc_Cnt_M_u16	37951	37951	✔
ISDATDIRASentTimer_mS_M_u32	1329630720	1329630720	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1329630720	1329630720	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1329630720	1329630720	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1329630720	1329630720	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1329630720	1329630720	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	484	484	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3370664704	3370664704	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	12409	12409	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	25187	25187	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	38017	38017	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	568976128	568976128	✔
IgnOnTimer_mS_M_u32	3844973312	3844973312	✔
IgnTimeOff_Sec_M_u32	1733886015	1733886015	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	55	55	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3387925248	3387925248	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	33	33	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2741060352	2741060352	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	244	244	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4209173248	4209173248	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4168385280	4168385280	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1584128768	1584128768	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	123	123	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2244461312	2244461312	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	135	135	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1703502592	1703502592	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	1	1	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2011267840	2011267840	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2918621952	2918621952	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	46	46	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3370664704	3370664704	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	35	35	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	568976128	568976128	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3763483392	3763483392	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	171.855499	171.855499	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	27750	27750	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	9971	9971	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	18538	18538	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	568.335022	568.335022	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	360.924011	360.924011	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	488.315613	488.315613	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	26316	26316	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1733886015	1733886015	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	423.718689	423.718689 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	104.2332	104.2332	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0102	0x0102	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	4	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	8	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	8	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.216 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3184560640
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	2343

Name	Input Value
AASNodeAbsentTimer_mS_M_u32	851671552
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	2195
ANGLEVOLANTSigValidCount_Cnt_M_u16	33423
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	40036
AngleVolantMsgTimer_mS_M_u32	3184560640
AngleVolantValidCount_Cnt_M_u16	12629
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	249.249084
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2538813952
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1808906752
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1667967488
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3790203392
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	42682
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2327030272
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	56477
CAVNodeAbsentTimer_mS_M_u32	4294056448
CDD_SrlComVehSpd_Kph_G_f32	405.972198
CMM388NTCEnableTimer_mS_M_u32	1374575104
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	847780352
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	61784
CMMNodeAbsentTimer_mS_M_u32	2245257728
CONSANGLECPKSigInvalidCount_Cnt_M_u16	64239
CONSANGLECPKSigValidCount_Cnt_M_u16	5691
CONSANGLECPK_Cnt_M_u16	46854
CONSANGLECPK_HwDeg_M_f32	315.728607
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	46854
CPKVehicleSpeedMsgTimer_mS_M_u32	472877568
CPKVehicleSpeedValidCount_Cnt_M_u16	65310
CityParkInputConsistentCount_Cnt_M_u16	33465
CityParkInputInvalidCount_Cnt_M_u16	26134
CityParkInputMsgTimer_mS_M_u32	3387925248
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3710351872
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	12427
ComputerRazGCTSigInvalidTimer_mS_M_u32	1046649344
ComputerRazGCTSigValidCount_Cnt_M_u16	38830
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	28850
DMDFCTCPKSigValidCount_Cnt_M_u16	15894
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	10309
DMDRELAXECPKSigValidCount_Cnt_M_u16	25537
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	42796
DateInvalidTimer_mS_M_u32	1808906752
DiagMuxOnAbsentTimer_mS_M_u32	964315648
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3790203392
ESPNTCEnableTimer_mS_M_u32	1680112128
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	42064
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	4
EffacDefaultDiagTimer_mS_M_u32[1]	749
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	7
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4173703680
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0

Name	Input Value
EtatMTSigInvalidCount_Cnt_M_u16	38729
EtatMTSigValidCount_Cnt_M_u16	14514
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	45217
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	3437
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	27308
ISDAT4V2BSI552MsgTimer_mS_M_u32	4080527872
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	602
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	11
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	14514
ISDATBSI3F2MsgTimer_mS_M_u32	2613594624
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	17441
ISDATBSI412MsgLenValidCount_Cnt_M_u16	54785
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	38729
ISDATBSI412MsgTimer_mS_M_u32	3860761088
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	25020
ISDATBSI432MsgLenValidCount_Cnt_M_u16	22452
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	59678
ISDATDIRASentFltAcc_Cnt_M_u16	34450
ISDATDIRASentTimer_mS_M_u32	472877568
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	55252
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	12629
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	47193
ISDYN2CMMMsgTimer_mS_M_u32	2223929856
ISDYNAASChkSumInvalidCount_Cnt_M_u16	46297
ISDYNAASChkSumValidCount_Cnt_M_u16	40949
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	16124
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	43432
ISDYNAASMsgLenValidCount_Cnt_M_u16	3901
ISDYNAASMsgTimeValidCount_Cnt_M_u16	46297
ISDYNAASMsgTimer_mS_M_u32	1099586048
ISDYNABRChkSumInvalidCount_Cnt_M_u16	62252
ISDYNABRChkSumValidCount_Cnt_M_u16	57201
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	42240
ISDYNABRMsgCountValidCount_Cnt_M_u16	12124
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	52758
ISDYNABRMsgLenValidCount_Cnt_M_u16	51362
ISDYNABRMsgTimeValidCount_Cnt_M_u16	46854
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	159
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	203
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	14514
ISDYNCMM208MsgTimer_mS_M_u32	3364370944
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	487
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	309
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	65535
ISDYNCMM388MsgTimer_mS_M_u32	570284544
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	5437
ISDYNVOLChkSumValidCount_Cnt_M_u16	61193
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	44544
ISDYNVOLMsgCountValidCount_Cnt_M_u16	31204
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	9001
ISDYNVOLMsgLenValidCount_Cnt_M_u16	11606
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	61784
ISDYNVOLMsgTimer_mS_M_u32	1509857792
IgnOnTimer_mS_M_u32	1247926784
IgnTimeOff_Sec_M_u32	1245343854
ManVehSpd_Kph_M_f32	61.4471016
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	95
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	43
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2118011392
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	60
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1651649024
PrevISDATBSI412MsgDLCError_Cnt_M_u08	155

Name	Input Value
PrevISDATBSI412MsgRxTime_MSec_M_u32	456333824
PrevISDATBSI432MsgDLCError_Cnt_M_u08	191
PrevISDATBSI432MsgRxTime_MSec_M_u32	402160128
PrevISDATDIRAMsgTxTime_MSec_M_u32	2812746240
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	106
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3469699584
PrevISDYNAASMsgDLCError_Cnt_M_u08	15
PrevISDYNAASMsgRxTime_MSec_M_u32	3268188672
PrevISDYNABRMsgDLCError_Cnt_M_u08	232
PrevISDYNABRMsgRxTime_MSec_M_u32	3701070336
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	231
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1367448064
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	52
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1438874112
PrevISDYNVOLMsgDLCError_Cnt_M_u08	155
PrevISDYNVOLMsgRxTime_MSec_M_u32	3703577088
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3245115904
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	271.316101
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	44278
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	37131
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	61775
VitesseVehicleBVRampValidCount_Cnt_M_u16	38436
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	56940
VitesseVehicleBVSigValidCount_Cnt_M_u16	14632
VitesseVehicleBV_Kph_M_f32	74.0791016
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	49315
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	42263
VitesseVehiculeRoues_Kph_M_f32	202.774994
k_AASNTCEnableTimeout_mS_u16	13221
k_AASNodeAbsentDiag_Cnt_str.Threshold	39833
k_AASNodeAbsentDiag_Cnt_str.PStep	44032
k_AASNodeAbsentDiag_Cnt_str.NStep	32603
k_AASNodeAbsentTimeout_mS_u16	24728
k_AASNodeTimeout_mS_u16	13323
k_ABSNodeTimeout_mS_u16	56743
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	6719
k_ANGLEVOLANTSigValidThresh_Cnt_u16	31863
k_AngleVolantInvalidThresh_Cnt_u16	26982
k_AngleVolantValidThresh_Cnt_u16	26134
k_BSI552MsgTimeout_mS_u16	25286
k_BSINTCEnableTimeout_mS_u16	25588
k_BSINodeAbsentDiag_Cnt_str.Threshold	3772
k_BSINodeAbsentDiag_Cnt_str.PStep	43937
k_BSINodeAbsentDiag_Cnt_str.NStep	2262
k_BSINodeAbsentTimeout_mS_u16	53404
k_BSINodeTimeout_mS_u16	59678
k_BattOvHi_Volt_f32	23.5951004
k_BattOvLo_Volt_f32	21.9519997
k_BattUvHi_Volt_f32	6.44610023
k_BattUvLo_Volt_f32	18.5464993
k_CAVNTCEnableTimeout_mS_u16	64412
k_CAVNodeAbsentDiag_Cnt_str.Threshold	11805
k_CAVNodeAbsentDiag_Cnt_str.PStep	38824
k_CAVNodeAbsentDiag_Cnt_str.NStep	45863
k_CAVNodeAbsentTimeout_mS_u16	64235
k_CAVNodeTimeout_mS_u16	57995
k_CMM388MsgTimeout_mS_u16	60455

Name	Input Value
k_CMM388NTCEnableTimeout_mS_u16	1219
k_CMMNTCEnableTimeout_mS_u16	57490
k_CMMNodeAbsentDiag_Cnt_str.Threshold	6433
k_CMMNodeAbsentDiag_Cnt_str.PStep	49176
k_CMMNodeAbsentDiag_Cnt_str.NStep	26114
k_CMMNodeAbsentTimeout_mS_u16	54195
k_CONSANGLECPKMax_HwDeg_f32	634.825073
k_CONSANGLECPKMin_HwDeg_f32	-295.086914
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	9123
k_CONSANGLECPKSigValidThresh_Cnt_u16	18455
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	31649
k_CPKVehicleSpeedValidThresh_Cnt_u16	28396
k_CityParkInputInvalidThresh_Cnt_u16	1858
k_CityParkInputValidThresh_Cnt_u16	33465
k_ComputerRazGCTSigValidThresh_Cnt_u16	65360
k_CptTemporelSigValidThresh_Cnt_u16	59777
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	45334
k_DMDFCTCPKSigValidThresh_Cnt_u16	60322
k_DMDFCTCPKValidCount_Cnt_u16	25986
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	47193
k_DMDRELAXECPKSigValidThresh_Cnt_u16	50429
k_DMDRelaxeConsistentThresh_Cnt_u16	38547
k_DateValidThresh_Cnt_u16	27308
k_DefaultVehSpd_Kph_f32	77.4673996
k_DiagMuxOnAbsentTimeout_mS_u16	40460
k_EMNodeTimeout_mS_u16	16524
k_ESPNTCEnableTimeout_mS_u16	34361
k_ESPNodeAbsentDiag_Cnt_str.Threshold	23220
k_ESPNodeAbsentDiag_Cnt_str.PStep	8059
k_ESPNodeAbsentDiag_Cnt_str.NStep	53045
k_ESPNodeAbsentTimeout_mS_u16	22907
k_EtatMTSigInvalidThresh_Cnt_u16	27131
k_EtatMTSigValidThresh_Cnt_u16	9088
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	16460
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	22164
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	47378
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	10423
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	8744
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	47749
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	12697
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	17233
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	4640
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	50890
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	36043
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	51083
k_ISDATDIRASentDiag_Cnt_str.Threshold	3858
k_ISDATDIRASentDiag_Cnt_str.PStep	45405
k_ISDATDIRASentDiag_Cnt_str.NStep	21916
k_ISDATDIRASentTimeout_mS_u16	22728
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	43456
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	40036
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	3941
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	22060
k_ISDYNAASChkSumValidThresh_Cnt_u16	33393
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	34816
k_ISDYNAASMsgCountValidThresh_Cnt_u16	21084
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	12432
k_ISDYNAASMsgLenValidThresh_Cnt_u16	23919
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	41023
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	45924
k_ISDYNABRChkSumValidThresh_Cnt_u16	44144
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	35258
k_ISDYNABRMsgCountValidThresh_Cnt_u16	25334
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	37976
k_ISDYNABRMsgLenValidThresh_Cnt_u16	34640
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	38437
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	30298
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	13242
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	14522
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	60307
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	42383
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	7758
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	34084

Name	Input Value
k_ISDYNVOLChkSumValidThresh_Cnt_u16	58180
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	42637
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	8149
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	9701
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	50254
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	10418
k_IgnOnTimeout_mS_u16	24256
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	165.395706
k_PowerCutVehSpdLowThresh_Kph_f32	203.091003
k_PowerCutVehSpdLowTimeout_mS_u16	52529
k_VBattMaxAAS_Volt_f32	15.4556999
k_VBattMaxBSI_Volt_f32	2.56850004
k_VBattMaxCAV_Volt_f32	0.580500007
k_VBattMaxCMM388_Volt_f32	30.3409996
k_VBattMaxCMM_Volt_f32	19.6277008
k_VBattMaxESP_Volt_f32	29.7199993
k_VBattMinAAS_Volt_f32	11.4216003
k_VBattMinBSI_Volt_f32	29.7199993
k_VBattMinCAV_Volt_f32	20.2187996
k_VBattMinCMM388_Volt_f32	2.16179991
k_VBattMinCMM_Volt_f32	20.6772995
k_VBattMinESP_Volt_f32	19.6277008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	52522
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	61306
k_VitesseVehicleBVRampValidThresh_Cnt_u16	4352
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	4617
k_VitesseVehicleBVSigValidThresh_Cnt_u16	6474
k_VitesseVehicleBVSpeedPassThresh_kph_f32	48.8395996
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	16285
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	41714
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1808906752
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	1
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	38937
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1368725760
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	52
target_SrlComInput_Per1_Batt_Volt_f32.value	7.70240021
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2459216384
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	88
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.762987494
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	605805056
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3863411200
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1849825792
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1141717504
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4020787712
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4178803200
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	179
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3897465344
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	91

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	209
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3116775936
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	43
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	194
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1409735168
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1370618368
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	130
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3576502784
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	55
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	229
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	247
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1597254144
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3505
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.505835056
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1030134
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	153.457397
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	63968

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1368725760	1368725760	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1368725760	1368725760	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1368725760	1368725760	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	249.249084	249.249084	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1368725760	1368725760	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1368725760	1368725760	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1368725760	1368725760	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1368725760	1368725760	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	3772	3772	✔
BSINodeAbsentTimer_mS_M_u32	1368725760	1368725760	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1368725760	1368725760	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	11805	11805	✔
CAVNodeAbsentTimer_mS_M_u32	1368725760	1368725760	✔
CDD_SrlComVehSpd_Kph_G_f32	61.4471016	61.4471016	✔
CMM388NTCEnableTimer_mS_M_u32	1368725760	1368725760	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CMMNTCEnableTimer_mS_M_u32	1368725760	1368725760	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1368725760	1368725760	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	46854	46854	✔
CONSANGLECPK_HwDeg_M_f32	315.728607	315.728607 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1368725760	1368725760	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1368725760	1368725760	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1368725760	1368725760	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1368725760	1368725760	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1368725760	1368725760	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1368725760	1368725760	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1368725760	1368725760	✔
ESPNTCEnableTimer_mS_M_u32	1368725760	1368725760	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1368725760	1368725760	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4	4	✔
EffacDefaultDiagTimer_mS_M_u32[1]	749	749	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	6	6	✔
ElecIntTimer_mS_M_u32[1]	7	7	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1368725760	1368725760	✔
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	27308	27308	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1368725760	1368725760	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	14514	14514	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1368725760	1368725760	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	38729	38729	✔
ISDATBSI412MsgTimer_mS_M_u32	1368725760	1368725760	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	59678	59678	✔
ISDATBSI432MsgTimer_mS_M_u32	1368725760	1368725760	✔
ISDATDIRASentFltAcc_Cnt_M_u16	3858	3858	✔
ISDATDIRASentTimer_mS_M_u32	1368725760	1368725760	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	47193	47193	✔
ISDYN2CMMMsgTimer_mS_M_u32	1368725760	1368725760	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	46297	46297	✔
ISDYNAASMsgTimer_mS_M_u32	1368725760	1368725760	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	46854	46854	✔
ISDYNABRMsgTimer_mS_M_u32	1368725760	1368725760	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	14514	14514	✔
ISDYNCMM208MsgTimer_mS_M_u32	1368725760	1368725760	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	65535	65535	✔
ISDYNCMM388MsgTimer_mS_M_u32	1368725760	1368725760	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	61784	61784	✔
ISDYNVOLMsgTimer_mS_M_u32	1368725760	1368725760	✔
IgnOnTimer_mS_M_u32	1247926784	1247926784	✔
IgnTimeOff_Sec_M_u32	1245343854	1245343854	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	202	202	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	605805056	605805056	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	60	60	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3863411200	3863411200	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	49	49	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1849825792	1849825792	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	46	46	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1141717504	1141717504	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2812746240	2812746240	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	104	104	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4178803200	4178803200	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	179	179	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3897465344	3897465344	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	173	173	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3116775936	3116775936	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1409735168	1409735168	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	242	242	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1370618368	1370618368	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	130	130	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3576502784	3576502784	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1597254144	1597254144	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	271.316101	271.316101	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	74.0791016	74.0791016	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	202.774994	202.774994	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	249.249084	249.249084	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	46854	46854	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1245343854	1245343854	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	315.728607	315.728607 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	61.4471016	61.4471016	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.217 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1356145920
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	59601
AASNodeAbsentTimer_mS_M_u32	2847692032
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	15500
ANGLEVOLANTSigValidCount_Cnt_M_u16	35926
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	25370
AngleVolantMsgTimer_mS_M_u32	1356145920
AngleVolantValidCount_Cnt_M_u16	20679
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	483.318542
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1796019456
BSI3F2NTCsEnabled_Cnt_M_lgc	0

© Report created by TESSY V3.1.13, report template V2.1

Name	Input Value
BSI412NTCEnableTimer_mS_M_u32	126981376
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2458207488
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2181629184
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	48663
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3735799040
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	4333
CAVNodeAbsentTimer_mS_M_u32	3299898624
CDD_SrlComVehSpd_Kph_G_f32	419.155396
CMM388NTCEnableTimer_mS_M_u32	263959808
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	82736384
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	22909
CMMNodeAbsentTimer_mS_M_u32	3192587520
CONSANGLECPKSigInvalidCount_Cnt_M_u16	33912
CONSANGLECPKSigValidCount_Cnt_M_u16	12371
CONSANGLECPK_Cnt_M_u16	14834
CONSANGLECPK_HwDeg_M_f32	747.074829
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	14834
CPKVehicleSpeedMsgTimer_mS_M_u32	1907893504
CPKVehicleSpeedValidCount_Cnt_M_u16	12308
CityParkInputConsistentCount_Cnt_M_u16	60571
CityParkInputInvalidCount_Cnt_M_u16	18307
CityParkInputMsgTimer_mS_M_u32	605805056
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	982537472
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	677
ComputerRazGCTSigInvalidTimer_mS_M_u32	1801385216
ComputerRazGCTSigValidCount_Cnt_M_u16	49596
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	38831
DMDFCTCPKSigValidCount_Cnt_M_u16	36162
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	9590
DMDRELAXECPKSigValidCount_Cnt_M_u16	12480
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	46017
DateInvalidTimer_mS_M_u32	126981376
DiagMuxOnAbsentTimer_mS_M_u32	3034047744
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2181629184
ESPNTCEnableTimer_mS_M_u32	3650704640
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	61012
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	45
EffacDefaultDiagTimer_mS_M_u32[1]	99
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	9
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1551222016
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	48297
EtatMTSigValidCount_Cnt_M_u16	17968
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	43874
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	37565
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	57216
ISDAT4V2BSI552MsgTimer_mS_M_u32	102696192
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	63733
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	36260
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	17968
ISDATBSI3F2MsgTimer_mS_M_u32	1173218560
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	7331
ISDATBSI412MsgLenValidCount_Cnt_M_u16	46273

Name	Input Value
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	48297
ISDATBSI412MsgTimer_mS_M_u32	2414552320
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	38993
ISDATBSI432MsgLenValidCount_Cnt_M_u16	25640
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	12138
ISDATDIRASentFltAcc_Cnt_M_u16	9998
ISDATDIRASentTimer_mS_M_u32	1907893504
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	36744
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	20679
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	7354
ISDYN2CMMMsgTimer_mS_M_u32	2690340096
ISDYNAASChkSumInvalidCount_Cnt_M_u16	11707
ISDYNAASChkSumValidCount_Cnt_M_u16	43558
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	33746
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	38348
ISDYNAASMsgLenValidCount_Cnt_M_u16	33487
ISDYNAASMsgTimeValidCount_Cnt_M_u16	11707
ISDYNAASMsgTimer_mS_M_u32	2967975168
ISDYNABRChkSumInvalidCount_Cnt_M_u16	6720
ISDYNABRChkSumValidCount_Cnt_M_u16	13106
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	47430
ISDYNABRMsgCountValidCount_Cnt_M_u16	22513
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	26371
ISDYNABRMsgLenValidCount_Cnt_M_u16	29982
ISDYNABRMsgTimeValidCount_Cnt_M_u16	14834
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	160
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	205
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	17968
ISDYNCMM208MsgTimer_mS_M_u32	3949860096
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	491
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	311
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	5729
ISDYNCMM388MsgTimer_mS_M_u32	1032664320
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	60814
ISDYNVOLChkSumValidCount_Cnt_M_u16	24041
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	38853
ISDYNVOLMsgCountValidCount_Cnt_M_u16	37336
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	5577
ISDYNVOLMsgLenValidCount_Cnt_M_u16	29956
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	22909
ISDYNVOLMsgTimer_mS_M_u32	2290808064
IgnOnTimer_mS_M_u32	1415656704
IgnTimeOff_Sec_M_u32	2818087642
ManVehSpd_Kph_M_f32	406.047699
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	96
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	95
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4136363264
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	235
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1903183104
PrevISDATBSI412MsgDLCError_Cnt_M_u08	202
PrevISDATBSI412MsgRxTime_MSec_M_u32	3069015296
PrevISDATBSI432MsgDLCError_Cnt_M_u08	156
PrevISDATBSI432MsgRxTime_MSec_M_u32	236803328
PrevISDATDIRAMsgTxTime_MSec_M_u32	3784406272
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	38
PrevISDYN2CMMMsgRxTime_MSec_M_u32	827884800
PrevISDYNAASMsgDLCError_Cnt_M_u08	26
PrevISDYNAASMsgRxTime_MSec_M_u32	102823168
PrevISDYNABRMsgDLCError_Cnt_M_u08	161
PrevISDYNABRMsgRxTime_MSec_M_u32	2109289728
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	67
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1845622016

Name	Input Value
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	117
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1086084352
PrevISDYNVOLMsgDLCError_Cnt_M_u08	58
PrevISDYNVOLMsgRxTime_MSec_M_u32	3863377152
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3053528320
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	192.421906
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	17378
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	46437
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	6871
VitesseVehicleBVRampValidCount_Cnt_M_u16	18970
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	24321
VitesseVehicleBVSigValidCount_Cnt_M_u16	3211
VitesseVehicleBV_Kph_M_f32	432.888397
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	23261
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	19263
VitesseVehiculeRoues_Kph_M_f32	214.7314
k_AASNTCEnableTimeout_mS_u16	21
k_AASNodeAbsentDiag_Cnt_str.Threshold	15169
k_AASNodeAbsentDiag_Cnt_str.PStep	16589
k_AASNodeAbsentDiag_Cnt_str.NStep	52605
k_AASNodeAbsentTimeout_mS_u16	36606
k_AASNodeTimeout_mS_u16	52325
k_ABSNodeTimeout_mS_u16	25808
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	15048
k_ANGLEVOLANTSigValidThresh_Cnt_u16	49631
k_AngleVolantInvalidThresh_Cnt_u16	30482
k_AngleVolantValidThresh_Cnt_u16	18307
k_BSI552MsgTimeout_mS_u16	36402
k_BSINTCEnableTimeout_mS_u16	29097
k_BSINodeAbsentDiag_Cnt_str.Threshold	3812
k_BSINodeAbsentDiag_Cnt_str.PStep	43920
k_BSINodeAbsentDiag_Cnt_str.NStep	2285
k_BSINodeAbsentTimeout_mS_u16	42610
k_BSINodeTimeout_mS_u16	12138
k_BattOvHi_Volt_f32	25.8927994
k_BattOvLo_Volt_f32	25.5853004
k_BattUvHi_Volt_f32	14.9424
k_BattUvLo_Volt_f32	12.8866997
k_CAVNTCEnableTimeout_mS_u16	7921
k_CAVNodeAbsentDiag_Cnt_str.Threshold	49013
k_CAVNodeAbsentDiag_Cnt_str.PStep	18837
k_CAVNodeAbsentDiag_Cnt_str.NStep	36313
k_CAVNodeAbsentTimeout_mS_u16	28163
k_CAVNodeTimeout_mS_u16	15780
k_CMM388MsgTimeout_mS_u16	16337
k_CMM388NTCEnableTimeout_mS_u16	26109
k_CMMNTCEnableTimeout_mS_u16	15949
k_CMMNodeAbsentDiag_Cnt_str.Threshold	37289
k_CMMNodeAbsentDiag_Cnt_str.PStep	4997
k_CMMNodeAbsentDiag_Cnt_str.NStep	26757
k_CMMNodeAbsentTimeout_mS_u16	12139
k_CONSANGLECPKMax_HwDeg_f32	48.8678017
k_CONSANGLECPKMin_HwDeg_f32	-93.0102005
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	12765
k_CONSANGLECPKSigValidThresh_Cnt_u16	25151
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	52643
k_CPKVehicleSpeedValidThresh_Cnt_u16	34882

Name	Input Value
k_CityParkInputInvalidThresh_Cnt_u16	46590
k_CityParkInputValidThresh_Cnt_u16	60571
k_ComputerRazGCTSigValidThresh_Cnt_u16	23059
k_CptTemporelSigValidThresh_Cnt_u16	10562
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	48643
k_DMDFCTCPKSigValidThresh_Cnt_u16	3102
k_DMDFCTCPKValidCount_Cnt_u16	41407
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	7354
k_DMDRELAXECPKSigValidThresh_Cnt_u16	21645
k_DMDRelaxeConsistentThresh_Cnt_u16	47051
k_DateValidThresh_Cnt_u16	57216
k_DefaultVehSpd_Kph_f32	166.3741
k_DiagMuxOnAbsentTimeout_mS_u16	7392
k_EMNodeTimeout_mS_u16	26529
k_ESPNTCEnableTimeout_mS_u16	33817
k_ESPNodeAbsentDiag_Cnt_str.Threshold	34801
k_ESPNodeAbsentDiag_Cnt_str.PStep	61533
k_ESPNodeAbsentDiag_Cnt_str.NStep	26605
k_ESPNodeAbsentTimeout_mS_u16	48659
k_EtatMTSigInvalidThresh_Cnt_u16	45523
k_EtatMTSigValidThresh_Cnt_u16	25349
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	60322
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	38537
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	60816
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	14814
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	56141
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	18807
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	56506
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	21841
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	5925
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	6822
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	38501
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	2916
k_ISDATDIRASentDiag_Cnt_str.Threshold	12438
k_ISDATDIRASentDiag_Cnt_str.PStep	4214
k_ISDATDIRASentDiag_Cnt_str.NStep	47738
k_ISDATDIRASentTimeout_mS_u16	22892
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	30917
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	25370
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	39061
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	61760
k_ISDYNAASChkSumValidThresh_Cnt_u16	18994
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	4166
k_ISDYNAASMsgCountValidThresh_Cnt_u16	61169
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	61972
k_ISDYNAASMsgLenValidThresh_Cnt_u16	57401
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	30343
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	28441
k_ISDYNABRChkSumValidThresh_Cnt_u16	33204
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	5399
k_ISDYNABRMsgCountValidThresh_Cnt_u16	18209
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	28797
k_ISDYNABRMsgLenValidThresh_Cnt_u16	17748
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	10644
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	30646
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	61912
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	14936
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	37772
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	9046
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	65243
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	9626
k_ISDYNVOLChkSumValidThresh_Cnt_u16	22776
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	7069
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	518
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	32981
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	4956
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	15726
k_IgnOnTimeout_mS_u16	2246
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	221.089401
k_PowerCutVehSpdLowThresh_Kph_f32	180.003494
k_PowerCutVehSpdLowTimeout_mS_u16	25457
k_VBattMaxAAS_Volt_f32	0.1391

Name	Input Value
k_VBattMaxBSI_Volt_f32	1.99820006
k_VBattMaxCAV_Volt_f32	12.6349001
k_VBattMaxCMM388_Volt_f32	30.9256001
k_VBattMaxCMM_Volt_f32	21.2677994
k_VBattMaxESP_Volt_f32	16.6110001
k_VBattMinAAS_Volt_f32	32
k_VBattMinBSI_Volt_f32	16.6110001
k_VBattMinCAV_Volt_f32	25.6175003
k_VBattMinCMM388_Volt_f32	1.23570001
k_VBattMinCMM_Volt_f32	30.2038994
k_VBattMinESP_Volt_f32	21.2677994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	13959
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	56662
k_VitesseVehicleBVRampValidThresh_Cnt_u16	28357
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	62697
k_VitesseVehicleBVSigValidThresh_Cnt_u16	44264
k_VitesseVehicleBVSpeedPassThresh_kph_f32	598.982117
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	59373
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	56240
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	126981376
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	1
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	24687
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	511932416
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	117
target_SrlComInput_Per1_Batt_Volt_f32.value	28.1149998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2332607744
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	235
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0761216804
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	791885056
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4247901440
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3116397824
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	89
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3437171968
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2660087040
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	87
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2529973504
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	41
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	496694528
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	37
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	63
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	86
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	93
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	164
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2410943744
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	139
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	140
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	165

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	188
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	196
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	192034048
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	653317376
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4043273472
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	57
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	58
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	106
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	117
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	225
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	53101824
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1856
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.442856252
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	326207
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	196.154099
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	34084

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	511932416	511932416	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	511932416	511932416	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	511932416	511932416	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	483.318542	483.318542	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	511932416	511932416	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	511932416	511932416	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	511932416	511932416	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	511932416	511932416	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	3812	3812	✔
BSINodeAbsentTimer_mS_M_u32	511932416	511932416	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	511932416	511932416	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	49013	49013	✔
CAVNodeAbsentTimer_mS_M_u32	511932416	511932416	✔
CDD_SrlComVehSpd_Kph_G_f32	406.047699	406.047699	✔
CMM388NTCEnableTimer_mS_M_u32	511932416	511932416	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	511932416	511932416	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	511932416	511932416	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	14834	14834	✔
CONSANGLECPK_HwDeg_M_f32	747.074829	747.074829 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	511932416	511932416	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	511932416	511932416	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	511932416	511932416	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	511932416	511932416	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	511932416	511932416	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	511932416	511932416	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	511932416	511932416	✔
ESPNTCEnableTimer_mS_M_u32	511932416	511932416	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	511932416	511932416	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	45	45	✔
EffacDefaultDiagTimer_mS_M_u32[1]	99	99	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	8	8	✔
ElecIntTimer_mS_M_u32[1]	9	9	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	511932416	511932416	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	57216	57216	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	511932416	511932416	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	17968	17968	✔
ISDATBSI3F2MsgTimer_mS_M_u32	511932416	511932416	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	48297	48297	✔
ISDATBSI412MsgTimer_mS_M_u32	511932416	511932416	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	12138	12138	✔
ISDATBSI432MsgTimer_mS_M_u32	511932416	511932416	✔
ISDATDIRASentFltAcc_Cnt_M_u16	12438	12438	✔
ISDATDIRASentTimer_mS_M_u32	511932416	511932416	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	7354	7354	✔
ISDYN2CMMMsgTimer_mS_M_u32	511932416	511932416	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	11707	11707	✔
ISDYNAASMsgTimer_mS_M_u32	511932416	511932416	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	14834	14834	✔
ISDYNABRMsgTimer_mS_M_u32	511932416	511932416	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	17968	17968	✔
ISDYNCMM208MsgTimer_mS_M_u32	511932416	511932416	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	5729	5729	✔
ISDYNCMM388MsgTimer_mS_M_u32	511932416	511932416	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	22909	22909	✔
ISDYNVOLMsgTimer_mS_M_u32	511932416	511932416	✔
IgnOnTimer_mS_M_u32	1415656704	1415656704	✔
IgnTimeOff_Sec_M_u32	2818087642	2818087642	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	105	105	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	791885056	791885056	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	134	134	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4247901440	4247901440	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	95	95	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3116397824	3116397824	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	89	89	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3437171968	3437171968	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3784406272	3784406272	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	87	87	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2529973504	2529973504	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	41	41	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	496694528	496694528	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	2	2	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2410943744	2410943744	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	192034048	192034048	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	653317376	653317376	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	215	215	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4043273472	4043273472	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	53101824	53101824	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	192.421906	192.421906	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	432.888397	432.888397	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	214.7314	214.7314	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	483.318542	483.318542	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	14834	14834	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2818087642	2818087642	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	747.074829	747.074829 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	406.047699	406.047699	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.218 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4294136832
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	51709
AASNodeAbsentTimer_mS_M_u32	3455960064
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	55502
ANGLEVOLANTSigValidCount_Cnt_M_u16	45102
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	48930
AngleVolantMsgTimer_mS_M_u32	4294136832
AngleVolantValidCount_Cnt_M_u16	61596
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3171648512
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2575172608
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2741171200
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2480387072
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	16429
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2028958720
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	27177
CAVNodeAbsentTimer_mS_M_u32	4120994816

Name	Input Value
CDD_SrlComVehSpd_Kph_G_f32	110.844398
CMM388NTCEnableTimer_mS_M_u32	1367319552
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2900845568
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	64569
CMMNodeAbsentTimer_mS_M_u32	1729213440
CONSANGLECPKSigInvalidCount_Cnt_M_u16	41992
CONSANGLECPKSigValidCount_Cnt_M_u16	42808
CONSANGLECPK_Cnt_M_u16	50779
CONSANGLECPK_HwDeg_M_f32	-186.154007
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	50779
CPKVehicleSpeedMsgTimer_mS_M_u32	3913962496
CPKVehicleSpeedValidCount_Cnt_M_u16	6334
CityParkInputConsistentCount_Cnt_M_u16	27936
CityParkInputInvalidCount_Cnt_M_u16	19816
CityParkInputMsgTimer_mS_M_u32	791885056
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1803666432
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	52353
ComputerRazGCTSigInvalidTimer_mS_M_u32	3684033536
ComputerRazGCTSigValidCount_Cnt_M_u16	45501
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	3300
DMDFCTCPKSigValidCount_Cnt_M_u16	4844
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	17936
DMDRELAXECPKSigValidCount_Cnt_M_u16	60144
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	31277
DateInvalidTimer_mS_M_u32	2575172608
DiagMuxOnAbsentTimer_mS_M_u32	1324028928
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2480387072
ESPNTCEnableTimer_mS_M_u32	4066821120
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	13429
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	66
EffacDefaultDiagTimer_mS_M_u32[1]	79
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	11
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2811327488
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	54196
EtatMTSigValidCount_Cnt_M_u16	60896
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	22346
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	43002
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	37938
ISDAT4V2BSI552MsgTimer_mS_M_u32	3751130112
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	42577
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	16133
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	60896
ISDATBSI3F2MsgTimer_mS_M_u32	1940460544
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	32841
ISDATBSI412MsgLenValidCount_Cnt_M_u16	52909
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	54196
ISDATBSI412MsgTimer_mS_M_u32	447828992
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	36797
ISDATBSI432MsgLenValidCount_Cnt_M_u16	8953
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	17074
ISDATDIRASentFltAcc_Cnt_M_u16	60358
ISDATDIRASentTimer_mS_M_u32	3913962496
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	40345
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	61596
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	27075
ISDYN2CMMMsgTimer_mS_M_u32	639681536
ISDYNAASChkSumInvalidCount_Cnt_M_u16	9023

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNAASChkSumValidCount_Cnt_M_u16	62655
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	17275
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	6028
ISDYNAASMsgLenValidCount_Cnt_M_u16	63300
ISDYNAASMsgTimeValidCount_Cnt_M_u16	9023
ISDYNAASMsgTimer_mS_M_u32	503030784
ISDYNABRChkSumInvalidCount_Cnt_M_u16	26418
ISDYNABRChkSumValidCount_Cnt_M_u16	33562
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	27806
ISDYNABRMsgCountValidCount_Cnt_M_u16	55134
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	59495
ISDYNABRMsgLenValidCount_Cnt_M_u16	50391
ISDYNABRMsgTimeValidCount_Cnt_M_u16	50779
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	161
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	207
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	60896
ISDYNCMM208MsgTimer_mS_M_u32	4293428224
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	495
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	313
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	43610
ISDYNCMM388MsgTimer_mS_M_u32	3993707520
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	16582
ISDYNVOLChkSumValidCount_Cnt_M_u16	63094
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	58530
ISDYNVOLMsgCountValidCount_Cnt_M_u16	56618
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	53782
ISDYNVOLMsgLenValidCount_Cnt_M_u16	15142
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	64569
ISDYNVOLMsgTimer_mS_M_u32	873587712
IgnOnTimer_mS_M_u32	4186907648
IgnTimeOff_Sec_M_u32	2357137361
ManVehSpd_Kph_M_f32	8.51599979
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	97
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	208
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1506743296
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	240
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1923216384
PrevISDATBSI412MsgDLCError_Cnt_M_u08	90
PrevISDATBSI412MsgRxTime_MSec_M_u32	1391092736
PrevISDATBSI432MsgDLCError_Cnt_M_u08	43
PrevISDATBSI432MsgRxTime_MSec_M_u32	1692058624
PrevISDATDIRAMsgTxTime_MSec_M_u32	1660838912
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	241
PrevISDYN2CMMMsgRxTime_MSec_M_u32	602485760
PrevISDYNAASMsgDLCError_Cnt_M_u08	96
PrevISDYNAASMsgRxTime_MSec_M_u32	2471486464
PrevISDYNABRMsgDLCError_Cnt_M_u08	155
PrevISDYNABRMsgRxTime_MSec_M_u32	3716621312
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	211
PrevISDYNCMM208MsgRxTime_MSec_M_u32	531424256
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	246
PrevISDYNCMM388MsgRxTime_MSec_M_u32	150848512
PrevISDYNVOLMsgDLCError_Cnt_M_u08	182
PrevISDYNVOLMsgRxTime_MSec_M_u32	1759470592
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2154779648
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	57.7901993
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	58698
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	14210
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	29803
VitesseVehicleBVRampValidCount_Cnt_M_u16	36195
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	34159
VitesseVehicleBVSigValidCount_Cnt_M_u16	0
VitesseVehicleBV_Kph_M_f32	390.123901
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	43610
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	65522
VitesseVehiculeRoues_Kph_M_f32	540.802612
k_AASNTCEnableTimeout_mS_u16	49138
k_AASNodeAbsentDiag_Cnt_str.Threshold	54615
k_AASNodeAbsentDiag_Cnt_str.PStep	8307
k_AASNodeAbsentDiag_Cnt_str.NStep	26147
k_AASNodeAbsentTimeout_mS_u16	53751
k_AASNodeTimeout_mS_u16	62082
k_ABSNodeTimeout_mS_u16	27009
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	17496
k_ANGLEVOLANTSigValidThresh_Cnt_u16	42452
k_AngleVolantInvalidThresh_Cnt_u16	4667
k_AngleVolantValidThresh_Cnt_u16	19816
k_BSI552MsgTimeout_mS_u16	49945
k_BSINTCEnableTimeout_mS_u16	25525
k_BSINodeAbsentDiag_Cnt_str.Threshold	3852
k_BSINodeAbsentDiag_Cnt_str.PStep	43903
k_BSINodeAbsentDiag_Cnt_str.NStep	2308
k_BSINodeAbsentTimeout_mS_u16	21786
k_BSINodeTimeout_mS_u16	17074
k_BattOvHi_Volt_f32	8.23050022
k_BattOvLo_Volt_f32	24.8633995
k_BattUvHi_Volt_f32	0.773999989
k_BattUvLo_Volt_f32	1.70430005
k_CAVNTCEnableTimeout_mS_u16	65310
k_CAVNodeAbsentDiag_Cnt_str.Threshold	38266
k_CAVNodeAbsentDiag_Cnt_str.PStep	41690
k_CAVNodeAbsentDiag_Cnt_str.NStep	4559
k_CAVNodeAbsentTimeout_mS_u16	10983
k_CAVNodeTimeout_mS_u16	10372
k_CMM388MsgTimeout_mS_u16	50429
k_CMM388NTCEnableTimeout_mS_u16	633
k_CMMNTCEnableTimeout_mS_u16	13897
k_CMMNodeAbsentDiag_Cnt_str.Threshold	25884
k_CMMNodeAbsentDiag_Cnt_str.PStep	31561
k_CMMNodeAbsentDiag_Cnt_str.NStep	43017
k_CMMNodeAbsentTimeout_mS_u16	878
k_CONSANGLECPKMax_HwDeg_f32	684.576599
k_CONSANGLECPKMin_HwDeg_f32	-231.946594
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	9562
k_CONSANGLECPKSigValidThresh_Cnt_u16	47858
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	26312
k_CPKVehicleSpeedValidThresh_Cnt_u16	31084
k_CityParkInputInvalidThresh_Cnt_u16	3064
k_CityParkInputValidThresh_Cnt_u16	27936
k_ComputerRazGCTSigValidThresh_Cnt_u16	31479
k_CptTemporelSigValidThresh_Cnt_u16	25643
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	58215
k_DMDFCTCPKSigValidThresh_Cnt_u16	65495
k_DMDFCTCPKValidCount_Cnt_u16	13621
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	27075
k_DMDRELAXECPKSigValidThresh_Cnt_u16	43275
k_DMDRelaxeConsistentThresh_Cnt_u16	63313
k_DateValidThresh_Cnt_u16	37938
k_DefaultVehSpd_Kph_f32	241.826004

Name	Input Value
k_DiagMuxOnAbsentTimeout_mS_u16	21905
k_EMNodeTimeout_mS_u16	56973
k_ESPNTCEnableTimeout_mS_u16	49317
k_ESPNodeAbsentDiag_Cnt_str.Threshold	20805
k_ESPNodeAbsentDiag_Cnt_str.PStep	62401
k_ESPNodeAbsentDiag_Cnt_str.NStep	63698
k_ESPNodeAbsentTimeout_mS_u16	63350
k_EtatMTSigInvalidThresh_Cnt_u16	44153
k_EtatMTSigValidThresh_Cnt_u16	65441
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	51403
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	65239
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	32321
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	51094
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	14858
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	18893
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	42626
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	13182
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	25409
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	62527
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	6082
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	18693
k_ISDATDIRASentDiag_Cnt_str.Threshold	1559
k_ISDATDIRASentDiag_Cnt_str.PStep	4663
k_ISDATDIRASentDiag_Cnt_str.NStep	20460
k_ISDATDIRASentTimeout_mS_u16	22958
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	50402
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	48930
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	29489
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	57906
k_ISDYNAASChkSumValidThresh_Cnt_u16	15898
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	26526
k_ISDYNAASMsgCountValidThresh_Cnt_u16	4702
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	12214
k_ISDYNAASMsgLenValidThresh_Cnt_u16	1798
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	10204
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	43045
k_ISDYNABRChkSumValidThresh_Cnt_u16	30485
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	15149
k_ISDYNABRMsgCountValidThresh_Cnt_u16	27597
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46905
k_ISDYNABRMsgLenValidThresh_Cnt_u16	12149
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	20596
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	39374
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	5290
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	13481
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	54222
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	60206
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	34656
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	356
k_ISDYNVOLChkSumValidThresh_Cnt_u16	32264
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	4250
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	26270
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	14128
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	13916
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	45672
k_IgnOnTimeout_mS_u16	2016
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	146.179993
k_PowerCutVehSpdLowThresh_Kph_f32	53.4378014
k_PowerCutVehSpdLowTimeout_mS_u16	1502
k_VBattMaxAAS_Volt_f32	10.7908001
k_VBattMaxBSI_Volt_f32	16.6215992
k_VBattMaxCAV_Volt_f32	3.69300008
k_VBattMaxCMM388_Volt_f32	22.1042995
k_VBattMaxCMM_Volt_f32	11.4712
k_VBattMaxESP_Volt_f32	14.5811996
k_VBattMinAAS_Volt_f32	17.4738007
k_VBattMinBSI_Volt_f32	14.5811996
k_VBattMinCAV_Volt_f32	13.0528002
k_VBattMinCMM388_Volt_f32	21.8565006
k_VBattMinCMM_Volt_f32	14.4078999
k_VBattMinESP_Volt_f32	11.4712
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	5020

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	62960
k_VitesseVehicleBVRampValidThresh_Cnt_u16	24482
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	12662
k_VitesseVehicleBVSigValidThresh_Cnt_u16	41017
k_VitesseVehicleBVSpeedPassThresh_kph_f32	277.058197
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	58665
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	45217
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2575172608
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	232
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	50632
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3958659840
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	246
target_SrlComInput_Per1_Batt_Volt_f32.value	4.14849997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	668496896
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	239
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.969729006
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	249
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	823731200
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2308785152
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	156
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1450271744
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1603634176
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1829348352
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1187890176
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3034702848
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	102
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	153
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	223
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2870379520
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	69
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	93
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	164
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	173
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	205
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1482433536
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3361752064
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1823761408
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	91
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	106
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	123

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	176
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	186
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	203
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	628356096
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2911
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.904535234
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	683897
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	147.235901
target_SrlComInput_Per1_VitesseVehiculeBV_Cnt_u16.value	43396

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3958659840	3958659840	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3958659840	3958659840	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3958659840	3958659840	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3958659840	3958659840	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3958659840	3958659840	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3958659840	3958659840	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3958659840	3958659840	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	3852	3852	✔
BSINodeAbsentTimer_mS_M_u32	3958659840	3958659840	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3958659840	3958659840	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	38266	38266	✔
CAVNodeAbsentTimer_mS_M_u32	3958659840	3958659840	✔
CDD_SrlComVehSpd_Kph_G_f32	8.51599979	8.51599979	✔
CMM388NTCEnableTimer_mS_M_u32	3958659840	3958659840	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3958659840	3958659840	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3958659840	3958659840	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	50779	50779	✔
CONSANGLECPK_HwDeg_M_f32	-186.154007	-186.154007 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3958659840	3958659840	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3958659840	3958659840	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3958659840	3958659840	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3958659840	3958659840	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3958659840	3958659840	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3958659840	3958659840	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3958659840	3958659840	✔
ESPNTCEnableTimer_mS_M_u32	3958659840	3958659840	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3958659840	3958659840	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	66	66	✔
EffacDefaultDiagTimer_mS_M_u32[1]	79	79	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	10	10	✔
ElecIntTimer_mS_M_u32[1]	11	11	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3958659840	3958659840	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	37938	37938	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3958659840	3958659840	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	60896	60896	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3958659840	3958659840	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	54196	54196	✔
ISDATBSI412MsgTimer_mS_M_u32	3958659840	3958659840	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	17074	17074	✔
ISDATBSI432MsgTimer_mS_M_u32	3958659840	3958659840	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1559	1559	✔
ISDATDIRASentTimer_mS_M_u32	3958659840	3958659840	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	27075	27075	✔
ISDYN2CMMMsgTimer_mS_M_u32	3958659840	3958659840	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	9023	9023	✔
ISDYNAASMsgTimer_mS_M_u32	3958659840	3958659840	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	50779	50779	✔
ISDYNABRMsgTimer_mS_M_u32	3958659840	3958659840	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	60896	60896	✔
ISDYNCMM208MsgTimer_mS_M_u32	3958659840	3958659840	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	43610	43610	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM388MsgTimer_mS_M_u32	3958659840	3958659840	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	64569	64569	✔
ISDYNVOLMsgTimer_mS_M_u32	3958659840	3958659840	✔
IgnOnTimer_mS_M_u32	4186907648	4186907648	✔
IgnTimeOff_Sec_M_u32	2357137361	2357137361	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	249	249	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	823731200	823731200	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	67	67	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2308785152	2308785152	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	156	156	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1450271744	1450271744	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	206	206	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1603634176	1603634176	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1660838912	1660838912	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	219	219	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1187890176	1187890176	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	70	70	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3034702848	3034702848	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	105	105	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2870379520	2870379520	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	29	29	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1482433536	1482433536	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	30	30	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3361752064	3361752064	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	239	239	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1823761408	1823761408	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	628356096	628356096	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	57.7901993	57.7901993	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	390.123901	390.123901	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	540.802612	540.802612	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	50779	50779	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2357137361	2357137361	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-186.154007	-186.154007 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	8.51599979	8.51599979	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.219 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1779746560
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	22005
AASNodeAbsentTimer_mS_M_u32	1974826752
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	2947
ANGLEVOLANTSigValidCount_Cnt_M_u16	12579
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	19078
AngleVolantMsgTimer_mS_M_u32	1779746560
AngleVolantValidCount_Cnt_M_u16	50839
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	260847360
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1681176320
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1178986240
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	937928448
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	4454
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2543871744
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	11250
CAVNodeAbsentTimer_mS_M_u32	2504693504
CDD_SrlComVehSpd_Kph_G_f32	324.275085
CMM388NTCEnableTimer_mS_M_u32	3400521472
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	125343488
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	12929
CMMNodeAbsentTimer_mS_M_u32	641312512
CONSANGLECPKSigInvalidCount_Cnt_M_u16	49366
CONSANGLECPKSigValidCount_Cnt_M_u16	41734
CONSANGLECPK_Cnt_M_u16	37277
CONSANGLECPK_HwDeg_M_f32	-517.70929
CPKOK_Cnt_M_lgc	0

Name	Input Value
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37277
CPKVehicleSpeedMsgTimer_mS_M_u32	3390031616
CPKVehicleSpeedValidCount_Cnt_M_u16	7195
CityParkInputConsistentCount_Cnt_M_u16	24843
CityParkInputInvalidCount_Cnt_M_u16	60726
CityParkInputMsgTimer_mS_M_u32	823731200
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2905175808
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	24169
ComputerRazGCTSigInvalidTimer_mS_M_u32	1433212672
ComputerRazGCTSigValidCount_Cnt_M_u16	18228
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	40642
DMDFCTCPKSigValidCount_Cnt_M_u16	55402
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	19389
DMDRELAXECPKSigValidCount_Cnt_M_u16	2269
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	4711
DateInvalidTimer_mS_M_u32	1681176320
DiagMuxOnAbsentTimer_mS_M_u32	204310272
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	937928448
ESPNTCEnableTimer_mS_M_u32	3967448832
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	42382
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	1
ElecIntTimer_mS_M_u32[0]	80
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	330983168
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	43280
EtatMTSigValidCount_Cnt_M_u16	13900
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	12048
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	10432
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	60568
ISDAT4V2BSI552MsgTimer_mS_M_u32	3433932544
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	39610
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	52319
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13900
ISDATBSI3F2MsgTimer_mS_M_u32	368281344
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	15826
ISDATBSI412MsgLenValidCount_Cnt_M_u16	3686
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	43280
ISDATBSI412MsgTimer_mS_M_u32	2447034112
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	34805
ISDATBSI432MsgLenValidCount_Cnt_M_u16	59906
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	1623
ISDATDIRASentFltAcc_Cnt_M_u16	23323
ISDATDIRASentTimer_mS_M_u32	3390031616
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	33763
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	50839
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	50213
ISDYN2CMMMsgTimer_mS_M_u32	3108796160
ISDYNAASChkSumInvalidCount_Cnt_M_u16	53807
ISDYNAASChkSumValidCount_Cnt_M_u16	35183
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	2554
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	28617
ISDYNAASMsgLenValidCount_Cnt_M_u16	56417
ISDYNAASMsgTimeValidCount_Cnt_M_u16	53807
ISDYNAASMsgTimer_mS_M_u32	1429985024
ISDYNABRChkSumInvalidCount_Cnt_M_u16	59862
ISDYNABRChkSumValidCount_Cnt_M_u16	25054
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	12818
ISDYNABRMsgCountValidCount_Cnt_M_u16	7570
ISDYNABRMsgCount_Cnt_M_u08	12

Name	Input Value
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	12217
ISDYNABRMsgLenValidCount_Cnt_M_u16	34345
ISDYNABRMsgTimeValidCount_Cnt_M_u16	37277
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	725
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1335
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13900
ISDYNCMM208MsgTimer_mS_M_u32	4210374400
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2751
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1441
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	4445
ISDYNCMM388MsgTimer_mS_M_u32	2198689536
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	25244
ISDYNVOLChkSumValidCount_Cnt_M_u16	11596
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	36744
ISDYNVOLMsgCountValidCount_Cnt_M_u16	61872
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	37035
ISDYNVOLMsgLenValidCount_Cnt_M_u16	49467
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	12929
ISDYNVOLMsgTimer_mS_M_u32	1006180096
IgnOnTimer_mS_M_u32	1887524608
IgnTimeOff_Sec_M_u32	2713333955
ManVehSpd_Kph_M_f32	399.874786
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	187
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2072086272
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	87
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2492000000
PrevISDATBSI412MsgDLCError_Cnt_M_u08	3
PrevISDATBSI412MsgRxTime_MSec_M_u32	3782186752
PrevISDATBSI432MsgDLCError_Cnt_M_u08	186
PrevISDATBSI432MsgRxTime_MSec_M_u32	1696495360
PrevISDATDIRAMsgTxTime_MSec_M_u32	20158208
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	67
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2914199296
PrevISDYNAASMsgDLCError_Cnt_M_u08	13
PrevISDYNAASMsgRxTime_MSec_M_u32	2520717056
PrevISDYNABRMsgDLCError_Cnt_M_u08	243
PrevISDYNABRMsgRxTime_MSec_M_u32	2761512704
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	234
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2770867968
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	84
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3300226816
PrevISDYNVOLMsgDLCError_Cnt_M_u08	234
PrevISDYNVOLMsgRxTime_MSec_M_u32	3012597504
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3634415360
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	57.8423004
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	32399
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	37799
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0

Name	Input Value
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	38188
VitesseVehicleBVRampValidCount_Cnt_M_u16	22020
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	51616
VitesseVehicleBVSigValidCount_Cnt_M_u16	65535
VitesseVehicleBV_Kph_M_f32	494.020996
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	4445
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	40022
VitesseVehiculeRoues_Kph_M_f32	240.681503
k_AASNTCEnableTimeout_mS_u16	49368
k_AASNodeAbsentDiag_Cnt_str.Threshold	10757
k_AASNodeAbsentDiag_Cnt_str.PStep	7105
k_AASNodeAbsentDiag_Cnt_str.NStep	65461
k_AASNodeAbsentTimeout_mS_u16	20102
k_AASNodeTimeout_mS_u16	25255
k_ABSNodeTimeout_mS_u16	15595
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	38436
k_ANGLEVOLANTSigValidThresh_Cnt_u16	36209
k_AngleVolantInvalidThresh_Cnt_u16	42044
k_AngleVolantValidThresh_Cnt_u16	60726
k_BSI552MsgTimeout_mS_u16	44769
k_BSINTCEnableTimeout_mS_u16	60429
k_BSINodeAbsentDiag_Cnt_str.Threshold	26412
k_BSINodeAbsentDiag_Cnt_str.PStep	34315
k_BSINodeAbsentDiag_Cnt_str.NStep	15280
k_BSINodeAbsentTimeout_mS_u16	26782
k_BSINodeTimeout_mS_u16	1623
k_BattOvHi_Volt_f32	18.3689003
k_BattOvLo_Volt_f32	18.8388004
k_BattUvHi_Volt_f32	31.5
k_BattUvLo_Volt_f32	12.0806999
k_CAVNTCEnableTimeout_mS_u16	12308
k_CAVNodeAbsentDiag_Cnt_str.Threshold	9850
k_CAVNodeAbsentDiag_Cnt_str.PStep	55599
k_CAVNodeAbsentDiag_Cnt_str.NStep	26463
k_CAVNodeAbsentTimeout_mS_u16	25016
k_CAVNodeTimeout_mS_u16	9058
k_CMM388MsgTimeout_mS_u16	25845
k_CMM388NTCEnableTimeout_mS_u16	40065
k_CMMNTCEnableTimeout_mS_u16	51922
k_CMMNodeAbsentDiag_Cnt_str.Threshold	32647
k_CMMNodeAbsentDiag_Cnt_str.PStep	42126
k_CMMNodeAbsentDiag_Cnt_str.NStep	57005
k_CMMNodeAbsentTimeout_mS_u16	33250
k_CONSANGLECPKMax_HwDeg_f32	337.877289
k_CONSANGLECPKMin_HwDeg_f32	-680.081421
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	41053
k_CONSANGLECPKSigValidThresh_Cnt_u16	27478
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	40405
k_CPKVehicleSpeedValidThresh_Cnt_u16	40553
k_CityParkInputInvalidThresh_Cnt_u16	37764
k_CityParkInputValidThresh_Cnt_u16	24843
k_ComputerRazGCTSigValidThresh_Cnt_u16	13512
k_CptTemporelSigValidThresh_Cnt_u16	29933
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	16057
k_DMDFCTCPKSigValidThresh_Cnt_u16	54569
k_DMDFCTCPKValidCount_Cnt_u16	21070
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	50213
k_DMDRELAXECPKSigValidThresh_Cnt_u16	21005
k_DMDRelaxeConsistentThresh_Cnt_u16	65339
k_DateValidThresh_Cnt_u16	60568
k_DefaultVehSpd_Kph_f32	188.954697
k_DiagMuxOnAbsentTimeout_mS_u16	15355
k_EMNodeTimeout_mS_u16	25927
k_ESPNTCEnableTimeout_mS_u16	6270
k_ESPNodeAbsentDiag_Cnt_str.Threshold	40274
k_ESPNodeAbsentDiag_Cnt_str.PStep	1844
k_ESPNodeAbsentDiag_Cnt_str.NStep	56738
k_ESPNodeAbsentTimeout_mS_u16	50634
k_EtatMTSigInvalidThresh_Cnt_u16	62977
k_EtatMTSigValidThresh_Cnt_u16	51273
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	17356
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	64872
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	61864

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	35563
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	12112
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	61766
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	38822
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	3187
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	7529
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	38897
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	26917
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	9373
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	610
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	25862
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	19078
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	12506
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	30934
k_ISDYNAASChkSumValidThresh_Cnt_u16	12510
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	16658
k_ISDYNAASMsgCountValidThresh_Cnt_u16	27794
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	41034
k_ISDYNAASMsgLenValidThresh_Cnt_u16	13595
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	10073
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	26751
k_ISDYNABRChkSumValidThresh_Cnt_u16	59247
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	8294
k_ISDYNABRMsgCountValidThresh_Cnt_u16	14918
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	385
k_ISDYNABRMsgLenValidThresh_Cnt_u16	46222
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	59473
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	28931
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	17583
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	63538
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	6787
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	32803
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	8014
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	59009
k_ISDYNVOLChkSumValidThresh_Cnt_u16	11349
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	58655
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	51026
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	28316
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	19672
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	59894
k_IgnOnTimeout_mS_u16	49933
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	14.3927002
k_PowerCutVehSpdLowThresh_Kph_f32	172.619202
k_PowerCutVehSpdLowTimeout_mS_u16	40724
k_VBattMaxAAS_Volt_f32	8.41759968
k_VBattMaxBSI_Volt_f32	22.7005997
k_VBattMaxCAV_Volt_f32	4.54209995
k_VBattMaxCMM388_Volt_f32	26.4587002
k_VBattMaxCMM_Volt_f32	12.1772003
k_VBattMaxESP_Volt_f32	2.42840004
k_VBattMinAAS_Volt_f32	6.38339996
k_VBattMinBSI_Volt_f32	2.42840004
k_VBattMinCAV_Volt_f32	29.5398998
k_VBattMinCMM388_Volt_f32	10.1541996
k_VBattMinCMM_Volt_f32	13.132
k_VBattMinESP_Volt_f32	12.1772003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	57560
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	46492
k_VitesseVehicleBVRampValidThresh_Cnt_u16	7816
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	31820
k_VitesseVehicleBVSigValidThresh_Cnt_u16	27584
k_VitesseVehicleBVSpeedPassThresh_kph_f32	333.912598
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	47858
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	25674
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1681176320
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	61
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1

Name	Input Value
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	84
target_SrlComInput_Per1_Batt_Volt_f32.value	18.2334995
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1860527872
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	93
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.947960734
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	179
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1910724352
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	550958848
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	58
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3000669952
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	61
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3488495360
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	538040064
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	7
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1262843648
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4186511104
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	123
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	214
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	829110016
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	169
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	177
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	223
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	225
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	246
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3357169408
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	814610176
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1007785728
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	71
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	188
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1142089472
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2461
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.554696381
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	626990
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	232.475006
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	39393

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	10757	10757	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26412	26412	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	32647	32647	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	37277	37277	✔
CONSANGLECPK_HwDeg_M_f32	-517.70929	-517.70929 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3251510528	3251510528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	80	80	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	1887524608	1887524608	✔
IgnTimeOff_Sec_M_u32	2713333955	2713333955	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	179	179	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1910724352	1910724352	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	239	239	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	550958848	550958848	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	58	58	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3000669952	3000669952	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	61	61	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3488495360	3488495360	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	20158208	20158208	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	7	7	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1262843648	1262843648	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	31	31	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4186511104	4186511104	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	178	178	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	829110016	829110016	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3357169408	3357169408	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	814610176	814610176	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	15	15	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1007785728	1007785728	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1142089472	1142089472	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	57.8423004	57.8423004	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	494.020996	494.020996	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	240.681503	240.681503	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	37277	37277	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2713333955	2713333955	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-517.70929	-517.70929 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.220 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3040636416
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	5018
AASNodeAbsentTimer_mS_M_u32	823811584
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	19695
ANGLEVOLANTSigValidCount_Cnt_M_u16	55502
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	47591
AngleVolantMsgTimer_mS_M_u32	3040636416
AngleVolantValidCount_Cnt_M_u16	5171
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	781590016
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1922866688
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3442019840
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2940456448
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	34630
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1662619136
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	28195
CAVNodeAbsentTimer_mS_M_u32	249232896
CDD_SrlComVehSpd_Kph_G_f32	464.78891
CMM388NTCEnableTimer_mS_M_u32	2477473280
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	4031839744
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	9269
CMMNodeAbsentTimer_mS_M_u32	2890780160
CONSANGLECPKSigInvalidCount_Cnt_M_u16	59383
CONSANGLECPKSigValidCount_Cnt_M_u16	32294
CONSANGLECPK_Cnt_M_u16	52833
CONSANGLECPK_HwDeg_M_f32	407.119385
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	52833
CPKVehicleSpeedMsgTimer_mS_M_u32	1095462400
CPKVehicleSpeedValidCount_Cnt_M_u16	18927
CityParkInputConsistentCount_Cnt_M_u16	5335
CityParkInputInvalidCount_Cnt_M_u16	59736

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	1910724352
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1522425344
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	51774
ComputerRazGCTSigInvalidTimer_mS_M_u32	2020834816
ComputerRazGCTSigValidCount_Cnt_M_u16	18012
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	1204
DMDFCTCPKSigValidCount_Cnt_M_u16	29819
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	62529
DMDRELAXECPKSigValidCount_Cnt_M_u16	47520
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	30532
DateInvalidTimer_mS_M_u32	1922866688
DiagMuxOnAbsentTimer_mS_M_u32	569519616
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2940456448
ESPNTCEnableTimer_mS_M_u32	550198784
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	30672
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	2006148864
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	9
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3603664384
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	51594
EtatMTSigValidCount_Cnt_M_u16	36501
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1353
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	21752
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	28657
ISDAT4V2BSI552MsgTimer_mS_M_u32	2297548288
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	47113
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	12253
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	36501
ISDATBSI3F2MsgTimer_mS_M_u32	2627743232
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	15300
ISDATBSI412MsgLenValidCount_Cnt_M_u16	38599
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	51594
ISDATBSI412MsgTimer_mS_M_u32	3588910592
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	62425
ISDATBSI432MsgLenValidCount_Cnt_M_u16	31348
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	45812
ISDATDIRASentFltAcc_Cnt_M_u16	50344
ISDATDIRASentTimer_mS_M_u32	1095462400
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	36751
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	5171
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	57483
ISDYN2CMMMsgTimer_mS_M_u32	2186632704
ISDYNAASChkSumInvalidCount_Cnt_M_u16	1772
ISDYNAASChkSumValidCount_Cnt_M_u16	24044
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	38410
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	48798
ISDYNAASMsgLenValidCount_Cnt_M_u16	21909
ISDYNAASMsgTimeValidCount_Cnt_M_u16	1772
ISDYNAASMsgTimer_mS_M_u32	604454400
ISDYNABRChkSumInvalidCount_Cnt_M_u16	5494
ISDYNABRChkSumValidCount_Cnt_M_u16	18974
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	13123
ISDYNABRMsgCountValidCount_Cnt_M_u16	60803
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	59214
ISDYNABRMsgLenValidCount_Cnt_M_u16	8381
ISDYNABRMsgTimeValidCount_Cnt_M_u16	52833
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	157
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	199

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	36501
ISDYNCMM208MsgTimer_mS_M_u32	1348148736
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	479
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	305
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	52193
ISDYNCMM388MsgTimer_mS_M_u32	3230842368
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	39589
ISDYNVOLChkSumValidCount_Cnt_M_u16	30548
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	51810
ISDYNVOLMsgCountValidCount_Cnt_M_u16	49321
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	27257
ISDYNVOLMsgLenValidCount_Cnt_M_u16	38281
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	9269
ISDYNVOLMsgTimer_mS_M_u32	4107238912
IgnOnTimer_mS_M_u32	3359030784
IgnTimeOff_Sec_M_u32	1340499920
ManVehSpd_Kph_M_f32	275.806091
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	93
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	206
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	603336192
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	175
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2925530624
PrevISDATBSI412MsgDLCError_Cnt_M_u08	240
PrevISDATBSI412MsgRxTime_MSec_M_u32	4268490240
PrevISDATBSI432MsgDLCError_Cnt_M_u08	78
PrevISDATBSI432MsgRxTime_MSec_M_u32	1189043712
PrevISDATDIRAMsgTxTime_MSec_M_u32	2938109440
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	37
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3688975872
PrevISDYNAASMsgDLCError_Cnt_M_u08	125
PrevISDYNAASMsgRxTime_MSec_M_u32	2113764864
PrevISDYNABRMsgDLCError_Cnt_M_u08	7
PrevISDYNABRMsgRxTime_MSec_M_u32	2347679232
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	67
PrevISDYNCMM208MsgRxTime_MSec_M_u32	893550080
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	136
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1142578688
PrevISDYNVOLMsgDLCError_Cnt_M_u08	72
PrevISDYNVOLMsgRxTime_MSec_M_u32	1275657728
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2576903680
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	571.853821
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	10828
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	51139
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	39541
VitesseVehicleBVRampValidCount_Cnt_M_u16	13484
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	50840
VitesseVehicleBVSigValidCount_Cnt_M_u16	5729
VitesseVehicleBV_Kph_M_f32	214.497696

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	52193
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	34744
VitesseVehiculeRoues_Kph_M_f32	378.426208
k_AASNTCEnableTimeout_mS_u16	60592
k_AASNodeAbsentDiag_Cnt_str.Threshold	47636
k_AASNodeAbsentDiag_Cnt_str.PStep	34578
k_AASNodeAbsentDiag_Cnt_str.NStep	62563
k_AASNodeAbsentTimeout_mS_u16	63590
k_AASNodeTimeout_mS_u16	23235
k_ABSNodeTimeout_mS_u16	3641
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	17740
k_ANGLEVOLANTSigValidThresh_Cnt_u16	3111
k_AngleVolantInvalidThresh_Cnt_u16	46022
k_AngleVolantValidThresh_Cnt_u16	59736
k_BSI552MsgTimeout_mS_u16	15383
k_BSINTCEnableTimeout_mS_u16	10129
k_BSINodeAbsentDiag_Cnt_str.Threshold	3692
k_BSINodeAbsentDiag_Cnt_str.PStep	43971
k_BSINodeAbsentDiag_Cnt_str.NStep	2216
k_BSINodeAbsentTimeout_mS_u16	49055
k_BSINodeTimeout_mS_u16	45812
k_BattOvHi_Volt_f32	16.9682007
k_BattOvLo_Volt_f32	26.9526997
k_BattUvHi_Volt_f32	4.32299995
k_BattUvLo_Volt_f32	15.9329996
k_CAVNTCEnableTimeout_mS_u16	6334
k_CAVNodeAbsentDiag_Cnt_str.Threshold	14101
k_CAVNodeAbsentDiag_Cnt_str.PStep	13590
k_CAVNodeAbsentDiag_Cnt_str.NStep	2667
k_CAVNodeAbsentTimeout_mS_u16	25809
k_CAVNodeTimeout_mS_u16	61523
k_CMM388MsgTimeout_mS_u16	59034
k_CMM388NTCEnableTimeout_mS_u16	28662
k_CMMNTCEnableTimeout_mS_u16	34753
k_CMMNodeAbsentDiag_Cnt_str.Threshold	62414
k_CMMNodeAbsentDiag_Cnt_str.PStep	42715
k_CMMNodeAbsentDiag_Cnt_str.NStep	22076
k_CMMNodeAbsentTimeout_mS_u16	1812
k_CONSANGLECPKMax_HwDeg_f32	552.881775
k_CONSANGLECPKMin_HwDeg_f32	-694.657227
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	7905
k_CONSANGLECPKSigValidThresh_Cnt_u16	6840
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	57657
k_CPKVehicleSpeedValidThresh_Cnt_u16	13823
k_CityParkInputInvalidThresh_Cnt_u16	20588
k_CityParkInputValidThresh_Cnt_u16	5335
k_ComputerRazGCTSigValidThresh_Cnt_u16	41439
k_CptTemporelSigValidThresh_Cnt_u16	60979
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	47694
k_DMDFCTCPKSigValidThresh_Cnt_u16	13245
k_DMDFCTCPKValidCount_Cnt_u16	25742
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	57483
k_DMDRELAXECPKSigValidThresh_Cnt_u16	21394
k_DMDRelaxeConsistentThresh_Cnt_u16	33800
k_DateValidThresh_Cnt_u16	28657
k_DefaultVehSpd_Kph_f32	67.1154022
k_DiagMuxOnAbsentTimeout_mS_u16	51015
k_EMNodeTimeout_mS_u16	65188
k_ESPNTCEnableTimeout_mS_u16	55423
k_ESPNodeAbsentDiag_Cnt_str.Threshold	62971
k_ESPNodeAbsentDiag_Cnt_str.PStep	11352
k_ESPNodeAbsentDiag_Cnt_str.NStep	60169
k_ESPNodeAbsentTimeout_mS_u16	56156
k_EtatMTSigInvalidThresh_Cnt_u16	23797
k_EtatMTSigValidThresh_Cnt_u16	33501
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	35668
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	19264
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	5888
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	60278
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	2826
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	61800
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	51398
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	5921

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	893
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	2917
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	58505
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	50274
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	64466
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	59175
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	47591
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	65387
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	26742
k_ISDYNAASChkSumValidThresh_Cnt_u16	56606
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	1603
k_ISDYNAASMsgCountValidThresh_Cnt_u16	131
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	49690
k_ISDYNAASMsgLenValidThresh_Cnt_u16	45927
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	56943
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	54524
k_ISDYNABRChkSumValidThresh_Cnt_u16	38123
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	23110
k_ISDYNABRMsgCountValidThresh_Cnt_u16	2405
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46901
k_ISDYNABRMsgLenValidThresh_Cnt_u16	19152
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	60228
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	8944
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	56109
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	34338
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	8175
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	60366
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	45840
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	48567
k_ISDYNVOLChkSumValidThresh_Cnt_u16	47354
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	15645
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	59842
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	43238
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	31473
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	28631
k_IgnOnTimeout_mS_u16	22547
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	183.301498
k_PowerCutVehSpdLowThresh_Kph_f32	68.6218033
k_PowerCutVehSpdLowTimeout_mS_u16	16892
k_VBattMaxAAS_Volt_f32	23.7287998
k_VBattMaxBSI_Volt_f32	17.5536995
k_VBattMaxCAV_Volt_f32	11.8622999
k_VBattMaxCMM388_Volt_f32	11.6611996
k_VBattMaxCMM_Volt_f32	28.0478001
k_VBattMaxESP_Volt_f32	25.5510998
k_VBattMinAAS_Volt_f32	8.78750038
k_VBattMinBSI_Volt_f32	25.5510998
k_VBattMinCAV_Volt_f32	8.63729954
k_VBattMinCMM388_Volt_f32	12.7182999
k_VBattMinCMM_Volt_f32	28.8894997
k_VBattMinESP_Volt_f32	28.0478001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	15281
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	18980
k_VitesseVehicleBVRampValidThresh_Cnt_u16	7522
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	35412
k_VitesseVehicleBVSigValidThresh_Cnt_u16	2232
k_VitesseVehicleBVSpeedPassThresh_kph_f32	223.719604
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	49443
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	41434
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1922866688
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	58
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	136

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	19.4220009
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	826969600
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	154
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0597340204
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3423649280
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	54
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2511724032
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4130012672
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4117765632
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2609200640
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	71
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4033502720
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4229922304
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	108
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	121
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	203
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	207
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	221
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	83435008
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	68
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	80
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	130
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	147
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1701559808
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	43048448
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4135976448
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	38
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	118
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	242
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1203899904
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3716
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.595987499
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	778019
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	145.304703
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	41046

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	47591	47591	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	14101	14101	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	52833	52833	✔
CONSANGLECPK_HwDeg_M_f32	407.119385	407.119385 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	52833	52833	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1095462400	1095462400	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	18927	18927	✔
CityParkInputConsistentCount_Cnt_M_u16	5335	5335	✔
CityParkInputInvalidCount_Cnt_M_u16	59736	59736	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	62971	62971	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2006148864	2006148864	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	2006148864	2006148864	✔
ElecIntTimer_mS_M_u32[1]	9	9	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11170	11170	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	3359030784	3359030784	✔
IgnTimeOff_Sec_M_u32	1340499920	1340499920	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	53	53	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3423649280	3423649280	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	54	54	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2511724032	2511724032	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	74	74	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4130012672	4130012672	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	121	121	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4117765632	4117765632	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2938109440	2938109440	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	71	71	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4033502720	4033502720	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	246	246	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4229922304	4229922304	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	77	77	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	83435008	83435008	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	172	172	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1701559808	1701559808	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	43048448	43048448	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	105	105	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4135976448	4135976448	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1203899904	1203899904	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	571.853821	571.853821	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	214.497696	214.497696	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	378.426208	378.426208	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	52833	52833	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1340499920	1340499920	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	407.119385	407.119385 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	67.1154022	67.1154022	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.221 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1730246912
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	58885
AASNodeAbsentTimer_mS_M_u32	390572288
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	11272
ANGLEVOLANTSigValidCount_Cnt_M_u16	37418
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	26398
AngleVolantMsgTimer_mS_M_u32	1730246912
AngleVolantValidCount_Cnt_M_u16	60605
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3184814336
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	734062848
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	433821952
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1317755136
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	39171
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3121223936
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	16620
CAVNodeAbsentTimer_mS_M_u32	3364210944
CDD_SrlComVehSpd_Kph_G_f32	449.253601
CMM388NTCEnableTimer_mS_M_u32	3407153408
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2082720000
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	49527
CMMNodeAbsentTimer_mS_M_u32	4285356288
CONSANGLECPKSigInvalidCount_Cnt_M_u16	10737
CONSANGLECPKSigValidCount_Cnt_M_u16	45346
CONSANGLECPK_Cnt_M_u16	27761
CONSANGLECPK_HwDeg_M_f32	-304.167603
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	27761
CPKVehicleSpeedMsgTimer_mS_M_u32	3203692800
CPKVehicleSpeedValidCount_Cnt_M_u16	51377
CityParkInputConsistentCount_Cnt_M_u16	31441

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	37453
CityParkInputMsgTimer_mS_M_u32	3423649280
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	710650112
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	21017
ComputerRazGCTSigInvalidTimer_mS_M_u32	2377926912
ComputerRazGCTSigValidCount_Cnt_M_u16	14914
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	45113
DMDFCTCPKSigValidCount_Cnt_M_u16	2723
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	65042
DMDRELAXECPKSigValidCount_Cnt_M_u16	47028
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	61450
DateInvalidTimer_mS_M_u32	734062848
DiagMuxOnAbsentTimer_mS_M_u32	671103232
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1317755136
ESPNTCEnableTimer_mS_M_u32	1278519552
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	49252
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	201
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	9
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2801015040
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	46711
EtatMTSigValidCount_Cnt_M_u16	8468
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	39419
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	62636
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	28737
ISDAT4V2BSI552MsgTimer_mS_M_u32	4186003712
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	41081
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	4798
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	8468
ISDATBSI3F2MsgTimer_mS_M_u32	4025891072
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	52810
ISDATBSI412MsgLenValidCount_Cnt_M_u16	22272
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	46711
ISDATBSI412MsgTimer_mS_M_u32	1024948480
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	57995
ISDATBSI432MsgLenValidCount_Cnt_M_u16	18552
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	63097
ISDATDIRASentFltAcc_Cnt_M_u16	37213
ISDATDIRASentTimer_mS_M_u32	3203692800
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	24807
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	60605
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	14516
ISDYN2CMMMsgTimer_mS_M_u32	3482757376
ISDYNAASChkSumInvalidCount_Cnt_M_u16	54287
ISDYNAASChkSumValidCount_Cnt_M_u16	22737
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	33592
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	64379
ISDYNAASMsgLenValidCount_Cnt_M_u16	41044
ISDYNAASMsgTimeValidCount_Cnt_M_u16	54287
ISDYNAASMsgTimer_mS_M_u32	2315323648
ISDYNABRChkSumInvalidCount_Cnt_M_u16	42994
ISDYNABRChkSumValidCount_Cnt_M_u16	13244
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	27402
ISDYNABRMsgCountValidCount_Cnt_M_u16	50700
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	18412
ISDYNABRMsgLenValidCount_Cnt_M_u16	58717
ISDYNABRMsgTimeValidCount_Cnt_M_u16	27761
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	157

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	199
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	8468
ISDYNCMM208MsgTimer_mS_M_u32	2894424320
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	479
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	305
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	64947
ISDYNCMM388MsgTimer_mS_M_u32	1113491712
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	18919
ISDYNVOLChkSumValidCount_Cnt_M_u16	64920
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	38703
ISDYNVOLMsgCountValidCount_Cnt_M_u16	24089
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	52329
ISDYNVOLMsgLenValidCount_Cnt_M_u16	5371
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	49527
ISDYNVOLMsgTimer_mS_M_u32	2292730112
IgnOnTimer_mS_M_u32	3144845568
IgnTimeOff_Sec_M_u32	598675785
ManVehSpd_Kph_M_f32	246.412704
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	93
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	121
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	838088960
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	50
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	305568000
PrevISDATBSI412MsgDLCError_Cnt_M_u08	165
PrevISDATBSI412MsgRxTime_MSec_M_u32	2110966016
PrevISDATBSI432MsgDLCError_Cnt_M_u08	255
PrevISDATBSI432MsgRxTime_MSec_M_u32	704162048
PrevISDATDIRAMsgTxTime_MSec_M_u32	1001834752
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	36
PrevISDYN2CMMMsgRxTime_MSec_M_u32	515037440
PrevISDYNAASMsgDLCError_Cnt_M_u08	247
PrevISDYNAASMsgRxTime_MSec_M_u32	622741760
PrevISDYNABRMsgDLCError_Cnt_M_u08	164
PrevISDYNABRMsgRxTime_MSec_M_u32	1347062016
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	145
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1397704960
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	49
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3729238272
PrevISDYNVOLMsgDLCError_Cnt_M_u08	112
PrevISDYNVOLMsgRxTime_MSec_M_u32	1224460544
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	705526016
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	235.739807
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	61553
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	33226
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	33782
VitesseVehicleBVRampValidCount_Cnt_M_u16	7951
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0
VitesseVehicleBVSigValidCount_Cnt_M_u16	45807

Name	Input Value
VitesseVehicleBV_Kph_M_f32	423.287415
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	64947
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	46061
VitesseVehiculeRoues_Kph_M_f32	407.091888
k_AASNTCEnableTimeout_mS_u16	3460
k_AASNodeAbsentDiag_Cnt_str.Threshold	47636
k_AASNodeAbsentDiag_Cnt_str.PStep	34578
k_AASNodeAbsentDiag_Cnt_str.NStep	62563
k_AASNodeAbsentTimeout_mS_u16	52260
k_AASNodeTimeout_mS_u16	51402
k_ABSNodeTimeout_mS_u16	59306
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	31282
k_ANGLEVOLANTSigValidThresh_Cnt_u16	8031
k_AngleVolantInvalidThresh_Cnt_u16	25730
k_AngleVolantValidThresh_Cnt_u16	37453
k_BSI552MsgTimeout_mS_u16	53968
k_BSINTCEnableTimeout_mS_u16	10083
k_BSINodeAbsentDiag_Cnt_str.Threshold	3692
k_BSINodeAbsentDiag_Cnt_str.PStep	43971
k_BSINodeAbsentDiag_Cnt_str.NStep	2216
k_BSINodeAbsentTimeout_mS_u16	13814
k_BSINodeTimeout_mS_u16	63097
k_BattOvHi_Volt_f32	5.21999979
k_BattOvLo_Volt_f32	6.08430004
k_BattUvHi_Volt_f32	26.4610996
k_BattUvLo_Volt_f32	3.02519989
k_CAVNTCEnableTimeout_mS_u16	7195
k_CAVNodeAbsentDiag_Cnt_str.Threshold	14101
k_CAVNodeAbsentDiag_Cnt_str.PStep	13590
k_CAVNodeAbsentDiag_Cnt_str.NStep	2667
k_CAVNodeAbsentTimeout_mS_u16	38114
k_CAVNodeTimeout_mS_u16	32989
k_CMM388MsgTimeout_mS_u16	27909
k_CMM388NTCEnableTimeout_mS_u16	16625
k_CMMNTCEnableTimeout_mS_u16	4433
k_CMMNodeAbsentDiag_Cnt_str.Threshold	62414
k_CMMNodeAbsentDiag_Cnt_str.PStep	42715
k_CMMNodeAbsentDiag_Cnt_str.NStep	22076
k_CMMNodeAbsentTimeout_mS_u16	42457
k_CONSANGLECPKMax_HwDeg_f32	186.585907
k_CONSANGLECPKMin_HwDeg_f32	-332.552185
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	1203
k_CONSANGLECPKSigValidThresh_Cnt_u16	64237
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	36200
k_CPKVehicleSpeedValidThresh_Cnt_u16	35737
k_CityParkInputInvalidThresh_Cnt_u16	20240
k_CityParkInputValidThresh_Cnt_u16	31441
k_ComputerRazGCTSigValidThresh_Cnt_u16	47863
k_CptTemporelSigValidThresh_Cnt_u16	44988
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	52972
k_DMDFCTCPKSigValidThresh_Cnt_u16	44125
k_DMDFCTCPKValidCount_Cnt_u16	8491
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	14516
k_DMDRELAXECPKSigValidThresh_Cnt_u16	35166
k_DMDRelaxeConsistentThresh_Cnt_u16	20476
k_DateValidThresh_Cnt_u16	28737
k_DefaultVehSpd_Kph_f32	41.9925995
k_DiagMuxOnAbsentTimeout_mS_u16	39359
k_EMNodeTimeout_mS_u16	55786
k_ESPNTCEnableTimeout_mS_u16	29144
k_ESPNodeAbsentDiag_Cnt_str.Threshold	62971
k_ESPNodeAbsentDiag_Cnt_str.PStep	11352
k_ESPNodeAbsentDiag_Cnt_str.NStep	60169
k_ESPNodeAbsentTimeout_mS_u16	18689
k_EtatMTSigInvalidThresh_Cnt_u16	36213
k_EtatMTSigValidThresh_Cnt_u16	17791
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	47895
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	46357
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	22614
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	64050
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	30007
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	15710
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	22468

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	26225
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	17311
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	50533
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	21435
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	32111
k_ISDATDIRASentDiag_Cnt_str.Threshold	1170
k_ISDATDIRASentDiag_Cnt_str.PStep	4955
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	25822
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	26912
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	26398
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	44308
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	44786
k_ISDYNAASChkSumValidThresh_Cnt_u16	31420
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	61962
k_ISDYNAASMsgCountValidThresh_Cnt_u16	36108
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	12806
k_ISDYNAASMsgLenValidThresh_Cnt_u16	20190
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	51335
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	46818
k_ISDYNABRChkSumValidThresh_Cnt_u16	49363
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	8195
k_ISDYNABRMsgCountValidThresh_Cnt_u16	7269
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	2167
k_ISDYNABRMsgLenValidThresh_Cnt_u16	18276
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	45768
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	38533
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	54287
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	33453
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	45832
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	22826
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	5413
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	54385
k_ISDYNVOLChkSumValidThresh_Cnt_u16	31847
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	58493
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	58576
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	34915
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	52224
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	34959
k_IgnOnTimeout_mS_u16	30045
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	147.934494
k_PowerCutVehSpdLowThresh_Kph_f32	179.973495
k_PowerCutVehSpdLowTimeout_mS_u16	15776
k_VBattMaxAAS_Volt_f32	25.4078999
k_VBattMaxBSI_Volt_f32	32
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	1.44400001
k_VBattMaxCMM_Volt_f32	31.6580009
k_VBattMaxESP_Volt_f32	2.37759995
k_VBattMinAAS_Volt_f32	1.36370003
k_VBattMinBSI_Volt_f32	2.37759995
k_VBattMinCAV_Volt_f32	24.8563995
k_VBattMinCMM388_Volt_f32	9.84189987
k_VBattMinCMM_Volt_f32	18.0149002
k_VBattMinESP_Volt_f32	31.6580009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	4994
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	16872
k_VitesseVehicleBVRampValidThresh_Cnt_u16	40495
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	50328
k_VitesseVehicleBVSigValidThresh_Cnt_u16	25390
k_VitesseVehicleBVSpeedPassThresh_kph_f32	496.251892
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	18412
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	3973
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	734062848
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	58
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	49
target_SrlComInput_Per1_Batt_Volt_f32.value	19.5263004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1400314112
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	127
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.220909297
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	213
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2548336896
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3077908736
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1385548032
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1363568896
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2609318144
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	425175296
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	124
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2998421760
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	43
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	69
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	76
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	185
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2259380480
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	109
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	172
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	155
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4157835520
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	25
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2632198400
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2105854208
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	90
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	121
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	138
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1309710592
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1670
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.884758174
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	544505
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	205.174896

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	13907		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	3692	3692	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	14101	14101	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	246.412704	246.412704	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	27761	27761	✔
CONSANGLECPK_HwDeg_M_f32	-304.167603	-304.167603 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2006148864	2006148864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	201	201	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	8	8	✔
ElecIntTimer_mS_M_u32[1]	9	9	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	28737	28737	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	8468	8468	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	46711	46711	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	63097	63097	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1170	1170	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	14516	14516	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	54287	54287	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	27761	27761	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	8468	8468	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	64947	64947	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	49527	49527	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	3144845568	3144845568	✔
IgnTimeOff_Sec_M_u32	598675785	598675785	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	213	213	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2548336896	2548336896	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	174	174	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3077908736	3077908736	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	143	143	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1385548032	1385548032	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1363568896	1363568896	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1001834752	1001834752	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	425175296	425175296	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	124	124	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2998421760	2998421760	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	70	70	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2259380480	2259380480	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	155	155	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4157835520	4157835520	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	25	25	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2632198400	2632198400	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	95	95	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2105854208	2105854208	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1309710592	1309710592	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	235.739807	235.739807	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	423.287415	423.287415	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	407.091888	407.091888	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	27761	27761	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	598675785	598675785	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-304.167603	-304.167603 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	246.412704	246.412704	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.222 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	123623424
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	48304
AASNodeAbsentTimer_mS_M_u32	2343290880
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	5289
ANGLEVOLANTSigValidCount_Cnt_M_u16	50436
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	56677
AngleVolantMsgTimer_mS_M_u32	123623424
AngleVolantValidCount_Cnt_M_u16	36617
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3137701888
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3275753472
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	4289722368
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3500193792
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	31160
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	4179916800
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	27774
CAVNodeAbsentTimer_mS_M_u32	2557569024
CDD_SrlComVehSpd_Kph_G_f32	221.329498
CMM388NTCEnableTimer_mS_M_u32	3720587264
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1972856832
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	669
CMMNodeAbsentTimer_mS_M_u32	3321542656
CONSANGLECPKSigInvalidCount_Cnt_M_u16	44527
CONSANGLECPKSigValidCount_Cnt_M_u16	15130
CONSANGLECPK_Cnt_M_u16	1325
CONSANGLECPK_HwDeg_M_f32	-554.966614
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	1325
CPKVehicleSpeedMsgTimer_mS_M_u32	199579648
CPKVehicleSpeedValidCount_Cnt_M_u16	9143
CityParkInputConsistentCount_Cnt_M_u16	13517
CityParkInputInvalidCount_Cnt_M_u16	12121
CityParkInputMsgTimer_mS_M_u32	2548336896
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2725234688
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	51316

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1120790528
ComputerRazGCTSigValidCount_Cnt_M_u16	64122
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	34197
DMDFCTCPKSigValidCount_Cnt_M_u16	31000
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	18059
DMDRELAXECPKSigValidCount_Cnt_M_u16	64614
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	65444
DateInvalidTimer_mS_M_u32	3275753472
DiagMuxOnAbsentTimer_mS_M_u32	2948732928
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3500193792
ESPNTCEnableTimer_mS_M_u32	3773089792
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	6292
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	66
EffacDefaultDiagTimer_mS_M_u32[1]	78
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	16
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1516664832
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	29852
EtatMTSigValidCount_Cnt_M_u16	1923
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1489
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	6268
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	16446
ISDAT4V2BSI552MsgTimer_mS_M_u32	666810368
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	38423
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	45574
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	1923
ISDATBSI3F2MsgTimer_mS_M_u32	2950699008
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	57763
ISDATBSI412MsgLenValidCount_Cnt_M_u16	31298
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	29852
ISDATBSI412MsgTimer_mS_M_u32	3715913728
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	61281
ISDATBSI432MsgLenValidCount_Cnt_M_u16	53336
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	49111
ISDATDIRASentFltAcc_Cnt_M_u16	32555
ISDATDIRASentTimer_mS_M_u32	199579648
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	32715
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	36617
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	38948
ISDYN2CMMMsgTimer_mS_M_u32	1589561344
ISDYNAASChkSumInvalidCount_Cnt_M_u16	39570
ISDYNAASChkSumValidCount_Cnt_M_u16	28429
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	30616
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	14545
ISDYNAASMsgLenValidCount_Cnt_M_u16	3332
ISDYNAASMsgTimeValidCount_Cnt_M_u16	39570
ISDYNAASMsgTimer_mS_M_u32	1358931968
ISDYNABRChkSumInvalidCount_Cnt_M_u16	8299
ISDYNABRChkSumValidCount_Cnt_M_u16	65486
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	33185
ISDYNABRMsgCountValidCount_Cnt_M_u16	54108
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	65534
ISDYNABRMsgLenValidCount_Cnt_M_u16	19049
ISDYNABRMsgTimeValidCount_Cnt_M_u16	1325
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	141
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	167
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	1923
ISDYNCMM208MsgTimer_mS_M_u32	4075980800
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	415
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	273
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	46119

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2112301056
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	42509
ISDYNVOLChkSumValidCount_Cnt_M_u16	44472
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	10419
ISDYNVOLMsgCountValidCount_Cnt_M_u16	54966
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	18565
ISDYNVOLMsgLenValidCount_Cnt_M_u16	4496
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	669
ISDYNVOLMsgTimer_mS_M_u32	34203648
IgnOnTimer_mS_M_u32	1655384064
IgnTimeOff_Sec_M_u32	2872943912
ManVehSpd_Kph_M_f32	513.860718
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	77
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	181
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1642469376
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	122
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1117714432
PrevISDATBSI412MsgDLCError_Cnt_M_u08	129
PrevISDATBSI412MsgRxTime_MSec_M_u32	3968493568
PrevISDATBSI432MsgDLCError_Cnt_M_u08	16
PrevISDATBSI432MsgRxTime_MSec_M_u32	1469630464
PrevISDATDIRAMsgTxTime_MSec_M_u32	1121871872
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	164
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1579825152
PrevISDYNAASMsgDLCError_Cnt_M_u08	156
PrevISDYNAASMsgRxTime_MSec_M_u32	2225596416
PrevISDYNABRMsgDLCError_Cnt_M_u08	174
PrevISDYNABRMsgRxTime_MSec_M_u32	69412864
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	7
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4262782976
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	219
PrevISDYNCMM388MsgRxTime_MSec_M_u32	917227520
PrevISDYNVOLMsgDLCError_Cnt_M_u08	157
PrevISDYNVOLMsgRxTime_MSec_M_u32	1863280640
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1855608832
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	538.828613
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	45551
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	49314
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	19296
VitesseVehicleBVRampValidCount_Cnt_M_u16	15571
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	65535
VitesseVehicleBVSigValidCount_Cnt_M_u16	46773
VitesseVehicleBV_Kph_M_f32	4.38810015
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	46119
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	54330
VitesseVehiculeRoues_Kph_M_f32	595.224121
k_AASNTCEnableTimeout_mS_u16	11764
k_AASNodeAbsentDiag_Cnt_str.Threshold	4467

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	60116
k_AASNodeAbsentDiag_Cnt_str.NStep	906
k_AASNodeAbsentTimeout_mS_u16	19668
k_AASNodeTimeout_mS_u16	60322
k_ABSNodeTimeout_mS_u16	58178
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	33900
k_ANGLEVOLANTSigValidThresh_Cnt_u16	42915
k_AngleVolantInvalidThresh_Cnt_u16	9274
k_AngleVolantValidThresh_Cnt_u16	12121
k_BSI552MsgTimeout_mS_u16	50065
k_BSINTCEnableTimeout_mS_u16	32985
k_BSINodeAbsentDiag_Cnt_str.Threshold	3052
k_BSINodeAbsentDiag_Cnt_str.PStep	44243
k_BSINodeAbsentDiag_Cnt_str.NStep	1848
k_BSINodeAbsentTimeout_mS_u16	53469
k_BSINodeTimeout_mS_u16	49111
k_BattOvHi_Volt_f32	5.03480005
k_BattOvLo_Volt_f32	7.48820019
k_BattUvHi_Volt_f32	23.8943996
k_BattUvLo_Volt_f32	27.5198994
k_CAVNTCEnableTimeout_mS_u16	18927
k_CAVNodeAbsentDiag_Cnt_str.Threshold	41800
k_CAVNodeAbsentDiag_Cnt_str.PStep	20653
k_CAVNodeAbsentDiag_Cnt_str.NStep	46182
k_CAVNodeAbsentTimeout_mS_u16	51356
k_CAVNodeTimeout_mS_u16	22827
k_CMM388MsgTimeout_mS_u16	10160
k_CMM388NTCEnableTimeout_mS_u16	23532
k_CMMNTCEnableTimeout_mS_u16	41871
k_CMMNodeAbsentDiag_Cnt_str.Threshold	10365
k_CMMNodeAbsentDiag_Cnt_str.PStep	62446
k_CMMNodeAbsentDiag_Cnt_str.NStep	23219
k_CMMNodeAbsentTimeout_mS_u16	44662
k_CONSANGLECPKMax_HwDeg_f32	10.0085001
k_CONSANGLECPKMin_HwDeg_f32	-470.312592
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	40743
k_CONSANGLECPKSigValidThresh_Cnt_u16	65338
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	38344
k_CPKVehicleSpeedValidThresh_Cnt_u16	42422
k_CityParkInputInvalidThresh_Cnt_u16	8977
k_CityParkInputValidThresh_Cnt_u16	13517
k_ComputerRazGCTSigValidThresh_Cnt_u16	48797
k_CptTemporelSigValidThresh_Cnt_u16	21260
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	27390
k_DMDFCTCPKSigValidThresh_Cnt_u16	62825
k_DMDFCTCPKValidCount_Cnt_u16	33088
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	38948
k_DMDRELAXECPKSigValidThresh_Cnt_u16	43239
k_DMDRelaxeConsistentThresh_Cnt_u16	19725
k_DateValidThresh_Cnt_u16	16446
k_DefaultVehSpd_Kph_f32	121.283096
k_DiagMuxOnAbsentTimeout_mS_u16	13635
k_EMNodeTimeout_mS_u16	49668
k_ESPNTCEnableTimeout_mS_u16	35258
k_ESPNodeAbsentDiag_Cnt_str.Threshold	17978
k_ESPNodeAbsentDiag_Cnt_str.PStep	37115
k_ESPNodeAbsentDiag_Cnt_str.NStep	784
k_ESPNodeAbsentTimeout_mS_u16	25854
k_EtatMTSigInvalidThresh_Cnt_u16	15330
k_EtatMTSigValidThresh_Cnt_u16	38533
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	35003
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	60802
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	61502
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	44268
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	44699
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	58471
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	46006
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	39533
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	7205
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	51793
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	53775
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	63795
k_ISDATDIRASentDiag_Cnt_str.Threshold	6549

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	63930
k_ISDATDIRASentDiag_Cnt_str.NStep	24627
k_ISDATDIRASentTimeout_mS_u16	39335
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	14880
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	56677
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	51206
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	2923
k_ISDYNAASChkSumValidThresh_Cnt_u16	10958
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	60577
k_ISDYNAASMsgCountValidThresh_Cnt_u16	32348
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	53807
k_ISDYNAASMsgLenValidThresh_Cnt_u16	43366
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	19499
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	2844
k_ISDYNABRChkSumValidThresh_Cnt_u16	4103
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	58552
k_ISDYNABRMsgCountValidThresh_Cnt_u16	53843
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	11677
k_ISDYNABRMsgLenValidThresh_Cnt_u16	33684
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	23338
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	4019
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	9300
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	2553
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	32681
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	28676
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	1745
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	11054
k_ISDYNVOLChkSumValidThresh_Cnt_u16	26125
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	20553
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	15506
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	44760
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	46783
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	44884
k_IgnOnTimeout_mS_u16	63594
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	231.957397
k_PowerCutVehSpdLowThresh_Kph_f32	47.8401985
k_PowerCutVehSpdLowTimeout_mS_u16	3488
k_VBattMaxAAS_Volt_f32	23.9699993
k_VBattMaxBSI_Volt_f32	1.523
k_VBattMaxCAV_Volt_f32	22.2938004
k_VBattMaxCMM388_Volt_f32	12.3627996
k_VBattMaxCMM_Volt_f32	13.5986996
k_VBattMaxESP_Volt_f32	13.7514
k_VBattMinAAS_Volt_f32	5.70709991
k_VBattMinBSI_Volt_f32	13.7514
k_VBattMinCAV_Volt_f32	31.1032009
k_VBattMinCMM388_Volt_f32	18.4610996
k_VBattMinCMM_Volt_f32	21.8824005
k_VBattMinESP_Volt_f32	13.5986996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	17146
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	43657
k_VitesseVehicleBVRampValidThresh_Cnt_u16	5043
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	22712
k_VitesseVehicleBVSigValidThresh_Cnt_u16	12214
k_VitesseVehicleBVSpeedPassThresh_kph_f32	139.943604
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	22398
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	50033
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3275753472
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	186
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65036
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	163190528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	219
target_SrlComInput_Per1_Batt_Volt_f32.value	22.2036991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	551385088
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	105
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.74167484
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	237
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	357902336
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1092831232
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	977364992
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	82
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1219463168
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3027085312
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	187
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3313223680
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	58
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3285837824
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	78
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	136
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	145
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	163
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	177
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	112
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2088798208
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	76
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1904748544
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	10
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	215369728
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	226
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	896821248
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	104
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	114
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	132
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	145
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1997600768
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3312
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.897710145
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	384114
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	230.485992
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	59465

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	163190528	163190528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	4467	4467	✔
AASNodeAbsentTimer_mS_M_u32	163190528	163190528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	163190528	163190528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	163190528	163190528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CDD_SrlComVehSpd_Kph_G_f32	513.860718	513.860718	✔
CMM388NTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	10365	10365	✔
CMMNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	1325	1325	✔
CONSANGLECPK_HwDeg_M_f32	-554.966614	-554.966614 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	163190528	163190528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	163190528	163190528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	163190528	163190528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	163190528	163190528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	163190528	163190528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	163190528	163190528	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	163190528	163190528	✔
ESPNTCEnableTimer_mS_M_u32	163190528	163190528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	17978	17978	✔
ESPNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	66	66	✔
EffacDefaultDiagTimer_mS_M_u32[1]	78	78	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	6	6	✔
ElecIntTimer_mS_M_u32[1]	16	16	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	163190528	163190528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	16446	16446	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	1923	1923	✔
ISDATBSI3F2MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	29852	29852	✔
ISDATBSI412MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	49111	49111	✔
ISDATBSI432MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	163190528	163190528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	38948	38948	✔
ISDYN2CMMMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	39570	39570	✔
ISDYNAASMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	1325	1325	✔
ISDYNABRMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	1923	1923	✔
ISDYNCMM208MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	46119	46119	✔
ISDYNCMM388MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	669	669	✔
ISDYNVOLMsgTimer_mS_M_u32	163190528	163190528	✔
IgnOnTimer_mS_M_u32	1655384064	1655384064	✔
IgnTimeOff_Sec_M_u32	2872943912	2872943912	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	237	237	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	357902336	357902336	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	206	206	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1092831232	1092831232	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	215	215	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	977364992	977364992	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	82	82	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1219463168	1219463168	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1121871872	1121871872	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	187	187	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3313223680	3313223680	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	58	58	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3285837824	3285837824	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	112	112	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2088798208	2088798208	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	26	26	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1904748544	1904748544	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	10	10	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	215369728	215369728	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	226	226	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	896821248	896821248	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1997600768	1997600768	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	538.828613	538.828613	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	4.38810015	4.38810015	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	595.224121	595.224121	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	1325	1325	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2872943912	2872943912	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-554.966614	-554.966614 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	513.860718	513.860718	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.223 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3034823424
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	65260
AASNodeAbsentTimer_mS_M_u32	1773890304
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	30978
ANGLEVOLANTSigValidCount_Cnt_M_u16	49073
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	45261
AngleVolantMsgTimer_mS_M_u32	3034823424
AngleVolantValidCount_Cnt_M_u16	54368
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1924016896
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1677634304
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2590956288
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3667696384
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	17877
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	538008320
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	44547
CAVNodeAbsentTimer_mS_M_u32	3790244608
CDD_SrlComVehSpd_Kph_G_f32	210.905304
CMM388NTCEnableTimer_mS_M_u32	720620288
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1652067072
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	42085
CMMNodeAbsentTimer_mS_M_u32	3800996608
CONSANGLECPKSigInvalidCount_Cnt_M_u16	62513
CONSANGLECPKSigValidCount_Cnt_M_u16	58480
CONSANGLECPK_Cnt_M_u16	37431
CONSANGLECPK_HwDeg_M_f32	619.597717
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37431
CPKVehicleSpeedMsgTimer_mS_M_u32	2202974976
CPKVehicleSpeedValidCount_Cnt_M_u16	48320
CityParkInputConsistentCount_Cnt_M_u16	62228
CityParkInputInvalidCount_Cnt_M_u16	16499
CityParkInputMsgTimer_mS_M_u32	357902336
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	896494336
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	60320

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	4107602688
ComputerRazGCTSigValidCount_Cnt_M_u16	38413
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	11711
DMDFCTCPKSigValidCount_Cnt_M_u16	19190
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	60252
DMDRELAXECPKSigValidCount_Cnt_M_u16	8587
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	4882
DateInvalidTimer_mS_M_u32	1677634304
DiagMuxOnAbsentTimer_mS_M_u32	4206394112
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3667696384
ESPNTCEnableTimer_mS_M_u32	2383440640
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	10816
EffacDefaultDiagCount_Cnt_M_u08	1
EffacDefaultDiagTimer_mS_M_u32[0]	2050
EffacDefaultDiagTimer_mS_M_u32[1]	2717483008
ElecIntCount_Cnt_M_u08	2
ElecIntTimer_mS_M_u32[0]	56
ElecIntTimer_mS_M_u32[1]	457
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2219531008
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	23400
EtatMTSigValidCount_Cnt_M_u16	10867
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	62603
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	21578
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	3460
ISDAT4V2BSI552MsgTimer_mS_M_u32	3443694336
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	22648
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	44140
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	10867
ISDATBSI3F2MsgTimer_mS_M_u32	4066278144
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	63188
ISDATBSI412MsgLenValidCount_Cnt_M_u16	38071
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	23400
ISDATBSI412MsgTimer_mS_M_u32	713669376
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	60953
ISDATBSI432MsgLenValidCount_Cnt_M_u16	4852
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	22520
ISDATDIRASentFltAcc_Cnt_M_u16	27132
ISDATDIRASentTimer_mS_M_u32	2202974976
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	6749
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	54368
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	61970
ISDYN2CMMMsgTimer_mS_M_u32	4236405504
ISDYNAASChkSumInvalidCount_Cnt_M_u16	27974
ISDYNAASChkSumValidCount_Cnt_M_u16	51093
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	5811
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	21770
ISDYNAASMsgLenValidCount_Cnt_M_u16	36913
ISDYNAASMsgTimeValidCount_Cnt_M_u16	27974
ISDYNAASMsgTimer_mS_M_u32	3242183424
ISDYNABRChkSumInvalidCount_Cnt_M_u16	55099
ISDYNABRChkSumValidCount_Cnt_M_u16	45266
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	46105
ISDYNABRMsgCountValidCount_Cnt_M_u16	38568
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	64004
ISDYNABRMsgLenValidCount_Cnt_M_u16	45699
ISDYNABRMsgTimeValidCount_Cnt_M_u16	37431
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	703
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1291
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	10867
ISDYNCMM208MsgTimer_mS_M_u32	3202820864
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2663
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1397
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	23814

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	948521728
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	983
ISDYNVOLChkSumValidCount_Cnt_M_u16	33942
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	15461
ISDYNVOLMsgCountValidCount_Cnt_M_u16	10780
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	40557
ISDYNVOLMsgLenValidCount_Cnt_M_u16	23309
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	42085
ISDYNVOLMsgTimer_mS_M_u32	2803960576
IgnOnTimer_mS_M_u32	2587708160
IgnTimeOff_Sec_M_u32	1278669360
ManVehSpd_Kph_M_f32	281.287292
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	227
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	252
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1951169280
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	222
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1302452992
PrevISDATBSI412MsgDLCError_Cnt_M_u08	171
PrevISDATBSI412MsgRxTime_MSec_M_u32	2308934400
PrevISDATBSI432MsgDLCError_Cnt_M_u08	32
PrevISDATBSI432MsgRxTime_MSec_M_u32	4193544960
PrevISDATDIRAMsgTxTime_MSec_M_u32	3601042176
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	94
PrevISDYN2CMMMsgRxTime_MSec_M_u32	939531008
PrevISDYNAASMsgDLCError_Cnt_M_u08	32
PrevISDYNAASMsgRxTime_MSec_M_u32	390531840
PrevISDYNABRMsgDLCError_Cnt_M_u08	158
PrevISDYNABRMsgRxTime_MSec_M_u32	2513783552
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	51
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2667580160
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	164
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1757113088
PrevISDYNVOLMsgDLCError_Cnt_M_u08	213
PrevISDYNVOLMsgRxTime_MSec_M_u32	1443924736
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1865399040
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	227.535202
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57776
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	27991
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	6493
VitesseVehicleBVRampValidCount_Cnt_M_u16	64708
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	41501
VitesseVehicleBVSigValidCount_Cnt_M_u16	61086
VitesseVehicleBV_Kph_M_f32	433.570313
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	23814
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	13454
VitesseVehiculeRoues_Kph_M_f32	316.013489
k_AASNTCEnableTimeout_mS_u16	62434
k_AASNodeAbsentDiag_Cnt_str.Threshold	8025

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	40741
k_AASNodeAbsentDiag_Cnt_str.NStep	23056
k_AASNodeAbsentTimeout_mS_u16	34559
k_AASNodeTimeout_mS_u16	60503
k_ABSNodeTimeout_mS_u16	2232
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	6904
k_ANGLEVOLANTSigValidThresh_Cnt_u16	30995
k_AngleVolantInvalidThresh_Cnt_u16	8014
k_AngleVolantValidThresh_Cnt_u16	16499
k_BSI552MsgTimeout_mS_u16	33417
k_BSINTCEnableTimeout_mS_u16	6577
k_BSINodeAbsentDiag_Cnt_str.Threshold	25532
k_BSINodeAbsentDiag_Cnt_str.PStep	34689
k_BSINodeAbsentDiag_Cnt_str.NStep	14774
k_BSINodeAbsentTimeout_mS_u16	46693
k_BSINodeTimeout_mS_u16	22520
k_BattOvHi_Volt_f32	4.22359991
k_BattOvLo_Volt_f32	14.2243004
k_BattUvHi_Volt_f32	24.8959007
k_BattUvLo_Volt_f32	19.0655994
k_CAVNTCEnableTimeout_mS_u16	51377
k_CAVNodeAbsentDiag_Cnt_str.Threshold	43612
k_CAVNodeAbsentDiag_Cnt_str.PStep	33532
k_CAVNodeAbsentDiag_Cnt_str.NStep	50919
k_CAVNodeAbsentTimeout_mS_u16	37289
k_CAVNodeTimeout_mS_u16	57981
k_CMM388MsgTimeout_mS_u16	48620
k_CMM388NTCEnableTimeout_mS_u16	4408
k_CMMNTCEnableTimeout_mS_u16	4112
k_CMMNodeAbsentDiag_Cnt_str.Threshold	62640
k_CMMNodeAbsentDiag_Cnt_str.PStep	29375
k_CMMNodeAbsentDiag_Cnt_str.NStep	51731
k_CMMNodeAbsentTimeout_mS_u16	38362
k_CONSANGLECPKMax_HwDeg_f32	217.072998
k_CONSANGLECPKMin_HwDeg_f32	-22.7577
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	39942
k_CONSANGLECPKSigValidThresh_Cnt_u16	45966
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	1509
k_CPKVehicleSpeedValidThresh_Cnt_u16	46747
k_CityParkInputInvalidThresh_Cnt_u16	59209
k_CityParkInputValidThresh_Cnt_u16	62228
k_ComputerRazGCTSigValidThresh_Cnt_u16	30438
k_CptTemporelSigValidThresh_Cnt_u16	24922
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	47364
k_DMDFCTCPKSigValidThresh_Cnt_u16	45443
k_DMDFCTCPKValidCount_Cnt_u16	20285
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	61970
k_DMDRELAXECPKSigValidThresh_Cnt_u16	46985
k_DMDRelaxeConsistentThresh_Cnt_u16	58135
k_DateValidThresh_Cnt_u16	3460
k_DefaultVehSpd_Kph_f32	47.6459007
k_DiagMuxOnAbsentTimeout_mS_u16	55797
k_EMNodeTimeout_mS_u16	19442
k_ESPNTCEnableTimeout_mS_u16	17999
k_ESPNodeAbsentDiag_Cnt_str.Threshold	40036
k_ESPNodeAbsentDiag_Cnt_str.PStep	46639
k_ESPNodeAbsentDiag_Cnt_str.NStep	47261
k_ESPNodeAbsentTimeout_mS_u16	37442
k_EtatMTSigInvalidThresh_Cnt_u16	8406
k_EtatMTSigValidThresh_Cnt_u16	34989
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	47372
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	37495
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	50369
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	43001
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	19117
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	65160
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	13594
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	18613
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	30669
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	53963
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	41806
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	16675
k_ISDATDIRASentDiag_Cnt_str.Threshold	25239

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	16638
k_ISDATDIRASentDiag_Cnt_str.NStep	16248
k_ISDATDIRASentTimeout_mS_u16	23431
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	29276
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	45261
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	47979
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	5691
k_ISDYNAASChkSumValidThresh_Cnt_u16	12242
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	29465
k_ISDYNAASMsgCountValidThresh_Cnt_u16	38312
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	53743
k_ISDYNAASMsgLenValidThresh_Cnt_u16	49931
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	43899
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	53418
k_ISDYNABRChkSumValidThresh_Cnt_u16	22953
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	1237
k_ISDYNABRMsgCountValidThresh_Cnt_u16	37828
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	9061
k_ISDYNABRMsgLenValidThresh_Cnt_u16	59712
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	5439
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	55396
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	12993
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	44370
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	14338
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	48817
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	39435
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	1587
k_ISDYNVOLChkSumValidThresh_Cnt_u16	48470
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	38689
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	2694
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	40116
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	3263
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	38978
k_IgnOnTimeout_mS_u16	36479
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	222.123001
k_PowerCutVehSpdLowThresh_Kph_f32	14.4744997
k_PowerCutVehSpdLowTimeout_mS_u16	1246
k_VBattMaxAAS_Volt_f32	7.17339993
k_VBattMaxBSI_Volt_f32	8.3210001
k_VBattMaxCAV_Volt_f32	19.5174007
k_VBattMaxCMM388_Volt_f32	28.4920006
k_VBattMaxCMM_Volt_f32	13.1505003
k_VBattMaxESP_Volt_f32	11.7579002
k_VBattMinAAS_Volt_f32	3.1487
k_VBattMinBSI_Volt_f32	11.7579002
k_VBattMinCAV_Volt_f32	2.33820009
k_VBattMinCMM388_Volt_f32	15.3210001
k_VBattMinCMM_Volt_f32	20.2359009
k_VBattMinESP_Volt_f32	13.1505003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	16334
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	12513
k_VitesseVehicleBVRampValidThresh_Cnt_u16	31589
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	33686
k_VitesseVehicleBVSigValidThresh_Cnt_u16	58969
k_VitesseVehicleBVSpeedPassThresh_kph_f32	276.235992
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	60675
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	24810
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1677634304
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	224
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	15965
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2717483008
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	164
target_SrlComInput_Per1_Batt_Volt_f32.value	27.2007008
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3437648640
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	137
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.620151639
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2856274688
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2270489344
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1014663936
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4054854400
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3472214784
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	65
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4232801024
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	197
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2712734464
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	129
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	141
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	149
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	201
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	218
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3661441792
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	47
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	82
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	158
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	232
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	564546304
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	96
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2956716800
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	214
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3605105408
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	118
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	166
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	186
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	187
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4165720832
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	4058
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.849385023
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	548716
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	227.787292
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	9890

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	8025	8025	✔
AASNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2717483008	2717483008	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	25532	25532	✔
BSINodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	37431	37431	✔
CONSANGLECPK_HwDeg_M_f32	619.597717	619.597717 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2717483008	2717483008	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2717483008	2717483008	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2717483008	2717483008	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2717483008	2717483008	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2717483008	2717483008	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2717483008	2717483008	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2717483008	2717483008	✔
ESPNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	40036	40036	✔
ESPNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
EffacDefaultDiagCount_Cnt_M_u08	2	2	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2050	2050	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2717483008	2717483008	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2717483008	2717483008	✔
ElecIntTimer_mS_M_u32[1]	457	457	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2717483008	2717483008	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2717483008	2717483008	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2717483008	2717483008	✔
IgnOnTimer_mS_M_u32	2717483008	2717483008	✔
IgnTimeOff_Sec_M_u32	1278669360	1278669360	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	104	104	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2856274688	2856274688	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	136	136	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2270489344	2270489344	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	108	108	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1014663936	1014663936	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	60	60	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4054854400	4054854400	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3601042176	3601042176	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	65	65	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4232801024	4232801024	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	197	197	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2712734464	2712734464	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3661441792	3661441792	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	110	110	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	564546304	564546304	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	96	96	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2956716800	2956716800	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	214	214	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3605105408	3605105408	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4165720832	4165720832	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	227.535202	227.535202	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	433.570313	433.570313	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	316.013489	316.013489	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	37431	37431	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1278669360	1278669360	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	619.597717	619.597717 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	47.6459007	47.6459007	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.224 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4053766656
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	54662
AASNodeAbsentTimer_mS_M_u32	232292864
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	57666
ANGLEVOLANTSigValidCount_Cnt_M_u16	1525
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	33763
AngleVolantMsgTimer_mS_M_u32	4053766656
AngleVolantValidCount_Cnt_M_u16	28584
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	771768832
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1007600128
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3581817344
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4227133952
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	34505
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4002853376
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	36032
CAVNodeAbsentTimer_mS_M_u32	3385532928
CDD_SrlComVehSpd_Kph_G_f32	314.726288
CMM388NTCEnableTimer_mS_M_u32	2746180096
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2171392
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	32601
CMMNodeAbsentTimer_mS_M_u32	740225536
CONSANGLECPKSigInvalidCount_Cnt_M_u16	39606
CONSANGLECPKSigValidCount_Cnt_M_u16	696
CONSANGLECPK_Cnt_M_u16	54627
CONSANGLECPK_HwDeg_M_f32	414.840088
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	54627
CPKVehicleSpeedMsgTimer_mS_M_u32	4066284032
CPKVehicleSpeedValidCount_Cnt_M_u16	25425
CityParkInputConsistentCount_Cnt_M_u16	58252
CityParkInputInvalidCount_Cnt_M_u16	17521

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	2856274688
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2059174400
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	57194
ComputerRazGCTSigInvalidTimer_mS_M_u32	1527489024
ComputerRazGCTSigValidCount_Cnt_M_u16	7841
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	44173
DMDFCTCPKSigValidCount_Cnt_M_u16	28071
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	29236
DMDRELAXECPKSigValidCount_Cnt_M_u16	51303
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	531
DateInvalidTimer_mS_M_u32	1007600128
DiagMuxOnAbsentTimer_mS_M_u32	1663128064
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4227133952
ESPNTCEnableTimer_mS_M_u32	886669824
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	38535
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	20
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	17
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	703115776
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	13138
EtatMTSigValidCount_Cnt_M_u16	12017
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	33192
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	39722
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	56829
ISDAT4V2BSI552MsgTimer_mS_M_u32	1006825984
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	6048
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	9350
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	12017
ISDATBSI3F2MsgTimer_mS_M_u32	2486129152
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	47502
ISDATBSI412MsgLenValidCount_Cnt_M_u16	43172
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	13138
ISDATBSI412MsgTimer_mS_M_u32	2829947392
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	29245
ISDATBSI432MsgLenValidCount_Cnt_M_u16	44139
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	41697
ISDATDIRASentFltAcc_Cnt_M_u16	31957
ISDATDIRASentTimer_mS_M_u32	4066284032
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	21745
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	28584
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	27540
ISDYN2CMMMsgTimer_mS_M_u32	830702080
ISDYNAASChkSumInvalidCount_Cnt_M_u16	29304
ISDYNAASChkSumValidCount_Cnt_M_u16	56394
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	46255
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	29611
ISDYNAASMsgLenValidCount_Cnt_M_u16	39670
ISDYNAASMsgTimeValidCount_Cnt_M_u16	29304
ISDYNAASMsgTimer_mS_M_u32	281764352
ISDYNABRChkSumInvalidCount_Cnt_M_u16	16919
ISDYNABRChkSumValidCount_Cnt_M_u16	19986
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	43519
ISDYNABRMsgCountValidCount_Cnt_M_u16	31505
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	38205
ISDYNABRMsgLenValidCount_Cnt_M_u16	42111
ISDYNABRMsgTimeValidCount_Cnt_M_u16	54627
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	9783
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	3732

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	12017
ISDYNCMM208MsgTimer_mS_M_u32	1834304000
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	9783
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	3732
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	60854
ISDYNCMM388MsgTimer_mS_M_u32	2968445440
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	33732
ISDYNVOLChkSumValidCount_Cnt_M_u16	14918
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	39067
ISDYNVOLMsgCountValidCount_Cnt_M_u16	59445
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	11776
ISDYNVOLMsgLenValidCount_Cnt_M_u16	45283
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	32601
ISDYNVOLMsgTimer_mS_M_u32	1948754432
IgnOnTimer_mS_M_u32	1540547072
IgnTimeOff_Sec_M_u32	2917376528
ManVehSpd_Kph_M_f32	541.354004
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	96
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	33
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1181045248
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	235
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1206202880
PrevISDATBSI412MsgDLCError_Cnt_M_u08	224
PrevISDATBSI412MsgRxTime_MSec_M_u32	3870040576
PrevISDATBSI432MsgDLCError_Cnt_M_u08	27
PrevISDATBSI432MsgRxTime_MSec_M_u32	2167243264
PrevISDATDIRAMsgTxTime_MSec_M_u32	262152704
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	116
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3519705600
PrevISDYNAASMsgDLCError_Cnt_M_u08	40
PrevISDYNAASMsgRxTime_MSec_M_u32	1001759232
PrevISDYNABRMsgDLCError_Cnt_M_u08	150
PrevISDYNABRMsgRxTime_MSec_M_u32	3372933632
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	246
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3364528640
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	225
PrevISDYNCMM388MsgRxTime_MSec_M_u32	282624512
PrevISDYNVOLMsgDLCError_Cnt_M_u08	227
PrevISDYNVOLMsgRxTime_MSec_M_u32	2237211136
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4072378880
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	639.155701
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	58809
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	7044
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	12978
VitesseVehicleBVRampValidCount_Cnt_M_u16	0
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	12219
VitesseVehicleBVSigValidCount_Cnt_M_u16	27950
VitesseVehicleBV_Kph_M_f32	274.869202

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	60854
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	49120
VitesseVehiculeRoues_Kph_M_f32	257.066406
k_AASNTCEnableTimeout_mS_u16	7266
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	37835
k_AASNodeTimeout_mS_u16	40580
k_ABSNodeTimeout_mS_u16	16290
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	10144
k_ANGLEVOLANTSigValidThresh_Cnt_u16	46606
k_AngleVolantInvalidThresh_Cnt_u16	28509
k_AngleVolantValidThresh_Cnt_u16	17521
k_BSI552MsgTimeout_mS_u16	33263
k_BSINTCEnableTimeout_mS_u16	20341
k_BSINodeAbsentDiag_Cnt_str.Threshold	30397
k_BSINodeAbsentDiag_Cnt_str.PStep	60380
k_BSINodeAbsentDiag_Cnt_str.NStep	40319
k_BSINodeAbsentTimeout_mS_u16	54043
k_BSINodeTimeout_mS_u16	41697
k_BattOvHi_Volt_f32	8.7262001
k_BattOvLo_Volt_f32	24.1415005
k_BattUvHi_Volt_f32	7.45629978
k_BattUvLo_Volt_f32	9.80809975
k_CAVNTCEnableTimeout_mS_u16	9143
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	63950
k_CAVNodeTimeout_mS_u16	65490
k_CMM388MsgTimeout_mS_u16	39046
k_CMM388NTCEnableTimeout_mS_u16	52898
k_CMMNTCEnableTimeout_mS_u16	20696
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	52220
k_CONSANGLECPKMax_HwDeg_f32	515.070374
k_CONSANGLECPKMin_HwDeg_f32	-736.055481
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	12470
k_CONSANGLECPKSigValidThresh_Cnt_u16	17120
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	2522
k_CPKVehicleSpeedValidThresh_Cnt_u16	22073
k_CityParkInputInvalidThresh_Cnt_u16	51693
k_CityParkInputValidThresh_Cnt_u16	58252
k_ComputerRazGCTSigValidThresh_Cnt_u16	62550
k_CptTemporelSigValidThresh_Cnt_u16	15804
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	22589
k_DMDFCTCPKSigValidThresh_Cnt_u16	42879
k_DMDFCTCPKValidCount_Cnt_u16	2705
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	27540
k_DMDRELAXECPKSigValidThresh_Cnt_u16	13294
k_DMDRelaxeConsistentThresh_Cnt_u16	26948
k_DateValidThresh_Cnt_u16	56829
k_DefaultVehSpd_Kph_f32	15.8542995
k_DiagMuxOnAbsentTimeout_mS_u16	30249
k_EMNodeTimeout_mS_u16	55155
k_ESPNTCEnableTimeout_mS_u16	62428
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	30404
k_EtatMTSigInvalidThresh_Cnt_u16	37190
k_EtatMTSigValidThresh_Cnt_u16	62081
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	19557
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	43235
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	25221
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	27933
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	36291
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	29298
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	57658
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	20264

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	42273
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	25511
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	15070
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	10144
k_ISDATDIRASentDiag_Cnt_str.Threshold	93
k_ISDATDIRASentDiag_Cnt_str.PStep	55293
k_ISDATDIRASentDiag_Cnt_str.NStep	55204
k_ISDATDIRASentTimeout_mS_u16	58675
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	47093
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	33763
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	1160
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	34071
k_ISDYNAASChkSumValidThresh_Cnt_u16	53522
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	27903
k_ISDYNAASMsgCountValidThresh_Cnt_u16	32273
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	8699
k_ISDYNAASMsgLenValidThresh_Cnt_u16	60008
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	48854
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	10571
k_ISDYNABRChkSumValidThresh_Cnt_u16	50957
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	18889
k_ISDYNABRMsgCountValidThresh_Cnt_u16	38332
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	601
k_ISDYNABRMsgLenValidThresh_Cnt_u16	22919
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	48459
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	53661
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	63943
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	1939
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	42050
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	2293
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	38825
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	51057
k_ISDYNVOLChkSumValidThresh_Cnt_u16	27335
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	5092
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	4342
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	40814
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	47117
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	46531
k_IgnOnTimeout_mS_u16	24205
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	20.9230995
k_PowerCutVehSpdLowThresh_Kph_f32	107.868401
k_PowerCutVehSpdLowTimeout_mS_u16	55662
k_VBattMaxAAS_Volt_f32	19.8320007
k_VBattMaxBSI_Volt_f32	16.9692001
k_VBattMaxCAV_Volt_f32	26.8537006
k_VBattMaxCMM388_Volt_f32	29.3848
k_VBattMaxCMM_Volt_f32	11.3107004
k_VBattMaxESP_Volt_f32	18.2922001
k_VBattMinAAS_Volt_f32	10.3465996
k_VBattMinBSI_Volt_f32	18.2922001
k_VBattMinCAV_Volt_f32	17.6441994
k_VBattMinCMM388_Volt_f32	20.5258007
k_VBattMinCMM_Volt_f32	26.2450008
k_VBattMinESP_Volt_f32	11.3107004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	38815
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	19749
k_VitesseVehicleBVRampValidThresh_Cnt_u16	56219
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	15686
k_VitesseVehicleBVSigValidThresh_Cnt_u16	23997
k_VitesseVehicleBVSpeedPassThresh_kph_f32	655.215271
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	53184
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	19659
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1007600128
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60573
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1277031168
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	225

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	3.12179995
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2081927680
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	124
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.474362582
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3016548864
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4211868160
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4196082176
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	955924992
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1068065280
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	80
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2519237120
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	193
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3296174592
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	34
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	52
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	116
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	172
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	186
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	228
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	28
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4082319872
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	60
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	126
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	234
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2845303296
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3696689664
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	114
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2263228928
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	88
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	151
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	154
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1877422592
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1331
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.57705313
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	126774
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	0.180199996
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	24291

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	33763	33763	✔
AngleVolantMsgTimer_mS_M_u32	1277031168	1277031168	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	54627	54627	✔
CONSANGLECPK_HwDeg_M_f32	414.840088	414.840088 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	54627	54627	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4066284032	4066284032	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	25425	25425	✔
CityParkInputConsistentCount_Cnt_M_u16	58252	58252	✔
CityParkInputInvalidCount_Cnt_M_u16	17523	17523	✔
CityParkInputMsgTimer_mS_M_u32	1277031168	1277031168	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1277031168	1277031168	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1277031168	1277031168	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1277031168	1277031168	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1277031168	1277031168	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1277031168	1277031168	✔
ESPNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	20	20	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	6	6	✔
ElecIntTimer_mS_M_u32[1]	17	17	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1277031168	1277031168	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATDIRASentFltAcc_Cnt_M_u16	93	93	✔
ISDATDIRASentTimer_mS_M_u32	1277031168	1277031168	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1277031168	1277031168	✔
IgnOnTimer_mS_M_u32	1277031168	1277031168	✔
IgnTimeOff_Sec_M_u32	2917376528	2917376528	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	162	162	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3016548864	3016548864	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	0	0	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4211868160	4211868160	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	83	83	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4196082176	4196082176	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	33	33	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	955924992	955924992	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	262152704	262152704	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	80	80	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2519237120	2519237120	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	193	193	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3296174592	3296174592	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	28	28	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4082319872	4082319872	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	234	234	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2845303296	2845303296	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	212	212	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3696689664	3696689664	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	114	114	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2263228928	2263228928	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1877422592	1877422592	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	639.155701	639.155701	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	274.869202	274.869202	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	257.066406	257.066406	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	54627	54627	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2917376528	2917376528	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	414.840088	414.840088 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	15.8542995	15.8542995	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.225 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2609384704
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	43476
AASNodeAbsentTimer_mS_M_u32	2526887168
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	6303
ANGLEVOLANTSigValidCount_Cnt_M_u16	49223
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	21181
AngleVolantMsgTimer_mS_M_u32	2609384704
AngleVolantValidCount_Cnt_M_u16	35822
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2233859328
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3036314880
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	845950208
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	168291584
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	1034
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3911363840
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	13988
CAVNodeAbsentTimer_mS_M_u32	4114963712
CDD_SrlComVehSpd_Kph_G_f32	565.022278
CMM388NTCEnableTimer_mS_M_u32	1217961216
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	709057792
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	56730
CMMNodeAbsentTimer_mS_M_u32	2710170880
CONSANGLECPKSigInvalidCount_Cnt_M_u16	27459
CONSANGLECPKSigValidCount_Cnt_M_u16	35068
CONSANGLECPK_Cnt_M_u16	31995
CONSANGLECPK_HwDeg_M_f32	730.994812
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	31995
CPKVehicleSpeedMsgTimer_mS_M_u32	1430981888
CPKVehicleSpeedValidCount_Cnt_M_u16	51866
CityParkInputConsistentCount_Cnt_M_u16	49218

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	49810
CityParkInputMsgTimer_mS_M_u32	3016548864
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3757128960
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	7208
ComputerRazGCTSigInvalidTimer_mS_M_u32	3817069824
ComputerRazGCTSigValidCount_Cnt_M_u16	41731
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	64062
DMDFCTCPKSigValidCount_Cnt_M_u16	27823
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	44489
DMDRELAXECPKSigValidCount_Cnt_M_u16	49393
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	59692
DateInvalidTimer_mS_M_u32	3036314880
DiagMuxOnAbsentTimer_mS_M_u32	2114112768
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	168291584
ESPNTCEnableTimer_mS_M_u32	1704606976
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	40399
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	12
EffacDefaultDiagTimer_mS_M_u32[1]	13
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	88
ElecIntTimer_mS_M_u32[1]	109
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	4281117952
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	13998
EtatMTSigValidCount_Cnt_M_u16	2451
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	65133
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1958
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	62381
ISDAT4V2BSI552MsgTimer_mS_M_u32	31321344
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	63302
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	46675
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	2451
ISDATBSI3F2MsgTimer_mS_M_u32	2732117248
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	39547
ISDATBSI412MsgLenValidCount_Cnt_M_u16	29432
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	13998
ISDATBSI412MsgTimer_mS_M_u32	777915648
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	38126
ISDATBSI432MsgLenValidCount_Cnt_M_u16	60451
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	47169
ISDATDIRASentFltAcc_Cnt_M_u16	64101
ISDATDIRASentTimer_mS_M_u32	1430981888
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	46673
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	35822
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	39209
ISDYN2CMMMsgTimer_mS_M_u32	2543598848
ISDYNAASChkSumInvalidCount_Cnt_M_u16	6910
ISDYNAASChkSumValidCount_Cnt_M_u16	29511
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	39129
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	60899
ISDYNAASMsgLenValidCount_Cnt_M_u16	60868
ISDYNAASMsgTimeValidCount_Cnt_M_u16	6910
ISDYNAASMsgTimer_mS_M_u32	1900322048
ISDYNABRChkSumInvalidCount_Cnt_M_u16	33694
ISDYNABRChkSumValidCount_Cnt_M_u16	38255
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	20585
ISDYNABRMsgCountValidCount_Cnt_M_u16	29426
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	22446
ISDYNABRMsgLenValidCount_Cnt_M_u16	32679
ISDYNABRMsgTimeValidCount_Cnt_M_u16	31995
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	56900

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	21997
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	2451
ISDYNCMM208MsgTimer_mS_M_u32	1529281792
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	56900
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	21997
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	51652
ISDYNCMM388MsgTimer_mS_M_u32	2128223488
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	26649
ISDYNVOLChkSumValidCount_Cnt_M_u16	39506
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	60948
ISDYNVOLMsgCountValidCount_Cnt_M_u16	46341
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	64356
ISDYNVOLMsgLenValidCount_Cnt_M_u16	18556
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	56730
ISDYNVOLMsgTimer_mS_M_u32	137354496
IgnOnTimer_mS_M_u32	237903104
IgnTimeOff_Sec_M_u32	1660545486
ManVehSpd_Kph_M_f32	540.838013
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	97
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	241
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3828796672
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	75
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	926362880
PrevISDATBSI412MsgDLCError_Cnt_M_u08	91
PrevISDATBSI412MsgRxTime_MSec_M_u32	1654807808
PrevISDATBSI432MsgDLCError_Cnt_M_u08	215
PrevISDATBSI432MsgRxTime_MSec_M_u32	3500031232
PrevISDATDIRAMsgTxTime_MSec_M_u32	3083230464
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	147
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3196546304
PrevISDYNAASMsgDLCError_Cnt_M_u08	134
PrevISDYNAASMsgRxTime_MSec_M_u32	1770380544
PrevISDYNABRMsgDLCError_Cnt_M_u08	134
PrevISDYNABRMsgRxTime_MSec_M_u32	2793807104
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	5
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1460067584
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	139
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2375892224
PrevISDYNVOLMsgDLCError_Cnt_M_u08	202
PrevISDYNVOLMsgRxTime_MSec_M_u32	2057002240
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	137628928
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	437.797302
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	20409
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	9242
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	36046
VitesseVehicleBVRampValidCount_Cnt_M_u16	65535
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	20788
VitesseVehicleBVSigValidCount_Cnt_M_u16	44700

Name	Input Value
VitesseVehicleBV_Kph_M_f32	112.859596
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	51652
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	18692
VitesseVehiculeRoues_Kph_M_f32	621.347595
k_AASNTCEnableTimeout_mS_u16	25598
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	27525
k_AASNodeTimeout_mS_u16	39706
k_ABSNodeTimeout_mS_u16	54527
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	49349
k_ANGLEVOLANTSigValidThresh_Cnt_u16	6970
k_AngleVolantInvalidThresh_Cnt_u16	60237
k_AngleVolantValidThresh_Cnt_u16	49810
k_BSI552MsgTimeout_mS_u16	65239
k_BSINTCEnableTimeout_mS_u16	56646
k_BSINodeAbsentDiag_Cnt_str.Threshold	32305
k_BSINodeAbsentDiag_Cnt_str.PStep	56853
k_BSINodeAbsentDiag_Cnt_str.NStep	39020
k_BSINodeAbsentTimeout_mS_u16	17685
k_BSINodeTimeout_mS_u16	47169
k_BattOvHi_Volt_f32	27.6051998
k_BattOvLo_Volt_f32	7.60699987
k_BattUvHi_Volt_f32	11.6738997
k_BattUvLo_Volt_f32	17.5359001
k_CAVNTCEnableTimeout_mS_u16	48320
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	42874
k_CAVNodeTimeout_mS_u16	44015
k_CMM388MsgTimeout_mS_u16	24788
k_CMM388NTCEnableTimeout_mS_u16	11904
k_CMMNTCEnableTimeout_mS_u16	11166
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	38064
k_CONSANGLECPKMax_HwDeg_f32	133.942993
k_CONSANGLECPKMin_HwDeg_f32	-337.824585
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	196
k_CONSANGLECPKSigValidThresh_Cnt_u16	49156
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	12568
k_CPKVehicleSpeedValidThresh_Cnt_u16	12410
k_CityParkInputInvalidThresh_Cnt_u16	50204
k_CityParkInputValidThresh_Cnt_u16	49218
k_ComputerRazGCTSigValidThresh_Cnt_u16	47396
k_CptTemporelSigValidThresh_Cnt_u16	49841
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	3758
k_DMDFCTCPKSigValidThresh_Cnt_u16	30375
k_DMDFCTCPKValidCount_Cnt_u16	39090
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	39209
k_DMDRELAXECPKSigValidThresh_Cnt_u16	62938
k_DMDRelaxeConsistentThresh_Cnt_u16	11736
k_DateValidThresh_Cnt_u16	62381
k_DefaultVehSpd_Kph_f32	149.338593
k_DiagMuxOnAbsentTimeout_mS_u16	12969
k_EMNodeTimeout_mS_u16	59660
k_ESPNTCEnableTimeout_mS_u16	29008
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	46168
k_EtatMTSigInvalidThresh_Cnt_u16	4625
k_EtatMTSigValidThresh_Cnt_u16	9250
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	21879
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	34236
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	26455
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	10959
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	44700
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	65487
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	31735

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	14316
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	35906
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	57903
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	33356
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	26949
k_ISDATDIRASentDiag_Cnt_str.Threshold	11630
k_ISDATDIRASentDiag_Cnt_str.PStep	28093
k_ISDATDIRASentDiag_Cnt_str.NStep	10447
k_ISDATDIRASentTimeout_mS_u16	2634
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	19526
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	21181
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	61260
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	47774
k_ISDYNAASChkSumValidThresh_Cnt_u16	3183
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	1897
k_ISDYNAASMsgCountValidThresh_Cnt_u16	27122
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	29682
k_ISDYNAASMsgLenValidThresh_Cnt_u16	18286
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	8418
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	21380
k_ISDYNABRChkSumValidThresh_Cnt_u16	53245
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	47882
k_ISDYNABRMsgCountValidThresh_Cnt_u16	60658
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	21658
k_ISDYNABRMsgLenValidThresh_Cnt_u16	21711
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	29253
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	7181
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	64976
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	23533
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	53151
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	46919
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	43242
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	48338
k_ISDYNVOLChkSumValidThresh_Cnt_u16	30863
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	55736
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	56515
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	25178
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	56895
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	1115
k_IgnOnTimeout_mS_u16	26494
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	84.6320038
k_PowerCutVehSpdLowThresh_Kph_f32	151.796097
k_PowerCutVehSpdLowTimeout_mS_u16	23770
k_VBattMaxAAS_Volt_f32	2.23729992
k_VBattMaxBSI_Volt_f32	9.08549976
k_VBattMaxCAV_Volt_f32	14.0110998
k_VBattMaxCMM388_Volt_f32	17.0524998
k_VBattMaxCMM_Volt_f32	32
k_VBattMaxESP_Volt_f32	3.21530008
k_VBattMinAAS_Volt_f32	29.3724003
k_VBattMinBSI_Volt_f32	3.21530008
k_VBattMinCAV_Volt_f32	25.8808994
k_VBattMinCMM388_Volt_f32	23.7458992
k_VBattMinCMM_Volt_f32	11.1968002
k_VBattMinESP_Volt_f32	32
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	54600
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	6772
k_VitesseVehicleBVRampValidThresh_Cnt_u16	9492
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	37202
k_VitesseVehicleBVSigValidThresh_Cnt_u16	21935
k_VitesseVehicleBVSpeedPassThresh_kph_f32	559.472107
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	28068
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	27717
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3036314880
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	22411
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	4207995392
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	139
target_SrlComInput_Per1_Batt_Volt_f32.value	12.6223001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2225057024
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	220
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.514373004
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1849695488
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4244815104
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2757057792
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	185
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3426221312
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3702168832
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	116
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1034763520
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	36
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1463803136
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	118
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	119
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	167
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1093467392
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	114
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	185
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	220
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2027887872
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1159838976
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3925105920
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	50
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	155
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1194405120
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3391
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.373450071
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	213392
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	158.110794

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	3131		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	4207995392	4207995392	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4207995392	4207995392	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	21183	21183	✔
AngleVolantMsgTimer_mS_M_u32	4207995392	4207995392	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	4207995392	4207995392	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4207995392	4207995392	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4207995392	4207995392	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4207995392	4207995392	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	4207995392	4207995392	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4207995392	4207995392	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4207995392	4207995392	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4207995392	4207995392	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4207995392	4207995392	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4207995392	4207995392	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	31995	31995	✔
CONSANGLECPK_HwDeg_M_f32	730.994812	730.994812 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	31995	31995	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1430981888	1430981888	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	51866	51866	✔
CityParkInputConsistentCount_Cnt_M_u16	49218	49218	✔
CityParkInputInvalidCount_Cnt_M_u16	49812	49812	✔
CityParkInputMsgTimer_mS_M_u32	4207995392	4207995392	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4207995392	4207995392	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4207995392	4207995392	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4207995392	4207995392	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4207995392	4207995392	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4207995392	4207995392	✔
ESPNTCEnableTimer_mS_M_u32	4207995392	4207995392	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4207995392	4207995392	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4207995392	4207995392	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	13	13	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	4207995392	4207995392	✔
ElecIntTimer_mS_M_u32[1]	109	109	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4207995392	4207995392	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4207995392	4207995392	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4207995392	4207995392	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4207995392	4207995392	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4207995392	4207995392	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11630	11630	✔
ISDATDIRASentTimer_mS_M_u32	4207995392	4207995392	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4207995392	4207995392	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4207995392	4207995392	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4207995392	4207995392	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4207995392	4207995392	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4207995392	4207995392	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4207995392	4207995392	✔
IgnOnTimer_mS_M_u32	237903104	237903104	✔
IgnTimeOff_Sec_M_u32	1660545486	1660545486	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	39	39	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1849695488	1849695488	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4244815104	4244815104	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	223	223	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2757057792	2757057792	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	185	185	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3426221312	3426221312	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3083230464	3083230464	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	116	116	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1034763520	1034763520	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	36	36	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1463803136	1463803136	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	108	108	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1093467392	1093467392	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	59	59	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2027887872	2027887872	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1159838976	1159838976	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3925105920	3925105920	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1194405120	1194405120	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	437.797302	437.797302	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	112.859596	112.859596	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	621.347595	621.347595	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	31995	31995	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1660545486	1660545486	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	730.994812	730.994812 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.226 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3984235520
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	38037
AASNodeAbsentTimer_mS_M_u32	217779200
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	37429
ANGLEVOLANTSigValidCount_Cnt_M_u16	23035
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	32218
AngleVolantMsgTimer_mS_M_u32	3984235520
AngleVolantValidCount_Cnt_M_u16	56520
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1415629824
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3068349440
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1632517120
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4185586688
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	15348
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	925547520
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	54948
CAVNodeAbsentTimer_mS_M_u32	964865024
CDD_SrlComVehSpd_Kph_G_f32	385.026611
CMM388NTCEnableTimer_mS_M_u32	2626219008
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	310946816
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	25986
CMMNodeAbsentTimer_mS_M_u32	3136617472
CONSANGLECPKSigInvalidCount_Cnt_M_u16	7495
CONSANGLECPKSigValidCount_Cnt_M_u16	49885
CONSANGLECPK_Cnt_M_u16	41696
CONSANGLECPK_HwDeg_M_f32	-201.177094
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	41696
CPKVehicleSpeedMsgTimer_mS_M_u32	2352061440
CPKVehicleSpeedValidCount_Cnt_M_u16	29643
CityParkInputConsistentCount_Cnt_M_u16	36812
CityParkInputInvalidCount_Cnt_M_u16	6619
CityParkInputMsgTimer_mS_M_u32	1849695488
CityParkInputValidCount_Cnt_M_u16	2

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2164198400
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	36249
ComputerRazGCTSigInvalidTimer_mS_M_u32	2294754304
ComputerRazGCTSigValidCount_Cnt_M_u16	11145
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	8919
DMDFCTCPKSigValidCount_Cnt_M_u16	43589
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	64183
DMDRELAXECPKSigValidCount_Cnt_M_u16	32765
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	34700
DateInvalidTimer_mS_M_u32	3068349440
DiagMuxOnAbsentTimer_mS_M_u32	2701810688
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4185586688
ESPNTCEnableTimer_mS_M_u32	3557035008
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	5028
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	101
EffacDefaultDiagTimer_mS_M_u32[1]	202
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1
ElecIntTimer_mS_M_u32[1]	12
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2634857472
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	64326
EtatMTSigValidCount_Cnt_M_u16	12632
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	35785
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	28383
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	36171
ISDAT4V2BSI552MsgTimer_mS_M_u32	3925408768
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	28926
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	33432
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	12632
ISDATBSI3F2MsgTimer_mS_M_u32	176708608
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	60510
ISDATBSI412MsgLenValidCount_Cnt_M_u16	29096
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	64326
ISDATBSI412MsgTimer_mS_M_u32	217619456
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	36742
ISDATBSI432MsgLenValidCount_Cnt_M_u16	30888
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	1485
ISDATDIRASentFltAcc_Cnt_M_u16	53089
ISDATDIRASentTimer_mS_M_u32	2352061440
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	52958
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	56520
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	45590
ISDYN2CMMMsgTimer_mS_M_u32	3321760768
ISDYNAASChkSumInvalidCount_Cnt_M_u16	26903
ISDYNAASChkSumValidCount_Cnt_M_u16	40701
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	8711
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	27879
ISDYNAASMsgLenValidCount_Cnt_M_u16	3077
ISDYNAASMsgTimeValidCount_Cnt_M_u16	26903
ISDYNAASMsgTimer_mS_M_u32	3531926528
ISDYNABRChkSumInvalidCount_Cnt_M_u16	43189
ISDYNABRChkSumValidCount_Cnt_M_u16	53763
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	13526
ISDYNABRMsgCountValidCount_Cnt_M_u16	3068
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	50182
ISDYNABRMsgLenValidCount_Cnt_M_u16	19164
ISDYNABRMsgTimeValidCount_Cnt_M_u16	41696
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	37816
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	39551
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	12632
ISDYNCMM208MsgTimer_mS_M_u32	375245824

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	37816
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	39551
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	64326
ISDYNCMM388MsgTimer_mS_M_u32	3754191872
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	65221
ISDYNVOLChkSumValidCount_Cnt_M_u16	26331
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	8021
ISDYNVOLMsgCountValidCount_Cnt_M_u16	43331
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	36581
ISDYNVOLMsgLenValidCount_Cnt_M_u16	9819
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	25986
ISDYNVOLMsgTimer_mS_M_u32	3401788416
IgnOnTimer_mS_M_u32	2177395712
IgnTimeOff_Sec_M_u32	2216936227
ManVehSpd_Kph_M_f32	459.502197
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	98
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	56
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1047419904
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	5
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1055734784
PrevISDATBSI412MsgDLCError_Cnt_M_u08	14
PrevISDATBSI412MsgRxTime_MSec_M_u32	2775297024
PrevISDATBSI432MsgDLCError_Cnt_M_u08	16
PrevISDATBSI432MsgRxTime_MSec_M_u32	2734164992
PrevISDATDIRAMsgTxTime_MSec_M_u32	905948160
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	125
PrevISDYN2CMMMsgRxTime_MSec_M_u32	972848128
PrevISDYNAASMsgDLCError_Cnt_M_u08	122
PrevISDYNAASMsgRxTime_MSec_M_u32	2126588928
PrevISDYNABRMsgDLCError_Cnt_M_u08	161
PrevISDYNABRMsgRxTime_MSec_M_u32	415263744
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	67
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4198378496
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	219
PrevISDYNCMM388MsgRxTime_MSec_M_u32	670764032
PrevISDYNVOLMsgDLCError_Cnt_M_u08	84
PrevISDYNVOLMsgRxTime_MSec_M_u32	2172693504
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1467390976
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	197.531693
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	8037
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	16643
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	64550
VitesseVehicleBVRampValidCount_Cnt_M_u16	60196
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	31862
VitesseVehicleBVSigValidCount_Cnt_M_u16	8956
VitesseVehicleBV_Kph_M_f32	175.015503
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	64326
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	40004

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	566.013123
k_AASNTCEnableTimeout_mS_u16	47575
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	23043
k_AASNodeTimeout_mS_u16	56323
k_ABSNodeTimeout_mS_u16	54932
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	10241
k_ANGLEVOLANTSigValidThresh_Cnt_u16	1891
k_AngleVolantInvalidThresh_Cnt_u16	41770
k_AngleVolantValidThresh_Cnt_u16	6619
k_BSI552MsgTimeout_mS_u16	34507
k_BSINTCEnableTimeout_mS_u16	5758
k_BSINodeAbsentDiag_Cnt_str.Threshold	65394
k_BSINodeAbsentDiag_Cnt_str.PStep	41479
k_BSINodeAbsentDiag_Cnt_str.NStep	1344
k_BSINodeAbsentTimeout_mS_u16	1746
k_BSINodeTimeout_mS_u16	1485
k_BattOvHi_Volt_f32	18.0263004
k_BattOvLo_Volt_f32	31.5
k_BattUvHi_Volt_f32	27.5438995
k_BattUvLo_Volt_f32	3.70539999
k_CAVNTCEnableTimeout_mS_u16	25425
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	23586
k_CAVNodeTimeout_mS_u16	2883
k_CMM388MsgTimeout_mS_u16	28565
k_CMM388NTCEnableTimeout_mS_u16	46737
k_CMMNTCEnableTimeout_mS_u16	13302
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	26944
k_CONSANGLECPKMax_HwDeg_f32	80.4179993
k_CONSANGLECPKMin_HwDeg_f32	-651.842773
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	22086
k_CONSANGLECPKSigValidThresh_Cnt_u16	14148
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	37385
k_CPKVehicleSpeedValidThresh_Cnt_u16	58977
k_CityParkInputInvalidThresh_Cnt_u16	24379
k_CityParkInputValidThresh_Cnt_u16	36812
k_ComputerRazGCTSigValidThresh_Cnt_u16	9060
k_CptTemporelSigValidThresh_Cnt_u16	21886
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	40710
k_DMDFCTCPKSigValidThresh_Cnt_u16	26076
k_DMDFCTCPKValidCount_Cnt_u16	7676
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	45590
k_DMDRELAXECPKSigValidThresh_Cnt_u16	31428
k_DMDRelaxeConsistentThresh_Cnt_u16	19146
k_DateValidThresh_Cnt_u16	36171
k_DefaultVehSpd_Kph_f32	2.55760002
k_DiagMuxOnAbsentTimeout_mS_u16	47574
k_EMNodeTimeout_mS_u16	2028
k_ESPNTCEnableTimeout_mS_u16	54944
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	43592
k_EtatMTSigInvalidThresh_Cnt_u16	35164
k_EtatMTSigValidThresh_Cnt_u16	45546
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	24812
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	65246
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	11917
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	14947
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	64957
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	3170
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	15979
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	63821
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	63882
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	17220

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	61870
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	13571
k_ISDATDIRASentDiag_Cnt_str.Threshold	14294
k_ISDATDIRASentDiag_Cnt_str.PStep	34147
k_ISDATDIRASentDiag_Cnt_str.NStep	18148
k_ISDATDIRASentTimeout_mS_u16	50353
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	53248
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	32218
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	19628
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	949
k_ISDYNAASChkSumValidThresh_Cnt_u16	27907
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	4054
k_ISDYNAASMsgCountValidThresh_Cnt_u16	9980
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	10169
k_ISDYNAASMsgLenValidThresh_Cnt_u16	9991
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	38507
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	43140
k_ISDYNABRChkSumValidThresh_Cnt_u16	12762
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	5876
k_ISDYNABRMsgCountValidThresh_Cnt_u16	16378
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	130
k_ISDYNABRMsgLenValidThresh_Cnt_u16	61092
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	48129
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	2665
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	22111
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	42378
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	27957
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	29947
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	50899
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	41305
k_ISDYNVOLChkSumValidThresh_Cnt_u16	31971
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	17385
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	19463
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	10306
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	25428
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	37697
k_IgnOnTimeout_mS_u16	20821
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	89.1772003
k_PowerCutVehSpdLowThresh_Kph_f32	183.684998
k_PowerCutVehSpdLowTimeout_mS_u16	16195
k_VBattMaxAAS_Volt_f32	8.31509972
k_VBattMaxBSI_Volt_f32	25.9911995
k_VBattMaxCAV_Volt_f32	6.47720003
k_VBattMaxCMM388_Volt_f32	31.4486008
k_VBattMaxCMM_Volt_f32	2.00629997
k_VBattMaxESP_Volt_f32	16.3059998
k_VBattMinAAS_Volt_f32	29.8736
k_VBattMinBSI_Volt_f32	16.3059998
k_VBattMinCAV_Volt_f32	18.1441994
k_VBattMinCMM388_Volt_f32	5.01980019
k_VBattMinCMM_Volt_f32	28.8419991
k_VBattMinESP_Volt_f32	2.00629997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	48378
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	48179
k_VitesseVehicleBVRampValidThresh_Cnt_u16	31317
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	33243
k_VitesseVehicleBVSigValidThresh_Cnt_u16	50053
k_VitesseVehicleBVSpeedPassThresh_kph_f32	635.626404
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	12708
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	54402
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3068349440
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	41596
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2471757056
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSe	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	219
target_SrlComInput_Per1_Batt_Volt_f32.value	26.3297997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2561915904
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	129
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.789746165
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	697461760
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1338674176
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	234
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1817357312
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1193987072
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2824006656
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1472924672
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	496184320
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	9
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	47
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	151
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	183
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	234
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	236
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4232825856
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	174
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	186
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	245
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1169517568
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	10
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3010300928
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	122
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3614813184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	84
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	188
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	203
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1996438528
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2698
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.858435512
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	306326
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	90.9908981
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	29151

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2471757056	2471757056	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2471757056	2471757056	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2471757056	2471757056	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2471757056	2471757056	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2471757056	2471757056	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2471757056	2471757056	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2471757056	2471757056	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2471757056	2471757056	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2471757056	2471757056	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2471757056	2471757056	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2471757056	2471757056	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2471757056	2471757056	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2471757056	2471757056	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	41696	41696	✔
CONSANGLECPK_HwDeg_M_f32	-201.177094	-201.177094 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2471757056	2471757056	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2471757056	2471757056	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2471757056	2471757056	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2471757056	2471757056	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2471757056	2471757056	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2471757056	2471757056	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2471757056	2471757056	✔
ESPNTCEnableTimer_mS_M_u32	2471757056	2471757056	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2471757056	2471757056	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2471757056	2471757056	✔
EffacDefaultDiagTimer_mS_M_u32[1]	202	202	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2471757056	2471757056	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	12	12	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2471757056	2471757056	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2471757056	2471757056	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2471757056	2471757056	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2471757056	2471757056	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2471757056	2471757056	✔
ISDATDIRASentFltAcc_Cnt_M_u16	14294	14294	✔
ISDATDIRASentTimer_mS_M_u32	2471757056	2471757056	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2471757056	2471757056	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2471757056	2471757056	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2471757056	2471757056	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2471757056	2471757056	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2471757056	2471757056	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2471757056	2471757056	✔
IgnOnTimer_mS_M_u32	2177395712	2177395712	✔
IgnTimeOff_Sec_M_u32	2216936227	2216936227	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	108	108	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	697461760	697461760	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	34	34	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1338674176	1338674176	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	234	234	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1817357312	1817357312	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	141	141	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1193987072	1193987072	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	905948160	905948160	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	129	129	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1472924672	1472924672	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	99	99	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	496184320	496184320	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	137	137	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4232825856	4232825856	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	108	108	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1169517568	1169517568	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	10	10	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3010300928	3010300928	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	122	122	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3614813184	3614813184	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1996438528	1996438528	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	197.531693	197.531693	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	175.015503	175.015503	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	566.013123	566.013123	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	41696	41696	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2216936227	2216936227	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-201.177094	-201.177094 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.227 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3097423616
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	19791
AASNodeAbsentTimer_mS_M_u32	668835584
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	30317
ANGLEVOLANTSigValidCount_Cnt_M_u16	58076
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	58752
AngleVolantMsgTimer_mS_M_u32	3097423616
AngleVolantValidCount_Cnt_M_u16	43318
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	413949696
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	455401216
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3013873408
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2384318208
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	13616
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1141804800
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	52640
CAVNodeAbsentTimer_mS_M_u32	3368468224
CDD_SrlComVehSpd_Kph_G_f32	319.910095
CMM388NTCEnableTimer_mS_M_u32	2293497600
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3585392384
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	38341
CMMNodeAbsentTimer_mS_M_u32	2981089024
CONSANGLECPKSigInvalidCount_Cnt_M_u16	19512
CONSANGLECPKSigValidCount_Cnt_M_u16	24374
CONSANGLECPK_Cnt_M_u16	35629
CONSANGLECPK_HwDeg_M_f32	497.649414
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	35629
CPKVehicleSpeedMsgTimer_mS_M_u32	2021256960
CPKVehicleSpeedValidCount_Cnt_M_u16	2835
CityParkInputConsistentCount_Cnt_M_u16	41002
CityParkInputInvalidCount_Cnt_M_u16	20220
CityParkInputMsgTimer_mS_M_u32	697461760
CityParkInputValidCount_Cnt_M_u16	5

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3687948032
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	29251
ComputerRazGCTSigInvalidTimer_mS_M_u32	2365144832
ComputerRazGCTSigValidCount_Cnt_M_u16	243
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	9224
DMDFCTCPKSigValidCount_Cnt_M_u16	61822
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	50407
DMDRELAXECPKSigValidCount_Cnt_M_u16	63702
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	24937
DateInvalidTimer_mS_M_u32	455401216
DiagMuxOnAbsentTimer_mS_M_u32	2364518144
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2384318208
ESPNTCEnableTimer_mS_M_u32	918724352
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	48928
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	305
EffacDefaultDiagTimer_mS_M_u32[1]	706
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	12
ElecIntTimer_mS_M_u32[1]	17
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	443059968
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	61820
EtatMTSigValidCount_Cnt_M_u16	17158
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	34994
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	58160
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	57452
ISDAT4V2BSI552MsgTimer_mS_M_u32	883150592
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	27091
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	18629
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	17158
ISDATBSI3F2MsgTimer_mS_M_u32	3363155712
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	51378
ISDATBSI412MsgLenValidCount_Cnt_M_u16	3220
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	61820
ISDATBSI412MsgTimer_mS_M_u32	3525635840
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	10169
ISDATBSI432MsgLenValidCount_Cnt_M_u16	40980
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	9253
ISDATDIRASentFltAcc_Cnt_M_u16	5993
ISDATDIRASentTimer_mS_M_u32	2021256960
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	32563
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	43318
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	12875
ISDYN2CMMMsgTimer_mS_M_u32	3369377536
ISDYNAASChkSumInvalidCount_Cnt_M_u16	22473
ISDYNAASChkSumValidCount_Cnt_M_u16	63959
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	38265
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	54999
ISDYNAASMsgLenValidCount_Cnt_M_u16	7485
ISDYNAASMsgTimeValidCount_Cnt_M_u16	22473
ISDYNAASMsgTimer_mS_M_u32	3602906880
ISDYNABRChkSumInvalidCount_Cnt_M_u16	11372
ISDYNABRChkSumValidCount_Cnt_M_u16	37954
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	45196
ISDYNABRMsgCountValidCount_Cnt_M_u16	28378
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	5115
ISDYNABRMsgLenValidCount_Cnt_M_u16	33593
ISDYNABRMsgTimeValidCount_Cnt_M_u16	35629
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	19079
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	60659
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	17158
ISDYNCMM208MsgTimer_mS_M_u32	112549632

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	19079
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	60659
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	50620
ISDYNCMM388MsgTimer_mS_M_u32	218201856
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	8126
ISDYNVOLChkSumValidCount_Cnt_M_u16	60220
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	42638
ISDYNVOLMsgCountValidCount_Cnt_M_u16	27780
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	37213
ISDYNVOLMsgLenValidCount_Cnt_M_u16	20155
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	38341
ISDYNVOLMsgTimer_mS_M_u32	3070574336
IgnOnTimer_mS_M_u32	922058496
IgnTimeOff_Sec_M_u32	2824444163
ManVehSpd_Kph_M_f32	90.714798
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	99
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	242
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1153675008
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	247
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1455886080
PrevISDATBSI412MsgDLCError_Cnt_M_u08	53
PrevISDATBSI412MsgRxTime_MSec_M_u32	1762377472
PrevISDATBSI432MsgDLCError_Cnt_M_u08	201
PrevISDATBSI432MsgRxTime_MSec_M_u32	2582028032
PrevISDATDIRAMsgTxTime_MSec_M_u32	122666752
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	155
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2996391680
PrevISDYNAASMsgDLCError_Cnt_M_u08	38
PrevISDYNAASMsgRxTime_MSec_M_u32	319504128
PrevISDYNABRMsgDLCError_Cnt_M_u08	63
PrevISDYNABRMsgRxTime_MSec_M_u32	1376616192
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	250
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3566485248
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	181
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3604848384
PrevISDYNVOLMsgDLCError_Cnt_M_u08	166
PrevISDYNVOLMsgRxTime_MSec_M_u32	1758248704
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1789587200
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	620.884521
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	14173
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	63043
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0
VitesseVehicleBVRampValidCount_Cnt_M_u16	26560
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	64426
VitesseVehicleBVSigValidCount_Cnt_M_u16	52185
VitesseVehicleBV_Kph_M_f32	398.720306
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	50620
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	34434

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	39.7430992
k_AASNTCEnableTimeout_mS_u16	57928
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	56709
k_AASNodeTimeout_mS_u16	9539
k_ABSNodeTimeout_mS_u16	15569
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	2632
k_ANGLEVOLANTSigValidThresh_Cnt_u16	40931
k_AngleVolantInvalidThresh_Cnt_u16	43150
k_AngleVolantValidThresh_Cnt_u16	20220
k_BSI552MsgTimeout_mS_u16	41709
k_BSINTCEnableTimeout_mS_u16	29393
k_BSINodeAbsentDiag_Cnt_str.Threshold	9435
k_BSINodeAbsentDiag_Cnt_str.PStep	63067
k_BSINodeAbsentDiag_Cnt_str.NStep	5615
k_BSINodeAbsentTimeout_mS_u16	10904
k_BSINodeTimeout_mS_u16	9253
k_BattOvHi_Volt_f32	25.4328003
k_BattOvLo_Volt_f32	25.4057007
k_BattUvHi_Volt_f32	14.2090998
k_BattUvLo_Volt_f32	6.98180008
k_CAVNTCEnableTimeout_mS_u16	51866
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	46374
k_CAVNodeTimeout_mS_u16	29252
k_CMM388MsgTimeout_mS_u16	48207
k_CMM388NTCEnableTimeout_mS_u16	55131
k_CMMNTCEnableTimeout_mS_u16	235
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	3982
k_CONSANGLECPKMax_HwDeg_f32	463.652405
k_CONSANGLECPKMin_HwDeg_f32	-252.874802
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	46268
k_CONSANGLECPKSigValidThresh_Cnt_u16	46466
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	39729
k_CPKVehicleSpeedValidThresh_Cnt_u16	42665
k_CityParkInputInvalidThresh_Cnt_u16	41178
k_CityParkInputValidThresh_Cnt_u16	41002
k_ComputerRazGCTSigValidThresh_Cnt_u16	27297
k_CptTemporelSigValidThresh_Cnt_u16	59411
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	33531
k_DMDFCTCPKSigValidThresh_Cnt_u16	12857
k_DMDFCTCPKValidCount_Cnt_u16	44824
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	12875
k_DMDRELAXECPKSigValidThresh_Cnt_u16	15361
k_DMDRelaxeConsistentThresh_Cnt_u16	25583
k_DateValidThresh_Cnt_u16	57452
k_DefaultVehSpd_Kph_f32	113.885002
k_DiagMuxOnAbsentTimeout_mS_u16	40523
k_EMNodeTimeout_mS_u16	24649
k_ESPNTCEnableTimeout_mS_u16	48556
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	27766
k_EtatMTSigInvalidThresh_Cnt_u16	58999
k_EtatMTSigValidThresh_Cnt_u16	20621
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	31368
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	5234
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	2023
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	57764
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	43862
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	30886
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	61194
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	61989
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	63917
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	14849

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	33412
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	53189
k_ISDATDIRASentDiag_Cnt_str.Threshold	6491
k_ISDATDIRASentDiag_Cnt_str.PStep	58700
k_ISDATDIRASentDiag_Cnt_str.NStep	43168
k_ISDATDIRASentTimeout_mS_u16	51320
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	13006
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58752
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	35720
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	7020
k_ISDYNAASChkSumValidThresh_Cnt_u16	49986
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	8076
k_ISDYNAASMsgCountValidThresh_Cnt_u16	7642
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	48992
k_ISDYNAASMsgLenValidThresh_Cnt_u16	21559
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	4811
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	56961
k_ISDYNABRChkSumValidThresh_Cnt_u16	17983
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	42032
k_ISDYNABRMsgCountValidThresh_Cnt_u16	60639
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	50373
k_ISDYNABRMsgLenValidThresh_Cnt_u16	11808
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	21706
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	34385
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	52911
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	42158
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	58733
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	37340
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	10260
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	21953
k_ISDYNVOLChkSumValidThresh_Cnt_u16	38627
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	33361
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	13878
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	23176
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	40210
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	9866
k_IgnOnTimeout_mS_u16	13773
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	176.526093
k_PowerCutVehSpdLowThresh_Kph_f32	29.0027008
k_PowerCutVehSpdLowTimeout_mS_u16	516
k_VBattMaxAAS_Volt_f32	20.8883991
k_VBattMaxBSI_Volt_f32	18.198
k_VBattMaxCAV_Volt_f32	24.9517002
k_VBattMaxCMM388_Volt_f32	12.7504997
k_VBattMaxCMM_Volt_f32	16.7402992
k_VBattMaxESP_Volt_f32	30.1413002
k_VBattMinAAS_Volt_f32	10.3212004
k_VBattMinBSI_Volt_f32	30.1413002
k_VBattMinCAV_Volt_f32	13.1216002
k_VBattMinCMM388_Volt_f32	12.0829
k_VBattMinCMM_Volt_f32	15.0917997
k_VBattMinESP_Volt_f32	16.7402992
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	54240
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	27122
k_VitesseVehicleBVRampValidThresh_Cnt_u16	38286
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	39484
k_VitesseVehicleBVSigValidThresh_Cnt_u16	10495
k_VitesseVehicleBVSpeedPassThresh_kph_f32	178.942795
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	48288
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	63430
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	455401216
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	3700
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1274459136
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	181
target_SrlComInput_Per1_Batt_Volt_f32.value	8.5802002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2205388544
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	246
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.781361401
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	211
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3885465344
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4251918080
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1884733184
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3897450240
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	223739648
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	157
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2272108288
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	32
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4271193856
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	39
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	130
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	131
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	242
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	185
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2364235520
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	71
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	122
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	236
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	238
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3744366336
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	512106240
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2062401280
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	22
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	124
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	173
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1989218048
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3568
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.876509845
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	378735
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	16.3348999
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	42991

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1274459136	1274459136	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1274459136	1274459136	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	58752	58752	✔
AngleVolantMsgTimer_mS_M_u32	1274459136	1274459136	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1274459136	1274459136	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1274459136	1274459136	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1274459136	1274459136	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1274459136	1274459136	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1274459136	1274459136	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1274459136	1274459136	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1274459136	1274459136	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1274459136	1274459136	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1274459136	1274459136	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1274459136	1274459136	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	35629	35629	✔
CONSANGLECPK_HwDeg_M_f32	497.649414	497.649414 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	35629	35629	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2021256960	2021256960	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	2835	2835	✔
CityParkInputConsistentCount_Cnt_M_u16	41002	41002	✔
CityParkInputInvalidCount_Cnt_M_u16	20222	20222	✔
CityParkInputMsgTimer_mS_M_u32	1274459136	1274459136	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1274459136	1274459136	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1274459136	1274459136	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1274459136	1274459136	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1274459136	1274459136	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1274459136	1274459136	✔
ESPNTCEnableTimer_mS_M_u32	1274459136	1274459136	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1274459136	1274459136	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	305	305	✔
EffacDefaultDiagTimer_mS_M_u32[1]	706	706	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	12	12	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	17	17	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1274459136	1274459136	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1274459136	1274459136	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1274459136	1274459136	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1274459136	1274459136	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1274459136	1274459136	✔
ISDATDIRASentFltAcc_Cnt_M_u16	6491	6491	✔
ISDATDIRASentTimer_mS_M_u32	1274459136	1274459136	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1274459136	1274459136	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1274459136	1274459136	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1274459136	1274459136	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1274459136	1274459136	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1274459136	1274459136	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1274459136	1274459136	✔
IgnOnTimer_mS_M_u32	922058496	922058496	✔
IgnTimeOff_Sec_M_u32	2824444163	2824444163	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	211	211	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3885465344	3885465344	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	153	153	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4251918080	4251918080	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	104	104	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1884733184	1884733184	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	233	233	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3897450240	3897450240	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	122666752	122666752	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	157	157	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2272108288	2272108288	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	32	32	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4271193856	4271193856	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	185	185	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2364235520	2364235520	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	29	29	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3744366336	3744366336	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	45	45	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	512106240	512106240	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2062401280	2062401280	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1989218048	1989218048	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	620.884521	620.884521	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	398.720306	398.720306	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	39.7430992	39.7430992	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	35629	35629	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2824444163	2824444163	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	497.649414	497.649414 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.228 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	71169536
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	43052
AASNodeAbsentTimer_mS_M_u32	1296164352
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	50896
ANGLEVOLANTSigValidCount_Cnt_M_u16	13894
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	58265
AngleVolantMsgTimer_mS_M_u32	71169536
AngleVolantValidCount_Cnt_M_u16	63224
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	634758656
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2691442176
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	263099904
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2537641472
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	22151
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	678368768
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	21433
CAVNodeAbsentTimer_mS_M_u32	4144399872
CDD_SrlComVehSpd_Kph_G_f32	320.528809
CMM388NTCEnableTimer_mS_M_u32	4231972352
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	138184192
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	40200
CMMNodeAbsentTimer_mS_M_u32	4102772224
CONSANGLECPKSigInvalidCount_Cnt_M_u16	57456
CONSANGLECPKSigValidCount_Cnt_M_u16	39990
CONSANGLECPK_Cnt_M_u16	46161
CONSANGLECPK_HwDeg_M_f32	-86.3255005
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	46161
CPKVehicleSpeedMsgTimer_mS_M_u32	4037867008
CPKVehicleSpeedValidCount_Cnt_M_u16	64681
CityParkInputConsistentCount_Cnt_M_u16	57884

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	61093
CityParkInputMsgTimer_mS_M_u32	3885465344
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	23455232
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	2384
ComputerRazGCTSigInvalidTimer_mS_M_u32	2490304000
ComputerRazGCTSigValidCount_Cnt_M_u16	9153
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	40833
DMDFCTCPKSigValidCount_Cnt_M_u16	3039
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	17250
DMDRELAXECPKSigValidCount_Cnt_M_u16	23640
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	42205
DateInvalidTimer_mS_M_u32	2691442176
DiagMuxOnAbsentTimer_mS_M_u32	3125523968
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2537641472
ESPNTCEnableTimer_mS_M_u32	4103267840
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	34234
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	999
EffacDefaultDiagTimer_mS_M_u32[1]	1001
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	79
ElecIntTimer_mS_M_u32[1]	100
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2371950080
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	13030
EtatMTSigValidCount_Cnt_M_u16	25351
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	37634
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	30792
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	30485
ISDAT4V2BSI552MsgTimer_mS_M_u32	1001346560
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	15713
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	25930
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	25351
ISDATBSI3F2MsgTimer_mS_M_u32	2679748096
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	44483
ISDATBSI412MsgLenValidCount_Cnt_M_u16	26333
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	13030
ISDATBSI412MsgTimer_mS_M_u32	1336669696
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	46892
ISDATBSI432MsgLenValidCount_Cnt_M_u16	45790
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	42026
ISDATDIRASentFltAcc_Cnt_M_u16	55902
ISDATDIRASentTimer_mS_M_u32	4037867008
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	28735
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	63224
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	16568
ISDYN2CMMMsgTimer_mS_M_u32	106751488
ISDYNAASChkSumInvalidCount_Cnt_M_u16	61630
ISDYNAASChkSumValidCount_Cnt_M_u16	16211
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	65071
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	54292
ISDYNAASMsgLenValidCount_Cnt_M_u16	38305
ISDYNAASMsgTimeValidCount_Cnt_M_u16	61630
ISDYNAASMsgTimer_mS_M_u32	1109050880
ISDYNABRChkSumInvalidCount_Cnt_M_u16	47188
ISDYNABRChkSumValidCount_Cnt_M_u16	54673
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	45685
ISDYNABRMsgCountValidCount_Cnt_M_u16	44106
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	21799
ISDYNABRMsgLenValidCount_Cnt_M_u16	64557
ISDYNABRMsgTimeValidCount_Cnt_M_u16	46161
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	20631

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	17683
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	25351
ISDYNCMM208MsgTimer_mS_M_u32	3216680448
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	20631
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	17683
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	14694
ISDYNCMM388MsgTimer_mS_M_u32	2237023744
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	64990
ISDYNVOLChkSumValidCount_Cnt_M_u16	36900
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	45039
ISDYNVOLMsgCountValidCount_Cnt_M_u16	13005
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	17155
ISDYNVOLMsgLenValidCount_Cnt_M_u16	32680
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	40200
ISDYNVOLMsgTimer_mS_M_u32	1179321856
IgnOnTimer_mS_M_u32	3615114752
IgnTimeOff_Sec_M_u32	343080882
ManVehSpd_Kph_M_f32	369.080688
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	100
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3805263360
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	178
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1917163008
PrevISDATBSI412MsgDLCError_Cnt_M_u08	235
PrevISDATBSI412MsgRxTime_MSec_M_u32	1782023680
PrevISDATBSI432MsgDLCError_Cnt_M_u08	99
PrevISDATBSI432MsgRxTime_MSec_M_u32	1529275904
PrevISDATDIRAMsgTxTime_MSec_M_u32	2674624000
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	158
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2010043904
PrevISDYNAASMsgDLCError_Cnt_M_u08	125
PrevISDYNAASMsgRxTime_MSec_M_u32	3392734720
PrevISDYNABRMsgDLCError_Cnt_M_u08	135
PrevISDYNABRMsgRxTime_MSec_M_u32	3862054400
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	115
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3919447552
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	183
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1078060544
PrevISDYNVOLMsgDLCError_Cnt_M_u08	205
PrevISDYNVOLMsgRxTime_MSec_M_u32	2935260672
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	505017856
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	202.1371
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	19074
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	41615
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	65535
VitesseVehicleBVRampValidCount_Cnt_M_u16	33304
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	27417
VitesseVehicleBVSigValidCount_Cnt_M_u16	44879

Name	Input Value
VitesseVehicleBV_Kph_M_f32	425.087402
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	14694
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	3028
VitesseVehiculeRoues_Kph_M_f32	372.652893
k_AASNTCEnableTimeout_mS_u16	56064
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	22027
k_AASNodeTimeout_mS_u16	5519
k_ABSNodeTimeout_mS_u16	47398
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	2943
k_ANGLEVOLANTSigValidThresh_Cnt_u16	44913
k_AngleVolantInvalidThresh_Cnt_u16	368
k_AngleVolantValidThresh_Cnt_u16	61093
k_BSI552MsgTimeout_mS_u16	8851
k_BSINTCEnableTimeout_mS_u16	13796
k_BSINodeAbsentDiag_Cnt_str.Threshold	26907
k_BSINodeAbsentDiag_Cnt_str.PStep	51419
k_BSINodeAbsentDiag_Cnt_str.NStep	36447
k_BSINodeAbsentTimeout_mS_u16	29777
k_BSINodeTimeout_mS_u16	42026
k_BattOvHi_Volt_f32	0.172499999
k_BattOvLo_Volt_f32	6.56960011
k_BattUvHi_Volt_f32	14.3561001
k_BattUvLo_Volt_f32	12.2659998
k_CAVNTCEnableTimeout_mS_u16	29643
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	13607
k_CAVNodeTimeout_mS_u16	40524
k_CMM388MsgTimeout_mS_u16	23340
k_CMM388NTCEnableTimeout_mS_u16	14856
k_CMMNTCEnableTimeout_mS_u16	55321
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	41136
k_CONSANGLECPKMax_HwDeg_f32	159.1586
k_CONSANGLECPKMin_HwDeg_f32	-650.331116
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	27750
k_CONSANGLECPKSigValidThresh_Cnt_u16	32468
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	60357
k_CPKVehicleSpeedValidThresh_Cnt_u16	45022
k_CityParkInputInvalidThresh_Cnt_u16	37642
k_CityParkInputValidThresh_Cnt_u16	57884
k_ComputerRazGCTSigValidThresh_Cnt_u16	62199
k_CptTemporelSigValidThresh_Cnt_u16	16224
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	2087
k_DMDFCTCPKSigValidThresh_Cnt_u16	61229
k_DMDFCTCPKValidCount_Cnt_u16	35023
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	16568
k_DMDRELAXECPKSigValidThresh_Cnt_u16	63574
k_DMDRelaxeConsistentThresh_Cnt_u16	47244
k_DateValidThresh_Cnt_u16	30485
k_DefaultVehSpd_Kph_f32	238.9496
k_DiagMuxOnAbsentTimeout_mS_u16	29431
k_EMNodeTimeout_mS_u16	10301
k_ESPNTCEnableTimeout_mS_u16	45973
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	10744
k_EtatMTSigInvalidThresh_Cnt_u16	30259
k_EtatMTSigValidThresh_Cnt_u16	36016
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	27072
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	16577
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	57061
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	23022
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	49559
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	28135
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	58681

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	16555
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	4432
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	63445
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	8974
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	62857
k_ISDATDIRASentDiag_Cnt_str.Threshold	25239
k_ISDATDIRASentDiag_Cnt_str.PStep	16638
k_ISDATDIRASentDiag_Cnt_str.NStep	16248
k_ISDATDIRASentTimeout_mS_u16	5168
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	12398
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58265
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	47617
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	60244
k_ISDYNAASChkSumValidThresh_Cnt_u16	18577
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	25973
k_ISDYNAASMsgCountValidThresh_Cnt_u16	40778
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	53112
k_ISDYNAASMsgLenValidThresh_Cnt_u16	22707
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	63161
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	36245
k_ISDYNABRChkSumValidThresh_Cnt_u16	19227
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	2439
k_ISDYNABRMsgCountValidThresh_Cnt_u16	58429
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	4104
k_ISDYNABRMsgLenValidThresh_Cnt_u16	14522
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	6268
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	11686
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	53196
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	846
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	31184
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	10566
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	50013
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	662
k_ISDYNVOLChkSumValidThresh_Cnt_u16	50160
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	16423
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	49077
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	10178
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	34019
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	40123
k_IgnOnTimeout_mS_u16	37490
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	107.526199
k_PowerCutVehSpdLowThresh_Kph_f32	142.096497
k_PowerCutVehSpdLowTimeout_mS_u16	27596
k_VBattMaxAAS_Volt_f32	20.6861992
k_VBattMaxBSI_Volt_f32	9.74359989
k_VBattMaxCAV_Volt_f32	12.8470001
k_VBattMaxCMM388_Volt_f32	26.3118992
k_VBattMaxCMM_Volt_f32	3.35299993
k_VBattMaxESP_Volt_f32	25.2507992
k_VBattMinAAS_Volt_f32	22.0625992
k_VBattMinBSI_Volt_f32	25.2507992
k_VBattMinCAV_Volt_f32	11.8245001
k_VBattMinCMM388_Volt_f32	4.17700005
k_VBattMinCMM_Volt_f32	2.72329998
k_VBattMinESP_Volt_f32	3.35299993
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	5432
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	38850
k_VitesseVehicleBVRampValidThresh_Cnt_u16	58095
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	33572
k_VitesseVehicleBVSigValidThresh_Cnt_u16	56221
k_VitesseVehicleBVSpeedPassThresh_kph_f32	223.6147
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	34489
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	27142
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2691442176
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	5160
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1267377920
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	183
target_SrlComInput_Per1_Batt_Volt_f32.value	21.7098999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1044387328
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	96
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.615411758
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3449046528
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4069352960
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1079412224
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	65
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3203376640
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1985529344
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1855055360
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2946172416
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	28
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	46
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	58
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	98
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	179
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	189
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2232985088
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	39
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	161
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	228
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	47138304
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2873648640
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	62
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1016169984
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	15
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	157
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	215
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3135739392
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	648
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.633093596
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	874009
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	28.3497009

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	49356		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1267377920	1267377920	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1267377920	1267377920	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1267377920	1267377920	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1267377920	1267377920	✔
CDD_SrlComVehSpd_Kph_G_f32	369.080688	369.080688	✔
CMM388NTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1267377920	1267377920	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	46161	46161	✔
CONSANGLECPK_HwDeg_M_f32	-86.3255005	-86.3255005 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1267377920	1267377920	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1267377920	1267377920	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1267377920	1267377920	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1267377920	1267377920	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1267377920	1267377920	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1267377920	1267377920	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1267377920	1267377920	✔
ESPNTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1267377920	1267377920	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	999	999	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	1001	1001	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	79	79	✔
ElecIntTimer_mS_M_u32[1]	100	100	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1267377920	1267377920	✔
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	30485	30485	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	25351	25351	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	13030	13030	✔
ISDATBSI412MsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	42026	42026	✔
ISDATBSI432MsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDATDIRASentFltAcc_Cnt_M_u16	25239	25239	✔
ISDATDIRASentTimer_mS_M_u32	1267377920	1267377920	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	16568	16568	✔
ISDYN2CMMMsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	61630	61630	✔
ISDYNAASMsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	46161	46161	✔
ISDYNABRMsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	25351	25351	✔
ISDYNCMM208MsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	14694	14694	✔
ISDYNCMM388MsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	40200	40200	✔
ISDYNVOLMsgTimer_mS_M_u32	1267377920	1267377920	✔
IgnOnTimer_mS_M_u32	3615114752	3615114752	✔
IgnTimeOff_Sec_M_u32	343080882	343080882	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	239	239	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3449046528	3449046528	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	227	227	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4069352960	4069352960	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	251	251	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1079412224	1079412224	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	65	65	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3203376640	3203376640	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2674624000	2674624000	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	113	113	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1855055360	1855055360	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2946172416	2946172416	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	131	131	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2232985088	2232985088	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	47138304	47138304	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2873648640	2873648640	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	62	62	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1016169984	1016169984	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3135739392	3135739392	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	202.1371	202.1371	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	425.087402	425.087402	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	372.652893	372.652893	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	46161	46161	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	343080882	343080882	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-86.3255005	-86.3255005 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	369.080688	369.080688	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.229 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1245503744
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	14449
AASNodeAbsentTimer_mS_M_u32	2867925248
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	3715
ANGLEVOLANTSigValidCount_Cnt_M_u16	41443
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	31274
AngleVolantMsgTimer_mS_M_u32	1245503744
AngleVolantValidCount_Cnt_M_u16	9357
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	540397824
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	712134912
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	845873408
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1454555392
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	64350
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2317975808
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	45131
CAVNodeAbsentTimer_mS_M_u32	136524032
CDD_SrlComVehSpd_Kph_G_f32	369.588806
CMM388NTCEnableTimer_mS_M_u32	695890176
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	746664192
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	61212
CMMNodeAbsentTimer_mS_M_u32	3872702720
CONSANGLECPKSigInvalidCount_Cnt_M_u16	61604
CONSANGLECPKSigValidCount_Cnt_M_u16	57108
CONSANGLECPK_Cnt_M_u16	49859
CONSANGLECPK_HwDeg_M_f32	542.773193
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	49859
CPKVehicleSpeedMsgTimer_mS_M_u32	15720704
CPKVehicleSpeedValidCount_Cnt_M_u16	45475
CityParkInputConsistentCount_Cnt_M_u16	62241
CityParkInputInvalidCount_Cnt_M_u16	33413
CityParkInputMsgTimer_mS_M_u32	3449046528
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	512037120
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	42245

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1911140608
ComputerRazGCTSigValidCount_Cnt_M_u16	562
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	57329
DMDFCTCPKSigValidCount_Cnt_M_u16	7320
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	24781
DMDRELAXECPKSigValidCount_Cnt_M_u16	63405
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	38749
DateInvalidTimer_mS_M_u32	712134912
DiagMuxOnAbsentTimer_mS_M_u32	2400428288
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1454555392
ESPNTCEnableTimer_mS_M_u32	956174592
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	1736
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	102
EffacDefaultDiagTimer_mS_M_u32[1]	106
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	18
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2740158720
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	12932
EtatMTSigValidCount_Cnt_M_u16	13280
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	41198
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	4830
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	13046
ISDAT4V2BSI552MsgTimer_mS_M_u32	2707996928
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	47250
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	62102
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13280
ISDATBSI3F2MsgTimer_mS_M_u32	382312704
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	49259
ISDATBSI412MsgLenValidCount_Cnt_M_u16	1759
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	12932
ISDATBSI412MsgTimer_mS_M_u32	2683494656
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	12464
ISDATBSI432MsgLenValidCount_Cnt_M_u16	3932
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	49912
ISDATDIRASentFltAcc_Cnt_M_u16	61532
ISDATDIRASentTimer_mS_M_u32	15720704
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	50937
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	9357
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	38988
ISDYN2CMMMsgTimer_mS_M_u32	2879394048
ISDYNAASChkSumInvalidCount_Cnt_M_u16	9915
ISDYNAASChkSumValidCount_Cnt_M_u16	40123
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	43752
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	23354
ISDYNAASMsgLenValidCount_Cnt_M_u16	22610
ISDYNAASMsgTimeValidCount_Cnt_M_u16	9915
ISDYNAASMsgTimer_mS_M_u32	3353768192
ISDYNABRChkSumInvalidCount_Cnt_M_u16	65401
ISDYNABRChkSumValidCount_Cnt_M_u16	43393
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	32150
ISDYNABRMsgCountValidCount_Cnt_M_u16	61910
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	11903
ISDYNABRMsgLenValidCount_Cnt_M_u16	23343
ISDYNABRMsgTimeValidCount_Cnt_M_u16	49859
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	29238
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	32275
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13280
ISDYNCMM208MsgTimer_mS_M_u32	646369536
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	29238
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	32275
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	38211

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1278472448
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	53338
ISDYNVOLChkSumValidCount_Cnt_M_u16	15178
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	59047
ISDYNVOLMsgCountValidCount_Cnt_M_u16	57294
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	13037
ISDYNVOLMsgLenValidCount_Cnt_M_u16	7868
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	61212
ISDYNVOLMsgTimer_mS_M_u32	3428167936
IgnOnTimer_mS_M_u32	3855085824
IgnTimeOff_Sec_M_u32	805494139
ManVehSpd_Kph_M_f32	172.015594
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	101
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	45
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	629645568
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	0
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	648413440
PrevISDATBSI412MsgDLCError_Cnt_M_u08	123
PrevISDATBSI412MsgRxTime_MSec_M_u32	2995794176
PrevISDATBSI432MsgDLCError_Cnt_M_u08	120
PrevISDATBSI432MsgRxTime_MSec_M_u32	1430393088
PrevISDATDIRAMsgTxTime_MSec_M_u32	3807654144
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	177
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3406446848
PrevISDYNAASMsgDLCError_Cnt_M_u08	150
PrevISDYNAASMsgRxTime_MSec_M_u32	2022420736
PrevISDYNABRMsgDLCError_Cnt_M_u08	126
PrevISDYNABRMsgRxTime_MSec_M_u32	2577395968
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	88
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3999052032
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	44
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3522236672
PrevISDYNVOLMsgDLCError_Cnt_M_u08	51
PrevISDYNVOLMsgRxTime_MSec_M_u32	408498432
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1823006976
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	340.189911
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	12272
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	27016
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	15196
VitesseVehicleBVRampValidCount_Cnt_M_u16	12013
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	34216
VitesseVehicleBVSigValidCount_Cnt_M_u16	39624
VitesseVehicleBV_Kph_M_f32	345.625488
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	38211
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	57274
VitesseVehiculeRoues_Kph_M_f32	609.328003
k_AASNTCEnableTimeout_mS_u16	51894
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	4948
k_AASNodeTimeout_mS_u16	4232
k_ABSNodeTimeout_mS_u16	26370
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	16311
k_ANGLEVOLANTSigValidThresh_Cnt_u16	9635
k_AngleVolantInvalidThresh_Cnt_u16	60326
k_AngleVolantValidThresh_Cnt_u16	33413
k_BSI552MsgTimeout_mS_u16	22397
k_BSINTCEnableTimeout_mS_u16	38024
k_BSINodeAbsentDiag_Cnt_str.Threshold	5597
k_BSINodeAbsentDiag_Cnt_str.PStep	24603
k_BSINodeAbsentDiag_Cnt_str.NStep	56894
k_BSINodeAbsentTimeout_mS_u16	43010
k_BSINodeTimeout_mS_u16	49912
k_BattOvHi_Volt_f32	26.1699009
k_BattOvLo_Volt_f32	20.530899
k_BattUvHi_Volt_f32	9.58100033
k_BattUvLo_Volt_f32	22.1671009
k_CAVNTCEnableTimeout_mS_u16	2835
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	17409
k_CAVNodeTimeout_mS_u16	10000
k_CMM388MsgTimeout_mS_u16	8049
k_CMM388NTCEnableTimeout_mS_u16	62173
k_CMMNTCEnableTimeout_mS_u16	51306
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	37158
k_CONSANGLECPKMax_HwDeg_f32	245.449402
k_CONSANGLECPKMin_HwDeg_f32	-147.867798
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	64579
k_CONSANGLECPKSigValidThresh_Cnt_u16	34490
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	58854
k_CPKVehicleSpeedValidThresh_Cnt_u16	58906
k_CityParkInputInvalidThresh_Cnt_u16	51031
k_CityParkInputValidThresh_Cnt_u16	62241
k_ComputerRazGCTSigValidThresh_Cnt_u16	28624
k_CptTemporelSigValidThresh_Cnt_u16	15444
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	5503
k_DMDFCTCPKSigValidThresh_Cnt_u16	33327
k_DMDFCTCPKValidCount_Cnt_u16	33926
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	38988
k_DMDRELAXECPKSigValidThresh_Cnt_u16	62259
k_DMDRelaxeConsistentThresh_Cnt_u16	2705
k_DateValidThresh_Cnt_u16	13046
k_DefaultVehSpd_Kph_f32	70.6151962
k_DiagMuxOnAbsentTimeout_mS_u16	40657
k_EMNodeTimeout_mS_u16	36157
k_ESPNTCEnableTimeout_mS_u16	183
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	5454
k_EtatMTSigInvalidThresh_Cnt_u16	476
k_EtatMTSigValidThresh_Cnt_u16	49188
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	6133
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	42160
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	24774
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	55019
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	20911
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	4095
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	6793
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	55797
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	45636
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	2103
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	30795
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	53785
k_ISDATDIRASentDiag_Cnt_str.Threshold	60800

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	27554
k_ISDATDIRASentDiag_Cnt_str.NStep	30413
k_ISDATDIRASentTimeout_mS_u16	23525
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	62826
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	31274
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	40307
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	26233
k_ISDYNAASChkSumValidThresh_Cnt_u16	20609
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	25750
k_ISDYNAASMsgCountValidThresh_Cnt_u16	6358
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	18957
k_ISDYNAASMsgLenValidThresh_Cnt_u16	55068
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	28619
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	48437
k_ISDYNABRChkSumValidThresh_Cnt_u16	42597
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	57950
k_ISDYNABRMsgCountValidThresh_Cnt_u16	13310
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	38428
k_ISDYNABRMsgLenValidThresh_Cnt_u16	60872
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	21313
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	5764
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	48720
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	843
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	62851
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	51427
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	58461
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	52722
k_ISDYNVOLChkSumValidThresh_Cnt_u16	64422
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	52097
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	31509
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	50160
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	15948
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	55812
k_IgnOnTimeout_mS_u16	36446
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	39.3852997
k_PowerCutVehSpdLowThresh_Kph_f32	135.674301
k_PowerCutVehSpdLowTimeout_mS_u16	18514
k_VBattMaxAAS_Volt_f32	13.9268999
k_VBattMaxBSI_Volt_f32	4.79580021
k_VBattMaxCAV_Volt_f32	24.3929996
k_VBattMaxCMM388_Volt_f32	20.4141006
k_VBattMaxCMM_Volt_f32	23.2586002
k_VBattMaxESP_Volt_f32	2.26349998
k_VBattMinAAS_Volt_f32	1.77330005
k_VBattMinBSI_Volt_f32	2.26349998
k_VBattMinCAV_Volt_f32	4.99849987
k_VBattMinCMM388_Volt_f32	27.2318001
k_VBattMinCMM_Volt_f32	8.87339973
k_VBattMinESP_Volt_f32	23.2586002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	61196
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	39215
k_VitesseVehicleBVRampValidThresh_Cnt_u16	19879
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	25162
k_VitesseVehicleBVSigValidThresh_Cnt_u16	19102
k_VitesseVehicleBVSpeedPassThresh_kph_f32	250.759506
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	5963
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	44835
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	712134912
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	38458
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3227176448
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	44
target_SrlComInput_Per1_Batt_Volt_f32.value	12.6782999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3434512640
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	243
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.959873676
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	214
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3950637312
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1225691392
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1815294208
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1021825280
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2737598720
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2264994048
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3496325376
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	124
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	150
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	193
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3463237888
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	227
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	207
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4157141248
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3403518208
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	47
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	595734784
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	55
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	119
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	126
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	161
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	218
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	234
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1421869312
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1158
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0614137165
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	197529
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	164.164795
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	29970

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3227176448	3227176448	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3227176448	3227176448	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3227176448	3227176448	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3227176448	3227176448	✔
CDD_SrlComVehSpd_Kph_G_f32	172.015594	172.015594	✔
CMM388NTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3227176448	3227176448	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	49859	49859	✔
CONSANGLECPK_HwDeg_M_f32	542.773193	542.773193 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3227176448	3227176448	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3227176448	3227176448	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3227176448	3227176448	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3227176448	3227176448	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3227176448	3227176448	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3227176448	3227176448	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3227176448	3227176448	✔
ESPNTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3227176448	3227176448	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	102	102	✔
EffacDefaultDiagTimer_mS_M_u32[1]	106	106	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	6	6	✔
ElecIntTimer_mS_M_u32[1]	18	18	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3227176448	3227176448	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	13046	13046	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13280	13280	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	12932	12932	✔
ISDATBSI412MsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	49912	49912	✔
ISDATBSI432MsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDATDIRASentFltAcc_Cnt_M_u16	60800	60800	✔
ISDATDIRASentTimer_mS_M_u32	3227176448	3227176448	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	38988	38988	✔
ISDYN2CMMMsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	9915	9915	✔
ISDYNAASMsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	49859	49859	✔
ISDYNABRMsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13280	13280	✔
ISDYNCMM208MsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	38211	38211	✔
ISDYNCMM388MsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	61212	61212	✔
ISDYNVOLMsgTimer_mS_M_u32	3227176448	3227176448	✔
IgnOnTimer_mS_M_u32	3855085824	3855085824	✔
IgnTimeOff_Sec_M_u32	805494139	805494139	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	214	214	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3950637312	3950637312	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1225691392	1225691392	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	75	75	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1815294208	1815294208	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1021825280	1021825280	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3807654144	3807654144	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	174	174	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2264994048	2264994048	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	40	40	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3496325376	3496325376	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	67	67	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3463237888	3463237888	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	207	207	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4157141248	4157141248	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	183	183	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3403518208	3403518208	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	47	47	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	595734784	595734784	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1421869312	1421869312	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	340.189911	340.189911	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	345.625488	345.625488	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	609.328003	609.328003	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	49859	49859	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	805494139	805494139	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	542.773193	542.773193 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.230 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1839996928
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	5390
AASNodeAbsentTimer_mS_M_u32	2555351040
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	64727
ANGLEVOLANTSigValidCount_Cnt_M_u16	40312
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	29667
AngleVolantMsgTimer_mS_M_u32	1839996928
AngleVolantValidCount_Cnt_M_u16	51003
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	998330368
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2932592640
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2510405632
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4157243392
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	25158
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2825273344
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	15872
CAVNodeAbsentTimer_mS_M_u32	1899573248
CDD_SrlComVehSpd_Kph_G_f32	356.809601
CMM388NTCEnableTimer_mS_M_u32	2050191360
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4229902336
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	12621
CMMNodeAbsentTimer_mS_M_u32	1331986432
CONSANGLECPKSigInvalidCount_Cnt_M_u16	51572
CONSANGLECPKSigValidCount_Cnt_M_u16	39141
CONSANGLECPK_Cnt_M_u16	27096
CONSANGLECPK_HwDeg_M_f32	-415.106812
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	27096
CPKVehicleSpeedMsgTimer_mS_M_u32	3583188992
CPKVehicleSpeedValidCount_Cnt_M_u16	58751
CityParkInputConsistentCount_Cnt_M_u16	43903
CityParkInputInvalidCount_Cnt_M_u16	56915
CityParkInputMsgTimer_mS_M_u32	3950637312
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2375258112
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	8018

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1843769344
ComputerRazGCTSigValidCount_Cnt_M_u16	588
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	30223
DMDFCTCPKSigValidCount_Cnt_M_u16	15063
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	44537
DMDRELAXECPKSigValidCount_Cnt_M_u16	17434
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	63817
DateInvalidTimer_mS_M_u32	2932592640
DiagMuxOnAbsentTimer_mS_M_u32	1780998144
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4157243392
ESPNTCEnableTimer_mS_M_u32	1646825472
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	29962
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	89
EffacDefaultDiagTimer_mS_M_u32[1]	789
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	88
ElecIntTimer_mS_M_u32[1]	110
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2229813248
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	22548
EtatMTSigValidCount_Cnt_M_u16	40641
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24726
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	42375
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	61373
ISDAT4V2BSI552MsgTimer_mS_M_u32	1873313792
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	54635
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	4640
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	40641
ISDATBSI3F2MsgTimer_mS_M_u32	721805312
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	45791
ISDATBSI412MsgLenValidCount_Cnt_M_u16	35396
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	22548
ISDATBSI412MsgTimer_mS_M_u32	3297386496
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	48273
ISDATBSI432MsgLenValidCount_Cnt_M_u16	43854
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	63993
ISDATDIRASentFltAcc_Cnt_M_u16	461
ISDATDIRASentTimer_mS_M_u32	3583188992
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	46390
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	51003
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	30974
ISDYN2CMMMsgTimer_mS_M_u32	306352128
ISDYNAASChkSumInvalidCount_Cnt_M_u16	62000
ISDYNAASChkSumValidCount_Cnt_M_u16	27377
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	24618
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	47411
ISDYNAASMsgLenValidCount_Cnt_M_u16	64684
ISDYNAASMsgTimeValidCount_Cnt_M_u16	62000
ISDYNAASMsgTimer_mS_M_u32	1324314624
ISDYNABRChkSumInvalidCount_Cnt_M_u16	55669
ISDYNABRChkSumValidCount_Cnt_M_u16	54814
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	6559
ISDYNABRMsgCountValidCount_Cnt_M_u16	38816
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	15331
ISDYNABRMsgLenValidCount_Cnt_M_u16	20628
ISDYNABRMsgTimeValidCount_Cnt_M_u16	27096
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	64863
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	44166
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	40641
ISDYNCMM208MsgTimer_mS_M_u32	2895007744
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	64863
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	44166
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	52505

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3624333312
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	33362
ISDYNVOLChkSumValidCount_Cnt_M_u16	56387
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	47597
ISDYNVOLMsgCountValidCount_Cnt_M_u16	18741
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	50331
ISDYNVOLMsgLenValidCount_Cnt_M_u16	7148
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	12621
ISDYNVOLMsgTimer_mS_M_u32	245477376
IgnOnTimer_mS_M_u32	1531637760
IgnTimeOff_Sec_M_u32	2645965124
ManVehSpd_Kph_M_f32	448.941589
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	102
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	247
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1993072640
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	6
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1693499392
PrevISDATBSI412MsgDLCError_Cnt_M_u08	36
PrevISDATBSI412MsgRxTime_MSec_M_u32	1710370816
PrevISDATBSI432MsgDLCError_Cnt_M_u08	253
PrevISDATBSI432MsgRxTime_MSec_M_u32	492605440
PrevISDATDIRAMsgTxTime_MSec_M_u32	1690710016
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	150
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1489240064
PrevISDYNAASMsgDLCError_Cnt_M_u08	94
PrevISDYNAASMsgRxTime_MSec_M_u32	1644146688
PrevISDYNABRMsgDLCError_Cnt_M_u08	153
PrevISDYNABRMsgRxTime_MSec_M_u32	2680352768
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	43
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2223812608
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	209
PrevISDYNCMM388MsgRxTime_MSec_M_u32	592416768
PrevISDYNVOLMsgDLCError_Cnt_M_u08	230
PrevISDYNVOLMsgRxTime_MSec_M_u32	2560045056
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3060277248
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	286.049011
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	37649
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	8458
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	48162
VitesseVehicleBVRampValidCount_Cnt_M_u16	42203
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	27496
VitesseVehicleBVSigValidCount_Cnt_M_u16	34505
VitesseVehicleBV_Kph_M_f32	215.901703
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	52505
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	43122
VitesseVehiculeRoues_Kph_M_f32	418.27771
k_AASNTCEnableTimeout_mS_u16	56831
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	55014
k_AASNodeTimeout_mS_u16	11274
k_ABSNodeTimeout_mS_u16	25820
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	27516
k_ANGLEVOLANTSigValidThresh_Cnt_u16	17529
k_AngleVolantInvalidThresh_Cnt_u16	48752
k_AngleVolantValidThresh_Cnt_u16	56915
k_BSI552MsgTimeout_mS_u16	3369
k_BSINTCEnableTimeout_mS_u16	61705
k_BSINodeAbsentDiag_Cnt_str.Threshold	26601
k_BSINodeAbsentDiag_Cnt_str.PStep	9838
k_BSINodeAbsentDiag_Cnt_str.NStep	55623
k_BSINodeAbsentTimeout_mS_u16	19035
k_BSINodeTimeout_mS_u16	63993
k_BattOvHi_Volt_f32	14.2467003
k_BattOvLo_Volt_f32	23.0070992
k_BattUvHi_Volt_f32	18.6277008
k_BattUvLo_Volt_f32	26.9216995
k_CAVNTCEnableTimeout_mS_u16	64681
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	56030
k_CAVNodeTimeout_mS_u16	54832
k_CMM388MsgTimeout_mS_u16	24590
k_CMM388NTCEnableTimeout_mS_u16	38346
k_CMMNTCEnableTimeout_mS_u16	1507
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	17454
k_CONSANGLECPKMax_HwDeg_f32	466.836609
k_CONSANGLECPKMin_HwDeg_f32	-24.8533993
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	38937
k_CONSANGLECPKSigValidThresh_Cnt_u16	45938
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	41968
k_CPKVehicleSpeedValidThresh_Cnt_u16	48594
k_CityParkInputInvalidThresh_Cnt_u16	31195
k_CityParkInputValidThresh_Cnt_u16	43903
k_ComputerRazGCTSigValidThresh_Cnt_u16	10161
k_CptTemporelSigValidThresh_Cnt_u16	44262
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	34531
k_DMDFCTCPKSigValidThresh_Cnt_u16	56212
k_DMDFCTCPKValidCount_Cnt_u16	26318
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	30974
k_DMDRELAXECPKSigValidThresh_Cnt_u16	58118
k_DMDRelaxeConsistentThresh_Cnt_u16	38124
k_DateValidThresh_Cnt_u16	61373
k_DefaultVehSpd_Kph_f32	67.0400009
k_DiagMuxOnAbsentTimeout_mS_u16	36270
k_EMNodeTimeout_mS_u16	38825
k_ESPNTCEnableTimeout_mS_u16	64700
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	22454
k_EtatMTSigInvalidThresh_Cnt_u16	7756
k_EtatMTSigValidThresh_Cnt_u16	56885
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	2499
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	11856
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	13968
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	7776
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	39125
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	5155
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	41734
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	61315
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	34773
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	27004
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	17409
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	49879
k_ISDATDIRASentDiag_Cnt_str.Threshold	35056

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	8835
k_ISDATDIRASentDiag_Cnt_str.NStep	19771
k_ISDATDIRASentTimeout_mS_u16	29745
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	56548
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	29667
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	5768
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	42101
k_ISDYNAASChkSumValidThresh_Cnt_u16	57630
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	25759
k_ISDYNAASMsgCountValidThresh_Cnt_u16	8864
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	18873
k_ISDYNAASMsgLenValidThresh_Cnt_u16	10318
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	1537
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	59329
k_ISDYNABRChkSumValidThresh_Cnt_u16	50930
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	44358
k_ISDYNABRMsgCountValidThresh_Cnt_u16	4903
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	15437
k_ISDYNABRMsgLenValidThresh_Cnt_u16	49162
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	33118
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	12117
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	36144
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	8129
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	18391
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	10360
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	6347
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	26186
k_ISDYNVOLChkSumValidThresh_Cnt_u16	34799
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	19167
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	45410
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	21456
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	12157
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	45715
k_IgnOnTimeout_mS_u16	54534
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	157.229996
k_PowerCutVehSpdLowThresh_Kph_f32	36.3628006
k_PowerCutVehSpdLowTimeout_mS_u16	54571
k_VBattMaxAAS_Volt_f32	4.73969984
k_VBattMaxBSI_Volt_f32	26.0100002
k_VBattMaxCAV_Volt_f32	12.4968004
k_VBattMaxCMM388_Volt_f32	14.1855001
k_VBattMaxCMM_Volt_f32	5.74840021
k_VBattMaxESP_Volt_f32	0.639100015
k_VBattMinAAS_Volt_f32	32
k_VBattMinBSI_Volt_f32	0.639100015
k_VBattMinCAV_Volt_f32	6.06610012
k_VBattMinCMM388_Volt_f32	7.49289989
k_VBattMinCMM_Volt_f32	31.7275009
k_VBattMinESP_Volt_f32	5.74840021
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	63486
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	25683
k_VitesseVehicleBVRampValidThresh_Cnt_u16	34029
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	26435
k_VitesseVehicleBVSigValidThresh_Cnt_u16	55560
k_VitesseVehicleBVSpeedPassThresh_kph_f32	629.332214
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	2304
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	31801
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2932592640
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	1664
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	927357184
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	209
target_SrlComInput_Per1_Batt_Volt_f32.value	26.7007008
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1421819904
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	55
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.381654501
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2452942848
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	97
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	334958592
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2231971840
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	762007552
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1427992576
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1142919168
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1114746880
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	54
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	147
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	149
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	176
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	190
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	226
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	24
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3436990464
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	36
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	156
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	157
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	184
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1766322176
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	176
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2324303872
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1528573952
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	52
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	91
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	115
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	213
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	226
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3265445888
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2904
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.333145976
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	338395
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	121.141403
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	52139

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	927357184	927357184	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	927357184	927357184	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	29669	29669	✔
AngleVolantMsgTimer_mS_M_u32	927357184	927357184	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	927357184	927357184	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	927357184	927357184	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	927357184	927357184	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	927357184	927357184	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	927357184	927357184	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	927357184	927357184	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	927357184	927357184	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	927357184	927357184	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	927357184	927357184	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	927357184	927357184	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	27096	27096	✔
CONSANGLECPK_HwDeg_M_f32	-415.106812	-415.106812 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	27096	27096	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3583188992	3583188992	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	58751	58751	✔
CityParkInputConsistentCount_Cnt_M_u16	43903	43903	✔
CityParkInputInvalidCount_Cnt_M_u16	56915	56915	✔
CityParkInputMsgTimer_mS_M_u32	927357184	927357184	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	927357184	927357184	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	927357184	927357184	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	927357184	927357184	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	927357184	927357184	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	927357184	927357184	✔
ESPNTCEnableTimer_mS_M_u32	927357184	927357184	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	927357184	927357184	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	89	89	✔
EffacDefaultDiagTimer_mS_M_u32[1]	789	789	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	927357184	927357184	✔
ElecIntTimer_mS_M_u32[1]	110	110	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	927357184	927357184	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	927357184	927357184	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	927357184	927357184	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	927357184	927357184	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	927357184	927357184	✔
ISDATDIRASentFltAcc_Cnt_M_u16	35056	35056	✔
ISDATDIRASentTimer_mS_M_u32	927357184	927357184	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	927357184	927357184	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	927357184	927357184	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	927357184	927357184	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	927357184	927357184	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	927357184	927357184	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	927357184	927357184	✔
IgnOnTimer_mS_M_u32	1531637760	1531637760	✔
IgnTimeOff_Sec_M_u32	2645965124	2645965124	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	220	220	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2452942848	2452942848	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	97	97	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	334958592	334958592	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	178	178	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2231971840	2231971840	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	21	21	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	762007552	762007552	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1690710016	1690710016	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	55	55	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1142919168	1142919168	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	132	132	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1114746880	1114746880	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	24	24	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3436990464	3436990464	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	235	235	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1766322176	1766322176	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	176	176	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2324303872	2324303872	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	0	0	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1528573952	1528573952	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3265445888	3265445888	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	286.049011	286.049011	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	215.901703	215.901703	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	418.27771	418.27771	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	27096	27096	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2645965124	2645965124	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-415.106812	-415.106812 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.231 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3541721856
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	34546
AASNodeAbsentTimer_mS_M_u32	1827672832
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	37273
ANGLEVOLANTSigValidCount_Cnt_M_u16	40822
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	65139
AngleVolantMsgTimer_mS_M_u32	3541721856
AngleVolantValidCount_Cnt_M_u16	3307
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2052772608
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1786467072
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3115942656
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	641680128
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	56652
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	862716672
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	23198
CAVNodeAbsentTimer_mS_M_u32	280179456
CDD_SrlComVehSpd_Kph_G_f32	443.178711
CMM388NTCEnableTimer_mS_M_u32	2932110080
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2281779968
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	29046
CMMNodeAbsentTimer_mS_M_u32	124863232
CONSANGLECPKSigInvalidCount_Cnt_M_u16	53952
CONSANGLECPKSigValidCount_Cnt_M_u16	37933
CONSANGLECPK_Cnt_M_u16	44372
CONSANGLECPK_HwDeg_M_f32	743.471985
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	44372
CPKVehicleSpeedMsgTimer_mS_M_u32	4150616832
CPKVehicleSpeedValidCount_Cnt_M_u16	33160
CityParkInputConsistentCount_Cnt_M_u16	28703
CityParkInputInvalidCount_Cnt_M_u16	13477
CityParkInputMsgTimer_mS_M_u32	2452942848
CityParkInputValidCount_Cnt_M_u16	8

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2636387072
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	30758
ComputerRazGCTSigInvalidTimer_mS_M_u32	1823322880
ComputerRazGCTSigValidCount_Cnt_M_u16	57272
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	23921
DMDFCTCPKSigValidCount_Cnt_M_u16	40662
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	34355
DMDRELAXECPKSigValidCount_Cnt_M_u16	45968
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	55105
DateInvalidTimer_mS_M_u32	1786467072
DiagMuxOnAbsentTimer_mS_M_u32	2091328256
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	641680128
ESPNTCEnableTimer_mS_M_u32	3009745664
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	1535
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	99
EffacDefaultDiagTimer_mS_M_u32[1]	759
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	12
ElecIntTimer_mS_M_u32[1]	18
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	635831040
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	10784
EtatMTSigValidCount_Cnt_M_u16	30169
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	5466
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	30279
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	38948
ISDAT4V2BSI552MsgTimer_mS_M_u32	3064283904
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	33693
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	3390
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	30169
ISDATBSI3F2MsgTimer_mS_M_u32	839721728
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	3136
ISDATBSI412MsgLenValidCount_Cnt_M_u16	34258
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	10784
ISDATBSI412MsgTimer_mS_M_u32	3330302720
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	57258
ISDATBSI432MsgLenValidCount_Cnt_M_u16	29491
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	19123
ISDATDIRASentFltAcc_Cnt_M_u16	33591
ISDATDIRASentTimer_mS_M_u32	4150616832
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	49978
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	3307
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	53412
ISDYN2CMMMsgTimer_mS_M_u32	2333545216
ISDYNAASChkSumInvalidCount_Cnt_M_u16	63372
ISDYNAASChkSumValidCount_Cnt_M_u16	64778
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	48670
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	29957
ISDYNAASMsgLenValidCount_Cnt_M_u16	64090
ISDYNAASMsgTimeValidCount_Cnt_M_u16	63372
ISDYNAASMsgTimer_mS_M_u32	546337536
ISDYNABRChkSumInvalidCount_Cnt_M_u16	60734
ISDYNABRChkSumValidCount_Cnt_M_u16	1795
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	64831
ISDYNABRMsgCountValidCount_Cnt_M_u16	62205
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	63347
ISDYNABRMsgLenValidCount_Cnt_M_u16	59680
ISDYNABRMsgTimeValidCount_Cnt_M_u16	44372
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	14893
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	13324
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	30169
ISDYNCMM208MsgTimer_mS_M_u32	2603864832

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	14893
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	13324
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	62289
ISDYNCMM388MsgTimer_mS_M_u32	1128919808
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	40998
ISDYNVOLChkSumValidCount_Cnt_M_u16	49683
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	35287
ISDYNVOLMsgCountValidCount_Cnt_M_u16	27580
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	39756
ISDYNVOLMsgLenValidCount_Cnt_M_u16	17689
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	29046
ISDYNVOLMsgTimer_mS_M_u32	2054796032
IgnOnTimer_mS_M_u32	3380474624
IgnTimeOff_Sec_M_u32	2371744905
ManVehSpd_Kph_M_f32	355.865204
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	103
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	153
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3871023872
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	213
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1204585216
PrevISDATBSI412MsgDLCError_Cnt_M_u08	202
PrevISDATBSI412MsgRxTime_MSec_M_u32	1451766528
PrevISDATBSI432MsgDLCError_Cnt_M_u08	210
PrevISDATBSI432MsgRxTime_MSec_M_u32	1372132096
PrevISDATDIRAMsgTxTime_MSec_M_u32	2852926208
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	65
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3377644288
PrevISDYNAASMsgDLCError_Cnt_M_u08	126
PrevISDYNAASMsgRxTime_MSec_M_u32	2019537664
PrevISDYNABRMsgDLCError_Cnt_M_u08	247
PrevISDYNABRMsgRxTime_MSec_M_u32	3692425984
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	225
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2226696960
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	137
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3421508352
PrevISDYNVOLMsgDLCError_Cnt_M_u08	203
PrevISDYNVOLMsgRxTime_MSec_M_u32	2459513600
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3907412736
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	475.992706
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57195
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	34112
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	59448
VitesseVehicleBVRampValidCount_Cnt_M_u16	32205
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	51686
VitesseVehicleBVSigValidCount_Cnt_M_u16	26499
VitesseVehicleBV_Kph_M_f32	191.615601
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	62289
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	12550

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	542.077576
k_AASNTCEnableTimeout_mS_u16	44255
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	18922
k_AASNodeTimeout_mS_u16	25664
k_ABSNodeTimeout_mS_u16	1290
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	16105
k_ANGLEVOLANTSigValidThresh_Cnt_u16	5042
k_AngleVolantInvalidThresh_Cnt_u16	16845
k_AngleVolantValidThresh_Cnt_u16	13477
k_BSI552MsgTimeout_mS_u16	40673
k_BSINTCEnableTimeout_mS_u16	8770
k_BSINodeAbsentDiag_Cnt_str.Threshold	64518
k_BSINodeAbsentDiag_Cnt_str.PStep	48436
k_BSINodeAbsentDiag_Cnt_str.NStep	13653
k_BSINodeAbsentTimeout_mS_u16	23307
k_BSINodeTimeout_mS_u16	19123
k_BattOvHi_Volt_f32	4.15250015
k_BattOvLo_Volt_f32	2.34159994
k_BattUvHi_Volt_f32	29.6669006
k_BattUvLo_Volt_f32	29.1278992
k_CAVNTCEnableTimeout_mS_u16	45475
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	31748
k_CAVNodeTimeout_mS_u16	40076
k_CMM388MsgTimeout_mS_u16	42482
k_CMM388NTCEnableTimeout_mS_u16	62654
k_CMMNTCEnableTimeout_mS_u16	53813
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	19922
k_CONSANGLECPKMax_HwDeg_f32	460.833496
k_CONSANGLECPKMin_HwDeg_f32	-62.1716995
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	37457
k_CONSANGLECPKSigValidThresh_Cnt_u16	4102
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	5262
k_CPKVehicleSpeedValidThresh_Cnt_u16	30567
k_CityParkInputInvalidThresh_Cnt_u16	9228
k_CityParkInputValidThresh_Cnt_u16	28703
k_ComputerRazGCTSigValidThresh_Cnt_u16	9419
k_CptTemporelSigValidThresh_Cnt_u16	54508
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	5747
k_DMDFCTCPKSigValidThresh_Cnt_u16	18464
k_DMDFCTCPKValidCount_Cnt_u16	61364
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	53412
k_DMDRELAXECPKSigValidThresh_Cnt_u16	8777
k_DMDRelaxeConsistentThresh_Cnt_u16	9367
k_DateValidThresh_Cnt_u16	38948
k_DefaultVehSpd_Kph_f32	243.5
k_DiagMuxOnAbsentTimeout_mS_u16	6610
k_EMNodeTimeout_mS_u16	31777
k_ESPNTCEnableTimeout_mS_u16	3690
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	13114
k_EtatMTSigInvalidThresh_Cnt_u16	15033
k_EtatMTSigValidThresh_Cnt_u16	2750
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	61205
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	8494
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	21228
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	48318
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	36127
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	63604
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	16459
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	47764
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	36318
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	15976

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	11929
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	3416
k_ISDATDIRASentDiag_Cnt_str.Threshold	45598
k_ISDATDIRASentDiag_Cnt_str.PStep	35197
k_ISDATDIRASentDiag_Cnt_str.NStep	1197
k_ISDATDIRASentTimeout_mS_u16	3338
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	13105
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	65139
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	61702
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	35902
k_ISDYNAASChkSumValidThresh_Cnt_u16	58883
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	7231
k_ISDYNAASMsgCountValidThresh_Cnt_u16	20989
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	44146
k_ISDYNAASMsgLenValidThresh_Cnt_u16	32628
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	61210
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	60377
k_ISDYNABRChkSumValidThresh_Cnt_u16	32262
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	64588
k_ISDYNABRMsgCountValidThresh_Cnt_u16	47721
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	20598
k_ISDYNABRMsgLenValidThresh_Cnt_u16	9471
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	3012
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	6815
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	333
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	9499
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	45209
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	65142
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	25917
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	24063
k_ISDYNVOLChkSumValidThresh_Cnt_u16	63697
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	6272
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	34103
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	9964
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	45989
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	10146
k_IgnOnTimeout_mS_u16	459
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	239.430206
k_PowerCutVehSpdLowThresh_Kph_f32	98.0317993
k_PowerCutVehSpdLowTimeout_mS_u16	30555
k_VBattMaxAAS_Volt_f32	11.3843002
k_VBattMaxBSI_Volt_f32	31.9424
k_VBattMaxCAV_Volt_f32	2.64709997
k_VBattMaxCMM388_Volt_f32	28.3251991
k_VBattMaxCMM_Volt_f32	20.3463993
k_VBattMaxESP_Volt_f32	8.95860004
k_VBattMinAAS_Volt_f32	21.5624008
k_VBattMinBSI_Volt_f32	8.95860004
k_VBattMinCAV_Volt_f32	17.7821007
k_VBattMinCMM388_Volt_f32	7.12069988
k_VBattMinCMM_Volt_f32	26.9393997
k_VBattMinESP_Volt_f32	20.3463993
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	51683
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	17572
k_VitesseVehicleBVRampValidThresh_Cnt_u16	10455
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	8467
k_VitesseVehicleBVSigValidThresh_Cnt_u16	19332
k_VitesseVehicleBVSpeedPassThresh_kph_f32	533.847229
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	63902
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	61363
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1786467072
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	49721
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3262101504
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSe	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	137
target_SrlComInput_Per1_Batt_Volt_f32.value	13.8505001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3529573120
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	43
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.587200999
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1287648000
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	78
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4160328448
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	356725504
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	19
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3432829696
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1174827776
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2843742976
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	520729344
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	44
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	154
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	162
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	208
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4064924416
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	57
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	128
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	163
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	239
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3548836608
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2688586496
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	78
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2668245760
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	12
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	176
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	199
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1991672576
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1666
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.357446462
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	842041
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	100.946098
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	7581

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3262101504	3262101504	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3262101504	3262101504	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3262101504	3262101504	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3262101504	3262101504	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3262101504	3262101504	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3262101504	3262101504	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3262101504	3262101504	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3262101504	3262101504	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3262101504	3262101504	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3262101504	3262101504	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3262101504	3262101504	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3262101504	3262101504	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3262101504	3262101504	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	44372	44372	✔
CONSANGLECPK_HwDeg_M_f32	743.471985	743.471985 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3262101504	3262101504	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3262101504	3262101504	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3262101504	3262101504	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3262101504	3262101504	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3262101504	3262101504	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3262101504	3262101504	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3262101504	3262101504	✔
ESPNTCEnableTimer_mS_M_u32	3262101504	3262101504	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3262101504	3262101504	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3262101504	3262101504	✔
EffacDefaultDiagTimer_mS_M_u32[1]	759	759	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3262101504	3262101504	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	18	18	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3262101504	3262101504	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3262101504	3262101504	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3262101504	3262101504	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3262101504	3262101504	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3262101504	3262101504	✔
ISDATDIRASentFltAcc_Cnt_M_u16	45598	45598	✔
ISDATDIRASentTimer_mS_M_u32	3262101504	3262101504	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3262101504	3262101504	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3262101504	3262101504	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3262101504	3262101504	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3262101504	3262101504	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3262101504	3262101504	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3262101504	3262101504	✔
IgnOnTimer_mS_M_u32	3380474624	3380474624	✔
IgnTimeOff_Sec_M_u32	2371744905	2371744905	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	77	77	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1287648000	1287648000	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	78	78	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4160328448	4160328448	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	45	45	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	356725504	356725504	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	19	19	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3432829696	3432829696	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2852926208	2852926208	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	144	144	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2843742976	2843742976	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	119	119	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	520729344	520729344	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	16	16	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4064924416	4064924416	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3548836608	3548836608	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	110	110	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2688586496	2688586496	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	78	78	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2668245760	2668245760	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1991672576	1991672576	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	475.992706	475.992706	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	191.615601	191.615601	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	542.077576	542.077576	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	44372	44372	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2371744905	2371744905	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	743.471985	743.471985 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.232 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	597400064
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	2578
AASNodeAbsentTimer_mS_M_u32	148539904
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	42014
ANGLEVOLANTSigValidCount_Cnt_M_u16	43847
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	59279
AngleVolantMsgTimer_mS_M_u32	597400064
AngleVolantValidCount_Cnt_M_u16	41640
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	4221192704
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1295567360
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1413364224
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1437399552
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	19717
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3508976128
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	41872
CAVNodeAbsentTimer_mS_M_u32	2450598400
CDD_SrlComVehSpd_Kph_G_f32	655.295105
CMM388NTCEnableTimer_mS_M_u32	2363320832
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3827771904
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	36039
CMMNodeAbsentTimer_mS_M_u32	4195809792
CONSANGLECPKSigInvalidCount_Cnt_M_u16	60330
CONSANGLECPKSigValidCount_Cnt_M_u16	6178
CONSANGLECPK_Cnt_M_u16	10413
CONSANGLECPK_HwDeg_M_f32	754.356384
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	10413
CPKVehicleSpeedMsgTimer_mS_M_u32	2730138112
CPKVehicleSpeedValidCount_Cnt_M_u16	30361
CityParkInputConsistentCount_Cnt_M_u16	18700
CityParkInputInvalidCount_Cnt_M_u16	58489

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	1287648000
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1212058112
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	1654
ComputerRazGCTSigInvalidTimer_mS_M_u32	2283907584
ComputerRazGCTSigValidCount_Cnt_M_u16	40513
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	39445
DMDFCTCPKSigValidCount_Cnt_M_u16	9893
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	44624
DMDRELAXECPKSigValidCount_Cnt_M_u16	22265
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	8743
DateInvalidTimer_mS_M_u32	1295567360
DiagMuxOnAbsentTimer_mS_M_u32	1240816128
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1437399552
ESPNTCEnableTimer_mS_M_u32	1232833024
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	45035
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1121
EffacDefaultDiagTimer_mS_M_u32[1]	2235
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	79
ElecIntTimer_mS_M_u32[1]	101
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1639496192
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	56264
EtatMTSigValidCount_Cnt_M_u16	39261
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	3036
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	22996
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	62139
ISDAT4V2BSI552MsgTimer_mS_M_u32	3162176000
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	23250
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	65198
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	39261
ISDATBSI3F2MsgTimer_mS_M_u32	1103321600
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	24040
ISDATBSI412MsgLenValidCount_Cnt_M_u16	61940
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	56264
ISDATBSI412MsgTimer_mS_M_u32	1634310656
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	4651
ISDATBSI432MsgLenValidCount_Cnt_M_u16	14415
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	26449
ISDATDIRASentFltAcc_Cnt_M_u16	52677
ISDATDIRASentTimer_mS_M_u32	2730138112
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	65275
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	41640
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52348
ISDYN2CMMMsgTimer_mS_M_u32	174426624
ISDYNAASChkSumInvalidCount_Cnt_M_u16	41028
ISDYNAASChkSumValidCount_Cnt_M_u16	16524
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	6927
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	45147
ISDYNAASMsgLenValidCount_Cnt_M_u16	12572
ISDYNAASMsgTimeValidCount_Cnt_M_u16	41028
ISDYNAASMsgTimer_mS_M_u32	1736010240
ISDYNABRChkSumInvalidCount_Cnt_M_u16	48303
ISDYNABRChkSumValidCount_Cnt_M_u16	16416
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	6955
ISDYNABRMsgCountValidCount_Cnt_M_u16	60083
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	2449
ISDYNABRMsgLenValidCount_Cnt_M_u16	42313
ISDYNABRMsgTimeValidCount_Cnt_M_u16	10413
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	19997
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	9794

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	39261
ISDYNCMM208MsgTimer_mS_M_u32	1024412160
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	19997
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	9794
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	1910
ISDYNCMM388MsgTimer_mS_M_u32	3310152192
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	39800
ISDYNVOLChkSumValidCount_Cnt_M_u16	42608
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	11491
ISDYNVOLMsgCountValidCount_Cnt_M_u16	55283
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	25604
ISDYNVOLMsgLenValidCount_Cnt_M_u16	22365
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	36039
ISDYNVOLMsgTimer_mS_M_u32	2394794496
IgnOnTimer_mS_M_u32	45148672
IgnTimeOff_Sec_M_u32	3179436356
ManVehSpd_Kph_M_f32	349.988586
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	104
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	169
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1538873856
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	188
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3053795840
PrevISDATBSI412MsgDLCError_Cnt_M_u08	231
PrevISDATBSI412MsgRxTime_MSec_M_u32	1418865152
PrevISDATBSI432MsgDLCError_Cnt_M_u08	27
PrevISDATBSI432MsgRxTime_MSec_M_u32	4266625536
PrevISDATDIRAMsgTxTime_MSec_M_u32	1778788864
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	30
PrevISDYN2CMMMsgRxTime_MSec_M_u32	443709952
PrevISDYNAASMsgDLCError_Cnt_M_u08	172
PrevISDYNAASMsgRxTime_MSec_M_u32	2903222784
PrevISDYNABRMsgDLCError_Cnt_M_u08	193
PrevISDYNABRMsgRxTime_MSec_M_u32	719907328
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	34
PrevISDYNCMM208MsgRxTime_MSec_M_u32	738241024
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	88
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3956967936
PrevISDYNVOLMsgDLCError_Cnt_M_u08	12
PrevISDYNVOLMsgRxTime_MSec_M_u32	610216448
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	305633792
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	438.916992
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	35113
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	43114
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	58050
VitesseVehicleBVRampValidCount_Cnt_M_u16	12995
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	28471
VitesseVehicleBVSigValidCount_Cnt_M_u16	50976
VitesseVehicleBV_Kph_M_f32	151.144806

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	1910
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	57110
VitesseVehiculeRoues_Kph_M_f32	165.029297
k_AASNTCEnableTimeout_mS_u16	5644
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	42923
k_AASNodeTimeout_mS_u16	2922
k_ABSNodeTimeout_mS_u16	18250
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	45166
k_ANGLEVOLANTSigValidThresh_Cnt_u16	4818
k_AngleVolantInvalidThresh_Cnt_u16	46209
k_AngleVolantValidThresh_Cnt_u16	58489
k_BSI552MsgTimeout_mS_u16	49541
k_BSINTCEnableTimeout_mS_u16	43619
k_BSINodeAbsentDiag_Cnt_str.Threshold	1043
k_BSINodeAbsentDiag_Cnt_str.PStep	10954
k_BSINodeAbsentDiag_Cnt_str.NStep	64677
k_BSINodeAbsentTimeout_mS_u16	12743
k_BSINodeTimeout_mS_u16	26449
k_BattOvHi_Volt_f32	7.49539995
k_BattOvLo_Volt_f32	4.51730013
k_BattUvHi_Volt_f32	9.98050022
k_BattUvLo_Volt_f32	3.56760001
k_CAVNTCEnableTimeout_mS_u16	58751
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	22366
k_CAVNodeTimeout_mS_u16	48710
k_CMM388MsgTimeout_mS_u16	44306
k_CMM388NTCEnableTimeout_mS_u16	61614
k_CMMNTCEnableTimeout_mS_u16	53002
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	47282
k_CONSANGLECPKMax_HwDeg_f32	17.5550995
k_CONSANGLECPKMin_HwDeg_f32	-213.203705
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	10870
k_CONSANGLECPKSigValidThresh_Cnt_u16	16918
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	45696
k_CPKVehicleSpeedValidThresh_Cnt_u16	30835
k_CityParkInputInvalidThresh_Cnt_u16	53317
k_CityParkInputValidThresh_Cnt_u16	18700
k_ComputerRazGCTSigValidThresh_Cnt_u16	44872
k_CptTemporelSigValidThresh_Cnt_u16	57252
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	44177
k_DMDFCTCPKSigValidThresh_Cnt_u16	34889
k_DMDFCTCPKValidCount_Cnt_u16	46541
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	52348
k_DMDRELAXECPKSigValidThresh_Cnt_u16	10316
k_DMDRelaxeConsistentThresh_Cnt_u16	55650
k_DateValidThresh_Cnt_u16	62139
k_DefaultVehSpd_Kph_f32	224.916901
k_DiagMuxOnAbsentTimeout_mS_u16	23347
k_EMNodeTimeout_mS_u16	45959
k_ESPNTCEnableTimeout_mS_u16	47148
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	43130
k_EtatMTSigInvalidThresh_Cnt_u16	32830
k_EtatMTSigValidThresh_Cnt_u16	57583
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	65259
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	35167
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	5285
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	29551
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	17163
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	26956
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	46152
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	9772

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	55183
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	50545
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	30110
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	51106
k_ISDATDIRASentDiag_Cnt_str.Threshold	58745
k_ISDATDIRASentDiag_Cnt_str.PStep	41340
k_ISDATDIRASentDiag_Cnt_str.NStep	16989
k_ISDATDIRASentTimeout_mS_u16	36171
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	64023
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	59279
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	32856
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	57263
k_ISDYNAASChkSumValidThresh_Cnt_u16	41760
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	48683
k_ISDYNAASMsgCountValidThresh_Cnt_u16	52659
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	20243
k_ISDYNAASMsgLenValidThresh_Cnt_u16	35278
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	8346
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	17503
k_ISDYNABRChkSumValidThresh_Cnt_u16	65175
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	61445
k_ISDYNABRMsgCountValidThresh_Cnt_u16	58990
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	61383
k_ISDYNABRMsgLenValidThresh_Cnt_u16	21227
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	7773
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	42893
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	62145
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	62681
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	18206
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	36423
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	45745
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	9387
k_ISDYNVOLChkSumValidThresh_Cnt_u16	21751
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	48232
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	38276
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	5476
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	4089
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	48193
k_IgnOnTimeout_mS_u16	26951
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	205.626404
k_PowerCutVehSpdLowThresh_Kph_f32	93.821701
k_PowerCutVehSpdLowTimeout_mS_u16	42648
k_VBattMaxAAS_Volt_f32	19.1392002
k_VBattMaxBSI_Volt_f32	1.35749996
k_VBattMaxCAV_Volt_f32	1.74820006
k_VBattMaxCMM388_Volt_f32	30.4815998
k_VBattMaxCMM_Volt_f32	22.2879009
k_VBattMaxESP_Volt_f32	4.59889984
k_VBattMinAAS_Volt_f32	7.2638998
k_VBattMinBSI_Volt_f32	4.59889984
k_VBattMinCAV_Volt_f32	1.81490004
k_VBattMinCMM388_Volt_f32	19.9417
k_VBattMinCMM_Volt_f32	12.9182997
k_VBattMinESP_Volt_f32	22.2879009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	32257
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	52861
k_VitesseVehicleBVRampValidThresh_Cnt_u16	20451
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	35184
k_VitesseVehicleBVSigValidThresh_Cnt_u16	35549
k_VitesseVehicleBVSpeedPassThresh_kph_f32	283.941193
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	50832
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	62737
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1295567360
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	39273
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	19897088
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	88

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	26.7507
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	138918400
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	251
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.435949773
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	15395328
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1841170944
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	155
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3294702080
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	185
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2362722816
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1326934528
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	160
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2469038592
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	120
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3775769088
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	115
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	132
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	265112064
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	55
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	100
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	141
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	155
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	167
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	207
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	161
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1217784320
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1357449728
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	51128832
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	83
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	90
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	165
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1363622400
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1792
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.942548573
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	740362
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	81.3287964
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	5779

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	19897088	19897088	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	19897088	19897088	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	19897088	19897088	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	19897088	19897088	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	19897088	19897088	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	19897088	19897088	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	19897088	19897088	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	19897088	19897088	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	19897088	19897088	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	19897088	19897088	✔
CDD_SrlComVehSpd_Kph_G_f32	349.988586	349.988586	✔
CMM388NTCEnableTimer_mS_M_u32	19897088	19897088	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	19897088	19897088	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	19897088	19897088	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	10413	10413	✔
CONSANGLECPK_HwDeg_M_f32	754.356384	754.356384 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	19897088	19897088	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	19897088	19897088	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	19897088	19897088	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	19897088	19897088	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	19897088	19897088	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	19897088	19897088	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	19897088	19897088	✔
ESPNTCEnableTimer_mS_M_u32	19897088	19897088	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	19897088	19897088	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1121	1121	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2235	2235	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	79	79	✔
ElecIntTimer_mS_M_u32[1]	101	101	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	19897088	19897088	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	62139	62139	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	19897088	19897088	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	39261	39261	✔
ISDATBSI3F2MsgTimer_mS_M_u32	19897088	19897088	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	56264	56264	✔
ISDATBSI412MsgTimer_mS_M_u32	19897088	19897088	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	26449	26449	✔
ISDATBSI432MsgTimer_mS_M_u32	19897088	19897088	✔
ISDATDIRASentFltAcc_Cnt_M_u16	58745	58745	✔
ISDATDIRASentTimer_mS_M_u32	19897088	19897088	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52348	52348	✔
ISDYN2CMMMsgTimer_mS_M_u32	19897088	19897088	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	41028	41028	✔
ISDYNAASMsgTimer_mS_M_u32	19897088	19897088	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	10413	10413	✔
ISDYNABRMsgTimer_mS_M_u32	19897088	19897088	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	39261	39261	✔
ISDYNCMM208MsgTimer_mS_M_u32	19897088	19897088	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	1910	1910	✔
ISDYNCMM388MsgTimer_mS_M_u32	19897088	19897088	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	36039	36039	✔
ISDYNVOLMsgTimer_mS_M_u32	19897088	19897088	✔
IgnOnTimer_mS_M_u32	45148672	45148672	✔
IgnTimeOff_Sec_M_u32	3179436356	3179436356	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	95	95	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	15395328	15395328	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	170	170	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1841170944	1841170944	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	155	155	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3294702080	3294702080	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	185	185	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2362722816	2362722816	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1778788864	1778788864	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	160	160	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2469038592	2469038592	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	120	120	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3775769088	3775769088	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	181	181	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	265112064	265112064	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	161	161	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1217784320	1217784320	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1357449728	1357449728	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	51128832	51128832	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1363622400	1363622400	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	438.916992	438.916992	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	151.144806	151.144806	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	165.029297	165.029297	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	10413	10413	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3179436356	3179436356	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	754.356384	754.356384 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.233 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3753112832
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	9808
AASNodeAbsentTimer_mS_M_u32	397878528
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	10794
ANGLEVOLANTSigValidCount_Cnt_M_u16	33393
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	49625
AngleVolantMsgTimer_mS_M_u32	3753112832
AngleVolantValidCount_Cnt_M_u16	56590
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	4000834816
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2476500224
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2689340672
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3338654976
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	35701
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1804768512
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	7252
CAVNodeAbsentTimer_mS_M_u32	512967936
CDD_SrlComVehSpd_Kph_G_f32	41.0189018
CMM388NTCEnableTimer_mS_M_u32	2939061504
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	5326080
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	55152
CMMNodeAbsentTimer_mS_M_u32	29480192
CONSANGLECPKSigInvalidCount_Cnt_M_u16	12935
CONSANGLECPKSigValidCount_Cnt_M_u16	23262
CONSANGLECPK_Cnt_M_u16	5437
CONSANGLECPK_HwDeg_M_f32	-79.4717026
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	5437
CPKVehicleSpeedMsgTimer_mS_M_u32	2656498944
CPKVehicleSpeedValidCount_Cnt_M_u16	60385
CityParkInputConsistentCount_Cnt_M_u16	31202
CityParkInputInvalidCount_Cnt_M_u16	60570
CityParkInputMsgTimer_mS_M_u32	15395328
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3918210304
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	49444

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	509723904
ComputerRazGCTSigValidCount_Cnt_M_u16	36419
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	15302
DMDFCTCPKSigValidCount_Cnt_M_u16	41941
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	21396
DMDRELAXECPKSigValidCount_Cnt_M_u16	51035
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	49936
DateInvalidTimer_mS_M_u32	2476500224
DiagMuxOnAbsentTimer_mS_M_u32	61256960
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3338654976
ESPNTCEnableTimer_mS_M_u32	433333504
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	52163
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	3
EffacDefaultDiagTimer_mS_M_u32[1]	6
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	19
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2178716928
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	32620
EtatMTSigValidCount_Cnt_M_u16	25711
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	6641
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	56776
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	6035
ISDAT4V2BSI552MsgTimer_mS_M_u32	1251333376
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	24528
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	45563
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	25711
ISDATBSI3F2MsgTimer_mS_M_u32	3560748288
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	32653
ISDATBSI412MsgLenValidCount_Cnt_M_u16	49448
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	32620
ISDATBSI412MsgTimer_mS_M_u32	3729388800
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	55108
ISDATBSI432MsgLenValidCount_Cnt_M_u16	49815
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	5393
ISDATDIRASentFltAcc_Cnt_M_u16	45493
ISDATDIRASentTimer_mS_M_u32	2656498944
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	19027
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	56590
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	145
ISDYN2CMMMsgTimer_mS_M_u32	4279641344
ISDYNAASChkSumInvalidCount_Cnt_M_u16	43962
ISDYNAASChkSumValidCount_Cnt_M_u16	47265
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	53209
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	57843
ISDYNAASMsgLenValidCount_Cnt_M_u16	11634
ISDYNAASMsgTimeValidCount_Cnt_M_u16	43962
ISDYNAASMsgTimer_mS_M_u32	2405074176
ISDYNABRChkSumInvalidCount_Cnt_M_u16	24054
ISDYNABRChkSumValidCount_Cnt_M_u16	24933
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	38661
ISDYNABRMsgCountValidCount_Cnt_M_u16	5676
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	13522
ISDYNABRMsgLenValidCount_Cnt_M_u16	3945
ISDYNABRMsgTimeValidCount_Cnt_M_u16	5437
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	56419
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	23853
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	25711
ISDYNCMM208MsgTimer_mS_M_u32	1041818880
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	56419
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	23853
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	26276

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	601883904
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	56093
ISDYNVOLChkSumValidCount_Cnt_M_u16	26612
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	15196
ISDYNVOLMsgCountValidCount_Cnt_M_u16	18411
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	21368
ISDYNVOLMsgLenValidCount_Cnt_M_u16	42798
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	55152
ISDYNVOLMsgTimer_mS_M_u32	2056111360
IgnOnTimer_mS_M_u32	4222878976
IgnTimeOff_Sec_M_u32	1398482621
ManVehSpd_Kph_M_f32	33.3193016
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	105
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	197
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3730486528
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	59
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1459033344
PrevISDATBSI412MsgDLCError_Cnt_M_u08	150
PrevISDATBSI412MsgRxTime_MSec_M_u32	454051072
PrevISDATBSI432MsgDLCError_Cnt_M_u08	25
PrevISDATBSI432MsgRxTime_MSec_M_u32	1264067840
PrevISDATDIRAMsgTxTime_MSec_M_u32	2863940864
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	26
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1856984320
PrevISDYNAASMsgDLCError_Cnt_M_u08	166
PrevISDYNAASMsgRxTime_MSec_M_u32	3617834240
PrevISDYNABRMsgDLCError_Cnt_M_u08	230
PrevISDYNABRMsgRxTime_MSec_M_u32	1661732096
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	99
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1858389248
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	58
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1857496320
PrevISDYNVOLMsgDLCError_Cnt_M_u08	167
PrevISDYNVOLMsgRxTime_MSec_M_u32	531186944
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2212492544
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	387.62149
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	3977
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	32648
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	42686
VitesseVehicleBVRampValidCount_Cnt_M_u16	33917
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	27871
VitesseVehicleBVSigValidCount_Cnt_M_u16	53990
VitesseVehicleBV_Kph_M_f32	79.2686005
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	26276
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	11650
VitesseVehiculeRoues_Kph_M_f32	123.503403
k_AASNTCEnableTimeout_mS_u16	35104
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	39429
k_AASNodeTimeout_mS_u16	22152
k_ABSNodeTimeout_mS_u16	18471
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	51323
k_ANGLEVOLANTSigValidThresh_Cnt_u16	65294
k_AngleVolantInvalidThresh_Cnt_u16	38401
k_AngleVolantValidThresh_Cnt_u16	60570
k_BSI552MsgTimeout_mS_u16	565
k_BSINTCEnableTimeout_mS_u16	61084
k_BSINodeAbsentDiag_Cnt_str.Threshold	61699
k_BSINodeAbsentDiag_Cnt_str.PStep	50677
k_BSINodeAbsentDiag_Cnt_str.NStep	16171
k_BSINodeAbsentTimeout_mS_u16	49969
k_BSINodeTimeout_mS_u16	5393
k_BattOvHi_Volt_f32	19.3799
k_BattOvLo_Volt_f32	21.0461998
k_BattUvHi_Volt_f32	2.33979988
k_BattUvLo_Volt_f32	13.1677999
k_CAVNTCEnableTimeout_mS_u16	33160
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	47338
k_CAVNodeTimeout_mS_u16	10931
k_CMM388MsgTimeout_mS_u16	15696
k_CMM388NTCEnableTimeout_mS_u16	57980
k_CMMNTCEnableTimeout_mS_u16	58152
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	4270
k_CONSANGLECPKMax_HwDeg_f32	534.690613
k_CONSANGLECPKMin_HwDeg_f32	-386.709686
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	64932
k_CONSANGLECPKSigValidThresh_Cnt_u16	1154
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	14662
k_CPKVehicleSpeedValidThresh_Cnt_u16	7148
k_CityParkInputInvalidThresh_Cnt_u16	64308
k_CityParkInputValidThresh_Cnt_u16	31202
k_ComputerRazGCTSigValidThresh_Cnt_u16	47726
k_CptTemporelSigValidThresh_Cnt_u16	26393
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	19410
k_DMDFCTCPKSigValidThresh_Cnt_u16	26217
k_DMDFCTCPKValidCount_Cnt_u16	28957
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	145
k_DMDRELAXECPKSigValidThresh_Cnt_u16	64224
k_DMDRelaxeConsistentThresh_Cnt_u16	49054
k_DateValidThresh_Cnt_u16	6035
k_DefaultVehSpd_Kph_f32	76.2757034
k_DiagMuxOnAbsentTimeout_mS_u16	5547
k_EMNodeTimeout_mS_u16	36592
k_ESPNTCEnableTimeout_mS_u16	20096
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	24918
k_EtatMTSigInvalidThresh_Cnt_u16	3913
k_EtatMTSigValidThresh_Cnt_u16	31480
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	49157
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	48743
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	47895
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	51705
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	39140
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	60769
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	42221
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	44288
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	5912
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	20209
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	48172
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	64351
k_ISDATDIRASentDiag_Cnt_str.Threshold	39767

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	14534
k_ISDATDIRASentDiag_Cnt_str.NStep	62426
k_ISDATDIRASentTimeout_mS_u16	23586
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	30720
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	49625
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	42492
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	62710
k_ISDYNAASChkSumValidThresh_Cnt_u16	14437
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	44549
k_ISDYNAASMsgCountValidThresh_Cnt_u16	27948
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	14026
k_ISDYNAASMsgLenValidThresh_Cnt_u16	27484
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	62902
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	15464
k_ISDYNABRChkSumValidThresh_Cnt_u16	47999
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	41589
k_ISDYNABRMsgCountValidThresh_Cnt_u16	11516
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	44656
k_ISDYNABRMsgLenValidThresh_Cnt_u16	58051
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	303
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	17501
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	25858
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	5691
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	16682
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	55665
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	25074
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	63300
k_ISDYNVOLChkSumValidThresh_Cnt_u16	25631
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	55884
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	61753
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	17048
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	28827
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	21249
k_IgnOnTimeout_mS_u16	39280
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	228.647293
k_PowerCutVehSpdLowThresh_Kph_f32	124.061401
k_PowerCutVehSpdLowTimeout_mS_u16	1916
k_VBattMaxAAS_Volt_f32	17.9960995
k_VBattMaxBSI_Volt_f32	5.66340017
k_VBattMaxCAV_Volt_f32	2.9763999
k_VBattMaxCMM388_Volt_f32	28.4738007
k_VBattMaxCMM_Volt_f32	17.4442997
k_VBattMaxESP_Volt_f32	28.0690002
k_VBattMinAAS_Volt_f32	30.6443005
k_VBattMinBSI_Volt_f32	28.0690002
k_VBattMinCAV_Volt_f32	31.3612995
k_VBattMinCMM388_Volt_f32	18.5534
k_VBattMinCMM_Volt_f32	14.3256998
k_VBattMinESP_Volt_f32	17.4442997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	5186
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	57484
k_VitesseVehicleBVRampValidThresh_Cnt_u16	53852
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	48884
k_VitesseVehicleBVSigValidThresh_Cnt_u16	14447
k_VitesseVehicleBVSpeedPassThresh_kph_f32	140.445496
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	45908
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	62867
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2476500224
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	25798
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2486956544
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	58
target_SrlComInput_Per1_Batt_Volt_f32.value	7.00110006
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2318374144
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	177
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.632644534
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1762002176
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3607930112
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3349366016
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	25
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2731140352
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3498083584
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	78
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3100058880
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	27
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3281896704
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	94
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	187
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1038017792
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	10
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	46
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	94
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	195
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4261741824
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2576065792
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	225
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2007123200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	131
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	167
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	216
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	224
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	221320448
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3831
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.612854123
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	514848
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	172.7901
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	36683

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2486956544	2486956544	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2486956544	2486956544	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2486956544	2486956544	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2486956544	2486956544	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2486956544	2486956544	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2486956544	2486956544	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2486956544	2486956544	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2486956544	2486956544	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2486956544	2486956544	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2486956544	2486956544	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2486956544	2486956544	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2486956544	2486956544	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2486956544	2486956544	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	5437	5437	✔
CONSANGLECPK_HwDeg_M_f32	-79.4717026	-79.4717026 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2486956544	2486956544	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2486956544	2486956544	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2486956544	2486956544	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2486956544	2486956544	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2486956544	2486956544	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2486956544	2486956544	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2486956544	2486956544	✔
ESPNTCEnableTimer_mS_M_u32	2486956544	2486956544	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2486956544	2486956544	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3	3	✔
EffacDefaultDiagTimer_mS_M_u32[1]	6	6	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2486956544	2486956544	✔
ElecIntTimer_mS_M_u32[1]	19	19	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2486956544	2486956544	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2486956544	2486956544	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2486956544	2486956544	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2486956544	2486956544	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2486956544	2486956544	✔
ISDATDIRASentFltAcc_Cnt_M_u16	39767	39767	✔
ISDATDIRASentTimer_mS_M_u32	2486956544	2486956544	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2486956544	2486956544	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2486956544	2486956544	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2486956544	2486956544	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2486956544	2486956544	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2486956544	2486956544	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2486956544	2486956544	✔
IgnOnTimer_mS_M_u32	2486956544	2486956544	✔
IgnTimeOff_Sec_M_u32	1398482621	1398482621	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1762002176	1762002176	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3607930112	3607930112	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	224	224	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3349366016	3349366016	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	25	25	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2731140352	2731140352	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2863940864	2863940864	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	78	78	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3100058880	3100058880	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	27	27	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3281896704	3281896704	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	74	74	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1038017792	1038017792	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	208	208	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4261741824	4261741824	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	81	81	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2576065792	2576065792	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	225	225	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2007123200	2007123200	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	221320448	221320448	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	387.62149	387.62149	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	79.2686005	79.2686005	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	123.503403	123.503403	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	5437	5437	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1398482621	1398482621	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-79.4717026	-79.4717026 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.234 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	311878656
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	20673
AASNodeAbsentTimer_mS_M_u32	3008189440
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	53041
ANGLEVOLANTSigValidCount_Cnt_M_u16	32029
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	57894
AngleVolantMsgTimer_mS_M_u32	311878656
AngleVolantValidCount_Cnt_M_u16	43784
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	571151360
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1688048640
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3645801472
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3828564992
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	38736
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2977629184
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	10037
CAVNodeAbsentTimer_mS_M_u32	3073963008
CDD_SrlComVehSpd_Kph_G_f32	135.757202
CMM388NTCEnableTimer_mS_M_u32	2187801600
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2315187200
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	37281
CMMNodeAbsentTimer_mS_M_u32	3152888832
CONSANGLECPKSigInvalidCount_Cnt_M_u16	6427
CONSANGLECPKSigValidCount_Cnt_M_u16	38615
CONSANGLECPK_Cnt_M_u16	41914
CONSANGLECPK_HwDeg_M_f32	-735.525085
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	41914
CPKVehicleSpeedMsgTimer_mS_M_u32	581821440
CPKVehicleSpeedValidCount_Cnt_M_u16	32406
CityParkInputConsistentCount_Cnt_M_u16	9356
CityParkInputInvalidCount_Cnt_M_u16	64867

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	1762002176
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2379305984
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	53317
ComputerRazGCTSigInvalidTimer_mS_M_u32	298677248
ComputerRazGCTSigValidCount_Cnt_M_u16	43881
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	49119
DMDFCTCPKSigValidCount_Cnt_M_u16	24179
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	31475
DMDRELAXECPKSigValidCount_Cnt_M_u16	54879
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	52096
DateInvalidTimer_mS_M_u32	1688048640
DiagMuxOnAbsentTimer_mS_M_u32	3787367424
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3828564992
ESPNTCEnableTimer_mS_M_u32	1626756096
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	39785
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	9
EffacDefaultDiagTimer_mS_M_u32[1]	81
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	88
ElecIntTimer_mS_M_u32[1]	111
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	379388928
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	55980
EtatMTSigValidCount_Cnt_M_u16	53860
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	35549
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	13849
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	31545
ISDAT4V2BSI552MsgTimer_mS_M_u32	829506560
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	8448
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	28992
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	53860
ISDATBSI3F2MsgTimer_mS_M_u32	1207739392
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	18121
ISDATBSI412MsgLenValidCount_Cnt_M_u16	35001
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	55980
ISDATBSI412MsgTimer_mS_M_u32	4006929408
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	57893
ISDATBSI432MsgLenValidCount_Cnt_M_u16	1773
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	28926
ISDATDIRASentFltAcc_Cnt_M_u16	11026
ISDATDIRASentTimer_mS_M_u32	581821440
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	56440
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	43784
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	23934
ISDYN2CMMMsgTimer_mS_M_u32	959468544
ISDYNAASChkSumInvalidCount_Cnt_M_u16	59523
ISDYNAASChkSumValidCount_Cnt_M_u16	63631
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	48807
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	4696
ISDYNAASMsgLenValidCount_Cnt_M_u16	50843
ISDYNAASMsgTimeValidCount_Cnt_M_u16	59523
ISDYNAASMsgTimer_mS_M_u32	2447586304
ISDYNABRChkSumInvalidCount_Cnt_M_u16	47950
ISDYNABRChkSumValidCount_Cnt_M_u16	1986
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	4770
ISDYNABRMsgCountValidCount_Cnt_M_u16	52206
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	65082
ISDYNABRMsgLenValidCount_Cnt_M_u16	25910
ISDYNABRMsgTimeValidCount_Cnt_M_u16	41914
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	52785
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	28818

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	53860
ISDYNCMM208MsgTimer_mS_M_u32	4146598912
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	52785
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	28818
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	58950
ISDYNCMM388MsgTimer_mS_M_u32	3394417664
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	63321
ISDYNVOLChkSumValidCount_Cnt_M_u16	18325
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	39197
ISDYNVOLMsgCountValidCount_Cnt_M_u16	18993
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	6218
ISDYNVOLMsgLenValidCount_Cnt_M_u16	37862
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	37281
ISDYNVOLMsgTimer_mS_M_u32	2907272192
IgnOnTimer_mS_M_u32	2463544320
IgnTimeOff_Sec_M_u32	3023342970
ManVehSpd_Kph_M_f32	304.353302
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	106
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	254
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	564306944
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	143
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	558728192
PrevISDATBSI412MsgDLCError_Cnt_M_u08	229
PrevISDATBSI412MsgRxTime_MSec_M_u32	4123128832
PrevISDATBSI432MsgDLCError_Cnt_M_u08	5
PrevISDATBSI432MsgRxTime_MSec_M_u32	3697955840
PrevISDATDIRAMsgTxTime_MSec_M_u32	3604345856
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	228
PrevISDYN2CMMMsgRxTime_MSec_M_u32	186958848
PrevISDYNAASMsgDLCError_Cnt_M_u08	156
PrevISDYNAASMsgRxTime_MSec_M_u32	1845982208
PrevISDYNABRMsgDLCError_Cnt_M_u08	89
PrevISDYNABRMsgRxTime_MSec_M_u32	3167663104
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	3
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1822716928
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	24
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2924303360
PrevISDYNVOLMsgDLCError_Cnt_M_u08	46
PrevISDYNVOLMsgRxTime_MSec_M_u32	2348217344
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3591562240
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	3.54480004
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	24982
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	43097
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	45047
VitesseVehicleBVRampValidCount_Cnt_M_u16	44410
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	6930
VitesseVehicleBVSigValidCount_Cnt_M_u16	40894
VitesseVehicleBV_Kph_M_f32	505.571899

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	58950
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	43114
VitesseVehiculeRoues_Kph_M_f32	115.202797
k_AASNTCEnableTimeout_mS_u16	37905
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	4131
k_AASNodeTimeout_mS_u16	9049
k_ABSNodeTimeout_mS_u16	24252
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	43648
k_ANGLEVOLANTSigValidThresh_Cnt_u16	60808
k_AngleVolantInvalidThresh_Cnt_u16	46255
k_AngleVolantValidThresh_Cnt_u16	64867
k_BSI552MsgTimeout_mS_u16	46673
k_BSINTCEnableTimeout_mS_u16	64541
k_BSINodeAbsentDiag_Cnt_str.Threshold	2511
k_BSINodeAbsentDiag_Cnt_str.PStep	22074
k_BSINodeAbsentDiag_Cnt_str.NStep	50649
k_BSINodeAbsentTimeout_mS_u16	15902
k_BSINodeTimeout_mS_u16	28926
k_BattOvHi_Volt_f32	29.7050991
k_BattOvLo_Volt_f32	14.0107002
k_BattUvHi_Volt_f32	12.0804996
k_BattUvLo_Volt_f32	4.8283
k_CAVNTCEnableTimeout_mS_u16	30361
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	10611
k_CAVNodeTimeout_mS_u16	57495
k_CMM388MsgTimeout_mS_u16	3009
k_CMM388NTCEnableTimeout_mS_u16	52285
k_CMMNTCEnableTimeout_mS_u16	63224
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	44774
k_CONSANGLECPKMax_HwDeg_f32	201.070206
k_CONSANGLECPKMin_HwDeg_f32	-768.69873
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	8518
k_CONSANGLECPKSigValidThresh_Cnt_u16	9066
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	62239
k_CPKVehicleSpeedValidThresh_Cnt_u16	44460
k_CityParkInputInvalidThresh_Cnt_u16	23444
k_CityParkInputValidThresh_Cnt_u16	9356
k_ComputerRazGCTSigValidThresh_Cnt_u16	2342
k_CptTemporelSigValidThresh_Cnt_u16	18918
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	47418
k_DMDFCTCPKSigValidThresh_Cnt_u16	24630
k_DMDFCTCPKValidCount_Cnt_u16	34392
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	23934
k_DMDRELAXECPKSigValidThresh_Cnt_u16	17746
k_DMDRelaxeConsistentThresh_Cnt_u16	28440
k_DateValidThresh_Cnt_u16	31545
k_DefaultVehSpd_Kph_f32	223.371201
k_DiagMuxOnAbsentTimeout_mS_u16	55920
k_EMNodeTimeout_mS_u16	59360
k_ESPNTCEnableTimeout_mS_u16	16561
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	23790
k_EtatMTSigInvalidThresh_Cnt_u16	45909
k_EtatMTSigValidThresh_Cnt_u16	50953
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	6882
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	18042
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	29933
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	50821
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	41093
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	19789
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	23850
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	11186

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	29353
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	50846
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	1454
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	43093
k_ISDATDIRASentDiag_Cnt_str.Threshold	52217
k_ISDATDIRASentDiag_Cnt_str.PStep	24388
k_ISDATDIRASentDiag_Cnt_str.NStep	13533
k_ISDATDIRASentTimeout_mS_u16	28874
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	63090
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	57894
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10813
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	63054
k_ISDYNAASChkSumValidThresh_Cnt_u16	33474
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	52642
k_ISDYNAASMsgCountValidThresh_Cnt_u16	50926
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	32978
k_ISDYNAASMsgLenValidThresh_Cnt_u16	13533
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	43408
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	49016
k_ISDYNABRChkSumValidThresh_Cnt_u16	14580
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	21072
k_ISDYNABRMsgCountValidThresh_Cnt_u16	27004
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	3233
k_ISDYNABRMsgLenValidThresh_Cnt_u16	22121
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	30947
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	4890
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	43626
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	28736
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	35377
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	30749
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	64859
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	31652
k_ISDYNVOLChkSumValidThresh_Cnt_u16	15316
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	54222
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	43078
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	16680
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	24032
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	239
k_IgnOnTimeout_mS_u16	17696
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	250.756393
k_PowerCutVehSpdLowThresh_Kph_f32	92.5141983
k_PowerCutVehSpdLowTimeout_mS_u16	35069
k_VBattMaxAAS_Volt_f32	2.49830008
k_VBattMaxBSI_Volt_f32	5.52939987
k_VBattMaxCAV_Volt_f32	18.1343002
k_VBattMaxCMM388_Volt_f32	2.55060005
k_VBattMaxCMM_Volt_f32	10.4700003
k_VBattMaxESP_Volt_f32	6.92309999
k_VBattMinAAS_Volt_f32	0.486099988
k_VBattMinBSI_Volt_f32	6.92309999
k_VBattMinCAV_Volt_f32	12.2248001
k_VBattMinCMM388_Volt_f32	24.9319
k_VBattMinCMM_Volt_f32	14.5082998
k_VBattMinESP_Volt_f32	10.4700003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	43436
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	2956
k_VitesseVehicleBVRampValidThresh_Cnt_u16	54301
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	17045
k_VitesseVehicleBVSigValidThresh_Cnt_u16	23781
k_VitesseVehicleBVSpeedPassThresh_kph_f32	256.0224
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	25141
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	12856
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1688048640
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	49132
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	489876736
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	24

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	23.3964005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	161743872
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	141
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.115802854
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	316716032
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2873938944
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4228445184
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	112
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3440710656
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3866178560
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	270357504
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	177
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	303657984
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	61
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	71
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	88
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	90
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2413171712
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	70
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	97
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	111
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	254
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	266580992
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	61
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	533713920
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2819355648
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	97
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1721730048
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1463
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.300979078
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	628443
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	168.577896
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	27216

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	489876736	489876736	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	489876736	489876736	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	57894	57894	✔
AngleVolantMsgTimer_mS_M_u32	489876736	489876736	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	489876736	489876736	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	489876736	489876736	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	489876736	489876736	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	489876736	489876736	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	489876736	489876736	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	489876736	489876736	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	489876736	489876736	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	489876736	489876736	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	489876736	489876736	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	489876736	489876736	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	41914	41914	✔
CONSANGLECPK_HwDeg_M_f32	-735.525085	-735.525085 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	41914	41914	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	581821440	581821440	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	32406	32406	✔
CityParkInputConsistentCount_Cnt_M_u16	9356	9356	✔
CityParkInputInvalidCount_Cnt_M_u16	64867	64867	✔
CityParkInputMsgTimer_mS_M_u32	489876736	489876736	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	489876736	489876736	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	489876736	489876736	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	489876736	489876736	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	489876736	489876736	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	489876736	489876736	✔
ESPNTCEnableTimer_mS_M_u32	489876736	489876736	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	489876736	489876736	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	489876736	489876736	✔
EffacDefaultDiagTimer_mS_M_u32[1]	81	81	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	489876736	489876736	✔
ElecIntTimer_mS_M_u32[1]	111	111	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	489876736	489876736	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	489876736	489876736	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	489876736	489876736	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	489876736	489876736	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	489876736	489876736	✔
ISDATDIRASentFltAcc_Cnt_M_u16	52217	52217	✔
ISDATDIRASentTimer_mS_M_u32	489876736	489876736	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	489876736	489876736	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	489876736	489876736	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	489876736	489876736	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	489876736	489876736	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	489876736	489876736	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	489876736	489876736	✔
IgnOnTimer_mS_M_u32	2463544320	2463544320	✔
IgnTimeOff_Sec_M_u32	3023342970	3023342970	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	53	53	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	316716032	316716032	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	92	92	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2873938944	2873938944	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	216	216	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4228445184	4228445184	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	112	112	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3440710656	3440710656	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3604345856	3604345856	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	270357504	270357504	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	177	177	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	303657984	303657984	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	113	113	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2413171712	2413171712	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	254	254	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	266580992	266580992	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	61	61	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	533713920	533713920	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	144	144	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2819355648	2819355648	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1721730048	1721730048	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	3.54480004	3.54480004	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	505.571899	505.571899	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	115.202797	115.202797	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	41914	41914	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3023342970	3023342970	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-735.525085	-735.525085 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.235 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4100593408
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	1002
AASNodeAbsentTimer_mS_M_u32	939968256
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	60057
ANGLEVOLANTSigValidCount_Cnt_M_u16	48277
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	9147
AngleVolantMsgTimer_mS_M_u32	4100593408
AngleVolantValidCount_Cnt_M_u16	31125
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	315459328
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3038119680
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2260940544
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3910465280
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	52796
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1346221824
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	22287
CAVNodeAbsentTimer_mS_M_u32	3804489472
CDD_SrlComVehSpd_Kph_G_f32	296.326508
CMM388NTCEnableTimer_mS_M_u32	171517696
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	41019136
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	17547
CMMNodeAbsentTimer_mS_M_u32	3387356928
CONSANGLECPKSigInvalidCount_Cnt_M_u16	58331
CONSANGLECPKSigValidCount_Cnt_M_u16	34408
CONSANGLECPK_Cnt_M_u16	43967
CONSANGLECPK_HwDeg_M_f32	-709.563721
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43967
CPKVehicleSpeedMsgTimer_mS_M_u32	3760527104
CPKVehicleSpeedValidCount_Cnt_M_u16	7891
CityParkInputConsistentCount_Cnt_M_u16	7433

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	65411
CityParkInputMsgTimer_mS_M_u32	316716032
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3095054080
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	38238
ComputerRazGCTSigInvalidTimer_mS_M_u32	3305531136
ComputerRazGCTSigValidCount_Cnt_M_u16	15474
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	43023
DMDFCTCPKSigValidCount_Cnt_M_u16	18451
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	28499
DMDRELAXECPKSigValidCount_Cnt_M_u16	14543
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	41132
DateInvalidTimer_mS_M_u32	3038119680
DiagMuxOnAbsentTimer_mS_M_u32	3589461760
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3910465280
ESPNTCEnableTimer_mS_M_u32	319538944
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	29427
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	20
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1
ElecIntTimer_mS_M_u32[1]	14
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	685225728
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	42601
EtatMTSigValidCount_Cnt_M_u16	51969
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	5781
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	12450
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	35265
ISDAT4V2BSI552MsgTimer_mS_M_u32	2036004608
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	7404
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	22508
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	51969
ISDATBSI3F2MsgTimer_mS_M_u32	456709888
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	7315
ISDATBSI412MsgLenValidCount_Cnt_M_u16	17027
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	42601
ISDATBSI412MsgTimer_mS_M_u32	3618641664
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	25343
ISDATBSI432MsgLenValidCount_Cnt_M_u16	16487
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	56756
ISDATDIRASentFltAcc_Cnt_M_u16	65400
ISDATDIRASentTimer_mS_M_u32	3760527104
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	31109
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	31125
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	2866
ISDYN2CMMMsgTimer_mS_M_u32	4066232064
ISDYNAASChkSumInvalidCount_Cnt_M_u16	50340
ISDYNAASChkSumValidCount_Cnt_M_u16	61504
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	31416
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	57766
ISDYNAASMsgLenValidCount_Cnt_M_u16	154
ISDYNAASMsgTimeValidCount_Cnt_M_u16	50340
ISDYNAASMsgTimer_mS_M_u32	3418695424
ISDYNABRChkSumInvalidCount_Cnt_M_u16	36803
ISDYNABRChkSumValidCount_Cnt_M_u16	42536
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	33351
ISDYNABRMsgCountValidCount_Cnt_M_u16	45603
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	28798
ISDYNABRMsgLenValidCount_Cnt_M_u16	22347
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43967
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	19619

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	63295
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	51969
ISDYNCMM208MsgTimer_mS_M_u32	1198950144
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	19619
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	63295
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	16347
ISDYNCMM388MsgTimer_mS_M_u32	1081517824
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	49441
ISDYNVOLChkSumValidCount_Cnt_M_u16	60462
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	37973
ISDYNVOLMsgCountValidCount_Cnt_M_u16	64729
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	49232
ISDYNVOLMsgLenValidCount_Cnt_M_u16	59708
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	17547
ISDYNVOLMsgTimer_mS_M_u32	3801245440
IgnOnTimer_mS_M_u32	4142573312
IgnTimeOff_Sec_M_u32	1937137488
ManVehSpd_Kph_M_f32	10.3864002
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	107
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	92
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2789660416
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	204
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1791375104
PrevISDATBSI412MsgDLCError_Cnt_M_u08	149
PrevISDATBSI412MsgRxTime_MSec_M_u32	2334713600
PrevISDATBSI432MsgDLCError_Cnt_M_u08	60
PrevISDATBSI432MsgRxTime_MSec_M_u32	1890567936
PrevISDATDIRAMsgTxTime_MSec_M_u32	938272512
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	250
PrevISDYN2CMMMsgRxTime_MSec_M_u32	440432384
PrevISDYNAASMsgDLCError_Cnt_M_u08	186
PrevISDYNAASMsgRxTime_MSec_M_u32	408446720
PrevISDYNABRMsgDLCError_Cnt_M_u08	12
PrevISDYNABRMsgRxTime_MSec_M_u32	1493346048
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	173
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3498141440
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	162
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1191626496
PrevISDYNVOLMsgDLCError_Cnt_M_u08	68
PrevISDYNVOLMsgRxTime_MSec_M_u32	3700025088
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2583041792
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	595.538208
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	27628
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	54112
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	17609
VitesseVehicleBVRampValidCount_Cnt_M_u16	34813
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	51958
VitesseVehicleBVSigValidCount_Cnt_M_u16	6322

Name	Input Value
VitesseVehicleBV_Kph_M_f32	358.55191
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	16347
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	46383
VitesseVehiculeRoues_Kph_M_f32	333.633392
k_AASNTCEnableTimeout_mS_u16	63162
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	30276
k_AASNodeTimeout_mS_u16	25184
k_ABSNodeTimeout_mS_u16	32632
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	13806
k_ANGLEVOLANTSigValidThresh_Cnt_u16	47254
k_AngleVolantInvalidThresh_Cnt_u16	48929
k_AngleVolantValidThresh_Cnt_u16	65411
k_BSI552MsgTimeout_mS_u16	59258
k_BSINTCEnableTimeout_mS_u16	62743
k_BSINodeAbsentDiag_Cnt_str.Threshold	11591
k_BSINodeAbsentDiag_Cnt_str.PStep	58951
k_BSINodeAbsentDiag_Cnt_str.NStep	1451
k_BSINodeAbsentTimeout_mS_u16	61395
k_BSINodeTimeout_mS_u16	56756
k_BattOvHi_Volt_f32	13.1366997
k_BattOvLo_Volt_f32	27.3076
k_BattUvHi_Volt_f32	12.2459002
k_BattUvLo_Volt_f32	23.3068008
k_CAVNTCEnableTimeout_mS_u16	60385
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	51285
k_CAVNodeTimeout_mS_u16	32103
k_CMM388MsgTimeout_mS_u16	53994
k_CMM388NTCEnableTimeout_mS_u16	33142
k_CMMNTCEnableTimeout_mS_u16	31492
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	37307
k_CONSANGLECPKMax_HwDeg_f32	428.510712
k_CONSANGLECPKMin_HwDeg_f32	-283.273499
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	36571
k_CONSANGLECPKSigValidThresh_Cnt_u16	17455
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	35598
k_CPKVehicleSpeedValidThresh_Cnt_u16	13290
k_CityParkInputInvalidThresh_Cnt_u16	18161
k_CityParkInputValidThresh_Cnt_u16	7433
k_ComputerRazGCTSigValidThresh_Cnt_u16	31866
k_CptTemporelSigValidThresh_Cnt_u16	58874
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	16254
k_DMDFCTCPKSigValidThresh_Cnt_u16	26187
k_DMDFCTCPKValidCount_Cnt_u16	8484
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	2866
k_DMDRELAXECPKSigValidThresh_Cnt_u16	53110
k_DMDRelaxeConsistentThresh_Cnt_u16	59940
k_DateValidThresh_Cnt_u16	35265
k_DefaultVehSpd_Kph_f32	86.5691986
k_DiagMuxOnAbsentTimeout_mS_u16	24477
k_EMNodeTimeout_mS_u16	52108
k_ESPNTCEnableTimeout_mS_u16	64155
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	42915
k_EtatMTSigInvalidThresh_Cnt_u16	33710
k_EtatMTSigValidThresh_Cnt_u16	17491
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	57285
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	59582
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	61414
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	32861
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	7709
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	6407
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	17904

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	9752
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	49523
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	54035
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	33187
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	30958
k_ISDATDIRASentDiag_Cnt_str.Threshold	13150
k_ISDATDIRASentDiag_Cnt_str.PStep	38581
k_ISDATDIRASentDiag_Cnt_str.NStep	24929
k_ISDATDIRASentTimeout_mS_u16	24399
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	17047
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	9147
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	28151
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	57027
k_ISDYNAASChkSumValidThresh_Cnt_u16	13608
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	20807
k_ISDYNAASMsgCountValidThresh_Cnt_u16	49443
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	20279
k_ISDYNAASMsgLenValidThresh_Cnt_u16	15828
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	42110
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	42180
k_ISDYNABRChkSumValidThresh_Cnt_u16	21521
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	40252
k_ISDYNABRMsgCountValidThresh_Cnt_u16	13176
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	54155
k_ISDYNABRMsgLenValidThresh_Cnt_u16	16883
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	24899
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	26464
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	46512
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	55211
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	47513
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	52117
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	57243
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	43522
k_ISDYNVOLChkSumValidThresh_Cnt_u16	21810
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	40388
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	54428
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	25333
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	6285
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	20639
k_IgnOnTimeout_mS_u16	15758
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	86.9133987
k_PowerCutVehSpdLowThresh_Kph_f32	185.639999
k_PowerCutVehSpdLowTimeout_mS_u16	51190
k_VBattMaxAAS_Volt_f32	29.4601994
k_VBattMaxBSI_Volt_f32	23.2672005
k_VBattMaxCAV_Volt_f32	4.82070017
k_VBattMaxCMM388_Volt_f32	0.847299993
k_VBattMaxCMM_Volt_f32	19.5960007
k_VBattMaxESP_Volt_f32	11.2551003
k_VBattMinAAS_Volt_f32	26.6989002
k_VBattMinBSI_Volt_f32	11.2551003
k_VBattMinCAV_Volt_f32	15.8141003
k_VBattMinCMM388_Volt_f32	21.8430004
k_VBattMinCMM_Volt_f32	23.4330997
k_VBattMinESP_Volt_f32	19.5960007
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	37097
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	5897
k_VitesseVehicleBVRampValidThresh_Cnt_u16	58197
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	64302
k_VitesseVehicleBVSigValidThresh_Cnt_u16	6142
k_VitesseVehicleBVSpeedPassThresh_kph_f32	648.916077
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	42511
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	29123
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3038119680
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	31061
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2996883200
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	162
target_SrlComInput_Per1_Batt_Volt_f32.value	28.7712002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	734181120
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	180
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.372288167
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	516728576
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2919778048
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1414784768
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	188
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3115288320
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2249926400
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	255
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1637271296
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4095895296
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	212
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	252
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3043788544
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	153
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	176
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	243
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4089685760
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	478103296
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	474670848
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1657812736
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2037
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.793390274
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	989650
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	58.6987991

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	47550		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	2996883200	2996883200	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2996883200	2996883200	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2996883200	2996883200	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2996883200	2996883200	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2996883200	2996883200	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2996883200	2996883200	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2996883200	2996883200	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2996883200	2996883200	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2996883200	2996883200	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2996883200	2996883200	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2996883200	2996883200	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2996883200	2996883200	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2996883200	2996883200	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	43967	43967	✔
CONSANGLECPK_HwDeg_M_f32	-709.563721	-709.563721 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2996883200	2996883200	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2996883200	2996883200	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2996883200	2996883200	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2996883200	2996883200	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2996883200	2996883200	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2996883200	2996883200	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2996883200	2996883200	✔
ESPNTCEnableTimer_mS_M_u32	2996883200	2996883200	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2996883200	2996883200	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2996883200	2996883200	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	20	20	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2996883200	2996883200	✔
ElecIntTimer_mS_M_u32[1]	14	14	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2996883200	2996883200	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2996883200	2996883200	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2996883200	2996883200	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2996883200	2996883200	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2996883200	2996883200	✔
ISDATDIRASentFltAcc_Cnt_M_u16	13150	13150	✔
ISDATDIRASentTimer_mS_M_u32	2996883200	2996883200	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2996883200	2996883200	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2996883200	2996883200	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2996883200	2996883200	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2996883200	2996883200	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2996883200	2996883200	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2996883200	2996883200	✔
IgnOnTimer_mS_M_u32	2996883200	2996883200	✔
IgnTimeOff_Sec_M_u32	1937137488	1937137488	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	131	131	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	516728576	516728576	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	198	198	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2919778048	2919778048	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	75	75	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1414784768	1414784768	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	188	188	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3115288320	3115288320	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	938272512	938272512	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	255	255	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1637271296	1637271296	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4095895296	4095895296	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	252	252	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3043788544	3043788544	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	243	243	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4089685760	4089685760	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	239	239	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	478103296	478103296	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	239	239	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	474670848	474670848	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1657812736	1657812736	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	595.538208	595.538208	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	358.55191	358.55191	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	333.633392	333.633392	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	43967	43967	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1937137488	1937137488	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-709.563721	-709.563721 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.236 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3481042432
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	17146
AASNodeAbsentTimer_mS_M_u32	2472963584
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	26863
ANGLEVOLANTSigValidCount_Cnt_M_u16	24506
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	26503
AngleVolantMsgTimer_mS_M_u32	3481042432
AngleVolantValidCount_Cnt_M_u16	21627
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2383556096
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1765322240
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1693523456
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3036405248
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	2566
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	310484480
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	50699
CAVNodeAbsentTimer_mS_M_u32	1873743360
CDD_SrlComVehSpd_Kph_G_f32	408.265106
CMM388NTCEnableTimer_mS_M_u32	1582255616
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1218776576
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	30553
CMMNodeAbsentTimer_mS_M_u32	3666206208
CONSANGLECPKSigInvalidCount_Cnt_M_u16	63527
CONSANGLECPKSigValidCount_Cnt_M_u16	48450
CONSANGLECPK_Cnt_M_u16	26941
CONSANGLECPK_HwDeg_M_f32	258.585785
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	26941
CPKVehicleSpeedMsgTimer_mS_M_u32	3091955200
CPKVehicleSpeedValidCount_Cnt_M_u16	42247
CityParkInputConsistentCount_Cnt_M_u16	14879

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	19376
CityParkInputMsgTimer_mS_M_u32	516728576
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3792334336
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	24222
ComputerRazGCTSigInvalidTimer_mS_M_u32	4075261440
ComputerRazGCTSigValidCount_Cnt_M_u16	49124
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	33292
DMDFCTCPKSigValidCount_Cnt_M_u16	11967
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	17089
DMDRELAXECPKSigValidCount_Cnt_M_u16	21260
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	17844
DateInvalidTimer_mS_M_u32	1765322240
DiagMuxOnAbsentTimer_mS_M_u32	1038237184
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3036405248
ESPNTCEnableTimer_mS_M_u32	1448570368
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	2272
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	80
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	12
ElecIntTimer_mS_M_u32[1]	19
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1890819584
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	39614
EtatMTSigValidCount_Cnt_M_u16	2485
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	51193
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	9876
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	41397
ISDAT4V2BSI552MsgTimer_mS_M_u32	2619989504
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	23221
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	9845
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	2485
ISDATBSI3F2MsgTimer_mS_M_u32	101727744
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	2240
ISDATBSI412MsgLenValidCount_Cnt_M_u16	54191
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	39614
ISDATBSI412MsgTimer_mS_M_u32	3182067200
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	60413
ISDATBSI432MsgLenValidCount_Cnt_M_u16	28804
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	1564
ISDATDIRASentFltAcc_Cnt_M_u16	45264
ISDATDIRASentTimer_mS_M_u32	3091955200
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	38891
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	21627
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	42147
ISDYN2CMMMsgTimer_mS_M_u32	2153868800
ISDYNAASChkSumInvalidCount_Cnt_M_u16	26828
ISDYNAASChkSumValidCount_Cnt_M_u16	53944
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	40210
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	16966
ISDYNAASMsgLenValidCount_Cnt_M_u16	12842
ISDYNAASMsgTimeValidCount_Cnt_M_u16	26828
ISDYNAASMsgTimer_mS_M_u32	0
ISDYNABRChkSumInvalidCount_Cnt_M_u16	15598
ISDYNABRChkSumValidCount_Cnt_M_u16	1666
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	31715
ISDYNABRMsgCountValidCount_Cnt_M_u16	55567
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	40510
ISDYNABRMsgLenValidCount_Cnt_M_u16	38553
ISDYNABRMsgTimeValidCount_Cnt_M_u16	26941
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	17847

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	37028
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	2485
ISDYNCMM208MsgTimer_mS_M_u32	3558288896
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	17847
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	37028
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	39337
ISDYNCMM388MsgTimer_mS_M_u32	2442579456
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	63573
ISDYNVOLChkSumValidCount_Cnt_M_u16	9200
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	21818
ISDYNVOLMsgCountValidCount_Cnt_M_u16	43117
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	54473
ISDYNVOLMsgLenValidCount_Cnt_M_u16	34501
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	30553
ISDYNVOLMsgTimer_mS_M_u32	3393424896
IgnOnTimer_mS_M_u32	1044041216
IgnTimeOff_Sec_M_u32	1828244
ManVehSpd_Kph_M_f32	606.540588
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	108
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	23
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	484851200
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	89
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2229804544
PrevISDATBSI412MsgDLCError_Cnt_M_u08	163
PrevISDATBSI412MsgRxTime_MSec_M_u32	1249906176
PrevISDATBSI432MsgDLCError_Cnt_M_u08	143
PrevISDATBSI432MsgRxTime_MSec_M_u32	3446369792
PrevISDATDIRAMsgTxTime_MSec_M_u32	1412697600
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	72
PrevISDYN2CMMMsgRxTime_MSec_M_u32	796483072
PrevISDYNAASMsgDLCError_Cnt_M_u08	78
PrevISDYNAASMsgRxTime_MSec_M_u32	3237056000
PrevISDYNABRMsgDLCError_Cnt_M_u08	198
PrevISDYNABRMsgRxTime_MSec_M_u32	2012401152
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	3
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2088144384
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	137
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1717988864
PrevISDYNVOLMsgDLCError_Cnt_M_u08	242
PrevISDYNVOLMsgRxTime_MSec_M_u32	442306048
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	249069056
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	459.246307
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	15220
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	20952
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	25821
VitesseVehicleBVRampValidCount_Cnt_M_u16	59393
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	31704
VitesseVehicleBVSigValidCount_Cnt_M_u16	65379

Name	Input Value
VitesseVehicleBV_Kph_M_f32	644.620483
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	39337
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1644
VitesseVehiculeRoues_Kph_M_f32	369.413391
k_AASNTCEnableTimeout_mS_u16	13388
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	55918
k_AASNodeTimeout_mS_u16	42200
k_ABSNodeTimeout_mS_u16	57297
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	61232
k_ANGLEVOLANTSigValidThresh_Cnt_u16	33783
k_AngleVolantInvalidThresh_Cnt_u16	23638
k_AngleVolantValidThresh_Cnt_u16	19376
k_BSI552MsgTimeout_mS_u16	23435
k_BSINTCEnableTimeout_mS_u16	38325
k_BSINodeAbsentDiag_Cnt_str.Threshold	59725
k_BSINodeAbsentDiag_Cnt_str.PStep	58252
k_BSINodeAbsentDiag_Cnt_str.NStep	15007
k_BSINodeAbsentTimeout_mS_u16	25407
k_BSINodeTimeout_mS_u16	1564
k_BattOvHi_Volt_f32	17.5890999
k_BattOvLo_Volt_f32	8.81429958
k_BattUvHi_Volt_f32	19.0555992
k_BattUvLo_Volt_f32	17.9603004
k_CAVNTCEnableTimeout_mS_u16	32406
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	2617
k_CAVNodeTimeout_mS_u16	23427
k_CMM388MsgTimeout_mS_u16	54778
k_CMM388NTCEnableTimeout_mS_u16	64086
k_CMMNTCEnableTimeout_mS_u16	41069
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	41160
k_CONSANGLECPKMax_HwDeg_f32	455.638885
k_CONSANGLECPKMin_HwDeg_f32	-587.736084
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	44201
k_CONSANGLECPKSigValidThresh_Cnt_u16	22892
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	25294
k_CPKVehicleSpeedValidThresh_Cnt_u16	57019
k_CityParkInputInvalidThresh_Cnt_u16	20324
k_CityParkInputValidThresh_Cnt_u16	14879
k_ComputerRazGCTSigValidThresh_Cnt_u16	62475
k_CptTemporelSigValidThresh_Cnt_u16	13387
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	12606
k_DMDFCTCPKSigValidThresh_Cnt_u16	27033
k_DMDFCTCPKValidCount_Cnt_u16	45390
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	42147
k_DMDRELAXECPKSigValidThresh_Cnt_u16	58518
k_DMDRelaxeConsistentThresh_Cnt_u16	52364
k_DateValidThresh_Cnt_u16	41397
k_DefaultVehSpd_Kph_f32	79.5218964
k_DiagMuxOnAbsentTimeout_mS_u16	17827
k_EMNodeTimeout_mS_u16	17684
k_ESPNTCEnableTimeout_mS_u16	2919
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	65296
k_EtatMTSigInvalidThresh_Cnt_u16	52525
k_EtatMTSigValidThresh_Cnt_u16	38913
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	169
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	17024
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	30088
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	13410
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	55266
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	58212
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	18218

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	50033
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	41121
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	17217
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	62545
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	28846
k_ISDATDIRASentDiag_Cnt_str.Threshold	16715
k_ISDATDIRASentDiag_Cnt_str.PStep	40862
k_ISDATDIRASentDiag_Cnt_str.NStep	15667
k_ISDATDIRASentTimeout_mS_u16	65098
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	63411
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	26503
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	8531
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	20462
k_ISDYNAASChkSumValidThresh_Cnt_u16	22914
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	3811
k_ISDYNAASMsgCountValidThresh_Cnt_u16	44047
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	52882
k_ISDYNAASMsgLenValidThresh_Cnt_u16	57980
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	24639
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	39276
k_ISDYNABRChkSumValidThresh_Cnt_u16	14407
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	40198
k_ISDYNABRMsgCountValidThresh_Cnt_u16	18193
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	51801
k_ISDYNABRMsgLenValidThresh_Cnt_u16	39904
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	43440
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	6424
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	61801
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	12535
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	64495
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	12986
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	2920
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	56435
k_ISDYNVOLChkSumValidThresh_Cnt_u16	6050
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	3181
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	19238
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	38170
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	20753
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	17691
k_IgnOnTimeout_mS_u16	20943
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	86.9891968
k_PowerCutVehSpdLowThresh_Kph_f32	150.809494
k_PowerCutVehSpdLowTimeout_mS_u16	45208
k_VBattMaxAAS_Volt_f32	5.10599995
k_VBattMaxBSI_Volt_f32	14.9836998
k_VBattMaxCAV_Volt_f32	12.2187996
k_VBattMaxCMM388_Volt_f32	11.3127003
k_VBattMaxCMM_Volt_f32	25.5463009
k_VBattMaxESP_Volt_f32	8.51340008
k_VBattMinAAS_Volt_f32	6.78350019
k_VBattMinBSI_Volt_f32	8.51340008
k_VBattMinCAV_Volt_f32	32
k_VBattMinCMM388_Volt_f32	13.9067001
k_VBattMinCMM_Volt_f32	32
k_VBattMinESP_Volt_f32	25.5463009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	54461
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	16156
k_VitesseVehicleBVRampValidThresh_Cnt_u16	26682
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	63216
k_VitesseVehicleBVSigValidThresh_Cnt_u16	23872
k_VitesseVehicleBVSpeedPassThresh_kph_f32	492.040894
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	55563
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	49839
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1765322240
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	40019
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	4122498560
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	137
target_SrlComInput_Per1_Batt_Volt_f32.value	6.96500015
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3555892736
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	252
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.967003644
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	61
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3465858560
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	76
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	392293888
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1526664704
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	213
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2708221440
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4071181824
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1454796288
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3583217152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	45
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	109
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	179
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3795136000
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	50
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	106
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3954167296
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1744629248
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2669284864
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	78
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	108
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	148
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	238
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1154096640
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	796
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.967363119
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	516092
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	227.882996

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	6654		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	4122498560	4122498560	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4122498560	4122498560	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	4122498560	4122498560	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4122498560	4122498560	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4122498560	4122498560	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4122498560	4122498560	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4122498560	4122498560	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	4122498560	4122498560	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4122498560	4122498560	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4122498560	4122498560	✔
CDD_SrlComVehSpd_Kph_G_f32	606.540588	606.540588	✔
CMM388NTCEnableTimer_mS_M_u32	4122498560	4122498560	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4122498560	4122498560	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4122498560	4122498560	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	26941	26941	✔
CONSANGLECPK_HwDeg_M_f32	258.585785	258.585785 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4122498560	4122498560	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	4122498560	4122498560	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4122498560	4122498560	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4122498560	4122498560	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4122498560	4122498560	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4122498560	4122498560	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	4122498560	4122498560	✔
ESPNTCEnableTimer_mS_M_u32	4122498560	4122498560	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4122498560	4122498560	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	80	80	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	12	12	✔
ElecIntTimer_mS_M_u32[1]	19	19	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4122498560	4122498560	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	41397	41397	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4122498560	4122498560	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	2485	2485	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4122498560	4122498560	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	39614	39614	✔
ISDATBSI412MsgTimer_mS_M_u32	4122498560	4122498560	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	1564	1564	✔
ISDATBSI432MsgTimer_mS_M_u32	4122498560	4122498560	✔
ISDATDIRASentFltAcc_Cnt_M_u16	16715	16715	✔
ISDATDIRASentTimer_mS_M_u32	4122498560	4122498560	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	42147	42147	✔
ISDYN2CMMMsgTimer_mS_M_u32	4122498560	4122498560	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	26828	26828	✔
ISDYNAASMsgTimer_mS_M_u32	4122498560	4122498560	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	26941	26941	✔
ISDYNABRMsgTimer_mS_M_u32	4122498560	4122498560	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	2485	2485	✔
ISDYNCMM208MsgTimer_mS_M_u32	4122498560	4122498560	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	39337	39337	✔
ISDYNCMM388MsgTimer_mS_M_u32	4122498560	4122498560	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	30553	30553	✔
ISDYNVOLMsgTimer_mS_M_u32	4122498560	4122498560	✔
IgnOnTimer_mS_M_u32	1044041216	1044041216	✔
IgnTimeOff_Sec_M_u32	1828244	1828244	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	61	61	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3465858560	3465858560	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	76	76	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	392293888	392293888	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1526664704	1526664704	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	213	213	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2708221440	2708221440	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1412697600	1412697600	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	121	121	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1454796288	1454796288	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3583217152	3583217152	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	74	74	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3795136000	3795136000	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	137	137	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3954167296	3954167296	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	106	106	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1744629248	1744629248	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	131	131	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2669284864	2669284864	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1154096640	1154096640	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	459.246307	459.246307	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	644.620483	644.620483	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	369.413391	369.413391	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	26941	26941	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1828244	1828244	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	258.585785	258.585785 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.237 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3969992960
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	44069
AASNodeAbsentTimer_mS_M_u32	4104354048
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	44104
ANGLEVOLANTSigValidCount_Cnt_M_u16	33189
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	45694
AngleVolantMsgTimer_mS_M_u32	3969992960
AngleVolantValidCount_Cnt_M_u16	8229
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1671444736
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2351741184
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1187211520
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	4054001920
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	58627
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	538044672
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	44403
CAVNodeAbsentTimer_mS_M_u32	3393820928
CDD_SrlComVehSpd_Kph_G_f32	383.593689
CMM388NTCEnableTimer_mS_M_u32	3479755008
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2540148992
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	11338
CMMNodeAbsentTimer_mS_M_u32	688204032
CONSANGLECPKSigInvalidCount_Cnt_M_u16	36257
CONSANGLECPKSigValidCount_Cnt_M_u16	14350
CONSANGLECPK_Cnt_M_u16	57373
CONSANGLECPK_HwDeg_M_f32	752.723328
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	57373
CPKVehicleSpeedMsgTimer_mS_M_u32	775178496
CPKVehicleSpeedValidCount_Cnt_M_u16	36263
CityParkInputConsistentCount_Cnt_M_u16	65337
CityParkInputInvalidCount_Cnt_M_u16	40837
CityParkInputMsgTimer_mS_M_u32	3465858560
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2562160896
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	59705

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3265272064
ComputerRazGCTSigValidCount_Cnt_M_u16	49642
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	27761
DMDFCTCPKSigValidCount_Cnt_M_u16	49175
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	59090
DMDRELAXECPKSigValidCount_Cnt_M_u16	28591
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	6394
DateInvalidTimer_mS_M_u32	2351741184
DiagMuxOnAbsentTimer_mS_M_u32	1752172800
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4054001920
ESPNTCEnableTimer_mS_M_u32	2949675264
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	8564
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	150
EffacDefaultDiagTimer_mS_M_u32[1]	1150
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	79
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1299966208
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	59163
EtatMTSigValidCount_Cnt_M_u16	1012
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	58923
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	50200
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	48949
ISDAT4V2BSI552MsgTimer_mS_M_u32	1947805952
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	15540
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	25398
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	1012
ISDATBSI3F2MsgTimer_mS_M_u32	1206257920
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	11158
ISDATBSI412MsgLenValidCount_Cnt_M_u16	5255
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	59163
ISDATBSI412MsgTimer_mS_M_u32	1511475456
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	24158
ISDATBSI432MsgLenValidCount_Cnt_M_u16	31368
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	28992
ISDATDIRASentFltAcc_Cnt_M_u16	16676
ISDATDIRASentTimer_mS_M_u32	775178496
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	35859
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	8229
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	8364
ISDYN2CMMMsgTimer_mS_M_u32	3652352256
ISDYNAASChkSumInvalidCount_Cnt_M_u16	687
ISDYNAASChkSumValidCount_Cnt_M_u16	65197
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	25184
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	58562
ISDYNAASMsgLenValidCount_Cnt_M_u16	11992
ISDYNAASMsgTimeValidCount_Cnt_M_u16	687
ISDYNAASMsgTimer_mS_M_u32	4294967295
ISDYNABRChkSumInvalidCount_Cnt_M_u16	58826
ISDYNABRChkSumValidCount_Cnt_M_u16	25295
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	58730
ISDYNABRMsgCountValidCount_Cnt_M_u16	1960
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	46940
ISDYNABRMsgLenValidCount_Cnt_M_u16	51209
ISDYNABRMsgTimeValidCount_Cnt_M_u16	57373
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	44343
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	60464
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	1012
ISDYNCMM208MsgTimer_mS_M_u32	3851499776
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	44343
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	60464
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	34971

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3012712704
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	50455
ISDYNVOLChkSumValidCount_Cnt_M_u16	15364
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	10983
ISDYNVOLMsgCountValidCount_Cnt_M_u16	35597
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	41401
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1415
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	11338
ISDYNVOLMsgTimer_mS_M_u32	2894862592
IgnOnTimer_mS_M_u32	1034311936
IgnTimeOff_Sec_M_u32	2875930046
ManVehSpd_Kph_M_f32	454.721802
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	109
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	146
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3680766208
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	25
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2195613952
PrevISDATBSI412MsgDLCError_Cnt_M_u08	79
PrevISDATBSI412MsgRxTime_MSec_M_u32	3184957696
PrevISDATBSI432MsgDLCError_Cnt_M_u08	226
PrevISDATBSI432MsgRxTime_MSec_M_u32	2593421568
PrevISDATDIRAMsgTxTime_MSec_M_u32	1891277056
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	224
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1479190784
PrevISDYNAASMsgDLCError_Cnt_M_u08	248
PrevISDYNAASMsgRxTime_MSec_M_u32	8526080
PrevISDYNABRMsgDLCError_Cnt_M_u08	77
PrevISDYNABRMsgRxTime_MSec_M_u32	1887328512
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	52
PrevISDYNCMM208MsgRxTime_MSec_M_u32	569579776
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	114
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2074310912
PrevISDYNVOLMsgDLCError_Cnt_M_u08	72
PrevISDYNVOLMsgRxTime_MSec_M_u32	37722368
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2660059392
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	10.1611004
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	12600
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1998
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	39165
VitesseVehicleBVRampValidCount_Cnt_M_u16	10579
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	22413
VitesseVehicleBVSigValidCount_Cnt_M_u16	34474
VitesseVehicleBV_Kph_M_f32	374.452606
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	34971
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	56337
VitesseVehiculeRoues_Kph_M_f32	280.941711
k_AASNTCEnableTimeout_mS_u16	31472
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	6732
k_AASNodeTimeout_mS_u16	3790
k_ABSNodeTimeout_mS_u16	42786
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	57541
k_ANGLEVOLANTSigValidThresh_Cnt_u16	52271
k_AngleVolantInvalidThresh_Cnt_u16	32530
k_AngleVolantValidThresh_Cnt_u16	40837
k_BSI552MsgTimeout_mS_u16	6324
k_BSINTCEnableTimeout_mS_u16	16694
k_BSINodeAbsentDiag_Cnt_str.Threshold	61942
k_BSINodeAbsentDiag_Cnt_str.PStep	37752
k_BSINodeAbsentDiag_Cnt_str.NStep	28287
k_BSINodeAbsentTimeout_mS_u16	40790
k_BSINodeTimeout_mS_u16	28992
k_BattOvHi_Volt_f32	16.0842991
k_BattOvLo_Volt_f32	6.1953001
k_BattUvHi_Volt_f32	15.3030005
k_BattUvLo_Volt_f32	19.8265991
k_CAVNTCEnableTimeout_mS_u16	7891
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	6377
k_CAVNodeTimeout_mS_u16	54157
k_CMM388MsgTimeout_mS_u16	62245
k_CMM388NTCEnableTimeout_mS_u16	62993
k_CMMNTCEnableTimeout_mS_u16	19340
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	31997
k_CONSANGLECPKMax_HwDeg_f32	735.343018
k_CONSANGLECPKMin_HwDeg_f32	-640.349609
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	20379
k_CONSANGLECPKSigValidThresh_Cnt_u16	58129
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	11500
k_CPKVehicleSpeedValidThresh_Cnt_u16	21925
k_CityParkInputInvalidThresh_Cnt_u16	1640
k_CityParkInputValidThresh_Cnt_u16	65337
k_ComputerRazGCTSigValidThresh_Cnt_u16	18610
k_CptTemporelSigValidThresh_Cnt_u16	4532
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	65116
k_DMDFCTCPKSigValidThresh_Cnt_u16	20233
k_DMDFCTCPKValidCount_Cnt_u16	3883
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	8364
k_DMDRELAXECPKSigValidThresh_Cnt_u16	47762
k_DMDRelaxeConsistentThresh_Cnt_u16	23216
k_DateValidThresh_Cnt_u16	48949
k_DefaultVehSpd_Kph_f32	121.023102
k_DiagMuxOnAbsentTimeout_mS_u16	25323
k_EMNodeTimeout_mS_u16	39642
k_ESPNTCEnableTimeout_mS_u16	19807
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	33317
k_EtatMTSigInvalidThresh_Cnt_u16	61709
k_EtatMTSigValidThresh_Cnt_u16	27218
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	32603
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	41877
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	12542
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	41901
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	17135
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	11178
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	16599
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	30145
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	53362
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	25105
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	6307
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	31947
k_ISDATDIRASentDiag_Cnt_str.Threshold	47919

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	26416
k_ISDATDIRASentDiag_Cnt_str.NStep	62887
k_ISDATDIRASentTimeout_mS_u16	4534
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	15292
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	45694
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	48027
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	44234
k_ISDYNAASChkSumValidThresh_Cnt_u16	27087
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	11370
k_ISDYNAASMsgCountValidThresh_Cnt_u16	36520
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	49374
k_ISDYNAASMsgLenValidThresh_Cnt_u16	58850
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	22359
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	64978
k_ISDYNABRChkSumValidThresh_Cnt_u16	6911
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	11267
k_ISDYNABRMsgCountValidThresh_Cnt_u16	59296
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	13130
k_ISDYNABRMsgLenValidThresh_Cnt_u16	26740
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	64451
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	10316
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	21915
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	42609
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	62280
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	2213
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	16477
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	15485
k_ISDYNVOLChkSumValidThresh_Cnt_u16	54446
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	35533
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	9443
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	26631
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	40416
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	60675
k_IgnOnTimeout_mS_u16	19561
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	73.1212006
k_PowerCutVehSpdLowThresh_Kph_f32	81.6603012
k_PowerCutVehSpdLowTimeout_mS_u16	13836
k_VBattMaxAAS_Volt_f32	13.7620001
k_VBattMaxBSI_Volt_f32	10.2321997
k_VBattMaxCAV_Volt_f32	27.8404007
k_VBattMaxCMM388_Volt_f32	3.03710008
k_VBattMaxCMM_Volt_f32	12.8979998
k_VBattMaxESP_Volt_f32	25.1637001
k_VBattMinAAS_Volt_f32	28.5487995
k_VBattMinBSI_Volt_f32	25.1637001
k_VBattMinCAV_Volt_f32	5.54449987
k_VBattMinCMM388_Volt_f32	29.5121002
k_VBattMinCMM_Volt_f32	4.5703001
k_VBattMinESP_Volt_f32	12.8979998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	19614
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	5952
k_VitesseVehicleBVRampValidThresh_Cnt_u16	61927
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	49924
k_VitesseVehicleBVSigValidThresh_Cnt_u16	22998
k_VitesseVehicleBVSpeedPassThresh_kph_f32	645.673218
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	29811
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	53577
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2351741184
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	54100
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3612197120
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	114
target_SrlComInput_Per1_Batt_Volt_f32.value	31
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3753830656
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	27
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.512578368
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	80
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1956141312
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3065051392
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	207
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1213831424
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	191
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	294795520
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4200257792
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	139
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3937630464
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	54
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3399227648
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	205
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3006740736
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1229412608
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4041210112
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	228
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2819135744
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	43
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	174
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	207
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1261988096
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2563
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.165821984
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	443406
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	249.689804
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	15770

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3612197120	3612197120	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3612197120	3612197120	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3612197120	3612197120	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3612197120	3612197120	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3612197120	3612197120	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3612197120	3612197120	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3612197120	3612197120	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3612197120	3612197120	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3612197120	3612197120	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3612197120	3612197120	✔
CDD_SrlComVehSpd_Kph_G_f32	454.721802	454.721802	✔
CMM388NTCEnableTimer_mS_M_u32	3612197120	3612197120	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3612197120	3612197120	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3612197120	3612197120	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	57373	57373	✔
CONSANGLECPK_HwDeg_M_f32	752.723328	752.723328 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3612197120	3612197120	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3612197120	3612197120	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3612197120	3612197120	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3612197120	3612197120	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3612197120	3612197120	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3612197120	3612197120	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3612197120	3612197120	✔
ESPNTCEnableTimer_mS_M_u32	3612197120	3612197120	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3612197120	3612197120	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	150	150	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1150	1150	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	79	79	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3612197120	3612197120	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	48949	48949	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3612197120	3612197120	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	1012	1012	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3612197120	3612197120	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	59163	59163	✔
ISDATBSI412MsgTimer_mS_M_u32	3612197120	3612197120	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	28992	28992	✔
ISDATBSI432MsgTimer_mS_M_u32	3612197120	3612197120	✔
ISDATDIRASentFltAcc_Cnt_M_u16	47919	47919	✔
ISDATDIRASentTimer_mS_M_u32	3612197120	3612197120	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	8364	8364	✔
ISDYN2CMMMsgTimer_mS_M_u32	3612197120	3612197120	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	687	687	✔
ISDYNAASMsgTimer_mS_M_u32	3612197120	3612197120	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	57373	57373	✔
ISDYNABRMsgTimer_mS_M_u32	3612197120	3612197120	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	1012	1012	✔
ISDYNCMM208MsgTimer_mS_M_u32	3612197120	3612197120	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	34971	34971	✔
ISDYNCMM388MsgTimer_mS_M_u32	3612197120	3612197120	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	11338	11338	✔
ISDYNVOLMsgTimer_mS_M_u32	3612197120	3612197120	✔
IgnOnTimer_mS_M_u32	1034311936	1034311936	✔
IgnTimeOff_Sec_M_u32	2875930046	2875930046	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	80	80	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1956141312	1956141312	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	162	162	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3065051392	3065051392	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	207	207	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1213831424	1213831424	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	191	191	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	294795520	294795520	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1891277056	1891277056	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	139	139	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3937630464	3937630464	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	54	54	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3399227648	3399227648	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	194	194	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3006740736	3006740736	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	154	154	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1229412608	1229412608	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	113	113	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4041210112	4041210112	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	228	228	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2819135744	2819135744	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1261988096	1261988096	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	10.1611004	10.1611004	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	374.452606	374.452606	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	280.941711	280.941711	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	57373	57373	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2875930046	2875930046	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	752.723328	752.723328 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.238 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4196329472
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	28049
AASNodeAbsentTimer_mS_M_u32	3872937984
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	5929
ANGLEVOLANTSigValidCount_Cnt_M_u16	27088
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	65158
AngleVolantMsgTimer_mS_M_u32	4196329472
AngleVolantValidCount_Cnt_M_u16	6162
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2095192064
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3577518080
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2620950528
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3399043072
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	6392
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1783433216
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	51751
CAVNodeAbsentTimer_mS_M_u32	644216832
CDD_SrlComVehSpd_Kph_G_f32	467.662994
CMM388NTCEnableTimer_mS_M_u32	2752002048
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3071014912
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	38242
CMMNodeAbsentTimer_mS_M_u32	745752576
CONSANGLECPKSigInvalidCount_Cnt_M_u16	50719
CONSANGLECPKSigValidCount_Cnt_M_u16	55702
CONSANGLECPK_Cnt_M_u16	56681
CONSANGLECPK_HwDeg_M_f32	684.490723
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	56681
CPKVehicleSpeedMsgTimer_mS_M_u32	1097197568
CPKVehicleSpeedValidCount_Cnt_M_u16	21012
CityParkInputConsistentCount_Cnt_M_u16	51926
CityParkInputInvalidCount_Cnt_M_u16	27377
CityParkInputMsgTimer_mS_M_u32	1956141312
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1251760128
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	1621

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3076683776
ComputerRazGCTSigValidCount_Cnt_M_u16	34499
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	46125
DMDFCTCPKSigValidCount_Cnt_M_u16	44028
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	3979
DMDRELAXECPKSigValidCount_Cnt_M_u16	18354
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	51220
DateInvalidTimer_mS_M_u32	3577518080
DiagMuxOnAbsentTimer_mS_M_u32	833792000
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3399043072
ESPNTCEnableTimer_mS_M_u32	2840680448
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	47269
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	64
EffacDefaultDiagTimer_mS_M_u32[1]	894
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2500
ElecIntTimer_mS_M_u32[1]	3504
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	168757248
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	62961
EtatMTSigValidCount_Cnt_M_u16	25124
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	25729
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	56696
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	42658
ISDAT4V2BSI552MsgTimer_mS_M_u32	2604091392
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	13475
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	9182
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	25124
ISDATBSI3F2MsgTimer_mS_M_u32	3947931648
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	32000
ISDATBSI412MsgLenValidCount_Cnt_M_u16	58603
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	62961
ISDATBSI412MsgTimer_mS_M_u32	163375104
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	20262
ISDATBSI432MsgLenValidCount_Cnt_M_u16	64873
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	62144
ISDATDIRASentFltAcc_Cnt_M_u16	4884
ISDATDIRASentTimer_mS_M_u32	1097197568
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	12679
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	6162
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	17276
ISDYN2CMMMsgTimer_mS_M_u32	866867200
ISDYNAASChkSumInvalidCount_Cnt_M_u16	4595
ISDYNAASChkSumValidCount_Cnt_M_u16	28858
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	64865
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	8250
ISDYNAASMsgLenValidCount_Cnt_M_u16	62648
ISDYNAASMsgTimeValidCount_Cnt_M_u16	4595
ISDYNAASMsgTimer_mS_M_u32	490344192
ISDYNABRChkSumInvalidCount_Cnt_M_u16	18980
ISDYNABRChkSumValidCount_Cnt_M_u16	17875
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	5570
ISDYNABRMsgCountValidCount_Cnt_M_u16	457
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	62702
ISDYNABRMsgLenValidCount_Cnt_M_u16	54693
ISDYNABRMsgTimeValidCount_Cnt_M_u16	56681
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	28291
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	21080
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	25124
ISDYNCMM208MsgTimer_mS_M_u32	4212070400
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	28291
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	21080
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	14000

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2106308608
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	30653
ISDYNVOLChkSumValidCount_Cnt_M_u16	9652
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	53451
ISDYNVOLMsgCountValidCount_Cnt_M_u16	41754
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	35798
ISDYNVOLMsgLenValidCount_Cnt_M_u16	62253
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	38242
ISDYNVOLMsgTimer_mS_M_u32	2845734912
IgnOnTimer_mS_M_u32	793753600
IgnTimeOff_Sec_M_u32	1257463428
ManVehSpd_Kph_M_f32	225.435699
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	110
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	141
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2832640000
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	25
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	333940736
PrevISDATBSI412MsgDLCError_Cnt_M_u08	53
PrevISDATBSI412MsgRxTime_MSec_M_u32	3216963584
PrevISDATBSI432MsgDLCError_Cnt_M_u08	124
PrevISDATBSI432MsgRxTime_MSec_M_u32	4177876992
PrevISDATDIRAMsgTxTime_MSec_M_u32	923990016
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	4
PrevISDYN2CMMMsgRxTime_MSec_M_u32	352503808
PrevISDYNAASMsgDLCError_Cnt_M_u08	61
PrevISDYNAASMsgRxTime_MSec_M_u32	96237568
PrevISDYNABRMsgDLCError_Cnt_M_u08	7
PrevISDYNABRMsgRxTime_MSec_M_u32	4140283904
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	114
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2775152640
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	75
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1373132800
PrevISDYNVOLMsgDLCError_Cnt_M_u08	153
PrevISDYNVOLMsgRxTime_MSec_M_u32	3598972928
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2488985600
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	280.408386
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	37592
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	49622
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	44937
VitesseVehicleBVRampValidCount_Cnt_M_u16	45383
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	26970
VitesseVehicleBVSigValidCount_Cnt_M_u16	44737
VitesseVehicleBV_Kph_M_f32	364.331207
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	14000
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	28431
VitesseVehiculeRoues_Kph_M_f32	120.560997
k_AASNTCEnableTimeout_mS_u16	6384
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	34205
k_AASNodeTimeout_mS_u16	44246
k_ABSNodeTimeout_mS_u16	2074
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	9201
k_ANGLEVOLANTSigValidThresh_Cnt_u16	25716
k_AngleVolantInvalidThresh_Cnt_u16	38859
k_AngleVolantValidThresh_Cnt_u16	27377
k_BSI552MsgTimeout_mS_u16	1318
k_BSINTCEnableTimeout_mS_u16	1694
k_BSINodeAbsentDiag_Cnt_str.Threshold	4552
k_BSINodeAbsentDiag_Cnt_str.PStep	31872
k_BSINodeAbsentDiag_Cnt_str.NStep	19115
k_BSINodeAbsentTimeout_mS_u16	38910
k_BSINodeTimeout_mS_u16	62144
k_BattOvHi_Volt_f32	31.5
k_BattOvLo_Volt_f32	7.56780005
k_BattUvHi_Volt_f32	23.2499008
k_BattUvLo_Volt_f32	5.96589994
k_CAVNTCEnableTimeout_mS_u16	42247
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	57285
k_CAVNodeTimeout_mS_u16	42075
k_CMM388MsgTimeout_mS_u16	39057
k_CMM388NTCEnableTimeout_mS_u16	16333
k_CMMNTCEnableTimeout_mS_u16	26651
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	15435
k_CONSANGLECPKMax_HwDeg_f32	716.652405
k_CONSANGLECPKMin_HwDeg_f32	-366.817596
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	57776
k_CONSANGLECPKSigValidThresh_Cnt_u16	23055
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	19068
k_CPKVehicleSpeedValidThresh_Cnt_u16	64211
k_CityParkInputInvalidThresh_Cnt_u16	57418
k_CityParkInputValidThresh_Cnt_u16	51926
k_ComputerRazGCTSigValidThresh_Cnt_u16	34985
k_CptTemporelSigValidThresh_Cnt_u16	36964
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	8174
k_DMDFCTCPKSigValidThresh_Cnt_u16	16549
k_DMDFCTCPKValidCount_Cnt_u16	14976
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	17276
k_DMDRELAXECPKSigValidThresh_Cnt_u16	26763
k_DMDRelaxeConsistentThresh_Cnt_u16	32817
k_DateValidThresh_Cnt_u16	42658
k_DefaultVehSpd_Kph_f32	47.4415016
k_DiagMuxOnAbsentTimeout_mS_u16	3327
k_EMNodeTimeout_mS_u16	49780
k_ESPNTCEnableTimeout_mS_u16	39523
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	52435
k_EtatMTSigInvalidThresh_Cnt_u16	62555
k_EtatMTSigValidThresh_Cnt_u16	64330
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	53039
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	42306
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	35207
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	9144
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	43187
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	52420
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	52155
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	12222
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	18666
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	10125
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	42648
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	61024
k_ISDATDIRASentDiag_Cnt_str.Threshold	4736

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	39317
k_ISDATDIRASentDiag_Cnt_str.NStep	39046
k_ISDATDIRASentTimeout_mS_u16	30304
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	46477
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	65158
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	16303
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	62756
k_ISDYNAASChkSumValidThresh_Cnt_u16	12499
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	16578
k_ISDYNAASMsgCountValidThresh_Cnt_u16	27849
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	2280
k_ISDYNAASMsgLenValidThresh_Cnt_u16	30618
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	25340
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	31116
k_ISDYNABRChkSumValidThresh_Cnt_u16	13507
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	17400
k_ISDYNABRMsgCountValidThresh_Cnt_u16	58335
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	32866
k_ISDYNABRMsgLenValidThresh_Cnt_u16	58277
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	62326
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	64924
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	21233
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	12781
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	16937
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	54480
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	59497
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	42571
k_ISDYNVOLChkSumValidThresh_Cnt_u16	118
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	8346
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	20375
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	9005
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	17504
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	54584
k_IgnOnTimeout_mS_u16	9863
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	11.6471004
k_PowerCutVehSpdLowThresh_Kph_f32	154.029907
k_PowerCutVehSpdLowTimeout_mS_u16	22428
k_VBattMaxAAS_Volt_f32	30.4519005
k_VBattMaxBSI_Volt_f32	28.7306004
k_VBattMaxCAV_Volt_f32	13.9654999
k_VBattMaxCMM388_Volt_f32	5.93989992
k_VBattMaxCMM_Volt_f32	16.6725998
k_VBattMaxESP_Volt_f32	30.3745003
k_VBattMinAAS_Volt_f32	25.6334
k_VBattMinBSI_Volt_f32	30.3745003
k_VBattMinCAV_Volt_f32	31.7077007
k_VBattMinCMM388_Volt_f32	21.7444992
k_VBattMinCMM_Volt_f32	6.94770002
k_VBattMinESP_Volt_f32	16.6725998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	35559
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	3522
k_VitesseVehicleBVRampValidThresh_Cnt_u16	31691
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	37044
k_VitesseVehicleBVSigValidThresh_Cnt_u16	28415
k_VitesseVehicleBVSpeedPassThresh_kph_f32	110.224899
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	29991
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	4453
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3577518080
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	15965
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2717483008
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	75
target_SrlComInput_Per1_Batt_Volt_f32.value	30.9032001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	524683264
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	73
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.594602942
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3531192320
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3064977408
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3962959872
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	211
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3138131968
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1798453248
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1151883264
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2406381568
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	97
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	135
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	230
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	239
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	157
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2854033408
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	85
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	117
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	180
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	197
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	199
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3496785920
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2216876032
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1227421696
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	19
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	133
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	172
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	196
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2732165120
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	911
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.925352335
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	26995
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	244.191299
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	30130

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2717483008	2717483008	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
CDD_SrlComVehSpd_Kph_G_f32	225.435699	225.435699	✔
CMM388NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	56681	56681	✔
CONSANGLECPK_HwDeg_M_f32	684.490723	684.490723 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2717483008	2717483008	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2717483008	2717483008	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2717483008	2717483008	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2717483008	2717483008	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2717483008	2717483008	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2717483008	2717483008	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2717483008	2717483008	✔
ESPNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	64	64	✔
EffacDefaultDiagTimer_mS_M_u32[1]	894	894	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2500	2500	✔
ElecIntTimer_mS_M_u32[1]	3504	3504	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2717483008	2717483008	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	42658	42658	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	25124	25124	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	62961	62961	✔
ISDATBSI412MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	62144	62144	✔
ISDATBSI432MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATDIRASentFltAcc_Cnt_M_u16	4736	4736	✔
ISDATDIRASentTimer_mS_M_u32	2717483008	2717483008	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	17276	17276	✔
ISDYN2CMMMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	4595	4595	✔
ISDYNAASMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	56681	56681	✔
ISDYNABRMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	25124	25124	✔
ISDYNCMM208MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	14000	14000	✔
ISDYNCMM388MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	38242	38242	✔
ISDYNVOLMsgTimer_mS_M_u32	2717483008	2717483008	✔
IgnOnTimer_mS_M_u32	793753600	793753600	✔
IgnTimeOff_Sec_M_u32	1257463428	1257463428	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	192	192	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3531192320	3531192320	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	86	86	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3064977408	3064977408	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	154	154	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3962959872	3962959872	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	211	211	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3138131968	3138131968	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	923990016	923990016	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	70	70	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1151883264	1151883264	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	15	15	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2406381568	2406381568	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	157	157	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2854033408	2854033408	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3496785920	3496785920	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2216876032	2216876032	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	215	215	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1227421696	1227421696	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2732165120	2732165120	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	280.408386	280.408386	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	364.331207	364.331207	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	120.560997	120.560997	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	56681	56681	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1257463428	1257463428	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	684.490723	684.490723 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	225.435699	225.435699	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.239 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1390545664
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	57994
AASNodeAbsentTimer_mS_M_u32	2121644800
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	59329
ANGLEVOLANTSigValidCount_Cnt_M_u16	30604
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	17323
AngleVolantMsgTimer_mS_M_u32	1390545664
AngleVolantValidCount_Cnt_M_u16	53127
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	324565760
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2487810816
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1528113920
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1123216128
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	56916
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3805784832
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	43849
CAVNodeAbsentTimer_mS_M_u32	2118966016
CDD_SrlComVehSpd_Kph_G_f32	636.523987
CMM388NTCEnableTimer_mS_M_u32	1583749888
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3831159552
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	29272
CMMNodeAbsentTimer_mS_M_u32	90499840
CONSANGLECPKSigInvalidCount_Cnt_M_u16	57823
CONSANGLECPKSigValidCount_Cnt_M_u16	28474
CONSANGLECPK_Cnt_M_u16	28609
CONSANGLECPK_HwDeg_M_f32	-719.163818
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	28609
CPKVehicleSpeedMsgTimer_mS_M_u32	1494027008
CPKVehicleSpeedValidCount_Cnt_M_u16	47593
CityParkInputConsistentCount_Cnt_M_u16	51003
CityParkInputInvalidCount_Cnt_M_u16	25577
CityParkInputMsgTimer_mS_M_u32	3531192320
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1663679232
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	10302

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1566006016
ComputerRazGCTSigValidCount_Cnt_M_u16	34676
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	30773
DMDFCTCPKSigValidCount_Cnt_M_u16	47240
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	1691
DMDRELAXECPKSigValidCount_Cnt_M_u16	58854
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	61440
DateInvalidTimer_mS_M_u32	2487810816
DiagMuxOnAbsentTimer_mS_M_u32	2871446272
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1123216128
ESPNTCEnableTimer_mS_M_u32	1527429888
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	79
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1123
EffacDefaultDiagTimer_mS_M_u32[1]	5523
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	20
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2341579520
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	40362
EtatMTSigValidCount_Cnt_M_u16	4305
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	3769
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	27540
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	57494
ISDAT4V2BSI552MsgTimer_mS_M_u32	3373853440
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	8979
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	11554
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	4305
ISDATBSI3F2MsgTimer_mS_M_u32	1984744192
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	2814
ISDATBSI412MsgLenValidCount_Cnt_M_u16	27389
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	40362
ISDATBSI412MsgTimer_mS_M_u32	470289152
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	21772
ISDATBSI432MsgLenValidCount_Cnt_M_u16	16899
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	54654
ISDATDIRASentFltAcc_Cnt_M_u16	50306
ISDATDIRASentTimer_mS_M_u32	1494027008
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	27495
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	53127
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	50760
ISDYN2CMMMsgTimer_mS_M_u32	2751249152
ISDYNAASChkSumInvalidCount_Cnt_M_u16	64868
ISDYNAASChkSumValidCount_Cnt_M_u16	59599
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	7066
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	46352
ISDYNAASMsgLenValidCount_Cnt_M_u16	8019
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0
ISDYNAASMsgTimer_mS_M_u32	1538398976
ISDYNABRChkSumInvalidCount_Cnt_M_u16	45137
ISDYNABRChkSumValidCount_Cnt_M_u16	25861
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	60919
ISDYNABRMsgCountValidCount_Cnt_M_u16	12706
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	20850
ISDYNABRMsgLenValidCount_Cnt_M_u16	30477
ISDYNABRMsgTimeValidCount_Cnt_M_u16	28609
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	29499
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	58750
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	4305
ISDYNCMM208MsgTimer_mS_M_u32	2362538752
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	29499
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	58750
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	27565

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1071356672
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	50437
ISDYNVOLChkSumValidCount_Cnt_M_u16	33504
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	6747
ISDYNVOLMsgCountValidCount_Cnt_M_u16	52014
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	35516
ISDYNVOLMsgLenValidCount_Cnt_M_u16	40055
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	29272
ISDYNVOLMsgTimer_mS_M_u32	1990417152
IgnOnTimer_mS_M_u32	982489856
IgnTimeOff_Sec_M_u32	31671922
ManVehSpd_Kph_M_f32	137.055099
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	111
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3585788672
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	9
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1879583488
PrevISDATBSI412MsgDLCError_Cnt_M_u08	118
PrevISDATBSI412MsgRxTime_MSec_M_u32	1447156480
PrevISDATBSI432MsgDLCError_Cnt_M_u08	160
PrevISDATBSI432MsgRxTime_MSec_M_u32	1005501184
PrevISDATDIRAMsgTxTime_MSec_M_u32	1078319872
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	132
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3921046272
PrevISDYNAASMsgDLCError_Cnt_M_u08	84
PrevISDYNAASMsgRxTime_MSec_M_u32	1514756864
PrevISDYNABRMsgDLCError_Cnt_M_u08	153
PrevISDYNABRMsgRxTime_MSec_M_u32	3290929920
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	248
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1866619648
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	185
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1031125760
PrevISDYNVOLMsgDLCError_Cnt_M_u08	87
PrevISDYNVOLMsgRxTime_MSec_M_u32	1710414592
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1949174528
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	526.564819
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	21814
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	45049
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	803
VitesseVehicleBVRampValidCount_Cnt_M_u16	58790
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	62766
VitesseVehicleBVSigValidCount_Cnt_M_u16	44217
VitesseVehicleBV_Kph_M_f32	26.1049995
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	27565
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	10832
VitesseVehiculeRoues_Kph_M_f32	361.304291
k_AASNTCEnableTimeout_mS_u16	39212
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	29414
k_AASNodeTimeout_mS_u16	61177
k_ABSNodeTimeout_mS_u16	28782
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	49835
k_ANGLEVOLANTSigValidThresh_Cnt_u16	63714
k_AngleVolantInvalidThresh_Cnt_u16	31453
k_AngleVolantValidThresh_Cnt_u16	25577
k_BSI552MsgTimeout_mS_u16	33803
k_BSINTCEnableTimeout_mS_u16	3748
k_BSINodeAbsentDiag_Cnt_str.Threshold	13549
k_BSINodeAbsentDiag_Cnt_str.PStep	1798
k_BSINodeAbsentDiag_Cnt_str.NStep	32451
k_BSINodeAbsentTimeout_mS_u16	22339
k_BSINodeTimeout_mS_u16	54654
k_BattOvHi_Volt_f32	6.08930016
k_BattOvLo_Volt_f32	12.7476997
k_BattUvHi_Volt_f32	31.5
k_BattUvLo_Volt_f32	29.6772003
k_CAVNTCEnableTimeout_mS_u16	36263
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	25199
k_CAVNodeTimeout_mS_u16	14123
k_CMM388MsgTimeout_mS_u16	24970
k_CMM388NTCEnableTimeout_mS_u16	23510
k_CMMNTCEnableTimeout_mS_u16	26795
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	45724
k_CONSANGLECPKMax_HwDeg_f32	410.396088
k_CONSANGLECPKMin_HwDeg_f32	-216.550095
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	27309
k_CONSANGLECPKSigValidThresh_Cnt_u16	26960
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	11783
k_CPKVehicleSpeedValidThresh_Cnt_u16	40325
k_CityParkInputInvalidThresh_Cnt_u16	1503
k_CityParkInputValidThresh_Cnt_u16	51003
k_ComputerRazGCTSigValidThresh_Cnt_u16	48897
k_CptTemporelSigValidThresh_Cnt_u16	32656
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	53362
k_DMDFCTCPKSigValidThresh_Cnt_u16	13837
k_DMDFCTCPKValidCount_Cnt_u16	39356
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	50760
k_DMDRELAXECPKSigValidThresh_Cnt_u16	32475
k_DMDRelaxeConsistentThresh_Cnt_u16	20457
k_DateValidThresh_Cnt_u16	57494
k_DefaultVehSpd_Kph_f32	35.4206009
k_DiagMuxOnAbsentTimeout_mS_u16	47359
k_EMNodeTimeout_mS_u16	32992
k_ESPNTCEnableTimeout_mS_u16	10901
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	8452
k_EtatMTSigInvalidThresh_Cnt_u16	19884
k_EtatMTSigValidThresh_Cnt_u16	57504
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	11246
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	57718
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	36648
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	59860
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	12963
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	11186
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	29517
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	16132
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	30656
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	8533
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	48117
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	34781
k_ISDATDIRASentDiag_Cnt_str.Threshold	44440

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	55056
k_ISDATDIRASentDiag_Cnt_str.NStep	15158
k_ISDATDIRASentTimeout_mS_u16	7069
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	9814
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	17323
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	27313
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	44881
k_ISDYNAASChkSumValidThresh_Cnt_u16	41989
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	27895
k_ISDYNAASMsgCountValidThresh_Cnt_u16	61602
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	33797
k_ISDYNAASMsgLenValidThresh_Cnt_u16	40621
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	7498
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	48024
k_ISDYNABRChkSumValidThresh_Cnt_u16	20915
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	23892
k_ISDYNABRMsgCountValidThresh_Cnt_u16	1375
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	45400
k_ISDYNABRMsgLenValidThresh_Cnt_u16	32591
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	62106
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	9450
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	36139
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	31668
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	26305
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	13964
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	52097
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	31517
k_ISDYNVOLChkSumValidThresh_Cnt_u16	1116
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	56432
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	22457
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	1526
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	23069
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	11476
k_IgnOnTimeout_mS_u16	60009
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	169.303894
k_PowerCutVehSpdLowThresh_Kph_f32	6.1553998
k_PowerCutVehSpdLowTimeout_mS_u16	36136
k_VBattMaxAAS_Volt_f32	7.09600019
k_VBattMaxBSI_Volt_f32	16.1914997
k_VBattMaxCAV_Volt_f32	12.3078003
k_VBattMaxCMM388_Volt_f32	19.6912994
k_VBattMaxCMM_Volt_f32	31.5470009
k_VBattMaxESP_Volt_f32	3.94420004
k_VBattMinAAS_Volt_f32	1.92519999
k_VBattMinBSI_Volt_f32	3.94420004
k_VBattMinCAV_Volt_f32	7.5177002
k_VBattMinCMM388_Volt_f32	16.5890999
k_VBattMinCMM_Volt_f32	32
k_VBattMinESP_Volt_f32	31.5470009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	36424
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	23927
k_VitesseVehicleBVRampValidThresh_Cnt_u16	6491
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	16864
k_VitesseVehicleBVSigValidThresh_Cnt_u16	48832
k_VitesseVehicleBVSpeedPassThresh_kph_f32	422.437408
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	43593
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	48460
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2487810816
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	64798
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2746368768
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	185
target_SrlComInput_Per1_Batt_Volt_f32.value	27.8834991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3891047168
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	210
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.820290744
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2031196928
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3438230272
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1826413312
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2161801984
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	820517632
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	247
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2768616192
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	61
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	87251712
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	56
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	57
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	80
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	107
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	235
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	244
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	933722880
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	64
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	65
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	90
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	176
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	183
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	188259072
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4036377344
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3791903488
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	4
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	16
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	93
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	117
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	187837184
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2300
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.206194654
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	761487
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	0.921299994
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	38056

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2746368768	2746368768	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2746368768	2746368768	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	17325	17325	✔
AngleVolantMsgTimer_mS_M_u32	2746368768	2746368768	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2746368768	2746368768	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2746368768	2746368768	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2746368768	2746368768	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2746368768	2746368768	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2746368768	2746368768	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2746368768	2746368768	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2746368768	2746368768	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2746368768	2746368768	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2746368768	2746368768	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2746368768	2746368768	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	28609	28609	✔
CONSANGLECPK_HwDeg_M_f32	-719.163818	-719.163818 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	28609	28609	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1494027008	1494027008	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	47593	47593	✔
CityParkInputConsistentCount_Cnt_M_u16	51003	51003	✔
CityParkInputInvalidCount_Cnt_M_u16	25577	25577	✔
CityParkInputMsgTimer_mS_M_u32	2746368768	2746368768	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2746368768	2746368768	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2746368768	2746368768	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2746368768	2746368768	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2746368768	2746368768	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2746368768	2746368768	✔
ESPNTCEnableTimer_mS_M_u32	2746368768	2746368768	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2746368768	2746368768	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1123	1123	✔
EffacDefaultDiagTimer_mS_M_u32[1]	5523	5523	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2746368768	2746368768	✔
ElecIntTimer_mS_M_u32[1]	20	20	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2746368768	2746368768	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2746368768	2746368768	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2746368768	2746368768	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2746368768	2746368768	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2746368768	2746368768	✔
ISDATDIRASentFltAcc_Cnt_M_u16	44440	44440	✔
ISDATDIRASentTimer_mS_M_u32	2746368768	2746368768	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2746368768	2746368768	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2746368768	2746368768	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2746368768	2746368768	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2746368768	2746368768	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2746368768	2746368768	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2746368768	2746368768	✔
IgnOnTimer_mS_M_u32	982489856	982489856	✔
IgnTimeOff_Sec_M_u32	31671922	31671922	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	39	39	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2031196928	2031196928	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	195	195	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3438230272	3438230272	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	152	152	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1826413312	1826413312	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	205	205	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2161801984	2161801984	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1078319872	1078319872	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	247	247	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2768616192	2768616192	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	61	61	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	87251712	87251712	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	244	244	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	933722880	933722880	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	216	216	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	188259072	188259072	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4036377344	4036377344	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3791903488	3791903488	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	187837184	187837184	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	526.564819	526.564819	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	26.1049995	26.1049995	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	361.304291	361.304291	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	28609	28609	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	31671922	31671922	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-719.163818	-719.163818 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.240 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3034882560
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	18411
AASNodeAbsentTimer_mS_M_u32	1558811136
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	12871
ANGLEVOLANTSigValidCount_Cnt_M_u16	60326
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	59528
AngleVolantMsgTimer_mS_M_u32	3034882560
AngleVolantValidCount_Cnt_M_u16	47989
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2571194880
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2020594176
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3502981632
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3224502784
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	23182
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1669579264
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	21037
CAVNodeAbsentTimer_mS_M_u32	568603136
CDD_SrlComVehSpd_Kph_G_f32	138.3936
CMM388NTCEnableTimer_mS_M_u32	1989702144
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2813997568
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	33474
CMMNodeAbsentTimer_mS_M_u32	3235643904
CONSANGLECPKSigInvalidCount_Cnt_M_u16	12011
CONSANGLECPKSigValidCount_Cnt_M_u16	12185
CONSANGLECPK_Cnt_M_u16	2564
CONSANGLECPK_HwDeg_M_f32	414.293701
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2564
CPKVehicleSpeedMsgTimer_mS_M_u32	241410560
CPKVehicleSpeedValidCount_Cnt_M_u16	54039
CityParkInputConsistentCount_Cnt_M_u16	42073

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	22350
CityParkInputMsgTimer_mS_M_u32	2031196928
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2127401472
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	18127
ComputerRazGCTSigInvalidTimer_mS_M_u32	3468997120
ComputerRazGCTSigValidCount_Cnt_M_u16	34734
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	19050
DMDFCTCPKSigValidCount_Cnt_M_u16	4656
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	48569
DMDRELAXECPKSigValidCount_Cnt_M_u16	34968
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	51336
DateInvalidTimer_mS_M_u32	2020594176
DiagMuxOnAbsentTimer_mS_M_u32	2937479680
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3224502784
ESPNTCEnableTimer_mS_M_u32	1529516544
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	61852
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	54
EffacDefaultDiagTimer_mS_M_u32[1]	64
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	88
ElecIntTimer_mS_M_u32[1]	112
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3512058368
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	6603
EtatMTSigValidCount_Cnt_M_u16	39190
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	36957
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	8843
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20998
ISDAT4V2BSI552MsgTimer_mS_M_u32	1170211328
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	50449
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	8099
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	39190
ISDATBSI3F2MsgTimer_mS_M_u32	1705271808
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	51791
ISDATBSI412MsgLenValidCount_Cnt_M_u16	58129
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	6603
ISDATBSI412MsgTimer_mS_M_u32	1903337984
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	43686
ISDATBSI432MsgLenValidCount_Cnt_M_u16	64640
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	59278
ISDATDIRASentFltAcc_Cnt_M_u16	10882
ISDATDIRASentTimer_mS_M_u32	241410560
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	12050
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	47989
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	27697
ISDYN2CMMMsgTimer_mS_M_u32	3360985600
ISDYNAASChkSumInvalidCount_Cnt_M_u16	57181
ISDYNAASChkSumValidCount_Cnt_M_u16	1499
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	58172
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	4312
ISDYNAASMsgLenValidCount_Cnt_M_u16	6863
ISDYNAASMsgTimeValidCount_Cnt_M_u16	65535
ISDYNAASMsgTimer_mS_M_u32	2931061248
ISDYNABRChkSumInvalidCount_Cnt_M_u16	46101
ISDYNABRChkSumValidCount_Cnt_M_u16	40635
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	6564
ISDYNABRMsgCountValidCount_Cnt_M_u16	14178
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	60466
ISDYNABRMsgLenValidCount_Cnt_M_u16	9248
ISDYNABRMsgTimeValidCount_Cnt_M_u16	2564
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	64319

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	19255
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	39190
ISDYNCMM208MsgTimer_mS_M_u32	1356222976
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	64319
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	19255
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	65283
ISDYNCMM388MsgTimer_mS_M_u32	2285367808
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	40313
ISDYNVOLChkSumValidCount_Cnt_M_u16	3239
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	31736
ISDYNVOLMsgCountValidCount_Cnt_M_u16	62014
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	18005
ISDYNVOLMsgLenValidCount_Cnt_M_u16	14820
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	33474
ISDYNVOLMsgTimer_mS_M_u32	3001070080
IgnOnTimer_mS_M_u32	1746661888
IgnTimeOff_Sec_M_u32	2642733516
ManVehSpd_Kph_M_f32	64.5326996
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	112
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	50
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2136629760
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	87
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	502415872
PrevISDATBSI412MsgDLCError_Cnt_M_u08	203
PrevISDATBSI412MsgRxTime_MSec_M_u32	2919576064
PrevISDATBSI432MsgDLCError_Cnt_M_u08	73
PrevISDATBSI432MsgRxTime_MSec_M_u32	1216254464
PrevISDATDIRAMsgTxTime_MSec_M_u32	4294521344
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	47
PrevISDYN2CMMMsgRxTime_MSec_M_u32	971473408
PrevISDYNAASMsgDLCError_Cnt_M_u08	75
PrevISDYNAASMsgRxTime_MSec_M_u32	535736832
PrevISDYNABRMsgDLCError_Cnt_M_u08	147
PrevISDYNABRMsgRxTime_MSec_M_u32	726921728
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	149
PrevISDYNCMM208MsgRxTime_MSec_M_u32	84128256
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	112
PrevISDYNCMM388MsgRxTime_MSec_M_u32	535400960
PrevISDYNVOLMsgDLCError_Cnt_M_u08	249
PrevISDYNVOLMsgRxTime_MSec_M_u32	2196910592
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2164302336
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	514.419983
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	18534
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	32989
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	12959
VitesseVehicleBVRampValidCount_Cnt_M_u16	54230
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	65024
VitesseVehicleBVSigValidCount_Cnt_M_u16	16415

Name	Input Value
VitesseVehicleBV_Kph_M_f32	136.513306
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	65283
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	35801
VitesseVehiculeRoues_Kph_M_f32	319.249908
k_AASNTCEnableTimeout_mS_u16	63939
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	3416
k_AASNodeTimeout_mS_u16	50141
k_ABSNodeTimeout_mS_u16	34239
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	40393
k_ANGLEVOLANTSigValidThresh_Cnt_u16	5091
k_AngleVolantInvalidThresh_Cnt_u16	14834
k_AngleVolantValidThresh_Cnt_u16	22350
k_BSI552MsgTimeout_mS_u16	10920
k_BSINTCEnableTimeout_mS_u16	56798
k_BSINodeAbsentDiag_Cnt_str.Threshold	45995
k_BSINodeAbsentDiag_Cnt_str.PStep	1695
k_BSINodeAbsentDiag_Cnt_str.NStep	63655
k_BSINodeAbsentTimeout_mS_u16	3520
k_BSINodeTimeout_mS_u16	59278
k_BattOvHi_Volt_f32	16.9985008
k_BattOvLo_Volt_f32	31.5
k_BattUvHi_Volt_f32	5.02089977
k_BattUvLo_Volt_f32	10.1239996
k_CAVNTCEnableTimeout_mS_u16	21012
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	17595
k_CAVNodeTimeout_mS_u16	24327
k_CMM388MsgTimeout_mS_u16	51947
k_CMM388NTCEnableTimeout_mS_u16	3079
k_CMMNTCEnableTimeout_mS_u16	21577
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	8949
k_CONSANGLECPKMax_HwDeg_f32	24.3362999
k_CONSANGLECPKMin_HwDeg_f32	-504.755493
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	515
k_CONSANGLECPKSigValidThresh_Cnt_u16	52953
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	48819
k_CPKVehicleSpeedValidThresh_Cnt_u16	61114
k_CityParkInputInvalidThresh_Cnt_u16	27499
k_CityParkInputValidThresh_Cnt_u16	42073
k_ComputerRazGCTSigValidThresh_Cnt_u16	10567
k_CptTemporelSigValidThresh_Cnt_u16	24665
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	28466
k_DMDFCTCPKSigValidThresh_Cnt_u16	59168
k_DMDFCTCPKValidCount_Cnt_u16	51286
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	27697
k_DMDRELAXECPKSigValidThresh_Cnt_u16	52023
k_DMDRelaxeConsistentThresh_Cnt_u16	4109
k_DateValidThresh_Cnt_u16	20998
k_DefaultVehSpd_Kph_f32	241.780304
k_DiagMuxOnAbsentTimeout_mS_u16	42570
k_EMNodeTimeout_mS_u16	38376
k_ESPNTCEnableTimeout_mS_u16	1097
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	30653
k_EtatMTSigInvalidThresh_Cnt_u16	2052
k_EtatMTSigValidThresh_Cnt_u16	22506
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	8446
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	22824
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	16530
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	46286
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	21280
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	14387
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	37859

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	18813
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	4746
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	17736
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	11819
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	57521
k_ISDATDIRASentDiag_Cnt_str.Threshold	10540
k_ISDATDIRASentDiag_Cnt_str.PStep	20636
k_ISDATDIRASentDiag_Cnt_str.NStep	57668
k_ISDATDIRASentTimeout_mS_u16	41521
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	10566
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	59528
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	46069
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	46869
k_ISDYNAASChkSumValidThresh_Cnt_u16	57787
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	40100
k_ISDYNAASMsgCountValidThresh_Cnt_u16	64098
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	2297
k_ISDYNAASMsgLenValidThresh_Cnt_u16	33985
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	18091
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	50624
k_ISDYNABRChkSumValidThresh_Cnt_u16	44078
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	56718
k_ISDYNABRMsgCountValidThresh_Cnt_u16	20013
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	50626
k_ISDYNABRMsgLenValidThresh_Cnt_u16	29852
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	12924
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	43338
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	14280
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	51628
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	46407
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	44710
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	32902
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	46578
k_ISDYNVOLChkSumValidThresh_Cnt_u16	21236
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	8505
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	38559
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	4327
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	60722
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	58700
k_IgnOnTimeout_mS_u16	38926
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	16.6303997
k_PowerCutVehSpdLowThresh_Kph_f32	226.075699
k_PowerCutVehSpdLowTimeout_mS_u16	3535
k_VBattMaxAAS_Volt_f32	27.9596996
k_VBattMaxBSI_Volt_f32	21.8782997
k_VBattMaxCAV_Volt_f32	13.0653
k_VBattMaxCMM388_Volt_f32	7.99499989
k_VBattMaxCMM_Volt_f32	5.26679993
k_VBattMaxESP_Volt_f32	14.5664997
k_VBattMinAAS_Volt_f32	3.34990001
k_VBattMinBSI_Volt_f32	14.5664997
k_VBattMinCAV_Volt_f32	14.1260004
k_VBattMinCMM388_Volt_f32	16.3670998
k_VBattMinCMM_Volt_f32	18.9985008
k_VBattMinESP_Volt_f32	5.26679993
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	14704
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	50339
k_VitesseVehicleBVRampValidThresh_Cnt_u16	32504
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	53159
k_VitesseVehicleBVSigValidThresh_Cnt_u16	4554
k_VitesseVehicleBVSpeedPassThresh_kph_f32	45.4754982
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	21805
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	25828
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2020594176
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	12613
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1767111168
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	112
target_SrlComInput_Per1_Batt_Volt_f32.value	16.7297001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3896820224
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	239
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.708959341
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	882242048
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	930943488
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2520003072
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3636154880
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2266132992
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	41
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	691638784
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	120
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1194373632
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	20
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	22
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	24
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	134
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	146
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	196
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	676614656
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	123
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	218
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	236
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	10
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3659592192
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	254
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	680006144
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2462003712
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	47
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	57
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	164
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	183
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1953776128
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	528
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.505308807
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	146582
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	214.028107

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	53776		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1767111168	1767111168	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1767111168	1767111168	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1767111168	1767111168	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1767111168	1767111168	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1767111168	1767111168	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1767111168	1767111168	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1767111168	1767111168	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1767111168	1767111168	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1767111168	1767111168	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1767111168	1767111168	✔
CDD_SrlComVehSpd_Kph_G_f32	64.5326996	64.5326996	✔
CMM388NTCEnableTimer_mS_M_u32	1767111168	1767111168	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1767111168	1767111168	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1767111168	1767111168	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	2564	2564	✔
CONSANGLECPK_HwDeg_M_f32	414.293701	414.293701 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1767111168	1767111168	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1767111168	1767111168	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1767111168	1767111168	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1767111168	1767111168	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1767111168	1767111168	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1767111168	1767111168	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1767111168	1767111168	✔
ESPNTCEnableTimer_mS_M_u32	1767111168	1767111168	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1767111168	1767111168	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	54	54	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	64	64	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	88	88	✔
ElecIntTimer_mS_M_u32[1]	112	112	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1767111168	1767111168	✔
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20998	20998	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1767111168	1767111168	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	39190	39190	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1767111168	1767111168	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	6603	6603	✔
ISDATBSI412MsgTimer_mS_M_u32	1767111168	1767111168	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	59278	59278	✔
ISDATBSI432MsgTimer_mS_M_u32	1767111168	1767111168	✔
ISDATDIRASentFltAcc_Cnt_M_u16	10540	10540	✔
ISDATDIRASentTimer_mS_M_u32	1767111168	1767111168	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	27697	27697	✔
ISDYN2CMMMsgTimer_mS_M_u32	1767111168	1767111168	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	65535	65535	✔
ISDYNAASMsgTimer_mS_M_u32	1767111168	1767111168	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	2564	2564	✔
ISDYNABRMsgTimer_mS_M_u32	1767111168	1767111168	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	39190	39190	✔
ISDYNCMM208MsgTimer_mS_M_u32	1767111168	1767111168	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	65283	65283	✔
ISDYNCMM388MsgTimer_mS_M_u32	1767111168	1767111168	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	33474	33474	✔
ISDYNVOLMsgTimer_mS_M_u32	1767111168	1767111168	✔
IgnOnTimer_mS_M_u32	1746661888	1746661888	✔
IgnTimeOff_Sec_M_u32	2642733516	2642733516	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	195	195	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	882242048	882242048	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	930943488	930943488	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	106	106	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2520003072	2520003072	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3636154880	3636154880	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4294521344	4294521344	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	41	41	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	691638784	691638784	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	120	120	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1194373632	1194373632	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	676614656	676614656	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	10	10	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3659592192	3659592192	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	254	254	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	680006144	680006144	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2462003712	2462003712	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1953776128	1953776128	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	514.419983	514.419983	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	136.513306	136.513306	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	319.249908	319.249908	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	2564	2564	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2642733516	2642733516	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	414.293701	414.293701 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.241 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2046352640
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	64229
AASNodeAbsentTimer_mS_M_u32	27921664
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	19919
ANGLEVOLANTSigValidCount_Cnt_M_u16	59252
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	52494
AngleVolantMsgTimer_mS_M_u32	2046352640
AngleVolantValidCount_Cnt_M_u16	61638
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1537395968
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2551663872
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2294611200
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3314597120
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	45306
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1385921792
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	44701
CAVNodeAbsentTimer_mS_M_u32	1698311424
CDD_SrlComVehSpd_Kph_G_f32	417.810608
CMM388NTCEnableTimer_mS_M_u32	2283629824
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2880974080
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	35743
CMMNodeAbsentTimer_mS_M_u32	3952262400
CONSANGLECPKSigInvalidCount_Cnt_M_u16	38628
CONSANGLECPKSigValidCount_Cnt_M_u16	39577
CONSANGLECPK_Cnt_M_u16	30552
CONSANGLECPK_HwDeg_M_f32	295.127014
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	30552
CPKVehicleSpeedMsgTimer_mS_M_u32	695983360
CPKVehicleSpeedValidCount_Cnt_M_u16	17801
CityParkInputConsistentCount_Cnt_M_u16	50714
CityParkInputInvalidCount_Cnt_M_u16	4667
CityParkInputMsgTimer_mS_M_u32	882242048
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	738069760
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	36409

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2157489408
ComputerRazGCTSigValidCount_Cnt_M_u16	45083
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	43239
DMDFCTCPKSigValidCount_Cnt_M_u16	46931
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	62329
DMDRELAXECPKSigValidCount_Cnt_M_u16	22686
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	32269
DateInvalidTimer_mS_M_u32	2551663872
DiagMuxOnAbsentTimer_mS_M_u32	2187566336
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3314597120
ESPNTCEnableTimer_mS_M_u32	1256656128
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	62672
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	65
EffacDefaultDiagTimer_mS_M_u32[1]	655
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	54
ElecIntTimer_mS_M_u32[1]	64
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3508894976
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	31619
EtatMTSigValidCount_Cnt_M_u16	29540
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	47758
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	2499
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	53201
ISDAT4V2BSI552MsgTimer_mS_M_u32	3974544640
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	50995
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	19772
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	29540
ISDATBSI3F2MsgTimer_mS_M_u32	381263104
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	32888
ISDATBSI412MsgLenValidCount_Cnt_M_u16	35825
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	31619
ISDATBSI412MsgTimer_mS_M_u32	4233026816
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	41971
ISDATBSI432MsgLenValidCount_Cnt_M_u16	25636
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	45690
ISDATDIRASentFltAcc_Cnt_M_u16	47518
ISDATDIRASentTimer_mS_M_u32	695983360
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	49198
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	61638
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	8082
ISDYN2CMMMsgTimer_mS_M_u32	728304896
ISDYNAASChkSumInvalidCount_Cnt_M_u16	31887
ISDYNAASChkSumValidCount_Cnt_M_u16	20180
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	21873
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	56988
ISDYNAASMsgLenValidCount_Cnt_M_u16	59001
ISDYNAASMsgTimeValidCount_Cnt_M_u16	15055
ISDYNAASMsgTimer_mS_M_u32	1338600704
ISDYNABRChkSumInvalidCount_Cnt_M_u16	13799
ISDYNABRChkSumValidCount_Cnt_M_u16	23476
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	43450
ISDYNABRMsgCountValidCount_Cnt_M_u16	38463
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	15119
ISDYNABRMsgLenValidCount_Cnt_M_u16	39172
ISDYNABRMsgTimeValidCount_Cnt_M_u16	30552
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	30697
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	288
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	29540
ISDYNCMM208MsgTimer_mS_M_u32	3370372352
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	30697
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	288
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	56860

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	826207488
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	826
ISDYNVOLChkSumValidCount_Cnt_M_u16	47983
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	52285
ISDYNVOLMsgCountValidCount_Cnt_M_u16	53033
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	6821
ISDYNVOLMsgLenValidCount_Cnt_M_u16	50617
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	35743
ISDYNVOLMsgTimer_mS_M_u32	1145351424
IgnOnTimer_mS_M_u32	563277056
IgnTimeOff_Sec_M_u32	1790836508
ManVehSpd_Kph_M_f32	105.476097
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	113
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	563584256
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	63
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4249877760
PrevISDATBSI412MsgDLCError_Cnt_M_u08	178
PrevISDATBSI412MsgRxTime_MSec_M_u32	2228694272
PrevISDATBSI432MsgDLCError_Cnt_M_u08	69
PrevISDATBSI432MsgRxTime_MSec_M_u32	3538619648
PrevISDATDIRAMsgTxTime_MSec_M_u32	1593519360
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	221
PrevISDYN2CMMMsgRxTime_MSec_M_u32	242236672
PrevISDYNAASMsgDLCError_Cnt_M_u08	230
PrevISDYNAASMsgRxTime_MSec_M_u32	3038424320
PrevISDYNABRMsgDLCError_Cnt_M_u08	200
PrevISDYNABRMsgRxTime_MSec_M_u32	3085626624
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	97
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2581310720
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	119
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3098152192
PrevISDYNVOLMsgDLCError_Cnt_M_u08	175
PrevISDYNVOLMsgRxTime_MSec_M_u32	4195364096
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2242174208
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	463.964508
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	61426
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	27727
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	21831
VitesseVehicleBVRampValidCount_Cnt_M_u16	38756
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	3748
VitesseVehicleBVSigValidCount_Cnt_M_u16	3593
VitesseVehicleBV_Kph_M_f32	15.8029003
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	56860
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	56665
VitesseVehiculeRoues_Kph_M_f32	496.970001
k_AASNTCEnableTimeout_mS_u16	25627
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	18205
k_AASNodeTimeout_mS_u16	41807
k_ABSNodeTimeout_mS_u16	35560
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	5770
k_ANGLEVOLANTSigValidThresh_Cnt_u16	27131
k_AngleVolantInvalidThresh_Cnt_u16	62414
k_AngleVolantValidThresh_Cnt_u16	4667
k_BSI552MsgTimeout_mS_u16	64748
k_BSINTCEnableTimeout_mS_u16	59979
k_BSINodeAbsentDiag_Cnt_str.Threshold	50868
k_BSINodeAbsentDiag_Cnt_str.PStep	55240
k_BSINodeAbsentDiag_Cnt_str.NStep	41105
k_BSINodeAbsentTimeout_mS_u16	15718
k_BSINodeTimeout_mS_u16	45690
k_BattOvHi_Volt_f32	26.1793003
k_BattOvLo_Volt_f32	4.53679991
k_BattUvHi_Volt_f32	30.1835995
k_BattUvLo_Volt_f32	17.6354008
k_CAVNTCEnableTimeout_mS_u16	47593
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	36595
k_CAVNodeTimeout_mS_u16	30352
k_CMM388MsgTimeout_mS_u16	29157
k_CMM388NTCEnableTimeout_mS_u16	7825
k_CMMNTCEnableTimeout_mS_u16	63883
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	34821
k_CONSANGLECPKMax_HwDeg_f32	557.43927
k_CONSANGLECPKMin_HwDeg_f32	-762.493225
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	54556
k_CONSANGLECPKSigValidThresh_Cnt_u16	5209
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	35533
k_CPKVehicleSpeedValidThresh_Cnt_u16	32567
k_CityParkInputInvalidThresh_Cnt_u16	59365
k_CityParkInputValidThresh_Cnt_u16	50714
k_ComputerRazGCTSigValidThresh_Cnt_u16	62097
k_CptTemporelSigValidThresh_Cnt_u16	58138
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	45583
k_DMDFCTCPKSigValidThresh_Cnt_u16	20484
k_DMDFCTCPKValidCount_Cnt_u16	34722
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	8082
k_DMDRELAXECPKSigValidThresh_Cnt_u16	26686
k_DMDRelaxeConsistentThresh_Cnt_u16	29116
k_DateValidThresh_Cnt_u16	53201
k_DefaultVehSpd_Kph_f32	183.810501
k_DiagMuxOnAbsentTimeout_mS_u16	14982
k_EMNodeTimeout_mS_u16	38381
k_ESPNTCEnableTimeout_mS_u16	2121
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	43437
k_EtatMTSigInvalidThresh_Cnt_u16	46618
k_EtatMTSigValidThresh_Cnt_u16	44071
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	20460
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	40236
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	5487
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	11260
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	59077
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	50892
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	7228
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	45357
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	64583
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	54668
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	61604
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	38482
k_ISDATDIRASentDiag_Cnt_str.Threshold	16348

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	15877
k_ISDATDIRASentDiag_Cnt_str.NStep	46278
k_ISDATDIRASentTimeout_mS_u16	56211
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	20627
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	52494
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	43333
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	11495
k_ISDYNAASChkSumValidThresh_Cnt_u16	37556
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	8378
k_ISDYNAASMsgCountValidThresh_Cnt_u16	19775
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	51003
k_ISDYNAASMsgLenValidThresh_Cnt_u16	61603
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	61859
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	26213
k_ISDYNABRChkSumValidThresh_Cnt_u16	47322
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	10234
k_ISDYNABRMsgCountValidThresh_Cnt_u16	39903
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	49823
k_ISDYNABRMsgLenValidThresh_Cnt_u16	27600
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	60146
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	23878
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	23565
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	36322
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	50383
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	40564
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	30355
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	2447
k_ISDYNVOLChkSumValidThresh_Cnt_u16	34888
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	6649
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	1032
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	1583
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	59152
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	44543
k_IgnOnTimeout_mS_u16	54075
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	73.7602005
k_PowerCutVehSpdLowThresh_Kph_f32	29.4242992
k_PowerCutVehSpdLowTimeout_mS_u16	22519
k_VBattMaxAAS_Volt_f32	20.1678009
k_VBattMaxBSI_Volt_f32	7.7968998
k_VBattMaxCAV_Volt_f32	29.6273003
k_VBattMaxCMM388_Volt_f32	26.5979996
k_VBattMaxCMM_Volt_f32	2.26609993
k_VBattMaxESP_Volt_f32	29.8931999
k_VBattMinAAS_Volt_f32	16.3633995
k_VBattMinBSI_Volt_f32	29.8931999
k_VBattMinCAV_Volt_f32	0.373899996
k_VBattMinCMM388_Volt_f32	4.28550005
k_VBattMinCMM_Volt_f32	7.1869998
k_VBattMinESP_Volt_f32	2.26609993
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	18453
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	48189
k_VitesseVehicleBVRampValidThresh_Cnt_u16	49981
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	29295
k_VitesseVehicleBVSigValidThresh_Cnt_u16	33223
k_VitesseVehicleBVSpeedPassThresh_kph_f32	276.738098
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	42397
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	39994
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2551663872
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	62348
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3893024000
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	119
target_SrlComInput_Per1_Batt_Volt_f32.value	20.8297005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	140016896
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	157
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.833816409
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	606399744
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	250
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	535792896
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1212820736
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	101
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	87346432
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3199167744
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3703180544
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3344215296
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	12
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	25
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	175
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	191
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3127495936
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	58
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	84
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	107
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	115
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	528739584
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	953060608
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1051274496
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	49
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	248
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2177498368
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	106
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.547628701
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	216193
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	148.817093
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	31476

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3893024000	3893024000	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3893024000	3893024000	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3893024000	3893024000	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3893024000	3893024000	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3893024000	3893024000	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3893024000	3893024000	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3893024000	3893024000	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3893024000	3893024000	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3893024000	3893024000	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3893024000	3893024000	✔
CDD_SrlComVehSpd_Kph_G_f32	105.476097	105.476097	✔
CMM388NTCEnableTimer_mS_M_u32	3893024000	3893024000	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3893024000	3893024000	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3893024000	3893024000	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	30552	30552	✔
CONSANGLECPK_HwDeg_M_f32	295.127014	295.127014 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3893024000	3893024000	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3893024000	3893024000	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3893024000	3893024000	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3893024000	3893024000	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3893024000	3893024000	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3893024000	3893024000	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3893024000	3893024000	✔
ESPNTCEnableTimer_mS_M_u32	3893024000	3893024000	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3893024000	3893024000	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	65	65	✔
EffacDefaultDiagTimer_mS_M_u32[1]	655	655	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	54	54	✔
ElecIntTimer_mS_M_u32[1]	64	64	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3893024000	3893024000	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	53201	53201	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3893024000	3893024000	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	29540	29540	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3893024000	3893024000	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	31619	31619	✔
ISDATBSI412MsgTimer_mS_M_u32	3893024000	3893024000	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	45690	45690	✔
ISDATBSI432MsgTimer_mS_M_u32	3893024000	3893024000	✔
ISDATDIRASentFltAcc_Cnt_M_u16	16348	16348	✔
ISDATDIRASentTimer_mS_M_u32	3893024000	3893024000	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	8082	8082	✔
ISDYN2CMMMsgTimer_mS_M_u32	3893024000	3893024000	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	15055	15055	✔
ISDYNAASMsgTimer_mS_M_u32	3893024000	3893024000	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	30552	30552	✔
ISDYNABRMsgTimer_mS_M_u32	3893024000	3893024000	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	29540	29540	✔
ISDYNCMM208MsgTimer_mS_M_u32	3893024000	3893024000	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	56860	56860	✔
ISDYNCMM388MsgTimer_mS_M_u32	3893024000	3893024000	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	35743	35743	✔
ISDYNVOLMsgTimer_mS_M_u32	3893024000	3893024000	✔
IgnOnTimer_mS_M_u32	563277056	563277056	✔
IgnTimeOff_Sec_M_u32	1790836508	1790836508	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	174	174	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	606399744	606399744	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	250	250	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	535792896	535792896	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	192	192	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1212820736	1212820736	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	101	101	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	87346432	87346432	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1593519360	1593519360	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	242	242	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3703180544	3703180544	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	169	169	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3344215296	3344215296	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	8	8	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3127495936	3127495936	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	195	195	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	528739584	528739584	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	77	77	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	953060608	953060608	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	15	15	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1051274496	1051274496	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2177498368	2177498368	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	463.964508	463.964508	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	15.8029003	15.8029003	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	496.970001	496.970001	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	30552	30552	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1790836508	1790836508	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	295.127014	295.127014 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	105.476097	105.476097	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.242 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3647482880
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	43170
AASNodeAbsentTimer_mS_M_u32	3272907776
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	31203
ANGLEVOLANTSigValidCount_Cnt_M_u16	23477
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	5671
AngleVolantMsgTimer_mS_M_u32	3647482880
AngleVolantValidCount_Cnt_M_u16	54653
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2284477440
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1154276352
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2240007168
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2921368576
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	48226
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2717928448
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	5626
CAVNodeAbsentTimer_mS_M_u32	2162441216
CDD_SrlComVehSpd_Kph_G_f32	229.930695
CMM388NTCEnableTimer_mS_M_u32	3040508928
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	627719168
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	12980
CMMNodeAbsentTimer_mS_M_u32	3290074112
CONSANGLECPKSigInvalidCount_Cnt_M_u16	57764
CONSANGLECPKSigValidCount_Cnt_M_u16	50502
CONSANGLECPK_Cnt_M_u16	60169
CONSANGLECPK_HwDeg_M_f32	-703.053223
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	60169
CPKVehicleSpeedMsgTimer_mS_M_u32	2531208192
CPKVehicleSpeedValidCount_Cnt_M_u16	42045
CityParkInputConsistentCount_Cnt_M_u16	42369
CityParkInputInvalidCount_Cnt_M_u16	37409
CityParkInputMsgTimer_mS_M_u32	606399744
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2484640768
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	16038

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3368598528
ComputerRazGCTSigValidCount_Cnt_M_u16	11134
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	32285
DMDFCTCPKSigValidCount_Cnt_M_u16	8598
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	45285
DMDRELAXECPKSigValidCount_Cnt_M_u16	12343
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	4137
DateInvalidTimer_mS_M_u32	1154276352
DiagMuxOnAbsentTimer_mS_M_u32	3676826624
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2921368576
ESPNTCEnableTimer_mS_M_u32	459119616
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	54754
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	100
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3462548480
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	17415
EtatMTSigValidCount_Cnt_M_u16	64293
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	40614
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	40904
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20508
ISDAT4V2BSI552MsgTimer_mS_M_u32	270437376
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	30840
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	9502
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	64293
ISDATBSI3F2MsgTimer_mS_M_u32	4129680384
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	61864
ISDATBSI412MsgLenValidCount_Cnt_M_u16	52734
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	17415
ISDATBSI412MsgTimer_mS_M_u32	711339008
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	14776
ISDATBSI432MsgLenValidCount_Cnt_M_u16	55270
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	48739
ISDATDIRASentFltAcc_Cnt_M_u16	14583
ISDATDIRASentTimer_mS_M_u32	2531208192
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	59527
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	54653
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	34332
ISDYN2CMMMsgTimer_mS_M_u32	30907392
ISDYNAASChkSumInvalidCount_Cnt_M_u16	19364
ISDYNAASChkSumValidCount_Cnt_M_u16	0
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	4988
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	16893
ISDYNAASMsgLenValidCount_Cnt_M_u16	47399
ISDYNAASMsgTimeValidCount_Cnt_M_u16	19364
ISDYNAASMsgTimer_mS_M_u32	238451712
ISDYNABRChkSumInvalidCount_Cnt_M_u16	31003
ISDYNABRChkSumValidCount_Cnt_M_u16	22133
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	12323
ISDYNABRMsgCountValidCount_Cnt_M_u16	39253
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	24867
ISDYNABRMsgLenValidCount_Cnt_M_u16	13829
ISDYNABRMsgTimeValidCount_Cnt_M_u16	60169
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	48026
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	35251
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	64293
ISDYNCMM208MsgTimer_mS_M_u32	2221366272
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	48026
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	35251
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	58747

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	534117376
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	29858
ISDYNVOLChkSumValidCount_Cnt_M_u16	15044
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	60443
ISDYNVOLMsgCountValidCount_Cnt_M_u16	45588
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	63587
ISDYNVOLMsgLenValidCount_Cnt_M_u16	26085
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	12980
ISDYNVOLMsgTimer_mS_M_u32	767867904
IgnOnTimer_mS_M_u32	2665085952
IgnTimeOff_Sec_M_u32	721841208
ManVehSpd_Kph_M_f32	143.325699
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	114
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	27
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3448499200
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	128
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	333630464
PrevISDATBSI412MsgDLCError_Cnt_M_u08	192
PrevISDATBSI412MsgRxTime_MSec_M_u32	3591191552
PrevISDATBSI432MsgDLCError_Cnt_M_u08	220
PrevISDATBSI432MsgRxTime_MSec_M_u32	2471599104
PrevISDATDIRAMsgTxTime_MSec_M_u32	3617668096
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	55
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2978089984
PrevISDYNAASMsgDLCError_Cnt_M_u08	0
PrevISDYNAASMsgRxTime_MSec_M_u32	3007495168
PrevISDYNABRMsgDLCError_Cnt_M_u08	51
PrevISDYNABRMsgRxTime_MSec_M_u32	1003617280
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	134
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1224719360
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	79
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2652150784
PrevISDYNVOLMsgDLCError_Cnt_M_u08	45
PrevISDYNVOLMsgRxTime_MSec_M_u32	2590129152
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1717840896
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	506.809113
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	58875
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	65445
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	18940
VitesseVehicleBVRampValidCount_Cnt_M_u16	4710
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	52068
VitesseVehicleBVSigValidCount_Cnt_M_u16	31734
VitesseVehicleBV_Kph_M_f32	33.5399017
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	58747
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	63109
VitesseVehiculeRoues_Kph_M_f32	96.2873993
k_AASNTCEnableTimeout_mS_u16	61632
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	61048
k_AASNodeTimeout_mS_u16	23205
k_ABSNodeTimeout_mS_u16	7194
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	65011
k_ANGLEVOLANTSigValidThresh_Cnt_u16	57953
k_AngleVolantInvalidThresh_Cnt_u16	20712
k_AngleVolantValidThresh_Cnt_u16	37409
k_BSI552MsgTimeout_mS_u16	41932
k_BSINTCEnableTimeout_mS_u16	50864
k_BSINodeAbsentDiag_Cnt_str.Threshold	4793
k_BSINodeAbsentDiag_Cnt_str.PStep	42427
k_BSINodeAbsentDiag_Cnt_str.NStep	57762
k_BSINodeAbsentTimeout_mS_u16	9503
k_BSINodeTimeout_mS_u16	48739
k_BattOvHi_Volt_f32	17.1305008
k_BattOvLo_Volt_f32	9.40919971
k_BattUvHi_Volt_f32	3.40370011
k_BattUvLo_Volt_f32	0.264600009
k_CAVNTCEnableTimeout_mS_u16	54039
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	19704
k_CAVNodeTimeout_mS_u16	62112
k_CMM388MsgTimeout_mS_u16	17314
k_CMM388NTCEnableTimeout_mS_u16	60830
k_CMMNTCEnableTimeout_mS_u16	16752
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	42625
k_CONSANGLECPKMax_HwDeg_f32	394.047394
k_CONSANGLECPKMin_HwDeg_f32	-185.531296
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	123
k_CONSANGLECPKSigValidThresh_Cnt_u16	20869
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	7211
k_CPKVehicleSpeedValidThresh_Cnt_u16	45419
k_CityParkInputInvalidThresh_Cnt_u16	56097
k_CityParkInputValidThresh_Cnt_u16	42369
k_ComputerRazGCTSigValidThresh_Cnt_u16	61022
k_CptTemporelSigValidThresh_Cnt_u16	23428
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	64547
k_DMDFCTCPKSigValidThresh_Cnt_u16	4357
k_DMDFCTCPKValidCount_Cnt_u16	55402
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	34332
k_DMDRELAXECPKSigValidThresh_Cnt_u16	31445
k_DMDRelaxeConsistentThresh_Cnt_u16	54875
k_DateValidThresh_Cnt_u16	20508
k_DefaultVehSpd_Kph_f32	66.3917999
k_DiagMuxOnAbsentTimeout_mS_u16	55679
k_EMNodeTimeout_mS_u16	18569
k_ESPNTCEnableTimeout_mS_u16	47350
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	57737
k_EtatMTSigInvalidThresh_Cnt_u16	33922
k_EtatMTSigValidThresh_Cnt_u16	61724
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	2254
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	16332
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	19330
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	44573
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	48259
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	28332
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	13533
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	21707
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	32956
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	41069
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	52707
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	42268
k_ISDATDIRASentDiag_Cnt_str.Threshold	3976

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	38821
k_ISDATDIRASentDiag_Cnt_str.NStep	39228
k_ISDATDIRASentTimeout_mS_u16	14359
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	47705
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	5671
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	50690
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	37915
k_ISDYNAASChkSumValidThresh_Cnt_u16	45429
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	52003
k_ISDYNAASMsgCountValidThresh_Cnt_u16	29781
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	5407
k_ISDYNAASMsgLenValidThresh_Cnt_u16	49833
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	60265
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	46881
k_ISDYNABRChkSumValidThresh_Cnt_u16	44675
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	22370
k_ISDYNABRMsgCountValidThresh_Cnt_u16	43636
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	36276
k_ISDYNABRMsgLenValidThresh_Cnt_u16	28898
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	51515
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	60927
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	62185
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	42732
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	5347
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	14005
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	50457
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	29283
k_ISDYNVOLChkSumValidThresh_Cnt_u16	62713
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	19047
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	44409
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	21507
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	20513
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	60818
k_IgnOnTimeout_mS_u16	50527
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	193.042694
k_PowerCutVehSpdLowThresh_Kph_f32	110.050499
k_PowerCutVehSpdLowTimeout_mS_u16	34092
k_VBattMaxAAS_Volt_f32	25.5832996
k_VBattMaxBSI_Volt_f32	22.5417004
k_VBattMaxCAV_Volt_f32	3.8757
k_VBattMaxCMM388_Volt_f32	1.68410003
k_VBattMaxCMM_Volt_f32	7.22989988
k_VBattMaxESP_Volt_f32	21.7691994
k_VBattMinAAS_Volt_f32	5.89779997
k_VBattMinBSI_Volt_f32	21.7691994
k_VBattMinCAV_Volt_f32	4.84959984
k_VBattMinCMM388_Volt_f32	27.2105999
k_VBattMinCMM_Volt_f32	19.1184006
k_VBattMinESP_Volt_f32	7.22989988
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	23507
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	48665
k_VitesseVehicleBVRampValidThresh_Cnt_u16	1819
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	5572
k_VitesseVehicleBVSigValidThresh_Cnt_u16	26234
k_VitesseVehicleBVSpeedPassThresh_kph_f32	599.948792
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	12538
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	56292
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1154276352
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	36411
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2323117824
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	79
target_SrlComInput_Per1_Batt_Volt_f32.value	14.6138
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3033091072
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	246
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.745405853
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1596193792
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	11
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1581521920
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	207
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	397687808
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1400134656
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3649338368
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1910807552
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3834952704
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	57
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	72
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	169
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	209
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1205165056
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	80
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	92
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2835807232
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1336351744
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	28
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1888959488
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	58
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	109
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	121
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	138
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	140
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	178
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4000631808
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2424
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.660168111
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	916159
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	14.1219997
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	52469

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3647482880	3647482880	✔
AASNTCsEnabled_Cnt_M_lgc	1	1	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2323117824	2323117824	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	5673	5673	✔
AngleVolantMsgTimer_mS_M_u32	2323117824	2323117824	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2323117824	2323117824	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2323117824	2323117824	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2323117824	2323117824	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2323117824	2323117824	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2323117824	2323117824	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2323117824	2323117824	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2323117824	2323117824	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2323117824	2323117824	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2323117824	2323117824	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2323117824	2323117824	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	57764	57764	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	60169	60169	✔
CONSANGLECPK_HwDeg_M_f32	-703.053223	-703.053223 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	60169	60169	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2531208192	2531208192	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	42045	42045	✔
CityParkInputConsistentCount_Cnt_M_u16	42369	42369	✔
CityParkInputInvalidCount_Cnt_M_u16	37411	37411	✔
CityParkInputMsgTimer_mS_M_u32	2323117824	2323117824	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2323117824	2323117824	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2323117824	2323117824	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	32285	32285	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	45285	45285	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2323117824	2323117824	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2323117824	2323117824	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2323117824	2323117824	✔
ESPNTCEnableTimer_mS_M_u32	2323117824	2323117824	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2323117824	2323117824	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	8	8	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2323117824	2323117824	✔
ElecIntTimer_mS_M_u32[1]	100	100	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2323117824	2323117824	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2323117824	2323117824	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2323117824	2323117824	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2323117824	2323117824	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2323117824	2323117824	✔
ISDATDIRASentFltAcc_Cnt_M_u16	3976	3976	✔
ISDATDIRASentTimer_mS_M_u32	2323117824	2323117824	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2323117824	2323117824	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	19364	19364	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	4988	4988	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	16893	16893	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3834952704	3834952704	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2323117824	2323117824	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2323117824	2323117824	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2323117824	2323117824	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2323117824	2323117824	✔
IgnOnTimer_mS_M_u32	2665085952	2665085952	✔
IgnTimeOff_Sec_M_u32	721841208	721841208	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	30	30	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1596193792	1596193792	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	11	11	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1581521920	1581521920	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	207	207	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	397687808	397687808	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	48	48	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1400134656	1400134656	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3617668096	3617668096	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	238	238	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1910807552	1910807552	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	219	219	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3834952704	3834952704	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	91	91	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1205165056	1205165056	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	29	29	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2835807232	2835807232	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	81	81	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1336351744	1336351744	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	28	28	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1888959488	1888959488	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4000631808	4000631808	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	506.809113	506.809113	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	33.5399017	33.5399017	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	96.2873993	96.2873993	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	60169	60169	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	721841208	721841208	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-703.053223	-703.053223 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	66.3917999	66.3917999	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0148	0x0148	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.243 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1595293440
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	64358
AASNodeAbsentTimer_mS_M_u32	533786368
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	10661
ANGLEVOLANTSigValidCount_Cnt_M_u16	30703
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	1751
AngleVolantMsgTimer_mS_M_u32	1595293440
AngleVolantValidCount_Cnt_M_u16	18773
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1469034240
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3416796928
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3510853376
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3127713536
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	7720
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	231595776
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	6623
CAVNodeAbsentTimer_mS_M_u32	753012480
CDD_SrlComVehSpd_Kph_G_f32	606.370972
CMM388NTCEnableTimer_mS_M_u32	3101642496
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3612348160
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	43121
CMMNodeAbsentTimer_mS_M_u32	3766427392
CONSANGLECPKSigInvalidCount_Cnt_M_u16	10591
CONSANGLECPKSigValidCount_Cnt_M_u16	45626
CONSANGLECPK_Cnt_M_u16	3313
CONSANGLECPK_HwDeg_M_f32	-373.283691
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	3313

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CPKVehicleSpeedMsgTimer_mS_M_u32	3266395904
CPKVehicleSpeedValidCount_Cnt_M_u16	38397
CityParkInputConsistentCount_Cnt_M_u16	59721
CityParkInputInvalidCount_Cnt_M_u16	45163
CityParkInputMsgTimer_mS_M_u32	1596193792
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3167022848
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	18778
ComputerRazGCTSigInvalidTimer_mS_M_u32	2268368640
ComputerRazGCTSigValidCount_Cnt_M_u16	35666
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	56439
DMDFCTCPKSigValidCount_Cnt_M_u16	34249
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	3231
DMDRELAXECPKSigValidCount_Cnt_M_u16	33385
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	61904
DateInvalidTimer_mS_M_u32	3416796928
DiagMuxOnAbsentTimer_mS_M_u32	148307712
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3127713536
ESPNTCEnableTimer_mS_M_u32	2062937856
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	8871
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	79
EffacDefaultDiagTimer_mS_M_u32[1]	699
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	655
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2426920704
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	53623
EtatMTSigValidCount_Cnt_M_u16	53213
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	31321
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	43700
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	37431
ISDAT4V2BSI552MsgTimer_mS_M_u32	208871168
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	60838
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	11124
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	53213
ISDATBSI3F2MsgTimer_mS_M_u32	803012352
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	37653
ISDATBSI412MsgLenValidCount_Cnt_M_u16	467
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	53623
ISDATBSI412MsgTimer_mS_M_u32	3827056384
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	41829
ISDATBSI432MsgLenValidCount_Cnt_M_u16	11419
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	1188
ISDATDIRASentFltAcc_Cnt_M_u16	58600
ISDATDIRASentTimer_mS_M_u32	3266395904
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	35959
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	18773
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	32890
ISDYN2CMMMsgTimer_mS_M_u32	797437696
ISDYNAASChkSumInvalidCount_Cnt_M_u16	39520
ISDYNAASChkSumValidCount_Cnt_M_u16	65535
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	19288
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	25046
ISDYNAASMsgLenValidCount_Cnt_M_u16	20505
ISDYNAASMsgTimeValidCount_Cnt_M_u16	39520
ISDYNAASMsgTimer_mS_M_u32	2649444096
ISDYNABRChkSumInvalidCount_Cnt_M_u16	1404
ISDYNABRChkSumValidCount_Cnt_M_u16	33070
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	43235
ISDYNABRMsgCountValidCount_Cnt_M_u16	57613
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	26338

Name	Input Value
ISDYNABRMsgLenValidCount_Cnt_M_u16	7165
ISDYNABRMsgTimeValidCount_Cnt_M_u16	3313
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	13428
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	36071
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	53213
ISDYNCMM208MsgTimer_mS_M_u32	2530782976
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	13428
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	36071
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	37211
ISDYNCMM388MsgTimer_mS_M_u32	1192021760
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	59493
ISDYNVOLChkSumValidCount_Cnt_M_u16	51648
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	2685
ISDYNVOLMsgCountValidCount_Cnt_M_u16	19535
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	65316
ISDYNVOLMsgLenValidCount_Cnt_M_u16	27230
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	43121
ISDYNVOLMsgTimer_mS_M_u32	1212190464
IgnOnTimer_mS_M_u32	3657486080
IgnTimeOff_Sec_M_u32	1066987078
ManVehSpd_Kph_M_f32	655.310913
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	115
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	210
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3249209088
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	129
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1646681856
PrevISDATBSI412MsgDLCError_Cnt_M_u08	251
PrevISDATBSI412MsgRxTime_MSec_M_u32	291966720
PrevISDATBSI432MsgDLCError_Cnt_M_u08	30
PrevISDATBSI432MsgRxTime_MSec_M_u32	3810127616
PrevISDATDIRAMsgTxTime_MSec_M_u32	1554714368
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	169
PrevISDYN2CMMMsgRxTime_MSec_M_u32	373858048
PrevISDYNAASMsgDLCError_Cnt_M_u08	156
PrevISDYNAASMsgRxTime_MSec_M_u32	801541888
PrevISDYNABRMsgDLCError_Cnt_M_u08	132
PrevISDYNABRMsgRxTime_MSec_M_u32	3810053888
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	42
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2727317248
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	179
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2396057344
PrevISDYNVOLMsgDLCError_Cnt_M_u08	133
PrevISDYNVOLMsgRxTime_MSec_M_u32	1483214592
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2820816640
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	498.735291
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	60892
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	62623
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	1497

Name	Input Value
VitesseVehicleBVRampValidCount_Cnt_M_u16	92
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	31010
VitesseVehicleBVSigValidCount_Cnt_M_u16	23340
VitesseVehicleBV_Kph_M_f32	152.065094
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	37211
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	12797
VitesseVehiculeRoues_Kph_M_f32	39.4556999
k_AASNTCEnableTimeout_mS_u16	38860
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	43620
k_AASNodeTimeout_mS_u16	58271
k_ABSNodeTimeout_mS_u16	13952
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	692
k_ANGLEVOLANTSigValidThresh_Cnt_u16	47402
k_AngleVolantInvalidThresh_Cnt_u16	18837
k_AngleVolantValidThresh_Cnt_u16	45163
k_BSI552MsgTimeout_mS_u16	1576
k_BSINTCEnableTimeout_mS_u16	56445
k_BSINodeAbsentDiag_Cnt_str.Threshold	25750
k_BSINodeAbsentDiag_Cnt_str.PStep	22735
k_BSINodeAbsentDiag_Cnt_str.NStep	57948
k_BSINodeAbsentTimeout_mS_u16	47599
k_BSINodeTimeout_mS_u16	1188
k_BattOvHi_Volt_f32	11.1402998
k_BattOvLo_Volt_f32	24.7507992
k_BattUvHi_Volt_f32	24.9620991
k_BattUvLo_Volt_f32	26.7306004
k_CAVNTCEnableTimeout_mS_u16	17801
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	60645
k_CAVNodeTimeout_mS_u16	58987
k_CMM388MsgTimeout_mS_u16	10854
k_CMM388NTCEnableTimeout_mS_u16	7282
k_CMMNTCEnableTimeout_mS_u16	29374
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	4617
k_CONSANGLECPKMax_HwDeg_f32	237.409698
k_CONSANGLECPKMin_HwDeg_f32	-9.7262001
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	16475
k_CONSANGLECPKSigValidThresh_Cnt_u16	8445
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	14093
k_CPKVehicleSpeedValidThresh_Cnt_u16	8140
k_CityParkInputInvalidThresh_Cnt_u16	30570
k_CityParkInputValidThresh_Cnt_u16	59721
k_ComputerRazGCTSigValidThresh_Cnt_u16	41972
k_CptTemporelSigValidThresh_Cnt_u16	41026
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	38370
k_DMDFCTCPKSigValidThresh_Cnt_u16	35581
k_DMDFCTCPKValidCount_Cnt_u16	59920
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	32890
k_DMDRELAXECPKSigValidThresh_Cnt_u16	13836
k_DMDRelaxeConsistentThresh_Cnt_u16	47994
k_DateValidThresh_Cnt_u16	37431
k_DefaultVehSpd_Kph_f32	188.632294
k_DiagMuxOnAbsentTimeout_mS_u16	39311
k_EMNodeTimeout_mS_u16	51376
k_ESPNTCEnableTimeout_mS_u16	8427
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	33009
k_EtatMTSigInvalidThresh_Cnt_u16	16199
k_EtatMTSigValidThresh_Cnt_u16	3385
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	48420
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	48106
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	15174
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	8375

Name	Input Value
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	14661
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	11273
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	34294
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	35308
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	56921
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	31941
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	30755
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	39352
k_ISDATDIRASentDiag_Cnt_str.Threshold	21842
k_ISDATDIRASentDiag_Cnt_str.PStep	38193
k_ISDATDIRASentDiag_Cnt_str.NStep	48870
k_ISDATDIRASentTimeout_mS_u16	47240
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	36353
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	1751
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10695
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	46204
k_ISDYNAASChkSumValidThresh_Cnt_u16	28718
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	55267
k_ISDYNAASMsgCountValidThresh_Cnt_u16	20493
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	16752
k_ISDYNAASMsgLenValidThresh_Cnt_u16	48019
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	48658
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	56552
k_ISDYNABRChkSumValidThresh_Cnt_u16	10883
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	19752
k_ISDYNABRMsgCountValidThresh_Cnt_u16	18354
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	38769
k_ISDYNABRMsgLenValidThresh_Cnt_u16	20903
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	51037
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	58832
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	54098
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	56010
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	22693
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	59119
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	63363
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	48356
k_ISDYNVOLChkSumValidThresh_Cnt_u16	14562
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	6424
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	35874
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	37251
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	49385
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	4565
k_IgnOnTimeout_mS_u16	46064
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	163.179703
k_PowerCutVehSpdLowThresh_Kph_f32	36.1562004
k_PowerCutVehSpdLowTimeout_mS_u16	35464
k_VBattMaxAAS_Volt_f32	19.9050999
k_VBattMaxBSI_Volt_f32	17.4927006
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	6.42770004
k_VBattMaxCMM_Volt_f32	27.1410999
k_VBattMaxESP_Volt_f32	21.2605
k_VBattMinAAS_Volt_f32	7.2572999
k_VBattMinBSI_Volt_f32	21.2605
k_VBattMinCAV_Volt_f32	25.4519005
k_VBattMinCMM388_Volt_f32	21.0818005
k_VBattMinCMM_Volt_f32	10.5214005
k_VBattMinESP_Volt_f32	27.1410999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	4499
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	44674
k_VitesseVehicleBVRampValidThresh_Cnt_u16	47485
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	14528
k_VitesseVehicleBVSigValidThresh_Cnt_u16	51806
k_VitesseVehicleBVSpeedPassThresh_kph_f32	312.254913
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	51423
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	7138
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3416796928
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	46913

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	483581440
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	179
target_SrlComInput_Per1_Batt_Volt_f32.value	5.00960016
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	963829504
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	113
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.692129135
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1092800256
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1816293120
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2826047232
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2645667584
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4093726464
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	160
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1398861568
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1674612480
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	113
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	148
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	155
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	201
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	76
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2223943424
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	88
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	142
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	144
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	189
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	216
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	234
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2943995648
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3826872064
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	138
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3922267904
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	6
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	30
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	79
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	123
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	150
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	170
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2591055616
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3534
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.432012469
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	309991
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	49.1916008
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	41198

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	483581440	483581440	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	483581440	483581440	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	483581440	483581440	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	483581440	483581440	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	483581440	483581440	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	483581440	483581440	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	483581440	483581440	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	483581440	483581440	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	483581440	483581440	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	483581440	483581440	✔
CDD_SrlComVehSpd_Kph_G_f32	655.310913	655.310913	✔
CMM388NTCEnableTimer_mS_M_u32	483581440	483581440	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	483581440	483581440	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	483581440	483581440	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	3313	3313	✔
CONSANGLECPK_HwDeg_M_f32	-373.283691	-373.283691 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	483581440	483581440	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	483581440	483581440	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	483581440	483581440	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	483581440	483581440	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	483581440	483581440	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	483581440	483581440	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	483581440	483581440	✔
ESPNTCEnableTimer_mS_M_u32	483581440	483581440	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ESPNodeAbsentTimer_mS_M_u32	483581440	483581440	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	79	79	✔
EffacDefaultDiagTimer_mS_M_u32[1]	699	699	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	65	65	✔
ElecIntTimer_mS_M_u32[1]	655	655	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	483581440	483581440	✔
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	37431	37431	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	483581440	483581440	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	53213	53213	✔
ISDATBSI3F2MsgTimer_mS_M_u32	483581440	483581440	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	53623	53623	✔
ISDATBSI412MsgTimer_mS_M_u32	483581440	483581440	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	1188	1188	✔
ISDATBSI432MsgTimer_mS_M_u32	483581440	483581440	✔
ISDATDIRASentFltAcc_Cnt_M_u16	21842	21842	✔
ISDATDIRASentTimer_mS_M_u32	483581440	483581440	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	32890	32890	✔
ISDYN2CMMMsgTimer_mS_M_u32	483581440	483581440	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	39520	39520	✔
ISDYNAASMsgTimer_mS_M_u32	483581440	483581440	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	3313	3313	✔
ISDYNABRMsgTimer_mS_M_u32	483581440	483581440	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	53213	53213	✔
ISDYNCMM208MsgTimer_mS_M_u32	483581440	483581440	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	37211	37211	✔
ISDYNCMM388MsgTimer_mS_M_u32	483581440	483581440	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	43121	43121	✔
ISDYNVOLMsgTimer_mS_M_u32	483581440	483581440	✔
IgnOnTimer_mS_M_u32	3657486080	3657486080	✔
IgnTimeOff_Sec_M_u32	1066987078	1066987078	✔
Msg348Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	229	229	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1092800256	1092800256	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	167	167	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1816293120	1816293120	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	37	37	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2826047232	2826047232	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	9	9	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2645667584	2645667584	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1554714368	1554714368	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	160	160	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1398861568	1398861568	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1674612480	1674612480	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	76	76	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2223943424	2223943424	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	55	55	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2943995648	2943995648	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	34	34	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3826872064	3826872064	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	138	138	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3922267904	3922267904	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2591055616	2591055616	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	498.735291	498.735291	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	152.065094	152.065094	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	39.4556999	39.4556999	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	3313	3313	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1066987078	1066987078	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-373.283691	-373.283691 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.244 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3524789760
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	57126
AASNodeAbsentTimer_mS_M_u32	380106240
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	28267
ANGLEVOLANTSigValidCount_Cnt_M_u16	43084
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	49363
AngleVolantMsgTimer_mS_M_u32	3524789760
AngleVolantValidCount_Cnt_M_u16	30682
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3664492032
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2149725696
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	403744256
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	865297920
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	23778
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2893096448
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	20539
CAVNodeAbsentTimer_mS_M_u32	469014016
CDD_SrlComVehSpd_Kph_G_f32	653.967285
CMM388NTCEnableTimer_mS_M_u32	4244428288
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1420465664
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	63046
CMMNodeAbsentTimer_mS_M_u32	2304599552
CONSANGLECPKSigInvalidCount_Cnt_M_u16	51770
CONSANGLECPKSigValidCount_Cnt_M_u16	37996
CONSANGLECPK_Cnt_M_u16	8263
CONSANGLECPK_HwDeg_M_f32	290.1586
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	8263
CPKVehicleSpeedMsgTimer_mS_M_u32	3544647168
CPKVehicleSpeedValidCount_Cnt_M_u16	1835
CityParkInputConsistentCount_Cnt_M_u16	26622
CityParkInputInvalidCount_Cnt_M_u16	27543
CityParkInputMsgTimer_mS_M_u32	1092800256
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	265025024
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	50506

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1996297728
ComputerRazGCTSigValidCount_Cnt_M_u16	58851
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	6003
DMDFCTCPKSigValidCount_Cnt_M_u16	24637
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	11645
DMDRELAXECPKSigValidCount_Cnt_M_u16	61662
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	29927
DateInvalidTimer_mS_M_u32	2149725696
DiagMuxOnAbsentTimer_mS_M_u32	3352675840
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	865297920
ESPNTCEnableTimer_mS_M_u32	3644388864
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	23652
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	86
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	88
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	199435776
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	25652
EtatMTSigValidCount_Cnt_M_u16	64961
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	16204
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	4862
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	29427
ISDAT4V2BSI552MsgTimer_mS_M_u32	3582027264
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	58151
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	24188
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	64961
ISDATBSI3F2MsgTimer_mS_M_u32	3938698752
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	49113
ISDATBSI412MsgLenValidCount_Cnt_M_u16	26719
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	25652
ISDATBSI412MsgTimer_mS_M_u32	3674605056
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	54634
ISDATBSI432MsgLenValidCount_Cnt_M_u16	3720
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	58348
ISDATDIRASentFltAcc_Cnt_M_u16	21280
ISDATDIRASentTimer_mS_M_u32	3544647168
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	14773
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	30682
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	63338
ISDYN2CMMMsgTimer_mS_M_u32	2206397952
ISDYNAASChkSumInvalidCount_Cnt_M_u16	27192
ISDYNAASChkSumValidCount_Cnt_M_u16	55473
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	15825
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	5206
ISDYNAASMsgLenValidCount_Cnt_M_u16	20047
ISDYNAASMsgTimeValidCount_Cnt_M_u16	27192
ISDYNAASMsgTimer_mS_M_u32	2111362560
ISDYNABRChkSumInvalidCount_Cnt_M_u16	20070
ISDYNABRChkSumValidCount_Cnt_M_u16	40975
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	2735
ISDYNABRMsgCountValidCount_Cnt_M_u16	1776
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	56753
ISDYNABRMsgLenValidCount_Cnt_M_u16	8995
ISDYNABRMsgTimeValidCount_Cnt_M_u16	8263
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	44577
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	23688
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	64961
ISDYNCMM208MsgTimer_mS_M_u32	2156967424
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	44577
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	23688
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	14280

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3899938304
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	9512
ISDYNVOLChkSumValidCount_Cnt_M_u16	58842
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	9569
ISDYNVOLMsgCountValidCount_Cnt_M_u16	42155
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	64237
ISDYNVOLMsgLenValidCount_Cnt_M_u16	40446
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	63046
ISDYNVOLMsgTimer_mS_M_u32	1675171328
IgnOnTimer_mS_M_u32	4288173568
IgnTimeOff_Sec_M_u32	2047726560
ManVehSpd_Kph_M_f32	483.432098
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	116
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	201
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3982083584
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	38
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2976359936
PrevISDATBSI412MsgDLCError_Cnt_M_u08	11
PrevISDATBSI412MsgRxTime_MSec_M_u32	3261437440
PrevISDATBSI432MsgDLCError_Cnt_M_u08	52
PrevISDATBSI432MsgRxTime_MSec_M_u32	818738688
PrevISDATDIRAMsgTxTime_MSec_M_u32	4036597248
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	197
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3993036288
PrevISDYNAASMsgDLCError_Cnt_M_u08	251
PrevISDYNAASMsgRxTime_MSec_M_u32	1162286592
PrevISDYNABRMsgDLCError_Cnt_M_u08	199
PrevISDYNABRMsgRxTime_MSec_M_u32	1146115584
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	246
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1357649408
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	178
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3383227904
PrevISDYNVOLMsgDLCError_Cnt_M_u08	242
PrevISDYNVOLMsgRxTime_MSec_M_u32	828544512
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	653526528
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	120.555901
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	2116
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	63677
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	62541
VitesseVehicleBVRampValidCount_Cnt_M_u16	2438
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	46068
VitesseVehicleBVSigValidCount_Cnt_M_u16	12949
VitesseVehicleBV_Kph_M_f32	552.939026
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	14280
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	55970
VitesseVehiculeRoues_Kph_M_f32	7.52839994
k_AASNTCEnableTimeout_mS_u16	43958
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	20653
k_AASNodeTimeout_mS_u16	11197
k_ABSNodeTimeout_mS_u16	27992
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	45949
k_ANGLEVOLANTSigValidThresh_Cnt_u16	25819
k_AngleVolantInvalidThresh_Cnt_u16	8090
k_AngleVolantValidThresh_Cnt_u16	27543
k_BSI552MsgTimeout_mS_u16	51745
k_BSINTCEnableTimeout_mS_u16	35362
k_BSINodeAbsentDiag_Cnt_str.Threshold	32059
k_BSINodeAbsentDiag_Cnt_str.PStep	39120
k_BSINodeAbsentDiag_Cnt_str.NStep	17513
k_BSINodeAbsentTimeout_mS_u16	1931
k_BSINodeTimeout_mS_u16	58348
k_BattOvHi_Volt_f32	28.9899006
k_BattOvLo_Volt_f32	16.8181
k_BattUvHi_Volt_f32	4.59959984
k_BattUvLo_Volt_f32	22.2408009
k_CAVNTCEnableTimeout_mS_u16	42045
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	28457
k_CAVNodeTimeout_mS_u16	49942
k_CMM388MsgTimeout_mS_u16	21030
k_CMM388NTCEnableTimeout_mS_u16	44034
k_CMMNTCEnableTimeout_mS_u16	46047
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	27262
k_CONSANGLECPKMax_HwDeg_f32	255.950104
k_CONSANGLECPKMin_HwDeg_f32	-58.0259018
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	10952
k_CONSANGLECPKSigValidThresh_Cnt_u16	3490
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	26995
k_CPKVehicleSpeedValidThresh_Cnt_u16	46516
k_CityParkInputInvalidThresh_Cnt_u16	12444
k_CityParkInputValidThresh_Cnt_u16	26622
k_ComputerRazGCTSigValidThresh_Cnt_u16	30781
k_CptTemporelSigValidThresh_Cnt_u16	47122
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	20657
k_DMDFCTCPKSigValidThresh_Cnt_u16	54819
k_DMDFCTCPKValidCount_Cnt_u16	39210
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	63338
k_DMDRELAXECPKSigValidThresh_Cnt_u16	7028
k_DMDRelaxeConsistentThresh_Cnt_u16	49962
k_DateValidThresh_Cnt_u16	29427
k_DefaultVehSpd_Kph_f32	239.957596
k_DiagMuxOnAbsentTimeout_mS_u16	29293
k_EMNodeTimeout_mS_u16	28743
k_ESPNTCEnableTimeout_mS_u16	27415
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	48582
k_EtatMTSigInvalidThresh_Cnt_u16	36101
k_EtatMTSigValidThresh_Cnt_u16	59374
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	62254
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	2972
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	42503
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	52724
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	47369
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	50429
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	45495
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	31381
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	62606
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	8395
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	41840
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	18671
k_ISDATDIRASentDiag_Cnt_str.Threshold	38287

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	11594
k_ISDATDIRASentDiag_Cnt_str.NStep	1219
k_ISDATDIRASentTimeout_mS_u16	25922
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	53268
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	49363
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	49283
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	16742
k_ISDYNAASChkSumValidThresh_Cnt_u16	54031
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	32175
k_ISDYNAASMsgCountValidThresh_Cnt_u16	47600
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	27274
k_ISDYNAASMsgLenValidThresh_Cnt_u16	29665
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	63011
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	5023
k_ISDYNABRChkSumValidThresh_Cnt_u16	36753
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	53218
k_ISDYNABRMsgCountValidThresh_Cnt_u16	1283
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	10566
k_ISDYNABRMsgLenValidThresh_Cnt_u16	53092
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	61954
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	61544
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	13090
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	45628
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	57707
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	23372
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	63055
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	15980
k_ISDYNVOLChkSumValidThresh_Cnt_u16	48946
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	32017
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	20275
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	21520
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	23197
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	60441
k_IgnOnTimeout_mS_u16	35144
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	20.8155003
k_PowerCutVehSpdLowThresh_Kph_f32	249.885803
k_PowerCutVehSpdLowTimeout_mS_u16	50050
k_VBattMaxAAS_Volt_f32	3.17210007
k_VBattMaxBSI_Volt_f32	12.0206003
k_VBattMaxCAV_Volt_f32	26.8806
k_VBattMaxCMM388_Volt_f32	2.12890005
k_VBattMaxCMM_Volt_f32	25.9368
k_VBattMaxESP_Volt_f32	29.3668003
k_VBattMinAAS_Volt_f32	25.2278996
k_VBattMinBSI_Volt_f32	29.3668003
k_VBattMinCAV_Volt_f32	24.4946003
k_VBattMinCMM388_Volt_f32	14.4664001
k_VBattMinCMM_Volt_f32	18.6583004
k_VBattMinESP_Volt_f32	25.9368
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	3422
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	60244
k_VitesseVehicleBVRampValidThresh_Cnt_u16	6241
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	39130
k_VitesseVehicleBVSigValidThresh_Cnt_u16	22719
k_VitesseVehicleBVSpeedPassThresh_kph_f32	401.180511
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	17211
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	20212
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2149725696
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	62889
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3592300800
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	178
target_SrlComInput_Per1_Batt_Volt_f32.value	20.5781002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4253165056
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	96
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0642749369
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3526514176
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3612571136
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3913586176
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	193
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	268809728
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1402394112
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	138
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3153589760
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1361647104
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	85
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	140
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	190
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	192
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	258913792
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	67
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	131
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	187
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	97
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2737657344
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2345563648
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	116
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1094686208
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	53
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	77
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	94
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	177
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	189
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2961810944
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2540
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.164741233
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	826415
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	11.0296001
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	46862

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3592300800	3592300800	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3592300800	3592300800	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	49363	49363	✔
AngleVolantMsgTimer_mS_M_u32	3592300800	3592300800	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3592300800	3592300800	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3592300800	3592300800	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3592300800	3592300800	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3592300800	3592300800	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3592300800	3592300800	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3592300800	3592300800	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3592300800	3592300800	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3592300800	3592300800	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3592300800	3592300800	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3592300800	3592300800	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	8263	8263	✔
CONSANGLECPK_HwDeg_M_f32	290.1586	290.1586 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	8263	8263	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3544647168	3544647168	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	1835	1835	✔
CityParkInputConsistentCount_Cnt_M_u16	26622	26622	✔
CityParkInputInvalidCount_Cnt_M_u16	27543	27543	✔
CityParkInputMsgTimer_mS_M_u32	3592300800	3592300800	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3592300800	3592300800	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3592300800	3592300800	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3592300800	3592300800	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3592300800	3592300800	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3592300800	3592300800	✔
ESPNTCEnableTimer_mS_M_u32	3592300800	3592300800	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3592300800	3592300800	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔
EffacDefaultDiagTimer_mS_M_u32[1]	86	86	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	8	8	✔
ElecIntTimer_mS_M_u32[1]	88	88	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3592300800	3592300800	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3592300800	3592300800	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3592300800	3592300800	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3592300800	3592300800	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3592300800	3592300800	✔
ISDATDIRASentFltAcc_Cnt_M_u16	38287	38287	✔
ISDATDIRASentTimer_mS_M_u32	3592300800	3592300800	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3592300800	3592300800	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3592300800	3592300800	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3592300800	3592300800	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3592300800	3592300800	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3592300800	3592300800	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3592300800	3592300800	✔
IgnOnTimer_mS_M_u32	4288173568	4288173568	✔
IgnTimeOff_Sec_M_u32	2047726560	2047726560	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	57	57	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3526514176	3526514176	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	91	91	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3612571136	3612571136	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	134	134	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3913586176	3913586176	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	193	193	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	268809728	268809728	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4036597248	4036597248	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	138	138	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3153589760	3153589760	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	40	40	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1361647104	1361647104	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	173	173	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	258913792	258913792	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	97	97	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2737657344	2737657344	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2345563648	2345563648	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	116	116	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1094686208	1094686208	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2961810944	2961810944	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	120.555901	120.555901	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	552.939026	552.939026	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	7.52839994	7.52839994	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	8263	8263	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2047726560	2047726560	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	290.1586	290.1586 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	239.957596	239.957596	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.245 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2632888576
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	53187
AASNodeAbsentTimer_mS_M_u32	989782272
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	54261
ANGLEVOLANTSigValidCount_Cnt_M_u16	47121
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	7868
AngleVolantMsgTimer_mS_M_u32	2632888576
AngleVolantValidCount_Cnt_M_u16	32294
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2931007744
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3079676160
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	4119122176
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	503091456
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	42128
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1516458240
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	5893
CAVNodeAbsentTimer_mS_M_u32	2778267904
CDD_SrlComVehSpd_Kph_G_f32	385.190186
CMM388NTCEnableTimer_mS_M_u32	1937785088
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1400307968
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	12194
CMMNodeAbsentTimer_mS_M_u32	3298726144
CONSANGLECPKSigInvalidCount_Cnt_M_u16	44934
CONSANGLECPKSigValidCount_Cnt_M_u16	8882
CONSANGLECPK_Cnt_M_u16	43809
CONSANGLECPK_HwDeg_M_f32	-121.732903
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43809
CPKVehicleSpeedMsgTimer_mS_M_u32	358723840
CPKVehicleSpeedValidCount_Cnt_M_u16	36956
CityParkInputConsistentCount_Cnt_M_u16	15802
CityParkInputInvalidCount_Cnt_M_u16	10223

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	3526514176
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3750945024
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	44375
ComputerRazGCTSigInvalidTimer_mS_M_u32	1451196672
ComputerRazGCTSigValidCount_Cnt_M_u16	38923
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	37979
DMDFCTCPKSigValidCount_Cnt_M_u16	60350
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	24255
DMDRELAXECPKSigValidCount_Cnt_M_u16	42587
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	41855
DateInvalidTimer_mS_M_u32	3079676160
DiagMuxOnAbsentTimer_mS_M_u32	3803541760
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	503091456
ESPNTCEnableTimer_mS_M_u32	2001461504
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	32521
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	5
EffacDefaultDiagTimer_mS_M_u32[1]	155
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	79
ElecIntTimer_mS_M_u32[1]	699
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2215465216
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	10970
EtatMTSigValidCount_Cnt_M_u16	40946
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	6224
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	28412
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	2972
ISDAT4V2BSI552MsgTimer_mS_M_u32	1882362112
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	13184
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	9024
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	40946
ISDATBSI3F2MsgTimer_mS_M_u32	2984997120
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	13929
ISDATBSI412MsgLenValidCount_Cnt_M_u16	24217
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	10970
ISDATBSI412MsgTimer_mS_M_u32	3122966784
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	8758
ISDATBSI432MsgLenValidCount_Cnt_M_u16	63645
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	24562
ISDATDIRASentFltAcc_Cnt_M_u16	57942
ISDATDIRASentTimer_mS_M_u32	358723840
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	38615
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	32294
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36982
ISDYN2CMMMsgTimer_mS_M_u32	544071936
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0
ISDYNAASChkSumValidCount_Cnt_M_u16	50504
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	51265
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	63156
ISDYNAASMsgLenValidCount_Cnt_M_u16	14984
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0
ISDYNAASMsgTimer_mS_M_u32	1626095872
ISDYNABRChkSumInvalidCount_Cnt_M_u16	55683
ISDYNABRChkSumValidCount_Cnt_M_u16	38471
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	45352
ISDYNABRMsgCountValidCount_Cnt_M_u16	52771
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	4385
ISDYNABRMsgLenValidCount_Cnt_M_u16	4749
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43809
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	33894
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	20977

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	40946
ISDYNCMM208MsgTimer_mS_M_u32	2420416768
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	33894
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	20977
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	30300
ISDYNCMM388MsgTimer_mS_M_u32	4011442432
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	54972
ISDYNVOLChkSumValidCount_Cnt_M_u16	26216
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	41617
ISDYNVOLMsgCountValidCount_Cnt_M_u16	22132
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	1902
ISDYNVOLMsgLenValidCount_Cnt_M_u16	28666
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	12194
ISDYNVOLMsgTimer_mS_M_u32	4293624064
IgnOnTimer_mS_M_u32	967688448
IgnTimeOff_Sec_M_u32	24461840
ManVehSpd_Kph_M_f32	311.602203
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	117
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	197
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2183753984
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	113
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1166004480
PrevISDATBSI412MsgDLCError_Cnt_M_u08	199
PrevISDATBSI412MsgRxTime_MSec_M_u32	3058041088
PrevISDATBSI432MsgDLCError_Cnt_M_u08	146
PrevISDATBSI432MsgRxTime_MSec_M_u32	3230654720
PrevISDATDIRAMsgTxTime_MSec_M_u32	4222222592
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	72
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2226393344
PrevISDYNAASMsgDLCError_Cnt_M_u08	121
PrevISDYNAASMsgRxTime_MSec_M_u32	2476835072
PrevISDYNABRMsgDLCError_Cnt_M_u08	136
PrevISDYNABRMsgRxTime_MSec_M_u32	1267056896
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	156
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1152549120
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	105
PrevISDYNCMM388MsgRxTime_MSec_M_u32	570351872
PrevISDYNVOLMsgDLCError_Cnt_M_u08	128
PrevISDYNVOLMsgRxTime_MSec_M_u32	2639200512
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	240824576
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	616.340271
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	21226
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	29502
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	62159
VitesseVehicleBVRampValidCount_Cnt_M_u16	42211
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	26458
VitesseVehicleBVSigValidCount_Cnt_M_u16	32054
VitesseVehicleBV_Kph_M_f32	485.732788

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	30300
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	65424
VitesseVehiculeRoues_Kph_M_f32	177.300995
k_AASNTCEnableTimeout_mS_u16	34004
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	65453
k_AASNodeTimeout_mS_u16	55870
k_ABSNodeTimeout_mS_u16	26284
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	37885
k_ANGLEVOLANTSigValidThresh_Cnt_u16	420
k_AngleVolantInvalidThresh_Cnt_u16	36199
k_AngleVolantValidThresh_Cnt_u16	10223
k_BSI552MsgTimeout_mS_u16	60691
k_BSINTCEnableTimeout_mS_u16	58382
k_BSINodeAbsentDiag_Cnt_str.Threshold	63639
k_BSINodeAbsentDiag_Cnt_str.PStep	48409
k_BSINodeAbsentDiag_Cnt_str.NStep	57742
k_BSINodeAbsentTimeout_mS_u16	10900
k_BSINodeTimeout_mS_u16	24562
k_BattOvHi_Volt_f32	14.3978996
k_BattOvLo_Volt_f32	29.9342995
k_BattUvHi_Volt_f32	3.84319997
k_BattUvLo_Volt_f32	12.0791998
k_CAVNTCEnableTimeout_mS_u16	38397
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	62011
k_CAVNodeTimeout_mS_u16	13554
k_CMM388MsgTimeout_mS_u16	30403
k_CMM388NTCEnableTimeout_mS_u16	55599
k_CMMNTCEnableTimeout_mS_u16	41304
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	49148
k_CONSANGLECPKMax_HwDeg_f32	138.884293
k_CONSANGLECPKMin_HwDeg_f32	-423.036194
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	40284
k_CONSANGLECPKSigValidThresh_Cnt_u16	26256
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	31004
k_CPKVehicleSpeedValidThresh_Cnt_u16	32984
k_CityParkInputInvalidThresh_Cnt_u16	35553
k_CityParkInputValidThresh_Cnt_u16	15802
k_ComputerRazGCTSigValidThresh_Cnt_u16	19518
k_CptTemporelSigValidThresh_Cnt_u16	61054
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	47137
k_DMDFCTCPKSigValidThresh_Cnt_u16	63885
k_DMDFCTCPKValidCount_Cnt_u16	4024
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	36982
k_DMDRELAXECPKSigValidThresh_Cnt_u16	22041
k_DMDRelaxeConsistentThresh_Cnt_u16	46839
k_DateValidThresh_Cnt_u16	2972
k_DefaultVehSpd_Kph_f32	159.841095
k_DiagMuxOnAbsentTimeout_mS_u16	52399
k_EMNodeTimeout_mS_u16	12639
k_ESPNTCEnableTimeout_mS_u16	13937
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	58916
k_EtatMTSigInvalidThresh_Cnt_u16	22950
k_EtatMTSigValidThresh_Cnt_u16	64170
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	34795
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	98
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	59295
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	59161
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	34713
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	46845
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	335
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	10358

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	21706
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	47509
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	54116
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	50214
k_ISDATDIRASentDiag_Cnt_str.Threshold	4099
k_ISDATDIRASentDiag_Cnt_str.PStep	41674
k_ISDATDIRASentDiag_Cnt_str.NStep	32409
k_ISDATDIRASentTimeout_mS_u16	1263
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	695
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	7868
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	58925
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	131
k_ISDYNAASChkSumValidThresh_Cnt_u16	64839
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	22568
k_ISDYNAASMsgCountValidThresh_Cnt_u16	46371
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	5399
k_ISDYNAASMsgLenValidThresh_Cnt_u16	37330
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	28108
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	42839
k_ISDYNABRChkSumValidThresh_Cnt_u16	1347
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	19344
k_ISDYNABRMsgCountValidThresh_Cnt_u16	15852
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	38562
k_ISDYNABRMsgLenValidThresh_Cnt_u16	9737
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	13039
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	10878
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16526
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	705
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	31477
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	40721
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	26567
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	50864
k_ISDYNVOLChkSumValidThresh_Cnt_u16	26144
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	4354
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	6363
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	52038
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	63838
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	47146
k_IgnOnTimeout_mS_u16	22044
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	167.767303
k_PowerCutVehSpdLowThresh_Kph_f32	192.556396
k_PowerCutVehSpdLowTimeout_mS_u16	28016
k_VBattMaxAAS_Volt_f32	28.8607998
k_VBattMaxBSI_Volt_f32	30.4813004
k_VBattMaxCAV_Volt_f32	8.62100029
k_VBattMaxCMM388_Volt_f32	24.4171009
k_VBattMaxCMM_Volt_f32	25.1487999
k_VBattMaxESP_Volt_f32	24.4946995
k_VBattMinAAS_Volt_f32	10.3565998
k_VBattMinBSI_Volt_f32	24.4946995
k_VBattMinCAV_Volt_f32	16.0046997
k_VBattMinCMM388_Volt_f32	16.5053005
k_VBattMinCMM_Volt_f32	20.3973007
k_VBattMinESP_Volt_f32	25.1487999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	62169
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	15033
k_VitesseVehicleBVRampValidThresh_Cnt_u16	51601
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	19816
k_VitesseVehicleBVSigValidThresh_Cnt_u16	44919
k_VitesseVehicleBVSpeedPassThresh_kph_f32	610.915283
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	15877
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	3225
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3079676160
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65021
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3374860288
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	105

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	19.6049995
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3945812224
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	159
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.198150694
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	116
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2850013440
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	117203200
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2108227840
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4125466880
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1471299840
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2333008128
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2012971264
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	31
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	104
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	244
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3685392640
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	28
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	44
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	121
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	133
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	182
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	192
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3807297792
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2508939520
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	565707008
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	32
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	48
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	56
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	68
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	72
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	149
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1343869184
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2913
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.152817532
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	421174
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	228.375
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	61068

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3374860288	3374860288	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3374860288	3374860288	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	7870	7870	✔
AngleVolantMsgTimer_mS_M_u32	3374860288	3374860288	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3374860288	3374860288	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3374860288	3374860288	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3374860288	3374860288	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3374860288	3374860288	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3374860288	3374860288	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3374860288	3374860288	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3374860288	3374860288	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3374860288	3374860288	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3374860288	3374860288	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3374860288	3374860288	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	43809	43809	✔
CONSANGLECPK_HwDeg_M_f32	-121.732903	-121.732903 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43809	43809	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	358723840	358723840	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	36956	36956	✔
CityParkInputConsistentCount_Cnt_M_u16	15802	15802	✔
CityParkInputInvalidCount_Cnt_M_u16	10225	10225	✔
CityParkInputMsgTimer_mS_M_u32	3374860288	3374860288	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3374860288	3374860288	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3374860288	3374860288	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3374860288	3374860288	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3374860288	3374860288	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3374860288	3374860288	✔
ESPNTCEnableTimer_mS_M_u32	3374860288	3374860288	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3374860288	3374860288	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3374860288	3374860288	✔
EffacDefaultDiagTimer_mS_M_u32[1]	155	155	✔
ElecIntCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	3374860288	3374860288	✔
ElecIntTimer_mS_M_u32[1]	699	699	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3374860288	3374860288	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3374860288	3374860288	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3374860288	3374860288	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3374860288	3374860288	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3374860288	3374860288	✔
ISDATDIRASentFltAcc_Cnt_M_u16	4099	4099	✔
ISDATDIRASentTimer_mS_M_u32	3374860288	3374860288	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3374860288	3374860288	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3374860288	3374860288	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3374860288	3374860288	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3374860288	3374860288	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3374860288	3374860288	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3374860288	3374860288	✔
IgnOnTimer_mS_M_u32	967688448	967688448	✔
IgnTimeOff_Sec_M_u32	24461840	24461840	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	116	116	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2850013440	2850013440	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	117203200	117203200	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	104	104	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2108227840	2108227840	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	3	3	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4125466880	4125466880	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4222222592	4222222592	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	0	0	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2333008128	2333008128	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	51	51	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2012971264	2012971264	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	34	34	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3685392640	3685392640	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	170	170	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3807297792	3807297792	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	135	135	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2508939520	2508939520	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	565707008	565707008	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1343869184	1343869184	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	616.340271	616.340271	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	485.732788	485.732788	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	177.300995	177.300995	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	43809	43809	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	24461840	24461840	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-121.732903	-121.732903 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	159.841095	159.841095	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.246 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1087811584
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	39513
AASNodeAbsentTimer_mS_M_u32	593895424
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	30657
ANGLEVOLANTSigValidCount_Cnt_M_u16	5678
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	53614
AngleVolantMsgTimer_mS_M_u32	1087811584
AngleVolantValidCount_Cnt_M_u16	9646
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2336743424
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2192728064
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3079950336
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3442282496
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	12784
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	586731520
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	62738
CAVNodeAbsentTimer_mS_M_u32	1947713536
CDD_SrlComVehSpd_Kph_G_f32	543.954712
CMM388NTCEnableTimer_mS_M_u32	3076653056
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1652408320
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	35580
CMMNodeAbsentTimer_mS_M_u32	3779530752
CONSANGLECPKSigInvalidCount_Cnt_M_u16	6159
CONSANGLECPKSigValidCount_Cnt_M_u16	18764
CONSANGLECPK_Cnt_M_u16	11263
CONSANGLECPK_HwDeg_M_f32	183.572601
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	11263
CPKVehicleSpeedMsgTimer_mS_M_u32	1669181440
CPKVehicleSpeedValidCount_Cnt_M_u16	20118
CityParkInputConsistentCount_Cnt_M_u16	14066
CityParkInputInvalidCount_Cnt_M_u16	39253
CityParkInputMsgTimer_mS_M_u32	2850013440
CityParkInputValidCount_Cnt_M_u16	9

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2242519040
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	20893
ComputerRazGCTSigInvalidTimer_mS_M_u32	459554816
ComputerRazGCTSigValidCount_Cnt_M_u16	44031
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	1041
DMDFCTCPKSigValidCount_Cnt_M_u16	26790
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	32611
DMDRELAXECPKSigValidCount_Cnt_M_u16	62288
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	24612
DateInvalidTimer_mS_M_u32	2192728064
DiagMuxOnAbsentTimer_mS_M_u32	4202852352
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3442282496
ESPNTCEnableTimer_mS_M_u32	3799982080
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	6020
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1111
EffacDefaultDiagTimer_mS_M_u32[1]	2222
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	37
ElecIntTimer_mS_M_u32[1]	86
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3455766528
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	51795
EtatMTSigValidCount_Cnt_M_u16	42444
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	34225
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	3182
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	268
ISDAT4V2BSI552MsgTimer_mS_M_u32	780865536
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	8161
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	11106
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	42444
ISDATBSI3F2MsgTimer_mS_M_u32	3839913984
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	19493
ISDATBSI412MsgLenValidCount_Cnt_M_u16	28246
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	51795
ISDATBSI412MsgTimer_mS_M_u32	1093971968
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	832
ISDATBSI432MsgLenValidCount_Cnt_M_u16	64200
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	3659
ISDATDIRASentFltAcc_Cnt_M_u16	5919
ISDATDIRASentTimer_mS_M_u32	1669181440
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	49373
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	9646
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	15296
ISDYN2CMMMsgTimer_mS_M_u32	4011401216
ISDYNAASChkSumInvalidCount_Cnt_M_u16	65535
ISDYNAASChkSumValidCount_Cnt_M_u16	11400
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	29533
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	53765
ISDYNAASMsgLenValidCount_Cnt_M_u16	12618
ISDYNAASMsgTimeValidCount_Cnt_M_u16	65535
ISDYNAASMsgTimer_mS_M_u32	2669543424
ISDYNABRChkSumInvalidCount_Cnt_M_u16	30360
ISDYNABRChkSumValidCount_Cnt_M_u16	11021
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	51754
ISDYNABRMsgCountValidCount_Cnt_M_u16	15863
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	7998
ISDYNABRMsgLenValidCount_Cnt_M_u16	42427
ISDYNABRMsgTimeValidCount_Cnt_M_u16	11263
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	26546
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	29907
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	42444
ISDYNCMM208MsgTimer_mS_M_u32	1788141568

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	26546
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	29907
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	38156
ISDYNCMM388MsgTimer_mS_M_u32	2325053440
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	64109
ISDYNVOLChkSumValidCount_Cnt_M_u16	54826
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	12655
ISDYNVOLMsgCountValidCount_Cnt_M_u16	32900
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	21077
ISDYNVOLMsgLenValidCount_Cnt_M_u16	9074
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	35580
ISDYNVOLMsgTimer_mS_M_u32	3474997248
IgnOnTimer_mS_M_u32	4208558080
IgnTimeOff_Sec_M_u32	1545755817
ManVehSpd_Kph_M_f32	551.280029
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	118
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	156
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3961942016
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	79
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1940082688
PrevISDATBSI412MsgDLCError_Cnt_M_u08	62
PrevISDATBSI412MsgRxTime_MSec_M_u32	907067392
PrevISDATBSI432MsgDLCError_Cnt_M_u08	11
PrevISDATBSI432MsgRxTime_MSec_M_u32	380837888
PrevISDATDIRAMsgTxTime_MSec_M_u32	4125409280
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	170
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3607531520
PrevISDYNAASMsgDLCError_Cnt_M_u08	160
PrevISDYNAASMsgRxTime_MSec_M_u32	1811824640
PrevISDYNABRMsgDLCError_Cnt_M_u08	21
PrevISDYNABRMsgRxTime_MSec_M_u32	626098176
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	249
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3704307712
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	148
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1852186624
PrevISDYNVOLMsgDLCError_Cnt_M_u08	203
PrevISDYNVOLMsgRxTime_MSec_M_u32	3841310720
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2626859008
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	19.7168999
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	5475
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	57128
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	2484
VitesseVehicleBVRampValidCount_Cnt_M_u16	7737
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	37266
VitesseVehicleBVSigValidCount_Cnt_M_u16	39615
VitesseVehicleBV_Kph_M_f32	193.614105
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	38156
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	42033

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	389.500305
k_AASNTCEnableTimeout_mS_u16	10982
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	32025
k_AASNodeTimeout_mS_u16	43560
k_ABSNodeTimeout_mS_u16	4382
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	35307
k_ANGLEVOLANTSigValidThresh_Cnt_u16	48051
k_AngleVolantInvalidThresh_Cnt_u16	58474
k_AngleVolantValidThresh_Cnt_u16	39253
k_BSI552MsgTimeout_mS_u16	42920
k_BSINTCEnableTimeout_mS_u16	7608
k_BSINodeAbsentDiag_Cnt_str.Threshold	26272
k_BSINodeAbsentDiag_Cnt_str.PStep	54107
k_BSINodeAbsentDiag_Cnt_str.NStep	61498
k_BSINodeAbsentTimeout_mS_u16	3558
k_BSINodeTimeout_mS_u16	3659
k_BattOvHi_Volt_f32	20.5223007
k_BattOvLo_Volt_f32	4.35020018
k_BattUvHi_Volt_f32	10.8629999
k_BattUvLo_Volt_f32	30.1762009
k_CAVNTCEnableTimeout_mS_u16	1835
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	47984
k_CAVNodeTimeout_mS_u16	14283
k_CMM388MsgTimeout_mS_u16	42329
k_CMM388NTCEnableTimeout_mS_u16	11797
k_CMMNTCEnableTimeout_mS_u16	13913
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	4845
k_CONSANGLECPKMax_HwDeg_f32	235.103104
k_CONSANGLECPKMin_HwDeg_f32	-580.589417
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	8204
k_CONSANGLECPKSigValidThresh_Cnt_u16	28465
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	50574
k_CPKVehicleSpeedValidThresh_Cnt_u16	59608
k_CityParkInputInvalidThresh_Cnt_u16	23166
k_CityParkInputValidThresh_Cnt_u16	14066
k_ComputerRazGCTSigValidThresh_Cnt_u16	19879
k_CptTemporelSigValidThresh_Cnt_u16	16808
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	10814
k_DMDFCTCPKSigValidThresh_Cnt_u16	61627
k_DMDFCTCPKValidCount_Cnt_u16	36984
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	15296
k_DMDRELAXECPKSigValidThresh_Cnt_u16	21909
k_DMDRelaxeConsistentThresh_Cnt_u16	11003
k_DateValidThresh_Cnt_u16	268
k_DefaultVehSpd_Kph_f32	34.6124992
k_DiagMuxOnAbsentTimeout_mS_u16	32597
k_EMNodeTimeout_mS_u16	13956
k_ESPNTCEnableTimeout_mS_u16	18126
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	16501
k_EtatMTSigInvalidThresh_Cnt_u16	16943
k_EtatMTSigValidThresh_Cnt_u16	18916
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	38177
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	59002
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	3395
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	43286
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	41559
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	6761
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	2549
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	3901
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	48004
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	53411

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	40436
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	10222
k_ISDATDIRASentDiag_Cnt_str.Threshold	40739
k_ISDATDIRASentDiag_Cnt_str.PStep	47335
k_ISDATDIRASentDiag_Cnt_str.NStep	57041
k_ISDATDIRASentTimeout_mS_u16	42068
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	61499
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	53614
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10138
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	408
k_ISDYNAASChkSumValidThresh_Cnt_u16	62989
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	54570
k_ISDYNAASMsgCountValidThresh_Cnt_u16	35063
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	5084
k_ISDYNAASMsgLenValidThresh_Cnt_u16	54124
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	5947
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	46236
k_ISDYNABRChkSumValidThresh_Cnt_u16	9625
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	15600
k_ISDYNABRMsgCountValidThresh_Cnt_u16	45213
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	22012
k_ISDYNABRMsgLenValidThresh_Cnt_u16	8836
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	40340
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	56999
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	438
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	64671
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	33473
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	24878
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	14797
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	30544
k_ISDYNVOLChkSumValidThresh_Cnt_u16	13249
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	34201
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	62289
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	39183
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	18824
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	45922
k_IgnOnTimeout_mS_u16	30988
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	167.333694
k_PowerCutVehSpdLowThresh_Kph_f32	4.96659994
k_PowerCutVehSpdLowTimeout_mS_u16	57618
k_VBattMaxAAS_Volt_f32	6.76319981
k_VBattMaxBSI_Volt_f32	16.4037991
k_VBattMaxCAV_Volt_f32	13.8254004
k_VBattMaxCMM388_Volt_f32	9.81410027
k_VBattMaxCMM_Volt_f32	22.1529999
k_VBattMaxESP_Volt_f32	28.2082005
k_VBattMinAAS_Volt_f32	18.2866993
k_VBattMinBSI_Volt_f32	28.2082005
k_VBattMinCAV_Volt_f32	23.9974003
k_VBattMinCMM388_Volt_f32	12.2475996
k_VBattMinCMM_Volt_f32	17.1683998
k_VBattMinESP_Volt_f32	22.1529999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	10197
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	43766
k_VitesseVehicleBVRampValidThresh_Cnt_u16	48239
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	8490
k_VitesseVehicleBVSigValidThresh_Cnt_u16	5563
k_VitesseVehicleBVSpeedPassThresh_kph_f32	152.005096
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	32786
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	16151
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2192728064
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	51805
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1128655616
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	148
target_SrlComInput_Per1_Batt_Volt_f32.value	27.3269005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3834761216
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	44
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.903392553
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4064509952
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2506989568
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	736608256
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	112
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4256292864
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1389101056
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1932926976
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2800762880
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	55
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	64
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	102
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2690834432
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	24
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	62
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	166
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	230
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1125548032
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	234
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3854606336
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1002094592
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	33
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	146
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	185
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1003835392
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2374
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.847157776
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	428942
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	147.760696
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	19069

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1128655616	1128655616	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1128655616	1128655616	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	53616	53616	✔
AngleVolantMsgTimer_mS_M_u32	1128655616	1128655616	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1128655616	1128655616	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1128655616	1128655616	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1128655616	1128655616	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	11263	11263	✔
CONSANGLECPK_HwDeg_M_f32	183.572601	183.572601 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	11263	11263	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1669181440	1669181440	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	20118	20118	✔
CityParkInputConsistentCount_Cnt_M_u16	14066	14066	✔
CityParkInputInvalidCount_Cnt_M_u16	39253	39253	✔
CityParkInputMsgTimer_mS_M_u32	1128655616	1128655616	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1128655616	1128655616	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1128655616	1128655616	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1128655616	1128655616	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1128655616	1128655616	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1128655616	1128655616	✔
ESPNTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1128655616	1128655616	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1111	1111	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2222	2222	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1128655616	1128655616	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	86	86	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1128655616	1128655616	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDATDIRASentFltAcc_Cnt_M_u16	40739	40739	✔
ISDATDIRASentTimer_mS_M_u32	1128655616	1128655616	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1128655616	1128655616	✔
IgnOnTimer_mS_M_u32	4208558080	4208558080	✔
IgnTimeOff_Sec_M_u32	1545755817	1545755817	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	141	141	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4064509952	4064509952	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	241	241	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2506989568	2506989568	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	37	37	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	736608256	736608256	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	112	112	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4256292864	4256292864	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4125409280	4125409280	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1932926976	1932926976	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	174	174	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2800762880	2800762880	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	102	102	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2690834432	2690834432	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	230	230	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1125548032	1125548032	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	234	234	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3854606336	3854606336	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	125	125	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1002094592	1002094592	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1003835392	1003835392	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	19.7168999	19.7168999	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	193.614105	193.614105	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	389.500305	389.500305	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	11263	11263	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1545755817	1545755817	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	183.572601	183.572601 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.247 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4158305024
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	5459
AASNodeAbsentTimer_mS_M_u32	434922240
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	48921
ANGLEVOLANTSigValidCount_Cnt_M_u16	914
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	1044
AngleVolantMsgTimer_mS_M_u32	4158305024
AngleVolantValidCount_Cnt_M_u16	45011
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2571576064
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2097652480
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	304206592
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	609719040
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	3212
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	32789248
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	29606
CAVNodeAbsentTimer_mS_M_u32	1985446656
CDD_SrlComVehSpd_Kph_G_f32	492.575592
CMM388NTCEnableTimer_mS_M_u32	2776154880
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3274015488
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	4778
CMMNodeAbsentTimer_mS_M_u32	3490288384
CONSANGLECPKSigInvalidCount_Cnt_M_u16	17712
CONSANGLECPKSigValidCount_Cnt_M_u16	4409
CONSANGLECPK_Cnt_M_u16	62752
CONSANGLECPK_HwDeg_M_f32	9.95049953
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	62752
CPKVehicleSpeedMsgTimer_mS_M_u32	3957699328
CPKVehicleSpeedValidCount_Cnt_M_u16	13955
CityParkInputConsistentCount_Cnt_M_u16	35847

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	478
CityParkInputMsgTimer_mS_M_u32	4064509952
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	52454144
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	65415
ComputerRazGCTSigInvalidTimer_mS_M_u32	1383203584
ComputerRazGCTSigValidCount_Cnt_M_u16	41184
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	45482
DMDFCTCPKSigValidCount_Cnt_M_u16	17323
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	45107
DMDRELAXECPKSigValidCount_Cnt_M_u16	29740
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	241
DateInvalidTimer_mS_M_u32	2097652480
DiagMuxOnAbsentTimer_mS_M_u32	701985536
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	609719040
ESPNTCEnableTimer_mS_M_u32	2158060288
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	64719
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	65535
EffacDefaultDiagTimer_mS_M_u32[1]	95535
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	5
ElecIntTimer_mS_M_u32[1]	155
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2297320192
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	49573
EtatMTSigValidCount_Cnt_M_u16	32506
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1098
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	53203
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	37497
ISDAT4V2BSI552MsgTimer_mS_M_u32	4164784896
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	29305
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	49079
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	32506
ISDATBSI3F2MsgTimer_mS_M_u32	1656582912
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	20141
ISDATBSI412MsgLenValidCount_Cnt_M_u16	6106
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	49573
ISDATBSI412MsgTimer_mS_M_u32	4005606144
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	47582
ISDATBSI432MsgLenValidCount_Cnt_M_u16	25347
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	19451
ISDATDIRASentFltAcc_Cnt_M_u16	33151
ISDATDIRASentTimer_mS_M_u32	3957699328
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	11910
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	45011
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	34461
ISDYN2CMMMsgTimer_mS_M_u32	1121149696
ISDYNAASChkSumInvalidCount_Cnt_M_u16	15055
ISDYNAASChkSumValidCount_Cnt_M_u16	1670
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	17094
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	26829
ISDYNAASMsgLenValidCount_Cnt_M_u16	51902
ISDYNAASMsgTimeValidCount_Cnt_M_u16	15055
ISDYNAASMsgTimer_mS_M_u32	3729048320
ISDYNABRChkSumInvalidCount_Cnt_M_u16	37910
ISDYNABRChkSumValidCount_Cnt_M_u16	46711
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	2528
ISDYNABRMsgCountValidCount_Cnt_M_u16	20025
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	43939
ISDYNABRMsgLenValidCount_Cnt_M_u16	30700
ISDYNABRMsgTimeValidCount_Cnt_M_u16	62752
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	64378

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	29400
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	32506
ISDYNCMM208MsgTimer_mS_M_u32	1868571392
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	64378
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	29400
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	22969
ISDYNCMM388MsgTimer_mS_M_u32	1507738368
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	38422
ISDYNVOLChkSumValidCount_Cnt_M_u16	25247
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	8592
ISDYNVOLMsgCountValidCount_Cnt_M_u16	62481
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	53340
ISDYNVOLMsgLenValidCount_Cnt_M_u16	15558
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	4778
ISDYNVOLMsgTimer_mS_M_u32	658375424
IgnOnTimer_mS_M_u32	420627200
IgnTimeOff_Sec_M_u32	76611435
ManVehSpd_Kph_M_f32	454.575714
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	119
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	104
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3840635648
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	39
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3656700672
PrevISDATBSI412MsgDLCError_Cnt_M_u08	140
PrevISDATBSI412MsgRxTime_MSec_M_u32	1416397568
PrevISDATBSI432MsgDLCError_Cnt_M_u08	151
PrevISDATBSI432MsgRxTime_MSec_M_u32	3020251904
PrevISDATDIRAMsgTxTime_MSec_M_u32	1693483776
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	113
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1288377088
PrevISDYNAASMsgDLCError_Cnt_M_u08	245
PrevISDYNAASMsgRxTime_MSec_M_u32	1218708224
PrevISDYNABRMsgDLCError_Cnt_M_u08	177
PrevISDYNABRMsgRxTime_MSec_M_u32	2041201408
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	165
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1782383360
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	208
PrevISDYNCMM388MsgRxTime_MSec_M_u32	955015936
PrevISDYNVOLMsgDLCError_Cnt_M_u08	188
PrevISDYNVOLMsgRxTime_MSec_M_u32	465404672
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3567694592
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	244.970901
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	38579
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	47396
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	15808
VitesseVehicleBVRampValidCount_Cnt_M_u16	32753
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	62886
VitesseVehicleBVSigValidCount_Cnt_M_u16	63967

Name	Input Value
VitesseVehicleBV_Kph_M_f32	377.055603
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	22969
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	11275
VitesseVehiculeRoues_Kph_M_f32	8.60420036
k_AASNTCEnableTimeout_mS_u16	21611
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	5522
k_AASNodeTimeout_mS_u16	22564
k_ABSNodeTimeout_mS_u16	65155
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	37341
k_ANGLEVOLANTSigValidThresh_Cnt_u16	35906
k_AngleVolantInvalidThresh_Cnt_u16	44573
k_AngleVolantValidThresh_Cnt_u16	478
k_BSI552MsgTimeout_mS_u16	48550
k_BSINTCEnableTimeout_mS_u16	19062
k_BSINodeAbsentDiag_Cnt_str.Threshold	60466
k_BSINodeAbsentDiag_Cnt_str.PStep	30528
k_BSINodeAbsentDiag_Cnt_str.NStep	33250
k_BSINodeAbsentTimeout_mS_u16	11948
k_BSINodeTimeout_mS_u16	19451
k_BattOvHi_Volt_f32	7.44750023
k_BattOvLo_Volt_f32	29.6525993
k_BattUvHi_Volt_f32	30.3950996
k_BattUvLo_Volt_f32	2.89240003
k_CAVNTCEnableTimeout_mS_u16	36956
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	6284
k_CAVNodeTimeout_mS_u16	54780
k_CMM388MsgTimeout_mS_u16	62547
k_CMM388NTCEnableTimeout_mS_u16	18975
k_CMMNTCEnableTimeout_mS_u16	3857
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	53207
k_CONSANGLECPKMax_HwDeg_f32	467.320099
k_CONSANGLECPKMin_HwDeg_f32	-499.240112
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	47289
k_CONSANGLECPKSigValidThresh_Cnt_u16	51979
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	7666
k_CPKVehicleSpeedValidThresh_Cnt_u16	1172
k_CityParkInputInvalidThresh_Cnt_u16	100
k_CityParkInputValidThresh_Cnt_u16	35847
k_ComputerRazGCTSigValidThresh_Cnt_u16	33063
k_CptTemporelSigValidThresh_Cnt_u16	5349
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	35491
k_DMDFCTCPKSigValidThresh_Cnt_u16	38636
k_DMDFCTCPKValidCount_Cnt_u16	4340
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	34461
k_DMDRELAXECPKSigValidThresh_Cnt_u16	63710
k_DMDRelaxeConsistentThresh_Cnt_u16	37036
k_DateValidThresh_Cnt_u16	37497
k_DefaultVehSpd_Kph_f32	147.032501
k_DiagMuxOnAbsentTimeout_mS_u16	54046
k_EMNodeTimeout_mS_u16	64977
k_ESPNTCEnableTimeout_mS_u16	28274
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	26431
k_EtatMTSigInvalidThresh_Cnt_u16	19793
k_EtatMTSigValidThresh_Cnt_u16	30194
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	47929
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	38638
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	36116
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	60122
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	28376
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	62433
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	47551

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	14756
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	41234
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	38708
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	57089
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	11348
k_ISDATDIRASentDiag_Cnt_str.Threshold	58959
k_ISDATDIRASentDiag_Cnt_str.PStep	33467
k_ISDATDIRASentDiag_Cnt_str.NStep	17654
k_ISDATDIRASentTimeout_mS_u16	64226
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	18285
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	1044
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	64526
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	62230
k_ISDYNAASChkSumValidThresh_Cnt_u16	21879
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	59616
k_ISDYNAASMsgCountValidThresh_Cnt_u16	27961
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	52298
k_ISDYNAASMsgLenValidThresh_Cnt_u16	60504
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39338
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	58249
k_ISDYNABRChkSumValidThresh_Cnt_u16	61522
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	60300
k_ISDYNABRMsgCountValidThresh_Cnt_u16	45125
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	45482
k_ISDYNABRMsgLenValidThresh_Cnt_u16	56271
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	34144
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	19175
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	45562
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	64703
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	40473
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	8850
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	118
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	14636
k_ISDYNVOLChkSumValidThresh_Cnt_u16	13209
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	18064
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	28075
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	17777
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	33734
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	21367
k_IgnOnTimeout_mS_u16	9208
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	47.3689003
k_PowerCutVehSpdLowThresh_Kph_f32	30.4705009
k_PowerCutVehSpdLowTimeout_mS_u16	57831
k_VBattMaxAAS_Volt_f32	29.8381996
k_VBattMaxBSI_Volt_f32	23.4106007
k_VBattMaxCAV_Volt_f32	4.6230998
k_VBattMaxCMM388_Volt_f32	18.5263996
k_VBattMaxCMM_Volt_f32	3.90700006
k_VBattMaxESP_Volt_f32	6.46320009
k_VBattMinAAS_Volt_f32	28.2355003
k_VBattMinBSI_Volt_f32	6.46320009
k_VBattMinCAV_Volt_f32	9.13749981
k_VBattMinCMM388_Volt_f32	9.13099957
k_VBattMinCMM_Volt_f32	10.5784998
k_VBattMinESP_Volt_f32	3.90700006
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	34975
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	61180
k_VitesseVehicleBVRampValidThresh_Cnt_u16	32912
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	33183
k_VitesseVehicleBVSigValidThresh_Cnt_u16	21420
k_VitesseVehicleBVSpeedPassThresh_kph_f32	156.406799
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	53926
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	5463
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2097652480
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	9514
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3409510912
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	208
target_SrlComInput_Per1_Batt_Volt_f32.value	11.7530003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1630098176
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	90
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.367092162
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1523860224
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	156
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1104536320
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2397537024
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1778983680
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4214932224
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1786536704
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	25
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3754820352
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	46
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	48
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	68
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	137
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	161
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	188
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2247500544
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	77
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	151
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	222
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1952137984
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1557979904
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	116
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1802404608
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	37
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	85
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	130
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	156
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	174
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3378434816
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3510
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0353714265
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	272003
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	131.337906

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	57189		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3409510912	3409510912	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3409510912	3409510912	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3409510912	3409510912	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3409510912	3409510912	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3409510912	3409510912	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	62752	62752	✔
CONSANGLECPK_HwDeg_M_f32	9.95049953	9.95049953 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3409510912	3409510912	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3409510912	3409510912	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3409510912	3409510912	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3409510912	3409510912	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3409510912	3409510912	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3409510912	3409510912	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3409510912	3409510912	✔
ESPNTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3409510912	3409510912	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	65535	65535	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	95535	95535	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3409510912	3409510912	✔
ElecIntTimer_mS_M_u32[1]	155	155	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3409510912	3409510912	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDATDIRASentFltAcc_Cnt_M_u16	58959	58959	✔
ISDATDIRASentTimer_mS_M_u32	3409510912	3409510912	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3409510912	3409510912	✔
IgnOnTimer_mS_M_u32	3409510912	3409510912	✔
IgnTimeOff_Sec_M_u32	76611435	76611435	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	153	153	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1523860224	1523860224	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	156	156	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1104536320	1104536320	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	113	113	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2397537024	2397537024	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	64	64	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1778983680	1778983680	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1693483776	1693483776	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	108	108	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1786536704	1786536704	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	25	25	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3754820352	3754820352	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	99	99	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2247500544	2247500544	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	153	153	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1952137984	1952137984	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	190	190	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1557979904	1557979904	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	116	116	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1802404608	1802404608	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3378434816	3378434816	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	244.970901	244.970901	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	377.055603	377.055603	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	8.60420036	8.60420036	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	62752	62752	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	76611435	76611435	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	9.95049953	9.95049953 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.248 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3667569152
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	1073
AASNodeAbsentTimer_mS_M_u32	388340224
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	16605
ANGLEVOLANTSigValidCount_Cnt_M_u16	5170
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	31726
AngleVolantMsgTimer_mS_M_u32	3667569152
AngleVolantValidCount_Cnt_M_u16	32559
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1947556352
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1792268800
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	272976384
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3768846848
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	58500
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2865613312
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	40375
CAVNodeAbsentTimer_mS_M_u32	375667200
CDD_SrlComVehSpd_Kph_G_f32	643.628296
CMM388NTCEnableTimer_mS_M_u32	2650831360
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3891935744
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	40554
CMMNodeAbsentTimer_mS_M_u32	630065664
CONSANGLECPKSigInvalidCount_Cnt_M_u16	31129
CONSANGLECPKSigValidCount_Cnt_M_u16	63037
CONSANGLECPK_Cnt_M_u16	42632
CONSANGLECPK_HwDeg_M_f32	-232.628693
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	42632
CPKVehicleSpeedMsgTimer_mS_M_u32	3933841920
CPKVehicleSpeedValidCount_Cnt_M_u16	34537
CityParkInputConsistentCount_Cnt_M_u16	47763

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	33296
CityParkInputMsgTimer_mS_M_u32	1523860224
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	730438144
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	5525
ComputerRazGCTSigInvalidTimer_mS_M_u32	202684928
ComputerRazGCTSigValidCount_Cnt_M_u16	8200
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	41644
DMDFCTCPKSigValidCount_Cnt_M_u16	44392
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	21903
DMDRELAXECPKSigValidCount_Cnt_M_u16	43620
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	35414
DateInvalidTimer_mS_M_u32	1792268800
DiagMuxOnAbsentTimer_mS_M_u32	665086464
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3768846848
ESPNTCEnableTimer_mS_M_u32	4144404992
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	12474
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	579
EffacDefaultDiagTimer_mS_M_u32[1]	989
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1111
ElecIntTimer_mS_M_u32[1]	2222
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2111818240
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	19067
EtatMTSigValidCount_Cnt_M_u16	9020
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	9291
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	41583
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	30974
ISDAT4V2BSI552MsgTimer_mS_M_u32	2096237056
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	9085
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	60549
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	9020
ISDATBSI3F2MsgTimer_mS_M_u32	2498914816
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	27619
ISDATBSI412MsgLenValidCount_Cnt_M_u16	33051
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	19067
ISDATBSI412MsgTimer_mS_M_u32	233351680
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	30926
ISDATBSI432MsgLenValidCount_Cnt_M_u16	52766
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	43192
ISDATDIRASentFltAcc_Cnt_M_u16	6188
ISDATDIRASentTimer_mS_M_u32	3933841920
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	4694
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	32559
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	45011
ISDYN2CMMMsgTimer_mS_M_u32	4168129024
ISDYNAASChkSumInvalidCount_Cnt_M_u16	42211
ISDYNAASChkSumValidCount_Cnt_M_u16	14679
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	21078
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	6722
ISDYNAASMsgLenValidCount_Cnt_M_u16	29999
ISDYNAASMsgTimeValidCount_Cnt_M_u16	42211
ISDYNAASMsgTimer_mS_M_u32	597457408
ISDYNABRChkSumInvalidCount_Cnt_M_u16	19815
ISDYNABRChkSumValidCount_Cnt_M_u16	9987
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	39562
ISDYNABRMsgCountValidCount_Cnt_M_u16	60990
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	53824
ISDYNABRMsgLenValidCount_Cnt_M_u16	20004
ISDYNABRMsgTimeValidCount_Cnt_M_u16	42632
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	14110

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	62660
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	9020
ISDYNCMM208MsgTimer_mS_M_u32	2513066496
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	14110
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	62660
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	39293
ISDYNCMM388MsgTimer_mS_M_u32	4140825088
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	40679
ISDYNVOLChkSumValidCount_Cnt_M_u16	6667
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	27386
ISDYNVOLMsgCountValidCount_Cnt_M_u16	46134
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	10771
ISDYNVOLMsgLenValidCount_Cnt_M_u16	17816
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	40554
ISDYNVOLMsgTimer_mS_M_u32	3182475776
IgnOnTimer_mS_M_u32	2301884928
IgnTimeOff_Sec_M_u32	1371032939
ManVehSpd_Kph_M_f32	149.359695
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	120
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1181248000
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	58
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3301722624
PrevISDATBSI412MsgDLCError_Cnt_M_u08	119
PrevISDATBSI412MsgRxTime_MSec_M_u32	270875136
PrevISDATBSI432MsgDLCError_Cnt_M_u08	1
PrevISDATBSI432MsgRxTime_MSec_M_u32	3973749248
PrevISDATDIRAMsgTxTime_MSec_M_u32	4003019264
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	68
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2504624640
PrevISDYNAASMsgDLCError_Cnt_M_u08	139
PrevISDYNAASMsgRxTime_MSec_M_u32	1904130560
PrevISDYNABRMsgDLCError_Cnt_M_u08	8
PrevISDYNABRMsgRxTime_MSec_M_u32	3345742336
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	75
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2964568576
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	216
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3123026432
PrevISDYNVOLMsgDLCError_Cnt_M_u08	95
PrevISDYNVOLMsgRxTime_MSec_M_u32	1043479040
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1949739520
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	283.996307
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	43152
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	49661
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	10089
VitesseVehicleBVRampValidCount_Cnt_M_u16	57750
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	4406
VitesseVehicleBVSigValidCount_Cnt_M_u16	42315

Name	Input Value
VitesseVehicleBV_Kph_M_f32	551.773621
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	39293
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	9033
VitesseVehiculeRoues_Kph_M_f32	343.165894
k_AASNTCEnableTimeout_mS_u16	29863
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	2546
k_AASNodeTimeout_mS_u16	58621
k_ABSNodeTimeout_mS_u16	24609
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	44241
k_ANGLEVOLANTSigValidThresh_Cnt_u16	3681
k_AngleVolantInvalidThresh_Cnt_u16	54480
k_AngleVolantValidThresh_Cnt_u16	33296
k_BSI552MsgTimeout_mS_u16	39544
k_BSINTCEnableTimeout_mS_u16	9990
k_BSINodeAbsentDiag_Cnt_str.Threshold	40054
k_BSINodeAbsentDiag_Cnt_str.PStep	34700
k_BSINodeAbsentDiag_Cnt_str.NStep	17382
k_BSINodeAbsentTimeout_mS_u16	23590
k_BSINodeTimeout_mS_u16	43192
k_BattOvHi_Volt_f32	28.7457008
k_BattOvLo_Volt_f32	8.5635004
k_BattUvHi_Volt_f32	10.4938002
k_BattUvLo_Volt_f32	1.69060004
k_CAVNTCEnableTimeout_mS_u16	20118
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	50949
k_CAVNodeTimeout_mS_u16	63285
k_CMM388MsgTimeout_mS_u16	26417
k_CMM388NTCEnableTimeout_mS_u16	38349
k_CMMNTCEnableTimeout_mS_u16	44469
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	26597
k_CONSANGLECPKMax_HwDeg_f32	502.236786
k_CONSANGLECPKMin_HwDeg_f32	-399.169495
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	31869
k_CONSANGLECPKSigValidThresh_Cnt_u16	17993
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	19347
k_CPKVehicleSpeedValidThresh_Cnt_u16	42542
k_CityParkInputInvalidThresh_Cnt_u16	49277
k_CityParkInputValidThresh_Cnt_u16	47763
k_ComputerRazGCTSigValidThresh_Cnt_u16	12147
k_CptTemporelSigValidThresh_Cnt_u16	9467
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	13632
k_DMDFCTCPKSigValidThresh_Cnt_u16	61732
k_DMDFCTCPKValidCount_Cnt_u16	30540
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	45011
k_DMDRELAXECPKSigValidThresh_Cnt_u16	6607
k_DMDRelaxeConsistentThresh_Cnt_u16	2661
k_DateValidThresh_Cnt_u16	30974
k_DefaultVehSpd_Kph_f32	71.5695038
k_DiagMuxOnAbsentTimeout_mS_u16	33934
k_EMNodeTimeout_mS_u16	5046
k_ESPNTCEnableTimeout_mS_u16	56659
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	16813
k_EtatMTSigInvalidThresh_Cnt_u16	52662
k_EtatMTSigValidThresh_Cnt_u16	38034
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	20414
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	19806
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	11116
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	32346
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	41762
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	19527
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	15659

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	3643
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	37682
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	4172
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	10661
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	32749
k_ISDATDIRASentDiag_Cnt_str.Threshold	25385
k_ISDATDIRASentDiag_Cnt_str.PStep	45245
k_ISDATDIRASentDiag_Cnt_str.NStep	44580
k_ISDATDIRASentTimeout_mS_u16	18691
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	53922
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	31726
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	42111
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	12391
k_ISDYNAASChkSumValidThresh_Cnt_u16	18947
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	64906
k_ISDYNAASMsgCountValidThresh_Cnt_u16	37182
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	29899
k_ISDYNAASMsgLenValidThresh_Cnt_u16	63585
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	34345
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	17038
k_ISDYNABRChkSumValidThresh_Cnt_u16	64754
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	18308
k_ISDYNABRMsgCountValidThresh_Cnt_u16	39449
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	49514
k_ISDYNABRMsgLenValidThresh_Cnt_u16	37818
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	18120
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	23540
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	46588
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	9004
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	41949
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	46898
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	58952
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	26726
k_ISDYNVOLChkSumValidThresh_Cnt_u16	59870
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	38775
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	53607
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	61207
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	17624
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	44548
k_IgnOnTimeout_mS_u16	55298
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	243.060196
k_PowerCutVehSpdLowThresh_Kph_f32	13.7554998
k_PowerCutVehSpdLowTimeout_mS_u16	48179
k_VBattMaxAAS_Volt_f32	22.2042007
k_VBattMaxBSI_Volt_f32	7.00470018
k_VBattMaxCAV_Volt_f32	10.9343996
k_VBattMaxCMM388_Volt_f32	29.6170006
k_VBattMaxCMM_Volt_f32	6.28289986
k_VBattMaxESP_Volt_f32	2.44930005
k_VBattMinAAS_Volt_f32	27.1089001
k_VBattMinBSI_Volt_f32	2.44930005
k_VBattMinCAV_Volt_f32	24.3005009
k_VBattMinCMM388_Volt_f32	31.0876007
k_VBattMinCMM_Volt_f32	11.1150999
k_VBattMinESP_Volt_f32	6.28289986
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	22284
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	21685
k_VitesseVehicleBVRampValidThresh_Cnt_u16	19962
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	48395
k_VitesseVehicleBVSigValidThresh_Cnt_u16	14244
k_VitesseVehicleBVSpeedPassThresh_kph_f32	281.127686
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	32951
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	14692
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1792268800
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	34046
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2155592960
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	216
target_SrlComInput_Per1_Batt_Volt_f32.value	1.69949996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2704198144
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	67
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.172770068
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	97
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1273887232
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	199
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	627644928
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	213137920
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	120
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2312067584
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	616200704
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1702205952
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	54
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3556817408
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	209
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	1
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	705190400
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	43
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	194
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3680041472
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2958301696
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	199
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1394555392
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	71
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	512641536
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2777
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.382168859
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	804874
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	171.403198

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	5754		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2155592960	2155592960	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2155592960	2155592960	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	40054	40054	✔
BSINodeAbsentTimer_mS_M_u32	2155592960	2155592960	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2155592960	2155592960	✔
CDD_SrlComVehSpd_Kph_G_f32	149.359695	149.359695	✔
CMM388NTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2155592960	2155592960	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	42632	42632	✔
CONSANGLECPK_HwDeg_M_f32	-232.628693	-232.628693 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2155592960	2155592960	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2155592960	2155592960	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2155592960	2155592960	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2155592960	2155592960	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2155592960	2155592960	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2155592960	2155592960	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2155592960	2155592960	✔
ESPNTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2155592960	2155592960	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	579	579	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	989	989	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1111	1111	✔
ElecIntTimer_mS_M_u32[1]	2222	2222	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2155592960	2155592960	✔
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	30974	30974	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	9020	9020	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	19067	19067	✔
ISDATBSI412MsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	43192	43192	✔
ISDATBSI432MsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2155592960	2155592960	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	45011	45011	✔
ISDYN2CMMMsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	42211	42211	✔
ISDYNAASMsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	42632	42632	✔
ISDYNABRMsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	9020	9020	✔
ISDYNCMM208MsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	39293	39293	✔
ISDYNCMM388MsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	40554	40554	✔
ISDYNVOLMsgTimer_mS_M_u32	2155592960	2155592960	✔
IgnOnTimer_mS_M_u32	2301884928	2301884928	✔
IgnTimeOff_Sec_M_u32	1371032939	1371032939	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	97	97	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1273887232	1273887232	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	199	199	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	627644928	627644928	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	246	246	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	213137920	213137920	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	120	120	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2312067584	2312067584	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4003019264	4003019264	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	143	143	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1702205952	1702205952	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	54	54	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3556817408	3556817408	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	1	1	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	705190400	705190400	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	59	59	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3680041472	3680041472	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	60	60	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2958301696	2958301696	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	199	199	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1394555392	1394555392	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	512641536	512641536	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	283.996307	283.996307	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	551.773621	551.773621	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	343.165894	343.165894	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	42632	42632	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1371032939	1371032939	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-232.628693	-232.628693 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.249 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1257686272
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	18483
AASNodeAbsentTimer_mS_M_u32	2903897344
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	58413
ANGLEVOLANTSigValidCount_Cnt_M_u16	34800
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	5372
AngleVolantMsgTimer_mS_M_u32	1257686272
AngleVolantValidCount_Cnt_M_u16	63416
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	88519936
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	990590208
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	477553920
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2522522880
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	21816
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	249390336
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	24095
CAVNodeAbsentTimer_mS_M_u32	1910117632
CDD_SrlComVehSpd_Kph_G_f32	322.787811
CMM388NTCEnableTimer_mS_M_u32	2617595136
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3575125248
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	49863
CMMNodeAbsentTimer_mS_M_u32	4020020480
CONSANGLECPKSigInvalidCount_Cnt_M_u16	55546
CONSANGLECPKSigValidCount_Cnt_M_u16	49357
CONSANGLECPK_Cnt_M_u16	39916
CONSANGLECPK_HwDeg_M_f32	-43.8667984
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	39916
CPKVehicleSpeedMsgTimer_mS_M_u32	1465500928
CPKVehicleSpeedValidCount_Cnt_M_u16	11570
CityParkInputConsistentCount_Cnt_M_u16	54668
CityParkInputInvalidCount_Cnt_M_u16	1045
CityParkInputMsgTimer_mS_M_u32	1273887232
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4293522688
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	41991

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	4073231616
ComputerRazGCTSigValidCount_Cnt_M_u16	47405
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	4673
DMDFCTCPKSigValidCount_Cnt_M_u16	45003
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	60951
DMDRELAXECPKSigValidCount_Cnt_M_u16	3418
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	56003
DateInvalidTimer_mS_M_u32	990590208
DiagMuxOnAbsentTimer_mS_M_u32	3134817536
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2522522880
ESPNTCEnableTimer_mS_M_u32	3513971968
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	6550
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1000
EffacDefaultDiagTimer_mS_M_u32[1]	2000
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65535
ElecIntTimer_mS_M_u32[1]	95535
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1571251456
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	37779
EtatMTSigValidCount_Cnt_M_u16	55058
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	8420
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1079
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	9481
ISDAT4V2BSI552MsgTimer_mS_M_u32	2037425408
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	17935
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	55478
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	55058
ISDATBSI3F2MsgTimer_mS_M_u32	720340224
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	54748
ISDATBSI412MsgLenValidCount_Cnt_M_u16	17395
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	37779
ISDATBSI412MsgTimer_mS_M_u32	1762444544
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	50075
ISDATBSI432MsgLenValidCount_Cnt_M_u16	53610
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	33052
ISDATDIRASentFltAcc_Cnt_M_u16	704
ISDATDIRASentTimer_mS_M_u32	1465500928
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	4226
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	63416
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	18124
ISDYN2CMMMsgTimer_mS_M_u32	4113888512
ISDYNAASChkSumInvalidCount_Cnt_M_u16	44573
ISDYNAASChkSumValidCount_Cnt_M_u16	36479
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	55875
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	54398
ISDYNAASMsgLenValidCount_Cnt_M_u16	16761
ISDYNAASMsgTimeValidCount_Cnt_M_u16	44573
ISDYNAASMsgTimer_mS_M_u32	2066830592
ISDYNABRChkSumInvalidCount_Cnt_M_u16	7185
ISDYNABRChkSumValidCount_Cnt_M_u16	52476
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	10536
ISDYNABRMsgCountValidCount_Cnt_M_u16	52170
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	11013
ISDYNABRMsgLenValidCount_Cnt_M_u16	5400
ISDYNABRMsgTimeValidCount_Cnt_M_u16	39916
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	36671
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	60172
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	55058
ISDYNCMM208MsgTimer_mS_M_u32	3022501120
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	36671
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	60172
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	24782

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	798414080
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	8464
ISDYNVOLChkSumValidCount_Cnt_M_u16	3427
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	29015
ISDYNVOLMsgCountValidCount_Cnt_M_u16	21345
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	53643
ISDYNVOLMsgLenValidCount_Cnt_M_u16	23741
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	49863
ISDYNVOLMsgTimer_mS_M_u32	1307874560
IgnOnTimer_mS_M_u32	141219072
IgnTimeOff_Sec_M_u32	1053744358
ManVehSpd_Kph_M_f32	348.698303
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	121
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	105
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1854768384
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	96
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3672237312
PrevISDATBSI412MsgDLCError_Cnt_M_u08	102
PrevISDATBSI412MsgRxTime_MSec_M_u32	3365344512
PrevISDATBSI432MsgDLCError_Cnt_M_u08	198
PrevISDATBSI432MsgRxTime_MSec_M_u32	1073149184
PrevISDATDIRAMsgTxTime_MSec_M_u32	4248507648
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	135
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3999933696
PrevISDYNAASMsgDLCError_Cnt_M_u08	56
PrevISDYNAASMsgRxTime_MSec_M_u32	3934950656
PrevISDYNABRMsgDLCError_Cnt_M_u08	178
PrevISDYNABRMsgRxTime_MSec_M_u32	767743232
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	136
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1089180928
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	186
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3289773312
PrevISDYNVOLMsgDLCError_Cnt_M_u08	65
PrevISDYNVOLMsgRxTime_MSec_M_u32	2993689856
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3995256064
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	114.641998
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57748
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	4879
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	2313
VitesseVehicleBVRampValidCount_Cnt_M_u16	22596
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	5922
VitesseVehicleBVSigValidCount_Cnt_M_u16	30885
VitesseVehicleBV_Kph_M_f32	600.915588
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	24782
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	49449
VitesseVehiculeRoues_Kph_M_f32	574.244507
k_AASNTCEnableTimeout_mS_u16	28047
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	9071
k_AASNodeTimeout_mS_u16	43535
k_ABSNodeTimeout_mS_u16	60898
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	62354
k_ANGLEVOLANTSigValidThresh_Cnt_u16	56481
k_AngleVolantInvalidThresh_Cnt_u16	1364
k_AngleVolantValidThresh_Cnt_u16	1045
k_BSI552MsgTimeout_mS_u16	55196
k_BSINTCEnableTimeout_mS_u16	39155
k_BSINodeAbsentDiag_Cnt_str.Threshold	47285
k_BSINodeAbsentDiag_Cnt_str.PStep	21172
k_BSINodeAbsentDiag_Cnt_str.NStep	35047
k_BSINodeAbsentTimeout_mS_u16	21588
k_BSINodeTimeout_mS_u16	33052
k_BattOvHi_Volt_f32	24.7233009
k_BattOvLo_Volt_f32	10.9707003
k_BattUvHi_Volt_f32	25.2066002
k_BattUvLo_Volt_f32	0.549300015
k_CAVNTCEnableTimeout_mS_u16	13955
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	39477
k_CAVNodeTimeout_mS_u16	53286
k_CMM388MsgTimeout_mS_u16	7987
k_CMM388NTCEnableTimeout_mS_u16	863
k_CMMNTCEnableTimeout_mS_u16	34663
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	25429
k_CONSANGLECPKMax_HwDeg_f32	692.220703
k_CONSANGLECPKMin_HwDeg_f32	-23.2994995
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	47054
k_CONSANGLECPKSigValidThresh_Cnt_u16	22569
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	20045
k_CPKVehicleSpeedValidThresh_Cnt_u16	4859
k_CityParkInputInvalidThresh_Cnt_u16	39631
k_CityParkInputValidThresh_Cnt_u16	54668
k_ComputerRazGCTSigValidThresh_Cnt_u16	31277
k_CptTemporelSigValidThresh_Cnt_u16	34644
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	517
k_DMDFCTCPKSigValidThresh_Cnt_u16	11288
k_DMDFCTCPKValidCount_Cnt_u16	48352
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	18124
k_DMDRELAXECPKSigValidThresh_Cnt_u16	50838
k_DMDRelaxeConsistentThresh_Cnt_u16	52436
k_DateValidThresh_Cnt_u16	9481
k_DefaultVehSpd_Kph_f32	72.5679016
k_DiagMuxOnAbsentTimeout_mS_u16	39386
k_EMNodeTimeout_mS_u16	48803
k_ESPNTCEnableTimeout_mS_u16	3915
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	62973
k_EtatMTSigInvalidThresh_Cnt_u16	38692
k_EtatMTSigValidThresh_Cnt_u16	32847
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	44492
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	682
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	9985
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	59768
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	26847
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	50352
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	10884
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	50451
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	1135
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	28320
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	20566
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	37565
k_ISDATDIRASentDiag_Cnt_str.Threshold	25991

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	29762
k_ISDATDIRASentDiag_Cnt_str.NStep	4038
k_ISDATDIRASentTimeout_mS_u16	39229
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	44702
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	5372
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	27079
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	29457
k_ISDYNAASChkSumValidThresh_Cnt_u16	25596
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	40
k_ISDYNAASMsgCountValidThresh_Cnt_u16	58058
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	13797
k_ISDYNAASMsgLenValidThresh_Cnt_u16	65507
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	38217
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	37403
k_ISDYNABRChkSumValidThresh_Cnt_u16	49326
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	11320
k_ISDYNABRMsgCountValidThresh_Cnt_u16	21051
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	22983
k_ISDYNABRMsgLenValidThresh_Cnt_u16	61590
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	51246
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	22376
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	39825
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	27522
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	47917
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	40688
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	46957
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	44115
k_ISDYNVOLChkSumValidThresh_Cnt_u16	54698
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	6495
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	24016
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	5567
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	57918
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	7671
k_IgnOnTimeout_mS_u16	52607
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	196.595795
k_PowerCutVehSpdLowThresh_Kph_f32	188.509796
k_PowerCutVehSpdLowTimeout_mS_u16	50923
k_VBattMaxAAS_Volt_f32	31.5205002
k_VBattMaxBSI_Volt_f32	15.5663996
k_VBattMaxCAV_Volt_f32	29.0753002
k_VBattMaxCMM388_Volt_f32	22.8495998
k_VBattMaxCMM_Volt_f32	30.4290009
k_VBattMaxESP_Volt_f32	30.4249001
k_VBattMinAAS_Volt_f32	16.5163994
k_VBattMinBSI_Volt_f32	30.4249001
k_VBattMinCAV_Volt_f32	7.24919987
k_VBattMinCMM388_Volt_f32	32
k_VBattMinCMM_Volt_f32	7.39239979
k_VBattMinESP_Volt_f32	30.4290009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	18784
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	48679
k_VitesseVehicleBVRampValidThresh_Cnt_u16	51287
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	9315
k_VitesseVehicleBVSigValidThresh_Cnt_u16	57945
k_VitesseVehicleBVSpeedPassThresh_kph_f32	272.591003
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	46367
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	2266
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	990590208
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	1230
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3915353088
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	186
target_SrlComInput_Per1_Batt_Volt_f32.value	16.1861
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4021970176
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	90
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.421494544
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	116
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	675075328
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	247
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4031476992
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3471447296
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	739816704
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1876382976
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	36041984
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1258591488
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	37
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	63
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	86
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	93
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	164
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1869460736
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	139
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	140
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	188
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	196
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3858486528
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	4
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3146413312
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1739134208
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	74
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	122
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	133
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1436280064
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2868
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.218556821
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	863500
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	126.816704
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	49110

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3915353088	3915353088	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	5372	5372	✔
AngleVolantMsgTimer_mS_M_u32	3915353088	3915353088	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	47285	47285	✔
BSINodeAbsentTimer_mS_M_u32	3915353088	3915353088	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3915353088	3915353088	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3915353088	3915353088	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	39916	39916	✔
CONSANGLECPK_HwDeg_M_f32	-43.8667984	-43.8667984 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	39916	39916	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1465500928	1465500928	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	11570	11570	✔
CityParkInputConsistentCount_Cnt_M_u16	54668	54668	✔
CityParkInputInvalidCount_Cnt_M_u16	1047	1047	✔
CityParkInputMsgTimer_mS_M_u32	3915353088	3915353088	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3915353088	3915353088	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3915353088	3915353088	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3915353088	3915353088	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3915353088	3915353088	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3915353088	3915353088	✔
ESPNTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3915353088	3915353088	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1000	1000	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2000	2000	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3915353088	3915353088	✔
ElecIntTimer_mS_M_u32[1]	95535	95535	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3915353088	3915353088	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3915353088	3915353088	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3915353088	3915353088	✔
IgnOnTimer_mS_M_u32	141219072	141219072	✔
IgnTimeOff_Sec_M_u32	1053744358	1053744358	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	116	116	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	675075328	675075328	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	247	247	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4031476992	4031476992	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3471447296	3471447296	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	15	15	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	739816704	739816704	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4248507648	4248507648	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	240	240	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	36041984	36041984	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	241	241	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1258591488	1258591488	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	152	152	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1869460736	1869460736	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	83	83	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3858486528	3858486528	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	4	4	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3146413312	3146413312	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	88	88	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1739134208	1739134208	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1436280064	1436280064	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	114.641998	114.641998	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	600.915588	600.915588	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	574.244507	574.244507	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	39916	39916	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1053744358	1053744358	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-43.8667984	-43.8667984 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	72.5679016	72.5679016	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.250 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	537818112
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	47704
AASNodeAbsentTimer_mS_M_u32	2993742848
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	61545
ANGLEVOLANTSigValidCount_Cnt_M_u16	44001
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	47101
AngleVolantMsgTimer_mS_M_u32	537818112
AngleVolantValidCount_Cnt_M_u16	19016
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1558094848
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1838228480
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1410208768
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	627233792
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	35144
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	920294400
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	53524
CAVNodeAbsentTimer_mS_M_u32	480543744
CDD_SrlComVehSpd_Kph_G_f32	519.165283
CMM388NTCEnableTimer_mS_M_u32	1529005056
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1793754112
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	28380
CMMNodeAbsentTimer_mS_M_u32	2711409664
CONSANGLECPKSigInvalidCount_Cnt_M_u16	13571
CONSANGLECPKSigValidCount_Cnt_M_u16	25675
CONSANGLECPK_Cnt_M_u16	3822
CONSANGLECPK_HwDeg_M_f32	128.711899
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	3822
CPKVehicleSpeedMsgTimer_mS_M_u32	1189442560
CPKVehicleSpeedValidCount_Cnt_M_u16	25570
CityParkInputConsistentCount_Cnt_M_u16	204
CityParkInputInvalidCount_Cnt_M_u16	58931
CityParkInputMsgTimer_mS_M_u32	675075328
CityParkInputValidCount_Cnt_M_u16	7

Name	Input Value
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	167044096
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	63196
ComputerRazGCTSigInvalidTimer_mS_M_u32	1943602176
ComputerRazGCTSigValidCount_Cnt_M_u16	6633
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	27567
DMDFCTCPKSigValidCount_Cnt_M_u16	22991
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	64171
DMDRELAXECPKSigValidCount_Cnt_M_u16	17315
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	37800
DateInvalidTimer_mS_M_u32	1838228480
DiagMuxOnAbsentTimer_mS_M_u32	3412472832
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	627233792
ESPNTCEnableTimer_mS_M_u32	4183417856
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	16688
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	2500
EffacDefaultDiagTimer_mS_M_u32[1]	3500
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	579
ElecIntTimer_mS_M_u32[1]	989
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4068250624
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	32120
EtatMTSigValidCount_Cnt_M_u16	18875
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	34117
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	49677
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	29205
ISDAT4V2BSI552MsgTimer_mS_M_u32	1411437568
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	44420
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	11344
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	18875
ISDATBSI3F2MsgTimer_mS_M_u32	1394881536
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	49948
ISDATBSI412MsgLenValidCount_Cnt_M_u16	28568
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	32120
ISDATBSI412MsgTimer_mS_M_u32	2647421952
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	48224
ISDATBSI432MsgLenValidCount_Cnt_M_u16	27060
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	39965
ISDATDIRASentFltAcc_Cnt_M_u16	42801
ISDATDIRASentTimer_mS_M_u32	1189442560
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	35116
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	19016
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	47630
ISDYN2CMMMsgTimer_mS_M_u32	370402304
ISDYNAASChkSumInvalidCount_Cnt_M_u16	45210
ISDYNAASChkSumValidCount_Cnt_M_u16	13874
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	36519
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	43511
ISDYNAASMsgLenValidCount_Cnt_M_u16	59847
ISDYNAASMsgTimeValidCount_Cnt_M_u16	45210
ISDYNAASMsgTimer_mS_M_u32	1839121408
ISDYNABRChkSumInvalidCount_Cnt_M_u16	12349
ISDYNABRChkSumValidCount_Cnt_M_u16	25661
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	11129
ISDYNABRMsgCountValidCount_Cnt_M_u16	27217
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	10978
ISDYNABRMsgLenValidCount_Cnt_M_u16	21354
ISDYNABRMsgTimeValidCount_Cnt_M_u16	3822
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	38329
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	50193
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	18875
ISDYNCMM208MsgTimer_mS_M_u32	339452928

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	38329
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	50193
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	59142
ISDYNCMM388MsgTimer_mS_M_u32	3329115136
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	13505
ISDYNVOLChkSumValidCount_Cnt_M_u16	22153
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	9837
ISDYNVOLMsgCountValidCount_Cnt_M_u16	18189
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	11601
ISDYNVOLMsgLenValidCount_Cnt_M_u16	62073
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28380
ISDYNVOLMsgTimer_mS_M_u32	307561472
IgnOnTimer_mS_M_u32	2347910144
IgnTimeOff_Sec_M_u32	2256587309
ManVehSpd_Kph_M_f32	217.739594
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	122
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2152346624
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	62
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2228032512
PrevISDATBSI412MsgDLCError_Cnt_M_u08	245
PrevISDATBSI412MsgRxTime_MSec_M_u32	1282245632
PrevISDATBSI432MsgDLCError_Cnt_M_u08	220
PrevISDATBSI432MsgRxTime_MSec_M_u32	3184387072
PrevISDATDIRAMsgTxTime_MSec_M_u32	1048675328
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	252
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3140768768
PrevISDYNAASMsgDLCError_Cnt_M_u08	85
PrevISDYNAASMsgRxTime_MSec_M_u32	345179136
PrevISDYNABRMsgDLCError_Cnt_M_u08	22
PrevISDYNABRMsgRxTime_MSec_M_u32	2078950400
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	179
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3580888064
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	151
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1836114944
PrevISDYNVOLMsgDLCError_Cnt_M_u08	177
PrevISDYNVOLMsgRxTime_MSec_M_u32	853705728
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3867833344
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	410.3479
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	23221
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	19717
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	63574
VitesseVehicleBVRampValidCount_Cnt_M_u16	37222
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	27530
VitesseVehicleBVSigValidCount_Cnt_M_u16	60866
VitesseVehicleBV_Kph_M_f32	333.430511
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	59142
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	52406

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	401.906494
k_AASNTCEnableTimeout_mS_u16	58885
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	25379
k_AASNodeTimeout_mS_u16	34821
k_ABSNodeTimeout_mS_u16	40140
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	51323
k_ANGLEVOLANTSigValidThresh_Cnt_u16	58383
k_AngleVolantInvalidThresh_Cnt_u16	62966
k_AngleVolantValidThresh_Cnt_u16	58931
k_BSI552MsgTimeout_mS_u16	5469
k_BSINTCEnableTimeout_mS_u16	40024
k_BSINodeAbsentDiag_Cnt_str.Threshold	3284
k_BSINodeAbsentDiag_Cnt_str.PStep	11545
k_BSINodeAbsentDiag_Cnt_str.NStep	18625
k_BSINodeAbsentTimeout_mS_u16	23029
k_BSINodeTimeout_mS_u16	39965
k_BattOvHi_Volt_f32	1.39240003
k_BattOvLo_Volt_f32	5.54820013
k_BattUvHi_Volt_f32	0.259799987
k_BattUvLo_Volt_f32	31.5
k_CAVNTCEnableTimeout_mS_u16	34537
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	62674
k_CAVNodeTimeout_mS_u16	65407
k_CMM388MsgTimeout_mS_u16	13656
k_CMM388NTCEnableTimeout_mS_u16	14548
k_CMMNTCEnableTimeout_mS_u16	18812
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	38450
k_CONSANGLECPKMax_HwDeg_f32	360.754303
k_CONSANGLECPKMin_HwDeg_f32	-494.467194
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	57862
k_CONSANGLECPKSigValidThresh_Cnt_u16	1974
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	4939
k_CPKVehicleSpeedValidThresh_Cnt_u16	18367
k_CityParkInputInvalidThresh_Cnt_u16	11267
k_CityParkInputValidThresh_Cnt_u16	204
k_ComputerRazGCTSigValidThresh_Cnt_u16	2346
k_CptTemporelSigValidThresh_Cnt_u16	6262
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	42466
k_DMDFCTCPKSigValidThresh_Cnt_u16	3690
k_DMDFCTCPKValidCount_Cnt_u16	62032
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	47630
k_DMDRELAXECPKSigValidThresh_Cnt_u16	366
k_DMDRelaxeConsistentThresh_Cnt_u16	26292
k_DateValidThresh_Cnt_u16	29205
k_DefaultVehSpd_Kph_f32	89.7444
k_DiagMuxOnAbsentTimeout_mS_u16	19748
k_EMNodeTimeout_mS_u16	26632
k_ESPNTCEnableTimeout_mS_u16	28048
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	32314
k_EtatMTSigInvalidThresh_Cnt_u16	51972
k_EtatMTSigValidThresh_Cnt_u16	22084
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	45262
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	51442
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	8301
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	42825
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	24533
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	18080
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	27557
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	29369
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	18916
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	26322

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	14446
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	41336
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	26809
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	4565
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	47101
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	19996
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	11069
k_ISDYNAASChkSumValidThresh_Cnt_u16	40765
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	42617
k_ISDYNAASMsgCountValidThresh_Cnt_u16	9553
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	12993
k_ISDYNAASMsgLenValidThresh_Cnt_u16	54921
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	23063
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	52640
k_ISDYNABRChkSumValidThresh_Cnt_u16	10408
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	1096
k_ISDYNABRMsgCountValidThresh_Cnt_u16	14592
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	43484
k_ISDYNABRMsgLenValidThresh_Cnt_u16	48176
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	25383
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	18745
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	34301
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	53164
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	27497
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	26337
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	11307
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	56247
k_ISDYNVOLChkSumValidThresh_Cnt_u16	22131
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	42453
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	449
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	42740
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	55351
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	48971
k_IgnOnTimeout_mS_u16	10291
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	106.160896
k_PowerCutVehSpdLowThresh_Kph_f32	170.418793
k_PowerCutVehSpdLowTimeout_mS_u16	18929
k_VBattMaxAAS_Volt_f32	25.7656994
k_VBattMaxBSI_Volt_f32	27.2861996
k_VBattMaxCAV_Volt_f32	9.86600018
k_VBattMaxCMM388_Volt_f32	11.0762997
k_VBattMaxCMM_Volt_f32	10.6066999
k_VBattMaxESP_Volt_f32	12.1336002
k_VBattMinAAS_Volt_f32	5.64820004
k_VBattMinBSI_Volt_f32	12.1336002
k_VBattMinCAV_Volt_f32	20.5268993
k_VBattMinCMM388_Volt_f32	5.42659998
k_VBattMinCMM_Volt_f32	6.33669996
k_VBattMinESP_Volt_f32	10.6066999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	51599
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	8699
k_VitesseVehicleBVRampValidThresh_Cnt_u16	8557
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	4489
k_VitesseVehicleBVSigValidThresh_Cnt_u16	20069
k_VitesseVehicleBVSpeedPassThresh_kph_f32	144.811996
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	52244
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	22436
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1838228480
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	55161
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3299876608
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	151
target_SrlComInput_Per1_Batt_Volt_f32.value	1.74769998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1212388352
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	17
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.330356985
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	103
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4101784576
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2664457216
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1165263872
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2959647744
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2813117440
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4081116160
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	255
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1529152512
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	102
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	153
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	223
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2053743616
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	69
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	93
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	164
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	173
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	205
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2000634880
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	85
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4178797568
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	124
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	926385152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	107
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	122
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	202
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2090800128
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	626
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.882540584
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	866134
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	145.748093
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	18415

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3299876608	3299876608	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3299876608	3299876608	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	47103	47103	✔
AngleVolantMsgTimer_mS_M_u32	3299876608	3299876608	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	3284	3284	✔
BSINodeAbsentTimer_mS_M_u32	3299876608	3299876608	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3299876608	3299876608	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3299876608	3299876608	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	3822	3822	✔
CONSANGLECPK_HwDeg_M_f32	128.711899	128.711899 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	3822	3822	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1189442560	1189442560	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	25570	25570	✔
CityParkInputConsistentCount_Cnt_M_u16	204	204	✔
CityParkInputInvalidCount_Cnt_M_u16	58931	58931	✔
CityParkInputMsgTimer_mS_M_u32	3299876608	3299876608	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3299876608	3299876608	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3299876608	3299876608	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3299876608	3299876608	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3299876608	3299876608	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3299876608	3299876608	✔
ESPNTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3299876608	3299876608	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2500	2500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3500	3500	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3299876608	3299876608	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	989	989	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3299876608	3299876608	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3299876608	3299876608	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3299876608	3299876608	✔
IgnOnTimer_mS_M_u32	3299876608	3299876608	✔
IgnTimeOff_Sec_M_u32	2256587309	2256587309	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	103	103	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4101784576	4101784576	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	190	190	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2664457216	2664457216	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	174	174	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1165263872	1165263872	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	253	253	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2959647744	2959647744	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1048675328	1048675328	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	222	222	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4081116160	4081116160	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	255	255	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1529152512	1529152512	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	246	246	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2053743616	2053743616	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	134	134	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2000634880	2000634880	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	85	85	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4178797568	4178797568	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	124	124	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	926385152	926385152	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2090800128	2090800128	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	410.3479	410.3479	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	333.430511	333.430511	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	401.906494	401.906494	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	3822	3822	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2256587309	2256587309	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	128.711899	128.711899 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	89.7444	89.7444	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.251 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3728959232
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	22883
AASNodeAbsentTimer_mS_M_u32	4242282240
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	39218
ANGLEVOLANTSigValidCount_Cnt_M_u16	29322
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	13428
AngleVolantMsgTimer_mS_M_u32	3728959232
AngleVolantValidCount_Cnt_M_u16	52758
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3834828544
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2625328896
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1220839168
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	398870272
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	2709
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1918830336
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	2993
CAVNodeAbsentTimer_mS_M_u32	2495690496
CDD_SrlComVehSpd_Kph_G_f32	54.3382988
CMM388NTCEnableTimer_mS_M_u32	2722526976
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1106196224
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	53016
CMMNodeAbsentTimer_mS_M_u32	186140416
CONSANGLECPKSigInvalidCount_Cnt_M_u16	25189
CONSANGLECPKSigValidCount_Cnt_M_u16	8269
CONSANGLECPK_Cnt_M_u16	27748
CONSANGLECPK_HwDeg_M_f32	28.5697994
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	27748
CPKVehicleSpeedMsgTimer_mS_M_u32	2243847936
CPKVehicleSpeedValidCount_Cnt_M_u16	29487

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	47754
CityParkInputInvalidCount_Cnt_M_u16	46932
CityParkInputMsgTimer_mS_M_u32	4101784576
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	105912064
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	46039
ComputerRazGCTSigInvalidTimer_mS_M_u32	19117824
ComputerRazGCTSigValidCount_Cnt_M_u16	9011
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	5856
DMDFCTCPKSigValidCount_Cnt_M_u16	63552
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	620
DMDRELAXECPKSigValidCount_Cnt_M_u16	13124
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	6774
DateInvalidTimer_mS_M_u32	2625328896
DiagMuxOnAbsentTimer_mS_M_u32	3946587904
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	398870272
ESPNTCEnableTimer_mS_M_u32	203495168
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	54236
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	979
EffacDefaultDiagTimer_mS_M_u32[1]	1085
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1000
ElecIntTimer_mS_M_u32[1]	2000
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1199113984
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	8262
EtatMTSigValidCount_Cnt_M_u16	63290
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	63903
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	36615
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	18286
ISDAT4V2BSI552MsgTimer_mS_M_u32	59524864
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	47521
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	39165
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	63290
ISDATBSI3F2MsgTimer_mS_M_u32	3422693120
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	10712
ISDATBSI412MsgLenValidCount_Cnt_M_u16	16421
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	8262
ISDATBSI412MsgTimer_mS_M_u32	3708380928
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	63116
ISDATBSI432MsgLenValidCount_Cnt_M_u16	27216
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	3734
ISDATDIRASentFltAcc_Cnt_M_u16	15706
ISDATDIRASentTimer_mS_M_u32	2243847936
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	30122
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	52758
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	26563
ISDYN2CMMMsgTimer_mS_M_u32	502470400
ISDYNAASChkSumInvalidCount_Cnt_M_u16	65181
ISDYNAASChkSumValidCount_Cnt_M_u16	63894
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	52488
ISDYNAASMsgLenValidCount_Cnt_M_u16	31064
ISDYNAASMsgTimeValidCount_Cnt_M_u16	65181
ISDYNAASMsgTimer_mS_M_u32	1523742464
ISDYNABRChkSumInvalidCount_Cnt_M_u16	9013
ISDYNABRChkSumValidCount_Cnt_M_u16	45813
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	51712
ISDYNABRMsgCountValidCount_Cnt_M_u16	39225
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	48328
ISDYNABRMsgLenValidCount_Cnt_M_u16	36592
ISDYNABRMsgTimeValidCount_Cnt_M_u16	27748

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	50614
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	30063
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	63290
ISDYNCMM208MsgTimer_mS_M_u32	1920718592
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	50614
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	30063
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	28636
ISDYNCMM388MsgTimer_mS_M_u32	3999528704
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	56107
ISDYNVOLChkSumValidCount_Cnt_M_u16	49555
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	24230
ISDYNVOLMsgCountValidCount_Cnt_M_u16	43142
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	54137
ISDYNVOLMsgLenValidCount_Cnt_M_u16	20417
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	53016
ISDYNVOLMsgTimer_mS_M_u32	363837184
IgnOnTimer_mS_M_u32	2916611840
IgnTimeOff_Sec_M_u32	84907832
ManVehSpd_Kph_M_f32	317.017395
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	123
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	136
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1552951040
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	98
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1921484544
PrevISDATBSI412MsgDLCError_Cnt_M_u08	229
PrevISDATBSI412MsgRxTime_MSec_M_u32	1768306432
PrevISDATBSI432MsgDLCError_Cnt_M_u08	28
PrevISDATBSI432MsgRxTime_MSec_M_u32	2395281152
PrevISDATDIRAMsgTxTime_MSec_M_u32	3811194624
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	150
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2085734144
PrevISDYNAASMsgDLCError_Cnt_M_u08	65
PrevISDYNAASMsgRxTime_MSec_M_u32	2264250112
PrevISDYNABRMsgDLCError_Cnt_M_u08	117
PrevISDYNABRMsgRxTime_MSec_M_u32	3186620160
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	64
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4166956800
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	38
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3420198656
PrevISDYNVOLMsgDLCError_Cnt_M_u08	206
PrevISDYNVOLMsgRxTime_MSec_M_u32	3389470464
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2060412672
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	611.535217
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	13006
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	51102
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	7659
VitesseVehicleBVRampValidCount_Cnt_M_u16	48763
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	60367

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	28903
VitesseVehicleBV_Kph_M_f32	634.617188
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	28636
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	43660
VitesseVehiculeRoues_Kph_M_f32	463.800903
k_AASNTCEnableTimeout_mS_u16	799
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	44933
k_AASNodeTimeout_mS_u16	5790
k_ABSNodeTimeout_mS_u16	14217
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	65083
k_ANGLEVOLANTSigValidThresh_Cnt_u16	10047
k_AngleVolantInvalidThresh_Cnt_u16	19850
k_AngleVolantValidThresh_Cnt_u16	46932
k_BSI552MsgTimeout_mS_u16	11415
k_BSINTCEnableTimeout_mS_u16	13988
k_BSINodeAbsentDiag_Cnt_str.Threshold	34276
k_BSINodeAbsentDiag_Cnt_str.PStep	23127
k_BSINodeAbsentDiag_Cnt_str.NStep	52382
k_BSINodeAbsentTimeout_mS_u16	11916
k_BSINodeTimeout_mS_u16	3734
k_BattOvHi_Volt_f32	4.92309999
k_BattOvLo_Volt_f32	6.26179981
k_BattUvHi_Volt_f32	7.36880016
k_BattUvLo_Volt_f32	3.7486999
k_CAVNTCEnableTimeout_mS_u16	11570
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	6263
k_CAVNodeTimeout_mS_u16	62193
k_CMM388MsgTimeout_mS_u16	59491
k_CMM388NTCEnableTimeout_mS_u16	52719
k_CMMNTCEnableTimeout_mS_u16	50617
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	15896
k_CONSANGLECPKMax_HwDeg_f32	395.635101
k_CONSANGLECPKMin_HwDeg_f32	-513.353516
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	32476
k_CONSANGLECPKSigValidThresh_Cnt_u16	63884
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	3276
k_CPKVehicleSpeedValidThresh_Cnt_u16	59375
k_CityParkInputInvalidThresh_Cnt_u16	51171
k_CityParkInputValidThresh_Cnt_u16	47754
k_ComputerRazGCTSigValidThresh_Cnt_u16	48815
k_CptTemporelSigValidThresh_Cnt_u16	60555
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	19400
k_DMDFCTCPKSigValidThresh_Cnt_u16	24048
k_DMDFCTCPKValidCount_Cnt_u16	61309
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	26563
k_DMDRELAXECPKSigValidThresh_Cnt_u16	15715
k_DMDRelaxeConsistentThresh_Cnt_u16	42385
k_DateValidThresh_Cnt_u16	18286
k_DefaultVehSpd_Kph_f32	153.699295
k_DiagMuxOnAbsentTimeout_mS_u16	2498
k_EMNodeTimeout_mS_u16	7510
k_ESPNTCEnableTimeout_mS_u16	9789
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	42496
k_EtatMTSigInvalidThresh_Cnt_u16	12000
k_EtatMTSigValidThresh_Cnt_u16	47328
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	67
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	29591
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	8103
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	8274
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	21102
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	44876

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	15549
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	41793
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	24064
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	62648
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	7076
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	20420
k_ISDATDIRASentDiag_Cnt_str.Threshold	2451
k_ISDATDIRASentDiag_Cnt_str.PStep	5266
k_ISDATDIRASentDiag_Cnt_str.NStep	3881
k_ISDATDIRASentTimeout_mS_u16	27073
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	45741
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	13428
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	46233
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	12853
k_ISDYNAASChkSumValidThresh_Cnt_u16	501
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	22784
k_ISDYNAASMsgCountValidThresh_Cnt_u16	26681
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	11177
k_ISDYNAASMsgLenValidThresh_Cnt_u16	15122
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	58663
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	19598
k_ISDYNABRChkSumValidThresh_Cnt_u16	34614
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	39317
k_ISDYNABRMsgCountValidThresh_Cnt_u16	1837
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	7704
k_ISDYNABRMsgLenValidThresh_Cnt_u16	25308
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	58552
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	30530
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	42293
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	39849
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	10290
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	16778
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	50540
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	3079
k_ISDYNVOLChkSumValidThresh_Cnt_u16	46996
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	31213
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	60009
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	37842
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	15302
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	47052
k_IgnOnTimeout_mS_u16	5779
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	218.949799
k_PowerCutVehSpdLowThresh_Kph_f32	162.176407
k_PowerCutVehSpdLowTimeout_mS_u16	34651
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	1.59959996
k_VBattMaxCAV_Volt_f32	17.5408001
k_VBattMaxCMM388_Volt_f32	0.310200006
k_VBattMaxCMM_Volt_f32	0.913299978
k_VBattMaxESP_Volt_f32	24.7889004
k_VBattMinAAS_Volt_f32	23.8777008
k_VBattMinBSI_Volt_f32	24.7889004
k_VBattMinCAV_Volt_f32	18.0102005
k_VBattMinCMM388_Volt_f32	12.5866003
k_VBattMinCMM_Volt_f32	2.86310005
k_VBattMinESP_Volt_f32	0.913299978
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	62335
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	50683
k_VitesseVehicleBVRampValidThresh_Cnt_u16	28070
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	37011
k_VitesseVehicleBVSigValidThresh_Cnt_u16	30143
k_VitesseVehicleBVSpeedPassThresh_kph_f32	126.869698
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	6833
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	58305
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2625328896
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	55588
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3771360768
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	38
target_SrlComInput_Per1_Batt_Volt_f32.value	11.9983997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	572786432
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	170
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.324140698
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	191
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	473560832
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	18
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	364746496
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1515271936
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	197
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2448742144
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1688762112
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2053904128
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2067773184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	123
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	214
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2012337920
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	169
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	177
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	223
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	225
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	246
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1609627392
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3539244800
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	62
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1359492864
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	197
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	204
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1393657600
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	70
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0548456311
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	272079
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	97.4383011
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	54048

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3771360768	3771360768	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3771360768	3771360768	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3771360768	3771360768	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3771360768	3771360768	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3771360768	3771360768	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3771360768	3771360768	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3771360768	3771360768	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	34276	34276	✔
BSINodeAbsentTimer_mS_M_u32	3771360768	3771360768	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3771360768	3771360768	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3771360768	3771360768	✔
CDD_SrlComVehSpd_Kph_G_f32	317.017395	317.017395	✔
CMM388NTCEnableTimer_mS_M_u32	3771360768	3771360768	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3771360768	3771360768	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3771360768	3771360768	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	27748	27748	✔
CONSANGLECPK_HwDeg_M_f32	28.5697994	28.5697994 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3771360768	3771360768	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3771360768	3771360768	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3771360768	3771360768	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3771360768	3771360768	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3771360768	3771360768	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3771360768	3771360768	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3771360768	3771360768	✔
ESPNTCEnableTimer_mS_M_u32	3771360768	3771360768	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3771360768	3771360768	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	979	979	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1085	1085	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1000	1000	✔
ElecIntTimer_mS_M_u32[1]	2000	2000	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3771360768	3771360768	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	18286	18286	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3771360768	3771360768	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	63290	63290	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3771360768	3771360768	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	8262	8262	✔
ISDATBSI412MsgTimer_mS_M_u32	3771360768	3771360768	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	3734	3734	✔
ISDATBSI432MsgTimer_mS_M_u32	3771360768	3771360768	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3771360768	3771360768	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	26563	26563	✔
ISDYN2CMMMsgTimer_mS_M_u32	3771360768	3771360768	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	65181	65181	✔
ISDYNAASMsgTimer_mS_M_u32	3771360768	3771360768	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	27748	27748	✔
ISDYNABRMsgTimer_mS_M_u32	3771360768	3771360768	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	63290	63290	✔
ISDYNCMM208MsgTimer_mS_M_u32	3771360768	3771360768	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	28636	28636	✔
ISDYNCMM388MsgTimer_mS_M_u32	3771360768	3771360768	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	53016	53016	✔
ISDYNVOLMsgTimer_mS_M_u32	3771360768	3771360768	✔
IgnOnTimer_mS_M_u32	2916611840	2916611840	✔
IgnTimeOff_Sec_M_u32	84907832	84907832	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	191	191	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	473560832	473560832	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	18	18	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	364746496	364746496	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	220	220	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1515271936	1515271936	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	197	197	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2448742144	2448742144	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3811194624	3811194624	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2053904128	2053904128	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	202	202	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2067773184	2067773184	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	30	30	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2012337920	2012337920	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	46	46	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1609627392	1609627392	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	26	26	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3539244800	3539244800	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	62	62	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1359492864	1359492864	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1393657600	1393657600	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	611.535217	611.535217	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	634.617188	634.617188	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	463.800903	463.800903	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	27748	27748	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	84907832	84907832	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	28.5697994	28.5697994 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	317.017395	317.017395	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.252 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3677392384
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	35791
AASNodeAbsentTimer_mS_M_u32	4263935488
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	9827
ANGLEVOLANTSigValidCount_Cnt_M_u16	30490
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	32412
AngleVolantMsgTimer_mS_M_u32	3677392384
AngleVolantValidCount_Cnt_M_u16	49207
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2449620480
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2890448384
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2284662272
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1378348544
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	7738
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2505944576
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	37223
CAVNodeAbsentTimer_mS_M_u32	3002539520
CDD_SrlComVehSpd_Kph_G_f32	378.541412
CMM388NTCEnableTimer_mS_M_u32	795303424
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3815579136
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	28913
CMMNodeAbsentTimer_mS_M_u32	1077014016
CONSANGLECPKSigInvalidCount_Cnt_M_u16	1483
CONSANGLECPKSigValidCount_Cnt_M_u16	59602
CONSANGLECPK_Cnt_M_u16	8333
CONSANGLECPK_HwDeg_M_f32	539.651123
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	8333
CPKVehicleSpeedMsgTimer_mS_M_u32	2428472832
CPKVehicleSpeedValidCount_Cnt_M_u16	39732
CityParkInputConsistentCount_Cnt_M_u16	51931
CityParkInputInvalidCount_Cnt_M_u16	52604
CityParkInputMsgTimer_mS_M_u32	473560832
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2982837760
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	19571

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	399482368
ComputerRazGCTSigValidCount_Cnt_M_u16	29920
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	57048
DMDFCTCPKSigValidCount_Cnt_M_u16	14199
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	21173
DMDRELAXECPKSigValidCount_Cnt_M_u16	40172
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	24984
DateInvalidTimer_mS_M_u32	2890448384
DiagMuxOnAbsentTimer_mS_M_u32	2269531648
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1378348544
ESPNTCEnableTimer_mS_M_u32	609713664
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	61284
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	6
EffacDefaultDiagTimer_mS_M_u32[1]	16
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2500
ElecIntTimer_mS_M_u32[1]	3500
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4262440448
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	1638
EtatMTSigValidCount_Cnt_M_u16	52810
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	43037
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1188
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	33261
ISDAT4V2BSI552MsgTimer_mS_M_u32	651554304
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	48597
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	3201
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	52810
ISDATBSI3F2MsgTimer_mS_M_u32	2096385536
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	23088
ISDATBSI412MsgLenValidCount_Cnt_M_u16	50187
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	1638
ISDATBSI412MsgTimer_mS_M_u32	1994296832
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	51861
ISDATBSI432MsgLenValidCount_Cnt_M_u16	64520
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	23736
ISDATDIRASentFltAcc_Cnt_M_u16	57452
ISDATDIRASentTimer_mS_M_u32	2428472832
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	40123
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	49207
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	14383
ISDYN2CMMMsgTimer_mS_M_u32	3068231168
ISDYNAASChkSumInvalidCount_Cnt_M_u16	1057
ISDYNAASChkSumValidCount_Cnt_M_u16	28664
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	65535
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	26978
ISDYNAASMsgLenValidCount_Cnt_M_u16	8498
ISDYNAASMsgTimeValidCount_Cnt_M_u16	1057
ISDYNAASMsgTimer_mS_M_u32	901996032
ISDYNABRChkSumInvalidCount_Cnt_M_u16	43994
ISDYNABRChkSumValidCount_Cnt_M_u16	31066
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	60920
ISDYNABRMsgCountValidCount_Cnt_M_u16	56591
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	17058
ISDYNABRMsgLenValidCount_Cnt_M_u16	59625
ISDYNABRMsgTimeValidCount_Cnt_M_u16	8333
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	7036
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	23569
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	52810
ISDYNCMM208MsgTimer_mS_M_u32	3427220992
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	7036
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	23569
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	29413

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2702106112
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	13177
ISDYNVOLChkSumValidCount_Cnt_M_u16	40192
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	40838
ISDYNVOLMsgCountValidCount_Cnt_M_u16	48805
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	42125
ISDYNVOLMsgLenValidCount_Cnt_M_u16	52341
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28913
ISDYNVOLMsgTimer_mS_M_u32	170630656
IgnOnTimer_mS_M_u32	850583040
IgnTimeOff_Sec_M_u32	2090327135
ManVehSpd_Kph_M_f32	202.618103
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	124
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	252
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2202684928
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	177
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3605278208
PrevISDATBSI412MsgDLCError_Cnt_M_u08	43
PrevISDATBSI412MsgRxTime_MSec_M_u32	151526912
PrevISDATBSI432MsgDLCError_Cnt_M_u08	202
PrevISDATBSI432MsgRxTime_MSec_M_u32	745242112
PrevISDATDIRAMsgTxTime_MSec_M_u32	2881232384
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	205
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2995088896
PrevISDYNAASMsgDLCError_Cnt_M_u08	163
PrevISDYNAASMsgRxTime_MSec_M_u32	1314496000
PrevISDYNABRMsgDLCError_Cnt_M_u08	163
PrevISDYNABRMsgRxTime_MSec_M_u32	1651170816
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	98
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3726548480
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	247
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2435218944
PrevISDYNVOLMsgDLCError_Cnt_M_u08	29
PrevISDYNVOLMsgRxTime_MSec_M_u32	2871336448
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	898403840
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	640.076904
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	53264
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	52832
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	49849
VitesseVehicleBVRampValidCount_Cnt_M_u16	40393
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	57996
VitesseVehicleBVSigValidCount_Cnt_M_u16	12291
VitesseVehicleBV_Kph_M_f32	537.501221
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	29413
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	65428
VitesseVehiculeRoues_Kph_M_f32	289.775085
k_AASNTCEnableTimeout_mS_u16	2140
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	38890
k_AASNodeTimeout_mS_u16	57696
k_ABSNodeTimeout_mS_u16	24797
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	12168
k_ANGLEVOLANTSigValidThresh_Cnt_u16	16699
k_AngleVolantInvalidThresh_Cnt_u16	47706
k_AngleVolantValidThresh_Cnt_u16	52604
k_BSI552MsgTimeout_mS_u16	25971
k_BSINTCEnableTimeout_mS_u16	27213
k_BSINodeAbsentDiag_Cnt_str.Threshold	27250
k_BSINodeAbsentDiag_Cnt_str.PStep	19801
k_BSINodeAbsentDiag_Cnt_str.NStep	42692
k_BSINodeAbsentTimeout_mS_u16	61524
k_BSINodeTimeout_mS_u16	23736
k_BattOvHi_Volt_f32	29.1854992
k_BattOvLo_Volt_f32	16.2509995
k_BattUvHi_Volt_f32	24.7049999
k_BattUvLo_Volt_f32	16.8712997
k_CAVNTCEnableTimeout_mS_u16	25570
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	789
k_CAVNodeTimeout_mS_u16	33831
k_CMM388MsgTimeout_mS_u16	57039
k_CMM388NTCEnableTimeout_mS_u16	24107
k_CMMNTCEnableTimeout_mS_u16	63885
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	29936
k_CONSANGLECPKMax_HwDeg_f32	777.735413
k_CONSANGLECPKMin_HwDeg_f32	-113.338799
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	17893
k_CONSANGLECPKSigValidThresh_Cnt_u16	4756
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	14038
k_CPKVehicleSpeedValidThresh_Cnt_u16	15339
k_CityParkInputInvalidThresh_Cnt_u16	62928
k_CityParkInputValidThresh_Cnt_u16	51931
k_ComputerRazGCTSigValidThresh_Cnt_u16	26283
k_CptTemporelSigValidThresh_Cnt_u16	51671
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	38306
k_DMDFCTCPKSigValidThresh_Cnt_u16	31721
k_DMDFCTCPKValidCount_Cnt_u16	3970
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	14383
k_DMDRELAXECPKSigValidThresh_Cnt_u16	46094
k_DMDRelaxeConsistentThresh_Cnt_u16	45956
k_DateValidThresh_Cnt_u16	33261
k_DefaultVehSpd_Kph_f32	111.381599
k_DiagMuxOnAbsentTimeout_mS_u16	16499
k_EMNodeTimeout_mS_u16	55544
k_ESPNTCEnableTimeout_mS_u16	29123
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	56632
k_EtatMTSigInvalidThresh_Cnt_u16	62681
k_EtatMTSigValidThresh_Cnt_u16	54169
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	63601
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	27444
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	20356
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	36290
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	58414
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	39380
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	64514
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	21813
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	25657
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	55185
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	36749
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	42350
k_ISDATDIRASentDiag_Cnt_str.Threshold	42732

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	3144
k_ISDATDIRASentDiag_Cnt_str.NStep	10267
k_ISDATDIRASentTimeout_mS_u16	2102
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	24755
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	32412
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	13999
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	32474
k_ISDYNAASChkSumValidThresh_Cnt_u16	35930
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	16632
k_ISDYNAASMsgCountValidThresh_Cnt_u16	28687
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	25214
k_ISDYNAASMsgLenValidThresh_Cnt_u16	17412
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	42883
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	11088
k_ISDYNABRChkSumValidThresh_Cnt_u16	38935
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	28986
k_ISDYNABRMsgCountValidThresh_Cnt_u16	1329
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	33777
k_ISDYNABRMsgLenValidThresh_Cnt_u16	16996
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	22672
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	53940
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	39961
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	15935
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	31075
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	2586
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	820
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	12195
k_ISDYNVOLChkSumValidThresh_Cnt_u16	55742
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	33073
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	41726
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	56258
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	12454
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	10451
k_IgnOnTimeout_mS_u16	16383
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	84.1300964
k_PowerCutVehSpdLowThresh_Kph_f32	102.450401
k_PowerCutVehSpdLowTimeout_mS_u16	27560
k_VBattMaxAAS_Volt_f32	10.6469002
k_VBattMaxBSI_Volt_f32	15.1791
k_VBattMaxCAV_Volt_f32	10.3134003
k_VBattMaxCMM388_Volt_f32	3.8039999
k_VBattMaxCMM_Volt_f32	4.41169977
k_VBattMaxESP_Volt_f32	12.4168997
k_VBattMinAAS_Volt_f32	10.2518997
k_VBattMinBSI_Volt_f32	12.4168997
k_VBattMinCAV_Volt_f32	10.5488005
k_VBattMinCMM388_Volt_f32	13.9933004
k_VBattMinCMM_Volt_f32	31.1434002
k_VBattMinESP_Volt_f32	4.41169977
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	26173
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	23432
k_VitesseVehicleBVRampValidThresh_Cnt_u16	29318
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	12288
k_VitesseVehicleBVSigValidThresh_Cnt_u16	44348
k_VitesseVehicleBVSpeedPassThresh_kph_f32	30.8327999
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	25703
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	50679
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2890448384
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	5919
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2992083200
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	247
target_SrlComInput_Per1_Batt_Volt_f32.value	14.4397001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3658395136
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	147
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.558238626
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	19
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4018986496
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	17
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	427949568
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2722569728
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2447130112
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4030815744
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3312877056
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	427531776
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	108
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	121
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	203
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	207
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	221
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	333790720
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	68
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	80
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	130
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	147
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	98
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3228032512
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	147
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2111634944
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1512185344
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	134
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	175
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3712364032
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	971
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.825236738
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	938993
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	200.914505
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	46874

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2992083200	2992083200	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2992083200	2992083200	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2992083200	2992083200	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2992083200	2992083200	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2992083200	2992083200	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2992083200	2992083200	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2992083200	2992083200	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	27250	27250	✔
BSINodeAbsentTimer_mS_M_u32	2992083200	2992083200	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2992083200	2992083200	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2992083200	2992083200	✔
CDD_SrlComVehSpd_Kph_G_f32	202.618103	202.618103	✔
CMM388NTCEnableTimer_mS_M_u32	2992083200	2992083200	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2992083200	2992083200	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2992083200	2992083200	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	8333	8333	✔
CONSANGLECPK_HwDeg_M_f32	539.651123	539.651123 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2992083200	2992083200	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2992083200	2992083200	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2992083200	2992083200	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2992083200	2992083200	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2992083200	2992083200	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2992083200	2992083200	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2992083200	2992083200	✔
ESPNTCEnableTimer_mS_M_u32	2992083200	2992083200	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2992083200	2992083200	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	6	6	✔
EffacDefaultDiagTimer_mS_M_u32[1]	16	16	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2500	2500	✔
ElecIntTimer_mS_M_u32[1]	3500	3500	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2992083200	2992083200	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	33261	33261	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2992083200	2992083200	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	52810	52810	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2992083200	2992083200	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	1638	1638	✔
ISDATBSI412MsgTimer_mS_M_u32	2992083200	2992083200	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	23736	23736	✔
ISDATBSI432MsgTimer_mS_M_u32	2992083200	2992083200	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2992083200	2992083200	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	14383	14383	✔
ISDYN2CMMMsgTimer_mS_M_u32	2992083200	2992083200	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	1057	1057	✔
ISDYNAASMsgTimer_mS_M_u32	2992083200	2992083200	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	8333	8333	✔
ISDYNABRMsgTimer_mS_M_u32	2992083200	2992083200	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	52810	52810	✔
ISDYNCMM208MsgTimer_mS_M_u32	2992083200	2992083200	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	29413	29413	✔
ISDYNCMM388MsgTimer_mS_M_u32	2992083200	2992083200	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28913	28913	✔
ISDYNVOLMsgTimer_mS_M_u32	2992083200	2992083200	✔
IgnOnTimer_mS_M_u32	850583040	850583040	✔
IgnTimeOff_Sec_M_u32	2090327135	2090327135	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	19	19	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4018986496	4018986496	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	17	17	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	427949568	427949568	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	233	233	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2722569728	2722569728	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	164	164	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2447130112	2447130112	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2881232384	2881232384	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3312877056	3312877056	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	119	119	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	427531776	427531776	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	333790720	333790720	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	98	98	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3228032512	3228032512	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	147	147	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2111634944	2111634944	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	95	95	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1512185344	1512185344	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3712364032	3712364032	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	640.076904	640.076904	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	537.501221	537.501221	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	289.775085	289.775085	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	8333	8333	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2090327135	2090327135	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	539.651123	539.651123 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.253 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1841633536
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	62953
AASNodeAbsentTimer_mS_M_u32	2292402432
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	6188
ANGLEVOLANTSigValidCount_Cnt_M_u16	36805
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	37250
AngleVolantMsgTimer_mS_M_u32	1841633536
AngleVolantValidCount_Cnt_M_u16	41265
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3960473856
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3611068672
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2706323712
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2657024256
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	19623
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3686643968
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	36767
CAVNodeAbsentTimer_mS_M_u32	4105267456
CDD_SrlComVehSpd_Kph_G_f32	114.470001
CMM388NTCEnableTimer_mS_M_u32	2422253824
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3142543616
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	29634
CMMNodeAbsentTimer_mS_M_u32	2084632832
CONSANGLECPKSigInvalidCount_Cnt_M_u16	51444
CONSANGLECPKSigValidCount_Cnt_M_u16	51614
CONSANGLECPK_Cnt_M_u16	52845
CONSANGLECPK_HwDeg_M_f32	228.129807
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	52845
CPKVehicleSpeedMsgTimer_mS_M_u32	1226316032
CPKVehicleSpeedValidCount_Cnt_M_u16	53601
CityParkInputConsistentCount_Cnt_M_u16	4421
CityParkInputInvalidCount_Cnt_M_u16	7777
CityParkInputMsgTimer_mS_M_u32	4018986496
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4256647424
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	17405

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3358058752
ComputerRazGCTSigValidCount_Cnt_M_u16	26422
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	23117
DMDFCTCPKSigValidCount_Cnt_M_u16	23087
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	23350
DMDRELAXECPKSigValidCount_Cnt_M_u16	58959
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	10637
DateInvalidTimer_mS_M_u32	3611068672
DiagMuxOnAbsentTimer_mS_M_u32	4035172608
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2657024256
ESPNTCEnableTimer_mS_M_u32	437274880
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	21032
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	88
EffacDefaultDiagTimer_mS_M_u32[1]	108
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	979
ElecIntTimer_mS_M_u32[1]	1085
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3920083200
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	6242
EtatMTSigValidCount_Cnt_M_u16	55928
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	43518
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	15912
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	53965
ISDAT4V2BSI552MsgTimer_mS_M_u32	1481963776
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	26516
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	46418
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	55928
ISDATBSI3F2MsgTimer_mS_M_u32	1199167744
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	52102
ISDATBSI412MsgLenValidCount_Cnt_M_u16	34739
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	6242
ISDATBSI412MsgTimer_mS_M_u32	3535476992
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	63190
ISDATBSI432MsgLenValidCount_Cnt_M_u16	48188
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	45484
ISDATDIRASentFltAcc_Cnt_M_u16	63120
ISDATDIRASentTimer_mS_M_u32	1226316032
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	37347
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	41265
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	27208
ISDYN2CMMMsgTimer_mS_M_u32	175261952
ISDYNAASChkSumInvalidCount_Cnt_M_u16	21747
ISDYNAASChkSumValidCount_Cnt_M_u16	64301
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	53980
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	45998
ISDYNAASMsgLenValidCount_Cnt_M_u16	22016
ISDYNAASMsgTimeValidCount_Cnt_M_u16	21747
ISDYNAASMsgTimer_mS_M_u32	3981224192
ISDYNABRChkSumInvalidCount_Cnt_M_u16	7493
ISDYNABRChkSumValidCount_Cnt_M_u16	16007
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	45934
ISDYNABRMsgCountValidCount_Cnt_M_u16	53224
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	11887
ISDYNABRMsgLenValidCount_Cnt_M_u16	58713
ISDYNABRMsgTimeValidCount_Cnt_M_u16	52845
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	22774
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	42999
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	55928
ISDYNCMM208MsgTimer_mS_M_u32	2436958464
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	22774
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	42999
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	49447

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	963258624
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	30698
ISDYNVOLChkSumValidCount_Cnt_M_u16	58644
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	20547
ISDYNVOLMsgCountValidCount_Cnt_M_u16	64677
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	5805
ISDYNVOLMsgLenValidCount_Cnt_M_u16	51383
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	29634
ISDYNVOLMsgTimer_mS_M_u32	1628694784
IgnOnTimer_mS_M_u32	343812352
IgnTimeOff_Sec_M_u32	644731610
ManVehSpd_Kph_M_f32	118.578003
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	125
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	169
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	209180928
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	196
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1361721600
PrevISDATBSI412MsgDLCError_Cnt_M_u08	76
PrevISDATBSI412MsgRxTime_MSec_M_u32	1987995904
PrevISDATBSI432MsgDLCError_Cnt_M_u08	164
PrevISDATBSI432MsgRxTime_MSec_M_u32	1372866816
PrevISDATDIRAMsgTxTime_MSec_M_u32	1583507712
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	68
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3544611072
PrevISDYNAASMsgDLCError_Cnt_M_u08	62
PrevISDYNAASMsgRxTime_MSec_M_u32	3431590144
PrevISDYNABRMsgDLCError_Cnt_M_u08	106
PrevISDYNABRMsgRxTime_MSec_M_u32	1700145408
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	203
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1899686144
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	61
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3483584768
PrevISDYNVOLMsgDLCError_Cnt_M_u08	108
PrevISDYNVOLMsgRxTime_MSec_M_u32	1143433472
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3467712768
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	93.8843002
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	47012
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	34422
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	50089
VitesseVehicleBVRampValidCount_Cnt_M_u16	64571
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	51121
VitesseVehicleBVSigValidCount_Cnt_M_u16	18698
VitesseVehicleBV_Kph_M_f32	501.600586
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	49447
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	25816
VitesseVehiculeRoues_Kph_M_f32	243.604095
k_AASNTCEnableTimeout_mS_u16	4864
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	42520
k_AASNodeTimeout_mS_u16	19830
k_ABSNodeTimeout_mS_u16	10302
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	21501
k_ANGLEVOLANTSigValidThresh_Cnt_u16	30883
k_AngleVolantInvalidThresh_Cnt_u16	18758
k_AngleVolantValidThresh_Cnt_u16	7777
k_BSI552MsgTimeout_mS_u16	28475
k_BSINTCEnableTimeout_mS_u16	63406
k_BSINodeAbsentDiag_Cnt_str.Threshold	48531
k_BSINodeAbsentDiag_Cnt_str.PStep	62495
k_BSINodeAbsentDiag_Cnt_str.NStep	55070
k_BSINodeAbsentTimeout_mS_u16	7258
k_BSINodeTimeout_mS_u16	45484
k_BattOvHi_Volt_f32	20.4284
k_BattOvLo_Volt_f32	20.9871998
k_BattUvHi_Volt_f32	25.3005009
k_BattUvLo_Volt_f32	7.38310003
k_CAVNTCEnableTimeout_mS_u16	29487
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	29333
k_CAVNodeTimeout_mS_u16	48608
k_CMM388MsgTimeout_mS_u16	64745
k_CMM388NTCEnableTimeout_mS_u16	61141
k_CMMNTCEnableTimeout_mS_u16	37996
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	29892
k_CONSANGLECPKMax_HwDeg_f32	660.644287
k_CONSANGLECPKMin_HwDeg_f32	-635.013
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	18471
k_CONSANGLECPKSigValidThresh_Cnt_u16	11224
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	42260
k_CPKVehicleSpeedValidThresh_Cnt_u16	53845
k_CityParkInputInvalidThresh_Cnt_u16	38755
k_CityParkInputValidThresh_Cnt_u16	4421
k_ComputerRazGCTSigValidThresh_Cnt_u16	17682
k_CptTemporelSigValidThresh_Cnt_u16	21840
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	13679
k_DMDFCTCPKSigValidThresh_Cnt_u16	11353
k_DMDFCTCPKValidCount_Cnt_u16	39119
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	27208
k_DMDRELAXECPKSigValidThresh_Cnt_u16	106
k_DMDRelaxeConsistentThresh_Cnt_u16	23048
k_DateValidThresh_Cnt_u16	53965
k_DefaultVehSpd_Kph_f32	93.6941986
k_DiagMuxOnAbsentTimeout_mS_u16	34491
k_EMNodeTimeout_mS_u16	17261
k_ESPNTCEnableTimeout_mS_u16	24203
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	23532
k_EtatMTSigInvalidThresh_Cnt_u16	65096
k_EtatMTSigValidThresh_Cnt_u16	60362
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	35907
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	52665
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	26442
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	60365
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	8779
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	40090
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	22159
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	42165
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	47594
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	47457
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	2863
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	45771
k_ISDATDIRASentDiag_Cnt_str.Threshold	53644

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	28273
k_ISDATDIRASentDiag_Cnt_str.NStep	22576
k_ISDATDIRASentTimeout_mS_u16	30769
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	54524
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	37250
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	49095
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	42053
k_ISDYNAASChkSumValidThresh_Cnt_u16	1415
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	47726
k_ISDYNAASMsgCountValidThresh_Cnt_u16	5864
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	35161
k_ISDYNAASMsgLenValidThresh_Cnt_u16	46474
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	26059
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	44133
k_ISDYNABRChkSumValidThresh_Cnt_u16	4047
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	21415
k_ISDYNABRMsgCountValidThresh_Cnt_u16	384
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	15042
k_ISDYNABRMsgLenValidThresh_Cnt_u16	22824
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	17251
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	16312
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	59851
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	29401
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	7980
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	54981
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	23865
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	55085
k_ISDYNVOLChkSumValidThresh_Cnt_u16	53914
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	4289
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	20891
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	2126
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	9060
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	63003
k_IgnOnTimeout_mS_u16	5657
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	181.948593
k_PowerCutVehSpdLowThresh_Kph_f32	70.9877014
k_PowerCutVehSpdLowTimeout_mS_u16	6428
k_VBattMaxAAS_Volt_f32	22.4368
k_VBattMaxBSI_Volt_f32	6.06879997
k_VBattMaxCAV_Volt_f32	23.7917995
k_VBattMaxCMM388_Volt_f32	19.9237003
k_VBattMaxCMM_Volt_f32	10.8494997
k_VBattMaxESP_Volt_f32	11.9385996
k_VBattMinAAS_Volt_f32	0.128900006
k_VBattMinBSI_Volt_f32	11.9385996
k_VBattMinCAV_Volt_f32	18.1550999
k_VBattMinCMM388_Volt_f32	13.3000002
k_VBattMinCMM_Volt_f32	30.9113998
k_VBattMinESP_Volt_f32	10.8494997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	27742
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	17979
k_VitesseVehicleBVRampValidThresh_Cnt_u16	55107
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	11284
k_VitesseVehicleBVSigValidThresh_Cnt_u16	11810
k_VitesseVehicleBVSpeedPassThresh_kph_f32	235.258499
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	5791
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	48049
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3611068672
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	33851
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1008472064
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	61
target_SrlComInput_Per1_Batt_Volt_f32.value	9.53590012
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	296401152
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	234
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.339613676
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3320850688
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	87
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	76597504
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1723951360
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	149
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3565291776
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	902998272
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1924352256
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	115
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1931733248
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	43
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	69
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	76
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	185
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2993096960
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	109
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	172
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	114
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2136942848
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	58706176
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	244
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1798334720
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	45
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	80
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	106
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	129
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	137
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	153
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1174681856
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2438
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.734811425
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	730816
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	62.8454018
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	43654

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1008472064	1008472064	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1008472064	1008472064	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	48531	48531	✔
BSINodeAbsentTimer_mS_M_u32	1008472064	1008472064	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1008472064	1008472064	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1008472064	1008472064	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	52845	52845	✔
CONSANGLECPK_HwDeg_M_f32	228.129807	228.129807 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1008472064	1008472064	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1008472064	1008472064	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1008472064	1008472064	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1008472064	1008472064	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1008472064	1008472064	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1008472064	1008472064	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1008472064	1008472064	✔
ESPNTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1008472064	1008472064	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	88	88	✔
EffacDefaultDiagTimer_mS_M_u32[1]	108	108	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1008472064	1008472064	✔
ElecIntTimer_mS_M_u32[1]	1085	1085	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1008472064	1008472064	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1008472064	1008472064	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1008472064	1008472064	✔
IgnOnTimer_mS_M_u32	1008472064	1008472064	✔
IgnTimeOff_Sec_M_u32	644731610	644731610	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	51	51	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3320850688	3320850688	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	87	87	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	76597504	76597504	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1723951360	1723951360	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	149	149	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3565291776	3565291776	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1583507712	1583507712	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	210	210	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1924352256	1924352256	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	115	115	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1931733248	1931733248	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	133	133	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2993096960	2993096960	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	114	114	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2136942848	2136942848	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	251	251	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	58706176	58706176	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	244	244	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1798334720	1798334720	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1174681856	1174681856	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	93.8843002	93.8843002	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	501.600586	501.600586	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	243.604095	243.604095	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	52845	52845	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	644731610	644731610	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	228.129807	228.129807 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	93.6941986	93.6941986	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.254 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2314434560
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	9093
AASNodeAbsentTimer_mS_M_u32	2920867840
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	59070
ANGLEVOLANTSigValidCount_Cnt_M_u16	17073
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	62650
AngleVolantMsgTimer_mS_M_u32	2314434560
AngleVolantValidCount_Cnt_M_u16	18479
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	651339776
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3075287040
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1070929920
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	933615616
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	62797
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1787402240
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	22243
CAVNodeAbsentTimer_mS_M_u32	3396241408
CDD_SrlComVehSpd_Kph_G_f32	380.898987
CMM388NTCEnableTimer_mS_M_u32	3294676992
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1855227904
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	8762
CMMNodeAbsentTimer_mS_M_u32	2785007616
CONSANGLECPKSigInvalidCount_Cnt_M_u16	59236
CONSANGLECPKSigValidCount_Cnt_M_u16	0
CONSANGLECPK_Cnt_M_u16	54714
CONSANGLECPK_HwDeg_M_f32	-258.536499
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	54714
CPKVehicleSpeedMsgTimer_mS_M_u32	66746368
CPKVehicleSpeedValidCount_Cnt_M_u16	5157
CityParkInputConsistentCount_Cnt_M_u16	18419

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	57758
CityParkInputMsgTimer_mS_M_u32	3320850688
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2665277440
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	35145
ComputerRazGCTSigInvalidTimer_mS_M_u32	1242236928
ComputerRazGCTSigValidCount_Cnt_M_u16	18976
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	56794
DMDFCTCPKSigValidCount_Cnt_M_u16	49397
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	50592
DMDRELAXECPKSigValidCount_Cnt_M_u16	59155
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	27033
DateInvalidTimer_mS_M_u32	3075287040
DiagMuxOnAbsentTimer_mS_M_u32	1823946752
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	933615616
ESPNTCEnableTimer_mS_M_u32	3989956608
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	31177
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1
EffacDefaultDiagTimer_mS_M_u32[1]	11
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	16
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1758173184
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	1370
EtatMTSigValidCount_Cnt_M_u16	29144
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	60486
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	12937
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20251
ISDAT4V2BSI552MsgTimer_mS_M_u32	1640224768
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	46916
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	8395
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	29144
ISDATBSI3F2MsgTimer_mS_M_u32	3218421760
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	57456
ISDATBSI412MsgLenValidCount_Cnt_M_u16	48807
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	1370
ISDATBSI412MsgTimer_mS_M_u32	3004266496
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	59646
ISDATBSI432MsgLenValidCount_Cnt_M_u16	35725
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	25788
ISDATDIRASentFltAcc_Cnt_M_u16	9744
ISDATDIRASentTimer_mS_M_u32	66746368
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	58200
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	18479
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	23017
ISDYN2CMMMsgTimer_mS_M_u32	615245824
ISDYNAASChkSumInvalidCount_Cnt_M_u16	44647
ISDYNAASChkSumValidCount_Cnt_M_u16	65146
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	39486
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	59062
ISDYNAASMsgLenValidCount_Cnt_M_u16	41601
ISDYNAASMsgTimeValidCount_Cnt_M_u16	44647
ISDYNAASMsgTimer_mS_M_u32	1570555904
ISDYNABRChkSumInvalidCount_Cnt_M_u16	5872
ISDYNABRChkSumValidCount_Cnt_M_u16	5611
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	16118
ISDYNABRMsgCountValidCount_Cnt_M_u16	11337
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	25331
ISDYNABRMsgLenValidCount_Cnt_M_u16	16630
ISDYNABRMsgTimeValidCount_Cnt_M_u16	54714
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	5154

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	62689
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	29144
ISDYNCMM208MsgTimer_mS_M_u32	994027520
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	5154
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	62689
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	16461
ISDYNCMM388MsgTimer_mS_M_u32	3477358592
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	12930
ISDYNVOLChkSumValidCount_Cnt_M_u16	60869
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	21496
ISDYNVOLMsgCountValidCount_Cnt_M_u16	12691
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	32826
ISDYNVOLMsgLenValidCount_Cnt_M_u16	60637
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	8762
ISDYNVOLMsgTimer_mS_M_u32	793184256
IgnOnTimer_mS_M_u32	2382907392
IgnTimeOff_Sec_M_u32	2218436033
ManVehSpd_Kph_M_f32	626.880676
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	126
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	252
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3906680832
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	249
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1547966464
PrevISDATBSI412MsgDLCError_Cnt_M_u08	128
PrevISDATBSI412MsgRxTime_MSec_M_u32	3104278528
PrevISDATBSI432MsgDLCError_Cnt_M_u08	215
PrevISDATBSI432MsgRxTime_MSec_M_u32	1451616256
PrevISDATDIRAMsgTxTime_MSec_M_u32	2438694912
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	250
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2532268032
PrevISDYNAASMsgDLCError_Cnt_M_u08	157
PrevISDYNAASMsgRxTime_MSec_M_u32	1155860480
PrevISDYNABRMsgDLCError_Cnt_M_u08	146
PrevISDYNABRMsgRxTime_MSec_M_u32	4219488256
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	143
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1523714048
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	172
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3642288128
PrevISDYNVOLMsgDLCError_Cnt_M_u08	66
PrevISDYNVOLMsgRxTime_MSec_M_u32	873236480
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	388986880
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	119.613899
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	13012
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	26911
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	25285
VitesseVehicleBVRampValidCount_Cnt_M_u16	23504
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	11311
VitesseVehicleBVSigValidCount_Cnt_M_u16	27362

Name	Input Value
VitesseVehicleBV_Kph_M_f32	565.517212
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	16461
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	30712
VitesseVehiculeRoues_Kph_M_f32	404.991302
k_AASNTCEnableTimeout_mS_u16	5121
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	38266
k_AASNodeTimeout_mS_u16	5151
k_ABSNodeTimeout_mS_u16	30727
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	11657
k_ANGLEVOLANTSigValidThresh_Cnt_u16	45656
k_AngleVolantInvalidThresh_Cnt_u16	35951
k_AngleVolantValidThresh_Cnt_u16	57758
k_BSI552MsgTimeout_mS_u16	42191
k_BSINTCEnableTimeout_mS_u16	18038
k_BSINodeAbsentDiag_Cnt_str.Threshold	61899
k_BSINodeAbsentDiag_Cnt_str.PStep	45161
k_BSINodeAbsentDiag_Cnt_str.NStep	14762
k_BSINodeAbsentTimeout_mS_u16	46130
k_BSINodeTimeout_mS_u16	25788
k_BattOvHi_Volt_f32	31.3285999
k_BattOvLo_Volt_f32	14.3858995
k_BattUvHi_Volt_f32	9.92020035
k_BattUvLo_Volt_f32	25.4277
k_CAVNTCEnableTimeout_mS_u16	39732
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	1537
k_CAVNodeTimeout_mS_u16	47264
k_CMM388MsgTimeout_mS_u16	3717
k_CMM388NTCEnableTimeout_mS_u16	59585
k_CMMNTCEnableTimeout_mS_u16	37052
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	63540
k_CONSANGLECPKMax_HwDeg_f32	608.976074
k_CONSANGLECPKMin_HwDeg_f32	-763.412476
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	43853
k_CONSANGLECPKSigValidThresh_Cnt_u16	8952
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	1349
k_CPKVehicleSpeedValidThresh_Cnt_u16	51203
k_CityParkInputInvalidThresh_Cnt_u16	41110
k_CityParkInputValidThresh_Cnt_u16	18419
k_ComputerRazGCTSigValidThresh_Cnt_u16	38602
k_CptTemporelSigValidThresh_Cnt_u16	47313
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	19955
k_DMDFCTCPKSigValidThresh_Cnt_u16	27638
k_DMDFCTCPKValidCount_Cnt_u16	45269
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	23017
k_DMDRELAXECPKSigValidThresh_Cnt_u16	31300
k_DMDRelaxeConsistentThresh_Cnt_u16	25962
k_DateValidThresh_Cnt_u16	20251
k_DefaultVehSpd_Kph_f32	180.678101
k_DiagMuxOnAbsentTimeout_mS_u16	25808
k_EMNodeTimeout_mS_u16	39929
k_ESPNTCEnableTimeout_mS_u16	39455
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	58044
k_EtatMTSigInvalidThresh_Cnt_u16	16359
k_EtatMTSigValidThresh_Cnt_u16	55842
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	52152
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	14871
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	39396
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	20121
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	64992
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	48436
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	60883

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	63010
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	61378
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	58590
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	33333
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	53152
k_ISDATDIRASentDiag_Cnt_str.Threshold	63911
k_ISDATDIRASentDiag_Cnt_str.PStep	39954
k_ISDATDIRASentDiag_Cnt_str.NStep	1837
k_ISDATDIRASentTimeout_mS_u16	46636
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	27917
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	62650
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	26219
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	33264
k_ISDYNAASChkSumValidThresh_Cnt_u16	49387
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	10742
k_ISDYNAASMsgCountValidThresh_Cnt_u16	22345
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	8884
k_ISDYNAASMsgLenValidThresh_Cnt_u16	11235
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	35552
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	16657
k_ISDYNABRChkSumValidThresh_Cnt_u16	6548
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	57421
k_ISDYNABRMsgCountValidThresh_Cnt_u16	39296
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	52538
k_ISDYNABRMsgLenValidThresh_Cnt_u16	25801
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	8151
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	60056
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	55713
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	61430
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	53694
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	28081
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	34070
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	6523
k_ISDYNVOLChkSumValidThresh_Cnt_u16	14834
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	57854
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	11439
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	58774
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	18196
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	40241
k_IgnOnTimeout_mS_u16	3255
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	152.414902
k_PowerCutVehSpdLowThresh_Kph_f32	141.297699
k_PowerCutVehSpdLowTimeout_mS_u16	29101
k_VBattMaxAAS_Volt_f32	27.5335999
k_VBattMaxBSI_Volt_f32	18.9521008
k_VBattMaxCAV_Volt_f32	22.4051991
k_VBattMaxCMM388_Volt_f32	5.19899988
k_VBattMaxCMM_Volt_f32	21.1744995
k_VBattMaxESP_Volt_f32	8.59370041
k_VBattMinAAS_Volt_f32	32
k_VBattMinBSI_Volt_f32	8.59370041
k_VBattMinCAV_Volt_f32	21.1075001
k_VBattMinCMM388_Volt_f32	19.2371998
k_VBattMinCMM_Volt_f32	23.218399
k_VBattMinESP_Volt_f32	21.1744995
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	44775
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	62478
k_VitesseVehicleBVRampValidThresh_Cnt_u16	48888
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	6341
k_VitesseVehicleBVSigValidThresh_Cnt_u16	42332
k_VitesseVehicleBVSpeedPassThresh_kph_f32	160.185104
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	49635
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	30062
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3075287040
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	63428
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1401590528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	172
target_SrlComInput_Per1_Batt_Volt_f32.value	30.9874992
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3166869504
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	32
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.866229057
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3249686528
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3494930432
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	155
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3023996928
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3044845568
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	470468608
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	803792896
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	957810688
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	78
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	136
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	145
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	163
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	177
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4023232512
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	76
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	171
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	291850240
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1334011904
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	586254336
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	104
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	114
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	132
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	145
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1706432512
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1969
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.931365132
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	729864
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	71.9747009

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	25134		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1401590528	1401590528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1401590528	1401590528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1401590528	1401590528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1401590528	1401590528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1401590528	1401590528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1401590528	1401590528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1401590528	1401590528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	61899	61899	✔
BSINodeAbsentTimer_mS_M_u32	1401590528	1401590528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1401590528	1401590528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1401590528	1401590528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1401590528	1401590528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1401590528	1401590528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1401590528	1401590528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	54714	54714	✔
CONSANGLECPK_HwDeg_M_f32	-258.536499	-258.536499 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1401590528	1401590528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1401590528	1401590528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1401590528	1401590528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1401590528	1401590528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1401590528	1401590528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1401590528	1401590528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1401590528	1401590528	✔
ESPNTCEnableTimer_mS_M_u32	1401590528	1401590528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1401590528	1401590528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	11	11	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	1401590528	1401590528	✔
ElecIntTimer_mS_M_u32[1]	16	16	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1401590528	1401590528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1401590528	1401590528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1401590528	1401590528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1401590528	1401590528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1401590528	1401590528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1401590528	1401590528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1401590528	1401590528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1401590528	1401590528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1401590528	1401590528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1401590528	1401590528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1401590528	1401590528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1401590528	1401590528	✔
IgnOnTimer_mS_M_u32	1401590528	1401590528	✔
IgnTimeOff_Sec_M_u32	2218436033	2218436033	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	235	235	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3249686528	3249686528	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3494930432	3494930432	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	155	155	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3023996928	3023996928	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	132	132	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3044845568	3044845568	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2438694912	2438694912	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	803792896	803792896	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	233	233	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	957810688	957810688	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	137	137	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4023232512	4023232512	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	171	171	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	291850240	291850240	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	186	186	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1334011904	1334011904	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	186	186	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	586254336	586254336	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1706432512	1706432512	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	119.613899	119.613899	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	565.517212	565.517212	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	404.991302	404.991302	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	54714	54714	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2218436033	2218436033	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-258.536499	-258.536499 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	180.678101	180.678101	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.255 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1772378880
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	1772
AASNodeAbsentTimer_mS_M_u32	2666793728
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	16195
ANGLEVOLANTSigValidCount_Cnt_M_u16	58154
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	42829
AngleVolantMsgTimer_mS_M_u32	1772378880
AngleVolantValidCount_Cnt_M_u16	9585
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1271319296
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2757184256
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1451195136
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2718776064
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	3990
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1214380800
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	27475
CAVNodeAbsentTimer_mS_M_u32	678636288
CDD_SrlComVehSpd_Kph_G_f32	297.520905
CMM388NTCEnableTimer_mS_M_u32	3550243584
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1409362688
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	41486
CMMNodeAbsentTimer_mS_M_u32	1056914176
CONSANGLECPKSigInvalidCount_Cnt_M_u16	1106
CONSANGLECPKSigValidCount_Cnt_M_u16	65535
CONSANGLECPK_Cnt_M_u16	15632
CONSANGLECPK_HwDeg_M_f32	294.34079
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	15632
CPKVehicleSpeedMsgTimer_mS_M_u32	3616496384
CPKVehicleSpeedValidCount_Cnt_M_u16	52214
CityParkInputConsistentCount_Cnt_M_u16	13861
CityParkInputInvalidCount_Cnt_M_u16	9763

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	3249686528
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3702000384
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	58784
ComputerRazGCTSigInvalidTimer_mS_M_u32	3147672320
ComputerRazGCTSigValidCount_Cnt_M_u16	9118
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	8559
DMDFCTCPKSigValidCount_Cnt_M_u16	53214
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	43677
DMDRELAXECPKSigValidCount_Cnt_M_u16	65028
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	37299
DateInvalidTimer_mS_M_u32	2757184256
DiagMuxOnAbsentTimer_mS_M_u32	2153323264
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2718776064
ESPNTCEnableTimer_mS_M_u32	63507200
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	49953
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	12
EffacDefaultDiagTimer_mS_M_u32[1]	16
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	54
ElecIntTimer_mS_M_u32[1]	65
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3583769344
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	34224
EtatMTSigValidCount_Cnt_M_u16	10227
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	64940
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	8867
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	15724
ISDAT4V2BSI552MsgTimer_mS_M_u32	464730880
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	37233
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	23708
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	10227
ISDATBSI3F2MsgTimer_mS_M_u32	2130647808
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	5868
ISDATBSI412MsgLenValidCount_Cnt_M_u16	17415
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	34224
ISDATBSI412MsgTimer_mS_M_u32	3863632640
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	24002
ISDATBSI432MsgLenValidCount_Cnt_M_u16	40405
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	58824
ISDATDIRASentFltAcc_Cnt_M_u16	61900
ISDATDIRASentTimer_mS_M_u32	3616496384
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	3126
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	9585
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	43330
ISDYN2CMMMsgTimer_mS_M_u32	1195051776
ISDYNAASChkSumInvalidCount_Cnt_M_u16	28230
ISDYNAASChkSumValidCount_Cnt_M_u16	46542
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	11076
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	51162
ISDYNAASMsgLenValidCount_Cnt_M_u16	44090
ISDYNAASMsgTimeValidCount_Cnt_M_u16	28230
ISDYNAASMsgTimer_mS_M_u32	4159204096
ISDYNABRChkSumInvalidCount_Cnt_M_u16	61484
ISDYNABRChkSumValidCount_Cnt_M_u16	51963
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	47257
ISDYNABRMsgCountValidCount_Cnt_M_u16	10337
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	36261
ISDYNABRMsgLenValidCount_Cnt_M_u16	60252
ISDYNABRMsgTimeValidCount_Cnt_M_u16	15632
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	63435
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	60494

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	10227
ISDYNCMM208MsgTimer_mS_M_u32	41929472
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	63435
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	60494
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	13591
ISDYNCMM388MsgTimer_mS_M_u32	2700208896
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	6904
ISDYNVOLChkSumValidCount_Cnt_M_u16	57583
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	46869
ISDYNVOLMsgCountValidCount_Cnt_M_u16	30212
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	46030
ISDYNVOLMsgLenValidCount_Cnt_M_u16	58789
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	41486
ISDYNVOLMsgTimer_mS_M_u32	4226394880
IgnOnTimer_mS_M_u32	1957030656
IgnTimeOff_Sec_M_u32	1606078217
ManVehSpd_Kph_M_f32	97.3388977
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	127
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	165
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2616007424
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	190
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2100460288
PrevISDATBSI412MsgDLCError_Cnt_M_u08	201
PrevISDATBSI412MsgRxTime_MSec_M_u32	11021056
PrevISDATBSI432MsgDLCError_Cnt_M_u08	166
PrevISDATBSI432MsgRxTime_MSec_M_u32	2578254592
PrevISDATDIRAMsgTxTime_MSec_M_u32	3349949184
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	56
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2318449408
PrevISDYNAASMsgDLCError_Cnt_M_u08	154
PrevISDYNAASMsgRxTime_MSec_M_u32	3004148480
PrevISDYNABRMsgDLCError_Cnt_M_u08	78
PrevISDYNABRMsgRxTime_MSec_M_u32	205384448
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	247
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1699261184
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	78
PrevISDYNCMM388MsgRxTime_MSec_M_u32	502532864
PrevISDYNVOLMsgDLCError_Cnt_M_u08	34
PrevISDYNVOLMsgRxTime_MSec_M_u32	3818466048
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2985319168
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	81.4832993
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	56192
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	20576
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	20397
VitesseVehicleBVRampValidCount_Cnt_M_u16	31821
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	29424
VitesseVehicleBVSigValidCount_Cnt_M_u16	28311
VitesseVehicleBV_Kph_M_f32	300.01709

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	13591
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	9686
VitesseVehiculeRoues_Kph_M_f32	303.44101
k_AASNTCEnableTimeout_mS_u16	24123
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	10640
k_AASNodeTimeout_mS_u16	20320
k_ABSNodeTimeout_mS_u16	18152
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	31777
k_ANGLEVOLANTSigValidThresh_Cnt_u16	5492
k_AngleVolantInvalidThresh_Cnt_u16	41775
k_AngleVolantValidThresh_Cnt_u16	9763
k_BSI552MsgTimeout_mS_u16	47953
k_BSINTCEnableTimeout_mS_u16	9562
k_BSINodeAbsentDiag_Cnt_str.Threshold	15438
k_BSINodeAbsentDiag_Cnt_str.PStep	55734
k_BSINodeAbsentDiag_Cnt_str.NStep	42803
k_BSINodeAbsentTimeout_mS_u16	18661
k_BSINodeTimeout_mS_u16	58824
k_BattOvHi_Volt_f32	2.0855
k_BattOvLo_Volt_f32	1.2119
k_BattUvHi_Volt_f32	21.6867008
k_BattUvLo_Volt_f32	24.8978004
k_CAVNTCEnableTimeout_mS_u16	53601
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	22009
k_CAVNodeTimeout_mS_u16	32926
k_CMM388MsgTimeout_mS_u16	17900
k_CMM388NTCEnableTimeout_mS_u16	42808
k_CMMNTCEnableTimeout_mS_u16	58633
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	38178
k_CONSANGLECPKMax_HwDeg_f32	166.742493
k_CONSANGLECPKMin_HwDeg_f32	-228.010696
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	62487
k_CONSANGLECPKSigValidThresh_Cnt_u16	9430
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	37870
k_CPKVehicleSpeedValidThresh_Cnt_u16	27699
k_CityParkInputInvalidThresh_Cnt_u16	27450
k_CityParkInputValidThresh_Cnt_u16	13861
k_ComputerRazGCTSigValidThresh_Cnt_u16	35551
k_CptTemporelSigValidThresh_Cnt_u16	11402
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	52389
k_DMDFCTCPKSigValidThresh_Cnt_u16	27228
k_DMDFCTCPKValidCount_Cnt_u16	64766
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	43330
k_DMDRELAXECPKSigValidThresh_Cnt_u16	40945
k_DMDRelaxeConsistentThresh_Cnt_u16	63103
k_DateValidThresh_Cnt_u16	15724
k_DefaultVehSpd_Kph_f32	249.960907
k_DiagMuxOnAbsentTimeout_mS_u16	26574
k_EMNodeTimeout_mS_u16	31379
k_ESPNTCEnableTimeout_mS_u16	37279
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	62858
k_EtatMTSigInvalidThresh_Cnt_u16	4423
k_EtatMTSigValidThresh_Cnt_u16	6742
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	52373
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	59704
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	17490
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	24434
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	22877
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	37024
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	58179
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	61974

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	22902
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	40868
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	3935
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	23132
k_ISDATDIRASentDiag_Cnt_str.Threshold	31074
k_ISDATDIRASentDiag_Cnt_str.PStep	34522
k_ISDATDIRASentDiag_Cnt_str.NStep	11395
k_ISDATDIRASentTimeout_mS_u16	632
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	30229
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	42829
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	23739
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	44844
k_ISDYNAASChkSumValidThresh_Cnt_u16	51707
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	63385
k_ISDYNAASMsgCountValidThresh_Cnt_u16	42849
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	56544
k_ISDYNAASMsgLenValidThresh_Cnt_u16	6164
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	43996
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	60235
k_ISDYNABRChkSumValidThresh_Cnt_u16	22914
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	20118
k_ISDYNABRMsgCountValidThresh_Cnt_u16	55997
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	41230
k_ISDYNABRMsgLenValidThresh_Cnt_u16	545
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	25528
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	50228
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	12121
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	55259
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	32323
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	25130
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	7099
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	22475
k_ISDYNVOLChkSumValidThresh_Cnt_u16	48678
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	40578
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	38575
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	54524
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	38975
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	11050
k_IgnOnTimeout_mS_u16	28183
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	137.250397
k_PowerCutVehSpdLowThresh_Kph_f32	178.602005
k_PowerCutVehSpdLowTimeout_mS_u16	62775
k_VBattMaxAAS_Volt_f32	12.5312996
k_VBattMaxBSI_Volt_f32	13.3325005
k_VBattMaxCAV_Volt_f32	31.1072006
k_VBattMaxCMM388_Volt_f32	4.15719986
k_VBattMaxCMM_Volt_f32	22.9719009
k_VBattMaxESP_Volt_f32	22.6548996
k_VBattMinAAS_Volt_f32	15.8824997
k_VBattMinBSI_Volt_f32	22.6548996
k_VBattMinCAV_Volt_f32	23.6240997
k_VBattMinCMM388_Volt_f32	12.5417995
k_VBattMinCMM_Volt_f32	28.1518993
k_VBattMinESP_Volt_f32	22.9719009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	39047
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	20690
k_VitesseVehicleBVRampValidThresh_Cnt_u16	30229
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	24559
k_VitesseVehicleBVSigValidThresh_Cnt_u16	490
k_VitesseVehicleBVSpeedPassThresh_kph_f32	534.708191
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	10835
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	10099
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2757184256
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	56468
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3742042624
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	78

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	0.412
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1974926080
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	131
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.912679553
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	27781888
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1984793344
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2869111552
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3351825152
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4104022784
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	197
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1501825792
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	511290112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	129
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	141
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	149
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	201
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	218
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	150
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2631256832
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	47
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	82
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	158
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	232
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2660166400
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	76
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2226424576
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3941214976
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	118
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	166
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	186
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	187
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2833021696
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2831
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.174511075
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	450807
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	155.820999
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	13682

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3742042624	3742042624	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3742042624	3742042624	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3742042624	3742042624	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3742042624	3742042624	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3742042624	3742042624	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3742042624	3742042624	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3742042624	3742042624	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	15438	15438	✔
BSINodeAbsentTimer_mS_M_u32	3742042624	3742042624	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3742042624	3742042624	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3742042624	3742042624	✔
CDD_SrlComVehSpd_Kph_G_f32	97.3388977	97.3388977	✔
CMM388NTCEnableTimer_mS_M_u32	3742042624	3742042624	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3742042624	3742042624	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3742042624	3742042624	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	15632	15632	✔
CONSANGLECPK_HwDeg_M_f32	294.34079	294.34079 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3742042624	3742042624	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3742042624	3742042624	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3742042624	3742042624	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3742042624	3742042624	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3742042624	3742042624	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3742042624	3742042624	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3742042624	3742042624	✔
ESPNTCEnableTimer_mS_M_u32	3742042624	3742042624	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3742042624	3742042624	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	12	12	✔
EffacDefaultDiagTimer_mS_M_u32[1]	16	16	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	54	54	✔
ElecIntTimer_mS_M_u32[1]	65	65	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3742042624	3742042624	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	15724	15724	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3742042624	3742042624	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	10227	10227	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3742042624	3742042624	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	34224	34224	✔
ISDATBSI412MsgTimer_mS_M_u32	3742042624	3742042624	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	58824	58824	✔
ISDATBSI432MsgTimer_mS_M_u32	3742042624	3742042624	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3742042624	3742042624	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	43330	43330	✔
ISDYN2CMMMsgTimer_mS_M_u32	3742042624	3742042624	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	28230	28230	✔
ISDYNAASMsgTimer_mS_M_u32	3742042624	3742042624	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	15632	15632	✔
ISDYNABRMsgTimer_mS_M_u32	3742042624	3742042624	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	10227	10227	✔
ISDYNCMM208MsgTimer_mS_M_u32	3742042624	3742042624	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	13591	13591	✔
ISDYNCMM388MsgTimer_mS_M_u32	3742042624	3742042624	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	41486	41486	✔
ISDYNVOLMsgTimer_mS_M_u32	3742042624	3742042624	✔
IgnOnTimer_mS_M_u32	1957030656	1957030656	✔
IgnTimeOff_Sec_M_u32	1606078217	1606078217	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	27781888	27781888	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	110	110	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1984793344	1984793344	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2869111552	2869111552	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	33	33	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3351825152	3351825152	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3349949184	3349949184	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	197	197	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1501825792	1501825792	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	245	245	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	511290112	511290112	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	150	150	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2631256832	2631256832	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	119	119	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2660166400	2660166400	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	76	76	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2226424576	2226424576	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	141	141	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3941214976	3941214976	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2833021696	2833021696	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	81.4832993	81.4832993	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	300.01709	300.01709	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	303.44101	303.44101	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	15632	15632	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1606078217	1606078217	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	294.34079	294.34079 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	97.3388977	97.3388977	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.256 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	501068288
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	2052
AASNodeAbsentTimer_mS_M_u32	2561581568
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	55552
ANGLEVOLANTSigValidCount_Cnt_M_u16	50699
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	60129
AngleVolantMsgTimer_mS_M_u32	501068288
AngleVolantValidCount_Cnt_M_u16	1782
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1295409664
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	629465600
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	734810624
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2955088384
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	29703
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2413056
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	57166
CAVNodeAbsentTimer_mS_M_u32	1622229504
CDD_SrlComVehSpd_Kph_G_f32	327.927185
CMM388NTCEnableTimer_mS_M_u32	2486534656
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2517058048
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	28895
CMMNodeAbsentTimer_mS_M_u32	558699008
CONSANGLECPKSigInvalidCount_Cnt_M_u16	13524
CONSANGLECPKSigValidCount_Cnt_M_u16	7282
CONSANGLECPK_Cnt_M_u16	32601
CONSANGLECPK_HwDeg_M_f32	-301.488586
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	32601
CPKVehicleSpeedMsgTimer_mS_M_u32	1075622400
CPKVehicleSpeedValidCount_Cnt_M_u16	37936
CityParkInputConsistentCount_Cnt_M_u16	42202
CityParkInputInvalidCount_Cnt_M_u16	40415
CityParkInputMsgTimer_mS_M_u32	27781888
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2945622528
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	15336

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1899086336
ComputerRazGCTSigValidCount_Cnt_M_u16	111
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	56315
DMDFCTCPKSigValidCount_Cnt_M_u16	51566
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	32498
DMDRELAXECPKSigValidCount_Cnt_M_u16	23933
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	20657
DateInvalidTimer_mS_M_u32	629465600
DiagMuxOnAbsentTimer_mS_M_u32	2629792256
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2955088384
ESPNTCEnableTimer_mS_M_u32	4264534528
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	38501
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	79
EffacDefaultDiagTimer_mS_M_u32[1]	99
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	101
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3229012480
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	7928
EtatMTSigValidCount_Cnt_M_u16	33007
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	12486
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	55968
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	14532
ISDAT4V2BSI552MsgTimer_mS_M_u32	1529942528
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	38710
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	7796
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	33007
ISDATBSI3F2MsgTimer_mS_M_u32	3100471808
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	964
ISDATBSI412MsgLenValidCount_Cnt_M_u16	9522
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	7928
ISDATBSI412MsgTimer_mS_M_u32	3219894784
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	3523
ISDATBSI432MsgLenValidCount_Cnt_M_u16	54857
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	33775
ISDATDIRASentFltAcc_Cnt_M_u16	28643
ISDATDIRASentTimer_mS_M_u32	1075622400
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	10727
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	1782
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	20610
ISDYN2CMMMsgTimer_mS_M_u32	2077860352
ISDYNAASChkSumInvalidCount_Cnt_M_u16	47606
ISDYNAASChkSumValidCount_Cnt_M_u16	15392
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	381
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	42425
ISDYNAASMsgLenValidCount_Cnt_M_u16	45404
ISDYNAASMsgTimeValidCount_Cnt_M_u16	47606
ISDYNAASMsgTimer_mS_M_u32	1464959488
ISDYNABRChkSumInvalidCount_Cnt_M_u16	454
ISDYNABRChkSumValidCount_Cnt_M_u16	59928
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	59133
ISDYNABRMsgCountValidCount_Cnt_M_u16	61543
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	42203
ISDYNABRMsgLenValidCount_Cnt_M_u16	42101
ISDYNABRMsgTimeValidCount_Cnt_M_u16	32601
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	48461
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	7041
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	33007
ISDYNCMM208MsgTimer_mS_M_u32	1292591616
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	48461
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	7041
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	61444

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1647641088
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	2274
ISDYNVOLChkSumValidCount_Cnt_M_u16	53180
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	13065
ISDYNVOLMsgCountValidCount_Cnt_M_u16	61180
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	47198
ISDYNVOLMsgLenValidCount_Cnt_M_u16	48025
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28895
ISDYNVOLMsgTimer_mS_M_u32	3763192320
IgnOnTimer_mS_M_u32	3071869440
IgnTimeOff_Sec_M_u32	473222303
ManVehSpd_Kph_M_f32	627.86438
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	128
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	178
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2583917056
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	54
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1135825408
PrevISDATBSI412MsgDLCError_Cnt_M_u08	46
PrevISDATBSI412MsgRxTime_MSec_M_u32	3960619520
PrevISDATBSI432MsgDLCError_Cnt_M_u08	245
PrevISDATBSI432MsgRxTime_MSec_M_u32	3431178752
PrevISDATDIRAMsgTxTime_MSec_M_u32	2802205184
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	79
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3854078464
PrevISDYNAASMsgDLCError_Cnt_M_u08	69
PrevISDYNAASMsgRxTime_MSec_M_u32	3537617408
PrevISDYNABRMsgDLCError_Cnt_M_u08	114
PrevISDYNABRMsgRxTime_MSec_M_u32	1347486208
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	150
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3761291776
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	144
PrevISDYNCMM388MsgRxTime_MSec_M_u32	464429568
PrevISDYNVOLMsgDLCError_Cnt_M_u08	70
PrevISDYNVOLMsgRxTime_MSec_M_u32	1195328000
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1962521088
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	37.6787987
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	33479
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	56554
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	6720
VitesseVehicleBVRampValidCount_Cnt_M_u16	19747
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	12793
VitesseVehicleBVSigValidCount_Cnt_M_u16	6084
VitesseVehicleBV_Kph_M_f32	620.406372
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	61444
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	22150
VitesseVehiculeRoues_Kph_M_f32	75.5766983
k_AASNTCEnableTimeout_mS_u16	34776
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	13977
k_AASNodeTimeout_mS_u16	57322
k_ABSNodeTimeout_mS_u16	36752
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	61094
k_ANGLEVOLANTSigValidThresh_Cnt_u16	43884
k_AngleVolantInvalidThresh_Cnt_u16	44603
k_AngleVolantValidThresh_Cnt_u16	40415
k_BSI552MsgTimeout_mS_u16	16917
k_BSINTCEnableTimeout_mS_u16	5883
k_BSINodeAbsentDiag_Cnt_str.Threshold	22338
k_BSINodeAbsentDiag_Cnt_str.PStep	62281
k_BSINodeAbsentDiag_Cnt_str.NStep	20245
k_BSINodeAbsentTimeout_mS_u16	26137
k_BSINodeTimeout_mS_u16	33775
k_BattOvHi_Volt_f32	12.4109001
k_BattOvLo_Volt_f32	7.63660002
k_BattUvHi_Volt_f32	22.4794006
k_BattUvLo_Volt_f32	26.1443996
k_CAVNTCEnableTimeout_mS_u16	5157
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	14172
k_CAVNodeTimeout_mS_u16	61424
k_CMM388MsgTimeout_mS_u16	19204
k_CMM388NTCEnableTimeout_mS_u16	22304
k_CMMNTCEnableTimeout_mS_u16	64622
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	14498
k_CONSANGLECPKMax_HwDeg_f32	112.345001
k_CONSANGLECPKMin_HwDeg_f32	-771.638611
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	45828
k_CONSANGLECPKSigValidThresh_Cnt_u16	22918
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	51776
k_CPKVehicleSpeedValidThresh_Cnt_u16	57327
k_CityParkInputInvalidThresh_Cnt_u16	18588
k_CityParkInputValidThresh_Cnt_u16	42202
k_ComputerRazGCTSigValidThresh_Cnt_u16	58092
k_CptTemporelSigValidThresh_Cnt_u16	59050
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	59355
k_DMDFCTCPKSigValidThresh_Cnt_u16	10101
k_DMDFCTCPKValidCount_Cnt_u16	19407
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	20610
k_DMDRELAXECPKSigValidThresh_Cnt_u16	25909
k_DMDRelaxeConsistentThresh_Cnt_u16	6539
k_DateValidThresh_Cnt_u16	14532
k_DefaultVehSpd_Kph_f32	59.4095001
k_DiagMuxOnAbsentTimeout_mS_u16	30495
k_EMNodeTimeout_mS_u16	5649
k_ESPNTCEnableTimeout_mS_u16	40042
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	46954
k_EtatMTSigInvalidThresh_Cnt_u16	51829
k_EtatMTSigValidThresh_Cnt_u16	10247
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	31819
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	61217
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	28243
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	28979
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	27697
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	26280
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	49472
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	7558
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	60071
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	42909
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	33068
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	1654
k_ISDATDIRASentDiag_Cnt_str.Threshold	16910

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	7039
k_ISDATDIRASentDiag_Cnt_str.NStep	21916
k_ISDATDIRASentTimeout_mS_u16	64226
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	55115
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	60129
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	43798
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	50374
k_ISDYNAASChkSumValidThresh_Cnt_u16	60696
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	10749
k_ISDYNAASMsgCountValidThresh_Cnt_u16	29543
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	2986
k_ISDYNAASMsgLenValidThresh_Cnt_u16	21966
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	34868
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	41961
k_ISDYNABRChkSumValidThresh_Cnt_u16	29187
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	46855
k_ISDYNABRMsgCountValidThresh_Cnt_u16	60242
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	29663
k_ISDYNABRMsgLenValidThresh_Cnt_u16	55653
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	64609
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	39083
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	44669
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	62073
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	7168
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	18699
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	7447
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	32039
k_ISDYNVOLChkSumValidThresh_Cnt_u16	62165
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	51266
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	22268
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	24852
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	24587
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	59274
k_IgnOnTimeout_mS_u16	27203
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	222.040802
k_PowerCutVehSpdLowThresh_Kph_f32	73.9860992
k_PowerCutVehSpdLowTimeout_mS_u16	45796
k_VBattMaxAAS_Volt_f32	21.6116009
k_VBattMaxBSI_Volt_f32	28.0380993
k_VBattMaxCAV_Volt_f32	22.3129005
k_VBattMaxCMM388_Volt_f32	8.86769962
k_VBattMaxCMM_Volt_f32	16.2001991
k_VBattMaxESP_Volt_f32	32
k_VBattMinAAS_Volt_f32	18.8736
k_VBattMinBSI_Volt_f32	32
k_VBattMinCAV_Volt_f32	12.8898001
k_VBattMinCMM388_Volt_f32	30.2169991
k_VBattMinCMM_Volt_f32	32
k_VBattMinESP_Volt_f32	16.2001991
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	47093
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	63444
k_VitesseVehicleBVRampValidThresh_Cnt_u16	62985
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	21180
k_VitesseVehicleBVSigValidThresh_Cnt_u16	38283
k_VitesseVehicleBVSpeedPassThresh_kph_f32	234.888901
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	41550
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	25521
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	629465600
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8161
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	4146439424
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	144
target_SrlComInput_Per1_Batt_Volt_f32.value	20.8006001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	203805184
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	58
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.315090775
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2551382528
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1487020544
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	419512832
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1630560768
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3106898432
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2835259904
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	124
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3097346560
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	34
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	52
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	116
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	172
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	186
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	228
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	17
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1443455488
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	60
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	126
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	156
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	492700160
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	27
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2305630720
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	150
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3041673728
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	88
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	151
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	154
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3904197120
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1240
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0237487257
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	982008
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	66.5791016
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	48369

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4146439424	4146439424	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4146439424	4146439424	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	4146439424	4146439424	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4146439424	4146439424	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4146439424	4146439424	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4146439424	4146439424	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4146439424	4146439424	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	22338	22338	✔
BSINodeAbsentTimer_mS_M_u32	4146439424	4146439424	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4146439424	4146439424	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4146439424	4146439424	✔
CDD_SrlComVehSpd_Kph_G_f32	627.86438	627.86438	✔
CMM388NTCEnableTimer_mS_M_u32	4146439424	4146439424	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4146439424	4146439424	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4146439424	4146439424	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	32601	32601	✔
CONSANGLECPK_HwDeg_M_f32	-301.488586	-301.488586 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4146439424	4146439424	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	4146439424	4146439424	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4146439424	4146439424	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4146439424	4146439424	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4146439424	4146439424	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4146439424	4146439424	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	4146439424	4146439424	✔
ESPNTCEnableTimer_mS_M_u32	4146439424	4146439424	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4146439424	4146439424	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	79	79	✔
EffacDefaultDiagTimer_mS_M_u32[1]	99	99	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	10	10	✔
ElecIntTimer_mS_M_u32[1]	101	101	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	4146439424	4146439424	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	14532	14532	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4146439424	4146439424	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	33007	33007	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4146439424	4146439424	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	7928	7928	✔
ISDATBSI412MsgTimer_mS_M_u32	4146439424	4146439424	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	33775	33775	✔
ISDATBSI432MsgTimer_mS_M_u32	4146439424	4146439424	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	4146439424	4146439424	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	20610	20610	✔
ISDYN2CMMMsgTimer_mS_M_u32	4146439424	4146439424	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	47606	47606	✔
ISDYNAASMsgTimer_mS_M_u32	4146439424	4146439424	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	32601	32601	✔
ISDYNABRMsgTimer_mS_M_u32	4146439424	4146439424	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	33007	33007	✔
ISDYNCMM208MsgTimer_mS_M_u32	4146439424	4146439424	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	61444	61444	✔
ISDYNCMM388MsgTimer_mS_M_u32	4146439424	4146439424	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28895	28895	✔
ISDYNVOLMsgTimer_mS_M_u32	4146439424	4146439424	✔
IgnOnTimer_mS_M_u32	3071869440	3071869440	✔
IgnTimeOff_Sec_M_u32	473222303	473222303	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	37	37	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2551382528	2551382528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	88	88	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1487020544	1487020544	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	200	200	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	419512832	419512832	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	251	251	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1630560768	1630560768	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2802205184	2802205184	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	205	205	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2835259904	2835259904	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	124	124	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3097346560	3097346560	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	17	17	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1443455488	1443455488	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	156	156	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	492700160	492700160	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	27	27	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2305630720	2305630720	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	150	150	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3041673728	3041673728	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3904197120	3904197120	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	37.6787987	37.6787987	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	620.406372	620.406372	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	75.5766983	75.5766983	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	32601	32601	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	473222303	473222303	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-301.488586	-301.488586 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.257 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	927837440
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	13018
AASNodeAbsentTimer_mS_M_u32	1989860608
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	20964
ANGLEVOLANTSigValidCount_Cnt_M_u16	133
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	15939
AngleVolantMsgTimer_mS_M_u32	927837440
AngleVolantValidCount_Cnt_M_u16	9859
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	671325440
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4179107072
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2416037120
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3455945984
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	23759
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	351816960
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	40826
CAVNodeAbsentTimer_mS_M_u32	4044553472
CDD_SrlComVehSpd_Kph_G_f32	362.616302
CMM388NTCEnableTimer_mS_M_u32	3079027968
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	688979200
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	18824
CMMNodeAbsentTimer_mS_M_u32	2726268160
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0
CONSANGLECPKSigValidCount_Cnt_M_u16	18970
CONSANGLECPK_Cnt_M_u16	32665
CONSANGLECPK_HwDeg_M_f32	151.2798
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	32665
CPKVehicleSpeedMsgTimer_mS_M_u32	2358291712
CPKVehicleSpeedValidCount_Cnt_M_u16	7292
CityParkInputConsistentCount_Cnt_M_u16	56535
CityParkInputInvalidCount_Cnt_M_u16	38600
CityParkInputMsgTimer_mS_M_u32	2551382528
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3253656832
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	10030

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1636924672
ComputerRazGCTSigValidCount_Cnt_M_u16	24088
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	19572
DMDFCTCPKSigValidCount_Cnt_M_u16	39388
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	43022
DMDRELAXECPKSigValidCount_Cnt_M_u16	33327
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	40402
DateInvalidTimer_mS_M_u32	4179107072
DiagMuxOnAbsentTimer_mS_M_u32	1906863360
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3455945984
ESPNTCEnableTimer_mS_M_u32	2316819712
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	16052
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	68
EffacDefaultDiagTimer_mS_M_u32[1]	868
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	656
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2617396480
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	13372
EtatMTSigValidCount_Cnt_M_u16	13337
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	37267
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	18884
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	9178
ISDAT4V2BSI552MsgTimer_mS_M_u32	2228456704
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	63748
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	43273
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13337
ISDATBSI3F2MsgTimer_mS_M_u32	3581832448
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	48217
ISDATBSI412MsgLenValidCount_Cnt_M_u16	24014
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	13372
ISDATBSI412MsgTimer_mS_M_u32	153332992
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	732
ISDATBSI432MsgLenValidCount_Cnt_M_u16	3848
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	30103
ISDATDIRASentFltAcc_Cnt_M_u16	33211
ISDATDIRASentTimer_mS_M_u32	2358291712
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	14319
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	9859
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	51935
ISDYN2CMMMsgTimer_mS_M_u32	957996288
ISDYNAASChkSumInvalidCount_Cnt_M_u16	25860
ISDYNAASChkSumValidCount_Cnt_M_u16	54340
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	4846
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	47161
ISDYNAASMsgLenValidCount_Cnt_M_u16	27409
ISDYNAASMsgTimeValidCount_Cnt_M_u16	25860
ISDYNAASMsgTimer_mS_M_u32	3727834368
ISDYNABRChkSumInvalidCount_Cnt_M_u16	9492
ISDYNABRChkSumValidCount_Cnt_M_u16	477
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	47599
ISDYNABRMsgCountValidCount_Cnt_M_u16	37743
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	51540
ISDYNABRMsgLenValidCount_Cnt_M_u16	32837
ISDYNABRMsgTimeValidCount_Cnt_M_u16	32665
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	2897
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	15733
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13337
ISDYNCMM208MsgTimer_mS_M_u32	3162807552
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2897
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	15733
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	9049

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2877799680
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	31039
ISDYNVOLChkSumValidCount_Cnt_M_u16	55920
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	65354
ISDYNVOLMsgCountValidCount_Cnt_M_u16	57650
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	64713
ISDYNVOLMsgLenValidCount_Cnt_M_u16	10458
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	18824
ISDYNVOLMsgTimer_mS_M_u32	2218622208
IgnOnTimer_mS_M_u32	1021033728
IgnTimeOff_Sec_M_u32	638247131
ManVehSpd_Kph_M_f32	364.631195
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	129
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	159
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2312924416
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	171
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2756496640
PrevISDATBSI412MsgDLCError_Cnt_M_u08	111
PrevISDATBSI412MsgRxTime_MSec_M_u32	317717760
PrevISDATBSI432MsgDLCError_Cnt_M_u08	8
PrevISDATBSI432MsgRxTime_MSec_M_u32	1864097024
PrevISDATDIRAMsgTxTime_MSec_M_u32	2987654400
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	195
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1664945408
PrevISDYNAASMsgDLCError_Cnt_M_u08	144
PrevISDYNAASMsgRxTime_MSec_M_u32	1687387392
PrevISDYNABRMsgDLCError_Cnt_M_u08	49
PrevISDYNABRMsgRxTime_MSec_M_u32	1362345216
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	101
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3499392256
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	128
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3986349312
PrevISDYNVOLMsgDLCError_Cnt_M_u08	194
PrevISDYNVOLMsgRxTime_MSec_M_u32	4117298432
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2717494528
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	110.404701
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	55567
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	41063
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	13988
VitesseVehicleBVRampValidCount_Cnt_M_u16	29628
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	27385
VitesseVehicleBVSigValidCount_Cnt_M_u16	12122
VitesseVehicleBV_Kph_M_f32	554.294983
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	9049
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	17810
VitesseVehiculeRoues_Kph_M_f32	510.758789
k_AASNTCEnableTimeout_mS_u16	8732
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	58266
k_AASNodeTimeout_mS_u16	38759
k_ABSNodeTimeout_mS_u16	50613
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	44083
k_ANGLEVOLANTSigValidThresh_Cnt_u16	56223
k_AngleVolantInvalidThresh_Cnt_u16	53042
k_AngleVolantValidThresh_Cnt_u16	38600
k_BSI552MsgTimeout_mS_u16	32485
k_BSINTCEnableTimeout_mS_u16	50996
k_BSINodeAbsentDiag_Cnt_str.Threshold	1780
k_BSINodeAbsentDiag_Cnt_str.PStep	54813
k_BSINodeAbsentDiag_Cnt_str.NStep	30201
k_BSINodeAbsentTimeout_mS_u16	44187
k_BSINodeTimeout_mS_u16	30103
k_BattOvHi_Volt_f32	24.7395992
k_BattOvLo_Volt_f32	28.7474995
k_BattUvHi_Volt_f32	15.4177999
k_BattUvLo_Volt_f32	29.5277996
k_CAVNTCEnableTimeout_mS_u16	52214
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	20304
k_CAVNodeTimeout_mS_u16	31765
k_CMM388MsgTimeout_mS_u16	27098
k_CMM388NTCEnableTimeout_mS_u16	46470
k_CMMNTCEnableTimeout_mS_u16	43356
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	3902
k_CONSANGLECPKMax_HwDeg_f32	660.269775
k_CONSANGLECPKMin_HwDeg_f32	-620.05011
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	55897
k_CONSANGLECPKSigValidThresh_Cnt_u16	15506
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	45157
k_CPKVehicleSpeedValidThresh_Cnt_u16	37848
k_CityParkInputInvalidThresh_Cnt_u16	10386
k_CityParkInputValidThresh_Cnt_u16	56535
k_ComputerRazGCTSigValidThresh_Cnt_u16	28130
k_CptTemporelSigValidThresh_Cnt_u16	43111
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	84
k_DMDFCTCPKSigValidThresh_Cnt_u16	63301
k_DMDFCTCPKValidCount_Cnt_u16	62839
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	51935
k_DMDRELAXECPKSigValidThresh_Cnt_u16	41607
k_DMDRelaxeConsistentThresh_Cnt_u16	23941
k_DateValidThresh_Cnt_u16	9178
k_DefaultVehSpd_Kph_f32	115.172997
k_DiagMuxOnAbsentTimeout_mS_u16	12359
k_EMNodeTimeout_mS_u16	52658
k_ESPNTCEnableTimeout_mS_u16	55334
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	45798
k_EtatMTSigInvalidThresh_Cnt_u16	18183
k_EtatMTSigValidThresh_Cnt_u16	50192
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	34372
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	54145
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	42092
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	40717
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	62418
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	9133
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	7269
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	27985
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	64560
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	5837
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	4065
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	19778
k_ISDATDIRASentDiag_Cnt_str.Threshold	32887

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	20123
k_ISDATDIRASentDiag_Cnt_str.NStep	32507
k_ISDATDIRASentTimeout_mS_u16	43456
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	28355
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	15939
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	23586
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	56340
k_ISDYNAASChkSumValidThresh_Cnt_u16	63709
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	61679
k_ISDYNAASMsgCountValidThresh_Cnt_u16	2671
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	38760
k_ISDYNAASMsgLenValidThresh_Cnt_u16	50619
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	25927
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	33834
k_ISDYNABRChkSumValidThresh_Cnt_u16	53147
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	37839
k_ISDYNABRMsgCountValidThresh_Cnt_u16	27824
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	16520
k_ISDYNABRMsgLenValidThresh_Cnt_u16	30132
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	13699
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	10083
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	57390
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	23482
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	35044
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	30597
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	63776
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	39984
k_ISDYNVOLChkSumValidThresh_Cnt_u16	16613
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	23837
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	19249
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	56808
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	1733
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	44936
k_IgnOnTimeout_mS_u16	17628
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	153.779007
k_PowerCutVehSpdLowThresh_Kph_f32	157.9431
k_PowerCutVehSpdLowTimeout_mS_u16	53496
k_VBattMaxAAS_Volt_f32	9.3380003
k_VBattMaxBSI_Volt_f32	29.5683002
k_VBattMaxCAV_Volt_f32	2.94810009
k_VBattMaxCMM388_Volt_f32	29.1685009
k_VBattMaxCMM_Volt_f32	13.8417997
k_VBattMaxESP_Volt_f32	18.9165001
k_VBattMinAAS_Volt_f32	28.6058998
k_VBattMinBSI_Volt_f32	18.9165001
k_VBattMinCAV_Volt_f32	27.8334007
k_VBattMinCMM388_Volt_f32	23.6117992
k_VBattMinCMM_Volt_f32	0.0693999976
k_VBattMinESP_Volt_f32	13.8417997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	62661
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	64234
k_VitesseVehicleBVRampValidThresh_Cnt_u16	46666
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	20848
k_VitesseVehicleBVSigValidThresh_Cnt_u16	3780
k_VitesseVehicleBVSpeedPassThresh_kph_f32	98.8405991
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	22138
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	59410
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	4179107072
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	28870
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	4009874432
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	128
target_SrlComInput_Per1_Batt_Volt_f32.value	19.6485004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	888491264
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	164
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.880334377
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	32357632
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1690328320
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	159
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	136510720
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	138
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1410702592
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2962767104
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2242567424
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	994934016
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	118
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	119
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	167
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	237
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	428514560
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	114
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	185
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	220
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	197
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1577893120
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	76
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3193920768
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	32
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	524418304
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	50
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	155
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1028050176
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3375
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.872186661
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	402051
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	151.414001
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	21137

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	4009874432	4009874432	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	1780	1780	✔
BSINodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	32665	32665	✔
CONSANGLECPK_HwDeg_M_f32	151.2798	151.2798 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4009874432	4009874432	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	4009874432	4009874432	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4009874432	4009874432	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4009874432	4009874432	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4009874432	4009874432	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4009874432	4009874432	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4009874432	4009874432	✔
ESPNTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	68	68	✔
EffacDefaultDiagTimer_mS_M_u32[1]	868	868	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4009874432	4009874432	✔
ElecIntTimer_mS_M_u32[1]	656	656	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4009874432	4009874432	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	4009874432	4009874432	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4009874432	4009874432	✔
IgnOnTimer_mS_M_u32	4009874432	4009874432	✔
IgnTimeOff_Sec_M_u32	638247131	638247131	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	64	64	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	32357632	32357632	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	169	169	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1690328320	1690328320	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	159	159	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	136510720	136510720	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	138	138	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1410702592	1410702592	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2987654400	2987654400	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	221	221	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2242567424	2242567424	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	994934016	994934016	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	237	237	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	428514560	428514560	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	197	197	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1577893120	1577893120	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	76	76	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3193920768	3193920768	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	32	32	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	524418304	524418304	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1028050176	1028050176	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	110.404701	110.404701	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	554.294983	554.294983	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	510.758789	510.758789	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	32665	32665	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	638247131	638247131	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	151.2798	151.2798 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	115.172997	115.172997	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.258 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3098131456
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	38916
AASNodeAbsentTimer_mS_M_u32	3951176704
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	34020
ANGLEVOLANTSigValidCount_Cnt_M_u16	6082
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	22985
AngleVolantMsgTimer_mS_M_u32	3098131456
AngleVolantValidCount_Cnt_M_u16	60295
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1783098368
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3909774336
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	655186944
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	203037696
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	53283
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2452216832
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	31395
CAVNodeAbsentTimer_mS_M_u32	77188096
CDD_SrlComVehSpd_Kph_G_f32	167.973801
CMM388NTCEnableTimer_mS_M_u32	2386562048
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3567242240
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	24634
CMMNodeAbsentTimer_mS_M_u32	378805248
CONSANGLECPKSigInvalidCount_Cnt_M_u16	65535
CONSANGLECPKSigValidCount_Cnt_M_u16	32260
CONSANGLECPK_Cnt_M_u16	39303
CONSANGLECPK_HwDeg_M_f32	358.071503
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	39303
CPKVehicleSpeedMsgTimer_mS_M_u32	2229320704
CPKVehicleSpeedValidCount_Cnt_M_u16	53411
CityParkInputConsistentCount_Cnt_M_u16	6283

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	64442
CityParkInputMsgTimer_mS_M_u32	32357632
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1501965312
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	2824
ComputerRazGCTSigInvalidTimer_mS_M_u32	3441314816
ComputerRazGCTSigValidCount_Cnt_M_u16	55496
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	35510
DMDFCTCPKSigValidCount_Cnt_M_u16	24892
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	43622
DMDRELAXECPKSigValidCount_Cnt_M_u16	47812
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	34843
DateInvalidTimer_mS_M_u32	3909774336
DiagMuxOnAbsentTimer_mS_M_u32	3835264000
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	203037696
ESPNTCEnableTimer_mS_M_u32	3842714624
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	20339
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	117
EffacDefaultDiagTimer_mS_M_u32[1]	777
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	89
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2769017856
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	49437
EtatMTSigValidCount_Cnt_M_u16	20551
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	61656
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	42758
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	15170
ISDAT4V2BSI552MsgTimer_mS_M_u32	3214416896
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	59973
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	2295
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	20551
ISDATBSI3F2MsgTimer_mS_M_u32	2434235392
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	34117
ISDATBSI412MsgLenValidCount_Cnt_M_u16	36775
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	49437
ISDATBSI412MsgTimer_mS_M_u32	455588864
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	33854
ISDATBSI432MsgLenValidCount_Cnt_M_u16	11895
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	44108
ISDATDIRASentFltAcc_Cnt_M_u16	6112
ISDATDIRASentTimer_mS_M_u32	2229320704
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	18565
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	60295
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	31605
ISDYN2CMMMsgTimer_mS_M_u32	1610951680
ISDYNAASChkSumInvalidCount_Cnt_M_u16	10630
ISDYNAASChkSumValidCount_Cnt_M_u16	64132
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	37446
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	60518
ISDYNAASMsgLenValidCount_Cnt_M_u16	21148
ISDYNAASMsgTimeValidCount_Cnt_M_u16	10630
ISDYNAASMsgTimer_mS_M_u32	3392932864
ISDYNABRChkSumInvalidCount_Cnt_M_u16	8917
ISDYNABRChkSumValidCount_Cnt_M_u16	52027
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	38597
ISDYNABRMsgCountValidCount_Cnt_M_u16	10499
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	36245
ISDYNABRMsgLenValidCount_Cnt_M_u16	18307
ISDYNABRMsgTimeValidCount_Cnt_M_u16	39303
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	30113

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	63735
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	20551
ISDYNCMM208MsgTimer_mS_M_u32	4039437312
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	30113
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	63735
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	52485
ISDYNCMM388MsgTimer_mS_M_u32	2554039296
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	59860
ISDYNVOLChkSumValidCount_Cnt_M_u16	42242
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	18996
ISDYNVOLMsgCountValidCount_Cnt_M_u16	25402
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	43316
ISDYNVOLMsgLenValidCount_Cnt_M_u16	33730
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	24634
ISDYNVOLMsgTimer_mS_M_u32	354044928
IgnOnTimer_mS_M_u32	876579840
IgnTimeOff_Sec_M_u32	1681890388
ManVehSpd_Kph_M_f32	81.8095016
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	130
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1811774464
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	35
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3593231360
PrevISDATBSI412MsgDLCError_Cnt_M_u08	208
PrevISDATBSI412MsgRxTime_MSec_M_u32	1392692224
PrevISDATBSI432MsgDLCError_Cnt_M_u08	61
PrevISDATBSI432MsgRxTime_MSec_M_u32	1174350848
PrevISDATDIRAMsgTxTime_MSec_M_u32	93768704
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	173
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2858130432
PrevISDYNAASMsgDLCError_Cnt_M_u08	60
PrevISDYNAASMsgRxTime_MSec_M_u32	1276660736
PrevISDYNABRMsgDLCError_Cnt_M_u08	221
PrevISDYNABRMsgRxTime_MSec_M_u32	1463258112
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	98
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1276464128
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	250
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2256677888
PrevISDYNVOLMsgDLCError_Cnt_M_u08	10
PrevISDYNVOLMsgRxTime_MSec_M_u32	3482831872
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	681950208
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	355.43869
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	25060
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	35482
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	56613
VitesseVehicleBVRampValidCount_Cnt_M_u16	42139
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	52645
VitesseVehicleBVSigValidCount_Cnt_M_u16	8003

Name	Input Value
VitesseVehicleBV_Kph_M_f32	323.628693
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	52485
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	25883
VitesseVehiculeRoues_Kph_M_f32	237.593994
k_AASNTCEnableTimeout_mS_u16	32254
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	53314
k_AASNodeTimeout_mS_u16	42394
k_ABSNodeTimeout_mS_u16	25331
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	42041
k_ANGLEVOLANTSigValidThresh_Cnt_u16	58546
k_AngleVolantInvalidThresh_Cnt_u16	5625
k_AngleVolantValidThresh_Cnt_u16	64442
k_BSI552MsgTimeout_mS_u16	50466
k_BSINTCEnableTimeout_mS_u16	38710
k_BSINodeAbsentDiag_Cnt_str.Threshold	9785
k_BSINodeAbsentDiag_Cnt_str.PStep	52991
k_BSINodeAbsentDiag_Cnt_str.NStep	54697
k_BSINodeAbsentTimeout_mS_u16	28353
k_BSINodeTimeout_mS_u16	44108
k_BattOvHi_Volt_f32	2.05760002
k_BattOvLo_Volt_f32	20.9785995
k_BattUvHi_Volt_f32	31.5
k_BattUvLo_Volt_f32	12.2266998
k_CAVNTCEnableTimeout_mS_u16	37936
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	17185
k_CAVNodeTimeout_mS_u16	47442
k_CMM388MsgTimeout_mS_u16	62212
k_CMM388NTCEnableTimeout_mS_u16	49152
k_CMMNTCEnableTimeout_mS_u16	14653
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	47127
k_CONSANGLECPKMax_HwDeg_f32	546.986389
k_CONSANGLECPKMin_HwDeg_f32	-200.242294
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	43013
k_CONSANGLECPKSigValidThresh_Cnt_u16	32795
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	53920
k_CPKVehicleSpeedValidThresh_Cnt_u16	47816
k_CityParkInputInvalidThresh_Cnt_u16	36955
k_CityParkInputValidThresh_Cnt_u16	6283
k_ComputerRazGCTSigValidThresh_Cnt_u16	33707
k_CptTemporelSigValidThresh_Cnt_u16	733
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	59541
k_DMDFCTCPKSigValidThresh_Cnt_u16	57987
k_DMDFCTCPKValidCount_Cnt_u16	42539
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	31605
k_DMDRELAXECPKSigValidThresh_Cnt_u16	45883
k_DMDRelaxeConsistentThresh_Cnt_u16	64065
k_DateValidThresh_Cnt_u16	15170
k_DefaultVehSpd_Kph_f32	71.5541
k_DiagMuxOnAbsentTimeout_mS_u16	49021
k_EMNodeTimeout_mS_u16	30843
k_ESPNTCEnableTimeout_mS_u16	32927
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	27935
k_EtatMTSigInvalidThresh_Cnt_u16	18684
k_EtatMTSigValidThresh_Cnt_u16	4258
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	36099
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	46093
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	21964
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	23594
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	35996
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	40777
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	39843

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	30620
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	59458
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	41963
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	10093
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	1930
k_ISDATDIRASentDiag_Cnt_str.Threshold	44024
k_ISDATDIRASentDiag_Cnt_str.PStep	4643
k_ISDATDIRASentDiag_Cnt_str.NStep	50395
k_ISDATDIRASentTimeout_mS_u16	17617
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	59143
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	22985
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	58539
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	64981
k_ISDYNAASChkSumValidThresh_Cnt_u16	58939
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	61893
k_ISDYNAASMsgCountValidThresh_Cnt_u16	50179
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	7129
k_ISDYNAASMsgLenValidThresh_Cnt_u16	27294
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	59322
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	13587
k_ISDYNABRChkSumValidThresh_Cnt_u16	12673
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	11043
k_ISDYNABRMsgCountValidThresh_Cnt_u16	16193
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	31546
k_ISDYNABRMsgLenValidThresh_Cnt_u16	43635
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	61640
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	50920
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	44486
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	25761
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	57316
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	45762
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	13490
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	448
k_ISDYNVOLChkSumValidThresh_Cnt_u16	610
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	55352
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	16191
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	29721
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	34883
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	53304
k_IgnOnTimeout_mS_u16	47036
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	168.236298
k_PowerCutVehSpdLowThresh_Kph_f32	195.744095
k_PowerCutVehSpdLowTimeout_mS_u16	57706
k_VBattMaxAAS_Volt_f32	15.6945
k_VBattMaxBSI_Volt_f32	1.47440004
k_VBattMaxCAV_Volt_f32	14.7228003
k_VBattMaxCMM388_Volt_f32	11.4073
k_VBattMaxCMM_Volt_f32	4.37459993
k_VBattMaxESP_Volt_f32	26.7590008
k_VBattMinAAS_Volt_f32	23.7299995
k_VBattMinBSI_Volt_f32	26.7590008
k_VBattMinCAV_Volt_f32	16.2182999
k_VBattMinCMM388_Volt_f32	17.6037998
k_VBattMinCMM_Volt_f32	4.2809
k_VBattMinESP_Volt_f32	4.37459993
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	56577
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	31059
k_VitesseVehicleBVRampValidThresh_Cnt_u16	9524
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	16386
k_VitesseVehicleBVSigValidThresh_Cnt_u16	30404
k_VitesseVehicleBVSpeedPassThresh_kph_f32	618.95282
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	21923
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	8089
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3909774336
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	23985
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	4142483200
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	250
target_SrlComInput_Per1_Batt_Volt_f32.value	17.0638008
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1714609152
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	41
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.845768273
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2903084032
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2534517760
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4285123584
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	249
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2920410112
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1795820544
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	165
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4266798080
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	803884032
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	9
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	47
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	151
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	183
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	234
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	236
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1907551232
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	174
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	186
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	245
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	236
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3568077824
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3325340672
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	1
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4128033792
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	84
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	188
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	203
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1933466624
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3006
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.941939175
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	232180
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	45.5811996

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	32094		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4142483200	4142483200	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	4142483200	4142483200	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	9785	9785	✔
BSINodeAbsentTimer_mS_M_u32	4142483200	4142483200	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4142483200	4142483200	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4142483200	4142483200	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	39303	39303	✔
CONSANGLECPK_HwDeg_M_f32	358.071503	358.071503 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4142483200	4142483200	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	4142483200	4142483200	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4142483200	4142483200	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4142483200	4142483200	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4142483200	4142483200	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4142483200	4142483200	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4142483200	4142483200	✔
ESPNTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4142483200	4142483200	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	117	117	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	777	777	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4142483200	4142483200	✔
ElecIntTimer_mS_M_u32[1]	89	89	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4142483200	4142483200	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	4142483200	4142483200	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4142483200	4142483200	✔
IgnOnTimer_mS_M_u32	4142483200	4142483200	✔
IgnTimeOff_Sec_M_u32	1681890388	1681890388	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	64	64	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2903084032	2903084032	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	246	246	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2534517760	2534517760	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4285123584	4285123584	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	249	249	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2920410112	2920410112	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	93768704	93768704	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	165	165	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4266798080	4266798080	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	46	46	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	803884032	803884032	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1907551232	1907551232	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	236	236	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3568077824	3568077824	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	74	74	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3325340672	3325340672	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	1	1	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4128033792	4128033792	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1933466624	1933466624	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	355.43869	355.43869	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	323.628693	323.628693	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	237.593994	237.593994	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	39303	39303	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1681890388	1681890388	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	358.071503	358.071503 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.259 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2073136896
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	26498
AASNodeAbsentTimer_mS_M_u32	281558784
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	49888
ANGLEVOLANTSigValidCount_Cnt_M_u16	11782
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	30259
AngleVolantMsgTimer_mS_M_u32	2073136896
AngleVolantValidCount_Cnt_M_u16	57720
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3682008832
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2301591296
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3337006848
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	985689856
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	40227
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2542874368
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	17955
CAVNodeAbsentTimer_mS_M_u32	738287360
CDD_SrlComVehSpd_Kph_G_f32	162.180893
CMM388NTCEnableTimer_mS_M_u32	4161707776
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1408196352
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	59936
CMMNodeAbsentTimer_mS_M_u32	2203217664
CONSANGLECPKSigInvalidCount_Cnt_M_u16	31964
CONSANGLECPKSigValidCount_Cnt_M_u16	12865
CONSANGLECPK_Cnt_M_u16	43960
CONSANGLECPK_HwDeg_M_f32	-762.406799
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43960
CPKVehicleSpeedMsgTimer_mS_M_u32	3001847552
CPKVehicleSpeedValidCount_Cnt_M_u16	64778
CityParkInputConsistentCount_Cnt_M_u16	27244

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	36318
CityParkInputMsgTimer_mS_M_u32	2903084032
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3602661120
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	7798
ComputerRazGCTSigInvalidTimer_mS_M_u32	2222186240
ComputerRazGCTSigValidCount_Cnt_M_u16	23989
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	53482
DMDFCTCPKSigValidCount_Cnt_M_u16	4377
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	55898
DMDRELAXECPKSigValidCount_Cnt_M_u16	52480
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	1084
DateInvalidTimer_mS_M_u32	2301591296
DiagMuxOnAbsentTimer_mS_M_u32	1724010240
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	985689856
ESPNTCEnableTimer_mS_M_u32	2284666624
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	45106
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	555
EffacDefaultDiagTimer_mS_M_u32[1]	5555
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	79
ElecIntTimer_mS_M_u32[1]	700
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1726689024
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	25718
EtatMTSigValidCount_Cnt_M_u16	2745
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	65029
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	16187
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	6919
ISDAT4V2BSI552MsgTimer_mS_M_u32	2554752768
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	33405
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	39463
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	2745
ISDATBSI3F2MsgTimer_mS_M_u32	3645394688
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	636
ISDATBSI412MsgLenValidCount_Cnt_M_u16	5911
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	25718
ISDATBSI412MsgTimer_mS_M_u32	3424096000
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	36372
ISDATBSI432MsgLenValidCount_Cnt_M_u16	8998
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	38184
ISDATDIRASentFltAcc_Cnt_M_u16	41580
ISDATDIRASentTimer_mS_M_u32	3001847552
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	5822
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	57720
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	47789
ISDYN2CMMMsgTimer_mS_M_u32	2134851328
ISDYNAASChkSumInvalidCount_Cnt_M_u16	15100
ISDYNAASChkSumValidCount_Cnt_M_u16	27586
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	43323
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	48346
ISDYNAASMsgLenValidCount_Cnt_M_u16	3576
ISDYNAASMsgTimeValidCount_Cnt_M_u16	15100
ISDYNAASMsgTimer_mS_M_u32	874159872
ISDYNABRChkSumInvalidCount_Cnt_M_u16	41615
ISDYNABRChkSumValidCount_Cnt_M_u16	60701
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	44863
ISDYNABRMsgCountValidCount_Cnt_M_u16	40005
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	23502
ISDYNABRMsgLenValidCount_Cnt_M_u16	37316
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43960
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	43421

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	53851
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	2745
ISDYNCMM208MsgTimer_mS_M_u32	2080374528
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	43421
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	53851
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	46334
ISDYNCMM388MsgTimer_mS_M_u32	672931584
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	785
ISDYNVOLChkSumValidCount_Cnt_M_u16	13639
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	2672
ISDYNVOLMsgCountValidCount_Cnt_M_u16	33567
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	59119
ISDYNVOLMsgLenValidCount_Cnt_M_u16	15109
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	59936
ISDYNVOLMsgTimer_mS_M_u32	2625625856
IgnOnTimer_mS_M_u32	1678778112
IgnTimeOff_Sec_M_u32	2494860398
ManVehSpd_Kph_M_f32	4.69259977
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	131
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	218
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1620463360
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	225
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4119441152
PrevISDATBSI412MsgDLCError_Cnt_M_u08	245
PrevISDATBSI412MsgRxTime_MSec_M_u32	616980224
PrevISDATBSI432MsgDLCError_Cnt_M_u08	7
PrevISDATBSI432MsgRxTime_MSec_M_u32	894516992
PrevISDATDIRAMsgTxTime_MSec_M_u32	1560960768
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	210
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1174138624
PrevISDYNAASMsgDLCError_Cnt_M_u08	67
PrevISDYNAASMsgRxTime_MSec_M_u32	1871044352
PrevISDYNABRMsgDLCError_Cnt_M_u08	209
PrevISDYNABRMsgRxTime_MSec_M_u32	3676839680
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	224
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2744049408
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	93
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1070087936
PrevISDYNVOLMsgDLCError_Cnt_M_u08	170
PrevISDYNVOLMsgRxTime_MSec_M_u32	1124556544
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	463310592
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	650.955688
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	54368
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	56830
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	42653
VitesseVehicleBVRampValidCount_Cnt_M_u16	54267
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	11421
VitesseVehicleBVSigValidCount_Cnt_M_u16	23427

Name	Input Value
VitesseVehicleBV_Kph_M_f32	128.503098
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	46334
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	61564
VitesseVehiculeRoues_Kph_M_f32	380.197601
k_AASNTCEnableTimeout_mS_u16	39507
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	57159
k_AASNodeTimeout_mS_u16	36094
k_ABSNodeTimeout_mS_u16	31795
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	55843
k_ANGLEVOLANTSigValidThresh_Cnt_u16	44149
k_AngleVolantInvalidThresh_Cnt_u16	62624
k_AngleVolantValidThresh_Cnt_u16	36318
k_BSI552MsgTimeout_mS_u16	44135
k_BSINTCEnableTimeout_mS_u16	13612
k_BSINodeAbsentDiag_Cnt_str.Threshold	44374
k_BSINodeAbsentDiag_Cnt_str.PStep	28739
k_BSINodeAbsentDiag_Cnt_str.NStep	43397
k_BSINodeAbsentTimeout_mS_u16	5963
k_BSINodeTimeout_mS_u16	38184
k_BattOvHi_Volt_f32	17.0352993
k_BattOvLo_Volt_f32	29.9377003
k_BattUvHi_Volt_f32	16.5471992
k_BattUvLo_Volt_f32	10.4266996
k_CAVNTCEnableTimeout_mS_u16	7292
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	25769
k_CAVNodeTimeout_mS_u16	3223
k_CMM388MsgTimeout_mS_u16	22146
k_CMM388NTCEnableTimeout_mS_u16	57230
k_CMMNTCEnableTimeout_mS_u16	30101
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	59272
k_CONSANGLECPKMax_HwDeg_f32	737.300598
k_CONSANGLECPKMin_HwDeg_f32	-422.447906
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	9214
k_CONSANGLECPKSigValidThresh_Cnt_u16	40828
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	40428
k_CPKVehicleSpeedValidThresh_Cnt_u16	11763
k_CityParkInputInvalidThresh_Cnt_u16	61949
k_CityParkInputValidThresh_Cnt_u16	27244
k_ComputerRazGCTSigValidThresh_Cnt_u16	52811
k_CptTemporelSigValidThresh_Cnt_u16	50293
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	19150
k_DMDFCTCPKSigValidThresh_Cnt_u16	49348
k_DMDFCTCPKValidCount_Cnt_u16	15115
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	47789
k_DMDRELAXECPKSigValidThresh_Cnt_u16	55068
k_DMDRelaxeConsistentThresh_Cnt_u16	39434
k_DateValidThresh_Cnt_u16	6919
k_DefaultVehSpd_Kph_f32	7.39519978
k_DiagMuxOnAbsentTimeout_mS_u16	37334
k_EMNodeTimeout_mS_u16	45852
k_ESPNTCEnableTimeout_mS_u16	9263
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	59504
k_EtatMTSigInvalidThresh_Cnt_u16	35866
k_EtatMTSigValidThresh_Cnt_u16	30952
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	47811
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	6501
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	63145
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	206
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	58168
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	50288
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	7141

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	7095
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	29192
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	7308
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	17862
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	56496
k_ISDATDIRASentDiag_Cnt_str.Threshold	25921
k_ISDATDIRASentDiag_Cnt_str.PStep	8439
k_ISDATDIRASentDiag_Cnt_str.NStep	40264
k_ISDATDIRASentTimeout_mS_u16	11419
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	29241
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	30259
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10251
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	4495
k_ISDYNAASChkSumValidThresh_Cnt_u16	39965
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	40511
k_ISDYNAASMsgCountValidThresh_Cnt_u16	52037
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	51075
k_ISDYNAASMsgLenValidThresh_Cnt_u16	19954
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	50013
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	56660
k_ISDYNABRChkSumValidThresh_Cnt_u16	19402
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	35875
k_ISDYNABRMsgCountValidThresh_Cnt_u16	29577
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	39200
k_ISDYNABRMsgLenValidThresh_Cnt_u16	40754
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	15092
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	46420
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	52473
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	11241
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	45536
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	23814
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	49910
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	14603
k_ISDYNVOLChkSumValidThresh_Cnt_u16	27366
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	27107
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	41233
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	15234
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	21189
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	46117
k_IgnOnTimeout_mS_u16	1815
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	103.8489
k_PowerCutVehSpdLowThresh_Kph_f32	157.325394
k_PowerCutVehSpdLowTimeout_mS_u16	8207
k_VBattMaxAAS_Volt_f32	11.7051001
k_VBattMaxBSI_Volt_f32	13.9534998
k_VBattMaxCAV_Volt_f32	9.04520035
k_VBattMaxCMM388_Volt_f32	23.9545002
k_VBattMaxCMM_Volt_f32	6.09079981
k_VBattMaxESP_Volt_f32	24.1121998
k_VBattMinAAS_Volt_f32	21.0820999
k_VBattMinBSI_Volt_f32	24.1121998
k_VBattMinCAV_Volt_f32	7.10459995
k_VBattMinCMM388_Volt_f32	3.78579998
k_VBattMinCMM_Volt_f32	31.6053009
k_VBattMinESP_Volt_f32	6.09079981
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	63563
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	5909
k_VitesseVehicleBVRampValidThresh_Cnt_u16	31088
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	25671
k_VitesseVehicleBVSigValidThresh_Cnt_u16	29633
k_VitesseVehicleBVSpeedPassThresh_kph_f32	486.628387
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	46371
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	56065
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2301591296
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	26653
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	12512768
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	93
target_SrlComInput_Per1_Batt_Volt_f32.value	0.940900028
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2138451712
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	1
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.799671412
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	249
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2712805120
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2887368448
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	120
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2073124608
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3088645888
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	162569984
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	22
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	408436480
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2349850368
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	39
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	130
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	131
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	242
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	825622272
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	71
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	122
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	236
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	238
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1992892160
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	82
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1789968128
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3819462400
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	22
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	124
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	173
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3864243968
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	661
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.220094502
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	640169
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	93.0639038

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	59890		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	12512768	12512768	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	12512768	12512768	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	12512768	12512768	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	12512768	12512768	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	12512768	12512768	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	12512768	12512768	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	12512768	12512768	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	44374	44374	✔
BSINodeAbsentTimer_mS_M_u32	12512768	12512768	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	12512768	12512768	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	12512768	12512768	✔
CDD_SrlComVehSpd_Kph_G_f32	4.69259977	4.69259977	✔
CMM388NTCEnableTimer_mS_M_u32	12512768	12512768	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	12512768	12512768	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	12512768	12512768	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	43960	43960	✔
CONSANGLECPK_HwDeg_M_f32	-762.406799	-762.406799 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	12512768	12512768	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	12512768	12512768	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	12512768	12512768	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	12512768	12512768	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	12512768	12512768	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	12512768	12512768	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	12512768	12512768	✔
ESPNTCEnableTimer_mS_M_u32	12512768	12512768	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	12512768	12512768	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	555	555	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	5555	5555	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	79	79	✔
ElecIntTimer_mS_M_u32[1]	700	700	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	12512768	12512768	✔
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	6919	6919	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	12512768	12512768	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	2745	2745	✔
ISDATBSI3F2MsgTimer_mS_M_u32	12512768	12512768	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	25718	25718	✔
ISDATBSI412MsgTimer_mS_M_u32	12512768	12512768	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	38184	38184	✔
ISDATBSI432MsgTimer_mS_M_u32	12512768	12512768	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	12512768	12512768	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	47789	47789	✔
ISDYN2CMMMsgTimer_mS_M_u32	12512768	12512768	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	15100	15100	✔
ISDYNAASMsgTimer_mS_M_u32	12512768	12512768	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43960	43960	✔
ISDYNABRMsgTimer_mS_M_u32	12512768	12512768	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	2745	2745	✔
ISDYNCMM208MsgTimer_mS_M_u32	12512768	12512768	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	46334	46334	✔
ISDYNCMM388MsgTimer_mS_M_u32	12512768	12512768	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	59936	59936	✔
ISDYNVOLMsgTimer_mS_M_u32	12512768	12512768	✔
IgnOnTimer_mS_M_u32	1678778112	1678778112	✔
IgnTimeOff_Sec_M_u32	2494860398	2494860398	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	249	249	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2712805120	2712805120	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	0	0	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2887368448	2887368448	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	120	120	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2073124608	2073124608	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	9	9	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3088645888	3088645888	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1560960768	1560960768	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	22	22	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	408436480	408436480	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2349850368	2349850368	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	14	14	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	825622272	825622272	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1992892160	1992892160	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	82	82	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1789968128	1789968128	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3819462400	3819462400	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3864243968	3864243968	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	650.955688	650.955688	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	128.503098	128.503098	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	380.197601	380.197601	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	43960	43960	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2494860398	2494860398	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-762.406799	-762.406799 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	4.69259977	4.69259977	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.260 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1306924544
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	60436
AASNodeAbsentTimer_mS_M_u32	84018688
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	29689
ANGLEVOLANTSigValidCount_Cnt_M_u16	51014
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	50177
AngleVolantMsgTimer_mS_M_u32	1306924544
AngleVolantValidCount_Cnt_M_u16	8368
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3488990720
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1221346816
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2825303552
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3822679552
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	45360
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	6764032
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	48305
CAVNodeAbsentTimer_mS_M_u32	2144773632
CDD_SrlComVehSpd_Kph_G_f32	595.019897
CMM388NTCEnableTimer_mS_M_u32	3769558528
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1074570752
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	53880
CMMNodeAbsentTimer_mS_M_u32	3525539328
CONSANGLECPKSigInvalidCount_Cnt_M_u16	60920
CONSANGLECPKSigValidCount_Cnt_M_u16	5526
CONSANGLECPK_Cnt_M_u16	17713
CONSANGLECPK_HwDeg_M_f32	-681.22522
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17713
CPKVehicleSpeedMsgTimer_mS_M_u32	3553957376
CPKVehicleSpeedValidCount_Cnt_M_u16	3394
CityParkInputConsistentCount_Cnt_M_u16	21972
CityParkInputInvalidCount_Cnt_M_u16	33917
CityParkInputMsgTimer_mS_M_u32	2712805120
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2200307200
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	38712

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1618945536
ComputerRazGCTSigValidCount_Cnt_M_u16	57337
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	60249
DMDFCTCPKSigValidCount_Cnt_M_u16	0
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	38283
DMDRELAXECPKSigValidCount_Cnt_M_u16	21080
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	52965
DateInvalidTimer_mS_M_u32	1221346816
DiagMuxOnAbsentTimer_mS_M_u32	1062458880
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3822679552
ESPNTCEnableTimer_mS_M_u32	1926432256
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	50434
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	963
EffacDefaultDiagTimer_mS_M_u32[1]	7852
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	37
ElecIntTimer_mS_M_u32[1]	87
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2052666880
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	35958
EtatMTSigValidCount_Cnt_M_u16	40559
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	17802
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	22184
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	63941
ISDAT4V2BSI552MsgTimer_mS_M_u32	1665627648
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	26081
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	50082
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	40559
ISDATBSI3F2MsgTimer_mS_M_u32	2143409664
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	62179
ISDATBSI412MsgLenValidCount_Cnt_M_u16	6613
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	35958
ISDATBSI412MsgTimer_mS_M_u32	4099151360
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	46748
ISDATBSI432MsgLenValidCount_Cnt_M_u16	15398
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	9122
ISDATDIRASentFltAcc_Cnt_M_u16	3030
ISDATDIRASentTimer_mS_M_u32	3553957376
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	39967
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	8368
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	64016
ISDYN2CMMMsgTimer_mS_M_u32	1436354048
ISDYNAASChkSumInvalidCount_Cnt_M_u16	55718
ISDYNAASChkSumValidCount_Cnt_M_u16	23572
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	38247
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	62604
ISDYNAASMsgLenValidCount_Cnt_M_u16	30193
ISDYNAASMsgTimeValidCount_Cnt_M_u16	55718
ISDYNAASMsgTimer_mS_M_u32	1552606720
ISDYNABRChkSumInvalidCount_Cnt_M_u16	43116
ISDYNABRChkSumValidCount_Cnt_M_u16	64897
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	18653
ISDYNABRMsgCountValidCount_Cnt_M_u16	38539
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	36911
ISDYNABRMsgLenValidCount_Cnt_M_u16	49933
ISDYNABRMsgTimeValidCount_Cnt_M_u16	17713
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	25831
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	53866
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	40559
ISDYNCMM208MsgTimer_mS_M_u32	1381680640
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	25831
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	53866
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	15902

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1720083968
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	26214
ISDYNVOLChkSumValidCount_Cnt_M_u16	42116
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	54983
ISDYNVOLMsgCountValidCount_Cnt_M_u16	8573
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	21707
ISDYNVOLMsgLenValidCount_Cnt_M_u16	44360
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	53880
ISDYNVOLMsgTimer_mS_M_u32	1213933056
IgnOnTimer_mS_M_u32	2192205312
IgnTimeOff_Sec_M_u32	765724022
ManVehSpd_Kph_M_f32	346.408112
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	133
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	35
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2715276800
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	37
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1753069056
PrevISDATBSI412MsgDLCError_Cnt_M_u08	156
PrevISDATBSI412MsgRxTime_MSec_M_u32	3917981184
PrevISDATBSI432MsgDLCError_Cnt_M_u08	92
PrevISDATBSI432MsgRxTime_MSec_M_u32	4217832960
PrevISDATDIRAMsgTxTime_MSec_M_u32	1354475008
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	171
PrevISDYN2CMMMsgRxTime_MSec_M_u32	270988800
PrevISDYNAASMsgDLCError_Cnt_M_u08	248
PrevISDYNAASMsgRxTime_MSec_M_u32	1732847104
PrevISDYNABRMsgDLCError_Cnt_M_u08	3
PrevISDYNABRMsgRxTime_MSec_M_u32	2103600640
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	244
PrevISDYNCMM208MsgRxTime_MSec_M_u32	791553536
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	181
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2013398528
PrevISDYNVOLMsgDLCError_Cnt_M_u08	85
PrevISDYNVOLMsgRxTime_MSec_M_u32	3536102912
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2646742528
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	569.566895
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	17914
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	40415
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	835
VitesseVehicleBVRampValidCount_Cnt_M_u16	61416
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	27330
VitesseVehicleBVSigValidCount_Cnt_M_u16	29391
VitesseVehicleBV_Kph_M_f32	52.5323982
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	15902
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	32868
VitesseVehiculeRoues_Kph_M_f32	629.357422
k_AASNTCEnableTimeout_mS_u16	42336
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	9027
k_AASNodeTimeout_mS_u16	37087
k_ABSNodeTimeout_mS_u16	19838
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	52847
k_ANGLEVOLANTSigValidThresh_Cnt_u16	39993
k_AngleVolantInvalidThresh_Cnt_u16	12216
k_AngleVolantValidThresh_Cnt_u16	33917
k_BSI552MsgTimeout_mS_u16	47267
k_BSINTCEnableTimeout_mS_u16	8532
k_BSINodeAbsentDiag_Cnt_str.Threshold	6458
k_BSINodeAbsentDiag_Cnt_str.PStep	39090
k_BSINodeAbsentDiag_Cnt_str.NStep	1327
k_BSINodeAbsentTimeout_mS_u16	16569
k_BSINodeTimeout_mS_u16	9122
k_BattOvHi_Volt_f32	31.5
k_BattOvLo_Volt_f32	11.5724001
k_BattUvHi_Volt_f32	21.8780994
k_BattUvLo_Volt_f32	12.4048996
k_CAVNTCEnableTimeout_mS_u16	53411
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	63775
k_CAVNodeTimeout_mS_u16	57812
k_CMM388MsgTimeout_mS_u16	7956
k_CMM388NTCEnableTimeout_mS_u16	46064
k_CMMNTCEnableTimeout_mS_u16	60569
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	52032
k_CONSANGLECPKMax_HwDeg_f32	566.15332
k_CONSANGLECPKMin_HwDeg_f32	-573.297424
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	61726
k_CONSANGLECPKSigValidThresh_Cnt_u16	29540
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	38421
k_CPKVehicleSpeedValidThresh_Cnt_u16	3198
k_CityParkInputInvalidThresh_Cnt_u16	61986
k_CityParkInputValidThresh_Cnt_u16	21972
k_ComputerRazGCTSigValidThresh_Cnt_u16	14967
k_CptTemporelSigValidThresh_Cnt_u16	64696
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	49967
k_DMDFCTCPKSigValidThresh_Cnt_u16	13837
k_DMDFCTCPKValidCount_Cnt_u16	30584
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	64016
k_DMDRELAXECPKSigValidThresh_Cnt_u16	22918
k_DMDRelaxeConsistentThresh_Cnt_u16	18620
k_DateValidThresh_Cnt_u16	63941
k_DefaultVehSpd_Kph_f32	0.918799996
k_DiagMuxOnAbsentTimeout_mS_u16	35543
k_EMNodeTimeout_mS_u16	16965
k_ESPNTCEnableTimeout_mS_u16	21133
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	26760
k_EtatMTSigInvalidThresh_Cnt_u16	55243
k_EtatMTSigValidThresh_Cnt_u16	17952
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	23440
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	50282
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	58653
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	28398
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	27759
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	32007
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	37161
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	54899
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	56000
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	17077
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	43974
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	16714
k_ISDATDIRASentDiag_Cnt_str.Threshold	46594

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	38967
k_ISDATDIRASentDiag_Cnt_str.NStep	17884
k_ISDATDIRASentTimeout_mS_u16	14920
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	58543
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	50177
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	46841
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	23404
k_ISDYNAASChkSumValidThresh_Cnt_u16	61569
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	31709
k_ISDYNAASMsgCountValidThresh_Cnt_u16	2443
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	2448
k_ISDYNAASMsgLenValidThresh_Cnt_u16	7683
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	63361
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	41885
k_ISDYNABRChkSumValidThresh_Cnt_u16	11515
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	58416
k_ISDYNABRMsgCountValidThresh_Cnt_u16	49853
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	50552
k_ISDYNABRMsgLenValidThresh_Cnt_u16	63490
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	55420
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	29470
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	51052
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	8222
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	42745
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	14918
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	17717
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	19254
k_ISDYNVOLChkSumValidThresh_Cnt_u16	6760
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	39919
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	45477
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	14162
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	63051
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	9835
k_IgnOnTimeout_mS_u16	4370
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	88.0579987
k_PowerCutVehSpdLowThresh_Kph_f32	31.6282997
k_PowerCutVehSpdLowTimeout_mS_u16	1068
k_VBattMaxAAS_Volt_f32	9.37069988
k_VBattMaxBSI_Volt_f32	24.8619995
k_VBattMaxCAV_Volt_f32	1.07630002
k_VBattMaxCMM388_Volt_f32	7.45949984
k_VBattMaxCMM_Volt_f32	12.9364004
k_VBattMaxESP_Volt_f32	0.347799987
k_VBattMinAAS_Volt_f32	12.7895002
k_VBattMinBSI_Volt_f32	0.347799987
k_VBattMinCAV_Volt_f32	32
k_VBattMinCMM388_Volt_f32	6.70289993
k_VBattMinCMM_Volt_f32	25.6928005
k_VBattMinESP_Volt_f32	12.9364004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	6777
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	58074
k_VitesseVehicleBVRampValidThresh_Cnt_u16	35271
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	6020
k_VitesseVehicleBVSigValidThresh_Cnt_u16	52693
k_VitesseVehicleBVSpeedPassThresh_kph_f32	496.583588
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	28593
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	29398
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1221346816
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	34134
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2929326336
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	181
target_SrlComInput_Per1_Batt_Volt_f32.value	22.9403992
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	481834496
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	49
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.742503226
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3519309312
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	255
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1494058496
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3508971008
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1108329984
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3016287744
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	87
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	777127424
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	185
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3115001344
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	28
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	46
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	58
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	98
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	179
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	189
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	87
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2327365120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	39
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	161
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	228
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1853842944
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	961054208
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3034686976
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	15
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	157
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	215
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1042265600
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3666
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.412548542
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	106695
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	232.662704
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	52548

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2929326336	2929326336	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2929326336	2929326336	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2929326336	2929326336	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2929326336	2929326336	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2929326336	2929326336	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2929326336	2929326336	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2929326336	2929326336	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	6458	6458	✔
BSINodeAbsentTimer_mS_M_u32	2929326336	2929326336	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2929326336	2929326336	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2929326336	2929326336	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2929326336	2929326336	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2929326336	2929326336	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2929326336	2929326336	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	17713	17713	✔
CONSANGLECPK_HwDeg_M_f32	-681.22522	-681.22522 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2929326336	2929326336	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2929326336	2929326336	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2929326336	2929326336	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2929326336	2929326336	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2929326336	2929326336	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2929326336	2929326336	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2929326336	2929326336	✔
ESPNTCEnableTimer_mS_M_u32	2929326336	2929326336	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2929326336	2929326336	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	963	963	✔
EffacDefaultDiagTimer_mS_M_u32[1]	7852	7852	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2929326336	2929326336	✔
ElecIntTimer_mS_M_u32[1]	87	87	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2929326336	2929326336	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2929326336	2929326336	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2929326336	2929326336	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2929326336	2929326336	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2929326336	2929326336	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2929326336	2929326336	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2929326336	2929326336	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2929326336	2929326336	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2929326336	2929326336	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2929326336	2929326336	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2929326336	2929326336	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2929326336	2929326336	✔
IgnOnTimer_mS_M_u32	2192205312	2192205312	✔
IgnTimeOff_Sec_M_u32	765724022	765724022	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	141	141	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3519309312	3519309312	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	255	255	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1494058496	1494058496	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3508971008	3508971008	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	178	178	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1108329984	1108329984	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1354475008	1354475008	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	87	87	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	777127424	777127424	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	185	185	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3115001344	3115001344	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	87	87	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2327365120	2327365120	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	208	208	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1853842944	1853842944	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	961054208	961054208	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	40	40	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3034686976	3034686976	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1042265600	1042265600	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	569.566895	569.566895	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	52.5323982	52.5323982	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	629.357422	629.357422	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	17713	17713	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	765724022	765724022	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-681.22522	-681.22522 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.261 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3049554176
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	46393
AASNodeAbsentTimer_mS_M_u32	741388544
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	20363
ANGLEVOLANTSigValidCount_Cnt_M_u16	38755
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	8562
AngleVolantMsgTimer_mS_M_u32	3049554176
AngleVolantValidCount_Cnt_M_u16	12260
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1247113472
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1506930944
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	4039287040
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2037014784
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	13286
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2327912704
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	64995
CAVNodeAbsentTimer_mS_M_u32	1446170880
CDD_SrlComVehSpd_Kph_G_f32	142.205505
CMM388NTCEnableTimer_mS_M_u32	3836350720
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1838207232
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	46924
CMMNodeAbsentTimer_mS_M_u32	1452040448
CONSANGLECPKSigInvalidCount_Cnt_M_u16	37004
CONSANGLECPKSigValidCount_Cnt_M_u16	39795
CONSANGLECPK_Cnt_M_u16	14498
CONSANGLECPK_HwDeg_M_f32	-157.322906
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	14498
CPKVehicleSpeedMsgTimer_mS_M_u32	2683797760
CPKVehicleSpeedValidCount_Cnt_M_u16	52312
CityParkInputConsistentCount_Cnt_M_u16	8312

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	51580
CityParkInputMsgTimer_mS_M_u32	3519309312
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1103409408
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	17357
ComputerRazGCTSigInvalidTimer_mS_M_u32	4130951424
ComputerRazGCTSigValidCount_Cnt_M_u16	22025
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	1256
DMDFCTCPKSigValidCount_Cnt_M_u16	65535
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	45781
DMDRELAXECPKSigValidCount_Cnt_M_u16	48685
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	57797
DateInvalidTimer_mS_M_u32	1506930944
DiagMuxOnAbsentTimer_mS_M_u32	3363520768
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2037014784
ESPNTCEnableTimer_mS_M_u32	1723707648
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	4463
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	200
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	5
ElecIntTimer_mS_M_u32[1]	156
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1693131008
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	3668
EtatMTSigValidCount_Cnt_M_u16	51752
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	20950
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	41021
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	4966
ISDAT4V2BSI552MsgTimer_mS_M_u32	857760000
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	59282
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	57357
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	51752
ISDATBSI3F2MsgTimer_mS_M_u32	1060192512
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	6539
ISDATBSI412MsgLenValidCount_Cnt_M_u16	30327
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	3668
ISDATBSI412MsgTimer_mS_M_u32	4202332416
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	39648
ISDATBSI432MsgLenValidCount_Cnt_M_u16	15363
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	52496
ISDATDIRASentFltAcc_Cnt_M_u16	58484
ISDATDIRASentTimer_mS_M_u32	2683797760
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	27608
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	12260
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	29891
ISDYN2CMMMsgTimer_mS_M_u32	1717547264
ISDYNAASChkSumInvalidCount_Cnt_M_u16	46211
ISDYNAASChkSumValidCount_Cnt_M_u16	61178
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	28095
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	33362
ISDYNAASMsgLenValidCount_Cnt_M_u16	40929
ISDYNAASMsgTimeValidCount_Cnt_M_u16	46211
ISDYNAASMsgTimer_mS_M_u32	3776319744
ISDYNABRChkSumInvalidCount_Cnt_M_u16	14257
ISDYNABRChkSumValidCount_Cnt_M_u16	39473
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	734
ISDYNABRMsgCountValidCount_Cnt_M_u16	56213
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	17895
ISDYNABRMsgLenValidCount_Cnt_M_u16	12046
ISDYNABRMsgTimeValidCount_Cnt_M_u16	14498
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	7507

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	7562
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	51752
ISDYNCMM208MsgTimer_mS_M_u32	2535878912
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	7507
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	7562
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	3994
ISDYNCMM388MsgTimer_mS_M_u32	287543552
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	24386
ISDYNVOLChkSumValidCount_Cnt_M_u16	9897
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	31390
ISDYNVOLMsgCountValidCount_Cnt_M_u16	31806
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	50708
ISDYNVOLMsgLenValidCount_Cnt_M_u16	48732
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	46924
ISDYNVOLMsgTimer_mS_M_u32	2930069760
IgnOnTimer_mS_M_u32	1287098624
IgnTimeOff_Sec_M_u32	1235889189
ManVehSpd_Kph_M_f32	425.911011
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	134
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	100
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2968469760
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	17
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3430785280
PrevISDATBSI412MsgDLCError_Cnt_M_u08	143
PrevISDATBSI412MsgRxTime_MSec_M_u32	488624384
PrevISDATBSI432MsgDLCError_Cnt_M_u08	119
PrevISDATBSI432MsgRxTime_MSec_M_u32	486650112
PrevISDATDIRAMsgTxTime_MSec_M_u32	3078869248
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	115
PrevISDYN2CMMMsgRxTime_MSec_M_u32	176283904
PrevISDYNAASMsgDLCError_Cnt_M_u08	173
PrevISDYNAASMsgRxTime_MSec_M_u32	2312851712
PrevISDYNABRMsgDLCError_Cnt_M_u08	114
PrevISDYNABRMsgRxTime_MSec_M_u32	1016041728
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	64
PrevISDYNCMM208MsgRxTime_MSec_M_u32	103567616
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	92
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3543183616
PrevISDYNVOLMsgDLCError_Cnt_M_u08	227
PrevISDYNVOLMsgRxTime_MSec_M_u32	2506674432
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	909148416
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	490.330292
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	50696
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	24599
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	61997
VitesseVehicleBVRampValidCount_Cnt_M_u16	52732
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	53040
VitesseVehicleBVSigValidCount_Cnt_M_u16	63688

Name	Input Value
VitesseVehicleBV_Kph_M_f32	418.530609
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	3994
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	27274
VitesseVehiculeRoues_Kph_M_f32	599.389404
k_AASNTCEnableTimeout_mS_u16	37909
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	13355
k_AASNodeTimeout_mS_u16	34583
k_ABSNodeTimeout_mS_u16	45689
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	24423
k_ANGLEVOLANTSigValidThresh_Cnt_u16	10186
k_AngleVolantInvalidThresh_Cnt_u16	10573
k_AngleVolantValidThresh_Cnt_u16	51580
k_BSI552MsgTimeout_mS_u16	32205
k_BSINTCEnableTimeout_mS_u16	15032
k_BSINodeAbsentDiag_Cnt_str.Threshold	49628
k_BSINodeAbsentDiag_Cnt_str.PStep	60082
k_BSINodeAbsentDiag_Cnt_str.NStep	23675
k_BSINodeAbsentTimeout_mS_u16	35658
k_BSINodeTimeout_mS_u16	52496
k_BattOvHi_Volt_f32	9.62619972
k_BattOvLo_Volt_f32	14.7265997
k_BattUvHi_Volt_f32	8.40649986
k_BattUvLo_Volt_f32	22.8293991
k_CAVNTCEnableTimeout_mS_u16	64778
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	32921
k_CAVNodeTimeout_mS_u16	9464
k_CMM388MsgTimeout_mS_u16	7225
k_CMM388NTCEnableTimeout_mS_u16	52645
k_CMMNTCEnableTimeout_mS_u16	13162
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	63990
k_CONSANGLECPKMax_HwDeg_f32	26.6466999
k_CONSANGLECPKMin_HwDeg_f32	-645.912292
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	63130
k_CONSANGLECPKSigValidThresh_Cnt_u16	37258
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	53109
k_CPKVehicleSpeedValidThresh_Cnt_u16	63674
k_CityParkInputInvalidThresh_Cnt_u16	45711
k_CityParkInputValidThresh_Cnt_u16	8312
k_ComputerRazGCTSigValidThresh_Cnt_u16	16848
k_CptTemporelSigValidThresh_Cnt_u16	3275
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	44263
k_DMDFCTCPKSigValidThresh_Cnt_u16	54798
k_DMDFCTCPKValidCount_Cnt_u16	270
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	29891
k_DMDRELAXECPKSigValidThresh_Cnt_u16	14371
k_DMDRelaxeConsistentThresh_Cnt_u16	49793
k_DateValidThresh_Cnt_u16	4966
k_DefaultVehSpd_Kph_f32	153.207504
k_DiagMuxOnAbsentTimeout_mS_u16	32688
k_EMNodeTimeout_mS_u16	1957
k_ESPNTCEnableTimeout_mS_u16	44111
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	16926
k_EtatMTSigInvalidThresh_Cnt_u16	58772
k_EtatMTSigValidThresh_Cnt_u16	64596
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	11012
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	25144
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	54941
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	16491
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	22950
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	2847
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	32569

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	57628
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	48756
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	20502
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	26274
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	38744
k_ISDATDIRASentDiag_Cnt_str.Threshold	48619
k_ISDATDIRASentDiag_Cnt_str.PStep	14149
k_ISDATDIRASentDiag_Cnt_str.NStep	9868
k_ISDATDIRASentTimeout_mS_u16	61981
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	33065
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	8562
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	12043
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	7857
k_ISDYNAASChkSumValidThresh_Cnt_u16	49457
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	27102
k_ISDYNAASMsgCountValidThresh_Cnt_u16	33429
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	42053
k_ISDYNAASMsgLenValidThresh_Cnt_u16	28587
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	13810
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	17309
k_ISDYNABRChkSumValidThresh_Cnt_u16	10564
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	39654
k_ISDYNABRMsgCountValidThresh_Cnt_u16	16638
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	56908
k_ISDYNABRMsgLenValidThresh_Cnt_u16	30831
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	48065
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	52892
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	65520
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	38234
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	46731
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	15971
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	26452
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	7314
k_ISDYNVOLChkSumValidThresh_Cnt_u16	32958
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	32936
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	3525
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	32192
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	12948
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	42356
k_IgnOnTimeout_mS_u16	15102
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	42.2901001
k_PowerCutVehSpdLowThresh_Kph_f32	155.579102
k_PowerCutVehSpdLowTimeout_mS_u16	42929
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	18.2863998
k_VBattMaxCAV_Volt_f32	7.17570019
k_VBattMaxCMM388_Volt_f32	32
k_VBattMaxCMM_Volt_f32	28.6040001
k_VBattMaxESP_Volt_f32	7.94329977
k_VBattMinAAS_Volt_f32	26.5634003
k_VBattMinBSI_Volt_f32	7.94329977
k_VBattMinCAV_Volt_f32	2.53699994
k_VBattMinCMM388_Volt_f32	20.7500992
k_VBattMinCMM_Volt_f32	19.4354
k_VBattMinESP_Volt_f32	28.6040001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	34763
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	49255
k_VitesseVehicleBVRampValidThresh_Cnt_u16	24990
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	52649
k_VitesseVehicleBVSigValidThresh_Cnt_u16	64629
k_VitesseVehicleBVSpeedPassThresh_kph_f32	438.155487
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	58595
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	32050
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1506930944
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	26677
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3002390528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	92
target_SrlComInput_Per1_Batt_Volt_f32.value	10.0493002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3117293824
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	169
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.107345477
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1198100736
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3188601088
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2722287872
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3691475200
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1398542592
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4030771456
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2595574016
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	124
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	150
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	193
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3859575040
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	227
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	490246400
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3378327808
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2735853824
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	55
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	119
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	126
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	161
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	218
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	234
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1402446080
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	350
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.843186975
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	424005
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	39.7257996

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	55338		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	3002390528	3002390528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3002390528	3002390528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	8564	8564	✔
AngleVolantMsgTimer_mS_M_u32	3002390528	3002390528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3002390528	3002390528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3002390528	3002390528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3002390528	3002390528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3002390528	3002390528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	49628	49628	✔
BSINodeAbsentTimer_mS_M_u32	3002390528	3002390528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3002390528	3002390528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3002390528	3002390528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3002390528	3002390528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3002390528	3002390528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3002390528	3002390528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	14498	14498	✔
CONSANGLECPK_HwDeg_M_f32	-157.322906	-157.322906 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	14498	14498	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2683797760	2683797760	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	52312	52312	✔
CityParkInputConsistentCount_Cnt_M_u16	8312	8312	✔
CityParkInputInvalidCount_Cnt_M_u16	51580	51580	✔
CityParkInputMsgTimer_mS_M_u32	3002390528	3002390528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3002390528	3002390528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3002390528	3002390528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3002390528	3002390528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3002390528	3002390528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3002390528	3002390528	✔
ESPNTCEnableTimer_mS_M_u32	3002390528	3002390528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3002390528	3002390528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	200	200	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3002390528	3002390528	✔
ElecIntTimer_mS_M_u32[1]	156	156	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3002390528	3002390528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3002390528	3002390528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3002390528	3002390528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3002390528	3002390528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3002390528	3002390528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3002390528	3002390528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3002390528	3002390528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3002390528	3002390528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3002390528	3002390528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3002390528	3002390528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3002390528	3002390528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3002390528	3002390528	✔
IgnOnTimer_mS_M_u32	3002390528	3002390528	✔
IgnTimeOff_Sec_M_u32	1235889189	1235889189	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1198100736	1198100736	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3188601088	3188601088	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	107	107	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2722287872	2722287872	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	93	93	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3691475200	3691475200	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3078869248	3078869248	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4030771456	4030771456	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	141	141	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2595574016	2595574016	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	81	81	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3859575040	3859575040	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	167	167	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	490246400	490246400	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3378327808	3378327808	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	186	186	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2735853824	2735853824	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1402446080	1402446080	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	490.330292	490.330292	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	418.530609	418.530609	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	599.389404	599.389404	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	14498	14498	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1235889189	1235889189	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-157.322906	-157.322906 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	153.207504	153.207504	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.262 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1368735744
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	50487
AASNodeAbsentTimer_mS_M_u32	454078464
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	24640
ANGLEVOLANTSigValidCount_Cnt_M_u16	50041
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	42124
AngleVolantMsgTimer_mS_M_u32	1368735744
AngleVolantValidCount_Cnt_M_u16	2996
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1134718976
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2804740096
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3239763968
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1982046208
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	57135
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	220160000
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	48057
CAVNodeAbsentTimer_mS_M_u32	3448393728
CDD_SrlComVehSpd_Kph_G_f32	563.369324
CMM388NTCEnableTimer_mS_M_u32	254054400
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2138066944
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	40766
CMMNodeAbsentTimer_mS_M_u32	3871186944
CONSANGLECPKSigInvalidCount_Cnt_M_u16	36926
CONSANGLECPKSigValidCount_Cnt_M_u16	59974
CONSANGLECPK_Cnt_M_u16	36537
CONSANGLECPK_HwDeg_M_f32	-226.433701
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	36537
CPKVehicleSpeedMsgTimer_mS_M_u32	519847936
CPKVehicleSpeedValidCount_Cnt_M_u16	45025

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	35320
CityParkInputInvalidCount_Cnt_M_u16	61420
CityParkInputMsgTimer_mS_M_u32	1198100736
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	710193152
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	27003
ComputerRazGCTSigInvalidTimer_mS_M_u32	662097920
ComputerRazGCTSigValidCount_Cnt_M_u16	27973
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	60840
DMDFCTCPKSigValidCount_Cnt_M_u16	21529
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56930
DMDRELAXECPKSigValidCount_Cnt_M_u16	63259
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	49299
DateInvalidTimer_mS_M_u32	2804740096
DiagMuxOnAbsentTimer_mS_M_u32	1685127168
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1982046208
ESPNTCEnableTimer_mS_M_u32	3748245504
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	64403
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	89
EffacDefaultDiagTimer_mS_M_u32[1]	898
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1111
ElecIntTimer_mS_M_u32[1]	2223
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2795593728
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	2853
EtatMTSigValidCount_Cnt_M_u16	618
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	62560
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	33768
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	5359
ISDAT4V2BSI552MsgTimer_mS_M_u32	2701238272
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	20204
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	12345
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	618
ISDATBSI3F2MsgTimer_mS_M_u32	1481572352
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	11776
ISDATBSI412MsgLenValidCount_Cnt_M_u16	41469
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	2853
ISDATBSI412MsgTimer_mS_M_u32	3681763328
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	17538
ISDATBSI432MsgLenValidCount_Cnt_M_u16	52183
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	16946
ISDATDIRASentFltAcc_Cnt_M_u16	35846
ISDATDIRASentTimer_mS_M_u32	519847936
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	19735
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	2996
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	51735
ISDYN2CMMMsgTimer_mS_M_u32	3900944384
ISDYNAASChkSumInvalidCount_Cnt_M_u16	28505
ISDYNAASChkSumValidCount_Cnt_M_u16	31410
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	32291
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	43628
ISDYNAASMsgLenValidCount_Cnt_M_u16	27773
ISDYNAASMsgTimeValidCount_Cnt_M_u16	28505
ISDYNAASMsgTimer_mS_M_u32	3386937344
ISDYNABRChkSumInvalidCount_Cnt_M_u16	5966
ISDYNABRChkSumValidCount_Cnt_M_u16	51855
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	45128
ISDYNABRMsgCountValidCount_Cnt_M_u16	57569
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	39981
ISDYNABRMsgLenValidCount_Cnt_M_u16	23413
ISDYNABRMsgTimeValidCount_Cnt_M_u16	36537

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	25899
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	35400
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	618
ISDYNCMM208MsgTimer_mS_M_u32	3777982464
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	25899
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	35400
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	50322
ISDYNCMM388MsgTimer_mS_M_u32	1337462784
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	31772
ISDYNVOLChkSumValidCount_Cnt_M_u16	41124
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	58502
ISDYNVOLMsgCountValidCount_Cnt_M_u16	14951
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	45476
ISDYNVOLMsgLenValidCount_Cnt_M_u16	50061
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	40766
ISDYNVOLMsgTimer_mS_M_u32	2922565632
IgnOnTimer_mS_M_u32	3975942144
IgnTimeOff_Sec_M_u32	2630078568
ManVehSpd_Kph_M_f32	442.302887
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	136
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	185
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2064973824
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	155
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3655983104
PrevISDATBSI412MsgDLCError_Cnt_M_u08	112
PrevISDATBSI412MsgRxTime_MSec_M_u32	1824739328
PrevISDATBSI432MsgDLCError_Cnt_M_u08	71
PrevISDATBSI432MsgRxTime_MSec_M_u32	3432886272
PrevISDATDIRAMsgTxTime_MSec_M_u32	764891136
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	150
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2161975296
PrevISDYNAASMsgDLCError_Cnt_M_u08	130
PrevISDYNAASMsgRxTime_MSec_M_u32	1955647488
PrevISDYNABRMsgDLCError_Cnt_M_u08	132
PrevISDYNABRMsgRxTime_MSec_M_u32	2104758272
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	57
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2208157696
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	199
PrevISDYNCMM388MsgRxTime_MSec_M_u32	638627840
PrevISDYNVOLMsgDLCError_Cnt_M_u08	253
PrevISDYNVOLMsgRxTime_MSec_M_u32	1743278080
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2152808448
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	16.3775997
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	14154
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	33755
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	34523
VitesseVehicleBVRampValidCount_Cnt_M_u16	3628
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	46417

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	29514
VitesseVehicleBV_Kph_M_f32	506.106293
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	50322
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	20099
VitesseVehiculeRoues_Kph_M_f32	136.588303
k_AASNTCEnableTimeout_mS_u16	2144
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	56031
k_AASNodeTimeout_mS_u16	3803
k_ABSNodeTimeout_mS_u16	26869
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	53997
k_ANGLEVOLANTSigValidThresh_Cnt_u16	58498
k_AngleVolantInvalidThresh_Cnt_u16	44025
k_AngleVolantValidThresh_Cnt_u16	61420
k_BSI552MsgTimeout_mS_u16	57530
k_BSINTCEnableTimeout_mS_u16	50426
k_BSINodeAbsentDiag_Cnt_str.Threshold	13072
k_BSINodeAbsentDiag_Cnt_str.PStep	49872
k_BSINodeAbsentDiag_Cnt_str.NStep	18355
k_BSINodeAbsentTimeout_mS_u16	50948
k_BSINodeTimeout_mS_u16	16946
k_BattOvHi_Volt_f32	24.0781994
k_BattOvLo_Volt_f32	12.8078003
k_BattUvHi_Volt_f32	22.9764004
k_BattUvLo_Volt_f32	21.6973991
k_CAVNTCEnableTimeout_mS_u16	3394
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	35735
k_CAVNodeTimeout_mS_u16	33530
k_CMM388MsgTimeout_mS_u16	36919
k_CMM388NTCEnableTimeout_mS_u16	11251
k_CMMNTCEnableTimeout_mS_u16	52068
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	20543
k_CONSANGLECPKMax_HwDeg_f32	459.699707
k_CONSANGLECPKMin_HwDeg_f32	-72.889801
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	3986
k_CONSANGLECPKSigValidThresh_Cnt_u16	55683
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	11713
k_CPKVehicleSpeedValidThresh_Cnt_u16	3187
k_CityParkInputInvalidThresh_Cnt_u16	40628
k_CityParkInputValidThresh_Cnt_u16	35320
k_ComputerRazGCTSigValidThresh_Cnt_u16	47154
k_CptTemporelSigValidThresh_Cnt_u16	8703
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	26413
k_DMDFCTCPKSigValidThresh_Cnt_u16	26229
k_DMDFCTCPKValidCount_Cnt_u16	6071
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	51735
k_DMDRELAXECPKSigValidThresh_Cnt_u16	55992
k_DMDRelaxeConsistentThresh_Cnt_u16	13214
k_DateValidThresh_Cnt_u16	5359
k_DefaultVehSpd_Kph_f32	177.763199
k_DiagMuxOnAbsentTimeout_mS_u16	29071
k_EMNodeTimeout_mS_u16	52979
k_ESPNTCEnableTimeout_mS_u16	24693
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	6087
k_EtatMTSigInvalidThresh_Cnt_u16	22949
k_EtatMTSigValidThresh_Cnt_u16	61478
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	5908
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	7225
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	15241
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	59489
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	26478
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	43332

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	15223
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	32908
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	10694
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	6237
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	57210
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	31128
k_ISDATDIRASentDiag_Cnt_str.Threshold	26541
k_ISDATDIRASentDiag_Cnt_str.PStep	31670
k_ISDATDIRASentDiag_Cnt_str.NStep	42297
k_ISDATDIRASentTimeout_mS_u16	38922
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	16421
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	42124
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	51265
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	25166
k_ISDYNAASChkSumValidThresh_Cnt_u16	21903
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	31560
k_ISDYNAASMsgCountValidThresh_Cnt_u16	60385
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	8594
k_ISDYNAASMsgLenValidThresh_Cnt_u16	42271
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	23050
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	64267
k_ISDYNABRChkSumValidThresh_Cnt_u16	50387
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	43567
k_ISDYNABRMsgCountValidThresh_Cnt_u16	62120
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	10814
k_ISDYNABRMsgLenValidThresh_Cnt_u16	50835
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	20063
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	28046
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	20177
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	45074
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	11072
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	52857
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	30308
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	235
k_ISDYNVOLChkSumValidThresh_Cnt_u16	24360
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	53736
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	49107
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	27873
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	31014
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	5829
k_IgnOnTimeout_mS_u16	21927
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	59.0155983
k_PowerCutVehSpdLowThresh_Kph_f32	143.148407
k_PowerCutVehSpdLowTimeout_mS_u16	15756
k_VBattMaxAAS_Volt_f32	28.3260994
k_VBattMaxBSI_Volt_f32	7.00099993
k_VBattMaxCAV_Volt_f32	23.7364006
k_VBattMaxCMM388_Volt_f32	11.1890001
k_VBattMaxCMM_Volt_f32	19.4251003
k_VBattMaxESP_Volt_f32	25.6877003
k_VBattMinAAS_Volt_f32	32
k_VBattMinBSI_Volt_f32	25.6877003
k_VBattMinCAV_Volt_f32	1.91349995
k_VBattMinCMM388_Volt_f32	23.6511002
k_VBattMinCMM_Volt_f32	25.6292
k_VBattMinESP_Volt_f32	19.4251003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	13375
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	54572
k_VitesseVehicleBVRampValidThresh_Cnt_u16	12166
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	43940
k_VitesseVehicleBVSigValidThresh_Cnt_u16	10753
k_VitesseVehicleBVSpeedPassThresh_kph_f32	329.936401
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	1721
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	22666
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2804740096
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	16373
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	740309760
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	199
target_SrlComInput_Per1_Batt_Volt_f32.value	31
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4093140992
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	153
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0893024653
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1155928064
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3145216000
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	693784576
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3599527936
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	185503744
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	22
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	249606144
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	704827392
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	54
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	147
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	149
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	176
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	190
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	226
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	209547264
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	36
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	156
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	157
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	184
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	10
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3212382208
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	128
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2508926976
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	585977856
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	52
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	91
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	115
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	213
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	226
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	748412928
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	308
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.881454289
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	886596
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	52.9583015
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	2276

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	740309760	740309760	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	740309760	740309760	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	740309760	740309760	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	740309760	740309760	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	740309760	740309760	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	740309760	740309760	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	740309760	740309760	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	13072	13072	✔
BSINodeAbsentTimer_mS_M_u32	740309760	740309760	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	740309760	740309760	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	740309760	740309760	✔
CDD_SrlComVehSpd_Kph_G_f32	442.302887	442.302887	✔
CMM388NTCEnableTimer_mS_M_u32	740309760	740309760	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	740309760	740309760	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	740309760	740309760	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	36537	36537	✔
CONSANGLECPK_HwDeg_M_f32	-226.433701	-226.433701 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	740309760	740309760	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	740309760	740309760	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	740309760	740309760	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	740309760	740309760	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	740309760	740309760	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	740309760	740309760	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	740309760	740309760	✔
ESPNTCEnableTimer_mS_M_u32	740309760	740309760	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	740309760	740309760	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	89	89	✔
EffacDefaultDiagTimer_mS_M_u32[1]	898	898	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1111	1111	✔
ElecIntTimer_mS_M_u32[1]	2223	2223	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	740309760	740309760	✔
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	5359	5359	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	740309760	740309760	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	618	618	✔
ISDATBSI3F2MsgTimer_mS_M_u32	740309760	740309760	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	2853	2853	✔
ISDATBSI412MsgTimer_mS_M_u32	740309760	740309760	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	16946	16946	✔
ISDATBSI432MsgTimer_mS_M_u32	740309760	740309760	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	740309760	740309760	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	51735	51735	✔
ISDYN2CMMMsgTimer_mS_M_u32	740309760	740309760	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	28505	28505	✔
ISDYNAASMsgTimer_mS_M_u32	740309760	740309760	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	36537	36537	✔
ISDYNABRMsgTimer_mS_M_u32	740309760	740309760	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	618	618	✔
ISDYNCMM208MsgTimer_mS_M_u32	740309760	740309760	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	50322	50322	✔
ISDYNCMM388MsgTimer_mS_M_u32	740309760	740309760	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	40766	40766	✔
ISDYNVOLMsgTimer_mS_M_u32	740309760	740309760	✔
IgnOnTimer_mS_M_u32	3975942144	3975942144	✔
IgnTimeOff_Sec_M_u32	2630078568	2630078568	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	183	183	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1155928064	1155928064	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	45	45	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3145216000	3145216000	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	118	118	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	693784576	693784576	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3599527936	3599527936	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	764891136	764891136	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	22	22	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	249606144	249606144	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	125	125	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	704827392	704827392	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	84	84	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	209547264	209547264	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	10	10	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3212382208	3212382208	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	128	128	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2508926976	2508926976	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	136	136	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	585977856	585977856	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	748412928	748412928	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	16.3775997	16.3775997	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	506.106293	506.106293	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	136.588303	136.588303	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	36537	36537	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2630078568	2630078568	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-226.433701	-226.433701 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	442.302887	442.302887	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.263 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3017736960
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	759
AASNodeAbsentTimer_mS_M_u32	3509367552
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	62430
ANGLEVOLANTSigValidCount_Cnt_M_u16	6643
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	63736
AngleVolantMsgTimer_mS_M_u32	3017736960
AngleVolantValidCount_Cnt_M_u16	3072
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3463934720
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3990352640
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	63841024
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	4155761408
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	62225
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3519062784
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	44530
CAVNodeAbsentTimer_mS_M_u32	675271424
CDD_SrlComVehSpd_Kph_G_f32	593.930115
CMM388NTCEnableTimer_mS_M_u32	2624656128
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	713937664
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	54307
CMMNodeAbsentTimer_mS_M_u32	2380653312
CONSANGLECPKSigInvalidCount_Cnt_M_u16	35556
CONSANGLECPKSigValidCount_Cnt_M_u16	3209
CONSANGLECPK_Cnt_M_u16	43824
CONSANGLECPK_HwDeg_M_f32	-331.701385
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43824
CPKVehicleSpeedMsgTimer_mS_M_u32	2812936960
CPKVehicleSpeedValidCount_Cnt_M_u16	53985
CityParkInputConsistentCount_Cnt_M_u16	41268
CityParkInputInvalidCount_Cnt_M_u16	19546
CityParkInputMsgTimer_mS_M_u32	1155928064
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3009458944
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	9771

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1819955968
ComputerRazGCTSigValidCount_Cnt_M_u16	27469
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0
DMDFCTCPKSigValidCount_Cnt_M_u16	20675
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	33144
DMDRELAXECPKSigValidCount_Cnt_M_u16	34573
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	36325
DateInvalidTimer_mS_M_u32	3990352640
DiagMuxOnAbsentTimer_mS_M_u32	2588656384
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4155761408
ESPNTCEnableTimer_mS_M_u32	673297152
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	32484
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	4
EffacDefaultDiagTimer_mS_M_u32[1]	748
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65535
ElecIntTimer_mS_M_u32[1]	95536
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2369430272
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	15725
EtatMTSigValidCount_Cnt_M_u16	55134
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	26238
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	18339
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	54545
ISDAT4V2BSI552MsgTimer_mS_M_u32	1863967488
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	922
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	65395
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	55134
ISDATBSI3F2MsgTimer_mS_M_u32	3065103104
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1885
ISDATBSI412MsgLenValidCount_Cnt_M_u16	2854
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	15725
ISDATBSI412MsgTimer_mS_M_u32	239403776
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	62551
ISDATBSI432MsgLenValidCount_Cnt_M_u16	7704
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	16007
ISDATDIRASentFltAcc_Cnt_M_u16	45323
ISDATDIRASentTimer_mS_M_u32	2812936960
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	26646
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	3072
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	10713
ISDYN2CMMMsgTimer_mS_M_u32	4107514624
ISDYNAASChkSumInvalidCount_Cnt_M_u16	3217
ISDYNAASChkSumValidCount_Cnt_M_u16	47686
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	12467
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	28121
ISDYNAASMsgLenValidCount_Cnt_M_u16	55142
ISDYNAASMsgTimeValidCount_Cnt_M_u16	3217
ISDYNAASMsgTimer_mS_M_u32	1547506432
ISDYNABRChkSumInvalidCount_Cnt_M_u16	32818
ISDYNABRChkSumValidCount_Cnt_M_u16	54832
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	50628
ISDYNABRMsgCountValidCount_Cnt_M_u16	953
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	58135
ISDYNABRMsgLenValidCount_Cnt_M_u16	13564
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43824
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	43600
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	51642
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	55134
ISDYNCMM208MsgTimer_mS_M_u32	1775268608
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	43600
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	51642
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	55654

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2293666560
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	48970
ISDYNVOLChkSumValidCount_Cnt_M_u16	57711
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	22156
ISDYNVOLMsgCountValidCount_Cnt_M_u16	17577
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	57521
ISDYNVOLMsgLenValidCount_Cnt_M_u16	47798
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	54307
ISDYNVOLMsgTimer_mS_M_u32	3360051968
IgnOnTimer_mS_M_u32	3236598528
IgnTimeOff_Sec_M_u32	1778644792
ManVehSpd_Kph_M_f32	79.6591034
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	137
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	31
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3865035520
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	193
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3043042048
PrevISDATBSI412MsgDLCError_Cnt_M_u08	83
PrevISDATBSI412MsgRxTime_MSec_M_u32	1855247104
PrevISDATBSI432MsgDLCError_Cnt_M_u08	32
PrevISDATBSI432MsgRxTime_MSec_M_u32	814068480
PrevISDATDIRAMsgTxTime_MSec_M_u32	2082001664
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	109
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2642895616
PrevISDYNAASMsgDLCError_Cnt_M_u08	222
PrevISDYNAASMsgRxTime_MSec_M_u32	1831621376
PrevISDYNABRMsgDLCError_Cnt_M_u08	227
PrevISDYNABRMsgRxTime_MSec_M_u32	4018311936
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	97
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3020247808
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	21
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2955719424
PrevISDYNVOLMsgDLCError_Cnt_M_u08	21
PrevISDYNVOLMsgRxTime_MSec_M_u32	1361433344
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	397083392
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	86.4172974
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	48959
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	35148
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	21644
VitesseVehicleBVRampValidCount_Cnt_M_u16	28249
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	30891
VitesseVehicleBVSigValidCount_Cnt_M_u16	36480
VitesseVehicleBV_Kph_M_f32	419.602295
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	55654
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	27475
VitesseVehiculeRoues_Kph_M_f32	352.640991
k_AASNTCEnableTimeout_mS_u16	39483
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	2687
k_AASNodeTimeout_mS_u16	59468
k_ABSNodeTimeout_mS_u16	17727
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	46358
k_ANGLEVOLANTSigValidThresh_Cnt_u16	16407
k_AngleVolantInvalidThresh_Cnt_u16	34226
k_AngleVolantValidThresh_Cnt_u16	19546
k_BSI552MsgTimeout_mS_u16	20654
k_BSINTCEnableTimeout_mS_u16	21231
k_BSINodeAbsentDiag_Cnt_str.Threshold	3616
k_BSINodeAbsentDiag_Cnt_str.PStep	16418
k_BSINodeAbsentDiag_Cnt_str.NStep	8888
k_BSINodeAbsentTimeout_mS_u16	29072
k_BSINodeTimeout_mS_u16	16007
k_BattOvHi_Volt_f32	29.0573997
k_BattOvLo_Volt_f32	18.2765007
k_BattUvHi_Volt_f32	14.1451998
k_BattUvLo_Volt_f32	22.0128994
k_CAVNTCEnableTimeout_mS_u16	52312
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	13912
k_CAVNodeTimeout_mS_u16	41648
k_CMM388MsgTimeout_mS_u16	41463
k_CMM388NTCEnableTimeout_mS_u16	48835
k_CMMNTCEnableTimeout_mS_u16	28210
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	22047
k_CONSANGLECPKMax_HwDeg_f32	129.878799
k_CONSANGLECPKMin_HwDeg_f32	-758.552795
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	63590
k_CONSANGLECPKSigValidThresh_Cnt_u16	51795
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	41882
k_CPKVehicleSpeedValidThresh_Cnt_u16	63492
k_CityParkInputInvalidThresh_Cnt_u16	512
k_CityParkInputValidThresh_Cnt_u16	41268
k_ComputerRazGCTSigValidThresh_Cnt_u16	24520
k_CptTemporelSigValidThresh_Cnt_u16	49697
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	33303
k_DMDFCTCPKSigValidThresh_Cnt_u16	5116
k_DMDFCTCPKValidCount_Cnt_u16	27001
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	10713
k_DMDRELAXECPKSigValidThresh_Cnt_u16	59318
k_DMDRelaxeConsistentThresh_Cnt_u16	62724
k_DateValidThresh_Cnt_u16	54545
k_DefaultVehSpd_Kph_f32	115.830597
k_DiagMuxOnAbsentTimeout_mS_u16	55982
k_EMNodeTimeout_mS_u16	58053
k_ESPNTCEnableTimeout_mS_u16	44990
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	8071
k_EtatMTSigInvalidThresh_Cnt_u16	54573
k_EtatMTSigValidThresh_Cnt_u16	33131
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	62369
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	58355
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	4225
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	19259
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	28116
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	42385
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	9080
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	5113
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	21643
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	40516
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	10414
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	54676
k_ISDATDIRASentDiag_Cnt_str.Threshold	5619

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	47502
k_ISDATDIRASentDiag_Cnt_str.NStep	46845
k_ISDATDIRASentTimeout_mS_u16	60926
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	62957
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	63736
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	43098
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	40754
k_ISDYNAASChkSumValidThresh_Cnt_u16	13616
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	25796
k_ISDYNAASMsgCountValidThresh_Cnt_u16	58041
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	29030
k_ISDYNAASMsgLenValidThresh_Cnt_u16	13696
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	65407
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	48765
k_ISDYNABRChkSumValidThresh_Cnt_u16	61666
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	37393
k_ISDYNABRMsgCountValidThresh_Cnt_u16	2150
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	13091
k_ISDYNABRMsgLenValidThresh_Cnt_u16	7652
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	37185
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	11379
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	10474
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	41127
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	37598
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	63731
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	39154
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	64156
k_ISDYNVOLChkSumValidThresh_Cnt_u16	16293
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	36837
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	1636
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	2105
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	25386
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	42895
k_IgnOnTimeout_mS_u16	60520
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	34.5732994
k_PowerCutVehSpdLowThresh_Kph_f32	46.1749001
k_PowerCutVehSpdLowTimeout_mS_u16	43703
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	24.5809002
k_VBattMaxCAV_Volt_f32	24.1646996
k_VBattMaxCMM388_Volt_f32	1.801
k_VBattMaxCMM_Volt_f32	22.1776009
k_VBattMaxESP_Volt_f32	5.54890013
k_VBattMinAAS_Volt_f32	25.1459007
k_VBattMinBSI_Volt_f32	5.54890013
k_VBattMinCAV_Volt_f32	31.8512993
k_VBattMinCMM388_Volt_f32	1.50750005
k_VBattMinCMM_Volt_f32	1.47060001
k_VBattMinESP_Volt_f32	22.1776009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	415
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	16024
k_VitesseVehicleBVRampValidThresh_Cnt_u16	30092
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	49263
k_VitesseVehicleBVSigValidThresh_Cnt_u16	9497
k_VitesseVehicleBVSpeedPassThresh_kph_f32	643.65741
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	52466
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	34623
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3990352640
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	42915
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	501879296
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	21
target_SrlComInput_Per1_Batt_Volt_f32.value	9.31369972
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3241517824
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	112
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.90260011
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3777794816
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	54
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3992335104
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1422906112
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1035563776
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3501396736
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	62
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	901559040
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	27
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2497073920
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	44
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	154
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	162
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	208
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2682680064
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	57
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	128
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	163
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	239
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2104726272
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1807561472
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1947652864
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	12
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	176
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	199
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	88810240
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2688
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.546267509
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	952936
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	93.9953995
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	12913

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	501879296	501879296	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	501879296	501879296	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	63736	63736	✔
AngleVolantMsgTimer_mS_M_u32	501879296	501879296	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	501879296	501879296	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	501879296	501879296	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	501879296	501879296	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	501879296	501879296	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	3616	3616	✔
BSINodeAbsentTimer_mS_M_u32	501879296	501879296	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	501879296	501879296	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	501879296	501879296	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	501879296	501879296	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	501879296	501879296	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	501879296	501879296	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	43824	43824	✔
CONSANGLECPK_HwDeg_M_f32	-331.701385	-331.701385 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43824	43824	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2812936960	2812936960	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	53985	53985	✔
CityParkInputConsistentCount_Cnt_M_u16	41268	41268	✔
CityParkInputInvalidCount_Cnt_M_u16	19546	19546	✔
CityParkInputMsgTimer_mS_M_u32	501879296	501879296	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	501879296	501879296	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	501879296	501879296	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	501879296	501879296	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	501879296	501879296	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	501879296	501879296	✔
ESPNTCEnableTimer_mS_M_u32	501879296	501879296	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	501879296	501879296	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4	4	✔
EffacDefaultDiagTimer_mS_M_u32[1]	748	748	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	501879296	501879296	✔
ElecIntTimer_mS_M_u32[1]	95536	95536	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	501879296	501879296	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	501879296	501879296	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	501879296	501879296	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	501879296	501879296	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	501879296	501879296	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	501879296	501879296	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	501879296	501879296	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	501879296	501879296	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	501879296	501879296	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	501879296	501879296	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	501879296	501879296	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	501879296	501879296	✔
IgnOnTimer_mS_M_u32	3236598528	3236598528	✔
IgnTimeOff_Sec_M_u32	1778644792	1778644792	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	200	200	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3777794816	3777794816	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	54	54	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3992335104	3992335104	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	107	107	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1422906112	1422906112	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	142	142	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1035563776	1035563776	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2082001664	2082001664	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	62	62	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	901559040	901559040	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	27	27	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2497073920	2497073920	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	40	40	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2682680064	2682680064	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2104726272	2104726272	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	75	75	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1807561472	1807561472	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1947652864	1947652864	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	88810240	88810240	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	86.4172974	86.4172974	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	419.602295	419.602295	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	352.640991	352.640991	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	43824	43824	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1778644792	1778644792	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-331.701385	-331.701385 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	115.830597	115.830597	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.264 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3687692800
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	61572
AASNodeAbsentTimer_mS_M_u32	379890176
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	55248
ANGLEVOLANTSigValidCount_Cnt_M_u16	30289
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	21121
AngleVolantMsgTimer_mS_M_u32	3687692800
AngleVolantValidCount_Cnt_M_u16	16362
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3116657152
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2107828736
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	276847104
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4224653824
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	26167
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2426984960
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	17426
CAVNodeAbsentTimer_mS_M_u32	3320531456
CDD_SrlComVehSpd_Kph_G_f32	517.109985
CMM388NTCEnableTimer_mS_M_u32	3193408000
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1996573184
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	24385
CMMNodeAbsentTimer_mS_M_u32	2168003072
CONSANGLECPKSigInvalidCount_Cnt_M_u16	40380
CONSANGLECPKSigValidCount_Cnt_M_u16	27020
CONSANGLECPK_Cnt_M_u16	59799
CONSANGLECPK_HwDeg_M_f32	-736.660522
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	59799
CPKVehicleSpeedMsgTimer_mS_M_u32	3966548480
CPKVehicleSpeedValidCount_Cnt_M_u16	28940

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	20558
CityParkInputInvalidCount_Cnt_M_u16	47067
CityParkInputMsgTimer_mS_M_u32	3777794816
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1074309632
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	22248
ComputerRazGCTSigInvalidTimer_mS_M_u32	54249984
ComputerRazGCTSigValidCount_Cnt_M_u16	38403
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	65535
DMDFCTCPKSigValidCount_Cnt_M_u16	2912
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	5890
DMDRELAXECPKSigValidCount_Cnt_M_u16	5891
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	55481
DateInvalidTimer_mS_M_u32	2107828736
DiagMuxOnAbsentTimer_mS_M_u32	3414653440
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4224653824
ESPNTCEnableTimer_mS_M_u32	633711104
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	8125
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	20
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	579
ElecIntTimer_mS_M_u32[1]	990
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3325745664
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	7266
EtatMTSigValidCount_Cnt_M_u16	53071
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	62190
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	41022
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	13942
ISDAT4V2BSI552MsgTimer_mS_M_u32	2912754176
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	5468
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	17040
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	53071
ISDATBSI3F2MsgTimer_mS_M_u32	2387966464
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	10002
ISDATBSI412MsgLenValidCount_Cnt_M_u16	64630
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	7266
ISDATBSI412MsgTimer_mS_M_u32	3835410944
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	52901
ISDATBSI432MsgLenValidCount_Cnt_M_u16	4641
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	9811
ISDATDIRASentFltAcc_Cnt_M_u16	57031
ISDATDIRASentTimer_mS_M_u32	3966548480
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	51941
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	16362
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	56158
ISDYN2CMMMsgTimer_mS_M_u32	128952832
ISDYNAASChkSumInvalidCount_Cnt_M_u16	48054
ISDYNAASChkSumValidCount_Cnt_M_u16	17238
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	24017
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	24669
ISDYNAASMsgLenValidCount_Cnt_M_u16	5238
ISDYNAASMsgTimeValidCount_Cnt_M_u16	48054
ISDYNAASMsgTimer_mS_M_u32	2935196160
ISDYNABRChkSumInvalidCount_Cnt_M_u16	7762
ISDYNABRChkSumValidCount_Cnt_M_u16	52506
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	7197
ISDYNABRMsgCountValidCount_Cnt_M_u16	62205
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	8483
ISDYNABRMsgLenValidCount_Cnt_M_u16	31795
ISDYNABRMsgTimeValidCount_Cnt_M_u16	59799

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	13533
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	10848
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	53071
ISDYNCMM208MsgTimer_mS_M_u32	2344184320
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	13533
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	10848
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	61368
ISDYNCMM388MsgTimer_mS_M_u32	4018604544
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	6282
ISDYNVOLChkSumValidCount_Cnt_M_u16	730
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	57669
ISDYNVOLMsgCountValidCount_Cnt_M_u16	18350
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	28246
ISDYNVOLMsgLenValidCount_Cnt_M_u16	45319
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	24385
ISDYNVOLMsgTimer_mS_M_u32	534235648
IgnOnTimer_mS_M_u32	384502272
IgnTimeOff_Sec_M_u32	510744040
ManVehSpd_Kph_M_f32	97.9534988
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	139
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	175
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	927693312
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	239
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	130505216
PrevISDATBSI412MsgDLCError_Cnt_M_u08	5
PrevISDATBSI412MsgRxTime_MSec_M_u32	2263632384
PrevISDATBSI432MsgDLCError_Cnt_M_u08	170
PrevISDATBSI432MsgRxTime_MSec_M_u32	2627316224
PrevISDATDIRAMsgTxTime_MSec_M_u32	1851804160
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	22
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3092552192
PrevISDYNAASMsgDLCError_Cnt_M_u08	39
PrevISDYNAASMsgRxTime_MSec_M_u32	1227213312
PrevISDYNABRMsgDLCError_Cnt_M_u08	246
PrevISDYNABRMsgRxTime_MSec_M_u32	3944942080
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	155
PrevISDYNCMM208MsgRxTime_MSec_M_u32	412797440
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	109
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2040834560
PrevISDYNVOLMsgDLCError_Cnt_M_u08	139
PrevISDYNVOLMsgRxTime_MSec_M_u32	1664698880
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3765025280
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	609.032288
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	33835
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	5828
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	14404
VitesseVehicleBVRampValidCount_Cnt_M_u16	56221
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	48489

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	36010
VitesseVehicleBV_Kph_M_f32	109.423798
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	61368
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	43696
VitesseVehiculeRoues_Kph_M_f32	555.153076
k_AASNTCEnableTimeout_mS_u16	2166
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	109
k_AASNodeTimeout_mS_u16	63940
k_ABSNodeTimeout_mS_u16	41260
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	18536
k_ANGLEVOLANTSigValidThresh_Cnt_u16	26660
k_AngleVolantInvalidThresh_Cnt_u16	50003
k_AngleVolantValidThresh_Cnt_u16	47067
k_BSI552MsgTimeout_mS_u16	9887
k_BSINTCEnableTimeout_mS_u16	4829
k_BSINodeAbsentDiag_Cnt_str.Threshold	41198
k_BSINodeAbsentDiag_Cnt_str.PStep	26408
k_BSINodeAbsentDiag_Cnt_str.NStep	27557
k_BSINodeAbsentTimeout_mS_u16	18617
k_BSINodeTimeout_mS_u16	9811
k_BattOvHi_Volt_f32	29.5823002
k_BattOvLo_Volt_f32	0.701799989
k_BattUvHi_Volt_f32	31.4722996
k_BattUvLo_Volt_f32	28.2768993
k_CAVNTCEnableTimeout_mS_u16	45025
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	49888
k_CAVNodeTimeout_mS_u16	34392
k_CMM388MsgTimeout_mS_u16	4996
k_CMM388NTCEnableTimeout_mS_u16	60704
k_CMMNTCEnableTimeout_mS_u16	13716
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	6732
k_CONSANGLECPKMax_HwDeg_f32	505.514801
k_CONSANGLECPKMin_HwDeg_f32	-288.589905
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	37560
k_CONSANGLECPKSigValidThresh_Cnt_u16	36272
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	32730
k_CPKVehicleSpeedValidThresh_Cnt_u16	45341
k_CityParkInputInvalidThresh_Cnt_u16	20712
k_CityParkInputValidThresh_Cnt_u16	20558
k_ComputerRazGCTSigValidThresh_Cnt_u16	14546
k_CptTemporelSigValidThresh_Cnt_u16	12934
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	17443
k_DMDFCTCPKSigValidThresh_Cnt_u16	57139
k_DMDFCTCPKValidCount_Cnt_u16	41727
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	56158
k_DMDRELAXECPKSigValidThresh_Cnt_u16	53895
k_DMDRelaxeConsistentThresh_Cnt_u16	25245
k_DateValidThresh_Cnt_u16	13942
k_DefaultVehSpd_Kph_f32	250.425201
k_DiagMuxOnAbsentTimeout_mS_u16	54045
k_EMNodeTimeout_mS_u16	23065
k_ESPNTCEnableTimeout_mS_u16	28334
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	24084
k_EtatMTSigInvalidThresh_Cnt_u16	52065
k_EtatMTSigValidThresh_Cnt_u16	30569
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	27589
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	39825
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	30311
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	633
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	47981
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	7286

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	1346
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	62590
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	32265
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	24667
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	8672
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	43372
k_ISDATDIRASentDiag_Cnt_str.Threshold	14460
k_ISDATDIRASentDiag_Cnt_str.PStep	36482
k_ISDATDIRASentDiag_Cnt_str.NStep	2126
k_ISDATDIRASentTimeout_mS_u16	1262
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	60513
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	21121
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	62682
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	49490
k_ISDYNAASChkSumValidThresh_Cnt_u16	45082
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	16157
k_ISDYNAASMsgCountValidThresh_Cnt_u16	22013
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	6838
k_ISDYNAASMsgLenValidThresh_Cnt_u16	57896
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	51692
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	42737
k_ISDYNABRChkSumValidThresh_Cnt_u16	24705
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	35127
k_ISDYNABRMsgCountValidThresh_Cnt_u16	14072
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	16961
k_ISDYNABRMsgLenValidThresh_Cnt_u16	17085
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	51303
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	3215
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	13931
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	64691
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	64208
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	55633
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	12819
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	2389
k_ISDYNVOLChkSumValidThresh_Cnt_u16	6905
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	12474
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	3198
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	60414
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	23531
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	14076
k_IgnOnTimeout_mS_u16	25585
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	14.6971998
k_PowerCutVehSpdLowThresh_Kph_f32	211.892502
k_PowerCutVehSpdLowTimeout_mS_u16	50946
k_VBattMaxAAS_Volt_f32	7.24860001
k_VBattMaxBSI_Volt_f32	18.6077995
k_VBattMaxCAV_Volt_f32	2.48650002
k_VBattMaxCMM388_Volt_f32	18.5951004
k_VBattMaxCMM_Volt_f32	20.2103996
k_VBattMaxESP_Volt_f32	30.6189003
k_VBattMinAAS_Volt_f32	12.3044004
k_VBattMinBSI_Volt_f32	30.6189003
k_VBattMinCAV_Volt_f32	20.7733002
k_VBattMinCMM388_Volt_f32	7.19710016
k_VBattMinCMM_Volt_f32	22.6154995
k_VBattMinESP_Volt_f32	20.2103996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	4427
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	64288
k_VitesseVehicleBVRampValidThresh_Cnt_u16	33861
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	26074
k_VitesseVehicleBVSigValidThresh_Cnt_u16	39071
k_VitesseVehicleBVSpeedPassThresh_kph_f32	350.622009
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	59154
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	43243
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2107828736
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	21460
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1621658880
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	109
target_SrlComInput_Per1_Batt_Volt_f32.value	11.6736002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3595164160
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	232
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.240634471
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1042614784
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3326618112
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2151369216
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	226
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4093536768
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2844887552
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	175
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	687122944
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	230
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4196911616
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	115
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	132
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3245828608
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	55
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	100
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	141
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	155
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	167
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	207
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1162873344
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	687024640
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4268116480
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	83
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	90
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	165
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1074354688
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	450
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.17830646
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	111759
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	224.680801
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	29333

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1621658880	1621658880	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1621658880	1621658880	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1621658880	1621658880	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1621658880	1621658880	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1621658880	1621658880	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1621658880	1621658880	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1621658880	1621658880	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	41198	41198	✔
BSINodeAbsentTimer_mS_M_u32	1621658880	1621658880	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1621658880	1621658880	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1621658880	1621658880	✔
CDD_SrlComVehSpd_Kph_G_f32	97.9534988	97.9534988	✔
CMM388NTCEnableTimer_mS_M_u32	1621658880	1621658880	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1621658880	1621658880	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1621658880	1621658880	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	59799	59799	✔
CONSANGLECPK_HwDeg_M_f32	-736.660522	-736.660522 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1621658880	1621658880	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1621658880	1621658880	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1621658880	1621658880	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1621658880	1621658880	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1621658880	1621658880	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1621658880	1621658880	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1621658880	1621658880	✔
ESPNTCEnableTimer_mS_M_u32	1621658880	1621658880	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1621658880	1621658880	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	20	20	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	579	579	✔
ElecIntTimer_mS_M_u32[1]	990	990	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1621658880	1621658880	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	13942	13942	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1621658880	1621658880	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	53071	53071	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1621658880	1621658880	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	7266	7266	✔
ISDATBSI412MsgTimer_mS_M_u32	1621658880	1621658880	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	9811	9811	✔
ISDATBSI432MsgTimer_mS_M_u32	1621658880	1621658880	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1621658880	1621658880	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	56158	56158	✔
ISDYN2CMMMsgTimer_mS_M_u32	1621658880	1621658880	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	48054	48054	✔
ISDYNAASMsgTimer_mS_M_u32	1621658880	1621658880	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	59799	59799	✔
ISDYNABRMsgTimer_mS_M_u32	1621658880	1621658880	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	53071	53071	✔
ISDYNCMM208MsgTimer_mS_M_u32	1621658880	1621658880	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	61368	61368	✔
ISDYNCMM388MsgTimer_mS_M_u32	1621658880	1621658880	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	24385	24385	✔
ISDYNVOLMsgTimer_mS_M_u32	1621658880	1621658880	✔
IgnOnTimer_mS_M_u32	384502272	384502272	✔
IgnTimeOff_Sec_M_u32	510744040	510744040	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	202	202	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1042614784	1042614784	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	12	12	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3326618112	3326618112	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	60	60	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2151369216	2151369216	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	226	226	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4093536768	4093536768	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1851804160	1851804160	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	175	175	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	687122944	687122944	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	230	230	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4196911616	4196911616	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	8	8	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3245828608	3245828608	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	107	107	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1162873344	1162873344	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	169	169	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	687024640	687024640	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4268116480	4268116480	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1074354688	1074354688	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	609.032288	609.032288	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	109.423798	109.423798	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	555.153076	555.153076	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	59799	59799	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	510744040	510744040	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-736.660522	-736.660522 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.265 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2812122368
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	25466
AASNodeAbsentTimer_mS_M_u32	1054393600
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	32660
ANGLEVOLANTSigValidCount_Cnt_M_u16	29139
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	29059
AngleVolantMsgTimer_mS_M_u32	2812122368
AngleVolantValidCount_Cnt_M_u16	13767
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2222556416
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3537765632
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2617619712
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2233038080
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	12383
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1569469696
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	27470
CAVNodeAbsentTimer_mS_M_u32	327476480
CDD_SrlComVehSpd_Kph_G_f32	169.707306
CMM388NTCEnableTimer_mS_M_u32	725624064
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3628262656
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	28802
CMMNodeAbsentTimer_mS_M_u32	484144384
CONSANGLECPKSigInvalidCount_Cnt_M_u16	36049
CONSANGLECPKSigValidCount_Cnt_M_u16	14112
CONSANGLECPK_Cnt_M_u16	41727
CONSANGLECPK_HwDeg_M_f32	-188.809692
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	41727
CPKVehicleSpeedMsgTimer_mS_M_u32	2982188288
CPKVehicleSpeedValidCount_Cnt_M_u16	12552
CityParkInputConsistentCount_Cnt_M_u16	38043
CityParkInputInvalidCount_Cnt_M_u16	8947
CityParkInputMsgTimer_mS_M_u32	1042614784
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1387054336
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	49230

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1033069824
ComputerRazGCTSigValidCount_Cnt_M_u16	55164
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	54511
DMDFCTCPKSigValidCount_Cnt_M_u16	1574
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	2558
DMDRELAXECPKSigValidCount_Cnt_M_u16	55229
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	4058
DateInvalidTimer_mS_M_u32	3537765632
DiagMuxOnAbsentTimer_mS_M_u32	4017116416
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2233038080
ESPNTCEnableTimer_mS_M_u32	3581265152
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	60620
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	12
EffacDefaultDiagTimer_mS_M_u32[1]	13
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1000
ElecIntTimer_mS_M_u32[1]	2001
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2228630784
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	19998
EtatMTSigValidCount_Cnt_M_u16	45849
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	54587
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	56074
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	23780
ISDAT4V2BSI552MsgTimer_mS_M_u32	665810176
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	32946
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	38612
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	45849
ISDATBSI3F2MsgTimer_mS_M_u32	1594250496
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	62607
ISDATBSI412MsgLenValidCount_Cnt_M_u16	53794
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	19998
ISDATBSI412MsgTimer_mS_M_u32	1161008384
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	45654
ISDATBSI432MsgLenValidCount_Cnt_M_u16	42400
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	2187
ISDATDIRASentFltAcc_Cnt_M_u16	44847
ISDATDIRASentTimer_mS_M_u32	2982188288
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	46869
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	13767
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	33898
ISDYN2CMMMsgTimer_mS_M_u32	1471661312
ISDYNAASChkSumInvalidCount_Cnt_M_u16	18916
ISDYNAASChkSumValidCount_Cnt_M_u16	194
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	14354
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	621
ISDYNAASMsgLenValidCount_Cnt_M_u16	5091
ISDYNAASMsgTimeValidCount_Cnt_M_u16	18916
ISDYNAASMsgTimer_mS_M_u32	3379307776
ISDYNABRChkSumInvalidCount_Cnt_M_u16	59792
ISDYNABRChkSumValidCount_Cnt_M_u16	51959
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	33967
ISDYNABRMsgCountValidCount_Cnt_M_u16	19917
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	24220
ISDYNABRMsgLenValidCount_Cnt_M_u16	23339
ISDYNABRMsgTimeValidCount_Cnt_M_u16	41727
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	30529
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	39802
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	45849
ISDYNCMM208MsgTimer_mS_M_u32	580551936
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	30529
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	39802
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	56925

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3048318208
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	54375
ISDYNVOLChkSumValidCount_Cnt_M_u16	9014
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	52917
ISDYNVOLMsgCountValidCount_Cnt_M_u16	2364
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	42241
ISDYNVOLMsgLenValidCount_Cnt_M_u16	27312
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28802
ISDYNVOLMsgTimer_mS_M_u32	1472161024
IgnOnTimer_mS_M_u32	3481642240
IgnTimeOff_Sec_M_u32	452585538
ManVehSpd_Kph_M_f32	93.3451996
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	140
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	225
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3156497664
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	176
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2452665600
PrevISDATBSI412MsgDLCError_Cnt_M_u08	14
PrevISDATBSI412MsgRxTime_MSec_M_u32	344057088
PrevISDATBSI432MsgDLCError_Cnt_M_u08	250
PrevISDATBSI432MsgRxTime_MSec_M_u32	3237594368
PrevISDATDIRAMsgTxTime_MSec_M_u32	774235392
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	195
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1166603520
PrevISDYNAASMsgDLCError_Cnt_M_u08	102
PrevISDYNAASMsgRxTime_MSec_M_u32	2480235776
PrevISDYNABRMsgDLCError_Cnt_M_u08	87
PrevISDYNABRMsgRxTime_MSec_M_u32	853386496
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	8
PrevISDYNCMM208MsgRxTime_MSec_M_u32	964060416
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	202
PrevISDYNCMM388MsgRxTime_MSec_M_u32	366527744
PrevISDYNVOLMsgDLCError_Cnt_M_u08	28
PrevISDYNVOLMsgRxTime_MSec_M_u32	4087014656
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	164205824
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	247.748901
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	20227
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	50425
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	54968
VitesseVehicleBVRampValidCount_Cnt_M_u16	6766
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	29385
VitesseVehicleBVSigValidCount_Cnt_M_u16	53960
VitesseVehicleBV_Kph_M_f32	246.734894
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	56925
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	23348
VitesseVehiculeRoues_Kph_M_f32	144.030304
k_AASNTCEnableTimeout_mS_u16	33378
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	49214
k_AASNodeTimeout_mS_u16	7161
k_ABSNodeTimeout_mS_u16	60160
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	4365
k_ANGLEVOLANTSigValidThresh_Cnt_u16	28567
k_AngleVolantInvalidThresh_Cnt_u16	55818
k_AngleVolantValidThresh_Cnt_u16	8947
k_BSI552MsgTimeout_mS_u16	25447
k_BSINTCEnableTimeout_mS_u16	50606
k_BSINodeAbsentDiag_Cnt_str.Threshold	27792
k_BSINodeAbsentDiag_Cnt_str.PStep	1314
k_BSINodeAbsentDiag_Cnt_str.NStep	62185
k_BSINodeAbsentTimeout_mS_u16	28379
k_BSINodeTimeout_mS_u16	2187
k_BattOvHi_Volt_f32	20.2138996
k_BattOvLo_Volt_f32	30.5247993
k_BattUvHi_Volt_f32	13.0839996
k_BattUvLo_Volt_f32	26.4470997
k_CAVNTCEnableTimeout_mS_u16	53985
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	42724
k_CAVNodeTimeout_mS_u16	17149
k_CMM388MsgTimeout_mS_u16	64122
k_CMM388NTCEnableTimeout_mS_u16	56742
k_CMMNTCEnableTimeout_mS_u16	10
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	31840
k_CONSANGLECPKMax_HwDeg_f32	585.524597
k_CONSANGLECPKMin_HwDeg_f32	-695.963318
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	62813
k_CONSANGLECPKSigValidThresh_Cnt_u16	45620
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	25015
k_CPKVehicleSpeedValidThresh_Cnt_u16	17006
k_CityParkInputInvalidThresh_Cnt_u16	10702
k_CityParkInputValidThresh_Cnt_u16	38043
k_ComputerRazGCTSigValidThresh_Cnt_u16	28240
k_CptTemporelSigValidThresh_Cnt_u16	7922
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	62876
k_DMDFCTCPKSigValidThresh_Cnt_u16	12843
k_DMDFCTCPKValidCount_Cnt_u16	39431
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	33898
k_DMDRELAXECPKSigValidThresh_Cnt_u16	3249
k_DMDRelaxeConsistentThresh_Cnt_u16	13423
k_DateValidThresh_Cnt_u16	23780
k_DefaultVehSpd_Kph_f32	48.2508011
k_DiagMuxOnAbsentTimeout_mS_u16	32365
k_EMNodeTimeout_mS_u16	3002
k_ESPNTCEnableTimeout_mS_u16	23418
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	53512
k_EtatMTSigInvalidThresh_Cnt_u16	56931
k_EtatMTSigValidThresh_Cnt_u16	51210
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	2550
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	30801
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	50768
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	27995
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	57405
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	42083
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	49791
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	45705
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	13354
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	20147
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	59365
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	42624
k_ISDATDIRASentDiag_Cnt_str.Threshold	47308

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	21554
k_ISDATDIRASentDiag_Cnt_str.NStep	61574
k_ISDATDIRASentTimeout_mS_u16	42428
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	61857
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	29059
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	30966
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	144
k_ISDYNAASChkSumValidThresh_Cnt_u16	8695
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	7087
k_ISDYNAASMsgCountValidThresh_Cnt_u16	9421
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	33892
k_ISDYNAASMsgLenValidThresh_Cnt_u16	62157
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	27199
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	34098
k_ISDYNABRChkSumValidThresh_Cnt_u16	26177
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	51039
k_ISDYNABRMsgCountValidThresh_Cnt_u16	35806
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	51074
k_ISDYNABRMsgLenValidThresh_Cnt_u16	33740
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	21393
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	17879
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	27268
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	36652
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	5780
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	18643
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	37963
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	6598
k_ISDYNVOLChkSumValidThresh_Cnt_u16	17049
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	60885
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	40139
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	20298
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	32069
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	62290
k_IgnOnTimeout_mS_u16	31218
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	145.934906
k_PowerCutVehSpdLowThresh_Kph_f32	138.348999
k_PowerCutVehSpdLowTimeout_mS_u16	30398
k_VBattMaxAAS_Volt_f32	26.9195995
k_VBattMaxBSI_Volt_f32	1.41439998
k_VBattMaxCAV_Volt_f32	2.88860011
k_VBattMaxCMM388_Volt_f32	8.51019955
k_VBattMaxCMM_Volt_f32	13.4288998
k_VBattMaxESP_Volt_f32	1.63590002
k_VBattMinAAS_Volt_f32	1.14979994
k_VBattMinBSI_Volt_f32	1.63590002
k_VBattMinCAV_Volt_f32	21.9883003
k_VBattMinCMM388_Volt_f32	13.5389004
k_VBattMinCMM_Volt_f32	20.3610001
k_VBattMinESP_Volt_f32	13.4288998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	43747
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	2854
k_VitesseVehicleBVRampValidThresh_Cnt_u16	58805
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	64054
k_VitesseVehicleBVSigValidThresh_Cnt_u16	16296
k_VitesseVehicleBVSpeedPassThresh_kph_f32	64.748703
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	33358
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	27268
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3537765632
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	38284
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3222871040
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	202
target_SrlComInput_Per1_Batt_Volt_f32.value	10.2948999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1353266432
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	187
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.182493761
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3252135168
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	502154496
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	237
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	613737728
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1036748032
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3516015872
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1206437120
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	147809536
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	94
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	187
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4183852288
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	10
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	46
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	94
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	195
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	408331520
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1642939648
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	80
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	370402560
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	131
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	167
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	216
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	224
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1902818560
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3630
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.298346788
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	375685
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	143.233994
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	43973

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3222871040	3222871040	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3222871040	3222871040	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3222871040	3222871040	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3222871040	3222871040	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3222871040	3222871040	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3222871040	3222871040	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3222871040	3222871040	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	27792	27792	✔
BSINodeAbsentTimer_mS_M_u32	3222871040	3222871040	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3222871040	3222871040	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3222871040	3222871040	✔
CDD_SrlComVehSpd_Kph_G_f32	93.3451996	93.3451996	✔
CMM388NTCEnableTimer_mS_M_u32	3222871040	3222871040	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3222871040	3222871040	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3222871040	3222871040	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	41727	41727	✔
CONSANGLECPK_HwDeg_M_f32	-188.809692	-188.809692 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3222871040	3222871040	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3222871040	3222871040	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3222871040	3222871040	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3222871040	3222871040	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3222871040	3222871040	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3222871040	3222871040	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3222871040	3222871040	✔
ESPNTCEnableTimer_mS_M_u32	3222871040	3222871040	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3222871040	3222871040	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	12	12	✔
EffacDefaultDiagTimer_mS_M_u32[1]	13	13	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1000	1000	✔
ElecIntTimer_mS_M_u32[1]	2001	2001	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3222871040	3222871040	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	23780	23780	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3222871040	3222871040	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	45849	45849	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3222871040	3222871040	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	19998	19998	✔
ISDATBSI412MsgTimer_mS_M_u32	3222871040	3222871040	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	2187	2187	✔
ISDATBSI432MsgTimer_mS_M_u32	3222871040	3222871040	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3222871040	3222871040	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	33898	33898	✔
ISDYN2CMMMsgTimer_mS_M_u32	3222871040	3222871040	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	18916	18916	✔
ISDYNAASMsgTimer_mS_M_u32	3222871040	3222871040	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	41727	41727	✔
ISDYNABRMsgTimer_mS_M_u32	3222871040	3222871040	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	45849	45849	✔
ISDYNCMM208MsgTimer_mS_M_u32	3222871040	3222871040	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	56925	56925	✔
ISDYNCMM388MsgTimer_mS_M_u32	3222871040	3222871040	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28802	28802	✔
ISDYNVOLMsgTimer_mS_M_u32	3222871040	3222871040	✔
IgnOnTimer_mS_M_u32	3481642240	3481642240	✔
IgnTimeOff_Sec_M_u32	452585538	452585538	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	91	91	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3252135168	3252135168	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	233	233	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	502154496	502154496	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	237	237	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	613737728	613737728	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	208	208	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1036748032	1036748032	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	774235392	774235392	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	209	209	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1206437120	1206437120	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	192	192	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	147809536	147809536	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	129	129	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4183852288	4183852288	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	408331520	408331520	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	126	126	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1642939648	1642939648	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	80	80	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	370402560	370402560	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1902818560	1902818560	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	247.748901	247.748901	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	246.734894	246.734894	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	144.030304	144.030304	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	41727	41727	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	452585538	452585538	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-188.809692	-188.809692 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	93.3451996	93.3451996	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.266 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3914990592
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	51140
AASNodeAbsentTimer_mS_M_u32	1281913856
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	64885
ANGLEVOLANTSigValidCount_Cnt_M_u16	48504
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	425
AngleVolantMsgTimer_mS_M_u32	3914990592
AngleVolantValidCount_Cnt_M_u16	3931
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	4001772544
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	895005696
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1419879424
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2556847104
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	55060
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1242440704
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	43208
CAVNodeAbsentTimer_mS_M_u32	652481536
CDD_SrlComVehSpd_Kph_G_f32	607.29248
CMM388NTCEnableTimer_mS_M_u32	3702674432
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1353323520
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	38124
CMMNodeAbsentTimer_mS_M_u32	1495294976
CONSANGLECPKSigInvalidCount_Cnt_M_u16	47294
CONSANGLECPKSigValidCount_Cnt_M_u16	37010
CONSANGLECPK_Cnt_M_u16	35061
CONSANGLECPK_HwDeg_M_f32	-709.345093
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	35061
CPKVehicleSpeedMsgTimer_mS_M_u32	384893952
CPKVehicleSpeedValidCount_Cnt_M_u16	4514
CityParkInputConsistentCount_Cnt_M_u16	17119
CityParkInputInvalidCount_Cnt_M_u16	18646
CityParkInputMsgTimer_mS_M_u32	3252135168
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1626108928
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	328

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	45650944
ComputerRazGCTSigValidCount_Cnt_M_u16	15932
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	20818
DMDFCTCPKSigValidCount_Cnt_M_u16	1534
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	34359
DMDRELAXECPKSigValidCount_Cnt_M_u16	0
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	37795
DateInvalidTimer_mS_M_u32	895005696
DiagMuxOnAbsentTimer_mS_M_u32	3437347840
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2556847104
ESPNTCEnableTimer_mS_M_u32	1016165376
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	59084
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	101
EffacDefaultDiagTimer_mS_M_u32[1]	202
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2500
ElecIntTimer_mS_M_u32[1]	3501
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2083529728
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	48407
EtatMTSigValidCount_Cnt_M_u16	5351
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1920
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	52436
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	31172
ISDAT4V2BSI552MsgTimer_mS_M_u32	2292474880
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	52443
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	45363
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	5351
ISDATBSI3F2MsgTimer_mS_M_u32	1444922368
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	30276
ISDATBSI412MsgLenValidCount_Cnt_M_u16	50252
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	48407
ISDATBSI412MsgTimer_mS_M_u32	3902276608
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	8048
ISDATBSI432MsgLenValidCount_Cnt_M_u16	3152
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	1297
ISDATDIRASentFltAcc_Cnt_M_u16	41253
ISDATDIRASentTimer_mS_M_u32	384893952
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	9395
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	3931
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	49265
ISDYN2CMMMsgTimer_mS_M_u32	1036743680
ISDYNAASChkSumInvalidCount_Cnt_M_u16	15494
ISDYNAASChkSumValidCount_Cnt_M_u16	11946
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	62586
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	8043
ISDYNAASMsgLenValidCount_Cnt_M_u16	25031
ISDYNAASMsgTimeValidCount_Cnt_M_u16	15494
ISDYNAASMsgTimer_mS_M_u32	2989380608
ISDYNABRChkSumInvalidCount_Cnt_M_u16	1793
ISDYNABRChkSumValidCount_Cnt_M_u16	39309
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	30757
ISDYNABRMsgCountValidCount_Cnt_M_u16	13193
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	12125
ISDYNABRMsgLenValidCount_Cnt_M_u16	4209
ISDYNABRMsgTimeValidCount_Cnt_M_u16	35061
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	14835
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	48903
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	5351
ISDYNCMM208MsgTimer_mS_M_u32	3626185728
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	14835
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	48903
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	60825

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3814577152
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	47612
ISDYNVOLChkSumValidCount_Cnt_M_u16	42064
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	52624
ISDYNVOLMsgCountValidCount_Cnt_M_u16	54460
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	53805
ISDYNVOLMsgLenValidCount_Cnt_M_u16	55265
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	38124
ISDYNVOLMsgTimer_mS_M_u32	1681167360
IgnOnTimer_mS_M_u32	3856782336
IgnTimeOff_Sec_M_u32	865596314
ManVehSpd_Kph_M_f32	243.493698
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	141
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	23
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	918930432
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	254
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3726681088
PrevISDATBSI412MsgDLCError_Cnt_M_u08	13
PrevISDATBSI412MsgRxTime_MSec_M_u32	1475154944
PrevISDATBSI432MsgDLCError_Cnt_M_u08	175
PrevISDATBSI432MsgRxTime_MSec_M_u32	2315613184
PrevISDATDIRAMsgTxTime_MSec_M_u32	2600539136
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	56
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1964499968
PrevISDYNAASMsgDLCError_Cnt_M_u08	204
PrevISDYNAASMsgRxTime_MSec_M_u32	2280821760
PrevISDYNABRMsgDLCError_Cnt_M_u08	213
PrevISDYNABRMsgRxTime_MSec_M_u32	467260416
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	227
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1527747584
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	245
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3345511424
PrevISDYNVOLMsgDLCError_Cnt_M_u08	255
PrevISDYNVOLMsgRxTime_MSec_M_u32	1587680256
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1926628352
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	624.423096
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	4521
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	9861
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	36490
VitesseVehicleBVRampValidCount_Cnt_M_u16	14886
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	14294
VitesseVehicleBVSigValidCount_Cnt_M_u16	44697
VitesseVehicleBV_Kph_M_f32	532.603516
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	60825
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	28117
VitesseVehiculeRoues_Kph_M_f32	418.96759
k_AASNTCEnableTimeout_mS_u16	14028
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	3062
k_AASNodeTimeout_mS_u16	8581
k_ABSNodeTimeout_mS_u16	25775
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	40779
k_ANGLEVOLANTSigValidThresh_Cnt_u16	19051
k_AngleVolantInvalidThresh_Cnt_u16	38674
k_AngleVolantValidThresh_Cnt_u16	18646
k_BSI552MsgTimeout_mS_u16	57660
k_BSINTCEnableTimeout_mS_u16	17768
k_BSINodeAbsentDiag_Cnt_str.Threshold	44422
k_BSINodeAbsentDiag_Cnt_str.PStep	8719
k_BSINodeAbsentDiag_Cnt_str.NStep	26363
k_BSINodeAbsentTimeout_mS_u16	27041
k_BSINodeTimeout_mS_u16	1297
k_BattOvHi_Volt_f32	20.9192009
k_BattOvLo_Volt_f32	23.9780006
k_BattUvHi_Volt_f32	14.1886997
k_BattUvLo_Volt_f32	27.7686996
k_CAVNTCEnableTimeout_mS_u16	28940
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	52742
k_CAVNodeTimeout_mS_u16	17978
k_CMM388MsgTimeout_mS_u16	708
k_CMM388NTCEnableTimeout_mS_u16	2368
k_CMMNTCEnableTimeout_mS_u16	44755
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	47697
k_CONSANGLECPKMax_HwDeg_f32	190.429703
k_CONSANGLECPKMin_HwDeg_f32	-577.701599
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	43161
k_CONSANGLECPKSigValidThresh_Cnt_u16	26837
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	51275
k_CPKVehicleSpeedValidThresh_Cnt_u16	51367
k_CityParkInputInvalidThresh_Cnt_u16	48711
k_CityParkInputValidThresh_Cnt_u16	17119
k_ComputerRazGCTSigValidThresh_Cnt_u16	64513
k_CptTemporelSigValidThresh_Cnt_u16	4313
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	27229
k_DMDFCTCPKSigValidThresh_Cnt_u16	35697
k_DMDFCTCPKValidCount_Cnt_u16	14876
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	49265
k_DMDRELAXECPKSigValidThresh_Cnt_u16	56925
k_DMDRelaxeConsistentThresh_Cnt_u16	57123
k_DateValidThresh_Cnt_u16	31172
k_DefaultVehSpd_Kph_f32	161.945908
k_DiagMuxOnAbsentTimeout_mS_u16	11947
k_EMNodeTimeout_mS_u16	8195
k_ESPNTCEnableTimeout_mS_u16	34884
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	23641
k_EtatMTSigInvalidThresh_Cnt_u16	13448
k_EtatMTSigValidThresh_Cnt_u16	44628
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	35726
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	18238
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	49600
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	60128
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	47352
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	46792
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	54005
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	51605
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	59892
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	21977
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	61697
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	46448
k_ISDATDIRASentDiag_Cnt_str.Threshold	12314

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	25984
k_ISDATDIRASentDiag_Cnt_str.NStep	21340
k_ISDATDIRASentTimeout_mS_u16	33405
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	38925
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	425
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	8144
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	49665
k_ISDYNAASChkSumValidThresh_Cnt_u16	38029
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	45861
k_ISDYNAASMsgCountValidThresh_Cnt_u16	44681
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	34437
k_ISDYNAASMsgLenValidThresh_Cnt_u16	60681
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	64115
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	37787
k_ISDYNABRChkSumValidThresh_Cnt_u16	50991
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	4628
k_ISDYNABRMsgCountValidThresh_Cnt_u16	23383
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	36844
k_ISDYNABRMsgLenValidThresh_Cnt_u16	8652
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	36926
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	32045
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	10341
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	21484
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	14453
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	14456
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	21710
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	41631
k_ISDYNVOLChkSumValidThresh_Cnt_u16	3815
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	18353
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	29713
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	27027
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	26211
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	61050
k_IgnOnTimeout_mS_u16	12827
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	161.3936
k_PowerCutVehSpdLowThresh_Kph_f32	224.151398
k_PowerCutVehSpdLowTimeout_mS_u16	51640
k_VBattMaxAAS_Volt_f32	22.9717999
k_VBattMaxBSI_Volt_f32	7.77080011
k_VBattMaxCAV_Volt_f32	12.0169001
k_VBattMaxCMM388_Volt_f32	31.3103008
k_VBattMaxCMM_Volt_f32	20.2604008
k_VBattMaxESP_Volt_f32	30.3412991
k_VBattMinAAS_Volt_f32	0.0888999999
k_VBattMinBSI_Volt_f32	30.3412991
k_VBattMinCAV_Volt_f32	29.8381996
k_VBattMinCMM388_Volt_f32	4.71939993
k_VBattMinCMM_Volt_f32	23.0217991
k_VBattMinESP_Volt_f32	20.2604008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	62535
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	31295
k_VitesseVehicleBVRampValidThresh_Cnt_u16	34960
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	8016
k_VitesseVehicleBVSigValidThresh_Cnt_u16	46520
k_VitesseVehicleBVSpeedPassThresh_kph_f32	110.075798
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	25544
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	8676
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	895005696
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	11650
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3670241024
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	245
target_SrlComInput_Per1_Batt_Volt_f32.value	11.3275995
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	615982080
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	252
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.875210881
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3605779456
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3844600832
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	867439616
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	185
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2324706304
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2981909504
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1899525120
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2432996352
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	61
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	71
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	88
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	90
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3956356096
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	70
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	97
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	111
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2406405120
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3576361984
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	115
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	456594432
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	97
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2826085376
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3361
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.759341776
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	859136
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	79.7463989
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	33635

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3670241024	3670241024	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3670241024	3670241024	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3670241024	3670241024	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3670241024	3670241024	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3670241024	3670241024	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3670241024	3670241024	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3670241024	3670241024	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	44422	44422	✔
BSINodeAbsentTimer_mS_M_u32	3670241024	3670241024	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3670241024	3670241024	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3670241024	3670241024	✔
CDD_SrlComVehSpd_Kph_G_f32	243.493698	243.493698	✔
CMM388NTCEnableTimer_mS_M_u32	3670241024	3670241024	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3670241024	3670241024	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3670241024	3670241024	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	35061	35061	✔
CONSANGLECPK_HwDeg_M_f32	-709.345093	-709.345093 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3670241024	3670241024	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3670241024	3670241024	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3670241024	3670241024	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3670241024	3670241024	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3670241024	3670241024	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3670241024	3670241024	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3670241024	3670241024	✔
ESPNTCEnableTimer_mS_M_u32	3670241024	3670241024	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3670241024	3670241024	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	101	101	✔
EffacDefaultDiagTimer_mS_M_u32[1]	202	202	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2500	2500	✔
ElecIntTimer_mS_M_u32[1]	3501	3501	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3670241024	3670241024	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	31172	31172	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3670241024	3670241024	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	5351	5351	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3670241024	3670241024	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	48407	48407	✔
ISDATBSI412MsgTimer_mS_M_u32	3670241024	3670241024	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	1297	1297	✔
ISDATBSI432MsgTimer_mS_M_u32	3670241024	3670241024	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3670241024	3670241024	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	49265	49265	✔
ISDYN2CMMMsgTimer_mS_M_u32	3670241024	3670241024	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	15494	15494	✔
ISDYNAASMsgTimer_mS_M_u32	3670241024	3670241024	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	35061	35061	✔
ISDYNABRMsgTimer_mS_M_u32	3670241024	3670241024	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	5351	5351	✔
ISDYNCMM208MsgTimer_mS_M_u32	3670241024	3670241024	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	60825	60825	✔
ISDYNCMM388MsgTimer_mS_M_u32	3670241024	3670241024	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	38124	38124	✔
ISDYNVOLMsgTimer_mS_M_u32	3670241024	3670241024	✔
IgnOnTimer_mS_M_u32	3856782336	3856782336	✔
IgnTimeOff_Sec_M_u32	865596314	865596314	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	81	81	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3605779456	3605779456	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	170	170	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3844600832	3844600832	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	223	223	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	867439616	867439616	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	185	185	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2324706304	2324706304	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2600539136	2600539136	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	121	121	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1899525120	1899525120	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	240	240	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2432996352	2432996352	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	57	57	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3956356096	3956356096	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	118	118	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2406405120	2406405120	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	166	166	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3576361984	3576361984	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	115	115	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	456594432	456594432	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2826085376	2826085376	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	624.423096	624.423096	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	532.603516	532.603516	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	418.96759	418.96759	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	35061	35061	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	865596314	865596314	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-709.345093	-709.345093 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.267 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3835737856
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	4961
AASNodeAbsentTimer_mS_M_u32	1094018816
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	54351
ANGLEVOLANTSigValidCount_Cnt_M_u16	53251
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	14770
AngleVolantMsgTimer_mS_M_u32	3835737856
AngleVolantValidCount_Cnt_M_u16	283
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	31205120
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2539955968
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3377059584
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	16488192
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	33650
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	990140160
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	34518
CAVNodeAbsentTimer_mS_M_u32	2822932224
CDD_SrlComVehSpd_Kph_G_f32	246.959
CMM388NTCEnableTimer_mS_M_u32	2413283072
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3270543104
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	53033
CMMNodeAbsentTimer_mS_M_u32	651007744
CONSANGLECPKSigInvalidCount_Cnt_M_u16	63858
CONSANGLECPKSigValidCount_Cnt_M_u16	60854
CONSANGLECPK_Cnt_M_u16	20621
CONSANGLECPK_HwDeg_M_f32	117.398201
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	20621
CPKVehicleSpeedMsgTimer_mS_M_u32	2010887936
CPKVehicleSpeedValidCount_Cnt_M_u16	15919
CityParkInputConsistentCount_Cnt_M_u16	30351
CityParkInputInvalidCount_Cnt_M_u16	20906
CityParkInputMsgTimer_mS_M_u32	3605779456
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	329869056
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	30421

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	113575680
ComputerRazGCTSigValidCount_Cnt_M_u16	14456
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	10294
DMDFCTCPKSigValidCount_Cnt_M_u16	58866
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	49673
DMDRELAXECPKSigValidCount_Cnt_M_u16	65535
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	15555
DateInvalidTimer_mS_M_u32	2539955968
DiagMuxOnAbsentTimer_mS_M_u32	151615232
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	16488192
ESPNTCEnableTimer_mS_M_u32	1421502208
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	34121
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	305
EffacDefaultDiagTimer_mS_M_u32[1]	706
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	979
ElecIntTimer_mS_M_u32[1]	1086
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2896058112
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	5032
EtatMTSigValidCount_Cnt_M_u16	30712
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	38188
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	49392
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	8864
ISDAT4V2BSI552MsgTimer_mS_M_u32	2822870784
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	60890
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	52371
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	30712
ISDATBSI3F2MsgTimer_mS_M_u32	3847190272
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	58018
ISDATBSI412MsgLenValidCount_Cnt_M_u16	17482
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	5032
ISDATBSI412MsgTimer_mS_M_u32	1592178432
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	16285
ISDATBSI432MsgLenValidCount_Cnt_M_u16	9405
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	54779
ISDATDIRASentFltAcc_Cnt_M_u16	20927
ISDATDIRASentTimer_mS_M_u32	2010887936
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	62803
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	283
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	5849
ISDYN2CMMMsgTimer_mS_M_u32	3104597760
ISDYNAASChkSumInvalidCount_Cnt_M_u16	15643
ISDYNAASChkSumValidCount_Cnt_M_u16	8815
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	36286
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	28397
ISDYNAASMsgLenValidCount_Cnt_M_u16	17305
ISDYNAASMsgTimeValidCount_Cnt_M_u16	15643
ISDYNAASMsgTimer_mS_M_u32	4284729088
ISDYNABRChkSumInvalidCount_Cnt_M_u16	57642
ISDYNABRChkSumValidCount_Cnt_M_u16	34118
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	50750
ISDYNABRMsgCountValidCount_Cnt_M_u16	20434
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	53653
ISDYNABRMsgLenValidCount_Cnt_M_u16	43545
ISDYNABRMsgTimeValidCount_Cnt_M_u16	20621
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	50248
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	24525
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	30712
ISDYNCMM208MsgTimer_mS_M_u32	4177864448
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	50248
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	24525
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	56929

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2312455936
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	28088
ISDYNVOLChkSumValidCount_Cnt_M_u16	10876
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	11132
ISDYNVOLMsgCountValidCount_Cnt_M_u16	61880
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	34598
ISDYNVOLMsgLenValidCount_Cnt_M_u16	29131
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	53033
ISDYNVOLMsgTimer_mS_M_u32	3528525568
IgnOnTimer_mS_M_u32	2454275840
IgnTimeOff_Sec_M_u32	1100739175
ManVehSpd_Kph_M_f32	491.651215
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	142
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	195
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1532851968
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	21
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3905738496
PrevISDATBSI412MsgDLCError_Cnt_M_u08	113
PrevISDATBSI412MsgRxTime_MSec_M_u32	2032633600
PrevISDATBSI432MsgDLCError_Cnt_M_u08	85
PrevISDATBSI432MsgRxTime_MSec_M_u32	1012819712
PrevISDATDIRAMsgTxTime_MSec_M_u32	4293625600
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	20
PrevISDYN2CMMMsgRxTime_MSec_M_u32	283580160
PrevISDYNAASMsgDLCError_Cnt_M_u08	223
PrevISDYNAASMsgRxTime_MSec_M_u32	3742828288
PrevISDYNABRMsgDLCError_Cnt_M_u08	44
PrevISDYNABRMsgRxTime_MSec_M_u32	3496036096
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	161
PrevISDYNCMM208MsgRxTime_MSec_M_u32	432015104
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	93
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3493160704
PrevISDYNVOLMsgDLCError_Cnt_M_u08	69
PrevISDYNVOLMsgRxTime_MSec_M_u32	2030601984
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	942454528
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	98.1417999
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	4147
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	27999
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	23952
VitesseVehicleBVRampValidCount_Cnt_M_u16	63100
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	59692
VitesseVehicleBVSigValidCount_Cnt_M_u16	49312
VitesseVehicleBV_Kph_M_f32	1.84549999
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	56929
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	31086
VitesseVehiculeRoues_Kph_M_f32	295.32251
k_AASNTCEnableTimeout_mS_u16	25352
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	14154
k_AASNodeTimeout_mS_u16	31839
k_ABSNodeTimeout_mS_u16	41503
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	60428
k_ANGLEVOLANTSigValidThresh_Cnt_u16	38508
k_AngleVolantInvalidThresh_Cnt_u16	3191
k_AngleVolantValidThresh_Cnt_u16	20906
k_BSI552MsgTimeout_mS_u16	31545
k_BSINTCEnableTimeout_mS_u16	44469
k_BSINodeAbsentDiag_Cnt_str.Threshold	28430
k_BSINodeAbsentDiag_Cnt_str.PStep	22197
k_BSINodeAbsentDiag_Cnt_str.NStep	23856
k_BSINodeAbsentTimeout_mS_u16	57802
k_BSINodeTimeout_mS_u16	54779
k_BattOvHi_Volt_f32	25.8472004
k_BattOvLo_Volt_f32	12.1955004
k_BattUvHi_Volt_f32	0.398900002
k_BattUvLo_Volt_f32	26.1506996
k_CAVNTCEnableTimeout_mS_u16	12552
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	36636
k_CAVNodeTimeout_mS_u16	16638
k_CMM388MsgTimeout_mS_u16	25185
k_CMM388NTCEnableTimeout_mS_u16	16109
k_CMMNTCEnableTimeout_mS_u16	10226
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	33786
k_CONSANGLECPKMax_HwDeg_f32	34.8482018
k_CONSANGLECPKMin_HwDeg_f32	-207.973694
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	44385
k_CONSANGLECPKSigValidThresh_Cnt_u16	34926
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	8205
k_CPKVehicleSpeedValidThresh_Cnt_u16	14201
k_CityParkInputInvalidThresh_Cnt_u16	21336
k_CityParkInputValidThresh_Cnt_u16	30351
k_ComputerRazGCTSigValidThresh_Cnt_u16	30824
k_CptTemporelSigValidThresh_Cnt_u16	50593
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	8341
k_DMDFCTCPKSigValidThresh_Cnt_u16	14617
k_DMDFCTCPKValidCount_Cnt_u16	31322
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	5849
k_DMDRELAXECPKSigValidThresh_Cnt_u16	39125
k_DMDRelaxeConsistentThresh_Cnt_u16	11907
k_DateValidThresh_Cnt_u16	8864
k_DefaultVehSpd_Kph_f32	195.345093
k_DiagMuxOnAbsentTimeout_mS_u16	46955
k_EMNodeTimeout_mS_u16	6051
k_ESPNTCEnableTimeout_mS_u16	55394
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	48610
k_EtatMTSigInvalidThresh_Cnt_u16	13461
k_EtatMTSigValidThresh_Cnt_u16	8945
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	41540
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	23284
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	48620
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	59339
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	2372
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	12566
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	30990
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	16622
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	61457
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	31201
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	29737
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	9757
k_ISDATDIRASentDiag_Cnt_str.Threshold	53628

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	31362
k_ISDATDIRASentDiag_Cnt_str.NStep	51301
k_ISDATDIRASentTimeout_mS_u16	24246
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	12870
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	14770
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	16830
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	45098
k_ISDYNAASChkSumValidThresh_Cnt_u16	37958
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	5438
k_ISDYNAASMsgCountValidThresh_Cnt_u16	57042
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	29342
k_ISDYNAASMsgLenValidThresh_Cnt_u16	10707
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	42580
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	7387
k_ISDYNABRChkSumValidThresh_Cnt_u16	64991
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	53874
k_ISDYNABRMsgCountValidThresh_Cnt_u16	12902
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	56873
k_ISDYNABRMsgLenValidThresh_Cnt_u16	54345
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	61361
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	56743
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	36927
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	16682
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	9039
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	24323
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	3522
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	35217
k_ISDYNVOLChkSumValidThresh_Cnt_u16	36985
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	13978
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	1466
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	65076
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	29572
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	7294
k_IgnOnTimeout_mS_u16	51997
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	87.5018005
k_PowerCutVehSpdLowThresh_Kph_f32	35.2284012
k_PowerCutVehSpdLowTimeout_mS_u16	23108
k_VBattMaxAAS_Volt_f32	24.3073006
k_VBattMaxBSI_Volt_f32	15.0608997
k_VBattMaxCAV_Volt_f32	9.3156004
k_VBattMaxCMM388_Volt_f32	7.96070004
k_VBattMaxCMM_Volt_f32	29.9923992
k_VBattMaxESP_Volt_f32	9.64309978
k_VBattMinAAS_Volt_f32	30.5331993
k_VBattMinBSI_Volt_f32	9.64309978
k_VBattMinCAV_Volt_f32	27.4915009
k_VBattMinCMM388_Volt_f32	23.2481995
k_VBattMinCMM_Volt_f32	17.0354004
k_VBattMinESP_Volt_f32	29.9923992
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	34200
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	65392
k_VitesseVehicleBVRampValidThresh_Cnt_u16	64124
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	47484
k_VitesseVehicleBVSigValidThresh_Cnt_u16	49668
k_VitesseVehicleBVSpeedPassThresh_kph_f32	236.847
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	21974
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	46914
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2539955968
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	48714
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3486545408
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	93
target_SrlComInput_Per1_Batt_Volt_f32.value	7.5401001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2399753984
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	188
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.939722776
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1730889472
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3572950784
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3251799808
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3586008832
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3099182848
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	4
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	314926848
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2346780416
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	212
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4126877440
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	153
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	176
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	161629952
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	231
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3505252096
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	185
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3611920128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1373034240
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3096
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.735108078
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	978222
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	89.6934967
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	8965

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3486545408	3486545408	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	14770	14770	✔
AngleVolantMsgTimer_mS_M_u32	3486545408	3486545408	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	28430	28430	✔
BSINodeAbsentTimer_mS_M_u32	3486545408	3486545408	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3486545408	3486545408	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3486545408	3486545408	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	20621	20621	✔
CONSANGLECPK_HwDeg_M_f32	117.398201	117.398201 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	20621	20621	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2010887936	2010887936	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	15919	15919	✔
CityParkInputConsistentCount_Cnt_M_u16	30351	30351	✔
CityParkInputInvalidCount_Cnt_M_u16	20908	20908	✔
CityParkInputMsgTimer_mS_M_u32	3486545408	3486545408	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3486545408	3486545408	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3486545408	3486545408	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3486545408	3486545408	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3486545408	3486545408	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3486545408	3486545408	✔
ESPNTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3486545408	3486545408	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	305	305	✔
EffacDefaultDiagTimer_mS_M_u32[1]	706	706	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3486545408	3486545408	✔
ElecIntTimer_mS_M_u32[1]	1086	1086	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3486545408	3486545408	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3486545408	3486545408	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3486545408	3486545408	✔
IgnOnTimer_mS_M_u32	3486545408	3486545408	✔
IgnTimeOff_Sec_M_u32	1100739175	1100739175	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	35	35	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1730889472	1730889472	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	16	16	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3572950784	3572950784	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	169	169	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3251799808	3251799808	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	148	148	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3586008832	3586008832	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4293625600	4293625600	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	4	4	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	314926848	314926848	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	216	216	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2346780416	2346780416	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	88	88	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4126877440	4126877440	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	129	129	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	161629952	161629952	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	231	231	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3505252096	3505252096	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	185	185	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3611920128	3611920128	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1373034240	1373034240	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	98.1417999	98.1417999	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	1.84549999	1.84549999	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	295.32251	295.32251	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	20621	20621	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1100739175	1100739175	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	117.398201	117.398201 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	195.345093	195.345093	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.268 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2706939392
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	46871
AASNodeAbsentTimer_mS_M_u32	4200238592
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	20043
ANGLEVOLANTSigValidCount_Cnt_M_u16	42991
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	51236
AngleVolantMsgTimer_mS_M_u32	2706939392
AngleVolantValidCount_Cnt_M_u16	41063
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3278261760
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3301756416
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2145205760
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3485990400
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	36066
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	883801600
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	6455
CAVNodeAbsentTimer_mS_M_u32	3786616320
CDD_SrlComVehSpd_Kph_G_f32	398.692108
CMM388NTCEnableTimer_mS_M_u32	267611648
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3383307776
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	6653
CMMNodeAbsentTimer_mS_M_u32	642907648
CONSANGLECPKSigInvalidCount_Cnt_M_u16	55779
CONSANGLECPKSigValidCount_Cnt_M_u16	35286
CONSANGLECPK_Cnt_M_u16	32081
CONSANGLECPK_HwDeg_M_f32	-255.805695
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	32081
CPKVehicleSpeedMsgTimer_mS_M_u32	2477235712
CPKVehicleSpeedValidCount_Cnt_M_u16	48500
CityParkInputConsistentCount_Cnt_M_u16	4107

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	47036
CityParkInputMsgTimer_mS_M_u32	1730889472
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1392414208
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	23739
ComputerRazGCTSigInvalidTimer_mS_M_u32	4029394432
ComputerRazGCTSigValidCount_Cnt_M_u16	44624
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	25624
DMDFCTCPKSigValidCount_Cnt_M_u16	38819
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	60701
DMDRELAXECPKSigValidCount_Cnt_M_u16	28361
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	37872
DateInvalidTimer_mS_M_u32	3301756416
DiagMuxOnAbsentTimer_mS_M_u32	3340656128
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3485990400
ESPNTCEnableTimer_mS_M_u32	332107264
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	62556
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	999
EffacDefaultDiagTimer_mS_M_u32[1]	1001
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	17
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3353329152
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	5506
EtatMTSigValidCount_Cnt_M_u16	42322
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	28341
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	30760
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	6553
ISDAT4V2BSI552MsgTimer_mS_M_u32	1911946752
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	27242
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	11009
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	42322
ISDATBSI3F2MsgTimer_mS_M_u32	3394002432
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	47380
ISDATBSI412MsgLenValidCount_Cnt_M_u16	45275
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	5506
ISDATBSI412MsgTimer_mS_M_u32	3397819904
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	39073
ISDATBSI432MsgLenValidCount_Cnt_M_u16	58880
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	65480
ISDATDIRASentFltAcc_Cnt_M_u16	40060
ISDATDIRASentTimer_mS_M_u32	2477235712
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	9983
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	41063
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	58415
ISDYN2CMMMsgTimer_mS_M_u32	2933231104
ISDYNAASChkSumInvalidCount_Cnt_M_u16	41449
ISDYNAASChkSumValidCount_Cnt_M_u16	48812
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	18046
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	31986
ISDYNAASMsgLenValidCount_Cnt_M_u16	11182
ISDYNAASMsgTimeValidCount_Cnt_M_u16	41449
ISDYNAASMsgTimer_mS_M_u32	4048514560
ISDYNABRChkSumInvalidCount_Cnt_M_u16	43834
ISDYNABRChkSumValidCount_Cnt_M_u16	43942
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	21120
ISDYNABRMsgCountValidCount_Cnt_M_u16	33411
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	40314
ISDYNABRMsgLenValidCount_Cnt_M_u16	41133
ISDYNABRMsgTimeValidCount_Cnt_M_u16	32081
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	24068

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	2869
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	42322
ISDYNCMM208MsgTimer_mS_M_u32	3253423616
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	24068
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	2869
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	41109
ISDYNCMM388MsgTimer_mS_M_u32	4160417280
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	5393
ISDYNVOLChkSumValidCount_Cnt_M_u16	27524
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	62022
ISDYNVOLMsgCountValidCount_Cnt_M_u16	3153
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	41669
ISDYNVOLMsgLenValidCount_Cnt_M_u16	61337
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	6653
ISDYNVOLMsgTimer_mS_M_u32	3179785728
IgnOnTimer_mS_M_u32	2929651200
IgnTimeOff_Sec_M_u32	2143986028
ManVehSpd_Kph_M_f32	235.708099
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	143
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	197
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	539123200
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	192
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3981721088
PrevISDATBSI412MsgDLCError_Cnt_M_u08	16
PrevISDATBSI412MsgRxTime_MSec_M_u32	1124347392
PrevISDATBSI432MsgDLCError_Cnt_M_u08	8
PrevISDATBSI432MsgRxTime_MSec_M_u32	3974073856
PrevISDATDIRAMsgTxTime_MSec_M_u32	3199741440
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	190
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2919595520
PrevISDYNAASMsgDLCError_Cnt_M_u08	196
PrevISDYNAASMsgRxTime_MSec_M_u32	792047104
PrevISDYNABRMsgDLCError_Cnt_M_u08	167
PrevISDYNABRMsgRxTime_MSec_M_u32	1414983168
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	105
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1664790016
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	90
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1297780224
PrevISDYNVOLMsgDLCError_Cnt_M_u08	146
PrevISDYNVOLMsgRxTime_MSec_M_u32	123809280
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3602161152
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	481.080109
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	12576
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	18012
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	64777
VitesseVehicleBVRampValidCount_Cnt_M_u16	24325
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	50100
VitesseVehicleBVSigValidCount_Cnt_M_u16	35352

Name	Input Value
VitesseVehicleBV_Kph_M_f32	572.554199
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	41109
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	31792
VitesseVehiculeRoues_Kph_M_f32	490.755798
k_AASNTCEnableTimeout_mS_u16	61920
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	31194
k_AASNodeTimeout_mS_u16	6492
k_ABSNodeTimeout_mS_u16	55901
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	3924
k_ANGLEVOLANTSigValidThresh_Cnt_u16	3315
k_AngleVolantInvalidThresh_Cnt_u16	38610
k_AngleVolantValidThresh_Cnt_u16	47036
k_BSI552MsgTimeout_mS_u16	25295
k_BSINTCEnableTimeout_mS_u16	44633
k_BSINodeAbsentDiag_Cnt_str.Threshold	19762
k_BSINodeAbsentDiag_Cnt_str.PStep	50813
k_BSINodeAbsentDiag_Cnt_str.NStep	13132
k_BSINodeAbsentTimeout_mS_u16	12252
k_BSINodeTimeout_mS_u16	65480
k_BattOvHi_Volt_f32	20.3999996
k_BattOvLo_Volt_f32	9.78040028
k_BattUvHi_Volt_f32	6.1638999
k_BattUvLo_Volt_f32	21.9335995
k_CAVNTCEnableTimeout_mS_u16	4514
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	39013
k_CAVNodeTimeout_mS_u16	13119
k_CMM388MsgTimeout_mS_u16	51735
k_CMM388NTCEnableTimeout_mS_u16	25715
k_CMMNTCEnableTimeout_mS_u16	7202
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	35980
k_CONSANGLECPKMax_HwDeg_f32	570.378296
k_CONSANGLECPKMin_HwDeg_f32	-415.508514
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	13205
k_CONSANGLECPKSigValidThresh_Cnt_u16	20272
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	26194
k_CPKVehicleSpeedValidThresh_Cnt_u16	54927
k_CityParkInputInvalidThresh_Cnt_u16	36016
k_CityParkInputValidThresh_Cnt_u16	4107
k_ComputerRazGCTSigValidThresh_Cnt_u16	33472
k_CptTemporelSigValidThresh_Cnt_u16	63447
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	45178
k_DMDFCTCPKSigValidThresh_Cnt_u16	62381
k_DMDFCTCPKValidCount_Cnt_u16	18474
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	58415
k_DMDRELAXECPKSigValidThresh_Cnt_u16	51962
k_DMDRelaxeConsistentThresh_Cnt_u16	16880
k_DateValidThresh_Cnt_u16	6553
k_DefaultVehSpd_Kph_f32	235.694305
k_DiagMuxOnAbsentTimeout_mS_u16	16567
k_EMNodeTimeout_mS_u16	33616
k_ESPNTCEnableTimeout_mS_u16	21651
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	32468
k_EtatMTSigInvalidThresh_Cnt_u16	7417
k_EtatMTSigValidThresh_Cnt_u16	16037
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	31661
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	36444
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	60916
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	32919
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	30958
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	40376
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	61518

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	38253
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	22341
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	20821
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	65341
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	60322
k_ISDATDIRASentDiag_Cnt_str.Threshold	1905
k_ISDATDIRASentDiag_Cnt_str.PStep	4278
k_ISDATDIRASentDiag_Cnt_str.NStep	49319
k_ISDATDIRASentTimeout_mS_u16	25238
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	43815
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	51236
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	34943
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	15930
k_ISDYNAASChkSumValidThresh_Cnt_u16	32422
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	25984
k_ISDYNAASMsgCountValidThresh_Cnt_u16	54659
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	50910
k_ISDYNAASMsgLenValidThresh_Cnt_u16	57600
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	32059
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	21416
k_ISDYNABRChkSumValidThresh_Cnt_u16	15707
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	40930
k_ISDYNABRMsgCountValidThresh_Cnt_u16	52422
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	60669
k_ISDYNABRMsgLenValidThresh_Cnt_u16	1884
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	32997
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	39108
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	25661
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	46843
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	24907
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	64239
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	58228
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	16455
k_ISDYNVOLChkSumValidThresh_Cnt_u16	18510
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	25705
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	64074
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	34270
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	58030
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	9215
k_IgnOnTimeout_mS_u16	43939
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	119.724098
k_PowerCutVehSpdLowThresh_Kph_f32	124.544403
k_PowerCutVehSpdLowTimeout_mS_u16	64556
k_VBattMaxAAS_Volt_f32	16.7619991
k_VBattMaxBSI_Volt_f32	11.0501003
k_VBattMaxCAV_Volt_f32	7.30630016
k_VBattMaxCMM388_Volt_f32	6.79500008
k_VBattMaxCMM_Volt_f32	7.05429983
k_VBattMaxESP_Volt_f32	5.4217
k_VBattMinAAS_Volt_f32	20.3528996
k_VBattMinBSI_Volt_f32	5.4217
k_VBattMinCAV_Volt_f32	1.85979998
k_VBattMinCMM388_Volt_f32	22.3883991
k_VBattMinCMM_Volt_f32	26.9438992
k_VBattMinESP_Volt_f32	7.05429983
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	31025
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	59496
k_VitesseVehicleBVRampValidThresh_Cnt_u16	34118
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	48772
k_VitesseVehicleBVSigValidThresh_Cnt_u16	16812
k_VitesseVehicleBVSpeedPassThresh_kph_f32	339.934998
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	44087
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	46259
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3301756416
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	45551
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1367695616
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	90
target_SrlComInput_Per1_Batt_Volt_f32.value	18.9708996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2359213568
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	232
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0428109393
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	127
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	939060736
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	622202368
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3573755392
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1338002944
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2639097344
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3316289024
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3503795712
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	45
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	109
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	179
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	24
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	587812352
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	50
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	106
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3969117696
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3442544128
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	815672832
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	78
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	108
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	148
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	238
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1513504256
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2776
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.957528889
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	244428
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	73.3991013

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	49322		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	51236	51236	✔
AngleVolantMsgTimer_mS_M_u32	1367695616	1367695616	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	19762	19762	✔
BSINodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	32081	32081	✔
CONSANGLECPK_HwDeg_M_f32	-255.805695	-255.805695 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	32081	32081	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2477235712	2477235712	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	48500	48500	✔
CityParkInputConsistentCount_Cnt_M_u16	4107	4107	✔
CityParkInputInvalidCount_Cnt_M_u16	47036	47036	✔
CityParkInputMsgTimer_mS_M_u32	1367695616	1367695616	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1367695616	1367695616	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1367695616	1367695616	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1367695616	1367695616	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1367695616	1367695616	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1367695616	1367695616	✔
ESPNTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1367695616	1367695616	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	1001	1001	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1367695616	1367695616	✔
ElecIntTimer_mS_M_u32[1]	17	17	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1367695616	1367695616	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1367695616	1367695616	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1367695616	1367695616	✔
IgnOnTimer_mS_M_u32	1367695616	1367695616	✔
IgnTimeOff_Sec_M_u32	2143986028	2143986028	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	127	127	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	939060736	939060736	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	206	206	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	622202368	622202368	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	92	92	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3573755392	3573755392	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	48	48	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1338002944	1338002944	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3199741440	3199741440	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	205	205	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3316289024	3316289024	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	166	166	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3503795712	3503795712	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	24	24	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	587812352	587812352	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	2	2	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3969117696	3969117696	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	229	229	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3442544128	3442544128	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	198	198	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	815672832	815672832	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1513504256	1513504256	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	481.080109	481.080109	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	572.554199	572.554199	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	490.755798	490.755798	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	32081	32081	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2143986028	2143986028	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-255.805695	-255.805695 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	235.694305	235.694305	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.269 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2408376576
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	26705
AASNodeAbsentTimer_mS_M_u32	944183552
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	5299
ANGLEVOLANTSigValidCount_Cnt_M_u16	8585
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	43306
AngleVolantMsgTimer_mS_M_u32	2408376576
AngleVolantValidCount_Cnt_M_u16	38113
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3156465920
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1911576832
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1316948224
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2042546432
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	29934
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	302876928
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	3183
CAVNodeAbsentTimer_mS_M_u32	750598400
CDD_SrlComVehSpd_Kph_G_f32	228.999207
CMM388NTCEnableTimer_mS_M_u32	4076632320
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3436919040
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	31966
CMMNodeAbsentTimer_mS_M_u32	505465088
CONSANGLECPKSigInvalidCount_Cnt_M_u16	33004
CONSANGLECPKSigValidCount_Cnt_M_u16	51922
CONSANGLECPK_Cnt_M_u16	40033
CONSANGLECPK_HwDeg_M_f32	-481.584686
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	40033
CPKVehicleSpeedMsgTimer_mS_M_u32	3030378752
CPKVehicleSpeedValidCount_Cnt_M_u16	57568

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	54773
CityParkInputInvalidCount_Cnt_M_u16	13281
CityParkInputMsgTimer_mS_M_u32	939060736
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3193641216
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	1893
ComputerRazGCTSigInvalidTimer_mS_M_u32	2203302144
ComputerRazGCTSigValidCount_Cnt_M_u16	20262
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	40653
DMDFCTCPKSigValidCount_Cnt_M_u16	48618
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0
DMDRELAXECPKSigValidCount_Cnt_M_u16	32915
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	50885
DateInvalidTimer_mS_M_u32	1911576832
DiagMuxOnAbsentTimer_mS_M_u32	1698408704
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2042546432
ESPNTCEnableTimer_mS_M_u32	4025751808
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	63360
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	252
EffacDefaultDiagTimer_mS_M_u32[1]	378
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	54
ElecIntTimer_mS_M_u32[1]	66
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2692188416
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	12110
EtatMTSigValidCount_Cnt_M_u16	18848
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	35446
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	51164
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	36872
ISDAT4V2BSI552MsgTimer_mS_M_u32	3409234176
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	34328
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	11794
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	18848
ISDATBSI3F2MsgTimer_mS_M_u32	2477893888
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	4889
ISDATBSI412MsgLenValidCount_Cnt_M_u16	54659
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	12110
ISDATBSI412MsgTimer_mS_M_u32	1275259136
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	37106
ISDATBSI432MsgLenValidCount_Cnt_M_u16	45716
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	56508
ISDATDIRASentFltAcc_Cnt_M_u16	54944
ISDATDIRASentTimer_mS_M_u32	3030378752
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	55127
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	38113
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	14984
ISDYN2CMMMsgTimer_mS_M_u32	3335919872
ISDYNAASChkSumInvalidCount_Cnt_M_u16	28635
ISDYNAASChkSumValidCount_Cnt_M_u16	45905
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	48796
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	36158
ISDYNAASMsgLenValidCount_Cnt_M_u16	64204
ISDYNAASMsgTimeValidCount_Cnt_M_u16	28635
ISDYNAASMsgTimer_mS_M_u32	3202906368
ISDYNABRChkSumInvalidCount_Cnt_M_u16	29541
ISDYNABRChkSumValidCount_Cnt_M_u16	44003
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	31254
ISDYNABRMsgCountValidCount_Cnt_M_u16	33740
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	21031
ISDYNABRMsgLenValidCount_Cnt_M_u16	41549
ISDYNABRMsgTimeValidCount_Cnt_M_u16	40033

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	54941
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	20426
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	18848
ISDYNCMM208MsgTimer_mS_M_u32	345299200
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	54941
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	20426
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	52311
ISDYNCMM388MsgTimer_mS_M_u32	3102079232
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	1890
ISDYNVOLChkSumValidCount_Cnt_M_u16	24008
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	11331
ISDYNVOLMsgCountValidCount_Cnt_M_u16	38880
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	53317
ISDYNVOLMsgLenValidCount_Cnt_M_u16	50058
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	31966
ISDYNVOLMsgTimer_mS_M_u32	2336209152
IgnOnTimer_mS_M_u32	620361984
IgnTimeOff_Sec_M_u32	735704165
ManVehSpd_Kph_M_f32	317.352997
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	144
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	226
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1781508352
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	25
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2719615232
PrevISDATBSI412MsgDLCError_Cnt_M_u08	1
PrevISDATBSI412MsgRxTime_MSec_M_u32	2362063104
PrevISDATBSI432MsgDLCError_Cnt_M_u08	45
PrevISDATBSI432MsgRxTime_MSec_M_u32	3031963904
PrevISDATDIRAMsgTxTime_MSec_M_u32	3920509184
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	54
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3037088000
PrevISDYNAASMsgDLCError_Cnt_M_u08	239
PrevISDYNAASMsgRxTime_MSec_M_u32	1849014528
PrevISDYNABRMsgDLCError_Cnt_M_u08	225
PrevISDYNABRMsgRxTime_MSec_M_u32	332527872
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	60
PrevISDYNCMM208MsgRxTime_MSec_M_u32	640071936
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	248
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1061624064
PrevISDYNVOLMsgDLCError_Cnt_M_u08	128
PrevISDYNVOLMsgRxTime_MSec_M_u32	4088609024
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1601759488
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	417.685913
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	43188
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	58050
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	10489
VitesseVehicleBVRampValidCount_Cnt_M_u16	31943
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	39032

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	24334
VitesseVehicleBV_Kph_M_f32	79.1679001
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	52311
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	13124
VitesseVehiculeRoues_Kph_M_f32	554.025696
k_AASNTCEnableTimeout_mS_u16	15028
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	38024
k_AASNodeTimeout_mS_u16	27074
k_ABSNodeTimeout_mS_u16	36862
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	47321
k_ANGLEVOLANTSigValidThresh_Cnt_u16	51643
k_AngleVolantInvalidThresh_Cnt_u16	26654
k_AngleVolantValidThresh_Cnt_u16	13281
k_BSI552MsgTimeout_mS_u16	47975
k_BSINTCEnableTimeout_mS_u16	12234
k_BSINodeAbsentDiag_Cnt_str.Threshold	14994
k_BSINodeAbsentDiag_Cnt_str.PStep	15858
k_BSINodeAbsentDiag_Cnt_str.NStep	30405
k_BSINodeAbsentTimeout_mS_u16	20994
k_BSINodeTimeout_mS_u16	56508
k_BattOvHi_Volt_f32	14.8245001
k_BattOvLo_Volt_f32	6.40740013
k_BattUvHi_Volt_f32	4.27580023
k_BattUvLo_Volt_f32	2.89199996
k_CAVNTCEnableTimeout_mS_u16	15919
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	50917
k_CAVNodeTimeout_mS_u16	58584
k_CMM388MsgTimeout_mS_u16	12113
k_CMM388NTCEnableTimeout_mS_u16	53309
k_CMMNTCEnableTimeout_mS_u16	20720
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	29232
k_CONSANGLECPKMax_HwDeg_f32	465.868713
k_CONSANGLECPKMin_HwDeg_f32	-8.4133997
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	4951
k_CONSANGLECPKSigValidThresh_Cnt_u16	47684
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	56032
k_CPKVehicleSpeedValidThresh_Cnt_u16	26280
k_CityParkInputInvalidThresh_Cnt_u16	9987
k_CityParkInputValidThresh_Cnt_u16	54773
k_ComputerRazGCTSigValidThresh_Cnt_u16	5398
k_CptTemporelSigValidThresh_Cnt_u16	40848
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	6439
k_DMDFCTCPKSigValidThresh_Cnt_u16	43341
k_DMDFCTCPKValidCount_Cnt_u16	25366
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	14984
k_DMDRELAXECPKSigValidThresh_Cnt_u16	16357
k_DMDRelaxeConsistentThresh_Cnt_u16	13059
k_DateValidThresh_Cnt_u16	36872
k_DefaultVehSpd_Kph_f32	253.005997
k_DiagMuxOnAbsentTimeout_mS_u16	27183
k_EMNodeTimeout_mS_u16	30885
k_ESPNTCEnableTimeout_mS_u16	51803
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	47960
k_EtatMTSigInvalidThresh_Cnt_u16	55848
k_EtatMTSigValidThresh_Cnt_u16	44774
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	50895
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	55424
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	8250
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	14225
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	14411
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	62765

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	32235
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	38989
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	58630
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	12373
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	20575
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	33903
k_ISDATDIRASentDiag_Cnt_str.Threshold	34622
k_ISDATDIRASentDiag_Cnt_str.PStep	48742
k_ISDATDIRASentDiag_Cnt_str.NStep	16845
k_ISDATDIRASentTimeout_mS_u16	48465
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	39392
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	43306
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	56983
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	47717
k_ISDYNAASChkSumValidThresh_Cnt_u16	13027
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	16662
k_ISDYNAASMsgCountValidThresh_Cnt_u16	35532
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	45177
k_ISDYNAASMsgLenValidThresh_Cnt_u16	41686
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39139
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	26525
k_ISDYNABRChkSumValidThresh_Cnt_u16	1091
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	15342
k_ISDYNABRMsgCountValidThresh_Cnt_u16	52996
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	990
k_ISDYNABRMsgLenValidThresh_Cnt_u16	48768
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	61095
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	456
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	62878
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	52453
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	56243
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	10377
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	37049
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	2432
k_ISDYNVOLChkSumValidThresh_Cnt_u16	39722
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	7001
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	20471
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	20026
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	396
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	35030
k_IgnOnTimeout_mS_u16	14188
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	127.416603
k_PowerCutVehSpdLowThresh_Kph_f32	56.9556999
k_PowerCutVehSpdLowTimeout_mS_u16	19408
k_VBattMaxAAS_Volt_f32	23.2021008
k_VBattMaxBSI_Volt_f32	8.69120026
k_VBattMaxCAV_Volt_f32	16.8610001
k_VBattMaxCMM388_Volt_f32	32
k_VBattMaxCMM_Volt_f32	30.2819996
k_VBattMaxESP_Volt_f32	25.2219009
k_VBattMinAAS_Volt_f32	11.6236
k_VBattMinBSI_Volt_f32	25.2219009
k_VBattMinCAV_Volt_f32	17.9575996
k_VBattMinCMM388_Volt_f32	31.9752007
k_VBattMinCMM_Volt_f32	27.5576992
k_VBattMinESP_Volt_f32	30.2819996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	55234
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	62427
k_VitesseVehicleBVRampValidThresh_Cnt_u16	29507
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	25800
k_VitesseVehicleBVSigValidThresh_Cnt_u16	1298
k_VitesseVehicleBVSpeedPassThresh_kph_f32	16.2096004
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	21359
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	46013
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1911576832
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	54541
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	433233920
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	248
target_SrlComInput_Per1_Batt_Volt_f32.value	22.4733009
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	238717184
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	80
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.951529622
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1894512896
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	243
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	102013184
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2462923008
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4279621888
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	854489344
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	374806784
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2437921024
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	205
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3912947968
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2132474112
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	969120000
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2885433600
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	43
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	174
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	207
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1668548864
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3485
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.858716726
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	480009
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	129.641495
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	41494

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	433233920	433233920	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	433233920	433233920	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	43306	43306	✔
AngleVolantMsgTimer_mS_M_u32	433233920	433233920	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	433233920	433233920	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	433233920	433233920	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	433233920	433233920	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	433233920	433233920	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	14994	14994	✔
BSINodeAbsentTimer_mS_M_u32	433233920	433233920	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	433233920	433233920	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	433233920	433233920	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	433233920	433233920	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	433233920	433233920	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	433233920	433233920	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	40033	40033	✔
CONSANGLECPK_HwDeg_M_f32	-481.584686	-481.584686 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	40033	40033	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3030378752	3030378752	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	57568	57568	✔
CityParkInputConsistentCount_Cnt_M_u16	54773	54773	✔
CityParkInputInvalidCount_Cnt_M_u16	13281	13281	✔
CityParkInputMsgTimer_mS_M_u32	433233920	433233920	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	433233920	433233920	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	433233920	433233920	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	433233920	433233920	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	433233920	433233920	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	433233920	433233920	✔
ESPNTCEnableTimer_mS_M_u32	433233920	433233920	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	433233920	433233920	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	433233920	433233920	✔
EffacDefaultDiagTimer_mS_M_u32[1]	378	378	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	433233920	433233920	✔
ElecIntTimer_mS_M_u32[1]	66	66	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	433233920	433233920	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	433233920	433233920	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	433233920	433233920	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	433233920	433233920	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	433233920	433233920	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	433233920	433233920	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	433233920	433233920	✔
IgnOnTimer_mS_M_u32	433233920	433233920	✔
IgnTimeOff_Sec_M_u32	735704165	735704165	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	34	34	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1894512896	1894512896	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	243	243	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	102013184	102013184	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2462923008	2462923008	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4279621888	4279621888	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3920509184	3920509184	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	104	104	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	374806784	374806784	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	218	218	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2437921024	2437921024	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	178	178	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3912947968	3912947968	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	198	198	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2132474112	2132474112	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	969120000	969120000	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	53	53	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2885433600	2885433600	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1668548864	1668548864	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	417.685913	417.685913	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	79.1679001	79.1679001	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	554.025696	554.025696	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	40033	40033	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	735704165	735704165	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-481.584686	-481.584686 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.270 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3353085952
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	61326
AASNodeAbsentTimer_mS_M_u32	2993518592
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	37991
ANGLEVOLANTSigValidCount_Cnt_M_u16	8357
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	53507
AngleVolantMsgTimer_mS_M_u32	3353085952
AngleVolantValidCount_Cnt_M_u16	45151
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2312583168
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	980531200
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2072356864
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2831575040
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	8118
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2329552896
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	41908
CAVNodeAbsentTimer_mS_M_u32	3582662656
CDD_SrlComVehSpd_Kph_G_f32	168.707794
CMM388NTCEnableTimer_mS_M_u32	2412599296
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3979417600
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	64039
CMMNodeAbsentTimer_mS_M_u32	3282069504
CONSANGLECPKSigInvalidCount_Cnt_M_u16	8892
CONSANGLECPKSigValidCount_Cnt_M_u16	14283
CONSANGLECPK_Cnt_M_u16	48926
CONSANGLECPK_HwDeg_M_f32	231.861801
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	48926
CPKVehicleSpeedMsgTimer_mS_M_u32	1688406016
CPKVehicleSpeedValidCount_Cnt_M_u16	33514

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	15651
CityParkInputInvalidCount_Cnt_M_u16	9310
CityParkInputMsgTimer_mS_M_u32	1894512896
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1882290176
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	25170
ComputerRazGCTSigInvalidTimer_mS_M_u32	1271371776
ComputerRazGCTSigValidCount_Cnt_M_u16	54672
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	37786
DMDFCTCPKSigValidCount_Cnt_M_u16	2305
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	65535
DMDRELAXECPKSigValidCount_Cnt_M_u16	43911
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	62769
DateInvalidTimer_mS_M_u32	980531200
DiagMuxOnAbsentTimer_mS_M_u32	1909442560
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2831575040
ESPNTCEnableTimer_mS_M_u32	2137421824
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	27906
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	102
EffacDefaultDiagTimer_mS_M_u32[1]	106
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	127674368
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	62422
EtatMTSigValidCount_Cnt_M_u16	18337
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	44574
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	59565
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	35495
ISDAT4V2BSI552MsgTimer_mS_M_u32	207906816
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	61176
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	14795
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	18337
ISDATBSI3F2MsgTimer_mS_M_u32	1047382016
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	56565
ISDATBSI412MsgLenValidCount_Cnt_M_u16	39032
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	62422
ISDATBSI412MsgTimer_mS_M_u32	3933865984
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	3563
ISDATBSI432MsgLenValidCount_Cnt_M_u16	35782
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	42701
ISDATDIRASentFltAcc_Cnt_M_u16	18721
ISDATDIRASentTimer_mS_M_u32	1688406016
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	26172
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	45151
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	27753
ISDYN2CMMMsgTimer_mS_M_u32	46168064
ISDYNAASChkSumInvalidCount_Cnt_M_u16	33008
ISDYNAASChkSumValidCount_Cnt_M_u16	59727
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	57134
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	7495
ISDYNAASMsgLenValidCount_Cnt_M_u16	26462
ISDYNAASMsgTimeValidCount_Cnt_M_u16	33008
ISDYNAASMsgTimer_mS_M_u32	3691599872
ISDYNABRChkSumInvalidCount_Cnt_M_u16	6097
ISDYNABRChkSumValidCount_Cnt_M_u16	49432
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	3647
ISDYNABRMsgCountValidCount_Cnt_M_u16	9182
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	23307
ISDYNABRMsgLenValidCount_Cnt_M_u16	23898
ISDYNABRMsgTimeValidCount_Cnt_M_u16	48926

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	52077
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	56744
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	18337
ISDYNCMM208MsgTimer_mS_M_u32	2223257600
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	52077
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	56744
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	25085
ISDYNCMM388MsgTimer_mS_M_u32	3289438208
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	59226
ISDYNVOLChkSumValidCount_Cnt_M_u16	55017
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	17208
ISDYNVOLMsgCountValidCount_Cnt_M_u16	54047
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	14003
ISDYNVOLMsgLenValidCount_Cnt_M_u16	53154
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	64039
ISDYNVOLMsgTimer_mS_M_u32	3825440768
IgnOnTimer_mS_M_u32	3486832640
IgnTimeOff_Sec_M_u32	1189670664
ManVehSpd_Kph_M_f32	449.100891
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	145
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	147
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	854837248
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	109
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2897520640
PrevISDATBSI412MsgDLCError_Cnt_M_u08	53
PrevISDATBSI412MsgRxTime_MSec_M_u32	694425600
PrevISDATBSI432MsgDLCError_Cnt_M_u08	113
PrevISDATBSI432MsgRxTime_MSec_M_u32	1092253696
PrevISDATDIRAMsgTxTime_MSec_M_u32	2729973760
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	215
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1961879552
PrevISDYNAASMsgDLCError_Cnt_M_u08	77
PrevISDYNAASMsgRxTime_MSec_M_u32	2468452352
PrevISDYNABRMsgDLCError_Cnt_M_u08	161
PrevISDYNABRMsgRxTime_MSec_M_u32	1665980416
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	176
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1867421696
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	205
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2641197056
PrevISDYNVOLMsgDLCError_Cnt_M_u08	170
PrevISDYNVOLMsgRxTime_MSec_M_u32	3634960384
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	135792640
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	264.115295
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	8933
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1916
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	62998
VitesseVehicleBVRampValidCount_Cnt_M_u16	36205
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	23832

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	48150
VitesseVehicleBV_Kph_M_f32	159.276306
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	25085
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	16372
VitesseVehiculeRoues_Kph_M_f32	15.3351002
k_AASNTCEnableTimeout_mS_u16	61477
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	3434
k_AASNodeTimeout_mS_u16	29308
k_ABSNodeTimeout_mS_u16	50183
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	62006
k_ANGLEVOLANTSigValidThresh_Cnt_u16	41553
k_AngleVolantInvalidThresh_Cnt_u16	4904
k_AngleVolantValidThresh_Cnt_u16	9310
k_BSI552MsgTimeout_mS_u16	62347
k_BSINTCEnableTimeout_mS_u16	37219
k_BSINodeAbsentDiag_Cnt_str.Threshold	2830
k_BSINodeAbsentDiag_Cnt_str.PStep	45872
k_BSINodeAbsentDiag_Cnt_str.NStep	35573
k_BSINodeAbsentTimeout_mS_u16	13947
k_BSINodeTimeout_mS_u16	42701
k_BattOvHi_Volt_f32	14.0214996
k_BattOvLo_Volt_f32	30.1005993
k_BattUvHi_Volt_f32	10.4382
k_BattUvLo_Volt_f32	6.81349993
k_CAVNTCEnableTimeout_mS_u16	48500
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	52306
k_CAVNodeTimeout_mS_u16	42744
k_CMM388MsgTimeout_mS_u16	39566
k_CMM388NTCEnableTimeout_mS_u16	26570
k_CMMNTCEnableTimeout_mS_u16	61040
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	13104
k_CONSANGLECPKMax_HwDeg_f32	519.842773
k_CONSANGLECPKMin_HwDeg_f32	-241.483902
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	36093
k_CONSANGLECPKSigValidThresh_Cnt_u16	43764
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	5922
k_CPKVehicleSpeedValidThresh_Cnt_u16	56904
k_CityParkInputInvalidThresh_Cnt_u16	62711
k_CityParkInputValidThresh_Cnt_u16	15651
k_ComputerRazGCTSigValidThresh_Cnt_u16	47614
k_CptTemporelSigValidThresh_Cnt_u16	23889
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	1547
k_DMDFCTCPKSigValidThresh_Cnt_u16	18522
k_DMDFCTCPKValidCount_Cnt_u16	62782
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	27753
k_DMDRELAXECPKSigValidThresh_Cnt_u16	12048
k_DMDRelaxeConsistentThresh_Cnt_u16	19894
k_DateValidThresh_Cnt_u16	35495
k_DefaultVehSpd_Kph_f32	153.992798
k_DiagMuxOnAbsentTimeout_mS_u16	3508
k_EMNodeTimeout_mS_u16	24465
k_ESPNTCEnableTimeout_mS_u16	6640
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	63416
k_EtatMTSigInvalidThresh_Cnt_u16	44936
k_EtatMTSigValidThresh_Cnt_u16	33807
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	53077
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	48384
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	45652
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	65165
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	16160
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	34489

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	27392
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	65179
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	25007
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	54082
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	62949
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	28149
k_ISDATDIRASentDiag_Cnt_str.Threshold	21203
k_ISDATDIRASentDiag_Cnt_str.PStep	38003
k_ISDATDIRASentDiag_Cnt_str.NStep	12439
k_ISDATDIRASentTimeout_mS_u16	59917
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	12706
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	53507
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	52540
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	17105
k_ISDYNAASChkSumValidThresh_Cnt_u16	11288
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	47423
k_ISDYNAASMsgCountValidThresh_Cnt_u16	3806
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	45205
k_ISDYNAASMsgLenValidThresh_Cnt_u16	5952
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	54489
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	29353
k_ISDYNABRChkSumValidThresh_Cnt_u16	36728
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	51894
k_ISDYNABRMsgCountValidThresh_Cnt_u16	50228
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	25895
k_ISDYNABRMsgLenValidThresh_Cnt_u16	6146
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	45387
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	26537
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	35174
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	38163
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	16231
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	2981
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	28118
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	21952
k_ISDYNVOLChkSumValidThresh_Cnt_u16	41859
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	42359
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	9436
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	18194
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	53213
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	22589
k_IgnOnTimeout_mS_u16	31740
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	159.260895
k_PowerCutVehSpdLowThresh_Kph_f32	26.6436996
k_PowerCutVehSpdLowTimeout_mS_u16	11473
k_VBattMaxAAS_Volt_f32	0.906700015
k_VBattMaxBSI_Volt_f32	7.37900019
k_VBattMaxCAV_Volt_f32	25.0541
k_VBattMaxCMM388_Volt_f32	4.08139992
k_VBattMaxCMM_Volt_f32	12.7959003
k_VBattMaxESP_Volt_f32	24.8502998
k_VBattMinAAS_Volt_f32	5.05940008
k_VBattMinBSI_Volt_f32	24.8502998
k_VBattMinCAV_Volt_f32	1.49389994
k_VBattMinCMM388_Volt_f32	29.6305008
k_VBattMinCMM_Volt_f32	15.1358004
k_VBattMinESP_Volt_f32	12.7959003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	32764
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	61039
k_VitesseVehicleBVRampValidThresh_Cnt_u16	28216
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	49641
k_VitesseVehicleBVSigValidThresh_Cnt_u16	25548
k_VitesseVehicleBVSpeedPassThresh_kph_f32	5.23939991
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	52916
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	16523
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	980531200
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	41358
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2292638464
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	205
target_SrlComInput_Per1_Batt_Volt_f32.value	8.58150005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2320705536
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	192
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.797970176
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	872339456
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1594161152
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3814397952
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	151074816
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	402085888
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1480423424
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	217
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	299079680
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	97
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	135
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	230
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	239
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	197
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	512899072
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	85
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	117
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	180
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	197
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	199
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	19
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2238830592
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	156
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1073215488
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	332273664
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	19
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	133
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	172
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	196
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1353099264
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1294
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.605178654
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	156987
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	50.8362999
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	16063

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2292638464	2292638464	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	2830	2830	✔
BSINodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	64039	64039	✔
CMMNodeAbsentTimer_mS_M_u32	1480423424	1480423424	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	48926	48926	✔
CONSANGLECPK_HwDeg_M_f32	231.861801	231.861801 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2292638464	2292638464	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2292638464	2292638464	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2292638464	2292638464	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2292638464	2292638464	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2292638464	2292638464	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2292638464	2292638464	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2292638464	2292638464	✔
ESPNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	2292638464	2292638464	✔
EffacDefaultDiagTimer_mS_M_u32[1]	106	106	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2292638464	2292638464	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2292638464	2292638464	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2292638464	2292638464	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2292638464	2292638464	✔
IgnOnTimer_mS_M_u32	3486832640	3486832640	✔
IgnTimeOff_Sec_M_u32	1189670664	1189670664	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	129	129	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	872339456	872339456	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1594161152	1594161152	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	233	233	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3814397952	3814397952	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	245	245	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	151074816	151074816	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2729973760	2729973760	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	37	37	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1480423424	1480423424	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	217	217	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	299079680	299079680	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	197	197	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	512899072	512899072	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	19	19	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2238830592	2238830592	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	156	156	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1073215488	1073215488	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	154	154	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	332273664	332273664	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1353099264	1353099264	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	264.115295	264.115295	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	159.276306	159.276306	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	15.3351002	15.3351002	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	48926	48926	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1189670664	1189670664	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	231.861801	231.861801 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	153.992798	153.992798	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.271 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3324685056
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	14611
AASNodeAbsentTimer_mS_M_u32	1479957248
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	19593
ANGLEVOLANTSigValidCount_Cnt_M_u16	36748
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	43188
AngleVolantMsgTimer_mS_M_u32	3324685056
AngleVolantValidCount_Cnt_M_u16	8991
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2834897664
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	556374784
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3652045568
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1156287232
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	42652
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2645576448
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	15138
CAVNodeAbsentTimer_mS_M_u32	3982326528
CDD_SrlComVehSpd_Kph_G_f32	539.906006
CMM388NTCEnableTimer_mS_M_u32	2543237888
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3194714880
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	16520
CMMNodeAbsentTimer_mS_M_u32	3697117952
CONSANGLECPKSigInvalidCount_Cnt_M_u16	10376
CONSANGLECPKSigValidCount_Cnt_M_u16	4379
CONSANGLECPK_Cnt_M_u16	34594
CONSANGLECPK_HwDeg_M_f32	617.381104
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	34594
CPKVehicleSpeedMsgTimer_mS_M_u32	3419777792
CPKVehicleSpeedValidCount_Cnt_M_u16	42982
CityParkInputConsistentCount_Cnt_M_u16	36051
CityParkInputInvalidCount_Cnt_M_u16	54306
CityParkInputMsgTimer_mS_M_u32	872339456

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	787110656
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	61639
ComputerRazGCTSigInvalidTimer_mS_M_u32	480770816
ComputerRazGCTSigValidCount_Cnt_M_u16	46988
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	30318
DMDFCTCPKSigValidCount_Cnt_M_u16	40441
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	48166
DMDRELAXECPKSigValidCount_Cnt_M_u16	63206
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	50473
DateInvalidTimer_mS_M_u32	556374784
DiagMuxOnAbsentTimer_mS_M_u32	1196387072
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1156287232
ESPNTCEnableTimer_mS_M_u32	357260032
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	16311
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	89
EffacDefaultDiagTimer_mS_M_u32[1]	789
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	657
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2942978816
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	8314
EtatMTSigValidCount_Cnt_M_u16	15578
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	36450
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1653
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	12551
ISDAT4V2BSI552MsgTimer_mS_M_u32	303139584
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	12435
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	34779
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	15578
ISDATBSI3F2MsgTimer_mS_M_u32	3648350976
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	42911
ISDATBSI412MsgLenValidCount_Cnt_M_u16	27862
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	8314
ISDATBSI412MsgTimer_mS_M_u32	1448127232
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	5436
ISDATBSI432MsgLenValidCount_Cnt_M_u16	62315
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	54743
ISDATDIRASentFltAcc_Cnt_M_u16	16091
ISDATDIRASentTimer_mS_M_u32	3419777792
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	35272
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	8991
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	59393
ISDYN2CMMMsgTimer_mS_M_u32	1933400832
ISDYNAASChkSumInvalidCount_Cnt_M_u16	36077
ISDYNAASChkSumValidCount_Cnt_M_u16	48016
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	37554
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	55913
ISDYNAASMsgLenValidCount_Cnt_M_u16	17380
ISDYNAASMsgTimeValidCount_Cnt_M_u16	36077
ISDYNAASMsgTimer_mS_M_u32	2732768000
ISDYNABRChkSumInvalidCount_Cnt_M_u16	58314
ISDYNABRChkSumValidCount_Cnt_M_u16	61365
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	57600
ISDYNABRMsgCountValidCount_Cnt_M_u16	2019
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	31643
ISDYNABRMsgLenValidCount_Cnt_M_u16	40046
ISDYNABRMsgTimeValidCount_Cnt_M_u16	34594
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	16682
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	37178
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	15578

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimer_mS_M_u32	2901547776
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	16682
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	37178
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	1605
ISDYNCMM388MsgTimer_mS_M_u32	1758214912
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	53934
ISDYNVOLChkSumValidCount_Cnt_M_u16	11201
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	24468
ISDYNVOLMsgCountValidCount_Cnt_M_u16	14239
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	59044
ISDYNVOLMsgLenValidCount_Cnt_M_u16	50072
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	16520
ISDYNVOLMsgTimer_mS_M_u32	1140062976
IgnOnTimer_mS_M_u32	1434467072
IgnTimeOff_Sec_M_u32	589645433
ManVehSpd_Kph_M_f32	31.3834991
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	146
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	22
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2481154816
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	9
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3256929024
PrevISDATBSI412MsgDLCError_Cnt_M_u08	49
PrevISDATBSI412MsgRxTime_MSec_M_u32	2513599232
PrevISDATBSI432MsgDLCError_Cnt_M_u08	62
PrevISDATBSI432MsgRxTime_MSec_M_u32	2687458048
PrevISDATDIRAMsgTxTime_MSec_M_u32	2044099328
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	135
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1718553344
PrevISDYNAASMsgDLCError_Cnt_M_u08	64
PrevISDYNAASMsgRxTime_MSec_M_u32	781843200
PrevISDYNABRMsgDLCError_Cnt_M_u08	201
PrevISDYNABRMsgRxTime_MSec_M_u32	2065185536
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	60
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2383608576
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	239
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2536921856
PrevISDYNVOLMsgDLCError_Cnt_M_u08	3
PrevISDYNVOLMsgRxTime_MSec_M_u32	3691215616
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4118194944
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	238.300598
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	49551
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	23434
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	19452
VitesseVehicleBVRampValidCount_Cnt_M_u16	52663
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	63094
VitesseVehicleBVSigValidCount_Cnt_M_u16	49465
VitesseVehicleBV_Kph_M_f32	632.296387
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	1605

Name	Input Value
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	13344
VitesseVehiculeRoues_Kph_M_f32	503.923492
k_AASNTCEnableTimeout_mS_u16	53261
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	63486
k_AASNodeTimeout_mS_u16	6794
k_ABSNodeTimeout_mS_u16	55591
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	21595
k_ANGLEVOLANTSigValidThresh_Cnt_u16	39882
k_AngleVolantInvalidThresh_Cnt_u16	25925
k_AngleVolantValidThresh_Cnt_u16	54306
k_BSI552MsgTimeout_mS_u16	13659
k_BSINTCEnableTimeout_mS_u16	27348
k_BSINodeAbsentDiag_Cnt_str.Threshold	16326
k_BSINodeAbsentDiag_Cnt_str.PStep	12450
k_BSINodeAbsentDiag_Cnt_str.NStep	8850
k_BSINodeAbsentTimeout_mS_u16	22604
k_BSINodeTimeout_mS_u16	54743
k_BattOvHi_Volt_f32	26.3624992
k_BattOvLo_Volt_f32	5.64260006
k_BattUvHi_Volt_f32	12.8010998
k_BattUvLo_Volt_f32	14.5026999
k_CAVNTCEnableTimeout_mS_u16	57568
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	47432
k_CAVNodeTimeout_mS_u16	35796
k_CMM388MsgTimeout_mS_u16	14355
k_CMM388NTCEnableTimeout_mS_u16	49247
k_CMMNTCEnableTimeout_mS_u16	4651
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	19052
k_CONSANGLECPKMax_HwDeg_f32	111.5224
k_CONSANGLECPKMin_HwDeg_f32	-407.979187
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	34117
k_CONSANGLECPKSigValidThresh_Cnt_u16	62240
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	17560
k_CPKVehicleSpeedValidThresh_Cnt_u16	44966
k_CityParkInputInvalidThresh_Cnt_u16	25688
k_CityParkInputValidThresh_Cnt_u16	36051
k_ComputerRazGCTSigValidThresh_Cnt_u16	26497
k_CptTemporelSigValidThresh_Cnt_u16	46409
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	31387
k_DMDFCTCPKSigValidThresh_Cnt_u16	56174
k_DMDFCTCPKValidCount_Cnt_u16	17924
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	59393
k_DMDRELAXECPKSigValidThresh_Cnt_u16	10188
k_DMDRelaxeConsistentThresh_Cnt_u16	58330
k_DateValidThresh_Cnt_u16	12551
k_DefaultVehSpd_Kph_f32	0.266799986
k_DiagMuxOnAbsentTimeout_mS_u16	29536
k_EMNodeTimeout_mS_u16	1545
k_ESPNTCEnableTimeout_mS_u16	51310
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	7380
k_EtatMTSigInvalidThresh_Cnt_u16	47269
k_EtatMTSigValidThresh_Cnt_u16	17104
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	43007
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	30398
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	12608
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	38356
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	3036
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	47699
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	37373
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	12012
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	10736

Name	Input Value
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	55990
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	60045
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	17822
k_ISDATDIRASentDiag_Cnt_str.Threshold	255
k_ISDATDIRASentDiag_Cnt_str.PStep	39431
k_ISDATDIRASentDiag_Cnt_str.NStep	31970
k_ISDATDIRASentTimeout_mS_u16	23830
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	61079
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	43188
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	56970
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	25290
k_ISDYNAASChkSumValidThresh_Cnt_u16	44725
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	57344
k_ISDYNAASMsgCountValidThresh_Cnt_u16	18147
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	10622
k_ISDYNAASMsgLenValidThresh_Cnt_u16	15422
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	9266
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	11457
k_ISDYNABRChkSumValidThresh_Cnt_u16	65044
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	42396
k_ISDYNABRMsgCountValidThresh_Cnt_u16	41183
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	65416
k_ISDYNABRMsgLenValidThresh_Cnt_u16	16055
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	62874
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	835
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	42572
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	52933
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	19337
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	52876
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	55226
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	10558
k_ISDYNVOLChkSumValidThresh_Cnt_u16	14261
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	43608
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	54377
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	5830
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	37926
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	41029
k_IgnOnTimeout_mS_u16	42634
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	74.9626007
k_PowerCutVehSpdLowThresh_Kph_f32	224.814102
k_PowerCutVehSpdLowTimeout_mS_u16	51721
k_VBattMaxAAS_Volt_f32	0.405200005
k_VBattMaxBSI_Volt_f32	26.1699009
k_VBattMaxCAV_Volt_f32	11.5910997
k_VBattMaxCMM388_Volt_f32	0.0656000003
k_VBattMaxCMM_Volt_f32	30.3509007
k_VBattMaxESP_Volt_f32	3.56579995
k_VBattMinAAS_Volt_f32	13.6962996
k_VBattMinBSI_Volt_f32	3.56579995
k_VBattMinCAV_Volt_f32	11.0831003
k_VBattMinCMM388_Volt_f32	13.1049004
k_VBattMinCMM_Volt_f32	7.8302002
k_VBattMinESP_Volt_f32	30.3509007
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	60297
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	22512
k_VitesseVehicleBVRampValidThresh_Cnt_u16	56980
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	27329
k_VitesseVehicleBVSigValidThresh_Cnt_u16	64728
k_VitesseVehicleBVSpeedPassThresh_kph_f32	154.123093
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	47650
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	44125
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	556374784
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	2679
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3572898304
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	239
target_SrlComInput_Per1_Batt_Volt_f32.value	18.4111996

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3276098304
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	40
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.406888187
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1359100672
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	275766016
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	65895168
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1400576768
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	655932160
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2798017280
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	187
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4202953472
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	56
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	57
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	80
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	107
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	235
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2529696512
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	64
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	65
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	90
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	176
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	183
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	23
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3903404800
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4187413248
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4271143680
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	4
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	16
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	93
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	117
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	508218112
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2014
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.930049062
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	430249
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	193.486298
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	22017

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3572898304	3572898304	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3572898304	3572898304	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	16326	16326	✔
BSINodeAbsentTimer_mS_M_u32	3572898304	3572898304	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3572898304	3572898304	✔
CDD_SrlComVehSpd_Kph_G_f32	31.3834991	31.3834991	✔
CMM388NTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3572898304	3572898304	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	34594	34594	✔
CONSANGLECPK_HwDeg_M_f32	617.381104	617.381104 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3572898304	3572898304	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3572898304	3572898304	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3572898304	3572898304	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3572898304	3572898304	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3572898304	3572898304	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3572898304	3572898304	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3572898304	3572898304	✔
ESPNTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3572898304	3572898304	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	89	89	✔
EffacDefaultDiagTimer_mS_M_u32[1]	789	789	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	65	65	✔
ElecIntTimer_mS_M_u32[1]	657	657	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3572898304	3572898304	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	12551	12551	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	15578	15578	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	8314	8314	✔
ISDATBSI412MsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	54743	54743	✔
ISDATBSI432MsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3572898304	3572898304	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	59393	59393	✔
ISDYN2CMMMsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	36077	36077	✔
ISDYNAASMsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	34594	34594	✔
ISDYNABRMsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	15578	15578	✔
ISDYNCMM208MsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	1605	1605	✔
ISDYNCMM388MsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	16520	16520	✔
ISDYNVOLMsgTimer_mS_M_u32	3572898304	3572898304	✔
IgnOnTimer_mS_M_u32	1434467072	1434467072	✔
IgnTimeOff_Sec_M_u32	589645433	589645433	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	64	64	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1359100672	1359100672	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	212	212	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	275766016	275766016	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	137	137	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	65895168	65895168	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	133	133	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1400576768	1400576768	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2044099328	2044099328	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	246	246	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2798017280	2798017280	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	187	187	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4202953472	4202953472	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	152	152	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2529696512	2529696512	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	23	23	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3903404800	3903404800	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	29	29	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4187413248	4187413248	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	3	3	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4271143680	4271143680	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	508218112	508218112	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	238.300598	238.300598	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	632.296387	632.296387	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	503.923492	503.923492	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	34594	34594	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	589645433	589645433	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	617.381104	617.381104 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.272 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3314205184
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	44753
AASNodeAbsentTimer_mS_M_u32	438809088
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	28269
ANGLEVOLANTSigValidCount_Cnt_M_u16	60964
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	9198
AngleVolantMsgTimer_mS_M_u32	3314205184
AngleVolantValidCount_Cnt_M_u16	27435
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2732552704
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2622353920
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	4286669312
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3838321152
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	27700
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3715752448
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	19747
CAVNodeAbsentTimer_mS_M_u32	1597133312
CDD_SrlComVehSpd_Kph_G_f32	126.997803
CMM388NTCEnableTimer_mS_M_u32	3582366208
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2752008704
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	8880
CMMNodeAbsentTimer_mS_M_u32	1718755840
CONSANGLECPKSigInvalidCount_Cnt_M_u16	17777
CONSANGLECPKSigValidCount_Cnt_M_u16	5239
CONSANGLECPK_Cnt_M_u16	36450
CONSANGLECPK_HwDeg_M_f32	-409.315613
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	36450
CPKVehicleSpeedMsgTimer_mS_M_u32	545899008
CPKVehicleSpeedValidCount_Cnt_M_u16	34718
CityParkInputConsistentCount_Cnt_M_u16	65039
CityParkInputInvalidCount_Cnt_M_u16	12580
CityParkInputMsgTimer_mS_M_u32	1359100672
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1712042496
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	22453

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	458412544
ComputerRazGCTSigValidCount_Cnt_M_u16	41444
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	31296
DMDFCTCPKSigValidCount_Cnt_M_u16	27743
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	20191
DMDRELAXECPKSigValidCount_Cnt_M_u16	40982
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	13198
DateInvalidTimer_mS_M_u32	2622353920
DiagMuxOnAbsentTimer_mS_M_u32	3306979840
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3838321152
ESPNTCEnableTimer_mS_M_u32	1994961408
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	7651
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	56
EffacDefaultDiagTimer_mS_M_u32[1]	456
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	54
ElecIntTimer_mS_M_u32[1]	67
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	273408512
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	7129
EtatMTSigValidCount_Cnt_M_u16	32636
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	64483
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	7273
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	27445
ISDAT4V2BSI552MsgTimer_mS_M_u32	2505449984
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	59151
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	14841
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	32636
ISDATBSI3F2MsgTimer_mS_M_u32	648708608
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	48877
ISDATBSI412MsgLenValidCount_Cnt_M_u16	34823
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	7129
ISDATBSI412MsgTimer_mS_M_u32	756597248
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	29844
ISDATBSI432MsgLenValidCount_Cnt_M_u16	53959
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	37124
ISDATDIRASentFltAcc_Cnt_M_u16	26104
ISDATDIRASentTimer_mS_M_u32	545899008
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	40560
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	27435
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	12679
ISDYN2CMMMsgTimer_mS_M_u32	2769465856
ISDYNAASChkSumInvalidCount_Cnt_M_u16	39747
ISDYNAASChkSumValidCount_Cnt_M_u16	55321
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	10354
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	19278
ISDYNAASMsgLenValidCount_Cnt_M_u16	0
ISDYNAASMsgTimeValidCount_Cnt_M_u16	39747
ISDYNAASMsgTimer_mS_M_u32	3819082240
ISDYNABRChkSumInvalidCount_Cnt_M_u16	17451
ISDYNABRChkSumValidCount_Cnt_M_u16	2345
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	43786
ISDYNABRMsgCountValidCount_Cnt_M_u16	65312
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	22584
ISDYNABRMsgLenValidCount_Cnt_M_u16	32382
ISDYNABRMsgTimeValidCount_Cnt_M_u16	36450
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	37743
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	3839
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	32636
ISDYNCMM208MsgTimer_mS_M_u32	3136582144
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	37743
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	3839
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	55737

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	400953856
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	24319
ISDYNVOLChkSumValidCount_Cnt_M_u16	56453
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	54990
ISDYNVOLMsgCountValidCount_Cnt_M_u16	46957
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	7452
ISDYNVOLMsgLenValidCount_Cnt_M_u16	36610
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	8880
ISDYNVOLMsgTimer_mS_M_u32	3580809728
IgnOnTimer_mS_M_u32	566891008
IgnTimeOff_Sec_M_u32	3090163328
ManVehSpd_Kph_M_f32	654.594971
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	147
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	187
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	794853888
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	96
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3525861888
PrevISDATBSI412MsgDLCError_Cnt_M_u08	100
PrevISDATBSI412MsgRxTime_MSec_M_u32	2043892224
PrevISDATBSI432MsgDLCError_Cnt_M_u08	250
PrevISDATBSI432MsgRxTime_MSec_M_u32	1715253760
PrevISDATDIRAMsgTxTime_MSec_M_u32	3720827392
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	176
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3997016576
PrevISDYNAASMsgDLCError_Cnt_M_u08	48
PrevISDYNAASMsgRxTime_MSec_M_u32	763154944
PrevISDYNABRMsgDLCError_Cnt_M_u08	13
PrevISDYNABRMsgRxTime_MSec_M_u32	285348352
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	212
PrevISDYNCMM208MsgRxTime_MSec_M_u32	856805888
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	153
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1562882560
PrevISDYNVOLMsgDLCError_Cnt_M_u08	96
PrevISDYNVOLMsgRxTime_MSec_M_u32	2873119232
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1738981888
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	421.622711
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	44508
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	2219
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	661
VitesseVehicleBVRampValidCount_Cnt_M_u16	42532
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	25766
VitesseVehicleBVSigValidCount_Cnt_M_u16	19741
VitesseVehicleBV_Kph_M_f32	313.879395
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	55737
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	63719
VitesseVehiculeRoues_Kph_M_f32	410.567505
k_AASNTCEnableTimeout_mS_u16	8097
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	10382
k_AASNodeTimeout_mS_u16	52139
k_ABSNodeTimeout_mS_u16	30229
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	62263
k_ANGLEVOLANTSigValidThresh_Cnt_u16	5546
k_AngleVolantInvalidThresh_Cnt_u16	25913
k_AngleVolantValidThresh_Cnt_u16	12580
k_BSI552MsgTimeout_mS_u16	41270
k_BSINTCEnableTimeout_mS_u16	54220
k_BSINodeAbsentDiag_Cnt_str.Threshold	24347
k_BSINodeAbsentDiag_Cnt_str.PStep	53447
k_BSINodeAbsentDiag_Cnt_str.NStep	36663
k_BSINodeAbsentTimeout_mS_u16	29990
k_BSINodeTimeout_mS_u16	37124
k_BattOvHi_Volt_f32	22.5121002
k_BattOvLo_Volt_f32	2.12059999
k_BattUvHi_Volt_f32	6.13079977
k_BattUvLo_Volt_f32	28.5431995
k_CAVNTCEnableTimeout_mS_u16	33514
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	60081
k_CAVNodeTimeout_mS_u16	19341
k_CMM388MsgTimeout_mS_u16	45521
k_CMM388NTCEnableTimeout_mS_u16	18669
k_CMMNTCEnableTimeout_mS_u16	41543
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	58883
k_CONSANGLECPKMax_HwDeg_f32	464.865906
k_CONSANGLECPKMin_HwDeg_f32	-484.185089
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	23737
k_CONSANGLECPKSigValidThresh_Cnt_u16	48103
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	1409
k_CPKVehicleSpeedValidThresh_Cnt_u16	33496
k_CityParkInputInvalidThresh_Cnt_u16	31361
k_CityParkInputValidThresh_Cnt_u16	65039
k_ComputerRazGCTSigValidThresh_Cnt_u16	31301
k_CptTemporelSigValidThresh_Cnt_u16	59823
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	23352
k_DMDFCTCPKSigValidThresh_Cnt_u16	49534
k_DMDFCTCPKValidCount_Cnt_u16	11772
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	12679
k_DMDRELAXECPKSigValidThresh_Cnt_u16	56038
k_DMDRelaxeConsistentThresh_Cnt_u16	24252
k_DateValidThresh_Cnt_u16	27445
k_DefaultVehSpd_Kph_f32	5.74170017
k_DiagMuxOnAbsentTimeout_mS_u16	16808
k_EMNodeTimeout_mS_u16	61678
k_ESPNTCEnableTimeout_mS_u16	54591
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	3787
k_EtatMTSigInvalidThresh_Cnt_u16	61850
k_EtatMTSigValidThresh_Cnt_u16	15320
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	14156
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	974
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	1224
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	64332
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	61942
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	22225
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	16977
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	25668
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	1656
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	58278
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	19681
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	61935
k_ISDATDIRASentDiag_Cnt_str.Threshold	64711

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	35441
k_ISDATDIRASentDiag_Cnt_str.NStep	35487
k_ISDATDIRASentTimeout_mS_u16	2119
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	6916
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	9198
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	747
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	50987
k_ISDYNAASChkSumValidThresh_Cnt_u16	52265
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	44554
k_ISDYNAASMsgCountValidThresh_Cnt_u16	16928
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	17167
k_ISDYNAASMsgLenValidThresh_Cnt_u16	13967
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	7282
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	23750
k_ISDYNABRChkSumValidThresh_Cnt_u16	29068
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	28468
k_ISDYNABRMsgCountValidThresh_Cnt_u16	50731
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	58800
k_ISDYNABRMsgLenValidThresh_Cnt_u16	8419
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	29690
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	47296
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	46822
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	23290
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	29037
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	12580
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	34396
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	30224
k_ISDYNVOLChkSumValidThresh_Cnt_u16	25450
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	41472
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	11021
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	26869
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	43416
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	38267
k_IgnOnTimeout_mS_u16	11820
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	22.1543007
k_PowerCutVehSpdLowThresh_Kph_f32	60.5996017
k_PowerCutVehSpdLowTimeout_mS_u16	8621
k_VBattMaxAAS_Volt_f32	4.01039982
k_VBattMaxBSI_Volt_f32	22.1714001
k_VBattMaxCAV_Volt_f32	16.5690002
k_VBattMaxCMM388_Volt_f32	10.4755001
k_VBattMaxCMM_Volt_f32	14.3336
k_VBattMaxESP_Volt_f32	0.555100024
k_VBattMinAAS_Volt_f32	18.8901997
k_VBattMinBSI_Volt_f32	0.555100024
k_VBattMinCAV_Volt_f32	0.658399999
k_VBattMinCMM388_Volt_f32	32
k_VBattMinCMM_Volt_f32	29.3987007
k_VBattMinESP_Volt_f32	14.3336
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	27694
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	65465
k_VitesseVehicleBVRampValidThresh_Cnt_u16	22990
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	8069
k_VitesseVehicleBVSigValidThresh_Cnt_u16	512
k_VitesseVehicleBVSpeedPassThresh_kph_f32	631.211304
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	53283
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	8754
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2622353920
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	5241
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1436841216
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	153
target_SrlComInput_Per1_Batt_Volt_f32.value	18.4592991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	12247552
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	183
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.391018003
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	98
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3074691584
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3078304256
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	4
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1535267328
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	727282176
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2936050176
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1853338112
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	103
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4055814656
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	20
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	22
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	24
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	134
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	146
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	196
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	232
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3581047296
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	123
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	218
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	236
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1280250368
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1476801024
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3347927552
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	47
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	57
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	164
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	183
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3853148672
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	797
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.506376445
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	652988
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	30.8332996
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	14470

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1436841216	1436841216	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	9200	9200	✔
AngleVolantMsgTimer_mS_M_u32	1436841216	1436841216	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	24347	24347	✔
BSINodeAbsentTimer_mS_M_u32	1436841216	1436841216	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1436841216	1436841216	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1436841216	1436841216	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	36450	36450	✔
CONSANGLECPK_HwDeg_M_f32	-409.315613	-409.315613 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	36450	36450	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	545899008	545899008	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	34718	34718	✔
CityParkInputConsistentCount_Cnt_M_u16	65039	65039	✔
CityParkInputInvalidCount_Cnt_M_u16	12582	12582	✔
CityParkInputMsgTimer_mS_M_u32	1436841216	1436841216	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1436841216	1436841216	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1436841216	1436841216	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1436841216	1436841216	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1436841216	1436841216	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1436841216	1436841216	✔
ESPNTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1436841216	1436841216	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1436841216	1436841216	✔
EffacDefaultDiagTimer_mS_M_u32[1]	456	456	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	1436841216	1436841216	✔
ElecIntTimer_mS_M_u32[1]	67	67	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1436841216	1436841216	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1436841216	1436841216	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1436841216	1436841216	✔
IgnOnTimer_mS_M_u32	566891008	566891008	✔
IgnTimeOff_Sec_M_u32	3090163328	3090163328	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	98	98	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3074691584	3074691584	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	195	195	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3078304256	3078304256	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	4	4	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1535267328	1535267328	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	173	173	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	727282176	727282176	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3720827392	3720827392	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	86	86	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1853338112	1853338112	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	103	103	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4055814656	4055814656	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	232	232	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3581047296	3581047296	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	57	57	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1280250368	1280250368	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1476801024	1476801024	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	242	242	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3347927552	3347927552	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3853148672	3853148672	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	421.622711	421.622711	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	313.879395	313.879395	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	410.567505	410.567505	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	36450	36450	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3090163328	3090163328	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-409.315613	-409.315613 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.273 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	143031552
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	34482
AASNodeAbsentTimer_mS_M_u32	3933187328
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	23005
ANGLEVOLANTSigValidCount_Cnt_M_u16	122
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	56155
AngleVolantMsgTimer_mS_M_u32	143031552
AngleVolantValidCount_Cnt_M_u16	57892
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3746065664
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3439127808
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	4246904064
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3629014272
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	15496
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3845725440
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	48699
CAVNodeAbsentTimer_mS_M_u32	231722240
CDD_SrlComVehSpd_Kph_G_f32	43.0672989
CMM388NTCEnableTimer_mS_M_u32	1272122624
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	390974720
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	35925
CMMNodeAbsentTimer_mS_M_u32	2068864256
CONSANGLECPKSigInvalidCount_Cnt_M_u16	37842
CONSANGLECPKSigValidCount_Cnt_M_u16	35966
CONSANGLECPK_Cnt_M_u16	35517
CONSANGLECPK_HwDeg_M_f32	-548.121094
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	35517
CPKVehicleSpeedMsgTimer_mS_M_u32	3012132096
CPKVehicleSpeedValidCount_Cnt_M_u16	44148
CityParkInputConsistentCount_Cnt_M_u16	47480
CityParkInputInvalidCount_Cnt_M_u16	1336
CityParkInputMsgTimer_mS_M_u32	3074691584
CityParkInputValidCount_Cnt_M_u16	2

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2529406208
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	7174
ComputerRazGCTSigInvalidTimer_mS_M_u32	4218309888
ComputerRazGCTSigValidCount_Cnt_M_u16	25081
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	39396
DMDFCTCPKSigValidCount_Cnt_M_u16	35145
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	135
DMDRELAXECPKSigValidCount_Cnt_M_u16	12964
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	32123
DateInvalidTimer_mS_M_u32	3439127808
DiagMuxOnAbsentTimer_mS_M_u32	2161196288
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3629014272
ESPNTCEnableTimer_mS_M_u32	405581056
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	45181
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	99
EffacDefaultDiagTimer_mS_M_u32[1]	759
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	103
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	348331264
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	54745
EtatMTSigValidCount_Cnt_M_u16	32945
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	47228
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	48296
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	25799
ISDAT4V2BSI552MsgTimer_mS_M_u32	2124700928
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	33209
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	32441
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	32945
ISDATBSI3F2MsgTimer_mS_M_u32	338115840
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	17182
ISDATBSI412MsgLenValidCount_Cnt_M_u16	40335
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	54745
ISDATBSI412MsgTimer_mS_M_u32	2312928512
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	9897
ISDATBSI432MsgLenValidCount_Cnt_M_u16	8657
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	46744
ISDATDIRASentFltAcc_Cnt_M_u16	1980
ISDATDIRASentTimer_mS_M_u32	3012132096
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	4755
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	57892
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	20495
ISDYN2CMMMsgTimer_mS_M_u32	3048123648
ISDYNAASChkSumInvalidCount_Cnt_M_u16	2396
ISDYNAASChkSumValidCount_Cnt_M_u16	63641
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	34383
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	12218
ISDYNAASMsgLenValidCount_Cnt_M_u16	65535
ISDYNAASMsgTimeValidCount_Cnt_M_u16	2396
ISDYNAASMsgTimer_mS_M_u32	2441022720
ISDYNABRChkSumInvalidCount_Cnt_M_u16	1573
ISDYNABRChkSumValidCount_Cnt_M_u16	64746
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	46599
ISDYNABRMsgCountValidCount_Cnt_M_u16	24452
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	14205
ISDYNABRMsgLenValidCount_Cnt_M_u16	10857
ISDYNABRMsgTimeValidCount_Cnt_M_u16	35517
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	29229
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	48189
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	32945
ISDYNCMM208MsgTimer_mS_M_u32	722038016

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	29229
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	48189
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	20090
ISDYNCMM388MsgTimer_mS_M_u32	1655999744
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	65320
ISDYNVOLChkSumValidCount_Cnt_M_u16	60500
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	15418
ISDYNVOLMsgCountValidCount_Cnt_M_u16	24607
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	54994
ISDYNVOLMsgLenValidCount_Cnt_M_u16	26335
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	35925
ISDYNVOLMsgTimer_mS_M_u32	1025133824
IgnOnTimer_mS_M_u32	3574107392
IgnTimeOff_Sec_M_u32	454768041
ManVehSpd_Kph_M_f32	141.506195
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	148
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	108
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1376075008
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	4
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3777862912
PrevISDATBSI412MsgDLCError_Cnt_M_u08	135
PrevISDATBSI412MsgRxTime_MSec_M_u32	2179779840
PrevISDATBSI432MsgDLCError_Cnt_M_u08	147
PrevISDATBSI432MsgRxTime_MSec_M_u32	2586881280
PrevISDATDIRAMsgTxTime_MSec_M_u32	638635264
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	186
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1911414016
PrevISDYNAASMsgDLCError_Cnt_M_u08	55
PrevISDYNAASMsgRxTime_MSec_M_u32	3975171328
PrevISDYNABRMsgDLCError_Cnt_M_u08	56
PrevISDYNABRMsgRxTime_MSec_M_u32	3881864448
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	134
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1882279168
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	157
PrevISDYNCMM388MsgRxTime_MSec_M_u32	560966912
PrevISDYNVOLMsgDLCError_Cnt_M_u08	58
PrevISDYNVOLMsgRxTime_MSec_M_u32	3785739520
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2452782336
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	333.425903
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	49168
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	13668
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	58853
VitesseVehicleBVRampValidCount_Cnt_M_u16	33017
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	39730
VitesseVehicleBVSigValidCount_Cnt_M_u16	1935
VitesseVehicleBV_Kph_M_f32	59.2840004
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	20090
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	63151

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	634.511719
k_AASNTCEnableTimeout_mS_u16	37632
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	62971
k_AASNodeTimeout_mS_u16	60516
k_ABSNodeTimeout_mS_u16	14949
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	63168
k_ANGLEVOLANTSigValidThresh_Cnt_u16	42280
k_AngleVolantInvalidThresh_Cnt_u16	45691
k_AngleVolantValidThresh_Cnt_u16	1336
k_BSI552MsgTimeout_mS_u16	63938
k_BSINTCEnableTimeout_mS_u16	59649
k_BSINodeAbsentDiag_Cnt_str.Threshold	47272
k_BSINodeAbsentDiag_Cnt_str.PStep	38629
k_BSINodeAbsentDiag_Cnt_str.NStep	40661
k_BSINodeAbsentTimeout_mS_u16	51123
k_BSINodeTimeout_mS_u16	46744
k_BattOvHi_Volt_f32	5.63950014
k_BattOvLo_Volt_f32	21.9678001
k_BattUvHi_Volt_f32	30.9799004
k_BattUvLo_Volt_f32	11.1913996
k_CAVNTCEnableTimeout_mS_u16	42982
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	40337
k_CAVNodeTimeout_mS_u16	61822
k_CMM388MsgTimeout_mS_u16	32178
k_CMM388NTCEnableTimeout_mS_u16	10334
k_CMMNTCEnableTimeout_mS_u16	12305
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	40795
k_CONSANGLECPKMax_HwDeg_f32	604.126099
k_CONSANGLECPKMin_HwDeg_f32	-725.054016
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	50554
k_CONSANGLECPKSigValidThresh_Cnt_u16	44463
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	5858
k_CPKVehicleSpeedValidThresh_Cnt_u16	25437
k_CityParkInputInvalidThresh_Cnt_u16	15139
k_CityParkInputValidThresh_Cnt_u16	47480
k_ComputerRazGCTSigValidThresh_Cnt_u16	8215
k_CptTemporelSigValidThresh_Cnt_u16	51095
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	11901
k_DMDFCTCPKSigValidThresh_Cnt_u16	24937
k_DMDFCTCPKValidCount_Cnt_u16	5936
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	20495
k_DMDRELAXECPKSigValidThresh_Cnt_u16	6580
k_DMDRelaxeConsistentThresh_Cnt_u16	26162
k_DateValidThresh_Cnt_u16	25799
k_DefaultVehSpd_Kph_f32	124.426201
k_DiagMuxOnAbsentTimeout_mS_u16	2283
k_EMNodeTimeout_mS_u16	50523
k_ESPNTCEnableTimeout_mS_u16	38375
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	17667
k_EtatMTSigInvalidThresh_Cnt_u16	31192
k_EtatMTSigValidThresh_Cnt_u16	57565
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	28033
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	23994
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	51533
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	30978
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	35522
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	2930
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	61810
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	41306
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	253
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	39665

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	38146
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	33559
k_ISDATDIRASentDiag_Cnt_str.Threshold	39837
k_ISDATDIRASentDiag_Cnt_str.PStep	59486
k_ISDATDIRASentDiag_Cnt_str.NStep	60819
k_ISDATDIRASentTimeout_mS_u16	10705
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	39896
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	56155
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	48355
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	32037
k_ISDYNAASChkSumValidThresh_Cnt_u16	46058
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	44295
k_ISDYNAASMsgCountValidThresh_Cnt_u16	38532
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	39289
k_ISDYNAASMsgLenValidThresh_Cnt_u16	15288
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	45264
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	57811
k_ISDYNABRChkSumValidThresh_Cnt_u16	2367
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	13192
k_ISDYNABRMsgCountValidThresh_Cnt_u16	21605
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	17237
k_ISDYNABRMsgLenValidThresh_Cnt_u16	42877
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	18168
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	12132
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	32563
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	14967
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	20701
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	14202
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	58768
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	27061
k_ISDYNVOLChkSumValidThresh_Cnt_u16	22374
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	55334
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	10046
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	24197
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	29277
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	32245
k_IgnOnTimeout_mS_u16	45409
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	121.6884
k_PowerCutVehSpdLowThresh_Kph_f32	78.3525009
k_PowerCutVehSpdLowTimeout_mS_u16	48348
k_VBattMaxAAS_Volt_f32	26.0802002
k_VBattMaxBSI_Volt_f32	15.2320004
k_VBattMaxCAV_Volt_f32	15.0556002
k_VBattMaxCMM388_Volt_f32	23.3460007
k_VBattMaxCMM_Volt_f32	24.6301003
k_VBattMaxESP_Volt_f32	18.3670006
k_VBattMinAAS_Volt_f32	15.1819
k_VBattMinBSI_Volt_f32	18.3670006
k_VBattMinCAV_Volt_f32	16.0911999
k_VBattMinCMM388_Volt_f32	6.05679989
k_VBattMinCMM_Volt_f32	4.92589998
k_VBattMinESP_Volt_f32	24.6301003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	53338
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	35707
k_VitesseVehicleBVRampValidThresh_Cnt_u16	45882
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	9044
k_VitesseVehicleBVSigValidThresh_Cnt_u16	45477
k_VitesseVehicleBVSpeedPassThresh_kph_f32	489.832489
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	13627
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	50383
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3439127808
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	6206
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	314926080
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSe	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	157
target_SrlComInput_Per1_Batt_Volt_f32.value	31
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3212188928
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	229
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.400283158
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	17
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2090503424
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	146
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3228904704
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	179
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1491062016
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2916773120
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	660933888
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	234
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	763342080
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	157
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	673860864
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	12
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	25
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	175
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	191
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1401908480
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	58
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	84
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	107
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	115
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	120
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2843315456
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3402902784
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	12504320
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	49
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	248
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	782736640
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3434
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.421007186
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	90931
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	26.9015999
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	18450

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	314926080	314926080	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	314926080	314926080	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	314926080	314926080	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	314926080	314926080	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	314926080	314926080	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	314926080	314926080	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	314926080	314926080	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	47272	47272	✔
BSINodeAbsentTimer_mS_M_u32	314926080	314926080	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	314926080	314926080	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	314926080	314926080	✔
CDD_SrlComVehSpd_Kph_G_f32	141.506195	141.506195	✔
CMM388NTCEnableTimer_mS_M_u32	314926080	314926080	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	314926080	314926080	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	314926080	314926080	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	35517	35517	✔
CONSANGLECPK_HwDeg_M_f32	-548.121094	-548.121094 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	314926080	314926080	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	314926080	314926080	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	314926080	314926080	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	314926080	314926080	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	314926080	314926080	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	314926080	314926080	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	314926080	314926080	✔
ESPNTCEnableTimer_mS_M_u32	314926080	314926080	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	314926080	314926080	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	99	99	✔
EffacDefaultDiagTimer_mS_M_u32[1]	759	759	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	10	10	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	103	103	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	314926080	314926080	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	25799	25799	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	314926080	314926080	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	32945	32945	✔
ISDATBSI3F2MsgTimer_mS_M_u32	314926080	314926080	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	54745	54745	✔
ISDATBSI412MsgTimer_mS_M_u32	314926080	314926080	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	46744	46744	✔
ISDATBSI432MsgTimer_mS_M_u32	314926080	314926080	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	314926080	314926080	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	20495	20495	✔
ISDYN2CMMMsgTimer_mS_M_u32	314926080	314926080	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	2396	2396	✔
ISDYNAASMsgTimer_mS_M_u32	314926080	314926080	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	35517	35517	✔
ISDYNABRMsgTimer_mS_M_u32	314926080	314926080	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	32945	32945	✔
ISDYNCMM208MsgTimer_mS_M_u32	314926080	314926080	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	20090	20090	✔
ISDYNCMM388MsgTimer_mS_M_u32	314926080	314926080	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	35925	35925	✔
ISDYNVOLMsgTimer_mS_M_u32	314926080	314926080	✔
IgnOnTimer_mS_M_u32	3574107392	3574107392	✔
IgnTimeOff_Sec_M_u32	454768041	454768041	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	17	17	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2090503424	2090503424	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	146	146	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3228904704	3228904704	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	179	179	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1491062016	1491062016	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	221	221	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2916773120	2916773120	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	638635264	638635264	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	234	234	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	763342080	763342080	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	157	157	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	673860864	673860864	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	208	208	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1401908480	1401908480	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	120	120	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2843315456	2843315456	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	246	246	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3402902784	3402902784	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	212	212	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	12504320	12504320	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	782736640	782736640	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	333.425903	333.425903	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	59.2840004	59.2840004	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	634.511719	634.511719	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	35517	35517	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	454768041	454768041	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-548.121094	-548.121094 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.274 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3963571200
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	50105
AASNodeAbsentTimer_mS_M_u32	2806234112
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	5178
ANGLEVOLANTSigValidCount_Cnt_M_u16	44836
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	43454
AngleVolantMsgTimer_mS_M_u32	3963571200
AngleVolantValidCount_Cnt_M_u16	65508
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	465140736
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3298556928
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	652930048
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4100434944
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	55353
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3903286272
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	58785
CAVNodeAbsentTimer_mS_M_u32	1705204736
CDD_SrlComVehSpd_Kph_G_f32	611.932312
CMM388NTCEnableTimer_mS_M_u32	3365510144
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3240713216
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	36627
CMMNodeAbsentTimer_mS_M_u32	2472651776
CONSANGLECPKSigInvalidCount_Cnt_M_u16	10588
CONSANGLECPKSigValidCount_Cnt_M_u16	3605
CONSANGLECPK_Cnt_M_u16	53080
CONSANGLECPK_HwDeg_M_f32	-719.080383
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	53080
CPKVehicleSpeedMsgTimer_mS_M_u32	3073788928
CPKVehicleSpeedValidCount_Cnt_M_u16	57854
CityParkInputConsistentCount_Cnt_M_u16	51688
CityParkInputInvalidCount_Cnt_M_u16	14248
CityParkInputMsgTimer_mS_M_u32	2090503424
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4064787456
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	21437

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	919067648
ComputerRazGCTSigValidCount_Cnt_M_u16	5221
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	10660
DMDFCTCPKSigValidCount_Cnt_M_u16	2614
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	18492
DMDRELAXECPKSigValidCount_Cnt_M_u16	16550
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	20577
DateInvalidTimer_mS_M_u32	3298556928
DiagMuxOnAbsentTimer_mS_M_u32	509545472
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4100434944
ESPNTCEnableTimer_mS_M_u32	1376566272
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	57689
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1121
EffacDefaultDiagTimer_mS_M_u32[1]	2235
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	658
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	34171904
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	4998
EtatMTSigValidCount_Cnt_M_u16	37308
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	58206
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	42391
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	61372
ISDAT4V2BSI552MsgTimer_mS_M_u32	3647319040
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	59239
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	3877
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	37308
ISDATBSI3F2MsgTimer_mS_M_u32	1012730880
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	51255
ISDATBSI412MsgLenValidCount_Cnt_M_u16	38821
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	4998
ISDATBSI412MsgTimer_mS_M_u32	1077758976
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	4119
ISDATBSI432MsgLenValidCount_Cnt_M_u16	56669
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	45194
ISDATDIRASentFltAcc_Cnt_M_u16	19742
ISDATDIRASentTimer_mS_M_u32	3073788928
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	4054
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	65508
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	29475
ISDYN2CMMMsgTimer_mS_M_u32	25607168
ISDYNAASChkSumInvalidCount_Cnt_M_u16	25531
ISDYNAASChkSumValidCount_Cnt_M_u16	42181
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	32611
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	19748
ISDYNAASMsgLenValidCount_Cnt_M_u16	13131
ISDYNAASMsgTimeValidCount_Cnt_M_u16	25531
ISDYNAASMsgTimer_mS_M_u32	2811599872
ISDYNABRChkSumInvalidCount_Cnt_M_u16	34530
ISDYNABRChkSumValidCount_Cnt_M_u16	53588
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	51642
ISDYNABRMsgCountValidCount_Cnt_M_u16	56324
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	43611
ISDYNABRMsgLenValidCount_Cnt_M_u16	41044
ISDYNABRMsgTimeValidCount_Cnt_M_u16	53080
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	34125
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	28895
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	37308
ISDYNCMM208MsgTimer_mS_M_u32	2088139776
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	34125
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	28895
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	37602

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3925154816
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	48986
ISDYNVOLChkSumValidCount_Cnt_M_u16	50835
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	6818
ISDYNVOLMsgCountValidCount_Cnt_M_u16	23988
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	602
ISDYNVOLMsgLenValidCount_Cnt_M_u16	41204
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	36627
ISDYNVOLMsgTimer_mS_M_u32	566483968
IgnOnTimer_mS_M_u32	3807976448
IgnTimeOff_Sec_M_u32	1526247704
ManVehSpd_Kph_M_f32	523.644775
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	149
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	235
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2059602944
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	144
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1724509184
PrevISDATBSI412MsgDLCError_Cnt_M_u08	95
PrevISDATBSI412MsgRxTime_MSec_M_u32	3175898112
PrevISDATBSI432MsgDLCError_Cnt_M_u08	211
PrevISDATBSI432MsgRxTime_MSec_M_u32	3691035648
PrevISDATDIRAMsgTxTime_MSec_M_u32	1625316352
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	128
PrevISDYN2CMMMsgRxTime_MSec_M_u32	92875776
PrevISDYNAASMsgDLCError_Cnt_M_u08	15
PrevISDYNAASMsgRxTime_MSec_M_u32	3930184704
PrevISDYNABRMsgDLCError_Cnt_M_u08	64
PrevISDYNABRMsgRxTime_MSec_M_u32	200350720
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	119
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2759777280
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	252
PrevISDYNCMM388MsgRxTime_MSec_M_u32	37993472
PrevISDYNVOLMsgDLCError_Cnt_M_u08	75
PrevISDYNVOLMsgRxTime_MSec_M_u32	3256966144
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4282076160
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	156.196793
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	29730
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	33508
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	38563
VitesseVehicleBVRampValidCount_Cnt_M_u16	13349
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	58427
VitesseVehicleBVSigValidCount_Cnt_M_u16	11749
VitesseVehicleBV_Kph_M_f32	145.378204
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	37602
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	35076
VitesseVehiculeRoues_Kph_M_f32	418.19931
k_AASNTCEnableTimeout_mS_u16	33423
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	57439
k_AASNodeTimeout_mS_u16	24036
k_ABSNodeTimeout_mS_u16	35873
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	48082
k_ANGLEVOLANTSigValidThresh_Cnt_u16	28504
k_AngleVolantInvalidThresh_Cnt_u16	21343
k_AngleVolantValidThresh_Cnt_u16	14248
k_BSI552MsgTimeout_mS_u16	35787
k_BSINTCEnableTimeout_mS_u16	10511
k_BSINodeAbsentDiag_Cnt_str.Threshold	46429
k_BSINodeAbsentDiag_Cnt_str.PStep	32999
k_BSINodeAbsentDiag_Cnt_str.NStep	40789
k_BSINodeAbsentTimeout_mS_u16	17590
k_BSINodeTimeout_mS_u16	45194
k_BattOvHi_Volt_f32	25.7469997
k_BattOvLo_Volt_f32	13.8006001
k_BattUvHi_Volt_f32	21.1371002
k_BattUvLo_Volt_f32	3.15630007
k_CAVNTCEnableTimeout_mS_u16	34718
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	8095
k_CAVNodeTimeout_mS_u16	49240
k_CMM388MsgTimeout_mS_u16	57017
k_CMM388NTCEnableTimeout_mS_u16	36533
k_CMMNTCEnableTimeout_mS_u16	15455
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	16128
k_CONSANGLECPKMax_HwDeg_f32	54.1609001
k_CONSANGLECPKMin_HwDeg_f32	-595.299805
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	11746
k_CONSANGLECPKSigValidThresh_Cnt_u16	25604
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	22122
k_CPKVehicleSpeedValidThresh_Cnt_u16	9082
k_CityParkInputInvalidThresh_Cnt_u16	24552
k_CityParkInputValidThresh_Cnt_u16	51688
k_ComputerRazGCTSigValidThresh_Cnt_u16	1101
k_CptTemporelSigValidThresh_Cnt_u16	11403
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	50523
k_DMDFCTCPKSigValidThresh_Cnt_u16	64340
k_DMDFCTCPKValidCount_Cnt_u16	59457
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	29475
k_DMDRELAXECPKSigValidThresh_Cnt_u16	50421
k_DMDRelaxeConsistentThresh_Cnt_u16	22395
k_DateValidThresh_Cnt_u16	61372
k_DefaultVehSpd_Kph_f32	243.044601
k_DiagMuxOnAbsentTimeout_mS_u16	36046
k_EMNodeTimeout_mS_u16	63681
k_ESPNTCEnableTimeout_mS_u16	3741
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	60936
k_EtatMTSigInvalidThresh_Cnt_u16	47049
k_EtatMTSigValidThresh_Cnt_u16	45435
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	36493
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	48291
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	11881
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	25996
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	20234
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	48955
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	5052
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	49858
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	53531
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	28348
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	57162
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	32075
k_ISDATDIRASentDiag_Cnt_str.Threshold	47253

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	61715
k_ISDATDIRASentDiag_Cnt_str.NStep	53301
k_ISDATDIRASentTimeout_mS_u16	52190
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	30472
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	43454
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	35241
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	8674
k_ISDYNAASChkSumValidThresh_Cnt_u16	44116
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	58554
k_ISDYNAASMsgCountValidThresh_Cnt_u16	14084
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	7398
k_ISDYNAASMsgLenValidThresh_Cnt_u16	49128
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	60512
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	33625
k_ISDYNABRChkSumValidThresh_Cnt_u16	56274
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	62265
k_ISDYNABRMsgCountValidThresh_Cnt_u16	8035
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	27155
k_ISDYNABRMsgLenValidThresh_Cnt_u16	64601
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	21418
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	30246
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	43000
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	32683
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	12090
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	2596
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	63136
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	28786
k_ISDYNVOLChkSumValidThresh_Cnt_u16	34336
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	20062
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	41560
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	10626
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	27832
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	56370
k_IgnOnTimeout_mS_u16	18798
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	111.758003
k_PowerCutVehSpdLowThresh_Kph_f32	25.7658005
k_PowerCutVehSpdLowTimeout_mS_u16	29947
k_VBattMaxAAS_Volt_f32	7.65280008
k_VBattMaxBSI_Volt_f32	8.29310036
k_VBattMaxCAV_Volt_f32	26.7723007
k_VBattMaxCMM388_Volt_f32	31.8719006
k_VBattMaxCMM_Volt_f32	22.4444008
k_VBattMaxESP_Volt_f32	19.0294991
k_VBattMinAAS_Volt_f32	5.12400007
k_VBattMinBSI_Volt_f32	19.0294991
k_VBattMinCAV_Volt_f32	31.7542992
k_VBattMinCMM388_Volt_f32	5.20340014
k_VBattMinCMM_Volt_f32	5.08330011
k_VBattMinESP_Volt_f32	22.4444008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	24962
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	52960
k_VitesseVehicleBVRampValidThresh_Cnt_u16	46498
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	8595
k_VitesseVehicleBVSigValidThresh_Cnt_u16	54625
k_VitesseVehicleBVSpeedPassThresh_kph_f32	613.159729
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	32929
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	16547
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3298556928
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	55180
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3453916928
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	252
target_SrlComInput_Per1_Batt_Volt_f32.value	29.8048
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2381343744
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	60
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0900673643
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3024296960
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	456342528
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	179
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3295894528
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2013494272
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4259552256
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	504609792
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2694044672
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	57
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	72
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	169
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	209
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2598665216
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	80
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	92
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1772493824
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	213
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	940981248
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	139
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	148265984
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	58
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	109
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	121
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	138
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	140
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	178
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3864783872
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1277
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.771967888
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	728145
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	90.3685989
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	25628

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3453916928	3453916928	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	43454	43454	✔
AngleVolantMsgTimer_mS_M_u32	3453916928	3453916928	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	46429	46429	✔
BSINodeAbsentTimer_mS_M_u32	3453916928	3453916928	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3453916928	3453916928	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3453916928	3453916928	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	53080	53080	✔
CONSANGLECPK_HwDeg_M_f32	-719.080383	-719.080383 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	53080	53080	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3073788928	3073788928	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	57854	57854	✔
CityParkInputConsistentCount_Cnt_M_u16	51688	51688	✔
CityParkInputInvalidCount_Cnt_M_u16	14250	14250	✔
CityParkInputMsgTimer_mS_M_u32	3453916928	3453916928	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3453916928	3453916928	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3453916928	3453916928	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3453916928	3453916928	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3453916928	3453916928	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3453916928	3453916928	✔
ESPNTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3453916928	3453916928	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3453916928	3453916928	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2235	2235	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3453916928	3453916928	✔
ElecIntTimer_mS_M_u32[1]	658	658	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3453916928	3453916928	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3453916928	3453916928	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3453916928	3453916928	✔
IgnOnTimer_mS_M_u32	3807976448	3807976448	✔
IgnTimeOff_Sec_M_u32	1526247704	1526247704	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	51	51	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3024296960	3024296960	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	195	195	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	456342528	456342528	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	179	179	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3295894528	3295894528	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	200	200	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2013494272	2013494272	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1625316352	1625316352	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	134	134	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	504609792	504609792	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	190	190	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2694044672	2694044672	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	2	2	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2598665216	2598665216	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	60	60	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1772493824	1772493824	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	213	213	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	940981248	940981248	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	139	139	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	148265984	148265984	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3864783872	3864783872	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	156.196793	156.196793	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	145.378204	145.378204	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	418.19931	418.19931	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	53080	53080	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1526247704	1526247704	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-719.080383	-719.080383 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.275 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3943751424
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	28321
AASNodeAbsentTimer_mS_M_u32	2546175744
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	7967
ANGLEVOLANTSigValidCount_Cnt_M_u16	41506
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	4242
AngleVolantMsgTimer_mS_M_u32	3943751424
AngleVolantValidCount_Cnt_M_u16	52895
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1096961792
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4038774528
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	4052614912
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1813495552
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	36642
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1045987072
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	44906
CAVNodeAbsentTimer_mS_M_u32	3810832128
CDD_SrlComVehSpd_Kph_G_f32	374.370789
CMM388NTCEnableTimer_mS_M_u32	1665265408
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1754443520
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	30675
CMMNodeAbsentTimer_mS_M_u32	4146708224
CONSANGLECPKSigInvalidCount_Cnt_M_u16	38586
CONSANGLECPKSigValidCount_Cnt_M_u16	31820
CONSANGLECPK_Cnt_M_u16	1155
CONSANGLECPK_HwDeg_M_f32	-492.887695
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	1155
CPKVehicleSpeedMsgTimer_mS_M_u32	640409344
CPKVehicleSpeedValidCount_Cnt_M_u16	34108

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	32915
CityParkInputInvalidCount_Cnt_M_u16	17494
CityParkInputMsgTimer_mS_M_u32	3024296960
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3333918464
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	52885
ComputerRazGCTSigInvalidTimer_mS_M_u32	2713136896
ComputerRazGCTSigValidCount_Cnt_M_u16	54556
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	24162
DMDFCTCPKSigValidCount_Cnt_M_u16	45164
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	2841
DMDRELAXECPKSigValidCount_Cnt_M_u16	30108
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	30123
DateInvalidTimer_mS_M_u32	4038774528
DiagMuxOnAbsentTimer_mS_M_u32	2209455872
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1813495552
ESPNTCEnableTimer_mS_M_u32	4217933568
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	17602
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	41
EffacDefaultDiagTimer_mS_M_u32[1]	46
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	54
ElecIntTimer_mS_M_u32[1]	68
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	4197613312
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	51066
EtatMTSigValidCount_Cnt_M_u16	53400
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	61620
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	15814
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	38874
ISDAT4V2BSI552MsgTimer_mS_M_u32	891141888
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	50521
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	61919
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	53400
ISDATBSI3F2MsgTimer_mS_M_u32	2713165568
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	46056
ISDATBSI412MsgLenValidCount_Cnt_M_u16	43358
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	51066
ISDATBSI412MsgTimer_mS_M_u32	1729552128
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1223
ISDATBSI432MsgLenValidCount_Cnt_M_u16	24758
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	12975
ISDATDIRASentFltAcc_Cnt_M_u16	44275
ISDATDIRASentTimer_mS_M_u32	640409344
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	47881
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	52895
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	15845
ISDYN2CMMMsgTimer_mS_M_u32	1425706752
ISDYNAASChkSumInvalidCount_Cnt_M_u16	5787
ISDYNAASChkSumValidCount_Cnt_M_u16	10045
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	3106
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0
ISDYNAASMsgLenValidCount_Cnt_M_u16	29659
ISDYNAASMsgTimeValidCount_Cnt_M_u16	5787
ISDYNAASMsgTimer_mS_M_u32	3058560768
ISDYNABRChkSumInvalidCount_Cnt_M_u16	24742
ISDYNABRChkSumValidCount_Cnt_M_u16	62736
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	41118
ISDYNABRMsgCountValidCount_Cnt_M_u16	15744
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	53181
ISDYNABRMsgLenValidCount_Cnt_M_u16	33167
ISDYNABRMsgTimeValidCount_Cnt_M_u16	1155

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	44505
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	36324
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	53400
ISDYNCMM208MsgTimer_mS_M_u32	1395347200
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	44505
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	36324
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	36261
ISDYNCMM388MsgTimer_mS_M_u32	3442437888
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	19648
ISDYNVOLChkSumValidCount_Cnt_M_u16	51922
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	872
ISDYNVOLMsgCountValidCount_Cnt_M_u16	11762
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	9663
ISDYNVOLMsgLenValidCount_Cnt_M_u16	23985
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	30675
ISDYNVOLMsgTimer_mS_M_u32	3502452480
IgnOnTimer_mS_M_u32	4062408448
IgnTimeOff_Sec_M_u32	1894892311
ManVehSpd_Kph_M_f32	18.1457996
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	151
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	102
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4270169856
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	54
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1844510464
PrevISDATBSI412MsgDLCError_Cnt_M_u08	194
PrevISDATBSI412MsgRxTime_MSec_M_u32	3223957248
PrevISDATBSI432MsgDLCError_Cnt_M_u08	159
PrevISDATBSI432MsgRxTime_MSec_M_u32	764186368
PrevISDATDIRAMsgTxTime_MSec_M_u32	627945216
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	51
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2662547200
PrevISDYNAASMsgDLCError_Cnt_M_u08	118
PrevISDYNAASMsgRxTime_MSec_M_u32	4014550784
PrevISDYNABRMsgDLCError_Cnt_M_u08	65
PrevISDYNABRMsgRxTime_MSec_M_u32	1463512832
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	59
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4103220992
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	81
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2260963072
PrevISDYNVOLMsgDLCError_Cnt_M_u08	242
PrevISDYNVOLMsgRxTime_MSec_M_u32	1168813824
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2719801088
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	495.556793
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	18407
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	53089
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	9316
VitesseVehicleBVRampValidCount_Cnt_M_u16	65438
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	62236

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	27103
VitesseVehicleBV_Kph_M_f32	402.385101
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	36261
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	57088
VitesseVehiculeRoues_Kph_M_f32	151.809799
k_AASNTCEnableTimeout_mS_u16	34526
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	55598
k_AASNodeTimeout_mS_u16	15969
k_ABSNodeTimeout_mS_u16	27371
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	44438
k_ANGLEVOLANTSigValidThresh_Cnt_u16	22213
k_AngleVolantInvalidThresh_Cnt_u16	34480
k_AngleVolantValidThresh_Cnt_u16	17494
k_BSI552MsgTimeout_mS_u16	45739
k_BSINTCEnableTimeout_mS_u16	39391
k_BSINodeAbsentDiag_Cnt_str.Threshold	4907
k_BSINodeAbsentDiag_Cnt_str.PStep	32204
k_BSINodeAbsentDiag_Cnt_str.NStep	32705
k_BSINodeAbsentTimeout_mS_u16	8106
k_BSINodeTimeout_mS_u16	12975
k_BattOvHi_Volt_f32	14.2995996
k_BattOvLo_Volt_f32	4.02299976
k_BattUvHi_Volt_f32	8.89589977
k_BattUvLo_Volt_f32	2.37680006
k_CAVNTCEnableTimeout_mS_u16	44148
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	31088
k_CAVNodeTimeout_mS_u16	49606
k_CMM388MsgTimeout_mS_u16	7585
k_CMM388NTCEnableTimeout_mS_u16	64941
k_CMMNTCEnableTimeout_mS_u16	42609
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	44300
k_CONSANGLECPKMax_HwDeg_f32	294.547791
k_CONSANGLECPKMin_HwDeg_f32	-231.0672
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	48293
k_CONSANGLECPKSigValidThresh_Cnt_u16	19968
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	60623
k_CPKVehicleSpeedValidThresh_Cnt_u16	28191
k_CityParkInputInvalidThresh_Cnt_u16	28052
k_CityParkInputValidThresh_Cnt_u16	32915
k_ComputerRazGCTSigValidThresh_Cnt_u16	34471
k_CptTemporelSigValidThresh_Cnt_u16	45485
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	32445
k_DMDFCTCPKSigValidThresh_Cnt_u16	28815
k_DMDFCTCPKValidCount_Cnt_u16	32522
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	15845
k_DMDRELAXECPKSigValidThresh_Cnt_u16	15407
k_DMDRelaxeConsistentThresh_Cnt_u16	7325
k_DateValidThresh_Cnt_u16	38874
k_DefaultVehSpd_Kph_f32	175.173798
k_DiagMuxOnAbsentTimeout_mS_u16	9249
k_EMNodeTimeout_mS_u16	64651
k_ESPNTCEnableTimeout_mS_u16	9334
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	49140
k_EtatMTSigInvalidThresh_Cnt_u16	10737
k_EtatMTSigValidThresh_Cnt_u16	45211
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	36966
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	2532
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	38672
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	7914
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	1584
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	57052

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	52696
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	33927
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	53691
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	46679
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	18541
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	13739
k_ISDATDIRASentDiag_Cnt_str.Threshold	25913
k_ISDATDIRASentDiag_Cnt_str.PStep	24447
k_ISDATDIRASentDiag_Cnt_str.NStep	62938
k_ISDATDIRASentTimeout_mS_u16	33202
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	31860
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	4242
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	58194
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	36774
k_ISDYNAASChkSumValidThresh_Cnt_u16	25616
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	20382
k_ISDYNAASMsgCountValidThresh_Cnt_u16	11392
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	44698
k_ISDYNAASMsgLenValidThresh_Cnt_u16	10325
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	65453
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	48323
k_ISDYNABRChkSumValidThresh_Cnt_u16	18197
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	15906
k_ISDYNABRMsgCountValidThresh_Cnt_u16	3429
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	59091
k_ISDYNABRMsgLenValidThresh_Cnt_u16	62402
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	19600
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	20955
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	22693
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	46348
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	52767
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	37154
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	59246
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	26423
k_ISDYNVOLChkSumValidThresh_Cnt_u16	35309
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	20915
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	37380
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	30086
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	12196
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	10872
k_IgnOnTimeout_mS_u16	52291
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	219.533707
k_PowerCutVehSpdLowThresh_Kph_f32	101.510201
k_PowerCutVehSpdLowTimeout_mS_u16	24474
k_VBattMaxAAS_Volt_f32	8.27670002
k_VBattMaxBSI_Volt_f32	3.06859994
k_VBattMaxCAV_Volt_f32	25.7805004
k_VBattMaxCMM388_Volt_f32	19.5694008
k_VBattMaxCMM_Volt_f32	31.5776005
k_VBattMaxESP_Volt_f32	9.43470001
k_VBattMinAAS_Volt_f32	22.5340004
k_VBattMinBSI_Volt_f32	9.43470001
k_VBattMinCAV_Volt_f32	19.5678997
k_VBattMinCMM388_Volt_f32	5.18330002
k_VBattMinCMM_Volt_f32	16.0818005
k_VBattMinESP_Volt_f32	31.5776005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	9478
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	172
k_VitesseVehicleBVRampValidThresh_Cnt_u16	12904
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	47570
k_VitesseVehicleBVSigValidThresh_Cnt_u16	33320
k_VitesseVehicleBVSpeedPassThresh_kph_f32	284.15921
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	56938
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	21028
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4038774528
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	43468
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3038707200
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	81
target_SrlComInput_Per1_Batt_Volt_f32.value	7.99910021
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2994568960
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	67
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0978955925
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	237
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	642084608
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1509232384
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	62
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	112504576
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3565440768
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1801711360
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1934855936
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2488479488
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	113
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	148
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	155
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	201
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	803294976
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	88
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	142
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	144
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	189
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	216
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	234
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	28
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1377595136
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	28
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1330384640
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2240524032
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	6
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	30
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	79
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	123
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	150
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	170
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3074096896
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	911
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.497987717
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	415361
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	176.951904
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	57337

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3038707200	3038707200	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3038707200	3038707200	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	4907	4907	✔
BSINodeAbsentTimer_mS_M_u32	3038707200	3038707200	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3038707200	3038707200	✔
CDD_SrlComVehSpd_Kph_G_f32	18.1457996	18.1457996	✔
CMM388NTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3038707200	3038707200	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	1155	1155	✔
CONSANGLECPK_HwDeg_M_f32	-492.887695	-492.887695 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3038707200	3038707200	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3038707200	3038707200	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3038707200	3038707200	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3038707200	3038707200	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3038707200	3038707200	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3038707200	3038707200	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3038707200	3038707200	✔
ESPNTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3038707200	3038707200	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	41	41	✔
EffacDefaultDiagTimer_mS_M_u32[1]	46	46	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	54	54	✔
ElecIntTimer_mS_M_u32[1]	68	68	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3038707200	3038707200	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	38874	38874	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	53400	53400	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	51066	51066	✔
ISDATBSI412MsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	12975	12975	✔
ISDATBSI432MsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3038707200	3038707200	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	15845	15845	✔
ISDYN2CMMMsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	5787	5787	✔
ISDYNAASMsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	1155	1155	✔
ISDYNABRMsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	53400	53400	✔
ISDYNCMM208MsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	36261	36261	✔
ISDYNCMM388MsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	30675	30675	✔
ISDYNVOLMsgTimer_mS_M_u32	3038707200	3038707200	✔
IgnOnTimer_mS_M_u32	4062408448	4062408448	✔
IgnTimeOff_Sec_M_u32	1894892311	1894892311	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	237	237	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	642084608	642084608	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	3	3	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1509232384	1509232384	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	62	62	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	112504576	112504576	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3565440768	3565440768	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	627945216	627945216	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	94	94	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1934855936	1934855936	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	190	190	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2488479488	2488479488	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	94	94	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	803294976	803294976	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	28	28	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1377595136	1377595136	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	28	28	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1330384640	1330384640	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	0	0	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2240524032	2240524032	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3074096896	3074096896	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	495.556793	495.556793	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	402.385101	402.385101	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	151.809799	151.809799	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	1155	1155	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1894892311	1894892311	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-492.887695	-492.887695 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	18.1457996	18.1457996	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.276 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3769116160
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	14326
AASNodeAbsentTimer_mS_M_u32	1095767552
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	16507
ANGLEVOLANTSigValidCount_Cnt_M_u16	48180
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	22051
AngleVolantMsgTimer_mS_M_u32	3769116160
AngleVolantValidCount_Cnt_M_u16	55930
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	796120576
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	594171392
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2846934528
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2433975808
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	48242
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	223430144
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	33307
CAVNodeAbsentTimer_mS_M_u32	3417093632
CDD_SrlComVehSpd_Kph_G_f32	576.973572
CMM388NTCEnableTimer_mS_M_u32	1347745280
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1935848960
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	55966
CMMNodeAbsentTimer_mS_M_u32	3084748288
CONSANGLECPKSigInvalidCount_Cnt_M_u16	46250
CONSANGLECPKSigValidCount_Cnt_M_u16	18612
CONSANGLECPK_Cnt_M_u16	19471
CONSANGLECPK_HwDeg_M_f32	-408.972809
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	19471
CPKVehicleSpeedMsgTimer_mS_M_u32	1532438016
CPKVehicleSpeedValidCount_Cnt_M_u16	16364
CityParkInputConsistentCount_Cnt_M_u16	38046
CityParkInputInvalidCount_Cnt_M_u16	8792
CityParkInputMsgTimer_mS_M_u32	642084608
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2222200320
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	59418

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	4193596928
ComputerRazGCTSigValidCount_Cnt_M_u16	64259
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	1076
DMDFCTCPKSigValidCount_Cnt_M_u16	13013
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	58509
DMDRELAXECPKSigValidCount_Cnt_M_u16	43462
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	7127
DateInvalidTimer_mS_M_u32	594171392
DiagMuxOnAbsentTimer_mS_M_u32	2311448064
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2433975808
ESPNTCEnableTimer_mS_M_u32	3932231168
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	10388
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	3
EffacDefaultDiagTimer_mS_M_u32[1]	6
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	104
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3250800128
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	21676
EtatMTSigValidCount_Cnt_M_u16	44561
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	3772
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	27718
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	46219
ISDAT4V2BSI552MsgTimer_mS_M_u32	3456206336
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	61071
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	32189
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	44561
ISDATBSI3F2MsgTimer_mS_M_u32	3350455808
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	28641
ISDATBSI412MsgLenValidCount_Cnt_M_u16	25663
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	21676
ISDATBSI412MsgTimer_mS_M_u32	76948992
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	962
ISDATBSI432MsgLenValidCount_Cnt_M_u16	42168
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	19532
ISDATDIRASentFltAcc_Cnt_M_u16	60800
ISDATDIRASentTimer_mS_M_u32	1532438016
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	49277
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	55930
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	12715
ISDYN2CMMMsgTimer_mS_M_u32	2779452928
ISDYNAASChkSumInvalidCount_Cnt_M_u16	43016
ISDYNAASChkSumValidCount_Cnt_M_u16	64226
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	60913
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	65535
ISDYNAASMsgLenValidCount_Cnt_M_u16	46471
ISDYNAASMsgTimeValidCount_Cnt_M_u16	43016
ISDYNAASMsgTimer_mS_M_u32	2268132864
ISDYNABRChkSumInvalidCount_Cnt_M_u16	44902
ISDYNABRChkSumValidCount_Cnt_M_u16	38631
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	54783
ISDYNABRMsgCountValidCount_Cnt_M_u16	33817
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	54689
ISDYNABRMsgLenValidCount_Cnt_M_u16	1259
ISDYNABRMsgTimeValidCount_Cnt_M_u16	19471
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	48753
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	13841
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	44561
ISDYNCMM208MsgTimer_mS_M_u32	1578685952
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	48753
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	13841
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	13672

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2827777536
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	10904
ISDYNVOLChkSumValidCount_Cnt_M_u16	62754
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	44322
ISDYNVOLMsgCountValidCount_Cnt_M_u16	21059
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	47517
ISDYNVOLMsgLenValidCount_Cnt_M_u16	54918
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	55966
ISDYNVOLMsgTimer_mS_M_u32	2630956544
IgnOnTimer_mS_M_u32	162559488
IgnTimeOff_Sec_M_u32	2581180706
ManVehSpd_Kph_M_f32	227.210693
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	152
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	253
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1766450688
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	87
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2156381696
PrevISDATBSI412MsgDLCError_Cnt_M_u08	200
PrevISDATBSI412MsgRxTime_MSec_M_u32	2292037120
PrevISDATBSI432MsgDLCError_Cnt_M_u08	131
PrevISDATBSI432MsgRxTime_MSec_M_u32	3824489984
PrevISDATDIRAMsgTxTime_MSec_M_u32	1758574080
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	249
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3342927360
PrevISDYNAASMsgDLCError_Cnt_M_u08	95
PrevISDYNAASMsgRxTime_MSec_M_u32	3644798464
PrevISDYNABRMsgDLCError_Cnt_M_u08	226
PrevISDYNABRMsgRxTime_MSec_M_u32	979924480
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	21
PrevISDYNCMM208MsgRxTime_MSec_M_u32	761542144
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	234
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1951405568
PrevISDYNVOLMsgDLCError_Cnt_M_u08	95
PrevISDYNVOLMsgRxTime_MSec_M_u32	1008383488
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3951306240
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	13.4371996
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	60580
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	15093
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	35629
VitesseVehicleBVRampValidCount_Cnt_M_u16	56894
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	63620
VitesseVehicleBVSigValidCount_Cnt_M_u16	39165
VitesseVehicleBV_Kph_M_f32	13.4947996
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	13672
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	42522
VitesseVehiculeRoues_Kph_M_f32	374.237091
k_AASNTCEnableTimeout_mS_u16	61694
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	46797
k_AASNodeTimeout_mS_u16	60917
k_ABSNodeTimeout_mS_u16	17049
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	1365
k_ANGLEVOLANTSigValidThresh_Cnt_u16	48779
k_AngleVolantInvalidThresh_Cnt_u16	39626
k_AngleVolantValidThresh_Cnt_u16	8792
k_BSI552MsgTimeout_mS_u16	38681
k_BSINTCEnableTimeout_mS_u16	42106
k_BSINodeAbsentDiag_Cnt_str.Threshold	44540
k_BSINodeAbsentDiag_Cnt_str.PStep	1625
k_BSINodeAbsentDiag_Cnt_str.NStep	59577
k_BSINodeAbsentTimeout_mS_u16	35035
k_BSINodeTimeout_mS_u16	19532
k_BattOvHi_Volt_f32	29.9857006
k_BattOvLo_Volt_f32	4.1624999
k_BattUvHi_Volt_f32	6.39680004
k_BattUvLo_Volt_f32	12.3385
k_CAVNTCEnableTimeout_mS_u16	57854
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	48137
k_CAVNodeTimeout_mS_u16	25478
k_CMM388MsgTimeout_mS_u16	10998
k_CMM388NTCEnableTimeout_mS_u16	47826
k_CMMNTCEnableTimeout_mS_u16	43847
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	27638
k_CONSANGLECPKMax_HwDeg_f32	629.100281
k_CONSANGLECPKMin_HwDeg_f32	-509.063385
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	43112
k_CONSANGLECPKSigValidThresh_Cnt_u16	22810
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	6827
k_CPKVehicleSpeedValidThresh_Cnt_u16	56636
k_CityParkInputInvalidThresh_Cnt_u16	49308
k_CityParkInputValidThresh_Cnt_u16	38046
k_ComputerRazGCTSigValidThresh_Cnt_u16	25253
k_CptTemporelSigValidThresh_Cnt_u16	63059
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	51361
k_DMDFCTCPKSigValidThresh_Cnt_u16	14315
k_DMDFCTCPKValidCount_Cnt_u16	36026
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	12715
k_DMDRELAXECPKSigValidThresh_Cnt_u16	23436
k_DMDRelaxeConsistentThresh_Cnt_u16	62018
k_DateValidThresh_Cnt_u16	46219
k_DefaultVehSpd_Kph_f32	10.8331003
k_DiagMuxOnAbsentTimeout_mS_u16	58677
k_EMNodeTimeout_mS_u16	1847
k_ESPNTCEnableTimeout_mS_u16	21239
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	54078
k_EtatMTSigInvalidThresh_Cnt_u16	16261
k_EtatMTSigValidThresh_Cnt_u16	20550
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	19430
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	54316
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	34087
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	26076
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	50378
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	48901
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	11407
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	48453
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	27878
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	34451
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	9488
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	1944
k_ISDATDIRASentDiag_Cnt_str.Threshold	9798

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	30270
k_ISDATDIRASentDiag_Cnt_str.NStep	25322
k_ISDATDIRASentTimeout_mS_u16	31810
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	38717
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	22051
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	34403
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	8806
k_ISDYNAASChkSumValidThresh_Cnt_u16	18919
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	51455
k_ISDYNAASMsgCountValidThresh_Cnt_u16	46873
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	38282
k_ISDYNAASMsgLenValidThresh_Cnt_u16	25
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	25555
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	42639
k_ISDYNABRChkSumValidThresh_Cnt_u16	19545
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	44914
k_ISDYNABRMsgCountValidThresh_Cnt_u16	18027
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	36254
k_ISDYNABRMsgLenValidThresh_Cnt_u16	7060
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	62698
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	40648
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	46506
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	62964
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	13179
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	61236
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	39184
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	20980
k_ISDYNVOLChkSumValidThresh_Cnt_u16	48786
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	1473
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	36875
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	31368
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	49389
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	62641
k_IgnOnTimeout_mS_u16	21200
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	158.253494
k_PowerCutVehSpdLowThresh_Kph_f32	104.323799
k_PowerCutVehSpdLowTimeout_mS_u16	22218
k_VBattMaxAAS_Volt_f32	3.31719995
k_VBattMaxBSI_Volt_f32	28.8027
k_VBattMaxCAV_Volt_f32	23.2189999
k_VBattMaxCMM388_Volt_f32	14.5886002
k_VBattMaxCMM_Volt_f32	27.3871002
k_VBattMaxESP_Volt_f32	25.9790001
k_VBattMinAAS_Volt_f32	6.53249979
k_VBattMinBSI_Volt_f32	25.9790001
k_VBattMinCAV_Volt_f32	15.6564999
k_VBattMinCMM388_Volt_f32	10.9215002
k_VBattMinCMM_Volt_f32	12.6119003
k_VBattMinESP_Volt_f32	27.3871002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	25991
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	26452
k_VitesseVehicleBVRampValidThresh_Cnt_u16	8226
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	10274
k_VitesseVehicleBVSigValidThresh_Cnt_u16	9183
k_VitesseVehicleBVSpeedPassThresh_kph_f32	450.855896
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	62747
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	32428
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	594171392
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	45704
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3854158080
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	234
target_SrlComInput_Per1_Batt_Volt_f32.value	25.9218998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2229421568
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	252
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.651487112
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1967814144
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	184
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2696648192
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	237
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2700916224
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2114835968
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1072625152
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	193
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4003468800
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2451650048
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	85
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	140
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	190
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	192
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	536270336
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	67
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	131
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	187
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	231044608
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	139
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3702953472
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1081587200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	53
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	77
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	94
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	177
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	189
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1286194688
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3002
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.663219333
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	323887
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	94.2489014
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	60526

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3854158080	3854158080	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	44540	44540	✔
BSINodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
CDD_SrlComVehSpd_Kph_G_f32	227.210693	227.210693	✔
CMM388NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	19471	19471	✔
CONSANGLECPK_HwDeg_M_f32	-408.972809	-408.972809 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3854158080	3854158080	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3854158080	3854158080	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3854158080	3854158080	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3854158080	3854158080	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3854158080	3854158080	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3854158080	3854158080	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3854158080	3854158080	✔
ESPNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3	3	✔
EffacDefaultDiagTimer_mS_M_u32[1]	6	6	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	10	10	✔
ElecIntTimer_mS_M_u32[1]	104	104	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3854158080	3854158080	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	46219	46219	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	44561	44561	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	21676	21676	✔
ISDATBSI412MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	19532	19532	✔
ISDATBSI432MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3854158080	3854158080	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	12715	12715	✔
ISDYN2CMMMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	43016	43016	✔
ISDYNAASMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	19471	19471	✔
ISDYNABRMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	44561	44561	✔
ISDYNCMM208MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	13672	13672	✔
ISDYNCMM388MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	55966	55966	✔
ISDYNVOLMsgTimer_mS_M_u32	3854158080	3854158080	✔
IgnOnTimer_mS_M_u32	162559488	162559488	✔
IgnTimeOff_Sec_M_u32	2581180706	2581180706	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	84	84	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1967814144	1967814144	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	184	184	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2696648192	2696648192	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	237	237	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2700916224	2700916224	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	251	251	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2114835968	2114835968	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1758574080	1758574080	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	193	193	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4003468800	4003468800	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	137	137	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2451650048	2451650048	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	106	106	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	536270336	536270336	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	231044608	231044608	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	139	139	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3702953472	3702953472	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	195	195	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1081587200	1081587200	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1286194688	1286194688	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	13.4371996	13.4371996	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	13.4947996	13.4947996	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	374.237091	374.237091	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	19471	19471	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2581180706	2581180706	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-408.972809	-408.972809 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.277 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1505644800
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	44498
AASNodeAbsentTimer_mS_M_u32	59146496
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	17989
ANGLEVOLANTSigValidCount_Cnt_M_u16	50393
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	18251
AngleVolantMsgTimer_mS_M_u32	1505644800
AngleVolantValidCount_Cnt_M_u16	32454
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2015052032
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2520236288
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1763995904
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2918985984
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	28256
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1614999808
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	43492
CAVNodeAbsentTimer_mS_M_u32	519086336
CDD_SrlComVehSpd_Kph_G_f32	309.793915
CMM388NTCEnableTimer_mS_M_u32	2180505856
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2144248064
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	35609
CMMNodeAbsentTimer_mS_M_u32	3785240832
CONSANGLECPKSigInvalidCount_Cnt_M_u16	22710
CONSANGLECPKSigValidCount_Cnt_M_u16	52825
CONSANGLECPK_Cnt_M_u16	61512
CONSANGLECPK_HwDeg_M_f32	466.491394
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	61512
CPKVehicleSpeedMsgTimer_mS_M_u32	1706119424
CPKVehicleSpeedValidCount_Cnt_M_u16	53912
CityParkInputConsistentCount_Cnt_M_u16	57434
CityParkInputInvalidCount_Cnt_M_u16	44078
CityParkInputMsgTimer_mS_M_u32	1967814144
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3390734592
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	11622

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1444356352
ComputerRazGCTSigValidCount_Cnt_M_u16	33067
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	30362
DMDFCTCPKSigValidCount_Cnt_M_u16	31862
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	8719
DMDRELAXECPKSigValidCount_Cnt_M_u16	50211
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	5935
DateInvalidTimer_mS_M_u32	2520236288
DiagMuxOnAbsentTimer_mS_M_u32	90509568
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2918985984
ESPNTCEnableTimer_mS_M_u32	2354282752
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	33529
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	9
EffacDefaultDiagTimer_mS_M_u32[1]	81
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	659
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2330784000
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	57842
EtatMTSigValidCount_Cnt_M_u16	30593
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	4736
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	11171
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20308
ISDAT4V2BSI552MsgTimer_mS_M_u32	791818496
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	22984
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	28159
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	30593
ISDATBSI3F2MsgTimer_mS_M_u32	2207977728
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	61137
ISDATBSI412MsgLenValidCount_Cnt_M_u16	37752
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	57842
ISDATBSI412MsgTimer_mS_M_u32	636768512
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	40877
ISDATBSI432MsgLenValidCount_Cnt_M_u16	40589
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	20305
ISDATDIRASentFltAcc_Cnt_M_u16	15285
ISDATDIRASentTimer_mS_M_u32	1706119424
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	51966
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	32454
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	35381
ISDYN2CMMMsgTimer_mS_M_u32	41255168
ISDYNAASChkSumInvalidCount_Cnt_M_u16	9628
ISDYNAASChkSumValidCount_Cnt_M_u16	40656
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	57441
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	41001
ISDYNAASMsgLenValidCount_Cnt_M_u16	36191
ISDYNAASMsgTimeValidCount_Cnt_M_u16	9628
ISDYNAASMsgTimer_mS_M_u32	1298391296
ISDYNABRChkSumInvalidCount_Cnt_M_u16	24323
ISDYNABRChkSumValidCount_Cnt_M_u16	47678
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	14263
ISDYNABRMsgCountValidCount_Cnt_M_u16	40747
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	37329
ISDYNABRMsgLenValidCount_Cnt_M_u16	13748
ISDYNABRMsgTimeValidCount_Cnt_M_u16	61512
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	56820
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	12247
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	30593
ISDYNCMM208MsgTimer_mS_M_u32	3224125696
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	56820
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	12247
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	42492

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3075563776
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	12012
ISDYNVOLChkSumValidCount_Cnt_M_u16	271
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	46032
ISDYNVOLMsgCountValidCount_Cnt_M_u16	22060
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	13278
ISDYNVOLMsgLenValidCount_Cnt_M_u16	36578
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	35609
ISDYNVOLMsgTimer_mS_M_u32	3716358400
IgnOnTimer_mS_M_u32	602235136
IgnTimeOff_Sec_M_u32	2113133873
ManVehSpd_Kph_M_f32	363.676208
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	153
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	81
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1993937152
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	229
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	10449152
PrevISDATBSI412MsgDLCError_Cnt_M_u08	89
PrevISDATBSI412MsgRxTime_MSec_M_u32	3961364736
PrevISDATBSI432MsgDLCError_Cnt_M_u08	44
PrevISDATBSI432MsgRxTime_MSec_M_u32	4019683584
PrevISDATDIRAMsgTxTime_MSec_M_u32	461480192
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	53
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2708713728
PrevISDYNAASMsgDLCError_Cnt_M_u08	117
PrevISDYNAASMsgRxTime_MSec_M_u32	1614356736
PrevISDYNABRMsgDLCError_Cnt_M_u08	64
PrevISDYNABRMsgRxTime_MSec_M_u32	1908236544
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	72
PrevISDYNCMM208MsgRxTime_MSec_M_u32	935993600
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	137
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1787199744
PrevISDYNVOLMsgDLCError_Cnt_M_u08	33
PrevISDYNVOLMsgRxTime_MSec_M_u32	94806272
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2838122752
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	631.318909
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	52809
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	13589
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	22190
VitesseVehicleBVRampValidCount_Cnt_M_u16	44858
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	33322
VitesseVehicleBVSigValidCount_Cnt_M_u16	37502
VitesseVehicleBV_Kph_M_f32	156.837997
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	42492
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	9640
VitesseVehiculeRoues_Kph_M_f32	247.562195
k_AASNTCEnableTimeout_mS_u16	32123
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	62925
k_AASNodeTimeout_mS_u16	7189
k_ABSNodeTimeout_mS_u16	36715
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	42740
k_ANGLEVOLANTSigValidThresh_Cnt_u16	23828
k_AngleVolantInvalidThresh_Cnt_u16	33879
k_AngleVolantValidThresh_Cnt_u16	44078
k_BSI552MsgTimeout_mS_u16	3755
k_BSINTCEnableTimeout_mS_u16	40325
k_BSINodeAbsentDiag_Cnt_str.Threshold	45269
k_BSINodeAbsentDiag_Cnt_str.PStep	57087
k_BSINodeAbsentDiag_Cnt_str.NStep	32540
k_BSINodeAbsentTimeout_mS_u16	36643
k_BSINodeTimeout_mS_u16	20305
k_BattOvHi_Volt_f32	12.4893999
k_BattOvLo_Volt_f32	31.5
k_BattUvHi_Volt_f32	7.65560007
k_BattUvLo_Volt_f32	30.6776009
k_CAVNTCEnableTimeout_mS_u16	34108
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	13338
k_CAVNodeTimeout_mS_u16	48162
k_CMM388MsgTimeout_mS_u16	54482
k_CMM388NTCEnableTimeout_mS_u16	38206
k_CMMNTCEnableTimeout_mS_u16	928
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	17428
k_CONSANGLECPKMax_HwDeg_f32	509.740509
k_CONSANGLECPKMin_HwDeg_f32	-410.742188
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	19708
k_CONSANGLECPKSigValidThresh_Cnt_u16	3240
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	60915
k_CPKVehicleSpeedValidThresh_Cnt_u16	53952
k_CityParkInputInvalidThresh_Cnt_u16	33633
k_CityParkInputValidThresh_Cnt_u16	57434
k_ComputerRazGCTSigValidThresh_Cnt_u16	54662
k_CptTemporelSigValidThresh_Cnt_u16	56381
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	47313
k_DMDFCTCPKSigValidThresh_Cnt_u16	40116
k_DMDFCTCPKValidCount_Cnt_u16	7560
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	35381
k_DMDRELAXECPKSigValidThresh_Cnt_u16	40529
k_DMDRelaxeConsistentThresh_Cnt_u16	12847
k_DateValidThresh_Cnt_u16	20308
k_DefaultVehSpd_Kph_f32	119.7146
k_DiagMuxOnAbsentTimeout_mS_u16	15574
k_EMNodeTimeout_mS_u16	54543
k_ESPNTCEnableTimeout_mS_u16	42832
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	11836
k_EtatMTSigInvalidThresh_Cnt_u16	60070
k_EtatMTSigValidThresh_Cnt_u16	51745
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	1602
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	36658
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	29375
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	26593
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	3288
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	37221
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	39238
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	51430
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	62529
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	20668
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	30468
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	53422
k_ISDATDIRASentDiag_Cnt_str.Threshold	61866

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	48259
k_ISDATDIRASentDiag_Cnt_str.NStep	33088
k_ISDATDIRASentTimeout_mS_u16	26735
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	62911
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	18251
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	48396
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	1539
k_ISDYNAASChkSumValidThresh_Cnt_u16	41278
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	24247
k_ISDYNAASMsgCountValidThresh_Cnt_u16	1579
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	15511
k_ISDYNAASMsgLenValidThresh_Cnt_u16	30121
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	36156
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	22279
k_ISDYNABRChkSumValidThresh_Cnt_u16	38762
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	38240
k_ISDYNABRMsgCountValidThresh_Cnt_u16	49716
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	29209
k_ISDYNABRMsgLenValidThresh_Cnt_u16	43513
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	29367
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	18397
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	33142
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	49176
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	27973
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	11225
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	10246
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	21656
k_ISDYNVOLChkSumValidThresh_Cnt_u16	36991
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	57202
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	24274
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	57438
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	44781
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	42722
k_IgnOnTimeout_mS_u16	49668
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	115.9534
k_PowerCutVehSpdLowThresh_Kph_f32	221.742401
k_PowerCutVehSpdLowTimeout_mS_u16	31767
k_VBattMaxAAS_Volt_f32	0.646300018
k_VBattMaxBSI_Volt_f32	26.6058006
k_VBattMaxCAV_Volt_f32	20.7017002
k_VBattMaxCMM388_Volt_f32	29.3838005
k_VBattMaxCMM_Volt_f32	9.51879978
k_VBattMaxESP_Volt_f32	19.2537003
k_VBattMinAAS_Volt_f32	18.0384007
k_VBattMinBSI_Volt_f32	19.2537003
k_VBattMinCAV_Volt_f32	22.9897003
k_VBattMinCMM388_Volt_f32	15.8606005
k_VBattMinCMM_Volt_f32	6.6322999
k_VBattMinESP_Volt_f32	9.51879978
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	13025
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	28473
k_VitesseVehicleBVRampValidThresh_Cnt_u16	23248
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	26639
k_VitesseVehicleBVSigValidThresh_Cnt_u16	30359
k_VitesseVehicleBVSpeedPassThresh_kph_f32	565.724121
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	20708
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	1520
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2520236288
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	2529
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	282421248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	137
target_SrlComInput_Per1_Batt_Volt_f32.value	24.6361008
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2106585344
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	149
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.893435597
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	140
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3373752576
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4081320192
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3741360384
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1951219968
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2603213056
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	999719168
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	249
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1033052416
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	31
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	104
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	244
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1922187520
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	28
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	44
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	121
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	133
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	182
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	192
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	139
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2879807744
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	161
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3948085504
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2895094016
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	32
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	48
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	56
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	68
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	72
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	149
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2755227904
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3923
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.511685073
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	457059
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	115.2173
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	30443

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	282421248	282421248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	282421248	282421248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	18253	18253	✔
AngleVolantMsgTimer_mS_M_u32	282421248	282421248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	45269	45269	✔
BSINodeAbsentTimer_mS_M_u32	282421248	282421248	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	282421248	282421248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	282421248	282421248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	282421248	282421248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	61512	61512	✔
CONSANGLECPK_HwDeg_M_f32	466.491394	466.491394 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	61512	61512	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1706119424	1706119424	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	53912	53912	✔
CityParkInputConsistentCount_Cnt_M_u16	57434	57434	✔
CityParkInputInvalidCount_Cnt_M_u16	44078	44078	✔
CityParkInputMsgTimer_mS_M_u32	282421248	282421248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	282421248	282421248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	282421248	282421248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	282421248	282421248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	282421248	282421248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	282421248	282421248	✔
ESPNTCEnableTimer_mS_M_u32	282421248	282421248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	9	9	✔
EffacDefaultDiagTimer_mS_M_u32[1]	81	81	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	282421248	282421248	✔
ElecIntTimer_mS_M_u32[1]	659	659	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	282421248	282421248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	282421248	282421248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	282421248	282421248	✔
IgnOnTimer_mS_M_u32	282421248	282421248	✔
IgnTimeOff_Sec_M_u32	2113133873	2113133873	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	140	140	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3373752576	3373752576	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	108	108	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4081320192	4081320192	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	26	26	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3741360384	3741360384	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	125	125	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1951219968	1951219968	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	461480192	461480192	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	5	5	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	999719168	999719168	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	249	249	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1033052416	1033052416	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1922187520	1922187520	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	139	139	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2879807744	2879807744	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	161	161	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3948085504	3948085504	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2895094016	2895094016	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2755227904	2755227904	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	631.318909	631.318909	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	156.837997	156.837997	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	247.562195	247.562195	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	61512	61512	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2113133873	2113133873	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	466.491394	466.491394 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	119.7146	119.7146	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.278 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1357369344
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	18090
AASNodeAbsentTimer_mS_M_u32	4031725568
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	26450
ANGLEVOLANTSigValidCount_Cnt_M_u16	5719
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	40511
AngleVolantMsgTimer_mS_M_u32	1357369344
AngleVolantValidCount_Cnt_M_u16	43599
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3583049728
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2369486848
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3811930112
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	598618112
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	6913
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2547642368
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	49907
CAVNodeAbsentTimer_mS_M_u32	1854988288
CDD_SrlComVehSpd_Kph_G_f32	376.5961
CMM388NTCEnableTimer_mS_M_u32	1920671744
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1140252672
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	24341
CMMNodeAbsentTimer_mS_M_u32	2429038592
CONSANGLECPKSigInvalidCount_Cnt_M_u16	58112
CONSANGLECPKSigValidCount_Cnt_M_u16	60629
CONSANGLECPK_Cnt_M_u16	776
CONSANGLECPK_HwDeg_M_f32	-175.590698
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	776
CPKVehicleSpeedMsgTimer_mS_M_u32	3104755712
CPKVehicleSpeedValidCount_Cnt_M_u16	49760
CityParkInputConsistentCount_Cnt_M_u16	54675
CityParkInputInvalidCount_Cnt_M_u16	4886

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	3373752576
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3969073152
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	6126
ComputerRazGCTSigInvalidTimer_mS_M_u32	2199740416
ComputerRazGCTSigValidCount_Cnt_M_u16	30496
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	25554
DMDFCTCPKSigValidCount_Cnt_M_u16	40191
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	31732
DMDRELAXECPKSigValidCount_Cnt_M_u16	49273
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	52117
DateInvalidTimer_mS_M_u32	2369486848
DiagMuxOnAbsentTimer_mS_M_u32	1492357120
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	598618112
ESPNTCEnableTimer_mS_M_u32	3387441152
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	53814
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	20
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	54
ElecIntTimer_mS_M_u32[1]	69
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1071378432
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	2956
EtatMTSigValidCount_Cnt_M_u16	26013
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	23970
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	31991
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	7269
ISDAT4V2BSI552MsgTimer_mS_M_u32	4161548288
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	54154
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	20899
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	26013
ISDATBSI3F2MsgTimer_mS_M_u32	911314944
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	51567
ISDATBSI412MsgLenValidCount_Cnt_M_u16	22071
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	2956
ISDATBSI412MsgTimer_mS_M_u32	1145425920
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	29017
ISDATBSI432MsgLenValidCount_Cnt_M_u16	53114
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	50860
ISDATDIRASentFltAcc_Cnt_M_u16	37248
ISDATDIRASentTimer_mS_M_u32	3104755712
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	51942
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	43599
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	21761
ISDYN2CMMMsgTimer_mS_M_u32	1870807040
ISDYNAASChkSumInvalidCount_Cnt_M_u16	34636
ISDYNAASChkSumValidCount_Cnt_M_u16	50801
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	45438
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	29542
ISDYNAASMsgLenValidCount_Cnt_M_u16	40771
ISDYNAASMsgTimeValidCount_Cnt_M_u16	34636
ISDYNAASMsgTimer_mS_M_u32	3224838144
ISDYNABRChkSumInvalidCount_Cnt_M_u16	60569
ISDYNABRChkSumValidCount_Cnt_M_u16	42406
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	31995
ISDYNABRMsgCountValidCount_Cnt_M_u16	61792
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	25519
ISDYNABRMsgLenValidCount_Cnt_M_u16	58052
ISDYNABRMsgTimeValidCount_Cnt_M_u16	776
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	48008
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	39840

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	26013
ISDYNCMM208MsgTimer_mS_M_u32	0
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	48008
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	39840
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	36013
ISDYNCMM388MsgTimer_mS_M_u32	409903104
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	47198
ISDYNVOLChkSumValidCount_Cnt_M_u16	44211
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	1072
ISDYNVOLMsgCountValidCount_Cnt_M_u16	26589
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	37767
ISDYNVOLMsgLenValidCount_Cnt_M_u16	27964
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	24341
ISDYNVOLMsgTimer_mS_M_u32	2631491584
IgnOnTimer_mS_M_u32	582131712
IgnTimeOff_Sec_M_u32	138316314
ManVehSpd_Kph_M_f32	575.807922
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	154
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	126
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3566702592
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	218
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3368316928
PrevISDATBSI412MsgDLCError_Cnt_M_u08	44
PrevISDATBSI412MsgRxTime_MSec_M_u32	4211728384
PrevISDATBSI432MsgDLCError_Cnt_M_u08	163
PrevISDATBSI432MsgRxTime_MSec_M_u32	2954641408
PrevISDATDIRAMsgTxTime_MSec_M_u32	4242399232
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	73
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2269622272
PrevISDYNAASMsgDLCError_Cnt_M_u08	52
PrevISDYNAASMsgRxTime_MSec_M_u32	1823956992
PrevISDYNABRMsgDLCError_Cnt_M_u08	214
PrevISDYNABRMsgRxTime_MSec_M_u32	2569707520
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	222
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1778671616
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	219
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3142533120
PrevISDYNVOLMsgDLCError_Cnt_M_u08	45
PrevISDYNVOLMsgRxTime_MSec_M_u32	309256192
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	312725504
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	237.573502
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	10692
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	33
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	25749
VitesseVehicleBVRampValidCount_Cnt_M_u16	26034
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	34723
VitesseVehicleBVSigValidCount_Cnt_M_u16	33128
VitesseVehicleBV_Kph_M_f32	458.580994

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	36013
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	39018
VitesseVehiculeRoues_Kph_M_f32	605.594177
k_AASNTCEnableTimeout_mS_u16	59247
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	8506
k_AASNodeTimeout_mS_u16	19233
k_ABSNodeTimeout_mS_u16	40287
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	14212
k_ANGLEVOLANTSigValidThresh_Cnt_u16	28645
k_AngleVolantInvalidThresh_Cnt_u16	50716
k_AngleVolantValidThresh_Cnt_u16	4886
k_BSI552MsgTimeout_mS_u16	43361
k_BSINTCEnableTimeout_mS_u16	55249
k_BSINodeAbsentDiag_Cnt_str.Threshold	24165
k_BSINodeAbsentDiag_Cnt_str.PStep	11816
k_BSINodeAbsentDiag_Cnt_str.NStep	30736
k_BSINodeAbsentTimeout_mS_u16	9911
k_BSINodeTimeout_mS_u16	50860
k_BattOvHi_Volt_f32	23.0102997
k_BattOvLo_Volt_f32	5.85039997
k_BattUvHi_Volt_f32	4.31360006
k_BattUvLo_Volt_f32	7.70599985
k_CAVNTCEnableTimeout_mS_u16	16364
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	31825
k_CAVNodeTimeout_mS_u16	26812
k_CMM388MsgTimeout_mS_u16	53674
k_CMM388NTCEnableTimeout_mS_u16	16486
k_CMMNTCEnableTimeout_mS_u16	13826
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	60710
k_CONSANGLECPKMax_HwDeg_f32	118.614799
k_CONSANGLECPKMin_HwDeg_f32	-500.016296
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	38829
k_CONSANGLECPKSigValidThresh_Cnt_u16	58218
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	52615
k_CPKVehicleSpeedValidThresh_Cnt_u16	39330
k_CityParkInputInvalidThresh_Cnt_u16	30591
k_CityParkInputValidThresh_Cnt_u16	54675
k_ComputerRazGCTSigValidThresh_Cnt_u16	55376
k_CptTemporelSigValidThresh_Cnt_u16	32489
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	61103
k_DMDFCTCPKSigValidThresh_Cnt_u16	44484
k_DMDFCTCPKValidCount_Cnt_u16	44425
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	21761
k_DMDRELAXECPKSigValidThresh_Cnt_u16	25454
k_DMDRelaxeConsistentThresh_Cnt_u16	40916
k_DateValidThresh_Cnt_u16	7269
k_DefaultVehSpd_Kph_f32	33.4919014
k_DiagMuxOnAbsentTimeout_mS_u16	54622
k_EMNodeTimeout_mS_u16	4597
k_ESPNTCEnableTimeout_mS_u16	31407
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	52910
k_EtatMTSigInvalidThresh_Cnt_u16	38320
k_EtatMTSigValidThresh_Cnt_u16	49661
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	32922
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	32907
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	62052
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	19775
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	6424
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	12723
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	10382
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	62575

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	50077
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	45484
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	14741
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	10455
k_ISDATDIRASentDiag_Cnt_str.Threshold	28362
k_ISDATDIRASentDiag_Cnt_str.PStep	56832
k_ISDATDIRASentDiag_Cnt_str.NStep	61321
k_ISDATDIRASentTimeout_mS_u16	32853
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	15780
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	40511
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10619
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	63385
k_ISDYNAASChkSumValidThresh_Cnt_u16	61606
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	2043
k_ISDYNAASMsgCountValidThresh_Cnt_u16	48224
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	41949
k_ISDYNAASMsgLenValidThresh_Cnt_u16	36453
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	32621
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	27661
k_ISDYNABRChkSumValidThresh_Cnt_u16	5538
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	42497
k_ISDYNABRMsgCountValidThresh_Cnt_u16	19014
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	43541
k_ISDYNABRMsgLenValidThresh_Cnt_u16	23862
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	1213
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	3336
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	58752
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	11032
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	62034
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	57687
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	65422
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	29722
k_ISDYNVOLChkSumValidThresh_Cnt_u16	15138
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	57547
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	2026
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	49224
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	28505
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	52667
k_IgnOnTimeout_mS_u16	56278
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	9.27560043
k_PowerCutVehSpdLowThresh_Kph_f32	115.908401
k_PowerCutVehSpdLowTimeout_mS_u16	23451
k_VBattMaxAAS_Volt_f32	9.74470043
k_VBattMaxBSI_Volt_f32	20.618
k_VBattMaxCAV_Volt_f32	7.29610014
k_VBattMaxCMM388_Volt_f32	32
k_VBattMaxCMM_Volt_f32	3.88109994
k_VBattMaxESP_Volt_f32	24.1441994
k_VBattMinAAS_Volt_f32	8.45409966
k_VBattMinBSI_Volt_f32	24.1441994
k_VBattMinCAV_Volt_f32	28.6306
k_VBattMinCMM388_Volt_f32	15.0197001
k_VBattMinCMM_Volt_f32	22.1762009
k_VBattMinESP_Volt_f32	3.88109994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	36414
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	5111
k_VitesseVehicleBVRampValidThresh_Cnt_u16	3888
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	30643
k_VitesseVehicleBVSigValidThresh_Cnt_u16	18140
k_VitesseVehicleBVSpeedPassThresh_kph_f32	632.413574
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	52723
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	47504
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2369486848
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16 Elaps	57136
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	146705152
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	219

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	13.0461998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3019042816
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	240
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.258763641
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2065473536
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4145463296
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1851842560
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	687538176
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1860509696
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2283749376
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3165216768
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	55
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	64
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	18
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2183921664
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	24
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	62
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	166
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3480199168
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	183091200
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	28565504
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	33
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	146
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	185
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3321262080
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3072
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.432254016
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	376668
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	77.733902
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	14302

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	146705152	146705152	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	146705152	146705152	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	146705152	146705152	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	146705152	146705152	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
CDD_SrlComVehSpd_Kph_G_f32	575.807922	575.807922	✔
CMM388NTCEnableTimer_mS_M_u32	146705152	146705152	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	146705152	146705152	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	776	776	✔
CONSANGLECPK_HwDeg_M_f32	-175.590698	-175.590698 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	146705152	146705152	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	146705152	146705152	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	146705152	146705152	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	146705152	146705152	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	146705152	146705152	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	146705152	146705152	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	146705152	146705152	✔
ESPNTCEnableTimer_mS_M_u32	146705152	146705152	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	20	20	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	54	54	✔
ElecIntTimer_mS_M_u32[1]	69	69	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	146705152	146705152	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	7269	7269	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	26013	26013	✔
ISDATBSI3F2MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	2956	2956	✔
ISDATBSI412MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	50860	50860	✔
ISDATBSI432MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	146705152	146705152	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	21761	21761	✔
ISDYN2CMMMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	34636	34636	✔
ISDYNAASMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	776	776	✔
ISDYNABRMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	26013	26013	✔
ISDYNCMM208MsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	36013	36013	✔
ISDYNCMM388MsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	24341	24341	✔
ISDYNVOLMsgTimer_mS_M_u32	146705152	146705152	✔
IgnOnTimer_mS_M_u32	582131712	582131712	✔
IgnTimeOff_Sec_M_u32	138316314	138316314	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2065473536	2065473536	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4145463296	4145463296	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	86	86	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1851842560	1851842560	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	134	134	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	687538176	687538176	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4242399232	4242399232	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2283749376	2283749376	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3165216768	3165216768	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	18	18	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2183921664	2183921664	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	9	9	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3480199168	3480199168	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	183091200	183091200	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	210	210	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	28565504	28565504	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3321262080	3321262080	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	237.573502	237.573502	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	458.580994	458.580994	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	605.594177	605.594177	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	776	776	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	138316314	138316314	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-175.590698	-175.590698 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	575.807922	575.807922	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.279 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4096217856
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	15583
AASNodeAbsentTimer_mS_M_u32	1068565248
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	7398
ANGLEVOLANTSigValidCount_Cnt_M_u16	36759
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	51744
AngleVolantMsgTimer_mS_M_u32	4096217856
AngleVolantValidCount_Cnt_M_u16	36464
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3337339648
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1777091328
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	4223562496
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	223621888
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	32217
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	265351936
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	30338
CAVNodeAbsentTimer_mS_M_u32	1399595776
CDD_SrlComVehSpd_Kph_G_f32	206.274399
CMM388NTCEnableTimer_mS_M_u32	3232588544
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3946455808
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	58079
CMMNodeAbsentTimer_mS_M_u32	2919641856
CONSANGLECPKSigInvalidCount_Cnt_M_u16	37085
CONSANGLECPKSigValidCount_Cnt_M_u16	13086
CONSANGLECPK_Cnt_M_u16	31877
CONSANGLECPK_HwDeg_M_f32	-7.08900023
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	31877
CPKVehicleSpeedMsgTimer_mS_M_u32	397562624
CPKVehicleSpeedValidCount_Cnt_M_u16	11172
CityParkInputConsistentCount_Cnt_M_u16	7332
CityParkInputInvalidCount_Cnt_M_u16	33050
CityParkInputMsgTimer_mS_M_u32	2065473536
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1524957952
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	55571

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3888554752
ComputerRazGCTSigValidCount_Cnt_M_u16	44029
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	32486
DMDFCTCPKSigValidCount_Cnt_M_u16	62239
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	59136
DMDRELAXECPKSigValidCount_Cnt_M_u16	39217
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	27422
DateInvalidTimer_mS_M_u32	1777091328
DiagMuxOnAbsentTimer_mS_M_u32	3137606400
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	223621888
ESPNTCEnableTimer_mS_M_u32	1457914624
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	31036
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	80
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	105
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2680877824
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	51833
EtatMTSigValidCount_Cnt_M_u16	27654
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	10487
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	35512
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	36077
ISDAT4V2BSI552MsgTimer_mS_M_u32	2285515520
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	58366
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	14707
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	27654
ISDATBSI3F2MsgTimer_mS_M_u32	451547904
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	58193
ISDATBSI412MsgLenValidCount_Cnt_M_u16	52406
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	51833
ISDATBSI412MsgTimer_mS_M_u32	302863104
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	48147
ISDATBSI432MsgLenValidCount_Cnt_M_u16	37232
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	36695
ISDATDIRASentFltAcc_Cnt_M_u16	32475
ISDATDIRASentTimer_mS_M_u32	397562624
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	7403
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	36464
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	10073
ISDYN2CMMMsgTimer_mS_M_u32	1310196480
ISDYNAASChkSumInvalidCount_Cnt_M_u16	33529
ISDYNAASChkSumValidCount_Cnt_M_u16	50507
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	62691
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	61737
ISDYNAASMsgLenValidCount_Cnt_M_u16	19795
ISDYNAASMsgTimeValidCount_Cnt_M_u16	33529
ISDYNAASMsgTimer_mS_M_u32	3346621184
ISDYNABRChkSumInvalidCount_Cnt_M_u16	7827
ISDYNABRChkSumValidCount_Cnt_M_u16	37676
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	7660
ISDYNABRMsgCountValidCount_Cnt_M_u16	49278
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	35536
ISDYNABRMsgLenValidCount_Cnt_M_u16	52561
ISDYNABRMsgTimeValidCount_Cnt_M_u16	31877
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	56953
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	48367
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	27654
ISDYNCMM208MsgTimer_mS_M_u32	4294967295
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	56953
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	48367
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	57174

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	4241679104
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	2243
ISDYNVOLChkSumValidCount_Cnt_M_u16	60292
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	38348
ISDYNVOLMsgCountValidCount_Cnt_M_u16	35461
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	47433
ISDYNVOLMsgLenValidCount_Cnt_M_u16	27626
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	58079
ISDYNVOLMsgTimer_mS_M_u32	2324865792
IgnOnTimer_mS_M_u32	3993428736
IgnTimeOff_Sec_M_u32	2463744163
ManVehSpd_Kph_M_f32	495.082489
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	155
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	46
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3625456384
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	209
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1192325888
PrevISDATBSI412MsgDLCError_Cnt_M_u08	207
PrevISDATBSI412MsgRxTime_MSec_M_u32	3523289856
PrevISDATBSI432MsgDLCError_Cnt_M_u08	155
PrevISDATBSI432MsgRxTime_MSec_M_u32	1951007488
PrevISDATDIRAMsgTxTime_MSec_M_u32	478487296
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	98
PrevISDYN2CMMMsgRxTime_MSec_M_u32	679981824
PrevISDYNAASMsgDLCError_Cnt_M_u08	165
PrevISDYNAASMsgRxTime_MSec_M_u32	318284544
PrevISDYNABRMsgDLCError_Cnt_M_u08	187
PrevISDYNABRMsgRxTime_MSec_M_u32	1788797696
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	67
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2400297728
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	6
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3736142592
PrevISDYNVOLMsgDLCError_Cnt_M_u08	193
PrevISDYNVOLMsgRxTime_MSec_M_u32	1607607040
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2666746624
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	115.704102
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	50703
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	8889
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	39324
VitesseVehicleBVRampValidCount_Cnt_M_u16	30214
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	16371
VitesseVehicleBVSigValidCount_Cnt_M_u16	53860
VitesseVehicleBV_Kph_M_f32	434.627808
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	57174
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	7135
VitesseVehiculeRoues_Kph_M_f32	48.7103004
k_AASNTCEnableTimeout_mS_u16	11088
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	38319
k_AASNodeTimeout_mS_u16	16825
k_ABSNodeTimeout_mS_u16	17983
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	54674
k_ANGLEVOLANTSigValidThresh_Cnt_u16	7215
k_AngleVolantInvalidThresh_Cnt_u16	46474
k_AngleVolantValidThresh_Cnt_u16	33050
k_BSI552MsgTimeout_mS_u16	34042
k_BSINTCEnableTimeout_mS_u16	26795
k_BSINodeAbsentDiag_Cnt_str.Threshold	41825
k_BSINodeAbsentDiag_Cnt_str.PStep	9559
k_BSINodeAbsentDiag_Cnt_str.NStep	51425
k_BSINodeAbsentTimeout_mS_u16	4280
k_BSINodeTimeout_mS_u16	36695
k_BattOvHi_Volt_f32	9.69519997
k_BattOvLo_Volt_f32	30.8013992
k_BattUvHi_Volt_f32	2.88030005
k_BattUvLo_Volt_f32	2.82730007
k_CAVNTCEnableTimeout_mS_u16	53912
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	17000
k_CAVNodeTimeout_mS_u16	61353
k_CMM388MsgTimeout_mS_u16	39903
k_CMM388NTCEnableTimeout_mS_u16	16299
k_CMMNTCEnableTimeout_mS_u16	40086
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	3499
k_CONSANGLECPKMax_HwDeg_f32	171.5448
k_CONSANGLECPKMin_HwDeg_f32	-312.324585
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	48726
k_CONSANGLECPKSigValidThresh_Cnt_u16	15071
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	53895
k_CPKVehicleSpeedValidThresh_Cnt_u16	65208
k_CityParkInputInvalidThresh_Cnt_u16	38369
k_CityParkInputValidThresh_Cnt_u16	7332
k_ComputerRazGCTSigValidThresh_Cnt_u16	28076
k_CptTemporelSigValidThresh_Cnt_u16	18849
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	59856
k_DMDFCTCPKSigValidThresh_Cnt_u16	27729
k_DMDFCTCPKValidCount_Cnt_u16	58945
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	10073
k_DMDRELAXECPKSigValidThresh_Cnt_u16	7122
k_DMDRelaxeConsistentThresh_Cnt_u16	32416
k_DateValidThresh_Cnt_u16	36077
k_DefaultVehSpd_Kph_f32	2.89429998
k_DiagMuxOnAbsentTimeout_mS_u16	56707
k_EMNodeTimeout_mS_u16	6142
k_ESPNTCEnableTimeout_mS_u16	16206
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	35091
k_EtatMTSigInvalidThresh_Cnt_u16	16206
k_EtatMTSigValidThresh_Cnt_u16	23079
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	50510
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	62779
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	18993
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	35551
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	63252
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	47749
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	43636
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	13969
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	54599
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	153
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	30878
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	46617
k_ISDATDIRASentDiag_Cnt_str.Threshold	35205

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	52390
k_ISDATDIRASentDiag_Cnt_str.NStep	30922
k_ISDATDIRASentTimeout_mS_u16	21343
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	60338
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	51744
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	25322
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	64915
k_ISDYNAASChkSumValidThresh_Cnt_u16	45612
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	31980
k_ISDYNAASMsgCountValidThresh_Cnt_u16	24446
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	2247
k_ISDYNAASMsgLenValidThresh_Cnt_u16	34797
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	3479
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	27062
k_ISDYNABRChkSumValidThresh_Cnt_u16	11447
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	56537
k_ISDYNABRMsgCountValidThresh_Cnt_u16	28618
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	479
k_ISDYNABRMsgLenValidThresh_Cnt_u16	55356
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	56421
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	11331
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	4894
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	15828
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	31718
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	11927
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	39858
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	20304
k_ISDYNVOLChkSumValidThresh_Cnt_u16	35317
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	57725
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	31840
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	40005
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	16082
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	20715
k_IgnOnTimeout_mS_u16	2076
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	182.043304
k_PowerCutVehSpdLowThresh_Kph_f32	126.144798
k_PowerCutVehSpdLowTimeout_mS_u16	32460
k_VBattMaxAAS_Volt_f32	1.87989998
k_VBattMaxBSI_Volt_f32	0.00430000015
k_VBattMaxCAV_Volt_f32	1.07249999
k_VBattMaxCMM388_Volt_f32	0.449699998
k_VBattMaxCMM_Volt_f32	23.2089996
k_VBattMaxESP_Volt_f32	12.0165005
k_VBattMinAAS_Volt_f32	18.0944996
k_VBattMinBSI_Volt_f32	12.0165005
k_VBattMinCAV_Volt_f32	17.4743996
k_VBattMinCMM388_Volt_f32	31.3012009
k_VBattMinCMM_Volt_f32	5.41650009
k_VBattMinESP_Volt_f32	23.2089996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	57828
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	41081
k_VitesseVehicleBVRampValidThresh_Cnt_u16	29900
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	35460
k_VitesseVehicleBVSigValidThresh_Cnt_u16	11465
k_VitesseVehicleBVSpeedPassThresh_kph_f32	306.036407
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	21890
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	29292
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1777091328
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	15663
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2773426688
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	6
target_SrlComInput_Per1_Batt_Volt_f32.value	20.1576004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1602614016
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	24
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.35280773
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	199
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	214491904
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	139
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2841281280
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	10
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2482774784
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4105028352
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4084163328
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	114
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3091268352
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1797432064
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	46
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	48
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	68
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	137
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	161
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	188
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3977954048
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	77
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	151
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	222
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	466608896
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2044822272
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	163
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3858965248
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	37
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	85
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	130
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	156
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	174
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2541449984
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3679
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.810901344
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	460019
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	33.918499
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	33729

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2773426688	2773426688	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2773426688	2773426688	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	41825	41825	✔
BSINodeAbsentTimer_mS_M_u32	2773426688	2773426688	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2773426688	2773426688	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2773426688	2773426688	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	31877	31877	✔
CONSANGLECPK_HwDeg_M_f32	-7.08900023	-7.08900023 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2773426688	2773426688	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2773426688	2773426688	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2773426688	2773426688	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2773426688	2773426688	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2773426688	2773426688	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2773426688	2773426688	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2773426688	2773426688	✔
ESPNTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2773426688	2773426688	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	80	80	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2773426688	2773426688	✔
ElecIntTimer_mS_M_u32[1]	105	105	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2773426688	2773426688	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2773426688	2773426688	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2773426688	2773426688	✔
IgnOnTimer_mS_M_u32	2773426688	2773426688	✔
IgnTimeOff_Sec_M_u32	2463744163	2463744163	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	199	199	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	214491904	214491904	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	139	139	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2841281280	2841281280	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	10	10	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2482774784	2482774784	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	107	107	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4105028352	4105028352	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	478487296	478487296	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	114	114	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3091268352	3091268352	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	105	105	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1797432064	1797432064	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3977954048	3977954048	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	221	221	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	466608896	466608896	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	131	131	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2044822272	2044822272	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	163	163	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3858965248	3858965248	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2541449984	2541449984	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	115.704102	115.704102	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	434.627808	434.627808	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	48.7103004	48.7103004	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	31877	31877	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2463744163	2463744163	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-7.08900023	-7.08900023 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.280 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1614072320
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	2059
AASNodeAbsentTimer_mS_M_u32	5749248
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	41463
ANGLEVOLANTSigValidCount_Cnt_M_u16	51876
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	42056
AngleVolantMsgTimer_mS_M_u32	1614072320
AngleVolantValidCount_Cnt_M_u16	40409
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3316087296
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2124806656
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	233794048
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1613638144
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	2846
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1001908736
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	20385
CAVNodeAbsentTimer_mS_M_u32	430332416
CDD_SrlComVehSpd_Kph_G_f32	585.963379
CMM388NTCEnableTimer_mS_M_u32	1726126592
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	171727360
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	18508
CMMNodeAbsentTimer_mS_M_u32	3323472384
CONSANGLECPKSigInvalidCount_Cnt_M_u16	37139
CONSANGLECPKSigValidCount_Cnt_M_u16	27407
CONSANGLECPK_Cnt_M_u16	60122
CONSANGLECPK_HwDeg_M_f32	-19.9223003
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	60122
CPKVehicleSpeedMsgTimer_mS_M_u32	3784559104
CPKVehicleSpeedValidCount_Cnt_M_u16	46596

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	49981
CityParkInputInvalidCount_Cnt_M_u16	16090
CityParkInputMsgTimer_mS_M_u32	214491904
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2126232064
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	879
ComputerRazGCTSigInvalidTimer_mS_M_u32	3868645888
ComputerRazGCTSigValidCount_Cnt_M_u16	47410
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	30070
DMDFCTCPKSigValidCount_Cnt_M_u16	47499
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	11177
DMDRELAXECPKSigValidCount_Cnt_M_u16	38358
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	18000
DateInvalidTimer_mS_M_u32	2124806656
DiagMuxOnAbsentTimer_mS_M_u32	1855883776
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1613638144
ESPNTCEnableTimer_mS_M_u32	3468212736
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	46581
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	150
EffacDefaultDiagTimer_mS_M_u32[1]	1150
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	660
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4090096128
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	51837
EtatMTSigValidCount_Cnt_M_u16	54934
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	45253
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	19521
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	42017
ISDAT4V2BSI552MsgTimer_mS_M_u32	125577728
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	10607
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	47567
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	54934
ISDATBSI3F2MsgTimer_mS_M_u32	1726777856
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	34933
ISDATBSI412MsgLenValidCount_Cnt_M_u16	7429
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	51837
ISDATBSI412MsgTimer_mS_M_u32	511887872
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	36016
ISDATBSI432MsgLenValidCount_Cnt_M_u16	15705
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	39202
ISDATDIRASentFltAcc_Cnt_M_u16	55958
ISDATDIRASentTimer_mS_M_u32	3784559104
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	8616
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	40409
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	2077
ISDYN2CMMMsgTimer_mS_M_u32	824359424
ISDYNAASChkSumInvalidCount_Cnt_M_u16	7613
ISDYNAASChkSumValidCount_Cnt_M_u16	22409
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	63104
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	15276
ISDYNAASMsgLenValidCount_Cnt_M_u16	34801
ISDYNAASMsgTimeValidCount_Cnt_M_u16	7613
ISDYNAASMsgTimer_mS_M_u32	2189335040
ISDYNABRChkSumInvalidCount_Cnt_M_u16	59505
ISDYNABRChkSumValidCount_Cnt_M_u16	43877
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	55524
ISDYNABRMsgCountValidCount_Cnt_M_u16	61936
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	12090
ISDYNABRMsgLenValidCount_Cnt_M_u16	10358
ISDYNABRMsgTimeValidCount_Cnt_M_u16	60122

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	62113
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	56063
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	54934
ISDYNCMM208MsgTimer_mS_M_u32	313195776
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	62113
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	56063
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	49959
ISDYNCMM388MsgTimer_mS_M_u32	678566400
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	16737
ISDYNVOLChkSumValidCount_Cnt_M_u16	23005
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	18628
ISDYNVOLMsgCountValidCount_Cnt_M_u16	2905
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	27086
ISDYNVOLMsgLenValidCount_Cnt_M_u16	37546
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	18508
ISDYNVOLMsgTimer_mS_M_u32	775084544
IgnOnTimer_mS_M_u32	618011136
IgnTimeOff_Sec_M_u32	2900328097
ManVehSpd_Kph_M_f32	341.908386
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	156
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	106
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1734511104
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	85
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	938895872
PrevISDATBSI412MsgDLCError_Cnt_M_u08	136
PrevISDATBSI412MsgRxTime_MSec_M_u32	837245440
PrevISDATBSI432MsgDLCError_Cnt_M_u08	144
PrevISDATBSI432MsgRxTime_MSec_M_u32	109885952
PrevISDATDIRAMsgTxTime_MSec_M_u32	1650153984
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	11
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1016310272
PrevISDYNAASMsgDLCError_Cnt_M_u08	55
PrevISDYNAASMsgRxTime_MSec_M_u32	2902514176
PrevISDYNABRMsgDLCError_Cnt_M_u08	5
PrevISDYNABRMsgRxTime_MSec_M_u32	252582400
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	140
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3702905344
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	17
PrevISDYNCMM388MsgRxTime_MSec_M_u32	592951808
PrevISDYNVOLMsgDLCError_Cnt_M_u08	203
PrevISDYNVOLMsgRxTime_MSec_M_u32	208951808
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2412825088
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	411.567993
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	54522
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	8127
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	52819
VitesseVehicleBVRampValidCount_Cnt_M_u16	39384
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	44240

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	30269
VitesseVehicleBV_Kph_M_f32	446.998413
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	49959
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	61003
VitesseVehiculeRoues_Kph_M_f32	126.704002
k_AASNTCEnableTimeout_mS_u16	51833
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	17436
k_AASNodeTimeout_mS_u16	49855
k_ABSNodeTimeout_mS_u16	50027
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	64563
k_ANGLEVOLANTSigValidThresh_Cnt_u16	22812
k_AngleVolantInvalidThresh_Cnt_u16	47371
k_AngleVolantValidThresh_Cnt_u16	16090
k_BSI552MsgTimeout_mS_u16	57082
k_BSINTCEnableTimeout_mS_u16	59112
k_BSINodeAbsentDiag_Cnt_str.Threshold	39785
k_BSINodeAbsentDiag_Cnt_str.PStep	16839
k_BSINodeAbsentDiag_Cnt_str.NStep	54121
k_BSINodeAbsentTimeout_mS_u16	12416
k_BSINodeTimeout_mS_u16	39202
k_BattOvHi_Volt_f32	25.3666
k_BattOvLo_Volt_f32	20.6686993
k_BattUvHi_Volt_f32	7.02740002
k_BattUvLo_Volt_f32	9.31280041
k_CAVNTCEnableTimeout_mS_u16	49760
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	1007
k_CAVNodeTimeout_mS_u16	42159
k_CMM388MsgTimeout_mS_u16	60171
k_CMM388NTCEnableTimeout_mS_u16	12199
k_CMMNTCEnableTimeout_mS_u16	24487
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	18663
k_CONSANGLECPKMax_HwDeg_f32	201.283493
k_CONSANGLECPKMin_HwDeg_f32	-683.82019
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	9767
k_CONSANGLECPKSigValidThresh_Cnt_u16	37195
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	51285
k_CPKVehicleSpeedValidThresh_Cnt_u16	37440
k_CityParkInputInvalidThresh_Cnt_u16	14983
k_CityParkInputValidThresh_Cnt_u16	49981
k_ComputerRazGCTSigValidThresh_Cnt_u16	50277
k_CptTemporelSigValidThresh_Cnt_u16	49477
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	4666
k_DMDFCTCPKSigValidThresh_Cnt_u16	19318
k_DMDFCTCPKValidCount_Cnt_u16	29158
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	2077
k_DMDRELAXECPKSigValidThresh_Cnt_u16	52082
k_DMDRelaxeConsistentThresh_Cnt_u16	23304
k_DateValidThresh_Cnt_u16	42017
k_DefaultVehSpd_Kph_f32	178.483994
k_DiagMuxOnAbsentTimeout_mS_u16	16352
k_EMNodeTimeout_mS_u16	49072
k_ESPNTCEnableTimeout_mS_u16	9533
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	30383
k_EtatMTSigInvalidThresh_Cnt_u16	12864
k_EtatMTSigValidThresh_Cnt_u16	628
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	52224
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	44280
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	44694
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	63692
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	17644
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	53977

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	34189
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	4598
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	4372
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	44702
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	5967
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	15647
k_ISDATDIRASentDiag_Cnt_str.Threshold	62208
k_ISDATDIRASentDiag_Cnt_str.PStep	30559
k_ISDATDIRASentDiag_Cnt_str.NStep	53426
k_ISDATDIRASentTimeout_mS_u16	31245
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	16468
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	42056
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10857
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	19313
k_ISDYNAASChkSumValidThresh_Cnt_u16	20069
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	48100
k_ISDYNAASMsgCountValidThresh_Cnt_u16	5360
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	63957
k_ISDYNAASMsgLenValidThresh_Cnt_u16	49187
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	9444
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	43656
k_ISDYNABRChkSumValidThresh_Cnt_u16	8772
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	60958
k_ISDYNABRMsgCountValidThresh_Cnt_u16	46603
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	60236
k_ISDYNABRMsgLenValidThresh_Cnt_u16	39157
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	39994
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	29278
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	27918
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	64110
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	34039
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	60836
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	20242
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	120
k_ISDYNVOLChkSumValidThresh_Cnt_u16	41288
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	49458
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	49097
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	34073
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	36402
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	53287
k_IgnOnTimeout_mS_u16	1556
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	89.5373001
k_PowerCutVehSpdLowThresh_Kph_f32	233.232605
k_PowerCutVehSpdLowTimeout_mS_u16	49157
k_VBattMaxAAS_Volt_f32	31.1200008
k_VBattMaxBSI_Volt_f32	10.5143995
k_VBattMaxCAV_Volt_f32	25.0023003
k_VBattMaxCMM388_Volt_f32	29.5133991
k_VBattMaxCMM_Volt_f32	21.9179001
k_VBattMaxESP_Volt_f32	5.70529985
k_VBattMinAAS_Volt_f32	11.4478998
k_VBattMinBSI_Volt_f32	5.70529985
k_VBattMinCAV_Volt_f32	31.5807991
k_VBattMinCMM388_Volt_f32	5.11810017
k_VBattMinCMM_Volt_f32	30.0170994
k_VBattMinESP_Volt_f32	21.9179001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	42430
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	31423
k_VitesseVehicleBVRampValidThresh_Cnt_u16	43972
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	31965
k_VitesseVehicleBVSigValidThresh_Cnt_u16	26318
k_VitesseVehicleBVSpeedPassThresh_kph_f32	310.392609
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	45729
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	48294
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2124806656
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14703
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1924750592
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	17
target_SrlComInput_Per1_Batt_Volt_f32.value	15.7981997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1620634112
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	227
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.234137774
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1351621120
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	50
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1230715392
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	165
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2549504512
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	177
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3294722560
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1453103616
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	184
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3601316352
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3431127552
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	209
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3474618880
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	43
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	194
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4286257664
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3016112640
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2111920640
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	71
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1857579520
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	334
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.673732102
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	775221
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	106.161499
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	58340

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1924750592	1924750592	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	42058	42058	✔
AngleVolantMsgTimer_mS_M_u32	1924750592	1924750592	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	39785	39785	✔
BSINodeAbsentTimer_mS_M_u32	1924750592	1924750592	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1924750592	1924750592	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1924750592	1924750592	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	60122	60122	✔
CONSANGLECPK_HwDeg_M_f32	-19.9223003	-19.9223003 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	60122	60122	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3784559104	3784559104	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	46596	46596	✔
CityParkInputConsistentCount_Cnt_M_u16	49981	49981	✔
CityParkInputInvalidCount_Cnt_M_u16	16090	16090	✔
CityParkInputMsgTimer_mS_M_u32	1924750592	1924750592	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1924750592	1924750592	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1924750592	1924750592	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1924750592	1924750592	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1924750592	1924750592	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1924750592	1924750592	✔
ESPNTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1924750592	1924750592	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	150	150	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1150	1150	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	65	65	✔
ElecIntTimer_mS_M_u32[1]	660	660	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1924750592	1924750592	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1924750592	1924750592	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1924750592	1924750592	✔
IgnOnTimer_mS_M_u32	1924750592	1924750592	✔
IgnTimeOff_Sec_M_u32	2900328097	2900328097	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1351621120	1351621120	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	50	50	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1230715392	1230715392	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	165	165	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2549504512	2549504512	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	177	177	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3294722560	3294722560	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1650153984	1650153984	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	184	184	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3601316352	3601316352	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	194	194	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3431127552	3431127552	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	133	133	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3474618880	3474618880	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	107	107	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4286257664	4286257664	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	39	39	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3016112640	3016112640	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	181	181	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2111920640	2111920640	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1857579520	1857579520	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	411.567993	411.567993	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	446.998413	446.998413	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	126.704002	126.704002	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	60122	60122	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2900328097	2900328097	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-19.9223003	-19.9223003 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	178.483994	178.483994	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.281 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1252549888
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	52516
AASNodeAbsentTimer_mS_M_u32	3791623424
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	20831
ANGLEVOLANTSigValidCount_Cnt_M_u16	21786
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	11373
AngleVolantMsgTimer_mS_M_u32	1252549888
AngleVolantValidCount_Cnt_M_u16	27706
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2165331200
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1880413440
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	4093150464
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1748780288
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	29162
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	748619008
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	6369
CAVNodeAbsentTimer_mS_M_u32	2559816960
CDD_SrlComVehSpd_Kph_G_f32	620.127991
CMM388NTCEnableTimer_mS_M_u32	4057920768
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2664543488
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	30112
CMMNodeAbsentTimer_mS_M_u32	1585333504
CONSANGLECPKSigInvalidCount_Cnt_M_u16	41740
CONSANGLECPKSigValidCount_Cnt_M_u16	53974
CONSANGLECPK_Cnt_M_u16	16245
CONSANGLECPK_HwDeg_M_f32	394.250397
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	16245
CPKVehicleSpeedMsgTimer_mS_M_u32	42689792
CPKVehicleSpeedValidCount_Cnt_M_u16	29793
CityParkInputConsistentCount_Cnt_M_u16	35854
CityParkInputInvalidCount_Cnt_M_u16	7734

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	1351621120
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4141061376
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	27384
ComputerRazGCTSigInvalidTimer_mS_M_u32	2478978304
ComputerRazGCTSigValidCount_Cnt_M_u16	48687
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	60002
DMDFCTCPKSigValidCount_Cnt_M_u16	15333
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	64585
DMDRELAXECPKSigValidCount_Cnt_M_u16	15236
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	46933
DateInvalidTimer_mS_M_u32	1880413440
DiagMuxOnAbsentTimer_mS_M_u32	4134216960
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1748780288
ESPNTCEnableTimer_mS_M_u32	987534592
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	39527
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	64
EffacDefaultDiagTimer_mS_M_u32[1]	894
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1100
ElecIntTimer_mS_M_u32[1]	1150
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3429434624
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	17421
EtatMTSigValidCount_Cnt_M_u16	19843
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	35830
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	30528
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	21539
ISDAT4V2BSI552MsgTimer_mS_M_u32	710034688
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	9401
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	49495
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	19843
ISDATBSI3F2MsgTimer_mS_M_u32	3313575168
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	61606
ISDATBSI412MsgLenValidCount_Cnt_M_u16	16565
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	17421
ISDATBSI412MsgTimer_mS_M_u32	3351143680
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	14452
ISDATBSI432MsgLenValidCount_Cnt_M_u16	37947
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	32862
ISDATDIRASentFltAcc_Cnt_M_u16	35842
ISDATDIRASentTimer_mS_M_u32	42689792
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	21259
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	27706
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36461
ISDYN2CMMMsgTimer_mS_M_u32	1000248576
ISDYNAASChkSumInvalidCount_Cnt_M_u16	54286
ISDYNAASChkSumValidCount_Cnt_M_u16	9321
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	48709
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	16576
ISDYNAASMsgLenValidCount_Cnt_M_u16	14770
ISDYNAASMsgTimeValidCount_Cnt_M_u16	54286
ISDYNAASMsgTimer_mS_M_u32	252376320
ISDYNABRChkSumInvalidCount_Cnt_M_u16	39795
ISDYNABRChkSumValidCount_Cnt_M_u16	61525
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	65177
ISDYNABRMsgCountValidCount_Cnt_M_u16	45364
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	9367
ISDYNABRMsgLenValidCount_Cnt_M_u16	63137
ISDYNABRMsgTimeValidCount_Cnt_M_u16	16245
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	12087
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	60124

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0
ISDYNCMM208MsgTimer_mS_M_u32	2658227456
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	12087
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	60124
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	46160
ISDYNCMM388MsgTimer_mS_M_u32	1261466880
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	18978
ISDYNVOLChkSumValidCount_Cnt_M_u16	48748
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	10360
ISDYNVOLMsgCountValidCount_Cnt_M_u16	65147
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	8924
ISDYNVOLMsgLenValidCount_Cnt_M_u16	58887
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	30112
ISDYNVOLMsgTimer_mS_M_u32	753808640
IgnOnTimer_mS_M_u32	3859051776
IgnTimeOff_Sec_M_u32	2245138850
ManVehSpd_Kph_M_f32	141.525299
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	157
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	471803136
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	192
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1373865216
PrevISDATBSI412MsgDLCError_Cnt_M_u08	163
PrevISDATBSI412MsgRxTime_MSec_M_u32	2479928576
PrevISDATBSI432MsgDLCError_Cnt_M_u08	74
PrevISDATBSI432MsgRxTime_MSec_M_u32	3814757632
PrevISDATDIRAMsgTxTime_MSec_M_u32	3530863872
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	98
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1225508096
PrevISDYNAASMsgDLCError_Cnt_M_u08	3
PrevISDYNAASMsgRxTime_MSec_M_u32	1753494784
PrevISDYNABRMsgDLCError_Cnt_M_u08	108
PrevISDYNABRMsgRxTime_MSec_M_u32	123499776
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	119
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3982832896
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	128
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2030015744
PrevISDYNVOLMsgDLCError_Cnt_M_u08	141
PrevISDYNVOLMsgRxTime_MSec_M_u32	2015999232
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	735339776
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	512.612488
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	11478
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	10824
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	58571
VitesseVehicleBVRampValidCount_Cnt_M_u16	24573
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	54484
VitesseVehicleBVSigValidCount_Cnt_M_u16	63055
VitesseVehicleBV_Kph_M_f32	55.0768013

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	46160
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	37027
VitesseVehiculeRoues_Kph_M_f32	199.380997
k_AASNTCEnableTimeout_mS_u16	56472
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	17777
k_AASNodeTimeout_mS_u16	16712
k_ABSNodeTimeout_mS_u16	5251
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	46571
k_ANGLEVOLANTSigValidThresh_Cnt_u16	3314
k_AngleVolantInvalidThresh_Cnt_u16	26917
k_AngleVolantValidThresh_Cnt_u16	7734
k_BSI552MsgTimeout_mS_u16	14998
k_BSINTCEnableTimeout_mS_u16	2508
k_BSINodeAbsentDiag_Cnt_str.Threshold	20062
k_BSINodeAbsentDiag_Cnt_str.PStep	54916
k_BSINodeAbsentDiag_Cnt_str.NStep	44255
k_BSINodeAbsentTimeout_mS_u16	26565
k_BSINodeTimeout_mS_u16	32862
k_BattOvHi_Volt_f32	24.7677002
k_BattOvLo_Volt_f32	25.4997005
k_BattUvHi_Volt_f32	1.13789999
k_BattUvLo_Volt_f32	20.4023991
k_CAVNTCEnableTimeout_mS_u16	11172
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	46071
k_CAVNodeTimeout_mS_u16	55352
k_CMM388MsgTimeout_mS_u16	9252
k_CMM388NTCEnableTimeout_mS_u16	50768
k_CMMNTCEnableTimeout_mS_u16	25105
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	61647
k_CONSANGLECPKMax_HwDeg_f32	473.918488
k_CONSANGLECPKMin_HwDeg_f32	-778.634521
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	35664
k_CONSANGLECPKSigValidThresh_Cnt_u16	42915
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	2182
k_CPKVehicleSpeedValidThresh_Cnt_u16	48965
k_CityParkInputInvalidThresh_Cnt_u16	32049
k_CityParkInputValidThresh_Cnt_u16	35854
k_ComputerRazGCTSigValidThresh_Cnt_u16	43991
k_CptTemporelSigValidThresh_Cnt_u16	757
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	31639
k_DMDFCTCPKSigValidThresh_Cnt_u16	36257
k_DMDFCTCPKValidCount_Cnt_u16	23954
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	36461
k_DMDRELAXECPKSigValidThresh_Cnt_u16	25136
k_DMDRelaxeConsistentThresh_Cnt_u16	35694
k_DateValidThresh_Cnt_u16	21539
k_DefaultVehSpd_Kph_f32	216.324295
k_DiagMuxOnAbsentTimeout_mS_u16	55395
k_EMNodeTimeout_mS_u16	52021
k_ESPNTCEnableTimeout_mS_u16	2061
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	34679
k_EtatMTSigInvalidThresh_Cnt_u16	47622
k_EtatMTSigValidThresh_Cnt_u16	59176
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	27013
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	29788
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	28163
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	27298
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	54272
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	41338
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	477
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	51812

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	15176
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	1065
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	22488
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	19367
k_ISDATDIRASentDiag_Cnt_str.Threshold	52471
k_ISDATDIRASentDiag_Cnt_str.PStep	60363
k_ISDATDIRASentDiag_Cnt_str.NStep	42803
k_ISDATDIRASentTimeout_mS_u16	22175
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	22024
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	11373
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	43145
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	29299
k_ISDYNAASChkSumValidThresh_Cnt_u16	1877
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	21913
k_ISDYNAASMsgCountValidThresh_Cnt_u16	18484
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	63303
k_ISDYNAASMsgLenValidThresh_Cnt_u16	55580
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	51610
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	27309
k_ISDYNABRChkSumValidThresh_Cnt_u16	49463
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	51434
k_ISDYNABRMsgCountValidThresh_Cnt_u16	61157
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	36000
k_ISDYNABRMsgLenValidThresh_Cnt_u16	61799
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	47192
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	58538
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	59099
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	5691
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	43103
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	60442
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	52622
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	21661
k_ISDYNVOLChkSumValidThresh_Cnt_u16	32748
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	44208
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	17193
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	33849
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	38575
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	26641
k_IgnOnTimeout_mS_u16	46025
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	161.664597
k_PowerCutVehSpdLowThresh_Kph_f32	58.578701
k_PowerCutVehSpdLowTimeout_mS_u16	11252
k_VBattMaxAAS_Volt_f32	31.6502991
k_VBattMaxBSI_Volt_f32	7.16419983
k_VBattMaxCAV_Volt_f32	9.62339973
k_VBattMaxCMM388_Volt_f32	21.1625996
k_VBattMaxCMM_Volt_f32	26.9009991
k_VBattMaxESP_Volt_f32	26.9090004
k_VBattMinAAS_Volt_f32	3.75149989
k_VBattMinBSI_Volt_f32	26.9090004
k_VBattMinCAV_Volt_f32	20.5354004
k_VBattMinCMM388_Volt_f32	21.8708992
k_VBattMinCMM_Volt_f32	6.43849993
k_VBattMinESP_Volt_f32	26.9009991
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	19914
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	40073
k_VitesseVehicleBVRampValidThresh_Cnt_u16	65400
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	21868
k_VitesseVehicleBVSigValidThresh_Cnt_u16	9563
k_VitesseVehicleBVSpeedPassThresh_kph_f32	63.0143013
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	61409
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	44947
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1880413440
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	61949
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2435230720
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	128

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	15.9525003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2180777216
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	234
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.590905845
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	52
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3403052288
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1962218752
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	226
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1571009792
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3974255872
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2326852864
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	199
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2668598528
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2449356032
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	37
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	63
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	86
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	93
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	164
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4038546688
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	139
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	140
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	188
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	196
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	213
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	706049280
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2712933632
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	400733440
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	74
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	122
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	133
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	899515648
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1647
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.268755317
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	118781
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	115.041801
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	10264

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2435230720	2435230720	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2435230720	2435230720	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	20062	20062	✔
BSINodeAbsentTimer_mS_M_u32	2435230720	2435230720	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2435230720	2435230720	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2435230720	2435230720	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	16245	16245	✔
CONSANGLECPK_HwDeg_M_f32	394.250397	394.250397 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2435230720	2435230720	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2435230720	2435230720	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2435230720	2435230720	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2435230720	2435230720	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2435230720	2435230720	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2435230720	2435230720	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2435230720	2435230720	✔
ESPNTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2435230720	2435230720	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	64	64	✔
EffacDefaultDiagTimer_mS_M_u32[1]	894	894	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	1100	1100	✔
ElecIntTimer_mS_M_u32[1]	1150	1150	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2435230720	2435230720	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2435230720	2435230720	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2435230720	2435230720	✔
IgnOnTimer_mS_M_u32	3859051776	3859051776	✔
IgnTimeOff_Sec_M_u32	2245138850	2245138850	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	52	52	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3403052288	3403052288	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1962218752	1962218752	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	226	226	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1571009792	1571009792	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	49	49	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3974255872	3974255872	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3530863872	3530863872	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	199	199	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2668598528	2668598528	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	222	222	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2449356032	2449356032	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	219	219	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4038546688	4038546688	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	213	213	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	706049280	706049280	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2712933632	2712933632	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	30	30	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	400733440	400733440	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	899515648	899515648	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	512.612488	512.612488	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	55.0768013	55.0768013	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	199.380997	199.380997	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	16245	16245	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2245138850	2245138850	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	394.250397	394.250397 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.282 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1870238720
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	31236
AASNodeAbsentTimer_mS_M_u32	1110705152
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	63316
ANGLEVOLANTSigValidCount_Cnt_M_u16	29412
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	49193
AngleVolantMsgTimer_mS_M_u32	1870238720
AngleVolantValidCount_Cnt_M_u16	31555
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2550252544
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2096382976
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1544107008
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3191731200
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	33203
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1813361664
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	12111
CAVNodeAbsentTimer_mS_M_u32	385328128
CDD_SrlComVehSpd_Kph_G_f32	566.78772
CMM388NTCEnableTimer_mS_M_u32	1209394176
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2084414464
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	17615
CMMNodeAbsentTimer_mS_M_u32	1668805632
CONSANGLECPKSigInvalidCount_Cnt_M_u16	42318
CONSANGLECPKSigValidCount_Cnt_M_u16	56494
CONSANGLECPK_Cnt_M_u16	53969
CONSANGLECPK_HwDeg_M_f32	268.651398
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	53969
CPKVehicleSpeedMsgTimer_mS_M_u32	2479920128
CPKVehicleSpeedValidCount_Cnt_M_u16	4310

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	27591
CityParkInputInvalidCount_Cnt_M_u16	42574
CityParkInputMsgTimer_mS_M_u32	3403052288
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1404568576
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	61576
ComputerRazGCTSigInvalidTimer_mS_M_u32	4285277184
ComputerRazGCTSigValidCount_Cnt_M_u16	39268
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	61898
DMDFCTCPKSigValidCount_Cnt_M_u16	41986
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	7830
DMDRELAXECPKSigValidCount_Cnt_M_u16	59302
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	52339
DateInvalidTimer_mS_M_u32	2096382976
DiagMuxOnAbsentTimer_mS_M_u32	3878769664
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3191731200
ESPNTCEnableTimer_mS_M_u32	3952935936
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	36155
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1123
EffacDefaultDiagTimer_mS_M_u32[1]	5523
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2050
ElecIntTimer_mS_M_u32[1]	6070
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	884454400
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	55947
EtatMTSigValidCount_Cnt_M_u16	13543
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	4752
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	6000
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	54088
ISDAT4V2BSI552MsgTimer_mS_M_u32	1341912064
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	16391
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	33003
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13543
ISDATBSI3F2MsgTimer_mS_M_u32	1374639104
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	8511
ISDATBSI412MsgLenValidCount_Cnt_M_u16	2003
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	55947
ISDATBSI412MsgTimer_mS_M_u32	3493303296
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	19539
ISDATBSI432MsgLenValidCount_Cnt_M_u16	61375
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	11480
ISDATDIRASentFltAcc_Cnt_M_u16	39404
ISDATDIRASentTimer_mS_M_u32	2479920128
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	28687
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	31555
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	61865
ISDYN2CMMMsgTimer_mS_M_u32	1901528064
ISDYNAASChkSumInvalidCount_Cnt_M_u16	36166
ISDYNAASChkSumValidCount_Cnt_M_u16	41718
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	28962
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	62386
ISDYNAASMsgLenValidCount_Cnt_M_u16	28570
ISDYNAASMsgTimeValidCount_Cnt_M_u16	36166
ISDYNAASMsgTimer_mS_M_u32	2693915648
ISDYNABRChkSumInvalidCount_Cnt_M_u16	49304
ISDYNABRChkSumValidCount_Cnt_M_u16	59568
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	63909
ISDYNABRMsgCountValidCount_Cnt_M_u16	59541
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	3245
ISDYNABRMsgLenValidCount_Cnt_M_u16	23885
ISDYNABRMsgTimeValidCount_Cnt_M_u16	53969

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	15953
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	44320
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	65535
ISDYNCMM208MsgTimer_mS_M_u32	64930816
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	15953
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	44320
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	31489
ISDYNCMM388MsgTimer_mS_M_u32	1646355456
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	34828
ISDYNVOLChkSumValidCount_Cnt_M_u16	61932
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	3976
ISDYNVOLMsgCountValidCount_Cnt_M_u16	13376
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	2012
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1308
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	17615
ISDYNVOLMsgTimer_mS_M_u32	3823641600
IgnOnTimer_mS_M_u32	3785712640
IgnTimeOff_Sec_M_u32	455379924
ManVehSpd_Kph_M_f32	384.179413
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	158
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	198
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1175802880
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	15
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2923967488
PrevISDATBSI412MsgDLCError_Cnt_M_u08	236
PrevISDATBSI412MsgRxTime_MSec_M_u32	1497408512
PrevISDATBSI432MsgDLCError_Cnt_M_u08	192
PrevISDATBSI432MsgRxTime_MSec_M_u32	34669568
PrevISDATDIRAMsgTxTime_MSec_M_u32	760521728
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	218
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3117380608
PrevISDYNAASMsgDLCError_Cnt_M_u08	130
PrevISDYNAASMsgRxTime_MSec_M_u32	153494528
PrevISDYNABRMsgDLCError_Cnt_M_u08	213
PrevISDYNABRMsgRxTime_MSec_M_u32	3718079488
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	213
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1048781824
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	244
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2100560896
PrevISDYNVOLMsgDLCError_Cnt_M_u08	27
PrevISDYNVOLMsgRxTime_MSec_M_u32	1345692672
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2079691776
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	156.079498
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	1904
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	30168
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	62353
VitesseVehicleBVRampValidCount_Cnt_M_u16	59577
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	33013

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	41797
VitesseVehicleBV_Kph_M_f32	613.39978
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	31489
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	52425
VitesseVehiculeRoues_Kph_M_f32	4.86490011
k_AASNTCEnableTimeout_mS_u16	18280
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	35742
k_AASNodeTimeout_mS_u16	12504
k_ABSNodeTimeout_mS_u16	14183
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	28654
k_ANGLEVOLANTSigValidThresh_Cnt_u16	8602
k_AngleVolantInvalidThresh_Cnt_u16	39169
k_AngleVolantValidThresh_Cnt_u16	42574
k_BSI552MsgTimeout_mS_u16	23280
k_BSINTCEnableTimeout_mS_u16	14411
k_BSINodeAbsentDiag_Cnt_str.Threshold	37980
k_BSINodeAbsentDiag_Cnt_str.PStep	35368
k_BSINodeAbsentDiag_Cnt_str.NStep	25945
k_BSINodeAbsentTimeout_mS_u16	28193
k_BSINodeTimeout_mS_u16	11480
k_BattOvHi_Volt_f32	31.5
k_BattOvLo_Volt_f32	4.42700005
k_BattUvHi_Volt_f32	13.3692999
k_BattUvLo_Volt_f32	7.21400023
k_CAVNTCEnableTimeout_mS_u16	46596
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	13837
k_CAVNodeTimeout_mS_u16	46538
k_CMM388MsgTimeout_mS_u16	29956
k_CMM388NTCEnableTimeout_mS_u16	16000
k_CMMNTCEnableTimeout_mS_u16	59391
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	23621
k_CONSANGLECPKMax_HwDeg_f32	474.147186
k_CONSANGLECPKMin_HwDeg_f32	-429.600891
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	62977
k_CONSANGLECPKSigValidThresh_Cnt_u16	34761
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	21278
k_CPKVehicleSpeedValidThresh_Cnt_u16	61794
k_CityParkInputInvalidThresh_Cnt_u16	37726
k_CityParkInputValidThresh_Cnt_u16	27591
k_ComputerRazGCTSigValidThresh_Cnt_u16	41645
k_CptTemporelSigValidThresh_Cnt_u16	46097
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	1965
k_DMDFCTCPKSigValidThresh_Cnt_u16	38989
k_DMDFCTCPKValidCount_Cnt_u16	24251
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	61865
k_DMDRELAXECPKSigValidThresh_Cnt_u16	7457
k_DMDRelaxeConsistentThresh_Cnt_u16	6503
k_DateValidThresh_Cnt_u16	54088
k_DefaultVehSpd_Kph_f32	56.975399
k_DiagMuxOnAbsentTimeout_mS_u16	16391
k_EMNodeTimeout_mS_u16	4307
k_ESPNTCEnableTimeout_mS_u16	4555
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	14413
k_EtatMTSigInvalidThresh_Cnt_u16	28895
k_EtatMTSigValidThresh_Cnt_u16	4151
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	60449
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	49757
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	55784
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	21068
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	11504
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	24259

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	54296
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	12612
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	37847
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	21685
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	45161
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	42300
k_ISDATDIRASentDiag_Cnt_str.Threshold	3472
k_ISDATDIRASentDiag_Cnt_str.PStep	32212
k_ISDATDIRASentDiag_Cnt_str.NStep	26715
k_ISDATDIRASentTimeout_mS_u16	16148
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	18969
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	49193
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	8279
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	15256
k_ISDYNAASChkSumValidThresh_Cnt_u16	41904
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	62629
k_ISDYNAASMsgCountValidThresh_Cnt_u16	9109
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	64796
k_ISDYNAASMsgLenValidThresh_Cnt_u16	47452
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	35746
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	4715
k_ISDYNABRChkSumValidThresh_Cnt_u16	54667
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	31923
k_ISDYNABRMsgCountValidThresh_Cnt_u16	37251
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	65487
k_ISDYNABRMsgLenValidThresh_Cnt_u16	34875
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	49450
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	12276
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	21152
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	15871
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	62036
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	44516
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	63558
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	37210
k_ISDYNVOLChkSumValidThresh_Cnt_u16	58926
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	47712
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	16436
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	51719
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	2403
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	53118
k_IgnOnTimeout_mS_u16	9174
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	161.454407
k_PowerCutVehSpdLowThresh_Kph_f32	254.712204
k_PowerCutVehSpdLowTimeout_mS_u16	51540
k_VBattMaxAAS_Volt_f32	10.7455997
k_VBattMaxBSI_Volt_f32	13.1120996
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	22.1315994
k_VBattMaxCMM_Volt_f32	23.0597992
k_VBattMaxESP_Volt_f32	3.92540002
k_VBattMinAAS_Volt_f32	25.1870995
k_VBattMinBSI_Volt_f32	3.92540002
k_VBattMinCAV_Volt_f32	7.28739977
k_VBattMinCMM388_Volt_f32	6.43919992
k_VBattMinCMM_Volt_f32	6.94250011
k_VBattMinESP_Volt_f32	23.0597992
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	60115
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	38230
k_VitesseVehicleBVRampValidThresh_Cnt_u16	35464
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	11500
k_VitesseVehicleBVSigValidThresh_Cnt_u16	5088
k_VitesseVehicleBVSpeedPassThresh_kph_f32	482.547485
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	43599
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	53751
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2096382976
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	61551
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1373290240
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	244
target_SrlComInput_Per1_Batt_Volt_f32.value	4.26100016
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	536785920
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	15
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.731399834
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	244
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4214187008
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	161
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1062437888
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	130524160
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	36
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	478921728
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1168106496
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1258554368
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4105708544
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	102
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	153
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	223
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	187
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2769077248
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	69
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	93
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	164
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	173
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	205
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2574410752
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	179
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1964409856
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	120
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2500502528
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	107
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	122
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	202
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1796879360
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	108
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.533802688
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	260715
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	35.5727997
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	40362

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1373290240	1373290240	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1373290240	1373290240	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1373290240	1373290240	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1373290240	1373290240	✔
CDD_SrlComVehSpd_Kph_G_f32	384.179413	384.179413	✔
CMM388NTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1373290240	1373290240	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	53969	53969	✔
CONSANGLECPK_HwDeg_M_f32	268.651398	268.651398 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1373290240	1373290240	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1373290240	1373290240	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1373290240	1373290240	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1373290240	1373290240	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1373290240	1373290240	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1373290240	1373290240	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1373290240	1373290240	✔
ESPNTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1373290240	1373290240	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	1123	1123	✔
EffacDefaultDiagTimer_mS_M_u32[1]	5523	5523	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2050	2050	✔
ElecIntTimer_mS_M_u32[1]	6070	6070	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1373290240	1373290240	✔
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	54088	54088	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13543	13543	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	55947	55947	✔
ISDATBSI412MsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	11480	11480	✔
ISDATBSI432MsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1373290240	1373290240	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	61865	61865	✔
ISDYN2CMMMsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	36166	36166	✔
ISDYNAASMsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	53969	53969	✔
ISDYNABRMsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	65535	65535	✔
ISDYNCMM208MsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	31489	31489	✔
ISDYNCMM388MsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	17615	17615	✔
ISDYNVOLMsgTimer_mS_M_u32	1373290240	1373290240	✔
IgnOnTimer_mS_M_u32	3785712640	3785712640	✔
IgnTimeOff_Sec_M_u32	455379924	455379924	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	244	244	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4214187008	4214187008	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	161	161	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1062437888	1062437888	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	110	110	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	130524160	130524160	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	36	36	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	478921728	478921728	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	760521728	760521728	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	104	104	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1258554368	1258554368	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	134	134	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4105708544	4105708544	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	187	187	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2769077248	2769077248	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	206	206	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2574410752	2574410752	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	179	179	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1964409856	1964409856	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	120	120	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2500502528	2500502528	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1796879360	1796879360	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	156.079498	156.079498	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	613.39978	613.39978	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	4.86490011	4.86490011	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	53969	53969	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	455379924	455379924	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	268.651398	268.651398 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	384.179413	384.179413	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.283 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	75630336
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	12002
AASNodeAbsentTimer_mS_M_u32	3256006400
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	39153
ANGLEVOLANTSigValidCount_Cnt_M_u16	37377
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	12403
AngleVolantMsgTimer_mS_M_u32	75630336
AngleVolantValidCount_Cnt_M_u16	36773
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	665417472
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1657927424
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2236819200
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	565503744
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	13780
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	657303296
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	17791
CAVNodeAbsentTimer_mS_M_u32	1514657536
CDD_SrlComVehSpd_Kph_G_f32	374.242188
CMM388NTCEnableTimer_mS_M_u32	267196160
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3262502656
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	33215
CMMNodeAbsentTimer_mS_M_u32	2584143616
CONSANGLECPKSigInvalidCount_Cnt_M_u16	42499
CONSANGLECPKSigValidCount_Cnt_M_u16	43939
CONSANGLECPK_Cnt_M_u16	5434
CONSANGLECPK_HwDeg_M_f32	-71.1214981
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	5434
CPKVehicleSpeedMsgTimer_mS_M_u32	3011315456
CPKVehicleSpeedValidCount_Cnt_M_u16	58579
CityParkInputConsistentCount_Cnt_M_u16	52761
CityParkInputInvalidCount_Cnt_M_u16	19331
CityParkInputMsgTimer_mS_M_u32	4214187008
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2642851584
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	56150

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	317347584
ComputerRazGCTSigValidCount_Cnt_M_u16	63810
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	22799
DMDFCTCPKSigValidCount_Cnt_M_u16	20007
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	43819
DMDRELAXECPKSigValidCount_Cnt_M_u16	48059
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	1172
DateInvalidTimer_mS_M_u32	1657927424
DiagMuxOnAbsentTimer_mS_M_u32	744146688
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	565503744
ESPNTCEnableTimer_mS_M_u32	2849486592
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	33851
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	54
EffacDefaultDiagTimer_mS_M_u32[1]	64
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	9900
ElecIntTimer_mS_M_u32[1]	11000
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3578242816
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	48525
EtatMTSigValidCount_Cnt_M_u16	19001
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	58941
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	33629
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	22613
ISDAT4V2BSI552MsgTimer_mS_M_u32	3833259776
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	30360
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	28588
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	19001
ISDATBSI3F2MsgTimer_mS_M_u32	1679869696
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1007
ISDATBSI412MsgLenValidCount_Cnt_M_u16	52211
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	48525
ISDATBSI412MsgTimer_mS_M_u32	1514669824
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	31539
ISDATBSI432MsgLenValidCount_Cnt_M_u16	27823
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	45284
ISDATDIRASentFltAcc_Cnt_M_u16	47528
ISDATDIRASentTimer_mS_M_u32	3011315456
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	46464
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	36773
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	38258
ISDYN2CMMMsgTimer_mS_M_u32	2158606080
ISDYNAASChkSumInvalidCount_Cnt_M_u16	32028
ISDYNAASChkSumValidCount_Cnt_M_u16	10188
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	59912
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	17494
ISDYNAASMsgLenValidCount_Cnt_M_u16	40030
ISDYNAASMsgTimeValidCount_Cnt_M_u16	32028
ISDYNAASMsgTimer_mS_M_u32	4135130880
ISDYNABRChkSumInvalidCount_Cnt_M_u16	18083
ISDYNABRChkSumValidCount_Cnt_M_u16	23068
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	29695
ISDYNABRMsgCountValidCount_Cnt_M_u16	37615
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	44006
ISDYNABRMsgLenValidCount_Cnt_M_u16	26054
ISDYNABRMsgTimeValidCount_Cnt_M_u16	5434
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	12911
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	192
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	19001
ISDYNCMM208MsgTimer_mS_M_u32	2551346944
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	12911
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	192
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	2155

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1338676992
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	30153
ISDYNVOLChkSumValidCount_Cnt_M_u16	58345
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	30677
ISDYNVOLMsgCountValidCount_Cnt_M_u16	5485
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	55384
ISDYNVOLMsgLenValidCount_Cnt_M_u16	3160
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	33215
ISDYNVOLMsgTimer_mS_M_u32	1433818880
IgnOnTimer_mS_M_u32	3778975488
IgnTimeOff_Sec_M_u32	169601704
ManVehSpd_Kph_M_f32	526.596497
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	159
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	137
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2679031552
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	35
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1251354368
PrevISDATBSI412MsgDLCError_Cnt_M_u08	246
PrevISDATBSI412MsgRxTime_MSec_M_u32	4151105280
PrevISDATBSI432MsgDLCError_Cnt_M_u08	36
PrevISDATBSI432MsgRxTime_MSec_M_u32	914077440
PrevISDATDIRAMsgTxTime_MSec_M_u32	3408975616
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	176
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1426089728
PrevISDYNAASMsgDLCError_Cnt_M_u08	16
PrevISDYNAASMsgRxTime_MSec_M_u32	1572624128
PrevISDYNABRMsgDLCError_Cnt_M_u08	110
PrevISDYNABRMsgRxTime_MSec_M_u32	3445004032
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	12
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1906661120
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	5
PrevISDYNCMM388MsgRxTime_MSec_M_u32	286439168
PrevISDYNVOLMsgDLCError_Cnt_M_u08	165
PrevISDYNVOLMsgRxTime_MSec_M_u32	646829824
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3473803008
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	524.431396
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	33052
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	420
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	32953
VitesseVehicleBVRampValidCount_Cnt_M_u16	27905
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	49166
VitesseVehicleBVSigValidCount_Cnt_M_u16	50398
VitesseVehicleBV_Kph_M_f32	585.65033
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	2155
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	24275
VitesseVehiculeRoues_Kph_M_f32	312.761597
k_AASNTCEnableTimeout_mS_u16	54133
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	35476
k_AASNodeTimeout_mS_u16	53412
k_ABSNodeTimeout_mS_u16	15416
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	15458
k_ANGLEVOLANTSigValidThresh_Cnt_u16	798
k_AngleVolantInvalidThresh_Cnt_u16	63721
k_AngleVolantValidThresh_Cnt_u16	19331
k_BSI552MsgTimeout_mS_u16	4190
k_BSINTCEnableTimeout_mS_u16	38731
k_BSINodeAbsentDiag_Cnt_str.Threshold	5581
k_BSINodeAbsentDiag_Cnt_str.PStep	35240
k_BSINodeAbsentDiag_Cnt_str.NStep	56663
k_BSINodeAbsentTimeout_mS_u16	1675
k_BSINodeTimeout_mS_u16	45284
k_BattOvHi_Volt_f32	18.6532001
k_BattOvLo_Volt_f32	12.2278996
k_BattUvHi_Volt_f32	15.3304005
k_BattUvLo_Volt_f32	8.88169956
k_CAVNTCEnableTimeout_mS_u16	29793
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	43333
k_CAVNodeTimeout_mS_u16	25743
k_CMM388MsgTimeout_mS_u16	15842
k_CMM388NTCEnableTimeout_mS_u16	53614
k_CMMNTCEnableTimeout_mS_u16	24240
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	41055
k_CONSANGLECPKMax_HwDeg_f32	117.997597
k_CONSANGLECPKMin_HwDeg_f32	-352.536499
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	38763
k_CONSANGLECPKSigValidThresh_Cnt_u16	11731
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	466
k_CPKVehicleSpeedValidThresh_Cnt_u16	57222
k_CityParkInputInvalidThresh_Cnt_u16	26193
k_CityParkInputValidThresh_Cnt_u16	52761
k_ComputerRazGCTSigValidThresh_Cnt_u16	26278
k_CptTemporelSigValidThresh_Cnt_u16	60986
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	47846
k_DMDFCTCPKSigValidThresh_Cnt_u16	46278
k_DMDFCTCPKValidCount_Cnt_u16	48828
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	38258
k_DMDRELAXECPKSigValidThresh_Cnt_u16	7882
k_DMDRelaxeConsistentThresh_Cnt_u16	49656
k_DateValidThresh_Cnt_u16	22613
k_DefaultVehSpd_Kph_f32	80.5065002
k_DiagMuxOnAbsentTimeout_mS_u16	9624
k_EMNodeTimeout_mS_u16	46964
k_ESPNTCEnableTimeout_mS_u16	36363
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	11335
k_EtatMTSigInvalidThresh_Cnt_u16	4558
k_EtatMTSigValidThresh_Cnt_u16	49031
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	713
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	39894
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	18358
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	37833
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	49053
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	23395
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	14308
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	64544
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	46247
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	8078
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	2099
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	47354
k_ISDATDIRASentDiag_Cnt_str.Threshold	2435

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	9638
k_ISDATDIRASentDiag_Cnt_str.NStep	54621
k_ISDATDIRASentTimeout_mS_u16	47919
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	32355
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	12403
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	37479
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	54691
k_ISDYNAASChkSumValidThresh_Cnt_u16	10524
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	33535
k_ISDYNAASMsgCountValidThresh_Cnt_u16	57839
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	41239
k_ISDYNAASMsgLenValidThresh_Cnt_u16	18200
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	58630
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	4780
k_ISDYNABRChkSumValidThresh_Cnt_u16	29964
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	17620
k_ISDYNABRMsgCountValidThresh_Cnt_u16	29220
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	20671
k_ISDYNABRMsgLenValidThresh_Cnt_u16	37691
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	16175
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	6032
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	13260
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	1327
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	42993
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	57601
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	13723
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	57246
k_ISDYNVOLChkSumValidThresh_Cnt_u16	23778
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	53452
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	25488
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	57113
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	48325
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	48051
k_IgnOnTimeout_mS_u16	6186
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	201.569397
k_PowerCutVehSpdLowThresh_Kph_f32	57.7960014
k_PowerCutVehSpdLowTimeout_mS_u16	64945
k_VBattMaxAAS_Volt_f32	22.0883999
k_VBattMaxBSI_Volt_f32	30.2644005
k_VBattMaxCAV_Volt_f32	21.0084991
k_VBattMaxCMM388_Volt_f32	15.1619997
k_VBattMaxCMM_Volt_f32	23.9466
k_VBattMaxESP_Volt_f32	6.6809001
k_VBattMinAAS_Volt_f32	21.5284996
k_VBattMinBSI_Volt_f32	6.6809001
k_VBattMinCAV_Volt_f32	10.8712997
k_VBattMinCMM388_Volt_f32	3.94120002
k_VBattMinCMM_Volt_f32	7.8132
k_VBattMinESP_Volt_f32	23.9466
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	1077
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	16489
k_VitesseVehicleBVRampValidThresh_Cnt_u16	1749
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	13033
k_VitesseVehicleBVSigValidThresh_Cnt_u16	31182
k_VitesseVehicleBVSpeedPassThresh_kph_f32	642.986572
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	54399
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	10567
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1657927424
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60612
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2882176512
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	5
target_SrlComInput_Per1_Batt_Volt_f32.value	31
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4017268480
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	166
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.408320367
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1017157376
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	62
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2830382848
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	175
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3352811264
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1108047616
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3209631488
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3886200576
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1661359872
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	123
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	214
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3968366336
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	169
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	177
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	223
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	225
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	246
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	769103616
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3547019008
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3960395520
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	197
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	204
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3693094656
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1785
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.101277575
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	78794
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	96.4642029
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	9838

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2882176512	2882176512	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2882176512	2882176512	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2882176512	2882176512	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2882176512	2882176512	✔
CDD_SrlComVehSpd_Kph_G_f32	526.596497	526.596497	✔
CMM388NTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2882176512	2882176512	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	5434	5434	✔
CONSANGLECPK_HwDeg_M_f32	-71.1214981	-71.1214981 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2882176512	2882176512	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2882176512	2882176512	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2882176512	2882176512	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2882176512	2882176512	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2882176512	2882176512	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2882176512	2882176512	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2882176512	2882176512	✔
ESPNTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2882176512	2882176512	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	54	54	✔
EffacDefaultDiagTimer_mS_M_u32[1]	64	64	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	9900	9900	✔
ElecIntTimer_mS_M_u32[1]	11000	11000	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2882176512	2882176512	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	22613	22613	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	19001	19001	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	48525	48525	✔
ISDATBSI412MsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	45284	45284	✔
ISDATBSI432MsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2882176512	2882176512	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	38258	38258	✔
ISDYN2CMMMsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	32028	32028	✔
ISDYNAASMsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	5434	5434	✔
ISDYNABRMsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	19001	19001	✔
ISDYNCMM208MsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	2155	2155	✔
ISDYNCMM388MsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	33215	33215	✔
ISDYNVOLMsgTimer_mS_M_u32	2882176512	2882176512	✔
IgnOnTimer_mS_M_u32	3778975488	3778975488	✔
IgnTimeOff_Sec_M_u32	169601704	169601704	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	173	173	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1017157376	1017157376	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	62	62	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2830382848	2830382848	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	175	175	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3352811264	3352811264	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	167	167	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1108047616	1108047616	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3408975616	3408975616	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3886200576	3886200576	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	72	72	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1661359872	1661359872	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	37	37	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3968366336	3968366336	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	233	233	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	769103616	769103616	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	212	212	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3547019008	3547019008	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	94	94	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3960395520	3960395520	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3693094656	3693094656	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	524.431396	524.431396	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	585.65033	585.65033	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	312.761597	312.761597	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	5434	5434	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	169601704	169601704	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-71.1214981	-71.1214981 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.284 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	720678400
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	52691
AASNodeAbsentTimer_mS_M_u32	1359126016
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	59815
ANGLEVOLANTSigValidCount_Cnt_M_u16	47927
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	19744
AngleVolantMsgTimer_mS_M_u32	720678400
AngleVolantValidCount_Cnt_M_u16	32267
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3946733056
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2076499456
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3573632512
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3067874816
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	24318
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2037501440
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	59003
CAVNodeAbsentTimer_mS_M_u32	1155743232
CDD_SrlComVehSpd_Kph_G_f32	655.340027
CMM388NTCEnableTimer_mS_M_u32	1223917056
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1146699264
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	47997
CMMNodeAbsentTimer_mS_M_u32	367398400
CONSANGLECPKSigInvalidCount_Cnt_M_u16	32111
CONSANGLECPKSigValidCount_Cnt_M_u16	26958
CONSANGLECPK_Cnt_M_u16	18569
CONSANGLECPK_HwDeg_M_f32	-121.6558
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	18569
CPKVehicleSpeedMsgTimer_mS_M_u32	3389238784
CPKVehicleSpeedValidCount_Cnt_M_u16	56521
CityParkInputConsistentCount_Cnt_M_u16	37551
CityParkInputInvalidCount_Cnt_M_u16	37744
CityParkInputMsgTimer_mS_M_u32	1017157376
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2393284096
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	39031

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3304832512
ComputerRazGCTSigValidCount_Cnt_M_u16	62772
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	39628
DMDFCTCPKSigValidCount_Cnt_M_u16	38979
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	6905
DMDRELAXECPKSigValidCount_Cnt_M_u16	42505
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	58812
DateInvalidTimer_mS_M_u32	2076499456
DiagMuxOnAbsentTimer_mS_M_u32	107638272
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3067874816
ESPNTCEnableTimer_mS_M_u32	3987971584
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	8392
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6454
ElecIntTimer_mS_M_u32[1]	8257
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1461964288
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	4370
EtatMTSigValidCount_Cnt_M_u16	38862
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	9409
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	18976
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	45497
ISDAT4V2BSI552MsgTimer_mS_M_u32	109710848
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	10610
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	2805
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	38862
ISDATBSI3F2MsgTimer_mS_M_u32	4145573376
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	61036
ISDATBSI412MsgLenValidCount_Cnt_M_u16	8991
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	4370
ISDATBSI412MsgTimer_mS_M_u32	3248664064
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	40737
ISDATBSI432MsgLenValidCount_Cnt_M_u16	14188
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	30796
ISDATDIRASentFltAcc_Cnt_M_u16	28160
ISDATDIRASentTimer_mS_M_u32	3389238784
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	65463
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	32267
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	12707
ISDYN2CMMMsgTimer_mS_M_u32	826121728
ISDYNAASChkSumInvalidCount_Cnt_M_u16	19237
ISDYNAASChkSumValidCount_Cnt_M_u16	34772
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	47842
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	1526
ISDYNAASMsgLenValidCount_Cnt_M_u16	39582
ISDYNAASMsgTimeValidCount_Cnt_M_u16	19237
ISDYNAASMsgTimer_mS_M_u32	3310321152
ISDYNABRChkSumInvalidCount_Cnt_M_u16	50191
ISDYNABRChkSumValidCount_Cnt_M_u16	58982
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	45692
ISDYNABRMsgCountValidCount_Cnt_M_u16	37483
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	47046
ISDYNABRMsgLenValidCount_Cnt_M_u16	34533
ISDYNABRMsgTimeValidCount_Cnt_M_u16	18569
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	41424
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	59037
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	38862
ISDYNCMM208MsgTimer_mS_M_u32	2114149888
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	41424
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	59037
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	43961

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3747282432
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	42525
ISDYNVOLChkSumValidCount_Cnt_M_u16	22652
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	54906
ISDYNVOLMsgCountValidCount_Cnt_M_u16	55921
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	55409
ISDYNVOLMsgLenValidCount_Cnt_M_u16	47409
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	47997
ISDYNVOLMsgTimer_mS_M_u32	760724992
IgnOnTimer_mS_M_u32	4211015168
IgnTimeOff_Sec_M_u32	1867350361
ManVehSpd_Kph_M_f32	72.5450974
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	160
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	251
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4235095552
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	209
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1362644480
PrevISDATBSI412MsgDLCError_Cnt_M_u08	27
PrevISDATBSI412MsgRxTime_MSec_M_u32	1098137088
PrevISDATBSI432MsgDLCError_Cnt_M_u08	147
PrevISDATBSI432MsgRxTime_MSec_M_u32	3620183552
PrevISDATDIRAMsgTxTime_MSec_M_u32	3592961536
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	99
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2868481536
PrevISDYNAASMsgDLCError_Cnt_M_u08	58
PrevISDYNAASMsgRxTime_MSec_M_u32	2894446080
PrevISDYNABRMsgDLCError_Cnt_M_u08	28
PrevISDYNABRMsgRxTime_MSec_M_u32	2528574976
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	96
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1422573056
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	123
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1677893120
PrevISDYNVOLMsgDLCError_Cnt_M_u08	91
PrevISDYNVOLMsgRxTime_MSec_M_u32	2014395904
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4216368640
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	169.415405
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	59300
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	716
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	40141
VitesseVehicleBVRampValidCount_Cnt_M_u16	29877
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	10320
VitesseVehicleBVSigValidCount_Cnt_M_u16	54944
VitesseVehicleBV_Kph_M_f32	280.598907
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	43961
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	50496
VitesseVehiculeRoues_Kph_M_f32	175.005005
k_AASNTCEnableTimeout_mS_u16	47576
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	2366
k_AASNodeTimeout_mS_u16	38348
k_ABSNodeTimeout_mS_u16	54609
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	55188
k_ANGLEVOLANTSigValidThresh_Cnt_u16	61471
k_AngleVolantInvalidThresh_Cnt_u16	64190
k_AngleVolantValidThresh_Cnt_u16	37744
k_BSI552MsgTimeout_mS_u16	40095
k_BSINTCEnableTimeout_mS_u16	43737
k_BSINodeAbsentDiag_Cnt_str.Threshold	18231
k_BSINodeAbsentDiag_Cnt_str.PStep	60389
k_BSINodeAbsentDiag_Cnt_str.NStep	16664
k_BSINodeAbsentTimeout_mS_u16	10968
k_BSINodeTimeout_mS_u16	30796
k_BattOvHi_Volt_f32	0.500100017
k_BattOvLo_Volt_f32	23.0450993
k_BattUvHi_Volt_f32	21.4498997
k_BattUvLo_Volt_f32	18.0398006
k_CAVNTCEnableTimeout_mS_u16	4310
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	21289
k_CAVNodeTimeout_mS_u16	29131
k_CMM388MsgTimeout_mS_u16	41171
k_CMM388NTCEnableTimeout_mS_u16	5679
k_CMMNTCEnableTimeout_mS_u16	53546
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	12444
k_CONSANGLECPKMax_HwDeg_f32	642.02478
k_CONSANGLECPKMin_HwDeg_f32	-100.037903
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	65209
k_CONSANGLECPKSigValidThresh_Cnt_u16	22592
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	14914
k_CPKVehicleSpeedValidThresh_Cnt_u16	30631
k_CityParkInputInvalidThresh_Cnt_u16	40197
k_CityParkInputValidThresh_Cnt_u16	37551
k_ComputerRazGCTSigValidThresh_Cnt_u16	4424
k_CptTemporelSigValidThresh_Cnt_u16	18251
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	35526
k_DMDFCTCPKSigValidThresh_Cnt_u16	39397
k_DMDFCTCPKValidCount_Cnt_u16	25670
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	12707
k_DMDRELAXECPKSigValidThresh_Cnt_u16	29274
k_DMDRelaxeConsistentThresh_Cnt_u16	49360
k_DateValidThresh_Cnt_u16	45497
k_DefaultVehSpd_Kph_f32	77.4601974
k_DiagMuxOnAbsentTimeout_mS_u16	3951
k_EMNodeTimeout_mS_u16	19740
k_ESPNTCEnableTimeout_mS_u16	15575
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	11492
k_EtatMTSigInvalidThresh_Cnt_u16	52878
k_EtatMTSigValidThresh_Cnt_u16	8741
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	54109
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	46328
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	55768
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	54751
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	7970
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	47120
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	27918
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	36121
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	49861
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	31117
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	52321
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	3146
k_ISDATDIRASentDiag_Cnt_str.Threshold	50189

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	7148
k_ISDATDIRASentDiag_Cnt_str.NStep	24623
k_ISDATDIRASentTimeout_mS_u16	38507
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	40975
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	19744
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	40899
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	5903
k_ISDYNAASChkSumValidThresh_Cnt_u16	31078
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	34172
k_ISDYNAASMsgCountValidThresh_Cnt_u16	42347
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	33971
k_ISDYNAASMsgLenValidThresh_Cnt_u16	624
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	60007
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	7028
k_ISDYNABRChkSumValidThresh_Cnt_u16	61715
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	12798
k_ISDYNABRMsgCountValidThresh_Cnt_u16	26318
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	20093
k_ISDYNABRMsgLenValidThresh_Cnt_u16	62408
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	60333
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	62536
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	4821
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	58411
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	48295
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	52791
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	13608
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	55135
k_ISDYNVOLChkSumValidThresh_Cnt_u16	60498
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	48917
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	39434
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	56430
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	28714
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	32671
k_IgnOnTimeout_mS_u16	23995
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	202.771194
k_PowerCutVehSpdLowThresh_Kph_f32	226.091507
k_PowerCutVehSpdLowTimeout_mS_u16	11044
k_VBattMaxAAS_Volt_f32	8.11120033
k_VBattMaxBSI_Volt_f32	3.75690007
k_VBattMaxCAV_Volt_f32	12.6076002
k_VBattMaxCMM388_Volt_f32	13.1961002
k_VBattMaxCMM_Volt_f32	18.1343002
k_VBattMaxESP_Volt_f32	29.9381008
k_VBattMinAAS_Volt_f32	13.4968004
k_VBattMinBSI_Volt_f32	29.9381008
k_VBattMinCAV_Volt_f32	7.53770018
k_VBattMinCMM388_Volt_f32	23.7520008
k_VBattMinCMM_Volt_f32	28.9902992
k_VBattMinESP_Volt_f32	18.1343002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	54937
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	28349
k_VitesseVehicleBVRampValidThresh_Cnt_u16	10618
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	27516
k_VitesseVehicleBVSigValidThresh_Cnt_u16	41872
k_VitesseVehicleBVSpeedPassThresh_kph_f32	457.911804
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	14715
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	55267
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2076499456
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	49346
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	4191629568
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	123
target_SrlComInput_Per1_Batt_Volt_f32.value	5.68389988
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1956826624
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	195
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.41370818
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	139
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4040752640
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	13
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	52305408
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	50
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1009991168
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	1
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2753060352
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1120763392
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	193
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	542285312
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	193
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1151843840
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	108
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	121
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	203
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	207
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	221
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	187
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3634454016
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	68
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	80
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	130
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	147
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	114
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3107192320
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	231
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	519642624
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	191
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1804484096
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	134
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	175
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1150963200
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2229
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.282947719
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	316867
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	174.336899
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	49070

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4191629568	4191629568	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	4191629568	4191629568	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	4191629568	4191629568	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4191629568	4191629568	✔
CDD_SrlComVehSpd_Kph_G_f32	72.5450974	72.5450974	✔
CMM388NTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4191629568	4191629568	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	18569	18569	✔
CONSANGLECPK_HwDeg_M_f32	-121.6558	-121.6558 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4191629568	4191629568	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	4191629568	4191629568	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4191629568	4191629568	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4191629568	4191629568	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4191629568	4191629568	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4191629568	4191629568	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4191629568	4191629568	✔
ESPNTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4191629568	4191629568	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	6454	6454	✔
ElecIntTimer_mS_M_u32[1]	8257	8257	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4191629568	4191629568	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	45497	45497	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	38862	38862	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	4370	4370	✔
ISDATBSI412MsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	30796	30796	✔
ISDATBSI432MsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	4191629568	4191629568	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	12707	12707	✔
ISDYN2CMMMsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	19237	19237	✔
ISDYNAASMsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	18569	18569	✔
ISDYNABRMsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	38862	38862	✔
ISDYNCMM208MsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	43961	43961	✔
ISDYNCMM388MsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	47997	47997	✔
ISDYNVOLMsgTimer_mS_M_u32	4191629568	4191629568	✔
IgnOnTimer_mS_M_u32	4211015168	4211015168	✔
IgnTimeOff_Sec_M_u32	1867350361	1867350361	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	139	139	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4040752640	4040752640	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	13	13	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	52305408	52305408	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	50	50	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1009991168	1009991168	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	1	1	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2753060352	2753060352	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3592961536	3592961536	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	193	193	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	542285312	542285312	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	193	193	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1151843840	1151843840	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	187	187	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3634454016	3634454016	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	114	114	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3107192320	3107192320	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	231	231	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	519642624	519642624	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	191	191	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1804484096	1804484096	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1150963200	1150963200	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	169.415405	169.415405	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	280.598907	280.598907	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	175.005005	175.005005	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	18569	18569	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1867350361	1867350361	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-121.6558	-121.6558 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.285 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	922269952
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	59485
AASNodeAbsentTimer_mS_M_u32	2827938048
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	34527
ANGLEVOLANTSigValidCount_Cnt_M_u16	56305
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	56950
AngleVolantMsgTimer_mS_M_u32	922269952
AngleVolantValidCount_Cnt_M_u16	24628
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2027661568
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	21506304
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3008551168
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3905067264
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	17114
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	671176960
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	35043
CAVNodeAbsentTimer_mS_M_u32	2540505344
CDD_SrlComVehSpd_Kph_G_f32	165.702805
CMM388NTCEnableTimer_mS_M_u32	473712896
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4044032256
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	27806
CMMNodeAbsentTimer_mS_M_u32	1940166912
CONSANGLECPKSigInvalidCount_Cnt_M_u16	39560
CONSANGLECPKSigValidCount_Cnt_M_u16	57514
CONSANGLECPK_Cnt_M_u16	61177
CONSANGLECPK_HwDeg_M_f32	410.193115
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	61177
CPKVehicleSpeedMsgTimer_mS_M_u32	1439414528
CPKVehicleSpeedValidCount_Cnt_M_u16	18722
CityParkInputConsistentCount_Cnt_M_u16	45640
CityParkInputInvalidCount_Cnt_M_u16	17669
CityParkInputMsgTimer_mS_M_u32	4040752640
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2141382912
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	6257

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	421759232
ComputerRazGCTSigValidCount_Cnt_M_u16	57017
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	40689
DMDFCTCPKSigValidCount_Cnt_M_u16	4170
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	47849
DMDRELAXECPKSigValidCount_Cnt_M_u16	58235
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	54689
DateInvalidTimer_mS_M_u32	21506304
DiagMuxOnAbsentTimer_mS_M_u32	2878830848
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3905067264
ESPNTCEnableTimer_mS_M_u32	3598444800
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	63099
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	65
EffacDefaultDiagTimer_mS_M_u32[1]	655
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8976
ElecIntTimer_mS_M_u32[1]	15234
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3605747968
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	20702
EtatMTSigValidCount_Cnt_M_u16	13932
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	27794
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1588
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	7144
ISDAT4V2BSI552MsgTimer_mS_M_u32	834181376
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	15680
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	12918
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13932
ISDATBSI3F2MsgTimer_mS_M_u32	294484224
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	42833
ISDATBSI412MsgLenValidCount_Cnt_M_u16	25335
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	20702
ISDATBSI412MsgTimer_mS_M_u32	2867771648
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	20914
ISDATBSI432MsgLenValidCount_Cnt_M_u16	17039
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	22384
ISDATDIRASentFltAcc_Cnt_M_u16	18004
ISDATDIRASentTimer_mS_M_u32	1439414528
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	367
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	24628
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	63084
ISDYN2CMMMsgTimer_mS_M_u32	3017664768
ISDYNAASChkSumInvalidCount_Cnt_M_u16	14439
ISDYNAASChkSumValidCount_Cnt_M_u16	52248
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	50607
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	54898
ISDYNAASMsgLenValidCount_Cnt_M_u16	16956
ISDYNAASMsgTimeValidCount_Cnt_M_u16	14439
ISDYNAASMsgTimer_mS_M_u32	388516096
ISDYNABRChkSumInvalidCount_Cnt_M_u16	19753
ISDYNABRChkSumValidCount_Cnt_M_u16	53219
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	7778
ISDYNABRMsgCountValidCount_Cnt_M_u16	51283
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	1923
ISDYNABRMsgLenValidCount_Cnt_M_u16	41957
ISDYNABRMsgTimeValidCount_Cnt_M_u16	61177
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	24696
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	33489
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13932
ISDYNCMM208MsgTimer_mS_M_u32	344762624
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	24696
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	33489
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	3882

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1459996928
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	22654
ISDYNVOLChkSumValidCount_Cnt_M_u16	19232
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	9191
ISDYNVOLMsgCountValidCount_Cnt_M_u16	33216
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	45952
ISDYNVOLMsgLenValidCount_Cnt_M_u16	39682
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	27806
ISDYNVOLMsgTimer_mS_M_u32	1343195392
IgnOnTimer_mS_M_u32	2484717824
IgnTimeOff_Sec_M_u32	1220347399
ManVehSpd_Kph_M_f32	325.483185
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	161
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	163
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3649796352
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	61
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3668826368
PrevISDATBSI412MsgDLCError_Cnt_M_u08	19
PrevISDATBSI412MsgRxTime_MSec_M_u32	632948992
PrevISDATBSI432MsgDLCError_Cnt_M_u08	160
PrevISDATBSI432MsgRxTime_MSec_M_u32	1749018880
PrevISDATDIRAMsgTxTime_MSec_M_u32	933103872
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	219
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1651120384
PrevISDYNAASMsgDLCError_Cnt_M_u08	112
PrevISDYNAASMsgRxTime_MSec_M_u32	176523520
PrevISDYNABRMsgDLCError_Cnt_M_u08	215
PrevISDYNABRMsgRxTime_MSec_M_u32	2700200192
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	172
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1706461440
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	72
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1871636736
PrevISDYNVOLMsgDLCError_Cnt_M_u08	105
PrevISDYNVOLMsgRxTime_MSec_M_u32	904071424
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	904182016
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	420.087585
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	26984
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	16818
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	11757
VitesseVehicleBVRampValidCount_Cnt_M_u16	53239
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	44772
VitesseVehicleBVSigValidCount_Cnt_M_u16	28086
VitesseVehicleBV_Kph_M_f32	514.696411
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	3882
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	27732
VitesseVehiculeRoues_Kph_M_f32	322.558197
k_AASNTCEnableTimeout_mS_u16	38668
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	19099
k_AASNodeTimeout_mS_u16	34994
k_ABSNodeTimeout_mS_u16	17250
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	13401
k_ANGLEVOLANTSigValidThresh_Cnt_u16	42102
k_AngleVolantInvalidThresh_Cnt_u16	49305
k_AngleVolantValidThresh_Cnt_u16	17669
k_BSI552MsgTimeout_mS_u16	8759
k_BSINTCEnableTimeout_mS_u16	3722
k_BSINodeAbsentDiag_Cnt_str.Threshold	33221
k_BSINodeAbsentDiag_Cnt_str.PStep	37625
k_BSINodeAbsentDiag_Cnt_str.NStep	41632
k_BSINodeAbsentTimeout_mS_u16	9550
k_BSINodeTimeout_mS_u16	22384
k_BattOvHi_Volt_f32	3.96989989
k_BattOvLo_Volt_f32	24.0279999
k_BattUvHi_Volt_f32	5.67609978
k_BattUvLo_Volt_f32	19.1756992
k_CAVNTCEnableTimeout_mS_u16	58579
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	31449
k_CAVNodeTimeout_mS_u16	11636
k_CMM388MsgTimeout_mS_u16	28509
k_CMM388NTCEnableTimeout_mS_u16	32585
k_CMMNTCEnableTimeout_mS_u16	9752
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	39488
k_CONSANGLECPKMax_HwDeg_f32	68.6452026
k_CONSANGLECPKMin_HwDeg_f32	-600.171814
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	5674
k_CONSANGLECPKSigValidThresh_Cnt_u16	45908
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	62288
k_CPKVehicleSpeedValidThresh_Cnt_u16	47008
k_CityParkInputInvalidThresh_Cnt_u16	6727
k_CityParkInputValidThresh_Cnt_u16	45640
k_ComputerRazGCTSigValidThresh_Cnt_u16	23998
k_CptTemporelSigValidThresh_Cnt_u16	21876
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	36483
k_DMDFCTCPKSigValidThresh_Cnt_u16	27365
k_DMDFCTCPKValidCount_Cnt_u16	21250
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	63084
k_DMDRELAXECPKSigValidThresh_Cnt_u16	40453
k_DMDRelaxeConsistentThresh_Cnt_u16	2723
k_DateValidThresh_Cnt_u16	7144
k_DefaultVehSpd_Kph_f32	187.958405
k_DiagMuxOnAbsentTimeout_mS_u16	45639
k_EMNodeTimeout_mS_u16	8065
k_ESPNTCEnableTimeout_mS_u16	62927
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	50536
k_EtatMTSigInvalidThresh_Cnt_u16	59820
k_EtatMTSigValidThresh_Cnt_u16	55462
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	21503
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	43244
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	49357
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	11257
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	59887
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	55909
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	56299
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	13704
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	30406
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	27629
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	19762
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	38582
k_ISDATDIRASentDiag_Cnt_str.Threshold	13378

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	37990
k_ISDATDIRASentDiag_Cnt_str.NStep	48989
k_ISDATDIRASentTimeout_mS_u16	17941
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	12135
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	56950
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	32011
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	21545
k_ISDYNAASChkSumValidThresh_Cnt_u16	5859
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	42338
k_ISDYNAASMsgCountValidThresh_Cnt_u16	36691
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	39741
k_ISDYNAASMsgLenValidThresh_Cnt_u16	53958
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	54686
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	5241
k_ISDYNABRChkSumValidThresh_Cnt_u16	40283
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	51674
k_ISDYNABRMsgCountValidThresh_Cnt_u16	62764
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	45982
k_ISDYNABRMsgLenValidThresh_Cnt_u16	32123
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	41615
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	54140
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7702
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	55701
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	3551
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	41713
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	16349
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	30840
k_ISDYNVOLChkSumValidThresh_Cnt_u16	37726
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	36756
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	17655
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	24266
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	7512
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	51766
k_IgnOnTimeout_mS_u16	21860
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	138.525299
k_PowerCutVehSpdLowThresh_Kph_f32	12.5642996
k_PowerCutVehSpdLowTimeout_mS_u16	29480
k_VBattMaxAAS_Volt_f32	29.0772991
k_VBattMaxBSI_Volt_f32	14.6188002
k_VBattMaxCAV_Volt_f32	11.8175001
k_VBattMaxCMM388_Volt_f32	27.9055996
k_VBattMaxCMM_Volt_f32	18.2150993
k_VBattMaxESP_Volt_f32	3.78309989
k_VBattMinAAS_Volt_f32	1.80239999
k_VBattMinBSI_Volt_f32	3.78309989
k_VBattMinCAV_Volt_f32	1.47160006
k_VBattMinCMM388_Volt_f32	32
k_VBattMinCMM_Volt_f32	32
k_VBattMinESP_Volt_f32	18.2150993
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	13257
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	34079
k_VitesseVehicleBVRampValidThresh_Cnt_u16	10983
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	4640
k_VitesseVehicleBVSigValidThresh_Cnt_u16	17317
k_VitesseVehicleBVSpeedPassThresh_kph_f32	247.473007
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	36835
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	56941
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	21506304
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	55763
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1813852160
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	72
target_SrlComInput_Per1_Batt_Volt_f32.value	18.8658009
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	980310272
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	243
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.596886039
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2592852224
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1614571776
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4051503360
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	911059200
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	380520704
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	177
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2057234688
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	78
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1243580672
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	43
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	69
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	76
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	185
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	175
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4239567104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	109
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	172
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1836763392
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	120
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	950757632
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	140
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2406222080
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	45
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	80
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	106
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	129
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	137
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	153
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	143120640
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	922
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.85655719
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	66535
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	231.078293
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	35146

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	56950	56950	✔
AngleVolantMsgTimer_mS_M_u32	1813852160	1813852160	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	33221	33221	✔
BSINodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	61177	61177	✔
CONSANGLECPK_HwDeg_M_f32	410.193115	410.193115 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	61177	61177	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1439414528	1439414528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	18722	18722	✔
CityParkInputConsistentCount_Cnt_M_u16	45640	45640	✔
CityParkInputInvalidCount_Cnt_M_u16	17669	17669	✔
CityParkInputMsgTimer_mS_M_u32	1813852160	1813852160	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1813852160	1813852160	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1813852160	1813852160	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1813852160	1813852160	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1813852160	1813852160	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1813852160	1813852160	✔
ESPNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1813852160	1813852160	✔
EffacDefaultDiagTimer_mS_M_u32[1]	655	655	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1813852160	1813852160	✔
ElecIntTimer_mS_M_u32[1]	15234	15234	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1813852160	1813852160	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1813852160	1813852160	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1813852160	1813852160	✔
IgnOnTimer_mS_M_u32	1813852160	1813852160	✔
IgnTimeOff_Sec_M_u32	1220347399	1220347399	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2592852224	2592852224	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1614571776	1614571776	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	8	8	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4051503360	4051503360	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	118	118	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	911059200	911059200	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	933103872	933103872	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	177	177	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2057234688	2057234688	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	78	78	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1243580672	1243580672	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	175	175	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4239567104	4239567104	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	123	123	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1836763392	1836763392	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	120	120	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	950757632	950757632	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	140	140	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2406222080	2406222080	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	143120640	143120640	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	420.087585	420.087585	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	514.696411	514.696411	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	322.558197	322.558197	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	61177	61177	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1220347399	1220347399	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	410.193115	410.193115 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.286 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	81303552
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	8875
AASNodeAbsentTimer_mS_M_u32	81135616
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	28963
ANGLEVOLANTSigValidCount_Cnt_M_u16	5294
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	58464
AngleVolantMsgTimer_mS_M_u32	81303552
AngleVolantValidCount_Cnt_M_u16	8612
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3069167616
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1873430528
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	541734912
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4009424896
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	59698
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2621356032
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	33176
CAVNodeAbsentTimer_mS_M_u32	3636176896
CDD_SrlComVehSpd_Kph_G_f32	202.844406
CMM388NTCEnableTimer_mS_M_u32	2538465280
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3286345728
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	44583
CMMNodeAbsentTimer_mS_M_u32	1448409088
CONSANGLECPKSigInvalidCount_Cnt_M_u16	51497
CONSANGLECPKSigValidCount_Cnt_M_u16	55684
CONSANGLECPK_Cnt_M_u16	43671
CONSANGLECPK_HwDeg_M_f32	-82.1540985
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43671
CPKVehicleSpeedMsgTimer_mS_M_u32	3026163712
CPKVehicleSpeedValidCount_Cnt_M_u16	63331
CityParkInputConsistentCount_Cnt_M_u16	31592

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	1075
CityParkInputMsgTimer_mS_M_u32	2592852224
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3482978304
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	57967
ComputerRazGCTSigInvalidTimer_mS_M_u32	1301817344
ComputerRazGCTSigValidCount_Cnt_M_u16	64021
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	42607
DMDFCTCPKSigValidCount_Cnt_M_u16	5410
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	32005
DMDRELAXECPKSigValidCount_Cnt_M_u16	42512
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	48094
DateInvalidTimer_mS_M_u32	1873430528
DiagMuxOnAbsentTimer_mS_M_u32	2449233920
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4009424896
ESPNTCEnableTimer_mS_M_u32	1863256064
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	58190
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	5
ElecIntTimer_mS_M_u32[1]	55
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3078666240
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	21095
EtatMTSigValidCount_Cnt_M_u16	13438
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	64267
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	4326
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	59976
ISDAT4V2BSI552MsgTimer_mS_M_u32	1813575680
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	60609
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	16352
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13438
ISDATBSI3F2MsgTimer_mS_M_u32	3088734208
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	33677
ISDATBSI412MsgLenValidCount_Cnt_M_u16	17244
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	21095
ISDATBSI412MsgTimer_mS_M_u32	16160768
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	20203
ISDATBSI432MsgLenValidCount_Cnt_M_u16	20242
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	35313
ISDATDIRASentFltAcc_Cnt_M_u16	19781
ISDATDIRASentTimer_mS_M_u32	3026163712
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	52021
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	8612
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	19454
ISDYN2CMMMsgTimer_mS_M_u32	3739813888
ISDYNAASChkSumInvalidCount_Cnt_M_u16	55949
ISDYNAASChkSumValidCount_Cnt_M_u16	16952
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	40243
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	38123
ISDYNAASMsgLenValidCount_Cnt_M_u16	54350
ISDYNAASMsgTimeValidCount_Cnt_M_u16	55949
ISDYNAASMsgTimer_mS_M_u32	1451878400
ISDYNABRChkSumInvalidCount_Cnt_M_u16	7621
ISDYNABRChkSumValidCount_Cnt_M_u16	55384
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	54428
ISDYNABRMsgCountValidCount_Cnt_M_u16	63879
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	11832
ISDYNABRMsgLenValidCount_Cnt_M_u16	15315
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43671
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	11804

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	62674
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13438
ISDYNCMM208MsgTimer_mS_M_u32	3890006016
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	11804
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	62674
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	27842
ISDYNCMM388MsgTimer_mS_M_u32	3975243776
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	59207
ISDYNVOLChkSumValidCount_Cnt_M_u16	61986
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	28557
ISDYNVOLMsgCountValidCount_Cnt_M_u16	6336
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	63
ISDYNVOLMsgLenValidCount_Cnt_M_u16	44154
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	44583
ISDYNVOLMsgTimer_mS_M_u32	1490298880
IgnOnTimer_mS_M_u32	2243258368
IgnTimeOff_Sec_M_u32	771532259
ManVehSpd_Kph_M_f32	556.106323
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	162
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	35
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3625998336
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	4
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3594074112
PrevISDATBSI412MsgDLCError_Cnt_M_u08	100
PrevISDATBSI412MsgRxTime_MSec_M_u32	2715068416
PrevISDATBSI432MsgDLCError_Cnt_M_u08	219
PrevISDATBSI432MsgRxTime_MSec_M_u32	3385001984
PrevISDATDIRAMsgTxTime_MSec_M_u32	4230522880
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	44
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2147776512
PrevISDYNAASMsgDLCError_Cnt_M_u08	31
PrevISDYNAASMsgRxTime_MSec_M_u32	2171742208
PrevISDYNABRMsgDLCError_Cnt_M_u08	195
PrevISDYNABRMsgRxTime_MSec_M_u32	3207424000
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	100
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1944004608
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	193
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2950039552
PrevISDYNVOLMsgDLCError_Cnt_M_u08	32
PrevISDYNVOLMsgRxTime_MSec_M_u32	1431939072
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3088357376
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	429.327606
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	13321
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	11756
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	14970
VitesseVehicleBVRampValidCount_Cnt_M_u16	55069
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	19732
VitesseVehicleBVSigValidCount_Cnt_M_u16	45919

Name	Input Value
VitesseVehicleBV_Kph_M_f32	173.7034
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	27842
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	22533
VitesseVehiculeRoues_Kph_M_f32	307.857513
k_AASNTCEnableTimeout_mS_u16	48734
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	48751
k_AASNodeTimeout_mS_u16	22764
k_ABSNodeTimeout_mS_u16	48412
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	758
k_ANGLEVOLANTSigValidThresh_Cnt_u16	34141
k_AngleVolantInvalidThresh_Cnt_u16	31988
k_AngleVolantValidThresh_Cnt_u16	1075
k_BSI552MsgTimeout_mS_u16	33372
k_BSINTCEnableTimeout_mS_u16	30819
k_BSINodeAbsentDiag_Cnt_str.Threshold	38325
k_BSINodeAbsentDiag_Cnt_str.PStep	25690
k_BSINodeAbsentDiag_Cnt_str.NStep	1956
k_BSINodeAbsentTimeout_mS_u16	28632
k_BSINodeTimeout_mS_u16	35313
k_BattOvHi_Volt_f32	30.7479
k_BattOvLo_Volt_f32	31.5
k_BattUvHi_Volt_f32	26.9622002
k_BattUvLo_Volt_f32	9.15649986
k_CAVNTCEnableTimeout_mS_u16	56521
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	950
k_CAVNodeTimeout_mS_u16	49253
k_CMM388MsgTimeout_mS_u16	36267
k_CMM388NTCEnableTimeout_mS_u16	3559
k_CMMNTCEnableTimeout_mS_u16	37433
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	32321
k_CONSANGLECPKMax_HwDeg_f32	696.365784
k_CONSANGLECPKMin_HwDeg_f32	-311.168396
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	22466
k_CONSANGLECPKSigValidThresh_Cnt_u16	33541
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	4370
k_CPKVehicleSpeedValidThresh_Cnt_u16	20128
k_CityParkInputInvalidThresh_Cnt_u16	44651
k_CityParkInputValidThresh_Cnt_u16	31592
k_ComputerRazGCTSigValidThresh_Cnt_u16	839
k_CptTemporelSigValidThresh_Cnt_u16	20198
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	39224
k_DMDFCTCPKSigValidThresh_Cnt_u16	59091
k_DMDFCTCPKValidCount_Cnt_u16	22714
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	19454
k_DMDRELAXECPKSigValidThresh_Cnt_u16	6129
k_DMDRelaxeConsistentThresh_Cnt_u16	51735
k_DateValidThresh_Cnt_u16	59976
k_DefaultVehSpd_Kph_f32	176.385605
k_DiagMuxOnAbsentTimeout_mS_u16	6317
k_EMNodeTimeout_mS_u16	24126
k_ESPNTCEnableTimeout_mS_u16	60116
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	40137
k_EtatMTSigInvalidThresh_Cnt_u16	5180
k_EtatMTSigValidThresh_Cnt_u16	35343
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	27397
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	32508
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	41945
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	17558
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	15733
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	14929
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	54336

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	39463
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	12207
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	955
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	53930
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	55902
k_ISDATDIRASentDiag_Cnt_str.Threshold	829
k_ISDATDIRASentDiag_Cnt_str.PStep	43924
k_ISDATDIRASentDiag_Cnt_str.NStep	17262
k_ISDATDIRASentTimeout_mS_u16	58113
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	5195
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58464
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	17696
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	2245
k_ISDYNAASChkSumValidThresh_Cnt_u16	856
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	16284
k_ISDYNAASMsgCountValidThresh_Cnt_u16	42119
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	33673
k_ISDYNAASMsgLenValidThresh_Cnt_u16	51888
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	37349
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	24406
k_ISDYNABRChkSumValidThresh_Cnt_u16	42865
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	21554
k_ISDYNABRMsgCountValidThresh_Cnt_u16	29949
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	55591
k_ISDYNABRMsgLenValidThresh_Cnt_u16	20046
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	47316
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	17869
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	29502
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	45635
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	56355
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	49070
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	29611
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	27672
k_ISDYNVOLChkSumValidThresh_Cnt_u16	3623
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	48131
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	51484
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	55459
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	12218
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	38750
k_IgnOnTimeout_mS_u16	34132
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	113.184898
k_PowerCutVehSpdLowThresh_Kph_f32	147.067703
k_PowerCutVehSpdLowTimeout_mS_u16	39434
k_VBattMaxAAS_Volt_f32	10.5124998
k_VBattMaxBSI_Volt_f32	4.45270014
k_VBattMaxCAV_Volt_f32	7.60370016
k_VBattMaxCMM388_Volt_f32	4.77860022
k_VBattMaxCMM_Volt_f32	18.4780998
k_VBattMaxESP_Volt_f32	31.8355999
k_VBattMinAAS_Volt_f32	26.6917
k_VBattMinBSI_Volt_f32	31.8355999
k_VBattMinCAV_Volt_f32	16.3083
k_VBattMinCMM388_Volt_f32	13.8660002
k_VBattMinCMM_Volt_f32	1.3915
k_VBattMinESP_Volt_f32	18.4780998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	3877
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	52707
k_VitesseVehicleBVRampValidThresh_Cnt_u16	23181
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	40226
k_VitesseVehicleBVSigValidThresh_Cnt_u16	31569
k_VitesseVehicleBVSpeedPassThresh_kph_f32	181.227798
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	27800
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	955
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1873430528
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	44013
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	68495872
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	193
target_SrlComInput_Per1_Batt_Volt_f32.value	21.8103008
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1492629504
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	58
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0904200152
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3126814720
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1942849536
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	176924672
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	247
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3331966976
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4026001408
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3466987520
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2862884864
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	78
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	136
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	145
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	163
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	177
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1198180352
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	76
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3180488704
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1719699456
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	201
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2898176000
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	104
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	114
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	132
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	145
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	883636224
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1167
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.770385444
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	507585
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	69.776001

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	56419		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	68495872	68495872	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	68495872	68495872	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	68495872	68495872	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	68495872	68495872	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
CDD_SrlComVehSpd_Kph_G_f32	556.106323	556.106323	✔
CMM388NTCEnableTimer_mS_M_u32	68495872	68495872	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	68495872	68495872	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	43671	43671	✔
CONSANGLECPK_HwDeg_M_f32	-82.1540985	-82.1540985 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	68495872	68495872	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	68495872	68495872	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	68495872	68495872	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	68495872	68495872	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	68495872	68495872	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	68495872	68495872	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	68495872	68495872	✔
ESPNTCEnableTimer_mS_M_u32	68495872	68495872	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	8	8	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	5	5	✔
ElecIntTimer_mS_M_u32[1]	55	55	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	68495872	68495872	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	59976	59976	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13438	13438	✔
ISDATBSI3F2MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	21095	21095	✔
ISDATBSI412MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	35313	35313	✔
ISDATBSI432MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	68495872	68495872	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	19454	19454	✔
ISDYN2CMMMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	55949	55949	✔
ISDYNAASMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43671	43671	✔
ISDYNABRMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13438	13438	✔
ISDYNCMM208MsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	27842	27842	✔
ISDYNCMM388MsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	44583	44583	✔
ISDYNVOLMsgTimer_mS_M_u32	68495872	68495872	✔
IgnOnTimer_mS_M_u32	2243258368	2243258368	✔
IgnTimeOff_Sec_M_u32	771532259	771532259	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	210	210	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3126814720	3126814720	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	55	55	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1942849536	1942849536	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	215	215	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	176924672	176924672	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	247	247	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3331966976	3331966976	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4230522880	4230522880	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	220	220	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3466987520	3466987520	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	48	48	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2862884864	2862884864	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	34	34	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1198180352	1198180352	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	229	229	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3180488704	3180488704	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1719699456	1719699456	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	201	201	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2898176000	2898176000	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	883636224	883636224	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	429.327606	429.327606	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	173.7034	173.7034	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	307.857513	307.857513	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	43671	43671	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	771532259	771532259	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-82.1540985	-82.1540985 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.287 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1970600704
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	34301
AASNodeAbsentTimer_mS_M_u32	2000464640
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	7315
ANGLEVOLANTSigValidCount_Cnt_M_u16	18867
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	21726
AngleVolantMsgTimer_mS_M_u32	1970600704
AngleVolantValidCount_Cnt_M_u16	21906
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	4159662848
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3619678976
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1906318080
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3096304384
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	45158
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1875024640
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	42932
CAVNodeAbsentTimer_mS_M_u32	436980480
CDD_SrlComVehSpd_Kph_G_f32	248.413803
CMM388NTCEnableTimer_mS_M_u32	4149545728
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1889127168
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	39623
CMMNodeAbsentTimer_mS_M_u32	1786764032
CONSANGLECPKSigInvalidCount_Cnt_M_u16	23426
CONSANGLECPKSigValidCount_Cnt_M_u16	33329
CONSANGLECPK_Cnt_M_u16	6904
CONSANGLECPK_HwDeg_M_f32	719.476624
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	6904
CPKVehicleSpeedMsgTimer_mS_M_u32	1121975040
CPKVehicleSpeedValidCount_Cnt_M_u16	17083
CityParkInputConsistentCount_Cnt_M_u16	22598
CityParkInputInvalidCount_Cnt_M_u16	64228
CityParkInputMsgTimer_mS_M_u32	3126814720
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	653306624
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	22193

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3447081728
ComputerRazGCTSigValidCount_Cnt_M_u16	53311
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	1072
DMDFCTCPKSigValidCount_Cnt_M_u16	28631
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	237
DMDRELAXECPKSigValidCount_Cnt_M_u16	40333
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	38755
DateInvalidTimer_mS_M_u32	3619678976
DiagMuxOnAbsentTimer_mS_M_u32	218741504
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3096304384
ESPNTCEnableTimer_mS_M_u32	1553050368
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	33554
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	79
EffacDefaultDiagTimer_mS_M_u32[1]	699
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	977
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2784795392
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	47881
EtatMTSigValidCount_Cnt_M_u16	23684
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	52700
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	58379
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	2149
ISDAT4V2BSI552MsgTimer_mS_M_u32	959699712
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	52602
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	15325
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	23684
ISDATBSI3F2MsgTimer_mS_M_u32	2460990208
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	35349
ISDATBSI412MsgLenValidCount_Cnt_M_u16	29288
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	47881
ISDATBSI412MsgTimer_mS_M_u32	2031811328
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	51323
ISDATBSI432MsgLenValidCount_Cnt_M_u16	20422
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	12969
ISDATDIRASentFltAcc_Cnt_M_u16	14509
ISDATDIRASentTimer_mS_M_u32	1121975040
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	45342
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	21906
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	3971
ISDYN2CMMMsgTimer_mS_M_u32	4110658304
ISDYNAASChkSumInvalidCount_Cnt_M_u16	26199
ISDYNAASChkSumValidCount_Cnt_M_u16	50966
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	57061
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	31163
ISDYNAASMsgLenValidCount_Cnt_M_u16	13138
ISDYNAASMsgTimeValidCount_Cnt_M_u16	26199
ISDYNAASMsgTimer_mS_M_u32	2845903616
ISDYNABRChkSumInvalidCount_Cnt_M_u16	6188
ISDYNABRChkSumValidCount_Cnt_M_u16	8244
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	29738
ISDYNABRMsgCountValidCount_Cnt_M_u16	40233
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	10325
ISDYNABRMsgLenValidCount_Cnt_M_u16	22340
ISDYNABRMsgTimeValidCount_Cnt_M_u16	6904
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	6238
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	15098
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	23684
ISDYNCMM208MsgTimer_mS_M_u32	1495821056
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	6238
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	15098
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	27704

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3832187648
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	63784
ISDYNVOLChkSumValidCount_Cnt_M_u16	12375
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	41174
ISDYNVOLMsgCountValidCount_Cnt_M_u16	23805
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	12351
ISDYNVOLMsgLenValidCount_Cnt_M_u16	846
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	39623
ISDYNVOLMsgTimer_mS_M_u32	2613201664
IgnOnTimer_mS_M_u32	706644736
IgnTimeOff_Sec_M_u32	1921822757
ManVehSpd_Kph_M_f32	628.858826
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	163
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	237
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3399334656
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	57
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3419609856
PrevISDATBSI412MsgDLCError_Cnt_M_u08	123
PrevISDATBSI412MsgRxTime_MSec_M_u32	1656802048
PrevISDATBSI432MsgDLCError_Cnt_M_u08	182
PrevISDATBSI432MsgRxTime_MSec_M_u32	477473536
PrevISDATDIRAMsgTxTime_MSec_M_u32	2747583232
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	190
PrevISDYN2CMMMsgRxTime_MSec_M_u32	191978240
PrevISDYNAASMsgDLCError_Cnt_M_u08	211
PrevISDYNAASMsgRxTime_MSec_M_u32	434653952
PrevISDYNABRMsgDLCError_Cnt_M_u08	88
PrevISDYNABRMsgRxTime_MSec_M_u32	1572244224
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	21
PrevISDYNCMM208MsgRxTime_MSec_M_u32	916540160
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	106
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1983687424
PrevISDYNVOLMsgDLCError_Cnt_M_u08	7
PrevISDYNVOLMsgRxTime_MSec_M_u32	2620508928
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1270938368
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	538.09137
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	37985
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	7800
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	34062
VitesseVehicleBVRampValidCount_Cnt_M_u16	9957
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	36032
VitesseVehicleBVSigValidCount_Cnt_M_u16	29088
VitesseVehicleBV_Kph_M_f32	564.017578
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	27704
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	41519
VitesseVehiculeRoues_Kph_M_f32	175.656494
k_AASNTCEnableTimeout_mS_u16	48035
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	27441
k_AASNodeTimeout_mS_u16	40312
k_ABSNodeTimeout_mS_u16	46121
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	39002
k_ANGLEVOLANTSigValidThresh_Cnt_u16	39141
k_AngleVolantInvalidThresh_Cnt_u16	52768
k_AngleVolantValidThresh_Cnt_u16	64228
k_BSI552MsgTimeout_mS_u16	16170
k_BSINTCEnableTimeout_mS_u16	11283
k_BSINodeAbsentDiag_Cnt_str.Threshold	32530
k_BSINodeAbsentDiag_Cnt_str.PStep	3170
k_BSINodeAbsentDiag_Cnt_str.NStep	43974
k_BSINodeAbsentTimeout_mS_u16	37494
k_BSINodeTimeout_mS_u16	12969
k_BattOvHi_Volt_f32	23.6956005
k_BattOvLo_Volt_f32	27.6898994
k_BattUvHi_Volt_f32	31.0538006
k_BattUvLo_Volt_f32	16.3922997
k_CAVNTCEnableTimeout_mS_u16	18722
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	6490
k_CAVNodeTimeout_mS_u16	26062
k_CMM388MsgTimeout_mS_u16	17661
k_CMM388NTCEnableTimeout_mS_u16	46153
k_CMMNTCEnableTimeout_mS_u16	48402
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	8059
k_CONSANGLECPKMax_HwDeg_f32	284.395691
k_CONSANGLECPKMin_HwDeg_f32	-131.045593
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	43832
k_CONSANGLECPKSigValidThresh_Cnt_u16	8495
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	36102
k_CPKVehicleSpeedValidThresh_Cnt_u16	13532
k_CityParkInputInvalidThresh_Cnt_u16	32314
k_CityParkInputValidThresh_Cnt_u16	22598
k_ComputerRazGCTSigValidThresh_Cnt_u16	8680
k_CptTemporelSigValidThresh_Cnt_u16	42699
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	59221
k_DMDFCTCPKSigValidThresh_Cnt_u16	22084
k_DMDFCTCPKValidCount_Cnt_u16	33230
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	3971
k_DMDRELAXECPKSigValidThresh_Cnt_u16	25450
k_DMDRelaxeConsistentThresh_Cnt_u16	25848
k_DateValidThresh_Cnt_u16	2149
k_DefaultVehSpd_Kph_f32	195.338303
k_DiagMuxOnAbsentTimeout_mS_u16	43190
k_EMNodeTimeout_mS_u16	12355
k_ESPNTCEnableTimeout_mS_u16	23552
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	58339
k_EtatMTSigInvalidThresh_Cnt_u16	53447
k_EtatMTSigValidThresh_Cnt_u16	42767
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	2861
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	38664
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	58099
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	23035
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	55070
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	30153
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	52348
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	647
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	13871
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	40844
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	55936
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	5796
k_ISDATDIRASentDiag_Cnt_str.Threshold	42873

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	21557
k_ISDATDIRASentDiag_Cnt_str.NStep	16998
k_ISDATDIRASentTimeout_mS_u16	47224
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	23773
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	21726
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	32028
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	22316
k_ISDYNAASChkSumValidThresh_Cnt_u16	40756
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	13098
k_ISDYNAASMsgCountValidThresh_Cnt_u16	39977
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	63200
k_ISDYNAASMsgLenValidThresh_Cnt_u16	22572
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	37709
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	36091
k_ISDYNABRChkSumValidThresh_Cnt_u16	3178
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	28518
k_ISDYNABRMsgCountValidThresh_Cnt_u16	9414
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	6599
k_ISDYNABRMsgLenValidThresh_Cnt_u16	16914
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	30017
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	28437
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	48898
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	44403
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	56211
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	18611
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	35964
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	48244
k_ISDYNVOLChkSumValidThresh_Cnt_u16	65031
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	3315
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	24040
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	6229
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	23248
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	55587
k_IgnOnTimeout_mS_u16	24768
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	251.440399
k_PowerCutVehSpdLowThresh_Kph_f32	157.791901
k_PowerCutVehSpdLowTimeout_mS_u16	55455
k_VBattMaxAAS_Volt_f32	21.8934994
k_VBattMaxBSI_Volt_f32	23.3794994
k_VBattMaxCAV_Volt_f32	29.6854992
k_VBattMaxCMM388_Volt_f32	0.842299998
k_VBattMaxCMM_Volt_f32	5.8599
k_VBattMaxESP_Volt_f32	22.6028004
k_VBattMinAAS_Volt_f32	5.29239988
k_VBattMinBSI_Volt_f32	22.6028004
k_VBattMinCAV_Volt_f32	4.5704999
k_VBattMinCMM388_Volt_f32	3.45420003
k_VBattMinCMM_Volt_f32	14.8064003
k_VBattMinESP_Volt_f32	5.8599
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	21583
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	65490
k_VitesseVehicleBVRampValidThresh_Cnt_u16	57302
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	12119
k_VitesseVehicleBVSigValidThresh_Cnt_u16	15499
k_VitesseVehicleBVSpeedPassThresh_kph_f32	298.52179
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	59060
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	39179
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3619678976
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65109
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3632743680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	106
target_SrlComInput_Per1_Batt_Volt_f32.value	3.50600004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1570216704
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	144
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.640858769
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	116
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3022031616
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1750477568
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3298544384
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4042353408
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	358025984
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	25
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1506585344
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	156
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3864152832
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	129
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	141
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	149
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	201
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	218
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4068371200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	47
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	82
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	158
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	232
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	914852608
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	473770752
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1778567936
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	118
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	166
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	186
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	187
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4168948480
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2803
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.341520965
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	650669
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	190.917206
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	33619

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	21728	21728	✔
AngleVolantMsgTimer_mS_M_u32	3632743680	3632743680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	32530	32530	✔
BSINodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	6904	6904	✔
CONSANGLECPK_HwDeg_M_f32	719.476624	719.476624 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	6904	6904	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1121975040	1121975040	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	17083	17083	✔
CityParkInputConsistentCount_Cnt_M_u16	22598	22598	✔
CityParkInputInvalidCount_Cnt_M_u16	64228	64228	✔
CityParkInputMsgTimer_mS_M_u32	3632743680	3632743680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3632743680	3632743680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3632743680	3632743680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3632743680	3632743680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3632743680	3632743680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3632743680	3632743680	✔
ESPNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3632743680	3632743680	✔
EffacDefaultDiagTimer_mS_M_u32[1]	699	699	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3632743680	3632743680	✔
ElecIntTimer_mS_M_u32[1]	977	977	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3632743680	3632743680	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3632743680	3632743680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3632743680	3632743680	✔
IgnOnTimer_mS_M_u32	3632743680	3632743680	✔
IgnTimeOff_Sec_M_u32	1921822757	1921822757	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	116	116	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3022031616	3022031616	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	131	131	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1750477568	1750477568	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3298544384	3298544384	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	134	134	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4042353408	4042353408	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2747583232	2747583232	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	25	25	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1506585344	1506585344	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	156	156	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3864152832	3864152832	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	135	135	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4068371200	4068371200	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	198	198	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	914852608	914852608	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	473770752	473770752	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	219	219	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1778567936	1778567936	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4168948480	4168948480	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	538.09137	538.09137	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	564.017578	564.017578	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	175.656494	175.656494	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	6904	6904	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1921822757	1921822757	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	719.476624	719.476624 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	195.338303	195.338303	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.288 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2230047232
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	5458
AASNodeAbsentTimer_mS_M_u32	2052375040
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	52110
ANGLEVOLANTSigValidCount_Cnt_M_u16	64753
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	27823
AngleVolantMsgTimer_mS_M_u32	2230047232
AngleVolantValidCount_Cnt_M_u16	16660
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	859603456
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1976238592
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2766828032
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3072406016
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	7189
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1417867776
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	62636
CAVNodeAbsentTimer_mS_M_u32	912744960
CDD_SrlComVehSpd_Kph_G_f32	256.041107
CMM388NTCEnableTimer_mS_M_u32	1401659904
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3938279936
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	45365
CMMNodeAbsentTimer_mS_M_u32	3914019328
CONSANGLECPKSigInvalidCount_Cnt_M_u16	14786
CONSANGLECPKSigValidCount_Cnt_M_u16	48757
CONSANGLECPK_Cnt_M_u16	53280
CONSANGLECPK_HwDeg_M_f32	243.254196
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	53280
CPKVehicleSpeedMsgTimer_mS_M_u32	2292896256
CPKVehicleSpeedValidCount_Cnt_M_u16	52831

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	2296
CityParkInputInvalidCount_Cnt_M_u16	27165
CityParkInputMsgTimer_mS_M_u32	3022031616
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	993575424
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	29494
ComputerRazGCTSigInvalidTimer_mS_M_u32	3861373440
ComputerRazGCTSigValidCount_Cnt_M_u16	50445
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	32313
DMDFCTCPKSigValidCount_Cnt_M_u16	5124
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	1664
DMDRELAXECPKSigValidCount_Cnt_M_u16	59747
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	18975
DateInvalidTimer_mS_M_u32	1976238592
DiagMuxOnAbsentTimer_mS_M_u32	19763712
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3072406016
ESPNTCEnableTimer_mS_M_u32	1582678528
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	24852
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	5
EffacDefaultDiagTimer_mS_M_u32[1]	155
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	19
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	433385984
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	10606
EtatMTSigValidCount_Cnt_M_u16	28093
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	51892
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	32999
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	602
ISDAT4V2BSI552MsgTimer_mS_M_u32	1294938624
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	19868
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	52018
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	28093
ISDATBSI3F2MsgTimer_mS_M_u32	2285605376
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	38090
ISDATBSI412MsgLenValidCount_Cnt_M_u16	25744
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	10606
ISDATBSI412MsgTimer_mS_M_u32	2449068544
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	63513
ISDATBSI432MsgLenValidCount_Cnt_M_u16	51960
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	26573
ISDATDIRASentFltAcc_Cnt_M_u16	26049
ISDATDIRASentTimer_mS_M_u32	2292896256
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	9646
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	16660
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	26688
ISDYN2CMMMsgTimer_mS_M_u32	3707748864
ISDYNAASChkSumInvalidCount_Cnt_M_u16	23620
ISDYNAASChkSumValidCount_Cnt_M_u16	29382
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	45339
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	23191
ISDYNAASMsgLenValidCount_Cnt_M_u16	50834
ISDYNAASMsgTimeValidCount_Cnt_M_u16	23620
ISDYNAASMsgTimer_mS_M_u32	1822925312
ISDYNABRChkSumInvalidCount_Cnt_M_u16	54340
ISDYNABRChkSumValidCount_Cnt_M_u16	5358
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	16075
ISDYNABRMsgCountValidCount_Cnt_M_u16	64653
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	57161
ISDYNABRMsgLenValidCount_Cnt_M_u16	19260
ISDYNABRMsgTimeValidCount_Cnt_M_u16	53280

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	62845
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	34425
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	28093
ISDYNCMM208MsgTimer_mS_M_u32	865174016
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	62845
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	34425
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	5410
ISDYNCMM388MsgTimer_mS_M_u32	3259703808
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	30928
ISDYNVOLChkSumValidCount_Cnt_M_u16	52227
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	49223
ISDYNVOLMsgCountValidCount_Cnt_M_u16	25746
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	19853
ISDYNVOLMsgLenValidCount_Cnt_M_u16	19743
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	45365
ISDYNVOLMsgTimer_mS_M_u32	2873352704
IgnOnTimer_mS_M_u32	3241091584
IgnTimeOff_Sec_M_u32	2045481027
ManVehSpd_Kph_M_f32	44.7350006
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	164
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	166
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	410096128
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	239
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	575762944
PrevISDATBSI412MsgDLCError_Cnt_M_u08	4
PrevISDATBSI412MsgRxTime_MSec_M_u32	1883791872
PrevISDATBSI432MsgDLCError_Cnt_M_u08	111
PrevISDATBSI432MsgRxTime_MSec_M_u32	2930360832
PrevISDATDIRAMsgTxTime_MSec_M_u32	3174851072
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	105
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2893459968
PrevISDYNAASMsgDLCError_Cnt_M_u08	101
PrevISDYNAASMsgRxTime_MSec_M_u32	1221714432
PrevISDYNABRMsgDLCError_Cnt_M_u08	125
PrevISDYNABRMsgRxTime_MSec_M_u32	2254905856
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	102
PrevISDYNCMM208MsgRxTime_MSec_M_u32	380035584
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	37
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2102706688
PrevISDYNVOLMsgDLCError_Cnt_M_u08	35
PrevISDYNVOLMsgRxTime_MSec_M_u32	3354747392
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	839373312
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	417.667511
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	8869
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	7456
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	17566
VitesseVehicleBVRampValidCount_Cnt_M_u16	63449
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	28423

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	31018
VitesseVehicleBV_Kph_M_f32	593.707825
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	5410
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	35836
VitesseVehiculeRoues_Kph_M_f32	403.808014
k_AASNTCEnableTimeout_mS_u16	23071
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	15415
k_AASNodeTimeout_mS_u16	40992
k_ABSNodeTimeout_mS_u16	37454
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	50300
k_ANGLEVOLANTSigValidThresh_Cnt_u16	11163
k_AngleVolantInvalidThresh_Cnt_u16	14314
k_AngleVolantValidThresh_Cnt_u16	27165
k_BSI552MsgTimeout_mS_u16	24843
k_BSINTCEnableTimeout_mS_u16	11601
k_BSINodeAbsentDiag_Cnt_str.Threshold	42192
k_BSINodeAbsentDiag_Cnt_str.PStep	8993
k_BSINodeAbsentDiag_Cnt_str.NStep	25637
k_BSINodeAbsentTimeout_mS_u16	5095
k_BSINodeTimeout_mS_u16	26573
k_BattOvHi_Volt_f32	17.9761009
k_BattOvLo_Volt_f32	10.7856998
k_BattUvHi_Volt_f32	7.89870024
k_BattUvLo_Volt_f32	28.6191006
k_CAVNTCEnableTimeout_mS_u16	63331
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	47034
k_CAVNodeTimeout_mS_u16	19166
k_CMM388MsgTimeout_mS_u16	55378
k_CMM388NTCEnableTimeout_mS_u16	47726
k_CMMNTCEnableTimeout_mS_u16	57044
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	17432
k_CONSANGLECPKMax_HwDeg_f32	181.918594
k_CONSANGLECPKMin_HwDeg_f32	-737.62561
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	22562
k_CONSANGLECPKSigValidThresh_Cnt_u16	3836
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	35190
k_CPKVehicleSpeedValidThresh_Cnt_u16	28789
k_CityParkInputInvalidThresh_Cnt_u16	23066
k_CityParkInputValidThresh_Cnt_u16	2296
k_ComputerRazGCTSigValidThresh_Cnt_u16	34898
k_CptTemporelSigValidThresh_Cnt_u16	49768
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	41545
k_DMDFCTCPKSigValidThresh_Cnt_u16	20028
k_DMDFCTCPKValidCount_Cnt_u16	18397
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	26688
k_DMDRELAXECPKSigValidThresh_Cnt_u16	17739
k_DMDRelaxeConsistentThresh_Cnt_u16	63649
k_DateValidThresh_Cnt_u16	602
k_DefaultVehSpd_Kph_f32	169.7771
k_DiagMuxOnAbsentTimeout_mS_u16	40678
k_EMNodeTimeout_mS_u16	65407
k_ESPNTCEnableTimeout_mS_u16	1992
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	38624
k_EtatMTSigInvalidThresh_Cnt_u16	54899
k_EtatMTSigValidThresh_Cnt_u16	44125
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	27393
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	28719
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	23793
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	60441
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	15727
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	41390

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	12310
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	63157
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	32509
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	37476
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	59978
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	15388
k_ISDATDIRASentDiag_Cnt_str.Threshold	14146
k_ISDATDIRASentDiag_Cnt_str.PStep	16332
k_ISDATDIRASentDiag_Cnt_str.NStep	21498
k_ISDATDIRASentTimeout_mS_u16	9056
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	36209
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	27823
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	5236
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	5956
k_ISDYNAASChkSumValidThresh_Cnt_u16	38894
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	459
k_ISDYNAASMsgCountValidThresh_Cnt_u16	65421
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	2088
k_ISDYNAASMsgLenValidThresh_Cnt_u16	16388
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	56419
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	51543
k_ISDYNABRChkSumValidThresh_Cnt_u16	17354
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	57109
k_ISDYNABRMsgCountValidThresh_Cnt_u16	30648
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	13365
k_ISDYNABRMsgLenValidThresh_Cnt_u16	9236
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	12871
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	25225
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	59907
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	7215
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	36494
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	65521
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	5461
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	14765
k_ISDYNVOLChkSumValidThresh_Cnt_u16	64947
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	34673
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	11218
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	16778
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	41689
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	2080
k_IgnOnTimeout_mS_u16	31945
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	145.970993
k_PowerCutVehSpdLowThresh_Kph_f32	146.916306
k_PowerCutVehSpdLowTimeout_mS_u16	62251
k_VBattMaxAAS_Volt_f32	19.6287003
k_VBattMaxBSI_Volt_f32	32
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	32
k_VBattMaxCMM_Volt_f32	11.1396999
k_VBattMaxESP_Volt_f32	21.4645996
k_VBattMinAAS_Volt_f32	6.62249994
k_VBattMinBSI_Volt_f32	21.4645996
k_VBattMinCAV_Volt_f32	5.40430021
k_VBattMinCMM388_Volt_f32	1.08319998
k_VBattMinCMM_Volt_f32	12.2405996
k_VBattMinESP_Volt_f32	11.1396999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	61211
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	13650
k_VitesseVehicleBVRampValidThresh_Cnt_u16	839
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	52995
k_VitesseVehicleBVSigValidThresh_Cnt_u16	45097
k_VitesseVehicleBVSpeedPassThresh_kph_f32	149.943298
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	14252
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	47463
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1976238592
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	61417
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1499264000
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	37
target_SrlComInput_Per1_Batt_Volt_f32.value	20.8309002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	520352256
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	254
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.126988187
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	82
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2871599616
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3976741376
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	248
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1991729664
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3493233152
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2173018624
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	312787456
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	17
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	194241024
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	34
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	52
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	116
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	172
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	186
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	228
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1066369536
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	60
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	126
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	185
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2146705920
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	214
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	760431104
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	54
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3800195584
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	88
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	151
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	154
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3293803008
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	562
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.782521904
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	171232
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	131.790604
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	40399

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1499264000	1499264000	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
CDD_SrlComVehSpd_Kph_G_f32	44.7350006	44.7350006	✔
CMM388NTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	53280	53280	✔
CONSANGLECPK_HwDeg_M_f32	243.254196	243.254196 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1499264000	1499264000	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1499264000	1499264000	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1499264000	1499264000	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1499264000	1499264000	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1499264000	1499264000	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1499264000	1499264000	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1499264000	1499264000	✔
ESPNTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	5	5	✔
EffacDefaultDiagTimer_mS_M_u32[1]	155	155	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	20	20	✔
ElecIntTimer_mS_M_u32[1]	19	19	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1499264000	1499264000	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	602	602	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	28093	28093	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	10606	10606	✔
ISDATBSI412MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	26573	26573	✔
ISDATBSI432MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1499264000	1499264000	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	26688	26688	✔
ISDYN2CMMMsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	23620	23620	✔
ISDYNAASMsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	53280	53280	✔
ISDYNABRMsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	28093	28093	✔
ISDYNCMM208MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	5410	5410	✔
ISDYNCMM388MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	45365	45365	✔
ISDYNVOLMsgTimer_mS_M_u32	1499264000	1499264000	✔
IgnOnTimer_mS_M_u32	3241091584	3241091584	✔
IgnTimeOff_Sec_M_u32	2045481027	2045481027	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	82	82	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2871599616	2871599616	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	99	99	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3976741376	3976741376	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	248	248	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1991729664	1991729664	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	152	152	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3493233152	3493233152	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3174851072	3174851072	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	29	29	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	312787456	312787456	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	17	17	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	194241024	194241024	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	9	9	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1066369536	1066369536	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	185	185	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2146705920	2146705920	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	214	214	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	760431104	760431104	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	54	54	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3800195584	3800195584	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3293803008	3293803008	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	417.667511	417.667511	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	593.707825	593.707825	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	403.808014	403.808014	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	53280	53280	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2045481027	2045481027	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	243.254196	243.254196 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.289 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1654869248
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	27503
AASNodeAbsentTimer_mS_M_u32	2452126976
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	55994
ANGLEVOLANTSigValidCount_Cnt_M_u16	7250
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	6488
AngleVolantMsgTimer_mS_M_u32	1654869248
AngleVolantValidCount_Cnt_M_u16	6313
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3060874496
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1220918528
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3307695360
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3649252608
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	50469
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3093163264
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	65503
CAVNodeAbsentTimer_mS_M_u32	1886428416
CDD_SrlComVehSpd_Kph_G_f32	579.556519
CMM388NTCEnableTimer_mS_M_u32	4194557184
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	728669440
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	2309
CMMNodeAbsentTimer_mS_M_u32	1795501312
CONSANGLECPKSigInvalidCount_Cnt_M_u16	3871
CONSANGLECPKSigValidCount_Cnt_M_u16	38599
CONSANGLECPK_Cnt_M_u16	52678
CONSANGLECPK_HwDeg_M_f32	-699.399902
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	52678
CPKVehicleSpeedMsgTimer_mS_M_u32	325471488
CPKVehicleSpeedValidCount_Cnt_M_u16	37487
CityParkInputConsistentCount_Cnt_M_u16	20733
CityParkInputInvalidCount_Cnt_M_u16	21133
CityParkInputMsgTimer_mS_M_u32	2871599616
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3749477632
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	57795

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	53419264
ComputerRazGCTSigValidCount_Cnt_M_u16	45246
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	34361
DMDFCTCPKSigValidCount_Cnt_M_u16	15002
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	29156
DMDRELAXECPKSigValidCount_Cnt_M_u16	40700
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	37384
DateInvalidTimer_mS_M_u32	1220918528
DiagMuxOnAbsentTimer_mS_M_u32	618532096
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3649252608
ESPNTCEnableTimer_mS_M_u32	707099904
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	48938
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1111
EffacDefaultDiagTimer_mS_M_u32[1]	2222
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	555
ElecIntTimer_mS_M_u32[1]	5555
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	812117248
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	5466
EtatMTSigValidCount_Cnt_M_u16	52782
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	42057
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	38769
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	18328
ISDAT4V2BSI552MsgTimer_mS_M_u32	3478727936
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	38481
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	49998
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	52782
ISDATBSI3F2MsgTimer_mS_M_u32	1202982144
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	18887
ISDATBSI412MsgLenValidCount_Cnt_M_u16	16435
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	5466
ISDATBSI412MsgTimer_mS_M_u32	4084813056
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	50265
ISDATBSI432MsgLenValidCount_Cnt_M_u16	4478
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	27260
ISDATDIRASentFltAcc_Cnt_M_u16	16544
ISDATDIRASentTimer_mS_M_u32	325471488
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	34076
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	6313
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	42020
ISDYN2CMMMsgTimer_mS_M_u32	3592912128
ISDYNAASChkSumInvalidCount_Cnt_M_u16	56985
ISDYNAASChkSumValidCount_Cnt_M_u16	61650
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	42132
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	14878
ISDYNAASMsgLenValidCount_Cnt_M_u16	11247
ISDYNAASMsgTimeValidCount_Cnt_M_u16	56985
ISDYNAASMsgTimer_mS_M_u32	514841856
ISDYNABRChkSumInvalidCount_Cnt_M_u16	52762
ISDYNABRChkSumValidCount_Cnt_M_u16	474
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	4868
ISDYNABRMsgCountValidCount_Cnt_M_u16	12157
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	64138
ISDYNABRMsgLenValidCount_Cnt_M_u16	52338
ISDYNABRMsgTimeValidCount_Cnt_M_u16	52678
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	3997
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	54891
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	52782
ISDYNCMM208MsgTimer_mS_M_u32	1232223488
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	3997
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	54891
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	21631

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	197483776
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	2549
ISDYNVOLChkSumValidCount_Cnt_M_u16	9757
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	30735
ISDYNVOLMsgCountValidCount_Cnt_M_u16	240
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	7615
ISDYNVOLMsgLenValidCount_Cnt_M_u16	46280
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	2309
ISDYNVOLMsgTimer_mS_M_u32	601562368
IgnOnTimer_mS_M_u32	2669239552
IgnTimeOff_Sec_M_u32	1103537927
ManVehSpd_Kph_M_f32	392.408905
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	165
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	101
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4010937600
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	255
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2834459904
PrevISDATBSI412MsgDLCError_Cnt_M_u08	47
PrevISDATBSI412MsgRxTime_MSec_M_u32	2261622016
PrevISDATBSI432MsgDLCError_Cnt_M_u08	156
PrevISDATBSI432MsgRxTime_MSec_M_u32	2301197568
PrevISDATDIRAMsgTxTime_MSec_M_u32	1878105344
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	118
PrevISDYN2CMMMsgRxTime_MSec_M_u32	797093120
PrevISDYNAASMsgDLCError_Cnt_M_u08	208
PrevISDYNAASMsgRxTime_MSec_M_u32	53550336
PrevISDYNABRMsgDLCError_Cnt_M_u08	145
PrevISDYNABRMsgRxTime_MSec_M_u32	795958528
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	120
PrevISDYNCMM208MsgRxTime_MSec_M_u32	766647552
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	1
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2301132032
PrevISDYNVOLMsgDLCError_Cnt_M_u08	138
PrevISDYNVOLMsgRxTime_MSec_M_u32	1942396160
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3410971904
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	284.400787
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	39412
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	57413
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	22537
VitesseVehicleBVRampValidCount_Cnt_M_u16	29722
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	5199
VitesseVehicleBVSigValidCount_Cnt_M_u16	52135
VitesseVehicleBV_Kph_M_f32	307.502808
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	21631
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	42416
VitesseVehiculeRoues_Kph_M_f32	347.771698
k_AASNTCEnableTimeout_mS_u16	60361
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	29504
k_AASNodeTimeout_mS_u16	22341
k_ABSNodeTimeout_mS_u16	56826
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	43824
k_ANGLEVOLANTSigValidThresh_Cnt_u16	15253
k_AngleVolantInvalidThresh_Cnt_u16	4776
k_AngleVolantValidThresh_Cnt_u16	21133
k_BSI552MsgTimeout_mS_u16	8835
k_BSINTCEnableTimeout_mS_u16	1201
k_BSINodeAbsentDiag_Cnt_str.Threshold	25892
k_BSINodeAbsentDiag_Cnt_str.PStep	41075
k_BSINodeAbsentDiag_Cnt_str.NStep	25509
k_BSINodeAbsentTimeout_mS_u16	944
k_BSINodeTimeout_mS_u16	27260
k_BattOvHi_Volt_f32	24.3575993
k_BattOvLo_Volt_f32	31.5
k_BattUvHi_Volt_f32	18.5984001
k_BattUvLo_Volt_f32	26.2297993
k_CAVNTCEnableTimeout_mS_u16	17083
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	28341
k_CAVNodeTimeout_mS_u16	19403
k_CMM388MsgTimeout_mS_u16	8815
k_CMM388NTCEnableTimeout_mS_u16	60443
k_CMMNTCEnableTimeout_mS_u16	49833
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	60764
k_CONSANGLECPKMax_HwDeg_f32	745.949402
k_CONSANGLECPKMin_HwDeg_f32	-134.813507
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	35711
k_CONSANGLECPKSigValidThresh_Cnt_u16	7344
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	29507
k_CPKVehicleSpeedValidThresh_Cnt_u16	8902
k_CityParkInputInvalidThresh_Cnt_u16	5272
k_CityParkInputValidThresh_Cnt_u16	20733
k_ComputerRazGCTSigValidThresh_Cnt_u16	15919
k_CptTemporelSigValidThresh_Cnt_u16	13740
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	45450
k_DMDFCTCPKSigValidThresh_Cnt_u16	50034
k_DMDFCTCPKValidCount_Cnt_u16	25037
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	42020
k_DMDRELAXECPKSigValidThresh_Cnt_u16	33477
k_DMDRelaxeConsistentThresh_Cnt_u16	16579
k_DateValidThresh_Cnt_u16	18328
k_DefaultVehSpd_Kph_f32	200.570007
k_DiagMuxOnAbsentTimeout_mS_u16	63860
k_EMNodeTimeout_mS_u16	61928
k_ESPNTCEnableTimeout_mS_u16	13963
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	5380
k_EtatMTSigInvalidThresh_Cnt_u16	17293
k_EtatMTSigValidThresh_Cnt_u16	46989
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	47778
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	45271
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	30994
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	61146
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	41111
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	45851
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	20578
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	49735
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	49069
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	38650
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	29959
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	27856
k_ISDATDIRASentDiag_Cnt_str.Threshold	625

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	48276
k_ISDATDIRASentDiag_Cnt_str.NStep	58314
k_ISDATDIRASentTimeout_mS_u16	20678
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	3281
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	6488
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	49287
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	1306
k_ISDYNAASChkSumValidThresh_Cnt_u16	30938
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	51716
k_ISDYNAASMsgCountValidThresh_Cnt_u16	9853
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	49774
k_ISDYNAASMsgLenValidThresh_Cnt_u16	1945
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	18749
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	62560
k_ISDYNABRChkSumValidThresh_Cnt_u16	39624
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	31781
k_ISDYNABRMsgCountValidThresh_Cnt_u16	34813
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	32773
k_ISDYNABRMsgLenValidThresh_Cnt_u16	30250
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	21584
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	27208
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	28188
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	57112
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	37306
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	4946
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	12517
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	42782
k_ISDYNVOLChkSumValidThresh_Cnt_u16	49354
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	19
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	19758
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	15622
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	40666
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	52806
k_IgnOnTimeout_mS_u16	19914
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	94.4885025
k_PowerCutVehSpdLowThresh_Kph_f32	163.652496
k_PowerCutVehSpdLowTimeout_mS_u16	20645
k_VBattMaxAAS_Volt_f32	2.97609997
k_VBattMaxBSI_Volt_f32	12.8697996
k_VBattMaxCAV_Volt_f32	23.2819004
k_VBattMaxCMM388_Volt_f32	15.9624996
k_VBattMaxCMM_Volt_f32	0.212799996
k_VBattMaxESP_Volt_f32	18.5769005
k_VBattMinAAS_Volt_f32	32
k_VBattMinBSI_Volt_f32	18.5769005
k_VBattMinCAV_Volt_f32	13.2294998
k_VBattMinCMM388_Volt_f32	16.2024994
k_VBattMinCMM_Volt_f32	12.0887003
k_VBattMinESP_Volt_f32	0.212799996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	4051
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	25328
k_VitesseVehicleBVRampValidThresh_Cnt_u16	44815
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	7453
k_VitesseVehicleBVSigValidThresh_Cnt_u16	24426
k_VitesseVehicleBVSpeedPassThresh_kph_f32	108.831802
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	14047
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	59248
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1220918528
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	37067
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2354571008
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	1
target_SrlComInput_Per1_Batt_Volt_f32.value	23.6200008
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2631593216
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	151
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.242991313
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1227578624
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1745747200
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	112
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4018183424
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	82
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1199783168
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3625311488
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	154696960
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	182
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1122704640
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	118
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	119
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	167
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2641902848
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	114
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	185
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	220
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	79
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3066715392
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	62
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2469199104
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2552208640
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	50
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	155
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1257008384
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1879
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.976594925
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	206807
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	212.279694
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	20598

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2354571008	2354571008	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2354571008	2354571008	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2354571008	2354571008	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2354571008	2354571008	✔
CDD_SrlComVehSpd_Kph_G_f32	392.408905	392.408905	✔
CMM388NTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2354571008	2354571008	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	52678	52678	✔
CONSANGLECPK_HwDeg_M_f32	-699.399902	-699.399902 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2354571008	2354571008	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2354571008	2354571008	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2354571008	2354571008	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2354571008	2354571008	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2354571008	2354571008	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2354571008	2354571008	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2354571008	2354571008	✔
ESPNTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2354571008	2354571008	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1111	1111	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2222	2222	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	555	555	✔
ElecIntTimer_mS_M_u32[1]	5555	5555	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2354571008	2354571008	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	18328	18328	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	52782	52782	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	5466	5466	✔
ISDATBSI412MsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	27260	27260	✔
ISDATBSI432MsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2354571008	2354571008	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	42020	42020	✔
ISDYN2CMMMsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	56985	56985	✔
ISDYNAASMsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	52678	52678	✔
ISDYNABRMsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	52782	52782	✔
ISDYNCMM208MsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	21631	21631	✔
ISDYNCMM388MsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	2309	2309	✔
ISDYNVOLMsgTimer_mS_M_u32	2354571008	2354571008	✔
IgnOnTimer_mS_M_u32	2669239552	2669239552	✔
IgnTimeOff_Sec_M_u32	1103537927	1103537927	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	152	152	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1227578624	1227578624	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	170	170	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1745747200	1745747200	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	112	112	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4018183424	4018183424	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	82	82	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1199783168	1199783168	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1878105344	1878105344	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	14	14	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	154696960	154696960	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	182	182	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1122704640	1122704640	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	166	166	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2641902848	2641902848	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	79	79	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3066715392	3066715392	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	62	62	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2469199104	2469199104	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2552208640	2552208640	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1257008384	1257008384	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	284.400787	284.400787	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	307.502808	307.502808	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	347.771698	347.771698	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	52678	52678	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1103537927	1103537927	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-699.399902	-699.399902 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	392.408905	392.408905	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.290 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	354999296
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	52419
AASNodeAbsentTimer_mS_M_u32	1465469952
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	51427
ANGLEVOLANTSigValidCount_Cnt_M_u16	33497
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	42760
AngleVolantMsgTimer_mS_M_u32	354999296
AngleVolantValidCount_Cnt_M_u16	13206
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	4252961792
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	948014080
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2786884608
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2282306560
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	30114
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3329817600
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	30706
CAVNodeAbsentTimer_mS_M_u32	2231430144
CDD_SrlComVehSpd_Kph_G_f32	169.647507
CMM388NTCEnableTimer_mS_M_u32	1162292224
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3423005696
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	41025
CMMNodeAbsentTimer_mS_M_u32	1535327232
CONSANGLECPKSigInvalidCount_Cnt_M_u16	44725
CONSANGLECPKSigValidCount_Cnt_M_u16	54907
CONSANGLECPK_Cnt_M_u16	60798
CONSANGLECPK_HwDeg_M_f32	559.463928
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	60798
CPKVehicleSpeedMsgTimer_mS_M_u32	3470777344
CPKVehicleSpeedValidCount_Cnt_M_u16	332
CityParkInputConsistentCount_Cnt_M_u16	55962
CityParkInputInvalidCount_Cnt_M_u16	26345
CityParkInputMsgTimer_mS_M_u32	1227578624
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3210562560
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	47559

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3871697920
ComputerRazGCTSigValidCount_Cnt_M_u16	65367
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	31717
DMDFCTCPKSigValidCount_Cnt_M_u16	64899
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	11109
DMDRELAXECPKSigValidCount_Cnt_M_u16	8923
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	2554
DateInvalidTimer_mS_M_u32	948014080
DiagMuxOnAbsentTimer_mS_M_u32	695770112
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2282306560
ESPNTCEnableTimer_mS_M_u32	3277999104
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	11411
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	65535
EffacDefaultDiagTimer_mS_M_u32[1]	95535
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	963
ElecIntTimer_mS_M_u32[1]	7852
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	106626048
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	7236
EtatMTSigValidCount_Cnt_M_u16	24710
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	5943
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	64637
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20105
ISDAT4V2BSI552MsgTimer_mS_M_u32	2122791936
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	53468
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	22694
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	24710
ISDATBSI3F2MsgTimer_mS_M_u32	2566298624
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	7037
ISDATBSI412MsgLenValidCount_Cnt_M_u16	1782
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	7236
ISDATBSI412MsgTimer_mS_M_u32	984013824
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	48709
ISDATBSI432MsgLenValidCount_Cnt_M_u16	34199
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	60443
ISDATDIRASentFltAcc_Cnt_M_u16	63919
ISDATDIRASentTimer_mS_M_u32	3470777344
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	40828
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	13206
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36388
ISDYN2CMMMsgTimer_mS_M_u32	0
ISDYNAASChkSumInvalidCount_Cnt_M_u16	39749
ISDYNAASChkSumValidCount_Cnt_M_u16	25435
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	64469
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	34101
ISDYNAASMsgLenValidCount_Cnt_M_u16	3715
ISDYNAASMsgTimeValidCount_Cnt_M_u16	39749
ISDYNAASMsgTimer_mS_M_u32	2269326336
ISDYNABRChkSumInvalidCount_Cnt_M_u16	50756
ISDYNABRChkSumValidCount_Cnt_M_u16	18882
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	27140
ISDYNABRMsgCountValidCount_Cnt_M_u16	4954
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	22644
ISDYNABRMsgLenValidCount_Cnt_M_u16	41338
ISDYNABRMsgTimeValidCount_Cnt_M_u16	60798
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	53802
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	4225
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	24710
ISDYNCMM208MsgTimer_mS_M_u32	2289830912
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	53802
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	4225
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	22548

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	4127370240
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	38451
ISDYNVOLChkSumValidCount_Cnt_M_u16	121
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	32355
ISDYNVOLMsgCountValidCount_Cnt_M_u16	33409
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	42196
ISDYNVOLMsgLenValidCount_Cnt_M_u16	7802
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	41025
ISDYNVOLMsgTimer_mS_M_u32	885091328
IgnOnTimer_mS_M_u32	2349247488
IgnTimeOff_Sec_M_u32	665497092
ManVehSpd_Kph_M_f32	568.928101
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	166
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	218
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2598149120
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	166
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3871046656
PrevISDATBSI412MsgDLCError_Cnt_M_u08	206
PrevISDATBSI412MsgRxTime_MSec_M_u32	4125748224
PrevISDATBSI432MsgDLCError_Cnt_M_u08	127
PrevISDATBSI432MsgRxTime_MSec_M_u32	3059108864
PrevISDATDIRAMsgTxTime_MSec_M_u32	3397250048
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	145
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3825908736
PrevISDYNAASMsgDLCError_Cnt_M_u08	152
PrevISDYNAASMsgRxTime_MSec_M_u32	1858038784
PrevISDYNABRMsgDLCError_Cnt_M_u08	62
PrevISDYNABRMsgRxTime_MSec_M_u32	989768704
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	167
PrevISDYNCMM208MsgRxTime_MSec_M_u32	859597824
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	182
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1918454784
PrevISDYNVOLMsgDLCError_Cnt_M_u08	145
PrevISDYNVOLMsgRxTime_MSec_M_u32	1392438272
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2334448640
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	485.944794
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	15795
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	51585
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	38772
VitesseVehicleBVRampValidCount_Cnt_M_u16	41474
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	45092
VitesseVehicleBVSigValidCount_Cnt_M_u16	2266
VitesseVehicleBV_Kph_M_f32	75.6496964
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	22548
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	17218
VitesseVehiculeRoues_Kph_M_f32	230.454605
k_AASNTCEnableTimeout_mS_u16	24437
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	16337
k_AASNodeTimeout_mS_u16	25729
k_ABSNodeTimeout_mS_u16	47266
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	9664
k_ANGLEVOLANTSigValidThresh_Cnt_u16	9042
k_AngleVolantInvalidThresh_Cnt_u16	43545
k_AngleVolantValidThresh_Cnt_u16	26345
k_BSI552MsgTimeout_mS_u16	55497
k_BSINTCEnableTimeout_mS_u16	23869
k_BSINodeAbsentDiag_Cnt_str.Threshold	42772
k_BSINodeAbsentDiag_Cnt_str.PStep	53865
k_BSINodeAbsentDiag_Cnt_str.NStep	62994
k_BSINodeAbsentTimeout_mS_u16	18432
k_BSINodeTimeout_mS_u16	60443
k_BattOvHi_Volt_f32	19.2632008
k_BattOvLo_Volt_f32	8.31459999
k_BattUvHi_Volt_f32	14.5144997
k_BattUvLo_Volt_f32	9.74279976
k_CAVNTCEnableTimeout_mS_u16	52831
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	880
k_CAVNodeTimeout_mS_u16	43185
k_CMM388MsgTimeout_mS_u16	42947
k_CMM388NTCEnableTimeout_mS_u16	64191
k_CMMNTCEnableTimeout_mS_u16	43988
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	7230
k_CONSANGLECPKMax_HwDeg_f32	187.746506
k_CONSANGLECPKMin_HwDeg_f32	-293.778198
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	45844
k_CONSANGLECPKSigValidThresh_Cnt_u16	56898
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	34951
k_CPKVehicleSpeedValidThresh_Cnt_u16	19584
k_CityParkInputInvalidThresh_Cnt_u16	27338
k_CityParkInputValidThresh_Cnt_u16	55962
k_ComputerRazGCTSigValidThresh_Cnt_u16	53570
k_CptTemporelSigValidThresh_Cnt_u16	63884
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	13172
k_DMDFCTCPKSigValidThresh_Cnt_u16	48250
k_DMDFCTCPKValidCount_Cnt_u16	16298
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	36388
k_DMDRELAXECPKSigValidThresh_Cnt_u16	37122
k_DMDRelaxeConsistentThresh_Cnt_u16	53000
k_DateValidThresh_Cnt_u16	20105
k_DefaultVehSpd_Kph_f32	101.863197
k_DiagMuxOnAbsentTimeout_mS_u16	41588
k_EMNodeTimeout_mS_u16	27226
k_ESPNTCEnableTimeout_mS_u16	33774
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	17734
k_EtatMTSigInvalidThresh_Cnt_u16	61931
k_EtatMTSigValidThresh_Cnt_u16	46249
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	61034
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	64140
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	63067
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	11073
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	9419
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	12161
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	32298
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	55100
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	7241
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	25058
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	5756
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	26465
k_ISDATDIRASentDiag_Cnt_str.Threshold	64711

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	35441
k_ISDATDIRASentDiag_Cnt_str.NStep	35487
k_ISDATDIRASentTimeout_mS_u16	60992
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	52062
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	42760
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	54778
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	8516
k_ISDYNAASChkSumValidThresh_Cnt_u16	58562
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	17668
k_ISDYNAASMsgCountValidThresh_Cnt_u16	11866
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	14664
k_ISDYNAASMsgLenValidThresh_Cnt_u16	41861
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39514
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	17138
k_ISDYNABRChkSumValidThresh_Cnt_u16	3704
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	20642
k_ISDYNABRMsgCountValidThresh_Cnt_u16	43992
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	15169
k_ISDYNABRMsgLenValidThresh_Cnt_u16	1939
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	21215
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	7351
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	17022
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	55560
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	41955
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	40409
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	11233
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	8056
k_ISDYNVOLChkSumValidThresh_Cnt_u16	41265
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	19928
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	47046
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	21824
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	40578
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	62079
k_IgnOnTimeout_mS_u16	56180
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	184.607803
k_PowerCutVehSpdLowThresh_Kph_f32	17.1156998
k_PowerCutVehSpdLowTimeout_mS_u16	41185
k_VBattMaxAAS_Volt_f32	5.71190023
k_VBattMaxBSI_Volt_f32	30.7516994
k_VBattMaxCAV_Volt_f32	3.02810001
k_VBattMaxCMM388_Volt_f32	9.58199978
k_VBattMaxCMM_Volt_f32	32
k_VBattMaxESP_Volt_f32	27.5844002
k_VBattMinAAS_Volt_f32	12.0837002
k_VBattMinBSI_Volt_f32	27.5844002
k_VBattMinCAV_Volt_f32	6.21150017
k_VBattMinCMM388_Volt_f32	27.2632999
k_VBattMinCMM_Volt_f32	17.5296001
k_VBattMinESP_Volt_f32	32
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	19032
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	57282
k_VitesseVehicleBVRampValidThresh_Cnt_u16	55651
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	7033
k_VitesseVehicleBVSigValidThresh_Cnt_u16	41811
k_VitesseVehicleBVSpeedPassThresh_kph_f32	10.8360004
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	54002
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	8192
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	948014080
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	48464
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3270708736
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	182
target_SrlComInput_Per1_Batt_Volt_f32.value	24.9617996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1291975680
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	143
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.103855088
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	150
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1439738880
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1269353472
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1204874240
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	306777088
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1930505216
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	841567232
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	395406336
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	9
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	47
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	151
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	183
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	234
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	236
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	610929664
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	150
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	174
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	186
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	245
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1223928832
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	19
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	105630720
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2314464256
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	84
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	188
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	203
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1758297088
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3350
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.381182879
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	557194
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	117.4841
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	41517

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3270708736	3270708736	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3270708736	3270708736	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3270708736	3270708736	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3270708736	3270708736	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3270708736	3270708736	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3270708736	3270708736	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3270708736	3270708736	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3270708736	3270708736	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3270708736	3270708736	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3270708736	3270708736	✔
CDD_SrlComVehSpd_Kph_G_f32	568.928101	568.928101	✔
CMM388NTCEnableTimer_mS_M_u32	3270708736	3270708736	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3270708736	3270708736	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3270708736	3270708736	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	60798	60798	✔
CONSANGLECPK_HwDeg_M_f32	559.463928	559.463928 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3270708736	3270708736	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3270708736	3270708736	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3270708736	3270708736	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3270708736	3270708736	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3270708736	3270708736	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3270708736	3270708736	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3270708736	3270708736	✔
ESPNTCEnableTimer_mS_M_u32	3270708736	3270708736	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3270708736	3270708736	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	65535	65535	✔
EffacDefaultDiagTimer_mS_M_u32[1]	95535	95535	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	963	963	✔
ElecIntTimer_mS_M_u32[1]	7852	7852	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3270708736	3270708736	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20105	20105	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3270708736	3270708736	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	24710	24710	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3270708736	3270708736	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	7236	7236	✔
ISDATBSI412MsgTimer_mS_M_u32	3270708736	3270708736	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	60443	60443	✔
ISDATBSI432MsgTimer_mS_M_u32	3270708736	3270708736	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3270708736	3270708736	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36388	36388	✔
ISDYN2CMMMsgTimer_mS_M_u32	3270708736	3270708736	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	39749	39749	✔
ISDYNAASMsgTimer_mS_M_u32	3270708736	3270708736	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	60798	60798	✔
ISDYNABRMsgTimer_mS_M_u32	3270708736	3270708736	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	24710	24710	✔
ISDYNCMM208MsgTimer_mS_M_u32	3270708736	3270708736	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	22548	22548	✔
ISDYNCMM388MsgTimer_mS_M_u32	3270708736	3270708736	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	41025	41025	✔
ISDYNVOLMsgTimer_mS_M_u32	3270708736	3270708736	✔
IgnOnTimer_mS_M_u32	2349247488	2349247488	✔
IgnTimeOff_Sec_M_u32	665497092	665497092	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	150	150	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1439738880	1439738880	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	148	148	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1269353472	1269353472	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	180	180	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1204874240	1204874240	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	190	190	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	306777088	306777088	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3397250048	3397250048	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	178	178	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	841567232	841567232	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	395406336	395406336	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	215	215	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	610929664	610929664	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	174	174	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1223928832	1223928832	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	19	19	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	105630720	105630720	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	90	90	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2314464256	2314464256	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1758297088	1758297088	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	485.944794	485.944794	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	75.6496964	75.6496964	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	230.454605	230.454605	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	60798	60798	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	665497092	665497092	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	559.463928	559.463928 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	568.928101	568.928101	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.291 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3398708992
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	11716
AASNodeAbsentTimer_mS_M_u32	2445467392
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	23395
ANGLEVOLANTSigValidCount_Cnt_M_u16	45377
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	62197
AngleVolantMsgTimer_mS_M_u32	3398708992
AngleVolantValidCount_Cnt_M_u16	44491
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1716625152
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3746176768
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3996733184
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3950186240
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	4390
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2669924096
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	62133
CAVNodeAbsentTimer_mS_M_u32	2940993280
CDD_SrlComVehSpd_Kph_G_f32	168.696793
CMM388NTCEnableTimer_mS_M_u32	1467563776
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1916403456
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	44683
CMMNodeAbsentTimer_mS_M_u32	3640987392
CONSANGLECPKSigInvalidCount_Cnt_M_u16	8429
CONSANGLECPKSigValidCount_Cnt_M_u16	27996
CONSANGLECPK_Cnt_M_u16	62547
CONSANGLECPK_HwDeg_M_f32	-558.64447
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	62547
CPKVehicleSpeedMsgTimer_mS_M_u32	963587840
CPKVehicleSpeedValidCount_Cnt_M_u16	45970
CityParkInputConsistentCount_Cnt_M_u16	51391
CityParkInputInvalidCount_Cnt_M_u16	28881
CityParkInputMsgTimer_mS_M_u32	1439738880
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1773592320
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	30392

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1006534400
ComputerRazGCTSigValidCount_Cnt_M_u16	36488
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	8669
DMDFCTCPKSigValidCount_Cnt_M_u16	49347
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	48093
DMDRELAXECPKSigValidCount_Cnt_M_u16	22843
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	25374
DateInvalidTimer_mS_M_u32	3746176768
DiagMuxOnAbsentTimer_mS_M_u32	2091183872
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3950186240
ESPNTCEnableTimer_mS_M_u32	2980568832
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	64853
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	579
EffacDefaultDiagTimer_mS_M_u32[1]	989
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	200
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3883781888
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	22401
EtatMTSigValidCount_Cnt_M_u16	15995
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	28519
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	33622
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	26033
ISDAT4V2BSI552MsgTimer_mS_M_u32	2147028736
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	37688
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	53146
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	15995
ISDATBSI3F2MsgTimer_mS_M_u32	2787831552
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	33879
ISDATBSI412MsgLenValidCount_Cnt_M_u16	21929
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	22401
ISDATBSI412MsgTimer_mS_M_u32	3524931328
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	25727
ISDATBSI432MsgLenValidCount_Cnt_M_u16	585
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	31290
ISDATDIRASentFltAcc_Cnt_M_u16	41342
ISDATDIRASentTimer_mS_M_u32	963587840
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	22105
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	44491
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	42784
ISDYN2CMMMsgTimer_mS_M_u32	4294967295
ISDYNAASChkSumInvalidCount_Cnt_M_u16	19006
ISDYNAASChkSumValidCount_Cnt_M_u16	62908
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	4366
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	38636
ISDYNAASMsgLenValidCount_Cnt_M_u16	57026
ISDYNAASMsgTimeValidCount_Cnt_M_u16	19006
ISDYNAASMsgTimer_mS_M_u32	2172993280
ISDYNABRChkSumInvalidCount_Cnt_M_u16	56514
ISDYNABRChkSumValidCount_Cnt_M_u16	62984
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	39425
ISDYNABRMsgCountValidCount_Cnt_M_u16	41407
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	57264
ISDYNABRMsgLenValidCount_Cnt_M_u16	51295
ISDYNABRMsgTimeValidCount_Cnt_M_u16	62547
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	1984
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	38011
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	15995
ISDYNCMM208MsgTimer_mS_M_u32	4183465728
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	1984
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	38011
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	47185

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2470887168
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	57971
ISDYNVOLChkSumValidCount_Cnt_M_u16	26466
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	37475
ISDYNVOLMsgCountValidCount_Cnt_M_u16	43465
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	55442
ISDYNVOLMsgLenValidCount_Cnt_M_u16	44896
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	44683
ISDYNVOLMsgTimer_mS_M_u32	1107984128
IgnOnTimer_mS_M_u32	3778723584
IgnTimeOff_Sec_M_u32	1220467004
ManVehSpd_Kph_M_f32	113.681602
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	167
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	21
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3094933248
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	220
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1750880000
PrevISDATBSI412MsgDLCError_Cnt_M_u08	62
PrevISDATBSI412MsgRxTime_MSec_M_u32	1083244288
PrevISDATBSI432MsgDLCError_Cnt_M_u08	69
PrevISDATBSI432MsgRxTime_MSec_M_u32	2831933184
PrevISDATDIRAMsgTxTime_MSec_M_u32	315948800
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	42
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3178139392
PrevISDYNAASMsgDLCError_Cnt_M_u08	212
PrevISDYNAASMsgRxTime_MSec_M_u32	202407680
PrevISDYNABRMsgDLCError_Cnt_M_u08	51
PrevISDYNABRMsgRxTime_MSec_M_u32	3025321728
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	151
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4070145792
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	108
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1086512896
PrevISDYNVOLMsgDLCError_Cnt_M_u08	121
PrevISDYNVOLMsgRxTime_MSec_M_u32	3176267520
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1486892800
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	270.974609
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	58738
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	9672
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	7215
VitesseVehicleBVRampValidCount_Cnt_M_u16	57413
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	59808
VitesseVehicleBVSigValidCount_Cnt_M_u16	25406
VitesseVehicleBV_Kph_M_f32	555.807373
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	47185
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	23175
VitesseVehiculeRoues_Kph_M_f32	577.238098
k_AASNTCEnableTimeout_mS_u16	14958
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	13594
k_AASNodeTimeout_mS_u16	21704
k_ABSNodeTimeout_mS_u16	40870
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	55822
k_ANGLEVOLANTSigValidThresh_Cnt_u16	54552
k_AngleVolantInvalidThresh_Cnt_u16	7363
k_AngleVolantValidThresh_Cnt_u16	28881
k_BSI552MsgTimeout_mS_u16	30194
k_BSINTCEnableTimeout_mS_u16	26519
k_BSINodeAbsentDiag_Cnt_str.Threshold	2178
k_BSINodeAbsentDiag_Cnt_str.PStep	61123
k_BSINodeAbsentDiag_Cnt_str.NStep	15368
k_BSINodeAbsentTimeout_mS_u16	61453
k_BSINodeTimeout_mS_u16	31290
k_BattOvHi_Volt_f32	14.7396002
k_BattOvLo_Volt_f32	15.6885004
k_BattUvHi_Volt_f32	30.0650005
k_BattUvLo_Volt_f32	22.5123997
k_CAVNTCEnableTimeout_mS_u16	37487
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	51259
k_CAVNodeTimeout_mS_u16	8953
k_CMM388MsgTimeout_mS_u16	40132
k_CMM388NTCEnableTimeout_mS_u16	37840
k_CMMNTCEnableTimeout_mS_u16	57936
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	49043
k_CONSANGLECPKMax_HwDeg_f32	559.623901
k_CONSANGLECPKMin_HwDeg_f32	-323.361603
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	42833
k_CONSANGLECPKSigValidThresh_Cnt_u16	35207
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	32950
k_CPKVehicleSpeedValidThresh_Cnt_u16	48462
k_CityParkInputInvalidThresh_Cnt_u16	34608
k_CityParkInputValidThresh_Cnt_u16	51391
k_ComputerRazGCTSigValidThresh_Cnt_u16	43526
k_CptTemporelSigValidThresh_Cnt_u16	1256
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	20144
k_DMDFCTCPKSigValidThresh_Cnt_u16	30559
k_DMDFCTCPKValidCount_Cnt_u16	54030
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	42784
k_DMDRELAXECPKSigValidThresh_Cnt_u16	49734
k_DMDRelaxeConsistentThresh_Cnt_u16	41012
k_DateValidThresh_Cnt_u16	26033
k_DefaultVehSpd_Kph_f32	80.9680023
k_DiagMuxOnAbsentTimeout_mS_u16	11633
k_EMNodeTimeout_mS_u16	49662
k_ESPNTCEnableTimeout_mS_u16	48833
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	25723
k_EtatMTSigInvalidThresh_Cnt_u16	46541
k_EtatMTSigValidThresh_Cnt_u16	4435
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	39693
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	43624
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	47484
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	22537
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	16171
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	22603
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	63696
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	57690
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	23155
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	10023
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	7449
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	33194
k_ISDATDIRASentDiag_Cnt_str.Threshold	64711

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	35441
k_ISDATDIRASentDiag_Cnt_str.NStep	35487
k_ISDATDIRASentTimeout_mS_u16	21710
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	35251
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	62197
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	63645
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	52162
k_ISDYNAASChkSumValidThresh_Cnt_u16	9480
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	2305
k_ISDYNAASMsgCountValidThresh_Cnt_u16	20671
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	37814
k_ISDYNAASMsgLenValidThresh_Cnt_u16	42940
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	36864
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	38966
k_ISDYNABRChkSumValidThresh_Cnt_u16	63845
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	32806
k_ISDYNABRMsgCountValidThresh_Cnt_u16	62020
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	56715
k_ISDYNABRMsgLenValidThresh_Cnt_u16	27733
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	55599
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	22630
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	21332
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	54067
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	51811
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	24641
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	489
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	9318
k_ISDYNVOLChkSumValidThresh_Cnt_u16	13048
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	60806
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	48124
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	40077
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	29831
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	53711
k_IgnOnTimeout_mS_u16	57458
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	27.2341003
k_PowerCutVehSpdLowThresh_Kph_f32	153.710693
k_PowerCutVehSpdLowTimeout_mS_u16	9770
k_VBattMaxAAS_Volt_f32	29.8581009
k_VBattMaxBSI_Volt_f32	21.5764008
k_VBattMaxCAV_Volt_f32	28.2091999
k_VBattMaxCMM388_Volt_f32	21.7604008
k_VBattMaxCMM_Volt_f32	24.8398991
k_VBattMaxESP_Volt_f32	22.2161999
k_VBattMinAAS_Volt_f32	23.6012001
k_VBattMinBSI_Volt_f32	22.2161999
k_VBattMinCAV_Volt_f32	0.579999983
k_VBattMinCMM388_Volt_f32	12.5124998
k_VBattMinCMM_Volt_f32	8.9392004
k_VBattMinESP_Volt_f32	24.8398991
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	29893
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	2120
k_VitesseVehicleBVRampValidThresh_Cnt_u16	33123
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	5730
k_VitesseVehicleBVSigValidThresh_Cnt_u16	37524
k_VitesseVehicleBVSpeedPassThresh_kph_f32	107.368401
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	57781
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	56907
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3746176768
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	11265
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3016357888
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	108
target_SrlComInput_Per1_Batt_Volt_f32.value	13.8093996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1871236864
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	20
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.609404504
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	735887104
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	76
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1389649664
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2799435520
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3488849664
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1981497088
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1095950080
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3650780928
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	39
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	130
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	131
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	242
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1569758976
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	71
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	122
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	236
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	238
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	226
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2658385664
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	27
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1860919040
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	237
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	745733888
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	22
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	124
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	173
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2854637312
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1264
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.884896696
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	359834
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	137.855499
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	8196

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3016357888	3016357888	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3016357888	3016357888	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	62197	62197	✔
AngleVolantMsgTimer_mS_M_u32	3016357888	3016357888	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3016357888	3016357888	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3016357888	3016357888	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3016357888	3016357888	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3016357888	3016357888	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	2178	2178	✔
BSINodeAbsentTimer_mS_M_u32	3016357888	3016357888	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3016357888	3016357888	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3016357888	3016357888	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3016357888	3016357888	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3016357888	3016357888	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3016357888	3016357888	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	62547	62547	✔
CONSANGLECPK_HwDeg_M_f32	-558.64447	-558.64447 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	62547	62547	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	963587840	963587840	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	45970	45970	✔
CityParkInputConsistentCount_Cnt_M_u16	51391	51391	✔
CityParkInputInvalidCount_Cnt_M_u16	28883	28883	✔
CityParkInputMsgTimer_mS_M_u32	3016357888	3016357888	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3016357888	3016357888	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3016357888	3016357888	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3016357888	3016357888	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3016357888	3016357888	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3016357888	3016357888	✔
ESPNTCEnableTimer_mS_M_u32	3016357888	3016357888	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3016357888	3016357888	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3016357888	3016357888	✔
EffacDefaultDiagTimer_mS_M_u32[1]	989	989	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3016357888	3016357888	✔
ElecIntTimer_mS_M_u32[1]	200	200	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3016357888	3016357888	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3016357888	3016357888	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3016357888	3016357888	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3016357888	3016357888	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3016357888	3016357888	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3016357888	3016357888	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3016357888	3016357888	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3016357888	3016357888	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3016357888	3016357888	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3016357888	3016357888	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3016357888	3016357888	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3016357888	3016357888	✔
IgnOnTimer_mS_M_u32	3778723584	3778723584	✔
IgnTimeOff_Sec_M_u32	1220467004	1220467004	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	220	220	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	735887104	735887104	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	76	76	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1389649664	1389649664	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	148	148	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2799435520	2799435520	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3488849664	3488849664	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	315948800	315948800	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1095950080	1095950080	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	81	81	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3650780928	3650780928	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	215	215	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1569758976	1569758976	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	226	226	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2658385664	2658385664	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	27	27	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1860919040	1860919040	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	237	237	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	745733888	745733888	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2854637312	2854637312	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	270.974609	270.974609	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	555.807373	555.807373	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	577.238098	577.238098	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	62547	62547	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1220467004	1220467004	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-558.64447	-558.64447 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	80.9680023	80.9680023	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.292 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	861812224
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	27596
AASNodeAbsentTimer_mS_M_u32	881993216
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	31985
ANGLEVOLANTSigValidCount_Cnt_M_u16	61462
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	8249
AngleVolantMsgTimer_mS_M_u32	861812224
AngleVolantValidCount_Cnt_M_u16	52792
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1642456576
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2029807104
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1156503040
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1682019840
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	10152
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4230960640
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	51577
CAVNodeAbsentTimer_mS_M_u32	3900098048
CDD_SrlComVehSpd_Kph_G_f32	540.860291
CMM388NTCEnableTimer_mS_M_u32	888079872
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3618424320
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	63417
CMMNodeAbsentTimer_mS_M_u32	1670092288
CONSANGLECPKSigInvalidCount_Cnt_M_u16	51024
CONSANGLECPKSigValidCount_Cnt_M_u16	38598
CONSANGLECPK_Cnt_M_u16	40417
CONSANGLECPK_HwDeg_M_f32	-594.330627
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	40417
CPKVehicleSpeedMsgTimer_mS_M_u32	315438592
CPKVehicleSpeedValidCount_Cnt_M_u16	4139
CityParkInputConsistentCount_Cnt_M_u16	19804
CityParkInputInvalidCount_Cnt_M_u16	28198

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	735887104
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2092312064
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	24816
ComputerRazGCTSigInvalidTimer_mS_M_u32	744441344
ComputerRazGCTSigValidCount_Cnt_M_u16	24577
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	35586
DMDFCTCPKSigValidCount_Cnt_M_u16	17167
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	50051
DMDRELAXECPKSigValidCount_Cnt_M_u16	24616
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	1213
DateInvalidTimer_mS_M_u32	2029807104
DiagMuxOnAbsentTimer_mS_M_u32	1345058304
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1682019840
ESPNTCEnableTimer_mS_M_u32	2833458688
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	12314
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1000
EffacDefaultDiagTimer_mS_M_u32[1]	2000
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	89
ElecIntTimer_mS_M_u32[1]	898
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	186734080
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	42454
EtatMTSigValidCount_Cnt_M_u16	54695
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	17378
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	48344
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	35909
ISDAT4V2BSI552MsgTimer_mS_M_u32	1051694592
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	58929
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	46539
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	54695
ISDATBSI3F2MsgTimer_mS_M_u32	1805252096
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	40915
ISDATBSI412MsgLenValidCount_Cnt_M_u16	28829
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	42454
ISDATBSI412MsgTimer_mS_M_u32	3033282048
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	42461
ISDATBSI432MsgLenValidCount_Cnt_M_u16	61758
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	34538
ISDATDIRASentFltAcc_Cnt_M_u16	8478
ISDATDIRASentTimer_mS_M_u32	315438592
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	4047
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	52792
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	51001
ISDYN2CMMMsgTimer_mS_M_u32	2001391872
ISDYNAASChkSumInvalidCount_Cnt_M_u16	32350
ISDYNAASChkSumValidCount_Cnt_M_u16	28836
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	28783
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	30932
ISDYNAASMsgLenValidCount_Cnt_M_u16	62993
ISDYNAASMsgTimeValidCount_Cnt_M_u16	32350
ISDYNAASMsgTimer_mS_M_u32	3872065024
ISDYNABRChkSumInvalidCount_Cnt_M_u16	35924
ISDYNABRChkSumValidCount_Cnt_M_u16	21826
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	23317
ISDYNABRMsgCountValidCount_Cnt_M_u16	14491
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	22279
ISDYNABRMsgLenValidCount_Cnt_M_u16	20925
ISDYNABRMsgTimeValidCount_Cnt_M_u16	40417
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	57161
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	25048

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	54695
ISDYNCMM208MsgTimer_mS_M_u32	214623744
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	57161
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	25048
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	18086
ISDYNCMM388MsgTimer_mS_M_u32	2542175744
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	6846
ISDYNVOLChkSumValidCount_Cnt_M_u16	16564
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	53616
ISDYNVOLMsgCountValidCount_Cnt_M_u16	8189
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	53859
ISDYNVOLMsgLenValidCount_Cnt_M_u16	33464
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	63417
ISDYNVOLMsgTimer_mS_M_u32	1245398528
IgnOnTimer_mS_M_u32	2108327424
IgnTimeOff_Sec_M_u32	1633944048
ManVehSpd_Kph_M_f32	559.127014
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	169
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	130
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3970954752
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	167
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	579196416
PrevISDATBSI412MsgDLCError_Cnt_M_u08	246
PrevISDATBSI412MsgRxTime_MSec_M_u32	2292696576
PrevISDATBSI432MsgDLCError_Cnt_M_u08	148
PrevISDATBSI432MsgRxTime_MSec_M_u32	1400317440
PrevISDATDIRAMsgTxTime_MSec_M_u32	568051200
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	152
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1011815936
PrevISDYNAASMsgDLCError_Cnt_M_u08	88
PrevISDYNAASMsgRxTime_MSec_M_u32	2217297408
PrevISDYNABRMsgDLCError_Cnt_M_u08	79
PrevISDYNABRMsgRxTime_MSec_M_u32	1684178432
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	68
PrevISDYNCMM208MsgRxTime_MSec_M_u32	881739264
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	186
PrevISDYNCMM388MsgRxTime_MSec_M_u32	663889408
PrevISDYNVOLMsgDLCError_Cnt_M_u08	185
PrevISDYNVOLMsgRxTime_MSec_M_u32	1449444864
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3107599872
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	362.218597
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	9538
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	47359
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	46347
VitesseVehicleBVRampValidCount_Cnt_M_u16	48520
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	1594
VitesseVehicleBVSigValidCount_Cnt_M_u16	3615
VitesseVehicleBV_Kph_M_f32	376.85791

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	18086
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	13508
VitesseVehiculeRoues_Kph_M_f32	167.709396
k_AASNTCEnableTimeout_mS_u16	63376
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	13387
k_AASNodeTimeout_mS_u16	11263
k_ABSNodeTimeout_mS_u16	30119
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	16688
k_ANGLEVOLANTSigValidThresh_Cnt_u16	29905
k_AngleVolantInvalidThresh_Cnt_u16	2512
k_AngleVolantValidThresh_Cnt_u16	28198
k_BSI552MsgTimeout_mS_u16	20099
k_BSINTCEnableTimeout_mS_u16	64661
k_BSINodeAbsentDiag_Cnt_str.Threshold	24194
k_BSINodeAbsentDiag_Cnt_str.PStep	29440
k_BSINodeAbsentDiag_Cnt_str.NStep	25201
k_BSINodeAbsentTimeout_mS_u16	35057
k_BSINodeTimeout_mS_u16	34538
k_BattOvHi_Volt_f32	20.6993008
k_BattOvLo_Volt_f32	16.0436001
k_BattUvHi_Volt_f32	3.98569989
k_BattUvLo_Volt_f32	27.2465992
k_CAVNTCEnableTimeout_mS_u16	332
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	57575
k_CAVNodeTimeout_mS_u16	61740
k_CMM388MsgTimeout_mS_u16	7884
k_CMM388NTCEnableTimeout_mS_u16	27048
k_CMMNTCEnableTimeout_mS_u16	22761
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	13728
k_CONSANGLECPKMax_HwDeg_f32	179.373001
k_CONSANGLECPKMin_HwDeg_f32	-325.991913
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	31142
k_CONSANGLECPKSigValidThresh_Cnt_u16	42948
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	57397
k_CPKVehicleSpeedValidThresh_Cnt_u16	37102
k_CityParkInputInvalidThresh_Cnt_u16	50442
k_CityParkInputValidThresh_Cnt_u16	19804
k_ComputerRazGCTSigValidThresh_Cnt_u16	22983
k_CptTemporelSigValidThresh_Cnt_u16	52705
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	2567
k_DMDFCTCPKSigValidThresh_Cnt_u16	17597
k_DMDFCTCPKValidCount_Cnt_u16	33264
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	51001
k_DMDRELAXECPKSigValidThresh_Cnt_u16	2694
k_DMDRelaxeConsistentThresh_Cnt_u16	43196
k_DateValidThresh_Cnt_u16	35909
k_DefaultVehSpd_Kph_f32	54.7005005
k_DiagMuxOnAbsentTimeout_mS_u16	60039
k_EMNodeTimeout_mS_u16	26653
k_ESPNTCEnableTimeout_mS_u16	38229
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	59112
k_EtatMTSigInvalidThresh_Cnt_u16	60723
k_EtatMTSigValidThresh_Cnt_u16	61281
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	44336
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	58338
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	44837
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	7102
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	60184
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	62455
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	27882
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	55307

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	37889
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	21861
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	14414
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	1242
k_ISDATDIRASentDiag_Cnt_str.Threshold	62208
k_ISDATDIRASentDiag_Cnt_str.PStep	30559
k_ISDATDIRASentDiag_Cnt_str.NStep	53426
k_ISDATDIRASentTimeout_mS_u16	21552
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	20671
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	8249
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	22465
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	48980
k_ISDYNAASChkSumValidThresh_Cnt_u16	51266
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	3605
k_ISDYNAASMsgCountValidThresh_Cnt_u16	11163
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	14200
k_ISDYNAASMsgLenValidThresh_Cnt_u16	803
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	58393
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	50549
k_ISDYNABRChkSumValidThresh_Cnt_u16	22187
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	55976
k_ISDYNABRMsgCountValidThresh_Cnt_u16	63757
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	27321
k_ISDYNABRMsgLenValidThresh_Cnt_u16	58138
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	45132
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	40038
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	26332
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	7358
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	12273
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	58134
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	6878
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	48038
k_ISDYNVOLChkSumValidThresh_Cnt_u16	54448
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	25479
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	54118
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	1714
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	25475
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	16363
k_IgnOnTimeout_mS_u16	46978
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	144.402206
k_PowerCutVehSpdLowThresh_Kph_f32	124.972504
k_PowerCutVehSpdLowTimeout_mS_u16	9308
k_VBattMaxAAS_Volt_f32	23.2966995
k_VBattMaxBSI_Volt_f32	12.6280003
k_VBattMaxCAV_Volt_f32	24.3439007
k_VBattMaxCMM388_Volt_f32	4.05159998
k_VBattMaxCMM_Volt_f32	8.57380009
k_VBattMaxESP_Volt_f32	4.29559994
k_VBattMinAAS_Volt_f32	3.4921999
k_VBattMinBSI_Volt_f32	4.29559994
k_VBattMinCAV_Volt_f32	29.4687004
k_VBattMinCMM388_Volt_f32	32
k_VBattMinCMM_Volt_f32	9.45069981
k_VBattMinESP_Volt_f32	8.57380009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	22409
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	41410
k_VitesseVehicleBVRampValidThresh_Cnt_u16	1136
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	13236
k_VitesseVehicleBVSigValidThresh_Cnt_u16	33757
k_VitesseVehicleBVSpeedPassThresh_kph_f32	369.114502
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	64633
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	23414
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2029807104
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	186

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	2.64750004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1593857536
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	41
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.661811531
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2781120000
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	175
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	392013312
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1103545856
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	754968064
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3775464960
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1709319680
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	65
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3280684544
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	28
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	46
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	58
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	98
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	179
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	189
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	942204416
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	39
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	161
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	228
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1778353664
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3742934528
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3439445504
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	15
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	157
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	215
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	86496768
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2947
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.581087828
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	107310
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	84.7882004
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	15756

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	559.127014	559.127014	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	40417	40417	✔
CONSANGLECPK_HwDeg_M_f32	-594.330627	-594.330627 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1713429248	1713429248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1000	1000	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2000	2000	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	89	89	✔
ElecIntTimer_mS_M_u32[1]	898	898	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	35909	35909	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	54695	54695	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	42454	42454	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	34538	34538	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	51001	51001	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	32350	32350	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	40417	40417	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	54695	54695	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	18086	18086	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	63417	63417	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	2108327424	2108327424	✔
IgnTimeOff_Sec_M_u32	1633944048	1633944048	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	55	55	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2781120000	2781120000	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	175	175	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	392013312	392013312	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	220	220	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1103545856	1103545856	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	198	198	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	754968064	754968064	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	568051200	568051200	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	240	240	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1709319680	1709319680	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	65	65	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3280684544	3280684544	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	14	14	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	942204416	942204416	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1778353664	1778353664	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	93	93	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3742934528	3742934528	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	238	238	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3439445504	3439445504	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	86496768	86496768	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	362.218597	362.218597	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	376.85791	376.85791	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	167.709396	167.709396	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	40417	40417	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1633944048	1633944048	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-594.330627	-594.330627 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.293 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2380013824
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	48784
AASNodeAbsentTimer_mS_M_u32	2248167680
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	48419
ANGLEVOLANTSigValidCount_Cnt_M_u16	1394
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	38217
AngleVolantMsgTimer_mS_M_u32	2380013824
AngleVolantValidCount_Cnt_M_u16	61388
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	4244967680
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	834769152
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3819585792
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1085407488
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	22782
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1609089280
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	40970
CAVNodeAbsentTimer_mS_M_u32	1154642176
CDD_SrlComVehSpd_Kph_G_f32	408.519409
CMM388NTCEnableTimer_mS_M_u32	2422845696
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3476058368
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	61451
CMMNodeAbsentTimer_mS_M_u32	3939762432
CONSANGLECPKSigInvalidCount_Cnt_M_u16	3331
CONSANGLECPKSigValidCount_Cnt_M_u16	32867
CONSANGLECPK_Cnt_M_u16	38674
CONSANGLECPK_HwDeg_M_f32	609.448425
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	38674
CPKVehicleSpeedMsgTimer_mS_M_u32	1804542208
CPKVehicleSpeedValidCount_Cnt_M_u16	20509
CityParkInputConsistentCount_Cnt_M_u16	608
CityParkInputInvalidCount_Cnt_M_u16	21764
CityParkInputMsgTimer_mS_M_u32	2781120000
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1033130240
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	28452

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3138973952
ComputerRazGCTSigValidCount_Cnt_M_u16	40561
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	28272
DMDFCTCPKSigValidCount_Cnt_M_u16	34824
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	45421
DMDRELAXECPKSigValidCount_Cnt_M_u16	32060
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	18620
DateInvalidTimer_mS_M_u32	834769152
DiagMuxOnAbsentTimer_mS_M_u32	2658328832
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1085407488
ESPNTCEnableTimer_mS_M_u32	2903331072
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	55463
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	2500
EffacDefaultDiagTimer_mS_M_u32[1]	3500
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	748
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2064826624
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	60083
EtatMTSigValidCount_Cnt_M_u16	0
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24397
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	54829
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	1126
ISDAT4V2BSI552MsgTimer_mS_M_u32	3915907328
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	20257
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	21013
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0
ISDATBSI3F2MsgTimer_mS_M_u32	2217271552
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	31547
ISDATBSI412MsgLenValidCount_Cnt_M_u16	15006
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	60083
ISDATBSI412MsgTimer_mS_M_u32	1100095744
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	30111
ISDATBSI432MsgLenValidCount_Cnt_M_u16	9531
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	27575
ISDATDIRASentFltAcc_Cnt_M_u16	27931
ISDATDIRASentTimer_mS_M_u32	1804542208
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	31048
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	61388
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	21963
ISDYN2CMMMsgTimer_mS_M_u32	3115274496
ISDYNAASChkSumInvalidCount_Cnt_M_u16	20186
ISDYNAASChkSumValidCount_Cnt_M_u16	39370
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	42279
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	48633
ISDYNAASMsgLenValidCount_Cnt_M_u16	18433
ISDYNAASMsgTimeValidCount_Cnt_M_u16	20186
ISDYNAASMsgTimer_mS_M_u32	3939873024
ISDYNABRChkSumInvalidCount_Cnt_M_u16	54393
ISDYNABRChkSumValidCount_Cnt_M_u16	15216
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	21685
ISDYNABRMsgCountValidCount_Cnt_M_u16	56805
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	63966
ISDYNABRMsgLenValidCount_Cnt_M_u16	60286
ISDYNABRMsgTimeValidCount_Cnt_M_u16	38674
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	8137
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	7645
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0
ISDYNCMM208MsgTimer_mS_M_u32	3495301376
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	8137
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	7645
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	48770

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	648229120
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	19129
ISDYNVOLChkSumValidCount_Cnt_M_u16	47769
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	54054
ISDYNVOLMsgCountValidCount_Cnt_M_u16	10558
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	21964
ISDYNVOLMsgLenValidCount_Cnt_M_u16	42636
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	61451
ISDYNVOLMsgTimer_mS_M_u32	3515150592
IgnOnTimer_mS_M_u32	70725888
IgnTimeOff_Sec_M_u32	1125837579
ManVehSpd_Kph_M_f32	137.716904
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	170
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	16
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3639009536
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	50
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1726300416
PrevISDATBSI412MsgDLCError_Cnt_M_u08	235
PrevISDATBSI412MsgRxTime_MSec_M_u32	1748988160
PrevISDATBSI432MsgDLCError_Cnt_M_u08	246
PrevISDATBSI432MsgRxTime_MSec_M_u32	4249964800
PrevISDATDIRAMsgTxTime_MSec_M_u32	1822650624
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	213
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3465117952
PrevISDYNAASMsgDLCError_Cnt_M_u08	87
PrevISDYNAASMsgRxTime_MSec_M_u32	1538978048
PrevISDYNABRMsgDLCError_Cnt_M_u08	54
PrevISDYNABRMsgRxTime_MSec_M_u32	806301952
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	248
PrevISDYNCMM208MsgRxTime_MSec_M_u32	512487680
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	181
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2902479104
PrevISDYNVOLMsgDLCError_Cnt_M_u08	63
PrevISDYNVOLMsgRxTime_MSec_M_u32	856191232
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1816666368
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	559.870422
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	61615
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	14135
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	42324
VitesseVehicleBVRampValidCount_Cnt_M_u16	36252
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	34120
VitesseVehicleBVSigValidCount_Cnt_M_u16	3927
VitesseVehicleBV_Kph_M_f32	533.899109
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	48770
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	30185
VitesseVehiculeRoues_Kph_M_f32	283.233612
k_AASNTCEnableTimeout_mS_u16	1541
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	51603
k_AASNodeTimeout_mS_u16	56887
k_ABSNodeTimeout_mS_u16	33409
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	44966
k_ANGLEVOLANTSigValidThresh_Cnt_u16	42626
k_AngleVolantInvalidThresh_Cnt_u16	41861
k_AngleVolantValidThresh_Cnt_u16	21764
k_BSI552MsgTimeout_mS_u16	58540
k_BSINTCEnableTimeout_mS_u16	20855
k_BSINodeAbsentDiag_Cnt_str.Threshold	7582
k_BSINodeAbsentDiag_Cnt_str.PStep	35429
k_BSINodeAbsentDiag_Cnt_str.NStep	13905
k_BSINodeAbsentTimeout_mS_u16	15137
k_BSINodeTimeout_mS_u16	27575
k_BattOvHi_Volt_f32	31.5
k_BattOvLo_Volt_f32	18.6420994
k_BattUvHi_Volt_f32	26.6002998
k_BattUvLo_Volt_f32	20.0084991
k_CAVNTCEnableTimeout_mS_u16	45970
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	37312
k_CAVNodeTimeout_mS_u16	65391
k_CMM388MsgTimeout_mS_u16	42384
k_CMM388NTCEnableTimeout_mS_u16	13564
k_CMMNTCEnableTimeout_mS_u16	55033
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	58197
k_CONSANGLECPKMax_HwDeg_f32	41.4194984
k_CONSANGLECPKMin_HwDeg_f32	-678.521973
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	9602
k_CONSANGLECPKSigValidThresh_Cnt_u16	7401
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	6549
k_CPKVehicleSpeedValidThresh_Cnt_u16	54250
k_CityParkInputInvalidThresh_Cnt_u16	33367
k_CityParkInputValidThresh_Cnt_u16	608
k_ComputerRazGCTSigValidThresh_Cnt_u16	52319
k_CptTemporelSigValidThresh_Cnt_u16	57811
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	57566
k_DMDFCTCPKSigValidThresh_Cnt_u16	4734
k_DMDFCTCPKValidCount_Cnt_u16	27174
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	21963
k_DMDRELAXECPKSigValidThresh_Cnt_u16	52643
k_DMDRelaxeConsistentThresh_Cnt_u16	19201
k_DateValidThresh_Cnt_u16	1126
k_DefaultVehSpd_Kph_f32	192.362305
k_DiagMuxOnAbsentTimeout_mS_u16	51488
k_EMNodeTimeout_mS_u16	40604
k_ESPNTCEnableTimeout_mS_u16	44150
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	61309
k_EtatMTSigInvalidThresh_Cnt_u16	60892
k_EtatMTSigValidThresh_Cnt_u16	43283
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	24228
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	35920
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	16645
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	8826
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	9774
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	3791
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	38008
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	58580
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	15155
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	32902
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	35210
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	13608
k_ISDATDIRASentDiag_Cnt_str.Threshold	52471

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	60363
k_ISDATDIRASentDiag_Cnt_str.NStep	42803
k_ISDATDIRASentTimeout_mS_u16	60645
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	9593
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	38217
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	5426
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	15225
k_ISDYNAASChkSumValidThresh_Cnt_u16	57968
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	15285
k_ISDYNAASMsgCountValidThresh_Cnt_u16	1253
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	25357
k_ISDYNAASMsgLenValidThresh_Cnt_u16	59595
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	30890
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	59028
k_ISDYNABRChkSumValidThresh_Cnt_u16	5300
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	16382
k_ISDYNABRMsgCountValidThresh_Cnt_u16	34445
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	38667
k_ISDYNABRMsgLenValidThresh_Cnt_u16	49063
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	7376
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	6979
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	35360
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	51194
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	42019
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	11378
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	11996
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	13250
k_ISDYNVOLChkSumValidThresh_Cnt_u16	6757
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	12896
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	20740
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	14367
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	29547
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	372
k_IgnOnTimeout_mS_u16	45102
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	137.757294
k_PowerCutVehSpdLowThresh_Kph_f32	140.046402
k_PowerCutVehSpdLowTimeout_mS_u16	44961
k_VBattMaxAAS_Volt_f32	16.5368996
k_VBattMaxBSI_Volt_f32	23.0839996
k_VBattMaxCAV_Volt_f32	25.0935001
k_VBattMaxCMM388_Volt_f32	6.88660002
k_VBattMaxCMM_Volt_f32	18.0375996
k_VBattMaxESP_Volt_f32	1.32050002
k_VBattMinAAS_Volt_f32	26.6760006
k_VBattMinBSI_Volt_f32	1.32050002
k_VBattMinCAV_Volt_f32	12.0073996
k_VBattMinCMM388_Volt_f32	18.9813995
k_VBattMinCMM_Volt_f32	23.8824997
k_VBattMinESP_Volt_f32	18.0375996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	47387
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	52271
k_VitesseVehicleBVRampValidThresh_Cnt_u16	14886
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	57753
k_VitesseVehicleBVSigValidThresh_Cnt_u16	41693
k_VitesseVehicleBVSpeedPassThresh_kph_f32	21.9302998
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	1802
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	60370
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	834769152
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8524
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1236548
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	181
target_SrlComInput_Per1_Batt_Volt_f32.value	15.9905005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3145056512
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	40
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.129861891
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	207
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1944662272
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	19
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1805504768
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2028105984
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	232
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2209812736
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1947971840
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	130
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	839930112
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2778001664
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	124
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	150
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	193
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	244
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1178341632
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	227
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3543675136
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3228356864
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2201055488
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	55
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	119
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	126
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	161
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	218
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	234
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3338617088
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3431
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.930926442
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	359279
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	11.8493996
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	20433

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1236548	1236548	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1236548	1236548	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1236548	1236548	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1236548	1236548	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CDD_SrlComVehSpd_Kph_G_f32	137.716904	137.716904	✔
CMM388NTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	38674	38674	✔
CONSANGLECPK_HwDeg_M_f32	609.448425	609.448425 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1236548	1236548	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1236548	1236548	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1236548	1236548	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1236548	1236548	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1236548	1236548	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1236548	1236548	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1236548	1236548	✔
ESPNTCEnableTimer_mS_M_u32	1236548	1236548	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2500	2500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3500	3500	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4	4	✔
ElecIntTimer_mS_M_u32[1]	748	748	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1236548	1236548	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	1126	1126	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	60083	60083	✔
ISDATBSI412MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	27575	27575	✔
ISDATBSI432MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1236548	1236548	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	21963	21963	✔
ISDYN2CMMMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	20186	20186	✔
ISDYNAASMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	38674	38674	✔
ISDYNABRMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	48770	48770	✔
ISDYNCMM388MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	61451	61451	✔
ISDYNVOLMsgTimer_mS_M_u32	1236548	1236548	✔
IgnOnTimer_mS_M_u32	70725888	70725888	✔
IgnTimeOff_Sec_M_u32	1125837579	1125837579	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	207	207	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1944662272	1944662272	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	19	19	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1805504768	1805504768	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	121	121	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2028105984	2028105984	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	232	232	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2209812736	2209812736	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1822650624	1822650624	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	130	130	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	839930112	839930112	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	126	126	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2778001664	2778001664	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	244	244	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1178341632	1178341632	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	92	92	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3543675136	3543675136	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	181	181	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3228356864	3228356864	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	240	240	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2201055488	2201055488	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3338617088	3338617088	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	559.870422	559.870422	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	533.899109	533.899109	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	283.233612	283.233612	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	38674	38674	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1125837579	1125837579	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	609.448425	609.448425 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.294 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	802054144
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	4016
AASNodeAbsentTimer_mS_M_u32	1411502080
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	32249
ANGLEVOLANTSigValidCount_Cnt_M_u16	49098
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	44933
AngleVolantMsgTimer_mS_M_u32	802054144
AngleVolantValidCount_Cnt_M_u16	29310
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	4061368320
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3856535552
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2397306880
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1187823616
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	54888
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	875069440
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	31682
CAVNodeAbsentTimer_mS_M_u32	2284548096
CDD_SrlComVehSpd_Kph_G_f32	109.262497
CMM388NTCEnableTimer_mS_M_u32	308654080
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3776016384
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	64383
CMMNodeAbsentTimer_mS_M_u32	1348911104
CONSANGLECPKSigInvalidCount_Cnt_M_u16	343
CONSANGLECPKSigValidCount_Cnt_M_u16	504
CONSANGLECPK_Cnt_M_u16	14827
CONSANGLECPK_HwDeg_M_f32	634.887024
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	14827
CPKVehicleSpeedMsgTimer_mS_M_u32	582311936
CPKVehicleSpeedValidCount_Cnt_M_u16	32531
CityParkInputConsistentCount_Cnt_M_u16	35522
CityParkInputInvalidCount_Cnt_M_u16	29653
CityParkInputMsgTimer_mS_M_u32	1944662272
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2103824384
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	19956

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1599598592
ComputerRazGCTSigValidCount_Cnt_M_u16	14991
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	55185
DMDFCTCPKSigValidCount_Cnt_M_u16	50570
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	18715
DMDRELAXECPKSigValidCount_Cnt_M_u16	108
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	29228
DateInvalidTimer_mS_M_u32	3856535552
DiagMuxOnAbsentTimer_mS_M_u32	3372883968
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1187823616
ESPNTCEnableTimer_mS_M_u32	1392168960
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	35948
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	979
EffacDefaultDiagTimer_mS_M_u32[1]	1085
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	45
ElecIntTimer_mS_M_u32[1]	98
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	178946048
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	64646
EtatMTSigValidCount_Cnt_M_u16	65535
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	45689
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	43162
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	18544
ISDAT4V2BSI552MsgTimer_mS_M_u32	2762653696
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	24253
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	162
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	65535
ISDATBSI3F2MsgTimer_mS_M_u32	1877483520
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	53105
ISDATBSI412MsgLenValidCount_Cnt_M_u16	64518
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	64646
ISDATBSI412MsgTimer_mS_M_u32	1823236096
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	47811
ISDATBSI432MsgLenValidCount_Cnt_M_u16	63152
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	3259
ISDATDIRASentFltAcc_Cnt_M_u16	39055
ISDATDIRASentTimer_mS_M_u32	582311936
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	60233
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	29310
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	19840
ISDYN2CMMMsgTimer_mS_M_u32	890556416
ISDYNAASChkSumInvalidCount_Cnt_M_u16	1746
ISDYNAASChkSumValidCount_Cnt_M_u16	49347
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	32365
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	40437
ISDYNAASMsgLenValidCount_Cnt_M_u16	64158
ISDYNAASMsgTimeValidCount_Cnt_M_u16	1746
ISDYNAASMsgTimer_mS_M_u32	3005329408
ISDYNABRChkSumInvalidCount_Cnt_M_u16	26487
ISDYNABRChkSumValidCount_Cnt_M_u16	60752
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	8513
ISDYNABRMsgCountValidCount_Cnt_M_u16	8306
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	26310
ISDYNABRMsgLenValidCount_Cnt_M_u16	60583
ISDYNABRMsgTimeValidCount_Cnt_M_u16	14827
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	30967
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	60793
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	65535
ISDYNCMM208MsgTimer_mS_M_u32	4229992448
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	30967
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	60793
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	24156

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	364457984
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	41013
ISDYNVOLChkSumValidCount_Cnt_M_u16	43862
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	367
ISDYNVOLMsgCountValidCount_Cnt_M_u16	14824
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	59645
ISDYNVOLMsgLenValidCount_Cnt_M_u16	53630
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	64383
ISDYNVOLMsgTimer_mS_M_u32	3423858688
IgnOnTimer_mS_M_u32	3439144960
IgnTimeOff_Sec_M_u32	1846679993
ManVehSpd_Kph_M_f32	256.997498
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	171
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	93
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3920502784
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	62
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2972909568
PrevISDATBSI412MsgDLCError_Cnt_M_u08	34
PrevISDATBSI412MsgRxTime_MSec_M_u32	300183552
PrevISDATBSI432MsgDLCError_Cnt_M_u08	79
PrevISDATBSI432MsgRxTime_MSec_M_u32	1915670528
PrevISDATDIRAMsgTxTime_MSec_M_u32	2495115264
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	245
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1531330560
PrevISDYNAASMsgDLCError_Cnt_M_u08	40
PrevISDYNAASMsgRxTime_MSec_M_u32	2238836736
PrevISDYNABRMsgDLCError_Cnt_M_u08	61
PrevISDYNABRMsgRxTime_MSec_M_u32	2843029504
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	22
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3237933056
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	130
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3743535104
PrevISDYNVOLMsgDLCError_Cnt_M_u08	77
PrevISDYNVOLMsgRxTime_MSec_M_u32	361328640
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1149919232
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	152.592194
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	24019
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	34044
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	5092
VitesseVehicleBVRampValidCount_Cnt_M_u16	21965
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	63882
VitesseVehicleBVSigValidCount_Cnt_M_u16	30235
VitesseVehicleBV_Kph_M_f32	176.665695
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	24156
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	45796
VitesseVehiculeRoues_Kph_M_f32	281.295593
k_AASNTCEnableTimeout_mS_u16	30994
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	49449
k_AASNodeTimeout_mS_u16	36860
k_ABSNodeTimeout_mS_u16	8030
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	59566
k_ANGLEVOLANTSigValidThresh_Cnt_u16	20187
k_AngleVolantInvalidThresh_Cnt_u16	9170
k_AngleVolantValidThresh_Cnt_u16	29653
k_BSI552MsgTimeout_mS_u16	12955
k_BSINTCEnableTimeout_mS_u16	34619
k_BSINodeAbsentDiag_Cnt_str.Threshold	3319
k_BSINodeAbsentDiag_Cnt_str.PStep	51169
k_BSINodeAbsentDiag_Cnt_str.NStep	21855
k_BSINodeAbsentTimeout_mS_u16	7677
k_BSINodeTimeout_mS_u16	3259
k_BattOvHi_Volt_f32	23.5391998
k_BattOvLo_Volt_f32	14.0739002
k_BattUvHi_Volt_f32	9.84519958
k_BattUvLo_Volt_f32	2.54789996
k_CAVNTCEnableTimeout_mS_u16	4139
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	65184
k_CAVNodeTimeout_mS_u16	55827
k_CMM388MsgTimeout_mS_u16	23216
k_CMM388NTCEnableTimeout_mS_u16	23660
k_CMMNTCEnableTimeout_mS_u16	10037
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	6816
k_CONSANGLECPKMax_HwDeg_f32	728.086487
k_CONSANGLECPKMin_HwDeg_f32	-540.980713
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	10588
k_CONSANGLECPKSigValidThresh_Cnt_u16	48612
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	54754
k_CPKVehicleSpeedValidThresh_Cnt_u16	16740
k_CityParkInputInvalidThresh_Cnt_u16	21981
k_CityParkInputValidThresh_Cnt_u16	35522
k_ComputerRazGCTSigValidThresh_Cnt_u16	24323
k_CptTemporelSigValidThresh_Cnt_u16	51560
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	45510
k_DMDFCTCPKSigValidThresh_Cnt_u16	30631
k_DMDFCTCPKValidCount_Cnt_u16	17136
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	19840
k_DMDRELAXECPKSigValidThresh_Cnt_u16	8377
k_DMDRelaxeConsistentThresh_Cnt_u16	41119
k_DateValidThresh_Cnt_u16	18544
k_DefaultVehSpd_Kph_f32	226.798798
k_DiagMuxOnAbsentTimeout_mS_u16	23489
k_EMNodeTimeout_mS_u16	61580
k_ESPNTCEnableTimeout_mS_u16	1662
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	38440
k_EtatMTSigInvalidThresh_Cnt_u16	26446
k_EtatMTSigValidThresh_Cnt_u16	61543
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	693
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	1138
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	41683
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	34994
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	10327
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	25781
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	568
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	23525
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	47623
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	19855
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	7492
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	59049
k_ISDATDIRASentDiag_Cnt_str.Threshold	3472

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	32212
k_ISDATDIRASentDiag_Cnt_str.NStep	26715
k_ISDATDIRASentTimeout_mS_u16	52787
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	39350
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	44933
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	48202
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	12919
k_ISDYNAASChkSumValidThresh_Cnt_u16	63568
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	27713
k_ISDYNAASMsgCountValidThresh_Cnt_u16	43890
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	3003
k_ISDYNAASMsgLenValidThresh_Cnt_u16	49216
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	30819
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	63652
k_ISDYNABRChkSumValidThresh_Cnt_u16	51461
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	8552
k_ISDYNABRMsgCountValidThresh_Cnt_u16	26745
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	1663
k_ISDYNABRMsgLenValidThresh_Cnt_u16	55148
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	29104
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	11799
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	30402
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	40627
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	51449
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	19146
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	17997
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	33244
k_ISDYNVOLChkSumValidThresh_Cnt_u16	14513
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	41793
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	64660
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	50242
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	7455
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	2374
k_IgnOnTimeout_mS_u16	48280
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	3.11380005
k_PowerCutVehSpdLowThresh_Kph_f32	164.246597
k_PowerCutVehSpdLowTimeout_mS_u16	60478
k_VBattMaxAAS_Volt_f32	31.5855999
k_VBattMaxBSI_Volt_f32	22.3211994
k_VBattMaxCAV_Volt_f32	3.8210001
k_VBattMaxCMM388_Volt_f32	31.6937008
k_VBattMaxCMM_Volt_f32	23.0874004
k_VBattMaxESP_Volt_f32	29.8938999
k_VBattMinAAS_Volt_f32	16.9913998
k_VBattMinBSI_Volt_f32	29.8938999
k_VBattMinCAV_Volt_f32	3.21519995
k_VBattMinCMM388_Volt_f32	0.919799984
k_VBattMinCMM_Volt_f32	13.1259003
k_VBattMinESP_Volt_f32	23.0874004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	59088
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	55381
k_VitesseVehicleBVRampValidThresh_Cnt_u16	52335
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	13910
k_VitesseVehicleBVSigValidThresh_Cnt_u16	56651
k_VitesseVehicleBVSpeedPassThresh_kph_f32	36.4695015
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	18114
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	37675
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3856535552
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	33485
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	130
target_SrlComInput_Per1_Batt_Volt_f32.value	18.3892994
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2508292096
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	226
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.725366652
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3320262656
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4182331392
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	182
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	737898496
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2784858112
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2941235200
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2414989312
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2414080000
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	54
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	147
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	149
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	176
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	190
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	226
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	18
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2993590272
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	36
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	156
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	157
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	184
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	211
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2751082496
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4141633536
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	151941120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	52
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	91
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	115
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	213
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	226
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2028273664
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	610
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.255301356
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	682345
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	15.0875998
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	18541

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	3319	3319	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	14827	14827	✔
CONSANGLECPK_HwDeg_M_f32	634.887024	634.887024 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1713429248	1713429248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	979	979	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1085	1085	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1713429248	1713429248	✔
ElecIntTimer_mS_M_u32[1]	98	98	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	3439144960	3439144960	✔
IgnTimeOff_Sec_M_u32	1846679993	1846679993	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	125	125	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3320262656	3320262656	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	172	172	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4182331392	4182331392	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	182	182	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	737898496	737898496	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	227	227	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2784858112	2784858112	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2495115264	2495115264	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	200	200	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2414989312	2414989312	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	15	15	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2414080000	2414080000	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	18	18	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2993590272	2993590272	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	211	211	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2751082496	2751082496	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	194	194	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4141633536	4141633536	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	75	75	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	151941120	151941120	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2028273664	2028273664	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	152.592194	152.592194	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	176.665695	176.665695	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	281.295593	281.295593	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	14827	14827	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1846679993	1846679993	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	634.887024	634.887024 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	226.798798	226.798798	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.295 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3853755136
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	61452
AASNodeAbsentTimer_mS_M_u32	1383682816
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	26418
ANGLEVOLANTSigValidCount_Cnt_M_u16	20863
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	42125
AngleVolantMsgTimer_mS_M_u32	3853755136
AngleVolantValidCount_Cnt_M_u16	58404
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1873023744
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3729036032
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2800927488
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	305693440
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	55781
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1764049664
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	31319
CAVNodeAbsentTimer_mS_M_u32	1692168960
CDD_SrlComVehSpd_Kph_G_f32	265.405792
CMM388NTCEnableTimer_mS_M_u32	2133701376
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1915384576
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	43999
CMMNodeAbsentTimer_mS_M_u32	3714745088
CONSANGLECPKSigInvalidCount_Cnt_M_u16	33817
CONSANGLECPKSigValidCount_Cnt_M_u16	29174
CONSANGLECPK_Cnt_M_u16	22045
CONSANGLECPK_HwDeg_M_f32	87.4320984
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	22045
CPKVehicleSpeedMsgTimer_mS_M_u32	1761518336
CPKVehicleSpeedValidCount_Cnt_M_u16	21963
CityParkInputConsistentCount_Cnt_M_u16	43864

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	19743
CityParkInputMsgTimer_mS_M_u32	3320262656
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3870118656
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	17728
ComputerRazGCTSigInvalidTimer_mS_M_u32	827781888
ComputerRazGCTSigValidCount_Cnt_M_u16	4081
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	4587
DMDFCTCPKSigValidCount_Cnt_M_u16	38848
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	3532
DMDRELAXECPKSigValidCount_Cnt_M_u16	38809
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	50586
DateInvalidTimer_mS_M_u32	3729036032
DiagMuxOnAbsentTimer_mS_M_u32	3103810304
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	305693440
ESPNTCEnableTimer_mS_M_u32	4193145600
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	6360
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	6
EffacDefaultDiagTimer_mS_M_u32[1]	16
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	66
ElecIntTimer_mS_M_u32[1]	78
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1839153920
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	54729
EtatMTSigValidCount_Cnt_M_u16	51778
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	30899
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	34320
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	9998
ISDAT4V2BSI552MsgTimer_mS_M_u32	4036920064
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	166
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	6840
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	51778
ISDATBSI3F2MsgTimer_mS_M_u32	3160826624
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	53130
ISDATBSI412MsgLenValidCount_Cnt_M_u16	2443
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	54729
ISDATBSI412MsgTimer_mS_M_u32	655991552
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	32275
ISDATBSI432MsgLenValidCount_Cnt_M_u16	59916
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	60268
ISDATDIRASentFltAcc_Cnt_M_u16	38896
ISDATDIRASentTimer_mS_M_u32	1761518336
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	14851
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	58404
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	11294
ISDYN2CMMMsgTimer_mS_M_u32	1000362752
ISDYNAASChkSumInvalidCount_Cnt_M_u16	4774
ISDYNAASChkSumValidCount_Cnt_M_u16	5267
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	15447
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	40894
ISDYNAASMsgLenValidCount_Cnt_M_u16	39299
ISDYNAASMsgTimeValidCount_Cnt_M_u16	4774
ISDYNAASMsgTimer_mS_M_u32	2365174528
ISDYNABRChkSumInvalidCount_Cnt_M_u16	7223
ISDYNABRChkSumValidCount_Cnt_M_u16	23148
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	16217
ISDYNABRMsgCountValidCount_Cnt_M_u16	29062
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	53196
ISDYNABRMsgLenValidCount_Cnt_M_u16	11753
ISDYNABRMsgTimeValidCount_Cnt_M_u16	22045
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	52584

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	9122
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	51778
ISDYNCMM208MsgTimer_mS_M_u32	3313308416
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	52584
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	9122
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	6282
ISDYNCMM388MsgTimer_mS_M_u32	590557952
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	40831
ISDYNVOLChkSumValidCount_Cnt_M_u16	28124
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	35921
ISDYNVOLMsgCountValidCount_Cnt_M_u16	12966
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	34597
ISDYNVOLMsgLenValidCount_Cnt_M_u16	15715
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	43999
ISDYNVOLMsgTimer_mS_M_u32	3676500736
IgnOnTimer_mS_M_u32	224867072
IgnTimeOff_Sec_M_u32	1099228737
ManVehSpd_Kph_M_f32	503.538208
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	172
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	63
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3876872960
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	195
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1007010560
PrevISDATBSI412MsgDLCError_Cnt_M_u08	234
PrevISDATBSI412MsgRxTime_MSec_M_u32	3954275072
PrevISDATBSI432MsgDLCError_Cnt_M_u08	115
PrevISDATBSI432MsgRxTime_MSec_M_u32	1817334528
PrevISDATDIRAMsgTxTime_MSec_M_u32	3006624512
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	190
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2597061376
PrevISDYNAASMsgDLCError_Cnt_M_u08	247
PrevISDYNAASMsgRxTime_MSec_M_u32	2802381568
PrevISDYNABRMsgDLCError_Cnt_M_u08	165
PrevISDYNABRMsgRxTime_MSec_M_u32	1476342528
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	183
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1751249664
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	143
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2977518336
PrevISDYNVOLMsgDLCError_Cnt_M_u08	239
PrevISDYNVOLMsgRxTime_MSec_M_u32	3032642304
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2541724416
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	612.288696
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	22564
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	62057
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	47601
VitesseVehicleBVRampValidCount_Cnt_M_u16	1014
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	30847
VitesseVehicleBVSigValidCount_Cnt_M_u16	45708

Name	Input Value
VitesseVehicleBV_Kph_M_f32	45.2495995
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	6282
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	43695
VitesseVehiculeRoues_Kph_M_f32	360.779388
k_AASNTCEnableTimeout_mS_u16	62632
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	25635
k_AASNodeTimeout_mS_u16	53609
k_ABSNodeTimeout_mS_u16	44676
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	24658
k_ANGLEVOLANTSigValidThresh_Cnt_u16	19851
k_AngleVolantInvalidThresh_Cnt_u16	27302
k_AngleVolantValidThresh_Cnt_u16	19743
k_BSI552MsgTimeout_mS_u16	51082
k_BSINTCEnableTimeout_mS_u16	63659
k_BSINodeAbsentDiag_Cnt_str.Threshold	26856
k_BSINodeAbsentDiag_Cnt_str.PStep	13418
k_BSINodeAbsentDiag_Cnt_str.NStep	55344
k_BSINodeAbsentTimeout_mS_u16	14629
k_BSINodeTimeout_mS_u16	60268
k_BattOvHi_Volt_f32	28.1987991
k_BattOvLo_Volt_f32	7.94010019
k_BattUvHi_Volt_f32	26.6881008
k_BattUvLo_Volt_f32	31.5
k_CAVNTCEnableTimeout_mS_u16	20509
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	59837
k_CAVNodeTimeout_mS_u16	59877
k_CMM388MsgTimeout_mS_u16	3852
k_CMM388NTCEnableTimeout_mS_u16	63960
k_CMMNTCEnableTimeout_mS_u16	34622
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	25467
k_CONSANGLECPKMax_HwDeg_f32	729.603088
k_CONSANGLECPKMin_HwDeg_f32	0
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	46986
k_CONSANGLECPKSigValidThresh_Cnt_u16	35247
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	6071
k_CPKVehicleSpeedValidThresh_Cnt_u16	1457
k_CityParkInputInvalidThresh_Cnt_u16	26885
k_CityParkInputValidThresh_Cnt_u16	43864
k_ComputerRazGCTSigValidThresh_Cnt_u16	38868
k_CptTemporelSigValidThresh_Cnt_u16	22630
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	61132
k_DMDFCTCPKSigValidThresh_Cnt_u16	36073
k_DMDFCTCPKValidCount_Cnt_u16	46157
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	11294
k_DMDRELAXECPKSigValidThresh_Cnt_u16	563
k_DMDRelaxeConsistentThresh_Cnt_u16	39553
k_DateValidThresh_Cnt_u16	9998
k_DefaultVehSpd_Kph_f32	237.223694
k_DiagMuxOnAbsentTimeout_mS_u16	51355
k_EMNodeTimeout_mS_u16	51834
k_ESPNTCEnableTimeout_mS_u16	51747
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	4323
k_EtatMTSigInvalidThresh_Cnt_u16	14514
k_EtatMTSigValidThresh_Cnt_u16	27943
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	40254
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	63431
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	59173
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	38599
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	47001
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	8126
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	48052

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	52845
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	36935
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	43825
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	31698
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	47841
k_ISDATDIRASentDiag_Cnt_str.Threshold	64711
k_ISDATDIRASentDiag_Cnt_str.PStep	35441
k_ISDATDIRASentDiag_Cnt_str.NStep	35487
k_ISDATDIRASentTimeout_mS_u16	55299
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	5562
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	42125
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	55487
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	47927
k_ISDYNAASChkSumValidThresh_Cnt_u16	14700
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	24153
k_ISDYNAASMsgCountValidThresh_Cnt_u16	53382
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	16235
k_ISDYNAASMsgLenValidThresh_Cnt_u16	20637
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	61683
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	4658
k_ISDYNABRChkSumValidThresh_Cnt_u16	37071
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	63717
k_ISDYNABRMsgCountValidThresh_Cnt_u16	54130
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	35551
k_ISDYNABRMsgLenValidThresh_Cnt_u16	14296
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	21453
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	63320
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	23959
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	16708
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	34354
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	45183
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	46519
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	9289
k_ISDYNVOLChkSumValidThresh_Cnt_u16	49034
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	26713
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	15520
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	28309
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	17343
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	48268
k_IgnOnTimeout_mS_u16	25621
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	22.7789001
k_PowerCutVehSpdLowThresh_Kph_f32	59.3804016
k_PowerCutVehSpdLowTimeout_mS_u16	19236
k_VBattMaxAAS_Volt_f32	24.8194008
k_VBattMaxBSI_Volt_f32	21.4815006
k_VBattMaxCAV_Volt_f32	15.3972998
k_VBattMaxCMM388_Volt_f32	12.0232
k_VBattMaxCMM_Volt_f32	29.302
k_VBattMaxESP_Volt_f32	6.91690016
k_VBattMinAAS_Volt_f32	21.132
k_VBattMinBSI_Volt_f32	6.91690016
k_VBattMinCAV_Volt_f32	4.80749989
k_VBattMinCMM388_Volt_f32	21.8125992
k_VBattMinCMM_Volt_f32	3.46700001
k_VBattMinESP_Volt_f32	29.302
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	5740
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	49565
k_VitesseVehicleBVRampValidThresh_Cnt_u16	11089
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	52444
k_VitesseVehicleBVSigValidThresh_Cnt_u16	6077
k_VitesseVehicleBVSpeedPassThresh_kph_f32	243.426102
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	6487
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	17372
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3729036032
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	13090
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	143
target_SrlComInput_Per1_Batt_Volt_f32.value	1.90970004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3910812416
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	65
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.386954188
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1252602624
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1627575040
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	122
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3110892288
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	130
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2078675712
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3496981248
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3741930240
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3484611328
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	44
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	154
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	162
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	208
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	249
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1519588096
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	57
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	128
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	163
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	239
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	204
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3161469696
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	18
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1950995200
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	775123712
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	12
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	176
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	199
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	753910528
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	938
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.278495789
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1002178
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	60.1072006

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	32854		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	503.538208	503.538208	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	22045	22045	✔
CONSANGLECPK_HwDeg_M_f32	87.4320984	87.4320984 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1713429248	1713429248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	6	6	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	16	16	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	66	66	✔
ElecIntTimer_mS_M_u32[1]	78	78	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	9998	9998	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	51778	51778	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	54729	54729	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	60268	60268	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	11294	11294	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	4774	4774	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	22045	22045	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	51778	51778	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	6282	6282	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	43999	43999	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	224867072	224867072	✔
IgnTimeOff_Sec_M_u32	1099228737	1099228737	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	195	195	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1252602624	1252602624	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	72	72	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1627575040	1627575040	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	122	122	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3110892288	3110892288	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	130	130	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2078675712	2078675712	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3006624512	3006624512	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	181	181	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3741930240	3741930240	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	48	48	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3484611328	3484611328	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	249	249	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1519588096	1519588096	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	204	204	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3161469696	3161469696	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	18	18	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1950995200	1950995200	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	198	198	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	775123712	775123712	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	753910528	753910528	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	612.288696	612.288696	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	45.2495995	45.2495995	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	360.779388	360.779388	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	22045	22045	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1099228737	1099228737	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	87.4320984	87.4320984 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.296 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3771718144
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	50118
AASNodeAbsentTimer_mS_M_u32	222218752
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	6226
ANGLEVOLANTSigValidCount_Cnt_M_u16	18987
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	59971
AngleVolantMsgTimer_mS_M_u32	3771718144
AngleVolantValidCount_Cnt_M_u16	37372
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3502148096
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2799503872
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	26376704
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	113326592
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	19513
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2767911424
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	47460
CAVNodeAbsentTimer_mS_M_u32	3398789632
CDD_SrlComVehSpd_Kph_G_f32	11.8168001
CMM388NTCEnableTimer_mS_M_u32	1352772096
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1521183232
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	4747
CMMNodeAbsentTimer_mS_M_u32	3979033088
CONSANGLECPKSigInvalidCount_Cnt_M_u16	52382
CONSANGLECPKSigValidCount_Cnt_M_u16	13255
CONSANGLECPK_Cnt_M_u16	58194
CONSANGLECPK_HwDeg_M_f32	-76.3479996
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	58194
CPKVehicleSpeedMsgTimer_mS_M_u32	1122949632
CPKVehicleSpeedValidCount_Cnt_M_u16	5840
CityParkInputConsistentCount_Cnt_M_u16	3168
CityParkInputInvalidCount_Cnt_M_u16	4109
CityParkInputMsgTimer_mS_M_u32	1252602624
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	547539456
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	37930

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1864755712
ComputerRazGCTSigValidCount_Cnt_M_u16	33429
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	61865
DMDFCTCPKSigValidCount_Cnt_M_u16	28906
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	3204
DMDRELAXECPKSigValidCount_Cnt_M_u16	24541
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	19483
DateInvalidTimer_mS_M_u32	2799503872
DiagMuxOnAbsentTimer_mS_M_u32	2313787904
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	113326592
ESPNTCEnableTimer_mS_M_u32	719309312
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	27744
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	88
EffacDefaultDiagTimer_mS_M_u32[1]	108
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	101
ElecIntTimer_mS_M_u32[1]	105
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4287429120
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	0
EtatMTSigValidCount_Cnt_M_u16	45585
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	54992
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	57209
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	31488
ISDAT4V2BSI552MsgTimer_mS_M_u32	2207201792
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	39094
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	19266
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	45585
ISDATBSI3F2MsgTimer_mS_M_u32	2545392128
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	51468
ISDATBSI412MsgLenValidCount_Cnt_M_u16	56264
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0
ISDATBSI412MsgTimer_mS_M_u32	882760192
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	27631
ISDATBSI432MsgLenValidCount_Cnt_M_u16	51396
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	64037
ISDATDIRASentFltAcc_Cnt_M_u16	1177
ISDATDIRASentTimer_mS_M_u32	1122949632
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	20384
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	37372
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	12048
ISDYN2CMMMsgTimer_mS_M_u32	2915682816
ISDYNAASChkSumInvalidCount_Cnt_M_u16	17400
ISDYNAASChkSumValidCount_Cnt_M_u16	44784
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	5475
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	42287
ISDYNAASMsgLenValidCount_Cnt_M_u16	34976
ISDYNAASMsgTimeValidCount_Cnt_M_u16	17400
ISDYNAASMsgTimer_mS_M_u32	1463659008
ISDYNABRChkSumInvalidCount_Cnt_M_u16	42180
ISDYNABRChkSumValidCount_Cnt_M_u16	31460
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	18911
ISDYNABRMsgCountValidCount_Cnt_M_u16	9239
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	30085
ISDYNABRMsgLenValidCount_Cnt_M_u16	35822
ISDYNABRMsgTimeValidCount_Cnt_M_u16	58194
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	40993
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	33330
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	45585
ISDYNCMM208MsgTimer_mS_M_u32	1932757504
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	40993
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	33330
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	3274

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1519462912
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	37484
ISDYNVOLChkSumValidCount_Cnt_M_u16	22549
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	39543
ISDYNVOLMsgCountValidCount_Cnt_M_u16	47160
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	38265
ISDYNVOLMsgLenValidCount_Cnt_M_u16	9089
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	4747
ISDYNVOLMsgTimer_mS_M_u32	2713840128
IgnOnTimer_mS_M_u32	1811229184
IgnTimeOff_Sec_M_u32	2082419548
ManVehSpd_Kph_M_f32	535.107483
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	173
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	43
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1336777216
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	36
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1314486784
PrevISDATBSI412MsgDLCError_Cnt_M_u08	59
PrevISDATBSI412MsgRxTime_MSec_M_u32	3390466560
PrevISDATBSI432MsgDLCError_Cnt_M_u08	107
PrevISDATBSI432MsgRxTime_MSec_M_u32	1672727040
PrevISDATDIRAMsgTxTime_MSec_M_u32	2206886400
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	222
PrevISDYN2CMMMsgRxTime_MSec_M_u32	453425664
PrevISDYNAASMsgDLCError_Cnt_M_u08	182
PrevISDYNAASMsgRxTime_MSec_M_u32	1443883520
PrevISDYNABRMsgDLCError_Cnt_M_u08	236
PrevISDYNABRMsgRxTime_MSec_M_u32	3962382848
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	214
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3053775360
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	251
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4030646784
PrevISDYNVOLMsgDLCError_Cnt_M_u08	151
PrevISDYNVOLMsgRxTime_MSec_M_u32	4074990080
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4218149376
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	165.911896
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	37885
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	38382
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	58006
VitesseVehicleBVRampValidCount_Cnt_M_u16	54599
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	22635
VitesseVehicleBVSigValidCount_Cnt_M_u16	39684
VitesseVehicleBV_Kph_M_f32	69.7857971
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	3274
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	42778
VitesseVehiculeRoues_Kph_M_f32	516.63678
k_AASNTCEnableTimeout_mS_u16	62385
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	52735
k_AASNodeTimeout_mS_u16	63726
k_ABSNodeTimeout_mS_u16	49118
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	33074
k_ANGLEVOLANTSigValidThresh_Cnt_u16	23111
k_AngleVolantInvalidThresh_Cnt_u16	12022
k_AngleVolantValidThresh_Cnt_u16	4109
k_BSI552MsgTimeout_mS_u16	31881
k_BSINTCEnableTimeout_mS_u16	23591
k_BSINodeAbsentDiag_Cnt_str.Threshold	50976
k_BSINodeAbsentDiag_Cnt_str.PStep	28634
k_BSINodeAbsentDiag_Cnt_str.NStep	40905
k_BSINodeAbsentTimeout_mS_u16	35963
k_BSINodeTimeout_mS_u16	64037
k_BattOvHi_Volt_f32	7.0848999
k_BattOvLo_Volt_f32	18.8253994
k_BattUvHi_Volt_f32	9.39540005
k_BattUvLo_Volt_f32	8.90960026
k_CAVNTCEnableTimeout_mS_u16	32531
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	33586
k_CAVNodeTimeout_mS_u16	52026
k_CMM388MsgTimeout_mS_u16	26310
k_CMM388NTCEnableTimeout_mS_u16	54882
k_CMMNTCEnableTimeout_mS_u16	25838
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	44214
k_CONSANGLECPKMax_HwDeg_f32	739.687622
k_CONSANGLECPKMin_HwDeg_f32	-629.966003
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	12234
k_CONSANGLECPKSigValidThresh_Cnt_u16	2586
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	56836
k_CPKVehicleSpeedValidThresh_Cnt_u16	33431
k_CityParkInputInvalidThresh_Cnt_u16	30298
k_CityParkInputValidThresh_Cnt_u16	3168
k_ComputerRazGCTSigValidThresh_Cnt_u16	2860
k_CptTemporelSigValidThresh_Cnt_u16	51768
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	6277
k_DMDFCTCPKSigValidThresh_Cnt_u16	28398
k_DMDFCTCPKValidCount_Cnt_u16	23809
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	12048
k_DMDRELAXECPKSigValidThresh_Cnt_u16	48529
k_DMDRelaxeConsistentThresh_Cnt_u16	44199
k_DateValidThresh_Cnt_u16	31488
k_DefaultVehSpd_Kph_f32	104.746002
k_DiagMuxOnAbsentTimeout_mS_u16	984
k_EMNodeTimeout_mS_u16	48507
k_ESPNTCEnableTimeout_mS_u16	64000
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	17534
k_EtatMTSigInvalidThresh_Cnt_u16	64339
k_EtatMTSigValidThresh_Cnt_u16	61107
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	10607
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	64147
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	52473
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	39507
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	14495
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	43120
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	30476
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	57249
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	1363
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	13334
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	754
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	29702
k_ISDATDIRASentDiag_Cnt_str.Threshold	39837

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	59486
k_ISDATDIRASentDiag_Cnt_str.NStep	60819
k_ISDATDIRASentTimeout_mS_u16	41312
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	1915
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	59971
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	15916
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	51140
k_ISDYNAASChkSumValidThresh_Cnt_u16	56804
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	60639
k_ISDYNAASMsgCountValidThresh_Cnt_u16	1815
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	2856
k_ISDYNAASMsgLenValidThresh_Cnt_u16	19282
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	4111
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	50771
k_ISDYNABRChkSumValidThresh_Cnt_u16	31548
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	61241
k_ISDYNABRMsgCountValidThresh_Cnt_u16	20562
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	30091
k_ISDYNABRMsgLenValidThresh_Cnt_u16	3936
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	64321
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	34401
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	37605
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	54621
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	47954
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	11563
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	13893
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	34511
k_ISDYNVOLChkSumValidThresh_Cnt_u16	30155
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	49629
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	42056
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	29544
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	21677
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	12934
k_IgnOnTimeout_mS_u16	63339
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	76.5804977
k_PowerCutVehSpdLowThresh_Kph_f32	198.775803
k_PowerCutVehSpdLowTimeout_mS_u16	57405
k_VBattMaxAAS_Volt_f32	26.9160004
k_VBattMaxBSI_Volt_f32	31.3223
k_VBattMaxCAV_Volt_f32	3.32949996
k_VBattMaxCMM388_Volt_f32	3.71950006
k_VBattMaxCMM_Volt_f32	10.5031996
k_VBattMaxESP_Volt_f32	17.5561008
k_VBattMinAAS_Volt_f32	15.3871002
k_VBattMinBSI_Volt_f32	17.5561008
k_VBattMinCAV_Volt_f32	6.32070017
k_VBattMinCMM388_Volt_f32	23.948
k_VBattMinCMM_Volt_f32	24.1674995
k_VBattMinESP_Volt_f32	10.5031996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	19813
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	52370
k_VitesseVehicleBVRampValidThresh_Cnt_u16	48503
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	15125
k_VitesseVehicleBVSigValidThresh_Cnt_u16	39729
k_VitesseVehicleBVSpeedPassThresh_kph_f32	142.492493
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	56420
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	11669
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2799503872
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	54592
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1236548
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	251
target_SrlComInput_Per1_Batt_Volt_f32.value	13.1981001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	958134784
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	110
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0111433091
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1009723904
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3886172672
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	216361472
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	871926272
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3839601152
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	163
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2811152896
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	68282880
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	115
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	132
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	112
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2347862528
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	55
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	100
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	141
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	155
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	167
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	207
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3269077504
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	175
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2311932416
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2324720128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	83
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	90
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	165
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2744875520
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3773
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.654946566
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	220971
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	0.845399976
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	25447

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1236548	1236548	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1236548	1236548	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1236548	1236548	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1236548	1236548	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CDD_SrlComVehSpd_Kph_G_f32	535.107483	535.107483	✔
CMM388NTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	58194	58194	✔
CONSANGLECPK_HwDeg_M_f32	-76.3479996	-76.3479996 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1236548	1236548	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1236548	1236548	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1236548	1236548	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1236548	1236548	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1236548	1236548	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1236548	1236548	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1236548	1236548	✔
ESPNTCEnableTimer_mS_M_u32	1236548	1236548	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	88	88	✔
EffacDefaultDiagTimer_mS_M_u32[1]	108	108	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	101	101	✔
ElecIntTimer_mS_M_u32[1]	105	105	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1236548	1236548	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	31488	31488	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	45585	45585	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	64037	64037	✔
ISDATBSI432MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1236548	1236548	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	12048	12048	✔
ISDYN2CMMMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	17400	17400	✔
ISDYNAASMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	58194	58194	✔
ISDYNABRMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	45585	45585	✔
ISDYNCMM208MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	3274	3274	✔
ISDYNCMM388MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	4747	4747	✔
ISDYNVOLMsgTimer_mS_M_u32	1236548	1236548	✔
IgnOnTimer_mS_M_u32	1811229184	1811229184	✔
IgnTimeOff_Sec_M_u32	2082419548	2082419548	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	241	241	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1009723904	1009723904	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	51	51	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3886172672	3886172672	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	170	170	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	216361472	216361472	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	223	223	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	871926272	871926272	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2206886400	2206886400	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	163	163	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2811152896	2811152896	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	68282880	68282880	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	112	112	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2347862528	2347862528	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	178	178	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3269077504	3269077504	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	175	175	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2311932416	2311932416	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2324720128	2324720128	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2744875520	2744875520	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	165.911896	165.911896	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	69.7857971	69.7857971	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	516.63678	516.63678	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	58194	58194	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2082419548	2082419548	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-76.3479996	-76.3479996 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.297 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3373741312
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	6707
AASNodeAbsentTimer_mS_M_u32	3951715584
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	61070
ANGLEVOLANTSigValidCount_Cnt_M_u16	34500
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	55996
AngleVolantMsgTimer_mS_M_u32	3373741312
AngleVolantValidCount_Cnt_M_u16	45073
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1342907648
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1739564288
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	961500416
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1422071040
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	44761
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2434127104
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	31703
CAVNodeAbsentTimer_mS_M_u32	3590751488
CDD_SrlComVehSpd_Kph_G_f32	251.125198
CMM388NTCEnableTimer_mS_M_u32	3303130368
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4257514752
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	42787
CMMNodeAbsentTimer_mS_M_u32	3380942080
CONSANGLECPKSigInvalidCount_Cnt_M_u16	45226
CONSANGLECPKSigValidCount_Cnt_M_u16	59633
CONSANGLECPK_Cnt_M_u16	50768
CONSANGLECPK_HwDeg_M_f32	-117.885803
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	50768
CPKVehicleSpeedMsgTimer_mS_M_u32	3736745216
CPKVehicleSpeedValidCount_Cnt_M_u16	46142
CityParkInputConsistentCount_Cnt_M_u16	53477
CityParkInputInvalidCount_Cnt_M_u16	2781
CityParkInputMsgTimer_mS_M_u32	1009723904
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1096705280
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	14599

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3394569472
ComputerRazGCTSigValidCount_Cnt_M_u16	33350
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	54793
DMDFCTCPKSigValidCount_Cnt_M_u16	9736
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	23032
DMDRELAXECPKSigValidCount_Cnt_M_u16	36270
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	26163
DateInvalidTimer_mS_M_u32	1739564288
DiagMuxOnAbsentTimer_mS_M_u32	1690957056
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1422071040
ESPNTCEnableTimer_mS_M_u32	1453810944
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	46950
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1
EffacDefaultDiagTimer_mS_M_u32[1]	11
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	99
ElecIntTimer_mS_M_u32[1]	999
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1231017216
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	65535
EtatMTSigValidCount_Cnt_M_u16	15186
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	55828
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	11739
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	57286
ISDAT4V2BSI552MsgTimer_mS_M_u32	2522420480
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	34595
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	27966
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	15186
ISDATBSI3F2MsgTimer_mS_M_u32	4083152128
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	7969
ISDATBSI412MsgLenValidCount_Cnt_M_u16	42155
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	65535
ISDATBSI412MsgTimer_mS_M_u32	2242721024
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	10999
ISDATBSI432MsgLenValidCount_Cnt_M_u16	12858
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	64916
ISDATDIRASentFltAcc_Cnt_M_u16	44600
ISDATDIRASentTimer_mS_M_u32	3736745216
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	14694
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	45073
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	31188
ISDYN2CMMMsgTimer_mS_M_u32	4125713664
ISDYNAASChkSumInvalidCount_Cnt_M_u16	57757
ISDYNAASChkSumValidCount_Cnt_M_u16	20084
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	33244
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	42102
ISDYNAASMsgLenValidCount_Cnt_M_u16	34789
ISDYNAASMsgTimeValidCount_Cnt_M_u16	57757
ISDYNAASMsgTimer_mS_M_u32	554550528
ISDYNABRChkSumInvalidCount_Cnt_M_u16	18106
ISDYNABRChkSumValidCount_Cnt_M_u16	4632
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	11240
ISDYNABRMsgCountValidCount_Cnt_M_u16	19199
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	4597
ISDYNABRMsgLenValidCount_Cnt_M_u16	15484
ISDYNABRMsgTimeValidCount_Cnt_M_u16	50768
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	59346
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	37726
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	15186
ISDYNCMM208MsgTimer_mS_M_u32	2091656448
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	59346
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	37726
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	63399

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3306374400
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	5952
ISDYNVOLChkSumValidCount_Cnt_M_u16	13319
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	37791
ISDYNVOLMsgCountValidCount_Cnt_M_u16	2078
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	57371
ISDYNVOLMsgLenValidCount_Cnt_M_u16	9154
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	42787
ISDYNVOLMsgTimer_mS_M_u32	2726364416
IgnOnTimer_mS_M_u32	552027392
IgnTimeOff_Sec_M_u32	322412982
ManVehSpd_Kph_M_f32	218.908905
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	175
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	223
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	595457280
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	99
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	788157696
PrevISDATBSI412MsgDLCError_Cnt_M_u08	123
PrevISDATBSI412MsgRxTime_MSec_M_u32	461604096
PrevISDATBSI432MsgDLCError_Cnt_M_u08	137
PrevISDATBSI432MsgRxTime_MSec_M_u32	4230702336
PrevISDATDIRAMsgTxTime_MSec_M_u32	3207038208
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	57
PrevISDYN2CMMMsgRxTime_MSec_M_u32	234001664
PrevISDYNAASMsgDLCError_Cnt_M_u08	39
PrevISDYNAASMsgRxTime_MSec_M_u32	1033307392
PrevISDYNABRMsgDLCError_Cnt_M_u08	198
PrevISDYNABRMsgRxTime_MSec_M_u32	2151630080
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	170
PrevISDYNCMM208MsgRxTime_MSec_M_u32	834143488
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	48
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1116366080
PrevISDYNVOLMsgDLCError_Cnt_M_u08	42
PrevISDYNVOLMsgRxTime_MSec_M_u32	354190592
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3913495808
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	142.648193
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	36876
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	6139
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	18497
VitesseVehicleBVRampValidCount_Cnt_M_u16	65008
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	53827
VitesseVehicleBVSigValidCount_Cnt_M_u16	14393
VitesseVehicleBV_Kph_M_f32	572.036804
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	63399
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	13942
VitesseVehiculeRoues_Kph_M_f32	301.882202
k_AASNTCEnableTimeout_mS_u16	53555
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	51208
k_AASNodeTimeout_mS_u16	61179
k_ABSNodeTimeout_mS_u16	32618
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	46894
k_ANGLEVOLANTSigValidThresh_Cnt_u16	18865
k_AngleVolantInvalidThresh_Cnt_u16	18340
k_AngleVolantValidThresh_Cnt_u16	2781
k_BSI552MsgTimeout_mS_u16	12841
k_BSINTCEnableTimeout_mS_u16	14927
k_BSINodeAbsentDiag_Cnt_str.Threshold	34390
k_BSINodeAbsentDiag_Cnt_str.PStep	27238
k_BSINodeAbsentDiag_Cnt_str.NStep	35034
k_BSINodeAbsentTimeout_mS_u16	54292
k_BSINodeTimeout_mS_u16	64916
k_BattOvHi_Volt_f32	0.425900012
k_BattOvLo_Volt_f32	14.8112001
k_BattUvHi_Volt_f32	0.159400001
k_BattUvLo_Volt_f32	17.5811005
k_CAVNTCEnableTimeout_mS_u16	21963
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	54893
k_CAVNodeTimeout_mS_u16	9430
k_CMM388MsgTimeout_mS_u16	12595
k_CMM388NTCEnableTimeout_mS_u16	21087
k_CMMNTCEnableTimeout_mS_u16	635
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	38306
k_CONSANGLECPKMax_HwDeg_f32	30.969101
k_CONSANGLECPKMin_HwDeg_f32	-11.9968996
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	36519
k_CONSANGLECPKSigValidThresh_Cnt_u16	3446
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	6073
k_CPKVehicleSpeedValidThresh_Cnt_u16	56960
k_CityParkInputInvalidThresh_Cnt_u16	43512
k_CityParkInputValidThresh_Cnt_u16	53477
k_ComputerRazGCTSigValidThresh_Cnt_u16	34753
k_CptTemporelSigValidThresh_Cnt_u16	18524
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	10485
k_DMDFCTCPKSigValidThresh_Cnt_u16	37756
k_DMDFCTCPKValidCount_Cnt_u16	40065
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	31188
k_DMDRELAXECPKSigValidThresh_Cnt_u16	39955
k_DMDRelaxeConsistentThresh_Cnt_u16	42705
k_DateValidThresh_Cnt_u16	57286
k_DefaultVehSpd_Kph_f32	85.7883987
k_DiagMuxOnAbsentTimeout_mS_u16	64702
k_EMNodeTimeout_mS_u16	37395
k_ESPNTCEnableTimeout_mS_u16	10755
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	61002
k_EtatMTSigInvalidThresh_Cnt_u16	16141
k_EtatMTSigValidThresh_Cnt_u16	45739
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	41336
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	35787
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	13082
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	13900
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	22823
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	4341
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	48544
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	41379
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	61131
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	58372
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	46383
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	55090
k_ISDATDIRASentDiag_Cnt_str.Threshold	58959

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	33467
k_ISDATDIRASentDiag_Cnt_str.NStep	17654
k_ISDATDIRASentTimeout_mS_u16	49382
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	12499
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	55996
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	3455
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	56762
k_ISDYNAASChkSumValidThresh_Cnt_u16	59672
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	17128
k_ISDYNAASMsgCountValidThresh_Cnt_u16	41471
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	41870
k_ISDYNAASMsgLenValidThresh_Cnt_u16	34767
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	18521
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	55179
k_ISDYNABRChkSumValidThresh_Cnt_u16	9874
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	50649
k_ISDYNABRMsgCountValidThresh_Cnt_u16	53327
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	32291
k_ISDYNABRMsgLenValidThresh_Cnt_u16	52838
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	19330
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	18656
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	26006
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	54702
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	1422
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	56772
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	30773
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	45528
k_ISDYNVOLChkSumValidThresh_Cnt_u16	41634
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	60143
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	9708
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	35212
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	50046
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	20788
k_IgnOnTimeout_mS_u16	53252
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	136.785004
k_PowerCutVehSpdLowThresh_Kph_f32	98.1990967
k_PowerCutVehSpdLowTimeout_mS_u16	15247
k_VBattMaxAAS_Volt_f32	15.4195995
k_VBattMaxBSI_Volt_f32	19.0230007
k_VBattMaxCAV_Volt_f32	10.7365999
k_VBattMaxCMM388_Volt_f32	5.76370001
k_VBattMaxCMM_Volt_f32	7.55240011
k_VBattMaxESP_Volt_f32	1.70120001
k_VBattMinAAS_Volt_f32	18.7784996
k_VBattMinBSI_Volt_f32	1.70120001
k_VBattMinCAV_Volt_f32	22.0977993
k_VBattMinCMM388_Volt_f32	27.2884007
k_VBattMinCMM_Volt_f32	26.0820007
k_VBattMinESP_Volt_f32	7.55240011
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	34581
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	34640
k_VitesseVehicleBVRampValidThresh_Cnt_u16	10911
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	35591
k_VitesseVehicleBVSigValidThresh_Cnt_u16	43122
k_VitesseVehicleBVSpeedPassThresh_kph_f32	321.227997
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	4823
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	44294
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1739564288
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8524
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1813852160
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	48
target_SrlComInput_Per1_Batt_Volt_f32.value	3.78399992
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2561856768
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	59
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.776823342
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	149
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	406406400
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	101
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1247798528
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	211
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1326875904
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2388468992
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1882440960
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	230
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1553622272
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3146843392
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	94
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	187
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2859607296
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	10
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	46
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	94
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	195
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4030219520
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3487491328
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1108706560
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	131
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	167
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	216
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	224
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3073660160
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1903
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.98088026
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	530883
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	255
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	18894

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1813852160	1813852160	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
CDD_SrlComVehSpd_Kph_G_f32	218.908905	218.908905	✔
CMM388NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	50768	50768	✔
CONSANGLECPK_HwDeg_M_f32	-117.885803	-117.885803 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1813852160	1813852160	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1813852160	1813852160	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1813852160	1813852160	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1813852160	1813852160	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1813852160	1813852160	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1813852160	1813852160	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1813852160	1813852160	✔
ESPNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[1]	11	11	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	99	99	✔
ElecIntTimer_mS_M_u32[1]	999	999	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1813852160	1813852160	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	57286	57286	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	15186	15186	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	65535	65535	✔
ISDATBSI412MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	64916	64916	✔
ISDATBSI432MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1813852160	1813852160	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	31188	31188	✔
ISDYN2CMMMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	57757	57757	✔
ISDYNAASMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	50768	50768	✔
ISDYNABRMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	15186	15186	✔
ISDYNCMM208MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	63399	63399	✔
ISDYNCMM388MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	42787	42787	✔
ISDYNVOLMsgTimer_mS_M_u32	1813852160	1813852160	✔
IgnOnTimer_mS_M_u32	552027392	552027392	✔
IgnTimeOff_Sec_M_u32	322412982	322412982	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	149	149	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	406406400	406406400	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	101	101	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1247798528	1247798528	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	211	211	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1326875904	1326875904	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	72	72	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2388468992	2388468992	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3207038208	3207038208	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	230	230	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1553622272	1553622272	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	223	223	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3146843392	3146843392	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	186	186	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2859607296	2859607296	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	190	190	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4030219520	4030219520	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	92	92	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3487491328	3487491328	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	88	88	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1108706560	1108706560	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3073660160	3073660160	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	142.648193	142.648193	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	572.036804	572.036804	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	301.882202	301.882202	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	50768	50768	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	322412982	322412982	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-117.885803	-117.885803 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.298 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4084016128
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	4631
AASNodeAbsentTimer_mS_M_u32	2496893952
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	7944
ANGLEVOLANTSigValidCount_Cnt_M_u16	52516
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	13436
AngleVolantMsgTimer_mS_M_u32	4084016128
AngleVolantValidCount_Cnt_M_u16	20222
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1515279360
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1164170240
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	725926912
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1474921472
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	51751
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1576092672
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	9643
CAVNodeAbsentTimer_mS_M_u32	1843344384
CDD_SrlComVehSpd_Kph_G_f32	72.0446014
CMM388NTCEnableTimer_mS_M_u32	508392448
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1856320512
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	65415
CMMNodeAbsentTimer_mS_M_u32	2174977024
CONSANGLECPKSigInvalidCount_Cnt_M_u16	15281
CONSANGLECPKSigValidCount_Cnt_M_u16	18845
CONSANGLECPK_Cnt_M_u16	60800
CONSANGLECPK_HwDeg_M_f32	727.299011
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	60800
CPKVehicleSpeedMsgTimer_mS_M_u32	4270072832
CPKVehicleSpeedValidCount_Cnt_M_u16	10878
CityParkInputConsistentCount_Cnt_M_u16	15490
CityParkInputInvalidCount_Cnt_M_u16	49050
CityParkInputMsgTimer_mS_M_u32	406406400
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3814167552
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	1435

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3941839872
ComputerRazGCTSigValidCount_Cnt_M_u16	60511
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	3606
DMDFCTCPKSigValidCount_Cnt_M_u16	46297
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	1226
DMDRELAXECPKSigValidCount_Cnt_M_u16	57446
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	32534
DateInvalidTimer_mS_M_u32	1164170240
DiagMuxOnAbsentTimer_mS_M_u32	1532290048
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1474921472
ESPNTCEnableTimer_mS_M_u32	125604864
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	30079
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	12
EffacDefaultDiagTimer_mS_M_u32[1]	16
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	9
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3709027328
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	4631
EtatMTSigValidCount_Cnt_M_u16	60090
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	59251
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	41695
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	65439
ISDAT4V2BSI552MsgTimer_mS_M_u32	1797751808
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	2055
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	23671
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	60090
ISDATBSI3F2MsgTimer_mS_M_u32	2274550784
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	50447
ISDATBSI412MsgLenValidCount_Cnt_M_u16	64303
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	4631
ISDATBSI412MsgTimer_mS_M_u32	2511021056
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	50187
ISDATBSI432MsgLenValidCount_Cnt_M_u16	21763
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	54388
ISDATDIRASentFltAcc_Cnt_M_u16	21128
ISDATDIRASentTimer_mS_M_u32	4270072832
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	27710
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	20222
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	3765
ISDYN2CMMMsgTimer_mS_M_u32	2981532672
ISDYNAASChkSumInvalidCount_Cnt_M_u16	58329
ISDYNAASChkSumValidCount_Cnt_M_u16	37909
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	50589
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	59342
ISDYNAASMsgLenValidCount_Cnt_M_u16	37954
ISDYNAASMsgTimeValidCount_Cnt_M_u16	58329
ISDYNAASMsgTimer_mS_M_u32	3116987392
ISDYNABRChkSumInvalidCount_Cnt_M_u16	7684
ISDYNABRChkSumValidCount_Cnt_M_u16	53928
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	61688
ISDYNABRMsgCountValidCount_Cnt_M_u16	35444
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	976
ISDYNABRMsgLenValidCount_Cnt_M_u16	15100
ISDYNABRMsgTimeValidCount_Cnt_M_u16	60800
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	16681
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	18758
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	60090
ISDYNCMM208MsgTimer_mS_M_u32	2557367296
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	16681
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	18758
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	20540

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3283678208
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	57327
ISDYNVOLChkSumValidCount_Cnt_M_u16	16475
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	44372
ISDYNVOLMsgCountValidCount_Cnt_M_u16	59031
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	3936
ISDYNVOLMsgLenValidCount_Cnt_M_u16	31532
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	65415
ISDYNVOLMsgTimer_mS_M_u32	309310464
IgnOnTimer_mS_M_u32	3994624
IgnTimeOff_Sec_M_u32	242096076
ManVehSpd_Kph_M_f32	150.105499
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	176
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	205
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4013483008
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	243
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3057894400
PrevISDATBSI412MsgDLCError_Cnt_M_u08	148
PrevISDATBSI412MsgRxTime_MSec_M_u32	3513267200
PrevISDATBSI432MsgDLCError_Cnt_M_u08	143
PrevISDATBSI432MsgRxTime_MSec_M_u32	653300736
PrevISDATDIRAMsgTxTime_MSec_M_u32	1987851264
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	99
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1247478784
PrevISDYNAASMsgDLCError_Cnt_M_u08	56
PrevISDYNAASMsgRxTime_MSec_M_u32	422425600
PrevISDYNABRMsgDLCError_Cnt_M_u08	152
PrevISDYNABRMsgRxTime_MSec_M_u32	1110766592
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	10
PrevISDYNCMM208MsgRxTime_MSec_M_u32	13284352
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	147
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2413007872
PrevISDYNVOLMsgDLCError_Cnt_M_u08	68
PrevISDYNVOLMsgRxTime_MSec_M_u32	2292003840
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1122575360
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	648.730713
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	64780
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	48128
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	59501
VitesseVehicleBVRampValidCount_Cnt_M_u16	7713
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	34793
VitesseVehicleBVSigValidCount_Cnt_M_u16	52421
VitesseVehicleBV_Kph_M_f32	250.213104
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	20540
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	27280
VitesseVehiculeRoues_Kph_M_f32	474.842285
k_AASNTCEnableTimeout_mS_u16	6359
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	41753
k_AASNodeTimeout_mS_u16	14080
k_ABSNodeTimeout_mS_u16	54771
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	47974
k_ANGLEVOLANTSigValidThresh_Cnt_u16	43678
k_AngleVolantInvalidThresh_Cnt_u16	15557
k_AngleVolantValidThresh_Cnt_u16	49050
k_BSI552MsgTimeout_mS_u16	887
k_BSINTCEnableTimeout_mS_u16	62979
k_BSINodeAbsentDiag_Cnt_str.Threshold	11039
k_BSINodeAbsentDiag_Cnt_str.PStep	58414
k_BSINodeAbsentDiag_Cnt_str.NStep	32273
k_BSINodeAbsentTimeout_mS_u16	43124
k_BSINodeTimeout_mS_u16	54388
k_BattOvHi_Volt_f32	17.1240005
k_BattOvLo_Volt_f32	20.1471996
k_BattUvHi_Volt_f32	30.4284
k_BattUvLo_Volt_f32	27.7702999
k_CAVNTCEnableTimeout_mS_u16	5840
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	60905
k_CAVNodeTimeout_mS_u16	36653
k_CMM388MsgTimeout_mS_u16	52503
k_CMM388NTCEnableTimeout_mS_u16	6547
k_CMMNTCEnableTimeout_mS_u16	62975
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	64780
k_CONSANGLECPKMax_HwDeg_f32	629.207397
k_CONSANGLECPKMin_HwDeg_f32	-47.114399
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	35644
k_CONSANGLECPKSigValidThresh_Cnt_u16	58768
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	13510
k_CPKVehicleSpeedValidThresh_Cnt_u16	49906
k_CityParkInputInvalidThresh_Cnt_u16	27722
k_CityParkInputValidThresh_Cnt_u16	15490
k_ComputerRazGCTSigValidThresh_Cnt_u16	65069
k_CptTemporelSigValidThresh_Cnt_u16	49949
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	48848
k_DMDFCTCPKSigValidThresh_Cnt_u16	13820
k_DMDFCTCPKValidCount_Cnt_u16	41263
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	3765
k_DMDRELAXECPKSigValidThresh_Cnt_u16	16056
k_DMDRelaxeConsistentThresh_Cnt_u16	38526
k_DateValidThresh_Cnt_u16	65439
k_DefaultVehSpd_Kph_f32	223.833099
k_DiagMuxOnAbsentTimeout_mS_u16	33334
k_EMNodeTimeout_mS_u16	31606
k_ESPNTCEnableTimeout_mS_u16	52007
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	37652
k_EtatMTSigInvalidThresh_Cnt_u16	16651
k_EtatMTSigValidThresh_Cnt_u16	64751
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	21385
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	31569
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	10723
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	56972
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	31932
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	16275
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	61456
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	60104
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	51343
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	25700
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	14244
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	29147
k_ISDATDIRASentDiag_Cnt_str.Threshold	25385

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	45245
k_ISDATDIRASentDiag_Cnt_str.NStep	44580
k_ISDATDIRASentTimeout_mS_u16	24448
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	10488
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	13436
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	4275
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	22788
k_ISDYNAASChkSumValidThresh_Cnt_u16	19880
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	44024
k_ISDYNAASMsgCountValidThresh_Cnt_u16	34164
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	22408
k_ISDYNAASMsgLenValidThresh_Cnt_u16	48260
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	20134
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	35598
k_ISDYNABRChkSumValidThresh_Cnt_u16	21690
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	34087
k_ISDYNABRMsgCountValidThresh_Cnt_u16	56451
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	31367
k_ISDYNABRMsgLenValidThresh_Cnt_u16	12415
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	63210
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	8848
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	1456
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	3815
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	55816
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	51236
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	55186
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	43242
k_ISDYNVOLChkSumValidThresh_Cnt_u16	40266
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	16100
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	59180
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	18766
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	566
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	58197
k_IgnOnTimeout_mS_u16	65126
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	171.343307
k_PowerCutVehSpdLowThresh_Kph_f32	71.1010971
k_PowerCutVehSpdLowTimeout_mS_u16	18883
k_VBattMaxAAS_Volt_f32	13.9660997
k_VBattMaxBSI_Volt_f32	18.6891003
k_VBattMaxCAV_Volt_f32	23.3421001
k_VBattMaxCMM388_Volt_f32	16.6690006
k_VBattMaxCMM_Volt_f32	10.8839998
k_VBattMaxESP_Volt_f32	15.5146999
k_VBattMinAAS_Volt_f32	31.5718002
k_VBattMinBSI_Volt_f32	15.5146999
k_VBattMinCAV_Volt_f32	27.2535
k_VBattMinCMM388_Volt_f32	2.46510005
k_VBattMinCMM_Volt_f32	7.72779989
k_VBattMinESP_Volt_f32	10.8839998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	44594
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	13378
k_VitesseVehicleBVRampValidThresh_Cnt_u16	59476
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	15195
k_VitesseVehicleBVSigValidThresh_Cnt_u16	10715
k_VitesseVehicleBVSpeedPassThresh_kph_f32	444.366211
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	24747
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	59615
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1164170240
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	55763
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	810352896
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	147
target_SrlComInput_Per1_Batt_Volt_f32.value	4.6729002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4212802560
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	74
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.397420317
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3796300800
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2924680192
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1118778368
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	254
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1734038528
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3830936576
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2174981120
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	121615360
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	61
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	71
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	88
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	90
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2803651584
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	70
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	97
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	111
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	373945344
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3654685696
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	632435712
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	97
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2241184768
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1068
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.249480084
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	647852
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	142.227402
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	22470

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	810352896	810352896	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	810352896	810352896	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	810352896	810352896	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	810352896	810352896	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	810352896	810352896	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	810352896	810352896	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	810352896	810352896	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	810352896	810352896	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	810352896	810352896	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	810352896	810352896	✔
CDD_SrlComVehSpd_Kph_G_f32	150.105499	150.105499	✔
CMM388NTCEnableTimer_mS_M_u32	810352896	810352896	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	810352896	810352896	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	810352896	810352896	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	60800	60800	✔
CONSANGLECPK_HwDeg_M_f32	727.299011	727.299011 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	810352896	810352896	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	810352896	810352896	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	810352896	810352896	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	810352896	810352896	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	810352896	810352896	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	810352896	810352896	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	810352896	810352896	✔
ESPNTCEnableTimer_mS_M_u32	810352896	810352896	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	810352896	810352896	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	12	12	✔
EffacDefaultDiagTimer_mS_M_u32[1]	16	16	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	8	8	✔
ElecIntTimer_mS_M_u32[1]	9	9	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	810352896	810352896	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	65439	65439	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	810352896	810352896	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	60090	60090	✔
ISDATBSI3F2MsgTimer_mS_M_u32	810352896	810352896	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	4631	4631	✔
ISDATBSI412MsgTimer_mS_M_u32	810352896	810352896	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	54388	54388	✔
ISDATBSI432MsgTimer_mS_M_u32	810352896	810352896	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	810352896	810352896	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	3765	3765	✔
ISDYN2CMMMsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	58329	58329	✔
ISDYNAASMsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	60800	60800	✔
ISDYNABRMsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	60090	60090	✔
ISDYNCMM208MsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	20540	20540	✔
ISDYNCMM388MsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	65415	65415	✔
ISDYNVOLMsgTimer_mS_M_u32	810352896	810352896	✔
IgnOnTimer_mS_M_u32	3994624	3994624	✔
IgnTimeOff_Sec_M_u32	242096076	242096076	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	144	144	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3796300800	3796300800	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	99	99	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2924680192	2924680192	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	154	154	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1118778368	1118778368	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	254	254	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1734038528	1734038528	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1987851264	1987851264	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	106	106	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2174981120	2174981120	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	2	2	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	121615360	121615360	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	60	60	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2803651584	2803651584	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	373945344	373945344	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	59	59	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3654685696	3654685696	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	202	202	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	632435712	632435712	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2241184768	2241184768	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	648.730713	648.730713	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	250.213104	250.213104	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	474.842285	474.842285	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	60800	60800	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	242096076	242096076	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	727.299011	727.299011 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	150.105499	150.105499	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.299 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2061981440
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	59623
AASNodeAbsentTimer_mS_M_u32	2087978752
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	9238
ANGLEVOLANTSigValidCount_Cnt_M_u16	46466
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	21944
AngleVolantMsgTimer_mS_M_u32	2061981440
AngleVolantValidCount_Cnt_M_u16	0
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1392166656
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4223878912
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	971011840
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	921843456
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	24249
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4091213568
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	1196
CAVNodeAbsentTimer_mS_M_u32	668018432
CDD_SrlComVehSpd_Kph_G_f32	100.326302
CMM388NTCEnableTimer_mS_M_u32	2676385536
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3179226880
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	25560
CMMNodeAbsentTimer_mS_M_u32	566507264
CONSANGLECPKSigInvalidCount_Cnt_M_u16	42265
CONSANGLECPKSigValidCount_Cnt_M_u16	22293
CONSANGLECPK_Cnt_M_u16	46956
CONSANGLECPK_HwDeg_M_f32	225.217697
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	46956
CPKVehicleSpeedMsgTimer_mS_M_u32	1973573376
CPKVehicleSpeedValidCount_Cnt_M_u16	3098
CityParkInputConsistentCount_Cnt_M_u16	32294
CityParkInputInvalidCount_Cnt_M_u16	25056
CityParkInputMsgTimer_mS_M_u32	3796300800
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2699560704
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	7771

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2727585536
ComputerRazGCTSigValidCount_Cnt_M_u16	8847
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	26220
DMDFCTCPKSigValidCount_Cnt_M_u16	44512
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	64208
DMDRELAXECPKSigValidCount_Cnt_M_u16	956
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	44778
DateInvalidTimer_mS_M_u32	4223878912
DiagMuxOnAbsentTimer_mS_M_u32	2452625152
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	921843456
ESPNTCEnableTimer_mS_M_u32	142149376
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	3504
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	79
EffacDefaultDiagTimer_mS_M_u32[1]	99
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	5
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2121594624
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	39670
EtatMTSigValidCount_Cnt_M_u16	43774
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	10707
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	54095
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	25998
ISDAT4V2BSI552MsgTimer_mS_M_u32	1966618368
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	20697
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	16201
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	43774
ISDATBSI3F2MsgTimer_mS_M_u32	2239108864
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	35520
ISDATBSI412MsgLenValidCount_Cnt_M_u16	37920
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	39670
ISDATBSI412MsgTimer_mS_M_u32	204297984
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	9804
ISDATBSI432MsgLenValidCount_Cnt_M_u16	32548
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	23633
ISDATDIRASentFltAcc_Cnt_M_u16	12821
ISDATDIRASentTimer_mS_M_u32	1973573376
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	45874
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	41103
ISDYN2CMMMsgTimer_mS_M_u32	1909131008
ISDYNAASChkSumInvalidCount_Cnt_M_u16	64417
ISDYNAASChkSumValidCount_Cnt_M_u16	1710
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	3797
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	2627
ISDYNAASMsgLenValidCount_Cnt_M_u16	168
ISDYNAASMsgTimeValidCount_Cnt_M_u16	64417
ISDYNAASMsgTimer_mS_M_u32	3172099840
ISDYNABRChkSumInvalidCount_Cnt_M_u16	4257
ISDYNABRChkSumValidCount_Cnt_M_u16	44661
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	4164
ISDYNABRMsgCountValidCount_Cnt_M_u16	24465
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	35004
ISDYNABRMsgLenValidCount_Cnt_M_u16	48888
ISDYNABRMsgTimeValidCount_Cnt_M_u16	46956
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	21472
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	6986
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	43774
ISDYNCMM208MsgTimer_mS_M_u32	1285801728
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	21472
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	6986
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	43768

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3175343872
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	12383
ISDYNVOLChkSumValidCount_Cnt_M_u16	60123
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	178
ISDYNVOLMsgCountValidCount_Cnt_M_u16	37030
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	1037
ISDYNVOLMsgLenValidCount_Cnt_M_u16	7273
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	25560
ISDYNVOLMsgTimer_mS_M_u32	471836416
IgnOnTimer_mS_M_u32	397928192
IgnTimeOff_Sec_M_u32	2828157608
ManVehSpd_Kph_M_f32	578.246826
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	177
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	152
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1719932672
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	8
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1424193280
PrevISDATBSI412MsgDLCError_Cnt_M_u08	112
PrevISDATBSI412MsgRxTime_MSec_M_u32	1630938880
PrevISDATBSI432MsgDLCError_Cnt_M_u08	7
PrevISDATBSI432MsgRxTime_MSec_M_u32	2048722688
PrevISDATDIRAMsgTxTime_MSec_M_u32	3254396672
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	231
PrevISDYN2CMMMsgRxTime_MSec_M_u32	94222080
PrevISDYNAASMsgDLCError_Cnt_M_u08	145
PrevISDYNAASMsgRxTime_MSec_M_u32	2145756928
PrevISDYNABRMsgDLCError_Cnt_M_u08	183
PrevISDYNABRMsgRxTime_MSec_M_u32	835708672
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	255
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2098112256
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	26
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2339636992
PrevISDYNVOLMsgDLCError_Cnt_M_u08	44
PrevISDYNVOLMsgRxTime_MSec_M_u32	1335305984
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2087933696
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	241.862701
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	17033
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	366
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	17510
VitesseVehicleBVRampValidCount_Cnt_M_u16	40715
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	44403
VitesseVehicleBVSigValidCount_Cnt_M_u16	31391
VitesseVehicleBV_Kph_M_f32	81.1501999
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	43768
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	55228
VitesseVehiculeRoues_Kph_M_f32	508.42691
k_AASNTCEnableTimeout_mS_u16	20839
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	26209
k_AASNodeTimeout_mS_u16	36974
k_ABSNodeTimeout_mS_u16	49877
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	27707
k_ANGLEVOLANTSigValidThresh_Cnt_u16	43603
k_AngleVolantInvalidThresh_Cnt_u16	20446
k_AngleVolantValidThresh_Cnt_u16	25056
k_BSI552MsgTimeout_mS_u16	26887
k_BSINTCEnableTimeout_mS_u16	28772
k_BSINodeAbsentDiag_Cnt_str.Threshold	17791
k_BSINodeAbsentDiag_Cnt_str.PStep	60050
k_BSINodeAbsentDiag_Cnt_str.NStep	15656
k_BSINodeAbsentTimeout_mS_u16	55760
k_BSINodeTimeout_mS_u16	23633
k_BattOvHi_Volt_f32	31.5
k_BattOvLo_Volt_f32	14.1030998
k_BattUvHi_Volt_f32	19.2824993
k_BattUvLo_Volt_f32	8.43599987
k_CAVNTCEnableTimeout_mS_u16	46142
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	9202
k_CAVNodeTimeout_mS_u16	39589
k_CMM388MsgTimeout_mS_u16	47079
k_CMM388NTCEnableTimeout_mS_u16	49779
k_CMMNTCEnableTimeout_mS_u16	26353
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	4168
k_CONSANGLECPKMax_HwDeg_f32	50.1810989
k_CONSANGLECPKMin_HwDeg_f32	-175.194199
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	63992
k_CONSANGLECPKSigValidThresh_Cnt_u16	26300
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	12060
k_CPKVehicleSpeedValidThresh_Cnt_u16	56599
k_CityParkInputInvalidThresh_Cnt_u16	48591
k_CityParkInputValidThresh_Cnt_u16	32294
k_ComputerRazGCTSigValidThresh_Cnt_u16	34407
k_CptTemporelSigValidThresh_Cnt_u16	9047
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	22460
k_DMDFCTCPKSigValidThresh_Cnt_u16	52728
k_DMDFCTCPKValidCount_Cnt_u16	63905
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	41103
k_DMDRELAXECPKSigValidThresh_Cnt_u16	19523
k_DMDRelaxeConsistentThresh_Cnt_u16	56561
k_DateValidThresh_Cnt_u16	25998
k_DefaultVehSpd_Kph_f32	254.183502
k_DiagMuxOnAbsentTimeout_mS_u16	20810
k_EMNodeTimeout_mS_u16	14794
k_ESPNTCEnableTimeout_mS_u16	1080
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	28208
k_EtatMTSigInvalidThresh_Cnt_u16	33676
k_EtatMTSigValidThresh_Cnt_u16	2976
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	40659
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	29499
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	31235
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	8522
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	12922
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	11060
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	63037
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	4565
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	10432
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	58048
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	38080
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	1372
k_ISDATDIRASentDiag_Cnt_str.Threshold	25991

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	29762
k_ISDATDIRASentDiag_Cnt_str.NStep	4038
k_ISDATDIRASentTimeout_mS_u16	15405
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	37893
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	21944
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	25492
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	24481
k_ISDYNAASChkSumValidThresh_Cnt_u16	15733
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	57156
k_ISDYNAASMsgCountValidThresh_Cnt_u16	28305
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	29717
k_ISDYNAASMsgLenValidThresh_Cnt_u16	4066
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	56891
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	27394
k_ISDYNABRChkSumValidThresh_Cnt_u16	59838
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	11705
k_ISDYNABRMsgCountValidThresh_Cnt_u16	50021
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	62168
k_ISDYNABRMsgLenValidThresh_Cnt_u16	56496
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	53296
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	57853
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	36061
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	25785
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	62230
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	50306
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	63992
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	2863
k_ISDYNVOLChkSumValidThresh_Cnt_u16	55759
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	34177
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	33001
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	45954
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	21642
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	4716
k_IgnOnTimeout_mS_u16	64187
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	110.152702
k_PowerCutVehSpdLowThresh_Kph_f32	34.8792992
k_PowerCutVehSpdLowTimeout_mS_u16	28323
k_VBattMaxAAS_Volt_f32	16.8421001
k_VBattMaxBSI_Volt_f32	22.0734997
k_VBattMaxCAV_Volt_f32	2.73270011
k_VBattMaxCMM388_Volt_f32	21.5273991
k_VBattMaxCMM_Volt_f32	7.13899994
k_VBattMaxESP_Volt_f32	32
k_VBattMinAAS_Volt_f32	12.9771004
k_VBattMinBSI_Volt_f32	32
k_VBattMinCAV_Volt_f32	9.01290035
k_VBattMinCMM388_Volt_f32	12.0286999
k_VBattMinCMM_Volt_f32	24.3099003
k_VBattMinESP_Volt_f32	7.13899994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	27735
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	17895
k_VitesseVehicleBVRampValidThresh_Cnt_u16	20402
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	63963
k_VitesseVehicleBVSigValidThresh_Cnt_u16	23067
k_VitesseVehicleBVSpeedPassThresh_kph_f32	517.171875
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	21420
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	46801
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4223878912
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	44013
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2751184896
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	26
target_SrlComInput_Per1_Batt_Volt_f32.value	10.0668001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	6289152
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	101
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.391060591
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	429516544
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	89
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2381678336
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	44
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3915458304
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3554461440
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4117260032
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4127459072
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2108663552
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	212
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1486472960
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	153
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	176
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1234233088
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3614213888
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	207103744
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2934798080
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2263
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.793430805
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	267125
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	242.750595
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	39515

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2751184896	2751184896	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	21944	21944	✔
AngleVolantMsgTimer_mS_M_u32	2751184896	2751184896	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	17791	17791	✔
BSINodeAbsentTimer_mS_M_u32	2751184896	2751184896	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2751184896	2751184896	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2751184896	2751184896	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	46956	46956	✔
CONSANGLECPK_HwDeg_M_f32	225.217697	225.217697 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	46956	46956	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1973573376	1973573376	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	3098	3098	✔
CityParkInputConsistentCount_Cnt_M_u16	32294	32294	✔
CityParkInputInvalidCount_Cnt_M_u16	25058	25058	✔
CityParkInputMsgTimer_mS_M_u32	2751184896	2751184896	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2751184896	2751184896	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2751184896	2751184896	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2751184896	2751184896	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2751184896	2751184896	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2751184896	2751184896	✔
ESPNTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2751184896	2751184896	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	79	79	✔
EffacDefaultDiagTimer_mS_M_u32[1]	99	99	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2751184896	2751184896	✔
ElecIntTimer_mS_M_u32[1]	5	5	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2751184896	2751184896	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2751184896	2751184896	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2751184896	2751184896	✔
IgnOnTimer_mS_M_u32	2751184896	2751184896	✔
IgnTimeOff_Sec_M_u32	2828157608	2828157608	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	153	153	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	429516544	429516544	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	89	89	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2381678336	2381678336	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	44	44	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3915458304	3915458304	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	186	186	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3554461440	3554461440	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3254396672	3254396672	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	167	167	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4127459072	4127459072	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	86	86	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2108663552	2108663552	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1486472960	1486472960	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1234233088	1234233088	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	158	158	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3614213888	3614213888	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	106	106	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	207103744	207103744	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2934798080	2934798080	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	241.862701	241.862701	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	81.1501999	81.1501999	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	508.42691	508.42691	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	46956	46956	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2828157608	2828157608	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	225.217697	225.217697 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.300 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3238313472
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	6403
AASNodeAbsentTimer_mS_M_u32	186560000
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	16759
ANGLEVOLANTSigValidCount_Cnt_M_u16	47603
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	22160
AngleVolantMsgTimer_mS_M_u32	3238313472
AngleVolantValidCount_Cnt_M_u16	65535
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	311062016
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3660639744
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1352228352
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3496222208
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	56718
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	749329920
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	49715
CAVNodeAbsentTimer_mS_M_u32	1703366144
CDD_SrlComVehSpd_Kph_G_f32	188.659698
CMM388NTCEnableTimer_mS_M_u32	1667730944
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3699199488
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	56945
CMMNodeAbsentTimer_mS_M_u32	3622706688
CONSANGLECPKSigInvalidCount_Cnt_M_u16	14703
CONSANGLECPKSigValidCount_Cnt_M_u16	36922
CONSANGLECPK_Cnt_M_u16	35637
CONSANGLECPK_HwDeg_M_f32	216.479797
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	35637
CPKVehicleSpeedMsgTimer_mS_M_u32	2094251520
CPKVehicleSpeedValidCount_Cnt_M_u16	2610
CityParkInputConsistentCount_Cnt_M_u16	7111
CityParkInputInvalidCount_Cnt_M_u16	10648

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	429516544
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1841475072
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	18599
ComputerRazGCTSigInvalidTimer_mS_M_u32	524275200
ComputerRazGCTSigValidCount_Cnt_M_u16	4748
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	19444
DMDFCTCPKSigValidCount_Cnt_M_u16	49752
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	9545
DMDRELAXECPKSigValidCount_Cnt_M_u16	14149
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	40956
DateInvalidTimer_mS_M_u32	3660639744
DiagMuxOnAbsentTimer_mS_M_u32	2385149440
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3496222208
ESPNTCEnableTimer_mS_M_u32	3138366976
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	48552
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	68
EffacDefaultDiagTimer_mS_M_u32[1]	868
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1100
ElecIntTimer_mS_M_u32[1]	1151
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1960566272
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	33302
EtatMTSigValidCount_Cnt_M_u16	61118
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	4929
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	33676
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	54094
ISDAT4V2BSI552MsgTimer_mS_M_u32	2912034304
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1006
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	30045
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	61118
ISDATBSI3F2MsgTimer_mS_M_u32	1280867840
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	824
ISDATBSI412MsgLenValidCount_Cnt_M_u16	58327
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	33302
ISDATBSI412MsgTimer_mS_M_u32	2771566080
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	26389
ISDATBSI432MsgLenValidCount_Cnt_M_u16	14668
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	36676
ISDATDIRASentFltAcc_Cnt_M_u16	7672
ISDATDIRASentTimer_mS_M_u32	2094251520
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	12259
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	65535
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	59787
ISDYN2CMMMsgTimer_mS_M_u32	1192865280
ISDYNAASChkSumInvalidCount_Cnt_M_u16	18645
ISDYNAASChkSumValidCount_Cnt_M_u16	54384
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	58810
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	52590
ISDYNAASMsgLenValidCount_Cnt_M_u16	63234
ISDYNAASMsgTimeValidCount_Cnt_M_u16	18645
ISDYNAASMsgTimer_mS_M_u32	985894400
ISDYNABRChkSumInvalidCount_Cnt_M_u16	48983
ISDYNABRChkSumValidCount_Cnt_M_u16	45722
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	22252
ISDYNABRMsgCountValidCount_Cnt_M_u16	5575
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	55942
ISDYNABRMsgLenValidCount_Cnt_M_u16	42129
ISDYNABRMsgTimeValidCount_Cnt_M_u16	35637
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	44935
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	47628

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	61118
ISDYNCMM208MsgTimer_mS_M_u32	160394752
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	44935
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	47628
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	23889
ISDYNCMM388MsgTimer_mS_M_u32	3761180160
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	12189
ISDYNVOLChkSumValidCount_Cnt_M_u16	27880
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	5410
ISDYNVOLMsgCountValidCount_Cnt_M_u16	45574
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	36497
ISDYNVOLMsgLenValidCount_Cnt_M_u16	12861
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	56945
ISDYNVOLMsgTimer_mS_M_u32	3801861632
IgnOnTimer_mS_M_u32	2698186240
IgnTimeOff_Sec_M_u32	576113572
ManVehSpd_Kph_M_f32	556.628479
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	178
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	104
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1630436864
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	106
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3415236096
PrevISDATBSI412MsgDLCError_Cnt_M_u08	86
PrevISDATBSI412MsgRxTime_MSec_M_u32	2371374592
PrevISDATBSI432MsgDLCError_Cnt_M_u08	244
PrevISDATBSI432MsgRxTime_MSec_M_u32	4129533440
PrevISDATDIRAMsgTxTime_MSec_M_u32	2064403968
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	70
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1919000064
PrevISDYNAASMsgDLCError_Cnt_M_u08	207
PrevISDYNAASMsgRxTime_MSec_M_u32	1330236928
PrevISDYNABRMsgDLCError_Cnt_M_u08	138
PrevISDYNABRMsgRxTime_MSec_M_u32	2995457536
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	208
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1003408896
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	100
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3726552576
PrevISDYNVOLMsgDLCError_Cnt_M_u08	192
PrevISDYNVOLMsgRxTime_MSec_M_u32	2251640320
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3965763072
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	56.3272018
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	48284
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	36016
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	27397
VitesseVehicleBVRampValidCount_Cnt_M_u16	26585
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	22880
VitesseVehicleBVSigValidCount_Cnt_M_u16	7836
VitesseVehicleBV_Kph_M_f32	12.8797998

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	23889
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	25540
VitesseVehiculeRoues_Kph_M_f32	21.9370995
k_AASNTCEnableTimeout_mS_u16	26948
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	3862
k_AASNodeTimeout_mS_u16	57264
k_ABSNodeTimeout_mS_u16	6841
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	4424
k_ANGLEVOLANTSigValidThresh_Cnt_u16	13247
k_AngleVolantInvalidThresh_Cnt_u16	12062
k_AngleVolantValidThresh_Cnt_u16	10648
k_BSI552MsgTimeout_mS_u16	39907
k_BSINTCEnableTimeout_mS_u16	59597
k_BSINodeAbsentDiag_Cnt_str.Threshold	52268
k_BSINodeAbsentDiag_Cnt_str.PStep	27700
k_BSINodeAbsentDiag_Cnt_str.NStep	5039
k_BSINodeAbsentTimeout_mS_u16	10824
k_BSINodeTimeout_mS_u16	36676
k_BattOvHi_Volt_f32	19.3785
k_BattOvLo_Volt_f32	0.3125
k_BattUvHi_Volt_f32	6.70550013
k_BattUvLo_Volt_f32	30.7073002
k_CAVNTCEnableTimeout_mS_u16	10878
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	64609
k_CAVNodeTimeout_mS_u16	35019
k_CMM388MsgTimeout_mS_u16	44035
k_CMM388NTCEnableTimeout_mS_u16	48223
k_CMMNTCEnableTimeout_mS_u16	8614
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	59936
k_CONSANGLECPKMax_HwDeg_f32	434.381714
k_CONSANGLECPKMin_HwDeg_f32	-701.469971
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	28753
k_CONSANGLECPKSigValidThresh_Cnt_u16	46788
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	15270
k_CPKVehicleSpeedValidThresh_Cnt_u16	10291
k_CityParkInputInvalidThresh_Cnt_u16	61389
k_CityParkInputValidThresh_Cnt_u16	7111
k_ComputerRazGCTSigValidThresh_Cnt_u16	6980
k_CptTemporelSigValidThresh_Cnt_u16	33075
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	28038
k_DMDFCTCPKSigValidThresh_Cnt_u16	30609
k_DMDFCTCPKValidCount_Cnt_u16	44246
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	59787
k_DMDRELAXECPKSigValidThresh_Cnt_u16	13103
k_DMDRelaxeConsistentThresh_Cnt_u16	47397
k_DateValidThresh_Cnt_u16	54094
k_DefaultVehSpd_Kph_f32	93.6791992
k_DiagMuxOnAbsentTimeout_mS_u16	46491
k_EMNodeTimeout_mS_u16	32604
k_ESPNTCEnableTimeout_mS_u16	62351
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	28776
k_EtatMTSigInvalidThresh_Cnt_u16	53910
k_EtatMTSigValidThresh_Cnt_u16	1817
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	34945
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	10248
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	56368
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	38555
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	40906
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	61916
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	64322
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	34105

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	12217
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	22841
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	49145
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	4198
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	27827
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	18539
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	22160
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	17787
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	53847
k_ISDYNAASChkSumValidThresh_Cnt_u16	1434
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	59884
k_ISDYNAASMsgCountValidThresh_Cnt_u16	59591
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	25851
k_ISDYNAASMsgLenValidThresh_Cnt_u16	12628
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	14343
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	52148
k_ISDYNABRChkSumValidThresh_Cnt_u16	48191
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	28814
k_ISDYNABRMsgCountValidThresh_Cnt_u16	56394
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	12657
k_ISDYNABRMsgLenValidThresh_Cnt_u16	20648
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	41449
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	44608
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	45281
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	20175
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	54391
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	36083
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	49488
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	65003
k_ISDYNVOLChkSumValidThresh_Cnt_u16	36554
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	55861
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	2878
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	26738
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	8730
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	50356
k_IgnOnTimeout_mS_u16	24391
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	150.2715
k_PowerCutVehSpdLowThresh_Kph_f32	224.091797
k_PowerCutVehSpdLowTimeout_mS_u16	400
k_VBattMaxAAS_Volt_f32	10.6047001
k_VBattMaxBSI_Volt_f32	2.70950007
k_VBattMaxCAV_Volt_f32	10.8774996
k_VBattMaxCMM388_Volt_f32	24.1672001
k_VBattMaxCMM_Volt_f32	30.5617008
k_VBattMaxESP_Volt_f32	4.6262002
k_VBattMinAAS_Volt_f32	7.34350014
k_VBattMinBSI_Volt_f32	4.6262002
k_VBattMinCAV_Volt_f32	3.9928
k_VBattMinCMM388_Volt_f32	10.9944
k_VBattMinCMM_Volt_f32	21.9428005
k_VBattMinESP_Volt_f32	30.5617008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	34677
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	46981
k_VitesseVehicleBVRampValidThresh_Cnt_u16	10274
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	16360
k_VitesseVehicleBVSigValidThresh_Cnt_u16	39912
k_VitesseVehicleBVSpeedPassThresh_kph_f32	243.752594
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	54579
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	47239
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3660639744
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	100

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	31
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1528487424
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	46
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0382138491
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	128
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2737638912
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3164220928
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1624722944
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	225
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2548329984
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1774292480
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3731795456
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4260089344
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	45
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	109
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	179
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	124
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1034776064
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	50
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	106
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	250
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2940734976
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2083859968
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	150
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2482130432
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	78
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	108
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	148
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	238
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1701993984
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3252
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.837188423
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	374691
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	128.727798
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	32038

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	52268	52268	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	35637	35637	✔
CONSANGLECPK_HwDeg_M_f32	216.479797	216.479797 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1713429248	1713429248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1713429248	1713429248	✔
EffacDefaultDiagTimer_mS_M_u32[1]	868	868	✔
ElecIntCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	1713429248	1713429248	✔
ElecIntTimer_mS_M_u32[1]	1151	1151	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	1713429248	1713429248	✔
IgnTimeOff_Sec_M_u32	576113572	576113572	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	128	128	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2737638912	2737638912	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	151	151	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3164220928	3164220928	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	180	180	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1624722944	1624722944	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	225	225	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2548329984	2548329984	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2064403968	2064403968	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	135	135	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3731795456	3731795456	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	16	16	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4260089344	4260089344	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	124	124	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1034776064	1034776064	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	250	250	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2940734976	2940734976	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2083859968	2083859968	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	150	150	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2482130432	2482130432	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1701993984	1701993984	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	56.3272018	56.3272018	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	320.380005	320.380005	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	21.9370995	21.9370995	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	35637	35637	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	576113572	576113572	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	216.479797	216.479797 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.301 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2299037952
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	39693
AASNodeAbsentTimer_mS_M_u32	3195713792
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	37807
ANGLEVOLANTSigValidCount_Cnt_M_u16	41981
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	22118
AngleVolantMsgTimer_mS_M_u32	2299037952
AngleVolantValidCount_Cnt_M_u16	26723
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	121075968
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1782839552
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1959438592
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2422892800
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	56170
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3264817408
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	43515
CAVNodeAbsentTimer_mS_M_u32	2579552512
CDD_SrlComVehSpd_Kph_G_f32	183.527496
CMM388NTCEnableTimer_mS_M_u32	1897928960
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2363414784
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	43010
CMMNodeAbsentTimer_mS_M_u32	567044352
CONSANGLECPKSigInvalidCount_Cnt_M_u16	15048
CONSANGLECPKSigValidCount_Cnt_M_u16	61477
CONSANGLECPK_Cnt_M_u16	43828
CONSANGLECPK_HwDeg_M_f32	397.326385
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43828
CPKVehicleSpeedMsgTimer_mS_M_u32	1369147648
CPKVehicleSpeedValidCount_Cnt_M_u16	55080
CityParkInputConsistentCount_Cnt_M_u16	19264
CityParkInputInvalidCount_Cnt_M_u16	63180

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	2737638912
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	646887680
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	39969
ComputerRazGCTSigInvalidTimer_mS_M_u32	4002896128
ComputerRazGCTSigValidCount_Cnt_M_u16	47857
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	65464
DMDFCTCPKSigValidCount_Cnt_M_u16	46670
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	45113
DMDRELAXECPKSigValidCount_Cnt_M_u16	62471
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	31521
DateInvalidTimer_mS_M_u32	1782839552
DiagMuxOnAbsentTimer_mS_M_u32	3902228736
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2422892800
ESPNTCEnableTimer_mS_M_u32	2997336320
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	29723
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	117
EffacDefaultDiagTimer_mS_M_u32[1]	777
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2050
ElecIntTimer_mS_M_u32[1]	6071
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	839067904
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	57874
EtatMTSigValidCount_Cnt_M_u16	50652
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	30034
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	56879
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	56172
ISDAT4V2BSI552MsgTimer_mS_M_u32	820013312
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	29196
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	26493
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	50652
ISDATBSI3F2MsgTimer_mS_M_u32	3859630336
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	27949
ISDATBSI412MsgLenValidCount_Cnt_M_u16	54543
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	57874
ISDATBSI412MsgTimer_mS_M_u32	343836928
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	40470
ISDATBSI432MsgLenValidCount_Cnt_M_u16	37167
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	50888
ISDATDIRASentFltAcc_Cnt_M_u16	60076
ISDATDIRASentTimer_mS_M_u32	1369147648
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	62762
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	26723
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	17139
ISDYN2CMMMsgTimer_mS_M_u32	3062479104
ISDYNAASChkSumInvalidCount_Cnt_M_u16	54167
ISDYNAASChkSumValidCount_Cnt_M_u16	10884
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	31079
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	13386
ISDYNAASMsgLenValidCount_Cnt_M_u16	37199
ISDYNAASMsgTimeValidCount_Cnt_M_u16	54167
ISDYNAASMsgTimer_mS_M_u32	1527519488
ISDYNABRChkSumInvalidCount_Cnt_M_u16	20369
ISDYNABRChkSumValidCount_Cnt_M_u16	3975
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	50514
ISDYNABRMsgCountValidCount_Cnt_M_u16	33407
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	29571
ISDYNABRMsgLenValidCount_Cnt_M_u16	53024
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43828
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	4399
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	53089

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	50652
ISDYNCMM208MsgTimer_mS_M_u32	1982363904
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	4399
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	53089
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	11938
ISDYNCMM388MsgTimer_mS_M_u32	2026477824
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	36926
ISDYNVOLChkSumValidCount_Cnt_M_u16	37403
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	56366
ISDYNVOLMsgCountValidCount_Cnt_M_u16	8004
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	58720
ISDYNVOLMsgLenValidCount_Cnt_M_u16	13342
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	43010
ISDYNVOLMsgTimer_mS_M_u32	344152320
IgnOnTimer_mS_M_u32	3336411392
IgnTimeOff_Sec_M_u32	966444999
ManVehSpd_Kph_M_f32	237.830505
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	179
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	145
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2139834624
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	149
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2682628352
PrevISDATBSI412MsgDLCError_Cnt_M_u08	102
PrevISDATBSI412MsgRxTime_MSec_M_u32	2790119680
PrevISDATBSI432MsgDLCError_Cnt_M_u08	99
PrevISDATBSI432MsgRxTime_MSec_M_u32	1366014208
PrevISDATDIRAMsgTxTime_MSec_M_u32	2905725184
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	151
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2154948864
PrevISDYNAASMsgDLCError_Cnt_M_u08	101
PrevISDYNAASMsgRxTime_MSec_M_u32	108615936
PrevISDYNABRMsgDLCError_Cnt_M_u08	176
PrevISDYNABRMsgRxTime_MSec_M_u32	1907726592
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	127
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2498386176
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	18
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1165670656
PrevISDYNVOLMsgDLCError_Cnt_M_u08	78
PrevISDYNVOLMsgRxTime_MSec_M_u32	1874254080
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1995737344
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	360.036102
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	40640
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	2117
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	30597
VitesseVehicleBVRampValidCount_Cnt_M_u16	23242
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	12276
VitesseVehicleBVSigValidCount_Cnt_M_u16	23042
VitesseVehicleBV_Kph_M_f32	98.1125031

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	11938
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	29960
VitesseVehiculeRoues_Kph_M_f32	136.318298
k_AASNTCEnableTimeout_mS_u16	3335
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	27987
k_AASNodeTimeout_mS_u16	3909
k_ABSNodeTimeout_mS_u16	59241
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	11133
k_ANGLEVOLANTSigValidThresh_Cnt_u16	11734
k_AngleVolantInvalidThresh_Cnt_u16	30649
k_AngleVolantValidThresh_Cnt_u16	63180
k_BSI552MsgTimeout_mS_u16	2219
k_BSINTCEnableTimeout_mS_u16	63726
k_BSINodeAbsentDiag_Cnt_str.Threshold	59072
k_BSINodeAbsentDiag_Cnt_str.PStep	22761
k_BSINodeAbsentDiag_Cnt_str.NStep	33975
k_BSINodeAbsentTimeout_mS_u16	47934
k_BSINodeTimeout_mS_u16	50888
k_BattOvHi_Volt_f32	0.68690002
k_BattOvLo_Volt_f32	13.5462999
k_BattUvHi_Volt_f32	26.0739002
k_BattUvLo_Volt_f32	12.1813002
k_CAVNTCEnableTimeout_mS_u16	3098
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	13169
k_CAVNodeTimeout_mS_u16	48308
k_CMM388MsgTimeout_mS_u16	57869
k_CMM388NTCEnableTimeout_mS_u16	8441
k_CMMNTCEnableTimeout_mS_u16	63716
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	20980
k_CONSANGLECPKMax_HwDeg_f32	362.852692
k_CONSANGLECPKMin_HwDeg_f32	-149.6595
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	62882
k_CONSANGLECPKSigValidThresh_Cnt_u16	31752
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	21347
k_CPKVehicleSpeedValidThresh_Cnt_u16	43580
k_CityParkInputInvalidThresh_Cnt_u16	5679
k_CityParkInputValidThresh_Cnt_u16	19264
k_ComputerRazGCTSigValidThresh_Cnt_u16	1034
k_CptTemporelSigValidThresh_Cnt_u16	7163
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	47747
k_DMDFCTCPKSigValidThresh_Cnt_u16	22048
k_DMDFCTCPKValidCount_Cnt_u16	36242
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	17139
k_DMDRELAXECPKSigValidThresh_Cnt_u16	32713
k_DMDRelaxeConsistentThresh_Cnt_u16	17895
k_DateValidThresh_Cnt_u16	56172
k_DefaultVehSpd_Kph_f32	63.5513992
k_DiagMuxOnAbsentTimeout_mS_u16	17410
k_EMNodeTimeout_mS_u16	23809
k_ESPNTCEnableTimeout_mS_u16	34279
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	57116
k_EtatMTSigInvalidThresh_Cnt_u16	53716
k_EtatMTSigValidThresh_Cnt_u16	52746
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	39122
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	25596
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	60933
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	44549
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	56374
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	12609
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	54671
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	41320

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	54314
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	20776
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	42666
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	52898
k_ISDATDIRASentDiag_Cnt_str.Threshold	2451
k_ISDATDIRASentDiag_Cnt_str.PStep	5266
k_ISDATDIRASentDiag_Cnt_str.NStep	3881
k_ISDATDIRASentTimeout_mS_u16	46973
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	31379
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	22118
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	16419
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	5777
k_ISDYNAASChkSumValidThresh_Cnt_u16	5767
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	3154
k_ISDYNAASMsgCountValidThresh_Cnt_u16	2431
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	61093
k_ISDYNAASMsgLenValidThresh_Cnt_u16	43609
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	16638
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	55289
k_ISDYNABRChkSumValidThresh_Cnt_u16	49174
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	8810
k_ISDYNABRMsgCountValidThresh_Cnt_u16	22776
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	44802
k_ISDYNABRMsgLenValidThresh_Cnt_u16	47899
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	17435
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	22996
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	18482
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	65000
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	55983
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	11005
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	4004
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	2324
k_ISDYNVOLChkSumValidThresh_Cnt_u16	24630
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	37492
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	38299
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	40702
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	39880
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	7994
k_IgnOnTimeout_mS_u16	21760
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	252.274597
k_PowerCutVehSpdLowThresh_Kph_f32	230.813599
k_PowerCutVehSpdLowTimeout_mS_u16	29731
k_VBattMaxAAS_Volt_f32	28.3320007
k_VBattMaxBSI_Volt_f32	28.6210995
k_VBattMaxCAV_Volt_f32	21.6807003
k_VBattMaxCMM388_Volt_f32	3.78999996
k_VBattMaxCMM_Volt_f32	28.9183006
k_VBattMaxESP_Volt_f32	26.6417007
k_VBattMinAAS_Volt_f32	16.6849995
k_VBattMinBSI_Volt_f32	26.6417007
k_VBattMinCAV_Volt_f32	6.46659994
k_VBattMinCMM388_Volt_f32	3.31550002
k_VBattMinCMM_Volt_f32	25.0942001
k_VBattMinESP_Volt_f32	28.9183006
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	25973
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	40711
k_VitesseVehicleBVRampValidThresh_Cnt_u16	41774
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	6427
k_VitesseVehicleBVSigValidThresh_Cnt_u16	36573
k_VitesseVehicleBVSpeedPassThresh_kph_f32	39.4003983
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	28923
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	41152
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1782839552
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	18

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	19.3383007
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	994453760
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	184
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0536668748
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2815400192
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4161288448
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	149
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3889223936
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	140
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1596553472
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1175591168
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2223683840
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	43211008
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	205
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	32
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3519969536
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2944309504
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	116
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3845601536
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2055198976
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	43
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	174
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	207
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3661605120
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	653
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.658897102
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	742018
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	212.155701
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	1314

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	237.830505	237.830505	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	43828	43828	✔
CONSANGLECPK_HwDeg_M_f32	397.326385	397.326385 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1713429248	1713429248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	117	117	✔
EffacDefaultDiagTimer_mS_M_u32[1]	777	777	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	2050	2050	✔
ElecIntTimer_mS_M_u32[1]	6071	6071	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	56172	56172	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	50652	50652	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	57874	57874	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	50888	50888	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	17139	17139	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	54167	54167	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43828	43828	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	50652	50652	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	11938	11938	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	43010	43010	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	3336411392	3336411392	✔
IgnTimeOff_Sec_M_u32	966444999	966444999	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	251	251	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2815400192	2815400192	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	178	178	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4161288448	4161288448	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	149	149	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3889223936	3889223936	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	140	140	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1596553472	1596553472	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2905725184	2905725184	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	83	83	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2223683840	2223683840	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	245	245	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	43211008	43211008	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	32	32	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3519969536	3519969536	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	183	183	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2944309504	2944309504	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	116	116	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3845601536	3845601536	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	29	29	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2055198976	2055198976	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3661605120	3661605120	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	360.036102	360.036102	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	98.1125031	98.1125031	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	136.318298	136.318298	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	43828	43828	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	966444999	966444999	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	397.326385	397.326385 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.302 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3521718272
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	19931
AASNodeAbsentTimer_mS_M_u32	4132608000
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	3572
ANGLEVOLANTSigValidCount_Cnt_M_u16	28619
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	49104
AngleVolantMsgTimer_mS_M_u32	3521718272
AngleVolantValidCount_Cnt_M_u16	44284
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	4280047616
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2817972224
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1059244032
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	457410560
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	58051
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2948024320
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	401
CAVNodeAbsentTimer_mS_M_u32	2768254976
CDD_SrlComVehSpd_Kph_G_f32	362.808899
CMM388NTCEnableTimer_mS_M_u32	2883745792
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3282450432
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	3900
CMMNodeAbsentTimer_mS_M_u32	1864206336
CONSANGLECPKSigInvalidCount_Cnt_M_u16	27561
CONSANGLECPKSigValidCount_Cnt_M_u16	7760
CONSANGLECPK_Cnt_M_u16	59683
CONSANGLECPK_HwDeg_M_f32	73.8259964
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	59683
CPKVehicleSpeedMsgTimer_mS_M_u32	2217748480
CPKVehicleSpeedValidCount_Cnt_M_u16	2704
CityParkInputConsistentCount_Cnt_M_u16	5056
CityParkInputInvalidCount_Cnt_M_u16	37404
CityParkInputMsgTimer_mS_M_u32	2815400192
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	236361728
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	39583

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	545044480
ComputerRazGCTSigValidCount_Cnt_M_u16	51373
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	10072
DMDFCTCPKSigValidCount_Cnt_M_u16	46678
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	24662
DMDRELAXECPKSigValidCount_Cnt_M_u16	10157
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	20126
DateInvalidTimer_mS_M_u32	2817972224
DiagMuxOnAbsentTimer_mS_M_u32	1581049856
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	457410560
ESPNTCEnableTimer_mS_M_u32	231446528
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	28079
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	555
EffacDefaultDiagTimer_mS_M_u32[1]	5555
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	9900
ElecIntTimer_mS_M_u32[1]	11001
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2306426880
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	61963
EtatMTSigValidCount_Cnt_M_u16	51566
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	25611
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	64562
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	16124
ISDAT4V2BSI552MsgTimer_mS_M_u32	2447476736
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	414
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	17417
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	51566
ISDATBSI3F2MsgTimer_mS_M_u32	3185240064
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	9530
ISDATBSI412MsgLenValidCount_Cnt_M_u16	53333
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	61963
ISDATBSI412MsgTimer_mS_M_u32	2273781760
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	32000
ISDATBSI432MsgLenValidCount_Cnt_M_u16	26227
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	7978
ISDATDIRASentFltAcc_Cnt_M_u16	17278
ISDATDIRASentTimer_mS_M_u32	2217748480
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	44284
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	2471
ISDYN2CMMMsgTimer_mS_M_u32	170235904
ISDYNAASChkSumInvalidCount_Cnt_M_u16	19517
ISDYNAASChkSumValidCount_Cnt_M_u16	23092
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	58699
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	24228
ISDYNAASMsgLenValidCount_Cnt_M_u16	47699
ISDYNAASMsgTimeValidCount_Cnt_M_u16	19517
ISDYNAASMsgTimer_mS_M_u32	2652796928
ISDYNABRChkSumInvalidCount_Cnt_M_u16	14798
ISDYNABRChkSumValidCount_Cnt_M_u16	11437
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	8972
ISDYNABRMsgCountValidCount_Cnt_M_u16	65091
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	28024
ISDYNABRMsgLenValidCount_Cnt_M_u16	11615
ISDYNABRMsgTimeValidCount_Cnt_M_u16	59683
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	65125
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	10893
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	51566
ISDYNCMM208MsgTimer_mS_M_u32	3058259968
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	65125
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	10893
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	29082

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	451278848
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	49991
ISDYNVOLChkSumValidCount_Cnt_M_u16	36974
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	59894
ISDYNVOLMsgCountValidCount_Cnt_M_u16	54132
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	28128
ISDYNVOLMsgLenValidCount_Cnt_M_u16	54375
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	3900
ISDYNVOLMsgTimer_mS_M_u32	1589164032
IgnOnTimer_mS_M_u32	2158622720
IgnTimeOff_Sec_M_u32	1175533756
ManVehSpd_Kph_M_f32	6.97200012
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	180
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	189
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1767958528
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	145
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3922839552
PrevISDATBSI412MsgDLCError_Cnt_M_u08	94
PrevISDATBSI412MsgRxTime_MSec_M_u32	4082710528
PrevISDATBSI432MsgDLCError_Cnt_M_u08	231
PrevISDATBSI432MsgRxTime_MSec_M_u32	1098881024
PrevISDATDIRAMsgTxTime_MSec_M_u32	1856845824
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	202
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3375171584
PrevISDYNAASMsgDLCError_Cnt_M_u08	34
PrevISDYNAASMsgRxTime_MSec_M_u32	3772168192
PrevISDYNABRMsgDLCError_Cnt_M_u08	203
PrevISDYNABRMsgRxTime_MSec_M_u32	3760322560
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	125
PrevISDYNCMM208MsgRxTime_MSec_M_u32	964933632
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	216
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1632802816
PrevISDYNVOLMsgDLCError_Cnt_M_u08	54
PrevISDYNVOLMsgRxTime_MSec_M_u32	2065577984
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3089442816
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	494.750885
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	30530
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	44401
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	16627
VitesseVehicleBVRampValidCount_Cnt_M_u16	2530
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	36133
VitesseVehicleBVSigValidCount_Cnt_M_u16	41404
VitesseVehicleBV_Kph_M_f32	488.298798
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	29082
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	37161
VitesseVehiculeRoues_Kph_M_f32	177.548492
k_AASNTCEnableTimeout_mS_u16	53162
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	47495
k_AASNodeTimeout_mS_u16	39025
k_ABSNodeTimeout_mS_u16	29765
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	12491
k_ANGLEVOLANTSigValidThresh_Cnt_u16	60542
k_AngleVolantInvalidThresh_Cnt_u16	23253
k_AngleVolantValidThresh_Cnt_u16	37404
k_BSI552MsgTimeout_mS_u16	8768
k_BSINTCEnableTimeout_mS_u16	52344
k_BSINodeAbsentDiag_Cnt_str.Threshold	64305
k_BSINodeAbsentDiag_Cnt_str.PStep	44533
k_BSINodeAbsentDiag_Cnt_str.NStep	50125
k_BSINodeAbsentTimeout_mS_u16	61768
k_BSINodeTimeout_mS_u16	7978
k_BattOvHi_Volt_f32	10.5408001
k_BattOvLo_Volt_f32	7.47770023
k_BattUvHi_Volt_f32	4.77540016
k_BattUvLo_Volt_f32	2.11479998
k_CAVNTCEnableTimeout_mS_u16	2610
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	48431
k_CAVNodeTimeout_mS_u16	38373
k_CMM388MsgTimeout_mS_u16	30939
k_CMM388NTCEnableTimeout_mS_u16	27671
k_CMMNTCEnableTimeout_mS_u16	52502
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	43621
k_CONSANGLECPKMax_HwDeg_f32	18.9083996
k_CONSANGLECPKMin_HwDeg_f32	-725.353027
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	7322
k_CONSANGLECPKSigValidThresh_Cnt_u16	31785
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	50199
k_CPKVehicleSpeedValidThresh_Cnt_u16	27149
k_CityParkInputInvalidThresh_Cnt_u16	56820
k_CityParkInputValidThresh_Cnt_u16	5056
k_ComputerRazGCTSigValidThresh_Cnt_u16	50084
k_CptTemporelSigValidThresh_Cnt_u16	40591
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	39032
k_DMDFCTCPKSigValidThresh_Cnt_u16	39007
k_DMDFCTCPKValidCount_Cnt_u16	27723
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	2471
k_DMDRELAXECPKSigValidThresh_Cnt_u16	1509
k_DMDRelaxeConsistentThresh_Cnt_u16	43915
k_DateValidThresh_Cnt_u16	16124
k_DefaultVehSpd_Kph_f32	8.85659981
k_DiagMuxOnAbsentTimeout_mS_u16	54969
k_EMNodeTimeout_mS_u16	10494
k_ESPNTCEnableTimeout_mS_u16	7629
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	41709
k_EtatMTSigInvalidThresh_Cnt_u16	32517
k_EtatMTSigValidThresh_Cnt_u16	48420
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	28618
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	4365
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	32625
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	29107
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	2526
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	10494
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	64149
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	22984
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	10948
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	51015
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	10626
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	26074
k_ISDATDIRASentDiag_Cnt_str.Threshold	42732

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	3144
k_ISDATDIRASentDiag_Cnt_str.NStep	10267
k_ISDATDIRASentTimeout_mS_u16	45578
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	26119
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	49104
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	57113
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	58574
k_ISDYNAASChkSumValidThresh_Cnt_u16	6061
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	19980
k_ISDYNAASMsgCountValidThresh_Cnt_u16	26947
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	44178
k_ISDYNAASMsgLenValidThresh_Cnt_u16	5941
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	21254
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	38934
k_ISDYNABRChkSumValidThresh_Cnt_u16	45693
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	3523
k_ISDYNABRMsgCountValidThresh_Cnt_u16	64730
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	64060
k_ISDYNABRMsgLenValidThresh_Cnt_u16	39087
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	34673
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	38406
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	59435
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	6280
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	14580
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	56011
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	42900
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	44421
k_ISDYNVOLChkSumValidThresh_Cnt_u16	35552
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	46756
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	60017
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	27463
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	63402
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	11154
k_IgnOnTimeout_mS_u16	31169
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	159.187103
k_PowerCutVehSpdLowThresh_Kph_f32	135.569901
k_PowerCutVehSpdLowTimeout_mS_u16	2646
k_VBattMaxAAS_Volt_f32	25.5424995
k_VBattMaxBSI_Volt_f32	28.8645992
k_VBattMaxCAV_Volt_f32	29.9953995
k_VBattMaxCMM388_Volt_f32	17.7320004
k_VBattMaxCMM_Volt_f32	7.41260004
k_VBattMaxESP_Volt_f32	23.4913006
k_VBattMinAAS_Volt_f32	25.7756004
k_VBattMinBSI_Volt_f32	23.4913006
k_VBattMinCAV_Volt_f32	18.2422009
k_VBattMinCMM388_Volt_f32	7.13490009
k_VBattMinCMM_Volt_f32	8.92669964
k_VBattMinESP_Volt_f32	7.41260004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	44385
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	41836
k_VitesseVehicleBVRampValidThresh_Cnt_u16	38134
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	64366
k_VitesseVehicleBVSigValidThresh_Cnt_u16	64745
k_VitesseVehicleBVSpeedPassThresh_kph_f32	75.395401
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	44177
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	36864
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2817972224
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	216
target_SrlComInput_Per1_Batt_Volt_f32.value	8.79880047
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	967854080
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	224
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.32011947
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	634648576
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1604982784
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	244
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4207949824
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	155
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1061574656
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1963751424
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	24
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3827472384
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	127
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3565729792
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	97
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	135
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	230
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	239
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3143063552
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	85
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	117
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	180
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	197
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	199
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2328295424
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	337451008
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3200464896
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	19
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	133
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	172
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	196
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	583256064
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1190
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.177788481
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	527706
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	81.7938004
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	19484

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	6.97200012	6.97200012	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	59683	59683	✔
CONSANGLECPK_HwDeg_M_f32	73.8259964	73.8259964 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1713429248	1713429248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	555	555	✔
EffacDefaultDiagTimer_mS_M_u32[1]	5555	5555	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	9900	9900	✔
ElecIntTimer_mS_M_u32[1]	11001	11001	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	16124	16124	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	51566	51566	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	61963	61963	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	7978	7978	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	2471	2471	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	19517	19517	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	59683	59683	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	51566	51566	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	29082	29082	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	3900	3900	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	2158622720	2158622720	✔
IgnTimeOff_Sec_M_u32	1175533756	1175533756	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	110	110	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	634648576	634648576	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	83	83	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1604982784	1604982784	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	244	244	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4207949824	4207949824	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	155	155	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1061574656	1061574656	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1856845824	1856845824	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	24	24	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3827472384	3827472384	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	127	127	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3565729792	3565729792	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	178	178	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3143063552	3143063552	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	180	180	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2328295424	2328295424	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	135	135	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	337451008	337451008	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	216	216	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3200464896	3200464896	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	583256064	583256064	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	494.750885	494.750885	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	488.298798	488.298798	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	177.548492	177.548492	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	59683	59683	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1175533756	1175533756	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	73.8259964	73.8259964 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.303 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3296938752
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	15019
AASNodeAbsentTimer_mS_M_u32	151452416
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	64610
ANGLEVOLANTSigValidCount_Cnt_M_u16	7837
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	63692
AngleVolantMsgTimer_mS_M_u32	3296938752
AngleVolantValidCount_Cnt_M_u16	35272
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1168751360
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3575266048
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3948309248
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3388222208
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	31221
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2342054656
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	32266
CAVNodeAbsentTimer_mS_M_u32	998120192
CDD_SrlComVehSpd_Kph_G_f32	440.884399
CMM388NTCEnableTimer_mS_M_u32	2144819968
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	4153154304
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	15817
CMMNodeAbsentTimer_mS_M_u32	3060148992
CONSANGLECPKSigInvalidCount_Cnt_M_u16	59969
CONSANGLECPKSigValidCount_Cnt_M_u16	23052
CONSANGLECPK_Cnt_M_u16	1427
CONSANGLECPK_HwDeg_M_f32	-100.603104
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	1427
CPKVehicleSpeedMsgTimer_mS_M_u32	2309901056
CPKVehicleSpeedValidCount_Cnt_M_u16	53620
CityParkInputConsistentCount_Cnt_M_u16	25980
CityParkInputInvalidCount_Cnt_M_u16	26474
CityParkInputMsgTimer_mS_M_u32	634648576
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3518692096
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	25695

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1527290624
ComputerRazGCTSigValidCount_Cnt_M_u16	15029
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	38838
DMDFCTCPKSigValidCount_Cnt_M_u16	53881
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	3388
DMDRELAXECPKSigValidCount_Cnt_M_u16	65271
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	21858
DateInvalidTimer_mS_M_u32	3575266048
DiagMuxOnAbsentTimer_mS_M_u32	512232192
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3388222208
ESPNTCEnableTimer_mS_M_u32	3868982016
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	55856
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	963
EffacDefaultDiagTimer_mS_M_u32[1]	7852
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6454
ElecIntTimer_mS_M_u32[1]	8258
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2253581056
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	57947
EtatMTSigValidCount_Cnt_M_u16	54258
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	2331
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	51302
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20615
ISDAT4V2BSI552MsgTimer_mS_M_u32	1578773248
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	29988
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	17827
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	54258
ISDATBSI3F2MsgTimer_mS_M_u32	4155378432
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	52047
ISDATBSI412MsgLenValidCount_Cnt_M_u16	8638
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	57947
ISDATBSI412MsgTimer_mS_M_u32	2611563264
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1149
ISDATBSI432MsgLenValidCount_Cnt_M_u16	65508
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	51519
ISDATDIRASentFltAcc_Cnt_M_u16	44099
ISDATDIRASentTimer_mS_M_u32	2309901056
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	65535
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	35272
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	60617
ISDYN2CMMMsgTimer_mS_M_u32	3649960704
ISDYNAASChkSumInvalidCount_Cnt_M_u16	18309
ISDYNAASChkSumValidCount_Cnt_M_u16	58720
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	56539
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	29393
ISDYNAASMsgLenValidCount_Cnt_M_u16	1925
ISDYNAASMsgTimeValidCount_Cnt_M_u16	18309
ISDYNAASMsgTimer_mS_M_u32	2569231104
ISDYNABRChkSumInvalidCount_Cnt_M_u16	23123
ISDYNABRChkSumValidCount_Cnt_M_u16	59766
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	48920
ISDYNABRMsgCountValidCount_Cnt_M_u16	62771
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	57556
ISDYNABRMsgLenValidCount_Cnt_M_u16	10463
ISDYNABRMsgTimeValidCount_Cnt_M_u16	1427
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	45117
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	63365
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	54258
ISDYNCMM208MsgTimer_mS_M_u32	337820416
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	45117
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	63365
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	13294

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2697779968
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	56167
ISDYNVOLChkSumValidCount_Cnt_M_u16	64434
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	18396
ISDYNVOLMsgCountValidCount_Cnt_M_u16	29471
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	56733
ISDYNVOLMsgLenValidCount_Cnt_M_u16	45512
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	15817
ISDYNVOLMsgTimer_mS_M_u32	2421463808
IgnOnTimer_mS_M_u32	2139151104
IgnTimeOff_Sec_M_u32	1782935377
ManVehSpd_Kph_M_f32	118.159401
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	181
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	245
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2367425280
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	217
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1732864768
PrevISDATBSI412MsgDLCError_Cnt_M_u08	180
PrevISDATBSI412MsgRxTime_MSec_M_u32	4101184256
PrevISDATBSI432MsgDLCError_Cnt_M_u08	155
PrevISDATBSI432MsgRxTime_MSec_M_u32	461372160
PrevISDATDIRAMsgTxTime_MSec_M_u32	3531021056
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	105
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1178053376
PrevISDYNAASMsgDLCError_Cnt_M_u08	31
PrevISDYNAASMsgRxTime_MSec_M_u32	33200896
PrevISDYNABRMsgDLCError_Cnt_M_u08	136
PrevISDYNABRMsgRxTime_MSec_M_u32	1092147968
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	15
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3958610688
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	204
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3355900672
PrevISDYNVOLMsgDLCError_Cnt_M_u08	122
PrevISDYNVOLMsgRxTime_MSec_M_u32	2971933440
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	30362368
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	29.6753998
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	8439
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	9771
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	51172
VitesseVehicleBVRampValidCount_Cnt_M_u16	5336
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	33487
VitesseVehicleBVSigValidCount_Cnt_M_u16	36042
VitesseVehicleBV_Kph_M_f32	456.680389
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	13294
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	64769
VitesseVehiculeRoues_Kph_M_f32	8.30970001
k_AASNTCEnableTimeout_mS_u16	11774
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	20519
k_AASNodeTimeout_mS_u16	25899
k_ABSNodeTimeout_mS_u16	42223
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	54556
k_ANGLEVOLANTSigValidThresh_Cnt_u16	22979
k_AngleVolantInvalidThresh_Cnt_u16	10942
k_AngleVolantValidThresh_Cnt_u16	26474
k_BSI552MsgTimeout_mS_u16	26044
k_BSINTCEnableTimeout_mS_u16	62997
k_BSINodeAbsentDiag_Cnt_str.Threshold	16730
k_BSINodeAbsentDiag_Cnt_str.PStep	3405
k_BSINodeAbsentDiag_Cnt_str.NStep	5
k_BSINodeAbsentTimeout_mS_u16	17508
k_BSINodeTimeout_mS_u16	51519
k_BattOvHi_Volt_f32	11.9853001
k_BattOvLo_Volt_f32	12.1294003
k_BattUvHi_Volt_f32	13.0950003
k_BattUvLo_Volt_f32	24.0918999
k_CAVNTCEnableTimeout_mS_u16	55080
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	17200
k_CAVNodeTimeout_mS_u16	23437
k_CMM388MsgTimeout_mS_u16	47531
k_CMM388NTCEnableTimeout_mS_u16	53239
k_CMMNTCEnableTimeout_mS_u16	62140
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	41293
k_CONSANGLECPKMax_HwDeg_f32	139.272797
k_CONSANGLECPKMin_HwDeg_f32	-138.549606
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	13038
k_CONSANGLECPKSigValidThresh_Cnt_u16	15361
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	64057
k_CPKVehicleSpeedValidThresh_Cnt_u16	2262
k_CityParkInputInvalidThresh_Cnt_u16	34273
k_CityParkInputValidThresh_Cnt_u16	25980
k_ComputerRazGCTSigValidThresh_Cnt_u16	50962
k_CptTemporelSigValidThresh_Cnt_u16	52753
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	24532
k_DMDFCTCPKSigValidThresh_Cnt_u16	59359
k_DMDFCTCPKValidCount_Cnt_u16	64861
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	60617
k_DMDRELAXECPKSigValidThresh_Cnt_u16	57292
k_DMDRelaxeConsistentThresh_Cnt_u16	1754
k_DateValidThresh_Cnt_u16	20615
k_DefaultVehSpd_Kph_f32	16.1755009
k_DiagMuxOnAbsentTimeout_mS_u16	5329
k_EMNodeTimeout_mS_u16	17986
k_ESPNTCEnableTimeout_mS_u16	6486
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	55221
k_EtatMTSigInvalidThresh_Cnt_u16	9902
k_EtatMTSigValidThresh_Cnt_u16	54289
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	33568
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	38679
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	9833
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	47333
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	34852
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	53251
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	8126
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	47589
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	2865
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	64295
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	44086
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	55918
k_ISDATDIRASentDiag_Cnt_str.Threshold	53644

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	28273
k_ISDATDIRASentDiag_Cnt_str.NStep	22576
k_ISDATDIRASentTimeout_mS_u16	57759
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	52711
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	63692
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	1394
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	22867
k_ISDYNAASChkSumValidThresh_Cnt_u16	10358
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	15896
k_ISDYNAASMsgCountValidThresh_Cnt_u16	46131
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	4615
k_ISDYNAASMsgLenValidThresh_Cnt_u16	63711
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	17963
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	22778
k_ISDYNABRChkSumValidThresh_Cnt_u16	37253
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	63733
k_ISDYNABRMsgCountValidThresh_Cnt_u16	29552
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	31945
k_ISDYNABRMsgLenValidThresh_Cnt_u16	22832
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	61355
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	54443
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	34428
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	230
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	31586
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	56733
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	1794
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	7790
k_ISDYNVOLChkSumValidThresh_Cnt_u16	56861
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	4945
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	49194
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	26279
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	14654
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	25285
k_IgnOnTimeout_mS_u16	43450
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	231.683807
k_PowerCutVehSpdLowThresh_Kph_f32	54.5353012
k_PowerCutVehSpdLowTimeout_mS_u16	11770
k_VBattMaxAAS_Volt_f32	4.42180014
k_VBattMaxBSI_Volt_f32	14.8868999
k_VBattMaxCAV_Volt_f32	4.56599998
k_VBattMaxCMM388_Volt_f32	8.16289997
k_VBattMaxCMM_Volt_f32	8.92459965
k_VBattMaxESP_Volt_f32	31.9416008
k_VBattMinAAS_Volt_f32	8.8465004
k_VBattMinBSI_Volt_f32	31.9416008
k_VBattMinCAV_Volt_f32	14.0120001
k_VBattMinCMM388_Volt_f32	10.0155001
k_VBattMinCMM_Volt_f32	1.25629997
k_VBattMinESP_Volt_f32	8.92459965
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	57305
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	5497
k_VitesseVehicleBVRampValidThresh_Cnt_u16	18140
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	47794
k_VitesseVehicleBVSigValidThresh_Cnt_u16	36353
k_VitesseVehicleBVSpeedPassThresh_kph_f32	180.809204
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	32010
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	31358
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3575266048
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8524
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1236548
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	204
target_SrlComInput_Per1_Batt_Volt_f32.value	13.3216
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	296610560
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	197
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.883521616
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3087194880
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2332064512
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2047744768
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2905324288
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1280924416
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	248
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2140601088
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1860475648
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	56
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	57
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	80
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	107
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	235
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3170417408
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	80
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	81
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	106
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	191
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	355064576
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	54
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4188502784
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3124042496
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	4
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	16
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	93
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	117
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	74672896
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2638
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.201919049
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	214167
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	33.1137009
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	35433

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1236548	1236548	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1236548	1236548	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1236548	1236548	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1236548	1236548	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CDD_SrlComVehSpd_Kph_G_f32	118.159401	118.159401	✔
CMM388NTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	1427	1427	✔
CONSANGLECPK_HwDeg_M_f32	-100.603104	-100.603104 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1236548	1236548	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1236548	1236548	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1236548	1236548	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1236548	1236548	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1236548	1236548	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1236548	1236548	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1236548	1236548	✔
ESPNTCEnableTimer_mS_M_u32	1236548	1236548	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	963	963	✔
EffacDefaultDiagTimer_mS_M_u32[1]	7852	7852	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	6454	6454	✔
ElecIntTimer_mS_M_u32[1]	8258	8258	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1236548	1236548	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20615	20615	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	54258	54258	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	57947	57947	✔
ISDATBSI412MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	51519	51519	✔
ISDATBSI432MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1236548	1236548	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	60617	60617	✔
ISDYN2CMMMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	18309	18309	✔
ISDYNAASMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	1427	1427	✔
ISDYNABRMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	54258	54258	✔
ISDYNCMM208MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	13294	13294	✔
ISDYNCMM388MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	15817	15817	✔
ISDYNVOLMsgTimer_mS_M_u32	1236548	1236548	✔
IgnOnTimer_mS_M_u32	2139151104	2139151104	✔
IgnTimeOff_Sec_M_u32	1782935377	1782935377	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	20	20	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3087194880	3087194880	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	72	72	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2332064512	2332064512	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	132	132	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2047744768	2047744768	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	240	240	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2905324288	2905324288	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3531021056	3531021056	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	248	248	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2140601088	2140601088	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	229	229	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1860475648	1860475648	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	48	48	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3170417408	3170417408	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	208	208	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	355064576	355064576	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	54	54	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4188502784	4188502784	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	99	99	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3124042496	3124042496	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	74672896	74672896	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	29.6753998	29.6753998	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	456.680389	456.680389	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	8.30970001	8.30970001	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	1427	1427	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1782935377	1782935377	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-100.603104	-100.603104 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	118.159401	118.159401	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.304 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1962992128
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	21639
AASNodeAbsentTimer_mS_M_u32	2453000704
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	2403
ANGLEVOLANTSigValidCount_Cnt_M_u16	52082
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	56868
AngleVolantMsgTimer_mS_M_u32	1962992128
AngleVolantValidCount_Cnt_M_u16	8625
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3612185088
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2331775488
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3037168128
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3224257024
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	40106
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4265607680
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	28394
CAVNodeAbsentTimer_mS_M_u32	1062236672
CDD_SrlComVehSpd_Kph_G_f32	286.897797
CMM388NTCEnableTimer_mS_M_u32	1732555264
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3274076672
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	30062
CMMNodeAbsentTimer_mS_M_u32	1121468928
CONSANGLECPKSigInvalidCount_Cnt_M_u16	10951
CONSANGLECPKSigValidCount_Cnt_M_u16	17446
CONSANGLECPK_Cnt_M_u16	7569
CONSANGLECPK_HwDeg_M_f32	637.91217
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	7569
CPKVehicleSpeedMsgTimer_mS_M_u32	2441077248
CPKVehicleSpeedValidCount_Cnt_M_u16	51573
CityParkInputConsistentCount_Cnt_M_u16	24213
CityParkInputInvalidCount_Cnt_M_u16	57802
CityParkInputMsgTimer_mS_M_u32	3087194880
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	135909888
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	42859

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	716239360
ComputerRazGCTSigValidCount_Cnt_M_u16	746
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	32998
DMDFCTCPKSigValidCount_Cnt_M_u16	6493
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	48853
DMDRELAXECPKSigValidCount_Cnt_M_u16	4708
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	44388
DateInvalidTimer_mS_M_u32	2331775488
DiagMuxOnAbsentTimer_mS_M_u32	1777508864
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3224257024
ESPNTCEnableTimer_mS_M_u32	2373374464
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	30969
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	200
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8976
ElecIntTimer_mS_M_u32[1]	15235
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1980891648
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	41143
EtatMTSigValidCount_Cnt_M_u16	25778
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	46649
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	57624
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	22323
ISDAT4V2BSI552MsgTimer_mS_M_u32	465322496
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	41949
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	27423
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	25778
ISDATBSI3F2MsgTimer_mS_M_u32	4135625216
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	24155
ISDATBSI412MsgLenValidCount_Cnt_M_u16	21454
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	41143
ISDATBSI412MsgTimer_mS_M_u32	126804480
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	61778
ISDATBSI432MsgLenValidCount_Cnt_M_u16	55261
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	41291
ISDATDIRASentFltAcc_Cnt_M_u16	2111
ISDATDIRASentTimer_mS_M_u32	2441077248
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	3100
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	8625
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36269
ISDYN2CMMMsgTimer_mS_M_u32	4238397952
ISDYNAASChkSumInvalidCount_Cnt_M_u16	5625
ISDYNAASChkSumValidCount_Cnt_M_u16	58663
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	13432
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	27797
ISDYNAASMsgLenValidCount_Cnt_M_u16	46907
ISDYNAASMsgTimeValidCount_Cnt_M_u16	5625
ISDYNAASMsgTimer_mS_M_u32	1264628224
ISDYNABRChkSumInvalidCount_Cnt_M_u16	19217
ISDYNABRChkSumValidCount_Cnt_M_u16	26215
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	47936
ISDYNABRMsgCountValidCount_Cnt_M_u16	49582
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	21262
ISDYNABRMsgLenValidCount_Cnt_M_u16	58285
ISDYNABRMsgTimeValidCount_Cnt_M_u16	7569
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	7745
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	58665
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	25778
ISDYNCMM208MsgTimer_mS_M_u32	2413990400
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	7745
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	58665
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	15167

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3127128576
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	28501
ISDYNVOLChkSumValidCount_Cnt_M_u16	30516
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	34932
ISDYNVOLMsgCountValidCount_Cnt_M_u16	20331
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	25266
ISDYNVOLMsgLenValidCount_Cnt_M_u16	52976
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	30062
ISDYNVOLMsgTimer_mS_M_u32	3133993472
IgnOnTimer_mS_M_u32	3997708800
IgnTimeOff_Sec_M_u32	2427927839
ManVehSpd_Kph_M_f32	175.060196
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	182
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1849074176
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	60
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3442377216
PrevISDATBSI412MsgDLCError_Cnt_M_u08	232
PrevISDATBSI412MsgRxTime_MSec_M_u32	678523392
PrevISDATBSI432MsgDLCError_Cnt_M_u08	173
PrevISDATBSI432MsgRxTime_MSec_M_u32	2127221248
PrevISDATDIRAMsgTxTime_MSec_M_u32	2657448448
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	212
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3110322688
PrevISDYNAASMsgDLCError_Cnt_M_u08	125
PrevISDYNAASMsgRxTime_MSec_M_u32	2111500800
PrevISDYNABRMsgDLCError_Cnt_M_u08	27
PrevISDYNABRMsgRxTime_MSec_M_u32	159396352
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	165
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3824153088
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	13
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1429590528
PrevISDYNVOLMsgDLCError_Cnt_M_u08	166
PrevISDYNVOLMsgRxTime_MSec_M_u32	4133384704
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3978093056
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	253.993698
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	31267
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	29513
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	31068
VitesseVehicleBVRampValidCount_Cnt_M_u16	39746
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	27164
VitesseVehicleBVSigValidCount_Cnt_M_u16	29931
VitesseVehicleBV_Kph_M_f32	375.392487
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	15167
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	26821
VitesseVehiculeRoues_Kph_M_f32	611.648987
k_AASNTCEnableTimeout_mS_u16	4176
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	2708
k_AASNodeTimeout_mS_u16	46665
k_ABSNodeTimeout_mS_u16	32059
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	47989
k_ANGLEVOLANTSigValidThresh_Cnt_u16	1600
k_AngleVolantInvalidThresh_Cnt_u16	16207
k_AngleVolantValidThresh_Cnt_u16	57802
k_BSI552MsgTimeout_mS_u16	55956
k_BSINTCEnableTimeout_mS_u16	31882
k_BSINodeAbsentDiag_Cnt_str.Threshold	54380
k_BSINodeAbsentDiag_Cnt_str.PStep	50129
k_BSINodeAbsentDiag_Cnt_str.NStep	20201
k_BSINodeAbsentTimeout_mS_u16	23388
k_BSINodeTimeout_mS_u16	41291
k_BattOvHi_Volt_f32	10.1014996
k_BattOvLo_Volt_f32	4.30569983
k_BattUvHi_Volt_f32	22.8320999
k_BattUvLo_Volt_f32	13.2959995
k_CAVNTCEnableTimeout_mS_u16	2704
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	14200
k_CAVNodeTimeout_mS_u16	1763
k_CMM388MsgTimeout_mS_u16	55175
k_CMM388NTCEnableTimeout_mS_u16	50339
k_CMMNTCEnableTimeout_mS_u16	35605
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	44001
k_CONSANGLECPKMax_HwDeg_f32	120.772598
k_CONSANGLECPKMin_HwDeg_f32	-88.9405975
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	15935
k_CONSANGLECPKSigValidThresh_Cnt_u16	43973
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	44831
k_CPKVehicleSpeedValidThresh_Cnt_u16	33222
k_CityParkInputInvalidThresh_Cnt_u16	32871
k_CityParkInputValidThresh_Cnt_u16	24213
k_ComputerRazGCTSigValidThresh_Cnt_u16	58899
k_CptTemporelSigValidThresh_Cnt_u16	2517
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	54798
k_DMDFCTCPKSigValidThresh_Cnt_u16	42669
k_DMDFCTCPKValidCount_Cnt_u16	45682
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	36269
k_DMDRELAXECPKSigValidThresh_Cnt_u16	64868
k_DMDRelaxeConsistentThresh_Cnt_u16	16442
k_DateValidThresh_Cnt_u16	22323
k_DefaultVehSpd_Kph_f32	192.515701
k_DiagMuxOnAbsentTimeout_mS_u16	26583
k_EMNodeTimeout_mS_u16	23236
k_ESPNTCEnableTimeout_mS_u16	52486
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	43177
k_EtatMTSigInvalidThresh_Cnt_u16	4608
k_EtatMTSigValidThresh_Cnt_u16	53910
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	28778
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	19780
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	4046
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	7322
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	59292
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	8255
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	58255
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	60890
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	44342
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	36053
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	62055
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	48637
k_ISDATDIRASentDiag_Cnt_str.Threshold	63911

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	39954
k_ISDATDIRASentDiag_Cnt_str.NStep	1837
k_ISDATDIRASentTimeout_mS_u16	58669
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	1938
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	56868
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	30898
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	19985
k_ISDYNAASChkSumValidThresh_Cnt_u16	43367
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	15936
k_ISDYNAASMsgCountValidThresh_Cnt_u16	33966
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	62453
k_ISDYNAASMsgLenValidThresh_Cnt_u16	52013
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	57608
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	668
k_ISDYNABRChkSumValidThresh_Cnt_u16	49595
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	8106
k_ISDYNABRMsgCountValidThresh_Cnt_u16	55545
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	47214
k_ISDYNABRMsgLenValidThresh_Cnt_u16	64505
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	4168
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	12039
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	8404
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	36632
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	35939
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	36466
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	25346
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	41214
k_ISDYNVOLChkSumValidThresh_Cnt_u16	23217
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	37270
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	45643
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	17363
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	25806
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	39033
k_IgnOnTimeout_mS_u16	12058
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	106.490799
k_PowerCutVehSpdLowThresh_Kph_f32	101.936096
k_PowerCutVehSpdLowTimeout_mS_u16	92
k_VBattMaxAAS_Volt_f32	22.1893005
k_VBattMaxBSI_Volt_f32	28.4988995
k_VBattMaxCAV_Volt_f32	14.2477999
k_VBattMaxCMM388_Volt_f32	4.03730011
k_VBattMaxCMM_Volt_f32	26.3411007
k_VBattMaxESP_Volt_f32	7.53119993
k_VBattMinAAS_Volt_f32	26.5431004
k_VBattMinBSI_Volt_f32	7.53119993
k_VBattMinCAV_Volt_f32	30.3502007
k_VBattMinCMM388_Volt_f32	22.2949009
k_VBattMinCMM_Volt_f32	25.7238998
k_VBattMinESP_Volt_f32	26.3411007
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	6588
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	12703
k_VitesseVehicleBVRampValidThresh_Cnt_u16	35700
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	14900
k_VitesseVehicleBVSigValidThresh_Cnt_u16	14598
k_VitesseVehicleBVSpeedPassThresh_kph_f32	496.030701
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	29162
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	33360
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2331775488
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	55763
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1813852160
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	13
target_SrlComInput_Per1_Batt_Volt_f32.value	15.0403996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	66048
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	234
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.278850228
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3435278848
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3528020480
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	188
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3282072064
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	87
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	684167680
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2310976000
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	187
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1854263808
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1595732480
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	20
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	22
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	24
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	134
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	146
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	196
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1835045376
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	48
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	170
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	234
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	54
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	290271744
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3797176832
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	122
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1596682752
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	47
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	57
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	164
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	183
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	498106880
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	333
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.726331055
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	69662
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	202.451004
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	34253

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1813852160	1813852160	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
CDD_SrlComVehSpd_Kph_G_f32	175.060196	175.060196	✔
CMM388NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	7569	7569	✔
CONSANGLECPK_HwDeg_M_f32	637.91217	637.91217 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1813852160	1813852160	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1813852160	1813852160	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1813852160	1813852160	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1813852160	1813852160	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1813852160	1813852160	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1813852160	1813852160	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1813852160	1813852160	✔
ESPNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔
EffacDefaultDiagTimer_mS_M_u32[1]	200	200	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	8976	8976	✔
ElecIntTimer_mS_M_u32[1]	15235	15235	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1813852160	1813852160	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	22323	22323	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	25778	25778	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	41143	41143	✔
ISDATBSI412MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	41291	41291	✔
ISDATBSI432MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1813852160	1813852160	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36269	36269	✔
ISDYN2CMMMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	5625	5625	✔
ISDYNAASMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	7569	7569	✔
ISDYNABRMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	25778	25778	✔
ISDYNCMM208MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	15167	15167	✔
ISDYNCMM388MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	30062	30062	✔
ISDYNVOLMsgTimer_mS_M_u32	1813852160	1813852160	✔
IgnOnTimer_mS_M_u32	3997708800	3997708800	✔
IgnTimeOff_Sec_M_u32	2427927839	2427927839	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	15	15	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3435278848	3435278848	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	210	210	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3528020480	3528020480	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	188	188	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3282072064	3282072064	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	87	87	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	684167680	684167680	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2657448448	2657448448	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	187	187	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1854263808	1854263808	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1595732480	1595732480	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	12	12	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1835045376	1835045376	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	54	54	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	290271744	290271744	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3797176832	3797176832	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	122	122	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1596682752	1596682752	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	498106880	498106880	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	253.993698	253.993698	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	375.392487	375.392487	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	611.648987	611.648987	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	7569	7569	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2427927839	2427927839	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	637.91217	637.91217 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.305 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4205059328
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	38416
AASNodeAbsentTimer_mS_M_u32	3804581120
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	35195
ANGLEVOLANTSigValidCount_Cnt_M_u16	51471
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	44345
AngleVolantMsgTimer_mS_M_u32	4205059328
AngleVolantValidCount_Cnt_M_u16	65298
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	578686208
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3782380800
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	487603456
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	110886144
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	43942
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3278290176
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	39272
CAVNodeAbsentTimer_mS_M_u32	234188032
CDD_SrlComVehSpd_Kph_G_f32	631.201721
CMM388NTCEnableTimer_mS_M_u32	3071847680
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1517513984
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	46234
CMMNodeAbsentTimer_mS_M_u32	2795371776
CONSANGLECPKSigInvalidCount_Cnt_M_u16	25679
CONSANGLECPKSigValidCount_Cnt_M_u16	56820
CONSANGLECPK_Cnt_M_u16	48563
CONSANGLECPK_HwDeg_M_f32	-369.630707
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	48563
CPKVehicleSpeedMsgTimer_mS_M_u32	1629953280
CPKVehicleSpeedValidCount_Cnt_M_u16	43886
CityParkInputConsistentCount_Cnt_M_u16	55398
CityParkInputInvalidCount_Cnt_M_u16	46022
CityParkInputMsgTimer_mS_M_u32	3435278848
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	286870784
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	11620

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1842605312
ComputerRazGCTSigValidCount_Cnt_M_u16	32615
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	18034
DMDFCTCPKSigValidCount_Cnt_M_u16	41679
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	45349
DMDRELAXECPKSigValidCount_Cnt_M_u16	15417
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	36984
DateInvalidTimer_mS_M_u32	3782380800
DiagMuxOnAbsentTimer_mS_M_u32	315546880
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	110886144
ESPNTCEnableTimer_mS_M_u32	889343232
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	8123
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	89
EffacDefaultDiagTimer_mS_M_u32[1]	898
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	5
ElecIntTimer_mS_M_u32[1]	56
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	602979584
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	59326
EtatMTSigValidCount_Cnt_M_u16	53647
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	2553
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	20254
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	49485
ISDAT4V2BSI552MsgTimer_mS_M_u32	2884762880
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	43982
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	43975
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	53647
ISDATBSI3F2MsgTimer_mS_M_u32	0
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	17748
ISDATBSI412MsgLenValidCount_Cnt_M_u16	31420
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	59326
ISDATBSI412MsgTimer_mS_M_u32	4210695424
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	53486
ISDATBSI432MsgLenValidCount_Cnt_M_u16	37647
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	50757
ISDATDIRASentFltAcc_Cnt_M_u16	24937
ISDATDIRASentTimer_mS_M_u32	1629953280
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	1161
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	65298
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	64541
ISDYN2CMMMsgTimer_mS_M_u32	260328704
ISDYNAASChkSumInvalidCount_Cnt_M_u16	39354
ISDYNAASChkSumValidCount_Cnt_M_u16	12783
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	41661
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	3175
ISDYNAASMsgLenValidCount_Cnt_M_u16	4660
ISDYNAASMsgTimeValidCount_Cnt_M_u16	39354
ISDYNAASMsgTimer_mS_M_u32	2059709696
ISDYNABRChkSumInvalidCount_Cnt_M_u16	45554
ISDYNABRChkSumValidCount_Cnt_M_u16	1455
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	34277
ISDYNABRMsgCountValidCount_Cnt_M_u16	30810
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	51066
ISDYNABRMsgLenValidCount_Cnt_M_u16	56159
ISDYNABRMsgTimeValidCount_Cnt_M_u16	48563
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	31121
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	20123
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	53647
ISDYNCMM208MsgTimer_mS_M_u32	2361330944
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	31121
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	20123
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	27240

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2612669696
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	20133
ISDYNVOLChkSumValidCount_Cnt_M_u16	64714
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	59336
ISDYNVOLMsgCountValidCount_Cnt_M_u16	47269
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	34448
ISDYNVOLMsgLenValidCount_Cnt_M_u16	34709
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	46234
ISDYNVOLMsgTimer_mS_M_u32	763358464
IgnOnTimer_mS_M_u32	2416848128
IgnTimeOff_Sec_M_u32	58843476
ManVehSpd_Kph_M_f32	268.712402
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	183
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	189
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	369286400
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	145
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	815480064
PrevISDATBSI412MsgDLCError_Cnt_M_u08	220
PrevISDATBSI412MsgRxTime_MSec_M_u32	378694912
PrevISDATBSI432MsgDLCError_Cnt_M_u08	24
PrevISDATBSI432MsgRxTime_MSec_M_u32	2969980160
PrevISDATDIRAMsgTxTime_MSec_M_u32	2226547968
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	238
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3506142464
PrevISDYNAASMsgDLCError_Cnt_M_u08	146
PrevISDYNAASMsgRxTime_MSec_M_u32	2622876928
PrevISDYNABRMsgDLCError_Cnt_M_u08	48
PrevISDYNABRMsgRxTime_MSec_M_u32	510012672
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	50
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4262915328
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	34
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2579844352
PrevISDYNVOLMsgDLCError_Cnt_M_u08	104
PrevISDYNVOLMsgRxTime_MSec_M_u32	2697686272
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	38804736
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	591.467407
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	39869
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	38410
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	49682
VitesseVehicleBVRampValidCount_Cnt_M_u16	16927
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	35664
VitesseVehicleBVSigValidCount_Cnt_M_u16	61604
VitesseVehicleBV_Kph_M_f32	614.409119
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	27240
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	18324
VitesseVehiculeRoues_Kph_M_f32	606.846619
k_AASNTCEnableTimeout_mS_u16	41334
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	36969
k_AASNodeTimeout_mS_u16	52490
k_ABSNodeTimeout_mS_u16	58739
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	48773
k_ANGLEVOLANTSigValidThresh_Cnt_u16	21478
k_AngleVolantInvalidThresh_Cnt_u16	42169
k_AngleVolantValidThresh_Cnt_u16	46022
k_BSI552MsgTimeout_mS_u16	60967
k_BSINTCEnableTimeout_mS_u16	3910
k_BSINodeAbsentDiag_Cnt_str.Threshold	6800
k_BSINodeAbsentDiag_Cnt_str.PStep	21155
k_BSINodeAbsentDiag_Cnt_str.NStep	34713
k_BSINodeAbsentTimeout_mS_u16	5521
k_BSINodeTimeout_mS_u16	50757
k_BattOvHi_Volt_f32	14.4973001
k_BattOvLo_Volt_f32	15.4762001
k_BattUvHi_Volt_f32	25.6268005
k_BattUvLo_Volt_f32	16.3715
k_CAVNTCEnableTimeout_mS_u16	53620
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	63422
k_CAVNodeTimeout_mS_u16	16379
k_CMM388MsgTimeout_mS_u16	3344
k_CMM388NTCEnableTimeout_mS_u16	46524
k_CMMNTCEnableTimeout_mS_u16	54822
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	60992
k_CONSANGLECPKMax_HwDeg_f32	75.9311981
k_CONSANGLECPKMin_HwDeg_f32	-54.3871994
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	24936
k_CONSANGLECPKSigValidThresh_Cnt_u16	32404
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	47752
k_CPKVehicleSpeedValidThresh_Cnt_u16	18195
k_CityParkInputInvalidThresh_Cnt_u16	59888
k_CityParkInputValidThresh_Cnt_u16	55398
k_ComputerRazGCTSigValidThresh_Cnt_u16	15660
k_CptTemporelSigValidThresh_Cnt_u16	10149
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	15994
k_DMDFCTCPKSigValidThresh_Cnt_u16	37471
k_DMDFCTCPKValidCount_Cnt_u16	35406
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	64541
k_DMDRELAXECPKSigValidThresh_Cnt_u16	53946
k_DMDRelaxeConsistentThresh_Cnt_u16	57912
k_DateValidThresh_Cnt_u16	49485
k_DefaultVehSpd_Kph_f32	140.604401
k_DiagMuxOnAbsentTimeout_mS_u16	30433
k_EMNodeTimeout_mS_u16	2136
k_ESPNTCEnableTimeout_mS_u16	61204
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	6120
k_EtatMTSigInvalidThresh_Cnt_u16	55589
k_EtatMTSigValidThresh_Cnt_u16	15650
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	25255
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	33240
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	59579
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	30103
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	27216
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	36776
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	11831
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	34072
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	11586
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	32743
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	58608
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	32621
k_ISDATDIRASentDiag_Cnt_str.Threshold	31074

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	34522
k_ISDATDIRASentDiag_Cnt_str.NStep	11395
k_ISDATDIRASentTimeout_mS_u16	21406
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	13998
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	44345
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	39952
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	43250
k_ISDYNAASChkSumValidThresh_Cnt_u16	15535
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	64741
k_ISDYNAASMsgCountValidThresh_Cnt_u16	12122
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	18246
k_ISDYNAASMsgLenValidThresh_Cnt_u16	7774
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	58254
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	28880
k_ISDYNABRChkSumValidThresh_Cnt_u16	63797
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	8870
k_ISDYNABRMsgCountValidThresh_Cnt_u16	31866
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	60314
k_ISDYNABRMsgLenValidThresh_Cnt_u16	38587
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	53901
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	3345
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	8681
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	16029
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	123
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	32783
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	4126
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	51563
k_ISDYNVOLChkSumValidThresh_Cnt_u16	45587
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	35300
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	45571
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	28266
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	16699
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	38267
k_IgnOnTimeout_mS_u16	36631
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	253.179199
k_PowerCutVehSpdLowThresh_Kph_f32	82.8432007
k_PowerCutVehSpdLowTimeout_mS_u16	338
k_VBattMaxAAS_Volt_f32	12.8579998
k_VBattMaxBSI_Volt_f32	12.8137999
k_VBattMaxCAV_Volt_f32	26.2087994
k_VBattMaxCMM388_Volt_f32	22.1000004
k_VBattMaxCMM_Volt_f32	13.4221001
k_VBattMaxESP_Volt_f32	18.1282005
k_VBattMinAAS_Volt_f32	12.9126997
k_VBattMinBSI_Volt_f32	18.1282005
k_VBattMinCAV_Volt_f32	9.58030033
k_VBattMinCMM388_Volt_f32	27.8810005
k_VBattMinCMM_Volt_f32	20.1396999
k_VBattMinESP_Volt_f32	13.4221001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	10288
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	46664
k_VitesseVehicleBVRampValidThresh_Cnt_u16	57032
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	46026
k_VitesseVehicleBVSigValidThresh_Cnt_u16	19731
k_VitesseVehicleBVSpeedPassThresh_kph_f32	404.401215
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	36968
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	17653
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3782380800
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	44013
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	68495872
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	34
target_SrlComInput_Per1_Batt_Volt_f32.value	2.02270007
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	35896576
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	45
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.565700769
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1554001152
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3498757376
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	138
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3238358272
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	32
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2517634304
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3081415936
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2379566336
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2156915968
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	12
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	25
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	175
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	191
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1816464640
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	74
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	100
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	107
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	123
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	131
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	224
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2063543552
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2355744000
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	61
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3664014592
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	49
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	248
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3340057856
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	746
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.961951613
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	21412
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	184.548492
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	41151

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	68495872	68495872	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	68495872	68495872	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	44345	44345	✔
AngleVolantMsgTimer_mS_M_u32	68495872	68495872	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	6800	6800	✔
BSINodeAbsentTimer_mS_M_u32	68495872	68495872	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	68495872	68495872	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	68495872	68495872	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	68495872	68495872	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	48563	48563	✔
CONSANGLECPK_HwDeg_M_f32	-369.630707	-369.630707 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	48563	48563	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1629953280	1629953280	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	43886	43886	✔
CityParkInputConsistentCount_Cnt_M_u16	55398	55398	✔
CityParkInputInvalidCount_Cnt_M_u16	46024	46024	✔
CityParkInputMsgTimer_mS_M_u32	68495872	68495872	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	68495872	68495872	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	68495872	68495872	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	68495872	68495872	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	68495872	68495872	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	68495872	68495872	✔
ESPNTCEnableTimer_mS_M_u32	68495872	68495872	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	89	89	✔
EffacDefaultDiagTimer_mS_M_u32[1]	898	898	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	68495872	68495872	✔
ElecIntTimer_mS_M_u32[1]	56	56	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	68495872	68495872	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	68495872	68495872	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	68495872	68495872	✔
IgnOnTimer_mS_M_u32	68495872	68495872	✔
IgnTimeOff_Sec_M_u32	58843476	58843476	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	136	136	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1554001152	1554001152	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	37	37	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3498757376	3498757376	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	138	138	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3238358272	3238358272	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	32	32	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2517634304	2517634304	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2226547968	2226547968	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	125	125	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2379566336	2379566336	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2156915968	2156915968	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1816464640	1816464640	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	0	0	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2063543552	2063543552	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	90	90	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2355744000	2355744000	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	61	61	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3664014592	3664014592	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3340057856	3340057856	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	591.467407	591.467407	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	614.409119	614.409119	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	606.846619	606.846619	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	48563	48563	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	58843476	58843476	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-369.630707	-369.630707 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.306 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	342256640
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	37920
AASNodeAbsentTimer_mS_M_u32	2630016000
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	33761
ANGLEVOLANTSigValidCount_Cnt_M_u16	13283
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	12965
AngleVolantMsgTimer_mS_M_u32	342256640
AngleVolantValidCount_Cnt_M_u16	59292
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2962791424
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3854244864
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	94505984
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	671009792
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	35168
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2359200768
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	37528
CAVNodeAbsentTimer_mS_M_u32	2209512448
CDD_SrlComVehSpd_Kph_G_f32	238.405807
CMM388NTCEnableTimer_mS_M_u32	625523712
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	372800512
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	46274
CMMNodeAbsentTimer_mS_M_u32	3489188864
CONSANGLECPKSigInvalidCount_Cnt_M_u16	13923
CONSANGLECPKSigValidCount_Cnt_M_u16	30773
CONSANGLECPK_Cnt_M_u16	38136
CONSANGLECPK_HwDeg_M_f32	-288.07309
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	38136
CPKVehicleSpeedMsgTimer_mS_M_u32	2900192256
CPKVehicleSpeedValidCount_Cnt_M_u16	38798

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	43936
CityParkInputInvalidCount_Cnt_M_u16	60031
CityParkInputMsgTimer_mS_M_u32	1554001152
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1640422400
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	7716
ComputerRazGCTSigInvalidTimer_mS_M_u32	4262919168
ComputerRazGCTSigValidCount_Cnt_M_u16	64157
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	57979
DMDFCTCPKSigValidCount_Cnt_M_u16	23589
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	13539
DMDRELAXECPKSigValidCount_Cnt_M_u16	613
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	38376
DateInvalidTimer_mS_M_u32	3854244864
DiagMuxOnAbsentTimer_mS_M_u32	3873844224
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	671009792
ESPNTCEnableTimer_mS_M_u32	3658210304
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	4640
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	4
EffacDefaultDiagTimer_mS_M_u32[1]	748
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	978
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	318802944
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	64597
EtatMTSigValidCount_Cnt_M_u16	40355
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	28005
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	19639
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	30891
ISDAT4V2BSI552MsgTimer_mS_M_u32	268225536
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	18342
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	18044
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	40355
ISDATBSI3F2MsgTimer_mS_M_u32	4294967295
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	8214
ISDATBSI412MsgLenValidCount_Cnt_M_u16	16028
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	64597
ISDATBSI412MsgTimer_mS_M_u32	3949227008
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	44998
ISDATBSI432MsgLenValidCount_Cnt_M_u16	2084
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	49153
ISDATDIRASentFltAcc_Cnt_M_u16	32405
ISDATDIRASentTimer_mS_M_u32	2900192256
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	39030
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	59292
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	11642
ISDYN2CMMMsgTimer_mS_M_u32	3531987968
ISDYNAASChkSumInvalidCount_Cnt_M_u16	45346
ISDYNAASChkSumValidCount_Cnt_M_u16	55108
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	26779
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	62875
ISDYNAASMsgLenValidCount_Cnt_M_u16	13045
ISDYNAASMsgTimeValidCount_Cnt_M_u16	45346
ISDYNAASMsgTimer_mS_M_u32	2319760384
ISDYNABRChkSumInvalidCount_Cnt_M_u16	16889
ISDYNABRChkSumValidCount_Cnt_M_u16	21891
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	22689
ISDYNABRMsgCountValidCount_Cnt_M_u16	28675
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	30946
ISDYNABRMsgLenValidCount_Cnt_M_u16	60404
ISDYNABRMsgTimeValidCount_Cnt_M_u16	38136

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	59278
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	60209
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	40355
ISDYNCMM208MsgTimer_mS_M_u32	3050675200
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	59278
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	60209
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	32154
ISDYNCMM388MsgTimer_mS_M_u32	3714333696
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	20321
ISDYNVOLChkSumValidCount_Cnt_M_u16	62387
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	54905
ISDYNVOLMsgCountValidCount_Cnt_M_u16	62115
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	29089
ISDYNVOLMsgLenValidCount_Cnt_M_u16	40275
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	46274
ISDYNVOLMsgTimer_mS_M_u32	1863515136
IgnOnTimer_mS_M_u32	1349008384
IgnTimeOff_Sec_M_u32	306506492
ManVehSpd_Kph_M_f32	138.180496
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	184
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	57
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2907319296
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	137
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3070299136
PrevISDATBSI412MsgDLCError_Cnt_M_u08	191
PrevISDATBSI412MsgRxTime_MSec_M_u32	500923392
PrevISDATBSI432MsgDLCError_Cnt_M_u08	99
PrevISDATBSI432MsgRxTime_MSec_M_u32	1979702272
PrevISDATDIRAMsgTxTime_MSec_M_u32	1668250624
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	2
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2799717376
PrevISDYNAASMsgDLCError_Cnt_M_u08	58
PrevISDYNAASMsgRxTime_MSec_M_u32	4203805696
PrevISDYNABRMsgDLCError_Cnt_M_u08	246
PrevISDYNABRMsgRxTime_MSec_M_u32	90192896
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	18
PrevISDYNCMM208MsgRxTime_MSec_M_u32	424541184
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	202
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2009259008
PrevISDYNVOLMsgDLCError_Cnt_M_u08	189
PrevISDYNVOLMsgRxTime_MSec_M_u32	2737863680
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2908908544
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	116.609001
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	8089
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	32627
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	16538
VitesseVehicleBVRampValidCount_Cnt_M_u16	3892
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	4706

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	20772
VitesseVehicleBV_Kph_M_f32	199.049606
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	32154
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	46291
VitesseVehiculeRoues_Kph_M_f32	87.1362
k_AASNTCEnableTimeout_mS_u16	46511
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	20375
k_AASNodeTimeout_mS_u16	55923
k_ABSNodeTimeout_mS_u16	18808
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	769
k_ANGLEVOLANTSigValidThresh_Cnt_u16	57759
k_AngleVolantInvalidThresh_Cnt_u16	64294
k_AngleVolantValidThresh_Cnt_u16	60031
k_BSI552MsgTimeout_mS_u16	52506
k_BSINTCEnableTimeout_mS_u16	21694
k_BSINodeAbsentDiag_Cnt_str.Threshold	47632
k_BSINodeAbsentDiag_Cnt_str.PStep	65305
k_BSINodeAbsentDiag_Cnt_str.NStep	56694
k_BSINodeAbsentTimeout_mS_u16	22941
k_BSINodeTimeout_mS_u16	49153
k_BattOvHi_Volt_f32	19.2957993
k_BattOvLo_Volt_f32	0.585099995
k_BattUvHi_Volt_f32	0.443300009
k_BattUvLo_Volt_f32	11.8006001
k_CAVNTCEnableTimeout_mS_u16	51573
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	20374
k_CAVNodeTimeout_mS_u16	21343
k_CMM388MsgTimeout_mS_u16	12064
k_CMM388NTCEnableTimeout_mS_u16	58652
k_CMMNTCEnableTimeout_mS_u16	10398
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	28879
k_CONSANGLECPKMax_HwDeg_f32	72.1690979
k_CONSANGLECPKMin_HwDeg_f32	-366.501587
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	39066
k_CONSANGLECPKSigValidThresh_Cnt_u16	4051
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	35321
k_CPKVehicleSpeedValidThresh_Cnt_u16	55001
k_CityParkInputInvalidThresh_Cnt_u16	4607
k_CityParkInputValidThresh_Cnt_u16	43936
k_ComputerRazGCTSigValidThresh_Cnt_u16	35724
k_CptTemporelSigValidThresh_Cnt_u16	51938
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	5090
k_DMDFCTCPKSigValidThresh_Cnt_u16	50932
k_DMDFCTCPKValidCount_Cnt_u16	36200
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	11642
k_DMDRELAXECPKSigValidThresh_Cnt_u16	14436
k_DMDRelaxeConsistentThresh_Cnt_u16	33258
k_DateValidThresh_Cnt_u16	30891
k_DefaultVehSpd_Kph_f32	1.00989997
k_DiagMuxOnAbsentTimeout_mS_u16	41326
k_EMNodeTimeout_mS_u16	44616
k_ESPNTCEnableTimeout_mS_u16	16788
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	37847
k_EtatMTSigInvalidThresh_Cnt_u16	22624
k_EtatMTSigValidThresh_Cnt_u16	15146
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	52636
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	20170
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	3745
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	20043
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	28385
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	37146

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	64491
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	38409
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	60106
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	7772
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	11778
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	26314
k_ISDATDIRASentDiag_Cnt_str.Threshold	16910
k_ISDATDIRASentDiag_Cnt_str.PStep	7039
k_ISDATDIRASentDiag_Cnt_str.NStep	21916
k_ISDATDIRASentTimeout_mS_u16	3317
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	34055
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	12965
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10912
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	23801
k_ISDYNAASChkSumValidThresh_Cnt_u16	45187
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	62369
k_ISDYNAASMsgCountValidThresh_Cnt_u16	19203
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	53757
k_ISDYNAASMsgLenValidThresh_Cnt_u16	13943
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	53927
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	21728
k_ISDYNABRChkSumValidThresh_Cnt_u16	27250
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	9312
k_ISDYNABRMsgCountValidThresh_Cnt_u16	34210
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	4034
k_ISDYNABRMsgLenValidThresh_Cnt_u16	44320
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	36713
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	7069
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7767
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	37306
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	7905
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	3811
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	13687
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	45009
k_ISDYNVOLChkSumValidThresh_Cnt_u16	46231
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	47013
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	41095
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	6225
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	65183
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	13345
k_IgnOnTimeout_mS_u16	3789
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	99.7857971
k_PowerCutVehSpdLowThresh_Kph_f32	138.793594
k_PowerCutVehSpdLowTimeout_mS_u16	1563
k_VBattMaxAAS_Volt_f32	22.3757992
k_VBattMaxBSI_Volt_f32	31.8542995
k_VBattMaxCAV_Volt_f32	13.7441998
k_VBattMaxCMM388_Volt_f32	31.2914009
k_VBattMaxCMM_Volt_f32	14.625
k_VBattMaxESP_Volt_f32	23.6777
k_VBattMinAAS_Volt_f32	15.8629999
k_VBattMinBSI_Volt_f32	23.6777
k_VBattMinCAV_Volt_f32	1.59379995
k_VBattMinCMM388_Volt_f32	30.2873001
k_VBattMinCMM_Volt_f32	12.8736
k_VBattMinESP_Volt_f32	14.625
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	14465
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	3319
k_VitesseVehicleBVRampValidThresh_Cnt_u16	61817
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	52915
k_VitesseVehicleBVSigValidThresh_Cnt_u16	16793
k_VitesseVehicleBVSpeedPassThresh_kph_f32	373.352905
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	44440
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	57010
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3854244864
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65109
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3632743680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	202
target_SrlComInput_Per1_Batt_Volt_f32.value	14.6597996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	73894912
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	195
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.451112539
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	76
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2998025216
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	201
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3379715072
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	44
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2860678144
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	61
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	501390336
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3952262144
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	138
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3683834880
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3051551744
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	57
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	72
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	169
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	209
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	197
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2940443648
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	126
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	140
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	176
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	222
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2476030976
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	101
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3520420864
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	80
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2590342144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	58
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	109
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	121
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	138
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	140
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	178
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1536363520
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1850
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0363518074
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	945758
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	159.927704
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	39059

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3632743680	3632743680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
CDD_SrlComVehSpd_Kph_G_f32	138.180496	138.180496	✔
CMM388NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	38136	38136	✔
CONSANGLECPK_HwDeg_M_f32	-288.07309	-288.07309 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3632743680	3632743680	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3632743680	3632743680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3632743680	3632743680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3632743680	3632743680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3632743680	3632743680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3632743680	3632743680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3632743680	3632743680	✔
ESPNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	4	4	✔
EffacDefaultDiagTimer_mS_M_u32[1]	748	748	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	97	97	✔
ElecIntTimer_mS_M_u32[1]	978	978	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3632743680	3632743680	✔
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	30891	30891	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	40355	40355	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	64597	64597	✔
ISDATBSI412MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	49153	49153	✔
ISDATBSI432MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3632743680	3632743680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	11642	11642	✔
ISDYN2CMMMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	45346	45346	✔
ISDYNAASMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	38136	38136	✔
ISDYNABRMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	40355	40355	✔
ISDYNCMM208MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	32154	32154	✔
ISDYNCMM388MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	46274	46274	✔
ISDYNVOLMsgTimer_mS_M_u32	3632743680	3632743680	✔
IgnOnTimer_mS_M_u32	1349008384	1349008384	✔
IgnTimeOff_Sec_M_u32	306506492	306506492	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	76	76	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2998025216	2998025216	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	201	201	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3379715072	3379715072	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	44	44	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2860678144	2860678144	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	61	61	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	501390336	501390336	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1668250624	1668250624	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	138	138	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3683834880	3683834880	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	86	86	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3051551744	3051551744	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	197	197	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2940443648	2940443648	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2476030976	2476030976	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	101	101	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3520420864	3520420864	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	80	80	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2590342144	2590342144	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1536363520	1536363520	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	116.609001	116.609001	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	199.049606	199.049606	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	87.1362	87.1362	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	38136	38136	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	306506492	306506492	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-288.07309	-288.07309 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.307 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1998290688
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	491
AASNodeAbsentTimer_mS_M_u32	465972992
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	54442
ANGLEVOLANTSigValidCount_Cnt_M_u16	30820
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	31324
AngleVolantMsgTimer_mS_M_u32	1998290688
AngleVolantValidCount_Cnt_M_u16	23546
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1732570880
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1910337280
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2582159104
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2513592064
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	32813
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2532515584
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	60677
CAVNodeAbsentTimer_mS_M_u32	762793728
CDD_SrlComVehSpd_Kph_G_f32	604.02002
CMM388NTCEnableTimer_mS_M_u32	1907658496
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	233131776
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	11078
CMMNodeAbsentTimer_mS_M_u32	98852608
CONSANGLECPKSigInvalidCount_Cnt_M_u16	62501
CONSANGLECPKSigValidCount_Cnt_M_u16	8815
CONSANGLECPK_Cnt_M_u16	38950
CONSANGLECPK_HwDeg_M_f32	-2.34500003
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	38950
CPKVehicleSpeedMsgTimer_mS_M_u32	1236696832
CPKVehicleSpeedValidCount_Cnt_M_u16	19724
CityParkInputConsistentCount_Cnt_M_u16	8174
CityParkInputInvalidCount_Cnt_M_u16	61520
CityParkInputMsgTimer_mS_M_u32	2998025216
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3703189248
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	29663

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	4031368960
ComputerRazGCTSigValidCount_Cnt_M_u16	26359
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	63580
DMDFCTCPKSigValidCount_Cnt_M_u16	57119
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	18852
DMDRELAXECPKSigValidCount_Cnt_M_u16	38110
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	10646
DateInvalidTimer_mS_M_u32	1910337280
DiagMuxOnAbsentTimer_mS_M_u32	2929475328
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2513592064
ESPNTCEnableTimer_mS_M_u32	3354078976
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	14060
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	45
EffacDefaultDiagTimer_mS_M_u32[1]	98
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	7
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	197992192
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	45452
EtatMTSigValidCount_Cnt_M_u16	45410
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	55071
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	11497
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	8589
ISDAT4V2BSI552MsgTimer_mS_M_u32	1440243456
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	2331
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	4185
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	45410
ISDATBSI3F2MsgTimer_mS_M_u32	2635863040
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	37066
ISDATBSI412MsgLenValidCount_Cnt_M_u16	63737
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	45452
ISDATBSI412MsgTimer_mS_M_u32	1780580096
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	19002
ISDATBSI432MsgLenValidCount_Cnt_M_u16	25824
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	18634
ISDATDIRASentFltAcc_Cnt_M_u16	23822
ISDATDIRASentTimer_mS_M_u32	1236696832
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	1452
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	23546
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	54111
ISDYN2CMMMsgTimer_mS_M_u32	1182609152
ISDYNAASChkSumInvalidCount_Cnt_M_u16	13029
ISDYNAASChkSumValidCount_Cnt_M_u16	62528
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	38141
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	36860
ISDYNAASMsgLenValidCount_Cnt_M_u16	60334
ISDYNAASMsgTimeValidCount_Cnt_M_u16	13029
ISDYNAASMsgTimer_mS_M_u32	851480320
ISDYNABRChkSumInvalidCount_Cnt_M_u16	62433
ISDYNABRChkSumValidCount_Cnt_M_u16	36099
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	63592
ISDYNABRMsgCountValidCount_Cnt_M_u16	58883
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	59560
ISDYNABRMsgLenValidCount_Cnt_M_u16	33586
ISDYNABRMsgTimeValidCount_Cnt_M_u16	38950
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	52690
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	15017
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	45410
ISDYNCMM208MsgTimer_mS_M_u32	2341334784
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	52690
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	15017
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	4608

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	392302336
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	8491
ISDYNVOLChkSumValidCount_Cnt_M_u16	10229
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	37986
ISDYNVOLMsgCountValidCount_Cnt_M_u16	37797
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	23657
ISDYNVOLMsgLenValidCount_Cnt_M_u16	19731
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	11078
ISDYNVOLMsgTimer_mS_M_u32	2371211008
IgnOnTimer_mS_M_u32	3461746432
IgnTimeOff_Sec_M_u32	36116664
ManVehSpd_Kph_M_f32	529.735901
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	185
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	195
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3950001920
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	112
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3251347200
PrevISDATBSI412MsgDLCError_Cnt_M_u08	133
PrevISDATBSI412MsgRxTime_MSec_M_u32	1123831552
PrevISDATBSI432MsgDLCError_Cnt_M_u08	148
PrevISDATBSI432MsgRxTime_MSec_M_u32	3289329408
PrevISDATDIRAMsgTxTime_MSec_M_u32	3258994432
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	82
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2133712640
PrevISDYNAASMsgDLCError_Cnt_M_u08	57
PrevISDYNAASMsgRxTime_MSec_M_u32	1658572544
PrevISDYNABRMsgDLCError_Cnt_M_u08	66
PrevISDYNABRMsgRxTime_MSec_M_u32	2406354688
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	144
PrevISDYNCMM208MsgRxTime_MSec_M_u32	983879424
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	203
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2328243968
PrevISDYNVOLMsgDLCError_Cnt_M_u08	158
PrevISDYNVOLMsgRxTime_MSec_M_u32	1191005952
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2619834112
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	379.730103
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	35330
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	32308
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	27391
VitesseVehicleBVRampValidCount_Cnt_M_u16	4849
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	27943
VitesseVehicleBVSigValidCount_Cnt_M_u16	25761
VitesseVehicleBV_Kph_M_f32	334.950714
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	4608
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	18
VitesseVehiculeRoues_Kph_M_f32	418.153687
k_AASNTCEnableTimeout_mS_u16	53761
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	53257
k_AASNodeTimeout_mS_u16	27956
k_ABSNodeTimeout_mS_u16	63333
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	64649
k_ANGLEVOLANTSigValidThresh_Cnt_u16	33903
k_AngleVolantInvalidThresh_Cnt_u16	5082
k_AngleVolantValidThresh_Cnt_u16	61520
k_BSI552MsgTimeout_mS_u16	37693
k_BSINTCEnableTimeout_mS_u16	15186
k_BSINodeAbsentDiag_Cnt_str.Threshold	13772
k_BSINodeAbsentDiag_Cnt_str.PStep	40689
k_BSINodeAbsentDiag_Cnt_str.NStep	35866
k_BSINodeAbsentTimeout_mS_u16	58740
k_BSINodeTimeout_mS_u16	18634
k_BattOvHi_Volt_f32	5.78709984
k_BattOvLo_Volt_f32	11.7406998
k_BattUvHi_Volt_f32	18.7360992
k_BattUvLo_Volt_f32	1.39020002
k_CAVNTCEnableTimeout_mS_u16	43886
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	11787
k_CAVNodeTimeout_mS_u16	36145
k_CMM388MsgTimeout_mS_u16	12523
k_CMM388NTCEnableTimeout_mS_u16	65271
k_CMMNTCEnableTimeout_mS_u16	17971
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	48158
k_CONSANGLECPKMax_HwDeg_f32	254.251602
k_CONSANGLECPKMin_HwDeg_f32	-610.858215
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	49408
k_CONSANGLECPKSigValidThresh_Cnt_u16	61202
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	63138
k_CPKVehicleSpeedValidThresh_Cnt_u16	14465
k_CityParkInputInvalidThresh_Cnt_u16	7119
k_CityParkInputValidThresh_Cnt_u16	8174
k_ComputerRazGCTSigValidThresh_Cnt_u16	21865
k_CptTemporelSigValidThresh_Cnt_u16	39719
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	6056
k_DMDFCTCPKSigValidThresh_Cnt_u16	62002
k_DMDFCTCPKValidCount_Cnt_u16	37909
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	54111
k_DMDRELAXECPKSigValidThresh_Cnt_u16	1634
k_DMDRelaxeConsistentThresh_Cnt_u16	49616
k_DateValidThresh_Cnt_u16	8589
k_DefaultVehSpd_Kph_f32	201.777802
k_DiagMuxOnAbsentTimeout_mS_u16	51908
k_EMNodeTimeout_mS_u16	24694
k_ESPNTCEnableTimeout_mS_u16	53265
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	29446
k_EtatMTSigInvalidThresh_Cnt_u16	3244
k_EtatMTSigValidThresh_Cnt_u16	14350
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	30649
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	22511
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	15083
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	51500
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	27434
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	19902
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	14795
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	36657
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	43310
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	35834
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	41160
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	56750
k_ISDATDIRASentDiag_Cnt_str.Threshold	32887

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	20123
k_ISDATDIRASentDiag_Cnt_str.NStep	32507
k_ISDATDIRASentTimeout_mS_u16	33517
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	46839
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	31324
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	17645
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	41697
k_ISDYNAASChkSumValidThresh_Cnt_u16	31747
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	10088
k_ISDYNAASMsgCountValidThresh_Cnt_u16	21763
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	21461
k_ISDYNAASMsgLenValidThresh_Cnt_u16	26920
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	53591
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	52398
k_ISDYNABRChkSumValidThresh_Cnt_u16	32696
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	44845
k_ISDYNABRMsgCountValidThresh_Cnt_u16	16167
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	6726
k_ISDYNABRMsgLenValidThresh_Cnt_u16	26092
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	64978
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	42486
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	55815
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	9055
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	938
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	59236
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	61288
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	36249
k_ISDYNVOLChkSumValidThresh_Cnt_u16	17160
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	39517
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	48119
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	19864
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	32366
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	18219
k_IgnOnTimeout_mS_u16	24741
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	131.950195
k_PowerCutVehSpdLowThresh_Kph_f32	150.926697
k_PowerCutVehSpdLowTimeout_mS_u16	37053
k_VBattMaxAAS_Volt_f32	5.93760014
k_VBattMaxBSI_Volt_f32	15.4651003
k_VBattMaxCAV_Volt_f32	3.56960011
k_VBattMaxCMM388_Volt_f32	1.26600003
k_VBattMaxCMM_Volt_f32	14.3659
k_VBattMaxESP_Volt_f32	16.6949997
k_VBattMinAAS_Volt_f32	11.5219002
k_VBattMinBSI_Volt_f32	16.6949997
k_VBattMinCAV_Volt_f32	28.1294003
k_VBattMinCMM388_Volt_f32	21.2616997
k_VBattMinCMM_Volt_f32	30.4158993
k_VBattMinESP_Volt_f32	14.3659
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	1161
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	2791
k_VitesseVehicleBVRampValidThresh_Cnt_u16	17250
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	38645
k_VitesseVehicleBVSigValidThresh_Cnt_u16	33283
k_VitesseVehicleBVSpeedPassThresh_kph_f32	522.861877
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	39941
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	7287
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1910337280
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60393
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1305159680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	203
target_SrlComInput_Per1_Batt_Volt_f32.value	13.9965
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2476220160
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	146
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.276940376
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1333268224
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3015159552
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4178005760
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	44
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3345411840
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3335950080
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2673225472
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	249
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4175810304
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	113
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	148
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	155
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	201
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3611553536
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	158
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	205
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4174319360
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3868110592
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1969114880
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	6
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	30
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	79
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	123
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	150
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	170
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2618662656
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1279
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0418286063
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	203046
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	132.774597
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	34580

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1305159680	1305159680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	38950	38950	✔
CONSANGLECPK_HwDeg_M_f32	-2.34500003	-2.34500003 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1305159680	1305159680	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1305159680	1305159680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1305159680	1305159680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1305159680	1305159680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1305159680	1305159680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1305159680	1305159680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1305159680	1305159680	✔
ESPNTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1305159680	1305159680	✔
EffacDefaultDiagTimer_mS_M_u32[1]	98	98	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1305159680	1305159680	✔
ElecIntTimer_mS_M_u32[1]	7	7	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1305159680	1305159680	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	32887	32887	✔
ISDATDIRASentTimer_mS_M_u32	1305159680	1305159680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1305159680	1305159680	✔
IgnOnTimer_mS_M_u32	3461746432	3461746432	✔
IgnTimeOff_Sec_M_u32	36116664	36116664	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	37	37	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1333268224	1333268224	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	183	183	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3015159552	3015159552	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	215	215	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4178005760	4178005760	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	44	44	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3345411840	3345411840	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3258994432	3258994432	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2673225472	2673225472	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	249	249	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4175810304	4175810304	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	88	88	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3611553536	3611553536	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	241	241	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4174319360	4174319360	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	46	46	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3868110592	3868110592	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	183	183	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1969114880	1969114880	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2618662656	2618662656	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	379.730103	379.730103	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	334.950714	334.950714	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	418.153687	418.153687	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	38950	38950	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	36116664	36116664	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-2.34500003	-2.34500003 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	201.777802	201.777802	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.308 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	789071360
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	28822
AASNodeAbsentTimer_mS_M_u32	2278045184
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	4699
ANGLEVOLANTSigValidCount_Cnt_M_u16	3052
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	2883
AngleVolantMsgTimer_mS_M_u32	789071360
AngleVolantValidCount_Cnt_M_u16	25834
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	273413632
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4068636160
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3810584064
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3328419328
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	56274
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	906061312
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	64459
CAVNodeAbsentTimer_mS_M_u32	4281652736
CDD_SrlComVehSpd_Kph_G_f32	591.796997
CMM388NTCEnableTimer_mS_M_u32	3078428160
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2515195392
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	21191
CMMNodeAbsentTimer_mS_M_u32	1043179008
CONSANGLECPKSigInvalidCount_Cnt_M_u16	3819
CONSANGLECPKSigValidCount_Cnt_M_u16	43212
CONSANGLECPK_Cnt_M_u16	58279
CONSANGLECPK_HwDeg_M_f32	573.705627
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	58279
CPKVehicleSpeedMsgTimer_mS_M_u32	3812050432
CPKVehicleSpeedValidCount_Cnt_M_u16	12029
CityParkInputConsistentCount_Cnt_M_u16	59662

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	53480
CityParkInputMsgTimer_mS_M_u32	1333268224
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	351024640
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	60090
ComputerRazGCTSigInvalidTimer_mS_M_u32	549279232
ComputerRazGCTSigValidCount_Cnt_M_u16	30707
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	59588
DMDFCTCPKSigValidCount_Cnt_M_u16	14653
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	7021
DMDRELAXECPKSigValidCount_Cnt_M_u16	7806
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	29336
DateInvalidTimer_mS_M_u32	4068636160
DiagMuxOnAbsentTimer_mS_M_u32	2072380928
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3328419328
ESPNTCEnableTimer_mS_M_u32	1465464320
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	50324
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	66
EffacDefaultDiagTimer_mS_M_u32[1]	78
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	20
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3212011008
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	43252
EtatMTSigValidCount_Cnt_M_u16	65073
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	52733
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	61790
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	43507
ISDAT4V2BSI552MsgTimer_mS_M_u32	508667392
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	62919
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	54477
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0
ISDATBSI3F2MsgTimer_mS_M_u32	1416889856
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	11193
ISDATBSI412MsgLenValidCount_Cnt_M_u16	42991
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	43252
ISDATBSI412MsgTimer_mS_M_u32	3992339968
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	50667
ISDATBSI432MsgLenValidCount_Cnt_M_u16	2744
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	15484
ISDATDIRASentFltAcc_Cnt_M_u16	4016
ISDATDIRASentTimer_mS_M_u32	3812050432
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	13077
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	25834
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	9147
ISDYN2CMMMsgTimer_mS_M_u32	2745382400
ISDYNAASChkSumInvalidCount_Cnt_M_u16	17832
ISDYNAASChkSumValidCount_Cnt_M_u16	26202
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	34273
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	44774
ISDYNAASMsgLenValidCount_Cnt_M_u16	24719
ISDYNAASMsgTimeValidCount_Cnt_M_u16	17832
ISDYNAASMsgTimer_mS_M_u32	2757301760
ISDYNABRChkSumInvalidCount_Cnt_M_u16	43062
ISDYNABRChkSumValidCount_Cnt_M_u16	24976
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	49439
ISDYNABRMsgCountValidCount_Cnt_M_u16	23825
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	64866
ISDYNABRMsgLenValidCount_Cnt_M_u16	21123
ISDYNABRMsgTimeValidCount_Cnt_M_u16	58279
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	31314

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	52365
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	65073
ISDYNCMM208MsgTimer_mS_M_u32	124843520
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	31314
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	52365
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	56024
ISDYNCMM388MsgTimer_mS_M_u32	1551144448
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	8153
ISDYNVOLChkSumValidCount_Cnt_M_u16	12346
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	44210
ISDYNVOLMsgCountValidCount_Cnt_M_u16	45995
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	34845
ISDYNVOLMsgLenValidCount_Cnt_M_u16	23262
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	21191
ISDYNVOLMsgTimer_mS_M_u32	2040092160
IgnOnTimer_mS_M_u32	127440384
IgnTimeOff_Sec_M_u32	2415553488
ManVehSpd_Kph_M_f32	626.848694
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	186
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	25
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	352978432
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	61
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3078088192
PrevISDATBSI412MsgDLCError_Cnt_M_u08	208
PrevISDATBSI412MsgRxTime_MSec_M_u32	312858112
PrevISDATBSI432MsgDLCError_Cnt_M_u08	183
PrevISDATBSI432MsgRxTime_MSec_M_u32	4075632128
PrevISDATDIRAMsgTxTime_MSec_M_u32	2765739520
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	176
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3629196800
PrevISDYNAASMsgDLCError_Cnt_M_u08	75
PrevISDYNAASMsgRxTime_MSec_M_u32	2433177088
PrevISDYNABRMsgDLCError_Cnt_M_u08	113
PrevISDYNABRMsgRxTime_MSec_M_u32	609261056
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	168
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1840010752
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	206
PrevISDYNCMM388MsgRxTime_MSec_M_u32	986199552
PrevISDYNVOLMsgDLCError_Cnt_M_u08	76
PrevISDYNVOLMsgRxTime_MSec_M_u32	1252185600
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4024714752
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	408.348114
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	22740
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	16637
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	59869
VitesseVehicleBVRampValidCount_Cnt_M_u16	46790
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	31972
VitesseVehicleBVSigValidCount_Cnt_M_u16	31541

Name	Input Value
VitesseVehicleBV_Kph_M_f32	591.398926
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	56024
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	21858
VitesseVehiculeRoues_Kph_M_f32	443.061188
k_AASNTCEnableTimeout_mS_u16	25110
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	1213
k_AASNodeTimeout_mS_u16	29693
k_ABSNodeTimeout_mS_u16	20393
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	43774
k_ANGLEVOLANTSigValidThresh_Cnt_u16	43019
k_AngleVolantInvalidThresh_Cnt_u16	26058
k_AngleVolantValidThresh_Cnt_u16	53480
k_BSI552MsgTimeout_mS_u16	2017
k_BSINTCEnableTimeout_mS_u16	21155
k_BSINodeAbsentDiag_Cnt_str.Threshold	41955
k_BSINodeAbsentDiag_Cnt_str.PStep	49077
k_BSINodeAbsentDiag_Cnt_str.NStep	24442
k_BSINodeAbsentTimeout_mS_u16	10747
k_BSINodeTimeout_mS_u16	15484
k_BattOvHi_Volt_f32	9.12180042
k_BattOvLo_Volt_f32	11.7955999
k_BattUvHi_Volt_f32	3.59990001
k_BattUvLo_Volt_f32	5.45930004
k_CAVNTCEnableTimeout_mS_u16	38798
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	53433
k_CAVNodeTimeout_mS_u16	29639
k_CMM388MsgTimeout_mS_u16	58262
k_CMM388NTCEnableTimeout_mS_u16	43378
k_CMMNTCEnableTimeout_mS_u16	40575
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	20798
k_CONSANGLECPKMax_HwDeg_f32	708.803406
k_CONSANGLECPKMin_HwDeg_f32	-289.501007
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	52696
k_CONSANGLECPKSigValidThresh_Cnt_u16	34914
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	4019
k_CPKVehicleSpeedValidThresh_Cnt_u16	53396
k_CityParkInputInvalidThresh_Cnt_u16	26732
k_CityParkInputValidThresh_Cnt_u16	59662
k_ComputerRazGCTSigValidThresh_Cnt_u16	51421
k_CptTemporelSigValidThresh_Cnt_u16	60515
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	28770
k_DMDFCTCPKSigValidThresh_Cnt_u16	1411
k_DMDFCTCPKValidCount_Cnt_u16	16410
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	9147
k_DMDRELAXECPKSigValidThresh_Cnt_u16	36724
k_DMDRelaxeConsistentThresh_Cnt_u16	38186
k_DateValidThresh_Cnt_u16	43507
k_DefaultVehSpd_Kph_f32	237.521103
k_DiagMuxOnAbsentTimeout_mS_u16	17357
k_EMNodeTimeout_mS_u16	19960
k_ESPNTCEnableTimeout_mS_u16	33447
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	52358
k_EtatMTSigInvalidThresh_Cnt_u16	18901
k_EtatMTSigValidThresh_Cnt_u16	19567
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	43118
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	56460
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	52247
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	14740
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	18522
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	50397
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	31544

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	4037
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	30991
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	22571
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	20096
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	57872
k_ISDATDIRASentDiag_Cnt_str.Threshold	58484
k_ISDATDIRASentDiag_Cnt_str.PStep	41555
k_ISDATDIRASentDiag_Cnt_str.NStep	45799
k_ISDATDIRASentTimeout_mS_u16	11026
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	47669
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	2883
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	37907
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	39734
k_ISDYNAASChkSumValidThresh_Cnt_u16	38032
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	13343
k_ISDYNAASMsgCountValidThresh_Cnt_u16	4113
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	22618
k_ISDYNAASMsgLenValidThresh_Cnt_u16	20513
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	24915
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	59728
k_ISDYNABRChkSumValidThresh_Cnt_u16	62705
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	20178
k_ISDYNABRMsgCountValidThresh_Cnt_u16	33699
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	34247
k_ISDYNABRMsgLenValidThresh_Cnt_u16	14228
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	45986
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	54520
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	33794
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	48508
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	34139
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	48876
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	13216
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	12620
k_ISDYNVOLChkSumValidThresh_Cnt_u16	50626
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	40513
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	42164
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	1232
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	50957
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	12569
k_IgnOnTimeout_mS_u16	59432
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	23.5039997
k_PowerCutVehSpdLowThresh_Kph_f32	70.5743027
k_PowerCutVehSpdLowTimeout_mS_u16	5602
k_VBattMaxAAS_Volt_f32	16.8444004
k_VBattMaxBSI_Volt_f32	6.3730998
k_VBattMaxCAV_Volt_f32	9.73620033
k_VBattMaxCMM388_Volt_f32	30.6334991
k_VBattMaxCMM_Volt_f32	3.03189993
k_VBattMaxESP_Volt_f32	6.58269978
k_VBattMinAAS_Volt_f32	8.95359993
k_VBattMinBSI_Volt_f32	6.58269978
k_VBattMinCAV_Volt_f32	4.73180008
k_VBattMinCMM388_Volt_f32	18.6963005
k_VBattMinCMM_Volt_f32	21.4944
k_VBattMinESP_Volt_f32	3.03189993
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	39295
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	64292
k_VitesseVehicleBVRampValidThresh_Cnt_u16	40882
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	58170
k_VitesseVehicleBVSigValidThresh_Cnt_u16	22223
k_VitesseVehicleBVSpeedPassThresh_kph_f32	520.561218
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	61131
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	12852
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4068636160
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	2073
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1490897664
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	206
target_SrlComInput_Per1_Batt_Volt_f32.value	30.2423
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	336750080
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	99
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.825273812
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2352125440
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1710470656
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3699693056
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4159043072
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3222738432
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	79
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1024996864
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	201
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1995003392
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	85
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	140
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	190
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	192
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2085549568
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	65
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	147
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	217
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	213
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2888668672
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	7
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3916346880
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	146
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2206193152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	53
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	77
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	94
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	177
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	189
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3499746816
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2383
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.588585258
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	920512
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	245.280594

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	10654		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1490897664	1490897664	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1490897664	1490897664	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	41955	41955	✔
BSINodeAbsentTimer_mS_M_u32	1490897664	1490897664	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1490897664	1490897664	✔
CDD_SrlComVehSpd_Kph_G_f32	626.848694	626.848694	✔
CMM388NTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1490897664	1490897664	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	58279	58279	✔
CONSANGLECPK_HwDeg_M_f32	573.705627	573.705627 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1490897664	1490897664	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1490897664	1490897664	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1490897664	1490897664	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1490897664	1490897664	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1490897664	1490897664	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1490897664	1490897664	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1490897664	1490897664	✔
ESPNTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1490897664	1490897664	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	66	66	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	78	78	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	20	20	✔
ElecIntTimer_mS_M_u32[1]	20	20	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1490897664	1490897664	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	43507	43507	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	43252	43252	✔
ISDATBSI412MsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	15484	15484	✔
ISDATBSI432MsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDATDIRASentFltAcc_Cnt_M_u16	58484	58484	✔
ISDATDIRASentTimer_mS_M_u32	1490897664	1490897664	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	9147	9147	✔
ISDYN2CMMMsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	17832	17832	✔
ISDYNAASMsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	58279	58279	✔
ISDYNABRMsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	65073	65073	✔
ISDYNCMM208MsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	56024	56024	✔
ISDYNCMM388MsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	21191	21191	✔
ISDYNVOLMsgTimer_mS_M_u32	1490897664	1490897664	✔
IgnOnTimer_mS_M_u32	127440384	127440384	✔
IgnTimeOff_Sec_M_u32	2415553488	2415553488	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	31	31	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2352125440	2352125440	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	77	77	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1710470656	1710470656	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	21	21	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3699693056	3699693056	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	125	125	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4159043072	4159043072	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2765739520	2765739520	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	79	79	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1024996864	1024996864	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	201	201	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1995003392	1995003392	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	174	174	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2085549568	2085549568	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	213	213	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2888668672	2888668672	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	7	7	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3916346880	3916346880	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	146	146	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2206193152	2206193152	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3499746816	3499746816	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	408.348114	408.348114	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	591.398926	591.398926	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	443.061188	443.061188	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	58279	58279	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2415553488	2415553488	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	573.705627	573.705627 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	626.848694	626.848694	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.309 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2535321856
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	11378
AASNodeAbsentTimer_mS_M_u32	3097370880
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	63780
ANGLEVOLANTSigValidCount_Cnt_M_u16	24112
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	20587
AngleVolantMsgTimer_mS_M_u32	2535321856
AngleVolantValidCount_Cnt_M_u16	18422
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3725779200
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	829382912
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	626266368
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	4136358144
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	14527
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1320325376
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	42324
CAVNodeAbsentTimer_mS_M_u32	1289240832
CDD_SrlComVehSpd_Kph_G_f32	123.031197
CMM388NTCEnableTimer_mS_M_u32	2499772672
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3770040576
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	27425
CMMNodeAbsentTimer_mS_M_u32	925749504
CONSANGLECPKSigInvalidCount_Cnt_M_u16	62069
CONSANGLECPKSigValidCount_Cnt_M_u16	46737
CONSANGLECPK_Cnt_M_u16	12800
CONSANGLECPK_HwDeg_M_f32	-478.463715
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	12800
CPKVehicleSpeedMsgTimer_mS_M_u32	4136694016
CPKVehicleSpeedValidCount_Cnt_M_u16	12773
CityParkInputConsistentCount_Cnt_M_u16	19338
CityParkInputInvalidCount_Cnt_M_u16	35070
CityParkInputMsgTimer_mS_M_u32	2352125440
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2704417024
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	19974

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2856239360
ComputerRazGCTSigValidCount_Cnt_M_u16	29403
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	45418
DMDFCTCPKSigValidCount_Cnt_M_u16	45502
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	42478
DMDRELAXECPKSigValidCount_Cnt_M_u16	61050
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	47982
DateInvalidTimer_mS_M_u32	829382912
DiagMuxOnAbsentTimer_mS_M_u32	3634671872
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4136358144
ESPNTCEnableTimer_mS_M_u32	3454738688
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	22393
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	101
EffacDefaultDiagTimer_mS_M_u32[1]	105
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	555
ElecIntTimer_mS_M_u32[1]	5556
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4200370432
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	44441
EtatMTSigValidCount_Cnt_M_u16	44961
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	32063
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	42203
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	47004
ISDAT4V2BSI552MsgTimer_mS_M_u32	650236160
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	52383
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	20815
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	65535
ISDATBSI3F2MsgTimer_mS_M_u32	2245701888
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	50120
ISDATBSI412MsgLenValidCount_Cnt_M_u16	12520
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	44441
ISDATBSI412MsgTimer_mS_M_u32	2454974720
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	41397
ISDATBSI432MsgLenValidCount_Cnt_M_u16	5389
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	59201
ISDATDIRASentFltAcc_Cnt_M_u16	15781
ISDATDIRASentTimer_mS_M_u32	4136694016
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	31670
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	18422
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	40069
ISDYN2CMMMsgTimer_mS_M_u32	2433556736
ISDYNAASChkSumInvalidCount_Cnt_M_u16	30012
ISDYNAASChkSumValidCount_Cnt_M_u16	58600
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	33041
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	47107
ISDYNAASMsgLenValidCount_Cnt_M_u16	21703
ISDYNAASMsgTimeValidCount_Cnt_M_u16	30012
ISDYNAASMsgTimer_mS_M_u32	1047232768
ISDYNABRChkSumInvalidCount_Cnt_M_u16	23826
ISDYNABRChkSumValidCount_Cnt_M_u16	41670
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	40663
ISDYNABRMsgCountValidCount_Cnt_M_u16	40131
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	49936
ISDYNABRMsgLenValidCount_Cnt_M_u16	21868
ISDYNABRMsgTimeValidCount_Cnt_M_u16	12800
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	34541
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	50686
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	44961
ISDYNCMM208MsgTimer_mS_M_u32	3433292032
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	34541
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	50686
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	7724

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3826843904
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	63403
ISDYNVOLChkSumValidCount_Cnt_M_u16	22599
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	40352
ISDYNVOLMsgCountValidCount_Cnt_M_u16	31348
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	28894
ISDYNVOLMsgLenValidCount_Cnt_M_u16	2649
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	27425
ISDYNVOLMsgTimer_mS_M_u32	262848768
IgnOnTimer_mS_M_u32	1923940608
IgnTimeOff_Sec_M_u32	725061995
ManVehSpd_Kph_M_f32	581.277283
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	187
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	102
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	471380224
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	125
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3293516032
PrevISDATBSI412MsgDLCError_Cnt_M_u08	73
PrevISDATBSI412MsgRxTime_MSec_M_u32	377831680
PrevISDATBSI432MsgDLCError_Cnt_M_u08	91
PrevISDATBSI432MsgRxTime_MSec_M_u32	1261379840
PrevISDATDIRAMsgTxTime_MSec_M_u32	803815680
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	215
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1455640832
PrevISDYNAASMsgDLCError_Cnt_M_u08	25
PrevISDYNAASMsgRxTime_MSec_M_u32	23118080
PrevISDYNABRMsgDLCError_Cnt_M_u08	219
PrevISDYNABRMsgRxTime_MSec_M_u32	4236574976
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	215
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1064419584
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	229
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2677940480
PrevISDYNVOLMsgDLCError_Cnt_M_u08	131
PrevISDYNVOLMsgRxTime_MSec_M_u32	2727231744
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3297374464
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	616.973816
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	62009
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	60285
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	41758
VitesseVehicleBVRampValidCount_Cnt_M_u16	60962
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	7561
VitesseVehicleBVSigValidCount_Cnt_M_u16	29781
VitesseVehicleBV_Kph_M_f32	578.023071
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	7724
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	57423
VitesseVehiculeRoues_Kph_M_f32	62.8827019
k_AASNTCEnableTimeout_mS_u16	12979
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	29821
k_AASNodeTimeout_mS_u16	21117
k_ABSNodeTimeout_mS_u16	20667
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	65148
k_ANGLEVOLANTSigValidThresh_Cnt_u16	18708
k_AngleVolantInvalidThresh_Cnt_u16	52183
k_AngleVolantValidThresh_Cnt_u16	35070
k_BSI552MsgTimeout_mS_u16	34002
k_BSINTCEnableTimeout_mS_u16	56205
k_BSINodeAbsentDiag_Cnt_str.Threshold	58811
k_BSINodeAbsentDiag_Cnt_str.PStep	35974
k_BSINodeAbsentDiag_Cnt_str.NStep	30581
k_BSINodeAbsentTimeout_mS_u16	54339
k_BSINodeTimeout_mS_u16	59201
k_BattOvHi_Volt_f32	19.2852001
k_BattOvLo_Volt_f32	14.6597996
k_BattUvHi_Volt_f32	0.87529999
k_BattUvLo_Volt_f32	15.8318996
k_CAVNTCEnableTimeout_mS_u16	19724
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	24202
k_CAVNodeTimeout_mS_u16	13281
k_CMM388MsgTimeout_mS_u16	54130
k_CMM388NTCEnableTimeout_mS_u16	61918
k_CMMNTCEnableTimeout_mS_u16	45687
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	23739
k_CONSANGLECPKMax_HwDeg_f32	394.187592
k_CONSANGLECPKMin_HwDeg_f32	-652.997803
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	17708
k_CONSANGLECPKSigValidThresh_Cnt_u16	18255
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	55131
k_CPKVehicleSpeedValidThresh_Cnt_u16	311
k_CityParkInputInvalidThresh_Cnt_u16	29808
k_CityParkInputValidThresh_Cnt_u16	19338
k_ComputerRazGCTSigValidThresh_Cnt_u16	11101
k_CptTemporelSigValidThresh_Cnt_u16	57997
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	27152
k_DMDFCTCPKSigValidThresh_Cnt_u16	15468
k_DMDFCTCPKValidCount_Cnt_u16	11239
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	40069
k_DMDRELAXECPKSigValidThresh_Cnt_u16	19225
k_DMDRelaxeConsistentThresh_Cnt_u16	37367
k_DateValidThresh_Cnt_u16	47004
k_DefaultVehSpd_Kph_f32	56.1506996
k_DiagMuxOnAbsentTimeout_mS_u16	10638
k_EMNodeTimeout_mS_u16	43342
k_ESPNTCEnableTimeout_mS_u16	32960
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	2787
k_EtatMTSigInvalidThresh_Cnt_u16	46133
k_EtatMTSigValidThresh_Cnt_u16	7721
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	47402
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	40593
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	1647
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	30008
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	27304
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	34908
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	62926
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	31206
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	6217
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	58484
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	25396
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	51654
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	17534
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	5463
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	20587
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	64636
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	33810
k_ISDYNAASChkSumValidThresh_Cnt_u16	2502
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	17879
k_ISDYNAASMsgCountValidThresh_Cnt_u16	33731
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	56486
k_ISDYNAASMsgLenValidThresh_Cnt_u16	19985
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	15676
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	14150
k_ISDYNABRChkSumValidThresh_Cnt_u16	42530
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	57279
k_ISDYNABRMsgCountValidThresh_Cnt_u16	37643
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	53793
k_ISDYNABRMsgLenValidThresh_Cnt_u16	65145
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	48910
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	3533
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7917
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	12800
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	40996
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	17712
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	16598
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	48911
k_ISDYNVOLChkSumValidThresh_Cnt_u16	58223
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	48754
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	26970
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	2565
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	50445
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	14890
k_IgnOnTimeout_mS_u16	2683
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	176.701904
k_PowerCutVehSpdLowThresh_Kph_f32	235.490997
k_PowerCutVehSpdLowTimeout_mS_u16	18255
k_VBattMaxAAS_Volt_f32	6.53550005
k_VBattMaxBSI_Volt_f32	16.6154003
k_VBattMaxCAV_Volt_f32	4.49560022
k_VBattMaxCMM388_Volt_f32	31.8449001
k_VBattMaxCMM_Volt_f32	13.5550003
k_VBattMaxESP_Volt_f32	4.28830004
k_VBattMinAAS_Volt_f32	3.62080002
k_VBattMinBSI_Volt_f32	4.28830004
k_VBattMinCAV_Volt_f32	11.4846001
k_VBattMinCMM388_Volt_f32	22.5070992
k_VBattMinCMM_Volt_f32	22.3304996
k_VBattMinESP_Volt_f32	13.5550003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	8057
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	40008
k_VitesseVehicleBVRampValidThresh_Cnt_u16	50336
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	16199
k_VitesseVehicleBVSigValidThresh_Cnt_u16	17991
k_VitesseVehicleBVSpeedPassThresh_kph_f32	624.528198
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	52308
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	46040
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	829382912
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	21877
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2683494912
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	229
target_SrlComInput_Per1_Batt_Volt_f32.value	8.73750019
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	947884288
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	104
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.773620725
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3437166848
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	149
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	740008192
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	204
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4108861696
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	97
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	256172288
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1664188672
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3635290368
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	96
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1471856896
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	31
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	104
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	244
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	177
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1711923456
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	44
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	60
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	107
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	418251008
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1303027968
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	1
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2885107968
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	32
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	48
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	56
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	68
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	72
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	149
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2162757888
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	176
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.116139427
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1028777
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	118.622101
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	10203

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2683494912	2683494912	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	58811	58811	✔
BSINodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔
CDD_SrlComVehSpd_Kph_G_f32	581.277283	581.277283	✔
CMM388NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	12800	12800	✔
CONSANGLECPK_HwDeg_M_f32	-478.463715	-478.463715 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2683494912	2683494912	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2683494912	2683494912	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2683494912	2683494912	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2683494912	2683494912	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2683494912	2683494912	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2683494912	2683494912	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2683494912	2683494912	✔
ESPNTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	101	101	✔
EffacDefaultDiagTimer_mS_M_u32[1]	105	105	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	555	555	✔
ElecIntTimer_mS_M_u32[1]	5556	5556	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2683494912	2683494912	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	47004	47004	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	65535	65535	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	44441	44441	✔
ISDATBSI412MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	59201	59201	✔
ISDATBSI432MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11170	11170	✔
ISDATDIRASentTimer_mS_M_u32	2683494912	2683494912	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	40069	40069	✔
ISDYN2CMMMsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	30012	30012	✔
ISDYNAASMsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	12800	12800	✔
ISDYNABRMsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	44961	44961	✔
ISDYNCMM208MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	7724	7724	✔
ISDYNCMM388MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	27425	27425	✔
ISDYNVOLMsgTimer_mS_M_u32	2683494912	2683494912	✔
IgnOnTimer_mS_M_u32	1923940608	1923940608	✔
IgnTimeOff_Sec_M_u32	725061995	725061995	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	212	212	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3437166848	3437166848	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	149	149	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	740008192	740008192	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	204	204	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4108861696	4108861696	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	97	97	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	256172288	256172288	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	803815680	803815680	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	67	67	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3635290368	3635290368	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	96	96	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1471856896	1471856896	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	177	177	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1711923456	1711923456	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	93	93	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	418251008	418251008	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1303027968	1303027968	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	1	1	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2885107968	2885107968	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2162757888	2162757888	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	616.973816	616.973816	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	578.023071	578.023071	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	62.8827019	62.8827019	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	12800	12800	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	725061995	725061995	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-478.463715	-478.463715 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.310 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	524873728
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	20811
AASNodeAbsentTimer_mS_M_u32	931684352
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	54579
ANGLEVOLANTSigValidCount_Cnt_M_u16	45264
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	2400
AngleVolantMsgTimer_mS_M_u32	524873728
AngleVolantValidCount_Cnt_M_u16	5440
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2318016512
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2719260672
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1965461504
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2424262656
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	16994
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2466975744
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	38693
CAVNodeAbsentTimer_mS_M_u32	2337931264
CDD_SrlComVehSpd_Kph_G_f32	51.0812988
CMM388NTCEnableTimer_mS_M_u32	1608794112
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3351248896
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	58750
CMMNodeAbsentTimer_mS_M_u32	3600371712
CONSANGLECPKSigInvalidCount_Cnt_M_u16	7233
CONSANGLECPKSigValidCount_Cnt_M_u16	6830
CONSANGLECPK_Cnt_M_u16	9313
CONSANGLECPK_HwDeg_M_f32	-227.965607
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	9313
CPKVehicleSpeedMsgTimer_mS_M_u32	2364534784
CPKVehicleSpeedValidCount_Cnt_M_u16	7930
CityParkInputConsistentCount_Cnt_M_u16	23172
CityParkInputInvalidCount_Cnt_M_u16	49959
CityParkInputMsgTimer_mS_M_u32	3437166848
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3452723200
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	15503

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	757497856
ComputerRazGCTSigValidCount_Cnt_M_u16	26769
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	63971
DMDFCTCPKSigValidCount_Cnt_M_u16	9128
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	30421
DMDRELAXECPKSigValidCount_Cnt_M_u16	42994
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	58710
DateInvalidTimer_mS_M_u32	2719260672
DiagMuxOnAbsentTimer_mS_M_u32	3853824000
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2424262656
ESPNTCEnableTimer_mS_M_u32	1805737984
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	23351
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	99
EffacDefaultDiagTimer_mS_M_u32[1]	999
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	963
ElecIntTimer_mS_M_u32[1]	7853
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3087863808
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	20245
EtatMTSigValidCount_Cnt_M_u16	17342
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	9187
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	63440
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	2574
ISDAT4V2BSI552MsgTimer_mS_M_u32	1474121728
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	57731
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	60980
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	51627
ISDATBSI3F2MsgTimer_mS_M_u32	907194368
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	12552
ISDATBSI412MsgLenValidCount_Cnt_M_u16	17513
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	20245
ISDATBSI412MsgTimer_mS_M_u32	2242310144
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	37314
ISDATBSI432MsgLenValidCount_Cnt_M_u16	29307
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	50526
ISDATDIRASentFltAcc_Cnt_M_u16	21042
ISDATDIRASentTimer_mS_M_u32	2364534784
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	40767
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	5440
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	25746
ISDYN2CMMMsgTimer_mS_M_u32	708534272
ISDYNAASChkSumInvalidCount_Cnt_M_u16	7917
ISDYNAASChkSumValidCount_Cnt_M_u16	23210
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	38383
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	56088
ISDYNAASMsgLenValidCount_Cnt_M_u16	61325
ISDYNAASMsgTimeValidCount_Cnt_M_u16	7917
ISDYNAASMsgTimer_mS_M_u32	329269248
ISDYNABRChkSumInvalidCount_Cnt_M_u16	14570
ISDYNABRChkSumValidCount_Cnt_M_u16	4751
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	52764
ISDYNABRMsgCountValidCount_Cnt_M_u16	24345
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	54896
ISDYNABRMsgLenValidCount_Cnt_M_u16	27165
ISDYNABRMsgTimeValidCount_Cnt_M_u16	9313
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	39624
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	15446
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	17342
ISDYNCMM208MsgTimer_mS_M_u32	1115103232
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	39624
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	15446
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	60062

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3096952832
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	25759
ISDYNVOLChkSumValidCount_Cnt_M_u16	36236
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	36161
ISDYNVOLMsgCountValidCount_Cnt_M_u16	8582
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	58120
ISDYNVOLMsgLenValidCount_Cnt_M_u16	57685
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	58750
ISDYNVOLMsgTimer_mS_M_u32	2900525056
IgnOnTimer_mS_M_u32	1557905408
IgnTimeOff_Sec_M_u32	401984541
ManVehSpd_Kph_M_f32	267.839294
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	188
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3948457984
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	56
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1144360960
PrevISDATBSI412MsgDLCError_Cnt_M_u08	68
PrevISDATBSI412MsgRxTime_MSec_M_u32	575864832
PrevISDATBSI432MsgDLCError_Cnt_M_u08	189
PrevISDATBSI432MsgRxTime_MSec_M_u32	64315392
PrevISDATDIRAMsgTxTime_MSec_M_u32	1713831936
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	10
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2916667392
PrevISDYNAASMsgDLCError_Cnt_M_u08	15
PrevISDYNAASMsgRxTime_MSec_M_u32	801144832
PrevISDYNABRMsgDLCError_Cnt_M_u08	41
PrevISDYNABRMsgRxTime_MSec_M_u32	525582336
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	85
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4186800128
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	173
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2189975552
PrevISDYNVOLMsgDLCError_Cnt_M_u08	142
PrevISDYNVOLMsgRxTime_MSec_M_u32	3795320832
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1191505920
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	51.1464005
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	33910
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	33643
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	17863
VitesseVehicleBVRampValidCount_Cnt_M_u16	20348
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	15364
VitesseVehicleBVSigValidCount_Cnt_M_u16	16993
VitesseVehicleBV_Kph_M_f32	606.413025
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	60062
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	3827
VitesseVehiculeRoues_Kph_M_f32	437.9151
k_AASNTCEnableTimeout_mS_u16	44616
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	27563
k_AASNodeTimeout_mS_u16	20075
k_ABSNodeTimeout_mS_u16	40944
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	22381
k_ANGLEVOLANTSigValidThresh_Cnt_u16	45670
k_AngleVolantInvalidThresh_Cnt_u16	63005
k_AngleVolantValidThresh_Cnt_u16	49959
k_BSI552MsgTimeout_mS_u16	60778
k_BSINTCEnableTimeout_mS_u16	17466
k_BSINodeAbsentDiag_Cnt_str.Threshold	60384
k_BSINodeAbsentDiag_Cnt_str.PStep	2238
k_BSINodeAbsentDiag_Cnt_str.NStep	59696
k_BSINodeAbsentTimeout_mS_u16	56792
k_BSINodeTimeout_mS_u16	50526
k_BattOvHi_Volt_f32	7.51070023
k_BattOvLo_Volt_f32	11.1989002
k_BattUvHi_Volt_f32	5.16709995
k_BattUvLo_Volt_f32	28.6935005
k_CAVNTCEnableTimeout_mS_u16	12029
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	50051
k_CAVNodeTimeout_mS_u16	2045
k_CMM388MsgTimeout_mS_u16	23627
k_CMM388NTCEnableTimeout_mS_u16	45319
k_CMMNTCEnableTimeout_mS_u16	36859
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	18863
k_CONSANGLECPKMax_HwDeg_f32	94.603302
k_CONSANGLECPKMin_HwDeg_f32	-241.544601
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	30110
k_CONSANGLECPKSigValidThresh_Cnt_u16	55795
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	47057
k_CPKVehicleSpeedValidThresh_Cnt_u16	62651
k_CityParkInputInvalidThresh_Cnt_u16	60112
k_CityParkInputValidThresh_Cnt_u16	23172
k_ComputerRazGCTSigValidThresh_Cnt_u16	15689
k_CptTemporelSigValidThresh_Cnt_u16	45690
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	57712
k_DMDFCTCPKSigValidThresh_Cnt_u16	46365
k_DMDFCTCPKValidCount_Cnt_u16	2282
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	25746
k_DMDRELAXECPKSigValidThresh_Cnt_u16	33687
k_DMDRelaxeConsistentThresh_Cnt_u16	42749
k_DateValidThresh_Cnt_u16	2574
k_DefaultVehSpd_Kph_f32	166.683807
k_DiagMuxOnAbsentTimeout_mS_u16	62903
k_EMNodeTimeout_mS_u16	39862
k_ESPNTCEnableTimeout_mS_u16	46305
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	57143
k_EtatMTSigInvalidThresh_Cnt_u16	32641
k_EtatMTSigValidThresh_Cnt_u16	60518
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	3684
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	55532
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	64981
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	35768
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	17961
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	13132
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	14711
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	59376
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	32262
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	56581
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	15238
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	42000
k_ISDATDIRASentDiag_Cnt_str.Threshold	6549

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	63930
k_ISDATDIRASentDiag_Cnt_str.NStep	24627
k_ISDATDIRASentTimeout_mS_u16	12966
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	17757
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	2400
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	12717
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	50154
k_ISDYNAASChkSumValidThresh_Cnt_u16	56719
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	55580
k_ISDYNAASMsgCountValidThresh_Cnt_u16	43545
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	2606
k_ISDYNAASMsgLenValidThresh_Cnt_u16	43951
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	30190
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	53710
k_ISDYNABRChkSumValidThresh_Cnt_u16	53243
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	19810
k_ISDYNABRMsgCountValidThresh_Cnt_u16	15935
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	45182
k_ISDYNABRMsgLenValidThresh_Cnt_u16	26167
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	34358
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	33210
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	62361
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	31714
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	57395
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	64464
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	64415
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	6963
k_ISDYNVOLChkSumValidThresh_Cnt_u16	2260
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	19020
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	3795
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	59857
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	45946
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	14948
k_IgnOnTimeout_mS_u16	59631
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	89.5299988
k_PowerCutVehSpdLowThresh_Kph_f32	81.1628036
k_PowerCutVehSpdLowTimeout_mS_u16	57460
k_VBattMaxAAS_Volt_f32	17.6650009
k_VBattMaxBSI_Volt_f32	18.4270992
k_VBattMaxCAV_Volt_f32	27.8773994
k_VBattMaxCMM388_Volt_f32	5.70629978
k_VBattMaxCMM_Volt_f32	0.860499978
k_VBattMaxESP_Volt_f32	24.5032997
k_VBattMinAAS_Volt_f32	7.16970015
k_VBattMinBSI_Volt_f32	24.5032997
k_VBattMinCAV_Volt_f32	30.9836998
k_VBattMinCMM388_Volt_f32	4.16800022
k_VBattMinCMM_Volt_f32	13.0445995
k_VBattMinESP_Volt_f32	0.860499978
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	12023
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	54088
k_VitesseVehicleBVRampValidThresh_Cnt_u16	6209
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	55436
k_VitesseVehicleBVSigValidThresh_Cnt_u16	40525
k_VitesseVehicleBVSpeedPassThresh_kph_f32	308.58139
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	8741
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	22106
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2719260672
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	173
target_SrlComInput_Per1_Batt_Volt_f32.value	5.55459976
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1235488768
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	96
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.889289796
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	58
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2521153536
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3004162048
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3542745088
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1049894912
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1028538368
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	391667712
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	347242496
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	55
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	64
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2386894848
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	40
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2920857600
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1247993856
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2851930112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	33
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	146
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	185
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4133982208
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1035
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0104011958
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	896424
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	234.019501
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	60304

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	60384	60384	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	267.839294	267.839294	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	9313	9313	✔
CONSANGLECPK_HwDeg_M_f32	-227.965607	-227.965607 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3251510528	3251510528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	99	99	✔
EffacDefaultDiagTimer_mS_M_u32[1]	999	999	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	963	963	✔
ElecIntTimer_mS_M_u32[1]	7853	7853	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	2574	2574	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	51627	51627	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	20245	20245	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	50526	50526	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	6549	6549	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	25746	25746	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	7917	7917	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	9313	9313	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	17342	17342	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	60062	60062	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	58750	58750	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	1557905408	1557905408	✔
IgnTimeOff_Sec_M_u32	401984541	401984541	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	58	58	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2521153536	2521153536	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	16	16	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3004162048	3004162048	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	198	198	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3542745088	3542745088	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	162	162	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1049894912	1049894912	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1713831936	1713831936	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	242	242	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	391667712	391667712	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	245	245	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	347242496	347242496	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	5	5	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2386894848	2386894848	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	154	154	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2920857600	2920857600	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	144	144	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1247993856	1247993856	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	37	37	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2851930112	2851930112	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4133982208	4133982208	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	51.1464005	51.1464005	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	606.413025	606.413025	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	437.9151	437.9151	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	9313	9313	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	401984541	401984541	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-227.965607	-227.965607 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.311 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4119065344
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	35196
AASNodeAbsentTimer_mS_M_u32	914727680
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	16322
ANGLEVOLANTSigValidCount_Cnt_M_u16	36012
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	62781
AngleVolantMsgTimer_mS_M_u32	4119065344
AngleVolantValidCount_Cnt_M_u16	64029
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	4120929024
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2011226880
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	4067103488
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4083208960
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	29749
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3401421568
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	42607
CAVNodeAbsentTimer_mS_M_u32	160482048
CDD_SrlComVehSpd_Kph_G_f32	558.526611
CMM388NTCEnableTimer_mS_M_u32	2230452992
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1818149632
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	56356
CMMNodeAbsentTimer_mS_M_u32	152228608
CONSANGLECPKSigInvalidCount_Cnt_M_u16	53657
CONSANGLECPKSigValidCount_Cnt_M_u16	62994
CONSANGLECPK_Cnt_M_u16	25849
CONSANGLECPK_HwDeg_M_f32	-554.24353
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	25849
CPKVehicleSpeedMsgTimer_mS_M_u32	143586048
CPKVehicleSpeedValidCount_Cnt_M_u16	42582
CityParkInputConsistentCount_Cnt_M_u16	14929
CityParkInputInvalidCount_Cnt_M_u16	40295
CityParkInputMsgTimer_mS_M_u32	2521153536
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2209981184
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	55216

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	4130030336
ComputerRazGCTSigValidCount_Cnt_M_u16	33834
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	59699
DMDFCTCPKSigValidCount_Cnt_M_u16	60324
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	25308
DMDRELAXECPKSigValidCount_Cnt_M_u16	44870
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	2650
DateInvalidTimer_mS_M_u32	2011226880
DiagMuxOnAbsentTimer_mS_M_u32	21017344
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4083208960
ESPNTCEnableTimer_mS_M_u32	1044030208
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	51897
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	9
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	201
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3820458752
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	3166
EtatMTSigValidCount_Cnt_M_u16	15907
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	49843
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	26284
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20594
ISDAT4V2BSI552MsgTimer_mS_M_u32	2504446720
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	34451
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	15907
ISDATBSI3F2MsgTimer_mS_M_u32	136753920
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	63750
ISDATBSI412MsgLenValidCount_Cnt_M_u16	44707
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	3166
ISDATBSI412MsgTimer_mS_M_u32	3127505664
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	59224
ISDATBSI432MsgLenValidCount_Cnt_M_u16	38125
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	16324
ISDATDIRASentFltAcc_Cnt_M_u16	59720
ISDATDIRASentTimer_mS_M_u32	143586048
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	60511
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	64029
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	9510
ISDYN2CMMMsgTimer_mS_M_u32	3932988160
ISDYNAASChkSumInvalidCount_Cnt_M_u16	10390
ISDYNAASChkSumValidCount_Cnt_M_u16	54559
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	62480
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	26262
ISDYNAASMsgLenValidCount_Cnt_M_u16	26871
ISDYNAASMsgTimeValidCount_Cnt_M_u16	10390
ISDYNAASMsgTimer_mS_M_u32	1505624832
ISDYNABRChkSumInvalidCount_Cnt_M_u16	26143
ISDYNABRChkSumValidCount_Cnt_M_u16	55537
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	38665
ISDYNABRMsgCountValidCount_Cnt_M_u16	17362
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	7948
ISDYNABRMsgLenValidCount_Cnt_M_u16	33733
ISDYNABRMsgTimeValidCount_Cnt_M_u16	25849
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	25139
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	24905
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	15907
ISDYNCMM208MsgTimer_mS_M_u32	1085891328
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	25139
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	24905
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	29187

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2832696064
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	61567
ISDYNVOLChkSumValidCount_Cnt_M_u16	38264
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	10009
ISDYNVOLMsgCountValidCount_Cnt_M_u16	59914
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	46918
ISDYNVOLMsgLenValidCount_Cnt_M_u16	23583
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	56356
ISDYNVOLMsgTimer_mS_M_u32	1727480576
IgnOnTimer_mS_M_u32	3423306496
IgnTimeOff_Sec_M_u32	633837700
ManVehSpd_Kph_M_f32	384.483612
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	189
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	65
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2153034496
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	69
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2168328960
PrevISDATBSI412MsgDLCError_Cnt_M_u08	211
PrevISDATBSI412MsgRxTime_MSec_M_u32	1755693824
PrevISDATBSI432MsgDLCError_Cnt_M_u08	88
PrevISDATBSI432MsgRxTime_MSec_M_u32	1168024320
PrevISDATDIRAMsgTxTime_MSec_M_u32	3978937088
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	44
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3780399872
PrevISDYNAASMsgDLCError_Cnt_M_u08	193
PrevISDYNAASMsgRxTime_MSec_M_u32	3596436224
PrevISDYNABRMsgDLCError_Cnt_M_u08	78
PrevISDYNABRMsgRxTime_MSec_M_u32	1688437504
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	106
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3975561984
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	221
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1434821376
PrevISDYNVOLMsgDLCError_Cnt_M_u08	11
PrevISDYNVOLMsgRxTime_MSec_M_u32	4244030208
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1850733312
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	50.6932983
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	25212
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	42333
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	41609
VitesseVehicleBVRampValidCount_Cnt_M_u16	50474
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	36687
VitesseVehicleBVSigValidCount_Cnt_M_u16	23545
VitesseVehicleBV_Kph_M_f32	351.349701
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	29187
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	50372
VitesseVehiculeRoues_Kph_M_f32	91.5404968
k_AASNTCEnableTimeout_mS_u16	9028
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	25308
k_AASNodeTimeout_mS_u16	17501
k_ABSNodeTimeout_mS_u16	27404
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	599
k_ANGLEVOLANTSigValidThresh_Cnt_u16	16684
k_AngleVolantInvalidThresh_Cnt_u16	4615
k_AngleVolantValidThresh_Cnt_u16	40295
k_BSI552MsgTimeout_mS_u16	50527
k_BSINTCEnableTimeout_mS_u16	45040
k_BSINodeAbsentDiag_Cnt_str.Threshold	9836
k_BSINodeAbsentDiag_Cnt_str.PStep	39953
k_BSINodeAbsentDiag_Cnt_str.NStep	5883
k_BSINodeAbsentTimeout_mS_u16	22485
k_BSINodeTimeout_mS_u16	16324
k_BattOvHi_Volt_f32	9.03100014
k_BattOvLo_Volt_f32	28.5305004
k_BattUvHi_Volt_f32	26.281601
k_BattUvLo_Volt_f32	10.5142002
k_CAVNTCEnableTimeout_mS_u16	12773
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	6485
k_CAVNodeTimeout_mS_u16	65125
k_CMM388MsgTimeout_mS_u16	26748
k_CMM388NTCEnableTimeout_mS_u16	23112
k_CMMNTCEnableTimeout_mS_u16	23339
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	1168
k_CONSANGLECPKMax_HwDeg_f32	574.588989
k_CONSANGLECPKMin_HwDeg_f32	-463.855194
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	53507
k_CONSANGLECPKSigValidThresh_Cnt_u16	25540
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	8235
k_CPKVehicleSpeedValidThresh_Cnt_u16	14829
k_CityParkInputInvalidThresh_Cnt_u16	26733
k_CityParkInputValidThresh_Cnt_u16	14929
k_ComputerRazGCTSigValidThresh_Cnt_u16	2881
k_CptTemporelSigValidThresh_Cnt_u16	56174
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	65036
k_DMDFCTCPKSigValidThresh_Cnt_u16	41669
k_DMDFCTCPKValidCount_Cnt_u16	16541
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	9510
k_DMDRELAXECPKSigValidThresh_Cnt_u16	18391
k_DMDRelaxeConsistentThresh_Cnt_u16	62885
k_DateValidThresh_Cnt_u16	20594
k_DefaultVehSpd_Kph_f32	31.8185997
k_DiagMuxOnAbsentTimeout_mS_u16	51447
k_EMNodeTimeout_mS_u16	26426
k_ESPNTCEnableTimeout_mS_u16	15675
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	25592
k_EtatMTSigInvalidThresh_Cnt_u16	44634
k_EtatMTSigValidThresh_Cnt_u16	26476
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	10354
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	22679
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	54366
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	39924
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	40033
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	570
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	1081
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	18574
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	12940
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	51981
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	8011
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	4333
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	26859
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	41222
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	62781
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	63191
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	50463
k_ISDYNAASChkSumValidThresh_Cnt_u16	30705
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	30217
k_ISDYNAASMsgCountValidThresh_Cnt_u16	25298
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	595
k_ISDYNAASMsgLenValidThresh_Cnt_u16	15505
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	5780
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	9458
k_ISDYNABRChkSumValidThresh_Cnt_u16	18987
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	21301
k_ISDYNABRMsgCountValidThresh_Cnt_u16	24671
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	31524
k_ISDYNABRMsgLenValidThresh_Cnt_u16	43449
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	9338
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	31408
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	13651
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	22520
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	7874
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	43948
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	54271
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	42629
k_ISDYNVOLChkSumValidThresh_Cnt_u16	52578
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	37242
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	62501
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	11306
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	57071
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	38768
k_IgnOnTimeout_mS_u16	11601
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	177.780106
k_PowerCutVehSpdLowThresh_Kph_f32	210.881607
k_PowerCutVehSpdLowTimeout_mS_u16	15552
k_VBattMaxAAS_Volt_f32	0.355500013
k_VBattMaxBSI_Volt_f32	4.0632
k_VBattMaxCAV_Volt_f32	23.4400005
k_VBattMaxCMM388_Volt_f32	9.32240009
k_VBattMaxCMM_Volt_f32	5.00740004
k_VBattMaxESP_Volt_f32	12.5506001
k_VBattMinAAS_Volt_f32	23.5592995
k_VBattMinBSI_Volt_f32	12.5506001
k_VBattMinCAV_Volt_f32	7.90140009
k_VBattMinCMM388_Volt_f32	3.5927
k_VBattMinCMM_Volt_f32	17.9228001
k_VBattMinESP_Volt_f32	5.00740004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	52280
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	36613
k_VitesseVehicleBVRampValidThresh_Cnt_u16	34329
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	46200
k_VitesseVehicleBVSigValidThresh_Cnt_u16	54006
k_VitesseVehicleBVSpeedPassThresh_kph_f32	407.113586
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	1391
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	43152
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2011226880
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8816
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3873991680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	221
target_SrlComInput_Per1_Batt_Volt_f32.value	16.1949997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1257411328
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	24
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.443533421
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1204650752
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1106191104
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1914749696
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	6447872
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	347341568
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3608519424
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1871135488
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	46
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	48
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	68
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	137
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	161
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	188
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	159
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	357524224
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	93
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	167
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	187
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	22
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	206865152
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2281054976
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	23
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4188521216
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	37
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	85
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	130
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	156
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	174
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2997359360
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	389
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.654532373
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	503376
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	89.5615997
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	5422

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3873991680	3873991680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	9836	9836	✔
BSINodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
CDD_SrlComVehSpd_Kph_G_f32	384.483612	384.483612	✔
CMM388NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	25849	25849	✔
CONSANGLECPK_HwDeg_M_f32	-554.24353	-554.24353 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3873991680	3873991680	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3873991680	3873991680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3873991680	3873991680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3873991680	3873991680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3873991680	3873991680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3873991680	3873991680	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3873991680	3873991680	✔
ESPNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	8	8	✔
EffacDefaultDiagTimer_mS_M_u32[1]	9	9	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	20	20	✔
ElecIntTimer_mS_M_u32[1]	201	201	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3873991680	3873991680	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20594	20594	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	15907	15907	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	3166	3166	✔
ISDATBSI412MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	16324	16324	✔
ISDATBSI432MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	41895	41895	✔
ISDATDIRASentTimer_mS_M_u32	3873991680	3873991680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	9510	9510	✔
ISDYN2CMMMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	10390	10390	✔
ISDYNAASMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	25849	25849	✔
ISDYNABRMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	15907	15907	✔
ISDYNCMM208MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	29187	29187	✔
ISDYNCMM388MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	56356	56356	✔
ISDYNVOLMsgTimer_mS_M_u32	3873991680	3873991680	✔
IgnOnTimer_mS_M_u32	3423306496	3423306496	✔
IgnTimeOff_Sec_M_u32	633837700	633837700	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1204650752	1204650752	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	88	88	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1106191104	1106191104	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1914749696	1914749696	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	194	194	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	6447872	6447872	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3978937088	3978937088	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	245	245	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3608519424	3608519424	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	222	222	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1871135488	1871135488	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	159	159	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	357524224	357524224	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	22	22	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	206865152	206865152	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	229	229	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2281054976	2281054976	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	23	23	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4188521216	4188521216	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2997359360	2997359360	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	50.6932983	50.6932983	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	351.349701	351.349701	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	91.5404968	91.5404968	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	25849	25849	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	633837700	633837700	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-554.24353	-554.24353 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.312 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	379513344
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	56501
AASNodeAbsentTimer_mS_M_u32	3059341824
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	62433
ANGLEVOLANTSigValidCount_Cnt_M_u16	28134
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	56690
AngleVolantMsgTimer_mS_M_u32	379513344
AngleVolantValidCount_Cnt_M_u16	21843
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1409915392
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1866996224
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	610896384
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	680020480
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	57992
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	91359744
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	47708
CAVNodeAbsentTimer_mS_M_u32	3518528000
CDD_SrlComVehSpd_Kph_G_f32	89.4032974
CMM388NTCEnableTimer_mS_M_u32	1955904000
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1632532992
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	46846
CMMNodeAbsentTimer_mS_M_u32	796019200
CONSANGLECPKSigInvalidCount_Cnt_M_u16	2397
CONSANGLECPKSigValidCount_Cnt_M_u16	15538
CONSANGLECPK_Cnt_M_u16	19453
CONSANGLECPK_HwDeg_M_f32	612.379028
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	19453
CPKVehicleSpeedMsgTimer_mS_M_u32	3380472320
CPKVehicleSpeedValidCount_Cnt_M_u16	37999
CityParkInputConsistentCount_Cnt_M_u16	25783
CityParkInputInvalidCount_Cnt_M_u16	25716
CityParkInputMsgTimer_mS_M_u32	1204650752
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2663242240
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	49689

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2515073536
ComputerRazGCTSigValidCount_Cnt_M_u16	11052
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	45328
DMDFCTCPKSigValidCount_Cnt_M_u16	10877
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	29331
DMDRELAXECPKSigValidCount_Cnt_M_u16	60952
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	41754
DateInvalidTimer_mS_M_u32	1866996224
DiagMuxOnAbsentTimer_mS_M_u32	3597183488
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	680020480
ESPNTCEnableTimer_mS_M_u32	3006978560
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	64511
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	4
EffacDefaultDiagTimer_mS_M_u32[1]	5
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	89
ElecIntTimer_mS_M_u32[1]	899
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	579078656
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	57167
EtatMTSigValidCount_Cnt_M_u16	6848
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	7695
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	53988
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	46099
ISDAT4V2BSI552MsgTimer_mS_M_u32	1523993088
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	56369
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	65535
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	6848
ISDATBSI3F2MsgTimer_mS_M_u32	3652626944
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	25047
ISDATBSI412MsgLenValidCount_Cnt_M_u16	29120
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	57167
ISDATBSI412MsgTimer_mS_M_u32	3756845568
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	25954
ISDATBSI432MsgLenValidCount_Cnt_M_u16	28003
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	33373
ISDATDIRASentFltAcc_Cnt_M_u16	38353
ISDATDIRASentTimer_mS_M_u32	3380472320
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	52683
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	21843
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	35127
ISDYN2CMMMsgTimer_mS_M_u32	4137998848
ISDYNAASChkSumInvalidCount_Cnt_M_u16	59239
ISDYNAASChkSumValidCount_Cnt_M_u16	49803
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	62330
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	54759
ISDYNAASMsgLenValidCount_Cnt_M_u16	3971
ISDYNAASMsgTimeValidCount_Cnt_M_u16	59239
ISDYNAASMsgTimer_mS_M_u32	640727552
ISDYNABRChkSumInvalidCount_Cnt_M_u16	35915
ISDYNABRChkSumValidCount_Cnt_M_u16	13463
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	10254
ISDYNABRMsgCountValidCount_Cnt_M_u16	626
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	44292
ISDYNABRMsgLenValidCount_Cnt_M_u16	8089
ISDYNABRMsgTimeValidCount_Cnt_M_u16	19453
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	62207
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	19068
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	6848
ISDYNCMM208MsgTimer_mS_M_u32	381590016
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	62207
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	19068
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	1441

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2128886272
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	50347
ISDYNVOLChkSumValidCount_Cnt_M_u16	30336
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	3934
ISDYNVOLMsgCountValidCount_Cnt_M_u16	18251
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	43608
ISDYNVOLMsgLenValidCount_Cnt_M_u16	56460
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	46846
ISDYNVOLMsgTimer_mS_M_u32	1938094592
IgnOnTimer_mS_M_u32	3846715904
IgnTimeOff_Sec_M_u32	1951344830
ManVehSpd_Kph_M_f32	495.519012
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	190
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	43
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2838276608
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	85
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2213579264
PrevISDATBSI412MsgDLCError_Cnt_M_u08	150
PrevISDATBSI412MsgRxTime_MSec_M_u32	1215920640
PrevISDATBSI432MsgDLCError_Cnt_M_u08	52
PrevISDATBSI432MsgRxTime_MSec_M_u32	755948032
PrevISDATDIRAMsgTxTime_MSec_M_u32	3404560896
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	135
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2360199680
PrevISDYNAASMsgDLCError_Cnt_M_u08	221
PrevISDYNAASMsgRxTime_MSec_M_u32	1028848128
PrevISDYNABRMsgDLCError_Cnt_M_u08	166
PrevISDYNABRMsgRxTime_MSec_M_u32	2072001024
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	113
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2642934272
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	166
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1499060736
PrevISDYNVOLMsgDLCError_Cnt_M_u08	168
PrevISDYNVOLMsgRxTime_MSec_M_u32	260471296
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3694848512
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	510.456909
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	64053
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	29265
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	44558
VitesseVehicleBVRampValidCount_Cnt_M_u16	34538
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	31034
VitesseVehicleBVSigValidCount_Cnt_M_u16	29695
VitesseVehicleBV_Kph_M_f32	272.519196
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	1441
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	52765
VitesseVehiculeRoues_Kph_M_f32	66.1548004
k_AASNTCEnableTimeout_mS_u16	64796
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	55062
k_AASNodeTimeout_mS_u16	38225
k_ABSNodeTimeout_mS_u16	53125
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	53349
k_ANGLEVOLANTSigValidThresh_Cnt_u16	9382
k_AngleVolantInvalidThresh_Cnt_u16	56853
k_AngleVolantValidThresh_Cnt_u16	25716
k_BSI552MsgTimeout_mS_u16	63564
k_BSINTCEnableTimeout_mS_u16	27546
k_BSINodeAbsentDiag_Cnt_str.Threshold	32726
k_BSINodeAbsentDiag_Cnt_str.PStep	47652
k_BSINodeAbsentDiag_Cnt_str.NStep	62631
k_BSINodeAbsentTimeout_mS_u16	5546
k_BSINodeTimeout_mS_u16	33373
k_BattOvHi_Volt_f32	6.34849977
k_BattOvLo_Volt_f32	18.6583004
k_BattUvHi_Volt_f32	21.4375992
k_BattUvLo_Volt_f32	1.80379999
k_CAVNTCEnableTimeout_mS_u16	7930
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	31146
k_CAVNodeTimeout_mS_u16	45817
k_CMM388MsgTimeout_mS_u16	16309
k_CMM388NTCEnableTimeout_mS_u16	39505
k_CMMNTCEnableTimeout_mS_u16	48745
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	16057
k_CONSANGLECPKMax_HwDeg_f32	342.12149
k_CONSANGLECPKMin_HwDeg_f32	-538.882813
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	59553
k_CONSANGLECPKSigValidThresh_Cnt_u16	61725
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	47591
k_CPKVehicleSpeedValidThresh_Cnt_u16	64290
k_CityParkInputInvalidThresh_Cnt_u16	15713
k_CityParkInputValidThresh_Cnt_u16	25783
k_ComputerRazGCTSigValidThresh_Cnt_u16	34343
k_CptTemporelSigValidThresh_Cnt_u16	34399
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	4100
k_DMDFCTCPKSigValidThresh_Cnt_u16	49817
k_DMDFCTCPKValidCount_Cnt_u16	7504
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	35127
k_DMDRELAXECPKSigValidThresh_Cnt_u16	41444
k_DMDRelaxeConsistentThresh_Cnt_u16	20602
k_DateValidThresh_Cnt_u16	46099
k_DefaultVehSpd_Kph_f32	86.2110977
k_DiagMuxOnAbsentTimeout_mS_u16	38915
k_EMNodeTimeout_mS_u16	3194
k_ESPNTCEnableTimeout_mS_u16	9720
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	49281
k_EtatMTSigInvalidThresh_Cnt_u16	24474
k_EtatMTSigValidThresh_Cnt_u16	13606
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	32018
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	15714
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	2704
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	24590
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	53126
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	5691
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	53951
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	5760
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	21446
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	27073
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	7625
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	50977
k_ISDATDIRASentDiag_Cnt_str.Threshold	3472

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	32212
k_ISDATDIRASentDiag_Cnt_str.NStep	26715
k_ISDATDIRASentTimeout_mS_u16	46055
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	47830
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	56690
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	26916
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	28491
k_ISDYNAASChkSumValidThresh_Cnt_u16	22423
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	35598
k_ISDYNAASMsgCountValidThresh_Cnt_u16	42354
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	34735
k_ISDYNAASMsgLenValidThresh_Cnt_u16	31925
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	17518
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	45906
k_ISDYNABRChkSumValidThresh_Cnt_u16	58471
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	17800
k_ISDYNABRMsgCountValidThresh_Cnt_u16	32461
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	55806
k_ISDYNABRMsgLenValidThresh_Cnt_u16	24319
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	24188
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	33177
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	8432
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	34432
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	22241
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	4326
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	8364
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	5466
k_ISDYNVOLChkSumValidThresh_Cnt_u16	53635
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	60348
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	45819
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	45035
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	26716
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	22297
k_IgnOnTimeout_mS_u16	45302
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	160.826797
k_PowerCutVehSpdLowThresh_Kph_f32	37.5220985
k_PowerCutVehSpdLowTimeout_mS_u16	41128
k_VBattMaxAAS_Volt_f32	1.9842
k_VBattMaxBSI_Volt_f32	5.87890005
k_VBattMaxCAV_Volt_f32	2.56570005
k_VBattMaxCMM388_Volt_f32	22.8113003
k_VBattMaxCMM_Volt_f32	26.3139
k_VBattMaxESP_Volt_f32	32
k_VBattMinAAS_Volt_f32	23.2196999
k_VBattMinBSI_Volt_f32	32
k_VBattMinCAV_Volt_f32	1.84080005
k_VBattMinCMM388_Volt_f32	5.03450012
k_VBattMinCMM_Volt_f32	4.1644001
k_VBattMinESP_Volt_f32	26.3139
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	33088
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	10649
k_VitesseVehicleBVRampValidThresh_Cnt_u16	62046
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	6528
k_VitesseVehicleBVSigValidThresh_Cnt_u16	28360
k_VitesseVehicleBVSpeedPassThresh_kph_f32	649.400024
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	40284
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	62648
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1866996224
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	56852
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2274721536
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	166
target_SrlComInput_Per1_Batt_Volt_f32.value	10.9983997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2563967488
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	0
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.132538095
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	226
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4194449920
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	438131200
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	4
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3624434176
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3150158336
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1297005056
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	346675712
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2580871680
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	209
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1895602688
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	59
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	77
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	210
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	219
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	233
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2288859648
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	604527104
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	494107136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	71
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	397576704
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3826
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.734294176
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	821038
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	157.7323
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	10783

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2274721536	2274721536	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	32726	32726	✔
BSINodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
CDD_SrlComVehSpd_Kph_G_f32	495.519012	495.519012	✔
CMM388NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	19453	19453	✔
CONSANGLECPK_HwDeg_M_f32	612.379028	612.379028 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2274721536	2274721536	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2274721536	2274721536	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2274721536	2274721536	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2274721536	2274721536	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2274721536	2274721536	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2274721536	2274721536	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2274721536	2274721536	✔
ESPNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4	4	✔
EffacDefaultDiagTimer_mS_M_u32[1]	5	5	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	89	89	✔
ElecIntTimer_mS_M_u32[1]	899	899	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2274721536	2274721536	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	46099	46099	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	6848	6848	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	57167	57167	✔
ISDATBSI412MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	33373	33373	✔
ISDATBSI432MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDATDIRASentFltAcc_Cnt_M_u16	3472	3472	✔
ISDATDIRASentTimer_mS_M_u32	2274721536	2274721536	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	35127	35127	✔
ISDYN2CMMMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	59239	59239	✔
ISDYNAASMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	19453	19453	✔
ISDYNABRMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	6848	6848	✔
ISDYNCMM208MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	1441	1441	✔
ISDYNCMM388MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	46846	46846	✔
ISDYNVOLMsgTimer_mS_M_u32	2274721536	2274721536	✔
IgnOnTimer_mS_M_u32	3846715904	3846715904	✔
IgnTimeOff_Sec_M_u32	1951344830	1951344830	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	226	226	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4194449920	4194449920	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	438131200	438131200	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	4	4	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3624434176	3624434176	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	164	164	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3150158336	3150158336	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3404560896	3404560896	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	169	169	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	346675712	346675712	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	31	31	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2580871680	2580871680	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	2	2	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1895602688	1895602688	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	251	251	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2288859648	2288859648	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	123	123	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	604527104	604527104	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	494107136	494107136	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	397576704	397576704	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	510.456909	510.456909	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	272.519196	272.519196	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	66.1548004	66.1548004	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	19453	19453	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1951344830	1951344830	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	612.379028	612.379028 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	495.519012	495.519012	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.313 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4159309056
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	8102
AASNodeAbsentTimer_mS_M_u32	4034475264
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	11297
ANGLEVOLANTSigValidCount_Cnt_M_u16	39891
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	20847
AngleVolantMsgTimer_mS_M_u32	4159309056
AngleVolantValidCount_Cnt_M_u16	22092
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2255090944
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1320056064
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3238667520
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2678973696
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	48172
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3757090048
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	59698
CAVNodeAbsentTimer_mS_M_u32	3772601600
CDD_SrlComVehSpd_Kph_G_f32	429.219208
CMM388NTCEnableTimer_mS_M_u32	3108541696
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	169563392
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	6666
CMMNodeAbsentTimer_mS_M_u32	3002066176
CONSANGLECPKSigInvalidCount_Cnt_M_u16	35501
CONSANGLECPKSigValidCount_Cnt_M_u16	3696
CONSANGLECPK_Cnt_M_u16	52367
CONSANGLECPK_HwDeg_M_f32	-36.1673012
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	52367
CPKVehicleSpeedMsgTimer_mS_M_u32	458032384
CPKVehicleSpeedValidCount_Cnt_M_u16	60832
CityParkInputConsistentCount_Cnt_M_u16	47136
CityParkInputInvalidCount_Cnt_M_u16	15848
CityParkInputMsgTimer_mS_M_u32	4194449920
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3343725824
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	65402

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	4132164864
ComputerRazGCTSigValidCount_Cnt_M_u16	30913
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	51220
DMDFCTCPKSigValidCount_Cnt_M_u16	55695
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	63499
DMDRELAXECPKSigValidCount_Cnt_M_u16	25405
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	61814
DateInvalidTimer_mS_M_u32	1320056064
DiagMuxOnAbsentTimer_mS_M_u32	260883712
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2678973696
ESPNTCEnableTimer_mS_M_u32	3184932096
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	6345
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	6
EffacDefaultDiagTimer_mS_M_u32[1]	7
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	749
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1354409216
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	30230
EtatMTSigValidCount_Cnt_M_u16	20869
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	38039
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	37850
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	5325
ISDAT4V2BSI552MsgTimer_mS_M_u32	3234063616
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	15602
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	51627
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	20869
ISDATBSI3F2MsgTimer_mS_M_u32	3181561088
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	5375
ISDATBSI412MsgLenValidCount_Cnt_M_u16	21254
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	30230
ISDATBSI412MsgTimer_mS_M_u32	1409287424
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	40670
ISDATBSI432MsgLenValidCount_Cnt_M_u16	21661
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	54575
ISDATDIRASentFltAcc_Cnt_M_u16	27347
ISDATDIRASentTimer_mS_M_u32	458032384
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	65317
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	22092
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	39839
ISDYN2CMMMsgTimer_mS_M_u32	462959872
ISDYNAASChkSumInvalidCount_Cnt_M_u16	18320
ISDYNAASChkSumValidCount_Cnt_M_u16	5091
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	55255
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	33425
ISDYNAASMsgLenValidCount_Cnt_M_u16	4988
ISDYNAASMsgTimeValidCount_Cnt_M_u16	18320
ISDYNAASMsgTimer_mS_M_u32	343184640
ISDYNABRChkSumInvalidCount_Cnt_M_u16	16484
ISDYNABRChkSumValidCount_Cnt_M_u16	17727
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	57755
ISDYNABRMsgCountValidCount_Cnt_M_u16	45102
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	64440
ISDYNABRMsgLenValidCount_Cnt_M_u16	49595
ISDYNABRMsgTimeValidCount_Cnt_M_u16	52367
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	47992
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	46784
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	20869
ISDYNCMM208MsgTimer_mS_M_u32	1380644096
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	47992
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	46784
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	64866

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	945427712
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	4291
ISDYNVOLChkSumValidCount_Cnt_M_u16	6406
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	25898
ISDYNVOLMsgCountValidCount_Cnt_M_u16	15141
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	45502
ISDYNVOLMsgLenValidCount_Cnt_M_u16	47328
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	6666
ISDYNVOLMsgTimer_mS_M_u32	3447182592
IgnOnTimer_mS_M_u32	2502825216
IgnTimeOff_Sec_M_u32	2112244620
ManVehSpd_Kph_M_f32	215.251602
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	191
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	207
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2806039808
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	176
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2121606400
PrevISDATBSI412MsgDLCError_Cnt_M_u08	42
PrevISDATBSI412MsgRxTime_MSec_M_u32	3231339776
PrevISDATBSI432MsgDLCError_Cnt_M_u08	207
PrevISDATBSI432MsgRxTime_MSec_M_u32	2690266368
PrevISDATDIRAMsgTxTime_MSec_M_u32	155079936
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	94
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3913114880
PrevISDYNAASMsgDLCError_Cnt_M_u08	36
PrevISDYNAASMsgRxTime_MSec_M_u32	671995136
PrevISDYNABRMsgDLCError_Cnt_M_u08	120
PrevISDYNABRMsgRxTime_MSec_M_u32	2995131648
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	183
PrevISDYNCMM208MsgRxTime_MSec_M_u32	460248320
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	111
PrevISDYNCMM388MsgRxTime_MSec_M_u32	125383936
PrevISDYNVOLMsgDLCError_Cnt_M_u08	199
PrevISDYNVOLMsgRxTime_MSec_M_u32	3748877568
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	387319040
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	504.376404
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	52647
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	41746
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	22044
VitesseVehicleBVRampValidCount_Cnt_M_u16	2375
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	16406
VitesseVehicleBVSigValidCount_Cnt_M_u16	11656
VitesseVehicleBV_Kph_M_f32	538.77533
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	64866
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	25004
VitesseVehiculeRoues_Kph_M_f32	177.204193
k_AASNTCEnableTimeout_mS_u16	62770
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	40195
k_AASNodeTimeout_mS_u16	14866
k_ABSNodeTimeout_mS_u16	32949
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	10709
k_ANGLEVOLANTSigValidThresh_Cnt_u16	64212
k_AngleVolantInvalidThresh_Cnt_u16	19079
k_AngleVolantValidThresh_Cnt_u16	15848
k_BSI552MsgTimeout_mS_u16	24351
k_BSINTCEnableTimeout_mS_u16	27702
k_BSINodeAbsentDiag_Cnt_str.Threshold	34932
k_BSINodeAbsentDiag_Cnt_str.PStep	1992
k_BSINodeAbsentDiag_Cnt_str.NStep	22144
k_BSINodeAbsentTimeout_mS_u16	35015
k_BSINodeTimeout_mS_u16	54575
k_BattOvHi_Volt_f32	14.8542995
k_BattOvLo_Volt_f32	25.5004997
k_BattUvHi_Volt_f32	29.0643997
k_BattUvLo_Volt_f32	28.7742004
k_CAVNTCEnableTimeout_mS_u16	42582
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	25416
k_CAVNodeTimeout_mS_u16	64985
k_CMM388MsgTimeout_mS_u16	63142
k_CMM388NTCEnableTimeout_mS_u16	22226
k_CMMNTCEnableTimeout_mS_u16	30282
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	32728
k_CONSANGLECPKMax_HwDeg_f32	687.492615
k_CONSANGLECPKMin_HwDeg_f32	-284.483887
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	21602
k_CONSANGLECPKSigValidThresh_Cnt_u16	63660
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	42064
k_CPKVehicleSpeedValidThresh_Cnt_u16	13598
k_CityParkInputInvalidThresh_Cnt_u16	1314
k_CityParkInputValidThresh_Cnt_u16	47136
k_ComputerRazGCTSigValidThresh_Cnt_u16	38672
k_CptTemporelSigValidThresh_Cnt_u16	17447
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	53944
k_DMDFCTCPKSigValidThresh_Cnt_u16	55483
k_DMDFCTCPKValidCount_Cnt_u16	11220
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	39839
k_DMDRELAXECPKSigValidThresh_Cnt_u16	53082
k_DMDRelaxeConsistentThresh_Cnt_u16	39832
k_DateValidThresh_Cnt_u16	5325
k_DefaultVehSpd_Kph_f32	253.643097
k_DiagMuxOnAbsentTimeout_mS_u16	32893
k_EMNodeTimeout_mS_u16	13654
k_ESPNTCEnableTimeout_mS_u16	5726
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	6784
k_EtatMTSigInvalidThresh_Cnt_u16	49783
k_EtatMTSigValidThresh_Cnt_u16	16274
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	50895
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	37790
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	27285
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	25947
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	50354
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	34771
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	2759
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	3398
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	25522
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	33603
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	21738
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	56865
k_ISDATDIRASentDiag_Cnt_str.Threshold	2435

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	9638
k_ISDATDIRASentDiag_Cnt_str.NStep	54621
k_ISDATDIRASentTimeout_mS_u16	14736
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	5890
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	20847
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	64730
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	38756
k_ISDYNAASChkSumValidThresh_Cnt_u16	56383
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	47259
k_ISDYNAASMsgCountValidThresh_Cnt_u16	50990
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	56888
k_ISDYNAASMsgLenValidThresh_Cnt_u16	5094
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	47996
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	41166
k_ISDYNABRChkSumValidThresh_Cnt_u16	11089
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	37676
k_ISDYNABRMsgCountValidThresh_Cnt_u16	50462
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	45322
k_ISDYNABRMsgLenValidThresh_Cnt_u16	61385
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	41489
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	51067
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	31668
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	57989
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	801
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	45779
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	59712
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	50806
k_ISDYNVOLChkSumValidThresh_Cnt_u16	65469
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	32146
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	23059
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	29762
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	55473
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	50107
k_IgnOnTimeout_mS_u16	25506
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	28.2959995
k_PowerCutVehSpdLowThresh_Kph_f32	214.210007
k_PowerCutVehSpdLowTimeout_mS_u16	14990
k_VBattMaxAAS_Volt_f32	22.1844997
k_VBattMaxBSI_Volt_f32	31.4477005
k_VBattMaxCAV_Volt_f32	8.93540001
k_VBattMaxCMM388_Volt_f32	14.5207005
k_VBattMaxCMM_Volt_f32	32
k_VBattMaxESP_Volt_f32	27.7194996
k_VBattMinAAS_Volt_f32	15.9379997
k_VBattMinBSI_Volt_f32	27.7194996
k_VBattMinCAV_Volt_f32	21.1324997
k_VBattMinCMM388_Volt_f32	7.74840021
k_VBattMinCMM_Volt_f32	15.9984999
k_VBattMinESP_Volt_f32	32
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	60356
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	8314
k_VitesseVehicleBVRampValidThresh_Cnt_u16	48170
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	12294
k_VitesseVehicleBVSigValidThresh_Cnt_u16	7661
k_VitesseVehicleBVSpeedPassThresh_kph_f32	400.975189
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	16434
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	30685
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1320056064
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	42709
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1704609280
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	111
target_SrlComInput_Per1_Batt_Volt_f32.value	16.4143009
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3922568448
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	68
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.425680727
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	82
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3204453632
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	858699008
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	149
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	233657600
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3074159872
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2535101696
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	361313536
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2592593152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	37
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	63
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	86
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	93
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	164
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	116
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3146839296
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	155
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	156
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	116
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2143229184
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2171450624
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2846643456
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	74
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	122
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	133
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1261380864
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3655
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.400590271
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	776825
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	72.8293991
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	26089

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1704609280	1704609280	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	34932	34932	✔
BSINodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
CDD_SrlComVehSpd_Kph_G_f32	215.251602	215.251602	✔
CMM388NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	52367	52367	✔
CONSANGLECPK_HwDeg_M_f32	-36.1673012	-36.1673012 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1704609280	1704609280	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1704609280	1704609280	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1704609280	1704609280	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1704609280	1704609280	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1704609280	1704609280	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1704609280	1704609280	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1704609280	1704609280	✔
ESPNTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	6	6	✔
EffacDefaultDiagTimer_mS_M_u32[1]	7	7	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4	4	✔
ElecIntTimer_mS_M_u32[1]	749	749	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1704609280	1704609280	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	5325	5325	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	20869	20869	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	30230	30230	✔
ISDATBSI412MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	54575	54575	✔
ISDATBSI432MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDATDIRASentFltAcc_Cnt_M_u16	2435	2435	✔
ISDATDIRASentTimer_mS_M_u32	1704609280	1704609280	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	39839	39839	✔
ISDYN2CMMMsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	18320	18320	✔
ISDYNAASMsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	52367	52367	✔
ISDYNABRMsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	20869	20869	✔
ISDYNCMM208MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	64866	64866	✔
ISDYNCMM388MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	6666	6666	✔
ISDYNVOLMsgTimer_mS_M_u32	1704609280	1704609280	✔
IgnOnTimer_mS_M_u32	2502825216	2502825216	✔
IgnTimeOff_Sec_M_u32	2112244620	2112244620	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	82	82	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3204453632	3204453632	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	90	90	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	858699008	858699008	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	149	149	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	233657600	233657600	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	106	106	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3074159872	3074159872	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	155079936	155079936	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	131	131	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	361313536	361313536	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	152	152	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2592593152	2592593152	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	116	116	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3146839296	3146839296	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	116	116	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2143229184	2143229184	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2171450624	2171450624	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	210	210	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2846643456	2846643456	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1261380864	1261380864	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	504.376404	504.376404	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	538.77533	538.77533	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	177.204193	177.204193	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	52367	52367	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2112244620	2112244620	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-36.1673012	-36.1673012 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.314 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4130649088
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	4351
AASNodeAbsentTimer_mS_M_u32	2236032000
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	62863
ANGLEVOLANTSigValidCount_Cnt_M_u16	3383
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	57252
AngleVolantMsgTimer_mS_M_u32	4130649088
AngleVolantValidCount_Cnt_M_u16	35726
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1987372032
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3483853824
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3277083648
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1718162432
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	12654
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	547410944
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	36058
CAVNodeAbsentTimer_mS_M_u32	3969565696
CDD_SrlComVehSpd_Kph_G_f32	274.222107
CMM388NTCEnableTimer_mS_M_u32	542704640
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3907044352
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	34323
CMMNodeAbsentTimer_mS_M_u32	3030586368
CONSANGLECPKSigInvalidCount_Cnt_M_u16	64745
CONSANGLECPKSigValidCount_Cnt_M_u16	6241
CONSANGLECPK_Cnt_M_u16	6660
CONSANGLECPK_HwDeg_M_f32	282.445496
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	6660
CPKVehicleSpeedMsgTimer_mS_M_u32	3624645632
CPKVehicleSpeedValidCount_Cnt_M_u16	26522
CityParkInputConsistentCount_Cnt_M_u16	46610
CityParkInputInvalidCount_Cnt_M_u16	38329
CityParkInputMsgTimer_mS_M_u32	3204453632
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1355490304
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	49539

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2253341696
ComputerRazGCTSigValidCount_Cnt_M_u16	14383
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	42805
DMDFCTCPKSigValidCount_Cnt_M_u16	63877
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	47569
DMDRELAXECPKSigValidCount_Cnt_M_u16	57081
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	11406
DateInvalidTimer_mS_M_u32	3483853824
DiagMuxOnAbsentTimer_mS_M_u32	2857137152
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1718162432
ESPNTCEnableTimer_mS_M_u32	3509593088
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	8342
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	9
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	45
ElecIntTimer_mS_M_u32[1]	99
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1984091136
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	62190
EtatMTSigValidCount_Cnt_M_u16	46946
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1835
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	45091
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	49099
ISDAT4V2BSI552MsgTimer_mS_M_u32	3676771328
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	17622
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	46946
ISDATBSI3F2MsgTimer_mS_M_u32	2013950976
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	41650
ISDATBSI412MsgLenValidCount_Cnt_M_u16	40798
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	62190
ISDATBSI412MsgTimer_mS_M_u32	3119690752
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	18327
ISDATBSI432MsgLenValidCount_Cnt_M_u16	48410
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	64739
ISDATDIRASentFltAcc_Cnt_M_u16	52215
ISDATDIRASentTimer_mS_M_u32	3624645632
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	23106
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	35726
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	6292
ISDYN2CMMMsgTimer_mS_M_u32	1072309248
ISDYNAASChkSumInvalidCount_Cnt_M_u16	49473
ISDYNAASChkSumValidCount_Cnt_M_u16	17161
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	62189
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	64701
ISDYNAASMsgLenValidCount_Cnt_M_u16	37053
ISDYNAASMsgTimeValidCount_Cnt_M_u16	49473
ISDYNAASMsgTimer_mS_M_u32	3201631232
ISDYNABRChkSumInvalidCount_Cnt_M_u16	8260
ISDYNABRChkSumValidCount_Cnt_M_u16	6260
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	57120
ISDYNABRMsgCountValidCount_Cnt_M_u16	23080
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	38344
ISDYNABRMsgLenValidCount_Cnt_M_u16	60032
ISDYNABRMsgTimeValidCount_Cnt_M_u16	6660
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	24952
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	27233
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	46946
ISDYNCMM208MsgTimer_mS_M_u32	3604079616
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	24952
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	27233
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	28236

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3374613504
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	17063
ISDYNVOLChkSumValidCount_Cnt_M_u16	53407
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	42995
ISDYNVOLMsgCountValidCount_Cnt_M_u16	44227
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	27063
ISDYNVOLMsgLenValidCount_Cnt_M_u16	31503
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	34323
ISDYNVOLMsgTimer_mS_M_u32	2966111232
IgnOnTimer_mS_M_u32	44598272
IgnTimeOff_Sec_M_u32	238186707
ManVehSpd_Kph_M_f32	528.345886
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	192
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	44
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3006297088
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	108
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4145239040
PrevISDATBSI412MsgDLCError_Cnt_M_u08	70
PrevISDATBSI412MsgRxTime_MSec_M_u32	2170799104
PrevISDATBSI432MsgDLCError_Cnt_M_u08	223
PrevISDATBSI432MsgRxTime_MSec_M_u32	967058432
PrevISDATDIRAMsgTxTime_MSec_M_u32	930595840
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	148
PrevISDYN2CMMMsgRxTime_MSec_M_u32	666539008
PrevISDYNAASMsgDLCError_Cnt_M_u08	238
PrevISDYNAASMsgRxTime_MSec_M_u32	2030650368
PrevISDYNABRMsgDLCError_Cnt_M_u08	223
PrevISDYNABRMsgRxTime_MSec_M_u32	178291712
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	67
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1659257856
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	19
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1078404096
PrevISDYNVOLMsgDLCError_Cnt_M_u08	252
PrevISDYNVOLMsgRxTime_MSec_M_u32	3369649152
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1219539968
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	628.175598
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	62331
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	47611
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	28188
VitesseVehicleBVRampValidCount_Cnt_M_u16	39772
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	52656
VitesseVehicleBVSigValidCount_Cnt_M_u16	27672
VitesseVehicleBV_Kph_M_f32	594.202393
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	28236
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	2092
VitesseVehiculeRoues_Kph_M_f32	26.5284996
k_AASNTCEnableTimeout_mS_u16	60443
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	21353
k_AASNodeTimeout_mS_u16	62715
k_ABSNodeTimeout_mS_u16	16722
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	17074
k_ANGLEVOLANTSigValidThresh_Cnt_u16	26229
k_AngleVolantInvalidThresh_Cnt_u16	860
k_AngleVolantValidThresh_Cnt_u16	38329
k_BSI552MsgTimeout_mS_u16	39891
k_BSINTCEnableTimeout_mS_u16	16271
k_BSINodeAbsentDiag_Cnt_str.Threshold	40966
k_BSINodeAbsentDiag_Cnt_str.PStep	38729
k_BSINodeAbsentDiag_Cnt_str.NStep	45152
k_BSINodeAbsentTimeout_mS_u16	39324
k_BSINodeTimeout_mS_u16	64739
k_BattOvHi_Volt_f32	2.18099999
k_BattOvLo_Volt_f32	22.5153999
k_BattUvHi_Volt_f32	8.61800003
k_BattUvLo_Volt_f32	24.5645008
k_CAVNTCEnableTimeout_mS_u16	37999
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	63128
k_CAVNodeTimeout_mS_u16	21349
k_CMM388MsgTimeout_mS_u16	35839
k_CMM388NTCEnableTimeout_mS_u16	7035
k_CMMNTCEnableTimeout_mS_u16	6610
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	23976
k_CONSANGLECPKMax_HwDeg_f32	268.161285
k_CONSANGLECPKMin_HwDeg_f32	-12.9413004
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	26956
k_CONSANGLECPKSigValidThresh_Cnt_u16	17196
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	11841
k_CPKVehicleSpeedValidThresh_Cnt_u16	32341
k_CityParkInputInvalidThresh_Cnt_u16	18954
k_CityParkInputValidThresh_Cnt_u16	46610
k_ComputerRazGCTSigValidThresh_Cnt_u16	20352
k_CptTemporelSigValidThresh_Cnt_u16	16124
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	4296
k_DMDFCTCPKSigValidThresh_Cnt_u16	42368
k_DMDFCTCPKValidCount_Cnt_u16	33398
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	6292
k_DMDRELAXECPKSigValidThresh_Cnt_u16	1060
k_DMDRelaxeConsistentThresh_Cnt_u16	5994
k_DateValidThresh_Cnt_u16	49099
k_DefaultVehSpd_Kph_f32	151.518906
k_DiagMuxOnAbsentTimeout_mS_u16	13882
k_EMNodeTimeout_mS_u16	57582
k_ESPNTCEnableTimeout_mS_u16	46422
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	11696
k_EtatMTSigInvalidThresh_Cnt_u16	42507
k_EtatMTSigValidThresh_Cnt_u16	13691
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	33476
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	62232
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	45747
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	53407
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	43355
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	39478
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	59356
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	30495
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	18715
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	50664
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	34740
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	23631
k_ISDATDIRASentDiag_Cnt_str.Threshold	50189

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	7148
k_ISDATDIRASentDiag_Cnt_str.NStep	24623
k_ISDATDIRASentTimeout_mS_u16	58560
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	30124
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	57252
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	61922
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	6980
k_ISDYNAASChkSumValidThresh_Cnt_u16	21364
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	23072
k_ISDYNAASMsgCountValidThresh_Cnt_u16	5416
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	38600
k_ISDYNAASMsgLenValidThresh_Cnt_u16	46975
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	50301
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	32390
k_ISDYNABRChkSumValidThresh_Cnt_u16	34238
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	44142
k_ISDYNABRMsgCountValidThresh_Cnt_u16	32086
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	49427
k_ISDYNABRMsgLenValidThresh_Cnt_u16	39830
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	29309
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	22015
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	33427
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	34722
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	28815
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	51255
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	62385
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	10829
k_ISDYNVOLChkSumValidThresh_Cnt_u16	13625
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	22075
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	10744
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	43114
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	53726
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	60161
k_IgnOnTimeout_mS_u16	713
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	64.0604019
k_PowerCutVehSpdLowThresh_Kph_f32	58.3181992
k_PowerCutVehSpdLowTimeout_mS_u16	35847
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	8.13059998
k_VBattMaxCAV_Volt_f32	8.02420044
k_VBattMaxCMM388_Volt_f32	23.3013992
k_VBattMaxCMM_Volt_f32	16.8617992
k_VBattMaxESP_Volt_f32	23.9880009
k_VBattMinAAS_Volt_f32	11.1218004
k_VBattMinBSI_Volt_f32	23.9880009
k_VBattMinCAV_Volt_f32	7.36549997
k_VBattMinCMM388_Volt_f32	25.9258003
k_VBattMinCMM_Volt_f32	17.2565994
k_VBattMinESP_Volt_f32	16.8617992
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	32614
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	22530
k_VitesseVehicleBVRampValidThresh_Cnt_u16	41715
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	35743
k_VitesseVehicleBVSigValidThresh_Cnt_u16	63659
k_VitesseVehicleBVSpeedPassThresh_kph_f32	654.435425
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	34778
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	10138
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3483853824
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	2445
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3144151296
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	19
target_SrlComInput_Per1_Batt_Volt_f32.value	12.6883001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3070874624
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	240
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.430075735
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1295156224
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	243
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1931912192
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	230
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2775237632
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2885608448
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1323500544
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1444357120
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2308654080
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	102
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	153
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	223
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	191
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	855630848
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	47
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	85
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	109
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	180
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	189
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	189
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	207
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	254
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3337978880
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1147773952
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2385363968
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	107
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	122
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	202
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4175778816
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2592
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.837311327
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	148335
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	80.7099991
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	45749

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3144151296	3144151296	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	40966	40966	✔
BSINodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
CDD_SrlComVehSpd_Kph_G_f32	528.345886	528.345886	✔
CMM388NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	6660	6660	✔
CONSANGLECPK_HwDeg_M_f32	282.445496	282.445496 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3144151296	3144151296	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3144151296	3144151296	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3144151296	3144151296	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3144151296	3144151296	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3144151296	3144151296	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3144151296	3144151296	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3144151296	3144151296	✔
ESPNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	8	8	✔
EffacDefaultDiagTimer_mS_M_u32[1]	9	9	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	45	45	✔
ElecIntTimer_mS_M_u32[1]	99	99	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3144151296	3144151296	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	49099	49099	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	46946	46946	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	62190	62190	✔
ISDATBSI412MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	64739	64739	✔
ISDATBSI432MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATDIRASentFltAcc_Cnt_M_u16	50189	50189	✔
ISDATDIRASentTimer_mS_M_u32	3144151296	3144151296	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	6292	6292	✔
ISDYN2CMMMsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	49473	49473	✔
ISDYNAASMsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	6660	6660	✔
ISDYNABRMsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	46946	46946	✔
ISDYNCMM208MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	28236	28236	✔
ISDYNCMM388MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	34323	34323	✔
ISDYNVOLMsgTimer_mS_M_u32	3144151296	3144151296	✔
IgnOnTimer_mS_M_u32	44598272	44598272	✔
IgnTimeOff_Sec_M_u32	238186707	238186707	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	168	168	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1295156224	1295156224	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	243	243	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1931912192	1931912192	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	230	230	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2775237632	2775237632	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	73	73	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2885608448	2885608448	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	930595840	930595840	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	129	129	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1444357120	1444357120	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	229	229	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2308654080	2308654080	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	191	191	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	855630848	855630848	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	254	254	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3337978880	3337978880	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	64	64	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1147773952	1147773952	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	235	235	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2385363968	2385363968	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4175778816	4175778816	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	628.175598	628.175598	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	594.202393	594.202393	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	26.5284996	26.5284996	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	6660	6660	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	238186707	238186707	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	282.445496	282.445496 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	528.345886	528.345886	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.315 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3302008576
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	48753
AASNodeAbsentTimer_mS_M_u32	2908313344
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	62143
ANGLEVOLANTSigValidCount_Cnt_M_u16	30599
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	9858
AngleVolantMsgTimer_mS_M_u32	3302008576
AngleVolantValidCount_Cnt_M_u16	62275
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3234862848
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2671286016
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3824273152
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1035175680
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	31522
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2651604736
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	49502
CAVNodeAbsentTimer_mS_M_u32	3453908736
CDD_SrlComVehSpd_Kph_G_f32	566.114929
CMM388NTCEnableTimer_mS_M_u32	4221810432
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1896642304
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	12917
CMMNodeAbsentTimer_mS_M_u32	3137701632
CONSANGLECPKSigInvalidCount_Cnt_M_u16	29618
CONSANGLECPKSigValidCount_Cnt_M_u16	11530
CONSANGLECPK_Cnt_M_u16	29729
CONSANGLECPK_HwDeg_M_f32	597.872986
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	29729
CPKVehicleSpeedMsgTimer_mS_M_u32	994813696
CPKVehicleSpeedValidCount_Cnt_M_u16	39174
CityParkInputConsistentCount_Cnt_M_u16	33719
CityParkInputInvalidCount_Cnt_M_u16	37314
CityParkInputMsgTimer_mS_M_u32	1295156224
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1523406592
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	48357

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1925248768
ComputerRazGCTSigValidCount_Cnt_M_u16	45408
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	19790
DMDFCTCPKSigValidCount_Cnt_M_u16	49694
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	11769
DMDRELAXECPKSigValidCount_Cnt_M_u16	35393
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	47299
DateInvalidTimer_mS_M_u32	2671286016
DiagMuxOnAbsentTimer_mS_M_u32	3079235328
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1035175680
ESPNTCEnableTimer_mS_M_u32	2912835328
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	40617
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	11
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	66
ElecIntTimer_mS_M_u32[1]	79
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2770749184
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	26851
EtatMTSigValidCount_Cnt_M_u16	5960
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	56556
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	60868
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	1868
ISDAT4V2BSI552MsgTimer_mS_M_u32	1467582208
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	65535
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	14443
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	5960
ISDATBSI3F2MsgTimer_mS_M_u32	3327092480
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	46102
ISDATBSI412MsgLenValidCount_Cnt_M_u16	39378
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	26851
ISDATBSI412MsgTimer_mS_M_u32	4053182208
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	65001
ISDATBSI432MsgLenValidCount_Cnt_M_u16	55581
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	54595
ISDATDIRASentFltAcc_Cnt_M_u16	47111
ISDATDIRASentTimer_mS_M_u32	994813696
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	11111
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	62275
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	13617
ISDYN2CMMMsgTimer_mS_M_u32	3379582720
ISDYNAASChkSumInvalidCount_Cnt_M_u16	13739
ISDYNAASChkSumValidCount_Cnt_M_u16	64531
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	63782
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	48565
ISDYNAASMsgLenValidCount_Cnt_M_u16	11637
ISDYNAASMsgTimeValidCount_Cnt_M_u16	13739
ISDYNAASMsgTimer_mS_M_u32	271562496
ISDYNABRChkSumInvalidCount_Cnt_M_u16	15394
ISDYNABRChkSumValidCount_Cnt_M_u16	16210
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	6158
ISDYNABRMsgCountValidCount_Cnt_M_u16	62134
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	58645
ISDYNABRMsgLenValidCount_Cnt_M_u16	62125
ISDYNABRMsgTimeValidCount_Cnt_M_u16	29729
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	8501
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	5690
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	5960
ISDYNCMM208MsgTimer_mS_M_u32	1404638976
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	8501
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	5690
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	49929

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2403415808
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	6776
ISDYNVOLChkSumValidCount_Cnt_M_u16	31824
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	49940
ISDYNVOLMsgCountValidCount_Cnt_M_u16	8292
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	34630
ISDYNVOLMsgLenValidCount_Cnt_M_u16	57087
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	12917
ISDYNVOLMsgTimer_mS_M_u32	3813472000
IgnOnTimer_mS_M_u32	4071962368
IgnTimeOff_Sec_M_u32	2668809073
ManVehSpd_Kph_M_f32	310.740509
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	193
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	236
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	752707328
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	130
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	78956288
PrevISDATBSI412MsgDLCError_Cnt_M_u08	28
PrevISDATBSI412MsgRxTime_MSec_M_u32	1937995520
PrevISDATBSI432MsgDLCError_Cnt_M_u08	186
PrevISDATBSI432MsgRxTime_MSec_M_u32	1145198336
PrevISDATDIRAMsgTxTime_MSec_M_u32	2705815296
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	119
PrevISDYN2CMMMsgRxTime_MSec_M_u32	532612864
PrevISDYNAASMsgDLCError_Cnt_M_u08	96
PrevISDYNAASMsgRxTime_MSec_M_u32	43185920
PrevISDYNABRMsgDLCError_Cnt_M_u08	196
PrevISDYNABRMsgRxTime_MSec_M_u32	3134011136
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	55
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4177262336
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	218
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2086229760
PrevISDYNVOLMsgDLCError_Cnt_M_u08	86
PrevISDYNVOLMsgRxTime_MSec_M_u32	2971956992
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3176965888
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	391.338989
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	20859
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	10683
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	42392
VitesseVehicleBVRampValidCount_Cnt_M_u16	18840
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	11868
VitesseVehicleBVSigValidCount_Cnt_M_u16	7908
VitesseVehicleBV_Kph_M_f32	285.588593
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	49929
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	41257
VitesseVehiculeRoues_Kph_M_f32	382.371796
k_AASNTCEnableTimeout_mS_u16	6620
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	51122
k_AASNodeTimeout_mS_u16	30907
k_ABSNodeTimeout_mS_u16	13047
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	14488
k_ANGLEVOLANTSigValidThresh_Cnt_u16	2316
k_AngleVolantInvalidThresh_Cnt_u16	36439
k_AngleVolantValidThresh_Cnt_u16	37314
k_BSI552MsgTimeout_mS_u16	16948
k_BSINTCEnableTimeout_mS_u16	62977
k_BSINodeAbsentDiag_Cnt_str.Threshold	29963
k_BSINodeAbsentDiag_Cnt_str.PStep	12162
k_BSINodeAbsentDiag_Cnt_str.NStep	54397
k_BSINodeAbsentTimeout_mS_u16	55450
k_BSINodeTimeout_mS_u16	54595
k_BattOvHi_Volt_f32	24.0123005
k_BattOvLo_Volt_f32	1.19029999
k_BattUvHi_Volt_f32	19.9993
k_BattUvLo_Volt_f32	24.4328003
k_CAVNTCEnableTimeout_mS_u16	60832
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	64548
k_CAVNodeTimeout_mS_u16	24638
k_CMM388MsgTimeout_mS_u16	19825
k_CMM388NTCEnableTimeout_mS_u16	36605
k_CMMNTCEnableTimeout_mS_u16	32182
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	37045
k_CONSANGLECPKMax_HwDeg_f32	212.746094
k_CONSANGLECPKMin_HwDeg_f32	-270.849213
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	53769
k_CONSANGLECPKSigValidThresh_Cnt_u16	61481
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	25833
k_CPKVehicleSpeedValidThresh_Cnt_u16	27949
k_CityParkInputInvalidThresh_Cnt_u16	22224
k_CityParkInputValidThresh_Cnt_u16	33719
k_ComputerRazGCTSigValidThresh_Cnt_u16	5292
k_CptTemporelSigValidThresh_Cnt_u16	25081
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	29717
k_DMDFCTCPKSigValidThresh_Cnt_u16	49581
k_DMDFCTCPKValidCount_Cnt_u16	43018
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	13617
k_DMDRELAXECPKSigValidThresh_Cnt_u16	56897
k_DMDRelaxeConsistentThresh_Cnt_u16	15471
k_DateValidThresh_Cnt_u16	1868
k_DefaultVehSpd_Kph_f32	201.376099
k_DiagMuxOnAbsentTimeout_mS_u16	30591
k_EMNodeTimeout_mS_u16	7075
k_ESPNTCEnableTimeout_mS_u16	14314
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	16541
k_EtatMTSigInvalidThresh_Cnt_u16	34509
k_EtatMTSigValidThresh_Cnt_u16	50237
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	13152
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	24100
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	20948
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	52559
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	24284
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	56714
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	28954
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	65294
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	2397
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	117
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	5841
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	18497
k_ISDATDIRASentDiag_Cnt_str.Threshold	13378

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	37990
k_ISDATDIRASentDiag_Cnt_str.NStep	48989
k_ISDATDIRASentTimeout_mS_u16	57006
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	45098
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	9858
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	45638
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	19234
k_ISDYNAASChkSumValidThresh_Cnt_u16	36434
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	42766
k_ISDYNAASMsgCountValidThresh_Cnt_u16	49590
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	59542
k_ISDYNAASMsgLenValidThresh_Cnt_u16	16687
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	3828
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	41691
k_ISDYNABRChkSumValidThresh_Cnt_u16	39155
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	2594
k_ISDYNABRMsgCountValidThresh_Cnt_u16	25386
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	33141
k_ISDYNABRMsgLenValidThresh_Cnt_u16	11689
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	57269
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	14831
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	55411
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	7366
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	33215
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	18055
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	22490
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	18757
k_ISDYNVOLChkSumValidThresh_Cnt_u16	1089
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	53690
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	6854
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	14447
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	47060
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	56746
k_IgnOnTimeout_mS_u16	45009
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	194.251602
k_PowerCutVehSpdLowThresh_Kph_f32	91.4781036
k_PowerCutVehSpdLowTimeout_mS_u16	59928
k_VBattMaxAAS_Volt_f32	8.18190002
k_VBattMaxBSI_Volt_f32	6.6013999
k_VBattMaxCAV_Volt_f32	11.8514004
k_VBattMaxCMM388_Volt_f32	1.92019999
k_VBattMaxCMM_Volt_f32	12.1831999
k_VBattMaxESP_Volt_f32	11.0106001
k_VBattMinAAS_Volt_f32	29.2420998
k_VBattMinBSI_Volt_f32	11.0106001
k_VBattMinCAV_Volt_f32	5.02960014
k_VBattMinCMM388_Volt_f32	14.1240997
k_VBattMinCMM_Volt_f32	24.8885994
k_VBattMinESP_Volt_f32	12.1831999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	64252
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	3304
k_VitesseVehicleBVRampValidThresh_Cnt_u16	53780
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	19280
k_VitesseVehicleBVSigValidThresh_Cnt_u16	24556
k_VitesseVehicleBVSpeedPassThresh_kph_f32	508.051392
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	53342
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	7390
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2671286016
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	39539
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1516957696
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	218
target_SrlComInput_Per1_Batt_Volt_f32.value	8.30179977
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3201386240
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	55
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.922583044
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	101
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3138860800
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3250247424
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	156
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3815667456
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3358725888
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	403027712
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2062112512
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	128
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2564617984
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	123
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	214
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1999574784
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	7
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	30
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	56
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	239
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	47
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	432944896
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	435279616
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	89
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4112873216
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	197
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	204
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3342780160
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3948
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.966752052
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	351926
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	205.552597
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	31693

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1516957696	1516957696	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	29963	29963	✔
BSINodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔
CDD_SrlComVehSpd_Kph_G_f32	310.740509	310.740509	✔
CMM388NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	29729	29729	✔
CONSANGLECPK_HwDeg_M_f32	597.872986	597.872986 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1516957696	1516957696	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1516957696	1516957696	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1516957696	1516957696	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1516957696	1516957696	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1516957696	1516957696	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1516957696	1516957696	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1516957696	1516957696	✔
ESPNTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	11	11	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	66	66	✔
ElecIntTimer_mS_M_u32[1]	79	79	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1516957696	1516957696	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	1868	1868	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	5960	5960	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	26851	26851	✔
ISDATBSI412MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	54595	54595	✔
ISDATBSI432MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDATDIRASentFltAcc_Cnt_M_u16	13378	13378	✔
ISDATDIRASentTimer_mS_M_u32	1516957696	1516957696	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	13617	13617	✔
ISDYN2CMMMsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	13739	13739	✔
ISDYNAASMsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	29729	29729	✔
ISDYNABRMsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	5960	5960	✔
ISDYNCMM208MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	49929	49929	✔
ISDYNCMM388MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	12917	12917	✔
ISDYNVOLMsgTimer_mS_M_u32	1516957696	1516957696	✔
IgnOnTimer_mS_M_u32	4071962368	4071962368	✔
IgnTimeOff_Sec_M_u32	2668809073	2668809073	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	101	101	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3138860800	3138860800	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	93	93	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3250247424	3250247424	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	156	156	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3815667456	3815667456	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	202	202	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3358725888	3358725888	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2705815296	2705815296	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2062112512	2062112512	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	128	128	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2564617984	2564617984	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	173	173	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1999574784	1999574784	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	47	47	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	432944896	432944896	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	64	64	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	435279616	435279616	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	89	89	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4112873216	4112873216	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3342780160	3342780160	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	391.338989	391.338989	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	285.588593	285.588593	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	382.371796	382.371796	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	29729	29729	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2668809073	2668809073	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	597.872986	597.872986 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	310.740509	310.740509	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.316 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3968388608
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	8615
AASNodeAbsentTimer_mS_M_u32	1907277312
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	57019
ANGLEVOLANTSigValidCount_Cnt_M_u16	60707
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	28020
AngleVolantMsgTimer_mS_M_u32	3968388608
AngleVolantValidCount_Cnt_M_u16	38319
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2185920000
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	688979456
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	4221922816
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	627060224
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	37266
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1465249280
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	46431
CAVNodeAbsentTimer_mS_M_u32	211770880
CDD_SrlComVehSpd_Kph_G_f32	168.710602
CMM388NTCEnableTimer_mS_M_u32	676306432
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1528126976
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	19417
CMMNodeAbsentTimer_mS_M_u32	1969892864
CONSANGLECPKSigInvalidCount_Cnt_M_u16	38627
CONSANGLECPKSigValidCount_Cnt_M_u16	18330
CONSANGLECPK_Cnt_M_u16	36437
CONSANGLECPK_HwDeg_M_f32	423.230011
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	36437
CPKVehicleSpeedMsgTimer_mS_M_u32	890752512
CPKVehicleSpeedValidCount_Cnt_M_u16	38574
CityParkInputConsistentCount_Cnt_M_u16	46163
CityParkInputInvalidCount_Cnt_M_u16	33588
CityParkInputMsgTimer_mS_M_u32	3138860800
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	961723904
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	63051

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3354910208
ComputerRazGCTSigValidCount_Cnt_M_u16	3928
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	32912
DMDFCTCPKSigValidCount_Cnt_M_u16	57056
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	38157
DMDRELAXECPKSigValidCount_Cnt_M_u16	7413
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	19376
DateInvalidTimer_mS_M_u32	688979456
DiagMuxOnAbsentTimer_mS_M_u32	3881733632
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	627060224
ESPNTCEnableTimer_mS_M_u32	3302997504
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	21501
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	21
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	101
ElecIntTimer_mS_M_u32[1]	106
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	705162752
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	12686
EtatMTSigValidCount_Cnt_M_u16	13090
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	49973
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	28012
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	18262
ISDAT4V2BSI552MsgTimer_mS_M_u32	1879977472
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	21717
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	29497
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13090
ISDATBSI3F2MsgTimer_mS_M_u32	1393331712
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	16504
ISDATBSI412MsgLenValidCount_Cnt_M_u16	64515
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	12686
ISDATBSI412MsgTimer_mS_M_u32	4265004544
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	47485
ISDATBSI432MsgLenValidCount_Cnt_M_u16	29857
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	19888
ISDATDIRASentFltAcc_Cnt_M_u16	46436
ISDATDIRASentTimer_mS_M_u32	890752512
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	131
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	38319
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	5351
ISDYN2CMMMsgTimer_mS_M_u32	963231232
ISDYNAASChkSumInvalidCount_Cnt_M_u16	9209
ISDYNAASChkSumValidCount_Cnt_M_u16	60800
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	53254
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	56410
ISDYNAASMsgLenValidCount_Cnt_M_u16	2522
ISDYNAASMsgTimeValidCount_Cnt_M_u16	9209
ISDYNAASMsgTimer_mS_M_u32	447454720
ISDYNABRChkSumInvalidCount_Cnt_M_u16	42515
ISDYNABRChkSumValidCount_Cnt_M_u16	55618
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	51408
ISDYNABRMsgCountValidCount_Cnt_M_u16	21911
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	36538
ISDYNABRMsgLenValidCount_Cnt_M_u16	17073
ISDYNABRMsgTimeValidCount_Cnt_M_u16	36437
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	48330
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	44667
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13090
ISDYNCMM208MsgTimer_mS_M_u32	2911862272
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	48330
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	44667
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	48733

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3279363584
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	14993
ISDYNVOLChkSumValidCount_Cnt_M_u16	61896
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	46910
ISDYNVOLMsgCountValidCount_Cnt_M_u16	23566
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	20006
ISDYNVOLMsgLenValidCount_Cnt_M_u16	41917
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	19417
ISDYNVOLMsgTimer_mS_M_u32	2790514176
IgnOnTimer_mS_M_u32	1763384832
IgnTimeOff_Sec_M_u32	1567389099
ManVehSpd_Kph_M_f32	70.1828003
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	194
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	20
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3613560320
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	86
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1700556288
PrevISDATBSI412MsgDLCError_Cnt_M_u08	10
PrevISDATBSI412MsgRxTime_MSec_M_u32	4021313024
PrevISDATBSI432MsgDLCError_Cnt_M_u08	243
PrevISDATBSI432MsgRxTime_MSec_M_u32	2431892992
PrevISDATDIRAMsgTxTime_MSec_M_u32	1986289152
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	47
PrevISDYN2CMMMsgRxTime_MSec_M_u32	222146048
PrevISDYNAASMsgDLCError_Cnt_M_u08	140
PrevISDYNAASMsgRxTime_MSec_M_u32	3766607360
PrevISDYNABRMsgDLCError_Cnt_M_u08	187
PrevISDYNABRMsgRxTime_MSec_M_u32	1892883968
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	131
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3779517952
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	94
PrevISDYNCMM388MsgRxTime_MSec_M_u32	78560768
PrevISDYNVOLMsgDLCError_Cnt_M_u08	75
PrevISDYNVOLMsgRxTime_MSec_M_u32	4207762944
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	853855744
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	0.804899991
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	47368
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	44296
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	28849
VitesseVehicleBVRampValidCount_Cnt_M_u16	369
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	57316
VitesseVehicleBVSigValidCount_Cnt_M_u16	43788
VitesseVehicleBV_Kph_M_f32	284.726288
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	48733
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	8380
VitesseVehiculeRoues_Kph_M_f32	218.711502
k_AASNTCEnableTimeout_mS_u16	18724
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	37986
k_AASNodeTimeout_mS_u16	49160
k_ABSNodeTimeout_mS_u16	45973
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	34160
k_ANGLEVOLANTSigValidThresh_Cnt_u16	24788
k_AngleVolantInvalidThresh_Cnt_u16	48371
k_AngleVolantValidThresh_Cnt_u16	33588
k_BSI552MsgTimeout_mS_u16	10651
k_BSINTCEnableTimeout_mS_u16	12597
k_BSINodeAbsentDiag_Cnt_str.Threshold	37575
k_BSINodeAbsentDiag_Cnt_str.PStep	33443
k_BSINodeAbsentDiag_Cnt_str.NStep	49906
k_BSINodeAbsentTimeout_mS_u16	46892
k_BSINodeTimeout_mS_u16	19888
k_BattOvHi_Volt_f32	5.05259991
k_BattOvLo_Volt_f32	23.9754009
k_BattUvHi_Volt_f32	3.69840002
k_BattUvLo_Volt_f32	28.5788994
k_CAVNTCEnableTimeout_mS_u16	26522
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	40205
k_CAVNodeTimeout_mS_u16	319
k_CMM388MsgTimeout_mS_u16	29863
k_CMM388NTCEnableTimeout_mS_u16	57347
k_CMMNTCEnableTimeout_mS_u16	22166
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	33304
k_CONSANGLECPKMax_HwDeg_f32	365.406189
k_CONSANGLECPKMin_HwDeg_f32	-435.097992
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	37213
k_CONSANGLECPKSigValidThresh_Cnt_u16	13244
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	13182
k_CPKVehicleSpeedValidThresh_Cnt_u16	12595
k_CityParkInputInvalidThresh_Cnt_u16	36361
k_CityParkInputValidThresh_Cnt_u16	46163
k_ComputerRazGCTSigValidThresh_Cnt_u16	59828
k_CptTemporelSigValidThresh_Cnt_u16	44687
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	57786
k_DMDFCTCPKSigValidThresh_Cnt_u16	54705
k_DMDFCTCPKValidCount_Cnt_u16	43738
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	5351
k_DMDRELAXECPKSigValidThresh_Cnt_u16	54903
k_DMDRelaxeConsistentThresh_Cnt_u16	62445
k_DateValidThresh_Cnt_u16	18262
k_DefaultVehSpd_Kph_f32	37.3512993
k_DiagMuxOnAbsentTimeout_mS_u16	31803
k_EMNodeTimeout_mS_u16	41744
k_ESPNTCEnableTimeout_mS_u16	33211
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	4704
k_EtatMTSigInvalidThresh_Cnt_u16	12818
k_EtatMTSigValidThresh_Cnt_u16	46721
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	25625
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	28812
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	65020
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	3019
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	998
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	37916
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	25578
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	1742
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	26401
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	14681
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	58117
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	16630
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	61039
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	60731
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	28020
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	33447
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	30995
k_ISDYNAASChkSumValidThresh_Cnt_u16	60482
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	7120
k_ISDYNAASMsgCountValidThresh_Cnt_u16	59543
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	28855
k_ISDYNAASMsgLenValidThresh_Cnt_u16	13996
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	61212
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	60776
k_ISDYNABRChkSumValidThresh_Cnt_u16	59359
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	58514
k_ISDYNABRMsgCountValidThresh_Cnt_u16	30266
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	24281
k_ISDYNABRMsgLenValidThresh_Cnt_u16	42749
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	60569
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	53164
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	34657
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	49127
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	12731
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	32803
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	37100
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	64747
k_ISDYNVOLChkSumValidThresh_Cnt_u16	14518
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	16074
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	5862
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	62186
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	33150
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	48188
k_IgnOnTimeout_mS_u16	63815
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	99.2248001
k_PowerCutVehSpdLowThresh_Kph_f32	255
k_PowerCutVehSpdLowTimeout_mS_u16	51312
k_VBattMaxAAS_Volt_f32	25.4027996
k_VBattMaxBSI_Volt_f32	25.5683002
k_VBattMaxCAV_Volt_f32	28.0261002
k_VBattMaxCMM388_Volt_f32	16.1187
k_VBattMaxCMM_Volt_f32	12.4967003
k_VBattMaxESP_Volt_f32	21.3960991
k_VBattMinAAS_Volt_f32	27.8034
k_VBattMinBSI_Volt_f32	21.3960991
k_VBattMinCAV_Volt_f32	8.88519955
k_VBattMinCMM388_Volt_f32	18.2756004
k_VBattMinCMM_Volt_f32	31.7115002
k_VBattMinESP_Volt_f32	12.4967003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	54469
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	52161
k_VitesseVehicleBVRampValidThresh_Cnt_u16	35390
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	33992
k_VitesseVehicleBVSigValidThresh_Cnt_u16	13236
k_VitesseVehicleBVSpeedPassThresh_kph_f32	376.872009
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	34911
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	8095
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	688979456
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60573
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1277031168
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	94
target_SrlComInput_Per1_Batt_Volt_f32.value	2.15459991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1225190912
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	113
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.432783306
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	401939968
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	115
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2592751104
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	200236544
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1948548608
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3676937728
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1224654336
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	28
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3315850752
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	108
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	121
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	203
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	207
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	221
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2603449856
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	84
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	146
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	163
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	216
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	228
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2546998784
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	101
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	769998336
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1925864960
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	134
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	175
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3317591552
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	221
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0636903048
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	351395
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	137.571701
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	28022	28022	✔
AngleVolantMsgTimer_mS_M_u32	1277031168	1277031168	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	36437	36437	✔
CONSANGLECPK_HwDeg_M_f32	423.230011	423.230011 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	36437	36437	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	890752512	890752512	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	38574	38574	✔
CityParkInputConsistentCount_Cnt_M_u16	46163	46163	✔
CityParkInputInvalidCount_Cnt_M_u16	33590	33590	✔
CityParkInputMsgTimer_mS_M_u32	1277031168	1277031168	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1277031168	1277031168	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1277031168	1277031168	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1277031168	1277031168	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1277031168	1277031168	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1277031168	1277031168	✔
ESPNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1277031168	1277031168	✔
EffacDefaultDiagTimer_mS_M_u32[1]	21	21	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1277031168	1277031168	✔
ElecIntTimer_mS_M_u32[1]	106	106	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1277031168	1277031168	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATDIRASentFltAcc_Cnt_M_u16	41895	41895	✔
ISDATDIRASentTimer_mS_M_u32	1277031168	1277031168	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1277031168	1277031168	✔
IgnOnTimer_mS_M_u32	1277031168	1277031168	✔
IgnTimeOff_Sec_M_u32	1567389099	1567389099	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	229	229	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	401939968	401939968	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	115	115	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2592751104	2592751104	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	108	108	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	200236544	200236544	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	216	216	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1948548608	1948548608	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1986289152	1986289152	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	40	40	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1224654336	1224654336	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	28	28	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3315850752	3315850752	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2603449856	2603449856	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	35	35	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2546998784	2546998784	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	101	101	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	769998336	769998336	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	209	209	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1925864960	1925864960	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3317591552	3317591552	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	0.804899991	0.804899991	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	284.726288	284.726288	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	218.711502	218.711502	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	36437	36437	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1567389099	1567389099	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	423.230011	423.230011 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	37.3512993	37.3512993	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.317 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3938212096
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	58720
AASNodeAbsentTimer_mS_M_u32	2668267776
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	40995
ANGLEVOLANTSigValidCount_Cnt_M_u16	40621
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	30201
AngleVolantMsgTimer_mS_M_u32	3938212096
AngleVolantValidCount_Cnt_M_u16	20936
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2352433408
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3521366272
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2011592960
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1438005504
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	41886
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3335846144
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	21686
CAVNodeAbsentTimer_mS_M_u32	3635980544
CDD_SrlComVehSpd_Kph_G_f32	49.1650009
CMM388NTCEnableTimer_mS_M_u32	2527586560
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1163307264
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	54281
CMMNodeAbsentTimer_mS_M_u32	228079872
CONSANGLECPKSigInvalidCount_Cnt_M_u16	50860
CONSANGLECPKSigValidCount_Cnt_M_u16	7749
CONSANGLECPK_Cnt_M_u16	62996
CONSANGLECPK_HwDeg_M_f32	485.928497
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	62996
CPKVehicleSpeedMsgTimer_mS_M_u32	219109632
CPKVehicleSpeedValidCount_Cnt_M_u16	38898

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	34268
CityParkInputInvalidCount_Cnt_M_u16	11832
CityParkInputMsgTimer_mS_M_u32	401939968
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3625879808
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	63348
ComputerRazGCTSigInvalidTimer_mS_M_u32	2830051584
ComputerRazGCTSigValidCount_Cnt_M_u16	51405
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	42532
DMDFCTCPKSigValidCount_Cnt_M_u16	21750
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	17709
DMDRELAXECPKSigValidCount_Cnt_M_u16	55095
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	7237
DateInvalidTimer_mS_M_u32	3521366272
DiagMuxOnAbsentTimer_mS_M_u32	2168133888
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1438005504
ESPNTCEnableTimer_mS_M_u32	2843183360
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	54623
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	22
EffacDefaultDiagTimer_mS_M_u32[1]	23
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	99
ElecIntTimer_mS_M_u32[1]	1000
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2529097984
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	34794
EtatMTSigValidCount_Cnt_M_u16	23791
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	2486
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	29903
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	29588
ISDAT4V2BSI552MsgTimer_mS_M_u32	2913745152
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	18812
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	45609
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	23791
ISDATBSI3F2MsgTimer_mS_M_u32	1982929152
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	35245
ISDATBSI412MsgLenValidCount_Cnt_M_u16	4298
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	34794
ISDATBSI412MsgTimer_mS_M_u32	0
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	6941
ISDATBSI432MsgLenValidCount_Cnt_M_u16	883
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	4035
ISDATDIRASentFltAcc_Cnt_M_u16	43175
ISDATDIRASentTimer_mS_M_u32	219109632
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	55178
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	20936
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	1311
ISDYN2CMMMsgTimer_mS_M_u32	4091119872
ISDYNAASChkSumInvalidCount_Cnt_M_u16	42602
ISDYNAASChkSumValidCount_Cnt_M_u16	62356
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	48835
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	35781
ISDYNAASMsgLenValidCount_Cnt_M_u16	36103
ISDYNAASMsgTimeValidCount_Cnt_M_u16	42602
ISDYNAASMsgTimer_mS_M_u32	798222592
ISDYNABRChkSumInvalidCount_Cnt_M_u16	24477
ISDYNABRChkSumValidCount_Cnt_M_u16	4046
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	54245
ISDYNABRMsgCountValidCount_Cnt_M_u16	55119
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	64295
ISDYNABRMsgLenValidCount_Cnt_M_u16	18688
ISDYNABRMsgTimeValidCount_Cnt_M_u16	62996

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	35237
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	16980
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	23791
ISDYNCMM208MsgTimer_mS_M_u32	1583892736
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	35237
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	16980
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	4030
ISDYNCMM388MsgTimer_mS_M_u32	3274795264
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	5026
ISDYNVOLChkSumValidCount_Cnt_M_u16	22459
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	14874
ISDYNVOLMsgCountValidCount_Cnt_M_u16	5484
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	51940
ISDYNVOLMsgLenValidCount_Cnt_M_u16	46046
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	54281
ISDYNVOLMsgTimer_mS_M_u32	2107320576
IgnOnTimer_mS_M_u32	1648716032
IgnTimeOff_Sec_M_u32	2823200653
ManVehSpd_Kph_M_f32	313.341309
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	195
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	144
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3241089280
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	197
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3603003648
PrevISDATBSI412MsgDLCError_Cnt_M_u08	31
PrevISDATBSI412MsgRxTime_MSec_M_u32	3011881216
PrevISDATBSI432MsgDLCError_Cnt_M_u08	26
PrevISDATBSI432MsgRxTime_MSec_M_u32	2503706880
PrevISDATDIRAMsgTxTime_MSec_M_u32	4016679168
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	16
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4095588608
PrevISDYNAASMsgDLCError_Cnt_M_u08	180
PrevISDYNAASMsgRxTime_MSec_M_u32	118565120
PrevISDYNABRMsgDLCError_Cnt_M_u08	18
PrevISDYNABRMsgRxTime_MSec_M_u32	723347712
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	91
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1489119488
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	122
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3859450112
PrevISDYNVOLMsgDLCError_Cnt_M_u08	146
PrevISDYNVOLMsgRxTime_MSec_M_u32	1177463040
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2275956992
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	4.22289991
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	11707
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	56189
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	60096
VitesseVehicleBVRampValidCount_Cnt_M_u16	49730
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	32936

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	18674
VitesseVehicleBV_Kph_M_f32	565.12793
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	4030
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	62048
VitesseVehiculeRoues_Kph_M_f32	90.1675034
k_AASNTCEnableTimeout_mS_u16	49575
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	57775
k_AASNodeTimeout_mS_u16	41597
k_ABSNodeTimeout_mS_u16	24853
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	17220
k_ANGLEVOLANTSigValidThresh_Cnt_u16	51930
k_AngleVolantInvalidThresh_Cnt_u16	62077
k_AngleVolantValidThresh_Cnt_u16	11832
k_BSI552MsgTimeout_mS_u16	5059
k_BSINTCEnableTimeout_mS_u16	37877
k_BSINodeAbsentDiag_Cnt_str.Threshold	37679
k_BSINodeAbsentDiag_Cnt_str.PStep	26076
k_BSINodeAbsentDiag_Cnt_str.NStep	5933
k_BSINodeAbsentTimeout_mS_u16	30929
k_BSINodeTimeout_mS_u16	4035
k_BattOvHi_Volt_f32	25.9227009
k_BattOvLo_Volt_f32	20.2847004
k_BattUvHi_Volt_f32	5.16620016
k_BattUvLo_Volt_f32	10.9811001
k_CAVNTCEnableTimeout_mS_u16	39174
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	54700
k_CAVNodeTimeout_mS_u16	63384
k_CMM388MsgTimeout_mS_u16	60512
k_CMM388NTCEnableTimeout_mS_u16	6732
k_CMMNTCEnableTimeout_mS_u16	61012
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	15948
k_CONSANGLECPKMax_HwDeg_f32	94.6201019
k_CONSANGLECPKMin_HwDeg_f32	-105.997398
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	38590
k_CONSANGLECPKSigValidThresh_Cnt_u16	47456
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	40987
k_CPKVehicleSpeedValidThresh_Cnt_u16	25468
k_CityParkInputInvalidThresh_Cnt_u16	65467
k_CityParkInputValidThresh_Cnt_u16	34268
k_ComputerRazGCTSigValidThresh_Cnt_u16	11514
k_CptTemporelSigValidThresh_Cnt_u16	55335
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	551
k_DMDFCTCPKSigValidThresh_Cnt_u16	36864
k_DMDFCTCPKValidCount_Cnt_u16	30662
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	1311
k_DMDRELAXECPKSigValidThresh_Cnt_u16	35377
k_DMDRelaxeConsistentThresh_Cnt_u16	35279
k_DateValidThresh_Cnt_u16	29588
k_DefaultVehSpd_Kph_f32	108.785004
k_DiagMuxOnAbsentTimeout_mS_u16	17506
k_EMNodeTimeout_mS_u16	38437
k_ESPNTCEnableTimeout_mS_u16	24482
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	44404
k_EtatMTSigInvalidThresh_Cnt_u16	30624
k_EtatMTSigValidThresh_Cnt_u16	13329
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	14922
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	28336
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	36065
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	58037
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	62498
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	7873

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	4054
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	16620
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	41521
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	1288
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	16838
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	20786
k_ISDATDIRASentDiag_Cnt_str.Threshold	12314
k_ISDATDIRASentDiag_Cnt_str.PStep	25984
k_ISDATDIRASentDiag_Cnt_str.NStep	21340
k_ISDATDIRASentTimeout_mS_u16	63113
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	41059
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	30201
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	3294
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	59037
k_ISDYNAASChkSumValidThresh_Cnt_u16	54990
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	56037
k_ISDYNAASMsgCountValidThresh_Cnt_u16	7759
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	36785
k_ISDYNAASMsgLenValidThresh_Cnt_u16	52881
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	16386
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	5917
k_ISDYNABRChkSumValidThresh_Cnt_u16	37238
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	43678
k_ISDYNABRMsgCountValidThresh_Cnt_u16	8040
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	39689
k_ISDYNABRMsgLenValidThresh_Cnt_u16	56415
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	63563
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	31183
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	39154
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	57056
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	42787
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	58797
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	58640
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	57428
k_ISDYNVOLChkSumValidThresh_Cnt_u16	59057
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	35064
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	59106
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	46038
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	57819
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	11490
k_IgnOnTimeout_mS_u16	23360
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	57.6643982
k_PowerCutVehSpdLowThresh_Kph_f32	44.7034988
k_PowerCutVehSpdLowTimeout_mS_u16	29635
k_VBattMaxAAS_Volt_f32	17.4857006
k_VBattMaxBSI_Volt_f32	30.7178001
k_VBattMaxCAV_Volt_f32	1.72029996
k_VBattMaxCMM388_Volt_f32	30.5459995
k_VBattMaxCMM_Volt_f32	25.9109993
k_VBattMaxESP_Volt_f32	16.0673008
k_VBattMinAAS_Volt_f32	11.5407
k_VBattMinBSI_Volt_f32	16.0673008
k_VBattMinCAV_Volt_f32	12.9622002
k_VBattMinCMM388_Volt_f32	6.76970005
k_VBattMinCMM_Volt_f32	27.2733994
k_VBattMinESP_Volt_f32	25.9109993
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	37317
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	9875
k_VitesseVehicleBVRampValidThresh_Cnt_u16	49434
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	40635
k_VitesseVehicleBVSigValidThresh_Cnt_u16	52153
k_VitesseVehicleBVSpeedPassThresh_kph_f32	635.448486
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	56246
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	40888
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3521366272
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	122
target_SrlComInput_Per1_Batt_Volt_f32.value	20.5160007
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4123130112
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	195
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.215936825
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1035430144
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	96
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4067952896
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	449358080
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2661894400
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1712974080
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1494911232
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1605052672
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	43
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	69
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	76
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	185
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2374912256
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	125
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	141
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	161
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	188
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	211
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	218
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3928385792
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1684474112
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	78
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	305637632
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	45
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	80
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	106
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	129
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	137
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	153
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3181082880
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	86
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.110807493
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	385840
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	237.873703
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	64157

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	37679	37679	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	313.341309	313.341309	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	62996	62996	✔
CONSANGLECPK_HwDeg_M_f32	485.928497	485.928497 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1713429248	1713429248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	22	22	✔
EffacDefaultDiagTimer_mS_M_u32[1]	23	23	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	99	99	✔
ElecIntTimer_mS_M_u32[1]	1000	1000	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	29588	29588	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	23791	23791	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	34794	34794	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	4035	4035	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	12314	12314	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	1311	1311	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	42602	42602	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	62996	62996	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	23791	23791	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	4030	4030	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	54281	54281	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	1648716032	1648716032	✔
IgnTimeOff_Sec_M_u32	2823200653	2823200653	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	110	110	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1035430144	1035430144	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	96	96	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4067952896	4067952896	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	81	81	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	449358080	449358080	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2661894400	2661894400	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4016679168	4016679168	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	51	51	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1494911232	1494911232	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	51	51	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1605052672	1605052672	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	235	235	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2374912256	2374912256	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	223	223	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3928385792	3928385792	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	183	183	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1684474112	1684474112	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	78	78	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	305637632	305637632	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3181082880	3181082880	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	4.22289991	4.22289991	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	565.12793	565.12793	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	90.1675034	90.1675034	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	62996	62996	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2823200653	2823200653	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	485.928497	485.928497 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.318 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	899072
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	16928
AASNodeAbsentTimer_mS_M_u32	400762880
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	15320
ANGLEVOLANTSigValidCount_Cnt_M_u16	49915
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	13397
AngleVolantMsgTimer_mS_M_u32	899072
AngleVolantValidCount_Cnt_M_u16	41833
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	4082952192
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1951885312
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	688871424
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2124421120
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	56679
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	373544960
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	29853
CAVNodeAbsentTimer_mS_M_u32	1264109568
CDD_SrlComVehSpd_Kph_G_f32	35.8462982
CMM388NTCEnableTimer_mS_M_u32	3733653504
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	4252944384
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	11877
CMMNodeAbsentTimer_mS_M_u32	1593448448
CONSANGLECPKSigInvalidCount_Cnt_M_u16	56126
CONSANGLECPKSigValidCount_Cnt_M_u16	38705
CONSANGLECPK_Cnt_M_u16	3012
CONSANGLECPK_HwDeg_M_f32	-757.538025
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	3012
CPKVehicleSpeedMsgTimer_mS_M_u32	2769598464
CPKVehicleSpeedValidCount_Cnt_M_u16	38257
CityParkInputConsistentCount_Cnt_M_u16	22317
CityParkInputInvalidCount_Cnt_M_u16	7960
CityParkInputMsgTimer_mS_M_u32	1035430144
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3165071360
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	23524

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3581233152
ComputerRazGCTSigValidCount_Cnt_M_u16	37466
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	26452
DMDFCTCPKSigValidCount_Cnt_M_u16	64927
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	62650
DMDRELAXECPKSigValidCount_Cnt_M_u16	49501
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	32371
DateInvalidTimer_mS_M_u32	1951885312
DiagMuxOnAbsentTimer_mS_M_u32	2811328512
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2124421120
ESPNTCEnableTimer_mS_M_u32	3969656832
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	56611
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	28
EffacDefaultDiagTimer_mS_M_u32[1]	29
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	10
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3464878080
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	58308
EtatMTSigValidCount_Cnt_M_u16	55155
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	47648
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	15251
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	39365
ISDAT4V2BSI552MsgTimer_mS_M_u32	3468564480
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	48782
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	38725
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	55155
ISDATBSI3F2MsgTimer_mS_M_u32	548370432
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	21242
ISDATBSI412MsgLenValidCount_Cnt_M_u16	36961
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	58308
ISDATBSI412MsgTimer_mS_M_u32	4294967295
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	43305
ISDATBSI432MsgLenValidCount_Cnt_M_u16	41703
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	46966
ISDATDIRASentFltAcc_Cnt_M_u16	31946
ISDATDIRASentTimer_mS_M_u32	2769598464
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	48994
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	41833
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	63075
ISDYN2CMMMsgTimer_mS_M_u32	360065024
ISDYNAASChkSumInvalidCount_Cnt_M_u16	42754
ISDYNAASChkSumValidCount_Cnt_M_u16	49733
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	2168
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	52080
ISDYNAASMsgLenValidCount_Cnt_M_u16	10859
ISDYNAASMsgTimeValidCount_Cnt_M_u16	42754
ISDYNAASMsgTimer_mS_M_u32	3284600832
ISDYNABRChkSumInvalidCount_Cnt_M_u16	48363
ISDYNABRChkSumValidCount_Cnt_M_u16	53014
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	51857
ISDYNABRMsgCountValidCount_Cnt_M_u16	49940
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	59853
ISDYNABRMsgLenValidCount_Cnt_M_u16	49920
ISDYNABRMsgTimeValidCount_Cnt_M_u16	3012
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	46145
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	57589
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	55155
ISDYNCMM208MsgTimer_mS_M_u32	2160715776
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	46145
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	57589
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	49543

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1592690688
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	19548
ISDYNVOLChkSumValidCount_Cnt_M_u16	17103
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	882
ISDYNVOLMsgCountValidCount_Cnt_M_u16	5181
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	20628
ISDYNVOLMsgLenValidCount_Cnt_M_u16	55399
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	11877
ISDYNVOLMsgTimer_mS_M_u32	112281600
IgnOnTimer_mS_M_u32	3518138368
IgnTimeOff_Sec_M_u32	224336091
ManVehSpd_Kph_M_f32	650.218018
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	196
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	178
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3082123264
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	36
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	947804160
PrevISDATBSI412MsgDLCError_Cnt_M_u08	180
PrevISDATBSI412MsgRxTime_MSec_M_u32	787597312
PrevISDATBSI432MsgDLCError_Cnt_M_u08	164
PrevISDATBSI432MsgRxTime_MSec_M_u32	961554432
PrevISDATDIRAMsgTxTime_MSec_M_u32	189122560
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	195
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2708051968
PrevISDYNAASMsgDLCError_Cnt_M_u08	168
PrevISDYNAASMsgRxTime_MSec_M_u32	3259975680
PrevISDYNABRMsgDLCError_Cnt_M_u08	200
PrevISDYNABRMsgRxTime_MSec_M_u32	3609888768
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	13
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3510388736
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	163
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1122183168
PrevISDYNVOLMsgDLCError_Cnt_M_u08	189
PrevISDYNVOLMsgRxTime_MSec_M_u32	1526122496
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3645487104
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	503.970306
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	15758
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	38665
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	23167
VitesseVehicleBVRampValidCount_Cnt_M_u16	14010
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	61001
VitesseVehicleBVSigValidCount_Cnt_M_u16	6188
VitesseVehicleBV_Kph_M_f32	490.307404
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	49543
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	64610
VitesseVehiculeRoues_Kph_M_f32	652.503296
k_AASNTCEnableTimeout_mS_u16	46347
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	20404
k_AASNodeTimeout_mS_u16	16905
k_ABSNodeTimeout_mS_u16	14977
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	36020
k_ANGLEVOLANTSigValidThresh_Cnt_u16	43186
k_AngleVolantInvalidThresh_Cnt_u16	32201
k_AngleVolantValidThresh_Cnt_u16	7960
k_BSI552MsgTimeout_mS_u16	58425
k_BSINTCEnableTimeout_mS_u16	40609
k_BSINodeAbsentDiag_Cnt_str.Threshold	62757
k_BSINodeAbsentDiag_Cnt_str.PStep	38493
k_BSINodeAbsentDiag_Cnt_str.NStep	11177
k_BSINodeAbsentTimeout_mS_u16	35789
k_BSINodeTimeout_mS_u16	46966
k_BattOvHi_Volt_f32	20.5585003
k_BattOvLo_Volt_f32	14.0815001
k_BattUvHi_Volt_f32	27.2861004
k_BattUvLo_Volt_f32	28.4717999
k_CAVNTCEnableTimeout_mS_u16	38574
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	18875
k_CAVNodeTimeout_mS_u16	63610
k_CMM388MsgTimeout_mS_u16	11552
k_CMM388NTCEnableTimeout_mS_u16	21340
k_CMMNTCEnableTimeout_mS_u16	12294
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	51358
k_CONSANGLECPKMax_HwDeg_f32	687.083801
k_CONSANGLECPKMin_HwDeg_f32	-260.674103
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	11399
k_CONSANGLECPKSigValidThresh_Cnt_u16	42850
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	16687
k_CPKVehicleSpeedValidThresh_Cnt_u16	49549
k_CityParkInputInvalidThresh_Cnt_u16	54417
k_CityParkInputValidThresh_Cnt_u16	22317
k_ComputerRazGCTSigValidThresh_Cnt_u16	35860
k_CptTemporelSigValidThresh_Cnt_u16	40267
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	54477
k_DMDFCTCPKSigValidThresh_Cnt_u16	60928
k_DMDFCTCPKValidCount_Cnt_u16	239
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	63075
k_DMDRELAXECPKSigValidThresh_Cnt_u16	2542
k_DMDRelaxeConsistentThresh_Cnt_u16	788
k_DateValidThresh_Cnt_u16	39365
k_DefaultVehSpd_Kph_f32	244.405594
k_DiagMuxOnAbsentTimeout_mS_u16	55514
k_EMNodeTimeout_mS_u16	37075
k_ESPNTCEnableTimeout_mS_u16	985
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	6950
k_EtatMTSigInvalidThresh_Cnt_u16	16610
k_EtatMTSigValidThresh_Cnt_u16	11853
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	61090
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	17457
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	38430
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	5859
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	62810
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	58302
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	61182
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	3708
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	25581
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	44776
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	19311
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	41323
k_ISDATDIRASentDiag_Cnt_str.Threshold	53628

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	31362
k_ISDATDIRASentDiag_Cnt_str.NStep	51301
k_ISDATDIRASentTimeout_mS_u16	43047
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	47064
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	13397
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	60453
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	10219
k_ISDYNAASChkSumValidThresh_Cnt_u16	31254
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	46481
k_ISDYNAASMsgCountValidThresh_Cnt_u16	60948
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	31919
k_ISDYNAASMsgLenValidThresh_Cnt_u16	3533
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	59706
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	60907
k_ISDYNABRChkSumValidThresh_Cnt_u16	16798
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	51303
k_ISDYNABRMsgCountValidThresh_Cnt_u16	60618
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	55653
k_ISDYNABRMsgLenValidThresh_Cnt_u16	51235
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	44577
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	43346
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	31019
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	55520
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	9944
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	60923
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	23184
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	43781
k_ISDYNVOLChkSumValidThresh_Cnt_u16	27308
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	26200
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	39386
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	4096
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	63663
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	9691
k_IgnOnTimeout_mS_u16	59969
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	250.267502
k_PowerCutVehSpdLowThresh_Kph_f32	201.150299
k_PowerCutVehSpdLowTimeout_mS_u16	3767
k_VBattMaxAAS_Volt_f32	23.4379005
k_VBattMaxBSI_Volt_f32	8.55609989
k_VBattMaxCAV_Volt_f32	28.4206009
k_VBattMaxCMM388_Volt_f32	28.6329002
k_VBattMaxCMM_Volt_f32	23.0408001
k_VBattMaxESP_Volt_f32	2.0085001
k_VBattMinAAS_Volt_f32	4.50229979
k_VBattMinBSI_Volt_f32	2.0085001
k_VBattMinCAV_Volt_f32	1.23689997
k_VBattMinCMM388_Volt_f32	19.8787994
k_VBattMinCMM_Volt_f32	6.93300009
k_VBattMinESP_Volt_f32	23.0408001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	60338
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	49161
k_VitesseVehicleBVRampValidThresh_Cnt_u16	28274
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	28111
k_VitesseVehicleBVSigValidThresh_Cnt_u16	14742
k_VitesseVehicleBVSpeedPassThresh_kph_f32	551.752319
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	57245
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	63064
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1951885312
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	38041
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	242062592
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	163
target_SrlComInput_Per1_Batt_Volt_f32.value	11.6722002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2105333760
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	65
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.299748778
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2270988288
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3013257216
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	19
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3307784192
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	50
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	67561472
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3090483200
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	44
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	699607040
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2692827136
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	78
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	136
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	145
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	163
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	177
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	190310400
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	92
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	121
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	79
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4262430720
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	243
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3654133760
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1524353024
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	104
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	114
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	132
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	145
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1810913280
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2574
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.380910993
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	749741
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	103.889801
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	57064

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	242062592	242062592	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	242062592	242062592	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	13399	13399	✔
AngleVolantMsgTimer_mS_M_u32	242062592	242062592	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	242062592	242062592	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	242062592	242062592	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	242062592	242062592	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	242062592	242062592	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	242062592	242062592	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	242062592	242062592	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	242062592	242062592	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	242062592	242062592	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	242062592	242062592	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	242062592	242062592	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	3012	3012	✔
CONSANGLECPK_HwDeg_M_f32	-757.538025	-757.538025 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	3012	3012	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2769598464	2769598464	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	38257	38257	✔
CityParkInputConsistentCount_Cnt_M_u16	22317	22317	✔
CityParkInputInvalidCount_Cnt_M_u16	7962	7962	✔
CityParkInputMsgTimer_mS_M_u32	242062592	242062592	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	242062592	242062592	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	242062592	242062592	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	242062592	242062592	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	242062592	242062592	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	242062592	242062592	✔
ESPNTCEnableTimer_mS_M_u32	242062592	242062592	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	242062592	242062592	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	242062592	242062592	✔
EffacDefaultDiagTimer_mS_M_u32[1]	29	29	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	242062592	242062592	✔
ElecIntTimer_mS_M_u32[1]	10	10	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	242062592	242062592	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	242062592	242062592	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	242062592	242062592	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	242062592	242062592	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	242062592	242062592	✔
ISDATDIRASentFltAcc_Cnt_M_u16	53628	53628	✔
ISDATDIRASentTimer_mS_M_u32	242062592	242062592	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	242062592	242062592	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	242062592	242062592	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	242062592	242062592	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	242062592	242062592	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	242062592	242062592	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	242062592	242062592	✔
IgnOnTimer_mS_M_u32	242062592	242062592	✔
IgnTimeOff_Sec_M_u32	224336091	224336091	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2270988288	2270988288	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	125	125	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3013257216	3013257216	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	19	19	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3307784192	3307784192	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	50	50	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	67561472	67561472	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	189122560	189122560	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	44	44	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	699607040	699607040	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	151	151	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2692827136	2692827136	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	196	196	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	190310400	190310400	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	79	79	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4262430720	4262430720	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	243	243	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3654133760	3654133760	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	153	153	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1524353024	1524353024	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1810913280	1810913280	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	503.970306	503.970306	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	490.307404	490.307404	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	652.503296	652.503296	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	3012	3012	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	224336091	224336091	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-757.538025	-757.538025 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	244.405594	244.405594	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.319 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1079352064
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	58398
AASNodeAbsentTimer_mS_M_u32	1519733504
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	30964
ANGLEVOLANTSigValidCount_Cnt_M_u16	23371
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	8575
AngleVolantMsgTimer_mS_M_u32	1079352064
AngleVolantValidCount_Cnt_M_u16	52418
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3743943424
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1714981632
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1406188288
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2250144512
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	36935
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4264770304
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	52005
CAVNodeAbsentTimer_mS_M_u32	515140352
CDD_SrlComVehSpd_Kph_G_f32	330.222198
CMM388NTCEnableTimer_mS_M_u32	4263357184
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	541223680
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	63119
CMMNodeAbsentTimer_mS_M_u32	3440409344
CONSANGLECPKSigInvalidCount_Cnt_M_u16	25027
CONSANGLECPKSigValidCount_Cnt_M_u16	58794
CONSANGLECPK_Cnt_M_u16	37873
CONSANGLECPK_HwDeg_M_f32	-592.838379
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37873
CPKVehicleSpeedMsgTimer_mS_M_u32	759208704
CPKVehicleSpeedValidCount_Cnt_M_u16	51473
CityParkInputConsistentCount_Cnt_M_u16	49526

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	9908
CityParkInputMsgTimer_mS_M_u32	2270988288
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2085178112
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	42706
ComputerRazGCTSigInvalidTimer_mS_M_u32	2455694080
ComputerRazGCTSigValidCount_Cnt_M_u16	1007
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	15872
DMDFCTCPKSigValidCount_Cnt_M_u16	37600
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	22094
DMDRELAXECPKSigValidCount_Cnt_M_u16	26661
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	35876
DateInvalidTimer_mS_M_u32	1714981632
DiagMuxOnAbsentTimer_mS_M_u32	147479296
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2250144512
ESPNTCEnableTimer_mS_M_u32	6966016
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	53778
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	200
EffacDefaultDiagTimer_mS_M_u32[1]	300
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	6
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1567439616
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	25457
EtatMTSigValidCount_Cnt_M_u16	12325
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	52509
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	132
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	54894
ISDAT4V2BSI552MsgTimer_mS_M_u32	2378464000
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	29842
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	45613
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	12325
ISDATBSI3F2MsgTimer_mS_M_u32	2507168512
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	47182
ISDATBSI412MsgLenValidCount_Cnt_M_u16	34777
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	25457
ISDATBSI412MsgTimer_mS_M_u32	3175290880
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	38467
ISDATBSI432MsgLenValidCount_Cnt_M_u16	37062
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	42650
ISDATDIRASentFltAcc_Cnt_M_u16	42654
ISDATDIRASentTimer_mS_M_u32	759208704
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	28951
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	52418
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36051
ISDYN2CMMMsgTimer_mS_M_u32	1843153664
ISDYNAASChkSumInvalidCount_Cnt_M_u16	48504
ISDYNAASChkSumValidCount_Cnt_M_u16	25455
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	39317
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	53932
ISDYNAASMsgLenValidCount_Cnt_M_u16	36219
ISDYNAASMsgTimeValidCount_Cnt_M_u16	48504
ISDYNAASMsgTimer_mS_M_u32	1047112448
ISDYNABRChkSumInvalidCount_Cnt_M_u16	46909
ISDYNABRChkSumValidCount_Cnt_M_u16	6268
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	20171
ISDYNABRMsgCountValidCount_Cnt_M_u16	23810
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	12822
ISDYNABRMsgLenValidCount_Cnt_M_u16	24125
ISDYNABRMsgTimeValidCount_Cnt_M_u16	37873
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	12522

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	42639
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	12325
ISDYNCMM208MsgTimer_mS_M_u32	719391488
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	12522
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	42639
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	27240
ISDYNCMM388MsgTimer_mS_M_u32	1794321152
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	1641
ISDYNVOLChkSumValidCount_Cnt_M_u16	56016
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	24998
ISDYNVOLMsgCountValidCount_Cnt_M_u16	18182
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	31679
ISDYNVOLMsgLenValidCount_Cnt_M_u16	7175
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	63119
ISDYNVOLMsgTimer_mS_M_u32	4004178688
IgnOnTimer_mS_M_u32	581380864
IgnTimeOff_Sec_M_u32	334728480
ManVehSpd_Kph_M_f32	173.465103
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	197
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	59
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1751014144
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	183
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2709764864
PrevISDATBSI412MsgDLCError_Cnt_M_u08	40
PrevISDATBSI412MsgRxTime_MSec_M_u32	401173248
PrevISDATBSI432MsgDLCError_Cnt_M_u08	185
PrevISDATBSI432MsgRxTime_MSec_M_u32	3930999552
PrevISDATDIRAMsgTxTime_MSec_M_u32	3538774784
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	86
PrevISDYN2CMMMsgRxTime_MSec_M_u32	599915264
PrevISDYNAASMsgDLCError_Cnt_M_u08	51
PrevISDYNAASMsgRxTime_MSec_M_u32	3016813312
PrevISDYNABRMsgDLCError_Cnt_M_u08	38
PrevISDYNABRMsgRxTime_MSec_M_u32	4064226048
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	247
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2064247552
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	97
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3650439936
PrevISDYNVOLMsgDLCError_Cnt_M_u08	234
PrevISDYNVOLMsgRxTime_MSec_M_u32	3889851136
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2762054400
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	551.317383
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	29778
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	16289
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	8575
VitesseVehicleBVRampValidCount_Cnt_M_u16	25742
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	26017
VitesseVehicleBVSigValidCount_Cnt_M_u16	24504

Name	Input Value
VitesseVehicleBV_Kph_M_f32	179.529694
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	27240
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	4503
VitesseVehiculeRoues_Kph_M_f32	199.298004
k_AASNTCEnableTimeout_mS_u16	29724
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	46049
k_AASNodeTimeout_mS_u16	16033
k_ABSNodeTimeout_mS_u16	47225
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	55202
k_ANGLEVOLANTSigValidThresh_Cnt_u16	27493
k_AngleVolantInvalidThresh_Cnt_u16	2080
k_AngleVolantValidThresh_Cnt_u16	9908
k_BSI552MsgTimeout_mS_u16	30226
k_BSINTCEnableTimeout_mS_u16	38363
k_BSINodeAbsentDiag_Cnt_str.Threshold	21951
k_BSINodeAbsentDiag_Cnt_str.PStep	9815
k_BSINodeAbsentDiag_Cnt_str.NStep	27314
k_BSINodeAbsentTimeout_mS_u16	64279
k_BSINodeTimeout_mS_u16	42650
k_BattOvHi_Volt_f32	17.257
k_BattOvLo_Volt_f32	9.36139965
k_BattUvHi_Volt_f32	1.20019996
k_BattUvLo_Volt_f32	6.75209999
k_CAVNTCEnableTimeout_mS_u16	38898
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	17355
k_CAVNodeTimeout_mS_u16	64015
k_CMM388MsgTimeout_mS_u16	8990
k_CMM388NTCEnableTimeout_mS_u16	41066
k_CMMNTCEnableTimeout_mS_u16	42
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	40163
k_CONSANGLECPKMax_HwDeg_f32	106.313797
k_CONSANGLECPKMin_HwDeg_f32	-195.581207
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	10600
k_CONSANGLECPKSigValidThresh_Cnt_u16	4247
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	22831
k_CPKVehicleSpeedValidThresh_Cnt_u16	30869
k_CityParkInputInvalidThresh_Cnt_u16	34891
k_CityParkInputValidThresh_Cnt_u16	49526
k_ComputerRazGCTSigValidThresh_Cnt_u16	41984
k_CptTemporelSigValidThresh_Cnt_u16	14363
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	28950
k_DMDFCTCPKSigValidThresh_Cnt_u16	56637
k_DMDFCTCPKValidCount_Cnt_u16	17839
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	36051
k_DMDRELAXECPKSigValidThresh_Cnt_u16	27123
k_DMDRelaxeConsistentThresh_Cnt_u16	38529
k_DateValidThresh_Cnt_u16	54894
k_DefaultVehSpd_Kph_f32	243.778198
k_DiagMuxOnAbsentTimeout_mS_u16	1199
k_EMNodeTimeout_mS_u16	54532
k_ESPNTCEnableTimeout_mS_u16	3441
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	50507
k_EtatMTSigInvalidThresh_Cnt_u16	51032
k_EtatMTSigValidThresh_Cnt_u16	38615
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	56534
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	1001
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	2211
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	65427
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	11246
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	5634
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	22724

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	57863
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	30199
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	14981
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	27824
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	56829
k_ISDATDIRASentDiag_Cnt_str.Threshold	1905
k_ISDATDIRASentDiag_Cnt_str.PStep	4278
k_ISDATDIRASentDiag_Cnt_str.NStep	49319
k_ISDATDIRASentTimeout_mS_u16	58761
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	36534
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	8575
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	33933
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	30269
k_ISDYNAASChkSumValidThresh_Cnt_u16	6012
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	36299
k_ISDYNAASMsgCountValidThresh_Cnt_u16	56322
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	34801
k_ISDYNAASMsgLenValidThresh_Cnt_u16	60245
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	51661
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	7612
k_ISDYNABRChkSumValidThresh_Cnt_u16	55907
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	53063
k_ISDYNABRMsgCountValidThresh_Cnt_u16	55774
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	62863
k_ISDYNABRMsgLenValidThresh_Cnt_u16	4370
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	45529
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	16646
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	18875
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	38428
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	47092
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	55883
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	21580
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	39981
k_ISDYNVOLChkSumValidThresh_Cnt_u16	58616
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	19059
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	51248
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	52925
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	48241
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	2604
k_IgnOnTimeout_mS_u16	52857
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	156.692795
k_PowerCutVehSpdLowThresh_Kph_f32	56.0443993
k_PowerCutVehSpdLowTimeout_mS_u16	5912
k_VBattMaxAAS_Volt_f32	15.6660004
k_VBattMaxBSI_Volt_f32	18.8680992
k_VBattMaxCAV_Volt_f32	28.6585999
k_VBattMaxCMM388_Volt_f32	31.9533005
k_VBattMaxCMM_Volt_f32	8.2208004
k_VBattMaxESP_Volt_f32	25.0079994
k_VBattMinAAS_Volt_f32	17.7845001
k_VBattMinBSI_Volt_f32	25.0079994
k_VBattMinCAV_Volt_f32	24.5834999
k_VBattMinCMM388_Volt_f32	1.46449995
k_VBattMinCMM_Volt_f32	26.6056004
k_VBattMinESP_Volt_f32	8.2208004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	56104
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	42467
k_VitesseVehicleBVRampValidThresh_Cnt_u16	8358
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	22992
k_VitesseVehicleBVSigValidThresh_Cnt_u16	65083
k_VitesseVehicleBVSpeedPassThresh_kph_f32	490.654907
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	35365
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	7604
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1714981632
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	97
target_SrlComInput_Per1_Batt_Volt_f32.value	17.4829006
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3968350976
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	23
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.200403377
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	698952448
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3312372480
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4047792896
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3576302336
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2568989440
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	163
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1696942848
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1631251200
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	129
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	141
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	149
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	201
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	218
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	159
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1127680768
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	63
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	97
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	105
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	151
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	174
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	175
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1368402688
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3738553088
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3156962048
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	118
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	166
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	186
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	187
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1328397056
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	166
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.428992689
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	437103
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	181.075897

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	30788		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	21951	21951	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	173.465103	173.465103	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	37873	37873	✔
CONSANGLECPK_HwDeg_M_f32	-592.838379	-592.838379 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2006148864	2006148864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	200	200	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	300	300	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4	4	✔
ElecIntTimer_mS_M_u32[1]	6	6	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	54894	54894	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	12325	12325	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	25457	25457	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	42650	42650	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1905	1905	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36051	36051	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	48504	48504	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	37873	37873	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	12325	12325	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	27240	27240	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	63119	63119	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	581380864	581380864	✔
IgnTimeOff_Sec_M_u32	334728480	334728480	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	173	173	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	698952448	698952448	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	48	48	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3312372480	3312372480	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	46	46	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4047792896	4047792896	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3576302336	3576302336	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3538774784	3538774784	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	163	163	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1696942848	1696942848	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	34	34	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1631251200	1631251200	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	159	159	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1127680768	1127680768	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1368402688	1368402688	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	88	88	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3738553088	3738553088	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	40	40	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3156962048	3156962048	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1328397056	1328397056	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	551.317383	551.317383	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	179.529694	179.529694	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	199.298004	199.298004	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	37873	37873	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	334728480	334728480	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-592.838379	-592.838379 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.320 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4006212096
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	50544
AASNodeAbsentTimer_mS_M_u32	2060116480
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	33004
ANGLEVOLANTSigValidCount_Cnt_M_u16	29351
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	53581
AngleVolantMsgTimer_mS_M_u32	4006212096
AngleVolantValidCount_Cnt_M_u16	58882
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2819793408
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4108395008
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	148410880
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3639562752
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	18163
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3014726144
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	38107
CAVNodeAbsentTimer_mS_M_u32	317555200
CDD_SrlComVehSpd_Kph_G_f32	611.833618
CMM388NTCEnableTimer_mS_M_u32	2846999040
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3326312960
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	2139
CMMNodeAbsentTimer_mS_M_u32	1276727808
CONSANGLECPKSigInvalidCount_Cnt_M_u16	29056
CONSANGLECPKSigValidCount_Cnt_M_u16	48779
CONSANGLECPK_Cnt_M_u16	36790
CONSANGLECPK_HwDeg_M_f32	146.599792
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	36790
CPKVehicleSpeedMsgTimer_mS_M_u32	2483614208
CPKVehicleSpeedValidCount_Cnt_M_u16	6622
CityParkInputConsistentCount_Cnt_M_u16	55270
CityParkInputInvalidCount_Cnt_M_u16	28971
CityParkInputMsgTimer_mS_M_u32	698952448
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3853443584
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	19796

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2179858944
ComputerRazGCTSigValidCount_Cnt_M_u16	13435
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	23367
DMDFCTCPKSigValidCount_Cnt_M_u16	5482
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	53470
DMDRELAXECPKSigValidCount_Cnt_M_u16	13337
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	46685
DateInvalidTimer_mS_M_u32	4108395008
DiagMuxOnAbsentTimer_mS_M_u32	1483452928
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3639562752
ESPNTCEnableTimer_mS_M_u32	491512320
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	48786
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	500
EffacDefaultDiagTimer_mS_M_u32[1]	600
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1100
ElecIntTimer_mS_M_u32[1]	1152
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4261614080
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	6837
EtatMTSigValidCount_Cnt_M_u16	48475
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	6002
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	22013
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	704
ISDAT4V2BSI552MsgTimer_mS_M_u32	3657257472
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	722
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	62144
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	48475
ISDATBSI3F2MsgTimer_mS_M_u32	3396973056
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	13472
ISDATBSI412MsgLenValidCount_Cnt_M_u16	11967
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0
ISDATBSI412MsgTimer_mS_M_u32	3872911872
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	63807
ISDATBSI432MsgLenValidCount_Cnt_M_u16	21110
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	5756
ISDATDIRASentFltAcc_Cnt_M_u16	9840
ISDATDIRASentTimer_mS_M_u32	2483614208
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	4164
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	58882
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	31438
ISDYN2CMMMsgTimer_mS_M_u32	485876224
ISDYNAASChkSumInvalidCount_Cnt_M_u16	8546
ISDYNAASChkSumValidCount_Cnt_M_u16	18492
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	35721
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	23110
ISDYNAASMsgLenValidCount_Cnt_M_u16	41624
ISDYNAASMsgTimeValidCount_Cnt_M_u16	8546
ISDYNAASMsgTimer_mS_M_u32	416137728
ISDYNABRChkSumInvalidCount_Cnt_M_u16	33170
ISDYNABRChkSumValidCount_Cnt_M_u16	38548
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	31081
ISDYNABRMsgCountValidCount_Cnt_M_u16	26499
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	3207
ISDYNABRMsgLenValidCount_Cnt_M_u16	24786
ISDYNABRMsgTimeValidCount_Cnt_M_u16	36790
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	46457
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	24909
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	48475
ISDYNCMM208MsgTimer_mS_M_u32	3907494400
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	46457
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	24909
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	9488

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2570142208
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	39822
ISDYNVOLChkSumValidCount_Cnt_M_u16	63257
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	2133
ISDYNVOLMsgCountValidCount_Cnt_M_u16	4344
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	46475
ISDYNVOLMsgLenValidCount_Cnt_M_u16	11637
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	2139
ISDYNVOLMsgTimer_mS_M_u32	2634678784
IgnOnTimer_mS_M_u32	1108689408
IgnTimeOff_Sec_M_u32	567132201
ManVehSpd_Kph_M_f32	617.411316
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	198
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	196
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2309992960
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	224
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2881458688
PrevISDATBSI412MsgDLCError_Cnt_M_u08	40
PrevISDATBSI412MsgRxTime_MSec_M_u32	995000832
PrevISDATBSI432MsgDLCError_Cnt_M_u08	79
PrevISDATBSI432MsgRxTime_MSec_M_u32	4020232704
PrevISDATDIRAMsgTxTime_MSec_M_u32	440566272
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	138
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3993293312
PrevISDYNAASMsgDLCError_Cnt_M_u08	80
PrevISDYNAASMsgRxTime_MSec_M_u32	1704460800
PrevISDYNABRMsgDLCError_Cnt_M_u08	127
PrevISDYNABRMsgRxTime_MSec_M_u32	860701184
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	43
PrevISDYNCMM208MsgRxTime_MSec_M_u32	871170560
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	105
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4257931776
PrevISDYNVOLMsgDLCError_Cnt_M_u08	67
PrevISDYNVOLMsgRxTime_MSec_M_u32	3480977920
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4058378752
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	322.867188
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	36180
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	42022
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	31181
VitesseVehicleBVRampValidCount_Cnt_M_u16	10591
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	44773
VitesseVehicleBVSigValidCount_Cnt_M_u16	22880
VitesseVehicleBV_Kph_M_f32	51.1990013
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	9488
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	10307
VitesseVehiculeRoues_Kph_M_f32	441.8461
k_AASNTCEnableTimeout_mS_u16	23349
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	27813
k_AASNodeTimeout_mS_u16	42790
k_ABSNodeTimeout_mS_u16	4060
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	28962
k_ANGLEVOLANTSigValidThresh_Cnt_u16	65177
k_AngleVolantInvalidThresh_Cnt_u16	54376
k_AngleVolantValidThresh_Cnt_u16	28971
k_BSI552MsgTimeout_mS_u16	42706
k_BSINTCEnableTimeout_mS_u16	23159
k_BSINodeAbsentDiag_Cnt_str.Threshold	36988
k_BSINodeAbsentDiag_Cnt_str.PStep	501
k_BSINodeAbsentDiag_Cnt_str.NStep	10273
k_BSINodeAbsentTimeout_mS_u16	42117
k_BSINodeTimeout_mS_u16	5756
k_BattOvHi_Volt_f32	18.3124008
k_BattOvLo_Volt_f32	26.4794006
k_BattUvHi_Volt_f32	21.6047993
k_BattUvLo_Volt_f32	10.1226997
k_CAVNTCEnableTimeout_mS_u16	38257
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	17129
k_CAVNodeTimeout_mS_u16	55452
k_CMM388MsgTimeout_mS_u16	2160
k_CMM388NTCEnableTimeout_mS_u16	49292
k_CMMNTCEnableTimeout_mS_u16	49162
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	46687
k_CONSANGLECPKMax_HwDeg_f32	552.94751
k_CONSANGLECPKMin_HwDeg_f32	-23.8605003
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	59408
k_CONSANGLECPKSigValidThresh_Cnt_u16	11075
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	3964
k_CPKVehicleSpeedValidThresh_Cnt_u16	53195
k_CityParkInputInvalidThresh_Cnt_u16	50792
k_CityParkInputValidThresh_Cnt_u16	55270
k_ComputerRazGCTSigValidThresh_Cnt_u16	44168
k_CptTemporelSigValidThresh_Cnt_u16	39158
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	20359
k_DMDFCTCPKSigValidThresh_Cnt_u16	58322
k_DMDFCTCPKValidCount_Cnt_u16	50875
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	31438
k_DMDRELAXECPKSigValidThresh_Cnt_u16	39985
k_DMDRelaxeConsistentThresh_Cnt_u16	52871
k_DateValidThresh_Cnt_u16	704
k_DefaultVehSpd_Kph_f32	34.9572983
k_DiagMuxOnAbsentTimeout_mS_u16	46460
k_EMNodeTimeout_mS_u16	23485
k_ESPNTCEnableTimeout_mS_u16	65015
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	56615
k_EtatMTSigInvalidThresh_Cnt_u16	32065
k_EtatMTSigValidThresh_Cnt_u16	18307
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	57479
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	62477
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	63071
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	42447
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	51581
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	60292
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	62908
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	41651
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	10787
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	60410
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	15928
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	37010
k_ISDATDIRASentDiag_Cnt_str.Threshold	6549

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	63930
k_ISDATDIRASentDiag_Cnt_str.NStep	24627
k_ISDATDIRASentTimeout_mS_u16	9902
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	41575
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	53581
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	2211
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	17554
k_ISDYNAASChkSumValidThresh_Cnt_u16	39316
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	48233
k_ISDYNAASMsgCountValidThresh_Cnt_u16	60035
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	57206
k_ISDYNAASMsgLenValidThresh_Cnt_u16	28938
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	33633
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	24981
k_ISDYNABRChkSumValidThresh_Cnt_u16	1120
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	35315
k_ISDYNABRMsgCountValidThresh_Cnt_u16	750
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	2907
k_ISDYNABRMsgLenValidThresh_Cnt_u16	402
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	9981
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	63288
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	29785
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	19637
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	50156
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	62887
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	18531
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	50435
k_ISDYNVOLChkSumValidThresh_Cnt_u16	21346
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	6511
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	22392
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	2257
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	18551
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	57222
k_IgnOnTimeout_mS_u16	24095
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	248.713699
k_PowerCutVehSpdLowThresh_Kph_f32	14.6590004
k_PowerCutVehSpdLowTimeout_mS_u16	25153
k_VBattMaxAAS_Volt_f32	6.6645999
k_VBattMaxBSI_Volt_f32	22.3885002
k_VBattMaxCAV_Volt_f32	15.8656998
k_VBattMaxCMM388_Volt_f32	27.1865997
k_VBattMaxCMM_Volt_f32	21.9104004
k_VBattMaxESP_Volt_f32	11.4773998
k_VBattMinAAS_Volt_f32	32
k_VBattMinBSI_Volt_f32	11.4773998
k_VBattMinCAV_Volt_f32	20.9687996
k_VBattMinCMM388_Volt_f32	24.9057999
k_VBattMinCMM_Volt_f32	23.5713005
k_VBattMinESP_Volt_f32	21.9104004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	1297
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	52640
k_VitesseVehicleBVRampValidThresh_Cnt_u16	52053
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	31257
k_VitesseVehicleBVSigValidThresh_Cnt_u16	30103
k_VitesseVehicleBVSpeedPassThresh_kph_f32	256.804108
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	22491
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	5613
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	4108395008
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65036
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	163190528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	105
target_SrlComInput_Per1_Batt_Volt_f32.value	28.2127991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2092044800
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	146
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.823314965
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3037676032
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2151571968
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	171
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3678241280
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	193
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1309450752
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1621869056
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2602230272
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2237268480
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	34
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	52
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	116
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	172
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	186
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	228
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2011537920
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	35
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	76
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	90
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	140
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	142
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	170
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2572829184
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2416534016
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	24
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3599270400
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	88
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	151
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	154
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3401683456
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1646
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.165346399
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	860914
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	139.814499
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	51582

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	163190528	163190528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	163190528	163190528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	163190528	163190528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	36988	36988	✔
BSINodeAbsentTimer_mS_M_u32	163190528	163190528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CDD_SrlComVehSpd_Kph_G_f32	617.411316	617.411316	✔
CMM388NTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	36790	36790	✔
CONSANGLECPK_HwDeg_M_f32	146.599792	146.599792 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	163190528	163190528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	163190528	163190528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	163190528	163190528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	163190528	163190528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	163190528	163190528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	163190528	163190528	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	163190528	163190528	✔
ESPNTCEnableTimer_mS_M_u32	163190528	163190528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	500	500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	600	600	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1100	1100	✔
ElecIntTimer_mS_M_u32[1]	1152	1152	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	163190528	163190528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	704	704	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	48475	48475	✔
ISDATBSI3F2MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	5756	5756	✔
ISDATBSI432MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	6549	6549	✔
ISDATDIRASentTimer_mS_M_u32	163190528	163190528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	31438	31438	✔
ISDYN2CMMMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	8546	8546	✔
ISDYNAASMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	36790	36790	✔
ISDYNABRMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	48475	48475	✔
ISDYNCMM208MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	9488	9488	✔
ISDYNCMM388MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	2139	2139	✔
ISDYNVOLMsgTimer_mS_M_u32	163190528	163190528	✔
IgnOnTimer_mS_M_u32	1108689408	1108689408	✔
IgnTimeOff_Sec_M_u32	567132201	567132201	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	242	242	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3037676032	3037676032	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	233	233	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2151571968	2151571968	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	171	171	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3678241280	3678241280	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	193	193	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1309450752	1309450752	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	440566272	440566272	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	8	8	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2602230272	2602230272	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2237268480	2237268480	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2011537920	2011537920	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	9	9	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2572829184	2572829184	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2416534016	2416534016	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	24	24	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3599270400	3599270400	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3401683456	3401683456	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	322.867188	322.867188	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	51.1990013	51.1990013	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	441.8461	441.8461	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	36790	36790	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	567132201	567132201	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	146.599792	146.599792 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.321 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3314085120
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	64405
AASNodeAbsentTimer_mS_M_u32	2437291264
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	23327
ANGLEVOLANTSigValidCount_Cnt_M_u16	48048
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	35838
AngleVolantMsgTimer_mS_M_u32	3314085120
AngleVolantValidCount_Cnt_M_u16	2655
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3631144192
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1275288832
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2044529920
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3566783744
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	58634
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2069073152
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	65493
CAVNodeAbsentTimer_mS_M_u32	459160832
CDD_SrlComVehSpd_Kph_G_f32	333.885895
CMM388NTCEnableTimer_mS_M_u32	3088153856
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3646700800
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	50195
CMMNodeAbsentTimer_mS_M_u32	2736442624
CONSANGLECPKSigInvalidCount_Cnt_M_u16	34916
CONSANGLECPKSigValidCount_Cnt_M_u16	5893
CONSANGLECPK_Cnt_M_u16	3972
CONSANGLECPK_HwDeg_M_f32	764.362183
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	3972
CPKVehicleSpeedMsgTimer_mS_M_u32	2446060800
CPKVehicleSpeedValidCount_Cnt_M_u16	5234
CityParkInputConsistentCount_Cnt_M_u16	50355
CityParkInputInvalidCount_Cnt_M_u16	40419
CityParkInputMsgTimer_mS_M_u32	3037676032
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3768196352
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	62441

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1885125888
ComputerRazGCTSigValidCount_Cnt_M_u16	17140
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	20367
DMDFCTCPKSigValidCount_Cnt_M_u16	63207
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	45897
DMDRELAXECPKSigValidCount_Cnt_M_u16	48986
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	28109
DateInvalidTimer_mS_M_u32	1275288832
DiagMuxOnAbsentTimer_mS_M_u32	1067691264
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3566783744
ESPNTCEnableTimer_mS_M_u32	3988987136
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	50992
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	850
EffacDefaultDiagTimer_mS_M_u32[1]	1050
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2050
ElecIntTimer_mS_M_u32[1]	6072
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1683852544
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	33287
EtatMTSigValidCount_Cnt_M_u16	32724
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	56974
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	39087
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	1765
ISDAT4V2BSI552MsgTimer_mS_M_u32	2305740032
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	30511
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	44324
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	32724
ISDATBSI3F2MsgTimer_mS_M_u32	2709105920
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	60100
ISDATBSI412MsgLenValidCount_Cnt_M_u16	49705
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	65535
ISDATBSI412MsgTimer_mS_M_u32	2506026240
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	33127
ISDATBSI432MsgLenValidCount_Cnt_M_u16	39812
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	16114
ISDATDIRASentFltAcc_Cnt_M_u16	57110
ISDATDIRASentTimer_mS_M_u32	2446060800
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	17882
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	2655
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52474
ISDYN2CMMMsgTimer_mS_M_u32	382016768
ISDYNAASChkSumInvalidCount_Cnt_M_u16	12223
ISDYNAASChkSumValidCount_Cnt_M_u16	28912
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	62922
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	7060
ISDYNAASMsgLenValidCount_Cnt_M_u16	55389
ISDYNAASMsgTimeValidCount_Cnt_M_u16	12223
ISDYNAASMsgTimer_mS_M_u32	3669851392
ISDYNABRChkSumInvalidCount_Cnt_M_u16	9903
ISDYNABRChkSumValidCount_Cnt_M_u16	15720
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	938
ISDYNABRMsgCountValidCount_Cnt_M_u16	61211
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	37711
ISDYNABRMsgLenValidCount_Cnt_M_u16	3120
ISDYNABRMsgTimeValidCount_Cnt_M_u16	3972
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	26665
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	15982
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	32724
ISDYNCMM208MsgTimer_mS_M_u32	2851069184
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	26665
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	15982
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	1333

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1200815360
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	49722
ISDYNVOLChkSumValidCount_Cnt_M_u16	9563
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	101
ISDYNVOLMsgCountValidCount_Cnt_M_u16	48189
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	1605
ISDYNVOLMsgLenValidCount_Cnt_M_u16	37957
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	50195
ISDYNVOLMsgTimer_mS_M_u32	2399714560
IgnOnTimer_mS_M_u32	3706125568
IgnTimeOff_Sec_M_u32	1961527376
ManVehSpd_Kph_M_f32	398.554413
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	199
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	234
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3151473920
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	238
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3978824960
PrevISDATBSI412MsgDLCError_Cnt_M_u08	66
PrevISDATBSI412MsgRxTime_MSec_M_u32	1715158272
PrevISDATBSI432MsgDLCError_Cnt_M_u08	59
PrevISDATBSI432MsgRxTime_MSec_M_u32	3334937856
PrevISDATDIRAMsgTxTime_MSec_M_u32	2573155584
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	85
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3411561728
PrevISDYNAASMsgDLCError_Cnt_M_u08	241
PrevISDYNAASMsgRxTime_MSec_M_u32	3982408960
PrevISDYNABRMsgDLCError_Cnt_M_u08	75
PrevISDYNABRMsgRxTime_MSec_M_u32	3913219328
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	231
PrevISDYNCMM208MsgRxTime_MSec_M_u32	375373056
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	181
PrevISDYNCMM388MsgRxTime_MSec_M_u32	138812672
PrevISDYNVOLMsgDLCError_Cnt_M_u08	201
PrevISDYNVOLMsgRxTime_MSec_M_u32	2645835008
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	741666048
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	77.828598
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	14954
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	35763
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	39167
VitesseVehicleBVRampValidCount_Cnt_M_u16	8200
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	62772
VitesseVehicleBVSigValidCount_Cnt_M_u16	11141
VitesseVehicleBV_Kph_M_f32	459.54599
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	1333
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	4445
VitesseVehiculeRoues_Kph_M_f32	563.109375
k_AASNTCEnableTimeout_mS_u16	26887
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	49782
k_AASNodeTimeout_mS_u16	33459
k_ABSNodeTimeout_mS_u16	50640
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	26046
k_ANGLEVOLANTSigValidThresh_Cnt_u16	58139
k_AngleVolantInvalidThresh_Cnt_u16	23982
k_AngleVolantValidThresh_Cnt_u16	40419
k_BSI552MsgTimeout_mS_u16	37296
k_BSINTCEnableTimeout_mS_u16	15807
k_BSINodeAbsentDiag_Cnt_str.Threshold	64160
k_BSINodeAbsentDiag_Cnt_str.PStep	64630
k_BSINodeAbsentDiag_Cnt_str.NStep	45105
k_BSINodeAbsentTimeout_mS_u16	62038
k_BSINodeTimeout_mS_u16	16114
k_BattOvHi_Volt_f32	15.2872
k_BattOvLo_Volt_f32	4.84619999
k_BattUvHi_Volt_f32	10.0437002
k_BattUvLo_Volt_f32	28.9699993
k_CAVNTCEnableTimeout_mS_u16	51473
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	44459
k_CAVNodeTimeout_mS_u16	49936
k_CMM388MsgTimeout_mS_u16	12949
k_CMM388NTCEnableTimeout_mS_u16	31297
k_CMMNTCEnableTimeout_mS_u16	8071
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	55049
k_CONSANGLECPKMax_HwDeg_f32	122.513
k_CONSANGLECPKMin_HwDeg_f32	-712.583496
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	48181
k_CONSANGLECPKSigValidThresh_Cnt_u16	2141
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	8625
k_CPKVehicleSpeedValidThresh_Cnt_u16	34115
k_CityParkInputInvalidThresh_Cnt_u16	12333
k_CityParkInputValidThresh_Cnt_u16	50355
k_ComputerRazGCTSigValidThresh_Cnt_u16	53773
k_CptTemporelSigValidThresh_Cnt_u16	4738
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	51791
k_DMDFCTCPKSigValidThresh_Cnt_u16	33584
k_DMDFCTCPKValidCount_Cnt_u16	34226
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	52474
k_DMDRELAXECPKSigValidThresh_Cnt_u16	16018
k_DMDRelaxeConsistentThresh_Cnt_u16	32656
k_DateValidThresh_Cnt_u16	1765
k_DefaultVehSpd_Kph_f32	61.5294991
k_DiagMuxOnAbsentTimeout_mS_u16	13874
k_EMNodeTimeout_mS_u16	64941
k_ESPNTCEnableTimeout_mS_u16	13441
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	33457
k_EtatMTSigInvalidThresh_Cnt_u16	44962
k_EtatMTSigValidThresh_Cnt_u16	42651
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	39568
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	50620
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	36168
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	49720
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	23789
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	22040
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	49136
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	57037
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	32443
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	2744
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	22973
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	28654
k_ISDATDIRASentDiag_Cnt_str.Threshold	1170

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	4955
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	42843
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	52847
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	35838
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	50301
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	56751
k_ISDYNAASChkSumValidThresh_Cnt_u16	13416
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	15018
k_ISDYNAASMsgCountValidThresh_Cnt_u16	26139
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	40195
k_ISDYNAASMsgLenValidThresh_Cnt_u16	46343
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	29891
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	19493
k_ISDYNABRChkSumValidThresh_Cnt_u16	55686
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	7178
k_ISDYNABRMsgCountValidThresh_Cnt_u16	59099
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	47891
k_ISDYNABRMsgLenValidThresh_Cnt_u16	65072
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	30382
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	36030
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	20377
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	36358
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	37407
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	12976
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	63547
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	34203
k_ISDYNVOLChkSumValidThresh_Cnt_u16	41024
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	27289
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	35516
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	10163
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	20096
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	2195
k_IgnOnTimeout_mS_u16	10823
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	74.760498
k_PowerCutVehSpdLowThresh_Kph_f32	80.9244995
k_PowerCutVehSpdLowTimeout_mS_u16	33763
k_VBattMaxAAS_Volt_f32	4.80779982
k_VBattMaxBSI_Volt_f32	13.6459999
k_VBattMaxCAV_Volt_f32	30.6686001
k_VBattMaxCMM388_Volt_f32	32
k_VBattMaxCMM_Volt_f32	13.3399
k_VBattMaxESP_Volt_f32	23.8528004
k_VBattMinAAS_Volt_f32	29.4815998
k_VBattMinBSI_Volt_f32	23.8528004
k_VBattMinCAV_Volt_f32	3.72550011
k_VBattMinCMM388_Volt_f32	23.1742992
k_VBattMinCMM_Volt_f32	2.91100001
k_VBattMinESP_Volt_f32	13.3399
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	52849
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	64133
k_VitesseVehicleBVRampValidThresh_Cnt_u16	46949
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	40027
k_VitesseVehicleBVSigValidThresh_Cnt_u16	61344
k_VitesseVehicleBVSpeedPassThresh_kph_f32	363.828796
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	46805
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	4702
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1275288832
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	181
target_SrlComInput_Per1_Batt_Volt_f32.value	13.5368004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1683000576
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	93
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.889307737
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3958963456
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2934676736
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	248
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	40779008
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1317068032
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4213406976
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1884691712
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	370720000
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	118
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	119
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	167
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1962269952
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	37
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	130
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	194
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	236
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	128
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	722992384
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	191
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1804246272
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	155
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4237114624
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	50
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	155
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	404884736
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1853
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0878945664
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1000743
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	252.707993
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	44524

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	35838	35838	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	3972	3972	✔
CONSANGLECPK_HwDeg_M_f32	764.362183	764.362183 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	3972	3972	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2446060800	2446060800	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	5234	5234	✔
CityParkInputConsistentCount_Cnt_M_u16	50355	50355	✔
CityParkInputInvalidCount_Cnt_M_u16	40419	40419	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	850	850	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1050	1050	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3251510528	3251510528	✔
ElecIntTimer_mS_M_u32[1]	6072	6072	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1170	1170	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	3251510528	3251510528	✔
IgnTimeOff_Sec_M_u32	1961527376	1961527376	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	216	216	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3958963456	3958963456	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	121	121	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2934676736	2934676736	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	248	248	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	40779008	40779008	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	186	186	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1317068032	1317068032	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2573155584	2573155584	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	174	174	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1884691712	1884691712	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	174	174	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	370720000	370720000	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	63	63	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1962269952	1962269952	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	128	128	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	722992384	722992384	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	191	191	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1804246272	1804246272	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	155	155	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4237114624	4237114624	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	404884736	404884736	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	77.828598	77.828598	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	459.54599	459.54599	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	563.109375	563.109375	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	3972	3972	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1961527376	1961527376	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	764.362183	764.362183 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.322 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	184024064
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	15058
AASNodeAbsentTimer_mS_M_u32	1484811264
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	26162
ANGLEVOLANTSigValidCount_Cnt_M_u16	41792
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	28055
AngleVolantMsgTimer_mS_M_u32	184024064
AngleVolantValidCount_Cnt_M_u16	48373
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	369503232
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2907220992
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3866860544
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1967676416
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	13425
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3692567552
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	54930
CAVNodeAbsentTimer_mS_M_u32	3266841600
CDD_SrlComVehSpd_Kph_G_f32	410.558502
CMM388NTCEnableTimer_mS_M_u32	3382594560
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	12454912
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	11672
CMMNodeAbsentTimer_mS_M_u32	2445433856
CONSANGLECPKSigInvalidCount_Cnt_M_u16	57700
CONSANGLECPKSigValidCount_Cnt_M_u16	54338
CONSANGLECPK_Cnt_M_u16	42693
CONSANGLECPK_HwDeg_M_f32	451.781311
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	42693
CPKVehicleSpeedMsgTimer_mS_M_u32	1915681792
CPKVehicleSpeedValidCount_Cnt_M_u16	19908

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	56825
CityParkInputInvalidCount_Cnt_M_u16	25448
CityParkInputMsgTimer_mS_M_u32	3958963456
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3129240576
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	41430
ComputerRazGCTSigInvalidTimer_mS_M_u32	3720121344
ComputerRazGCTSigValidCount_Cnt_M_u16	42806
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	65124
DMDFCTCPKSigValidCount_Cnt_M_u16	34586
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	34228
DMDRELAXECPKSigValidCount_Cnt_M_u16	49218
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	5417
DateInvalidTimer_mS_M_u32	2907220992
DiagMuxOnAbsentTimer_mS_M_u32	2007481344
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1967676416
ESPNTCEnableTimer_mS_M_u32	1997106176
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	45826
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1100
EffacDefaultDiagTimer_mS_M_u32[1]	1150
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	9900
ElecIntTimer_mS_M_u32[1]	11002
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3371834368
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	5307
EtatMTSigValidCount_Cnt_M_u16	27157
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1766
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	30532
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	53024
ISDAT4V2BSI552MsgTimer_mS_M_u32	784751616
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	11459
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	31141
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	27157
ISDATBSI3F2MsgTimer_mS_M_u32	707116032
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	46852
ISDATBSI412MsgLenValidCount_Cnt_M_u16	57238
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	17578
ISDATBSI412MsgTimer_mS_M_u32	1937112064
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	17820
ISDATBSI432MsgLenValidCount_Cnt_M_u16	34310
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	52539
ISDATDIRASentFltAcc_Cnt_M_u16	31951
ISDATDIRASentTimer_mS_M_u32	1915681792
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	56259
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	48373
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	61987
ISDYN2CMMMsgTimer_mS_M_u32	2214816768
ISDYNAASChkSumInvalidCount_Cnt_M_u16	50772
ISDYNAASChkSumValidCount_Cnt_M_u16	57730
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	26292
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	16213
ISDYNAASMsgLenValidCount_Cnt_M_u16	18363
ISDYNAASMsgTimeValidCount_Cnt_M_u16	50772
ISDYNAASMsgTimer_mS_M_u32	295324672
ISDYNABRChkSumInvalidCount_Cnt_M_u16	39683
ISDYNABRChkSumValidCount_Cnt_M_u16	21913
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	46739
ISDYNABRMsgCountValidCount_Cnt_M_u16	54017
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	11427
ISDYNABRMsgLenValidCount_Cnt_M_u16	24769
ISDYNABRMsgTimeValidCount_Cnt_M_u16	42693

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	65287
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	61174
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	27157
ISDYNCMM208MsgTimer_mS_M_u32	3850578944
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	65287
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	61174
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	42099
ISDYNCMM388MsgTimer_mS_M_u32	18467840
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	3042
ISDYNVOLChkSumValidCount_Cnt_M_u16	33088
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	50146
ISDYNVOLMsgCountValidCount_Cnt_M_u16	3864
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	35267
ISDYNVOLMsgLenValidCount_Cnt_M_u16	65153
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	11672
ISDYNVOLMsgTimer_mS_M_u32	834178048
IgnOnTimer_mS_M_u32	2434649088
IgnTimeOff_Sec_M_u32	2452427840
ManVehSpd_Kph_M_f32	628.688599
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	200
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	169
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3540761600
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	151
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2023398400
PrevISDATBSI412MsgDLCError_Cnt_M_u08	18
PrevISDATBSI412MsgRxTime_MSec_M_u32	2518748160
PrevISDATBSI432MsgDLCError_Cnt_M_u08	223
PrevISDATBSI432MsgRxTime_MSec_M_u32	4227689472
PrevISDATDIRAMsgTxTime_MSec_M_u32	2360675328
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	51
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4010400768
PrevISDYNAASMsgDLCError_Cnt_M_u08	149
PrevISDYNAASMsgRxTime_MSec_M_u32	4004940800
PrevISDYNABRMsgDLCError_Cnt_M_u08	204
PrevISDYNABRMsgRxTime_MSec_M_u32	3423980544
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	25
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3081997312
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	24
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4085279744
PrevISDYNVOLMsgDLCError_Cnt_M_u08	241
PrevISDYNVOLMsgRxTime_MSec_M_u32	330697728
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2264136704
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	609.560608
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	47827
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1465
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	13076
VitesseVehicleBVRampValidCount_Cnt_M_u16	56506
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	11251

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	59329
VitesseVehicleBV_Kph_M_f32	107.9291
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	42099
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	16057
VitesseVehiculeRoues_Kph_M_f32	565.10553
k_AASNTCEnableTimeout_mS_u16	26172
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	45232
k_AASNodeTimeout_mS_u16	8377
k_ABSNodeTimeout_mS_u16	57249
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	46231
k_ANGLEVOLANTSigValidThresh_Cnt_u16	52033
k_AngleVolantInvalidThresh_Cnt_u16	26504
k_AngleVolantValidThresh_Cnt_u16	25448
k_BSI552MsgTimeout_mS_u16	51648
k_BSINTCEnableTimeout_mS_u16	28820
k_BSINodeAbsentDiag_Cnt_str.Threshold	56609
k_BSINodeAbsentDiag_Cnt_str.PStep	54494
k_BSINodeAbsentDiag_Cnt_str.NStep	18159
k_BSINodeAbsentTimeout_mS_u16	39567
k_BSINodeTimeout_mS_u16	52539
k_BattOvHi_Volt_f32	5.65899992
k_BattOvLo_Volt_f32	27.3015995
k_BattUvHi_Volt_f32	7.48799992
k_BattUvLo_Volt_f32	29.7691994
k_CAVNTCEnableTimeout_mS_u16	6622
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	42256
k_CAVNodeTimeout_mS_u16	57696
k_CMM388MsgTimeout_mS_u16	38354
k_CMM388NTCEnableTimeout_mS_u16	28366
k_CMMNTCEnableTimeout_mS_u16	37819
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	40373
k_CONSANGLECPKMax_HwDeg_f32	589.104492
k_CONSANGLECPKMin_HwDeg_f32	-127.044403
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	32627
k_CONSANGLECPKSigValidThresh_Cnt_u16	22969
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	48063
k_CPKVehicleSpeedValidThresh_Cnt_u16	41863
k_CityParkInputInvalidThresh_Cnt_u16	63113
k_CityParkInputValidThresh_Cnt_u16	56825
k_ComputerRazGCTSigValidThresh_Cnt_u16	5161
k_CptTemporelSigValidThresh_Cnt_u16	16779
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	34723
k_DMDFCTCPKSigValidThresh_Cnt_u16	64449
k_DMDFCTCPKValidCount_Cnt_u16	62073
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	61987
k_DMDRELAXECPKSigValidThresh_Cnt_u16	7193
k_DMDRelaxeConsistentThresh_Cnt_u16	53535
k_DateValidThresh_Cnt_u16	53024
k_DefaultVehSpd_Kph_f32	101.484802
k_DiagMuxOnAbsentTimeout_mS_u16	27323
k_EMNodeTimeout_mS_u16	58761
k_ESPNTCEnableTimeout_mS_u16	59534
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	15037
k_EtatMTSigInvalidThresh_Cnt_u16	35882
k_EtatMTSigValidThresh_Cnt_u16	42496
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	36130
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	55899
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	6202
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	44968
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	52810
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	50440

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	60929
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	8235
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	40352
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	34089
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	50907
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	23688
k_ISDATDIRASentDiag_Cnt_str.Threshold	47720
k_ISDATDIRASentDiag_Cnt_str.PStep	17950
k_ISDATDIRASentDiag_Cnt_str.NStep	21543
k_ISDATDIRASentTimeout_mS_u16	51455
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	34053
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	28055
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10394
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	30211
k_ISDYNAASChkSumValidThresh_Cnt_u16	28825
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	4499
k_ISDYNAASMsgCountValidThresh_Cnt_u16	28161
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	34823
k_ISDYNAASMsgLenValidThresh_Cnt_u16	55741
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	46665
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	55841
k_ISDYNABRChkSumValidThresh_Cnt_u16	53439
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	36721
k_ISDYNABRMsgCountValidThresh_Cnt_u16	36287
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	18584
k_ISDYNABRMsgLenValidThresh_Cnt_u16	3586
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	59974
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	5079
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7301
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	2752
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	49458
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	15936
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	46176
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	639
k_ISDYNVOLChkSumValidThresh_Cnt_u16	24913
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	44231
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	48541
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	54199
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	44561
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	534
k_IgnOnTimeout_mS_u16	50299
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	146.291901
k_PowerCutVehSpdLowThresh_Kph_f32	167.799698
k_PowerCutVehSpdLowTimeout_mS_u16	34216
k_VBattMaxAAS_Volt_f32	12.3985004
k_VBattMaxBSI_Volt_f32	15.8546
k_VBattMaxCAV_Volt_f32	5.42449999
k_VBattMaxCMM388_Volt_f32	27.0041008
k_VBattMaxCMM_Volt_f32	21.9936008
k_VBattMaxESP_Volt_f32	19.8132992
k_VBattMinAAS_Volt_f32	28.9659004
k_VBattMinBSI_Volt_f32	19.8132992
k_VBattMinCAV_Volt_f32	22.1550999
k_VBattMinCMM388_Volt_f32	2.02940011
k_VBattMinCMM_Volt_f32	3.61929989
k_VBattMinESP_Volt_f32	21.9936008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	3327
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	63361
k_VitesseVehicleBVRampValidThresh_Cnt_u16	40674
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	7232
k_VitesseVehicleBVSigValidThresh_Cnt_u16	20786
k_VitesseVehicleBVSpeedPassThresh_kph_f32	144.466797
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	45458
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	56760
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2907220992
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	24
target_SrlComInput_Per1_Batt_Volt_f32.value	19.0238991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1428233216
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	186
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.560772836
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	736611328
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1972366336
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1300761600
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2077240320
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3362278400
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	176
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4216351744
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	97
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3699936256
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	9
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	47
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	151
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	183
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	234
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	236
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	477178880
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	32
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	46
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	166
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	202
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	184
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2861222912
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2075323392
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2603289600
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	84
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	188
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	203
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1605147648
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1665
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.001538435
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	218012
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	58.6994019
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	59469

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	56609	56609	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	628.688599	628.688599	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	42693	42693	✔
CONSANGLECPK_HwDeg_M_f32	451.781311	451.781311 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1713429248	1713429248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	1100	1100	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1150	1150	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	9900	9900	✔
ElecIntTimer_mS_M_u32[1]	11002	11002	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	53024	53024	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	27157	27157	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	17578	17578	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	52539	52539	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	47720	47720	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	61987	61987	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	50772	50772	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	42693	42693	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	27157	27157	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	42099	42099	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	11672	11672	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	2434649088	2434649088	✔
IgnTimeOff_Sec_M_u32	2452427840	2452427840	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	117	117	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	736611328	736611328	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	3	3	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1972366336	1972366336	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	59	59	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1300761600	1300761600	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	229	229	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2077240320	2077240320	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2360675328	2360675328	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	176	176	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4216351744	4216351744	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	97	97	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3699936256	3699936256	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	108	108	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	477178880	477178880	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	184	184	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2861222912	2861222912	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2075323392	2075323392	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	141	141	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2603289600	2603289600	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1605147648	1605147648	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	609.560608	609.560608	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	107.9291	107.9291	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	565.10553	565.10553	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	42693	42693	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2452427840	2452427840	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	451.781311	451.781311 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	628.688599	628.688599	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.323 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2376519424
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	34839
AASNodeAbsentTimer_mS_M_u32	2462940928
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	10229
ANGLEVOLANTSigValidCount_Cnt_M_u16	21643
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	17352
AngleVolantMsgTimer_mS_M_u32	2376519424
AngleVolantValidCount_Cnt_M_u16	63021
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2705080064
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	91537152
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	295431936
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2285219584
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	31032
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1120300800
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	47960
CAVNodeAbsentTimer_mS_M_u32	983998208
CDD_SrlComVehSpd_Kph_G_f32	277.926208
CMM388NTCEnableTimer_mS_M_u32	2398347008
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	412393216
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	51973
CMMNodeAbsentTimer_mS_M_u32	2596777728
CONSANGLECPKSigInvalidCount_Cnt_M_u16	44384
CONSANGLECPKSigValidCount_Cnt_M_u16	63622
CONSANGLECPK_Cnt_M_u16	19709
CONSANGLECPK_HwDeg_M_f32	-598.407227
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	19709
CPKVehicleSpeedMsgTimer_mS_M_u32	4093759232
CPKVehicleSpeedValidCount_Cnt_M_u16	22186
CityParkInputConsistentCount_Cnt_M_u16	41761
CityParkInputInvalidCount_Cnt_M_u16	57300
CityParkInputMsgTimer_mS_M_u32	736611328
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2093055744
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	25355

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2610503424
ComputerRazGCTSigValidCount_Cnt_M_u16	31594
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	65248
DMDFCTCPKSigValidCount_Cnt_M_u16	59518
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	20847
DMDRELAXECPKSigValidCount_Cnt_M_u16	34181
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	26129
DateInvalidTimer_mS_M_u32	91537152
DiagMuxOnAbsentTimer_mS_M_u32	3063385856
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2285219584
ESPNTCEnableTimer_mS_M_u32	2603777792
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	36488
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	2050
EffacDefaultDiagTimer_mS_M_u32[1]	6070
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6454
ElecIntTimer_mS_M_u32[1]	8259
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2216718080
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	45724
EtatMTSigValidCount_Cnt_M_u16	50766
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	50394
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	38784
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	43116
ISDAT4V2BSI552MsgTimer_mS_M_u32	3552292608
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	33794
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	53533
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	50766
ISDATBSI3F2MsgTimer_mS_M_u32	387813120
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	13890
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	45724
ISDATBSI412MsgTimer_mS_M_u32	3425488640
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	37625
ISDATBSI432MsgLenValidCount_Cnt_M_u16	9596
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	47965
ISDATDIRASentFltAcc_Cnt_M_u16	64673
ISDATDIRASentTimer_mS_M_u32	4093759232
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	9731
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	63021
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	57251
ISDYN2CMMMsgTimer_mS_M_u32	3695476480
ISDYNAASChkSumInvalidCount_Cnt_M_u16	28049
ISDYNAASChkSumValidCount_Cnt_M_u16	32711
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	46320
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	19727
ISDYNAASMsgLenValidCount_Cnt_M_u16	30621
ISDYNAASMsgTimeValidCount_Cnt_M_u16	28049
ISDYNAASMsgTimer_mS_M_u32	2801786624
ISDYNABRChkSumInvalidCount_Cnt_M_u16	49924
ISDYNABRChkSumValidCount_Cnt_M_u16	38658
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	22740
ISDYNABRMsgCountValidCount_Cnt_M_u16	26442
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	34723
ISDYNABRMsgLenValidCount_Cnt_M_u16	3849
ISDYNABRMsgTimeValidCount_Cnt_M_u16	19709
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	56744
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	46492
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	50766
ISDYNCMM208MsgTimer_mS_M_u32	1724202752
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	56744
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	46492
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	47027

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	914448128
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	42470
ISDYNVOLChkSumValidCount_Cnt_M_u16	27020
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	9830
ISDYNVOLMsgCountValidCount_Cnt_M_u16	51332
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	20037
ISDYNVOLMsgLenValidCount_Cnt_M_u16	37835
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	51973
ISDYNVOLMsgTimer_mS_M_u32	2409963264
IgnOnTimer_mS_M_u32	2524274432
IgnTimeOff_Sec_M_u32	1887793480
ManVehSpd_Kph_M_f32	356.149902
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	201
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	141
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	879464192
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	207
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2537484032
PrevISDATBSI412MsgDLCError_Cnt_M_u08	246
PrevISDATBSI412MsgRxTime_MSec_M_u32	2758516480
PrevISDATBSI432MsgDLCError_Cnt_M_u08	107
PrevISDATBSI432MsgRxTime_MSec_M_u32	3696656128
PrevISDATDIRAMsgTxTime_MSec_M_u32	279944960
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	137
PrevISDYN2CMMMsgRxTime_MSec_M_u32	15806208
PrevISDYNAASMsgDLCError_Cnt_M_u08	193
PrevISDYNAASMsgRxTime_MSec_M_u32	3500875520
PrevISDYNABRMsgDLCError_Cnt_M_u08	77
PrevISDYNABRMsgRxTime_MSec_M_u32	3314376448
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	5
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2847153920
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	203
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3251470080
PrevISDYNVOLMsgDLCError_Cnt_M_u08	253
PrevISDYNVOLMsgRxTime_MSec_M_u32	3215761152
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	162713344
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	75.7492981
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	21141
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	46499
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	11730
VitesseVehicleBVRampValidCount_Cnt_M_u16	29856
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	6834
VitesseVehicleBVSigValidCount_Cnt_M_u16	51976
VitesseVehicleBV_Kph_M_f32	306.421204
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	47027
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	44194
VitesseVehiculeRoues_Kph_M_f32	569.33252
k_AASNTCEnableTimeout_mS_u16	43672
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	50940
k_AASNodeTimeout_mS_u16	25763
k_ABSNodeTimeout_mS_u16	36649
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	61960
k_ANGLEVOLANTSigValidThresh_Cnt_u16	459
k_AngleVolantInvalidThresh_Cnt_u16	2294
k_AngleVolantValidThresh_Cnt_u16	57300
k_BSI552MsgTimeout_mS_u16	59277
k_BSINTCEnableTimeout_mS_u16	61969
k_BSINodeAbsentDiag_Cnt_str.Threshold	33499
k_BSINodeAbsentDiag_Cnt_str.PStep	41956
k_BSINodeAbsentDiag_Cnt_str.NStep	42480
k_BSINodeAbsentTimeout_mS_u16	40160
k_BSINodeTimeout_mS_u16	47965
k_BattOvHi_Volt_f32	15.4986
k_BattOvLo_Volt_f32	12.1113005
k_BattUvHi_Volt_f32	19.2157993
k_BattUvLo_Volt_f32	7.69189978
k_CAVNTCEnableTimeout_mS_u16	5234
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	51166
k_CAVNodeTimeout_mS_u16	40300
k_CMM388MsgTimeout_mS_u16	30487
k_CMM388NTCEnableTimeout_mS_u16	56355
k_CMMNTCEnableTimeout_mS_u16	12058
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	32686
k_CONSANGLECPKMax_HwDeg_f32	638.403503
k_CONSANGLECPKMin_HwDeg_f32	-28.8344994
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	9907
k_CONSANGLECPKSigValidThresh_Cnt_u16	23458
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	11153
k_CPKVehicleSpeedValidThresh_Cnt_u16	15545
k_CityParkInputInvalidThresh_Cnt_u16	18546
k_CityParkInputValidThresh_Cnt_u16	41761
k_ComputerRazGCTSigValidThresh_Cnt_u16	58832
k_CptTemporelSigValidThresh_Cnt_u16	37227
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	30371
k_DMDFCTCPKSigValidThresh_Cnt_u16	15881
k_DMDFCTCPKValidCount_Cnt_u16	24352
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	57251
k_DMDRELAXECPKSigValidThresh_Cnt_u16	58753
k_DMDRelaxeConsistentThresh_Cnt_u16	24175
k_DateValidThresh_Cnt_u16	43116
k_DefaultVehSpd_Kph_f32	54.6032982
k_DiagMuxOnAbsentTimeout_mS_u16	22811
k_EMNodeTimeout_mS_u16	29937
k_ESPNTCEnableTimeout_mS_u16	30052
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	51350
k_EtatMTSigInvalidThresh_Cnt_u16	19343
k_EtatMTSigValidThresh_Cnt_u16	461
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	872
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	44922
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	14430
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	53075
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	42798
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	7222
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	28106
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	11021
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	39661
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	16849
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	61563
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	42677
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	10512
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	24894
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	17352
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	58688
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	12804
k_ISDYNAASChkSumValidThresh_Cnt_u16	17922
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	18388
k_ISDYNAASMsgCountValidThresh_Cnt_u16	38474
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	3064
k_ISDYNAASMsgLenValidThresh_Cnt_u16	18839
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	24755
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	63273
k_ISDYNABRChkSumValidThresh_Cnt_u16	14095
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	26680
k_ISDYNABRMsgCountValidThresh_Cnt_u16	20750
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	31237
k_ISDYNABRMsgLenValidThresh_Cnt_u16	32136
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	6009
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	22409
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	18879
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	33422
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	5877
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	33675
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	52460
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	65489
k_ISDYNVOLChkSumValidThresh_Cnt_u16	55067
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	62777
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	28406
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	26024
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	59994
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	26506
k_IgnOnTimeout_mS_u16	43485
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	178.6819
k_PowerCutVehSpdLowThresh_Kph_f32	250.158401
k_PowerCutVehSpdLowTimeout_mS_u16	64596
k_VBattMaxAAS_Volt_f32	6.25339985
k_VBattMaxBSI_Volt_f32	4.97300005
k_VBattMaxCAV_Volt_f32	13.3500004
k_VBattMaxCMM388_Volt_f32	3.07439995
k_VBattMaxCMM_Volt_f32	3.89400005
k_VBattMaxESP_Volt_f32	21.3595009
k_VBattMinAAS_Volt_f32	14.7845001
k_VBattMinBSI_Volt_f32	21.3595009
k_VBattMinCAV_Volt_f32	23.4542007
k_VBattMinCMM388_Volt_f32	2.16910005
k_VBattMinCMM_Volt_f32	10
k_VBattMinESP_Volt_f32	3.89400005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	12624
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	9610
k_VitesseVehicleBVRampValidThresh_Cnt_u16	38246
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	39052
k_VitesseVehicleBVSigValidThresh_Cnt_u16	28022
k_VitesseVehicleBVSpeedPassThresh_kph_f32	292.310791
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	10840
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	59814
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	91537152
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8524
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1236548
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	203
target_SrlComInput_Per1_Batt_Volt_f32.value	12.1856003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1001090816
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	24
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0766759589
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1847025408
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3651075840
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3661012736
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	400441088
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	982900480
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3931995904
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3476365056
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	39
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	130
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	131
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	242
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	252
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4193992448
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	18
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	88
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	111
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	252
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	231
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1043226368
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	112
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	322305792
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1028497152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	22
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	124
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	173
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2852712192
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3760
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.731318891
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	692237
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	126.709503
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	12839

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1236548	1236548	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1236548	1236548	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1236548	1236548	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1236548	1236548	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	19709	19709	✔
CONSANGLECPK_HwDeg_M_f32	-598.407227	-598.407227 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1236548	1236548	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1236548	1236548	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1236548	1236548	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1236548	1236548	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1236548	1236548	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1236548	1236548	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1236548	1236548	✔
ESPNTCEnableTimer_mS_M_u32	1236548	1236548	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1236548	1236548	✔
EffacDefaultDiagTimer_mS_M_u32[1]	6070	6070	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1236548	1236548	✔
ElecIntTimer_mS_M_u32[1]	8259	8259	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1236548	1236548	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATDIRASentFltAcc_Cnt_M_u16	41895	41895	✔
ISDATDIRASentTimer_mS_M_u32	1236548	1236548	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1236548	1236548	✔
IgnOnTimer_mS_M_u32	2524274432	2524274432	✔
IgnTimeOff_Sec_M_u32	1887793480	1887793480	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	99	99	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1847025408	1847025408	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	99	99	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3651075840	3651075840	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	164	164	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3661012736	3661012736	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	206	206	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	400441088	400441088	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	279944960	279944960	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	126	126	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3931995904	3931995904	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	83	83	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3476365056	3476365056	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	252	252	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4193992448	4193992448	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	231	231	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1043226368	1043226368	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	112	112	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	322305792	322305792	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	251	251	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1028497152	1028497152	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2852712192	2852712192	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	75.7492981	75.7492981	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	306.421204	306.421204	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	569.33252	569.33252	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	19709	19709	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1887793480	1887793480	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-598.407227	-598.407227 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	54.6032982	54.6032982	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.324 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4238759424
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	28500
AASNodeAbsentTimer_mS_M_u32	603080192
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	10681
ANGLEVOLANTSigValidCount_Cnt_M_u16	63670
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	16449
AngleVolantMsgTimer_mS_M_u32	4238759424
AngleVolantValidCount_Cnt_M_u16	18320
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	598083072
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2029815296
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	759625216
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1618589184
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	496
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1674016256
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	49681
CAVNodeAbsentTimer_mS_M_u32	2028398080
CDD_SrlComVehSpd_Kph_G_f32	342.645599
CMM388NTCEnableTimer_mS_M_u32	1090463232
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	387769856
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	21705
CMMNodeAbsentTimer_mS_M_u32	4039357952
CONSANGLECPKSigInvalidCount_Cnt_M_u16	46201
CONSANGLECPKSigValidCount_Cnt_M_u16	26566
CONSANGLECPK_Cnt_M_u16	1633
CONSANGLECPK_HwDeg_M_f32	613.389404
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	1633
CPKVehicleSpeedMsgTimer_mS_M_u32	4120204800
CPKVehicleSpeedValidCount_Cnt_M_u16	36196

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	4276
CityParkInputInvalidCount_Cnt_M_u16	62366
CityParkInputMsgTimer_mS_M_u32	1847025408
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	907429376
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	44664
ComputerRazGCTSigInvalidTimer_mS_M_u32	1074750976
ComputerRazGCTSigValidCount_Cnt_M_u16	60377
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	50810
DMDFCTCPKSigValidCount_Cnt_M_u16	32351
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	5451
DMDRELAXECPKSigValidCount_Cnt_M_u16	52680
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	36454
DateInvalidTimer_mS_M_u32	2029815296
DiagMuxOnAbsentTimer_mS_M_u32	886314496
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1618589184
ESPNTCEnableTimer_mS_M_u32	3737339392
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	3842
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	9900
EffacDefaultDiagTimer_mS_M_u32[1]	11000
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8976
ElecIntTimer_mS_M_u32[1]	15236
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2277078528
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	50950
EtatMTSigValidCount_Cnt_M_u16	20655
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	54795
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	62168
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	30357
ISDAT4V2BSI552MsgTimer_mS_M_u32	367506944
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1617
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	33731
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	20655
ISDATBSI3F2MsgTimer_mS_M_u32	2873234944
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	64660
ISDATBSI412MsgLenValidCount_Cnt_M_u16	65535
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	50950
ISDATBSI412MsgTimer_mS_M_u32	3641988608
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	52461
ISDATBSI432MsgLenValidCount_Cnt_M_u16	6694
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	5634
ISDATDIRASentFltAcc_Cnt_M_u16	25142
ISDATDIRASentTimer_mS_M_u32	4120204800
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	4943
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	18320
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	61489
ISDYN2CMMMsgTimer_mS_M_u32	3817686528
ISDYNAASChkSumInvalidCount_Cnt_M_u16	9958
ISDYNAASChkSumValidCount_Cnt_M_u16	50436
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	55111
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	43244
ISDYNAASMsgLenValidCount_Cnt_M_u16	24065
ISDYNAASMsgTimeValidCount_Cnt_M_u16	9958
ISDYNAASMsgTimer_mS_M_u32	685450752
ISDYNABRChkSumInvalidCount_Cnt_M_u16	44044
ISDYNABRChkSumValidCount_Cnt_M_u16	9426
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	12573
ISDYNABRMsgCountValidCount_Cnt_M_u16	55931
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	61872
ISDYNABRMsgLenValidCount_Cnt_M_u16	61501
ISDYNABRMsgTimeValidCount_Cnt_M_u16	1633

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	18448
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	51446
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	20655
ISDYNCMM208MsgTimer_mS_M_u32	923469312
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	18448
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	51446
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	39678
ISDYNCMM388MsgTimer_mS_M_u32	1616291328
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	25319
ISDYNVOLChkSumValidCount_Cnt_M_u16	44212
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	59368
ISDYNVOLMsgCountValidCount_Cnt_M_u16	30285
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	971
ISDYNVOLMsgLenValidCount_Cnt_M_u16	18425
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	21705
ISDYNVOLMsgTimer_mS_M_u32	2481677824
IgnOnTimer_mS_M_u32	276473344
IgnTimeOff_Sec_M_u32	658424461
ManVehSpd_Kph_M_f32	535.49292
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	202
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	108
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	190322176
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	129
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3898471936
PrevISDATBSI412MsgDLCError_Cnt_M_u08	63
PrevISDATBSI412MsgRxTime_MSec_M_u32	2409096704
PrevISDATBSI432MsgDLCError_Cnt_M_u08	84
PrevISDATBSI432MsgRxTime_MSec_M_u32	2874623488
PrevISDATDIRAMsgTxTime_MSec_M_u32	1523312128
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	172
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1145517568
PrevISDYNAASMsgDLCError_Cnt_M_u08	227
PrevISDYNAASMsgRxTime_MSec_M_u32	1759077888
PrevISDYNABRMsgDLCError_Cnt_M_u08	179
PrevISDYNABRMsgRxTime_MSec_M_u32	3811747328
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	171
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1102996992
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	15
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2532460032
PrevISDYNVOLMsgDLCError_Cnt_M_u08	65
PrevISDYNVOLMsgRxTime_MSec_M_u32	2178213376
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3095549440
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	421.027588
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	12378
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	15343
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	53923
VitesseVehicleBVRampValidCount_Cnt_M_u16	13048
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	34178

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	51519
VitesseVehicleBV_Kph_M_f32	269.979614
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	39678
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	28916
VitesseVehiculeRoues_Kph_M_f32	484.984406
k_AASNTCEnableTimeout_mS_u16	6544
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	53539
k_AASNodeTimeout_mS_u16	12015
k_ABSNodeTimeout_mS_u16	31135
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	43968
k_ANGLEVOLANTSigValidThresh_Cnt_u16	33081
k_AngleVolantInvalidThresh_Cnt_u16	55224
k_AngleVolantValidThresh_Cnt_u16	62366
k_BSI552MsgTimeout_mS_u16	11315
k_BSINTCEnableTimeout_mS_u16	4005
k_BSINodeAbsentDiag_Cnt_str.Threshold	39416
k_BSINodeAbsentDiag_Cnt_str.PStep	7710
k_BSINodeAbsentDiag_Cnt_str.NStep	3896
k_BSINodeAbsentTimeout_mS_u16	38137
k_BSINodeTimeout_mS_u16	5634
k_BattOvHi_Volt_f32	8.58329964
k_BattOvLo_Volt_f32	29.1238003
k_BattUvHi_Volt_f32	2.31949997
k_BattUvLo_Volt_f32	0.931699991
k_CAVNTCEnableTimeout_mS_u16	19908
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	13439
k_CAVNodeTimeout_mS_u16	5205
k_CMM388MsgTimeout_mS_u16	41556
k_CMM388NTCEnableTimeout_mS_u16	41776
k_CMMNTCEnableTimeout_mS_u16	25865
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	10192
k_CONSANGLECPKMax_HwDeg_f32	780
k_CONSANGLECPKMin_HwDeg_f32	-469.758514
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	19966
k_CONSANGLECPKSigValidThresh_Cnt_u16	25588
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	4645
k_CPKVehicleSpeedValidThresh_Cnt_u16	34095
k_CityParkInputInvalidThresh_Cnt_u16	21442
k_CityParkInputValidThresh_Cnt_u16	4276
k_ComputerRazGCTSigValidThresh_Cnt_u16	39143
k_CptTemporelSigValidThresh_Cnt_u16	64217
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	9392
k_DMDFCTCPKSigValidThresh_Cnt_u16	25405
k_DMDFCTCPKValidCount_Cnt_u16	61496
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	61489
k_DMDRELAXECPKSigValidThresh_Cnt_u16	21334
k_DMDRelaxeConsistentThresh_Cnt_u16	8332
k_DateValidThresh_Cnt_u16	30357
k_DefaultVehSpd_Kph_f32	216.2948
k_DiagMuxOnAbsentTimeout_mS_u16	55815
k_EMNodeTimeout_mS_u16	57798
k_ESPNTCEnableTimeout_mS_u16	50157
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	60696
k_EtatMTSigInvalidThresh_Cnt_u16	65131
k_EtatMTSigValidThresh_Cnt_u16	53361
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	42656
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	59178
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	34045
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	43102
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	34192
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	6840

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	49274
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	36211
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	34065
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	30693
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	4262
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	34874
k_ISDATDIRASentDiag_Cnt_str.Threshold	6549
k_ISDATDIRASentDiag_Cnt_str.PStep	63930
k_ISDATDIRASentDiag_Cnt_str.NStep	24627
k_ISDATDIRASentTimeout_mS_u16	43496
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	48287
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	16449
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	58457
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	24332
k_ISDYNAASChkSumValidThresh_Cnt_u16	6098
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	25629
k_ISDYNAASMsgCountValidThresh_Cnt_u16	19835
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	41264
k_ISDYNAASMsgLenValidThresh_Cnt_u16	20499
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	1153
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	15134
k_ISDYNABRChkSumValidThresh_Cnt_u16	4139
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	13552
k_ISDYNABRMsgCountValidThresh_Cnt_u16	53037
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	18377
k_ISDYNABRMsgLenValidThresh_Cnt_u16	16898
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	59372
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	61822
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	63005
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	16686
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	23737
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	27574
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	35926
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	39911
k_ISDYNVOLChkSumValidThresh_Cnt_u16	15048
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	57071
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	27894
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	56802
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	5259
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	12603
k_IgnOnTimeout_mS_u16	52675
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	92.5588989
k_PowerCutVehSpdLowThresh_Kph_f32	238.129196
k_PowerCutVehSpdLowTimeout_mS_u16	5212
k_VBattMaxAAS_Volt_f32	5.74539995
k_VBattMaxBSI_Volt_f32	15.323
k_VBattMaxCAV_Volt_f32	25.9311008
k_VBattMaxCMM388_Volt_f32	25.3694992
k_VBattMaxCMM_Volt_f32	32
k_VBattMaxESP_Volt_f32	13.3754997
k_VBattMinAAS_Volt_f32	3.4519999
k_VBattMinBSI_Volt_f32	13.3754997
k_VBattMinCAV_Volt_f32	12.7309999
k_VBattMinCMM388_Volt_f32	24.5725994
k_VBattMinCMM_Volt_f32	29.2782001
k_VBattMinESP_Volt_f32	32
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	5225
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	7290
k_VitesseVehicleBVRampValidThresh_Cnt_u16	39656
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	8116
k_VitesseVehicleBVSigValidThresh_Cnt_u16	17845
k_VitesseVehicleBVSpeedPassThresh_kph_f32	25.8031006
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	29969
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	27622
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2029815296
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	33485
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3144151296
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	15
target_SrlComInput_Per1_Batt_Volt_f32.value	1.8312
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1293448704
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	146
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.911011755
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2442438144
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1971176960
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	191
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3661030912
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	199
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3351250432
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1176053248
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1564624384
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	76
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	356214272
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	28
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	46
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	58
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	98
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	179
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	189
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3580429824
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	41
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	55
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	177
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	199
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1028630016
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3837314560
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3438405120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	15
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	157
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	215
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1476392448
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3989
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.297963023
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	310615
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	168.726196
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	22948

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3144151296	3144151296	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	39416	39416	✔
BSINodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
CDD_SrlComVehSpd_Kph_G_f32	535.49292	535.49292	✔
CMM388NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	1633	1633	✔
CONSANGLECPK_HwDeg_M_f32	613.389404	613.389404 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3144151296	3144151296	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3144151296	3144151296	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3144151296	3144151296	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3144151296	3144151296	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3144151296	3144151296	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3144151296	3144151296	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3144151296	3144151296	✔
ESPNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	9900	9900	✔
EffacDefaultDiagTimer_mS_M_u32[1]	11000	11000	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	8976	8976	✔
ElecIntTimer_mS_M_u32[1]	15236	15236	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3144151296	3144151296	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	30357	30357	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	20655	20655	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	50950	50950	✔
ISDATBSI412MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	5634	5634	✔
ISDATBSI432MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATDIRASentFltAcc_Cnt_M_u16	6549	6549	✔
ISDATDIRASentTimer_mS_M_u32	3144151296	3144151296	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	61489	61489	✔
ISDYN2CMMMsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	9958	9958	✔
ISDYNAASMsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	1633	1633	✔
ISDYNABRMsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	20655	20655	✔
ISDYNCMM208MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	39678	39678	✔
ISDYNCMM388MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	21705	21705	✔
ISDYNVOLMsgTimer_mS_M_u32	3144151296	3144151296	✔
IgnOnTimer_mS_M_u32	276473344	276473344	✔
IgnTimeOff_Sec_M_u32	658424461	658424461	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	53	53	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2442438144	2442438144	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	59	59	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1971176960	1971176960	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	191	191	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3661030912	3661030912	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	199	199	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3351250432	3351250432	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1523312128	1523312128	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	134	134	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1564624384	1564624384	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	76	76	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	356214272	356214272	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	241	241	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3580429824	3580429824	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	199	199	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1028630016	1028630016	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	49	49	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3837314560	3837314560	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	216	216	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3438405120	3438405120	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1476392448	1476392448	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	421.027588	421.027588	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	269.979614	269.979614	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	484.984406	484.984406	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	1633	1633	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	658424461	658424461	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	613.389404	613.389404 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.325 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4202938624
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	31864
AASNodeAbsentTimer_mS_M_u32	3764384000
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	32586
ANGLEVOLANTSigValidCount_Cnt_M_u16	5138
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	64945
AngleVolantMsgTimer_mS_M_u32	4202938624
AngleVolantValidCount_Cnt_M_u16	35907
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1615114496
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3661705472
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	857858304
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3565789440
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	37541
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	832594176
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	48834
CAVNodeAbsentTimer_mS_M_u32	4227993856
CDD_SrlComVehSpd_Kph_G_f32	614.743591
CMM388NTCEnableTimer_mS_M_u32	1421431040
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2036338944
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	49499
CMMNodeAbsentTimer_mS_M_u32	3417022720
CONSANGLECPKSigInvalidCount_Cnt_M_u16	36363
CONSANGLECPKSigValidCount_Cnt_M_u16	46563
CONSANGLECPK_Cnt_M_u16	1554
CONSANGLECPK_HwDeg_M_f32	-35.0065002
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	1554
CPKVehicleSpeedMsgTimer_mS_M_u32	2344009984
CPKVehicleSpeedValidCount_Cnt_M_u16	42225
CityParkInputConsistentCount_Cnt_M_u16	49367
CityParkInputInvalidCount_Cnt_M_u16	19740
CityParkInputMsgTimer_mS_M_u32	2442438144
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	972288256
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	20236

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3901264128
ComputerRazGCTSigValidCount_Cnt_M_u16	872
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	17544
DMDFCTCPKSigValidCount_Cnt_M_u16	48791
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	33940
DMDRELAXECPKSigValidCount_Cnt_M_u16	23772
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	62532
DateInvalidTimer_mS_M_u32	3661705472
DiagMuxOnAbsentTimer_mS_M_u32	955941120
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3565789440
ESPNTCEnableTimer_mS_M_u32	871166208
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	33903
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	6454
EffacDefaultDiagTimer_mS_M_u32[1]	8257
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1100
ElecIntTimer_mS_M_u32[1]	1151
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	231366912
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	61347
EtatMTSigValidCount_Cnt_M_u16	1127
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	61781
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	56493
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	11765
ISDAT4V2BSI552MsgTimer_mS_M_u32	3963592960
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	5953
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	28845
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	1127
ISDATBSI3F2MsgTimer_mS_M_u32	229671168
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	3450
ISDATBSI412MsgLenValidCount_Cnt_M_u16	17578
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	61347
ISDATBSI412MsgTimer_mS_M_u32	2637807872
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	59631
ISDATBSI432MsgLenValidCount_Cnt_M_u16	62211
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	50927
ISDATDIRASentFltAcc_Cnt_M_u16	45651
ISDATDIRASentTimer_mS_M_u32	2344009984
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	5960
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	35907
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	25443
ISDYN2CMMMsgTimer_mS_M_u32	3448697088
ISDYNAASChkSumInvalidCount_Cnt_M_u16	7618
ISDYNAASChkSumValidCount_Cnt_M_u16	50473
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	31006
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	13873
ISDYNAASMsgLenValidCount_Cnt_M_u16	30897
ISDYNAASMsgTimeValidCount_Cnt_M_u16	7618
ISDYNAASMsgTimer_mS_M_u32	220549376
ISDYNABRChkSumInvalidCount_Cnt_M_u16	64976
ISDYNABRChkSumValidCount_Cnt_M_u16	46400
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	39709
ISDYNABRMsgCountValidCount_Cnt_M_u16	8388
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	29286
ISDYNABRMsgLenValidCount_Cnt_M_u16	47230
ISDYNABRMsgTimeValidCount_Cnt_M_u16	1554
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	9718
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	35075
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	1127
ISDYNCMM208MsgTimer_mS_M_u32	4195725568
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	9718
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	35075
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	51705

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3031617792
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	47809
ISDYNVOLChkSumValidCount_Cnt_M_u16	7961
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	6206
ISDYNVOLMsgCountValidCount_Cnt_M_u16	3789
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	2580
ISDYNVOLMsgLenValidCount_Cnt_M_u16	65355
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	49499
ISDYNVOLMsgTimer_mS_M_u32	1559531776
IgnOnTimer_mS_M_u32	877056256
IgnTimeOff_Sec_M_u32	973016808
ManVehSpd_Kph_M_f32	66.3265991
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	203
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	88
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3312353536
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	139
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	501014784
PrevISDATBSI412MsgDLCError_Cnt_M_u08	184
PrevISDATBSI412MsgRxTime_MSec_M_u32	3153006848
PrevISDATBSI432MsgDLCError_Cnt_M_u08	30
PrevISDATBSI432MsgRxTime_MSec_M_u32	506523904
PrevISDATDIRAMsgTxTime_MSec_M_u32	710086912
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	1
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1059135744
PrevISDYNAASMsgDLCError_Cnt_M_u08	190
PrevISDYNAASMsgRxTime_MSec_M_u32	371888384
PrevISDYNABRMsgDLCError_Cnt_M_u08	243
PrevISDYNABRMsgRxTime_MSec_M_u32	2619265280
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	169
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1601933568
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	94
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2271211776
PrevISDYNVOLMsgDLCError_Cnt_M_u08	113
PrevISDYNVOLMsgRxTime_MSec_M_u32	423104768
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	921682176
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	651.36322
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	55271
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	5863
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	21772
VitesseVehicleBVRampValidCount_Cnt_M_u16	38348
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	53231
VitesseVehicleBVSigValidCount_Cnt_M_u16	1655
VitesseVehicleBV_Kph_M_f32	137.944107
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	51705
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	10713
VitesseVehiculeRoues_Kph_M_f32	419.753693
k_AASNTCEnableTimeout_mS_u16	18565
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	64394
k_AASNodeTimeout_mS_u16	15847
k_ABSNodeTimeout_mS_u16	65305
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	22646
k_ANGLEVOLANTSigValidThresh_Cnt_u16	51658
k_AngleVolantInvalidThresh_Cnt_u16	33357
k_AngleVolantValidThresh_Cnt_u16	19740
k_BSI552MsgTimeout_mS_u16	46108
k_BSINTCEnableTimeout_mS_u16	199
k_BSINodeAbsentDiag_Cnt_str.Threshold	27580
k_BSINodeAbsentDiag_Cnt_str.PStep	10635
k_BSINodeAbsentDiag_Cnt_str.NStep	28798
k_BSINodeAbsentTimeout_mS_u16	57225
k_BSINodeTimeout_mS_u16	50927
k_BattOvHi_Volt_f32	0.112199999
k_BattOvLo_Volt_f32	4.85559988
k_BattUvHi_Volt_f32	4.24049997
k_BattUvLo_Volt_f32	18.7824001
k_CAVNTCEnableTimeout_mS_u16	22186
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	40824
k_CAVNodeTimeout_mS_u16	56951
k_CMM388MsgTimeout_mS_u16	58232
k_CMM388NTCEnableTimeout_mS_u16	20708
k_CMMNTCEnableTimeout_mS_u16	56089
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	30021
k_CONSANGLECPKMax_HwDeg_f32	411.798889
k_CONSANGLECPKMin_HwDeg_f32	-123.665604
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	45305
k_CONSANGLECPKSigValidThresh_Cnt_u16	20697
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	60485
k_CPKVehicleSpeedValidThresh_Cnt_u16	40873
k_CityParkInputInvalidThresh_Cnt_u16	24238
k_CityParkInputValidThresh_Cnt_u16	49367
k_ComputerRazGCTSigValidThresh_Cnt_u16	14207
k_CptTemporelSigValidThresh_Cnt_u16	58219
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	55654
k_DMDFCTCPKSigValidThresh_Cnt_u16	24446
k_DMDFCTCPKValidCount_Cnt_u16	59341
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	25443
k_DMDRELAXECPKSigValidThresh_Cnt_u16	56242
k_DMDRelaxeConsistentThresh_Cnt_u16	52240
k_DateValidThresh_Cnt_u16	11765
k_DefaultVehSpd_Kph_f32	228.079605
k_DiagMuxOnAbsentTimeout_mS_u16	41760
k_EMNodeTimeout_mS_u16	31268
k_ESPNTCEnableTimeout_mS_u16	10542
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	17773
k_EtatMTSigInvalidThresh_Cnt_u16	17075
k_EtatMTSigValidThresh_Cnt_u16	61027
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	56020
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	19191
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	51196
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	42266
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	57158
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	17166
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	33352
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	3356
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	20611
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	49542
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	2305
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	54151
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	29756
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	2648
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	64945
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	30698
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	58576
k_ISDYNAASChkSumValidThresh_Cnt_u16	56384
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	541
k_ISDYNAASMsgCountValidThresh_Cnt_u16	51140
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	44644
k_ISDYNAASMsgLenValidThresh_Cnt_u16	27259
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	24562
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	52764
k_ISDYNABRChkSumValidThresh_Cnt_u16	37044
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	63909
k_ISDYNABRMsgCountValidThresh_Cnt_u16	11437
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	59483
k_ISDYNABRMsgLenValidThresh_Cnt_u16	60271
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	40560
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	9339
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	34015
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	49962
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	58954
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	47890
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	25332
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	15233
k_ISDYNVOLChkSumValidThresh_Cnt_u16	61597
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	2216
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	27860
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	6927
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	10451
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	5635
k_IgnOnTimeout_mS_u16	5613
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	109.787102
k_PowerCutVehSpdLowThresh_Kph_f32	129.076202
k_PowerCutVehSpdLowTimeout_mS_u16	34849
k_VBattMaxAAS_Volt_f32	4.28660011
k_VBattMaxBSI_Volt_f32	24.3446999
k_VBattMaxCAV_Volt_f32	17.3026009
k_VBattMaxCMM388_Volt_f32	14.1534996
k_VBattMaxCMM_Volt_f32	29.7154999
k_VBattMaxESP_Volt_f32	20.5515003
k_VBattMinAAS_Volt_f32	7.26739979
k_VBattMinBSI_Volt_f32	20.5515003
k_VBattMinCAV_Volt_f32	5.56589985
k_VBattMinCMM388_Volt_f32	27.0821991
k_VBattMinCMM_Volt_f32	27.3708
k_VBattMinESP_Volt_f32	29.7154999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	43770
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	58502
k_VitesseVehicleBVRampValidThresh_Cnt_u16	65342
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	50713
k_VitesseVehicleBVSigValidThresh_Cnt_u16	26068
k_VitesseVehicleBVSpeedPassThresh_kph_f32	417.316895
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	42434
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	8962
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3661705472
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	13090
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1516957696
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	94
target_SrlComInput_Per1_Batt_Volt_f32.value	3.50200009
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4188889344
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	152
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.13759993
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2566443264
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	248
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2042458368
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	403837184
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1542893824
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	762007808
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1953493248
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	36
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	419729664
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	124
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	150
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	193
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	385593600
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	36
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	43
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	114
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	242
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1103614208
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3624694016
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3957395712
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	55
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	119
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	126
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	161
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	218
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	234
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3606503680
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3692
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.569908977
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	862957
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	120.5354
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	1033

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1516957696	1516957696	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	27580	27580	✔
BSINodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔
CDD_SrlComVehSpd_Kph_G_f32	66.3265991	66.3265991	✔
CMM388NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	1554	1554	✔
CONSANGLECPK_HwDeg_M_f32	-35.0065002	-35.0065002 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1516957696	1516957696	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1516957696	1516957696	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1516957696	1516957696	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1516957696	1516957696	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1516957696	1516957696	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1516957696	1516957696	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1516957696	1516957696	✔
ESPNTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	6454	6454	✔
EffacDefaultDiagTimer_mS_M_u32[1]	8257	8257	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1100	1100	✔
ElecIntTimer_mS_M_u32[1]	1151	1151	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1516957696	1516957696	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	11765	11765	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	1127	1127	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	61347	61347	✔
ISDATBSI412MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	50927	50927	✔
ISDATBSI432MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11170	11170	✔
ISDATDIRASentTimer_mS_M_u32	1516957696	1516957696	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	25443	25443	✔
ISDYN2CMMMsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	7618	7618	✔
ISDYNAASMsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	1554	1554	✔
ISDYNABRMsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	1127	1127	✔
ISDYNCMM208MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	51705	51705	✔
ISDYNCMM388MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	49499	49499	✔
ISDYNVOLMsgTimer_mS_M_u32	1516957696	1516957696	✔
IgnOnTimer_mS_M_u32	877056256	877056256	✔
IgnTimeOff_Sec_M_u32	973016808	973016808	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	31	31	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2566443264	2566443264	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	248	248	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2042458368	2042458368	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	154	154	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	403837184	403837184	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	238	238	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1542893824	1542893824	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	710086912	710086912	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	75	75	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1953493248	1953493248	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	36	36	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	419729664	419729664	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	83	83	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	385593600	385593600	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1103614208	1103614208	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	195	195	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3624694016	3624694016	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	251	251	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3957395712	3957395712	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3606503680	3606503680	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	651.36322	651.36322	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	137.944107	137.944107	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	419.753693	419.753693	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	1554	1554	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	973016808	973016808	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-35.0065002	-35.0065002 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	66.3265991	66.3265991	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.326 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2421653504
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	31866
AASNodeAbsentTimer_mS_M_u32	3414355968
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	56834
ANGLEVOLANTSigValidCount_Cnt_M_u16	6763
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	7375
AngleVolantMsgTimer_mS_M_u32	2421653504
AngleVolantValidCount_Cnt_M_u16	33687
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3470045184
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	4074713088
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2264735744
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	4056276992
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	53233
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2776735744
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	1563
CAVNodeAbsentTimer_mS_M_u32	689737728
CDD_SrlComVehSpd_Kph_G_f32	655.340027
CMM388NTCEnableTimer_mS_M_u32	200724480
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2835517440
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	52752
CMMNodeAbsentTimer_mS_M_u32	341827584
CONSANGLECPKSigInvalidCount_Cnt_M_u16	42176
CONSANGLECPKSigValidCount_Cnt_M_u16	26617
CONSANGLECPK_Cnt_M_u16	62316
CONSANGLECPK_HwDeg_M_f32	-123.863297
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	62316
CPKVehicleSpeedMsgTimer_mS_M_u32	1757315072
CPKVehicleSpeedValidCount_Cnt_M_u16	6933
CityParkInputConsistentCount_Cnt_M_u16	13787
CityParkInputInvalidCount_Cnt_M_u16	61966
CityParkInputMsgTimer_mS_M_u32	2566443264
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	247918592
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	21694

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2643005440
ComputerRazGCTSigValidCount_Cnt_M_u16	61992
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	48074
DMDFCTCPKSigValidCount_Cnt_M_u16	26715
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	30244
DMDRELAXECPKSigValidCount_Cnt_M_u16	59405
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	38421
DateInvalidTimer_mS_M_u32	4074713088
DiagMuxOnAbsentTimer_mS_M_u32	536035328
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4056276992
ESPNTCEnableTimer_mS_M_u32	1155264512
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	44949
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8976
EffacDefaultDiagTimer_mS_M_u32[1]	15234
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2050
ElecIntTimer_mS_M_u32[1]	6071
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	956538880
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	46136
EtatMTSigValidCount_Cnt_M_u16	24749
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	8930
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	39835
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	4673
ISDAT4V2BSI552MsgTimer_mS_M_u32	44294144
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	36062
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	2907
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	24749
ISDATBSI3F2MsgTimer_mS_M_u32	4191240192
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0
ISDATBSI412MsgLenValidCount_Cnt_M_u16	8287
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	46136
ISDATBSI412MsgTimer_mS_M_u32	3506176
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	42836
ISDATBSI432MsgLenValidCount_Cnt_M_u16	46041
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	57748
ISDATDIRASentFltAcc_Cnt_M_u16	44904
ISDATDIRASentTimer_mS_M_u32	1757315072
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	6090
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	33687
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	35641
ISDYN2CMMMsgTimer_mS_M_u32	2146824192
ISDYNAASChkSumInvalidCount_Cnt_M_u16	16540
ISDYNAASChkSumValidCount_Cnt_M_u16	50468
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	59654
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	7118
ISDYNAASMsgLenValidCount_Cnt_M_u16	12047
ISDYNAASMsgTimeValidCount_Cnt_M_u16	16540
ISDYNAASMsgTimer_mS_M_u32	2461192192
ISDYNABRChkSumInvalidCount_Cnt_M_u16	20976
ISDYNABRChkSumValidCount_Cnt_M_u16	50785
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	62603
ISDYNABRMsgCountValidCount_Cnt_M_u16	56915
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	9135
ISDYNABRMsgLenValidCount_Cnt_M_u16	35880
ISDYNABRMsgTimeValidCount_Cnt_M_u16	62316
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	42222
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	51848
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	24749
ISDYNCMM208MsgTimer_mS_M_u32	2237771776
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	42222
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	51848
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	8821

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2987020288
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	30366
ISDYNVOLChkSumValidCount_Cnt_M_u16	33879
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	39080
ISDYNVOLMsgCountValidCount_Cnt_M_u16	53177
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	62118
ISDYNVOLMsgLenValidCount_Cnt_M_u16	52671
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	52752
ISDYNVOLMsgTimer_mS_M_u32	4031057920
IgnOnTimer_mS_M_u32	2202947584
IgnTimeOff_Sec_M_u32	1987872898
ManVehSpd_Kph_M_f32	241.705902
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	204
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	107
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1251426304
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	120
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1925980160
PrevISDATBSI412MsgDLCError_Cnt_M_u08	194
PrevISDATBSI412MsgRxTime_MSec_M_u32	3713372160
PrevISDATBSI432MsgDLCError_Cnt_M_u08	158
PrevISDATBSI432MsgRxTime_MSec_M_u32	2517626880
PrevISDATDIRAMsgTxTime_MSec_M_u32	573149184
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	58
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1879007232
PrevISDYNAASMsgDLCError_Cnt_M_u08	217
PrevISDYNAASMsgRxTime_MSec_M_u32	480448512
PrevISDYNABRMsgDLCError_Cnt_M_u08	76
PrevISDYNABRMsgRxTime_MSec_M_u32	2881900544
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	74
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3299872768
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	140
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3598905344
PrevISDYNVOLMsgDLCError_Cnt_M_u08	96
PrevISDYNVOLMsgRxTime_MSec_M_u32	695898112
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2333310976
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	387.033508
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	36524
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	44141
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	60221
VitesseVehicleBVRampValidCount_Cnt_M_u16	958
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	49171
VitesseVehicleBVSigValidCount_Cnt_M_u16	5948
VitesseVehicleBV_Kph_M_f32	232.600403
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	8821
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	23958
VitesseVehiculeRoues_Kph_M_f32	544.740173
k_AASNTCEnableTimeout_mS_u16	47123
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	4546
k_AASNodeTimeout_mS_u16	14189
k_ABSNodeTimeout_mS_u16	4119
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	13503
k_ANGLEVOLANTSigValidThresh_Cnt_u16	2948
k_AngleVolantInvalidThresh_Cnt_u16	44539
k_AngleVolantValidThresh_Cnt_u16	61966
k_BSI552MsgTimeout_mS_u16	35533
k_BSINTCEnableTimeout_mS_u16	49100
k_BSINodeAbsentDiag_Cnt_str.Threshold	8478
k_BSINodeAbsentDiag_Cnt_str.PStep	2288
k_BSINodeAbsentDiag_Cnt_str.NStep	58710
k_BSINodeAbsentTimeout_mS_u16	55111
k_BSINodeTimeout_mS_u16	57748
k_BattOvHi_Volt_f32	29.8953991
k_BattOvLo_Volt_f32	11.5711002
k_BattUvHi_Volt_f32	28.9997997
k_BattUvLo_Volt_f32	19.2388
k_CAVNTCEnableTimeout_mS_u16	36196
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	48121
k_CAVNodeTimeout_mS_u16	25468
k_CMM388MsgTimeout_mS_u16	18298
k_CMM388NTCEnableTimeout_mS_u16	44854
k_CMMNTCEnableTimeout_mS_u16	41302
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	11090
k_CONSANGLECPKMax_HwDeg_f32	124.903297
k_CONSANGLECPKMin_HwDeg_f32	-233.219696
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	28021
k_CONSANGLECPKSigValidThresh_Cnt_u16	59542
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	9299
k_CPKVehicleSpeedValidThresh_Cnt_u16	58533
k_CityParkInputInvalidThresh_Cnt_u16	10070
k_CityParkInputValidThresh_Cnt_u16	13787
k_ComputerRazGCTSigValidThresh_Cnt_u16	42020
k_CptTemporelSigValidThresh_Cnt_u16	11041
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	61103
k_DMDFCTCPKSigValidThresh_Cnt_u16	38696
k_DMDFCTCPKValidCount_Cnt_u16	28793
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	35641
k_DMDRELAXECPKSigValidThresh_Cnt_u16	15626
k_DMDRelaxeConsistentThresh_Cnt_u16	25584
k_DateValidThresh_Cnt_u16	4673
k_DefaultVehSpd_Kph_f32	94.1470032
k_DiagMuxOnAbsentTimeout_mS_u16	54338
k_EMNodeTimeout_mS_u16	33909
k_ESPNTCEnableTimeout_mS_u16	30423
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	23258
k_EtatMTSigInvalidThresh_Cnt_u16	53063
k_EtatMTSigValidThresh_Cnt_u16	26360
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	21670
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	28411
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	62572
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	34643
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	25488
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	52854
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	32585
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	2446
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	49304
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	37136
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	34141
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	37386
k_ISDATDIRASentDiag_Cnt_str.Threshold	25239

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	16638
k_ISDATDIRASentDiag_Cnt_str.NStep	16248
k_ISDATDIRASentTimeout_mS_u16	40620
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	29079
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	7375
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	31395
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	40176
k_ISDYNAASChkSumValidThresh_Cnt_u16	20833
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	49035
k_ISDYNAASMsgCountValidThresh_Cnt_u16	59731
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	36916
k_ISDYNAASMsgLenValidThresh_Cnt_u16	433
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	59660
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	26765
k_ISDYNABRChkSumValidThresh_Cnt_u16	23430
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	39665
k_ISDYNABRMsgCountValidThresh_Cnt_u16	64666
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	22800
k_ISDYNABRMsgLenValidThresh_Cnt_u16	31381
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	29521
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	63728
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	36099
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	29604
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	43266
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	9579
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	4230
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	28957
k_ISDYNVOLChkSumValidThresh_Cnt_u16	40074
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	18154
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	61349
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	57844
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	41833
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	4631
k_IgnOnTimeout_mS_u16	37337
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	125.524399
k_PowerCutVehSpdLowThresh_Kph_f32	235.657196
k_PowerCutVehSpdLowTimeout_mS_u16	26943
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	23.5021
k_VBattMaxCAV_Volt_f32	3.2816999
k_VBattMaxCMM388_Volt_f32	27.2308998
k_VBattMaxCMM_Volt_f32	1.26660001
k_VBattMaxESP_Volt_f32	30.7887001
k_VBattMinAAS_Volt_f32	1.80519998
k_VBattMinBSI_Volt_f32	30.7887001
k_VBattMinCAV_Volt_f32	27.5025005
k_VBattMinCMM388_Volt_f32	22.8304005
k_VBattMinCMM_Volt_f32	11.7488003
k_VBattMinESP_Volt_f32	1.26660001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	38833
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	62926
k_VitesseVehicleBVRampValidThresh_Cnt_u16	58280
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	36695
k_VitesseVehicleBVSigValidThresh_Cnt_u16	31460
k_VitesseVehicleBVSpeedPassThresh_kph_f32	97.6119995
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	20763
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	46108
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4074713088
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1277031168
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	140
target_SrlComInput_Per1_Batt_Volt_f32.value	4.66720009
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3243941888
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	153
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.864875674
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2637713408
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1433038848
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	247
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	351047680
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	599699456
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3386953728
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1330835456
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4229238784
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	54
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	147
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	149
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	176
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	190
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	226
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1185918976
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	88
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	103
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	115
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	134
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	172
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	173
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	200
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	207
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2664124416
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	254
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	914190336
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2508165120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	52
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	91
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	115
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	213
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	226
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	796794880
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2058
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.797266543
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	968948
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	143.529495
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	4678

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	7377	7377	✔
AngleVolantMsgTimer_mS_M_u32	1277031168	1277031168	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	62316	62316	✔
CONSANGLECPK_HwDeg_M_f32	-123.863297	-123.863297 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	62316	62316	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1757315072	1757315072	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	6933	6933	✔
CityParkInputConsistentCount_Cnt_M_u16	13787	13787	✔
CityParkInputInvalidCount_Cnt_M_u16	61966	61966	✔
CityParkInputMsgTimer_mS_M_u32	1277031168	1277031168	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1277031168	1277031168	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1277031168	1277031168	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1277031168	1277031168	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1277031168	1277031168	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1277031168	1277031168	✔
ESPNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	8976	8976	✔
EffacDefaultDiagTimer_mS_M_u32[1]	15234	15234	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	1277031168	1277031168	✔
ElecIntTimer_mS_M_u32[1]	6071	6071	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1277031168	1277031168	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATDIRASentFltAcc_Cnt_M_u16	25239	25239	✔
ISDATDIRASentTimer_mS_M_u32	1277031168	1277031168	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1277031168	1277031168	✔
IgnOnTimer_mS_M_u32	1277031168	1277031168	✔
IgnTimeOff_Sec_M_u32	1987872898	1987872898	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	181	181	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2637713408	2637713408	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	100	100	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1433038848	1433038848	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	247	247	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	351047680	351047680	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	181	181	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	599699456	599699456	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	573149184	573149184	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	212	212	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1330835456	1330835456	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	196	196	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4229238784	4229238784	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	219	219	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1185918976	1185918976	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	207	207	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2664124416	2664124416	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	254	254	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	914190336	914190336	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	208	208	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2508165120	2508165120	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	796794880	796794880	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	387.033508	387.033508	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	232.600403	232.600403	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	544.740173	544.740173	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	62316	62316	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1987872898	1987872898	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-123.863297	-123.863297 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	94.1470032	94.1470032	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.327 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3499639552
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	46640
AASNodeAbsentTimer_mS_M_u32	1490416384
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	21399
ANGLEVOLANTSigValidCount_Cnt_M_u16	44572
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	26929
AngleVolantMsgTimer_mS_M_u32	3499639552
AngleVolantValidCount_Cnt_M_u16	64857
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3319837440
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2747347712
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	187130624
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3721208576
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	63946
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1637475072
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	10187
CAVNodeAbsentTimer_mS_M_u32	780735232
CDD_SrlComVehSpd_Kph_G_f32	380.584015
CMM388NTCEnableTimer_mS_M_u32	3204076288
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3335983872
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	24748
CMMNodeAbsentTimer_mS_M_u32	1577001728
CONSANGLECPKSigInvalidCount_Cnt_M_u16	9822
CONSANGLECPKSigValidCount_Cnt_M_u16	11379
CONSANGLECPK_Cnt_M_u16	5658
CONSANGLECPK_HwDeg_M_f32	-486.971313
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	5658
CPKVehicleSpeedMsgTimer_mS_M_u32	2741191424
CPKVehicleSpeedValidCount_Cnt_M_u16	45637
CityParkInputConsistentCount_Cnt_M_u16	63117
CityParkInputInvalidCount_Cnt_M_u16	40691
CityParkInputMsgTimer_mS_M_u32	2637713408
CityParkInputValidCount_Cnt_M_u16	1

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2668229376
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	15716
ComputerRazGCTSigInvalidTimer_mS_M_u32	591631104
ComputerRazGCTSigValidCount_Cnt_M_u16	13734
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	12735
DMDFCTCPKSigValidCount_Cnt_M_u16	56268
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	37681
DMDRELAXECPKSigValidCount_Cnt_M_u16	19766
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	58975
DateInvalidTimer_mS_M_u32	2747347712
DiagMuxOnAbsentTimer_mS_M_u32	1086653184
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3721208576
ESPNTCEnableTimer_mS_M_u32	2429219584
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	15325
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	5
EffacDefaultDiagTimer_mS_M_u32[1]	55
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	9900
ElecIntTimer_mS_M_u32[1]	11001
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	789832448
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	23350
EtatMTSigValidCount_Cnt_M_u16	38295
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	46072
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	39309
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	63002
ISDAT4V2BSI552MsgTimer_mS_M_u32	2738037504
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	58051
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	50956
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	38295
ISDATBSI3F2MsgTimer_mS_M_u32	2871722752
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	65535
ISDATBSI412MsgLenValidCount_Cnt_M_u16	59647
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	23350
ISDATBSI412MsgTimer_mS_M_u32	2029929216
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	58592
ISDATBSI432MsgLenValidCount_Cnt_M_u16	16145
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	47456
ISDATDIRASentFltAcc_Cnt_M_u16	40932
ISDATDIRASentTimer_mS_M_u32	2741191424
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	41216
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	64857
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	16242
ISDYN2CMMMsgTimer_mS_M_u32	3346854656
ISDYNAASChkSumInvalidCount_Cnt_M_u16	29130
ISDYNAASChkSumValidCount_Cnt_M_u16	29679
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	18700
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	29362
ISDYNAASMsgLenValidCount_Cnt_M_u16	43184
ISDYNAASMsgTimeValidCount_Cnt_M_u16	29130
ISDYNAASMsgTimer_mS_M_u32	449204992
ISDYNABRChkSumInvalidCount_Cnt_M_u16	10572
ISDYNABRChkSumValidCount_Cnt_M_u16	64441
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	53757
ISDYNABRMsgCountValidCount_Cnt_M_u16	42082
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	9617
ISDYNABRMsgLenValidCount_Cnt_M_u16	15334
ISDYNABRMsgTimeValidCount_Cnt_M_u16	5658
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	36355
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	12533
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	38295
ISDYNCMM208MsgTimer_mS_M_u32	372880128

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	36355
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	12533
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	6335
ISDYNCMM388MsgTimer_mS_M_u32	2059391744
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	43204
ISDYNVOLChkSumValidCount_Cnt_M_u16	53081
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	37669
ISDYNVOLMsgCountValidCount_Cnt_M_u16	40370
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	63146
ISDYNVOLMsgLenValidCount_Cnt_M_u16	13599
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	24748
ISDYNVOLMsgTimer_mS_M_u32	454005504
IgnOnTimer_mS_M_u32	385078016
IgnTimeOff_Sec_M_u32	1627458240
ManVehSpd_Kph_M_f32	581.460815
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	205
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	96
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1356399360
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	66
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1136288512
PrevISDATBSI412MsgDLCError_Cnt_M_u08	246
PrevISDATBSI412MsgRxTime_MSec_M_u32	903746304
PrevISDATBSI432MsgDLCError_Cnt_M_u08	52
PrevISDATBSI432MsgRxTime_MSec_M_u32	1831793408
PrevISDATDIRAMsgTxTime_MSec_M_u32	3076657920
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	155
PrevISDYN2CMMMsgRxTime_MSec_M_u32	690004736
PrevISDYNAASMsgDLCError_Cnt_M_u08	49
PrevISDYNAASMsgRxTime_MSec_M_u32	2381681408
PrevISDYNABRMsgDLCError_Cnt_M_u08	163
PrevISDYNABRMsgRxTime_MSec_M_u32	2106315520
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	73
PrevISDYNCMM208MsgRxTime_MSec_M_u32	164532992
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	93
PrevISDYNCMM388MsgRxTime_MSec_M_u32	936768256
PrevISDYNVOLMsgDLCError_Cnt_M_u08	194
PrevISDYNVOLMsgRxTime_MSec_M_u32	628036352
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3496231680
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	351.225189
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	4632
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	10390
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	32869
VitesseVehicleBVRampValidCount_Cnt_M_u16	42659
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	12644
VitesseVehicleBVSigValidCount_Cnt_M_u16	15273
VitesseVehicleBV_Kph_M_f32	647.87561
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	6335
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	22300

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	176.791
k_AASNTCEnableTimeout_mS_u16	9253
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	48856
k_AASNodeTimeout_mS_u16	34710
k_ABSNodeTimeout_mS_u16	43224
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	43167
k_ANGLEVOLANTSigValidThresh_Cnt_u16	42000
k_AngleVolantInvalidThresh_Cnt_u16	22699
k_AngleVolantValidThresh_Cnt_u16	40691
k_BSI552MsgTimeout_mS_u16	27511
k_BSINTCEnableTimeout_mS_u16	31608
k_BSINodeAbsentDiag_Cnt_str.Threshold	12531
k_BSINodeAbsentDiag_Cnt_str.PStep	5565
k_BSINodeAbsentDiag_Cnt_str.NStep	27851
k_BSINodeAbsentTimeout_mS_u16	6601
k_BSINodeTimeout_mS_u16	47456
k_BattOvHi_Volt_f32	14.7798004
k_BattOvLo_Volt_f32	17.0354004
k_BattUvHi_Volt_f32	15.4987001
k_BattUvLo_Volt_f32	8.18760014
k_CAVNTCEnableTimeout_mS_u16	42225
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	65073
k_CAVNodeTimeout_mS_u16	55850
k_CMM388MsgTimeout_mS_u16	21808
k_CMM388NTCEnableTimeout_mS_u16	3580
k_CMMNTCEnableTimeout_mS_u16	34139
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	56808
k_CONSANGLECPKMax_HwDeg_f32	234.287598
k_CONSANGLECPKMin_HwDeg_f32	-591.793579
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	14271
k_CONSANGLECPKSigValidThresh_Cnt_u16	46620
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	55524
k_CPKVehicleSpeedValidThresh_Cnt_u16	2157
k_CityParkInputInvalidThresh_Cnt_u16	49434
k_CityParkInputValidThresh_Cnt_u16	63117
k_ComputerRazGCTSigValidThresh_Cnt_u16	13553
k_CptTemporelSigValidThresh_Cnt_u16	65466
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	50321
k_DMDFCTCPKSigValidThresh_Cnt_u16	6886
k_DMDFCTCPKValidCount_Cnt_u16	14386
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	16242
k_DMDRELAXECPKSigValidThresh_Cnt_u16	55743
k_DMDRelaxeConsistentThresh_Cnt_u16	32013
k_DateValidThresh_Cnt_u16	63002
k_DefaultVehSpd_Kph_f32	199.679199
k_DiagMuxOnAbsentTimeout_mS_u16	19352
k_EMNodeTimeout_mS_u16	39743
k_ESPNTCEnableTimeout_mS_u16	50583
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	28496
k_EtatMTSigInvalidThresh_Cnt_u16	52551
k_EtatMTSigValidThresh_Cnt_u16	13812
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	21483
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	50348
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	16090
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	1892
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	53869
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	52986
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	28929
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	20978
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	43284
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	52526

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	36871
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	9533
k_ISDATDIRASentDiag_Cnt_str.Threshold	19232
k_ISDATDIRASentDiag_Cnt_str.PStep	3193
k_ISDATDIRASentDiag_Cnt_str.NStep	10166
k_ISDATDIRASentTimeout_mS_u16	13080
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	64150
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	26929
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	59955
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	18508
k_ISDYNAASChkSumValidThresh_Cnt_u16	23225
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	28925
k_ISDYNAASMsgCountValidThresh_Cnt_u16	33634
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	32384
k_ISDYNAASMsgLenValidThresh_Cnt_u16	14538
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	11128
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	20215
k_ISDYNABRChkSumValidThresh_Cnt_u16	50636
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	39114
k_ISDYNABRMsgCountValidThresh_Cnt_u16	33679
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	49068
k_ISDYNABRMsgLenValidThresh_Cnt_u16	56029
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	47978
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	58188
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	1875
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	28401
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	62103
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	36124
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	9099
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	17157
k_ISDYNVOLChkSumValidThresh_Cnt_u16	57470
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	2526
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	36845
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	49666
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	48483
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	52888
k_IgnOnTimeout_mS_u16	53457
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	52.0469017
k_PowerCutVehSpdLowThresh_Kph_f32	241.648499
k_PowerCutVehSpdLowTimeout_mS_u16	49313
k_VBattMaxAAS_Volt_f32	0.289200008
k_VBattMaxBSI_Volt_f32	3.05019999
k_VBattMaxCAV_Volt_f32	22.7514
k_VBattMaxCMM388_Volt_f32	6.39799976
k_VBattMaxCMM_Volt_f32	22.1259003
k_VBattMaxESP_Volt_f32	26.4685993
k_VBattMinAAS_Volt_f32	22.927
k_VBattMinBSI_Volt_f32	26.4685993
k_VBattMinCAV_Volt_f32	16.0569
k_VBattMinCMM388_Volt_f32	15.4420996
k_VBattMinCMM_Volt_f32	13.3346996
k_VBattMinESP_Volt_f32	22.1259003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	28744
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	13746
k_VitesseVehicleBVRampValidThresh_Cnt_u16	45605
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	44633
k_VitesseVehicleBVSigValidThresh_Cnt_u16	35698
k_VitesseVehicleBVSpeedPassThresh_kph_f32	256.131287
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	18123
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	36233
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2747347712
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	45704
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3854158080
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	93
target_SrlComInput_Per1_Batt_Volt_f32.value	4.63850021
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2987320064
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	8
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.288653404
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4046836480
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	234
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3105846016
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2870547200
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4012028672
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2906411776
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	224785152
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	933204736
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	44
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	154
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	162
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	208
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2320478976
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	25
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	164
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	178
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	103
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4168930048
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	568750848
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	895488768
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	12
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	176
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	199
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1436836608
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3018
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.683599293
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1044163
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	103.281502
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	28490

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3854158080	3854158080	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	5658	5658	✔
CONSANGLECPK_HwDeg_M_f32	-486.971313	-486.971313 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3854158080	3854158080	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3854158080	3854158080	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3854158080	3854158080	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3854158080	3854158080	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3854158080	3854158080	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3854158080	3854158080	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3854158080	3854158080	✔
ESPNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	5	5	✔
EffacDefaultDiagTimer_mS_M_u32[1]	55	55	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3854158080	3854158080	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	11001	11001	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3854158080	3854158080	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATDIRASentFltAcc_Cnt_M_u16	19232	19232	✔
ISDATDIRASentTimer_mS_M_u32	3854158080	3854158080	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3854158080	3854158080	✔
IgnOnTimer_mS_M_u32	3854158080	3854158080	✔
IgnTimeOff_Sec_M_u32	1627458240	1627458240	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	168	168	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4046836480	4046836480	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	234	234	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3105846016	3105846016	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	194	194	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2870547200	2870547200	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	88	88	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4012028672	4012028672	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3076657920	3076657920	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	94	94	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	224785152	224785152	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	30	30	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	933204736	933204736	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	235	235	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2320478976	2320478976	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	103	103	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4168930048	4168930048	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	568750848	568750848	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	67	67	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	895488768	895488768	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1436836608	1436836608	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	351.225189	351.225189	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	647.87561	647.87561	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	176.791	176.791	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	5658	5658	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1627458240	1627458240	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-486.971313	-486.971313 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.328 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4204919296
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	19416
AASNodeAbsentTimer_mS_M_u32	3030968832
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	11684
ANGLEVOLANTSigValidCount_Cnt_M_u16	61141
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	30421
AngleVolantMsgTimer_mS_M_u32	4204919296
AngleVolantValidCount_Cnt_M_u16	24798
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	143174144
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2431068672
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	4017396224
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1048795648
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	50955
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3592231424
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	52103
CAVNodeAbsentTimer_mS_M_u32	1745848832
CDD_SrlComVehSpd_Kph_G_f32	308.521088
CMM388NTCEnableTimer_mS_M_u32	196856320
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1462077952
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	28325
CMMNodeAbsentTimer_mS_M_u32	99441152
CONSANGLECPKSigInvalidCount_Cnt_M_u16	16464
CONSANGLECPKSigValidCount_Cnt_M_u16	16081
CONSANGLECPK_Cnt_M_u16	56796
CONSANGLECPK_HwDeg_M_f32	-728.174927
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	56796
CPKVehicleSpeedMsgTimer_mS_M_u32	1849752064
CPKVehicleSpeedValidCount_Cnt_M_u16	28643
CityParkInputConsistentCount_Cnt_M_u16	17730
CityParkInputInvalidCount_Cnt_M_u16	46351
CityParkInputMsgTimer_mS_M_u32	4046836480
CityParkInputValidCount_Cnt_M_u16	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2987190784
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	34364
ComputerRazGCTSigInvalidTimer_mS_M_u32	2480933376
ComputerRazGCTSigValidCount_Cnt_M_u16	11255
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	11435
DMDFCTCPKSigValidCount_Cnt_M_u16	8004
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	22230
DMDRELAXECPKSigValidCount_Cnt_M_u16	63879
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	17485
DateInvalidTimer_mS_M_u32	2431068672
DiagMuxOnAbsentTimer_mS_M_u32	1293662720
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1048795648
ESPNTCEnableTimer_mS_M_u32	550103552
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	24018
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	97
EffacDefaultDiagTimer_mS_M_u32[1]	977
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6454
ElecIntTimer_mS_M_u32[1]	8258
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3585022464
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	30727
EtatMTSigValidCount_Cnt_M_u16	2467
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	32642
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	57219
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	34906
ISDAT4V2BSI552MsgTimer_mS_M_u32	105994752
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	44256
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	57540
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	2467
ISDATBSI3F2MsgTimer_mS_M_u32	636074496
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	15719
ISDATBSI412MsgLenValidCount_Cnt_M_u16	22507
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	30727
ISDATBSI412MsgTimer_mS_M_u32	426768896
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	45577
ISDATBSI432MsgLenValidCount_Cnt_M_u16	9270
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	43720
ISDATDIRASentFltAcc_Cnt_M_u16	1852
ISDATDIRASentTimer_mS_M_u32	1849752064
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	21802
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	24798
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36754
ISDYN2CMMMsgTimer_mS_M_u32	3300125184
ISDYNAASChkSumInvalidCount_Cnt_M_u16	266
ISDYNAASChkSumValidCount_Cnt_M_u16	19290
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	2501
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	18130
ISDYNAASMsgLenValidCount_Cnt_M_u16	21914
ISDYNAASMsgTimeValidCount_Cnt_M_u16	266
ISDYNAASMsgTimer_mS_M_u32	676841984
ISDYNABRChkSumInvalidCount_Cnt_M_u16	6150
ISDYNABRChkSumValidCount_Cnt_M_u16	4478
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	27761
ISDYNABRMsgCountValidCount_Cnt_M_u16	17921
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	52919
ISDYNABRMsgLenValidCount_Cnt_M_u16	40056
ISDYNABRMsgTimeValidCount_Cnt_M_u16	56796
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	37073
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	27834
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	2467
ISDYNCMM208MsgTimer_mS_M_u32	3145574912

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	37073
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	27834
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	9900
ISDYNCMM388MsgTimer_mS_M_u32	3463137792
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	53534
ISDYNVOLChkSumValidCount_Cnt_M_u16	28191
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	8313
ISDYNVOLMsgCountValidCount_Cnt_M_u16	61842
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	41323
ISDYNVOLMsgLenValidCount_Cnt_M_u16	30411
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28325
ISDYNVOLMsgTimer_mS_M_u32	3699116544
IgnOnTimer_mS_M_u32	3385805312
IgnTimeOff_Sec_M_u32	827442381
ManVehSpd_Kph_M_f32	205.196106
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	206
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	227
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1826601472
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	33
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1371249152
PrevISDATBSI412MsgDLCError_Cnt_M_u08	82
PrevISDATBSI412MsgRxTime_MSec_M_u32	3859843584
PrevISDATBSI432MsgDLCError_Cnt_M_u08	36
PrevISDATBSI432MsgRxTime_MSec_M_u32	463333888
PrevISDATDIRAMsgTxTime_MSec_M_u32	1904511488
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	64
PrevISDYN2CMMMsgRxTime_MSec_M_u32	176740864
PrevISDYNAASMsgDLCError_Cnt_M_u08	35
PrevISDYNAASMsgRxTime_MSec_M_u32	2613709312
PrevISDYNABRMsgDLCError_Cnt_M_u08	107
PrevISDYNABRMsgRxTime_MSec_M_u32	4127672832
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	152
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3426683392
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	202
PrevISDYNCMM388MsgRxTime_MSec_M_u32	396945920
PrevISDYNVOLMsgDLCError_Cnt_M_u08	247
PrevISDYNVOLMsgRxTime_MSec_M_u32	2606598656
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	725481984
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	278.661499
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	32928
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	60904
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	43449
VitesseVehicleBVRampValidCount_Cnt_M_u16	59329
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	2109
VitesseVehicleBVSigValidCount_Cnt_M_u16	47662
VitesseVehicleBV_Kph_M_f32	544.996582
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	9900
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	40021

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	562.246094
k_AASNTCEnableTimeout_mS_u16	40891
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	55393
k_AASNodeTimeout_mS_u16	53480
k_ABSNodeTimeout_mS_u16	27488
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	8908
k_ANGLEVOLANTSigValidThresh_Cnt_u16	45369
k_AngleVolantInvalidThresh_Cnt_u16	49000
k_AngleVolantValidThresh_Cnt_u16	46351
k_BSI552MsgTimeout_mS_u16	35652
k_BSINTCEnableTimeout_mS_u16	20033
k_BSINodeAbsentDiag_Cnt_str.Threshold	24960
k_BSINodeAbsentDiag_Cnt_str.PStep	56930
k_BSINodeAbsentDiag_Cnt_str.NStep	5241
k_BSINodeAbsentTimeout_mS_u16	50445
k_BSINodeTimeout_mS_u16	43720
k_BattOvHi_Volt_f32	30.3938007
k_BattOvLo_Volt_f32	19.2787991
k_BattUvHi_Volt_f32	1.64040005
k_BattUvLo_Volt_f32	3.35649991
k_CAVNTCEnableTimeout_mS_u16	6933
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	24661
k_CAVNodeTimeout_mS_u16	21740
k_CMM388MsgTimeout_mS_u16	28376
k_CMM388NTCEnableTimeout_mS_u16	29812
k_CMMNTCEnableTimeout_mS_u16	9496
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	14321
k_CONSANGLECPKMax_HwDeg_f32	549.229675
k_CONSANGLECPKMin_HwDeg_f32	-627.176025
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	51628
k_CONSANGLECPKSigValidThresh_Cnt_u16	32597
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	38142
k_CPKVehicleSpeedValidThresh_Cnt_u16	46305
k_CityParkInputInvalidThresh_Cnt_u16	2204
k_CityParkInputValidThresh_Cnt_u16	17730
k_ComputerRazGCTSigValidThresh_Cnt_u16	61014
k_CptTemporelSigValidThresh_Cnt_u16	28346
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	61879
k_DMDFCTCPKSigValidThresh_Cnt_u16	65400
k_DMDFCTCPKValidCount_Cnt_u16	43987
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	36754
k_DMDRELAXECPKSigValidThresh_Cnt_u16	45419
k_DMDRelaxeConsistentThresh_Cnt_u16	32641
k_DateValidThresh_Cnt_u16	34906
k_DefaultVehSpd_Kph_f32	243.879303
k_DiagMuxOnAbsentTimeout_mS_u16	46434
k_EMNodeTimeout_mS_u16	42413
k_ESPNTCEnableTimeout_mS_u16	8739
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	9145
k_EtatMTSigInvalidThresh_Cnt_u16	55317
k_EtatMTSigValidThresh_Cnt_u16	3789
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	65513
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	28261
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	57435
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	765
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	33441
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	54586
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	53670
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	44947
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	13677
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	2208

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	57556
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	61296
k_ISDATDIRASentDiag_Cnt_str.Threshold	47720
k_ISDATDIRASentDiag_Cnt_str.PStep	17950
k_ISDATDIRASentDiag_Cnt_str.NStep	21543
k_ISDATDIRASentTimeout_mS_u16	10914
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	4965
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	30421
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	9295
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	47878
k_ISDYNAASChkSumValidThresh_Cnt_u16	62590
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	36721
k_ISDYNAASMsgCountValidThresh_Cnt_u16	43265
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	59498
k_ISDYNAASMsgLenValidThresh_Cnt_u16	36172
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	47873
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	27269
k_ISDYNABRChkSumValidThresh_Cnt_u16	5830
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	59915
k_ISDYNABRMsgCountValidThresh_Cnt_u16	64124
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	20901
k_ISDYNABRMsgLenValidThresh_Cnt_u16	32978
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	32491
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	56580
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	53295
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	18135
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	20644
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	20949
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	34631
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	25881
k_ISDYNVOLChkSumValidThresh_Cnt_u16	11630
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	14287
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	9442
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	29603
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	49727
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	30432
k_IgnOnTimeout_mS_u16	60341
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	79.2762985
k_PowerCutVehSpdLowThresh_Kph_f32	254.471603
k_PowerCutVehSpdLowTimeout_mS_u16	47687
k_VBattMaxAAS_Volt_f32	4.9224
k_VBattMaxBSI_Volt_f32	32
k_VBattMaxCAV_Volt_f32	30.0585003
k_VBattMaxCMM388_Volt_f32	11.6363001
k_VBattMaxCMM_Volt_f32	18.9475994
k_VBattMaxESP_Volt_f32	24.1917992
k_VBattMinAAS_Volt_f32	9.29339981
k_VBattMinBSI_Volt_f32	24.1917992
k_VBattMinCAV_Volt_f32	17.2385998
k_VBattMinCMM388_Volt_f32	29.9754009
k_VBattMinCMM_Volt_f32	10.3554001
k_VBattMinESP_Volt_f32	18.9475994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	64079
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	2772
k_VitesseVehicleBVRampValidThresh_Cnt_u16	50041
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	53535
k_VitesseVehicleBVSigValidThresh_Cnt_u16	23187
k_VitesseVehicleBVSpeedPassThresh_kph_f32	172.318298
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	28295
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	19215
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2431068672
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	2529
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	282421248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	202
target_SrlComInput_Per1_Batt_Volt_f32.value	24.3241005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4173208064
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	84
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.467589974
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	157
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3272165888
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	230
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2580310528
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	845122048
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	348301824
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3371551232
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3606637056
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	82
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3335260672
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	115
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	132
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	926657024
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	57
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	71
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	153
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	183
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	223
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	62
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2301905408
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	997681664
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	4
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1871350272
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	83
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	90
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	165
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1140693504
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	243
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.816385984
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	68137
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	121.822403
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	45322

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	282421248	282421248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	282421248	282421248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	282421248	282421248	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	282421248	282421248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	282421248	282421248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	282421248	282421248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	56796	56796	✔
CONSANGLECPK_HwDeg_M_f32	-728.174927	-728.174927 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	282421248	282421248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	282421248	282421248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	282421248	282421248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	282421248	282421248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	282421248	282421248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	282421248	282421248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	282421248	282421248	✔
ESPNTCEnableTimer_mS_M_u32	282421248	282421248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	97	97	✔
EffacDefaultDiagTimer_mS_M_u32[1]	977	977	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	6454	6454	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	8258	8258	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	282421248	282421248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	47720	47720	✔
ISDATDIRASentTimer_mS_M_u32	282421248	282421248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	282421248	282421248	✔
IgnOnTimer_mS_M_u32	3385805312	3385805312	✔
IgnTimeOff_Sec_M_u32	827442381	827442381	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	157	157	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3272165888	3272165888	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	230	230	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2580310528	2580310528	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	173	173	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	845122048	845122048	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	121	121	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	348301824	348301824	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1904511488	1904511488	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	68	68	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3606637056	3606637056	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	82	82	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3335260672	3335260672	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	181	181	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	926657024	926657024	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	62	62	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2301905408	2301905408	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	2	2	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	997681664	997681664	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	4	4	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1871350272	1871350272	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1140693504	1140693504	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	278.661499	278.661499	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	544.996582	544.996582	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	562.246094	562.246094	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	56796	56796	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	827442381	827442381	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-728.174927	-728.174927 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.329 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3961574656
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	62077
AASNodeAbsentTimer_mS_M_u32	3318482176
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	7959
ANGLEVOLANTSigValidCount_Cnt_M_u16	26950
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	42374
AngleVolantMsgTimer_mS_M_u32	3961574656
AngleVolantValidCount_Cnt_M_u16	62442
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	4180460800
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	4195435776
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	539555072
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3724326144
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	44770
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2922345728
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	62961
CAVNodeAbsentTimer_mS_M_u32	236463360
CDD_SrlComVehSpd_Kph_G_f32	59.6554985
CMM388NTCEnableTimer_mS_M_u32	605250816
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	416687360
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	9045
CMMNodeAbsentTimer_mS_M_u32	2948510976
CONSANGLECPKSigInvalidCount_Cnt_M_u16	17940
CONSANGLECPKSigValidCount_Cnt_M_u16	6227
CONSANGLECPK_Cnt_M_u16	10034
CONSANGLECPK_HwDeg_M_f32	-403.29361
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	10034
CPKVehicleSpeedMsgTimer_mS_M_u32	3443774720
CPKVehicleSpeedValidCount_Cnt_M_u16	23941
CityParkInputConsistentCount_Cnt_M_u16	54974

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	19543
CityParkInputMsgTimer_mS_M_u32	3272165888
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1570768128
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	54097
ComputerRazGCTSigInvalidTimer_mS_M_u32	1822860544
ComputerRazGCTSigValidCount_Cnt_M_u16	13983
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	21891
DMDFCTCPKSigValidCount_Cnt_M_u16	43897
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	60289
DMDRELAXECPKSigValidCount_Cnt_M_u16	37168
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	28189
DateInvalidTimer_mS_M_u32	4195435776
DiagMuxOnAbsentTimer_mS_M_u32	196318464
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3724326144
ESPNTCEnableTimer_mS_M_u32	1164510464
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	54160
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	4
EffacDefaultDiagTimer_mS_M_u32[1]	6
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8976
ElecIntTimer_mS_M_u32[1]	15235
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2004448512
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	7217
EtatMTSigValidCount_Cnt_M_u16	42268
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	53374
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	32317
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	18487
ISDAT4V2BSI552MsgTimer_mS_M_u32	1049801984
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	6949
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	56632
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	42268
ISDATBSI3F2MsgTimer_mS_M_u32	961123584
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	42818
ISDATBSI412MsgLenValidCount_Cnt_M_u16	57541
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	7217
ISDATBSI412MsgTimer_mS_M_u32	1203164416
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	59689
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	39982
ISDATDIRASentFltAcc_Cnt_M_u16	22226
ISDATDIRASentTimer_mS_M_u32	3443774720
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	31048
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	62442
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	35022
ISDYN2CMMMsgTimer_mS_M_u32	2175468800
ISDYNAASChkSumInvalidCount_Cnt_M_u16	6887
ISDYNAASChkSumValidCount_Cnt_M_u16	18870
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	21813
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	28688
ISDYNAASMsgLenValidCount_Cnt_M_u16	12663
ISDYNAASMsgTimeValidCount_Cnt_M_u16	6887
ISDYNAASMsgTimer_mS_M_u32	1044342016
ISDYNABRChkSumInvalidCount_Cnt_M_u16	7539
ISDYNABRChkSumValidCount_Cnt_M_u16	57034
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	13490
ISDYNABRMsgCountValidCount_Cnt_M_u16	46529
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	63199
ISDYNABRMsgLenValidCount_Cnt_M_u16	23390
ISDYNABRMsgTimeValidCount_Cnt_M_u16	10034
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	32322

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	40006
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	42268
ISDYNCMM208MsgTimer_mS_M_u32	4098737408
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	32322
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	40006
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	23168
ISDYNCMM388MsgTimer_mS_M_u32	4194624768
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	19370
ISDYNVOLChkSumValidCount_Cnt_M_u16	17001
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	12825
ISDYNVOLMsgCountValidCount_Cnt_M_u16	60559
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	44229
ISDYNVOLMsgLenValidCount_Cnt_M_u16	31331
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	9045
ISDYNVOLMsgTimer_mS_M_u32	47359232
IgnOnTimer_mS_M_u32	2547574016
IgnTimeOff_Sec_M_u32	3098210453
ManVehSpd_Kph_M_f32	184.3936
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	207
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	102
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3160904960
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	252
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3579049216
PrevISDATBSI412MsgDLCError_Cnt_M_u08	133
PrevISDATBSI412MsgRxTime_MSec_M_u32	3625264384
PrevISDATBSI432MsgDLCError_Cnt_M_u08	110
PrevISDATBSI432MsgRxTime_MSec_M_u32	2766996736
PrevISDATDIRAMsgTxTime_MSec_M_u32	96019712
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	37
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1877751040
PrevISDYNAASMsgDLCError_Cnt_M_u08	145
PrevISDYNAASMsgRxTime_MSec_M_u32	2095621376
PrevISDYNABRMsgDLCError_Cnt_M_u08	218
PrevISDYNABRMsgRxTime_MSec_M_u32	4080067840
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	242
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4287210752
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	19
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2630616320
PrevISDYNVOLMsgDLCError_Cnt_M_u08	121
PrevISDYNVOLMsgRxTime_MSec_M_u32	741221632
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3394032896
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	503.042603
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	31398
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	8333
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	41819
VitesseVehicleBVRampValidCount_Cnt_M_u16	55042
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	13132
VitesseVehicleBVSigValidCount_Cnt_M_u16	43835

Name	Input Value
VitesseVehicleBV_Kph_M_f32	173.217606
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	23168
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	26439
VitesseVehiculeRoues_Kph_M_f32	371.442291
k_AASNTCEnableTimeout_mS_u16	7573
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	22881
k_AASNodeTimeout_mS_u16	30605
k_ABSNodeTimeout_mS_u16	44388
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	25312
k_ANGLEVOLANTSigValidThresh_Cnt_u16	13659
k_AngleVolantInvalidThresh_Cnt_u16	34510
k_AngleVolantValidThresh_Cnt_u16	19543
k_BSI552MsgTimeout_mS_u16	5754
k_BSINTCEnableTimeout_mS_u16	62593
k_BSINodeAbsentDiag_Cnt_str.Threshold	57269
k_BSINodeAbsentDiag_Cnt_str.PStep	59214
k_BSINodeAbsentDiag_Cnt_str.NStep	37706
k_BSINodeAbsentTimeout_mS_u16	39646
k_BSINodeTimeout_mS_u16	39982
k_BattOvHi_Volt_f32	13.8439999
k_BattOvLo_Volt_f32	27.7334995
k_BattUvHi_Volt_f32	17.3941002
k_BattUvLo_Volt_f32	7.89769983
k_CAVNTCEnableTimeout_mS_u16	45637
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	61319
k_CAVNodeTimeout_mS_u16	30784
k_CMM388MsgTimeout_mS_u16	35197
k_CMM388NTCEnableTimeout_mS_u16	59561
k_CMMNTCEnableTimeout_mS_u16	37501
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	1139
k_CONSANGLECPKMax_HwDeg_f32	164.555496
k_CONSANGLECPKMin_HwDeg_f32	-165.279297
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	29056
k_CONSANGLECPKSigValidThresh_Cnt_u16	48711
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	843
k_CPKVehicleSpeedValidThresh_Cnt_u16	38945
k_CityParkInputInvalidThresh_Cnt_u16	9137
k_CityParkInputValidThresh_Cnt_u16	54974
k_ComputerRazGCTSigValidThresh_Cnt_u16	44739
k_CptTemporelSigValidThresh_Cnt_u16	35670
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	36319
k_DMDFCTCPKSigValidThresh_Cnt_u16	12894
k_DMDFCTCPKValidCount_Cnt_u16	8330
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	35022
k_DMDRELAXECPKSigValidThresh_Cnt_u16	20740
k_DMDRelaxeConsistentThresh_Cnt_u16	48834
k_DateValidThresh_Cnt_u16	18487
k_DefaultVehSpd_Kph_f32	100.888496
k_DiagMuxOnAbsentTimeout_mS_u16	14496
k_EMNodeTimeout_mS_u16	51709
k_ESPNTCEnableTimeout_mS_u16	25117
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	24859
k_EtatMTSigInvalidThresh_Cnt_u16	55622
k_EtatMTSigValidThresh_Cnt_u16	58077
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	11914
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	41172
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	43379
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	52430
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	43937
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	56086
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	15954

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	8781
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	61181
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	46822
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	52232
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	13684
k_ISDATDIRASentDiag_Cnt_str.Threshold	52110
k_ISDATDIRASentDiag_Cnt_str.PStep	20589
k_ISDATDIRASentDiag_Cnt_str.NStep	35392
k_ISDATDIRASentTimeout_mS_u16	21919
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	56725
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	42374
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	2969
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	13427
k_ISDYNAASChkSumValidThresh_Cnt_u16	13770
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	52146
k_ISDYNAASMsgCountValidThresh_Cnt_u16	36033
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	15431
k_ISDYNAASMsgLenValidThresh_Cnt_u16	53857
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	14339
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	56181
k_ISDYNABRChkSumValidThresh_Cnt_u16	42100
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	17890
k_ISDYNABRMsgCountValidThresh_Cnt_u16	41553
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	31317
k_ISDYNABRMsgLenValidThresh_Cnt_u16	27280
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	37124
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	62842
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	65079
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	37312
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	46615
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	16454
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	46511
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	26489
k_ISDYNVOLChkSumValidThresh_Cnt_u16	11324
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	31129
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	13470
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	39261
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	60232
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	5285
k_IgnOnTimeout_mS_u16	17317
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	113.197601
k_PowerCutVehSpdLowThresh_Kph_f32	171.611603
k_PowerCutVehSpdLowTimeout_mS_u16	65009
k_VBattMaxAAS_Volt_f32	5.15220022
k_VBattMaxBSI_Volt_f32	14.1455002
k_VBattMaxCAV_Volt_f32	15.1766005
k_VBattMaxCMM388_Volt_f32	8.89050007
k_VBattMaxCMM_Volt_f32	21.4710999
k_VBattMaxESP_Volt_f32	16.9209995
k_VBattMinAAS_Volt_f32	6.1868
k_VBattMinBSI_Volt_f32	16.9209995
k_VBattMinCAV_Volt_f32	20.3463001
k_VBattMinCMM388_Volt_f32	15.4580002
k_VBattMinCMM_Volt_f32	20.1450996
k_VBattMinESP_Volt_f32	21.4710999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	20695
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	64777
k_VitesseVehicleBVRampValidThresh_Cnt_u16	18713
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	6505
k_VitesseVehicleBVSigValidThresh_Cnt_u16	6859
k_VitesseVehicleBVSpeedPassThresh_kph_f32	27.9263
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	3313
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	25880
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4195435776
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	57136
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	146705152
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	19
target_SrlComInput_Per1_Batt_Volt_f32.value	8.4684
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	172782848
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	217
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.738255084
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	338355456
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	73499904
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4012385536
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1014940928
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1415931136
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	52
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2665219328
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2212668672
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	94
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	187
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	157
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4178822400
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	26
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	62
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	766108928
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	147
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2338358528
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	161
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2745640192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	131
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	167
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	216
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	224
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2257450240
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3199
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.815938056
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	245736
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	164.809204

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	4456		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	146705152	146705152	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	42374	42374	✔
AngleVolantMsgTimer_mS_M_u32	146705152	146705152	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	146705152	146705152	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	146705152	146705152	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	146705152	146705152	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	146705152	146705152	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	9045	9045	✔
CMMNodeAbsentTimer_mS_M_u32	2665219328	2665219328	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	10034	10034	✔
CONSANGLECPK_HwDeg_M_f32	-403.29361	-403.29361 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	10034	10034	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3443774720	3443774720	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	23941	23941	✔
CityParkInputConsistentCount_Cnt_M_u16	54974	54974	✔
CityParkInputInvalidCount_Cnt_M_u16	19543	19543	✔
CityParkInputMsgTimer_mS_M_u32	146705152	146705152	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	146705152	146705152	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	146705152	146705152	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	146705152	146705152	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	146705152	146705152	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	146705152	146705152	✔
ESPNTCEnableTimer_mS_M_u32	146705152	146705152	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	146705152	146705152	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	6	6	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	146705152	146705152	✔
ElecIntTimer_mS_M_u32[1]	15235	15235	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	146705152	146705152	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATDIRASentFltAcc_Cnt_M_u16	52110	52110	✔
ISDATDIRASentTimer_mS_M_u32	146705152	146705152	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	146705152	146705152	✔
IgnOnTimer_mS_M_u32	2547574016	2547574016	✔
IgnTimeOff_Sec_M_u32	3098210453	3098210453	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	129	129	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	338355456	338355456	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	123	123	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	73499904	73499904	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	59	59	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4012385536	4012385536	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	43	43	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1014940928	1014940928	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	96019712	96019712	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	52	52	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2665219328	2665219328	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	31	31	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2212668672	2212668672	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	157	157	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4178822400	4178822400	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	12	12	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	766108928	766108928	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	147	147	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2338358528	2338358528	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	161	161	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2745640192	2745640192	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2257450240	2257450240	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	503.042603	503.042603	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	173.217606	173.217606	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	371.442291	371.442291	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	10034	10034	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3098210453	3098210453	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-403.29361	-403.29361 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	100.888496	100.888496	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.330 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	953172992
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	14266
AASNodeAbsentTimer_mS_M_u32	2492380160
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	15339
ANGLEVOLANTSigValidCount_Cnt_M_u16	46111
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	33439
AngleVolantMsgTimer_mS_M_u32	953172992
AngleVolantValidCount_Cnt_M_u16	29169
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1835824128
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2629760000
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1698161664
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	717005824
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	30858
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	4112802816
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	42462
CAVNodeAbsentTimer_mS_M_u32	2485801984
CDD_SrlComVehSpd_Kph_G_f32	519.544006
CMM388NTCEnableTimer_mS_M_u32	1329107968
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3958395904
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	55666
CMMNodeAbsentTimer_mS_M_u32	1031185408
CONSANGLECPKSigInvalidCount_Cnt_M_u16	43509
CONSANGLECPKSigValidCount_Cnt_M_u16	51704
CONSANGLECPK_Cnt_M_u16	55643
CONSANGLECPK_HwDeg_M_f32	501.188507
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	55643
CPKVehicleSpeedMsgTimer_mS_M_u32	3781641216
CPKVehicleSpeedValidCount_Cnt_M_u16	4394
CityParkInputConsistentCount_Cnt_M_u16	6517
CityParkInputInvalidCount_Cnt_M_u16	27053
CityParkInputMsgTimer_mS_M_u32	338355456

Name	Input Value
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	487764992
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	58686
ComputerRazGCTSigInvalidTimer_mS_M_u32	3531527168
ComputerRazGCTSigValidCount_Cnt_M_u16	48594
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	65065
DMDFCTCPKSigValidCount_Cnt_M_u16	29445
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	65197
DMDRELAXECPKSigValidCount_Cnt_M_u16	25697
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	38362
DateInvalidTimer_mS_M_u32	2629760000
DiagMuxOnAbsentTimer_mS_M_u32	2501379072
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	717005824
ESPNTCEnableTimer_mS_M_u32	3384259584
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	20354
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	19
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	5
ElecIntTimer_mS_M_u32[1]	56
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1095132160
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	45021
EtatMTSigValidCount_Cnt_M_u16	23517
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	12983
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	49210
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	5323
ISDAT4V2BSI552MsgTimer_mS_M_u32	3774522368
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	55938
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	31498
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	23517
ISDATBSI3F2MsgTimer_mS_M_u32	3830842368
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	15146
ISDATBSI412MsgLenValidCount_Cnt_M_u16	13666
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	45021
ISDATBSI412MsgTimer_mS_M_u32	4262347776
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	55286
ISDATBSI432MsgLenValidCount_Cnt_M_u16	65535
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	59175
ISDATDIRASentFltAcc_Cnt_M_u16	18235
ISDATDIRASentTimer_mS_M_u32	3781641216
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	47897
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	29169
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	20552
ISDYN2CMMMsgTimer_mS_M_u32	2633085952
ISDYNAASChkSumInvalidCount_Cnt_M_u16	59004
ISDYNAASChkSumValidCount_Cnt_M_u16	12496
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	14864
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	29569
ISDYNAASMsgLenValidCount_Cnt_M_u16	26125
ISDYNAASMsgTimeValidCount_Cnt_M_u16	59004
ISDYNAASMsgTimer_mS_M_u32	2964624384
ISDYNABRChkSumInvalidCount_Cnt_M_u16	2135
ISDYNABRChkSumValidCount_Cnt_M_u16	47891
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	34075
ISDYNABRMsgCountValidCount_Cnt_M_u16	55471
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	33684
ISDYNABRMsgLenValidCount_Cnt_M_u16	60631
ISDYNABRMsgTimeValidCount_Cnt_M_u16	55643
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	17499
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	54544
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	23517

Name	Input Value
ISDYNCMM208MsgTimer_mS_M_u32	1074361344
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	17499
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	54544
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	5679
ISDYNCMM388MsgTimer_mS_M_u32	1935938560
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	28979
ISDYNVOLChkSumValidCount_Cnt_M_u16	9142
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	16487
ISDYNVOLMsgCountValidCount_Cnt_M_u16	34755
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	55267
ISDYNVOLMsgLenValidCount_Cnt_M_u16	34247
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	55666
ISDYNVOLMsgTimer_mS_M_u32	3220886528
IgnOnTimer_mS_M_u32	3924300800
IgnTimeOff_Sec_M_u32	1252377756
ManVehSpd_Kph_M_f32	44.6994019
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	208
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	37
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1392247808
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	121
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2981553152
PrevISDATBSI412MsgDLCError_Cnt_M_u08	131
PrevISDATBSI412MsgRxTime_MSec_M_u32	1781748736
PrevISDATBSI432MsgDLCError_Cnt_M_u08	176
PrevISDATBSI432MsgRxTime_MSec_M_u32	3140203520
PrevISDATDIRAMsgTxTime_MSec_M_u32	1900499968
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	109
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2465080320
PrevISDYNAASMsgDLCError_Cnt_M_u08	230
PrevISDYNAASMsgRxTime_MSec_M_u32	699978752
PrevISDYNABRMsgDLCError_Cnt_M_u08	171
PrevISDYNABRMsgRxTime_MSec_M_u32	937432064
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	129
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1708512256
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	247
PrevISDYNCMM388MsgRxTime_MSec_M_u32	261010432
PrevISDYNVOLMsgDLCError_Cnt_M_u08	4
PrevISDYNVOLMsgRxTime_MSec_M_u32	300438528
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1313620992
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	96.9781036
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	11199
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	28875
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	50592
VitesseVehicleBVRampValidCount_Cnt_M_u16	24940
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	4940
VitesseVehicleBVSigValidCount_Cnt_M_u16	576
VitesseVehicleBV_Kph_M_f32	335.251404
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	5679

Name	Input Value
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	42651
VitesseVehiculeRoues_Kph_M_f32	303.337494
k_AASNTCEnableTimeout_mS_u16	16946
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	56716
k_AASNodeTimeout_mS_u16	27595
k_ABSNodeTimeout_mS_u16	47750
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	1745
k_ANGLEVOLANTSigValidThresh_Cnt_u16	5665
k_AngleVolantInvalidThresh_Cnt_u16	44488
k_AngleVolantValidThresh_Cnt_u16	27053
k_BSI552MsgTimeout_mS_u16	9474
k_BSINTCEnableTimeout_mS_u16	5614
k_BSINodeAbsentDiag_Cnt_str.Threshold	42368
k_BSINodeAbsentDiag_Cnt_str.PStep	5112
k_BSINodeAbsentDiag_Cnt_str.NStep	9539
k_BSINodeAbsentTimeout_mS_u16	663
k_BSINodeTimeout_mS_u16	59175
k_BattOvHi_Volt_f32	19.3353004
k_BattOvLo_Volt_f32	3.53369999
k_BattUvHi_Volt_f32	29.3150997
k_BattUvLo_Volt_f32	5.84859991
k_CAVNTCEnableTimeout_mS_u16	28643
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	37148
k_CAVNodeTimeout_mS_u16	50033
k_CMM388MsgTimeout_mS_u16	29370
k_CMM388NTCEnableTimeout_mS_u16	1334
k_CMMNTCEnableTimeout_mS_u16	54394
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	32535
k_CONSANGLECPKMax_HwDeg_f32	760.80957
k_CONSANGLECPKMin_HwDeg_f32	-714.530884
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	53551
k_CONSANGLECPKSigValidThresh_Cnt_u16	41371
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	16529
k_CPKVehicleSpeedValidThresh_Cnt_u16	42125
k_CityParkInputInvalidThresh_Cnt_u16	28061
k_CityParkInputValidThresh_Cnt_u16	6517
k_ComputerRazGCTSigValidThresh_Cnt_u16	6056
k_CptTemporelSigValidThresh_Cnt_u16	26800
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	48788
k_DMDFCTCPKSigValidThresh_Cnt_u16	26583
k_DMDFCTCPKValidCount_Cnt_u16	50066
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	20552
k_DMDRELAXECPKSigValidThresh_Cnt_u16	28260
k_DMDRelaxeConsistentThresh_Cnt_u16	40234
k_DateValidThresh_Cnt_u16	5323
k_DefaultVehSpd_Kph_f32	161.032806
k_DiagMuxOnAbsentTimeout_mS_u16	56593
k_EMNodeTimeout_mS_u16	570
k_ESPNTCEnableTimeout_mS_u16	4442
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	2335
k_EtatMTSigInvalidThresh_Cnt_u16	57566
k_EtatMTSigValidThresh_Cnt_u16	47834
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	31444
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	60084
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	46422
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	43399
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	62415
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	61358
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	48251
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	38731
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	5754

Name	Input Value
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	64063
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	57751
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	58774
k_ISDATDIRASentDiag_Cnt_str.Threshold	26593
k_ISDATDIRASentDiag_Cnt_str.PStep	61445
k_ISDATDIRASentDiag_Cnt_str.NStep	10573
k_ISDATDIRASentTimeout_mS_u16	4051
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	45363
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	33439
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	1254
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	50007
k_ISDYNAASChkSumValidThresh_Cnt_u16	46611
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	49179
k_ISDYNAASMsgCountValidThresh_Cnt_u16	21423
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	64475
k_ISDYNAASMsgLenValidThresh_Cnt_u16	43855
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	44585
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	44498
k_ISDYNABRChkSumValidThresh_Cnt_u16	59797
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	45962
k_ISDYNABRMsgCountValidThresh_Cnt_u16	62718
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	54386
k_ISDYNABRMsgLenValidThresh_Cnt_u16	35458
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	46309
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	2883
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	19019
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	43314
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	30443
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	12063
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	36261
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	38533
k_ISDYNVOLChkSumValidThresh_Cnt_u16	61181
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	49511
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	2455
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	59481
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	14681
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	59265
k_IgnOnTimeout_mS_u16	45569
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	32.6054993
k_PowerCutVehSpdLowThresh_Kph_f32	153.363297
k_PowerCutVehSpdLowTimeout_mS_u16	4382
k_VBattMaxAAS_Volt_f32	9.51229954
k_VBattMaxBSI_Volt_f32	6.31570005
k_VBattMaxCAV_Volt_f32	20.1410999
k_VBattMaxCMM388_Volt_f32	25.6576996
k_VBattMaxCMM_Volt_f32	16.3722
k_VBattMaxESP_Volt_f32	29.4743996
k_VBattMinAAS_Volt_f32	29.9661007
k_VBattMinBSI_Volt_f32	29.4743996
k_VBattMinCAV_Volt_f32	5.50220013
k_VBattMinCMM388_Volt_f32	19.2003002
k_VBattMinCMM_Volt_f32	2.65770006
k_VBattMinESP_Volt_f32	16.3722
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	57197
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	16789
k_VitesseVehicleBVRampValidThresh_Cnt_u16	64359
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	40630
k_VitesseVehicleBVSigValidThresh_Cnt_u16	49486
k_VitesseVehicleBVSpeedPassThresh_kph_f32	623.064209
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	24798
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	36650
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2629760000
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65036
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	163190528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	247
target_SrlComInput_Per1_Batt_Volt_f32.value	4.43219995

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2496488448
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	128
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.265730351
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1022497792
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	248394752
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	17
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	821711872
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1802925056
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2252510208
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1230943232
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2093667328
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	61
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	71
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	88
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	90
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3384243200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	23
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2893353984
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	902902784
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	156
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3481097216
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	97
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	101245952
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1866
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.204625323
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	303458
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	108.020798
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	61305

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	163190528	163190528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	163190528	163190528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	42368	42368	✔
BSINodeAbsentTimer_mS_M_u32	163190528	163190528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CDD_SrlComVehSpd_Kph_G_f32	44.6994019	44.6994019	✔
CMM388NTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	55643	55643	✔
CONSANGLECPK_HwDeg_M_f32	501.188507	501.188507 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	163190528	163190528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	163190528	163190528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	163190528	163190528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	163190528	163190528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	163190528	163190528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	163190528	163190528	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	163190528	163190528	✔
ESPNTCEnableTimer_mS_M_u32	163190528	163190528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔
EffacDefaultDiagTimer_mS_M_u32[1]	19	19	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	5	5	✔
ElecIntTimer_mS_M_u32[1]	56	56	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	163190528	163190528	✔
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	5323	5323	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	23517	23517	✔
ISDATBSI3F2MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	45021	45021	✔
ISDATBSI412MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	59175	59175	✔
ISDATBSI432MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	26593	26593	✔
ISDATDIRASentTimer_mS_M_u32	163190528	163190528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	20552	20552	✔
ISDYN2CMMMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	59004	59004	✔
ISDYNAASMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	55643	55643	✔
ISDYNABRMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	23517	23517	✔
ISDYNCMM208MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	5679	5679	✔
ISDYNCMM388MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	55666	55666	✔
ISDYNVOLMsgTimer_mS_M_u32	163190528	163190528	✔
IgnOnTimer_mS_M_u32	3924300800	3924300800	✔
IgnTimeOff_Sec_M_u32	1252377756	1252377756	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	251	251	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1022497792	1022497792	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	144	144	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	248394752	248394752	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	17	17	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	821711872	821711872	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1802925056	1802925056	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1900499968	1900499968	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	238	238	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1230943232	1230943232	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	240	240	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2093667328	2093667328	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	131	131	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3384243200	3384243200	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	23	23	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2893353984	2893353984	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	3	3	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	902902784	902902784	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	156	156	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3481097216	3481097216	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	101245952	101245952	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	96.9781036	96.9781036	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	335.251404	335.251404	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	303.337494	303.337494	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	55643	55643	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1252377756	1252377756	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	501.188507	501.188507 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	44.6994019	44.6994019	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.331 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2671638272
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	27774
AASNodeAbsentTimer_mS_M_u32	3519194880
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	49644
ANGLEVOLANTSigValidCount_Cnt_M_u16	21777
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	24527
AngleVolantMsgTimer_mS_M_u32	2671638272
AngleVolantValidCount_Cnt_M_u16	601
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3995690752
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3392268032
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3230078720
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1928910592
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	18447
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1656854272
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	47251
CAVNodeAbsentTimer_mS_M_u32	1232062208
CDD_SrlComVehSpd_Kph_G_f32	451.236511
CMM388NTCEnableTimer_mS_M_u32	558171904
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3659384576
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	60055
CMMNodeAbsentTimer_mS_M_u32	2731202304
CONSANGLECPKSigInvalidCount_Cnt_M_u16	52943
CONSANGLECPKSigValidCount_Cnt_M_u16	43651
CONSANGLECPK_Cnt_M_u16	51290
CONSANGLECPK_HwDeg_M_f32	-532.448792
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	51290
CPKVehicleSpeedMsgTimer_mS_M_u32	3245930240
CPKVehicleSpeedValidCount_Cnt_M_u16	45206
CityParkInputConsistentCount_Cnt_M_u16	7117
CityParkInputInvalidCount_Cnt_M_u16	6183
CityParkInputMsgTimer_mS_M_u32	1022497792
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1211541248
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	29682

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2154972928
ComputerRazGCTSigValidCount_Cnt_M_u16	58038
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	19123
DMDFCTCPKSigValidCount_Cnt_M_u16	34783
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	422
DMDRELAXECPKSigValidCount_Cnt_M_u16	52299
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	57120
DateInvalidTimer_mS_M_u32	3392268032
DiagMuxOnAbsentTimer_mS_M_u32	1499903744
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1928910592
ESPNTCEnableTimer_mS_M_u32	373794560
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	62503
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	555
EffacDefaultDiagTimer_mS_M_u32[1]	5555
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	978
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2254149376
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	9301
EtatMTSigValidCount_Cnt_M_u16	19477
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	48265
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	20413
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	14989
ISDAT4V2BSI552MsgTimer_mS_M_u32	3359561472
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	11752
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	38928
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	19477
ISDATBSI3F2MsgTimer_mS_M_u32	3819747072
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	64751
ISDATBSI412MsgLenValidCount_Cnt_M_u16	6663
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	9301
ISDATBSI412MsgTimer_mS_M_u32	3347314432
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	65291
ISDATBSI432MsgLenValidCount_Cnt_M_u16	14043
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	22712
ISDATDIRASentFltAcc_Cnt_M_u16	34940
ISDATDIRASentTimer_mS_M_u32	3245930240
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	39712
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	601
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36950
ISDYN2CMMMsgTimer_mS_M_u32	77178624
ISDYNAASChkSumInvalidCount_Cnt_M_u16	59448
ISDYNAASChkSumValidCount_Cnt_M_u16	34044
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	58876
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	39850
ISDYNAASMsgLenValidCount_Cnt_M_u16	8134
ISDYNAASMsgTimeValidCount_Cnt_M_u16	59448
ISDYNAASMsgTimer_mS_M_u32	3973121792
ISDYNABRChkSumInvalidCount_Cnt_M_u16	1575
ISDYNABRChkSumValidCount_Cnt_M_u16	2484
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	18523
ISDYNABRMsgCountValidCount_Cnt_M_u16	51551
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	32242
ISDYNABRMsgLenValidCount_Cnt_M_u16	32230
ISDYNABRMsgTimeValidCount_Cnt_M_u16	51290
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	63181
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	33902
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	19477
ISDYNCMM208MsgTimer_mS_M_u32	710043392
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	63181
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	33902
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	36255

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3267528448
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	61717
ISDYNVOLChkSumValidCount_Cnt_M_u16	5449
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	64505
ISDYNVOLMsgCountValidCount_Cnt_M_u16	49573
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	7940
ISDYNVOLMsgLenValidCount_Cnt_M_u16	53528
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	60055
ISDYNVOLMsgTimer_mS_M_u32	2818459392
IgnOnTimer_mS_M_u32	1865844480
IgnTimeOff_Sec_M_u32	450514287
ManVehSpd_Kph_M_f32	208.641205
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	96
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	195
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2948249344
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	141
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2534020864
PrevISDATBSI412MsgDLCError_Cnt_M_u08	120
PrevISDATBSI412MsgRxTime_MSec_M_u32	726976256
PrevISDATBSI432MsgDLCError_Cnt_M_u08	59
PrevISDATBSI432MsgRxTime_MSec_M_u32	300656384
PrevISDATDIRAMsgTxTime_MSec_M_u32	1712899840
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	93
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3764672256
PrevISDYNAASMsgDLCError_Cnt_M_u08	185
PrevISDYNAASMsgRxTime_MSec_M_u32	3804514048
PrevISDYNABRMsgDLCError_Cnt_M_u08	147
PrevISDYNABRMsgRxTime_MSec_M_u32	1699645184
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	176
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3798812416
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	194
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1623369472
PrevISDYNVOLMsgDLCError_Cnt_M_u08	225
PrevISDYNVOLMsgRxTime_MSec_M_u32	1211483904
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1321858816
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	308.828888
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	60144
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	30604
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	57677
VitesseVehicleBVRampValidCount_Cnt_M_u16	27049
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	65481
VitesseVehicleBVSigValidCount_Cnt_M_u16	11950
VitesseVehicleBV_Kph_M_f32	534.934021
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	36255
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	47131
VitesseVehiculeRoues_Kph_M_f32	255.074905
k_AASNTCEnableTimeout_mS_u16	43477
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	60296
k_AASNodeTimeout_mS_u16	34444
k_ABSNodeTimeout_mS_u16	51612
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	40570
k_ANGLEVOLANTSigValidThresh_Cnt_u16	56394
k_AngleVolantInvalidThresh_Cnt_u16	29013
k_AngleVolantValidThresh_Cnt_u16	6183
k_BSI552MsgTimeout_mS_u16	39142
k_BSINTCEnableTimeout_mS_u16	9507
k_BSINodeAbsentDiag_Cnt_str.Threshold	17115
k_BSINodeAbsentDiag_Cnt_str.PStep	26550
k_BSINodeAbsentDiag_Cnt_str.NStep	62485
k_BSINodeAbsentTimeout_mS_u16	49127
k_BSINodeTimeout_mS_u16	22712
k_BattOvHi_Volt_f32	27.6788006
k_BattOvLo_Volt_f32	29.9834995
k_BattUvHi_Volt_f32	0.849799991
k_BattUvLo_Volt_f32	31.5
k_CAVNTCEnableTimeout_mS_u16	23941
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	28377
k_CAVNodeTimeout_mS_u16	29275
k_CMM388MsgTimeout_mS_u16	47998
k_CMM388NTCEnableTimeout_mS_u16	62474
k_CMMNTCEnableTimeout_mS_u16	8192
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	7847
k_CONSANGLECPKMax_HwDeg_f32	401.290497
k_CONSANGLECPKMin_HwDeg_f32	-258.153687
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	23711
k_CONSANGLECPKSigValidThresh_Cnt_u16	50971
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	41018
k_CPKVehicleSpeedValidThresh_Cnt_u16	3270
k_CityParkInputInvalidThresh_Cnt_u16	28245
k_CityParkInputValidThresh_Cnt_u16	7117
k_ComputerRazGCTSigValidThresh_Cnt_u16	36470
k_CptTemporelSigValidThresh_Cnt_u16	59166
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	52466
k_DMDFCTCPKSigValidThresh_Cnt_u16	3302
k_DMDFCTCPKValidCount_Cnt_u16	34551
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	36950
k_DMDRELAXECPKSigValidThresh_Cnt_u16	53698
k_DMDRelaxeConsistentThresh_Cnt_u16	56688
k_DateValidThresh_Cnt_u16	14989
k_DefaultVehSpd_Kph_f32	239.084305
k_DiagMuxOnAbsentTimeout_mS_u16	5432
k_EMNodeTimeout_mS_u16	6656
k_ESPNTCEnableTimeout_mS_u16	26143
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	41103
k_EtatMTSigInvalidThresh_Cnt_u16	22674
k_EtatMTSigValidThresh_Cnt_u16	58975
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	48497
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	6545
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	3114
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	5337
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	33217
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	61283
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	42364
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	32972
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	21375
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	62894
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	52071
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	65194
k_ISDATDIRASentDiag_Cnt_str.Threshold	40598

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	346
k_ISDATDIRASentDiag_Cnt_str.NStep	15969
k_ISDATDIRASentTimeout_mS_u16	57267
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	20435
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	24527
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	47995
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	54567
k_ISDYNAASChkSumValidThresh_Cnt_u16	6324
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	38747
k_ISDYNAASMsgCountValidThresh_Cnt_u16	22623
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	15259
k_ISDYNAASMsgLenValidThresh_Cnt_u16	55296
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	13362
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	30520
k_ISDYNABRChkSumValidThresh_Cnt_u16	65452
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	38671
k_ISDYNABRMsgCountValidThresh_Cnt_u16	52852
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	63895
k_ISDYNABRMsgLenValidThresh_Cnt_u16	17191
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	60095
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	23652
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	37772
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	10839
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	4332
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	58385
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	35903
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	5854
k_ISDYNVOLChkSumValidThresh_Cnt_u16	6454
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	29304
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	11816
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	27361
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	41889
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	6763
k_IgnOnTimeout_mS_u16	46186
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	130.866104
k_PowerCutVehSpdLowThresh_Kph_f32	160.592606
k_PowerCutVehSpdLowTimeout_mS_u16	60689
k_VBattMaxAAS_Volt_f32	3.97099996
k_VBattMaxBSI_Volt_f32	8.2112999
k_VBattMaxCAV_Volt_f32	14.9780998
k_VBattMaxCMM388_Volt_f32	5.45370007
k_VBattMaxCMM_Volt_f32	13.9421997
k_VBattMaxESP_Volt_f32	9.27910042
k_VBattMinAAS_Volt_f32	3.9368
k_VBattMinBSI_Volt_f32	9.27910042
k_VBattMinCAV_Volt_f32	23.2845993
k_VBattMinCMM388_Volt_f32	18.0905991
k_VBattMinCMM_Volt_f32	9.1626997
k_VBattMinESP_Volt_f32	13.9421997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	11557
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	53869
k_VitesseVehicleBVRampValidThresh_Cnt_u16	51961
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	42057
k_VitesseVehicleBVSigValidThresh_Cnt_u16	51266
k_VitesseVehicleBVSpeedPassThresh_kph_f32	115.678596
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	34707
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	22639
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3392268032
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	194
target_SrlComInput_Per1_Batt_Volt_f32.value	1.35119998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1741068032
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	153
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.575120747
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	504923904
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3238274816
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	189
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3003107072
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	22
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2617992960
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	606537472
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4082280192
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	130
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2978891520
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	212
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	163
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3309856512
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	77
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	79
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	150
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	169
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	192
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2609874688
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	250
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	402335488
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2742470400
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1645483776
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3161
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.715662718
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	949294
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	237.870193
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	1986

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	24529	24529	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	51290	51290	✔
CONSANGLECPK_HwDeg_M_f32	-532.448792	-532.448792 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	51290	51290	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3245930240	3245930240	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	45206	45206	✔
CityParkInputConsistentCount_Cnt_M_u16	7117	7117	✔
CityParkInputInvalidCount_Cnt_M_u16	6185	6185	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	555	555	✔
EffacDefaultDiagTimer_mS_M_u32[1]	5555	5555	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2006148864	2006148864	✔
ElecIntTimer_mS_M_u32[1]	978	978	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	40598	40598	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	1865844480	1865844480	✔
IgnTimeOff_Sec_M_u32	450514287	450514287	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	205	205	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	504923904	504923904	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	136	136	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3238274816	3238274816	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	189	189	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3003107072	3003107072	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	22	22	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2617992960	2617992960	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1712899840	1712899840	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	208	208	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4082280192	4082280192	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	130	130	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2978891520	2978891520	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	163	163	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3309856512	3309856512	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2609874688	2609874688	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	250	250	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	402335488	402335488	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	233	233	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2742470400	2742470400	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1645483776	1645483776	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	308.828888	308.828888	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	534.934021	534.934021	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	255.074905	255.074905	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	51290	51290	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	450514287	450514287	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-532.448792	-532.448792 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.332 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1988156928
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	45247
AASNodeAbsentTimer_mS_M_u32	229821952
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	35443
ANGLEVOLANTSigValidCount_Cnt_M_u16	56775
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	23244
AngleVolantMsgTimer_mS_M_u32	1988156928
AngleVolantValidCount_Cnt_M_u16	8623
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3279851008
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4049931776
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	522550784
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4275060224
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	17418
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1115028992
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	2303
CAVNodeAbsentTimer_mS_M_u32	1126919680
CDD_SrlComVehSpd_Kph_G_f32	619.103699
CMM388NTCEnableTimer_mS_M_u32	2695605760
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3374411264
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	3253
CMMNodeAbsentTimer_mS_M_u32	928660992
CONSANGLECPKSigInvalidCount_Cnt_M_u16	24267
CONSANGLECPKSigValidCount_Cnt_M_u16	6255
CONSANGLECPK_Cnt_M_u16	56042
CONSANGLECPK_HwDeg_M_f32	553.473572
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	56042
CPKVehicleSpeedMsgTimer_mS_M_u32	3150962176
CPKVehicleSpeedValidCount_Cnt_M_u16	4927
CityParkInputConsistentCount_Cnt_M_u16	42323
CityParkInputInvalidCount_Cnt_M_u16	59716
CityParkInputMsgTimer_mS_M_u32	504923904
CityParkInputValidCount_Cnt_M_u16	3

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2052509184
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	27235
ComputerRazGCTSigInvalidTimer_mS_M_u32	3357797888
ComputerRazGCTSigValidCount_Cnt_M_u16	13464
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	33184
DMDFCTCPKSigValidCount_Cnt_M_u16	63196
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	13125
DMDRELAXECPKSigValidCount_Cnt_M_u16	57369
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	45528
DateInvalidTimer_mS_M_u32	4049931776
DiagMuxOnAbsentTimer_mS_M_u32	3674643968
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4275060224
ESPNTCEnableTimer_mS_M_u32	2485374464
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	44229
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	963
EffacDefaultDiagTimer_mS_M_u32[1]	7852
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	7
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3215457792
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	10362
EtatMTSigValidCount_Cnt_M_u16	11770
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	64925
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	37057
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	5842
ISDAT4V2BSI552MsgTimer_mS_M_u32	2533244416
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	28482
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	19849
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	11770
ISDATBSI3F2MsgTimer_mS_M_u32	3560218112
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	12076
ISDATBSI412MsgLenValidCount_Cnt_M_u16	46243
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	10362
ISDATBSI412MsgTimer_mS_M_u32	2511265280
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0
ISDATBSI432MsgLenValidCount_Cnt_M_u16	45673
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	64656
ISDATDIRASentFltAcc_Cnt_M_u16	32068
ISDATDIRASentTimer_mS_M_u32	3150962176
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	64152
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	8623
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	64695
ISDYN2CMMMsgTimer_mS_M_u32	2435698176
ISDYNAASChkSumInvalidCount_Cnt_M_u16	42385
ISDYNAASChkSumValidCount_Cnt_M_u16	23556
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	49862
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	31674
ISDYNAASMsgLenValidCount_Cnt_M_u16	56358
ISDYNAASMsgTimeValidCount_Cnt_M_u16	42385
ISDYNAASMsgTimer_mS_M_u32	1845997056
ISDYNABRChkSumInvalidCount_Cnt_M_u16	49475
ISDYNABRChkSumValidCount_Cnt_M_u16	25438
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	53544
ISDYNABRMsgCountValidCount_Cnt_M_u16	56027
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	40290
ISDYNABRMsgLenValidCount_Cnt_M_u16	59974
ISDYNABRMsgTimeValidCount_Cnt_M_u16	56042
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	49474
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	22814
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	11770
ISDYNCMM208MsgTimer_mS_M_u32	4077096448

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	49474
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	22814
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	6109
ISDYNCMM388MsgTimer_mS_M_u32	2452827648
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	36857
ISDYNVOLChkSumValidCount_Cnt_M_u16	28701
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	1486
ISDYNVOLMsgCountValidCount_Cnt_M_u16	57738
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	57390
ISDYNVOLMsgLenValidCount_Cnt_M_u16	38577
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	3253
ISDYNVOLMsgTimer_mS_M_u32	2172644864
IgnOnTimer_mS_M_u32	1557605888
IgnTimeOff_Sec_M_u32	2564302379
ManVehSpd_Kph_M_f32	441.217499
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	97
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	73
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	671784448
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	158
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1738309120
PrevISDATBSI412MsgDLCError_Cnt_M_u08	191
PrevISDATBSI412MsgRxTime_MSec_M_u32	1903980032
PrevISDATBSI432MsgDLCError_Cnt_M_u08	153
PrevISDATBSI432MsgRxTime_MSec_M_u32	825740800
PrevISDATDIRAMsgTxTime_MSec_M_u32	3509612032
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	39
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3297623552
PrevISDYNAASMsgDLCError_Cnt_M_u08	184
PrevISDYNAASMsgRxTime_MSec_M_u32	1764617728
PrevISDYNABRMsgDLCError_Cnt_M_u08	183
PrevISDYNABRMsgRxTime_MSec_M_u32	3666816512
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	129
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1311960576
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	241
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1622330880
PrevISDYNVOLMsgDLCError_Cnt_M_u08	196
PrevISDYNVOLMsgRxTime_MSec_M_u32	3738791424
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2547834368
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	25.9230003
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	9704
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	27860
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	63185
VitesseVehicleBVRampValidCount_Cnt_M_u16	19069
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	34012
VitesseVehicleBVSigValidCount_Cnt_M_u16	1264
VitesseVehicleBV_Kph_M_f32	462.872894
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	6109
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1320

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	460.232697
k_AASNTCEnableTimeout_mS_u16	57977
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	57890
k_AASNodeTimeout_mS_u16	16340
k_ABSNodeTimeout_mS_u16	59621
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	15628
k_ANGLEVOLANTSigValidThresh_Cnt_u16	16476
k_AngleVolantInvalidThresh_Cnt_u16	27963
k_AngleVolantValidThresh_Cnt_u16	59716
k_BSI552MsgTimeout_mS_u16	20167
k_BSINTCEnableTimeout_mS_u16	36113
k_BSINodeAbsentDiag_Cnt_str.Threshold	36502
k_BSINodeAbsentDiag_Cnt_str.PStep	53062
k_BSINodeAbsentDiag_Cnt_str.NStep	59754
k_BSINodeAbsentTimeout_mS_u16	39556
k_BSINodeTimeout_mS_u16	64656
k_BattOvHi_Volt_f32	23.6651993
k_BattOvLo_Volt_f32	22.0513
k_BattUvHi_Volt_f32	29.8209991
k_BattUvLo_Volt_f32	20.9221001
k_CAVNTCEnableTimeout_mS_u16	4394
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	32301
k_CAVNodeTimeout_mS_u16	42023
k_CMM388MsgTimeout_mS_u16	50111
k_CMM388NTCEnableTimeout_mS_u16	18971
k_CMMNTCEnableTimeout_mS_u16	63738
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	388
k_CONSANGLECPKMax_HwDeg_f32	267.305206
k_CONSANGLECPKMin_HwDeg_f32	-444.9646
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	43741
k_CONSANGLECPKSigValidThresh_Cnt_u16	55336
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	10954
k_CPKVehicleSpeedValidThresh_Cnt_u16	7079
k_CityParkInputInvalidThresh_Cnt_u16	49337
k_CityParkInputValidThresh_Cnt_u16	42323
k_ComputerRazGCTSigValidThresh_Cnt_u16	1432
k_CptTemporelSigValidThresh_Cnt_u16	6239
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	45154
k_DMDFCTCPKSigValidThresh_Cnt_u16	15686
k_DMDFCTCPKValidCount_Cnt_u16	10066
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	64695
k_DMDRELAXECPKSigValidThresh_Cnt_u16	25907
k_DMDRelaxeConsistentThresh_Cnt_u16	31273
k_DateValidThresh_Cnt_u16	5842
k_DefaultVehSpd_Kph_f32	237.476501
k_DiagMuxOnAbsentTimeout_mS_u16	60496
k_EMNodeTimeout_mS_u16	33080
k_ESPNTCEnableTimeout_mS_u16	12379
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	7116
k_EtatMTSigInvalidThresh_Cnt_u16	13826
k_EtatMTSigValidThresh_Cnt_u16	14685
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	28453
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	22404
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	34876
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	48751
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	38006
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	10192
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	45062
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	56022
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	29181
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	41710

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	32389
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	9978
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	25759
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	6015
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	23244
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	41031
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	21571
k_ISDYNAASChkSumValidThresh_Cnt_u16	13918
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	58408
k_ISDYNAASMsgCountValidThresh_Cnt_u16	11739
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	61671
k_ISDYNAASMsgLenValidThresh_Cnt_u16	7032
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	55460
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	18832
k_ISDYNABRChkSumValidThresh_Cnt_u16	64756
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	22282
k_ISDYNABRMsgCountValidThresh_Cnt_u16	48542
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	57269
k_ISDYNABRMsgLenValidThresh_Cnt_u16	49093
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	21693
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	41356
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	8021
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	16499
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	40307
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	12487
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	60668
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	23903
k_ISDYNVOLChkSumValidThresh_Cnt_u16	13078
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	46546
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	50690
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	34006
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	22358
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	28472
k_IgnOnTimeout_mS_u16	46267
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	250.631302
k_PowerCutVehSpdLowThresh_Kph_f32	9.45160007
k_PowerCutVehSpdLowTimeout_mS_u16	2245
k_VBattMaxAAS_Volt_f32	28.9155006
k_VBattMaxBSI_Volt_f32	32
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	6.7105999
k_VBattMaxCMM_Volt_f32	6.34950018
k_VBattMaxESP_Volt_f32	15.408
k_VBattMinAAS_Volt_f32	10.0365
k_VBattMinBSI_Volt_f32	15.408
k_VBattMinCAV_Volt_f32	15.1251001
k_VBattMinCMM388_Volt_f32	22.0058002
k_VBattMinCMM_Volt_f32	26.4566002
k_VBattMinESP_Volt_f32	6.34950018
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	18313
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	62577
k_VitesseVehicleBVRampValidThresh_Cnt_u16	39118
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	49949
k_VitesseVehicleBVSigValidThresh_Cnt_u16	46068
k_VitesseVehicleBVSpeedPassThresh_kph_f32	388.089386
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	39935
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	5675
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	4049931776
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	45704
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3854158080
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSe	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	241
target_SrlComInput_Per1_Batt_Volt_f32.value	22.1625004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2271673856
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	21
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0749983117
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1479618048
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	237
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	636374528
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1182494208
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3252194816
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2684726784
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3909275136
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	176
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2765090304
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	45
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	109
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	179
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	189
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2049019392
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	2
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	122
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	178
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2076978688
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	50
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3171503616
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	286682624
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	78
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	108
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	148
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	238
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2927525376
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1860
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0873580202
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	837632
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	209.868896
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	38770

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3854158080	3854158080	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	56042	56042	✔
CONSANGLECPK_HwDeg_M_f32	553.473572	553.473572 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3854158080	3854158080	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3854158080	3854158080	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3854158080	3854158080	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3854158080	3854158080	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3854158080	3854158080	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3854158080	3854158080	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3854158080	3854158080	✔
ESPNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3854158080	3854158080	✔
EffacDefaultDiagTimer_mS_M_u32[1]	7852	7852	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3854158080	3854158080	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	7	7	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3854158080	3854158080	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATDIRASentFltAcc_Cnt_M_u16	41895	41895	✔
ISDATDIRASentTimer_mS_M_u32	3854158080	3854158080	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3854158080	3854158080	✔
IgnOnTimer_mS_M_u32	3854158080	3854158080	✔
IgnTimeOff_Sec_M_u32	2564302379	2564302379	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	133	133	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1479618048	1479618048	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	237	237	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	636374528	636374528	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	35	35	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1182494208	1182494208	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	48	48	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3252194816	3252194816	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3509612032	3509612032	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	238	238	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3909275136	3909275136	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	176	176	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2765090304	2765090304	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	189	189	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2049019392	2049019392	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	183	183	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2076978688	2076978688	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	50	50	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3171503616	3171503616	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	60	60	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	286682624	286682624	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2927525376	2927525376	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	25.9230003	25.9230003	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	462.872894	462.872894	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	460.232697	460.232697	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	56042	56042	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2564302379	2564302379	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	553.473572	553.473572 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.333 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	18098432
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	27736
AASNodeAbsentTimer_mS_M_u32	2940098816
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	20795
ANGLEVOLANTSigValidCount_Cnt_M_u16	12544
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	57905
AngleVolantMsgTimer_mS_M_u32	18098432
AngleVolantValidCount_Cnt_M_u16	33288
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1826298112
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2636617984
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3785771264
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1571162368
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	16502
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1505020160
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	44566
CAVNodeAbsentTimer_mS_M_u32	961837312
CDD_SrlComVehSpd_Kph_G_f32	349.731903
CMM388NTCEnableTimer_mS_M_u32	1909700864
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	4285692160
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	54709
CMMNodeAbsentTimer_mS_M_u32	1544030464
CONSANGLECPKSigInvalidCount_Cnt_M_u16	58163
CONSANGLECPKSigValidCount_Cnt_M_u16	53257
CONSANGLECPK_Cnt_M_u16	13464
CONSANGLECPK_HwDeg_M_f32	511.362701
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	13464
CPKVehicleSpeedMsgTimer_mS_M_u32	757541120
CPKVehicleSpeedValidCount_Cnt_M_u16	55425
CityParkInputConsistentCount_Cnt_M_u16	34588

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	4168
CityParkInputMsgTimer_mS_M_u32	1479618048
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4182923520
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	53100
ComputerRazGCTSigInvalidTimer_mS_M_u32	745208064
ComputerRazGCTSigValidCount_Cnt_M_u16	11597
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	46900
DMDFCTCPKSigValidCount_Cnt_M_u16	53570
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	7877
DMDRELAXECPKSigValidCount_Cnt_M_u16	61962
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	24076
DateInvalidTimer_mS_M_u32	2636617984
DiagMuxOnAbsentTimer_mS_M_u32	444786944
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1571162368
ESPNTCEnableTimer_mS_M_u32	535517440
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	48967
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	200
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	20
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	706660608
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	10085
EtatMTSigValidCount_Cnt_M_u16	41127
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	52925
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	12051
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	51552
ISDAT4V2BSI552MsgTimer_mS_M_u32	3441166592
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	10383
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	14201
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	41127
ISDATBSI3F2MsgTimer_mS_M_u32	1727588608
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	25041
ISDATBSI412MsgLenValidCount_Cnt_M_u16	15146
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	10085
ISDATBSI412MsgTimer_mS_M_u32	3683264768
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	65535
ISDATBSI432MsgLenValidCount_Cnt_M_u16	15963
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	22371
ISDATDIRASentFltAcc_Cnt_M_u16	42311
ISDATDIRASentTimer_mS_M_u32	757541120
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	3470
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	33288
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	25071
ISDYN2CMMMsgTimer_mS_M_u32	3503118592
ISDYNAASChkSumInvalidCount_Cnt_M_u16	21986
ISDYNAASChkSumValidCount_Cnt_M_u16	35912
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	47811
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	485
ISDYNAASMsgLenValidCount_Cnt_M_u16	6755
ISDYNAASMsgTimeValidCount_Cnt_M_u16	21986
ISDYNAASMsgTimer_mS_M_u32	2042607872
ISDYNABRChkSumInvalidCount_Cnt_M_u16	41549
ISDYNABRChkSumValidCount_Cnt_M_u16	46522
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	61213
ISDYNABRMsgCountValidCount_Cnt_M_u16	11203
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	17262
ISDYNABRMsgLenValidCount_Cnt_M_u16	30340
ISDYNABRMsgTimeValidCount_Cnt_M_u16	13464
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	60544

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	25259
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	41127
ISDYNCMM208MsgTimer_mS_M_u32	843847936
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	60544
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	25259
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	55166
ISDYNCMM388MsgTimer_mS_M_u32	456997120
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	34729
ISDYNVOLChkSumValidCount_Cnt_M_u16	255
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	25258
ISDYNVOLMsgCountValidCount_Cnt_M_u16	18744
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	2316
ISDYNVOLMsgLenValidCount_Cnt_M_u16	32578
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	54709
ISDYNVOLMsgTimer_mS_M_u32	1884748032
IgnOnTimer_mS_M_u32	1263614208
IgnTimeOff_Sec_M_u32	880694048
ManVehSpd_Kph_M_f32	318.707489
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	98
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	198
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1131866368
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	179
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2755741952
PrevISDATBSI412MsgDLCError_Cnt_M_u08	165
PrevISDATBSI412MsgRxTime_MSec_M_u32	845248768
PrevISDATBSI432MsgDLCError_Cnt_M_u08	171
PrevISDATBSI432MsgRxTime_MSec_M_u32	2561628416
PrevISDATDIRAMsgTxTime_MSec_M_u32	3812980992
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	43
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3798829312
PrevISDYNAASMsgDLCError_Cnt_M_u08	130
PrevISDYNAASMsgRxTime_MSec_M_u32	4048353536
PrevISDYNABRMsgDLCError_Cnt_M_u08	226
PrevISDYNABRMsgRxTime_MSec_M_u32	2989046016
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	37
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2520643840
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	230
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3057539328
PrevISDYNVOLMsgDLCError_Cnt_M_u08	218
PrevISDYNVOLMsgRxTime_MSec_M_u32	2655680768
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	218114304
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	596.104797
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	15195
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	41049
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	44192
VitesseVehicleBVRampValidCount_Cnt_M_u16	60254
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	17920
VitesseVehicleBVSigValidCount_Cnt_M_u16	40837

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBV_Kph_M_f32	533.839294
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	55166
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	51547
VitesseVehiculeRoues_Kph_M_f32	443.05249
k_AASNTCEnableTimeout_mS_u16	6635
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	52399
k_AASNodeTimeout_mS_u16	10073
k_ABSNodeTimeout_mS_u16	54629
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	24752
k_ANGLEVOLANTSigValidThresh_Cnt_u16	8322
k_AngleVolantInvalidThresh_Cnt_u16	54757
k_AngleVolantValidThresh_Cnt_u16	4168
k_BSI552MsgTimeout_mS_u16	10366
k_BSINTCEnableTimeout_mS_u16	50337
k_BSINodeAbsentDiag_Cnt_str.Threshold	28674
k_BSINodeAbsentDiag_Cnt_str.PStep	41011
k_BSINodeAbsentDiag_Cnt_str.NStep	5128
k_BSINodeAbsentTimeout_mS_u16	777
k_BSINodeTimeout_mS_u16	22371
k_BattOvHi_Volt_f32	11.2496004
k_BattOvLo_Volt_f32	0.190300003
k_BattUvHi_Volt_f32	20.7754002
k_BattUvLo_Volt_f32	20.2723007
k_CAVNTCEnableTimeout_mS_u16	45206
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	34444
k_CAVNodeTimeout_mS_u16	33567
k_CMM388MsgTimeout_mS_u16	13144
k_CMM388NTCEnableTimeout_mS_u16	4164
k_CMMNTCEnableTimeout_mS_u16	27495
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	17479
k_CONSANGLECPKMax_HwDeg_f32	548.326172
k_CONSANGLECPKMin_HwDeg_f32	-161.056702
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	7806
k_CONSANGLECPKSigValidThresh_Cnt_u16	20571
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	48759
k_CPKVehicleSpeedValidThresh_Cnt_u16	18528
k_CityParkInputInvalidThresh_Cnt_u16	64491
k_CityParkInputValidThresh_Cnt_u16	34588
k_ComputerRazGCTSigValidThresh_Cnt_u16	15757
k_CptTemporelSigValidThresh_Cnt_u16	44791
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	2670
k_DMDFCTCPKSigValidThresh_Cnt_u16	32132
k_DMDFCTCPKValidCount_Cnt_u16	46750
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	25071
k_DMDRELAXECPKSigValidThresh_Cnt_u16	41533
k_DMDRelaxeConsistentThresh_Cnt_u16	47963
k_DateValidThresh_Cnt_u16	51552
k_DefaultVehSpd_Kph_f32	104.659302
k_DiagMuxOnAbsentTimeout_mS_u16	6246
k_EMNodeTimeout_mS_u16	28652
k_ESPNTCEnableTimeout_mS_u16	43010
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	5487
k_EtatMTSigInvalidThresh_Cnt_u16	16
k_EtatMTSigValidThresh_Cnt_u16	61373
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	7526
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	28168
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	49761
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	12040
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	22194
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	2021
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	28610

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	47380
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	50653
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	60556
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	17286
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	33638
k_ISDATDIRASentDiag_Cnt_str.Threshold	1170
k_ISDATDIRASentDiag_Cnt_str.PStep	4955
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	10297
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	1495
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	57905
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	2110
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	59725
k_ISDYNAASChkSumValidThresh_Cnt_u16	15546
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	46621
k_ISDYNAASMsgCountValidThresh_Cnt_u16	12995
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	41825
k_ISDYNAASMsgLenValidThresh_Cnt_u16	9325
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	30634
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	30436
k_ISDYNABRChkSumValidThresh_Cnt_u16	30330
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	1910
k_ISDYNABRMsgCountValidThresh_Cnt_u16	44411
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	23733
k_ISDYNABRMsgLenValidThresh_Cnt_u16	34375
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	9246
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	22639
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	30038
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	24956
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	6203
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	14336
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	58656
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	25400
k_ISDYNVOLChkSumValidThresh_Cnt_u16	19409
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	6176
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	7630
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	33361
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	38035
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	55342
k_IgnOnTimeout_mS_u16	52516
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	231.695007
k_PowerCutVehSpdLowThresh_Kph_f32	131.233994
k_PowerCutVehSpdLowTimeout_mS_u16	55047
k_VBattMaxAAS_Volt_f32	1.30780005
k_VBattMaxBSI_Volt_f32	9.17819977
k_VBattMaxCAV_Volt_f32	14.4556999
k_VBattMaxCMM388_Volt_f32	22.1931992
k_VBattMaxCMM_Volt_f32	13.9629002
k_VBattMaxESP_Volt_f32	1.57930005
k_VBattMinAAS_Volt_f32	15.8892002
k_VBattMinBSI_Volt_f32	1.57930005
k_VBattMinCAV_Volt_f32	9.22780037
k_VBattMinCMM388_Volt_f32	14.6892996
k_VBattMinCMM_Volt_f32	2.33599997
k_VBattMinESP_Volt_f32	13.9629002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	7609
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	16579
k_VitesseVehicleBVRampValidThresh_Cnt_u16	43434
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	2047
k_VitesseVehicleBVSigValidThresh_Cnt_u16	7993
k_VitesseVehicleBVSpeedPassThresh_kph_f32	161.458893
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	62742
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	49236
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2636617984
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	230
target_SrlComInput_Per1_Batt_Volt_f32.value	27.0237007
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2397161728
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	122
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.154446825
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	1
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1094924544
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3029063936
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	226
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1868855552
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	120
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1506613504
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1539684608
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1565415680
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1181153536
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	205
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2498894080
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	67
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	68
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	94
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	41040128
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	456841472
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	999520512
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	43
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	174
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	207
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3617278208
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3061
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.269106776
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	373225
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	25.2322998

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	36541		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	57905	57905	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	13464	13464	✔
CONSANGLECPK_HwDeg_M_f32	511.362701	511.362701 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	13464	13464	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	757541120	757541120	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	55425	55425	✔
CityParkInputConsistentCount_Cnt_M_u16	34588	34588	✔
CityParkInputInvalidCount_Cnt_M_u16	4170	4170	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	200	200	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3251510528	3251510528	✔
ElecIntTimer_mS_M_u32[1]	20	20	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1170	1170	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	1263614208	1263614208	✔
IgnTimeOff_Sec_M_u32	880694048	880694048	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1094924544	1094924544	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	8	8	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3029063936	3029063936	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	226	226	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1868855552	1868855552	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	120	120	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1506613504	1506613504	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3812980992	3812980992	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	118	118	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1565415680	1565415680	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	174	174	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1181153536	1181153536	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	53	53	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2498894080	2498894080	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	152	152	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	41040128	41040128	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	456841472	456841472	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	195	195	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	999520512	999520512	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3617278208	3617278208	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	596.104797	596.104797	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	533.839294	533.839294	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	443.05249	443.05249	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	13464	13464	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	880694048	880694048	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	511.362701	511.362701 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.334 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2688960512
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	4216
AASNodeAbsentTimer_mS_M_u32	981972992
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	3025
ANGLEVOLANTSigValidCount_Cnt_M_u16	57152
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	21229
AngleVolantMsgTimer_mS_M_u32	2688960512
AngleVolantValidCount_Cnt_M_u16	38377
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1689352192
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2781607936
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1863313408
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2853218304
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	59936
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1625581568
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	27582
CAVNodeAbsentTimer_mS_M_u32	482695168
CDD_SrlComVehSpd_Kph_G_f32	85.9667969
CMM388NTCEnableTimer_mS_M_u32	2152175616
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3261814784
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	23713
CMMNodeAbsentTimer_mS_M_u32	3068831744
CONSANGLECPKSigInvalidCount_Cnt_M_u16	10471
CONSANGLECPKSigValidCount_Cnt_M_u16	5413
CONSANGLECPK_Cnt_M_u16	58232
CONSANGLECPK_HwDeg_M_f32	-521.335693
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	58232
CPKVehicleSpeedMsgTimer_mS_M_u32	671959040
CPKVehicleSpeedValidCount_Cnt_M_u16	45318

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	54957
CityParkInputInvalidCount_Cnt_M_u16	15401
CityParkInputMsgTimer_mS_M_u32	1094924544
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2890643456
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	14140
ComputerRazGCTSigInvalidTimer_mS_M_u32	3179403264
ComputerRazGCTSigValidCount_Cnt_M_u16	59418
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	63333
DMDFCTCPKSigValidCount_Cnt_M_u16	15356
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	19251
DMDRELAXECPKSigValidCount_Cnt_M_u16	17442
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	23644
DateInvalidTimer_mS_M_u32	2781607936
DiagMuxOnAbsentTimer_mS_M_u32	2130315264
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2853218304
ESPNTCEnableTimer_mS_M_u32	3699423232
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	17068
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	89
EffacDefaultDiagTimer_mS_M_u32[1]	898
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	555
ElecIntTimer_mS_M_u32[1]	5556
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	396781568
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	30864
EtatMTSigValidCount_Cnt_M_u16	28555
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	3657
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	40967
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	19362
ISDAT4V2BSI552MsgTimer_mS_M_u32	3014567936
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	62611
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	51862
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	28555
ISDATBSI3F2MsgTimer_mS_M_u32	4053272576
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	56783
ISDATBSI412MsgLenValidCount_Cnt_M_u16	5250
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	30864
ISDATBSI412MsgTimer_mS_M_u32	1759791104
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	20348
ISDATBSI432MsgLenValidCount_Cnt_M_u16	5488
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	58327
ISDATDIRASentFltAcc_Cnt_M_u16	35371
ISDATDIRASentTimer_mS_M_u32	671959040
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	45206
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	38377
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	41780
ISDYN2CMMMsgTimer_mS_M_u32	3520772096
ISDYNAASChkSumInvalidCount_Cnt_M_u16	64474
ISDYNAASChkSumValidCount_Cnt_M_u16	19305
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	38840
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	27729
ISDYNAASMsgLenValidCount_Cnt_M_u16	30104
ISDYNAASMsgTimeValidCount_Cnt_M_u16	64474
ISDYNAASMsgTimer_mS_M_u32	411277312
ISDYNABRChkSumInvalidCount_Cnt_M_u16	14363
ISDYNABRChkSumValidCount_Cnt_M_u16	4242
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	56361
ISDYNABRMsgCountValidCount_Cnt_M_u16	6392
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	46134
ISDYNABRMsgLenValidCount_Cnt_M_u16	52660
ISDYNABRMsgTimeValidCount_Cnt_M_u16	58232

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	15088
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	7984
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	28555
ISDYNCMM208MsgTimer_mS_M_u32	408844288
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	15088
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	7984
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	60807
ISDYNCMM388MsgTimer_mS_M_u32	168499200
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	37765
ISDYNVOLChkSumValidCount_Cnt_M_u16	55875
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	19715
ISDYNVOLMsgCountValidCount_Cnt_M_u16	11290
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	47453
ISDYNVOLMsgLenValidCount_Cnt_M_u16	35196
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	23713
ISDYNVOLMsgTimer_mS_M_u32	2713573376
IgnOnTimer_mS_M_u32	3385792512
IgnTimeOff_Sec_M_u32	2907156203
ManVehSpd_Kph_M_f32	560.409607
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	99
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	147
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3558737920
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	14
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1396631552
PrevISDATBSI412MsgDLCError_Cnt_M_u08	55
PrevISDATBSI412MsgRxTime_MSec_M_u32	2778617856
PrevISDATBSI432MsgDLCError_Cnt_M_u08	100
PrevISDATBSI432MsgRxTime_MSec_M_u32	2184493056
PrevISDATDIRAMsgTxTime_MSec_M_u32	586307584
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	102
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2579113984
PrevISDYNAASMsgDLCError_Cnt_M_u08	66
PrevISDYNAASMsgRxTime_MSec_M_u32	1994119168
PrevISDYNABRMsgDLCError_Cnt_M_u08	13
PrevISDYNABRMsgRxTime_MSec_M_u32	4115077120
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	100
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2349389824
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	243
PrevISDYNCMM388MsgRxTime_MSec_M_u32	629651456
PrevISDYNVOLMsgDLCError_Cnt_M_u08	199
PrevISDYNVOLMsgRxTime_MSec_M_u32	1172527104
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	746735616
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	8.31589985
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	6127
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	15286
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	6176
VitesseVehicleBVRampValidCount_Cnt_M_u16	44711
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	33154

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	59313
VitesseVehicleBV_Kph_M_f32	387.399414
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	60807
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	60078
VitesseVehiculeRoues_Kph_M_f32	299.541901
k_AASNTCEnableTimeout_mS_u16	16255
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	4596
k_AASNodeTimeout_mS_u16	42678
k_ABSNodeTimeout_mS_u16	41170
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	26544
k_ANGLEVOLANTSigValidThresh_Cnt_u16	51963
k_AngleVolantInvalidThresh_Cnt_u16	63186
k_AngleVolantValidThresh_Cnt_u16	15401
k_BSI552MsgTimeout_mS_u16	6469
k_BSINTCEnableTimeout_mS_u16	16349
k_BSINodeAbsentDiag_Cnt_str.Threshold	60908
k_BSINodeAbsentDiag_Cnt_str.PStep	34456
k_BSINodeAbsentDiag_Cnt_str.NStep	58456
k_BSINodeAbsentTimeout_mS_u16	20581
k_BSINodeTimeout_mS_u16	58327
k_BattOvHi_Volt_f32	6.08409977
k_BattOvLo_Volt_f32	21.9647999
k_BattUvHi_Volt_f32	23.5272999
k_BattUvLo_Volt_f32	9.13549995
k_CAVNTCEnableTimeout_mS_u16	4927
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	14940
k_CAVNodeTimeout_mS_u16	63779
k_CMM388MsgTimeout_mS_u16	47992
k_CMM388NTCEnableTimeout_mS_u16	54452
k_CMMNTCEnableTimeout_mS_u16	35851
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	10730
k_CONSANGLECPKMax_HwDeg_f32	409.755402
k_CONSANGLECPKMin_HwDeg_f32	-622.518677
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	6279
k_CONSANGLECPKSigValidThresh_Cnt_u16	21934
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	55644
k_CPKVehicleSpeedValidThresh_Cnt_u16	9762
k_CityParkInputInvalidThresh_Cnt_u16	9025
k_CityParkInputValidThresh_Cnt_u16	54957
k_ComputerRazGCTSigValidThresh_Cnt_u16	11673
k_CptTemporelSigValidThresh_Cnt_u16	56348
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	24374
k_DMDFCTCPKSigValidThresh_Cnt_u16	47284
k_DMDFCTCPKValidCount_Cnt_u16	10152
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	41780
k_DMDRELAXECPKSigValidThresh_Cnt_u16	29963
k_DMDRelaxeConsistentThresh_Cnt_u16	8625
k_DateValidThresh_Cnt_u16	19362
k_DefaultVehSpd_Kph_f32	4.0328002
k_DiagMuxOnAbsentTimeout_mS_u16	61454
k_EMNodeTimeout_mS_u16	42684
k_ESPNTCEnableTimeout_mS_u16	11770
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	22130
k_EtatMTSigInvalidThresh_Cnt_u16	60114
k_EtatMTSigValidThresh_Cnt_u16	11913
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	14479
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	10602
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	30942
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	1320
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	37099
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	15251

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	634
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	51525
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	11305
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	35740
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	51567
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	24079
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	22103
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	55996
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	21229
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	64838
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	25371
k_ISDYNAASChkSumValidThresh_Cnt_u16	31634
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	34601
k_ISDYNAASMsgCountValidThresh_Cnt_u16	1016
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	34015
k_ISDYNAASMsgLenValidThresh_Cnt_u16	65402
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	25987
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	29140
k_ISDYNABRChkSumValidThresh_Cnt_u16	9682
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	38176
k_ISDYNABRMsgCountValidThresh_Cnt_u16	5583
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	51105
k_ISDYNABRMsgLenValidThresh_Cnt_u16	60844
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	64998
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	4275
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	63296
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	17485
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	46801
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	51776
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	7585
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	13722
k_ISDYNVOLChkSumValidThresh_Cnt_u16	16013
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	56353
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	10326
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	6092
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	17351
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	55096
k_IgnOnTimeout_mS_u16	42966
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	147.425903
k_PowerCutVehSpdLowThresh_Kph_f32	104.808701
k_PowerCutVehSpdLowTimeout_mS_u16	30763
k_VBattMaxAAS_Volt_f32	22.8903999
k_VBattMaxBSI_Volt_f32	11.7187004
k_VBattMaxCAV_Volt_f32	13.3206997
k_VBattMaxCMM388_Volt_f32	31.4228001
k_VBattMaxCMM_Volt_f32	18.0540009
k_VBattMaxESP_Volt_f32	10.8288002
k_VBattMinAAS_Volt_f32	6.31330013
k_VBattMinBSI_Volt_f32	10.8288002
k_VBattMinCAV_Volt_f32	0.483900011
k_VBattMinCMM388_Volt_f32	4.78900003
k_VBattMinCMM_Volt_f32	5.85169983
k_VBattMinESP_Volt_f32	18.0540009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	39702
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	46265
k_VitesseVehicleBVRampValidThresh_Cnt_u16	30723
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	50499
k_VitesseVehicleBVSigValidThresh_Cnt_u16	49750
k_VitesseVehicleBVSpeedPassThresh_kph_f32	13.0334997
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	38590
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	34757
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2781607936
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65036
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	163190528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	243
target_SrlComInput_Per1_Batt_Volt_f32.value	16.5552998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3042797568
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	48
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.372707665
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	804853760
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	71
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1084176384
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3130349568
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3856365568
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	175216640
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1884796928
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	138
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1603131392
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	97
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	135
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	230
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	239
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	234
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	141326336
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	133
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	184
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	186
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	196
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	213
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	215
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	201
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1751914496
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	175
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2291283968
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	27
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3523762176
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	19
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	133
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	172
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	196
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2704336896
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	528
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.122436069
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1036544
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	217.063797
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	9673

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	163190528	163190528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	163190528	163190528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	163190528	163190528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	58232	58232	✔
CONSANGLECPK_HwDeg_M_f32	-521.335693	-521.335693 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	163190528	163190528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	163190528	163190528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	163190528	163190528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	163190528	163190528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	163190528	163190528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	163190528	163190528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	163190528	163190528	✔
ESPNTCEnableTimer_mS_M_u32	163190528	163190528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	89	89	✔
EffacDefaultDiagTimer_mS_M_u32[1]	898	898	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	163190528	163190528	✔
ElecIntTimer_mS_M_u32[1]	5556	5556	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	163190528	163190528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11170	11170	✔
ISDATDIRASentTimer_mS_M_u32	163190528	163190528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	163190528	163190528	✔
IgnOnTimer_mS_M_u32	163190528	163190528	✔
IgnTimeOff_Sec_M_u32	2907156203	2907156203	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	16	16	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	804853760	804853760	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	71	71	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1084176384	1084176384	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	67	67	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3130349568	3130349568	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	77	77	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3856365568	3856365568	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	586307584	586307584	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	168	168	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1884796928	1884796928	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	138	138	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1603131392	1603131392	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	234	234	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	141326336	141326336	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	201	201	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1751914496	1751914496	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	175	175	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2291283968	2291283968	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	27	27	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3523762176	3523762176	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2704336896	2704336896	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	8.31589985	8.31589985	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	387.399414	387.399414	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	299.541901	299.541901	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	58232	58232	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2907156203	2907156203	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-521.335693	-521.335693 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.335 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3052137216
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	20308
AASNodeAbsentTimer_mS_M_u32	4175928064
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	24394
ANGLEVOLANTSigValidCount_Cnt_M_u16	36030
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	39925
AngleVolantMsgTimer_mS_M_u32	3052137216
AngleVolantValidCount_Cnt_M_u16	27521
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1365924608
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	404413184
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	4161735424
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	973916928
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	49245
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	345082624
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	56323
CAVNodeAbsentTimer_mS_M_u32	3501112064
CDD_SrlComVehSpd_Kph_G_f32	606.09729
CMM388NTCEnableTimer_mS_M_u32	2133326592
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4156340992
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	53785
CMMNodeAbsentTimer_mS_M_u32	4219390720
CONSANGLECPKSigInvalidCount_Cnt_M_u16	36617
CONSANGLECPKSigValidCount_Cnt_M_u16	45580
CONSANGLECPK_Cnt_M_u16	21267
CONSANGLECPK_HwDeg_M_f32	-677.960022
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21267
CPKVehicleSpeedMsgTimer_mS_M_u32	4204194560
CPKVehicleSpeedValidCount_Cnt_M_u16	56978
CityParkInputConsistentCount_Cnt_M_u16	47413

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	34243
CityParkInputMsgTimer_mS_M_u32	804853760
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3013319424
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	60168
ComputerRazGCTSigInvalidTimer_mS_M_u32	2155428608
ComputerRazGCTSigValidCount_Cnt_M_u16	30958
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	17423
DMDFCTCPKSigValidCount_Cnt_M_u16	48650
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	43300
DMDRELAXECPKSigValidCount_Cnt_M_u16	26136
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	2218
DateInvalidTimer_mS_M_u32	404413184
DiagMuxOnAbsentTimer_mS_M_u32	2563812096
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	973916928
ESPNTCEnableTimer_mS_M_u32	922524416
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	14265
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	4
EffacDefaultDiagTimer_mS_M_u32[1]	748
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	963
ElecIntTimer_mS_M_u32[1]	7853
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2018216704
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	19276
EtatMTSigValidCount_Cnt_M_u16	15899
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	59107
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	6502
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	42776
ISDAT4V2BSI552MsgTimer_mS_M_u32	0
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	22725
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	52860
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	15899
ISDATBSI3F2MsgTimer_mS_M_u32	955689728
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	56848
ISDATBSI412MsgLenValidCount_Cnt_M_u16	61879
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	19276
ISDATBSI412MsgTimer_mS_M_u32	1410460416
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	35533
ISDATBSI432MsgLenValidCount_Cnt_M_u16	53101
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	6072
ISDATDIRASentFltAcc_Cnt_M_u16	29884
ISDATDIRASentTimer_mS_M_u32	4204194560
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	58297
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	27521
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	15522
ISDYN2CMMMsgTimer_mS_M_u32	1055824640
ISDYNAASChkSumInvalidCount_Cnt_M_u16	38190
ISDYNAASChkSumValidCount_Cnt_M_u16	52801
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	25108
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	58954
ISDYNAASMsgLenValidCount_Cnt_M_u16	53813
ISDYNAASMsgTimeValidCount_Cnt_M_u16	38190
ISDYNAASMsgTimer_mS_M_u32	2792618752
ISDYNABRChkSumInvalidCount_Cnt_M_u16	31723
ISDYNABRChkSumValidCount_Cnt_M_u16	47686
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	61505
ISDYNABRMsgCountValidCount_Cnt_M_u16	24980
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	59676
ISDYNABRMsgLenValidCount_Cnt_M_u16	33887
ISDYNABRMsgTimeValidCount_Cnt_M_u16	21267
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	36636

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	3612
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	15899
ISDYNCMM208MsgTimer_mS_M_u32	711154432
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	36636
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	3612
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	23719
ISDYNCMM388MsgTimer_mS_M_u32	1339915008
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	18223
ISDYNVOLChkSumValidCount_Cnt_M_u16	23218
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	15157
ISDYNVOLMsgCountValidCount_Cnt_M_u16	58800
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	55206
ISDYNVOLMsgLenValidCount_Cnt_M_u16	53001
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	53785
ISDYNVOLMsgTimer_mS_M_u32	3284482816
IgnOnTimer_mS_M_u32	546405120
IgnTimeOff_Sec_M_u32	1720367254
ManVehSpd_Kph_M_f32	7.68060017
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	100
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	694463232
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	223
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3347188480
PrevISDATBSI412MsgDLCError_Cnt_M_u08	101
PrevISDATBSI412MsgRxTime_MSec_M_u32	3659774720
PrevISDATBSI432MsgDLCError_Cnt_M_u08	31
PrevISDATBSI432MsgRxTime_MSec_M_u32	367041280
PrevISDATDIRAMsgTxTime_MSec_M_u32	2988948224
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	146
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4044376832
PrevISDYNAASMsgDLCError_Cnt_M_u08	90
PrevISDYNAASMsgRxTime_MSec_M_u32	1013660416
PrevISDYNABRMsgDLCError_Cnt_M_u08	62
PrevISDYNABRMsgRxTime_MSec_M_u32	2116647680
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	217
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4041489152
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	184
PrevISDYNCMM388MsgRxTime_MSec_M_u32	937925376
PrevISDYNVOLMsgDLCError_Cnt_M_u08	36
PrevISDYNVOLMsgRxTime_MSec_M_u32	1297398528
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	20441856
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	167.327103
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	56176
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	30683
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	57053
VitesseVehicleBVRampValidCount_Cnt_M_u16	8968
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	567
VitesseVehicleBVSigValidCount_Cnt_M_u16	30571

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBV_Kph_M_f32	422.235291
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	23719
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	60658
VitesseVehiculeRoues_Kph_M_f32	453.781097
k_AASNTCEnableTimeout_mS_u16	6910
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	58208
k_AASNodeTimeout_mS_u16	14043
k_ABSNodeTimeout_mS_u16	15304
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	44268
k_ANGLEVOLANTSigValidThresh_Cnt_u16	39628
k_AngleVolantInvalidThresh_Cnt_u16	13127
k_AngleVolantValidThresh_Cnt_u16	34243
k_BSI552MsgTimeout_mS_u16	32045
k_BSINTCEnableTimeout_mS_u16	6245
k_BSINodeAbsentDiag_Cnt_str.Threshold	48552
k_BSINodeAbsentDiag_Cnt_str.PStep	30692
k_BSINodeAbsentDiag_Cnt_str.NStep	13028
k_BSINodeAbsentTimeout_mS_u16	33677
k_BSINodeTimeout_mS_u16	6072
k_BattOvHi_Volt_f32	8.66110039
k_BattOvLo_Volt_f32	12.9111996
k_BattUvHi_Volt_f32	13.2699003
k_BattUvLo_Volt_f32	6.6480999
k_CAVNTCEnableTimeout_mS_u16	55425
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	26665
k_CAVNodeTimeout_mS_u16	3669
k_CMM388MsgTimeout_mS_u16	20052
k_CMM388NTCEnableTimeout_mS_u16	62112
k_CMMNTCEnableTimeout_mS_u16	29277
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	7998
k_CONSANGLECPKMax_HwDeg_f32	29.9288998
k_CONSANGLECPKMin_HwDeg_f32	-652.980225
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	56231
k_CONSANGLECPKSigValidThresh_Cnt_u16	44018
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	46825
k_CPKVehicleSpeedValidThresh_Cnt_u16	4375
k_CityParkInputInvalidThresh_Cnt_u16	53881
k_CityParkInputValidThresh_Cnt_u16	47413
k_ComputerRazGCTSigValidThresh_Cnt_u16	17843
k_CptTemporelSigValidThresh_Cnt_u16	12778
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	59420
k_DMDFCTCPKSigValidThresh_Cnt_u16	50015
k_DMDFCTCPKValidCount_Cnt_u16	10181
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	15522
k_DMDRELAXECPKSigValidThresh_Cnt_u16	3805
k_DMDRelaxeConsistentThresh_Cnt_u16	8427
k_DateValidThresh_Cnt_u16	42776
k_DefaultVehSpd_Kph_f32	187.146698
k_DiagMuxOnAbsentTimeout_mS_u16	1361
k_EMNodeTimeout_mS_u16	43402
k_ESPNTCEnableTimeout_mS_u16	34127
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	47526
k_EtatMTSigInvalidThresh_Cnt_u16	65478
k_EtatMTSigValidThresh_Cnt_u16	64609
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	9552
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	43647
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	54946
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	47878
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	3965
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	54468
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	33934

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	18414
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	33665
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	60071
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	26863
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	44623
k_ISDATDIRASentDiag_Cnt_str.Threshold	24699
k_ISDATDIRASentDiag_Cnt_str.PStep	10108
k_ISDATDIRASentDiag_Cnt_str.NStep	32066
k_ISDATDIRASentTimeout_mS_u16	4407
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	11336
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	39925
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	18283
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	64235
k_ISDYNAASChkSumValidThresh_Cnt_u16	31046
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	61249
k_ISDYNAASMsgCountValidThresh_Cnt_u16	41108
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	42399
k_ISDYNAASMsgLenValidThresh_Cnt_u16	15503
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	60212
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	43074
k_ISDYNABRChkSumValidThresh_Cnt_u16	29701
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	48989
k_ISDYNABRMsgCountValidThresh_Cnt_u16	58641
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	37145
k_ISDYNABRMsgLenValidThresh_Cnt_u16	14009
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	18636
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	292
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	38333
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	31254
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	24138
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	52158
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	49499
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	49839
k_ISDYNVOLChkSumValidThresh_Cnt_u16	24470
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	32602
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	33530
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	23960
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	45415
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	56406
k_IgnOnTimeout_mS_u16	23547
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	231.467499
k_PowerCutVehSpdLowThresh_Kph_f32	111.319
k_PowerCutVehSpdLowTimeout_mS_u16	8442
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	28.7486992
k_VBattMaxCAV_Volt_f32	4.6388998
k_VBattMaxCMM388_Volt_f32	24.3892994
k_VBattMaxCMM_Volt_f32	13.6743002
k_VBattMaxESP_Volt_f32	3.47779989
k_VBattMinAAS_Volt_f32	0.782100022
k_VBattMinBSI_Volt_f32	3.47779989
k_VBattMinCAV_Volt_f32	29.7106991
k_VBattMinCMM388_Volt_f32	20.7271004
k_VBattMinCMM_Volt_f32	26.5303001
k_VBattMinESP_Volt_f32	13.6743002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	54074
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	65041
k_VitesseVehicleBVRampValidThresh_Cnt_u16	47669
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	39346
k_VitesseVehicleBVSigValidThresh_Cnt_u16	55866
k_VitesseVehicleBVSpeedPassThresh_kph_f32	112.7938
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	23299
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	36782
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	404413184
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	184
target_SrlComInput_Per1_Batt_Volt_f32.value	25.6149006
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	992381696
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	18
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.412999272
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	11
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	370375424
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2762021632
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	926857984
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4125907712
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	145357568
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	102
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2541198080
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3394583296
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	56
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	57
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	80
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	107
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	235
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	305748736
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	80
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	81
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	106
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	191
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4172970752
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1489509120
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	247
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2095430400
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	4
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	16
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	93
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	117
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	632032000
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	269
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.995132565
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	195586
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	135.803604

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	39394		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	48552	48552	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	7.68060017	7.68060017	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	21267	21267	✔
CONSANGLECPK_HwDeg_M_f32	-677.960022	-677.960022 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2006148864	2006148864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4	4	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	748	748	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	963	963	✔
ElecIntTimer_mS_M_u32[1]	7853	7853	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	42776	42776	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	15899	15899	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	19276	19276	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	6072	6072	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	24699	24699	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	15522	15522	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	38190	38190	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	21267	21267	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	15899	15899	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	23719	23719	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	53785	53785	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	546405120	546405120	✔
IgnTimeOff_Sec_M_u32	1720367254	1720367254	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	370375424	370375424	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	135	135	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2762021632	2762021632	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	242	242	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	926857984	926857984	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	118	118	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4125907712	4125907712	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2988948224	2988948224	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	102	102	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2541198080	2541198080	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3394583296	3394583296	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	34	34	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	305748736	305748736	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4172970752	4172970752	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1489509120	1489509120	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	247	247	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2095430400	2095430400	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	632032000	632032000	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	167.327103	167.327103	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	422.235291	422.235291	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	453.781097	453.781097	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	21267	21267	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1720367254	1720367254	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-677.960022	-677.960022 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	7.68060017	7.68060017	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.336 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2336686592
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	269
AASNodeAbsentTimer_mS_M_u32	2366894592
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	52010
ANGLEVOLANTSigValidCount_Cnt_M_u16	19344
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	57130
AngleVolantMsgTimer_mS_M_u32	2336686592
AngleVolantValidCount_Cnt_M_u16	42759
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	4270567936
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	209334784
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3109921280
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	442786304
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	46065
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2379620864
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	32640
CAVNodeAbsentTimer_mS_M_u32	2319356416
CDD_SrlComVehSpd_Kph_G_f32	474.519196
CMM388NTCEnableTimer_mS_M_u32	4090679808
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3440677376
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	17148
CMMNodeAbsentTimer_mS_M_u32	504259072
CONSANGLECPKSigInvalidCount_Cnt_M_u16	42733
CONSANGLECPKSigValidCount_Cnt_M_u16	34468
CONSANGLECPK_Cnt_M_u16	32655
CONSANGLECPK_HwDeg_M_f32	92.5084
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	32655
CPKVehicleSpeedMsgTimer_mS_M_u32	692453888
CPKVehicleSpeedValidCount_Cnt_M_u16	41116
CityParkInputConsistentCount_Cnt_M_u16	36331
CityParkInputInvalidCount_Cnt_M_u16	12608
CityParkInputMsgTimer_mS_M_u32	370375424
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	754446848
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	65009

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3302953472
ComputerRazGCTSigValidCount_Cnt_M_u16	29376
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	9820
DMDFCTCPKSigValidCount_Cnt_M_u16	57643
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	54684
DMDRELAXECPKSigValidCount_Cnt_M_u16	42882
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	65034
DateInvalidTimer_mS_M_u32	209334784
DiagMuxOnAbsentTimer_mS_M_u32	1704509952
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	442786304
ESPNTCEnableTimer_mS_M_u32	1725231616
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	51935
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	45
EffacDefaultDiagTimer_mS_M_u32[1]	98
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	201
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3400016384
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	28774
EtatMTSigValidCount_Cnt_M_u16	4280
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	34655
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	14486
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	56833
ISDAT4V2BSI552MsgTimer_mS_M_u32	4294967295
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	50043
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	31509
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	4280
ISDATBSI3F2MsgTimer_mS_M_u32	2636562944
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	28825
ISDATBSI412MsgLenValidCount_Cnt_M_u16	3684
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	28774
ISDATBSI412MsgTimer_mS_M_u32	3369402880
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	59616
ISDATBSI432MsgLenValidCount_Cnt_M_u16	54211
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	57441
ISDATDIRASentFltAcc_Cnt_M_u16	55637
ISDATDIRASentTimer_mS_M_u32	692453888
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	58781
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	42759
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	18595
ISDYN2CMMMsgTimer_mS_M_u32	2533290496
ISDYNAASChkSumInvalidCount_Cnt_M_u16	6015
ISDYNAASChkSumValidCount_Cnt_M_u16	62725
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	53070
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	15531
ISDYNAASMsgLenValidCount_Cnt_M_u16	25001
ISDYNAASMsgTimeValidCount_Cnt_M_u16	6015
ISDYNAASMsgTimer_mS_M_u32	2918109696
ISDYNABRChkSumInvalidCount_Cnt_M_u16	37063
ISDYNABRChkSumValidCount_Cnt_M_u16	32373
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	4678
ISDYNABRMsgCountValidCount_Cnt_M_u16	18188
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	42164
ISDYNABRMsgLenValidCount_Cnt_M_u16	7083
ISDYNABRMsgTimeValidCount_Cnt_M_u16	32655
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	50213
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	50149
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	4280
ISDYNCMM208MsgTimer_mS_M_u32	2543890944
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	50213
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	50149
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	60309

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	934433280
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	38523
ISDYNVOLChkSumValidCount_Cnt_M_u16	42162
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	22762
ISDYNVOLMsgCountValidCount_Cnt_M_u16	33337
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	57112
ISDYNVOLMsgLenValidCount_Cnt_M_u16	49582
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	17148
ISDYNVOLMsgTimer_mS_M_u32	721097216
IgnOnTimer_mS_M_u32	2509656576
IgnTimeOff_Sec_M_u32	3144414550
ManVehSpd_Kph_M_f32	451.373993
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	101
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	234
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	64799232
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	179
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3607405056
PrevISDATBSI412MsgDLCError_Cnt_M_u08	30
PrevISDATBSI412MsgRxTime_MSec_M_u32	2178912768
PrevISDATBSI432MsgDLCError_Cnt_M_u08	44
PrevISDATBSI432MsgRxTime_MSec_M_u32	1512632832
PrevISDATDIRAMsgTxTime_MSec_M_u32	164860416
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	99
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1666834944
PrevISDYNAASMsgDLCError_Cnt_M_u08	248
PrevISDYNAASMsgRxTime_MSec_M_u32	3641250304
PrevISDYNABRMsgDLCError_Cnt_M_u08	131
PrevISDYNABRMsgRxTime_MSec_M_u32	3704508928
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	209
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3751678464
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	147
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3490968064
PrevISDYNVOLMsgDLCError_Cnt_M_u08	147
PrevISDYNVOLMsgRxTime_MSec_M_u32	743215616
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3647144448
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	524.298523
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	30009
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	34999
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	24306
VitesseVehicleBVRampValidCount_Cnt_M_u16	31536
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	54883
VitesseVehicleBVSigValidCount_Cnt_M_u16	32649
VitesseVehicleBV_Kph_M_f32	177.478195
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	60309
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	41844
VitesseVehiculeRoues_Kph_M_f32	122.580002
k_AASNTCEnableTimeout_mS_u16	37838
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	31594
k_AASNodeTimeout_mS_u16	19383
k_ABSNodeTimeout_mS_u16	25393
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	48771
k_ANGLEVOLANTSigValidThresh_Cnt_u16	44454
k_AngleVolantInvalidThresh_Cnt_u16	36917
k_AngleVolantValidThresh_Cnt_u16	12608
k_BSI552MsgTimeout_mS_u16	40643
k_BSINTCEnableTimeout_mS_u16	40984
k_BSINodeAbsentDiag_Cnt_str.Threshold	25088
k_BSINodeAbsentDiag_Cnt_str.PStep	42637
k_BSINodeAbsentDiag_Cnt_str.NStep	63693
k_BSINodeAbsentTimeout_mS_u16	34914
k_BSINodeTimeout_mS_u16	57441
k_BattOvHi_Volt_f32	5.15740013
k_BattOvLo_Volt_f32	31.5
k_BattUvHi_Volt_f32	15.5155001
k_BattUvLo_Volt_f32	22.2730007
k_CAVNTCEnableTimeout_mS_u16	45318
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	62222
k_CAVNodeTimeout_mS_u16	22793
k_CMM388MsgTimeout_mS_u16	1037
k_CMM388NTCEnableTimeout_mS_u16	18217
k_CMMNTCEnableTimeout_mS_u16	54963
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	15504
k_CONSANGLECPKMax_HwDeg_f32	383.212799
k_CONSANGLECPKMin_HwDeg_f32	-270.865814
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	28309
k_CONSANGLECPKSigValidThresh_Cnt_u16	26228
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	33677
k_CPKVehicleSpeedValidThresh_Cnt_u16	45956
k_CityParkInputInvalidThresh_Cnt_u16	17693
k_CityParkInputValidThresh_Cnt_u16	36331
k_ComputerRazGCTSigValidThresh_Cnt_u16	13489
k_CptTemporelSigValidThresh_Cnt_u16	35019
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	42932
k_DMDFCTCPKSigValidThresh_Cnt_u16	24235
k_DMDFCTCPKValidCount_Cnt_u16	7609
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	18595
k_DMDRELAXECPKSigValidThresh_Cnt_u16	64178
k_DMDRelaxeConsistentThresh_Cnt_u16	31880
k_DateValidThresh_Cnt_u16	56833
k_DefaultVehSpd_Kph_f32	234.102097
k_DiagMuxOnAbsentTimeout_mS_u16	57557
k_EMNodeTimeout_mS_u16	39786
k_ESPNTCEnableTimeout_mS_u16	45980
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	3416
k_EtatMTSigInvalidThresh_Cnt_u16	12598
k_EtatMTSigValidThresh_Cnt_u16	58404
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	37976
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	64907
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	10660
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	57528
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	64530
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	23677
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	16285
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	44608
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	52932
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	2259
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	59069
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	3291
k_ISDATDIRASentDiag_Cnt_str.Threshold	55184

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	37963
k_ISDATDIRASentDiag_Cnt_str.NStep	46267
k_ISDATDIRASentTimeout_mS_u16	227
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	46832
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	57130
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	56648
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	5063
k_ISDYNAASChkSumValidThresh_Cnt_u16	16757
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	5446
k_ISDYNAASMsgCountValidThresh_Cnt_u16	35340
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	58283
k_ISDYNAASMsgLenValidThresh_Cnt_u16	2715
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	23662
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	32578
k_ISDYNABRChkSumValidThresh_Cnt_u16	25785
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	46833
k_ISDYNABRMsgCountValidThresh_Cnt_u16	20119
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	1532
k_ISDYNABRMsgLenValidThresh_Cnt_u16	52703
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	53094
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	54301
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	15762
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	11782
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	52778
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	36496
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	56952
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	65212
k_ISDYNVOLChkSumValidThresh_Cnt_u16	199
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	47100
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	62553
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	27010
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	59092
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	46663
k_IgnOnTimeout_mS_u16	25304
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	213.639694
k_PowerCutVehSpdLowThresh_Kph_f32	38.0849991
k_PowerCutVehSpdLowTimeout_mS_u16	29146
k_VBattMaxAAS_Volt_f32	9.27750015
k_VBattMaxBSI_Volt_f32	0.642099977
k_VBattMaxCAV_Volt_f32	31.8827991
k_VBattMaxCMM388_Volt_f32	14.4616003
k_VBattMaxCMM_Volt_f32	1.07050002
k_VBattMaxESP_Volt_f32	28.2761002
k_VBattMinAAS_Volt_f32	19.0897007
k_VBattMinBSI_Volt_f32	28.2761002
k_VBattMinCAV_Volt_f32	29.9827003
k_VBattMinCMM388_Volt_f32	12.1385002
k_VBattMinCMM_Volt_f32	0.755500019
k_VBattMinESP_Volt_f32	1.07050002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	2586
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	8789
k_VitesseVehicleBVRampValidThresh_Cnt_u16	56298
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	59314
k_VitesseVehicleBVSigValidThresh_Cnt_u16	32476
k_VitesseVehicleBVSpeedPassThresh_kph_f32	152.699295
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	640
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	19774
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	209334784
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	15965
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2717483008
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	147
target_SrlComInput_Per1_Batt_Volt_f32.value	31
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2920751616
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	80
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.354992419
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1024479744
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1340568064
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2525925888
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2567287296
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3746353664
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4049859072
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	201
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1464537600
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	20
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	22
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	24
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	134
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	146
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	196
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3089019392
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	48
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	170
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	234
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4045099520
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2406642176
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	563712512
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	47
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	57
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	164
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	183
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3834028544
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	495
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.193207949
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	466331
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	160.881104
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	33251

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2717483008	2717483008	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	32655	32655	✔
CONSANGLECPK_HwDeg_M_f32	92.5084	92.5084 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2717483008	2717483008	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2717483008	2717483008	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2717483008	2717483008	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2717483008	2717483008	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2717483008	2717483008	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2717483008	2717483008	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2717483008	2717483008	✔
ESPNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2717483008	2717483008	✔
EffacDefaultDiagTimer_mS_M_u32[1]	98	98	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2717483008	2717483008	✔
ElecIntTimer_mS_M_u32[1]	201	201	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2717483008	2717483008	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATDIRASentFltAcc_Cnt_M_u16	55184	55184	✔
ISDATDIRASentTimer_mS_M_u32	2717483008	2717483008	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2717483008	2717483008	✔
IgnOnTimer_mS_M_u32	2717483008	2717483008	✔
IgnTimeOff_Sec_M_u32	3144414550	3144414550	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	148	148	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1024479744	1024479744	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	192	192	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1340568064	1340568064	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	92	92	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2525925888	2525925888	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	239	239	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2567287296	2567287296	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	164860416	164860416	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	30	30	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4049859072	4049859072	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	201	201	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1464537600	1464537600	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	95	95	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3089019392	3089019392	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	202	202	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4045099520	4045099520	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	34	34	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2406642176	2406642176	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	169	169	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	563712512	563712512	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3834028544	3834028544	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	524.298523	524.298523	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	177.478195	177.478195	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	122.580002	122.580002	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	32655	32655	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3144414550	3144414550	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	92.5084	92.5084 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.337 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4166106368
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	53502
AASNodeAbsentTimer_mS_M_u32	2460675328
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	33960
ANGLEVOLANTSigValidCount_Cnt_M_u16	59701
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	60071
AngleVolantMsgTimer_mS_M_u32	4166106368
AngleVolantValidCount_Cnt_M_u16	61327
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3443764480
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2105027840
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2425216256
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4168719616
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	42579
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2502188288
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	59430
CAVNodeAbsentTimer_mS_M_u32	229313792
CDD_SrlComVehSpd_Kph_G_f32	643.916992
CMM388NTCEnableTimer_mS_M_u32	1911442688
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	489229568
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	44144
CMMNodeAbsentTimer_mS_M_u32	360422656
CONSANGLECPKSigInvalidCount_Cnt_M_u16	45149
CONSANGLECPKSigValidCount_Cnt_M_u16	14074
CONSANGLECPK_Cnt_M_u16	47161
CONSANGLECPK_HwDeg_M_f32	294.004486
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	47161
CPKVehicleSpeedMsgTimer_mS_M_u32	3662986496
CPKVehicleSpeedValidCount_Cnt_M_u16	10873

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	51939
CityParkInputInvalidCount_Cnt_M_u16	50660
CityParkInputMsgTimer_mS_M_u32	1024479744
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1124003072
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	27218
ComputerRazGCTSigInvalidTimer_mS_M_u32	2143915264
ComputerRazGCTSigValidCount_Cnt_M_u16	45156
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	22160
DMDFCTCPKSigValidCount_Cnt_M_u16	44004
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	44370
DMDRELAXECPKSigValidCount_Cnt_M_u16	7519
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	24326
DateInvalidTimer_mS_M_u32	2105027840
DiagMuxOnAbsentTimer_mS_M_u32	3764157696
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4168719616
ESPNTCEnableTimer_mS_M_u32	1231547648
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	60040
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	66
EffacDefaultDiagTimer_mS_M_u32[1]	78
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	89
ElecIntTimer_mS_M_u32[1]	899
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2796444928
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	22836
EtatMTSigValidCount_Cnt_M_u16	3581
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	22279
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	26916
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	36194
ISDAT4V2BSI552MsgTimer_mS_M_u32	3869554176
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	60788
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	31845
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	3581
ISDATBSI3F2MsgTimer_mS_M_u32	4055006464
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	12057
ISDATBSI412MsgLenValidCount_Cnt_M_u16	52090
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	22836
ISDATBSI412MsgTimer_mS_M_u32	4154965248
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	19140
ISDATBSI432MsgLenValidCount_Cnt_M_u16	24540
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	35203
ISDATDIRASentFltAcc_Cnt_M_u16	28327
ISDATDIRASentTimer_mS_M_u32	3662986496
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	15887
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	61327
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52155
ISDYN2CMMMsgTimer_mS_M_u32	3773426944
ISDYNAASChkSumInvalidCount_Cnt_M_u16	54696
ISDYNAASChkSumValidCount_Cnt_M_u16	41684
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	21178
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	7333
ISDYNAASMsgLenValidCount_Cnt_M_u16	62314
ISDYNAASMsgTimeValidCount_Cnt_M_u16	54696
ISDYNAASMsgTimer_mS_M_u32	3013233920
ISDYNABRChkSumInvalidCount_Cnt_M_u16	57680
ISDYNABRChkSumValidCount_Cnt_M_u16	7685
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	49491
ISDYNABRMsgCountValidCount_Cnt_M_u16	35007
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	37640
ISDYNABRMsgLenValidCount_Cnt_M_u16	21477
ISDYNABRMsgTimeValidCount_Cnt_M_u16	47161

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	49252
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	19174
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	3581
ISDYNCMM208MsgTimer_mS_M_u32	2516888832
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	49252
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	19174
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	55781
ISDYNCMM388MsgTimer_mS_M_u32	2219822336
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	39347
ISDYNVOLChkSumValidCount_Cnt_M_u16	38096
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	30438
ISDYNVOLMsgCountValidCount_Cnt_M_u16	32954
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	53725
ISDYNVOLMsgLenValidCount_Cnt_M_u16	53210
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	44144
ISDYNVOLMsgTimer_mS_M_u32	3178597632
IgnOnTimer_mS_M_u32	4205038848
IgnTimeOff_Sec_M_u32	2693308314
ManVehSpd_Kph_M_f32	261.477814
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	102
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	161
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	361790720
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	141
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2476268800
PrevISDATBSI412MsgDLCError_Cnt_M_u08	88
PrevISDATBSI412MsgRxTime_MSec_M_u32	3938979072
PrevISDATBSI432MsgDLCError_Cnt_M_u08	124
PrevISDATBSI432MsgRxTime_MSec_M_u32	3211521280
PrevISDATDIRAMsgTxTime_MSec_M_u32	585895168
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	34
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3550027008
PrevISDYNAASMsgDLCError_Cnt_M_u08	161
PrevISDYNAASMsgRxTime_MSec_M_u32	1800113408
PrevISDYNABRMsgDLCError_Cnt_M_u08	88
PrevISDYNABRMsgRxTime_MSec_M_u32	83610880
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	13
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3951856896
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	175
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3383422208
PrevISDYNVOLMsgDLCError_Cnt_M_u08	226
PrevISDYNVOLMsgRxTime_MSec_M_u32	3749776640
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2113780992
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	356.132294
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	11003
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	13888
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	37328
VitesseVehicleBVRampValidCount_Cnt_M_u16	33493
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	34557

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	29002
VitesseVehicleBV_Kph_M_f32	142.881302
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	55781
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	30730
VitesseVehiculeRoues_Kph_M_f32	188.358002
k_AASNTCEnableTimeout_mS_u16	14204
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	48742
k_AASNodeTimeout_mS_u16	60736
k_ABSNodeTimeout_mS_u16	13329
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	5595
k_ANGLEVOLANTSigValidThresh_Cnt_u16	7731
k_AngleVolantInvalidThresh_Cnt_u16	29318
k_AngleVolantValidThresh_Cnt_u16	50660
k_BSI552MsgTimeout_mS_u16	33309
k_BSINTCEnableTimeout_mS_u16	1308
k_BSINodeAbsentDiag_Cnt_str.Threshold	27220
k_BSINodeAbsentDiag_Cnt_str.PStep	17134
k_BSINodeAbsentDiag_Cnt_str.NStep	49772
k_BSINodeAbsentTimeout_mS_u16	52991
k_BSINodeTimeout_mS_u16	35203
k_BattOvHi_Volt_f32	9.08080006
k_BattOvLo_Volt_f32	6.38990021
k_BattUvHi_Volt_f32	2.9526
k_BattUvLo_Volt_f32	22.0039005
k_CAVNTCEnableTimeout_mS_u16	56978
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	17788
k_CAVNodeTimeout_mS_u16	2569
k_CMM388MsgTimeout_mS_u16	51198
k_CMM388NTCEnableTimeout_mS_u16	28330
k_CMMNTCEnableTimeout_mS_u16	37836
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	7350
k_CONSANGLECPKMax_HwDeg_f32	266.386108
k_CONSANGLECPKMin_HwDeg_f32	-580.961182
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	20709
k_CONSANGLECPKSigValidThresh_Cnt_u16	12042
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	7614
k_CPKVehicleSpeedValidThresh_Cnt_u16	53848
k_CityParkInputInvalidThresh_Cnt_u16	40014
k_CityParkInputValidThresh_Cnt_u16	51939
k_ComputerRazGCTSigValidThresh_Cnt_u16	61906
k_CptTemporelSigValidThresh_Cnt_u16	43843
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	35336
k_DMDFCTCPKSigValidThresh_Cnt_u16	35557
k_DMDFCTCPKValidCount_Cnt_u16	35067
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	52155
k_DMDRELAXECPKSigValidThresh_Cnt_u16	15183
k_DMDRelaxeConsistentThresh_Cnt_u16	36301
k_DateValidThresh_Cnt_u16	36194
k_DefaultVehSpd_Kph_f32	144.3452
k_DiagMuxOnAbsentTimeout_mS_u16	11367
k_EMNodeTimeout_mS_u16	1766
k_ESPNTCEnableTimeout_mS_u16	48082
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	51806
k_EtatMTSigInvalidThresh_Cnt_u16	31747
k_EtatMTSigValidThresh_Cnt_u16	26872
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	55133
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	45445
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	7096
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	51645
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	11630
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	64365

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	31373
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	1125
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	10520
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	11373
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	34925
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	13138
k_ISDATDIRASentDiag_Cnt_str.Threshold	32735
k_ISDATDIRASentDiag_Cnt_str.PStep	25081
k_ISDATDIRASentDiag_Cnt_str.NStep	58726
k_ISDATDIRASentTimeout_mS_u16	252
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	51475
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	60071
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	61134
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	22608
k_ISDYNAASChkSumValidThresh_Cnt_u16	54533
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	47187
k_ISDYNAASMsgCountValidThresh_Cnt_u16	49087
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	30884
k_ISDYNAASMsgLenValidThresh_Cnt_u16	16532
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	12763
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	47966
k_ISDYNABRChkSumValidThresh_Cnt_u16	12475
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	40275
k_ISDYNABRMsgCountValidThresh_Cnt_u16	48160
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	25456
k_ISDYNABRMsgLenValidThresh_Cnt_u16	57736
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	13747
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	40527
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	60462
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	16979
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	31656
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	8245
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	40508
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	53424
k_ISDYNVOLChkSumValidThresh_Cnt_u16	16465
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	55089
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	19545
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	56800
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	64425
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	40080
k_IgnOnTimeout_mS_u16	5212
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	124.232399
k_PowerCutVehSpdLowThresh_Kph_f32	210.896393
k_PowerCutVehSpdLowTimeout_mS_u16	52568
k_VBattMaxAAS_Volt_f32	2.15759993
k_VBattMaxBSI_Volt_f32	22.1986008
k_VBattMaxCAV_Volt_f32	18.7432003
k_VBattMaxCMM388_Volt_f32	11.5164003
k_VBattMaxCMM_Volt_f32	23.2984009
k_VBattMaxESP_Volt_f32	17.8328991
k_VBattMinAAS_Volt_f32	31.2122002
k_VBattMinBSI_Volt_f32	17.8328991
k_VBattMinCAV_Volt_f32	2.49729991
k_VBattMinCMM388_Volt_f32	25.4144993
k_VBattMinCMM_Volt_f32	8.48449993
k_VBattMinESP_Volt_f32	23.2984009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	63381
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	58534
k_VitesseVehicleBVRampValidThresh_Cnt_u16	60902
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	52176
k_VitesseVehicleBVSigValidThresh_Cnt_u16	64528
k_VitesseVehicleBVSpeedPassThresh_kph_f32	451.167297
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	24358
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	50347
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2105027840
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	19695
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2232967680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	175
target_SrlComInput_Per1_Batt_Volt_f32.value	16.7872009
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2019646720
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	28
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0837510452
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	187
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1815465216
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4163923200
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	237
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	683347200
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1708502272
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	394284288
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2780491008
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	184
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2022018304
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	12
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	25
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	175
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	191
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2894769408
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	74
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	100
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	107
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	123
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	131
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	224
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	4
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1007996160
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	630156544
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1939475712
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	49
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	248
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4078099712
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	843
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.535272658
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	81327
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	21.7579994
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	11517

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2232967680	2232967680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2232967680	2232967680	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2232967680	2232967680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2232967680	2232967680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2232967680	2232967680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2232967680	2232967680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2232967680	2232967680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2232967680	2232967680	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2232967680	2232967680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2232967680	2232967680	✔
CDD_SrlComVehSpd_Kph_G_f32	261.477814	261.477814	✔
CMM388NTCEnableTimer_mS_M_u32	2232967680	2232967680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2232967680	2232967680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2232967680	2232967680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	47161	47161	✔
CONSANGLECPK_HwDeg_M_f32	294.004486	294.004486 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2232967680	2232967680	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2232967680	2232967680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2232967680	2232967680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2232967680	2232967680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2232967680	2232967680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2232967680	2232967680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2232967680	2232967680	✔
ESPNTCEnableTimer_mS_M_u32	2232967680	2232967680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2232967680	2232967680	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	66	66	✔
EffacDefaultDiagTimer_mS_M_u32[1]	78	78	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	89	89	✔
ElecIntTimer_mS_M_u32[1]	899	899	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2232967680	2232967680	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	36194	36194	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2232967680	2232967680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	3581	3581	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2232967680	2232967680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	22836	22836	✔
ISDATBSI412MsgTimer_mS_M_u32	2232967680	2232967680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	35203	35203	✔
ISDATBSI432MsgTimer_mS_M_u32	2232967680	2232967680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	32735	32735	✔
ISDATDIRASentTimer_mS_M_u32	2232967680	2232967680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52155	52155	✔
ISDYN2CMMMsgTimer_mS_M_u32	2232967680	2232967680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	54696	54696	✔
ISDYNAASMsgTimer_mS_M_u32	2232967680	2232967680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	47161	47161	✔
ISDYNABRMsgTimer_mS_M_u32	2232967680	2232967680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	3581	3581	✔
ISDYNCMM208MsgTimer_mS_M_u32	2232967680	2232967680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	55781	55781	✔
ISDYNCMM388MsgTimer_mS_M_u32	2232967680	2232967680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	44144	44144	✔
ISDYNVOLMsgTimer_mS_M_u32	2232967680	2232967680	✔
IgnOnTimer_mS_M_u32	4205038848	4205038848	✔
IgnTimeOff_Sec_M_u32	2693308314	2693308314	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	187	187	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1815465216	1815465216	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	92	92	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4163923200	4163923200	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	237	237	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	683347200	683347200	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	215	215	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1708502272	1708502272	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	585895168	585895168	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	84	84	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2780491008	2780491008	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	184	184	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2022018304	2022018304	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2894769408	2894769408	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	4	4	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1007996160	1007996160	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	34	34	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	630156544	630156544	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	241	241	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1939475712	1939475712	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4078099712	4078099712	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	356.132294	356.132294	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	142.881302	142.881302	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	188.358002	188.358002	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	47161	47161	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2693308314	2693308314	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	294.004486	294.004486 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.338 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1507691520
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	8664
AASNodeAbsentTimer_mS_M_u32	2878471168
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	53464
ANGLEVOLANTSigValidCount_Cnt_M_u16	61938
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	47325
AngleVolantMsgTimer_mS_M_u32	1507691520
AngleVolantValidCount_Cnt_M_u16	38051
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1321712640
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2955557888
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	698952704
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1357245440
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	55255
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2514856960
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	9439
CAVNodeAbsentTimer_mS_M_u32	3809582080
CDD_SrlComVehSpd_Kph_G_f32	442.541901
CMM388NTCEnableTimer_mS_M_u32	3544701952
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	748133376
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	43969
CMMNodeAbsentTimer_mS_M_u32	2178935808
CONSANGLECPKSigInvalidCount_Cnt_M_u16	4282
CONSANGLECPKSigValidCount_Cnt_M_u16	2980
CONSANGLECPK_Cnt_M_u16	17383
CONSANGLECPK_HwDeg_M_f32	638.749817
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17383
CPKVehicleSpeedMsgTimer_mS_M_u32	2144635904
CPKVehicleSpeedValidCount_Cnt_M_u16	3310
CityParkInputConsistentCount_Cnt_M_u16	21159
CityParkInputInvalidCount_Cnt_M_u16	45734
CityParkInputMsgTimer_mS_M_u32	1815465216
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	0
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	42460

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	649468928
ComputerRazGCTSigValidCount_Cnt_M_u16	58916
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	45218
DMDFCTCPKSigValidCount_Cnt_M_u16	8036
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	32474
DMDRELAXECPKSigValidCount_Cnt_M_u16	32116
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	59583
DateInvalidTimer_mS_M_u32	2955557888
DiagMuxOnAbsentTimer_mS_M_u32	1019038720
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1357245440
ESPNTCEnableTimer_mS_M_u32	3143302144
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	28727
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	101
EffacDefaultDiagTimer_mS_M_u32[1]	105
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	749
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	155692032
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	1653
EtatMTSigValidCount_Cnt_M_u16	9947
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	17596
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	40230
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	62186
ISDAT4V2BSI552MsgTimer_mS_M_u32	3152276480
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	41269
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	54051
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	9947
ISDATBSI3F2MsgTimer_mS_M_u32	3770371072
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	325
ISDATBSI412MsgLenValidCount_Cnt_M_u16	51939
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	1653
ISDATBSI412MsgTimer_mS_M_u32	870026240
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	8389
ISDATBSI432MsgLenValidCount_Cnt_M_u16	24635
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	62664
ISDATDIRASentFltAcc_Cnt_M_u16	54620
ISDATDIRASentTimer_mS_M_u32	2144635904
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	35429
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	38051
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	48417
ISDYN2CMMMsgTimer_mS_M_u32	2094332928
ISDYNAASChkSumInvalidCount_Cnt_M_u16	15322
ISDYNAASChkSumValidCount_Cnt_M_u16	41747
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	55074
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	17250
ISDYNAASMsgLenValidCount_Cnt_M_u16	60884
ISDYNAASMsgTimeValidCount_Cnt_M_u16	15322
ISDYNAASMsgTimer_mS_M_u32	3192118272
ISDYNABRChkSumInvalidCount_Cnt_M_u16	45664
ISDYNABRChkSumValidCount_Cnt_M_u16	60162
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	58585
ISDYNABRMsgCountValidCount_Cnt_M_u16	23890
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	54457
ISDYNABRMsgLenValidCount_Cnt_M_u16	8419
ISDYNABRMsgTimeValidCount_Cnt_M_u16	17383
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	27027
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	11470
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	9947
ISDYNCMM208MsgTimer_mS_M_u32	948222976
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	27027
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	11470
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	44449

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	35871744
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	11448
ISDYNVOLChkSumValidCount_Cnt_M_u16	51746
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	10144
ISDYNVOLMsgCountValidCount_Cnt_M_u16	30946
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	20024
ISDYNVOLMsgLenValidCount_Cnt_M_u16	25346
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	43969
ISDYNVOLMsgTimer_mS_M_u32	498211840
IgnOnTimer_mS_M_u32	4012334080
IgnTimeOff_Sec_M_u32	347289073
ManVehSpd_Kph_M_f32	320.123505
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	103
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1830898688
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	115
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	210250752
PrevISDATBSI412MsgDLCError_Cnt_M_u08	233
PrevISDATBSI412MsgRxTime_MSec_M_u32	4290419712
PrevISDATBSI432MsgDLCError_Cnt_M_u08	148
PrevISDATBSI432MsgRxTime_MSec_M_u32	1766784000
PrevISDATDIRAMsgTxTime_MSec_M_u32	3880688640
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	197
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2642897920
PrevISDYNAASMsgDLCError_Cnt_M_u08	139
PrevISDYNAASMsgRxTime_MSec_M_u32	3962575872
PrevISDYNABRMsgDLCError_Cnt_M_u08	94
PrevISDYNABRMsgRxTime_MSec_M_u32	807361536
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	94
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2943163392
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	194
PrevISDYNCMM388MsgRxTime_MSec_M_u32	110230528
PrevISDYNVOLMsgDLCError_Cnt_M_u08	141
PrevISDYNVOLMsgRxTime_MSec_M_u32	1167039488
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2027523072
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	408.556091
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	61536
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	64850
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	20449
VitesseVehicleBVRampValidCount_Cnt_M_u16	43923
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	24025
VitesseVehicleBVSigValidCount_Cnt_M_u16	60851
VitesseVehicleBV_Kph_M_f32	215.064697
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	44449
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	33267
VitesseVehiculeRoues_Kph_M_f32	436.288788
k_AASNTCEnableTimeout_mS_u16	37406
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	17438
k_AASNodeTimeout_mS_u16	55378
k_ABSNodeTimeout_mS_u16	23583
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	56192
k_ANGLEVOLANTSigValidThresh_Cnt_u16	16694
k_AngleVolantInvalidThresh_Cnt_u16	20541
k_AngleVolantValidThresh_Cnt_u16	45734
k_BSI552MsgTimeout_mS_u16	28602
k_BSINTCEnableTimeout_mS_u16	20925
k_BSINodeAbsentDiag_Cnt_str.Threshold	57669
k_BSINodeAbsentDiag_Cnt_str.PStep	25782
k_BSINodeAbsentDiag_Cnt_str.NStep	33659
k_BSINodeAbsentTimeout_mS_u16	27605
k_BSINodeTimeout_mS_u16	62664
k_BattOvHi_Volt_f32	31.2924004
k_BattOvLo_Volt_f32	3.27850008
k_BattUvHi_Volt_f32	7.33799982
k_BattUvLo_Volt_f32	27.2131004
k_CAVNTCEnableTimeout_mS_u16	41116
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	58589
k_CAVNodeTimeout_mS_u16	46006
k_CMM388MsgTimeout_mS_u16	15576
k_CMM388NTCEnableTimeout_mS_u16	63700
k_CMMNTCEnableTimeout_mS_u16	3629
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	17391
k_CONSANGLECPKMax_HwDeg_f32	472.478394
k_CONSANGLECPKMin_HwDeg_f32	-255.730606
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	18593
k_CONSANGLECPKSigValidThresh_Cnt_u16	23795
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	48856
k_CPKVehicleSpeedValidThresh_Cnt_u16	54152
k_CityParkInputInvalidThresh_Cnt_u16	63846
k_CityParkInputValidThresh_Cnt_u16	21159
k_ComputerRazGCTSigValidThresh_Cnt_u16	35867
k_CptTemporelSigValidThresh_Cnt_u16	16009
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	61369
k_DMDFCTCPKSigValidThresh_Cnt_u16	31715
k_DMDFCTCPKValidCount_Cnt_u16	53215
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	48417
k_DMDRELAXECPKSigValidThresh_Cnt_u16	56611
k_DMDRelaxeConsistentThresh_Cnt_u16	23977
k_DateValidThresh_Cnt_u16	62186
k_DefaultVehSpd_Kph_f32	116.287804
k_DiagMuxOnAbsentTimeout_mS_u16	8029
k_EMNodeTimeout_mS_u16	28959
k_ESPNTCEnableTimeout_mS_u16	23003
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	56055
k_EtatMTSigInvalidThresh_Cnt_u16	28231
k_EtatMTSigValidThresh_Cnt_u16	38441
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	52731
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	65089
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	62504
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	28762
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	9224
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	60489
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	62826
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	54944
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	54729
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	46923
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	49673
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	27033
k_ISDATDIRASentDiag_Cnt_str.Threshold	5639

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	36987
k_ISDATDIRASentDiag_Cnt_str.NStep	30451
k_ISDATDIRASentTimeout_mS_u16	860
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	60502
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	47325
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	45287
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	19808
k_ISDYNAASChkSumValidThresh_Cnt_u16	50690
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	65497
k_ISDYNAASMsgCountValidThresh_Cnt_u16	47186
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	15460
k_ISDYNAASMsgLenValidThresh_Cnt_u16	11862
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	42558
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	13239
k_ISDYNABRChkSumValidThresh_Cnt_u16	25185
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	62167
k_ISDYNABRMsgCountValidThresh_Cnt_u16	58673
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	34497
k_ISDYNABRMsgLenValidThresh_Cnt_u16	35639
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	33912
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	58980
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	24070
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	58649
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	60376
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	19698
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	35230
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	14464
k_ISDYNVOLChkSumValidThresh_Cnt_u16	34910
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	36412
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	45062
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	10353
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	3543
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	64864
k_IgnOnTimeout_mS_u16	7548
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	165.126205
k_PowerCutVehSpdLowThresh_Kph_f32	201.134003
k_PowerCutVehSpdLowTimeout_mS_u16	16522
k_VBattMaxAAS_Volt_f32	4.78369999
k_VBattMaxBSI_Volt_f32	28.2565994
k_VBattMaxCAV_Volt_f32	31.8229008
k_VBattMaxCMM388_Volt_f32	0.973800004
k_VBattMaxCMM_Volt_f32	17.8029003
k_VBattMaxESP_Volt_f32	3.74510002
k_VBattMinAAS_Volt_f32	6.14629984
k_VBattMinBSI_Volt_f32	3.74510002
k_VBattMinCAV_Volt_f32	14.3993998
k_VBattMinCMM388_Volt_f32	4.49359989
k_VBattMinCMM_Volt_f32	10.5206003
k_VBattMinESP_Volt_f32	17.8029003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	59600
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	32862
k_VitesseVehicleBVRampValidThresh_Cnt_u16	49824
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	9506
k_VitesseVehicleBVSigValidThresh_Cnt_u16	45856
k_VitesseVehicleBVSpeedPassThresh_kph_f32	557.379028
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	49119
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	48657
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2955557888
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	5937
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2287836416
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	194
target_SrlComInput_Per1_Batt_Volt_f32.value	2.1789
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	539929600
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	148
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.944769621
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	115
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1651596288
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1895922688
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3521223680
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1293007872
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2861685760
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	4
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2992765952
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	746724352
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	57
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	72
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	169
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	209
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2364718080
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	126
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	140
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	176
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	222
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	785669120
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	618953728
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	114
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	759471104
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	58
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	109
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	121
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	138
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	140
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	178
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1444555776
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	279
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.611671448
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	287858
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	230.799301
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	29274

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2287836416	2287836416	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2287836416	2287836416	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	47325	47325	✔
AngleVolantMsgTimer_mS_M_u32	2287836416	2287836416	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2287836416	2287836416	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2287836416	2287836416	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2287836416	2287836416	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2287836416	2287836416	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2287836416	2287836416	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2287836416	2287836416	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2287836416	2287836416	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2287836416	2287836416	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2287836416	2287836416	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2287836416	2287836416	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	17383	17383	✔
CONSANGLECPK_HwDeg_M_f32	638.749817	638.749817 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17383	17383	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2144635904	2144635904	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	3310	3310	✔
CityParkInputConsistentCount_Cnt_M_u16	21159	21159	✔
CityParkInputInvalidCount_Cnt_M_u16	45736	45736	✔
CityParkInputMsgTimer_mS_M_u32	2287836416	2287836416	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2287836416	2287836416	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2287836416	2287836416	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2287836416	2287836416	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2287836416	2287836416	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2287836416	2287836416	✔
ESPNTCEnableTimer_mS_M_u32	2287836416	2287836416	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2287836416	2287836416	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	101	101	✔
EffacDefaultDiagTimer_mS_M_u32[1]	105	105	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2287836416	2287836416	✔
ElecIntTimer_mS_M_u32[1]	749	749	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2287836416	2287836416	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2287836416	2287836416	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2287836416	2287836416	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2287836416	2287836416	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2287836416	2287836416	✔
ISDATDIRASentFltAcc_Cnt_M_u16	5639	5639	✔
ISDATDIRASentTimer_mS_M_u32	2287836416	2287836416	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2287836416	2287836416	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2287836416	2287836416	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2287836416	2287836416	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2287836416	2287836416	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2287836416	2287836416	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2287836416	2287836416	✔
IgnOnTimer_mS_M_u32	2287836416	2287836416	✔
IgnTimeOff_Sec_M_u32	347289073	347289073	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	115	115	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1651596288	1651596288	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	35	35	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1895922688	1895922688	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	66	66	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3521223680	3521223680	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	151	151	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1293007872	1293007872	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3880688640	3880688640	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	4	4	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2992765952	2992765952	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	172	172	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	746724352	746724352	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	174	174	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2364718080	2364718080	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	212	212	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	785669120	785669120	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	12	12	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	618953728	618953728	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	114	114	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	759471104	759471104	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1444555776	1444555776	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	408.556091	408.556091	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	215.064697	215.064697	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	436.288788	436.288788	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	17383	17383	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	347289073	347289073	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	638.749817	638.749817 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.339 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3946192640
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	40262
AASNodeAbsentTimer_mS_M_u32	2480459520
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	12869
ANGLEVOLANTSigValidCount_Cnt_M_u16	58039
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	11319
AngleVolantMsgTimer_mS_M_u32	3946192640
AngleVolantValidCount_Cnt_M_u16	55653
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2973208320
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	923799296
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2991800064
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	530382592
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	55624
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	4288528128
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	47791
CAVNodeAbsentTimer_mS_M_u32	4091145984
CDD_SrlComVehSpd_Kph_G_f32	577.446472
CMM388NTCEnableTimer_mS_M_u32	3426168576
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2940727040
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	43721
CMMNodeAbsentTimer_mS_M_u32	4105109248
CONSANGLECPKSigInvalidCount_Cnt_M_u16	10655
CONSANGLECPKSigValidCount_Cnt_M_u16	36002
CONSANGLECPK_Cnt_M_u16	45017
CONSANGLECPK_HwDeg_M_f32	-608.999207
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	45017
CPKVehicleSpeedMsgTimer_mS_M_u32	357637888
CPKVehicleSpeedValidCount_Cnt_M_u16	5483
CityParkInputConsistentCount_Cnt_M_u16	44889
CityParkInputInvalidCount_Cnt_M_u16	40027

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	1651596288
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4294967295
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	8506
ComputerRazGCTSigInvalidTimer_mS_M_u32	1525444352
ComputerRazGCTSigValidCount_Cnt_M_u16	10466
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	37479
DMDFCTCPKSigValidCount_Cnt_M_u16	63969
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	45119
DMDRELAXECPKSigValidCount_Cnt_M_u16	51249
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	62864
DateInvalidTimer_mS_M_u32	923799296
DiagMuxOnAbsentTimer_mS_M_u32	1905712896
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	530382592
ESPNTCEnableTimer_mS_M_u32	3363688192
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	57639
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	99
EffacDefaultDiagTimer_mS_M_u32[1]	999
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	45
ElecIntTimer_mS_M_u32[1]	99
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2910306048
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	30639
EtatMTSigValidCount_Cnt_M_u16	23101
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	5529
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	24604
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	5967
ISDAT4V2BSI552MsgTimer_mS_M_u32	1453522688
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	41198
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	28388
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	23101
ISDATBSI3F2MsgTimer_mS_M_u32	4254916352
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	4541
ISDATBSI412MsgLenValidCount_Cnt_M_u16	55459
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	30639
ISDATBSI412MsgTimer_mS_M_u32	3577487104
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	23485
ISDATBSI432MsgLenValidCount_Cnt_M_u16	8475
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	12020
ISDATDIRASentFltAcc_Cnt_M_u16	56632
ISDATDIRASentTimer_mS_M_u32	357637888
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	21599
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	55653
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	10474
ISDYN2CMMMsgTimer_mS_M_u32	3960459008
ISDYNAASChkSumInvalidCount_Cnt_M_u16	55104
ISDYNAASChkSumValidCount_Cnt_M_u16	13650
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	52712
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	11046
ISDYNAASMsgLenValidCount_Cnt_M_u16	40848
ISDYNAASMsgTimeValidCount_Cnt_M_u16	55104
ISDYNAASMsgTimer_mS_M_u32	4215484160
ISDYNABRChkSumInvalidCount_Cnt_M_u16	42795
ISDYNABRChkSumValidCount_Cnt_M_u16	12550
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	38979
ISDYNABRMsgCountValidCount_Cnt_M_u16	49813
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	39330
ISDYNABRMsgLenValidCount_Cnt_M_u16	2277
ISDYNABRMsgTimeValidCount_Cnt_M_u16	45017
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	17475
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	53842

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	23101
ISDYNCMM208MsgTimer_mS_M_u32	671125248
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	17475
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	53842
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	1643
ISDYNCMM388MsgTimer_mS_M_u32	228896512
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	19877
ISDYNVOLChkSumValidCount_Cnt_M_u16	51496
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	42349
ISDYNVOLMsgCountValidCount_Cnt_M_u16	25959
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	35620
ISDYNVOLMsgLenValidCount_Cnt_M_u16	8326
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	43721
ISDYNVOLMsgTimer_mS_M_u32	1710780160
IgnOnTimer_mS_M_u32	1452846848
IgnTimeOff_Sec_M_u32	1562325639
ManVehSpd_Kph_M_f32	159.529404
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	104
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	208
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1886052096
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	22
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1169571584
PrevISDATBSI412MsgDLCError_Cnt_M_u08	45
PrevISDATBSI412MsgRxTime_MSec_M_u32	2178871040
PrevISDATBSI432MsgDLCError_Cnt_M_u08	229
PrevISDATBSI432MsgRxTime_MSec_M_u32	2392968960
PrevISDATDIRAMsgTxTime_MSec_M_u32	455274240
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	236
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2679668480
PrevISDYNAASMsgDLCError_Cnt_M_u08	203
PrevISDYNAASMsgRxTime_MSec_M_u32	1920888576
PrevISDYNABRMsgDLCError_Cnt_M_u08	112
PrevISDYNABRMsgRxTime_MSec_M_u32	1940958976
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	17
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1556573952
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	9
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2195246848
PrevISDYNVOLMsgDLCError_Cnt_M_u08	115
PrevISDYNVOLMsgRxTime_MSec_M_u32	1147137792
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2118262528
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	89.7232971
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	39980
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	59670
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	49577
VitesseVehicleBVRampValidCount_Cnt_M_u16	8787
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	53058
VitesseVehicleBVSigValidCount_Cnt_M_u16	13172
VitesseVehicleBV_Kph_M_f32	544.569885

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	1643
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	32053
VitesseVehiculeRoues_Kph_M_f32	120.6157
k_AASNTCEnableTimeout_mS_u16	24884
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	30452
k_AASNodeTimeout_mS_u16	22550
k_ABSNodeTimeout_mS_u16	50160
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	55180
k_ANGLEVOLANTSigValidThresh_Cnt_u16	10794
k_AngleVolantInvalidThresh_Cnt_u16	55573
k_AngleVolantValidThresh_Cnt_u16	40027
k_BSI552MsgTimeout_mS_u16	36832
k_BSINTCEnableTimeout_mS_u16	43221
k_BSINodeAbsentDiag_Cnt_str.Threshold	31917
k_BSINodeAbsentDiag_Cnt_str.PStep	51866
k_BSINodeAbsentDiag_Cnt_str.NStep	38539
k_BSINodeAbsentTimeout_mS_u16	62287
k_BSINodeTimeout_mS_u16	12020
k_BattOvHi_Volt_f32	15.0558996
k_BattOvLo_Volt_f32	12.3569002
k_BattUvHi_Volt_f32	18.9358006
k_BattUvLo_Volt_f32	20.7241001
k_CAVNTCEnableTimeout_mS_u16	10873
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	62133
k_CAVNodeTimeout_mS_u16	12459
k_CMM388MsgTimeout_mS_u16	19526
k_CMM388NTCEnableTimeout_mS_u16	2130
k_CMMNTCEnableTimeout_mS_u16	14854
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	10049
k_CONSANGLECPKMax_HwDeg_f32	43.3022995
k_CONSANGLECPKMin_HwDeg_f32	-441.317902
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	13675
k_CONSANGLECPKSigValidThresh_Cnt_u16	60469
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	15492
k_CPKVehicleSpeedValidThresh_Cnt_u16	26356
k_CityParkInputInvalidThresh_Cnt_u16	27161
k_CityParkInputValidThresh_Cnt_u16	44889
k_ComputerRazGCTSigValidThresh_Cnt_u16	63548
k_CptTemporelSigValidThresh_Cnt_u16	17586
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	18594
k_DMDFCTCPKSigValidThresh_Cnt_u16	63461
k_DMDFCTCPKValidCount_Cnt_u16	4400
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	10474
k_DMDRELAXECPKSigValidThresh_Cnt_u16	31908
k_DMDRelaxeConsistentThresh_Cnt_u16	37650
k_DateValidThresh_Cnt_u16	5967
k_DefaultVehSpd_Kph_f32	244.444305
k_DiagMuxOnAbsentTimeout_mS_u16	30071
k_EMNodeTimeout_mS_u16	56432
k_ESPNTCEnableTimeout_mS_u16	3003
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	33321
k_EtatMTSigInvalidThresh_Cnt_u16	53110
k_EtatMTSigValidThresh_Cnt_u16	35729
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	23323
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	36362
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	3798
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	1919
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	20533
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	24753
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	45518
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	37356

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	19633
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	58797
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	26931
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	31168
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	42039
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	9609
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	11319
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	13975
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	54827
k_ISDYNAASChkSumValidThresh_Cnt_u16	40966
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	18243
k_ISDYNAASMsgCountValidThresh_Cnt_u16	45461
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	6431
k_ISDYNAASMsgLenValidThresh_Cnt_u16	26122
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	6930
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	62632
k_ISDYNABRChkSumValidThresh_Cnt_u16	48235
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	34888
k_ISDYNABRMsgCountValidThresh_Cnt_u16	50426
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	6601
k_ISDYNABRMsgLenValidThresh_Cnt_u16	36903
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	49957
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	51744
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16250
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	3521
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	57669
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	53687
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	63347
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	6156
k_ISDYNVOLChkSumValidThresh_Cnt_u16	19506
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	56088
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	61946
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	443
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	38217
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	20461
k_IgnOnTimeout_mS_u16	22808
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	132.429199
k_PowerCutVehSpdLowThresh_Kph_f32	160.405701
k_PowerCutVehSpdLowTimeout_mS_u16	1520
k_VBattMaxAAS_Volt_f32	9.79399967
k_VBattMaxBSI_Volt_f32	18.5883999
k_VBattMaxCAV_Volt_f32	28.2887001
k_VBattMaxCMM388_Volt_f32	14.4238005
k_VBattMaxCMM_Volt_f32	5.41230011
k_VBattMaxESP_Volt_f32	6.94780016
k_VBattMinAAS_Volt_f32	4.12720013
k_VBattMinBSI_Volt_f32	6.94780016
k_VBattMinCAV_Volt_f32	15.0426998
k_VBattMinCMM388_Volt_f32	0.223100007
k_VBattMinCMM_Volt_f32	17.4298992
k_VBattMinESP_Volt_f32	5.41230011
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	38939
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	46385
k_VitesseVehicleBVRampValidThresh_Cnt_u16	54381
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	47144
k_VitesseVehicleBVSigValidThresh_Cnt_u16	45550
k_VitesseVehicleBVSpeedPassThresh_kph_f32	310.491089
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	59823
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	25305
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	923799296
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	12726
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	825879552
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	9

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	20.0016994
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3301097216
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	68
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0963833705
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2763697920
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1636454144
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1734995712
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1582927616
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3998822144
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3211316992
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2038984448
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	113
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	148
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	155
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	201
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1656131328
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	158
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	205
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	159
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2341580544
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2447462144
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	149
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2705387264
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	6
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	30
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	79
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	123
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	150
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	170
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	822099712
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3872
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0637973472
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	93547
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	148.659897
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	32318

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	825879552	825879552	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	825879552	825879552	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	825879552	825879552	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	825879552	825879552	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	825879552	825879552	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	825879552	825879552	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	825879552	825879552	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	825879552	825879552	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	825879552	825879552	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	825879552	825879552	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	825879552	825879552	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	825879552	825879552	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	825879552	825879552	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	45017	45017	✔
CONSANGLECPK_HwDeg_M_f32	-608.999207	-608.999207 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	825879552	825879552	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	825879552	825879552	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	825879552	825879552	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	825879552	825879552	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	825879552	825879552	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	825879552	825879552	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	825879552	825879552	✔
ESPNTCEnableTimer_mS_M_u32	825879552	825879552	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	825879552	825879552	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	99	99	✔
EffacDefaultDiagTimer_mS_M_u32[1]	999	999	✔
ElecIntCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	825879552	825879552	✔
ElecIntTimer_mS_M_u32[1]	99	99	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	825879552	825879552	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	825879552	825879552	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	825879552	825879552	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	825879552	825879552	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	825879552	825879552	✔
ISDATDIRASentFltAcc_Cnt_M_u16	41895	41895	✔
ISDATDIRASentTimer_mS_M_u32	825879552	825879552	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	825879552	825879552	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	825879552	825879552	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	825879552	825879552	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	825879552	825879552	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	825879552	825879552	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	825879552	825879552	✔
IgnOnTimer_mS_M_u32	1452846848	1452846848	✔
IgnTimeOff_Sec_M_u32	1562325639	1562325639	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	117	117	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2763697920	2763697920	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	172	172	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1636454144	1636454144	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	216	216	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1734995712	1734995712	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	162	162	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1582927616	1582927616	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	455274240	455274240	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	172	172	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3211316992	3211316992	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	60	60	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2038984448	2038984448	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	34	34	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1656131328	1656131328	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	159	159	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2341580544	2341580544	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	64	64	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2447462144	2447462144	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	149	149	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2705387264	2705387264	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	822099712	822099712	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	89.7232971	89.7232971	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	544.569885	544.569885	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	120.6157	120.6157	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	45017	45017	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1562325639	1562325639	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-608.999207	-608.999207 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	244.444305	244.444305	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.340 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	87582208
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	53510
AASNodeAbsentTimer_mS_M_u32	839931392
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	11275
ANGLEVOLANTSigValidCount_Cnt_M_u16	57204
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	10291
AngleVolantMsgTimer_mS_M_u32	87582208
AngleVolantValidCount_Cnt_M_u16	24363
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3304330752
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	896177664
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	207685120
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	461620736
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	770
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1853982208
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	1355
CAVNodeAbsentTimer_mS_M_u32	4270650880
CDD_SrlComVehSpd_Kph_G_f32	226.6931
CMM388NTCEnableTimer_mS_M_u32	2054501888
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	71497216
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	42687
CMMNodeAbsentTimer_mS_M_u32	1682818560
CONSANGLECPKSigInvalidCount_Cnt_M_u16	8443
CONSANGLECPKSigValidCount_Cnt_M_u16	64692
CONSANGLECPK_Cnt_M_u16	12047
CONSANGLECPK_HwDeg_M_f32	555.224976
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	12047
CPKVehicleSpeedMsgTimer_mS_M_u32	3001509376
CPKVehicleSpeedValidCount_Cnt_M_u16	23646
CityParkInputConsistentCount_Cnt_M_u16	44367
CityParkInputInvalidCount_Cnt_M_u16	48968
CityParkInputMsgTimer_mS_M_u32	2763697920
CityParkInputValidCount_Cnt_M_u16	3

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2919801088
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	5418
ComputerRazGCTSigInvalidTimer_mS_M_u32	861238784
ComputerRazGCTSigValidCount_Cnt_M_u16	42164
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	3364
DMDFCTCPKSigValidCount_Cnt_M_u16	47989
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	6685
DMDRELAXECPKSigValidCount_Cnt_M_u16	38662
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	49448
DateInvalidTimer_mS_M_u32	896177664
DiagMuxOnAbsentTimer_mS_M_u32	3843433984
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	461620736
ESPNTCEnableTimer_mS_M_u32	1747015168
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	30820
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	9
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	66
ElecIntTimer_mS_M_u32[1]	79
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1291027968
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	43276
EtatMTSigValidCount_Cnt_M_u16	13857
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	50445
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	59974
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	39723
ISDAT4V2BSI552MsgTimer_mS_M_u32	242337280
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	16591
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	43949
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13857
ISDATBSI3F2MsgTimer_mS_M_u32	3640927744
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	15202
ISDATBSI412MsgLenValidCount_Cnt_M_u16	31599
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	43276
ISDATBSI412MsgTimer_mS_M_u32	3743835648
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	25571
ISDATBSI432MsgLenValidCount_Cnt_M_u16	34952
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	64636
ISDATDIRASentFltAcc_Cnt_M_u16	432
ISDATDIRASentTimer_mS_M_u32	3001509376
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	55677
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	24363
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	5531
ISDYN2CMMMsgTimer_mS_M_u32	3312145920
ISDYNAASChkSumInvalidCount_Cnt_M_u16	35608
ISDYNAASChkSumValidCount_Cnt_M_u16	46498
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	19874
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	20454
ISDYNAASMsgLenValidCount_Cnt_M_u16	38759
ISDYNAASMsgTimeValidCount_Cnt_M_u16	35608
ISDYNAASMsgTimer_mS_M_u32	491861504
ISDYNABRChkSumInvalidCount_Cnt_M_u16	32982
ISDYNABRChkSumValidCount_Cnt_M_u16	18440
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	5135
ISDYNABRMsgCountValidCount_Cnt_M_u16	55769
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	40178
ISDYNABRMsgLenValidCount_Cnt_M_u16	21483
ISDYNABRMsgTimeValidCount_Cnt_M_u16	12047
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	8577
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	61459
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13857
ISDYNCMM208MsgTimer_mS_M_u32	3298366976

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	8577
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	61459
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	28697
ISDYNCMM388MsgTimer_mS_M_u32	1277998592
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	19689
ISDYNVOLChkSumValidCount_Cnt_M_u16	57122
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	27666
ISDYNVOLMsgCountValidCount_Cnt_M_u16	4323
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	44653
ISDYNVOLMsgLenValidCount_Cnt_M_u16	29447
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	42687
ISDYNVOLMsgTimer_mS_M_u32	1110537728
IgnOnTimer_mS_M_u32	1095808512
IgnTimeOff_Sec_M_u32	2446664407
ManVehSpd_Kph_M_f32	554.261597
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	105
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	101
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	949626368
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	30
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2654471680
PrevISDATBSI412MsgDLCError_Cnt_M_u08	108
PrevISDATBSI412MsgRxTime_MSec_M_u32	2826827264
PrevISDATBSI432MsgDLCError_Cnt_M_u08	22
PrevISDATBSI432MsgRxTime_MSec_M_u32	2780124672
PrevISDATDIRAMsgTxTime_MSec_M_u32	3971085824
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	52
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1764836864
PrevISDYNAASMsgDLCError_Cnt_M_u08	7
PrevISDYNAASMsgRxTime_MSec_M_u32	3030349312
PrevISDYNABRMsgDLCError_Cnt_M_u08	188
PrevISDYNABRMsgRxTime_MSec_M_u32	1242084864
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	247
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1506047488
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	166
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1695569408
PrevISDYNVOLMsgDLCError_Cnt_M_u08	0
PrevISDYNVOLMsgRxTime_MSec_M_u32	2767910400
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2081711616
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	177.204193
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	38100
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	21205
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	22621
VitesseVehicleBVRampValidCount_Cnt_M_u16	56094
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	35092
VitesseVehicleBVSigValidCount_Cnt_M_u16	8509
VitesseVehicleBV_Kph_M_f32	502.22699
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	28697
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	12410

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	398.596008
k_AASNTCEnableTimeout_mS_u16	18174
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	33406
k_AASNodeTimeout_mS_u16	1493
k_ABSNodeTimeout_mS_u16	56457
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	60534
k_ANGLEVOLANTSigValidThresh_Cnt_u16	26971
k_AngleVolantInvalidThresh_Cnt_u16	51354
k_AngleVolantValidThresh_Cnt_u16	48968
k_BSI552MsgTimeout_mS_u16	25721
k_BSINTCEnableTimeout_mS_u16	56475
k_BSINodeAbsentDiag_Cnt_str.Threshold	39361
k_BSINodeAbsentDiag_Cnt_str.PStep	10043
k_BSINodeAbsentDiag_Cnt_str.NStep	19113
k_BSINodeAbsentTimeout_mS_u16	13035
k_BSINodeTimeout_mS_u16	64636
k_BattOvHi_Volt_f32	8.03880024
k_BattOvLo_Volt_f32	16.3581009
k_BattUvHi_Volt_f32	5.34959984
k_BattUvLo_Volt_f32	10.7438002
k_CAVNTCEnableTimeout_mS_u16	3310
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	62777
k_CAVNodeTimeout_mS_u16	15319
k_CMM388MsgTimeout_mS_u16	50182
k_CMM388NTCEnableTimeout_mS_u16	49122
k_CMMNTCEnableTimeout_mS_u16	54663
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	25174
k_CONSANGLECPKMax_HwDeg_f32	714.71582
k_CONSANGLECPKMin_HwDeg_f32	-741.682495
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	58137
k_CONSANGLECPKSigValidThresh_Cnt_u16	58234
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	37003
k_CPKVehicleSpeedValidThresh_Cnt_u16	55229
k_CityParkInputInvalidThresh_Cnt_u16	28684
k_CityParkInputValidThresh_Cnt_u16	44367
k_ComputerRazGCTSigValidThresh_Cnt_u16	62181
k_CptTemporelSigValidThresh_Cnt_u16	57923
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	36850
k_DMDFCTCPKSigValidThresh_Cnt_u16	34539
k_DMDFCTCPKValidCount_Cnt_u16	64330
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	5531
k_DMDRELAXECPKSigValidThresh_Cnt_u16	65324
k_DMDRelaxeConsistentThresh_Cnt_u16	62434
k_DateValidThresh_Cnt_u16	39723
k_DefaultVehSpd_Kph_f32	224.021606
k_DiagMuxOnAbsentTimeout_mS_u16	54837
k_EMNodeTimeout_mS_u16	35976
k_ESPNTCEnableTimeout_mS_u16	16935
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	61854
k_EtatMTSigInvalidThresh_Cnt_u16	62453
k_EtatMTSigValidThresh_Cnt_u16	9319
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	20678
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	27836
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	49880
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	37148
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	35770
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	7814
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	58800
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	47637
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	24839
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	56723

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	26561
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	8280
k_ISDATDIRASentDiag_Cnt_str.Threshold	1170
k_ISDATDIRASentDiag_Cnt_str.PStep	4955
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	47538
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	33021
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	10291
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	12691
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	62422
k_ISDYNAASChkSumValidThresh_Cnt_u16	64264
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	1807
k_ISDYNAASMsgCountValidThresh_Cnt_u16	3289
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	64250
k_ISDYNAASMsgLenValidThresh_Cnt_u16	44025
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	13987
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	9184
k_ISDYNABRChkSumValidThresh_Cnt_u16	53593
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	62978
k_ISDYNABRMsgCountValidThresh_Cnt_u16	1195
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	22975
k_ISDYNABRMsgLenValidThresh_Cnt_u16	27492
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	30250
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	56056
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	58923
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	20692
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	7947
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	4724
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	3584
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	9333
k_ISDYNVOLChkSumValidThresh_Cnt_u16	7362
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	36497
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	54572
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	15080
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	46333
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	59729
k_IgnOnTimeout_mS_u16	37201
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	200.567001
k_PowerCutVehSpdLowThresh_Kph_f32	220.637299
k_PowerCutVehSpdLowTimeout_mS_u16	18634
k_VBattMaxAAS_Volt_f32	20.0349007
k_VBattMaxBSI_Volt_f32	20.0130005
k_VBattMaxCAV_Volt_f32	28.7136993
k_VBattMaxCMM388_Volt_f32	26.5447998
k_VBattMaxCMM_Volt_f32	28.1525993
k_VBattMaxESP_Volt_f32	13.4590998
k_VBattMinAAS_Volt_f32	8.7723999
k_VBattMinBSI_Volt_f32	13.4590998
k_VBattMinCAV_Volt_f32	1.00160003
k_VBattMinCMM388_Volt_f32	14.0718002
k_VBattMinCMM_Volt_f32	21.5870991
k_VBattMinESP_Volt_f32	28.1525993
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	61767
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	61124
k_VitesseVehicleBVRampValidThresh_Cnt_u16	57106
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	4642
k_VitesseVehicleBVSigValidThresh_Cnt_u16	14736
k_VitesseVehicleBVSpeedPassThresh_kph_f32	138.552094
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	30795
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	45452
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	896177664
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	42563
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3466657536
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	166
target_SrlComInput_Per1_Batt_Volt_f32.value	10.5391998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4078077440
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	222
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.288023263
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	226
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1592440320
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	98
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1861998080
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3822908928
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3314423296
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	470758912
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4016068096
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	50
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1199666688
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	85
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	140
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	190
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	192
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1819743744
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	65
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	147
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	217
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	127
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3328554496
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4193703424
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	41
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1381496320
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	53
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	77
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	94
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	177
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	189
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2220492288
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	537
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.163764447
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	643421
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	24.1247997
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	46750

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3466657536	3466657536	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3466657536	3466657536	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
CDD_SrlComVehSpd_Kph_G_f32	554.261597	554.261597	✔
CMM388NTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	12047	12047	✔
CONSANGLECPK_HwDeg_M_f32	555.224976	555.224976 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3466657536	3466657536	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3466657536	3466657536	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3466657536	3466657536	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3466657536	3466657536	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3466657536	3466657536	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3466657536	3466657536	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3466657536	3466657536	✔
ESPNTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	8	8	✔
EffacDefaultDiagTimer_mS_M_u32[1]	9	9	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	66	66	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	79	79	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3466657536	3466657536	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	39723	39723	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	13857	13857	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	43276	43276	✔
ISDATBSI412MsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	64636	64636	✔
ISDATBSI432MsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1170	1170	✔
ISDATDIRASentTimer_mS_M_u32	3466657536	3466657536	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	5531	5531	✔
ISDYN2CMMMsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	35608	35608	✔
ISDYNAASMsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	12047	12047	✔
ISDYNABRMsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	13857	13857	✔
ISDYNCMM208MsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	28697	28697	✔
ISDYNCMM388MsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	42687	42687	✔
ISDYNVOLMsgTimer_mS_M_u32	3466657536	3466657536	✔
IgnOnTimer_mS_M_u32	1095808512	1095808512	✔
IgnTimeOff_Sec_M_u32	2446664407	2446664407	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	226	226	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1592440320	1592440320	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	98	98	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1861998080	1861998080	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	68	68	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3822908928	3822908928	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	142	142	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3314423296	3314423296	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3971085824	3971085824	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	125	125	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4016068096	4016068096	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	50	50	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1199666688	1199666688	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	194	194	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1819743744	1819743744	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	127	127	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3328554496	3328554496	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4193703424	4193703424	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	41	41	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1381496320	1381496320	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2220492288	2220492288	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	177.204193	177.204193	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	502.22699	502.22699	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	398.596008	398.596008	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	12047	12047	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2446664407	2446664407	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	555.224976	555.224976 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.341 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2098041088
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	29602
AASNodeAbsentTimer_mS_M_u32	2185609472
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	5268
ANGLEVOLANTSigValidCount_Cnt_M_u16	44056
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	25115
AngleVolantMsgTimer_mS_M_u32	2098041088
AngleVolantValidCount_Cnt_M_u16	437
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	144343296
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2973171968
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1377022208
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	531329280
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	11183
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1303523584
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	12628
CAVNodeAbsentTimer_mS_M_u32	1464852736
CDD_SrlComVehSpd_Kph_G_f32	583.795471
CMM388NTCEnableTimer_mS_M_u32	3566674176
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2653806848
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	63417
CMMNodeAbsentTimer_mS_M_u32	3981275392
CONSANGLECPKSigInvalidCount_Cnt_M_u16	42181
CONSANGLECPKSigValidCount_Cnt_M_u16	857
CONSANGLECPK_Cnt_M_u16	38984
CONSANGLECPK_HwDeg_M_f32	409.308014
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	38984
CPKVehicleSpeedMsgTimer_mS_M_u32	4026568960
CPKVehicleSpeedValidCount_Cnt_M_u16	5697
CityParkInputConsistentCount_Cnt_M_u16	42825
CityParkInputInvalidCount_Cnt_M_u16	58973
CityParkInputMsgTimer_mS_M_u32	1592440320
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2363080960
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2062967040
ComputerRazGCTSigValidCount_Cnt_M_u16	38170
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	27849
DMDFCTCPKSigValidCount_Cnt_M_u16	45973
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	4702
DMDRELAXECPKSigValidCount_Cnt_M_u16	19810
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	47166
DateInvalidTimer_mS_M_u32	2973171968
DiagMuxOnAbsentTimer_mS_M_u32	2222215424
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	531329280
ESPNTCEnableTimer_mS_M_u32	1678950656
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	9352
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	4
EffacDefaultDiagTimer_mS_M_u32[1]	5
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	101
ElecIntTimer_mS_M_u32[1]	106
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	4200345856
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	46545
EtatMTSigValidCount_Cnt_M_u16	28753
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	32911
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	675
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	27763
ISDAT4V2BSI552MsgTimer_mS_M_u32	2128703744
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	46087
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	62766
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	28753
ISDATBSI3F2MsgTimer_mS_M_u32	3769258240
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	56656
ISDATBSI412MsgLenValidCount_Cnt_M_u16	24296
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	46545
ISDATBSI412MsgTimer_mS_M_u32	658739456
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	20557
ISDATBSI432MsgLenValidCount_Cnt_M_u16	33820
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	20417
ISDATDIRASentFltAcc_Cnt_M_u16	4133
ISDATDIRASentTimer_mS_M_u32	4026568960
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	53502
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	437
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	61284
ISDYN2CMMMsgTimer_mS_M_u32	4097097984
ISDYNAASChkSumInvalidCount_Cnt_M_u16	3436
ISDYNAASChkSumValidCount_Cnt_M_u16	49039
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	53840
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	32131
ISDYNAASMsgLenValidCount_Cnt_M_u16	47294
ISDYNAASMsgTimeValidCount_Cnt_M_u16	3436
ISDYNAASMsgTimer_mS_M_u32	1543708928
ISDYNABRChkSumInvalidCount_Cnt_M_u16	64434
ISDYNABRChkSumValidCount_Cnt_M_u16	30686
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	3719
ISDYNABRMsgCountValidCount_Cnt_M_u16	61162
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	52448
ISDYNABRMsgLenValidCount_Cnt_M_u16	39348
ISDYNABRMsgTimeValidCount_Cnt_M_u16	38984
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	29155
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	39916
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	28753
ISDYNCMM208MsgTimer_mS_M_u32	3719004416
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	29155
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	39916
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	1771

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2641404160
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	22779
ISDYNVOLChkSumValidCount_Cnt_M_u16	37903
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	34815
ISDYNVOLMsgCountValidCount_Cnt_M_u16	60235
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	58989
ISDYNVOLMsgLenValidCount_Cnt_M_u16	2657
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	63417
ISDYNVOLMsgTimer_mS_M_u32	3194118400
IgnOnTimer_mS_M_u32	1308926208
IgnTimeOff_Sec_M_u32	2728195707
ManVehSpd_Kph_M_f32	410.618805
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	106
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	43
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2582139136
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	98
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3096359168
PrevISDATBSI412MsgDLCError_Cnt_M_u08	189
PrevISDATBSI412MsgRxTime_MSec_M_u32	1568465152
PrevISDATBSI432MsgDLCError_Cnt_M_u08	70
PrevISDATBSI432MsgRxTime_MSec_M_u32	4216766720
PrevISDATDIRAMsgTxTime_MSec_M_u32	1625350400
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	86
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3433230592
PrevISDYNAASMsgDLCError_Cnt_M_u08	141
PrevISDYNAASMsgRxTime_MSec_M_u32	2669175040
PrevISDYNABRMsgDLCError_Cnt_M_u08	132
PrevISDYNABRMsgRxTime_MSec_M_u32	333226240
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	116
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2208915712
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	166
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3913662720
PrevISDYNVOLMsgDLCError_Cnt_M_u08	205
PrevISDYNVOLMsgRxTime_MSec_M_u32	2617630976
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2289668352
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	19.5179005
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	59065
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	48756
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	30
VitesseVehicleBVRampValidCount_Cnt_M_u16	35225
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	24953
VitesseVehicleBVSigValidCount_Cnt_M_u16	19133
VitesseVehicleBV_Kph_M_f32	539.161316
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	1771
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	22407
VitesseVehiculeRoues_Kph_M_f32	382.155609
k_AASNTCEnableTimeout_mS_u16	52347
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	41916
k_AASNodeTimeout_mS_u16	42356
k_ABSNodeTimeout_mS_u16	53914
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	49812
k_ANGLEVOLANTSigValidThresh_Cnt_u16	60835
k_AngleVolantInvalidThresh_Cnt_u16	35814
k_AngleVolantValidThresh_Cnt_u16	58973
k_BSI552MsgTimeout_mS_u16	30602
k_BSINTCEnableTimeout_mS_u16	50725
k_BSINodeAbsentDiag_Cnt_str.Threshold	42144
k_BSINodeAbsentDiag_Cnt_str.PStep	38516
k_BSINodeAbsentDiag_Cnt_str.NStep	38507
k_BSINodeAbsentTimeout_mS_u16	8691
k_BSINodeTimeout_mS_u16	20417
k_BattOvHi_Volt_f32	7.36329985
k_BattOvLo_Volt_f32	14.2391005
k_BattUvHi_Volt_f32	21.0804996
k_BattUvLo_Volt_f32	5.11999989
k_CAVNTCEnableTimeout_mS_u16	5483
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	39306
k_CAVNodeTimeout_mS_u16	50225
k_CMM388MsgTimeout_mS_u16	39586
k_CMM388NTCEnableTimeout_mS_u16	5902
k_CMMNTCEnableTimeout_mS_u16	54751
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	12787
k_CONSANGLECPKMax_HwDeg_f32	695.257202
k_CONSANGLECPKMin_HwDeg_f32	-246.771698
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	44523
k_CONSANGLECPKSigValidThresh_Cnt_u16	16007
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	23890
k_CPKVehicleSpeedValidThresh_Cnt_u16	13375
k_CityParkInputInvalidThresh_Cnt_u16	34320
k_CityParkInputValidThresh_Cnt_u16	42825
k_ComputerRazGCTSigValidThresh_Cnt_u16	30149
k_CptTemporelSigValidThresh_Cnt_u16	10604
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	62432
k_DMDFCTCPKSigValidThresh_Cnt_u16	180
k_DMDFCTCPKValidCount_Cnt_u16	25303
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	61284
k_DMDRELAXECPKSigValidThresh_Cnt_u16	33904
k_DMDRelaxeConsistentThresh_Cnt_u16	65102
k_DateValidThresh_Cnt_u16	27763
k_DefaultVehSpd_Kph_f32	9.14920044
k_DiagMuxOnAbsentTimeout_mS_u16	47830
k_EMNodeTimeout_mS_u16	54814
k_ESPNTCEnableTimeout_mS_u16	60096
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	42011
k_EtatMTSigInvalidThresh_Cnt_u16	56917
k_EtatMTSigValidThresh_Cnt_u16	7873
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	51361
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	22145
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	51886
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	14112
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	51463
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	50148
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	16102
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	25461
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	59617
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	40124
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	49139
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	55149
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	49438
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	35198
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	25115
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	52348
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	41650
k_ISDYNAASChkSumValidThresh_Cnt_u16	24286
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	13703
k_ISDYNAASMsgCountValidThresh_Cnt_u16	21994
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	7494
k_ISDYNAASMsgLenValidThresh_Cnt_u16	17160
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	42443
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	28694
k_ISDYNABRChkSumValidThresh_Cnt_u16	22890
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	21167
k_ISDYNABRMsgCountValidThresh_Cnt_u16	55411
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	57017
k_ISDYNABRMsgLenValidThresh_Cnt_u16	19336
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	16374
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	42061
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16629
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	32887
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	15252
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	4888
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	55861
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	11799
k_ISDYNVOLChkSumValidThresh_Cnt_u16	34543
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	54785
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	24690
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	28733
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	25533
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	39425
k_IgnOnTimeout_mS_u16	22403
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	134.013
k_PowerCutVehSpdLowThresh_Kph_f32	17.802
k_PowerCutVehSpdLowTimeout_mS_u16	63255
k_VBattMaxAAS_Volt_f32	18.6847
k_VBattMaxBSI_Volt_f32	5.66620016
k_VBattMaxCAV_Volt_f32	31.1588993
k_VBattMaxCMM388_Volt_f32	3.95670009
k_VBattMaxCMM_Volt_f32	9.4137001
k_VBattMaxESP_Volt_f32	17.7548008
k_VBattMinAAS_Volt_f32	5.26020002
k_VBattMinBSI_Volt_f32	17.7548008
k_VBattMinCAV_Volt_f32	19.6457996
k_VBattMinCMM388_Volt_f32	8.6012001
k_VBattMinCMM_Volt_f32	6.6480999
k_VBattMinESP_Volt_f32	9.4137001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	57504
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	59880
k_VitesseVehicleBVRampValidThresh_Cnt_u16	12031
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	64271
k_VitesseVehicleBVSigValidThresh_Cnt_u16	18054
k_VitesseVehicleBVSpeedPassThresh_kph_f32	233.540604
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	55380
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	15951
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2973171968
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	27719
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	511165952
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	166
target_SrlComInput_Per1_Batt_Volt_f32.value	8.90919971
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1140797696
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	63
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.494600654
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3711344896
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	127
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3649257728
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3881820416
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	213
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4006379776
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3620282624
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	225
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2320875776
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4000473344
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	31
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	79
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	104
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	244
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3725689088
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	44
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	60
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	107
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	71
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1388683520
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	7
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3834790144
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	165
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1206837504
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	32
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	48
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	56
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	68
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	72
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	149
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	237547776
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3552
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.670106649
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	671639
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	22.5893993
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	10587

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	511165952	511165952	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	511165952	511165952	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	511165952	511165952	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	511165952	511165952	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	511165952	511165952	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	511165952	511165952	✔
CDD_SrlComVehSpd_Kph_G_f32	410.618805	410.618805	✔
CMM388NTCEnableTimer_mS_M_u32	511165952	511165952	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	511165952	511165952	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	511165952	511165952	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	38984	38984	✔
CONSANGLECPK_HwDeg_M_f32	409.308014	409.308014 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	511165952	511165952	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	511165952	511165952	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	511165952	511165952	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	511165952	511165952	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	511165952	511165952	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	511165952	511165952	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	511165952	511165952	✔
ESPNTCEnableTimer_mS_M_u32	511165952	511165952	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	511165952	511165952	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4	4	✔
EffacDefaultDiagTimer_mS_M_u32[1]	5	5	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	101	101	✔
ElecIntTimer_mS_M_u32[1]	106	106	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	511165952	511165952	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	27763	27763	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	28753	28753	✔
ISDATBSI3F2MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	46545	46545	✔
ISDATBSI412MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	20417	20417	✔
ISDATBSI432MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11170	11170	✔
ISDATDIRASentTimer_mS_M_u32	511165952	511165952	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	61284	61284	✔
ISDYN2CMMMsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	3436	3436	✔
ISDYNAASMsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	38984	38984	✔
ISDYNABRMsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	28753	28753	✔
ISDYNCMM208MsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	1771	1771	✔
ISDYNCMM388MsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	63417	63417	✔
ISDYNVOLMsgTimer_mS_M_u32	511165952	511165952	✔
IgnOnTimer_mS_M_u32	1308926208	1308926208	✔
IgnTimeOff_Sec_M_u32	2728195707	2728195707	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	117	117	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3711344896	3711344896	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	127	127	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3649257728	3649257728	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	167	167	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3881820416	3881820416	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	213	213	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4006379776	4006379776	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1625350400	1625350400	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	225	225	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2320875776	2320875776	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	143	143	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4000473344	4000473344	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	30	30	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3725689088	3725689088	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	71	71	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1388683520	1388683520	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	7	7	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3834790144	3834790144	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	165	165	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1206837504	1206837504	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	237547776	237547776	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	19.5179005	19.5179005	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	539.161316	539.161316	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	382.155609	382.155609	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	38984	38984	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2728195707	2728195707	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	409.308014	409.308014 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	410.618805	410.618805	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.342 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	872026112
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	16956
AASNodeAbsentTimer_mS_M_u32	2165407744
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	18789
ANGLEVOLANTSigValidCount_Cnt_M_u16	28058
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	39633
AngleVolantMsgTimer_mS_M_u32	872026112
AngleVolantValidCount_Cnt_M_u16	61057
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	823345152
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1228783616
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	4117213184
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2610982912
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	12308
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2626433024
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	63910
CAVNodeAbsentTimer_mS_M_u32	1383276544
CDD_SrlComVehSpd_Kph_G_f32	572.43103
CMM388NTCEnableTimer_mS_M_u32	127754240
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1977163776
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	42551
CMMNodeAbsentTimer_mS_M_u32	985296896
CONSANGLECPKSigInvalidCount_Cnt_M_u16	19410
CONSANGLECPKSigValidCount_Cnt_M_u16	23255
CONSANGLECPK_Cnt_M_u16	6154
CONSANGLECPK_HwDeg_M_f32	-705.270996
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	6154
CPKVehicleSpeedMsgTimer_mS_M_u32	1730220032
CPKVehicleSpeedValidCount_Cnt_M_u16	11364
CityParkInputConsistentCount_Cnt_M_u16	19909
CityParkInputInvalidCount_Cnt_M_u16	12680
CityParkInputMsgTimer_mS_M_u32	3711344896
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2975170560
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	65535

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2709495808
ComputerRazGCTSigValidCount_Cnt_M_u16	2130
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	20036
DMDFCTCPKSigValidCount_Cnt_M_u16	33953
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	63495
DMDRELAXECPKSigValidCount_Cnt_M_u16	12732
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	13671
DateInvalidTimer_mS_M_u32	1228783616
DiagMuxOnAbsentTimer_mS_M_u32	684052480
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2610982912
ESPNTCEnableTimer_mS_M_u32	1336573952
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	14984
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	6
EffacDefaultDiagTimer_mS_M_u32[1]	7
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	99
ElecIntTimer_mS_M_u32[1]	1000
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3196989440
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	7406
EtatMTSigValidCount_Cnt_M_u16	51247
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24692
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1273
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20999
ISDAT4V2BSI552MsgTimer_mS_M_u32	3590221824
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	53709
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	35093
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	51247
ISDATBSI3F2MsgTimer_mS_M_u32	1814286336
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	2801
ISDATBSI412MsgLenValidCount_Cnt_M_u16	49386
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	7406
ISDATBSI412MsgTimer_mS_M_u32	2371358720
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	60539
ISDATBSI432MsgLenValidCount_Cnt_M_u16	27596
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	37471
ISDATDIRASentFltAcc_Cnt_M_u16	57651
ISDATDIRASentTimer_mS_M_u32	1730220032
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	50664
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	61057
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	62067
ISDYN2CMMMsgTimer_mS_M_u32	2806284288
ISDYNAASChkSumInvalidCount_Cnt_M_u16	7390
ISDYNAASChkSumValidCount_Cnt_M_u16	28979
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	43184
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	37145
ISDYNAASMsgLenValidCount_Cnt_M_u16	43558
ISDYNAASMsgTimeValidCount_Cnt_M_u16	7390
ISDYNAASMsgTimer_mS_M_u32	559505408
ISDYNABRChkSumInvalidCount_Cnt_M_u16	58251
ISDYNABRChkSumValidCount_Cnt_M_u16	63944
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	17805
ISDYNABRMsgCountValidCount_Cnt_M_u16	3874
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	65409
ISDYNABRMsgLenValidCount_Cnt_M_u16	50118
ISDYNABRMsgTimeValidCount_Cnt_M_u16	6154
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	14440
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	63758
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	51247
ISDYNCMM208MsgTimer_mS_M_u32	903888896
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	14440
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	63758
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	14047

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	4077969408
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	34608
ISDYNVOLChkSumValidCount_Cnt_M_u16	181
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	21666
ISDYNVOLMsgCountValidCount_Cnt_M_u16	13695
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	51417
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1982
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	42551
ISDYNVOLMsgTimer_mS_M_u32	2268831744
IgnOnTimer_mS_M_u32	827645952
IgnTimeOff_Sec_M_u32	843727999
ManVehSpd_Kph_M_f32	632.394897
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	107
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	189
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3093942272
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	240
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1844883456
PrevISDATBSI412MsgDLCError_Cnt_M_u08	14
PrevISDATBSI412MsgRxTime_MSec_M_u32	871112704
PrevISDATBSI432MsgDLCError_Cnt_M_u08	226
PrevISDATBSI432MsgRxTime_MSec_M_u32	2581495808
PrevISDATDIRAMsgTxTime_MSec_M_u32	3116376064
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	117
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3535400960
PrevISDYNAASMsgDLCError_Cnt_M_u08	184
PrevISDYNAASMsgRxTime_MSec_M_u32	1025089536
PrevISDYNABRMsgDLCError_Cnt_M_u08	150
PrevISDYNABRMsgRxTime_MSec_M_u32	1070391296
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	230
PrevISDYNCMM208MsgRxTime_MSec_M_u32	325492736
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	145
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1276215296
PrevISDYNVOLMsgDLCError_Cnt_M_u08	117
PrevISDYNVOLMsgRxTime_MSec_M_u32	3696304128
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3249934336
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	465.456207
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	44407
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	61700
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	13640
VitesseVehicleBVRampValidCount_Cnt_M_u16	25493
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	14006
VitesseVehicleBVSigValidCount_Cnt_M_u16	26027
VitesseVehicleBV_Kph_M_f32	329.450714
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	14047
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	36812
VitesseVehiculeRoues_Kph_M_f32	235.1436
k_AASNTCEnableTimeout_mS_u16	1905
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	58476
k_AASNodeTimeout_mS_u16	15364
k_ABSNodeTimeout_mS_u16	41169
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	29094
k_ANGLEVOLANTSigValidThresh_Cnt_u16	2871
k_AngleVolantInvalidThresh_Cnt_u16	64622
k_AngleVolantValidThresh_Cnt_u16	12680
k_BSI552MsgTimeout_mS_u16	64451
k_BSINTCEnableTimeout_mS_u16	60147
k_BSINodeAbsentDiag_Cnt_str.Threshold	52655
k_BSINodeAbsentDiag_Cnt_str.PStep	10614
k_BSINodeAbsentDiag_Cnt_str.NStep	60112
k_BSINodeAbsentTimeout_mS_u16	47945
k_BSINodeTimeout_mS_u16	37471
k_BattOvHi_Volt_f32	23.7889996
k_BattOvLo_Volt_f32	5.16120005
k_BattUvHi_Volt_f32	30.6891994
k_BattUvLo_Volt_f32	12.9042997
k_CAVNTCEnableTimeout_mS_u16	23646
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	6404
k_CAVNodeTimeout_mS_u16	40334
k_CMM388MsgTimeout_mS_u16	52540
k_CMM388NTCEnableTimeout_mS_u16	2040
k_CMMNTCEnableTimeout_mS_u16	52293
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	45192
k_CONSANGLECPKMax_HwDeg_f32	577.974792
k_CONSANGLECPKMin_HwDeg_f32	-171.267807
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	16863
k_CONSANGLECPKSigValidThresh_Cnt_u16	56012
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	3178
k_CPKVehicleSpeedValidThresh_Cnt_u16	33316
k_CityParkInputInvalidThresh_Cnt_u16	15473
k_CityParkInputValidThresh_Cnt_u16	19909
k_ComputerRazGCTSigValidThresh_Cnt_u16	1171
k_CptTemporelSigValidThresh_Cnt_u16	25691
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	35457
k_DMDFCTCPKSigValidThresh_Cnt_u16	36550
k_DMDFCTCPKValidCount_Cnt_u16	10908
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	62067
k_DMDRELAXECPKSigValidThresh_Cnt_u16	15888
k_DMDRelaxeConsistentThresh_Cnt_u16	51318
k_DateValidThresh_Cnt_u16	20999
k_DefaultVehSpd_Kph_f32	58.1882019
k_DiagMuxOnAbsentTimeout_mS_u16	26720
k_EMNodeTimeout_mS_u16	23495
k_ESPNTCEnableTimeout_mS_u16	32098
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	64016
k_EtatMTSigInvalidThresh_Cnt_u16	34722
k_EtatMTSigValidThresh_Cnt_u16	20767
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	50813
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	30622
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	46998
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	60546
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	45450
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	42805
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	50352
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	29121
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	29375
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	55982
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	11207
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	8601
k_ISDATDIRASentDiag_Cnt_str.Threshold	37951

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	62140
k_ISDATDIRASentDiag_Cnt_str.NStep	43836
k_ISDATDIRASentTimeout_mS_u16	17223
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	36710
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	39633
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	51246
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	61067
k_ISDYNAASChkSumValidThresh_Cnt_u16	17608
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	53389
k_ISDYNAASMsgCountValidThresh_Cnt_u16	55842
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	52943
k_ISDYNAASMsgLenValidThresh_Cnt_u16	45896
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	33471
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	28127
k_ISDYNABRChkSumValidThresh_Cnt_u16	56484
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	47892
k_ISDYNABRMsgCountValidThresh_Cnt_u16	5257
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	61751
k_ISDYNABRMsgLenValidThresh_Cnt_u16	50568
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	43520
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	50363
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	46082
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	30459
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	54373
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	14490
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	46592
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	62620
k_ISDYNVOLChkSumValidThresh_Cnt_u16	9429
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	18973
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	36876
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	40362
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	40427
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	33117
k_IgnOnTimeout_mS_u16	10328
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	32.0969009
k_PowerCutVehSpdLowThresh_Kph_f32	36.7296982
k_PowerCutVehSpdLowTimeout_mS_u16	63389
k_VBattMaxAAS_Volt_f32	15.0551996
k_VBattMaxBSI_Volt_f32	27.3624992
k_VBattMaxCAV_Volt_f32	27.1005001
k_VBattMaxCMM388_Volt_f32	11.8339005
k_VBattMaxCMM_Volt_f32	30.6222992
k_VBattMaxESP_Volt_f32	13.8167
k_VBattMinAAS_Volt_f32	31.9645004
k_VBattMinBSI_Volt_f32	13.8167
k_VBattMinCAV_Volt_f32	15.5880003
k_VBattMinCMM388_Volt_f32	30.2236996
k_VBattMinCMM_Volt_f32	7.30480003
k_VBattMinESP_Volt_f32	30.6222992
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	37376
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	28905
k_VitesseVehicleBVRampValidThresh_Cnt_u16	24482
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	52149
k_VitesseVehicleBVSigValidThresh_Cnt_u16	41998
k_VitesseVehicleBVSpeedPassThresh_kph_f32	185.5289
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	1190
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	40307
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1228783616
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	145
target_SrlComInput_Per1_Batt_Volt_f32.value	21.8519993
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	765800448
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	1
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.054976292
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3418284032
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	217
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1364787200
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3796049920
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3330097152
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1174888448
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2833350656
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	923508736
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	55
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	64
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1286488064
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	40
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1729224704
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	741081088
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	254
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3163955200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	33
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	146
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	185
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1428729856
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3472
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.444082022
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	562305
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	240.617706
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	60817

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	39635	39635	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	6154	6154	✔
CONSANGLECPK_HwDeg_M_f32	-705.270996	-705.270996 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	6154	6154	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1730220032	1730220032	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	11364	11364	✔
CityParkInputConsistentCount_Cnt_M_u16	19909	19909	✔
CityParkInputInvalidCount_Cnt_M_u16	12682	12682	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3251510528	3251510528	✔
EffacDefaultDiagTimer_mS_M_u32[1]	7	7	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3251510528	3251510528	✔
ElecIntTimer_mS_M_u32[1]	1000	1000	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	37951	37951	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	827645952	827645952	✔
IgnTimeOff_Sec_M_u32	843727999	843727999	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	158	158	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3418284032	3418284032	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	217	217	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1364787200	1364787200	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	251	251	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3796049920	3796049920	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	77	77	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3330097152	3330097152	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3116376064	3116376064	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	158	158	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2833350656	2833350656	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	46	46	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	923508736	923508736	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	198	198	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1286488064	1286488064	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	34	34	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1729224704	1729224704	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	60	60	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	741081088	741081088	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	254	254	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3163955200	3163955200	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1428729856	1428729856	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	465.456207	465.456207	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	329.450714	329.450714	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	235.1436	235.1436	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	6154	6154	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	843727999	843727999	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-705.270996	-705.270996 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	58.1882019	58.1882019	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.343 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1676710656
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	25385
AASNodeAbsentTimer_mS_M_u32	1718240000
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	36783
ANGLEVOLANTSigValidCount_Cnt_M_u16	25296
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	60778
AngleVolantMsgTimer_mS_M_u32	1676710656
AngleVolantValidCount_Cnt_M_u16	23257
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2372207360
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	249922304
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1579660032
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1048408832
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	22434
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2595894016
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	27500
CAVNodeAbsentTimer_mS_M_u32	12935936
CDD_SrlComVehSpd_Kph_G_f32	503.290314
CMM388NTCEnableTimer_mS_M_u32	1514578688
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2928894720
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	26232
CMMNodeAbsentTimer_mS_M_u32	1227846400
CONSANGLECPKSigInvalidCount_Cnt_M_u16	28518
CONSANGLECPKSigValidCount_Cnt_M_u16	49687
CONSANGLECPK_Cnt_M_u16	5758
CONSANGLECPK_HwDeg_M_f32	563.643188
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	5758
CPKVehicleSpeedMsgTimer_mS_M_u32	645632768
CPKVehicleSpeedValidCount_Cnt_M_u16	20120
CityParkInputConsistentCount_Cnt_M_u16	19725
CityParkInputInvalidCount_Cnt_M_u16	48835

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	3418284032
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3852354304
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	8520
ComputerRazGCTSigInvalidTimer_mS_M_u32	3852460800
ComputerRazGCTSigValidCount_Cnt_M_u16	37222
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	22671
DMDFCTCPKSigValidCount_Cnt_M_u16	38201
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	35785
DMDRELAXECPKSigValidCount_Cnt_M_u16	7786
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	18087
DateInvalidTimer_mS_M_u32	249922304
DiagMuxOnAbsentTimer_mS_M_u32	1686983424
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1048408832
ESPNTCEnableTimer_mS_M_u32	2661237504
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	22853
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	9
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	10
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3165926144
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	61266
EtatMTSigValidCount_Cnt_M_u16	23888
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	14720
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	52145
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	17671
ISDAT4V2BSI552MsgTimer_mS_M_u32	2271441664
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	49719
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	11292
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	23888
ISDATBSI3F2MsgTimer_mS_M_u32	2457031424
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	63435
ISDATBSI412MsgLenValidCount_Cnt_M_u16	9632
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	61266
ISDATBSI412MsgTimer_mS_M_u32	1339462400
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	41900
ISDATBSI432MsgLenValidCount_Cnt_M_u16	54649
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	50497
ISDATDIRASentFltAcc_Cnt_M_u16	10437
ISDATDIRASentTimer_mS_M_u32	645632768
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	1252
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	23257
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	59394
ISDYN2CMMMsgTimer_mS_M_u32	2144420608
ISDYNAASChkSumInvalidCount_Cnt_M_u16	56131
ISDYNAASChkSumValidCount_Cnt_M_u16	40452
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	43084
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	12563
ISDYNAASMsgLenValidCount_Cnt_M_u16	34220
ISDYNAASMsgTimeValidCount_Cnt_M_u16	56131
ISDYNAASMsgTimer_mS_M_u32	4245857024
ISDYNABRChkSumInvalidCount_Cnt_M_u16	53948
ISDYNABRChkSumValidCount_Cnt_M_u16	61381
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	56630
ISDYNABRMsgCountValidCount_Cnt_M_u16	16439
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	53337
ISDYNABRMsgLenValidCount_Cnt_M_u16	842
ISDYNABRMsgTimeValidCount_Cnt_M_u16	5758
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	28118
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	28580

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	23888
ISDYNCMM208MsgTimer_mS_M_u32	4076733184
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	28118
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	28580
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	31167
ISDYNCMM388MsgTimer_mS_M_u32	3320587008
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	46412
ISDYNVOLChkSumValidCount_Cnt_M_u16	51325
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	15733
ISDYNVOLMsgCountValidCount_Cnt_M_u16	31391
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	12882
ISDYNVOLMsgLenValidCount_Cnt_M_u16	30052
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	26232
ISDYNVOLMsgTimer_mS_M_u32	611050240
IgnOnTimer_mS_M_u32	455090944
IgnTimeOff_Sec_M_u32	2251125546
ManVehSpd_Kph_M_f32	389.417206
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	108
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1168200448
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	233
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4034573056
PrevISDATBSI412MsgDLCError_Cnt_M_u08	0
PrevISDATBSI412MsgRxTime_MSec_M_u32	2153407232
PrevISDATBSI432MsgDLCError_Cnt_M_u08	54
PrevISDATBSI432MsgRxTime_MSec_M_u32	2416132864
PrevISDATDIRAMsgTxTime_MSec_M_u32	1054761728
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	56
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3744527104
PrevISDYNAASMsgDLCError_Cnt_M_u08	178
PrevISDYNAASMsgRxTime_MSec_M_u32	4208059136
PrevISDYNABRMsgDLCError_Cnt_M_u08	210
PrevISDYNABRMsgRxTime_MSec_M_u32	3484951296
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	130
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3958039296
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	189
PrevISDYNCMM388MsgRxTime_MSec_M_u32	90850048
PrevISDYNVOLMsgDLCError_Cnt_M_u08	2
PrevISDYNVOLMsgRxTime_MSec_M_u32	1529570048
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2864485120
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	316.576599
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	54265
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	43282
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	49286
VitesseVehicleBVRampValidCount_Cnt_M_u16	54623
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	19388
VitesseVehicleBVSigValidCount_Cnt_M_u16	65181
VitesseVehicleBV_Kph_M_f32	393.859406

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	31167
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	36536
VitesseVehiculeRoues_Kph_M_f32	403.73291
k_AASNTCEnableTimeout_mS_u16	42057
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	58648
k_AASNodeTimeout_mS_u16	51218
k_ABSNodeTimeout_mS_u16	54504
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	32811
k_ANGLEVOLANTSigValidThresh_Cnt_u16	25400
k_AngleVolantInvalidThresh_Cnt_u16	11155
k_AngleVolantValidThresh_Cnt_u16	48835
k_BSI552MsgTimeout_mS_u16	59091
k_BSINTCEnableTimeout_mS_u16	34884
k_BSINodeAbsentDiag_Cnt_str.Threshold	9598
k_BSINodeAbsentDiag_Cnt_str.PStep	32364
k_BSINodeAbsentDiag_Cnt_str.NStep	63134
k_BSINodeAbsentTimeout_mS_u16	27650
k_BSINodeTimeout_mS_u16	50497
k_BattOvHi_Volt_f32	18.6580009
k_BattOvLo_Volt_f32	3.54279995
k_BattUvHi_Volt_f32	16.3022003
k_BattUvLo_Volt_f32	6.65630007
k_CAVNTCEnableTimeout_mS_u16	5697
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	1362
k_CAVNodeTimeout_mS_u16	27186
k_CMM388MsgTimeout_mS_u16	49705
k_CMM388NTCEnableTimeout_mS_u16	501
k_CMMNTCEnableTimeout_mS_u16	45775
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	7300
k_CONSANGLECPKMax_HwDeg_f32	431.7341
k_CONSANGLECPKMin_HwDeg_f32	-636.550598
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	22719
k_CONSANGLECPKSigValidThresh_Cnt_u16	44472
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	28384
k_CPKVehicleSpeedValidThresh_Cnt_u16	7730
k_CityParkInputInvalidThresh_Cnt_u16	57354
k_CityParkInputValidThresh_Cnt_u16	19725
k_ComputerRazGCTSigValidThresh_Cnt_u16	49637
k_CptTemporelSigValidThresh_Cnt_u16	12874
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	12121
k_DMDFCTCPKSigValidThresh_Cnt_u16	41546
k_DMDFCTCPKValidCount_Cnt_u16	34826
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	59394
k_DMDRELAXECPKSigValidThresh_Cnt_u16	58604
k_DMDRelaxeConsistentThresh_Cnt_u16	23994
k_DateValidThresh_Cnt_u16	17671
k_DefaultVehSpd_Kph_f32	81.8054962
k_DiagMuxOnAbsentTimeout_mS_u16	64892
k_EMNodeTimeout_mS_u16	21383
k_ESPNTCEnableTimeout_mS_u16	53304
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	24556
k_EtatMTSigInvalidThresh_Cnt_u16	631
k_EtatMTSigValidThresh_Cnt_u16	1472
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	19623
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	10500
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	37786
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	34328
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	50877
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	13055
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	12045
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	55194

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	8416
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	24210
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	15111
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	42194
k_ISDATDIRASentDiag_Cnt_str.Threshold	3858
k_ISDATDIRASentDiag_Cnt_str.PStep	45405
k_ISDATDIRASentDiag_Cnt_str.NStep	21916
k_ISDATDIRASentTimeout_mS_u16	41864
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	53099
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	60778
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	8148
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	45500
k_ISDYNAASChkSumValidThresh_Cnt_u16	3781
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	15414
k_ISDYNAASMsgCountValidThresh_Cnt_u16	57143
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	8432
k_ISDYNAASMsgLenValidThresh_Cnt_u16	29254
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	7328
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	32063
k_ISDYNABRChkSumValidThresh_Cnt_u16	45232
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	46754
k_ISDYNABRMsgCountValidThresh_Cnt_u16	59907
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	34168
k_ISDYNABRMsgLenValidThresh_Cnt_u16	47173
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	50590
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	40493
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	32920
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	45869
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	61103
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	464
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	4443
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	42698
k_ISDYNVOLChkSumValidThresh_Cnt_u16	26079
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	48774
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	15609
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	23838
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	52252
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	36613
k_IgnOnTimeout_mS_u16	64406
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	138.579407
k_PowerCutVehSpdLowThresh_Kph_f32	132.681
k_PowerCutVehSpdLowTimeout_mS_u16	33733
k_VBattMaxAAS_Volt_f32	5.6711998
k_VBattMaxBSI_Volt_f32	15.9933996
k_VBattMaxCAV_Volt_f32	19.1320992
k_VBattMaxCMM388_Volt_f32	25.5508003
k_VBattMaxCMM_Volt_f32	28.7082996
k_VBattMaxESP_Volt_f32	21.4715996
k_VBattMinAAS_Volt_f32	25.0359993
k_VBattMinBSI_Volt_f32	21.4715996
k_VBattMinCAV_Volt_f32	26.8246994
k_VBattMinCMM388_Volt_f32	5.41179991
k_VBattMinCMM_Volt_f32	28.5035
k_VBattMinESP_Volt_f32	28.7082996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	44957
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	8866
k_VitesseVehicleBVRampValidThresh_Cnt_u16	7285
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	26493
k_VitesseVehicleBVSigValidThresh_Cnt_u16	44594
k_VitesseVehicleBVSpeedPassThresh_kph_f32	69.9364014
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	19052
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	8133
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	249922304
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	189

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	12.8652
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2339320576
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	192
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.464209288
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1944199936
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1939063552
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	52
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2438292224
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	175
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4112974592
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3339232000
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	788153088
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1425793792
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	46
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	48
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	68
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	137
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	161
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	188
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1720976128
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	93
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	167
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	187
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2917737216
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4011508480
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	56
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	240935680
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	37
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	85
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	130
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	156
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	174
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2196026112
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3166
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.941083491
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	998804
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	146.267105
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	64427

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	5758	5758	✔
CONSANGLECPK_HwDeg_M_f32	563.643188	563.643188 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2006148864	2006148864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	8	8	✔
EffacDefaultDiagTimer_mS_M_u32[1]	9	9	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	2006148864	2006148864	✔
ElecIntTimer_mS_M_u32[1]	10	10	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	3858	3858	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	455090944	455090944	✔
IgnTimeOff_Sec_M_u32	2251125546	2251125546	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1944199936	1944199936	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	106	106	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1939063552	1939063552	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	52	52	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2438292224	2438292224	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	175	175	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4112974592	4112974592	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1054761728	1054761728	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	93	93	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	788153088	788153088	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	223	223	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1425793792	1425793792	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1720976128	1720976128	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	172	172	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2917737216	2917737216	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	77	77	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4011508480	4011508480	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	56	56	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	240935680	240935680	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2196026112	2196026112	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	316.576599	316.576599	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	393.859406	393.859406	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	403.73291	403.73291	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	5758	5758	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2251125546	2251125546	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	563.643188	563.643188 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	81.8054962	81.8054962	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.344 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3319335424
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	18991
AASNodeAbsentTimer_mS_M_u32	19659264
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	65180
ANGLEVOLANTSigValidCount_Cnt_M_u16	50680
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	61292
AngleVolantMsgTimer_mS_M_u32	3319335424
AngleVolantValidCount_Cnt_M_u16	28061
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3879451136
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	79313408
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	464759296
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	28469760
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	12995
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3489409536
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	42470
CAVNodeAbsentTimer_mS_M_u32	110795264
CDD_SrlComVehSpd_Kph_G_f32	323.053406
CMM388NTCEnableTimer_mS_M_u32	2400639488
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3039861248
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	45696
CMMNodeAbsentTimer_mS_M_u32	698116608
CONSANGLECPKSigInvalidCount_Cnt_M_u16	43639
CONSANGLECPKSigValidCount_Cnt_M_u16	13092
CONSANGLECPK_Cnt_M_u16	37359
CONSANGLECPK_HwDeg_M_f32	-238.193405
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37359
CPKVehicleSpeedMsgTimer_mS_M_u32	1782057472
CPKVehicleSpeedValidCount_Cnt_M_u16	10794
CityParkInputConsistentCount_Cnt_M_u16	26369

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	47838
CityParkInputMsgTimer_mS_M_u32	1944199936
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1401944576
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	6547
ComputerRazGCTSigInvalidTimer_mS_M_u32	0
ComputerRazGCTSigValidCount_Cnt_M_u16	15862
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	7546
DMDFCTCPKSigValidCount_Cnt_M_u16	51263
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	62030
DMDRELAXECPKSigValidCount_Cnt_M_u16	31530
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	26804
DateInvalidTimer_mS_M_u32	79313408
DiagMuxOnAbsentTimer_mS_M_u32	654494208
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	28469760
ESPNTCEnableTimer_mS_M_u32	1821178368
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	51929
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	11
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	6
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3524143616
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	20722
EtatMTSigValidCount_Cnt_M_u16	47034
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	13353
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	65110
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	28885
ISDAT4V2BSI552MsgTimer_mS_M_u32	1056991744
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	963
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	5843
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	47034
ISDATBSI3F2MsgTimer_mS_M_u32	3041970688
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	49161
ISDATBSI412MsgLenValidCount_Cnt_M_u16	18250
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	20722
ISDATBSI412MsgTimer_mS_M_u32	438766080
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	51940
ISDATBSI432MsgLenValidCount_Cnt_M_u16	9789
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	11367
ISDATDIRASentFltAcc_Cnt_M_u16	4571
ISDATDIRASentTimer_mS_M_u32	1782057472
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	57021
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	28061
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	64289
ISDYN2CMMMsgTimer_mS_M_u32	284621312
ISDYNAASChkSumInvalidCount_Cnt_M_u16	51681
ISDYNAASChkSumValidCount_Cnt_M_u16	16989
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	4420
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	45297
ISDYNAASMsgLenValidCount_Cnt_M_u16	54245
ISDYNAASMsgTimeValidCount_Cnt_M_u16	51681
ISDYNAASMsgTimer_mS_M_u32	3602045440
ISDYNABRChkSumInvalidCount_Cnt_M_u16	245
ISDYNABRChkSumValidCount_Cnt_M_u16	35481
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	20488
ISDYNABRMsgCountValidCount_Cnt_M_u16	59332
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	5022
ISDYNABRMsgLenValidCount_Cnt_M_u16	64395
ISDYNABRMsgTimeValidCount_Cnt_M_u16	37359
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	8855

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	20972
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	47034
ISDYNCMM208MsgTimer_mS_M_u32	1517337088
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	8855
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	20972
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	10475
ISDYNCMM388MsgTimer_mS_M_u32	3257293312
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	61637
ISDYNVOLChkSumValidCount_Cnt_M_u16	14322
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	34504
ISDYNVOLMsgCountValidCount_Cnt_M_u16	12301
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	46002
ISDYNVOLMsgLenValidCount_Cnt_M_u16	60222
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	45696
ISDYNVOLMsgTimer_mS_M_u32	1437014528
IgnOnTimer_mS_M_u32	2458540544
IgnTimeOff_Sec_M_u32	1012470637
ManVehSpd_Kph_M_f32	466.617096
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	109
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3553020416
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	2
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1891281408
PrevISDATBSI412MsgDLCError_Cnt_M_u08	105
PrevISDATBSI412MsgRxTime_MSec_M_u32	467376640
PrevISDATBSI432MsgDLCError_Cnt_M_u08	180
PrevISDATBSI432MsgRxTime_MSec_M_u32	677444096
PrevISDATDIRAMsgTxTime_MSec_M_u32	4031748608
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	128
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1301801472
PrevISDYNAASMsgDLCError_Cnt_M_u08	67
PrevISDYNAASMsgRxTime_MSec_M_u32	3933542912
PrevISDYNABRMsgDLCError_Cnt_M_u08	180
PrevISDYNABRMsgRxTime_MSec_M_u32	3569506816
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	196
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3140098560
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	97
PrevISDYNCMM388MsgRxTime_MSec_M_u32	606861824
PrevISDYNVOLMsgDLCError_Cnt_M_u08	189
PrevISDYNVOLMsgRxTime_MSec_M_u32	258513408
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	561318400
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	437.088593
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57407
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	33203
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	36504
VitesseVehicleBVRampValidCount_Cnt_M_u16	28876
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	15989
VitesseVehicleBVSigValidCount_Cnt_M_u16	26257

Name	Input Value
VitesseVehicleBV_Kph_M_f32	541.101379
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	10475
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	35520
VitesseVehiculeRoues_Kph_M_f32	17.9440994
k_AASNTCEnableTimeout_mS_u16	54414
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	35552
k_AASNodeTimeout_mS_u16	9395
k_ABSNodeTimeout_mS_u16	19567
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	61799
k_ANGLEVOLANTSigValidThresh_Cnt_u16	14592
k_AngleVolantInvalidThresh_Cnt_u16	3055
k_AngleVolantValidThresh_Cnt_u16	47838
k_BSI552MsgTimeout_mS_u16	44655
k_BSINTCEnableTimeout_mS_u16	32028
k_BSINodeAbsentDiag_Cnt_str.Threshold	38174
k_BSINodeAbsentDiag_Cnt_str.PStep	17812
k_BSINodeAbsentDiag_Cnt_str.NStep	43071
k_BSINodeAbsentTimeout_mS_u16	54180
k_BSINodeTimeout_mS_u16	11367
k_BattOvHi_Volt_f32	29.5820007
k_BattOvLo_Volt_f32	27.9230003
k_BattUvHi_Volt_f32	14.1150999
k_BattUvLo_Volt_f32	4.55420017
k_CAVNTCEnableTimeout_mS_u16	11364
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	61492
k_CAVNodeTimeout_mS_u16	59923
k_CMM388MsgTimeout_mS_u16	11567
k_CMM388NTCEnableTimeout_mS_u16	40395
k_CMMNTCEnableTimeout_mS_u16	37371
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	4444
k_CONSANGLECPKMax_HwDeg_f32	753.906921
k_CONSANGLECPKMin_HwDeg_f32	-135.201004
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	35819
k_CONSANGLECPKSigValidThresh_Cnt_u16	11712
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	59465
k_CPKVehicleSpeedValidThresh_Cnt_u16	43220
k_CityParkInputInvalidThresh_Cnt_u16	37131
k_CityParkInputValidThresh_Cnt_u16	26369
k_ComputerRazGCTSigValidThresh_Cnt_u16	15545
k_CptTemporelSigValidThresh_Cnt_u16	15433
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	63134
k_DMDFCTCPKSigValidThresh_Cnt_u16	7819
k_DMDFCTCPKValidCount_Cnt_u16	16779
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	64289
k_DMDRELAXECPKSigValidThresh_Cnt_u16	25894
k_DMDRelaxeConsistentThresh_Cnt_u16	45756
k_DateValidThresh_Cnt_u16	28885
k_DefaultVehSpd_Kph_f32	250.750595
k_DiagMuxOnAbsentTimeout_mS_u16	21749
k_EMNodeTimeout_mS_u16	49684
k_ESPNTCEnableTimeout_mS_u16	42882
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	59172
k_EtatMTSigInvalidThresh_Cnt_u16	7620
k_EtatMTSigValidThresh_Cnt_u16	62632
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	10996
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	50845
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	1882
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	31776
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	2800
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	56941
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	60609

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	58330
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	9032
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	2483
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	1299
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	58867
k_ISDATDIRASentDiag_Cnt_str.Threshold	12438
k_ISDATDIRASentDiag_Cnt_str.PStep	4214
k_ISDATDIRASentDiag_Cnt_str.NStep	47738
k_ISDATDIRASentTimeout_mS_u16	48785
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	2600
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	61292
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10414
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	25589
k_ISDYNAASChkSumValidThresh_Cnt_u16	11673
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	13064
k_ISDYNAASMsgCountValidThresh_Cnt_u16	2756
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	58969
k_ISDYNAASMsgLenValidThresh_Cnt_u16	62999
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	44232
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	9452
k_ISDYNABRChkSumValidThresh_Cnt_u16	2905
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	5571
k_ISDYNABRMsgCountValidThresh_Cnt_u16	48223
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	21888
k_ISDYNABRMsgLenValidThresh_Cnt_u16	44505
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	21902
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	20899
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	39330
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	36706
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	57756
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	59640
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	8982
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	28428
k_ISDYNVOLChkSumValidThresh_Cnt_u16	17037
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	57110
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	29437
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	14222
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	39766
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	2779
k_IgnOnTimeout_mS_u16	41128
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	144.928894
k_PowerCutVehSpdLowThresh_Kph_f32	138.624207
k_PowerCutVehSpdLowTimeout_mS_u16	9754
k_VBattMaxAAS_Volt_f32	26.5781994
k_VBattMaxBSI_Volt_f32	18.8794003
k_VBattMaxCAV_Volt_f32	2.40560007
k_VBattMaxCMM388_Volt_f32	2.29209995
k_VBattMaxCMM_Volt_f32	12.2521
k_VBattMaxESP_Volt_f32	8.92199993
k_VBattMinAAS_Volt_f32	22.2056999
k_VBattMinBSI_Volt_f32	8.92199993
k_VBattMinCAV_Volt_f32	26.8617001
k_VBattMinCMM388_Volt_f32	23.6182995
k_VBattMinCMM_Volt_f32	25.3383007
k_VBattMinESP_Volt_f32	12.2521
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	45458
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	10563
k_VitesseVehicleBVRampValidThresh_Cnt_u16	59848
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	23282
k_VitesseVehicleBVSigValidThresh_Cnt_u16	6034
k_VitesseVehicleBVSpeedPassThresh_kph_f32	498.235596
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	2278
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	43418
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	79313408
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	97
target_SrlComInput_Per1_Batt_Volt_f32.value	12.3002996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	299706880
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	98
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.155861214
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	272914944
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1605335552
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2498402816
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	24
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	938850816
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3503348224
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3883661824
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	66525696
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	209
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3618552320
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	59
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	77
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	210
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	219
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	233
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1043290624
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	255
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3373955584
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4191525376
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	71
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3783043584
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3410
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.655275106
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	73684
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	14.1155996

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	45353		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	61292	61292	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	37359	37359	✔
CONSANGLECPK_HwDeg_M_f32	-238.193405	-238.193405 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37359	37359	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1782057472	1782057472	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	10794	10794	✔
CityParkInputConsistentCount_Cnt_M_u16	26369	26369	✔
CityParkInputInvalidCount_Cnt_M_u16	47838	47838	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	11	11	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4	4	✔
ElecIntTimer_mS_M_u32[1]	6	6	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	12438	12438	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	2006148864	2006148864	✔
IgnTimeOff_Sec_M_u32	1012470637	1012470637	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	92	92	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	272914944	272914944	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1605335552	1605335552	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	221	221	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2498402816	2498402816	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	24	24	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	938850816	938850816	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4031748608	4031748608	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3883661824	3883661824	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	66525696	66525696	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	64	64	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3618552320	3618552320	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	180	180	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1043290624	1043290624	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	255	255	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3373955584	3373955584	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	172	172	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4191525376	4191525376	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3783043584	3783043584	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	437.088593	437.088593	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	541.101379	541.101379	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	17.9440994	17.9440994	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	37359	37359	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1012470637	1012470637	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-238.193405	-238.193405 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.345 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4206601472
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	59320
AASNodeAbsentTimer_mS_M_u32	2156057856
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	7282
ANGLEVOLANTSigValidCount_Cnt_M_u16	1053
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	11265
AngleVolantMsgTimer_mS_M_u32	4206601472
AngleVolantValidCount_Cnt_M_u16	24045
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3176371456
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2128090368
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	732677376
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3836708096
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	56317
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3503441152
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	30484
CAVNodeAbsentTimer_mS_M_u32	4072076544
CDD_SrlComVehSpd_Kph_G_f32	180.7845
CMM388NTCEnableTimer_mS_M_u32	2588030208
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3203724544
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	22532
CMMNodeAbsentTimer_mS_M_u32	2498856192
CONSANGLECPKSigInvalidCount_Cnt_M_u16	14303
CONSANGLECPKSigValidCount_Cnt_M_u16	7066
CONSANGLECPK_Cnt_M_u16	60217
CONSANGLECPK_HwDeg_M_f32	-310.713715
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	60217
CPKVehicleSpeedMsgTimer_mS_M_u32	1235133696
CPKVehicleSpeedValidCount_Cnt_M_u16	33006
CityParkInputConsistentCount_Cnt_M_u16	449
CityParkInputInvalidCount_Cnt_M_u16	2858
CityParkInputMsgTimer_mS_M_u32	272914944
CityParkInputValidCount_Cnt_M_u16	4

Name	Input Value
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	425121024
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	2444
ComputerRazGCTSigInvalidTimer_mS_M_u32	4294967295
ComputerRazGCTSigValidCount_Cnt_M_u16	37090
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	21334
DMDFCTCPKSigValidCount_Cnt_M_u16	12488
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	35164
DMDRELAXECPKSigValidCount_Cnt_M_u16	11399
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	12584
DateInvalidTimer_mS_M_u32	2128090368
DiagMuxOnAbsentTimer_mS_M_u32	2923324672
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3836708096
ESPNTCEnableTimer_mS_M_u32	39834880
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	15546
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	21
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1100
ElecIntTimer_mS_M_u32[1]	1152
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2459714816
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	53680
EtatMTSigValidCount_Cnt_M_u16	35607
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	58057
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	516
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	3846
ISDAT4V2BSI552MsgTimer_mS_M_u32	3838149888
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	14012
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	2891
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	35607
ISDATBSI3F2MsgTimer_mS_M_u32	3142870272
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	60137
ISDATBSI412MsgLenValidCount_Cnt_M_u16	8936
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	53680
ISDATBSI412MsgTimer_mS_M_u32	3050415360
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	40664
ISDATBSI432MsgLenValidCount_Cnt_M_u16	47758
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	10129
ISDATDIRASentFltAcc_Cnt_M_u16	18229
ISDATDIRASentTimer_mS_M_u32	1235133696
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	48335
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	24045
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	5729
ISDYN2CMMMsgTimer_mS_M_u32	1025627392
ISDYNAASChkSumInvalidCount_Cnt_M_u16	45218
ISDYNAASChkSumValidCount_Cnt_M_u16	1260
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	52984
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	16883
ISDYNAASMsgLenValidCount_Cnt_M_u16	30421
ISDYNAASMsgTimeValidCount_Cnt_M_u16	45218
ISDYNAASMsgTimer_mS_M_u32	862860544
ISDYNABRChkSumInvalidCount_Cnt_M_u16	45798
ISDYNABRChkSumValidCount_Cnt_M_u16	29625
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	31277
ISDYNABRMsgCountValidCount_Cnt_M_u16	28855
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	22634
ISDYNABRMsgLenValidCount_Cnt_M_u16	7781
ISDYNABRMsgTimeValidCount_Cnt_M_u16	60217
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	13616
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	2288
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	35607
ISDYNCMM208MsgTimer_mS_M_u32	2008323328

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	13616
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	2288
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	58371
ISDYNCMM388MsgTimer_mS_M_u32	2668868864
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	7413
ISDYNVOLChkSumValidCount_Cnt_M_u16	50480
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	53100
ISDYNVOLMsgCountValidCount_Cnt_M_u16	45406
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	9775
ISDYNVOLMsgLenValidCount_Cnt_M_u16	32074
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	22532
ISDYNVOLMsgTimer_mS_M_u32	3616634112
IgnOnTimer_mS_M_u32	3186078976
IgnTimeOff_Sec_M_u32	2745307168
ManVehSpd_Kph_M_f32	344.260498
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	110
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	122
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3086116096
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	218
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	144098560
PrevISDATBSI412MsgDLCError_Cnt_M_u08	162
PrevISDATBSI412MsgRxTime_MSec_M_u32	4143183104
PrevISDATBSI432MsgDLCError_Cnt_M_u08	253
PrevISDATBSI432MsgRxTime_MSec_M_u32	518247680
PrevISDATDIRAMsgTxTime_MSec_M_u32	1234695424
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	36
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1996424448
PrevISDYNAASMsgDLCError_Cnt_M_u08	67
PrevISDYNAASMsgRxTime_MSec_M_u32	3509024000
PrevISDYNABRMsgDLCError_Cnt_M_u08	126
PrevISDYNABRMsgRxTime_MSec_M_u32	3611276544
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	241
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1929934080
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	49
PrevISDYNCMM388MsgRxTime_MSec_M_u32	394450176
PrevISDYNVOLMsgDLCError_Cnt_M_u08	150
PrevISDYNVOLMsgRxTime_MSec_M_u32	2420962560
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1474798848
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	520.656982
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	27657
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	9579
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	1278
VitesseVehicleBVRampValidCount_Cnt_M_u16	64544
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	231
VitesseVehicleBVSigValidCount_Cnt_M_u16	50770
VitesseVehicleBV_Kph_M_f32	513.714111
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	58371
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	56390

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	282.096985
k_AASNTCEnableTimeout_mS_u16	24412
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	53796
k_AASNodeTimeout_mS_u16	15467
k_ABSNodeTimeout_mS_u16	55927
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	63311
k_ANGLEVOLANTSigValidThresh_Cnt_u16	20037
k_AngleVolantInvalidThresh_Cnt_u16	20856
k_AngleVolantValidThresh_Cnt_u16	2858
k_BSI552MsgTimeout_mS_u16	60729
k_BSINTCEnableTimeout_mS_u16	26672
k_BSINodeAbsentDiag_Cnt_str.Threshold	4379
k_BSINodeAbsentDiag_Cnt_str.PStep	52728
k_BSINodeAbsentDiag_Cnt_str.NStep	17464
k_BSINodeAbsentTimeout_mS_u16	24409
k_BSINodeTimeout_mS_u16	10129
k_BattOvHi_Volt_f32	16.3111
k_BattOvLo_Volt_f32	31.5
k_BattUvHi_Volt_f32	0.314300001
k_BattUvLo_Volt_f32	14.4927998
k_CAVNTCEnableTimeout_mS_u16	20120
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	20522
k_CAVNodeTimeout_mS_u16	59659
k_CMM388MsgTimeout_mS_u16	16056
k_CMM388NTCEnableTimeout_mS_u16	23780
k_CMMNTCEnableTimeout_mS_u16	27668
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	47218
k_CONSANGLECPKMax_HwDeg_f32	283.474091
k_CONSANGLECPKMin_HwDeg_f32	-371.316498
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	47875
k_CONSANGLECPKSigValidThresh_Cnt_u16	62278
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	51625
k_CPKVehicleSpeedValidThresh_Cnt_u16	7304
k_CityParkInputInvalidThresh_Cnt_u16	55972
k_CityParkInputValidThresh_Cnt_u16	449
k_ComputerRazGCTSigValidThresh_Cnt_u16	58330
k_CptTemporelSigValidThresh_Cnt_u16	62185
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	44906
k_DMDFCTCPKSigValidThresh_Cnt_u16	46437
k_DMDFCTCPKValidCount_Cnt_u16	53157
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	5729
k_DMDRELAXECPKSigValidThresh_Cnt_u16	46611
k_DMDRelaxeConsistentThresh_Cnt_u16	42321
k_DateValidThresh_Cnt_u16	3846
k_DefaultVehSpd_Kph_f32	96.524498
k_DiagMuxOnAbsentTimeout_mS_u16	14887
k_EMNodeTimeout_mS_u16	42248
k_ESPNTCEnableTimeout_mS_u16	57920
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	22298
k_EtatMTSigInvalidThresh_Cnt_u16	22649
k_EtatMTSigValidThresh_Cnt_u16	12684
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	28072
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	2159
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	50358
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	33189
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	58100
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	8125
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	60737
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	13751
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	9644
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	37869

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	61323
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	61994
k_ISDATDIRASentDiag_Cnt_str.Threshold	1559
k_ISDATDIRASentDiag_Cnt_str.PStep	4663
k_ISDATDIRASentDiag_Cnt_str.NStep	20460
k_ISDATDIRASentTimeout_mS_u16	59922
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	39307
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	11265
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	3772
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	35302
k_ISDYNAASChkSumValidThresh_Cnt_u16	35513
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	53549
k_ISDYNAASMsgCountValidThresh_Cnt_u16	1975
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	37562
k_ISDYNAASMsgLenValidThresh_Cnt_u16	22591
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	4845
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	56448
k_ISDYNABRChkSumValidThresh_Cnt_u16	42747
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	13053
k_ISDYNABRMsgCountValidThresh_Cnt_u16	31976
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	28420
k_ISDYNABRMsgLenValidThresh_Cnt_u16	37818
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	11611
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	42973
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	542
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	30814
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	29554
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	39709
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	45698
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	43488
k_ISDYNVOLChkSumValidThresh_Cnt_u16	64799
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	13315
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	19085
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	36316
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	20547
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	55540
k_IgnOnTimeout_mS_u16	34060
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	220.489807
k_PowerCutVehSpdLowThresh_Kph_f32	55.4039001
k_PowerCutVehSpdLowTimeout_mS_u16	39608
k_VBattMaxAAS_Volt_f32	24.7796001
k_VBattMaxBSI_Volt_f32	11.0733004
k_VBattMaxCAV_Volt_f32	15.6674995
k_VBattMaxCMM388_Volt_f32	24.5802002
k_VBattMaxCMM_Volt_f32	2.40240002
k_VBattMaxESP_Volt_f32	21.5126991
k_VBattMinAAS_Volt_f32	8.73209953
k_VBattMinBSI_Volt_f32	21.5126991
k_VBattMinCAV_Volt_f32	30.6965008
k_VBattMinCMM388_Volt_f32	11.8741999
k_VBattMinCMM_Volt_f32	24.7287006
k_VBattMinESP_Volt_f32	2.40240002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	52045
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	61948
k_VitesseVehicleBVRampValidThresh_Cnt_u16	42604
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	23600
k_VitesseVehicleBVSigValidThresh_Cnt_u16	29710
k_VitesseVehicleBVSpeedPassThresh_kph_f32	404.516693
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	19988
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	2486
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2128090368
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	63029
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	4103887872
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSe	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	49
target_SrlComInput_Per1_Batt_Volt_f32.value	6.57130003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3475981568
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	15
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.123830296
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2897851648
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	156
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3539490048
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2277963008
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	96
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	858100992
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1024734464
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	227726592
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	211907840
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	37
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	63
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	86
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	93
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	164
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	10
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2012910848
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	155
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	156
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2398663936
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	45569280
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	27
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3305501952
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	74
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	122
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	133
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1045480704
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	425
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.959398389
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	969501
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	168.179504
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	8523

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4103887872	4103887872	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4103887872	4103887872	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	4103887872	4103887872	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	4103887872	4103887872	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4103887872	4103887872	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4103887872	4103887872	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4103887872	4103887872	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	4103887872	4103887872	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4103887872	4103887872	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4103887872	4103887872	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4103887872	4103887872	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4103887872	4103887872	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4103887872	4103887872	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	60217	60217	✔
CONSANGLECPK_HwDeg_M_f32	-310.713715	-310.713715 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4103887872	4103887872	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	4103887872	4103887872	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4103887872	4103887872	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4103887872	4103887872	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4103887872	4103887872	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4103887872	4103887872	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4103887872	4103887872	✔
ESPNTCEnableTimer_mS_M_u32	4103887872	4103887872	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4103887872	4103887872	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔
EffacDefaultDiagTimer_mS_M_u32[1]	21	21	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	4103887872	4103887872	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	1152	1152	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4103887872	4103887872	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4103887872	4103887872	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4103887872	4103887872	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4103887872	4103887872	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4103887872	4103887872	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1559	1559	✔
ISDATDIRASentTimer_mS_M_u32	4103887872	4103887872	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4103887872	4103887872	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4103887872	4103887872	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4103887872	4103887872	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4103887872	4103887872	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4103887872	4103887872	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4103887872	4103887872	✔
IgnOnTimer_mS_M_u32	3186078976	3186078976	✔
IgnTimeOff_Sec_M_u32	2745307168	2745307168	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	118	118	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2897851648	2897851648	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	156	156	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3539490048	3539490048	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	29	29	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2277963008	2277963008	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	96	96	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	858100992	858100992	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1234695424	1234695424	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	206	206	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	227726592	227726592	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	200	200	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	211907840	211907840	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	10	10	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2012910848	2012910848	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2398663936	2398663936	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	45569280	45569280	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	27	27	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3305501952	3305501952	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1045480704	1045480704	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	520.656982	520.656982	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	513.714111	513.714111	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	282.096985	282.096985	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	60217	60217	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2745307168	2745307168	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-310.713715	-310.713715 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.346 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3158299648
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	34634
AASNodeAbsentTimer_mS_M_u32	2208973824
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	62234
ANGLEVOLANTSigValidCount_Cnt_M_u16	33498
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	7791
AngleVolantMsgTimer_mS_M_u32	3158299648
AngleVolantValidCount_Cnt_M_u16	33577
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3671040
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1839891456
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2448389120
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	635712512
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	41081
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1551627264
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	61877
CAVNodeAbsentTimer_mS_M_u32	2777539584
CDD_SrlComVehSpd_Kph_G_f32	318.319214
CMM388NTCEnableTimer_mS_M_u32	3958121472
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3100894208
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	15014
CMMNodeAbsentTimer_mS_M_u32	2636002304
CONSANGLECPKSigInvalidCount_Cnt_M_u16	17364
CONSANGLECPKSigValidCount_Cnt_M_u16	8036
CONSANGLECPK_Cnt_M_u16	60551
CONSANGLECPK_HwDeg_M_f32	218.875702
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	60551
CPKVehicleSpeedMsgTimer_mS_M_u32	462869504
CPKVehicleSpeedValidCount_Cnt_M_u16	45102
CityParkInputConsistentCount_Cnt_M_u16	59309
CityParkInputInvalidCount_Cnt_M_u16	48244

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	2897851648
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	154027008
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	29134
ComputerRazGCTSigInvalidTimer_mS_M_u32	457450240
ComputerRazGCTSigValidCount_Cnt_M_u16	65098
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	37872
DMDFCTCPKSigValidCount_Cnt_M_u16	25176
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	54364
DMDRELAXECPKSigValidCount_Cnt_M_u16	12700
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	48121
DateInvalidTimer_mS_M_u32	1839891456
DiagMuxOnAbsentTimer_mS_M_u32	481793024
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	635712512
ESPNTCEnableTimer_mS_M_u32	2987607040
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	834
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	22
EffacDefaultDiagTimer_mS_M_u32[1]	23
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2050
ElecIntTimer_mS_M_u32[1]	6072
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3206411264
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	52897
EtatMTSigValidCount_Cnt_M_u16	55597
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	27414
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	37926
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	16286
ISDAT4V2BSI552MsgTimer_mS_M_u32	4255265792
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	9981
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	32785
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	55597
ISDATBSI3F2MsgTimer_mS_M_u32	3447034880
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	20342
ISDATBSI412MsgLenValidCount_Cnt_M_u16	15929
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	52897
ISDATBSI412MsgTimer_mS_M_u32	1660802048
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	46634
ISDATBSI432MsgLenValidCount_Cnt_M_u16	55750
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	5182
ISDATDIRASentFltAcc_Cnt_M_u16	17746
ISDATDIRASentTimer_mS_M_u32	462869504
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	20421
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	33577
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	14031
ISDYN2CMMMsgTimer_mS_M_u32	2311930880
ISDYNAASChkSumInvalidCount_Cnt_M_u16	21644
ISDYNAASChkSumValidCount_Cnt_M_u16	7788
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	7176
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	52504
ISDYNAASMsgLenValidCount_Cnt_M_u16	21808
ISDYNAASMsgTimeValidCount_Cnt_M_u16	21644
ISDYNAASMsgTimer_mS_M_u32	3496485888
ISDYNABRChkSumInvalidCount_Cnt_M_u16	22335
ISDYNABRChkSumValidCount_Cnt_M_u16	64391
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	58347
ISDYNABRMsgCountValidCount_Cnt_M_u16	50955
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	52787
ISDYNABRMsgLenValidCount_Cnt_M_u16	771
ISDYNABRMsgTimeValidCount_Cnt_M_u16	60551
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	56017
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	14930

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	55597
ISDYNCMM208MsgTimer_mS_M_u32	2501182464
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	56017
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	14930
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	51431
ISDYNCMM388MsgTimer_mS_M_u32	58172416
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	27794
ISDYNVOLChkSumValidCount_Cnt_M_u16	64162
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	63406
ISDYNVOLMsgCountValidCount_Cnt_M_u16	47254
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	23267
ISDYNVOLMsgLenValidCount_Cnt_M_u16	23635
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	15014
ISDYNVOLMsgTimer_mS_M_u32	2164155392
IgnOnTimer_mS_M_u32	4143686656
IgnTimeOff_Sec_M_u32	1704543159
ManVehSpd_Kph_M_f32	14.4097996
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	111
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	57
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3483079680
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	91
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1731097600
PrevISDATBSI412MsgDLCError_Cnt_M_u08	11
PrevISDATBSI412MsgRxTime_MSec_M_u32	3436635136
PrevISDATBSI432MsgDLCError_Cnt_M_u08	66
PrevISDATBSI432MsgRxTime_MSec_M_u32	1820804096
PrevISDATDIRAMsgTxTime_MSec_M_u32	1693115392
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	48
PrevISDYN2CMMMsgRxTime_MSec_M_u32	217428992
PrevISDYNAASMsgDLCError_Cnt_M_u08	161
PrevISDYNAASMsgRxTime_MSec_M_u32	1815897088
PrevISDYNABRMsgDLCError_Cnt_M_u08	60
PrevISDYNABRMsgRxTime_MSec_M_u32	183739392
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	5
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1251566592
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	254
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3198829568
PrevISDYNVOLMsgDLCError_Cnt_M_u08	92
PrevISDYNVOLMsgRxTime_MSec_M_u32	2764825600
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1421595648
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	534.466919
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	9942
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	8558
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	28663
VitesseVehicleBVRampValidCount_Cnt_M_u16	45391
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	22971
VitesseVehicleBVSigValidCount_Cnt_M_u16	20539
VitesseVehicleBV_Kph_M_f32	296.348907

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	51431
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	34527
VitesseVehiculeRoues_Kph_M_f32	487.407898
k_AASNTCEnableTimeout_mS_u16	56350
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	49796
k_AASNodeTimeout_mS_u16	56430
k_ABSNodeTimeout_mS_u16	49805
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	18629
k_ANGLEVOLANTSigValidThresh_Cnt_u16	47777
k_AngleVolantInvalidThresh_Cnt_u16	15624
k_AngleVolantValidThresh_Cnt_u16	48244
k_BSI552MsgTimeout_mS_u16	57350
k_BSINTCEnableTimeout_mS_u16	47650
k_BSINodeAbsentDiag_Cnt_str.Threshold	44175
k_BSINodeAbsentDiag_Cnt_str.PStep	2874
k_BSINodeAbsentDiag_Cnt_str.NStep	52665
k_BSINodeAbsentTimeout_mS_u16	58471
k_BSINodeTimeout_mS_u16	5182
k_BattOvHi_Volt_f32	11.8388996
k_BattOvLo_Volt_f32	28.3290997
k_BattUvHi_Volt_f32	19.5216999
k_BattUvLo_Volt_f32	20.4995995
k_CAVNTCEnableTimeout_mS_u16	10794
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	15987
k_CAVNodeTimeout_mS_u16	57424
k_CMM388MsgTimeout_mS_u16	33354
k_CMM388NTCEnableTimeout_mS_u16	55238
k_CMMNTCEnableTimeout_mS_u16	59125
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	41563
k_CONSANGLECPKMax_HwDeg_f32	548.203125
k_CONSANGLECPKMin_HwDeg_f32	-1.08229995
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	17383
k_CONSANGLECPKSigValidThresh_Cnt_u16	16863
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	44212
k_CPKVehicleSpeedValidThresh_Cnt_u16	63129
k_CityParkInputInvalidThresh_Cnt_u16	22533
k_CityParkInputValidThresh_Cnt_u16	59309
k_ComputerRazGCTSigValidThresh_Cnt_u16	6051
k_CptTemporelSigValidThresh_Cnt_u16	49463
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	51507
k_DMDFCTCPKSigValidThresh_Cnt_u16	15875
k_DMDFCTCPKValidCount_Cnt_u16	25985
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	14031
k_DMDRELAXECPKSigValidThresh_Cnt_u16	48759
k_DMDRelaxeConsistentThresh_Cnt_u16	26813
k_DateValidThresh_Cnt_u16	16286
k_DefaultVehSpd_Kph_f32	125.374802
k_DiagMuxOnAbsentTimeout_mS_u16	14269
k_EMNodeTimeout_mS_u16	57433
k_ESPNTCEnableTimeout_mS_u16	24625
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	26211
k_EtatMTSigInvalidThresh_Cnt_u16	29318
k_EtatMTSigValidThresh_Cnt_u16	52750
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	31927
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	25379
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	45774
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	10818
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	56598
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	250
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	44783
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	19531

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	29102
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	49771
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	50767
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	52914
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	25019
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	40079
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	7791
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	51901
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	53823
k_ISDYNAASChkSumValidThresh_Cnt_u16	46727
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	57067
k_ISDYNAASMsgCountValidThresh_Cnt_u16	523
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	1987
k_ISDYNAASMsgLenValidThresh_Cnt_u16	55538
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	3241
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	6641
k_ISDYNABRChkSumValidThresh_Cnt_u16	16705
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	39801
k_ISDYNABRMsgCountValidThresh_Cnt_u16	1145
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	62886
k_ISDYNABRMsgLenValidThresh_Cnt_u16	65090
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	32544
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	50010
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7639
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	46229
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	60954
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	48602
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	9836
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	44689
k_ISDYNVOLChkSumValidThresh_Cnt_u16	19348
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	33127
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	50955
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	18973
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	14761
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	6612
k_IgnOnTimeout_mS_u16	52493
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	77.9787979
k_PowerCutVehSpdLowThresh_Kph_f32	101.236603
k_PowerCutVehSpdLowTimeout_mS_u16	39434
k_VBattMaxAAS_Volt_f32	26.8460007
k_VBattMaxBSI_Volt_f32	13.3731003
k_VBattMaxCAV_Volt_f32	2.07189989
k_VBattMaxCMM388_Volt_f32	15.6169004
k_VBattMaxCMM_Volt_f32	26.0438995
k_VBattMaxESP_Volt_f32	7.3526001
k_VBattMinAAS_Volt_f32	30.4834995
k_VBattMinBSI_Volt_f32	7.3526001
k_VBattMinCAV_Volt_f32	21.7924995
k_VBattMinCMM388_Volt_f32	31.9174995
k_VBattMinCMM_Volt_f32	5.31020021
k_VBattMinESP_Volt_f32	26.0438995
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	36681
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	29181
k_VitesseVehicleBVRampValidThresh_Cnt_u16	29358
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	13730
k_VitesseVehicleBVSigValidThresh_Cnt_u16	1222
k_VitesseVehicleBVSpeedPassThresh_kph_f32	24.6462994
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	27829
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	24717
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1839891456
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	16518
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1513729792
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	254

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	28.0296001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	358937600
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	188
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.299164057
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	139
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4068844544
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	188
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1112130560
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	643687424
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1723991040
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3413517312
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	477774848
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	36
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	567174144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	102
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	153
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	223
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	10
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	742589440
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	47
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	85
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	109
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	180
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	189
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	189
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	207
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	130589696
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1863107584
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	715187200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	107
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	122
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	202
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	771781632
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3347
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.364682227
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	42482
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	33.1596985
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	36624

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1513729792	1513729792	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1513729792	1513729792	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	7793	7793	✔
AngleVolantMsgTimer_mS_M_u32	1513729792	1513729792	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1513729792	1513729792	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1513729792	1513729792	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1513729792	1513729792	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1513729792	1513729792	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1513729792	1513729792	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1513729792	1513729792	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1513729792	1513729792	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1513729792	1513729792	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1513729792	1513729792	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1513729792	1513729792	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	60551	60551	✔
CONSANGLECPK_HwDeg_M_f32	218.875702	218.875702 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	60551	60551	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	462869504	462869504	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	45102	45102	✔
CityParkInputConsistentCount_Cnt_M_u16	59309	59309	✔
CityParkInputInvalidCount_Cnt_M_u16	48244	48244	✔
CityParkInputMsgTimer_mS_M_u32	1513729792	1513729792	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1513729792	1513729792	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1513729792	1513729792	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1513729792	1513729792	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1513729792	1513729792	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1513729792	1513729792	✔
ESPNTCEnableTimer_mS_M_u32	1513729792	1513729792	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1513729792	1513729792	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1513729792	1513729792	✔
EffacDefaultDiagTimer_mS_M_u32[1]	23	23	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	1513729792	1513729792	✔
ElecIntTimer_mS_M_u32[1]	6072	6072	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1513729792	1513729792	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1513729792	1513729792	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1513729792	1513729792	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1513729792	1513729792	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1513729792	1513729792	✔
ISDATDIRASentFltAcc_Cnt_M_u16	41895	41895	✔
ISDATDIRASentTimer_mS_M_u32	1513729792	1513729792	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1513729792	1513729792	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1513729792	1513729792	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1513729792	1513729792	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1513729792	1513729792	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1513729792	1513729792	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1513729792	1513729792	✔
IgnOnTimer_mS_M_u32	4143686656	4143686656	✔
IgnTimeOff_Sec_M_u32	1704543159	1704543159	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	139	139	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4068844544	4068844544	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	188	188	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1112130560	1112130560	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	29	29	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	643687424	643687424	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	118	118	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1723991040	1723991040	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1693115392	1693115392	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	49	49	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	477774848	477774848	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	36	36	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	567174144	567174144	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	10	10	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	742589440	742589440	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	29	29	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	130589696	130589696	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	5	5	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1863107584	1863107584	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	221	221	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	715187200	715187200	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	771781632	771781632	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	534.466919	534.466919	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	296.348907	296.348907	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	487.407898	487.407898	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	60551	60551	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1704543159	1704543159	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	218.875702	218.875702 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.347 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	120538880
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	61455
AASNodeAbsentTimer_mS_M_u32	2796549888
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	36510
ANGLEVOLANTSigValidCount_Cnt_M_u16	2846
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	65184
AngleVolantMsgTimer_mS_M_u32	120538880
AngleVolantValidCount_Cnt_M_u16	57586
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2550576896
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	967784192
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1285580544
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1405232896
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	49793
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3204114176
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	26444
CAVNodeAbsentTimer_mS_M_u32	3615823616
CDD_SrlComVehSpd_Kph_G_f32	568.424622
CMM388NTCEnableTimer_mS_M_u32	1298814720
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	900929280
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	51516
CMMNodeAbsentTimer_mS_M_u32	1444161280
CONSANGLECPKSigInvalidCount_Cnt_M_u16	45937
CONSANGLECPKSigValidCount_Cnt_M_u16	35969
CONSANGLECPK_Cnt_M_u16	28952
CONSANGLECPK_HwDeg_M_f32	328.209503
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	28952
CPKVehicleSpeedMsgTimer_mS_M_u32	86656768
CPKVehicleSpeedValidCount_Cnt_M_u16	47050
CityParkInputConsistentCount_Cnt_M_u16	50022

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	29200
CityParkInputMsgTimer_mS_M_u32	4068844544
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	639891200
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	16515
ComputerRazGCTSigInvalidTimer_mS_M_u32	145200896
ComputerRazGCTSigValidCount_Cnt_M_u16	0
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	56220
DMDFCTCPKSigValidCount_Cnt_M_u16	15396
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	29400
DMDRELAXECPKSigValidCount_Cnt_M_u16	34520
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	7938
DateInvalidTimer_mS_M_u32	967784192
DiagMuxOnAbsentTimer_mS_M_u32	1959266048
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1405232896
ESPNTCEnableTimer_mS_M_u32	4285855488
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	2856
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	28
EffacDefaultDiagTimer_mS_M_u32[1]	29
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	9900
ElecIntTimer_mS_M_u32[1]	11002
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2668947200
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	2634
EtatMTSigValidCount_Cnt_M_u16	18022
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	50603
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	46651
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	15442
ISDAT4V2BSI552MsgTimer_mS_M_u32	1149773568
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	27317
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	56121
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	18022
ISDATBSI3F2MsgTimer_mS_M_u32	3666740992
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	8780
ISDATBSI412MsgLenValidCount_Cnt_M_u16	37312
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	2634
ISDATBSI412MsgTimer_mS_M_u32	2331330304
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	26288
ISDATBSI432MsgLenValidCount_Cnt_M_u16	38812
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	25521
ISDATDIRASentFltAcc_Cnt_M_u16	8309
ISDATDIRASentTimer_mS_M_u32	86656768
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	48990
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	57586
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	12031
ISDYN2CMMMsgTimer_mS_M_u32	3762747136
ISDYNAASChkSumInvalidCount_Cnt_M_u16	4169
ISDYNAASChkSumValidCount_Cnt_M_u16	24169
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	21077
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	8483
ISDYNAASMsgLenValidCount_Cnt_M_u16	5276
ISDYNAASMsgTimeValidCount_Cnt_M_u16	4169
ISDYNAASMsgTimer_mS_M_u32	2415286016
ISDYNABRChkSumInvalidCount_Cnt_M_u16	60337
ISDYNABRChkSumValidCount_Cnt_M_u16	19097
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	40492
ISDYNABRMsgCountValidCount_Cnt_M_u16	41100
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	20564
ISDYNABRMsgLenValidCount_Cnt_M_u16	7588
ISDYNABRMsgTimeValidCount_Cnt_M_u16	28952
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	425

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	21223
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	18022
ISDYNCMM208MsgTimer_mS_M_u32	2372908800
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	425
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	21223
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	34744
ISDYNCMM388MsgTimer_mS_M_u32	2496124672
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	45367
ISDYNVOLChkSumValidCount_Cnt_M_u16	29383
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	10338
ISDYNVOLMsgCountValidCount_Cnt_M_u16	45418
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	51269
ISDYNVOLMsgLenValidCount_Cnt_M_u16	44981
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	51516
ISDYNVOLMsgTimer_mS_M_u32	2805176064
IgnOnTimer_mS_M_u32	3392919296
IgnTimeOff_Sec_M_u32	913651437
ManVehSpd_Kph_M_f32	264.257294
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	112
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	154
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3961259776
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	103
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2296604416
PrevISDATBSI412MsgDLCError_Cnt_M_u08	65
PrevISDATBSI412MsgRxTime_MSec_M_u32	3316258560
PrevISDATBSI432MsgDLCError_Cnt_M_u08	199
PrevISDATBSI432MsgRxTime_MSec_M_u32	2685990656
PrevISDATDIRAMsgTxTime_MSec_M_u32	1299060480
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	213
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3297617664
PrevISDYNAASMsgDLCError_Cnt_M_u08	26
PrevISDYNAASMsgRxTime_MSec_M_u32	1568249600
PrevISDYNABRMsgDLCError_Cnt_M_u08	97
PrevISDYNABRMsgRxTime_MSec_M_u32	1850988288
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	167
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1986172672
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	142
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4121949952
PrevISDYNVOLMsgDLCError_Cnt_M_u08	201
PrevISDYNVOLMsgRxTime_MSec_M_u32	1372264192
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	767248128
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	150.725998
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	35817
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	10210
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	29830
VitesseVehicleBVRampValidCount_Cnt_M_u16	15423
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	7867
VitesseVehicleBVSigValidCount_Cnt_M_u16	26363

Name	Input Value
VitesseVehicleBV_Kph_M_f32	329.23999
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	34744
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	22928
VitesseVehiculeRoues_Kph_M_f32	611.099609
k_AASNTCEnableTimeout_mS_u16	48723
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	20193
k_AASNodeTimeout_mS_u16	63202
k_ABSNodeTimeout_mS_u16	965
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	56031
k_ANGLEVOLANTSigValidThresh_Cnt_u16	8459
k_AngleVolantInvalidThresh_Cnt_u16	62934
k_AngleVolantValidThresh_Cnt_u16	29200
k_BSI552MsgTimeout_mS_u16	43547
k_BSINTCEnableTimeout_mS_u16	15048
k_BSINodeAbsentDiag_Cnt_str.Threshold	23536
k_BSINodeAbsentDiag_Cnt_str.PStep	32815
k_BSINodeAbsentDiag_Cnt_str.NStep	51441
k_BSINodeAbsentTimeout_mS_u16	36024
k_BSINodeTimeout_mS_u16	25521
k_BattOvHi_Volt_f32	17.9535999
k_BattOvLo_Volt_f32	2.6019001
k_BattUvHi_Volt_f32	18.3283005
k_BattUvLo_Volt_f32	14.8550997
k_CAVNTCEnableTimeout_mS_u16	33006
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	63762
k_CAVNodeTimeout_mS_u16	52733
k_CMM388MsgTimeout_mS_u16	65295
k_CMM388NTCEnableTimeout_mS_u16	61083
k_CMMNTCEnableTimeout_mS_u16	2765
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	63260
k_CONSANGLECPKMax_HwDeg_f32	606.661926
k_CONSANGLECPKMin_HwDeg_f32	-341.510193
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	5816
k_CONSANGLECPKSigValidThresh_Cnt_u16	10384
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	7696
k_CPKVehicleSpeedValidThresh_Cnt_u16	30947
k_CityParkInputInvalidThresh_Cnt_u16	33119
k_CityParkInputValidThresh_Cnt_u16	50022
k_ComputerRazGCTSigValidThresh_Cnt_u16	45251
k_CptTemporelSigValidThresh_Cnt_u16	12231
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	24404
k_DMDFCTCPKSigValidThresh_Cnt_u16	27812
k_DMDFCTCPKValidCount_Cnt_u16	37737
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	12031
k_DMDRELAXECPKSigValidThresh_Cnt_u16	25543
k_DMDRelaxeConsistentThresh_Cnt_u16	64757
k_DateValidThresh_Cnt_u16	15442
k_DefaultVehSpd_Kph_f32	236.308197
k_DiagMuxOnAbsentTimeout_mS_u16	59254
k_EMNodeTimeout_mS_u16	12770
k_ESPNTCEnableTimeout_mS_u16	3032
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	51972
k_EtatMTSigInvalidThresh_Cnt_u16	30172
k_EtatMTSigValidThresh_Cnt_u16	44804
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	31239
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	41603
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	9731
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	46310
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	6186
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	7616
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	53345

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	37901
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	17444
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	32620
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	12160
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	58775
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	48189
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	12288
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	65184
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	64564
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	31409
k_ISDYNAASChkSumValidThresh_Cnt_u16	6553
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	44332
k_ISDYNAASMsgCountValidThresh_Cnt_u16	61324
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	59941
k_ISDYNAASMsgLenValidThresh_Cnt_u16	4438
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	19187
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	58650
k_ISDYNABRChkSumValidThresh_Cnt_u16	56042
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	53633
k_ISDYNABRMsgCountValidThresh_Cnt_u16	49729
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	38972
k_ISDYNABRMsgLenValidThresh_Cnt_u16	6696
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	44620
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	50781
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	31529
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	51821
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	40350
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	23070
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	5160
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	12539
k_ISDYNVOLChkSumValidThresh_Cnt_u16	38319
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	25785
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	63501
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	34774
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	5362
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	1456
k_IgnOnTimeout_mS_u16	50567
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	172.996201
k_PowerCutVehSpdLowThresh_Kph_f32	239.222794
k_PowerCutVehSpdLowTimeout_mS_u16	13455
k_VBattMaxAAS_Volt_f32	20.3225994
k_VBattMaxBSI_Volt_f32	26.5167007
k_VBattMaxCAV_Volt_f32	19.9759007
k_VBattMaxCMM388_Volt_f32	23.4911003
k_VBattMaxCMM_Volt_f32	28.5293999
k_VBattMaxESP_Volt_f32	1.68439996
k_VBattMinAAS_Volt_f32	10.9245996
k_VBattMinBSI_Volt_f32	1.68439996
k_VBattMinCAV_Volt_f32	30.3911991
k_VBattMinCMM388_Volt_f32	7.04160023
k_VBattMinCMM_Volt_f32	17.9953995
k_VBattMinESP_Volt_f32	28.5293999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	49106
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	4983
k_VitesseVehicleBVRampValidThresh_Cnt_u16	46946
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	49607
k_VitesseVehicleBVSigValidThresh_Cnt_u16	4123
k_VitesseVehicleBVSpeedPassThresh_kph_f32	316.872192
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	63052
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	42629
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	967784192
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	58941
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	4201494016
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	142
target_SrlComInput_Per1_Batt_Volt_f32.value	4.84019995
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2017453824
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	71
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.637872458
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	207
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2141050624
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1221687040
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	140
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2501187328
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	24
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	208189184
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1456232192
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	473954048
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	89
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	79927040
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	123
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	214
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	160
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4293244672
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	7
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	30
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	56
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	239
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	231
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	198498048
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	71
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2391308032
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	22
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1414272768
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	197
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	204
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4235028224
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1077
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.141183481
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	591332
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	144.703506

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	47931		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	4201494016	4201494016	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4201494016	4201494016	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	4201494016	4201494016	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	4201494016	4201494016	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4201494016	4201494016	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4201494016	4201494016	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4201494016	4201494016	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	4201494016	4201494016	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	4201494016	4201494016	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4201494016	4201494016	✔
CDD_SrlComVehSpd_Kph_G_f32	264.257294	264.257294	✔
CMM388NTCEnableTimer_mS_M_u32	4201494016	4201494016	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4201494016	4201494016	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4201494016	4201494016	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	28952	28952	✔
CONSANGLECPK_HwDeg_M_f32	328.209503	328.209503 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4201494016	4201494016	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	4201494016	4201494016	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4201494016	4201494016	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4201494016	4201494016	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4201494016	4201494016	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4201494016	4201494016	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	4201494016	4201494016	✔
ESPNTCEnableTimer_mS_M_u32	4201494016	4201494016	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4201494016	4201494016	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	28	28	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	29	29	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	9900	9900	✔
ElecIntTimer_mS_M_u32[1]	11002	11002	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4201494016	4201494016	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	15442	15442	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4201494016	4201494016	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	18022	18022	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4201494016	4201494016	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	2634	2634	✔
ISDATBSI412MsgTimer_mS_M_u32	4201494016	4201494016	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	25521	25521	✔
ISDATBSI432MsgTimer_mS_M_u32	4201494016	4201494016	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11170	11170	✔
ISDATDIRASentTimer_mS_M_u32	4201494016	4201494016	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	12031	12031	✔
ISDYN2CMMMsgTimer_mS_M_u32	4201494016	4201494016	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	4169	4169	✔
ISDYNAASMsgTimer_mS_M_u32	4201494016	4201494016	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	28952	28952	✔
ISDYNABRMsgTimer_mS_M_u32	4201494016	4201494016	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	18022	18022	✔
ISDYNCMM208MsgTimer_mS_M_u32	4201494016	4201494016	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	34744	34744	✔
ISDYNCMM388MsgTimer_mS_M_u32	4201494016	4201494016	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	51516	51516	✔
ISDYNVOLMsgTimer_mS_M_u32	4201494016	4201494016	✔
IgnOnTimer_mS_M_u32	3392919296	3392919296	✔
IgnTimeOff_Sec_M_u32	913651437	913651437	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	207	207	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2141050624	2141050624	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	86	86	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1221687040	1221687040	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	140	140	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2501187328	2501187328	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	24	24	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	208189184	208189184	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1299060480	1299060480	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	215	215	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	473954048	473954048	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	89	89	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	79927040	79927040	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	160	160	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4293244672	4293244672	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	231	231	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	198498048	198498048	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	71	71	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2391308032	2391308032	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	22	22	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1414272768	1414272768	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4235028224	4235028224	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	150.725998	150.725998	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	329.23999	329.23999	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	611.099609	611.099609	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	28952	28952	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	913651437	913651437	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	328.209503	328.209503 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	264.257294	264.257294	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.348 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1743580672
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	53067
AASNodeAbsentTimer_mS_M_u32	2821381632
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	19871
ANGLEVOLANTSigValidCount_Cnt_M_u16	21727
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	10136
AngleVolantMsgTimer_mS_M_u32	1743580672
AngleVolantValidCount_Cnt_M_u16	20259
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2670108160
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	4230815232
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1142525440
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3853798912
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	65014
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1997147648
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	17940
CAVNodeAbsentTimer_mS_M_u32	1378582016
CDD_SrlComVehSpd_Kph_G_f32	414.318604
CMM388NTCEnableTimer_mS_M_u32	360431104
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1872854528
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	27141
CMMNodeAbsentTimer_mS_M_u32	2797489664
CONSANGLECPKSigInvalidCount_Cnt_M_u16	39463
CONSANGLECPKSigValidCount_Cnt_M_u16	52151
CONSANGLECPK_Cnt_M_u16	14834
CONSANGLECPK_HwDeg_M_f32	-508.6604
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	14834
CPKVehicleSpeedMsgTimer_mS_M_u32	435940864
CPKVehicleSpeedValidCount_Cnt_M_u16	20707
CityParkInputConsistentCount_Cnt_M_u16	30663
CityParkInputInvalidCount_Cnt_M_u16	58568
CityParkInputMsgTimer_mS_M_u32	2141050624
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4191084032
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	44527

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1757675008
ComputerRazGCTSigValidCount_Cnt_M_u16	65535
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	55332
DMDFCTCPKSigValidCount_Cnt_M_u16	21324
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	2289
DMDRELAXECPKSigValidCount_Cnt_M_u16	18865
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	56180
DateInvalidTimer_mS_M_u32	4230815232
DiagMuxOnAbsentTimer_mS_M_u32	1914875392
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3853798912
ESPNTCEnableTimer_mS_M_u32	4057718272
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	53505
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	200
EffacDefaultDiagTimer_mS_M_u32[1]	300
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6454
ElecIntTimer_mS_M_u32[1]	8259
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3199995392
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	45018
EtatMTSigValidCount_Cnt_M_u16	59462
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	52089
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	46729
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	35522
ISDAT4V2BSI552MsgTimer_mS_M_u32	2875346432
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	21018
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	36173
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	59462
ISDATBSI3F2MsgTimer_mS_M_u32	3637554688
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	38996
ISDATBSI412MsgLenValidCount_Cnt_M_u16	38584
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	45018
ISDATBSI412MsgTimer_mS_M_u32	1956310528
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	25001
ISDATBSI432MsgLenValidCount_Cnt_M_u16	64421
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	9445
ISDATDIRASentFltAcc_Cnt_M_u16	65177
ISDATDIRASentTimer_mS_M_u32	435940864
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	59168
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	20259
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	10747
ISDYN2CMMMsgTimer_mS_M_u32	392551936
ISDYNAASChkSumInvalidCount_Cnt_M_u16	54941
ISDYNAASChkSumValidCount_Cnt_M_u16	59644
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	18170
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	13455
ISDYNAASMsgLenValidCount_Cnt_M_u16	46822
ISDYNAASMsgTimeValidCount_Cnt_M_u16	54941
ISDYNAASMsgTimer_mS_M_u32	2111290880
ISDYNABRChkSumInvalidCount_Cnt_M_u16	39399
ISDYNABRChkSumValidCount_Cnt_M_u16	39406
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	30964
ISDYNABRMsgCountValidCount_Cnt_M_u16	28307
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	3966
ISDYNABRMsgLenValidCount_Cnt_M_u16	25678
ISDYNABRMsgTimeValidCount_Cnt_M_u16	14834
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	13805
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	62197
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	59462
ISDYNCMM208MsgTimer_mS_M_u32	2733350400
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	13805
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	62197
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	62161

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2506309120
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	14549
ISDYNVOLChkSumValidCount_Cnt_M_u16	45285
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	35282
ISDYNVOLMsgCountValidCount_Cnt_M_u16	35706
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	19882
ISDYNVOLMsgLenValidCount_Cnt_M_u16	54297
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	27141
ISDYNVOLMsgTimer_mS_M_u32	3172990464
IgnOnTimer_mS_M_u32	3305586176
IgnTimeOff_Sec_M_u32	2086262849
ManVehSpd_Kph_M_f32	380.126892
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	113
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	143
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1546038784
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	138
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1532005888
PrevISDATBSI412MsgDLCError_Cnt_M_u08	62
PrevISDATBSI412MsgRxTime_MSec_M_u32	1539079680
PrevISDATBSI432MsgDLCError_Cnt_M_u08	48
PrevISDATBSI432MsgRxTime_MSec_M_u32	2683297280
PrevISDATDIRAMsgTxTime_MSec_M_u32	3564142080
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	120
PrevISDYN2CMMMsgRxTime_MSec_M_u32	559009280
PrevISDYNAASMsgDLCError_Cnt_M_u08	223
PrevISDYNAASMsgRxTime_MSec_M_u32	843972096
PrevISDYNABRMsgDLCError_Cnt_M_u08	200
PrevISDYNABRMsgRxTime_MSec_M_u32	952057344
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	20
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3415408128
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	230
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3140148736
PrevISDYNVOLMsgDLCError_Cnt_M_u08	53
PrevISDYNVOLMsgRxTime_MSec_M_u32	2069462528
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	608759296
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	318.841003
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	35901
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	5396
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	34406
VitesseVehicleBVRampValidCount_Cnt_M_u16	35837
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	20808
VitesseVehicleBVSigValidCount_Cnt_M_u16	62792
VitesseVehicleBV_Kph_M_f32	78.1390991
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	62161
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	23048
VitesseVehiculeRoues_Kph_M_f32	605.490173
k_AASNTCEnableTimeout_mS_u16	65089
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	33110
k_AASNodeTimeout_mS_u16	43028
k_ABSNodeTimeout_mS_u16	17321
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	33052
k_ANGLEVOLANTSigValidThresh_Cnt_u16	56152
k_AngleVolantInvalidThresh_Cnt_u16	18679
k_AngleVolantValidThresh_Cnt_u16	58568
k_BSI552MsgTimeout_mS_u16	21607
k_BSINTCEnableTimeout_mS_u16	17761
k_BSINodeAbsentDiag_Cnt_str.Threshold	47257
k_BSINodeAbsentDiag_Cnt_str.PStep	35613
k_BSINodeAbsentDiag_Cnt_str.NStep	21
k_BSINodeAbsentTimeout_mS_u16	56656
k_BSINodeTimeout_mS_u16	9445
k_BattOvHi_Volt_f32	19.4836998
k_BattOvLo_Volt_f32	28.1828003
k_BattUvHi_Volt_f32	13.0909996
k_BattUvLo_Volt_f32	25.1294003
k_CAVNTCEnableTimeout_mS_u16	45102
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	10434
k_CAVNodeTimeout_mS_u16	31363
k_CMM388MsgTimeout_mS_u16	41547
k_CMM388NTCEnableTimeout_mS_u16	935
k_CMMNTCEnableTimeout_mS_u16	53714
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	45412
k_CONSANGLECPKMax_HwDeg_f32	167.535904
k_CONSANGLECPKMin_HwDeg_f32	-117.8629
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	17873
k_CONSANGLECPKSigValidThresh_Cnt_u16	60680
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	27274
k_CPKVehicleSpeedValidThresh_Cnt_u16	45199
k_CityParkInputInvalidThresh_Cnt_u16	4317
k_CityParkInputValidThresh_Cnt_u16	30663
k_ComputerRazGCTSigValidThresh_Cnt_u16	14320
k_CptTemporelSigValidThresh_Cnt_u16	18339
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	57982
k_DMDFCTCPKSigValidThresh_Cnt_u16	30542
k_DMDFCTCPKValidCount_Cnt_u16	11070
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	10747
k_DMDRELAXECPKSigValidThresh_Cnt_u16	10339
k_DMDRelaxeConsistentThresh_Cnt_u16	38105
k_DateValidThresh_Cnt_u16	35522
k_DefaultVehSpd_Kph_f32	63.0549011
k_DiagMuxOnAbsentTimeout_mS_u16	52952
k_EMNodeTimeout_mS_u16	8916
k_ESPNTCEnableTimeout_mS_u16	34928
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	54700
k_EtatMTSigInvalidThresh_Cnt_u16	26470
k_EtatMTSigValidThresh_Cnt_u16	55469
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	62117
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	58864
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	1008
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	30599
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	55930
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	30200
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	10390
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	2642
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	39245
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	24310
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	7033
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	35698
k_ISDATDIRASentDiag_Cnt_str.Threshold	1170

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	4955
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	22595
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	36919
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	10136
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10076
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	60647
k_ISDYNAASChkSumValidThresh_Cnt_u16	11502
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	19444
k_ISDYNAASMsgCountValidThresh_Cnt_u16	33171
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	28299
k_ISDYNAASMsgLenValidThresh_Cnt_u16	10424
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	64928
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	59692
k_ISDYNABRChkSumValidThresh_Cnt_u16	50300
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	53494
k_ISDYNABRMsgCountValidThresh_Cnt_u16	31606
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	64773
k_ISDYNABRMsgLenValidThresh_Cnt_u16	41985
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	41813
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	44257
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16829
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	6515
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	8351
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	26591
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	24192
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	59463
k_ISDYNVOLChkSumValidThresh_Cnt_u16	1771
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	18510
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	24978
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	26422
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	44194
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	9896
k_IgnOnTimeout_mS_u16	23203
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	101.490898
k_PowerCutVehSpdLowThresh_Kph_f32	6.81120014
k_PowerCutVehSpdLowTimeout_mS_u16	35725
k_VBattMaxAAS_Volt_f32	5.80310011
k_VBattMaxBSI_Volt_f32	23.8945999
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	21.8530998
k_VBattMaxCMM_Volt_f32	29.7803001
k_VBattMaxESP_Volt_f32	29.0720997
k_VBattMinAAS_Volt_f32	29.4531002
k_VBattMinBSI_Volt_f32	29.0720997
k_VBattMinCAV_Volt_f32	23.8726997
k_VBattMinCMM388_Volt_f32	6.8453002
k_VBattMinCMM_Volt_f32	15.5881996
k_VBattMinESP_Volt_f32	29.7803001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	43201
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	47765
k_VitesseVehicleBVRampValidThresh_Cnt_u16	56530
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	50149
k_VitesseVehicleBVSigValidThresh_Cnt_u16	42408
k_VitesseVehicleBVSpeedPassThresh_kph_f32	628.64917
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	39188
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	58667
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4230815232
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	5909
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3601703168
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	230
target_SrlComInput_Per1_Batt_Volt_f32.value	12.8520002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2671447552
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	228
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.358222574
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2900442624
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	139
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	667311616
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	225
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1501265408
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1241554432
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	22396416
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	98
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2272976384
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3832544768
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	108
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	121
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	203
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	207
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	221
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2743705088
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	84
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	146
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	163
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	216
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	228
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	191
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2755411456
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	85
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4070661632
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3084287488
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	134
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	175
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2830274048
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3049
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.550082505
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	985038
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	162.619095
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	50759

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3601703168	3601703168	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3601703168	3601703168	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3601703168	3601703168	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3601703168	3601703168	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3601703168	3601703168	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3601703168	3601703168	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3601703168	3601703168	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3601703168	3601703168	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3601703168	3601703168	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3601703168	3601703168	✔
CDD_SrlComVehSpd_Kph_G_f32	380.126892	380.126892	✔
CMM388NTCEnableTimer_mS_M_u32	3601703168	3601703168	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3601703168	3601703168	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3601703168	3601703168	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	14834	14834	✔
CONSANGLECPK_HwDeg_M_f32	-508.6604	-508.6604 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3601703168	3601703168	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3601703168	3601703168	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3601703168	3601703168	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3601703168	3601703168	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3601703168	3601703168	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3601703168	3601703168	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3601703168	3601703168	✔
ESPNTCEnableTimer_mS_M_u32	3601703168	3601703168	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3601703168	3601703168	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	200	200	✔
EffacDefaultDiagTimer_mS_M_u32[1]	300	300	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	6454	6454	✔
ElecIntTimer_mS_M_u32[1]	8259	8259	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3601703168	3601703168	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	35522	35522	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3601703168	3601703168	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	59462	59462	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3601703168	3601703168	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	45018	45018	✔
ISDATBSI412MsgTimer_mS_M_u32	3601703168	3601703168	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	9445	9445	✔
ISDATBSI432MsgTimer_mS_M_u32	3601703168	3601703168	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1170	1170	✔
ISDATDIRASentTimer_mS_M_u32	3601703168	3601703168	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	10747	10747	✔
ISDYN2CMMMsgTimer_mS_M_u32	3601703168	3601703168	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	54941	54941	✔
ISDYNAASMsgTimer_mS_M_u32	3601703168	3601703168	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	14834	14834	✔
ISDYNABRMsgTimer_mS_M_u32	3601703168	3601703168	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	59462	59462	✔
ISDYNCMM208MsgTimer_mS_M_u32	3601703168	3601703168	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	62161	62161	✔
ISDYNCMM388MsgTimer_mS_M_u32	3601703168	3601703168	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	27141	27141	✔
ISDYNVOLMsgTimer_mS_M_u32	3601703168	3601703168	✔
IgnOnTimer_mS_M_u32	3305586176	3305586176	✔
IgnTimeOff_Sec_M_u32	2086262849	2086262849	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	105	105	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2900442624	2900442624	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	139	139	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	667311616	667311616	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	225	225	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1501265408	1501265408	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	113	113	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1241554432	1241554432	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3564142080	3564142080	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	98	98	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2272976384	2272976384	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	210	210	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3832544768	3832544768	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	15	15	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2743705088	2743705088	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	191	191	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2755411456	2755411456	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	85	85	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4070661632	4070661632	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	221	221	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3084287488	3084287488	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2830274048	2830274048	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	318.841003	318.841003	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	78.1390991	78.1390991	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	605.490173	605.490173	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	14834	14834	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2086262849	2086262849	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-508.6604	-508.6604 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	380.126892	380.126892	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.349 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2970614016
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	5364
AASNodeAbsentTimer_mS_M_u32	2484480256
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	35830
ANGLEVOLANTSigValidCount_Cnt_M_u16	65528
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	32781
AngleVolantMsgTimer_mS_M_u32	2970614016
AngleVolantValidCount_Cnt_M_u16	40428
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1310910720
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1896835328
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	386537728
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	221894912
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	38641
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3761805568
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	6938
CAVNodeAbsentTimer_mS_M_u32	3767814400
CDD_SrlComVehSpd_Kph_G_f32	523.749878
CMM388NTCEnableTimer_mS_M_u32	665028864
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3761391872
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	53765
CMMNodeAbsentTimer_mS_M_u32	1914427648
CONSANGLECPKSigInvalidCount_Cnt_M_u16	30047
CONSANGLECPKSigValidCount_Cnt_M_u16	43633
CONSANGLECPK_Cnt_M_u16	3008
CONSANGLECPK_HwDeg_M_f32	699.242188
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	3008
CPKVehicleSpeedMsgTimer_mS_M_u32	2531457280
CPKVehicleSpeedValidCount_Cnt_M_u16	9683
CityParkInputConsistentCount_Cnt_M_u16	46080
CityParkInputInvalidCount_Cnt_M_u16	508
CityParkInputMsgTimer_mS_M_u32	2900442624
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	791292160
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	2312

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2664089856
ComputerRazGCTSigValidCount_Cnt_M_u16	8734
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	38888
DMDFCTCPKSigValidCount_Cnt_M_u16	20530
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	8704
DMDRELAXECPKSigValidCount_Cnt_M_u16	59778
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	9592
DateInvalidTimer_mS_M_u32	1896835328
DiagMuxOnAbsentTimer_mS_M_u32	2574170368
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	221894912
ESPNTCEnableTimer_mS_M_u32	3137546496
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	5843
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	500
EffacDefaultDiagTimer_mS_M_u32[1]	600
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8976
ElecIntTimer_mS_M_u32[1]	15236
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1361221888
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	58757
EtatMTSigValidCount_Cnt_M_u16	30211
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	43369
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	45563
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	464
ISDAT4V2BSI552MsgTimer_mS_M_u32	4096776448
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	46151
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	23661
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	30211
ISDATBSI3F2MsgTimer_mS_M_u32	2640623872
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	39576
ISDATBSI412MsgLenValidCount_Cnt_M_u16	47406
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	58757
ISDATBSI412MsgTimer_mS_M_u32	3271948544
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	31513
ISDATBSI432MsgLenValidCount_Cnt_M_u16	9959
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	679
ISDATDIRASentFltAcc_Cnt_M_u16	17803
ISDATDIRASentTimer_mS_M_u32	2531457280
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	15414
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	40428
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	48739
ISDYN2CMMMsgTimer_mS_M_u32	4066715904
ISDYNAASChkSumInvalidCount_Cnt_M_u16	50942
ISDYNAASChkSumValidCount_Cnt_M_u16	39328
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	53863
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	64425
ISDYNAASMsgLenValidCount_Cnt_M_u16	24163
ISDYNAASMsgTimeValidCount_Cnt_M_u16	50942
ISDYNAASMsgTimer_mS_M_u32	1586465024
ISDYNABRChkSumInvalidCount_Cnt_M_u16	31904
ISDYNABRChkSumValidCount_Cnt_M_u16	9802
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	64505
ISDYNABRMsgCountValidCount_Cnt_M_u16	9435
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	12634
ISDYNABRMsgLenValidCount_Cnt_M_u16	64684
ISDYNABRMsgTimeValidCount_Cnt_M_u16	3008
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	52927
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	34150
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	30211
ISDYNCMM208MsgTimer_mS_M_u32	2530470144
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	52927
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	34150
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	60130

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2783774976
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	53589
ISDYNVOLChkSumValidCount_Cnt_M_u16	13031
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	47838
ISDYNVOLMsgCountValidCount_Cnt_M_u16	57256
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	34008
ISDYNVOLMsgLenValidCount_Cnt_M_u16	15177
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	53765
ISDYNVOLMsgTimer_mS_M_u32	297191680
IgnOnTimer_mS_M_u32	2801862912
IgnTimeOff_Sec_M_u32	2765832872
ManVehSpd_Kph_M_f32	184.705505
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	114
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	152
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3949115648
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	131
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1835342080
PrevISDATBSI412MsgDLCError_Cnt_M_u08	155
PrevISDATBSI412MsgRxTime_MSec_M_u32	1205946624
PrevISDATBSI432MsgDLCError_Cnt_M_u08	59
PrevISDATBSI432MsgRxTime_MSec_M_u32	13052160
PrevISDATDIRAMsgTxTime_MSec_M_u32	2915387648
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	12
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2959169792
PrevISDYNAASMsgDLCError_Cnt_M_u08	51
PrevISDYNAASMsgRxTime_MSec_M_u32	3928803584
PrevISDYNABRMsgDLCError_Cnt_M_u08	68
PrevISDYNABRMsgRxTime_MSec_M_u32	735643904
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	1
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1918748928
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	250
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1528178944
PrevISDYNVOLMsgDLCError_Cnt_M_u08	12
PrevISDYNVOLMsgRxTime_MSec_M_u32	2634696960
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3959159040
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	261.523285
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	11423
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	31705
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	8740
VitesseVehicleBVRampValidCount_Cnt_M_u16	64286
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	25851
VitesseVehicleBVSigValidCount_Cnt_M_u16	701
VitesseVehicleBV_Kph_M_f32	99.1082993
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	60130
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	7931
VitesseVehiculeRoues_Kph_M_f32	305.325012
k_AASNTCEnableTimeout_mS_u16	47827
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	37715
k_AASNodeTimeout_mS_u16	49881
k_ABSNodeTimeout_mS_u16	43353
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	43200
k_ANGLEVOLANTSigValidThresh_Cnt_u16	5070
k_AngleVolantInvalidThresh_Cnt_u16	1777
k_AngleVolantValidThresh_Cnt_u16	508
k_BSI552MsgTimeout_mS_u16	27614
k_BSINTCEnableTimeout_mS_u16	45041
k_BSINodeAbsentDiag_Cnt_str.Threshold	37432
k_BSINodeAbsentDiag_Cnt_str.PStep	23790
k_BSINodeAbsentDiag_Cnt_str.NStep	4167
k_BSINodeAbsentTimeout_mS_u16	16101
k_BSINodeTimeout_mS_u16	679
k_BattOvHi_Volt_f32	26.3649006
k_BattOvLo_Volt_f32	14.8353996
k_BattUvHi_Volt_f32	28.8486996
k_BattUvLo_Volt_f32	20.3773994
k_CAVNTCEnableTimeout_mS_u16	47050
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	43792
k_CAVNodeTimeout_mS_u16	17483
k_CMM388MsgTimeout_mS_u16	39924
k_CMM388NTCEnableTimeout_mS_u16	59360
k_CMMNTCEnableTimeout_mS_u16	5407
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	35047
k_CONSANGLECPKMax_HwDeg_f32	79.5999985
k_CONSANGLECPKMin_HwDeg_f32	-592.458496
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	61922
k_CONSANGLECPKSigValidThresh_Cnt_u16	26107
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	54135
k_CPKVehicleSpeedValidThresh_Cnt_u16	64999
k_CityParkInputInvalidThresh_Cnt_u16	28606
k_CityParkInputValidThresh_Cnt_u16	46080
k_ComputerRazGCTSigValidThresh_Cnt_u16	56005
k_CptTemporelSigValidThresh_Cnt_u16	1387
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	47194
k_DMDFCTCPKSigValidThresh_Cnt_u16	50092
k_DMDFCTCPKValidCount_Cnt_u16	12057
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	48739
k_DMDRELAXECPKSigValidThresh_Cnt_u16	60653
k_DMDRelaxeConsistentThresh_Cnt_u16	65419
k_DateValidThresh_Cnt_u16	464
k_DefaultVehSpd_Kph_f32	152.174194
k_DiagMuxOnAbsentTimeout_mS_u16	25870
k_EMNodeTimeout_mS_u16	53080
k_ESPNTCEnableTimeout_mS_u16	50182
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	15375
k_EtatMTSigInvalidThresh_Cnt_u16	53283
k_EtatMTSigValidThresh_Cnt_u16	9741
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	26406
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	18179
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	62341
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	14336
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	26854
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	37292
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	6738
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	61152
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	25645
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	44212
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	4330
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	2622
k_ISDATDIRASentDiag_Cnt_str.Threshold	6549

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	63930
k_ISDATDIRASentDiag_Cnt_str.NStep	24627
k_ISDATDIRASentTimeout_mS_u16	45452
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	20463
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	32781
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	38722
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	33696
k_ISDYNAASChkSumValidThresh_Cnt_u16	27978
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	33529
k_ISDYNAASMsgCountValidThresh_Cnt_u16	60379
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	36532
k_ISDYNAASMsgLenValidThresh_Cnt_u16	53485
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	52470
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	56400
k_ISDYNABRChkSumValidThresh_Cnt_u16	5154
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	7665
k_ISDYNABRMsgCountValidThresh_Cnt_u16	43059
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	6405
k_ISDYNABRMsgLenValidThresh_Cnt_u16	40403
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	27798
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	23219
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	33373
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	43708
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	4854
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	50936
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	29908
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	14015
k_ISDYNVOLChkSumValidThresh_Cnt_u16	62613
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	9452
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	24414
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	12145
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	39151
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	17950
k_IgnOnTimeout_mS_u16	20395
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	235.366104
k_PowerCutVehSpdLowThresh_Kph_f32	207.405197
k_PowerCutVehSpdLowTimeout_mS_u16	17135
k_VBattMaxAAS_Volt_f32	25.8181
k_VBattMaxBSI_Volt_f32	26.5221004
k_VBattMaxCAV_Volt_f32	31.656601
k_VBattMaxCMM388_Volt_f32	0.00109999999
k_VBattMaxCMM_Volt_f32	6.09350014
k_VBattMaxESP_Volt_f32	20.9473991
k_VBattMinAAS_Volt_f32	1.49989998
k_VBattMinBSI_Volt_f32	20.9473991
k_VBattMinCAV_Volt_f32	24.7831001
k_VBattMinCMM388_Volt_f32	7.09380007
k_VBattMinCMM_Volt_f32	21.0515003
k_VBattMinESP_Volt_f32	6.09350014
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	44625
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	21142
k_VitesseVehicleBVRampValidThresh_Cnt_u16	49630
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	63975
k_VitesseVehicleBVSigValidThresh_Cnt_u16	61021
k_VitesseVehicleBVSpeedPassThresh_kph_f32	189.058304
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	8730
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	10132
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1896835328
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	250
target_SrlComInput_Per1_Batt_Volt_f32.value	19.4864998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1806014720
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	129
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.595817804
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	155
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3614640384
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3812862208
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	178538752
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	217
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	898951424
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1276479744
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	128
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	908470528
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3687237888
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	43
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	69
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	76
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	185
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	98
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2365188352
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	125
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	141
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	161
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	188
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	211
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	218
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	492964096
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	225
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2930944256
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	462637312
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	45
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	80
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	106
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	129
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	137
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	153
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2369722624
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	35
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0809573904
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	507700
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	123.231598
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	9857

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	184.705505	184.705505	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	3008	3008	✔
CONSANGLECPK_HwDeg_M_f32	699.242188	699.242188 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3251510528	3251510528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	500	500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	600	600	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	8976	8976	✔
ElecIntTimer_mS_M_u32[1]	15236	15236	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	464	464	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	30211	30211	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	58757	58757	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	679	679	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	6549	6549	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	48739	48739	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	50942	50942	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	3008	3008	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	30211	30211	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	60130	60130	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	53765	53765	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	2801862912	2801862912	✔
IgnTimeOff_Sec_M_u32	2765832872	2765832872	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	155	155	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3614640384	3614640384	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	16	16	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3812862208	3812862208	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	45	45	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	178538752	178538752	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	217	217	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	898951424	898951424	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2915387648	2915387648	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	128	128	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	908470528	908470528	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	75	75	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3687237888	3687237888	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	98	98	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2365188352	2365188352	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	198	198	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	492964096	492964096	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	225	225	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2930944256	2930944256	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	99	99	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	462637312	462637312	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2369722624	2369722624	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	261.523285	261.523285	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	99.1082993	99.1082993	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	305.325012	305.325012	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	3008	3008	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2765832872	2765832872	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	699.242188	699.242188 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.350 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	59955200
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	2533
AASNodeAbsentTimer_mS_M_u32	1866483712
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	52957
ANGLEVOLANTSigValidCount_Cnt_M_u16	54680
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	27802
AngleVolantMsgTimer_mS_M_u32	59955200
AngleVolantValidCount_Cnt_M_u16	21886
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1679427584
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1297385472
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3794040832
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1855272960
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	23020
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1620637696
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	47090
CAVNodeAbsentTimer_mS_M_u32	2856708096
CDD_SrlComVehSpd_Kph_G_f32	228.585403
CMM388NTCEnableTimer_mS_M_u32	572008448
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2741757952
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	10994
CMMNodeAbsentTimer_mS_M_u32	1206859776
CONSANGLECPKSigInvalidCount_Cnt_M_u16	42403
CONSANGLECPKSigValidCount_Cnt_M_u16	43310
CONSANGLECPK_Cnt_M_u16	33089
CONSANGLECPK_HwDeg_M_f32	105.593002
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	33089
CPKVehicleSpeedMsgTimer_mS_M_u32	1578752000
CPKVehicleSpeedValidCount_Cnt_M_u16	46671
CityParkInputConsistentCount_Cnt_M_u16	25410
CityParkInputInvalidCount_Cnt_M_u16	47693
CityParkInputMsgTimer_mS_M_u32	3614640384
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3993257984
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	32169

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1772251136
ComputerRazGCTSigValidCount_Cnt_M_u16	39663
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	43145
DMDFCTCPKSigValidCount_Cnt_M_u16	620
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	46271
DMDRELAXECPKSigValidCount_Cnt_M_u16	49402
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	14680
DateInvalidTimer_mS_M_u32	1297385472
DiagMuxOnAbsentTimer_mS_M_u32	896964608
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1855272960
ESPNTCEnableTimer_mS_M_u32	4000925696
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	61257
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1100
EffacDefaultDiagTimer_mS_M_u32[1]	1150
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	979
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	903542784
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	16753
EtatMTSigValidCount_Cnt_M_u16	58040
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	45445
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	58770
ISDAT4V2BSI552MsgTimer_mS_M_u32	296957952
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	46251
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	44794
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	58040
ISDATBSI3F2MsgTimer_mS_M_u32	2173999104
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	54968
ISDATBSI412MsgLenValidCount_Cnt_M_u16	11702
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	16753
ISDATBSI412MsgTimer_mS_M_u32	632346624
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	32694
ISDATBSI432MsgLenValidCount_Cnt_M_u16	3853
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	30027
ISDATDIRASentFltAcc_Cnt_M_u16	15519
ISDATDIRASentTimer_mS_M_u32	1578752000
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	18399
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	21886
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	57624
ISDYN2CMMMsgTimer_mS_M_u32	1347635200
ISDYNAASChkSumInvalidCount_Cnt_M_u16	39879
ISDYNAASChkSumValidCount_Cnt_M_u16	1698
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	25613
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	4677
ISDYNAASMsgLenValidCount_Cnt_M_u16	11480
ISDYNAASMsgTimeValidCount_Cnt_M_u16	39879
ISDYNAASMsgTimer_mS_M_u32	760489984
ISDYNABRChkSumInvalidCount_Cnt_M_u16	31840
ISDYNABRChkSumValidCount_Cnt_M_u16	33315
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	43222
ISDYNABRMsgCountValidCount_Cnt_M_u16	4337
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	7602
ISDYNABRMsgLenValidCount_Cnt_M_u16	24189
ISDYNABRMsgTimeValidCount_Cnt_M_u16	33089
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	2001
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	11053
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	58040
ISDYNCMM208MsgTimer_mS_M_u32	2382825472
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2001
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	11053
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	50844

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2906368000
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	59841
ISDYNVOLChkSumValidCount_Cnt_M_u16	26572
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	38823
ISDYNVOLMsgCountValidCount_Cnt_M_u16	44042
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	63802
ISDYNVOLMsgLenValidCount_Cnt_M_u16	63653
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	10994
ISDYNVOLMsgTimer_mS_M_u32	3235801088
IgnOnTimer_mS_M_u32	4194281472
IgnTimeOff_Sec_M_u32	2268951028
ManVehSpd_Kph_M_f32	601.55658
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	115
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	49
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	261789696
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	223
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	185825280
PrevISDATBSI412MsgDLCError_Cnt_M_u08	248
PrevISDATBSI412MsgRxTime_MSec_M_u32	3898533888
PrevISDATBSI432MsgDLCError_Cnt_M_u08	184
PrevISDATBSI432MsgRxTime_MSec_M_u32	757942272
PrevISDATDIRAMsgTxTime_MSec_M_u32	1186129920
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	70
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2199828480
PrevISDYNAASMsgDLCError_Cnt_M_u08	194
PrevISDYNAASMsgRxTime_MSec_M_u32	2407294976
PrevISDYNABRMsgDLCError_Cnt_M_u08	41
PrevISDYNABRMsgRxTime_MSec_M_u32	3413616640
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	18
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4209600512
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	217
PrevISDYNCMM388MsgRxTime_MSec_M_u32	440420352
PrevISDYNVOLMsgDLCError_Cnt_M_u08	163
PrevISDYNVOLMsgRxTime_MSec_M_u32	3437488128
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	47110144
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	35.8825989
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	55139
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	11382
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	19156
VitesseVehicleBVRampValidCount_Cnt_M_u16	679
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	38862
VitesseVehicleBVSigValidCount_Cnt_M_u16	8521
VitesseVehicleBV_Kph_M_f32	551.329773
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	50844
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	60687
VitesseVehiculeRoues_Kph_M_f32	474.929413
k_AASNTCEnableTimeout_mS_u16	32776
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	53577
k_AASNodeTimeout_mS_u16	22390
k_ABSNodeTimeout_mS_u16	30774
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	21185
k_ANGLEVOLANTSigValidThresh_Cnt_u16	42072
k_AngleVolantInvalidThresh_Cnt_u16	5871
k_AngleVolantValidThresh_Cnt_u16	47693
k_BSI552MsgTimeout_mS_u16	21094
k_BSINTCEnableTimeout_mS_u16	16686
k_BSINodeAbsentDiag_Cnt_str.Threshold	13845
k_BSINodeAbsentDiag_Cnt_str.PStep	65269
k_BSINodeAbsentDiag_Cnt_str.NStep	38297
k_BSINodeAbsentTimeout_mS_u16	36882
k_BSINodeTimeout_mS_u16	30027
k_BattOvHi_Volt_f32	18.0258999
k_BattOvLo_Volt_f32	8.91069984
k_BattUvHi_Volt_f32	28.1574001
k_BattUvLo_Volt_f32	3.13919997
k_CAVNTCEnableTimeout_mS_u16	20707
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	24592
k_CAVNodeTimeout_mS_u16	59615
k_CMM388MsgTimeout_mS_u16	29925
k_CMM388NTCEnableTimeout_mS_u16	16673
k_CMMNTCEnableTimeout_mS_u16	61987
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	24395
k_CONSANGLECPKMax_HwDeg_f32	215.036499
k_CONSANGLECPKMin_HwDeg_f32	-197.0233
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	45468
k_CONSANGLECPKSigValidThresh_Cnt_u16	6159
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	7580
k_CPKVehicleSpeedValidThresh_Cnt_u16	43211
k_CityParkInputInvalidThresh_Cnt_u16	39686
k_CityParkInputValidThresh_Cnt_u16	25410
k_ComputerRazGCTSigValidThresh_Cnt_u16	47409
k_CptTemporelSigValidThresh_Cnt_u16	11264
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	34994
k_DMDFCTCPKSigValidThresh_Cnt_u16	2429
k_DMDFCTCPKValidCount_Cnt_u16	12660
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	57624
k_DMDRELAXECPKSigValidThresh_Cnt_u16	55355
k_DMDRelaxeConsistentThresh_Cnt_u16	39009
k_DateValidThresh_Cnt_u16	58770
k_DefaultVehSpd_Kph_f32	8.73820019
k_DiagMuxOnAbsentTimeout_mS_u16	11607
k_EMNodeTimeout_mS_u16	48056
k_ESPNTCEnableTimeout_mS_u16	27950
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	58835
k_EtatMTSigInvalidThresh_Cnt_u16	19927
k_EtatMTSigValidThresh_Cnt_u16	20186
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	56975
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	4534
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	63667
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	19840
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	44431
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	16764
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	50699
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	56098
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	5242
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	28261
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	29828
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	44232
k_ISDATDIRASentDiag_Cnt_str.Threshold	25239

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	16638
k_ISDATDIRASentDiag_Cnt_str.NStep	16248
k_ISDATDIRASentTimeout_mS_u16	36252
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	57269
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	27802
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	58234
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	26464
k_ISDYNAASChkSumValidThresh_Cnt_u16	44323
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	5078
k_ISDYNAASMsgCountValidThresh_Cnt_u16	48113
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	38436
k_ISDYNAASMsgLenValidThresh_Cnt_u16	32058
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	6368
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	29904
k_ISDYNABRChkSumValidThresh_Cnt_u16	28699
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	50412
k_ISDYNABRMsgCountValidThresh_Cnt_u16	35047
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	22002
k_ISDYNABRMsgLenValidThresh_Cnt_u16	23113
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	34750
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	40231
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	29545
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	60365
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	14813
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	32920
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	49605
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	24131
k_ISDYNVOLChkSumValidThresh_Cnt_u16	55169
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	26878
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	9959
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	5037
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	10740
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	53416
k_IgnOnTimeout_mS_u16	50047
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	187.662506
k_PowerCutVehSpdLowThresh_Kph_f32	183.545303
k_PowerCutVehSpdLowTimeout_mS_u16	22452
k_VBattMaxAAS_Volt_f32	17.8411999
k_VBattMaxBSI_Volt_f32	15.7936001
k_VBattMaxCAV_Volt_f32	3.38709998
k_VBattMaxCMM388_Volt_f32	28.2929993
k_VBattMaxCMM_Volt_f32	19.3936996
k_VBattMaxESP_Volt_f32	2.64350009
k_VBattMinAAS_Volt_f32	16.8999996
k_VBattMinBSI_Volt_f32	2.64350009
k_VBattMinCAV_Volt_f32	26.4246006
k_VBattMinCMM388_Volt_f32	21.8069
k_VBattMinCMM_Volt_f32	24.3742008
k_VBattMinESP_Volt_f32	19.3936996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	52367
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	21118
k_VitesseVehicleBVRampValidThresh_Cnt_u16	33447
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	4812
k_VitesseVehicleBVSigValidThresh_Cnt_u16	26667
k_VitesseVehicleBVSpeedPassThresh_kph_f32	307.759186
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	41714
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	54597
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1297385472
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	217
target_SrlComInput_Per1_Batt_Volt_f32.value	17.5730991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2991716352
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	189
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.278534055
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2963908608
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	397920256
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1813374976
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	189
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4123265024
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4240582656
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3373287424
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2729338880
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	78
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	136
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	145
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	163
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	177
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3281324032
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	92
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	121
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	114
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1524410368
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	140
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	829081600
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	177
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3041454080
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	104
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	114
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	132
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	145
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2474997760
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3369
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.013615232
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	908992
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	54.3160019
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	61885

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	59955200	59955200	✔
AASNTCsEnabled_Cnt_M_lgc	1	1	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	10994	10994	✔
CMMNodeAbsentTimer_mS_M_u32	3373287424	3373287424	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	33089	33089	✔
CONSANGLECPK_HwDeg_M_f32	105.593002	105.593002 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2006148864	2006148864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2006148864	2006148864	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1150	1150	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2006148864	2006148864	✔
ElecIntTimer_mS_M_u32[1]	979	979	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	25239	25239	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2729338880	2729338880	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	4194281472	4194281472	✔
IgnTimeOff_Sec_M_u32	2268951028	2268951028	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	119	119	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2963908608	2963908608	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	131	131	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	397920256	397920256	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	215	215	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1813374976	1813374976	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	189	189	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4123265024	4123265024	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1186129920	1186129920	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	93	93	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3373287424	3373287424	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	167	167	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2729338880	2729338880	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	246	246	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3281324032	3281324032	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	114	114	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1524410368	1524410368	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	140	140	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	829081600	829081600	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	177	177	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3041454080	3041454080	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2474997760	2474997760	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	35.8825989	35.8825989	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	551.329773	551.329773	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	474.929413	474.929413	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	33089	33089	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2268951028	2268951028	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	105.593002	105.593002 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	8.73820019	8.73820019	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0149	0x0149	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.351 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	843463424
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	35150
AASNodeAbsentTimer_mS_M_u32	2969430784
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	48229
ANGLEVOLANTSigValidCount_Cnt_M_u16	32756
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	29999
AngleVolantMsgTimer_mS_M_u32	843463424
AngleVolantValidCount_Cnt_M_u16	62211
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1768991488
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3082889984
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1695636224
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1925126912
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	5944
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1538513664
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	15781
CAVNodeAbsentTimer_mS_M_u32	2657946368
CDD_SrlComVehSpd_Kph_G_f32	153.244202
CMM388NTCEnableTimer_mS_M_u32	1341541120
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3405449984
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	7528
CMMNodeAbsentTimer_mS_M_u32	3467713280
CONSANGLECPKSigInvalidCount_Cnt_M_u16	32531
CONSANGLECPKSigValidCount_Cnt_M_u16	35891
CONSANGLECPK_Cnt_M_u16	4090
CONSANGLECPK_HwDeg_M_f32	113.551804
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	4090
CPKVehicleSpeedMsgTimer_mS_M_u32	4273027840

Name	Input Value
CPKVehicleSpeedValidCount_Cnt_M_u16	1782
CityParkInputConsistentCount_Cnt_M_u16	55735
CityParkInputInvalidCount_Cnt_M_u16	4501
CityParkInputMsgTimer_mS_M_u32	2963908608
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1152510720
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	15874
ComputerRazGCTSigInvalidTimer_mS_M_u32	1918339840
ComputerRazGCTSigValidCount_Cnt_M_u16	9904
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	14049
DMDFCTCPKSigValidCount_Cnt_M_u16	41208
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	4799
DMDRELAXECPKSigValidCount_Cnt_M_u16	50638
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	55284
DateInvalidTimer_mS_M_u32	3082889984
DiagMuxOnAbsentTimer_mS_M_u32	3684367104
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1925126912
ESPNTCEnableTimer_mS_M_u32	1465051904
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	6179
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	2050
EffacDefaultDiagTimer_mS_M_u32[1]	6070
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	8
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1676532480
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	59114
EtatMTSigValidCount_Cnt_M_u16	2773
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	25453
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	65535
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	3974
ISDAT4V2BSI552MsgTimer_mS_M_u32	2170886912
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	61115
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	10126
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	2773
ISDATBSI3F2MsgTimer_mS_M_u32	4014013184
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	2454
ISDATBSI412MsgLenValidCount_Cnt_M_u16	60505
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	59114
ISDATBSI412MsgTimer_mS_M_u32	3287038720
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	12060
ISDATBSI432MsgLenValidCount_Cnt_M_u16	51415
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	43418
ISDATDIRASentFltAcc_Cnt_M_u16	41886
ISDATDIRASentTimer_mS_M_u32	4273027840
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	46112
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	62211
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	35124
ISDYN2CMMMsgTimer_mS_M_u32	432335616
ISDYNAASChkSumInvalidCount_Cnt_M_u16	56232
ISDYNAASChkSumValidCount_Cnt_M_u16	62167
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	50006
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	15020
ISDYNAASMsgLenValidCount_Cnt_M_u16	8884
ISDYNAASMsgTimeValidCount_Cnt_M_u16	56232
ISDYNAASMsgTimer_mS_M_u32	507661056
ISDYNABRChkSumInvalidCount_Cnt_M_u16	13662
ISDYNABRChkSumValidCount_Cnt_M_u16	7125
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	45179
ISDYNABRMsgCountValidCount_Cnt_M_u16	53226
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	4838
ISDYNABRMsgLenValidCount_Cnt_M_u16	26694

Name	Input Value
ISDYNABRMsgTimeValidCount_Cnt_M_u16	4090
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	37701
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	5617
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	2773
ISDYNCMM208MsgTimer_mS_M_u32	3752438528
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	37701
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	5617
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	38825
ISDYNCMM388MsgTimer_mS_M_u32	2626407168
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	43705
ISDYNVOLChkSumValidCount_Cnt_M_u16	18521
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	24967
ISDYNVOLMsgCountValidCount_Cnt_M_u16	39966
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	65104
ISDYNVOLMsgLenValidCount_Cnt_M_u16	38863
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	7528
ISDYNVOLMsgTimer_mS_M_u32	1554221824
IgnOnTimer_mS_M_u32	3326069504
IgnTimeOff_Sec_M_u32	1323892887
ManVehSpd_Kph_M_f32	310.475891
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	116
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	249
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3710843648
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	160
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1715755776
PrevISDATBSI412MsgDLCError_Cnt_M_u08	56
PrevISDATBSI412MsgRxTime_MSec_M_u32	2283932416
PrevISDATBSI432MsgDLCError_Cnt_M_u08	24
PrevISDATBSI432MsgRxTime_MSec_M_u32	1798761216
PrevISDATDIRAMsgTxTime_MSec_M_u32	3173387008
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	106
PrevISDYN2CMMMsgRxTime_MSec_M_u32	992123648
PrevISDYNAASMsgDLCError_Cnt_M_u08	34
PrevISDYNAASMsgRxTime_MSec_M_u32	3905522432
PrevISDYNABRMsgDLCError_Cnt_M_u08	30
PrevISDYNABRMsgRxTime_MSec_M_u32	836225792
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	3
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2592246528
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	156
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2952653568
PrevISDYNVOLMsgDLCError_Cnt_M_u08	53
PrevISDYNVOLMsgRxTime_MSec_M_u32	781388544
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	613563136
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	387.7995
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	58194
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	7130
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	36095
VitesseVehicleBVRampValidCount_Cnt_M_u16	40263

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	26002
VitesseVehicleBVSigValidCount_Cnt_M_u16	41185
VitesseVehicleBV_Kph_M_f32	69.5317001
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	38825
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	56336
VitesseVehiculeRoues_Kph_M_f32	641.003784
k_AASNTCEnableTimeout_mS_u16	61349
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	27554
k_AASNodeTimeout_mS_u16	39642
k_ABSNodeTimeout_mS_u16	48090
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	41467
k_ANGLEVOLANTSigValidThresh_Cnt_u16	62710
k_AngleVolantInvalidThresh_Cnt_u16	47409
k_AngleVolantValidThresh_Cnt_u16	4501
k_BSI552MsgTimeout_mS_u16	51211
k_BSINTCEnableTimeout_mS_u16	51892
k_BSINodeAbsentDiag_Cnt_str.Threshold	4600
k_BSINodeAbsentDiag_Cnt_str.PStep	47769
k_BSINodeAbsentDiag_Cnt_str.NStep	2541
k_BSINodeAbsentTimeout_mS_u16	60103
k_BSINodeTimeout_mS_u16	43418
k_BattOvHi_Volt_f32	28.4729004
k_BattOvLo_Volt_f32	24.4293995
k_BattUvHi_Volt_f32	10.3292999
k_BattUvLo_Volt_f32	9.18039989
k_CAVNTCEnableTimeout_mS_u16	9683
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	15691
k_CAVNodeTimeout_mS_u16	42335
k_CMM388MsgTimeout_mS_u16	18510
k_CMM388NTCEnableTimeout_mS_u16	54170
k_CMMNTCEnableTimeout_mS_u16	5715
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	30044
k_CONSANGLECPKMax_HwDeg_f32	730.778076
k_CONSANGLECPKMin_HwDeg_f32	-104.336403
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	54953
k_CONSANGLECPKSigValidThresh_Cnt_u16	23312
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	24680
k_CPKVehicleSpeedValidThresh_Cnt_u16	40797
k_CityParkInputInvalidThresh_Cnt_u16	61804
k_CityParkInputValidThresh_Cnt_u16	55735
k_ComputerRazGCTSigValidThresh_Cnt_u16	31017
k_CptTemporelSigValidThresh_Cnt_u16	18556
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	53734
k_DMDFCTCPKSigValidThresh_Cnt_u16	26438
k_DMDFCTCPKValidCount_Cnt_u16	45216
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	35124
k_DMDRELAXECPKSigValidThresh_Cnt_u16	7051
k_DMDRelaxeConsistentThresh_Cnt_u16	62233
k_DateValidThresh_Cnt_u16	3974
k_DefaultVehSpd_Kph_f32	243.280701
k_DiagMuxOnAbsentTimeout_mS_u16	58296
k_EMNodeTimeout_mS_u16	53460
k_ESPNTCEnableTimeout_mS_u16	3569
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	452
k_EtatMTSigInvalidThresh_Cnt_u16	23801
k_EtatMTSigValidThresh_Cnt_u16	20912
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	43407
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	38874
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	7524
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	47164
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	49103

Name	Input Value
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	55626
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	61469
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	63640
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	32976
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	55438
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	11761
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	6245
k_ISDATDIRASentDiag_Cnt_str.Threshold	93
k_ISDATDIRASentDiag_Cnt_str.PStep	55293
k_ISDATDIRASentDiag_Cnt_str.NStep	55204
k_ISDATDIRASentTimeout_mS_u16	61866
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	29598
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	29999
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	56077
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	29790
k_ISDYNAASChkSumValidThresh_Cnt_u16	39637
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	28539
k_ISDYNAASMsgCountValidThresh_Cnt_u16	52970
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	63506
k_ISDYNAASMsgLenValidThresh_Cnt_u16	14734
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	46942
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	1420
k_ISDYNABRChkSumValidThresh_Cnt_u16	11116
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	54840
k_ISDYNABRMsgCountValidThresh_Cnt_u16	25095
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	40040
k_ISDYNABRMsgLenValidThresh_Cnt_u16	55075
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	33154
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	41478
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	14211
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	63957
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	31589
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	32500
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	56109
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	24309
k_ISDYNVOLChkSumValidThresh_Cnt_u16	56056
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	48900
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	15753
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	24630
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	9505
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	9796
k_IgnOnTimeout_mS_u16	8001
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	213.007706
k_PowerCutVehSpdLowThresh_Kph_f32	233.359299
k_PowerCutVehSpdLowTimeout_mS_u16	6305
k_VBattMaxAAS_Volt_f32	7.25519991
k_VBattMaxBSI_Volt_f32	13.2046003
k_VBattMaxCAV_Volt_f32	8.43270016
k_VBattMaxCMM388_Volt_f32	11.8965998
k_VBattMaxCMM_Volt_f32	10.4608002
k_VBattMaxESP_Volt_f32	10.2768002
k_VBattMinAAS_Volt_f32	0.765200019
k_VBattMinBSI_Volt_f32	10.2768002
k_VBattMinCAV_Volt_f32	31.0694008
k_VBattMinCMM388_Volt_f32	19.9790001
k_VBattMinCMM_Volt_f32	10.9559002
k_VBattMinESP_Volt_f32	10.4608002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	38160
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	43780
k_VitesseVehicleBVRampValidThresh_Cnt_u16	41095
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	18265
k_VitesseVehicleBVSigValidThresh_Cnt_u16	44796
k_VitesseVehicleBVSpeedPassThresh_kph_f32	65.0656967
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	31909
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	7533
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3082889984
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2006148864

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	156
target_SrlComInput_Per1_Batt_Volt_f32.value	23.3425999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2324224768
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	130
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.709507763
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	61
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3393309440
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4120341248
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2566720256
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3698502400
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3891809024
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3817728768
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4147350272
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	129
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	141
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	149
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	201
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	218
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4143950592
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	63
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	97
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	105
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	151
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	174
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	175
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	217
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1470679808
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	880700160
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1231293184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	118
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	166
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	186
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	187
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	351165184
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3509
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.516995847
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	261828

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1		
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	230.296997		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	31812		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	310.475891	310.475891	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	4090	4090	✔
CONSANGLECPK_HwDeg_M_f32	113.551804	113.551804 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2006148864	2006148864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2050	2050	✔
EffacDefaultDiagTimer_mS_M_u32[1]	6070	6070	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4	4	✔
ElecIntTimer_mS_M_u32[1]	8	8	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	3974	3974	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	2773	2773	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	59114	59114	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	43418	43418	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	93	93	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	35124	35124	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	56232	56232	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	4090	4090	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	2773	2773	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	38825	38825	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	7528	7528	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	3326069504	3326069504	✔
IgnTimeOff_Sec_M_u32	1323892887	1323892887	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	61	61	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3393309440	3393309440	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4120341248	4120341248	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	221	221	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2566720256	2566720256	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	108	108	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3698502400	3698502400	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3173387008	3173387008	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	205	205	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3817728768	3817728768	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	239	239	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4147350272	4147350272	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	70	70	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4143950592	4143950592	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	217	217	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1470679808	1470679808	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	880700160	880700160	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	221	221	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1231293184	1231293184	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	351165184	351165184	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	387.7995	387.7995	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	69.5317001	69.5317001	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	641.003784	641.003784	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	4090	4090	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1323892887	1323892887	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	113.551804	113.551804 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.352 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	595071488
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	57438
AASNodeAbsentTimer_mS_M_u32	1645281792
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	49435
ANGLEVOLANTSigValidCount_Cnt_M_u16	61229
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	57531
AngleVolantMsgTimer_mS_M_u32	595071488
AngleVolantValidCount_Cnt_M_u16	48576
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1941488128
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1791443456
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	529969664
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3717034496
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	48290
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3853464064
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	34777
CAVNodeAbsentTimer_mS_M_u32	3192103424
CDD_SrlComVehSpd_Kph_G_f32	595.39032
CMM388NTCEnableTimer_mS_M_u32	1588060672
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4036600320
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	15953
CMMNodeAbsentTimer_mS_M_u32	297234944
CONSANGLECPKSigInvalidCount_Cnt_M_u16	41998
CONSANGLECPKSigValidCount_Cnt_M_u16	13681
CONSANGLECPK_Cnt_M_u16	34332
CONSANGLECPK_HwDeg_M_f32	628.079407
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	34332
CPKVehicleSpeedMsgTimer_mS_M_u32	708252160
CPKVehicleSpeedValidCount_Cnt_M_u16	32429
CityParkInputConsistentCount_Cnt_M_u16	55716
CityParkInputInvalidCount_Cnt_M_u16	31497
CityParkInputMsgTimer_mS_M_u32	3393309440
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1995768320
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	37442

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	209986048
ComputerRazGCTSigValidCount_Cnt_M_u16	5817
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	15141
DMDFCTCPKSigValidCount_Cnt_M_u16	38304
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	42509
DMDRELAXECPKSigValidCount_Cnt_M_u16	1439
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	23915
DateInvalidTimer_mS_M_u32	1791443456
DiagMuxOnAbsentTimer_mS_M_u32	1786368512
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3717034496
ESPNTCEnableTimer_mS_M_u32	51511808
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	30432
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	6454
EffacDefaultDiagTimer_mS_M_u32[1]	8257
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	555
ElecIntTimer_mS_M_u32[1]	5557
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	889270784
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	47819
EtatMTSigValidCount_Cnt_M_u16	14281
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	57088
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	24363
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	502
ISDAT4V2BSI552MsgTimer_mS_M_u32	3382407680
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	32472
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	23838
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	14281
ISDATBSI3F2MsgTimer_mS_M_u32	1200083456
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	43846
ISDATBSI412MsgLenValidCount_Cnt_M_u16	19389
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	47819
ISDATBSI412MsgTimer_mS_M_u32	2256933376
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	55605
ISDATBSI432MsgLenValidCount_Cnt_M_u16	13508
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	22522
ISDATDIRASentFltAcc_Cnt_M_u16	31214
ISDATDIRASentTimer_mS_M_u32	708252160
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	45482
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	48576
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	20524
ISDYN2CMMMsgTimer_mS_M_u32	62652928
ISDYNAASChkSumInvalidCount_Cnt_M_u16	53584
ISDYNAASChkSumValidCount_Cnt_M_u16	33923
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	22727
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	27844
ISDYNAASMsgLenValidCount_Cnt_M_u16	3438
ISDYNAASMsgTimeValidCount_Cnt_M_u16	53584
ISDYNAASMsgTimer_mS_M_u32	600039936
ISDYNABRChkSumInvalidCount_Cnt_M_u16	53680
ISDYNABRChkSumValidCount_Cnt_M_u16	14090
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	24279
ISDYNABRMsgCountValidCount_Cnt_M_u16	63818
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	62613
ISDYNABRMsgLenValidCount_Cnt_M_u16	44344
ISDYNABRMsgTimeValidCount_Cnt_M_u16	34332
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	47156
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	62907
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	14281
ISDYNCMM208MsgTimer_mS_M_u32	890094080
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	47156
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	62907
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	59342

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2934399488
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	14620
ISDYNVOLChkSumValidCount_Cnt_M_u16	6399
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	54067
ISDYNVOLMsgCountValidCount_Cnt_M_u16	48174
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	47193
ISDYNVOLMsgLenValidCount_Cnt_M_u16	9371
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	15953
ISDYNVOLMsgTimer_mS_M_u32	2107646464
IgnOnTimer_mS_M_u32	30106112
IgnTimeOff_Sec_M_u32	1711699323
ManVehSpd_Kph_M_f32	233.298996
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	117
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	213
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3049116160
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	207
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2818421248
PrevISDATBSI412MsgDLCError_Cnt_M_u08	99
PrevISDATBSI412MsgRxTime_MSec_M_u32	354722304
PrevISDATBSI432MsgDLCError_Cnt_M_u08	94
PrevISDATBSI432MsgRxTime_MSec_M_u32	1466302976
PrevISDATDIRAMsgTxTime_MSec_M_u32	2249761280
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	121
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1919087104
PrevISDYNAASMsgDLCError_Cnt_M_u08	205
PrevISDYNAASMsgRxTime_MSec_M_u32	4046332416
PrevISDYNABRMsgDLCError_Cnt_M_u08	64
PrevISDYNABRMsgRxTime_MSec_M_u32	520315392
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	176
PrevISDYNCMM208MsgRxTime_MSec_M_u32	205312
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	36
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1695613440
PrevISDYNVOLMsgDLCError_Cnt_M_u08	111
PrevISDYNVOLMsgRxTime_MSec_M_u32	634495488
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2090078720
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	266.04361
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	35538
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	14844
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	33227
VitesseVehicleBVRampValidCount_Cnt_M_u16	43445
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	47508
VitesseVehicleBVSigValidCount_Cnt_M_u16	32870
VitesseVehicleBV_Kph_M_f32	161.985703
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	59342
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	62297
VitesseVehiculeRoues_Kph_M_f32	46.1164017
k_AASNTCEnableTimeout_mS_u16	21275
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	36835
k_AASNodeTimeout_mS_u16	48380
k_ABSNodeTimeout_mS_u16	53306
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	48280
k_ANGLEVOLANTSigValidThresh_Cnt_u16	60519
k_AngleVolantInvalidThresh_Cnt_u16	19382
k_AngleVolantValidThresh_Cnt_u16	31497
k_BSI552MsgTimeout_mS_u16	56168
k_BSINTCEnableTimeout_mS_u16	26221
k_BSINodeAbsentDiag_Cnt_str.Threshold	55166
k_BSINodeAbsentDiag_Cnt_str.PStep	65443
k_BSINodeAbsentDiag_Cnt_str.NStep	9244
k_BSINodeAbsentTimeout_mS_u16	57331
k_BSINodeTimeout_mS_u16	22522
k_BattOvHi_Volt_f32	6.31040001
k_BattOvLo_Volt_f32	15.1082001
k_BattUvHi_Volt_f32	23.9881992
k_BattUvLo_Volt_f32	28.5457993
k_CAVNTCEnableTimeout_mS_u16	46671
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	41191
k_CAVNodeTimeout_mS_u16	24874
k_CMM388MsgTimeout_mS_u16	41822
k_CMM388NTCEnableTimeout_mS_u16	12666
k_CMMNTCEnableTimeout_mS_u16	26640
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	22389
k_CONSANGLECPKMax_HwDeg_f32	273.588013
k_CONSANGLECPKMin_HwDeg_f32	-363.18689
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	10958
k_CONSANGLECPKSigValidThresh_Cnt_u16	30297
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	9298
k_CPKVehicleSpeedValidThresh_Cnt_u16	50673
k_CityParkInputInvalidThresh_Cnt_u16	21894
k_CityParkInputValidThresh_Cnt_u16	55716
k_ComputerRazGCTSigValidThresh_Cnt_u16	6030
k_CptTemporelSigValidThresh_Cnt_u16	12884
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	46997
k_DMDFCTCPKSigValidThresh_Cnt_u16	45112
k_DMDFCTCPKValidCount_Cnt_u16	36970
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	20524
k_DMDRELAXECPKSigValidThresh_Cnt_u16	12775
k_DMDRelaxeConsistentThresh_Cnt_u16	25405
k_DateValidThresh_Cnt_u16	502
k_DefaultVehSpd_Kph_f32	110.949997
k_DiagMuxOnAbsentTimeout_mS_u16	33506
k_EMNodeTimeout_mS_u16	62155
k_ESPNTCEnableTimeout_mS_u16	18165
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	21053
k_EtatMTSigInvalidThresh_Cnt_u16	34527
k_EtatMTSigValidThresh_Cnt_u16	49529
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	42205
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	17084
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	669
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	26197
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	55387
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	3114
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	55858
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	59777
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	46105
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	31840
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	17654
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	52185
k_ISDATDIRASentDiag_Cnt_str.Threshold	11630

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	28093
k_ISDATDIRASentDiag_Cnt_str.NStep	10447
k_ISDATDIRASentTimeout_mS_u16	52428
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	56878
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	57531
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	20385
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	5296
k_ISDYNAASChkSumValidThresh_Cnt_u16	47626
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	8663
k_ISDYNAASMsgCountValidThresh_Cnt_u16	64586
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	22932
k_ISDYNAASMsgLenValidThresh_Cnt_u16	45280
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	17711
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	13475
k_ISDYNABRChkSumValidThresh_Cnt_u16	31686
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	32674
k_ISDYNABRMsgCountValidThresh_Cnt_u16	21748
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	49489
k_ISDYNABRMsgLenValidThresh_Cnt_u16	14816
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	41603
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	7862
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	5503
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	19467
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	33819
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	61997
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	32321
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	59177
k_ISDYNVOLChkSumValidThresh_Cnt_u16	48096
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	17981
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	41454
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	32487
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	6373
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	13756
k_IgnOnTimeout_mS_u16	54853
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	218.268799
k_PowerCutVehSpdLowThresh_Kph_f32	133.214096
k_PowerCutVehSpdLowTimeout_mS_u16	51239
k_VBattMaxAAS_Volt_f32	8.50059986
k_VBattMaxBSI_Volt_f32	24.2325001
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	18.5851994
k_VBattMaxCMM_Volt_f32	8.29380035
k_VBattMaxESP_Volt_f32	28.1497002
k_VBattMinAAS_Volt_f32	22.9111004
k_VBattMinBSI_Volt_f32	28.1497002
k_VBattMinCAV_Volt_f32	19.3645
k_VBattMinCMM388_Volt_f32	28.4657993
k_VBattMinCMM_Volt_f32	26.4990005
k_VBattMinESP_Volt_f32	8.29380035
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	49624
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	35006
k_VitesseVehicleBVRampValidThresh_Cnt_u16	5683
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	7167
k_VitesseVehicleBVSigValidThresh_Cnt_u16	44501
k_VitesseVehicleBVSpeedPassThresh_kph_f32	411.897003
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	51929
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	16707
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1791443456
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60081
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1329630720
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	36
target_SrlComInput_Per1_Batt_Volt_f32.value	3.94630003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3979358720
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	188
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.425020576
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2110087680
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	177
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3661922816
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	244556288
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2729624064
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	513925632
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	174129664
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	236
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3991937536
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	34
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	52
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	116
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	172
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	186
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	228
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3339436544
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	35
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	76
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	90
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	140
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	142
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	170
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	831545856
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2039448064
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1499374080
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	88
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	151
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	154
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3288314368
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3588
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.6684497
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	538761
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	34.6509018
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	2044

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1329630720	1329630720	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1329630720	1329630720	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1329630720	1329630720	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1329630720	1329630720	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1329630720	1329630720	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1329630720	1329630720	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1329630720	1329630720	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1329630720	1329630720	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1329630720	1329630720	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1329630720	1329630720	✔
CDD_SrlComVehSpd_Kph_G_f32	233.298996	233.298996	✔
CMM388NTCEnableTimer_mS_M_u32	1329630720	1329630720	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1329630720	1329630720	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1329630720	1329630720	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	34332	34332	✔
CONSANGLECPK_HwDeg_M_f32	628.079407	628.079407 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1329630720	1329630720	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1329630720	1329630720	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1329630720	1329630720	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1329630720	1329630720	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1329630720	1329630720	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1329630720	1329630720	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1329630720	1329630720	✔
ESPNTCEnableTimer_mS_M_u32	1329630720	1329630720	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1329630720	1329630720	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	6454	6454	✔
EffacDefaultDiagTimer_mS_M_u32[1]	8257	8257	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	555	555	✔
ElecIntTimer_mS_M_u32[1]	5557	5557	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1329630720	1329630720	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	502	502	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1329630720	1329630720	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	14281	14281	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1329630720	1329630720	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	47819	47819	✔
ISDATBSI412MsgTimer_mS_M_u32	1329630720	1329630720	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	22522	22522	✔
ISDATBSI432MsgTimer_mS_M_u32	1329630720	1329630720	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11630	11630	✔
ISDATDIRASentTimer_mS_M_u32	1329630720	1329630720	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	20524	20524	✔
ISDYN2CMMMsgTimer_mS_M_u32	1329630720	1329630720	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	53584	53584	✔
ISDYNAASMsgTimer_mS_M_u32	1329630720	1329630720	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	34332	34332	✔
ISDYNABRMsgTimer_mS_M_u32	1329630720	1329630720	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	14281	14281	✔
ISDYNCMM208MsgTimer_mS_M_u32	1329630720	1329630720	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	59342	59342	✔
ISDYNCMM388MsgTimer_mS_M_u32	1329630720	1329630720	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	15953	15953	✔
ISDYNVOLMsgTimer_mS_M_u32	1329630720	1329630720	✔
IgnOnTimer_mS_M_u32	30106112	30106112	✔
IgnTimeOff_Sec_M_u32	1711699323	1711699323	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	205	205	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2110087680	2110087680	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	177	177	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3661922816	3661922816	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	168	168	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	244556288	244556288	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	60	60	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2729624064	2729624064	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2249761280	2249761280	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	86	86	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	174129664	174129664	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	236	236	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3991937536	3991937536	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3339436544	3339436544	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	83	83	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	831545856	831545856	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	195	195	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2039448064	2039448064	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	5	5	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1499374080	1499374080	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3288314368	3288314368	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	266.04361	266.04361	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	161.985703	161.985703	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	46.1164017	46.1164017	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	34332	34332	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1711699323	1711699323	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	628.079407	628.079407 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.353 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	134122752
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	35659
AASNodeAbsentTimer_mS_M_u32	468958464
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	31509
ANGLEVOLANTSigValidCount_Cnt_M_u16	34462
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	15924
AngleVolantMsgTimer_mS_M_u32	134122752
AngleVolantValidCount_Cnt_M_u16	41892
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	905739520
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2865822976
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1445113088
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1732144384
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	25728
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	98118912
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	18267
CAVNodeAbsentTimer_mS_M_u32	2581323008
CDD_SrlComVehSpd_Kph_G_f32	56.3277016
CMM388NTCEnableTimer_mS_M_u32	2578390272
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3671710976
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	8881
CMMNodeAbsentTimer_mS_M_u32	4072697088
CONSANGLECPKSigInvalidCount_Cnt_M_u16	20794
CONSANGLECPKSigValidCount_Cnt_M_u16	29394
CONSANGLECPK_Cnt_M_u16	60625
CONSANGLECPK_HwDeg_M_f32	-677.027893
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	60625
CPKVehicleSpeedMsgTimer_mS_M_u32	2948697344
CPKVehicleSpeedValidCount_Cnt_M_u16	35460
CityParkInputConsistentCount_Cnt_M_u16	57336
CityParkInputInvalidCount_Cnt_M_u16	8392
CityParkInputMsgTimer_mS_M_u32	2110087680
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1833417984
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	1439

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1360682240
ComputerRazGCTSigValidCount_Cnt_M_u16	48313
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	20596
DMDFCTCPKSigValidCount_Cnt_M_u16	30405
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	5183
DMDRELAXECPKSigValidCount_Cnt_M_u16	35656
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	55587
DateInvalidTimer_mS_M_u32	2865822976
DiagMuxOnAbsentTimer_mS_M_u32	1777945856
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1732144384
ESPNTCEnableTimer_mS_M_u32	2096151808
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	65221
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8976
EffacDefaultDiagTimer_mS_M_u32[1]	15234
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	963
ElecIntTimer_mS_M_u32[1]	7854
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3756207360
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	8773
EtatMTSigValidCount_Cnt_M_u16	61706
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	62844
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	2499
ISDAT4V2BSI552MsgTimer_mS_M_u32	1528065280
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	17309
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	3721
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	61706
ISDATBSI3F2MsgTimer_mS_M_u32	2328841472
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	18258
ISDATBSI412MsgLenValidCount_Cnt_M_u16	35759
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	8773
ISDATBSI412MsgTimer_mS_M_u32	2530512128
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	57861
ISDATBSI432MsgLenValidCount_Cnt_M_u16	21785
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	39672
ISDATDIRASentFltAcc_Cnt_M_u16	1308
ISDATDIRASentTimer_mS_M_u32	2948697344
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	8743
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	41892
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	60767
ISDYN2CMMMsgTimer_mS_M_u32	2733817088
ISDYNAASChkSumInvalidCount_Cnt_M_u16	117
ISDYNAASChkSumValidCount_Cnt_M_u16	64669
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	44687
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	1178
ISDYNAASMsgLenValidCount_Cnt_M_u16	6234
ISDYNAASMsgTimeValidCount_Cnt_M_u16	117
ISDYNAASMsgTimer_mS_M_u32	3126533376
ISDYNABRChkSumInvalidCount_Cnt_M_u16	54997
ISDYNABRChkSumValidCount_Cnt_M_u16	23686
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	13280
ISDYNABRMsgCountValidCount_Cnt_M_u16	31304
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	15269
ISDYNABRMsgLenValidCount_Cnt_M_u16	59261
ISDYNABRMsgTimeValidCount_Cnt_M_u16	60625
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	20129
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	40396
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	61706
ISDYNCMM208MsgTimer_mS_M_u32	2247982336
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	20129
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	40396
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	56698

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	116432128
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	18960
ISDYNVOLChkSumValidCount_Cnt_M_u16	32808
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	16458
ISDYNVOLMsgCountValidCount_Cnt_M_u16	47899
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	24154
ISDYNVOLMsgLenValidCount_Cnt_M_u16	28499
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	8881
ISDYNVOLMsgTimer_mS_M_u32	1841716480
IgnOnTimer_mS_M_u32	2655296768
IgnTimeOff_Sec_M_u32	2117324977
ManVehSpd_Kph_M_f32	157.450607
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	118
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	215
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2553105664
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	33
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	418229504
PrevISDATBSI412MsgDLCError_Cnt_M_u08	81
PrevISDATBSI412MsgRxTime_MSec_M_u32	1496898816
PrevISDATBSI432MsgDLCError_Cnt_M_u08	143
PrevISDATBSI432MsgRxTime_MSec_M_u32	3488922880
PrevISDATDIRAMsgTxTime_MSec_M_u32	3596410112
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	8
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3736988928
PrevISDYNAASMsgDLCError_Cnt_M_u08	153
PrevISDYNAASMsgRxTime_MSec_M_u32	3407633664
PrevISDYNABRMsgDLCError_Cnt_M_u08	10
PrevISDYNABRMsgRxTime_MSec_M_u32	647798016
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	89
PrevISDYNCMM208MsgRxTime_MSec_M_u32	849173760
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	69
PrevISDYNCMM388MsgRxTime_MSec_M_u32	317963520
PrevISDYNVOLMsgDLCError_Cnt_M_u08	40
PrevISDYNVOLMsgRxTime_MSec_M_u32	456252672
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1823116544
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	577.751282
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	25200
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	19120
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	41349
VitesseVehicleBVRampValidCount_Cnt_M_u16	8069
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	46506
VitesseVehicleBVSigValidCount_Cnt_M_u16	63219
VitesseVehicleBV_Kph_M_f32	128.468002
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	56698
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	12443
VitesseVehiculeRoues_Kph_M_f32	274.815186
k_AASNTCEnableTimeout_mS_u16	16852
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	31035
k_AASNodeTimeout_mS_u16	49584
k_ABSNodeTimeout_mS_u16	9525
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	33756
k_ANGLEVOLANTSigValidThresh_Cnt_u16	31280
k_AngleVolantInvalidThresh_Cnt_u16	22595
k_AngleVolantValidThresh_Cnt_u16	8392
k_BSI552MsgTimeout_mS_u16	29806
k_BSINTCEnableTimeout_mS_u16	6749
k_BSINodeAbsentDiag_Cnt_str.Threshold	61507
k_BSINodeAbsentDiag_Cnt_str.PStep	8212
k_BSINodeAbsentDiag_Cnt_str.NStep	43753
k_BSINodeAbsentTimeout_mS_u16	8332
k_BSINodeTimeout_mS_u16	39672
k_BattOvHi_Volt_f32	18.8565998
k_BattOvLo_Volt_f32	2.46070004
k_BattUvHi_Volt_f32	11.0819998
k_BattUvLo_Volt_f32	26.5765991
k_CAVNTCEnableTimeout_mS_u16	1782
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	46129
k_CAVNodeTimeout_mS_u16	35302
k_CMM388MsgTimeout_mS_u16	16971
k_CMM388NTCEnableTimeout_mS_u16	2039
k_CMMNTCEnableTimeout_mS_u16	26613
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	29767
k_CONSANGLECPKMax_HwDeg_f32	83.4918976
k_CONSANGLECPKMin_HwDeg_f32	-278.828888
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	5242
k_CONSANGLECPKSigValidThresh_Cnt_u16	42907
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	25518
k_CPKVehicleSpeedValidThresh_Cnt_u16	25425
k_CityParkInputInvalidThresh_Cnt_u16	9043
k_CityParkInputValidThresh_Cnt_u16	57336
k_ComputerRazGCTSigValidThresh_Cnt_u16	53627
k_CptTemporelSigValidThresh_Cnt_u16	59111
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	62117
k_DMDFCTCPKSigValidThresh_Cnt_u16	56957
k_DMDFCTCPKValidCount_Cnt_u16	2344
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	60767
k_DMDRELAXECPKSigValidThresh_Cnt_u16	32240
k_DMDRelaxeConsistentThresh_Cnt_u16	49646
k_DateValidThresh_Cnt_u16	2499
k_DefaultVehSpd_Kph_f32	122.051498
k_DiagMuxOnAbsentTimeout_mS_u16	36479
k_EMNodeTimeout_mS_u16	39171
k_ESPNTCEnableTimeout_mS_u16	31239
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	41967
k_EtatMTSigInvalidThresh_Cnt_u16	13128
k_EtatMTSigValidThresh_Cnt_u16	14649
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	52749
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	47666
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	35085
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	49446
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	53458
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	46246
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	4878
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	27362
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	57689
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	6661
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	26114
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	65179
k_ISDATDIRASentDiag_Cnt_str.Threshold	14294

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	34147
k_ISDATDIRASentDiag_Cnt_str.NStep	18148
k_ISDATDIRASentTimeout_mS_u16	21889
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	23452
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	15924
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	4099
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	3541
k_ISDYNAASChkSumValidThresh_Cnt_u16	54150
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	60128
k_ISDYNAASMsgCountValidThresh_Cnt_u16	29000
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	53033
k_ISDYNAASMsgLenValidThresh_Cnt_u16	30212
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	36824
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	13179
k_ISDYNABRChkSumValidThresh_Cnt_u16	13267
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	7040
k_ISDYNABRMsgCountValidThresh_Cnt_u16	12617
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	39345
k_ISDYNABRMsgLenValidThresh_Cnt_u16	46533
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	17564
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	14020
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	11431
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	4227
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	12821
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	32158
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	63264
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	57257
k_ISDYNVOLChkSumValidThresh_Cnt_u16	34630
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	17582
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	43994
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	17905
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	48566
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	1649
k_IgnOnTimeout_mS_u16	33365
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	6.59490013
k_PowerCutVehSpdLowThresh_Kph_f32	77.7590027
k_PowerCutVehSpdLowTimeout_mS_u16	4784
k_VBattMaxAAS_Volt_f32	3.48939991
k_VBattMaxBSI_Volt_f32	20.5534
k_VBattMaxCAV_Volt_f32	13.7645998
k_VBattMaxCMM388_Volt_f32	0.209299996
k_VBattMaxCMM_Volt_f32	8.87940025
k_VBattMaxESP_Volt_f32	23.4004002
k_VBattMinAAS_Volt_f32	8.4364996
k_VBattMinBSI_Volt_f32	23.4004002
k_VBattMinCAV_Volt_f32	20.9776001
k_VBattMinCMM388_Volt_f32	0.183500007
k_VBattMinCMM_Volt_f32	27.1924992
k_VBattMinESP_Volt_f32	8.87940025
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	55454
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	27051
k_VitesseVehicleBVRampValidThresh_Cnt_u16	30538
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	30504
k_VitesseVehicleBVSigValidThresh_Cnt_u16	26469
k_VitesseVehicleBVSpeedPassThresh_kph_f32	638.214722
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	32347
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	4315
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2865822976
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	38937
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1368725760
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	69
target_SrlComInput_Per1_Batt_Volt_f32.value	10.3989
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	861285632
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	159
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.954369545
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2455149824
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	193
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3780721920
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3907771648
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	286162176
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3250658560
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	101
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1661189376
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1557552384
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	118
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	119
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	167
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1208188160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	37
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	130
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	194
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	236
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	1
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1660263680
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	120
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4017634560
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4102741248
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	50
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	155
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1290251520
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3079
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.377546996
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	785565
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	184.6987
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	4850

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1368725760	1368725760	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1368725760	1368725760	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1368725760	1368725760	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1368725760	1368725760	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1368725760	1368725760	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1368725760	1368725760	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1368725760	1368725760	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1368725760	1368725760	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1368725760	1368725760	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1368725760	1368725760	✔
CDD_SrlComVehSpd_Kph_G_f32	157.450607	157.450607	✔
CMM388NTCEnableTimer_mS_M_u32	1368725760	1368725760	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1368725760	1368725760	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1368725760	1368725760	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	60625	60625	✔
CONSANGLECPK_HwDeg_M_f32	-677.027893	-677.027893 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1368725760	1368725760	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1368725760	1368725760	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1368725760	1368725760	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1368725760	1368725760	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1368725760	1368725760	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1368725760	1368725760	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1368725760	1368725760	✔
ESPNTCEnableTimer_mS_M_u32	1368725760	1368725760	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1368725760	1368725760	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	8976	8976	✔
EffacDefaultDiagTimer_mS_M_u32[1]	15234	15234	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	963	963	✔
ElecIntTimer_mS_M_u32[1]	7854	7854	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1368725760	1368725760	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	2499	2499	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1368725760	1368725760	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	61706	61706	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1368725760	1368725760	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	8773	8773	✔
ISDATBSI412MsgTimer_mS_M_u32	1368725760	1368725760	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	39672	39672	✔
ISDATBSI432MsgTimer_mS_M_u32	1368725760	1368725760	✔
ISDATDIRASentFltAcc_Cnt_M_u16	14294	14294	✔
ISDATDIRASentTimer_mS_M_u32	1368725760	1368725760	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	60767	60767	✔
ISDYN2CMMMsgTimer_mS_M_u32	1368725760	1368725760	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	117	117	✔
ISDYNAASMsgTimer_mS_M_u32	1368725760	1368725760	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	60625	60625	✔
ISDYNABRMsgTimer_mS_M_u32	1368725760	1368725760	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	61706	61706	✔
ISDYNCMM208MsgTimer_mS_M_u32	1368725760	1368725760	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	56698	56698	✔
ISDYNCMM388MsgTimer_mS_M_u32	1368725760	1368725760	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	8881	8881	✔
ISDYNVOLMsgTimer_mS_M_u32	1368725760	1368725760	✔
IgnOnTimer_mS_M_u32	2655296768	2655296768	✔
IgnTimeOff_Sec_M_u32	2117324977	2117324977	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	167	167	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2455149824	2455149824	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	193	193	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3780721920	3780721920	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	223	223	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3907771648	3907771648	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	106	106	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	286162176	286162176	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3596410112	3596410112	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	101	101	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1661189376	1661189376	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	166	166	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1557552384	1557552384	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	95	95	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1208188160	1208188160	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	1	1	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1660263680	1660263680	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	120	120	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4017634560	4017634560	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	180	180	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4102741248	4102741248	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1290251520	1290251520	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	577.751282	577.751282	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	128.468002	128.468002	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	274.815186	274.815186	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	60625	60625	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2117324977	2117324977	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-677.027893	-677.027893 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	157.450607	157.450607	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.354 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2719423488
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	59953
AASNodeAbsentTimer_mS_M_u32	4143418368
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	25810
ANGLEVOLANTSigValidCount_Cnt_M_u16	33016
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	46454
AngleVolantMsgTimer_mS_M_u32	2719423488
AngleVolantValidCount_Cnt_M_u16	36772
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3151842304
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1331678208
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	4029332480
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3688332288
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	5265
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3674684416
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	40577
CAVNodeAbsentTimer_mS_M_u32	3317640192
CDD_SrlComVehSpd_Kph_G_f32	254.877304
CMM388NTCEnableTimer_mS_M_u32	591752192
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2059742208
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	4159
CMMNodeAbsentTimer_mS_M_u32	3243342848
CONSANGLECPKSigInvalidCount_Cnt_M_u16	25955
CONSANGLECPKSigValidCount_Cnt_M_u16	32601
CONSANGLECPK_Cnt_M_u16	52572
CONSANGLECPK_HwDeg_M_f32	83.8050003
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	52572
CPKVehicleSpeedMsgTimer_mS_M_u32	1993219072
CPKVehicleSpeedValidCount_Cnt_M_u16	65036
CityParkInputConsistentCount_Cnt_M_u16	10920
CityParkInputInvalidCount_Cnt_M_u16	63799
CityParkInputMsgTimer_mS_M_u32	2455149824
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1392217088
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	52021

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3120802816
ComputerRazGCTSigValidCount_Cnt_M_u16	55397
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	6707
DMDFCTCPKSigValidCount_Cnt_M_u16	1537
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	49492
DMDRELAXECPKSigValidCount_Cnt_M_u16	39674
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	45480
DateInvalidTimer_mS_M_u32	1331678208
DiagMuxOnAbsentTimer_mS_M_u32	3609648128
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3688332288
ESPNTCEnableTimer_mS_M_u32	134253568
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	60097
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	97
EffacDefaultDiagTimer_mS_M_u32[1]	977
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	89
ElecIntTimer_mS_M_u32[1]	900
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	4108925952
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	45698
EtatMTSigValidCount_Cnt_M_u16	29940
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	65535
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	8027
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	50439
ISDAT4V2BSI552MsgTimer_mS_M_u32	3629480960
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1531
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	29684
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	29940
ISDATBSI3F2MsgTimer_mS_M_u32	1285872640
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	24539
ISDATBSI412MsgLenValidCount_Cnt_M_u16	8581
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	45698
ISDATBSI412MsgTimer_mS_M_u32	3449101312
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	8771
ISDATBSI432MsgLenValidCount_Cnt_M_u16	14277
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	22442
ISDATDIRASentFltAcc_Cnt_M_u16	43326
ISDATDIRASentTimer_mS_M_u32	1993219072
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	1370
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	36772
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	44914
ISDYN2CMMMsgTimer_mS_M_u32	502959104
ISDYNAASChkSumInvalidCount_Cnt_M_u16	45747
ISDYNAASChkSumValidCount_Cnt_M_u16	31993
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	56035
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	8900
ISDYNAASMsgLenValidCount_Cnt_M_u16	1602
ISDYNAASMsgTimeValidCount_Cnt_M_u16	45747
ISDYNAASMsgTimer_mS_M_u32	1900112896
ISDYNABRChkSumInvalidCount_Cnt_M_u16	43282
ISDYNABRChkSumValidCount_Cnt_M_u16	63168
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	33906
ISDYNABRMsgCountValidCount_Cnt_M_u16	28664
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	4642
ISDYNABRMsgLenValidCount_Cnt_M_u16	36184
ISDYNABRMsgTimeValidCount_Cnt_M_u16	52572
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	8116
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	29625
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	29940
ISDYNCMM208MsgTimer_mS_M_u32	265964544
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	8116
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	29625
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	47650

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3246451712
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	21217
ISDYNVOLChkSumValidCount_Cnt_M_u16	12119
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	8881
ISDYNVOLMsgCountValidCount_Cnt_M_u16	4351
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	24578
ISDYNVOLMsgLenValidCount_Cnt_M_u16	11224
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	4159
ISDYNVOLMsgTimer_mS_M_u32	335522816
IgnOnTimer_mS_M_u32	1267002368
IgnTimeOff_Sec_M_u32	771946130
ManVehSpd_Kph_M_f32	281.601593
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	119
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	129
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	478862336
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	253
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2479471616
PrevISDATBSI412MsgDLCError_Cnt_M_u08	164
PrevISDATBSI412MsgRxTime_MSec_M_u32	1000877056
PrevISDATBSI432MsgDLCError_Cnt_M_u08	99
PrevISDATBSI432MsgRxTime_MSec_M_u32	519343104
PrevISDATDIRAMsgTxTime_MSec_M_u32	1413229568
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	154
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3545824256
PrevISDYNAASMsgDLCError_Cnt_M_u08	60
PrevISDYNAASMsgRxTime_MSec_M_u32	3556617216
PrevISDYNABRMsgDLCError_Cnt_M_u08	143
PrevISDYNABRMsgRxTime_MSec_M_u32	310176768
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	192
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3782913024
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	39
PrevISDYNCMM388MsgRxTime_MSec_M_u32	301435904
PrevISDYNVOLMsgDLCError_Cnt_M_u08	51
PrevISDYNVOLMsgRxTime_MSec_M_u32	431827968
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	605232128
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	90.4568024
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57666
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	18240
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	47107
VitesseVehicleBVRampValidCount_Cnt_M_u16	23745
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	18707
VitesseVehicleBVSigValidCount_Cnt_M_u16	50169
VitesseVehicleBV_Kph_M_f32	440.977692
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	47650
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	24448
VitesseVehiculeRoues_Kph_M_f32	605.717407
k_AASNTCEnableTimeout_mS_u16	39507
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	10975
k_AASNodeTimeout_mS_u16	57920
k_ABSNodeTimeout_mS_u16	57328
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	22718
k_ANGLEVOLANTSigValidThresh_Cnt_u16	58496
k_AngleVolantInvalidThresh_Cnt_u16	22087
k_AngleVolantValidThresh_Cnt_u16	63799
k_BSI552MsgTimeout_mS_u16	40967
k_BSINTCEnableTimeout_mS_u16	55611
k_BSINodeAbsentDiag_Cnt_str.Threshold	50537
k_BSINodeAbsentDiag_Cnt_str.PStep	18497
k_BSINodeAbsentDiag_Cnt_str.NStep	40508
k_BSINodeAbsentTimeout_mS_u16	28270
k_BSINodeTimeout_mS_u16	22442
k_BattOvHi_Volt_f32	27.2604008
k_BattOvLo_Volt_f32	13.9552002
k_BattUvHi_Volt_f32	12.3078003
k_BattUvLo_Volt_f32	8.32159996
k_CAVNTCEnableTimeout_mS_u16	32429
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	12287
k_CAVNodeTimeout_mS_u16	27487
k_CMM388MsgTimeout_mS_u16	50481
k_CMM388NTCEnableTimeout_mS_u16	9261
k_CMMNTCEnableTimeout_mS_u16	63731
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	17532
k_CONSANGLECPKMax_HwDeg_f32	213.466599
k_CONSANGLECPKMin_HwDeg_f32	-456.634491
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	5410
k_CONSANGLECPKSigValidThresh_Cnt_u16	64128
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	29766
k_CPKVehicleSpeedValidThresh_Cnt_u16	51166
k_CityParkInputInvalidThresh_Cnt_u16	15256
k_CityParkInputValidThresh_Cnt_u16	10920
k_ComputerRazGCTSigValidThresh_Cnt_u16	21601
k_CptTemporelSigValidThresh_Cnt_u16	58074
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	60706
k_DMDFCTCPKSigValidThresh_Cnt_u16	43096
k_DMDFCTCPKValidCount_Cnt_u16	50841
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	44914
k_DMDRELAXECPKSigValidThresh_Cnt_u16	23680
k_DMDRelaxeConsistentThresh_Cnt_u16	2182
k_DateValidThresh_Cnt_u16	50439
k_DefaultVehSpd_Kph_f32	78.4188995
k_DiagMuxOnAbsentTimeout_mS_u16	8274
k_EMNodeTimeout_mS_u16	61960
k_ESPNTCEnableTimeout_mS_u16	46717
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	21892
k_EtatMTSigInvalidThresh_Cnt_u16	8121
k_EtatMTSigValidThresh_Cnt_u16	60583
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	28969
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	23419
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	50025
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	61792
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	37145
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	26591
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	62248
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	23146
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	29767
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	5568
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	16522
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	61183
k_ISDATDIRASentDiag_Cnt_str.Threshold	6491

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	58700
k_ISDATDIRASentDiag_Cnt_str.NStep	43168
k_ISDATDIRASentTimeout_mS_u16	56590
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	7164
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	46454
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	58505
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	1042
k_ISDYNAASChkSumValidThresh_Cnt_u16	37312
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	24434
k_ISDYNAASMsgCountValidThresh_Cnt_u16	35576
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	4118
k_ISDYNAASMsgLenValidThresh_Cnt_u16	5444
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	17288
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	672
k_ISDYNABRChkSumValidThresh_Cnt_u16	32854
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	61329
k_ISDYNABRMsgCountValidThresh_Cnt_u16	60663
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	43839
k_ISDYNABRMsgLenValidThresh_Cnt_u16	50625
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	48894
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	46150
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	17372
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	455
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	16338
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	39928
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	54831
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	45782
k_ISDYNVOLChkSumValidThresh_Cnt_u16	19136
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	64774
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	22724
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	63358
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	48880
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	1789
k_IgnOnTimeout_mS_u16	31442
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	61.2885017
k_PowerCutVehSpdLowThresh_Kph_f32	143.796295
k_PowerCutVehSpdLowTimeout_mS_u16	38847
k_VBattMaxAAS_Volt_f32	3.78550005
k_VBattMaxBSI_Volt_f32	23.8141003
k_VBattMaxCAV_Volt_f32	22.9433002
k_VBattMaxCMM388_Volt_f32	31.7047005
k_VBattMaxCMM_Volt_f32	6.30679989
k_VBattMaxESP_Volt_f32	4.4770999
k_VBattMinAAS_Volt_f32	9.40799999
k_VBattMinBSI_Volt_f32	4.4770999
k_VBattMinCAV_Volt_f32	32
k_VBattMinCMM388_Volt_f32	8.93350029
k_VBattMinCMM_Volt_f32	29.5813999
k_VBattMinESP_Volt_f32	6.30679989
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	11510
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	51344
k_VitesseVehicleBVRampValidThresh_Cnt_u16	32177
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	19031
k_VitesseVehicleBVSigValidThresh_Cnt_u16	34913
k_VitesseVehicleBVSpeedPassThresh_kph_f32	384.015686
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	63873
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	24767
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1331678208
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	24687
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	511932416
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	39
target_SrlComInput_Per1_Batt_Volt_f32.value	0.25
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2257599488
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	178
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.404002458
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	230
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	927919104
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	482806784
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	412036096
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4071050240
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1930390528
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1640467456
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	217
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2261756928
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	9
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	47
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	151
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	183
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	234
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	236
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	171
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1640516608
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	32
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	46
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	166
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	202
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	24243200
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	97
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	778701824
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	160
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	833760256
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	84
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	188
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	203
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1608236032
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2049
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0482092053
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	45329
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	133.227203
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	22460

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	511932416	511932416	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	511932416	511932416	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	46454	46454	✔
AngleVolantMsgTimer_mS_M_u32	511932416	511932416	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	511932416	511932416	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	511932416	511932416	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	511932416	511932416	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	511932416	511932416	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	511932416	511932416	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	511932416	511932416	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	511932416	511932416	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	511932416	511932416	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	511932416	511932416	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	511932416	511932416	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	52572	52572	✔
CONSANGLECPK_HwDeg_M_f32	83.8050003	83.8050003 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	52572	52572	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1993219072	1993219072	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	65036	65036	✔
CityParkInputConsistentCount_Cnt_M_u16	10920	10920	✔
CityParkInputInvalidCount_Cnt_M_u16	63799	63799	✔
CityParkInputMsgTimer_mS_M_u32	511932416	511932416	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	511932416	511932416	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	511932416	511932416	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	511932416	511932416	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	511932416	511932416	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	511932416	511932416	✔
ESPNTCEnableTimer_mS_M_u32	511932416	511932416	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	511932416	511932416	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	511932416	511932416	✔
EffacDefaultDiagTimer_mS_M_u32[1]	977	977	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	511932416	511932416	✔
ElecIntTimer_mS_M_u32[1]	900	900	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	511932416	511932416	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	511932416	511932416	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	511932416	511932416	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	511932416	511932416	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	511932416	511932416	✔
ISDATDIRASentFltAcc_Cnt_M_u16	6491	6491	✔
ISDATDIRASentTimer_mS_M_u32	511932416	511932416	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	511932416	511932416	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	511932416	511932416	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	511932416	511932416	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	511932416	511932416	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	511932416	511932416	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	511932416	511932416	✔
IgnOnTimer_mS_M_u32	1267002368	1267002368	✔
IgnTimeOff_Sec_M_u32	771946130	771946130	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	15	15	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	230	230	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	927919104	927919104	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	75	75	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	482806784	482806784	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	227	227	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	412036096	412036096	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	117	117	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4071050240	4071050240	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1413229568	1413229568	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	168	168	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1640467456	1640467456	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	217	217	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2261756928	2261756928	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	171	171	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1640516608	1640516608	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	24243200	24243200	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	97	97	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	778701824	778701824	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	160	160	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	833760256	833760256	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1608236032	1608236032	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	90.4568024	90.4568024	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	440.977692	440.977692	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	605.717407	605.717407	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	52572	52572	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	771946130	771946130	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	83.8050003	83.8050003 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	78.4188995	78.4188995	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.355 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2898882304
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	24185
AASNodeAbsentTimer_mS_M_u32	4226293504
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	4248
ANGLEVOLANTSigValidCount_Cnt_M_u16	65510
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	20650
AngleVolantMsgTimer_mS_M_u32	2898882304
AngleVolantValidCount_Cnt_M_u16	41632
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1949753088
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3819921152
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	420384512
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	4178071296
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	48475
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1786318592
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	34827
CAVNodeAbsentTimer_mS_M_u32	3054583552
CDD_SrlComVehSpd_Kph_G_f32	428.337006
CMM388NTCEnableTimer_mS_M_u32	2256436992
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	788479744
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	10128
CMMNodeAbsentTimer_mS_M_u32	2962902784
CONSANGLECPKSigInvalidCount_Cnt_M_u16	34275
CONSANGLECPKSigValidCount_Cnt_M_u16	48065
CONSANGLECPK_Cnt_M_u16	40376
CONSANGLECPK_HwDeg_M_f32	532.961121
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	40376
CPKVehicleSpeedMsgTimer_mS_M_u32	3399773952
CPKVehicleSpeedValidCount_Cnt_M_u16	3665
CityParkInputConsistentCount_Cnt_M_u16	57748

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	49894
CityParkInputMsgTimer_mS_M_u32	927919104
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4158398208
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	52077
ComputerRazGCTSigInvalidTimer_mS_M_u32	2336472832
ComputerRazGCTSigValidCount_Cnt_M_u16	3165
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	20466
DMDFCTCPKSigValidCount_Cnt_M_u16	28744
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	33554
DMDRELAXECPKSigValidCount_Cnt_M_u16	14816
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	62740
DateInvalidTimer_mS_M_u32	3819921152
DiagMuxOnAbsentTimer_mS_M_u32	4237963008
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4178071296
ESPNTCEnableTimer_mS_M_u32	751640320
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	19402
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	4
EffacDefaultDiagTimer_mS_M_u32[1]	6
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	750
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	617811712
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	24006
EtatMTSigValidCount_Cnt_M_u16	35376
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	9007
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	25531
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	52022
ISDAT4V2BSI552MsgTimer_mS_M_u32	2072923904
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	15581
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	34479
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	35376
ISDATBSI3F2MsgTimer_mS_M_u32	337653504
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	60
ISDATBSI412MsgLenValidCount_Cnt_M_u16	3839
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	24006
ISDATBSI412MsgTimer_mS_M_u32	2723114752
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	388
ISDATBSI432MsgLenValidCount_Cnt_M_u16	29886
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	16528
ISDATDIRASentFltAcc_Cnt_M_u16	39892
ISDATDIRASentTimer_mS_M_u32	3399773952
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	28094
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	41632
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	19509
ISDYN2CMMMsgTimer_mS_M_u32	1390354176
ISDYNAASChkSumInvalidCount_Cnt_M_u16	36083
ISDYNAASChkSumValidCount_Cnt_M_u16	61922
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	31971
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	51010
ISDYNAASMsgLenValidCount_Cnt_M_u16	49288
ISDYNAASMsgTimeValidCount_Cnt_M_u16	36083
ISDYNAASMsgTimer_mS_M_u32	2357886720
ISDYNABRChkSumInvalidCount_Cnt_M_u16	15703
ISDYNABRChkSumValidCount_Cnt_M_u16	47117
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	54198
ISDYNABRMsgCountValidCount_Cnt_M_u16	54501
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	15270
ISDYNABRMsgLenValidCount_Cnt_M_u16	19908
ISDYNABRMsgTimeValidCount_Cnt_M_u16	40376
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	13877

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	26855
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	35376
ISDYNCMM208MsgTimer_mS_M_u32	2889867008
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	13877
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	26855
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	39718
ISDYNCMM388MsgTimer_mS_M_u32	4190895872
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	13673
ISDYNVOLChkSumValidCount_Cnt_M_u16	9159
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	44664
ISDYNVOLMsgCountValidCount_Cnt_M_u16	51022
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	12295
ISDYNVOLMsgLenValidCount_Cnt_M_u16	53317
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	10128
ISDYNVOLMsgTimer_mS_M_u32	1833942784
IgnOnTimer_mS_M_u32	1807744768
IgnTimeOff_Sec_M_u32	1013097328
ManVehSpd_Kph_M_f32	14.2256002
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	120
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	41
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3161337600
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	162
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1781632768
PrevISDATBSI412MsgDLCError_Cnt_M_u08	7
PrevISDATBSI412MsgRxTime_MSec_M_u32	945176320
PrevISDATBSI432MsgDLCError_Cnt_M_u08	97
PrevISDATBSI432MsgRxTime_MSec_M_u32	3086032640
PrevISDATDIRAMsgTxTime_MSec_M_u32	1050296064
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	216
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4169387776
PrevISDYNAASMsgDLCError_Cnt_M_u08	242
PrevISDYNAASMsgRxTime_MSec_M_u32	2773860096
PrevISDYNABRMsgDLCError_Cnt_M_u08	7
PrevISDYNABRMsgRxTime_MSec_M_u32	4141350656
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	19
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2967387904
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	98
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2867339008
PrevISDYNVOLMsgDLCError_Cnt_M_u08	29
PrevISDYNVOLMsgRxTime_MSec_M_u32	840384256
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	383086336
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	3.74810004
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	968
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	30094
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	50053
VitesseVehicleBVRampValidCount_Cnt_M_u16	30987
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	42965
VitesseVehicleBVSigValidCount_Cnt_M_u16	31459

Name	Input Value
VitesseVehicleBV_Kph_M_f32	631.49292
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	39718
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	52940
VitesseVehiculeRoues_Kph_M_f32	294.949097
k_AASNTCEnableTimeout_mS_u16	53971
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	31983
k_AASNodeTimeout_mS_u16	42126
k_ABSNodeTimeout_mS_u16	12987
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	2579
k_ANGLEVOLANTSigValidThresh_Cnt_u16	6797
k_AngleVolantInvalidThresh_Cnt_u16	41272
k_AngleVolantValidThresh_Cnt_u16	49894
k_BSI552MsgTimeout_mS_u16	59703
k_BSINTCEnableTimeout_mS_u16	48284
k_BSINodeAbsentDiag_Cnt_str.Threshold	21141
k_BSINodeAbsentDiag_Cnt_str.PStep	2895
k_BSINodeAbsentDiag_Cnt_str.NStep	55965
k_BSINodeAbsentTimeout_mS_u16	1474
k_BSINodeTimeout_mS_u16	16528
k_BattOvHi_Volt_f32	16.2656002
k_BattOvLo_Volt_f32	16.1592007
k_BattUvHi_Volt_f32	13.4525995
k_BattUvLo_Volt_f32	27.9183998
k_CAVNTCEnableTimeout_mS_u16	35460
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	19345
k_CAVNodeTimeout_mS_u16	25583
k_CMM388MsgTimeout_mS_u16	52601
k_CMM388NTCEnableTimeout_mS_u16	41093
k_CMMNTCEnableTimeout_mS_u16	17397
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	4056
k_CONSANGLECPKMax_HwDeg_f32	119.420601
k_CONSANGLECPKMin_HwDeg_f32	-393.085602
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	35366
k_CONSANGLECPKSigValidThresh_Cnt_u16	64972
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	34428
k_CPKVehicleSpeedValidThresh_Cnt_u16	37939
k_CityParkInputInvalidThresh_Cnt_u16	7621
k_CityParkInputValidThresh_Cnt_u16	57748
k_ComputerRazGCTSigValidThresh_Cnt_u16	27051
k_CptTemporelSigValidThresh_Cnt_u16	20989
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	43686
k_DMDFCTCPKSigValidThresh_Cnt_u16	64708
k_DMDFCTCPKValidCount_Cnt_u16	51011
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	19509
k_DMDRELAXECPKSigValidThresh_Cnt_u16	10443
k_DMDRelaxeConsistentThresh_Cnt_u16	48313
k_DateValidThresh_Cnt_u16	52022
k_DefaultVehSpd_Kph_f32	160.300995
k_DiagMuxOnAbsentTimeout_mS_u16	64726
k_EMNodeTimeout_mS_u16	46068
k_ESPNTCEnableTimeout_mS_u16	12311
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	64704
k_EtatMTSigInvalidThresh_Cnt_u16	13666
k_EtatMTSigValidThresh_Cnt_u16	12888
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	56275
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	4253
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	23377
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	20142
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	832
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	63536
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	25301

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	57551
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	7032
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	21644
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	42990
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	13264
k_ISDATDIRASentDiag_Cnt_str.Threshold	25239
k_ISDATDIRASentDiag_Cnt_str.PStep	16638
k_ISDATDIRASentDiag_Cnt_str.NStep	16248
k_ISDATDIRASentTimeout_mS_u16	37219
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	57561
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	20650
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	54771
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	11351
k_ISDYNAASChkSumValidThresh_Cnt_u16	59149
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	17078
k_ISDYNAASMsgCountValidThresh_Cnt_u16	33765
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	6219
k_ISDYNAASMsgLenValidThresh_Cnt_u16	7042
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	7541
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	57900
k_ISDYNABRChkSumValidThresh_Cnt_u16	60618
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	11355
k_ISDYNABRMsgCountValidThresh_Cnt_u16	30697
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	22160
k_ISDYNABRMsgLenValidThresh_Cnt_u16	47818
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	56788
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	39612
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	38969
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	8697
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	32664
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	44774
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	3070
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	45899
k_ISDYNVOLChkSumValidThresh_Cnt_u16	16206
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	26875
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	41473
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	32466
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	39996
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	23892
k_IgnOnTimeout_mS_u16	19287
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	22.1921005
k_PowerCutVehSpdLowThresh_Kph_f32	166.668701
k_PowerCutVehSpdLowTimeout_mS_u16	35471
k_VBattMaxAAS_Volt_f32	3.7974999
k_VBattMaxBSI_Volt_f32	27.0494995
k_VBattMaxCAV_Volt_f32	27.3738995
k_VBattMaxCMM388_Volt_f32	30.8026009
k_VBattMaxCMM_Volt_f32	6.15920019
k_VBattMaxESP_Volt_f32	18.4482994
k_VBattMinAAS_Volt_f32	24.5384007
k_VBattMinBSI_Volt_f32	18.4482994
k_VBattMinCAV_Volt_f32	6.63320017
k_VBattMinCMM388_Volt_f32	2.66190004
k_VBattMinCMM_Volt_f32	31.6938
k_VBattMinESP_Volt_f32	6.15920019
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	5611
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	22237
k_VitesseVehicleBVRampValidThresh_Cnt_u16	40312
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	53959
k_VitesseVehicleBVSigValidThresh_Cnt_u16	60521
k_VitesseVehicleBVSpeedPassThresh_kph_f32	323.58371
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	30475
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	58641
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3819921152
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	50632
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3958659840
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	98
target_SrlComInput_Per1_Batt_Volt_f32.value	25.0697002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3420327680
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	243
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.698325157
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1348599552
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	47
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	679059200
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4255203072
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2010701568
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1059094272
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4218953472
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1423949568
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	39
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	130
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	131
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	242
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	101
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4000702208
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	18
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	88
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	111
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	252
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1039728384
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1066442496
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4265099008
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	22
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	124
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	173
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3455815424
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1090
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0657951236
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	380889
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	35.6259995

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	2138		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	3958659840	3958659840	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3958659840	3958659840	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3958659840	3958659840	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3958659840	3958659840	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3958659840	3958659840	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3958659840	3958659840	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3958659840	3958659840	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3958659840	3958659840	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3958659840	3958659840	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3958659840	3958659840	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3958659840	3958659840	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3958659840	3958659840	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3958659840	3958659840	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	40376	40376	✔
CONSANGLECPK_HwDeg_M_f32	532.961121	532.961121 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3958659840	3958659840	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3958659840	3958659840	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3958659840	3958659840	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3958659840	3958659840	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3958659840	3958659840	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3958659840	3958659840	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3958659840	3958659840	✔
ESPNTCEnableTimer_mS_M_u32	3958659840	3958659840	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3958659840	3958659840	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4	4	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	6	6	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4	4	✔
ElecIntTimer_mS_M_u32[1]	750	750	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3958659840	3958659840	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3958659840	3958659840	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3958659840	3958659840	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3958659840	3958659840	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3958659840	3958659840	✔
ISDATDIRASentFltAcc_Cnt_M_u16	25239	25239	✔
ISDATDIRASentTimer_mS_M_u32	3958659840	3958659840	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3958659840	3958659840	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3958659840	3958659840	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3958659840	3958659840	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3958659840	3958659840	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3958659840	3958659840	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3958659840	3958659840	✔
IgnOnTimer_mS_M_u32	3958659840	3958659840	✔
IgnTimeOff_Sec_M_u32	1013097328	1013097328	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	118	118	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1348599552	1348599552	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	47	47	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	679059200	679059200	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	144	144	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4255203072	4255203072	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	67	67	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2010701568	2010701568	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1050296064	1050296064	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	60	60	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4218953472	4218953472	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	210	210	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1423949568	1423949568	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	101	101	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4000702208	4000702208	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	55	55	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1039728384	1039728384	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	57	57	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1066442496	1066442496	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4265099008	4265099008	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3455815424	3455815424	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	3.74810004	3.74810004	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	631.49292	631.49292	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	294.949097	294.949097	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	40376	40376	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1013097328	1013097328	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	532.961121	532.961121 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.356 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4055791104
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	16044
AASNodeAbsentTimer_mS_M_u32	455239168
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	49745
ANGLEVOLANTSigValidCount_Cnt_M_u16	10534
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	27673
AngleVolantMsgTimer_mS_M_u32	4055791104
AngleVolantValidCount_Cnt_M_u16	54457
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1563829760
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2429330944
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2842629632
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	545379840
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	34824
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2133825024
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	61049
CAVNodeAbsentTimer_mS_M_u32	2032600576
CDD_SrlComVehSpd_Kph_G_f32	184.971405
CMM388NTCEnableTimer_mS_M_u32	1289700864
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1180501504
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	12713
CMMNodeAbsentTimer_mS_M_u32	3251361280
CONSANGLECPKSigInvalidCount_Cnt_M_u16	64881
CONSANGLECPKSigValidCount_Cnt_M_u16	53398
CONSANGLECPK_Cnt_M_u16	50865
CONSANGLECPK_HwDeg_M_f32	258.966187
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	50865
CPKVehicleSpeedMsgTimer_mS_M_u32	3291313664
CPKVehicleSpeedValidCount_Cnt_M_u16	3309
CityParkInputConsistentCount_Cnt_M_u16	59357

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	23782
CityParkInputMsgTimer_mS_M_u32	1348599552
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4148585984
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	51152
ComputerRazGCTSigInvalidTimer_mS_M_u32	3817833984
ComputerRazGCTSigValidCount_Cnt_M_u16	52098
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	58818
DMDFCTCPKSigValidCount_Cnt_M_u16	55679
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	53987
DMDRELAXECPKSigValidCount_Cnt_M_u16	58168
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	46046
DateInvalidTimer_mS_M_u32	2429330944
DiagMuxOnAbsentTimer_mS_M_u32	894187008
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	545379840
ESPNTCEnableTimer_mS_M_u32	1551066624
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	43450
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	19
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	45
ElecIntTimer_mS_M_u32[1]	100
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	941725184
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	14342
EtatMTSigValidCount_Cnt_M_u16	22407
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	17411
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	16552
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	181
ISDAT4V2BSI552MsgTimer_mS_M_u32	821024256
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	3649
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	30091
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	22407
ISDATBSI3F2MsgTimer_mS_M_u32	2260350464
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	20772
ISDATBSI412MsgLenValidCount_Cnt_M_u16	10653
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	14342
ISDATBSI412MsgTimer_mS_M_u32	2838263296
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	29645
ISDATBSI432MsgLenValidCount_Cnt_M_u16	65246
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	6378
ISDATDIRASentFltAcc_Cnt_M_u16	5918
ISDATDIRASentTimer_mS_M_u32	3291313664
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	61087
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	54457
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	48377
ISDYN2CMMMsgTimer_mS_M_u32	2990368256
ISDYNAASChkSumInvalidCount_Cnt_M_u16	6974
ISDYNAASChkSumValidCount_Cnt_M_u16	41268
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	4592
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	52436
ISDYNAASMsgLenValidCount_Cnt_M_u16	62914
ISDYNAASMsgTimeValidCount_Cnt_M_u16	6974
ISDYNAASMsgTimer_mS_M_u32	1790658048
ISDYNABRChkSumInvalidCount_Cnt_M_u16	20372
ISDYNABRChkSumValidCount_Cnt_M_u16	46130
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	4853
ISDYNABRMsgCountValidCount_Cnt_M_u16	50219
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	43048
ISDYNABRMsgLenValidCount_Cnt_M_u16	59021
ISDYNABRMsgTimeValidCount_Cnt_M_u16	50865
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	24237

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	14935
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	22407
ISDYNCMM208MsgTimer_mS_M_u32	421209600
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	24237
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	14935
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	33575
ISDYNCMM388MsgTimer_mS_M_u32	150390272
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	34527
ISDYNVOLChkSumValidCount_Cnt_M_u16	12420
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	25136
ISDYNVOLMsgCountValidCount_Cnt_M_u16	27757
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	12547
ISDYNVOLMsgLenValidCount_Cnt_M_u16	17673
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	12713
ISDYNVOLMsgTimer_mS_M_u32	1835763200
IgnOnTimer_mS_M_u32	2199569920
IgnTimeOff_Sec_M_u32	1920120761
ManVehSpd_Kph_M_f32	460.101593
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	121
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	43
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1171273216
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	252
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	33953280
PrevISDATBSI412MsgDLCError_Cnt_M_u08	192
PrevISDATBSI412MsgRxTime_MSec_M_u32	1180173824
PrevISDATBSI432MsgDLCError_Cnt_M_u08	228
PrevISDATBSI432MsgRxTime_MSec_M_u32	1258776064
PrevISDATDIRAMsgTxTime_MSec_M_u32	1133250048
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	48
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1880053248
PrevISDYNAASMsgDLCError_Cnt_M_u08	226
PrevISDYNAASMsgRxTime_MSec_M_u32	1566148096
PrevISDYNABRMsgDLCError_Cnt_M_u08	118
PrevISDYNABRMsgRxTime_MSec_M_u32	1104332288
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	115
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2663286272
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	252
PrevISDYNCMM388MsgRxTime_MSec_M_u32	237135360
PrevISDYNVOLMsgDLCError_Cnt_M_u08	52
PrevISDYNVOLMsgRxTime_MSec_M_u32	2635400704
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3818550784
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	274.249695
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	44866
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	28336
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	41995
VitesseVehicleBVRampValidCount_Cnt_M_u16	38969
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	12442
VitesseVehicleBVSigValidCount_Cnt_M_u16	60463

Name	Input Value
VitesseVehicleBV_Kph_M_f32	572.833008
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	33575
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	31988
VitesseVehiculeRoues_Kph_M_f32	453.097992
k_AASNTCEnableTimeout_mS_u16	21344
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	16844
k_AASNodeTimeout_mS_u16	57776
k_ABSNodeTimeout_mS_u16	41319
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	22048
k_ANGLEVOLANTSigValidThresh_Cnt_u16	2417
k_AngleVolantInvalidThresh_Cnt_u16	57712
k_AngleVolantValidThresh_Cnt_u16	23782
k_BSI552MsgTimeout_mS_u16	39347
k_BSINTCEnableTimeout_mS_u16	41605
k_BSINodeAbsentDiag_Cnt_str.Threshold	57614
k_BSINodeAbsentDiag_Cnt_str.PStep	62239
k_BSINodeAbsentDiag_Cnt_str.NStep	4469
k_BSINodeAbsentTimeout_mS_u16	44241
k_BSINodeTimeout_mS_u16	6378
k_BattOvHi_Volt_f32	4.56850004
k_BattOvLo_Volt_f32	27.4535999
k_BattUvHi_Volt_f32	26.0200996
k_BattUvLo_Volt_f32	7.6006999
k_CAVNTCEnableTimeout_mS_u16	65036
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	15335
k_CAVNodeTimeout_mS_u16	37709
k_CMM388MsgTimeout_mS_u16	61868
k_CMM388NTCEnableTimeout_mS_u16	43144
k_CMMNTCEnableTimeout_mS_u16	22777
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	59856
k_CONSANGLECPKMax_HwDeg_f32	246.111801
k_CONSANGLECPKMin_HwDeg_f32	-3.94090009
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	46631
k_CONSANGLECPKSigValidThresh_Cnt_u16	61428
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	29670
k_CPKVehicleSpeedValidThresh_Cnt_u16	12607
k_CityParkInputInvalidThresh_Cnt_u16	58954
k_CityParkInputValidThresh_Cnt_u16	59357
k_ComputerRazGCTSigValidThresh_Cnt_u16	16343
k_CptTemporelSigValidThresh_Cnt_u16	52129
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	23336
k_DMDFCTCPKSigValidThresh_Cnt_u16	55693
k_DMDFCTCPKValidCount_Cnt_u16	2640
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	48377
k_DMDRELAXECPKSigValidThresh_Cnt_u16	31734
k_DMDRelaxeConsistentThresh_Cnt_u16	63532
k_DateValidThresh_Cnt_u16	181
k_DefaultVehSpd_Kph_f32	45.7014999
k_DiagMuxOnAbsentTimeout_mS_u16	41303
k_EMNodeTimeout_mS_u16	63294
k_ESPNTCEnableTimeout_mS_u16	9813
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	49944
k_EtatMTSigInvalidThresh_Cnt_u16	21363
k_EtatMTSigValidThresh_Cnt_u16	12625
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	36833
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	5698
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	44710
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	23758
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	33752
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	14664
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	54234

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	16043
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	62961
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	62005
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	31951
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	4970
k_ISDATDIRASentDiag_Cnt_str.Threshold	60800
k_ISDATDIRASentDiag_Cnt_str.PStep	27554
k_ISDATDIRASentDiag_Cnt_str.NStep	30413
k_ISDATDIRASentTimeout_mS_u16	33648
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	28751
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	27673
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	42177
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	33428
k_ISDYNAASChkSumValidThresh_Cnt_u16	10034
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	50677
k_ISDYNAASMsgCountValidThresh_Cnt_u16	46891
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	36536
k_ISDYNAASMsgLenValidThresh_Cnt_u16	19668
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	41145
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	19606
k_ISDYNABRChkSumValidThresh_Cnt_u16	41339
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	15112
k_ISDYNABRMsgCountValidThresh_Cnt_u16	36125
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	42153
k_ISDYNABRMsgLenValidThresh_Cnt_u16	23738
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	51036
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	47718
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	48429
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	54639
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	30033
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	7206
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	57758
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	13303
k_ISDYNVOLChkSumValidThresh_Cnt_u16	38064
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	22055
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	50774
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	1250
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	20835
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	16987
k_IgnOnTimeout_mS_u16	39891
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	4.52820015
k_PowerCutVehSpdLowThresh_Kph_f32	187.098495
k_PowerCutVehSpdLowTimeout_mS_u16	7212
k_VBattMaxAAS_Volt_f32	31.9979992
k_VBattMaxBSI_Volt_f32	9.22819996
k_VBattMaxCAV_Volt_f32	15.1191998
k_VBattMaxCMM388_Volt_f32	14.6945
k_VBattMaxCMM_Volt_f32	28.1355
k_VBattMaxESP_Volt_f32	3.86870003
k_VBattMinAAS_Volt_f32	21.9500999
k_VBattMinBSI_Volt_f32	3.86870003
k_VBattMinCAV_Volt_f32	24.3285999
k_VBattMinCMM388_Volt_f32	25.4790001
k_VBattMinCMM_Volt_f32	28.4563999
k_VBattMinESP_Volt_f32	28.1355
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	39193
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	39682
k_VitesseVehicleBVRampValidThresh_Cnt_u16	38192
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	9092
k_VitesseVehicleBVSigValidThresh_Cnt_u16	23390
k_VitesseVehicleBVSpeedPassThresh_kph_f32	307.585114
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	8569
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	60455
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2429330944
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	252
target_SrlComInput_Per1_Batt_Volt_f32.value	29.4913998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	788567552
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	178
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.482283264
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3711223296
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3144541696
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3799451136
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1515202048
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	720979456
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1551001088
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4139484672
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	28
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	46
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	58
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	98
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	179
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	189
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2860066304
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	41
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	55
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	177
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	812631552
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	232
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2452153856
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4239525376
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	15
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	157
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	215
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2124944896
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	752
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.60523808
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	599660
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	44.4766998

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	27020		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	460.101593	460.101593	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	50865	50865	✔
CONSANGLECPK_HwDeg_M_f32	258.966187	258.966187 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3251510528	3251510528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	19	19	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	45	45	✔
ElecIntTimer_mS_M_u32[1]	100	100	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	181	181	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	22407	22407	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	14342	14342	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	6378	6378	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	60800	60800	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	48377	48377	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	6974	6974	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	50865	50865	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	22407	22407	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	33575	33575	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	12713	12713	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	2199569920	2199569920	✔
IgnTimeOff_Sec_M_u32	1920120761	1920120761	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	206	206	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3711223296	3711223296	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	235	235	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3144541696	3144541696	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	77	77	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3799451136	3799451136	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	251	251	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1515202048	1515202048	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1133250048	1133250048	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	95	95	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1551001088	1551001088	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	35	35	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4139484672	4139484672	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	72	72	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2860066304	2860066304	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	168	168	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	812631552	812631552	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	232	232	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2452153856	2452153856	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	45	45	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4239525376	4239525376	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2124944896	2124944896	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	274.249695	274.249695	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	572.833008	572.833008	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	453.097992	453.097992	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	50865	50865	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1920120761	1920120761	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	258.966187	258.966187 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.357 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	599482624
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	5871
AASNodeAbsentTimer_mS_M_u32	1666158848
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	48642
ANGLEVOLANTSigValidCount_Cnt_M_u16	60226
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	33448
AngleVolantMsgTimer_mS_M_u32	599482624
AngleVolantValidCount_Cnt_M_u16	11595
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2618577152
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2068893952
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	120160512
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1559314688
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	2269
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	669516032
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	33290
CAVNodeAbsentTimer_mS_M_u32	2747379968
CDD_SrlComVehSpd_Kph_G_f32	207.091095
CMM388NTCEnableTimer_mS_M_u32	1503195392
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2485104896
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	21306
CMMNodeAbsentTimer_mS_M_u32	554909952
CONSANGLECPKSigInvalidCount_Cnt_M_u16	15267
CONSANGLECPKSigValidCount_Cnt_M_u16	25586
CONSANGLECPK_Cnt_M_u16	44449
CONSANGLECPK_HwDeg_M_f32	-285.781586
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	44449
CPKVehicleSpeedMsgTimer_mS_M_u32	678322432
CPKVehicleSpeedValidCount_Cnt_M_u16	13014
CityParkInputConsistentCount_Cnt_M_u16	33759
CityParkInputInvalidCount_Cnt_M_u16	55747
CityParkInputMsgTimer_mS_M_u32	3711223296
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1591972096
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	2947

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2793943296
ComputerRazGCTSigValidCount_Cnt_M_u16	44272
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	44847
DMDFCTCPKSigValidCount_Cnt_M_u16	54711
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	21580
DMDRELAXECPKSigValidCount_Cnt_M_u16	34060
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	3164
DateInvalidTimer_mS_M_u32	2068893952
DiagMuxOnAbsentTimer_mS_M_u32	3222413568
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1559314688
ESPNTCEnableTimer_mS_M_u32	593268992
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	15558
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	555
EffacDefaultDiagTimer_mS_M_u32[1]	5555
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	66
ElecIntTimer_mS_M_u32[1]	80
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1158807808
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	17699
EtatMTSigValidCount_Cnt_M_u16	63582
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	12269
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	56252
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	47125
ISDAT4V2BSI552MsgTimer_mS_M_u32	1671905536
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	26609
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	25556
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	63582
ISDATBSI3F2MsgTimer_mS_M_u32	63447296
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	63562
ISDATBSI412MsgLenValidCount_Cnt_M_u16	24734
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	17699
ISDATBSI412MsgTimer_mS_M_u32	896622848
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	7374
ISDATBSI432MsgLenValidCount_Cnt_M_u16	52570
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	1719
ISDATDIRASentFltAcc_Cnt_M_u16	56347
ISDATDIRASentTimer_mS_M_u32	678322432
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	28119
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	11595
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	50570
ISDYN2CMMMsgTimer_mS_M_u32	3388903680
ISDYNAASChkSumInvalidCount_Cnt_M_u16	18745
ISDYNAASChkSumValidCount_Cnt_M_u16	39193
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	4518
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	4857
ISDYNAASMsgLenValidCount_Cnt_M_u16	23024
ISDYNAASMsgTimeValidCount_Cnt_M_u16	18745
ISDYNAASMsgTimer_mS_M_u32	1879372032
ISDYNABRChkSumInvalidCount_Cnt_M_u16	56248
ISDYNABRChkSumValidCount_Cnt_M_u16	12191
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	65044
ISDYNABRMsgCountValidCount_Cnt_M_u16	52276
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	55166
ISDYNABRMsgLenValidCount_Cnt_M_u16	48653
ISDYNABRMsgTimeValidCount_Cnt_M_u16	44449
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	37201
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	41746
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	63582
ISDYNCMM208MsgTimer_mS_M_u32	1013272832
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	37201
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	41746
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	23041

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3813830912
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	55129
ISDYNVOLChkSumValidCount_Cnt_M_u16	31784
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	29157
ISDYNVOLMsgCountValidCount_Cnt_M_u16	21741
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	2795
ISDYNVOLMsgLenValidCount_Cnt_M_u16	61595
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	21306
ISDYNVOLMsgTimer_mS_M_u32	2029269248
IgnOnTimer_mS_M_u32	82211072
IgnTimeOff_Sec_M_u32	1275104378
ManVehSpd_Kph_M_f32	314.293091
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	122
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	100
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2659590400
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	69
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	426017024
PrevISDATBSI412MsgDLCError_Cnt_M_u08	29
PrevISDATBSI412MsgRxTime_MSec_M_u32	1076801792
PrevISDATBSI432MsgDLCError_Cnt_M_u08	23
PrevISDATBSI432MsgRxTime_MSec_M_u32	2812317952
PrevISDATDIRAMsgTxTime_MSec_M_u32	412266752
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	28
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2219360512
PrevISDYNAASMsgDLCError_Cnt_M_u08	10
PrevISDYNAASMsgRxTime_MSec_M_u32	3777638656
PrevISDYNABRMsgDLCError_Cnt_M_u08	209
PrevISDYNABRMsgRxTime_MSec_M_u32	2831053056
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	123
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4042993920
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	128
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2320470272
PrevISDYNVOLMsgDLCError_Cnt_M_u08	158
PrevISDYNVOLMsgRxTime_MSec_M_u32	1878503680
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3190251776
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	211.022003
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	41903
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	10022
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	10580
VitesseVehicleBVRampValidCount_Cnt_M_u16	3723
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	55079
VitesseVehicleBVSigValidCount_Cnt_M_u16	1575
VitesseVehicleBV_Kph_M_f32	645.898804
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	23041
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	44633
VitesseVehiculeRoues_Kph_M_f32	455.162811
k_AASNTCEnableTimeout_mS_u16	33684
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	61970
k_AASNodeTimeout_mS_u16	52774
k_ABSNodeTimeout_mS_u16	20544
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	33237
k_ANGLEVOLANTSigValidThresh_Cnt_u16	47521
k_AngleVolantInvalidThresh_Cnt_u16	60836
k_AngleVolantValidThresh_Cnt_u16	55747
k_BSI552MsgTimeout_mS_u16	5148
k_BSINTCEnableTimeout_mS_u16	28838
k_BSINodeAbsentDiag_Cnt_str.Threshold	33712
k_BSINodeAbsentDiag_Cnt_str.PStep	39098
k_BSINodeAbsentDiag_Cnt_str.NStep	39161
k_BSINodeAbsentTimeout_mS_u16	41088
k_BSINodeTimeout_mS_u16	1719
k_BattOvHi_Volt_f32	17.2982998
k_BattOvLo_Volt_f32	10.9452
k_BattUvHi_Volt_f32	11.4052
k_BattUvLo_Volt_f32	24.2292995
k_CAVNTCEnableTimeout_mS_u16	3665
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	53696
k_CAVNodeTimeout_mS_u16	59919
k_CMM388MsgTimeout_mS_u16	65007
k_CMM388NTCEnableTimeout_mS_u16	18779
k_CMMNTCEnableTimeout_mS_u16	26569
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	55237
k_CONSANGLECPKMax_HwDeg_f32	478.816315
k_CONSANGLECPKMin_HwDeg_f32	-421.31189
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	49409
k_CONSANGLECPKSigValidThresh_Cnt_u16	21849
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	28548
k_CPKVehicleSpeedValidThresh_Cnt_u16	33785
k_CityParkInputInvalidThresh_Cnt_u16	28566
k_CityParkInputValidThresh_Cnt_u16	33759
k_ComputerRazGCTSigValidThresh_Cnt_u16	43823
k_CptTemporelSigValidThresh_Cnt_u16	14738
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	48766
k_DMDFCTCPKSigValidThresh_Cnt_u16	58637
k_DMDFCTCPKValidCount_Cnt_u16	41477
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	50570
k_DMDRELAXECPKSigValidThresh_Cnt_u16	35410
k_DMDRelaxeConsistentThresh_Cnt_u16	28080
k_DateValidThresh_Cnt_u16	47125
k_DefaultVehSpd_Kph_f32	44.3594017
k_DiagMuxOnAbsentTimeout_mS_u16	13743
k_EMNodeTimeout_mS_u16	49724
k_ESPNTCEnableTimeout_mS_u16	19062
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	27629
k_EtatMTSigInvalidThresh_Cnt_u16	3099
k_EtatMTSigValidThresh_Cnt_u16	62530
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	51091
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	50735
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	37764
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	61514
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	44269
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	53214
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	28839
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	33267
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	9826
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	15125
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	3337
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	39543
k_ISDATDIRASentDiag_Cnt_str.Threshold	35056

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	8835
k_ISDATDIRASentDiag_Cnt_str.NStep	19771
k_ISDATDIRASentTimeout_mS_u16	45092
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	22472
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	33448
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	32562
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	17080
k_ISDYNAASChkSumValidThresh_Cnt_u16	54943
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	58644
k_ISDYNAASMsgCountValidThresh_Cnt_u16	62260
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	44620
k_ISDYNAASMsgLenValidThresh_Cnt_u16	7354
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	5065
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	8756
k_ISDYNABRChkSumValidThresh_Cnt_u16	50499
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	61405
k_ISDYNABRMsgCountValidThresh_Cnt_u16	23389
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	64058
k_ISDYNABRMsgLenValidThresh_Cnt_u16	9158
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	26784
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	4675
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	6191
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	44777
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	42242
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	4674
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	11163
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	23505
k_ISDYNVOLChkSumValidThresh_Cnt_u16	11109
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	11135
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	35123
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	20111
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	31434
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	2851
k_IgnOnTimeout_mS_u16	37949
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	254.379395
k_PowerCutVehSpdLowThresh_Kph_f32	162.668503
k_PowerCutVehSpdLowTimeout_mS_u16	22832
k_VBattMaxAAS_Volt_f32	0.87440002
k_VBattMaxBSI_Volt_f32	27.2247009
k_VBattMaxCAV_Volt_f32	21.9591007
k_VBattMaxCMM388_Volt_f32	26.6490993
k_VBattMaxCMM_Volt_f32	2.79399991
k_VBattMaxESP_Volt_f32	4.79250002
k_VBattMinAAS_Volt_f32	6.49370003
k_VBattMinBSI_Volt_f32	4.79250002
k_VBattMinCAV_Volt_f32	21.3687992
k_VBattMinCMM388_Volt_f32	17.2085991
k_VBattMinCMM_Volt_f32	2.05669999
k_VBattMinESP_Volt_f32	2.79399991
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	34154
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	12654
k_VitesseVehicleBVRampValidThresh_Cnt_u16	55525
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	41768
k_VitesseVehicleBVSigValidThresh_Cnt_u16	27996
k_VitesseVehicleBVSpeedPassThresh_kph_f32	414.188507
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	59658
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	19137
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2068893952
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	128
target_SrlComInput_Per1_Batt_Volt_f32.value	9.58390045
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2624913664
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	32
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.342259288
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3734532352
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	177
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	275583232
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	248
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2815537408
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2361807104
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2806706432
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3747582208
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	486813952
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	124
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	150
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	193
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2152419584
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	36
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	43
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	114
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	242
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	250
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2431086848
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	102
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	943460608
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	86028544
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	55
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	119
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	126
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	161
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	218
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	234
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2877194496
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	807
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.302776337
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	193610
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	149.783997
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	7377

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	314.293091	314.293091	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	44449	44449	✔
CONSANGLECPK_HwDeg_M_f32	-285.781586	-285.781586 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2006148864	2006148864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	555	555	✔
EffacDefaultDiagTimer_mS_M_u32[1]	5555	5555	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	66	66	✔
ElecIntTimer_mS_M_u32[1]	80	80	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	47125	47125	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	63582	63582	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	17699	17699	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	1719	1719	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	35056	35056	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	50570	50570	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	18745	18745	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	44449	44449	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	63582	63582	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	23041	23041	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	21306	21306	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	82211072	82211072	✔
IgnTimeOff_Sec_M_u32	1275104378	1275104378	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3734532352	3734532352	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	177	177	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	275583232	275583232	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	248	248	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2815537408	2815537408	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	154	154	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2361807104	2361807104	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	412266752	412266752	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	137	137	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3747582208	3747582208	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	166	166	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	486813952	486813952	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	151	151	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2152419584	2152419584	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	250	250	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2431086848	2431086848	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	102	102	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	943460608	943460608	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	3	3	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	86028544	86028544	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2877194496	2877194496	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	211.022003	211.022003	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	645.898804	645.898804	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	455.162811	455.162811	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	44449	44449	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1275104378	1275104378	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-285.781586	-285.781586 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.358 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4214267904
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	37779
AASNodeAbsentTimer_mS_M_u32	154406912
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	2139
ANGLEVOLANTSigValidCount_Cnt_M_u16	23388
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	29800
AngleVolantMsgTimer_mS_M_u32	4214267904
AngleVolantValidCount_Cnt_M_u16	50944
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1642450944
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1446006784
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	828784640
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4279173120
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	21450
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3911892992
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	58052
CAVNodeAbsentTimer_mS_M_u32	945664000
CDD_SrlComVehSpd_Kph_G_f32	582.792114
CMM388NTCEnableTimer_mS_M_u32	2211966976
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1598271488
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	40689
CMMNodeAbsentTimer_mS_M_u32	3131637760
CONSANGLECPKSigInvalidCount_Cnt_M_u16	633
CONSANGLECPKSigValidCount_Cnt_M_u16	42058
CONSANGLECPK_Cnt_M_u16	17213
CONSANGLECPK_HwDeg_M_f32	-112.403397
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17213
CPKVehicleSpeedMsgTimer_mS_M_u32	2031591424
CPKVehicleSpeedValidCount_Cnt_M_u16	19431
CityParkInputConsistentCount_Cnt_M_u16	4932
CityParkInputInvalidCount_Cnt_M_u16	62103
CityParkInputMsgTimer_mS_M_u32	3734532352
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1719144448
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	1495

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1779052544
ComputerRazGCTSigValidCount_Cnt_M_u16	7185
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	8787
DMDFCTCPKSigValidCount_Cnt_M_u16	43388
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	60797
DMDRELAXECPKSigValidCount_Cnt_M_u16	13822
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	46158
DateInvalidTimer_mS_M_u32	1446006784
DiagMuxOnAbsentTimer_mS_M_u32	4046217216
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4279173120
ESPNTCEnableTimer_mS_M_u32	1024266240
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	60686
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	963
EffacDefaultDiagTimer_mS_M_u32[1]	7852
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	101
ElecIntTimer_mS_M_u32[1]	107
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3115106304
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	47673
EtatMTSigValidCount_Cnt_M_u16	27462
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	52635
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	58604
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	64098
ISDAT4V2BSI552MsgTimer_mS_M_u32	1122828288
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	24911
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	55396
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	27462
ISDATBSI3F2MsgTimer_mS_M_u32	2114609152
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	42307
ISDATBSI412MsgLenValidCount_Cnt_M_u16	38664
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	47673
ISDATBSI412MsgTimer_mS_M_u32	504274944
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	37429
ISDATBSI432MsgLenValidCount_Cnt_M_u16	35666
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	18621
ISDATDIRASentFltAcc_Cnt_M_u16	22673
ISDATDIRASentTimer_mS_M_u32	2031591424
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	23195
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	50944
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	2882
ISDYN2CMMMsgTimer_mS_M_u32	1361514496
ISDYNAASChkSumInvalidCount_Cnt_M_u16	42165
ISDYNAASChkSumValidCount_Cnt_M_u16	4054
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	17903
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	44023
ISDYNAASMsgLenValidCount_Cnt_M_u16	37328
ISDYNAASMsgTimeValidCount_Cnt_M_u16	42165
ISDYNAASMsgTimer_mS_M_u32	4036227072
ISDYNABRChkSumInvalidCount_Cnt_M_u16	24250
ISDYNABRChkSumValidCount_Cnt_M_u16	56770
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	45604
ISDYNABRMsgCountValidCount_Cnt_M_u16	41605
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	23272
ISDYNABRMsgLenValidCount_Cnt_M_u16	49657
ISDYNABRMsgTimeValidCount_Cnt_M_u16	17213
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	9538
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	445
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	27462
ISDYNCMM208MsgTimer_mS_M_u32	83021824
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	9538
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	445
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	39134

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2896916480
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	34647
ISDYNVOLChkSumValidCount_Cnt_M_u16	45992
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	12849
ISDYNVOLMsgCountValidCount_Cnt_M_u16	33754
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	22175
ISDYNVOLMsgLenValidCount_Cnt_M_u16	16464
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	40689
ISDYNVOLMsgTimer_mS_M_u32	2730897408
IgnOnTimer_mS_M_u32	2549051392
IgnTimeOff_Sec_M_u32	1560624783
ManVehSpd_Kph_M_f32	88.7687988
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	123
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	108
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	634413056
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	208
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2796896256
PrevISDATBSI412MsgDLCError_Cnt_M_u08	217
PrevISDATBSI412MsgRxTime_MSec_M_u32	1461104640
PrevISDATBSI432MsgDLCError_Cnt_M_u08	187
PrevISDATBSI432MsgRxTime_MSec_M_u32	3225489408
PrevISDATDIRAMsgTxTime_MSec_M_u32	1575661568
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	237
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1191739392
PrevISDYNAASMsgDLCError_Cnt_M_u08	28
PrevISDYNAASMsgRxTime_MSec_M_u32	3257151488
PrevISDYNABRMsgDLCError_Cnt_M_u08	58
PrevISDYNABRMsgRxTime_MSec_M_u32	208105472
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	91
PrevISDYNCMM208MsgRxTime_MSec_M_u32	380710912
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	109
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2486439936
PrevISDYNVOLMsgDLCError_Cnt_M_u08	190
PrevISDYNVOLMsgRxTime_MSec_M_u32	733720576
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3689717760
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	412.042114
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	20949
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	33326
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	38118
VitesseVehicleBVRampValidCount_Cnt_M_u16	40959
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	37100
VitesseVehicleBVSigValidCount_Cnt_M_u16	57005
VitesseVehicleBV_Kph_M_f32	366.25119
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	39134
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	54935
VitesseVehiculeRoues_Kph_M_f32	619.262817
k_AASNTCEnableTimeout_mS_u16	19812
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	21675
k_AASNodeTimeout_mS_u16	36142
k_ABSNodeTimeout_mS_u16	49952
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	16160
k_ANGLEVOLANTSigValidThresh_Cnt_u16	41597
k_AngleVolantInvalidThresh_Cnt_u16	53876
k_AngleVolantValidThresh_Cnt_u16	62103
k_BSI552MsgTimeout_mS_u16	29006
k_BSINTCEnableTimeout_mS_u16	63149
k_BSINodeAbsentDiag_Cnt_str.Threshold	57765
k_BSINodeAbsentDiag_Cnt_str.PStep	49349
k_BSINodeAbsentDiag_Cnt_str.NStep	44618
k_BSINodeAbsentTimeout_mS_u16	31456
k_BSINodeTimeout_mS_u16	18621
k_BattOvHi_Volt_f32	27.9123001
k_BattOvLo_Volt_f32	22.5650005
k_BattUvHi_Volt_f32	0.205799997
k_BattUvLo_Volt_f32	24.0358009
k_CAVNTCEnableTimeout_mS_u16	3309
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	19362
k_CAVNodeTimeout_mS_u16	42805
k_CMM388MsgTimeout_mS_u16	56979
k_CMM388NTCEnableTimeout_mS_u16	44111
k_CMMNTCEnableTimeout_mS_u16	49607
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	2643
k_CONSANGLECPKMax_HwDeg_f32	627.056213
k_CONSANGLECPKMin_HwDeg_f32	-296.700714
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	25566
k_CONSANGLECPKSigValidThresh_Cnt_u16	57751
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	41236
k_CPKVehicleSpeedValidThresh_Cnt_u16	32310
k_CityParkInputInvalidThresh_Cnt_u16	39712
k_CityParkInputValidThresh_Cnt_u16	4932
k_ComputerRazGCTSigValidThresh_Cnt_u16	3989
k_CptTemporelSigValidThresh_Cnt_u16	53034
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	42472
k_DMDFCTCPKSigValidThresh_Cnt_u16	19705
k_DMDFCTCPKValidCount_Cnt_u16	10322
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	2882
k_DMDRELAXECPKSigValidThresh_Cnt_u16	47019
k_DMDRelaxeConsistentThresh_Cnt_u16	1425
k_DateValidThresh_Cnt_u16	64098
k_DefaultVehSpd_Kph_f32	171.807602
k_DiagMuxOnAbsentTimeout_mS_u16	25363
k_EMNodeTimeout_mS_u16	4782
k_ESPNTCEnableTimeout_mS_u16	14720
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	60891
k_EtatMTSigInvalidThresh_Cnt_u16	6545
k_EtatMTSigValidThresh_Cnt_u16	56281
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	38119
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	58324
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	47189
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	27716
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	41241
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	28295
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	15018
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	4487
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	50553
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	27361
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	40902
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	956
k_ISDATDIRASentDiag_Cnt_str.Threshold	45598

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	35197
k_ISDATDIRASentDiag_Cnt_str.NStep	1197
k_ISDATDIRASentTimeout_mS_u16	37238
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	20425
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	29800
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	35660
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	10682
k_ISDYNAASChkSumValidThresh_Cnt_u16	59586
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	64804
k_ISDYNAASMsgCountValidThresh_Cnt_u16	11653
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	14078
k_ISDYNAASMsgLenValidThresh_Cnt_u16	61810
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	13317
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	53958
k_ISDYNABRChkSumValidThresh_Cnt_u16	1111
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	40650
k_ISDYNABRMsgCountValidThresh_Cnt_u16	14091
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	43505
k_ISDYNABRMsgLenValidThresh_Cnt_u16	14350
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	56130
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	22041
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	6548
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	46821
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	21339
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	58972
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	23823
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	22190
k_ISDYNVOLChkSumValidThresh_Cnt_u16	4787
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	17635
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	8454
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	19957
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	37890
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	47416
k_IgnOnTimeout_mS_u16	23914
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	50.2476006
k_PowerCutVehSpdLowThresh_Kph_f32	237.380402
k_PowerCutVehSpdLowTimeout_mS_u16	15504
k_VBattMaxAAS_Volt_f32	14.2488003
k_VBattMaxBSI_Volt_f32	28.0748005
k_VBattMaxCAV_Volt_f32	6.6500001
k_VBattMaxCMM388_Volt_f32	15.3318005
k_VBattMaxCMM_Volt_f32	4.49380016
k_VBattMaxESP_Volt_f32	12.9035997
k_VBattMinAAS_Volt_f32	4.96400023
k_VBattMinBSI_Volt_f32	12.9035997
k_VBattMinCAV_Volt_f32	26.3066006
k_VBattMinCMM388_Volt_f32	7.91410017
k_VBattMinCMM_Volt_f32	6.02909994
k_VBattMinESP_Volt_f32	4.49380016
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	52963
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	46488
k_VitesseVehicleBVRampValidThresh_Cnt_u16	64817
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	16040
k_VitesseVehicleBVSigValidThresh_Cnt_u16	35533
k_VitesseVehicleBVSpeedPassThresh_kph_f32	205.704605
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	44484
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	17245
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1446006784
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	109
target_SrlComInput_Per1_Batt_Volt_f32.value	7.23409986
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4286824448
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	71
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.525359631
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	231
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1389981696
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1474007040
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1814933504
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3620720640
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3804360704
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3573813248
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4137037824
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	54
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	147
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	149
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	176
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	190
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	226
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	54
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1363202048
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	88
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	103
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	115
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	134
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	172
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	173
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	200
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	938242048
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	188
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3698233344
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	159
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1346416640
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	52
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	91
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	115
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	213
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	226
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3630645248
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2969
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.3417418
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	724583
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	62.2839012
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	61039

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	29802	29802	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	17213	17213	✔
CONSANGLECPK_HwDeg_M_f32	-112.403397	-112.403397 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17213	17213	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2031591424	2031591424	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	19431	19431	✔
CityParkInputConsistentCount_Cnt_M_u16	4932	4932	✔
CityParkInputInvalidCount_Cnt_M_u16	62103	62103	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	963	963	✔
EffacDefaultDiagTimer_mS_M_u32[1]	7852	7852	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2006148864	2006148864	✔
ElecIntTimer_mS_M_u32[1]	107	107	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	45598	45598	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	2006148864	2006148864	✔
IgnTimeOff_Sec_M_u32	1560624783	1560624783	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	231	231	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1389981696	1389981696	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	223	223	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1474007040	1474007040	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	195	195	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1814933504	1814933504	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3620720640	3620720640	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1575661568	1575661568	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	194	194	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3573813248	3573813248	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	35	35	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4137037824	4137037824	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	54	54	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1363202048	1363202048	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	132	132	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	938242048	938242048	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	188	188	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3698233344	3698233344	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	159	159	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1346416640	1346416640	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3630645248	3630645248	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	412.042114	412.042114	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	366.25119	366.25119	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	619.262817	619.262817	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	17213	17213	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1560624783	1560624783	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-112.403397	-112.403397 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	171.807602	171.807602	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.359 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3700220672
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	48485
AASNodeAbsentTimer_mS_M_u32	1279431424
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	8459
ANGLEVOLANTSigValidCount_Cnt_M_u16	38857
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	44774
AngleVolantMsgTimer_mS_M_u32	3700220672
AngleVolantValidCount_Cnt_M_u16	49054
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	959271680
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2790118144
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2557215488
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3262235392
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	47806
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	589202176
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	7760
CAVNodeAbsentTimer_mS_M_u32	3980768000
CDD_SrlComVehSpd_Kph_G_f32	549.762878
CMM388NTCEnableTimer_mS_M_u32	3285644032
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2425598720
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	23176
CMMNodeAbsentTimer_mS_M_u32	2007220992
CONSANGLECPKSigInvalidCount_Cnt_M_u16	55730
CONSANGLECPKSigValidCount_Cnt_M_u16	41983
CONSANGLECPK_Cnt_M_u16	21286
CONSANGLECPK_HwDeg_M_f32	140.244705
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21286
CPKVehicleSpeedMsgTimer_mS_M_u32	3201819392
CPKVehicleSpeedValidCount_Cnt_M_u16	36942
CityParkInputConsistentCount_Cnt_M_u16	60114
CityParkInputInvalidCount_Cnt_M_u16	43480

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	1389981696
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1148621568
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	30361
ComputerRazGCTSigInvalidTimer_mS_M_u32	2856334080
ComputerRazGCTSigValidCount_Cnt_M_u16	17515
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	2724
DMDFCTCPKSigValidCount_Cnt_M_u16	34025
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	31141
DMDRELAXECPKSigValidCount_Cnt_M_u16	4067
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	22579
DateInvalidTimer_mS_M_u32	2790118144
DiagMuxOnAbsentTimer_mS_M_u32	2576982784
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3262235392
ESPNTCEnableTimer_mS_M_u32	1421316864
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	20466
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	200
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	99
ElecIntTimer_mS_M_u32[1]	1001
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	966296320
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	13747
EtatMTSigValidCount_Cnt_M_u16	49740
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	32844
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	59929
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	43575
ISDAT4V2BSI552MsgTimer_mS_M_u32	4007117568
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	4592
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	27761
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	49740
ISDATBSI3F2MsgTimer_mS_M_u32	3942621952
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	26387
ISDATBSI412MsgLenValidCount_Cnt_M_u16	4484
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	13747
ISDATBSI412MsgTimer_mS_M_u32	1811079936
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	37052
ISDATBSI432MsgLenValidCount_Cnt_M_u16	34086
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	4197
ISDATDIRASentFltAcc_Cnt_M_u16	12521
ISDATDIRASentTimer_mS_M_u32	3201819392
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	1292
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	49054
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52183
ISDYN2CMMMsgTimer_mS_M_u32	6918912
ISDYNAASChkSumInvalidCount_Cnt_M_u16	37375
ISDYNAASChkSumValidCount_Cnt_M_u16	16476
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	48849
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	20151
ISDYNAASMsgLenValidCount_Cnt_M_u16	27884
ISDYNAASMsgTimeValidCount_Cnt_M_u16	37375
ISDYNAASMsgTimer_mS_M_u32	1839395584
ISDYNABRChkSumInvalidCount_Cnt_M_u16	3952
ISDYNABRChkSumValidCount_Cnt_M_u16	8725
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	58802
ISDYNABRMsgCountValidCount_Cnt_M_u16	1103
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	19557
ISDYNABRMsgLenValidCount_Cnt_M_u16	50930
ISDYNABRMsgTimeValidCount_Cnt_M_u16	21286
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	21980
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	35625

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	49740
ISDYNCMM208MsgTimer_mS_M_u32	3288748800
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	21980
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	35625
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	16900
ISDYNCMM388MsgTimer_mS_M_u32	4150031104
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	17176
ISDYNVOLChkSumValidCount_Cnt_M_u16	28133
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	54026
ISDYNVOLMsgCountValidCount_Cnt_M_u16	60879
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	38719
ISDYNVOLMsgLenValidCount_Cnt_M_u16	2540
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	23176
ISDYNVOLMsgTimer_mS_M_u32	4027331328
IgnOnTimer_mS_M_u32	1167094528
IgnTimeOff_Sec_M_u32	1472158803
ManVehSpd_Kph_M_f32	580.065002
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	124
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	234
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2343412480
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	167
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	880739072
PrevISDATBSI412MsgDLCError_Cnt_M_u08	223
PrevISDATBSI412MsgRxTime_MSec_M_u32	3038425856
PrevISDATBSI432MsgDLCError_Cnt_M_u08	201
PrevISDATBSI432MsgRxTime_MSec_M_u32	2602275584
PrevISDATDIRAMsgTxTime_MSec_M_u32	4036932352
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	110
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2961523456
PrevISDYNAASMsgDLCError_Cnt_M_u08	244
PrevISDYNAASMsgRxTime_MSec_M_u32	2314351360
PrevISDYNABRMsgDLCError_Cnt_M_u08	71
PrevISDYNABRMsgRxTime_MSec_M_u32	3358094080
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	129
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4928256
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	233
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2873266944
PrevISDYNVOLMsgDLCError_Cnt_M_u08	247
PrevISDYNVOLMsgRxTime_MSec_M_u32	187413248
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	710468352
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	226.204697
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	21789
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	37842
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	4074
VitesseVehicleBVRampValidCount_Cnt_M_u16	48735
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	2904
VitesseVehicleBVSigValidCount_Cnt_M_u16	37334
VitesseVehicleBV_Kph_M_f32	525.098511

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	16900
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	55449
VitesseVehiculeRoues_Kph_M_f32	67.313797
k_AASNTCEnableTimeout_mS_u16	37041
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	33437
k_AASNodeTimeout_mS_u16	29394
k_ABSNodeTimeout_mS_u16	39997
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	62971
k_ANGLEVOLANTSigValidThresh_Cnt_u16	43941
k_AngleVolantInvalidThresh_Cnt_u16	47040
k_AngleVolantValidThresh_Cnt_u16	43480
k_BSI552MsgTimeout_mS_u16	42100
k_BSINTCEnableTimeout_mS_u16	17236
k_BSINodeAbsentDiag_Cnt_str.Threshold	26162
k_BSINodeAbsentDiag_Cnt_str.PStep	28177
k_BSINodeAbsentDiag_Cnt_str.NStep	56004
k_BSINodeAbsentTimeout_mS_u16	31614
k_BSINodeTimeout_mS_u16	4197
k_BattOvHi_Volt_f32	2.00349998
k_BattOvLo_Volt_f32	26.2656002
k_BattUvHi_Volt_f32	26.2800999
k_BattUvLo_Volt_f32	27.8834
k_CAVNTCEnableTimeout_mS_u16	13014
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	56246
k_CAVNodeTimeout_mS_u16	56190
k_CMM388MsgTimeout_mS_u16	56421
k_CMM388NTCEnableTimeout_mS_u16	25393
k_CMMNTCEnableTimeout_mS_u16	53384
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	11621
k_CONSANGLECPKMax_HwDeg_f32	523.213623
k_CONSANGLECPKMin_HwDeg_f32	-656.090881
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	57604
k_CONSANGLECPKSigValidThresh_Cnt_u16	47001
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	20256
k_CPKVehicleSpeedValidThresh_Cnt_u16	26682
k_CityParkInputInvalidThresh_Cnt_u16	29246
k_CityParkInputValidThresh_Cnt_u16	60114
k_ComputerRazGCTSigValidThresh_Cnt_u16	40734
k_CptTemporelSigValidThresh_Cnt_u16	8223
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	27493
k_DMDFCTCPKSigValidThresh_Cnt_u16	9714
k_DMDFCTCPKValidCount_Cnt_u16	23846
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	52183
k_DMDRELAXECPKSigValidThresh_Cnt_u16	54876
k_DMDRelaxeConsistentThresh_Cnt_u16	1194
k_DateValidThresh_Cnt_u16	43575
k_DefaultVehSpd_Kph_f32	107.197304
k_DiagMuxOnAbsentTimeout_mS_u16	52132
k_EMNodeTimeout_mS_u16	48403
k_ESPNTCEnableTimeout_mS_u16	2588
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	41677
k_EtatMTSigInvalidThresh_Cnt_u16	64235
k_EtatMTSigValidThresh_Cnt_u16	17360
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	32679
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	45728
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	32671
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	1297
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	9810
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	6983
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	43869
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	1671

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	1776
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	27706
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	52556
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	31914
k_ISDATDIRASentDiag_Cnt_str.Threshold	58745
k_ISDATDIRASentDiag_Cnt_str.PStep	41340
k_ISDATDIRASentDiag_Cnt_str.NStep	16989
k_ISDATDIRASentTimeout_mS_u16	26428
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	3203
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	44774
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	17592
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	44656
k_ISDYNAASChkSumValidThresh_Cnt_u16	277
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	1202
k_ISDYNAASMsgCountValidThresh_Cnt_u16	25423
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	38564
k_ISDYNAASMsgLenValidThresh_Cnt_u16	22022
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	5901
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	56523
k_ISDYNABRChkSumValidThresh_Cnt_u16	63448
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	55742
k_ISDYNABRMsgCountValidThresh_Cnt_u16	32956
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	14728
k_ISDYNABRMsgLenValidThresh_Cnt_u16	28402
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	12311
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	22609
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	36384
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	37293
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	16395
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	63177
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	19056
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	48850
k_ISDYNVOLChkSumValidThresh_Cnt_u16	2691
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	56435
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	26697
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	27263
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	14360
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	17845
k_IgnOnTimeout_mS_u16	39582
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	226.377502
k_PowerCutVehSpdLowThresh_Kph_f32	184.979004
k_PowerCutVehSpdLowTimeout_mS_u16	29485
k_VBattMaxAAS_Volt_f32	5.80229998
k_VBattMaxBSI_Volt_f32	15.6934004
k_VBattMaxCAV_Volt_f32	26.6329994
k_VBattMaxCMM388_Volt_f32	31.3316002
k_VBattMaxCMM_Volt_f32	14.0553999
k_VBattMaxESP_Volt_f32	11.6105003
k_VBattMinAAS_Volt_f32	10.9370003
k_VBattMinBSI_Volt_f32	11.6105003
k_VBattMinCAV_Volt_f32	13.0058002
k_VBattMinCMM388_Volt_f32	28.8024006
k_VBattMinCMM_Volt_f32	11.4799004
k_VBattMinESP_Volt_f32	14.0553999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	30517
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	726
k_VitesseVehicleBVRampValidThresh_Cnt_u16	29194
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	52453
k_VitesseVehicleBVSigValidThresh_Cnt_u16	59447
k_VitesseVehicleBVSpeedPassThresh_kph_f32	292.071198
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	48464
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	52293
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2790118144
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65036
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	163190528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	233

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	30.5000992
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2215871232
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	44
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.393129438
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1020424960
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1582043904
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	171
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2446701312
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4285485824
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3474518784
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	160
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	684888832
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	882651904
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	44
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	154
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	162
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	208
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	102
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2535215872
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	25
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	164
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	178
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	18
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2576970496
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3700626176
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	34
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4053578496
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	12
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	176
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	199
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3882418944
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1724
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.606440008
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	741240
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	71.5184021
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	26447

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	163190528	163190528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	163190528	163190528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	163190528	163190528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	21286	21286	✔
CONSANGLECPK_HwDeg_M_f32	140.244705	140.244705 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	163190528	163190528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	163190528	163190528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	163190528	163190528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	163190528	163190528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	163190528	163190528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	163190528	163190528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	163190528	163190528	✔
ESPNTCEnableTimer_mS_M_u32	163190528	163190528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	163190528	163190528	✔
EffacDefaultDiagTimer_mS_M_u32[1]	200	200	✔
ElecIntCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	163190528	163190528	✔
ElecIntTimer_mS_M_u32[1]	1001	1001	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	163190528	163190528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	58745	58745	✔
ISDATDIRASentTimer_mS_M_u32	163190528	163190528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	163190528	163190528	✔
IgnOnTimer_mS_M_u32	163190528	163190528	✔
IgnTimeOff_Sec_M_u32	1472158803	1472158803	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	222	222	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1020424960	1020424960	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	133	133	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1582043904	1582043904	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	171	171	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2446701312	2446701312	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	118	118	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4285485824	4285485824	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4036932352	4036932352	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	160	160	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	684888832	684888832	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	77	77	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	882651904	882651904	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	102	102	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2535215872	2535215872	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	18	18	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2576970496	2576970496	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	251	251	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3700626176	3700626176	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	34	34	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4053578496	4053578496	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3882418944	3882418944	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	226.204697	226.204697	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	525.098511	525.098511	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	67.313797	67.313797	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	21286	21286	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1472158803	1472158803	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	140.244705	140.244705 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.360 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4047772160
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	20666
AASNodeAbsentTimer_mS_M_u32	3571649024
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	57287
ANGLEVOLANTSigValidCount_Cnt_M_u16	11343
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	49207
AngleVolantMsgTimer_mS_M_u32	4047772160
AngleVolantValidCount_Cnt_M_u16	29840
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	690145792
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	62999040
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2720446976
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1796569600
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	40622
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3960420864
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	17017
CAVNodeAbsentTimer_mS_M_u32	1717152256
CDD_SrlComVehSpd_Kph_G_f32	607.308411
CMM388NTCEnableTimer_mS_M_u32	3081103872
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	879733248
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	15247
CMMNodeAbsentTimer_mS_M_u32	2474605056
CONSANGLECPKSigInvalidCount_Cnt_M_u16	49362
CONSANGLECPKSigValidCount_Cnt_M_u16	21163
CONSANGLECPK_Cnt_M_u16	41270
CONSANGLECPK_HwDeg_M_f32	88.3899994
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	41270
CPKVehicleSpeedMsgTimer_mS_M_u32	912464384
CPKVehicleSpeedValidCount_Cnt_M_u16	33862
CityParkInputConsistentCount_Cnt_M_u16	49908
CityParkInputInvalidCount_Cnt_M_u16	28385
CityParkInputMsgTimer_mS_M_u32	1020424960
CityParkInputValidCount_Cnt_M_u16	6

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3158772224
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	62750
ComputerRazGCTSigInvalidTimer_mS_M_u32	963258880
ComputerRazGCTSigValidCount_Cnt_M_u16	23081
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	31869
DMDFCTCPKSigValidCount_Cnt_M_u16	56942
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	48633
DMDRELAXECPKSigValidCount_Cnt_M_u16	44033
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	35151
DateInvalidTimer_mS_M_u32	62999040
DiagMuxOnAbsentTimer_mS_M_u32	3709721088
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1796569600
ESPNTCEnableTimer_mS_M_u32	3481537024
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	48148
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	89
EffacDefaultDiagTimer_mS_M_u32[1]	898
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	11
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	279001600
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	8977
EtatMTSigValidCount_Cnt_M_u16	40453
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	46340
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	26717
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	9860
ISDAT4V2BSI552MsgTimer_mS_M_u32	4259543552
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	6618
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	51990
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	40453
ISDATBSI3F2MsgTimer_mS_M_u32	15456768
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	46960
ISDATBSI412MsgLenValidCount_Cnt_M_u16	14557
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	8977
ISDATBSI412MsgTimer_mS_M_u32	1527912960
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	26867
ISDATBSI432MsgLenValidCount_Cnt_M_u16	60536
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	58
ISDATDIRASentFltAcc_Cnt_M_u16	44718
ISDATDIRASentTimer_mS_M_u32	912464384
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	41860
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	29840
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	50404
ISDYN2CMMMsgTimer_mS_M_u32	342755840
ISDYNAASChkSumInvalidCount_Cnt_M_u16	47852
ISDYNAASChkSumValidCount_Cnt_M_u16	57493
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	759
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	3396
ISDYNAASMsgLenValidCount_Cnt_M_u16	17252
ISDYNAASMsgTimeValidCount_Cnt_M_u16	47852
ISDYNAASMsgTimer_mS_M_u32	3930188288
ISDYNABRChkSumInvalidCount_Cnt_M_u16	16408
ISDYNABRChkSumValidCount_Cnt_M_u16	22760
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	19411
ISDYNABRMsgCountValidCount_Cnt_M_u16	8380
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	62649
ISDYNABRMsgLenValidCount_Cnt_M_u16	30162
ISDYNABRMsgTimeValidCount_Cnt_M_u16	41270
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	44746
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	44707
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	40453
ISDYNCMM208MsgTimer_mS_M_u32	748145152

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	44746
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	44707
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	1374
ISDYNCMM388MsgTimer_mS_M_u32	320170496
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	40096
ISDYNVOLChkSumValidCount_Cnt_M_u16	3321
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	15179
ISDYNVOLMsgCountValidCount_Cnt_M_u16	48060
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	23085
ISDYNVOLMsgLenValidCount_Cnt_M_u16	29413
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	15247
ISDYNVOLMsgTimer_mS_M_u32	2550540800
IgnOnTimer_mS_M_u32	4168706560
IgnTimeOff_Sec_M_u32	2419336037
ManVehSpd_Kph_M_f32	277.325104
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	125
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	161
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1457641984
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	175
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3656235520
PrevISDATBSI412MsgDLCError_Cnt_M_u08	19
PrevISDATBSI412MsgRxTime_MSec_M_u32	2732239360
PrevISDATBSI432MsgDLCError_Cnt_M_u08	158
PrevISDATBSI432MsgRxTime_MSec_M_u32	2354579968
PrevISDATDIRAMsgTxTime_MSec_M_u32	5155328
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	2
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1322973696
PrevISDYNAASMsgDLCError_Cnt_M_u08	53
PrevISDYNAASMsgRxTime_MSec_M_u32	3797166592
PrevISDYNABRMsgDLCError_Cnt_M_u08	59
PrevISDYNABRMsgRxTime_MSec_M_u32	3501287936
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	172
PrevISDYNCMM208MsgRxTime_MSec_M_u32	591997440
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	162
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3085109760
PrevISDYNVOLMsgDLCError_Cnt_M_u08	116
PrevISDYNVOLMsgRxTime_MSec_M_u32	614967808
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	937433600
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	147.366699
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	4626
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	59058
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	21931
VitesseVehicleBVRampValidCount_Cnt_M_u16	56075
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	38112
VitesseVehicleBVSigValidCount_Cnt_M_u16	45608
VitesseVehicleBV_Kph_M_f32	78.8018036
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	1374
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	21087

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	548.406677
k_AASNTCEnableTimeout_mS_u16	54421
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	59283
k_AASNodeTimeout_mS_u16	18866
k_ABSNodeTimeout_mS_u16	27570
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	62774
k_ANGLEVOLANTSigValidThresh_Cnt_u16	13563
k_AngleVolantInvalidThresh_Cnt_u16	15530
k_AngleVolantValidThresh_Cnt_u16	28385
k_BSI552MsgTimeout_mS_u16	6862
k_BSINTCEnableTimeout_mS_u16	45355
k_BSINodeAbsentDiag_Cnt_str.Threshold	44360
k_BSINodeAbsentDiag_Cnt_str.PStep	42475
k_BSINodeAbsentDiag_Cnt_str.NStep	49170
k_BSINodeAbsentTimeout_mS_u16	47727
k_BSINodeTimeout_mS_u16	58
k_BattOvHi_Volt_f32	27.3994999
k_BattOvLo_Volt_f32	27.4524002
k_BattUvHi_Volt_f32	1.09800005
k_BattUvLo_Volt_f32	4.50810003
k_CAVNTCEnableTimeout_mS_u16	19431
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	8775
k_CAVNodeTimeout_mS_u16	60270
k_CMM388MsgTimeout_mS_u16	62394
k_CMM388NTCEnableTimeout_mS_u16	36694
k_CMMNTCEnableTimeout_mS_u16	15890
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	33787
k_CONSANGLECPKMax_HwDeg_f32	544.297485
k_CONSANGLECPKMin_HwDeg_f32	-451.063293
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	10334
k_CONSANGLECPKSigValidThresh_Cnt_u16	46431
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	27848
k_CPKVehicleSpeedValidThresh_Cnt_u16	4091
k_CityParkInputInvalidThresh_Cnt_u16	53166
k_CityParkInputValidThresh_Cnt_u16	49908
k_ComputerRazGCTSigValidThresh_Cnt_u16	43600
k_CptTemporelSigValidThresh_Cnt_u16	59404
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	38841
k_DMDFCTCPKSigValidThresh_Cnt_u16	22738
k_DMDFCTCPKValidCount_Cnt_u16	22390
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	50404
k_DMDRELAXECPKSigValidThresh_Cnt_u16	30229
k_DMDRelaxeConsistentThresh_Cnt_u16	41771
k_DateValidThresh_Cnt_u16	9860
k_DefaultVehSpd_Kph_f32	99.8251038
k_DiagMuxOnAbsentTimeout_mS_u16	44988
k_EMNodeTimeout_mS_u16	55983
k_ESPNTCEnableTimeout_mS_u16	44821
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	50115
k_EtatMTSigInvalidThresh_Cnt_u16	10663
k_EtatMTSigValidThresh_Cnt_u16	40887
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	46899
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	48904
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	30861
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	1143
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	24947
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	27348
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	56592
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	11349
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	54871
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	42490

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	33670
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	58283
k_ISDATDIRASentDiag_Cnt_str.Threshold	39767
k_ISDATDIRASentDiag_Cnt_str.PStep	14534
k_ISDATDIRASentDiag_Cnt_str.NStep	62426
k_ISDATDIRASentTimeout_mS_u16	26804
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	55328
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	49207
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	28481
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	25368
k_ISDYNAASChkSumValidThresh_Cnt_u16	48104
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	61139
k_ISDYNAASMsgCountValidThresh_Cnt_u16	956
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	31356
k_ISDYNAASMsgLenValidThresh_Cnt_u16	28694
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	37571
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	23431
k_ISDYNABRChkSumValidThresh_Cnt_u16	64288
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	16814
k_ISDYNABRMsgCountValidThresh_Cnt_u16	64886
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	40591
k_ISDYNABRMsgLenValidThresh_Cnt_u16	24340
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	7013
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	55414
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	46665
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	6433
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	33479
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	3919
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	60697
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	27699
k_ISDYNVOLChkSumValidThresh_Cnt_u16	2528
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	23185
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	22092
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	46253
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	27809
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	52234
k_IgnOnTimeout_mS_u16	2255
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	222.784607
k_PowerCutVehSpdLowThresh_Kph_f32	66.9798965
k_PowerCutVehSpdLowTimeout_mS_u16	7457
k_VBattMaxAAS_Volt_f32	0.0491999984
k_VBattMaxBSI_Volt_f32	14.2685003
k_VBattMaxCAV_Volt_f32	9.45470047
k_VBattMaxCMM388_Volt_f32	2.12649989
k_VBattMaxCMM_Volt_f32	5.32490015
k_VBattMaxESP_Volt_f32	10.3072996
k_VBattMinAAS_Volt_f32	19.8043003
k_VBattMinBSI_Volt_f32	10.3072996
k_VBattMinCAV_Volt_f32	13.3079996
k_VBattMinCMM388_Volt_f32	18.0606995
k_VBattMinCMM_Volt_f32	6.9605999
k_VBattMinESP_Volt_f32	5.32490015
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	57354
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	32230
k_VitesseVehicleBVRampValidThresh_Cnt_u16	24139
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	61433
k_VitesseVehicleBVSigValidThresh_Cnt_u16	40645
k_VitesseVehicleBVSpeedPassThresh_kph_f32	296.524994
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	25977
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	51545
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	62999040
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	15965
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2717483008
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	162
target_SrlComInput_Per1_Batt_Volt_f32.value	6.05170012
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3710925312
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	99
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.822119415
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	150
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2595449344
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2764474880
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3098126848
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	120
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1583139328
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	501213696
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	89
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2134051328
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	173419008
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	115
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	132
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2337655296
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	57
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	71
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	153
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	183
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	223
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	214
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1616800256
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	99715584
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1968482816
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	83
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	90
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	165
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	169
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3912219136
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2523
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.458466411
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	656723
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	19.6119995
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	9084

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2717483008	2717483008	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1583139328	1583139328	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	17017	17017	✔
CAVNodeAbsentTimer_mS_M_u32	1968482816	1968482816	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	15247	15247	✔
CMMNodeAbsentTimer_mS_M_u32	2134051328	2134051328	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	41270	41270	✔
CONSANGLECPK_HwDeg_M_f32	88.3899994	88.3899994 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2717483008	2717483008	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2717483008	2717483008	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2717483008	2717483008	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2717483008	2717483008	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2717483008	2717483008	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2717483008	2717483008	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2717483008	2717483008	✔
ESPNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	89	89	✔
EffacDefaultDiagTimer_mS_M_u32[1]	898	898	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	8	8	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	11	11	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2717483008	2717483008	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATDIRASentFltAcc_Cnt_M_u16	44718	44718	✔
ISDATDIRASentTimer_mS_M_u32	2717483008	2717483008	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2717483008	2717483008	✔
IgnOnTimer_mS_M_u32	4168706560	4168706560	✔
IgnTimeOff_Sec_M_u32	2419336037	2419336037	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	150	150	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2595449344	2595449344	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	239	239	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2764474880	2764474880	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	12	12	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3098126848	3098126848	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	120	120	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1583139328	1583139328	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	5155328	5155328	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	89	89	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2134051328	2134051328	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	223	223	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	173419008	173419008	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	158	158	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2337655296	2337655296	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	214	214	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1616800256	1616800256	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	106	106	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	99715584	99715584	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	131	131	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1968482816	1968482816	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3912219136	3912219136	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	147.366699	147.366699	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	78.8018036	78.8018036	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	548.406677	548.406677	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	41270	41270	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2419336037	2419336037	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	88.3899994	88.3899994 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	99.8251038	99.8251038	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0106	0x0106	✔
Param	0x00	0x00	✔
Status	0x00	0x00	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.361 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3099227392
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	37974
AASNodeAbsentTimer_mS_M_u32	1973265664
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	47409
ANGLEVOLANTSigValidCount_Cnt_M_u16	49496
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	31199
AngleVolantMsgTimer_mS_M_u32	3099227392
AngleVolantValidCount_Cnt_M_u16	43348
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	668886272
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	839050496
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	4170355968
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3368441088
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	55420
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1557730560
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	33179
CAVNodeAbsentTimer_mS_M_u32	1673118976
CDD_SrlComVehSpd_Kph_G_f32	26.0214996
CMM388NTCEnableTimer_mS_M_u32	4040492288
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3514287360
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	36119
CMMNodeAbsentTimer_mS_M_u32	2005423360
CONSANGLECPKSigInvalidCount_Cnt_M_u16	62734
CONSANGLECPKSigValidCount_Cnt_M_u16	27972
CONSANGLECPK_Cnt_M_u16	28067
CONSANGLECPK_HwDeg_M_f32	-20.6270008
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	28067
CPKVehicleSpeedMsgTimer_mS_M_u32	626881792
CPKVehicleSpeedValidCount_Cnt_M_u16	5339
CityParkInputConsistentCount_Cnt_M_u16	20008
CityParkInputInvalidCount_Cnt_M_u16	36704
CityParkInputMsgTimer_mS_M_u32	2595449344
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1332847872

Name	Input Value
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	14122
ComputerRazGCTSigInvalidTimer_mS_M_u32	3431482624
ComputerRazGCTSigValidCount_Cnt_M_u16	40073
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	54924
DMDFCTCPKSigValidCount_Cnt_M_u16	15995
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	26267
DMDRELAXECPKSigValidCount_Cnt_M_u16	35394
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	53143
DateInvalidTimer_mS_M_u32	839050496
DiagMuxOnAbsentTimer_mS_M_u32	2351772928
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3368441088
ESPNTCEnableTimer_mS_M_u32	1236968704
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	59721
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	4
EffacDefaultDiagTimer_mS_M_u32[1]	748
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	7
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3072529664
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	27539
EtatMTSigValidCount_Cnt_M_u16	39029
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24696
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	29742
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	15929
ISDAT4V2BSI552MsgTimer_mS_M_u32	3361494272
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	58551
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	36545
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	39029
ISDATBSI3F2MsgTimer_mS_M_u32	3636671744
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	13556
ISDATBSI412MsgLenValidCount_Cnt_M_u16	11887
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	27539
ISDATBSI412MsgTimer_mS_M_u32	860910848
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	38123
ISDATBSI432MsgLenValidCount_Cnt_M_u16	59421
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	35928
ISDATDIRASentFltAcc_Cnt_M_u16	20732
ISDATDIRASentTimer_mS_M_u32	626881792
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	7865
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	43348
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	22871
ISDYN2CMMMsgTimer_mS_M_u32	2734466304
ISDYNAASChkSumInvalidCount_Cnt_M_u16	40384
ISDYNAASChkSumValidCount_Cnt_M_u16	39559
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	23071
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	3386
ISDYNAASMsgLenValidCount_Cnt_M_u16	47256
ISDYNAASMsgTimeValidCount_Cnt_M_u16	40384
ISDYNAASMsgTimer_mS_M_u32	3372287232
ISDYNABRChkSumInvalidCount_Cnt_M_u16	5565
ISDYNABRChkSumValidCount_Cnt_M_u16	55564
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	18187
ISDYNABRMsgCountValidCount_Cnt_M_u16	13842
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	46425
ISDYNABRMsgLenValidCount_Cnt_M_u16	24527
ISDYNABRMsgTimeValidCount_Cnt_M_u16	28067
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	54220
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	62720
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	39029
ISDYNCMM208MsgTimer_mS_M_u32	830432512
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	54220
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	62720

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	44778
ISDYNCMM388MsgTimer_mS_M_u32	4236674304
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	6564
ISDYNVOLChkSumValidCount_Cnt_M_u16	63066
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	21026
ISDYNVOLMsgCountValidCount_Cnt_M_u16	24209
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	45822
ISDYNVOLMsgLenValidCount_Cnt_M_u16	5781
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	36119
ISDYNVOLMsgTimer_mS_M_u32	548685056
IgnOnTimer_mS_M_u32	3696919808
IgnTimeOff_Sec_M_u32	1314815452
ManVehSpd_Kph_M_f32	420.522491
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	126
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	31
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	786511104
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	34
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	759010560
PrevISDATBSI412MsgDLCError_Cnt_M_u08	214
PrevISDATBSI412MsgRxTime_MSec_M_u32	4063675648
PrevISDATBSI432MsgDLCError_Cnt_M_u08	81
PrevISDATBSI432MsgRxTime_MSec_M_u32	1665049856
PrevISDATDIRAMsgTxTime_MSec_M_u32	2849686784
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	47
PrevISDYN2CMMMsgRxTime_MSec_M_u32	326489344
PrevISDYNAASMsgDLCError_Cnt_M_u08	77
PrevISDYNAASMsgRxTime_MSec_M_u32	4190782720
PrevISDYNABRMsgDLCError_Cnt_M_u08	59
PrevISDYNABRMsgRxTime_MSec_M_u32	867337472
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	136
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1256932608
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	28
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3432883456
PrevISDYNVOLMsgDLCError_Cnt_M_u08	178
PrevISDYNVOLMsgRxTime_MSec_M_u32	3771712768
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1424389376
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	446.975098
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	46800
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	34478
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	36869
VitesseVehicleBVRampValidCount_Cnt_M_u16	19875
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	15846
VitesseVehicleBVSigValidCount_Cnt_M_u16	54221
VitesseVehicleBV_Kph_M_f32	137.340302
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	44778
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	38313
VitesseVehiculeRoues_Kph_M_f32	127.093697
k_AASNTCEnableTimeout_mS_u16	3974

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	7243
k_AASNodeTimeout_mS_u16	23982
k_ABSNodeTimeout_mS_u16	7405
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	48162
k_ANGLEVOLANTSigValidThresh_Cnt_u16	55956
k_AngleVolantInvalidThresh_Cnt_u16	16263
k_AngleVolantValidThresh_Cnt_u16	36704
k_BSI552MsgTimeout_mS_u16	47196
k_BSINTCEnableTimeout_mS_u16	40003
k_BSINodeAbsentDiag_Cnt_str.Threshold	18897
k_BSINodeAbsentDiag_Cnt_str.PStep	12072
k_BSINodeAbsentDiag_Cnt_str.NStep	49140
k_BSINodeAbsentTimeout_mS_u16	27447
k_BSINodeTimeout_mS_u16	35928
k_BattOvHi_Volt_f32	16.7964993
k_BattOvLo_Volt_f32	25.6196995
k_BattUvHi_Volt_f32	21.1161995
k_BattUvLo_Volt_f32	18.7252998
k_CAVNTCEnableTimeout_mS_u16	36942
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	39473
k_CAVNodeTimeout_mS_u16	58682
k_CMM388MsgTimeout_mS_u16	43862
k_CMM388NTCEnableTimeout_mS_u16	18562
k_CMMNTCEnableTimeout_mS_u16	22543
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	28885
k_CONSANGLECPKMax_HwDeg_f32	717.81488
k_CONSANGLECPKMin_HwDeg_f32	-643.279175
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	17898
k_CONSANGLECPKSigValidThresh_Cnt_u16	27817
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	52332
k_CPKVehicleSpeedValidThresh_Cnt_u16	5971
k_CityParkInputInvalidThresh_Cnt_u16	16123
k_CityParkInputValidThresh_Cnt_u16	20008
k_ComputerRazGCTSigValidThresh_Cnt_u16	35669
k_CptTemporelSigValidThresh_Cnt_u16	36831
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	52313
k_DMDFCTCPKSigValidThresh_Cnt_u16	46799
k_DMDFCTCPKValidCount_Cnt_u16	52772
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	22871
k_DMDRELAXECPKSigValidThresh_Cnt_u16	54150
k_DMDRelaxeConsistentThresh_Cnt_u16	9284
k_DateValidThresh_Cnt_u16	15929
k_DefaultVehSpd_Kph_f32	5.55109978
k_DiagMuxOnAbsentTimeout_mS_u16	55825
k_EMNodeTimeout_mS_u16	23415
k_ESPNTCEnableTimeout_mS_u16	43975
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	53629
k_EtatMTSigInvalidThresh_Cnt_u16	21776
k_EtatMTSigValidThresh_Cnt_u16	159
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	22827
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	24430
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	53597
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	55520
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	32682
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	43720
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	60564
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	56454
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	56511
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	28503
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	54386
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	26949

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.Threshold	52217
k_ISDATDIRASentDiag_Cnt_str.PStep	24388
k_ISDATDIRASentDiag_Cnt_str.NStep	13533
k_ISDATDIRASentTimeout_mS_u16	3049
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	40934
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	31199
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	6979
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	44221
k_ISDYNAASChkSumValidThresh_Cnt_u16	45068
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	24075
k_ISDYNAASMsgCountValidThresh_Cnt_u16	36114
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	63121
k_ISDYNAASMsgLenValidThresh_Cnt_u16	31362
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	57660
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	14575
k_ISDYNABRChkSumValidThresh_Cnt_u16	34789
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	61308
k_ISDYNABRMsgCountValidThresh_Cnt_u16	43491
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	25623
k_ISDYNABRMsgLenValidThresh_Cnt_u16	73
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	52246
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	62372
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	56425
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	27489
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	53297
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	6232
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	62648
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	58027
k_ISDYNVOLChkSumValidThresh_Cnt_u16	34662
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	16850
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	28896
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	9919
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	40097
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	58791
k_IgnOnTimeout_mS_u16	31959
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	243.172699
k_PowerCutVehSpdLowThresh_Kph_f32	14.5867004
k_PowerCutVehSpdLowTimeout_mS_u16	26082
k_VBattMaxAAS_Volt_f32	17.7737007
k_VBattMaxBSI_Volt_f32	8.4382
k_VBattMaxCAV_Volt_f32	4.86499977
k_VBattMaxCMM388_Volt_f32	6.54680014
k_VBattMaxCMM_Volt_f32	10.8410997
k_VBattMaxESP_Volt_f32	2.95160007
k_VBattMinAAS_Volt_f32	18.030899
k_VBattMinBSI_Volt_f32	2.95160007
k_VBattMinCAV_Volt_f32	5.38999987
k_VBattMinCMM388_Volt_f32	32
k_VBattMinCMM_Volt_f32	24.2063999
k_VBattMinESP_Volt_f32	10.8410997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	45096
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	5203
k_VitesseVehicleBVRampValidThresh_Cnt_u16	59682
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	19802
k_VitesseVehicleBVSigValidThresh_Cnt_u16	16053
k_VitesseVehicleBVSpeedPassThresh_kph_f32	271.906799
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	6299
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	15033
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	839050496
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60573
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1277031168
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	28
target_SrlComInput_Per1_Batt_Volt_f32.value	13.3480997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1299584256
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	60
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.659816206
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1571587328
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4092798208
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2898904320
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4029703424
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	640091392
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3064833280
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	41
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	163857664
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	94
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	187
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2370135296
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	26
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	62
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	115
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2024506624
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	204
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1014113536
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3804808448
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	131
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	167
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	216
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	224
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2272761088
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3465
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.231255442
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	557321
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	39.9404984
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	43666

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1277031168	1277031168	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
CDD_SrlComVehSpd_Kph_G_f32	420.522491	420.522491	✔
CMM388NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	28067	28067	✔
CONSANGLECPK_HwDeg_M_f32	-20.6270008	-20.6270008 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1277031168	1277031168	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1277031168	1277031168	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1277031168	1277031168	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1277031168	1277031168	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1277031168	1277031168	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1277031168	1277031168	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1277031168	1277031168	✔
ESPNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4	4	✔
EffacDefaultDiagTimer_mS_M_u32[1]	748	748	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4	4	✔
ElecIntTimer_mS_M_u32[1]	7	7	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnAbsentTimer_mS_M_u32	1277031168	1277031168	✔
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	15929	15929	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	39029	39029	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	27539	27539	✔
ISDATBSI412MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	35928	35928	✔
ISDATBSI432MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATDIRASentFltAcc_Cnt_M_u16	52217	52217	✔
ISDATDIRASentTimer_mS_M_u32	1277031168	1277031168	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	22871	22871	✔
ISDYN2CMMMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	40384	40384	✔
ISDYNAASMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	28067	28067	✔
ISDYNABRMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	39029	39029	✔
ISDYNCMM208MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	44778	44778	✔
ISDYNCMM388MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	36119	36119	✔
ISDYNVOLMsgTimer_mS_M_u32	1277031168	1277031168	✔
IgnOnTimer_mS_M_u32	3696919808	3696919808	✔
IgnTimeOff_Sec_M_u32	1314815452	1314815452	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	198	198	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1571587328	1571587328	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	210	210	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4092798208	4092798208	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	205	205	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2898904320	2898904320	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	30	30	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4029703424	4029703424	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2849686784	2849686784	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3064833280	3064833280	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	41	41	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	163857664	163857664	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	209	209	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2370135296	2370135296	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	115	115	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2024506624	2024506624	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	204	204	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1014113536	1014113536	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	212	212	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3804808448	3804808448	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2272761088	2272761088	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	446.975098	446.975098	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	137.340302	137.340302	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	127.093697	127.093697	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	28067	28067	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1314815452	1314815452	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-20.6270008	-20.6270008 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.362 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3246613504
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	16557
AASNodeAbsentTimer_mS_M_u32	1402590208
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	23582
ANGLEVOLANTSigValidCount_Cnt_M_u16	31338
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	62482
AngleVolantMsgTimer_mS_M_u32	3246613504
AngleVolantValidCount_Cnt_M_u16	32821
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	802657280
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1131025408
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	175834112
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	417317888
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	59965
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	396854272
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	12641
CAVNodeAbsentTimer_mS_M_u32	2714072064
CDD_SrlComVehSpd_Kph_G_f32	1.28139997
CMM388NTCEnableTimer_mS_M_u32	2004071424
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3498800128
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	10925
CMMNodeAbsentTimer_mS_M_u32	2493105152
CONSANGLECPKSigInvalidCount_Cnt_M_u16	2952
CONSANGLECPKSigValidCount_Cnt_M_u16	6564
CONSANGLECPK_Cnt_M_u16	21639
CONSANGLECPK_HwDeg_M_f32	222.104599
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21639
CPKVehicleSpeedMsgTimer_mS_M_u32	3348784128
CPKVehicleSpeedValidCount_Cnt_M_u16	3494
CityParkInputConsistentCount_Cnt_M_u16	57785
CityParkInputInvalidCount_Cnt_M_u16	20240
CityParkInputMsgTimer_mS_M_u32	1571587328
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	371053568
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	43057

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3243897856
ComputerRazGCTSigValidCount_Cnt_M_u16	47766
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	10636
DMDFCTCPKSigValidCount_Cnt_M_u16	18560
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	31712
DMDRELAXECPKSigValidCount_Cnt_M_u16	18348
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	57325
DateInvalidTimer_mS_M_u32	1131025408
DiagMuxOnAbsentTimer_mS_M_u32	2183865344
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	417317888
ESPNTCEnableTimer_mS_M_u32	2336412672
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	31957
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	45
EffacDefaultDiagTimer_mS_M_u32[1]	98
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1100
ElecIntTimer_mS_M_u32[1]	1153
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2965996544
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	53304
EtatMTSigValidCount_Cnt_M_u16	28752
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	61770
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	11494
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	49478
ISDAT4V2BSI552MsgTimer_mS_M_u32	4062036992
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	19533
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	5357
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	28752
ISDATBSI3F2MsgTimer_mS_M_u32	1953047552
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	57493
ISDATBSI412MsgLenValidCount_Cnt_M_u16	31461
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	53304
ISDATBSI412MsgTimer_mS_M_u32	700539904
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	25393
ISDATBSI432MsgLenValidCount_Cnt_M_u16	53337
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	17706
ISDATDIRASentFltAcc_Cnt_M_u16	34622
ISDATDIRASentTimer_mS_M_u32	3348784128
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	6469
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	32821
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36139
ISDYN2CMMMsgTimer_mS_M_u32	125621248
ISDYNAASChkSumInvalidCount_Cnt_M_u16	19567
ISDYNAASChkSumValidCount_Cnt_M_u16	3291
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	22996
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	51844
ISDYNAASMsgLenValidCount_Cnt_M_u16	57128
ISDYNAASMsgTimeValidCount_Cnt_M_u16	19567
ISDYNAASMsgTimer_mS_M_u32	2666509312
ISDYNABRChkSumInvalidCount_Cnt_M_u16	52730
ISDYNABRChkSumValidCount_Cnt_M_u16	23246
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	15502
ISDYNABRMsgCountValidCount_Cnt_M_u16	9786
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	46759
ISDYNABRMsgLenValidCount_Cnt_M_u16	11779
ISDYNABRMsgTimeValidCount_Cnt_M_u16	21639
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	1378
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	16260
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	28752
ISDYNCMM208MsgTimer_mS_M_u32	3606352896
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	1378
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	16260
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	18291

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	4200543232
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	30150
ISDYNVOLChkSumValidCount_Cnt_M_u16	22114
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	36554
ISDYNVOLMsgCountValidCount_Cnt_M_u16	49214
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	13238
ISDYNVOLMsgLenValidCount_Cnt_M_u16	65458
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	10925
ISDYNVOLMsgTimer_mS_M_u32	1960178688
IgnOnTimer_mS_M_u32	2867016704
IgnTimeOff_Sec_M_u32	810840854
ManVehSpd_Kph_M_f32	604.125916
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	127
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	41
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1779377152
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	149
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3631875072
PrevISDATBSI412MsgDLCError_Cnt_M_u08	225
PrevISDATBSI412MsgRxTime_MSec_M_u32	709784576
PrevISDATBSI432MsgDLCError_Cnt_M_u08	23
PrevISDATBSI432MsgRxTime_MSec_M_u32	1320604672
PrevISDATDIRAMsgTxTime_MSec_M_u32	2472702976
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	95
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1456555008
PrevISDYNAASMsgDLCError_Cnt_M_u08	224
PrevISDYNAASMsgRxTime_MSec_M_u32	3247698944
PrevISDYNABRMsgDLCError_Cnt_M_u08	21
PrevISDYNABRMsgRxTime_MSec_M_u32	81474560
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	79
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2452681728
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	43
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1318704128
PrevISDYNVOLMsgDLCError_Cnt_M_u08	71
PrevISDYNVOLMsgRxTime_MSec_M_u32	42169344
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2633982976
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	302.355988
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	42434
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	19686
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	11811
VitesseVehicleBVRampValidCount_Cnt_M_u16	3079
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	57855
VitesseVehicleBVSigValidCount_Cnt_M_u16	22283
VitesseVehicleBV_Kph_M_f32	151.888794
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	18291
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	10742
VitesseVehiculeRoues_Kph_M_f32	581.303711
k_AASNTCEnableTimeout_mS_u16	47838
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	50000
k_AASNodeTimeout_mS_u16	51174
k_ABSNodeTimeout_mS_u16	6761
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	35212
k_ANGLEVOLANTSigValidThresh_Cnt_u16	38132
k_AngleVolantInvalidThresh_Cnt_u16	61979
k_AngleVolantValidThresh_Cnt_u16	20240
k_BSI552MsgTimeout_mS_u16	19933
k_BSINTCEnableTimeout_mS_u16	44329
k_BSINodeAbsentDiag_Cnt_str.Threshold	20179
k_BSINodeAbsentDiag_Cnt_str.PStep	12556
k_BSINodeAbsentDiag_Cnt_str.NStep	57578
k_BSINodeAbsentTimeout_mS_u16	32778
k_BSINodeTimeout_mS_u16	17706
k_BattOvHi_Volt_f32	28.5688
k_BattOvLo_Volt_f32	7.65329981
k_BattUvHi_Volt_f32	11.8646002
k_BattUvLo_Volt_f32	28.0193005
k_CAVNTCEnableTimeout_mS_u16	33862
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	49055
k_CAVNodeTimeout_mS_u16	60164
k_CMM388MsgTimeout_mS_u16	64429
k_CMM388NTCEnableTimeout_mS_u16	54313
k_CMMNTCEnableTimeout_mS_u16	21061
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	18546
k_CONSANGLECPKMax_HwDeg_f32	609.642517
k_CONSANGLECPKMin_HwDeg_f32	-212.5448
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	33395
k_CONSANGLECPKSigValidThresh_Cnt_u16	42230
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	62380
k_CPKVehicleSpeedValidThresh_Cnt_u16	30072
k_CityParkInputInvalidThresh_Cnt_u16	51776
k_CityParkInputValidThresh_Cnt_u16	57785
k_ComputerRazGCTSigValidThresh_Cnt_u16	20595
k_CptTemporelSigValidThresh_Cnt_u16	2451
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	29095
k_DMDFCTCPKSigValidThresh_Cnt_u16	10499
k_DMDFCTCPKValidCount_Cnt_u16	43333
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	36139
k_DMDRELAXECPKSigValidThresh_Cnt_u16	30047
k_DMDRelaxeConsistentThresh_Cnt_u16	64293
k_DateValidThresh_Cnt_u16	49478
k_DefaultVehSpd_Kph_f32	237.544998
k_DiagMuxOnAbsentTimeout_mS_u16	18237
k_EMNodeTimeout_mS_u16	48205
k_ESPNTCEnableTimeout_mS_u16	25309
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	50810
k_EtatMTSigInvalidThresh_Cnt_u16	7169
k_EtatMTSigValidThresh_Cnt_u16	61461
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	2415
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	40295
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	27674
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	21458
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	9778
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	53017
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	16438
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	55070
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	56245
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	8043
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	63195
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	6305
k_ISDATDIRASentDiag_Cnt_str.Threshold	13150

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	38581
k_ISDATDIRASentDiag_Cnt_str.NStep	24929
k_ISDATDIRASentTimeout_mS_u16	39798
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	14526
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	62482
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	1129
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	2298
k_ISDYNAASChkSumValidThresh_Cnt_u16	54734
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	63374
k_ISDYNAASMsgCountValidThresh_Cnt_u16	8506
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	31614
k_ISDYNAASMsgLenValidThresh_Cnt_u16	49514
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	8444
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	997
k_ISDYNABRChkSumValidThresh_Cnt_u16	36289
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	42301
k_ISDYNABRMsgCountValidThresh_Cnt_u16	44233
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	42413
k_ISDYNABRMsgLenValidThresh_Cnt_u16	14293
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	53808
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	16198
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	65078
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	10957
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	5918
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	30058
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	32520
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	29552
k_ISDYNVOLChkSumValidThresh_Cnt_u16	3072
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	55098
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	58194
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	20148
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	5068
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	764
k_IgnOnTimeout_mS_u16	21740
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	9.18019962
k_PowerCutVehSpdLowThresh_Kph_f32	222.938004
k_PowerCutVehSpdLowTimeout_mS_u16	10186
k_VBattMaxAAS_Volt_f32	10.6417999
k_VBattMaxBSI_Volt_f32	4.68170023
k_VBattMaxCAV_Volt_f32	3.4453001
k_VBattMaxCMM388_Volt_f32	26.3078995
k_VBattMaxCMM_Volt_f32	4.75610018
k_VBattMaxESP_Volt_f32	7.25169992
k_VBattMinAAS_Volt_f32	29.3029995
k_VBattMinBSI_Volt_f32	7.25169992
k_VBattMinCAV_Volt_f32	31.6152992
k_VBattMinCMM388_Volt_f32	22.9563007
k_VBattMinCMM_Volt_f32	8.84280014
k_VBattMinESP_Volt_f32	4.75610018
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	36856
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	43576
k_VitesseVehicleBVRampValidThresh_Cnt_u16	51658
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	20834
k_VitesseVehicleBVSigValidThresh_Cnt_u16	33810
k_VitesseVehicleBVSpeedPassThresh_kph_f32	10.3406
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	27745
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	7365
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1131025408
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	22411
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	4207995392
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	43
target_SrlComInput_Per1_Batt_Volt_f32.value	11.6056004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4191192064
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	165
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.2842758
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4008522752
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	56
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	244929536
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	110457856
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2665583616
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2675815424
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	13
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3496596480
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	193
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4188402688
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	61
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	71
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	88
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	90
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1537381376
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	80
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1508914176
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4045165568
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	546862080
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	97
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	835453952
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3646
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.738602281
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	929551
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	241.126801
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	21116

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4207995392	4207995392	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4207995392	4207995392	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	4207995392	4207995392	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4207995392	4207995392	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4207995392	4207995392	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4207995392	4207995392	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4207995392	4207995392	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	4207995392	4207995392	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	4207995392	4207995392	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4207995392	4207995392	✔
CDD_SrlComVehSpd_Kph_G_f32	604.125916	604.125916	✔
CMM388NTCEnableTimer_mS_M_u32	4207995392	4207995392	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4207995392	4207995392	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4207995392	4207995392	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	21639	21639	✔
CONSANGLECPK_HwDeg_M_f32	222.104599	222.104599 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4207995392	4207995392	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	4207995392	4207995392	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4207995392	4207995392	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4207995392	4207995392	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4207995392	4207995392	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4207995392	4207995392	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	4207995392	4207995392	✔
ESPNTCEnableTimer_mS_M_u32	4207995392	4207995392	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4207995392	4207995392	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	45	45	✔
EffacDefaultDiagTimer_mS_M_u32[1]	98	98	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1100	1100	✔
ElecIntTimer_mS_M_u32[1]	1153	1153	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4207995392	4207995392	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	49478	49478	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4207995392	4207995392	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	28752	28752	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4207995392	4207995392	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	53304	53304	✔
ISDATBSI412MsgTimer_mS_M_u32	4207995392	4207995392	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	17706	17706	✔
ISDATBSI432MsgTimer_mS_M_u32	4207995392	4207995392	✔
ISDATDIRASentFltAcc_Cnt_M_u16	13150	13150	✔
ISDATDIRASentTimer_mS_M_u32	4207995392	4207995392	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36139	36139	✔
ISDYN2CMMMsgTimer_mS_M_u32	4207995392	4207995392	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	19567	19567	✔
ISDYNAASMsgTimer_mS_M_u32	4207995392	4207995392	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	21639	21639	✔
ISDYNABRMsgTimer_mS_M_u32	4207995392	4207995392	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	28752	28752	✔
ISDYNCMM208MsgTimer_mS_M_u32	4207995392	4207995392	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	18291	18291	✔
ISDYNCMM388MsgTimer_mS_M_u32	4207995392	4207995392	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	10925	10925	✔
ISDYNVOLMsgTimer_mS_M_u32	4207995392	4207995392	✔
IgnOnTimer_mS_M_u32	2867016704	2867016704	✔
IgnTimeOff_Sec_M_u32	810840854	810840854	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	153	153	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4008522752	4008522752	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	56	56	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	244929536	244929536	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	75	75	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	110457856	110457856	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	154	154	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2665583616	2665583616	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2472702976	2472702976	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	13	13	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3496596480	3496596480	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	193	193	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4188402688	4188402688	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1537381376	1537381376	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	80	80	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1508914176	1508914176	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4045165568	4045165568	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	241	241	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	546862080	546862080	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	835453952	835453952	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	302.355988	302.355988	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	151.888794	151.888794	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	581.303711	581.303711	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	21639	21639	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	810840854	810840854	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	222.104599	222.104599 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	604.125916	604.125916	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.363 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	967087872
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	34341
AASNodeAbsentTimer_mS_M_u32	690046720
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	38355
ANGLEVOLANTSigValidCount_Cnt_M_u16	38575
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	16374
AngleVolantMsgTimer_mS_M_u32	967087872
AngleVolantValidCount_Cnt_M_u16	19471
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3144156928
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3937437440
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1161672448
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2635036416
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	10102
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1874343680
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	35466
CAVNodeAbsentTimer_mS_M_u32	4112410368
CDD_SrlComVehSpd_Kph_G_f32	581.81781
CMM388NTCEnableTimer_mS_M_u32	4245923584
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	13395712
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	19301
CMMNodeAbsentTimer_mS_M_u32	2447472384
CONSANGLECPKSigInvalidCount_Cnt_M_u16	24214
CONSANGLECPKSigValidCount_Cnt_M_u16	53250
CONSANGLECPK_Cnt_M_u16	27481
CONSANGLECPK_HwDeg_M_f32	-740.94519
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	27481
CPKVehicleSpeedMsgTimer_mS_M_u32	1130338048
CPKVehicleSpeedValidCount_Cnt_M_u16	21410
CityParkInputConsistentCount_Cnt_M_u16	14211
CityParkInputInvalidCount_Cnt_M_u16	23677
CityParkInputMsgTimer_mS_M_u32	4008522752
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4053092096
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	24473

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2288051968
ComputerRazGCTSigValidCount_Cnt_M_u16	24812
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	48393
DMDFCTCPKSigValidCount_Cnt_M_u16	23534
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	48781
DMDRELAXECPKSigValidCount_Cnt_M_u16	46825
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	46439
DateInvalidTimer_mS_M_u32	3937437440
DiagMuxOnAbsentTimer_mS_M_u32	1185765120
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2635036416
ESPNTCEnableTimer_mS_M_u32	1713784576
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	8365
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	66
EffacDefaultDiagTimer_mS_M_u32[1]	78
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	977
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2891069184
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	38851
EtatMTSigValidCount_Cnt_M_u16	17212
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	13648
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	7740
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	35228
ISDAT4V2BSI552MsgTimer_mS_M_u32	2304079616
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	27910
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	48870
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	17212
ISDATBSI3F2MsgTimer_mS_M_u32	3891484416
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	8494
ISDATBSI412MsgLenValidCount_Cnt_M_u16	48638
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	38851
ISDATBSI412MsgTimer_mS_M_u32	2028640000
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	45529
ISDATBSI432MsgLenValidCount_Cnt_M_u16	13857
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	45871
ISDATDIRASentFltAcc_Cnt_M_u16	15603
ISDATDIRASentTimer_mS_M_u32	1130338048
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	38175
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	19471
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52780
ISDYN2CMMMsgTimer_mS_M_u32	1501054720
ISDYNAASChkSumInvalidCount_Cnt_M_u16	60127
ISDYNAASChkSumValidCount_Cnt_M_u16	34139
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	64306
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	2849
ISDYNAASMsgLenValidCount_Cnt_M_u16	35061
ISDYNAASMsgTimeValidCount_Cnt_M_u16	60127
ISDYNAASMsgTimer_mS_M_u32	1990174464
ISDYNABRChkSumInvalidCount_Cnt_M_u16	43454
ISDYNABRChkSumValidCount_Cnt_M_u16	32514
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	22146
ISDYNABRMsgCountValidCount_Cnt_M_u16	30014
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	39225
ISDYNABRMsgLenValidCount_Cnt_M_u16	52965
ISDYNABRMsgTimeValidCount_Cnt_M_u16	27481
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	65227
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	30499
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	17212
ISDYNCMM208MsgTimer_mS_M_u32	2047936256
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	65227
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	30499
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	28245

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2186356480
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	38876
ISDYNVOLChkSumValidCount_Cnt_M_u16	37320
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	1359
ISDYNVOLMsgCountValidCount_Cnt_M_u16	27828
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	49162
ISDYNVOLMsgLenValidCount_Cnt_M_u16	30679
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	19301
ISDYNVOLMsgTimer_mS_M_u32	1575806720
IgnOnTimer_mS_M_u32	2160404224
IgnTimeOff_Sec_M_u32	39474712
ManVehSpd_Kph_M_f32	633.982483
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	128
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	44
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	520181504
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	140
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2537600768
PrevISDATBSI412MsgDLCError_Cnt_M_u08	115
PrevISDATBSI412MsgRxTime_MSec_M_u32	3213059840
PrevISDATBSI432MsgDLCError_Cnt_M_u08	218
PrevISDATBSI432MsgRxTime_MSec_M_u32	3955902208
PrevISDATDIRAMsgTxTime_MSec_M_u32	3561449216
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	92
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2302342912
PrevISDYNAASMsgDLCError_Cnt_M_u08	64
PrevISDYNAASMsgRxTime_MSec_M_u32	4021479168
PrevISDYNABRMsgDLCError_Cnt_M_u08	170
PrevISDYNABRMsgRxTime_MSec_M_u32	1390225152
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	154
PrevISDYNCMM208MsgRxTime_MSec_M_u32	836495104
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	59
PrevISDYNCMM388MsgRxTime_MSec_M_u32	941704960
PrevISDYNVOLMsgDLCError_Cnt_M_u08	76
PrevISDYNVOLMsgRxTime_MSec_M_u32	1256482560
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2536544000
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	237.508698
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	61799
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	47035
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	7236
VitesseVehicleBVRampValidCount_Cnt_M_u16	15960
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	51248
VitesseVehicleBVSigValidCount_Cnt_M_u16	50380
VitesseVehicleBV_Kph_M_f32	645.325073
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	28245
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	649
VitesseVehiculeRoues_Kph_M_f32	130.074493
k_AASNTCEnableTimeout_mS_u16	21588
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	44734
k_AASNodeTimeout_mS_u16	18107
k_ABSNodeTimeout_mS_u16	40562
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	27336
k_ANGLEVOLANTSigValidThresh_Cnt_u16	5200
k_AngleVolantInvalidThresh_Cnt_u16	22747
k_AngleVolantValidThresh_Cnt_u16	23677
k_BSI552MsgTimeout_mS_u16	62164
k_BSINTCEnableTimeout_mS_u16	46065
k_BSINodeAbsentDiag_Cnt_str.Threshold	8183
k_BSINodeAbsentDiag_Cnt_str.PStep	49803
k_BSINodeAbsentDiag_Cnt_str.NStep	35891
k_BSINodeAbsentTimeout_mS_u16	31758
k_BSINodeTimeout_mS_u16	45871
k_BattOvHi_Volt_f32	10.7060003
k_BattOvLo_Volt_f32	24.2896996
k_BattUvHi_Volt_f32	7.0539999
k_BattUvLo_Volt_f32	29.1438999
k_CAVNTCEnableTimeout_mS_u16	5339
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	22480
k_CAVNodeTimeout_mS_u16	45090
k_CMM388MsgTimeout_mS_u16	21797
k_CMM388NTCEnableTimeout_mS_u16	48049
k_CMMNTCEnableTimeout_mS_u16	15134
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	38677
k_CONSANGLECPKMax_HwDeg_f32	233.957901
k_CONSANGLECPKMin_HwDeg_f32	-530.070984
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	48469
k_CONSANGLECPKSigValidThresh_Cnt_u16	37257
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	23401
k_CPKVehicleSpeedValidThresh_Cnt_u16	44677
k_CityParkInputInvalidThresh_Cnt_u16	19692
k_CityParkInputValidThresh_Cnt_u16	14211
k_ComputerRazGCTSigValidThresh_Cnt_u16	30868
k_CptTemporelSigValidThresh_Cnt_u16	63732
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	26681
k_DMDFCTCPKSigValidThresh_Cnt_u16	56805
k_DMDFCTCPKValidCount_Cnt_u16	2654
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	52780
k_DMDRELAXECPKSigValidThresh_Cnt_u16	4433
k_DMDRelaxeConsistentThresh_Cnt_u16	6143
k_DateValidThresh_Cnt_u16	35228
k_DefaultVehSpd_Kph_f32	126.047699
k_DiagMuxOnAbsentTimeout_mS_u16	60215
k_EMNodeTimeout_mS_u16	41031
k_ESPNTCEnableTimeout_mS_u16	58902
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	15613
k_EtatMTSigInvalidThresh_Cnt_u16	39849
k_EtatMTSigValidThresh_Cnt_u16	39725
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	58912
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	13816
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	23648
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	43639
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	57111
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	26018
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	28362
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	30162
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	22605
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	39597
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	29
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	64009
k_ISDATDIRASentDiag_Cnt_str.Threshold	16715

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	40862
k_ISDATDIRASentDiag_Cnt_str.NStep	15667
k_ISDATDIRASentTimeout_mS_u16	12618
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	19890
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	16374
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	12658
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	63678
k_ISDYNAASChkSumValidThresh_Cnt_u16	3586
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	9602
k_ISDYNAASMsgCountValidThresh_Cnt_u16	33854
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	45362
k_ISDYNAASMsgLenValidThresh_Cnt_u16	27183
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	36920
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	10623
k_ISDYNABRChkSumValidThresh_Cnt_u16	10155
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	63094
k_ISDYNABRMsgCountValidThresh_Cnt_u16	15250
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	55909
k_ISDYNABRMsgLenValidThresh_Cnt_u16	61357
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	10077
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	13531
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	35915
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	31238
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	25811
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	42415
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	44181
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	38045
k_ISDYNVOLChkSumValidThresh_Cnt_u16	13997
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	58750
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	62838
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	3151
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	18632
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	7290
k_IgnOnTimeout_mS_u16	57385
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	125.641998
k_PowerCutVehSpdLowThresh_Kph_f32	132.3685
k_PowerCutVehSpdLowTimeout_mS_u16	48528
k_VBattMaxAAS_Volt_f32	15.6000004
k_VBattMaxBSI_Volt_f32	3.38070011
k_VBattMaxCAV_Volt_f32	9.95810032
k_VBattMaxCMM388_Volt_f32	22.6457996
k_VBattMaxCMM_Volt_f32	14.3080997
k_VBattMaxESP_Volt_f32	4.33970022
k_VBattMinAAS_Volt_f32	0.318699986
k_VBattMinBSI_Volt_f32	4.33970022
k_VBattMinCAV_Volt_f32	1.21270001
k_VBattMinCMM388_Volt_f32	5.34030008
k_VBattMinCMM_Volt_f32	1.50010002
k_VBattMinESP_Volt_f32	14.3080997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	45060
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	36100
k_VitesseVehicleBVRampValidThresh_Cnt_u16	21583
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	41160
k_VitesseVehicleBVSigValidThresh_Cnt_u16	62584
k_VitesseVehicleBVSpeedPassThresh_kph_f32	283.515503
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	55690
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	33822
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3937437440
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	41596
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2471757056
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	59
target_SrlComInput_Per1_Batt_Volt_f32.value	10.3935003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2906470144
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	63
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.664331138
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1554458368
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1445119744
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	112092928
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	373950208
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	754296576
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	103
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4071704320
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	259843840
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	212
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	97
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	604440320
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	77
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	79
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	150
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	169
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	192
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	78
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3885901568
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	228
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2056898304
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2225432320
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1397405440
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3453
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.195171341
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	651368
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	51.0523987
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	21305

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2471757056	2471757056	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2471757056	2471757056	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2471757056	2471757056	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2471757056	2471757056	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2471757056	2471757056	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2471757056	2471757056	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2471757056	2471757056	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2471757056	2471757056	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2471757056	2471757056	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2471757056	2471757056	✔
CDD_SrlComVehSpd_Kph_G_f32	633.982483	633.982483	✔
CMM388NTCEnableTimer_mS_M_u32	2471757056	2471757056	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2471757056	2471757056	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2471757056	2471757056	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	27481	27481	✔
CONSANGLECPK_HwDeg_M_f32	-740.94519	-740.94519 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2471757056	2471757056	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2471757056	2471757056	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2471757056	2471757056	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2471757056	2471757056	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2471757056	2471757056	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2471757056	2471757056	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2471757056	2471757056	✔
ESPNTCEnableTimer_mS_M_u32	2471757056	2471757056	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2471757056	2471757056	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	66	66	✔
EffacDefaultDiagTimer_mS_M_u32[1]	78	78	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	97	97	✔
ElecIntTimer_mS_M_u32[1]	977	977	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2471757056	2471757056	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	35228	35228	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2471757056	2471757056	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	17212	17212	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2471757056	2471757056	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	38851	38851	✔
ISDATBSI412MsgTimer_mS_M_u32	2471757056	2471757056	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	45871	45871	✔
ISDATBSI432MsgTimer_mS_M_u32	2471757056	2471757056	✔
ISDATDIRASentFltAcc_Cnt_M_u16	16715	16715	✔
ISDATDIRASentTimer_mS_M_u32	2471757056	2471757056	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52780	52780	✔
ISDYN2CMMMsgTimer_mS_M_u32	2471757056	2471757056	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	60127	60127	✔
ISDYNAASMsgTimer_mS_M_u32	2471757056	2471757056	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	27481	27481	✔
ISDYNABRMsgTimer_mS_M_u32	2471757056	2471757056	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	17212	17212	✔
ISDYNCMM208MsgTimer_mS_M_u32	2471757056	2471757056	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	28245	28245	✔
ISDYNCMM388MsgTimer_mS_M_u32	2471757056	2471757056	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	19301	19301	✔
ISDYNVOLMsgTimer_mS_M_u32	2471757056	2471757056	✔
IgnOnTimer_mS_M_u32	2160404224	2160404224	✔
IgnTimeOff_Sec_M_u32	39474712	39474712	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	168	168	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1554458368	1554458368	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	133	133	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1445119744	1445119744	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	69	69	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	112092928	112092928	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	144	144	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	373950208	373950208	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3561449216	3561449216	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	103	103	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4071704320	4071704320	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	67	67	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	259843840	259843840	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	97	97	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	604440320	604440320	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	78	78	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3885901568	3885901568	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	228	228	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2056898304	2056898304	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	30	30	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2225432320	2225432320	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1397405440	1397405440	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	237.508698	237.508698	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	645.325073	645.325073	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	130.074493	130.074493	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	27481	27481	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	39474712	39474712	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-740.94519	-740.94519 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.364 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	531613952
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	1076
AASNodeAbsentTimer_mS_M_u32	848427264
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	30038
ANGLEVOLANTSigValidCount_Cnt_M_u16	61588
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	29837
AngleVolantMsgTimer_mS_M_u32	531613952
AngleVolantValidCount_Cnt_M_u16	19059
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	353286400
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	849033472
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3172067584
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	158443776
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	52241
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4284508416
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	16578
CAVNodeAbsentTimer_mS_M_u32	863508736
CDD_SrlComVehSpd_Kph_G_f32	173.8255
CMM388NTCEnableTimer_mS_M_u32	488069376
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1284905216
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	11769
CMMNodeAbsentTimer_mS_M_u32	4107512064
CONSANGLECPKSigInvalidCount_Cnt_M_u16	41519
CONSANGLECPKSigValidCount_Cnt_M_u16	37501
CONSANGLECPK_Cnt_M_u16	24716
CONSANGLECPK_HwDeg_M_f32	104.430397
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	24716
CPKVehicleSpeedMsgTimer_mS_M_u32	1866647808
CPKVehicleSpeedValidCount_Cnt_M_u16	19689
CityParkInputConsistentCount_Cnt_M_u16	45447
CityParkInputInvalidCount_Cnt_M_u16	43092
CityParkInputMsgTimer_mS_M_u32	2667924992
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1587935488
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	51528

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1691261184
ComputerRazGCTSigValidCount_Cnt_M_u16	52792
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	60736
DMDFCTCPKSigValidCount_Cnt_M_u16	14021
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	29664
DMDRELAXECPKSigValidCount_Cnt_M_u16	41630
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	38792
DateInvalidTimer_mS_M_u32	849033472
DiagMuxOnAbsentTimer_mS_M_u32	587106560
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	158443776
ESPNTCEnableTimer_mS_M_u32	1606351104
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	259
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	101
EffacDefaultDiagTimer_mS_M_u32[1]	105
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	6
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2966055168
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	10057
EtatMTSigValidCount_Cnt_M_u16	515
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	48825
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	57991
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	33251
ISDAT4V2BSI552MsgTimer_mS_M_u32	3353848064
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	53667
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	50693
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	515
ISDATBSI3F2MsgTimer_mS_M_u32	1047824640
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	6404
ISDATBSI412MsgLenValidCount_Cnt_M_u16	12246
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	10057
ISDATBSI412MsgTimer_mS_M_u32	3374696704
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	59405
ISDATBSI432MsgLenValidCount_Cnt_M_u16	57879
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	46735
ISDATDIRASentFltAcc_Cnt_M_u16	11891
ISDATDIRASentTimer_mS_M_u32	1866647808
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	18562
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	19059
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	49019
ISDYN2CMMMsgTimer_mS_M_u32	1033959680
ISDYNAASChkSumInvalidCount_Cnt_M_u16	7870
ISDYNAASChkSumValidCount_Cnt_M_u16	155
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	43694
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	7697
ISDYNAASMsgLenValidCount_Cnt_M_u16	48647
ISDYNAASMsgTimeValidCount_Cnt_M_u16	7870
ISDYNAASMsgTimer_mS_M_u32	1124292864
ISDYNABRChkSumInvalidCount_Cnt_M_u16	37784
ISDYNABRChkSumValidCount_Cnt_M_u16	50814
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	8057
ISDYNABRMsgCountValidCount_Cnt_M_u16	42902
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	59882
ISDYNABRMsgLenValidCount_Cnt_M_u16	49272
ISDYNABRMsgTimeValidCount_Cnt_M_u16	24716
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	6154
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	15043
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	515
ISDYNCMM208MsgTimer_mS_M_u32	1895807232
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	6154
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	15043
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	61161

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3359693056
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	5541
ISDYNVOLChkSumValidCount_Cnt_M_u16	53875
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	59318
ISDYNVOLMsgCountValidCount_Cnt_M_u16	15803
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	25416
ISDYNVOLMsgLenValidCount_Cnt_M_u16	52469
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	11769
ISDYNVOLMsgTimer_mS_M_u32	3334117632
IgnOnTimer_mS_M_u32	3662993664
IgnTimeOff_Sec_M_u32	976128812
ManVehSpd_Kph_M_f32	0
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	129
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	170
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3723659520
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	155
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3610044672
PrevISDATBSI412MsgDLCError_Cnt_M_u08	230
PrevISDATBSI412MsgRxTime_MSec_M_u32	1493506304
PrevISDATBSI432MsgDLCError_Cnt_M_u08	46
PrevISDATBSI432MsgRxTime_MSec_M_u32	2994927872
PrevISDATDIRAMsgTxTime_MSec_M_u32	3018397952
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	25
PrevISDYN2CMMMsgRxTime_MSec_M_u32	49883392
PrevISDYNAASMsgDLCError_Cnt_M_u08	109
PrevISDYNAASMsgRxTime_MSec_M_u32	1454414080
PrevISDYNABRMsgDLCError_Cnt_M_u08	158
PrevISDYNABRMsgRxTime_MSec_M_u32	4247574784
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	85
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1377933568
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	156
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3113351424
PrevISDYNVOLMsgDLCError_Cnt_M_u08	77
PrevISDYNVOLMsgRxTime_MSec_M_u32	2809010432
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1234946304
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	572.105225
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	42631
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	54013
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	61516
VitesseVehicleBVRampValidCount_Cnt_M_u16	22146
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	667
VitesseVehicleBVSigValidCount_Cnt_M_u16	22425
VitesseVehicleBV_Kph_M_f32	176.221603
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	61161
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	22591
VitesseVehiculeRoues_Kph_M_f32	264.101593
k_AASNTCEnableTimeout_mS_u16	35167
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	55962
k_AASNodeTimeout_mS_u16	55805
k_ABSNodeTimeout_mS_u16	33265
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	32884
k_ANGLEVOLANTSigValidThresh_Cnt_u16	51646
k_AngleVolantInvalidThresh_Cnt_u16	43681
k_AngleVolantValidThresh_Cnt_u16	43092
k_BSI552MsgTimeout_mS_u16	17122
k_BSINTCEnableTimeout_mS_u16	47845
k_BSINodeAbsentDiag_Cnt_str.Threshold	48135
k_BSINodeAbsentDiag_Cnt_str.PStep	63627
k_BSINodeAbsentDiag_Cnt_str.NStep	4050
k_BSINodeAbsentTimeout_mS_u16	20837
k_BSINodeTimeout_mS_u16	46735
k_BattOvHi_Volt_f32	19.0907001
k_BattOvLo_Volt_f32	3.91729999
k_BattUvHi_Volt_f32	25.9584007
k_BattUvLo_Volt_f32	31.5
k_CAVNTCEnableTimeout_mS_u16	21410
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	59448
k_CAVNodeTimeout_mS_u16	24603
k_CMM388MsgTimeout_mS_u16	19252
k_CMM388NTCEnableTimeout_mS_u16	50720
k_CMMNTCEnableTimeout_mS_u16	53371
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	28971
k_CONSANGLECPKMax_HwDeg_f32	363.320496
k_CONSANGLECPKMin_HwDeg_f32	-701.573792
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	46569
k_CONSANGLECPKSigValidThresh_Cnt_u16	24383
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	17435
k_CPKVehicleSpeedValidThresh_Cnt_u16	26899
k_CityParkInputInvalidThresh_Cnt_u16	54
k_CityParkInputValidThresh_Cnt_u16	45447
k_ComputerRazGCTSigValidThresh_Cnt_u16	59809
k_CptTemporelSigValidThresh_Cnt_u16	32899
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	12522
k_DMDFCTCPKSigValidThresh_Cnt_u16	18296
k_DMDFCTCPKValidCount_Cnt_u16	1593
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	49019
k_DMDRELAXECPKSigValidThresh_Cnt_u16	53056
k_DMDRelaxeConsistentThresh_Cnt_u16	47966
k_DateValidThresh_Cnt_u16	33251
k_DefaultVehSpd_Kph_f32	160.329697
k_DiagMuxOnAbsentTimeout_mS_u16	3930
k_EMNodeTimeout_mS_u16	55656
k_ESPNTCEnableTimeout_mS_u16	22702
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	34387
k_EtatMTSigInvalidThresh_Cnt_u16	36059
k_EtatMTSigValidThresh_Cnt_u16	15361
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	31882
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	7843
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	50508
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	58012
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	53182
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	41240
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	29830
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	1872
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	57889
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	10880
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	20209
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	51897
k_ISDATDIRASentDiag_Cnt_str.Threshold	47919

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	26416
k_ISDATDIRASentDiag_Cnt_str.NStep	62887
k_ISDATDIRASentTimeout_mS_u16	14212
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	25514
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	29837
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	24298
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	23192
k_ISDYNAASChkSumValidThresh_Cnt_u16	52606
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	26233
k_ISDYNAASMsgCountValidThresh_Cnt_u16	11926
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	63148
k_ISDYNAASMsgLenValidThresh_Cnt_u16	14609
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	25830
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	27744
k_ISDYNABRChkSumValidThresh_Cnt_u16	20334
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	4881
k_ISDYNABRMsgCountValidThresh_Cnt_u16	62607
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	13561
k_ISDYNABRMsgLenValidThresh_Cnt_u16	18435
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	46770
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	9627
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	42249
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	8096
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	48214
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	30612
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	14636
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	16363
k_ISDYNVOLChkSumValidThresh_Cnt_u16	34301
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	54364
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	4242
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	8245
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	5103
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	56241
k_IgnOnTimeout_mS_u16	51159
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	105.677902
k_PowerCutVehSpdLowThresh_Kph_f32	54.2168999
k_PowerCutVehSpdLowTimeout_mS_u16	40059
k_VBattMaxAAS_Volt_f32	13.2859001
k_VBattMaxBSI_Volt_f32	21.5188007
k_VBattMaxCAV_Volt_f32	0.342299998
k_VBattMaxCMM388_Volt_f32	26.4892006
k_VBattMaxCMM_Volt_f32	23.5723
k_VBattMaxESP_Volt_f32	21.191
k_VBattMinAAS_Volt_f32	14.3924999
k_VBattMinBSI_Volt_f32	21.191
k_VBattMinCAV_Volt_f32	31.3974991
k_VBattMinCMM388_Volt_f32	5.25279999
k_VBattMinCMM_Volt_f32	30.4393997
k_VBattMinESP_Volt_f32	23.5723
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	10380
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	270
k_VitesseVehicleBVRampValidThresh_Cnt_u16	44726
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	22899
k_VitesseVehicleBVSigValidThresh_Cnt_u16	56868
k_VitesseVehicleBVSpeedPassThresh_kph_f32	484.938202
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	1986
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	14968
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	849033472
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	3700
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1274459136
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	156
target_SrlComInput_Per1_Batt_Volt_f32.value	18.5293999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	822962432
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	190
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.918607116
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1699141888
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1671395584
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1367873792
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	385923328
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2617858304
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3366058240
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2227869952
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	205
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	24
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1520810240
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	67
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	68
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	94
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2683689216
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	63863040
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	389486848
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	43
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	174
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	200
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	207
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2206656768
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1266
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.419140786
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	976446
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	120.871498
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	26345

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1274459136	1274459136	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1274459136	1274459136	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1274459136	1274459136	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1274459136	1274459136	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1274459136	1274459136	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1274459136	1274459136	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1274459136	1274459136	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	48135	48135	✔
BSINodeAbsentTimer_mS_M_u32	1274459136	1274459136	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1274459136	1274459136	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1274459136	1274459136	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1274459136	1274459136	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1274459136	1274459136	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1274459136	1274459136	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	24716	24716	✔
CONSANGLECPK_HwDeg_M_f32	104.430397	104.430397 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1274459136	1274459136	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1274459136	1274459136	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1274459136	1274459136	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1274459136	1274459136	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1274459136	1274459136	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1274459136	1274459136	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1274459136	1274459136	✔
ESPNTCEnableTimer_mS_M_u32	1274459136	1274459136	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1274459136	1274459136	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	101	101	✔
EffacDefaultDiagTimer_mS_M_u32[1]	105	105	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4	4	✔
ElecIntTimer_mS_M_u32[1]	6	6	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1274459136	1274459136	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	33251	33251	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1274459136	1274459136	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	515	515	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1274459136	1274459136	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	10057	10057	✔
ISDATBSI412MsgTimer_mS_M_u32	1274459136	1274459136	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	46735	46735	✔
ISDATBSI432MsgTimer_mS_M_u32	1274459136	1274459136	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1274459136	1274459136	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	49019	49019	✔
ISDYN2CMMMsgTimer_mS_M_u32	1274459136	1274459136	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	7870	7870	✔
ISDYNAASMsgTimer_mS_M_u32	1274459136	1274459136	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	24716	24716	✔
ISDYNABRMsgTimer_mS_M_u32	1274459136	1274459136	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	515	515	✔
ISDYNCMM208MsgTimer_mS_M_u32	1274459136	1274459136	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	61161	61161	✔
ISDYNCMM388MsgTimer_mS_M_u32	1274459136	1274459136	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	11769	11769	✔
ISDYNVOLMsgTimer_mS_M_u32	1274459136	1274459136	✔
IgnOnTimer_mS_M_u32	3662993664	3662993664	✔
IgnTimeOff_Sec_M_u32	976128812	976128812	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	95	95	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1699141888	1699141888	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	29	29	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1671395584	1671395584	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	86	86	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1367873792	1367873792	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	242	242	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	385923328	385923328	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3018397952	3018397952	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	246	246	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3366058240	3366058240	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	46	46	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2227869952	2227869952	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	24	24	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1520810240	1520810240	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	143	143	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2683689216	2683689216	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	210	210	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	63863040	63863040	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	81	81	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	389486848	389486848	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2206656768	2206656768	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	572.105225	572.105225	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	176.221603	176.221603	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	264.101593	264.101593	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	24716	24716	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	976128812	976128812	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	104.430397	104.430397 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.365 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3136514048
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	48997
AASNodeAbsentTimer_mS_M_u32	118282240
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	5630
ANGLEVOLANTSigValidCount_Cnt_M_u16	63237
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	4698
AngleVolantMsgTimer_mS_M_u32	3136514048
AngleVolantValidCount_Cnt_M_u16	62247
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1117165568
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3153139712
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2471299072
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3710765056
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	48589
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	643926016
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	27195
CAVNodeAbsentTimer_mS_M_u32	3302651904
CDD_SrlComVehSpd_Kph_G_f32	343.202087
CMM388NTCEnableTimer_mS_M_u32	2499590144
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1904244736
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	27222
CMMNodeAbsentTimer_mS_M_u32	587712512
CONSANGLECPKSigInvalidCount_Cnt_M_u16	57972
CONSANGLECPKSigValidCount_Cnt_M_u16	42059
CONSANGLECPK_Cnt_M_u16	13854
CONSANGLECPK_HwDeg_M_f32	-724.341797
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	13854
CPKVehicleSpeedMsgTimer_mS_M_u32	3627706368
CPKVehicleSpeedValidCount_Cnt_M_u16	15949
CityParkInputConsistentCount_Cnt_M_u16	3563
CityParkInputInvalidCount_Cnt_M_u16	43654
CityParkInputMsgTimer_mS_M_u32	1699141888
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3536902144
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	49193

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2866214912
ComputerRazGCTSigValidCount_Cnt_M_u16	48088
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	35778
DMDFCTCPKSigValidCount_Cnt_M_u16	8689
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	49760
DMDRELAXECPKSigValidCount_Cnt_M_u16	35047
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	42601
DateInvalidTimer_mS_M_u32	3153139712
DiagMuxOnAbsentTimer_mS_M_u32	1543972864
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3710765056
ESPNTCEnableTimer_mS_M_u32	1938151424
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	29689
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	9
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	102
ElecIntTimer_mS_M_u32[1]	106
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	975407104
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	3941
EtatMTSigValidCount_Cnt_M_u16	49656
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	13526
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	23597
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	14487
ISDAT4V2BSI552MsgTimer_mS_M_u32	4190881792
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	20440
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	21875
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	49656
ISDATBSI3F2MsgTimer_mS_M_u32	1638213632
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	36532
ISDATBSI412MsgLenValidCount_Cnt_M_u16	60671
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	3941
ISDATBSI412MsgTimer_mS_M_u32	378628096
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	35866
ISDATBSI432MsgLenValidCount_Cnt_M_u16	8381
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	31956
ISDATDIRASentFltAcc_Cnt_M_u16	42280
ISDATDIRASentTimer_mS_M_u32	3627706368
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	54844
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	62247
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	49425
ISDYN2CMMMsgTimer_mS_M_u32	3789543424
ISDYNAASChkSumInvalidCount_Cnt_M_u16	6087
ISDYNAASChkSumValidCount_Cnt_M_u16	17646
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	32374
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	52814
ISDYNAASMsgLenValidCount_Cnt_M_u16	8493
ISDYNAASMsgTimeValidCount_Cnt_M_u16	6087
ISDYNAASMsgTimer_mS_M_u32	3543709696
ISDYNABRChkSumInvalidCount_Cnt_M_u16	39608
ISDYNABRChkSumValidCount_Cnt_M_u16	62663
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	49558
ISDYNABRMsgCountValidCount_Cnt_M_u16	64509
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	46915
ISDYNABRMsgLenValidCount_Cnt_M_u16	50778
ISDYNABRMsgTimeValidCount_Cnt_M_u16	13854
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	33224
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	36290
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	49656
ISDYNCMM208MsgTimer_mS_M_u32	851679232
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	33224
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	36290
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	24005

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	427833344
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	57362
ISDYNVOLChkSumValidCount_Cnt_M_u16	15465
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	62560
ISDYNVOLMsgCountValidCount_Cnt_M_u16	25871
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	41258
ISDYNVOLMsgLenValidCount_Cnt_M_u16	30433
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	27222
ISDYNVOLMsgTimer_mS_M_u32	890435584
IgnOnTimer_mS_M_u32	860108800
IgnTimeOff_Sec_M_u32	1706369505
ManVehSpd_Kph_M_f32	655.340027
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	130
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	158
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4213909504
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	106
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1895565312
PrevISDATBSI412MsgDLCError_Cnt_M_u08	72
PrevISDATBSI412MsgRxTime_MSec_M_u32	3358816256
PrevISDATBSI432MsgDLCError_Cnt_M_u08	114
PrevISDATBSI432MsgRxTime_MSec_M_u32	2335823872
PrevISDATDIRAMsgTxTime_MSec_M_u32	1200060416
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	50
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1855408128
PrevISDYNAASMsgDLCError_Cnt_M_u08	55
PrevISDYNAASMsgRxTime_MSec_M_u32	3710973952
PrevISDYNABRMsgDLCError_Cnt_M_u08	239
PrevISDYNABRMsgRxTime_MSec_M_u32	716978176
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	234
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4007524352
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	166
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1913444352
PrevISDYNVOLMsgDLCError_Cnt_M_u08	228
PrevISDYNVOLMsgRxTime_MSec_M_u32	3237509120
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3979307008
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	466.170685
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	36076
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	14923
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	925
VitesseVehicleBVRampValidCount_Cnt_M_u16	956
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	49711
VitesseVehicleBVSigValidCount_Cnt_M_u16	5622
VitesseVehicleBV_Kph_M_f32	205.258698
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	24005
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	54403
VitesseVehiculeRoues_Kph_M_f32	73.655899
k_AASNTCEnableTimeout_mS_u16	51109
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	40626
k_AASNodeTimeout_mS_u16	9547
k_ABSNodeTimeout_mS_u16	53679
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	7909
k_ANGLEVOLANTSigValidThresh_Cnt_u16	50632
k_AngleVolantInvalidThresh_Cnt_u16	28447
k_AngleVolantValidThresh_Cnt_u16	43654
k_BSI552MsgTimeout_mS_u16	24730
k_BSINTCEnableTimeout_mS_u16	29586
k_BSINodeAbsentDiag_Cnt_str.Threshold	52391
k_BSINodeAbsentDiag_Cnt_str.PStep	31178
k_BSINodeAbsentDiag_Cnt_str.NStep	30672
k_BSINodeAbsentTimeout_mS_u16	56274
k_BSINodeTimeout_mS_u16	31956
k_BattOvHi_Volt_f32	17.9171009
k_BattOvLo_Volt_f32	25.8274994
k_BattUvHi_Volt_f32	18.9596004
k_BattUvLo_Volt_f32	12.6410999
k_CAVNTCEnableTimeout_mS_u16	24732
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	52185
k_CAVNodeTimeout_mS_u16	22704
k_CMM388MsgTimeout_mS_u16	60005
k_CMM388NTCEnableTimeout_mS_u16	10657
k_CMMNTCEnableTimeout_mS_u16	45904
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	14783
k_CONSANGLECPKMax_HwDeg_f32	545.290283
k_CONSANGLECPKMin_HwDeg_f32	-299.074799
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	2245
k_CONSANGLECPKSigValidThresh_Cnt_u16	49027
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	57073
k_CPKVehicleSpeedValidThresh_Cnt_u16	39559
k_CityParkInputInvalidThresh_Cnt_u16	19678
k_CityParkInputValidThresh_Cnt_u16	3563
k_ComputerRazGCTSigValidThresh_Cnt_u16	32734
k_CptTemporelSigValidThresh_Cnt_u16	40441
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	57923
k_DMDFCTCPKSigValidThresh_Cnt_u16	12634
k_DMDFCTCPKValidCount_Cnt_u16	44885
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	49425
k_DMDRELAXECPKSigValidThresh_Cnt_u16	1152
k_DMDRelaxeConsistentThresh_Cnt_u16	14374
k_DateValidThresh_Cnt_u16	14487
k_DefaultVehSpd_Kph_f32	19.5216007
k_DiagMuxOnAbsentTimeout_mS_u16	57780
k_EMNodeTimeout_mS_u16	24777
k_ESPNTCEnableTimeout_mS_u16	53879
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	39495
k_EtatMTSigInvalidThresh_Cnt_u16	31471
k_EtatMTSigValidThresh_Cnt_u16	24638
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	45476
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	36375
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	9884
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	16621
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	23624
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	18040
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	2735
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	54546
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	60894
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	43074
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	23981
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	56980
k_ISDATDIRASentDiag_Cnt_str.Threshold	4736

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	39317
k_ISDATDIRASentDiag_Cnt_str.NStep	39046
k_ISDATDIRASentTimeout_mS_u16	24308
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	6081
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	4698
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	44995
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	17848
k_ISDYNAASChkSumValidThresh_Cnt_u16	57287
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	60566
k_ISDYNAASMsgCountValidThresh_Cnt_u16	26365
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	49532
k_ISDYNAASMsgLenValidThresh_Cnt_u16	22543
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	37968
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	34785
k_ISDYNABRChkSumValidThresh_Cnt_u16	29048
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	59597
k_ISDYNABRMsgCountValidThresh_Cnt_u16	38676
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	21846
k_ISDYNABRMsgLenValidThresh_Cnt_u16	40697
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	40107
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	24496
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16037
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	41058
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	16638
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	25093
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	22526
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	30207
k_ISDYNVOLChkSumValidThresh_Cnt_u16	18058
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	40430
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	26251
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	54433
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	15412
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	58157
k_IgnOnTimeout_mS_u16	36411
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	3.97720003
k_PowerCutVehSpdLowThresh_Kph_f32	70.3600006
k_PowerCutVehSpdLowTimeout_mS_u16	65105
k_VBattMaxAAS_Volt_f32	10.4816999
k_VBattMaxBSI_Volt_f32	6.47230005
k_VBattMaxCAV_Volt_f32	25.5613003
k_VBattMaxCMM388_Volt_f32	29.6851006
k_VBattMaxCMM_Volt_f32	29.2513008
k_VBattMaxESP_Volt_f32	4.39410019
k_VBattMinAAS_Volt_f32	30.2038002
k_VBattMinBSI_Volt_f32	4.39410019
k_VBattMinCAV_Volt_f32	31.7502995
k_VBattMinCMM388_Volt_f32	7.12400007
k_VBattMinCMM_Volt_f32	23.4419003
k_VBattMinESP_Volt_f32	29.2513008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	53531
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	43606
k_VitesseVehicleBVRampValidThresh_Cnt_u16	40800
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	42857
k_VitesseVehicleBVSigValidThresh_Cnt_u16	15380
k_VitesseVehicleBVSpeedPassThresh_kph_f32	166.834396
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	5435
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	45018
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3153139712
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	5160
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1267377920
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	166
target_SrlComInput_Per1_Batt_Volt_f32.value	16.8507004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2237302784
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	56
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.768558264
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3664656384
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2313443328
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2863298560
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2227214336
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1613150208
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2229065728
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	987953152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	97
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	135
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	230
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	239
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	247
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2379323392
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	133
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	184
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	186
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	196
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	213
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	215
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2791389184
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	156
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	626481152
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	234
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3583866880
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	19
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	133
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	172
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	196
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1408108544
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3617
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0414256454
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	435897
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	80.6464005
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	21446

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1267377920	1267377920	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1267377920	1267377920	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	52391	52391	✔
BSINodeAbsentTimer_mS_M_u32	1267377920	1267377920	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1267377920	1267377920	✔
CDD_SrlComVehSpd_Kph_G_f32	655.340027	655.340027	✔
CMM388NTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1267377920	1267377920	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	13854	13854	✔
CONSANGLECPK_HwDeg_M_f32	-724.341797	-724.341797 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1267377920	1267377920	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1267377920	1267377920	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1267377920	1267377920	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1267377920	1267377920	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1267377920	1267377920	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1267377920	1267377920	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1267377920	1267377920	✔
ESPNTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1267377920	1267377920	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	8	8	✔
EffacDefaultDiagTimer_mS_M_u32[1]	9	9	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	102	102	✔
ElecIntTimer_mS_M_u32[1]	106	106	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1267377920	1267377920	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	14487	14487	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	49656	49656	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	3941	3941	✔
ISDATBSI412MsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	31956	31956	✔
ISDATBSI432MsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1267377920	1267377920	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	49425	49425	✔
ISDYN2CMMMsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	6087	6087	✔
ISDYNAASMsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	13854	13854	✔
ISDYNABRMsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	49656	49656	✔
ISDYNCMM208MsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	24005	24005	✔
ISDYNCMM388MsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	27222	27222	✔
ISDYNVOLMsgTimer_mS_M_u32	1267377920	1267377920	✔
IgnOnTimer_mS_M_u32	860108800	860108800	✔
IgnTimeOff_Sec_M_u32	1706369505	1706369505	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	238	238	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3664656384	3664656384	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	64	64	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2313443328	2313443328	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	95	95	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2863298560	2863298560	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	148	148	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2227214336	2227214336	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1200060416	1200060416	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	92	92	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2229065728	2229065728	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	129	129	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	987953152	987953152	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	247	247	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2379323392	2379323392	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2791389184	2791389184	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	156	156	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	626481152	626481152	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	234	234	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3583866880	3583866880	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1408108544	1408108544	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	466.170685	466.170685	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	205.258698	205.258698	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	73.655899	73.655899	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	13854	13854	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1706369505	1706369505	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-724.341797	-724.341797 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.366 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	40143616
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	57101
AASNodeAbsentTimer_mS_M_u32	2413312768
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	56643
ANGLEVOLANTSigValidCount_Cnt_M_u16	16878
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	64046
AngleVolantMsgTimer_mS_M_u32	40143616
AngleVolantValidCount_Cnt_M_u16	12361
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	876280576
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1378581248
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1742187264
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4248136448
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	57814
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2694458112
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	48396
CAVNodeAbsentTimer_mS_M_u32	351230720
CDD_SrlComVehSpd_Kph_G_f32	645.842896
CMM388NTCEnableTimer_mS_M_u32	4253588224
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	654138112
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	25978
CMMNodeAbsentTimer_mS_M_u32	329739008
CONSANGLECPKSigInvalidCount_Cnt_M_u16	32482
CONSANGLECPKSigValidCount_Cnt_M_u16	33053
CONSANGLECPK_Cnt_M_u16	55204
CONSANGLECPK_HwDeg_M_f32	-480.533508
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	55204
CPKVehicleSpeedMsgTimer_mS_M_u32	2257554176
CPKVehicleSpeedValidCount_Cnt_M_u16	30527
CityParkInputConsistentCount_Cnt_M_u16	61437
CityParkInputInvalidCount_Cnt_M_u16	38699
CityParkInputMsgTimer_mS_M_u32	3664656384
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1015823104
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	60609

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	4110015232
ComputerRazGCTSigValidCount_Cnt_M_u16	55862
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	58231
DMDFCTCPKSigValidCount_Cnt_M_u16	51371
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	57373
DMDRELAXECPKSigValidCount_Cnt_M_u16	37960
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	18179
DateInvalidTimer_mS_M_u32	1378581248
DiagMuxOnAbsentTimer_mS_M_u32	506022656
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4248136448
ESPNTCEnableTimer_mS_M_u32	1852652288
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	49233
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	4
EffacDefaultDiagTimer_mS_M_u32[1]	5
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	89
ElecIntTimer_mS_M_u32[1]	789
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3981716224
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	49996
EtatMTSigValidCount_Cnt_M_u16	58196
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	36796
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	24951
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	40121
ISDAT4V2BSI552MsgTimer_mS_M_u32	2673568512
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	17269
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	35428
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	58196
ISDATBSI3F2MsgTimer_mS_M_u32	89082624
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	18400
ISDATBSI412MsgLenValidCount_Cnt_M_u16	17600
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	49996
ISDATBSI412MsgTimer_mS_M_u32	3884616448
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	4142
ISDATBSI432MsgLenValidCount_Cnt_M_u16	51717
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	10561
ISDATDIRASentFltAcc_Cnt_M_u16	69
ISDATDIRASentTimer_mS_M_u32	2257554176
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	61258
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	12361
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	16266
ISDYN2CMMMsgTimer_mS_M_u32	190790400
ISDYNAASChkSumInvalidCount_Cnt_M_u16	56807
ISDYNAASChkSumValidCount_Cnt_M_u16	56882
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	35420
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	40147
ISDYNAASMsgLenValidCount_Cnt_M_u16	3062
ISDYNAASMsgTimeValidCount_Cnt_M_u16	56807
ISDYNAASMsgTimer_mS_M_u32	852794112
ISDYNABRChkSumInvalidCount_Cnt_M_u16	45204
ISDYNABRChkSumValidCount_Cnt_M_u16	51751
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	56442
ISDYNABRMsgCountValidCount_Cnt_M_u16	46341
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	64629
ISDYNABRMsgLenValidCount_Cnt_M_u16	5872
ISDYNABRMsgTimeValidCount_Cnt_M_u16	55204
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	48104
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	55995
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	58196
ISDYNCMM208MsgTimer_mS_M_u32	1471412992
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	48104
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	55995
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	59503

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3724417792
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	32264
ISDYNVOLChkSumValidCount_Cnt_M_u16	45251
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	41373
ISDYNVOLMsgCountValidCount_Cnt_M_u16	63313
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	15550
ISDYNVOLMsgLenValidCount_Cnt_M_u16	33625
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	25978
ISDYNVOLMsgTimer_mS_M_u32	1178983168
IgnOnTimer_mS_M_u32	2696026880
IgnTimeOff_Sec_M_u32	1695902566
ManVehSpd_Kph_M_f32	655.340027
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	131
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	202
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3502066432
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	133
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1254796032
PrevISDATBSI412MsgDLCError_Cnt_M_u08	173
PrevISDATBSI412MsgRxTime_MSec_M_u32	2934201088
PrevISDATBSI432MsgDLCError_Cnt_M_u08	50
PrevISDATBSI432MsgRxTime_MSec_M_u32	4149295872
PrevISDATDIRAMsgTxTime_MSec_M_u32	2162711296
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	107
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3472419584
PrevISDYNAASMsgDLCError_Cnt_M_u08	87
PrevISDYNAASMsgRxTime_MSec_M_u32	1173084928
PrevISDYNABRMsgDLCError_Cnt_M_u08	83
PrevISDYNABRMsgRxTime_MSec_M_u32	2588547840
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	2
PrevISDYNCMM208MsgRxTime_MSec_M_u32	82107136
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	27
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1322793728
PrevISDYNVOLMsgDLCError_Cnt_M_u08	105
PrevISDYNVOLMsgRxTime_MSec_M_u32	412441344
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1538296576
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	261.554108
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	22777
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	47260
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	63718
VitesseVehicleBVRampValidCount_Cnt_M_u16	24649
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	56496
VitesseVehicleBVSigValidCount_Cnt_M_u16	59675
VitesseVehicleBV_Kph_M_f32	139.259003
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	59503
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	27634
VitesseVehiculeRoues_Kph_M_f32	137.955795
k_AASNTCEnableTimeout_mS_u16	65295
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	6568
k_AASNodeTimeout_mS_u16	63388
k_ABSNodeTimeout_mS_u16	1456
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	17357
k_ANGLEVOLANTSigValidThresh_Cnt_u16	50916
k_AngleVolantInvalidThresh_Cnt_u16	59103
k_AngleVolantValidThresh_Cnt_u16	38699
k_BSI552MsgTimeout_mS_u16	58285
k_BSINTCEnableTimeout_mS_u16	14790
k_BSINodeAbsentDiag_Cnt_str.Threshold	4298
k_BSINodeAbsentDiag_Cnt_str.PStep	13987
k_BSINodeAbsentDiag_Cnt_str.NStep	63952
k_BSINodeAbsentTimeout_mS_u16	32198
k_BSINodeTimeout_mS_u16	10561
k_BattOvHi_Volt_f32	29.5928001
k_BattOvLo_Volt_f32	21.1912994
k_BattUvHi_Volt_f32	26.5289001
k_BattUvLo_Volt_f32	7.8743
k_CAVNTCEnableTimeout_mS_u16	19689
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	36914
k_CAVNodeTimeout_mS_u16	3118
k_CMM388MsgTimeout_mS_u16	24077
k_CMM388NTCEnableTimeout_mS_u16	36953
k_CMMNTCEnableTimeout_mS_u16	63757
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	11326
k_CONSANGLECPKMax_HwDeg_f32	100.771599
k_CONSANGLECPKMin_HwDeg_f32	-71.9896011
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	59247
k_CONSANGLECPKSigValidThresh_Cnt_u16	43762
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	58026
k_CPKVehicleSpeedValidThresh_Cnt_u16	12391
k_CityParkInputInvalidThresh_Cnt_u16	45602
k_CityParkInputValidThresh_Cnt_u16	61437
k_ComputerRazGCTSigValidThresh_Cnt_u16	19299
k_CptTemporelSigValidThresh_Cnt_u16	18642
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	31605
k_DMDFCTCPKSigValidThresh_Cnt_u16	54768
k_DMDFCTCPKValidCount_Cnt_u16	11582
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	16266
k_DMDRELAXECPKSigValidThresh_Cnt_u16	7422
k_DMDRelaxeConsistentThresh_Cnt_u16	39436
k_DateValidThresh_Cnt_u16	40121
k_DefaultVehSpd_Kph_f32	105.180298
k_DiagMuxOnAbsentTimeout_mS_u16	44258
k_EMNodeTimeout_mS_u16	38883
k_ESPNTCEnableTimeout_mS_u16	29784
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	10918
k_EtatMTSigInvalidThresh_Cnt_u16	44015
k_EtatMTSigValidThresh_Cnt_u16	9154
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	63121
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	6392
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	43498
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	1078
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	2533
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	12436
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	10351
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	16646
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	64226
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	4408
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	34999
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	10560
k_ISDATDIRASentDiag_Cnt_str.Threshold	44440

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	55056
k_ISDATDIRASentDiag_Cnt_str.NStep	15158
k_ISDATDIRASentTimeout_mS_u16	21472
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	29113
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	64046
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	3188
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	44948
k_ISDYNAASChkSumValidThresh_Cnt_u16	2343
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	23418
k_ISDYNAASMsgCountValidThresh_Cnt_u16	29701
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	19528
k_ISDYNAASMsgLenValidThresh_Cnt_u16	28496
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	31564
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	33435
k_ISDYNABRChkSumValidThresh_Cnt_u16	3478
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	24790
k_ISDYNABRMsgCountValidThresh_Cnt_u16	24001
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	42106
k_ISDYNABRMsgLenValidThresh_Cnt_u16	16209
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	26876
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	61613
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	15373
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	41559
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	23619
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	238
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	28355
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	32255
k_ISDYNVOLChkSumValidThresh_Cnt_u16	9247
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	22130
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	34011
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	25496
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	25760
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	29943
k_IgnOnTimeout_mS_u16	9547
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	178.313599
k_PowerCutVehSpdLowThresh_Kph_f32	243.165207
k_PowerCutVehSpdLowTimeout_mS_u16	2827
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	15.1615
k_VBattMaxCAV_Volt_f32	25.2157993
k_VBattMaxCMM388_Volt_f32	29.1511002
k_VBattMaxCMM_Volt_f32	25.0063
k_VBattMaxESP_Volt_f32	30.5806999
k_VBattMinAAS_Volt_f32	2.90939999
k_VBattMinBSI_Volt_f32	30.5806999
k_VBattMinCAV_Volt_f32	5.5854001
k_VBattMinCMM388_Volt_f32	25.6459999
k_VBattMinCMM_Volt_f32	31.0583992
k_VBattMinESP_Volt_f32	25.0063
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	11691
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	31162
k_VitesseVehicleBVRampValidThresh_Cnt_u16	41117
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	28611
k_VitesseVehicleBVSigValidThresh_Cnt_u16	18818
k_VitesseVehicleBVSpeedPassThresh_kph_f32	216.715302
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	48140
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	21487
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1378581248
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	38458
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3227176448
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	27
target_SrlComInput_Per1_Batt_Volt_f32.value	4.29099989
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2813274880
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	117
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.842380285
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3543407360
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	249
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3310467840
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2743032576
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	127
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2512190208
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3289029376
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1449671424
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	217
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1960172288
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	56
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	57
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	80
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	107
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	235
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4270455552
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	80
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	81
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	106
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	191
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	85
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4217051904
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	114
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2130230016
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2930137856
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	4
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	16
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	93
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	117
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3925125888
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	371
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.569807708
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	517115
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	93.5560989
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	60523

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3227176448	3227176448	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3227176448	3227176448	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	4298	4298	✔
BSINodeAbsentTimer_mS_M_u32	3227176448	3227176448	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3227176448	3227176448	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3227176448	3227176448	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	55204	55204	✔
CONSANGLECPK_HwDeg_M_f32	-480.533508	-480.533508 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3227176448	3227176448	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3227176448	3227176448	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3227176448	3227176448	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3227176448	3227176448	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3227176448	3227176448	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3227176448	3227176448	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3227176448	3227176448	✔
ESPNTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3227176448	3227176448	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4	4	✔
EffacDefaultDiagTimer_mS_M_u32[1]	5	5	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3227176448	3227176448	✔
ElecIntTimer_mS_M_u32[1]	789	789	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3227176448	3227176448	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3227176448	3227176448	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3227176448	3227176448	✔
IgnOnTimer_mS_M_u32	3227176448	3227176448	✔
IgnTimeOff_Sec_M_u32	1695902566	1695902566	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	142	142	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3543407360	3543407360	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	249	249	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3310467840	3310467840	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	60	60	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2743032576	2743032576	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	127	127	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2512190208	2512190208	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2162711296	2162711296	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	166	166	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1449671424	1449671424	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	217	217	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1960172288	1960172288	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	216	216	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4270455552	4270455552	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	85	85	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4217051904	4217051904	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	114	114	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2130230016	2130230016	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	38	38	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2930137856	2930137856	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3925125888	3925125888	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	261.554108	261.554108	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	139.259003	139.259003	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	137.955795	137.955795	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	55204	55204	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1695902566	1695902566	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-480.533508	-480.533508 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.367 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3800448000
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	58080
AASNodeAbsentTimer_mS_M_u32	985574400
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	52417
ANGLEVOLANTSigValidCount_Cnt_M_u16	9215
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	34469
AngleVolantMsgTimer_mS_M_u32	3800448000
AngleVolantValidCount_Cnt_M_u16	45987
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	4144262144
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	650570752
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3408518144
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3283524608
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	7680
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3410385920
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	55232
CAVNodeAbsentTimer_mS_M_u32	2518043648
CDD_SrlComVehSpd_Kph_G_f32	379.454498
CMM388NTCEnableTimer_mS_M_u32	1513917440
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1109150720
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	20534
CMMNodeAbsentTimer_mS_M_u32	4063271936
CONSANGLECPKSigInvalidCount_Cnt_M_u16	17074
CONSANGLECPKSigValidCount_Cnt_M_u16	57280
CONSANGLECPK_Cnt_M_u16	26947
CONSANGLECPK_HwDeg_M_f32	-495.683807
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	26947
CPKVehicleSpeedMsgTimer_mS_M_u32	3837606912
CPKVehicleSpeedValidCount_Cnt_M_u16	23076
CityParkInputConsistentCount_Cnt_M_u16	51367

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	12375
CityParkInputMsgTimer_mS_M_u32	3829677312
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2428677120
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	15844
ComputerRazGCTSigInvalidTimer_mS_M_u32	2207960064
ComputerRazGCTSigValidCount_Cnt_M_u16	39652
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	55123
DMDFCTCPKSigValidCount_Cnt_M_u16	33337
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	58947
DMDRELAXECPKSigValidCount_Cnt_M_u16	47873
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	59255
DateInvalidTimer_mS_M_u32	650570752
DiagMuxOnAbsentTimer_mS_M_u32	1341520896
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3283524608
ESPNTCEnableTimer_mS_M_u32	2118626304
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	56272
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	89
EffacDefaultDiagTimer_mS_M_u32[1]	789
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	3
ElecIntTimer_mS_M_u32[1]	7
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2452118528
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	64921
EtatMTSigValidCount_Cnt_M_u16	35107
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	25140
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	64706
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	14399
ISDAT4V2BSI552MsgTimer_mS_M_u32	2201263104
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	25730
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	20372
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	35107
ISDATBSI3F2MsgTimer_mS_M_u32	141818880
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	7682
ISDATBSI412MsgLenValidCount_Cnt_M_u16	54468
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	64921
ISDATBSI412MsgTimer_mS_M_u32	1359232000
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	23610
ISDATBSI432MsgLenValidCount_Cnt_M_u16	41684
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	37737
ISDATDIRASentFltAcc_Cnt_M_u16	34557
ISDATDIRASentTimer_mS_M_u32	3837606912
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	9281
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	45987
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52754
ISDYN2CMMMsgTimer_mS_M_u32	490843136
ISDYNAASChkSumInvalidCount_Cnt_M_u16	26722
ISDYNAASChkSumValidCount_Cnt_M_u16	15808
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	24674
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	14211
ISDYNAASMsgLenValidCount_Cnt_M_u16	21017
ISDYNAASMsgTimeValidCount_Cnt_M_u16	26722
ISDYNAASMsgTimer_mS_M_u32	2922941440
ISDYNABRChkSumInvalidCount_Cnt_M_u16	63601
ISDYNABRChkSumValidCount_Cnt_M_u16	13623
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	56225
ISDYNABRMsgCountValidCount_Cnt_M_u16	62015
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	4337
ISDYNABRMsgLenValidCount_Cnt_M_u16	12095
ISDYNABRMsgTimeValidCount_Cnt_M_u16	26947
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	13516

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	53398
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	35107
ISDYNCMM208MsgTimer_mS_M_u32	260140032
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	13516
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	53398
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	41249
ISDYNCMM388MsgTimer_mS_M_u32	1060637696
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	29488
ISDYNVOLChkSumValidCount_Cnt_M_u16	4798
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	41681
ISDYNVOLMsgCountValidCount_Cnt_M_u16	36919
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	12177
ISDYNVOLMsgLenValidCount_Cnt_M_u16	44671
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	20534
ISDYNVOLMsgTimer_mS_M_u32	3818310656
IgnOnTimer_mS_M_u32	3275492352
IgnTimeOff_Sec_M_u32	2093859463
ManVehSpd_Kph_M_f32	204.5177
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	154
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	106
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2136603648
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	224
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1078516736
PrevISDATBSI412MsgDLCError_Cnt_M_u08	138
PrevISDATBSI412MsgRxTime_MSec_M_u32	4001319936
PrevISDATBSI432MsgDLCError_Cnt_M_u08	21
PrevISDATBSI432MsgRxTime_MSec_M_u32	658222080
PrevISDATDIRAMsgTxTime_MSec_M_u32	689130496
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	206
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2566396928
PrevISDYNAASMsgDLCError_Cnt_M_u08	148
PrevISDYNAASMsgRxTime_MSec_M_u32	647285760
PrevISDYNABRMsgDLCError_Cnt_M_u08	144
PrevISDYNABRMsgRxTime_MSec_M_u32	372509696
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	165
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3096562688
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	236
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3586042880
PrevISDYNVOLMsgDLCError_Cnt_M_u08	94
PrevISDYNVOLMsgRxTime_MSec_M_u32	1830046720
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1786919936
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	261.823914
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	47361
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	38423
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	11842
VitesseVehicleBVRampValidCount_Cnt_M_u16	10776
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	3970
VitesseVehicleBVSigValidCount_Cnt_M_u16	42368

Name	Input Value
VitesseVehicleBV_Kph_M_f32	438.965912
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	41249
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	44439
VitesseVehiculeRoues_Kph_M_f32	372.800903
k_AASNTCEnableTimeout_mS_u16	954
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	46686
k_AASNodeTimeout_mS_u16	45335
k_ABSNodeTimeout_mS_u16	49552
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	6709
k_ANGLEVOLANTSigValidThresh_Cnt_u16	30479
k_AngleVolantInvalidThresh_Cnt_u16	32342
k_AngleVolantValidThresh_Cnt_u16	12375
k_BSI552MsgTimeout_mS_u16	25502
k_BSINTCEnableTimeout_mS_u16	40754
k_BSINodeAbsentDiag_Cnt_str.Threshold	43356
k_BSINodeAbsentDiag_Cnt_str.PStep	55038
k_BSINodeAbsentDiag_Cnt_str.NStep	15668
k_BSINodeAbsentTimeout_mS_u16	52125
k_BSINodeTimeout_mS_u16	37737
k_BattOvHi_Volt_f32	20.0832005
k_BattOvLo_Volt_f32	1.79110003
k_BattUvHi_Volt_f32	29.9895
k_BattUvLo_Volt_f32	11.4157
k_CAVNTCEnableTimeout_mS_u16	1229
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	44094
k_CAVNodeTimeout_mS_u16	20142
k_CMM388MsgTimeout_mS_u16	15840
k_CMM388NTCEnableTimeout_mS_u16	8924
k_CMMNTCEnableTimeout_mS_u16	58234
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	6291
k_CONSANGLECPKMax_HwDeg_f32	647.239075
k_CONSANGLECPKMin_HwDeg_f32	-477.142395
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	31777
k_CONSANGLECPKSigValidThresh_Cnt_u16	51351
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	47645
k_CPKVehicleSpeedValidThresh_Cnt_u16	49541
k_CityParkInputInvalidThresh_Cnt_u16	16887
k_CityParkInputValidThresh_Cnt_u16	51367
k_ComputerRazGCTSigValidThresh_Cnt_u16	39400
k_CptTemporelSigValidThresh_Cnt_u16	58746
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	27633
k_DMDFCTCPKSigValidThresh_Cnt_u16	51775
k_DMDFCTCPKValidCount_Cnt_u16	50184
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	52754
k_DMDRELAXECPKSigValidThresh_Cnt_u16	23096
k_DMDRelaxeConsistentThresh_Cnt_u16	32062
k_DateValidThresh_Cnt_u16	14399
k_DefaultVehSpd_Kph_f32	40.6655006
k_DiagMuxOnAbsentTimeout_mS_u16	52025
k_EMNodeTimeout_mS_u16	38871
k_ESPNTCEnableTimeout_mS_u16	62908
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	40347
k_EtatMTSigInvalidThresh_Cnt_u16	46232
k_EtatMTSigValidThresh_Cnt_u16	37022
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	41600
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	34282
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	65512
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	63591
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	30009
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	8198
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	38303

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	36345
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	43070
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	7079
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	35721
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	9926
k_ISDATDIRASentDiag_Cnt_str.Threshold	44024
k_ISDATDIRASentDiag_Cnt_str.PStep	4643
k_ISDATDIRASentDiag_Cnt_str.NStep	50395
k_ISDATDIRASentTimeout_mS_u16	12909
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	0
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	34469
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	4552
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	54129
k_ISDYNAASChkSumValidThresh_Cnt_u16	20535
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	13985
k_ISDYNAASMsgCountValidThresh_Cnt_u16	36159
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	55669
k_ISDYNAASMsgLenValidThresh_Cnt_u16	24091
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	18967
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	50287
k_ISDYNABRChkSumValidThresh_Cnt_u16	9533
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	30976
k_ISDYNABRMsgCountValidThresh_Cnt_u16	53630
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	27446
k_ISDYNABRMsgLenValidThresh_Cnt_u16	14032
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	55557
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	1541
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	49283
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	50718
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	10177
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	48895
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	39247
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	14461
k_ISDYNVOLChkSumValidThresh_Cnt_u16	25983
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	18069
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	37179
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	51349
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	55583
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	2357
k_IgnOnTimeout_mS_u16	1657
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	193.597595
k_PowerCutVehSpdLowThresh_Kph_f32	209.105392
k_PowerCutVehSpdLowTimeout_mS_u16	57126
k_VBattMaxAAS_Volt_f32	13.9041996
k_VBattMaxBSI_Volt_f32	22.6616001
k_VBattMaxCAV_Volt_f32	23.6154995
k_VBattMaxCMM388_Volt_f32	24.7150993
k_VBattMaxCMM_Volt_f32	19.6643009
k_VBattMaxESP_Volt_f32	15.6069002
k_VBattMinAAS_Volt_f32	20.4410992
k_VBattMinBSI_Volt_f32	15.6069002
k_VBattMinCAV_Volt_f32	4.01870012
k_VBattMinCMM388_Volt_f32	16.0067997
k_VBattMinCMM_Volt_f32	30.4470997
k_VBattMinESP_Volt_f32	19.6643009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	45629
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	23279
k_VitesseVehicleBVRampValidThresh_Cnt_u16	32209
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	44478
k_VitesseVehicleBVSigValidThresh_Cnt_u16	20704
k_VitesseVehicleBVSpeedPassThresh_kph_f32	93.6533966
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	45760
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	45334
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	650570752
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	34046
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2155592960
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	236
target_SrlComInput_Per1_Batt_Volt_f32.value	1.64020002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3914292224
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	128
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.92710942
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2147879936
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1229859840
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2967882752
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2127457280
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2064026624
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	161
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1838066688
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	510053376
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	9
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	47
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	151
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	183
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	234
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	236
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4235160576
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	32
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	46
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	166
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	202
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1437142016
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	644951040
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	157
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1435061248
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	44
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	84
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	188
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	203
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1901779968
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3088
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.236133501
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	915085
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	93.0675964

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	63611		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2155592960	2155592960	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2155592960	2155592960	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	43356	43356	✔
BSINodeAbsentTimer_mS_M_u32	2155592960	2155592960	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2155592960	2155592960	✔
CDD_SrlComVehSpd_Kph_G_f32	204.5177	204.5177	✔
CMM388NTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2155592960	2155592960	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	26947	26947	✔
CONSANGLECPK_HwDeg_M_f32	-495.683807	-495.683807 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2155592960	2155592960	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2155592960	2155592960	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2155592960	2155592960	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2155592960	2155592960	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2155592960	2155592960	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2155592960	2155592960	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2155592960	2155592960	✔
ESPNTCEnableTimer_mS_M_u32	2155592960	2155592960	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2155592960	2155592960	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	89	89	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	789	789	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3	3	✔
ElecIntTimer_mS_M_u32[1]	7	7	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2155592960	2155592960	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	14399	14399	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	35107	35107	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	64921	64921	✔
ISDATBSI412MsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	37737	37737	✔
ISDATBSI432MsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2155592960	2155592960	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52754	52754	✔
ISDYN2CMMMsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	26722	26722	✔
ISDYNAASMsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	26947	26947	✔
ISDYNABRMsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	35107	35107	✔
ISDYNCMM208MsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	41249	41249	✔
ISDYNCMM388MsgTimer_mS_M_u32	2155592960	2155592960	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	20534	20534	✔
ISDYNVOLMsgTimer_mS_M_u32	2155592960	2155592960	✔
IgnOnTimer_mS_M_u32	3275492352	3275492352	✔
IgnTimeOff_Sec_M_u32	2093859463	2093859463	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	240	240	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2147879936	2147879936	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	117	117	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1229859840	1229859840	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	180	180	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2967882752	2967882752	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	118	118	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2127457280	2127457280	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	689130496	689130496	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	161	161	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1838066688	1838066688	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	153	153	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	510053376	510053376	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	154	154	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4235160576	4235160576	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	202	202	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1437142016	1437142016	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	246	246	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	644951040	644951040	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	157	157	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1435061248	1435061248	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1901779968	1901779968	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	261.823914	261.823914	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	438.965912	438.965912	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	372.800903	372.800903	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	26947	26947	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2093859463	2093859463	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-495.683807	-495.683807 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	204.5177	204.5177	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.368 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	268177152
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	39148
AASNodeAbsentTimer_mS_M_u32	3037904640
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	64843
ANGLEVOLANTSigValidCount_Cnt_M_u16	39761
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	413
AngleVolantMsgTimer_mS_M_u32	268177152
AngleVolantValidCount_Cnt_M_u16	39715
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3342958336
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1643773696
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3968937728
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	636153600
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	50574
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4265324288
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	16589
CAVNodeAbsentTimer_mS_M_u32	160161536
CDD_SrlComVehSpd_Kph_G_f32	558.397522
CMM388NTCEnableTimer_mS_M_u32	639180544
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2642009856
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	44075
CMMNodeAbsentTimer_mS_M_u32	41742080
CONSANGLECPKSigInvalidCount_Cnt_M_u16	37493
CONSANGLECPKSigValidCount_Cnt_M_u16	40715
CONSANGLECPK_Cnt_M_u16	52866
CONSANGLECPK_HwDeg_M_f32	-432.883301
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	52866
CPKVehicleSpeedMsgTimer_mS_M_u32	2773946112
CPKVehicleSpeedValidCount_Cnt_M_u16	649
CityParkInputConsistentCount_Cnt_M_u16	27671
CityParkInputInvalidCount_Cnt_M_u16	521
CityParkInputMsgTimer_mS_M_u32	2147879936
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3271999232
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	38880

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	4076756736
ComputerRazGCTSigValidCount_Cnt_M_u16	10592
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	64789
DMDFCTCPKSigValidCount_Cnt_M_u16	16419
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	14533
DMDRELAXECPKSigValidCount_Cnt_M_u16	24139
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	63526
DateInvalidTimer_mS_M_u32	1643773696
DiagMuxOnAbsentTimer_mS_M_u32	917294848
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	636153600
ESPNTCEnableTimer_mS_M_u32	1316470528
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	7453
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	56
EffacDefaultDiagTimer_mS_M_u32[1]	456
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	9
ElecIntTimer_mS_M_u32[1]	82
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2979376896
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	16641
EtatMTSigValidCount_Cnt_M_u16	29219
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	48111
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	53253
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	46609
ISDAT4V2BSI552MsgTimer_mS_M_u32	1601236736
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	42440
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	55378
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	29219
ISDATBSI3F2MsgTimer_mS_M_u32	2234699520
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	51783
ISDATBSI412MsgLenValidCount_Cnt_M_u16	22977
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	16641
ISDATBSI412MsgTimer_mS_M_u32	1015156480
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	38943
ISDATBSI432MsgLenValidCount_Cnt_M_u16	55313
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	61906
ISDATDIRASentFltAcc_Cnt_M_u16	26390
ISDATDIRASentTimer_mS_M_u32	2773946112
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	5512
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	39715
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	54488
ISDYN2CMMMsgTimer_mS_M_u32	3649683200
ISDYNAASChkSumInvalidCount_Cnt_M_u16	36966
ISDYNAASChkSumValidCount_Cnt_M_u16	13324
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	20710
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	60804
ISDYNAASMsgLenValidCount_Cnt_M_u16	41346
ISDYNAASMsgTimeValidCount_Cnt_M_u16	36966
ISDYNAASMsgTimer_mS_M_u32	438640384
ISDYNABRChkSumInvalidCount_Cnt_M_u16	13241
ISDYNABRChkSumValidCount_Cnt_M_u16	16680
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	62121
ISDYNABRMsgCountValidCount_Cnt_M_u16	53903
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	58296
ISDYNABRMsgLenValidCount_Cnt_M_u16	27790
ISDYNABRMsgTimeValidCount_Cnt_M_u16	52866
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	10088
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	10186
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	29219
ISDYNCMM208MsgTimer_mS_M_u32	2982838016
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	10088
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	10186
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	19113

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3307642624
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	30971
ISDYNVOLChkSumValidCount_Cnt_M_u16	32273
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	4763
ISDYNVOLMsgCountValidCount_Cnt_M_u16	36393
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	26074
ISDYNVOLMsgLenValidCount_Cnt_M_u16	19664
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	44075
ISDYNVOLMsgTimer_mS_M_u32	3272236800
IgnOnTimer_mS_M_u32	1226481408
IgnTimeOff_Sec_M_u32	1482908048
ManVehSpd_Kph_M_f32	339.056793
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	155
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	209
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	947965696
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	60
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3375640320
PrevISDATBSI412MsgDLCError_Cnt_M_u08	87
PrevISDATBSI412MsgRxTime_MSec_M_u32	3830505216
PrevISDATBSI432MsgDLCError_Cnt_M_u08	15
PrevISDATBSI432MsgRxTime_MSec_M_u32	597409536
PrevISDATDIRAMsgTxTime_MSec_M_u32	2224348928
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	0
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2351329024
PrevISDYNAASMsgDLCError_Cnt_M_u08	80
PrevISDYNAASMsgRxTime_MSec_M_u32	1913675520
PrevISDYNABRMsgDLCError_Cnt_M_u08	74
PrevISDYNABRMsgRxTime_MSec_M_u32	808623872
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	169
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4028194560
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	25
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3826433792
PrevISDYNVOLMsgDLCError_Cnt_M_u08	192
PrevISDYNVOLMsgRxTime_MSec_M_u32	4237418240
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1745358592
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	649.77887
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57610
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	19848
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	50503
VitesseVehicleBVRampValidCount_Cnt_M_u16	54661
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	30984
VitesseVehicleBVSigValidCount_Cnt_M_u16	23246
VitesseVehicleBV_Kph_M_f32	156.810303
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	19113
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	43271
VitesseVehiculeRoues_Kph_M_f32	348.895905
k_AASNTCEnableTimeout_mS_u16	39709
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	16114
k_AASNodeTimeout_mS_u16	64648
k_ABSNodeTimeout_mS_u16	29278
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	2606
k_ANGLEVOLANTSigValidThresh_Cnt_u16	1888
k_AngleVolantInvalidThresh_Cnt_u16	52619
k_AngleVolantValidThresh_Cnt_u16	521
k_BSI552MsgTimeout_mS_u16	25330
k_BSINTCEnableTimeout_mS_u16	44855
k_BSINodeAbsentDiag_Cnt_str.Threshold	24888
k_BSINodeAbsentDiag_Cnt_str.PStep	46226
k_BSINodeAbsentDiag_Cnt_str.NStep	44592
k_BSINodeAbsentTimeout_mS_u16	4789
k_BSINodeTimeout_mS_u16	61906
k_BattOvHi_Volt_f32	13.9937
k_BattOvLo_Volt_f32	24.7854004
k_BattUvHi_Volt_f32	9.72859955
k_BattUvLo_Volt_f32	15.1450996
k_CAVNTCEnableTimeout_mS_u16	56487
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	15187
k_CAVNodeTimeout_mS_u16	24193
k_CMM388MsgTimeout_mS_u16	34796
k_CMM388NTCEnableTimeout_mS_u16	51448
k_CMMNTCEnableTimeout_mS_u16	2272
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	22547
k_CONSANGLECPKMax_HwDeg_f32	491.456512
k_CONSANGLECPKMin_HwDeg_f32	-708.333496
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	47529
k_CONSANGLECPKSigValidThresh_Cnt_u16	22535
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	31094
k_CPKVehicleSpeedValidThresh_Cnt_u16	43966
k_CityParkInputInvalidThresh_Cnt_u16	61223
k_CityParkInputValidThresh_Cnt_u16	27671
k_ComputerRazGCTSigValidThresh_Cnt_u16	7574
k_CptTemporelSigValidThresh_Cnt_u16	11936
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	53944
k_DMDFCTCPKSigValidThresh_Cnt_u16	39822
k_DMDFCTCPKValidCount_Cnt_u16	62326
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	54488
k_DMDRELAXECPKSigValidThresh_Cnt_u16	29734
k_DMDRelaxeConsistentThresh_Cnt_u16	41748
k_DateValidThresh_Cnt_u16	46609
k_DefaultVehSpd_Kph_f32	118.061302
k_DiagMuxOnAbsentTimeout_mS_u16	160
k_EMNodeTimeout_mS_u16	26374
k_ESPNTCEnableTimeout_mS_u16	55001
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	59643
k_EtatMTSigInvalidThresh_Cnt_u16	23364
k_EtatMTSigValidThresh_Cnt_u16	35571
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	3149
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	46544
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	2644
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	48665
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	15203
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	54331
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	49136
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	60066
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	50195
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	18262
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	11121
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	4346
k_ISDATDIRASentDiag_Cnt_str.Threshold	25921

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	8439
k_ISDATDIRASentDiag_Cnt_str.NStep	40264
k_ISDATDIRASentTimeout_mS_u16	30149
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	65535
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	413
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	45749
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	41657
k_ISDYNAASChkSumValidThresh_Cnt_u16	61480
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	57769
k_ISDYNAASMsgCountValidThresh_Cnt_u16	399
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	41133
k_ISDYNAASMsgLenValidThresh_Cnt_u16	1404
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	44616
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	16702
k_ISDYNABRChkSumValidThresh_Cnt_u16	660
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	46222
k_ISDYNABRMsgCountValidThresh_Cnt_u16	20180
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	23339
k_ISDYNABRMsgLenValidThresh_Cnt_u16	3101
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	5183
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	2558
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	9924
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	39283
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	60491
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	51793
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	42785
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	9942
k_ISDYNVOLChkSumValidThresh_Cnt_u16	21392
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	12494
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	15644
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	53261
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	29231
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	39727
k_IgnOnTimeout_mS_u16	44258
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	45.7649002
k_PowerCutVehSpdLowThresh_Kph_f32	135.241394
k_PowerCutVehSpdLowTimeout_mS_u16	47321
k_VBattMaxAAS_Volt_f32	19.3964996
k_VBattMaxBSI_Volt_f32	18.7122002
k_VBattMaxCAV_Volt_f32	1.18719995
k_VBattMaxCMM388_Volt_f32	2.8513999
k_VBattMaxCMM_Volt_f32	28.5419006
k_VBattMaxESP_Volt_f32	10.3889999
k_VBattMinAAS_Volt_f32	16.7691002
k_VBattMinBSI_Volt_f32	10.3889999
k_VBattMinCAV_Volt_f32	13.0235004
k_VBattMinCMM388_Volt_f32	10.8971004
k_VBattMinCMM_Volt_f32	4.92689991
k_VBattMinESP_Volt_f32	28.5419006
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	2709
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	33855
k_VitesseVehicleBVRampValidThresh_Cnt_u16	33179
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	44305
k_VitesseVehicleBVSigValidThresh_Cnt_u16	63340
k_VitesseVehicleBVSpeedPassThresh_kph_f32	139.655396
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	45005
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	47243
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1643773696
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	1230
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3915353088
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	25
target_SrlComInput_Per1_Batt_Volt_f32.value	17.4615993
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	136359680
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	143
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.279311001
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3132923648
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	150
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	660881152
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	65
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4179353344
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3622010624
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1807425280
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	54
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1554169600
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1385848576
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	39
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	130
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	131
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	242
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	587235072
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	18
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	88
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	111
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	252
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	188
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2245238528
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3690675968
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1462951680
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	22
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	124
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	173
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4261293824
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2337
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.606143117
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	551321
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	96.6050034
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	35484

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3915353088	3915353088	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	415	415	✔
AngleVolantMsgTimer_mS_M_u32	3915353088	3915353088	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	24888	24888	✔
BSINodeAbsentTimer_mS_M_u32	3915353088	3915353088	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3915353088	3915353088	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3915353088	3915353088	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	52866	52866	✔
CONSANGLECPK_HwDeg_M_f32	-432.883301	-432.883301 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	52866	52866	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2773946112	2773946112	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	649	649	✔
CityParkInputConsistentCount_Cnt_M_u16	27671	27671	✔
CityParkInputInvalidCount_Cnt_M_u16	523	523	✔
CityParkInputMsgTimer_mS_M_u32	3915353088	3915353088	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3915353088	3915353088	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3915353088	3915353088	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3915353088	3915353088	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3915353088	3915353088	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3915353088	3915353088	✔
ESPNTCEnableTimer_mS_M_u32	3915353088	3915353088	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3915353088	3915353088	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	56	56	✔
EffacDefaultDiagTimer_mS_M_u32[1]	456	456	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3915353088	3915353088	✔
ElecIntTimer_mS_M_u32[1]	82	82	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3915353088	3915353088	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3915353088	3915353088	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3915353088	3915353088	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3915353088	3915353088	✔
IgnOnTimer_mS_M_u32	3915353088	3915353088	✔
IgnTimeOff_Sec_M_u32	1482908048	1482908048	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	253	253	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3132923648	3132923648	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	150	150	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	660881152	660881152	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	65	65	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4179353344	4179353344	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	164	164	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3622010624	3622010624	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2224348928	2224348928	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	54	54	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1554169600	1554169600	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	180	180	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1385848576	1385848576	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	251	251	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	587235072	587235072	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	188	188	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2245238528	2245238528	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3690675968	3690675968	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	210	210	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1462951680	1462951680	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4261293824	4261293824	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	649.77887	649.77887	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	156.810303	156.810303	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	348.895905	348.895905	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	52866	52866	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1482908048	1482908048	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-432.883301	-432.883301 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	118.061302	118.061302	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.369 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1520866816
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	8661
AASNodeAbsentTimer_mS_M_u32	1646429696
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	36537
ANGLEVOLANTSigValidCount_Cnt_M_u16	51559
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	60354
AngleVolantMsgTimer_mS_M_u32	1520866816
AngleVolantValidCount_Cnt_M_u16	48561
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1452688896
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	141346304
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	23541248
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3965318656
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	496
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2523379200
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	38577
CAVNodeAbsentTimer_mS_M_u32	825697792
CDD_SrlComVehSpd_Kph_G_f32	252.433395
CMM388NTCEnableTimer_mS_M_u32	2693752320
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2909611520
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	54873
CMMNodeAbsentTimer_mS_M_u32	514061824
CONSANGLECPKSigInvalidCount_Cnt_M_u16	59961
CONSANGLECPKSigValidCount_Cnt_M_u16	6454
CONSANGLECPK_Cnt_M_u16	9937
CONSANGLECPK_HwDeg_M_f32	342.430786
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	9937
CPKVehicleSpeedMsgTimer_mS_M_u32	3331692032
CPKVehicleSpeedValidCount_Cnt_M_u16	5830

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	6869
CityParkInputInvalidCount_Cnt_M_u16	61950
CityParkInputMsgTimer_mS_M_u32	3132923648
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	138839552
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	62713
ComputerRazGCTSigInvalidTimer_mS_M_u32	1591715328
ComputerRazGCTSigValidCount_Cnt_M_u16	18170
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	12506
DMDFCTCPKSigValidCount_Cnt_M_u16	40047
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	17483
DMDRELAXECPKSigValidCount_Cnt_M_u16	59513
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	48422
DateInvalidTimer_mS_M_u32	141346304
DiagMuxOnAbsentTimer_mS_M_u32	2576635392
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3965318656
ESPNTCEnableTimer_mS_M_u32	1777567232
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	18498
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1121
EffacDefaultDiagTimer_mS_M_u32[1]	2235
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	80
ElecIntTimer_mS_M_u32[1]	101
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1683600896
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	16598
EtatMTSigValidCount_Cnt_M_u16	12848
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	54731
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	61000
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	29349
ISDAT4V2BSI552MsgTimer_mS_M_u32	3620206080
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	17922
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	54051
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	12848
ISDATBSI3F2MsgTimer_mS_M_u32	1174558208
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	58756
ISDATBSI412MsgLenValidCount_Cnt_M_u16	7125
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	16598
ISDATBSI412MsgTimer_mS_M_u32	1830065664
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	57981
ISDATBSI432MsgLenValidCount_Cnt_M_u16	59238
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	55202
ISDATDIRASentFltAcc_Cnt_M_u16	34774
ISDATDIRASentTimer_mS_M_u32	3331692032
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	59839
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	48561
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	30097
ISDYN2CMMMsgTimer_mS_M_u32	2428339712
ISDYNAASChkSumInvalidCount_Cnt_M_u16	41831
ISDYNAASChkSumValidCount_Cnt_M_u16	19764
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	26728
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	11404
ISDYNAASMsgLenValidCount_Cnt_M_u16	1362
ISDYNAASMsgTimeValidCount_Cnt_M_u16	41831
ISDYNAASMsgTimer_mS_M_u32	4100679168
ISDYNABRChkSumInvalidCount_Cnt_M_u16	48876
ISDYNABRChkSumValidCount_Cnt_M_u16	19298
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	18590
ISDYNABRMsgCountValidCount_Cnt_M_u16	15787
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	49776
ISDYNABRMsgLenValidCount_Cnt_M_u16	31917
ISDYNABRMsgTimeValidCount_Cnt_M_u16	9937

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	1233
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	60357
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	12848
ISDYNCMM208MsgTimer_mS_M_u32	4210771456
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	1233
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	60357
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	18207
ISDYNCMM388MsgTimer_mS_M_u32	3647399424
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	52903
ISDYNVOLChkSumValidCount_Cnt_M_u16	5156
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	34888
ISDYNVOLMsgCountValidCount_Cnt_M_u16	19037
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	41483
ISDYNVOLMsgLenValidCount_Cnt_M_u16	49641
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	54873
ISDYNVOLMsgTimer_mS_M_u32	515614208
IgnOnTimer_mS_M_u32	495642112
IgnTimeOff_Sec_M_u32	3129716448
ManVehSpd_Kph_M_f32	517.548584
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	156
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3826800128
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	94
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3078501888
PrevISDATBSI412MsgDLCError_Cnt_M_u08	193
PrevISDATBSI412MsgRxTime_MSec_M_u32	4108854784
PrevISDATBSI432MsgDLCError_Cnt_M_u08	140
PrevISDATBSI432MsgRxTime_MSec_M_u32	2055702016
PrevISDATDIRAMsgTxTime_MSec_M_u32	605824512
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	108
PrevISDYN2CMMMsgRxTime_MSec_M_u32	128415232
PrevISDYNAASMsgDLCError_Cnt_M_u08	156
PrevISDYNAASMsgRxTime_MSec_M_u32	2846467584
PrevISDYNABRMsgDLCError_Cnt_M_u08	226
PrevISDYNABRMsgRxTime_MSec_M_u32	3359827456
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	226
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2475599360
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	200
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3575809536
PrevISDYNVOLMsgDLCError_Cnt_M_u08	220
PrevISDYNVOLMsgRxTime_MSec_M_u32	4028966400
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2189596160
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	106.480499
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	59898
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	39232
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	28995
VitesseVehicleBVRampValidCount_Cnt_M_u16	13641
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	20354

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	48880
VitesseVehicleBV_Kph_M_f32	157.333893
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	18207
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	41156
VitesseVehiculeRoues_Kph_M_f32	256.645905
k_AASNTCEnableTimeout_mS_u16	60672
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	52804
k_AASNodeTimeout_mS_u16	35904
k_ABSNodeTimeout_mS_u16	13567
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	34896
k_ANGLEVOLANTSigValidThresh_Cnt_u16	21881
k_AngleVolantInvalidThresh_Cnt_u16	28408
k_AngleVolantValidThresh_Cnt_u16	61950
k_BSI552MsgTimeout_mS_u16	57091
k_BSINTCEnableTimeout_mS_u16	64821
k_BSINodeAbsentDiag_Cnt_str.Threshold	46117
k_BSINodeAbsentDiag_Cnt_str.PStep	7885
k_BSINodeAbsentDiag_Cnt_str.NStep	473
k_BSINodeAbsentTimeout_mS_u16	6266
k_BSINodeTimeout_mS_u16	55202
k_BattOvHi_Volt_f32	17.7954998
k_BattOvLo_Volt_f32	20.1737003
k_BattUvHi_Volt_f32	19.2282009
k_BattUvLo_Volt_f32	23.8943996
k_CAVNTCEnableTimeout_mS_u16	23076
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	16159
k_CAVNodeTimeout_mS_u16	46613
k_CMM388MsgTimeout_mS_u16	21717
k_CMM388NTCEnableTimeout_mS_u16	49585
k_CMMNTCEnableTimeout_mS_u16	31930
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	50080
k_CONSANGLECPKMax_HwDeg_f32	357.943512
k_CONSANGLECPKMin_HwDeg_f32	-270.88269
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	64031
k_CONSANGLECPKSigValidThresh_Cnt_u16	37828
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	19830
k_CPKVehicleSpeedValidThresh_Cnt_u16	56607
k_CityParkInputInvalidThresh_Cnt_u16	50338
k_CityParkInputValidThresh_Cnt_u16	6869
k_ComputerRazGCTSigValidThresh_Cnt_u16	38552
k_CptTemporelSigValidThresh_Cnt_u16	34873
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	62832
k_DMDFCTCPKSigValidThresh_Cnt_u16	61357
k_DMDFCTCPKValidCount_Cnt_u16	6200
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	30097
k_DMDRELAXECPKSigValidThresh_Cnt_u16	52326
k_DMDRelaxeConsistentThresh_Cnt_u16	30620
k_DateValidThresh_Cnt_u16	29349
k_DefaultVehSpd_Kph_f32	126.9207
k_DiagMuxOnAbsentTimeout_mS_u16	34935
k_EMNodeTimeout_mS_u16	61574
k_ESPNTCEnableTimeout_mS_u16	1165
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	45288
k_EtatMTSigInvalidThresh_Cnt_u16	13387
k_EtatMTSigValidThresh_Cnt_u16	23041
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	45297
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	47402
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	29726
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	33039
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	11760
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	38824

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	61194
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	13235
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	11937
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	3157
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	50375
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	61034
k_ISDATDIRASentDiag_Cnt_str.Threshold	46594
k_ISDATDIRASentDiag_Cnt_str.PStep	38967
k_ISDATDIRASentDiag_Cnt_str.NStep	17884
k_ISDATDIRASentTimeout_mS_u16	10440
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	28899
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	60354
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	57593
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	29164
k_ISDYNAASChkSumValidThresh_Cnt_u16	15970
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	31646
k_ISDYNAASMsgCountValidThresh_Cnt_u16	45227
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	18448
k_ISDYNAASMsgLenValidThresh_Cnt_u16	16740
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	193
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	16862
k_ISDYNABRChkSumValidThresh_Cnt_u16	21147
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	13552
k_ISDYNABRMsgCountValidThresh_Cnt_u16	31454
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	51545
k_ISDYNABRMsgLenValidThresh_Cnt_u16	31554
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	38557
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	16158
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	1037
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	8575
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	49593
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	15463
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	25270
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	52183
k_ISDYNVOLChkSumValidThresh_Cnt_u16	10856
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	4399
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	10118
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	50098
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	25100
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	47947
k_IgnOnTimeout_mS_u16	27059
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	208.309906
k_PowerCutVehSpdLowThresh_Kph_f32	43.8801994
k_PowerCutVehSpdLowTimeout_mS_u16	33740
k_VBattMaxAAS_Volt_f32	12.3358002
k_VBattMaxBSI_Volt_f32	3.6249001
k_VBattMaxCAV_Volt_f32	1.18929994
k_VBattMaxCMM388_Volt_f32	14.3079004
k_VBattMaxCMM_Volt_f32	4.62220001
k_VBattMaxESP_Volt_f32	18.0564995
k_VBattMinAAS_Volt_f32	2.26780009
k_VBattMinBSI_Volt_f32	18.0564995
k_VBattMinCAV_Volt_f32	7.54269981
k_VBattMinCMM388_Volt_f32	11.4082003
k_VBattMinCMM_Volt_f32	16.2667999
k_VBattMinESP_Volt_f32	4.62220001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	11673
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	25946
k_VitesseVehicleBVRampValidThresh_Cnt_u16	15176
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	34596
k_VitesseVehicleBVSigValidThresh_Cnt_u16	3286
k_VitesseVehicleBVSpeedPassThresh_kph_f32	86.3760986
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	18865
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	9271
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	141346304
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	55161
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3299876608
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	200
target_SrlComInput_Per1_Batt_Volt_f32.value	30.6282005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1287173632
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	210
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.15447551
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	76
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3500467712
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	7
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	825099776
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	207
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2726766080
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	749749760
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3618203136
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2876409344
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2953553408
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	28
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	46
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	58
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	98
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	179
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	189
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4284040704
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	41
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	55
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	177
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2338317824
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	795411968
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2755798528
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	15
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	65
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	157
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	215
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3240113664
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2412
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.909596086
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	89339
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	40.0396004
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	46404

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3299876608	3299876608	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3299876608	3299876608	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	46117	46117	✔
BSINodeAbsentTimer_mS_M_u32	3299876608	3299876608	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3299876608	3299876608	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3299876608	3299876608	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	9937	9937	✔
CONSANGLECPK_HwDeg_M_f32	342.430786	342.430786 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3299876608	3299876608	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3299876608	3299876608	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3299876608	3299876608	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3299876608	3299876608	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3299876608	3299876608	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3299876608	3299876608	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3299876608	3299876608	✔
ESPNTCEnableTimer_mS_M_u32	3299876608	3299876608	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3299876608	3299876608	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	1121	1121	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2235	2235	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3299876608	3299876608	✔
ElecIntTimer_mS_M_u32[1]	101	101	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3299876608	3299876608	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3299876608	3299876608	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3299876608	3299876608	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3299876608	3299876608	✔
IgnOnTimer_mS_M_u32	3299876608	3299876608	✔
IgnTimeOff_Sec_M_u32	3129716448	3129716448	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	76	76	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3500467712	3500467712	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	7	7	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	825099776	825099776	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	207	207	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2726766080	2726766080	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	172	172	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	749749760	749749760	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	605824512	605824512	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	195	195	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2876409344	2876409344	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	15	15	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2953553408	2953553408	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	91	91	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4284040704	4284040704	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	45	45	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2338317824	2338317824	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	795411968	795411968	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	55	55	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2755798528	2755798528	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3240113664	3240113664	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	106.480499	106.480499	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	157.333893	157.333893	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	256.645905	256.645905	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	9937	9937	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3129716448	3129716448	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	342.430786	342.430786 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	126.9207	126.9207	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.370 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	840644352
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	7643
AASNodeAbsentTimer_mS_M_u32	1787815680
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	34762
ANGLEVOLANTSigValidCount_Cnt_M_u16	25182
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	56876
AngleVolantMsgTimer_mS_M_u32	840644352
AngleVolantValidCount_Cnt_M_u16	64470
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2729879296
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1161766656
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2953074432
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2637567744
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	58605
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	46061312
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	25232
CAVNodeAbsentTimer_mS_M_u32	316475136
CDD_SrlComVehSpd_Kph_G_f32	430.538086
CMM388NTCEnableTimer_mS_M_u32	452085504
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	428541696
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	28228
CMMNodeAbsentTimer_mS_M_u32	3607631616
CONSANGLECPKSigInvalidCount_Cnt_M_u16	15468
CONSANGLECPKSigValidCount_Cnt_M_u16	44945
CONSANGLECPK_Cnt_M_u16	34920
CONSANGLECPK_HwDeg_M_f32	-546.615112
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	34920
CPKVehicleSpeedMsgTimer_mS_M_u32	3814078208
CPKVehicleSpeedValidCount_Cnt_M_u16	7485

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	47434
CityParkInputInvalidCount_Cnt_M_u16	5860
CityParkInputMsgTimer_mS_M_u32	3691520
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2231625472
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	51535
ComputerRazGCTSigInvalidTimer_mS_M_u32	2724169472
ComputerRazGCTSigValidCount_Cnt_M_u16	34099
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	42352
DMDFCTCPKSigValidCount_Cnt_M_u16	4620
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	6532
DMDRELAXECPKSigValidCount_Cnt_M_u16	43928
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	6589
DateInvalidTimer_mS_M_u32	1161766656
DiagMuxOnAbsentTimer_mS_M_u32	1107556096
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2637567744
ESPNTCEnableTimer_mS_M_u32	3759466240
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	31556
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	64
EffacDefaultDiagTimer_mS_M_u32[1]	894
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	89
ElecIntTimer_mS_M_u32[1]	791
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3629700864
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	56642
EtatMTSigValidCount_Cnt_M_u16	30834
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	31782
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	9931
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	15034
ISDAT4V2BSI552MsgTimer_mS_M_u32	2692486912
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	63029
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	39885
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	30834
ISDATBSI3F2MsgTimer_mS_M_u32	2051667712
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	57212
ISDATBSI412MsgLenValidCount_Cnt_M_u16	26628
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	56642
ISDATBSI412MsgTimer_mS_M_u32	140588800
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	9912
ISDATBSI432MsgLenValidCount_Cnt_M_u16	25272
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	21429
ISDATDIRASentFltAcc_Cnt_M_u16	14201
ISDATDIRASentTimer_mS_M_u32	3814078208
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	35118
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	64470
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	16915
ISDYN2CMMMsgTimer_mS_M_u32	1483138816
ISDYNAASChkSumInvalidCount_Cnt_M_u16	60309
ISDYNAASChkSumValidCount_Cnt_M_u16	61385
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	13945
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	16551
ISDYNAASMsgLenValidCount_Cnt_M_u16	9268
ISDYNAASMsgTimeValidCount_Cnt_M_u16	60309
ISDYNAASMsgTimer_mS_M_u32	1115571968
ISDYNABRChkSumInvalidCount_Cnt_M_u16	58213
ISDYNABRChkSumValidCount_Cnt_M_u16	63073
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	8888
ISDYNABRMsgCountValidCount_Cnt_M_u16	19244
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	49807
ISDYNABRMsgLenValidCount_Cnt_M_u16	39412
ISDYNABRMsgTimeValidCount_Cnt_M_u16	34920

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	7518
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	49869
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	30834
ISDYNCMM208MsgTimer_mS_M_u32	601859840
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	7518
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	49869
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	13596
ISDYNCMM388MsgTimer_mS_M_u32	3824142080
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	3250
ISDYNVOLChkSumValidCount_Cnt_M_u16	18519
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	1206
ISDYNVOLMsgCountValidCount_Cnt_M_u16	31186
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	53025
ISDYNVOLMsgLenValidCount_Cnt_M_u16	63653
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28228
ISDYNVOLMsgTimer_mS_M_u32	636192512
IgnOnTimer_mS_M_u32	878954240
IgnTimeOff_Sec_M_u32	1296432383
ManVehSpd_Kph_M_f32	480.058899
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	163
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	188
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2623010560
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	237
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1032279808
PrevISDATBSI412MsgDLCError_Cnt_M_u08	72
PrevISDATBSI412MsgRxTime_MSec_M_u32	96601856
PrevISDATBSI432MsgDLCError_Cnt_M_u08	202
PrevISDATBSI432MsgRxTime_MSec_M_u32	4021872384
PrevISDATDIRAMsgTxTime_MSec_M_u32	4102424320
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	206
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3894515456
PrevISDYNAASMsgDLCError_Cnt_M_u08	12
PrevISDYNAASMsgRxTime_MSec_M_u32	2393999104
PrevISDYNABRMsgDLCError_Cnt_M_u08	226
PrevISDYNABRMsgRxTime_MSec_M_u32	3799762688
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	167
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1398441728
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	111
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4186957568
PrevISDYNVOLMsgDLCError_Cnt_M_u08	85
PrevISDYNVOLMsgRxTime_MSec_M_u32	1067648768
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1034368768
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	622.710083
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	15853
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	43514
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	56650
VitesseVehicleBVRampValidCount_Cnt_M_u16	1303
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	61095

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	9467
VitesseVehicleBV_Kph_M_f32	350.791595
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	13596
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	40712
VitesseVehiculeRoues_Kph_M_f32	71.893898
k_AASNTCEnableTimeout_mS_u16	14563
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	38917
k_AASNodeTimeout_mS_u16	47354
k_ABSNodeTimeout_mS_u16	10585
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	47399
k_ANGLEVOLANTSigValidThresh_Cnt_u16	14951
k_AngleVolantInvalidThresh_Cnt_u16	61042
k_AngleVolantValidThresh_Cnt_u16	5860
k_BSI552MsgTimeout_mS_u16	24275
k_BSINTCEnableTimeout_mS_u16	1232
k_BSINodeAbsentDiag_Cnt_str.Threshold	62105
k_BSINodeAbsentDiag_Cnt_str.PStep	44405
k_BSINodeAbsentDiag_Cnt_str.NStep	23046
k_BSINodeAbsentTimeout_mS_u16	63044
k_BSINodeTimeout_mS_u16	21429
k_BattOvHi_Volt_f32	10.2452002
k_BattOvLo_Volt_f32	26.4750004
k_BattUvHi_Volt_f32	2.34809995
k_BattUvLo_Volt_f32	28.9726009
k_CAVNTCEnableTimeout_mS_u16	49730
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	50902
k_CAVNodeTimeout_mS_u16	15352
k_CMM388MsgTimeout_mS_u16	27867
k_CMM388NTCEnableTimeout_mS_u16	359
k_CMMNTCEnableTimeout_mS_u16	41037
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	24980
k_CONSANGLECPKMax_HwDeg_f32	255.964294
k_CONSANGLECPKMin_HwDeg_f32	-283.164795
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	1052
k_CONSANGLECPKSigValidThresh_Cnt_u16	44552
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	18600
k_CPKVehicleSpeedValidThresh_Cnt_u16	43603
k_CityParkInputInvalidThresh_Cnt_u16	16787
k_CityParkInputValidThresh_Cnt_u16	47434
k_ComputerRazGCTSigValidThresh_Cnt_u16	11459
k_CptTemporelSigValidThresh_Cnt_u16	16603
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	4495
k_DMDFCTCPKSigValidThresh_Cnt_u16	10484
k_DMDFCTCPKValidCount_Cnt_u16	27605
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	16915
k_DMDRELAXECPKSigValidThresh_Cnt_u16	62191
k_DMDRelaxeConsistentThresh_Cnt_u16	29853
k_DateValidThresh_Cnt_u16	15034
k_DefaultVehSpd_Kph_f32	147.073593
k_DiagMuxOnAbsentTimeout_mS_u16	47942
k_EMNodeTimeout_mS_u16	46237
k_ESPNTCEnableTimeout_mS_u16	27676
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	11132
k_EtatMTSigInvalidThresh_Cnt_u16	13520
k_EtatMTSigValidThresh_Cnt_u16	4620
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	223
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	45167
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	21159
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	51750
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	12926
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	30192

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	14889
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	55529
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	7980
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	47548
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	6884
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	57207
k_ISDATDIRASentDiag_Cnt_str.Threshold	53628
k_ISDATDIRASentDiag_Cnt_str.PStep	31362
k_ISDATDIRASentDiag_Cnt_str.NStep	51301
k_ISDATDIRASentTimeout_mS_u16	6385
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	30112
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	56876
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	44408
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	45669
k_ISDYNAASChkSumValidThresh_Cnt_u16	1377
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	29112
k_ISDYNAASMsgCountValidThresh_Cnt_u16	55852
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	48345
k_ISDYNAASMsgLenValidThresh_Cnt_u16	44654
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	55887
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	27093
k_ISDYNABRChkSumValidThresh_Cnt_u16	18874
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	13293
k_ISDYNABRMsgCountValidThresh_Cnt_u16	62145
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	32068
k_ISDYNABRMsgLenValidThresh_Cnt_u16	51780
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	28172
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	21345
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	24345
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	15301
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	54986
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	61790
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	17148
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	27755
k_ISDYNVOLChkSumValidThresh_Cnt_u16	6707
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	50837
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	48853
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	32718
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	11262
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	152
k_IgnOnTimeout_mS_u16	26103
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	70.4803009
k_PowerCutVehSpdLowThresh_Kph_f32	182.206894
k_PowerCutVehSpdLowTimeout_mS_u16	51231
k_VBattMaxAAS_Volt_f32	15.6356001
k_VBattMaxBSI_Volt_f32	4.48780012
k_VBattMaxCAV_Volt_f32	17.5790005
k_VBattMaxCMM388_Volt_f32	4.01009989
k_VBattMaxCMM_Volt_f32	5.14300013
k_VBattMaxESP_Volt_f32	14.1036997
k_VBattMinAAS_Volt_f32	32
k_VBattMinBSI_Volt_f32	14.1036997
k_VBattMinCAV_Volt_f32	5.70359993
k_VBattMinCMM388_Volt_f32	3.68390012
k_VBattMinCMM_Volt_f32	31.2283993
k_VBattMinESP_Volt_f32	5.14300013
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	56562
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	23979
k_VitesseVehicleBVRampValidThresh_Cnt_u16	54198
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	55127
k_VitesseVehicleBVSigValidThresh_Cnt_u16	50879
k_VitesseVehicleBVSpeedPassThresh_kph_f32	302.810486
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	12688
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	8669
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1161766656
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	28870
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	4009874432
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	111
target_SrlComInput_Per1_Batt_Volt_f32.value	2.19359994
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3099842304
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	62
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.330748618
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3175466752
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	894527232
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3429697280
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	714647296
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4157884160
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3693078272
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2138801920
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	212
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	102
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1557505792
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	77
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	79
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	150
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	169
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	192
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	364693248
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3880281856
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2548303616
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1787909888
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	81
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0176887717
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1038194
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	170.296997
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	25791

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	56878	56878	✔
AngleVolantMsgTimer_mS_M_u32	4009874432	4009874432	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	62105	62105	✔
BSINodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	34920	34920	✔
CONSANGLECPK_HwDeg_M_f32	-546.615112	-546.615112 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	34920	34920	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3814078208	3814078208	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	7485	7485	✔
CityParkInputConsistentCount_Cnt_M_u16	47434	47434	✔
CityParkInputInvalidCount_Cnt_M_u16	5862	5862	✔
CityParkInputMsgTimer_mS_M_u32	4009874432	4009874432	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4009874432	4009874432	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4009874432	4009874432	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4009874432	4009874432	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4009874432	4009874432	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4009874432	4009874432	✔
ESPNTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	4009874432	4009874432	✔
EffacDefaultDiagTimer_mS_M_u32[1]	894	894	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4009874432	4009874432	✔
ElecIntTimer_mS_M_u32[1]	791	791	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4009874432	4009874432	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	4009874432	4009874432	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4009874432	4009874432	✔
IgnOnTimer_mS_M_u32	878954240	878954240	✔
IgnTimeOff_Sec_M_u32	1296432383	1296432383	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	16	16	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3175466752	3175466752	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	55	55	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	894527232	894527232	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	170	170	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3429697280	3429697280	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	16	16	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	714647296	714647296	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4102424320	4102424320	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	84	84	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3693078272	3693078272	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	131	131	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2138801920	2138801920	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	102	102	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1557505792	1557505792	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	364693248	364693248	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3880281856	3880281856	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	241	241	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2548303616	2548303616	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1787909888	1787909888	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	622.710083	622.710083	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	350.791595	350.791595	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	71.893898	71.893898	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	34920	34920	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1296432383	1296432383	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-546.615112	-546.615112 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	147.073593	147.073593	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.371 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3270057472
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	41383
AASNodeAbsentTimer_mS_M_u32	139136512
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	15836
ANGLEVOLANTSigValidCount_Cnt_M_u16	31455
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	58548
AngleVolantMsgTimer_mS_M_u32	3270057472
AngleVolantValidCount_Cnt_M_u16	47671
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1792462336
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1161645568
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3584933376
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	85491200
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	29299
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3883810304
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	36872
CAVNodeAbsentTimer_mS_M_u32	736341504
CDD_SrlComVehSpd_Kph_G_f32	201.763107
CMM388NTCEnableTimer_mS_M_u32	4171492864
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1339665920
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	50861
CMMNodeAbsentTimer_mS_M_u32	530742784
CONSANGLECPKSigInvalidCount_Cnt_M_u16	6899
CONSANGLECPKSigValidCount_Cnt_M_u16	52807
CONSANGLECPK_Cnt_M_u16	24514
CONSANGLECPK_HwDeg_M_f32	-544.289185
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	24514
CPKVehicleSpeedMsgTimer_mS_M_u32	1530404352
CPKVehicleSpeedValidCount_Cnt_M_u16	31305
CityParkInputConsistentCount_Cnt_M_u16	20955

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	29196
CityParkInputMsgTimer_mS_M_u32	3175466752
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2297368064
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	28491
ComputerRazGCTSigInvalidTimer_mS_M_u32	2807836160
ComputerRazGCTSigValidCount_Cnt_M_u16	53792
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	63080
DMDFCTCPKSigValidCount_Cnt_M_u16	40276
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	61614
DMDRELAXECPKSigValidCount_Cnt_M_u16	1841
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	1792
DateInvalidTimer_mS_M_u32	1161645568
DiagMuxOnAbsentTimer_mS_M_u32	640605696
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	85491200
ESPNTCEnableTimer_mS_M_u32	4223405568
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	7277
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1123
EffacDefaultDiagTimer_mS_M_u32[1]	5523
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	56
ElecIntTimer_mS_M_u32[1]	458
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1320173056
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	17075
EtatMTSigValidCount_Cnt_M_u16	44514
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	50117
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	53401
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	23370
ISDAT4V2BSI552MsgTimer_mS_M_u32	2470870528
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	56154
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	51025
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	44514
ISDATBSI3F2MsgTimer_mS_M_u32	358407680
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	19588
ISDATBSI412MsgLenValidCount_Cnt_M_u16	20396
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	17075
ISDATBSI412MsgTimer_mS_M_u32	3625393664
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	27985
ISDATBSI432MsgLenValidCount_Cnt_M_u16	13841
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	37017
ISDATDIRASentFltAcc_Cnt_M_u16	62797
ISDATDIRASentTimer_mS_M_u32	1530404352
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	62832
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	47671
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	27775
ISDYN2CMMMsgTimer_mS_M_u32	1522929152
ISDYNAASChkSumInvalidCount_Cnt_M_u16	41081
ISDYNAASChkSumValidCount_Cnt_M_u16	57501
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	22094
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	4547
ISDYNAASMsgLenValidCount_Cnt_M_u16	5086
ISDYNAASMsgTimeValidCount_Cnt_M_u16	41081
ISDYNAASMsgTimer_mS_M_u32	2986339840
ISDYNABRChkSumInvalidCount_Cnt_M_u16	44683
ISDYNABRChkSumValidCount_Cnt_M_u16	57942
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	18192
ISDYNABRMsgCountValidCount_Cnt_M_u16	6772
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	54410
ISDYNABRMsgLenValidCount_Cnt_M_u16	23326
ISDYNABRMsgTimeValidCount_Cnt_M_u16	24514
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	58812

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	16173
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	44514
ISDYNCMM208MsgTimer_mS_M_u32	3411791360
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	58812
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	16173
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	42597
ISDYNCMM388MsgTimer_mS_M_u32	1940614656
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	16929
ISDYNVOLChkSumValidCount_Cnt_M_u16	39925
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	28822
ISDYNVOLMsgCountValidCount_Cnt_M_u16	65026
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	54486
ISDYNVOLMsgLenValidCount_Cnt_M_u16	58633
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	50861
ISDYNVOLMsgTimer_mS_M_u32	1287138816
IgnOnTimer_mS_M_u32	1380937216
IgnTimeOff_Sec_M_u32	1681325777
ManVehSpd_Kph_M_f32	296.123291
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	164
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	228
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1731386880
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	194
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4179934720
PrevISDATBSI412MsgDLCError_Cnt_M_u08	21
PrevISDATBSI412MsgRxTime_MSec_M_u32	657763840
PrevISDATBSI432MsgDLCError_Cnt_M_u08	50
PrevISDATBSI432MsgRxTime_MSec_M_u32	1557138944
PrevISDATDIRAMsgTxTime_MSec_M_u32	1793633792
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	24
PrevISDYN2CMMMsgRxTime_MSec_M_u32	844496384
PrevISDYNAASMsgDLCError_Cnt_M_u08	68
PrevISDYNAASMsgRxTime_MSec_M_u32	2858823168
PrevISDYNABRMsgDLCError_Cnt_M_u08	15
PrevISDYNABRMsgRxTime_MSec_M_u32	2819059200
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	225
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1080765952
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	174
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1531645440
PrevISDYNVOLMsgDLCError_Cnt_M_u08	110
PrevISDYNVOLMsgRxTime_MSec_M_u32	1032957440
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3494190592
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	573.863586
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	45553
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	6796
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	34778
VitesseVehicleBVRampValidCount_Cnt_M_u16	48437
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	48453
VitesseVehicleBVSigValidCount_Cnt_M_u16	59144

Name	Input Value
VitesseVehicleBV_Kph_M_f32	535.86438
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	42597
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	38241
VitesseVehiculeRoues_Kph_M_f32	202.169907
k_AASNTCEnableTimeout_mS_u16	64081
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	25002
k_AASNodeTimeout_mS_u16	60812
k_ABSNodeTimeout_mS_u16	20141
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	12804
k_ANGLEVOLANTSigValidThresh_Cnt_u16	11012
k_AngleVolantInvalidThresh_Cnt_u16	64227
k_AngleVolantValidThresh_Cnt_u16	29196
k_BSI552MsgTimeout_mS_u16	16896
k_BSINTCEnableTimeout_mS_u16	13065
k_BSINodeAbsentDiag_Cnt_str.Threshold	27019
k_BSINodeAbsentDiag_Cnt_str.PStep	7989
k_BSINodeAbsentDiag_Cnt_str.NStep	53188
k_BSINodeAbsentTimeout_mS_u16	64620
k_BSINodeTimeout_mS_u16	37017
k_BattOvHi_Volt_f32	19.7257996
k_BattOvLo_Volt_f32	0.711399972
k_BattUvHi_Volt_f32	17.8358994
k_BattUvLo_Volt_f32	14.7371998
k_CAVNTCEnableTimeout_mS_u16	26610
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	64310
k_CAVNodeTimeout_mS_u16	19535
k_CMM388MsgTimeout_mS_u16	46247
k_CMM388NTCEnableTimeout_mS_u16	9987
k_CMMNTCEnableTimeout_mS_u16	15634
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	32189
k_CONSANGLECPKMax_HwDeg_f32	718.537781
k_CONSANGLECPKMin_HwDeg_f32	-549.92749
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	14693
k_CONSANGLECPKSigValidThresh_Cnt_u16	26721
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	30338
k_CPKVehicleSpeedValidThresh_Cnt_u16	2047
k_CityParkInputInvalidThresh_Cnt_u16	52225
k_CityParkInputValidThresh_Cnt_u16	20955
k_ComputerRazGCTSigValidThresh_Cnt_u16	61360
k_CptTemporelSigValidThresh_Cnt_u16	36903
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	59274
k_DMDFCTCPKSigValidThresh_Cnt_u16	44574
k_DMDFCTCPKValidCount_Cnt_u16	32187
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	27775
k_DMDRELAXECPKSigValidThresh_Cnt_u16	18091
k_DMDRelaxeConsistentThresh_Cnt_u16	63905
k_DateValidThresh_Cnt_u16	23370
k_DefaultVehSpd_Kph_f32	134.508804
k_DiagMuxOnAbsentTimeout_mS_u16	48936
k_EMNodeTimeout_mS_u16	46688
k_ESPNTCEnableTimeout_mS_u16	41828
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	49157
k_EtatMTSigInvalidThresh_Cnt_u16	9802
k_EtatMTSigValidThresh_Cnt_u16	64341
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	59869
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	38893
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	14788
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	25479
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	1854
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	22824
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	14078

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	55166
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	21493
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	7110
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	5389
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	18835
k_ISDATDIRASentDiag_Cnt_str.Threshold	1905
k_ISDATDIRASentDiag_Cnt_str.PStep	4278
k_ISDATDIRASentDiag_Cnt_str.NStep	49319
k_ISDATDIRASentTimeout_mS_u16	15847
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	27416
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58548
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	20304
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	16779
k_ISDYNAASChkSumValidThresh_Cnt_u16	46422
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	23056
k_ISDYNAASMsgCountValidThresh_Cnt_u16	28020
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	61999
k_ISDYNAASMsgLenValidThresh_Cnt_u16	56624
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	60236
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	30392
k_ISDYNABRChkSumValidThresh_Cnt_u16	58316
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	34163
k_ISDYNABRMsgCountValidThresh_Cnt_u16	5558
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	39341
k_ISDYNABRMsgLenValidThresh_Cnt_u16	12141
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	36821
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	16789
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	33197
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	20779
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	20700
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	52703
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	19908
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	8631
k_ISDYNVOLChkSumValidThresh_Cnt_u16	46367
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	48762
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	22778
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	35599
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	49982
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	432
k_IgnOnTimeout_mS_u16	25875
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	180.788498
k_PowerCutVehSpdLowThresh_Kph_f32	205.608902
k_PowerCutVehSpdLowTimeout_mS_u16	15517
k_VBattMaxAAS_Volt_f32	11.0662003
k_VBattMaxBSI_Volt_f32	11.0584002
k_VBattMaxCAV_Volt_f32	0.305400014
k_VBattMaxCMM388_Volt_f32	3.43569994
k_VBattMaxCMM_Volt_f32	16.8917999
k_VBattMaxESP_Volt_f32	9.82890034
k_VBattMinAAS_Volt_f32	0.654699981
k_VBattMinBSI_Volt_f32	9.82890034
k_VBattMinCAV_Volt_f32	2.51259995
k_VBattMinCMM388_Volt_f32	16.3703003
k_VBattMinCMM_Volt_f32	2.15389991
k_VBattMinESP_Volt_f32	16.8917999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	64802
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	55225
k_VitesseVehicleBVRampValidThresh_Cnt_u16	918
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	61173
k_VitesseVehicleBVSigValidThresh_Cnt_u16	15740
k_VitesseVehicleBVSpeedPassThresh_kph_f32	167.6828
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	8968
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	65251
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1161645568
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	23985
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	4142483200
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	174
target_SrlComInput_Per1_Batt_Volt_f32.value	4.26030016
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	426720768
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	234
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0339200608
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3215552000
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	98
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2382794240
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	97
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1060351488
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	199
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3677408768
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1778249216
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	230
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4087025152
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	176
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2148019712
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	45
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	109
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	139
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	179
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	249
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2021248512
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	2
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	122
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	178
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	163
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1380216320
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	337743360
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	41
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2026810880
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	78
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	96
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	108
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	148
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	238
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	436649472
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3736
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.626384676
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	565879
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	225.588593

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	1403		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4142483200	4142483200	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	58550	58550	✔
AngleVolantMsgTimer_mS_M_u32	4142483200	4142483200	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	27019	27019	✔
BSINodeAbsentTimer_mS_M_u32	4142483200	4142483200	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4142483200	4142483200	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4142483200	4142483200	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	24514	24514	✔
CONSANGLECPK_HwDeg_M_f32	-544.289185	-544.289185 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	24514	24514	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1530404352	1530404352	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	31305	31305	✔
CityParkInputConsistentCount_Cnt_M_u16	20955	20955	✔
CityParkInputInvalidCount_Cnt_M_u16	29198	29198	✔
CityParkInputMsgTimer_mS_M_u32	4142483200	4142483200	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4142483200	4142483200	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4142483200	4142483200	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4142483200	4142483200	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4142483200	4142483200	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4142483200	4142483200	✔
ESPNTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4142483200	4142483200	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4142483200	4142483200	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	5523	5523	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	4142483200	4142483200	✔
ElecIntTimer_mS_M_u32[1]	458	458	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4142483200	4142483200	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	4142483200	4142483200	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4142483200	4142483200	✔
IgnOnTimer_mS_M_u32	4142483200	4142483200	✔
IgnTimeOff_Sec_M_u32	1681325777	1681325777	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	195	195	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3215552000	3215552000	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	98	98	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2382794240	2382794240	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	97	97	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1060351488	1060351488	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	199	199	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3677408768	3677408768	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1793633792	1793633792	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	230	230	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4087025152	4087025152	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	176	176	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2148019712	2148019712	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	249	249	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2021248512	2021248512	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	163	163	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1380216320	1380216320	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	215	215	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	337743360	337743360	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	41	41	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2026810880	2026810880	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	436649472	436649472	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	573.863586	573.863586	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	535.86438	535.86438	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	202.169907	202.169907	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	24514	24514	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1681325777	1681325777	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-544.289185	-544.289185 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	134.508804	134.508804	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.372 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	670683904
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	23986
AASNodeAbsentTimer_mS_M_u32	291734272
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	22200
ANGLEVOLANTSigValidCount_Cnt_M_u16	14922
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	58611
AngleVolantMsgTimer_mS_M_u32	670683904
AngleVolantValidCount_Cnt_M_u16	39810
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2552120064
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2015281920
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	886108928
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2749805312
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	34219
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	434336512
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	21653
CAVNodeAbsentTimer_mS_M_u32	1381933824
CDD_SrlComVehSpd_Kph_G_f32	236.905106
CMM388NTCEnableTimer_mS_M_u32	3625968384
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	372024064
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	52817
CMMNodeAbsentTimer_mS_M_u32	412660480
CONSANGLECPKSigInvalidCount_Cnt_M_u16	25135
CONSANGLECPKSigValidCount_Cnt_M_u16	5456
CONSANGLECPK_Cnt_M_u16	29879
CONSANGLECPK_HwDeg_M_f32	-595.834412
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	29879
CPKVehicleSpeedMsgTimer_mS_M_u32	2307183360
CPKVehicleSpeedValidCount_Cnt_M_u16	51147
CityParkInputConsistentCount_Cnt_M_u16	61878
CityParkInputInvalidCount_Cnt_M_u16	45229

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	2778800128
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4103570176
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	49638
ComputerRazGCTSigInvalidTimer_mS_M_u32	129573632
ComputerRazGCTSigValidCount_Cnt_M_u16	60175
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	59001
DMDFCTCPKSigValidCount_Cnt_M_u16	39826
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	34002
DMDRELAXECPKSigValidCount_Cnt_M_u16	42980
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	13936
DateInvalidTimer_mS_M_u32	2015281920
DiagMuxOnAbsentTimer_mS_M_u32	576099072
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2749805312
ESPNTCEnableTimer_mS_M_u32	1788379904
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	52623
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	579
EffacDefaultDiagTimer_mS_M_u32[1]	989
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2323
ElecIntTimer_mS_M_u32[1]	454646
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3453842176
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	14444
EtatMTSigValidCount_Cnt_M_u16	8921
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24137
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	53482
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	24928
ISDAT4V2BSI552MsgTimer_mS_M_u32	3133977344
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	42161
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	54022
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	8921
ISDATBSI3F2MsgTimer_mS_M_u32	507286272
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	20612
ISDATBSI412MsgLenValidCount_Cnt_M_u16	29385
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	14444
ISDATBSI412MsgTimer_mS_M_u32	3789542144
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	28549
ISDATBSI432MsgLenValidCount_Cnt_M_u16	44483
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	61290
ISDATDIRASentFltAcc_Cnt_M_u16	50926
ISDATDIRASentTimer_mS_M_u32	2307183360
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	45341
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	39810
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	23788
ISDYN2CMMMsgTimer_mS_M_u32	902464256
ISDYNAASChkSumInvalidCount_Cnt_M_u16	1996
ISDYNAASChkSumValidCount_Cnt_M_u16	64253
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	53237
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	25916
ISDYNAASMsgLenValidCount_Cnt_M_u16	25157
ISDYNAASMsgTimeValidCount_Cnt_M_u16	1996
ISDYNAASMsgTimer_mS_M_u32	384557824
ISDYNABRChkSumInvalidCount_Cnt_M_u16	47909
ISDYNABRChkSumValidCount_Cnt_M_u16	12446
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	28863
ISDYNABRMsgCountValidCount_Cnt_M_u16	17456
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	10786
ISDYNABRMsgLenValidCount_Cnt_M_u16	64899
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	34243
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	37744

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	8921
ISDYNCMM208MsgTimer_mS_M_u32	4072096512
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	34243
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	37744
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	34920
ISDYNCMM388MsgTimer_mS_M_u32	4081410816
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	30229
ISDYNVOLChkSumValidCount_Cnt_M_u16	27062
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	39263
ISDYNVOLMsgCountValidCount_Cnt_M_u16	52984
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	16284
ISDYNVOLMsgLenValidCount_Cnt_M_u16	49949
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	52817
ISDYNVOLMsgTimer_mS_M_u32	3800376064
IgnOnTimer_mS_M_u32	2893636352
IgnTimeOff_Sec_M_u32	1892314162
ManVehSpd_Kph_M_f32	499.754395
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	176
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	89
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3345650432
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	102
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	237236992
PrevISDATBSI412MsgDLCError_Cnt_M_u08	118
PrevISDATBSI412MsgRxTime_MSec_M_u32	3539182336
PrevISDATBSI432MsgDLCError_Cnt_M_u08	245
PrevISDATBSI432MsgRxTime_MSec_M_u32	805077760
PrevISDATDIRAMsgTxTime_MSec_M_u32	91726592
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	177
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1243230976
PrevISDYNAASMsgDLCError_Cnt_M_u08	181
PrevISDYNAASMsgRxTime_MSec_M_u32	116073216
PrevISDYNABRMsgDLCError_Cnt_M_u08	77
PrevISDYNABRMsgRxTime_MSec_M_u32	2568053504
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	37
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1828987648
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	56
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2959311616
PrevISDYNVOLMsgDLCError_Cnt_M_u08	151
PrevISDYNVOLMsgRxTime_MSec_M_u32	4207190784
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	180736768
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	282.217804
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	54818
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	54187
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	56239
VitesseVehicleBVRampValidCount_Cnt_M_u16	55544
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	43973
VitesseVehicleBVSigValidCount_Cnt_M_u16	12055
VitesseVehicleBV_Kph_M_f32	610.114807

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	34920
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	9682
VitesseVehiculeRoues_Kph_M_f32	277.39679
k_AASNTCEnableTimeout_mS_u16	57730
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	43201
k_AASNodeTimeout_mS_u16	62123
k_ABSNodeTimeout_mS_u16	6098
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	3844
k_ANGLEVOLANTSigValidThresh_Cnt_u16	16002
k_AngleVolantInvalidThresh_Cnt_u16	13789
k_AngleVolantValidThresh_Cnt_u16	45229
k_BSI552MsgTimeout_mS_u16	27885
k_BSINTCEnableTimeout_mS_u16	35869
k_BSINodeAbsentDiag_Cnt_str.Threshold	62697
k_BSINodeAbsentDiag_Cnt_str.PStep	59576
k_BSINodeAbsentDiag_Cnt_str.NStep	29963
k_BSINodeAbsentTimeout_mS_u16	39819
k_BSINodeTimeout_mS_u16	61290
k_BattOvHi_Volt_f32	24.0977001
k_BattOvLo_Volt_f32	3.23000002
k_BattUvHi_Volt_f32	14.0136995
k_BattUvLo_Volt_f32	17.1187
k_CAVNTCEnableTimeout_mS_u16	3627
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	48251
k_CAVNodeTimeout_mS_u16	63739
k_CMM388MsgTimeout_mS_u16	48306
k_CMM388NTCEnableTimeout_mS_u16	39038
k_CMMNTCEnableTimeout_mS_u16	52553
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	20382
k_CONSANGLECPKMax_HwDeg_f32	558.451782
k_CONSANGLECPKMin_HwDeg_f32	-557.31073
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	26472
k_CONSANGLECPKSigValidThresh_Cnt_u16	17618
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	44921
k_CPKVehicleSpeedValidThresh_Cnt_u16	33259
k_CityParkInputInvalidThresh_Cnt_u16	24179
k_CityParkInputValidThresh_Cnt_u16	61878
k_ComputerRazGCTSigValidThresh_Cnt_u16	6751
k_CptTemporelSigValidThresh_Cnt_u16	53044
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	35106
k_DMDFCTCPKSigValidThresh_Cnt_u16	40067
k_DMDFCTCPKValidCount_Cnt_u16	32275
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	23788
k_DMDRELAXECPKSigValidThresh_Cnt_u16	4677
k_DMDRelaxeConsistentThresh_Cnt_u16	41235
k_DateValidThresh_Cnt_u16	24928
k_DefaultVehSpd_Kph_f32	148.966599
k_DiagMuxOnAbsentTimeout_mS_u16	57781
k_EMNodeTimeout_mS_u16	41808
k_ESPNTCEnableTimeout_mS_u16	21857
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	23302
k_EtatMTSigInvalidThresh_Cnt_u16	63968
k_EtatMTSigValidThresh_Cnt_u16	38297
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	30784
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	45325
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	20803
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	34194
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	19111
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	61368
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	38886
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	3300

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	20665
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	32971
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	29104
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	6091
k_ISDATDIRASentDiag_Cnt_str.Threshold	28362
k_ISDATDIRASentDiag_Cnt_str.PStep	56832
k_ISDATDIRASentDiag_Cnt_str.NStep	61321
k_ISDATDIRASentTimeout_mS_u16	10225
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	14180
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58611
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	53501
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	39461
k_ISDYNAASChkSumValidThresh_Cnt_u16	20382
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	53183
k_ISDYNAASMsgCountValidThresh_Cnt_u16	58160
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	27993
k_ISDYNAASMsgLenValidThresh_Cnt_u16	223
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	49130
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	42248
k_ISDYNABRChkSumValidThresh_Cnt_u16	63721
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	58539
k_ISDYNABRMsgCountValidThresh_Cnt_u16	26749
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	60753
k_ISDYNABRMsgLenValidThresh_Cnt_u16	11407
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	45848
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	1110
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	12881
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	52422
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	46520
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	55626
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	15173
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	17027
k_ISDYNVOLChkSumValidThresh_Cnt_u16	13832
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	12240
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	57810
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	16952
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	11685
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	12638
k_IgnOnTimeout_mS_u16	13135
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	115.365501
k_PowerCutVehSpdLowThresh_Kph_f32	159.467102
k_PowerCutVehSpdLowTimeout_mS_u16	19710
k_VBattMaxAAS_Volt_f32	24.4479008
k_VBattMaxBSI_Volt_f32	18.0926991
k_VBattMaxCAV_Volt_f32	17.1145
k_VBattMaxCMM388_Volt_f32	1.6997
k_VBattMaxCMM_Volt_f32	24.4428997
k_VBattMaxESP_Volt_f32	19.0995998
k_VBattMinAAS_Volt_f32	3.65019989
k_VBattMinBSI_Volt_f32	19.0995998
k_VBattMinCAV_Volt_f32	5.78550005
k_VBattMinCMM388_Volt_f32	19.2577
k_VBattMinCMM_Volt_f32	31.5132008
k_VBattMinESP_Volt_f32	24.4428997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	406
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	55563
k_VitesseVehicleBVRampValidThresh_Cnt_u16	30815
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	2230
k_VitesseVehicleBVSigValidThresh_Cnt_u16	41947
k_VitesseVehicleBVSpeedPassThresh_kph_f32	460.051392
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	13205
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	29022
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2015281920
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	45551
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1367695616
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	56

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	28.1040993
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2878894848
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	172
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.155400917
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1060856576
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1108148992
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	854500096
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	970998528
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2128732928
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	703824640
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1662329600
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	46
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	48
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	68
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	137
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	161
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	188
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	187
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	609043200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	93
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	167
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	187
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2755814144
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1754530560
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3673531136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	37
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	85
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	130
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	156
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	174
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3800953600
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3676
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.643172741
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	863377
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	166.865799
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	26580

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1367695616	1367695616	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
CDD_SrlComVehSpd_Kph_G_f32	499.754395	499.754395	✔
CMM388NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	29879	29879	✔
CONSANGLECPK_HwDeg_M_f32	-595.834412	-595.834412 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1367695616	1367695616	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1367695616	1367695616	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1367695616	1367695616	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1367695616	1367695616	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1367695616	1367695616	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1367695616	1367695616	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1367695616	1367695616	✔
ESPNTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	579	579	✔
EffacDefaultDiagTimer_mS_M_u32[1]	989	989	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	2323	2323	✔
ElecIntTimer_mS_M_u32[1]	454646	454646	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1367695616	1367695616	✔
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	24928	24928	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	8921	8921	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	14444	14444	✔
ISDATBSI412MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	61290	61290	✔
ISDATBSI432MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1367695616	1367695616	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	23788	23788	✔
ISDYN2CMMMsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	1996	1996	✔
ISDYNAASMsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	8921	8921	✔
ISDYNCMM208MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	34920	34920	✔
ISDYNCMM388MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	52817	52817	✔
ISDYNVOLMsgTimer_mS_M_u32	1367695616	1367695616	✔
IgnOnTimer_mS_M_u32	2893636352	2893636352	✔
IgnTimeOff_Sec_M_u32	1892314162	1892314162	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	162	162	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1060856576	1060856576	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	253	253	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1108148992	1108148992	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	178	178	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	854500096	854500096	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	233	233	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	970998528	970998528	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	91726592	91726592	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	125	125	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	703824640	703824640	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1662329600	1662329600	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	187	187	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	609043200	609043200	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	142	142	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2755814144	2755814144	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1754530560	1754530560	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3673531136	3673531136	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3800953600	3800953600	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	282.217804	282.217804	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	610.114807	610.114807	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	277.39679	277.39679	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	29879	29879	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1892314162	1892314162	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-595.834412	-595.834412 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	499.754395	499.754395	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.373 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	784157184
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	3987
AASNodeAbsentTimer_mS_M_u32	1967143424
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	24192
ANGLEVOLANTSigValidCount_Cnt_M_u16	46220
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	48592
AngleVolantMsgTimer_mS_M_u32	784157184
AngleVolantValidCount_Cnt_M_u16	57505
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1007680000
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1041136128
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3434605056
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	108440064
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	23975
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2273339904
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	8042
CAVNodeAbsentTimer_mS_M_u32	114219520
CDD_SrlComVehSpd_Kph_G_f32	437.666992
CMM388NTCEnableTimer_mS_M_u32	176888320
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1935989248
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	28661
CMMNodeAbsentTimer_mS_M_u32	4032866816
CONSANGLECPKSigInvalidCount_Cnt_M_u16	34588
CONSANGLECPKSigValidCount_Cnt_M_u16	44664
CONSANGLECPK_Cnt_M_u16	60483
CONSANGLECPK_HwDeg_M_f32	51.1654015
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	60483
CPKVehicleSpeedMsgTimer_mS_M_u32	4129049088
CPKVehicleSpeedValidCount_Cnt_M_u16	39824
CityParkInputConsistentCount_Cnt_M_u16	44549
CityParkInputInvalidCount_Cnt_M_u16	6691
CityParkInputMsgTimer_mS_M_u32	1060856576
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2611231232
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	45815

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1891588608
ComputerRazGCTSigValidCount_Cnt_M_u16	26106
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	43199
DMDFCTCPKSigValidCount_Cnt_M_u16	43571
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	48178
DMDRELAXECPKSigValidCount_Cnt_M_u16	21438
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	20057
DateInvalidTimer_mS_M_u32	1041136128
DiagMuxOnAbsentTimer_mS_M_u32	2728856064
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	108440064
ESPNTCEnableTimer_mS_M_u32	2107718144
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	8957
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1000
EffacDefaultDiagTimer_mS_M_u32[1]	2000
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	56565
ElecIntTimer_mS_M_u32[1]	787879
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3549587968
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	27302
EtatMTSigValidCount_Cnt_M_u16	7198
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	31438
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	25514
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	4297
ISDAT4V2BSI552MsgTimer_mS_M_u32	3653544448
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	53591
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	22296
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	7198
ISDATBSI3F2MsgTimer_mS_M_u32	3337947648
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	10973
ISDATBSI412MsgLenValidCount_Cnt_M_u16	38094
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	27302
ISDATBSI412MsgTimer_mS_M_u32	420170240
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	23641
ISDATBSI432MsgLenValidCount_Cnt_M_u16	21089
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	58091
ISDATDIRASentFltAcc_Cnt_M_u16	27743
ISDATDIRASentTimer_mS_M_u32	4129049088
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	20241
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	57505
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	53606
ISDYN2CMMMsgTimer_mS_M_u32	1678457344
ISDYNAASChkSumInvalidCount_Cnt_M_u16	63813
ISDYNAASChkSumValidCount_Cnt_M_u16	41074
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	53064
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	18805
ISDYNAASMsgLenValidCount_Cnt_M_u16	13081
ISDYNAASMsgTimeValidCount_Cnt_M_u16	63813
ISDYNAASMsgTimer_mS_M_u32	2116491776
ISDYNABRChkSumInvalidCount_Cnt_M_u16	31929
ISDYNABRChkSumValidCount_Cnt_M_u16	48398
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	19052
ISDYNABRMsgCountValidCount_Cnt_M_u16	20697
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	47939
ISDYNABRMsgLenValidCount_Cnt_M_u16	33247
ISDYNABRMsgTimeValidCount_Cnt_M_u16	65535
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	40609
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	58969
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	7198
ISDYNCMM208MsgTimer_mS_M_u32	3494181376
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	40609
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	58969
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	12783

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	790272512
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	25450
ISDYNVOLChkSumValidCount_Cnt_M_u16	51526
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	43021
ISDYNVOLMsgCountValidCount_Cnt_M_u16	10241
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	16598
ISDYNVOLMsgLenValidCount_Cnt_M_u16	30482
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28661
ISDYNVOLMsgTimer_mS_M_u32	274422272
IgnOnTimer_mS_M_u32	3548289536
IgnTimeOff_Sec_M_u32	2748327474
ManVehSpd_Kph_M_f32	599.658325
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	177
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	83
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	57346560
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	130
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1287580160
PrevISDATBSI412MsgDLCError_Cnt_M_u08	125
PrevISDATBSI412MsgRxTime_MSec_M_u32	420469248
PrevISDATBSI432MsgDLCError_Cnt_M_u08	108
PrevISDATBSI432MsgRxTime_MSec_M_u32	3178576384
PrevISDATDIRAMsgTxTime_MSec_M_u32	2441337344
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	8
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1104947712
PrevISDYNAASMsgDLCError_Cnt_M_u08	113
PrevISDYNAASMsgRxTime_MSec_M_u32	3140049408
PrevISDYNABRMsgDLCError_Cnt_M_u08	55
PrevISDYNABRMsgRxTime_MSec_M_u32	1840683520
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	207
PrevISDYNCMM208MsgRxTime_MSec_M_u32	752769536
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	100
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2554345984
PrevISDYNVOLMsgDLCError_Cnt_M_u08	179
PrevISDYNVOLMsgRxTime_MSec_M_u32	631036416
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3059304960
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	511.962891
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	3779
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	63207
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	29212
VitesseVehicleBVRampValidCount_Cnt_M_u16	23296
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	54105
VitesseVehicleBVSigValidCount_Cnt_M_u16	18981
VitesseVehicleBV_Kph_M_f32	520.473083
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	12783
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	47732
VitesseVehiculeRoues_Kph_M_f32	40.5803986
k_AASNTCEnableTimeout_mS_u16	37346
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	29924
k_AASNodeTimeout_mS_u16	39399
k_ABSNodeTimeout_mS_u16	47284
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	14812
k_ANGLEVOLANTSigValidThresh_Cnt_u16	23588
k_AngleVolantInvalidThresh_Cnt_u16	41491
k_AngleVolantValidThresh_Cnt_u16	6691
k_BSI552MsgTimeout_mS_u16	4387
k_BSINTCEnableTimeout_mS_u16	26257
k_BSINodeAbsentDiag_Cnt_str.Threshold	25262
k_BSINodeAbsentDiag_Cnt_str.PStep	1665
k_BSINodeAbsentDiag_Cnt_str.NStep	61641
k_BSINodeAbsentTimeout_mS_u16	64008
k_BSINodeTimeout_mS_u16	58091
k_BattOvHi_Volt_f32	11.8662004
k_BattOvLo_Volt_f32	19.3398991
k_BattUvHi_Volt_f32	3.33410001
k_BattUvLo_Volt_f32	12.3956003
k_CAVNTCEnableTimeout_mS_u16	31145
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	65464
k_CAVNodeTimeout_mS_u16	62136
k_CMM388MsgTimeout_mS_u16	62099
k_CMM388NTCEnableTimeout_mS_u16	36655
k_CMMNTCEnableTimeout_mS_u16	46991
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	27920
k_CONSANGLECPKMax_HwDeg_f32	144.945297
k_CONSANGLECPKMin_HwDeg_f32	-15.9792004
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	38127
k_CONSANGLECPKSigValidThresh_Cnt_u16	23924
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	7037
k_CPKVehicleSpeedValidThresh_Cnt_u16	62120
k_CityParkInputInvalidThresh_Cnt_u16	19151
k_CityParkInputValidThresh_Cnt_u16	44549
k_ComputerRazGCTSigValidThresh_Cnt_u16	43085
k_CptTemporelSigValidThresh_Cnt_u16	39566
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	40515
k_DMDFCTCPKSigValidThresh_Cnt_u16	42207
k_DMDFCTCPKValidCount_Cnt_u16	5231
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	53606
k_DMDRELAXECPKSigValidThresh_Cnt_u16	53786
k_DMDRelaxeConsistentThresh_Cnt_u16	56752
k_DateValidThresh_Cnt_u16	4297
k_DefaultVehSpd_Kph_f32	102.267197
k_DiagMuxOnAbsentTimeout_mS_u16	7497
k_EMNodeTimeout_mS_u16	34745
k_ESPNTCEnableTimeout_mS_u16	19718
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	60120
k_EtatMTSigInvalidThresh_Cnt_u16	27784
k_EtatMTSigValidThresh_Cnt_u16	14877
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	40232
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	58241
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	862
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	62132
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	46133
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	7489
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	42806
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	63742
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	35005
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	6151
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	38423
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	520
k_ISDATDIRASentDiag_Cnt_str.Threshold	35205

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	52390
k_ISDATDIRASentDiag_Cnt_str.NStep	30922
k_ISDATDIRASentTimeout_mS_u16	26197
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	18237
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	48592
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	18994
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	57273
k_ISDYNAASChkSumValidThresh_Cnt_u16	24590
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	11628
k_ISDYNAASMsgCountValidThresh_Cnt_u16	29657
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	13853
k_ISDYNAASMsgLenValidThresh_Cnt_u16	16203
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	30700
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	25233
k_ISDYNABRChkSumValidThresh_Cnt_u16	42925
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	16551
k_ISDYNABRMsgCountValidThresh_Cnt_u16	46579
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	4853
k_ISDYNABRMsgLenValidThresh_Cnt_u16	1533
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	546
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	21543
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	63862
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	14230
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	16768
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	55180
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	55899
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	4320
k_ISDYNVOLChkSumValidThresh_Cnt_u16	1809
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	16442
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	31090
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	32066
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	11194
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	6351
k_IgnOnTimeout_mS_u16	28284
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	139.570496
k_PowerCutVehSpdLowThresh_Kph_f32	239.265793
k_PowerCutVehSpdLowTimeout_mS_u16	16238
k_VBattMaxAAS_Volt_f32	10.0803003
k_VBattMaxBSI_Volt_f32	2.91330004
k_VBattMaxCAV_Volt_f32	7.04029989
k_VBattMaxCMM388_Volt_f32	22.9272995
k_VBattMaxCMM_Volt_f32	31.8801994
k_VBattMaxESP_Volt_f32	14.6202002
k_VBattMinAAS_Volt_f32	18.9449005
k_VBattMinBSI_Volt_f32	14.6202002
k_VBattMinCAV_Volt_f32	14.3115997
k_VBattMinCMM388_Volt_f32	21.9123993
k_VBattMinCMM_Volt_f32	14.8909998
k_VBattMinESP_Volt_f32	31.8801994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	12455
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	15111
k_VitesseVehicleBVRampValidThresh_Cnt_u16	2829
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	60486
k_VitesseVehicleBVSigValidThresh_Cnt_u16	27542
k_VitesseVehicleBVSpeedPassThresh_kph_f32	120.113503
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	33386
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	43470
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1041136128
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	54541
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	433233920
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	100
target_SrlComInput_Per1_Batt_Volt_f32.value	5.20860004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3865143808
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	20
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0951075926
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2738395648
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1766046208
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	23
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2770262528
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	161
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3737778688
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2655328768
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1804614144
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3467336192
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	209
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	215
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	327350784
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	59
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	77
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	210
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	219
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	233
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	193
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1344510464
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3517889024
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2299124224
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	71
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4152420864
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	442
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.198295653
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	73386
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	197.319702
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	41389

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	433233920	433233920	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	433233920	433233920	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	433233920	433233920	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	433233920	433233920	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	433233920	433233920	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	433233920	433233920	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	433233920	433233920	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	433233920	433233920	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	433233920	433233920	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	433233920	433233920	✔
CDD_SrlComVehSpd_Kph_G_f32	599.658325	599.658325	✔
CMM388NTCEnableTimer_mS_M_u32	433233920	433233920	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	433233920	433233920	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	433233920	433233920	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	60483	60483	✔
CONSANGLECPK_HwDeg_M_f32	51.1654015	51.1654015 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	433233920	433233920	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	433233920	433233920	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	433233920	433233920	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	433233920	433233920	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	433233920	433233920	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	433233920	433233920	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	433233920	433233920	✔
ESPNTCEnableTimer_mS_M_u32	433233920	433233920	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	433233920	433233920	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1000	1000	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2000	2000	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	56565	56565	✔
ElecIntTimer_mS_M_u32[1]	787879	787879	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	433233920	433233920	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	4297	4297	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	433233920	433233920	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	7198	7198	✔
ISDATBSI3F2MsgTimer_mS_M_u32	433233920	433233920	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	27302	27302	✔
ISDATBSI412MsgTimer_mS_M_u32	433233920	433233920	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	58091	58091	✔
ISDATBSI432MsgTimer_mS_M_u32	433233920	433233920	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	433233920	433233920	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	53606	53606	✔
ISDYN2CMMMsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	63813	63813	✔
ISDYNAASMsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	65535	65535	✔
ISDYNABRMsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	7198	7198	✔
ISDYNCMM208MsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	12783	12783	✔
ISDYNCMM388MsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28661	28661	✔
ISDYNVOLMsgTimer_mS_M_u32	433233920	433233920	✔
IgnOnTimer_mS_M_u32	3548289536	3548289536	✔
IgnTimeOff_Sec_M_u32	2748327474	2748327474	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	169	169	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2738395648	2738395648	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	72	72	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1766046208	1766046208	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	23	23	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2770262528	2770262528	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	161	161	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3737778688	3737778688	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2441337344	2441337344	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	2	2	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1804614144	1804614144	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	233	233	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3467336192	3467336192	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	31	31	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	327350784	327350784	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	193	193	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1344510464	1344510464	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	186	186	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3517889024	3517889024	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	166	166	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2299124224	2299124224	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4152420864	4152420864	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	511.962891	511.962891	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	520.473083	520.473083	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	40.5803986	40.5803986	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	60483	60483	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2748327474	2748327474	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	51.1654015	51.1654015 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	599.658325	599.658325	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.374 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2702107904
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	30859
AASNodeAbsentTimer_mS_M_u32	3309704448
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	56773
ANGLEVOLANTSigValidCount_Cnt_M_u16	55648
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	41428
AngleVolantMsgTimer_mS_M_u32	2702107904
AngleVolantValidCount_Cnt_M_u16	26081
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1607914752
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1943753984
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2040464640
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	929219840
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	15440
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	189105408
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	27527
CAVNodeAbsentTimer_mS_M_u32	320484608
CDD_SrlComVehSpd_Kph_G_f32	577.889893
CMM388NTCEnableTimer_mS_M_u32	1222997248
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2774021376
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	16551
CMMNodeAbsentTimer_mS_M_u32	2711930112
CONSANGLECPKSigInvalidCount_Cnt_M_u16	33522
CONSANGLECPKSigValidCount_Cnt_M_u16	19101
CONSANGLECPK_Cnt_M_u16	32060
CONSANGLECPK_HwDeg_M_f32	583.432495
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	32060
CPKVehicleSpeedMsgTimer_mS_M_u32	2263999744
CPKVehicleSpeedValidCount_Cnt_M_u16	38331
CityParkInputConsistentCount_Cnt_M_u16	36277
CityParkInputInvalidCount_Cnt_M_u16	20061
CityParkInputMsgTimer_mS_M_u32	2738395648
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3793360128
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	7775

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	927511808
ComputerRazGCTSigValidCount_Cnt_M_u16	31190
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	4745
DMDFCTCPKSigValidCount_Cnt_M_u16	44011
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	3247
DMDRELAXECPKSigValidCount_Cnt_M_u16	17354
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	24891
DateInvalidTimer_mS_M_u32	1943753984
DiagMuxOnAbsentTimer_mS_M_u32	475112704
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	929219840
ESPNTCEnableTimer_mS_M_u32	1881347328
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	5454
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	2500
EffacDefaultDiagTimer_mS_M_u32[1]	3500
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	556
ElecIntTimer_mS_M_u32[1]	877877
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4010771712
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	42387
EtatMTSigValidCount_Cnt_M_u16	16106
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	61404
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	29447
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20521
ISDAT4V2BSI552MsgTimer_mS_M_u32	1970849024
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	28415
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	43902
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	16106
ISDATBSI3F2MsgTimer_mS_M_u32	1734845696
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	19308
ISDATBSI412MsgLenValidCount_Cnt_M_u16	39771
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	42387
ISDATBSI412MsgTimer_mS_M_u32	2586109184
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	2939
ISDATBSI432MsgLenValidCount_Cnt_M_u16	5922
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	25860
ISDATDIRASentFltAcc_Cnt_M_u16	39080
ISDATDIRASentTimer_mS_M_u32	2263999744
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	3282
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	26081
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	62612
ISDYN2CMMMsgTimer_mS_M_u32	3840218368
ISDYNAASChkSumInvalidCount_Cnt_M_u16	885
ISDYNAASChkSumValidCount_Cnt_M_u16	35760
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	62956
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	55654
ISDYNAASMsgLenValidCount_Cnt_M_u16	31289
ISDYNAASMsgTimeValidCount_Cnt_M_u16	885
ISDYNAASMsgTimer_mS_M_u32	1578202368
ISDYNABRChkSumInvalidCount_Cnt_M_u16	41113
ISDYNABRChkSumValidCount_Cnt_M_u16	64860
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	27648
ISDYNABRMsgCountValidCount_Cnt_M_u16	54907
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	17021
ISDYNABRMsgLenValidCount_Cnt_M_u16	11368
ISDYNABRMsgTimeValidCount_Cnt_M_u16	32060
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	46498
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	35897
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	16106
ISDYNCMM208MsgTimer_mS_M_u32	3073889536
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	46498
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	35897
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	10743

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2033644800
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	42504
ISDYNVOLChkSumValidCount_Cnt_M_u16	45619
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	52383
ISDYNVOLMsgCountValidCount_Cnt_M_u16	60033
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	24515
ISDYNVOLMsgLenValidCount_Cnt_M_u16	31437
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	16551
ISDYNVOLMsgTimer_mS_M_u32	3363091712
IgnOnTimer_mS_M_u32	470480128
IgnTimeOff_Sec_M_u32	1929740595
ManVehSpd_Kph_M_f32	521.998413
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	178
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	168142080
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	124
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3582592256
PrevISDATBSI412MsgDLCError_Cnt_M_u08	8
PrevISDATBSI412MsgRxTime_MSec_M_u32	542586112
PrevISDATBSI432MsgDLCError_Cnt_M_u08	247
PrevISDATBSI432MsgRxTime_MSec_M_u32	10949888
PrevISDATDIRAMsgTxTime_MSec_M_u32	2264610048
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	172
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4214375680
PrevISDYNAASMsgDLCError_Cnt_M_u08	24
PrevISDYNAASMsgRxTime_MSec_M_u32	2148185344
PrevISDYNABRMsgDLCError_Cnt_M_u08	22
PrevISDYNABRMsgRxTime_MSec_M_u32	761459968
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	241
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1055634688
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	200
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1548096768
PrevISDYNVOLMsgDLCError_Cnt_M_u08	149
PrevISDYNVOLMsgRxTime_MSec_M_u32	1857041664
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2050680064
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	380.640411
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	16764
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	59087
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	47985
VitesseVehicleBVRampValidCount_Cnt_M_u16	24196
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	9018
VitesseVehicleBVSigValidCount_Cnt_M_u16	48277
VitesseVehicleBV_Kph_M_f32	3.86529994
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	10743
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	28201
VitesseVehiculeRoues_Kph_M_f32	626.964478
k_AASNTCEnableTimeout_mS_u16	51295
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	29976
k_AASNodeTimeout_mS_u16	64975
k_ABSNodeTimeout_mS_u16	63146
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	16114
k_ANGLEVOLANTSigValidThresh_Cnt_u16	50649
k_AngleVolantInvalidThresh_Cnt_u16	28684
k_AngleVolantValidThresh_Cnt_u16	20061
k_BSI552MsgTimeout_mS_u16	58908
k_BSINTCEnableTimeout_mS_u16	52435
k_BSINodeAbsentDiag_Cnt_str.Threshold	13564
k_BSINodeAbsentDiag_Cnt_str.PStep	52161
k_BSINodeAbsentDiag_Cnt_str.NStep	24362
k_BSINodeAbsentTimeout_mS_u16	52524
k_BSINodeTimeout_mS_u16	25860
k_BattOvHi_Volt_f32	8.64789963
k_BattOvLo_Volt_f32	21.6149998
k_BattUvHi_Volt_f32	20.5967007
k_BattUvLo_Volt_f32	3.28279996
k_CAVNTCEnableTimeout_mS_u16	51147
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	33437
k_CAVNodeTimeout_mS_u16	45086
k_CMM388MsgTimeout_mS_u16	53131
k_CMM388NTCEnableTimeout_mS_u16	27063
k_CMMNTCEnableTimeout_mS_u16	40023
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	50773
k_CONSANGLECPKMax_HwDeg_f32	453.784607
k_CONSANGLECPKMin_HwDeg_f32	-237.806107
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	247
k_CONSANGLECPKSigValidThresh_Cnt_u16	34089
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	20749
k_CPKVehicleSpeedValidThresh_Cnt_u16	57355
k_CityParkInputInvalidThresh_Cnt_u16	3671
k_CityParkInputValidThresh_Cnt_u16	36277
k_ComputerRazGCTSigValidThresh_Cnt_u16	16925
k_CptTemporelSigValidThresh_Cnt_u16	14620
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	39293
k_DMDFCTCPKSigValidThresh_Cnt_u16	50024
k_DMDFCTCPKValidCount_Cnt_u16	14328
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	62612
k_DMDRELAXECPKSigValidThresh_Cnt_u16	36918
k_DMDRelaxeConsistentThresh_Cnt_u16	17780
k_DateValidThresh_Cnt_u16	20521
k_DefaultVehSpd_Kph_f32	126.974701
k_DiagMuxOnAbsentTimeout_mS_u16	33322
k_EMNodeTimeout_mS_u16	13595
k_ESPNTCEnableTimeout_mS_u16	21171
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	27901
k_EtatMTSigInvalidThresh_Cnt_u16	52524
k_EtatMTSigValidThresh_Cnt_u16	33327
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	14348
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	37570
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	12714
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	48872
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	18471
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	1088
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	57060
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	55115
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	5711
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	2544
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	40319
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	16110
k_ISDATDIRASentDiag_Cnt_str.Threshold	62208

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	30559
k_ISDATDIRASentDiag_Cnt_str.NStep	53426
k_ISDATDIRASentTimeout_mS_u16	21445
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	33615
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	41428
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	2863
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	30617
k_ISDYNAASChkSumValidThresh_Cnt_u16	5212
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	49920
k_ISDYNAASMsgCountValidThresh_Cnt_u16	28027
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	1133
k_ISDYNAASMsgLenValidThresh_Cnt_u16	40355
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	37505
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	1171
k_ISDYNABRChkSumValidThresh_Cnt_u16	29438
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	37712
k_ISDYNABRMsgCountValidThresh_Cnt_u16	12587
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	22439
k_ISDYNABRMsgLenValidThresh_Cnt_u16	27726
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	51358
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	336
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	33697
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	41154
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	13509
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	28768
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	60853
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	25955
k_ISDYNVOLChkSumValidThresh_Cnt_u16	4242
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	61847
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	22576
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	56767
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	32790
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	53271
k_IgnOnTimeout_mS_u16	48271
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	205.565002
k_PowerCutVehSpdLowThresh_Kph_f32	234.479095
k_PowerCutVehSpdLowTimeout_mS_u16	61371
k_VBattMaxAAS_Volt_f32	20.7770996
k_VBattMaxBSI_Volt_f32	21.9755993
k_VBattMaxCAV_Volt_f32	6.01730013
k_VBattMaxCMM388_Volt_f32	16.4284992
k_VBattMaxCMM_Volt_f32	22.0219994
k_VBattMaxESP_Volt_f32	8.67210007
k_VBattMinAAS_Volt_f32	22.7684002
k_VBattMinBSI_Volt_f32	8.67210007
k_VBattMinCAV_Volt_f32	31.3507004
k_VBattMinCMM388_Volt_f32	29.4957008
k_VBattMinCMM_Volt_f32	27.3246002
k_VBattMinESP_Volt_f32	22.0219994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	61201
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	7599
k_VitesseVehicleBVRampValidThresh_Cnt_u16	41887
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	18739
k_VitesseVehicleBVSigValidThresh_Cnt_u16	55554
k_VitesseVehicleBVSpeedPassThresh_kph_f32	474.894287
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	17031
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	10778
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1943753984
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	41358
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2292638464
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	200
target_SrlComInput_Per1_Batt_Volt_f32.value	7.97130013
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2996995328
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	155
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.354359448
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	350024960
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1463522560
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2016032000
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	36
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3752383744
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4122440960
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	576066816
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	41
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3448026368
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	37
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	63
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	86
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	93
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	164
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1702745344
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	155
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	156
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	149
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2048652544
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	156
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2314900736
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	946418944
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	74
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	122
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	133
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1564738816
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1802
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.788018286
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	996924
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	163.5672
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	45246

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	41428	41428	✔
AngleVolantMsgTimer_mS_M_u32	2292638464	2292638464	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	13564	13564	✔
BSINodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	32060	32060	✔
CONSANGLECPK_HwDeg_M_f32	583.432495	583.432495 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	32060	32060	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2263999744	2263999744	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	38331	38331	✔
CityParkInputConsistentCount_Cnt_M_u16	36277	36277	✔
CityParkInputInvalidCount_Cnt_M_u16	20061	20061	✔
CityParkInputMsgTimer_mS_M_u32	2292638464	2292638464	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2292638464	2292638464	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2292638464	2292638464	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2292638464	2292638464	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2292638464	2292638464	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2292638464	2292638464	✔
ESPNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2500	2500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3500	3500	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	556	556	✔
ElecIntTimer_mS_M_u32[1]	877877	877877	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2292638464	2292638464	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2292638464	2292638464	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2292638464	2292638464	✔
IgnOnTimer_mS_M_u32	470480128	470480128	✔
IgnTimeOff_Sec_M_u32	1929740595	1929740595	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	110	110	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	350024960	350024960	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	136	136	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1463522560	1463522560	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	77	77	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2016032000	2016032000	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	36	36	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3752383744	3752383744	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2264610048	2264610048	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	170	170	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	576066816	576066816	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	41	41	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3448026368	3448026368	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	208	208	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1702745344	1702745344	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	149	149	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2048652544	2048652544	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	156	156	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2314900736	2314900736	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	14	14	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	946418944	946418944	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1564738816	1564738816	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	380.640411	380.640411	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	3.86529994	3.86529994	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	626.964478	626.964478	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	32060	32060	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1929740595	1929740595	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	583.432495	583.432495 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.375 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	642126848
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	12752
AASNodeAbsentTimer_mS_M_u32	3529540608
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	3105
ANGLEVOLANTSigValidCount_Cnt_M_u16	8209
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	6645
AngleVolantMsgTimer_mS_M_u32	642126848
AngleVolantValidCount_Cnt_M_u16	18511
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	900613120
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2879439872
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2232792064
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	181040128
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	56448
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2317497344
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	61788
CAVNodeAbsentTimer_mS_M_u32	3781436416
CDD_SrlComVehSpd_Kph_G_f32	185.863907
CMM388NTCEnableTimer_mS_M_u32	2097308672
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2729059328
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	7612
CMMNodeAbsentTimer_mS_M_u32	1409577984
CONSANGLECPKSigInvalidCount_Cnt_M_u16	49050
CONSANGLECPKSigValidCount_Cnt_M_u16	44890
CONSANGLECPK_Cnt_M_u16	21373
CONSANGLECPK_HwDeg_M_f32	54.7689018
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21373
CPKVehicleSpeedMsgTimer_mS_M_u32	3231519744
CPKVehicleSpeedValidCount_Cnt_M_u16	14023
CityParkInputConsistentCount_Cnt_M_u16	8403
CityParkInputInvalidCount_Cnt_M_u16	53210

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	350024960
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3420750848
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	36948
ComputerRazGCTSigInvalidTimer_mS_M_u32	1322820608
ComputerRazGCTSigValidCount_Cnt_M_u16	8304
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	13142
DMDFCTCPKSigValidCount_Cnt_M_u16	36334
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	42851
DMDRELAXECPKSigValidCount_Cnt_M_u16	2259
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	35007
DateInvalidTimer_mS_M_u32	2879439872
DiagMuxOnAbsentTimer_mS_M_u32	796775424
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	181040128
ESPNTCEnableTimer_mS_M_u32	2244576256
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	54920
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	102
EffacDefaultDiagTimer_mS_M_u32[1]	106
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2323
ElecIntTimer_mS_M_u32[1]	45464
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2261005312
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	61431
EtatMTSigValidCount_Cnt_M_u16	6835
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	41180
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	24092
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	6452
ISDAT4V2BSI552MsgTimer_mS_M_u32	680031232
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	39732
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	31863
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	6835
ISDATBSI3F2MsgTimer_mS_M_u32	641455104
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	19180
ISDATBSI412MsgLenValidCount_Cnt_M_u16	45536
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	61431
ISDATBSI412MsgTimer_mS_M_u32	319034368
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	3392
ISDATBSI432MsgLenValidCount_Cnt_M_u16	8460
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	14565
ISDATDIRASentFltAcc_Cnt_M_u16	11769
ISDATDIRASentTimer_mS_M_u32	3231519744
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	31931
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	18511
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	31029
ISDYN2CMMMsgTimer_mS_M_u32	2944631808
ISDYNAASChkSumInvalidCount_Cnt_M_u16	47378
ISDYNAASChkSumValidCount_Cnt_M_u16	42786
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	33838
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	58303
ISDYNAASMsgLenValidCount_Cnt_M_u16	59399
ISDYNAASMsgTimeValidCount_Cnt_M_u16	47378
ISDYNAASMsgTimer_mS_M_u32	3984483328
ISDYNABRChkSumInvalidCount_Cnt_M_u16	27429
ISDYNABRChkSumValidCount_Cnt_M_u16	64413
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	27505
ISDYNABRMsgCountValidCount_Cnt_M_u16	45761
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	27897
ISDYNABRMsgLenValidCount_Cnt_M_u16	62969
ISDYNABRMsgTimeValidCount_Cnt_M_u16	21373
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	48074
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	11974

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	6835
ISDYNCMM208MsgTimer_mS_M_u32	4085990400
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	48074
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	11974
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	54285
ISDYNCMM388MsgTimer_mS_M_u32	302900224
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	11864
ISDYNVOLChkSumValidCount_Cnt_M_u16	20632
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	56596
ISDYNVOLMsgCountValidCount_Cnt_M_u16	43564
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	2857
ISDYNVOLMsgLenValidCount_Cnt_M_u16	32969
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	7612
ISDYNVOLMsgTimer_mS_M_u32	1263838208
IgnOnTimer_mS_M_u32	2039604224
IgnTimeOff_Sec_M_u32	530639065
ManVehSpd_Kph_M_f32	375.972198
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	179
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	105
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	912380928
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	21
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3713315840
PrevISDATBSI412MsgDLCError_Cnt_M_u08	248
PrevISDATBSI412MsgRxTime_MSec_M_u32	3987547136
PrevISDATBSI432MsgDLCError_Cnt_M_u08	241
PrevISDATBSI432MsgRxTime_MSec_M_u32	3829236736
PrevISDATDIRAMsgTxTime_MSec_M_u32	1237394432
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	52
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1566307328
PrevISDYNAASMsgDLCError_Cnt_M_u08	254
PrevISDYNAASMsgRxTime_MSec_M_u32	4237468672
PrevISDYNABRMsgDLCError_Cnt_M_u08	17
PrevISDYNABRMsgRxTime_MSec_M_u32	2777277440
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	161
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2213520384
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	86
PrevISDYNCMM388MsgRxTime_MSec_M_u32	224429056
PrevISDYNVOLMsgDLCError_Cnt_M_u08	187
PrevISDYNVOLMsgRxTime_MSec_M_u32	2795643904
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1254233088
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	44.3576012
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	33661
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	31301
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	10654
VitesseVehicleBVRampValidCount_Cnt_M_u16	10022
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	20418
VitesseVehicleBVSigValidCount_Cnt_M_u16	35442
VitesseVehicleBV_Kph_M_f32	259.39621

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	54285
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	28213
VitesseVehiculeRoues_Kph_M_f32	183.496597
k_AASNTCEnableTimeout_mS_u16	48660
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	46762
k_AASNodeTimeout_mS_u16	13637
k_ABSNodeTimeout_mS_u16	19187
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	3803
k_ANGLEVOLANTSigValidThresh_Cnt_u16	45287
k_AngleVolantInvalidThresh_Cnt_u16	15950
k_AngleVolantValidThresh_Cnt_u16	53210
k_BSI552MsgTimeout_mS_u16	37468
k_BSINTCEnableTimeout_mS_u16	10552
k_BSINodeAbsentDiag_Cnt_str.Threshold	56126
k_BSINodeAbsentDiag_Cnt_str.PStep	36910
k_BSINodeAbsentDiag_Cnt_str.NStep	57138
k_BSINodeAbsentTimeout_mS_u16	63469
k_BSINodeTimeout_mS_u16	14565
k_BattOvHi_Volt_f32	22.2600994
k_BattOvLo_Volt_f32	7.19449997
k_BattUvHi_Volt_f32	27.3561993
k_BattUvLo_Volt_f32	17.1860008
k_CAVNTCEnableTimeout_mS_u16	39824
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	33818
k_CAVNodeTimeout_mS_u16	59414
k_CMM388MsgTimeout_mS_u16	11472
k_CMM388NTCEnableTimeout_mS_u16	3660
k_CMMNTCEnableTimeout_mS_u16	29484
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	5553
k_CONSANGLECPKMax_HwDeg_f32	320.994385
k_CONSANGLECPKMin_HwDeg_f32	-313.1409
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	20237
k_CONSANGLECPKSigValidThresh_Cnt_u16	10549
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	45963
k_CPKVehicleSpeedValidThresh_Cnt_u16	51471
k_CityParkInputInvalidThresh_Cnt_u16	39403
k_CityParkInputValidThresh_Cnt_u16	8403
k_ComputerRazGCTSigValidThresh_Cnt_u16	6618
k_CptTemporelSigValidThresh_Cnt_u16	52125
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	26617
k_DMDFCTCPKSigValidThresh_Cnt_u16	12537
k_DMDFCTCPKValidCount_Cnt_u16	35208
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	31029
k_DMDRELAXECPKSigValidThresh_Cnt_u16	52493
k_DMDRelaxeConsistentThresh_Cnt_u16	9555
k_DateValidThresh_Cnt_u16	6452
k_DefaultVehSpd_Kph_f32	255
k_DiagMuxOnAbsentTimeout_mS_u16	31923
k_EMNodeTimeout_mS_u16	36127
k_ESPNTCEnableTimeout_mS_u16	60376
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	49593
k_EtatMTSigInvalidThresh_Cnt_u16	61804
k_EtatMTSigValidThresh_Cnt_u16	31012
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	47758
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	8490
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	18676
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	36729
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	35452
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	28784
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	30469
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	50321

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	15556
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	32097
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	39285
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	1384
k_ISDATDIRASentDiag_Cnt_str.Threshold	52471
k_ISDATDIRASentDiag_Cnt_str.PStep	60363
k_ISDATDIRASentDiag_Cnt_str.NStep	42803
k_ISDATDIRASentTimeout_mS_u16	417
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	64581
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	6645
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	45668
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	58917
k_ISDYNAASChkSumValidThresh_Cnt_u16	46749
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	26225
k_ISDYNAASMsgCountValidThresh_Cnt_u16	60865
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	36777
k_ISDYNAASMsgLenValidThresh_Cnt_u16	42441
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	60143
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	65207
k_ISDYNABRChkSumValidThresh_Cnt_u16	64055
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	55168
k_ISDYNABRMsgCountValidThresh_Cnt_u16	1200
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	55484
k_ISDYNABRMsgLenValidThresh_Cnt_u16	53640
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	51799
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	37889
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	46669
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	55404
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	1825
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	23313
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	20946
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	39175
k_ISDYNVOLChkSumValidThresh_Cnt_u16	60987
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	42413
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	15137
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	63347
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	1839
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	53610
k_IgnOnTimeout_mS_u16	17283
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	215.753204
k_PowerCutVehSpdLowThresh_Kph_f32	169.011002
k_PowerCutVehSpdLowTimeout_mS_u16	47104
k_VBattMaxAAS_Volt_f32	1.34179997
k_VBattMaxBSI_Volt_f32	25.6544991
k_VBattMaxCAV_Volt_f32	18.2607994
k_VBattMaxCMM388_Volt_f32	10.8102999
k_VBattMaxCMM_Volt_f32	28.6735992
k_VBattMaxESP_Volt_f32	0.112899996
k_VBattMinAAS_Volt_f32	8.61289978
k_VBattMinBSI_Volt_f32	0.112899996
k_VBattMinCAV_Volt_f32	31.8181
k_VBattMinCMM388_Volt_f32	7.54120016
k_VBattMinCMM_Volt_f32	17.7607994
k_VBattMinESP_Volt_f32	28.6735992
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	16639
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	52195
k_VitesseVehicleBVRampValidThresh_Cnt_u16	22548
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	35736
k_VitesseVehicleBVSigValidThresh_Cnt_u16	45804
k_VitesseVehicleBVSpeedPassThresh_kph_f32	380.119598
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	27740
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	40036
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2879439872
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	2679
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3572898304
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	86

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	19.4545994
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1208693760
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	54
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.748633027
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1461445632
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3531604992
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4063503360
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2117616640
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1049388032
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	120
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4214260736
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2082776064
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	102
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	138
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	153
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	223
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2159625216
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	47
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	85
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	109
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	180
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	189
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	189
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	207
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3814646784
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4131587072
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	96
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1836524544
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	107
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	122
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	202
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2921772032
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	10
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.191316605
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	727711
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	203.996597
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	48567

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3572898304	3572898304	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	6647	6647	✔
AngleVolantMsgTimer_mS_M_u32	3572898304	3572898304	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	900613120	900613120	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2232792064	2232792064	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	181040128	181040128	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	56126	56126	✔
BSINodeAbsentTimer_mS_M_u32	3572898304	3572898304	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3572898304	3572898304	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2729059328	2729059328	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	7612	7612	✔
CMMNodeAbsentTimer_mS_M_u32	4214260736	4214260736	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	21373	21373	✔
CONSANGLECPK_HwDeg_M_f32	54.7689018	54.7689018 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21373	21373	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3231519744	3231519744	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	14023	14023	✔
CityParkInputConsistentCount_Cnt_M_u16	8403	8403	✔
CityParkInputInvalidCount_Cnt_M_u16	53210	53210	✔
CityParkInputMsgTimer_mS_M_u32	3572898304	3572898304	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3572898304	3572898304	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3572898304	3572898304	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3572898304	3572898304	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3572898304	3572898304	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3572898304	3572898304	✔
ESPNTCEnableTimer_mS_M_u32	3572898304	3572898304	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3572898304	3572898304	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	102	102	✔
EffacDefaultDiagTimer_mS_M_u32[1]	106	106	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	2323	2323	✔
ElecIntTimer_mS_M_u32[1]	45464	45464	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3572898304	3572898304	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	39732	39732	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3531604992	3531604992	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3572898304	3572898304	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3572898304	3572898304	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3572898304	3572898304	✔
IgnOnTimer_mS_M_u32	2039604224	2039604224	✔
IgnTimeOff_Sec_M_u32	530639065	530639065	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1461445632	1461445632	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	212	212	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3531604992	3531604992	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	233	233	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4063503360	4063503360	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2117616640	2117616640	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1237394432	1237394432	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	120	120	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4214260736	4214260736	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	94	94	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2082776064	2082776064	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	151	151	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2159625216	2159625216	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3814646784	3814646784	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	84	84	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4131587072	4131587072	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	96	96	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1836524544	1836524544	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2921772032	2921772032	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	44.3576012	44.3576012	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	259.39621	259.39621	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	183.496597	183.496597	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	21373	21373	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	530639065	530639065	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	54.7689018	54.7689018 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	255	255	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	9	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.376 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2988214016
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	55677
AASNodeAbsentTimer_mS_M_u32	1670199040
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	11403
ANGLEVOLANTSigValidCount_Cnt_M_u16	56443
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	62734
AngleVolantMsgTimer_mS_M_u32	2988214016
AngleVolantValidCount_Cnt_M_u16	64127
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2695100160
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	684488448
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3693979392
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	235890432
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	63342
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2668111616
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	53594
CAVNodeAbsentTimer_mS_M_u32	1291998976
CDD_SrlComVehSpd_Kph_G_f32	414.567413
CMM388NTCEnableTimer_mS_M_u32	3274151680
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2704299776
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	18681
CMMNodeAbsentTimer_mS_M_u32	2590074624
CONSANGLECPKSigInvalidCount_Cnt_M_u16	10526
CONSANGLECPKSigValidCount_Cnt_M_u16	34206
CONSANGLECPK_Cnt_M_u16	58677
CONSANGLECPK_HwDeg_M_f32	-490.4664
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	58677
CPKVehicleSpeedMsgTimer_mS_M_u32	4279731968

Name	Input Value
CPKVehicleSpeedValidCount_Cnt_M_u16	54529
CityParkInputConsistentCount_Cnt_M_u16	33011
CityParkInputInvalidCount_Cnt_M_u16	41181
CityParkInputMsgTimer_mS_M_u32	1461445632
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2265003776
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	52721
ComputerRazGCTSigInvalidTimer_mS_M_u32	1990514432
ComputerRazGCTSigValidCount_Cnt_M_u16	13852
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	26217
DMDFCTCPKSigValidCount_Cnt_M_u16	57954
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	58053
DMDRELAXECPKSigValidCount_Cnt_M_u16	43573
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	41391
DateInvalidTimer_mS_M_u32	684488448
DiagMuxOnAbsentTimer_mS_M_u32	628442880
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	235890432
ESPNTCEnableTimer_mS_M_u32	760362752
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	31317
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	89
EffacDefaultDiagTimer_mS_M_u32[1]	789
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	5656
ElecIntTimer_mS_M_u32[1]	78788
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2971805440
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	53063
EtatMTSigValidCount_Cnt_M_u16	27348
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	3416
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	344
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	55440
ISDAT4V2BSI552MsgTimer_mS_M_u32	752183040
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	46866
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	20230
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	27348
ISDATBSI3F2MsgTimer_mS_M_u32	3107669760
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	55529
ISDATBSI412MsgLenValidCount_Cnt_M_u16	40910
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	53063
ISDATBSI412MsgTimer_mS_M_u32	1675790080
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	35437
ISDATBSI432MsgLenValidCount_Cnt_M_u16	43721
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	24255
ISDATDIRASentFltAcc_Cnt_M_u16	53123
ISDATDIRASentTimer_mS_M_u32	4279731968
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	57723
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	64127
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	53452
ISDYN2CMMMsgTimer_mS_M_u32	405026560
ISDYNAASChkSumInvalidCount_Cnt_M_u16	52151
ISDYNAASChkSumValidCount_Cnt_M_u16	27975
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	33506
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	17969
ISDYNAASMsgLenValidCount_Cnt_M_u16	34073
ISDYNAASMsgTimeValidCount_Cnt_M_u16	52151
ISDYNAASMsgTimer_mS_M_u32	1639159552
ISDYNABRChkSumInvalidCount_Cnt_M_u16	6398
ISDYNABRChkSumValidCount_Cnt_M_u16	29526
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	61594
ISDYNABRMsgCountValidCount_Cnt_M_u16	34410
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	23809
ISDYNABRMsgLenValidCount_Cnt_M_u16	60865

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNABRMsgTimeValidCount_Cnt_M_u16	58677
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	30670
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	15003
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	27348
ISDYNCMM208MsgTimer_mS_M_u32	453834496
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	30670
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	15003
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	53061
ISDYNCMM388MsgTimer_mS_M_u32	2449807104
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	21732
ISDYNVOLChkSumValidCount_Cnt_M_u16	6628
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	57647
ISDYNVOLMsgCountValidCount_Cnt_M_u16	1448
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	41074
ISDYNVOLMsgLenValidCount_Cnt_M_u16	60242
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	18681
ISDYNVOLMsgTimer_mS_M_u32	1899026176
IgnOnTimer_mS_M_u32	1803097856
IgnTimeOff_Sec_M_u32	2556631155
ManVehSpd_Kph_M_f32	433.282196
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	180
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	114
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2697545472
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	99
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2406524672
PrevISDATBSI412MsgDLCError_Cnt_M_u08	37
PrevISDATBSI412MsgRxTime_MSec_M_u32	2351388416
PrevISDATBSI432MsgDLCError_Cnt_M_u08	226
PrevISDATBSI432MsgRxTime_MSec_M_u32	3791009536
PrevISDATDIRAMsgTxTime_MSec_M_u32	3354089216
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	242
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1012590336
PrevISDYNAASMsgDLCError_Cnt_M_u08	109
PrevISDYNAASMsgRxTime_MSec_M_u32	3581335296
PrevISDYNABRMsgDLCError_Cnt_M_u08	12
PrevISDYNABRMsgRxTime_MSec_M_u32	3348174592
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	251
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4083144448
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	47
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2995599104
PrevISDYNVOLMsgDLCError_Cnt_M_u08	149
PrevISDYNVOLMsgRxTime_MSec_M_u32	1967675136
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	883459840
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	413.490814
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57079
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	18015
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	45204
VitesseVehicleBVRampValidCount_Cnt_M_u16	956

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	9640
VitesseVehicleBVSigValidCount_Cnt_M_u16	24920
VitesseVehicleBV_Kph_M_f32	545.215027
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	53061
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	52365
VitesseVehiculeRoues_Kph_M_f32	643.44043
k_AASNTCEnableTimeout_mS_u16	49520
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	56174
k_AASNodeTimeout_mS_u16	5471
k_ABSNodeTimeout_mS_u16	54162
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	45468
k_ANGLEVOLANTSigValidThresh_Cnt_u16	10040
k_AngleVolantInvalidThresh_Cnt_u16	56067
k_AngleVolantValidThresh_Cnt_u16	41181
k_BSI552MsgTimeout_mS_u16	48152
k_BSINTCEnableTimeout_mS_u16	5765
k_BSINodeAbsentDiag_Cnt_str.Threshold	16627
k_BSINodeAbsentDiag_Cnt_str.PStep	46691
k_BSINodeAbsentDiag_Cnt_str.NStep	44438
k_BSINodeAbsentTimeout_mS_u16	15142
k_BSINodeTimeout_mS_u16	24255
k_BattOvHi_Volt_f32	24.3950996
k_BattOvLo_Volt_f32	30.5858002
k_BattUvHi_Volt_f32	16.2798996
k_BattUvLo_Volt_f32	5.62580013
k_CAVNTCEnableTimeout_mS_u16	38331
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	37152
k_CAVNodeTimeout_mS_u16	40874
k_CMM388MsgTimeout_mS_u16	59517
k_CMM388NTCEnableTimeout_mS_u16	13321
k_CMMNTCEnableTimeout_mS_u16	3882
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	50713
k_CONSANGLECPKMax_HwDeg_f32	437.120087
k_CONSANGLECPKMin_HwDeg_f32	-451.752411
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	24133
k_CONSANGLECPKSigValidThresh_Cnt_u16	39821
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	12941
k_CPKVehicleSpeedValidThresh_Cnt_u16	43648
k_CityParkInputInvalidThresh_Cnt_u16	9388
k_CityParkInputValidThresh_Cnt_u16	33011
k_ComputerRazGCTSigValidThresh_Cnt_u16	21280
k_CptTemporelSigValidThresh_Cnt_u16	31124
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	27649
k_DMDFCTCPKSigValidThresh_Cnt_u16	15553
k_DMDFCTCPKValidCount_Cnt_u16	4182
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	53452
k_DMDRELAXECPKSigValidThresh_Cnt_u16	24837
k_DMDRelaxeConsistentThresh_Cnt_u16	61491
k_DateValidThresh_Cnt_u16	55440
k_DefaultVehSpd_Kph_f32	208.360001
k_DiagMuxOnAbsentTimeout_mS_u16	49555
k_EMNodeTimeout_mS_u16	5263
k_ESPNTCEnableTimeout_mS_u16	53734
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	57857
k_EtatMTSigInvalidThresh_Cnt_u16	25129
k_EtatMTSigValidThresh_Cnt_u16	54977
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	59780
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	20848
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	52368
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	11843
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	30967

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	30813
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	41246
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	5178
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	3041
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	63369
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	7949
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	60021
k_ISDATDIRASentDiag_Cnt_str.Threshold	3472
k_ISDATDIRASentDiag_Cnt_str.PStep	32212
k_ISDATDIRASentDiag_Cnt_str.NStep	26715
k_ISDATDIRASentTimeout_mS_u16	17802
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	47582
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	62734
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	44610
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	43006
k_ISDYNAASChkSumValidThresh_Cnt_u16	16982
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	65434
k_ISDYNAASMsgCountValidThresh_Cnt_u16	54634
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	47986
k_ISDYNAASMsgLenValidThresh_Cnt_u16	54227
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39200
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	8135
k_ISDYNABRChkSumValidThresh_Cnt_u16	22791
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	1646
k_ISDYNABRMsgCountValidThresh_Cnt_u16	27294
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	6137
k_ISDYNABRMsgLenValidThresh_Cnt_u16	35157
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	30121
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	48491
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	23238
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	34794
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	15243
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	11131
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	64245
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	6808
k_ISDYNVOLChkSumValidThresh_Cnt_u16	5821
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	57574
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	50378
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	43219
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	38240
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	2030
k_IgnOnTimeout_mS_u16	2852
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	248.673004
k_PowerCutVehSpdLowThresh_Kph_f32	12.8994999
k_PowerCutVehSpdLowTimeout_mS_u16	33708
k_VBattMaxAAS_Volt_f32	11.3703003
k_VBattMaxBSI_Volt_f32	19.7073994
k_VBattMaxCAV_Volt_f32	9.69419956
k_VBattMaxCMM388_Volt_f32	26.6963005
k_VBattMaxCMM_Volt_f32	1.17569995
k_VBattMaxESP_Volt_f32	28.6889
k_VBattMinAAS_Volt_f32	15.8217001
k_VBattMinBSI_Volt_f32	28.6889
k_VBattMinCAV_Volt_f32	30.3495007
k_VBattMinCMM388_Volt_f32	27.7054996
k_VBattMinCMM_Volt_f32	18.9286003
k_VBattMinESP_Volt_f32	1.17569995
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	21424
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	28356
k_VitesseVehicleBVRampValidThresh_Cnt_u16	28719
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	26852
k_VitesseVehicleBVSigValidThresh_Cnt_u16	28328
k_VitesseVehicleBVSpeedPassThresh_kph_f32	175.994293
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	24666
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	7170
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	684488448
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	5241
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1436841216

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	47
target_SrlComInput_Per1_Batt_Volt_f32.value	11.6904001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1229793024
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	129
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.535336852
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2061178624
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1093580544
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1519539968
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1862661888
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	646551296
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	689780480
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	147
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	515954432
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	75
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	123
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	194
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	214
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2877486848
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	7
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	30
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	56
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	239
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	76
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2719094528
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2716186368
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3033093888
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	197
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	204
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3841632000
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2435
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.34761402
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	342545

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0		
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	185.192703		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	38985		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1436841216	1436841216	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1436841216	1436841216	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	16627	16627	✔
BSINodeAbsentTimer_mS_M_u32	1436841216	1436841216	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1436841216	1436841216	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1436841216	1436841216	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	58677	58677	✔
CONSANGLECPK_HwDeg_M_f32	-490.4664	-490.4664 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1436841216	1436841216	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1436841216	1436841216	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1436841216	1436841216	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1436841216	1436841216	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1436841216	1436841216	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1436841216	1436841216	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1436841216	1436841216	✔
ESPNTCEnableTimer_mS_M_u32	1436841216	1436841216	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1436841216	1436841216	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	89	89	✔
EffacDefaultDiagTimer_mS_M_u32[1]	789	789	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	1436841216	1436841216	✔
ElecIntTimer_mS_M_u32[1]	78788	78788	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1436841216	1436841216	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1436841216	1436841216	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1436841216	1436841216	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1436841216	1436841216	✔
IgnOnTimer_mS_M_u32	1803097856	1803097856	✔
IgnTimeOff_Sec_M_u32	2556631155	2556631155	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	90	90	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2061178624	2061178624	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	118	118	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1093580544	1093580544	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	16	16	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1519539968	1519539968	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	210	210	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1862661888	1862661888	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3354089216	3354089216	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	107	107	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	689780480	689780480	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	147	147	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	515954432	515954432	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	99	99	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2877486848	2877486848	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	76	76	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2719094528	2719094528	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	194	194	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2716186368	2716186368	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	118	118	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3033093888	3033093888	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3841632000	3841632000	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	413.490814	413.490814	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	545.215027	545.215027	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	643.44043	643.44043	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	58677	58677	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2556631155	2556631155	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-490.4664	-490.4664 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.377 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2888117760
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	22531
AASNodeAbsentTimer_mS_M_u32	1989352960
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	47320
ANGLEVOLANTSigValidCount_Cnt_M_u16	58823
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	35152
AngleVolantMsgTimer_mS_M_u32	2888117760
AngleVolantValidCount_Cnt_M_u16	51067
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2320424448
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	869621248
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1517407744
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2077003264
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	42031
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2615299584
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	52460
CAVNodeAbsentTimer_mS_M_u32	1991491072
CDD_SrlComVehSpd_Kph_G_f32	560.539429
CMM388NTCEnableTimer_mS_M_u32	960757248
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2989080064
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	28621
CMMNodeAbsentTimer_mS_M_u32	2664861184
CONSANGLECPKSigInvalidCount_Cnt_M_u16	32287
CONSANGLECPKSigValidCount_Cnt_M_u16	58719
CONSANGLECPK_Cnt_M_u16	58010
CONSANGLECPK_HwDeg_M_f32	-363.644592
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	58010
CPKVehicleSpeedMsgTimer_mS_M_u32	1899245056
CPKVehicleSpeedValidCount_Cnt_M_u16	58941
CityParkInputConsistentCount_Cnt_M_u16	1055
CityParkInputInvalidCount_Cnt_M_u16	7521

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	2061178624
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3694599680
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	19111
ComputerRazGCTSigInvalidTimer_mS_M_u32	2748071424
ComputerRazGCTSigValidCount_Cnt_M_u16	51364
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	64701
DMDFCTCPKSigValidCount_Cnt_M_u16	58772
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	65066
DMDRELAXECPKSigValidCount_Cnt_M_u16	58521
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	39020
DateInvalidTimer_mS_M_u32	869621248
DiagMuxOnAbsentTimer_mS_M_u32	2770005504
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2077003264
ESPNTCEnableTimer_mS_M_u32	1833180672
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	51321
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	56
EffacDefaultDiagTimer_mS_M_u32[1]	456
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	5
ElecIntTimer_mS_M_u32[1]	87787
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1301564928
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	58851
EtatMTSigValidCount_Cnt_M_u16	49150
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	14705
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	55857
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	15114
ISDAT4V2BSI552MsgTimer_mS_M_u32	3078262272
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	29186
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	63206
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	49150
ISDATBSI3F2MsgTimer_mS_M_u32	2177428992
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	31100
ISDATBSI412MsgLenValidCount_Cnt_M_u16	12688
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	58851
ISDATBSI412MsgTimer_mS_M_u32	785591808
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	31601
ISDATBSI432MsgLenValidCount_Cnt_M_u16	1821
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	63677
ISDATDIRASentFltAcc_Cnt_M_u16	46705
ISDATDIRASentTimer_mS_M_u32	1899245056
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	34248
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	51067
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	2452
ISDYN2CMMMsgTimer_mS_M_u32	1959665152
ISDYNAASChkSumInvalidCount_Cnt_M_u16	59733
ISDYNAASChkSumValidCount_Cnt_M_u16	49509
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	31314
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	35431
ISDYNAASMsgLenValidCount_Cnt_M_u16	60014
ISDYNAASMsgTimeValidCount_Cnt_M_u16	59733
ISDYNAASMsgTimer_mS_M_u32	2376072704
ISDYNABRChkSumInvalidCount_Cnt_M_u16	55039
ISDYNABRChkSumValidCount_Cnt_M_u16	42166
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	50860
ISDYNABRMsgCountValidCount_Cnt_M_u16	49660
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	11894
ISDYNABRMsgLenValidCount_Cnt_M_u16	63734
ISDYNABRMsgTimeValidCount_Cnt_M_u16	58010
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	51278
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	11433

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	49150
ISDYNCMM208MsgTimer_mS_M_u32	4279492096
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	51278
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	11433
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	57641
ISDYNCMM388MsgTimer_mS_M_u32	581664256
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	37581
ISDYNVOLChkSumValidCount_Cnt_M_u16	49293
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	9323
ISDYNVOLMsgCountValidCount_Cnt_M_u16	5058
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	2594
ISDYNVOLMsgLenValidCount_Cnt_M_u16	9793
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28621
ISDYNVOLMsgTimer_mS_M_u32	3827842560
IgnOnTimer_mS_M_u32	1716485632
IgnTimeOff_Sec_M_u32	2793521384
ManVehSpd_Kph_M_f32	49.9564018
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	181
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	202
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2199842304
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	26
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	212389376
PrevISDATBSI412MsgDLCError_Cnt_M_u08	152
PrevISDATBSI412MsgRxTime_MSec_M_u32	2370092544
PrevISDATBSI432MsgDLCError_Cnt_M_u08	100
PrevISDATBSI432MsgRxTime_MSec_M_u32	3747094016
PrevISDATDIRAMsgTxTime_MSec_M_u32	3925392896
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	165
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2129268224
PrevISDYNAASMsgDLCError_Cnt_M_u08	171
PrevISDYNAASMsgRxTime_MSec_M_u32	1331052032
PrevISDYNABRMsgDLCError_Cnt_M_u08	75
PrevISDYNABRMsgRxTime_MSec_M_u32	2986835456
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	159
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3650829824
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	8
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2308120064
PrevISDYNVOLMsgDLCError_Cnt_M_u08	22
PrevISDYNVOLMsgRxTime_MSec_M_u32	2514599424
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1417752064
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	527.87561
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	22549
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	16028
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	38718
VitesseVehicleBVRampValidCount_Cnt_M_u16	47749
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	33153
VitesseVehicleBVSigValidCount_Cnt_M_u16	2864
VitesseVehicleBV_Kph_M_f32	427.543304

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	57641
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	34321
VitesseVehiculeRoues_Kph_M_f32	521.286987
k_AASNTCEnableTimeout_mS_u16	63977
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	41134
k_AASNodeTimeout_mS_u16	53660
k_ABSNodeTimeout_mS_u16	39234
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	33252
k_ANGLEVOLANTSigValidThresh_Cnt_u16	3536
k_AngleVolantInvalidThresh_Cnt_u16	56943
k_AngleVolantValidThresh_Cnt_u16	7521
k_BSI552MsgTimeout_mS_u16	41840
k_BSINTCEnableTimeout_mS_u16	14121
k_BSINodeAbsentDiag_Cnt_str.Threshold	63073
k_BSINodeAbsentDiag_Cnt_str.PStep	55633
k_BSINodeAbsentDiag_Cnt_str.NStep	18166
k_BSINodeAbsentTimeout_mS_u16	5896
k_BSINodeTimeout_mS_u16	63677
k_BattOvHi_Volt_f32	17.0438995
k_BattOvLo_Volt_f32	17.9909992
k_BattUvHi_Volt_f32	19.8712006
k_BattUvLo_Volt_f32	12.8269997
k_CAVNTCEnableTimeout_mS_u16	14023
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	9626
k_CAVNodeTimeout_mS_u16	19067
k_CMM388MsgTimeout_mS_u16	11011
k_CMM388NTCEnableTimeout_mS_u16	30815
k_CMMNTCEnableTimeout_mS_u16	51642
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	51565
k_CONSANGLECPKMax_HwDeg_f32	105.665199
k_CONSANGLECPKMin_HwDeg_f32	-552.882202
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	13353
k_CONSANGLECPKSigValidThresh_Cnt_u16	6417
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	45586
k_CPKVehicleSpeedValidThresh_Cnt_u16	8375
k_CityParkInputInvalidThresh_Cnt_u16	60405
k_CityParkInputValidThresh_Cnt_u16	1055
k_ComputerRazGCTSigValidThresh_Cnt_u16	21976
k_CptTemporelSigValidThresh_Cnt_u16	12092
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	374
k_DMDFCTCPKSigValidThresh_Cnt_u16	3062
k_DMDFCTCPKValidCount_Cnt_u16	63863
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	2452
k_DMDRELAXECPKSigValidThresh_Cnt_u16	46507
k_DMDRelaxeConsistentThresh_Cnt_u16	16417
k_DateValidThresh_Cnt_u16	15114
k_DefaultVehSpd_Kph_f32	87.8995972
k_DiagMuxOnAbsentTimeout_mS_u16	17792
k_EMNodeTimeout_mS_u16	49100
k_ESPNTCEnableTimeout_mS_u16	64328
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	5557
k_EtatMTSigInvalidThresh_Cnt_u16	26494
k_EtatMTSigValidThresh_Cnt_u16	58997
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	10541
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	7721
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	54600
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	4207
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	32019
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	27424
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	15198
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	52938

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	50965
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	64414
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	4561
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	33243
k_ISDATDIRASentDiag_Cnt_str.Threshold	2435
k_ISDATDIRASentDiag_Cnt_str.PStep	9638
k_ISDATDIRASentDiag_Cnt_str.NStep	54621
k_ISDATDIRASentTimeout_mS_u16	33115
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	63392
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	35152
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	54836
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	10751
k_ISDYNAASChkSumValidThresh_Cnt_u16	14262
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	39340
k_ISDYNAASMsgCountValidThresh_Cnt_u16	54524
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	49059
k_ISDYNAASMsgLenValidThresh_Cnt_u16	26176
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	22552
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	32292
k_ISDYNABRChkSumValidThresh_Cnt_u16	20260
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	30511
k_ISDYNABRMsgCountValidThresh_Cnt_u16	34654
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	717
k_ISDYNABRMsgLenValidThresh_Cnt_u16	39801
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	21053
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	36025
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	42981
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	26107
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	35800
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	63687
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	28441
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	12399
k_ISDYNVOLChkSumValidThresh_Cnt_u16	18627
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	6342
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	32858
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	35135
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	28762
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	42224
k_IgnOnTimeout_mS_u16	36555
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	199.460693
k_PowerCutVehSpdLowThresh_Kph_f32	242.781006
k_PowerCutVehSpdLowTimeout_mS_u16	41781
k_VBattMaxAAS_Volt_f32	25.0545006
k_VBattMaxBSI_Volt_f32	20.2168007
k_VBattMaxCAV_Volt_f32	14.8395996
k_VBattMaxCMM388_Volt_f32	12.8821001
k_VBattMaxCMM_Volt_f32	5.23579979
k_VBattMaxESP_Volt_f32	31.2031994
k_VBattMinAAS_Volt_f32	31.9064007
k_VBattMinBSI_Volt_f32	31.2031994
k_VBattMinCAV_Volt_f32	32
k_VBattMinCMM388_Volt_f32	3.24810004
k_VBattMinCMM_Volt_f32	29.9332008
k_VBattMinESP_Volt_f32	5.23579979
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	61994
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	28077
k_VitesseVehicleBVRampValidThresh_Cnt_u16	30571
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	54157
k_VitesseVehicleBVSigValidThresh_Cnt_u16	20224
k_VitesseVehicleBVSpeedPassThresh_kph_f32	243.676895
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	8172
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	2483
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	869621248
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16 Elaps	6206
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	314926080
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	8

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	16.9263
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4044574208
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	60
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.875575244
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1076461056
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1135517184
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2382609920
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	656989696
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	387841536
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1709383168
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	460865024
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	108
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	121
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	203
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	207
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	221
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	139
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2779897344
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	84
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	146
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	163
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	216
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	228
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	211
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1719959040
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3179912704
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	459193856
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	134
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	175
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3020606976
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3596
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.406395853
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	130102
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	174.151306
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	62495

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	314926080	314926080	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	314926080	314926080	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	314926080	314926080	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	314926080	314926080	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	314926080	314926080	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	314926080	314926080	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	314926080	314926080	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	314926080	314926080	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	314926080	314926080	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	314926080	314926080	✔
CDD_SrlComVehSpd_Kph_G_f32	49.9564018	49.9564018	✔
CMM388NTCEnableTimer_mS_M_u32	314926080	314926080	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	314926080	314926080	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	314926080	314926080	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	58010	58010	✔
CONSANGLECPK_HwDeg_M_f32	-363.644592	-363.644592 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	314926080	314926080	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	314926080	314926080	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	314926080	314926080	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	314926080	314926080	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	314926080	314926080	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	314926080	314926080	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	314926080	314926080	✔
ESPNTCEnableTimer_mS_M_u32	314926080	314926080	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	314926080	314926080	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	56	56	✔
EffacDefaultDiagTimer_mS_M_u32[1]	456	456	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	5	5	✔
ElecIntTimer_mS_M_u32[1]	87787	87787	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	314926080	314926080	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	15114	15114	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	314926080	314926080	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	49150	49150	✔
ISDATBSI3F2MsgTimer_mS_M_u32	314926080	314926080	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	58851	58851	✔
ISDATBSI412MsgTimer_mS_M_u32	314926080	314926080	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	63677	63677	✔
ISDATBSI432MsgTimer_mS_M_u32	314926080	314926080	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	314926080	314926080	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	2452	2452	✔
ISDYN2CMMMsgTimer_mS_M_u32	314926080	314926080	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	59733	59733	✔
ISDYNAASMsgTimer_mS_M_u32	314926080	314926080	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	58010	58010	✔
ISDYNABRMsgTimer_mS_M_u32	314926080	314926080	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	49150	49150	✔
ISDYNCMM208MsgTimer_mS_M_u32	314926080	314926080	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	57641	57641	✔
ISDYNCMM388MsgTimer_mS_M_u32	314926080	314926080	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	28621	28621	✔
ISDYNVOLMsgTimer_mS_M_u32	314926080	314926080	✔
IgnOnTimer_mS_M_u32	1716485632	1716485632	✔
IgnTimeOff_Sec_M_u32	2793521384	2793521384	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1076461056	1076461056	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	241	241	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1135517184	1135517184	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	151	151	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2382609920	2382609920	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	8	8	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	656989696	656989696	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3925392896	3925392896	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	106	106	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1709383168	1709383168	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	107	107	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	460865024	460865024	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	139	139	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2779897344	2779897344	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	211	211	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1719959040	1719959040	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	169	169	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3179912704	3179912704	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	3	3	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	459193856	459193856	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3020606976	3020606976	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	527.87561	527.87561	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	427.543304	427.543304	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	521.286987	521.286987	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	58010	58010	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2793521384	2793521384	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-363.644592	-363.644592 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.378 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4003312896
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	54458
AASNodeAbsentTimer_mS_M_u32	4126205184
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	51732
ANGLEVOLANTSigValidCount_Cnt_M_u16	29227
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	57155
AngleVolantMsgTimer_mS_M_u32	4003312896
AngleVolantValidCount_Cnt_M_u16	2263
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3052512512
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	848700672
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	504747264
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1661572352
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	18527
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	249320704
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	28062
CAVNodeAbsentTimer_mS_M_u32	128779520
CDD_SrlComVehSpd_Kph_G_f32	186.133102
CMM388NTCEnableTimer_mS_M_u32	1929921792
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3144353024
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	51530
CMMNodeAbsentTimer_mS_M_u32	1271633152
CONSANGLECPKSigInvalidCount_Cnt_M_u16	16305
CONSANGLECPKSigValidCount_Cnt_M_u16	10200
CONSANGLECPK_Cnt_M_u16	19255
CONSANGLECPK_HwDeg_M_f32	602.554688
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	19255
CPKVehicleSpeedMsgTimer_mS_M_u32	2990585088
CPKVehicleSpeedValidCount_Cnt_M_u16	19897
CityParkInputConsistentCount_Cnt_M_u16	12715
CityParkInputInvalidCount_Cnt_M_u16	47652
CityParkInputMsgTimer_mS_M_u32	1551346176
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1405412608
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	64398

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1694205184
ComputerRazGCTSigValidCount_Cnt_M_u16	7436
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	32080
DMDFCTCPKSigValidCount_Cnt_M_u16	11566
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	47486
DMDRELAXECPKSigValidCount_Cnt_M_u16	64789
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	16186
DateInvalidTimer_mS_M_u32	848700672
DiagMuxOnAbsentTimer_mS_M_u32	3117446400
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1661572352
ESPNTCEnableTimer_mS_M_u32	856548608
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	41324
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	65
EffacDefaultDiagTimer_mS_M_u32[1]	655
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2324
ElecIntTimer_mS_M_u32[1]	45465
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	187061504
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	8966
EtatMTSigValidCount_Cnt_M_u16	48089
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	60699
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	61634
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	29420
ISDAT4V2BSI552MsgTimer_mS_M_u32	547329280
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	47242
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	22149
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	48089
ISDATBSI3F2MsgTimer_mS_M_u32	3295048960
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	263
ISDATBSI412MsgLenValidCount_Cnt_M_u16	40562
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	8966
ISDATBSI412MsgTimer_mS_M_u32	657700096
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	21790
ISDATBSI432MsgLenValidCount_Cnt_M_u16	9280
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	347
ISDATDIRASentFltAcc_Cnt_M_u16	55807
ISDATDIRASentTimer_mS_M_u32	2990585088
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	14925
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	2263
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	57115
ISDYN2CMMMsgTimer_mS_M_u32	1179641088
ISDYNAASChkSumInvalidCount_Cnt_M_u16	8228
ISDYNAASChkSumValidCount_Cnt_M_u16	56538
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	39074
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	23613
ISDYNAASMsgLenValidCount_Cnt_M_u16	65420
ISDYNAASMsgTimeValidCount_Cnt_M_u16	8228
ISDYNAASMsgTimer_mS_M_u32	3342091520
ISDYNABRChkSumInvalidCount_Cnt_M_u16	2816
ISDYNABRChkSumValidCount_Cnt_M_u16	63039
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	10351
ISDYNABRMsgCountValidCount_Cnt_M_u16	5989
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	24316
ISDYNABRMsgLenValidCount_Cnt_M_u16	47459
ISDYNABRMsgTimeValidCount_Cnt_M_u16	19255
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	36821
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	30184
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	48089
ISDYNCMM208MsgTimer_mS_M_u32	2626856192
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	36821
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	30184
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	52333

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	171558144
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	8775
ISDYNVOLChkSumValidCount_Cnt_M_u16	61166
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	46822
ISDYNVOLMsgCountValidCount_Cnt_M_u16	35652
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	3105
ISDYNVOLMsgLenValidCount_Cnt_M_u16	49064
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	51530
ISDYNVOLMsgTimer_mS_M_u32	891782400
IgnOnTimer_mS_M_u32	1846396160
IgnTimeOff_Sec_M_u32	1986838031
ManVehSpd_Kph_M_f32	145.904907
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	194
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	198
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1082422528
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	182
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2445333760
PrevISDATBSI412MsgDLCError_Cnt_M_u08	231
PrevISDATBSI412MsgRxTime_MSec_M_u32	3744072960
PrevISDATBSI432MsgDLCError_Cnt_M_u08	174
PrevISDATBSI432MsgRxTime_MSec_M_u32	3230786816
PrevISDATDIRAMsgTxTime_MSec_M_u32	2865628416
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	59
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3208189184
PrevISDYNAASMsgDLCError_Cnt_M_u08	90
PrevISDYNAASMsgRxTime_MSec_M_u32	1279100160
PrevISDYNABRMsgDLCError_Cnt_M_u08	135
PrevISDYNABRMsgRxTime_MSec_M_u32	3177563392
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	59
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4200498432
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	63
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1290855680
PrevISDYNVOLMsgDLCError_Cnt_M_u08	129
PrevISDYNVOLMsgRxTime_MSec_M_u32	3267560704
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	113882368
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	152.007202
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	50131
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	2978
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	48648
VitesseVehicleBVRampValidCount_Cnt_M_u16	45975
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	61385
VitesseVehicleBVSigValidCount_Cnt_M_u16	58784
VitesseVehicleBV_Kph_M_f32	251.943893
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	52333
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	35612
VitesseVehiculeRoues_Kph_M_f32	419.562897
k_AASNTCEnableTimeout_mS_u16	33818
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	54990
k_AASNodeTimeout_mS_u16	58018
k_ABSNodeTimeout_mS_u16	24753
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	5973
k_ANGLEVOLANTSigValidThresh_Cnt_u16	61879
k_AngleVolantInvalidThresh_Cnt_u16	0
k_AngleVolantValidThresh_Cnt_u16	47652
k_BSI552MsgTimeout_mS_u16	54479
k_BSINTCEnableTimeout_mS_u16	21622
k_BSINodeAbsentDiag_Cnt_str.Threshold	44326
k_BSINodeAbsentDiag_Cnt_str.PStep	53104
k_BSINodeAbsentDiag_Cnt_str.NStep	54109
k_BSINodeAbsentTimeout_mS_u16	51355
k_BSINodeTimeout_mS_u16	347
k_BattOvHi_Volt_f32	11.6168003
k_BattOvLo_Volt_f32	29.0967007
k_BattUvHi_Volt_f32	8.33520031
k_BattUvLo_Volt_f32	24.7254009
k_CAVNTCEnableTimeout_mS_u16	28946
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	17460
k_CAVNodeTimeout_mS_u16	43997
k_CMM388MsgTimeout_mS_u16	60346
k_CMM388NTCEnableTimeout_mS_u16	1254
k_CMMNTCEnableTimeout_mS_u16	9186
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	57928
k_CONSANGLECPKMax_HwDeg_f32	447.47821
k_CONSANGLECPKMin_HwDeg_f32	-523.30658
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	25453
k_CONSANGLECPKSigValidThresh_Cnt_u16	25116
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	38752
k_CPKVehicleSpeedValidThresh_Cnt_u16	1638
k_CityParkInputInvalidThresh_Cnt_u16	64062
k_CityParkInputValidThresh_Cnt_u16	12715
k_ComputerRazGCTSigValidThresh_Cnt_u16	1320
k_CptTemporelSigValidThresh_Cnt_u16	32163
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	30204
k_DMDFCTCPKSigValidThresh_Cnt_u16	4195
k_DMDFCTCPKValidCount_Cnt_u16	17927
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	57115
k_DMDRELAXECPKSigValidThresh_Cnt_u16	57657
k_DMDRelaxeConsistentThresh_Cnt_u16	30711
k_DateValidThresh_Cnt_u16	29420
k_DefaultVehSpd_Kph_f32	155.563797
k_DiagMuxOnAbsentTimeout_mS_u16	60837
k_EMNodeTimeout_mS_u16	11034
k_ESPNTCEnableTimeout_mS_u16	5066
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	19184
k_EtatMTSigInvalidThresh_Cnt_u16	37203
k_EtatMTSigValidThresh_Cnt_u16	42194
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	10015
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	31057
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	54752
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	61875
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	19566
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	64219
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	29127
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	40361
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	8434
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	12523
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	23029
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	61848
k_ISDATDIRASentDiag_Cnt_str.Threshold	39837

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	59486
k_ISDATDIRASentDiag_Cnt_str.NStep	60819
k_ISDATDIRASentTimeout_mS_u16	32044
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	1337
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	57155
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	3910
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	41472
k_ISDYNAASChkSumValidThresh_Cnt_u16	52543
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	16239
k_ISDYNAASMsgCountValidThresh_Cnt_u16	28261
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	28628
k_ISDYNAASMsgLenValidThresh_Cnt_u16	33654
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	95
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	41106
k_ISDYNABRChkSumValidThresh_Cnt_u16	8057
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	24415
k_ISDYNABRMsgCountValidThresh_Cnt_u16	63926
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	41034
k_ISDYNABRMsgLenValidThresh_Cnt_u16	47212
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	49897
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	33959
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	2428
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	5973
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	57620
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	51499
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	6012
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	51646
k_ISDYNVOLChkSumValidThresh_Cnt_u16	21097
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	7925
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	4627
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	23090
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	15365
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	20570
k_IgnOnTimeout_mS_u16	57322
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	99.8104019
k_PowerCutVehSpdLowThresh_Kph_f32	193.224396
k_PowerCutVehSpdLowTimeout_mS_u16	50806
k_VBattMaxAAS_Volt_f32	0.308600008
k_VBattMaxBSI_Volt_f32	15.1590996
k_VBattMaxCAV_Volt_f32	26.6114998
k_VBattMaxCMM388_Volt_f32	6.07310009
k_VBattMaxCMM_Volt_f32	2.56049991
k_VBattMaxESP_Volt_f32	7.07019997
k_VBattMinAAS_Volt_f32	3.65140009
k_VBattMinBSI_Volt_f32	7.07019997
k_VBattMinCAV_Volt_f32	22.4878006
k_VBattMinCMM388_Volt_f32	10.0503998
k_VBattMinCMM_Volt_f32	16.9489994
k_VBattMinESP_Volt_f32	2.56049991
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	53115
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	51094
k_VitesseVehicleBVRampValidThresh_Cnt_u16	19942
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	17902
k_VitesseVehicleBVSigValidThresh_Cnt_u16	15160
k_VitesseVehicleBVSpeedPassThresh_kph_f32	156.567093
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	1182
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	57005
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	848700672
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	44013
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	68495872
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	63
target_SrlComInput_Per1_Batt_Volt_f32.value	11.6934004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3900265728
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	243
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.429115653
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	254
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2036319488
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	230
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	331769088
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	13
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	549258496
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	138650880
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	844776704
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	117499136
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3996615936
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	94
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	187
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	643343616
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	26
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	62
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3613312256
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	524641536
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2579236096
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	131
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	167
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	216
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	224
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3187332352
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2326
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.533061206
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1018777
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	102.890701
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	61845

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	68495872	68495872	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	68495872	68495872	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	57155	57155	✔
AngleVolantMsgTimer_mS_M_u32	68495872	68495872	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	68495872	68495872	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	68495872	68495872	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	68495872	68495872	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	68495872	68495872	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	19255	19255	✔
CONSANGLECPK_HwDeg_M_f32	602.554688	602.554688 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	19255	19255	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2990585088	2990585088	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	19897	19897	✔
CityParkInputConsistentCount_Cnt_M_u16	12715	12715	✔
CityParkInputInvalidCount_Cnt_M_u16	47654	47654	✔
CityParkInputMsgTimer_mS_M_u32	68495872	68495872	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	68495872	68495872	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	68495872	68495872	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	68495872	68495872	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	68495872	68495872	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	68495872	68495872	✔
ESPNTCEnableTimer_mS_M_u32	68495872	68495872	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	68495872	68495872	✔
EffacDefaultDiagTimer_mS_M_u32[1]	655	655	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	68495872	68495872	✔
ElecIntTimer_mS_M_u32[1]	45465	45465	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	68495872	68495872	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATDIRASentFltAcc_Cnt_M_u16	39837	39837	✔
ISDATDIRASentTimer_mS_M_u32	68495872	68495872	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	68495872	68495872	✔
IgnOnTimer_mS_M_u32	68495872	68495872	✔
IgnTimeOff_Sec_M_u32	1986838031	1986838031	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	254	254	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2036319488	2036319488	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	230	230	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	331769088	331769088	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	13	13	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	549258496	549258496	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	138650880	138650880	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2865628416	2865628416	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	8	8	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	117499136	117499136	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	57	57	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3996615936	3996615936	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	206	206	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	643343616	643343616	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	45	45	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3613312256	3613312256	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	524641536	524641536	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	151	151	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2579236096	2579236096	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3187332352	3187332352	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	152.007202	152.007202	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	251.943893	251.943893	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	419.562897	419.562897	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	19255	19255	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1986838031	1986838031	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	602.554688	602.554688 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.379 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3168379904
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	7300
AASNodeAbsentTimer_mS_M_u32	799020032
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	50804
ANGLEVOLANTSigValidCount_Cnt_M_u16	50416
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	24809
AngleVolantMsgTimer_mS_M_u32	3168379904
AngleVolantValidCount_Cnt_M_u16	32427
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3801994240
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2662355968
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3069264896
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1729496064
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	14227
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	513655808
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	35415
CAVNodeAbsentTimer_mS_M_u32	2464920576
CDD_SrlComVehSpd_Kph_G_f32	87.552803
CMM388NTCEnableTimer_mS_M_u32	3453613056
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4021400576
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	21267
CMMNodeAbsentTimer_mS_M_u32	886047744
CONSANGLECPKSigInvalidCount_Cnt_M_u16	51358
CONSANGLECPKSigValidCount_Cnt_M_u16	18154
CONSANGLECPK_Cnt_M_u16	6349
CONSANGLECPK_HwDeg_M_f32	-299.858307
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	6349
CPKVehicleSpeedMsgTimer_mS_M_u32	3186664448
CPKVehicleSpeedValidCount_Cnt_M_u16	26639
CityParkInputConsistentCount_Cnt_M_u16	21551
CityParkInputInvalidCount_Cnt_M_u16	60358
CityParkInputMsgTimer_mS_M_u32	2036319488
CityParkInputValidCount_Cnt_M_u16	5

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713640448
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	63496
ComputerRazGCTSigInvalidTimer_mS_M_u32	3573560320
ComputerRazGCTSigValidCount_Cnt_M_u16	22028
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	21058
DMDFCTCPKSigValidCount_Cnt_M_u16	22886
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	8246
DMDRELAXECPKSigValidCount_Cnt_M_u16	19506
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	11779
DateInvalidTimer_mS_M_u32	2662355968
DiagMuxOnAbsentTimer_mS_M_u32	2520867840
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1729496064
ESPNTCEnableTimer_mS_M_u32	742986752
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	61803
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	565
ElecIntTimer_mS_M_u32[1]	78789
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3519005696
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	34527
EtatMTSigValidCount_Cnt_M_u16	41767
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	59488
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	5164
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	44
ISDAT4V2BSI552MsgTimer_mS_M_u32	106169344
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	11731
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	55971
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	41767
ISDATBSI3F2MsgTimer_mS_M_u32	1316971520
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	55643
ISDATBSI412MsgLenValidCount_Cnt_M_u16	18395
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	34527
ISDATBSI412MsgTimer_mS_M_u32	3944195072
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	65431
ISDATBSI432MsgLenValidCount_Cnt_M_u16	47343
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	800
ISDATDIRASentFltAcc_Cnt_M_u16	2356
ISDATDIRASentTimer_mS_M_u32	3186664448
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	9099
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	32427
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	6369
ISDYN2CMMMsgTimer_mS_M_u32	2055410688
ISDYNAASChkSumInvalidCount_Cnt_M_u16	25158
ISDYNAASChkSumValidCount_Cnt_M_u16	41698
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	47946
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	64122
ISDYNAASMsgLenValidCount_Cnt_M_u16	59214
ISDYNAASMsgTimeValidCount_Cnt_M_u16	25158
ISDYNAASMsgTimer_mS_M_u32	2169893888
ISDYNABRChkSumInvalidCount_Cnt_M_u16	2865
ISDYNABRChkSumValidCount_Cnt_M_u16	57396
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	13669
ISDYNABRMsgCountValidCount_Cnt_M_u16	57153
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	22205
ISDYNABRMsgLenValidCount_Cnt_M_u16	32329
ISDYNABRMsgTimeValidCount_Cnt_M_u16	6349
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	15474
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	28922
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	41767
ISDYNCMM208MsgTimer_mS_M_u32	4072330240

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	15474
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	28922
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	3049
ISDYNCMM388MsgTimer_mS_M_u32	2923787264
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	63708
ISDYNVOLChkSumValidCount_Cnt_M_u16	51624
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	32128
ISDYNVOLMsgCountValidCount_Cnt_M_u16	5924
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	50508
ISDYNVOLMsgLenValidCount_Cnt_M_u16	24952
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	21267
ISDYNVOLMsgTimer_mS_M_u32	343684096
IgnOnTimer_mS_M_u32	3536417792
IgnTimeOff_Sec_M_u32	2340725303
ManVehSpd_Kph_M_f32	517.81958
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	195
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	82
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3525665792
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	180
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3354412032
PrevISDATBSI412MsgDLCError_Cnt_M_u08	10
PrevISDATBSI412MsgRxTime_MSec_M_u32	1081390080
PrevISDATBSI432MsgDLCError_Cnt_M_u08	220
PrevISDATBSI432MsgRxTime_MSec_M_u32	2478642176
PrevISDATDIRAMsgTxTime_MSec_M_u32	1837675520
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	24
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1887929344
PrevISDYNAASMsgDLCError_Cnt_M_u08	214
PrevISDYNAASMsgRxTime_MSec_M_u32	2805609472
PrevISDYNABRMsgDLCError_Cnt_M_u08	15
PrevISDYNABRMsgRxTime_MSec_M_u32	1153528832
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	17
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1624716288
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	32
PrevISDYNCMM388MsgRxTime_MSec_M_u32	715133952
PrevISDYNVOLMsgDLCError_Cnt_M_u08	119
PrevISDYNVOLMsgRxTime_MSec_M_u32	967422976
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	609592320
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	441.185791
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	39864
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	39692
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	49433
VitesseVehicleBVRampValidCount_Cnt_M_u16	46893
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	26965
VitesseVehicleBVSigValidCount_Cnt_M_u16	32401
VitesseVehicleBV_Kph_M_f32	374.68399
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	3049
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	9885

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	598.67218
k_AASNTCEnableTimeout_mS_u16	47652
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	45254
k_AASNodeTimeout_mS_u16	5644
k_ABSNodeTimeout_mS_u16	27679
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	21746
k_ANGLEVOLANTSigValidThresh_Cnt_u16	60554
k_AngleVolantInvalidThresh_Cnt_u16	65535
k_AngleVolantValidThresh_Cnt_u16	60358
k_BSI552MsgTimeout_mS_u16	54660
k_BSINTCEnableTimeout_mS_u16	24975
k_BSINodeAbsentDiag_Cnt_str.Threshold	25086
k_BSINodeAbsentDiag_Cnt_str.PStep	33890
k_BSINodeAbsentDiag_Cnt_str.NStep	37338
k_BSINodeAbsentTimeout_mS_u16	1249
k_BSINodeTimeout_mS_u16	800
k_BattOvHi_Volt_f32	7.1644001
k_BattOvLo_Volt_f32	17.1541004
k_BattUvHi_Volt_f32	29.5142002
k_BattUvLo_Volt_f32	13.7004995
k_CAVNTCEnableTimeout_mS_u16	65276
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	56981
k_CAVNodeTimeout_mS_u16	13338
k_CMM388MsgTimeout_mS_u16	55172
k_CMM388NTCEnableTimeout_mS_u16	15360
k_CMMNTCEnableTimeout_mS_u16	19403
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	53529
k_CONSANGLECPKMax_HwDeg_f32	337.625397
k_CONSANGLECPKMin_HwDeg_f32	-288.739899
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	18153
k_CONSANGLECPKSigValidThresh_Cnt_u16	41373
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	28626
k_CPKVehicleSpeedValidThresh_Cnt_u16	1342
k_CityParkInputInvalidThresh_Cnt_u16	46455
k_CityParkInputValidThresh_Cnt_u16	21551
k_ComputerRazGCTSigValidThresh_Cnt_u16	16377
k_CptTemporelSigValidThresh_Cnt_u16	23881
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	4541
k_DMDFCTCPKSigValidThresh_Cnt_u16	31049
k_DMDFCTCPKValidCount_Cnt_u16	56987
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	6369
k_DMDRELAXECPKSigValidThresh_Cnt_u16	10565
k_DMDRelaxeConsistentThresh_Cnt_u16	56587
k_DateValidThresh_Cnt_u16	44
k_DefaultVehSpd_Kph_f32	72.506897
k_DiagMuxOnAbsentTimeout_mS_u16	27011
k_EMNodeTimeout_mS_u16	60003
k_ESPNTCEnableTimeout_mS_u16	18387
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	14113
k_EtatMTSigInvalidThresh_Cnt_u16	33848
k_EtatMTSigValidThresh_Cnt_u16	57467
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	31893
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	60605
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	31632
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	26200
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	56552
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	15327
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	36252
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	12468
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	60443
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	14257

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	33617
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	56488
k_ISDATDIRASentDiag_Cnt_str.Threshold	58959
k_ISDATDIRASentDiag_Cnt_str.PStep	33467
k_ISDATDIRASentDiag_Cnt_str.NStep	17654
k_ISDATDIRASentTimeout_mS_u16	25773
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	26053
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	24809
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	17759
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	17969
k_ISDYNAASChkSumValidThresh_Cnt_u16	23348
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	61541
k_ISDYNAASMsgCountValidThresh_Cnt_u16	55873
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	11445
k_ISDYNAASMsgLenValidThresh_Cnt_u16	33680
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	24722
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	27131
k_ISDYNABRChkSumValidThresh_Cnt_u16	9223
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	62099
k_ISDYNABRMsgCountValidThresh_Cnt_u16	6735
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	52755
k_ISDYNABRMsgLenValidThresh_Cnt_u16	44139
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	19126
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	43324
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	54268
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	1011
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	33140
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	49136
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	13246
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	6966
k_ISDYNVOLChkSumValidThresh_Cnt_u16	51190
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	56528
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	56504
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	37211
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	53923
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	40930
k_IgnOnTimeout_mS_u16	34994
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	84.2671967
k_PowerCutVehSpdLowThresh_Kph_f32	100.025002
k_PowerCutVehSpdLowTimeout_mS_u16	25360
k_VBattMaxAAS_Volt_f32	0.775600016
k_VBattMaxBSI_Volt_f32	4.75740004
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	6.71729994
k_VBattMaxCMM_Volt_f32	0.336100012
k_VBattMaxESP_Volt_f32	23.3841991
k_VBattMinAAS_Volt_f32	1.92970002
k_VBattMinBSI_Volt_f32	23.3841991
k_VBattMinCAV_Volt_f32	0.560100019
k_VBattMinCMM388_Volt_f32	28.6555004
k_VBattMinCMM_Volt_f32	26.1032009
k_VBattMinESP_Volt_f32	0.336100012
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	36607
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	44399
k_VitesseVehicleBVRampValidThresh_Cnt_u16	47232
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	50344
k_VitesseVehicleBVSigValidThresh_Cnt_u16	43912
k_VitesseVehicleBVSpeedPassThresh_kph_f32	430.710785
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	50519
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	3563
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2662355968
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65109
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3632743680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	32
target_SrlComInput_Per1_Batt_Volt_f32.value	20.1945992
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1170654208
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	221
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.335017979
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2027123712
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	25
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	203396096
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2277225472
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3014120448
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1474556928
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	61
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1013978112
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	692859904
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	61
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	71
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	88
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	90
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3983070208
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	127
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	450262016
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2778895360
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3636376576
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	97
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2873246720
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	44
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.149012446
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	716315
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	17.2761993
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	39538

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	24811	24811	✔
AngleVolantMsgTimer_mS_M_u32	3632743680	3632743680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	21267	21267	✔
CMMNodeAbsentTimer_mS_M_u32	1013978112	1013978112	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	6349	6349	✔
CONSANGLECPK_HwDeg_M_f32	-299.858307	-299.858307 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	6349	6349	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3186664448	3186664448	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	26639	26639	✔
CityParkInputConsistentCount_Cnt_M_u16	21551	21551	✔
CityParkInputInvalidCount_Cnt_M_u16	60358	60358	✔
CityParkInputMsgTimer_mS_M_u32	3632743680	3632743680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3632743680	3632743680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3632743680	3632743680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3632743680	3632743680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3632743680	3632743680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3632743680	3632743680	✔
ESPNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	8	8	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	565	565	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	78789	78789	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3632743680	3632743680	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	58959	58959	✔
ISDATDIRASentTimer_mS_M_u32	3632743680	3632743680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3632743680	3632743680	✔
IgnOnTimer_mS_M_u32	3536417792	3536417792	✔
IgnTimeOff_Sec_M_u32	2340725303	2340725303	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	143	143	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2027123712	2027123712	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	25	25	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	203396096	203396096	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2277225472	2277225472	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	131	131	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3014120448	3014120448	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1837675520	1837675520	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	61	61	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1013978112	1013978112	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	45	45	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	692859904	692859904	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	59	59	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3983070208	3983070208	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	190	190	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	450262016	450262016	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	223	223	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2778895360	2778895360	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3636376576	3636376576	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2873246720	2873246720	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	441.185791	441.185791	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	374.68399	374.68399	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	598.67218	598.67218	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	6349	6349	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2340725303	2340725303	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-299.858307	-299.858307 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	72.506897	72.506897	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.380 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1889654528
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	7074
AASNodeAbsentTimer_mS_M_u32	2114881280
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	32720
ANGLEVOLANTSigValidCount_Cnt_M_u16	40989
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	8819
AngleVolantMsgTimer_mS_M_u32	1889654528
AngleVolantValidCount_Cnt_M_u16	63916
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2350204672
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3252537088
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3906664192
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1533851392
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	26739
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	64321280
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	10407
CAVNodeAbsentTimer_mS_M_u32	2326505216
CDD_SrlComVehSpd_Kph_G_f32	592.205811
CMM388NTCEnableTimer_mS_M_u32	1658906368
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	207202048
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	15154
CMMNodeAbsentTimer_mS_M_u32	1514059520
CONSANGLECPKSigInvalidCount_Cnt_M_u16	20563
CONSANGLECPKSigValidCount_Cnt_M_u16	12591
CONSANGLECPK_Cnt_M_u16	1926
CONSANGLECPK_HwDeg_M_f32	-95.8023987
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	1926
CPKVehicleSpeedMsgTimer_mS_M_u32	2304562944
CPKVehicleSpeedValidCount_Cnt_M_u16	13673
CityParkInputConsistentCount_Cnt_M_u16	35104
CityParkInputInvalidCount_Cnt_M_u16	12123
CityParkInputMsgTimer_mS_M_u32	2027123712
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3934422784
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	39190
ComputerRazGCTSigInvalidTimer_mS_M_u32	3060672256
ComputerRazGCTSigValidCount_Cnt_M_u16	14217
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	60391
DMDFCTCPKSigValidCount_Cnt_M_u16	37435
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	64138
DMDRELAXECPKSigValidCount_Cnt_M_u16	37463
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	62500
DateInvalidTimer_mS_M_u32	3252537088
DiagMuxOnAbsentTimer_mS_M_u32	862623488
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1533851392
ESPNTCEnableTimer_mS_M_u32	1813219072
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	60395
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	79
EffacDefaultDiagTimer_mS_M_u32[1]	699
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1234
ElecIntTimer_mS_M_u32[1]	23646
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4067391232
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	56529
EtatMTSigValidCount_Cnt_M_u16	54201
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	30989
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	20841
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	13801
ISDAT4V2BSI552MsgTimer_mS_M_u32	4122130176
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	45428
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	5828
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	54201
ISDATBSI3F2MsgTimer_mS_M_u32	2192611072
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	8155
ISDATBSI412MsgLenValidCount_Cnt_M_u16	27
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	56529
ISDATBSI412MsgTimer_mS_M_u32	1575474944
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	17830
ISDATBSI432MsgLenValidCount_Cnt_M_u16	42335
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	8780
ISDATDIRASentFltAcc_Cnt_M_u16	24592
ISDATDIRASentTimer_mS_M_u32	2304562944
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	24396
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	63916
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	54282
ISDYN2CMMMsgTimer_mS_M_u32	3915745024
ISDYNAASChkSumInvalidCount_Cnt_M_u16	53852
ISDYNAASChkSumValidCount_Cnt_M_u16	44104
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	32719
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	9278
ISDYNAASMsgLenValidCount_Cnt_M_u16	55682
ISDYNAASMsgTimeValidCount_Cnt_M_u16	53852
ISDYNAASMsgTimer_mS_M_u32	946661120
ISDYNABRChkSumInvalidCount_Cnt_M_u16	39707
ISDYNABRChkSumValidCount_Cnt_M_u16	22479
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	38143
ISDYNABRMsgCountValidCount_Cnt_M_u16	13099
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	57846
ISDYNABRMsgLenValidCount_Cnt_M_u16	50962
ISDYNABRMsgTimeValidCount_Cnt_M_u16	1926
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	51224
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	30272
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	54201
ISDYNCMM208MsgTimer_mS_M_u32	264128256
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	51224

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	30272
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	51698
ISDYNCMM388MsgTimer_mS_M_u32	3483264768
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	14233
ISDYNVOLChkSumValidCount_Cnt_M_u16	8437
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	57901
ISDYNVOLMsgCountValidCount_Cnt_M_u16	53505
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	13384
ISDYNVOLMsgLenValidCount_Cnt_M_u16	15236
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	15154
ISDYNVOLMsgTimer_mS_M_u32	3891930880
IgnOnTimer_mS_M_u32	1913808640
IgnTimeOff_Sec_M_u32	737644800
ManVehSpd_Kph_M_f32	341.678589
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	196
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	89
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	264148736
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	152
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1910372096
PrevISDATBSI412MsgDLCError_Cnt_M_u08	223
PrevISDATBSI412MsgRxTime_MSec_M_u32	3859851008
PrevISDATBSI432MsgDLCError_Cnt_M_u08	245
PrevISDATBSI432MsgRxTime_MSec_M_u32	95913728
PrevISDATDIRAMsgTxTime_MSec_M_u32	2933171968
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	154
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3843569408
PrevISDYNAASMsgDLCError_Cnt_M_u08	7
PrevISDYNAASMsgRxTime_MSec_M_u32	2814387968
PrevISDYNABRMsgDLCError_Cnt_M_u08	37
PrevISDYNABRMsgRxTime_MSec_M_u32	4230637312
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	190
PrevISDYNCMM208MsgRxTime_MSec_M_u32	787031808
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	68
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2366539520
PrevISDYNVOLMsgDLCError_Cnt_M_u08	228
PrevISDYNVOLMsgRxTime_MSec_M_u32	242329344
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	707647232
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	90.221199
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	47236
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	13896
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	3169
VitesseVehicleBVRampValidCount_Cnt_M_u16	42469
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	23341
VitesseVehicleBVSigValidCount_Cnt_M_u16	14138
VitesseVehicleBV_Kph_M_f32	246.141495
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	51698
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	30103
VitesseVehiculeRoues_Kph_M_f32	19.0011005

Name	Input Value
k_AASNTCEnableTimeout_mS_u16	16257
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	36699
k_AASNodeTimeout_mS_u16	50504
k_ABSNodeTimeout_mS_u16	21072
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	29077
k_ANGLEVOLANTSigValidThresh_Cnt_u16	13966
k_AngleVolantInvalidThresh_Cnt_u16	5583
k_AngleVolantValidThresh_Cnt_u16	12123
k_BSI552MsgTimeout_mS_u16	50402
k_BSINTCEnableTimeout_mS_u16	65470
k_BSINodeAbsentDiag_Cnt_str.Threshold	57076
k_BSINodeAbsentDiag_Cnt_str.PStep	56328
k_BSINodeAbsentDiag_Cnt_str.NStep	26592
k_BSINodeAbsentTimeout_mS_u16	5771
k_BSINodeTimeout_mS_u16	8780
k_BattOvHi_Volt_f32	23.2492008
k_BattOvLo_Volt_f32	0.992500007
k_BattUvHi_Volt_f32	16.1853008
k_BattUvLo_Volt_f32	28.5554008
k_CAVNTCEnableTimeout_mS_u16	19897
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	41965
k_CAVNodeTimeout_mS_u16	64991
k_CMM388MsgTimeout_mS_u16	60066
k_CMM388NTCEnableTimeout_mS_u16	44334
k_CMMNTCEnableTimeout_mS_u16	14220
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	26147
k_CONSANGLECPKMax_HwDeg_f32	394.091095
k_CONSANGLECPKMin_HwDeg_f32	-371.653809
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	6386
k_CONSANGLECPKSigValidThresh_Cnt_u16	1175
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	20470
k_CPKVehicleSpeedValidThresh_Cnt_u16	59442
k_CityParkInputInvalidThresh_Cnt_u16	13385
k_CityParkInputValidThresh_Cnt_u16	35104
k_ComputerRazGCTSigValidThresh_Cnt_u16	37634
k_CptTemporelSigValidThresh_Cnt_u16	42706
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	45302
k_DMDFCTCPKSigValidThresh_Cnt_u16	54802
k_DMDFCTCPKValidCount_Cnt_u16	37723
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	54282
k_DMDRELAXECPKSigValidThresh_Cnt_u16	24222
k_DMDRelaxeConsistentThresh_Cnt_u16	56140
k_DateValidThresh_Cnt_u16	13801
k_DefaultVehSpd_Kph_f32	22.1620007
k_DiagMuxOnAbsentTimeout_mS_u16	28004
k_EMNodeTimeout_mS_u16	16132
k_ESPNTCEnableTimeout_mS_u16	57395
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	21515
k_EtatMTSigInvalidThresh_Cnt_u16	3078
k_EtatMTSigValidThresh_Cnt_u16	13050
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	62893
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	28917
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	55037
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	23525
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	25589
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	2127
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	61335
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	37392
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	36890
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	15066
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	954

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	38646
k_ISDATDIRASentDiag_Cnt_str.Threshold	25385
k_ISDATDIRASentDiag_Cnt_str.PStep	45245
k_ISDATDIRASentDiag_Cnt_str.NStep	44580
k_ISDATDIRASentTimeout_mS_u16	32423
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	44959
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	8819
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	6031
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	59931
k_ISDYNAASChkSumValidThresh_Cnt_u16	59087
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	25599
k_ISDYNAASMsgCountValidThresh_Cnt_u16	16939
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	18063
k_ISDYNAASMsgLenValidThresh_Cnt_u16	36028
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	64118
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	8252
k_ISDYNABRChkSumValidThresh_Cnt_u16	19928
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	14195
k_ISDYNABRMsgCountValidThresh_Cnt_u16	56320
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	51762
k_ISDYNABRMsgLenValidThresh_Cnt_u16	47851
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	42699
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	40952
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	62456
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	22419
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	20176
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	44829
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	14195
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	34378
k_ISDYNVOLChkSumValidThresh_Cnt_u16	43978
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	64956
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	29251
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	44381
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	13637
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	44743
k_IgnOnTimeout_mS_u16	11734
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	197.381195
k_PowerCutVehSpdLowThresh_Kph_f32	30.1077995
k_PowerCutVehSpdLowTimeout_mS_u16	62653
k_VBattMaxAAS_Volt_f32	0.983900011
k_VBattMaxBSI_Volt_f32	8.43889999
k_VBattMaxCAV_Volt_f32	1.74699998
k_VBattMaxCMM388_Volt_f32	12.4527998
k_VBattMaxCMM_Volt_f32	16.3530998
k_VBattMaxESP_Volt_f32	2.47720003
k_VBattMinAAS_Volt_f32	29.9738007
k_VBattMinBSI_Volt_f32	2.47720003
k_VBattMinCAV_Volt_f32	0.663500011
k_VBattMinCMM388_Volt_f32	10.0278997
k_VBattMinCMM_Volt_f32	29.2539005
k_VBattMinESP_Volt_f32	16.3530998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	39921
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	11361
k_VitesseVehicleBVRampValidThresh_Cnt_u16	12589
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	12277
k_VitesseVehicleBVSigValidThresh_Cnt_u16	10005
k_VitesseVehicleBVSpeedPassThresh_kph_f32	112.031898
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	30631
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	6571
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3252537088
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	61417
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current	1499264000
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	68
target_SrlComInput_Per1_Batt_Volt_f32.value	5.75159979
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1918531328
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	128
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.810699046
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	670328576
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1183844096
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	214
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3963332352
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3237431040
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1824712448
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	127
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2543748864
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	41
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3918145280
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	212
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1471432448
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	77
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	79
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	150
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	169
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	192
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	233531136
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1174865664
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3308431104
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	181
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2414343936
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	537
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.766526163
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	893791
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	59.6040993
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	9302

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1499264000	1499264000	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2350204672	2350204672	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	3252537088	3252537088	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3906664192	3906664192	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	1533851392	1533851392	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	1926	1926	✔
CONSANGLECPK_HwDeg_M_f32	-95.8023987	-95.8023987 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1499264000	1499264000	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1499264000	1499264000	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1499264000	1499264000	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1499264000	1499264000	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1499264000	1499264000	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1499264000	1499264000	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1499264000	1499264000	✔
ESPNTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	79	79	✔
EffacDefaultDiagTimer_mS_M_u32[1]	699	699	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1234	1234	✔
ElecIntTimer_mS_M_u32[1]	23646	23646	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1499264000	1499264000	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3237431040	3237431040	✔
ISDATDIRASentFltAcc_Cnt_M_u16	25385	25385	✔
ISDATDIRASentTimer_mS_M_u32	1499264000	1499264000	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1499264000	1499264000	✔
IgnOnTimer_mS_M_u32	1499264000	1499264000	✔
IgnTimeOff_Sec_M_u32	737644800	737644800	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	7	7	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	238	238	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	670328576	670328576	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	136	136	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1183844096	1183844096	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	214	214	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3963332352	3963332352	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	126	126	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3237431040	3237431040	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2933171968	2933171968	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	127	127	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2543748864	2543748864	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	41	41	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3918145280	3918145280	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	152	152	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1471432448	1471432448	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	48	48	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	233531136	233531136	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	3	3	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1174865664	1174865664	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	74	74	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3308431104	3308431104	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2414343936	2414343936	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	90.221199	90.221199	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	246.141495	246.141495	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	19.0011005	19.0011005	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	1926	1926	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	737644800	737644800	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-95.8023987	-95.8023987 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	22.1620007	22.1620007	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.381 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	706931712
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	35549
AASNodeAbsentTimer_mS_M_u32	3219086336
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	14237
ANGLEVOLANTSigValidCount_Cnt_M_u16	54271
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	35682
AngleVolantMsgTimer_mS_M_u32	706931712
AngleVolantValidCount_Cnt_M_u16	35736
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2973047808
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1465359360
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2241760256
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3682290688
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	49948
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1637551104
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	35733
CAVNodeAbsentTimer_mS_M_u32	3641637888
CDD_SrlComVehSpd_Kph_G_f32	131.651398
CMM388NTCEnableTimer_mS_M_u32	354761728
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1200946176
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	51359
CMMNodeAbsentTimer_mS_M_u32	2809482240
CONSANGLECPKSigInvalidCount_Cnt_M_u16	49055
CONSANGLECPKSigValidCount_Cnt_M_u16	3537
CONSANGLECPK_Cnt_M_u16	6292
CONSANGLECPK_HwDeg_M_f32	637.924988
CPKOK_Cnt_M_lgc	0

Name	Input Value
CPKVehicleSpeedInvalidCount_Cnt_M_u16	6292
CPKVehicleSpeedMsgTimer_mS_M_u32	2023353344
CPKVehicleSpeedValidCount_Cnt_M_u16	48110
CityParkInputConsistentCount_Cnt_M_u16	14236
CityParkInputInvalidCount_Cnt_M_u16	56059
CityParkInputMsgTimer_mS_M_u32	1213639936
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1826839552
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	64737
ComputerRazGCTSigInvalidTimer_mS_M_u32	947092480
ComputerRazGCTSigValidCount_Cnt_M_u16	6297
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	60151
DMDFCTCPKSigValidCount_Cnt_M_u16	24833
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56479
DMDRELAXECPKSigValidCount_Cnt_M_u16	38529
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	33060
DateInvalidTimer_mS_M_u32	1465359360
DiagMuxOnAbsentTimer_mS_M_u32	3726814208
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3682290688
ESPNTCEnableTimer_mS_M_u32	3341310976
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	59997
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	2500
EffacDefaultDiagTimer_mS_M_u32[1]	3500
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2323
ElecIntTimer_mS_M_u32[1]	45466
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2617052160
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	15538
EtatMTSigValidCount_Cnt_M_u16	608
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	60065
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	54867
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	22919
ISDAT4V2BSI552MsgTimer_mS_M_u32	3480833024
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	54722
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	51448
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	608
ISDATBSI3F2MsgTimer_mS_M_u32	2334174208
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	11443
ISDATBSI412MsgLenValidCount_Cnt_M_u16	8089
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	15538
ISDATBSI412MsgTimer_mS_M_u32	220261376
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	43939
ISDATBSI432MsgLenValidCount_Cnt_M_u16	51297
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	49918
ISDATDIRASentFltAcc_Cnt_M_u16	2450
ISDATDIRASentTimer_mS_M_u32	2023353344
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	10258
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	35736
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	48118
ISDYN2CMMMsgTimer_mS_M_u32	3819068416
ISDYNAASChkSumInvalidCount_Cnt_M_u16	39903
ISDYNAASChkSumValidCount_Cnt_M_u16	61025
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	37527
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	23704
ISDYNAASMsgLenValidCount_Cnt_M_u16	30289
ISDYNAASMsgTimeValidCount_Cnt_M_u16	39903
ISDYNAASMsgTimer_mS_M_u32	2451651584
ISDYNABRChkSumInvalidCount_Cnt_M_u16	37750
ISDYNABRChkSumValidCount_Cnt_M_u16	25440
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	51550
ISDYNABRMsgCountValidCount_Cnt_M_u16	36128
ISDYNABRMsgCount_Cnt_M_u08	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	34846
ISDYNABRMsgLenValidCount_Cnt_M_u16	34704
ISDYNABRMsgTimeValidCount_Cnt_M_u16	6292
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	43301
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	61203
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	608
ISDYNCMM208MsgTimer_mS_M_u32	3362921472
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	43301
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	61203
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	11670
ISDYNCMM388MsgTimer_mS_M_u32	3896556544
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	58525
ISDYNVOLChkSumValidCount_Cnt_M_u16	38223
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	60149
ISDYNVOLMsgCountValidCount_Cnt_M_u16	895
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	50142
ISDYNVOLMsgLenValidCount_Cnt_M_u16	48112
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	51359
ISDYNVOLMsgTimer_mS_M_u32	3245308928
IgnOnTimer_mS_M_u32	1128578048
IgnTimeOff_Sec_M_u32	2657862575
ManVehSpd_Kph_M_f32	537.46167
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	203
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	242
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1283894272
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	41
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2096991232
PrevISDATBSI412MsgDLCError_Cnt_M_u08	110
PrevISDATBSI412MsgRxTime_MSec_M_u32	4248304640
PrevISDATBSI432MsgDLCError_Cnt_M_u08	63
PrevISDATBSI432MsgRxTime_MSec_M_u32	2870762496
PrevISDATDIRAMsgTxTime_MSec_M_u32	3402365952
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	231
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3512519680
PrevISDYNAASMsgDLCError_Cnt_M_u08	173
PrevISDYNAASMsgRxTime_MSec_M_u32	1491958784
PrevISDYNABRMsgDLCError_Cnt_M_u08	13
PrevISDYNABRMsgRxTime_MSec_M_u32	675068928
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	185
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2309651456
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	240
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2598329344
PrevISDYNVOLMsgDLCError_Cnt_M_u08	125
PrevISDYNVOLMsgRxTime_MSec_M_u32	76348416
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3676236800
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	197.014008
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	37526
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	52943
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	11671
VitesseVehicleBVRampValidCount_Cnt_M_u16	22672
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	16414
VitesseVehicleBVSigValidCount_Cnt_M_u16	60224
VitesseVehicleBV_Kph_M_f32	242.279099
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	11670
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	304
VitesseVehiculeRoues_Kph_M_f32	519.426697
k_AASNTCEnableTimeout_mS_u16	28491
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	37267
k_AASNodeTimeout_mS_u16	10703
k_ABSNodeTimeout_mS_u16	58356
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	7390
k_ANGLEVOLANTSigValidThresh_Cnt_u16	16348
k_AngleVolantInvalidThresh_Cnt_u16	44899
k_AngleVolantValidThresh_Cnt_u16	56059
k_BSI552MsgTimeout_mS_u16	61303
k_BSINTCEnableTimeout_mS_u16	32923
k_BSINodeAbsentDiag_Cnt_str.Threshold	23293
k_BSINodeAbsentDiag_Cnt_str.PStep	19323
k_BSINodeAbsentDiag_Cnt_str.NStep	34701
k_BSINodeAbsentTimeout_mS_u16	57946
k_BSINodeTimeout_mS_u16	49918
k_BattOvHi_Volt_f32	25.6257992
k_BattOvLo_Volt_f32	19.4676991
k_BattUvHi_Volt_f32	8.70940018
k_BattUvLo_Volt_f32	26.7157993
k_CAVNTCEnableTimeout_mS_u16	62961
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	21651
k_CAVNodeTimeout_mS_u16	62619
k_CMM388MsgTimeout_mS_u16	9693
k_CMM388NTCEnableTimeout_mS_u16	62425
k_CMMNTCEnableTimeout_mS_u16	59066
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	54572
k_CONSANGLECPKMax_HwDeg_f32	306.274902
k_CONSANGLECPKMin_HwDeg_f32	-387.517487
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	18582
k_CONSANGLECPKSigValidThresh_Cnt_u16	23600
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	46421
k_CPKVehicleSpeedValidThresh_Cnt_u16	53622
k_CityParkInputInvalidThresh_Cnt_u16	16252
k_CityParkInputValidThresh_Cnt_u16	14236
k_ComputerRazGCTSigValidThresh_Cnt_u16	46504
k_CptTemporelSigValidThresh_Cnt_u16	59742
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	8990
k_DMDFCTCPKSigValidThresh_Cnt_u16	25232
k_DMDFCTCPKValidCount_Cnt_u16	38692
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	48118
k_DMDRELAXECPKSigValidThresh_Cnt_u16	17216
k_DMDRelaxeConsistentThresh_Cnt_u16	26822
k_DateValidThresh_Cnt_u16	22919
k_DefaultVehSpd_Kph_f32	125.9963
k_DiagMuxOnAbsentTimeout_mS_u16	24842
k_EMNodeTimeout_mS_u16	22916
k_ESPNTCEnableTimeout_mS_u16	21137
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	51252
k_EtatMTSigInvalidThresh_Cnt_u16	49117
k_EtatMTSigValidThresh_Cnt_u16	57095
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	42744
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	3206
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	5277

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	32359
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	4957
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	34231
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	39368
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	30790
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	52903
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	18936
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	28158
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	23015
k_ISDATDIRASentDiag_Cnt_str.Threshold	31074
k_ISDATDIRASentDiag_Cnt_str.PStep	34522
k_ISDATDIRASentDiag_Cnt_str.NStep	11395
k_ISDATDIRASentTimeout_mS_u16	30322
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	35364
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	35682
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	62365
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	44662
k_ISDYNAASChkSumValidThresh_Cnt_u16	48736
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	25694
k_ISDYNAASMsgCountValidThresh_Cnt_u16	26656
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	2938
k_ISDYNAASMsgLenValidThresh_Cnt_u16	28115
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	228
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	28700
k_ISDYNABRChkSumValidThresh_Cnt_u16	4622
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	24092
k_ISDYNABRMsgCountValidThresh_Cnt_u16	11198
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	9119
k_ISDYNABRMsgLenValidThresh_Cnt_u16	34141
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	2949
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	30362
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	9460
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	46870
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	53917
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	44799
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	22003
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	55918
k_ISDYNVOLChkSumValidThresh_Cnt_u16	13204
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	61922
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	38500
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	28846
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	31580
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	20733
k_IgnOnTimeout_mS_u16	20842
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	137.022202
k_PowerCutVehSpdLowThresh_Kph_f32	164.029999
k_PowerCutVehSpdLowTimeout_mS_u16	14263
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	29.8222008
k_VBattMaxCAV_Volt_f32	19.0114994
k_VBattMaxCMM388_Volt_f32	5.91120005
k_VBattMaxCMM_Volt_f32	4.6329999
k_VBattMaxESP_Volt_f32	4.77510023
k_VBattMinAAS_Volt_f32	29.5737
k_VBattMinBSI_Volt_f32	4.77510023
k_VBattMinCAV_Volt_f32	23.9249992
k_VBattMinCMM388_Volt_f32	28.1585999
k_VBattMinCMM_Volt_f32	18.9143009
k_VBattMinESP_Volt_f32	4.6329999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	24990
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	27252
k_VitesseVehicleBVRampValidThresh_Cnt_u16	1525
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	28751
k_VitesseVehicleBVSigValidThresh_Cnt_u16	30613
k_VitesseVehicleBVSpeedPassThresh_kph_f32	575.860291
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	42645
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	13326
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1465359360
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	13090
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1813852160
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	240
target_SrlComInput_Per1_Batt_Volt_f32.value	22.7206001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2741242880
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	14
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0352316871
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3918445568
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2408504320
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	534707200
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1652497408
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	527383552
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	130
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	514808832
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	675249152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	37
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	73
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	88
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	158
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	185
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	187
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	225
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	769661952
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	126
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	140
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	176
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	222
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	11
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4168203264
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3320962048
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1036123136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	58
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	109
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	121
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	138
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	140
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	178
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3046083584
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1418
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.591741085
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	113723
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	19.2889996
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	12176

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1813852160	1813852160	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	23293	23293	✔
BSINodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
CDD_SrlComVehSpd_Kph_G_f32	537.46167	537.46167	✔
CMM388NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	6292	6292	✔
CONSANGLECPK_HwDeg_M_f32	637.924988	637.924988 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1813852160	1813852160	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1813852160	1813852160	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1813852160	1813852160	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1813852160	1813852160	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1813852160	1813852160	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1813852160	1813852160	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1813852160	1813852160	✔
ESPNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2500	2500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3500	3500	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2323	2323	✔
ElecIntTimer_mS_M_u32[1]	45466	45466	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1813852160	1813852160	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	22919	22919	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	608	608	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	15538	15538	✔
ISDATBSI412MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	49918	49918	✔
ISDATBSI432MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATDIRASentFltAcc_Cnt_M_u16	31074	31074	✔
ISDATDIRASentTimer_mS_M_u32	1813852160	1813852160	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	48118	48118	✔
ISDYN2CMMMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	39903	39903	✔
ISDYNAASMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	6292	6292	✔
ISDYNABRMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	608	608	✔
ISDYNCMM208MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	11670	11670	✔
ISDYNCMM388MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	51359	51359	✔
ISDYNVOLMsgTimer_mS_M_u32	1813852160	1813852160	✔
IgnOnTimer_mS_M_u32	1128578048	1128578048	✔
IgnTimeOff_Sec_M_u32	2657862575	2657862575	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	135	135	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3918445568	3918445568	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	131	131	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2408504320	2408504320	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	133	133	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	534707200	534707200	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	86	86	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1652497408	1652497408	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3402365952	3402365952	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	130	130	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	514808832	514808832	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	675249152	675249152	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	152	152	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	769661952	769661952	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	11	11	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4168203264	4168203264	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	206	206	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3320962048	3320962048	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	88	88	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1036123136	1036123136	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3046083584	3046083584	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	197.014008	197.014008	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	242.279099	242.279099	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	519.426697	519.426697	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	6292	6292	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2657862575	2657862575	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	637.924988	637.924988 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.382 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3353739008
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	44982
AASNodeAbsentTimer_mS_M_u32	3295719168
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	19316
ANGLEVOLANTSigValidCount_Cnt_M_u16	43535
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	551
AngleVolantMsgTimer_mS_M_u32	3353739008
AngleVolantValidCount_Cnt_M_u16	517
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2003791616
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	789049088
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2884837120
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	224190208
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	25847
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2851970816
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	37903
CAVNodeAbsentTimer_mS_M_u32	1063374592
CDD_SrlComVehSpd_Kph_G_f32	314.092102
CMM388NTCEnableTimer_mS_M_u32	3021934336
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2345651968
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	433
CMMNodeAbsentTimer_mS_M_u32	292478720
CONSANGLECPKSigInvalidCount_Cnt_M_u16	60015
CONSANGLECPKSigValidCount_Cnt_M_u16	29593
CONSANGLECPK_Cnt_M_u16	8016
CONSANGLECPK_HwDeg_M_f32	451.418304
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	8016
CPKVehicleSpeedMsgTimer_mS_M_u32	2021719808
CPKVehicleSpeedValidCount_Cnt_M_u16	490
CityParkInputConsistentCount_Cnt_M_u16	3577
CityParkInputInvalidCount_Cnt_M_u16	45275
CityParkInputMsgTimer_mS_M_u32	3918445568
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3445927680
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	27050

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1395937024
ComputerRazGCTSigValidCount_Cnt_M_u16	40706
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	28903
DMDFCTCPKSigValidCount_Cnt_M_u16	57993
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	58478
DMDRELAXECPKSigValidCount_Cnt_M_u16	60041
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	63968
DateInvalidTimer_mS_M_u32	789049088
DiagMuxOnAbsentTimer_mS_M_u32	1525071616
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	224190208
ESPNTCEnableTimer_mS_M_u32	311799552
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	16439
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	102
EffacDefaultDiagTimer_mS_M_u32[1]	106
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	5656
ElecIntTimer_mS_M_u32[1]	78790
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	47685376
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	631
EtatMTSigValidCount_Cnt_M_u16	5421
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	61801
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	41491
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	37111
ISDAT4V2BSI552MsgTimer_mS_M_u32	2841829120
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	28870
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	6884
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	5421
ISDATBSI3F2MsgTimer_mS_M_u32	3421290240
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	31989
ISDATBSI412MsgLenValidCount_Cnt_M_u16	59395
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	631
ISDATBSI412MsgTimer_mS_M_u32	2532048640
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	26789
ISDATBSI432MsgLenValidCount_Cnt_M_u16	46635
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	53716
ISDATDIRASentFltAcc_Cnt_M_u16	19992
ISDATDIRASentTimer_mS_M_u32	2021719808
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	26838
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	517
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	47594
ISDYN2CMMMsgTimer_mS_M_u32	623357696
ISDYNAASChkSumInvalidCount_Cnt_M_u16	1200
ISDYNAASChkSumValidCount_Cnt_M_u16	49386
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	43272
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	60678
ISDYNAASMsgLenValidCount_Cnt_M_u16	13208
ISDYNAASMsgTimeValidCount_Cnt_M_u16	1200
ISDYNAASMsgTimer_mS_M_u32	757796608
ISDYNABRChkSumInvalidCount_Cnt_M_u16	37227
ISDYNABRChkSumValidCount_Cnt_M_u16	30062
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	14387
ISDYNABRMsgCountValidCount_Cnt_M_u16	41133
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	19698
ISDYNABRMsgLenValidCount_Cnt_M_u16	49756
ISDYNABRMsgTimeValidCount_Cnt_M_u16	8016
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	18718
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	56084
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	5421
ISDYNCMM208MsgTimer_mS_M_u32	1706585856
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	18718
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	56084
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	37899

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	147623680
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	62325
ISDYNVOLChkSumValidCount_Cnt_M_u16	21791
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	59629
ISDYNVOLMsgCountValidCount_Cnt_M_u16	29455
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	63412
ISDYNVOLMsgLenValidCount_Cnt_M_u16	830
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	433
ISDYNVOLMsgTimer_mS_M_u32	2822786816
IgnOnTimer_mS_M_u32	130060032
IgnTimeOff_Sec_M_u32	1168843291
ManVehSpd_Kph_M_f32	362.5513
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	204
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	39
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2679815936
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	159
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	30809856
PrevISDATBSI412MsgDLCError_Cnt_M_u08	140
PrevISDATBSI412MsgRxTime_MSec_M_u32	3068579584
PrevISDATBSI432MsgDLCError_Cnt_M_u08	17
PrevISDATBSI432MsgRxTime_MSec_M_u32	918138624
PrevISDATDIRAMsgTxTime_MSec_M_u32	2653605632
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	180
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2444779264
PrevISDYNAASMsgDLCError_Cnt_M_u08	114
PrevISDYNAASMsgRxTime_MSec_M_u32	1506168576
PrevISDYNABRMsgDLCError_Cnt_M_u08	16
PrevISDYNABRMsgRxTime_MSec_M_u32	953716480
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	174
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4220473088
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	108
PrevISDYNCMM388MsgRxTime_MSec_M_u32	863022848
PrevISDYNVOLMsgDLCError_Cnt_M_u08	241
PrevISDYNVOLMsgRxTime_MSec_M_u32	887607040
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2767322880
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	184.663803
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	49932
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	41502
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	13833
VitesseVehicleBVRampValidCount_Cnt_M_u16	18651
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	30193
VitesseVehicleBVSigValidCount_Cnt_M_u16	43084
VitesseVehicleBV_Kph_M_f32	251.410995
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	37899
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	11517
VitesseVehiculeRoues_Kph_M_f32	480.111206
k_AASNTCEnableTimeout_mS_u16	46891
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	39956
k_AASNodeTimeout_mS_u16	37150
k_ABSNodeTimeout_mS_u16	47600
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	49396
k_ANGLEVOLANTSigValidThresh_Cnt_u16	64442
k_AngleVolantInvalidThresh_Cnt_u16	35109
k_AngleVolantValidThresh_Cnt_u16	45275
k_BSI552MsgTimeout_mS_u16	15912
k_BSINTCEnableTimeout_mS_u16	51645
k_BSINodeAbsentDiag_Cnt_str.Threshold	60182
k_BSINodeAbsentDiag_Cnt_str.PStep	26076
k_BSINodeAbsentDiag_Cnt_str.NStep	19942
k_BSINodeAbsentTimeout_mS_u16	56639
k_BSINodeTimeout_mS_u16	53716
k_BattOvHi_Volt_f32	21.5820999
k_BattOvLo_Volt_f32	6.12820005
k_BattUvHi_Volt_f32	28.7229996
k_BattUvLo_Volt_f32	7.67959976
k_CAVNTCEnableTimeout_mS_u16	47097
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	45333
k_CAVNodeTimeout_mS_u16	15227
k_CMM388MsgTimeout_mS_u16	57014
k_CMM388NTCEnableTimeout_mS_u16	25794
k_CMMNTCEnableTimeout_mS_u16	7646
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	41225
k_CONSANGLECPKMax_HwDeg_f32	778.348389
k_CONSANGLECPKMin_HwDeg_f32	-492.896698
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	17163
k_CONSANGLECPKSigValidThresh_Cnt_u16	7165
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	34444
k_CPKVehicleSpeedValidThresh_Cnt_u16	23212
k_CityParkInputInvalidThresh_Cnt_u16	9561
k_CityParkInputValidThresh_Cnt_u16	3577
k_ComputerRazGCTSigValidThresh_Cnt_u16	59668
k_CptTemporelSigValidThresh_Cnt_u16	53682
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	31730
k_DMDFCTCPKSigValidThresh_Cnt_u16	12636
k_DMDFCTCPKValidCount_Cnt_u16	2271
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	47594
k_DMDRELAXECPKSigValidThresh_Cnt_u16	63436
k_DMDRelaxeConsistentThresh_Cnt_u16	7994
k_DateValidThresh_Cnt_u16	37111
k_DefaultVehSpd_Kph_f32	228.818802
k_DiagMuxOnAbsentTimeout_mS_u16	40430
k_EMNodeTimeout_mS_u16	61632
k_ESPNTCEnableTimeout_mS_u16	12059
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	59377
k_EtatMTSigInvalidThresh_Cnt_u16	26678
k_EtatMTSigValidThresh_Cnt_u16	24185
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	64931
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	45241
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	47862
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	19159
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	4021
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	33257
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	29238
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	31356
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	3993
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	6948
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	29395
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	5720
k_ISDATDIRASentDiag_Cnt_str.Threshold	16910

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	7039
k_ISDATDIRASentDiag_Cnt_str.NStep	21916
k_ISDATDIRASentTimeout_mS_u16	55415
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	47521
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	551
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	31735
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	16491
k_ISDYNAASChkSumValidThresh_Cnt_u16	25710
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	26419
k_ISDYNAASMsgCountValidThresh_Cnt_u16	4013
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	14687
k_ISDYNAASMsgLenValidThresh_Cnt_u16	54546
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	55458
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	3320
k_ISDYNABRChkSumValidThresh_Cnt_u16	39650
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	37879
k_ISDYNABRMsgCountValidThresh_Cnt_u16	24274
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	61617
k_ISDYNABRMsgLenValidThresh_Cnt_u16	28471
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	39805
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	9984
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	55346
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	50505
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	31348
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	6415
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	8179
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	8132
k_ISDYNVOLChkSumValidThresh_Cnt_u16	22546
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	32168
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	60514
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	22147
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	39481
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	661
k_IgnOnTimeout_mS_u16	43728
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	166.241196
k_PowerCutVehSpdLowThresh_Kph_f32	221.217804
k_PowerCutVehSpdLowTimeout_mS_u16	3559
k_VBattMaxAAS_Volt_f32	27.5991001
k_VBattMaxBSI_Volt_f32	7.38149977
k_VBattMaxCAV_Volt_f32	23.0881004
k_VBattMaxCMM388_Volt_f32	13.7268
k_VBattMaxCMM_Volt_f32	30.1622009
k_VBattMaxESP_Volt_f32	9.72329998
k_VBattMinAAS_Volt_f32	5.71029997
k_VBattMinBSI_Volt_f32	9.72329998
k_VBattMinCAV_Volt_f32	12.9560003
k_VBattMinCMM388_Volt_f32	13.4680996
k_VBattMinCMM_Volt_f32	14.6140003
k_VBattMinESP_Volt_f32	30.1622009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	39731
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	33905
k_VitesseVehicleBVRampValidThresh_Cnt_u16	38893
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	50207
k_VitesseVehicleBVSigValidThresh_Cnt_u16	29198
k_VitesseVehicleBVSpeedPassThresh_kph_f32	289.658691
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	17167
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	11873
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	789049088
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	54592
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	68495872
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	108
target_SrlComInput_Per1_Batt_Volt_f32.value	8.06410027
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1218617088
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	196
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.371021539
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3168964352
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1935814400
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2867973888
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	115
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	194080512
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1027673856
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3892358912
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	71
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3016773376
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	58
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	129
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	164
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	171
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	240
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1835953920
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	158
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	205
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3694759680
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	473509632
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	50
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2638794496
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	6
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	30
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	79
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	123
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	150
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	170
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	538976000
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3495
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.499410689
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	53623
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	60.6907005
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	21534

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	68495872	68495872	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	68495872	68495872	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	553	553	✔
AngleVolantMsgTimer_mS_M_u32	68495872	68495872	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	68495872	68495872	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	68495872	68495872	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	68495872	68495872	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	68495872	68495872	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	8016	8016	✔
CONSANGLECPK_HwDeg_M_f32	451.418304	451.418304 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	8016	8016	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2021719808	2021719808	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	490	490	✔
CityParkInputConsistentCount_Cnt_M_u16	3577	3577	✔
CityParkInputInvalidCount_Cnt_M_u16	45275	45275	✔
CityParkInputMsgTimer_mS_M_u32	68495872	68495872	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	68495872	68495872	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	68495872	68495872	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	68495872	68495872	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	68495872	68495872	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	68495872	68495872	✔
ESPNTCEnableTimer_mS_M_u32	68495872	68495872	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	102	102	✔
EffacDefaultDiagTimer_mS_M_u32[1]	106	106	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	68495872	68495872	✔
ElecIntTimer_mS_M_u32[1]	78790	78790	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	68495872	68495872	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATDIRASentFltAcc_Cnt_M_u16	16910	16910	✔
ISDATDIRASentTimer_mS_M_u32	68495872	68495872	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	68495872	68495872	✔
IgnOnTimer_mS_M_u32	68495872	68495872	✔
IgnTimeOff_Sec_M_u32	1168843291	1168843291	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3168964352	3168964352	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	26	26	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1935814400	1935814400	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	92	92	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2867973888	2867973888	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	115	115	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	194080512	194080512	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2653605632	2653605632	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	192	192	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3892358912	3892358912	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	71	71	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3016773376	3016773376	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	113	113	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1835953920	1835953920	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	200	200	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3694759680	3694759680	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	134	134	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	473509632	473509632	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	50	50	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2638794496	2638794496	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	538976000	538976000	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	184.663803	184.663803	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	251.410995	251.410995	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	480.111206	480.111206	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	8016	8016	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1168843291	1168843291	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	451.418304	451.418304 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	228.818802	228.818802	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.383 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2259207680
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	45367
AASNodeAbsentTimer_mS_M_u32	1472771584
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	63483
ANGLEVOLANTSigValidCount_Cnt_M_u16	16621
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	48612
AngleVolantMsgTimer_mS_M_u32	2259207680
AngleVolantValidCount_Cnt_M_u16	48331
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2848749056
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2231563776
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	4144064000
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2848204288
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	30578
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1189209600
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	20651
CAVNodeAbsentTimer_mS_M_u32	2473940480
CDD_SrlComVehSpd_Kph_G_f32	10.4540005
CMM388NTCEnableTimer_mS_M_u32	3124598272
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3861599744
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	39303
CMMNodeAbsentTimer_mS_M_u32	1703814656
CONSANGLECPKSigInvalidCount_Cnt_M_u16	30219
CONSANGLECPKSigValidCount_Cnt_M_u16	32588
CONSANGLECPK_Cnt_M_u16	6183
CONSANGLECPK_HwDeg_M_f32	444.142303
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	6183
CPKVehicleSpeedMsgTimer_mS_M_u32	2698495488
CPKVehicleSpeedValidCount_Cnt_M_u16	43618
CityParkInputConsistentCount_Cnt_M_u16	26863
CityParkInputInvalidCount_Cnt_M_u16	55624

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	3168964352
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	216839680
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	21339
ComputerRazGCTSigInvalidTimer_mS_M_u32	3254638080
ComputerRazGCTSigValidCount_Cnt_M_u16	6612
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	51492
DMDFCTCPKSigValidCount_Cnt_M_u16	63742
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	38157
DMDRELAXECPKSigValidCount_Cnt_M_u16	59263
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	19384
DateInvalidTimer_mS_M_u32	2231563776
DiagMuxOnAbsentTimer_mS_M_u32	3232138752
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2848204288
ESPNTCEnableTimer_mS_M_u32	1096398336
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	62133
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	89
EffacDefaultDiagTimer_mS_M_u32[1]	789
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	5
ElecIntTimer_mS_M_u32[1]	87789
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	609478144
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	32820
EtatMTSigValidCount_Cnt_M_u16	7378
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	51485
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	23518
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	9652
ISDAT4V2BSI552MsgTimer_mS_M_u32	1840391680
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	35016
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	65325
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	7378
ISDATBSI3F2MsgTimer_mS_M_u32	93619712
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	12602
ISDATBSI412MsgLenValidCount_Cnt_M_u16	9423
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	32820
ISDATBSI412MsgTimer_mS_M_u32	2979448320
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	13483
ISDATBSI432MsgLenValidCount_Cnt_M_u16	24793
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	60252
ISDATDIRASentFltAcc_Cnt_M_u16	34448
ISDATDIRASentTimer_mS_M_u32	2698495488
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	54165
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	48331
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	47643
ISDYN2CMMMsgTimer_mS_M_u32	3517167104
ISDYNAASChkSumInvalidCount_Cnt_M_u16	6729
ISDYNAASChkSumValidCount_Cnt_M_u16	51802
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	37826
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	57798
ISDYNAASMsgLenValidCount_Cnt_M_u16	21200
ISDYNAASMsgTimeValidCount_Cnt_M_u16	6729
ISDYNAASMsgTimer_mS_M_u32	2132383232
ISDYNABRChkSumInvalidCount_Cnt_M_u16	6551
ISDYNABRChkSumValidCount_Cnt_M_u16	29264
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	19392
ISDYNABRMsgCountValidCount_Cnt_M_u16	63249
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	6786
ISDYNABRMsgLenValidCount_Cnt_M_u16	24323
ISDYNABRMsgTimeValidCount_Cnt_M_u16	6183
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	2111
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	10013

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	7378
ISDYNCMM208MsgTimer_mS_M_u32	1123120640
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	2111
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	10013
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	40633
ISDYNCMM388MsgTimer_mS_M_u32	1379210752
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	62201
ISDYNVOLChkSumValidCount_Cnt_M_u16	29370
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	63762
ISDYNVOLMsgCountValidCount_Cnt_M_u16	57196
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	62
ISDYNVOLMsgLenValidCount_Cnt_M_u16	607
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	39303
ISDYNVOLMsgTimer_mS_M_u32	4074362368
IgnOnTimer_mS_M_u32	626595328
IgnTimeOff_Sec_M_u32	3123212984
ManVehSpd_Kph_M_f32	5.44589996
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	205
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	55
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1110083072
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	121
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1096312320
PrevISDATBSI412MsgDLCError_Cnt_M_u08	136
PrevISDATBSI412MsgRxTime_MSec_M_u32	2162578944
PrevISDATBSI432MsgDLCError_Cnt_M_u08	10
PrevISDATBSI432MsgRxTime_MSec_M_u32	1693300224
PrevISDATDIRAMsgTxTime_MSec_M_u32	3675936256
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	85
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3937510912
PrevISDYNAASMsgDLCError_Cnt_M_u08	234
PrevISDYNAASMsgRxTime_MSec_M_u32	1984419328
PrevISDYNABRMsgDLCError_Cnt_M_u08	211
PrevISDYNABRMsgRxTime_MSec_M_u32	4061206016
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	26
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4109161984
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	180
PrevISDYNCMM388MsgRxTime_MSec_M_u32	180925952
PrevISDYNVOLMsgDLCError_Cnt_M_u08	157
PrevISDYNVOLMsgRxTime_MSec_M_u32	1256412672
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	528795136
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	198.760101
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	63412
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	40766
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	53949
VitesseVehicleBVRampValidCount_Cnt_M_u16	57095
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	44164
VitesseVehicleBVSigValidCount_Cnt_M_u16	31286
VitesseVehicleBV_Kph_M_f32	47.2313995

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	40633
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	39074
VitesseVehiculeRoues_Kph_M_f32	118.741898
k_AASNTCEnableTimeout_mS_u16	31894
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	60062
k_AASNodeTimeout_mS_u16	53822
k_ABSNodeTimeout_mS_u16	21001
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	10174
k_ANGLEVOLANTSigValidThresh_Cnt_u16	35884
k_AngleVolantInvalidThresh_Cnt_u16	20459
k_AngleVolantValidThresh_Cnt_u16	55624
k_BSI552MsgTimeout_mS_u16	53537
k_BSINTCEnableTimeout_mS_u16	29027
k_BSINodeAbsentDiag_Cnt_str.Threshold	64470
k_BSINodeAbsentDiag_Cnt_str.PStep	42693
k_BSINodeAbsentDiag_Cnt_str.NStep	6631
k_BSINodeAbsentTimeout_mS_u16	35996
k_BSINodeTimeout_mS_u16	60252
k_BattOvHi_Volt_f32	19.8813
k_BattOvLo_Volt_f32	5.52759981
k_BattUvHi_Volt_f32	31.5
k_BattUvLo_Volt_f32	28.4857006
k_CAVNTCEnableTimeout_mS_u16	48110
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	37273
k_CAVNodeTimeout_mS_u16	45799
k_CMM388MsgTimeout_mS_u16	9271
k_CMM388NTCEnableTimeout_mS_u16	49683
k_CMMNTCEnableTimeout_mS_u16	57728
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	27774
k_CONSANGLECPKMax_HwDeg_f32	143.270798
k_CONSANGLECPKMin_HwDeg_f32	-27.1278
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	37305
k_CONSANGLECPKSigValidThresh_Cnt_u16	52130
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	10740
k_CPKVehicleSpeedValidThresh_Cnt_u16	13333
k_CityParkInputInvalidThresh_Cnt_u16	38349
k_CityParkInputValidThresh_Cnt_u16	26863
k_ComputerRazGCTSigValidThresh_Cnt_u16	55262
k_CptTemporelSigValidThresh_Cnt_u16	37571
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	36226
k_DMDFCTCPKSigValidThresh_Cnt_u16	4611
k_DMDFCTCPKValidCount_Cnt_u16	11194
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	47643
k_DMDRELAXECPKSigValidThresh_Cnt_u16	34101
k_DMDRelaxeConsistentThresh_Cnt_u16	18155
k_DateValidThresh_Cnt_u16	9652
k_DefaultVehSpd_Kph_f32	230.397995
k_DiagMuxOnAbsentTimeout_mS_u16	37965
k_EMNodeTimeout_mS_u16	59160
k_ESPNTCEnableTimeout_mS_u16	44935
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	14278
k_EtatMTSigInvalidThresh_Cnt_u16	33078
k_EtatMTSigValidThresh_Cnt_u16	41775
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	57519
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	7212
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	38392
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	32405
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	42170
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	62046
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	39928
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	38886

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	4047
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	29867
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	8801
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	528
k_ISDATDIRASentDiag_Cnt_str.Threshold	32887
k_ISDATDIRASentDiag_Cnt_str.PStep	20123
k_ISDATDIRASentDiag_Cnt_str.NStep	32507
k_ISDATDIRASentTimeout_mS_u16	29811
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	31797
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	48612
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	14579
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	3223
k_ISDYNAASChkSumValidThresh_Cnt_u16	42320
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	48832
k_ISDYNAASMsgCountValidThresh_Cnt_u16	43537
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	61883
k_ISDYNAASMsgLenValidThresh_Cnt_u16	54882
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	38260
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	29296
k_ISDYNABRChkSumValidThresh_Cnt_u16	28017
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	60018
k_ISDYNABRMsgCountValidThresh_Cnt_u16	61092
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	52359
k_ISDYNABRMsgLenValidThresh_Cnt_u16	26037
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	42147
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	39896
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	21379
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	41405
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	27387
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	62445
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	60416
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	17613
k_ISDYNVOLChkSumValidThresh_Cnt_u16	53410
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	15970
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	56692
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	46096
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	48558
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	51418
k_IgnOnTimeout_mS_u16	54185
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	250.630997
k_PowerCutVehSpdLowThresh_Kph_f32	189.701294
k_PowerCutVehSpdLowTimeout_mS_u16	26722
k_VBattMaxAAS_Volt_f32	27.3987999
k_VBattMaxBSI_Volt_f32	7.16289997
k_VBattMaxCAV_Volt_f32	10.2199001
k_VBattMaxCMM388_Volt_f32	19.2900009
k_VBattMaxCMM_Volt_f32	31.1819992
k_VBattMaxESP_Volt_f32	20.5370007
k_VBattMinAAS_Volt_f32	19.4274998
k_VBattMinBSI_Volt_f32	20.5370007
k_VBattMinCAV_Volt_f32	26.7910995
k_VBattMinCMM388_Volt_f32	18.6159
k_VBattMinCMM_Volt_f32	28.9389992
k_VBattMinESP_Volt_f32	31.1819992
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	40831
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	55429
k_VitesseVehicleBVRampValidThresh_Cnt_u16	60434
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	9658
k_VitesseVehicleBVSigValidThresh_Cnt_u16	53424
k_VitesseVehicleBVSpeedPassThresh_kph_f32	97.2141037
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	17323
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	50805
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2231563776
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	61417
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3632743680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	180

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	25.2894001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1056105984
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	151
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.124911316
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	234034688
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	112
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4042536448
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2428851712
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4117132800
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	651662848
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	150
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	756594176
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	271177216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	43
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	101
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	208
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2211411456
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	65
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	147
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	217
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	156
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3421378048
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	309278208
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3586151936
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	53
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	77
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	94
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	177
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	189
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2390386176
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	590
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.755048752
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	936988
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	151.532593
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	3198

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	48612	48612	✔
AngleVolantMsgTimer_mS_M_u32	3632743680	3632743680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	6183	6183	✔
CONSANGLECPK_HwDeg_M_f32	444.142303	444.142303 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	6183	6183	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2698495488	2698495488	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	43618	43618	✔
CityParkInputConsistentCount_Cnt_M_u16	26863	26863	✔
CityParkInputInvalidCount_Cnt_M_u16	55624	55624	✔
CityParkInputMsgTimer_mS_M_u32	3632743680	3632743680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3632743680	3632743680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3632743680	3632743680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3632743680	3632743680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3632743680	3632743680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3632743680	3632743680	✔
ESPNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	89	89	✔
EffacDefaultDiagTimer_mS_M_u32[1]	789	789	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	5	5	✔
ElecIntTimer_mS_M_u32[1]	87789	87789	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3632743680	3632743680	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	32887	32887	✔
ISDATDIRASentTimer_mS_M_u32	3632743680	3632743680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3632743680	3632743680	✔
IgnOnTimer_mS_M_u32	3632743680	3632743680	✔
IgnTimeOff_Sec_M_u32	3123212984	3123212984	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	200	200	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	234034688	234034688	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	112	112	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4042536448	4042536448	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	208	208	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2428851712	2428851712	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	241	241	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4117132800	4117132800	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3675936256	3675936256	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	150	150	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	756594176	756594176	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	271177216	271177216	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	173	173	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2211411456	2211411456	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	156	156	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3421378048	3421378048	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	72	72	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	309278208	309278208	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	107	107	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3586151936	3586151936	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2390386176	2390386176	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	198.760101	198.760101	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	47.2313995	47.2313995	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	118.741898	118.741898	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	6183	6183	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3123212984	3123212984	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	444.142303	444.142303 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.384 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2990305536
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	35984
AASNodeAbsentTimer_mS_M_u32	3936133376
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	27203
ANGLEVOLANTSigValidCount_Cnt_M_u16	24879
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	23177
AngleVolantMsgTimer_mS_M_u32	2990305536
AngleVolantValidCount_Cnt_M_u16	25172
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3012649216
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	468574464
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	196251904
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1852461312
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	34782
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1041305856
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	51379
CAVNodeAbsentTimer_mS_M_u32	840352000
CDD_SrlComVehSpd_Kph_G_f32	313.380493
CMM388NTCEnableTimer_mS_M_u32	784204032
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2448736512
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	14560
CMMNodeAbsentTimer_mS_M_u32	3809235200
CONSANGLECPKSigInvalidCount_Cnt_M_u16	57108
CONSANGLECPKSigValidCount_Cnt_M_u16	54543
CONSANGLECPK_Cnt_M_u16	13950
CONSANGLECPK_HwDeg_M_f32	-662.953491
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	13950
CPKVehicleSpeedMsgTimer_mS_M_u32	3752816896
CPKVehicleSpeedValidCount_Cnt_M_u16	61879

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	60904
CityParkInputInvalidCount_Cnt_M_u16	37340
CityParkInputMsgTimer_mS_M_u32	234034688
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1529913600
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	13860
ComputerRazGCTSigInvalidTimer_mS_M_u32	1753039104
ComputerRazGCTSigValidCount_Cnt_M_u16	44857
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	12872
DMDFCTCPKSigValidCount_Cnt_M_u16	5244
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	23309
DMDRELAXECPKSigValidCount_Cnt_M_u16	13689
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	21005
DateInvalidTimer_mS_M_u32	468574464
DiagMuxOnAbsentTimer_mS_M_u32	725823744
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1852461312
ESPNTCEnableTimer_mS_M_u32	2984878336
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	61207
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	56
EffacDefaultDiagTimer_mS_M_u32[1]	456
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2324
ElecIntTimer_mS_M_u32[1]	45466
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3988459776
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	51672
EtatMTSigValidCount_Cnt_M_u16	30143
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	44510
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1881
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	58970
ISDAT4V2BSI552MsgTimer_mS_M_u32	1520455936
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	46494
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	62509
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	30143
ISDATBSI3F2MsgTimer_mS_M_u32	2490970368
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	21831
ISDATBSI412MsgLenValidCount_Cnt_M_u16	56391
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	51672
ISDATBSI412MsgTimer_mS_M_u32	1769107712
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	63348
ISDATBSI432MsgLenValidCount_Cnt_M_u16	13483
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	64672
ISDATDIRASentFltAcc_Cnt_M_u16	64260
ISDATDIRASentTimer_mS_M_u32	3752816896
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	15412
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	25172
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	64355
ISDYN2CMMMsgTimer_mS_M_u32	2836111616
ISDYNAASChkSumInvalidCount_Cnt_M_u16	6490
ISDYNAASChkSumValidCount_Cnt_M_u16	23270
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	31087
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	16738
ISDYNAASMsgLenValidCount_Cnt_M_u16	8197
ISDYNAASMsgTimeValidCount_Cnt_M_u16	6490
ISDYNAASMsgTimer_mS_M_u32	1344930048
ISDYNABRChkSumInvalidCount_Cnt_M_u16	10993
ISDYNABRChkSumValidCount_Cnt_M_u16	4741
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	8437
ISDYNABRMsgCountValidCount_Cnt_M_u16	28865
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	36271
ISDYNABRMsgLenValidCount_Cnt_M_u16	53738
ISDYNABRMsgTimeValidCount_Cnt_M_u16	13950

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	7607
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	17118
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	30143
ISDYNCMM208MsgTimer_mS_M_u32	3156369664
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	7607
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	17118
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	62602
ISDYNCMM388MsgTimer_mS_M_u32	2765586688
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	41034
ISDYNVOLChkSumValidCount_Cnt_M_u16	12997
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	55934
ISDYNVOLMsgCountValidCount_Cnt_M_u16	39218
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	10876
ISDYNVOLMsgLenValidCount_Cnt_M_u16	46552
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	14560
ISDYNVOLMsgTimer_mS_M_u32	1172914432
IgnOnTimer_mS_M_u32	3144384768
IgnTimeOff_Sec_M_u32	2210245382
ManVehSpd_Kph_M_f32	563.635986
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	206
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	46
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3065458944
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	108
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1219334400
PrevISDATBSI412MsgDLCError_Cnt_M_u08	196
PrevISDATBSI412MsgRxTime_MSec_M_u32	1841545472
PrevISDATBSI432MsgDLCError_Cnt_M_u08	3
PrevISDATBSI432MsgRxTime_MSec_M_u32	2536349952
PrevISDATDIRAMsgTxTime_MSec_M_u32	791134464
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	141
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1101123840
PrevISDYNAASMsgDLCError_Cnt_M_u08	94
PrevISDYNAASMsgRxTime_MSec_M_u32	4087300352
PrevISDYNABRMsgDLCError_Cnt_M_u08	88
PrevISDYNABRMsgRxTime_MSec_M_u32	893616384
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	36
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1269842176
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	212
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3516702976
PrevISDYNVOLMsgDLCError_Cnt_M_u08	176
PrevISDYNVOLMsgRxTime_MSec_M_u32	1137492224
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1470656768
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	348.397705
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	14232
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	29371
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	2685
VitesseVehicleBVRampValidCount_Cnt_M_u16	5984
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	45224

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	6484
VitesseVehicleBV_Kph_M_f32	0.505800009
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	62602
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	47246
VitesseVehiculeRoues_Kph_M_f32	138.500595
k_AASNTCEnableTimeout_mS_u16	34097
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	58587
k_AASNodeTimeout_mS_u16	55739
k_ABSNodeTimeout_mS_u16	27545
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	10811
k_ANGLEVOLANTSigValidThresh_Cnt_u16	48818
k_AngleVolantInvalidThresh_Cnt_u16	12149
k_AngleVolantValidThresh_Cnt_u16	37340
k_BSI552MsgTimeout_mS_u16	51985
k_BSINTCEnableTimeout_mS_u16	8524
k_BSINodeAbsentDiag_Cnt_str.Threshold	46706
k_BSINodeAbsentDiag_Cnt_str.PStep	25574
k_BSINodeAbsentDiag_Cnt_str.NStep	35007
k_BSINodeAbsentTimeout_mS_u16	52833
k_BSINodeTimeout_mS_u16	64672
k_BattOvHi_Volt_f32	7.57310009
k_BattOvLo_Volt_f32	5.2803998
k_BattUvHi_Volt_f32	1.89020002
k_BattUvLo_Volt_f32	16.0690994
k_CAVNTCEnableTimeout_mS_u16	490
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	15849
k_CAVNodeTimeout_mS_u16	39040
k_CMM388MsgTimeout_mS_u16	13200
k_CMM388NTCEnableTimeout_mS_u16	51708
k_CMMNTCEnableTimeout_mS_u16	35702
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	44282
k_CONSANGLECPKMax_HwDeg_f32	632.512085
k_CONSANGLECPKMin_HwDeg_f32	-164.890701
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	7050
k_CONSANGLECPKSigValidThresh_Cnt_u16	8078
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	10905
k_CPKVehicleSpeedValidThresh_Cnt_u16	30902
k_CityParkInputInvalidThresh_Cnt_u16	3663
k_CityParkInputValidThresh_Cnt_u16	60904
k_ComputerRazGCTSigValidThresh_Cnt_u16	41052
k_CptTemporelSigValidThresh_Cnt_u16	4459
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	13487
k_DMDFCTCPKSigValidThresh_Cnt_u16	47338
k_DMDFCTCPKValidCount_Cnt_u16	35590
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	64355
k_DMDRELAXECPKSigValidThresh_Cnt_u16	3031
k_DMDRelaxeConsistentThresh_Cnt_u16	7861
k_DateValidThresh_Cnt_u16	58970
k_DefaultVehSpd_Kph_f32	111.519798
k_DiagMuxOnAbsentTimeout_mS_u16	55820
k_EMNodeTimeout_mS_u16	65517
k_ESPNTCEnableTimeout_mS_u16	7199
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	27426
k_EtatMTSigInvalidThresh_Cnt_u16	12308
k_EtatMTSigValidThresh_Cnt_u16	48104
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	45672
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	432
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	51917
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	18487
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	30598
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	41435

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	13709
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	900
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	62984
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	12530
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	2450
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	3012
k_ISDATDIRASentDiag_Cnt_str.Threshold	58484
k_ISDATDIRASentDiag_Cnt_str.PStep	41555
k_ISDATDIRASentDiag_Cnt_str.NStep	45799
k_ISDATDIRASentTimeout_mS_u16	35421
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	29013
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	23177
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	12251
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	20977
k_ISDYNAASChkSumValidThresh_Cnt_u16	31109
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	51189
k_ISDYNAASMsgCountValidThresh_Cnt_u16	22465
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	12933
k_ISDYNAASMsgLenValidThresh_Cnt_u16	23887
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	49882
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	48613
k_ISDYNABRChkSumValidThresh_Cnt_u16	56992
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	11998
k_ISDYNABRMsgCountValidThresh_Cnt_u16	62474
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	40928
k_ISDYNABRMsgLenValidThresh_Cnt_u16	38423
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	36365
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	56108
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	21100
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	10046
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	4419
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	18479
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	14772
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	9870
k_ISDYNVOLChkSumValidThresh_Cnt_u16	58574
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	16
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	24857
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	40516
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	811
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	5352
k_IgnOnTimeout_mS_u16	59898
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	41.3210983
k_PowerCutVehSpdLowThresh_Kph_f32	168.110107
k_PowerCutVehSpdLowTimeout_mS_u16	61901
k_VBattMaxAAS_Volt_f32	12.2549
k_VBattMaxBSI_Volt_f32	18.6287994
k_VBattMaxCAV_Volt_f32	23.9274998
k_VBattMaxCMM388_Volt_f32	20.7583008
k_VBattMaxCMM_Volt_f32	32
k_VBattMaxESP_Volt_f32	16.3080006
k_VBattMinAAS_Volt_f32	26.0820007
k_VBattMinBSI_Volt_f32	16.3080006
k_VBattMinCAV_Volt_f32	15.6893997
k_VBattMinCMM388_Volt_f32	27.1308994
k_VBattMinCMM_Volt_f32	20.8794994
k_VBattMinESP_Volt_f32	32
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	44919
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	9767
k_VitesseVehicleBVRampValidThresh_Cnt_u16	382
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	6597
k_VitesseVehicleBVSigValidThresh_Cnt_u16	64165
k_VitesseVehicleBVSpeedPassThresh_kph_f32	12.7196999
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	61363
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	39190
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	468574464
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	37067
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	810352896
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	0
target_SrlComInput_Per1_Batt_Volt_f32.value	27.8460999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3655209216
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	111
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.154026657
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	250
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3919413504
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	80
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	756687104
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	187
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2049360128
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	36
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3099812096
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3505389824
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2863440128
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	96
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	771309824
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	11
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	46
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	47
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	95
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	103
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	196
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4052246784
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	44
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	60
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	107
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1538031872
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1957241088
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	150
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1463140608
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	25
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	32
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	48
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	56
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	68
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	72
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	149
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1766297856
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3352
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.783120692
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	573634
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	49.8661995
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	41274

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	810352896	810352896	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	810352896	810352896	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	810352896	810352896	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	810352896	810352896	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	810352896	810352896	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	810352896	810352896	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	810352896	810352896	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	810352896	810352896	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	810352896	810352896	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	810352896	810352896	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	810352896	810352896	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	810352896	810352896	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	810352896	810352896	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	13950	13950	✔
CONSANGLECPK_HwDeg_M_f32	-662.953491	-662.953491 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	810352896	810352896	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	810352896	810352896	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	810352896	810352896	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	810352896	810352896	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	810352896	810352896	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	810352896	810352896	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	810352896	810352896	✔
ESPNTCEnableTimer_mS_M_u32	810352896	810352896	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	810352896	810352896	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	810352896	810352896	✔
EffacDefaultDiagTimer_mS_M_u32[1]	456	456	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	810352896	810352896	✔
ElecIntTimer_mS_M_u32[1]	45466	45466	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	810352896	810352896	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	810352896	810352896	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	810352896	810352896	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	810352896	810352896	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	810352896	810352896	✔
ISDATDIRASentFltAcc_Cnt_M_u16	58484	58484	✔
ISDATDIRASentTimer_mS_M_u32	810352896	810352896	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	810352896	810352896	✔
IgnOnTimer_mS_M_u32	810352896	810352896	✔
IgnTimeOff_Sec_M_u32	2210245382	2210245382	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	250	250	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3919413504	3919413504	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	80	80	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	756687104	756687104	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	187	187	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2049360128	2049360128	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	36	36	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3099812096	3099812096	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	791134464	791134464	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	143	143	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2863440128	2863440128	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	96	96	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	771309824	771309824	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	215	215	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4052246784	4052246784	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1538031872	1538031872	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	117	117	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1957241088	1957241088	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	150	150	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1463140608	1463140608	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1766297856	1766297856	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	348.397705	348.397705	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	0.505800009	0.505800009	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	138.500595	138.500595	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	13950	13950	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2210245382	2210245382	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-662.953491	-662.953491 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.385 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1743613952
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	51951
AASNodeAbsentTimer_mS_M_u32	3146571776
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	7128
ANGLEVOLANTSigValidCount_Cnt_M_u16	49621
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	34052
AngleVolantMsgTimer_mS_M_u32	1743613952
AngleVolantValidCount_Cnt_M_u16	24613
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	598646784
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	4237893632
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1544228864
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3269709824
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	61191
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1592758272
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	50953
CAVNodeAbsentTimer_mS_M_u32	4120805376
CDD_SrlComVehSpd_Kph_G_f32	203.033203
CMM388NTCEnableTimer_mS_M_u32	2896740352
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3456401408
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	38466
CMMNodeAbsentTimer_mS_M_u32	1828573184
CONSANGLECPKSigInvalidCount_Cnt_M_u16	61542
CONSANGLECPKSigValidCount_Cnt_M_u16	55603
CONSANGLECPK_Cnt_M_u16	12518
CONSANGLECPK_HwDeg_M_f32	484.042908
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	12518
CPKVehicleSpeedMsgTimer_mS_M_u32	1804890112
CPKVehicleSpeedValidCount_Cnt_M_u16	18819
CityParkInputConsistentCount_Cnt_M_u16	3433
CityParkInputInvalidCount_Cnt_M_u16	17036

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	3919413504
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3117473792
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	7731
ComputerRazGCTSigInvalidTimer_mS_M_u32	208338944
ComputerRazGCTSigValidCount_Cnt_M_u16	19830
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	4424
DMDFCTCPKSigValidCount_Cnt_M_u16	5485
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	61818
DMDRELAXECPKSigValidCount_Cnt_M_u16	60663
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	47995
DateInvalidTimer_mS_M_u32	4237893632
DiagMuxOnAbsentTimer_mS_M_u32	2279157760
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3269709824
ESPNTCEnableTimer_mS_M_u32	3651526656
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	11867
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	99
EffacDefaultDiagTimer_mS_M_u32[1]	759
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	565
ElecIntTimer_mS_M_u32[1]	78790
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2012319744
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	5210
EtatMTSigValidCount_Cnt_M_u16	35682
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	11272
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	59989
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	38867
ISDAT4V2BSI552MsgTimer_mS_M_u32	1447153664
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	16520
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	40857
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	35682
ISDATBSI3F2MsgTimer_mS_M_u32	2755080192
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	38540
ISDATBSI412MsgLenValidCount_Cnt_M_u16	56397
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	5210
ISDATBSI412MsgTimer_mS_M_u32	2588635136
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	43654
ISDATBSI432MsgLenValidCount_Cnt_M_u16	44447
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	8002
ISDATDIRASentFltAcc_Cnt_M_u16	46102
ISDATDIRASentTimer_mS_M_u32	1804890112
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	30660
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	24613
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	57847
ISDYN2CMMMsgTimer_mS_M_u32	4232044544
ISDYNAASChkSumInvalidCount_Cnt_M_u16	52369
ISDYNAASChkSumValidCount_Cnt_M_u16	4782
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	18132
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	55548
ISDYNAASMsgLenValidCount_Cnt_M_u16	42961
ISDYNAASMsgTimeValidCount_Cnt_M_u16	52369
ISDYNAASMsgTimer_mS_M_u32	4167352320
ISDYNABRChkSumInvalidCount_Cnt_M_u16	26958
ISDYNABRChkSumValidCount_Cnt_M_u16	56659
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	57792
ISDYNABRMsgCountValidCount_Cnt_M_u16	64797
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	4245
ISDYNABRMsgLenValidCount_Cnt_M_u16	3746
ISDYNABRMsgTimeValidCount_Cnt_M_u16	12518
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	21693
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	24581

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	35682
ISDYNCMM208MsgTimer_mS_M_u32	2382077952
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	21693
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	24581
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	387
ISDYNCMM388MsgTimer_mS_M_u32	2421964800
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	1220
ISDYNVOLChkSumValidCount_Cnt_M_u16	6161
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	28838
ISDYNVOLMsgCountValidCount_Cnt_M_u16	57163
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	20524
ISDYNVOLMsgLenValidCount_Cnt_M_u16	63705
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	38466
ISDYNVOLMsgTimer_mS_M_u32	606535680
IgnOnTimer_mS_M_u32	2627747840
IgnTimeOff_Sec_M_u32	1047628755
ManVehSpd_Kph_M_f32	59.2528
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	207
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	71
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3044880384
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	134
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1360662528
PrevISDATBSI412MsgDLCError_Cnt_M_u08	235
PrevISDATBSI412MsgRxTime_MSec_M_u32	915898368
PrevISDATBSI432MsgDLCError_Cnt_M_u08	223
PrevISDATBSI432MsgRxTime_MSec_M_u32	970579968
PrevISDATDIRAMsgTxTime_MSec_M_u32	2188083200
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	4
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2268942336
PrevISDYNAASMsgDLCError_Cnt_M_u08	217
PrevISDYNAASMsgRxTime_MSec_M_u32	1929707520
PrevISDYNABRMsgDLCError_Cnt_M_u08	205
PrevISDYNABRMsgRxTime_MSec_M_u32	2400731136
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	137
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4006739968
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	252
PrevISDYNCMM388MsgRxTime_MSec_M_u32	109895680
PrevISDYNVOLMsgDLCError_Cnt_M_u08	161
PrevISDYNVOLMsgRxTime_MSec_M_u32	410812416
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	665415680
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	267.194
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	20058
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	1967
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	43435
VitesseVehicleBVRampValidCount_Cnt_M_u16	60864
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	7337
VitesseVehicleBVSigValidCount_Cnt_M_u16	28006
VitesseVehicleBV_Kph_M_f32	436.604401

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	387
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	41016
VitesseVehiculeRoues_Kph_M_f32	277.720886
k_AASNTCEnableTimeout_mS_u16	53453
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	46224
k_AASNodeTimeout_mS_u16	53935
k_ABSNodeTimeout_mS_u16	59733
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	60977
k_ANGLEVOLANTSigValidThresh_Cnt_u16	60298
k_AngleVolantInvalidThresh_Cnt_u16	25921
k_AngleVolantValidThresh_Cnt_u16	17036
k_BSI552MsgTimeout_mS_u16	13487
k_BSINTCEnableTimeout_mS_u16	36094
k_BSINodeAbsentDiag_Cnt_str.Threshold	12298
k_BSINodeAbsentDiag_Cnt_str.PStep	7405
k_BSINodeAbsentDiag_Cnt_str.NStep	13221
k_BSINodeAbsentTimeout_mS_u16	35196
k_BSINodeTimeout_mS_u16	8002
k_BattOvHi_Volt_f32	13.448
k_BattOvLo_Volt_f32	26.3878994
k_BattUvHi_Volt_f32	5.42320013
k_BattUvLo_Volt_f32	15.0324001
k_CAVNTCEnableTimeout_mS_u16	43618
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	48999
k_CAVNodeTimeout_mS_u16	29730
k_CMM388MsgTimeout_mS_u16	54767
k_CMM388NTCEnableTimeout_mS_u16	49835
k_CMMNTCEnableTimeout_mS_u16	7936
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	29428
k_CONSANGLECPKMax_HwDeg_f32	630.450378
k_CONSANGLECPKMin_HwDeg_f32	-64.5456009
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	35971
k_CONSANGLECPKSigValidThresh_Cnt_u16	27448
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	55317
k_CPKVehicleSpeedValidThresh_Cnt_u16	43071
k_CityParkInputInvalidThresh_Cnt_u16	46900
k_CityParkInputValidThresh_Cnt_u16	3433
k_ComputerRazGCTSigValidThresh_Cnt_u16	63566
k_CptTemporelSigValidThresh_Cnt_u16	49119
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	7061
k_DMDFCTCPKSigValidThresh_Cnt_u16	22946
k_DMDFCTCPKValidCount_Cnt_u16	34191
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	57847
k_DMDRELAXECPKSigValidThresh_Cnt_u16	23388
k_DMDRelaxeConsistentThresh_Cnt_u16	6850
k_DateValidThresh_Cnt_u16	38867
k_DefaultVehSpd_Kph_f32	154.576401
k_DiagMuxOnAbsentTimeout_mS_u16	65084
k_EMNodeTimeout_mS_u16	12763
k_ESPNTCEnableTimeout_mS_u16	31941
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	55420
k_EtatMTSigInvalidThresh_Cnt_u16	42469
k_EtatMTSigValidThresh_Cnt_u16	11562
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	15528
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	18833
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	19130
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	11453
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	47502
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	208
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	37947
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	58644

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	65226
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	4490
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	57963
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	63508
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	64266
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	19297
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	34052
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	12689
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	62542
k_ISDYNAASChkSumValidThresh_Cnt_u16	43091
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	60608
k_ISDYNAASMsgCountValidThresh_Cnt_u16	18461
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	41618
k_ISDYNAASMsgLenValidThresh_Cnt_u16	38899
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	32530
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	55283
k_ISDYNABRChkSumValidThresh_Cnt_u16	16512
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	64007
k_ISDYNABRMsgCountValidThresh_Cnt_u16	13636
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	24898
k_ISDYNABRMsgLenValidThresh_Cnt_u16	14683
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	13115
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	45982
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	29469
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	46630
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	9944
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	3285
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	43780
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	65207
k_ISDYNVOLChkSumValidThresh_Cnt_u16	40632
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	8048
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	16791
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	18198
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	37662
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	50217
k_IgnOnTimeout_mS_u16	25715
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	137.672607
k_PowerCutVehSpdLowThresh_Kph_f32	181.305405
k_PowerCutVehSpdLowTimeout_mS_u16	64249
k_VBattMaxAAS_Volt_f32	20.3582001
k_VBattMaxBSI_Volt_f32	32
k_VBattMaxCAV_Volt_f32	5.93330002
k_VBattMaxCMM388_Volt_f32	9.3178997
k_VBattMaxCMM_Volt_f32	29.9150009
k_VBattMaxESP_Volt_f32	24.7956009
k_VBattMinAAS_Volt_f32	9.13770008
k_VBattMinBSI_Volt_f32	24.7956009
k_VBattMinCAV_Volt_f32	5.22079992
k_VBattMinCMM388_Volt_f32	10.1483002
k_VBattMinCMM_Volt_f32	20.7490005
k_VBattMinESP_Volt_f32	29.9150009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	39163
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	53164
k_VitesseVehicleBVRampValidThresh_Cnt_u16	64422
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	25361
k_VitesseVehicleBVSigValidThresh_Cnt_u16	6962
k_VitesseVehicleBVSpeedPassThresh_kph_f32	569.816406
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	21001
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	49310
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	4237893632
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16 Elaps	48464
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2751184896
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	255

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	31
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4287139840
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	99
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.711674452
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	96
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1510621184
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	122
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3390332928
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	146
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1567522816
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1545117696
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	236109824
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3143426048
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2885091328
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	12
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	71
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	80
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	98
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	194
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	232
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	47
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	97099776
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	40
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4292689920
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	7
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4016529408
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	255
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3259072512
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	33
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	146
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	185
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3612086272
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	771
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.420164675
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	591745
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	210.287094
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	6516

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2751184896	2751184896	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2751184896	2751184896	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	12298	12298	✔
BSINodeAbsentTimer_mS_M_u32	2751184896	2751184896	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2751184896	2751184896	✔
CDD_SrlComVehSpd_Kph_G_f32	59.2528	59.2528	✔
CMM388NTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2751184896	2751184896	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	12518	12518	✔
CONSANGLECPK_HwDeg_M_f32	484.042908	484.042908 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2751184896	2751184896	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2751184896	2751184896	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2751184896	2751184896	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2751184896	2751184896	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2751184896	2751184896	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2751184896	2751184896	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2751184896	2751184896	✔
ESPNTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2751184896	2751184896	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	99	99	✔
EffacDefaultDiagTimer_mS_M_u32[1]	759	759	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	565	565	✔
ElecIntTimer_mS_M_u32[1]	78790	78790	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2751184896	2751184896	✔
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	38867	38867	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	35682	35682	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	5210	5210	✔
ISDATBSI412MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	8002	8002	✔
ISDATBSI432MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11170	11170	✔
ISDATDIRASentTimer_mS_M_u32	2751184896	2751184896	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	57847	57847	✔
ISDYN2CMMMsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	52369	52369	✔
ISDYNAASMsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	12518	12518	✔
ISDYNABRMsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	35682	35682	✔
ISDYNCMM208MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	387	387	✔
ISDYNCMM388MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	38466	38466	✔
ISDYNVOLMsgTimer_mS_M_u32	2751184896	2751184896	✔
IgnOnTimer_mS_M_u32	2627747840	2627747840	✔
IgnTimeOff_Sec_M_u32	1047628755	1047628755	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	96	96	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1510621184	1510621184	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	122	122	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3390332928	3390332928	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	146	146	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1567522816	1567522816	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	242	242	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1545117696	1545117696	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2188083200	2188083200	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	168	168	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3143426048	3143426048	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	142	142	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2885091328	2885091328	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	47	47	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	97099776	97099776	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	206	206	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4292689920	4292689920	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	7	7	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4016529408	4016529408	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	255	255	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3259072512	3259072512	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3612086272	3612086272	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	267.194	267.194	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	436.604401	436.604401	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	277.720886	277.720886	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	12518	12518	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1047628755	1047628755	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	484.042908	484.042908 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	59.2528	59.2528	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.386 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1301705472
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	20110
AASNodeAbsentTimer_mS_M_u32	1551377152
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	40405
ANGLEVOLANTSigValidCount_Cnt_M_u16	2974
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	46159
AngleVolantMsgTimer_mS_M_u32	1301705472
AngleVolantValidCount_Cnt_M_u16	19311
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3675448064
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	441672448
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1874694912
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2385728256
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	41032
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2567967488
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	18626
CAVNodeAbsentTimer_mS_M_u32	2093171456
CDD_SrlComVehSpd_Kph_G_f32	559.032288
CMM388NTCEnableTimer_mS_M_u32	1352958720
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	194069248
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	31702
CMMNodeAbsentTimer_mS_M_u32	2011517696
CONSANGLECPKSigInvalidCount_Cnt_M_u16	34604
CONSANGLECPKSigValidCount_Cnt_M_u16	27781
CONSANGLECPK_Cnt_M_u16	61804
CONSANGLECPK_HwDeg_M_f32	-43.8863983
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	61804
CPKVehicleSpeedMsgTimer_mS_M_u32	2661380864
CPKVehicleSpeedValidCount_Cnt_M_u16	59580
CityParkInputConsistentCount_Cnt_M_u16	21411
CityParkInputInvalidCount_Cnt_M_u16	20793
CityParkInputMsgTimer_mS_M_u32	1510621184
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1907106560
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	25794

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	173916928
ComputerRazGCTSigValidCount_Cnt_M_u16	1916
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	54533
DMDFCTCPKSigValidCount_Cnt_M_u16	51287
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	9455
DMDRELAXECPKSigValidCount_Cnt_M_u16	37432
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	47597
DateInvalidTimer_mS_M_u32	441672448
DiagMuxOnAbsentTimer_mS_M_u32	1288909568
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2385728256
ESPNTCEnableTimer_mS_M_u32	2787975936
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	33611
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1121
EffacDefaultDiagTimer_mS_M_u32[1]	2235
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1234
ElecIntTimer_mS_M_u32[1]	23647
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3590984448
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	28304
EtatMTSigValidCount_Cnt_M_u16	39221
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	56390
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	16671
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	22821
ISDAT4V2BSI552MsgTimer_mS_M_u32	3424211712
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	7045
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	44562
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	39221
ISDATBSI3F2MsgTimer_mS_M_u32	4021891840
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	31352
ISDATBSI412MsgLenValidCount_Cnt_M_u16	6390
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	28304
ISDATBSI412MsgTimer_mS_M_u32	2927391488
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	20234
ISDATBSI432MsgLenValidCount_Cnt_M_u16	5503
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	25623
ISDATDIRASentFltAcc_Cnt_M_u16	62875
ISDATDIRASentTimer_mS_M_u32	2661380864
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	5330
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	19311
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	57080
ISDYN2CMMMsgTimer_mS_M_u32	643769088
ISDYNAASChkSumInvalidCount_Cnt_M_u16	20904
ISDYNAASChkSumValidCount_Cnt_M_u16	24338
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	4962
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	40681
ISDYNAASMsgLenValidCount_Cnt_M_u16	61994
ISDYNAASMsgTimeValidCount_Cnt_M_u16	20904
ISDYNAASMsgTimer_mS_M_u32	1567654656
ISDYNABRChkSumInvalidCount_Cnt_M_u16	1778
ISDYNABRChkSumValidCount_Cnt_M_u16	10915
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	36379
ISDYNABRMsgCountValidCount_Cnt_M_u16	7109
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	41631
ISDYNABRMsgLenValidCount_Cnt_M_u16	18488
ISDYNABRMsgTimeValidCount_Cnt_M_u16	61804
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	63847
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	26444
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	39221
ISDYNCMM208MsgTimer_mS_M_u32	271311616
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	63847
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	26444
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	24405

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3549037312
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	16914
ISDYNVOLChkSumValidCount_Cnt_M_u16	42987
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	44779
ISDYNVOLMsgCountValidCount_Cnt_M_u16	25277
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	41432
ISDYNVOLMsgLenValidCount_Cnt_M_u16	51089
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	31702
ISDYNVOLMsgTimer_mS_M_u32	3005858560
IgnOnTimer_mS_M_u32	3200123648
IgnTimeOff_Sec_M_u32	2504137934
ManVehSpd_Kph_M_f32	482.094299
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	208
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	176
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1407660800
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	14
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2358285056
PrevISDATBSI412MsgDLCError_Cnt_M_u08	142
PrevISDATBSI412MsgRxTime_MSec_M_u32	3721937664
PrevISDATBSI432MsgDLCError_Cnt_M_u08	166
PrevISDATBSI432MsgRxTime_MSec_M_u32	1435575040
PrevISDATDIRAMsgTxTime_MSec_M_u32	1247560448
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	240
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2267468544
PrevISDYNAASMsgDLCError_Cnt_M_u08	149
PrevISDYNAASMsgRxTime_MSec_M_u32	3197092608
PrevISDYNABRMsgDLCError_Cnt_M_u08	20
PrevISDYNABRMsgRxTime_MSec_M_u32	3344302848
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	129
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3207119616
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	163
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2071470848
PrevISDYNVOLMsgDLCError_Cnt_M_u08	5
PrevISDYNVOLMsgRxTime_MSec_M_u32	204030720
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4267864832
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	515.252014
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	14031
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	51856
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	43228
VitesseVehicleBVRampValidCount_Cnt_M_u16	40029
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	8034
VitesseVehicleBVSigValidCount_Cnt_M_u16	36075
VitesseVehicleBV_Kph_M_f32	4.45679998
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	24405
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	49910
VitesseVehiculeRoues_Kph_M_f32	372.144501
k_AASNTCEnableTimeout_mS_u16	28087
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	47662
k_AASNodeTimeout_mS_u16	27024
k_ABSNodeTimeout_mS_u16	49374
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	61449
k_ANGLEVOLANTSigValidThresh_Cnt_u16	51134
k_AngleVolantInvalidThresh_Cnt_u16	63129
k_AngleVolantValidThresh_Cnt_u16	20793
k_BSI552MsgTimeout_mS_u16	41361
k_BSINTCEnableTimeout_mS_u16	34722
k_BSINodeAbsentDiag_Cnt_str.Threshold	30462
k_BSINodeAbsentDiag_Cnt_str.PStep	53396
k_BSINodeAbsentDiag_Cnt_str.NStep	64687
k_BSINodeAbsentTimeout_mS_u16	34535
k_BSINodeTimeout_mS_u16	25623
k_BattOvHi_Volt_f32	13.8168001
k_BattOvLo_Volt_f32	21.8111
k_BattUvHi_Volt_f32	15.6107998
k_BattUvLo_Volt_f32	25.3451996
k_CAVNTCEnableTimeout_mS_u16	61879
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	22440
k_CAVNodeTimeout_mS_u16	60408
k_CMM388MsgTimeout_mS_u16	11662
k_CMM388NTCEnableTimeout_mS_u16	22362
k_CMMNTCEnableTimeout_mS_u16	24605
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	15042
k_CONSANGLECPKMax_HwDeg_f32	681.586792
k_CONSANGLECPKMin_HwDeg_f32	-451.812988
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	48725
k_CONSANGLECPKSigValidThresh_Cnt_u16	25078
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	29022
k_CPKVehicleSpeedValidThresh_Cnt_u16	53599
k_CityParkInputInvalidThresh_Cnt_u16	13632
k_CityParkInputValidThresh_Cnt_u16	21411
k_ComputerRazGCTSigValidThresh_Cnt_u16	35891
k_CptTemporelSigValidThresh_Cnt_u16	58688
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	33183
k_DMDFCTCPKSigValidThresh_Cnt_u16	26424
k_DMDFCTCPKValidCount_Cnt_u16	64688
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	57080
k_DMDRELAXECPKSigValidThresh_Cnt_u16	29322
k_DMDRelaxeConsistentThresh_Cnt_u16	19544
k_DateValidThresh_Cnt_u16	22821
k_DefaultVehSpd_Kph_f32	118.1409
k_DiagMuxOnAbsentTimeout_mS_u16	24938
k_EMNodeTimeout_mS_u16	54989
k_ESPNTCEnableTimeout_mS_u16	6030
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	10794
k_EtatMTSigInvalidThresh_Cnt_u16	27949
k_EtatMTSigValidThresh_Cnt_u16	22302
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	20389
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	14506
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	8112
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	27366
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	29747
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	19372
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	42475
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	33568
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	25150
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	57216
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	23709
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	50912
k_ISDATDIRASentDiag_Cnt_str.Threshold	6549

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	63930
k_ISDATDIRASentDiag_Cnt_str.NStep	24627
k_ISDATDIRASentTimeout_mS_u16	16830
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	16633
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	46159
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10538
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	26098
k_ISDYNAASChkSumValidThresh_Cnt_u16	51619
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	27931
k_ISDYNAASMsgCountValidThresh_Cnt_u16	15045
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	27430
k_ISDYNAASMsgLenValidThresh_Cnt_u16	10692
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	11558
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	17541
k_ISDYNABRChkSumValidThresh_Cnt_u16	43678
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	32584
k_ISDYNABRMsgCountValidThresh_Cnt_u16	11601
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	6870
k_ISDYNABRMsgLenValidThresh_Cnt_u16	25163
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	53100
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	5891
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	26821
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	23339
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	31957
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	10910
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	63441
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	44535
k_ISDYNVOLChkSumValidThresh_Cnt_u16	15797
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	17420
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	3543
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	50780
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	29185
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	44067
k_IgnOnTimeout_mS_u16	27843
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	83.3523026
k_PowerCutVehSpdLowThresh_Kph_f32	216.453903
k_PowerCutVehSpdLowTimeout_mS_u16	40755
k_VBattMaxAAS_Volt_f32	31.7213001
k_VBattMaxBSI_Volt_f32	2.07439995
k_VBattMaxCAV_Volt_f32	13.2173996
k_VBattMaxCMM388_Volt_f32	21.4326992
k_VBattMaxCMM_Volt_f32	23.2891006
k_VBattMaxESP_Volt_f32	1.61899996
k_VBattMinAAS_Volt_f32	7.60029984
k_VBattMinBSI_Volt_f32	1.61899996
k_VBattMinCAV_Volt_f32	25.6352997
k_VBattMinCMM388_Volt_f32	25.0970993
k_VBattMinCMM_Volt_f32	17.7548008
k_VBattMinESP_Volt_f32	23.2891006
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	16427
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	52184
k_VitesseVehicleBVRampValidThresh_Cnt_u16	3563
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	50923
k_VitesseVehicleBVSigValidThresh_Cnt_u16	36424
k_VitesseVehicleBVSpeedPassThresh_kph_f32	407.939789
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	42946
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	7107
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	441672448
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	163
target_SrlComInput_Per1_Batt_Volt_f32.value	8.67280006
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1531253504
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	191
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.420324922
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	234
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2927624960
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	78
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2934022912
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	244
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2236826368
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1507123968
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1416004352
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	4
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2634556160
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1538900736
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	62
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	64
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	76
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	84
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	153
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	177
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	204
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1623319296
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	93
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	167
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	187
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	171
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3372679936
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	177
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1256760064
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	185
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1658471168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	37
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	85
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	105
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	130
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	156
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	174
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1106940672
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3584
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.872469425
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	975387
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	82.7587967
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	48513

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	30462	30462	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	482.094299	482.094299	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	61804	61804	✔
CONSANGLECPK_HwDeg_M_f32	-43.8863983	-43.8863983 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1713429248	1713429248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1121	1121	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2235	2235	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1234	1234	✔
ElecIntTimer_mS_M_u32[1]	23647	23647	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	22821	22821	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	39221	39221	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	28304	28304	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	25623	25623	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	6549	6549	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	57080	57080	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	20904	20904	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	61804	61804	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	39221	39221	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	24405	24405	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	31702	31702	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	3200123648	3200123648	✔
IgnTimeOff_Sec_M_u32	2504137934	2504137934	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	234	234	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2927624960	2927624960	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	78	78	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2934022912	2934022912	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	244	244	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2236826368	2236826368	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	5	5	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1507123968	1507123968	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1247560448	1247560448	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	4	4	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2634556160	2634556160	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	67	67	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1538900736	1538900736	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	83	83	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1623319296	1623319296	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	171	171	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3372679936	3372679936	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	177	177	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1256760064	1256760064	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	185	185	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1658471168	1658471168	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1106940672	1106940672	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	515.252014	515.252014	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	4.45679998	4.45679998	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	372.144501	372.144501	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	61804	61804	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2504137934	2504137934	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-43.8863983	-43.8863983 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.387 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2020043264
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	63357
AASNodeAbsentTimer_mS_M_u32	780294656
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	17322
ANGLEVOLANTSigValidCount_Cnt_M_u16	56078
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	2618
AngleVolantMsgTimer_mS_M_u32	2020043264
AngleVolantValidCount_Cnt_M_u16	52060
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2377259520
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1911593472
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	376572416
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3255880192
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	51281
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	75139584
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	15716
CAVNodeAbsentTimer_mS_M_u32	1646328320
CDD_SrlComVehSpd_Kph_G_f32	31.4818001
CMM388NTCEnableTimer_mS_M_u32	4219288064
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1840708096
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	49639
CMMNodeAbsentTimer_mS_M_u32	1291504128
CONSANGLECPKSigInvalidCount_Cnt_M_u16	21158
CONSANGLECPKSigValidCount_Cnt_M_u16	50010
CONSANGLECPK_Cnt_M_u16	37029
CONSANGLECPK_HwDeg_M_f32	508.159088
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37029
CPKVehicleSpeedMsgTimer_mS_M_u32	1900440064
CPKVehicleSpeedValidCount_Cnt_M_u16	34620
CityParkInputConsistentCount_Cnt_M_u16	33472
CityParkInputInvalidCount_Cnt_M_u16	45821
CityParkInputMsgTimer_mS_M_u32	2927624960
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3202767360
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	34017

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1129413120
ComputerRazGCTSigValidCount_Cnt_M_u16	2869
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	22425
DMDFCTCPKSigValidCount_Cnt_M_u16	32357
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	38492
DMDRELAXECPKSigValidCount_Cnt_M_u16	12096
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	65123
DateInvalidTimer_mS_M_u32	1911593472
DiagMuxOnAbsentTimer_mS_M_u32	1571891712
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3255880192
ESPNTCEnableTimer_mS_M_u32	1701009920
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	15431
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	41
EffacDefaultDiagTimer_mS_M_u32[1]	46
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	6448
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3045886464
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	41656
EtatMTSigValidCount_Cnt_M_u16	29576
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	15192
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	11660
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	33787
ISDAT4V2BSI552MsgTimer_mS_M_u32	543083008
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1881
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	16498
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	29576
ISDATBSI3F2MsgTimer_mS_M_u32	2365532672
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	51072
ISDATBSI412MsgLenValidCount_Cnt_M_u16	40136
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	41656
ISDATBSI412MsgTimer_mS_M_u32	1840605696
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	6219
ISDATBSI432MsgLenValidCount_Cnt_M_u16	21931
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	32613
ISDATDIRASentFltAcc_Cnt_M_u16	56025
ISDATDIRASentTimer_mS_M_u32	1900440064
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	15987
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	52060
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	50624
ISDYN2CMMMsgTimer_mS_M_u32	751655424
ISDYNAASChkSumInvalidCount_Cnt_M_u16	54831
ISDYNAASChkSumValidCount_Cnt_M_u16	3764
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	65411
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	38639
ISDYNAASMsgLenValidCount_Cnt_M_u16	24043
ISDYNAASMsgTimeValidCount_Cnt_M_u16	54831
ISDYNAASMsgTimer_mS_M_u32	85539328
ISDYNABRChkSumInvalidCount_Cnt_M_u16	5075
ISDYNABRChkSumValidCount_Cnt_M_u16	10624
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	44246
ISDYNABRMsgCountValidCount_Cnt_M_u16	25755
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	35917
ISDYNABRMsgLenValidCount_Cnt_M_u16	48193
ISDYNABRMsgTimeValidCount_Cnt_M_u16	37029
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	7731
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	9539
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	29576
ISDYNCMM208MsgTimer_mS_M_u32	2456230400
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	7731
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	9539
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	42922

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3905731072
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	14836
ISDYNVOLChkSumValidCount_Cnt_M_u16	10536
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	57831
ISDYNVOLMsgCountValidCount_Cnt_M_u16	50995
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	21664
ISDYNVOLMsgLenValidCount_Cnt_M_u16	33845
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	49639
ISDYNVOLMsgTimer_mS_M_u32	2028829184
IgnOnTimer_mS_M_u32	4147165696
IgnTimeOff_Sec_M_u32	844425504
ManVehSpd_Kph_M_f32	474.452606
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	210
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	71
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2557815296
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	229
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3422095872
PrevISDATBSI412MsgDLCError_Cnt_M_u08	78
PrevISDATBSI412MsgRxTime_MSec_M_u32	3538024960
PrevISDATBSI432MsgDLCError_Cnt_M_u08	51
PrevISDATBSI432MsgRxTime_MSec_M_u32	3879164416
PrevISDATDIRAMsgTxTime_MSec_M_u32	2639657472
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	40
PrevISDYN2CMMMsgRxTime_MSec_M_u32	87443968
PrevISDYNAASMsgDLCError_Cnt_M_u08	202
PrevISDYNAASMsgRxTime_MSec_M_u32	1857780224
PrevISDYNABRMsgDLCError_Cnt_M_u08	60
PrevISDYNABRMsgRxTime_MSec_M_u32	1030273536
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	23
PrevISDYNCMM208MsgRxTime_MSec_M_u32	284195328
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	61
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3514980864
PrevISDYNVOLMsgDLCError_Cnt_M_u08	35
PrevISDYNVOLMsgRxTime_MSec_M_u32	3421436416
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2516806144
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	373.056793
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	59197
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	60601
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	1302
VitesseVehicleBVRampValidCount_Cnt_M_u16	60242
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	13059
VitesseVehicleBVSigValidCount_Cnt_M_u16	52007
VitesseVehicleBV_Kph_M_f32	600.453796
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	42922
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	48518
VitesseVehiculeRoues_Kph_M_f32	480.618591
k_AASNTCEnableTimeout_mS_u16	1988
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	15135
k_AASNodeTimeout_mS_u16	4025
k_ABSNodeTimeout_mS_u16	14350
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	61774
k_ANGLEVOLANTSigValidThresh_Cnt_u16	64238
k_AngleVolantInvalidThresh_Cnt_u16	39517
k_AngleVolantValidThresh_Cnt_u16	45821
k_BSI552MsgTimeout_mS_u16	19893
k_BSINTCEnableTimeout_mS_u16	52867
k_BSINodeAbsentDiag_Cnt_str.Threshold	30448
k_BSINodeAbsentDiag_Cnt_str.PStep	2411
k_BSINodeAbsentDiag_Cnt_str.NStep	13403
k_BSINodeAbsentTimeout_mS_u16	62066
k_BSINodeTimeout_mS_u16	32613
k_BattOvHi_Volt_f32	21.6982002
k_BattOvLo_Volt_f32	19.7733994
k_BattUvHi_Volt_f32	18.1569996
k_BattUvLo_Volt_f32	3.26789999
k_CAVNTCEnableTimeout_mS_u16	18819
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	10418
k_CAVNodeTimeout_mS_u16	21570
k_CMM388MsgTimeout_mS_u16	23165
k_CMM388NTCEnableTimeout_mS_u16	3353
k_CMMNTCEnableTimeout_mS_u16	39313
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	34338
k_CONSANGLECPKMax_HwDeg_f32	344.510803
k_CONSANGLECPKMin_HwDeg_f32	-642.126709
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	35498
k_CONSANGLECPKSigValidThresh_Cnt_u16	57478
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	45135
k_CPKVehicleSpeedValidThresh_Cnt_u16	7883
k_CityParkInputInvalidThresh_Cnt_u16	16617
k_CityParkInputValidThresh_Cnt_u16	33472
k_ComputerRazGCTSigValidThresh_Cnt_u16	60751
k_CptTemporelSigValidThresh_Cnt_u16	53992
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	61261
k_DMDFCTCPKSigValidThresh_Cnt_u16	24385
k_DMDFCTCPKValidCount_Cnt_u16	21273
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	50624
k_DMDRELAXECPKSigValidThresh_Cnt_u16	3020
k_DMDRelaxeConsistentThresh_Cnt_u16	13922
k_DateValidThresh_Cnt_u16	33787
k_DefaultVehSpd_Kph_f32	189.244293
k_DiagMuxOnAbsentTimeout_mS_u16	47275
k_EMNodeTimeout_mS_u16	10179
k_ESPNTCEnableTimeout_mS_u16	256
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	22506
k_EtatMTSigInvalidThresh_Cnt_u16	36130
k_EtatMTSigValidThresh_Cnt_u16	20495
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	61818
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	1835
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	37529
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	56630
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	45583
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	9188
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	55208
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	53448
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	44719
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	5737
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	53202
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	36682
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	37743
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	50431
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	2618
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	15404
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	63187
k_ISDYNAASChkSumValidThresh_Cnt_u16	19584
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	4054
k_ISDYNAASMsgCountValidThresh_Cnt_u16	1947
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	46903
k_ISDYNAASMsgLenValidThresh_Cnt_u16	40733
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	27318
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	48795
k_ISDYNABRChkSumValidThresh_Cnt_u16	44303
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	11089
k_ISDYNABRMsgCountValidThresh_Cnt_u16	501
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	58599
k_ISDYNABRMsgLenValidThresh_Cnt_u16	40775
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	18340
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	5793
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	28825
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	26344
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	42666
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	32270
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	7989
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	59651
k_ISDYNVOLChkSumValidThresh_Cnt_u16	60043
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	15876
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	20452
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	52052
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	6436
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	769
k_IgnOnTimeout_mS_u16	56479
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	38.1100006
k_PowerCutVehSpdLowThresh_Kph_f32	126.805298
k_PowerCutVehSpdLowTimeout_mS_u16	25424
k_VBattMaxAAS_Volt_f32	20.5510006
k_VBattMaxBSI_Volt_f32	25.5091991
k_VBattMaxCAV_Volt_f32	30.3976002
k_VBattMaxCMM388_Volt_f32	16.6441994
k_VBattMaxCMM_Volt_f32	18.1326008
k_VBattMaxESP_Volt_f32	29.2280006
k_VBattMinAAS_Volt_f32	2.26060009
k_VBattMinBSI_Volt_f32	29.2280006
k_VBattMinCAV_Volt_f32	28.3031006
k_VBattMinCMM388_Volt_f32	20.1853008
k_VBattMinCMM_Volt_f32	1.83220005
k_VBattMinESP_Volt_f32	18.1326008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	3945
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	56609
k_VitesseVehicleBVRampValidThresh_Cnt_u16	50407
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	52264
k_VitesseVehicleBVSigValidThresh_Cnt_u16	42705
k_VitesseVehicleBVSpeedPassThresh_kph_f32	262.347107
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	8292
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	34080
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1911593472
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	61
target_SrlComInput_Per1_Batt_Volt_f32.value	14.8150997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3520825856
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	244
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.981748104
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	13
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2951395840
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	207
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3175471616
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	10
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2289105408
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	71
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2573998592
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2016885248
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	231
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2899466752
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	89
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3208477184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	54
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	107
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	121
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	225
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	79
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2024086016
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	59
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	77
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	210
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	219
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	233
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1012251136
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3308313088
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3420191232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	71
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3552250368
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2766
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.549261332
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	446511
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	156.140503
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	39719

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2620	2620	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	37029	37029	✔
CONSANGLECPK_HwDeg_M_f32	508.159088	508.159088 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37029	37029	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1900440064	1900440064	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	34620	34620	✔
CityParkInputConsistentCount_Cnt_M_u16	33472	33472	✔
CityParkInputInvalidCount_Cnt_M_u16	45821	45821	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	41	41	✔
EffacDefaultDiagTimer_mS_M_u32[1]	46	46	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	65	65	✔
ElecIntTimer_mS_M_u32[1]	6448	6448	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	41895	41895	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	4147165696	4147165696	✔
IgnTimeOff_Sec_M_u32	844425504	844425504	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2951395840	2951395840	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	207	207	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3175471616	3175471616	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	10	10	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2289105408	2289105408	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	71	71	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2573998592	2573998592	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2639657472	2639657472	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	231	231	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2899466752	2899466752	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	89	89	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3208477184	3208477184	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	79	79	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2024086016	2024086016	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1012251136	1012251136	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	129	129	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3308313088	3308313088	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	152	152	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3420191232	3420191232	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3552250368	3552250368	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	373.056793	373.056793	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	600.453796	600.453796	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	480.618591	480.618591	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	37029	37029	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	844425504	844425504	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	508.159088	508.159088 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.388 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2492499200
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	37197
AASNodeAbsentTimer_mS_M_u32	3388978432
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	65223
ANGLEVOLANTSigValidCount_Cnt_M_u16	38490
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	36118
AngleVolantMsgTimer_mS_M_u32	2492499200
AngleVolantValidCount_Cnt_M_u16	46642
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	460354816
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2293560576
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2901452032
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2501141760
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	52434
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2765563136
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	8729
CAVNodeAbsentTimer_mS_M_u32	1906562304
CDD_SrlComVehSpd_Kph_G_f32	115.8563
CMM388NTCEnableTimer_mS_M_u32	1720653056
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	652334336
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	15185
CMMNodeAbsentTimer_mS_M_u32	475424000
CONSANGLECPKSigInvalidCount_Cnt_M_u16	28884
CONSANGLECPKSigValidCount_Cnt_M_u16	48246
CONSANGLECPK_Cnt_M_u16	16533
CONSANGLECPK_HwDeg_M_f32	678.937683
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	16533
CPKVehicleSpeedMsgTimer_mS_M_u32	3857941760
CPKVehicleSpeedValidCount_Cnt_M_u16	59194
CityParkInputConsistentCount_Cnt_M_u16	8198
CityParkInputInvalidCount_Cnt_M_u16	5198
CityParkInputMsgTimer_mS_M_u32	2951395840
CityParkInputValidCount_Cnt_M_u16	5

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2832446720
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	31009
ComputerRazGCTSigInvalidTimer_mS_M_u32	806507776
ComputerRazGCTSigValidCount_Cnt_M_u16	39591
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	38522
DMDFCTCPKSigValidCount_Cnt_M_u16	8149
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	20145
DMDRELAXECPKSigValidCount_Cnt_M_u16	57796
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	41373
DateInvalidTimer_mS_M_u32	2293560576
DiagMuxOnAbsentTimer_mS_M_u32	1001604352
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2501141760
ESPNTCEnableTimer_mS_M_u32	3915166976
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	6639
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	3
EffacDefaultDiagTimer_mS_M_u32[1]	6
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	56565
ElecIntTimer_mS_M_u32[1]	787881
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1503732992
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	28125
EtatMTSigValidCount_Cnt_M_u16	2348
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	65214
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	50656
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	59155
ISDAT4V2BSI552MsgTimer_mS_M_u32	841639168
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	64889
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	32751
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	2348
ISDATBSI3F2MsgTimer_mS_M_u32	1707689216
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	9734
ISDATBSI412MsgLenValidCount_Cnt_M_u16	37869
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	28125
ISDATBSI412MsgTimer_mS_M_u32	1822852352
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	51237
ISDATBSI432MsgLenValidCount_Cnt_M_u16	24003
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	40982
ISDATDIRASentFltAcc_Cnt_M_u16	23994
ISDATDIRASentTimer_mS_M_u32	3857941760
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	61227
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	46642
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	43013
ISDYN2CMMMsgTimer_mS_M_u32	3139351808
ISDYNAASChkSumInvalidCount_Cnt_M_u16	15671
ISDYNAASChkSumValidCount_Cnt_M_u16	29033
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	30141
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	376
ISDYNAASMsgLenValidCount_Cnt_M_u16	27202
ISDYNAASMsgTimeValidCount_Cnt_M_u16	15671
ISDYNAASMsgTimer_mS_M_u32	3116045568
ISDYNABRChkSumInvalidCount_Cnt_M_u16	27595
ISDYNABRChkSumValidCount_Cnt_M_u16	43142
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	5442
ISDYNABRMsgCountValidCount_Cnt_M_u16	52148
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	8159
ISDYNABRMsgLenValidCount_Cnt_M_u16	11713
ISDYNABRMsgTimeValidCount_Cnt_M_u16	16533
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	42860
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	40955
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	2348
ISDYNCMM208MsgTimer_mS_M_u32	558986496

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	42860
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	40955
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	55624
ISDYNCMM388MsgTimer_mS_M_u32	1017156864
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	29418
ISDYNVOLChkSumValidCount_Cnt_M_u16	17164
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	44944
ISDYNVOLMsgCountValidCount_Cnt_M_u16	64875
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	29924
ISDYNVOLMsgLenValidCount_Cnt_M_u16	999
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	15185
ISDYNVOLMsgTimer_mS_M_u32	4282275072
IgnOnTimer_mS_M_u32	2708772096
IgnTimeOff_Sec_M_u32	1476466474
ManVehSpd_Kph_M_f32	119.493599
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	211
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	61
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2607236352
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	66
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1750836480
PrevISDATBSI412MsgDLCError_Cnt_M_u08	69
PrevISDATBSI412MsgRxTime_MSec_M_u32	1667290368
PrevISDATBSI432MsgDLCError_Cnt_M_u08	18
PrevISDATBSI432MsgRxTime_MSec_M_u32	3017848064
PrevISDATDIRAMsgTxTime_MSec_M_u32	3557086464
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	191
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1101260032
PrevISDYNAASMsgDLCError_Cnt_M_u08	31
PrevISDYNAASMsgRxTime_MSec_M_u32	3587462400
PrevISDYNABRMsgDLCError_Cnt_M_u08	249
PrevISDYNABRMsgRxTime_MSec_M_u32	2932643072
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	7
PrevISDYNCMM208MsgRxTime_MSec_M_u32	53826816
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	237
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3774854400
PrevISDYNVOLMsgDLCError_Cnt_M_u08	21
PrevISDYNVOLMsgRxTime_MSec_M_u32	3963213056
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2881258752
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	429.449493
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	51342
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	30168
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	4867
VitesseVehicleBVRampValidCount_Cnt_M_u16	7693
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	54460
VitesseVehicleBVSigValidCount_Cnt_M_u16	27151
VitesseVehicleBV_Kph_M_f32	380.523987
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	55624
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	54643

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	415.705292
k_AASNTCEnableTimeout_mS_u16	5944
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	13033
k_AASNodeTimeout_mS_u16	3288
k_ABSNodeTimeout_mS_u16	2331
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	2332
k_ANGLEVOLANTSigValidThresh_Cnt_u16	14842
k_AngleVolantInvalidThresh_Cnt_u16	55213
k_AngleVolantValidThresh_Cnt_u16	5198
k_BSI552MsgTimeout_mS_u16	41190
k_BSINTCEnableTimeout_mS_u16	34173
k_BSINodeAbsentDiag_Cnt_str.Threshold	10421
k_BSINodeAbsentDiag_Cnt_str.PStep	37763
k_BSINodeAbsentDiag_Cnt_str.NStep	1268
k_BSINodeAbsentTimeout_mS_u16	46190
k_BSINodeTimeout_mS_u16	40982
k_BattOvHi_Volt_f32	9.68420029
k_BattOvLo_Volt_f32	14.2841997
k_BattUvHi_Volt_f32	14.7854004
k_BattUvLo_Volt_f32	16.5105
k_CAVNTCEnableTimeout_mS_u16	59580
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	6191
k_CAVNodeTimeout_mS_u16	56320
k_CMM388MsgTimeout_mS_u16	26701
k_CMM388NTCEnableTimeout_mS_u16	49273
k_CMMNTCEnableTimeout_mS_u16	9937
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	60319
k_CONSANGLECPKMax_HwDeg_f32	491.175995
k_CONSANGLECPKMin_HwDeg_f32	-554.400574
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	12360
k_CONSANGLECPKSigValidThresh_Cnt_u16	27763
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	790
k_CPKVehicleSpeedValidThresh_Cnt_u16	3109
k_CityParkInputInvalidThresh_Cnt_u16	48265
k_CityParkInputValidThresh_Cnt_u16	8198
k_ComputerRazGCTSigValidThresh_Cnt_u16	41879
k_CptTemporelSigValidThresh_Cnt_u16	8333
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	63199
k_DMDFCTCPKSigValidThresh_Cnt_u16	17601
k_DMDFCTCPKValidCount_Cnt_u16	19578
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	43013
k_DMDRELAXECPKSigValidThresh_Cnt_u16	54176
k_DMDRelaxeConsistentThresh_Cnt_u16	11230
k_DateValidThresh_Cnt_u16	59155
k_DefaultVehSpd_Kph_f32	138.543503
k_DiagMuxOnAbsentTimeout_mS_u16	24707
k_EMNodeTimeout_mS_u16	42365
k_ESPNTCEnableTimeout_mS_u16	18245
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	38471
k_EtatMTSigInvalidThresh_Cnt_u16	64478
k_EtatMTSigValidThresh_Cnt_u16	12505
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	43925
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	63556
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	38011
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	12258
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	57112
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	41178
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	15886
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	41068
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	38137
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	48969

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	208
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	51111
k_ISDATDIRASentDiag_Cnt_str.Threshold	3472
k_ISDATDIRASentDiag_Cnt_str.PStep	32212
k_ISDATDIRASentDiag_Cnt_str.NStep	26715
k_ISDATDIRASentTimeout_mS_u16	23799
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	14984
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	36118
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	17857
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	49867
k_ISDYNAASChkSumValidThresh_Cnt_u16	16262
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	60482
k_ISDYNAASMsgCountValidThresh_Cnt_u16	58036
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	4511
k_ISDYNAASMsgLenValidThresh_Cnt_u16	61100
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	2722
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	16629
k_ISDYNABRChkSumValidThresh_Cnt_u16	4951
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	41938
k_ISDYNABRMsgCountValidThresh_Cnt_u16	32165
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	53841
k_ISDYNABRMsgLenValidThresh_Cnt_u16	61679
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	10392
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	51810
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	52923
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	33611
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	54727
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	44378
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	44966
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	36221
k_ISDYNVOLChkSumValidThresh_Cnt_u16	30372
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	18616
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	50522
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	25609
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	34904
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	513
k_IgnOnTimeout_mS_u16	8873
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	78.4464035
k_PowerCutVehSpdLowThresh_Kph_f32	140.360397
k_PowerCutVehSpdLowTimeout_mS_u16	13460
k_VBattMaxAAS_Volt_f32	24.4920006
k_VBattMaxBSI_Volt_f32	30.5648003
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	8.52980042
k_VBattMaxCMM_Volt_f32	15.8916998
k_VBattMaxESP_Volt_f32	12.3507004
k_VBattMinAAS_Volt_f32	21.3230991
k_VBattMinBSI_Volt_f32	12.3507004
k_VBattMinCAV_Volt_f32	32
k_VBattMinCMM388_Volt_f32	20.3038998
k_VBattMinCMM_Volt_f32	31.5028
k_VBattMinESP_Volt_f32	15.8916998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	33610
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	51169
k_VitesseVehicleBVRampValidThresh_Cnt_u16	1680
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	23052
k_VitesseVehicleBVSigValidThresh_Cnt_u16	14291
k_VitesseVehicleBVSpeedPassThresh_kph_f32	90.4965973
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	31001
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	2211
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2293560576
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	237
target_SrlComInput_Per1_Batt_Volt_f32.value	29.2143002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	11805952
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	171
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.297467947
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	147
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3745944832
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2343908608
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1051972864
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1614968064
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1482757376
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2400171264
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1817072896
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	32
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	52
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	53
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	79
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	102
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	109
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	180
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	79
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3868685568
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	155
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	156
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2785383680
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3757323520
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3765622016
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	74
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	122
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	133
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3642074368
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2366
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.248059675
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	718244
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	143.604797
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	54480

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	10421	10421	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	119.493599	119.493599	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	16533	16533	✔
CONSANGLECPK_HwDeg_M_f32	678.937683	678.937683 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1713429248	1713429248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3	3	✔
EffacDefaultDiagTimer_mS_M_u32[1]	6	6	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	56565	56565	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	787881	787881	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	59155	59155	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	2348	2348	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	28125	28125	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	40982	40982	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	3472	3472	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	43013	43013	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	15671	15671	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	16533	16533	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	2348	2348	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	55624	55624	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	15185	15185	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	2708772096	2708772096	✔
IgnTimeOff_Sec_M_u32	1476466474	1476466474	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	147	147	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3745944832	3745944832	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	131	131	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2343908608	2343908608	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	69	69	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1051972864	1051972864	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	67	67	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1614968064	1614968064	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3557086464	3557086464	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	141	141	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2400171264	2400171264	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	170	170	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1817072896	1817072896	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	79	79	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3868685568	3868685568	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	59	59	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2785383680	2785383680	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	216	216	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3757323520	3757323520	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	8	8	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3765622016	3765622016	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3642074368	3642074368	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	429.449493	429.449493	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	380.523987	380.523987	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	415.705292	415.705292	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	16533	16533	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1476466474	1476466474	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	678.937683	678.937683 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.389 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3937085184
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	24907
AASNodeAbsentTimer_mS_M_u32	4145272576
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	65178
ANGLEVOLANTSigValidCount_Cnt_M_u16	59970
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	58204
AngleVolantMsgTimer_mS_M_u32	3937085184
AngleVolantValidCount_Cnt_M_u16	63070
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2718603008
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1299388160
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3540797184
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2186151680
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	46333
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	774293248
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	25976
CAVNodeAbsentTimer_mS_M_u32	2295920384
CDD_SrlComVehSpd_Kph_G_f32	135.3367
CMM388NTCEnableTimer_mS_M_u32	3072210688
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	403109632
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	496
CMMNodeAbsentTimer_mS_M_u32	329254656
CONSANGLECPKSigInvalidCount_Cnt_M_u16	12044
CONSANGLECPKSigValidCount_Cnt_M_u16	61253
CONSANGLECPK_Cnt_M_u16	11356
CONSANGLECPK_HwDeg_M_f32	228.833801
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	11356
CPKVehicleSpeedMsgTimer_mS_M_u32	4280690432
CPKVehicleSpeedValidCount_Cnt_M_u16	9077
CityParkInputConsistentCount_Cnt_M_u16	52946
CityParkInputInvalidCount_Cnt_M_u16	48988
CityParkInputMsgTimer_mS_M_u32	643761152
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3968325376
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	42943

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	515602176
ComputerRazGCTSigValidCount_Cnt_M_u16	34427
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	13032
DMDFCTCPKSigValidCount_Cnt_M_u16	56984
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56788
DMDRELAXECPKSigValidCount_Cnt_M_u16	41212
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	36381
DateInvalidTimer_mS_M_u32	1299388160
DiagMuxOnAbsentTimer_mS_M_u32	3907249920
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2186151680
ESPNTCEnableTimer_mS_M_u32	3646478080
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	19716
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	9
EffacDefaultDiagTimer_mS_M_u32[1]	81
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	55656
ElecIntTimer_mS_M_u32[1]	87790
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2571159296
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	49886
EtatMTSigValidCount_Cnt_M_u16	12322
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	15430
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	21503
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	4038
ISDAT4V2BSI552MsgTimer_mS_M_u32	4162062080
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	8793
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	61445
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	12322
ISDATBSI3F2MsgTimer_mS_M_u32	1403643648
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	61776
ISDATBSI412MsgLenValidCount_Cnt_M_u16	34284
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	49886
ISDATBSI412MsgTimer_mS_M_u32	1936795392
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	5476
ISDATBSI432MsgLenValidCount_Cnt_M_u16	53112
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	39773
ISDATDIRASentFltAcc_Cnt_M_u16	58913
ISDATDIRASentTimer_mS_M_u32	4280690432
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	16290
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	63070
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	18635
ISDYN2CMMMsgTimer_mS_M_u32	153802496
ISDYNAASChkSumInvalidCount_Cnt_M_u16	31877
ISDYNAASChkSumValidCount_Cnt_M_u16	59853
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	10817
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	55247
ISDYNAASMsgLenValidCount_Cnt_M_u16	56943
ISDYNAASMsgTimeValidCount_Cnt_M_u16	31877
ISDYNAASMsgTimer_mS_M_u32	2208970496
ISDYNABRChkSumInvalidCount_Cnt_M_u16	26301
ISDYNABRChkSumValidCount_Cnt_M_u16	24781
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	36072
ISDYNABRMsgCountValidCount_Cnt_M_u16	36464
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	52847
ISDYNABRMsgLenValidCount_Cnt_M_u16	25320
ISDYNABRMsgTimeValidCount_Cnt_M_u16	11356
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	38125
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	33281
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	12322
ISDYNCMM208MsgTimer_mS_M_u32	1056151296
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	38125
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	33281
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	8740

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1505474304
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	12754
ISDYNVOLChkSumValidCount_Cnt_M_u16	39563
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	1198
ISDYNVOLMsgCountValidCount_Cnt_M_u16	39134
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	1953
ISDYNVOLMsgLenValidCount_Cnt_M_u16	9785
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	496
ISDYNVOLMsgTimer_mS_M_u32	1195865856
IgnOnTimer_mS_M_u32	87013120
IgnTimeOff_Sec_M_u32	2172419507
ManVehSpd_Kph_M_f32	525.726501
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	212
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	110
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1714939648
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	74
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3788457728
PrevISDATBSI412MsgDLCError_Cnt_M_u08	180
PrevISDATBSI412MsgRxTime_MSec_M_u32	3497916160
PrevISDATBSI432MsgDLCError_Cnt_M_u08	192
PrevISDATBSI432MsgRxTime_MSec_M_u32	2549929728
PrevISDATDIRAMsgTxTime_MSec_M_u32	1715599104
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	130
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3747186432
PrevISDYNAASMsgDLCError_Cnt_M_u08	214
PrevISDYNAASMsgRxTime_MSec_M_u32	3264050944
PrevISDYNABRMsgDLCError_Cnt_M_u08	235
PrevISDYNABRMsgRxTime_MSec_M_u32	1028110080
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	173
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3270932224
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	237
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3323188992
PrevISDYNVOLMsgDLCError_Cnt_M_u08	190
PrevISDYNVOLMsgRxTime_MSec_M_u32	3357472512
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2604082944
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	137.464905
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	51093
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	14005
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	60850
VitesseVehicleBVRampValidCount_Cnt_M_u16	43154
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	3127
VitesseVehicleBVSigValidCount_Cnt_M_u16	58271
VitesseVehicleBV_Kph_M_f32	594.474792
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	8740
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	22308
VitesseVehiculeRoues_Kph_M_f32	323.989685
k_AASNTCEnableTimeout_mS_u16	61463
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	45261
k_AASNodeTimeout_mS_u16	34229
k_ABSNodeTimeout_mS_u16	41617
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	46611
k_ANGLEVOLANTSigValidThresh_Cnt_u16	58727
k_AngleVolantInvalidThresh_Cnt_u16	10418
k_AngleVolantValidThresh_Cnt_u16	48988
k_BSI552MsgTimeout_mS_u16	13871
k_BSINTCEnableTimeout_mS_u16	32124
k_BSINodeAbsentDiag_Cnt_str.Threshold	28305
k_BSINodeAbsentDiag_Cnt_str.PStep	51049
k_BSINodeAbsentDiag_Cnt_str.NStep	40021
k_BSINodeAbsentTimeout_mS_u16	1396
k_BSINodeTimeout_mS_u16	39773
k_BattOvHi_Volt_f32	30.8015995
k_BattOvLo_Volt_f32	18.5641994
k_BattUvHi_Volt_f32	9.80850029
k_BattUvLo_Volt_f32	31.5
k_CAVNTCEnableTimeout_mS_u16	59194
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	64574
k_CAVNodeTimeout_mS_u16	54168
k_CMM388MsgTimeout_mS_u16	61515
k_CMM388NTCEnableTimeout_mS_u16	59863
k_CMMNTCEnableTimeout_mS_u16	22129
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	65200
k_CONSANGLECPKMax_HwDeg_f32	508.225006
k_CONSANGLECPKMin_HwDeg_f32	-637.771118
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	12580
k_CONSANGLECPKSigValidThresh_Cnt_u16	42532
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	24035
k_CPKVehicleSpeedValidThresh_Cnt_u16	41063
k_CityParkInputInvalidThresh_Cnt_u16	28011
k_CityParkInputValidThresh_Cnt_u16	52946
k_ComputerRazGCTSigValidThresh_Cnt_u16	10599
k_CptTemporelSigValidThresh_Cnt_u16	50579
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	23919
k_DMDFCTCPKSigValidThresh_Cnt_u16	12776
k_DMDFCTCPKValidCount_Cnt_u16	29157
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	18635
k_DMDRELAXECPKSigValidThresh_Cnt_u16	43195
k_DMDRelaxeConsistentThresh_Cnt_u16	62185
k_DateValidThresh_Cnt_u16	4038
k_DefaultVehSpd_Kph_f32	97.479599
k_DiagMuxOnAbsentTimeout_mS_u16	64442
k_EMNodeTimeout_mS_u16	45309
k_ESPNTCEnableTimeout_mS_u16	37892
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	16024
k_EtatMTSigInvalidThresh_Cnt_u16	12136
k_EtatMTSigValidThresh_Cnt_u16	58296
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	57946
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	35839
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	28399
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	36874
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	61558
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	25284
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	58005
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	53097
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	26840
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	49328
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	50668
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	8699
k_ISDATDIRASentDiag_Cnt_str.Threshold	2435

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	9638
k_ISDATDIRASentDiag_Cnt_str.NStep	54621
k_ISDATDIRASentTimeout_mS_u16	49481
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	37860
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58204
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	58976
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	30141
k_ISDYNAASChkSumValidThresh_Cnt_u16	45005
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	7144
k_ISDYNAASMsgCountValidThresh_Cnt_u16	23920
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	23345
k_ISDYNAASMsgLenValidThresh_Cnt_u16	38441
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	31567
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	59445
k_ISDYNABRChkSumValidThresh_Cnt_u16	25902
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	17405
k_ISDYNABRMsgCountValidThresh_Cnt_u16	33765
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	20720
k_ISDYNABRMsgLenValidThresh_Cnt_u16	56324
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	15984
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	63497
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	26541
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	26560
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	36250
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	47426
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	62836
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	60543
k_ISDYNVOLChkSumValidThresh_Cnt_u16	54875
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	39445
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	33857
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	19050
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	34990
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	45604
k_IgnOnTimeout_mS_u16	2827
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	41.6050987
k_PowerCutVehSpdLowThresh_Kph_f32	102.831596
k_PowerCutVehSpdLowTimeout_mS_u16	22611
k_VBattMaxAAS_Volt_f32	17.0897999
k_VBattMaxBSI_Volt_f32	19.7954006
k_VBattMaxCAV_Volt_f32	18.1005993
k_VBattMaxCMM388_Volt_f32	2.14299989
k_VBattMaxCMM_Volt_f32	17.2882996
k_VBattMaxESP_Volt_f32	25.8320999
k_VBattMinAAS_Volt_f32	32
k_VBattMinBSI_Volt_f32	25.8320999
k_VBattMinCAV_Volt_f32	31.7586994
k_VBattMinCMM388_Volt_f32	16.2644005
k_VBattMinCMM_Volt_f32	20.5674992
k_VBattMinESP_Volt_f32	17.2882996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	62134
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	37763
k_VitesseVehicleBVRampValidThresh_Cnt_u16	5038
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	27019
k_VitesseVehicleBVSigValidThresh_Cnt_u16	60679
k_VitesseVehicleBVSpeedPassThresh_kph_f32	103.231903
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	29816
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	55256
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1299388160
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8524
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1236548
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	237
target_SrlComInput_Per1_Batt_Volt_f32.value	16.0021992
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	820758272
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	123
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.570442557
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2173810432
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2188728064
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1047066368
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1567397632
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2273326848
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1688459008
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2631366400
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	65
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	139
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	230
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2657720064
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	7
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	30
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	56
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	239
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	373864192
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	279729920
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2250241792
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	197
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	204
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1750681344
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	0
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.934834003
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	911616
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	238.531097
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	1511

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1236548	1236548	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1236548	1236548	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1236548	1236548	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	28305	28305	✔
BSINodeAbsentTimer_mS_M_u32	1236548	1236548	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CDD_SrlComVehSpd_Kph_G_f32	525.726501	525.726501	✔
CMM388NTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	11356	11356	✔
CONSANGLECPK_HwDeg_M_f32	228.833801	228.833801 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1236548	1236548	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1236548	1236548	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1236548	1236548	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1236548	1236548	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1236548	1236548	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1236548	1236548	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1236548	1236548	✔
ESPNTCEnableTimer_mS_M_u32	1236548	1236548	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	9	9	✔
EffacDefaultDiagTimer_mS_M_u32[1]	81	81	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	55656	55656	✔
ElecIntTimer_mS_M_u32[1]	87790	87790	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1236548	1236548	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	4038	4038	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	12322	12322	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	49886	49886	✔
ISDATBSI412MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	39773	39773	✔
ISDATBSI432MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATDIRASentFltAcc_Cnt_M_u16	2435	2435	✔
ISDATDIRASentTimer_mS_M_u32	1236548	1236548	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	18635	18635	✔
ISDYN2CMMMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	31877	31877	✔
ISDYNAASMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	11356	11356	✔
ISDYNABRMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	12322	12322	✔
ISDYNCMM208MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	8740	8740	✔
ISDYNCMM388MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	496	496	✔
ISDYNVOLMsgTimer_mS_M_u32	1236548	1236548	✔
IgnOnTimer_mS_M_u32	87013120	87013120	✔
IgnTimeOff_Sec_M_u32	2172419507	2172419507	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	74	74	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2173810432	2173810432	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	109	109	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2188728064	2188728064	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	118	118	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1047066368	1047066368	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	15	15	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1567397632	1567397632	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1715599104	1715599104	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	141	141	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1688459008	1688459008	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	194	194	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2631366400	2631366400	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	3	3	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2657720064	2657720064	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	202	202	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	373864192	373864192	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	279729920	279729920	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	233	233	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2250241792	2250241792	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1750681344	1750681344	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	137.464905	137.464905	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	594.474792	594.474792	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	323.989685	323.989685	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	11356	11356	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2172419507	2172419507	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	228.833801	228.833801 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	525.726501	525.726501	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.390 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	83447296
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	49943
AASNodeAbsentTimer_mS_M_u32	2659139072
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	17708
ANGLEVOLANTSigValidCount_Cnt_M_u16	40691
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	49380
AngleVolantMsgTimer_mS_M_u32	83447296
AngleVolantValidCount_Cnt_M_u16	5727
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3902471680
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	677477888
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3092639232
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3784355328
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	28163
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	822504960
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	21264
CAVNodeAbsentTimer_mS_M_u32	3853508096
CDD_SrlComVehSpd_Kph_G_f32	174.003494
CMM388NTCEnableTimer_mS_M_u32	4292877824
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1881529856
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	59242
CMMNodeAbsentTimer_mS_M_u32	4120555008
CONSANGLECPKSigInvalidCount_Cnt_M_u16	61140
CONSANGLECPKSigValidCount_Cnt_M_u16	2795
CONSANGLECPK_Cnt_M_u16	28582
CONSANGLECPK_HwDeg_M_f32	30.3241005
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	28582
CPKVehicleSpeedMsgTimer_mS_M_u32	1938312704
CPKVehicleSpeedValidCount_Cnt_M_u16	53603
CityParkInputConsistentCount_Cnt_M_u16	23811
CityParkInputInvalidCount_Cnt_M_u16	33893
CityParkInputMsgTimer_mS_M_u32	2173810432
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2384674304
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	49083

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3456654848
ComputerRazGCTSigValidCount_Cnt_M_u16	6664
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	22977
DMDFCTCPKSigValidCount_Cnt_M_u16	37744
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	3966
DMDRELAXECPKSigValidCount_Cnt_M_u16	58053
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	21921
DateInvalidTimer_mS_M_u32	677477888
DiagMuxOnAbsentTimer_mS_M_u32	3712945664
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3784355328
ESPNTCEnableTimer_mS_M_u32	1269841408
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	53997
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	20
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	18
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3619188224
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	11679
EtatMTSigValidCount_Cnt_M_u16	29330
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	12070
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	17597
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	14310
ISDAT4V2BSI552MsgTimer_mS_M_u32	406760960
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	4782
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	54890
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	29330
ISDATBSI3F2MsgTimer_mS_M_u32	888999424
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	37576
ISDATBSI412MsgLenValidCount_Cnt_M_u16	49588
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	11679
ISDATBSI412MsgTimer_mS_M_u32	44518912
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	32014
ISDATBSI432MsgLenValidCount_Cnt_M_u16	7057
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	34145
ISDATDIRASentFltAcc_Cnt_M_u16	46357
ISDATDIRASentTimer_mS_M_u32	1938312704
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	52692
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	5727
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	25624
ISDYN2CMMMsgTimer_mS_M_u32	2218409472
ISDYNAASChkSumInvalidCount_Cnt_M_u16	55657
ISDYNAASChkSumValidCount_Cnt_M_u16	11857
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	50870
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	6155
ISDYNAASMsgLenValidCount_Cnt_M_u16	234
ISDYNAASMsgTimeValidCount_Cnt_M_u16	55657
ISDYNAASMsgTimer_mS_M_u32	3392937472
ISDYNABRChkSumInvalidCount_Cnt_M_u16	45123
ISDYNABRChkSumValidCount_Cnt_M_u16	32467
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	62528
ISDYNABRMsgCountValidCount_Cnt_M_u16	35944
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	23723
ISDYNABRMsgLenValidCount_Cnt_M_u16	64514
ISDYNABRMsgTimeValidCount_Cnt_M_u16	28582
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	57573
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	38249
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	29330
ISDYNCMM208MsgTimer_mS_M_u32	4125097472
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	57573
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	38249
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	11021

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1845992960
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	32386
ISDYNVOLChkSumValidCount_Cnt_M_u16	41241
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	31855
ISDYNVOLMsgCountValidCount_Cnt_M_u16	64670
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	22294
ISDYNVOLMsgLenValidCount_Cnt_M_u16	55309
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	59242
ISDYNVOLMsgTimer_mS_M_u32	2221170176
IgnOnTimer_mS_M_u32	1001102848
IgnTimeOff_Sec_M_u32	1588409170
ManVehSpd_Kph_M_f32	435.373108
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	213
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	27
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3042119168
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	7
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1477242368
PrevISDATBSI412MsgDLCError_Cnt_M_u08	78
PrevISDATBSI412MsgRxTime_MSec_M_u32	3804290560
PrevISDATBSI432MsgDLCError_Cnt_M_u08	235
PrevISDATBSI432MsgRxTime_MSec_M_u32	2680438272
PrevISDATDIRAMsgTxTime_MSec_M_u32	829742592
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	24
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1483615744
PrevISDYNAASMsgDLCError_Cnt_M_u08	179
PrevISDYNAASMsgRxTime_MSec_M_u32	2861719040
PrevISDYNABRMsgDLCError_Cnt_M_u08	82
PrevISDYNABRMsgRxTime_MSec_M_u32	4083392000
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	41
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2371313152
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	49
PrevISDYNCMM388MsgRxTime_MSec_M_u32	830422528
PrevISDYNVOLMsgDLCError_Cnt_M_u08	157
PrevISDYNVOLMsgRxTime_MSec_M_u32	3218988544
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	592793088
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	131.725403
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57529
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	36888
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	8802
VitesseVehicleBVRampValidCount_Cnt_M_u16	61057
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	53333
VitesseVehicleBVSigValidCount_Cnt_M_u16	26332
VitesseVehicleBV_Kph_M_f32	40.0460014
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	11021
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	2253
VitesseVehiculeRoues_Kph_M_f32	419.496307
k_AASNTCEnableTimeout_mS_u16	53365
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	25362
k_AASNodeTimeout_mS_u16	41752
k_ABSNodeTimeout_mS_u16	61126
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	5889
k_ANGLEVOLANTSigValidThresh_Cnt_u16	21956
k_AngleVolantInvalidThresh_Cnt_u16	30691
k_AngleVolantValidThresh_Cnt_u16	33893
k_BSI552MsgTimeout_mS_u16	22444
k_BSINTCEnableTimeout_mS_u16	42182
k_BSINodeAbsentDiag_Cnt_str.Threshold	15225
k_BSINodeAbsentDiag_Cnt_str.PStep	25905
k_BSINodeAbsentDiag_Cnt_str.NStep	27309
k_BSINodeAbsentTimeout_mS_u16	47772
k_BSINodeTimeout_mS_u16	34145
k_BattOvHi_Volt_f32	18.4543991
k_BattOvLo_Volt_f32	21.8729992
k_BattUvHi_Volt_f32	3.0401001
k_BattUvLo_Volt_f32	22.2553005
k_CAVNTCEnableTimeout_mS_u16	1227
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	9918
k_CAVNodeTimeout_mS_u16	12592
k_CMM388MsgTimeout_mS_u16	5655
k_CMM388NTCEnableTimeout_mS_u16	22899
k_CMMNTCEnableTimeout_mS_u16	54886
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	16937
k_CONSANGLECPKMax_HwDeg_f32	680.977295
k_CONSANGLECPKMin_HwDeg_f32	-84.8242035
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	65037
k_CONSANGLECPKSigValidThresh_Cnt_u16	7117
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	21134
k_CPKVehicleSpeedValidThresh_Cnt_u16	41347
k_CityParkInputInvalidThresh_Cnt_u16	54329
k_CityParkInputValidThresh_Cnt_u16	23811
k_ComputerRazGCTSigValidThresh_Cnt_u16	46468
k_CptTemporelSigValidThresh_Cnt_u16	3520
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	44971
k_DMDFCTCPKSigValidThresh_Cnt_u16	36610
k_DMDFCTCPKValidCount_Cnt_u16	55115
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	25624
k_DMDRELAXECPKSigValidThresh_Cnt_u16	33031
k_DMDRelaxeConsistentThresh_Cnt_u16	55933
k_DateValidThresh_Cnt_u16	14310
k_DefaultVehSpd_Kph_f32	231.040695
k_DiagMuxOnAbsentTimeout_mS_u16	63884
k_EMNodeTimeout_mS_u16	27905
k_ESPNTCEnableTimeout_mS_u16	63340
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	8817
k_EtatMTSigInvalidThresh_Cnt_u16	49730
k_EtatMTSigValidThresh_Cnt_u16	25106
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	24873
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	28925
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	12460
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	52635
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	55575
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	3692
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	6523
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	8126
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	21170
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	682
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	24501
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	48583
k_ISDATDIRASentDiag_Cnt_str.Threshold	50189

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	7148
k_ISDATDIRASentDiag_Cnt_str.NStep	24623
k_ISDATDIRASentTimeout_mS_u16	53407
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	19468
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	49380
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	28760
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	33603
k_ISDYNAASChkSumValidThresh_Cnt_u16	37331
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	18240
k_ISDYNAASMsgCountValidThresh_Cnt_u16	8040
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	41703
k_ISDYNAASMsgLenValidThresh_Cnt_u16	16828
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	13324
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	42841
k_ISDYNABRChkSumValidThresh_Cnt_u16	36144
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	49411
k_ISDYNABRMsgCountValidThresh_Cnt_u16	7690
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	64106
k_ISDYNABRMsgLenValidThresh_Cnt_u16	9709
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	55913
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	8029
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	58289
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	59639
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	38956
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	12787
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	16925
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	7483
k_ISDYNVOLChkSumValidThresh_Cnt_u16	19559
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	28602
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	58487
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	50939
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	39150
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	18636
k_IgnOnTimeout_mS_u16	61847
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	183.164307
k_PowerCutVehSpdLowThresh_Kph_f32	103.484596
k_PowerCutVehSpdLowTimeout_mS_u16	34753
k_VBattMaxAAS_Volt_f32	16.4682007
k_VBattMaxBSI_Volt_f32	3.77530003
k_VBattMaxCAV_Volt_f32	10.5676003
k_VBattMaxCMM388_Volt_f32	16.7392998
k_VBattMaxCMM_Volt_f32	14.9702997
k_VBattMaxESP_Volt_f32	11.2208004
k_VBattMinAAS_Volt_f32	18.2726002
k_VBattMinBSI_Volt_f32	11.2208004
k_VBattMinCAV_Volt_f32	12.4868002
k_VBattMinCMM388_Volt_f32	29.6436996
k_VBattMinCMM_Volt_f32	12.9638996
k_VBattMinESP_Volt_f32	14.9702997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	63382
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	49649
k_VitesseVehicleBVRampValidThresh_Cnt_u16	20335
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	13337
k_VitesseVehicleBVSigValidThresh_Cnt_u16	5732
k_VitesseVehicleBVSpeedPassThresh_kph_f32	632.458618
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	9744
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	63663
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	677477888
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	55763
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1813852160
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	49
target_SrlComInput_Per1_Batt_Volt_f32.value	28.3033009
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2092396032
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	177
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0443599261
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	191
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3464863232
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	207
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1650114048
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	83877376
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	150
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3195338240
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2528779776
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2513387008
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3283377664
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	124
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	137
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	182
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	219
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	223
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	237
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	236
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	796786176
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	84
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	146
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	163
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	216
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	228
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2892013056
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1404419584
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3386564096
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	134
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	175
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1819209216
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	65535
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.142361313
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	108616
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	48.6362
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	60867

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1813852160	1813852160	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	15225	15225	✔
BSINodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
CDD_SrlComVehSpd_Kph_G_f32	435.373108	435.373108	✔
CMM388NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	28582	28582	✔
CONSANGLECPK_HwDeg_M_f32	30.3241005	30.3241005 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1813852160	1813852160	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1813852160	1813852160	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1813852160	1813852160	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1813852160	1813852160	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1813852160	1813852160	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1813852160	1813852160	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1813852160	1813852160	✔
ESPNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	20	20	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	6	6	✔
ElecIntTimer_mS_M_u32[1]	18	18	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1813852160	1813852160	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	14310	14310	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	29330	29330	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	11679	11679	✔
ISDATBSI412MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	34145	34145	✔
ISDATBSI432MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATDIRASentFltAcc_Cnt_M_u16	50189	50189	✔
ISDATDIRASentTimer_mS_M_u32	1813852160	1813852160	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	25624	25624	✔
ISDYN2CMMMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	55657	55657	✔
ISDYNAASMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	28582	28582	✔
ISDYNABRMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	29330	29330	✔
ISDYNCMM208MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	11021	11021	✔
ISDYNCMM388MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	59242	59242	✔
ISDYNVOLMsgTimer_mS_M_u32	1813852160	1813852160	✔
IgnOnTimer_mS_M_u32	1001102848	1001102848	✔
IgnTimeOff_Sec_M_u32	1588409170	1588409170	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	191	191	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3464863232	3464863232	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	207	207	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1650114048	1650114048	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	105	105	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	83877376	83877376	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	150	150	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3195338240	3195338240	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	829742592	829742592	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	200	200	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2513387008	2513387008	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	222	222	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3283377664	3283377664	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	236	236	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	796786176	796786176	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2892013056	2892013056	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	158	158	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1404419584	1404419584	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	172	172	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3386564096	3386564096	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1819209216	1819209216	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	131.725403	131.725403	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	40.0460014	40.0460014	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	419.496307	419.496307	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	28582	28582	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1588409170	1588409170	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	30.3241005	30.3241005 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	435.373108	435.373108	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.391 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	57334016
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	25359
AASNodeAbsentTimer_mS_M_u32	4204333312
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	52945
ANGLEVOLANTSigValidCount_Cnt_M_u16	27451
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	56744
AngleVolantMsgTimer_mS_M_u32	57334016
AngleVolantValidCount_Cnt_M_u16	12726
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	994429184
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3052554496
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2748643584
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2200221952
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	28748
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2613278976
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	56741
CAVNodeAbsentTimer_mS_M_u32	797387008
CDD_SrlComVehSpd_Kph_G_f32	612.711487
CMM388NTCEnableTimer_mS_M_u32	4059457792
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3894749440
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	58200
CMMNodeAbsentTimer_mS_M_u32	4010195200
CONSANGLECPKSigInvalidCount_Cnt_M_u16	8410
CONSANGLECPKSigValidCount_Cnt_M_u16	46676
CONSANGLECPK_Cnt_M_u16	13347
CONSANGLECPK_HwDeg_M_f32	-79.2837982
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	13347
CPKVehicleSpeedMsgTimer_mS_M_u32	3015563520
CPKVehicleSpeedValidCount_Cnt_M_u16	22997
CityParkInputConsistentCount_Cnt_M_u16	60874
CityParkInputInvalidCount_Cnt_M_u16	36007
CityParkInputMsgTimer_mS_M_u32	3464863232
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3148679424
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	64803

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2021501184
ComputerRazGCTSigValidCount_Cnt_M_u16	2747
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	31891
DMDFCTCPKSigValidCount_Cnt_M_u16	6468
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	14299
DMDRELAXECPKSigValidCount_Cnt_M_u16	26565
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	24691
DateInvalidTimer_mS_M_u32	3052554496
DiagMuxOnAbsentTimer_mS_M_u32	23697664
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2200221952
ESPNTCEnableTimer_mS_M_u32	4144367872
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	47758
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	80
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	88
ElecIntTimer_mS_M_u32[1]	110
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	4021123328
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	30136
EtatMTSigValidCount_Cnt_M_u16	158
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	10212
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	53470
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	33762
ISDAT4V2BSI552MsgTimer_mS_M_u32	387627264
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	48138
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	60056
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	158
ISDATBSI3F2MsgTimer_mS_M_u32	845125888
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	29883
ISDATBSI412MsgLenValidCount_Cnt_M_u16	8633
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	30136
ISDATBSI412MsgTimer_mS_M_u32	1113643264
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	45676
ISDATBSI432MsgLenValidCount_Cnt_M_u16	28834
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	51890
ISDATDIRASentFltAcc_Cnt_M_u16	2966
ISDATDIRASentTimer_mS_M_u32	3015563520
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	20889
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	12726
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	31118
ISDYN2CMMMsgTimer_mS_M_u32	4117235968
ISDYNAASChkSumInvalidCount_Cnt_M_u16	59417
ISDYNAASChkSumValidCount_Cnt_M_u16	4899
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	15537
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	15028
ISDYNAASMsgLenValidCount_Cnt_M_u16	35286
ISDYNAASMsgTimeValidCount_Cnt_M_u16	59417
ISDYNAASMsgTimer_mS_M_u32	48392448
ISDYNABRChkSumInvalidCount_Cnt_M_u16	41739
ISDYNABRChkSumValidCount_Cnt_M_u16	285
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	45972
ISDYNABRMsgCountValidCount_Cnt_M_u16	5342
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	62293
ISDYNABRMsgLenValidCount_Cnt_M_u16	65295
ISDYNABRMsgTimeValidCount_Cnt_M_u16	13347
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	44938
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	7869
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	158
ISDYNCMM208MsgTimer_mS_M_u32	1735837952
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	44938
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	7869
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	11180

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2776623360
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	43472
ISDYNVOLChkSumValidCount_Cnt_M_u16	11210
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	19593
ISDYNVOLMsgCountValidCount_Cnt_M_u16	5562
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	4627
ISDYNVOLMsgLenValidCount_Cnt_M_u16	63724
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	58200
ISDYNVOLMsgTimer_mS_M_u32	3312036096
IgnOnTimer_mS_M_u32	3432245504
IgnTimeOff_Sec_M_u32	794314317
ManVehSpd_Kph_M_f32	125.3657
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	214
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	222
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2304612608
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	149
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1622145280
PrevISDATBSI412MsgDLCError_Cnt_M_u08	52
PrevISDATBSI412MsgRxTime_MSec_M_u32	3159632128
PrevISDATBSI432MsgDLCError_Cnt_M_u08	20
PrevISDATBSI432MsgRxTime_MSec_M_u32	1254754560
PrevISDATDIRAMsgTxTime_MSec_M_u32	2688035072
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	55
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1955346688
PrevISDYNAASMsgDLCError_Cnt_M_u08	159
PrevISDYNAASMsgRxTime_MSec_M_u32	2329913600
PrevISDYNABRMsgDLCError_Cnt_M_u08	48
PrevISDYNABRMsgRxTime_MSec_M_u32	2238441728
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	73
PrevISDYNCMM208MsgRxTime_MSec_M_u32	915450112
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	226
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1100548352
PrevISDYNVOLMsgDLCError_Cnt_M_u08	252
PrevISDYNVOLMsgRxTime_MSec_M_u32	3640469760
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	408344832
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	190.886597
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	6314
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	5196
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	14255
VitesseVehicleBVRampValidCount_Cnt_M_u16	56593
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	4438
VitesseVehicleBVSigValidCount_Cnt_M_u16	63360
VitesseVehicleBV_Kph_M_f32	565.914124
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	11180
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	7214
VitesseVehiculeRoues_Kph_M_f32	67.2381973
k_AASNTCEnableTimeout_mS_u16	3510
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	55197
k_AASNodeTimeout_mS_u16	56140
k_ABSNodeTimeout_mS_u16	4484
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	28819
k_ANGLEVOLANTSigValidThresh_Cnt_u16	19977
k_AngleVolantInvalidThresh_Cnt_u16	9132
k_AngleVolantValidThresh_Cnt_u16	36007
k_BSI552MsgTimeout_mS_u16	27537
k_BSINTCEnableTimeout_mS_u16	6980
k_BSINodeAbsentDiag_Cnt_str.Threshold	59725
k_BSINodeAbsentDiag_Cnt_str.PStep	53093
k_BSINodeAbsentDiag_Cnt_str.NStep	12850
k_BSINodeAbsentTimeout_mS_u16	53376
k_BSINodeTimeout_mS_u16	51890
k_BattOvHi_Volt_f32	14.4089003
k_BattOvLo_Volt_f32	6.53329992
k_BattUvHi_Volt_f32	3.33249998
k_BattUvLo_Volt_f32	9.89330006
k_CAVNTCEnableTimeout_mS_u16	9077
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	39579
k_CAVNodeTimeout_mS_u16	51654
k_CMM388MsgTimeout_mS_u16	27151
k_CMM388NTCEnableTimeout_mS_u16	4091
k_CMMNTCEnableTimeout_mS_u16	20706
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	57370
k_CONSANGLECPKMax_HwDeg_f32	227.883194
k_CONSANGLECPKMin_HwDeg_f32	-467.342194
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	45740
k_CONSANGLECPKSigValidThresh_Cnt_u16	58158
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	9450
k_CPKVehicleSpeedValidThresh_Cnt_u16	62602
k_CityParkInputInvalidThresh_Cnt_u16	36649
k_CityParkInputValidThresh_Cnt_u16	60874
k_ComputerRazGCTSigValidThresh_Cnt_u16	43912
k_CptTemporelSigValidThresh_Cnt_u16	7318
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	64085
k_DMDFCTCPKSigValidThresh_Cnt_u16	17935
k_DMDFCTCPKValidCount_Cnt_u16	21620
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	31118
k_DMDRELAXECPKSigValidThresh_Cnt_u16	27775
k_DMDRelaxeConsistentThresh_Cnt_u16	47133
k_DateValidThresh_Cnt_u16	33762
k_DefaultVehSpd_Kph_f32	137.716705
k_DiagMuxOnAbsentTimeout_mS_u16	44657
k_EMNodeTimeout_mS_u16	39507
k_ESPNTCEnableTimeout_mS_u16	24721
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	24386
k_EtatMTSigInvalidThresh_Cnt_u16	10510
k_EtatMTSigValidThresh_Cnt_u16	4960
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	9497
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	53086
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	22223
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	32579
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	54929
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	37327
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	53541
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	22555
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	49536
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	35607
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	11700
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	48321
k_ISDATDIRASentDiag_Cnt_str.Threshold	13378

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	37990
k_ISDATDIRASentDiag_Cnt_str.NStep	48989
k_ISDATDIRASentTimeout_mS_u16	45559
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	26098
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	56744
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	42445
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	10763
k_ISDYNAASChkSumValidThresh_Cnt_u16	51229
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	47764
k_ISDYNAASMsgCountValidThresh_Cnt_u16	23518
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	23327
k_ISDYNAASMsgLenValidThresh_Cnt_u16	36704
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	54065
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	19275
k_ISDYNABRChkSumValidThresh_Cnt_u16	33669
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	30540
k_ISDYNABRMsgCountValidThresh_Cnt_u16	2550
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	43608
k_ISDYNABRMsgLenValidThresh_Cnt_u16	49550
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	4313
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	60606
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	26112
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	17839
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	54737
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	45627
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	13183
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	24930
k_ISDYNVOLChkSumValidThresh_Cnt_u16	3488
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	22567
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	24625
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	6564
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	64906
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	26928
k_IgnOnTimeout_mS_u16	21582
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	159.8461
k_PowerCutVehSpdLowThresh_Kph_f32	86.8851013
k_PowerCutVehSpdLowTimeout_mS_u16	6098
k_VBattMaxAAS_Volt_f32	23.9221992
k_VBattMaxBSI_Volt_f32	9.72939968
k_VBattMaxCAV_Volt_f32	17.2285995
k_VBattMaxCMM388_Volt_f32	24.8169994
k_VBattMaxCMM_Volt_f32	31.1229
k_VBattMaxESP_Volt_f32	9.72599983
k_VBattMinAAS_Volt_f32	3.2658
k_VBattMinBSI_Volt_f32	9.72599983
k_VBattMinCAV_Volt_f32	14.7903004
k_VBattMinCMM388_Volt_f32	18.2980003
k_VBattMinCMM_Volt_f32	13.6489
k_VBattMinESP_Volt_f32	31.1229
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	2900
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	42497
k_VitesseVehicleBVRampValidThresh_Cnt_u16	54153
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	29386
k_VitesseVehicleBVSigValidThresh_Cnt_u16	34215
k_VitesseVehicleBVSpeedPassThresh_kph_f32	119.943802
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	25765
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	63111
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3052554496
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	44013
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	68495872
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	226
target_SrlComInput_Per1_Batt_Volt_f32.value	18.3199005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3165681920
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	228
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.336815685
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4228245760
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	176
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2097580288
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	295119104
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2713176320
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	359164160
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1420364032
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1199155456
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	59
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	85
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	92
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	176
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	201
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	182
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2996619520
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	125
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	141
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	161
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	188
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	211
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	218
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2390026496
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3572861184
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4010158336
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	45
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	80
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	106
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	129
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	137
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	153
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	730462464
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2768
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.482950032
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	378566
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	218.680298
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	39308

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	68495872	68495872	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	68495872	68495872	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	68495872	68495872	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	59725	59725	✔
BSINodeAbsentTimer_mS_M_u32	68495872	68495872	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	68495872	68495872	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
CDD_SrlComVehSpd_Kph_G_f32	125.3657	125.3657	✔
CMM388NTCEnableTimer_mS_M_u32	68495872	68495872	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	68495872	68495872	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	13347	13347	✔
CONSANGLECPK_HwDeg_M_f32	-79.2837982	-79.2837982 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	68495872	68495872	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	68495872	68495872	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	68495872	68495872	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	68495872	68495872	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	68495872	68495872	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	68495872	68495872	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	68495872	68495872	✔
ESPNTCEnableTimer_mS_M_u32	68495872	68495872	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	80	80	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	88	88	✔
ElecIntTimer_mS_M_u32[1]	110	110	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	68495872	68495872	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	33762	33762	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	158	158	✔
ISDATBSI3F2MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	30136	30136	✔
ISDATBSI412MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	51890	51890	✔
ISDATBSI432MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATDIRASentFltAcc_Cnt_M_u16	13378	13378	✔
ISDATDIRASentTimer_mS_M_u32	68495872	68495872	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	31118	31118	✔
ISDYN2CMMMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	59417	59417	✔
ISDYNAASMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	13347	13347	✔
ISDYNABRMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	158	158	✔
ISDYNCMM208MsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	11180	11180	✔
ISDYNCMM388MsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	58200	58200	✔
ISDYNVOLMsgTimer_mS_M_u32	68495872	68495872	✔
IgnOnTimer_mS_M_u32	3432245504	3432245504	✔
IgnTimeOff_Sec_M_u32	794314317	794314317	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	66	66	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4228245760	4228245760	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	176	176	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2097580288	2097580288	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	190	190	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	295119104	295119104	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	83	83	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2713176320	2713176320	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2688035072	2688035072	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	181	181	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1420364032	1420364032	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	81	81	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1199155456	1199155456	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	182	182	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2996619520	2996619520	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	26	26	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2390026496	2390026496	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3572861184	3572861184	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4010158336	4010158336	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	730462464	730462464	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	190.886597	190.886597	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	565.914124	565.914124	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	67.2381973	67.2381973	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	13347	13347	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	794314317	794314317	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-79.2837982	-79.2837982 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.392 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2416064512
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	41748
AASNodeAbsentTimer_mS_M_u32	1597483008
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	35277
ANGLEVOLANTSigValidCount_Cnt_M_u16	46928
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	55113
AngleVolantMsgTimer_mS_M_u32	2416064512
AngleVolantValidCount_Cnt_M_u16	56733
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1076979712
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	573302784
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2135152640
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3495204864
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	20828
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1903712256
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	46034
CAVNodeAbsentTimer_mS_M_u32	2699905024
CDD_SrlComVehSpd_Kph_G_f32	544.971497
CMM388NTCEnableTimer_mS_M_u32	647989248
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1863534592
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	23161
CMMNodeAbsentTimer_mS_M_u32	2494470144
CONSANGLECPKSigInvalidCount_Cnt_M_u16	42674
CONSANGLECPKSigValidCount_Cnt_M_u16	10501
CONSANGLECPK_Cnt_M_u16	43928
CONSANGLECPK_HwDeg_M_f32	-74.1121979
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43928
CPKVehicleSpeedMsgTimer_mS_M_u32	2332637184
CPKVehicleSpeedValidCount_Cnt_M_u16	63946
CityParkInputConsistentCount_Cnt_M_u16	63841
CityParkInputInvalidCount_Cnt_M_u16	56781
CityParkInputMsgTimer_mS_M_u32	4228245760
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1811654656
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	9432

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3221866496
ComputerRazGCTSigValidCount_Cnt_M_u16	42638
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	48649
DMDFCTCPKSigValidCount_Cnt_M_u16	2740
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	63151
DMDRELAXECPKSigValidCount_Cnt_M_u16	27058
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	35815
DateInvalidTimer_mS_M_u32	573302784
DiagMuxOnAbsentTimer_mS_M_u32	17168384
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3495204864
ESPNTCEnableTimer_mS_M_u32	1576052736
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	1944
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	64
EffacDefaultDiagTimer_mS_M_u32[1]	894
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	12
ElecIntTimer_mS_M_u32[1]	18
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2646235136
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	29784
EtatMTSigValidCount_Cnt_M_u16	50791
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	14740
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	33127
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	49882
ISDAT4V2BSI552MsgTimer_mS_M_u32	1819449344
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	49379
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	51194
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	50791
ISDATBSI3F2MsgTimer_mS_M_u32	3324246016
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	60367
ISDATBSI412MsgLenValidCount_Cnt_M_u16	14230
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	29784
ISDATBSI412MsgTimer_mS_M_u32	723531776
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	15677
ISDATBSI432MsgLenValidCount_Cnt_M_u16	13660
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	24747
ISDATDIRASentFltAcc_Cnt_M_u16	11775
ISDATDIRASentTimer_mS_M_u32	2332637184
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	43830
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	56733
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	29464
ISDYN2CMMMsgTimer_mS_M_u32	1791666176
ISDYNAASChkSumInvalidCount_Cnt_M_u16	48118
ISDYNAASChkSumValidCount_Cnt_M_u16	48537
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	26796
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	39077
ISDYNAASMsgLenValidCount_Cnt_M_u16	36352
ISDYNAASMsgTimeValidCount_Cnt_M_u16	48118
ISDYNAASMsgTimer_mS_M_u32	2749073408
ISDYNABRChkSumInvalidCount_Cnt_M_u16	52383
ISDYNABRChkSumValidCount_Cnt_M_u16	21802
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	1413
ISDYNABRMsgCountValidCount_Cnt_M_u16	25704
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	56129
ISDYNABRMsgLenValidCount_Cnt_M_u16	64212
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43928
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	32155
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	19434
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	50791
ISDYNCMM208MsgTimer_mS_M_u32	3214829568
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	32155
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	19434
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	18363

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	302188544
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	25552
ISDYNVOLChkSumValidCount_Cnt_M_u16	8355
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	42535
ISDYNVOLMsgCountValidCount_Cnt_M_u16	27986
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	21769
ISDYNVOLMsgLenValidCount_Cnt_M_u16	25404
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	23161
ISDYNVOLMsgTimer_mS_M_u32	2303051776
IgnOnTimer_mS_M_u32	3972466688
IgnTimeOff_Sec_M_u32	2653065473
ManVehSpd_Kph_M_f32	460.379608
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	215
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	162
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	959051776
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	13
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1957877760
PrevISDATBSI412MsgDLCError_Cnt_M_u08	207
PrevISDATBSI412MsgRxTime_MSec_M_u32	1854294016
PrevISDATBSI432MsgDLCError_Cnt_M_u08	16
PrevISDATBSI432MsgRxTime_MSec_M_u32	1923393536
PrevISDATDIRAMsgTxTime_MSec_M_u32	1390036992
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	168
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4196276224
PrevISDYNAASMsgDLCError_Cnt_M_u08	193
PrevISDYNAASMsgRxTime_MSec_M_u32	2430846976
PrevISDYNABRMsgDLCError_Cnt_M_u08	199
PrevISDYNABRMsgRxTime_MSec_M_u32	574556160
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	156
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2446379008
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	196
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2318903296
PrevISDYNVOLMsgDLCError_Cnt_M_u08	87
PrevISDYNVOLMsgRxTime_MSec_M_u32	4236986368
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	20854784
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	174.723694
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	22211
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	18078
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	19892
VitesseVehicleBVRampValidCount_Cnt_M_u16	16463
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	5694
VitesseVehicleBVSigValidCount_Cnt_M_u16	26241
VitesseVehicleBV_Kph_M_f32	62.3534012
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	18363
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	55542
VitesseVehiculeRoues_Kph_M_f32	295.695587
k_AASNTCEnableTimeout_mS_u16	10975
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	18408
k_AASNodeTimeout_mS_u16	61854
k_ABSNodeTimeout_mS_u16	822
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	24264
k_ANGLEVOLANTSigValidThresh_Cnt_u16	63783
k_AngleVolantInvalidThresh_Cnt_u16	50238
k_AngleVolantValidThresh_Cnt_u16	56781
k_BSI552MsgTimeout_mS_u16	14029
k_BSINTCEnableTimeout_mS_u16	25269
k_BSINodeAbsentDiag_Cnt_str.Threshold	45173
k_BSINodeAbsentDiag_Cnt_str.PStep	49618
k_BSINodeAbsentDiag_Cnt_str.NStep	21891
k_BSINodeAbsentTimeout_mS_u16	24257
k_BSINodeTimeout_mS_u16	24747
k_BattOvHi_Volt_f32	1.52569997
k_BattOvLo_Volt_f32	18.0112991
k_BattUvHi_Volt_f32	11.7126999
k_BattUvLo_Volt_f32	26.9109001
k_CAVNTCEnableTimeout_mS_u16	53603
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	54512
k_CAVNodeTimeout_mS_u16	23534
k_CMM388MsgTimeout_mS_u16	36372
k_CMM388NTCEnableTimeout_mS_u16	19536
k_CMMNTCEnableTimeout_mS_u16	25179
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	15666
k_CONSANGLECPKMax_HwDeg_f32	171.364807
k_CONSANGLECPKMin_HwDeg_f32	-464.069489
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	45755
k_CONSANGLECPKSigValidThresh_Cnt_u16	33782
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	3268
k_CPKVehicleSpeedValidThresh_Cnt_u16	26722
k_CityParkInputInvalidThresh_Cnt_u16	69
k_CityParkInputValidThresh_Cnt_u16	63841
k_ComputerRazGCTSigValidThresh_Cnt_u16	27241
k_CptTemporelSigValidThresh_Cnt_u16	43520
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	50753
k_DMDFCTCPKSigValidThresh_Cnt_u16	9684
k_DMDFCTCPKValidCount_Cnt_u16	17636
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	29464
k_DMDRELAXECPKSigValidThresh_Cnt_u16	48387
k_DMDRelaxeConsistentThresh_Cnt_u16	53801
k_DateValidThresh_Cnt_u16	49882
k_DefaultVehSpd_Kph_f32	119.610703
k_DiagMuxOnAbsentTimeout_mS_u16	62638
k_EMNodeTimeout_mS_u16	24135
k_ESPNTCEnableTimeout_mS_u16	56078
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	24506
k_EtatMTSigInvalidThresh_Cnt_u16	1686
k_EtatMTSigValidThresh_Cnt_u16	60001
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	34871
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	64550
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	4690
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	39736
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	10255
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	58515
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	1298
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	41713
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	24577
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	30396
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	24995
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	47295
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	20443
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	49452
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	55113
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	64346
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	14239
k_ISDYNAASChkSumValidThresh_Cnt_u16	42
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	61573
k_ISDYNAASMsgCountValidThresh_Cnt_u16	36712
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	62563
k_ISDYNAASMsgLenValidThresh_Cnt_u16	9570
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	2479
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	11103
k_ISDYNABRChkSumValidThresh_Cnt_u16	50546
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	15452
k_ISDYNABRMsgCountValidThresh_Cnt_u16	34591
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	1401
k_ISDYNABRMsgLenValidThresh_Cnt_u16	62104
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	48758
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	10887
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	27648
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	65141
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	29901
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	57936
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	18757
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	33242
k_ISDYNVOLChkSumValidThresh_Cnt_u16	53217
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	53965
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	34798
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	14484
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	32675
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	51952
k_IgnOnTimeout_mS_u16	22806
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	161.722504
k_PowerCutVehSpdLowThresh_Kph_f32	36.6053009
k_PowerCutVehSpdLowTimeout_mS_u16	31883
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	0.622600019
k_VBattMaxCAV_Volt_f32	26.4972992
k_VBattMaxCMM388_Volt_f32	24.4214993
k_VBattMaxCMM_Volt_f32	2.50670004
k_VBattMaxESP_Volt_f32	32
k_VBattMinAAS_Volt_f32	7.92859983
k_VBattMinBSI_Volt_f32	32
k_VBattMinCAV_Volt_f32	23.8542004
k_VBattMinCMM388_Volt_f32	13.3955002
k_VBattMinCMM_Volt_f32	26.4081993
k_VBattMinESP_Volt_f32	2.50670004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	55558
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	7101
k_VitesseVehicleBVRampValidThresh_Cnt_u16	4391
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	19363
k_VitesseVehicleBVSigValidThresh_Cnt_u16	58826
k_VitesseVehicleBVSpeedPassThresh_kph_f32	31.8209991
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	7890
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	19437
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	573302784
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65109
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3632743680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	196
target_SrlComInput_Per1_Batt_Volt_f32.value	13.5102997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	45176832
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	56
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0563158654
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2792425472
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	102
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1844389888
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	985483264
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	145
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1423665152
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	71927808
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	130
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2433198080
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	24
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1125500928
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	57
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	93
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	161
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	179
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	193
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	61
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4130105344
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	92
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	121
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1797523456
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3793889280
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	510674944
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	104
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	114
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	132
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	145
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4230273024
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2040
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.746820986
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	711430
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	251.469803
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	56349

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3632743680	3632743680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	45173	45173	✔
BSINodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
CDD_SrlComVehSpd_Kph_G_f32	460.379608	460.379608	✔
CMM388NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	43928	43928	✔
CONSANGLECPK_HwDeg_M_f32	-74.1121979	-74.1121979 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3632743680	3632743680	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3632743680	3632743680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3632743680	3632743680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3632743680	3632743680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3632743680	3632743680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3632743680	3632743680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3632743680	3632743680	✔
ESPNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	64	64	✔
EffacDefaultDiagTimer_mS_M_u32[1]	894	894	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	12	12	✔
ElecIntTimer_mS_M_u32[1]	18	18	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3632743680	3632743680	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	49882	49882	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	50791	50791	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	29784	29784	✔
ISDATBSI412MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	24747	24747	✔
ISDATBSI432MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	41895	41895	✔
ISDATDIRASentTimer_mS_M_u32	3632743680	3632743680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	29464	29464	✔
ISDYN2CMMMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	48118	48118	✔
ISDYNAASMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43928	43928	✔
ISDYNABRMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	50791	50791	✔
ISDYNCMM208MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	18363	18363	✔
ISDYNCMM388MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	23161	23161	✔
ISDYNVOLMsgTimer_mS_M_u32	3632743680	3632743680	✔
IgnOnTimer_mS_M_u32	3972466688	3972466688	✔
IgnTimeOff_Sec_M_u32	2653065473	2653065473	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	134	134	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2792425472	2792425472	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	102	102	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1844389888	1844389888	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	167	167	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	985483264	985483264	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	145	145	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1423665152	1423665152	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1390036992	1390036992	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	130	130	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2433198080	2433198080	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	24	24	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1125500928	1125500928	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	61	61	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4130105344	4130105344	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	123	123	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1797523456	1797523456	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	170	170	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3793889280	3793889280	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	251	251	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	510674944	510674944	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4230273024	4230273024	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	174.723694	174.723694	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	62.3534012	62.3534012	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	295.695587	295.695587	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	43928	43928	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2653065473	2653065473	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-74.1121979	-74.1121979 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.393 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	41425664
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	13120
AASNodeAbsentTimer_mS_M_u32	1989659392
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	279
ANGLEVOLANTSigValidCount_Cnt_M_u16	28750
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	43681
AngleVolantMsgTimer_mS_M_u32	41425664
AngleVolantValidCount_Cnt_M_u16	36901
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3937045248
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1320880896
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3274914560
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	50395904
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	42602
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1586871040
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	32647
CAVNodeAbsentTimer_mS_M_u32	267840256
CDD_SrlComVehSpd_Kph_G_f32	79.6331024
CMM388NTCEnableTimer_mS_M_u32	400567040
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3179604736
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	25682
CMMNodeAbsentTimer_mS_M_u32	2649946880
CONSANGLECPKSigInvalidCount_Cnt_M_u16	29029
CONSANGLECPKSigValidCount_Cnt_M_u16	8749
CONSANGLECPK_Cnt_M_u16	42612
CONSANGLECPK_HwDeg_M_f32	393.516998
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	42612
CPKVehicleSpeedMsgTimer_mS_M_u32	3982695168
CPKVehicleSpeedValidCount_Cnt_M_u16	40455
CityParkInputConsistentCount_Cnt_M_u16	19673
CityParkInputInvalidCount_Cnt_M_u16	23703
CityParkInputMsgTimer_mS_M_u32	2792425472
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1615579904
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	48628

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3298913024
ComputerRazGCTSigValidCount_Cnt_M_u16	14674
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	44003
DMDFCTCPKSigValidCount_Cnt_M_u16	23970
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	49777
DMDRELAXECPKSigValidCount_Cnt_M_u16	24872
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	54726
DateInvalidTimer_mS_M_u32	1320880896
DiagMuxOnAbsentTimer_mS_M_u32	1852627712
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	50395904
ESPNTCEnableTimer_mS_M_u32	2657929984
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	50357
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1123
EffacDefaultDiagTimer_mS_M_u32[1]	5523
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	79
ElecIntTimer_mS_M_u32[1]	101
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1641003776
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	41908
EtatMTSigValidCount_Cnt_M_u16	54599
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	49343
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	8455
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	19760
ISDAT4V2BSI552MsgTimer_mS_M_u32	648477440
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	24469
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	37392
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	54599
ISDATBSI3F2MsgTimer_mS_M_u32	387111680
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	57296
ISDATBSI412MsgLenValidCount_Cnt_M_u16	1083
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	41908
ISDATBSI412MsgTimer_mS_M_u32	689838848
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	52230
ISDATBSI432MsgLenValidCount_Cnt_M_u16	19305
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	7420
ISDATDIRASentFltAcc_Cnt_M_u16	1280
ISDATDIRASentTimer_mS_M_u32	3982695168
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	40858
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	36901
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	34998
ISDYN2CMMMsgTimer_mS_M_u32	1608436480
ISDYNAASChkSumInvalidCount_Cnt_M_u16	61594
ISDYNAASChkSumValidCount_Cnt_M_u16	25457
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	60152
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	56590
ISDYNAASMsgLenValidCount_Cnt_M_u16	21693
ISDYNAASMsgTimeValidCount_Cnt_M_u16	61594
ISDYNAASMsgTimer_mS_M_u32	2418813696
ISDYNABRChkSumInvalidCount_Cnt_M_u16	64031
ISDYNABRChkSumValidCount_Cnt_M_u16	30783
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	4077
ISDYNABRMsgCountValidCount_Cnt_M_u16	27396
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	53176
ISDYNABRMsgLenValidCount_Cnt_M_u16	43200
ISDYNABRMsgTimeValidCount_Cnt_M_u16	42612
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	21483
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	4286
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	54599
ISDYNCMM208MsgTimer_mS_M_u32	1617136384
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	21483
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	4286
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	18891

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1135979264
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	12811
ISDYNVOLChkSumValidCount_Cnt_M_u16	13139
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	60297
ISDYNVOLMsgCountValidCount_Cnt_M_u16	11720
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	57442
ISDYNVOLMsgLenValidCount_Cnt_M_u16	28041
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	25682
ISDYNVOLMsgTimer_mS_M_u32	1491954432
IgnOnTimer_mS_M_u32	3278482176
IgnTimeOff_Sec_M_u32	837193210
ManVehSpd_Kph_M_f32	378.916809
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	0
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	221
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1442896640
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	238
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1592146688
PrevISDATBSI412MsgDLCError_Cnt_M_u08	201
PrevISDATBSI412MsgRxTime_MSec_M_u32	1261169408
PrevISDATBSI432MsgDLCError_Cnt_M_u08	102
PrevISDATBSI432MsgRxTime_MSec_M_u32	810601216
PrevISDATDIRAMsgTxTime_MSec_M_u32	3996117760
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	152
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2342812416
PrevISDYNAASMsgDLCError_Cnt_M_u08	89
PrevISDYNAASMsgRxTime_MSec_M_u32	974351104
PrevISDYNABRMsgDLCError_Cnt_M_u08	26
PrevISDYNABRMsgRxTime_MSec_M_u32	50440960
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	60
PrevISDYNCMM208MsgRxTime_MSec_M_u32	726428416
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	238
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4120365824
PrevISDYNVOLMsgDLCError_Cnt_M_u08	142
PrevISDYNVOLMsgRxTime_MSec_M_u32	4112313088
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2663652096
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	190.483597
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	39604
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	8931
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	47585
VitesseVehicleBVRampValidCount_Cnt_M_u16	14800
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	24516
VitesseVehicleBVSigValidCount_Cnt_M_u16	26299
VitesseVehicleBV_Kph_M_f32	114.8181
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	18891
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	28122
VitesseVehiculeRoues_Kph_M_f32	577.487671
k_AASNTCEnableTimeout_mS_u16	1183
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	15684
k_AASNodeTimeout_mS_u16	8675
k_ABSNodeTimeout_mS_u16	53340
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	21349
k_ANGLEVOLANTSigValidThresh_Cnt_u16	60424
k_AngleVolantInvalidThresh_Cnt_u16	42691
k_AngleVolantValidThresh_Cnt_u16	23703
k_BSI552MsgTimeout_mS_u16	28757
k_BSINTCEnableTimeout_mS_u16	15262
k_BSINodeAbsentDiag_Cnt_str.Threshold	64221
k_BSINodeAbsentDiag_Cnt_str.PStep	20230
k_BSINodeAbsentDiag_Cnt_str.NStep	27699
k_BSINodeAbsentTimeout_mS_u16	62521
k_BSINodeTimeout_mS_u16	7420
k_BattOvHi_Volt_f32	7.5781002
k_BattOvLo_Volt_f32	12.0445004
k_BattUvHi_Volt_f32	13.6429005
k_BattUvLo_Volt_f32	25.9074001
k_CAVNTCEnableTimeout_mS_u16	22997
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	5165
k_CAVNodeTimeout_mS_u16	16817
k_CMM388MsgTimeout_mS_u16	29248
k_CMM388NTCEnableTimeout_mS_u16	10124
k_CMMNTCEnableTimeout_mS_u16	23341
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	12582
k_CONSANGLECPKMax_HwDeg_f32	439.260101
k_CONSANGLECPKMin_HwDeg_f32	-409.10611
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	2251
k_CONSANGLECPKSigValidThresh_Cnt_u16	27866
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	59505
k_CPKVehicleSpeedValidThresh_Cnt_u16	30231
k_CityParkInputInvalidThresh_Cnt_u16	30509
k_CityParkInputValidThresh_Cnt_u16	19673
k_ComputerRazGCTSigValidThresh_Cnt_u16	64259
k_CptTemporelSigValidThresh_Cnt_u16	33790
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	3768
k_DMDFCTCPKSigValidThresh_Cnt_u16	10176
k_DMDFCTCPKValidCount_Cnt_u16	60370
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	34998
k_DMDRELAXECPKSigValidThresh_Cnt_u16	17077
k_DMDRelaxeConsistentThresh_Cnt_u16	6979
k_DateValidThresh_Cnt_u16	19760
k_DefaultVehSpd_Kph_f32	220.162994
k_DiagMuxOnAbsentTimeout_mS_u16	41778
k_EMNodeTimeout_mS_u16	56998
k_ESPNTCEnableTimeout_mS_u16	63955
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	59790
k_EtatMTSigInvalidThresh_Cnt_u16	59450
k_EtatMTSigValidThresh_Cnt_u16	21658
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	536
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	19980
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	1542
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	25750
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	1489
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	1412
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	2183
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	38570
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	29626
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	54536
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	39955
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	35327
k_ISDATDIRASentDiag_Cnt_str.Threshold	12314

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	25984
k_ISDATDIRASentDiag_Cnt_str.NStep	21340
k_ISDATDIRASentTimeout_mS_u16	24683
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	25784
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	43681
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	51439
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	47391
k_ISDYNAASChkSumValidThresh_Cnt_u16	30527
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	20205
k_ISDYNAASMsgCountValidThresh_Cnt_u16	59908
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	37587
k_ISDYNAASMsgLenValidThresh_Cnt_u16	38551
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	55920
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	55134
k_ISDYNABRChkSumValidThresh_Cnt_u16	16614
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	58730
k_ISDYNABRMsgCountValidThresh_Cnt_u16	64737
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	25426
k_ISDYNABRMsgLenValidThresh_Cnt_u16	949
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	29404
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	12136
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	25405
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	5982
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	16407
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	61262
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	64047
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	2479
k_ISDYNVOLChkSumValidThresh_Cnt_u16	10074
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	30486
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	61427
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	18176
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	39315
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	3310
k_IgnOnTimeout_mS_u16	29691
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	24.3276005
k_PowerCutVehSpdLowThresh_Kph_f32	151.679092
k_PowerCutVehSpdLowTimeout_mS_u16	49051
k_VBattMaxAAS_Volt_f32	3.98510003
k_VBattMaxBSI_Volt_f32	24.3640003
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	9.78269958
k_VBattMaxCMM_Volt_f32	18.5184002
k_VBattMaxESP_Volt_f32	30.3267002
k_VBattMinAAS_Volt_f32	5.70079994
k_VBattMinBSI_Volt_f32	30.3267002
k_VBattMinCAV_Volt_f32	4.42710018
k_VBattMinCMM388_Volt_f32	2.6098001
k_VBattMinCMM_Volt_f32	32
k_VBattMinESP_Volt_f32	18.5184002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	1322
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	1221
k_VitesseVehicleBVRampValidThresh_Cnt_u16	43657
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	45651
k_VitesseVehicleBVSigValidThresh_Cnt_u16	27550
k_VitesseVehicleBVSpeedPassThresh_kph_f32	373.705292
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	16007
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	3830
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1320880896
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60393
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1305159680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	238
target_SrlComInput_Per1_Batt_Volt_f32.value	26.2185001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3471489792
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	37
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.463410884
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3194727168
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	231
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2289126144
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	228
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2189880064
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3568077568
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2799840000
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	556256000
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	17
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1803381504
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	145
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	234
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	165
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1958316800
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	63
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	97
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	105
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	151
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	174
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	175
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4233276160
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3084405504
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1668147968
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	118
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	166
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	186
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	187
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	277887744
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2788
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.505818129
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1017415
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	236.335602
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	62118

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1305159680	1305159680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	64221	64221	✔
BSINodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔
CDD_SrlComVehSpd_Kph_G_f32	378.916809	378.916809	✔
CMM388NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	42612	42612	✔
CONSANGLECPK_HwDeg_M_f32	393.516998	393.516998 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1305159680	1305159680	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1305159680	1305159680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1305159680	1305159680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1305159680	1305159680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1305159680	1305159680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1305159680	1305159680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1305159680	1305159680	✔
ESPNTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1123	1123	✔
EffacDefaultDiagTimer_mS_M_u32[1]	5523	5523	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	79	79	✔
ElecIntTimer_mS_M_u32[1]	101	101	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1305159680	1305159680	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	19760	19760	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	54599	54599	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	41908	41908	✔
ISDATBSI412MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	7420	7420	✔
ISDATBSI432MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	12314	12314	✔
ISDATDIRASentTimer_mS_M_u32	1305159680	1305159680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	34998	34998	✔
ISDYN2CMMMsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	61594	61594	✔
ISDYNAASMsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	42612	42612	✔
ISDYNABRMsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	54599	54599	✔
ISDYNCMM208MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	18891	18891	✔
ISDYNCMM388MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	25682	25682	✔
ISDYNVOLMsgTimer_mS_M_u32	1305159680	1305159680	✔
IgnOnTimer_mS_M_u32	3278482176	3278482176	✔
IgnTimeOff_Sec_M_u32	837193210	837193210	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3194727168	3194727168	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	231	231	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2289126144	2289126144	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	228	228	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2189880064	2189880064	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3568077568	3568077568	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3996117760	3996117760	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	556256000	556256000	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	17	17	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1803381504	1803381504	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	165	165	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1958316800	1958316800	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	180	180	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4233276160	4233276160	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	166	166	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3084405504	3084405504	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	117	117	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1668147968	1668147968	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	277887744	277887744	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	190.483597	190.483597	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	114.8181	114.8181	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	577.487671	577.487671	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	42612	42612	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	837193210	837193210	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	393.516998	393.516998 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.394 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2629790976
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	51147
AASNodeAbsentTimer_mS_M_u32	2438765824
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	10326
ANGLEVOLANTSigValidCount_Cnt_M_u16	31943
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	25140
AngleVolantMsgTimer_mS_M_u32	2629790976
AngleVolantValidCount_Cnt_M_u16	60629
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1141202176
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2090458368
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1750306048
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1016024320
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	45121
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3804892416
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	23372
CAVNodeAbsentTimer_mS_M_u32	2595536128
CDD_SrlComVehSpd_Kph_G_f32	57.858799
CMM388NTCEnableTimer_mS_M_u32	2749889792
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1689435392
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	41961
CMMNodeAbsentTimer_mS_M_u32	4279323904
CONSANGLECPKSigInvalidCount_Cnt_M_u16	6427
CONSANGLECPKSigValidCount_Cnt_M_u16	15259
CONSANGLECPK_Cnt_M_u16	47642
CONSANGLECPK_HwDeg_M_f32	299.951813
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	47642
CPKVehicleSpeedMsgTimer_mS_M_u32	1459776768
CPKVehicleSpeedValidCount_Cnt_M_u16	46364
CityParkInputConsistentCount_Cnt_M_u16	44841
CityParkInputInvalidCount_Cnt_M_u16	34521
CityParkInputMsgTimer_mS_M_u32	549962240
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3903888640
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	51231

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	951270656
ComputerRazGCTSigValidCount_Cnt_M_u16	10090
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	12421
DMDFCTCPKSigValidCount_Cnt_M_u16	7102
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	33920
DMDRELAXECPKSigValidCount_Cnt_M_u16	33905
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	2180
DateInvalidTimer_mS_M_u32	2090458368
DiagMuxOnAbsentTimer_mS_M_u32	3596233984
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1016024320
ESPNTCEnableTimer_mS_M_u32	2144967936
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	21222
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	19
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2413038848
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	51294
EtatMTSigValidCount_Cnt_M_u16	21002
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	29509
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	49477
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	14268
ISDAT4V2BSI552MsgTimer_mS_M_u32	3982839040
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	48710
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	36890
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	21002
ISDATBSI3F2MsgTimer_mS_M_u32	875572480
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	21083
ISDATBSI412MsgLenValidCount_Cnt_M_u16	9632
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	51294
ISDATBSI412MsgTimer_mS_M_u32	1754623232
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	26941
ISDATBSI432MsgLenValidCount_Cnt_M_u16	12090
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	27753
ISDATDIRASentFltAcc_Cnt_M_u16	13453
ISDATDIRASentTimer_mS_M_u32	1459776768
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	60528
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	60629
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	44016
ISDYN2CMMMsgTimer_mS_M_u32	2631638272
ISDYNAASChkSumInvalidCount_Cnt_M_u16	65525
ISDYNAASChkSumValidCount_Cnt_M_u16	29958
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	54848
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	32011
ISDYNAASMsgLenValidCount_Cnt_M_u16	56755
ISDYNAASMsgTimeValidCount_Cnt_M_u16	65525
ISDYNAASMsgTimer_mS_M_u32	3197369600
ISDYNABRChkSumInvalidCount_Cnt_M_u16	33958
ISDYNABRChkSumValidCount_Cnt_M_u16	40766
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	53728
ISDYNABRMsgCountValidCount_Cnt_M_u16	28977
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	8710
ISDYNABRMsgLenValidCount_Cnt_M_u16	44742
ISDYNABRMsgTimeValidCount_Cnt_M_u16	47642
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	21069
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	49465
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	21002
ISDYNCMM208MsgTimer_mS_M_u32	2407947520
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	21069
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	49465
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	58283

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3932781824
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	20209
ISDYNVOLChkSumValidCount_Cnt_M_u16	17905
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	56667
ISDYNVOLMsgCountValidCount_Cnt_M_u16	56596
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	37883
ISDYNVOLMsgLenValidCount_Cnt_M_u16	30172
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	41961
ISDYNVOLMsgTimer_mS_M_u32	1331641600
IgnOnTimer_mS_M_u32	2277342464
IgnTimeOff_Sec_M_u32	163205695
ManVehSpd_Kph_M_f32	288.855591
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	2
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	154
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	445525248
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	223
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2577304832
PrevISDATBSI412MsgDLCError_Cnt_M_u08	244
PrevISDATBSI412MsgRxTime_MSec_M_u32	932297984
PrevISDATBSI432MsgDLCError_Cnt_M_u08	78
PrevISDATBSI432MsgRxTime_MSec_M_u32	1088265472
PrevISDATDIRAMsgTxTime_MSec_M_u32	2461383936
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	165
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1984875776
PrevISDYNAASMsgDLCError_Cnt_M_u08	78
PrevISDYNAASMsgRxTime_MSec_M_u32	2847227136
PrevISDYNABRMsgDLCError_Cnt_M_u08	234
PrevISDYNABRMsgRxTime_MSec_M_u32	2216000768
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	86
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1287011584
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	170
PrevISDYNCMM388MsgRxTime_MSec_M_u32	140287232
PrevISDYNVOLMsgDLCError_Cnt_M_u08	147
PrevISDYNVOLMsgRxTime_MSec_M_u32	420134144
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4218121472
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	122.279999
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	38881
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	36105
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	63606
VitesseVehicleBVRampValidCount_Cnt_M_u16	41822
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	50283
VitesseVehicleBVSigValidCount_Cnt_M_u16	28316
VitesseVehicleBV_Kph_M_f32	543.736816
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	58283
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	21428
VitesseVehiculeRoues_Kph_M_f32	39.0318985
k_AASNTCEnableTimeout_mS_u16	33181
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	39660
k_AASNodeTimeout_mS_u16	33801
k_ABSNodeTimeout_mS_u16	41158
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	50068
k_ANGLEVOLANTSigValidThresh_Cnt_u16	27857
k_AngleVolantInvalidThresh_Cnt_u16	62820
k_AngleVolantValidThresh_Cnt_u16	34521
k_BSI552MsgTimeout_mS_u16	25095
k_BSINTCEnableTimeout_mS_u16	5525
k_BSINodeAbsentDiag_Cnt_str.Threshold	42962
k_BSINodeAbsentDiag_Cnt_str.PStep	12737
k_BSINodeAbsentDiag_Cnt_str.NStep	27861
k_BSINodeAbsentTimeout_mS_u16	47244
k_BSINodeTimeout_mS_u16	27753
k_BattOvHi_Volt_f32	26.1846008
k_BattOvLo_Volt_f32	29.5021992
k_BattUvHi_Volt_f32	25.0354004
k_BattUvLo_Volt_f32	6.8755002
k_CAVNTCEnableTimeout_mS_u16	40455
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	1314
k_CAVNodeTimeout_mS_u16	19399
k_CMM388MsgTimeout_mS_u16	65227
k_CMM388NTCEnableTimeout_mS_u16	15991
k_CMMNTCEnableTimeout_mS_u16	22174
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	4448
k_CONSANGLECPKMax_HwDeg_f32	7.23280001
k_CONSANGLECPKMin_HwDeg_f32	-279.104492
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	39595
k_CONSANGLECPKSigValidThresh_Cnt_u16	19124
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	12039
k_CPKVehicleSpeedValidThresh_Cnt_u16	29402
k_CityParkInputInvalidThresh_Cnt_u16	39460
k_CityParkInputValidThresh_Cnt_u16	44841
k_ComputerRazGCTSigValidThresh_Cnt_u16	58660
k_CptTemporelSigValidThresh_Cnt_u16	49528
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	22790
k_DMDFCTCPKSigValidThresh_Cnt_u16	9670
k_DMDFCTCPKValidCount_Cnt_u16	24809
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	44016
k_DMDRELAXECPKSigValidThresh_Cnt_u16	57705
k_DMDRelaxeConsistentThresh_Cnt_u16	11879
k_DateValidThresh_Cnt_u16	14268
k_DefaultVehSpd_Kph_f32	108.992401
k_DiagMuxOnAbsentTimeout_mS_u16	52424
k_EMNodeTimeout_mS_u16	22628
k_ESPNTCEnableTimeout_mS_u16	34808
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	52488
k_EtatMTSigInvalidThresh_Cnt_u16	56217
k_EtatMTSigValidThresh_Cnt_u16	22129
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	60902
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	25843
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	31166
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	21327
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	2531
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	50607
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	61894
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	15491
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	28305
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	32078
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	2099
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	32772
k_ISDATDIRASentDiag_Cnt_str.Threshold	1905

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	4278
k_ISDATDIRASentDiag_Cnt_str.NStep	49319
k_ISDATDIRASentTimeout_mS_u16	64850
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	22661
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	25140
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	12276
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	15270
k_ISDYNAASChkSumValidThresh_Cnt_u16	38462
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	2272
k_ISDYNAASMsgCountValidThresh_Cnt_u16	59441
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	762
k_ISDYNAASMsgLenValidThresh_Cnt_u16	48733
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	3705
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	55004
k_ISDYNABRChkSumValidThresh_Cnt_u16	30748
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	59201
k_ISDYNABRMsgCountValidThresh_Cnt_u16	9714
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	39657
k_ISDYNABRMsgLenValidThresh_Cnt_u16	35302
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	17349
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	62005
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	14640
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	7516
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	24406
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	62407
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	53553
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	25394
k_ISDYNVOLChkSumValidThresh_Cnt_u16	63927
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	79
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	62610
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	26122
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	6326
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	9578
k_IgnOnTimeout_mS_u16	65502
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	167.473297
k_PowerCutVehSpdLowThresh_Kph_f32	177.637405
k_PowerCutVehSpdLowTimeout_mS_u16	29817
k_VBattMaxAAS_Volt_f32	32
k_VBattMaxBSI_Volt_f32	30.6245995
k_VBattMaxCAV_Volt_f32	0.870400012
k_VBattMaxCMM388_Volt_f32	31.0706997
k_VBattMaxCMM_Volt_f32	7.53439999
k_VBattMaxESP_Volt_f32	6.23619986
k_VBattMinAAS_Volt_f32	20.2439003
k_VBattMinBSI_Volt_f32	6.23619986
k_VBattMinCAV_Volt_f32	20.8330994
k_VBattMinCMM388_Volt_f32	0.997699976
k_VBattMinCMM_Volt_f32	22.3549004
k_VBattMinESP_Volt_f32	7.53439999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	19591
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	21628
k_VitesseVehicleBVRampValidThresh_Cnt_u16	37979
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	48369
k_VitesseVehicleBVSigValidThresh_Cnt_u16	52246
k_VitesseVehicleBVSpeedPassThresh_kph_f32	634.217529
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	4684
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	37300
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2090458368
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	21877
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2683494912
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	170
target_SrlComInput_Per1_Batt_Volt_f32.value	28.6571007
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1573326080
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	219
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.507553101
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	718241024
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	244
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2382503168
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	566541568
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	182
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1310153984
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2063203584
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	275553536
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1987001600
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	45
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	134
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	183
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	190
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	124
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	915168512
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	37
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	130
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	194
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	236
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	804158720
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	128
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	278994176
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	76
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3789798656
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	50
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	155
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3902311680
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3742
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.491468459
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	0
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	242.045898
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	65379

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2683494912	2683494912	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	42962	42962	✔
BSINodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔
CDD_SrlComVehSpd_Kph_G_f32	288.855591	288.855591	✔
CMM388NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	47642	47642	✔
CONSANGLECPK_HwDeg_M_f32	299.951813	299.951813 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2683494912	2683494912	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2683494912	2683494912	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2683494912	2683494912	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2683494912	2683494912	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2683494912	2683494912	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2683494912	2683494912	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2683494912	2683494912	✔
ESPNTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	6	6	✔
ElecIntTimer_mS_M_u32[1]	19	19	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2683494912	2683494912	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	14268	14268	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	21002	21002	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	51294	51294	✔
ISDATBSI412MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	27753	27753	✔
ISDATBSI432MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1905	1905	✔
ISDATDIRASentTimer_mS_M_u32	2683494912	2683494912	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	44016	44016	✔
ISDYN2CMMMsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	65525	65525	✔
ISDYNAASMsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	47642	47642	✔
ISDYNABRMsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	21002	21002	✔
ISDYNCMM208MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	58283	58283	✔
ISDYNCMM388MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	41961	41961	✔
ISDYNVOLMsgTimer_mS_M_u32	2683494912	2683494912	✔
IgnOnTimer_mS_M_u32	2277342464	2277342464	✔
IgnTimeOff_Sec_M_u32	163205695	163205695	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	718241024	718241024	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	244	244	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2382503168	2382503168	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	99	99	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	566541568	566541568	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	182	182	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1310153984	1310153984	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2461383936	2461383936	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	170	170	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	275553536	275553536	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	26	26	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1987001600	1987001600	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	124	124	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	915168512	915168512	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	241	241	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	804158720	804158720	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	128	128	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	278994176	278994176	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	76	76	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3789798656	3789798656	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3902311680	3902311680	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	122.279999	122.279999	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	543.736816	543.736816	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	39.0318985	39.0318985	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	47642	47642	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	163205695	163205695	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	299.951813	299.951813 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.395 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2136243200
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	53294
AASNodeAbsentTimer_mS_M_u32	3527207936
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	63631
ANGLEVOLANTSigValidCount_Cnt_M_u16	55805
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	58611
AngleVolantMsgTimer_mS_M_u32	2136243200
AngleVolantValidCount_Cnt_M_u16	3986
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1296215040
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2508532736
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	353901568
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	929356800
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	52430
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2679413760
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	48686
CAVNodeAbsentTimer_mS_M_u32	3199503360
CDD_SrlComVehSpd_Kph_G_f32	238.746902
CMM388NTCEnableTimer_mS_M_u32	2149239808
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3636104192
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	2068
CMMNodeAbsentTimer_mS_M_u32	2011094016
CONSANGLECPKSigInvalidCount_Cnt_M_u16	10561
CONSANGLECPKSigValidCount_Cnt_M_u16	57471
CONSANGLECPK_Cnt_M_u16	8450
CONSANGLECPK_HwDeg_M_f32	-533.073608
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	8450
CPKVehicleSpeedMsgTimer_mS_M_u32	478903296
CPKVehicleSpeedValidCount_Cnt_M_u16	13764
CityParkInputConsistentCount_Cnt_M_u16	6294
CityParkInputInvalidCount_Cnt_M_u16	41605
CityParkInputMsgTimer_mS_M_u32	718241024
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	474016768
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	7986

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	4273540096
ComputerRazGCTSigValidCount_Cnt_M_u16	62419
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	21889
DMDFCTCPKSigValidCount_Cnt_M_u16	37527
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	3089
DMDRELAXECPKSigValidCount_Cnt_M_u16	60159
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	16134
DateInvalidTimer_mS_M_u32	2508532736
DiagMuxOnAbsentTimer_mS_M_u32	2911124480
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	929356800
ESPNTCEnableTimer_mS_M_u32	986049536
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	2526
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	65
EffacDefaultDiagTimer_mS_M_u32[1]	655
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	88
ElecIntTimer_mS_M_u32[1]	111
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1083612160
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	48056
EtatMTSigValidCount_Cnt_M_u16	60785
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	17091
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	30593
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	46749
ISDAT4V2BSI552MsgTimer_mS_M_u32	4242725888
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	53632
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	51906
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	60785
ISDATBSI3F2MsgTimer_mS_M_u32	1812085760
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	64064
ISDATBSI412MsgLenValidCount_Cnt_M_u16	44850
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	48056
ISDATBSI412MsgTimer_mS_M_u32	4090657792
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	2072
ISDATBSI432MsgLenValidCount_Cnt_M_u16	50402
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	16087
ISDATDIRASentFltAcc_Cnt_M_u16	30315
ISDATDIRASentTimer_mS_M_u32	478903296
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	25088
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	3986
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	20288
ISDYN2CMMMsgTimer_mS_M_u32	1807739904
ISDYNAASChkSumInvalidCount_Cnt_M_u16	20400
ISDYNAASChkSumValidCount_Cnt_M_u16	20286
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	48977
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	5361
ISDYNAASMsgLenValidCount_Cnt_M_u16	45495
ISDYNAASMsgTimeValidCount_Cnt_M_u16	20400
ISDYNAASMsgTimer_mS_M_u32	3759590400
ISDYNABRChkSumInvalidCount_Cnt_M_u16	31519
ISDYNABRChkSumValidCount_Cnt_M_u16	43541
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	17903
ISDYNABRMsgCountValidCount_Cnt_M_u16	50877
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	31360
ISDYNABRMsgLenValidCount_Cnt_M_u16	62206
ISDYNABRMsgTimeValidCount_Cnt_M_u16	8450
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	39403
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	7140
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	60785
ISDYNCMM208MsgTimer_mS_M_u32	2931796992
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	39403
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	7140
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	784

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2459323392
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	24511
ISDYNVOLChkSumValidCount_Cnt_M_u16	39293
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	9983
ISDYNVOLMsgCountValidCount_Cnt_M_u16	9877
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	55967
ISDYNVOLMsgLenValidCount_Cnt_M_u16	54205
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	2068
ISDYNVOLMsgTimer_mS_M_u32	1790249984
IgnOnTimer_mS_M_u32	177884160
IgnTimeOff_Sec_M_u32	1402469259
ManVehSpd_Kph_M_f32	286.062012
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	3
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	145
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2968009728
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	62
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1832328192
PrevISDATBSI412MsgDLCError_Cnt_M_u08	120
PrevISDATBSI412MsgRxTime_MSec_M_u32	2619182080
PrevISDATBSI432MsgDLCError_Cnt_M_u08	34
PrevISDATBSI432MsgRxTime_MSec_M_u32	129625088
PrevISDATDIRAMsgTxTime_MSec_M_u32	447843328
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	191
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3894828032
PrevISDYNAASMsgDLCError_Cnt_M_u08	119
PrevISDYNAASMsgRxTime_MSec_M_u32	867372032
PrevISDYNABRMsgDLCError_Cnt_M_u08	105
PrevISDYNABRMsgRxTime_MSec_M_u32	1972521984
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	70
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2393902080
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	180
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1832709120
PrevISDYNVOLMsgDLCError_Cnt_M_u08	144
PrevISDYNVOLMsgRxTime_MSec_M_u32	464686080
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	324041728
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	132.653503
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	40047
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	31669
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	3760
VitesseVehicleBVRampValidCount_Cnt_M_u16	52406
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	47184
VitesseVehicleBVSigValidCount_Cnt_M_u16	39038
VitesseVehicleBV_Kph_M_f32	168.143997
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	784
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	61878
VitesseVehiculeRoues_Kph_M_f32	481.105103
k_AASNTCEnableTimeout_mS_u16	38521
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	8525
k_AASNodeTimeout_mS_u16	38581
k_ABSNodeTimeout_mS_u16	18622
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	5395
k_ANGLEVOLANTSigValidThresh_Cnt_u16	10269
k_AngleVolantInvalidThresh_Cnt_u16	39524
k_AngleVolantValidThresh_Cnt_u16	41605
k_BSI552MsgTimeout_mS_u16	53949
k_BSINTCEnableTimeout_mS_u16	25360
k_BSINodeAbsentDiag_Cnt_str.Threshold	59098
k_BSINodeAbsentDiag_Cnt_str.PStep	59980
k_BSINodeAbsentDiag_Cnt_str.NStep	27219
k_BSINodeAbsentTimeout_mS_u16	16875
k_BSINodeTimeout_mS_u16	16087
k_BattOvHi_Volt_f32	20.9550991
k_BattOvLo_Volt_f32	17.5720997
k_BattUvHi_Volt_f32	10.5014
k_BattUvLo_Volt_f32	30.2910995
k_CAVNTCEnableTimeout_mS_u16	38139
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	39084
k_CAVNodeTimeout_mS_u16	16701
k_CMM388MsgTimeout_mS_u16	11054
k_CMM388NTCEnableTimeout_mS_u16	7210
k_CMMNTCEnableTimeout_mS_u16	26744
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	26802
k_CONSANGLECPKMax_HwDeg_f32	135.640396
k_CONSANGLECPKMin_HwDeg_f32	-274.286285
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	56848
k_CONSANGLECPKSigValidThresh_Cnt_u16	3254
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	3515
k_CPKVehicleSpeedValidThresh_Cnt_u16	21699
k_CityParkInputInvalidThresh_Cnt_u16	45733
k_CityParkInputValidThresh_Cnt_u16	6294
k_ComputerRazGCTSigValidThresh_Cnt_u16	21734
k_CptTemporelSigValidThresh_Cnt_u16	11944
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	54656
k_DMDFCTCPKSigValidThresh_Cnt_u16	36350
k_DMDFCTCPKValidCount_Cnt_u16	23254
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	20288
k_DMDRELAXECPKSigValidThresh_Cnt_u16	44438
k_DMDRelaxeConsistentThresh_Cnt_u16	16028
k_DateValidThresh_Cnt_u16	46749
k_DefaultVehSpd_Kph_f32	209.0961
k_DiagMuxOnAbsentTimeout_mS_u16	8440
k_EMNodeTimeout_mS_u16	53094
k_ESPNTCEnableTimeout_mS_u16	59434
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	54714
k_EtatMTSigInvalidThresh_Cnt_u16	582
k_EtatMTSigValidThresh_Cnt_u16	4220
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	3358
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	63160
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	19671
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	30309
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	49511
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	61508
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	53885
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	263
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	18460
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	42854
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	46456
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	42564
k_ISDATDIRASentDiag_Cnt_str.Threshold	6549

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	63930
k_ISDATDIRASentDiag_Cnt_str.NStep	24627
k_ISDATDIRASentTimeout_mS_u16	49435
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	24769
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58611
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	57398
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	22047
k_ISDYNAASChkSumValidThresh_Cnt_u16	50453
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	41199
k_ISDYNAASMsgCountValidThresh_Cnt_u16	25021
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	20515
k_ISDYNAASMsgLenValidThresh_Cnt_u16	14265
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	58149
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	13310
k_ISDYNABRChkSumValidThresh_Cnt_u16	28412
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	10190
k_ISDYNABRMsgCountValidThresh_Cnt_u16	19068
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	8980
k_ISDYNABRMsgLenValidThresh_Cnt_u16	25822
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	64771
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	56691
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	55745
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	54972
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	21391
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	29949
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	9085
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	58299
k_ISDYNVOLChkSumValidThresh_Cnt_u16	20205
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	58787
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	64025
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	37556
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	18797
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	9619
k_IgnOnTimeout_mS_u16	48567
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	118.153297
k_PowerCutVehSpdLowThresh_Kph_f32	127.661102
k_PowerCutVehSpdLowTimeout_mS_u16	11749
k_VBattMaxAAS_Volt_f32	28.4615993
k_VBattMaxBSI_Volt_f32	30.1452999
k_VBattMaxCAV_Volt_f32	11.5458002
k_VBattMaxCMM388_Volt_f32	12.7903996
k_VBattMaxCMM_Volt_f32	5.63679981
k_VBattMaxESP_Volt_f32	22.3896999
k_VBattMinAAS_Volt_f32	6.40560007
k_VBattMinBSI_Volt_f32	22.3896999
k_VBattMinCAV_Volt_f32	3.05909991
k_VBattMinCMM388_Volt_f32	1.78600001
k_VBattMinCMM_Volt_f32	27.0140991
k_VBattMinESP_Volt_f32	5.63679981
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	3259
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	58269
k_VitesseVehicleBVRampValidThresh_Cnt_u16	511
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	13437
k_VitesseVehicleBVSigValidThresh_Cnt_u16	46543
k_VitesseVehicleBVSpeedPassThresh_kph_f32	630.597717
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	39214
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	55732
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2508532736
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	180
target_SrlComInput_Per1_Batt_Volt_f32.value	4.91279984
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1656593408
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	187
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.535308123
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3915664384
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	140
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1380740096
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	243
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1770294272
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	236
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4144802816
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3269774336
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	182
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2500652032
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	22
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	897911808
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	25
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	63
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	167
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	250
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1370336256
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	32
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	46
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	166
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	202
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	96
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	369576960
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	36
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	107965440
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	115
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1697090560
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	43
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	204
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3897105408
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1886
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.557866573
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	65535
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	212.685699
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	60905

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	58611	58611	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	8450	8450	✔
CONSANGLECPK_HwDeg_M_f32	-533.073608	-533.073608 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	8450	8450	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	478903296	478903296	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	13764	13764	✔
CityParkInputConsistentCount_Cnt_M_u16	6294	6294	✔
CityParkInputInvalidCount_Cnt_M_u16	41607	41607	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	65	65	✔
EffacDefaultDiagTimer_mS_M_u32[1]	655	655	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3251510528	3251510528	✔
ElecIntTimer_mS_M_u32[1]	111	111	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	6549	6549	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	3251510528	3251510528	✔
IgnTimeOff_Sec_M_u32	1402469259	1402469259	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	239	239	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3915664384	3915664384	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	140	140	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1380740096	1380740096	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	243	243	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1770294272	1770294272	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	236	236	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4144802816	4144802816	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	447843328	447843328	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	182	182	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2500652032	2500652032	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	22	22	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	897911808	897911808	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	174	174	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1370336256	1370336256	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	96	96	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	369576960	369576960	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	36	36	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	107965440	107965440	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	115	115	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1697090560	1697090560	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3897105408	3897105408	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	132.653503	132.653503	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	168.143997	168.143997	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	481.105103	481.105103	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	8450	8450	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1402469259	1402469259	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-533.073608	-533.073608 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.396 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1116819200
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	55809
AASNodeAbsentTimer_mS_M_u32	3080191744
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	33504
ANGLEVOLANTSigValidCount_Cnt_M_u16	16982
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	61362
AngleVolantMsgTimer_mS_M_u32	1116819200
AngleVolantValidCount_Cnt_M_u16	4184
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2374418176
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3737075456
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2546364160
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1407201024
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	49699
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	166784768
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	5762
CAVNodeAbsentTimer_mS_M_u32	3635486464
CDD_SrlComVehSpd_Kph_G_f32	511.339691
CMM388NTCEnableTimer_mS_M_u32	4252917504
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	580853504
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	52624
CMMNodeAbsentTimer_mS_M_u32	4201787136
CONSANGLECPKSigInvalidCount_Cnt_M_u16	59339
CONSANGLECPKSigValidCount_Cnt_M_u16	26065
CONSANGLECPK_Cnt_M_u16	28744
CONSANGLECPK_HwDeg_M_f32	124.4151
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	28744
CPKVehicleSpeedMsgTimer_mS_M_u32	116150016
CPKVehicleSpeedValidCount_Cnt_M_u16	16552

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	1356
CityParkInputInvalidCount_Cnt_M_u16	13438
CityParkInputMsgTimer_mS_M_u32	3915664384
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3918266112
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	64757
ComputerRazGCTSigInvalidTimer_mS_M_u32	3399720704
ComputerRazGCTSigValidCount_Cnt_M_u16	42901
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	2954
DMDFCTCPKSigValidCount_Cnt_M_u16	22536
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	53338
DMDRELAXECPKSigValidCount_Cnt_M_u16	38736
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	64124
DateInvalidTimer_mS_M_u32	3737075456
DiagMuxOnAbsentTimer_mS_M_u32	654446336
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1407201024
ESPNTCEnableTimer_mS_M_u32	3791453952
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	39922
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1
ElecIntTimer_mS_M_u32[1]	14
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	793440000
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	20390
EtatMTSigValidCount_Cnt_M_u16	20024
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	9029
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	10443
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	33782
ISDAT4V2BSI552MsgTimer_mS_M_u32	2070294272
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	10189
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	61383
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	20024
ISDATBSI3F2MsgTimer_mS_M_u32	1669861120
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	65164
ISDATBSI412MsgLenValidCount_Cnt_M_u16	21366
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	20390
ISDATBSI412MsgTimer_mS_M_u32	1561808640
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	56708
ISDATBSI432MsgLenValidCount_Cnt_M_u16	31462
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	30855
ISDATDIRASentFltAcc_Cnt_M_u16	8651
ISDATDIRASentTimer_mS_M_u32	116150016
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	9550
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	4184
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	55885
ISDYN2CMMMsgTimer_mS_M_u32	3071213312
ISDYNAASChkSumInvalidCount_Cnt_M_u16	58235
ISDYNAASChkSumValidCount_Cnt_M_u16	51345
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	48411
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	56889
ISDYNAASMsgLenValidCount_Cnt_M_u16	52136
ISDYNAASMsgTimeValidCount_Cnt_M_u16	58235
ISDYNAASMsgTimer_mS_M_u32	3448397568
ISDYNABRChkSumInvalidCount_Cnt_M_u16	13487
ISDYNABRChkSumValidCount_Cnt_M_u16	11149
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	48318
ISDYNABRMsgCountValidCount_Cnt_M_u16	7700
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	45070
ISDYNABRMsgLenValidCount_Cnt_M_u16	59988
ISDYNABRMsgTimeValidCount_Cnt_M_u16	28744

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	16653
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	20191
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	20024
ISDYNCMM208MsgTimer_mS_M_u32	2635054848
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	16653
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	20191
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	44510
ISDYNCMM388MsgTimer_mS_M_u32	336322304
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	48209
ISDYNVOLChkSumValidCount_Cnt_M_u16	45783
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	3856
ISDYNVOLMsgCountValidCount_Cnt_M_u16	5134
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	28079
ISDYNVOLMsgLenValidCount_Cnt_M_u16	42517
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	52624
ISDYNVOLMsgTimer_mS_M_u32	1991220992
IgnOnTimer_mS_M_u32	3154108160
IgnTimeOff_Sec_M_u32	2076488099
ManVehSpd_Kph_M_f32	117.498497
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	4
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	229
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2899709696
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	106
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3412684544
PrevISDATBSI412MsgDLCError_Cnt_M_u08	88
PrevISDATBSI412MsgRxTime_MSec_M_u32	611720960
PrevISDATBSI432MsgDLCError_Cnt_M_u08	52
PrevISDATBSI432MsgRxTime_MSec_M_u32	1260453632
PrevISDATDIRAMsgTxTime_MSec_M_u32	4172947200
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	119
PrevISDYN2CMMMsgRxTime_MSec_M_u32	664514304
PrevISDYNAASMsgDLCError_Cnt_M_u08	46
PrevISDYNAASMsgRxTime_MSec_M_u32	2478153472
PrevISDYNABRMsgDLCError_Cnt_M_u08	7
PrevISDYNABRMsgRxTime_MSec_M_u32	1528291072
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	14
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3065945856
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	136
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3868720896
PrevISDYNVOLMsgDLCError_Cnt_M_u08	52
PrevISDYNVOLMsgRxTime_MSec_M_u32	968302336
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1990020864
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	568.109497
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	49087
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	58798
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	44284
VitesseVehicleBVRampValidCount_Cnt_M_u16	13995
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	34717

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	19155
VitesseVehicleBV_Kph_M_f32	500.095398
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	44510
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	9644
VitesseVehiculeRoues_Kph_M_f32	539.312683
k_AASNTCEnableTimeout_mS_u16	44003
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	34599
k_AASNodeTimeout_mS_u16	38062
k_ABSNodeTimeout_mS_u16	26067
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	25235
k_ANGLEVOLANTSigValidThresh_Cnt_u16	64821
k_AngleVolantInvalidThresh_Cnt_u16	33376
k_AngleVolantValidThresh_Cnt_u16	13438
k_BSI552MsgTimeout_mS_u16	24215
k_BSINTCEnableTimeout_mS_u16	44188
k_BSINodeAbsentDiag_Cnt_str.Threshold	29117
k_BSINodeAbsentDiag_Cnt_str.PStep	33703
k_BSINodeAbsentDiag_Cnt_str.NStep	28629
k_BSINodeAbsentTimeout_mS_u16	47306
k_BSINodeTimeout_mS_u16	30855
k_BattOvHi_Volt_f32	20.6453991
k_BattOvLo_Volt_f32	11.085
k_BattUvHi_Volt_f32	28.7106991
k_BattUvLo_Volt_f32	8.41119957
k_CAVNTCEnableTimeout_mS_u16	46364
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	65288
k_CAVNodeTimeout_mS_u16	36823
k_CMM388MsgTimeout_mS_u16	51457
k_CMM388NTCEnableTimeout_mS_u16	58893
k_CMMNTCEnableTimeout_mS_u16	17125
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	45240
k_CONSANGLECPKMax_HwDeg_f32	491.709808
k_CONSANGLECPKMin_HwDeg_f32	-703.694824
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	7390
k_CONSANGLECPKSigValidThresh_Cnt_u16	54444
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	51100
k_CPKVehicleSpeedValidThresh_Cnt_u16	47875
k_CityParkInputInvalidThresh_Cnt_u16	9757
k_CityParkInputValidThresh_Cnt_u16	1356
k_ComputerRazGCTSigValidThresh_Cnt_u16	46491
k_CptTemporelSigValidThresh_Cnt_u16	56341
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	40718
k_DMDFCTCPKSigValidThresh_Cnt_u16	6484
k_DMDFCTCPKValidCount_Cnt_u16	14347
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	55885
k_DMDRELAXECPKSigValidThresh_Cnt_u16	49931
k_DMDRelaxeConsistentThresh_Cnt_u16	43001
k_DateValidThresh_Cnt_u16	33782
k_DefaultVehSpd_Kph_f32	5.76929998
k_DiagMuxOnAbsentTimeout_mS_u16	51302
k_EMNodeTimeout_mS_u16	51548
k_ESPNTCEnableTimeout_mS_u16	34958
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	35232
k_EtatMTSigInvalidThresh_Cnt_u16	64314
k_EtatMTSigValidThresh_Cnt_u16	21592
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	5491
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	27749
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	44169
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	3358
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	57304
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	11392

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	21077
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	39543
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	11640
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	27932
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	13990
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	23423
k_ISDATDIRASentDiag_Cnt_str.Threshold	1170
k_ISDATDIRASentDiag_Cnt_str.PStep	4955
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	21179
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	24584
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	61362
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	53354
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	41903
k_ISDYNAASChkSumValidThresh_Cnt_u16	55949
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	43966
k_ISDYNAASMsgCountValidThresh_Cnt_u16	19732
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	50595
k_ISDYNAASMsgLenValidThresh_Cnt_u16	49570
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	60445
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	64404
k_ISDYNABRChkSumValidThresh_Cnt_u16	61018
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	45347
k_ISDYNABRMsgCountValidThresh_Cnt_u16	44249
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	31888
k_ISDYNABRMsgLenValidThresh_Cnt_u16	35570
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	28996
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	3251
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	41993
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	45209
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	29152
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	29014
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	37270
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	60955
k_ISDYNVOLChkSumValidThresh_Cnt_u16	8261
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	23715
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	19329
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	47794
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	10820
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	36628
k_IgnOnTimeout_mS_u16	20519
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	25.0979004
k_PowerCutVehSpdLowThresh_Kph_f32	132.574402
k_PowerCutVehSpdLowTimeout_mS_u16	38303
k_VBattMaxAAS_Volt_f32	26.3841991
k_VBattMaxBSI_Volt_f32	30.4211006
k_VBattMaxCAV_Volt_f32	13.8065004
k_VBattMaxCMM388_Volt_f32	31.5356998
k_VBattMaxCMM_Volt_f32	22.2845001
k_VBattMaxESP_Volt_f32	32
k_VBattMinAAS_Volt_f32	2.28590012
k_VBattMinBSI_Volt_f32	32
k_VBattMinCAV_Volt_f32	17.0625
k_VBattMinCMM388_Volt_f32	5.2198
k_VBattMinCMM_Volt_f32	24.6361008
k_VBattMinESP_Volt_f32	22.2845001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	50202
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	29493
k_VitesseVehicleBVRampValidThresh_Cnt_u16	32272
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	57815
k_VitesseVehicleBVSigValidThresh_Cnt_u16	20897
k_VitesseVehicleBVSpeedPassThresh_kph_f32	192.747101
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	34178
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	34737
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3737075456
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8816
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3873991680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	136
target_SrlComInput_Per1_Batt_Volt_f32.value	24.7688999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	618000128
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	166
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.206794679
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3349274368
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3580460800
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	406920960
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	942194432
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3709886208
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2938633984
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1447010048
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	9
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	55
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	147
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	172
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3963993856
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	18
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	88
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	111
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	252
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	1
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2377703168
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	83918592
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1901600512
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	45
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	115
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	140
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	189
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	573796096
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3512
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.182839006
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	2768
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	66.7505035
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	13137

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3873991680	3873991680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	29117	29117	✔
BSINodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
CDD_SrlComVehSpd_Kph_G_f32	117.498497	117.498497	✔
CMM388NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	28744	28744	✔
CONSANGLECPK_HwDeg_M_f32	124.4151	124.4151 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3873991680	3873991680	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3873991680	3873991680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3873991680	3873991680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3873991680	3873991680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3873991680	3873991680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3873991680	3873991680	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3873991680	3873991680	✔
ESPNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	8	8	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1	1	✔
ElecIntTimer_mS_M_u32[1]	14	14	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3873991680	3873991680	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	33782	33782	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	20024	20024	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	20390	20390	✔
ISDATBSI412MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	30855	30855	✔
ISDATBSI432MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1170	1170	✔
ISDATDIRASentTimer_mS_M_u32	3873991680	3873991680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	55885	55885	✔
ISDYN2CMMMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	58235	58235	✔
ISDYNAASMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	28744	28744	✔
ISDYNABRMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	20024	20024	✔
ISDYNCMM208MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	44510	44510	✔
ISDYNCMM388MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	52624	52624	✔
ISDYNVOLMsgTimer_mS_M_u32	3873991680	3873991680	✔
IgnOnTimer_mS_M_u32	3154108160	3154108160	✔
IgnTimeOff_Sec_M_u32	2076488099	2076488099	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3349274368	3349274368	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3580460800	3580460800	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	141	141	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	406920960	406920960	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	202	202	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	942194432	942194432	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4172947200	4172947200	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	126	126	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2938633984	2938633984	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1447010048	1447010048	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3963993856	3963993856	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	1	1	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2377703168	2377703168	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	93	93	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	83918592	83918592	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	90	90	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1901600512	1901600512	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	573796096	573796096	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	568.109497	568.109497	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	500.095398	500.095398	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	539.312683	539.312683	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	28744	28744	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2076488099	2076488099	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	124.4151	124.4151 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.397 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2816923136
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	17301
AASNodeAbsentTimer_mS_M_u32	4287809024
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	58105
ANGLEVOLANTSigValidCount_Cnt_M_u16	31063
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	1666
AngleVolantMsgTimer_mS_M_u32	2816923136
AngleVolantValidCount_Cnt_M_u16	49937
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2831582720
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	924648960
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1690793472
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3346675200
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	61744
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3628594688
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	31377
CAVNodeAbsentTimer_mS_M_u32	3905381888
CDD_SrlComVehSpd_Kph_G_f32	488.468292
CMM388NTCEnableTimer_mS_M_u32	1063233024
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1123902976
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	38697
CMMNodeAbsentTimer_mS_M_u32	2613327360
CONSANGLECPKSigInvalidCount_Cnt_M_u16	53049
CONSANGLECPKSigValidCount_Cnt_M_u16	27111
CONSANGLECPK_Cnt_M_u16	59010
CONSANGLECPK_HwDeg_M_f32	457.148895
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	59010
CPKVehicleSpeedMsgTimer_mS_M_u32	2262160896
CPKVehicleSpeedValidCount_Cnt_M_u16	59752
CityParkInputConsistentCount_Cnt_M_u16	46133
CityParkInputInvalidCount_Cnt_M_u16	49054
CityParkInputMsgTimer_mS_M_u32	3349274368
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	968279552
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	43705

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	4243580416
ComputerRazGCTSigValidCount_Cnt_M_u16	12634
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	27258
DMDFCTCPKSigValidCount_Cnt_M_u16	31168
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	25227
DMDRELAXECPKSigValidCount_Cnt_M_u16	57961
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	39718
DateInvalidTimer_mS_M_u32	924648960
DiagMuxOnAbsentTimer_mS_M_u32	2912196096
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3346675200
ESPNTCEnableTimer_mS_M_u32	1415824896
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	45251
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	79
EffacDefaultDiagTimer_mS_M_u32[1]	699
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	12
ElecIntTimer_mS_M_u32[1]	19
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1345975808
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	14822
EtatMTSigValidCount_Cnt_M_u16	33520
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	33995
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	35065
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	11766
ISDAT4V2BSI552MsgTimer_mS_M_u32	3907532288
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	25842
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	61891
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	33520
ISDATBSI3F2MsgTimer_mS_M_u32	2416088576
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	60852
ISDATBSI412MsgLenValidCount_Cnt_M_u16	37813
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	14822
ISDATBSI412MsgTimer_mS_M_u32	4032091648
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	14157
ISDATBSI432MsgLenValidCount_Cnt_M_u16	58343
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	43138
ISDATDIRASentFltAcc_Cnt_M_u16	48310
ISDATDIRASentTimer_mS_M_u32	2262160896
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	24432
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	49937
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	51761
ISDYN2CMMMsgTimer_mS_M_u32	2637022720
ISDYNAASChkSumInvalidCount_Cnt_M_u16	36647
ISDYNAASChkSumValidCount_Cnt_M_u16	13476
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	35016
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	49004
ISDYNAASMsgLenValidCount_Cnt_M_u16	44002
ISDYNAASMsgTimeValidCount_Cnt_M_u16	36647
ISDYNAASMsgTimer_mS_M_u32	4282099200
ISDYNABRChkSumInvalidCount_Cnt_M_u16	8461
ISDYNABRChkSumValidCount_Cnt_M_u16	45362
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	53086
ISDYNABRMsgCountValidCount_Cnt_M_u16	27
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	17008
ISDYNABRMsgLenValidCount_Cnt_M_u16	43102
ISDYNABRMsgTimeValidCount_Cnt_M_u16	59010
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	49585
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	56571
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	33520
ISDYNCMM208MsgTimer_mS_M_u32	3727394304
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	49585
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	56571
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	33407

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	297215488
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	59815
ISDYNVOLChkSumValidCount_Cnt_M_u16	6869
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	63464
ISDYNVOLMsgCountValidCount_Cnt_M_u16	56750
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	28556
ISDYNVOLMsgLenValidCount_Cnt_M_u16	23321
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	38697
ISDYNVOLMsgTimer_mS_M_u32	684451328
IgnOnTimer_mS_M_u32	3923453440
IgnTimeOff_Sec_M_u32	2605611981
ManVehSpd_Kph_M_f32	456.660187
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	5
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	46
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1813550592
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	249
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	366900736
PrevISDATBSI412MsgDLCError_Cnt_M_u08	98
PrevISDATBSI412MsgRxTime_MSec_M_u32	1501062656
PrevISDATBSI432MsgDLCError_Cnt_M_u08	67
PrevISDATBSI432MsgRxTime_MSec_M_u32	2834810368
PrevISDATDIRAMsgTxTime_MSec_M_u32	3970721280
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	44
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2588390912
PrevISDYNAASMsgDLCError_Cnt_M_u08	101
PrevISDYNAASMsgRxTime_MSec_M_u32	1773790720
PrevISDYNABRMsgDLCError_Cnt_M_u08	208
PrevISDYNABRMsgRxTime_MSec_M_u32	1821582848
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	217
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1688135168
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	33
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1922221568
PrevISDYNVOLMsgDLCError_Cnt_M_u08	102
PrevISDYNVOLMsgRxTime_MSec_M_u32	1572169216
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1002624512
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	446.350403
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	45786
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	62928
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	7971
VitesseVehicleBVRampValidCount_Cnt_M_u16	14041
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	2242
VitesseVehicleBVSigValidCount_Cnt_M_u16	37856
VitesseVehicleBV_Kph_M_f32	535.020325
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	33407
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	20436
VitesseVehiculeRoues_Kph_M_f32	108.427101
k_AASNTCEnableTimeout_mS_u16	24497
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	23204
k_AASNodeTimeout_mS_u16	59600
k_ABSNodeTimeout_mS_u16	49055
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	42016
k_ANGLEVOLANTSigValidThresh_Cnt_u16	22778
k_AngleVolantInvalidThresh_Cnt_u16	13689
k_AngleVolantValidThresh_Cnt_u16	49054
k_BSI552MsgTimeout_mS_u16	4371
k_BSINTCEnableTimeout_mS_u16	10757
k_BSINodeAbsentDiag_Cnt_str.Threshold	59680
k_BSINodeAbsentDiag_Cnt_str.PStep	24227
k_BSINodeAbsentDiag_Cnt_str.NStep	21849
k_BSINodeAbsentTimeout_mS_u16	2874
k_BSINodeTimeout_mS_u16	43138
k_BattOvHi_Volt_f32	2.53740001
k_BattOvLo_Volt_f32	25.3472004
k_BattUvHi_Volt_f32	15.7292004
k_BattUvLo_Volt_f32	24.4181995
k_CAVNTCEnableTimeout_mS_u16	13764
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	22783
k_CAVNodeTimeout_mS_u16	1813
k_CMM388MsgTimeout_mS_u16	30357
k_CMM388NTCEnableTimeout_mS_u16	20337
k_CMMNTCEnableTimeout_mS_u16	29610
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	57008
k_CONSANGLECPKMax_HwDeg_f32	274.812714
k_CONSANGLECPKMin_HwDeg_f32	-562.419983
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	13695
k_CONSANGLECPKSigValidThresh_Cnt_u16	17108
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	34822
k_CPKVehicleSpeedValidThresh_Cnt_u16	21583
k_CityParkInputInvalidThresh_Cnt_u16	33987
k_CityParkInputValidThresh_Cnt_u16	46133
k_ComputerRazGCTSigValidThresh_Cnt_u16	29576
k_CptTemporelSigValidThresh_Cnt_u16	58585
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	30064
k_DMDFCTCPKSigValidThresh_Cnt_u16	7006
k_DMDFCTCPKValidCount_Cnt_u16	12152
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	51761
k_DMDRELAXECPKSigValidThresh_Cnt_u16	1207
k_DMDRelaxeConsistentThresh_Cnt_u16	36333
k_DateValidThresh_Cnt_u16	11766
k_DefaultVehSpd_Kph_f32	52.7966995
k_DiagMuxOnAbsentTimeout_mS_u16	54824
k_EMNodeTimeout_mS_u16	44678
k_ESPNTCEnableTimeout_mS_u16	21613
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	62456
k_EtatMTSigInvalidThresh_Cnt_u16	47468
k_EtatMTSigValidThresh_Cnt_u16	8913
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	47745
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	31338
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	62078
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	14591
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	42384
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	13272
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	23770
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	2356
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	6001
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	16390
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	2087
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	46042
k_ISDATDIRASentDiag_Cnt_str.Threshold	47720

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	17950
k_ISDATDIRASentDiag_Cnt_str.NStep	21543
k_ISDATDIRASentTimeout_mS_u16	63209
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	2623
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	1666
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	60633
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	54285
k_ISDYNAASChkSumValidThresh_Cnt_u16	42034
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	606
k_ISDYNAASMsgCountValidThresh_Cnt_u16	29467
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	15921
k_ISDYNAASMsgLenValidThresh_Cnt_u16	12788
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	11330
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	63454
k_ISDYNABRChkSumValidThresh_Cnt_u16	13388
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	9264
k_ISDYNABRMsgCountValidThresh_Cnt_u16	1486
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	35369
k_ISDYNABRMsgLenValidThresh_Cnt_u16	58307
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	9357
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	39934
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	12605
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	271
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	5625
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	60503
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	2134
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	6919
k_ISDYNVOLChkSumValidThresh_Cnt_u16	10568
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	29360
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	8534
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	10434
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	7884
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	1180
k_IgnOnTimeout_mS_u16	9443
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	243.310898
k_PowerCutVehSpdLowThresh_Kph_f32	24.8812008
k_PowerCutVehSpdLowTimeout_mS_u16	37501
k_VBattMaxAAS_Volt_f32	4.39209986
k_VBattMaxBSI_Volt_f32	31.0175991
k_VBattMaxCAV_Volt_f32	1.10080004
k_VBattMaxCMM388_Volt_f32	15.5244999
k_VBattMaxCMM_Volt_f32	3.4138999
k_VBattMaxESP_Volt_f32	22.6408997
k_VBattMinAAS_Volt_f32	17.4869003
k_VBattMinBSI_Volt_f32	22.6408997
k_VBattMinCAV_Volt_f32	24.9452
k_VBattMinCMM388_Volt_f32	8.45960045
k_VBattMinCMM_Volt_f32	27.9088001
k_VBattMinESP_Volt_f32	3.4138999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	42505
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	64891
k_VitesseVehicleBVRampValidThresh_Cnt_u16	43752
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	36309
k_VitesseVehicleBVSigValidThresh_Cnt_u16	25398
k_VitesseVehicleBVSpeedPassThresh_kph_f32	186.047394
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	11665
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	56263
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	924648960
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	56852
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2274721536
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	33
target_SrlComInput_Per1_Batt_Volt_f32.value	21.3313999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1536751104
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	49
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.938675284
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	18
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3472172544
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	161
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3424536064
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1779918336
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	159
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2967504384
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2826544640
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1491256832
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3390825984
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	44
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	62
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	114
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	195
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	205
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	218
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1216972288
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	41
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	55
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	177
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2561680896
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1499022848
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2060609024
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	187
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	231
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3112203776
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2047
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.450580329
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	980914
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	166.603104
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	8228

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	1668	1668	✔
AngleVolantMsgTimer_mS_M_u32	2274721536	2274721536	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	39895	39895	✔
BSINodeAbsentTimer_mS_M_u32	2967504384	2967504384	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	31377	31377	✔
CAVNodeAbsentTimer_mS_M_u32	2060609024	2060609024	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	38697	38697	✔
CMMNodeAbsentTimer_mS_M_u32	1491256832	1491256832	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	59010	59010	✔
CONSANGLECPK_HwDeg_M_f32	457.148895	457.148895 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	59010	59010	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2262160896	2262160896	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	59752	59752	✔
CityParkInputConsistentCount_Cnt_M_u16	46133	46133	✔
CityParkInputInvalidCount_Cnt_M_u16	49054	49054	✔
CityParkInputMsgTimer_mS_M_u32	2274721536	2274721536	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2274721536	2274721536	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2274721536	2274721536	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2274721536	2274721536	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2274721536	2274721536	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2274721536	2274721536	✔
ESPNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	79	79	✔
EffacDefaultDiagTimer_mS_M_u32[1]	699	699	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	12	12	✔
ElecIntTimer_mS_M_u32[1]	19	19	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2274721536	2274721536	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDATDIRASentFltAcc_Cnt_M_u16	26767	26767	✔
ISDATDIRASentTimer_mS_M_u32	2274721536	2274721536	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2274721536	2274721536	✔
IgnOnTimer_mS_M_u32	3923453440	3923453440	✔
IgnTimeOff_Sec_M_u32	2605611981	2605611981	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	18	18	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3472172544	3472172544	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	161	161	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3424536064	3424536064	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	206	206	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1779918336	1779918336	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	159	159	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2967504384	2967504384	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2826544640	2826544640	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	81	81	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1491256832	1491256832	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	64	64	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3390825984	3390825984	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	212	212	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1216972288	1216972288	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2561680896	2561680896	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	53	53	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1499022848	1499022848	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	133	133	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2060609024	2060609024	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3112203776	3112203776	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	446.350403	446.350403	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	535.020325	535.020325	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	108.427101	108.427101	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	59010	59010	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2605611981	2605611981	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	457.148895	457.148895 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	52.7966995	52.7966995	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.398 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2596421888
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	41398
AASNodeAbsentTimer_mS_M_u32	1870557440
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	62857
ANGLEVOLANTSigValidCount_Cnt_M_u16	46128
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	19695
AngleVolantMsgTimer_mS_M_u32	2596421888
AngleVolantValidCount_Cnt_M_u16	48066
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	4074975488
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3252662528
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	782262528
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1099440384
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	26340
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1981735168
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	14144
CAVNodeAbsentTimer_mS_M_u32	3462435072
CDD_SrlComVehSpd_Kph_G_f32	264.445496
CMM388NTCEnableTimer_mS_M_u32	2073547008
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	398364928
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	7225
CMMNodeAbsentTimer_mS_M_u32	1823088896
CONSANGLECPKSigInvalidCount_Cnt_M_u16	57290
CONSANGLECPKSigValidCount_Cnt_M_u16	53633
CONSANGLECPK_Cnt_M_u16	34736
CONSANGLECPK_HwDeg_M_f32	641.0354
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	34736
CPKVehicleSpeedMsgTimer_mS_M_u32	2046116096
CPKVehicleSpeedValidCount_Cnt_M_u16	17124
CityParkInputConsistentCount_Cnt_M_u16	30806
CityParkInputInvalidCount_Cnt_M_u16	35610
CityParkInputMsgTimer_mS_M_u32	3472172544
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1360163072
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	64586
ComputerRazGCTSigInvalidTimer_mS_M_u32	3555135744
ComputerRazGCTSigValidCount_Cnt_M_u16	54503
CountEtatMT_Cnt_M_u08	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
DMDFCTCPKSigInvalidCount_Cnt_M_u16	64134
DMDFCTCPKSigValidCount_Cnt_M_u16	61046
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	16083
DMDRELAXECPKSigValidCount_Cnt_M_u16	16634
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	28675
DateInvalidTimer_mS_M_u32	3252662528
DiagMuxOnAbsentTimer_mS_M_u32	1891172608
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1099440384
ESPNTCEnableTimer_mS_M_u32	4111167744
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	16685
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	86
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	79
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1447616768
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	47362
EtatMTSigValidCount_Cnt_M_u16	4005
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	34580
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	15435
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	10708
ISDAT4V2BSI552MsgTimer_mS_M_u32	356393216
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	7519
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	51371
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	4005
ISDATBSI3F2MsgTimer_mS_M_u32	24051968
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	23577
ISDATBSI412MsgLenValidCount_Cnt_M_u16	31700
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	47362
ISDATBSI412MsgTimer_mS_M_u32	4185407744
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	52173
ISDATBSI432MsgLenValidCount_Cnt_M_u16	14273
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	45421
ISDATDIRASentFltAcc_Cnt_M_u16	17617
ISDATDIRASentTimer_mS_M_u32	2046116096
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	21734
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	48066
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	30561
ISDYN2CMMMsgTimer_mS_M_u32	3266146560
ISDYNAASChkSumInvalidCount_Cnt_M_u16	34560
ISDYNAASChkSumValidCount_Cnt_M_u16	38984
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	1693
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	38063
ISDYNAASMsgLenValidCount_Cnt_M_u16	45327
ISDYNAASMsgTimeValidCount_Cnt_M_u16	34560
ISDYNAASMsgTimer_mS_M_u32	2885931264
ISDYNABRChkSumInvalidCount_Cnt_M_u16	16591
ISDYNABRChkSumValidCount_Cnt_M_u16	12830
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	25179
ISDYNABRMsgCountValidCount_Cnt_M_u16	53731
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	8741
ISDYNABRMsgLenValidCount_Cnt_M_u16	45596
ISDYNABRMsgTimeValidCount_Cnt_M_u16	34736
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	3489
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	60804
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	4005
ISDYNCMM208MsgTimer_mS_M_u32	649343232
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	3489
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	60804
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	46456
ISDYNCMM388MsgTimer_mS_M_u32	3264303360
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	51328
ISDYNVOLChkSumValidCount_Cnt_M_u16	63159

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	35388
ISDYNVOLMsgCountValidCount_Cnt_M_u16	64172
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	26834
ISDYNVOLMsgLenValidCount_Cnt_M_u16	59370
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	7225
ISDYNVOLMsgTimer_mS_M_u32	3226669312
IgnOnTimer_mS_M_u32	3391443200
IgnTimeOff_Sec_M_u32	332184125
ManVehSpd_Kph_M_f32	61.8249016
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	6
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	181
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1160577280
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	71
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	928735488
PrevISDATBSI412MsgDLCError_Cnt_M_u08	112
PrevISDATBSI412MsgRxTime_MSec_M_u32	2152567040
PrevISDATBSI432MsgDLCError_Cnt_M_u08	116
PrevISDATBSI432MsgRxTime_MSec_M_u32	1196388608
PrevISDATDIRAMsgTxTime_MSec_M_u32	2528219392
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	163
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3743392000
PrevISDYNAASMsgDLCError_Cnt_M_u08	217
PrevISDYNAASMsgRxTime_MSec_M_u32	898175232
PrevISDYNABRMsgDLCError_Cnt_M_u08	189
PrevISDYNABRMsgRxTime_MSec_M_u32	570249472
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	67
PrevISDYNCMM208MsgRxTime_MSec_M_u32	416944384
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	74
PrevISDYNCMM388MsgRxTime_MSec_M_u32	377385216
PrevISDYNVOLMsgDLCError_Cnt_M_u08	163
PrevISDYNVOLMsgRxTime_MSec_M_u32	2811662592
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1328431360
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	6.2249999
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	62053
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	2885
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	4490
VitesseVehicleBVRampValidCount_Cnt_M_u16	44074
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	59438
VitesseVehicleBVSigValidCount_Cnt_M_u16	51349
VitesseVehicleBV_Kph_M_f32	86.3320999
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	46456
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	44856
VitesseVehiculeRoues_Kph_M_f32	323.915588
k_AASNTCEnableTimeout_mS_u16	38947
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	265

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeTimeout_mS_u16	12869
k_ABSNodeTimeout_mS_u16	53015
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	37204
k_ANGLEVOLANTSigValidThresh_Cnt_u16	58504
k_AngleVolantInvalidThresh_Cnt_u16	2827
k_AngleVolantValidThresh_Cnt_u16	35610
k_BSI552MsgTimeout_mS_u16	10107
k_BSINTCEnableTimeout_mS_u16	54181
k_BSINodeAbsentDiag_Cnt_str.Threshold	27348
k_BSINodeAbsentDiag_Cnt_str.PStep	2188
k_BSINodeAbsentDiag_Cnt_str.NStep	62121
k_BSINodeAbsentTimeout_mS_u16	7879
k_BSINodeTimeout_mS_u16	45421
k_BattOvHi_Volt_f32	22.5662994
k_BattOvLo_Volt_f32	4.25180006
k_BattUvHi_Volt_f32	0.827899992
k_BattUvLo_Volt_f32	1.38909996
k_CAVNTCEnableTimeout_mS_u16	16552
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	54262
k_CAVNodeTimeout_mS_u16	43062
k_CMM388MsgTimeout_mS_u16	2230
k_CMM388NTCEnableTimeout_mS_u16	60962
k_CMMNTCEnableTimeout_mS_u16	53559
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	29348
k_CONSANGLECPKMax_HwDeg_f32	80.0085983
k_CONSANGLECPKMin_HwDeg_f32	-522.954529
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	40056
k_CONSANGLECPKSigValidThresh_Cnt_u16	54840
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	44195
k_CPKVehicleSpeedValidThresh_Cnt_u16	21576
k_CityParkInputInvalidThresh_Cnt_u16	28077
k_CityParkInputValidThresh_Cnt_u16	30806
k_ComputerRazGCTSigValidThresh_Cnt_u16	51613
k_CptTemporelSigValidThresh_Cnt_u16	51049
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	35109
k_DMDFCTCPKSigValidThresh_Cnt_u16	22812
k_DMDFCTCPKValidCount_Cnt_u16	52236
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	30561
k_DMDRELAXECPKSigValidThresh_Cnt_u16	59793
k_DMDRelaxeConsistentThresh_Cnt_u16	42479
k_DateValidThresh_Cnt_u16	10708
k_DefaultVehSpd_Kph_f32	112.5737
k_DiagMuxOnAbsentTimeout_mS_u16	53438
k_EMNodeTimeout_mS_u16	46563
k_ESPNTCEnableTimeout_mS_u16	6572
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	21196
k_EtatMTSigInvalidThresh_Cnt_u16	46002
k_EtatMTSigValidThresh_Cnt_u16	6465
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	49458
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	13110
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	8571
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	5432
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	8516
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	6573
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	53030
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	15322
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	47969
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	35620
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	50304
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	29350
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	12091

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	17271
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	19695
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	104
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	10191
k_ISDYNAASChkSumValidThresh_Cnt_u16	22814
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	51547
k_ISDYNAASMsgCountValidThresh_Cnt_u16	30947
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	31075
k_ISDYNAASMsgLenValidThresh_Cnt_u16	59097
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	35504
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	14811
k_ISDYNABRChkSumValidThresh_Cnt_u16	18002
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	52708
k_ISDYNABRMsgCountValidThresh_Cnt_u16	43723
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	17209
k_ISDYNABRMsgLenValidThresh_Cnt_u16	43053
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	2702
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	50937
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	62846
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	42376
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	23689
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	23344
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	37106
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	57376
k_ISDYNVOLChkSumValidThresh_Cnt_u16	50971
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	61286
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	29106
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	23662
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	44049
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	48610
k_IgnOnTimeout_mS_u16	12940
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	75.5313034
k_PowerCutVehSpdLowThresh_Kph_f32	162.820297
k_PowerCutVehSpdLowTimeout_mS_u16	12223
k_VBattMaxAAS_Volt_f32	29.2292004
k_VBattMaxBSI_Volt_f32	31.1436996
k_VBattMaxCAV_Volt_f32	30.1763
k_VBattMaxCMM388_Volt_f32	15.0712004
k_VBattMaxCMM_Volt_f32	5.99599981
k_VBattMaxESP_Volt_f32	30.1382008
k_VBattMinAAS_Volt_f32	2.5453999
k_VBattMinBSI_Volt_f32	30.1382008
k_VBattMinCAV_Volt_f32	22.8062992
k_VBattMinCMM388_Volt_f32	30.3041
k_VBattMinCMM_Volt_f32	2.86179996
k_VBattMinESP_Volt_f32	5.99599981
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	6169
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	58245
k_VitesseVehicleBVRampValidThresh_Cnt_u16	28988
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	40375
k_VitesseVehicleBVSigValidThresh_Cnt_u16	44883
k_VitesseVehicleBVSpeedPassThresh_kph_f32	351.924286
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	7744
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	62816
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3252662528
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	42709
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1704609280
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	74
target_SrlComInput_Per1_Batt_Volt_f32.value	29.2513008
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1881923840
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	221
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.552166641
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	47665408
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2547773696
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2322632960
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	7
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3264557312
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	675926272
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	140
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2744021248
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	476254464
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	34
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	140
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	189
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	197
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	78
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3751424256
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	36
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	43
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	114
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	242
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1369854208
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	89
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2620059904
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	150
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	71274752
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	71
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	135
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	142
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	177
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	234
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1416978688
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	96
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.232005119
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	491224
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	160.904602
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	21127

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1704609280	1704609280	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
CDD_SrlComVehSpd_Kph_G_f32	61.8249016	61.8249016	✔
CMM388NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	34736	34736	✔
CONSANGLECPK_HwDeg_M_f32	641.0354	641.0354 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1704609280	1704609280	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1704609280	1704609280	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1704609280	1704609280	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1704609280	1704609280	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1704609280	1704609280	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1704609280	1704609280	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1704609280	1704609280	✔
ESPNTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔
EffacDefaultDiagTimer_mS_M_u32[1]	86	86	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	79	79	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1704609280	1704609280	✔
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	10708	10708	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	4005	4005	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	47362	47362	✔
ISDATBSI412MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	45421	45421	✔
ISDATBSI432MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDATDIRASentFltAcc_Cnt_M_u16	41895	41895	✔
ISDATDIRASentTimer_mS_M_u32	1704609280	1704609280	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	30561	30561	✔
ISDYN2CMMMsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	34560	34560	✔
ISDYNAASMsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	34736	34736	✔
ISDYNABRMsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	4005	4005	✔
ISDYNCMM208MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	46456	46456	✔
ISDYNCMM388MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	7225	7225	✔
ISDYNVOLMsgTimer_mS_M_u32	1704609280	1704609280	✔
IgnOnTimer_mS_M_u32	3391443200	3391443200	✔
IgnTimeOff_Sec_M_u32	332184125	332184125	✔
Msg348Valid_Cnt_M_Igc	0	0	✔
Msg432Valid_Cnt_M_Igc	0	0	✔
Msg552Valid_Cnt_M_Igc	1	1	✔
NetOn_Cnt_M_Igc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	47665408	47665408	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	104	104	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2547773696	2547773696	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	14	14	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI412MsgRxTime_MSec_M_u32	2322632960	2322632960	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	7	7	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3264557312	3264557312	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2528219392	2528219392	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	140	140	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2744021248	2744021248	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	233	233	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	476254464	476254464	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	78	78	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3751424256	3751424256	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1369854208	1369854208	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	89	89	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2620059904	2620059904	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	150	150	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	71274752	71274752	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1416978688	1416978688	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	6.2249999	6.2249999	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	86.3320999	86.3320999	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	323.915588	323.915588	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	34736	34736	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	332184125	332184125	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	641.0354	641.0354 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	61.8249016	61.8249016	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.399 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3382444032
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	9918
AASNodeAbsentTimer_mS_M_u32	3089592320
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	38215
ANGLEVOLANTSigValidCount_Cnt_M_u16	54287
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	18707
AngleVolantMsgTimer_mS_M_u32	3382444032
AngleVolantValidCount_Cnt_M_u16	3867
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2969120768
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3590565888
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2927730688
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3301597184
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	27958
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4060487680
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	46752
CAVNodeAbsentTimer_mS_M_u32	1275138048
CDD_SrlComVehSpd_Kph_G_f32	132.553497
CMM388NTCEnableTimer_mS_M_u32	828067840
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1743196160
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	22389
CMMNodeAbsentTimer_mS_M_u32	1264869376
CONSANGLECPKSigInvalidCount_Cnt_M_u16	51588
CONSANGLECPKSigValidCount_Cnt_M_u16	44829
CONSANGLECPK_Cnt_M_u16	2192
CONSANGLECPK_HwDeg_M_f32	348.049988
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2192
CPKVehicleSpeedMsgTimer_mS_M_u32	3087204352
CPKVehicleSpeedValidCount_Cnt_M_u16	11070
CityParkInputConsistentCount_Cnt_M_u16	10591
CityParkInputInvalidCount_Cnt_M_u16	21010
CityParkInputMsgTimer_mS_M_u32	47665408
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1667985408
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	26370

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1970114560
ComputerRazGCTSigValidCount_Cnt_M_u16	38828
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	46030
DMDFCTCPKSigValidCount_Cnt_M_u16	29375
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	24937
DMDRELAXECPKSigValidCount_Cnt_M_u16	54705
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	15577
DateInvalidTimer_mS_M_u32	3590565888
DiagMuxOnAbsentTimer_mS_M_u32	2461515776
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3301597184
ESPNTCEnableTimer_mS_M_u32	2608885760
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	37722
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	5
EffacDefaultDiagTimer_mS_M_u32[1]	155
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2500
ElecIntTimer_mS_M_u32[1]	3504
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2038964224
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	61980
EtatMTSigValidCount_Cnt_M_u16	22769
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	31654
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	5823
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	47269
ISDAT4V2BSI552MsgTimer_mS_M_u32	2712166400
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	5250
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	7519
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	22769
ISDATBSI3F2MsgTimer_mS_M_u32	949338112
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	52567
ISDATBSI412MsgLenValidCount_Cnt_M_u16	14564
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	61980
ISDATBSI412MsgTimer_mS_M_u32	91881472
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	39097
ISDATBSI432MsgLenValidCount_Cnt_M_u16	65438
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	15385
ISDATDIRASentFltAcc_Cnt_M_u16	4589
ISDATDIRASentTimer_mS_M_u32	3087204352
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	63726
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	3867
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	26941
ISDYN2CMMMsgTimer_mS_M_u32	983199744
ISDYNAASChkSumInvalidCount_Cnt_M_u16	7904
ISDYNAASChkSumValidCount_Cnt_M_u16	58825
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	23178
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	6739
ISDYNAASMsgLenValidCount_Cnt_M_u16	8180
ISDYNAASMsgTimeValidCount_Cnt_M_u16	7904
ISDYNAASMsgTimer_mS_M_u32	1343705088
ISDYNABRChkSumInvalidCount_Cnt_M_u16	41717
ISDYNABRChkSumValidCount_Cnt_M_u16	59846
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	47311
ISDYNABRMsgCountValidCount_Cnt_M_u16	25848
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	11891
ISDYNABRMsgLenValidCount_Cnt_M_u16	14668
ISDYNABRMsgTimeValidCount_Cnt_M_u16	2192
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	12351
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	64340
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	22769
ISDYNCMM208MsgTimer_mS_M_u32	2575708160
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	12351
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	64340
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	31225

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	577687552
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	26466
ISDYNVOLChkSumValidCount_Cnt_M_u16	38779
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	23724
ISDYNVOLMsgCountValidCount_Cnt_M_u16	42525
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	61547
ISDYNVOLMsgLenValidCount_Cnt_M_u16	44516
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	22389
ISDYNVOLMsgTimer_mS_M_u32	1613336576
IgnOnTimer_mS_M_u32	1538445312
IgnTimeOff_Sec_M_u32	1048725322
ManVehSpd_Kph_M_f32	321.870605
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	7
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	109
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3847995392
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	223
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1079025664
PrevISDATBSI412MsgDLCError_Cnt_M_u08	50
PrevISDATBSI412MsgRxTime_MSec_M_u32	708448256
PrevISDATBSI432MsgDLCError_Cnt_M_u08	56
PrevISDATBSI432MsgRxTime_MSec_M_u32	3031724032
PrevISDATDIRAMsgTxTime_MSec_M_u32	1997410304
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	236
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2852380672
PrevISDYNAASMsgDLCError_Cnt_M_u08	164
PrevISDYNAASMsgRxTime_MSec_M_u32	1485279232
PrevISDYNABRMsgDLCError_Cnt_M_u08	136
PrevISDYNABRMsgRxTime_MSec_M_u32	3022704640
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	22
PrevISDYNCMM208MsgRxTime_MSec_M_u32	848596992
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	100
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3274141696
PrevISDYNVOLMsgDLCError_Cnt_M_u08	228
PrevISDYNVOLMsgRxTime_MSec_M_u32	408883200
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1549271040
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	91.9179001
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	22833
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	26962
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	53186
VitesseVehicleBVRampValidCount_Cnt_M_u16	23203
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	37208
VitesseVehicleBVSigValidCount_Cnt_M_u16	27360
VitesseVehicleBV_Kph_M_f32	125.926102
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	31225
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	26490
VitesseVehiculeRoues_Kph_M_f32	570.74408
k_AASNTCEnableTimeout_mS_u16	25399
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	6982
k_AASNodeTimeout_mS_u16	62546
k_ABSNodeTimeout_mS_u16	47643
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	9252
k_ANGLEVOLANTSigValidThresh_Cnt_u16	54601
k_AngleVolantInvalidThresh_Cnt_u16	11712
k_AngleVolantValidThresh_Cnt_u16	21010
k_BSI552MsgTimeout_mS_u16	51889
k_BSINTCEnableTimeout_mS_u16	57649
k_BSINodeAbsentDiag_Cnt_str.Threshold	40485
k_BSINodeAbsentDiag_Cnt_str.PStep	51772
k_BSINodeAbsentDiag_Cnt_str.NStep	41255
k_BSINodeAbsentTimeout_mS_u16	13195
k_BSINodeTimeout_mS_u16	15385
k_BattOvHi_Volt_f32	14.5839005
k_BattOvLo_Volt_f32	16.6832008
k_BattUvHi_Volt_f32	26.2884007
k_BattUvLo_Volt_f32	9.71949959
k_CAVNTCEnableTimeout_mS_u16	59752
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	14462
k_CAVNodeTimeout_mS_u16	8256
k_CMM388MsgTimeout_mS_u16	61886
k_CMM388NTCEnableTimeout_mS_u16	61818
k_CMMNTCEnableTimeout_mS_u16	22778
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	52534
k_CONSANGLECPKMax_HwDeg_f32	418.594604
k_CONSANGLECPKMin_HwDeg_f32	-127.532799
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	50425
k_CONSANGLECPKSigValidThresh_Cnt_u16	62074
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	32056
k_CPKVehicleSpeedValidThresh_Cnt_u16	24778
k_CityParkInputInvalidThresh_Cnt_u16	5211
k_CityParkInputValidThresh_Cnt_u16	10591
k_ComputerRazGCTSigValidThresh_Cnt_u16	34760
k_CptTemporelSigValidThresh_Cnt_u16	39205
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	63859
k_DMDFCTCPKSigValidThresh_Cnt_u16	17484
k_DMDFCTCPKValidCount_Cnt_u16	56766
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	26941
k_DMDRELAXECPKSigValidThresh_Cnt_u16	44398
k_DMDRelaxeConsistentThresh_Cnt_u16	28756
k_DateValidThresh_Cnt_u16	47269
k_DefaultVehSpd_Kph_f32	210.664597
k_DiagMuxOnAbsentTimeout_mS_u16	58726
k_EMNodeTimeout_mS_u16	60217
k_ESPNTCEnableTimeout_mS_u16	48988
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	52414
k_EtatMTSigInvalidThresh_Cnt_u16	38476
k_EtatMTSigValidThresh_Cnt_u16	32861
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	15243
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	53312
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	496
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	53495
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	46996
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	58523
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	12974
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	38739
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	6653
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	52788
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	27873
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	20143
k_ISDATDIRASentDiag_Cnt_str.Threshold	6549

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	63930
k_ISDATDIRASentDiag_Cnt_str.NStep	24627
k_ISDATDIRASentTimeout_mS_u16	34737
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	24636
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	18707
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	64296
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	60917
k_ISDYNAASChkSumValidThresh_Cnt_u16	29894
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	33743
k_ISDYNAASMsgCountValidThresh_Cnt_u16	28664
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	18745
k_ISDYNAASMsgLenValidThresh_Cnt_u16	9878
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	33489
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	16209
k_ISDYNABRChkSumValidThresh_Cnt_u16	54442
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	14390
k_ISDYNABRMsgCountValidThresh_Cnt_u16	7230
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	57973
k_ISDYNABRMsgLenValidThresh_Cnt_u16	24154
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	51445
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	11125
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	54568
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	26249
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	24647
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	57103
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	41098
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	7490
k_ISDYNVOLChkSumValidThresh_Cnt_u16	13071
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	44207
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	31498
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	47064
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	13229
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	46203
k_IgnOnTimeout_mS_u16	54782
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	254.292007
k_PowerCutVehSpdLowThresh_Kph_f32	160.424805
k_PowerCutVehSpdLowTimeout_mS_u16	3171
k_VBattMaxAAS_Volt_f32	26.5730991
k_VBattMaxBSI_Volt_f32	6.45650005
k_VBattMaxCAV_Volt_f32	17.5119991
k_VBattMaxCMM388_Volt_f32	11.3294001
k_VBattMaxCMM_Volt_f32	9.77670002
k_VBattMaxESP_Volt_f32	21.8803997
k_VBattMinAAS_Volt_f32	2.82259989
k_VBattMinBSI_Volt_f32	21.8803997
k_VBattMinCAV_Volt_f32	12.1327
k_VBattMinCMM388_Volt_f32	16.5163002
k_VBattMinCMM_Volt_f32	6.12750006
k_VBattMinESP_Volt_f32	9.77670002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	59990
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	4819
k_VitesseVehicleBVRampValidThresh_Cnt_u16	42924
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	41595
k_VitesseVehicleBVSigValidThresh_Cnt_u16	47208
k_VitesseVehicleBVSpeedPassThresh_kph_f32	360.449402
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	416
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	55041
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3590565888
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	2445
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3144151296
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	100
target_SrlComInput_Per1_Batt_Volt_f32.value	26.6693993
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2011111424
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	102
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0941391662
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4187803648
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2500784128
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1473318912
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2313367552
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1933922304
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1542942720
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2348388352
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	70
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	163
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	192
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2262052864
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	88
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	103
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	115
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	134
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	172
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	173
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	200
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	154128384
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2216816640
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	27
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3865317376
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	68
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	107
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	131
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	143
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	201
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	229
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3506610176
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2324
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0295765754
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	821978
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	176.422104
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	16587

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3144151296	3144151296	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
CDD_SrlComVehSpd_Kph_G_f32	321.870605	321.870605	✔
CMM388NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	2192	2192	✔
CONSANGLECPK_HwDeg_M_f32	348.049988	348.049988 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3144151296	3144151296	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3144151296	3144151296	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3144151296	3144151296	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3144151296	3144151296	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3144151296	3144151296	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3144151296	3144151296	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3144151296	3144151296	✔
ESPNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	5	5	✔
EffacDefaultDiagTimer_mS_M_u32[1]	155	155	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2500	2500	✔
ElecIntTimer_mS_M_u32[1]	3504	3504	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3144151296	3144151296	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	47269	47269	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	22769	22769	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	61980	61980	✔
ISDATBSI412MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	15385	15385	✔
ISDATBSI432MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATDIRASentFltAcc_Cnt_M_u16	6549	6549	✔
ISDATDIRASentTimer_mS_M_u32	3144151296	3144151296	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	26941	26941	✔
ISDYN2CMMMsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	7904	7904	✔
ISDYNAASMsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	2192	2192	✔
ISDYNABRMsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	22769	22769	✔
ISDYNCMM208MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	31225	31225	✔
ISDYNCMM388MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	22389	22389	✔
ISDYNVOLMsgTimer_mS_M_u32	3144151296	3144151296	✔
IgnOnTimer_mS_M_u32	1538445312	1538445312	✔
IgnTimeOff_Sec_M_u32	1048725322	1048725322	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	172	172	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4187803648	4187803648	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	46	46	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2500784128	2500784128	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	181	181	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1473318912	1473318912	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	134	134	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2313367552	2313367552	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1997410304	1997410304	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1542942720	1542942720	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	142	142	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2348388352	2348388352	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2262052864	2262052864	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	83	83	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	154128384	154128384	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	86	86	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2216816640	2216816640	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	27	27	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3865317376	3865317376	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3506610176	3506610176	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	91.9179001	91.9179001	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	125.926102	125.926102	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	570.74408	570.74408	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	2192	2192	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1048725322	1048725322	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	348.049988	348.049988 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.400 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3603612416
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	26979
AASNodeAbsentTimer_mS_M_u32	3303568128
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	57289
ANGLEVOLANTSigValidCount_Cnt_M_u16	45870
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	38500
AngleVolantMsgTimer_mS_M_u32	3603612416
AngleVolantValidCount_Cnt_M_u16	3275
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1366504192
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	743682816
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1184490240
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	381657856
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	54268
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	772563712
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	51262
CAVNodeAbsentTimer_mS_M_u32	4158362368
CDD_SrlComVehSpd_Kph_G_f32	109.644501
CMM388NTCEnableTimer_mS_M_u32	2160907008
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3156841216
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	63102
CMMNodeAbsentTimer_mS_M_u32	1794220800
CONSANGLECPKSigInvalidCount_Cnt_M_u16	27152
CONSANGLECPKSigValidCount_Cnt_M_u16	35077
CONSANGLECPK_Cnt_M_u16	2220
CONSANGLECPK_HwDeg_M_f32	-36.8284988
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2220
CPKVehicleSpeedMsgTimer_mS_M_u32	1737868032
CPKVehicleSpeedValidCount_Cnt_M_u16	50123
CityParkInputConsistentCount_Cnt_M_u16	52735
CityParkInputInvalidCount_Cnt_M_u16	0
CityParkInputMsgTimer_mS_M_u32	4187803648
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3541857024
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	47255

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3449164544
ComputerRazGCTSigValidCount_Cnt_M_u16	63256
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	64434
DMDFCTCPKSigValidCount_Cnt_M_u16	61087
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	33635
DMDRELAXECPKSigValidCount_Cnt_M_u16	46664
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	42001
DateInvalidTimer_mS_M_u32	743682816
DiagMuxOnAbsentTimer_mS_M_u32	2591523584
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	381657856
ESPNTCEnableTimer_mS_M_u32	3202183936
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	17040
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	79
EffacDefaultDiagTimer_mS_M_u32[1]	699
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	12
ElecIntTimer_mS_M_u32[1]	19
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	528900864
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	54153
EtatMTSigValidCount_Cnt_M_u16	24266
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	23466
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	23071
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	13549
ISDAT4V2BSI552MsgTimer_mS_M_u32	2015732480
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	32213
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	17151
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	24266
ISDATBSI3F2MsgTimer_mS_M_u32	2698871552
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	62553
ISDATBSI412MsgLenValidCount_Cnt_M_u16	20850
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	54153
ISDATBSI412MsgTimer_mS_M_u32	456180480
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	17074
ISDATBSI432MsgLenValidCount_Cnt_M_u16	3524
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	23507
ISDATDIRASentFltAcc_Cnt_M_u16	10839
ISDATDIRASentTimer_mS_M_u32	1737868032
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	12178
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	3275
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	22373
ISDYN2CMMMsgTimer_mS_M_u32	3381621504
ISDYNAASChkSumInvalidCount_Cnt_M_u16	35069
ISDYNAASChkSumValidCount_Cnt_M_u16	17410
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	42622
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	10533
ISDYNAASMsgLenValidCount_Cnt_M_u16	2050
ISDYNAASMsgTimeValidCount_Cnt_M_u16	35069
ISDYNAASMsgTimer_mS_M_u32	345559808
ISDYNABRChkSumInvalidCount_Cnt_M_u16	59454
ISDYNABRChkSumValidCount_Cnt_M_u16	50059
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	14128
ISDYNABRMsgCountValidCount_Cnt_M_u16	17013
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	46915
ISDYNABRMsgLenValidCount_Cnt_M_u16	26232
ISDYNABRMsgTimeValidCount_Cnt_M_u16	2220
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	49585
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	56571
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	24266
ISDYNCMM208MsgTimer_mS_M_u32	197931776
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	49585
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	56571
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	50225

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1536316160
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	34934
ISDYNVOLChkSumValidCount_Cnt_M_u16	51179
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	63768
ISDYNVOLMsgCountValidCount_Cnt_M_u16	19589
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	44893
ISDYNVOLMsgLenValidCount_Cnt_M_u16	50866
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	63102
ISDYNVOLMsgTimer_mS_M_u32	4251063040
IgnOnTimer_mS_M_u32	3217445632
IgnTimeOff_Sec_M_u32	289293841
ManVehSpd_Kph_M_f32	140.988098
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	8
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	848003840
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	65
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2368529152
PrevISDATBSI412MsgDLCError_Cnt_M_u08	215
PrevISDATBSI412MsgRxTime_MSec_M_u32	2167444224
PrevISDATBSI432MsgDLCError_Cnt_M_u08	152
PrevISDATBSI432MsgRxTime_MSec_M_u32	1128362752
PrevISDATDIRAMsgTxTime_MSec_M_u32	3937702656
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	181
PrevISDYN2CMMMsgRxTime_MSec_M_u32	756228864
PrevISDYNAASMsgDLCError_Cnt_M_u08	131
PrevISDYNAASMsgRxTime_MSec_M_u32	206050048
PrevISDYNABRMsgDLCError_Cnt_M_u08	32
PrevISDYNABRMsgRxTime_MSec_M_u32	2522764032
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	22
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4062253824
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	10
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2749920000
PrevISDYNVOLMsgDLCError_Cnt_M_u08	235
PrevISDYNVOLMsgRxTime_MSec_M_u32	2327941888
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	244761344
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	52.0834999
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	25739
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	9192
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	34008
VitesseVehicleBVRampValidCount_Cnt_M_u16	54261
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	28566
VitesseVehicleBVSigValidCount_Cnt_M_u16	29371
VitesseVehicleBV_Kph_M_f32	439.749786
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	50225
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	27503
VitesseVehiculeRoues_Kph_M_f32	226.970901
k_AASNTCEnableTimeout_mS_u16	21687
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	21578
k_AASNodeTimeout_mS_u16	33512
k_ABSNodeTimeout_mS_u16	23755
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	3185
k_ANGLEVOLANTSigValidThresh_Cnt_u16	63683
k_AngleVolantInvalidThresh_Cnt_u16	35678
k_AngleVolantValidThresh_Cnt_u16	0
k_BSI552MsgTimeout_mS_u16	56778
k_BSINTCEnableTimeout_mS_u16	18762
k_BSINodeAbsentDiag_Cnt_str.Threshold	59680
k_BSINodeAbsentDiag_Cnt_str.PStep	24227
k_BSINodeAbsentDiag_Cnt_str.NStep	21849
k_BSINodeAbsentTimeout_mS_u16	46844
k_BSINodeTimeout_mS_u16	23507
k_BattOvHi_Volt_f32	2.0618999
k_BattOvLo_Volt_f32	24.2968006
k_BattUvHi_Volt_f32	29.9804993
k_BattUvLo_Volt_f32	26.8430004
k_CAVNTCEnableTimeout_mS_u16	17124
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	15012
k_CAVNodeTimeout_mS_u16	21980
k_CMM388MsgTimeout_mS_u16	2147
k_CMM388NTCEnableTimeout_mS_u16	63791
k_CMMNTCEnableTimeout_mS_u16	36973
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	10811
k_CONSANGLECPKMax_HwDeg_f32	677.252686
k_CONSANGLECPKMin_HwDeg_f32	-756.315308
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	58161
k_CONSANGLECPKSigValidThresh_Cnt_u16	51823
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	54
k_CPKVehicleSpeedValidThresh_Cnt_u16	50688
k_CityParkInputInvalidThresh_Cnt_u16	44044
k_CityParkInputValidThresh_Cnt_u16	52735
k_ComputerRazGCTSigValidThresh_Cnt_u16	48131
k_CptTemporelSigValidThresh_Cnt_u16	26541
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	22083
k_DMDFCTCPKSigValidThresh_Cnt_u16	17784
k_DMDFCTCPKValidCount_Cnt_u16	41572
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	22373
k_DMDRELAXECPKSigValidThresh_Cnt_u16	47762
k_DMDRelaxeConsistentThresh_Cnt_u16	35296
k_DateValidThresh_Cnt_u16	13549
k_DefaultVehSpd_Kph_f32	28.1264992
k_DiagMuxOnAbsentTimeout_mS_u16	18986
k_EMNodeTimeout_mS_u16	6385
k_ESPNTCEnableTimeout_mS_u16	40458
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	19363
k_EtatMTSigInvalidThresh_Cnt_u16	10809
k_EtatMTSigValidThresh_Cnt_u16	7110
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	53565
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	21214
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	51276
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	23670
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	34912
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	48781
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	35027
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	23205
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	52966
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	18368
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	35705
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	8528
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	10762
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	24745
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	38500
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	6822
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	1854
k_ISDYNAASChkSumValidThresh_Cnt_u16	8843
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	54832
k_ISDYNAASMsgCountValidThresh_Cnt_u16	8565
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	1394
k_ISDYNAASMsgLenValidThresh_Cnt_u16	64540
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	4139
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	31913
k_ISDYNABRChkSumValidThresh_Cnt_u16	35934
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	29436
k_ISDYNABRMsgCountValidThresh_Cnt_u16	22177
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	21886
k_ISDYNABRMsgLenValidThresh_Cnt_u16	57744
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	60540
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	64959
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	24806
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	51267
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	32457
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	37422
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	9598
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	28824
k_ISDYNVOLChkSumValidThresh_Cnt_u16	52977
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	35473
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	8127
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	29269
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	48790
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	6507
k_IgnOnTimeout_mS_u16	13924
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	99.7442017
k_PowerCutVehSpdLowThresh_Kph_f32	133.345703
k_PowerCutVehSpdLowTimeout_mS_u16	2355
k_VBattMaxAAS_Volt_f32	6.66330004
k_VBattMaxBSI_Volt_f32	11.1323004
k_VBattMaxCAV_Volt_f32	19.5058002
k_VBattMaxCMM388_Volt_f32	27.5478992
k_VBattMaxCMM_Volt_f32	19.5408993
k_VBattMaxESP_Volt_f32	26.6390991
k_VBattMinAAS_Volt_f32	26.3201008
k_VBattMinBSI_Volt_f32	26.6390991
k_VBattMinCAV_Volt_f32	19.1116009
k_VBattMinCMM388_Volt_f32	24.3299007
k_VBattMinCMM_Volt_f32	3.64380002
k_VBattMinESP_Volt_f32	19.5408993
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	43611
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	37028
k_VitesseVehicleBVRampValidThresh_Cnt_u16	6168
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	42731
k_VitesseVehicleBVSigValidThresh_Cnt_u16	34020
k_VitesseVehicleBVSpeedPassThresh_kph_f32	580.320374
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	59198
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	22235
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	743682816
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	39539
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1516957696
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	10
target_SrlComInput_Per1_Batt_Volt_f32.value	24.8819008
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1082221312
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	214
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.327742845
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	235426560
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	62
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	741470976
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	342594304
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4004852480
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3809399552
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	11
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	427324160
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3119649536
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	42
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	226
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4225905408
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	25
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	164
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	178
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	138
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3947844352
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1794700032
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1957860096
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	52
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	78
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	207
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	215
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	588702464
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	715
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.556749582
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	978206
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	54.6038017
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	38333

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1516957696	1516957696	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	2220	2220	✔
CONSANGLECPK_HwDeg_M_f32	-36.8284988	-36.8284988 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1516957696	1516957696	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1516957696	1516957696	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1516957696	1516957696	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1516957696	1516957696	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1516957696	1516957696	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1516957696	1516957696	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1516957696	1516957696	✔
ESPNTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	79	79	✔
EffacDefaultDiagTimer_mS_M_u32[1]	699	699	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	12	12	✔
ElecIntTimer_mS_M_u32[1]	19	19	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1516957696	1516957696	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11170	11170	✔
ISDATDIRASentTimer_mS_M_u32	1516957696	1516957696	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1516957696	1516957696	✔
IgnOnTimer_mS_M_u32	1516957696	1516957696	✔
IgnTimeOff_Sec_M_u32	289293841	289293841	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	118	118	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	235426560	235426560	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	62	62	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	741470976	741470976	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	60	60	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	342594304	342594304	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	152	152	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4004852480	4004852480	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3937702656	3937702656	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	11	11	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	427324160	427324160	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	113	113	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3119649536	3119649536	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	29	29	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4225905408	4225905408	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	138	138	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3947844352	3947844352	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	212	212	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1794700032	1794700032	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1957860096	1957860096	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	588702464	588702464	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	52.0834999	52.0834999	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	439.749786	439.749786	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	226.970901	226.970901	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	2220	2220	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	289293841	289293841	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-36.8284988	-36.8284988 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.401 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3523901952
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	7232
AASNodeAbsentTimer_mS_M_u32	3664865792
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	29453
ANGLEVOLANTSigValidCount_Cnt_M_u16	18845
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	55613
AngleVolantMsgTimer_mS_M_u32	3523901952
AngleVolantValidCount_Cnt_M_u16	7303
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3486591488
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1630513664
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	656218624
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2108414464
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	8820
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1522899456
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	54319
CAVNodeAbsentTimer_mS_M_u32	1981286912
CDD_SrlComVehSpd_Kph_G_f32	80.425499
CMM388NTCEnableTimer_mS_M_u32	809781760
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3777890816
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	5934
CMMNodeAbsentTimer_mS_M_u32	3373652480
CONSANGLECPKSigInvalidCount_Cnt_M_u16	24377
CONSANGLECPKSigValidCount_Cnt_M_u16	37657
CONSANGLECPK_Cnt_M_u16	28708
CONSANGLECPK_HwDeg_M_f32	128.748199
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	28708
CPKVehicleSpeedMsgTimer_mS_M_u32	195656192
CPKVehicleSpeedValidCount_Cnt_M_u16	30031
CityParkInputConsistentCount_Cnt_M_u16	43243

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	65535
CityParkInputMsgTimer_mS_M_u32	235426560
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2144692736
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	65188
ComputerRazGCTSigInvalidTimer_mS_M_u32	4276652544
ComputerRazGCTSigValidCount_Cnt_M_u16	53664
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	47316
DMDFCTCPKSigValidCount_Cnt_M_u16	20684
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	28735
DMDRELAXECPKSigValidCount_Cnt_M_u16	10319
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	62774
DateInvalidTimer_mS_M_u32	1630513664
DiagMuxOnAbsentTimer_mS_M_u32	704920064
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2108414464
ESPNTCEnableTimer_mS_M_u32	9595392
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	13242
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	86
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	79
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3998718464
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	30991
EtatMTSigValidCount_Cnt_M_u16	38923
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	29291
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1995
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	13794
ISDAT4V2BSI552MsgTimer_mS_M_u32	1903811072
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	17832
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	22253
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	38923
ISDATBSI3F2MsgTimer_mS_M_u32	785529344
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	65311
ISDATBSI412MsgLenValidCount_Cnt_M_u16	2195
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	30991
ISDATBSI412MsgTimer_mS_M_u32	483949056
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	658
ISDATBSI432MsgLenValidCount_Cnt_M_u16	41502
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	44400
ISDATDIRASentFltAcc_Cnt_M_u16	20964
ISDATDIRASentTimer_mS_M_u32	195656192
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	4978
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	7303
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	12731
ISDYN2CMMMsgTimer_mS_M_u32	679242240
ISDYNAASChkSumInvalidCount_Cnt_M_u16	42354
ISDYNAASChkSumValidCount_Cnt_M_u16	17699
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	56174
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	3450
ISDYNAASMsgLenValidCount_Cnt_M_u16	41379
ISDYNAASMsgTimeValidCount_Cnt_M_u16	42354
ISDYNAASMsgTimer_mS_M_u32	2766162432
ISDYNABRChkSumInvalidCount_Cnt_M_u16	50478
ISDYNABRChkSumValidCount_Cnt_M_u16	9223
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	9945
ISDYNABRMsgCountValidCount_Cnt_M_u16	54730
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	928
ISDYNABRMsgLenValidCount_Cnt_M_u16	34496
ISDYNABRMsgTimeValidCount_Cnt_M_u16	28708
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	3489

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	60804
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	38923
ISDYNCMM208MsgTimer_mS_M_u32	1153837568
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	3489
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	60804
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	3669
ISDYNCMM388MsgTimer_mS_M_u32	2515782144
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	7175
ISDYNVOLChkSumValidCount_Cnt_M_u16	61031
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	55458
ISDYNVOLMsgCountValidCount_Cnt_M_u16	20250
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	24915
ISDYNVOLMsgLenValidCount_Cnt_M_u16	11284
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	5934
ISDYNVOLMsgTimer_mS_M_u32	2676263424
IgnOnTimer_mS_M_u32	962054656
IgnTimeOff_Sec_M_u32	1383076953
ManVehSpd_Kph_M_f32	157.529999
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	9
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	197
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2982689280
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	143
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1600395776
PrevISDATBSI412MsgDLCError_Cnt_M_u08	24
PrevISDATBSI412MsgRxTime_MSec_M_u32	1847134720
PrevISDATBSI432MsgDLCError_Cnt_M_u08	97
PrevISDATBSI432MsgRxTime_MSec_M_u32	57043456
PrevISDATDIRAMsgTxTime_MSec_M_u32	1099762176
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	94
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3903937024
PrevISDYNAASMsgDLCError_Cnt_M_u08	22
PrevISDYNAASMsgRxTime_MSec_M_u32	2329053696
PrevISDYNABRMsgDLCError_Cnt_M_u08	95
PrevISDYNABRMsgRxTime_MSec_M_u32	361744896
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	156
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2101840384
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	47
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1030842880
PrevISDYNVOLMsgDLCError_Cnt_M_u08	104
PrevISDYNVOLMsgRxTime_MSec_M_u32	3580234240
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1520859648
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	135.172195
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	29512
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	26097
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	34401
VitesseVehicleBVRampValidCount_Cnt_M_u16	51658
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	14246
VitesseVehicleBVSigValidCount_Cnt_M_u16	32502

Name	Input Value
VitesseVehicleBV_Kph_M_f32	128.459702
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	3669
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	51549
VitesseVehiculeRoues_Kph_M_f32	27.1322002
k_AASNTCEnableTimeout_mS_u16	30723
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	522
k_AASNodeTimeout_mS_u16	18673
k_ABSNodeTimeout_mS_u16	14729
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	24917
k_ANGLEVOLANTSigValidThresh_Cnt_u16	40225
k_AngleVolantInvalidThresh_Cnt_u16	4432
k_AngleVolantValidThresh_Cnt_u16	65535
k_BSI552MsgTimeout_mS_u16	40524
k_BSINTCEnableTimeout_mS_u16	20170
k_BSINodeAbsentDiag_Cnt_str.Threshold	27348
k_BSINodeAbsentDiag_Cnt_str.PStep	2188
k_BSINodeAbsentDiag_Cnt_str.NStep	62121
k_BSINodeAbsentTimeout_mS_u16	55157
k_BSINodeTimeout_mS_u16	44400
k_BattOvHi_Volt_f32	17.0044003
k_BattOvLo_Volt_f32	27.2017002
k_BattUvHi_Volt_f32	4.15199995
k_BattUvLo_Volt_f32	9.59729958
k_CAVNTCEnableTimeout_mS_u16	11070
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	38141
k_CAVNodeTimeout_mS_u16	52181
k_CMM388MsgTimeout_mS_u16	16192
k_CMM388NTCEnableTimeout_mS_u16	40156
k_CMMNTCEnableTimeout_mS_u16	28128
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	48377
k_CONSANGLECPKMax_HwDeg_f32	715.217224
k_CONSANGLECPKMin_HwDeg_f32	-591.228027
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	45397
k_CONSANGLECPKSigValidThresh_Cnt_u16	44125
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	35079
k_CPKVehicleSpeedValidThresh_Cnt_u16	58922
k_CityParkInputInvalidThresh_Cnt_u16	12740
k_CityParkInputValidThresh_Cnt_u16	43243
k_ComputerRazGCTSigValidThresh_Cnt_u16	49950
k_CptTemporelSigValidThresh_Cnt_u16	8419
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	9888
k_DMDFCTCPKSigValidThresh_Cnt_u16	59840
k_DMDFCTCPKValidCount_Cnt_u16	22332
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	12731
k_DMDRELAXECPKSigValidThresh_Cnt_u16	30963
k_DMDRelaxeConsistentThresh_Cnt_u16	49929
k_DateValidThresh_Cnt_u16	13794
k_DefaultVehSpd_Kph_f32	224.537506
k_DiagMuxOnAbsentTimeout_mS_u16	9130
k_EMNodeTimeout_mS_u16	5782
k_ESPNTCEnableTimeout_mS_u16	33483
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	63681
k_EtatMTSigInvalidThresh_Cnt_u16	43837
k_EtatMTSigValidThresh_Cnt_u16	51030
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	61938
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	44494
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	11780
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	28101
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	19146
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	28803
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	62511

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	32635
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	11766
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	744
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	55421
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	25913
k_ISDATDIRASentDiag_Cnt_str.Threshold	25239
k_ISDATDIRASentDiag_Cnt_str.PStep	16638
k_ISDATDIRASentDiag_Cnt_str.NStep	16248
k_ISDATDIRASentTimeout_mS_u16	12234
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	19246
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	55613
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	31991
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	26670
k_ISDYNAASChkSumValidThresh_Cnt_u16	1799
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	18905
k_ISDYNAASMsgCountValidThresh_Cnt_u16	14538
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	15762
k_ISDYNAASMsgLenValidThresh_Cnt_u16	44373
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	63209
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	52078
k_ISDYNABRChkSumValidThresh_Cnt_u16	11534
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	17780
k_ISDYNABRMsgCountValidThresh_Cnt_u16	60228
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	64046
k_ISDYNABRMsgLenValidThresh_Cnt_u16	22202
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	21939
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	30636
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	11640
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	42208
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	38413
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	44189
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	27504
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	18018
k_ISDYNVOLChkSumValidThresh_Cnt_u16	19478
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	40887
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	57195
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	52395
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	43175
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	104
k_IgnOnTimeout_mS_u16	9470
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	170.184494
k_PowerCutVehSpdLowThresh_Kph_f32	45.3797989
k_PowerCutVehSpdLowTimeout_mS_u16	19087
k_VBattMaxAAS_Volt_f32	15.9643002
k_VBattMaxBSI_Volt_f32	5.19990015
k_VBattMaxCAV_Volt_f32	20.4591999
k_VBattMaxCMM388_Volt_f32	27.8505001
k_VBattMaxCMM_Volt_f32	23.8665009
k_VBattMaxESP_Volt_f32	4.3446002
k_VBattMinAAS_Volt_f32	12.7781
k_VBattMinBSI_Volt_f32	4.3446002
k_VBattMinCAV_Volt_f32	5.23839998
k_VBattMinCMM388_Volt_f32	0.476300001
k_VBattMinCMM_Volt_f32	20.0921001
k_VBattMinESP_Volt_f32	23.8665009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	46616
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	58364
k_VitesseVehicleBVRampValidThresh_Cnt_u16	31650
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	20839
k_VitesseVehicleBVSigValidThresh_Cnt_u16	22588
k_VitesseVehicleBVSpeedPassThresh_kph_f32	456.026886
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	30511
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	22808
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1630513664
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60573
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1277031168
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	47
target_SrlComInput_Per1_Batt_Volt_f32.value	24.8439007
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	929470976
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	85
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.887340605
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3599878656
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2861885952
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1617431040
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2148215296
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2440972800
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	482437632
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2849278464
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	69
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	131
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	149
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	7
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1283729920
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	57
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	71
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	153
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	183
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	223
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	189
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	448580096
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3393186304
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	462621184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	105
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	117
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	181
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	238
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	248
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3315997184
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3603
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.127571121
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	426797
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	117.855598

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	10162		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1277031168	1277031168	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
CDD_SrlComVehSpd_Kph_G_f32	157.529999	157.529999	✔
CMM388NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	28708	28708	✔
CONSANGLECPK_HwDeg_M_f32	128.748199	128.748199 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1277031168	1277031168	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1277031168	1277031168	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1277031168	1277031168	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1277031168	1277031168	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1277031168	1277031168	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1277031168	1277031168	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1277031168	1277031168	✔
ESPNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	86	86	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	79	79	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1277031168	1277031168	✔
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	13794	13794	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	38923	38923	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	30991	30991	✔
ISDATBSI412MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	44400	44400	✔
ISDATBSI432MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATDIRASentFltAcc_Cnt_M_u16	25239	25239	✔
ISDATDIRASentTimer_mS_M_u32	1277031168	1277031168	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	12731	12731	✔
ISDYN2CMMMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	42354	42354	✔
ISDYNAASMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	28708	28708	✔
ISDYNABRMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	38923	38923	✔
ISDYNCMM208MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	3669	3669	✔
ISDYNCMM388MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	5934	5934	✔
ISDYNVOLMsgTimer_mS_M_u32	1277031168	1277031168	✔
IgnOnTimer_mS_M_u32	962054656	962054656	✔
IgnTimeOff_Sec_M_u32	1383076953	1383076953	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	30	30	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3599878656	3599878656	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	212	212	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2861885952	2861885952	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1617431040	1617431040	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	162	162	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2148215296	2148215296	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1099762176	1099762176	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	39	39	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	482437632	482437632	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2849278464	2849278464	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	7	7	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1283729920	1283729920	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	189	189	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	448580096	448580096	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	238	238	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3393186304	3393186304	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	126	126	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	462621184	462621184	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3315997184	3315997184	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	135.172195	135.172195	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	128.459702	128.459702	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	27.1322002	27.1322002	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	28708	28708	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1383076953	1383076953	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	128.748199	128.748199 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.402 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2816955648
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	49987
AASNodeAbsentTimer_mS_M_u32	376603904
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	37086
ANGLEVOLANTSigValidCount_Cnt_M_u16	6893
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	49228
AngleVolantMsgTimer_mS_M_u32	2816955648
AngleVolantValidCount_Cnt_M_u16	753
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1699955968
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1261946112
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3140449536
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1652765952
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	57001
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1647703296
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	7671
CAVNodeAbsentTimer_mS_M_u32	2784929024
CDD_SrlComVehSpd_Kph_G_f32	584.984924
CMM388NTCEnableTimer_mS_M_u32	2021254400
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1018995968
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	60347
CMMNodeAbsentTimer_mS_M_u32	2823107840
CONSANGLECPKSigInvalidCount_Cnt_M_u16	11099
CONSANGLECPKSigValidCount_Cnt_M_u16	56697
CONSANGLECPK_Cnt_M_u16	12888
CONSANGLECPK_HwDeg_M_f32	-230.117798
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	12888
CPKVehicleSpeedMsgTimer_mS_M_u32	923424000
CPKVehicleSpeedValidCount_Cnt_M_u16	40767
CityParkInputConsistentCount_Cnt_M_u16	60869
CityParkInputInvalidCount_Cnt_M_u16	2768
CityParkInputMsgTimer_mS_M_u32	3599878656
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3058074880
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	44055

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3985450240
ComputerRazGCTSigValidCount_Cnt_M_u16	34726
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	62217
DMDFCTCPKSigValidCount_Cnt_M_u16	55520
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	57672
DMDRELAXECPKSigValidCount_Cnt_M_u16	50903
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	40292
DateInvalidTimer_mS_M_u32	1261946112
DiagMuxOnAbsentTimer_mS_M_u32	3069842688
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1652765952
ESPNTCEnableTimer_mS_M_u32	1745847552
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	37846
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	5
EffacDefaultDiagTimer_mS_M_u32[1]	155
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2500
ElecIntTimer_mS_M_u32[1]	3504
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1870656768
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	56088
EtatMTSigValidCount_Cnt_M_u16	15330
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	14789
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	51043
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	414
ISDAT4V2BSI552MsgTimer_mS_M_u32	1058616576
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	4812
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	48318
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	15330
ISDATBSI3F2MsgTimer_mS_M_u32	1620055296
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	36713
ISDATBSI412MsgLenValidCount_Cnt_M_u16	4299
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	56088
ISDATBSI412MsgTimer_mS_M_u32	2138920192
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	47503
ISDATBSI432MsgLenValidCount_Cnt_M_u16	55466
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	54836
ISDATDIRASentFltAcc_Cnt_M_u16	47320
ISDATDIRASentTimer_mS_M_u32	923424000
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	110
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	753
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	58452
ISDYN2CMMMsgTimer_mS_M_u32	407995648
ISDYNAASChkSumInvalidCount_Cnt_M_u16	28589
ISDYNAASChkSumValidCount_Cnt_M_u16	7772
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	8764
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	24086
ISDYNAASMsgLenValidCount_Cnt_M_u16	3933
ISDYNAASMsgTimeValidCount_Cnt_M_u16	28589
ISDYNAASMsgTimer_mS_M_u32	2326127872
ISDYNABRChkSumInvalidCount_Cnt_M_u16	22522
ISDYNABRChkSumValidCount_Cnt_M_u16	26928
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	18296
ISDYNABRMsgCountValidCount_Cnt_M_u16	51303
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	39462
ISDYNABRMsgLenValidCount_Cnt_M_u16	24196
ISDYNABRMsgTimeValidCount_Cnt_M_u16	12888
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	12351
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	64340
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	15330
ISDYNCMM208MsgTimer_mS_M_u32	443827456
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	12351
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	64340
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	58759

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1701537024
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	44273
ISDYNVOLChkSumValidCount_Cnt_M_u16	33679
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	19359
ISDYNVOLMsgCountValidCount_Cnt_M_u16	38390
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	44811
ISDYNVOLMsgLenValidCount_Cnt_M_u16	7306
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	60347
ISDYNVOLMsgTimer_mS_M_u32	2075731200
IgnOnTimer_mS_M_u32	188704000
IgnTimeOff_Sec_M_u32	2252474612
ManVehSpd_Kph_M_f32	496.604797
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	10
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	799937792
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	117
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3998905600
PrevISDATBSI412MsgDLCError_Cnt_M_u08	248
PrevISDATBSI412MsgRxTime_MSec_M_u32	33268992
PrevISDATBSI432MsgDLCError_Cnt_M_u08	121
PrevISDATBSI432MsgRxTime_MSec_M_u32	2945680640
PrevISDATDIRAMsgTxTime_MSec_M_u32	1470080256
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	141
PrevISDYN2CMMMsgRxTime_MSec_M_u32	393393408
PrevISDYNAASMsgDLCError_Cnt_M_u08	251
PrevISDYNAASMsgRxTime_MSec_M_u32	1909400832
PrevISDYNABRMsgDLCError_Cnt_M_u08	193
PrevISDYNABRMsgRxTime_MSec_M_u32	1452762368
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	170
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2926585088
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	169
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3983705344
PrevISDYNVOLMsgDLCError_Cnt_M_u08	103
PrevISDYNVOLMsgRxTime_MSec_M_u32	1075094784
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2115196160
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	118.212997
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	58540
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	31347
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	20321
VitesseVehicleBVRampValidCount_Cnt_M_u16	62184
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	59155
VitesseVehicleBVSigValidCount_Cnt_M_u16	7906
VitesseVehicleBV_Kph_M_f32	607.531128
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	58759
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	41518
VitesseVehiculeRoues_Kph_M_f32	505.146912
k_AASNTCEnableTimeout_mS_u16	22203
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	7784
k_AASNodeTimeout_mS_u16	53619
k_ABSNodeTimeout_mS_u16	34026
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	26950
k_ANGLEVOLANTSigValidThresh_Cnt_u16	45985
k_AngleVolantInvalidThresh_Cnt_u16	54036
k_AngleVolantValidThresh_Cnt_u16	2768
k_BSI552MsgTimeout_mS_u16	40801
k_BSINTCEnableTimeout_mS_u16	46311
k_BSINodeAbsentDiag_Cnt_str.Threshold	40485
k_BSINodeAbsentDiag_Cnt_str.PStep	51772
k_BSINodeAbsentDiag_Cnt_str.NStep	41255
k_BSINodeAbsentTimeout_mS_u16	42404
k_BSINodeTimeout_mS_u16	54836
k_BattOvHi_Volt_f32	13.6409998
k_BattOvLo_Volt_f32	12.3436003
k_BattUvHi_Volt_f32	1.98839998
k_BattUvLo_Volt_f32	30.0543003
k_CAVNTCEnableTimeout_mS_u16	50123
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	37773
k_CAVNodeTimeout_mS_u16	21895
k_CMM388MsgTimeout_mS_u16	23107
k_CMM388NTCEnableTimeout_mS_u16	45423
k_CMMNTCEnableTimeout_mS_u16	31268
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	14170
k_CONSANGLECPKMax_HwDeg_f32	648.944519
k_CONSANGLECPKMin_HwDeg_f32	-462.271606
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	64647
k_CONSANGLECPKSigValidThresh_Cnt_u16	63790
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	59697
k_CPKVehicleSpeedValidThresh_Cnt_u16	50760
k_CityParkInputInvalidThresh_Cnt_u16	59960
k_CityParkInputValidThresh_Cnt_u16	60869
k_ComputerRazGCTSigValidThresh_Cnt_u16	62058
k_CptTemporelSigValidThresh_Cnt_u16	46812
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	12582
k_DMDFCTCPKSigValidThresh_Cnt_u16	13700
k_DMDFCTCPKValidCount_Cnt_u16	24657
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	58452
k_DMDRELAXECPKSigValidThresh_Cnt_u16	48235
k_DMDRelaxeConsistentThresh_Cnt_u16	46633
k_DateValidThresh_Cnt_u16	414
k_DefaultVehSpd_Kph_f32	224.913895
k_DiagMuxOnAbsentTimeout_mS_u16	44998
k_EMNodeTimeout_mS_u16	47428
k_ESPNTCEnableTimeout_mS_u16	33315
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	41986
k_EtatMTSigInvalidThresh_Cnt_u16	41421
k_EtatMTSigValidThresh_Cnt_u16	31555
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	6768
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	9371
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	634
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	20085
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	38183
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	52029
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	39096
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	62611
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	51043
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	35340
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	9999
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	38426
k_ISDATDIRASentDiag_Cnt_str.Threshold	19232

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	3193
k_ISDATDIRASentDiag_Cnt_str.NStep	10166
k_ISDATDIRASentTimeout_mS_u16	34854
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	63547
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	49228
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	17311
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	28410
k_ISDYNAASChkSumValidThresh_Cnt_u16	49200
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	56952
k_ISDYNAASMsgCountValidThresh_Cnt_u16	40807
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	32462
k_ISDYNAASMsgLenValidThresh_Cnt_u16	13383
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	50761
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	64188
k_ISDYNABRChkSumValidThresh_Cnt_u16	9114
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	30121
k_ISDYNABRMsgCountValidThresh_Cnt_u16	37368
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	17083
k_ISDYNABRMsgLenValidThresh_Cnt_u16	10966
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	52907
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	26496
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	43102
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	14758
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	10206
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	61933
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	19253
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	34208
k_ISDYNVOLChkSumValidThresh_Cnt_u16	4674
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	33759
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	50948
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	20548
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	31246
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	14860
k_IgnOnTimeout_mS_u16	22988
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	162.473007
k_PowerCutVehSpdLowThresh_Kph_f32	96.887001
k_PowerCutVehSpdLowTimeout_mS_u16	3863
k_VBattMaxAAS_Volt_f32	13.5344
k_VBattMaxBSI_Volt_f32	4.89970016
k_VBattMaxCAV_Volt_f32	2.98219991
k_VBattMaxCMM388_Volt_f32	18.2556
k_VBattMaxCMM_Volt_f32	15.2223997
k_VBattMaxESP_Volt_f32	2.47070003
k_VBattMinAAS_Volt_f32	20.7404003
k_VBattMinBSI_Volt_f32	2.47070003
k_VBattMinCAV_Volt_f32	31.8544998
k_VBattMinCMM388_Volt_f32	13.4632998
k_VBattMinCMM_Volt_f32	15.9427996
k_VBattMinESP_Volt_f32	15.2223997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	57213
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	45968
k_VitesseVehicleBVRampValidThresh_Cnt_u16	25247
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	23183
k_VitesseVehicleBVSigValidThresh_Cnt_u16	25554
k_VitesseVehicleBVSpeedPassThresh_kph_f32	2.35310006
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	13559
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	64766
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1261946112
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	169
target_SrlComInput_Per1_Batt_Volt_f32.value	15.1590004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2421355776
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	151
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.756241977
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2609997056
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2483553536
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	11
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	655271168
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	243
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3164947712
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3167479040
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2407695616
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2630427904
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	18
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	203
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	214
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	215
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	231
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2067416320
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	26
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	62
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	990930176
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	17
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2701591808
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1636672768
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	55
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	183
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	209
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	239
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1133802752
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3904
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.398501992
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	347039
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	114.709503
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	61294

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	496.604797	496.604797	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	12888	12888	✔
CONSANGLECPK_HwDeg_M_f32	-230.117798	-230.117798 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1713429248	1713429248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	5	5	✔
EffacDefaultDiagTimer_mS_M_u32[1]	155	155	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2500	2500	✔
ElecIntTimer_mS_M_u32[1]	3504	3504	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	414	414	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	15330	15330	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	56088	56088	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	54836	54836	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	19232	19232	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	58452	58452	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	28589	28589	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	12888	12888	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	15330	15330	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	58759	58759	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	60347	60347	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	188704000	188704000	✔
IgnTimeOff_Sec_M_u32	2252474612	2252474612	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	64	64	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2609997056	2609997056	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	242	242	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2483553536	2483553536	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	11	11	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	655271168	655271168	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	243	243	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3164947712	3164947712	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1470080256	1470080256	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	205	205	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2407695616	2407695616	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	144	144	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2630427904	2630427904	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	231	231	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2067416320	2067416320	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	990930176	990930176	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	17	17	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2701591808	2701591808	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	119	119	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1636672768	1636672768	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1133802752	1133802752	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	118.212997	118.212997	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	607.531128	607.531128	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	505.146912	505.146912	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	12888	12888	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2252474612	2252474612	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-230.117798	-230.117798 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	496.604797	496.604797	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.403 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4074940672
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	807
AASNodeAbsentTimer_mS_M_u32	3152861440
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	55561
ANGLEVOLANTSigValidCount_Cnt_M_u16	61103
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	58112
AngleVolantMsgTimer_mS_M_u32	4074940672
AngleVolantValidCount_Cnt_M_u16	51990
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	755603712
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3528857856
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1991559424
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3560212736
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	58948
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3619899648
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	57381
CAVNodeAbsentTimer_mS_M_u32	3510827264
CDD_SrlComVehSpd_Kph_G_f32	587.992676
CMM388NTCEnableTimer_mS_M_u32	2923575552
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3814783232
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	50724
CMMNodeAbsentTimer_mS_M_u32	2258012416
CONSANGLECPKSigInvalidCount_Cnt_M_u16	63106
CONSANGLECPKSigValidCount_Cnt_M_u16	47416
CONSANGLECPK_Cnt_M_u16	17351
CONSANGLECPK_HwDeg_M_f32	-242.1147
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17351
CPKVehicleSpeedMsgTimer_mS_M_u32	754297088
CPKVehicleSpeedValidCount_Cnt_M_u16	27779
CityParkInputConsistentCount_Cnt_M_u16	22570
CityParkInputInvalidCount_Cnt_M_u16	63447
CityParkInputMsgTimer_mS_M_u32	2925637120
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2382420224
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	60987

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2103015680
ComputerRazGCTSigValidCount_Cnt_M_u16	22619
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	5827
DMDFCTCPKSigValidCount_Cnt_M_u16	46768
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	27283
DMDRELAXECPKSigValidCount_Cnt_M_u16	29625
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	56155
DateInvalidTimer_mS_M_u32	3528857856
DiagMuxOnAbsentTimer_mS_M_u32	3553716480
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3560212736
ESPNTCEnableTimer_mS_M_u32	2660882688
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	7573
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	79
EffacDefaultDiagTimer_mS_M_u32[1]	699
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	12
ElecIntTimer_mS_M_u32[1]	19
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	741165312
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	5716
EtatMTSigValidCount_Cnt_M_u16	56694
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	42508
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	56386
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	64206
ISDAT4V2BSI552MsgTimer_mS_M_u32	2141882624
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	3134
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	30984
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	56694
ISDATBSI3F2MsgTimer_mS_M_u32	1548183808
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	24063
ISDATBSI412MsgLenValidCount_Cnt_M_u16	62777
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	5716
ISDATBSI412MsgTimer_mS_M_u32	156805376
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	9784
ISDATBSI432MsgLenValidCount_Cnt_M_u16	9385
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	15218
ISDATDIRASentFltAcc_Cnt_M_u16	12630
ISDATDIRASentTimer_mS_M_u32	754297088
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	22717
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	51990
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	57214
ISDYN2CMMMsgTimer_mS_M_u32	58448128
ISDYNAASChkSumInvalidCount_Cnt_M_u16	45233
ISDYNAASChkSumValidCount_Cnt_M_u16	23798
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	8657
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	55796
ISDYNAASMsgLenValidCount_Cnt_M_u16	55377
ISDYNAASMsgTimeValidCount_Cnt_M_u16	45233
ISDYNAASMsgTimer_mS_M_u32	774781184
ISDYNABRChkSumInvalidCount_Cnt_M_u16	44763
ISDYNABRChkSumValidCount_Cnt_M_u16	2089
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	26604
ISDYNABRMsgCountValidCount_Cnt_M_u16	39537
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	29885
ISDYNABRMsgLenValidCount_Cnt_M_u16	64947
ISDYNABRMsgTimeValidCount_Cnt_M_u16	17351
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	49585
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	56571
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	56694
ISDYNCMM208MsgTimer_mS_M_u32	3430586624
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	49585
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	56571
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	23692

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2662054144
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	55032
ISDYNVOLChkSumValidCount_Cnt_M_u16	9774
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	65081
ISDYNVOLMsgCountValidCount_Cnt_M_u16	27302
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	18778
ISDYNVOLMsgLenValidCount_Cnt_M_u16	21872
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	50724
ISDYNVOLMsgTimer_mS_M_u32	960854272
IgnOnTimer_mS_M_u32	1455405312
IgnTimeOff_Sec_M_u32	956050392
ManVehSpd_Kph_M_f32	359.233002
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	14
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	253
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1153788160
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	164
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	391104768
PrevISDATBSI412MsgDLCError_Cnt_M_u08	75
PrevISDATBSI412MsgRxTime_MSec_M_u32	4233099520
PrevISDATBSI432MsgDLCError_Cnt_M_u08	166
PrevISDATBSI432MsgRxTime_MSec_M_u32	2136856832
PrevISDATDIRAMsgTxTime_MSec_M_u32	1429469440
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	147
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1811679488
PrevISDYNAASMsgDLCError_Cnt_M_u08	150
PrevISDYNAASMsgRxTime_MSec_M_u32	4131092736
PrevISDYNABRMsgDLCError_Cnt_M_u08	161
PrevISDYNABRMsgRxTime_MSec_M_u32	2912401664
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	180
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1965848832
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	159
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3270301952
PrevISDYNVOLMsgDLCError_Cnt_M_u08	158
PrevISDYNVOLMsgRxTime_MSec_M_u32	1916336384
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1993255168
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	621.56781
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	20330
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	39495
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	41647
VitesseVehicleBVRampValidCount_Cnt_M_u16	18252
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	45006
VitesseVehicleBVSigValidCount_Cnt_M_u16	48948
VitesseVehicleBV_Kph_M_f32	619.552307
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	23692
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	62538
VitesseVehiculeRoues_Kph_M_f32	464.028809
k_AASNTCEnableTimeout_mS_u16	46874
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	43965
k_AASNodeTimeout_mS_u16	8519
k_ABSNodeTimeout_mS_u16	36596
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	61215
k_ANGLEVOLANTSigValidThresh_Cnt_u16	40144
k_AngleVolantInvalidThresh_Cnt_u16	32819
k_AngleVolantValidThresh_Cnt_u16	63447
k_BSI552MsgTimeout_mS_u16	365
k_BSINTCEnableTimeout_mS_u16	11536
k_BSINodeAbsentDiag_Cnt_str.Threshold	59680
k_BSINodeAbsentDiag_Cnt_str.PStep	24227
k_BSINodeAbsentDiag_Cnt_str.NStep	21849
k_BSINodeAbsentTimeout_mS_u16	62424
k_BSINodeTimeout_mS_u16	15218
k_BattOvHi_Volt_f32	12.0661001
k_BattOvLo_Volt_f32	5.87860012
k_BattUvHi_Volt_f32	25.1783009
k_BattUvLo_Volt_f32	12.2180004
k_CAVNTCEnableTimeout_mS_u16	50213
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	62619
k_CAVNodeTimeout_mS_u16	3694
k_CMM388MsgTimeout_mS_u16	51751
k_CMM388NTCEnableTimeout_mS_u16	7955
k_CMMNTCEnableTimeout_mS_u16	16150
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	59190
k_CONSANGLECPKMax_HwDeg_f32	367.740204
k_CONSANGLECPKMin_HwDeg_f32	-372.531799
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	41868
k_CONSANGLECPKSigValidThresh_Cnt_u16	31562
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	1125
k_CPKVehicleSpeedValidThresh_Cnt_u16	27278
k_CityParkInputInvalidThresh_Cnt_u16	21625
k_CityParkInputValidThresh_Cnt_u16	22570
k_ComputerRazGCTSigValidThresh_Cnt_u16	11580
k_CptTemporelSigValidThresh_Cnt_u16	64646
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	15293
k_DMDFCTCPKSigValidThresh_Cnt_u16	1203
k_DMDFCTCPKValidCount_Cnt_u16	27756
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	57214
k_DMDRELAXECPKSigValidThresh_Cnt_u16	9643
k_DMDRelaxeConsistentThresh_Cnt_u16	35529
k_DateValidThresh_Cnt_u16	64206
k_DefaultVehSpd_Kph_f32	46.7159996
k_DiagMuxOnAbsentTimeout_mS_u16	21397
k_EMNodeTimeout_mS_u16	44347
k_ESPNTCEnableTimeout_mS_u16	21009
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	51294
k_EtatMTSigInvalidThresh_Cnt_u16	64158
k_EtatMTSigValidThresh_Cnt_u16	45100
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	18772
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	42966
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	30063
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	48311
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	49729
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	35859
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	37425
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	51554
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	50764
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	17339
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	39060
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	40980
k_ISDATDIRASentDiag_Cnt_str.Threshold	40598

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	346
k_ISDATDIRASentDiag_Cnt_str.NStep	15969
k_ISDATDIRASentTimeout_mS_u16	44231
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	64645
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58112
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	19021
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	62939
k_ISDYNAASChkSumValidThresh_Cnt_u16	36649
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	12012
k_ISDYNAASMsgCountValidThresh_Cnt_u16	41329
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	14319
k_ISDYNAASMsgLenValidThresh_Cnt_u16	42587
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	1016
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	58419
k_ISDYNABRChkSumValidThresh_Cnt_u16	14761
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	44356
k_ISDYNABRMsgCountValidThresh_Cnt_u16	2346
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	19748
k_ISDYNABRMsgLenValidThresh_Cnt_u16	58517
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	11725
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	62590
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	54148
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	2410
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	40969
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	62895
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	48303
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	30054
k_ISDYNVOLChkSumValidThresh_Cnt_u16	39904
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	57454
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	63549
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	59712
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	18786
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	13724
k_IgnOnTimeout_mS_u16	22354
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	7.00159979
k_PowerCutVehSpdLowThresh_Kph_f32	102.540703
k_PowerCutVehSpdLowTimeout_mS_u16	52278
k_VBattMaxAAS_Volt_f32	4.79559994
k_VBattMaxBSI_Volt_f32	3.80369997
k_VBattMaxCAV_Volt_f32	1.23399997
k_VBattMaxCMM388_Volt_f32	6.2967
k_VBattMaxCMM_Volt_f32	20.3511009
k_VBattMaxESP_Volt_f32	3.6329999
k_VBattMinAAS_Volt_f32	24.2593002
k_VBattMinBSI_Volt_f32	3.6329999
k_VBattMinCAV_Volt_f32	1.91970003
k_VBattMinCMM388_Volt_f32	2.64389992
k_VBattMinCMM_Volt_f32	9.48149967
k_VBattMinESP_Volt_f32	20.3511009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	51303
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	35153
k_VitesseVehicleBVRampValidThresh_Cnt_u16	17721
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	11566
k_VitesseVehicleBVSigValidThresh_Cnt_u16	49735
k_VitesseVehicleBVSpeedPassThresh_kph_f32	407.731598
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	10021
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	22594
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3528857856
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	159
target_SrlComInput_Per1_Batt_Volt_f32.value	9.96829987
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2129676544
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	44
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.938696623
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2696001792
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	98
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2956613888
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2807232768
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1845205248
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3962845440
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	167565568
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2941614336
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	39
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	115
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	186
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	221
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	222
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	41
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1260427520
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	67
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	68
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	94
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	139
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3353393408
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	163
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2095667456
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3649173760
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	190
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	216
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	223
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	782878976
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1346
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.61431998
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	15483
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	199.164001
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	22220

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	17351	17351	✔
CONSANGLECPK_HwDeg_M_f32	-242.1147	-242.1147 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3251510528	3251510528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	79	79	✔
EffacDefaultDiagTimer_mS_M_u32[1]	699	699	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	12	12	✔
ElecIntTimer_mS_M_u32[1]	19	19	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	40598	40598	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	3251510528	3251510528	✔
IgnTimeOff_Sec_M_u32	956050392	956050392	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	15	15	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2696001792	2696001792	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	98	98	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2956613888	2956613888	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2807232768	2807232768	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	74	74	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1845205248	1845205248	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1429469440	1429469440	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	64	64	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	167565568	167565568	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	229	229	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2941614336	2941614336	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	41	41	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1260427520	1260427520	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	139	139	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3353393408	3353393408	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	163	163	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2095667456	2095667456	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	239	239	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3649173760	3649173760	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	782878976	782878976	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	621.56781	621.56781	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	619.552307	619.552307	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	464.028809	464.028809	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	17351	17351	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	956050392	956050392	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-242.1147	-242.1147 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.404 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	618317824
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	42509
AASNodeAbsentTimer_mS_M_u32	4001118208
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	52837
ANGLEVOLANTSigValidCount_Cnt_M_u16	32820
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	43650
AngleVolantMsgTimer_mS_M_u32	618317824
AngleVolantValidCount_Cnt_M_u16	5310
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	4263901184
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3762321408
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	165963776
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2690983936
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	21172
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1085859840
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	12178
CAVNodeAbsentTimer_mS_M_u32	788125696
CDD_SrlComVehSpd_Kph_G_f32	586.439087
CMM388NTCEnableTimer_mS_M_u32	2767984640
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	4037007360
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	25942
CMMNodeAbsentTimer_mS_M_u32	2436835328
CONSANGLECPKSigInvalidCount_Cnt_M_u16	18683
CONSANGLECPKSigValidCount_Cnt_M_u16	13210
CONSANGLECPK_Cnt_M_u16	36845
CONSANGLECPK_HwDeg_M_f32	-53.6144981
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	36845
CPKVehicleSpeedMsgTimer_mS_M_u32	2191640576
CPKVehicleSpeedValidCount_Cnt_M_u16	7935
CityParkInputConsistentCount_Cnt_M_u16	48514
CityParkInputInvalidCount_Cnt_M_u16	57213
CityParkInputMsgTimer_mS_M_u32	2696001792
CityParkInputValidCount_Cnt_M_u16	3

Name	Input Value
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3359651840
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	13521
ComputerRazGCTSigInvalidTimer_mS_M_u32	2763413504
ComputerRazGCTSigValidCount_Cnt_M_u16	49391
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	12985
DMDFCTCPKSigValidCount_Cnt_M_u16	26032
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	49607
DMDRELAXECPKSigValidCount_Cnt_M_u16	39190
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	15984
DateInvalidTimer_mS_M_u32	3762321408
DiagMuxOnAbsentTimer_mS_M_u32	2903410688
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2690983936
ESPNTCEnableTimer_mS_M_u32	980760576
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	33217
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	86
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	79
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1803216896
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	34245
EtatMTSigValidCount_Cnt_M_u16	4896
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	57949
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	29308
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	37206
ISDAT4V2BSI552MsgTimer_mS_M_u32	4127401984
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	9095
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	24554
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	4896
ISDATBSI3F2MsgTimer_mS_M_u32	1806469120
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	49987
ISDATBSI412MsgLenValidCount_Cnt_M_u16	16470
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	34245
ISDATBSI412MsgTimer_mS_M_u32	964216832
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	38170
ISDATBSI432MsgLenValidCount_Cnt_M_u16	48261
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	37291
ISDATDIRASentFltAcc_Cnt_M_u16	16383
ISDATDIRASentTimer_mS_M_u32	2191640576
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	43275
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	5310
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	33928
ISDYN2CMMMsgTimer_mS_M_u32	332347392
ISDYNAASChkSumInvalidCount_Cnt_M_u16	17775
ISDYNAASChkSumValidCount_Cnt_M_u16	45918
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	48269
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	15909
ISDYNAASMsgLenValidCount_Cnt_M_u16	5580
ISDYNAASMsgTimeValidCount_Cnt_M_u16	17775
ISDYNAASMsgTimer_mS_M_u32	3577223168
ISDYNABRChkSumInvalidCount_Cnt_M_u16	27760
ISDYNABRChkSumValidCount_Cnt_M_u16	62279
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	52158
ISDYNABRMsgCountValidCount_Cnt_M_u16	42733
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	31306
ISDYNABRMsgLenValidCount_Cnt_M_u16	4649
ISDYNABRMsgTimeValidCount_Cnt_M_u16	36845
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	3489
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	60804
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	4896
ISDYNCMM208MsgTimer_mS_M_u32	601028608

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	3489
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	60804
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	47196
ISDYNCMM388MsgTimer_mS_M_u32	1505728512
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	65433
ISDYNVOLChkSumValidCount_Cnt_M_u16	17592
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	54359
ISDYNVOLMsgCountValidCount_Cnt_M_u16	41422
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	21106
ISDYNVOLMsgLenValidCount_Cnt_M_u16	57584
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	25942
ISDYNVOLMsgTimer_mS_M_u32	552753152
IgnOnTimer_mS_M_u32	2172884992
IgnTimeOff_Sec_M_u32	615725545
ManVehSpd_Kph_M_f32	13.2376003
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	16
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	72
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	707954688
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	19
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1410557952
PrevISDATBSI412MsgDLCError_Cnt_M_u08	30
PrevISDATBSI412MsgRxTime_MSec_M_u32	567465984
PrevISDATBSI432MsgDLCError_Cnt_M_u08	77
PrevISDATBSI432MsgRxTime_MSec_M_u32	2821273600
PrevISDATDIRAMsgTxTime_MSec_M_u32	2804340736
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	8
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1460578304
PrevISDYNAASMsgDLCError_Cnt_M_u08	96
PrevISDYNAASMsgRxTime_MSec_M_u32	1108367360
PrevISDYNABRMsgDLCError_Cnt_M_u08	168
PrevISDYNABRMsgRxTime_MSec_M_u32	3707475968
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	143
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3376240640
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	161
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3648796672
PrevISDYNVOLMsgDLCError_Cnt_M_u08	214
PrevISDYNVOLMsgRxTime_MSec_M_u32	2753026048
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1226229760
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	490.841309
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	13763
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	10218
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	36852
VitesseVehicleBVRampValidCount_Cnt_M_u16	29915
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	40470
VitesseVehicleBVSigValidCount_Cnt_M_u16	25253
VitesseVehicleBV_Kph_M_f32	32.8349991
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	47196
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	17379

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	139.1875
k_AASNTCEnableTimeout_mS_u16	16884
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	52937
k_AASNodeTimeout_mS_u16	37610
k_ABSNodeTimeout_mS_u16	52774
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	38501
k_ANGLEVOLANTSigValidThresh_Cnt_u16	45072
k_AngleVolantInvalidThresh_Cnt_u16	20967
k_AngleVolantValidThresh_Cnt_u16	57213
k_BSI552MsgTimeout_mS_u16	26746
k_BSINTCEnableTimeout_mS_u16	57490
k_BSINodeAbsentDiag_Cnt_str.Threshold	27348
k_BSINodeAbsentDiag_Cnt_str.PStep	2188
k_BSINodeAbsentDiag_Cnt_str.NStep	62121
k_BSINodeAbsentTimeout_mS_u16	55290
k_BSINodeTimeout_mS_u16	37291
k_BattOvHi_Volt_f32	31.3104
k_BattOvLo_Volt_f32	16.3255005
k_BattUvHi_Volt_f32	5.49429989
k_BattUvLo_Volt_f32	12.2243004
k_CAVNTCEnableTimeout_mS_u16	12947
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	18992
k_CAVNodeTimeout_mS_u16	45367
k_CMM388MsgTimeout_mS_u16	20749
k_CMM388NTCEnableTimeout_mS_u16	585
k_CMMNTCEnableTimeout_mS_u16	60159
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	6943
k_CONSANGLECPKMax_HwDeg_f32	445.08371
k_CONSANGLECPKMin_HwDeg_f32	-104.022903
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	58204
k_CONSANGLECPKSigValidThresh_Cnt_u16	44771
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	57744
k_CPKVehicleSpeedValidThresh_Cnt_u16	39318
k_CityParkInputInvalidThresh_Cnt_u16	29590
k_CityParkInputValidThresh_Cnt_u16	48514
k_ComputerRazGCTSigValidThresh_Cnt_u16	14477
k_CptTemporelSigValidThresh_Cnt_u16	19824
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	9546
k_DMDFCTCPKSigValidThresh_Cnt_u16	64809
k_DMDFCTCPKValidCount_Cnt_u16	24636
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	33928
k_DMDRELAXECPKSigValidThresh_Cnt_u16	50367
k_DMDRelaxeConsistentThresh_Cnt_u16	36197
k_DateValidThresh_Cnt_u16	37206
k_DefaultVehSpd_Kph_f32	11.8628998
k_DiagMuxOnAbsentTimeout_mS_u16	6275
k_EMNodeTimeout_mS_u16	18640
k_ESPNTCEnableTimeout_mS_u16	35278
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	6055
k_EtatMTSigInvalidThresh_Cnt_u16	21799
k_EtatMTSigValidThresh_Cnt_u16	51006
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	36547
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	54782
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	47539
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	13852
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	43071
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	35079
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	29999
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	62042
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	1246
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	24593

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	9284
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	57860
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	8876
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	53425
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	43650
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	37146
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	38768
k_ISDYNAASChkSumValidThresh_Cnt_u16	24135
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	30398
k_ISDYNAASMsgCountValidThresh_Cnt_u16	37357
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	8500
k_ISDYNAASMsgLenValidThresh_Cnt_u16	21422
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	6808
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	33768
k_ISDYNABRChkSumValidThresh_Cnt_u16	46663
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	64948
k_ISDYNABRMsgCountValidThresh_Cnt_u16	56515
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	53334
k_ISDYNABRMsgLenValidThresh_Cnt_u16	11457
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	47834
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	38535
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	46772
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	9857
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	31077
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	27444
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	61685
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	55566
k_ISDYNVOLChkSumValidThresh_Cnt_u16	43105
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	56630
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	29451
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	48385
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	32604
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	39148
k_IgnOnTimeout_mS_u16	58186
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	143.505997
k_PowerCutVehSpdLowThresh_Kph_f32	24.8887997
k_PowerCutVehSpdLowTimeout_mS_u16	29344
k_VBattMaxAAS_Volt_f32	24.0286007
k_VBattMaxBSI_Volt_f32	6.44379997
k_VBattMaxCAV_Volt_f32	15.0874004
k_VBattMaxCMM388_Volt_f32	8.21389961
k_VBattMaxCMM_Volt_f32	10.4911003
k_VBattMaxESP_Volt_f32	32
k_VBattMinAAS_Volt_f32	9.30459976
k_VBattMinBSI_Volt_f32	32
k_VBattMinCAV_Volt_f32	1.00989997
k_VBattMinCMM388_Volt_f32	19.5268993
k_VBattMinCMM_Volt_f32	12.5167999
k_VBattMinESP_Volt_f32	10.4911003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	29963
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	13582
k_VitesseVehicleBVRampValidThresh_Cnt_u16	65367
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	12216
k_VitesseVehicleBVSigValidThresh_Cnt_u16	13099
k_VitesseVehicleBVSpeedPassThresh_kph_f32	161.299896
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	23186
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	39417
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3762321408
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	161
target_SrlComInput_Per1_Batt_Volt_f32.value	14.9715004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1060235264
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	243
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.636306107
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3954022400
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	663992320
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	204
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3972651008
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2203056128
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	858134528
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	163
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1145845760
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4274149376
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	31
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	113
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	151
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	176
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	246
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	255
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3219191808
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	133
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	184
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	186
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	196
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	213
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	215
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4062222336
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1032239104
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3527202816
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	149
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	188
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	224
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4127549440
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	21
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0232890826
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	714997
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	169.268906
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	10141

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	13.2376003	13.2376003	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	36845	36845	✔
CONSANGLECPK_HwDeg_M_f32	-53.6144981	-53.6144981 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1713429248	1713429248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔
EffacDefaultDiagTimer_mS_M_u32[1]	86	86	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	79	79	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	37206	37206	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	4896	4896	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	34245	34245	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	37291	37291	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	41895	41895	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	33928	33928	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	17775	17775	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	36845	36845	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	4896	4896	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	47196	47196	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	25942	25942	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	2172884992	2172884992	✔
IgnTimeOff_Sec_M_u32	615725545	615725545	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	66	66	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3954022400	3954022400	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	148	148	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	663992320	663992320	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	204	204	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3972651008	3972651008	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	49	49	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2203056128	2203056128	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2804340736	2804340736	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	163	163	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1145845760	1145845760	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	63	63	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4274149376	4274149376	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	104	104	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3219191808	3219191808	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4062222336	4062222336	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	75	75	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1032239104	1032239104	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	242	242	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3527202816	3527202816	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4127549440	4127549440	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	490.841309	490.841309	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	32.8349991	32.8349991	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	139.1875	139.1875	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	36845	36845	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	615725545	615725545	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-53.6144981	-53.6144981 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	13.2376003	13.2376003	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.405 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	439249664
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	32918
AASNodeAbsentTimer_mS_M_u32	1326062336
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	2445
ANGLEVOLANTSigValidCount_Cnt_M_u16	7136
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	34615
AngleVolantMsgTimer_mS_M_u32	439249664
AngleVolantValidCount_Cnt_M_u16	57603
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	4144814848
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3669842688
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	428968704
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1225739008
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	30880
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1729366784
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	33414
CAVNodeAbsentTimer_mS_M_u32	202455808
CDD_SrlComVehSpd_Kph_G_f32	53.2969017
CMM388NTCEnableTimer_mS_M_u32	2198502144
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3743365888
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	10748
CMMNodeAbsentTimer_mS_M_u32	1585531648
CONSANGLECPKSigInvalidCount_Cnt_M_u16	8396
CONSANGLECPKSigValidCount_Cnt_M_u16	51375
CONSANGLECPK_Cnt_M_u16	49078
CONSANGLECPK_HwDeg_M_f32	175.009201
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	49078
CPKVehicleSpeedMsgTimer_mS_M_u32	3705236224
CPKVehicleSpeedValidCount_Cnt_M_u16	5800
CityParkInputConsistentCount_Cnt_M_u16	63159
CityParkInputInvalidCount_Cnt_M_u16	36293
CityParkInputMsgTimer_mS_M_u32	3954022400
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3518896896
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	58442

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1021033216
ComputerRazGCTSigValidCount_Cnt_M_u16	57456
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	33809
DMDFCTCPKSigValidCount_Cnt_M_u16	45804
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	14183
DMDRELAXECPKSigValidCount_Cnt_M_u16	55610
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	21613
DateInvalidTimer_mS_M_u32	3669842688
DiagMuxOnAbsentTimer_mS_M_u32	9644800
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1225739008
ESPNTCEnableTimer_mS_M_u32	2401180416
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	27771
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	5
EffacDefaultDiagTimer_mS_M_u32[1]	155
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2500
ElecIntTimer_mS_M_u32[1]	3504
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1858996992
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	38318
EtatMTSigValidCount_Cnt_M_u16	17757
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	23718
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	5129
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	18426
ISDAT4V2BSI552MsgTimer_mS_M_u32	1077234432
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	15847
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	126
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	17757
ISDATBSI3F2MsgTimer_mS_M_u32	3166251776
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	40882
ISDATBSI412MsgLenValidCount_Cnt_M_u16	24634
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	38318
ISDATBSI412MsgTimer_mS_M_u32	3562302208
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	43696
ISDATBSI432MsgLenValidCount_Cnt_M_u16	52271
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	59
ISDATDIRASentFltAcc_Cnt_M_u16	17727
ISDATDIRASentTimer_mS_M_u32	3705236224
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	27740
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	57603
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	35492
ISDYN2CMMMsgTimer_mS_M_u32	3943766784
ISDYNAASChkSumInvalidCount_Cnt_M_u16	43632
ISDYNAASChkSumValidCount_Cnt_M_u16	2148
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	58774
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	25293
ISDYNAASMsgLenValidCount_Cnt_M_u16	25496
ISDYNAASMsgTimeValidCount_Cnt_M_u16	43632
ISDYNAASMsgTimer_mS_M_u32	3797318400
ISDYNABRChkSumInvalidCount_Cnt_M_u16	53486
ISDYNABRChkSumValidCount_Cnt_M_u16	33833
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	4995
ISDYNABRMsgCountValidCount_Cnt_M_u16	10679
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	35039
ISDYNABRMsgLenValidCount_Cnt_M_u16	10498
ISDYNABRMsgTimeValidCount_Cnt_M_u16	49078
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	12351
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	64340
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	17757
ISDYNCMM208MsgTimer_mS_M_u32	2047204096
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	12351
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	64340
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	60969

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3535796992
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	62706
ISDYNVOLChkSumValidCount_Cnt_M_u16	36181
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	38711
ISDYNVOLMsgCountValidCount_Cnt_M_u16	63122
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	65128
ISDYNVOLMsgLenValidCount_Cnt_M_u16	15019
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	10748
ISDYNVOLMsgTimer_mS_M_u32	3089611520
IgnOnTimer_mS_M_u32	1802763008
IgnTimeOff_Sec_M_u32	2050200102
ManVehSpd_Kph_M_f32	300.622986
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	17
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	225
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	421997312
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	64
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3070528256
PrevISDATBSI412MsgDLCError_Cnt_M_u08	32
PrevISDATBSI412MsgRxTime_MSec_M_u32	3615898368
PrevISDATBSI432MsgDLCError_Cnt_M_u08	213
PrevISDATBSI432MsgRxTime_MSec_M_u32	369302272
PrevISDATDIRAMsgTxTime_MSec_M_u32	2542418688
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	30
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2870135552
PrevISDYNAASMsgDLCError_Cnt_M_u08	242
PrevISDYNAASMsgRxTime_MSec_M_u32	1288551168
PrevISDYNABRMsgDLCError_Cnt_M_u08	221
PrevISDYNABRMsgRxTime_MSec_M_u32	957086464
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	200
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2873539328
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	30
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2383026944
PrevISDYNVOLMsgDLCError_Cnt_M_u08	234
PrevISDYNVOLMsgRxTime_MSec_M_u32	2763471616
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2642045696
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	324.707092
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	29683
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	9534
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	26976
VitesseVehicleBVRampValidCount_Cnt_M_u16	17003
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	40570
VitesseVehicleBVSigValidCount_Cnt_M_u16	30861
VitesseVehicleBV_Kph_M_f32	465.524902
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	60969
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	21332
VitesseVehiculeRoues_Kph_M_f32	570.780823
k_AASNTCEnableTimeout_mS_u16	34209
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	40674
k_AASNodeTimeout_mS_u16	58430
k_ABSNodeTimeout_mS_u16	42442
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	37583
k_ANGLEVOLANTSigValidThresh_Cnt_u16	56718
k_AngleVolantInvalidThresh_Cnt_u16	5129
k_AngleVolantValidThresh_Cnt_u16	36293
k_BSI552MsgTimeout_mS_u16	399
k_BSINTCEnableTimeout_mS_u16	43080
k_BSINodeAbsentDiag_Cnt_str.Threshold	40485
k_BSINodeAbsentDiag_Cnt_str.PStep	51772
k_BSINodeAbsentDiag_Cnt_str.NStep	41255
k_BSINodeAbsentTimeout_mS_u16	57039
k_BSINodeTimeout_mS_u16	59
k_BattOvHi_Volt_f32	12.4549999
k_BattOvLo_Volt_f32	28.0515995
k_BattUvHi_Volt_f32	16.8416996
k_BattUvLo_Volt_f32	28.1044006
k_CAVNTCEnableTimeout_mS_u16	27779
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	10924
k_CAVNodeTimeout_mS_u16	55320
k_CMM388MsgTimeout_mS_u16	32662
k_CMM388NTCEnableTimeout_mS_u16	23522
k_CMMNTCEnableTimeout_mS_u16	51071
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	48544
k_CONSANGLECPKMax_HwDeg_f32	662.233093
k_CONSANGLECPKMin_HwDeg_f32	-298.678406
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	27945
k_CONSANGLECPKSigValidThresh_Cnt_u16	4692
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	4172
k_CPKVehicleSpeedValidThresh_Cnt_u16	10425
k_CityParkInputInvalidThresh_Cnt_u16	54140
k_CityParkInputValidThresh_Cnt_u16	63159
k_ComputerRazGCTSigValidThresh_Cnt_u16	38613
k_CptTemporelSigValidThresh_Cnt_u16	53228
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	34783
k_DMDFCTCPKSigValidThresh_Cnt_u16	26626
k_DMDFCTCPKValidCount_Cnt_u16	28680
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	35492
k_DMDRELAXECPKSigValidThresh_Cnt_u16	37311
k_DMDRelaxeConsistentThresh_Cnt_u16	20429
k_DateValidThresh_Cnt_u16	18426
k_DefaultVehSpd_Kph_f32	149.656403
k_DiagMuxOnAbsentTimeout_mS_u16	65012
k_EMNodeTimeout_mS_u16	46413
k_ESPNTCEnableTimeout_mS_u16	25554
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	59400
k_EtatMTSigInvalidThresh_Cnt_u16	45769
k_EtatMTSigValidThresh_Cnt_u16	42052
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	38067
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	38594
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	1572
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	39464
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	47999
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	24166
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	40561
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	48816
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	27492
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	57162
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	19057
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	38002
k_ISDATDIRASentDiag_Cnt_str.Threshold	1170

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	4955
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	40506
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	48235
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	34615
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	32238
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	20462
k_ISDYNAASChkSumValidThresh_Cnt_u16	17193
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	4739
k_ISDYNAASMsgCountValidThresh_Cnt_u16	26807
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	49826
k_ISDYNAASMsgLenValidThresh_Cnt_u16	45554
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	48630
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	25605
k_ISDYNABRChkSumValidThresh_Cnt_u16	13480
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	30624
k_ISDYNABRMsgCountValidThresh_Cnt_u16	563
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	59644
k_ISDYNABRMsgLenValidThresh_Cnt_u16	27515
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	33774
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	24999
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	51551
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	17785
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	2189
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	23264
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	14685
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	19025
k_ISDYNVOLChkSumValidThresh_Cnt_u16	5145
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	28188
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	5341
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	57338
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	61609
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	2360
k_IgnOnTimeout_mS_u16	7069
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	229.227203
k_PowerCutVehSpdLowThresh_Kph_f32	81.0787964
k_PowerCutVehSpdLowTimeout_mS_u16	41885
k_VBattMaxAAS_Volt_f32	27.3323994
k_VBattMaxBSI_Volt_f32	9.76850033
k_VBattMaxCAV_Volt_f32	14.0341997
k_VBattMaxCMM388_Volt_f32	9.7112999
k_VBattMaxCMM_Volt_f32	1.55840003
k_VBattMaxESP_Volt_f32	18.3516006
k_VBattMinAAS_Volt_f32	6.50360012
k_VBattMinBSI_Volt_f32	18.3516006
k_VBattMinCAV_Volt_f32	26.3281994
k_VBattMinCMM388_Volt_f32	7.70879984
k_VBattMinCMM_Volt_f32	21.2301998
k_VBattMinESP_Volt_f32	1.55840003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	46941
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	28436
k_VitesseVehicleBVRampValidThresh_Cnt_u16	5687
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	52309
k_VitesseVehicleBVSigValidThresh_Cnt_u16	31164
k_VitesseVehicleBVSpeedPassThresh_kph_f32	288.441101
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	390
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	51985
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3669842688
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8524
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1236548
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	30
target_SrlComInput_Per1_Batt_Volt_f32.value	28.6161003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2410220288
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	57
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0227154754
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	103
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1425406720
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	145
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1640209152
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	312556288
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	189
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2408504064
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	9206528
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2375686912
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	243
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1589099264
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	49
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	72
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	73
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	96
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	123
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	155
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1574689536
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	80
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	81
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	106
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	191
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	225
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3449617152
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	250
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2884279040
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	102
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3997711104
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	20
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	32
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	91
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	108
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	109
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	133
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	422480640
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1159
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.597972393
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	82287
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	137.1884
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	34405

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1236548	1236548	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1236548	1236548	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1236548	1236548	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1236548	1236548	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CDD_SrlComVehSpd_Kph_G_f32	300.622986	300.622986	✔
CMM388NTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	49078	49078	✔
CONSANGLECPK_HwDeg_M_f32	175.009201	175.009201 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1236548	1236548	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1236548	1236548	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1236548	1236548	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1236548	1236548	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1236548	1236548	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1236548	1236548	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1236548	1236548	✔
ESPNTCEnableTimer_mS_M_u32	1236548	1236548	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	5	5	✔
EffacDefaultDiagTimer_mS_M_u32[1]	155	155	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2500	2500	✔
ElecIntTimer_mS_M_u32[1]	3504	3504	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1236548	1236548	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	18426	18426	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	17757	17757	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	38318	38318	✔
ISDATBSI412MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	59	59	✔
ISDATBSI432MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1170	1170	✔
ISDATDIRASentTimer_mS_M_u32	1236548	1236548	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	35492	35492	✔
ISDYN2CMMMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	43632	43632	✔
ISDYNAASMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	49078	49078	✔
ISDYNABRMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	17757	17757	✔
ISDYNCMM208MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	60969	60969	✔
ISDYNCMM388MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	10748	10748	✔
ISDYNVOLMsgTimer_mS_M_u32	1236548	1236548	✔
IgnOnTimer_mS_M_u32	1802763008	1802763008	✔
IgnTimeOff_Sec_M_u32	2050200102	2050200102	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	103	103	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1425406720	1425406720	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	145	145	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1640209152	1640209152	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	75	75	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	312556288	312556288	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	189	189	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2408504064	2408504064	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2542418688	2542418688	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	105	105	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2375686912	2375686912	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	243	243	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1589099264	1589099264	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	155	155	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1574689536	1574689536	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	223	223	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3449617152	3449617152	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	250	250	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2884279040	2884279040	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	102	102	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3997711104	3997711104	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	422480640	422480640	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	324.707092	324.707092	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	465.524902	465.524902	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	570.780823	570.780823	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	49078	49078	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2050200102	2050200102	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	175.009201	175.009201 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	300.622986	300.622986	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.406 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2290057728
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	38726
AASNodeAbsentTimer_mS_M_u32	883716608
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	63074
ANGLEVOLANTSigValidCount_Cnt_M_u16	18472
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	18275
AngleVolantMsgTimer_mS_M_u32	2290057728
AngleVolantValidCount_Cnt_M_u16	28800
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3080991232
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1855107584
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2127962624
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	391963136
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	46377
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3226378752
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	46584
CAVNodeAbsentTimer_mS_M_u32	2182550016
CDD_SrlComVehSpd_Kph_G_f32	599.751221
CMM388NTCEnableTimer_mS_M_u32	2452312576
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3236762112
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	58709
CMMNodeAbsentTimer_mS_M_u32	520544768
CONSANGLECPKSigInvalidCount_Cnt_M_u16	7078
CONSANGLECPKSigValidCount_Cnt_M_u16	60604
CONSANGLECPK_Cnt_M_u16	58279
CONSANGLECPK_HwDeg_M_f32	131.202301
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	58279
CPKVehicleSpeedMsgTimer_mS_M_u32	2893971968
CPKVehicleSpeedValidCount_Cnt_M_u16	29272
CityParkInputConsistentCount_Cnt_M_u16	65380
CityParkInputInvalidCount_Cnt_M_u16	17209
CityParkInputMsgTimer_mS_M_u32	1425406720
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2089841152
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	15402

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	968331776
ComputerRazGCTSigValidCount_Cnt_M_u16	26169
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	36949
DMDFCTCPKSigValidCount_Cnt_M_u16	44163
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	21716
DMDRELAXECPKSigValidCount_Cnt_M_u16	63514
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	17603
DateInvalidTimer_mS_M_u32	1855107584
DiagMuxOnAbsentTimer_mS_M_u32	1481720320
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	391963136
ESPNTCEnableTimer_mS_M_u32	141390336
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	22167
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	579
EffacDefaultDiagTimer_mS_M_u32[1]	990
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	19
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	287351296
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	15166
EtatMTSigValidCount_Cnt_M_u16	9457
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	20504
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	62126
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	42329
ISDAT4V2BSI552MsgTimer_mS_M_u32	1240130048
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	48659
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	3854
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	9457
ISDATBSI3F2MsgTimer_mS_M_u32	1004487168
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	54706
ISDATBSI412MsgLenValidCount_Cnt_M_u16	60636
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	15166
ISDATBSI412MsgTimer_mS_M_u32	1913487872
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	13113
ISDATBSI432MsgLenValidCount_Cnt_M_u16	1915
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	20697
ISDATDIRASentFltAcc_Cnt_M_u16	37325
ISDATDIRASentTimer_mS_M_u32	2893971968
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	62901
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	28800
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	34972
ISDYN2CMMMsgTimer_mS_M_u32	1016558080
ISDYNAASChkSumInvalidCount_Cnt_M_u16	440
ISDYNAASChkSumValidCount_Cnt_M_u16	61598
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	28359
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	61731
ISDYNAASMsgLenValidCount_Cnt_M_u16	22402
ISDYNAASMsgTimeValidCount_Cnt_M_u16	440
ISDYNAASMsgTimer_mS_M_u32	2756137472
ISDYNABRChkSumInvalidCount_Cnt_M_u16	48063
ISDYNABRChkSumValidCount_Cnt_M_u16	51918
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	53887
ISDYNABRMsgCountValidCount_Cnt_M_u16	39077
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	61293
ISDYNABRMsgLenValidCount_Cnt_M_u16	55235
ISDYNABRMsgTimeValidCount_Cnt_M_u16	58279
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	54528
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	6575
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	9457
ISDYNCMM208MsgTimer_mS_M_u32	1387868672
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	54528
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	6575
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	24846

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1493881344
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	46900
ISDYNVOLChkSumValidCount_Cnt_M_u16	46794
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	28387
ISDYNVOLMsgCountValidCount_Cnt_M_u16	63889
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	38096
ISDYNVOLMsgLenValidCount_Cnt_M_u16	10439
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	58709
ISDYNVOLMsgTimer_mS_M_u32	4157837824
IgnOnTimer_mS_M_u32	1592709632
IgnTimeOff_Sec_M_u32	2677477383
ManVehSpd_Kph_M_f32	336.567596
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	18
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	153
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1586840064
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	58
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	847061504
PrevISDATBSI412MsgDLCError_Cnt_M_u08	149
PrevISDATBSI412MsgRxTime_MSec_M_u32	867701248
PrevISDATBSI432MsgDLCError_Cnt_M_u08	179
PrevISDATBSI432MsgRxTime_MSec_M_u32	63009280
PrevISDATDIRAMsgTxTime_MSec_M_u32	61608448
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	107
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1599234560
PrevISDYNAASMsgDLCError_Cnt_M_u08	88
PrevISDYNAASMsgRxTime_MSec_M_u32	1373737472
PrevISDYNABRMsgDLCError_Cnt_M_u08	81
PrevISDYNABRMsgRxTime_MSec_M_u32	1445384704
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	175
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1517720064
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	9
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2007790080
PrevISDYNVOLMsgDLCError_Cnt_M_u08	106
PrevISDYNVOLMsgRxTime_MSec_M_u32	3492090368
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	781943296
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	488.009399
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	54705
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	10896
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	59754
VitesseVehicleBVRampValidCount_Cnt_M_u16	50953
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	11163
VitesseVehicleBVSigValidCount_Cnt_M_u16	9761
VitesseVehicleBV_Kph_M_f32	483.460114
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	24846
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	6732
VitesseVehiculeRoues_Kph_M_f32	207.431702
k_AASNTCEnableTimeout_mS_u16	64998
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	29411
k_AASNodeTimeout_mS_u16	60816
k_ABSNodeTimeout_mS_u16	20266
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	46812
k_ANGLEVOLANTSigValidThresh_Cnt_u16	3934
k_AngleVolantInvalidThresh_Cnt_u16	6125
k_AngleVolantValidThresh_Cnt_u16	17209
k_BSI552MsgTimeout_mS_u16	48027
k_BSINTCEnableTimeout_mS_u16	39537
k_BSINodeAbsentDiag_Cnt_str.Threshold	51817
k_BSINodeAbsentDiag_Cnt_str.PStep	30839
k_BSINodeAbsentDiag_Cnt_str.NStep	44488
k_BSINodeAbsentTimeout_mS_u16	41115
k_BSINodeTimeout_mS_u16	20697
k_BattOvHi_Volt_f32	15.3575001
k_BattOvLo_Volt_f32	24.1413994
k_BattUvHi_Volt_f32	26.3822002
k_BattUvLo_Volt_f32	28.2360992
k_CAVNTCEnableTimeout_mS_u16	7935
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	54662
k_CAVNodeTimeout_mS_u16	9666
k_CMM388MsgTimeout_mS_u16	39494
k_CMM388NTCEnableTimeout_mS_u16	13666
k_CMMNTCEnableTimeout_mS_u16	33099
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	2920
k_CONSANGLECPKMax_HwDeg_f32	176.432999
k_CONSANGLECPKMin_HwDeg_f32	-34.1383018
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	58382
k_CONSANGLECPKSigValidThresh_Cnt_u16	56652
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	0
k_CPKVehicleSpeedValidThresh_Cnt_u16	5789
k_CityParkInputInvalidThresh_Cnt_u16	27669
k_CityParkInputValidThresh_Cnt_u16	65380
k_ComputerRazGCTSigValidThresh_Cnt_u16	60233
k_CptTemporelSigValidThresh_Cnt_u16	55492
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	62061
k_DMDFCTCPKSigValidThresh_Cnt_u16	6851
k_DMDFCTCPKValidCount_Cnt_u16	28401
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	34972
k_DMDRELAXECPKSigValidThresh_Cnt_u16	7178
k_DMDRelaxeConsistentThresh_Cnt_u16	39392
k_DateValidThresh_Cnt_u16	42329
k_DefaultVehSpd_Kph_f32	132.5728
k_DiagMuxOnAbsentTimeout_mS_u16	41197
k_EMNodeTimeout_mS_u16	41507
k_ESPNTCEnableTimeout_mS_u16	16916
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	11312
k_EtatMTSigInvalidThresh_Cnt_u16	16942
k_EtatMTSigValidThresh_Cnt_u16	38525
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	61489
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	25283
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	50461
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	60752
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	8715
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	27030
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	39926
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	29688
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	49437
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	54507
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	27702
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	1140
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	33755
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	45193
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	18275
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	25536
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	16063
k_ISDYNAASChkSumValidThresh_Cnt_u16	36302
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	54655
k_ISDYNAASMsgCountValidThresh_Cnt_u16	56229
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	46755
k_ISDYNAASMsgLenValidThresh_Cnt_u16	21620
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	3622
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	30203
k_ISDYNABRChkSumValidThresh_Cnt_u16	52433
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	47145
k_ISDYNABRMsgCountValidThresh_Cnt_u16	41263
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	43093
k_ISDYNABRMsgLenValidThresh_Cnt_u16	22935
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	51198
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	56469
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	19627
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	30175
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	63842
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	35624
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	41073
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	4565
k_ISDYNVOLChkSumValidThresh_Cnt_u16	3391
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	5556
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	59570
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	35930
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	21261
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	55711
k_IgnOnTimeout_mS_u16	52721
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	6.3604002
k_PowerCutVehSpdLowThresh_Kph_f32	170.805695
k_PowerCutVehSpdLowTimeout_mS_u16	37874
k_VBattMaxAAS_Volt_f32	30.3498993
k_VBattMaxBSI_Volt_f32	29.9967995
k_VBattMaxCAV_Volt_f32	25.6110001
k_VBattMaxCMM388_Volt_f32	14.4095001
k_VBattMaxCMM_Volt_f32	9.83230019
k_VBattMaxESP_Volt_f32	5.56869984
k_VBattMinAAS_Volt_f32	23.8393993
k_VBattMinBSI_Volt_f32	5.56869984
k_VBattMinCAV_Volt_f32	12.5443001
k_VBattMinCMM388_Volt_f32	23.6074009
k_VBattMinCMM_Volt_f32	5.56960011
k_VBattMinESP_Volt_f32	9.83230019
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	1971
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	63821
k_VitesseVehicleBVRampValidThresh_Cnt_u16	61923
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	63946
k_VitesseVehicleBVSigValidThresh_Cnt_u16	51797
k_VitesseVehicleBVSpeedPassThresh_kph_f32	389.77829
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	14584
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	17687
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1855107584
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	33485
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	163190528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	9
target_SrlComInput_Per1_Batt_Volt_f32.value	27.7194004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3666846208
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	131
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.212173641
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	171
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	711512576
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	204
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3263164928
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2925990400
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1981690368
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2711966208
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3103552000
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	127
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1143181824
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	36
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	150
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	162
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	32
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2134323712
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	48
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	170
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	234
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	159
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	477352448
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	236
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1074459136
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2003964416
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	118
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	872358400
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1386
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.57663548
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	248009
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	70.726799
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	58971

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	163190528	163190528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	163190528	163190528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	18275	18275	✔
AngleVolantMsgTimer_mS_M_u32	163190528	163190528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	163190528	163190528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	58279	58279	✔
CONSANGLECPK_HwDeg_M_f32	131.202301	131.202301 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	58279	58279	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2893971968	2893971968	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	29272	29272	✔
CityParkInputConsistentCount_Cnt_M_u16	65380	65380	✔
CityParkInputInvalidCount_Cnt_M_u16	17211	17211	✔
CityParkInputMsgTimer_mS_M_u32	163190528	163190528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	163190528	163190528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	163190528	163190528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	163190528	163190528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	163190528	163190528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	163190528	163190528	✔
ESPNTCEnableTimer_mS_M_u32	163190528	163190528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	163190528	163190528	✔
EffacDefaultDiagTimer_mS_M_u32[1]	990	990	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	163190528	163190528	✔
ElecIntTimer_mS_M_u32[1]	19	19	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	163190528	163190528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11170	11170	✔
ISDATDIRASentTimer_mS_M_u32	163190528	163190528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	163190528	163190528	✔
IgnOnTimer_mS_M_u32	1592709632	1592709632	✔
IgnTimeOff_Sec_M_u32	2677477383	2677477383	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	171	171	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	711512576	711512576	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	204	204	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3263164928	3263164928	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	125	125	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2925990400	2925990400	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1981690368	1981690368	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	61608448	61608448	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	63	63	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3103552000	3103552000	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	127	127	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1143181824	1143181824	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	32	32	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2134323712	2134323712	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	159	159	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	477352448	477352448	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	236	236	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1074459136	1074459136	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	136	136	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2003964416	2003964416	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	872358400	872358400	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	488.009399	488.009399	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	483.460114	483.460114	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	207.431702	207.431702	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	58279	58279	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2677477383	2677477383	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	131.202301	131.202301 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.407 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2192063744
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	36948
AASNodeAbsentTimer_mS_M_u32	2648796416
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	34047
ANGLEVOLANTSigValidCount_Cnt_M_u16	62827
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	13309
AngleVolantMsgTimer_mS_M_u32	2192063744
AngleVolantValidCount_Cnt_M_u16	5414
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2751081728
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1496231168
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3257163008
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2207259904
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	9386
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2142952704
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	50876
CAVNodeAbsentTimer_mS_M_u32	673287424
CDD_SrlComVehSpd_Kph_G_f32	273.348694
CMM388NTCEnableTimer_mS_M_u32	2565131520
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1134529792
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	51046
CMMNodeAbsentTimer_mS_M_u32	2492603648
CONSANGLECPKSigInvalidCount_Cnt_M_u16	54323
CONSANGLECPKSigValidCount_Cnt_M_u16	1712
CONSANGLECPK_Cnt_M_u16	36335
CONSANGLECPK_HwDeg_M_f32	190.118103
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	36335
CPKVehicleSpeedMsgTimer_mS_M_u32	3534437632
CPKVehicleSpeedValidCount_Cnt_M_u16	18243

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	63610
CityParkInputInvalidCount_Cnt_M_u16	4602
CityParkInputMsgTimer_mS_M_u32	711512576
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1446341888
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	12712
ComputerRazGCTSigInvalidTimer_mS_M_u32	591400192
ComputerRazGCTSigValidCount_Cnt_M_u16	22523
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	39590
DMDFCTCPKSigValidCount_Cnt_M_u16	19419
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	45481
DMDRELAXECPKSigValidCount_Cnt_M_u16	11669
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	3292
DateInvalidTimer_mS_M_u32	1496231168
DiagMuxOnAbsentTimer_mS_M_u32	2318597376
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2207259904
ESPNTCEnableTimer_mS_M_u32	1721658624
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	51551
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1000
EffacDefaultDiagTimer_mS_M_u32[1]	2001
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	88
ElecIntTimer_mS_M_u32[1]	111
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1430576384
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	64171
EtatMTSigValidCount_Cnt_M_u16	21331
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	32477
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	15578
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	14681
ISDAT4V2BSI552MsgTimer_mS_M_u32	2749766912
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	65450
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	17019
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	21331
ISDATBSI3F2MsgTimer_mS_M_u32	2542337280
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	464
ISDATBSI412MsgLenValidCount_Cnt_M_u16	45584
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	64171
ISDATBSI412MsgTimer_mS_M_u32	2113813760
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	28090
ISDATBSI432MsgLenValidCount_Cnt_M_u16	18099
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	47641
ISDATDIRASentFltAcc_Cnt_M_u16	51005
ISDATDIRASentTimer_mS_M_u32	3534437632
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	4037
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	5414
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36305
ISDYN2CMMMsgTimer_mS_M_u32	4062211328
ISDYNAASChkSumInvalidCount_Cnt_M_u16	39166
ISDYNAASChkSumValidCount_Cnt_M_u16	45579
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	63057
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	33083
ISDYNAASMsgLenValidCount_Cnt_M_u16	5088
ISDYNAASMsgTimeValidCount_Cnt_M_u16	39166
ISDYNAASMsgTimer_mS_M_u32	3532705024
ISDYNABRChkSumInvalidCount_Cnt_M_u16	57959
ISDYNABRChkSumValidCount_Cnt_M_u16	15099
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	681
ISDYNABRMsgCountValidCount_Cnt_M_u16	38390
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	13534
ISDYNABRMsgLenValidCount_Cnt_M_u16	8603
ISDYNABRMsgTimeValidCount_Cnt_M_u16	36335

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	46871
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	40397
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	21331
ISDYNCMM208MsgTimer_mS_M_u32	1723542784
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	46871
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	40397
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	64380
ISDYNCMM388MsgTimer_mS_M_u32	575032576
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	47497
ISDYNVOLChkSumValidCount_Cnt_M_u16	24710
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	46844
ISDYNVOLMsgCountValidCount_Cnt_M_u16	7345
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	12980
ISDYNVOLMsgLenValidCount_Cnt_M_u16	40081
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	51046
ISDYNVOLMsgTimer_mS_M_u32	1491864832
IgnOnTimer_mS_M_u32	2694466816
IgnTimeOff_Sec_M_u32	2526435687
ManVehSpd_Kph_M_f32	282.854706
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	19
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	20
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2271673600
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	249
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	53435648
PrevISDATBSI412MsgDLCError_Cnt_M_u08	245
PrevISDATBSI412MsgRxTime_MSec_M_u32	3611200768
PrevISDATBSI432MsgDLCError_Cnt_M_u08	234
PrevISDATBSI432MsgRxTime_MSec_M_u32	3298979072
PrevISDATDIRAMsgTxTime_MSec_M_u32	929205504
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	12
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1638898944
PrevISDYNAASMsgDLCError_Cnt_M_u08	2
PrevISDYNAASMsgRxTime_MSec_M_u32	46271744
PrevISDYNABRMsgDLCError_Cnt_M_u08	242
PrevISDYNABRMsgRxTime_MSec_M_u32	2599570688
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	119
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2097351936
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	79
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3571543296
PrevISDYNVOLMsgDLCError_Cnt_M_u08	223
PrevISDYNVOLMsgRxTime_MSec_M_u32	4126641408
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	5520640
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	470.127502
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	35729
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	21174
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	29798
VitesseVehicleBVRampValidCount_Cnt_M_u16	41291
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	2388

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	32640
VitesseVehicleBV_Kph_M_f32	542.743408
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	64380
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	5505
VitesseVehiculeRoues_Kph_M_f32	595.27063
k_AASNTCEnableTimeout_mS_u16	64306
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	23037
k_AASNodeTimeout_mS_u16	2486
k_ABSNodeTimeout_mS_u16	61991
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	11985
k_ANGLEVOLANTSigValidThresh_Cnt_u16	31498
k_AngleVolantInvalidThresh_Cnt_u16	23901
k_AngleVolantValidThresh_Cnt_u16	4602
k_BSI552MsgTimeout_mS_u16	11668
k_BSINTCEnableTimeout_mS_u16	6162
k_BSINodeAbsentDiag_Cnt_str.Threshold	28766
k_BSINodeAbsentDiag_Cnt_str.PStep	41333
k_BSINodeAbsentDiag_Cnt_str.NStep	19647
k_BSINodeAbsentTimeout_mS_u16	2133
k_BSINodeTimeout_mS_u16	47641
k_BattOvHi_Volt_f32	11.2342997
k_BattOvLo_Volt_f32	13.1612997
k_BattUvHi_Volt_f32	3.10660005
k_BattUvLo_Volt_f32	20.6184998
k_CAVNTCEnableTimeout_mS_u16	5800
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	8210
k_CAVNodeTimeout_mS_u16	9695
k_CMM388MsgTimeout_mS_u16	34644
k_CMM388NTCEnableTimeout_mS_u16	9728
k_CMMNTCEnableTimeout_mS_u16	38402
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	45613
k_CONSANGLECPKMax_HwDeg_f32	502.327087
k_CONSANGLECPKMin_HwDeg_f32	-504.042206
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	29308
k_CONSANGLECPKSigValidThresh_Cnt_u16	52353
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	65535
k_CPKVehicleSpeedValidThresh_Cnt_u16	43791
k_CityParkInputInvalidThresh_Cnt_u16	43365
k_CityParkInputValidThresh_Cnt_u16	63610
k_ComputerRazGCTSigValidThresh_Cnt_u16	53256
k_CptTemporelSigValidThresh_Cnt_u16	15705
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	11230
k_DMDFCTCPKSigValidThresh_Cnt_u16	22683
k_DMDFCTCPKValidCount_Cnt_u16	5970
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	36305
k_DMDRELAXECPKSigValidThresh_Cnt_u16	55622
k_DMDRelaxeConsistentThresh_Cnt_u16	14276
k_DateValidThresh_Cnt_u16	14681
k_DefaultVehSpd_Kph_f32	66.9330978
k_DiagMuxOnAbsentTimeout_mS_u16	60957
k_EMNodeTimeout_mS_u16	29884
k_ESPNTCEnableTimeout_mS_u16	37480
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	28629
k_EtatMTSigInvalidThresh_Cnt_u16	51994
k_EtatMTSigValidThresh_Cnt_u16	21486
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	50643
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	988
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	52047
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	42483
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	15748
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	54820

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	26499
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	13628
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	21518
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	51747
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	31236
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	20105
k_ISDATDIRASentDiag_Cnt_str.Threshold	24699
k_ISDATDIRASentDiag_Cnt_str.PStep	10108
k_ISDATDIRASentDiag_Cnt_str.NStep	32066
k_ISDATDIRASentTimeout_mS_u16	64019
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	56906
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	13309
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	56676
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	22887
k_ISDYNAASChkSumValidThresh_Cnt_u16	61947
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	63913
k_ISDYNAASMsgCountValidThresh_Cnt_u16	52470
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	33211
k_ISDYNAASMsgLenValidThresh_Cnt_u16	25866
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	40626
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	22836
k_ISDYNABRChkSumValidThresh_Cnt_u16	64113
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	7082
k_ISDYNABRMsgCountValidThresh_Cnt_u16	50774
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	32358
k_ISDYNABRMsgLenValidThresh_Cnt_u16	49247
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	19945
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	1765
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	49381
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	27849
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	31743
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	11371
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	55890
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	39271
k_ISDYNVOLChkSumValidThresh_Cnt_u16	40167
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	16392
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	29007
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	30551
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	14591
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	13447
k_IgnOnTimeout_mS_u16	54547
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	108.070297
k_PowerCutVehSpdLowThresh_Kph_f32	198.734299
k_PowerCutVehSpdLowTimeout_mS_u16	26894
k_VBattMaxAAS_Volt_f32	21.6982002
k_VBattMaxBSI_Volt_f32	16.8924999
k_VBattMaxCAV_Volt_f32	4.81650019
k_VBattMaxCMM388_Volt_f32	11.9306002
k_VBattMaxCMM_Volt_f32	13.7706003
k_VBattMaxESP_Volt_f32	20.2129002
k_VBattMinAAS_Volt_f32	17.2210999
k_VBattMinBSI_Volt_f32	20.2129002
k_VBattMinCAV_Volt_f32	5.57019997
k_VBattMinCMM388_Volt_f32	7.76569986
k_VBattMinCMM_Volt_f32	27.3001003
k_VBattMinESP_Volt_f32	13.7706003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	204
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	57789
k_VitesseVehicleBVRampValidThresh_Cnt_u16	11772
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	38790
k_VitesseVehicleBVSigValidThresh_Cnt_u16	39847
k_VitesseVehicleBVSpeedPassThresh_kph_f32	73.2279968
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	15804
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	57121
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1496231168
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	13090
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	79
target_SrlComInput_Per1_Batt_Volt_f32.value	12.2981997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1962401024
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	133
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.500284195
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	249
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2787921152
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2724654336
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	11
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3811675392
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	85
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3498847488
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3531001088
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	115
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1357999360
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	23
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3019640064
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	191
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	207
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	227
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1497443584
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	74
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	100
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	107
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	123
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	131
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	224
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3154857216
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	70
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	365292800
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	213
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1947241728
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	9
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	57
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	176
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2259246336
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3949
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.248256505
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	506838
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	38.2209015
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	33171

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	282.854706	282.854706	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	36335	36335	✔
CONSANGLECPK_HwDeg_M_f32	190.118103	190.118103 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3251510528	3251510528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	1000	1000	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2001	2001	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	88	88	✔
ElecIntTimer_mS_M_u32[1]	111	111	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	14681	14681	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	21331	21331	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	64171	64171	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	47641	47641	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	24699	24699	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36305	36305	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	39166	39166	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	36335	36335	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	21331	21331	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	64380	64380	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	51046	51046	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	2694466816	2694466816	✔
IgnTimeOff_Sec_M_u32	2526435687	2526435687	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	249	249	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2787921152	2787921152	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	186	186	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2724654336	2724654336	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	11	11	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3811675392	3811675392	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	85	85	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3498847488	3498847488	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	929205504	929205504	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	115	115	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1357999360	1357999360	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	23	23	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3019640064	3019640064	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	108	108	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1497443584	1497443584	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	8	8	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3154857216	3154857216	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	70	70	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	365292800	365292800	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	213	213	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1947241728	1947241728	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2259246336	2259246336	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	470.127502	470.127502	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	542.743408	542.743408	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	595.27063	595.27063	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	36335	36335	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2526435687	2526435687	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	190.118103	190.118103 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	282.854706	282.854706	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.408 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	886705152
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	24020
AASNodeAbsentTimer_mS_M_u32	2213444608
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	18901
ANGLEVOLANTSigValidCount_Cnt_M_u16	51022
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	22233
AngleVolantMsgTimer_mS_M_u32	886705152
AngleVolantValidCount_Cnt_M_u16	40415
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3299097600
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	386317312
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	249932800
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	698510336
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	54996
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1344416768
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	796
CAVNodeAbsentTimer_mS_M_u32	2376997888
CDD_SrlComVehSpd_Kph_G_f32	226.183807
CMM388NTCEnableTimer_mS_M_u32	1482972160
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3006536704
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	21726
CMMNodeAbsentTimer_mS_M_u32	2124180480
CONSANGLECPKSigInvalidCount_Cnt_M_u16	7990
CONSANGLECPKSigValidCount_Cnt_M_u16	38528
CONSANGLECPK_Cnt_M_u16	48323
CONSANGLECPK_HwDeg_M_f32	-647.17688
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	48323
CPKVehicleSpeedMsgTimer_mS_M_u32	282135552
CPKVehicleSpeedValidCount_Cnt_M_u16	142
CityParkInputConsistentCount_Cnt_M_u16	17379
CityParkInputInvalidCount_Cnt_M_u16	18530
CityParkInputMsgTimer_mS_M_u32	2787921152
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2868018176
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	51672

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	911383552
ComputerRazGCTSigValidCount_Cnt_M_u16	26976
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	24158
DMDFCTCPKSigValidCount_Cnt_M_u16	14720
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	60375
DMDRELAXECPKSigValidCount_Cnt_M_u16	18128
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	22843
DateInvalidTimer_mS_M_u32	386317312
DiagMuxOnAbsentTimer_mS_M_u32	3107572736
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	698510336
ESPNTCEnableTimer_mS_M_u32	1572305920
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	19892
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	2500
EffacDefaultDiagTimer_mS_M_u32[1]	3501
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1
ElecIntTimer_mS_M_u32[1]	14
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2005150720
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	7185
EtatMTSigValidCount_Cnt_M_u16	53463
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	18232
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	7170
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	59654
ISDAT4V2BSI552MsgTimer_mS_M_u32	2694867968
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	25745
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	64223
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	53463
ISDATBSI3F2MsgTimer_mS_M_u32	1765264384
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	33570
ISDATBSI412MsgLenValidCount_Cnt_M_u16	37152
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	7185
ISDATBSI412MsgTimer_mS_M_u32	450366464
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	45538
ISDATBSI432MsgLenValidCount_Cnt_M_u16	9656
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	56581
ISDATDIRASentFltAcc_Cnt_M_u16	17817
ISDATDIRASentTimer_mS_M_u32	282135552
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	3905
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	40415
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	61661
ISDYN2CMMMsgTimer_mS_M_u32	1127316480
ISDYNAASChkSumInvalidCount_Cnt_M_u16	27606
ISDYNAASChkSumValidCount_Cnt_M_u16	28528
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	26206
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	36767
ISDYNAASMsgLenValidCount_Cnt_M_u16	34417
ISDYNAASMsgTimeValidCount_Cnt_M_u16	27606
ISDYNAASMsgTimer_mS_M_u32	1533041664
ISDYNABRChkSumInvalidCount_Cnt_M_u16	10525
ISDYNABRChkSumValidCount_Cnt_M_u16	36383
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	39637
ISDYNABRMsgCountValidCount_Cnt_M_u16	12207
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	26933
ISDYNABRMsgLenValidCount_Cnt_M_u16	45503
ISDYNABRMsgTimeValidCount_Cnt_M_u16	48323
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	6574
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	18254
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	53463
ISDYNCMM208MsgTimer_mS_M_u32	3227597824
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	6574
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	18254
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	49885

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	574610432
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	18228
ISDYNVOLChkSumValidCount_Cnt_M_u16	24830
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	57692
ISDYNVOLMsgCountValidCount_Cnt_M_u16	40702
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	42421
ISDYNVOLMsgLenValidCount_Cnt_M_u16	63199
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	21726
ISDYNVOLMsgTimer_mS_M_u32	1162779648
IgnOnTimer_mS_M_u32	4148419584
IgnTimeOff_Sec_M_u32	2365823328
ManVehSpd_Kph_M_f32	568.779724
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	20
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	42
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2443037696
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	41
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	935635968
PrevISDATBSI412MsgDLCError_Cnt_M_u08	13
PrevISDATBSI412MsgRxTime_MSec_M_u32	878124032
PrevISDATBSI432MsgDLCError_Cnt_M_u08	69
PrevISDATBSI432MsgRxTime_MSec_M_u32	1403747328
PrevISDATDIRAMsgTxTime_MSec_M_u32	2750094336
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	0
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1833167872
PrevISDYNAASMsgDLCError_Cnt_M_u08	227
PrevISDYNAASMsgRxTime_MSec_M_u32	533502976
PrevISDYNABRMsgDLCError_Cnt_M_u08	138
PrevISDYNABRMsgRxTime_MSec_M_u32	1748753408
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	26
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4111047680
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	220
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3740171264
PrevISDYNVOLMsgDLCError_Cnt_M_u08	18
PrevISDYNVOLMsgRxTime_MSec_M_u32	4230749184
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1809189888
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	51.1875
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	18589
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	41455
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	8734
VitesseVehicleBVRampValidCount_Cnt_M_u16	18992
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	20694
VitesseVehicleBVSigValidCount_Cnt_M_u16	48399
VitesseVehicleBV_Kph_M_f32	312.775604
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	49885
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	41871
VitesseVehiculeRoues_Kph_M_f32	512.848083
k_AASNTCEnableTimeout_mS_u16	16634
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	60250
k_AASNodeTimeout_mS_u16	31983
k_ABSNodeTimeout_mS_u16	39899
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	35485
k_ANGLEVOLANTSigValidThresh_Cnt_u16	42163
k_AngleVolantInvalidThresh_Cnt_u16	2490
k_AngleVolantValidThresh_Cnt_u16	18530
k_BSI552MsgTimeout_mS_u16	26454
k_BSINTCEnableTimeout_mS_u16	4826
k_BSINodeAbsentDiag_Cnt_str.Threshold	8538
k_BSINodeAbsentDiag_Cnt_str.PStep	56406
k_BSINodeAbsentDiag_Cnt_str.NStep	63670
k_BSINodeAbsentTimeout_mS_u16	14801
k_BSINodeTimeout_mS_u16	56581
k_BattOvHi_Volt_f32	24.0702
k_BattOvLo_Volt_f32	30.9524994
k_BattUvHi_Volt_f32	6.11429977
k_BattUvLo_Volt_f32	14.3572998
k_CAVNTCEnableTimeout_mS_u16	29272
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	53018
k_CAVNodeTimeout_mS_u16	55858
k_CMM388MsgTimeout_mS_u16	30932
k_CMM388NTCEnableTimeout_mS_u16	19664
k_CMMNTCEnableTimeout_mS_u16	393
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	32139
k_CONSANGLECPKMax_HwDeg_f32	136.850693
k_CONSANGLECPKMin_HwDeg_f32	-504.792297
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	24029
k_CONSANGLECPKSigValidThresh_Cnt_u16	32399
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	60005
k_CPKVehicleSpeedValidThresh_Cnt_u16	17253
k_CityParkInputInvalidThresh_Cnt_u16	19491
k_CityParkInputValidThresh_Cnt_u16	17379
k_ComputerRazGCTSigValidThresh_Cnt_u16	60279
k_CptTemporelSigValidThresh_Cnt_u16	581
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	33845
k_DMDFCTCPKSigValidThresh_Cnt_u16	3263
k_DMDFCTCPKValidCount_Cnt_u16	40668
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	61661
k_DMDRELAXECPKSigValidThresh_Cnt_u16	64831
k_DMDRelaxeConsistentThresh_Cnt_u16	22981
k_DateValidThresh_Cnt_u16	59654
k_DefaultVehSpd_Kph_f32	214.524094
k_DiagMuxOnAbsentTimeout_mS_u16	54329
k_EMNodeTimeout_mS_u16	41371
k_ESPNTCEnableTimeout_mS_u16	20504
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	58515
k_EtatMTSigInvalidThresh_Cnt_u16	64260
k_EtatMTSigValidThresh_Cnt_u16	53062
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	64664
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	33086
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	24420
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	54710
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	28100
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	22054
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	10375
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	48669
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	20198
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	55335
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	26437
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	4598
k_ISDATDIRASentDiag_Cnt_str.Threshold	55184

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	37963
k_ISDATDIRASentDiag_Cnt_str.NStep	46267
k_ISDATDIRASentTimeout_mS_u16	37401
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	42675
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	22233
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	24356
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	50205
k_ISDYNAASChkSumValidThresh_Cnt_u16	26911
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	46549
k_ISDYNAASMsgCountValidThresh_Cnt_u16	35503
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	39713
k_ISDYNAASMsgLenValidThresh_Cnt_u16	47859
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	55739
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	54323
k_ISDYNABRChkSumValidThresh_Cnt_u16	65341
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	61908
k_ISDYNABRMsgCountValidThresh_Cnt_u16	49293
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	12254
k_ISDYNABRMsgLenValidThresh_Cnt_u16	26804
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	13780
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	9889
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	55779
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	24502
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	25813
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	8782
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	20314
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	55389
k_ISDYNVOLChkSumValidThresh_Cnt_u16	60571
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	52665
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	15139
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	22029
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	53203
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	12156
k_IgnOnTimeout_mS_u16	54617
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	79.6125031
k_PowerCutVehSpdLowThresh_Kph_f32	103.6203
k_PowerCutVehSpdLowTimeout_mS_u16	26470
k_VBattMaxAAS_Volt_f32	27.8883991
k_VBattMaxBSI_Volt_f32	26.9013004
k_VBattMaxCAV_Volt_f32	6.82940006
k_VBattMaxCMM388_Volt_f32	31.9578991
k_VBattMaxCMM_Volt_f32	29.1126003
k_VBattMaxESP_Volt_f32	28.8318005
k_VBattMinAAS_Volt_f32	14.3462
k_VBattMinBSI_Volt_f32	28.8318005
k_VBattMinCAV_Volt_f32	20.9074001
k_VBattMinCMM388_Volt_f32	7.16660023
k_VBattMinCMM_Volt_f32	19.3006001
k_VBattMinESP_Volt_f32	29.1126003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	50989
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	795
k_VitesseVehicleBVRampValidThresh_Cnt_u16	31836
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	48126
k_VitesseVehicleBVSigValidThresh_Cnt_u16	20060
k_VitesseVehicleBVSpeedPassThresh_kph_f32	34.9639015
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	40476
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	26798
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	386317312
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	220
target_SrlComInput_Per1_Batt_Volt_f32.value	30.8959999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2758487040
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	84
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.00255785603
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	52
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2928532480
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1818098688
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	97
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2625510400
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	149
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	116276224
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1940806656
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2864610304
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1948163072
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	37
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	73
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	88
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	158
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	185
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	187
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	225
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	102
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2161064960
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	126
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	140
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	176
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	222
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2834357248
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	25
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1312881664
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	635509760
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	74
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	137
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	156
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	194
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	358001664
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	374
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.33722207
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1033123
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	175.410599
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	61079

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	568.779724	568.779724	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	48323	48323	✔
CONSANGLECPK_HwDeg_M_f32	-647.17688	-647.17688 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3251510528	3251510528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2500	2500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3501	3501	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1	1	✔
ElecIntTimer_mS_M_u32[1]	14	14	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	59654	59654	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	53463	53463	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	7185	7185	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	56581	56581	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	55184	55184	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	61661	61661	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	27606	27606	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	48323	48323	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	53463	53463	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	49885	49885	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	21726	21726	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	4148419584	4148419584	✔
IgnTimeOff_Sec_M_u32	2365823328	2365823328	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	52	52	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2928532480	2928532480	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	131	131	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1818098688	1818098688	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	97	97	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2625510400	2625510400	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	149	149	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	116276224	116276224	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2750094336	2750094336	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2864610304	2864610304	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	8	8	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1948163072	1948163072	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	102	102	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2161064960	2161064960	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2834357248	2834357248	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	25	25	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1312881664	1312881664	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	63	63	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	635509760	635509760	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	358001664	358001664	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	51.1875	51.1875	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	312.775604	312.775604	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	512.848083	512.848083	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	48323	48323	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2365823328	2365823328	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-647.17688	-647.17688 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	568.779724	568.779724	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.409 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3963657984
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	31569
AASNodeAbsentTimer_mS_M_u32	482561792
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	22863
ANGLEVOLANTSigValidCount_Cnt_M_u16	29857
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	58434
AngleVolantMsgTimer_mS_M_u32	3963657984
AngleVolantValidCount_Cnt_M_u16	20399
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1638010624
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	343576320
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2493366016
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	661094144
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	28242
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1659387648
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	45562
CAVNodeAbsentTimer_mS_M_u32	100953856
CDD_SrlComVehSpd_Kph_G_f32	616.32959
CMM388NTCEnableTimer_mS_M_u32	1323413248
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	762474240
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	49523
CMMNodeAbsentTimer_mS_M_u32	2423881472
CONSANGLECPKSigInvalidCount_Cnt_M_u16	36906
CONSANGLECPKSigValidCount_Cnt_M_u16	65036
CONSANGLECPK_Cnt_M_u16	22339
CONSANGLECPK_HwDeg_M_f32	236.538498
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	22339
CPKVehicleSpeedMsgTimer_mS_M_u32	4099645184
CPKVehicleSpeedValidCount_Cnt_M_u16	23690
CityParkInputConsistentCount_Cnt_M_u16	28067
CityParkInputInvalidCount_Cnt_M_u16	27941
CityParkInputMsgTimer_mS_M_u32	2928532480
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3082243840
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	18245

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1041690368
ComputerRazGCTSigValidCount_Cnt_M_u16	12588
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	6961
DMDFCTCPKSigValidCount_Cnt_M_u16	48524
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	64329
DMDRELAXECPKSigValidCount_Cnt_M_u16	32283
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	13851
DateInvalidTimer_mS_M_u32	343576320
DiagMuxOnAbsentTimer_mS_M_u32	2384551680
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	661094144
ESPNTCEnableTimer_mS_M_u32	4083699456
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	55985
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	579
EffacDefaultDiagTimer_mS_M_u32[1]	990
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	19
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4106370816
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	18649
EtatMTSigValidCount_Cnt_M_u16	61000
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	40996
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	62854
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	18170
ISDAT4V2BSI552MsgTimer_mS_M_u32	980254464
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	26840
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	35246
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	61000
ISDATBSI3F2MsgTimer_mS_M_u32	4129775360
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	40488
ISDATBSI412MsgLenValidCount_Cnt_M_u16	6126
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	18649
ISDATBSI412MsgTimer_mS_M_u32	2990972672
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	47719
ISDATBSI432MsgLenValidCount_Cnt_M_u16	25253
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	2111
ISDATDIRASentFltAcc_Cnt_M_u16	7811
ISDATDIRASentTimer_mS_M_u32	4099645184
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	55241
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	20399
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	8116
ISDYN2CMMMsgTimer_mS_M_u32	2868530944
ISDYNAASChkSumInvalidCount_Cnt_M_u16	55627
ISDYNAASChkSumValidCount_Cnt_M_u16	57917
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	45618
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	55409
ISDYNAASMsgLenValidCount_Cnt_M_u16	59323
ISDYNAASMsgTimeValidCount_Cnt_M_u16	55627
ISDYNAASMsgTimer_mS_M_u32	904769280
ISDYNABRChkSumInvalidCount_Cnt_M_u16	54518
ISDYNABRChkSumValidCount_Cnt_M_u16	22960
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	2126
ISDYNABRMsgCountValidCount_Cnt_M_u16	23936
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	28205
ISDYNABRMsgLenValidCount_Cnt_M_u16	26703
ISDYNABRMsgTimeValidCount_Cnt_M_u16	22339
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	54528
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	6575
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	61000
ISDYNCMM208MsgTimer_mS_M_u32	2724925184
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	54528
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	6575
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	22709

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3209637632
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	36912
ISDYNVOLChkSumValidCount_Cnt_M_u16	5778
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	2615
ISDYNVOLMsgCountValidCount_Cnt_M_u16	1298
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	5806
ISDYNVOLMsgLenValidCount_Cnt_M_u16	30449
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	49523
ISDYNVOLMsgTimer_mS_M_u32	19066624
IgnOnTimer_mS_M_u32	1346580224
IgnTimeOff_Sec_M_u32	508381750
ManVehSpd_Kph_M_f32	444.219513
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	21
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2499108608
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	5
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1442889472
PrevISDATBSI412MsgDLCError_Cnt_M_u08	211
PrevISDATBSI412MsgRxTime_MSec_M_u32	4127813376
PrevISDATBSI432MsgDLCError_Cnt_M_u08	227
PrevISDATBSI432MsgRxTime_MSec_M_u32	3784068864
PrevISDATDIRAMsgTxTime_MSec_M_u32	4149047040
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	78
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3263364864
PrevISDYNAASMsgDLCError_Cnt_M_u08	84
PrevISDYNAASMsgRxTime_MSec_M_u32	3920162560
PrevISDYNABRMsgDLCError_Cnt_M_u08	253
PrevISDYNABRMsgRxTime_MSec_M_u32	3713740544
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	239
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2649878272
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	202
PrevISDYNCMM388MsgRxTime_MSec_M_u32	197349120
PrevISDYNVOLMsgDLCError_Cnt_M_u08	118
PrevISDYNVOLMsgRxTime_MSec_M_u32	847933184
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	927768320
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	551.638
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	9591
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	3393
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	56564
VitesseVehicleBVRampValidCount_Cnt_M_u16	22654
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	34892
VitesseVehicleBVSigValidCount_Cnt_M_u16	55134
VitesseVehicleBV_Kph_M_f32	297.586212
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	22709
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	10847
VitesseVehiculeRoues_Kph_M_f32	593.426575
k_AASNTCEnableTimeout_mS_u16	26270
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	4926
k_AASNodeTimeout_mS_u16	31809
k_ABSNodeTimeout_mS_u16	38586
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	56374
k_ANGLEVOLANTSigValidThresh_Cnt_u16	37300
k_AngleVolantInvalidThresh_Cnt_u16	16031
k_AngleVolantValidThresh_Cnt_u16	27941
k_BSI552MsgTimeout_mS_u16	47882
k_BSINTCEnableTimeout_mS_u16	30591
k_BSINodeAbsentDiag_Cnt_str.Threshold	51817
k_BSINodeAbsentDiag_Cnt_str.PStep	30839
k_BSINodeAbsentDiag_Cnt_str.NStep	44488
k_BSINodeAbsentTimeout_mS_u16	7002
k_BSINodeTimeout_mS_u16	2111
k_BattOvHi_Volt_f32	6.50769997
k_BattOvLo_Volt_f32	12.8698997
k_BattUvHi_Volt_f32	24.8918991
k_BattUvLo_Volt_f32	12.8264999
k_CAVNTCEnableTimeout_mS_u16	18243
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	50688
k_CAVNodeTimeout_mS_u16	20278
k_CMM388MsgTimeout_mS_u16	10833
k_CMM388NTCEnableTimeout_mS_u16	40541
k_CMMNTCEnableTimeout_mS_u16	29168
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	35947
k_CONSANGLECPKMax_HwDeg_f32	714.599304
k_CONSANGLECPKMin_HwDeg_f32	-420.218597
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	34741
k_CONSANGLECPKSigValidThresh_Cnt_u16	39263
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	52399
k_CPKVehicleSpeedValidThresh_Cnt_u16	10591
k_CityParkInputInvalidThresh_Cnt_u16	996
k_CityParkInputValidThresh_Cnt_u16	28067
k_ComputerRazGCTSigValidThresh_Cnt_u16	60454
k_CptTemporelSigValidThresh_Cnt_u16	35708
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	7469
k_DMDFCTCPKSigValidThresh_Cnt_u16	22351
k_DMDFCTCPKValidCount_Cnt_u16	13882
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	8116
k_DMDRELAXECPKSigValidThresh_Cnt_u16	11855
k_DMDRelaxeConsistentThresh_Cnt_u16	45245
k_DateValidThresh_Cnt_u16	18170
k_DefaultVehSpd_Kph_f32	95.7352982
k_DiagMuxOnAbsentTimeout_mS_u16	26849
k_EMNodeTimeout_mS_u16	56571
k_ESPNTCEnableTimeout_mS_u16	47878
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	30547
k_EtatMTSigInvalidThresh_Cnt_u16	47937
k_EtatMTSigValidThresh_Cnt_u16	62011
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	57670
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	38676
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	24352
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	59753
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	1279
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	13596
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	10872
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	28022
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	62299
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	38167
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	2941
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	37547
k_ISDATDIRASentDiag_Cnt_str.Threshold	32735

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	25081
k_ISDATDIRASentDiag_Cnt_str.NStep	58726
k_ISDATDIRASentTimeout_mS_u16	35330
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	2164
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58434
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	48610
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	1014
k_ISDYNAASChkSumValidThresh_Cnt_u16	51376
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	46926
k_ISDYNAASMsgCountValidThresh_Cnt_u16	19584
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	36586
k_ISDYNAASMsgLenValidThresh_Cnt_u16	53813
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	4764
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	42291
k_ISDYNABRChkSumValidThresh_Cnt_u16	63445
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	7506
k_ISDYNABRMsgCountValidThresh_Cnt_u16	17636
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	12403
k_ISDYNABRMsgLenValidThresh_Cnt_u16	35249
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	49423
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	39787
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	56805
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	45036
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	2127
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	25505
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	14397
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	19063
k_ISDYNVOLChkSumValidThresh_Cnt_u16	45437
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	44706
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	25252
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	35557
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	57684
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	52120
k_IgnOnTimeout_mS_u16	17283
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	22.9701996
k_PowerCutVehSpdLowThresh_Kph_f32	86.9468002
k_PowerCutVehSpdLowTimeout_mS_u16	41818
k_VBattMaxAAS_Volt_f32	25.3001995
k_VBattMaxBSI_Volt_f32	8.4744997
k_VBattMaxCAV_Volt_f32	6.58939981
k_VBattMaxCMM388_Volt_f32	22.7919006
k_VBattMaxCMM_Volt_f32	23.3033009
k_VBattMaxESP_Volt_f32	0.00829999987
k_VBattMinAAS_Volt_f32	14.8479004
k_VBattMinBSI_Volt_f32	0.00829999987
k_VBattMinCAV_Volt_f32	14.3389997
k_VBattMinCMM388_Volt_f32	11.0242996
k_VBattMinCMM_Volt_f32	26.4102993
k_VBattMinESP_Volt_f32	23.3033009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	3846
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	48892
k_VitesseVehicleBVRampValidThresh_Cnt_u16	14647
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	1426
k_VitesseVehicleBVSigValidThresh_Cnt_u16	29240
k_VitesseVehicleBVSpeedPassThresh_kph_f32	0
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	57594
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	29956
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	343576320
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	45704
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3854158080
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	202
target_SrlComInput_Per1_Batt_Volt_f32.value	16.1005993
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3389865728
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	23
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.508519828
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	197
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3529846528
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2171916032
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	13
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	429158144
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1120145152
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2768482048
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	232
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3897773824
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3031625472
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	58
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	129
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	164
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	171
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	240
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	139
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2569080576
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	158
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	205
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	792473344
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	667668224
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3379261184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	132
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	166
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	186
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2236268288
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	292
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.22388719
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	897247
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	76.8258972
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	39817

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3854158080	3854158080	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	22339	22339	✔
CONSANGLECPK_HwDeg_M_f32	236.538498	236.538498 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3854158080	3854158080	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3854158080	3854158080	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3854158080	3854158080	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3854158080	3854158080	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3854158080	3854158080	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3854158080	3854158080	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3854158080	3854158080	✔
ESPNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3854158080	3854158080	✔
EffacDefaultDiagTimer_mS_M_u32[1]	990	990	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3854158080	3854158080	✔
ElecIntTimer_mS_M_u32[1]	19	19	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3854158080	3854158080	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATDIRASentFltAcc_Cnt_M_u16	32735	32735	✔
ISDATDIRASentTimer_mS_M_u32	3854158080	3854158080	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3854158080	3854158080	✔
IgnOnTimer_mS_M_u32	1346580224	1346580224	✔
IgnTimeOff_Sec_M_u32	508381750	508381750	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	197	197	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3529846528	3529846528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	31	31	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2171916032	2171916032	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	13	13	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	429158144	429158144	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	57	57	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1120145152	1120145152	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4149047040	4149047040	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	232	232	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3897773824	3897773824	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	186	186	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3031625472	3031625472	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	139	139	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2569080576	2569080576	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	229	229	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	792473344	792473344	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	168	168	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	667668224	667668224	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	192	192	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3379261184	3379261184	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2236268288	2236268288	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	551.638	551.638	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	297.586212	297.586212	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	593.426575	593.426575	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	22339	22339	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	508381750	508381750	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	236.538498	236.538498 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.410 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1276700160
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	32999
AASNodeAbsentTimer_mS_M_u32	1632687616
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	235
ANGLEVOLANTSigValidCount_Cnt_M_u16	62389
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	18964
AngleVolantMsgTimer_mS_M_u32	1276700160
AngleVolantValidCount_Cnt_M_u16	17995
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2108986880
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1730876928
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2944501248
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1311000064
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	36322
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2392983040
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	26988
CAVNodeAbsentTimer_mS_M_u32	2450355712
CDD_SrlComVehSpd_Kph_G_f32	627.937195
CMM388NTCEnableTimer_mS_M_u32	3161830912
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1405318656
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	11455
CMMNodeAbsentTimer_mS_M_u32	3673048576
CONSANGLECPKSigInvalidCount_Cnt_M_u16	14171
CONSANGLECPKSigValidCount_Cnt_M_u16	29301
CONSANGLECPK_Cnt_M_u16	720
CONSANGLECPK_HwDeg_M_f32	-749.661499
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	720
CPKVehicleSpeedMsgTimer_mS_M_u32	1606936064
CPKVehicleSpeedValidCount_Cnt_M_u16	8451
CityParkInputConsistentCount_Cnt_M_u16	48239
CityParkInputInvalidCount_Cnt_M_u16	38632

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	3529846528
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1618269696
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	60683
ComputerRazGCTSigInvalidTimer_mS_M_u32	1406531072
ComputerRazGCTSigValidCount_Cnt_M_u16	54740
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	48324
DMDFCTCPKSigValidCount_Cnt_M_u16	14966
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	33533
DMDRELAXECPKSigValidCount_Cnt_M_u16	16199
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	18824
DateInvalidTimer_mS_M_u32	1730876928
DiagMuxOnAbsentTimer_mS_M_u32	3648431616
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1311000064
ESPNTCEnableTimer_mS_M_u32	2975979008
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	54725
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1000
EffacDefaultDiagTimer_mS_M_u32[1]	2001
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	88
ElecIntTimer_mS_M_u32[1]	111
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3239314944
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	65420
EtatMTSigValidCount_Cnt_M_u16	50178
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	28525
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	62471
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	54828
ISDAT4V2BSI552MsgTimer_mS_M_u32	2903655936
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	45840
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	42317
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	50178
ISDATBSI3F2MsgTimer_mS_M_u32	962897408
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	24610
ISDATBSI412MsgLenValidCount_Cnt_M_u16	1936
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	65420
ISDATBSI412MsgTimer_mS_M_u32	2449925632
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	4579
ISDATBSI432MsgLenValidCount_Cnt_M_u16	3561
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	47773
ISDATDIRASentFltAcc_Cnt_M_u16	34769
ISDATDIRASentTimer_mS_M_u32	1606936064
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	6462
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	17995
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	31547
ISDYN2CMMMsgTimer_mS_M_u32	1386993152
ISDYNAASChkSumInvalidCount_Cnt_M_u16	52985
ISDYNAASChkSumValidCount_Cnt_M_u16	30946
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	60098
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	37383
ISDYNAASMsgLenValidCount_Cnt_M_u16	35048
ISDYNAASMsgTimeValidCount_Cnt_M_u16	52985
ISDYNAASMsgTimer_mS_M_u32	928101888
ISDYNABRChkSumInvalidCount_Cnt_M_u16	16759
ISDYNABRChkSumValidCount_Cnt_M_u16	38920
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	3568
ISDYNABRMsgCountValidCount_Cnt_M_u16	54041
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	26962
ISDYNABRMsgLenValidCount_Cnt_M_u16	65452
ISDYNABRMsgTimeValidCount_Cnt_M_u16	720
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	46871
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	40397

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	50178
ISDYNCMM208MsgTimer_mS_M_u32	525964800
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	46871
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	40397
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	49977
ISDYNCMM388MsgTimer_mS_M_u32	19740160
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	53065
ISDYNVOLChkSumValidCount_Cnt_M_u16	49379
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	34738
ISDYNVOLMsgCountValidCount_Cnt_M_u16	64484
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	21966
ISDYNVOLMsgLenValidCount_Cnt_M_u16	14791
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	11455
ISDYNVOLMsgTimer_mS_M_u32	984741376
IgnOnTimer_mS_M_u32	508638720
IgnTimeOff_Sec_M_u32	158927450
ManVehSpd_Kph_M_f32	546.254578
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	22
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	18
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	351970816
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	25
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3076032000
PrevISDATBSI412MsgDLCError_Cnt_M_u08	67
PrevISDATBSI412MsgRxTime_MSec_M_u32	368997888
PrevISDATBSI432MsgDLCError_Cnt_M_u08	232
PrevISDATBSI432MsgRxTime_MSec_M_u32	1995822592
PrevISDATDIRAMsgTxTime_MSec_M_u32	573732352
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	215
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1255261696
PrevISDYNAASMsgDLCError_Cnt_M_u08	181
PrevISDYNAASMsgRxTime_MSec_M_u32	421524992
PrevISDYNABRMsgDLCError_Cnt_M_u08	221
PrevISDYNABRMsgRxTime_MSec_M_u32	3607705088
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	40
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1615132160
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	44
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2488325632
PrevISDYNVOLMsgDLCError_Cnt_M_u08	65
PrevISDYNVOLMsgRxTime_MSec_M_u32	2759554560
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2599740928
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	622.033386
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	17141
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	45142
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	20606
VitesseVehicleBVRampValidCount_Cnt_M_u16	671
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	42996
VitesseVehicleBVSigValidCount_Cnt_M_u16	65406
VitesseVehicleBV_Kph_M_f32	448.391602

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	49977
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	62202
VitesseVehiculeRoues_Kph_M_f32	154.396393
k_AASNTCEnableTimeout_mS_u16	191
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	63390
k_AASNodeTimeout_mS_u16	25430
k_ABSNodeTimeout_mS_u16	44585
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	43126
k_ANGLEVOLANTSigValidThresh_Cnt_u16	31932
k_AngleVolantInvalidThresh_Cnt_u16	57851
k_AngleVolantValidThresh_Cnt_u16	38632
k_BSI552MsgTimeout_mS_u16	44281
k_BSINTCEnableTimeout_mS_u16	15003
k_BSINodeAbsentDiag_Cnt_str.Threshold	28766
k_BSINodeAbsentDiag_Cnt_str.PStep	41333
k_BSINodeAbsentDiag_Cnt_str.NStep	19647
k_BSINodeAbsentTimeout_mS_u16	1228
k_BSINodeTimeout_mS_u16	47773
k_BattOvHi_Volt_f32	26.8281002
k_BattOvLo_Volt_f32	24.2134991
k_BattUvHi_Volt_f32	13.1257
k_BattUvLo_Volt_f32	11.3311996
k_CAVNTCEnableTimeout_mS_u16	142
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	50522
k_CAVNodeTimeout_mS_u16	10807
k_CMM388MsgTimeout_mS_u16	29671
k_CMM388NTCEnableTimeout_mS_u16	18371
k_CMMNTCEnableTimeout_mS_u16	63432
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	64726
k_CONSANGLECPKMax_HwDeg_f32	488.582611
k_CONSANGLECPKMin_HwDeg_f32	-188.722397
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	13881
k_CONSANGLECPKSigValidThresh_Cnt_u16	42490
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	43532
k_CPKVehicleSpeedValidThresh_Cnt_u16	23165
k_CityParkInputInvalidThresh_Cnt_u16	60589
k_CityParkInputValidThresh_Cnt_u16	48239
k_ComputerRazGCTSigValidThresh_Cnt_u16	57638
k_CptTemporelSigValidThresh_Cnt_u16	22499
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	23634
k_DMDFCTCPKSigValidThresh_Cnt_u16	12972
k_DMDFCTCPKValidCount_Cnt_u16	54826
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	31547
k_DMDRELAXECPKSigValidThresh_Cnt_u16	46125
k_DMDRelaxeConsistentThresh_Cnt_u16	25827
k_DateValidThresh_Cnt_u16	54828
k_DefaultVehSpd_Kph_f32	232.148499
k_DiagMuxOnAbsentTimeout_mS_u16	50678
k_EMNodeTimeout_mS_u16	54504
k_ESPNTCEnableTimeout_mS_u16	32328
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	56350
k_EtatMTSigInvalidThresh_Cnt_u16	31382
k_EtatMTSigValidThresh_Cnt_u16	47719
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	34887
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	39836
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	7160
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	46429
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	46938
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	27462
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	17840
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	29046

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	14087
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	39252
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	51937
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	40856
k_ISDATDIRASentDiag_Cnt_str.Threshold	5639
k_ISDATDIRASentDiag_Cnt_str.PStep	36987
k_ISDATDIRASentDiag_Cnt_str.NStep	30451
k_ISDATDIRASentTimeout_mS_u16	21075
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	41533
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	18964
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	58804
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	46199
k_ISDYNAASChkSumValidThresh_Cnt_u16	19208
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	240
k_ISDYNAASMsgCountValidThresh_Cnt_u16	1561
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	58267
k_ISDYNAASMsgLenValidThresh_Cnt_u16	12666
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	39428
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	23616
k_ISDYNABRChkSumValidThresh_Cnt_u16	59674
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	32994
k_ISDYNABRMsgCountValidThresh_Cnt_u16	20204
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	57279
k_ISDYNABRMsgLenValidThresh_Cnt_u16	51397
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	18027
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	45337
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	54507
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	13397
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	62443
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	9909
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	38304
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	22325
k_ISDYNVOLChkSumValidThresh_Cnt_u16	14051
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	24050
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	19756
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	26984
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	6878
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	16466
k_IgnOnTimeout_mS_u16	39953
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	90.9439011
k_PowerCutVehSpdLowThresh_Kph_f32	3.01430011
k_PowerCutVehSpdLowTimeout_mS_u16	14987
k_VBattMaxAAS_Volt_f32	16.0550995
k_VBattMaxBSI_Volt_f32	26.8936005
k_VBattMaxCAV_Volt_f32	20.8507004
k_VBattMaxCMM388_Volt_f32	27.4796009
k_VBattMaxCMM_Volt_f32	17.0184994
k_VBattMaxESP_Volt_f32	27.3167992
k_VBattMinAAS_Volt_f32	2.64960003
k_VBattMinBSI_Volt_f32	27.3167992
k_VBattMinCAV_Volt_f32	12.6518002
k_VBattMinCMM388_Volt_f32	24.2073002
k_VBattMinCMM_Volt_f32	20.6849995
k_VBattMinESP_Volt_f32	17.0184994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	22151
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	7013
k_VitesseVehicleBVRampValidThresh_Cnt_u16	64178
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	62435
k_VitesseVehicleBVSigValidThresh_Cnt_u16	17072
k_VitesseVehicleBVSpeedPassThresh_kph_f32	655.340027
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	56428
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	17677
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1730876928
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	2529
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	282421248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	44

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	31
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	758318592
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	49
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.522798538
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	58
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2682992128
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3644610048
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2539484672
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	18
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3796801024
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3255809536
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1050727936
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1610741248
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	43
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	101
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	208
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2469893632
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	65
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	147
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	217
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2774939136
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	211
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	37180928
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2748872192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	79
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	93
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	175
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3514467840
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1702
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.88817507
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	506458
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	185.626801
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	43199

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	282421248	282421248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	18966	18966	✔
AngleVolantMsgTimer_mS_M_u32	282421248	282421248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	282421248	282421248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	282421248	282421248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	282421248	282421248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	282421248	282421248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	720	720	✔
CONSANGLECPK_HwDeg_M_f32	-749.661499	-749.661499 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	720	720	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1606936064	1606936064	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	8451	8451	✔
CityParkInputConsistentCount_Cnt_M_u16	48239	48239	✔
CityParkInputInvalidCount_Cnt_M_u16	38634	38634	✔
CityParkInputMsgTimer_mS_M_u32	282421248	282421248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	282421248	282421248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	282421248	282421248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	282421248	282421248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	282421248	282421248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	282421248	282421248	✔
ESPNTCEnableTimer_mS_M_u32	282421248	282421248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1000	1000	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2001	2001	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	88	88	✔
ElecIntTimer_mS_M_u32[1]	111	111	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	282421248	282421248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	5639	5639	✔
ISDATDIRASentTimer_mS_M_u32	282421248	282421248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	282421248	282421248	✔
IgnOnTimer_mS_M_u32	508638720	508638720	✔
IgnTimeOff_Sec_M_u32	158927450	158927450	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	58	58	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2682992128	2682992128	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	84	84	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3644610048	3644610048	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	239	239	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2539484672	2539484672	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	18	18	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3796801024	3796801024	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	573732352	573732352	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1050727936	1050727936	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	2	2	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1610741248	1610741248	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	208	208	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2469893632	2469893632	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	246	246	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2774939136	2774939136	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	211	211	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	37180928	37180928	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	241	241	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2748872192	2748872192	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3514467840	3514467840	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	622.033386	622.033386	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	448.391602	448.391602	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	154.396393	154.396393	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	720	720	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	158927450	158927450	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-749.661499	-749.661499 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.411 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3396079872
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	34304
AASNodeAbsentTimer_mS_M_u32	2525249792
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	47091
ANGLEVOLANTSigValidCount_Cnt_M_u16	4438
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	7801
AngleVolantMsgTimer_mS_M_u32	3396079872
AngleVolantValidCount_Cnt_M_u16	28244
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2153316608
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3186983168
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2326933760
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2848583936
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	44302
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	256946432
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	9970
CAVNodeAbsentTimer_mS_M_u32	1053712640
CDD_SrlComVehSpd_Kph_G_f32	451.743286
CMM388NTCEnableTimer_mS_M_u32	2962596096
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1370251520
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	1975
CMMNodeAbsentTimer_mS_M_u32	2875977984
CONSANGLECPKSigInvalidCount_Cnt_M_u16	33699
CONSANGLECPKSigValidCount_Cnt_M_u16	17431
CONSANGLECPK_Cnt_M_u16	48902
CONSANGLECPK_HwDeg_M_f32	628.787903
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	48902
CPKVehicleSpeedMsgTimer_mS_M_u32	190779648
CPKVehicleSpeedValidCount_Cnt_M_u16	64084
CityParkInputConsistentCount_Cnt_M_u16	39912
CityParkInputInvalidCount_Cnt_M_u16	33148

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	2682992128
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	689455360
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	53652
ComputerRazGCTSigInvalidTimer_mS_M_u32	3144999168
ComputerRazGCTSigValidCount_Cnt_M_u16	9145
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	32744
DMDFCTCPKSigValidCount_Cnt_M_u16	55444
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	63933
DMDRELAXECPKSigValidCount_Cnt_M_u16	63136
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	16668
DateInvalidTimer_mS_M_u32	3186983168
DiagMuxOnAbsentTimer_mS_M_u32	3377647872
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2848583936
ESPNTCEnableTimer_mS_M_u32	709968128
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	11879
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	2500
EffacDefaultDiagTimer_mS_M_u32[1]	3501
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1
ElecIntTimer_mS_M_u32[1]	14
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3220877568
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	21583
EtatMTSigValidCount_Cnt_M_u16	59567
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	41837
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	34657
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	23922
ISDAT4V2BSI552MsgTimer_mS_M_u32	3305107712
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	65349
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	10829
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	59567
ISDATBSI3F2MsgTimer_mS_M_u32	3783840000
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	4367
ISDATBSI412MsgLenValidCount_Cnt_M_u16	56454
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	21583
ISDATBSI412MsgTimer_mS_M_u32	815927552
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	59467
ISDATBSI432MsgLenValidCount_Cnt_M_u16	5627
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	14175
ISDATDIRASentFltAcc_Cnt_M_u16	40899
ISDATDIRASentTimer_mS_M_u32	190779648
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	46012
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	28244
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	57475
ISDYN2CMMMsgTimer_mS_M_u32	4000530688
ISDYNAASChkSumInvalidCount_Cnt_M_u16	25546
ISDYNAASChkSumValidCount_Cnt_M_u16	6094
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	7407
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	55585
ISDYNAASMsgLenValidCount_Cnt_M_u16	34365
ISDYNAASMsgTimeValidCount_Cnt_M_u16	25546
ISDYNAASMsgTimer_mS_M_u32	2952896768
ISDYNABRChkSumInvalidCount_Cnt_M_u16	56272
ISDYNABRChkSumValidCount_Cnt_M_u16	10716
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	17125
ISDYNABRMsgCountValidCount_Cnt_M_u16	42281
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	35262
ISDYNABRMsgLenValidCount_Cnt_M_u16	14450
ISDYNABRMsgTimeValidCount_Cnt_M_u16	48902
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	6574
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	18254

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	59567
ISDYNCMM208MsgTimer_mS_M_u32	1869218048
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	6574
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	18254
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	12170
ISDYNCMM388MsgTimer_mS_M_u32	544153856
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	62425
ISDYNVOLChkSumValidCount_Cnt_M_u16	37069
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	22302
ISDYNVOLMsgCountValidCount_Cnt_M_u16	52298
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	4684
ISDYNVOLMsgLenValidCount_Cnt_M_u16	22560
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	1975
ISDYNVOLMsgTimer_mS_M_u32	1994449152
IgnOnTimer_mS_M_u32	1493377280
IgnTimeOff_Sec_M_u32	459024453
ManVehSpd_Kph_M_f32	521.809814
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	23
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	69
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	650563840
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	19
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2402103552
PrevISDATBSI412MsgDLCError_Cnt_M_u08	219
PrevISDATBSI412MsgRxTime_MSec_M_u32	3069927680
PrevISDATBSI432MsgDLCError_Cnt_M_u08	113
PrevISDATBSI432MsgRxTime_MSec_M_u32	697647360
PrevISDATDIRAMsgTxTime_MSec_M_u32	1650417920
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	13
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1237414144
PrevISDYNAASMsgDLCError_Cnt_M_u08	165
PrevISDYNAASMsgRxTime_MSec_M_u32	328655104
PrevISDYNABRMsgDLCError_Cnt_M_u08	195
PrevISDYNABRMsgRxTime_MSec_M_u32	249241856
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	131
PrevISDYNCMM208MsgRxTime_MSec_M_u32	304603392
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	183
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4253303040
PrevISDYNVOLMsgDLCError_Cnt_M_u08	45
PrevISDYNVOLMsgRxTime_MSec_M_u32	1065640192
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1306005760
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	413.050507
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	65111
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	18419
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	14780
VitesseVehicleBVRampValidCount_Cnt_M_u16	46360
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	9944
VitesseVehicleBVSigValidCount_Cnt_M_u16	20987
VitesseVehicleBV_Kph_M_f32	459.667603

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	12170
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	45573
VitesseVehiculeRoues_Kph_M_f32	217.414703
k_AASNTCEnableTimeout_mS_u16	16697
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	26203
k_AASNodeTimeout_mS_u16	12019
k_ABSNodeTimeout_mS_u16	32697
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	12434
k_ANGLEVOLANTSigValidThresh_Cnt_u16	54658
k_AngleVolantInvalidThresh_Cnt_u16	25029
k_AngleVolantValidThresh_Cnt_u16	33148
k_BSI552MsgTimeout_mS_u16	16392
k_BSINTCEnableTimeout_mS_u16	20003
k_BSINodeAbsentDiag_Cnt_str.Threshold	8538
k_BSINodeAbsentDiag_Cnt_str.PStep	56406
k_BSINodeAbsentDiag_Cnt_str.NStep	63670
k_BSINodeAbsentTimeout_mS_u16	52817
k_BSINodeTimeout_mS_u16	14175
k_BattOvHi_Volt_f32	4.0618
k_BattOvLo_Volt_f32	27.4890995
k_BattUvHi_Volt_f32	18.3185997
k_BattUvLo_Volt_f32	7.67420006
k_CAVNTCEnableTimeout_mS_u16	23690
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	19240
k_CAVNodeTimeout_mS_u16	6927
k_CMM388MsgTimeout_mS_u16	44288
k_CMM388NTCEnableTimeout_mS_u16	41324
k_CMMNTCEnableTimeout_mS_u16	4381
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	1137
k_CONSANGLECPKMax_HwDeg_f32	696.383301
k_CONSANGLECPKMin_HwDeg_f32	-630.425293
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	54922
k_CONSANGLECPKSigValidThresh_Cnt_u16	39173
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	45777
k_CPKVehicleSpeedValidThresh_Cnt_u16	19966
k_CityParkInputInvalidThresh_Cnt_u16	12846
k_CityParkInputValidThresh_Cnt_u16	39912
k_ComputerRazGCTSigValidThresh_Cnt_u16	19715
k_CptTemporelSigValidThresh_Cnt_u16	60043
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	45246
k_DMDFCTCPKSigValidThresh_Cnt_u16	40818
k_DMDFCTCPKValidCount_Cnt_u16	62518
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	57475
k_DMDRELAXECPKSigValidThresh_Cnt_u16	1903
k_DMDRelaxeConsistentThresh_Cnt_u16	19789
k_DateValidThresh_Cnt_u16	23922
k_DefaultVehSpd_Kph_f32	18.7682991
k_DiagMuxOnAbsentTimeout_mS_u16	36244
k_EMNodeTimeout_mS_u16	7932
k_ESPNTCEnableTimeout_mS_u16	22622
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	34457
k_EtatMTSigInvalidThresh_Cnt_u16	27763
k_EtatMTSigValidThresh_Cnt_u16	65215
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	50208
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	60384
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	57677
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	27742
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	26662
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	32675
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	49380
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	24404

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	2271
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	2938
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	47250
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	64428
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	6460
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	51133
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	7801
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	53786
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	33488
k_ISDYNAASChkSumValidThresh_Cnt_u16	4316
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	27109
k_ISDYNAASMsgCountValidThresh_Cnt_u16	3113
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	34148
k_ISDYNAASMsgLenValidThresh_Cnt_u16	21639
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	40362
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	59636
k_ISDYNABRChkSumValidThresh_Cnt_u16	46120
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	54286
k_ISDYNABRMsgCountValidThresh_Cnt_u16	39857
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	61111
k_ISDYNABRMsgLenValidThresh_Cnt_u16	21863
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	28980
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	17387
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	5812
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	30710
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	57075
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	30806
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	25940
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	14294
k_ISDYNVOLChkSumValidThresh_Cnt_u16	23181
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	35296
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	39536
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	34491
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	21531
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	14080
k_IgnOnTimeout_mS_u16	55618
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	240.882095
k_PowerCutVehSpdLowThresh_Kph_f32	192.671204
k_PowerCutVehSpdLowTimeout_mS_u16	50133
k_VBattMaxAAS_Volt_f32	2.00670004
k_VBattMaxBSI_Volt_f32	22.4071999
k_VBattMaxCAV_Volt_f32	9.63080025
k_VBattMaxCMM388_Volt_f32	22.0349998
k_VBattMaxCMM_Volt_f32	14.1984997
k_VBattMaxESP_Volt_f32	30.0646
k_VBattMinAAS_Volt_f32	11.5114002
k_VBattMinBSI_Volt_f32	30.0646
k_VBattMinCAV_Volt_f32	22.0781002
k_VBattMinCMM388_Volt_f32	15.5775003
k_VBattMinCMM_Volt_f32	30.2371006
k_VBattMinESP_Volt_f32	14.1984997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	21215
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	34310
k_VitesseVehicleBVRampValidThresh_Cnt_u16	65054
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	63437
k_VitesseVehicleBVSigValidThresh_Cnt_u16	19749
k_VitesseVehicleBVSpeedPassThresh_kph_f32	655.340027
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	52722
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	9678
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3186983168
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	57136
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	146705152
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	183

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	14.2989998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3080564992
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	232
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.360333174
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3157598464
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	204
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1019330816
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	201
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1860067584
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	982188288
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2278007040
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1049903360
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1190191360
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	11
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	46
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	47
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	95
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	103
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	196
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	22
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	198181120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	44
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	60
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	107
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1472471296
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1842397440
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4117586176
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	48
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	72
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	84
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	88
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	165
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1221013760
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2257
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.370662183
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	794897
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	212.083496
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	29945

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	146705152	146705152	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	146705152	146705152	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	146705152	146705152	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	146705152	146705152	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
CDD_SrlComVehSpd_Kph_G_f32	521.809814	521.809814	✔
CMM388NTCEnableTimer_mS_M_u32	146705152	146705152	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	146705152	146705152	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	48902	48902	✔
CONSANGLECPK_HwDeg_M_f32	628.787903	628.787903 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	146705152	146705152	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	146705152	146705152	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	146705152	146705152	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	146705152	146705152	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	146705152	146705152	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	146705152	146705152	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	146705152	146705152	✔
ESPNTCEnableTimer_mS_M_u32	146705152	146705152	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2500	2500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3501	3501	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	1	1	✔
ElecIntTimer_mS_M_u32[1]	14	14	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	146705152	146705152	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	23922	23922	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	59567	59567	✔
ISDATBSI3F2MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	21583	21583	✔
ISDATBSI412MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	14175	14175	✔
ISDATBSI432MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATDIRASentFltAcc_Cnt_M_u16	41895	41895	✔
ISDATDIRASentTimer_mS_M_u32	146705152	146705152	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	57475	57475	✔
ISDYN2CMMMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	25546	25546	✔
ISDYNAASMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	48902	48902	✔
ISDYNABRMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	59567	59567	✔
ISDYNCMM208MsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	12170	12170	✔
ISDYNCMM388MsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	1975	1975	✔
ISDYNVOLMsgTimer_mS_M_u32	146705152	146705152	✔
IgnOnTimer_mS_M_u32	1493377280	1493377280	✔
IgnTimeOff_Sec_M_u32	459024453	459024453	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	142	142	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3157598464	3157598464	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	204	204	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1019330816	1019330816	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	201	201	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1860067584	1860067584	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	107	107	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	982188288	982188288	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1650417920	1650417920	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	63	63	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1049903360	1049903360	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1190191360	1190191360	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	22	22	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	198181120	198181120	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1472471296	1472471296	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	251	251	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1842397440	1842397440	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	108	108	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4117586176	4117586176	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1221013760	1221013760	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	413.050507	413.050507	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	459.667603	459.667603	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	217.414703	217.414703	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	48902	48902	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	459024453	459024453	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	628.787903	628.787903 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	521.809814	521.809814	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.412 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3856568320
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	42273
AASNodeAbsentTimer_mS_M_u32	1582694400
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	63817
ANGLEVOLANTSigValidCount_Cnt_M_u16	22494
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	65462
AngleVolantMsgTimer_mS_M_u32	3856568320
AngleVolantValidCount_Cnt_M_u16	17062
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3822567424
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1023557632
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3851169792
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2537877504
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	17912
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4054888448
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	45770
CAVNodeAbsentTimer_mS_M_u32	3052904448
CDD_SrlComVehSpd_Kph_G_f32	378.907013
CMM388NTCEnableTimer_mS_M_u32	2376196096
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1969070080
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	36923
CMMNodeAbsentTimer_mS_M_u32	2589913088
CONSANGLECPKSigInvalidCount_Cnt_M_u16	18743
CONSANGLECPKSigValidCount_Cnt_M_u16	45724
CONSANGLECPK_Cnt_M_u16	48591
CONSANGLECPK_HwDeg_M_f32	355.8284
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	48591
CPKVehicleSpeedMsgTimer_mS_M_u32	2936377344
CPKVehicleSpeedValidCount_Cnt_M_u16	59949
CityParkInputConsistentCount_Cnt_M_u16	2538
CityParkInputInvalidCount_Cnt_M_u16	64045
CityParkInputMsgTimer_mS_M_u32	3157598464
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4137287680
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	4709

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	4194574336
ComputerRazGCTSigValidCount_Cnt_M_u16	63095
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	44777
DMDFCTCPKSigValidCount_Cnt_M_u16	12198
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56299
DMDRELAXECPKSigValidCount_Cnt_M_u16	20480
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	13516
DateInvalidTimer_mS_M_u32	1023557632
DiagMuxOnAbsentTimer_mS_M_u32	4096413696
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2537877504
ESPNTCEnableTimer_mS_M_u32	384761856
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	46828
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	579
EffacDefaultDiagTimer_mS_M_u32[1]	990
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	19
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	129150976
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	23411
EtatMTSigValidCount_Cnt_M_u16	63764
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	37337
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	37054
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	39180
ISDAT4V2BSI552MsgTimer_mS_M_u32	2644701184
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	2577
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	33722
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	63764
ISDATBSI3F2MsgTimer_mS_M_u32	59265024
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	35253
ISDATBSI412MsgLenValidCount_Cnt_M_u16	57870
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	23411
ISDATBSI412MsgTimer_mS_M_u32	188518400
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	15999
ISDATBSI432MsgLenValidCount_Cnt_M_u16	20528
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	30083
ISDATDIRASentFltAcc_Cnt_M_u16	52311
ISDATDIRASentTimer_mS_M_u32	2936377344
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	14253
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	17062
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	47384
ISDYN2CMMMsgTimer_mS_M_u32	3532193792
ISDYNAASChkSumInvalidCount_Cnt_M_u16	46019
ISDYNAASChkSumValidCount_Cnt_M_u16	33400
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	25301
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	6205
ISDYNAASMsgLenValidCount_Cnt_M_u16	23466
ISDYNAASMsgTimeValidCount_Cnt_M_u16	46019
ISDYNAASMsgTimer_mS_M_u32	1063116800
ISDYNABRChkSumInvalidCount_Cnt_M_u16	56623
ISDYNABRChkSumValidCount_Cnt_M_u16	64972
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	17010
ISDYNABRMsgCountValidCount_Cnt_M_u16	1639
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	25318
ISDYNABRMsgLenValidCount_Cnt_M_u16	395
ISDYNABRMsgTimeValidCount_Cnt_M_u16	48591
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	54528
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	6575
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	63764
ISDYNCMM208MsgTimer_mS_M_u32	2594488320
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	54528
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	6575
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	22276

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2215993344
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	20629
ISDYNVOLChkSumValidCount_Cnt_M_u16	9338
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	33095
ISDYNVOLMsgCountValidCount_Cnt_M_u16	44164
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	57149
ISDYNVOLMsgLenValidCount_Cnt_M_u16	14466
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	36923
ISDYNVOLMsgTimer_mS_M_u32	2009079808
IgnOnTimer_mS_M_u32	710500352
IgnTimeOff_Sec_M_u32	11892135
ManVehSpd_Kph_M_f32	37.3112984
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	24
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2882424832
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	247
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2216374272
PrevISDATBSI412MsgDLCError_Cnt_M_u08	207
PrevISDATBSI412MsgRxTime_MSec_M_u32	1097900032
PrevISDATBSI432MsgDLCError_Cnt_M_u08	125
PrevISDATBSI432MsgRxTime_MSec_M_u32	690159616
PrevISDATDIRAMsgTxTime_MSec_M_u32	3477381120
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	104
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4116606976
PrevISDYNAASMsgDLCError_Cnt_M_u08	11
PrevISDYNAASMsgRxTime_MSec_M_u32	4187889664
PrevISDYNABRMsgDLCError_Cnt_M_u08	243
PrevISDYNABRMsgRxTime_MSec_M_u32	1758552064
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	211
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2179670016
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	121
PrevISDYNCMM388MsgRxTime_MSec_M_u32	693501952
PrevISDYNVOLMsgDLCError_Cnt_M_u08	241
PrevISDYNVOLMsgRxTime_MSec_M_u32	198549504
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	194678784
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	7.8579998
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	155
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	28296
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	8812
VitesseVehicleBVRampValidCount_Cnt_M_u16	64281
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	32922
VitesseVehicleBVSigValidCount_Cnt_M_u16	27119
VitesseVehicleBV_Kph_M_f32	634.591309
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	22276
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	39505
VitesseVehiculeRoues_Kph_M_f32	139.686096
k_AASNTCEnableTimeout_mS_u16	49974
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	13969
k_AASNodeTimeout_mS_u16	47496
k_ABSNodeTimeout_mS_u16	13174
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	16810
k_ANGLEVOLANTSigValidThresh_Cnt_u16	60827
k_AngleVolantInvalidThresh_Cnt_u16	5330
k_AngleVolantValidThresh_Cnt_u16	64045
k_BSI552MsgTimeout_mS_u16	48200
k_BSINTCEnableTimeout_mS_u16	27895
k_BSINodeAbsentDiag_Cnt_str.Threshold	51817
k_BSINodeAbsentDiag_Cnt_str.PStep	30839
k_BSINodeAbsentDiag_Cnt_str.NStep	44488
k_BSINodeAbsentTimeout_mS_u16	20526
k_BSINodeTimeout_mS_u16	30083
k_BattOvHi_Volt_f32	4.49440002
k_BattOvLo_Volt_f32	17.4619999
k_BattUvHi_Volt_f32	9.77589989
k_BattUvLo_Volt_f32	24.7924995
k_CAVNTCEnableTimeout_mS_u16	8451
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	40488
k_CAVNodeTimeout_mS_u16	13043
k_CMM388MsgTimeout_mS_u16	12321
k_CMM388NTCEnableTimeout_mS_u16	733
k_CMMNTCEnableTimeout_mS_u16	13449
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	21261
k_CONSANGLECPKMax_HwDeg_f32	263.416595
k_CONSANGLECPKMin_HwDeg_f32	-502.986694
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	25092
k_CONSANGLECPKSigValidThresh_Cnt_u16	58705
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	9710
k_CPKVehicleSpeedValidThresh_Cnt_u16	0
k_CityParkInputInvalidThresh_Cnt_u16	53781
k_CityParkInputValidThresh_Cnt_u16	2538
k_ComputerRazGCTSigValidThresh_Cnt_u16	39127
k_CptTemporelSigValidThresh_Cnt_u16	47872
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	60902
k_DMDFCTCPKSigValidThresh_Cnt_u16	52363
k_DMDFCTCPKValidCount_Cnt_u16	4224
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	47384
k_DMDRELAXECPKSigValidThresh_Cnt_u16	53013
k_DMDRelaxeConsistentThresh_Cnt_u16	62843
k_DateValidThresh_Cnt_u16	39180
k_DefaultVehSpd_Kph_f32	183.330795
k_DiagMuxOnAbsentTimeout_mS_u16	2597
k_EMNodeTimeout_mS_u16	6956
k_ESPNTCEnableTimeout_mS_u16	52870
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	27797
k_EtatMTSigInvalidThresh_Cnt_u16	30534
k_EtatMTSigValidThresh_Cnt_u16	52003
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	60929
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	20866
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	3515
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	26310
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	28207
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	36345
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	22708
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	6181
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	11459
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	43123
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	56300
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	52958
k_ISDATDIRASentDiag_Cnt_str.Threshold	1170

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	4955
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	54507
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	61099
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	65462
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	20818
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	59439
k_ISDYNAASChkSumValidThresh_Cnt_u16	18636
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	52594
k_ISDYNAASMsgCountValidThresh_Cnt_u16	53607
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	12403
k_ISDYNAASMsgLenValidThresh_Cnt_u16	39116
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	13603
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	40260
k_ISDYNABRChkSumValidThresh_Cnt_u16	58985
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	53496
k_ISDYNABRMsgCountValidThresh_Cnt_u16	58573
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	56123
k_ISDYNABRMsgLenValidThresh_Cnt_u16	16876
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	12356
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	32735
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	19654
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	43647
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	33865
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	8926
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	44709
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	61792
k_ISDYNVOLChkSumValidThresh_Cnt_u16	17401
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	51329
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	64528
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	29743
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	26320
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	50274
k_IgnOnTimeout_mS_u16	48412
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	121.489502
k_PowerCutVehSpdLowThresh_Kph_f32	178.122299
k_PowerCutVehSpdLowTimeout_mS_u16	43874
k_VBattMaxAAS_Volt_f32	18.9407997
k_VBattMaxBSI_Volt_f32	29.9913006
k_VBattMaxCAV_Volt_f32	29.0363007
k_VBattMaxCMM388_Volt_f32	26.9505005
k_VBattMaxCMM_Volt_f32	3.11910009
k_VBattMaxESP_Volt_f32	13.2389002
k_VBattMinAAS_Volt_f32	16.5625
k_VBattMinBSI_Volt_f32	13.2389002
k_VBattMinCAV_Volt_f32	28.1424999
k_VBattMinCMM388_Volt_f32	29.1464005
k_VBattMinCMM_Volt_f32	5.88910007
k_VBattMinESP_Volt_f32	3.11910009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	21829
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	13965
k_VitesseVehicleBVRampValidThresh_Cnt_u16	35911
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	61306
k_VitesseVehicleBVSigValidThresh_Cnt_u16	10803
k_VitesseVehicleBVSpeedPassThresh_kph_f32	142.309402
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	48586
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	247
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1023557632
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65036
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	163190528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	121
target_SrlComInput_Per1_Batt_Volt_f32.value	24.9323006
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1825157120
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	30
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.466862172
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1220763648
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	140
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1100840960
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1707581440
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4248944640
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1342955520
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2787508224
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	176
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1200627712
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	12
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	71
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	80
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	98
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	194
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	232
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3715284992
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	40
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	127
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1914068992
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2859499520
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3457851392
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	37
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	49
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	80
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	162
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	201
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1062023168
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	990
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.989037395
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	350431
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	210.1353
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	42165

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	163190528	163190528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	163190528	163190528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	163190528	163190528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	163190528	163190528	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CDD_SrlComVehSpd_Kph_G_f32	37.3112984	37.3112984	✔
CMM388NTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	48591	48591	✔
CONSANGLECPK_HwDeg_M_f32	355.8284	355.8284 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	163190528	163190528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	163190528	163190528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	163190528	163190528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	163190528	163190528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	163190528	163190528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	163190528	163190528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	163190528	163190528	✔
ESPNTCEnableTimer_mS_M_u32	163190528	163190528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	579	579	✔
EffacDefaultDiagTimer_mS_M_u32[1]	990	990	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	6	6	✔
ElecIntTimer_mS_M_u32[1]	19	19	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	163190528	163190528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	39180	39180	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	63764	63764	✔
ISDATBSI3F2MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	23411	23411	✔
ISDATBSI412MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	30083	30083	✔
ISDATBSI432MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1170	1170	✔
ISDATDIRASentTimer_mS_M_u32	163190528	163190528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	47384	47384	✔
ISDYN2CMMMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	46019	46019	✔
ISDYNAASMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	48591	48591	✔
ISDYNABRMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	63764	63764	✔
ISDYNCMM208MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	22276	22276	✔
ISDYNCMM388MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	36923	36923	✔
ISDYNVOLMsgTimer_mS_M_u32	163190528	163190528	✔
IgnOnTimer_mS_M_u32	710500352	710500352	✔
IgnTimeOff_Sec_M_u32	11892135	11892135	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	238	238	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1220763648	1220763648	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	140	140	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1100840960	1100840960	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	49	49	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1707581440	1707581440	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4248944640	4248944640	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3477381120	3477381120	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	30	30	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2787508224	2787508224	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	176	176	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1200627712	1200627712	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	121	121	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3715284992	3715284992	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	127	127	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1914068992	1914068992	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	253	253	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2859499520	2859499520	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3457851392	3457851392	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1062023168	1062023168	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	7.8579998	7.8579998	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	634.591309	634.591309	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	139.686096	139.686096	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	48591	48591	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	11892135	11892135	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	355.8284	355.8284 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.413 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2151879424
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	27771
AASNodeAbsentTimer_mS_M_u32	2157757184
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	45570
ANGLEVOLANTSigValidCount_Cnt_M_u16	22019
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	61628
AngleVolantMsgTimer_mS_M_u32	2151879424
AngleVolantValidCount_Cnt_M_u16	36972
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	655852288
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3851944704
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3216651008
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2106585856
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	18421
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3444355840
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	29182
CAVNodeAbsentTimer_mS_M_u32	2285363968
CDD_SrlComVehSpd_Kph_G_f32	227.543594
CMM388NTCEnableTimer_mS_M_u32	2050564864
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1644552960
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	23147
CMMNodeAbsentTimer_mS_M_u32	1547825920
CONSANGLECPKSigInvalidCount_Cnt_M_u16	43320
CONSANGLECPKSigValidCount_Cnt_M_u16	27850
CONSANGLECPK_Cnt_M_u16	55089
CONSANGLECPK_HwDeg_M_f32	26.7278996
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	55089
CPKVehicleSpeedMsgTimer_mS_M_u32	2160988928
CPKVehicleSpeedValidCount_Cnt_M_u16	55102
CityParkInputConsistentCount_Cnt_M_u16	19104
CityParkInputInvalidCount_Cnt_M_u16	38614
CityParkInputMsgTimer_mS_M_u32	1220763648
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3352347392
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	13487

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2383569664
ComputerRazGCTSigValidCount_Cnt_M_u16	63737
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	26786
DMDFCTCPKSigValidCount_Cnt_M_u16	17963
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	4636
DMDRELAXECPKSigValidCount_Cnt_M_u16	30109
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	31353
DateInvalidTimer_mS_M_u32	3851944704
DiagMuxOnAbsentTimer_mS_M_u32	878695168
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2106585856
ESPNTCEnableTimer_mS_M_u32	4208050944
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	5656
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1000
EffacDefaultDiagTimer_mS_M_u32[1]	2001
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	88
ElecIntTimer_mS_M_u32[1]	111
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	323400448
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	58821
EtatMTSigValidCount_Cnt_M_u16	64674
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	55122
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	55908
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	8697
ISDAT4V2BSI552MsgTimer_mS_M_u32	1651897088
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	52074
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	28207
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	64674
ISDATBSI3F2MsgTimer_mS_M_u32	4265988864
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	11645
ISDATBSI412MsgLenValidCount_Cnt_M_u16	62514
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	58821
ISDATBSI412MsgTimer_mS_M_u32	136909568
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	24479
ISDATBSI432MsgLenValidCount_Cnt_M_u16	23116
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	19923
ISDATDIRASentFltAcc_Cnt_M_u16	39255
ISDATDIRASentTimer_mS_M_u32	2160988928
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	24983
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	36972
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	50709
ISDYN2CMMMsgTimer_mS_M_u32	2953036544
ISDYNAASChkSumInvalidCount_Cnt_M_u16	18581
ISDYNAASChkSumValidCount_Cnt_M_u16	7222
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	43999
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	52645
ISDYNAASMsgLenValidCount_Cnt_M_u16	8990
ISDYNAASMsgTimeValidCount_Cnt_M_u16	18581
ISDYNAASMsgTimer_mS_M_u32	1426400000
ISDYNABRChkSumInvalidCount_Cnt_M_u16	6094
ISDYNABRChkSumValidCount_Cnt_M_u16	38328
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	6280
ISDYNABRMsgCountValidCount_Cnt_M_u16	3177
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	55339
ISDYNABRMsgLenValidCount_Cnt_M_u16	64509
ISDYNABRMsgTimeValidCount_Cnt_M_u16	55089
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	46871
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	40397
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	64674
ISDYNCMM208MsgTimer_mS_M_u32	1991279360
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	46871
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	40397
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	19282

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3302925056
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	35614
ISDYNVOLChkSumValidCount_Cnt_M_u16	3888
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	59784
ISDYNVOLMsgCountValidCount_Cnt_M_u16	51089
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	8485
ISDYNVOLMsgLenValidCount_Cnt_M_u16	38166
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	23147
ISDYNVOLMsgTimer_mS_M_u32	81683200
IgnOnTimer_mS_M_u32	3792872192
IgnTimeOff_Sec_M_u32	2183594014
ManVehSpd_Kph_M_f32	333.839203
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	22
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	93
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2641613568
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	134
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3758961408
PrevISDATBSI412MsgDLCError_Cnt_M_u08	112
PrevISDATBSI412MsgRxTime_MSec_M_u32	164422400
PrevISDATBSI432MsgDLCError_Cnt_M_u08	24
PrevISDATBSI432MsgRxTime_MSec_M_u32	2486551296
PrevISDATDIRAMsgTxTime_MSec_M_u32	2958091008
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	15
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2839769856
PrevISDYNAASMsgDLCError_Cnt_M_u08	235
PrevISDYNAASMsgRxTime_MSec_M_u32	2000970496
PrevISDYNABRMsgDLCError_Cnt_M_u08	109
PrevISDYNABRMsgRxTime_MSec_M_u32	111846144
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	109
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1381851904
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	184
PrevISDYNCMM388MsgRxTime_MSec_M_u32	530367232
PrevISDYNVOLMsgDLCError_Cnt_M_u08	192
PrevISDYNVOLMsgRxTime_MSec_M_u32	2124276480
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4279177984
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	176.712708
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	3211
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	57988
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	11032
VitesseVehicleBVRampValidCount_Cnt_M_u16	49361
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	40975
VitesseVehicleBVSigValidCount_Cnt_M_u16	41936
VitesseVehicleBV_Kph_M_f32	591.138977
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	19282
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	8491
VitesseVehiculeRoues_Kph_M_f32	490.126892
k_AASNTCEnableTimeout_mS_u16	8956
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	8363
k_AASNodeTimeout_mS_u16	388
k_ABSNodeTimeout_mS_u16	20219
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	49694
k_ANGLEVOLANTSigValidThresh_Cnt_u16	60939
k_AngleVolantInvalidThresh_Cnt_u16	5222
k_AngleVolantValidThresh_Cnt_u16	38614
k_BSI552MsgTimeout_mS_u16	22342
k_BSINTCEnableTimeout_mS_u16	46135
k_BSINodeAbsentDiag_Cnt_str.Threshold	28766
k_BSINodeAbsentDiag_Cnt_str.PStep	41333
k_BSINodeAbsentDiag_Cnt_str.NStep	19647
k_BSINodeAbsentTimeout_mS_u16	57172
k_BSINodeTimeout_mS_u16	19923
k_BattOvHi_Volt_f32	1.63950002
k_BattOvLo_Volt_f32	5.48799992
k_BattUvHi_Volt_f32	4.13969994
k_BattUvLo_Volt_f32	9.83930016
k_CAVNTCEnableTimeout_mS_u16	64084
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	42980
k_CAVNodeTimeout_mS_u16	56324
k_CMM388MsgTimeout_mS_u16	52091
k_CMM388NTCEnableTimeout_mS_u16	17223
k_CMMNTCEnableTimeout_mS_u16	11266
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	59127
k_CONSANGLECPKMax_HwDeg_f32	746.947693
k_CONSANGLECPKMin_HwDeg_f32	-660.35498
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	10834
k_CONSANGLECPKSigValidThresh_Cnt_u16	16427
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	54354
k_CPKVehicleSpeedValidThresh_Cnt_u16	65535
k_CityParkInputInvalidThresh_Cnt_u16	20764
k_CityParkInputValidThresh_Cnt_u16	19104
k_ComputerRazGCTSigValidThresh_Cnt_u16	46872
k_CptTemporelSigValidThresh_Cnt_u16	24669
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	14123
k_DMDFCTCPKSigValidThresh_Cnt_u16	39677
k_DMDFCTCPKValidCount_Cnt_u16	2141
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	50709
k_DMDRELAXECPKSigValidThresh_Cnt_u16	58334
k_DMDRelaxeConsistentThresh_Cnt_u16	34988
k_DateValidThresh_Cnt_u16	8697
k_DefaultVehSpd_Kph_f32	12.3776999
k_DiagMuxOnAbsentTimeout_mS_u16	51759
k_EMNodeTimeout_mS_u16	18265
k_ESPNTCEnableTimeout_mS_u16	3786
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	47711
k_EtatMTSigInvalidThresh_Cnt_u16	25993
k_EtatMTSigValidThresh_Cnt_u16	18867
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	34841
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	52567
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	49965
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	51531
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	49872
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	12465
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	9472
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	5741
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	42195
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	42821
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	23706
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	20228
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	8346
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	25501
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	61628
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	46694
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	63182
k_ISDYNAASChkSumValidThresh_Cnt_u16	46264
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	30600
k_ISDYNAASMsgCountValidThresh_Cnt_u16	43881
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	11778
k_ISDYNAASMsgLenValidThresh_Cnt_u16	29624
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	14195
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	8465
k_ISDYNABRChkSumValidThresh_Cnt_u16	17763
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	42741
k_ISDYNABRMsgCountValidThresh_Cnt_u16	11062
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	31083
k_ISDYNABRMsgLenValidThresh_Cnt_u16	29976
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	58577
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	40639
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	26698
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	51871
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	4354
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	62723
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	22894
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	25212
k_ISDYNVOLChkSumValidThresh_Cnt_u16	14961
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	30041
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	43756
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	35729
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	41838
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	30711
k_IgnOnTimeout_mS_u16	61256
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	176.401703
k_PowerCutVehSpdLowThresh_Kph_f32	14.5031996
k_PowerCutVehSpdLowTimeout_mS_u16	6776
k_VBattMaxAAS_Volt_f32	0.459800005
k_VBattMaxBSI_Volt_f32	14.5524998
k_VBattMaxCAV_Volt_f32	3.26979995
k_VBattMaxCMM388_Volt_f32	3.14650011
k_VBattMaxCMM_Volt_f32	18.6629009
k_VBattMaxESP_Volt_f32	13.1504002
k_VBattMinAAS_Volt_f32	28.1874008
k_VBattMinBSI_Volt_f32	13.1504002
k_VBattMinCAV_Volt_f32	28.6065006
k_VBattMinCMM388_Volt_f32	15.0890999
k_VBattMinCMM_Volt_f32	22.6959
k_VBattMinESP_Volt_f32	18.6629009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	6095
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	948
k_VitesseVehicleBVRampValidThresh_Cnt_u16	51336
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	44592
k_VitesseVehicleBVSigValidThresh_Cnt_u16	19909
k_VitesseVehicleBVSpeedPassThresh_kph_f32	327.786407
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	20734
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	42807
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3851944704
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	184
target_SrlComInput_Per1_Batt_Volt_f32.value	9.87419987
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	111360
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	28
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.505061328
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2933170944
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1422279424
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3100107520
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	47809280
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1526407936
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3912024832
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3580781312
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	62
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	64
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	76
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	84
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	153
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	177
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	204
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	97
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1715897088
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	93
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	162
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	167
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	187
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	197
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1054581504
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	61
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	642597632
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2345591552
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	45
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	121
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	146
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	172
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	190
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4135006976
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1914
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.512674093
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	121215
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	159.714401
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	2109

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	333.839203	333.839203	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	55089	55089	✔
CONSANGLECPK_HwDeg_M_f32	26.7278996	26.7278996 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2006148864	2006148864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1000	1000	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2001	2001	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	88	88	✔
ElecIntTimer_mS_M_u32[1]	111	111	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	8697	8697	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	64674	64674	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	58821	58821	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	19923	19923	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11170	11170	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	50709	50709	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	18581	18581	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	55089	55089	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	64674	64674	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	19282	19282	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	23147	23147	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	3792872192	3792872192	✔
IgnTimeOff_Sec_M_u32	2183594014	2183594014	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	110	110	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2933170944	2933170944	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	132	132	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1422279424	1422279424	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3100107520	3100107520	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	86	86	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	47809280	47809280	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2958091008	2958091008	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	16	16	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3912024832	3912024832	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	137	137	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3580781312	3580781312	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	97	97	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1715897088	1715897088	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	197	197	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1054581504	1054581504	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	61	61	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	642597632	642597632	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	158	158	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2345591552	2345591552	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4135006976	4135006976	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	176.712708	176.712708	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	591.138977	591.138977	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	490.126892	490.126892	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	55089	55089	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2183594014	2183594014	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	26.7278996	26.7278996 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	333.839203	333.839203	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.414 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3672214016
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	38968
AASNodeAbsentTimer_mS_M_u32	2626976256
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	420
ANGLEVOLANTSigValidCount_Cnt_M_u16	54880
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	20341
AngleVolantMsgTimer_mS_M_u32	3672214016
AngleVolantValidCount_Cnt_M_u16	14054
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	69483008
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1789049344
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1627138560
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2927290880
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	52171
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2722408960
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	64558
CAVNodeAbsentTimer_mS_M_u32	1514347008
CDD_SrlComVehSpd_Kph_G_f32	437.549286
CMM388NTCEnableTimer_mS_M_u32	423582208
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2228820480
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	49321
CMMNodeAbsentTimer_mS_M_u32	1516562944
CONSANGLECPKSigInvalidCount_Cnt_M_u16	26368
CONSANGLECPKSigValidCount_Cnt_M_u16	7436
CONSANGLECPK_Cnt_M_u16	14807
CONSANGLECPK_HwDeg_M_f32	-322.596008
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	14807
CPKVehicleSpeedMsgTimer_mS_M_u32	3309341184
CPKVehicleSpeedValidCount_Cnt_M_u16	18999
CityParkInputConsistentCount_Cnt_M_u16	55370
CityParkInputInvalidCount_Cnt_M_u16	40103
CityParkInputMsgTimer_mS_M_u32	2933170944
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2532866560
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	3996

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3534985728
ComputerRazGCTSigValidCount_Cnt_M_u16	28991
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	22339
DMDFCTCPKSigValidCount_Cnt_M_u16	40807
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	51542
DMDRELAXECPKSigValidCount_Cnt_M_u16	24466
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	14141
DateInvalidTimer_mS_M_u32	1789049344
DiagMuxOnAbsentTimer_mS_M_u32	562776576
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2927290880
ESPNTCEnableTimer_mS_M_u32	1106606592
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	65121
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	2500
EffacDefaultDiagTimer_mS_M_u32[1]	3501
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1
ElecIntTimer_mS_M_u32[1]	14
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	945203712
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	22426
EtatMTSigValidCount_Cnt_M_u16	17347
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	50354
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	48190
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	50173
ISDAT4V2BSI552MsgTimer_mS_M_u32	399043072
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	53803
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	47772
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	17347
ISDATBSI3F2MsgTimer_mS_M_u32	3688450560
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	2290
ISDATBSI412MsgLenValidCount_Cnt_M_u16	17810
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	22426
ISDATBSI412MsgTimer_mS_M_u32	1529842176
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	33037
ISDATBSI432MsgLenValidCount_Cnt_M_u16	453
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	64687
ISDATDIRASentFltAcc_Cnt_M_u16	10787
ISDATDIRASentTimer_mS_M_u32	3309341184
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	45733
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	14054
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	51946
ISDYN2CMMMsgTimer_mS_M_u32	1784642048
ISDYNAASChkSumInvalidCount_Cnt_M_u16	60394
ISDYNAASChkSumValidCount_Cnt_M_u16	45510
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	28813
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	17721
ISDYNAASMsgLenValidCount_Cnt_M_u16	58766
ISDYNAASMsgTimeValidCount_Cnt_M_u16	60394
ISDYNAASMsgTimer_mS_M_u32	3101383168
ISDYNABRChkSumInvalidCount_Cnt_M_u16	39869
ISDYNABRChkSumValidCount_Cnt_M_u16	33474
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	2065
ISDYNABRMsgCountValidCount_Cnt_M_u16	27949
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	26151
ISDYNABRMsgLenValidCount_Cnt_M_u16	64371
ISDYNABRMsgTimeValidCount_Cnt_M_u16	14807
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	6574
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	18254
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	17347
ISDYNCMM208MsgTimer_mS_M_u32	3109632512
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	6574
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	18254
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	7732

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2941180416
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	55630
ISDYNVOLChkSumValidCount_Cnt_M_u16	19930
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	60561
ISDYNVOLMsgCountValidCount_Cnt_M_u16	13109
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	20794
ISDYNVOLMsgLenValidCount_Cnt_M_u16	30247
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	49321
ISDYNVOLMsgTimer_mS_M_u32	2656016896
IgnOnTimer_mS_M_u32	666032640
IgnTimeOff_Sec_M_u32	2533910608
ManVehSpd_Kph_M_f32	248.776794
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	23
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	124
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	911165952
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	21
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	201533952
PrevISDATBSI412MsgDLCError_Cnt_M_u08	4
PrevISDATBSI412MsgRxTime_MSec_M_u32	1770265088
PrevISDATBSI432MsgDLCError_Cnt_M_u08	247
PrevISDATBSI432MsgRxTime_MSec_M_u32	97090048
PrevISDATDIRAMsgTxTime_MSec_M_u32	2247629312
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	228
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1499490816
PrevISDYNAASMsgDLCError_Cnt_M_u08	3
PrevISDYNAASMsgRxTime_MSec_M_u32	1595775488
PrevISDYNABRMsgDLCError_Cnt_M_u08	206
PrevISDYNABRMsgRxTime_MSec_M_u32	434821632
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	237
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1909627392
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	91
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3214178816
PrevISDYNVOLMsgDLCError_Cnt_M_u08	236
PrevISDYNVOLMsgRxTime_MSec_M_u32	2400262656
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2390592000
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	143.935898
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	41095
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	48988
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	47328
VitesseVehicleBVRampValidCount_Cnt_M_u16	39029
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	43901
VitesseVehicleBVSigValidCount_Cnt_M_u16	24825
VitesseVehicleBV_Kph_M_f32	549.198486
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	7732
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	48488
VitesseVehiculeRoues_Kph_M_f32	358.697815
k_AASNTCEnableTimeout_mS_u16	17014
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	16937
k_AASNodeTimeout_mS_u16	25180
k_ABSNodeTimeout_mS_u16	18488
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	5520
k_ANGLEVOLANTSigValidThresh_Cnt_u16	648
k_AngleVolantInvalidThresh_Cnt_u16	47991
k_AngleVolantValidThresh_Cnt_u16	40103
k_BSI552MsgTimeout_mS_u16	18199
k_BSINTCEnableTimeout_mS_u16	58181
k_BSINodeAbsentDiag_Cnt_str.Threshold	8538
k_BSINodeAbsentDiag_Cnt_str.PStep	56406
k_BSINodeAbsentDiag_Cnt_str.NStep	63670
k_BSINodeAbsentTimeout_mS_u16	58285
k_BSINodeTimeout_mS_u16	64687
k_BattOvHi_Volt_f32	12.8443003
k_BattOvLo_Volt_f32	3.04439998
k_BattUvHi_Volt_f32	15.3094997
k_BattUvLo_Volt_f32	8.46220016
k_CAVNTCEnableTimeout_mS_u16	59949
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	29308
k_CAVNodeTimeout_mS_u16	65180
k_CMM388MsgTimeout_mS_u16	31544
k_CMM388NTCEnableTimeout_mS_u16	17364
k_CMMNTCEnableTimeout_mS_u16	4195
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	39940
k_CONSANGLECPKMax_HwDeg_f32	131.648804
k_CONSANGLECPKMin_HwDeg_f32	-130.904907
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	33076
k_CONSANGLECPKSigValidThresh_Cnt_u16	24680
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	41458
k_CPKVehicleSpeedValidThresh_Cnt_u16	8446
k_CityParkInputInvalidThresh_Cnt_u16	42963
k_CityParkInputValidThresh_Cnt_u16	55370
k_ComputerRazGCTSigValidThresh_Cnt_u16	18209
k_CptTemporelSigValidThresh_Cnt_u16	7186
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	18727
k_DMDFCTCPKSigValidThresh_Cnt_u16	7795
k_DMDFCTCPKValidCount_Cnt_u16	10899
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	51946
k_DMDRELAXECPKSigValidThresh_Cnt_u16	21070
k_DMDRelaxeConsistentThresh_Cnt_u16	7140
k_DateValidThresh_Cnt_u16	50173
k_DefaultVehSpd_Kph_f32	53.0337982
k_DiagMuxOnAbsentTimeout_mS_u16	55517
k_EMNodeTimeout_mS_u16	20637
k_ESPNTCEnableTimeout_mS_u16	21962
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	49612
k_EtatMTSigInvalidThresh_Cnt_u16	24204
k_EtatMTSigValidThresh_Cnt_u16	4817
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	25245
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	17317
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	58019
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	40072
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	32953
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	53078
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	62698
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	37218
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	33137
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	6555
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	2652
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	53596
k_ISDATDIRASentDiag_Cnt_str.Threshold	37951

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	62140
k_ISDATDIRASentDiag_Cnt_str.NStep	43836
k_ISDATDIRASentTimeout_mS_u16	45401
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	14225
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	20341
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	52982
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	65213
k_ISDYNAASChkSumValidThresh_Cnt_u16	9666
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	60177
k_ISDYNAASMsgCountValidThresh_Cnt_u16	36909
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	10529
k_ISDYNAASMsgLenValidThresh_Cnt_u16	56256
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	50768
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	41845
k_ISDYNABRChkSumValidThresh_Cnt_u16	14145
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	44747
k_ISDYNABRMsgCountValidThresh_Cnt_u16	58055
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	25513
k_ISDYNABRMsgLenValidThresh_Cnt_u16	57697
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	57846
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	47595
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	52363
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	13067
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	58532
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	63840
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	46303
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	9717
k_ISDYNVOLChkSumValidThresh_Cnt_u16	11989
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	9374
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	4902
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	38454
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	32607
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	14851
k_IgnOnTimeout_mS_u16	44945
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	137.462097
k_PowerCutVehSpdLowThresh_Kph_f32	87.157402
k_PowerCutVehSpdLowTimeout_mS_u16	19458
k_VBattMaxAAS_Volt_f32	22.8764
k_VBattMaxBSI_Volt_f32	3.86610007
k_VBattMaxCAV_Volt_f32	14.1563997
k_VBattMaxCMM388_Volt_f32	0.668900013
k_VBattMaxCMM_Volt_f32	23.0522995
k_VBattMaxESP_Volt_f32	31.0498009
k_VBattMinAAS_Volt_f32	9.91549969
k_VBattMinBSI_Volt_f32	31.0498009
k_VBattMinCAV_Volt_f32	2.18050003
k_VBattMinCMM388_Volt_f32	8.25049973
k_VBattMinCMM_Volt_f32	6.92509985
k_VBattMinESP_Volt_f32	23.0522995
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	25339
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	61451
k_VitesseVehicleBVRampValidThresh_Cnt_u16	20369
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	28890
k_VitesseVehicleBVSigValidThresh_Cnt_u16	41691
k_VitesseVehicleBVSpeedPassThresh_kph_f32	652.791321
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	24366
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	64835
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1789049344
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	45704
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3854158080
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	91
target_SrlComInput_Per1_Batt_Volt_f32.value	2.52320004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	505784832
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	57
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.100765876
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	250
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1231870464
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	231
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2786589184
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	150
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	143858176
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4175313408
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4277754368
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	124
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2732882432
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	130
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1822398976
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	54
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	107
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	121
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	225
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	96
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3264690688
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	59
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	77
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	89
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	210
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	219
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	233
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1968691712
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	226687488
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1803426304
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	23
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	86
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	157
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	199
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4039453184
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3720
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0158640165
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1024014
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	207.773804
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	62833

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3854158080	3854158080	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
CDD_SrlComVehSpd_Kph_G_f32	248.776794	248.776794	✔
CMM388NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	14807	14807	✔
CONSANGLECPK_HwDeg_M_f32	-322.596008	-322.596008 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3854158080	3854158080	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3854158080	3854158080	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3854158080	3854158080	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3854158080	3854158080	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3854158080	3854158080	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3854158080	3854158080	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3854158080	3854158080	✔
ESPNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2500	2500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3501	3501	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1	1	✔
ElecIntTimer_mS_M_u32[1]	14	14	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3854158080	3854158080	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	50173	50173	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	17347	17347	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	22426	22426	✔
ISDATBSI412MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	64687	64687	✔
ISDATBSI432MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATDIRASentFltAcc_Cnt_M_u16	37951	37951	✔
ISDATDIRASentTimer_mS_M_u32	3854158080	3854158080	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	51946	51946	✔
ISDYN2CMMMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	60394	60394	✔
ISDYNAASMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	14807	14807	✔
ISDYNABRMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	17347	17347	✔
ISDYNCMM208MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	7732	7732	✔
ISDYNCMM388MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	49321	49321	✔
ISDYNVOLMsgTimer_mS_M_u32	3854158080	3854158080	✔
IgnOnTimer_mS_M_u32	666032640	666032640	✔
IgnTimeOff_Sec_M_u32	2533910608	2533910608	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	250	250	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1231870464	1231870464	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	231	231	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2786589184	2786589184	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	150	150	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	143858176	143858176	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	142	142	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4175313408	4175313408	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2247629312	2247629312	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	124	124	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2732882432	2732882432	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	130	130	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1822398976	1822398976	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	96	96	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3264690688	3264690688	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	208	208	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1968691712	1968691712	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	153	153	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	226687488	226687488	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1803426304	1803426304	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4039453184	4039453184	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	143.935898	143.935898	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	549.198486	549.198486	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	358.697815	358.697815	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	14807	14807	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2533910608	2533910608	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-322.596008	-322.596008 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.415 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	933064192
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	43003
AASNodeAbsentTimer_mS_M_u32	4231749120
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	27472
ANGLEVOLANTSigValidCount_Cnt_M_u16	44527
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	45640
AngleVolantMsgTimer_mS_M_u32	933064192
AngleVolantValidCount_Cnt_M_u16	10004
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3971423744
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1656593920
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1477053952
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3106196992
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	37287
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	670731776
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	47876
CAVNodeAbsentTimer_mS_M_u32	4068212224
CDD_SrlComVehSpd_Kph_G_f32	602.28418
CMM388NTCEnableTimer_mS_M_u32	4098637312
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1274150400
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	3286
CMMNodeAbsentTimer_mS_M_u32	1043254784
CONSANGLECPKSigInvalidCount_Cnt_M_u16	26968
CONSANGLECPKSigValidCount_Cnt_M_u16	63047
CONSANGLECPK_Cnt_M_u16	33410
CONSANGLECPK_HwDeg_M_f32	703.641785
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	33410
CPKVehicleSpeedMsgTimer_mS_M_u32	262958592
CPKVehicleSpeedValidCount_Cnt_M_u16	56536
CityParkInputConsistentCount_Cnt_M_u16	30648
CityParkInputInvalidCount_Cnt_M_u16	32057
CityParkInputMsgTimer_mS_M_u32	1851283200
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1977572864
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	44703

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3054796288
ComputerRazGCTSigValidCount_Cnt_M_u16	27965
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	18581
DMDFCTCPKSigValidCount_Cnt_M_u16	36636
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	15010
DMDRELAXECPKSigValidCount_Cnt_M_u16	46785
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	23717
DateInvalidTimer_mS_M_u32	1656593920
DiagMuxOnAbsentTimer_mS_M_u32	3746770432
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3106196992
ESPNTCEnableTimer_mS_M_u32	2683067904
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	18225
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	579
EffacDefaultDiagTimer_mS_M_u32[1]	990
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	19
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1135382016
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	62251
EtatMTSigValidCount_Cnt_M_u16	24310
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	44714
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	62745
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	658
ISDAT4V2BSI552MsgTimer_mS_M_u32	1792200192
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	51498
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	34750
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	24310
ISDATBSI3F2MsgTimer_mS_M_u32	838938112
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	53733
ISDATBSI412MsgLenValidCount_Cnt_M_u16	13224
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	62251
ISDATBSI412MsgTimer_mS_M_u32	810249728
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	11386
ISDATBSI432MsgLenValidCount_Cnt_M_u16	39381
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	13269
ISDATDIRASentFltAcc_Cnt_M_u16	54665
ISDATDIRASentTimer_mS_M_u32	262958592
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	7088
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	10004
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	4204
ISDYN2CMMMsgTimer_mS_M_u32	2306235904
ISDYNAASChkSumInvalidCount_Cnt_M_u16	49997
ISDYNAASChkSumValidCount_Cnt_M_u16	20749
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	38123
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	18303
ISDYNAASMsgLenValidCount_Cnt_M_u16	30006
ISDYNAASMsgTimeValidCount_Cnt_M_u16	49997
ISDYNAASMsgTimer_mS_M_u32	883441152
ISDYNABRChkSumInvalidCount_Cnt_M_u16	47959
ISDYNABRChkSumValidCount_Cnt_M_u16	18111
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	56228
ISDYNABRMsgCountValidCount_Cnt_M_u16	52388
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	21679
ISDYNABRMsgLenValidCount_Cnt_M_u16	34014
ISDYNABRMsgTimeValidCount_Cnt_M_u16	33410
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	54528
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	6575
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	24310
ISDYNCMM208MsgTimer_mS_M_u32	3531349504
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	54528
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	6575
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	46786

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3342056960
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	62470
ISDYNVOLChkSumValidCount_Cnt_M_u16	51061
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	58947
ISDYNVOLMsgCountValidCount_Cnt_M_u16	45898
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	19930
ISDYNVOLMsgLenValidCount_Cnt_M_u16	61354
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	3286
ISDYNVOLMsgTimer_mS_M_u32	3799023104
IgnOnTimer_mS_M_u32	517455360
IgnTimeOff_Sec_M_u32	1600273966
ManVehSpd_Kph_M_f32	558.798706
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	24
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	237
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2975280640
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	193
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2772504064
PrevISDATBSI412MsgDLCError_Cnt_M_u08	106
PrevISDATBSI412MsgRxTime_MSec_M_u32	369950208
PrevISDATBSI432MsgDLCError_Cnt_M_u08	112
PrevISDATBSI432MsgRxTime_MSec_M_u32	3590348288
PrevISDATDIRAMsgTxTime_MSec_M_u32	1455488512
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	41
PrevISDYN2CMMMsgRxTime_MSec_M_u32	63065600
PrevISDYNAASMsgDLCError_Cnt_M_u08	222
PrevISDYNAASMsgRxTime_MSec_M_u32	1134460416
PrevISDYNABRMsgDLCError_Cnt_M_u08	230
PrevISDYNABRMsgRxTime_MSec_M_u32	1116716544
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	66
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3202579968
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	32
PrevISDYNCMM388MsgRxTime_MSec_M_u32	255548928
PrevISDYNVOLMsgDLCError_Cnt_M_u08	62
PrevISDYNVOLMsgRxTime_MSec_M_u32	128581120
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3422121472
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	304.264191
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	35629
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	48996
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	3926
VitesseVehicleBVRampValidCount_Cnt_M_u16	16461
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	63737
VitesseVehicleBVSigValidCount_Cnt_M_u16	22616
VitesseVehicleBV_Kph_M_f32	180.216507
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	46786
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	35161
VitesseVehiculeRoues_Kph_M_f32	86.4803009
k_AASNTCEnableTimeout_mS_u16	60625
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	42823
k_AASNodeTimeout_mS_u16	21092
k_ABSNodeTimeout_mS_u16	5658
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	6637
k_ANGLEVOLANTSigValidThresh_Cnt_u16	51080
k_AngleVolantInvalidThresh_Cnt_u16	64295
k_AngleVolantValidThresh_Cnt_u16	32057
k_BSI552MsgTimeout_mS_u16	51640
k_BSINTCEnableTimeout_mS_u16	49202
k_BSINodeAbsentDiag_Cnt_str.Threshold	51817
k_BSINodeAbsentDiag_Cnt_str.PStep	30839
k_BSINodeAbsentDiag_Cnt_str.NStep	44488
k_BSINodeAbsentTimeout_mS_u16	6144
k_BSINodeTimeout_mS_u16	13269
k_BattOvHi_Volt_f32	1.30589998
k_BattOvLo_Volt_f32	0.594600022
k_BattUvHi_Volt_f32	17.4155998
k_BattUvLo_Volt_f32	21.7574997
k_CAVNTCEnableTimeout_mS_u16	58527
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	35250
k_CAVNodeTimeout_mS_u16	8628
k_CMM388MsgTimeout_mS_u16	31483
k_CMM388NTCEnableTimeout_mS_u16	46167
k_CMMNTCEnableTimeout_mS_u16	63714
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	47285
k_CONSANGLECPKMax_HwDeg_f32	651.66272
k_CONSANGLECPKMin_HwDeg_f32	-428.845886
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	2498
k_CONSANGLECPKSigValidThresh_Cnt_u16	7257
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	20698
k_CPKVehicleSpeedValidThresh_Cnt_u16	2080
k_CityParkInputInvalidThresh_Cnt_u16	28237
k_CityParkInputValidThresh_Cnt_u16	30648
k_ComputerRazGCTSigValidThresh_Cnt_u16	43776
k_CptTemporelSigValidThresh_Cnt_u16	15892
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	10159
k_DMDFCTCPKSigValidThresh_Cnt_u16	38878
k_DMDFCTCPKValidCount_Cnt_u16	3823
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	4204
k_DMDRELAXECPKSigValidThresh_Cnt_u16	23091
k_DMDRelaxeConsistentThresh_Cnt_u16	681
k_DateValidThresh_Cnt_u16	658
k_DefaultVehSpd_Kph_f32	215.9944
k_DiagMuxOnAbsentTimeout_mS_u16	45928
k_EMNodeTimeout_mS_u16	25605
k_ESPNTCEnableTimeout_mS_u16	54624
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	11517
k_EtatMTSigInvalidThresh_Cnt_u16	3798
k_EtatMTSigValidThresh_Cnt_u16	35710
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	46837
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	40353
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	36321
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	57495
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	18155
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	55177
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	58727
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	6786
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	35870
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	36742
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	61290
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	12163
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	20915
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	5704
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	45640
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	60492
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	3671
k_ISDYNAASChkSumValidThresh_Cnt_u16	55743
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	44708
k_ISDYNAASMsgCountValidThresh_Cnt_u16	57252
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	47099
k_ISDYNAASMsgLenValidThresh_Cnt_u16	64264
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	14800
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	6749
k_ISDYNABRChkSumValidThresh_Cnt_u16	53516
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	25767
k_ISDYNABRMsgCountValidThresh_Cnt_u16	51846
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	40918
k_ISDYNABRMsgLenValidThresh_Cnt_u16	6705
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	14437
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	54225
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	34126
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	2499
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	15952
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	49391
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	42737
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	61400
k_ISDYNVOLChkSumValidThresh_Cnt_u16	61915
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	28798
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	13923
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	33415
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	64338
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	14968
k_IgnOnTimeout_mS_u16	14900
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	48.6804008
k_PowerCutVehSpdLowThresh_Kph_f32	230.000702
k_PowerCutVehSpdLowTimeout_mS_u16	45597
k_VBattMaxAAS_Volt_f32	8.11559963
k_VBattMaxBSI_Volt_f32	0.973699987
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	27.5333004
k_VBattMaxCMM_Volt_f32	18.7509995
k_VBattMaxESP_Volt_f32	11.5813999
k_VBattMinAAS_Volt_f32	29.1068993
k_VBattMinBSI_Volt_f32	11.5813999
k_VBattMinCAV_Volt_f32	9.84630013
k_VBattMinCMM388_Volt_f32	21.2105007
k_VBattMinCMM_Volt_f32	14.2751999
k_VBattMinESP_Volt_f32	18.7509995
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	62162
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	51205
k_VitesseVehicleBVRampValidThresh_Cnt_u16	14659
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	55925
k_VitesseVehicleBVSigValidThresh_Cnt_u16	57241
k_VitesseVehicleBVSpeedPassThresh_kph_f32	123.4198
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	3588
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	34171
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1656593920
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	15965
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2717483008
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	32
target_SrlComInput_Per1_Batt_Volt_f32.value	25.9069004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2854981120
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	12
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.909165621
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3937517056
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2530663936
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	432799232
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2073107968
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3290840576
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	25
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4220214784
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	700481024
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	124
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	137
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	182
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	219
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	223
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	237
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	521805312
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	84
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	146
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	163
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	216
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	228
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1074576896
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3216104960
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	111
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3592879616
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	30
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	150
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	191
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2795703808
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2924
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.996472478
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	477752
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	16.9335995
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	35127

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2717483008	2717483008	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
CDD_SrlComVehSpd_Kph_G_f32	558.798706	558.798706	✔
CMM388NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	33410	33410	✔
CONSANGLECPK_HwDeg_M_f32	703.641785	703.641785 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2717483008	2717483008	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2717483008	2717483008	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2717483008	2717483008	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2717483008	2717483008	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2717483008	2717483008	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2717483008	2717483008	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2717483008	2717483008	✔
ESPNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	579	579	✔
EffacDefaultDiagTimer_mS_M_u32[1]	990	990	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	6	6	✔
ElecIntTimer_mS_M_u32[1]	19	19	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2717483008	2717483008	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	658	658	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	24310	24310	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	62251	62251	✔
ISDATBSI412MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	13269	13269	✔
ISDATBSI432MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATDIRASentFltAcc_Cnt_M_u16	41895	41895	✔
ISDATDIRASentTimer_mS_M_u32	2717483008	2717483008	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	4204	4204	✔
ISDYN2CMMMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	49997	49997	✔
ISDYNAASMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	33410	33410	✔
ISDYNABRMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	24310	24310	✔
ISDYNCMM208MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	46786	46786	✔
ISDYNCMM388MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	3286	3286	✔
ISDYNVOLMsgTimer_mS_M_u32	2717483008	2717483008	✔
IgnOnTimer_mS_M_u32	517455360	517455360	✔
IgnTimeOff_Sec_M_u32	1600273966	1600273966	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	186	186	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3937517056	3937517056	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	126	126	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2530663936	2530663936	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	148	148	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	432799232	432799232	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2073107968	2073107968	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1455488512	1455488512	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	25	25	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4220214784	4220214784	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	203	203	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	700481024	700481024	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	110	110	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	521805312	521805312	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	238	238	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1074576896	1074576896	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	37	37	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3216104960	3216104960	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	111	111	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3592879616	3592879616	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2795703808	2795703808	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	304.264191	304.264191	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	180.216507	180.216507	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	86.4803009	86.4803009	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	33410	33410	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1600273966	1600273966	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	703.641785	703.641785 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	558.798706	558.798706	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.416 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2751363328
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	60642
AASNodeAbsentTimer_mS_M_u32	2045028608
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	38117
ANGLEVOLANTSigValidCount_Cnt_M_u16	54983
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	16891
AngleVolantMsgTimer_mS_M_u32	2751363328
AngleVolantValidCount_Cnt_M_u16	30746
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1198614784
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	526248192
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1027119360
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	4108867840
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	15840
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	795285760
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	7753
CAVNodeAbsentTimer_mS_M_u32	3785541888
CDD_SrlComVehSpd_Kph_G_f32	539.278076
CMM388NTCEnableTimer_mS_M_u32	1831995648
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	759220480
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	52116
CMMNodeAbsentTimer_mS_M_u32	231364864
CONSANGLECPKSigInvalidCount_Cnt_M_u16	27086
CONSANGLECPKSigValidCount_Cnt_M_u16	3263
CONSANGLECPK_Cnt_M_u16	5134
CONSANGLECPK_HwDeg_M_f32	1.40600002
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	5134
CPKVehicleSpeedMsgTimer_mS_M_u32	399603968
CPKVehicleSpeedValidCount_Cnt_M_u16	62454
CityParkInputConsistentCount_Cnt_M_u16	5678
CityParkInputInvalidCount_Cnt_M_u16	39594
CityParkInputMsgTimer_mS_M_u32	3937517056
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2633541888
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	26870

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2564376832
ComputerRazGCTSigValidCount_Cnt_M_u16	35231
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	43158
DMDFCTCPKSigValidCount_Cnt_M_u16	32448
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	61167
DMDRELAXECPKSigValidCount_Cnt_M_u16	33873
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	999
DateInvalidTimer_mS_M_u32	526248192
DiagMuxOnAbsentTimer_mS_M_u32	3017619712
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4108867840
ESPNTCEnableTimer_mS_M_u32	2463213824
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	5697
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1000
EffacDefaultDiagTimer_mS_M_u32[1]	2001
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	88
ElecIntTimer_mS_M_u32[1]	111
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	609294592
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	64916
EtatMTSigValidCount_Cnt_M_u16	29681
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	25048
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	55369
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	31838
ISDAT4V2BSI552MsgTimer_mS_M_u32	400447744
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	12566
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	53019
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	29681
ISDATBSI3F2MsgTimer_mS_M_u32	4090706176
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	53223
ISDATBSI412MsgLenValidCount_Cnt_M_u16	17501
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	64916
ISDATBSI412MsgTimer_mS_M_u32	4059330816
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	64680
ISDATBSI432MsgLenValidCount_Cnt_M_u16	44629
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	14294
ISDATDIRASentFltAcc_Cnt_M_u16	8890
ISDATDIRASentTimer_mS_M_u32	399603968
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	32900
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	30746
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	27921
ISDYN2CMMMsgTimer_mS_M_u32	2117314816
ISDYNAASChkSumInvalidCount_Cnt_M_u16	25324
ISDYNAASChkSumValidCount_Cnt_M_u16	17262
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	19093
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	9432
ISDYNAASMsgLenValidCount_Cnt_M_u16	1393
ISDYNAASMsgTimeValidCount_Cnt_M_u16	25324
ISDYNAASMsgTimer_mS_M_u32	471730432
ISDYNABRChkSumInvalidCount_Cnt_M_u16	31311
ISDYNABRChkSumValidCount_Cnt_M_u16	473
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	13799
ISDYNABRMsgCountValidCount_Cnt_M_u16	60585
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	50121
ISDYNABRMsgLenValidCount_Cnt_M_u16	31994
ISDYNABRMsgTimeValidCount_Cnt_M_u16	5134
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	46871
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	40397
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	29681
ISDYNCMM208MsgTimer_mS_M_u32	3928123648
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	46871
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	40397
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	272

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	4068182272
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	452
ISDYNVOLChkSumValidCount_Cnt_M_u16	53557
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	1932
ISDYNVOLMsgCountValidCount_Cnt_M_u16	18998
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	58950
ISDYNVOLMsgLenValidCount_Cnt_M_u16	51864
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	52116
ISDYNVOLMsgTimer_mS_M_u32	2210744576
IgnOnTimer_mS_M_u32	2073004288
IgnTimeOff_Sec_M_u32	2257973395
ManVehSpd_Kph_M_f32	556.285278
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	22
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	224
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1305557248
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	190
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4052982016
PrevISDATBSI412MsgDLCError_Cnt_M_u08	250
PrevISDATBSI412MsgRxTime_MSec_M_u32	4210018560
PrevISDATBSI432MsgDLCError_Cnt_M_u08	95
PrevISDATBSI432MsgRxTime_MSec_M_u32	1083549952
PrevISDATDIRAMsgTxTime_MSec_M_u32	148097280
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	221
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1796200704
PrevISDYNAASMsgDLCError_Cnt_M_u08	152
PrevISDYNAASMsgRxTime_MSec_M_u32	2554022144
PrevISDYNABRMsgDLCError_Cnt_M_u08	204
PrevISDYNABRMsgRxTime_MSec_M_u32	4033317120
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	89
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2053916928
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	44
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1088727296
PrevISDYNVOLMsgDLCError_Cnt_M_u08	81
PrevISDYNVOLMsgRxTime_MSec_M_u32	3659057408
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1458206976
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	228.338806
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	37326
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	24295
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	59731
VitesseVehicleBVRampValidCount_Cnt_M_u16	49196
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	53226
VitesseVehicleBVSigValidCount_Cnt_M_u16	48012
VitesseVehicleBV_Kph_M_f32	372.301208
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	272
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	29450
VitesseVehiculeRoues_Kph_M_f32	472.76001
k_AASNTCEnableTimeout_mS_u16	53537
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	33665
k_AASNodeTimeout_mS_u16	42471
k_ABSNodeTimeout_mS_u16	37895
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	49231
k_ANGLEVOLANTSigValidThresh_Cnt_u16	45372
k_AngleVolantInvalidThresh_Cnt_u16	21087
k_AngleVolantValidThresh_Cnt_u16	39594
k_BSI552MsgTimeout_mS_u16	60909
k_BSINTCEnableTimeout_mS_u16	8576
k_BSINodeAbsentDiag_Cnt_str.Threshold	28766
k_BSINodeAbsentDiag_Cnt_str.PStep	41333
k_BSINodeAbsentDiag_Cnt_str.NStep	19647
k_BSINodeAbsentTimeout_mS_u16	61651
k_BSINodeTimeout_mS_u16	14294
k_BattOvHi_Volt_f32	12.0897999
k_BattOvLo_Volt_f32	12.5416002
k_BattUvHi_Volt_f32	12.0663004
k_BattUvLo_Volt_f32	10.4345999
k_CAVNTCEnableTimeout_mS_u16	31864
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	59967
k_CAVNodeTimeout_mS_u16	45242
k_CMM388MsgTimeout_mS_u16	29666
k_CMM388NTCEnableTimeout_mS_u16	14286
k_CMMNTCEnableTimeout_mS_u16	33262
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	21750
k_CONSANGLECPKMax_HwDeg_f32	488.196198
k_CONSANGLECPKMin_HwDeg_f32	-532.032715
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	2064
k_CONSANGLECPKSigValidThresh_Cnt_u16	47626
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	645
k_CPKVehicleSpeedValidThresh_Cnt_u16	55606
k_CityParkInputInvalidThresh_Cnt_u16	47469
k_CityParkInputValidThresh_Cnt_u16	5678
k_ComputerRazGCTSigValidThresh_Cnt_u16	25492
k_CptTemporelSigValidThresh_Cnt_u16	33817
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	19145
k_DMDFCTCPKSigValidThresh_Cnt_u16	17402
k_DMDFCTCPKValidCount_Cnt_u16	58888
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	27921
k_DMDRELAXECPKSigValidThresh_Cnt_u16	14715
k_DMDRelaxeConsistentThresh_Cnt_u16	38937
k_DateValidThresh_Cnt_u16	31838
k_DefaultVehSpd_Kph_f32	47.3558998
k_DiagMuxOnAbsentTimeout_mS_u16	39260
k_EMNodeTimeout_mS_u16	28103
k_ESPNTCEnableTimeout_mS_u16	16181
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	6174
k_EtatMTSigInvalidThresh_Cnt_u16	15314
k_EtatMTSigValidThresh_Cnt_u16	61340
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	64564
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	33266
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	47027
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	57039
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	34196
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	20219
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	50657
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	8270
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	28092
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	64770
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	63256
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	12
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	10043
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	40893
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	16891
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	43633
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	33103
k_ISDYNAASChkSumValidThresh_Cnt_u16	18649
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	48359
k_ISDYNAASMsgCountValidThresh_Cnt_u16	45993
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	5219
k_ISDYNAASMsgLenValidThresh_Cnt_u16	15355
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	31332
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	43711
k_ISDYNABRChkSumValidThresh_Cnt_u16	53360
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	50400
k_ISDYNABRMsgCountValidThresh_Cnt_u16	40194
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	4756
k_ISDYNABRMsgLenValidThresh_Cnt_u16	40257
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	36709
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	18402
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	39340
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	48074
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	7141
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	40391
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	64898
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	526
k_ISDYNVOLChkSumValidThresh_Cnt_u16	38340
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	3674
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	49901
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	49024
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	3805
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	60588
k_IgnOnTimeout_mS_u16	37626
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	235.797699
k_PowerCutVehSpdLowThresh_Kph_f32	147.836807
k_PowerCutVehSpdLowTimeout_mS_u16	45373
k_VBattMaxAAS_Volt_f32	31.5132999
k_VBattMaxBSI_Volt_f32	8.91759968
k_VBattMaxCAV_Volt_f32	27.8610992
k_VBattMaxCMM388_Volt_f32	12.0932999
k_VBattMaxCMM_Volt_f32	18.8141994
k_VBattMaxESP_Volt_f32	3.55240011
k_VBattMinAAS_Volt_f32	31.6713009
k_VBattMinBSI_Volt_f32	3.55240011
k_VBattMinCAV_Volt_f32	13.4949999
k_VBattMinCMM388_Volt_f32	9.63090038
k_VBattMinCMM_Volt_f32	21.1233006
k_VBattMinESP_Volt_f32	18.8141994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	45599
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	35909
k_VitesseVehicleBVRampValidThresh_Cnt_u16	3724
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	38965
k_VitesseVehicleBVSigValidThresh_Cnt_u16	41611
k_VitesseVehicleBVSpeedPassThresh_kph_f32	643.321472
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	9545
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	10402
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	526248192
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	19695
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2232967680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	44
target_SrlComInput_Per1_Batt_Volt_f32.value	24.5716991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2899581184
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	237
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.7256459
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	100608
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	155
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2014456064
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	115
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2880620800
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	124
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2195941632
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3852732672
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	187
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3153373440
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3990178048
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	59
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	85
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	92
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	176
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	201
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4232603904
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	125
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	141
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	161
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	188
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	211
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	218
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	737184000
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	696330496
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2728511744
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	61
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	97
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	122
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	145
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	153
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	169
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4117600512
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	45
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.19926177
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	126806
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	18.2882004
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	16304

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2232967680	2232967680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2232967680	2232967680	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2232967680	2232967680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2232967680	2232967680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2232967680	2232967680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2232967680	2232967680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2232967680	2232967680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2232967680	2232967680	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2232967680	2232967680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2232967680	2232967680	✔
CDD_SrlComVehSpd_Kph_G_f32	556.285278	556.285278	✔
CMM388NTCEnableTimer_mS_M_u32	2232967680	2232967680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2232967680	2232967680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2232967680	2232967680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	5134	5134	✔
CONSANGLECPK_HwDeg_M_f32	1.40600002	1.40600002 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2232967680	2232967680	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2232967680	2232967680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2232967680	2232967680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2232967680	2232967680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2232967680	2232967680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2232967680	2232967680	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2232967680	2232967680	✔
ESPNTCEnableTimer_mS_M_u32	2232967680	2232967680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2232967680	2232967680	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1000	1000	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2001	2001	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	88	88	✔
ElecIntTimer_mS_M_u32[1]	111	111	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2232967680	2232967680	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	31838	31838	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2232967680	2232967680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	29681	29681	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2232967680	2232967680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	64916	64916	✔
ISDATBSI412MsgTimer_mS_M_u32	2232967680	2232967680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	14294	14294	✔
ISDATBSI432MsgTimer_mS_M_u32	2232967680	2232967680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11170	11170	✔
ISDATDIRASentTimer_mS_M_u32	2232967680	2232967680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	27921	27921	✔
ISDYN2CMMMsgTimer_mS_M_u32	2232967680	2232967680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	25324	25324	✔
ISDYNAASMsgTimer_mS_M_u32	2232967680	2232967680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	5134	5134	✔
ISDYNABRMsgTimer_mS_M_u32	2232967680	2232967680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	29681	29681	✔
ISDYNCMM208MsgTimer_mS_M_u32	2232967680	2232967680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	272	272	✔
ISDYNCMM388MsgTimer_mS_M_u32	2232967680	2232967680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	52116	52116	✔
ISDYNVOLMsgTimer_mS_M_u32	2232967680	2232967680	✔
IgnOnTimer_mS_M_u32	2073004288	2073004288	✔
IgnTimeOff_Sec_M_u32	2257973395	2257973395	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	100608	100608	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	155	155	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2014456064	2014456064	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	115	115	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2880620800	2880620800	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	124	124	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2195941632	2195941632	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	148097280	148097280	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	187	187	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3153373440	3153373440	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	194	194	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3990178048	3990178048	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	167	167	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4232603904	4232603904	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	154	154	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	737184000	737184000	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	696330496	696330496	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	16	16	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2728511744	2728511744	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4117600512	4117600512	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	228.338806	228.338806	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	372.301208	372.301208	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	472.76001	472.76001	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	5134	5134	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2257973395	2257973395	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	1.40600002	1.40600002 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	556.285278	556.285278	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.417 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	80173056
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	23577
AASNodeAbsentTimer_mS_M_u32	399820800
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	36370
ANGLEVOLANTSigValidCount_Cnt_M_u16	43821
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	206
AngleVolantMsgTimer_mS_M_u32	80173056
AngleVolantValidCount_Cnt_M_u16	41202
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3526264832
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2624129024
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1234761728
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2441721856
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	16161
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1292728320
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	34919
CAVNodeAbsentTimer_mS_M_u32	18507776
CDD_SrlComVehSpd_Kph_G_f32	412.7453
CMM388NTCEnableTimer_mS_M_u32	2876024832
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	373319680
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	38982
CMMNodeAbsentTimer_mS_M_u32	1323546624
CONSANGLECPKSigInvalidCount_Cnt_M_u16	41560
CONSANGLECPKSigValidCount_Cnt_M_u16	56387
CONSANGLECPK_Cnt_M_u16	49750
CONSANGLECPK_HwDeg_M_f32	-374.1091
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	49750
CPKVehicleSpeedMsgTimer_mS_M_u32	3041810432
CPKVehicleSpeedValidCount_Cnt_M_u16	62952
CityParkInputConsistentCount_Cnt_M_u16	5814
CityParkInputInvalidCount_Cnt_M_u16	51778
CityParkInputMsgTimer_mS_M_u32	100608
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4271425536
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	14301

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3581339648
ComputerRazGCTSigValidCount_Cnt_M_u16	49251
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	20606
DMDFCTCPKSigValidCount_Cnt_M_u16	53441
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	10228
DMDRELAXECPKSigValidCount_Cnt_M_u16	19087
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	30733
DateInvalidTimer_mS_M_u32	2624129024
DiagMuxOnAbsentTimer_mS_M_u32	3224049664
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2441721856
ESPNTCEnableTimer_mS_M_u32	3238905856
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	51965
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	2500
EffacDefaultDiagTimer_mS_M_u32[1]	3501
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1
ElecIntTimer_mS_M_u32[1]	14
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2521790464
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	21317
EtatMTSigValidCount_Cnt_M_u16	49900
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	25146
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	8613
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	53223
ISDAT4V2BSI552MsgTimer_mS_M_u32	2158475264
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	38976
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	12527
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	49900
ISDATBSI3F2MsgTimer_mS_M_u32	1481185280
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	37068
ISDATBSI412MsgLenValidCount_Cnt_M_u16	26155
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	21317
ISDATBSI412MsgTimer_mS_M_u32	1927632896
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	21770
ISDATBSI432MsgLenValidCount_Cnt_M_u16	21185
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	44992
ISDATDIRASentFltAcc_Cnt_M_u16	32532
ISDATDIRASentTimer_mS_M_u32	3041810432
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	54516
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	41202
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	44813
ISDYN2CMMMsgTimer_mS_M_u32	115853312
ISDYNAASChkSumInvalidCount_Cnt_M_u16	41467
ISDYNAASChkSumValidCount_Cnt_M_u16	25398
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	54657
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	28858
ISDYNAASMsgLenValidCount_Cnt_M_u16	37293
ISDYNAASMsgTimeValidCount_Cnt_M_u16	41467
ISDYNAASMsgTimer_mS_M_u32	1319675904
ISDYNABRChkSumInvalidCount_Cnt_M_u16	23892
ISDYNABRChkSumValidCount_Cnt_M_u16	18807
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	54538
ISDYNABRMsgCountValidCount_Cnt_M_u16	4997
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	16487
ISDYNABRMsgLenValidCount_Cnt_M_u16	14226
ISDYNABRMsgTimeValidCount_Cnt_M_u16	49750
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	6574
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	18254
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	49900
ISDYNCMM208MsgTimer_mS_M_u32	3994781696
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	6574
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	18254
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	24080

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	563095552
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	12918
ISDYNVOLChkSumValidCount_Cnt_M_u16	59105
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	35740
ISDYNVOLMsgCountValidCount_Cnt_M_u16	50783
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	44782
ISDYNVOLMsgLenValidCount_Cnt_M_u16	42169
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	38982
ISDYNVOLMsgTimer_mS_M_u32	3300059136
IgnOnTimer_mS_M_u32	3595839488
IgnTimeOff_Sec_M_u32	134599832
ManVehSpd_Kph_M_f32	45.7317009
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	23
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	51
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3259963392
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	138
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1485305856
PrevISDATBSI412MsgDLCError_Cnt_M_u08	52
PrevISDATBSI412MsgRxTime_MSec_M_u32	691234816
PrevISDATBSI432MsgDLCError_Cnt_M_u08	166
PrevISDATBSI432MsgRxTime_MSec_M_u32	3351365632
PrevISDATDIRAMsgTxTime_MSec_M_u32	2408015872
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	45
PrevISDYN2CMMMsgRxTime_MSec_M_u32	756234240
PrevISDYNAASMsgDLCError_Cnt_M_u08	108
PrevISDYNAASMsgRxTime_MSec_M_u32	3746621440
PrevISDYNABRMsgDLCError_Cnt_M_u08	234
PrevISDYNABRMsgRxTime_MSec_M_u32	3620481024
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	99
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1019078656
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	156
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3268724736
PrevISDYNVOLMsgDLCError_Cnt_M_u08	175
PrevISDYNVOLMsgRxTime_MSec_M_u32	1874356224
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2617464832
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	366.180786
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	33240
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	56651
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	53065
VitesseVehicleBVRampValidCount_Cnt_M_u16	3452
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	12547
VitesseVehicleBVSigValidCount_Cnt_M_u16	20702
VitesseVehicleBV_Kph_M_f32	618.835571
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	24080
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	19171
VitesseVehiculeRoues_Kph_M_f32	203.369003
k_AASNTCEnableTimeout_mS_u16	38685
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	55997
k_AASNodeTimeout_mS_u16	2123
k_ABSNodeTimeout_mS_u16	37419
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	26133
k_ANGLEVOLANTSigValidThresh_Cnt_u16	42508
k_AngleVolantInvalidThresh_Cnt_u16	3747
k_AngleVolantValidThresh_Cnt_u16	51778
k_BSI552MsgTimeout_mS_u16	9786
k_BSINTCEnableTimeout_mS_u16	18050
k_BSINodeAbsentDiag_Cnt_str.Threshold	8538
k_BSINodeAbsentDiag_Cnt_str.PStep	56406
k_BSINodeAbsentDiag_Cnt_str.NStep	63670
k_BSINodeAbsentTimeout_mS_u16	21574
k_BSINodeTimeout_mS_u16	44992
k_BattOvHi_Volt_f32	7.27680016
k_BattOvLo_Volt_f32	10.9680004
k_BattUvHi_Volt_f32	24.9302998
k_BattUvLo_Volt_f32	28.1432991
k_CAVNTCEnableTimeout_mS_u16	56536
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	31877
k_CAVNodeTimeout_mS_u16	32148
k_CMM388MsgTimeout_mS_u16	50969
k_CMM388NTCEnableTimeout_mS_u16	11093
k_CMMNTCEnableTimeout_mS_u16	1464
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	21791
k_CONSANGLECPKMax_HwDeg_f32	435.31839
k_CONSANGLECPKMin_HwDeg_f32	-103.730202
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	18704
k_CONSANGLECPKSigValidThresh_Cnt_u16	30179
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	60017
k_CPKVehicleSpeedValidThresh_Cnt_u16	28895
k_CityParkInputInvalidThresh_Cnt_u16	38906
k_CityParkInputValidThresh_Cnt_u16	5814
k_ComputerRazGCTSigValidThresh_Cnt_u16	30918
k_CptTemporelSigValidThresh_Cnt_u16	35317
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	43879
k_DMDFCTCPKSigValidThresh_Cnt_u16	58002
k_DMDFCTCPKValidCount_Cnt_u16	59049
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	44813
k_DMDRELAXECPKSigValidThresh_Cnt_u16	19600
k_DMDRelaxeConsistentThresh_Cnt_u16	10422
k_DateValidThresh_Cnt_u16	53223
k_DefaultVehSpd_Kph_f32	29.1931992
k_DiagMuxOnAbsentTimeout_mS_u16	60012
k_EMNodeTimeout_mS_u16	47725
k_ESPNTCEnableTimeout_mS_u16	54691
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	43943
k_EtatMTSigInvalidThresh_Cnt_u16	58571
k_EtatMTSigValidThresh_Cnt_u16	19502
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	31076
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	15083
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	34343
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	45845
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	12676
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	25488
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	7519
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	8406
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	20942
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	55162
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	39928
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	9564
k_ISDATDIRASentDiag_Cnt_str.Threshold	1170

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	4955
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	1680
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	19017
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	206
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	33775
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	18516
k_ISDYNAASChkSumValidThresh_Cnt_u16	29815
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	16394
k_ISDYNAASMsgCountValidThresh_Cnt_u16	48773
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	57112
k_ISDYNAASMsgLenValidThresh_Cnt_u16	38415
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	60052
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	58245
k_ISDYNABRChkSumValidThresh_Cnt_u16	38192
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	43553
k_ISDYNABRMsgCountValidThresh_Cnt_u16	1148
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	49990
k_ISDYNABRMsgLenValidThresh_Cnt_u16	13821
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	31059
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	44956
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	34685
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	4770
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	63762
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	22061
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	442
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	22103
k_ISDYNVOLChkSumValidThresh_Cnt_u16	52726
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	34482
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	22075
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	48513
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	41512
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	14077
k_IgnOnTimeout_mS_u16	21395
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	148.367599
k_PowerCutVehSpdLowThresh_Kph_f32	68.2503967
k_PowerCutVehSpdLowTimeout_mS_u16	26313
k_VBattMaxAAS_Volt_f32	28.8568993
k_VBattMaxBSI_Volt_f32	30.7087002
k_VBattMaxCAV_Volt_f32	26.375
k_VBattMaxCMM388_Volt_f32	3.6178
k_VBattMaxCMM_Volt_f32	9.33320045
k_VBattMaxESP_Volt_f32	0.430200011
k_VBattMinAAS_Volt_f32	3.98749995
k_VBattMinBSI_Volt_f32	0.430200011
k_VBattMinCAV_Volt_f32	22.3904991
k_VBattMinCMM388_Volt_f32	9.2972002
k_VBattMinCMM_Volt_f32	2.76049995
k_VBattMinESP_Volt_f32	9.33320045
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	6947
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	32626
k_VitesseVehicleBVRampValidThresh_Cnt_u16	30364
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	37345
k_VitesseVehicleBVSigValidThresh_Cnt_u16	9631
k_VitesseVehicleBVSpeedPassThresh_kph_f32	160.223907
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	29543
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	11290
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2624129024
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	5937
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2287836416
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	156
target_SrlComInput_Per1_Batt_Volt_f32.value	29.5674992
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3368450048
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	213
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.135197476
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2432575488
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	188
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3008120832
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3807012864
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1742243840
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2316740608
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2443495424
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	25
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3330467840
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	57
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	93
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	161
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	179
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	193
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3483994112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	92
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	121
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2301700096
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	452937728
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2048747520
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	129
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	130
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	148
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	161
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	888797184
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	929
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.211473793
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	916981
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	203.146103
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	32818

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2287836416	2287836416	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2287836416	2287836416	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	208	208	✔
AngleVolantMsgTimer_mS_M_u32	2287836416	2287836416	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2287836416	2287836416	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2287836416	2287836416	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2287836416	2287836416	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2287836416	2287836416	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2287836416	2287836416	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2287836416	2287836416	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2287836416	2287836416	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2287836416	2287836416	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2287836416	2287836416	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2287836416	2287836416	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	49750	49750	✔
CONSANGLECPK_HwDeg_M_f32	-374.1091	-374.1091 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	49750	49750	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3041810432	3041810432	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	62952	62952	✔
CityParkInputConsistentCount_Cnt_M_u16	5814	5814	✔
CityParkInputInvalidCount_Cnt_M_u16	51778	51778	✔
CityParkInputMsgTimer_mS_M_u32	2287836416	2287836416	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2287836416	2287836416	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2287836416	2287836416	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2287836416	2287836416	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2287836416	2287836416	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2287836416	2287836416	✔
ESPNTCEnableTimer_mS_M_u32	2287836416	2287836416	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2287836416	2287836416	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2500	2500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3501	3501	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2287836416	2287836416	✔
ElecIntTimer_mS_M_u32[1]	14	14	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2287836416	2287836416	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2287836416	2287836416	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2287836416	2287836416	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2287836416	2287836416	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2287836416	2287836416	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1170	1170	✔
ISDATDIRASentTimer_mS_M_u32	2287836416	2287836416	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2287836416	2287836416	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2287836416	2287836416	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2287836416	2287836416	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2287836416	2287836416	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2287836416	2287836416	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2287836416	2287836416	✔
IgnOnTimer_mS_M_u32	3595839488	3595839488	✔
IgnTimeOff_Sec_M_u32	134599832	134599832	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2432575488	2432575488	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	188	188	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3008120832	3008120832	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	220	220	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3807012864	3807012864	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	174	174	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1742243840	1742243840	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2408015872	2408015872	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	132	132	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2443495424	2443495424	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	25	25	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3330467840	3330467840	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	0	0	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3483994112	3483994112	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	206	206	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2301700096	2301700096	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	452937728	452937728	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	132	132	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2048747520	2048747520	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	888797184	888797184	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	366.180786	366.180786	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	618.835571	618.835571	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	203.369003	203.369003	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	49750	49750	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	134599832	134599832	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-374.1091	-374.1091 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	29.1931992	29.1931992	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.418 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2695412480
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	1201
AASNodeAbsentTimer_mS_M_u32	2839571200
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	61639
ANGLEVOLANTSigValidCount_Cnt_M_u16	61750
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	10898
AngleVolantMsgTimer_mS_M_u32	2695412480
AngleVolantValidCount_Cnt_M_u16	33445
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	288566016
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3162745600
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2696141568
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2078382848
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	55706
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	139877120
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	15944
CAVNodeAbsentTimer_mS_M_u32	2347731712
CDD_SrlComVehSpd_Kph_G_f32	221.210693
CMM388NTCEnableTimer_mS_M_u32	2784545536
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1685949184
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	51050
CMMNodeAbsentTimer_mS_M_u32	735288064
CONSANGLECPKSigInvalidCount_Cnt_M_u16	64246
CONSANGLECPKSigValidCount_Cnt_M_u16	58613
CONSANGLECPK_Cnt_M_u16	16060
CONSANGLECPK_HwDeg_M_f32	-93.7089996
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	16060
CPKVehicleSpeedMsgTimer_mS_M_u32	1796455168
CPKVehicleSpeedValidCount_Cnt_M_u16	18989
CityParkInputConsistentCount_Cnt_M_u16	12633
CityParkInputInvalidCount_Cnt_M_u16	21432
CityParkInputMsgTimer_mS_M_u32	2432575488
CityParkInputValidCount_Cnt_M_u16	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	83127040
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	33125
ComputerRazGCTSigInvalidTimer_mS_M_u32	551160576
ComputerRazGCTSigValidCount_Cnt_M_u16	10322
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	45316
DMDFCTCPKSigValidCount_Cnt_M_u16	10235
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	11041
DMDRELAXECPKSigValidCount_Cnt_M_u16	6928
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	36311
DateInvalidTimer_mS_M_u32	3162745600
DiagMuxOnAbsentTimer_mS_M_u32	2910681856
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2078382848
ESPNTCEnableTimer_mS_M_u32	3516230400
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	63237
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	579
EffacDefaultDiagTimer_mS_M_u32[1]	990
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	19
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3029359360
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	41837
EtatMTSigValidCount_Cnt_M_u16	56376
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	50000
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	7375
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	17033
ISDAT4V2BSI552MsgTimer_mS_M_u32	2793904896
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	13821
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	5041
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	56376
ISDATBSI3F2MsgTimer_mS_M_u32	3710089984
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	52569
ISDATBSI412MsgLenValidCount_Cnt_M_u16	46332
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	41837
ISDATBSI412MsgTimer_mS_M_u32	1313782528
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	41246
ISDATBSI432MsgLenValidCount_Cnt_M_u16	28601
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	27709
ISDATDIRASentFltAcc_Cnt_M_u16	20033
ISDATDIRASentTimer_mS_M_u32	1796455168
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	65250
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	33445
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	37207
ISDYN2CMMMsgTimer_mS_M_u32	3892800256
ISDYNAASChkSumInvalidCount_Cnt_M_u16	15115
ISDYNAASChkSumValidCount_Cnt_M_u16	53018
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	57592
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	37199
ISDYNAASMsgLenValidCount_Cnt_M_u16	58934
ISDYNAASMsgTimeValidCount_Cnt_M_u16	15115
ISDYNAASMsgTimer_mS_M_u32	2890189568
ISDYNABRChkSumInvalidCount_Cnt_M_u16	1152
ISDYNABRChkSumValidCount_Cnt_M_u16	47063
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	40414
ISDYNABRMsgCountValidCount_Cnt_M_u16	47661
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	7369
ISDYNABRMsgLenValidCount_Cnt_M_u16	53000
ISDYNABRMsgTimeValidCount_Cnt_M_u16	16060
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	54528
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	6575
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	56376
ISDYNCMM208MsgTimer_mS_M_u32	2976656128

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	54528
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	6575
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	17227
ISDYNCMM388MsgTimer_mS_M_u32	831408896
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	17052
ISDYNVOLChkSumValidCount_Cnt_M_u16	48411
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	63402
ISDYNVOLMsgCountValidCount_Cnt_M_u16	16161
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	20274
ISDYNVOLMsgLenValidCount_Cnt_M_u16	34194
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	51050
ISDYNVOLMsgTimer_mS_M_u32	1126566656
IgnOnTimer_mS_M_u32	591547136
IgnTimeOff_Sec_M_u32	2775055351
ManVehSpd_Kph_M_f32	301.207001
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	24
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	103
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	923892480
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	147
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4024883968
PrevISDATBSI412MsgDLCError_Cnt_M_u08	117
PrevISDATBSI412MsgRxTime_MSec_M_u32	3081014016
PrevISDATBSI432MsgDLCError_Cnt_M_u08	64
PrevISDATBSI432MsgRxTime_MSec_M_u32	2373544704
PrevISDATDIRAMsgTxTime_MSec_M_u32	3567815424
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	168
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2940541696
PrevISDYNAASMsgDLCError_Cnt_M_u08	148
PrevISDYNAASMsgRxTime_MSec_M_u32	3947629312
PrevISDYNABRMsgDLCError_Cnt_M_u08	207
PrevISDYNABRMsgRxTime_MSec_M_u32	4275718912
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	4
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3338996480
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	69
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2822793984
PrevISDYNVOLMsgDLCError_Cnt_M_u08	133
PrevISDYNVOLMsgRxTime_MSec_M_u32	940935936
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3405036288
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	17.3512993
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	22005
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	64348
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	29090
VitesseVehicleBVRampValidCount_Cnt_M_u16	28361
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	3060
VitesseVehicleBVSigValidCount_Cnt_M_u16	1059
VitesseVehicleBV_Kph_M_f32	487.460785
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	17227
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	46227

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	107.111603
k_AASNTCEnableTimeout_mS_u16	40039
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	49476
k_AASNodeTimeout_mS_u16	31324
k_ABSNodeTimeout_mS_u16	57341
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	23037
k_ANGLEVOLANTSigValidThresh_Cnt_u16	25048
k_AngleVolantInvalidThresh_Cnt_u16	17427
k_AngleVolantValidThresh_Cnt_u16	21432
k_BSI552MsgTimeout_mS_u16	16014
k_BSINTCEnableTimeout_mS_u16	44214
k_BSINodeAbsentDiag_Cnt_str.Threshold	51817
k_BSINodeAbsentDiag_Cnt_str.PStep	30839
k_BSINodeAbsentDiag_Cnt_str.NStep	44488
k_BSINodeAbsentTimeout_mS_u16	4138
k_BSINodeTimeout_mS_u16	27709
k_BattOvHi_Volt_f32	26.4428005
k_BattOvLo_Volt_f32	0.230199993
k_BattUvHi_Volt_f32	18.2334003
k_BattUvLo_Volt_f32	13.6408005
k_CAVNTCEnableTimeout_mS_u16	62454
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	23022
k_CAVNodeTimeout_mS_u16	22850
k_CMM388MsgTimeout_mS_u16	50097
k_CMM388NTCEnableTimeout_mS_u16	34557
k_CMMNTCEnableTimeout_mS_u16	52629
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	34271
k_CONSANGLECPKMax_HwDeg_f32	417.721405
k_CONSANGLECPKMin_HwDeg_f32	-426.926697
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	33355
k_CONSANGLECPKSigValidThresh_Cnt_u16	13203
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	60394
k_CPKVehicleSpeedValidThresh_Cnt_u16	14624
k_CityParkInputInvalidThresh_Cnt_u16	0
k_CityParkInputValidThresh_Cnt_u16	12633
k_ComputerRazGCTSigValidThresh_Cnt_u16	11371
k_CptTemporelSigValidThresh_Cnt_u16	41119
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	56265
k_DMDFCTCPKSigValidThresh_Cnt_u16	52744
k_DMDFCTCPKValidCount_Cnt_u16	770
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	37207
k_DMDRELAXECPKSigValidThresh_Cnt_u16	45198
k_DMDRelaxeConsistentThresh_Cnt_u16	13340
k_DateValidThresh_Cnt_u16	17033
k_DefaultVehSpd_Kph_f32	39.9155006
k_DiagMuxOnAbsentTimeout_mS_u16	40570
k_EMNodeTimeout_mS_u16	18103
k_ESPNTCEnableTimeout_mS_u16	18068
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	41543
k_EtatMTSigInvalidThresh_Cnt_u16	2587
k_EtatMTSigValidThresh_Cnt_u16	19378
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	51985
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	36412
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	59142
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	31102
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	42482
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	25869
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	56351
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	39290
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	47826
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	36688

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	10643
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	41128
k_ISDATDIRASentDiag_Cnt_str.Threshold	6549
k_ISDATDIRASentDiag_Cnt_str.PStep	63930
k_ISDATDIRASentDiag_Cnt_str.NStep	24627
k_ISDATDIRASentTimeout_mS_u16	63692
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	9697
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	10898
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	27568
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	17280
k_ISDYNAASChkSumValidThresh_Cnt_u16	14039
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	23774
k_ISDYNAASMsgCountValidThresh_Cnt_u16	47405
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	36660
k_ISDYNAASMsgLenValidThresh_Cnt_u16	57616
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	46144
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	11119
k_ISDYNABRChkSumValidThresh_Cnt_u16	44590
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	39066
k_ISDYNABRMsgCountValidThresh_Cnt_u16	57673
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	18026
k_ISDYNABRMsgLenValidThresh_Cnt_u16	46597
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	40644
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	56489
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	60742
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	30551
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	44999
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	61494
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	36176
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	26808
k_ISDYNVOLChkSumValidThresh_Cnt_u16	27035
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	55270
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	41355
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	21689
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	11908
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	58695
k_IgnOnTimeout_mS_u16	24836
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	188.892502
k_PowerCutVehSpdLowThresh_Kph_f32	181.244095
k_PowerCutVehSpdLowTimeout_mS_u16	56675
k_VBattMaxAAS_Volt_f32	21.9034004
k_VBattMaxBSI_Volt_f32	16.1546001
k_VBattMaxCAV_Volt_f32	3.6644001
k_VBattMaxCMM388_Volt_f32	18.1175995
k_VBattMaxCMM_Volt_f32	22.3376007
k_VBattMaxESP_Volt_f32	15.1120005
k_VBattMinAAS_Volt_f32	4.69810009
k_VBattMinBSI_Volt_f32	15.1120005
k_VBattMinCAV_Volt_f32	24.8670998
k_VBattMinCMM388_Volt_f32	6.20340014
k_VBattMinCMM_Volt_f32	7.99230003
k_VBattMinESP_Volt_f32	22.3376007
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	39763
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	38438
k_VitesseVehicleBVRampValidThresh_Cnt_u16	13994
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	48155
k_VitesseVehicleBVSigValidThresh_Cnt_u16	59550
k_VitesseVehicleBVSpeedPassThresh_kph_f32	143.608002
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	32072
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	2799
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3162745600
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	12726
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	825879552
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSe	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	69
target_SrlComInput_Per1_Batt_Volt_f32.value	1.60940003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3106626304
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	44
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.908193827
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	457460480
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	159
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	349825792
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	645892864
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2016750336
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	838519552
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2077256448
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	11
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2109082368
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	145
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	234
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3301059328
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	63
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	97
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	105
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	151
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	174
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	175
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3198896896
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	163
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1774250752
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	213
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3974531840
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	126
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	134
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	182
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	202
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	203
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	227
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2727402240
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	9
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0900667757
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	235701
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	25.8068008
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	17127

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	825879552	825879552	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	825879552	825879552	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	10900	10900	✔
AngleVolantMsgTimer_mS_M_u32	825879552	825879552	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	825879552	825879552	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	825879552	825879552	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	825879552	825879552	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	825879552	825879552	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	825879552	825879552	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	825879552	825879552	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	825879552	825879552	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	825879552	825879552	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	825879552	825879552	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	825879552	825879552	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	16060	16060	✔
CONSANGLECPK_HwDeg_M_f32	-93.7089996	-93.7089996 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	16060	16060	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1796455168	1796455168	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	18989	18989	✔
CityParkInputConsistentCount_Cnt_M_u16	12633	12633	✔
CityParkInputInvalidCount_Cnt_M_u16	21432	21432	✔
CityParkInputMsgTimer_mS_M_u32	825879552	825879552	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	825879552	825879552	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	825879552	825879552	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	825879552	825879552	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	825879552	825879552	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	825879552	825879552	✔
ESPNTCEnableTimer_mS_M_u32	825879552	825879552	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	825879552	825879552	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	825879552	825879552	✔
EffacDefaultDiagTimer_mS_M_u32[1]	990	990	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	825879552	825879552	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	19	19	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	825879552	825879552	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	825879552	825879552	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	825879552	825879552	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	825879552	825879552	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	825879552	825879552	✔
ISDATDIRASentFltAcc_Cnt_M_u16	6549	6549	✔
ISDATDIRASentTimer_mS_M_u32	825879552	825879552	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	825879552	825879552	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	825879552	825879552	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	825879552	825879552	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	825879552	825879552	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	825879552	825879552	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	825879552	825879552	✔
IgnOnTimer_mS_M_u32	825879552	825879552	✔
IgnTimeOff_Sec_M_u32	2775055351	2775055351	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	457460480	457460480	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	159	159	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	349825792	349825792	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	64	64	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	645892864	645892864	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	12	12	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2016750336	2016750336	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3567815424	3567815424	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	202	202	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2077256448	2077256448	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	11	11	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2109082368	2109082368	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	153	153	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3301059328	3301059328	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	53	53	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3198896896	3198896896	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	163	163	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1774250752	1774250752	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	213	213	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3974531840	3974531840	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2727402240	2727402240	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	17.3512993	17.3512993	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	487.460785	487.460785	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	107.111603	107.111603	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	16060	16060	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2775055351	2775055351	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-93.7089996	-93.7089996 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.419 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2186318336
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	6199
AASNodeAbsentTimer_mS_M_u32	2739503616
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	52723
ANGLEVOLANTSigValidCount_Cnt_M_u16	50534
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	27284
AngleVolantMsgTimer_mS_M_u32	2186318336
AngleVolantValidCount_Cnt_M_u16	47321
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2792440320
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2256519680
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	380580352
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1814426112
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	8058
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2311565824
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	12273
CAVNodeAbsentTimer_mS_M_u32	532423168
CDD_SrlComVehSpd_Kph_G_f32	499.171692
CMM388NTCEnableTimer_mS_M_u32	2258657792
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1309811200
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	27210
CMMNodeAbsentTimer_mS_M_u32	2756702720
CONSANGLECPKSigInvalidCount_Cnt_M_u16	55911
CONSANGLECPKSigValidCount_Cnt_M_u16	21801
CONSANGLECPK_Cnt_M_u16	9172
CONSANGLECPK_HwDeg_M_f32	-55.0367012
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	9172
CPKVehicleSpeedMsgTimer_mS_M_u32	2400162304
CPKVehicleSpeedValidCount_Cnt_M_u16	44810

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	31933
CityParkInputInvalidCount_Cnt_M_u16	24226
CityParkInputMsgTimer_mS_M_u32	457460480
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1613595136
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	29211
ComputerRazGCTSigInvalidTimer_mS_M_u32	721199616
ComputerRazGCTSigValidCount_Cnt_M_u16	48082
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	30398
DMDFCTCPKSigValidCount_Cnt_M_u16	10904
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	1765
DMDRELAXECPKSigValidCount_Cnt_M_u16	12248
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	58820
DateInvalidTimer_mS_M_u32	2256519680
DiagMuxOnAbsentTimer_mS_M_u32	2664583680
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1814426112
ESPNTCEnableTimer_mS_M_u32	3192553984
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	33848
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1000
EffacDefaultDiagTimer_mS_M_u32[1]	2001
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	88
ElecIntTimer_mS_M_u32[1]	111
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3977884160
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	44867
EtatMTSigValidCount_Cnt_M_u16	28066
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	26969
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	38299
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	37614
ISDAT4V2BSI552MsgTimer_mS_M_u32	70513152
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	54033
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	17079
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	28066
ISDATBSI3F2MsgTimer_mS_M_u32	669012480
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	35327
ISDATBSI412MsgLenValidCount_Cnt_M_u16	39893
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	44867
ISDATBSI412MsgTimer_mS_M_u32	2438894080
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	44334
ISDATBSI432MsgLenValidCount_Cnt_M_u16	59932
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	47634
ISDATDIRASentFltAcc_Cnt_M_u16	9222
ISDATDIRASentTimer_mS_M_u32	2400162304
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	64354
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	47321
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	57797
ISDYN2CMMMsgTimer_mS_M_u32	3270803968
ISDYNAASChkSumInvalidCount_Cnt_M_u16	23849
ISDYNAASChkSumValidCount_Cnt_M_u16	6587
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	43488
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	4828
ISDYNAASMsgLenValidCount_Cnt_M_u16	60647
ISDYNAASMsgTimeValidCount_Cnt_M_u16	23849
ISDYNAASMsgTimer_mS_M_u32	2747032064
ISDYNABRChkSumInvalidCount_Cnt_M_u16	3656
ISDYNABRChkSumValidCount_Cnt_M_u16	36099
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	16560
ISDYNABRMsgCountValidCount_Cnt_M_u16	25730
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	33006
ISDYNABRMsgLenValidCount_Cnt_M_u16	41712
ISDYNABRMsgTimeValidCount_Cnt_M_u16	9172

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	46871
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	40397
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	28066
ISDYNCMM208MsgTimer_mS_M_u32	3922084352
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	46871
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	40397
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	36583
ISDYNCMM388MsgTimer_mS_M_u32	434102784
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	7029
ISDYNVOLChkSumValidCount_Cnt_M_u16	58551
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	47820
ISDYNVOLMsgCountValidCount_Cnt_M_u16	64806
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	28593
ISDYNVOLMsgLenValidCount_Cnt_M_u16	34132
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	27210
ISDYNVOLMsgTimer_mS_M_u32	4095255040
IgnOnTimer_mS_M_u32	348381696
IgnTimeOff_Sec_M_u32	2658477306
ManVehSpd_Kph_M_f32	40.6162987
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	37
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	55
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1377194496
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	32
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3038130688
PrevISDATBSI412MsgDLCError_Cnt_M_u08	212
PrevISDATBSI412MsgRxTime_MSec_M_u32	2963087872
PrevISDATBSI432MsgDLCError_Cnt_M_u08	14
PrevISDATBSI432MsgRxTime_MSec_M_u32	446595584
PrevISDATDIRAMsgTxTime_MSec_M_u32	1771119104
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	234
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3220926976
PrevISDYNAASMsgDLCError_Cnt_M_u08	31
PrevISDYNAASMsgRxTime_MSec_M_u32	329687552
PrevISDYNABRMsgDLCError_Cnt_M_u08	87
PrevISDYNABRMsgRxTime_MSec_M_u32	3791380992
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	215
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2759565824
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	84
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2789835264
PrevISDYNVOLMsgDLCError_Cnt_M_u08	40
PrevISDYNVOLMsgRxTime_MSec_M_u32	860496384
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	862753280
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	172.388702
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	56554
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	50549
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	32227
VitesseVehicleBVRampValidCount_Cnt_M_u16	24366
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	28780

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	32927
VitesseVehicleBV_Kph_M_f32	328.559387
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	36583
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	37841
VitesseVehiculeRoues_Kph_M_f32	442.793701
k_AASNTCEnableTimeout_mS_u16	30419
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	14588
k_AASNodeTimeout_mS_u16	18549
k_ABSNodeTimeout_mS_u16	3539
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	48785
k_ANGLEVOLANTSigValidThresh_Cnt_u16	20415
k_AngleVolantInvalidThresh_Cnt_u16	21774
k_AngleVolantValidThresh_Cnt_u16	24226
k_BSI552MsgTimeout_mS_u16	41440
k_BSINTCEnableTimeout_mS_u16	60006
k_BSINodeAbsentDiag_Cnt_str.Threshold	28766
k_BSINodeAbsentDiag_Cnt_str.PStep	41333
k_BSINodeAbsentDiag_Cnt_str.NStep	19647
k_BSINodeAbsentTimeout_mS_u16	6604
k_BSINodeTimeout_mS_u16	47634
k_BattOvHi_Volt_f32	17.7325001
k_BattOvLo_Volt_f32	11.7877998
k_BattUvHi_Volt_f32	5.6079998
k_BattUvLo_Volt_f32	4.24650002
k_CAVNTCEnableTimeout_mS_u16	62952
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	62719
k_CAVNodeTimeout_mS_u16	61315
k_CMM388MsgTimeout_mS_u16	56119
k_CMM388NTCEnableTimeout_mS_u16	49491
k_CMMNTCEnableTimeout_mS_u16	27721
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	20461
k_CONSANGLECPKMax_HwDeg_f32	169.390701
k_CONSANGLECPKMin_HwDeg_f32	-48.2831001
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	53735
k_CONSANGLECPKSigValidThresh_Cnt_u16	5841
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	43979
k_CPKVehicleSpeedValidThresh_Cnt_u16	8874
k_CityParkInputInvalidThresh_Cnt_u16	65535
k_CityParkInputValidThresh_Cnt_u16	31933
k_ComputerRazGCTSigValidThresh_Cnt_u16	10183
k_CptTemporelSigValidThresh_Cnt_u16	54253
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	17390
k_DMDFCTCPKSigValidThresh_Cnt_u16	42480
k_DMDFCTCPKValidCount_Cnt_u16	17218
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	57797
k_DMDRELAXECPKSigValidThresh_Cnt_u16	40159
k_DMDRelaxeConsistentThresh_Cnt_u16	51765
k_DateValidThresh_Cnt_u16	37614
k_DefaultVehSpd_Kph_f32	123.0457
k_DiagMuxOnAbsentTimeout_mS_u16	31898
k_EMNodeTimeout_mS_u16	15140
k_ESPNTCEnableTimeout_mS_u16	18189
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	39605
k_EtatMTSigInvalidThresh_Cnt_u16	10615
k_EtatMTSigValidThresh_Cnt_u16	64882
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	27222
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	2452
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	20406
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	19598
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	53236
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	37603

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	16427
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	45273
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	12306
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	33304
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	64527
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	23825
k_ISDATDIRASentDiag_Cnt_str.Threshold	25239
k_ISDATDIRASentDiag_Cnt_str.PStep	16638
k_ISDATDIRASentDiag_Cnt_str.NStep	16248
k_ISDATDIRASentTimeout_mS_u16	24932
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	61798
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	27284
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	18361
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	20808
k_ISDYNAASChkSumValidThresh_Cnt_u16	4099
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	944
k_ISDYNAASMsgCountValidThresh_Cnt_u16	26498
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	15916
k_ISDYNAASMsgLenValidThresh_Cnt_u16	58457
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	63623
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	27900
k_ISDYNABRChkSumValidThresh_Cnt_u16	7550
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	57978
k_ISDYNABRMsgCountValidThresh_Cnt_u16	301
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	60746
k_ISDYNABRMsgLenValidThresh_Cnt_u16	18232
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	29884
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	6350
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7736
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	64900
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	37107
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	51302
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	4570
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	62434
k_ISDYNVOLChkSumValidThresh_Cnt_u16	47608
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	42389
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	40935
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	52063
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	42686
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	8884
k_IgnOnTimeout_mS_u16	15102
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	204.614502
k_PowerCutVehSpdLowThresh_Kph_f32	203.559799
k_PowerCutVehSpdLowTimeout_mS_u16	41951
k_VBattMaxAAS_Volt_f32	19.4699993
k_VBattMaxBSI_Volt_f32	4.29659986
k_VBattMaxCAV_Volt_f32	19.2406998
k_VBattMaxCMM388_Volt_f32	5.3362999
k_VBattMaxCMM_Volt_f32	27.5776005
k_VBattMaxESP_Volt_f32	19.0580997
k_VBattMinAAS_Volt_f32	16.5265007
k_VBattMinBSI_Volt_f32	19.0580997
k_VBattMinCAV_Volt_f32	26.8857002
k_VBattMinCMM388_Volt_f32	25.7066994
k_VBattMinCMM_Volt_f32	7.80380011
k_VBattMinESP_Volt_f32	27.5776005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	55568
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	29014
k_VitesseVehicleBVRampValidThresh_Cnt_u16	64972
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	59319
k_VitesseVehicleBVSigValidThresh_Cnt_u16	43758
k_VitesseVehicleBVSpeedPassThresh_kph_f32	612.120911
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	29425
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	41660
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2256519680
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	42563
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3466657536
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	84
target_SrlComInput_Per1_Batt_Volt_f32.value	26.3957005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	189313536
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	233
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.992273092
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3032343040
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2793210368
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2416714240
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	4
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4184556032
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1788502528
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1805222400
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2221449728
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	50
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	68
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	132
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	188
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	198
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	211
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2277786112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	35
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	76
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	90
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	140
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	142
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	170
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	234
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	646504960
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	63439360
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2564235776
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	104
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	167
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	170
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3306697216
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1070
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.480095178
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	79035
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	178.121597
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	24084

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3466657536	3466657536	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
CDD_SrlComVehSpd_Kph_G_f32	40.6162987	40.6162987	✔
CMM388NTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	9172	9172	✔
CONSANGLECPK_HwDeg_M_f32	-55.0367012	-55.0367012 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3466657536	3466657536	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3466657536	3466657536	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3466657536	3466657536	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3466657536	3466657536	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3466657536	3466657536	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3466657536	3466657536	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3466657536	3466657536	✔
ESPNTCEnableTimer_mS_M_u32	3466657536	3466657536	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3466657536	3466657536	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	1000	1000	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2001	2001	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	88	88	✔
ElecIntTimer_mS_M_u32[1]	111	111	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3466657536	3466657536	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	37614	37614	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	28066	28066	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	44867	44867	✔
ISDATBSI412MsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	47634	47634	✔
ISDATBSI432MsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDATDIRASentFltAcc_Cnt_M_u16	25239	25239	✔
ISDATDIRASentTimer_mS_M_u32	3466657536	3466657536	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	57797	57797	✔
ISDYN2CMMMsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	23849	23849	✔
ISDYNAASMsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	9172	9172	✔
ISDYNABRMsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	28066	28066	✔
ISDYNCMM208MsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	36583	36583	✔
ISDYNCMM388MsgTimer_mS_M_u32	3466657536	3466657536	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	27210	27210	✔
ISDYNVOLMsgTimer_mS_M_u32	3466657536	3466657536	✔
IgnOnTimer_mS_M_u32	348381696	348381696	✔
IgnTimeOff_Sec_M_u32	2658477306	2658477306	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3032343040	3032343040	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	15	15	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2793210368	2793210368	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	43	43	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2416714240	2416714240	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	4	4	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4184556032	4184556032	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1771119104	1771119104	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	8	8	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1805222400	1805222400	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	68	68	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2221449728	2221449728	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	211	211	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2277786112	2277786112	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	234	234	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	646504960	646504960	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	63439360	63439360	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	198	198	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2564235776	2564235776	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3306697216	3306697216	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	172.388702	172.388702	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	328.559387	328.559387	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	442.793701	442.793701	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	9172	9172	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2658477306	2658477306	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-55.0367012	-55.0367012 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	40.6162987	40.6162987	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.420 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3983871232
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	58817
AASNodeAbsentTimer_mS_M_u32	3662298368
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	22156
ANGLEVOLANTSigValidCount_Cnt_M_u16	34292
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	41642
AngleVolantMsgTimer_mS_M_u32	3983871232
AngleVolantValidCount_Cnt_M_u16	46171
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	533921024
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3651632384
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1926835456
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3178556672
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	15863
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	462400768
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	20753
CAVNodeAbsentTimer_mS_M_u32	4151467264
CDD_SrlComVehSpd_Kph_G_f32	21.9414005
CMM388NTCEnableTimer_mS_M_u32	2747636992
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1148214528
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	8391
CMMNodeAbsentTimer_mS_M_u32	1022815488
CONSANGLECPKSigInvalidCount_Cnt_M_u16	45104
CONSANGLECPKSigValidCount_Cnt_M_u16	38313
CONSANGLECPK_Cnt_M_u16	38312
CONSANGLECPK_HwDeg_M_f32	604.015808
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	38312
CPKVehicleSpeedMsgTimer_mS_M_u32	2201488640
CPKVehicleSpeedValidCount_Cnt_M_u16	2927
CityParkInputConsistentCount_Cnt_M_u16	63663
CityParkInputInvalidCount_Cnt_M_u16	30719
CityParkInputMsgTimer_mS_M_u32	3032343040
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	866008320
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	26645

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2008079616
ComputerRazGCTSigValidCount_Cnt_M_u16	53104
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	40875
DMDFCTCPKSigValidCount_Cnt_M_u16	14812
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	62390
DMDRELAXECPKSigValidCount_Cnt_M_u16	36510
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	16921
DateInvalidTimer_mS_M_u32	3651632384
DiagMuxOnAbsentTimer_mS_M_u32	3471822080
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3178556672
ESPNTCEnableTimer_mS_M_u32	3443997952
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	55484
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	2500
EffacDefaultDiagTimer_mS_M_u32[1]	3501
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1
ElecIntTimer_mS_M_u32[1]	14
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3113856256
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	50907
EtatMTSigValidCount_Cnt_M_u16	20864
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	19290
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	7251
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	55514
ISDAT4V2BSI552MsgTimer_mS_M_u32	2907368704
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	51443
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	24512
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	20864
ISDATBSI3F2MsgTimer_mS_M_u32	3955608832
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	11560
ISDATBSI412MsgLenValidCount_Cnt_M_u16	40293
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	50907
ISDATBSI412MsgTimer_mS_M_u32	2018184448
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	59419
ISDATBSI432MsgLenValidCount_Cnt_M_u16	14096
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	30382
ISDATDIRASentFltAcc_Cnt_M_u16	2258
ISDATDIRASentTimer_mS_M_u32	2201488640
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	50942
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	46171
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	14998
ISDYN2CMMMsgTimer_mS_M_u32	3880336640
ISDYNAASChkSumInvalidCount_Cnt_M_u16	24299
ISDYNAASChkSumValidCount_Cnt_M_u16	48884
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	48454
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	5200
ISDYNAASMsgLenValidCount_Cnt_M_u16	64497
ISDYNAASMsgTimeValidCount_Cnt_M_u16	24299
ISDYNAASMsgTimer_mS_M_u32	3161562368
ISDYNABRChkSumInvalidCount_Cnt_M_u16	8971
ISDYNABRChkSumValidCount_Cnt_M_u16	56476
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	36950
ISDYNABRMsgCountValidCount_Cnt_M_u16	47775
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	39067
ISDYNABRMsgLenValidCount_Cnt_M_u16	34900
ISDYNABRMsgTimeValidCount_Cnt_M_u16	38312
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	6574
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	18254
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	20864
ISDYNCMM208MsgTimer_mS_M_u32	3922984192
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	6574
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	18254
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	59953

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1208425728
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	42246
ISDYNVOLChkSumValidCount_Cnt_M_u16	40703
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	35713
ISDYNVOLMsgCountValidCount_Cnt_M_u16	31282
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	14929
ISDYNVOLMsgLenValidCount_Cnt_M_u16	53033
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	8391
ISDYNVOLMsgTimer_mS_M_u32	2354896128
IgnOnTimer_mS_M_u32	3881508096
IgnTimeOff_Sec_M_u32	2487010905
ManVehSpd_Kph_M_f32	84.2863998
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	38
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	181
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3307457792
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	176
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4087622912
PrevISDATBSI412MsgDLCError_Cnt_M_u08	129
PrevISDATBSI412MsgRxTime_MSec_M_u32	147807488
PrevISDATBSI432MsgDLCError_Cnt_M_u08	255
PrevISDATBSI432MsgRxTime_MSec_M_u32	139148544
PrevISDATDIRAMsgTxTime_MSec_M_u32	2918407424
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	53
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4159991040
PrevISDYNAASMsgDLCError_Cnt_M_u08	165
PrevISDYNAASMsgRxTime_MSec_M_u32	3853704448
PrevISDYNABRMsgDLCError_Cnt_M_u08	71
PrevISDYNABRMsgRxTime_MSec_M_u32	1605573888
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	102
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3342064896
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	56
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3511303424
PrevISDYNVOLMsgDLCError_Cnt_M_u08	0
PrevISDYNVOLMsgRxTime_MSec_M_u32	1959288064
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1243680000
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	535.673523
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	28198
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	10823
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	44859
VitesseVehicleBVRampValidCount_Cnt_M_u16	33052
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	37665
VitesseVehicleBVSigValidCount_Cnt_M_u16	30793
VitesseVehicleBV_Kph_M_f32	618.384521
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	59953
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	53553
VitesseVehiculeRoues_Kph_M_f32	74.4209976
k_AASNTCEnableTimeout_mS_u16	22699
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	32754
k_AASNodeTimeout_mS_u16	41287
k_ABSNodeTimeout_mS_u16	28268
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	65522
k_ANGLEVOLANTSigValidThresh_Cnt_u16	21031
k_AngleVolantInvalidThresh_Cnt_u16	15930
k_AngleVolantValidThresh_Cnt_u16	30719
k_BSI552MsgTimeout_mS_u16	41732
k_BSINTCEnableTimeout_mS_u16	4211
k_BSINodeAbsentDiag_Cnt_str.Threshold	8538
k_BSINodeAbsentDiag_Cnt_str.PStep	56406
k_BSINodeAbsentDiag_Cnt_str.NStep	63670
k_BSINodeAbsentTimeout_mS_u16	29954
k_BSINodeTimeout_mS_u16	30382
k_BattOvHi_Volt_f32	1.09430003
k_BattOvLo_Volt_f32	12.6757002
k_BattUvHi_Volt_f32	17.7264004
k_BattUvLo_Volt_f32	2.22860003
k_CAVNTCEnableTimeout_mS_u16	18989
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	47591
k_CAVNodeTimeout_mS_u16	57564
k_CMM388MsgTimeout_mS_u16	40129
k_CMM388NTCEnableTimeout_mS_u16	23149
k_CMMNTCEnableTimeout_mS_u16	56651
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	3293
k_CONSANGLECPKMax_HwDeg_f32	402.185303
k_CONSANGLECPKMin_HwDeg_f32	-45.9387016
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	8497
k_CONSANGLECPKSigValidThresh_Cnt_u16	18481
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	20293
k_CPKVehicleSpeedValidThresh_Cnt_u16	53031
k_CityParkInputInvalidThresh_Cnt_u16	64200
k_CityParkInputValidThresh_Cnt_u16	63663
k_ComputerRazGCTSigValidThresh_Cnt_u16	8913
k_CptTemporelSigValidThresh_Cnt_u16	1054
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	20379
k_DMDFCTCPKSigValidThresh_Cnt_u16	32596
k_DMDFCTCPKValidCount_Cnt_u16	62111
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	14998
k_DMDRELAXECPKSigValidThresh_Cnt_u16	48903
k_DMDRelaxeConsistentThresh_Cnt_u16	3845
k_DateValidThresh_Cnt_u16	55514
k_DefaultVehSpd_Kph_f32	87.7643967
k_DiagMuxOnAbsentTimeout_mS_u16	9046
k_EMNodeTimeout_mS_u16	49657
k_ESPNTCEnableTimeout_mS_u16	31677
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	19589
k_EtatMTSigInvalidThresh_Cnt_u16	19838
k_EtatMTSigValidThresh_Cnt_u16	1871
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	65444
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	26537
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	41924
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	36988
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	60425
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	41596
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	25380
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	5849
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	61295
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	35548
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	17081
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	52466
k_ISDATDIRASentDiag_Cnt_str.Threshold	93

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	55293
k_ISDATDIRASentDiag_Cnt_str.NStep	55204
k_ISDATDIRASentTimeout_mS_u16	39351
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	41971
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	41642
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10681
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	23051
k_ISDYNAASChkSumValidThresh_Cnt_u16	21404
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	18262
k_ISDYNAASMsgCountValidThresh_Cnt_u16	45471
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	9055
k_ISDYNAASMsgLenValidThresh_Cnt_u16	23963
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	30671
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	35953
k_ISDYNABRChkSumValidThresh_Cnt_u16	53418
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	62711
k_ISDYNABRMsgCountValidThresh_Cnt_u16	44703
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	38855
k_ISDYNABRMsgLenValidThresh_Cnt_u16	36796
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	20466
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	19066
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	38013
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	32282
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	3468
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	31988
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	15959
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	15231
k_ISDYNVOLChkSumValidThresh_Cnt_u16	36604
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	10405
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	13296
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	57991
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	5676
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	49544
k_IgnOnTimeout_mS_u16	54827
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	49.5578003
k_PowerCutVehSpdLowThresh_Kph_f32	124.721901
k_PowerCutVehSpdLowTimeout_mS_u16	391
k_VBattMaxAAS_Volt_f32	3.83909988
k_VBattMaxBSI_Volt_f32	14.6189003
k_VBattMaxCAV_Volt_f32	4.36569977
k_VBattMaxCMM388_Volt_f32	23.7138004
k_VBattMaxCMM_Volt_f32	17.2856998
k_VBattMaxESP_Volt_f32	1.43330002
k_VBattMinAAS_Volt_f32	11.3481998
k_VBattMinBSI_Volt_f32	1.43330002
k_VBattMinCAV_Volt_f32	31.6721001
k_VBattMinCMM388_Volt_f32	8.71879959
k_VBattMinCMM_Volt_f32	1.03579998
k_VBattMinESP_Volt_f32	17.2856998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	5365
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	45537
k_VitesseVehicleBVRampValidThresh_Cnt_u16	49793
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	38399
k_VitesseVehicleBVSigValidThresh_Cnt_u16	29212
k_VitesseVehicleBVSpeedPassThresh_kph_f32	42.6705017
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	34833
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	28274
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3651632384
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	27719
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	511165952
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	56
target_SrlComInput_Per1_Batt_Volt_f32.value	7.30049992
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3675041024
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	155
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.361696452
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	160
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1869421824
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4272930048
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	89
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3867303168
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2397371648
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1607965952
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	80
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3243916544
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	160
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	460119296
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	45
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	134
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	183
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	190
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2279210240
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	37
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	130
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	194
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	236
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	101457152
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3536764160
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	115
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3089194240
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	66
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	82
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	151
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1268657408
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1537
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.283417284
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	320651
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	140.286606
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	4776

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	511165952	511165952	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	511165952	511165952	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	511165952	511165952	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	511165952	511165952	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	511165952	511165952	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	511165952	511165952	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	511165952	511165952	✔
CDD_SrlComVehSpd_Kph_G_f32	84.2863998	84.2863998	✔
CMM388NTCEnableTimer_mS_M_u32	511165952	511165952	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	511165952	511165952	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	511165952	511165952	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	38312	38312	✔
CONSANGLECPK_HwDeg_M_f32	604.015808	604.015808 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	511165952	511165952	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	511165952	511165952	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	511165952	511165952	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	511165952	511165952	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	511165952	511165952	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	511165952	511165952	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	511165952	511165952	✔
ESPNTCEnableTimer_mS_M_u32	511165952	511165952	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	511165952	511165952	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2500	2500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3501	3501	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1	1	✔
ElecIntTimer_mS_M_u32[1]	14	14	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	511165952	511165952	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	55514	55514	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	20864	20864	✔
ISDATBSI3F2MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	50907	50907	✔
ISDATBSI412MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	30382	30382	✔
ISDATBSI432MsgTimer_mS_M_u32	511165952	511165952	✔
ISDATDIRASentFltAcc_Cnt_M_u16	93	93	✔
ISDATDIRASentTimer_mS_M_u32	511165952	511165952	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	14998	14998	✔
ISDYN2CMMMsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	24299	24299	✔
ISDYNAASMsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	38312	38312	✔
ISDYNABRMsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	20864	20864	✔
ISDYNCMM208MsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	59953	59953	✔
ISDYNCMM388MsgTimer_mS_M_u32	511165952	511165952	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	8391	8391	✔
ISDYNVOLMsgTimer_mS_M_u32	511165952	511165952	✔
IgnOnTimer_mS_M_u32	3881508096	3881508096	✔
IgnTimeOff_Sec_M_u32	2487010905	2487010905	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	160	160	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1869421824	1869421824	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	170	170	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4272930048	4272930048	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	89	89	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3867303168	3867303168	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	20	20	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2397371648	2397371648	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2918407424	2918407424	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	80	80	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3243916544	3243916544	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	160	160	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	460119296	460119296	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	74	74	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2279210240	2279210240	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	64	64	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	101457152	101457152	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	167	167	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3536764160	3536764160	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	115	115	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3089194240	3089194240	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1268657408	1268657408	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	535.673523	535.673523	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	618.384521	618.384521	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	74.4209976	74.4209976	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	38312	38312	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2487010905	2487010905	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	604.015808	604.015808 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.421 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3954416640
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	54478
AASNodeAbsentTimer_mS_M_u32	905186304
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	52334
ANGLEVOLANTSigValidCount_Cnt_M_u16	64756
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	33299
AngleVolantMsgTimer_mS_M_u32	3954416640
AngleVolantValidCount_Cnt_M_u16	22401
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2019150848
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1021070336
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2483502080
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3543399424
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	33325
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2481175552
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	31581
CAVNodeAbsentTimer_mS_M_u32	654027776
CDD_SrlComVehSpd_Kph_G_f32	14.4833002
CMM388NTCEnableTimer_mS_M_u32	2130832384
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3087117312
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	36859
CMMNodeAbsentTimer_mS_M_u32	3702389760
CONSANGLECPKSigInvalidCount_Cnt_M_u16	17024
CONSANGLECPKSigValidCount_Cnt_M_u16	37078
CONSANGLECPK_Cnt_M_u16	19673
CONSANGLECPK_HwDeg_M_f32	106.587799
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	19673
CPKVehicleSpeedMsgTimer_mS_M_u32	4134181888
CPKVehicleSpeedValidCount_Cnt_M_u16	17740
CityParkInputConsistentCount_Cnt_M_u16	55941
CityParkInputInvalidCount_Cnt_M_u16	60820
CityParkInputMsgTimer_mS_M_u32	1869421824
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2046299136
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	40402

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3225431040
ComputerRazGCTSigValidCount_Cnt_M_u16	39490
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	9872
DMDFCTCPKSigValidCount_Cnt_M_u16	14014
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	7408
DMDRELAXECPKSigValidCount_Cnt_M_u16	2806
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	28869
DateInvalidTimer_mS_M_u32	1021070336
DiagMuxOnAbsentTimer_mS_M_u32	2722323456
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3543399424
ESPNTCEnableTimer_mS_M_u32	2432502784
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	22237
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	579
EffacDefaultDiagTimer_mS_M_u32[1]	990
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	19
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1640348672
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	16063
EtatMTSigValidCount_Cnt_M_u16	19857
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	39170
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	9432
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	53700
ISDAT4V2BSI552MsgTimer_mS_M_u32	3685874688
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	61431
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	31313
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	19857
ISDATBSI3F2MsgTimer_mS_M_u32	599874560
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	10327
ISDATBSI412MsgLenValidCount_Cnt_M_u16	58977
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	16063
ISDATBSI412MsgTimer_mS_M_u32	590453760
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	35327
ISDATBSI432MsgLenValidCount_Cnt_M_u16	35809
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	48774
ISDATDIRASentFltAcc_Cnt_M_u16	38938
ISDATDIRASentTimer_mS_M_u32	4134181888
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	37079
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	22401
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	49615
ISDYN2CMMMsgTimer_mS_M_u32	3405188096
ISDYNAASChkSumInvalidCount_Cnt_M_u16	37200
ISDYNAASChkSumValidCount_Cnt_M_u16	45046
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	43200
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	60832
ISDYNAASMsgLenValidCount_Cnt_M_u16	54654
ISDYNAASMsgTimeValidCount_Cnt_M_u16	37200
ISDYNAASMsgTimer_mS_M_u32	3841846272
ISDYNABRChkSumInvalidCount_Cnt_M_u16	48750
ISDYNABRChkSumValidCount_Cnt_M_u16	61564
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	26895
ISDYNABRMsgCountValidCount_Cnt_M_u16	10485
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	62783
ISDYNABRMsgLenValidCount_Cnt_M_u16	9429
ISDYNABRMsgTimeValidCount_Cnt_M_u16	19673
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	54528
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	6575
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	19857
ISDYNCMM208MsgTimer_mS_M_u32	1582746624
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	54528
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	6575
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	36351

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2017291264
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	15358
ISDYNVOLChkSumValidCount_Cnt_M_u16	19668
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	15118
ISDYNVOLMsgCountValidCount_Cnt_M_u16	19900
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	50718
ISDYNVOLMsgLenValidCount_Cnt_M_u16	34388
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	36859
ISDYNVOLMsgTimer_mS_M_u32	842804224
IgnOnTimer_mS_M_u32	3930156032
IgnTimeOff_Sec_M_u32	2773372721
ManVehSpd_Kph_M_f32	485.711304
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	39
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	223
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2410109952
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	202
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4255529984
PrevISDATBSI412MsgDLCError_Cnt_M_u08	142
PrevISDATBSI412MsgRxTime_MSec_M_u32	2800004096
PrevISDATBSI432MsgDLCError_Cnt_M_u08	140
PrevISDATBSI432MsgRxTime_MSec_M_u32	4025551872
PrevISDATDIRAMsgTxTime_MSec_M_u32	1199090688
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	139
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2176154624
PrevISDYNAASMsgDLCError_Cnt_M_u08	19
PrevISDYNAASMsgRxTime_MSec_M_u32	4265225216
PrevISDYNABRMsgDLCError_Cnt_M_u08	82
PrevISDYNABRMsgRxTime_MSec_M_u32	3778636800
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	19
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2646027264
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	201
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1358171136
PrevISDYNVOLMsgDLCError_Cnt_M_u08	166
PrevISDYNVOLMsgRxTime_MSec_M_u32	2264509440
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2242878464
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	529.477295
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	47134
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	8828
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	35039
VitesseVehicleBVRampValidCount_Cnt_M_u16	45565
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	43695
VitesseVehicleBVSigValidCount_Cnt_M_u16	47605
VitesseVehicleBV_Kph_M_f32	596.69519
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	36351
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	63421
VitesseVehiculeRoues_Kph_M_f32	207.007095
k_AASNTCEnableTimeout_mS_u16	53200
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	4284
k_AASNodeTimeout_mS_u16	48508
k_ABSNodeTimeout_mS_u16	65101
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	24186
k_ANGLEVOLANTSigValidThresh_Cnt_u16	22172
k_AngleVolantInvalidThresh_Cnt_u16	40547
k_AngleVolantValidThresh_Cnt_u16	60820
k_BSI552MsgTimeout_mS_u16	36420
k_BSINTCEnableTimeout_mS_u16	28919
k_BSINodeAbsentDiag_Cnt_str.Threshold	51817
k_BSINodeAbsentDiag_Cnt_str.PStep	30839
k_BSINodeAbsentDiag_Cnt_str.NStep	44488
k_BSINodeAbsentTimeout_mS_u16	27403
k_BSINodeTimeout_mS_u16	48774
k_BattOvHi_Volt_f32	31.0354996
k_BattOvLo_Volt_f32	15.0485001
k_BattUvHi_Volt_f32	7.86269999
k_BattUvLo_Volt_f32	15.6037998
k_CAVNTCEnableTimeout_mS_u16	44810
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	6363
k_CAVNodeTimeout_mS_u16	24700
k_CMM388MsgTimeout_mS_u16	45006
k_CMM388NTCEnableTimeout_mS_u16	9930
k_CMMNTCEnableTimeout_mS_u16	4847
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	62649
k_CONSANGLECPKMax_HwDeg_f32	20.0816002
k_CONSANGLECPKMin_HwDeg_f32	-780
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	59647
k_CONSANGLECPKSigValidThresh_Cnt_u16	37565
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	11138
k_CPKVehicleSpeedValidThresh_Cnt_u16	65114
k_CityParkInputInvalidThresh_Cnt_u16	11508
k_CityParkInputValidThresh_Cnt_u16	55941
k_ComputerRazGCTSigValidThresh_Cnt_u16	55901
k_CptTemporelSigValidThresh_Cnt_u16	34103
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	53311
k_DMDFCTCPKSigValidThresh_Cnt_u16	16341
k_DMDFCTCPKValidCount_Cnt_u16	1077
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	49615
k_DMDRELAXECPKSigValidThresh_Cnt_u16	4925
k_DMDRelaxeConsistentThresh_Cnt_u16	39747
k_DateValidThresh_Cnt_u16	53700
k_DefaultVehSpd_Kph_f32	175.280197
k_DiagMuxOnAbsentTimeout_mS_u16	56271
k_EMNodeTimeout_mS_u16	28965
k_ESPNTCEnableTimeout_mS_u16	43865
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	54721
k_EtatMTSigInvalidThresh_Cnt_u16	51989
k_EtatMTSigValidThresh_Cnt_u16	64611
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	22117
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	19735
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	27974
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	64860
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	14710
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	6235
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	31972
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	20614
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	50179
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	15677
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	42087
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	65020
k_ISDATDIRASentDiag_Cnt_str.Threshold	11630

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	28093
k_ISDATDIRASentDiag_Cnt_str.NStep	10447
k_ISDATDIRASentTimeout_mS_u16	2666
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	48377
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	33299
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	37221
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	6510
k_ISDYNAASChkSumValidThresh_Cnt_u16	35708
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	17423
k_ISDYNAASMsgCountValidThresh_Cnt_u16	17397
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	3442
k_ISDYNAASMsgLenValidThresh_Cnt_u16	55424
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	34212
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	61885
k_ISDYNABRChkSumValidThresh_Cnt_u16	9171
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	23853
k_ISDYNABRMsgCountValidThresh_Cnt_u16	61171
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	11003
k_ISDYNABRMsgLenValidThresh_Cnt_u16	12765
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	5882
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	29474
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	34392
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	13059
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	42862
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	6132
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	64140
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	6482
k_ISDYNVOLChkSumValidThresh_Cnt_u16	11676
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	19234
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	14976
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	39867
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	44941
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	20410
k_IgnOnTimeout_mS_u16	63822
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	182.399796
k_PowerCutVehSpdLowThresh_Kph_f32	252.9077
k_PowerCutVehSpdLowTimeout_mS_u16	17724
k_VBattMaxAAS_Volt_f32	1.96290004
k_VBattMaxBSI_Volt_f32	7.8441
k_VBattMaxCAV_Volt_f32	0.866299987
k_VBattMaxCMM388_Volt_f32	9.91769981
k_VBattMaxCMM_Volt_f32	13.3142996
k_VBattMaxESP_Volt_f32	20.1051998
k_VBattMinAAS_Volt_f32	16.3994007
k_VBattMinBSI_Volt_f32	20.1051998
k_VBattMinCAV_Volt_f32	32
k_VBattMinCMM388_Volt_f32	15.5543003
k_VBattMinCMM_Volt_f32	24.7779007
k_VBattMinESP_Volt_f32	13.3142996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	61939
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	59884
k_VitesseVehicleBVRampValidThresh_Cnt_u16	38414
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	26580
k_VitesseVehicleBVSigValidThresh_Cnt_u16	25150
k_VitesseVehicleBVSpeedPassThresh_kph_f32	186.245407
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	54877
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	49659
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1021070336
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	201
target_SrlComInput_Per1_Batt_Volt_f32.value	8.79520035
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2305604608
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	57
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.250939131
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	436956160
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	138
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1053002752
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	112
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2580261888
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	114
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4079209472
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	315354112
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3234073600
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3305909248
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	25
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	63
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	167
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	250
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	226
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	474270720
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	32
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	46
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	166
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	202
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2452515840
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4268133376
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1626254336
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	43
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	204
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1572355072
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1349
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.935291111
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	456744
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	132.463593
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	21144

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	485.711304	485.711304	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	19673	19673	✔
CONSANGLECPK_HwDeg_M_f32	106.587799	106.587799 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3251510528	3251510528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	579	579	✔
EffacDefaultDiagTimer_mS_M_u32[1]	990	990	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	6	6	✔
ElecIntTimer_mS_M_u32[1]	19	19	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	53700	53700	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	19857	19857	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	16063	16063	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	48774	48774	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11630	11630	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	49615	49615	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	37200	37200	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	19673	19673	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	19857	19857	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	36351	36351	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	36859	36859	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	3930156032	3930156032	✔
IgnTimeOff_Sec_M_u32	2773372721	2773372721	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	245	245	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	436956160	436956160	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	138	138	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1053002752	1053002752	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	112	112	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2580261888	2580261888	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	114	114	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4079209472	4079209472	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1199090688	1199090688	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3234073600	3234073600	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3305909248	3305909248	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	226	226	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	474270720	474270720	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	81	81	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2452515840	2452515840	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	206	206	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4268133376	4268133376	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	92	92	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1626254336	1626254336	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1572355072	1572355072	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	529.477295	529.477295	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	596.69519	596.69519	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	207.007095	207.007095	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	19673	19673	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2773372721	2773372721	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	106.587799	106.587799 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	485.711304	485.711304	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.422 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3790860032
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	45220
AASNodeAbsentTimer_mS_M_u32	3505561344
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	60354
ANGLEVOLANTSigValidCount_Cnt_M_u16	7665
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	64725
AngleVolantMsgTimer_mS_M_u32	3790860032
AngleVolantValidCount_Cnt_M_u16	23819
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3502333696
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2906251008
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1064898304
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	619892480
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	34437
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1373867776
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	885
CAVNodeAbsentTimer_mS_M_u32	609992448
CDD_SrlComVehSpd_Kph_G_f32	211.1577
CMM388NTCEnableTimer_mS_M_u32	88669952
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	155827968
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	14938
CMMNodeAbsentTimer_mS_M_u32	1887751936
CONSANGLECPKSigInvalidCount_Cnt_M_u16	141
CONSANGLECPKSigValidCount_Cnt_M_u16	6475
CONSANGLECPK_Cnt_M_u16	45378
CONSANGLECPK_HwDeg_M_f32	-206.1297
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	45378
CPKVehicleSpeedMsgTimer_mS_M_u32	1573842688
CPKVehicleSpeedValidCount_Cnt_M_u16	55952
CityParkInputConsistentCount_Cnt_M_u16	58367
CityParkInputInvalidCount_Cnt_M_u16	63441
CityParkInputMsgTimer_mS_M_u32	436956160
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	350658304
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	26008

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	177094400
ComputerRazGCTSigValidCount_Cnt_M_u16	55496
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	15581
DMDFCTCPKSigValidCount_Cnt_M_u16	28691
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	33340
DMDRELAXECPKSigValidCount_Cnt_M_u16	31723
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	51646
DateInvalidTimer_mS_M_u32	2906251008
DiagMuxOnAbsentTimer_mS_M_u32	2906959616
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	619892480
ESPNTCEnableTimer_mS_M_u32	601333504
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	6517
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1000
EffacDefaultDiagTimer_mS_M_u32[1]	2001
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	88
ElecIntTimer_mS_M_u32[1]	111
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4030566144
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	19217
EtatMTSigValidCount_Cnt_M_u16	4699
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	34055
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	58693
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	14081
ISDAT4V2BSI552MsgTimer_mS_M_u32	2205732608
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	4328
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	34202
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	4699
ISDATBSI3F2MsgTimer_mS_M_u32	2697637632
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	14535
ISDATBSI412MsgLenValidCount_Cnt_M_u16	53865
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	19217
ISDATBSI412MsgTimer_mS_M_u32	3011112704
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	23630
ISDATBSI432MsgLenValidCount_Cnt_M_u16	35433
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	7674
ISDATDIRASentFltAcc_Cnt_M_u16	57662
ISDATDIRASentTimer_mS_M_u32	1573842688
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	23880
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	23819
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	10016
ISDYN2CMMMsgTimer_mS_M_u32	3723075328
ISDYNAASChkSumInvalidCount_Cnt_M_u16	798
ISDYNAASChkSumValidCount_Cnt_M_u16	60140
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	9550
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	30892
ISDYNAASMsgLenValidCount_Cnt_M_u16	58578
ISDYNAASMsgTimeValidCount_Cnt_M_u16	798
ISDYNAASMsgTimer_mS_M_u32	3277127424
ISDYNABRChkSumInvalidCount_Cnt_M_u16	3905
ISDYNABRChkSumValidCount_Cnt_M_u16	23767
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	14305
ISDYNABRMsgCountValidCount_Cnt_M_u16	15343
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	42064
ISDYNABRMsgLenValidCount_Cnt_M_u16	6478
ISDYNABRMsgTimeValidCount_Cnt_M_u16	45378
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	46871
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	40397
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	4699
ISDYNCMM208MsgTimer_mS_M_u32	1388994304
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	46871
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	40397
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	12689

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1737916160
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	35859
ISDYNVOLChkSumValidCount_Cnt_M_u16	23889
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	30563
ISDYNVOLMsgCountValidCount_Cnt_M_u16	41753
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	4018
ISDYNVOLMsgLenValidCount_Cnt_M_u16	21200
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	14938
ISDYNVOLMsgTimer_mS_M_u32	2761572096
IgnOnTimer_mS_M_u32	562724608
IgnTimeOff_Sec_M_u32	1603044431
ManVehSpd_Kph_M_f32	104.385201
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	37
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	34
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1964551936
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	205
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1050414848
PrevISDATBSI412MsgDLCError_Cnt_M_u08	217
PrevISDATBSI412MsgRxTime_MSec_M_u32	2292236032
PrevISDATBSI432MsgDLCError_Cnt_M_u08	122
PrevISDATBSI432MsgRxTime_MSec_M_u32	3606814464
PrevISDATDIRAMsgTxTime_MSec_M_u32	4142186240
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	151
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4285419264
PrevISDYNAASMsgDLCError_Cnt_M_u08	128
PrevISDYNAASMsgRxTime_MSec_M_u32	3097509632
PrevISDYNABRMsgDLCError_Cnt_M_u08	81
PrevISDYNABRMsgRxTime_MSec_M_u32	480411392
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	173
PrevISDYNCMM208MsgRxTime_MSec_M_u32	237584128
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	16
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2146606848
PrevISDYNVOLMsgDLCError_Cnt_M_u08	212
PrevISDYNVOLMsgRxTime_MSec_M_u32	2086780672
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	67104512
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	373.685394
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	37170
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	30168
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	25327
VitesseVehicleBVRampValidCount_Cnt_M_u16	2901
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	38143
VitesseVehicleBVSigValidCount_Cnt_M_u16	10990
VitesseVehicleBV_Kph_M_f32	538.65918
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	12689
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	38935
VitesseVehiculeRoues_Kph_M_f32	552.718994
k_AASNTCEnableTimeout_mS_u16	50269
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	56666
k_AASNodeTimeout_mS_u16	42200
k_ABSNodeTimeout_mS_u16	59814
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	35549
k_ANGLEVOLANTSigValidThresh_Cnt_u16	54840
k_AngleVolantInvalidThresh_Cnt_u16	56035
k_AngleVolantValidThresh_Cnt_u16	63441
k_BSI552MsgTimeout_mS_u16	45186
k_BSINTCEnableTimeout_mS_u16	34662
k_BSINodeAbsentDiag_Cnt_str.Threshold	28766
k_BSINodeAbsentDiag_Cnt_str.PStep	41333
k_BSINodeAbsentDiag_Cnt_str.NStep	19647
k_BSINodeAbsentTimeout_mS_u16	8685
k_BSINodeTimeout_mS_u16	7674
k_BattOvHi_Volt_f32	23.4754009
k_BattOvLo_Volt_f32	15.1646996
k_BattUvHi_Volt_f32	12.8231001
k_BattUvLo_Volt_f32	8.35700035
k_CAVNTCEnableTimeout_mS_u16	2927
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	41723
k_CAVNodeTimeout_mS_u16	38553
k_CMM388MsgTimeout_mS_u16	8100
k_CMM388NTCEnableTimeout_mS_u16	43696
k_CMMNTCEnableTimeout_mS_u16	34816
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	37155
k_CONSANGLECPKMax_HwDeg_f32	754.489624
k_CONSANGLECPKMin_HwDeg_f32	0
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	8337
k_CONSANGLECPKSigValidThresh_Cnt_u16	50967
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	62150
k_CPKVehicleSpeedValidThresh_Cnt_u16	33470
k_CityParkInputInvalidThresh_Cnt_u16	23471
k_CityParkInputValidThresh_Cnt_u16	58367
k_ComputerRazGCTSigValidThresh_Cnt_u16	27062
k_CptTemporelSigValidThresh_Cnt_u16	31976
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	4944
k_DMDFCTCPKSigValidThresh_Cnt_u16	51278
k_DMDFCTCPKValidCount_Cnt_u16	8301
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	10016
k_DMDRELAXECPKSigValidThresh_Cnt_u16	38550
k_DMDRelaxeConsistentThresh_Cnt_u16	38532
k_DateValidThresh_Cnt_u16	14081
k_DefaultVehSpd_Kph_f32	143.716995
k_DiagMuxOnAbsentTimeout_mS_u16	23648
k_EMNodeTimeout_mS_u16	18590
k_ESPNTCEnableTimeout_mS_u16	25473
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	3595
k_EtatMTSigInvalidThresh_Cnt_u16	17740
k_EtatMTSigValidThresh_Cnt_u16	38178
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	48669
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	19911
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	28604
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	48313
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	7211
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	30907
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	22431
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	4218
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	48706
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	28694
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	36441
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	39130
k_ISDATDIRASentDiag_Cnt_str.Threshold	14294

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	34147
k_ISDATDIRASentDiag_Cnt_str.NStep	18148
k_ISDATDIRASentTimeout_mS_u16	6989
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	36835
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	64725
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	57693
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	65089
k_ISDYNAASChkSumValidThresh_Cnt_u16	35799
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	42721
k_ISDYNAASMsgCountValidThresh_Cnt_u16	60143
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	12853
k_ISDYNAASMsgLenValidThresh_Cnt_u16	25548
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	26912
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	9942
k_ISDYNABRChkSumValidThresh_Cnt_u16	37972
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	62853
k_ISDYNABRMsgCountValidThresh_Cnt_u16	1012
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	26970
k_ISDYNABRMsgLenValidThresh_Cnt_u16	34933
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	26591
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	28710
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	25284
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	8259
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	23234
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	52465
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	45289
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	4566
k_ISDYNVOLChkSumValidThresh_Cnt_u16	43192
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	37030
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	36555
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	9245
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	56423
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	5407
k_IgnOnTimeout_mS_u16	25058
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	188.858093
k_PowerCutVehSpdLowThresh_Kph_f32	113.334702
k_PowerCutVehSpdLowTimeout_mS_u16	5145
k_VBattMaxAAS_Volt_f32	11.5854998
k_VBattMaxBSI_Volt_f32	11.2798996
k_VBattMaxCAV_Volt_f32	13.4251003
k_VBattMaxCMM388_Volt_f32	15.9836998
k_VBattMaxCMM_Volt_f32	20.4570007
k_VBattMaxESP_Volt_f32	23.3843002
k_VBattMinAAS_Volt_f32	22.3845005
k_VBattMinBSI_Volt_f32	23.3843002
k_VBattMinCAV_Volt_f32	8.5237999
k_VBattMinCMM388_Volt_f32	18.1198006
k_VBattMinCMM_Volt_f32	31.9246998
k_VBattMinESP_Volt_f32	20.4570007
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	22773
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	1223
k_VitesseVehicleBVRampValidThresh_Cnt_u16	26211
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	3153
k_VitesseVehicleBVSigValidThresh_Cnt_u16	28884
k_VitesseVehicleBVSpeedPassThresh_kph_f32	306.703491
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	62069
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	21339
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2906251008
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	16
target_SrlComInput_Per1_Batt_Volt_f32.value	1.68420005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3578302208
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	242
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.804975569
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	975994624
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1417944832
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	250
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	199999232
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	140730112
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4058709760
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	156
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1887608576
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	740966144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	9
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	55
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	147
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	172
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	211
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1358978816
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	18
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	87
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	88
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	111
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	252
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	146
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	499351296
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	6
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1637555968
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	42123008
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	45
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	115
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	140
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	189
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3865448192
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	290
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.91229248
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	782134
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	183.917007
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	10692

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	45378	45378	✔
CONSANGLECPK_HwDeg_M_f32	-206.1297	-206.1297 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2006148864	2006148864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1000	1000	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2001	2001	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	88	88	✔
ElecIntTimer_mS_M_u32[1]	111	111	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	14294	14294	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	562724608	562724608	✔
IgnTimeOff_Sec_M_u32	1603044431	1603044431	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	91	91	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	975994624	975994624	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	134	134	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1417944832	1417944832	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	250	250	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	199999232	199999232	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	95	95	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	140730112	140730112	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4142186240	4142186240	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	156	156	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1887608576	1887608576	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	196	196	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	740966144	740966144	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	211	211	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1358978816	1358978816	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	146	146	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	499351296	499351296	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	6	6	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1637555968	1637555968	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	131	131	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	42123008	42123008	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3865448192	3865448192	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	373.685394	373.685394	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	538.65918	538.65918	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	552.718994	552.718994	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	45378	45378	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1603044431	1603044431	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-206.1297	-206.1297 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	143.716995	143.716995	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.423 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	473888256
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	4653
AASNodeAbsentTimer_mS_M_u32	3858949632
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	64209
ANGLEVOLANTSigValidCount_Cnt_M_u16	6407
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	12698
AngleVolantMsgTimer_mS_M_u32	473888256
AngleVolantValidCount_Cnt_M_u16	28537
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2442569216
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2116888064
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3118592
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1724012032
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	63112
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2465207808
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	17978
CAVNodeAbsentTimer_mS_M_u32	2017953280
CDD_SrlComVehSpd_Kph_G_f32	369.892487
CMM388NTCEnableTimer_mS_M_u32	444581376
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	25003520
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	17225
CMMNodeAbsentTimer_mS_M_u32	1275876864
CONSANGLECPKSigInvalidCount_Cnt_M_u16	22385
CONSANGLECPKSigValidCount_Cnt_M_u16	503
CONSANGLECPK_Cnt_M_u16	54802
CONSANGLECPK_HwDeg_M_f32	-194.535095
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	54802
CPKVehicleSpeedMsgTimer_mS_M_u32	3568170496
CPKVehicleSpeedValidCount_Cnt_M_u16	49714
CityParkInputConsistentCount_Cnt_M_u16	43677

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	34854
CityParkInputMsgTimer_mS_M_u32	975994624
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3928417792
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	50001
ComputerRazGCTSigInvalidTimer_mS_M_u32	2947548672
ComputerRazGCTSigValidCount_Cnt_M_u16	12354
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	59650
DMDFCTCPKSigValidCount_Cnt_M_u16	9248
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	40803
DMDRELAXECPKSigValidCount_Cnt_M_u16	26393
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	65502
DateInvalidTimer_mS_M_u32	2116888064
DiagMuxOnAbsentTimer_mS_M_u32	3981227520
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1724012032
ESPNTCEnableTimer_mS_M_u32	3243501056
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	2747
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	2500
EffacDefaultDiagTimer_mS_M_u32[1]	3501
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1
ElecIntTimer_mS_M_u32[1]	14
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2682394112
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	47655
EtatMTSigValidCount_Cnt_M_u16	35080
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	12803
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1545
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	1878
ISDAT4V2BSI552MsgTimer_mS_M_u32	3811595776
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	56354
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	17099
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	35080
ISDATBSI3F2MsgTimer_mS_M_u32	2864363008
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	61828
ISDATBSI412MsgLenValidCount_Cnt_M_u16	43358
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	47655
ISDATBSI412MsgTimer_mS_M_u32	1068299776
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	44397
ISDATBSI432MsgLenValidCount_Cnt_M_u16	34783
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	19115
ISDATDIRASentFltAcc_Cnt_M_u16	4319
ISDATDIRASentTimer_mS_M_u32	3568170496
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	27136
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	28537
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	63033
ISDYN2CMMMsgTimer_mS_M_u32	1528686080
ISDYNAASChkSumInvalidCount_Cnt_M_u16	33471
ISDYNAASChkSumValidCount_Cnt_M_u16	20
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	58032
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	33429
ISDYNAASMsgLenValidCount_Cnt_M_u16	53986
ISDYNAASMsgTimeValidCount_Cnt_M_u16	33471
ISDYNAASMsgTimer_mS_M_u32	274449920
ISDYNABRChkSumInvalidCount_Cnt_M_u16	41941
ISDYNABRChkSumValidCount_Cnt_M_u16	4050
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	45174
ISDYNABRMsgCountValidCount_Cnt_M_u16	55563
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	14376
ISDYNABRMsgLenValidCount_Cnt_M_u16	52718
ISDYNABRMsgTimeValidCount_Cnt_M_u16	54802
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	6574

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	18254
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	35080
ISDYNCMM208MsgTimer_mS_M_u32	1870374400
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	6574
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	18254
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	35303
ISDYNCMM388MsgTimer_mS_M_u32	160908800
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	19679
ISDYNVOLChkSumValidCount_Cnt_M_u16	52709
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	53616
ISDYNVOLMsgCountValidCount_Cnt_M_u16	8974
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	23556
ISDYNVOLMsgLenValidCount_Cnt_M_u16	1897
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	17225
ISDYNVOLMsgTimer_mS_M_u32	294389248
IgnOnTimer_mS_M_u32	2881177088
IgnTimeOff_Sec_M_u32	2663550828
ManVehSpd_Kph_M_f32	51.1759987
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	38
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3855660544
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	194
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1321637376
PrevISDATBSI412MsgDLCError_Cnt_M_u08	147
PrevISDATBSI412MsgRxTime_MSec_M_u32	2675475968
PrevISDATBSI432MsgDLCError_Cnt_M_u08	226
PrevISDATBSI432MsgRxTime_MSec_M_u32	937944576
PrevISDATDIRAMsgTxTime_MSec_M_u32	1689028096
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	63
PrevISDYN2CMMMsgRxTime_MSec_M_u32	625989120
PrevISDYNAASMsgDLCError_Cnt_M_u08	4
PrevISDYNAASMsgRxTime_MSec_M_u32	1836713472
PrevISDYNABRMsgDLCError_Cnt_M_u08	227
PrevISDYNABRMsgRxTime_MSec_M_u32	443762176
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	240
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3504276992
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	61
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3640845824
PrevISDYNVOLMsgDLCError_Cnt_M_u08	217
PrevISDYNVOLMsgRxTime_MSec_M_u32	137725440
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3860526592
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	10.5009003
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	53507
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	47056
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	36812
VitesseVehicleBVRampValidCount_Cnt_M_u16	11097
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	13082
VitesseVehicleBVSigValidCount_Cnt_M_u16	9744

Name	Input Value
VitesseVehicleBV_Kph_M_f32	384.717194
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	35303
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	27413
VitesseVehiculeRoues_Kph_M_f32	525.851624
k_AASNTCEnableTimeout_mS_u16	51393
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	60044
k_AASNodeTimeout_mS_u16	10960
k_ABSNodeTimeout_mS_u16	18087
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	7616
k_ANGLEVOLANTSigValidThresh_Cnt_u16	41074
k_AngleVolantInvalidThresh_Cnt_u16	65137
k_AngleVolantValidThresh_Cnt_u16	34854
k_BSI552MsgTimeout_mS_u16	36308
k_BSINTCEnableTimeout_mS_u16	35877
k_BSINodeAbsentDiag_Cnt_str.Threshold	8538
k_BSINodeAbsentDiag_Cnt_str.PStep	56406
k_BSINodeAbsentDiag_Cnt_str.NStep	63670
k_BSINodeAbsentTimeout_mS_u16	8786
k_BSINodeTimeout_mS_u16	19115
k_BattOvHi_Volt_f32	24.8335991
k_BattOvLo_Volt_f32	23.5818005
k_BattUvHi_Volt_f32	4.8032999
k_BattUvLo_Volt_f32	26.9295998
k_CAVNTCEnableTimeout_mS_u16	17740
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	65448
k_CAVNodeTimeout_mS_u16	50509
k_CMM388MsgTimeout_mS_u16	50477
k_CMM388NTCEnableTimeout_mS_u16	21513
k_CMMNTCEnableTimeout_mS_u16	55002
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	45041
k_CONSANGLECPKMax_HwDeg_f32	519.16272
k_CONSANGLECPKMin_HwDeg_f32	0
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	48359
k_CONSANGLECPKSigValidThresh_Cnt_u16	56853
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	30982
k_CPKVehicleSpeedValidThresh_Cnt_u16	44959
k_CityParkInputInvalidThresh_Cnt_u16	63115
k_CityParkInputValidThresh_Cnt_u16	43677
k_ComputerRazGCTSigValidThresh_Cnt_u16	35256
k_CptTemporelSigValidThresh_Cnt_u16	5345
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	60200
k_DMDFCTCPKSigValidThresh_Cnt_u16	49390
k_DMDFCTCPKValidCount_Cnt_u16	51408
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	63033
k_DMDRELAXECPKSigValidThresh_Cnt_u16	31895
k_DMDRelaxeConsistentThresh_Cnt_u16	46285
k_DateValidThresh_Cnt_u16	1878
k_DefaultVehSpd_Kph_f32	41.4534988
k_DiagMuxOnAbsentTimeout_mS_u16	52408
k_EMNodeTimeout_mS_u16	830
k_ESPNTCEnableTimeout_mS_u16	22038
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	55609
k_EtatMTSigInvalidThresh_Cnt_u16	60852
k_EtatMTSigValidThresh_Cnt_u16	21233
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	13057
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	10434
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	15206
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	23727
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	792
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	424
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	16250

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	31148
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	22417
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	59798
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	37775
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	11850
k_ISDATDIRASentDiag_Cnt_str.Threshold	6491
k_ISDATDIRASentDiag_Cnt_str.PStep	58700
k_ISDATDIRASentDiag_Cnt_str.NStep	43168
k_ISDATDIRASentTimeout_mS_u16	44977
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	44335
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	12698
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	19586
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	54997
k_ISDYNAASChkSumValidThresh_Cnt_u16	33490
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	25462
k_ISDYNAASMsgCountValidThresh_Cnt_u16	52235
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	2809
k_ISDYNAASMsgLenValidThresh_Cnt_u16	48628
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	34746
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	18582
k_ISDYNABRChkSumValidThresh_Cnt_u16	62684
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	43400
k_ISDYNABRMsgCountValidThresh_Cnt_u16	13054
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46665
k_ISDYNABRMsgLenValidThresh_Cnt_u16	48571
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	29501
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	1063
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	42893
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	9359
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	44497
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	3079
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	48350
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	25175
k_ISDYNVOLChkSumValidThresh_Cnt_u16	8817
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	43304
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	18934
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	24323
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	23268
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	25852
k_IgnOnTimeout_mS_u16	41523
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	218.530106
k_PowerCutVehSpdLowThresh_Kph_f32	37.100399
k_PowerCutVehSpdLowTimeout_mS_u16	51597
k_VBattMaxAAS_Volt_f32	1.67309999
k_VBattMaxBSI_Volt_f32	16.5760994
k_VBattMaxCAV_Volt_f32	0.504700005
k_VBattMaxCMM388_Volt_f32	2.69039989
k_VBattMaxCMM_Volt_f32	11.2812004
k_VBattMaxESP_Volt_f32	31.5998993
k_VBattMinAAS_Volt_f32	4.95079994
k_VBattMinBSI_Volt_f32	31.5998993
k_VBattMinCAV_Volt_f32	11.6961002
k_VBattMinCMM388_Volt_f32	5.14429998
k_VBattMinCMM_Volt_f32	4.30289984
k_VBattMinESP_Volt_f32	11.2812004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	6649
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	23363
k_VitesseVehicleBVRampValidThresh_Cnt_u16	1136
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	49381
k_VitesseVehicleBVSigValidThresh_Cnt_u16	38942
k_VitesseVehicleBVSpeedPassThresh_kph_f32	219.779007
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	31034
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	60231
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2116888064
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	61
target_SrlComInput_Per1_Batt_Volt_f32.value	28.8978996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3703641600
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	0
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	8
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.178667426
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	234
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1775584768
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	176
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2169398784
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	26707456
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	115
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4071663104
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1553581568
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1196615168
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	23
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3134981632
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	44
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	62
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	114
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	195
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	205
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	218
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3436815872
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	41
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	55
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	177
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	241
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	98
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3675276800
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1980327424
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	970098176
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	187
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	231
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4285044224
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1428
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.444980085
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	926314
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	185.603607

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	53069		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	51.1759987	51.1759987	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	54802	54802	✔
CONSANGLECPK_HwDeg_M_f32	-194.535095	-194.535095 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2006148864	2006148864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2500	2500	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	3501	3501	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1	1	✔
ElecIntTimer_mS_M_u32[1]	14	14	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	1878	1878	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	35080	35080	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	47655	47655	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	19115	19115	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	6491	6491	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	63033	63033	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	33471	33471	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	54802	54802	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	35080	35080	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	35303	35303	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	17225	17225	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	2881177088	2881177088	✔
IgnTimeOff_Sec_M_u32	2663550828	2663550828	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	234	234	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1775584768	1775584768	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	176	176	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2169398784	2169398784	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	26707456	26707456	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	115	115	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4071663104	4071663104	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1689028096	1689028096	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	9	9	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1196615168	1196615168	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	23	23	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3134981632	3134981632	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	202	202	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3436815872	3436815872	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	98	98	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3675276800	3675276800	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	75	75	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1980327424	1980327424	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	90	90	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	970098176	970098176	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4285044224	4285044224	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	10.5009003	10.5009003	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	384.717194	384.717194	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	525.851624	525.851624	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	54802	54802	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2663550828	2663550828	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-194.535095	-194.535095 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	51.1759987	51.1759987	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.424 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1178198272
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	15982
AASNodeAbsentTimer_mS_M_u32	615387392
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	46720
ANGLEVOLANTSigValidCount_Cnt_M_u16	15776
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	54311
AngleVolantMsgTimer_mS_M_u32	1178198272
AngleVolantValidCount_Cnt_M_u16	65290
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	552784128
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3576647936
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2766668032
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	741327104
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	24411
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2393276672
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	7368
CAVNodeAbsentTimer_mS_M_u32	3361747200
CDD_SrlComVehSpd_Kph_G_f32	395.838013
CMM388NTCEnableTimer_mS_M_u32	314011904
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2227056896
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	16473
CMMNodeAbsentTimer_mS_M_u32	609337600
CONSANGLECPKSigInvalidCount_Cnt_M_u16	53153
CONSANGLECPKSigValidCount_Cnt_M_u16	61905
CONSANGLECPK_Cnt_M_u16	41344
CONSANGLECPK_HwDeg_M_f32	-278.957489
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	41344
CPKVehicleSpeedMsgTimer_mS_M_u32	2565660928
CPKVehicleSpeedValidCount_Cnt_M_u16	50440
CityParkInputConsistentCount_Cnt_M_u16	56734
CityParkInputInvalidCount_Cnt_M_u16	64002
CityParkInputMsgTimer_mS_M_u32	1775584768
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2822902016
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	47874

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1680257280
ComputerRazGCTSigValidCount_Cnt_M_u16	8367
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	18286
DMDFCTCPKSigValidCount_Cnt_M_u16	6101
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	37066
DMDRELAXECPKSigValidCount_Cnt_M_u16	7018
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	51802
DateInvalidTimer_mS_M_u32	3576647936
DiagMuxOnAbsentTimer_mS_M_u32	974168320
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	741327104
ESPNTCEnableTimer_mS_M_u32	381358336
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	48069
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	579
EffacDefaultDiagTimer_mS_M_u32[1]	990
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6
ElecIntTimer_mS_M_u32[1]	19
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2949677312
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	57537
EtatMTSigValidCount_Cnt_M_u16	1501
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	2027
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	44443
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	50739
ISDAT4V2BSI552MsgTimer_mS_M_u32	4008034560
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	8271
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	40467
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	1501
ISDATBSI3F2MsgTimer_mS_M_u32	969318656
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	14632
ISDATBSI412MsgLenValidCount_Cnt_M_u16	33628
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	57537
ISDATBSI412MsgTimer_mS_M_u32	334487808
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	37357
ISDATBSI432MsgLenValidCount_Cnt_M_u16	54361
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	4981
ISDATDIRASentFltAcc_Cnt_M_u16	37081
ISDATDIRASentTimer_mS_M_u32	2565660928
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	7606
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	65290
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	48073
ISDYN2CMMMsgTimer_mS_M_u32	4049408256
ISDYNAASChkSumInvalidCount_Cnt_M_u16	46264
ISDYNAASChkSumValidCount_Cnt_M_u16	40568
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	16741
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	37815
ISDYNAASMsgLenValidCount_Cnt_M_u16	58511
ISDYNAASMsgTimeValidCount_Cnt_M_u16	46264
ISDYNAASMsgTimer_mS_M_u32	2703454464
ISDYNABRChkSumInvalidCount_Cnt_M_u16	33014
ISDYNABRChkSumValidCount_Cnt_M_u16	16062
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	51091
ISDYNABRMsgCountValidCount_Cnt_M_u16	44947
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	51580
ISDYNABRMsgLenValidCount_Cnt_M_u16	10732
ISDYNABRMsgTimeValidCount_Cnt_M_u16	41344
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	54528
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	6575
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	1501
ISDYNCMM208MsgTimer_mS_M_u32	1531171072
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	54528
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	6575
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	59328

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	57733376
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	10071
ISDYNVOLChkSumValidCount_Cnt_M_u16	50695
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	50724
ISDYNVOLMsgCountValidCount_Cnt_M_u16	21259
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	11242
ISDYNVOLMsgLenValidCount_Cnt_M_u16	52089
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	16473
ISDYNVOLMsgTimer_mS_M_u32	2928849152
IgnOnTimer_mS_M_u32	2902782208
IgnTimeOff_Sec_M_u32	1060408054
ManVehSpd_Kph_M_f32	643.72998
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	39
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	100
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1619304704
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	20
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3575841024
PrevISDATBSI412MsgDLCError_Cnt_M_u08	200
PrevISDATBSI412MsgRxTime_MSec_M_u32	1456288000
PrevISDATBSI432MsgDLCError_Cnt_M_u08	62
PrevISDATBSI432MsgRxTime_MSec_M_u32	50270464
PrevISDATDIRAMsgTxTime_MSec_M_u32	3610325248
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	17
PrevISDYN2CMMMsgRxTime_MSec_M_u32	109527296
PrevISDYNAASMsgDLCError_Cnt_M_u08	71
PrevISDYNAASMsgRxTime_MSec_M_u32	3536367872
PrevISDYNABRMsgDLCError_Cnt_M_u08	173
PrevISDYNABRMsgRxTime_MSec_M_u32	1088221440
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	39
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2090447104
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	222
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1269698816
PrevISDYNVOLMsgDLCError_Cnt_M_u08	83
PrevISDYNVOLMsgRxTime_MSec_M_u32	1352020224
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1487266048
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	433.098602
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57453
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	28101
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	2066
VitesseVehicleBVRampValidCount_Cnt_M_u16	30506
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	29093
VitesseVehicleBVSigValidCount_Cnt_M_u16	31365
VitesseVehicleBV_Kph_M_f32	641.076599
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	59328
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	1527
VitesseVehiculeRoues_Kph_M_f32	324.071991
k_AASNTCEnableTimeout_mS_u16	17779
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	39377
k_AASNodeTimeout_mS_u16	5317
k_ABSNodeTimeout_mS_u16	639
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	19700
k_ANGLEVOLANTSigValidThresh_Cnt_u16	38560
k_AngleVolantInvalidThresh_Cnt_u16	14499
k_AngleVolantValidThresh_Cnt_u16	64002
k_BSI552MsgTimeout_mS_u16	22970
k_BSINTCEnableTimeout_mS_u16	54725
k_BSINodeAbsentDiag_Cnt_str.Threshold	51817
k_BSINodeAbsentDiag_Cnt_str.PStep	30839
k_BSINodeAbsentDiag_Cnt_str.NStep	44488
k_BSINodeAbsentTimeout_mS_u16	57855
k_BSINodeTimeout_mS_u16	4981
k_BattOvHi_Volt_f32	25.8192997
k_BattOvLo_Volt_f32	10.6271
k_BattUvHi_Volt_f32	14.3719997
k_BattUvLo_Volt_f32	19.3092003
k_CAVNTCEnableTimeout_mS_u16	55952
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	10366
k_CAVNodeTimeout_mS_u16	62989
k_CMM388MsgTimeout_mS_u16	9582
k_CMM388NTCEnableTimeout_mS_u16	59610
k_CMMNTCEnableTimeout_mS_u16	4135
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	42851
k_CONSANGLECPKMax_HwDeg_f32	153.890198
k_CONSANGLECPKMin_HwDeg_f32	0
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	20160
k_CONSANGLECPKSigValidThresh_Cnt_u16	44279
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	33315
k_CPKVehicleSpeedValidThresh_Cnt_u16	10967
k_CityParkInputInvalidThresh_Cnt_u16	57556
k_CityParkInputValidThresh_Cnt_u16	56734
k_ComputerRazGCTSigValidThresh_Cnt_u16	61325
k_CptTemporelSigValidThresh_Cnt_u16	65489
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	45180
k_DMDFCTCPKSigValidThresh_Cnt_u16	20716
k_DMDFCTCPKValidCount_Cnt_u16	2179
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	48073
k_DMDRELAXECPKSigValidThresh_Cnt_u16	43632
k_DMDRelaxeConsistentThresh_Cnt_u16	22990
k_DateValidThresh_Cnt_u16	50739
k_DefaultVehSpd_Kph_f32	219.1035
k_DiagMuxOnAbsentTimeout_mS_u16	54670
k_EMNodeTimeout_mS_u16	16442
k_ESPNTCEnableTimeout_mS_u16	23860
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	19339
k_EtatMTSigInvalidThresh_Cnt_u16	57177
k_EtatMTSigValidThresh_Cnt_u16	45409
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	50
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	12461
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	36675
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	4776
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	53548
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	39100
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	20422
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	29426
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	9089
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	30452
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	27336
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	27606
k_ISDATDIRASentDiag_Cnt_str.Threshold	25239

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	16638
k_ISDATDIRASentDiag_Cnt_str.NStep	16248
k_ISDATDIRASentTimeout_mS_u16	52578
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	49959
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	54311
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10736
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	59382
k_ISDYNAASChkSumValidThresh_Cnt_u16	58814
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	44691
k_ISDYNAASMsgCountValidThresh_Cnt_u16	54931
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	56202
k_ISDYNAASMsgLenValidThresh_Cnt_u16	60249
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	200
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	53298
k_ISDYNABRChkSumValidThresh_Cnt_u16	60706
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	18011
k_ISDYNABRMsgCountValidThresh_Cnt_u16	35771
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	59225
k_ISDYNABRMsgLenValidThresh_Cnt_u16	41669
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	34558
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	55041
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	31501
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	58248
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	40320
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	25760
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	15322
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	62127
k_ISDYNVOLChkSumValidThresh_Cnt_u16	9251
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	54398
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	8274
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	25133
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	73
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	50497
k_IgnOnTimeout_mS_u16	41755
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	30.3736
k_PowerCutVehSpdLowThresh_Kph_f32	6.66260004
k_PowerCutVehSpdLowTimeout_mS_u16	29455
k_VBattMaxAAS_Volt_f32	13.7320004
k_VBattMaxBSI_Volt_f32	26.0638008
k_VBattMaxCAV_Volt_f32	4.18540001
k_VBattMaxCMM388_Volt_f32	1.04439998
k_VBattMaxCMM_Volt_f32	8.23960018
k_VBattMaxESP_Volt_f32	24.9817009
k_VBattMinAAS_Volt_f32	28.8743
k_VBattMinBSI_Volt_f32	24.9817009
k_VBattMinCAV_Volt_f32	14.1492996
k_VBattMinCMM388_Volt_f32	0.0954999998
k_VBattMinCMM_Volt_f32	12.9001999
k_VBattMinESP_Volt_f32	8.23960018
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	9417
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	37548
k_VitesseVehicleBVRampValidThresh_Cnt_u16	11556
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	60679
k_VitesseVehicleBVSigValidThresh_Cnt_u16	22811
k_VitesseVehicleBVSpeedPassThresh_kph_f32	436.606903
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	33736
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	28512
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3576647936
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	63029
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	4103887872
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	222
target_SrlComInput_Per1_Batt_Volt_f32.value	31
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	892567808
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	87
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0823658034
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	41
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1521938688
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3771437312
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1819291904
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3852783872
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	879325440
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	44
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1086198016
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4070748416
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	34
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	140
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	189
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	197
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	992596224
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	36
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	43
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	114
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	222
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	242
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3003511040
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2929365248
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1874800896
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	71
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	135
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	142
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	177
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	234
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3409772800
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3969
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.640644908
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	349632
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	16.4030991
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	36239

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4103887872	4103887872	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4103887872	4103887872	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	4103887872	4103887872	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	4103887872	4103887872	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4103887872	4103887872	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4103887872	4103887872	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4103887872	4103887872	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	4103887872	4103887872	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4103887872	4103887872	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4103887872	4103887872	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4103887872	4103887872	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4103887872	4103887872	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4103887872	4103887872	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	41344	41344	✔
CONSANGLECPK_HwDeg_M_f32	-278.957489	-278.957489 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4103887872	4103887872	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	4103887872	4103887872	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4103887872	4103887872	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4103887872	4103887872	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4103887872	4103887872	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4103887872	4103887872	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4103887872	4103887872	✔
ESPNTCEnableTimer_mS_M_u32	4103887872	4103887872	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4103887872	4103887872	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4103887872	4103887872	✔
EffacDefaultDiagTimer_mS_M_u32[1]	990	990	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4103887872	4103887872	✔
ElecIntTimer_mS_M_u32[1]	19	19	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4103887872	4103887872	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4103887872	4103887872	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4103887872	4103887872	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4103887872	4103887872	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4103887872	4103887872	✔
ISDATDIRASentFltAcc_Cnt_M_u16	25239	25239	✔
ISDATDIRASentTimer_mS_M_u32	4103887872	4103887872	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4103887872	4103887872	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4103887872	4103887872	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4103887872	4103887872	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4103887872	4103887872	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4103887872	4103887872	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4103887872	4103887872	✔
IgnOnTimer_mS_M_u32	4103887872	4103887872	✔
IgnTimeOff_Sec_M_u32	1060408054	1060408054	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	41	41	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1521938688	1521938688	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	3	3	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3771437312	3771437312	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	239	239	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1819291904	1819291904	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	212	212	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3852783872	3852783872	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3610325248	3610325248	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	44	44	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1086198016	1086198016	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	110	110	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4070748416	4070748416	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	180	180	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	992596224	992596224	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	110	110	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3003511040	3003511040	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	222	222	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2929365248	2929365248	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	31	31	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1874800896	1874800896	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3409772800	3409772800	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	433.098602	433.098602	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	362.389984	362.390015	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	324.071991	324.071991	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	41344	41344	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1060408054	1060408054	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-278.957489	-278.957489 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.425 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2914328576
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	14103
AASNodeAbsentTimer_mS_M_u32	1595445248
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	14560
ANGLEVOLANTSigValidCount_Cnt_M_u16	65089
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	39404
AngleVolantMsgTimer_mS_M_u32	2914328576
AngleVolantValidCount_Cnt_M_u16	27588
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1833586688
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3801403392
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1915404288
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2874376192
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	27215
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3471785984
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	11401
CAVNodeAbsentTimer_mS_M_u32	1686253568
CDD_SrlComVehSpd_Kph_G_f32	411.381104
CMM388NTCEnableTimer_mS_M_u32	4068241408
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	661139456
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	29078
CMMNodeAbsentTimer_mS_M_u32	3404562432
CONSANGLECPKSigInvalidCount_Cnt_M_u16	24701
CONSANGLECPKSigValidCount_Cnt_M_u16	38062
CONSANGLECPK_Cnt_M_u16	417
CONSANGLECPK_HwDeg_M_f32	-754.83667
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	417
CPKVehicleSpeedMsgTimer_mS_M_u32	1100750848
CPKVehicleSpeedValidCount_Cnt_M_u16	32592

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	8200
CityParkInputInvalidCount_Cnt_M_u16	43996
CityParkInputMsgTimer_mS_M_u32	1521938688
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	610045952
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	4443
ComputerRazGCTSigInvalidTimer_mS_M_u32	3408834560
ComputerRazGCTSigValidCount_Cnt_M_u16	56021
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	29592
DMDFCTCPKSigValidCount_Cnt_M_u16	32032
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	20994
DMDRELAXECPKSigValidCount_Cnt_M_u16	3299
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	37970
DateInvalidTimer_mS_M_u32	3801403392
DiagMuxOnAbsentTimer_mS_M_u32	2637225984
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2874376192
ESPNTCEnableTimer_mS_M_u32	4243689472
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	35347
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1000
EffacDefaultDiagTimer_mS_M_u32[1]	2001
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	88
ElecIntTimer_mS_M_u32[1]	111
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2473672704
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	33117
EtatMTSigValidCount_Cnt_M_u16	23754
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24479
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	2384
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	27142
ISDAT4V2BSI552MsgTimer_mS_M_u32	3140583424
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	53812
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	17321
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	23754
ISDATBSI3F2MsgTimer_mS_M_u32	4128169984
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	31912
ISDATBSI412MsgLenValidCount_Cnt_M_u16	18637
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	33117
ISDATBSI412MsgTimer_mS_M_u32	2626887680
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	52442
ISDATBSI432MsgLenValidCount_Cnt_M_u16	36951
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	15490
ISDATDIRASentFltAcc_Cnt_M_u16	21590
ISDATDIRASentTimer_mS_M_u32	1100750848
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	58623
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	27588
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	17031
ISDYN2CMMMsgTimer_mS_M_u32	1963692032
ISDYNAASChkSumInvalidCount_Cnt_M_u16	31801
ISDYNAASChkSumValidCount_Cnt_M_u16	39354
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	53427
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	17340
ISDYNAASMsgLenValidCount_Cnt_M_u16	35829
ISDYNAASMsgTimeValidCount_Cnt_M_u16	31801
ISDYNAASMsgTimer_mS_M_u32	4147671040
ISDYNABRChkSumInvalidCount_Cnt_M_u16	35070
ISDYNABRChkSumValidCount_Cnt_M_u16	19047
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	28584
ISDYNABRMsgCountValidCount_Cnt_M_u16	37481
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	40684
ISDYNABRMsgLenValidCount_Cnt_M_u16	6237
ISDYNABRMsgTimeValidCount_Cnt_M_u16	417

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	46871
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	40397
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	23754
ISDYNCMM208MsgTimer_mS_M_u32	1113018368
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	46871
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	40397
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	2466
ISDYNCMM388MsgTimer_mS_M_u32	3863998464
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	45403
ISDYNVOLChkSumValidCount_Cnt_M_u16	28684
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	20342
ISDYNVOLMsgCountValidCount_Cnt_M_u16	9086
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	3492
ISDYNVOLMsgLenValidCount_Cnt_M_u16	18869
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	29078
ISDYNVOLMsgTimer_mS_M_u32	2615848960
IgnOnTimer_mS_M_u32	965996544
IgnTimeOff_Sec_M_u32	2528204130
ManVehSpd_Kph_M_f32	479.797607
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	37
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	135
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4191477760
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	0
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2373566464
PrevISDATBSI412MsgDLCError_Cnt_M_u08	114
PrevISDATBSI412MsgRxTime_MSec_M_u32	2906337280
PrevISDATBSI432MsgDLCError_Cnt_M_u08	222
PrevISDATBSI432MsgRxTime_MSec_M_u32	1210421248
PrevISDATDIRAMsgTxTime_MSec_M_u32	3155111936
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	169
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3662479360
PrevISDYNAASMsgDLCError_Cnt_M_u08	128
PrevISDYNAASMsgRxTime_MSec_M_u32	2269687808
PrevISDYNABRMsgDLCError_Cnt_M_u08	63
PrevISDYNABRMsgRxTime_MSec_M_u32	3725324288
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	241
PrevISDYNCMM208MsgRxTime_MSec_M_u32	232108032
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	237
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3927478272
PrevISDYNVOLMsgDLCError_Cnt_M_u08	186
PrevISDYNVOLMsgRxTime_MSec_M_u32	601894912
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	644947968
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	140.641907
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	46490
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	18515
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	4779
VitesseVehicleBVRampValidCount_Cnt_M_u16	36
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	56177

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	7058
VitesseVehicleBV_Kph_M_f32	119.207397
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	2466
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	27067
VitesseVehiculeRoues_Kph_M_f32	94.6845016
k_AASNTCEnableTimeout_mS_u16	41416
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	30575
k_AASNodeTimeout_mS_u16	21331
k_ABSNodeTimeout_mS_u16	50789
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	30661
k_ANGLEVOLANTSigValidThresh_Cnt_u16	9602
k_AngleVolantInvalidThresh_Cnt_u16	2937
k_AngleVolantValidThresh_Cnt_u16	43996
k_BSI552MsgTimeout_mS_u16	14962
k_BSINTCEnableTimeout_mS_u16	24914
k_BSINodeAbsentDiag_Cnt_str.Threshold	28766
k_BSINodeAbsentDiag_Cnt_str.PStep	41333
k_BSINodeAbsentDiag_Cnt_str.NStep	19647
k_BSINodeAbsentTimeout_mS_u16	53348
k_BSINodeTimeout_mS_u16	15490
k_BattOvHi_Volt_f32	21.9001007
k_BattOvLo_Volt_f32	26.8201008
k_BattUvHi_Volt_f32	10.8563004
k_BattUvLo_Volt_f32	9.59710026
k_CAVNTCEnableTimeout_mS_u16	49714
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	24935
k_CAVNodeTimeout_mS_u16	40249
k_CMM388MsgTimeout_mS_u16	33303
k_CMM388NTCEnableTimeout_mS_u16	59347
k_CMMNTCEnableTimeout_mS_u16	25260
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	13687
k_CONSANGLECPKMax_HwDeg_f32	119.1548
k_CONSANGLECPKMin_HwDeg_f32	-285
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	54434
k_CONSANGLECPKSigValidThresh_Cnt_u16	29883
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	825
k_CPKVehicleSpeedValidThresh_Cnt_u16	9115
k_CityParkInputInvalidThresh_Cnt_u16	24932
k_CityParkInputValidThresh_Cnt_u16	8200
k_ComputerRazGCTSigValidThresh_Cnt_u16	56442
k_CptTemporelSigValidThresh_Cnt_u16	38511
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	59884
k_DMDFCTCPKSigValidThresh_Cnt_u16	41821
k_DMDFCTCPKValidCount_Cnt_u16	3799
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	17031
k_DMDRELAXECPKSigValidThresh_Cnt_u16	61775
k_DMDRelaxeConsistentThresh_Cnt_u16	56117
k_DateValidThresh_Cnt_u16	27142
k_DefaultVehSpd_Kph_f32	185.575195
k_DiagMuxOnAbsentTimeout_mS_u16	7543
k_EMNodeTimeout_mS_u16	45746
k_ESPNTCEnableTimeout_mS_u16	6981
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	59647
k_EtatMTSigInvalidThresh_Cnt_u16	47573
k_EtatMTSigValidThresh_Cnt_u16	15998
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	34060
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	48729
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	57113
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	40745
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	20062
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	44524

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	14159
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	22668
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	26654
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	20805
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	41098
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	10656
k_ISDATDIRASentDiag_Cnt_str.Threshold	60800
k_ISDATDIRASentDiag_Cnt_str.PStep	27554
k_ISDATDIRASentDiag_Cnt_str.NStep	30413
k_ISDATDIRASentTimeout_mS_u16	21434
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	42925
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	39404
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	42257
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	21502
k_ISDYNAASChkSumValidThresh_Cnt_u16	21863
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	47784
k_ISDYNAASMsgCountValidThresh_Cnt_u16	7529
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	51522
k_ISDYNAASMsgLenValidThresh_Cnt_u16	8087
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	34570
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	58058
k_ISDYNABRChkSumValidThresh_Cnt_u16	9915
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	46415
k_ISDYNABRMsgCountValidThresh_Cnt_u16	16368
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	31894
k_ISDYNABRMsgLenValidThresh_Cnt_u16	54547
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	6695
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	8670
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	35577
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	45834
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	33760
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	35137
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	18004
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	11283
k_ISDYNVOLChkSumValidThresh_Cnt_u16	17016
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	25576
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	62891
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	44313
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	7558
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	9436
k_IgnOnTimeout_mS_u16	51919
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	236.265106
k_PowerCutVehSpdLowThresh_Kph_f32	219.397903
k_PowerCutVehSpdLowTimeout_mS_u16	35060
k_VBattMaxAAS_Volt_f32	12.0274
k_VBattMaxBSI_Volt_f32	1.90910006
k_VBattMaxCAV_Volt_f32	13.8226004
k_VBattMaxCMM388_Volt_f32	12.9976997
k_VBattMaxCMM_Volt_f32	24.5088005
k_VBattMaxESP_Volt_f32	5.18760014
k_VBattMinAAS_Volt_f32	23.6737995
k_VBattMinBSI_Volt_f32	5.18760014
k_VBattMinCAV_Volt_f32	18.3167
k_VBattMinCMM388_Volt_f32	29.6049004
k_VBattMinCMM_Volt_f32	26.3502007
k_VBattMinESP_Volt_f32	24.5088005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	35527
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	43996
k_VitesseVehicleBVRampValidThresh_Cnt_u16	6774
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	64268
k_VitesseVehicleBVSigValidThresh_Cnt_u16	57745
k_VitesseVehicleBVSpeedPassThresh_kph_f32	205.108795
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	63369
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	28546
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3801403392
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	16518
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1513729792
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	237
target_SrlComInput_Per1_Batt_Volt_f32.value	8.39260006
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1330135040
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	60
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.525998831
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	23
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2021519360
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2160070656
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	250
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3092393984
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1731481600
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3580260352
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1256755200
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	230
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	263892992
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	70
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	163
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	192
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	250
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3131396096
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	88
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	103
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	115
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	134
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	172
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	173
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	200
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1804660736
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	324210688
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2858758144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	68
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	107
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	131
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	143
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	201
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	229
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2469117952
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	272
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.404781491
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	591581
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	104.426498
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	46644

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1513729792	1513729792	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1513729792	1513729792	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1513729792	1513729792	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1513729792	1513729792	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1513729792	1513729792	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1513729792	1513729792	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1513729792	1513729792	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1513729792	1513729792	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1513729792	1513729792	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1513729792	1513729792	✔
CDD_SrlComVehSpd_Kph_G_f32	479.797607	479.797607	✔
CMM388NTCEnableTimer_mS_M_u32	1513729792	1513729792	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1513729792	1513729792	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1513729792	1513729792	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	417	417	✔
CONSANGLECPK_HwDeg_M_f32	-754.83667	-754.83667 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1513729792	1513729792	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1513729792	1513729792	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1513729792	1513729792	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1513729792	1513729792	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1513729792	1513729792	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1513729792	1513729792	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1513729792	1513729792	✔
ESPNTCEnableTimer_mS_M_u32	1513729792	1513729792	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1513729792	1513729792	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	1000	1000	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2001	2001	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	88	88	✔
ElecIntTimer_mS_M_u32[1]	111	111	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1513729792	1513729792	✔
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	27142	27142	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1513729792	1513729792	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	23754	23754	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1513729792	1513729792	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	33117	33117	✔
ISDATBSI412MsgTimer_mS_M_u32	1513729792	1513729792	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	15490	15490	✔
ISDATBSI432MsgTimer_mS_M_u32	1513729792	1513729792	✔
ISDATDIRASentFltAcc_Cnt_M_u16	60800	60800	✔
ISDATDIRASentTimer_mS_M_u32	1513729792	1513729792	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	17031	17031	✔
ISDYN2CMMMsgTimer_mS_M_u32	1513729792	1513729792	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	31801	31801	✔
ISDYNAASMsgTimer_mS_M_u32	1513729792	1513729792	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	417	417	✔
ISDYNABRMsgTimer_mS_M_u32	1513729792	1513729792	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	23754	23754	✔
ISDYNCMM208MsgTimer_mS_M_u32	1513729792	1513729792	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	2466	2466	✔
ISDYNCMM388MsgTimer_mS_M_u32	1513729792	1513729792	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	29078	29078	✔
ISDYNVOLMsgTimer_mS_M_u32	1513729792	1513729792	✔
IgnOnTimer_mS_M_u32	965996544	965996544	✔
IgnTimeOff_Sec_M_u32	2528204130	2528204130	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	23	23	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2021519360	2021519360	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	3	3	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2160070656	2160070656	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	250	250	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3092393984	3092393984	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	68	68	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1731481600	1731481600	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3155111936	3155111936	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	242	242	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1256755200	1256755200	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	230	230	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	263892992	263892992	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	250	250	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3131396096	3131396096	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1804660736	1804660736	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	110	110	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	324210688	324210688	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2858758144	2858758144	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2469117952	2469117952	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	140.641907	140.641907	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	119.207397	119.207397	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	94.6845016	94.6845016	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	417	417	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2528204130	2528204130	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-754.83667	-754.83667 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.426 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1996448512
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	34007
AASNodeAbsentTimer_mS_M_u32	2090144512
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	16766
ANGLEVOLANTSigValidCount_Cnt_M_u16	57627
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	61528
AngleVolantMsgTimer_mS_M_u32	1996448512
AngleVolantValidCount_Cnt_M_u16	33616
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1224725248
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	857756416
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2283700992
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1873036032
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	10545
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	600900352
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	62211
CAVNodeAbsentTimer_mS_M_u32	2597860096
CDD_SrlComVehSpd_Kph_G_f32	535.847107
CMM388NTCEnableTimer_mS_M_u32	2850648832
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1780888320
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	5275
CMMNodeAbsentTimer_mS_M_u32	4174791424
CONSANGLECPKSigInvalidCount_Cnt_M_u16	29093
CONSANGLECPKSigValidCount_Cnt_M_u16	1234
CONSANGLECPK_Cnt_M_u16	18937
CONSANGLECPK_HwDeg_M_f32	-749.57251
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	18937
CPKVehicleSpeedMsgTimer_mS_M_u32	390750976
CPKVehicleSpeedValidCount_Cnt_M_u16	14357
CityParkInputConsistentCount_Cnt_M_u16	30340
CityParkInputInvalidCount_Cnt_M_u16	12298
CityParkInputMsgTimer_mS_M_u32	2021519360
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1019810560
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	1547

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3100816128
ComputerRazGCTSigValidCount_Cnt_M_u16	47645
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	51414
DMDFCTCPKSigValidCount_Cnt_M_u16	15355
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	65048
DMDRELAXECPKSigValidCount_Cnt_M_u16	48437
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	27174
DateInvalidTimer_mS_M_u32	857756416
DiagMuxOnAbsentTimer_mS_M_u32	1200366336
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1873036032
ESPNTCEnableTimer_mS_M_u32	1191842560
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	10980
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	2500
EffacDefaultDiagTimer_mS_M_u32[1]	3501
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1
ElecIntTimer_mS_M_u32[1]	14
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1581974272
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	4677
EtatMTSigValidCount_Cnt_M_u16	40894
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	31807
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	44780
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	36169
ISDAT4V2BSI552MsgTimer_mS_M_u32	940196608
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	61762
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	56483
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	40894
ISDATBSI3F2MsgTimer_mS_M_u32	888283904
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	4837
ISDATBSI412MsgLenValidCount_Cnt_M_u16	44599
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	4677
ISDATBSI412MsgTimer_mS_M_u32	2724553472
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	4815
ISDATBSI432MsgLenValidCount_Cnt_M_u16	10264
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	59160
ISDATDIRASentFltAcc_Cnt_M_u16	61340
ISDATDIRASentTimer_mS_M_u32	390750976
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	38879
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	33616
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	55305
ISDYN2CMMMsgTimer_mS_M_u32	3334214400
ISDYNAASChkSumInvalidCount_Cnt_M_u16	48497
ISDYNAASChkSumValidCount_Cnt_M_u16	54447
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	53379
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	14698
ISDYNAASMsgLenValidCount_Cnt_M_u16	45183
ISDYNAASMsgTimeValidCount_Cnt_M_u16	48497
ISDYNAASMsgTimer_mS_M_u32	2343924480
ISDYNABRChkSumInvalidCount_Cnt_M_u16	17059
ISDYNABRChkSumValidCount_Cnt_M_u16	3624
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	24356
ISDYNABRMsgCountValidCount_Cnt_M_u16	26274
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	12888
ISDYNABRMsgLenValidCount_Cnt_M_u16	62917
ISDYNABRMsgTimeValidCount_Cnt_M_u16	18937
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	6574
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	18254
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	40894
ISDYNCMM208MsgTimer_mS_M_u32	1037619968
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	6574
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	18254
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	41398

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	2087645952
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	30475
ISDYNVOLChkSumValidCount_Cnt_M_u16	27320
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	11580
ISDYNVOLMsgCountValidCount_Cnt_M_u16	16609
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	9265
ISDYNVOLMsgLenValidCount_Cnt_M_u16	8126
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	5275
ISDYNVOLMsgTimer_mS_M_u32	916370176
IgnOnTimer_mS_M_u32	2460152576
IgnTimeOff_Sec_M_u32	784085638
ManVehSpd_Kph_M_f32	519.67981
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	38
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	75
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3248497408
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	74
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	842105600
PrevISDATBSI412MsgDLCError_Cnt_M_u08	69
PrevISDATBSI412MsgRxTime_MSec_M_u32	3836556032
PrevISDATBSI432MsgDLCError_Cnt_M_u08	146
PrevISDATBSI432MsgRxTime_MSec_M_u32	896406272
PrevISDATDIRAMsgTxTime_MSec_M_u32	137442048
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	108
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2830615296
PrevISDYNAASMsgDLCError_Cnt_M_u08	122
PrevISDYNAASMsgRxTime_MSec_M_u32	1820635904
PrevISDYNABRMsgDLCError_Cnt_M_u08	104
PrevISDYNABRMsgRxTime_MSec_M_u32	2235233024
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	242
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1289597696
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	154
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3683980032
PrevISDYNVOLMsgDLCError_Cnt_M_u08	179
PrevISDYNVOLMsgRxTime_MSec_M_u32	1421751040
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4241187584
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	512.256897
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	56272
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	29541
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	18589
VitesseVehicleBVRampValidCount_Cnt_M_u16	53234
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	56779
VitesseVehicleBVSigValidCount_Cnt_M_u16	3368
VitesseVehicleBV_Kph_M_f32	81.7415009
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	41398
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	20779
VitesseVehiculeRoues_Kph_M_f32	456.559906
k_AASNTCEnableTimeout_mS_u16	50564
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	52303
k_AASNodeTimeout_mS_u16	21093
k_ABSNodeTimeout_mS_u16	17519
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	32270
k_ANGLEVOLANTSigValidThresh_Cnt_u16	54423
k_AngleVolantInvalidThresh_Cnt_u16	48818
k_AngleVolantValidThresh_Cnt_u16	12298
k_BSI552MsgTimeout_mS_u16	31494
k_BSINTCEnableTimeout_mS_u16	13671
k_BSINodeAbsentDiag_Cnt_str.Threshold	8538
k_BSINodeAbsentDiag_Cnt_str.PStep	56406
k_BSINodeAbsentDiag_Cnt_str.NStep	63670
k_BSINodeAbsentTimeout_mS_u16	11504
k_BSINodeTimeout_mS_u16	59160
k_BattOvHi_Volt_f32	26.3875999
k_BattOvLo_Volt_f32	3.59780002
k_BattUvHi_Volt_f32	0.676500022
k_BattUvLo_Volt_f32	28.7971992
k_CAVNTCEnableTimeout_mS_u16	50440
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	19561
k_CAVNodeTimeout_mS_u16	43889
k_CMM388MsgTimeout_mS_u16	41943
k_CMM388NTCEnableTimeout_mS_u16	25251
k_CMMNTCEnableTimeout_mS_u16	8154
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	56823
k_CONSANGLECPKMax_HwDeg_f32	0
k_CONSANGLECPKMin_HwDeg_f32	-221.896805
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	16566
k_CONSANGLECPKSigValidThresh_Cnt_u16	12331
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	23219
k_CPKVehicleSpeedValidThresh_Cnt_u16	43532
k_CityParkInputInvalidThresh_Cnt_u16	53617
k_CityParkInputValidThresh_Cnt_u16	30340
k_ComputerRazGCTSigValidThresh_Cnt_u16	27248
k_CptTemporelSigValidThresh_Cnt_u16	31825
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	20824
k_DMDFCTCPKSigValidThresh_Cnt_u16	21701
k_DMDFCTCPKValidCount_Cnt_u16	23449
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	55305
k_DMDRELAXECPKSigValidThresh_Cnt_u16	23406
k_DMDRelaxeConsistentThresh_Cnt_u16	46524
k_DateValidThresh_Cnt_u16	36169
k_DefaultVehSpd_Kph_f32	243.894608
k_DiagMuxOnAbsentTimeout_mS_u16	52855
k_EMNodeTimeout_mS_u16	36614
k_ESPNTCEnableTimeout_mS_u16	5839
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	58207
k_EtatMTSigInvalidThresh_Cnt_u16	52254
k_EtatMTSigValidThresh_Cnt_u16	19939
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	57658
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	54547
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	48465
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	40547
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	53380
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	36633
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	59248
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	58233
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	20739
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	60173
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	31998
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	15613
k_ISDATDIRASentDiag_Cnt_str.Threshold	35056

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	8835
k_ISDATDIRASentDiag_Cnt_str.NStep	19771
k_ISDATDIRASentTimeout_mS_u16	53871
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	14038
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	61528
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	43371
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	57763
k_ISDYNAASChkSumValidThresh_Cnt_u16	60712
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	32292
k_ISDYNAASMsgCountValidThresh_Cnt_u16	50594
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	37335
k_ISDYNAASMsgLenValidThresh_Cnt_u16	64921
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	53247
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	24254
k_ISDYNABRChkSumValidThresh_Cnt_u16	49835
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	18481
k_ISDYNABRMsgCountValidThresh_Cnt_u16	38926
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	62363
k_ISDYNABRMsgLenValidThresh_Cnt_u16	18916
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	42345
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	42756
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	27634
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	53056
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	24702
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	16411
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	16546
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	28836
k_ISDYNVOLChkSumValidThresh_Cnt_u16	11574
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	12645
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	7260
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	32529
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	19850
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	13511
k_IgnOnTimeout_mS_u16	33904
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	102.324799
k_PowerCutVehSpdLowThresh_Kph_f32	160.9263
k_PowerCutVehSpdLowTimeout_mS_u16	49152
k_VBattMaxAAS_Volt_f32	2.41170001
k_VBattMaxBSI_Volt_f32	18.1357994
k_VBattMaxCAV_Volt_f32	11.5601997
k_VBattMaxCMM388_Volt_f32	11.7792997
k_VBattMaxCMM_Volt_f32	9.95590019
k_VBattMaxESP_Volt_f32	8.2038002
k_VBattMinAAS_Volt_f32	27.2528992
k_VBattMinBSI_Volt_f32	8.2038002
k_VBattMinCAV_Volt_f32	26.9207993
k_VBattMinCMM388_Volt_f32	19.6755009
k_VBattMinCMM_Volt_f32	22.9619007
k_VBattMinESP_Volt_f32	9.95590019
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	30088
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	53769
k_VitesseVehicleBVRampValidThresh_Cnt_u16	52284
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	51640
k_VitesseVehicleBVSigValidThresh_Cnt_u16	38377
k_VitesseVehicleBVSpeedPassThresh_kph_f32	93.8803024
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	37379
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	31192
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	857756416
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	58941
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	4201494016
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	154
target_SrlComInput_Per1_Batt_Volt_f32.value	17.2747993
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1187382016
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	126
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.330581337
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4259640064
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	362713856
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	185
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3748147968
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2202129152
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	690713344
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	193
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4179956480
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	456045312
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	42
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	226
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2364461824
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	25
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	164
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	178
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	138
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	816575232
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1776653056
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	355414784
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	52
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	78
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	207
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	215
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1763410688
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	74
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.327857375
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	923331
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	251.090607
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	49666

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4201494016	4201494016	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4201494016	4201494016	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	4201494016	4201494016	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4201494016	4201494016	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4201494016	4201494016	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4201494016	4201494016	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4201494016	4201494016	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	4201494016	4201494016	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4201494016	4201494016	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4201494016	4201494016	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4201494016	4201494016	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4201494016	4201494016	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4201494016	4201494016	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	18937	18937	✔
CONSANGLECPK_HwDeg_M_f32	-749.57251	-749.57251 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4201494016	4201494016	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	4201494016	4201494016	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4201494016	4201494016	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4201494016	4201494016	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4201494016	4201494016	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4201494016	4201494016	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4201494016	4201494016	✔
ESPNTCEnableTimer_mS_M_u32	4201494016	4201494016	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4201494016	4201494016	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2500	2500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3501	3501	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	4201494016	4201494016	✔
ElecIntTimer_mS_M_u32[1]	14	14	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	4201494016	4201494016	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4201494016	4201494016	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4201494016	4201494016	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4201494016	4201494016	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4201494016	4201494016	✔
ISDATDIRASentFltAcc_Cnt_M_u16	35056	35056	✔
ISDATDIRASentTimer_mS_M_u32	4201494016	4201494016	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4201494016	4201494016	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4201494016	4201494016	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4201494016	4201494016	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4201494016	4201494016	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4201494016	4201494016	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4201494016	4201494016	✔
IgnOnTimer_mS_M_u32	4201494016	4201494016	✔
IgnTimeOff_Sec_M_u32	784085638	784085638	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4259640064	4259640064	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	205	205	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	362713856	362713856	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	185	185	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3748147968	3748147968	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	235	235	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2202129152	2202129152	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	137442048	137442048	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	193	193	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4179956480	4179956480	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	181	181	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	456045312	456045312	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	205	205	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2364461824	2364461824	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	138	138	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	816575232	816575232	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	153	153	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1776653056	1776653056	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	134	134	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	355414784	355414784	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1763410688	1763410688	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	512.256897	512.256897	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	81.7415009	81.7415009	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	456.559906	456.559906	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	18937	18937	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	784085638	784085638	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-749.57251	-749.57251 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.427 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	200055296
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	58467
AASNodeAbsentTimer_mS_M_u32	2917894656
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	26735
ANGLEVOLANTSigValidCount_Cnt_M_u16	47704
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	58848
AngleVolantMsgTimer_mS_M_u32	200055296
AngleVolantValidCount_Cnt_M_u16	4985
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1672169984
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3343501824
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3171891712
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1300101632
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	15702
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3556227584
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	44641
CAVNodeAbsentTimer_mS_M_u32	3349293568
CDD_SrlComVehSpd_Kph_G_f32	264.481506
CMM388NTCEnableTimer_mS_M_u32	1869507072
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	297282048
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	30552
CMMNodeAbsentTimer_mS_M_u32	4192729600
CONSANGLECPKSigInvalidCount_Cnt_M_u16	58107
CONSANGLECPKSigValidCount_Cnt_M_u16	39475
CONSANGLECPK_Cnt_M_u16	9918
CONSANGLECPK_HwDeg_M_f32	282.192993
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	9918
CPKVehicleSpeedMsgTimer_mS_M_u32	386636288
CPKVehicleSpeedValidCount_Cnt_M_u16	50930
CityParkInputConsistentCount_Cnt_M_u16	2525
CityParkInputInvalidCount_Cnt_M_u16	50762
CityParkInputMsgTimer_mS_M_u32	4259640064
CityParkInputValidCount_Cnt_M_u16	6

Name	Input Value
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1028622848
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	12487
ComputerRazGCTSigInvalidTimer_mS_M_u32	2008197632
ComputerRazGCTSigValidCount_Cnt_M_u16	58130
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	11238
DMDFCTCPKSigValidCount_Cnt_M_u16	9014
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	6817
DMDRELAXECPKSigValidCount_Cnt_M_u16	3594
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	15736
DateInvalidTimer_mS_M_u32	3343501824
DiagMuxOnAbsentTimer_mS_M_u32	3175504384
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1300101632
ESPNTCEnableTimer_mS_M_u32	1653377536
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	5436
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	28
EffacDefaultDiagTimer_mS_M_u32[1]	29
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	5
ElecIntTimer_mS_M_u32[1]	156
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2357836288
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	63321
EtatMTSigValidCount_Cnt_M_u16	61358
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	43821
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	33765
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	59212
ISDAT4V2BSI552MsgTimer_mS_M_u32	206305792
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	58851
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	25727
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	61358
ISDATBSI3F2MsgTimer_mS_M_u32	219437568
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	7673
ISDATBSI412MsgLenValidCount_Cnt_M_u16	19653
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	63321
ISDATBSI412MsgTimer_mS_M_u32	2713360896
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	19644
ISDATBSI432MsgLenValidCount_Cnt_M_u16	60832
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	26146
ISDATDIRASentFltAcc_Cnt_M_u16	23702
ISDATDIRASentTimer_mS_M_u32	386636288
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	21772
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	4985
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	35405
ISDYN2CMMMsgTimer_mS_M_u32	729188864
ISDYNAASChkSumInvalidCount_Cnt_M_u16	8853
ISDYNAASChkSumValidCount_Cnt_M_u16	36253
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	47072
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	14124
ISDYNAASMsgLenValidCount_Cnt_M_u16	58029
ISDYNAASMsgTimeValidCount_Cnt_M_u16	8853
ISDYNAASMsgTimer_mS_M_u32	4194986496
ISDYNABRChkSumInvalidCount_Cnt_M_u16	36992
ISDYNABRChkSumValidCount_Cnt_M_u16	65201
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	51580
ISDYNABRMsgCountValidCount_Cnt_M_u16	25540
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	11490
ISDYNABRMsgLenValidCount_Cnt_M_u16	21338
ISDYNABRMsgTimeValidCount_Cnt_M_u16	9918
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	50708
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	58537
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	61358
ISDYNCMM208MsgTimer_mS_M_u32	689981952

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	50708
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	58537
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	53319
ISDYNCMM388MsgTimer_mS_M_u32	3990743552
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	60105
ISDYNVOLChkSumValidCount_Cnt_M_u16	32897
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	5812
ISDYNVOLMsgCountValidCount_Cnt_M_u16	11396
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	40277
ISDYNVOLMsgLenValidCount_Cnt_M_u16	39790
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	30552
ISDYNVOLMsgTimer_mS_M_u32	776907264
IgnOnTimer_mS_M_u32	2067917312
IgnTimeOff_Sec_M_u32	1024696906
ManVehSpd_Kph_M_f32	402.076385
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	39
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	102
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2668255744
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	48
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3403037184
PrevISDATBSI412MsgDLCError_Cnt_M_u08	75
PrevISDATBSI412MsgRxTime_MSec_M_u32	2116233728
PrevISDATBSI432MsgDLCError_Cnt_M_u08	174
PrevISDATBSI432MsgRxTime_MSec_M_u32	660638208
PrevISDATDIRAMsgTxTime_MSec_M_u32	597109248
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	115
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1346599424
PrevISDYNAASMsgDLCError_Cnt_M_u08	138
PrevISDYNAASMsgRxTime_MSec_M_u32	2761730560
PrevISDYNABRMsgDLCError_Cnt_M_u08	66
PrevISDYNABRMsgRxTime_MSec_M_u32	58321408
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	195
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2811341312
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	250
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2431355392
PrevISDYNVOLMsgDLCError_Cnt_M_u08	41
PrevISDYNVOLMsgRxTime_MSec_M_u32	2985306624
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2861079040
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	217.316101
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	26618
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	45563
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	38291
VitesseVehicleBVRampValidCount_Cnt_M_u16	4180
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	1928
VitesseVehicleBVSigValidCount_Cnt_M_u16	43569
VitesseVehicleBV_Kph_M_f32	367.958588
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	53319
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	21159

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	308.773895
k_AASNTCEnableTimeout_mS_u16	40989
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	62588
k_AASNodeTimeout_mS_u16	5371
k_ABSNodeTimeout_mS_u16	23835
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	50943
k_ANGLEVOLANTSigValidThresh_Cnt_u16	42019
k_AngleVolantInvalidThresh_Cnt_u16	4562
k_AngleVolantValidThresh_Cnt_u16	50762
k_BSI552MsgTimeout_mS_u16	278
k_BSINTCEnableTimeout_mS_u16	17652
k_BSINodeAbsentDiag_Cnt_str.Threshold	36569
k_BSINodeAbsentDiag_Cnt_str.PStep	11985
k_BSINodeAbsentDiag_Cnt_str.NStep	49724
k_BSINodeAbsentTimeout_mS_u16	36888
k_BSINodeTimeout_mS_u16	26146
k_BattOvHi_Volt_f32	0.203999996
k_BattOvLo_Volt_f32	27.6629009
k_BattUvHi_Volt_f32	26.3659
k_BattUvLo_Volt_f32	31.4738998
k_CAVNTCEnableTimeout_mS_u16	32592
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	47663
k_CAVNodeTimeout_mS_u16	26007
k_CMM388MsgTimeout_mS_u16	34659
k_CMM388NTCEnableTimeout_mS_u16	31487
k_CMMNTCEnableTimeout_mS_u16	47643
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	56387
k_CONSANGLECPKMax_HwDeg_f32	780
k_CONSANGLECPKMin_HwDeg_f32	-649.262817
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	62279
k_CONSANGLECPKSigValidThresh_Cnt_u16	46503
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	46097
k_CPKVehicleSpeedValidThresh_Cnt_u16	46212
k_CityParkInputInvalidThresh_Cnt_u16	39958
k_CityParkInputValidThresh_Cnt_u16	2525
k_ComputerRazGCTSigValidThresh_Cnt_u16	45657
k_CptTemporelSigValidThresh_Cnt_u16	48501
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	53218
k_DMDFCTCPKSigValidThresh_Cnt_u16	13914
k_DMDFCTCPKValidCount_Cnt_u16	17950
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	35405
k_DMDRELAXECPKSigValidThresh_Cnt_u16	20701
k_DMDRelaxeConsistentThresh_Cnt_u16	63987
k_DateValidThresh_Cnt_u16	59212
k_DefaultVehSpd_Kph_f32	179.733307
k_DiagMuxOnAbsentTimeout_mS_u16	4420
k_EMNodeTimeout_mS_u16	20184
k_ESPNTCEnableTimeout_mS_u16	29437
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	27659
k_EtatMTSigInvalidThresh_Cnt_u16	40975
k_EtatMTSigValidThresh_Cnt_u16	60288
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	64636
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	16816
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	43382
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	41600
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	19676
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	31069
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	37593
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	32637
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	25120
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	37762

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	24175
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	3251
k_ISDATDIRASentDiag_Cnt_str.Threshold	45598
k_ISDATDIRASentDiag_Cnt_str.PStep	35197
k_ISDATDIRASentDiag_Cnt_str.NStep	1197
k_ISDATDIRASentTimeout_mS_u16	4380
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	49960
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58848
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	11049
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	45952
k_ISDYNAASChkSumValidThresh_Cnt_u16	25009
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	27772
k_ISDYNAASMsgCountValidThresh_Cnt_u16	18116
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	29412
k_ISDYNAASMsgLenValidThresh_Cnt_u16	58207
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	20971
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	49072
k_ISDYNABRChkSumValidThresh_Cnt_u16	1192
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	57430
k_ISDYNABRMsgCountValidThresh_Cnt_u16	8575
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	55896
k_ISDYNABRMsgLenValidThresh_Cnt_u16	47164
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	9582
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	54878
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	34514
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	51818
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	2927
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	40280
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	62594
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	49340
k_ISDYNVOLChkSumValidThresh_Cnt_u16	35784
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	17849
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	42005
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	57589
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	5706
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	26834
k_IgnOnTimeout_mS_u16	46424
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	60.9427986
k_PowerCutVehSpdLowThresh_Kph_f32	117.1381
k_PowerCutVehSpdLowTimeout_mS_u16	41129
k_VBattMaxAAS_Volt_f32	7.38500023
k_VBattMaxBSI_Volt_f32	4.10529995
k_VBattMaxCAV_Volt_f32	2.3369
k_VBattMaxCMM388_Volt_f32	8.44719982
k_VBattMaxCMM_Volt_f32	14.7876997
k_VBattMaxESP_Volt_f32	1.19149995
k_VBattMinAAS_Volt_f32	17.5205002
k_VBattMinBSI_Volt_f32	1.19149995
k_VBattMinCAV_Volt_f32	1.72679996
k_VBattMinCMM388_Volt_f32	9.60550022
k_VBattMinCMM_Volt_f32	19.1788006
k_VBattMinESP_Volt_f32	14.7876997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	20242
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	64078
k_VitesseVehicleBVRampValidThresh_Cnt_u16	14772
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	25473
k_VitesseVehicleBVSigValidThresh_Cnt_u16	32686
k_VitesseVehicleBVSpeedPassThresh_kph_f32	178.353607
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	53601
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	10914
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3343501824
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	5909
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3601703168
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	250
target_SrlComInput_Per1_Batt_Volt_f32.value	10.9778004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2132326912
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	216
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.343053639
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	27
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3246123520
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3905882624
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	972171776
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	4
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1021659648
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2041080320
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2017167872
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	146
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3231623680
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	69
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	131
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	149
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	333335040
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	57
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	71
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	153
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	183
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	223
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	86436352
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3355052544
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1956456960
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	105
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	117
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	181
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	238
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	248
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1310210560
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2010
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.473100632
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	349069
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	98.8952026
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	64868

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3601703168	3601703168	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3601703168	3601703168	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3601703168	3601703168	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3601703168	3601703168	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3601703168	3601703168	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3601703168	3601703168	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3601703168	3601703168	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	36569	36569	✔
BSINodeAbsentTimer_mS_M_u32	3601703168	3601703168	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3601703168	3601703168	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3601703168	3601703168	✔
CDD_SrlComVehSpd_Kph_G_f32	402.076385	402.076385	✔
CMM388NTCEnableTimer_mS_M_u32	3601703168	3601703168	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3601703168	3601703168	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3601703168	3601703168	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	9918	9918	✔
CONSANGLECPK_HwDeg_M_f32	282.192993	282.192993 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3601703168	3601703168	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3601703168	3601703168	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3601703168	3601703168	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3601703168	3601703168	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3601703168	3601703168	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3601703168	3601703168	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3601703168	3601703168	✔
ESPNTCEnableTimer_mS_M_u32	3601703168	3601703168	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3601703168	3601703168	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	28	28	✔
EffacDefaultDiagTimer_mS_M_u32[1]	29	29	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	5	5	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	156	156	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3601703168	3601703168	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	59212	59212	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3601703168	3601703168	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	61358	61358	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3601703168	3601703168	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	63321	63321	✔
ISDATBSI412MsgTimer_mS_M_u32	3601703168	3601703168	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	26146	26146	✔
ISDATBSI432MsgTimer_mS_M_u32	3601703168	3601703168	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3601703168	3601703168	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	35405	35405	✔
ISDYN2CMMMsgTimer_mS_M_u32	3601703168	3601703168	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	8853	8853	✔
ISDYNAASMsgTimer_mS_M_u32	3601703168	3601703168	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	9918	9918	✔
ISDYNABRMsgTimer_mS_M_u32	3601703168	3601703168	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	61358	61358	✔
ISDYNCMM208MsgTimer_mS_M_u32	3601703168	3601703168	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	53319	53319	✔
ISDYNCMM388MsgTimer_mS_M_u32	3601703168	3601703168	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	30552	30552	✔
ISDYNVOLMsgTimer_mS_M_u32	3601703168	3601703168	✔
IgnOnTimer_mS_M_u32	2067917312	2067917312	✔
IgnTimeOff_Sec_M_u32	1024696906	1024696906	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	27	27	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3246123520	3246123520	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	0	0	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3905882624	3905882624	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	972171776	972171776	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	4	4	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1021659648	1021659648	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	597109248	597109248	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2017167872	2017167872	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	146	146	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3231623680	3231623680	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	84	84	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	333335040	333335040	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	88	88	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	86436352	86436352	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	121	121	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3355052544	3355052544	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	64	64	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1956456960	1956456960	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1310210560	1310210560	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	217.316101	217.316101	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	367.958588	367.958588	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	308.773895	308.773895	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	9918	9918	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1024696906	1024696906	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	282.192993	282.192993 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	402.076385	402.076385	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.428 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2864772352
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	7005
AASNodeAbsentTimer_mS_M_u32	2894341376
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	24887
ANGLEVOLANTSigValidCount_Cnt_M_u16	55614
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	19174
AngleVolantMsgTimer_mS_M_u32	2864772352
AngleVolantValidCount_Cnt_M_u16	3739
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	977593600
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2842256640
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3923318016
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1670173952
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	16002
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3877606656
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	32737
CAVNodeAbsentTimer_mS_M_u32	31474944
CDD_SrlComVehSpd_Kph_G_f32	239.204895
CMM388NTCEnableTimer_mS_M_u32	2340128000
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4221453568
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	39869
CMMNodeAbsentTimer_mS_M_u32	2253313280
CONSANGLECPKSigInvalidCount_Cnt_M_u16	53396
CONSANGLECPKSigValidCount_Cnt_M_u16	22699
CONSANGLECPK_Cnt_M_u16	40714
CONSANGLECPK_HwDeg_M_f32	580.90918
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	40714
CPKVehicleSpeedMsgTimer_mS_M_u32	3311662336
CPKVehicleSpeedValidCount_Cnt_M_u16	40662
CityParkInputConsistentCount_Cnt_M_u16	47983
CityParkInputInvalidCount_Cnt_M_u16	52007
CityParkInputMsgTimer_mS_M_u32	3246123520
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2388141312
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	50737

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3551446272
ComputerRazGCTSigValidCount_Cnt_M_u16	17360
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	2643
DMDFCTCPKSigValidCount_Cnt_M_u16	12834
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	37537
DMDRELAXECPKSigValidCount_Cnt_M_u16	9768
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	62749
DateInvalidTimer_mS_M_u32	2842256640
DiagMuxOnAbsentTimer_mS_M_u32	766752000
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1670173952
ESPNTCEnableTimer_mS_M_u32	1386292480
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	8144
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	200
EffacDefaultDiagTimer_mS_M_u32[1]	300
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1111
ElecIntTimer_mS_M_u32[1]	2223
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2238289152
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	45241
EtatMTSigValidCount_Cnt_M_u16	58748
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	49150
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	58261
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	48608
ISDAT4V2BSI552MsgTimer_mS_M_u32	3743601920
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	17053
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	1160
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	58748
ISDATBSI3F2MsgTimer_mS_M_u32	4132025600
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	50010
ISDATBSI412MsgLenValidCount_Cnt_M_u16	13493
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	45241
ISDATBSI412MsgTimer_mS_M_u32	2706830592
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	43921
ISDATBSI432MsgLenValidCount_Cnt_M_u16	9892
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	40094
ISDATDIRASentFltAcc_Cnt_M_u16	35138
ISDATDIRASentTimer_mS_M_u32	3311662336
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	52256
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	3739
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	19230
ISDYN2CMMMsgTimer_mS_M_u32	534979840
ISDYNAASChkSumInvalidCount_Cnt_M_u16	43207
ISDYNAASChkSumValidCount_Cnt_M_u16	21870
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	32102
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	53632
ISDYNAASMsgLenValidCount_Cnt_M_u16	40127
ISDYNAASMsgTimeValidCount_Cnt_M_u16	43207
ISDYNAASMsgTimer_mS_M_u32	1537705216
ISDYNABRChkSumInvalidCount_Cnt_M_u16	26243
ISDYNABRChkSumValidCount_Cnt_M_u16	43442
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	4114
ISDYNABRMsgCountValidCount_Cnt_M_u16	12025
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	20191
ISDYNABRMsgLenValidCount_Cnt_M_u16	35126
ISDYNABRMsgTimeValidCount_Cnt_M_u16	40714
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	61576
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	45707
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	58748
ISDYNCMM208MsgTimer_mS_M_u32	4259702016
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	61576
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	45707
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	36913

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	774702336
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	28970
ISDYNVOLChkSumValidCount_Cnt_M_u16	24001
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	489
ISDYNVOLMsgCountValidCount_Cnt_M_u16	52792
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	11141
ISDYNVOLMsgLenValidCount_Cnt_M_u16	24315
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	39869
ISDYNVOLMsgTimer_mS_M_u32	534430976
IgnOnTimer_mS_M_u32	369165568
IgnTimeOff_Sec_M_u32	3134764720
ManVehSpd_Kph_M_f32	215.481293
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	37
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	18
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2556933376
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	97
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2625901824
PrevISDATBSI412MsgDLCError_Cnt_M_u08	238
PrevISDATBSI412MsgRxTime_MSec_M_u32	576537856
PrevISDATBSI432MsgDLCError_Cnt_M_u08	226
PrevISDATBSI432MsgRxTime_MSec_M_u32	1411720448
PrevISDATDIRAMsgTxTime_MSec_M_u32	33637632
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	157
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1362908416
PrevISDYNAASMsgDLCError_Cnt_M_u08	142
PrevISDYNAASMsgRxTime_MSec_M_u32	1961936128
PrevISDYNABRMsgDLCError_Cnt_M_u08	233
PrevISDYNABRMsgRxTime_MSec_M_u32	1566115072
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	5
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2148648192
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	216
PrevISDYNCMM388MsgRxTime_MSec_M_u32	58991872
PrevISDYNVOLMsgDLCError_Cnt_M_u08	214
PrevISDYNVOLMsgRxTime_MSec_M_u32	4210443520
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1055716608
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	78.1694031
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	63254
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	59093
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	4683
VitesseVehicleBVRampValidCount_Cnt_M_u16	28618
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	10220
VitesseVehicleBVSigValidCount_Cnt_M_u16	44467
VitesseVehicleBV_Kph_M_f32	423.592712
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	36913
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	22223
VitesseVehiculeRoues_Kph_M_f32	30.6947994
k_AASNTCEnableTimeout_mS_u16	28397
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	14226
k_AASNodeTimeout_mS_u16	48597
k_ABSNodeTimeout_mS_u16	35508
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	2248
k_ANGLEVOLANTSigValidThresh_Cnt_u16	53019
k_AngleVolantInvalidThresh_Cnt_u16	526
k_AngleVolantValidThresh_Cnt_u16	52007
k_BSI552MsgTimeout_mS_u16	51074
k_BSINTCEnableTimeout_mS_u16	41705
k_BSINodeAbsentDiag_Cnt_str.Threshold	16826
k_BSINodeAbsentDiag_Cnt_str.PStep	29715
k_BSINodeAbsentDiag_Cnt_str.NStep	39952
k_BSINodeAbsentTimeout_mS_u16	11326
k_BSINodeTimeout_mS_u16	40094
k_BattOvHi_Volt_f32	25.5118999
k_BattOvLo_Volt_f32	0.8671
k_BattUvHi_Volt_f32	2.44140005
k_BattUvLo_Volt_f32	11.2065001
k_CAVNTCEnableTimeout_mS_u16	14357
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	5239
k_CAVNodeTimeout_mS_u16	47296
k_CMM388MsgTimeout_mS_u16	12893
k_CMM388NTCEnableTimeout_mS_u16	51081
k_CMMNTCEnableTimeout_mS_u16	42485
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	10747
k_CONSANGLECPKMax_HwDeg_f32	0.384299994
k_CONSANGLECPKMin_HwDeg_f32	-237.829193
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	10033
k_CONSANGLECPKSigValidThresh_Cnt_u16	11727
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	47251
k_CPKVehicleSpeedValidThresh_Cnt_u16	60345
k_CityParkInputInvalidThresh_Cnt_u16	7105
k_CityParkInputValidThresh_Cnt_u16	47983
k_ComputerRazGCTSigValidThresh_Cnt_u16	13627
k_CptTemporelSigValidThresh_Cnt_u16	20902
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	26079
k_DMDFCTCPKSigValidThresh_Cnt_u16	57398
k_DMDFCTCPKValidCount_Cnt_u16	17450
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	19230
k_DMDRELAXECPKSigValidThresh_Cnt_u16	1325
k_DMDRelaxeConsistentThresh_Cnt_u16	57835
k_DateValidThresh_Cnt_u16	48608
k_DefaultVehSpd_Kph_f32	87.8264999
k_DiagMuxOnAbsentTimeout_mS_u16	30584
k_EMNodeTimeout_mS_u16	16637
k_ESPNTCEnableTimeout_mS_u16	41485
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	39587
k_EtatMTSigInvalidThresh_Cnt_u16	13270
k_EtatMTSigValidThresh_Cnt_u16	57157
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	19282
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	6516
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	32932
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	49350
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	65393
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	16686
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	36154
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	9485
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	64357
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	26814
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	34233
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	45100
k_ISDATDIRASentDiag_Cnt_str.Threshold	58745

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	41340
k_ISDATDIRASentDiag_Cnt_str.NStep	16989
k_ISDATDIRASentTimeout_mS_u16	21679
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	41165
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	19174
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10633
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	64899
k_ISDYNAASChkSumValidThresh_Cnt_u16	32946
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	10002
k_ISDYNAASMsgCountValidThresh_Cnt_u16	34297
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	20311
k_ISDYNAASMsgLenValidThresh_Cnt_u16	58025
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	58819
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	20085
k_ISDYNABRChkSumValidThresh_Cnt_u16	11596
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	21890
k_ISDYNABRMsgCountValidThresh_Cnt_u16	65481
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	29373
k_ISDYNABRMsgLenValidThresh_Cnt_u16	14032
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	28668
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	15338
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	11471
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	6536
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	30775
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	12350
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	8319
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	42769
k_ISDYNVOLChkSumValidThresh_Cnt_u16	17324
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	49753
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	18822
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	25573
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	57768
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	53582
k_IgnOnTimeout_mS_u16	14653
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	26.6980991
k_PowerCutVehSpdLowThresh_Kph_f32	186.112106
k_PowerCutVehSpdLowTimeout_mS_u16	40265
k_VBattMaxAAS_Volt_f32	4.27409983
k_VBattMaxBSI_Volt_f32	14.4356003
k_VBattMaxCAV_Volt_f32	18.2261009
k_VBattMaxCMM388_Volt_f32	12.5925999
k_VBattMaxCMM_Volt_f32	23.9605999
k_VBattMaxESP_Volt_f32	22.3069992
k_VBattMinAAS_Volt_f32	16.8901005
k_VBattMinBSI_Volt_f32	22.3069992
k_VBattMinCAV_Volt_f32	15.6413002
k_VBattMinCMM388_Volt_f32	0.577499986
k_VBattMinCMM_Volt_f32	12.5598001
k_VBattMinESP_Volt_f32	23.9605999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	9487
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	57625
k_VitesseVehicleBVRampValidThresh_Cnt_u16	39145
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	46273
k_VitesseVehicleBVSigValidThresh_Cnt_u16	56828
k_VitesseVehicleBVSpeedPassThresh_kph_f32	139.293793
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	5857
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	55520
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2842256640
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	216
target_SrlComInput_Per1_Batt_Volt_f32.value	6.82000017
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2847708416
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	161
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.537971973
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	124
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2874344704
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3923354880
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	211
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3941614848
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	188
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	378987776
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3570238720
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	19
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2375296256
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	80
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2833958144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	18
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	203
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	214
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	215
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3047941376
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	26
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	62
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1280443648
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3092817152
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2800698624
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	55
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	183
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	209
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	239
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2596148480
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2595
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.616900444
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	936830
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	252.090897
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	24280

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	16826	16826	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	215.481293	215.481293	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	40714	40714	✔
CONSANGLECPK_HwDeg_M_f32	580.90918	580.90918 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3251510528	3251510528	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	200	200	✔
EffacDefaultDiagTimer_mS_M_u32[1]	300	300	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1111	1111	✔
ElecIntTimer_mS_M_u32[1]	2223	2223	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	48608	48608	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	58748	58748	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	45241	45241	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	40094	40094	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	19230	19230	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	43207	43207	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	40714	40714	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	58748	58748	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	36913	36913	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	39869	39869	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	369165568	369165568	✔
IgnTimeOff_Sec_M_u32	3134764720	3134764720	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	124	124	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2874344704	2874344704	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	224	224	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3923354880	3923354880	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	211	211	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3941614848	3941614848	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	188	188	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	378987776	378987776	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	33637632	33637632	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	19	19	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2375296256	2375296256	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	80	80	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2833958144	2833958144	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	241	241	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3047941376	3047941376	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	46	46	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1280443648	1280443648	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3092817152	3092817152	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2800698624	2800698624	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2596148480	2596148480	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	78.1694031	78.1694031	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	423.592712	423.592712	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	30.6947994	30.6947994	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	40714	40714	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3134764720	3134764720	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	580.90918	580.90918 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.429 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1490395648
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	7644
AASNodeAbsentTimer_mS_M_u32	1973064192
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	12856
ANGLEVOLANTSigValidCount_Cnt_M_u16	44631
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	25209
AngleVolantMsgTimer_mS_M_u32	1490395648
AngleVolantValidCount_Cnt_M_u16	47078
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1425166848
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2250297856
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3309060608
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2745369088
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	1663
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	838124032
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	10398
CAVNodeAbsentTimer_mS_M_u32	2601857536
CDD_SrlComVehSpd_Kph_G_f32	85.0438995
CMM388NTCEnableTimer_mS_M_u32	3167318528
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	418066944
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	53491
CMMNodeAbsentTimer_mS_M_u32	2890727936
CONSANGLECPKSigInvalidCount_Cnt_M_u16	16860
CONSANGLECPKSigValidCount_Cnt_M_u16	17738
CONSANGLECPK_Cnt_M_u16	7093
CONSANGLECPK_HwDeg_M_f32	549.609314
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	7093
CPKVehicleSpeedMsgTimer_mS_M_u32	3193217536
CPKVehicleSpeedValidCount_Cnt_M_u16	44048
CityParkInputConsistentCount_Cnt_M_u16	61642
CityParkInputInvalidCount_Cnt_M_u16	25791
CityParkInputMsgTimer_mS_M_u32	2656475904
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3883831808
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	27840

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	1106620928
ComputerRazGCTSigValidCount_Cnt_M_u16	55327
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	2011
DMDFCTCPKSigValidCount_Cnt_M_u16	45665
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	26026
DMDRELAXECPKSigValidCount_Cnt_M_u16	62281
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	32633
DateInvalidTimer_mS_M_u32	2250297856
DiagMuxOnAbsentTimer_mS_M_u32	3188154880
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2745369088
ESPNTCEnableTimer_mS_M_u32	1742443008
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	12941
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	500
EffacDefaultDiagTimer_mS_M_u32[1]	600
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65535
ElecIntTimer_mS_M_u32[1]	95536
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3351691776
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	14588
EtatMTSigValidCount_Cnt_M_u16	27399
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	19278
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	57404
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	59959
ISDAT4V2BSI552MsgTimer_mS_M_u32	2167472640
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	33730
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	12564
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	27399
ISDATBSI3F2MsgTimer_mS_M_u32	3432342016
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	56832
ISDATBSI412MsgLenValidCount_Cnt_M_u16	2434
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	14588
ISDATBSI412MsgTimer_mS_M_u32	1835246080
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	18647
ISDATBSI432MsgLenValidCount_Cnt_M_u16	36209
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	12799
ISDATDIRASentFltAcc_Cnt_M_u16	1267
ISDATDIRASentTimer_mS_M_u32	3193217536
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	39107
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	47078
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	54690
ISDYN2CMMMsgTimer_mS_M_u32	3708129792
ISDYNAASChkSumInvalidCount_Cnt_M_u16	23886
ISDYNAASChkSumValidCount_Cnt_M_u16	50828
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	35757
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	58185
ISDYNAASMsgLenValidCount_Cnt_M_u16	36864
ISDYNAASMsgTimeValidCount_Cnt_M_u16	23886
ISDYNAASMsgTimer_mS_M_u32	2766500352
ISDYNABRChkSumInvalidCount_Cnt_M_u16	62342
ISDYNABRChkSumValidCount_Cnt_M_u16	16620
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	17301
ISDYNABRMsgCountValidCount_Cnt_M_u16	42003
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	43811
ISDYNABRMsgLenValidCount_Cnt_M_u16	58833
ISDYNABRMsgTimeValidCount_Cnt_M_u16	7093
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	63320
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	22544
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	27399
ISDYNCMM208MsgTimer_mS_M_u32	277303808
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	63320
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	22544
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	21364

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3563647488
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	2154
ISDYNVOLChkSumValidCount_Cnt_M_u16	31320
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	37225
ISDYNVOLMsgCountValidCount_Cnt_M_u16	60015
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	56134
ISDYNVOLMsgLenValidCount_Cnt_M_u16	20885
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	53491
ISDYNVOLMsgTimer_mS_M_u32	3591483904
IgnOnTimer_mS_M_u32	72151552
IgnTimeOff_Sec_M_u32	3021483590
ManVehSpd_Kph_M_f32	269.488708
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	38
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	250
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1581998592
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	111
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1046692352
PrevISDATBSI412MsgDLCError_Cnt_M_u08	2
PrevISDATBSI412MsgRxTime_MSec_M_u32	2604020224
PrevISDATBSI432MsgDLCError_Cnt_M_u08	224
PrevISDATBSI432MsgRxTime_MSec_M_u32	1697616384
PrevISDATDIRAMsgTxTime_MSec_M_u32	2099917312
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	200
PrevISDYN2CMMMsgRxTime_MSec_M_u32	458785280
PrevISDYNAASMsgDLCError_Cnt_M_u08	142
PrevISDYNAASMsgRxTime_MSec_M_u32	2602545664
PrevISDYNABRMsgDLCError_Cnt_M_u08	55
PrevISDYNABRMsgRxTime_MSec_M_u32	663024128
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	89
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2218045952
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	166
PrevISDYNCMM388MsgRxTime_MSec_M_u32	949654016
PrevISDYNVOLMsgDLCError_Cnt_M_u08	81
PrevISDYNVOLMsgRxTime_MSec_M_u32	1411592704
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3572605440
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	138.028
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	29399
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	19982
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	45328
VitesseVehicleBVRampValidCount_Cnt_M_u16	62727
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	20977
VitesseVehicleBVSigValidCount_Cnt_M_u16	22224
VitesseVehicleBV_Kph_M_f32	116.493401
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	21364
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	778
VitesseVehiculeRoues_Kph_M_f32	21.0545998
k_AASNTCEnableTimeout_mS_u16	6004
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	26057
k_AASNodeTimeout_mS_u16	37134
k_ABSNodeTimeout_mS_u16	18224
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	38906
k_ANGLEVOLANTSigValidThresh_Cnt_u16	212
k_AngleVolantInvalidThresh_Cnt_u16	29411
k_AngleVolantValidThresh_Cnt_u16	25791
k_BSI552MsgTimeout_mS_u16	60889
k_BSINTCEnableTimeout_mS_u16	56335
k_BSINodeAbsentDiag_Cnt_str.Threshold	324
k_BSINodeAbsentDiag_Cnt_str.PStep	13176
k_BSINodeAbsentDiag_Cnt_str.NStep	5312
k_BSINodeAbsentTimeout_mS_u16	59313
k_BSINodeTimeout_mS_u16	12799
k_BattOvHi_Volt_f32	6.10489988
k_BattOvLo_Volt_f32	6.12510014
k_BattUvHi_Volt_f32	19.8351994
k_BattUvLo_Volt_f32	19.1937008
k_CAVNTCEnableTimeout_mS_u16	6021
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	29484
k_CAVNodeTimeout_mS_u16	8696
k_CMM388MsgTimeout_mS_u16	41180
k_CMM388NTCEnableTimeout_mS_u16	37368
k_CMMNTCEnableTimeout_mS_u16	29434
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	18982
k_CONSANGLECPKMax_HwDeg_f32	127.884102
k_CONSANGLECPKMin_HwDeg_f32	-197.5681
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	22132
k_CONSANGLECPKSigValidThresh_Cnt_u16	17930
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	33764
k_CPKVehicleSpeedValidThresh_Cnt_u16	65131
k_CityParkInputInvalidThresh_Cnt_u16	41692
k_CityParkInputValidThresh_Cnt_u16	61642
k_ComputerRazGCTSigValidThresh_Cnt_u16	24568
k_CptTemporelSigValidThresh_Cnt_u16	59850
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	11811
k_DMDFCTCPKSigValidThresh_Cnt_u16	43217
k_DMDFCTCPKValidCount_Cnt_u16	5191
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	54690
k_DMDRELAXECPKSigValidThresh_Cnt_u16	5992
k_DMDRelaxeConsistentThresh_Cnt_u16	21566
k_DateValidThresh_Cnt_u16	59959
k_DefaultVehSpd_Kph_f32	144.221695
k_DiagMuxOnAbsentTimeout_mS_u16	28667
k_EMNodeTimeout_mS_u16	52441
k_ESPNTCEnableTimeout_mS_u16	35514
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	16110
k_EtatMTSigInvalidThresh_Cnt_u16	4981
k_EtatMTSigValidThresh_Cnt_u16	50715
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	25135
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	52505
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	57603
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	38783
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	34961
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	39908
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	22036
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	65134
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	187
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	9977
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	41628
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	39266
k_ISDATDIRASentDiag_Cnt_str.Threshold	44440

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	55056
k_ISDATDIRASentDiag_Cnt_str.NStep	15158
k_ISDATDIRASentTimeout_mS_u16	37282
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	58871
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	25209
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10854
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	63110
k_ISDYNAASChkSumValidThresh_Cnt_u16	33772
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	50837
k_ISDYNAASMsgCountValidThresh_Cnt_u16	26387
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	39018
k_ISDYNAASMsgLenValidThresh_Cnt_u16	41458
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	54172
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	56497
k_ISDYNABRChkSumValidThresh_Cnt_u16	50655
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	35199
k_ISDYNABRMsgCountValidThresh_Cnt_u16	48350
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	5107
k_ISDYNABRMsgLenValidThresh_Cnt_u16	46477
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	60717
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	9147
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	40825
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	58077
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	46392
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	29015
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	60919
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	9635
k_ISDYNVOLChkSumValidThresh_Cnt_u16	54629
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	1578
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	35024
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	57368
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	28451
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	13693
k_IgnOnTimeout_mS_u16	47039
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	155.571793
k_PowerCutVehSpdLowThresh_Kph_f32	21.0170994
k_PowerCutVehSpdLowTimeout_mS_u16	39808
k_VBattMaxAAS_Volt_f32	17.7040997
k_VBattMaxBSI_Volt_f32	19.9370995
k_VBattMaxCAV_Volt_f32	1.74619997
k_VBattMaxCMM388_Volt_f32	0.865400016
k_VBattMaxCMM_Volt_f32	19.8901005
k_VBattMaxESP_Volt_f32	19.8763008
k_VBattMinAAS_Volt_f32	30.5737991
k_VBattMinBSI_Volt_f32	19.8763008
k_VBattMinCAV_Volt_f32	17.5988998
k_VBattMinCMM388_Volt_f32	3.40440011
k_VBattMinCMM_Volt_f32	29.8512993
k_VBattMinESP_Volt_f32	19.8901005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	65057
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	23572
k_VitesseVehicleBVRampValidThresh_Cnt_u16	37993
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	15704
k_VitesseVehicleBVSigValidThresh_Cnt_u16	4667
k_VitesseVehicleBVSpeedPassThresh_kph_f32	133.777298
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	11166
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	56853
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2250297856
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	166
target_SrlComInput_Per1_Batt_Volt_f32.value	6.40990019
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2864038400
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	158
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.85729599
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	415691264
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	204
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3861778944
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1332032000
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3698086400
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	356741632
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2179633664
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2858529280
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	0
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	348672
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	48
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	170
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	234
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	978448896
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1396249088
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	177
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3354407424
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	118
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2095399424
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2749
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.896981657
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	80195
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	171.219498
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	1153

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	25211	25211	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	324	324	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	7093	7093	✔
CONSANGLECPK_HwDeg_M_f32	549.609314	549.609314 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	7093	7093	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3193217536	3193217536	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	44048	44048	✔
CityParkInputConsistentCount_Cnt_M_u16	61642	61642	✔
CityParkInputInvalidCount_Cnt_M_u16	25793	25793	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	500	500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	600	600	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3251510528	3251510528	✔
ElecIntTimer_mS_M_u32[1]	95536	95536	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	3251510528	3251510528	✔
IgnTimeOff_Sec_M_u32	3021483590	3021483590	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	15	15	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	26	26	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	415691264	415691264	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	204	204	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3861778944	3861778944	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	86	86	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1332032000	1332032000	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	64	64	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3698086400	3698086400	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2099917312	2099917312	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	84	84	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2179633664	2179633664	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	142	142	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2858529280	2858529280	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	348672	348672	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	221	221	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	978448896	978448896	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	123	123	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1396249088	1396249088	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	177	177	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3354407424	3354407424	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2095399424	2095399424	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	138.028	138.028	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	116.493401	116.493401	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	21.0545998	21.0545998	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	7093	7093	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3021483590	3021483590	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	549.609314	549.609314 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.430 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2451954944
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	32018
AASNodeAbsentTimer_mS_M_u32	3147238656
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	20988
ANGLEVOLANTSigValidCount_Cnt_M_u16	41825
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	25403
AngleVolantMsgTimer_mS_M_u32	2451954944
AngleVolantValidCount_Cnt_M_u16	65395
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	747621632
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1929661696
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2943483136
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	524139776
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	45351
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3947396352
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	12106
CAVNodeAbsentTimer_mS_M_u32	4255591680
CDD_SrlComVehSpd_Kph_G_f32	588.114929
CMM388NTCEnableTimer_mS_M_u32	3112856832
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1545940224
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	42252
CMMNodeAbsentTimer_mS_M_u32	759151872
CONSANGLECPKSigInvalidCount_Cnt_M_u16	25105
CONSANGLECPKSigValidCount_Cnt_M_u16	23942
CONSANGLECPK_Cnt_M_u16	17989
CONSANGLECPK_HwDeg_M_f32	-86.4291
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17989
CPKVehicleSpeedMsgTimer_mS_M_u32	497605888
CPKVehicleSpeedValidCount_Cnt_M_u16	56990

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	58567
CityParkInputInvalidCount_Cnt_M_u16	60904
CityParkInputMsgTimer_mS_M_u32	415691264
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4125822208
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	8294
ComputerRazGCTSigInvalidTimer_mS_M_u32	721792256
ComputerRazGCTSigValidCount_Cnt_M_u16	49864
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	29844
DMDFCTCPKSigValidCount_Cnt_M_u16	56000
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	65446
DMDRELAXECPKSigValidCount_Cnt_M_u16	7307
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	23866
DateInvalidTimer_mS_M_u32	1929661696
DiagMuxOnAbsentTimer_mS_M_u32	1502649600
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	524139776
ESPNTCEnableTimer_mS_M_u32	684985600
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	13821
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	123
EffacDefaultDiagTimer_mS_M_u32[1]	234
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4057103616
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	8688
EtatMTSigValidCount_Cnt_M_u16	401
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	36283
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	54448
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	2878
ISDAT4V2BSI552MsgTimer_mS_M_u32	1049869568
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	36640
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	7401
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	401
ISDATBSI3F2MsgTimer_mS_M_u32	3857095936
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	18789
ISDATBSI412MsgLenValidCount_Cnt_M_u16	7326
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	8688
ISDATBSI412MsgTimer_mS_M_u32	209444096
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	52576
ISDATBSI432MsgLenValidCount_Cnt_M_u16	46417
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	55079
ISDATDIRASentFltAcc_Cnt_M_u16	11851
ISDATDIRASentTimer_mS_M_u32	497605888
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	34587
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	65395
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	59199
ISDYN2CMMMsgTimer_mS_M_u32	4048948480
ISDYNAASChkSumInvalidCount_Cnt_M_u16	1724
ISDYNAASChkSumValidCount_Cnt_M_u16	4289
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	24606
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	27465
ISDYNAASMsgLenValidCount_Cnt_M_u16	35558
ISDYNAASMsgTimeValidCount_Cnt_M_u16	1724
ISDYNAASMsgTimer_mS_M_u32	1899392256
ISDYNABRChkSumInvalidCount_Cnt_M_u16	31636
ISDYNABRChkSumValidCount_Cnt_M_u16	31009
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	12263
ISDYNABRMsgCountValidCount_Cnt_M_u16	21548
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	572
ISDYNABRMsgLenValidCount_Cnt_M_u16	22513
ISDYNABRMsgTimeValidCount_Cnt_M_u16	17989

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	55839
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	52992
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	401
ISDYNCMM208MsgTimer_mS_M_u32	2379271424
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	55839
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	52992
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	58569
ISDYNCMM388MsgTimer_mS_M_u32	1353444608
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	50791
ISDYNVOLChkSumValidCount_Cnt_M_u16	30300
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	36842
ISDYNVOLMsgCountValidCount_Cnt_M_u16	60054
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	24530
ISDYNVOLMsgLenValidCount_Cnt_M_u16	33446
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	42252
ISDYNVOLMsgTimer_mS_M_u32	3736186112
IgnOnTimer_mS_M_u32	1358949632
IgnTimeOff_Sec_M_u32	704354036
ManVehSpd_Kph_M_f32	157.2034
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	39
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	178
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2294586624
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	251
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2684157184
PrevISDATBSI412MsgDLCError_Cnt_M_u08	15
PrevISDATBSI412MsgRxTime_MSec_M_u32	3242470656
PrevISDATBSI432MsgDLCError_Cnt_M_u08	132
PrevISDATBSI432MsgRxTime_MSec_M_u32	2161642752
PrevISDATDIRAMsgTxTime_MSec_M_u32	3949473024
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	22
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1847409920
PrevISDYNAASMsgDLCError_Cnt_M_u08	108
PrevISDYNAASMsgRxTime_MSec_M_u32	1200073984
PrevISDYNABRMsgDLCError_Cnt_M_u08	223
PrevISDYNABRMsgRxTime_MSec_M_u32	3344428288
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	25
PrevISDYNCMM208MsgRxTime_MSec_M_u32	541633792
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	218
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1922501888
PrevISDYNVOLMsgDLCError_Cnt_M_u08	171
PrevISDYNVOLMsgRxTime_MSec_M_u32	2323459328
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2379341056
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	290.71579
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	29855
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	2236
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	56820
VitesseVehicleBVRampValidCount_Cnt_M_u16	14289
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	5841

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	52726
VitesseVehicleBV_Kph_M_f32	86.1177979
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	58569
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	31686
VitesseVehiculeRoues_Kph_M_f32	89.1311035
k_AASNTCEnableTimeout_mS_u16	3848
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	16842
k_AASNodeTimeout_mS_u16	16316
k_ABSNodeTimeout_mS_u16	19093
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	11255
k_ANGLEVOLANTSigValidThresh_Cnt_u16	42792
k_AngleVolantInvalidThresh_Cnt_u16	19707
k_AngleVolantValidThresh_Cnt_u16	60904
k_BSI552MsgTimeout_mS_u16	46937
k_BSINTCEnableTimeout_mS_u16	62392
k_BSINodeAbsentDiag_Cnt_str.Threshold	39053
k_BSINodeAbsentDiag_Cnt_str.PStep	52616
k_BSINodeAbsentDiag_Cnt_str.NStep	679
k_BSINodeAbsentTimeout_mS_u16	45971
k_BSINodeTimeout_mS_u16	55079
k_BattOvHi_Volt_f32	26.8682003
k_BattOvLo_Volt_f32	18.5238991
k_BattUvHi_Volt_f32	18.7483997
k_BattUvLo_Volt_f32	23.4340992
k_CAVNTCEnableTimeout_mS_u16	28054
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	1952
k_CAVNodeTimeout_mS_u16	12733
k_CMM388MsgTimeout_mS_u16	62482
k_CMM388NTCEnableTimeout_mS_u16	37054
k_CMMNTCEnableTimeout_mS_u16	41336
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	5746
k_CONSANGLECPKMax_HwDeg_f32	258.998993
k_CONSANGLECPKMin_HwDeg_f32	-109.852402
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	56265
k_CONSANGLECPKSigValidThresh_Cnt_u16	45766
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	16186
k_CPKVehicleSpeedValidThresh_Cnt_u16	21540
k_CityParkInputInvalidThresh_Cnt_u16	17810
k_CityParkInputValidThresh_Cnt_u16	58567
k_ComputerRazGCTSigValidThresh_Cnt_u16	21118
k_CptTemporelSigValidThresh_Cnt_u16	19143
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	31036
k_DMDFCTCPKSigValidThresh_Cnt_u16	3825
k_DMDFCTCPKValidCount_Cnt_u16	42959
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	59199
k_DMDRELAXECPKSigValidThresh_Cnt_u16	34731
k_DMDRelaxeConsistentThresh_Cnt_u16	43305
k_DateValidThresh_Cnt_u16	2878
k_DefaultVehSpd_Kph_f32	224.486298
k_DiagMuxOnAbsentTimeout_mS_u16	57715
k_EMNodeTimeout_mS_u16	62746
k_ESPNTCEnableTimeout_mS_u16	30966
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	22554
k_EtatMTSigInvalidThresh_Cnt_u16	38855
k_EtatMTSigValidThresh_Cnt_u16	26004
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	36953
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	17753
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	14364
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	34793
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	19058
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	40889

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	55721
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	38490
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	13748
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	13433
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	38737
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	28735
k_ISDATDIRASentDiag_Cnt_str.Threshold	10540
k_ISDATDIRASentDiag_Cnt_str.PStep	20636
k_ISDATDIRASentDiag_Cnt_str.NStep	57668
k_ISDATDIRASentTimeout_mS_u16	4416
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	7808
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	25403
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	18930
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	29332
k_ISDYNAASChkSumValidThresh_Cnt_u16	45089
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	42727
k_ISDYNAASMsgCountValidThresh_Cnt_u16	2860
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	7400
k_ISDYNAASMsgLenValidThresh_Cnt_u16	40208
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	20176
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	9618
k_ISDYNABRChkSumValidThresh_Cnt_u16	28615
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	10279
k_ISDYNABRMsgCountValidThresh_Cnt_u16	21452
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	56332
k_ISDYNABRMsgLenValidThresh_Cnt_u16	44285
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	48863
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	61939
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	10490
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	17999
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	51452
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	23137
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	12864
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	48764
k_ISDYNVOLChkSumValidThresh_Cnt_u16	1269
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	28454
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	12661
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	40092
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	25917
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	49516
k_IgnOnTimeout_mS_u16	30760
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	172.936005
k_PowerCutVehSpdLowThresh_Kph_f32	136.600098
k_PowerCutVehSpdLowTimeout_mS_u16	45796
k_VBattMaxAAS_Volt_f32	18.4501991
k_VBattMaxBSI_Volt_f32	14.1358995
k_VBattMaxCAV_Volt_f32	31.1000996
k_VBattMaxCMM388_Volt_f32	15.5024996
k_VBattMaxCMM_Volt_f32	24.9118004
k_VBattMaxESP_Volt_f32	14.4793997
k_VBattMinAAS_Volt_f32	1.20729995
k_VBattMinBSI_Volt_f32	14.4793997
k_VBattMinCAV_Volt_f32	23.4708004
k_VBattMinCMM388_Volt_f32	10.6890001
k_VBattMinCMM_Volt_f32	8.14420033
k_VBattMinESP_Volt_f32	24.9118004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	65026
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	63978
k_VitesseVehicleBVRampValidThresh_Cnt_u16	34538
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	11612
k_VitesseVehicleBVSigValidThresh_Cnt_u16	33908
k_VitesseVehicleBVSpeedPassThresh_kph_f32	22.0879002
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	9802
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	13479
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1929661696
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	218
target_SrlComInput_Per1_Batt_Volt_f32.value	20.2891998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3305471232
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	146
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.408851206
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2073160960
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	250
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	400329984
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	548875520
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4263628032
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	404516096
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	116
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3601272064
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2713824512
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	0
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	928435456
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	74
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	100
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	107
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	123
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	131
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	224
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	78
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	49343744
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3166407936
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2736139520
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	9
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	57
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	176
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1819737344
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1964
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.669010222
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	462703
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	25.2429008
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	59297

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	25403	25403	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	39053	39053	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	17989	17989	✔
CONSANGLECPK_HwDeg_M_f32	-86.4291	-86.4291 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17989	17989	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	497605888	497605888	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	56990	56990	✔
CityParkInputConsistentCount_Cnt_M_u16	58567	58567	✔
CityParkInputInvalidCount_Cnt_M_u16	60904	60904	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	2006148864	2006148864	✔
EffacDefaultDiagTimer_mS_M_u32[1]	234	234	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2006148864	2006148864	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	1358949632	1358949632	✔
IgnTimeOff_Sec_M_u32	704354036	704354036	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	173	173	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2073160960	2073160960	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	250	250	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	400329984	400329984	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	0	0	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	548875520	548875520	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4263628032	4263628032	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3949473024	3949473024	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	116	116	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3601272064	3601272064	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	108	108	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2713824512	2713824512	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	77	77	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	928435456	928435456	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	78	78	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	49343744	49343744	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	216	216	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3166407936	3166407936	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	219	219	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2736139520	2736139520	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1819737344	1819737344	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	290.71579	290.71579	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	86.1177979	86.1177979	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	89.1311035	89.1311035	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	17989	17989	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	704354036	704354036	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-86.4291	-86.4291 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	224.486298	224.486298	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.431 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2229349376
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	5659
AASNodeAbsentTimer_mS_M_u32	2303564800
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	24924
ANGLEVOLANTSigValidCount_Cnt_M_u16	7150
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	18336
AngleVolantMsgTimer_mS_M_u32	2229349376
AngleVolantValidCount_Cnt_M_u16	40310
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	157506560
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2818956288
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	92064768
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2501479424
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	45019
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3422112768
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	34803
CAVNodeAbsentTimer_mS_M_u32	2879208448
CDD_SrlComVehSpd_Kph_G_f32	344.591888
CMM388NTCEnableTimer_mS_M_u32	351501312
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	136526848
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	55917
CMMNodeAbsentTimer_mS_M_u32	4078144512
CONSANGLECPKSigInvalidCount_Cnt_M_u16	29725
CONSANGLECPKSigValidCount_Cnt_M_u16	28799
CONSANGLECPK_Cnt_M_u16	29250
CONSANGLECPK_HwDeg_M_f32	368.443207
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	29250
CPKVehicleSpeedMsgTimer_mS_M_u32	2925014016
CPKVehicleSpeedValidCount_Cnt_M_u16	27902
CityParkInputConsistentCount_Cnt_M_u16	15738
CityParkInputInvalidCount_Cnt_M_u16	62234

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	2073160960
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	709991424
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	31775
ComputerRazGCTSigInvalidTimer_mS_M_u32	3179396096
ComputerRazGCTSigValidCount_Cnt_M_u16	59255
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	3862
DMDFCTCPKSigValidCount_Cnt_M_u16	43855
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	32862
DMDRELAXECPKSigValidCount_Cnt_M_u16	55408
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	26274
DateInvalidTimer_mS_M_u32	2818956288
DiagMuxOnAbsentTimer_mS_M_u32	1235282944
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2501479424
ESPNTCEnableTimer_mS_M_u32	1972804608
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	1627
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	4560
EffacDefaultDiagTimer_mS_M_u32[1]	8523
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	657
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1616595968
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	17600
EtatMTSigValidCount_Cnt_M_u16	17566
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	6431
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	13057
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	37333
ISDAT4V2BSI552MsgTimer_mS_M_u32	253201408
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	5297
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	43543
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	17566
ISDATBSI3F2MsgTimer_mS_M_u32	2090789888
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	35553
ISDATBSI412MsgLenValidCount_Cnt_M_u16	4087
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	17600
ISDATBSI412MsgTimer_mS_M_u32	3990825984
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	45425
ISDATBSI432MsgLenValidCount_Cnt_M_u16	55391
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	17500
ISDATDIRASentFltAcc_Cnt_M_u16	52976
ISDATDIRASentTimer_mS_M_u32	2925014016
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	34752
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	40310
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	8981
ISDYN2CMMMsgTimer_mS_M_u32	2752551936
ISDYNAASChkSumInvalidCount_Cnt_M_u16	41245
ISDYNAASChkSumValidCount_Cnt_M_u16	45519
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	59253
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	36854
ISDYNAASMsgLenValidCount_Cnt_M_u16	49120
ISDYNAASMsgTimeValidCount_Cnt_M_u16	41245
ISDYNAASMsgTimer_mS_M_u32	2649717760
ISDYNABRChkSumInvalidCount_Cnt_M_u16	39956
ISDYNABRChkSumValidCount_Cnt_M_u16	61998
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	37276
ISDYNABRMsgCountValidCount_Cnt_M_u16	21390
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	65436
ISDYNABRMsgLenValidCount_Cnt_M_u16	60734
ISDYNABRMsgTimeValidCount_Cnt_M_u16	29250
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	38963
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	22609

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	17566
ISDYNCMM208MsgTimer_mS_M_u32	698375168
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	38963
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	22609
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	50548
ISDYNCMM388MsgTimer_mS_M_u32	3046046720
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	7963
ISDYNVOLChkSumValidCount_Cnt_M_u16	65021
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	38164
ISDYNVOLMsgCountValidCount_Cnt_M_u16	21453
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	7388
ISDYNVOLMsgLenValidCount_Cnt_M_u16	8990
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	55917
ISDYNVOLMsgTimer_mS_M_u32	1383971840
IgnOnTimer_mS_M_u32	76741632
IgnTimeOff_Sec_M_u32	646849374
ManVehSpd_Kph_M_f32	613.718079
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	37
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2349132800
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	66
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	534498304
PrevISDATBSI412MsgDLCError_Cnt_M_u08	157
PrevISDATBSI412MsgRxTime_MSec_M_u32	348535808
PrevISDATBSI432MsgDLCError_Cnt_M_u08	21
PrevISDATBSI432MsgRxTime_MSec_M_u32	2106235904
PrevISDATDIRAMsgTxTime_MSec_M_u32	643447808
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	130
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2256210944
PrevISDYNAASMsgDLCError_Cnt_M_u08	136
PrevISDYNAASMsgRxTime_MSec_M_u32	4026252288
PrevISDYNABRMsgDLCError_Cnt_M_u08	225
PrevISDYNABRMsgRxTime_MSec_M_u32	25885696
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	84
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2847456256
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	26
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1682807808
PrevISDYNVOLMsgDLCError_Cnt_M_u08	45
PrevISDYNVOLMsgRxTime_MSec_M_u32	3709549568
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1105013760
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	339.449188
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	19444
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	7774
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	41973
VitesseVehicleBVRampValidCount_Cnt_M_u16	9503
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	42717
VitesseVehicleBVSigValidCount_Cnt_M_u16	12335
VitesseVehicleBV_Kph_M_f32	448.169006

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	50548
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	3902
VitesseVehiculeRoues_Kph_M_f32	632.698303
k_AASNTCEnableTimeout_mS_u16	58361
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	62065
k_AASNodeTimeout_mS_u16	31070
k_ABSNodeTimeout_mS_u16	53523
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	45484
k_ANGLEVOLANTSigValidThresh_Cnt_u16	7898
k_AngleVolantInvalidThresh_Cnt_u16	14689
k_AngleVolantValidThresh_Cnt_u16	62234
k_BSI552MsgTimeout_mS_u16	26757
k_BSINTCEnableTimeout_mS_u16	40553
k_BSINodeAbsentDiag_Cnt_str.Threshold	19051
k_BSINodeAbsentDiag_Cnt_str.PStep	31929
k_BSINodeAbsentDiag_Cnt_str.NStep	16027
k_BSINodeAbsentTimeout_mS_u16	46744
k_BSINodeTimeout_mS_u16	17500
k_BattOvHi_Volt_f32	13.5405998
k_BattOvLo_Volt_f32	30.9242992
k_BattUvHi_Volt_f32	3.68589997
k_BattUvLo_Volt_f32	13.8451004
k_CAVNTCEnableTimeout_mS_u16	44048
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	55025
k_CAVNodeTimeout_mS_u16	46361
k_CMM388MsgTimeout_mS_u16	45339
k_CMM388NTCEnableTimeout_mS_u16	35607
k_CMMNTCEnableTimeout_mS_u16	15785
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	61242
k_CONSANGLECPKMax_HwDeg_f32	471.758911
k_CONSANGLECPKMin_HwDeg_f32	-618.062988
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	57460
k_CONSANGLECPKSigValidThresh_Cnt_u16	27198
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	62180
k_CPKVehicleSpeedValidThresh_Cnt_u16	9892
k_CityParkInputInvalidThresh_Cnt_u16	46618
k_CityParkInputValidThresh_Cnt_u16	15738
k_ComputerRazGCTSigValidThresh_Cnt_u16	49815
k_CptTemporelSigValidThresh_Cnt_u16	6269
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	39580
k_DMDFCTCPKSigValidThresh_Cnt_u16	51262
k_DMDFCTCPKValidCount_Cnt_u16	27619
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	8981
k_DMDRELAXECPKSigValidThresh_Cnt_u16	4238
k_DMDRelaxeConsistentThresh_Cnt_u16	9236
k_DateValidThresh_Cnt_u16	37333
k_DefaultVehSpd_Kph_f32	188.364395
k_DiagMuxOnAbsentTimeout_mS_u16	55480
k_EMNodeTimeout_mS_u16	7938
k_ESPNTCEnableTimeout_mS_u16	23279
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	51778
k_EtatMTSigInvalidThresh_Cnt_u16	54139
k_EtatMTSigValidThresh_Cnt_u16	47317
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	15239
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	15173
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	55163
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	36438
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	34172
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	55269
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	61590
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	39236

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	51317
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	30630
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	52700
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	2901
k_ISDATDIRASentDiag_Cnt_str.Threshold	16348
k_ISDATDIRASentDiag_Cnt_str.PStep	15877
k_ISDATDIRASentDiag_Cnt_str.NStep	46278
k_ISDATDIRASentTimeout_mS_u16	35600
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	17554
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	18336
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	55291
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	46868
k_ISDYNAASChkSumValidThresh_Cnt_u16	19758
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	11420
k_ISDYNAASMsgCountValidThresh_Cnt_u16	11918
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	2072
k_ISDYNAASMsgLenValidThresh_Cnt_u16	45410
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	51170
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	28058
k_ISDYNABRChkSumValidThresh_Cnt_u16	32188
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	19163
k_ISDYNABRMsgCountValidThresh_Cnt_u16	30381
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	13677
k_ISDYNABRMsgLenValidThresh_Cnt_u16	41307
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	16756
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	9208
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	32802
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	29093
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	64604
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	63214
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	34322
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	18332
k_ISDYNVOLChkSumValidThresh_Cnt_u16	29426
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	16096
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	6450
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	33980
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	51610
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	42827
k_IgnOnTimeout_mS_u16	51864
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	139.515305
k_PowerCutVehSpdLowThresh_Kph_f32	32.5231018
k_PowerCutVehSpdLowTimeout_mS_u16	26725
k_VBattMaxAAS_Volt_f32	29.1891003
k_VBattMaxBSI_Volt_f32	1.97759998
k_VBattMaxCAV_Volt_f32	30.9102993
k_VBattMaxCMM388_Volt_f32	0.423799992
k_VBattMaxCMM_Volt_f32	3.74589992
k_VBattMaxESP_Volt_f32	0.4639
k_VBattMinAAS_Volt_f32	16.8190994
k_VBattMinBSI_Volt_f32	0.4639
k_VBattMinCAV_Volt_f32	0.0120000001
k_VBattMinCMM388_Volt_f32	6.4531002
k_VBattMinCMM_Volt_f32	14.6997995
k_VBattMinESP_Volt_f32	3.74589992
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	11788
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	63762
k_VitesseVehicleBVRampValidThresh_Cnt_u16	45076
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	55549
k_VitesseVehicleBVSigValidThresh_Cnt_u16	21107
k_VitesseVehicleBVSpeedPassThresh_kph_f32	20.4535007
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	41715
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	1693
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2818956288
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	26

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	14.7354002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1925336064
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	11
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.807184935
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1289550848
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1786584064
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2188196864
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	226
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1554865152
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3242032128
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2015206400
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1229831168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	0
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3306052608
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	126
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	140
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	176
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	222
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	111
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4072668160
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3084917760
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	171
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	928005120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	74
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	137
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	156
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	194
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	577620992
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1201
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.4654966
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	328605
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	116.844704
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	31470

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	19051	19051	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	29250	29250	✔
CONSANGLECPK_HwDeg_M_f32	368.443207	368.443207 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2006148864	2006148864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2006148864	2006148864	✔
EffacDefaultDiagTimer_mS_M_u32[1]	8523	8523	✔
ElecIntCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	2006148864	2006148864	✔
ElecIntTimer_mS_M_u32[1]	657	657	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	76741632	76741632	✔
IgnTimeOff_Sec_M_u32	646849374	646849374	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	21	21	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1289550848	1289550848	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	0	0	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1786584064	1786584064	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	2	2	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2188196864	2188196864	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	226	226	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1554865152	1554865152	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	643447808	643447808	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	93	93	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2015206400	2015206400	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	136	136	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1229831168	1229831168	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	129	129	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3306052608	3306052608	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	111	111	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4072668160	4072668160	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3084917760	3084917760	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	171	171	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	928005120	928005120	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	577620992	577620992	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	339.449188	339.449188	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	448.169006	448.169006	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	632.698303	632.698303	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	29250	29250	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	646849374	646849374	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	368.443207	368.443207 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	188.364395	188.364395	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.432 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2158706432
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	55035
AASNodeAbsentTimer_mS_M_u32	4045795072
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	38714
ANGLEVOLANTSigValidCount_Cnt_M_u16	23364
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	38508
AngleVolantMsgTimer_mS_M_u32	2158706432
AngleVolantValidCount_Cnt_M_u16	5482
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	4158959360
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3321704192
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1968725760
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	696393472
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	26557
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3017989888
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	59380
CAVNodeAbsentTimer_mS_M_u32	3501657856
CDD_SrlComVehSpd_Kph_G_f32	354.685211
CMM388NTCEnableTimer_mS_M_u32	3182710528
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1394937600
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	54598
CMMNodeAbsentTimer_mS_M_u32	2006195968
CONSANGLECPKSigInvalidCount_Cnt_M_u16	38388
CONSANGLECPKSigValidCount_Cnt_M_u16	54415
CONSANGLECPK_Cnt_M_u16	39750
CONSANGLECPK_HwDeg_M_f32	-246.257202
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	39750
CPKVehicleSpeedMsgTimer_mS_M_u32	2688958208
CPKVehicleSpeedValidCount_Cnt_M_u16	32698
CityParkInputConsistentCount_Cnt_M_u16	17758
CityParkInputInvalidCount_Cnt_M_u16	45440
CityParkInputMsgTimer_mS_M_u32	1289550848
CityParkInputValidCount_Cnt_M_u16	9

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	505016064
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	46319
ComputerRazGCTSigInvalidTimer_mS_M_u32	3439955712
ComputerRazGCTSigValidCount_Cnt_M_u16	31591
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	19852
DMDFCTCPKSigValidCount_Cnt_M_u16	3230
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	49716
DMDRELAXECPKSigValidCount_Cnt_M_u16	44478
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	0
DateInvalidTimer_mS_M_u32	3321704192
DiagMuxOnAbsentTimer_mS_M_u32	3781951232
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	696393472
ESPNTCEnableTimer_mS_M_u32	2420829952
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	46396
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	456
EffacDefaultDiagTimer_mS_M_u32[1]	654
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	90
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	4273790720
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	62284
EtatMTSigValidCount_Cnt_M_u16	6002
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	12014
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	5385
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	61708
ISDAT4V2BSI552MsgTimer_mS_M_u32	864558848
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	15611
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	49289
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	6002
ISDATBSI3F2MsgTimer_mS_M_u32	3228696320
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	60266
ISDATBSI412MsgLenValidCount_Cnt_M_u16	24552
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	62284
ISDATBSI412MsgTimer_mS_M_u32	3182509824
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	24634
ISDATBSI432MsgLenValidCount_Cnt_M_u16	20272
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	38585
ISDATDIRASentFltAcc_Cnt_M_u16	18173
ISDATDIRASentTimer_mS_M_u32	2688958208
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	53964
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	5482
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52623
ISDYN2CMMMsgTimer_mS_M_u32	1826418432
ISDYNAASChkSumInvalidCount_Cnt_M_u16	48629
ISDYNAASChkSumValidCount_Cnt_M_u16	65439
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	62317
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	39915
ISDYNAASMsgLenValidCount_Cnt_M_u16	24558
ISDYNAASMsgTimeValidCount_Cnt_M_u16	48629
ISDYNAASMsgTimer_mS_M_u32	314593024
ISDYNABRChkSumInvalidCount_Cnt_M_u16	49297
ISDYNABRChkSumValidCount_Cnt_M_u16	53763
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	43128
ISDYNABRMsgCountValidCount_Cnt_M_u16	54882
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	44919
ISDYNABRMsgLenValidCount_Cnt_M_u16	6738
ISDYNABRMsgTimeValidCount_Cnt_M_u16	39750
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	34035
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	26713
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	6002
ISDYNCMM208MsgTimer_mS_M_u32	3408768768

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	34035
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	26713
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	5488
ISDYNCMM388MsgTimer_mS_M_u32	2850148096
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	3322
ISDYNVOLChkSumValidCount_Cnt_M_u16	42005
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	13202
ISDYNVOLMsgCountValidCount_Cnt_M_u16	35620
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	46521
ISDYNVOLMsgLenValidCount_Cnt_M_u16	22195
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	54598
ISDYNVOLMsgTimer_mS_M_u32	4262825728
IgnOnTimer_mS_M_u32	3436564224
IgnTimeOff_Sec_M_u32	1739872330
ManVehSpd_Kph_M_f32	649.111694
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	38
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	26
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2856320768
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	95
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1648058112
PrevISDATBSI412MsgDLCError_Cnt_M_u08	135
PrevISDATBSI412MsgRxTime_MSec_M_u32	2033979136
PrevISDATBSI432MsgDLCError_Cnt_M_u08	152
PrevISDATBSI432MsgRxTime_MSec_M_u32	1215229696
PrevISDATDIRAMsgTxTime_MSec_M_u32	2491420416
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	237
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3143474944
PrevISDYNAASMsgDLCError_Cnt_M_u08	142
PrevISDYNAASMsgRxTime_MSec_M_u32	2644217600
PrevISDYNABRMsgDLCError_Cnt_M_u08	159
PrevISDYNABRMsgRxTime_MSec_M_u32	3052261120
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	229
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2758053632
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	117
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1613098752
PrevISDYNVOLMsgDLCError_Cnt_M_u08	171
PrevISDYNVOLMsgRxTime_MSec_M_u32	3023900416
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	968310528
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	436.772705
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57329
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	48244
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	7150
VitesseVehicleBVRampValidCount_Cnt_M_u16	60465
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	2743
VitesseVehicleBVSigValidCount_Cnt_M_u16	25217
VitesseVehicleBV_Kph_M_f32	313.155701
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	5488
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	3026

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	491.540802
k_AASNTCEnableTimeout_mS_u16	57889
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	49785
k_AASNodeTimeout_mS_u16	43892
k_ABSNodeTimeout_mS_u16	15253
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	2953
k_ANGLEVOLANTSigValidThresh_Cnt_u16	10175
k_AngleVolantInvalidThresh_Cnt_u16	46122
k_AngleVolantValidThresh_Cnt_u16	45440
k_BSI552MsgTimeout_mS_u16	56317
k_BSINTCEnableTimeout_mS_u16	31058
k_BSINodeAbsentDiag_Cnt_str.Threshold	42443
k_BSINodeAbsentDiag_Cnt_str.PStep	39713
k_BSINodeAbsentDiag_Cnt_str.NStep	12731
k_BSINodeAbsentTimeout_mS_u16	10628
k_BSINodeTimeout_mS_u16	38585
k_BattOvHi_Volt_f32	26.4803009
k_BattOvLo_Volt_f32	29.7758007
k_BattUvHi_Volt_f32	28.6858997
k_BattUvLo_Volt_f32	23.0594006
k_CAVNTCEnableTimeout_mS_u16	56990
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	29434
k_CAVNodeTimeout_mS_u16	49920
k_CMM388MsgTimeout_mS_u16	1531
k_CMM388NTCEnableTimeout_mS_u16	26631
k_CMMNTCEnableTimeout_mS_u16	41491
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	23518
k_CONSANGLECPKMax_HwDeg_f32	114.103302
k_CONSANGLECPKMin_HwDeg_f32	-164.303101
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	50288
k_CONSANGLECPKSigValidThresh_Cnt_u16	64210
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	55010
k_CPKVehicleSpeedValidThresh_Cnt_u16	58401
k_CityParkInputInvalidThresh_Cnt_u16	2687
k_CityParkInputValidThresh_Cnt_u16	17758
k_ComputerRazGCTSigValidThresh_Cnt_u16	19273
k_CptTemporelSigValidThresh_Cnt_u16	36183
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	56951
k_DMDFCTCPKSigValidThresh_Cnt_u16	35154
k_DMDFCTCPKValidCount_Cnt_u16	21413
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	52623
k_DMDRELAXECPKSigValidThresh_Cnt_u16	39137
k_DMDRelaxeConsistentThresh_Cnt_u16	63055
k_DateValidThresh_Cnt_u16	61708
k_DefaultVehSpd_Kph_f32	114.714302
k_DiagMuxOnAbsentTimeout_mS_u16	49124
k_EMNodeTimeout_mS_u16	26949
k_ESPNTCEnableTimeout_mS_u16	24320
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	60102
k_EtatMTSigInvalidThresh_Cnt_u16	30300
k_EtatMTSigValidThresh_Cnt_u16	55822
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	18681
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	60799
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	47963
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	41996
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	602
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	5214
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	30411
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	57473
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	11054
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	6938

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	39992
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	35597
k_ISDATDIRASentDiag_Cnt_str.Threshold	3976
k_ISDATDIRASentDiag_Cnt_str.PStep	38821
k_ISDATDIRASentDiag_Cnt_str.NStep	39228
k_ISDATDIRASentTimeout_mS_u16	58269
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	4950
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	38508
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	6108
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	28561
k_ISDYNAASChkSumValidThresh_Cnt_u16	49411
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	55160
k_ISDYNAASMsgCountValidThresh_Cnt_u16	17762
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	35973
k_ISDYNAASMsgLenValidThresh_Cnt_u16	4968
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	19623
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	56701
k_ISDYNABRChkSumValidThresh_Cnt_u16	57560
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	38589
k_ISDYNABRMsgCountValidThresh_Cnt_u16	1799
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	50246
k_ISDYNABRMsgLenValidThresh_Cnt_u16	58428
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	33458
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	26597
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	20391
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	40607
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	50746
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	51780
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	55448
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	24889
k_ISDYNVOLChkSumValidThresh_Cnt_u16	58103
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	24493
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	27895
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	9048
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	30846
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	2218
k_IgnOnTimeout_mS_u16	51269
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	103.761703
k_PowerCutVehSpdLowThresh_Kph_f32	48.7383003
k_PowerCutVehSpdLowTimeout_mS_u16	1245
k_VBattMaxAAS_Volt_f32	13.7282
k_VBattMaxBSI_Volt_f32	17.8255997
k_VBattMaxCAV_Volt_f32	21.5519009
k_VBattMaxCMM388_Volt_f32	14.8493996
k_VBattMaxCMM_Volt_f32	9.2336998
k_VBattMaxESP_Volt_f32	23.8169994
k_VBattMinAAS_Volt_f32	12.1341
k_VBattMinBSI_Volt_f32	23.8169994
k_VBattMinCAV_Volt_f32	11.6050997
k_VBattMinCMM388_Volt_f32	21.9946995
k_VBattMinCMM_Volt_f32	28.4176998
k_VBattMinESP_Volt_f32	9.2336998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	48872
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	8599
k_VitesseVehicleBVRampValidThresh_Cnt_u16	58002
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	4885
k_VitesseVehicleBVSigValidThresh_Cnt_u16	10867
k_VitesseVehicleBVSpeedPassThresh_kph_f32	174.018494
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	38644
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	49079
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3321704192
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65036
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	163190528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSe	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	117
target_SrlComInput_Per1_Batt_Volt_f32.value	9.14480019
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	596107008
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	85
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.765152693
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2616708864
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	236
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1805086464
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	175
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2353467136
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	23
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2785455872
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1624657664
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1689644800
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1504022272
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	58
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	129
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	164
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	171
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	240
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	254
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	820227840
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	158
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	205
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4132359936
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3480121088
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	255
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3114143488
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	132
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	166
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	186
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	579165952
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1253
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.642514408
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	835996
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	33.0237007
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	47875

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	163190528	163190528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	38510	38510	✔
AngleVolantMsgTimer_mS_M_u32	163190528	163190528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	42443	42443	✔
BSINodeAbsentTimer_mS_M_u32	163190528	163190528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	39750	39750	✔
CONSANGLECPK_HwDeg_M_f32	-246.257202	-246.257202 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	39750	39750	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2688958208	2688958208	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	32698	32698	✔
CityParkInputConsistentCount_Cnt_M_u16	17758	17758	✔
CityParkInputInvalidCount_Cnt_M_u16	45440	45440	✔
CityParkInputMsgTimer_mS_M_u32	163190528	163190528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	163190528	163190528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	163190528	163190528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	163190528	163190528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	163190528	163190528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	163190528	163190528	✔
ESPNTCEnableTimer_mS_M_u32	163190528	163190528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	456	456	✔
EffacDefaultDiagTimer_mS_M_u32[1]	654	654	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	163190528	163190528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	90	90	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	163190528	163190528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	163190528	163190528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	163190528	163190528	✔
IgnOnTimer_mS_M_u32	3436564224	3436564224	✔
IgnTimeOff_Sec_M_u32	1739872330	1739872330	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2616708864	2616708864	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	236	236	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1805086464	1805086464	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	175	175	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2353467136	2353467136	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	23	23	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2785455872	2785455872	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2491420416	2491420416	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	119	119	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1689644800	1689644800	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	190	190	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1504022272	1504022272	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	254	254	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	820227840	820227840	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	99	99	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4132359936	4132359936	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	83	83	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3480121088	3480121088	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	255	255	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3114143488	3114143488	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	579165952	579165952	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	436.772705	436.772705	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	313.155701	313.155701	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	491.540802	491.540802	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	39750	39750	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1739872330	1739872330	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-246.257202	-246.257202 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	114.714302	114.714302	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.433 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	22611456
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	57447
AASNodeAbsentTimer_mS_M_u32	917042688
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	47532
ANGLEVOLANTSigValidCount_Cnt_M_u16	37453
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	42516
AngleVolantMsgTimer_mS_M_u32	22611456
AngleVolantValidCount_Cnt_M_u16	42907
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2372711936
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	623064576
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3218187776
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2052351488
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	5155
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1311909376
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	31228
CAVNodeAbsentTimer_mS_M_u32	3296040448
CDD_SrlComVehSpd_Kph_G_f32	475.79129
CMM388NTCEnableTimer_mS_M_u32	2189284864
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1965790720
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	967
CMMNodeAbsentTimer_mS_M_u32	1478387200
CONSANGLECPKSigInvalidCount_Cnt_M_u16	6267
CONSANGLECPKSigValidCount_Cnt_M_u16	49517
CONSANGLECPK_Cnt_M_u16	2376
CONSANGLECPK_HwDeg_M_f32	-749.468018
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2376
CPKVehicleSpeedMsgTimer_mS_M_u32	3465020928
CPKVehicleSpeedValidCount_Cnt_M_u16	32244
CityParkInputConsistentCount_Cnt_M_u16	59327

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	64600
CityParkInputMsgTimer_mS_M_u32	2616708864
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2144138752
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	5771
ComputerRazGCTSigInvalidTimer_mS_M_u32	964564480
ComputerRazGCTSigValidCount_Cnt_M_u16	43428
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	22580
DMDFCTCPKSigValidCount_Cnt_M_u16	24510
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	41150
DMDRELAXECPKSigValidCount_Cnt_M_u16	735
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	65535
DateInvalidTimer_mS_M_u32	623064576
DiagMuxOnAbsentTimer_mS_M_u32	3524707840
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2052351488
ESPNTCEnableTimer_mS_M_u32	758773248
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	14501
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	123
EffacDefaultDiagTimer_mS_M_u32[1]	234
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1436820992
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	37557
EtatMTSigValidCount_Cnt_M_u16	47874
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	46477
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	26623
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	60020
ISDAT4V2BSI552MsgTimer_mS_M_u32	4097992192
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	35112
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	13117
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	47874
ISDATBSI3F2MsgTimer_mS_M_u32	3439642112
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	19162
ISDATBSI412MsgLenValidCount_Cnt_M_u16	57888
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	37557
ISDATBSI412MsgTimer_mS_M_u32	3796305408
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	13035
ISDATBSI432MsgLenValidCount_Cnt_M_u16	15049
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	49581
ISDATDIRASentFltAcc_Cnt_M_u16	49377
ISDATDIRASentTimer_mS_M_u32	3465020928
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	64182
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	42907
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	42027
ISDYN2CMMMsgTimer_mS_M_u32	1602483712
ISDYNAASChkSumInvalidCount_Cnt_M_u16	37753
ISDYNAASChkSumValidCount_Cnt_M_u16	29498
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	55698
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	64023
ISDYNAASMsgLenValidCount_Cnt_M_u16	45776
ISDYNAASMsgTimeValidCount_Cnt_M_u16	37753
ISDYNAASMsgTimer_mS_M_u32	3009009152
ISDYNABRChkSumInvalidCount_Cnt_M_u16	45351
ISDYNABRChkSumValidCount_Cnt_M_u16	16784
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	40944
ISDYNABRMsgCountValidCount_Cnt_M_u16	47857
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	38898
ISDYNABRMsgLenValidCount_Cnt_M_u16	48164
ISDYNABRMsgTimeValidCount_Cnt_M_u16	2376
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	55839

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	52992
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	47874
ISDYNCMM208MsgTimer_mS_M_u32	2006038016
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	55839
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	52992
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	16265
ISDYNCMM388MsgTimer_mS_M_u32	1408587264
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	19305
ISDYNVOLChkSumValidCount_Cnt_M_u16	60123
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	15906
ISDYNVOLMsgCountValidCount_Cnt_M_u16	31788
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	27438
ISDYNVOLMsgLenValidCount_Cnt_M_u16	27903
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	967
ISDYNVOLMsgTimer_mS_M_u32	3596228096
IgnOnTimer_mS_M_u32	3138999808
IgnTimeOff_Sec_M_u32	1870477552
ManVehSpd_Kph_M_f32	225.136398
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	39
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	133
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3348809216
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	29
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1160291840
PrevISDATBSI412MsgDLCError_Cnt_M_u08	250
PrevISDATBSI412MsgRxTime_MSec_M_u32	518428160
PrevISDATBSI432MsgDLCError_Cnt_M_u08	90
PrevISDATBSI432MsgRxTime_MSec_M_u32	2496525824
PrevISDATDIRAMsgTxTime_MSec_M_u32	3709507072
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	142
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2462180864
PrevISDYNAASMsgDLCError_Cnt_M_u08	185
PrevISDYNAASMsgRxTime_MSec_M_u32	2412254720
PrevISDYNABRMsgDLCError_Cnt_M_u08	11
PrevISDYNABRMsgRxTime_MSec_M_u32	1607554560
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	90
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3748468224
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	255
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3920164352
PrevISDYNVOLMsgDLCError_Cnt_M_u08	21
PrevISDYNVOLMsgRxTime_MSec_M_u32	2984482304
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	104138240
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	29.5499992
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	50693
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	13630
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	17934
VitesseVehicleBVRampValidCount_Cnt_M_u16	55815
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	37685
VitesseVehicleBVSigValidCount_Cnt_M_u16	45206

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBV_Kph_M_f32	449.113892
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	16265
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	57635
VitesseVehiculeRoues_Kph_M_f32	343.399811
k_AASNTCEnableTimeout_mS_u16	24759
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	40046
k_AASNodeTimeout_mS_u16	26686
k_ABSNodeTimeout_mS_u16	61977
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	11518
k_ANGLEVOLANTSigValidThresh_Cnt_u16	44316
k_AngleVolantInvalidThresh_Cnt_u16	29659
k_AngleVolantValidThresh_Cnt_u16	64600
k_BSI552MsgTimeout_mS_u16	56482
k_BSINTCEnableTimeout_mS_u16	18339
k_BSINodeAbsentDiag_Cnt_str.Threshold	39053
k_BSINodeAbsentDiag_Cnt_str.PStep	52616
k_BSINodeAbsentDiag_Cnt_str.NStep	679
k_BSINodeAbsentTimeout_mS_u16	19660
k_BSINodeTimeout_mS_u16	49581
k_BattOvHi_Volt_f32	1.75890005
k_BattOvLo_Volt_f32	20.5319996
k_BattUvHi_Volt_f32	12.2172003
k_BattUvLo_Volt_f32	19.5435009
k_CAVNTCEnableTimeout_mS_u16	27902
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	28906
k_CAVNodeTimeout_mS_u16	49495
k_CMM388MsgTimeout_mS_u16	21351
k_CMM388NTCEnableTimeout_mS_u16	23875
k_CMMNTCEnableTimeout_mS_u16	47584
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	8447
k_CONSANGLECPKMax_HwDeg_f32	296.384888
k_CONSANGLECPKMin_HwDeg_f32	-704.779602
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	12937
k_CONSANGLECPKSigValidThresh_Cnt_u16	5155
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	7668
k_CPKVehicleSpeedValidThresh_Cnt_u16	64693
k_CityParkInputInvalidThresh_Cnt_u16	2909
k_CityParkInputValidThresh_Cnt_u16	59327
k_ComputerRazGCTSigValidThresh_Cnt_u16	5694
k_CptTemporelSigValidThresh_Cnt_u16	34003
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	2802
k_DMDFCTCPKSigValidThresh_Cnt_u16	28452
k_DMDFCTCPKValidCount_Cnt_u16	61547
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	42027
k_DMDRELAXECPKSigValidThresh_Cnt_u16	34549
k_DMDRelaxeConsistentThresh_Cnt_u16	42667
k_DateValidThresh_Cnt_u16	60020
k_DefaultVehSpd_Kph_f32	97.7115021
k_DiagMuxOnAbsentTimeout_mS_u16	37742
k_EMNodeTimeout_mS_u16	8840
k_ESPNTCEnableTimeout_mS_u16	17624
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	5191
k_EtatMTSigInvalidThresh_Cnt_u16	31686
k_EtatMTSigValidThresh_Cnt_u16	5487
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	58287
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	2781
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	47560
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	55285
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	61898
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	40958
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	29496

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	2774
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	41487
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	55756
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	52017
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	2288
k_ISDATDIRASentDiag_Cnt_str.Threshold	21842
k_ISDATDIRASentDiag_Cnt_str.PStep	38193
k_ISDATDIRASentDiag_Cnt_str.NStep	48870
k_ISDATDIRASentTimeout_mS_u16	30723
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	54293
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	42516
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	35396
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	42023
k_ISDYNAASChkSumValidThresh_Cnt_u16	29840
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	4848
k_ISDYNAASMsgCountValidThresh_Cnt_u16	28145
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	7499
k_ISDYNAASMsgLenValidThresh_Cnt_u16	98
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	56932
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	42464
k_ISDYNABRChkSumValidThresh_Cnt_u16	146
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	34595
k_ISDYNABRMsgCountValidThresh_Cnt_u16	23300
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	14023
k_ISDYNABRMsgLenValidThresh_Cnt_u16	43941
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	21507
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	65065
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	21027
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	64189
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	11436
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	17741
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	59152
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	58733
k_ISDYNVOLChkSumValidThresh_Cnt_u16	21747
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	15698
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	16564
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	12945
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	51166
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	39834
k_IgnOnTimeout_mS_u16	57417
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	91.069397
k_PowerCutVehSpdLowThresh_Kph_f32	104.139702
k_PowerCutVehSpdLowTimeout_mS_u16	59523
k_VBattMaxAAS_Volt_f32	7.78100014
k_VBattMaxBSI_Volt_f32	30.1002998
k_VBattMaxCAV_Volt_f32	11.3479004
k_VBattMaxCMM388_Volt_f32	28.9419994
k_VBattMaxCMM_Volt_f32	32
k_VBattMaxESP_Volt_f32	7.77549982
k_VBattMinAAS_Volt_f32	29.6756992
k_VBattMinBSI_Volt_f32	7.77549982
k_VBattMinCAV_Volt_f32	19.1133003
k_VBattMinCMM388_Volt_f32	30.8057995
k_VBattMinCMM_Volt_f32	17.0475006
k_VBattMinESP_Volt_f32	32
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	39263
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	9749
k_VitesseVehicleBVRampValidThresh_Cnt_u16	12578
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	40411
k_VitesseVehicleBVSigValidThresh_Cnt_u16	52352
k_VitesseVehicleBVSpeedPassThresh_kph_f32	538.996277
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	27900
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	63349
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	623064576
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	15965
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2717483008
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	255
target_SrlComInput_Per1_Batt_Volt_f32.value	26.6723003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3544393216
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	71
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.38909927
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1437816320
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	32
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1834251776
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3519387136
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2332472832
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2702693888
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	469300736
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	61478400
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	43
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	101
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	208
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2658121216
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	65
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	147
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	217
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	111
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1655592448
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	7
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1573877248
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1707120128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	79
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	93
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	175
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2890573312
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3822
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.377716482
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	251438
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	207.533493

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	64719		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	42516	42516	✔
AngleVolantMsgTimer_mS_M_u32	2717483008	2717483008	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	39053	39053	✔
BSINodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	2376	2376	✔
CONSANGLECPK_HwDeg_M_f32	-749.468018	-749.468018 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	2376	2376	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3465020928	3465020928	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	32244	32244	✔
CityParkInputConsistentCount_Cnt_M_u16	59327	59327	✔
CityParkInputInvalidCount_Cnt_M_u16	64600	64600	✔
CityParkInputMsgTimer_mS_M_u32	2717483008	2717483008	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2717483008	2717483008	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2717483008	2717483008	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2717483008	2717483008	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2717483008	2717483008	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2717483008	2717483008	✔
ESPNTCEnableTimer_mS_M_u32	2717483008	2717483008	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2717483008	2717483008	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2717483008	2717483008	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	234	234	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2717483008	2717483008	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2717483008	2717483008	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2717483008	2717483008	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2717483008	2717483008	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2717483008	2717483008	✔
IgnOnTimer_mS_M_u32	3138999808	3138999808	✔
IgnTimeOff_Sec_M_u32	1870477552	1870477552	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1437816320	1437816320	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	32	32	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1834251776	1834251776	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	125	125	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3519387136	3519387136	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	43	43	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2332472832	2332472832	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3709507072	3709507072	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	153	153	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	469300736	469300736	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	105	105	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	61478400	61478400	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2658121216	2658121216	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	111	111	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1655592448	1655592448	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	7	7	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1573877248	1573877248	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	167	167	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1707120128	1707120128	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2890573312	2890573312	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	29.5499992	29.5499992	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	449.113892	449.113892	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	343.399811	343.399811	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	2376	2376	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1870477552	1870477552	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-749.468018	-749.468018 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	97.7115021	97.7115021	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.434 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1395372288
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	4096
AASNodeAbsentTimer_mS_M_u32	519823616
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	13874
ANGLEVOLANTSigValidCount_Cnt_M_u16	15886
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	45817
AngleVolantMsgTimer_mS_M_u32	1395372288
AngleVolantValidCount_Cnt_M_u16	13027
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3652231424
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	210575616
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1111609600
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2377748736
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	49869
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3105902848
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	56770
CAVNodeAbsentTimer_mS_M_u32	4027973888
CDD_SrlComVehSpd_Kph_G_f32	437.718597
CMM388NTCEnableTimer_mS_M_u32	654131456
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	905183488
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	19231
CMMNodeAbsentTimer_mS_M_u32	2623246592
CONSANGLECPKSigInvalidCount_Cnt_M_u16	2243
CONSANGLECPKSigValidCount_Cnt_M_u16	57263
CONSANGLECPK_Cnt_M_u16	13342
CONSANGLECPK_HwDeg_M_f32	289.787415
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	13342
CPKVehicleSpeedMsgTimer_mS_M_u32	1738453248
CPKVehicleSpeedValidCount_Cnt_M_u16	36865

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	631
CityParkInputInvalidCount_Cnt_M_u16	47532
CityParkInputMsgTimer_mS_M_u32	1437816320
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3549421824
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	64916
ComputerRazGCTSigInvalidTimer_mS_M_u32	1392279808
ComputerRazGCTSigValidCount_Cnt_M_u16	37064
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	5656
DMDFCTCPKSigValidCount_Cnt_M_u16	12603
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	18684
DMDRELAXECPKSigValidCount_Cnt_M_u16	46168
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	56445
DateInvalidTimer_mS_M_u32	210575616
DiagMuxOnAbsentTimer_mS_M_u32	133329152
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2377748736
ESPNTCEnableTimer_mS_M_u32	3209224448
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	11846
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	4560
EffacDefaultDiagTimer_mS_M_u32[1]	8523
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	657
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3939127552
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	58199
EtatMTSigValidCount_Cnt_M_u16	44079
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	63885
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	46073
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	59673
ISDAT4V2BSI552MsgTimer_mS_M_u32	1475318016
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	34173
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	59645
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	44079
ISDATBSI3F2MsgTimer_mS_M_u32	1328050432
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	55654
ISDATBSI412MsgLenValidCount_Cnt_M_u16	13654
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	58199
ISDATBSI412MsgTimer_mS_M_u32	3898716416
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	19891
ISDATBSI432MsgLenValidCount_Cnt_M_u16	47066
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	2735
ISDATDIRASentFltAcc_Cnt_M_u16	56595
ISDATDIRASentTimer_mS_M_u32	1738453248
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	38868
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	13027
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52787
ISDYN2CMMMsgTimer_mS_M_u32	3496665344
ISDYNAASChkSumInvalidCount_Cnt_M_u16	48842
ISDYNAASChkSumValidCount_Cnt_M_u16	12613
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	14590
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	35185
ISDYNAASMsgLenValidCount_Cnt_M_u16	20741
ISDYNAASMsgTimeValidCount_Cnt_M_u16	48842
ISDYNAASMsgTimer_mS_M_u32	74006784
ISDYNABRChkSumInvalidCount_Cnt_M_u16	62784
ISDYNABRChkSumValidCount_Cnt_M_u16	62916
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	13669
ISDYNABRMsgCountValidCount_Cnt_M_u16	63008
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	9822
ISDYNABRMsgLenValidCount_Cnt_M_u16	35722
ISDYNABRMsgTimeValidCount_Cnt_M_u16	13342

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	38963
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	22609
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	44079
ISDYNCMM208MsgTimer_mS_M_u32	4014055680
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	38963
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	22609
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	41753
ISDYNCMM388MsgTimer_mS_M_u32	4036411648
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	43001
ISDYNVOLChkSumValidCount_Cnt_M_u16	39781
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	40014
ISDYNVOLMsgCountValidCount_Cnt_M_u16	5105
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	64171
ISDYNVOLMsgLenValidCount_Cnt_M_u16	18167
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	19231
ISDYNVOLMsgTimer_mS_M_u32	3966271744
IgnOnTimer_mS_M_u32	1261093120
IgnTimeOff_Sec_M_u32	1402260615
ManVehSpd_Kph_M_f32	604.489502
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	37
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	214
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	929460480
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	206
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3460092160
PrevISDATBSI412MsgDLCError_Cnt_M_u08	61
PrevISDATBSI412MsgRxTime_MSec_M_u32	3837985024
PrevISDATBSI432MsgDLCError_Cnt_M_u08	99
PrevISDATBSI432MsgRxTime_MSec_M_u32	3633111296
PrevISDATDIRAMsgTxTime_MSec_M_u32	2049376512
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	51
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3664843008
PrevISDYNAASMsgDLCError_Cnt_M_u08	132
PrevISDYNAASMsgRxTime_MSec_M_u32	4162748672
PrevISDYNABRMsgDLCError_Cnt_M_u08	2
PrevISDYNABRMsgRxTime_MSec_M_u32	1023590656
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	182
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3710877952
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	198
PrevISDYNCMM388MsgRxTime_MSec_M_u32	100393216
PrevISDYNVOLMsgDLCError_Cnt_M_u08	90
PrevISDYNVOLMsgRxTime_MSec_M_u32	1607205120
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3029840128
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	407.358307
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	23975
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	443
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	16780
VitesseVehicleBVRampValidCount_Cnt_M_u16	30560
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	3479

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	18227
VitesseVehicleBV_Kph_M_f32	315.208191
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	41753
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	12301
VitesseVehiculeRoues_Kph_M_f32	0.36680001
k_AASNTCEnableTimeout_mS_u16	43473
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	24682
k_AASNodeTimeout_mS_u16	26811
k_ABSNodeTimeout_mS_u16	7273
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	27514
k_ANGLEVOLANTSigValidThresh_Cnt_u16	27873
k_AngleVolantInvalidThresh_Cnt_u16	54436
k_AngleVolantValidThresh_Cnt_u16	47532
k_BSI552MsgTimeout_mS_u16	63888
k_BSINTCEnableTimeout_mS_u16	61323
k_BSINodeAbsentDiag_Cnt_str.Threshold	19051
k_BSINodeAbsentDiag_Cnt_str.PStep	31929
k_BSINodeAbsentDiag_Cnt_str.NStep	16027
k_BSINodeAbsentTimeout_mS_u16	40657
k_BSINodeTimeout_mS_u16	2735
k_BattOvHi_Volt_f32	7.22359991
k_BattOvLo_Volt_f32	27.4253998
k_BattUvHi_Volt_f32	22.1229992
k_BattUvLo_Volt_f32	28.8038006
k_CAVNTCEnableTimeout_mS_u16	32698
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	12536
k_CAVNodeTimeout_mS_u16	32303
k_CMM388MsgTimeout_mS_u16	46848
k_CMM388NTCEnableTimeout_mS_u16	2412
k_CMMNTCEnableTimeout_mS_u16	54101
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	57465
k_CONSANGLECPKMax_HwDeg_f32	225.033096
k_CONSANGLECPKMin_HwDeg_f32	-618.322021
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	51737
k_CONSANGLECPKSigValidThresh_Cnt_u16	38669
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	40857
k_CPKVehicleSpeedValidThresh_Cnt_u16	61397
k_CityParkInputInvalidThresh_Cnt_u16	16030
k_CityParkInputValidThresh_Cnt_u16	631
k_ComputerRazGCTSigValidThresh_Cnt_u16	46651
k_CptTemporelSigValidThresh_Cnt_u16	52283
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	52574
k_DMDFCTCPKSigValidThresh_Cnt_u16	29322
k_DMDFCTCPKValidCount_Cnt_u16	19957
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	52787
k_DMDRELAXECPKSigValidThresh_Cnt_u16	22422
k_DMDRelaxeConsistentThresh_Cnt_u16	20596
k_DateValidThresh_Cnt_u16	59673
k_DefaultVehSpd_Kph_f32	142.579407
k_DiagMuxOnAbsentTimeout_mS_u16	44460
k_EMNodeTimeout_mS_u16	24220
k_ESPNTCEnableTimeout_mS_u16	60718
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	9889
k_EtatMTSigInvalidThresh_Cnt_u16	53603
k_EtatMTSigValidThresh_Cnt_u16	46631
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	64104
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	18079
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	61532
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	3350
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	8534
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	27130

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	204
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	48051
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	36935
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	53906
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	40993
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	51235
k_ISDATDIRASentDiag_Cnt_str.Threshold	38287
k_ISDATDIRASentDiag_Cnt_str.PStep	11594
k_ISDATDIRASentDiag_Cnt_str.NStep	1219
k_ISDATDIRASentTimeout_mS_u16	4268
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	15028
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	45817
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	52458
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	7232
k_ISDYNAASChkSumValidThresh_Cnt_u16	23748
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	56421
k_ISDYNAASMsgCountValidThresh_Cnt_u16	56608
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	16596
k_ISDYNAASMsgLenValidThresh_Cnt_u16	12367
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	63753
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	13460
k_ISDYNABRChkSumValidThresh_Cnt_u16	63040
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	27085
k_ISDYNABRMsgCountValidThresh_Cnt_u16	32745
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	45599
k_ISDYNABRMsgLenValidThresh_Cnt_u16	54598
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	20716
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	17723
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	10123
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	27966
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	56626
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	9486
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	55684
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	5549
k_ISDYNVOLChkSumValidThresh_Cnt_u16	59613
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	5183
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	34904
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	29635
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	62875
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	60839
k_IgnOnTimeout_mS_u16	38169
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	25.0056
k_PowerCutVehSpdLowThresh_Kph_f32	185.794693
k_PowerCutVehSpdLowTimeout_mS_u16	17005
k_VBattMaxAAS_Volt_f32	23.7996998
k_VBattMaxBSI_Volt_f32	18.0081005
k_VBattMaxCAV_Volt_f32	30.9846992
k_VBattMaxCMM388_Volt_f32	18.7437
k_VBattMaxCMM_Volt_f32	13.5135002
k_VBattMaxESP_Volt_f32	32
k_VBattMinAAS_Volt_f32	5.77890015
k_VBattMinBSI_Volt_f32	32
k_VBattMinCAV_Volt_f32	7.9144001
k_VBattMinCMM388_Volt_f32	9.25279999
k_VBattMinCMM_Volt_f32	0.995400012
k_VBattMinESP_Volt_f32	13.5135002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	37590
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	52854
k_VitesseVehicleBVRampValidThresh_Cnt_u16	49998
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	33381
k_VitesseVehicleBVSigValidThresh_Cnt_u16	38964
k_VitesseVehicleBVSpeedPassThresh_kph_f32	371.808289
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	1218
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	22294
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	210575616
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60573
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1277031168
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	198
target_SrlComInput_Per1_Batt_Volt_f32.value	9.82229996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2918011136
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	46
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.99559319
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	65
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1667023104
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2298044672
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	136708352
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3370295552
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3006218496
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	24
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2936791296
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2759360768
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	11
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	46
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	47
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	95
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	103
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	196
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	237
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1923588352
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	44
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	60
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	107
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3899375872
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	201
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1669882112
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	244
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4164223232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	48
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	72
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	84
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	88
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	165
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2698432768
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	274
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.07732407
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	943269
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	218.863297
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	24905

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1277031168	1277031168	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	19051	19051	✔
BSINodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	13342	13342	✔
CONSANGLECPK_HwDeg_M_f32	289.787415	289.787415 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1277031168	1277031168	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1277031168	1277031168	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1277031168	1277031168	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1277031168	1277031168	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1277031168	1277031168	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1277031168	1277031168	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1277031168	1277031168	✔
ESPNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	1277031168	1277031168	✔
EffacDefaultDiagTimer_mS_M_u32[1]	8523	8523	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1277031168	1277031168	✔
ElecIntTimer_mS_M_u32[1]	657	657	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1277031168	1277031168	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1277031168	1277031168	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1277031168	1277031168	✔
IgnOnTimer_mS_M_u32	1261093120	1261093120	✔
IgnTimeOff_Sec_M_u32	1402260615	1402260615	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	65	65	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1667023104	1667023104	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	209	209	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2298044672	2298044672	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	198	198	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	136708352	136708352	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	9	9	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3370295552	3370295552	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2049376512	2049376512	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	24	24	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2936791296	2936791296	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	180	180	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2759360768	2759360768	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	237	237	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1923588352	1923588352	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	195	195	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3899375872	3899375872	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	201	201	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1669882112	1669882112	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	244	244	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4164223232	4164223232	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2698432768	2698432768	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	407.358307	407.358307	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	315.208191	315.208191	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	0.36680001	0.36680001	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	13342	13342	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1402260615	1402260615	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	289.787415	289.787415 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.435 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	71550208
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	43904
AASNodeAbsentTimer_mS_M_u32	3760387328
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	2426
ANGLEVOLANTSigValidCount_Cnt_M_u16	64765
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	3145
AngleVolantMsgTimer_mS_M_u32	71550208
AngleVolantValidCount_Cnt_M_u16	14213
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2941498624
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	790115584
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1950606592
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	19375360
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	63109
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	413820160
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	20460
CAVNodeAbsentTimer_mS_M_u32	325522688
CDD_SrlComVehSpd_Kph_G_f32	24.2320004
CMM388NTCEnableTimer_mS_M_u32	1989301504
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2393183488
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	34132
CMMNodeAbsentTimer_mS_M_u32	1114219776
CONSANGLECPKSigInvalidCount_Cnt_M_u16	9543
CONSANGLECPKSigValidCount_Cnt_M_u16	40154
CONSANGLECPK_Cnt_M_u16	1017
CONSANGLECPK_HwDeg_M_f32	605.843201
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	1017
CPKVehicleSpeedMsgTimer_mS_M_u32	1822868736
CPKVehicleSpeedValidCount_Cnt_M_u16	41063
CityParkInputConsistentCount_Cnt_M_u16	9561

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	12514
CityParkInputMsgTimer_mS_M_u32	935262720
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1123480832
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	5972
ComputerRazGCTSigInvalidTimer_mS_M_u32	3864368384
ComputerRazGCTSigValidCount_Cnt_M_u16	31994
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	12046
DMDFCTCPKSigValidCount_Cnt_M_u16	48216
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	7012
DMDRELAXECPKSigValidCount_Cnt_M_u16	35431
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	47888
DateInvalidTimer_mS_M_u32	790115584
DiagMuxOnAbsentTimer_mS_M_u32	2468775168
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	19375360
ESPNTCEnableTimer_mS_M_u32	2826958080
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	39907
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	456
EffacDefaultDiagTimer_mS_M_u32[1]	654
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	90
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4017382656
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	800
EtatMTSigValidCount_Cnt_M_u16	50783
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	30001
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	59460
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	18838
ISDAT4V2BSI552MsgTimer_mS_M_u32	3695027456
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	18204
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	31107
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	50783
ISDATBSI3F2MsgTimer_mS_M_u32	4215047424
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	30697
ISDATBSI412MsgLenValidCount_Cnt_M_u16	17856
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	800
ISDATBSI412MsgTimer_mS_M_u32	442090752
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	38440
ISDATBSI432MsgLenValidCount_Cnt_M_u16	25527
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	38633
ISDATDIRASentFltAcc_Cnt_M_u16	26765
ISDATDIRASentTimer_mS_M_u32	1822868736
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	28815
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	14213
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	57241
ISDYN2CMMMsgTimer_mS_M_u32	3024221440
ISDYNAASChkSumInvalidCount_Cnt_M_u16	6506
ISDYNAASChkSumValidCount_Cnt_M_u16	51596
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	38416
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	21067
ISDYNAASMsgLenValidCount_Cnt_M_u16	28422
ISDYNAASMsgTimeValidCount_Cnt_M_u16	6506
ISDYNAASMsgTimer_mS_M_u32	1170101504
ISDYNABRChkSumInvalidCount_Cnt_M_u16	62174
ISDYNABRChkSumValidCount_Cnt_M_u16	5001
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	4213
ISDYNABRMsgCountValidCount_Cnt_M_u16	33495
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	62290
ISDYNABRMsgLenValidCount_Cnt_M_u16	27941
ISDYNABRMsgTimeValidCount_Cnt_M_u16	1017
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	34035

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	26713
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	50783
ISDYNCMM208MsgTimer_mS_M_u32	3526669568
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	34035
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	26713
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	39067
ISDYNCMM388MsgTimer_mS_M_u32	3089356032
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	25949
ISDYNVOLChkSumValidCount_Cnt_M_u16	57712
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	34340
ISDYNVOLMsgCountValidCount_Cnt_M_u16	22510
ISDYNVOLMsgCount_Cnt_M_u08	2
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	55256
ISDYNVOLMsgLenValidCount_Cnt_M_u16	29386
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	34132
ISDYNVOLMsgTimer_mS_M_u32	830575872
IgnOnTimer_mS_M_u32	2700596480
IgnTimeOff_Sec_M_u32	1374756065
ManVehSpd_Kph_M_f32	485.352386
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	38
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	197
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3604645120
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	5
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	783213824
PrevISDATBSI412MsgDLCError_Cnt_M_u08	28
PrevISDATBSI412MsgRxTime_MSec_M_u32	2384729344
PrevISDATBSI432MsgDLCError_Cnt_M_u08	206
PrevISDATBSI432MsgRxTime_MSec_M_u32	3875796224
PrevISDATDIRAMsgTxTime_MSec_M_u32	315102464
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	200
PrevISDYN2CMMMsgRxTime_MSec_M_u32	523707648
PrevISDYNAASMsgDLCError_Cnt_M_u08	148
PrevISDYNAASMsgRxTime_MSec_M_u32	3323434240
PrevISDYNABRMsgDLCError_Cnt_M_u08	50
PrevISDYNABRMsgRxTime_MSec_M_u32	2790249728
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	169
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2423821568
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	54
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4146263296
PrevISDYNVOLMsgDLCError_Cnt_M_u08	94
PrevISDYNVOLMsgRxTime_MSec_M_u32	1274877184
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2540684544
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	292.958191
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	22369
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	14492
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	726
VitesseVehicleBVRampValidCount_Cnt_M_u16	465
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	49263
VitesseVehicleBVSigValidCount_Cnt_M_u16	29106

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBV_Kph_M_f32	612.583008
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	39067
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	10422
VitesseVehiculeRoues_Kph_M_f32	66.736702
k_AASNTCEnableTimeout_mS_u16	12700
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	53052
k_AASNodeTimeout_mS_u16	53148
k_ABSNodeTimeout_mS_u16	32431
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	12831
k_ANGLEVOLANTSigValidThresh_Cnt_u16	56046
k_AngleVolantInvalidThresh_Cnt_u16	40865
k_AngleVolantValidThresh_Cnt_u16	12514
k_BSI552MsgTimeout_mS_u16	56105
k_BSINTCEnableTimeout_mS_u16	19328
k_BSINodeAbsentDiag_Cnt_str.Threshold	42443
k_BSINodeAbsentDiag_Cnt_str.PStep	39713
k_BSINodeAbsentDiag_Cnt_str.NStep	12731
k_BSINodeAbsentTimeout_mS_u16	11169
k_BSINodeTimeout_mS_u16	38633
k_BattOvHi_Volt_f32	30.6331005
k_BattOvLo_Volt_f32	4.7881999
k_BattUvHi_Volt_f32	12.8985996
k_BattUvLo_Volt_f32	24.7719994
k_CAVNTCEnableTimeout_mS_u16	15184
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	33794
k_CAVNodeTimeout_mS_u16	3187
k_CMM388MsgTimeout_mS_u16	33408
k_CMM388NTCEnableTimeout_mS_u16	22188
k_CMMNTCEnableTimeout_mS_u16	26740
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	47842
k_CONSANGLECPKMax_HwDeg_f32	690.087524
k_CONSANGLECPKMin_HwDeg_f32	-172.632904
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	61339
k_CONSANGLECPKSigValidThresh_Cnt_u16	49078
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	35802
k_CPKVehicleSpeedValidThresh_Cnt_u16	16648
k_CityParkInputInvalidThresh_Cnt_u16	35228
k_CityParkInputValidThresh_Cnt_u16	9561
k_ComputerRazGCTSigValidThresh_Cnt_u16	4922
k_CptTemporelSigValidThresh_Cnt_u16	49185
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	51794
k_DMDFCTCPKSigValidThresh_Cnt_u16	33829
k_DMDFCTCPKValidCount_Cnt_u16	32301
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	57241
k_DMDRELAXECPKSigValidThresh_Cnt_u16	20259
k_DMDRelaxeConsistentThresh_Cnt_u16	28001
k_DateValidThresh_Cnt_u16	18838
k_DefaultVehSpd_Kph_f32	226.368698
k_DiagMuxOnAbsentTimeout_mS_u16	55783
k_EMNodeTimeout_mS_u16	7920
k_ESPNTCEnableTimeout_mS_u16	61720
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	28042
k_EtatMTSigInvalidThresh_Cnt_u16	35313
k_EtatMTSigValidThresh_Cnt_u16	58076
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	63321
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	19447
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	64206
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	65157
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	7596
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	30397
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	4369

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	27488
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	59132
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	26285
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	10275
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	58826
k_ISDATDIRASentDiag_Cnt_str.Threshold	25385
k_ISDATDIRASentDiag_Cnt_str.PStep	45245
k_ISDATDIRASentDiag_Cnt_str.NStep	44580
k_ISDATDIRASentTimeout_mS_u16	24586
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	30123
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	3145
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	31636
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	18910
k_ISDYNAASChkSumValidThresh_Cnt_u16	43657
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	59253
k_ISDYNAASMsgCountValidThresh_Cnt_u16	39383
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	7346
k_ISDYNAASMsgLenValidThresh_Cnt_u16	13680
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	45974
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	21096
k_ISDYNABRChkSumValidThresh_Cnt_u16	4283
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	52613
k_ISDYNABRMsgCountValidThresh_Cnt_u16	17224
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	7252
k_ISDYNABRMsgLenValidThresh_Cnt_u16	29411
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	21819
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	56629
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	49566
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	11535
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	57466
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	5117
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	50234
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	47712
k_ISDYNVOLChkSumValidThresh_Cnt_u16	17271
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	12204
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	46173
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	30028
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	49547
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	6788
k_IgnOnTimeout_mS_u16	52108
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	168.896606
k_PowerCutVehSpdLowThresh_Kph_f32	168.810593
k_PowerCutVehSpdLowTimeout_mS_u16	15096
k_VBattMaxAAS_Volt_f32	19.6355
k_VBattMaxBSI_Volt_f32	30.3005009
k_VBattMaxCAV_Volt_f32	27.5993996
k_VBattMaxCMM388_Volt_f32	27.3679008
k_VBattMaxCMM_Volt_f32	14.0321999
k_VBattMaxESP_Volt_f32	16.1872997
k_VBattMinAAS_Volt_f32	10.7866001
k_VBattMinBSI_Volt_f32	16.1872997
k_VBattMinCAV_Volt_f32	13.9911003
k_VBattMinCMM388_Volt_f32	8.19639969
k_VBattMinCMM_Volt_f32	21.9008999
k_VBattMinESP_Volt_f32	14.0321999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	63597
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	36084
k_VitesseVehicleBVRampValidThresh_Cnt_u16	56612
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	63600
k_VitesseVehicleBVSigValidThresh_Cnt_u16	38438
k_VitesseVehicleBVSpeedPassThresh_kph_f32	636.143799
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	42732
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	43623
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	790115584
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	5160
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1267377920
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	54
target_SrlComInput_Per1_Batt_Volt_f32.value	25.7861996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2642896128
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	168
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.703670263
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	116
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3905541376
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	559445248
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2960594176
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	4263884032
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1919177984
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1966273792
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1855034624
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	0
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1165669632
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	155
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	156
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	204
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2995311872
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	225
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4170675456
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1429607680
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	47
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	77
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	89
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	90
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	138
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	149
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4050183424
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3585
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.700641513
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1039470
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	140.367493

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	7587		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1267377920	1267377920	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1267377920	1267377920	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	42443	42443	✔
BSINodeAbsentTimer_mS_M_u32	1267377920	1267377920	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1267377920	1267377920	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1267377920	1267377920	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	1017	1017	✔
CONSANGLECPK_HwDeg_M_f32	605.843201	605.843201 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1267377920	1267377920	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1267377920	1267377920	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1267377920	1267377920	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1267377920	1267377920	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1267377920	1267377920	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1267377920	1267377920	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1267377920	1267377920	✔
ESPNTCEnableTimer_mS_M_u32	1267377920	1267377920	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1267377920	1267377920	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1267377920	1267377920	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	654	654	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1267377920	1267377920	✔
ElecIntTimer_mS_M_u32[1]	90	90	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1267377920	1267377920	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1267377920	1267377920	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1267377920	1267377920	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	2	2	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1267377920	1267377920	✔
IgnOnTimer_mS_M_u32	2700596480	2700596480	✔
IgnTimeOff_Sec_M_u32	1374756065	1374756065	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	116	116	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3905541376	3905541376	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	200	200	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	559445248	559445248	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	63	63	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2960594176	2960594176	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	64	64	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	4263884032	4263884032	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	315102464	315102464	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	131	131	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1966273792	1966273792	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1855034624	1855034624	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	206	206	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1165669632	1165669632	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	95	95	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2995311872	2995311872	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	225	225	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4170675456	4170675456	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1429607680	1429607680	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4050183424	4050183424	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	292.958191	292.958191	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	612.583008	612.583008	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	66.736702	66.736702	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	1017	1017	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1374756065	1374756065	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	605.843201	605.843201 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	226.368698	226.368698	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.436 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1747416064
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	1137
AASNodeAbsentTimer_mS_M_u32	2370429952
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	62594
ANGLEVOLANTSigValidCount_Cnt_M_u16	49338
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	17942
AngleVolantMsgTimer_mS_M_u32	1747416064
AngleVolantValidCount_Cnt_M_u16	65249
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3535250432
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	90842112
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3232175104
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1492898816
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	6497
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2373161984
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	28589
CAVNodeAbsentTimer_mS_M_u32	2885518336
CDD_SrlComVehSpd_Kph_G_f32	399.556702
CMM388NTCEnableTimer_mS_M_u32	1065075712
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2990769152
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	39733
CMMNodeAbsentTimer_mS_M_u32	490066944
CONSANGLECPKSigInvalidCount_Cnt_M_u16	50204
CONSANGLECPKSigValidCount_Cnt_M_u16	17444
CONSANGLECPK_Cnt_M_u16	19143
CONSANGLECPK_HwDeg_M_f32	447.909912
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	19143
CPKVehicleSpeedMsgTimer_mS_M_u32	2063496192
CPKVehicleSpeedValidCount_Cnt_M_u16	7747

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	34149
CityParkInputInvalidCount_Cnt_M_u16	54220
CityParkInputMsgTimer_mS_M_u32	3905541376
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3033392128
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	4341
ComputerRazGCTSigInvalidTimer_mS_M_u32	221381632
ComputerRazGCTSigValidCount_Cnt_M_u16	17026
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	35144
DMDFCTCPKSigValidCount_Cnt_M_u16	43048
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	59076
DMDRELAXECPKSigValidCount_Cnt_M_u16	16508
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	26305
DateInvalidTimer_mS_M_u32	90842112
DiagMuxOnAbsentTimer_mS_M_u32	3061789696
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1492898816
ESPNTCEnableTimer_mS_M_u32	3895649280
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	11849
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	123
EffacDefaultDiagTimer_mS_M_u32[1]	234
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2970981376
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	41681
EtatMTSigValidCount_Cnt_M_u16	61396
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	64606
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	35302
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	30830
ISDAT4V2BSI552MsgTimer_mS_M_u32	2679755776
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	7773
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	48617
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	61396
ISDATBSI3F2MsgTimer_mS_M_u32	1446851584
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	20725
ISDATBSI412MsgLenValidCount_Cnt_M_u16	56881
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	41681
ISDATBSI412MsgTimer_mS_M_u32	4259673088
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	47289
ISDATBSI432MsgLenValidCount_Cnt_M_u16	9933
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	52918
ISDATDIRASentFltAcc_Cnt_M_u16	59850
ISDATDIRASentTimer_mS_M_u32	2063496192
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	56581
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	65249
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	25511
ISDYN2CMMMsgTimer_mS_M_u32	1290593280
ISDYNAASChkSumInvalidCount_Cnt_M_u16	58035
ISDYNAASChkSumValidCount_Cnt_M_u16	63755
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	53056
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	42128
ISDYNAASMsgLenValidCount_Cnt_M_u16	54560
ISDYNAASMsgTimeValidCount_Cnt_M_u16	58035
ISDYNAASMsgTimer_mS_M_u32	2180498432
ISDYNABRChkSumInvalidCount_Cnt_M_u16	8150
ISDYNABRChkSumValidCount_Cnt_M_u16	1174
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	59794
ISDYNABRMsgCountValidCount_Cnt_M_u16	47402
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	17915
ISDYNABRMsgLenValidCount_Cnt_M_u16	48963
ISDYNABRMsgTimeValidCount_Cnt_M_u16	19143

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	55839
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	52992
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	61396
ISDYNCMM208MsgTimer_mS_M_u32	773104640
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	55839
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	52992
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	45983
ISDYNCMM388MsgTimer_mS_M_u32	2697413632
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	56282
ISDYNVOLChkSumValidCount_Cnt_M_u16	20066
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	23558
ISDYNVOLMsgCountValidCount_Cnt_M_u16	44390
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	36458
ISDYNVOLMsgLenValidCount_Cnt_M_u16	9298
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	39733
ISDYNVOLMsgTimer_mS_M_u32	3685614592
IgnOnTimer_mS_M_u32	910902272
IgnTimeOff_Sec_M_u32	2736816935
ManVehSpd_Kph_M_f32	105.181602
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	39
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	96
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3143840768
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	196
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4251325440
PrevISDATBSI412MsgDLCError_Cnt_M_u08	71
PrevISDATBSI412MsgRxTime_MSec_M_u32	1875280896
PrevISDATBSI432MsgDLCError_Cnt_M_u08	57
PrevISDATBSI432MsgRxTime_MSec_M_u32	1017570304
PrevISDATDIRAMsgTxTime_MSec_M_u32	1910146048
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	171
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2630702080
PrevISDYNAASMsgDLCError_Cnt_M_u08	137
PrevISDYNAASMsgRxTime_MSec_M_u32	4125885440
PrevISDYNABRMsgDLCError_Cnt_M_u08	9
PrevISDYNABRMsgRxTime_MSec_M_u32	2252555264
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	197
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1523123200
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	151
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1212802048
PrevISDYNVOLMsgDLCError_Cnt_M_u08	205
PrevISDYNVOLMsgRxTime_MSec_M_u32	3661333504
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1587770368
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	172.803207
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	27982
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	20574
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	32495
VitesseVehicleBVRampValidCount_Cnt_M_u16	2239
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	58275

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	30363
VitesseVehicleBV_Kph_M_f32	595.832275
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	45983
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	2575
VitesseVehiculeRoues_Kph_M_f32	252.813904
k_AASNTCEnableTimeout_mS_u16	3550
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	54204
k_AASNodeTimeout_mS_u16	35678
k_ABSNodeTimeout_mS_u16	24165
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	32980
k_ANGLEVOLANTSigValidThresh_Cnt_u16	23848
k_AngleVolantInvalidThresh_Cnt_u16	39695
k_AngleVolantValidThresh_Cnt_u16	54220
k_BSI552MsgTimeout_mS_u16	32438
k_BSINTCEnableTimeout_mS_u16	63665
k_BSINodeAbsentDiag_Cnt_str.Threshold	39053
k_BSINodeAbsentDiag_Cnt_str.PStep	52616
k_BSINodeAbsentDiag_Cnt_str.NStep	679
k_BSINodeAbsentTimeout_mS_u16	18446
k_BSINodeTimeout_mS_u16	52918
k_BattOvHi_Volt_f32	30.8896999
k_BattOvLo_Volt_f32	6.32229996
k_BattUvHi_Volt_f32	19.4104004
k_BattUvLo_Volt_f32	6.9907999
k_CAVNTCEnableTimeout_mS_u16	60546
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	43883
k_CAVNodeTimeout_mS_u16	48792
k_CMM388MsgTimeout_mS_u16	32625
k_CMM388NTCEnableTimeout_mS_u16	45805
k_CMMNTCEnableTimeout_mS_u16	6741
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	907
k_CONSANGLECPKMax_HwDeg_f32	721.044373
k_CONSANGLECPKMin_HwDeg_f32	-473.576508
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	44703
k_CONSANGLECPKSigValidThresh_Cnt_u16	17679
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	52900
k_CPKVehicleSpeedValidThresh_Cnt_u16	12696
k_CityParkInputInvalidThresh_Cnt_u16	54172
k_CityParkInputValidThresh_Cnt_u16	34149
k_ComputerRazGCTSigValidThresh_Cnt_u16	45571
k_CptTemporelSigValidThresh_Cnt_u16	57871
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	49403
k_DMDFCTCPKSigValidThresh_Cnt_u16	31299
k_DMDFCTCPKValidCount_Cnt_u16	8809
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	25511
k_DMDRELAXECPKSigValidThresh_Cnt_u16	56263
k_DMDRelaxeConsistentThresh_Cnt_u16	63757
k_DateValidThresh_Cnt_u16	30830
k_DefaultVehSpd_Kph_f32	0.342099994
k_DiagMuxOnAbsentTimeout_mS_u16	253
k_EMNodeTimeout_mS_u16	47905
k_ESPNTCEnableTimeout_mS_u16	15401
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	35731
k_EtatMTSigInvalidThresh_Cnt_u16	26269
k_EtatMTSigValidThresh_Cnt_u16	41629
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	18471
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	24843
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	6406
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	56354
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	46446
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	42105

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	11262
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	62418
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	5693
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	62123
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	9479
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	7249
k_ISDATDIRASentDiag_Cnt_str.Threshold	25991
k_ISDATDIRASentDiag_Cnt_str.PStep	29762
k_ISDATDIRASentDiag_Cnt_str.NStep	4038
k_ISDATDIRASentTimeout_mS_u16	34898
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	12462
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	17942
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	36021
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	6870
k_ISDYNAASChkSumValidThresh_Cnt_u16	16278
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	25746
k_ISDYNAASMsgCountValidThresh_Cnt_u16	29738
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	62042
k_ISDYNAASMsgLenValidThresh_Cnt_u16	43490
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	29488
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	185
k_ISDYNABRChkSumValidThresh_Cnt_u16	44161
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	37985
k_ISDYNABRMsgCountValidThresh_Cnt_u16	55769
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	54837
k_ISDYNABRMsgLenValidThresh_Cnt_u16	43337
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	12288
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	11218
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	34774
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	65285
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	28546
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	31674
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	31172
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	9616
k_ISDYNVOLChkSumValidThresh_Cnt_u16	33036
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	55022
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	29210
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	64589
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	44624
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	15780
k_IgnOnTimeout_mS_u16	41484
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	49.2585983
k_PowerCutVehSpdLowThresh_Kph_f32	89.5164032
k_PowerCutVehSpdLowTimeout_mS_u16	25034
k_VBattMaxAAS_Volt_f32	10.3739996
k_VBattMaxBSI_Volt_f32	31.0370998
k_VBattMaxCAV_Volt_f32	29.2467003
k_VBattMaxCMM388_Volt_f32	12.4745998
k_VBattMaxCMM_Volt_f32	8.75020027
k_VBattMaxESP_Volt_f32	3.79949999
k_VBattMinAAS_Volt_f32	4.79069996
k_VBattMinBSI_Volt_f32	3.79949999
k_VBattMinCAV_Volt_f32	15.2543001
k_VBattMinCMM388_Volt_f32	27.5466003
k_VBattMinCMM_Volt_f32	10.7643003
k_VBattMinESP_Volt_f32	8.75020027
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	12392
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	10644
k_VitesseVehicleBVRampValidThresh_Cnt_u16	22278
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	2402
k_VitesseVehicleBVSigValidThresh_Cnt_u16	42750
k_VitesseVehicleBVSpeedPassThresh_kph_f32	7.89760017
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	27309
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	59133
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	90842112
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	38458
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3227176448
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	151
target_SrlComInput_Per1_Batt_Volt_f32.value	19.4473991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3000800256
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	155
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.261920035
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	651510784
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2141807616
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	349012992
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2923537408
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	335922176
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	236577792
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1685980160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	0
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	201
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1816306688
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	47
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	85
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	109
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	180
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	189
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	189
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	207
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	213
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2241348608
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	50
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3052168192
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3801121792
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	123
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	138
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	155
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	208
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	218
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	235
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	490214400
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2269
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.060418766
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	63541
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	221.095795
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	41608

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3227176448	3227176448	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	17944	17944	✔
AngleVolantMsgTimer_mS_M_u32	3227176448	3227176448	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	39053	39053	✔
BSINodeAbsentTimer_mS_M_u32	3227176448	3227176448	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3227176448	3227176448	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3227176448	3227176448	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	19143	19143	✔
CONSANGLECPK_HwDeg_M_f32	447.909912	447.909912 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	19143	19143	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2063496192	2063496192	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	7747	7747	✔
CityParkInputConsistentCount_Cnt_M_u16	34149	34149	✔
CityParkInputInvalidCount_Cnt_M_u16	54220	54220	✔
CityParkInputMsgTimer_mS_M_u32	3227176448	3227176448	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3227176448	3227176448	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3227176448	3227176448	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3227176448	3227176448	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3227176448	3227176448	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3227176448	3227176448	✔
ESPNTCEnableTimer_mS_M_u32	3227176448	3227176448	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3227176448	3227176448	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	123	123	✔
EffacDefaultDiagTimer_mS_M_u32[1]	234	234	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3227176448	3227176448	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3227176448	3227176448	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3227176448	3227176448	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3227176448	3227176448	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3227176448	3227176448	✔
IgnOnTimer_mS_M_u32	3227176448	3227176448	✔
IgnTimeOff_Sec_M_u32	2736816935	2736816935	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	651510784	651510784	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	192	192	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2141807616	2141807616	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	126	126	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	349012992	349012992	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	220	220	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2923537408	2923537408	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1910146048	1910146048	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	154	154	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	236577792	236577792	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	137	137	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1685980160	1685980160	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	201	201	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1816306688	1816306688	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	213	213	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2241348608	2241348608	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	50	50	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3052168192	3052168192	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	40	40	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3801121792	3801121792	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	490214400	490214400	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	172.803207	172.803207	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	595.832275	595.832275	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	252.813904	252.813904	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	19143	19143	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2736816935	2736816935	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	447.909912	447.909912 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0.342099994	0.342099994	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.437 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2851628800
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	7960
AASNodeAbsentTimer_mS_M_u32	273749760
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	12519
ANGLEVOLANTSigValidCount_Cnt_M_u16	55295
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	11817
AngleVolantMsgTimer_mS_M_u32	2851628800
AngleVolantValidCount_Cnt_M_u16	21579
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	654825216
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2029016832
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2801370880
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	553338624
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	65098
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	311691008
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	54246
CAVNodeAbsentTimer_mS_M_u32	2327197440
CDD_SrlComVehSpd_Kph_G_f32	177.291901
CMM388NTCEnableTimer_mS_M_u32	2570811136
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	266614528
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	60941
CMMNodeAbsentTimer_mS_M_u32	1011697408
CONSANGLECPKSigInvalidCount_Cnt_M_u16	22810
CONSANGLECPKSigValidCount_Cnt_M_u16	9410
CONSANGLECPK_Cnt_M_u16	23769
CONSANGLECPK_HwDeg_M_f32	70.9914017
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	23769
CPKVehicleSpeedMsgTimer_mS_M_u32	2373150464
CPKVehicleSpeedValidCount_Cnt_M_u16	2060

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	53439
CityParkInputInvalidCount_Cnt_M_u16	37513
CityParkInputMsgTimer_mS_M_u32	651510784
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2848265984
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	2444
ComputerRazGCTSigInvalidTimer_mS_M_u32	3642275584
ComputerRazGCTSigValidCount_Cnt_M_u16	19816
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	25109
DMDFCTCPKSigValidCount_Cnt_M_u16	45365
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	57889
DMDRELAXECPKSigValidCount_Cnt_M_u16	57529
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	17707
DateInvalidTimer_mS_M_u32	2029016832
DiagMuxOnAbsentTimer_mS_M_u32	3455133440
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	553338624
ESPNTCEnableTimer_mS_M_u32	3818264320
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	45201
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	4560
EffacDefaultDiagTimer_mS_M_u32[1]	8523
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	657
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2947417856
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	21563
EtatMTSigValidCount_Cnt_M_u16	43247
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	14420
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	56188
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	55395
ISDAT4V2BSI552MsgTimer_mS_M_u32	3301000960
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	2838
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	34866
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	43247
ISDATBSI3F2MsgTimer_mS_M_u32	1723279104
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	9293
ISDATBSI412MsgLenValidCount_Cnt_M_u16	39002
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	21563
ISDATBSI412MsgTimer_mS_M_u32	1623090944
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	42369
ISDATBSI432MsgLenValidCount_Cnt_M_u16	55045
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	6859
ISDATDIRASentFltAcc_Cnt_M_u16	6543
ISDATDIRASentTimer_mS_M_u32	2373150464
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	7711
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	21579
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	3832
ISDYN2CMMMsgTimer_mS_M_u32	493360896
ISDYNAASChkSumInvalidCount_Cnt_M_u16	3154
ISDYNAASChkSumValidCount_Cnt_M_u16	21771
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	7982
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	33085
ISDYNAASMsgLenValidCount_Cnt_M_u16	23373
ISDYNAASMsgTimeValidCount_Cnt_M_u16	3154
ISDYNAASMsgTimer_mS_M_u32	3251074816
ISDYNABRChkSumInvalidCount_Cnt_M_u16	63594
ISDYNABRChkSumValidCount_Cnt_M_u16	30186
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	13237
ISDYNABRMsgCountValidCount_Cnt_M_u16	20654
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	3965
ISDYNABRMsgLenValidCount_Cnt_M_u16	61285
ISDYNABRMsgTimeValidCount_Cnt_M_u16	23769

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	38963
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	22609
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	43247
ISDYNCMM208MsgTimer_mS_M_u32	3371226880
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	38963
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	22609
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	44561
ISDYNCMM388MsgTimer_mS_M_u32	56162048
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	35296
ISDYNVOLChkSumValidCount_Cnt_M_u16	32264
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	25051
ISDYNVOLMsgCountValidCount_Cnt_M_u16	6523
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	21550
ISDYNVOLMsgLenValidCount_Cnt_M_u16	24118
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	60941
ISDYNVOLMsgTimer_mS_M_u32	1571075840
IgnOnTimer_mS_M_u32	1389164288
IgnTimeOff_Sec_M_u32	684696701
ManVehSpd_Kph_M_f32	418.819397
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	58
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1329932032
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	115
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2898036480
PrevISDATBSI412MsgDLCError_Cnt_M_u08	147
PrevISDATBSI412MsgRxTime_MSec_M_u32	2740664064
PrevISDATBSI432MsgDLCError_Cnt_M_u08	168
PrevISDATBSI432MsgRxTime_MSec_M_u32	3057260288
PrevISDATDIRAMsgTxTime_MSec_M_u32	3978245888
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	44
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2072430336
PrevISDYNAASMsgDLCError_Cnt_M_u08	208
PrevISDYNAASMsgRxTime_MSec_M_u32	2263529216
PrevISDYNABRMsgDLCError_Cnt_M_u08	66
PrevISDYNABRMsgRxTime_MSec_M_u32	1122301696
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	173
PrevISDYNCMM208MsgRxTime_MSec_M_u32	206812928
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	202
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3746633472
PrevISDYNVOLMsgDLCError_Cnt_M_u08	30
PrevISDYNVOLMsgRxTime_MSec_M_u32	2013017856
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3062130432
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	431.957092
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	40707
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	24979
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	11808
VitesseVehicleBVRampValidCount_Cnt_M_u16	64624
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	10116

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	31324
VitesseVehicleBV_Kph_M_f32	267.879608
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	44561
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	38529
VitesseVehiculeRoues_Kph_M_f32	18.8666
k_AASNTCEnableTimeout_mS_u16	12180
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	442
k_AASNodeTimeout_mS_u16	45203
k_ABSNodeTimeout_mS_u16	38590
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	31024
k_ANGLEVOLANTSigValidThresh_Cnt_u16	24564
k_AngleVolantInvalidThresh_Cnt_u16	575
k_AngleVolantValidThresh_Cnt_u16	37513
k_BSI552MsgTimeout_mS_u16	38028
k_BSINTCEnableTimeout_mS_u16	50585
k_BSINodeAbsentDiag_Cnt_str.Threshold	19051
k_BSINodeAbsentDiag_Cnt_str.PStep	31929
k_BSINodeAbsentDiag_Cnt_str.NStep	16027
k_BSINodeAbsentTimeout_mS_u16	2113
k_BSINodeTimeout_mS_u16	6859
k_BattOvHi_Volt_f32	2.25169992
k_BattOvLo_Volt_f32	24.7598
k_BattUvHi_Volt_f32	3.23729992
k_BattUvLo_Volt_f32	3.39409995
k_CAVNTCEnableTimeout_mS_u16	41063
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	39084
k_CAVNodeTimeout_mS_u16	22950
k_CMM388MsgTimeout_mS_u16	44568
k_CMM388NTCEnableTimeout_mS_u16	932
k_CMMNTCEnableTimeout_mS_u16	63278
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	39437
k_CONSANGLECPKMax_HwDeg_f32	596.092896
k_CONSANGLECPKMin_HwDeg_f32	-75.6975021
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	48401
k_CONSANGLECPKSigValidThresh_Cnt_u16	58753
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	32449
k_CPKVehicleSpeedValidThresh_Cnt_u16	52836
k_CityParkInputInvalidThresh_Cnt_u16	29976
k_CityParkInputValidThresh_Cnt_u16	53439
k_ComputerRazGCTSigValidThresh_Cnt_u16	26660
k_CptTemporelSigValidThresh_Cnt_u16	13248
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	40573
k_DMDFCTCPKSigValidThresh_Cnt_u16	48741
k_DMDFCTCPKValidCount_Cnt_u16	818
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	3832
k_DMDRELAXECPKSigValidThresh_Cnt_u16	21080
k_DMDRelaxeConsistentThresh_Cnt_u16	37510
k_DateValidThresh_Cnt_u16	55395
k_DefaultVehSpd_Kph_f32	73.9064026
k_DiagMuxOnAbsentTimeout_mS_u16	37431
k_EMNodeTimeout_mS_u16	51211
k_ESPNTCEnableTimeout_mS_u16	24178
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	8693
k_EtatMTSigInvalidThresh_Cnt_u16	21
k_EtatMTSigValidThresh_Cnt_u16	30677
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	56888
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	20300
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	55772
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	9671
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	62883
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	14785

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	40882
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	50166
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	40181
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	62765
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	63961
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	33593
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	44790
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	64034
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	11817
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	40142
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	1898
k_ISDYNAASChkSumValidThresh_Cnt_u16	50410
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	49845
k_ISDYNAASMsgCountValidThresh_Cnt_u16	8110
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	37086
k_ISDYNAASMsgLenValidThresh_Cnt_u16	25863
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	15836
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	22339
k_ISDYNABRChkSumValidThresh_Cnt_u16	40875
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	36170
k_ISDYNABRMsgCountValidThresh_Cnt_u16	51362
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	15629
k_ISDYNABRMsgLenValidThresh_Cnt_u16	16273
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	8749
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	29559
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	17322
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	45470
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	49127
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	42751
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	32929
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	53884
k_ISDYNVOLChkSumValidThresh_Cnt_u16	56265
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	35490
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	15710
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	14279
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	23931
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	57537
k_IgnOnTimeout_mS_u16	19720
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	41.6567993
k_PowerCutVehSpdLowThresh_Kph_f32	56.8834
k_PowerCutVehSpdLowTimeout_mS_u16	58320
k_VBattMaxAAS_Volt_f32	0.451400012
k_VBattMaxBSI_Volt_f32	11.4876003
k_VBattMaxCAV_Volt_f32	13.5391998
k_VBattMaxCMM388_Volt_f32	17.2558994
k_VBattMaxCMM_Volt_f32	27.6236
k_VBattMaxESP_Volt_f32	4.93179989
k_VBattMinAAS_Volt_f32	14.5909004
k_VBattMinBSI_Volt_f32	4.93179989
k_VBattMinCAV_Volt_f32	21.9685001
k_VBattMinCMM388_Volt_f32	0.367199987
k_VBattMinCMM_Volt_f32	10.7208996
k_VBattMinESP_Volt_f32	27.6236
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	25332
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	21296
k_VitesseVehicleBVRampValidThresh_Cnt_u16	28891
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	19720
k_VitesseVehicleBVSigValidThresh_Cnt_u16	4084
k_VitesseVehicleBVSpeedPassThresh_kph_f32	301.740814
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	58086
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	55734
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2029016832
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	1664
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	927357184
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	202
target_SrlComInput_Per1_Batt_Volt_f32.value	11.3992996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2253981440
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	177
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.947681129
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	690943744
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	177
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	389191424
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2420520704
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	205
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1013569280
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3281876736
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3454080768
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	53786368
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	0
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	0
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1181144832
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	7
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	30
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	56
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	239
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	228
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3638949632
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1080661760
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4076680960
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	108
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	213
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	356943616
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1950
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.528817356
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	315163
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	35.395401
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	26453

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	927357184	927357184	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	927357184	927357184	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	927357184	927357184	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	927357184	927357184	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	927357184	927357184	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	927357184	927357184	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	927357184	927357184	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	19051	19051	✔
BSINodeAbsentTimer_mS_M_u32	927357184	927357184	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	927357184	927357184	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	927357184	927357184	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	927357184	927357184	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	927357184	927357184	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	927357184	927357184	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	23769	23769	✔
CONSANGLECPK_HwDeg_M_f32	70.9914017	70.9914017 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	927357184	927357184	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	927357184	927357184	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	927357184	927357184	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	927357184	927357184	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	927357184	927357184	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	927357184	927357184	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	927357184	927357184	✔
ESPNTCEnableTimer_mS_M_u32	927357184	927357184	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	927357184	927357184	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	4560	4560	✔
EffacDefaultDiagTimer_mS_M_u32[1]	8523	8523	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	927357184	927357184	✔
ElecIntTimer_mS_M_u32[1]	657	657	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	927357184	927357184	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	927357184	927357184	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	927357184	927357184	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	927357184	927357184	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	927357184	927357184	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	927357184	927357184	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	927357184	927357184	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	927357184	927357184	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	927357184	927357184	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	927357184	927357184	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	927357184	927357184	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	927357184	927357184	✔
IgnOnTimer_mS_M_u32	927357184	927357184	✔
IgnTimeOff_Sec_M_u32	684696701	684696701	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	9	9	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	690943744	690943744	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	177	177	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	389191424	389191424	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	15	15	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2420520704	2420520704	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	205	205	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1013569280	1013569280	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3978245888	3978245888	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	5	5	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3454080768	3454080768	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	208	208	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	53786368	53786368	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	75	75	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1181144832	1181144832	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	228	228	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3638949632	3638949632	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	37	37	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1080661760	1080661760	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	221	221	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4076680960	4076680960	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	356943616	356943616	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	431.957092	431.957092	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	267.879608	267.879608	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	18.8666	18.8666	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	23769	23769	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	684696701	684696701	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	70.9914017	70.9914017 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.438 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2349960704
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	20144
AASNodeAbsentTimer_mS_M_u32	3620175360
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	29508
ANGLEVOLANTSigValidCount_Cnt_M_u16	23227
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	42365
AngleVolantMsgTimer_mS_M_u32	2349960704
AngleVolantValidCount_Cnt_M_u16	16792
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3735240192
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	719961600
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2173578752
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1250487808
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	22299
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3367939584
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	19656
CAVNodeAbsentTimer_mS_M_u32	3843563008
CDD_SrlComVehSpd_Kph_G_f32	60.9571991
CMM388NTCEnableTimer_mS_M_u32	1585995264
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2374901248
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	10258
CMMNodeAbsentTimer_mS_M_u32	3230854656
CONSANGLECPKSigInvalidCount_Cnt_M_u16	13740
CONSANGLECPKSigValidCount_Cnt_M_u16	61299
CONSANGLECPK_Cnt_M_u16	25390
CONSANGLECPK_HwDeg_M_f32	534.339478
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	25390
CPKVehicleSpeedMsgTimer_mS_M_u32	2376109568
CPKVehicleSpeedValidCount_Cnt_M_u16	37021
CityParkInputConsistentCount_Cnt_M_u16	0

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	20445
CityParkInputMsgTimer_mS_M_u32	690943744
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3681254912
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	24404
ComputerRazGCTSigInvalidTimer_mS_M_u32	2750455296
ComputerRazGCTSigValidCount_Cnt_M_u16	2625
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	4409
DMDFCTCPKSigValidCount_Cnt_M_u16	8344
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	51094
DMDRELAXECPKSigValidCount_Cnt_M_u16	43149
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	62841
DateInvalidTimer_mS_M_u32	719961600
DiagMuxOnAbsentTimer_mS_M_u32	4079439360
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1250487808
ESPNTCEnableTimer_mS_M_u32	2985852416
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	27973
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	456
EffacDefaultDiagTimer_mS_M_u32[1]	654
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	90
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3648040448
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	32391
EtatMTSigValidCount_Cnt_M_u16	52523
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	65534
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	13125
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	58126
ISDAT4V2BSI552MsgTimer_mS_M_u32	4147572224
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	56694
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	21218
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	52523
ISDATBSI3F2MsgTimer_mS_M_u32	3235204608
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	32465
ISDATBSI412MsgLenValidCount_Cnt_M_u16	53100
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	32391
ISDATBSI412MsgTimer_mS_M_u32	4290743808
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	53686
ISDATBSI432MsgLenValidCount_Cnt_M_u16	51689
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	19481
ISDATDIRASentFltAcc_Cnt_M_u16	24525
ISDATDIRASentTimer_mS_M_u32	2376109568
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	46940
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	16792
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	22160
ISDYN2CMMMsgTimer_mS_M_u32	3431104000
ISDYNAASChkSumInvalidCount_Cnt_M_u16	61186
ISDYNAASChkSumValidCount_Cnt_M_u16	29081
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	11503
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	24771
ISDYNAASMsgLenValidCount_Cnt_M_u16	36691
ISDYNAASMsgTimeValidCount_Cnt_M_u16	61186
ISDYNAASMsgTimer_mS_M_u32	350510592
ISDYNABRChkSumInvalidCount_Cnt_M_u16	16443
ISDYNABRChkSumValidCount_Cnt_M_u16	17531
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	50393
ISDYNABRMsgCountValidCount_Cnt_M_u16	51888
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	24195
ISDYNABRMsgLenValidCount_Cnt_M_u16	56202
ISDYNABRMsgTimeValidCount_Cnt_M_u16	25390
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	34035

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	26713
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	52523
ISDYNCMM208MsgTimer_mS_M_u32	3706207744
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	34035
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	26713
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	52294
ISDYNCMM388MsgTimer_mS_M_u32	1982848512
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	15194
ISDYNVOLChkSumValidCount_Cnt_M_u16	31649
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	43495
ISDYNVOLMsgCountValidCount_Cnt_M_u16	32710
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	13934
ISDYNVOLMsgLenValidCount_Cnt_M_u16	46358
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	10258
ISDYNVOLMsgTimer_mS_M_u32	1179426304
IgnOnTimer_mS_M_u32	1473502720
IgnTimeOff_Sec_M_u32	539799275
ManVehSpd_Kph_M_f32	604.828613
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	59
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	137
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3207286272
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	146
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1011166720
PrevISDATBSI412MsgDLCError_Cnt_M_u08	51
PrevISDATBSI412MsgRxTime_MSec_M_u32	1864965632
PrevISDATBSI432MsgDLCError_Cnt_M_u08	58
PrevISDATBSI432MsgRxTime_MSec_M_u32	3389816320
PrevISDATDIRAMsgTxTime_MSec_M_u32	2715622912
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	31
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3370544640
PrevISDYNAASMsgDLCError_Cnt_M_u08	114
PrevISDYNAASMsgRxTime_MSec_M_u32	1652203008
PrevISDYNABRMsgDLCError_Cnt_M_u08	80
PrevISDYNABRMsgRxTime_MSec_M_u32	3884703232
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	48
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3057622528
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	30
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1791458816
PrevISDYNVOLMsgDLCError_Cnt_M_u08	65
PrevISDYNVOLMsgRxTime_MSec_M_u32	3041271296
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2523762176
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	573.747925
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	40817
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	5249
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	42522
VitesseVehicleBVRampValidCount_Cnt_M_u16	63466
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	17261
VitesseVehicleBVSigValidCount_Cnt_M_u16	10148

Name	Input Value
VitesseVehicleBV_Kph_M_f32	376.310608
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	52294
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	20405
VitesseVehiculeRoues_Kph_M_f32	363.174713
k_AASNTCEnableTimeout_mS_u16	38653
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	46411
k_AASNodeTimeout_mS_u16	10113
k_ABSNodeTimeout_mS_u16	22334
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	53929
k_ANGLEVOLANTSigValidThresh_Cnt_u16	43804
k_AngleVolantInvalidThresh_Cnt_u16	45115
k_AngleVolantValidThresh_Cnt_u16	20445
k_BSI552MsgTimeout_mS_u16	16788
k_BSINTCEnableTimeout_mS_u16	53614
k_BSINodeAbsentDiag_Cnt_str.Threshold	42443
k_BSINodeAbsentDiag_Cnt_str.PStep	39713
k_BSINodeAbsentDiag_Cnt_str.NStep	12731
k_BSINodeAbsentTimeout_mS_u16	30517
k_BSINodeTimeout_mS_u16	19481
k_BattOvHi_Volt_f32	7.23899984
k_BattOvLo_Volt_f32	28.2961998
k_BattUvHi_Volt_f32	7.13840008
k_BattUvLo_Volt_f32	20.4741001
k_CAVNTCEnableTimeout_mS_u16	7747
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	38518
k_CAVNodeTimeout_mS_u16	25608
k_CMM388MsgTimeout_mS_u16	41392
k_CMM388NTCEnableTimeout_mS_u16	53516
k_CMMNTCEnableTimeout_mS_u16	31022
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	29969
k_CONSANGLECPKMax_HwDeg_f32	237.377701
k_CONSANGLECPKMin_HwDeg_f32	-584.291321
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	40774
k_CONSANGLECPKSigValidThresh_Cnt_u16	25269
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	62711
k_CPKVehicleSpeedValidThresh_Cnt_u16	40076
k_CityParkInputInvalidThresh_Cnt_u16	561
k_CityParkInputValidThresh_Cnt_u16	39996
k_ComputerRazGCTSigValidThresh_Cnt_u16	32332
k_CptTemporelSigValidThresh_Cnt_u16	2104
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	45443
k_DMDFCTCPKSigValidThresh_Cnt_u16	28298
k_DMDFCTCPKValidCount_Cnt_u16	59491
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	22160
k_DMDRELAXECPKSigValidThresh_Cnt_u16	35119
k_DMDRelaxeConsistentThresh_Cnt_u16	165
k_DateValidThresh_Cnt_u16	58126
k_DefaultVehSpd_Kph_f32	114.760498
k_DiagMuxOnAbsentTimeout_mS_u16	47892
k_EMNodeTimeout_mS_u16	60633
k_ESPNTCEnableTimeout_mS_u16	56612
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	32089
k_EtatMTSigInvalidThresh_Cnt_u16	38202
k_EtatMTSigValidThresh_Cnt_u16	43706
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	29330
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	60437
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	13541
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	37219
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	3727
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	3701
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	59171

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	1814
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	47962
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	59954
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	2286
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	7951
k_ISDATDIRASentDiag_Cnt_str.Threshold	2451
k_ISDATDIRASentDiag_Cnt_str.PStep	5266
k_ISDATDIRASentDiag_Cnt_str.NStep	3881
k_ISDATDIRASentTimeout_mS_u16	19607
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	40532
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	42365
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	37392
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	4923
k_ISDYNAASChkSumValidThresh_Cnt_u16	22395
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	6105
k_ISDYNAASMsgCountValidThresh_Cnt_u16	23984
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	18143
k_ISDYNAASMsgLenValidThresh_Cnt_u16	55845
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	45412
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	7985
k_ISDYNABRChkSumValidThresh_Cnt_u16	25272
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	43547
k_ISDYNABRMsgCountValidThresh_Cnt_u16	54482
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	15122
k_ISDYNABRMsgLenValidThresh_Cnt_u16	49221
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	46129
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	61973
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	54458
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	4192
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	50756
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	60859
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	58773
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	61508
k_ISDYNVOLChkSumValidThresh_Cnt_u16	33055
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	25362
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	48671
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	995
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	57223
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	49652
k_IgnOnTimeout_mS_u16	45216
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	124.009003
k_PowerCutVehSpdLowThresh_Kph_f32	182.3293
k_PowerCutVehSpdLowTimeout_mS_u16	27209
k_VBattMaxAAS_Volt_f32	9.27779961
k_VBattMaxBSI_Volt_f32	21.0932007
k_VBattMaxCAV_Volt_f32	24.8964996
k_VBattMaxCMM388_Volt_f32	21.5452003
k_VBattMaxCMM_Volt_f32	25.8589993
k_VBattMaxESP_Volt_f32	8.56630039
k_VBattMinAAS_Volt_f32	7.69040012
k_VBattMinBSI_Volt_f32	8.56630039
k_VBattMinCAV_Volt_f32	1.25199997
k_VBattMinCMM388_Volt_f32	20.2297001
k_VBattMinCMM_Volt_f32	10.1483002
k_VBattMinESP_Volt_f32	25.8589993
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	11230
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	51177
k_VitesseVehicleBVRampValidThresh_Cnt_u16	31975
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	3745
k_VitesseVehicleBVSigValidThresh_Cnt_u16	62109
k_VitesseVehicleBVSpeedPassThresh_kph_f32	213.836105
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	8136
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	63512
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	719961600
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	49721
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3262101504
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	30
target_SrlComInput_Per1_Batt_Volt_f32.value	18.7369995
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3245321728
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	148
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.221821114
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	71
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3702382080
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	71
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	690159104
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	98
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	342367744
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	160
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2793225728
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3881983488
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	163
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3742858752
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	122
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2510069248
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	124
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	137
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	182
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	219
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	223
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	237
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3162914304
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	84
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	146
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	163
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	216
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	228
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	82
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1770577408
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1232993792
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2286099968
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	30
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	150
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	191
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2863083008
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2241
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0319046155
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	197669
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	151.043396

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	3707		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	3262101504	3262101504	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3262101504	3262101504	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3262101504	3262101504	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3262101504	3262101504	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3262101504	3262101504	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3262101504	3262101504	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3262101504	3262101504	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	42443	42443	✔
BSINodeAbsentTimer_mS_M_u32	3262101504	3262101504	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3262101504	3262101504	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3262101504	3262101504	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3262101504	3262101504	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3262101504	3262101504	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3262101504	3262101504	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	25390	25390	✔
CONSANGLECPK_HwDeg_M_f32	534.339478	534.339478 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3262101504	3262101504	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3262101504	3262101504	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3262101504	3262101504	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3262101504	3262101504	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3262101504	3262101504	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3262101504	3262101504	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3262101504	3262101504	✔
ESPNTCEnableTimer_mS_M_u32	3262101504	3262101504	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3262101504	3262101504	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	456	456	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	654	654	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	8	8	✔
ElecIntTimer_mS_M_u32[1]	90	90	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3262101504	3262101504	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3262101504	3262101504	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3262101504	3262101504	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3262101504	3262101504	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3262101504	3262101504	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3262101504	3262101504	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3262101504	3262101504	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3262101504	3262101504	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3262101504	3262101504	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3262101504	3262101504	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3262101504	3262101504	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3262101504	3262101504	✔
IgnOnTimer_mS_M_u32	1473502720	1473502720	✔
IgnTimeOff_Sec_M_u32	539799275	539799275	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	71	71	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3702382080	3702382080	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	71	71	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	690159104	690159104	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	98	98	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	342367744	342367744	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	160	160	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2793225728	2793225728	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2715622912	2715622912	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	163	163	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3742858752	3742858752	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	122	122	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2510069248	2510069248	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	90	90	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3162914304	3162914304	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	82	82	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1770577408	1770577408	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	134	134	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1232993792	1232993792	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2286099968	2286099968	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2863083008	2863083008	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	573.747925	573.747925	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	376.310608	376.310608	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	363.174713	363.174713	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	25390	25390	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	539799275	539799275	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	534.339478	534.339478 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	114.760498	114.760498	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.439 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	522328320
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	28998
AASNodeAbsentTimer_mS_M_u32	3217049856
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	62857
ANGLEVOLANTSigValidCount_Cnt_M_u16	43234
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	57567
AngleVolantMsgTimer_mS_M_u32	522328320
AngleVolantValidCount_Cnt_M_u16	57614
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3391949056
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	525961472
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2032941312
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2033973504
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	26116
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	94025984
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	8572
CAVNodeAbsentTimer_mS_M_u32	575564032
CDD_SrlComVehSpd_Kph_G_f32	257.052887
CMM388NTCEnableTimer_mS_M_u32	3338512640
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2162977024
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	4703
CMMNodeAbsentTimer_mS_M_u32	3206412544
CONSANGLECPKSigInvalidCount_Cnt_M_u16	64849
CONSANGLECPKSigValidCount_Cnt_M_u16	31163
CONSANGLECPK_Cnt_M_u16	51850
CONSANGLECPK_HwDeg_M_f32	-121.794701
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	51850
CPKVehicleSpeedMsgTimer_mS_M_u32	376772864
CPKVehicleSpeedValidCount_Cnt_M_u16	54566
CityParkInputConsistentCount_Cnt_M_u16	65535

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	23358
CityParkInputMsgTimer_mS_M_u32	3702382080
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1154763008
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	53082
ComputerRazGCTSigInvalidTimer_mS_M_u32	3888441600
ComputerRazGCTSigValidCount_Cnt_M_u16	27411
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	34602
DMDFCTCPKSigValidCount_Cnt_M_u16	25292
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	49299
DMDRELAXECPKSigValidCount_Cnt_M_u16	34668
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	12778
DateInvalidTimer_mS_M_u32	525961472
DiagMuxOnAbsentTimer_mS_M_u32	1893783808
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2033973504
ESPNTCEnableTimer_mS_M_u32	892160256
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	40069
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	123
EffacDefaultDiagTimer_mS_M_u32[1]	234
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	102
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	461682944
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	29695
EtatMTSigValidCount_Cnt_M_u16	41429
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	26203
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	30277
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	29546
ISDAT4V2BSI552MsgTimer_mS_M_u32	2872178944
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	52401
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	42543
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	41429
ISDATBSI3F2MsgTimer_mS_M_u32	1071044864
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	8611
ISDATBSI412MsgLenValidCount_Cnt_M_u16	10640
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	29695
ISDATBSI412MsgTimer_mS_M_u32	4229437696
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	42355
ISDATBSI432MsgLenValidCount_Cnt_M_u16	5785
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	42889
ISDATDIRASentFltAcc_Cnt_M_u16	15469
ISDATDIRASentTimer_mS_M_u32	376772864
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	1536
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	57614
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	54053
ISDYN2CMMMsgTimer_mS_M_u32	2374977792
ISDYNAASChkSumInvalidCount_Cnt_M_u16	22608
ISDYNAASChkSumValidCount_Cnt_M_u16	47690
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	15113
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	37259
ISDYNAASMsgLenValidCount_Cnt_M_u16	53149
ISDYNAASMsgTimeValidCount_Cnt_M_u16	22608
ISDYNAASMsgTimer_mS_M_u32	334080256
ISDYNABRChkSumInvalidCount_Cnt_M_u16	9250
ISDYNABRChkSumValidCount_Cnt_M_u16	41252
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	62155
ISDYNABRMsgCountValidCount_Cnt_M_u16	51973
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	40652
ISDYNABRMsgLenValidCount_Cnt_M_u16	53622
ISDYNABRMsgTimeValidCount_Cnt_M_u16	51850
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	55839

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	52992
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	41429
ISDYNCMM208MsgTimer_mS_M_u32	593365248
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	55839
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	52992
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	30980
ISDYNCMM388MsgTimer_mS_M_u32	2114398464
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	9287
ISDYNVOLChkSumValidCount_Cnt_M_u16	3377
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	62752
ISDYNVOLMsgCountValidCount_Cnt_M_u16	32066
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	9482
ISDYNVOLMsgLenValidCount_Cnt_M_u16	53972
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	4703
ISDYNVOLMsgTimer_mS_M_u32	1890642176
IgnOnTimer_mS_M_u32	1763387648
IgnTimeOff_Sec_M_u32	1364662938
ManVehSpd_Kph_M_f32	70.7966995
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	60
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	197
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	483711232
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	229
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3842455808
PrevISDATBSI412MsgDLCError_Cnt_M_u08	246
PrevISDATBSI412MsgRxTime_MSec_M_u32	136014080
PrevISDATBSI432MsgDLCError_Cnt_M_u08	24
PrevISDATBSI432MsgRxTime_MSec_M_u32	1022445824
PrevISDATDIRAMsgTxTime_MSec_M_u32	1073703168
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	18
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1411610880
PrevISDYNAASMsgDLCError_Cnt_M_u08	148
PrevISDYNAASMsgRxTime_MSec_M_u32	1411836160
PrevISDYNABRMsgDLCError_Cnt_M_u08	39
PrevISDYNABRMsgRxTime_MSec_M_u32	2582849792
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	40
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2899831040
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	141
PrevISDYNCMM388MsgRxTime_MSec_M_u32	113264896
PrevISDYNVOLMsgDLCError_Cnt_M_u08	193
PrevISDYNVOLMsgRxTime_MSec_M_u32	3921963264
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1879972096
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	139.041702
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	3457
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	30739
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	56710
VitesseVehicleBVRampValidCount_Cnt_M_u16	45528
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	26894
VitesseVehicleBVSigValidCount_Cnt_M_u16	9767

Name	Input Value
VitesseVehicleBV_Kph_M_f32	175.002899
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	30980
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	14453
VitesseVehiculeRoues_Kph_M_f32	525.915588
k_AASNTCEnableTimeout_mS_u16	11037
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	4597
k_AASNodeTimeout_mS_u16	16147
k_ABSNodeTimeout_mS_u16	2331
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	11930
k_ANGLEVOLANTSigValidThresh_Cnt_u16	65280
k_AngleVolantInvalidThresh_Cnt_u16	11171
k_AngleVolantValidThresh_Cnt_u16	23358
k_BSI552MsgTimeout_mS_u16	40664
k_BSINTCEnableTimeout_mS_u16	34379
k_BSINodeAbsentDiag_Cnt_str.Threshold	39053
k_BSINodeAbsentDiag_Cnt_str.PStep	52616
k_BSINodeAbsentDiag_Cnt_str.NStep	679
k_BSINodeAbsentTimeout_mS_u16	19383
k_BSINodeTimeout_mS_u16	42889
k_BattOvHi_Volt_f32	13.6507998
k_BattOvLo_Volt_f32	9.73449993
k_BattUvHi_Volt_f32	5.38329983
k_BattUvLo_Volt_f32	21.4575005
k_CAVNTCEnableTimeout_mS_u16	2060
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	31858
k_CAVNodeTimeout_mS_u16	57917
k_CMM388MsgTimeout_mS_u16	30790
k_CMM388NTCEnableTimeout_mS_u16	23090
k_CMMNTCEnableTimeout_mS_u16	55689
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	14433
k_CONSANGLECPKMax_HwDeg_f32	536.670471
k_CONSANGLECPKMin_HwDeg_f32	-186.202499
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	4
k_CONSANGLECPKSigValidThresh_Cnt_u16	65397
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	11953
k_CPKVehicleSpeedValidThresh_Cnt_u16	29810
k_CityParkInputInvalidThresh_Cnt_u16	13888
k_CityParkInputValidThresh_Cnt_u16	24866
k_ComputerRazGCTSigValidThresh_Cnt_u16	49711
k_CptTemporelSigValidThresh_Cnt_u16	24109
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	42444
k_DMDFCTCPKSigValidThresh_Cnt_u16	6262
k_DMDFCTCPKValidCount_Cnt_u16	53804
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	54053
k_DMDRELAXECPKSigValidThresh_Cnt_u16	17671
k_DMDRelaxeConsistentThresh_Cnt_u16	13989
k_DateValidThresh_Cnt_u16	29546
k_DefaultVehSpd_Kph_f32	23.5575008
k_DiagMuxOnAbsentTimeout_mS_u16	56024
k_EMNodeTimeout_mS_u16	52170
k_ESPNTCEnableTimeout_mS_u16	57448
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	16265
k_EtatMTSigInvalidThresh_Cnt_u16	57637
k_EtatMTSigValidThresh_Cnt_u16	10855
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	57824
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	3862
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	31527
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	42218
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	26408
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	695
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	22828

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	21266
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	30855
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	17790
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	25356
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	2536
k_ISDATDIRASentDiag_Cnt_str.Threshold	42732
k_ISDATDIRASentDiag_Cnt_str.PStep	3144
k_ISDATDIRASentDiag_Cnt_str.NStep	10267
k_ISDATDIRASentTimeout_mS_u16	28430
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	57369
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	57567
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	29092
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	43810
k_ISDYNAASChkSumValidThresh_Cnt_u16	26660
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	63947
k_ISDYNAASMsgCountValidThresh_Cnt_u16	4613
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	41014
k_ISDYNAASMsgLenValidThresh_Cnt_u16	46887
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	3112
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	38082
k_ISDYNABRChkSumValidThresh_Cnt_u16	29676
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	27908
k_ISDYNABRMsgCountValidThresh_Cnt_u16	22173
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	55647
k_ISDYNABRMsgLenValidThresh_Cnt_u16	41861
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	62592
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	42389
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	1000
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	49270
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	64649
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	61410
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	31254
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	22858
k_ISDYNVOLChkSumValidThresh_Cnt_u16	41079
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	12062
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	50232
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	21483
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	56001
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	61112
k_IgnOnTimeout_mS_u16	34870
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	2.3118999
k_PowerCutVehSpdLowThresh_Kph_f32	27.3509998
k_PowerCutVehSpdLowTimeout_mS_u16	57657
k_VBattMaxAAS_Volt_f32	18.8099003
k_VBattMaxBSI_Volt_f32	13.5922003
k_VBattMaxCAV_Volt_f32	5.30840015
k_VBattMaxCMM388_Volt_f32	24.9657001
k_VBattMaxCMM_Volt_f32	4.77330017
k_VBattMaxESP_Volt_f32	15.7559996
k_VBattMinAAS_Volt_f32	0.0790000036
k_VBattMinBSI_Volt_f32	15.7559996
k_VBattMinCAV_Volt_f32	5.3112998
k_VBattMinCMM388_Volt_f32	19.8565998
k_VBattMinCMM_Volt_f32	20.1623001
k_VBattMinESP_Volt_f32	4.77330017
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	57211
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	50456
k_VitesseVehicleBVRampValidThresh_Cnt_u16	31776
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	21553
k_VitesseVehicleBVSigValidThresh_Cnt_u16	8703
k_VitesseVehicleBVSpeedPassThresh_kph_f32	188.759094
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	43132
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	59726
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	525961472
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	39273
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	19897088
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	141
target_SrlComInput_Per1_Batt_Volt_f32.value	21.1438007
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	528988416
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	172
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.601477563
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3264030976
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	120
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2578303232
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3562957056
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	103
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1520371968
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	342862080
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	85
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3922741504
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	47
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3267422464
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	59
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	85
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	92
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	176
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	201
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	155
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2089027840
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	125
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	141
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	161
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	188
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	211
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	218
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	102
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1207707904
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	232
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1687996672
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	25
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2764925184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	61
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	97
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	122
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	145
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	153
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	169
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2715891968
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3303
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.404879808
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	238533
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	152.458603

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	26723		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	19897088	19897088	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	19897088	19897088	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	19897088	19897088	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	19897088	19897088	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	19897088	19897088	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	19897088	19897088	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	19897088	19897088	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	39053	39053	✔
BSINodeAbsentTimer_mS_M_u32	19897088	19897088	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	19897088	19897088	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	19897088	19897088	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	19897088	19897088	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	19897088	19897088	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	19897088	19897088	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	51850	51850	✔
CONSANGLECPK_HwDeg_M_f32	-121.794701	-121.794701 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	19897088	19897088	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	19897088	19897088	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	19897088	19897088	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	19897088	19897088	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	19897088	19897088	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	19897088	19897088	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	19897088	19897088	✔
ESPNTCEnableTimer_mS_M_u32	19897088	19897088	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	19897088	19897088	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	19897088	19897088	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	234	234	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	19897088	19897088	✔
ElecIntTimer_mS_M_u32[1]	102	102	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	19897088	19897088	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	19897088	19897088	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	19897088	19897088	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	19897088	19897088	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	19897088	19897088	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	19897088	19897088	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	19897088	19897088	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	19897088	19897088	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	19897088	19897088	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	19897088	19897088	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	19897088	19897088	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	19897088	19897088	✔
IgnOnTimer_mS_M_u32	19897088	19897088	✔
IgnTimeOff_Sec_M_u32	1364662938	1364662938	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	91	91	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3264030976	3264030976	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	120	120	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2578303232	2578303232	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	132	132	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3562957056	3562957056	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	103	103	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1520371968	1520371968	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1073703168	1073703168	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	85	85	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3922741504	3922741504	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	47	47	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3267422464	3267422464	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	155	155	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2089027840	2089027840	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	102	102	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1207707904	1207707904	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	232	232	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1687996672	1687996672	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	25	25	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2764925184	2764925184	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2715891968	2715891968	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	139.041702	139.041702	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	175.002899	175.002899	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	525.915588	525.915588	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	51850	51850	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1364662938	1364662938	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-121.794701	-121.794701 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	23.5575008	23.5575008	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.440 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	702314496
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	25966
AASNodeAbsentTimer_mS_M_u32	3166824448
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	679
ANGLEVOLANTSigValidCount_Cnt_M_u16	43866
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	47779
AngleVolantMsgTimer_mS_M_u32	702314496
AngleVolantValidCount_Cnt_M_u16	15512
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1081845760
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2465605632
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1816008704
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1527699456
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	23862
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2700253184
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	21836
CAVNodeAbsentTimer_mS_M_u32	4120348672
CDD_SrlComVehSpd_Kph_G_f32	414.639404
CMM388NTCEnableTimer_mS_M_u32	3565799424
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3518859264
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	64099
CMMNodeAbsentTimer_mS_M_u32	2439567360
CONSANGLECPKSigInvalidCount_Cnt_M_u16	65101
CONSANGLECPKSigValidCount_Cnt_M_u16	35792
CONSANGLECPK_Cnt_M_u16	38243
CONSANGLECPK_HwDeg_M_f32	327.815094
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	38243
CPKVehicleSpeedMsgTimer_mS_M_u32	1340307456
CPKVehicleSpeedValidCount_Cnt_M_u16	23766
CityParkInputConsistentCount_Cnt_M_u16	3164
CityParkInputInvalidCount_Cnt_M_u16	57095
CityParkInputMsgTimer_mS_M_u32	3264030976
CityParkInputValidCount_Cnt_M_u16	7

Name	Input Value
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2105927680
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	39730
ComputerRazGCTSigInvalidTimer_mS_M_u32	2670987264
ComputerRazGCTSigValidCount_Cnt_M_u16	62089
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	2883
DMDFCTCPKSigValidCount_Cnt_M_u16	23326
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	18825
DMDRELAXECPKSigValidCount_Cnt_M_u16	47036
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	1154
DateInvalidTimer_mS_M_u32	2465605632
DiagMuxOnAbsentTimer_mS_M_u32	2678077440
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1527699456
ESPNTCEnableTimer_mS_M_u32	1350232064
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	20146
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	4560
EffacDefaultDiagTimer_mS_M_u32[1]	8523
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	657
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2268370944
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	42627
EtatMTSigValidCount_Cnt_M_u16	53185
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	27439
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	15922
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	8516
ISDAT4V2BSI552MsgTimer_mS_M_u32	489478144
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	15341
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	564
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	53185
ISDATBSI3F2MsgTimer_mS_M_u32	2327721984
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	37401
ISDATBSI412MsgLenValidCount_Cnt_M_u16	36112
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	42627
ISDATBSI412MsgTimer_mS_M_u32	3942283264
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	37159
ISDATBSI432MsgLenValidCount_Cnt_M_u16	12406
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	14117
ISDATDIRASentFltAcc_Cnt_M_u16	2169
ISDATDIRASentTimer_mS_M_u32	1340307456
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	15105
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	15512
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	54098
ISDYN2CMMMsgTimer_mS_M_u32	1330964480
ISDYNAASChkSumInvalidCount_Cnt_M_u16	22608
ISDYNAASChkSumValidCount_Cnt_M_u16	29987
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	55975
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	287
ISDYNAASMsgLenValidCount_Cnt_M_u16	59818
ISDYNAASMsgTimeValidCount_Cnt_M_u16	22608
ISDYNAASMsgTimer_mS_M_u32	2646984704
ISDYNABRChkSumInvalidCount_Cnt_M_u16	46681
ISDYNABRChkSumValidCount_Cnt_M_u16	41492
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	13535
ISDYNABRMsgCountValidCount_Cnt_M_u16	61170
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	50652
ISDYNABRMsgLenValidCount_Cnt_M_u16	12447
ISDYNABRMsgTimeValidCount_Cnt_M_u16	38243
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	38963
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	22609
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	53185
ISDYNCMM208MsgTimer_mS_M_u32	954771456

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	38963
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	22609
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	52406
ISDYNCMM388MsgTimer_mS_M_u32	3043837952
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	57707
ISDYNVOLChkSumValidCount_Cnt_M_u16	10606
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	6497
ISDYNVOLMsgCountValidCount_Cnt_M_u16	25532
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	2339
ISDYNVOLMsgLenValidCount_Cnt_M_u16	33414
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	64099
ISDYNVOLMsgTimer_mS_M_u32	3027240960
IgnOnTimer_mS_M_u32	1144080384
IgnTimeOff_Sec_M_u32	2298190796
ManVehSpd_Kph_M_f32	575.373779
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	58
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	92
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1808021504
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	75
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1420630016
PrevISDATBSI412MsgDLCError_Cnt_M_u08	54
PrevISDATBSI412MsgRxTime_MSec_M_u32	3090188288
PrevISDATBSI432MsgDLCError_Cnt_M_u08	49
PrevISDATBSI432MsgRxTime_MSec_M_u32	1227810816
PrevISDATDIRAMsgTxTime_MSec_M_u32	2693040128
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	69
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3361232896
PrevISDYNAASMsgDLCError_Cnt_M_u08	80
PrevISDYNAASMsgRxTime_MSec_M_u32	1645086720
PrevISDYNABRMsgDLCError_Cnt_M_u08	17
PrevISDYNABRMsgRxTime_MSec_M_u32	296306688
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	45
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1543178240
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	111
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3888244736
PrevISDYNVOLMsgDLCError_Cnt_M_u08	246
PrevISDYNVOLMsgRxTime_MSec_M_u32	4147480576
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3877140480
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	445.630707
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	58685
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	18504
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	51502
VitesseVehicleBVRampValidCount_Cnt_M_u16	61177
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	64536
VitesseVehicleBVSigValidCount_Cnt_M_u16	34699
VitesseVehicleBV_Kph_M_f32	37.7792015
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	52406
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	45345

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	19.5457001
k_AASNTCEnableTimeout_mS_u16	32682
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	1507
k_AASNodeTimeout_mS_u16	62280
k_ABSNodeTimeout_mS_u16	35184
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	20914
k_ANGLEVOLANTSigValidThresh_Cnt_u16	54081
k_AngleVolantInvalidThresh_Cnt_u16	39256
k_AngleVolantValidThresh_Cnt_u16	57095
k_BSI552MsgTimeout_mS_u16	51704
k_BSINTCEnableTimeout_mS_u16	20127
k_BSINodeAbsentDiag_Cnt_str.Threshold	19051
k_BSINodeAbsentDiag_Cnt_str.PStep	31929
k_BSINodeAbsentDiag_Cnt_str.NStep	16027
k_BSINodeAbsentTimeout_mS_u16	55835
k_BSINodeTimeout_mS_u16	14117
k_BattOvHi_Volt_f32	9.51290035
k_BattOvLo_Volt_f32	5.99550009
k_BattUvHi_Volt_f32	27.5235004
k_BattUvLo_Volt_f32	6.05600023
k_CAVNTCEnableTimeout_mS_u16	37021
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	40042
k_CAVNodeTimeout_mS_u16	65417
k_CMM388MsgTimeout_mS_u16	20590
k_CMM388NTCEnableTimeout_mS_u16	23210
k_CMMNTCEnableTimeout_mS_u16	30053
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	24925
k_CONSANGLECPKMax_HwDeg_f32	749.037903
k_CONSANGLECPKMin_HwDeg_f32	-779.703186
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	14262
k_CONSANGLECPKSigValidThresh_Cnt_u16	23585
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	7278
k_CPKVehicleSpeedValidThresh_Cnt_u16	38316
k_CityParkInputInvalidThresh_Cnt_u16	30719
k_CityParkInputValidThresh_Cnt_u16	3164
k_ComputerRazGCTSigValidThresh_Cnt_u16	54131
k_CptTemporelSigValidThresh_Cnt_u16	21050
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	45276
k_DMDFCTCPKSigValidThresh_Cnt_u16	23455
k_DMDFCTCPKValidCount_Cnt_u16	47294
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	54098
k_DMDRELAXECPKSigValidThresh_Cnt_u16	24685
k_DMDRelaxeConsistentThresh_Cnt_u16	33683
k_DateValidThresh_Cnt_u16	8516
k_DefaultVehSpd_Kph_f32	59.0882988
k_DiagMuxOnAbsentTimeout_mS_u16	7289
k_EMNodeTimeout_mS_u16	46818
k_ESPNTCEnableTimeout_mS_u16	51336
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	60389
k_EtatMTSigInvalidThresh_Cnt_u16	19280
k_EtatMTSigValidThresh_Cnt_u16	53835
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	32481
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	10752
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	4685
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	55106
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	58185
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	16093
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	39420
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	40715
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	26603
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	62599

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	11934
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	32329
k_ISDATDIRASentDiag_Cnt_str.Threshold	53644
k_ISDATDIRASentDiag_Cnt_str.PStep	28273
k_ISDATDIRASentDiag_Cnt_str.NStep	22576
k_ISDATDIRASentTimeout_mS_u16	34197
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	65462
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	47779
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	1236
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	8537
k_ISDYNAASChkSumValidThresh_Cnt_u16	19732
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	8159
k_ISDYNAASMsgCountValidThresh_Cnt_u16	6642
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	37405
k_ISDYNAASMsgLenValidThresh_Cnt_u16	56076
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	19401
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	15354
k_ISDYNABRChkSumValidThresh_Cnt_u16	41277
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	18486
k_ISDYNABRMsgCountValidThresh_Cnt_u16	20009
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	42339
k_ISDYNABRMsgLenValidThresh_Cnt_u16	14770
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	49280
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	27905
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	16202
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	47903
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	60839
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	54874
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	57983
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	18212
k_ISDYNVOLChkSumValidThresh_Cnt_u16	33883
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	15079
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	35032
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	46783
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	54525
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	26458
k_IgnOnTimeout_mS_u16	27232
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	103.325104
k_PowerCutVehSpdLowThresh_Kph_f32	196.207901
k_PowerCutVehSpdLowTimeout_mS_u16	52566
k_VBattMaxAAS_Volt_f32	28.6177006
k_VBattMaxBSI_Volt_f32	19.5849991
k_VBattMaxCAV_Volt_f32	2.05859995
k_VBattMaxCMM388_Volt_f32	13.2763004
k_VBattMaxCMM_Volt_f32	29.6063004
k_VBattMaxESP_Volt_f32	20.3448009
k_VBattMinAAS_Volt_f32	23.2896996
k_VBattMinBSI_Volt_f32	20.3448009
k_VBattMinCAV_Volt_f32	16.8419991
k_VBattMinCMM388_Volt_f32	22.7705002
k_VBattMinCMM_Volt_f32	12.6687002
k_VBattMinESP_Volt_f32	29.6063004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	2448
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	11127
k_VitesseVehicleBVRampValidThresh_Cnt_u16	33889
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	21614
k_VitesseVehicleBVSigValidThresh_Cnt_u16	32197
k_VitesseVehicleBVSpeedPassThresh_kph_f32	104.832497
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	49228
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	41111
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2465605632
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	25798
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2486956544
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	111
target_SrlComInput_Per1_Batt_Volt_f32.value	18.6637001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1194039296
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	141
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.654153466
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2145077248
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	124
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3304679424
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	526878720
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3609569280
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	875808768
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2123491328
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4265609216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	57
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	93
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	161
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	179
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	193
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	252
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1165404160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	92
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	121
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	130
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1804486656
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3761006592
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	706381824
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	129
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	130
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	148
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	161
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	102701056
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1109
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.781219244
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	24238
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	239.134903
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	56471

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2486956544	2486956544	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2486956544	2486956544	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	47779	47779	✔
AngleVolantMsgTimer_mS_M_u32	2486956544	2486956544	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2486956544	2486956544	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2486956544	2486956544	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2486956544	2486956544	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2486956544	2486956544	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	19051	19051	✔
BSINodeAbsentTimer_mS_M_u32	2486956544	2486956544	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2486956544	2486956544	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2486956544	2486956544	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2486956544	2486956544	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2486956544	2486956544	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2486956544	2486956544	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	38243	38243	✔
CONSANGLECPK_HwDeg_M_f32	327.815094	327.815094 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	38243	38243	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1340307456	1340307456	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	23766	23766	✔
CityParkInputConsistentCount_Cnt_M_u16	3164	3164	✔
CityParkInputInvalidCount_Cnt_M_u16	57095	57095	✔
CityParkInputMsgTimer_mS_M_u32	2486956544	2486956544	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2486956544	2486956544	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2486956544	2486956544	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2486956544	2486956544	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2486956544	2486956544	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2486956544	2486956544	✔
ESPNTCEnableTimer_mS_M_u32	2486956544	2486956544	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2486956544	2486956544	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4560	4560	✔
EffacDefaultDiagTimer_mS_M_u32[1]	8523	8523	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2486956544	2486956544	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	657	657	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2486956544	2486956544	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2486956544	2486956544	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2486956544	2486956544	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2486956544	2486956544	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2486956544	2486956544	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2486956544	2486956544	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2486956544	2486956544	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2486956544	2486956544	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2486956544	2486956544	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2486956544	2486956544	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2486956544	2486956544	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2486956544	2486956544	✔
IgnOnTimer_mS_M_u32	1144080384	1144080384	✔
IgnTimeOff_Sec_M_u32	2298190796	2298190796	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2145077248	2145077248	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	124	124	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3304679424	3304679424	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	67	67	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	526878720	526878720	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	195	195	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3609569280	3609569280	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2693040128	2693040128	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	15	15	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2123491328	2123491328	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	107	107	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4265609216	4265609216	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	252	252	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1165404160	1165404160	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	130	130	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1804486656	1804486656	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	167	167	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3761006592	3761006592	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	253	253	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	706381824	706381824	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	102701056	102701056	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	445.630707	445.630707	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	37.7792015	37.7792015	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	19.5457001	19.5457001	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	38243	38243	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2298190796	2298190796	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	327.815094	327.815094 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	59.0882988	59.0882988	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.441 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1844009728
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	9521
AASNodeAbsentTimer_mS_M_u32	1459161856
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	53128
ANGLEVOLANTSigValidCount_Cnt_M_u16	36143
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	14738
AngleVolantMsgTimer_mS_M_u32	1844009728
AngleVolantValidCount_Cnt_M_u16	11318
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3805006592
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	4116466432
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3041164032
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	466762496
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	48091
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2301033216
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	21528
CAVNodeAbsentTimer_mS_M_u32	2331519744
CDD_SrlComVehSpd_Kph_G_f32	124.512604
CMM388NTCEnableTimer_mS_M_u32	2267114240
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	243673856
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	64915
CMMNodeAbsentTimer_mS_M_u32	1623472896
CONSANGLECPKSigInvalidCount_Cnt_M_u16	41879
CONSANGLECPKSigValidCount_Cnt_M_u16	62158
CONSANGLECPK_Cnt_M_u16	57877
CONSANGLECPK_HwDeg_M_f32	-74.4483032
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	57877
CPKVehicleSpeedMsgTimer_mS_M_u32	3621018368
CPKVehicleSpeedValidCount_Cnt_M_u16	62947

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	52458
CityParkInputInvalidCount_Cnt_M_u16	4584
CityParkInputMsgTimer_mS_M_u32	2145077248
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	615320320
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	37861
ComputerRazGCTSigInvalidTimer_mS_M_u32	2686626560
ComputerRazGCTSigValidCount_Cnt_M_u16	3683
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	32052
DMDFCTCPKSigValidCount_Cnt_M_u16	58723
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	738
DMDRELAXECPKSigValidCount_Cnt_M_u16	28681
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	42232
DateInvalidTimer_mS_M_u32	4116466432
DiagMuxOnAbsentTimer_mS_M_u32	3416136448
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	466762496
ESPNTCEnableTimer_mS_M_u32	3217951488
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	10342
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	456
EffacDefaultDiagTimer_mS_M_u32[1]	654
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	90
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1583414016
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	34357
EtatMTSigValidCount_Cnt_M_u16	62008
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	25841
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	58280
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	43761
ISDAT4V2BSI552MsgTimer_mS_M_u32	3447208704
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	59254
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	40033
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	62008
ISDATBSI3F2MsgTimer_mS_M_u32	38017792
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	58865
ISDATBSI412MsgLenValidCount_Cnt_M_u16	48332
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	34357
ISDATBSI412MsgTimer_mS_M_u32	579820288
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	18759
ISDATBSI432MsgLenValidCount_Cnt_M_u16	37658
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	21133
ISDATDIRASentFltAcc_Cnt_M_u16	11921
ISDATDIRASentTimer_mS_M_u32	3621018368
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	59707
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	11318
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	8455
ISDYN2CMMMsgTimer_mS_M_u32	2873101056
ISDYNAASChkSumInvalidCount_Cnt_M_u16	21643
ISDYNAASChkSumValidCount_Cnt_M_u16	13779
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	19977
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	23711
ISDYNAASMsgLenValidCount_Cnt_M_u16	47807
ISDYNAASMsgTimeValidCount_Cnt_M_u16	21643
ISDYNAASMsgTimer_mS_M_u32	460155648
ISDYNABRChkSumInvalidCount_Cnt_M_u16	62961
ISDYNABRChkSumValidCount_Cnt_M_u16	2688
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	47838
ISDYNABRMsgCountValidCount_Cnt_M_u16	50278
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	18666
ISDYNABRMsgLenValidCount_Cnt_M_u16	97
ISDYNABRMsgTimeValidCount_Cnt_M_u16	57877

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	34035
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	26713
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	62008
ISDYNCMM208MsgTimer_mS_M_u32	3984902912
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	34035
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	26713
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	29660
ISDYNCMM388MsgTimer_mS_M_u32	3531008768
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	62013
ISDYNVOLChkSumValidCount_Cnt_M_u16	4596
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	19162
ISDYNVOLMsgCountValidCount_Cnt_M_u16	50057
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	64787
ISDYNVOLMsgLenValidCount_Cnt_M_u16	2218
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	64915
ISDYNVOLMsgTimer_mS_M_u32	1349430016
IgnOnTimer_mS_M_u32	908782336
IgnTimeOff_Sec_M_u32	1018439676
ManVehSpd_Kph_M_f32	180.072403
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	59
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	104
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4147256064
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	171
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2012707584
PrevISDATBSI412MsgDLCError_Cnt_M_u08	140
PrevISDATBSI412MsgRxTime_MSec_M_u32	3878497024
PrevISDATBSI432MsgDLCError_Cnt_M_u08	126
PrevISDATBSI432MsgRxTime_MSec_M_u32	2779908864
PrevISDATDIRAMsgTxTime_MSec_M_u32	2117151488
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	59
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3656760064
PrevISDYNAASMsgDLCError_Cnt_M_u08	103
PrevISDYNAASMsgRxTime_MSec_M_u32	1066707712
PrevISDYNABRMsgDLCError_Cnt_M_u08	183
PrevISDYNABRMsgRxTime_MSec_M_u32	2915232512
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	0
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1171106560
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	231
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3589868288
PrevISDYNVOLMsgDLCError_Cnt_M_u08	235
PrevISDYNVOLMsgRxTime_MSec_M_u32	2115906304
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	641030912
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	344.325806
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	43077
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	38629
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	114
VitesseVehicleBVRampValidCount_Cnt_M_u16	42706
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	59189

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	64668
VitesseVehicleBV_Kph_M_f32	498.763885
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	29660
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	24155
VitesseVehiculeRoues_Kph_M_f32	75.3104019
k_AASNTCEnableTimeout_mS_u16	65344
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	48213
k_AASNodeTimeout_mS_u16	38373
k_ABSNodeTimeout_mS_u16	63149
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	62374
k_ANGLEVOLANTSigValidThresh_Cnt_u16	38585
k_AngleVolantInvalidThresh_Cnt_u16	24692
k_AngleVolantValidThresh_Cnt_u16	4584
k_BSI552MsgTimeout_mS_u16	12246
k_BSINTCEnableTimeout_mS_u16	61663
k_BSINodeAbsentDiag_Cnt_str.Threshold	42443
k_BSINodeAbsentDiag_Cnt_str.PStep	39713
k_BSINodeAbsentDiag_Cnt_str.NStep	12731
k_BSINodeAbsentTimeout_mS_u16	47914
k_BSINodeTimeout_mS_u16	21133
k_BattOvHi_Volt_f32	31.4776001
k_BattOvLo_Volt_f32	22.8281994
k_BattUvHi_Volt_f32	30.3220005
k_BattUvLo_Volt_f32	14.4583998
k_CAVNTCEnableTimeout_mS_u16	54566
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	30398
k_CAVNodeTimeout_mS_u16	36835
k_CMM388MsgTimeout_mS_u16	25649
k_CMM388NTCEnableTimeout_mS_u16	13693
k_CMMNTCEnableTimeout_mS_u16	6926
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	15783
k_CONSANGLECPKMax_HwDeg_f32	442.135101
k_CONSANGLECPKMin_HwDeg_f32	-264.560486
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	13020
k_CONSANGLECPKSigValidThresh_Cnt_u16	23899
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	12915
k_CPKVehicleSpeedValidThresh_Cnt_u16	59192
k_CityParkInputInvalidThresh_Cnt_u16	51455
k_CityParkInputValidThresh_Cnt_u16	52458
k_ComputerRazGCTSigValidThresh_Cnt_u16	47332
k_CptTemporelSigValidThresh_Cnt_u16	17487
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	34794
k_DMDFCTCPKSigValidThresh_Cnt_u16	32609
k_DMDFCTCPKValidCount_Cnt_u16	0
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	8455
k_DMDRELAXECPKSigValidThresh_Cnt_u16	53622
k_DMDRelaxeConsistentThresh_Cnt_u16	32772
k_DateValidThresh_Cnt_u16	43761
k_DefaultVehSpd_Kph_f32	74.7304001
k_DiagMuxOnAbsentTimeout_mS_u16	9427
k_EMNodeTimeout_mS_u16	3544
k_ESPNTCEnableTimeout_mS_u16	60004
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	48655
k_EtatMTSigInvalidThresh_Cnt_u16	54028
k_EtatMTSigValidThresh_Cnt_u16	5595
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	38682
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	64893
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	48919
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	43383
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	36130
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	61349

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	49864
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	56155
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	54523
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	21673
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	60964
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	12897
k_ISDATDIRASentDiag_Cnt_str.Threshold	63911
k_ISDATDIRASentDiag_Cnt_str.PStep	39954
k_ISDATDIRASentDiag_Cnt_str.NStep	1837
k_ISDATDIRASentTimeout_mS_u16	30781
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	41498
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	14738
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	25984
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	46321
k_ISDYNAASChkSumValidThresh_Cnt_u16	2432
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	63966
k_ISDYNAASMsgCountValidThresh_Cnt_u16	17254
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	29349
k_ISDYNAASMsgLenValidThresh_Cnt_u16	61081
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	19745
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	56976
k_ISDYNABRChkSumValidThresh_Cnt_u16	42631
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	64219
k_ISDYNABRMsgCountValidThresh_Cnt_u16	41154
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	64659
k_ISDYNABRMsgLenValidThresh_Cnt_u16	26470
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	26045
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	8441
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	57950
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	23136
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	3720
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	3119
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	59264
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	45776
k_ISDYNVOLChkSumValidThresh_Cnt_u16	49899
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	30663
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	26164
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	17793
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	53892
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	45231
k_IgnOnTimeout_mS_u16	14620
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	0.519900024
k_PowerCutVehSpdLowThresh_Kph_f32	241.871506
k_PowerCutVehSpdLowTimeout_mS_u16	50748
k_VBattMaxAAS_Volt_f32	5.66960001
k_VBattMaxBSI_Volt_f32	7.82429981
k_VBattMaxCAV_Volt_f32	22.5373993
k_VBattMaxCMM388_Volt_f32	9.31599998
k_VBattMaxCMM_Volt_f32	27.0671997
k_VBattMaxESP_Volt_f32	16.7921009
k_VBattMinAAS_Volt_f32	8.21510029
k_VBattMinBSI_Volt_f32	16.7921009
k_VBattMinCAV_Volt_f32	32
k_VBattMinCMM388_Volt_f32	31.3323994
k_VBattMinCMM_Volt_f32	23.1914997
k_VBattMinESP_Volt_f32	27.0671997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	27788
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	36503
k_VitesseVehicleBVRampValidThresh_Cnt_u16	2522
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	37108
k_VitesseVehicleBVSigValidThresh_Cnt_u16	23727
k_VitesseVehicleBVSpeedPassThresh_kph_f32	628.979004
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	4888
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	35320
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4116466432
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	49132
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	489876736
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	231
target_SrlComInput_Per1_Batt_Volt_f32.value	1.88320005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3128687360
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	30
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0123880086
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2871847680
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2085784320
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1300769536
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1187891968
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2418240256
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1367935744
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3003034368
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	145
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	234
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2145045248
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	63
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	97
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	105
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	151
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	174
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	175
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	214
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1947462400
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	103
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3065613056
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	165
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3111070464
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	126
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	134
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	182
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	202
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	203
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	227
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2879486720
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2001
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.595763385
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	402613
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	138.3405
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	43575

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	489876736	489876736	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	489876736	489876736	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	14740	14740	✔
AngleVolantMsgTimer_mS_M_u32	489876736	489876736	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	489876736	489876736	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	489876736	489876736	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	489876736	489876736	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	489876736	489876736	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	42443	42443	✔
BSINodeAbsentTimer_mS_M_u32	489876736	489876736	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	489876736	489876736	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	489876736	489876736	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	489876736	489876736	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	489876736	489876736	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	489876736	489876736	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	57877	57877	✔
CONSANGLECPK_HwDeg_M_f32	-74.4483032	-74.4483032 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	57877	57877	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3621018368	3621018368	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	62947	62947	✔
CityParkInputConsistentCount_Cnt_M_u16	52458	52458	✔
CityParkInputInvalidCount_Cnt_M_u16	4586	4586	✔
CityParkInputMsgTimer_mS_M_u32	489876736	489876736	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	489876736	489876736	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	489876736	489876736	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	489876736	489876736	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	489876736	489876736	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	489876736	489876736	✔
ESPNTCEnableTimer_mS_M_u32	489876736	489876736	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	489876736	489876736	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	456	456	✔
EffacDefaultDiagTimer_mS_M_u32[1]	654	654	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	489876736	489876736	✔
ElecIntTimer_mS_M_u32[1]	90	90	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	489876736	489876736	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	489876736	489876736	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	489876736	489876736	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	489876736	489876736	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	489876736	489876736	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	489876736	489876736	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	489876736	489876736	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	489876736	489876736	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	489876736	489876736	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	489876736	489876736	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	489876736	489876736	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	489876736	489876736	✔
IgnOnTimer_mS_M_u32	489876736	489876736	✔
IgnTimeOff_Sec_M_u32	1018439676	1018439676	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2871847680	2871847680	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2085784320	2085784320	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	74	74	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1300769536	1300769536	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	74	74	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1187891968	1187891968	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2117151488	2117151488	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	39	39	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1367935744	1367935744	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	83	83	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3003034368	3003034368	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	35	35	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2145045248	2145045248	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	214	214	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1947462400	1947462400	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	103	103	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3065613056	3065613056	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	165	165	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3111070464	3111070464	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2879486720	2879486720	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	344.325806	344.325806	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	498.763885	498.763885	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	75.3104019	75.3104019	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	57877	57877	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1018439676	1018439676	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-74.4483032	-74.4483032 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.442 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1695461888
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	309
AASNodeAbsentTimer_mS_M_u32	3298796032
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	31793
ANGLEVOLANTSigValidCount_Cnt_M_u16	7164
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	34834
AngleVolantMsgTimer_mS_M_u32	1695461888
AngleVolantValidCount_Cnt_M_u16	18087
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3693568512
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2255872512
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1669157376
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2530480640
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	49976
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2446709248
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	30975
CAVNodeAbsentTimer_mS_M_u32	2367832576
CDD_SrlComVehSpd_Kph_G_f32	405.973694
CMM388NTCEnableTimer_mS_M_u32	3450241536
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3128443392
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	45648
CMMNodeAbsentTimer_mS_M_u32	268308992
CONSANGLECPKSigInvalidCount_Cnt_M_u16	43781
CONSANGLECPKSigValidCount_Cnt_M_u16	54815
CONSANGLECPK_Cnt_M_u16	58442
CONSANGLECPK_HwDeg_M_f32	-243.918198
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	58442
CPKVehicleSpeedMsgTimer_mS_M_u32	2471342592
CPKVehicleSpeedValidCount_Cnt_M_u16	2665
CityParkInputConsistentCount_Cnt_M_u16	13451
CityParkInputInvalidCount_Cnt_M_u16	11920
CityParkInputMsgTimer_mS_M_u32	2871847680
CityParkInputValidCount_Cnt_M_u16	2

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	730046976
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	34073
ComputerRazGCTSigInvalidTimer_mS_M_u32	396542464
ComputerRazGCTSigValidCount_Cnt_M_u16	37920
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	7340
DMDFCTCPKSigValidCount_Cnt_M_u16	56543
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	51747
DMDRELAXECPKSigValidCount_Cnt_M_u16	23406
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	27362
DateInvalidTimer_mS_M_u32	2255872512
DiagMuxOnAbsentTimer_mS_M_u32	250638848
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2530480640
ESPNTCEnableTimer_mS_M_u32	505455104
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	47766
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	23456
EffacDefaultDiagTimer_mS_M_u32[1]	56577
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	658
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2049430016
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	29033
EtatMTSigValidCount_Cnt_M_u16	30240
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	20215
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	60305
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	17461
ISDAT4V2BSI552MsgTimer_mS_M_u32	2581729792
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	59687
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	45861
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	30240
ISDATBSI3F2MsgTimer_mS_M_u32	2197713408
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	60085
ISDATBSI412MsgLenValidCount_Cnt_M_u16	3811
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	29033
ISDATBSI412MsgTimer_mS_M_u32	1595716096
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	40756
ISDATBSI432MsgLenValidCount_Cnt_M_u16	19066
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	37280
ISDATDIRASentFltAcc_Cnt_M_u16	3476
ISDATDIRASentTimer_mS_M_u32	2471342592
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	59096
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	18087
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	15667
ISDYN2CMMMsgTimer_mS_M_u32	2747965952
ISDYNAASChkSumInvalidCount_Cnt_M_u16	23335
ISDYNAASChkSumValidCount_Cnt_M_u16	4113
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	60718
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	15210
ISDYNAASMsgLenValidCount_Cnt_M_u16	55757
ISDYNAASMsgTimeValidCount_Cnt_M_u16	23335
ISDYNAASMsgTimer_mS_M_u32	1086489088
ISDYNABRChkSumInvalidCount_Cnt_M_u16	17527
ISDYNABRChkSumValidCount_Cnt_M_u16	32649
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	13358
ISDYNABRMsgCountValidCount_Cnt_M_u16	28760
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	50956
ISDYNABRMsgLenValidCount_Cnt_M_u16	47462
ISDYNABRMsgTimeValidCount_Cnt_M_u16	58442
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	11204
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	52923
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	30240
ISDYNCMM208MsgTimer_mS_M_u32	3757859328

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	11204
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	52923
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	34741
ISDYNCMM388MsgTimer_mS_M_u32	564527616
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	55059
ISDYNVOLChkSumValidCount_Cnt_M_u16	37037
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	52154
ISDYNVOLMsgCountValidCount_Cnt_M_u16	23149
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	12431
ISDYNVOLMsgLenValidCount_Cnt_M_u16	42634
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	45648
ISDYNVOLMsgTimer_mS_M_u32	918471168
IgnOnTimer_mS_M_u32	3330933248
IgnTimeOff_Sec_M_u32	96124674
ManVehSpd_Kph_M_f32	595.025391
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	60
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	190
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3694424576
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	193
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2808369664
PrevISDATBSI412MsgDLCError_Cnt_M_u08	57
PrevISDATBSI412MsgRxTime_MSec_M_u32	2357412352
PrevISDATBSI432MsgDLCError_Cnt_M_u08	192
PrevISDATBSI432MsgRxTime_MSec_M_u32	4235502080
PrevISDATDIRAMsgTxTime_MSec_M_u32	3614917120
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	156
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1248432640
PrevISDYNAASMsgDLCError_Cnt_M_u08	51
PrevISDYNAASMsgRxTime_MSec_M_u32	2169291264
PrevISDYNABRMsgDLCError_Cnt_M_u08	138
PrevISDYNABRMsgRxTime_MSec_M_u32	3217162752
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	206
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2460074496
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	25
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1201644032
PrevISDYNVOLMsgDLCError_Cnt_M_u08	65
PrevISDYNVOLMsgRxTime_MSec_M_u32	3417326080
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1814737408
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	120.852997
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	28792
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	23899
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	23537
VitesseVehicleBVRampValidCount_Cnt_M_u16	8596
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	10538
VitesseVehicleBVSigValidCount_Cnt_M_u16	49589
VitesseVehicleBV_Kph_M_f32	239.527695
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	34741
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	247

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	318.990112
k_AASNTCEnableTimeout_mS_u16	63689
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	53834
k_AASNodeTimeout_mS_u16	24667
k_ABSNodeTimeout_mS_u16	54337
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	56343
k_ANGLEVOLANTSigValidThresh_Cnt_u16	31645
k_AngleVolantInvalidThresh_Cnt_u16	51820
k_AngleVolantValidThresh_Cnt_u16	11920
k_BSI552MsgTimeout_mS_u16	14470
k_BSINTCEnableTimeout_mS_u16	2156
k_BSINodeAbsentDiag_Cnt_str.Threshold	50637
k_BSINodeAbsentDiag_Cnt_str.PStep	48099
k_BSINodeAbsentDiag_Cnt_str.NStep	35564
k_BSINodeAbsentTimeout_mS_u16	25418
k_BSINodeTimeout_mS_u16	37280
k_BattOvHi_Volt_f32	31.5
k_BattOvLo_Volt_f32	18.4519005
k_BattUvHi_Volt_f32	7.23759985
k_BattUvLo_Volt_f32	3.12680006
k_CAVNTCEnableTimeout_mS_u16	23766
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	10509
k_CAVNodeTimeout_mS_u16	5665
k_CMM388MsgTimeout_mS_u16	17461
k_CMM388NTCEnableTimeout_mS_u16	81
k_CMMNTCEnableTimeout_mS_u16	44639
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	37651
k_CONSANGLECPKMax_HwDeg_f32	323.4328
k_CONSANGLECPKMin_HwDeg_f32	-405.723602
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	19125
k_CONSANGLECPKSigValidThresh_Cnt_u16	1015
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	17073
k_CPKVehicleSpeedValidThresh_Cnt_u16	49888
k_CityParkInputInvalidThresh_Cnt_u16	33613
k_CityParkInputValidThresh_Cnt_u16	13451
k_ComputerRazGCTSigValidThresh_Cnt_u16	44253
k_CptTemporelSigValidThresh_Cnt_u16	62299
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	2572
k_DMDFCTCPKSigValidThresh_Cnt_u16	15462
k_DMDFCTCPKValidCount_Cnt_u16	65535
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	15667
k_DMDRELAXECPKSigValidThresh_Cnt_u16	9382
k_DMDRelaxeConsistentThresh_Cnt_u16	53500
k_DateValidThresh_Cnt_u16	17461
k_DefaultVehSpd_Kph_f32	157.100906
k_DiagMuxOnAbsentTimeout_mS_u16	37904
k_EMNodeTimeout_mS_u16	45122
k_ESPNTCEnableTimeout_mS_u16	58907
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	45531
k_EtatMTSigInvalidThresh_Cnt_u16	55590
k_EtatMTSigValidThresh_Cnt_u16	35192
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	28860
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	1618
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	20996
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	59172
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	9442
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	40345
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	30385
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	46519
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	52248
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	56462

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	14557
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	53863
k_ISDATDIRASentDiag_Cnt_str.Threshold	31074
k_ISDATDIRASentDiag_Cnt_str.PStep	34522
k_ISDATDIRASentDiag_Cnt_str.NStep	11395
k_ISDATDIRASentTimeout_mS_u16	60819
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	42812
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	34834
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	58567
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	1911
k_ISDYNAASChkSumValidThresh_Cnt_u16	33417
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	30510
k_ISDYNAASMsgCountValidThresh_Cnt_u16	62296
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	40539
k_ISDYNAASMsgLenValidThresh_Cnt_u16	9791
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	63589
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	7706
k_ISDYNABRChkSumValidThresh_Cnt_u16	57076
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	1592
k_ISDYNABRMsgCountValidThresh_Cnt_u16	60739
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46416
k_ISDYNABRMsgLenValidThresh_Cnt_u16	64918
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	19026
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	54876
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	59758
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	48874
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	48945
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	40700
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	3528
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	49176
k_ISDYNVOLChkSumValidThresh_Cnt_u16	14470
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	36979
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	15469
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	25477
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	1340
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	43771
k_IgnOnTimeout_mS_u16	23860
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	204.232193
k_PowerCutVehSpdLowThresh_Kph_f32	224.177505
k_PowerCutVehSpdLowTimeout_mS_u16	37845
k_VBattMaxAAS_Volt_f32	20.0249004
k_VBattMaxBSI_Volt_f32	22.3908997
k_VBattMaxCAV_Volt_f32	25.8502007
k_VBattMaxCMM388_Volt_f32	4.21950006
k_VBattMaxCMM_Volt_f32	14.7424002
k_VBattMaxESP_Volt_f32	27.7462006
k_VBattMinAAS_Volt_f32	19.7038994
k_VBattMinBSI_Volt_f32	27.7462006
k_VBattMinCAV_Volt_f32	29.1567001
k_VBattMinCMM388_Volt_f32	17.6732998
k_VBattMinCMM_Volt_f32	25.4347992
k_VBattMinESP_Volt_f32	14.7424002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	36838
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	37509
k_VitesseVehicleBVRampValidThresh_Cnt_u16	36538
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	5037
k_VitesseVehicleBVSigValidThresh_Cnt_u16	55612
k_VitesseVehicleBVSpeedPassThresh_kph_f32	167.438202
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	15359
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	36898
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2255872512
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	31061
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2996883200
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	25
target_SrlComInput_Per1_Batt_Volt_f32.value	26.8869991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2446774784
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	189
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.445275068
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4018405888
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2593333760
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	87
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2238857728
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	213
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	941711872
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	983597568
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	252
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	351248896
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1326367232
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	50
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	68
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	132
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	188
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	198
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	16409088
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	35
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	76
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	90
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	140
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	142
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	170
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4040098304
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	28
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1197351424
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2646426112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	104
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	167
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	170
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	879120896
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3341
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.774512887
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	584342
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	203.020493
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	45730

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2996883200	2996883200	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2996883200	2996883200	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	34836	34836	✔
AngleVolantMsgTimer_mS_M_u32	2996883200	2996883200	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2996883200	2996883200	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2996883200	2996883200	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2996883200	2996883200	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2996883200	2996883200	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	50637	50637	✔
BSINodeAbsentTimer_mS_M_u32	2996883200	2996883200	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2996883200	2996883200	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2996883200	2996883200	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2996883200	2996883200	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2996883200	2996883200	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2996883200	2996883200	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	58442	58442	✔
CONSANGLECPK_HwDeg_M_f32	-243.918198	-243.918198 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	58442	58442	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2471342592	2471342592	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	2665	2665	✔
CityParkInputConsistentCount_Cnt_M_u16	13451	13451	✔
CityParkInputInvalidCount_Cnt_M_u16	11922	11922	✔
CityParkInputMsgTimer_mS_M_u32	2996883200	2996883200	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2996883200	2996883200	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2996883200	2996883200	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2996883200	2996883200	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2996883200	2996883200	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2996883200	2996883200	✔
ESPNTCEnableTimer_mS_M_u32	2996883200	2996883200	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2996883200	2996883200	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	23456	23456	✔
EffacDefaultDiagTimer_mS_M_u32[1]	56577	56577	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2996883200	2996883200	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	658	658	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2996883200	2996883200	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2996883200	2996883200	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2996883200	2996883200	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2996883200	2996883200	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2996883200	2996883200	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2996883200	2996883200	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2996883200	2996883200	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2996883200	2996883200	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2996883200	2996883200	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2996883200	2996883200	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2996883200	2996883200	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2996883200	2996883200	✔
IgnOnTimer_mS_M_u32	2996883200	2996883200	✔
IgnTimeOff_Sec_M_u32	96124674	96124674	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	223	223	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4018405888	4018405888	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	221	221	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2593333760	2593333760	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	87	87	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2238857728	2238857728	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	213	213	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	941711872	941711872	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3614917120	3614917120	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	252	252	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	351248896	351248896	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	181	181	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1326367232	1326367232	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	190	190	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	16409088	16409088	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	210	210	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4040098304	4040098304	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	28	28	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1197351424	1197351424	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2646426112	2646426112	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	879120896	879120896	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	120.852997	120.852997	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	239.527695	239.527695	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	318.990112	318.990112	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	58442	58442	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	96124674	96124674	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-243.918198	-243.918198 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.443 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1706732800
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	19271
AASNodeAbsentTimer_mS_M_u32	4140293376
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	27729
ANGLEVOLANTSigValidCount_Cnt_M_u16	690
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	27312
AngleVolantMsgTimer_mS_M_u32	1706732800
AngleVolantValidCount_Cnt_M_u16	27504
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2133892352
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3661962496
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3975073024
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	501910784
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	29500
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1675971840
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	54887
CAVNodeAbsentTimer_mS_M_u32	1874853120
CDD_SrlComVehSpd_Kph_G_f32	138.731995
CMM388NTCEnableTimer_mS_M_u32	255016192
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3216899328
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	35125
CMMNodeAbsentTimer_mS_M_u32	3664547072
CONSANGLECPKSigInvalidCount_Cnt_M_u16	57046
CONSANGLECPKSigValidCount_Cnt_M_u16	4935
CONSANGLECPK_Cnt_M_u16	21702
CONSANGLECPK_HwDeg_M_f32	2.95900011
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21702
CPKVehicleSpeedMsgTimer_mS_M_u32	2533207296
CPKVehicleSpeedValidCount_Cnt_M_u16	56785
CityParkInputConsistentCount_Cnt_M_u16	12740

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	59573
CityParkInputMsgTimer_mS_M_u32	4018405888
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1377557760
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	20379
ComputerRazGCTSigInvalidTimer_mS_M_u32	1916697856
ComputerRazGCTSigValidCount_Cnt_M_u16	42757
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	36449
DMDFCTCPKSigValidCount_Cnt_M_u16	25481
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	51835
DMDRELAXECPKSigValidCount_Cnt_M_u16	35932
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	21311
DateInvalidTimer_mS_M_u32	3661962496
DiagMuxOnAbsentTimer_mS_M_u32	521497856
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	501910784
ESPNTCEnableTimer_mS_M_u32	776264960
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	54817
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	11
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	54
ElecIntTimer_mS_M_u32[1]	68
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1928285440
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	16617
EtatMTSigValidCount_Cnt_M_u16	22662
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	15104
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	6897
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	1415
ISDAT4V2BSI552MsgTimer_mS_M_u32	3435171072
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1841
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	61174
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	22662
ISDATBSI3F2MsgTimer_mS_M_u32	2062249216
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	2950
ISDATBSI412MsgLenValidCount_Cnt_M_u16	42171
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	16617
ISDATBSI412MsgTimer_mS_M_u32	798010624
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	21129
ISDATBSI432MsgLenValidCount_Cnt_M_u16	46709
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	20612
ISDATDIRASentFltAcc_Cnt_M_u16	44200
ISDATDIRASentTimer_mS_M_u32	2533207296
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	1308
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	27504
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	2252
ISDYN2CMMMsgTimer_mS_M_u32	3309755648
ISDYNAASChkSumInvalidCount_Cnt_M_u16	34161
ISDYNAASChkSumValidCount_Cnt_M_u16	23665
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	21467
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	64294
ISDYNAASMsgLenValidCount_Cnt_M_u16	62910
ISDYNAASMsgTimeValidCount_Cnt_M_u16	34161
ISDYNAASMsgTimer_mS_M_u32	635387136
ISDYNABRChkSumInvalidCount_Cnt_M_u16	24833
ISDYNABRChkSumValidCount_Cnt_M_u16	17802
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	54876
ISDYNABRMsgCountValidCount_Cnt_M_u16	6044
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	26305
ISDYNABRMsgLenValidCount_Cnt_M_u16	17778
ISDYNABRMsgTimeValidCount_Cnt_M_u16	21702
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	15832

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	31413
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	22662
ISDYNCMM208MsgTimer_mS_M_u32	129080576
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	15832
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	31413
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	24646
ISDYNCMM388MsgTimer_mS_M_u32	1899281664
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	4780
ISDYNVOLChkSumValidCount_Cnt_M_u16	39837
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	14647
ISDYNVOLMsgCountValidCount_Cnt_M_u16	41695
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	38966
ISDYNVOLMsgLenValidCount_Cnt_M_u16	27655
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	35125
ISDYNVOLMsgTimer_mS_M_u32	2229959936
IgnOnTimer_mS_M_u32	310951168
IgnTimeOff_Sec_M_u32	1819307768
ManVehSpd_Kph_M_f32	473.403595
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	58
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	128
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3343478016
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	13
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2100940032
PrevISDATBSI412MsgDLCError_Cnt_M_u08	82
PrevISDATBSI412MsgRxTime_MSec_M_u32	899480832
PrevISDATBSI432MsgDLCError_Cnt_M_u08	172
PrevISDATBSI432MsgRxTime_MSec_M_u32	3813203200
PrevISDATDIRAMsgTxTime_MSec_M_u32	616627456
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	226
PrevISDYN2CMMMsgRxTime_MSec_M_u32	959057152
PrevISDYNAASMsgDLCError_Cnt_M_u08	202
PrevISDYNAASMsgRxTime_MSec_M_u32	1564507392
PrevISDYNABRMsgDLCError_Cnt_M_u08	239
PrevISDYNABRMsgRxTime_MSec_M_u32	115391744
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	195
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3175185664
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	233
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1841814784
PrevISDYNVOLMsgDLCError_Cnt_M_u08	213
PrevISDYNVOLMsgRxTime_MSec_M_u32	1813380352
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3227954432
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	527.477478
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	5116
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	8980
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	30097
VitesseVehicleBVRampValidCount_Cnt_M_u16	64105
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	35174
VitesseVehicleBVSigValidCount_Cnt_M_u16	13703

Name	Input Value
VitesseVehicleBV_Kph_M_f32	394.506409
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	24646
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	19007
VitesseVehiculeRoues_Kph_M_f32	447.113708
k_AASNTCEnableTimeout_mS_u16	54089
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	5255
k_AASNodeTimeout_mS_u16	6676
k_ABSNodeTimeout_mS_u16	64418
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	59360
k_ANGLEVOLANTSigValidThresh_Cnt_u16	28428
k_AngleVolantInvalidThresh_Cnt_u16	32415
k_AngleVolantValidThresh_Cnt_u16	59573
k_BSI552MsgTimeout_mS_u16	40850
k_BSINTCEnableTimeout_mS_u16	63201
k_BSINodeAbsentDiag_Cnt_str.Threshold	11069
k_BSINodeAbsentDiag_Cnt_str.PStep	21309
k_BSINodeAbsentDiag_Cnt_str.NStep	49248
k_BSINodeAbsentTimeout_mS_u16	47368
k_BSINodeTimeout_mS_u16	20612
k_BattOvHi_Volt_f32	30.2844009
k_BattOvLo_Volt_f32	29.3094006
k_BattUvHi_Volt_f32	29.1509991
k_BattUvLo_Volt_f32	1.58870006
k_CAVNTCEnableTimeout_mS_u16	62947
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	32317
k_CAVNodeTimeout_mS_u16	3458
k_CMM388MsgTimeout_mS_u16	33351
k_CMM388NTCEnableTimeout_mS_u16	48627
k_CMMNTCEnableTimeout_mS_u16	38793
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	1003
k_CONSANGLECPKMax_HwDeg_f32	39.2094002
k_CONSANGLECPKMin_HwDeg_f32	-143.591995
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	5958
k_CONSANGLECPKSigValidThresh_Cnt_u16	16703
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	19218
k_CPKVehicleSpeedValidThresh_Cnt_u16	61189
k_CityParkInputInvalidThresh_Cnt_u16	31871
k_CityParkInputValidThresh_Cnt_u16	12740
k_ComputerRazGCTSigValidThresh_Cnt_u16	5135
k_CptTemporelSigValidThresh_Cnt_u16	34388
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	40385
k_DMDFCTCPKSigValidThresh_Cnt_u16	48242
k_DMDFCTCPKValidCount_Cnt_u16	3145
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	2252
k_DMDRELAXECPKSigValidThresh_Cnt_u16	26676
k_DMDRelaxeConsistentThresh_Cnt_u16	15154
k_DateValidThresh_Cnt_u16	1415
k_DefaultVehSpd_Kph_f32	82.0988007
k_DiagMuxOnAbsentTimeout_mS_u16	56692
k_EMNodeTimeout_mS_u16	799
k_ESPNTCEnableTimeout_mS_u16	65299
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	51091
k_EtatMTSigInvalidThresh_Cnt_u16	7924
k_EtatMTSigValidThresh_Cnt_u16	41917
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	44273
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	37358
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	64857
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	16698
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	52671
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	33498
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	18

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	43198
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	23517
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	31738
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	60622
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	60783
k_ISDATDIRASentDiag_Cnt_str.Threshold	16910
k_ISDATDIRASentDiag_Cnt_str.PStep	7039
k_ISDATDIRASentDiag_Cnt_str.NStep	21916
k_ISDATDIRASentTimeout_mS_u16	54701
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	752
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	27312
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	45839
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	6145
k_ISDYNAASChkSumValidThresh_Cnt_u16	15498
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	3420
k_ISDYNAASMsgCountValidThresh_Cnt_u16	36508
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	58197
k_ISDYNAASMsgLenValidThresh_Cnt_u16	22632
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	6324
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	6551
k_ISDYNABRChkSumValidThresh_Cnt_u16	36040
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	43580
k_ISDYNABRMsgCountValidThresh_Cnt_u16	27357
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	32821
k_ISDYNABRMsgLenValidThresh_Cnt_u16	3361
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	20400
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	29264
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	13147
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	64103
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	41809
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	31154
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	11021
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	55133
k_ISDYNVOLChkSumValidThresh_Cnt_u16	29650
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	2186
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	40670
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	55957
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	6962
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	26933
k_IgnOnTimeout_mS_u16	28681
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	211.204803
k_PowerCutVehSpdLowThresh_Kph_f32	223.368896
k_PowerCutVehSpdLowTimeout_mS_u16	12837
k_VBattMaxAAS_Volt_f32	14.6135998
k_VBattMaxBSI_Volt_f32	14.0256004
k_VBattMaxCAV_Volt_f32	25.8516006
k_VBattMaxCMM388_Volt_f32	10.6287003
k_VBattMaxCMM_Volt_f32	18.7306995
k_VBattMaxESP_Volt_f32	0.183300003
k_VBattMinAAS_Volt_f32	26.6305008
k_VBattMinBSI_Volt_f32	0.183300003
k_VBattMinCAV_Volt_f32	12.5483999
k_VBattMinCMM388_Volt_f32	28.7584991
k_VBattMinCMM_Volt_f32	22.4573002
k_VBattMinESP_Volt_f32	18.7306995
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	28914
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	11991
k_VitesseVehicleBVRampValidThresh_Cnt_u16	61495
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	4765
k_VitesseVehicleBVSigValidThresh_Cnt_u16	18353
k_VitesseVehicleBVSpeedPassThresh_kph_f32	311.447998
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	36199
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	26303
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3661962496
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	40019
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	4122498560
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	233
target_SrlComInput_Per1_Batt_Volt_f32.value	1.88919997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2816625920
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	31
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.499092668
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4288331008
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2733464832
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3335519488
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	1
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3544358144
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	809843968
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	85
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1171774720
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2080013568
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	45
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	134
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	183
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	190
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	232
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	481795328
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	37
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	130
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	194
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	236
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3887709440
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	78
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2290900224
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1777270016
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	66
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	82
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	151
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1580453120
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2825
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.112476803
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	116924
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	2.08979988

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	30078		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	4122498560	4122498560	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4122498560	4122498560	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	4122498560	4122498560	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4122498560	4122498560	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4122498560	4122498560	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4122498560	4122498560	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4122498560	4122498560	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	11069	11069	✔
BSINodeAbsentTimer_mS_M_u32	4122498560	4122498560	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4122498560	4122498560	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4122498560	4122498560	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4122498560	4122498560	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4122498560	4122498560	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4122498560	4122498560	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	21702	21702	✔
CONSANGLECPK_HwDeg_M_f32	2.95900011	2.95900011 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4122498560	4122498560	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	4122498560	4122498560	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4122498560	4122498560	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4122498560	4122498560	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4122498560	4122498560	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4122498560	4122498560	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4122498560	4122498560	✔
ESPNTCEnableTimer_mS_M_u32	4122498560	4122498560	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4122498560	4122498560	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	4122498560	4122498560	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	11	11	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	4122498560	4122498560	✔
ElecIntTimer_mS_M_u32[1]	68	68	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	4122498560	4122498560	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4122498560	4122498560	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4122498560	4122498560	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4122498560	4122498560	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4122498560	4122498560	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	4122498560	4122498560	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4122498560	4122498560	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4122498560	4122498560	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4122498560	4122498560	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4122498560	4122498560	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4122498560	4122498560	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4122498560	4122498560	✔
IgnOnTimer_mS_M_u32	310951168	310951168	✔
IgnTimeOff_Sec_M_u32	1819307768	1819307768	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	21	21	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4288331008	4288331008	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	31	31	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2733464832	2733464832	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	246	246	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3335519488	3335519488	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	1	1	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3544358144	3544358144	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	616627456	616627456	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	85	85	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1171774720	1171774720	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	110	110	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2080013568	2080013568	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	232	232	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	481795328	481795328	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	39	39	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3887709440	3887709440	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	78	78	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2290900224	2290900224	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	2	2	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1777270016	1777270016	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1580453120	1580453120	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	527.477478	527.477478	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	394.506409	394.506409	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	447.113708	447.113708	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	21702	21702	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1819307768	1819307768	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	2.95900011	2.95900011 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.444 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3767908096
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	35158
AASNodeAbsentTimer_mS_M_u32	3035260672
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	40004
ANGLEVOLANTSigValidCount_Cnt_M_u16	5560
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	58279
AngleVolantMsgTimer_mS_M_u32	3767908096
AngleVolantValidCount_Cnt_M_u16	55184
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1687234304
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	337225472
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2008995584
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	443586304
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	42855
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2876856064
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	8011
CAVNodeAbsentTimer_mS_M_u32	511149824
CDD_SrlComVehSpd_Kph_G_f32	370.553589
CMM388NTCEnableTimer_mS_M_u32	1192019712
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	287672064
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	44638
CMMNodeAbsentTimer_mS_M_u32	1749194496
CONSANGLECPKSigInvalidCount_Cnt_M_u16	57447
CONSANGLECPKSigValidCount_Cnt_M_u16	37483
CONSANGLECPK_Cnt_M_u16	57666
CONSANGLECPK_HwDeg_M_f32	-228.905807
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	57666
CPKVehicleSpeedMsgTimer_mS_M_u32	2949691136
CPKVehicleSpeedValidCount_Cnt_M_u16	58700
CityParkInputConsistentCount_Cnt_M_u16	56580
CityParkInputInvalidCount_Cnt_M_u16	48415
CityParkInputMsgTimer_mS_M_u32	2659505152
CityParkInputValidCount_Cnt_M_u16	2

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	392062720
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	31946
ComputerRazGCTSigInvalidTimer_mS_M_u32	3740927744
ComputerRazGCTSigValidCount_Cnt_M_u16	45805
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	939
DMDFCTCPKSigValidCount_Cnt_M_u16	57127
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	53758
DMDRELAXECPKSigValidCount_Cnt_M_u16	754
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	22456
DateInvalidTimer_mS_M_u32	337225472
DiagMuxOnAbsentTimer_mS_M_u32	3690886912
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	443586304
ESPNTCEnableTimer_mS_M_u32	2356111104
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	53822
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	21
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	10
ElecIntTimer_mS_M_u32[1]	104
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3843249920
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	18397
EtatMTSigValidCount_Cnt_M_u16	55789
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	50209
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	44453
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	62421
ISDAT4V2BSI552MsgTimer_mS_M_u32	2042009344
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	8079
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	19464
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	55789
ISDATBSI3F2MsgTimer_mS_M_u32	1883535104
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	64855
ISDATBSI412MsgLenValidCount_Cnt_M_u16	27839
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	18397
ISDATBSI412MsgTimer_mS_M_u32	316389120
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	44754
ISDATBSI432MsgLenValidCount_Cnt_M_u16	434
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	45680
ISDATDIRASentFltAcc_Cnt_M_u16	65076
ISDATDIRASentTimer_mS_M_u32	2949691136
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	15880
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	55184
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	20046
ISDYN2CMMMsgTimer_mS_M_u32	415328000
ISDYNAASChkSumInvalidCount_Cnt_M_u16	64272
ISDYNAASChkSumValidCount_Cnt_M_u16	56868
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	49203
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	62306
ISDYNAASMsgLenValidCount_Cnt_M_u16	42446
ISDYNAASMsgTimeValidCount_Cnt_M_u16	64272
ISDYNAASMsgTimer_mS_M_u32	647546624
ISDYNABRChkSumInvalidCount_Cnt_M_u16	50847
ISDYNABRChkSumValidCount_Cnt_M_u16	2171
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	57395
ISDYNABRMsgCountValidCount_Cnt_M_u16	26503
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	5258
ISDYNABRMsgLenValidCount_Cnt_M_u16	43726
ISDYNABRMsgTimeValidCount_Cnt_M_u16	57666
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	5193
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	60531
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	55789
ISDYNCMM208MsgTimer_mS_M_u32	1874470656

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	5193
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	60531
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	27862
ISDYNCMM388MsgTimer_mS_M_u32	3741992704
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	3245
ISDYNVOLChkSumValidCount_Cnt_M_u16	34609
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	48881
ISDYNVOLMsgCountValidCount_Cnt_M_u16	41709
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	30747
ISDYNVOLMsgLenValidCount_Cnt_M_u16	41088
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	44638
ISDYNVOLMsgTimer_mS_M_u32	444991232
IgnOnTimer_mS_M_u32	2004764416
IgnTimeOff_Sec_M_u32	1106425529
ManVehSpd_Kph_M_f32	60.8180008
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	68
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	149
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1045591808
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	102
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1933694720
PrevISDATBSI412MsgDLCError_Cnt_M_u08	64
PrevISDATBSI412MsgRxTime_MSec_M_u32	861701888
PrevISDATBSI432MsgDLCError_Cnt_M_u08	225
PrevISDATBSI432MsgRxTime_MSec_M_u32	3289605888
PrevISDATDIRAMsgTxTime_MSec_M_u32	2317387520
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	42
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2690389760
PrevISDYNAASMsgDLCError_Cnt_M_u08	27
PrevISDYNAASMsgRxTime_MSec_M_u32	3746301696
PrevISDYNABRMsgDLCError_Cnt_M_u08	57
PrevISDYNABRMsgRxTime_MSec_M_u32	2509653760
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	78
PrevISDYNCMM208MsgRxTime_MSec_M_u32	771032832
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	162
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1139435264
PrevISDYNVOLMsgDLCError_Cnt_M_u08	197
PrevISDYNVOLMsgRxTime_MSec_M_u32	2805827328
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2753672960
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	247.374603
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	19624
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	34708
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	15877
VitesseVehicleBVRampValidCount_Cnt_M_u16	46257
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	21793
VitesseVehicleBVSigValidCount_Cnt_M_u16	43605
VitesseVehicleBV_Kph_M_f32	456.173889
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	27862
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	26019

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	589.411621
k_AASNTCEnableTimeout_mS_u16	12221
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	55743
k_AASNodeTimeout_mS_u16	38548
k_ABSNodeTimeout_mS_u16	37268
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	10049
k_ANGLEVOLANTSigValidThresh_Cnt_u16	16225
k_AngleVolantInvalidThresh_Cnt_u16	12652
k_AngleVolantValidThresh_Cnt_u16	48415
k_BSI552MsgTimeout_mS_u16	58222
k_BSINTCEnableTimeout_mS_u16	64746
k_BSINodeAbsentDiag_Cnt_str.Threshold	6553
k_BSINodeAbsentDiag_Cnt_str.PStep	33499
k_BSINodeAbsentDiag_Cnt_str.NStep	44209
k_BSINodeAbsentTimeout_mS_u16	27583
k_BSINodeTimeout_mS_u16	45680
k_BattOvHi_Volt_f32	15.0825005
k_BattOvLo_Volt_f32	20.5690002
k_BattUvHi_Volt_f32	8.48670006
k_BattUvLo_Volt_f32	27.8591003
k_CAVNTCEnableTimeout_mS_u16	13437
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	57233
k_CAVNodeTimeout_mS_u16	38899
k_CMM388MsgTimeout_mS_u16	55382
k_CMM388NTCEnableTimeout_mS_u16	9442
k_CMMNTCEnableTimeout_mS_u16	14759
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	57391
k_CONSANGLECPKMax_HwDeg_f32	773.006226
k_CONSANGLECPKMin_HwDeg_f32	-257.679993
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	15318
k_CONSANGLECPKSigValidThresh_Cnt_u16	29859
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	4674
k_CPKVehicleSpeedValidThresh_Cnt_u16	15918
k_CityParkInputInvalidThresh_Cnt_u16	4301
k_CityParkInputValidThresh_Cnt_u16	56580
k_ComputerRazGCTSigValidThresh_Cnt_u16	541
k_CptTemporelSigValidThresh_Cnt_u16	40214
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	25482
k_DMDFCTCPKSigValidThresh_Cnt_u16	14798
k_DMDFCTCPKValidCount_Cnt_u16	48719
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	20046
k_DMDRELAXECPKSigValidThresh_Cnt_u16	60938
k_DMDRelaxeConsistentThresh_Cnt_u16	23480
k_DateValidThresh_Cnt_u16	62421
k_DefaultVehSpd_Kph_f32	67.8021011
k_DiagMuxOnAbsentTimeout_mS_u16	57376
k_EMNodeTimeout_mS_u16	45720
k_ESPNTCEnableTimeout_mS_u16	57559
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	14871
k_EtatMTSigInvalidThresh_Cnt_u16	5642
k_EtatMTSigValidThresh_Cnt_u16	41510
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	121
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	26345
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	51297
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	52608
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	15545
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	56267
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	40003
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	53731
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	61254
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	6806

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	41630
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	47570
k_ISDATDIRASentDiag_Cnt_str.Threshold	12314
k_ISDATDIRASentDiag_Cnt_str.PStep	25984
k_ISDATDIRASentDiag_Cnt_str.NStep	21340
k_ISDATDIRASentTimeout_mS_u16	46123
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	55803
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58279
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	64051
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	38303
k_ISDYNAASChkSumValidThresh_Cnt_u16	6011
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	12083
k_ISDYNAASMsgCountValidThresh_Cnt_u16	63111
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	59411
k_ISDYNAASMsgLenValidThresh_Cnt_u16	54280
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	28489
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	6096
k_ISDYNABRChkSumValidThresh_Cnt_u16	46740
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	63079
k_ISDYNABRMsgCountValidThresh_Cnt_u16	54299
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	48478
k_ISDYNABRMsgLenValidThresh_Cnt_u16	8510
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	3430
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	43548
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	20212
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	55135
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	60228
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	42168
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	22839
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	28742
k_ISDYNVOLChkSumValidThresh_Cnt_u16	34030
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	46991
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	6383
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	41577
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	17785
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	34227
k_IgnOnTimeout_mS_u16	8658
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	150.458801
k_PowerCutVehSpdLowThresh_Kph_f32	170.185394
k_PowerCutVehSpdLowTimeout_mS_u16	22265
k_VBattMaxAAS_Volt_f32	2.9677999
k_VBattMaxBSI_Volt_f32	6.41860008
k_VBattMaxCAV_Volt_f32	13.5962
k_VBattMaxCMM388_Volt_f32	4.31349993
k_VBattMaxCMM_Volt_f32	9.29740047
k_VBattMaxESP_Volt_f32	6.31820011
k_VBattMinAAS_Volt_f32	21.2786007
k_VBattMinBSI_Volt_f32	6.31820011
k_VBattMinCAV_Volt_f32	29.4195995
k_VBattMinCMM388_Volt_f32	13.1236
k_VBattMinCMM_Volt_f32	0.175400004
k_VBattMinESP_Volt_f32	9.29740047
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	21837
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	40165
k_VitesseVehicleBVRampValidThresh_Cnt_u16	36337
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	5681
k_VitesseVehicleBVSigValidThresh_Cnt_u16	44153
k_VitesseVehicleBVSpeedPassThresh_kph_f32	289.29541
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	61003
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	11639
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	337225472
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	51805
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1128655616
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	162
target_SrlComInput_Per1_Batt_Volt_f32.value	24.9722004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3279836928
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	226
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0367360711
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	94
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3026208512
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3064719104
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2013759232
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2691901184
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3622749952
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3329910528
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	336987904
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	48
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	83
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	90
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	136
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	228
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	233
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3836749568
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	77
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	79
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	150
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	169
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	192
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3268888320
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	513992448
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4185818880
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	58
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	85
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	105
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	119
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	196
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1682691840
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3253
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0675172061
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	836617
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	155.900497
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	34682

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1128655616	1128655616	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1128655616	1128655616	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	58279	58279	✔
AngleVolantMsgTimer_mS_M_u32	1128655616	1128655616	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	6553	6553	✔
BSINodeAbsentTimer_mS_M_u32	1128655616	1128655616	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1128655616	1128655616	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1128655616	1128655616	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	57666	57666	✔
CONSANGLECPK_HwDeg_M_f32	-228.905807	-228.905807 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	57666	57666	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2949691136	2949691136	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	58700	58700	✔
CityParkInputConsistentCount_Cnt_M_u16	56580	56580	✔
CityParkInputInvalidCount_Cnt_M_u16	48415	48415	✔
CityParkInputMsgTimer_mS_M_u32	1128655616	1128655616	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1128655616	1128655616	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1128655616	1128655616	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1128655616	1128655616	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1128655616	1128655616	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1128655616	1128655616	✔
ESPNTCEnableTimer_mS_M_u32	1128655616	1128655616	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1128655616	1128655616	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔
EffacDefaultDiagTimer_mS_M_u32[1]	21	21	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	10	10	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	104	104	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1128655616	1128655616	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1128655616	1128655616	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1128655616	1128655616	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1128655616	1128655616	✔
IgnOnTimer_mS_M_u32	1128655616	1128655616	✔
IgnTimeOff_Sec_M_u32	1106425529	1106425529	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	94	94	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3026208512	3026208512	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	64	64	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3064719104	3064719104	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	12	12	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2013759232	2013759232	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	108	108	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2691901184	2691901184	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2317387520	2317387520	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	133	133	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3329910528	3329910528	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	142	142	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	336987904	336987904	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	84	84	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3836749568	3836749568	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3268888320	3268888320	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	131	131	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	513992448	513992448	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	137	137	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4185818880	4185818880	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1682691840	1682691840	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	247.374603	247.374603	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	456.173889	456.173889	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	589.411621	589.411621	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	57666	57666	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1106425529	1106425529	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-228.905807	-228.905807 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.445 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3245972992
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	26936
AASNodeAbsentTimer_mS_M_u32	3007024640
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	2668
ANGLEVOLANTSigValidCount_Cnt_M_u16	60112
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	56901
AngleVolantMsgTimer_mS_M_u32	3245972992
AngleVolantValidCount_Cnt_M_u16	12552
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2940685824
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1655557632
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2289974784
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2540240384
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	13571
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4149132800
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	25560
CAVNodeAbsentTimer_mS_M_u32	2467573248
CDD_SrlComVehSpd_Kph_G_f32	79.1849976
CMM388NTCEnableTimer_mS_M_u32	4266946048
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4077530624
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	36958
CMMNodeAbsentTimer_mS_M_u32	1978859008
CONSANGLECPKSigInvalidCount_Cnt_M_u16	14596
CONSANGLECPKSigValidCount_Cnt_M_u16	44983
CONSANGLECPK_Cnt_M_u16	57138
CONSANGLECPK_HwDeg_M_f32	-655.940613
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	57138
CPKVehicleSpeedMsgTimer_mS_M_u32	4291337728
CPKVehicleSpeedValidCount_Cnt_M_u16	31773
CityParkInputConsistentCount_Cnt_M_u16	61612

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	35165
CityParkInputMsgTimer_mS_M_u32	3026208512
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1541377536
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	24284
ComputerRazGCTSigInvalidTimer_mS_M_u32	2072817152
ComputerRazGCTSigValidCount_Cnt_M_u16	21233
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	58809
DMDFCTCPKSigValidCount_Cnt_M_u16	49156
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	53566
DMDRELAXECPKSigValidCount_Cnt_M_u16	35618
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	22289
DateInvalidTimer_mS_M_u32	1655557632
DiagMuxOnAbsentTimer_mS_M_u32	1648320000
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2540240384
ESPNTCEnableTimer_mS_M_u32	2158792192
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	8573
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	23456
EffacDefaultDiagTimer_mS_M_u32[1]	56577
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	65
ElecIntTimer_mS_M_u32[1]	658
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	847298048
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	36067
EtatMTSigValidCount_Cnt_M_u16	37747
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	62934
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	50697
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	47610
ISDAT4V2BSI552MsgTimer_mS_M_u32	295108096
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	59723
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	49314
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	37747
ISDATBSI3F2MsgTimer_mS_M_u32	1030577664
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	31989
ISDATBSI412MsgLenValidCount_Cnt_M_u16	19324
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	36067
ISDATBSI412MsgTimer_mS_M_u32	3265764864
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	24322
ISDATBSI432MsgLenValidCount_Cnt_M_u16	25377
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	32361
ISDATDIRASentFltAcc_Cnt_M_u16	43805
ISDATDIRASentTimer_mS_M_u32	4291337728
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	24800
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	12552
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	20944
ISDYN2CMMMsgTimer_mS_M_u32	2746650112
ISDYNAASChkSumInvalidCount_Cnt_M_u16	31754
ISDYNAASChkSumValidCount_Cnt_M_u16	40845
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	49951
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	915
ISDYNAASMsgLenValidCount_Cnt_M_u16	6415
ISDYNAASMsgTimeValidCount_Cnt_M_u16	31754
ISDYNAASMsgTimer_mS_M_u32	2410704384
ISDYNABRChkSumInvalidCount_Cnt_M_u16	3803
ISDYNABRChkSumValidCount_Cnt_M_u16	13831
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	6305
ISDYNABRMsgCountValidCount_Cnt_M_u16	20324
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	59547
ISDYNABRMsgLenValidCount_Cnt_M_u16	45710
ISDYNABRMsgTimeValidCount_Cnt_M_u16	57138
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	11204

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	52923
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	37747
ISDYNCMM208MsgTimer_mS_M_u32	1909214720
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	11204
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	52923
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	2358
ISDYNCMM388MsgTimer_mS_M_u32	207351296
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	19506
ISDYNVOLChkSumValidCount_Cnt_M_u16	26981
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	19431
ISDYNVOLMsgCountValidCount_Cnt_M_u16	3250
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	58342
ISDYNVOLMsgLenValidCount_Cnt_M_u16	30586
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	36958
ISDYNVOLMsgTimer_mS_M_u32	4175998464
IgnOnTimer_mS_M_u32	318762496
IgnTimeOff_Sec_M_u32	2375765715
ManVehSpd_Kph_M_f32	266.804504
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	69
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	97
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2336448000
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	225
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1643462144
PrevISDATBSI412MsgDLCError_Cnt_M_u08	184
PrevISDATBSI412MsgRxTime_MSec_M_u32	677719552
PrevISDATBSI432MsgDLCError_Cnt_M_u08	120
PrevISDATBSI432MsgRxTime_MSec_M_u32	1774226944
PrevISDATDIRAMsgTxTime_MSec_M_u32	874065408
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	143
PrevISDYN2CMMMsgRxTime_MSec_M_u32	329678336
PrevISDYNAASMsgDLCError_Cnt_M_u08	34
PrevISDYNAASMsgRxTime_MSec_M_u32	1117171200
PrevISDYNABRMsgDLCError_Cnt_M_u08	148
PrevISDYNABRMsgRxTime_MSec_M_u32	414707200
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	117
PrevISDYNCMM208MsgRxTime_MSec_M_u32	983281152
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	160
PrevISDYNCMM388MsgRxTime_MSec_M_u32	104566272
PrevISDYNVOLMsgDLCError_Cnt_M_u08	38
PrevISDYNVOLMsgRxTime_MSec_M_u32	2428644864
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2799017472
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	84.6582031
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	36801
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	3005
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	28586
VitesseVehicleBVRampValidCount_Cnt_M_u16	14438
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	37845
VitesseVehicleBVSigValidCount_Cnt_M_u16	57593

Name	Input Value
VitesseVehicleBV_Kph_M_f32	573.525574
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	2358
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	52113
VitesseVehiculeRoues_Kph_M_f32	316.105011
k_AASNTCEnableTimeout_mS_u16	40897
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	42619
k_AASNodeTimeout_mS_u16	57021
k_ABSNodeTimeout_mS_u16	8190
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	29109
k_ANGLEVOLANTSigValidThresh_Cnt_u16	9748
k_AngleVolantInvalidThresh_Cnt_u16	15347
k_AngleVolantValidThresh_Cnt_u16	35165
k_BSI552MsgTimeout_mS_u16	15920
k_BSINTCEnableTimeout_mS_u16	54458
k_BSINodeAbsentDiag_Cnt_str.Threshold	50637
k_BSINodeAbsentDiag_Cnt_str.PStep	48099
k_BSINodeAbsentDiag_Cnt_str.NStep	35564
k_BSINodeAbsentTimeout_mS_u16	42493
k_BSINodeTimeout_mS_u16	32361
k_BattOvHi_Volt_f32	22.7332993
k_BattOvLo_Volt_f32	19.6991005
k_BattUvHi_Volt_f32	16.9396
k_BattUvLo_Volt_f32	19.3474998
k_CAVNTCEnableTimeout_mS_u16	6979
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	47878
k_CAVNodeTimeout_mS_u16	16992
k_CMM388MsgTimeout_mS_u16	31800
k_CMM388NTCEnableTimeout_mS_u16	50836
k_CMMNTCEnableTimeout_mS_u16	64259
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	35821
k_CONSANGLECPKMax_HwDeg_f32	759.919983
k_CONSANGLECPKMin_HwDeg_f32	-205.373993
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	39990
k_CONSANGLECPKSigValidThresh_Cnt_u16	40593
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	41907
k_CPKVehicleSpeedValidThresh_Cnt_u16	54896
k_CityParkInputInvalidThresh_Cnt_u16	26705
k_CityParkInputValidThresh_Cnt_u16	61612
k_ComputerRazGCTSigValidThresh_Cnt_u16	63905
k_CptTemporelSigValidThresh_Cnt_u16	34168
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	64411
k_DMDFCTCPKSigValidThresh_Cnt_u16	1422
k_DMDFCTCPKValidCount_Cnt_u16	36939
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	20944
k_DMDRELAXECPKSigValidThresh_Cnt_u16	57179
k_DMDRelaxeConsistentThresh_Cnt_u16	52817
k_DateValidThresh_Cnt_u16	47610
k_DefaultVehSpd_Kph_f32	126.323196
k_DiagMuxOnAbsentTimeout_mS_u16	55960
k_EMNodeTimeout_mS_u16	50801
k_ESPNTCEnableTimeout_mS_u16	20276
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	7733
k_EtatMTSigInvalidThresh_Cnt_u16	35994
k_EtatMTSigValidThresh_Cnt_u16	54534
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	29966
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	32381
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	58005
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	58232
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	62095
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	45465
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	39599

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	63118
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	28070
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	33590
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	34782
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	17539
k_ISDATDIRASentDiag_Cnt_str.Threshold	53628
k_ISDATDIRASentDiag_Cnt_str.PStep	31362
k_ISDATDIRASentDiag_Cnt_str.NStep	51301
k_ISDATDIRASentTimeout_mS_u16	30263
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	51208
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	56901
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	29472
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	41435
k_ISDYNAASChkSumValidThresh_Cnt_u16	2311
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	11169
k_ISDYNAASMsgCountValidThresh_Cnt_u16	41572
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	31359
k_ISDYNAASMsgLenValidThresh_Cnt_u16	63073
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	13916
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	30409
k_ISDYNABRChkSumValidThresh_Cnt_u16	10044
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	18435
k_ISDYNABRMsgCountValidThresh_Cnt_u16	64423
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	25438
k_ISDYNABRMsgLenValidThresh_Cnt_u16	13437
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	15302
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	18277
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	15390
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	2140
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	7532
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	15824
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	5397
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	41000
k_ISDYNVOLChkSumValidThresh_Cnt_u16	32495
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	62858
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	54443
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	44351
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	32975
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	64608
k_IgnOnTimeout_mS_u16	48004
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	206.852997
k_PowerCutVehSpdLowThresh_Kph_f32	251.673294
k_PowerCutVehSpdLowTimeout_mS_u16	6669
k_VBattMaxAAS_Volt_f32	17.3586998
k_VBattMaxBSI_Volt_f32	6.55499983
k_VBattMaxCAV_Volt_f32	30.0426998
k_VBattMaxCMM388_Volt_f32	20.3146
k_VBattMaxCMM_Volt_f32	5.71740007
k_VBattMaxESP_Volt_f32	17.9745007
k_VBattMinAAS_Volt_f32	17.6947002
k_VBattMinBSI_Volt_f32	17.9745007
k_VBattMinCAV_Volt_f32	31.6536999
k_VBattMinCMM388_Volt_f32	22.3405991
k_VBattMinCMM_Volt_f32	14.1021004
k_VBattMinESP_Volt_f32	5.71740007
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	7698
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	9225
k_VitesseVehicleBVRampValidThresh_Cnt_u16	57063
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	48229
k_VitesseVehicleBVSigValidThresh_Cnt_u16	38477
k_VitesseVehicleBVSpeedPassThresh_kph_f32	233.866592
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	63192
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	26132
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1655557632
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	9514
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3409510912
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	160
target_SrlComInput_Per1_Batt_Volt_f32.value	1.17460001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	54509056
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	136
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.433358699
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1683615232
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2482441728
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3328454144
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	187
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	60902912
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1403940352
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3196816896
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1278782976
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	43
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	61
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	125
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	155
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	195
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1793740288
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	2
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	66
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	122
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	178
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3572821504
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4161932800
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3724488192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	94
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	97
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	124
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	164
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	920075776
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3881
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0572625101
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	444278
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	150.778

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	42827		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3409510912	3409510912	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3409510912	3409510912	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	50637	50637	✔
BSINodeAbsentTimer_mS_M_u32	3409510912	3409510912	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3409510912	3409510912	✔
CDD_SrlComVehSpd_Kph_G_f32	266.804504	266.804504	✔
CMM388NTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3409510912	3409510912	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	57138	57138	✔
CONSANGLECPK_HwDeg_M_f32	-655.940613	-655.940613 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3409510912	3409510912	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3409510912	3409510912	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3409510912	3409510912	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3409510912	3409510912	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3409510912	3409510912	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3409510912	3409510912	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3409510912	3409510912	✔
ESPNTCEnableTimer_mS_M_u32	3409510912	3409510912	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3409510912	3409510912	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	23456	23456	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	56577	56577	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	65	65	✔
ElecIntTimer_mS_M_u32[1]	658	658	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3409510912	3409510912	✔
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	47610	47610	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	37747	37747	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	36067	36067	✔
ISDATBSI412MsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	32361	32361	✔
ISDATBSI432MsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3409510912	3409510912	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	20944	20944	✔
ISDYN2CMMMsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	31754	31754	✔
ISDYNAASMsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	57138	57138	✔
ISDYNABRMsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	37747	37747	✔
ISDYNCMM208MsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	2358	2358	✔
ISDYNCMM388MsgTimer_mS_M_u32	3409510912	3409510912	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	36958	36958	✔
ISDYNVOLMsgTimer_mS_M_u32	3409510912	3409510912	✔
IgnOnTimer_mS_M_u32	318762496	318762496	✔
IgnTimeOff_Sec_M_u32	2375765715	2375765715	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	227	227	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1683615232	1683615232	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	84	84	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2482441728	2482441728	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	68	68	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3328454144	3328454144	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	187	187	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	60902912	60902912	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	874065408	874065408	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	93	93	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3196816896	3196816896	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	152	152	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1278782976	1278782976	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	55	55	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1793740288	1793740288	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3572821504	3572821504	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4161932800	4161932800	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	106	106	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3724488192	3724488192	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	920075776	920075776	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	84.6582031	84.6582031	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	573.525574	573.525574	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	316.105011	316.105011	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	57138	57138	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2375765715	2375765715	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-655.940613	-655.940613 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.446 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2637397248
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	34143
AASNodeAbsentTimer_mS_M_u32	2161945856
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	55946
ANGLEVOLANTSigValidCount_Cnt_M_u16	39143
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	60936
AngleVolantMsgTimer_mS_M_u32	2637397248
AngleVolantValidCount_Cnt_M_u16	44369
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	213216512
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	74050816
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3763313920
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1853578496
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	47413
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	979770624
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	64360
CAVNodeAbsentTimer_mS_M_u32	3267153152
CDD_SrlComVehSpd_Kph_G_f32	286.440704
CMM388NTCEnableTimer_mS_M_u32	432016640
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3829058816
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	16962
CMMNodeAbsentTimer_mS_M_u32	4185742592
CONSANGLECPKSigInvalidCount_Cnt_M_u16	23423
CONSANGLECPKSigValidCount_Cnt_M_u16	44011
CONSANGLECPK_Cnt_M_u16	46634
CONSANGLECPK_HwDeg_M_f32	24.6060009
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	46634
CPKVehicleSpeedMsgTimer_mS_M_u32	607550720
CPKVehicleSpeedValidCount_Cnt_M_u16	26121
CityParkInputConsistentCount_Cnt_M_u16	38053
CityParkInputInvalidCount_Cnt_M_u16	7525
CityParkInputMsgTimer_mS_M_u32	301273600
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1026600192
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	10931

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3260763392
ComputerRazGCTSigValidCount_Cnt_M_u16	12582
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	41489
DMDFCTCPKSigValidCount_Cnt_M_u16	18742
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	35124
DMDRELAXECPKSigValidCount_Cnt_M_u16	54033
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	22824
DateInvalidTimer_mS_M_u32	74050816
DiagMuxOnAbsentTimer_mS_M_u32	1417559296
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1853578496
ESPNTCEnableTimer_mS_M_u32	3533286656
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	60970
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	3
EffacDefaultDiagTimer_mS_M_u32[1]	6
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	7
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4059045120
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	39110
EtatMTSigValidCount_Cnt_M_u16	35678
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	34857
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	58389
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	15540
ISDAT4V2BSI552MsgTimer_mS_M_u32	215047424
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	9766
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	35558
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	35678
ISDATBSI3F2MsgTimer_mS_M_u32	3755228416
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	26763
ISDATBSI412MsgLenValidCount_Cnt_M_u16	60092
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	39110
ISDATBSI412MsgTimer_mS_M_u32	378109184
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	60566
ISDATBSI432MsgLenValidCount_Cnt_M_u16	28542
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	38853
ISDATDIRASentFltAcc_Cnt_M_u16	14569
ISDATDIRASentTimer_mS_M_u32	607550720
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	13824
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	44369
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	21564
ISDYN2CMMMsgTimer_mS_M_u32	1478208768
ISDYNAASChkSumInvalidCount_Cnt_M_u16	4105
ISDYNAASChkSumValidCount_Cnt_M_u16	38662
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	19836
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	30951
ISDYNAASMsgLenValidCount_Cnt_M_u16	45435
ISDYNAASMsgTimeValidCount_Cnt_M_u16	4105
ISDYNAASMsgTimer_mS_M_u32	1332481280
ISDYNABRChkSumInvalidCount_Cnt_M_u16	34898
ISDYNABRChkSumValidCount_Cnt_M_u16	46807
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	47284
ISDYNABRMsgCountValidCount_Cnt_M_u16	63985
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	64298
ISDYNABRMsgLenValidCount_Cnt_M_u16	17878
ISDYNABRMsgTimeValidCount_Cnt_M_u16	46634
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	19061
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	29261
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	35678
ISDYNCMM208MsgTimer_mS_M_u32	1282829568
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	19061
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	29261
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	4519

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	513903872
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	48853
ISDYNVOLChkSumValidCount_Cnt_M_u16	961
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	15463
ISDYNVOLMsgCountValidCount_Cnt_M_u16	6156
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	6271
ISDYNVOLMsgLenValidCount_Cnt_M_u16	32844
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	16962
ISDYNVOLMsgTimer_mS_M_u32	4094119168
IgnOnTimer_mS_M_u32	2700446976
IgnTimeOff_Sec_M_u32	1713590788
ManVehSpd_Kph_M_f32	512.429993
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	67
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	212
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3048357120
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	92
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1079680256
PrevISDATBSI412MsgDLCError_Cnt_M_u08	64
PrevISDATBSI412MsgRxTime_MSec_M_u32	3671706880
PrevISDATBSI432MsgDLCError_Cnt_M_u08	238
PrevISDATBSI432MsgRxTime_MSec_M_u32	614313216
PrevISDATDIRAMsgTxTime_MSec_M_u32	3472739584
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	15
PrevISDYN2CMMMsgRxTime_MSec_M_u32	236641536
PrevISDYNAASMsgDLCError_Cnt_M_u08	120
PrevISDYNAASMsgRxTime_MSec_M_u32	2614971648
PrevISDYNABRMsgDLCError_Cnt_M_u08	236
PrevISDYNABRMsgRxTime_MSec_M_u32	2471333120
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	217
PrevISDYNCMM208MsgRxTime_MSec_M_u32	320752896
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	92
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3084692736
PrevISDYNVOLMsgDLCError_Cnt_M_u08	178
PrevISDYNVOLMsgRxTime_MSec_M_u32	2391985408
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	383745280
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	233.246307
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	317
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	61009
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	11026
VitesseVehicleBVRampValidCount_Cnt_M_u16	15846
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	8159
VitesseVehicleBVSigValidCount_Cnt_M_u16	41980
VitesseVehicleBV_Kph_M_f32	530.838074
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	4519
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	45468
VitesseVehiculeRoues_Kph_M_f32	463.826813
k_AASNTCEnableTimeout_mS_u16	39533
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	44328
k_AASNodeTimeout_mS_u16	42321
k_ABSNodeTimeout_mS_u16	13970
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	43181
k_ANGLEVOLANTSigValidThresh_Cnt_u16	57045
k_AngleVolantInvalidThresh_Cnt_u16	2088
k_AngleVolantValidThresh_Cnt_u16	7525
k_BSI552MsgTimeout_mS_u16	53423
k_BSINTCEnableTimeout_mS_u16	36590
k_BSINodeAbsentDiag_Cnt_str.Threshold	27858
k_BSINodeAbsentDiag_Cnt_str.PStep	42197
k_BSINodeAbsentDiag_Cnt_str.NStep	42749
k_BSINodeAbsentTimeout_mS_u16	47712
k_BSINodeTimeout_mS_u16	38853
k_BattOvHi_Volt_f32	26.1965008
k_BattOvLo_Volt_f32	19.2607002
k_BattUvHi_Volt_f32	15.0377998
k_BattUvLo_Volt_f32	24.6707001
k_CAVNTCEnableTimeout_mS_u16	38931
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	53950
k_CAVNodeTimeout_mS_u16	43307
k_CMM388MsgTimeout_mS_u16	31839
k_CMM388NTCEnableTimeout_mS_u16	5899
k_CMMNTCEnableTimeout_mS_u16	46206
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	19016
k_CONSANGLECPKMax_HwDeg_f32	685.507996
k_CONSANGLECPKMin_HwDeg_f32	-180.716003
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	34983
k_CONSANGLECPKSigValidThresh_Cnt_u16	26780
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	59343
k_CPKVehicleSpeedValidThresh_Cnt_u16	38090
k_CityParkInputInvalidThresh_Cnt_u16	54608
k_CityParkInputValidThresh_Cnt_u16	38053
k_ComputerRazGCTSigValidThresh_Cnt_u16	23684
k_CptTemporelSigValidThresh_Cnt_u16	27588
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	61994
k_DMDFCTCPKSigValidThresh_Cnt_u16	31958
k_DMDFCTCPKValidCount_Cnt_u16	46045
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	21564
k_DMDRELAXECPKSigValidThresh_Cnt_u16	54689
k_DMDRelaxeConsistentThresh_Cnt_u16	14879
k_DateValidThresh_Cnt_u16	15540
k_DefaultVehSpd_Kph_f32	97.6019974
k_DiagMuxOnAbsentTimeout_mS_u16	3160
k_EMNodeTimeout_mS_u16	8456
k_ESPNTCEnableTimeout_mS_u16	49940
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	4080
k_EtatMTSigInvalidThresh_Cnt_u16	38917
k_EtatMTSigValidThresh_Cnt_u16	14026
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	51822
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	33383
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	43130
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	45423
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	10991
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	16607
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	19295
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	33543
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	55018
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	22110
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	63535
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	14724
k_ISDATDIRASentDiag_Cnt_str.Threshold	64711

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	35441
k_ISDATDIRASentDiag_Cnt_str.NStep	35487
k_ISDATDIRASentTimeout_mS_u16	39934
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	17989
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	60936
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	6672
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	65362
k_ISDYNAASChkSumValidThresh_Cnt_u16	28119
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	44980
k_ISDYNAASMsgCountValidThresh_Cnt_u16	12529
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	11174
k_ISDYNAASMsgLenValidThresh_Cnt_u16	1189
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	2685
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	40320
k_ISDYNABRChkSumValidThresh_Cnt_u16	7340
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	45109
k_ISDYNABRMsgCountValidThresh_Cnt_u16	59602
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	63810
k_ISDYNABRMsgLenValidThresh_Cnt_u16	58666
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	63333
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	32913
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	43168
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	3940
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	53642
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	53223
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	56765
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	31522
k_ISDYNVOLChkSumValidThresh_Cnt_u16	37011
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	10707
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	61739
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	4466
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	27914
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	11746
k_IgnOnTimeout_mS_u16	45774
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	217.364197
k_PowerCutVehSpdLowThresh_Kph_f32	182.028305
k_PowerCutVehSpdLowTimeout_mS_u16	29769
k_VBattMaxAAS_Volt_f32	15.6613998
k_VBattMaxBSI_Volt_f32	21.1198006
k_VBattMaxCAV_Volt_f32	3.70230007
k_VBattMaxCMM388_Volt_f32	7.67430019
k_VBattMaxCMM_Volt_f32	22.0746002
k_VBattMaxESP_Volt_f32	6.62699986
k_VBattMinAAS_Volt_f32	3.69970012
k_VBattMinBSI_Volt_f32	6.62699986
k_VBattMinCAV_Volt_f32	5.73699999
k_VBattMinCMM388_Volt_f32	20.2591
k_VBattMinCMM_Volt_f32	26.0569992
k_VBattMinESP_Volt_f32	22.0746002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	25287
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	1448
k_VitesseVehicleBVRampValidThresh_Cnt_u16	45927
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	15041
k_VitesseVehicleBVSigValidThresh_Cnt_u16	28882
k_VitesseVehicleBVSpeedPassThresh_kph_f32	62.1239014
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	29288
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	31164
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	74050816
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	5919
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2992083200
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	92
target_SrlComInput_Per1_Batt_Volt_f32.value	6.72550011
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	950213888
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	55
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.976866603
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	13
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1887931648
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2497850624
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	112
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1305267456
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	55012608
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	491916544
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	65842432
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	521620736
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	191
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	207
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	227
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	209
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	754740480
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	90
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	123
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	139
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	147
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	164
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	255
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	694586624
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	190
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	725691648
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2175520000
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	9
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	57
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	176
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3587480832
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1968
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.713086545
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	791605
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	187.827301
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	28991

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2992083200	2992083200	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2992083200	2992083200	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2992083200	2992083200	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2992083200	2992083200	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2992083200	2992083200	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2992083200	2992083200	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2992083200	2992083200	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	27858	27858	✔
BSINodeAbsentTimer_mS_M_u32	2992083200	2992083200	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2992083200	2992083200	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2992083200	2992083200	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2992083200	2992083200	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2992083200	2992083200	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2992083200	2992083200	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	46634	46634	✔
CONSANGLECPK_HwDeg_M_f32	24.6060009	24.6060009 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2992083200	2992083200	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2992083200	2992083200	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2992083200	2992083200	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2992083200	2992083200	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2992083200	2992083200	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2992083200	2992083200	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2992083200	2992083200	✔
ESPNTCEnableTimer_mS_M_u32	2992083200	2992083200	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2992083200	2992083200	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3	3	✔
EffacDefaultDiagTimer_mS_M_u32[1]	6	6	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2992083200	2992083200	✔
ElecIntTimer_mS_M_u32[1]	7	7	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2992083200	2992083200	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2992083200	2992083200	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2992083200	2992083200	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2992083200	2992083200	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2992083200	2992083200	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2992083200	2992083200	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2992083200	2992083200	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2992083200	2992083200	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2992083200	2992083200	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2992083200	2992083200	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2992083200	2992083200	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2992083200	2992083200	✔
IgnOnTimer_mS_M_u32	2992083200	2992083200	✔
IgnTimeOff_Sec_M_u32	1713590788	1713590788	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	15	15	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1887931648	1887931648	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	206	206	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2497850624	2497850624	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	112	112	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1305267456	1305267456	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	90	90	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	55012608	55012608	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3472739584	3472739584	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	168	168	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	65842432	65842432	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	220	220	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	521620736	521620736	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	209	209	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	754740480	754740480	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	255	255	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	694586624	694586624	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	190	190	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	725691648	725691648	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	29	29	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2175520000	2175520000	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3587480832	3587480832	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	233.246307	233.246307	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	530.838074	530.838074	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	463.826813	463.826813	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	46634	46634	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1713590788	1713590788	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	24.6060009	24.6060009 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.447 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	574114816
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	48050
AASNodeAbsentTimer_mS_M_u32	3623664640
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	34355
ANGLEVOLANTSigValidCount_Cnt_M_u16	55773
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	26039
AngleVolantMsgTimer_mS_M_u32	574114816
AngleVolantValidCount_Cnt_M_u16	37469
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2272427008
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	307559424
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1902373888
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	635481088
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	22066
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3709889536
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	8730
CAVNodeAbsentTimer_mS_M_u32	987520000
CDD_SrlComVehSpd_Kph_G_f32	507.3862
CMM388NTCEnableTimer_mS_M_u32	1389534208
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1315068928
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	24908
CMMNodeAbsentTimer_mS_M_u32	215657472
CONSANGLECPKSigInvalidCount_Cnt_M_u16	50773
CONSANGLECPKSigValidCount_Cnt_M_u16	41934
CONSANGLECPK_Cnt_M_u16	16657
CONSANGLECPK_HwDeg_M_f32	611.566406
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	16657
CPKVehicleSpeedMsgTimer_mS_M_u32	1496271872
CPKVehicleSpeedValidCount_Cnt_M_u16	18751

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	11361
CityParkInputInvalidCount_Cnt_M_u16	58145
CityParkInputMsgTimer_mS_M_u32	1887931648
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4076911616
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	7094
ComputerRazGCTSigInvalidTimer_mS_M_u32	3590380544
ComputerRazGCTSigValidCount_Cnt_M_u16	39646
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	1309
DMDFCTCPKSigValidCount_Cnt_M_u16	48751
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	41525
DMDRELAXECPKSigValidCount_Cnt_M_u16	21343
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	45402
DateInvalidTimer_mS_M_u32	307559424
DiagMuxOnAbsentTimer_mS_M_u32	2539129856
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	635481088
ESPNTCEnableTimer_mS_M_u32	382057472
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	7250
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	9
EffacDefaultDiagTimer_mS_M_u32[1]	81
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	20
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1585605632
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	48831
EtatMTSigValidCount_Cnt_M_u16	26037
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	26711
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	9040
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	23541
ISDAT4V2BSI552MsgTimer_mS_M_u32	585018368
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	60960
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	56990
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	26037
ISDATBSI3F2MsgTimer_mS_M_u32	3444968448
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	19440
ISDATBSI412MsgLenValidCount_Cnt_M_u16	42014
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	48831
ISDATBSI412MsgTimer_mS_M_u32	2385923072
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	45648
ISDATBSI432MsgLenValidCount_Cnt_M_u16	59478
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	259
ISDATDIRASentFltAcc_Cnt_M_u16	44439
ISDATDIRASentTimer_mS_M_u32	1496271872
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	39311
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	37469
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	23196
ISDYN2CMMMsgTimer_mS_M_u32	239057920
ISDYNAASChkSumInvalidCount_Cnt_M_u16	17332
ISDYNAASChkSumValidCount_Cnt_M_u16	48510
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	7644
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	26013
ISDYNAASMsgLenValidCount_Cnt_M_u16	10911
ISDYNAASMsgTimeValidCount_Cnt_M_u16	17332
ISDYNAASMsgTimer_mS_M_u32	1640930304
ISDYNABRChkSumInvalidCount_Cnt_M_u16	62555
ISDYNABRChkSumValidCount_Cnt_M_u16	38797
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	46515
ISDYNABRMsgCountValidCount_Cnt_M_u16	189
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	21332
ISDYNABRMsgLenValidCount_Cnt_M_u16	16909
ISDYNABRMsgTimeValidCount_Cnt_M_u16	16657

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	9650
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	11496
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	26037
ISDYNCMM208MsgTimer_mS_M_u32	204438528
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	9650
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	11496
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	15707
ISDYNCMM388MsgTimer_mS_M_u32	2855148544
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	29779
ISDYNVOLChkSumValidCount_Cnt_M_u16	29772
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	3611
ISDYNVOLMsgCountValidCount_Cnt_M_u16	10733
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	12627
ISDYNVOLMsgLenValidCount_Cnt_M_u16	18605
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	24908
ISDYNVOLMsgTimer_mS_M_u32	4043103232
IgnOnTimer_mS_M_u32	1932663808
IgnTimeOff_Sec_M_u32	785612213
ManVehSpd_Kph_M_f32	36.4473991
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	68
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	170
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1136397312
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	124
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1027795968
PrevISDATBSI412MsgDLCError_Cnt_M_u08	39
PrevISDATBSI412MsgRxTime_MSec_M_u32	2793757696
PrevISDATBSI432MsgDLCError_Cnt_M_u08	182
PrevISDATBSI432MsgRxTime_MSec_M_u32	817478656
PrevISDATDIRAMsgTxTime_MSec_M_u32	1511611392
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	117
PrevISDYN2CMMMsgRxTime_MSec_M_u32	620899328
PrevISDYNAASMsgDLCError_Cnt_M_u08	63
PrevISDYNAASMsgRxTime_MSec_M_u32	3514489856
PrevISDYNABRMsgDLCError_Cnt_M_u08	24
PrevISDYNABRMsgRxTime_MSec_M_u32	4230618112
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	112
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2948062208
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	178
PrevISDYNCMM388MsgRxTime_MSec_M_u32	855424000
PrevISDYNVOLMsgDLCError_Cnt_M_u08	213
PrevISDYNVOLMsgRxTime_MSec_M_u32	2941934592
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1697926144
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	425.969604
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	42139
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	19485
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	47900
VitesseVehicleBVRampValidCount_Cnt_M_u16	61790
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	18996

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	19614
VitesseVehicleBV_Kph_M_f32	12.6300001
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	15707
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	19517
VitesseVehiculeRoues_Kph_M_f32	243.147903
k_AASNTCEnableTimeout_mS_u16	24648
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	44760
k_AASNodeTimeout_mS_u16	10013
k_ABSNodeTimeout_mS_u16	35738
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	39435
k_ANGLEVOLANTSigValidThresh_Cnt_u16	46673
k_AngleVolantInvalidThresh_Cnt_u16	18008
k_AngleVolantValidThresh_Cnt_u16	58145
k_BSI552MsgTimeout_mS_u16	64260
k_BSINTCEnableTimeout_mS_u16	11080
k_BSINodeAbsentDiag_Cnt_str.Threshold	27674
k_BSINodeAbsentDiag_Cnt_str.PStep	46416
k_BSINodeAbsentDiag_Cnt_str.NStep	12314
k_BSINodeAbsentTimeout_mS_u16	24751
k_BSINodeTimeout_mS_u16	259
k_BattOvHi_Volt_f32	27.5526009
k_BattOvLo_Volt_f32	20.3987007
k_BattUvHi_Volt_f32	2.43969989
k_BattUvLo_Volt_f32	26.1947994
k_CAVNTCEnableTimeout_mS_u16	43799
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	29720
k_CAVNodeTimeout_mS_u16	36177
k_CMM388MsgTimeout_mS_u16	54962
k_CMM388NTCEnableTimeout_mS_u16	46766
k_CMMNTCEnableTimeout_mS_u16	41752
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	12857
k_CONSANGLECPKMax_HwDeg_f32	554.405579
k_CONSANGLECPKMin_HwDeg_f32	-702.923279
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	55387
k_CONSANGLECPKSigValidThresh_Cnt_u16	10045
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	55203
k_CPKVehicleSpeedValidThresh_Cnt_u16	33587
k_CityParkInputInvalidThresh_Cnt_u16	34145
k_CityParkInputValidThresh_Cnt_u16	11361
k_ComputerRazGCTSigValidThresh_Cnt_u16	17158
k_CptTemporelSigValidThresh_Cnt_u16	13316
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	28244
k_DMDFCTCPKSigValidThresh_Cnt_u16	40205
k_DMDFCTCPKValidCount_Cnt_u16	1594
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	23196
k_DMDRELAXECPKSigValidThresh_Cnt_u16	34094
k_DMDRelaxeConsistentThresh_Cnt_u16	53172
k_DateValidThresh_Cnt_u16	23541
k_DefaultVehSpd_Kph_f32	55.5172997
k_DiagMuxOnAbsentTimeout_mS_u16	30343
k_EMNodeTimeout_mS_u16	55738
k_ESPNTCEnableTimeout_mS_u16	31510
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	33089
k_EtatMTSigInvalidThresh_Cnt_u16	20802
k_EtatMTSigValidThresh_Cnt_u16	41908
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	27590
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	17052
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	34018
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	45125
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	25219
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	4852

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	63989
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	4539
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	17236
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	12405
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	43459
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	19972
k_ISDATDIRASentDiag_Cnt_str.Threshold	39837
k_ISDATDIRASentDiag_Cnt_str.PStep	59486
k_ISDATDIRASentDiag_Cnt_str.NStep	60819
k_ISDATDIRASentTimeout_mS_u16	26967
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	27585
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	26039
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	26146
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	36699
k_ISDYNAASChkSumValidThresh_Cnt_u16	29325
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	53427
k_ISDYNAASMsgCountValidThresh_Cnt_u16	23485
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	23135
k_ISDYNAASMsgLenValidThresh_Cnt_u16	22817
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	54105
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	17490
k_ISDYNABRChkSumValidThresh_Cnt_u16	38283
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	28978
k_ISDYNABRMsgCountValidThresh_Cnt_u16	22044
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	15436
k_ISDYNABRMsgLenValidThresh_Cnt_u16	14162
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	13923
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	30367
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	8113
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	62692
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	41267
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	13533
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	537
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	12331
k_ISDYNVOLChkSumValidThresh_Cnt_u16	52889
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	19799
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	14481
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	1211
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	28849
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	49259
k_IgnOnTimeout_mS_u16	14631
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	68.7306976
k_PowerCutVehSpdLowThresh_Kph_f32	214.738495
k_PowerCutVehSpdLowTimeout_mS_u16	17076
k_VBattMaxAAS_Volt_f32	4.36210012
k_VBattMaxBSI_Volt_f32	22.0825005
k_VBattMaxCAV_Volt_f32	26.2852993
k_VBattMaxCMM388_Volt_f32	11.3401003
k_VBattMaxCMM_Volt_f32	28.5639
k_VBattMaxESP_Volt_f32	19.7026997
k_VBattMinAAS_Volt_f32	5.02370024
k_VBattMinBSI_Volt_f32	19.7026997
k_VBattMinCAV_Volt_f32	28.2702999
k_VBattMinCMM388_Volt_f32	27.0494995
k_VBattMinCMM_Volt_f32	6.14319992
k_VBattMinESP_Volt_f32	28.5639
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	40507
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	21593
k_VitesseVehicleBVRampValidThresh_Cnt_u16	43291
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	53068
k_VitesseVehicleBVSigValidThresh_Cnt_u16	35802
k_VitesseVehicleBVSpeedPassThresh_kph_f32	552.839722
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	48410
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	5596
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	307559424
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	33851
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1008472064
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	178
target_SrlComInput_Per1_Batt_Volt_f32.value	7.23890018
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	376007680
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	59
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.553263783
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	52
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3430685696
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2448178176
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3651951616
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1807514624
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	270310400
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2395782144
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2949438464
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	37
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	73
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	88
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	158
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	185
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	187
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	225
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	43875328
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	114
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	142
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	155
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	192
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3722386432
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	112
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	181353472
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	165
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2047826944
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	74
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	137
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	156
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	194
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3839159296
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2881
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.349816203
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	967796
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	107.591202
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	56469

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1008472064	1008472064	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	26039	26039	✔
AngleVolantMsgTimer_mS_M_u32	1008472064	1008472064	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	27674	27674	✔
BSINodeAbsentTimer_mS_M_u32	1008472064	1008472064	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1008472064	1008472064	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1008472064	1008472064	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	16657	16657	✔
CONSANGLECPK_HwDeg_M_f32	611.566406	611.566406 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	16657	16657	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1496271872	1496271872	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	18751	18751	✔
CityParkInputConsistentCount_Cnt_M_u16	11361	11361	✔
CityParkInputInvalidCount_Cnt_M_u16	58145	58145	✔
CityParkInputMsgTimer_mS_M_u32	1008472064	1008472064	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1008472064	1008472064	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1008472064	1008472064	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1008472064	1008472064	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1008472064	1008472064	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1008472064	1008472064	✔
ESPNTCEnableTimer_mS_M_u32	1008472064	1008472064	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1008472064	1008472064	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	9	9	✔
EffacDefaultDiagTimer_mS_M_u32[1]	81	81	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	20	20	✔
ElecIntTimer_mS_M_u32[1]	20	20	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1008472064	1008472064	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1008472064	1008472064	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1008472064	1008472064	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1008472064	1008472064	✔
IgnOnTimer_mS_M_u32	1008472064	1008472064	✔
IgnTimeOff_Sec_M_u32	785612213	785612213	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	52	52	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3430685696	3430685696	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	3	3	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2448178176	2448178176	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	113	113	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3651951616	3651951616	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	68	68	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1807514624	1807514624	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1511611392	1511611392	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	63	63	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2395782144	2395782144	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	246	246	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2949438464	2949438464	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	242	242	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	43875328	43875328	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	153	153	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3722386432	3722386432	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	112	112	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	181353472	181353472	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	165	165	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2047826944	2047826944	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3839159296	3839159296	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	425.969604	425.969604	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	12.6300001	12.6300001	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	243.147903	243.147903	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	16657	16657	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	785612213	785612213	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	611.566406	611.566406 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.448 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2899071744
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	53124
AASNodeAbsentTimer_mS_M_u32	4095083264
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	57739
ANGLEVOLANTSigValidCount_Cnt_M_u16	62972
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	20677
AngleVolantMsgTimer_mS_M_u32	2899071744
AngleVolantValidCount_Cnt_M_u16	31125
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2052113152
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2538685184
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1055093504
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	192492288
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	56958
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	4109759232
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	935
CAVNodeAbsentTimer_mS_M_u32	3796968192
CDD_SrlComVehSpd_Kph_G_f32	639.290894
CMM388NTCEnableTimer_mS_M_u32	2157077248
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3525255936
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	19140
CMMNodeAbsentTimer_mS_M_u32	1412117248
CONSANGLECPKSigInvalidCount_Cnt_M_u16	33922
CONSANGLECPKSigValidCount_Cnt_M_u16	2179
CONSANGLECPK_Cnt_M_u16	32234
CONSANGLECPK_HwDeg_M_f32	-300.419708
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	32234
CPKVehicleSpeedMsgTimer_mS_M_u32	1280791296
CPKVehicleSpeedValidCount_Cnt_M_u16	48369
CityParkInputConsistentCount_Cnt_M_u16	38857

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	45375
CityParkInputMsgTimer_mS_M_u32	4112883712
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2672427776
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	64440
ComputerRazGCTSigInvalidTimer_mS_M_u32	3098256128
ComputerRazGCTSigValidCount_Cnt_M_u16	64290
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	7947
DMDFCTCPKSigValidCount_Cnt_M_u16	54532
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	29605
DMDRELAXECPKSigValidCount_Cnt_M_u16	51094
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	21187
DateInvalidTimer_mS_M_u32	2538685184
DiagMuxOnAbsentTimer_mS_M_u32	3668513536
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	192492288
ESPNTCEnableTimer_mS_M_u32	2404057856
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	29409
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	64
EffacDefaultDiagTimer_mS_M_u32[1]	894
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	89
ElecIntTimer_mS_M_u32[1]	899
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3438277376
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	14174
EtatMTSigValidCount_Cnt_M_u16	10923
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	58524
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	10269
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	50898
ISDAT4V2BSI552MsgTimer_mS_M_u32	3193910016
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	30307
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	15768
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	10923
ISDATBSI3F2MsgTimer_mS_M_u32	1921979136
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	52918
ISDATBSI412MsgLenValidCount_Cnt_M_u16	59867
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	14174
ISDATBSI412MsgTimer_mS_M_u32	45241088
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	46072
ISDATBSI432MsgLenValidCount_Cnt_M_u16	6933
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	8316
ISDATDIRASentFltAcc_Cnt_M_u16	57344
ISDATDIRASentTimer_mS_M_u32	1280791296
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	22096
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	31125
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	25470
ISDYN2CMMMsgTimer_mS_M_u32	779944704
ISDYNAASChkSumInvalidCount_Cnt_M_u16	56734
ISDYNAASChkSumValidCount_Cnt_M_u16	16816
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	31752
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	43598
ISDYNAASMsgLenValidCount_Cnt_M_u16	2104
ISDYNAASMsgTimeValidCount_Cnt_M_u16	56734
ISDYNAASMsgTimer_mS_M_u32	4150158080
ISDYNABRChkSumInvalidCount_Cnt_M_u16	10424
ISDYNABRChkSumValidCount_Cnt_M_u16	24337
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	5265
ISDYNABRMsgCountValidCount_Cnt_M_u16	55523
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	6773
ISDYNABRMsgLenValidCount_Cnt_M_u16	16054
ISDYNABRMsgTimeValidCount_Cnt_M_u16	32234
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	35704

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	16009
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	10923
ISDYNCMM208MsgTimer_mS_M_u32	3202990848
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	35704
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	16009
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	635
ISDYNCMM388MsgTimer_mS_M_u32	2058871552
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	13416
ISDYNVOLChkSumValidCount_Cnt_M_u16	63721
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	28145
ISDYNVOLMsgCountValidCount_Cnt_M_u16	42090
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	5870
ISDYNVOLMsgLenValidCount_Cnt_M_u16	11087
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	19140
ISDYNVOLMsgTimer_mS_M_u32	3413615360
IgnOnTimer_mS_M_u32	4226540288
IgnTimeOff_Sec_M_u32	736113099
ManVehSpd_Kph_M_f32	55.7565002
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	69
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	85
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	129831680
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	139
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2788586240
PrevISDATBSI412MsgDLCError_Cnt_M_u08	46
PrevISDATBSI412MsgRxTime_MSec_M_u32	1692803840
PrevISDATBSI432MsgDLCError_Cnt_M_u08	224
PrevISDATBSI432MsgRxTime_MSec_M_u32	4239328000
PrevISDATDIRAMsgTxTime_MSec_M_u32	2137662208
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	145
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1017950976
PrevISDYNAASMsgDLCError_Cnt_M_u08	150
PrevISDYNAASMsgRxTime_MSec_M_u32	2346558208
PrevISDYNABRMsgDLCError_Cnt_M_u08	113
PrevISDYNABRMsgRxTime_MSec_M_u32	1485038336
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	153
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3690373888
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	123
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2467693312
PrevISDYNVOLMsgDLCError_Cnt_M_u08	190
PrevISDYNVOLMsgRxTime_MSec_M_u32	649536256
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3348648704
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	164.1465
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	46900
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	5534
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	61121
VitesseVehicleBVRampValidCount_Cnt_M_u16	52459
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	26776
VitesseVehicleBVSigValidCount_Cnt_M_u16	40137

Name	Input Value
VitesseVehicleBV_Kph_M_f32	501.016907
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	635
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	49348
VitesseVehiculeRoues_Kph_M_f32	549.668274
k_AASNTCEnableTimeout_mS_u16	43189
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	36052
k_AASNodeTimeout_mS_u16	13470
k_ABSNodeTimeout_mS_u16	47716
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	55671
k_ANGLEVOLANTSigValidThresh_Cnt_u16	45524
k_AngleVolantInvalidThresh_Cnt_u16	1839
k_AngleVolantValidThresh_Cnt_u16	45375
k_BSI552MsgTimeout_mS_u16	58847
k_BSINTCEnableTimeout_mS_u16	16528
k_BSINodeAbsentDiag_Cnt_str.Threshold	26710
k_BSINodeAbsentDiag_Cnt_str.PStep	59249
k_BSINodeAbsentDiag_Cnt_str.NStep	22112
k_BSINodeAbsentTimeout_mS_u16	30557
k_BSINodeTimeout_mS_u16	8316
k_BattOvHi_Volt_f32	24.4083996
k_BattOvLo_Volt_f32	18.4417992
k_BattUvHi_Volt_f32	27.3052998
k_BattUvLo_Volt_f32	25.4433002
k_CAVNTCEnableTimeout_mS_u16	6845
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	1933
k_CAVNodeTimeout_mS_u16	21326
k_CMM388MsgTimeout_mS_u16	11908
k_CMM388NTCEnableTimeout_mS_u16	16976
k_CMMNTCEnableTimeout_mS_u16	3835
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	8848
k_CONSANGLECPKMax_HwDeg_f32	411.471985
k_CONSANGLECPKMin_HwDeg_f32	-750.433472
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	57723
k_CONSANGLECPKSigValidThresh_Cnt_u16	57284
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	7532
k_CPKVehicleSpeedValidThresh_Cnt_u16	5661
k_CityParkInputInvalidThresh_Cnt_u16	63494
k_CityParkInputValidThresh_Cnt_u16	38857
k_ComputerRazGCTSigValidThresh_Cnt_u16	55313
k_CptTemporelSigValidThresh_Cnt_u16	9670
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	31093
k_DMDFCTCPKSigValidThresh_Cnt_u16	56758
k_DMDFCTCPKValidCount_Cnt_u16	26342
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	25470
k_DMDRELAXECPKSigValidThresh_Cnt_u16	39351
k_DMDRelaxeConsistentThresh_Cnt_u16	21637
k_DateValidThresh_Cnt_u16	50898
k_DefaultVehSpd_Kph_f32	248.038895
k_DiagMuxOnAbsentTimeout_mS_u16	63208
k_EMNodeTimeout_mS_u16	32675
k_ESPNTCEnableTimeout_mS_u16	15475
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	48632
k_EtatMTSigInvalidThresh_Cnt_u16	34163
k_EtatMTSigValidThresh_Cnt_u16	25100
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	48179
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	48608
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	10582
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	37188
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	28473
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	13802
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	5721

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	13366
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	23852
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	4606
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	15299
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	35454
k_ISDATDIRASentDiag_Cnt_str.Threshold	61866
k_ISDATDIRASentDiag_Cnt_str.PStep	48259
k_ISDATDIRASentDiag_Cnt_str.NStep	33088
k_ISDATDIRASentTimeout_mS_u16	52612
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	37911
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	20677
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	4111
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	1976
k_ISDYNAASChkSumValidThresh_Cnt_u16	32273
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	29585
k_ISDYNAASMsgCountValidThresh_Cnt_u16	30691
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	41708
k_ISDYNAASMsgLenValidThresh_Cnt_u16	2770
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	49980
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	12635
k_ISDYNABRChkSumValidThresh_Cnt_u16	54812
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	15742
k_ISDYNABRMsgCountValidThresh_Cnt_u16	29231
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	27076
k_ISDYNABRMsgLenValidThresh_Cnt_u16	53729
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	39626
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	44392
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	25219
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	60601
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	16523
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	38140
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	43991
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	18101
k_ISDYNVOLChkSumValidThresh_Cnt_u16	45850
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	53026
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	55365
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	31018
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	28023
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	41680
k_IgnOnTimeout_mS_u16	28545
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	129.687805
k_PowerCutVehSpdLowThresh_Kph_f32	17.7894001
k_PowerCutVehSpdLowTimeout_mS_u16	11313
k_VBattMaxAAS_Volt_f32	7.95720005
k_VBattMaxBSI_Volt_f32	13.6225996
k_VBattMaxCAV_Volt_f32	18.8479996
k_VBattMaxCMM388_Volt_f32	5.14109993
k_VBattMaxCMM_Volt_f32	19.6182995
k_VBattMaxESP_Volt_f32	11.8739996
k_VBattMinAAS_Volt_f32	7.89729977
k_VBattMinBSI_Volt_f32	11.8739996
k_VBattMinCAV_Volt_f32	4.53789997
k_VBattMinCMM388_Volt_f32	1.15569997
k_VBattMinCMM_Volt_f32	10.3014002
k_VBattMinESP_Volt_f32	19.6182995
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	12873
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	58014
k_VitesseVehicleBVRampValidThresh_Cnt_u16	19697
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	38889
k_VitesseVehicleBVSigValidThresh_Cnt_u16	60398
k_VitesseVehicleBVSpeedPassThresh_kph_f32	493.566498
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	58023
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	337
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2538685184
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	28870
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	4009874432
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	123
target_SrlComInput_Per1_Batt_Volt_f32.value	30.1756001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3366646528
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	80
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.527597904
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	44950272
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3955196672
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	171
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1658921728
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	56
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2417148672
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2605998848
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2896560896
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3959923456
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	62
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	64
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	76
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	84
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	153
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	177
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	204
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	124
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1820312320
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	40
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	109
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	183
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	203
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	145
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3182748416
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1749451520
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1625826048
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	45
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	121
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	146
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	172
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	190
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4271928064
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	717
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.586145282
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	173108
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	188.813004

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	7398		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	4009874432	4009874432	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	26710	26710	✔
BSINodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	32234	32234	✔
CONSANGLECPK_HwDeg_M_f32	-300.419708	-300.419708 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4009874432	4009874432	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	4009874432	4009874432	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4009874432	4009874432	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4009874432	4009874432	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4009874432	4009874432	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4009874432	4009874432	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4009874432	4009874432	✔
ESPNTCEnableTimer_mS_M_u32	4009874432	4009874432	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4009874432	4009874432	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	64	64	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	894	894	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4009874432	4009874432	✔
ElecIntTimer_mS_M_u32[1]	899	899	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4009874432	4009874432	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	4009874432	4009874432	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4009874432	4009874432	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4009874432	4009874432	✔
IgnOnTimer_mS_M_u32	4009874432	4009874432	✔
IgnTimeOff_Sec_M_u32	736113099	736113099	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	206	206	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	44950272	44950272	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	63	63	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3955196672	3955196672	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	171	171	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1658921728	1658921728	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	56	56	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2417148672	2417148672	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2137662208	2137662208	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	88	88	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2896560896	2896560896	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	60	60	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3959923456	3959923456	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	124	124	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1820312320	1820312320	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	145	145	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3182748416	3182748416	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1749451520	1749451520	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	240	240	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1625826048	1625826048	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4271928064	4271928064	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	164.1465	164.1465	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	501.016907	501.016907	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	549.668274	549.668274	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	32234	32234	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	736113099	736113099	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-300.419708	-300.419708 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.449 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	172345856
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	9244
AASNodeAbsentTimer_mS_M_u32	3072899584
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	10248
ANGLEVOLANTSigValidCount_Cnt_M_u16	27509
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	58457
AngleVolantMsgTimer_mS_M_u32	172345856
AngleVolantValidCount_Cnt_M_u16	45162
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2138601984
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3396794880
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	411068928
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	968829440
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	48431
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1615391232
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	31794
CAVNodeAbsentTimer_mS_M_u32	1089952256
CDD_SrlComVehSpd_Kph_G_f32	486.785309
CMM388NTCEnableTimer_mS_M_u32	4214462976
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	697129472
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	58525
CMMNodeAbsentTimer_mS_M_u32	2812881408
CONSANGLECPKSigInvalidCount_Cnt_M_u16	35364
CONSANGLECPKSigValidCount_Cnt_M_u16	48864
CONSANGLECPK_Cnt_M_u16	47787
CONSANGLECPK_HwDeg_M_f32	591.772583
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	47787
CPKVehicleSpeedMsgTimer_mS_M_u32	396675584
CPKVehicleSpeedValidCount_Cnt_M_u16	30237

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	9678
CityParkInputInvalidCount_Cnt_M_u16	33387
CityParkInputMsgTimer_mS_M_u32	44950272
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2240592384
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	28544
ComputerRazGCTSigInvalidTimer_mS_M_u32	1206376960
ComputerRazGCTSigValidCount_Cnt_M_u16	40899
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	26887
DMDFCTCPKSigValidCount_Cnt_M_u16	59356
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	22970
DMDRELAXECPKSigValidCount_Cnt_M_u16	56999
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	25441
DateInvalidTimer_mS_M_u32	3396794880
DiagMuxOnAbsentTimer_mS_M_u32	3819932160
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	968829440
ESPNTCEnableTimer_mS_M_u32	4186552832
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	40198
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1123
EffacDefaultDiagTimer_mS_M_u32[1]	5523
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	749
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1079699968
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	22478
EtatMTSigValidCount_Cnt_M_u16	28327
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	20950
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	18450
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	51826
ISDAT4V2BSI552MsgTimer_mS_M_u32	957164032
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	17984
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	33120
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	28327
ISDATBSI3F2MsgTimer_mS_M_u32	872253952
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	39494
ISDATBSI412MsgLenValidCount_Cnt_M_u16	39318
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	22478
ISDATBSI412MsgTimer_mS_M_u32	546556416
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	30977
ISDATBSI432MsgLenValidCount_Cnt_M_u16	29802
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	47539
ISDATDIRASentFltAcc_Cnt_M_u16	35623
ISDATDIRASentTimer_mS_M_u32	396675584
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	18809
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	45162
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	10158
ISDYN2CMMMsgTimer_mS_M_u32	1676917248
ISDYNAASChkSumInvalidCount_Cnt_M_u16	57806
ISDYNAASChkSumValidCount_Cnt_M_u16	46682
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	13585
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	58429
ISDYNAASMsgLenValidCount_Cnt_M_u16	11074
ISDYNAASMsgTimeValidCount_Cnt_M_u16	57806
ISDYNAASMsgTimer_mS_M_u32	3335494144
ISDYNABRChkSumInvalidCount_Cnt_M_u16	40450
ISDYNABRChkSumValidCount_Cnt_M_u16	7094
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	51445
ISDYNABRMsgCountValidCount_Cnt_M_u16	31937
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	21579
ISDYNABRMsgLenValidCount_Cnt_M_u16	43079
ISDYNABRMsgTimeValidCount_Cnt_M_u16	47787

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	64181
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	37186
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	28327
ISDYNCMM208MsgTimer_mS_M_u32	1437432320
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	64181
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	37186
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	11704
ISDYNCMM388MsgTimer_mS_M_u32	2193824256
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	37490
ISDYNVOLChkSumValidCount_Cnt_M_u16	1454
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	37973
ISDYNVOLMsgCountValidCount_Cnt_M_u16	37290
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	9439
ISDYNVOLMsgLenValidCount_Cnt_M_u16	10363
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	58525
ISDYNVOLMsgTimer_mS_M_u32	1065605632
IgnOnTimer_mS_M_u32	3475446272
IgnTimeOff_Sec_M_u32	1165504038
ManVehSpd_Kph_M_f32	234.397903
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	67
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	201
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2893253120
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	251
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4001851904
PrevISDATBSI412MsgDLCError_Cnt_M_u08	62
PrevISDATBSI412MsgRxTime_MSec_M_u32	1295538688
PrevISDATBSI432MsgDLCError_Cnt_M_u08	149
PrevISDATBSI432MsgRxTime_MSec_M_u32	1096661504
PrevISDATDIRAMsgTxTime_MSec_M_u32	229399040
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	83
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3559172608
PrevISDYNAASMsgDLCError_Cnt_M_u08	56
PrevISDYNAASMsgRxTime_MSec_M_u32	374462976
PrevISDYNABRMsgDLCError_Cnt_M_u08	183
PrevISDYNABRMsgRxTime_MSec_M_u32	425662976
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	94
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3389446656
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	133
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3660102144
PrevISDYNVOLMsgDLCError_Cnt_M_u08	169
PrevISDYNVOLMsgRxTime_MSec_M_u32	2344966656
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3923888640
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	153.432602
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	54667
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	6928
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	41700
VitesseVehicleBVRampValidCount_Cnt_M_u16	26921
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	1761

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	60174
VitesseVehicleBV_Kph_M_f32	135.022598
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	11704
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	54172
VitesseVehiculeRoues_Kph_M_f32	480.041504
k_AASNTCEnableTimeout_mS_u16	9802
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	12973
k_AASNodeTimeout_mS_u16	48656
k_ABSNodeTimeout_mS_u16	15100
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	50308
k_ANGLEVOLANTSigValidThresh_Cnt_u16	27693
k_AngleVolantInvalidThresh_Cnt_u16	38940
k_AngleVolantValidThresh_Cnt_u16	33387
k_BSI552MsgTimeout_mS_u16	36939
k_BSINTCEnableTimeout_mS_u16	13113
k_BSINodeAbsentDiag_Cnt_str.Threshold	45980
k_BSINodeAbsentDiag_Cnt_str.PStep	13962
k_BSINodeAbsentDiag_Cnt_str.NStep	14845
k_BSINodeAbsentTimeout_mS_u16	53393
k_BSINodeTimeout_mS_u16	47539
k_BattOvHi_Volt_f32	8.14120007
k_BattOvLo_Volt_f32	19.6615009
k_BattUvHi_Volt_f32	25.6662006
k_BattUvLo_Volt_f32	0.878799975
k_CAVNTCEnableTimeout_mS_u16	48625
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	34944
k_CAVNodeTimeout_mS_u16	19904
k_CMM388MsgTimeout_mS_u16	1820
k_CMM388NTCEnableTimeout_mS_u16	64440
k_CMMNTCEnableTimeout_mS_u16	56440
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	56888
k_CONSANGLECPKMax_HwDeg_f32	128.267303
k_CONSANGLECPKMin_HwDeg_f32	-284.727997
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	37048
k_CONSANGLECPKSigValidThresh_Cnt_u16	30364
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	48038
k_CPKVehicleSpeedValidThresh_Cnt_u16	8209
k_CityParkInputInvalidThresh_Cnt_u16	59416
k_CityParkInputValidThresh_Cnt_u16	9678
k_ComputerRazGCTSigValidThresh_Cnt_u16	22838
k_CptTemporelSigValidThresh_Cnt_u16	214
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	14155
k_DMDFCTCPKSigValidThresh_Cnt_u16	52039
k_DMDFCTCPKValidCount_Cnt_u16	50167
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	10158
k_DMDRELAXECPKSigValidThresh_Cnt_u16	9667
k_DMDRelaxeConsistentThresh_Cnt_u16	44377
k_DateValidThresh_Cnt_u16	51826
k_DefaultVehSpd_Kph_f32	167.0504
k_DiagMuxOnAbsentTimeout_mS_u16	51121
k_EMNodeTimeout_mS_u16	23745
k_ESPNTCEnableTimeout_mS_u16	462
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	44032
k_EtatMTSigInvalidThresh_Cnt_u16	13265
k_EtatMTSigValidThresh_Cnt_u16	48837
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	47953
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	9993
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	58663
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	47517
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	45181
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	13482

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	5598
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	60679
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	19813
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	20079
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	41440
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	37872
k_ISDATDIRASentDiag_Cnt_str.Threshold	28362
k_ISDATDIRASentDiag_Cnt_str.PStep	56832
k_ISDATDIRASentDiag_Cnt_str.NStep	61321
k_ISDATDIRASentTimeout_mS_u16	57246
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	6949
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58457
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	63226
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	258
k_ISDYNAASChkSumValidThresh_Cnt_u16	48822
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	44021
k_ISDYNAASMsgCountValidThresh_Cnt_u16	40897
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	65382
k_ISDYNAASMsgLenValidThresh_Cnt_u16	2932
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	55285
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	10137
k_ISDYNABRChkSumValidThresh_Cnt_u16	64021
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	41007
k_ISDYNABRMsgCountValidThresh_Cnt_u16	33500
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	34717
k_ISDYNABRMsgLenValidThresh_Cnt_u16	32774
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	13579
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	49903
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	21215
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	49599
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	2824
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	36469
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	62115
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	61001
k_ISDYNVOLChkSumValidThresh_Cnt_u16	63961
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	52291
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	32794
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	49770
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	54851
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	44664
k_IgnOnTimeout_mS_u16	41957
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	202.603699
k_PowerCutVehSpdLowThresh_Kph_f32	2.29900002
k_PowerCutVehSpdLowTimeout_mS_u16	35798
k_VBattMaxAAS_Volt_f32	7.21640015
k_VBattMaxBSI_Volt_f32	29.9878006
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	9.7670002
k_VBattMaxCMM_Volt_f32	27.0182991
k_VBattMaxESP_Volt_f32	0.460900009
k_VBattMinAAS_Volt_f32	3.36759996
k_VBattMinBSI_Volt_f32	0.460900009
k_VBattMinCAV_Volt_f32	31.7182999
k_VBattMinCMM388_Volt_f32	23.8824997
k_VBattMinCMM_Volt_f32	9.69069958
k_VBattMinESP_Volt_f32	27.0182991
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	34959
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	34896
k_VitesseVehicleBVRampValidThresh_Cnt_u16	63317
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	10414
k_VitesseVehicleBVSigValidThresh_Cnt_u16	64863
k_VitesseVehicleBVSpeedPassThresh_kph_f32	291.334106
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	57138
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	58359
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3396794880
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	23985
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	4142483200
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	133
target_SrlComInput_Per1_Batt_Volt_f32.value	12.2440004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4180273664
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	17
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.972140551
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1122048512
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	234
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1445739008
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4282866176
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3325196800
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	854432256
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	217
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3447241216
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	500423168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	54
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	107
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	121
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	225
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	619411968
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	75
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	93
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	105
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	235
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	36
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3989576192
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3164027392
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	163
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3778173440
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	23
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	86
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	157
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	199
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	222915072
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1553
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.705681264
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	763695
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	109.477898
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	60533

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4142483200	4142483200	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	58457	58457	✔
AngleVolantMsgTimer_mS_M_u32	4142483200	4142483200	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	45980	45980	✔
BSINodeAbsentTimer_mS_M_u32	4142483200	4142483200	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4142483200	4142483200	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	58525	58525	✔
CMMNodeAbsentTimer_mS_M_u32	3447241216	3447241216	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	47787	47787	✔
CONSANGLECPK_HwDeg_M_f32	591.772583	591.772583 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	47787	47787	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	396675584	396675584	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	30237	30237	✔
CityParkInputConsistentCount_Cnt_M_u16	9678	9678	✔
CityParkInputInvalidCount_Cnt_M_u16	33389	33389	✔
CityParkInputMsgTimer_mS_M_u32	4142483200	4142483200	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4142483200	4142483200	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4142483200	4142483200	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4142483200	4142483200	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4142483200	4142483200	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4142483200	4142483200	✔
ESPNTCEnableTimer_mS_M_u32	4142483200	4142483200	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4142483200	4142483200	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	4142483200	4142483200	✔
EffacDefaultDiagTimer_mS_M_u32[1]	5523	5523	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	4142483200	4142483200	✔
ElecIntTimer_mS_M_u32[1]	749	749	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4142483200	4142483200	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	4142483200	4142483200	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4142483200	4142483200	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4142483200	4142483200	✔
IgnOnTimer_mS_M_u32	3475446272	3475446272	✔
IgnTimeOff_Sec_M_u32	1165504038	1165504038	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	3	3	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	142	142	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1122048512	1122048512	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	234	234	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1445739008	1445739008	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	151	151	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4282866176	4282866176	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	30	30	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3325196800	3325196800	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	229399040	229399040	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	217	217	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3447241216	3447241216	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	30	30	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	500423168	500423168	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	619411968	619411968	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	36	36	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3989576192	3989576192	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3164027392	3164027392	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	163	163	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3778173440	3778173440	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	222915072	222915072	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	153.432602	153.432602	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	135.022598	135.022598	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	480.041504	480.041504	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	47787	47787	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1165504038	1165504038	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	591.772583	591.772583 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	167.0504	167.0504	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.450 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	140457472
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	37581
AASNodeAbsentTimer_mS_M_u32	1246963200
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	28146
ANGLEVOLANTSigValidCount_Cnt_M_u16	20439
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	11066
AngleVolantMsgTimer_mS_M_u32	140457472
AngleVolantValidCount_Cnt_M_u16	33721
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1252451840
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3552404992
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1919931904
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1891800576
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	33961
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2746242560
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	63738
CAVNodeAbsentTimer_mS_M_u32	1723319808
CDD_SrlComVehSpd_Kph_G_f32	582.532471
CMM388NTCEnableTimer_mS_M_u32	1345324544
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3454912000
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	39674
CMMNodeAbsentTimer_mS_M_u32	4161574400
CONSANGLECPKSigInvalidCount_Cnt_M_u16	64337
CONSANGLECPKSigValidCount_Cnt_M_u16	31111
CONSANGLECPK_Cnt_M_u16	15522
CONSANGLECPK_HwDeg_M_f32	-720.83313
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	15522
CPKVehicleSpeedMsgTimer_mS_M_u32	3016635904
CPKVehicleSpeedValidCount_Cnt_M_u16	64180
CityParkInputConsistentCount_Cnt_M_u16	21213
CityParkInputInvalidCount_Cnt_M_u16	17575
CityParkInputMsgTimer_mS_M_u32	2138160896

Name	Input Value
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3799459328
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	55281
ComputerRazGCTSigInvalidTimer_mS_M_u32	1151354368
ComputerRazGCTSigValidCount_Cnt_M_u16	43394
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	4483
DMDFCTCPKSigValidCount_Cnt_M_u16	22608
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56452
DMDRELAXECPKSigValidCount_Cnt_M_u16	59369
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	7358
DateInvalidTimer_mS_M_u32	0
DiagMuxOnAbsentTimer_mS_M_u32	1076688384
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1891800576
ESPNTCEnableTimer_mS_M_u32	4070843904
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	29211
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8976
ElecIntTimer_mS_M_u32[1]	15236
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1520588288
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	10775
EtatMTSigValidCount_Cnt_M_u16	47272
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	40931
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	51097
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	6534
ISDAT4V2BSI552MsgTimer_mS_M_u32	590386688
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	498
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	53324
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	47272
ISDATBSI3F2MsgTimer_mS_M_u32	865793536
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	24724
ISDATBSI412MsgLenValidCount_Cnt_M_u16	61470
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	10775
ISDATBSI412MsgTimer_mS_M_u32	1640838656
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	39198
ISDATBSI432MsgLenValidCount_Cnt_M_u16	33599
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	27243
ISDATDIRASentFltAcc_Cnt_M_u16	38047
ISDATDIRASentTimer_mS_M_u32	3016635904
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	34448
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	33721
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	47546
ISDYN2CMMMsgTimer_mS_M_u32	2926454272
ISDYNAASChkSumInvalidCount_Cnt_M_u16	52575
ISDYNAASChkSumValidCount_Cnt_M_u16	44645
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	37360
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	25685
ISDYNAASMsgLenValidCount_Cnt_M_u16	12370
ISDYNAASMsgTimeValidCount_Cnt_M_u16	52575
ISDYNAASMsgTimer_mS_M_u32	2987132416
ISDYNABRChkSumInvalidCount_Cnt_M_u16	46293
ISDYNABRChkSumValidCount_Cnt_M_u16	35971
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	5654
ISDYNABRMsgCountValidCount_Cnt_M_u16	57948
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	63240
ISDYNABRMsgLenValidCount_Cnt_M_u16	41086
ISDYNABRMsgTimeValidCount_Cnt_M_u16	15522
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	44400
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	47794
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	47272

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimer_mS_M_u32	965469696
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	44400
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	47794
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	54311
ISDYNCMM388MsgTimer_mS_M_u32	415729152
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	9919
ISDYNVOLChkSumValidCount_Cnt_M_u16	64373
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	12273
ISDYNVOLMsgCountValidCount_Cnt_M_u16	3390
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	43108
ISDYNVOLMsgLenValidCount_Cnt_M_u16	34681
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	39674
ISDYNVOLMsgTimer_mS_M_u32	310134272
IgnOnTimer_mS_M_u32	1324058112
IgnTimeOff_Sec_M_u32	1528236181
ManVehSpd_Kph_M_f32	69.4458008
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	68
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	195
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2897278464
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	180
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1007080960
PrevISDATBSI412MsgDLCError_Cnt_M_u08	27
PrevISDATBSI412MsgRxTime_MSec_M_u32	3135817216
PrevISDATBSI432MsgDLCError_Cnt_M_u08	16
PrevISDATBSI432MsgRxTime_MSec_M_u32	2906138112
PrevISDATDIRAMsgTxTime_MSec_M_u32	3827090944
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	54
PrevISDYN2CMMMsgRxTime_MSec_M_u32	651171328
PrevISDYNAASMsgDLCError_Cnt_M_u08	27
PrevISDYNAASMsgRxTime_MSec_M_u32	610944512
PrevISDYNABRMsgDLCError_Cnt_M_u08	168
PrevISDYNABRMsgRxTime_MSec_M_u32	2510521856
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	189
PrevISDYNCMM208MsgRxTime_MSec_M_u32	416237056
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	189
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1028859392
PrevISDYNVOLMsgDLCError_Cnt_M_u08	130
PrevISDYNVOLMsgRxTime_MSec_M_u32	2896545280
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1044067840
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	162.891006
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	59587
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	52032
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	3212
VitesseVehicleBVRampValidCount_Cnt_M_u16	25545
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	35643
VitesseVehicleBVSigValidCount_Cnt_M_u16	480
VitesseVehicleBV_Kph_M_f32	328.796204
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	54311

Name	Input Value
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	37125
VitesseVehiculeRoues_Kph_M_f32	641.386719
k_AASNTCEnableTimeout_mS_u16	25169
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	1484
k_AASNodeTimeout_mS_u16	15936
k_ABSNodeTimeout_mS_u16	16424
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	20593
k_ANGLEVOLANTSigValidThresh_Cnt_u16	8914
k_AngleVolantInvalidThresh_Cnt_u16	50129
k_AngleVolantValidThresh_Cnt_u16	17575
k_BSI552MsgTimeout_mS_u16	46788
k_BSINTCEnableTimeout_mS_u16	20438
k_BSINodeAbsentDiag_Cnt_str.Threshold	41712
k_BSINodeAbsentDiag_Cnt_str.PStep	46362
k_BSINodeAbsentDiag_Cnt_str.NStep	43480
k_BSINodeAbsentTimeout_mS_u16	62450
k_BSINodeTimeout_mS_u16	27243
k_BattOvHi_Volt_f32	12.4796
k_BattOvLo_Volt_f32	24.5499001
k_BattUvHi_Volt_f32	10.3021002
k_BattUvLo_Volt_f32	17.1543007
k_CAVNTCEnableTimeout_mS_u16	4045
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	59496
k_CAVNodeTimeout_mS_u16	54573
k_CMM388MsgTimeout_mS_u16	17869
k_CMM388NTCEnableTimeout_mS_u16	16553
k_CMMNTCEnableTimeout_mS_u16	54442
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	16865
k_CONSANGLECPKMax_HwDeg_f32	334.974701
k_CONSANGLECPKMin_HwDeg_f32	-223.016098
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	1831
k_CONSANGLECPKSigValidThresh_Cnt_u16	1029
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	27254
k_CPKVehicleSpeedValidThresh_Cnt_u16	3503
k_CityParkInputInvalidThresh_Cnt_u16	25995
k_CityParkInputValidThresh_Cnt_u16	21213
k_ComputerRazGCTSigValidThresh_Cnt_u16	28040
k_CptTemporelSigValidThresh_Cnt_u16	57442
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	43528
k_DMDFCTCPKSigValidThresh_Cnt_u16	37758
k_DMDFCTCPKValidCount_Cnt_u16	32497
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	47546
k_DMDRELAXECPKSigValidThresh_Cnt_u16	35783
k_DMDRelaxeConsistentThresh_Cnt_u16	41469
k_DateValidThresh_Cnt_u16	6534
k_DefaultVehSpd_Kph_f32	174.204407
k_DiagMuxOnAbsentTimeout_mS_u16	49480
k_EMNodeTimeout_mS_u16	30
k_ESPNTCEnableTimeout_mS_u16	29910
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	37673
k_EtatMTSigInvalidThresh_Cnt_u16	41396
k_EtatMTSigValidThresh_Cnt_u16	45730
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	29553
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	35043
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	18598
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	39807
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	27033
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	1208
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	50219
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	52748
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	55106

Name	Input Value
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	50214
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	58831
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	47771
k_ISDATDIRASentDiag_Cnt_str.Threshold	625
k_ISDATDIRASentDiag_Cnt_str.PStep	48276
k_ISDATDIRASentDiag_Cnt_str.NStep	58314
k_ISDATDIRASentTimeout_mS_u16	11441
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	19072
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	11066
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10050
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	59349
k_ISDYNAASChkSumValidThresh_Cnt_u16	65411
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	51478
k_ISDYNAASMsgCountValidThresh_Cnt_u16	54620
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	45049
k_ISDYNAASMsgLenValidThresh_Cnt_u16	25956
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	12826
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	15734
k_ISDYNABRChkSumValidThresh_Cnt_u16	32108
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	14249
k_ISDYNABRMsgCountValidThresh_Cnt_u16	50382
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	3578
k_ISDYNABRMsgLenValidThresh_Cnt_u16	9499
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	34829
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	45031
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	48029
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	15103
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	8434
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	17111
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	20831
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	39015
k_ISDYNVOLChkSumValidThresh_Cnt_u16	28721
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	35208
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	23207
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	15091
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	63108
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	1324
k_IgnOnTimeout_mS_u16	17475
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	188.406097
k_PowerCutVehSpdLowThresh_Kph_f32	208.976395
k_PowerCutVehSpdLowTimeout_mS_u16	65309
k_VBattMaxAAS_Volt_f32	12.1468
k_VBattMaxBSI_Volt_f32	20.8237991
k_VBattMaxCAV_Volt_f32	11.6148996
k_VBattMaxCMM388_Volt_f32	29.5433006
k_VBattMaxCMM_Volt_f32	24.3652992
k_VBattMaxESP_Volt_f32	10.2580004
k_VBattMinAAS_Volt_f32	18.9937
k_VBattMinBSI_Volt_f32	10.2580004
k_VBattMinCAV_Volt_f32	20.7035007
k_VBattMinCMM388_Volt_f32	8.23820019
k_VBattMinCMM_Volt_f32	10.6436005
k_VBattMinESP_Volt_f32	24.3652992
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	55626
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	41539
k_VitesseVehicleBVRampValidThresh_Cnt_u16	25329
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	61045
k_VitesseVehicleBVSigValidThresh_Cnt_u16	32094
k_VitesseVehicleBVSpeedPassThresh_kph_f32	521.672302
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	11258
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	55735
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3552404992
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	54541
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	433233920
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	189
target_SrlComInput_Per1_Batt_Volt_f32.value	17.4605007

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	981554688
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	70
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.672821522
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1057326592
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	589211136
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	509440
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	54
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3720406528
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3293185536
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	197
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3148031488
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3419162112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	44
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	62
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	114
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	195
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	205
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	218
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	146
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4243187200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	4
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	57
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	71
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	175
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	193
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	54
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1061193216
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	651798016
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	199
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3343042048
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	187
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	231
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2259211776
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2009
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.494737864
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	856156
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	239.042099
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	35085

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	433233920	433233920	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	37581	37581	✔
AASNodeAbsentTimer_mS_M_u32	3419162112	3419162112	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	11068	11068	✔
AngleVolantMsgTimer_mS_M_u32	433233920	433233920	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1252451840	1252451840	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	3552404992	3552404992	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	433233920	433233920	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1891800576	1891800576	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3720406528	3720406528	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	433233920	433233920	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	63738	63738	✔
CAVNodeAbsentTimer_mS_M_u32	3343042048	3343042048	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	433233920	433233920	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3454912000	3454912000	✔
CMMNTCsEnabled_Cnt_M_lgc	1	1	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	39674	39674	✔
CMMNodeAbsentTimer_mS_M_u32	3148031488	3148031488	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	15522	15522	✔
CONSANGLECPK_HwDeg_M_f32	-720.83313	-720.83313 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	15522	15522	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3016635904	3016635904	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	64180	64180	✔
CityParkInputConsistentCount_Cnt_M_u16	21213	21213	✔
CityParkInputInvalidCount_Cnt_M_u16	17577	17577	✔
CityParkInputMsgTimer_mS_M_u32	433233920	433233920	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3799459328	3799459328	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1151354368	1151354368	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	433233920	433233920	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	433233920	433233920	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1891800576	1891800576	✔
ESPNTCEnableTimer_mS_M_u32	433233920	433233920	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	433233920	433233920	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	8976	8976	✔
ElecIntTimer_mS_M_u32[1]	15236	15236	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	433233920	433233920	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	10775	10775	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	40931	40931	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1057326592	1057326592	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	499	499	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	865793536	865793536	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	24725	24725	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	509440	509440	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	433233920	433233920	✔
ISDATDIRASentFltAcc_Cnt_M_u16	625	625	✔
ISDATDIRASentTimer_mS_M_u32	433233920	433233920	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	34448	34448	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3148031488	3148031488	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	44401	44401	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1061193216	1061193216	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	433233920	433233920	✔
IgnOnTimer_mS_M_u32	1324058112	1324058112	✔
IgnTimeOff_Sec_M_u32	1528236181	1528236181	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	239	239	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1057326592	1057326592	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	186	186	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	589211136	589211136	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	121	121	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	509440	509440	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	54	54	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3720406528	3720406528	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3827090944	3827090944	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	197	197	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3148031488	3148031488	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	168	168	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3419162112	3419162112	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	146	146	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4243187200	4243187200	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	54	54	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1061193216	1061193216	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	651798016	651798016	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	199	199	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3343042048	3343042048	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2259211776	2259211776	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	162.891006	162.891006	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	328.796204	328.796204	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	641.386719	641.386719	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	15522	15522	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1528236181	1528236181	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-720.83313	-720.83313 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	174.204407	174.204407	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.451 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1389961472
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	36237
AASNodeAbsentTimer_mS_M_u32	2294108416
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	11808
ANGLEVOLANTSigValidCount_Cnt_M_u16	10799
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	47174
AngleVolantMsgTimer_mS_M_u32	1389961472
AngleVolantValidCount_Cnt_M_u16	4937
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2260865280
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1702793472
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2670149888
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1596915968
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	34299
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2909126912
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	21895
CAVNodeAbsentTimer_mS_M_u32	235892992
CDD_SrlComVehSpd_Kph_G_f32	457.842987
CMM388NTCEnableTimer_mS_M_u32	2191962368
CMM388NTCsEnabled_Cnt_M_lgc	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CMMNTCEnableTimer_mS_M_u32	812478720
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	19016
CMMNodeAbsentTimer_mS_M_u32	1901134080
CONSANGLECPKSigInvalidCount_Cnt_M_u16	46336
CONSANGLECPKSigValidCount_Cnt_M_u16	7200
CONSANGLECPK_Cnt_M_u16	65231
CONSANGLECPK_HwDeg_M_f32	-157.403305
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	65231
CPKVehicleSpeedMsgTimer_mS_M_u32	3431735552
CPKVehicleSpeedValidCount_Cnt_M_u16	62594
CityParkInputConsistentCount_Cnt_M_u16	13789
CityParkInputInvalidCount_Cnt_M_u16	5505
CityParkInputMsgTimer_mS_M_u32	1057326592
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1347506432
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	20001
ComputerRazGCTSigInvalidTimer_mS_M_u32	3059085568
ComputerRazGCTSigValidCount_Cnt_M_u16	1518
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	7917
DMDFCTCPKSigValidCount_Cnt_M_u16	35909
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	43626
DMDRELAXECPKSigValidCount_Cnt_M_u16	10745
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	17593
DateInvalidTimer_mS_M_u32	4294967295
DiagMuxOnAbsentTimer_mS_M_u32	309321984
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1596915968
ESPNTCEnableTimer_mS_M_u32	332026112
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	22180
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	5
ElecIntTimer_mS_M_u32[1]	57
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3499081984
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	41456
EtatMTSigValidCount_Cnt_M_u16	18428
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	36682
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	63978
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	41123
ISDAT4V2BSI552MsgTimer_mS_M_u32	2145714432
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	16350
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	18066
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	18428
ISDATBSI3F2MsgTimer_mS_M_u32	1881530624
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	31992
ISDATBSI412MsgLenValidCount_Cnt_M_u16	27
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	41456
ISDATBSI412MsgTimer_mS_M_u32	2123309312
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	57308
ISDATBSI432MsgLenValidCount_Cnt_M_u16	45880
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	1332
ISDATDIRASentFltAcc_Cnt_M_u16	22168
ISDATDIRASentTimer_mS_M_u32	3431735552
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	22789
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	4937
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	49736
ISDYN2CMMMsgTimer_mS_M_u32	2288800000
ISDYNAASChkSumInvalidCount_Cnt_M_u16	42455
ISDYNAASChkSumValidCount_Cnt_M_u16	9351
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	33956
ISDYNAASMsgCount_Cnt_M_u08	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	16246
ISDYNAASMsgLenValidCount_Cnt_M_u16	56638
ISDYNAASMsgTimeValidCount_Cnt_M_u16	42455
ISDYNAASMsgTimer_mS_M_u32	3440554240
ISDYNABRChkSumInvalidCount_Cnt_M_u16	40694
ISDYNABRChkSumValidCount_Cnt_M_u16	55725
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	26546
ISDYNABRMsgCountValidCount_Cnt_M_u16	9378
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	24027
ISDYNABRMsgLenValidCount_Cnt_M_u16	17211
ISDYNABRMsgTimeValidCount_Cnt_M_u16	65231
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	21501
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	57335
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	18428
ISDYNCMM208MsgTimer_mS_M_u32	2383614208
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	21501
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	57335
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	23039
ISDYNCMM388MsgTimer_mS_M_u32	3873452288
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	27318
ISDYNVOLChkSumValidCount_Cnt_M_u16	52822
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	64419
ISDYNVOLMsgCountValidCount_Cnt_M_u16	42363
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	6089
ISDYNVOLMsgLenValidCount_Cnt_M_u16	56393
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	19016
ISDYNVOLMsgTimer_mS_M_u32	3166826752
IgnOnTimer_mS_M_u32	3564384512
IgnTimeOff_Sec_M_u32	2289012931
ManVehSpd_Kph_M_f32	468.420685
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	69
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	143
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3705921792
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	78
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1583497472
PrevISDATBSI412MsgDLCError_Cnt_M_u08	193
PrevISDATBSI412MsgRxTime_MSec_M_u32	360476928
PrevISDATBSI432MsgDLCError_Cnt_M_u08	198
PrevISDATBSI432MsgRxTime_MSec_M_u32	873353472
PrevISDATDIRAMsgTxTime_MSec_M_u32	1776316672
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	63
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1392935168
PrevISDYNAASMsgDLCError_Cnt_M_u08	81
PrevISDYNAASMsgRxTime_MSec_M_u32	3203920128
PrevISDYNABRMsgDLCError_Cnt_M_u08	111
PrevISDYNABRMsgRxTime_MSec_M_u32	3763089664
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	209
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3049844992
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	241
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2948419840
PrevISDYNVOLMsgDLCError_Cnt_M_u08	40
PrevISDYNVOLMsgRxTime_MSec_M_u32	1950707968
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	558178560
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	19.5135994
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	59948
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	17524
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	58065
VitesseVehicleBVRampValidCount_Cnt_M_u16	57049
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	14917
VitesseVehicleBVSigValidCount_Cnt_M_u16	30740
VitesseVehicleBV_Kph_M_f32	196.084702
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	23039
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	42278
VitesseVehiculeRoues_Kph_M_f32	349.222107
k_AASNTCEnableTimeout_mS_u16	2498
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	39184
k_AASNodeTimeout_mS_u16	60276
k_ABSNodeTimeout_mS_u16	26366
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	50659
k_ANGLEVOLANTSigValidThresh_Cnt_u16	57471
k_AngleVolantInvalidThresh_Cnt_u16	47490
k_AngleVolantValidThresh_Cnt_u16	5505
k_BSI552MsgTimeout_mS_u16	61417
k_BSINTCEnableTimeout_mS_u16	39860
k_BSINodeAbsentDiag_Cnt_str.Threshold	51965
k_BSINodeAbsentDiag_Cnt_str.PStep	37055
k_BSINodeAbsentDiag_Cnt_str.NStep	65221
k_BSINodeAbsentTimeout_mS_u16	15902
k_BSINodeTimeout_mS_u16	1332
k_BattOvHi_Volt_f32	0.0395000018
k_BattOvLo_Volt_f32	1.75580001
k_BattUvHi_Volt_f32	16.2838993
k_BattUvLo_Volt_f32	26.4181995
k_CAVNTCEnableTimeout_mS_u16	52239
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	48957
k_CAVNodeTimeout_mS_u16	38764
k_CMM388MsgTimeout_mS_u16	29837
k_CMM388NTCEnableTimeout_mS_u16	62457
k_CMMNTCEnableTimeout_mS_u16	42934
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	658
k_CONSANGLECPKMax_HwDeg_f32	563.067322
k_CONSANGLECPKMin_HwDeg_f32	-779.996216
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	49407
k_CONSANGLECPKSigValidThresh_Cnt_u16	19494
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	48850
k_CPKVehicleSpeedValidThresh_Cnt_u16	41383
k_CityParkInputInvalidThresh_Cnt_u16	58580
k_CityParkInputValidThresh_Cnt_u16	13789
k_ComputerRazGCTSigValidThresh_Cnt_u16	54556
k_CptTemporelSigValidThresh_Cnt_u16	61008
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	17627
k_DMDFCTCPKSigValidThresh_Cnt_u16	27195
k_DMDFCTCPKValidCount_Cnt_u16	46883
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	49736
k_DMDRELAXECPKSigValidThresh_Cnt_u16	36320
k_DMDRelaxeConsistentThresh_Cnt_u16	41790
k_DateValidThresh_Cnt_u16	41123
k_DefaultVehSpd_Kph_f32	157.850601
k_DiagMuxOnAbsentTimeout_mS_u16	35037
k_EMNodeTimeout_mS_u16	6809
k_ESPNTCEnableTimeout_mS_u16	20979

Name	Input Value
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	11962
k_EtatMTSigInvalidThresh_Cnt_u16	5209
k_EtatMTSigValidThresh_Cnt_u16	41808
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	20449
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	57677
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	47234
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	59191
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	61099
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	8332
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	53941
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	18129
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	46448
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	30787
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	50439
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	22501
k_ISDATDIRASentDiag_Cnt_str.Threshold	64711
k_ISDATDIRASentDiag_Cnt_str.PStep	35441
k_ISDATDIRASentDiag_Cnt_str.NStep	35487
k_ISDATDIRASentTimeout_mS_u16	42850
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	31798
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	47174
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	60079
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	1526
k_ISDYNAASChkSumValidThresh_Cnt_u16	32941
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	20146
k_ISDYNAASMsgCountValidThresh_Cnt_u16	19362
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	15754
k_ISDYNAASMsgLenValidThresh_Cnt_u16	1544
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	53927
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	49809
k_ISDYNABRChkSumValidThresh_Cnt_u16	58481
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	27899
k_ISDYNABRMsgCountValidThresh_Cnt_u16	26442
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	61768
k_ISDYNABRMsgLenValidThresh_Cnt_u16	15780
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	55693
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	9408
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	53213
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	45367
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	5408
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	20783
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	53081
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	57727
k_ISDYNVOLChkSumValidThresh_Cnt_u16	35810
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	1117
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	65345
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	57180
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	65128
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	62897
k_IgnOnTimeout_mS_u16	19947
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	73.7455978
k_PowerCutVehSpdLowThresh_Kph_f32	212.034698
k_PowerCutVehSpdLowTimeout_mS_u16	25438
k_VBattMaxAAS_Volt_f32	25.7521992
k_VBattMaxBSI_Volt_f32	24.2621994
k_VBattMaxCAV_Volt_f32	6.04610014
k_VBattMaxCMM388_Volt_f32	5.17710018
k_VBattMaxCMM_Volt_f32	12.4286003
k_VBattMaxESP_Volt_f32	25.1989002
k_VBattMinAAS_Volt_f32	21.9372005
k_VBattMinBSI_Volt_f32	9.19890022
k_VBattMinCAV_Volt_f32	14.0683002
k_VBattMinCMM388_Volt_f32	1.25530005
k_VBattMinCMM_Volt_f32	29.0695
k_VBattMinESP_Volt_f32	12.4286003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	30680
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	3756
k_VitesseVehicleBVRampValidThresh_Cnt_u16	25251
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	62806

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VitesseVehicleBVSigValidThresh_Cnt_u16	64090
k_VitesseVehicleBVSpeedPassThresh_kph_f32	394.937195
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	48263
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	46351
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1702793472
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	41358
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2292638464
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	241
target_SrlComInput_Per1_Batt_Volt_f32.value	12.0515003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1827848448
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	22
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.274964303
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3961925888
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	56
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2354761984
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	230
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2183098624
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3044282624
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	240693504
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1959612672
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3503419648
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	34
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	140
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	189
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	197
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1006178560
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	3
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	29
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	59
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	130
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	222
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2541039872
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	757715200
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3631116544
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	71
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	135
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	142
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	177
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	226

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	234
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2256290048
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2045
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.149197087
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	66513
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	129.087708
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	45390

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2292638464	2292638464	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2260865280	2260865280	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	1702793472	1702793472	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1596915968	1596915968	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	19016	19016	✔
CMMNodeAbsentTimer_mS_M_u32	1959612672	1959612672	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	65231	65231	✔
CONSANGLECPK_HwDeg_M_f32	-157.403305	-157.403305 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2292638464	2292638464	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2292638464	2292638464	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2292638464	2292638464	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2292638464	2292638464	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2292638464	2292638464	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2292638464	2292638464	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2292638464	2292638464	✔
ESPNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2292638464	2292638464	✔
ElecIntTimer_mS_M_u32[1]	57	57	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2292638464	2292638464	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3961925888	3961925888	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2354761984	2354761984	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1	1	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2183098624	2183098624	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDATDIRASentFltAcc_Cnt_M_u16	64711	64711	✔
ISDATDIRASentTimer_mS_M_u32	2292638464	2292638464	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2292638464	2292638464	✔
IgnOnTimer_mS_M_u32	3564384512	3564384512	✔
IgnTimeOff_Sec_M_u32	2289012931	2289012931	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	235	235	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3961925888	3961925888	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	56	56	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2354761984	2354761984	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	230	230	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2183098624	2183098624	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	221	221	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3044282624	3044282624	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1776316672	1776316672	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1959612672	1959612672	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	141	141	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3503419648	3503419648	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	173	173	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1006178560	1006178560	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2541039872	2541039872	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	757715200	757715200	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	169	169	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3631116544	3631116544	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2256290048	2256290048	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	19.5135994	19.5135994	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	196.084702	196.084702	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	349.222107	349.222107	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	65231	65231	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2289012931	2289012931	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-157.403305	-157.403305 ± 0.0125	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	157.850601	157.850601	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.452 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	677501952
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	8700
AASNodeAbsentTimer_mS_M_u32	1431456768
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	6172
ANGLEVOLANTSigValidCount_Cnt_M_u16	64210
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	49217
AngleVolantMsgTimer_mS_M_u32	677501952
AngleVolantValidCount_Cnt_M_u16	17231
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	4135062528
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	4004268288
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1842707456
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	4139924480
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	53467
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3090283520

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	45483
CAVNodeAbsentTimer_mS_M_u32	3346656256
CDD_SrlComVehSpd_Kph_G_f32	17.0296001
CMM388NTCEnableTimer_mS_M_u32	2092968960
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3330272256
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	8122
CMMNodeAbsentTimer_mS_M_u32	305937408
CONSANGLECPKSigInvalidCount_Cnt_M_u16	59630
CONSANGLECPKSigValidCount_Cnt_M_u16	31092
CONSANGLECPK_Cnt_M_u16	27767
CONSANGLECPK_HwDeg_M_f32	-175.470505
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	27767
CPKVehicleSpeedMsgTimer_mS_M_u32	1310252032
CPKVehicleSpeedValidCount_Cnt_M_u16	4045
CityParkInputConsistentCount_Cnt_M_u16	47699
CityParkInputInvalidCount_Cnt_M_u16	53154
CityParkInputMsgTimer_mS_M_u32	2203606272
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2371243008
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	57088
ComputerRazGCTSigInvalidTimer_mS_M_u32	1933470720
ComputerRazGCTSigValidCount_Cnt_M_u16	784
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	5278
DMDFCTCPKSigValidCount_Cnt_M_u16	57084
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	25246
DMDRELAXECPKSigValidCount_Cnt_M_u16	33492
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	2099
DateInvalidTimer_mS_M_u32	4004268288
DiagMuxOnAbsentTimer_mS_M_u32	1068604416
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4139924480
ESPNTCEnableTimer_mS_M_u32	1432046592
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	33996
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	65535
EffacDefaultDiagTimer_mS_M_u32[1]	95535
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	9900
ElecIntTimer_mS_M_u32[1]	11002
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1611922432
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	46269
EtatMTSigValidCount_Cnt_M_u16	37311
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	14704
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	34678
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	59394
ISDAT4V2BSI552MsgTimer_mS_M_u32	88095744
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	9429
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	58719
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	37311
ISDATBSI3F2MsgTimer_mS_M_u32	3341786112
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	11382
ISDATBSI412MsgLenValidCount_Cnt_M_u16	4271
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	46269
ISDATBSI412MsgTimer_mS_M_u32	1709169664
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	3518
ISDATBSI432MsgLenValidCount_Cnt_M_u16	44496
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	14804
ISDATDIRASentFltAcc_Cnt_M_u16	22376
ISDATDIRASentTimer_mS_M_u32	1310252032
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	13941
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	17231

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	13021
ISDYN2CMMMsgTimer_mS_M_u32	559238144
ISDYNAASChkSumInvalidCount_Cnt_M_u16	55422
ISDYNAASChkSumValidCount_Cnt_M_u16	18772
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	6030
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	39662
ISDYNAASMsgLenValidCount_Cnt_M_u16	11516
ISDYNAASMsgTimeValidCount_Cnt_M_u16	55422
ISDYNAASMsgTimer_mS_M_u32	4005309440
ISDYNABRChkSumInvalidCount_Cnt_M_u16	28925
ISDYNABRChkSumValidCount_Cnt_M_u16	48443
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	45885
ISDYNABRMsgCountValidCount_Cnt_M_u16	1363
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	40621
ISDYNABRMsgLenValidCount_Cnt_M_u16	20595
ISDYNABRMsgTimeValidCount_Cnt_M_u16	27767
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	1082
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	2441
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	37311
ISDYNCMM208MsgTimer_mS_M_u32	2775911424
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	1082
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	2441
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	32717
ISDYNCMM388MsgTimer_mS_M_u32	3816532992
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	59500
ISDYNVOLChkSumValidCount_Cnt_M_u16	47986
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	12060
ISDYNVOLMsgCountValidCount_Cnt_M_u16	31738
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	61709
ISDYNVOLMsgLenValidCount_Cnt_M_u16	21363
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	8122
ISDYNVOLMsgTimer_mS_M_u32	4047137792
IgnOnTimer_mS_M_u32	1233103872
IgnTimeOff_Sec_M_u32	3075782274
ManVehSpd_Kph_M_f32	648.9776
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	67
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	3
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	21
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	18193408
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	192
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	980712448
PrevISDATBSI412MsgDLCError_Cnt_M_u08	35
PrevISDATBSI412MsgRxTime_MSec_M_u32	1281551360
PrevISDATBSI432MsgDLCError_Cnt_M_u08	80
PrevISDATBSI432MsgRxTime_MSec_M_u32	3629075456
PrevISDATDIRAMsgTxTime_MSec_M_u32	821488640
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	243
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3234053120
PrevISDYNAASMsgDLCError_Cnt_M_u08	198
PrevISDYNAASMsgRxTime_MSec_M_u32	1127771136
PrevISDYNABRMsgDLCError_Cnt_M_u08	67
PrevISDYNABRMsgRxTime_MSec_M_u32	1484237824
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	204
PrevISDYNCMM208MsgRxTime_MSec_M_u32	733309952
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	121
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1884441600
PrevISDYNVOLMsgDLCError_Cnt_M_u08	248
PrevISDYNVOLMsgRxTime_MSec_M_u32	2910317568
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3462257664
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	379.4758
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	27500
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	65530
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	47405
VitesseVehicleBVRampValidCount_Cnt_M_u16	52347
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	62301
VitesseVehicleBVSigValidCount_Cnt_M_u16	29907
VitesseVehicleBV_Kph_M_f32	58.9146996
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	32717
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	62395
VitesseVehiculeRoues_Kph_M_f32	417.543915
k_AASNTCEnableTimeout_mS_u16	19054
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	35722
k_AASNodeTimeout_mS_u16	39674
k_ABSNodeTimeout_mS_u16	30043
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	45369
k_ANGLEVOLANTSigValidThresh_Cnt_u16	34699
k_AngleVolantInvalidThresh_Cnt_u16	47698
k_AngleVolantValidThresh_Cnt_u16	53154
k_BSI552MsgTimeout_mS_u16	13634
k_BSINTCEnableTimeout_mS_u16	3254
k_BSINodeAbsentDiag_Cnt_str.Threshold	14579
k_BSINodeAbsentDiag_Cnt_str.PStep	15025
k_BSINodeAbsentDiag_Cnt_str.NStep	42850
k_BSINodeAbsentTimeout_mS_u16	49465
k_BSINodeTimeout_mS_u16	14804
k_BattOvHi_Volt_f32	10.5635004
k_BattOvLo_Volt_f32	26.7511005
k_BattUvHi_Volt_f32	21.8743
k_BattUvLo_Volt_f32	8.05720043
k_CAVNTCEnableTimeout_mS_u16	44824
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	21801
k_CAVNodeTimeout_mS_u16	4842
k_CMM388MsgTimeout_mS_u16	64764
k_CMM388NTCEnableTimeout_mS_u16	32760
k_CMMNTCEnableTimeout_mS_u16	24525
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	64695
k_CONSANGLECPKMax_HwDeg_f32	191.476593
k_CONSANGLECPKMin_HwDeg_f32	-556.228821
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	56013
k_CONSANGLECPKSigValidThresh_Cnt_u16	36539
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	30464
k_CPKVehicleSpeedValidThresh_Cnt_u16	14713
k_CityParkInputInvalidThresh_Cnt_u16	52611
k_CityParkInputValidThresh_Cnt_u16	47699
k_ComputerRazGCTSigValidThresh_Cnt_u16	23867
k_CptTemporelSigValidThresh_Cnt_u16	48709
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	31149
k_DMDFCTCPKSigValidThresh_Cnt_u16	27507
k_DMDFCTCPKValidCount_Cnt_u16	15075
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	13021
k_DMDRELAXECPKSigValidThresh_Cnt_u16	32379

Name	Input Value
k_DMDRelaxeConsistentThresh_Cnt_u16	29825
k_DateValidThresh_Cnt_u16	59394
k_DefaultVehSpd_Kph_f32	167.585907
k_DiagMuxOnAbsentTimeout_mS_u16	39277
k_EMNodeTimeout_mS_u16	59539
k_ESPNTCEnableTimeout_mS_u16	60839
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	50623
k_EtatMTSigInvalidThresh_Cnt_u16	51364
k_EtatMTSigValidThresh_Cnt_u16	21538
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	14563
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	24005
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	51732
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	49978
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	62852
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	4218
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	4515
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	17269
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	15298
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	12507
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	24117
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	1370
k_ISDATDIRASentDiag_Cnt_str.Threshold	42873
k_ISDATDIRASentDiag_Cnt_str.PStep	21557
k_ISDATDIRASentDiag_Cnt_str.NStep	16998
k_ISDATDIRASentTimeout_mS_u16	51449
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	36183
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	49217
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	44979
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	52221
k_ISDYNAASChkSumValidThresh_Cnt_u16	22587
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	36413
k_ISDYNAASMsgCountValidThresh_Cnt_u16	8275
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	46081
k_ISDYNAASMsgLenValidThresh_Cnt_u16	43518
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	40595
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	41259
k_ISDYNABRChkSumValidThresh_Cnt_u16	54641
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	43995
k_ISDYNABRMsgCountValidThresh_Cnt_u16	12241
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	47802
k_ISDYNABRMsgLenValidThresh_Cnt_u16	24524
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	33496
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	6768
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	18295
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	48001
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	62236
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	5586
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	62618
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	27761
k_ISDYNVOLChkSumValidThresh_Cnt_u16	59114
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	27153
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	64319
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	7609
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	65467
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	1016
k_IgnOnTimeout_mS_u16	22637
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	42.8305016
k_PowerCutVehSpdLowThresh_Kph_f32	107.338303
k_PowerCutVehSpdLowTimeout_mS_u16	31706
k_VBattMaxAAS_Volt_f32	18.5667992
k_VBattMaxBSI_Volt_f32	15.3116999
k_VBattMaxCAV_Volt_f32	8.37419987
k_VBattMaxCMM388_Volt_f32	15.5081997
k_VBattMaxCMM_Volt_f32	30.2082005
k_VBattMaxESP_Volt_f32	9.34060001
k_VBattMinAAS_Volt_f32	9.56649971
k_VBattMinBSI_Volt_f32	9.34060001
k_VBattMinCAV_Volt_f32	22.9979992
k_VBattMinCMM388_Volt_f32	24.0049

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_VBattMinCMM_Volt_f32	24.4225006
k_VBattMinESP_Volt_f32	30.2082005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	21585
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	41595
k_VitesseVehicleBVRampValidThresh_Cnt_u16	35356
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	54898
k_VitesseVehicleBVSigValidThresh_Cnt_u16	55052
k_VitesseVehicleBVSpeedPassThresh_kph_f32	599.80542
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	3243
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	25209
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4004268288
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	48714
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3486545408
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	121
target_SrlComInput_Per1_Batt_Volt_f32.value	26.0520992
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3535469568
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	28
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.959726751
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	52
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2605296640
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	145
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	262261760
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	79
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3393842176
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	56
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2470579200
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	847916032
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1881295872
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	336227328
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	25
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	63
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	167
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	250
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	197
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	425921536
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	48
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	218
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3932990464
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	642042880
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	82
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1751968768

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	43
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	204
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3834018816
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1235
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.706097603
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	124304
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	243.956696
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	6118

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3486545408	3486545408	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	3486545408	3486545408	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	14579	14579	✔
BSINodeAbsentTimer_mS_M_u32	3486545408	3486545408	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3486545408	3486545408	✔
CDD_SrlComVehSpd_Kph_G_f32	648.9776	648.9776	✔
CMM388NTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3486545408	3486545408	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	27767	27767	✔
CONSANGLECPK_HwDeg_M_f32	-175.470505	-175.470505 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3486545408	3486545408	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	3486545408	3486545408	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3486545408	3486545408	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3486545408	3486545408	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3486545408	3486545408	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3486545408	3486545408	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3486545408	3486545408	✔
ESPNTCEnableTimer_mS_M_u32	3486545408	3486545408	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3486545408	3486545408	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	65535	65535	✔
EffacDefaultDiagTimer_mS_M_u32[1]	95535	95535	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	9900	9900	✔
ElecIntTimer_mS_M_u32[1]	11002	11002	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3486545408	3486545408	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	59394	59394	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	37311	37311	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	46269	46269	✔
ISDATBSI412MsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	14804	14804	✔
ISDATBSI432MsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDATDIRASentFltAcc_Cnt_M_u16	42873	42873	✔
ISDATDIRASentTimer_mS_M_u32	3486545408	3486545408	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	13021	13021	✔
ISDYN2CMMMsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	55422	55422	✔
ISDYNAASMsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	27767	27767	✔
ISDYNABRMsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	37311	37311	✔
ISDYNCMM208MsgTimer_mS_M_u32	3486545408	3486545408	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	32717	32717	✔
ISDYNCMM388MsgTimer_mS_M_u32	3486545408	3486545408	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	8122	8122	✔
ISDYNVOLMsgTimer_mS_M_u32	3486545408	3486545408	✔
IgnOnTimer_mS_M_u32	1233103872	1233103872	✔
IgnTimeOff_Sec_M_u32	3075782274	3075782274	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	52	52	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2605296640	2605296640	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	145	145	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	262261760	262261760	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	79	79	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3393842176	3393842176	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	56	56	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2470579200	2470579200	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	821488640	821488640	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	169	169	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1881295872	1881295872	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	192	192	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	336227328	336227328	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	197	197	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	425921536	425921536	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	168	168	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3932990464	3932990464	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	108	108	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	642042880	642042880	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	82	82	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1751968768	1751968768	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3834018816	3834018816	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	379.4758	379.4758	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	58.9146996	58.9146996	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	417.543915	417.543915	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	27767	27767	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3075782274	3075782274	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-175.470505	-175.470505 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.453 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3035180800
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	21017
AASNodeAbsentTimer_mS_M_u32	3151486720
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	37304
ANGLEVOLANTSigValidCount_Cnt_M_u16	27990
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	52042
AngleVolantMsgTimer_mS_M_u32	3035180800
AngleVolantValidCount_Cnt_M_u16	41632
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2674302720
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	4066320128
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3138277120
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3276279552
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	9083
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3992506112
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	27018
CAVNodeAbsentTimer_mS_M_u32	199294720
CDD_SrlComVehSpd_Kph_G_f32	62.5083008
CMM388NTCEnableTimer_mS_M_u32	3574480640
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2798583552
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	21536
CMMNodeAbsentTimer_mS_M_u32	3638169344
CONSANGLECPKSigInvalidCount_Cnt_M_u16	38466
CONSANGLECPKSigValidCount_Cnt_M_u16	43121

Name	Input Value
CONSANGLECPK_Cnt_M_u16	39784
CONSANGLECPK_HwDeg_M_f32	304.674103
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	39784
CPKVehicleSpeedMsgTimer_mS_M_u32	3754176256
CPKVehicleSpeedValidCount_Cnt_M_u16	52239
CityParkInputConsistentCount_Cnt_M_u16	19860
CityParkInputInvalidCount_Cnt_M_u16	23206
CityParkInputMsgTimer_mS_M_u32	2605296640
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	600563456
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	11021
ComputerRazGCTSigInvalidTimer_mS_M_u32	3130228480
ComputerRazGCTSigValidCount_Cnt_M_u16	42845
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	31666
DMDFCTCPKSigValidCount_Cnt_M_u16	16472
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	14898
DMDRELAXECPKSigValidCount_Cnt_M_u16	23888
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	35955
DateInvalidTimer_mS_M_u32	4066320128
DiagMuxOnAbsentTimer_mS_M_u32	1576660736
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3276279552
ESPNTCEnableTimer_mS_M_u32	532471552
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	6314
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	2500
EffacDefaultDiagTimer_mS_M_u32[1]	3501
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	6454
ElecIntTimer_mS_M_u32[1]	8259
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4266839808
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	45590
EtatMTSigValidCount_Cnt_M_u16	52944
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	11452
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	1643
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	48454
ISDAT4V2BSI552MsgTimer_mS_M_u32	265162496
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	47949
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	19823
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	52944
ISDATBSI3F2MsgTimer_mS_M_u32	1065348864
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	30060
ISDATBSI412MsgLenValidCount_Cnt_M_u16	23678
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	45590
ISDATBSI412MsgTimer_mS_M_u32	1953443584
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	39444
ISDATBSI432MsgLenValidCount_Cnt_M_u16	44446
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	46351
ISDATDIRASentFltAcc_Cnt_M_u16	44115
ISDATDIRASentTimer_mS_M_u32	3754176256
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	46446
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	41632
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	56565
ISDYN2CMMMsgTimer_mS_M_u32	600760064
ISDYNAASChkSumInvalidCount_Cnt_M_u16	46739
ISDYNAASChkSumValidCount_Cnt_M_u16	26577
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	57827
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	31169
ISDYNAASMsgLenValidCount_Cnt_M_u16	42839
ISDYNAASMsgTimeValidCount_Cnt_M_u16	46739
ISDYNAASMsgTimer_mS_M_u32	1863991040
ISDYNABRChkSumInvalidCount_Cnt_M_u16	151
ISDYNABRChkSumValidCount_Cnt_M_u16	49053

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	57942
ISDYNABRMsgCountValidCount_Cnt_M_u16	61396
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	12549
ISDYNABRMsgLenValidCount_Cnt_M_u16	57204
ISDYNABRMsgTimeValidCount_Cnt_M_u16	39784
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	46326
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	10954
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	52944
ISDYNCMM208MsgTimer_mS_M_u32	3329203968
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	46326
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	10954
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	25894
ISDYNCMM388MsgTimer_mS_M_u32	4007378688
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	4040
ISDYNVOLChkSumValidCount_Cnt_M_u16	23159
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	42040
ISDYNVOLMsgCountValidCount_Cnt_M_u16	57694
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	6119
ISDYNVOLMsgLenValidCount_Cnt_M_u16	13429
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	21536
ISDYNVOLMsgTimer_mS_M_u32	815759104
IgnOnTimer_mS_M_u32	3436166912
IgnTimeOff_Sec_M_u32	807793209
ManVehSpd_Kph_M_f32	622.170776
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	68
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	134
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2848845568
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	180
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2435927808
PrevISDATBSI412MsgDLCError_Cnt_M_u08	99
PrevISDATBSI412MsgRxTime_MSec_M_u32	1629880064
PrevISDATBSI432MsgDLCError_Cnt_M_u08	247
PrevISDATBSI432MsgRxTime_MSec_M_u32	1726013184
PrevISDATDIRAMsgTxTime_MSec_M_u32	57278208
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	38
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1262718720
PrevISDYNAASMsgDLCError_Cnt_M_u08	111
PrevISDYNAASMsgRxTime_MSec_M_u32	2997190400
PrevISDYNABRMsgDLCError_Cnt_M_u08	70
PrevISDYNABRMsgRxTime_MSec_M_u32	2145894144
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	74
PrevISDYNCMM208MsgRxTime_MSec_M_u32	758021888
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	71
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1792532224
PrevISDYNVOLMsgDLCError_Cnt_M_u08	104
PrevISDYNVOLMsgRxTime_MSec_M_u32	3521576704
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3002412800
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	26.3393002
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	32839
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	42589
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1

Name	Input Value
VehSpdSync_Cnt_M_Igc	1
VehTimeValid_Cnt_M_Igc	1
VehicleSpeedValid_Cnt_M_Igc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	56068
VitesseVehicleBVRampValidCount_Cnt_M_u16	34010
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	17397
VitesseVehicleBVSigValidCount_Cnt_M_u16	17235
VitesseVehicleBV_Kph_M_f32	41.9701004
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	25894
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	27932
VitesseVehiculeRoues_Kph_M_f32	108.267899
k_AASNTCEnableTimeout_mS_u16	40323
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	30191
k_AASNodeTimeout_mS_u16	54621
k_ABSNodeTimeout_mS_u16	36219
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	23459
k_ANGLEVOLANTSigValidThresh_Cnt_u16	52333
k_AngleVolantInvalidThresh_Cnt_u16	4120
k_AngleVolantValidThresh_Cnt_u16	23206
k_BSI552MsgTimeout_mS_u16	33927
k_BSINTCEnableTimeout_mS_u16	32044
k_BSINodeAbsentDiag_Cnt_str.Threshold	37451
k_BSINodeAbsentDiag_Cnt_str.PStep	14162
k_BSINodeAbsentDiag_Cnt_str.NStep	27518
k_BSINodeAbsentTimeout_mS_u16	43106
k_BSINodeTimeout_mS_u16	46351
k_BattOvHi_Volt_f32	12.9091997
k_BattOvLo_Volt_f32	29.9493999
k_BattUvHi_Volt_f32	12.5558996
k_BattUvLo_Volt_f32	31.5
k_CAVNTCEnableTimeout_mS_u16	5188
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	63248
k_CAVNodeTimeout_mS_u16	2126
k_CMM388MsgTimeout_mS_u16	49433
k_CMM388NTCEnableTimeout_mS_u16	10277
k_CMMNTCEnableTimeout_mS_u16	60005
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	16936
k_CONSANGLECPKMax_HwDeg_f32	658.261902
k_CONSANGLECPKMin_HwDeg_f32	-207.181595
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	21542
k_CONSANGLECPKSigValidThresh_Cnt_u16	39964
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	55627
k_CPKVehicleSpeedValidThresh_Cnt_u16	6755
k_CityParkInputInvalidThresh_Cnt_u16	33541
k_CityParkInputValidThresh_Cnt_u16	19860
k_ComputerRazGCTSigValidThresh_Cnt_u16	10779
k_CptTemporelSigValidThresh_Cnt_u16	55997
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	40965
k_DMDFCTCPKSigValidThresh_Cnt_u16	36468
k_DMDFCTCPKValidCount_Cnt_u16	1379
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	56565
k_DMDRELAXECPKSigValidThresh_Cnt_u16	7643
k_DMDRelaxeConsistentThresh_Cnt_u16	54217
k_DateValidThresh_Cnt_u16	48454
k_DefaultVehSpd_Kph_f32	175.800003
k_DiagMuxOnAbsentTimeout_mS_u16	27782
k_EMNodeTimeout_mS_u16	27475
k_ESPNTCEnableTimeout_mS_u16	42390
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	1808
k_EtatMTSigInvalidThresh_Cnt_u16	21922
k_EtatMTSigValidThresh_Cnt_u16	22248

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	57250
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	42173
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	25169
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	46110
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	61696
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	55648
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	25189
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	49327
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	8200
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	56892
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	27118
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	52159
k_ISDATDIRASentDiag_Cnt_str.Threshold	14146
k_ISDATDIRASentDiag_Cnt_str.PStep	16332
k_ISDATDIRASentDiag_Cnt_str.NStep	21498
k_ISDATDIRASentTimeout_mS_u16	59555
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	26568
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	52042
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	36722
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	61335
k_ISDYNAASChkSumValidThresh_Cnt_u16	61085
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	20822
k_ISDYNAASMsgCountValidThresh_Cnt_u16	40660
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	18315
k_ISDYNAASMsgLenValidThresh_Cnt_u16	47185
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	42837
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	41355
k_ISDYNABRChkSumValidThresh_Cnt_u16	51322
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	37499
k_ISDYNABRMsgCountValidThresh_Cnt_u16	35417
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	33568
k_ISDYNABRMsgLenValidThresh_Cnt_u16	34730
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	27972
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	33595
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	26729
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	20424
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	184
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	7254
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	52158
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	24955
k_ISDYNVOLChkSumValidThresh_Cnt_u16	34253
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	48347
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	5521
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	26402
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	29916
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	49508
k_IgnOnTimeout_mS_u16	36231
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	232.566101
k_PowerCutVehSpdLowThresh_Kph_f32	175.042694
k_PowerCutVehSpdLowTimeout_mS_u16	47423
k_VBattMaxAAS_Volt_f32	28.9340992
k_VBattMaxBSI_Volt_f32	6.53719997
k_VBattMaxCAV_Volt_f32	16.8115997
k_VBattMaxCMM388_Volt_f32	8.6225996
k_VBattMaxCMM_Volt_f32	3.93540001
k_VBattMaxESP_Volt_f32	15.5881004
k_VBattMinAAS_Volt_f32	2.79340005
k_VBattMinBSI_Volt_f32	15.5881004
k_VBattMinCAV_Volt_f32	20.8610992
k_VBattMinCMM388_Volt_f32	26.9283009
k_VBattMinCMM_Volt_f32	25.9009991
k_VBattMinESP_Volt_f32	3.93540001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	31450
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	58397
k_VitesseVehicleBVRampValidThresh_Cnt_u16	37688
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	2423
k_VitesseVehicleBVSigValidThresh_Cnt_u16	7017
k_VitesseVehicleBVSpeedPassThresh_kph_f32	401.778015
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	22666
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	15072
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	4066320128

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	45551
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1367695616
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	71
target_SrlComInput_Per1_Batt_Volt_f32.value	15.0383997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	39702272
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	146
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.465838909
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2138160896
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	122
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	719937280
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	231
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1131478784
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1896390400
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1538277120
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2875711232
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	137330432
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	9
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	55
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	147
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	172
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	50
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2728763136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	26
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	34
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	127
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	153
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	23
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3725115136
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	855662336
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3037200128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	45
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	115
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	140
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	189
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1526419200
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	744
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.954785168
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	348980
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	50.4375
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	58073

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	52042	52042	✔
AngleVolantMsgTimer_mS_M_u32	1367695616	1367695616	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	39784	39784	✔
CONSANGLECPK_HwDeg_M_f32	304.674103	304.674103 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	39784	39784	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3754176256	3754176256	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	52239	52239	✔
CityParkInputConsistentCount_Cnt_M_u16	19860	19860	✔
CityParkInputInvalidCount_Cnt_M_u16	23208	23208	✔
CityParkInputMsgTimer_mS_M_u32	1367695616	1367695616	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1367695616	1367695616	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1367695616	1367695616	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1367695616	1367695616	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1367695616	1367695616	✔
DiagOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DmdDelestDATimer_mS_M_u32	1367695616	1367695616	✔
ESPNTCEnableTimer_mS_M_u32	1367695616	1367695616	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1367695616	1367695616	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2500	2500	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3501	3501	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	6454	6454	✔
ElecIntTimer_mS_M_u32[1]	8259	8259	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1367695616	1367695616	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDATDIRASentFltAcc_Cnt_M_u16	14146	14146	✔
ISDATDIRASentTimer_mS_M_u32	1367695616	1367695616	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1367695616	1367695616	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgTimer_mS_M_u32	1367695616	1367695616	✔
IgnOnTimer_mS_M_u32	3436166912	3436166912	✔
IgnTimeOff_Sec_M_u32	807793209	807793209	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2138160896	2138160896	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	122	122	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	719937280	719937280	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	231	231	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1131478784	1131478784	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	21	21	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1896390400	1896390400	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	57278208	57278208	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	84	84	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2875711232	2875711232	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	181	181	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	137330432	137330432	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	50	50	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2728763136	2728763136	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	23	23	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3725115136	3725115136	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	53	53	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	855662336	855662336	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3037200128	3037200128	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1526419200	1526419200	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	26.3393002	26.3393002	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	41.9701004	41.9701004	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	108.267899	108.267899	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	39784	39784	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	807793209	807793209	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	304.674103	304.674103 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.454 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	140457472
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	37581
AASNodeAbsentTimer_mS_M_u32	1246963200
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	28146
ANGLEVOLANTSigValidCount_Cnt_M_u16	20439
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	11066
AngleVolantMsgTimer_mS_M_u32	140457472
AngleVolantValidCount_Cnt_M_u16	33721
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1252451840
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3552404992
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1919931904
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1891800576
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	33961
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2746242560
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	63738
CAVNodeAbsentTimer_mS_M_u32	1723319808
CDD_SrlComVehSpd_Kph_G_f32	582.532471
CMM388NTCEnableTimer_mS_M_u32	1345324544
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3454912000
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	39674
CMMNodeAbsentTimer_mS_M_u32	4161574400
CONSANGLECPKSigInvalidCount_Cnt_M_u16	64337
CONSANGLECPKSigValidCount_Cnt_M_u16	31111
CONSANGLECPK_Cnt_M_u16	15522
CONSANGLECPK_HwDeg_M_f32	-720.83313
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	15522
CPKVehicleSpeedMsgTimer_mS_M_u32	3016635904
CPKVehicleSpeedValidCount_Cnt_M_u16	64180
CityParkInputConsistentCount_Cnt_M_u16	21213
CityParkInputInvalidCount_Cnt_M_u16	17575

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	2138160896
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3799459328
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	55281
ComputerRazGCTSigInvalidTimer_mS_M_u32	1151354368
ComputerRazGCTSigValidCount_Cnt_M_u16	43394
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	4483
DMDFCTCPKSigValidCount_Cnt_M_u16	22608
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56452
DMDRELAXECPKSigValidCount_Cnt_M_u16	59369
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	7358
DateInvalidTimer_mS_M_u32	3552404992
DiagMuxOnAbsentTimer_mS_M_u32	1076688384
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1891800576
ESPNTCEnableTimer_mS_M_u32	4070843904
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	29211
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8976
ElecIntTimer_mS_M_u32[1]	15236
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1520588288
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	10775
EtatMTSigValidCount_Cnt_M_u16	47272
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	40931
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	51097
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	6534
ISDAT4V2BSI552MsgTimer_mS_M_u32	590386688
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	498
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	53324
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	47272
ISDATBSI3F2MsgTimer_mS_M_u32	865793536
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	24724
ISDATBSI412MsgLenValidCount_Cnt_M_u16	61470
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	10775
ISDATBSI412MsgTimer_mS_M_u32	1640838656
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	39198
ISDATBSI432MsgLenValidCount_Cnt_M_u16	33599
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	27243
ISDATDIRASentFltAcc_Cnt_M_u16	38047
ISDATDIRASentTimer_mS_M_u32	3016635904
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	34448
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	33721
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	47546
ISDYN2CMMMsgTimer_mS_M_u32	2926454272
ISDYNAASChkSumInvalidCount_Cnt_M_u16	52575
ISDYNAASChkSumValidCount_Cnt_M_u16	44645
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	37360
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	25685
ISDYNAASMsgLenValidCount_Cnt_M_u16	12370
ISDYNAASMsgTimeValidCount_Cnt_M_u16	52575
ISDYNAASMsgTimer_mS_M_u32	2987132416
ISDYNABRChkSumInvalidCount_Cnt_M_u16	46293
ISDYNABRChkSumValidCount_Cnt_M_u16	35971
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	5654
ISDYNABRMsgCountValidCount_Cnt_M_u16	57948
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	63240
ISDYNABRMsgLenValidCount_Cnt_M_u16	41086
ISDYNABRMsgTimeValidCount_Cnt_M_u16	15522
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	44400
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	47794

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	47272
ISDYNCMM208MsgTimer_mS_M_u32	965469696
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	44400
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	47794
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	54311
ISDYNCMM388MsgTimer_mS_M_u32	415729152
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	9919
ISDYNVOLChkSumValidCount_Cnt_M_u16	64373
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	12273
ISDYNVOLMsgCountValidCount_Cnt_M_u16	3390
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	43108
ISDYNVOLMsgLenValidCount_Cnt_M_u16	34681
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	39674
ISDYNVOLMsgTimer_mS_M_u32	310134272
IgnOnTimer_mS_M_u32	1324058112
IgnTimeOff_Sec_M_u32	1528236181
ManVehSpd_Kph_M_f32	69.4458008
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	69
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	195
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2897278464
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	180
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1007080960
PrevISDATBSI412MsgDLCError_Cnt_M_u08	27
PrevISDATBSI412MsgRxTime_MSec_M_u32	3135817216
PrevISDATBSI432MsgDLCError_Cnt_M_u08	16
PrevISDATBSI432MsgRxTime_MSec_M_u32	2906138112
PrevISDATDIRAMsgTxTime_MSec_M_u32	3827090944
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	54
PrevISDYN2CMMMsgRxTime_MSec_M_u32	651171328
PrevISDYNAASMsgDLCError_Cnt_M_u08	27
PrevISDYNAASMsgRxTime_MSec_M_u32	610944512
PrevISDYNABRMsgDLCError_Cnt_M_u08	168
PrevISDYNABRMsgRxTime_MSec_M_u32	2510521856
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	189
PrevISDYNCMM208MsgRxTime_MSec_M_u32	416237056
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	189
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1028859392
PrevISDYNVOLMsgDLCError_Cnt_M_u08	130
PrevISDYNVOLMsgRxTime_MSec_M_u32	2896545280
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1044067840
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	162.891006
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	59587
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	52032
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	3212
VitesseVehicleBVRampValidCount_Cnt_M_u16	25545
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	35643
VitesseVehicleBVSigValidCount_Cnt_M_u16	480
VitesseVehicleBV_Kph_M_f32	328.796204

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	54311
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	37125
VitesseVehiculeRoues_Kph_M_f32	641.386719
k_AASNTCEnableTimeout_mS_u16	25169
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	1484
k_AASNodeTimeout_mS_u16	15936
k_ABSNodeTimeout_mS_u16	16424
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	20593
k_ANGLEVOLANTSigValidThresh_Cnt_u16	8914
k_AngleVolantInvalidThresh_Cnt_u16	50129
k_AngleVolantValidThresh_Cnt_u16	17575
k_BSI552MsgTimeout_mS_u16	46788
k_BSINTCEnableTimeout_mS_u16	20438
k_BSINodeAbsentDiag_Cnt_str.Threshold	41712
k_BSINodeAbsentDiag_Cnt_str.PStep	46362
k_BSINodeAbsentDiag_Cnt_str.NStep	43480
k_BSINodeAbsentTimeout_mS_u16	62450
k_BSINodeTimeout_mS_u16	27243
k_BattOvHi_Volt_f32	12.4796
k_BattOvLo_Volt_f32	24.5499001
k_BattUvHi_Volt_f32	10.3021002
k_BattUvLo_Volt_f32	17.1543007
k_CAVNTCEnableTimeout_mS_u16	4045
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	59496
k_CAVNodeTimeout_mS_u16	54573
k_CMM388MsgTimeout_mS_u16	17869
k_CMM388NTCEnableTimeout_mS_u16	16553
k_CMMNTCEnableTimeout_mS_u16	54442
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	16865
k_CONSANGLECPKMax_HwDeg_f32	334.974701
k_CONSANGLECPKMin_HwDeg_f32	-223.016098
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	1831
k_CONSANGLECPKSigValidThresh_Cnt_u16	1029
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	27254
k_CPKVehicleSpeedValidThresh_Cnt_u16	3503
k_CityParkInputInvalidThresh_Cnt_u16	25995
k_CityParkInputValidThresh_Cnt_u16	21213
k_ComputerRazGCTSigValidThresh_Cnt_u16	28040
k_CptTemporelSigValidThresh_Cnt_u16	57442
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	43528
k_DMDFCTCPKSigValidThresh_Cnt_u16	37758
k_DMDFCTCPKValidCount_Cnt_u16	32497
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	47546
k_DMDRELAXECPKSigValidThresh_Cnt_u16	35783
k_DMDRelaxeConsistentThresh_Cnt_u16	41469
k_DateValidThresh_Cnt_u16	6534
k_DefaultVehSpd_Kph_f32	174.204407
k_DiagMuxOnAbsentTimeout_mS_u16	49480
k_EMNodeTimeout_mS_u16	30
k_ESPNTCEnableTimeout_mS_u16	29910
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	37673
k_EtatMTSigInvalidThresh_Cnt_u16	41396
k_EtatMTSigValidThresh_Cnt_u16	45730
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	29553
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	35043
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	18598
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	39807
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	27033
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	1208
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	50219
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	52748

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	55106
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	50214
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	58831
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	47771
k_ISDATDIRASentDiag_Cnt_str.Threshold	625
k_ISDATDIRASentDiag_Cnt_str.PStep	48276
k_ISDATDIRASentDiag_Cnt_str.NStep	58314
k_ISDATDIRASentTimeout_mS_u16	11441
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	19072
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	11066
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10050
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	59349
k_ISDYNAASChkSumValidThresh_Cnt_u16	65411
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	51478
k_ISDYNAASMsgCountValidThresh_Cnt_u16	54620
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	45049
k_ISDYNAASMsgLenValidThresh_Cnt_u16	25956
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	12826
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	15734
k_ISDYNABRChkSumValidThresh_Cnt_u16	32108
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	14249
k_ISDYNABRMsgCountValidThresh_Cnt_u16	50382
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	3578
k_ISDYNABRMsgLenValidThresh_Cnt_u16	9499
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	34829
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	45031
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	48029
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	15103
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	8434
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	17111
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	20831
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	39015
k_ISDYNVOLChkSumValidThresh_Cnt_u16	28721
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	35208
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	23207
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	15091
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	63108
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	1324
k_IgnOnTimeout_mS_u16	17475
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	188.406097
k_PowerCutVehSpdLowThresh_Kph_f32	208.976395
k_PowerCutVehSpdLowTimeout_mS_u16	65309
k_VBattMaxAAS_Volt_f32	12.1468
k_VBattMaxBSI_Volt_f32	20.8237991
k_VBattMaxCAV_Volt_f32	11.6148996
k_VBattMaxCMM388_Volt_f32	29.5433006
k_VBattMaxCMM_Volt_f32	24.3652992
k_VBattMaxESP_Volt_f32	10.2580004
k_VBattMinAAS_Volt_f32	18.9937
k_VBattMinBSI_Volt_f32	10.2580004
k_VBattMinCAV_Volt_f32	20.7035007
k_VBattMinCMM388_Volt_f32	8.23820019
k_VBattMinCMM_Volt_f32	10.6436005
k_VBattMinESP_Volt_f32	24.3652992
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	55626
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	41539
k_VitesseVehicleBVRampValidThresh_Cnt_u16	25329
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	61045
k_VitesseVehicleBVSigValidThresh_Cnt_u16	32094
k_VitesseVehicleBVSpeedPassThresh_kph_f32	521.672302
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	11258
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	55735
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3552404992
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	54541
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	433233920
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	189

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	17.4605007
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	981554688
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	70
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.672821522
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1057326592
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	589211136
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	509440
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	54
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3720406528
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3293185536
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	197
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3148031488
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3419162112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	44
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	62
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	114
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	195
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	205
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	218
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	146
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4243187200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	4
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	57
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	71
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	175
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	193
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	54
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1061193216
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	651798016
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	199
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3343042048
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	187
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	231
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2259211776
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3667
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.494737864
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	741803
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	239.042099
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	35085

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	433233920	433233920	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	37581	37581	✔
AASNodeAbsentTimer_mS_M_u32	3419162112	3419162112	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	11068	11068	✔
AngleVolantMsgTimer_mS_M_u32	433233920	433233920	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	433233920	433233920	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	433233920	433233920	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	433233920	433233920	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	433233920	433233920	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3720406528	3720406528	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	433233920	433233920	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	63738	63738	✔
CAVNodeAbsentTimer_mS_M_u32	3343042048	3343042048	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	433233920	433233920	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	433233920	433233920	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	39674	39674	✔
CMMNodeAbsentTimer_mS_M_u32	3148031488	3148031488	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	15522	15522	✔
CONSANGLECPK_HwDeg_M_f32	-720.83313	-720.83313 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	15522	15522	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3016635904	3016635904	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	64180	64180	✔
CityParkInputConsistentCount_Cnt_M_u16	21213	21213	✔
CityParkInputInvalidCount_Cnt_M_u16	17577	17577	✔
CityParkInputMsgTimer_mS_M_u32	433233920	433233920	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	433233920	433233920	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	433233920	433233920	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	433233920	433233920	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	433233920	433233920	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	433233920	433233920	✔
ESPNTCEnableTimer_mS_M_u32	433233920	433233920	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	433233920	433233920	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	8976	8976	✔
ElecIntTimer_mS_M_u32[1]	15236	15236	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	433233920	433233920	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	433233920	433233920	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	433233920	433233920	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	433233920	433233920	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	433233920	433233920	✔
ISDATDIRASentFltAcc_Cnt_M_u16	625	625	✔
ISDATDIRASentTimer_mS_M_u32	433233920	433233920	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	433233920	433233920	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	433233920	433233920	✔
IgnOnTimer_mS_M_u32	1324058112	1324058112	✔
IgnTimeOff_Sec_M_u32	1528236181	1528236181	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	239	239	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1057326592	1057326592	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	186	186	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	589211136	589211136	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	121	121	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	509440	509440	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	54	54	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3720406528	3720406528	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3827090944	3827090944	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	197	197	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3148031488	3148031488	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	168	168	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3419162112	3419162112	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	146	146	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4243187200	4243187200	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	54	54	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1061193216	1061193216	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	651798016	651798016	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	199	199	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3343042048	3343042048	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2259211776	2259211776	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	162.891006	162.891006	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	328.796204	328.796204	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	641.386719	641.386719	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	15522	15522	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1528236181	1528236181	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-720.83313	-720.83313 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	174.204407	174.204407	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	3	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	2	NodeAbsentNTCProcessing	2	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.455 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1389961472
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	36237
AASNodeAbsentTimer_mS_M_u32	2294108416
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	11808
ANGLEVOLANTSigValidCount_Cnt_M_u16	10799
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	47174
AngleVolantMsgTimer_mS_M_u32	1389961472
AngleVolantValidCount_Cnt_M_u16	4937
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2260865280
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1702793472
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2670149888
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1596915968
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	34299
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2909126912
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	21895
CAVNodeAbsentTimer_mS_M_u32	235892992
CDD_SrlComVehSpd_Kph_G_f32	457.842987
CMM388NTCEnableTimer_mS_M_u32	2191962368
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	812478720
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	19016
CMMNodeAbsentTimer_mS_M_u32	1901134080
CONSANGLECPKSigInvalidCount_Cnt_M_u16	46336
CONSANGLECPKSigValidCount_Cnt_M_u16	7200
CONSANGLECPK_Cnt_M_u16	65231
CONSANGLECPK_HwDeg_M_f32	-157.403305
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	65231
CPKVehicleSpeedMsgTimer_mS_M_u32	3431735552
CPKVehicleSpeedValidCount_Cnt_M_u16	62594
CityParkInputConsistentCount_Cnt_M_u16	13789
CityParkInputInvalidCount_Cnt_M_u16	5505
CityParkInputMsgTimer_mS_M_u32	1057326592
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1347506432
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	20001

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3059085568
ComputerRazGCTSigValidCount_Cnt_M_u16	1518
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	7917
DMDFCTCPKSigValidCount_Cnt_M_u16	35909
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	43626
DMDRELAXECPKSigValidCount_Cnt_M_u16	10745
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	17593
DateInvalidTimer_mS_M_u32	1702793472
DiagMuxOnAbsentTimer_mS_M_u32	309321984
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1596915968
ESPNTCEnableTimer_mS_M_u32	332026112
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	22180
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	100
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	5
ElecIntTimer_mS_M_u32[1]	57
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3499081984
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	41456
EtatMTSigValidCount_Cnt_M_u16	18428
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	36682
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	63978
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	41123
ISDAT4V2BSI552MsgTimer_mS_M_u32	2145714432
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	16350
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	18066
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	18428
ISDATBSI3F2MsgTimer_mS_M_u32	1881530624
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	31992
ISDATBSI412MsgLenValidCount_Cnt_M_u16	27
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	41456
ISDATBSI412MsgTimer_mS_M_u32	2123309312
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	57308
ISDATBSI432MsgLenValidCount_Cnt_M_u16	45880
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	1332
ISDATDIRASentFltAcc_Cnt_M_u16	22168
ISDATDIRASentTimer_mS_M_u32	3431735552
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	22789
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	4937
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	49736
ISDYN2CMMMsgTimer_mS_M_u32	2288800000
ISDYNAASChkSumInvalidCount_Cnt_M_u16	42455
ISDYNAASChkSumValidCount_Cnt_M_u16	9351
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	33956
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	16246
ISDYNAASMsgLenValidCount_Cnt_M_u16	56638
ISDYNAASMsgTimeValidCount_Cnt_M_u16	42455
ISDYNAASMsgTimer_mS_M_u32	3440554240
ISDYNABRChkSumInvalidCount_Cnt_M_u16	40694
ISDYNABRChkSumValidCount_Cnt_M_u16	55725
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	26546
ISDYNABRMsgCountValidCount_Cnt_M_u16	9378
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	24027
ISDYNABRMsgLenValidCount_Cnt_M_u16	17211
ISDYNABRMsgTimeValidCount_Cnt_M_u16	65231
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	21501
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	57335
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	18428
ISDYNCMM208MsgTimer_mS_M_u32	2383614208
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	21501
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	57335
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	23039

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3873452288
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	27318
ISDYNVOLChkSumValidCount_Cnt_M_u16	52822
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	64419
ISDYNVOLMsgCountValidCount_Cnt_M_u16	42363
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	6089
ISDYNVOLMsgLenValidCount_Cnt_M_u16	56393
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	19016
ISDYNVOLMsgTimer_mS_M_u32	3166826752
IgnOnTimer_mS_M_u32	3564384512
IgnTimeOff_Sec_M_u32	2289012931
ManVehSpd_Kph_M_f32	468.420685
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	82
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	143
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3705921792
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	78
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1583497472
PrevISDATBSI412MsgDLCError_Cnt_M_u08	193
PrevISDATBSI412MsgRxTime_MSec_M_u32	360476928
PrevISDATBSI432MsgDLCError_Cnt_M_u08	198
PrevISDATBSI432MsgRxTime_MSec_M_u32	873353472
PrevISDATDIRAMsgTxTime_MSec_M_u32	1776316672
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	63
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1392935168
PrevISDYNAASMsgDLCError_Cnt_M_u08	81
PrevISDYNAASMsgRxTime_MSec_M_u32	3203920128
PrevISDYNABRMsgDLCError_Cnt_M_u08	111
PrevISDYNABRMsgRxTime_MSec_M_u32	3763089664
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	209
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3049844992
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	241
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2948419840
PrevISDYNVOLMsgDLCError_Cnt_M_u08	40
PrevISDYNVOLMsgRxTime_MSec_M_u32	1950707968
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	558178560
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	19.5135994
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	59948
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	17524
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	58065
VitesseVehicleBVRampValidCount_Cnt_M_u16	57049
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	14917
VitesseVehicleBVSigValidCount_Cnt_M_u16	30740
VitesseVehicleBV_Kph_M_f32	196.084702
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	23039
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	42278
VitesseVehiculeRoues_Kph_M_f32	349.222107
k_AASNTCEnableTimeout_mS_u16	2498
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	39184
k_AASNodeTimeout_mS_u16	60276
k_ABSNodeTimeout_mS_u16	26366
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	50659
k_ANGLEVOLANTSigValidThresh_Cnt_u16	57471
k_AngleVolantInvalidThresh_Cnt_u16	47490
k_AngleVolantValidThresh_Cnt_u16	5505
k_BSI552MsgTimeout_mS_u16	61417
k_BSINTCEnableTimeout_mS_u16	39860
k_BSINodeAbsentDiag_Cnt_str.Threshold	51965
k_BSINodeAbsentDiag_Cnt_str.PStep	37055
k_BSINodeAbsentDiag_Cnt_str.NStep	65221
k_BSINodeAbsentTimeout_mS_u16	15902
k_BSINodeTimeout_mS_u16	1332
k_BattOvHi_Volt_f32	0.0395000018
k_BattOvLo_Volt_f32	1.75580001
k_BattUvHi_Volt_f32	16.2838993
k_BattUvLo_Volt_f32	26.4181995
k_CAVNTCEnableTimeout_mS_u16	52239
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	48957
k_CAVNodeTimeout_mS_u16	38764
k_CMM388MsgTimeout_mS_u16	29837
k_CMM388NTCEnableTimeout_mS_u16	62457
k_CMMNTCEnableTimeout_mS_u16	42934
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	658
k_CONSANGLECPKMax_HwDeg_f32	563.067322
k_CONSANGLECPKMin_HwDeg_f32	-779.996216
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	49407
k_CONSANGLECPKSigValidThresh_Cnt_u16	19494
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	48850
k_CPKVehicleSpeedValidThresh_Cnt_u16	41383
k_CityParkInputInvalidThresh_Cnt_u16	58580
k_CityParkInputValidThresh_Cnt_u16	13789
k_ComputerRazGCTSigValidThresh_Cnt_u16	54556
k_CptTemporelSigValidThresh_Cnt_u16	61008
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	17627
k_DMDFCTCPKSigValidThresh_Cnt_u16	27195
k_DMDFCTCPKValidCount_Cnt_u16	46883
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	49736
k_DMDRELAXECPKSigValidThresh_Cnt_u16	36320
k_DMDRelaxeConsistentThresh_Cnt_u16	41790
k_DateValidThresh_Cnt_u16	41123
k_DefaultVehSpd_Kph_f32	157.850601
k_DiagMuxOnAbsentTimeout_mS_u16	35037
k_EMNodeTimeout_mS_u16	6809
k_ESPNTCEnableTimeout_mS_u16	20979
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	11962
k_EtatMTSigInvalidThresh_Cnt_u16	5209
k_EtatMTSigValidThresh_Cnt_u16	41808
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	20449
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	57677
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	47234
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	59191
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	61099
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	8332
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	53941
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	18129
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	46448
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	30787
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	50439
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	22501
k_ISDATDIRASentDiag_Cnt_str.Threshold	64711

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	35441
k_ISDATDIRASentDiag_Cnt_str.NStep	35487
k_ISDATDIRASentTimeout_mS_u16	42850
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	31798
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	47174
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	60079
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	1526
k_ISDYNAASChkSumValidThresh_Cnt_u16	32941
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	20146
k_ISDYNAASMsgCountValidThresh_Cnt_u16	19362
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	15754
k_ISDYNAASMsgLenValidThresh_Cnt_u16	1544
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	53927
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	49809
k_ISDYNABRChkSumValidThresh_Cnt_u16	58481
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	27899
k_ISDYNABRMsgCountValidThresh_Cnt_u16	26442
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	61768
k_ISDYNABRMsgLenValidThresh_Cnt_u16	15780
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	55693
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	9408
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	53213
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	45367
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	5408
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	20783
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	53081
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	57727
k_ISDYNVOLChkSumValidThresh_Cnt_u16	35810
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	1117
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	65345
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	57180
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	65128
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	62897
k_IgnOnTimeout_mS_u16	19947
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	73.7455978
k_PowerCutVehSpdLowThresh_Kph_f32	212.034698
k_PowerCutVehSpdLowTimeout_mS_u16	25438
k_VBattMaxAAS_Volt_f32	25.7521992
k_VBattMaxBSI_Volt_f32	24.2621994
k_VBattMaxCAV_Volt_f32	6.04610014
k_VBattMaxCMM388_Volt_f32	5.17710018
k_VBattMaxCMM_Volt_f32	12.4286003
k_VBattMaxESP_Volt_f32	25.1989002
k_VBattMinAAS_Volt_f32	21.9372005
k_VBattMinBSI_Volt_f32	9.19890022
k_VBattMinCAV_Volt_f32	14.0683002
k_VBattMinCMM388_Volt_f32	1.25530005
k_VBattMinCMM_Volt_f32	29.0695
k_VBattMinESP_Volt_f32	12.4286003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	30680
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	3756
k_VitesseVehicleBVRampValidThresh_Cnt_u16	25251
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	62806
k_VitesseVehicleBVSigValidThresh_Cnt_u16	64090
k_VitesseVehicleBVSpeedPassThresh_kph_f32	394.937195
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	48263
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	46351
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1702793472
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	41358
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2292638464
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	241
target_SrlComInput_Per1_Batt_Volt_f32.value	12.0515003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1827848448
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	22
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.274964303
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3961925888
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	56
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2354761984
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	230
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2183098624
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3044282624
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	240693504
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1959612672
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3503419648
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	34
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	140
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	189
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	197
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1006178560
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	3
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	29
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	59
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	130
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	222
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2541039872
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	757715200
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3631116544
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	71
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	135
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	142
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	177
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	234
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2256290048
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3034
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.149197087
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	949778
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	129.087708
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	45390

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2292638464	2292638464	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	19016	19016	✔
CMMNodeAbsentTimer_mS_M_u32	1959612672	1959612672	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	65231	65231	✔
CONSANGLECPK_HwDeg_M_f32	-157.403305	-157.403305 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2292638464	2292638464	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2292638464	2292638464	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2292638464	2292638464	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2292638464	2292638464	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2292638464	2292638464	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2292638464	2292638464	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2292638464	2292638464	✔
ESPNTCEnableTimer_mS_M_u32	2292638464	2292638464	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2292638464	2292638464	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	100	100	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	2292638464	2292638464	✔
ElecIntTimer_mS_M_u32[1]	57	57	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2292638464	2292638464	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDATDIRASentFltAcc_Cnt_M_u16	64711	64711	✔
ISDATDIRASentTimer_mS_M_u32	2292638464	2292638464	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2292638464	2292638464	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2292638464	2292638464	✔
IgnOnTimer_mS_M_u32	3564384512	3564384512	✔
IgnTimeOff_Sec_M_u32	2289012931	2289012931	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	235	235	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3961925888	3961925888	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	56	56	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2354761984	2354761984	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	230	230	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2183098624	2183098624	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	221	221	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3044282624	3044282624	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1776316672	1776316672	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1959612672	1959612672	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	141	141	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3503419648	3503419648	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	173	173	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1006178560	1006178560	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2541039872	2541039872	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	757715200	757715200	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	169	169	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3631116544	3631116544	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2256290048	2256290048	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	19.5135994	19.5135994	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	196.084702	196.084702	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	349.222107	349.222107	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	65231	65231	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2289012931	2289012931	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-157.403305	-157.403305 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	157.850601	157.850601	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.456 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	757347584
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	43072
AASNodeAbsentTimer_mS_M_u32	3646383360
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	48795
ANGLEVOLANTSigValidCount_Cnt_M_u16	13969
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	64713
AngleVolantMsgTimer_mS_M_u32	757347584
AngleVolantValidCount_Cnt_M_u16	64158
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	4107805952
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3598492928
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2614908160
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	173020416
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	64230
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	631428352
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	63588
CAVNodeAbsentTimer_mS_M_u32	2454947072
CDD_SrlComVehSpd_Kph_G_f32	349.321808
CMM388NTCEnableTimer_mS_M_u32	2049885440
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3524363520
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	17520
CMMNodeAbsentTimer_mS_M_u32	1729238272
CONSANGLECPKSigInvalidCount_Cnt_M_u16	59319
CONSANGLECPKSigValidCount_Cnt_M_u16	16318
CONSANGLECPK_Cnt_M_u16	43293
CONSANGLECPK_HwDeg_M_f32	304.686615
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43293
CPKVehicleSpeedMsgTimer_mS_M_u32	2663855360
CPKVehicleSpeedValidCount_Cnt_M_u16	18483
CityParkInputConsistentCount_Cnt_M_u16	11122
CityParkInputInvalidCount_Cnt_M_u16	618

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	163588608
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1059808512
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	55060
ComputerRazGCTSigInvalidTimer_mS_M_u32	1487013120
ComputerRazGCTSigValidCount_Cnt_M_u16	20691
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	48534
DMDFCTCPKSigValidCount_Cnt_M_u16	36181
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	12805
DMDRELAXECPKSigValidCount_Cnt_M_u16	17787
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	12608
DateInvalidTimer_mS_M_u32	3598492928
DiagMuxOnAbsentTimer_mS_M_u32	668398848
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	173020416
ESPNTCEnableTimer_mS_M_u32	3899942144
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	42099
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	707
EffacDefaultDiagTimer_mS_M_u32[1]	1235
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	979
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1710019840
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	21677
EtatMTSigValidCount_Cnt_M_u16	21855
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	6433
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	36008
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	24339
ISDAT4V2BSI552MsgTimer_mS_M_u32	1139152128
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	49904
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	55499
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	21855
ISDATBSI3F2MsgTimer_mS_M_u32	2926376192
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	48110
ISDATBSI412MsgLenValidCount_Cnt_M_u16	12600
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	21677
ISDATBSI412MsgTimer_mS_M_u32	3787076864
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	55364
ISDATBSI432MsgLenValidCount_Cnt_M_u16	12103
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	40481
ISDATDIRASentFltAcc_Cnt_M_u16	40645
ISDATDIRASentTimer_mS_M_u32	2663855360
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	5171
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	64158
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	56673
ISDYN2CMMMsgTimer_mS_M_u32	1874224384
ISDYNAASChkSumInvalidCount_Cnt_M_u16	30634
ISDYNAASChkSumValidCount_Cnt_M_u16	17473
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	18537
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	44291
ISDYNAASMsgLenValidCount_Cnt_M_u16	53298
ISDYNAASMsgTimeValidCount_Cnt_M_u16	30634
ISDYNAASMsgTimer_mS_M_u32	3327837440
ISDYNABRChkSumInvalidCount_Cnt_M_u16	26695
ISDYNABRChkSumValidCount_Cnt_M_u16	13157
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	15861
ISDYNABRMsgCountValidCount_Cnt_M_u16	48332
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	50434
ISDYNABRMsgLenValidCount_Cnt_M_u16	3913
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43293
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	57651

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	21855
ISDYNCMM208MsgTimer_mS_M_u32	2507744512
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	57651
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	14900
ISDYNCMM388MsgTimer_mS_M_u32	2824881408
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	17997
ISDYNVOLChkSumValidCount_Cnt_M_u16	33492
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	29484
ISDYNVOLMsgCountValidCount_Cnt_M_u16	26475
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	20776
ISDYNVOLMsgLenValidCount_Cnt_M_u16	13455
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	17520
ISDYNVOLMsgTimer_mS_M_u32	550372608
IgnOnTimer_mS_M_u32	338969856
IgnTimeOff_Sec_M_u32	2369743518
ManVehSpd_Kph_M_f32	136.996597
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	83
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	69
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1988818176
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	98
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2374456576
PrevISDATBSI412MsgDLCError_Cnt_M_u08	44
PrevISDATBSI412MsgRxTime_MSec_M_u32	4224746752
PrevISDATBSI432MsgDLCError_Cnt_M_u08	44
PrevISDATBSI432MsgRxTime_MSec_M_u32	1576559872
PrevISDATDIRAMsgTxTime_MSec_M_u32	4017390848
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	149
PrevISDYN2CMMMsgRxTime_MSec_M_u32	159356160
PrevISDYNAASMsgDLCError_Cnt_M_u08	39
PrevISDYNAASMsgRxTime_MSec_M_u32	3018065152
PrevISDYNABRMsgDLCError_Cnt_M_u08	161
PrevISDYNABRMsgRxTime_MSec_M_u32	1401701632
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	37
PrevISDYNCMM208MsgRxTime_MSec_M_u32	470091008
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	39
PrevISDYNCMM388MsgRxTime_MSec_M_u32	811033856
PrevISDYNVOLMsgDLCError_Cnt_M_u08	242
PrevISDYNVOLMsgRxTime_MSec_M_u32	3379135744
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1028666624
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	389.546814
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	37017
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	22600
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	52430
VitesseVehicleBVRampValidCount_Cnt_M_u16	49725
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	9808
VitesseVehicleBVSigValidCount_Cnt_M_u16	27654
VitesseVehicleBV_Kph_M_f32	160.031601

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	14900
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	14531
VitesseVehiculeRoues_Kph_M_f32	437.254303
k_AASNTCEnableTimeout_mS_u16	4096
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	32405
k_AASNodeTimeout_mS_u16	12104
k_ABSNodeTimeout_mS_u16	56055
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	53371
k_ANGLEVOLANTSigValidThresh_Cnt_u16	45758
k_AngleVolantInvalidThresh_Cnt_u16	19633
k_AngleVolantValidThresh_Cnt_u16	618
k_BSI552MsgTimeout_mS_u16	53366
k_BSINTCEnableTimeout_mS_u16	51100
k_BSINodeAbsentDiag_Cnt_str.Threshold	13537
k_BSINodeAbsentDiag_Cnt_str.PStep	61147
k_BSINodeAbsentDiag_Cnt_str.NStep	49162
k_BSINodeAbsentTimeout_mS_u16	54817
k_BSINodeTimeout_mS_u16	40481
k_BattOvHi_Volt_f32	1.60660005
k_BattOvLo_Volt_f32	14.0558996
k_BattUvHi_Volt_f32	11.5599003
k_BattUvLo_Volt_f32	18.7936001
k_CAVNTCEnableTimeout_mS_u16	9560
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	19194
k_CAVNodeTimeout_mS_u16	19427
k_CMM388MsgTimeout_mS_u16	48960
k_CMM388NTCEnableTimeout_mS_u16	53356
k_CMMNTCEnableTimeout_mS_u16	7752
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	34799
k_CONSANGLECPKMax_HwDeg_f32	159.256805
k_CONSANGLECPKMin_HwDeg_f32	-372.596802
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	53556
k_CONSANGLECPKSigValidThresh_Cnt_u16	4035
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	28678
k_CPKVehicleSpeedValidThresh_Cnt_u16	1869
k_CityParkInputInvalidThresh_Cnt_u16	58245
k_CityParkInputValidThresh_Cnt_u16	11122
k_ComputerRazGCTSigValidThresh_Cnt_u16	23438
k_CptTemporelSigValidThresh_Cnt_u16	19433
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	56322
k_DMDFCTCPKSigValidThresh_Cnt_u16	26185
k_DMDFCTCPKValidCount_Cnt_u16	2190
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	56673
k_DMDRELAXECPKSigValidThresh_Cnt_u16	32608
k_DMDRelaxeConsistentThresh_Cnt_u16	41502
k_DateValidThresh_Cnt_u16	24339
k_DefaultVehSpd_Kph_f32	122.339203
k_DiagMuxOnAbsentTimeout_mS_u16	46987
k_EMNodeTimeout_mS_u16	56608
k_ESPNTCEnableTimeout_mS_u16	38544
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	151
k_EtatMTSigInvalidThresh_Cnt_u16	31898
k_EtatMTSigValidThresh_Cnt_u16	61432
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	1477
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	32728
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	4519
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	34329
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	55476
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	48578
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	32493
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	45744

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	44056
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	22225
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	38844
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	58623
k_ISDATDIRASentDiag_Cnt_str.Threshold	3472
k_ISDATDIRASentDiag_Cnt_str.PStep	32212
k_ISDATDIRASentDiag_Cnt_str.NStep	26715
k_ISDATDIRASentTimeout_mS_u16	53875
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	45728
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	64713
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	43532
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	65351
k_ISDYNAASChkSumValidThresh_Cnt_u16	2661
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	21749
k_ISDYNAASMsgCountValidThresh_Cnt_u16	5068
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	54555
k_ISDYNAASMsgLenValidThresh_Cnt_u16	55324
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	53606
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	33432
k_ISDYNABRChkSumValidThresh_Cnt_u16	61791
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	4582
k_ISDYNABRMsgCountValidThresh_Cnt_u16	64540
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	7024
k_ISDYNABRMsgLenValidThresh_Cnt_u16	47987
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	4943
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	22893
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	34403
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	45563
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	54683
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	36241
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	20418
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	47781
k_ISDYNVOLChkSumValidThresh_Cnt_u16	39727
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	27644
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	22329
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	33753
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	52619
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	43137
k_IgnOnTimeout_mS_u16	51409
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	87.8358002
k_PowerCutVehSpdLowThresh_Kph_f32	57.2498016
k_PowerCutVehSpdLowTimeout_mS_u16	10844
k_VBattMaxAAS_Volt_f32	4.92030001
k_VBattMaxBSI_Volt_f32	14.5178003
k_VBattMaxCAV_Volt_f32	20.9589996
k_VBattMaxCMM388_Volt_f32	1.35520005
k_VBattMaxCMM_Volt_f32	17.2914009
k_VBattMaxESP_Volt_f32	23.9118996
k_VBattMinAAS_Volt_f32	32
k_VBattMinBSI_Volt_f32	23.9118996
k_VBattMinCAV_Volt_f32	26.1005001
k_VBattMinCMM388_Volt_f32	12.5352001
k_VBattMinCMM_Volt_f32	19.2887001
k_VBattMinESP_Volt_f32	17.2914009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	61666
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	41181
k_VitesseVehicleBVRampValidThresh_Cnt_u16	2604
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	55764
k_VitesseVehicleBVSigValidThresh_Cnt_u16	26367
k_VitesseVehicleBVSpeedPassThresh_kph_f32	384.171906
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	36708
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	26963
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3598492928
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target Rte Call Ap SrlComInput SystemTime DtrmnElapsedTime mS u16 Elaps	55180
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3453916928
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	39

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	6.72779989
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3510621440
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	132
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.343401223
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	864437504
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	1
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3056395520
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1264813312
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1529488640
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1300284672
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2322031872
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2044593408
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	18
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	203
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	214
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	215
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2067735808
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	42
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	126
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	134
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	151
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	394609920
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1202447616
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	240
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1247970560
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	55
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	183
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	209
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	239
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1572951296
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3282
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.297926456
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	889770
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	39.5410995
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	12891

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3453916928	3453916928	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3453916928	3453916928	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3453916928	3453916928	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3453916928	3453916928	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3453916928	3453916928	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	43293	43293	✔
CONSANGLECPK_HwDeg_M_f32	304.686615	304.686615 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3453916928	3453916928	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3453916928	3453916928	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3453916928	3453916928	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3453916928	3453916928	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3453916928	3453916928	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3453916928	3453916928	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3453916928	3453916928	✔
ESPNTCEnableTimer_mS_M_u32	3453916928	3453916928	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3453916928	3453916928	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3453916928	3453916928	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1235	1235	✔
ElecIntCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	3453916928	3453916928	✔
ElecIntTimer_mS_M_u32[1]	979	979	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3453916928	3453916928	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDATDIRASentFltAcc_Cnt_M_u16	3472	3472	✔
ISDATDIRASentTimer_mS_M_u32	3453916928	3453916928	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3453916928	3453916928	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3453916928	3453916928	✔
IgnOnTimer_mS_M_u32	338969856	338969856	✔
IgnTimeOff_Sec_M_u32	2369743518	2369743518	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	69	69	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	864437504	864437504	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	1	1	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3056395520	3056395520	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	95	95	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1264813312	1264813312	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	5	5	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1529488640	1529488640	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4017390848	4017390848	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	196	196	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2322031872	2322031872	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	173	173	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2044593408	2044593408	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	123	123	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2067735808	2067735808	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	181	181	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	394609920	394609920	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	3	3	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1202447616	1202447616	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	240	240	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1247970560	1247970560	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1572951296	1572951296	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	389.546814	389.546814	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	160.031601	160.031601	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	437.254303	437.254303	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	43293	43293	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2369743518	2369743518	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	304.686615	304.686615 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	122.339203	122.339203	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.457 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	994452480
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	56304
AASNodeAbsentTimer_mS_M_u32	1064080384
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	8929
ANGLEVOLANTSigValidCount_Cnt_M_u16	12733
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	16981
AngleVolantMsgTimer_mS_M_u32	994452480
AngleVolantValidCount_Cnt_M_u16	58199
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3756676096
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1828508672
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2006828032
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2873263104
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	23040
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	340411392
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	9220
CAVNodeAbsentTimer_mS_M_u32	2901947392
CDD_SrlComVehSpd_Kph_G_f32	74.8588028
CMM388NTCEnableTimer_mS_M_u32	1919316992
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1706963968
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	39840
CMMNodeAbsentTimer_mS_M_u32	486310912
CONSANGLECPKSigInvalidCount_Cnt_M_u16	2698
CONSANGLECPKSigValidCount_Cnt_M_u16	47414
CONSANGLECPK_Cnt_M_u16	47385
CONSANGLECPK_HwDeg_M_f32	166.910095
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	47385
CPKVehicleSpeedMsgTimer_mS_M_u32	844964864
CPKVehicleSpeedValidCount_Cnt_M_u16	33439
CityParkInputConsistentCount_Cnt_M_u16	41179
CityParkInputInvalidCount_Cnt_M_u16	19699
CityParkInputMsgTimer_mS_M_u32	864437504
CityParkInputValidCount_Cnt_M_u16	6

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1576047616
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	40820
ComputerRazGCTSigInvalidTimer_mS_M_u32	3020731392
ComputerRazGCTSigValidCount_Cnt_M_u16	62648
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	52079
DMDFCTCPKSigValidCount_Cnt_M_u16	62194
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	61603
DMDRELAXECPKSigValidCount_Cnt_M_u16	11519
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	37359
DateInvalidTimer_mS_M_u32	1828508672
DiagMuxOnAbsentTimer_mS_M_u32	2251154432
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2873263104
ESPNTCEnableTimer_mS_M_u32	3323302912
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	8792
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	8
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	4218176512
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	44011
EtatMTSigValidCount_Cnt_M_u16	4243
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	40524
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	64120
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	62904
ISDAT4V2BSI552MsgTimer_mS_M_u32	3598746624
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	51360
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	36304
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	4243
ISDATBSI3F2MsgTimer_mS_M_u32	3396068352
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	25256
ISDATBSI412MsgLenValidCount_Cnt_M_u16	51592
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	44011
ISDATBSI412MsgTimer_mS_M_u32	4119077888
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	12324
ISDATBSI432MsgLenValidCount_Cnt_M_u16	53724
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	26317
ISDATDIRASentFltAcc_Cnt_M_u16	62689
ISDATDIRASentTimer_mS_M_u32	844964864
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	20439
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	58199
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	22542
ISDYN2CMMMsgTimer_mS_M_u32	3092222976
ISDYNAASChkSumInvalidCount_Cnt_M_u16	38322
ISDYNAASChkSumValidCount_Cnt_M_u16	9902
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	58870
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	16935
ISDYNAASMsgLenValidCount_Cnt_M_u16	12123
ISDYNAASMsgTimeValidCount_Cnt_M_u16	38322
ISDYNAASMsgTimer_mS_M_u32	1038251008
ISDYNABRChkSumInvalidCount_Cnt_M_u16	11613
ISDYNABRChkSumValidCount_Cnt_M_u16	58049
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	11985
ISDYNABRMsgCountValidCount_Cnt_M_u16	43277
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	24233
ISDYNABRMsgLenValidCount_Cnt_M_u16	13973
ISDYNABRMsgTimeValidCount_Cnt_M_u16	47385
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	47707
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	4243
ISDYNCMM208MsgTimer_mS_M_u32	3255260160

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	47707
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	64661
ISDYNCMM388MsgTimer_mS_M_u32	2379346944
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	50888
ISDYNVOLChkSumValidCount_Cnt_M_u16	51188
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	33453
ISDYNVOLMsgCountValidCount_Cnt_M_u16	15536
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	12345
ISDYNVOLMsgLenValidCount_Cnt_M_u16	48325
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	39840
ISDYNVOLMsgTimer_mS_M_u32	193508352
IgnOnTimer_mS_M_u32	2589324288
IgnTimeOff_Sec_M_u32	1913641218
ManVehSpd_Kph_M_f32	36.9065018
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	84
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1779557376
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	106
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	245154816
PrevISDATBSI412MsgDLCError_Cnt_M_u08	246
PrevISDATBSI412MsgRxTime_MSec_M_u32	2759930880
PrevISDATBSI432MsgDLCError_Cnt_M_u08	29
PrevISDATBSI432MsgRxTime_MSec_M_u32	1971950592
PrevISDATDIRAMsgTxTime_MSec_M_u32	1502950400
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	194
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3417572352
PrevISDYNAASMsgDLCError_Cnt_M_u08	170
PrevISDYNAASMsgRxTime_MSec_M_u32	709276672
PrevISDYNABRMsgDLCError_Cnt_M_u08	122
PrevISDYNABRMsgRxTime_MSec_M_u32	1011741696
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	12
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3051598848
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	34
PrevISDYNCMM388MsgRxTime_MSec_M_u32	980194304
PrevISDYNVOLMsgDLCError_Cnt_M_u08	96
PrevISDYNVOLMsgRxTime_MSec_M_u32	3753260032
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3133285376
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	205.438797
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	28517
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	28441
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	52934
VitesseVehicleBVRampValidCount_Cnt_M_u16	17722
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	65474
VitesseVehicleBVSigValidCount_Cnt_M_u16	42334
VitesseVehicleBV_Kph_M_f32	470.952698
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	64661
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	55209

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	366.130005
k_AASNTCEnableTimeout_mS_u16	53360
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	62322
k_AASNodeTimeout_mS_u16	59929
k_ABSNodeTimeout_mS_u16	14156
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	58239
k_ANGLEVOLANTSigValidThresh_Cnt_u16	58231
k_AngleVolantInvalidThresh_Cnt_u16	41374
k_AngleVolantValidThresh_Cnt_u16	19699
k_BSI552MsgTimeout_mS_u16	40080
k_BSINTCEnableTimeout_mS_u16	49692
k_BSINodeAbsentDiag_Cnt_str.Threshold	33043
k_BSINodeAbsentDiag_Cnt_str.PStep	12643
k_BSINodeAbsentDiag_Cnt_str.NStep	27671
k_BSINodeAbsentTimeout_mS_u16	5709
k_BSINodeTimeout_mS_u16	26317
k_BattOvHi_Volt_f32	28.3083
k_BattOvLo_Volt_f32	4.6395998
k_BattUvHi_Volt_f32	10.9534998
k_BattUvLo_Volt_f32	6.35930014
k_CAVNTCEnableTimeout_mS_u16	7209
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	1090
k_CAVNodeTimeout_mS_u16	36358
k_CMM388MsgTimeout_mS_u16	38640
k_CMM388NTCEnableTimeout_mS_u16	4972
k_CMMNTCEnableTimeout_mS_u16	5784
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	39461
k_CONSANGLECPKMax_HwDeg_f32	598.234924
k_CONSANGLECPKMin_HwDeg_f32	-173.423904
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	14229
k_CONSANGLECPKSigValidThresh_Cnt_u16	21161
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	40927
k_CPKVehicleSpeedValidThresh_Cnt_u16	48267
k_CityParkInputInvalidThresh_Cnt_u16	13219
k_CityParkInputValidThresh_Cnt_u16	41179
k_ComputerRazGCTSigValidThresh_Cnt_u16	63174
k_CptTemporelSigValidThresh_Cnt_u16	11382
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	6569
k_DMDFCTCPKSigValidThresh_Cnt_u16	12693
k_DMDFCTCPKValidCount_Cnt_u16	53512
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	22542
k_DMDRELAXECPKSigValidThresh_Cnt_u16	2257
k_DMDRelaxeConsistentThresh_Cnt_u16	6295
k_DateValidThresh_Cnt_u16	62904
k_DefaultVehSpd_Kph_f32	230.180695
k_DiagMuxOnAbsentTimeout_mS_u16	50639
k_EMNodeTimeout_mS_u16	3663
k_ESPNTCEnableTimeout_mS_u16	63872
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	53293
k_EtatMTSigInvalidThresh_Cnt_u16	64612
k_EtatMTSigValidThresh_Cnt_u16	47368
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	39586
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	4906
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	572
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	25381
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	29205
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	44332
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	8233
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	11169
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	1192
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	32765

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	1021
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	48244
k_ISDATDIRASentDiag_Cnt_str.Threshold	64711
k_ISDATDIRASentDiag_Cnt_str.PStep	35441
k_ISDATDIRASentDiag_Cnt_str.NStep	35487
k_ISDATDIRASentTimeout_mS_u16	40665
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	6033
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	16981
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	44812
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	26717
k_ISDYNAASChkSumValidThresh_Cnt_u16	24001
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	59857
k_ISDYNAASMsgCountValidThresh_Cnt_u16	41997
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	14049
k_ISDYNAASMsgLenValidThresh_Cnt_u16	16285
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	10111
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	64999
k_ISDYNABRChkSumValidThresh_Cnt_u16	26707
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	5376
k_ISDYNABRMsgCountValidThresh_Cnt_u16	52508
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	5792
k_ISDYNABRMsgLenValidThresh_Cnt_u16	56664
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	4995
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	25833
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	5961
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	60928
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	56801
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	11453
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	50411
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	643
k_ISDYNVOLChkSumValidThresh_Cnt_u16	10147
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	12221
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	51013
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	52839
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	22543
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	20846
k_IgnOnTimeout_mS_u16	34815
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	178.190994
k_PowerCutVehSpdLowThresh_Kph_f32	53.9487991
k_PowerCutVehSpdLowTimeout_mS_u16	61788
k_VBattMaxAAS_Volt_f32	27.4171009
k_VBattMaxBSI_Volt_f32	14.1576996
k_VBattMaxCAV_Volt_f32	7.62809992
k_VBattMaxCMM388_Volt_f32	11.8476
k_VBattMaxCMM_Volt_f32	29.6201992
k_VBattMaxESP_Volt_f32	29.8358994
k_VBattMinAAS_Volt_f32	3.86960006
k_VBattMinBSI_Volt_f32	29.8358994
k_VBattMinCAV_Volt_f32	30.1987991
k_VBattMinCMM388_Volt_f32	28.6779003
k_VBattMinCMM_Volt_f32	10.0607004
k_VBattMinESP_Volt_f32	29.6201992
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	58571
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	23451
k_VitesseVehicleBVRampValidThresh_Cnt_u16	48557
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	49908
k_VitesseVehicleBVSigValidThresh_Cnt_u16	25140
k_VitesseVehicleBVSpeedPassThresh_kph_f32	552.938293
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	24324
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	10232
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1828508672
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	43468
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3038707200
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	34
target_SrlComInput_Per1_Batt_Volt_f32.value	10.3413
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3312665600
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	228
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.744372964
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	13
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	73397248
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3740013568
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3251123200
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1962169344
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3228595200
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1815909376
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	12
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1079555072
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	77
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	104
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	106
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	111
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2830455808
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	31
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	43
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	111
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	142
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	225
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	95
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	342029312
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	184
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3866039296
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2160800768
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	44
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	56
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	114
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	99533824
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2497
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.75163734
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	748759
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	137.324997
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	4639

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3038707200	3038707200	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3038707200	3038707200	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	16983	16983	✔
AngleVolantMsgTimer_mS_M_u32	3038707200	3038707200	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3038707200	3038707200	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3038707200	3038707200	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3038707200	3038707200	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	47385	47385	✔
CONSANGLECPK_HwDeg_M_f32	166.910095	166.910095 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	47385	47385	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	844964864	844964864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	33439	33439	✔
CityParkInputConsistentCount_Cnt_M_u16	41179	41179	✔
CityParkInputInvalidCount_Cnt_M_u16	19699	19699	✔
CityParkInputMsgTimer_mS_M_u32	3038707200	3038707200	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3038707200	3038707200	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3038707200	3038707200	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3038707200	3038707200	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3038707200	3038707200	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3038707200	3038707200	✔
ESPNTCEnableTimer_mS_M_u32	3038707200	3038707200	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3038707200	3038707200	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	3038707200	3038707200	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	8	8	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3038707200	3038707200	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDATDIRASentFltAcc_Cnt_M_u16	64711	64711	✔
ISDATDIRASentTimer_mS_M_u32	3038707200	3038707200	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3038707200	3038707200	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3038707200	3038707200	✔
IgnOnTimer_mS_M_u32	2589324288	2589324288	✔
IgnTimeOff_Sec_M_u32	1913641218	1913641218	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	73397248	73397248	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	5	5	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3740013568	3740013568	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	106	106	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3251123200	3251123200	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	60	60	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1962169344	1962169344	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1502950400	1502950400	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1815909376	1815909376	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	12	12	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1079555072	1079555072	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	111	111	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2830455808	2830455808	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	95	95	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	342029312	342029312	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	184	184	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3866039296	3866039296	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	118	118	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2160800768	2160800768	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	99533824	99533824	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	205.438797	205.438797	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	470.952698	470.952698	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	366.130005	366.130005	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	47385	47385	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1913641218	1913641218	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	166.910095	166.910095 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.458 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1873133056
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	22948
AASNodeAbsentTimer_mS_M_u32	847228416
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	35864
ANGLEVOLANTSigValidCount_Cnt_M_u16	27476
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	64305
AngleVolantMsgTimer_mS_M_u32	1873133056
AngleVolantValidCount_Cnt_M_u16	33092
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3974852096
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1720839680
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	666525184
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3867483648
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	5167
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3184188928
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	56148
CAVNodeAbsentTimer_mS_M_u32	3311947264
CDD_SrlComVehSpd_Kph_G_f32	316.54071
CMM388NTCEnableTimer_mS_M_u32	2152238592
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3026079232
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	33618
CMMNodeAbsentTimer_mS_M_u32	1980702208
CONSANGLECPKSigInvalidCount_Cnt_M_u16	42768
CONSANGLECPKSigValidCount_Cnt_M_u16	42139
CONSANGLECPK_Cnt_M_u16	56214
CONSANGLECPK_HwDeg_M_f32	99.8860016
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	56214
CPKVehicleSpeedMsgTimer_mS_M_u32	2004139520
CPKVehicleSpeedValidCount_Cnt_M_u16	35675
CityParkInputConsistentCount_Cnt_M_u16	51944
CityParkInputInvalidCount_Cnt_M_u16	18873
CityParkInputMsgTimer_mS_M_u32	1464788736
CityParkInputValidCount_Cnt_M_u16	7

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3844320768
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	55624
ComputerRazGCTSigInvalidTimer_mS_M_u32	1495322112
ComputerRazGCTSigValidCount_Cnt_M_u16	34221
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	7189
DMDFCTCPKSigValidCount_Cnt_M_u16	6457
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	38890
DMDRELAXECPKSigValidCount_Cnt_M_u16	4262
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	29085
DateInvalidTimer_mS_M_u32	1720839680
DiagMuxOnAbsentTimer_mS_M_u32	936082944
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3867483648
ESPNTCEnableTimer_mS_M_u32	2523966976
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	63817
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	87
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	21
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2919030272
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	42999
EtatMTSigValidCount_Cnt_M_u16	27487
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	43234
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	49133
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	41519
ISDAT4V2BSI552MsgTimer_mS_M_u32	2612207104
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	61775
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	22910
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	27487
ISDATBSI3F2MsgTimer_mS_M_u32	3455680000
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	46489
ISDATBSI412MsgLenValidCount_Cnt_M_u16	19704
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	42999
ISDATBSI412MsgTimer_mS_M_u32	735297024
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	23542
ISDATBSI432MsgLenValidCount_Cnt_M_u16	50413
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	56421
ISDATDIRASentFltAcc_Cnt_M_u16	64281
ISDATDIRASentTimer_mS_M_u32	2004139520
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	22596
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	33092
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	42412
ISDYN2CMMMsgTimer_mS_M_u32	2860166656
ISDYNAASChkSumInvalidCount_Cnt_M_u16	45430
ISDYNAASChkSumValidCount_Cnt_M_u16	9169
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	12507
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	8847
ISDYNAASMsgLenValidCount_Cnt_M_u16	37603
ISDYNAASMsgTimeValidCount_Cnt_M_u16	45430
ISDYNAASMsgTimer_mS_M_u32	128224768
ISDYNABRChkSumInvalidCount_Cnt_M_u16	29048
ISDYNABRChkSumValidCount_Cnt_M_u16	27515
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	43917
ISDYNABRMsgCountValidCount_Cnt_M_u16	20776
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	13351
ISDYNABRMsgLenValidCount_Cnt_M_u16	42226
ISDYNABRMsgTimeValidCount_Cnt_M_u16	56214
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	43890
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	2127
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	27487
ISDYNCMM208MsgTimer_mS_M_u32	2817551872

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	43890
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	2127
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	38002
ISDYNCMM388MsgTimer_mS_M_u32	588254720
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	30014
ISDYNVOLChkSumValidCount_Cnt_M_u16	22857
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	48451
ISDYNVOLMsgCountValidCount_Cnt_M_u16	57575
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	56882
ISDYNVOLMsgLenValidCount_Cnt_M_u16	43166
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	33618
ISDYNVOLMsgTimer_mS_M_u32	3430731264
IgnOnTimer_mS_M_u32	867438080
IgnTimeOff_Sec_M_u32	192017353
ManVehSpd_Kph_M_f32	296.730499
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	82
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	241
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3671031296
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	185
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	246504960
PrevISDATBSI412MsgDLCError_Cnt_M_u08	237
PrevISDATBSI412MsgRxTime_MSec_M_u32	557403648
PrevISDATBSI432MsgDLCError_Cnt_M_u08	18
PrevISDATBSI432MsgRxTime_MSec_M_u32	3783568896
PrevISDATDIRAMsgTxTime_MSec_M_u32	2666352128
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	198
PrevISDYN2CMMMsgRxTime_MSec_M_u32	646094336
PrevISDYNAASMsgDLCError_Cnt_M_u08	252
PrevISDYNAASMsgRxTime_MSec_M_u32	288017920
PrevISDYNABRMsgDLCError_Cnt_M_u08	165
PrevISDYNABRMsgRxTime_MSec_M_u32	2775322112
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	11
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3249524224
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	153
PrevISDYNCMM388MsgRxTime_MSec_M_u32	92253696
PrevISDYNVOLMsgDLCError_Cnt_M_u08	227
PrevISDYNVOLMsgRxTime_MSec_M_u32	3189132800
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1258405376
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	107.293198
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	59837
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	145
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	44070
VitesseVehicleBVRampValidCount_Cnt_M_u16	61370
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	47105
VitesseVehicleBVSigValidCount_Cnt_M_u16	58365
VitesseVehicleBV_Kph_M_f32	133.069199
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	38002
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	24997

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	458.759308
k_AASNTCEnableTimeout_mS_u16	1445
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	2615
k_AASNodeTimeout_mS_u16	21393
k_ABSNodeTimeout_mS_u16	44762
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	41513
k_ANGLEVOLANTSigValidThresh_Cnt_u16	23392
k_AngleVolantInvalidThresh_Cnt_u16	58047
k_AngleVolantValidThresh_Cnt_u16	18873
k_BSI552MsgTimeout_mS_u16	9668
k_BSINTCEnableTimeout_mS_u16	15790
k_BSINodeAbsentDiag_Cnt_str.Threshold	28392
k_BSINodeAbsentDiag_Cnt_str.PStep	49975
k_BSINodeAbsentDiag_Cnt_str.NStep	2138
k_BSINodeAbsentTimeout_mS_u16	12009
k_BSINodeTimeout_mS_u16	56421
k_BattOvHi_Volt_f32	27.6151009
k_BattOvLo_Volt_f32	28.3220997
k_BattUvHi_Volt_f32	31.5
k_BattUvLo_Volt_f32	5.58699989
k_CAVNTCEnableTimeout_mS_u16	33439
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	60802
k_CAVNodeTimeout_mS_u16	42604
k_CMM388MsgTimeout_mS_u16	60580
k_CMM388NTCEnableTimeout_mS_u16	44288
k_CMMNTCEnableTimeout_mS_u16	28423
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	38913
k_CONSANGLECPKMax_HwDeg_f32	277.659698
k_CONSANGLECPKMin_HwDeg_f32	-154.224197
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	42866
k_CONSANGLECPKSigValidThresh_Cnt_u16	46245
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	10119
k_CPKVehicleSpeedValidThresh_Cnt_u16	5780
k_CityParkInputInvalidThresh_Cnt_u16	6638
k_CityParkInputValidThresh_Cnt_u16	51944
k_ComputerRazGCTSigValidThresh_Cnt_u16	165
k_CptTemporelSigValidThresh_Cnt_u16	23892
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	50983
k_DMDFCTCPKSigValidThresh_Cnt_u16	30706
k_DMDFCTCPKValidCount_Cnt_u16	33655
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	42412
k_DMDRELAXECPKSigValidThresh_Cnt_u16	30224
k_DMDRelaxeConsistentThresh_Cnt_u16	29702
k_DateValidThresh_Cnt_u16	41519
k_DefaultVehSpd_Kph_f32	190.808105
k_DiagMuxOnAbsentTimeout_mS_u16	15868
k_EMNodeTimeout_mS_u16	53501
k_ESPNTCEnableTimeout_mS_u16	48304
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	48713
k_EtatMTSigInvalidThresh_Cnt_u16	37047
k_EtatMTSigValidThresh_Cnt_u16	52218
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	12386
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	42665
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	40785
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	26620
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	26603
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	62525
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	54307
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	62682
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	29850
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	31130

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	5914
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	55239
k_ISDATDIRASentDiag_Cnt_str.Threshold	39837
k_ISDATDIRASentDiag_Cnt_str.PStep	59486
k_ISDATDIRASentDiag_Cnt_str.NStep	60819
k_ISDATDIRASentTimeout_mS_u16	52948
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	54220
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	64305
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	65180
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	33912
k_ISDYNAASChkSumValidThresh_Cnt_u16	48763
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	16013
k_ISDYNAASMsgCountValidThresh_Cnt_u16	9256
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	26396
k_ISDYNAASMsgLenValidThresh_Cnt_u16	62773
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	65448
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	64853
k_ISDYNABRChkSumValidThresh_Cnt_u16	38048
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	42799
k_ISDYNABRMsgCountValidThresh_Cnt_u16	31147
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	54866
k_ISDYNABRMsgLenValidThresh_Cnt_u16	35913
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	52042
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	11105
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	30530
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	20144
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	7960
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	15956
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	16753
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	19532
k_ISDYNVOLChkSumValidThresh_Cnt_u16	37867
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	31190
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	5151
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	15955
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	20155
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	52117
k_IgnOnTimeout_mS_u16	23976
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	251.900406
k_PowerCutVehSpdLowThresh_Kph_f32	109.720703
k_PowerCutVehSpdLowTimeout_mS_u16	3569
k_VBattMaxAAS_Volt_f32	4.82060003
k_VBattMaxBSI_Volt_f32	0.0835999995
k_VBattMaxCAV_Volt_f32	6.6079998
k_VBattMaxCMM388_Volt_f32	18.9309006
k_VBattMaxCMM_Volt_f32	6.3439002
k_VBattMaxESP_Volt_f32	6.67309999
k_VBattMinAAS_Volt_f32	27.1795006
k_VBattMinBSI_Volt_f32	6.67309999
k_VBattMinCAV_Volt_f32	2.6559
k_VBattMinCMM388_Volt_f32	21.0657005
k_VBattMinCMM_Volt_f32	15.0951996
k_VBattMinESP_Volt_f32	6.3439002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	39638
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	16806
k_VitesseVehicleBVRampValidThresh_Cnt_u16	53315
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	11337
k_VitesseVehicleBVSigValidThresh_Cnt_u16	48905
k_VitesseVehicleBVSpeedPassThresh_kph_f32	10.7748003
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	61012
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	6248
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1720839680
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	45704
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3854158080
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	153
target_SrlComInput_Per1_Batt_Volt_f32.value	23.7194996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2688278016
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	188
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	11
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0158556364
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4262333952
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	107
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2583375360
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	12078592
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	58
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	977628672
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1319276032
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	101
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1171238400
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	667733504
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	43
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	61
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	125
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	155
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	195
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1947102720
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	17
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	18
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	82
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	152
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	194
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3324579328
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	362163712
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4023602688
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	94
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	97
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	124
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	164
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	278093312
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	92
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.331199706
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	646399
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	124.606697
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	12871

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3854158080	3854158080	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	56214	56214	✔
CONSANGLECPK_HwDeg_M_f32	99.8860016	99.8860016 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3854158080	3854158080	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3854158080	3854158080	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3854158080	3854158080	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3854158080	3854158080	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3854158080	3854158080	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3854158080	3854158080	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	3854158080	3854158080	✔
ESPNTCEnableTimer_mS_M_u32	3854158080	3854158080	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3854158080	3854158080	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔
EffacDefaultDiagTimer_mS_M_u32[1]	87	87	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	20	20	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	21	21	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3854158080	3854158080	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDATDIRASentFltAcc_Cnt_M_u16	39837	39837	✔
ISDATDIRASentTimer_mS_M_u32	3854158080	3854158080	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3854158080	3854158080	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3854158080	3854158080	✔
IgnOnTimer_mS_M_u32	867438080	867438080	✔
IgnTimeOff_Sec_M_u32	192017353	192017353	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	241	241	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4262333952	4262333952	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	107	107	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2583375360	2583375360	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	43	43	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	12078592	12078592	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	58	58	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	977628672	977628672	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2666352128	2666352128	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	101	101	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1171238400	1171238400	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	144	144	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	667733504	667733504	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	105	105	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1947102720	1947102720	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3324579328	3324579328	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	245	245	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	362163712	362163712	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	200	200	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4023602688	4023602688	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	278093312	278093312	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	107.293198	107.293198	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	133.069199	133.069199	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	458.759308	458.759308	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	56214	56214	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	192017353	192017353	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	99.8860016	99.8860016 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.459 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1092978944
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	40234
AASNodeAbsentTimer_mS_M_u32	207075584
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	30668
ANGLEVOLANTSigValidCount_Cnt_M_u16	21466
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	11395
AngleVolantMsgTimer_mS_M_u32	1092978944
AngleVolantValidCount_Cnt_M_u16	20169
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1007974656
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2300639488
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3009915136
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	302475520
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	64391
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3543542016
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	8856
CAVNodeAbsentTimer_mS_M_u32	1042143488
CDD_SrlComVehSpd_Kph_G_f32	302.394989
CMM388NTCEnableTimer_mS_M_u32	3732740352
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3376142592
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	32095
CMMNodeAbsentTimer_mS_M_u32	191457536
CONSANGLECPKSigInvalidCount_Cnt_M_u16	46565
CONSANGLECPKSigValidCount_Cnt_M_u16	30466
CONSANGLECPK_Cnt_M_u16	32273
CONSANGLECPK_HwDeg_M_f32	381.248596
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	32273
CPKVehicleSpeedMsgTimer_mS_M_u32	632850688
CPKVehicleSpeedValidCount_Cnt_M_u16	14253

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	477
CityParkInputInvalidCount_Cnt_M_u16	23145
CityParkInputMsgTimer_mS_M_u32	4262333952
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2221652224
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	44606
ComputerRazGCTSigInvalidTimer_mS_M_u32	83122432
ComputerRazGCTSigValidCount_Cnt_M_u16	9614
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	21333
DMDFCTCPKSigValidCount_Cnt_M_u16	30123
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	7254
DMDRELAXECPKSigValidCount_Cnt_M_u16	11236
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	51774
DateInvalidTimer_mS_M_u32	2300639488
DiagMuxOnAbsentTimer_mS_M_u32	2947827968
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	302475520
ESPNTCEnableTimer_mS_M_u32	3833903360
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	34104
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	707
EffacDefaultDiagTimer_mS_M_u32[1]	1235
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	979
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1252010240
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	13423
EtatMTSigValidCount_Cnt_M_u16	5113
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	30831
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	60684
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	13001
ISDAT4V2BSI552MsgTimer_mS_M_u32	712861952
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	28137
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	32538
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	5113
ISDATBSI3F2MsgTimer_mS_M_u32	623528192
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	6666
ISDATBSI412MsgLenValidCount_Cnt_M_u16	23980
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	13423
ISDATBSI412MsgTimer_mS_M_u32	1151043840
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	33651
ISDATBSI432MsgLenValidCount_Cnt_M_u16	45644
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	41829
ISDATDIRASentFltAcc_Cnt_M_u16	5961
ISDATDIRASentTimer_mS_M_u32	632850688
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	16391
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	20169
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	53904
ISDYN2CMMMsgTimer_mS_M_u32	1348909312
ISDYNAASChkSumInvalidCount_Cnt_M_u16	23988
ISDYNAASChkSumValidCount_Cnt_M_u16	97
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	23556
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	63719
ISDYNAASMsgLenValidCount_Cnt_M_u16	33196
ISDYNAASMsgTimeValidCount_Cnt_M_u16	23988
ISDYNAASMsgTimer_mS_M_u32	3093895424
ISDYNABRChkSumInvalidCount_Cnt_M_u16	64814
ISDYNABRChkSumValidCount_Cnt_M_u16	43236
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	35695
ISDYNABRMsgCountValidCount_Cnt_M_u16	37980
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	10912
ISDYNABRMsgLenValidCount_Cnt_M_u16	37373
ISDYNABRMsgTimeValidCount_Cnt_M_u16	32273

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	57651
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	5113
ISDYNCMM208MsgTimer_mS_M_u32	1594194176
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	57651
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	19775
ISDYNCMM388MsgTimer_mS_M_u32	1948686592
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	33627
ISDYNVOLChkSumValidCount_Cnt_M_u16	37112
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	42955
ISDYNVOLMsgCountValidCount_Cnt_M_u16	22177
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	47741
ISDYNVOLMsgLenValidCount_Cnt_M_u16	38139
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	32095
ISDYNVOLMsgTimer_mS_M_u32	450910464
IgnOnTimer_mS_M_u32	3527055616
IgnTimeOff_Sec_M_u32	1372217406
ManVehSpd_Kph_M_f32	207.354996
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	83
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	11
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	106
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3601352960
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	108
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2592254208
PrevISDATBSI412MsgDLCError_Cnt_M_u08	103
PrevISDATBSI412MsgRxTime_MSec_M_u32	2930432256
PrevISDATBSI432MsgDLCError_Cnt_M_u08	205
PrevISDATBSI432MsgRxTime_MSec_M_u32	1397274880
PrevISDATDIRAMsgTxTime_MSec_M_u32	93247744
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	220
PrevISDYN2CMMMsgRxTime_MSec_M_u32	672065792
PrevISDYNAASMsgDLCError_Cnt_M_u08	162
PrevISDYNAASMsgRxTime_MSec_M_u32	2228640000
PrevISDYNABRMsgDLCError_Cnt_M_u08	36
PrevISDYNABRMsgRxTime_MSec_M_u32	1561499904
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	147
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3343341824
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	57
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2471999744
PrevISDYNVOLMsgDLCError_Cnt_M_u08	170
PrevISDYNVOLMsgRxTime_MSec_M_u32	2350110976
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	521242880
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	53.3081017
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	56157
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	28834
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	30754
VitesseVehicleBVRampValidCount_Cnt_M_u16	34599
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	55313

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	52703
VitesseVehicleBV_Kph_M_f32	240.054398
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	19775
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	16229
VitesseVehiculeRoues_Kph_M_f32	641.04187
k_AASNTCEnableTimeout_mS_u16	64484
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	16368
k_AASNodeTimeout_mS_u16	30626
k_ABSNodeTimeout_mS_u16	61190
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	15578
k_ANGLEVOLANTSigValidThresh_Cnt_u16	31475
k_AngleVolantInvalidThresh_Cnt_u16	8406
k_AngleVolantValidThresh_Cnt_u16	23145
k_BSI552MsgTimeout_mS_u16	12040
k_BSINTCEnableTimeout_mS_u16	48715
k_BSINodeAbsentDiag_Cnt_str.Threshold	13537
k_BSINodeAbsentDiag_Cnt_str.PStep	61147
k_BSINodeAbsentDiag_Cnt_str.NStep	49162
k_BSINodeAbsentTimeout_mS_u16	29019
k_BSINodeTimeout_mS_u16	41829
k_BattOvHi_Volt_f32	0.860000014
k_BattOvLo_Volt_f32	19.4004993
k_BattUvHi_Volt_f32	9.0447998
k_BattUvLo_Volt_f32	14.9251003
k_CAVNTCEnableTimeout_mS_u16	51127
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	9230
k_CAVNodeTimeout_mS_u16	10193
k_CMM388MsgTimeout_mS_u16	58410
k_CMM388NTCEnableTimeout_mS_u16	4886
k_CMMNTCEnableTimeout_mS_u16	54465
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	3153
k_CONSANGLECPKMax_HwDeg_f32	649.97168
k_CONSANGLECPKMin_HwDeg_f32	-412.443787
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	5183
k_CONSANGLECPKSigValidThresh_Cnt_u16	18021
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	21440
k_CPKVehicleSpeedValidThresh_Cnt_u16	41753
k_CityParkInputInvalidThresh_Cnt_u16	23500
k_CityParkInputValidThresh_Cnt_u16	477
k_ComputerRazGCTSigValidThresh_Cnt_u16	6119
k_CptTemporelSigValidThresh_Cnt_u16	19352
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	29088
k_DMDFCTCPKSigValidThresh_Cnt_u16	6397
k_DMDFCTCPKValidCount_Cnt_u16	52655
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	53904
k_DMDRELAXECPKSigValidThresh_Cnt_u16	31526
k_DMDRelaxeConsistentThresh_Cnt_u16	55620
k_DateValidThresh_Cnt_u16	13001
k_DefaultVehSpd_Kph_f32	224.164703
k_DiagMuxOnAbsentTimeout_mS_u16	28383
k_EMNodeTimeout_mS_u16	11294
k_ESPNTCEnableTimeout_mS_u16	61060
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	47481
k_EtatMTSigInvalidThresh_Cnt_u16	23409
k_EtatMTSigValidThresh_Cnt_u16	17255
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	25903
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	44057
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	26786
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	64994
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	18387
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	60958

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	3820
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	5765
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	51591
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	46085
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	25927
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	15487
k_ISDATDIRASentDiag_Cnt_str.Threshold	58959
k_ISDATDIRASentDiag_Cnt_str.PStep	33467
k_ISDATDIRASentDiag_Cnt_str.NStep	17654
k_ISDATDIRASentTimeout_mS_u16	21786
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	40048
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	11395
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	55488
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	50222
k_ISDYNAASChkSumValidThresh_Cnt_u16	45028
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	53871
k_ISDYNAASMsgCountValidThresh_Cnt_u16	7004
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	44098
k_ISDYNAASMsgLenValidThresh_Cnt_u16	8886
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	44571
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	1814
k_ISDYNABRChkSumValidThresh_Cnt_u16	64243
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	17031
k_ISDYNABRMsgCountValidThresh_Cnt_u16	17621
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	33887
k_ISDYNABRMsgLenValidThresh_Cnt_u16	52280
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	35832
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	42609
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	47375
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	49733
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	48844
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	56026
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	21313
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	57841
k_ISDYNVOLChkSumValidThresh_Cnt_u16	5331
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	30609
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	16120
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	57691
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	55781
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	52887
k_IgnOnTimeout_mS_u16	7645
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	143.387802
k_PowerCutVehSpdLowThresh_Kph_f32	1.92690003
k_PowerCutVehSpdLowTimeout_mS_u16	4864
k_VBattMaxAAS_Volt_f32	4.95009995
k_VBattMaxBSI_Volt_f32	28.7646008
k_VBattMaxCAV_Volt_f32	26.7549
k_VBattMaxCMM388_Volt_f32	11.7645998
k_VBattMaxCMM_Volt_f32	27.8372002
k_VBattMaxESP_Volt_f32	12.7666998
k_VBattMinAAS_Volt_f32	15.4427004
k_VBattMinBSI_Volt_f32	12.7666998
k_VBattMinCAV_Volt_f32	2.74289989
k_VBattMinCMM388_Volt_f32	31.3672009
k_VBattMinCMM_Volt_f32	4.90280008
k_VBattMinESP_Volt_f32	27.8372002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	61266
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	50340
k_VitesseVehicleBVRampValidThresh_Cnt_u16	28363
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	6136
k_VitesseVehicleBVSigValidThresh_Cnt_u16	59770
k_VitesseVehicleBVSpeedPassThresh_kph_f32	584.504272
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	59800
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	17693
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2300639488
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	2529
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	282421248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	57
target_SrlComInput_Per1_Batt_Volt_f32.value	3.78999996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	803416320
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	209
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.738501072
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1529649408
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	250
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	602224896
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3425556736
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1007057152
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1534007552
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	125
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	308787456
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1223710976
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	39
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	115
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	186
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	221
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	222
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4071323904
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	83
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	84
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	140
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	211
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	235
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	243
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	786143488
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	136
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3709090048
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	73
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	719116544
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	59
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	190
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	216
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	223
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2631706880
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	638
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.167369038
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	643110
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	164.518906
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	43455

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	282421248	282421248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	282421248	282421248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	282421248	282421248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	282421248	282421248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	282421248	282421248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	282421248	282421248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	282421248	282421248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	32273	32273	✔
CONSANGLECPK_HwDeg_M_f32	381.248596	381.248596 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	282421248	282421248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	282421248	282421248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	282421248	282421248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	282421248	282421248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	282421248	282421248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	282421248	282421248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	282421248	282421248	✔
ESPNTCEnableTimer_mS_M_u32	282421248	282421248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	282421248	282421248	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	282421248	282421248	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1235	1235	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	282421248	282421248	✔
ElecIntTimer_mS_M_u32[1]	979	979	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	282421248	282421248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	282421248	282421248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	58959	58959	✔
ISDATDIRASentTimer_mS_M_u32	282421248	282421248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	282421248	282421248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	282421248	282421248	✔
IgnOnTimer_mS_M_u32	3527055616	3527055616	✔
IgnTimeOff_Sec_M_u32	1372217406	1372217406	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	11	11	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	106	106	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1529649408	1529649408	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	250	250	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	602224896	602224896	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	245	245	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3425556736	3425556736	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	68	68	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1007057152	1007057152	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	93247744	93247744	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	125	125	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	308787456	308787456	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	55	55	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1223710976	1223710976	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	29	29	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4071323904	4071323904	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	243	243	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	786143488	786143488	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	136	136	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3709090048	3709090048	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	73	73	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	719116544	719116544	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2631706880	2631706880	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	53.3081017	53.3081017	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	240.054398	240.054398	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	641.04187	641.04187	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	32273	32273	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1372217406	1372217406	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	381.248596	381.248596 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.460 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	92818176
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	5552
AASNodeAbsentTimer_mS_M_u32	2378955520
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	51559
ANGLEVOLANTSigValidCount_Cnt_M_u16	5474
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	18385
AngleVolantMsgTimer_mS_M_u32	92818176
AngleVolantValidCount_Cnt_M_u16	11597
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3916348160
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3000974080
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3873139456
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	544811776
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	25338
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3911052032
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	33679
CAVNodeAbsentTimer_mS_M_u32	3401784064
CDD_SrlComVehSpd_Kph_G_f32	54.4373016
CMM388NTCEnableTimer_mS_M_u32	538729216
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3738245888
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	34318
CMMNodeAbsentTimer_mS_M_u32	3035310848
CONSANGLECPKSigInvalidCount_Cnt_M_u16	1606
CONSANGLECPKSigValidCount_Cnt_M_u16	57297
CONSANGLECPK_Cnt_M_u16	14168
CONSANGLECPK_HwDeg_M_f32	-586.772095
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	14168
CPKVehicleSpeedMsgTimer_mS_M_u32	3333638912
CPKVehicleSpeedValidCount_Cnt_M_u16	15905
CityParkInputConsistentCount_Cnt_M_u16	39169
CityParkInputInvalidCount_Cnt_M_u16	45039

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	3216832512
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3867147008
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	53092
ComputerRazGCTSigInvalidTimer_mS_M_u32	3964508928
ComputerRazGCTSigValidCount_Cnt_M_u16	49722
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	20539
DMDFCTCPKSigValidCount_Cnt_M_u16	21694
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	41537
DMDRELAXECPKSigValidCount_Cnt_M_u16	48572
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	58727
DateInvalidTimer_mS_M_u32	3000974080
DiagMuxOnAbsentTimer_mS_M_u32	3868003072
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	544811776
ESPNTCEnableTimer_mS_M_u32	1868626688
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	15413
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	8
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	735570688
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	36768
EtatMTSigValidCount_Cnt_M_u16	23287
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	60704
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	5675
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	10956
ISDAT4V2BSI552MsgTimer_mS_M_u32	3969854208
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	6121
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	57896
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	23287
ISDATBSI3F2MsgTimer_mS_M_u32	4155706112
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	42772
ISDATBSI412MsgLenValidCount_Cnt_M_u16	46915
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	36768
ISDATBSI412MsgTimer_mS_M_u32	346966784
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	56514
ISDATBSI432MsgLenValidCount_Cnt_M_u16	61929
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	21188
ISDATDIRASentFltAcc_Cnt_M_u16	1480
ISDATDIRASentTimer_mS_M_u32	3333638912
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	63742
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	11597
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	49486
ISDYN2CMMMsgTimer_mS_M_u32	173210368
ISDYNAASChkSumInvalidCount_Cnt_M_u16	60042
ISDYNAASChkSumValidCount_Cnt_M_u16	12837
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	40032
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	9302
ISDYNAASMsgLenValidCount_Cnt_M_u16	17098
ISDYNAASMsgTimeValidCount_Cnt_M_u16	60042
ISDYNAASMsgTimer_mS_M_u32	2842188544
ISDYNABRChkSumInvalidCount_Cnt_M_u16	15576
ISDYNABRChkSumValidCount_Cnt_M_u16	5563
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	32285
ISDYNABRMsgCountValidCount_Cnt_M_u16	24056
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	6361
ISDYNABRMsgLenValidCount_Cnt_M_u16	51876
ISDYNABRMsgTimeValidCount_Cnt_M_u16	14168
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	47707

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	23287
ISDYNCMM208MsgTimer_mS_M_u32	199736064
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	47707
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	3955
ISDYNCMM388MsgTimer_mS_M_u32	1058134784
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	12140
ISDYNVOLChkSumValidCount_Cnt_M_u16	47479
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	14433
ISDYNVOLMsgCountValidCount_Cnt_M_u16	11620
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	9122
ISDYNVOLMsgLenValidCount_Cnt_M_u16	57741
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	34318
ISDYNVOLMsgTimer_mS_M_u32	2442763008
IgnOnTimer_mS_M_u32	2915425024
IgnTimeOff_Sec_M_u32	1553002540
ManVehSpd_Kph_M_f32	356.645386
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	84
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	84
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1696664320
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	51
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4274940672
PrevISDATBSI412MsgDLCError_Cnt_M_u08	131
PrevISDATBSI412MsgRxTime_MSec_M_u32	129506048
PrevISDATBSI432MsgDLCError_Cnt_M_u08	32
PrevISDATBSI432MsgRxTime_MSec_M_u32	4098161408
PrevISDATDIRAMsgTxTime_MSec_M_u32	3049003776
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	153
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4072450816
PrevISDYNAASMsgDLCError_Cnt_M_u08	9
PrevISDYNAASMsgRxTime_MSec_M_u32	994024192
PrevISDYNABRMsgDLCError_Cnt_M_u08	94
PrevISDYNABRMsgRxTime_MSec_M_u32	1331550976
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	133
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2033752832
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	242
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1288436480
PrevISDYNVOLMsgDLCError_Cnt_M_u08	127
PrevISDYNVOLMsgRxTime_MSec_M_u32	2020154112
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3000257280
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	407.249115
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	2684
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	39280
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	38249
VitesseVehicleBVRampValidCount_Cnt_M_u16	27677
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	13268
VitesseVehicleBVSigValidCount_Cnt_M_u16	26511
VitesseVehicleBV_Kph_M_f32	277.903503

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	3955
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	57926
VitesseVehiculeRoues_Kph_M_f32	469.207886
k_AASNTCEnableTimeout_mS_u16	23491
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	32684
k_AASNodeTimeout_mS_u16	55408
k_ABSNodeTimeout_mS_u16	45428
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	14689
k_ANGLEVOLANTSigValidThresh_Cnt_u16	55240
k_AngleVolantInvalidThresh_Cnt_u16	58563
k_AngleVolantValidThresh_Cnt_u16	45039
k_BSI552MsgTimeout_mS_u16	34561
k_BSINTCEnableTimeout_mS_u16	44634
k_BSINodeAbsentDiag_Cnt_str.Threshold	33043
k_BSINodeAbsentDiag_Cnt_str.PStep	12643
k_BSINodeAbsentDiag_Cnt_str.NStep	27671
k_BSINodeAbsentTimeout_mS_u16	29545
k_BSINodeTimeout_mS_u16	21188
k_BattOvHi_Volt_f32	6.43359995
k_BattOvLo_Volt_f32	25.2080002
k_BattUvHi_Volt_f32	15.224
k_BattUvLo_Volt_f32	9.17739964
k_CAVNTCEnableTimeout_mS_u16	14253
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	32949
k_CAVNodeTimeout_mS_u16	59282
k_CMM388MsgTimeout_mS_u16	38064
k_CMM388NTCEnableTimeout_mS_u16	6908
k_CMMNTCEnableTimeout_mS_u16	30081
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	63122
k_CONSANGLECPKMax_HwDeg_f32	209.500397
k_CONSANGLECPKMin_HwDeg_f32	-331.451996
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	3699
k_CONSANGLECPKSigValidThresh_Cnt_u16	8518
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	50558
k_CPKVehicleSpeedValidThresh_Cnt_u16	37019
k_CityParkInputInvalidThresh_Cnt_u16	49254
k_CityParkInputValidThresh_Cnt_u16	39169
k_ComputerRazGCTSigValidThresh_Cnt_u16	16855
k_CptTemporelSigValidThresh_Cnt_u16	17046
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	38873
k_DMDFCTCPKSigValidThresh_Cnt_u16	35236
k_DMDFCTCPKValidCount_Cnt_u16	1634
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	49486
k_DMDRELAXECPKSigValidThresh_Cnt_u16	32273
k_DMDRelaxeConsistentThresh_Cnt_u16	64799
k_DateValidThresh_Cnt_u16	10956
k_DefaultVehSpd_Kph_f32	125.695
k_DiagMuxOnAbsentTimeout_mS_u16	24214
k_EMNodeTimeout_mS_u16	22087
k_ESPNTCEnableTimeout_mS_u16	36571
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	19706
k_EtatMTSigInvalidThresh_Cnt_u16	50483
k_EtatMTSigValidThresh_Cnt_u16	48214
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	31333
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	59420
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	15854
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	20394
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	6313
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	15304
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	60419
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	40938

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	29558
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	15596
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	10171
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	32563
k_ISDATDIRASentDiag_Cnt_str.Threshold	25385
k_ISDATDIRASentDiag_Cnt_str.PStep	45245
k_ISDATDIRASentDiag_Cnt_str.NStep	44580
k_ISDATDIRASentTimeout_mS_u16	13348
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	50860
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	18385
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	10999
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	15320
k_ISDYNAASChkSumValidThresh_Cnt_u16	21691
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	64797
k_ISDYNAASMsgCountValidThresh_Cnt_u16	7416
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	33932
k_ISDYNAASMsgLenValidThresh_Cnt_u16	64548
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	58416
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	51455
k_ISDYNABRChkSumValidThresh_Cnt_u16	27466
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	57850
k_ISDYNABRMsgCountValidThresh_Cnt_u16	34357
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	50446
k_ISDYNABRMsgLenValidThresh_Cnt_u16	47925
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	15984
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	20016
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	17985
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	45099
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	18535
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	54370
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	12167
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	34355
k_ISDYNVOLChkSumValidThresh_Cnt_u16	65442
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	59734
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	31855
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	33772
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	12355
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	21770
k_IgnOnTimeout_mS_u16	33151
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	219.703293
k_PowerCutVehSpdLowThresh_Kph_f32	242.554901
k_PowerCutVehSpdLowTimeout_mS_u16	35775
k_VBattMaxAAS_Volt_f32	17.7660999
k_VBattMaxBSI_Volt_f32	8.95979977
k_VBattMaxCAV_Volt_f32	10.0148001
k_VBattMaxCMM388_Volt_f32	6.71519995
k_VBattMaxCMM_Volt_f32	24.9759007
k_VBattMaxESP_Volt_f32	31.8474007
k_VBattMinAAS_Volt_f32	23.4475994
k_VBattMinBSI_Volt_f32	31.8474007
k_VBattMinCAV_Volt_f32	6.2802
k_VBattMinCMM388_Volt_f32	24.2621994
k_VBattMinCMM_Volt_f32	10.3143997
k_VBattMinESP_Volt_f32	24.9759007
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	32926
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	12286
k_VitesseVehicleBVRampValidThresh_Cnt_u16	14177
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	30839
k_VitesseVehicleBVSigValidThresh_Cnt_u16	34182
k_VitesseVehicleBVSpeedPassThresh_kph_f32	348.790009
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	33423
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	2499
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	0
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	536
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	146705152
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	242

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	26.3866005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1932716800
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	109
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.612483382
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	84
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3460815616
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	149
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3720706816
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1230183168
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	54
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	955300608
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3567147776
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	55
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1146878720
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2955516672
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	49
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	72
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	73
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	96
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	123
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	217
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2898115328
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	97
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	122
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	170
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	207
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	215
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1466882816
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	174
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2020375296
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	184
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3044678400
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	20
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	32
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	91
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	108
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	109
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	133
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2750966528
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1632
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.484900564
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	865538
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	60.3832016
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	7150

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	146705152	146705152	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	18387	18387	✔
AngleVolantMsgTimer_mS_M_u32	146705152	146705152	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	146705152	146705152	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	146705152	146705152	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	146705152	146705152	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	146705152	146705152	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	146705152	146705152	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	14168	14168	✔
CONSANGLECPK_HwDeg_M_f32	-586.772095	-586.772095 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	14168	14168	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3333638912	3333638912	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	15905	15905	✔
CityParkInputConsistentCount_Cnt_M_u16	39169	39169	✔
CityParkInputInvalidCount_Cnt_M_u16	45041	45041	✔
CityParkInputMsgTimer_mS_M_u32	146705152	146705152	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	146705152	146705152	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	146705152	146705152	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	146705152	146705152	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	146705152	146705152	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	146705152	146705152	✔
ESPNTCEnableTimer_mS_M_u32	146705152	146705152	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	146705152	146705152	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	146705152	146705152	✔
ElecIntTimer_mS_M_u32[1]	8	8	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	146705152	146705152	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	146705152	146705152	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	146705152	146705152	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	146705152	146705152	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	146705152	146705152	✔
IgnOnTimer_mS_M_u32	146705152	146705152	✔
IgnTimeOff_Sec_M_u32	193271680	193271680	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	84	84	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3460815616	3460815616	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	149	149	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3720706816	3720706816	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	173	173	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1230183168	1230183168	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	54	54	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	955300608	955300608	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3049003776	3049003776	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	55	55	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1146878720	1146878720	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	0	0	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2955516672	2955516672	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	217	217	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2898115328	2898115328	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	172	172	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1466882816	1466882816	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	174	174	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2020375296	2020375296	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	184	184	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3044678400	3044678400	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2750966528	2750966528	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	407.249115	407.249115	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	277.903503	277.903503	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	469.207886	469.207886	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	14168	14168	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	193271680	193271680	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-586.772095	-586.772095 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	125.695	125.695	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.461 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	99738112
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	6008
AASNodeAbsentTimer_mS_M_u32	1474744832
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	63060
ANGLEVOLANTSigValidCount_Cnt_M_u16	15139
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	17685
AngleVolantMsgTimer_mS_M_u32	99738112
AngleVolantValidCount_Cnt_M_u16	35618
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1073648128
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1168970240
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	376996352
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	278872576
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	13723
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	967901696
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	45659
CAVNodeAbsentTimer_mS_M_u32	3850465792
CDD_SrlComVehSpd_Kph_G_f32	348.92041
CMM388NTCEnableTimer_mS_M_u32	3665146368
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1633120768
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	61599
CMMNodeAbsentTimer_mS_M_u32	2605269504
CONSANGLECPKSigInvalidCount_Cnt_M_u16	10936
CONSANGLECPKSigValidCount_Cnt_M_u16	1751
CONSANGLECPK_Cnt_M_u16	56386
CONSANGLECPK_HwDeg_M_f32	-513.377686
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	56386
CPKVehicleSpeedMsgTimer_mS_M_u32	779149824
CPKVehicleSpeedValidCount_Cnt_M_u16	30574
CityParkInputConsistentCount_Cnt_M_u16	6150
CityParkInputInvalidCount_Cnt_M_u16	23611

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	3460815616
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	499831296
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	47708
ComputerRazGCTSigInvalidTimer_mS_M_u32	3403805184
ComputerRazGCTSigValidCount_Cnt_M_u16	49243
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	43863
DMDFCTCPKSigValidCount_Cnt_M_u16	59022
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	21446
DMDRELAXECPKSigValidCount_Cnt_M_u16	10773
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	20821
DateInvalidTimer_mS_M_u32	1168970240
DiagMuxOnAbsentTimer_mS_M_u32	1709416960
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	278872576
ESPNTCEnableTimer_mS_M_u32	1193792000
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	42730
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	87
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	21
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3649241600
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	60648
EtatMTSigValidCount_Cnt_M_u16	9123
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	24106
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	19401
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	7268
ISDAT4V2BSI552MsgTimer_mS_M_u32	3291300352
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	3982
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	59792
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	9123
ISDATBSI3F2MsgTimer_mS_M_u32	1248961024
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	7948
ISDATBSI412MsgLenValidCount_Cnt_M_u16	59199
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	60648
ISDATBSI412MsgTimer_mS_M_u32	4034912768
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	48259
ISDATBSI432MsgLenValidCount_Cnt_M_u16	21966
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	22716
ISDATDIRASentFltAcc_Cnt_M_u16	20400
ISDATDIRASentTimer_mS_M_u32	779149824
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	44880
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	35618
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	25630
ISDYN2CMMMsgTimer_mS_M_u32	3193033216
ISDYNAASChkSumInvalidCount_Cnt_M_u16	33002
ISDYNAASChkSumValidCount_Cnt_M_u16	21208
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	18921
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	44038
ISDYNAASMsgLenValidCount_Cnt_M_u16	22892
ISDYNAASMsgTimeValidCount_Cnt_M_u16	33002
ISDYNAASMsgTimer_mS_M_u32	1855042048
ISDYNABRChkSumInvalidCount_Cnt_M_u16	63362
ISDYNABRChkSumValidCount_Cnt_M_u16	13720
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	53809
ISDYNABRMsgCountValidCount_Cnt_M_u16	56159
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	65279
ISDYNABRMsgLenValidCount_Cnt_M_u16	21086
ISDYNABRMsgTimeValidCount_Cnt_M_u16	56386
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	43890
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	2127

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	9123
ISDYNCMM208MsgTimer_mS_M_u32	4237529600
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	43890
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	2127
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	64688
ISDYNCMM388MsgTimer_mS_M_u32	865415680
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	51014
ISDYNVOLChkSumValidCount_Cnt_M_u16	37349
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	2789
ISDYNVOLMsgCountValidCount_Cnt_M_u16	29852
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	58531
ISDYNVOLMsgLenValidCount_Cnt_M_u16	37793
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	61599
ISDYNVOLMsgTimer_mS_M_u32	184414720
IgnOnTimer_mS_M_u32	3078173184
IgnTimeOff_Sec_M_u32	977713101
ManVehSpd_Kph_M_f32	331.303497
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	82
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	65
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	975675904
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	129
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1520402944
PrevISDATBSI412MsgDLCError_Cnt_M_u08	204
PrevISDATBSI412MsgRxTime_MSec_M_u32	1117942272
PrevISDATBSI432MsgDLCError_Cnt_M_u08	114
PrevISDATBSI432MsgRxTime_MSec_M_u32	1216074240
PrevISDATDIRAMsgTxTime_MSec_M_u32	1217819136
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	154
PrevISDYN2CMMMsgRxTime_MSec_M_u32	131383808
PrevISDYNAASMsgDLCError_Cnt_M_u08	20
PrevISDYNAASMsgRxTime_MSec_M_u32	638317056
PrevISDYNABRMsgDLCError_Cnt_M_u08	236
PrevISDYNABRMsgRxTime_MSec_M_u32	850473472
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	150
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2418078208
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	239
PrevISDYNCMM388MsgRxTime_MSec_M_u32	451334656
PrevISDYNVOLMsgDLCError_Cnt_M_u08	235
PrevISDYNVOLMsgRxTime_MSec_M_u32	4103041536
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	772661760
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	649.314026
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	4500
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	28026
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	25805
VitesseVehicleBVRampValidCount_Cnt_M_u16	59763
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	43789
VitesseVehicleBVSigValidCount_Cnt_M_u16	14492
VitesseVehicleBV_Kph_M_f32	470.744812

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	64688
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	3318
VitesseVehiculeRoues_Kph_M_f32	100.655998
k_AASNTCEnableTimeout_mS_u16	56065
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	53253
k_AASNodeTimeout_mS_u16	45178
k_ABSNodeTimeout_mS_u16	43948
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	58022
k_ANGLEVOLANTSigValidThresh_Cnt_u16	57393
k_AngleVolantInvalidThresh_Cnt_u16	25920
k_AngleVolantValidThresh_Cnt_u16	23611
k_BSI552MsgTimeout_mS_u16	51909
k_BSINTCEnableTimeout_mS_u16	42939
k_BSINodeAbsentDiag_Cnt_str.Threshold	28392
k_BSINodeAbsentDiag_Cnt_str.PStep	49975
k_BSINodeAbsentDiag_Cnt_str.NStep	2138
k_BSINodeAbsentTimeout_mS_u16	8781
k_BSINodeTimeout_mS_u16	22716
k_BattOvHi_Volt_f32	4.92080021
k_BattOvLo_Volt_f32	8.23379993
k_BattUvHi_Volt_f32	27.1093998
k_BattUvLo_Volt_f32	3.70359993
k_CAVNTCEnableTimeout_mS_u16	15617
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	53993
k_CAVNodeTimeout_mS_u16	46804
k_CMM388MsgTimeout_mS_u16	39544
k_CMM388NTCEnableTimeout_mS_u16	14228
k_CMMNTCEnableTimeout_mS_u16	22214
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	18
k_CONSANGLECPKMax_HwDeg_f32	166.355606
k_CONSANGLECPKMin_HwDeg_f32	-34.9679985
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	65456
k_CONSANGLECPKSigValidThresh_Cnt_u16	20470
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	41296
k_CPKVehicleSpeedValidThresh_Cnt_u16	15991
k_CityParkInputInvalidThresh_Cnt_u16	9432
k_CityParkInputValidThresh_Cnt_u16	6150
k_ComputerRazGCTSigValidThresh_Cnt_u16	51652
k_CptTemporelSigValidThresh_Cnt_u16	70
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	33279
k_DMDFCTCPKSigValidThresh_Cnt_u16	5470
k_DMDFCTCPKValidCount_Cnt_u16	60259
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	25630
k_DMDRELAXECPKSigValidThresh_Cnt_u16	30357
k_DMDRelaxeConsistentThresh_Cnt_u16	45419
k_DateValidThresh_Cnt_u16	7268
k_DefaultVehSpd_Kph_f32	203.957108
k_DiagMuxOnAbsentTimeout_mS_u16	56968
k_EMNodeTimeout_mS_u16	32437
k_ESPNTCEnableTimeout_mS_u16	49271
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	40154
k_EtatMTSigInvalidThresh_Cnt_u16	35441
k_EtatMTSigValidThresh_Cnt_u16	28103
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	56987
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	44597
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	7487
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	44107
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	35341
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	12528
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	53952
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	36811

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	51303
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	7046
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	54232
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	9134
k_ISDATDIRASentDiag_Cnt_str.Threshold	25991
k_ISDATDIRASentDiag_Cnt_str.PStep	29762
k_ISDATDIRASentDiag_Cnt_str.NStep	4038
k_ISDATDIRASentTimeout_mS_u16	16798
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	28995
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	17685
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	23587
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	64130
k_ISDYNAASChkSumValidThresh_Cnt_u16	30872
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	21809
k_ISDYNAASMsgCountValidThresh_Cnt_u16	40543
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	61542
k_ISDYNAASMsgLenValidThresh_Cnt_u16	5470
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	23289
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	1677
k_ISDYNABRChkSumValidThresh_Cnt_u16	34924
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	47259
k_ISDYNABRMsgCountValidThresh_Cnt_u16	62634
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	13215
k_ISDYNABRMsgLenValidThresh_Cnt_u16	10730
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	30713
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	5752
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	13701
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	54601
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	31060
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	65059
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	15731
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	48559
k_ISDYNVOLChkSumValidThresh_Cnt_u16	18978
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	25479
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	53628
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	16388
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	54207
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	5546
k_IgnOnTimeout_mS_u16	64459
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	226.432205
k_PowerCutVehSpdLowThresh_Kph_f32	133.877502
k_PowerCutVehSpdLowTimeout_mS_u16	15117
k_VBattMaxAAS_Volt_f32	25.9843998
k_VBattMaxBSI_Volt_f32	24.1086006
k_VBattMaxCAV_Volt_f32	8.72949982
k_VBattMaxCMM388_Volt_f32	19.2084999
k_VBattMaxCMM_Volt_f32	22.0151997
k_VBattMaxESP_Volt_f32	18.6417999
k_VBattMinAAS_Volt_f32	26.5678005
k_VBattMinBSI_Volt_f32	18.6417999
k_VBattMinCAV_Volt_f32	31.3738995
k_VBattMinCMM388_Volt_f32	23.3829994
k_VBattMinCMM_Volt_f32	9.37749958
k_VBattMinESP_Volt_f32	22.0151997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	35693
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	13840
k_VitesseVehicleBVRampValidThresh_Cnt_u16	3557
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	21733
k_VitesseVehicleBVSigValidThresh_Cnt_u16	42615
k_VitesseVehicleBVSpeedPassThresh_kph_f32	207.449799
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	46427
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	10369
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	4294967295
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	163
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2773426688
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	239

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	18.3456001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	796000768
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	70
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0112911277
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	65
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3723702784
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	64
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	771379712
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	149
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2849075712
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3648557568
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1156559360
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1949749760
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4014862848
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	36
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	150
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	162
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4061237760
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	64
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	186
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2659070464
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	79
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3120910848
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	207
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3244061184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	118
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2468446720
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2808
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.609229386
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	199810
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	204.642395
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	9534

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2773426688	2773426688	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2773426688	2773426688	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2773426688	2773426688	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2773426688	2773426688	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2773426688	2773426688	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	56386	56386	✔
CONSANGLECPK_HwDeg_M_f32	-513.377686	-513.377686 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2773426688	2773426688	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2773426688	2773426688	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2773426688	2773426688	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2773426688	2773426688	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2773426688	2773426688	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2773426688	2773426688	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2773426688	2773426688	✔
ESPNTCEnableTimer_mS_M_u32	2773426688	2773426688	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2773426688	2773426688	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2773426688	2773426688	✔
EffacDefaultDiagTimer_mS_M_u32[1]	87	87	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	2773426688	2773426688	✔
ElecIntTimer_mS_M_u32[1]	21	21	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2773426688	2773426688	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2773426688	2773426688	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2773426688	2773426688	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2773426688	2773426688	✔
IgnOnTimer_mS_M_u32	2773426688	2773426688	✔
IgnTimeOff_Sec_M_u32	977713101	977713101	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	65	65	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3723702784	3723702784	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	64	64	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	771379712	771379712	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	149	149	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2849075712	2849075712	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3648557568	3648557568	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1217819136	1217819136	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	83	83	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1949749760	1949749760	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	151	151	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4014862848	4014862848	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4061237760	4061237760	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	246	246	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2659070464	2659070464	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	79	79	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3120910848	3120910848	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	207	207	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3244061184	3244061184	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2468446720	2468446720	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	649.314026	649.314026	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	470.744812	470.744812	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	100.655998	100.655998	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	56386	56386	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	977713101	977713101	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-513.377686	-513.377686 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	203.957108	203.957108	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.462 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1271995648
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	20797
AASNodeAbsentTimer_mS_M_u32	2511490304
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	50856
ANGLEVOLANTSigValidCount_Cnt_M_u16	32252
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	31846
AngleVolantMsgTimer_mS_M_u32	1271995648
AngleVolantValidCount_Cnt_M_u16	50879
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3966438656
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3042938112
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	4240260352
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	424213760
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	58579
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	353615104
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	54037
CAVNodeAbsentTimer_mS_M_u32	526544128
CDD_SrlComVehSpd_Kph_G_f32	455.389191
CMM388NTCEnableTimer_mS_M_u32	1636150528
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2212523264
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	18183
CMMNodeAbsentTimer_mS_M_u32	2706046208
CONSANGLECPKSigInvalidCount_Cnt_M_u16	26748
CONSANGLECPKSigValidCount_Cnt_M_u16	39393
CONSANGLECPK_Cnt_M_u16	34208
CONSANGLECPK_HwDeg_M_f32	-13.3704004
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	34208
CPKVehicleSpeedMsgTimer_mS_M_u32	2387877120
CPKVehicleSpeedValidCount_Cnt_M_u16	50563

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	45075
CityParkInputInvalidCount_Cnt_M_u16	18547
CityParkInputMsgTimer_mS_M_u32	3723702784
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3557182720
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	63633
ComputerRazGCTSigInvalidTimer_mS_M_u32	2436951296
ComputerRazGCTSigValidCount_Cnt_M_u16	19220
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	51999
DMDFCTCPKSigValidCount_Cnt_M_u16	16188
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	63058
DMDRELAXECPKSigValidCount_Cnt_M_u16	63782
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	43173
DateInvalidTimer_mS_M_u32	3042938112
DiagMuxOnAbsentTimer_mS_M_u32	586931456
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	424213760
ESPNTCEnableTimer_mS_M_u32	200232192
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	39400
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	707
EffacDefaultDiagTimer_mS_M_u32[1]	1235
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	979
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	4254973184
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	1835
EtatMTSigValidCount_Cnt_M_u16	39100
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	5670
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	4875
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	30138
ISDAT4V2BSI552MsgTimer_mS_M_u32	3063872768
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	27835
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	13428
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	39100
ISDATBSI3F2MsgTimer_mS_M_u32	760339712
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	1857
ISDATBSI412MsgLenValidCount_Cnt_M_u16	50281
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	1835
ISDATBSI412MsgTimer_mS_M_u32	1143414016
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	29531
ISDATBSI432MsgLenValidCount_Cnt_M_u16	7484
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	41970
ISDATDIRASentFltAcc_Cnt_M_u16	36630
ISDATDIRASentTimer_mS_M_u32	2387877120
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	50294
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	50879
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	31946
ISDYN2CMMMsgTimer_mS_M_u32	3463531776
ISDYNAASChkSumInvalidCount_Cnt_M_u16	23783
ISDYNAASChkSumValidCount_Cnt_M_u16	60636
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	26218
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	21012
ISDYNAASMsgLenValidCount_Cnt_M_u16	12193
ISDYNAASMsgTimeValidCount_Cnt_M_u16	23783
ISDYNAASMsgTimer_mS_M_u32	355577088
ISDYNABRChkSumInvalidCount_Cnt_M_u16	45215
ISDYNABRChkSumValidCount_Cnt_M_u16	39964
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	17682
ISDYNABRMsgCountValidCount_Cnt_M_u16	12103
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	51111
ISDYNABRMsgLenValidCount_Cnt_M_u16	37708
ISDYNABRMsgTimeValidCount_Cnt_M_u16	34208

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	57651
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	39100
ISDYNCMM208MsgTimer_mS_M_u32	1252789504
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	57651
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	10773
ISDYNCMM388MsgTimer_mS_M_u32	874982656
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	19154
ISDYNVOLChkSumValidCount_Cnt_M_u16	45239
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	25717
ISDYNVOLMsgCountValidCount_Cnt_M_u16	19730
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	1213
ISDYNVOLMsgLenValidCount_Cnt_M_u16	15746
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	18183
ISDYNVOLMsgTimer_mS_M_u32	1089268992
IgnOnTimer_mS_M_u32	947596544
IgnTimeOff_Sec_M_u32	1274119442
ManVehSpd_Kph_M_f32	466.577789
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	83
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	32
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3056590080
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	197
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2353544448
PrevISDATBSI412MsgDLCError_Cnt_M_u08	50
PrevISDATBSI412MsgRxTime_MSec_M_u32	3422514432
PrevISDATBSI432MsgDLCError_Cnt_M_u08	207
PrevISDATBSI432MsgRxTime_MSec_M_u32	1475562752
PrevISDATDIRAMsgTxTime_MSec_M_u32	2317577472
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	159
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3920133376
PrevISDYNAASMsgDLCError_Cnt_M_u08	208
PrevISDYNAASMsgRxTime_MSec_M_u32	2814569728
PrevISDYNABRMsgDLCError_Cnt_M_u08	192
PrevISDYNABRMsgRxTime_MSec_M_u32	2798857472
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	98
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4253281536
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	126
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1286753536
PrevISDYNVOLMsgDLCError_Cnt_M_u08	157
PrevISDYNVOLMsgRxTime_MSec_M_u32	2855824640
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1132272896
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	72.1018982
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	55658
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	43895
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	959
VitesseVehicleBVRampValidCount_Cnt_M_u16	23436
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	52349

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	43409
VitesseVehicleBV_Kph_M_f32	338.6073
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	10773
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	24321
VitesseVehiculeRoues_Kph_M_f32	181.060898
k_AASNTCEnableTimeout_mS_u16	17763
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	17430
k_AASNodeTimeout_mS_u16	57975
k_ABSNodeTimeout_mS_u16	24096
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	19698
k_ANGLEVOLANTSigValidThresh_Cnt_u16	51731
k_AngleVolantInvalidThresh_Cnt_u16	14054
k_AngleVolantValidThresh_Cnt_u16	18547
k_BSI552MsgTimeout_mS_u16	8596
k_BSINTCEnableTimeout_mS_u16	37299
k_BSINodeAbsentDiag_Cnt_str.Threshold	13537
k_BSINodeAbsentDiag_Cnt_str.PStep	61147
k_BSINodeAbsentDiag_Cnt_str.NStep	49162
k_BSINodeAbsentTimeout_mS_u16	50366
k_BSINodeTimeout_mS_u16	41970
k_BattOvHi_Volt_f32	30.5473995
k_BattOvLo_Volt_f32	4.19969988
k_BattUvHi_Volt_f32	13.3030005
k_BattUvLo_Volt_f32	13.1564999
k_CAVNTCEnableTimeout_mS_u16	15905
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	10603
k_CAVNodeTimeout_mS_u16	13352
k_CMM388MsgTimeout_mS_u16	51261
k_CMM388NTCEnableTimeout_mS_u16	24809
k_CMMNTCEnableTimeout_mS_u16	30483
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	62893
k_CONSANGLECPKMax_HwDeg_f32	732.385498
k_CONSANGLECPKMin_HwDeg_f32	-204.101898
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	8469
k_CONSANGLECPKSigValidThresh_Cnt_u16	38401
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	59381
k_CPKVehicleSpeedValidThresh_Cnt_u16	5376
k_CityParkInputInvalidThresh_Cnt_u16	157
k_CityParkInputValidThresh_Cnt_u16	45075
k_ComputerRazGCTSigValidThresh_Cnt_u16	38425
k_CptTemporelSigValidThresh_Cnt_u16	18514
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	16039
k_DMDFCTCPKSigValidThresh_Cnt_u16	19020
k_DMDFCTCPKValidCount_Cnt_u16	58235
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	31946
k_DMDRELAXECPKSigValidThresh_Cnt_u16	27431
k_DMDRelaxeConsistentThresh_Cnt_u16	37541
k_DateValidThresh_Cnt_u16	30138
k_DefaultVehSpd_Kph_f32	110.280197
k_DiagMuxOnAbsentTimeout_mS_u16	5838
k_EMNodeTimeout_mS_u16	41093
k_ESPNTCEnableTimeout_mS_u16	6337
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	16213
k_EtatMTSigInvalidThresh_Cnt_u16	29650
k_EtatMTSigValidThresh_Cnt_u16	28559
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	7188
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	25349
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	50280
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	51844
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	34557
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	24981

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	25764
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	41797
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	57263
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	55252
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	17565
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	21082
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	16971
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	64923
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	31846
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	62909
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	42911
k_ISDYNAASChkSumValidThresh_Cnt_u16	54044
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	48146
k_ISDYNAASMsgCountValidThresh_Cnt_u16	58951
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	22003
k_ISDYNAASMsgLenValidThresh_Cnt_u16	17355
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	31163
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	26877
k_ISDYNABRChkSumValidThresh_Cnt_u16	43298
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	23507
k_ISDYNABRMsgCountValidThresh_Cnt_u16	11623
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	32263
k_ISDYNABRMsgLenValidThresh_Cnt_u16	4328
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	40826
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	23230
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	59350
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	28682
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	15784
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	13564
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	33995
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	30552
k_ISDYNVOLChkSumValidThresh_Cnt_u16	59328
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	6161
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	22640
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	32215
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	63592
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	8680
k_IgnOnTimeout_mS_u16	11524
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	153.354904
k_PowerCutVehSpdLowThresh_Kph_f32	247.018997
k_PowerCutVehSpdLowTimeout_mS_u16	21823
k_VBattMaxAAS_Volt_f32	1.98810005
k_VBattMaxBSI_Volt_f32	26.5004997
k_VBattMaxCAV_Volt_f32	10.2793999
k_VBattMaxCMM388_Volt_f32	10.1021996
k_VBattMaxCMM_Volt_f32	26.9155006
k_VBattMaxESP_Volt_f32	18.3120003
k_VBattMinAAS_Volt_f32	13.3542995
k_VBattMinBSI_Volt_f32	18.3120003
k_VBattMinCAV_Volt_f32	7.02479982
k_VBattMinCMM388_Volt_f32	25.1322002
k_VBattMinCMM_Volt_f32	3.69460011
k_VBattMinESP_Volt_f32	26.9155006
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	55069
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	44277
k_VitesseVehicleBVRampValidThresh_Cnt_u16	23413
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	26551
k_VitesseVehicleBVSigValidThresh_Cnt_u16	2240
k_VitesseVehicleBVSpeedPassThresh_kph_f32	624.059204
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	51733
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	22114
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3042938112
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	103
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1924750592
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	126
target_SrlComInput_Per1_Batt_Volt_f32.value	24.6072006
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2010168576
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	27
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	4
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.00649284385
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	32
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	755838208
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3245853952
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	309488896
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2281508096
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2316807424
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	184
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2160217344
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3556568320
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	191
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	207
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	227
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3794930944
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	90
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	123
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	139
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	147
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	164
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3614190848
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	159
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	156683520
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	66
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3083955456
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	9
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	57
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	176
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1791114496
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	611
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.142412454
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	200167
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	181.974304
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	50796

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1924750592	1924750592	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	31846	31846	✔
AngleVolantMsgTimer_mS_M_u32	1924750592	1924750592	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1924750592	1924750592	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1924750592	1924750592	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1924750592	1924750592	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	34208	34208	✔
CONSANGLECPK_HwDeg_M_f32	-13.3704004	-13.3704004 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	34208	34208	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2387877120	2387877120	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	50563	50563	✔
CityParkInputConsistentCount_Cnt_M_u16	45075	45075	✔
CityParkInputInvalidCount_Cnt_M_u16	18547	18547	✔
CityParkInputMsgTimer_mS_M_u32	1924750592	1924750592	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1924750592	1924750592	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1924750592	1924750592	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1924750592	1924750592	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1924750592	1924750592	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1924750592	1924750592	✔
ESPNTCEnableTimer_mS_M_u32	1924750592	1924750592	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1924750592	1924750592	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	1924750592	1924750592	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1235	1235	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1924750592	1924750592	✔
ElecIntTimer_mS_M_u32[1]	979	979	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1924750592	1924750592	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1924750592	1924750592	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1924750592	1924750592	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1924750592	1924750592	✔
IgnOnTimer_mS_M_u32	1924750592	1924750592	✔
IgnTimeOff_Sec_M_u32	1274119442	1274119442	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	32	32	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	755838208	755838208	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	222	222	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3245853952	3245853952	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	3	3	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	309488896	309488896	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	154	154	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2281508096	2281508096	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2317577472	2317577472	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	184	184	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2160217344	2160217344	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	16	16	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3556568320	3556568320	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3794930944	3794930944	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3614190848	3614190848	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	159	159	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	156683520	156683520	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	66	66	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3083955456	3083955456	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1791114496	1791114496	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	72.1018982	72.1018982	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	338.6073	338.6073	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	181.060898	181.060898	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	34208	34208	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1274119442	1274119442	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-13.3704004	-13.3704004 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	110.280197	110.280197	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.463 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	350186496
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	22169
AASNodeAbsentTimer_mS_M_u32	2012994560
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	49242
ANGLEVOLANTSigValidCount_Cnt_M_u16	2332
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	47390
AngleVolantMsgTimer_mS_M_u32	350186496
AngleVolantValidCount_Cnt_M_u16	33941
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1188142080
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1576279040
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1520110592
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3824667648
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	53721
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2341964800
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	55697
CAVNodeAbsentTimer_mS_M_u32	1131117568
CDD_SrlComVehSpd_Kph_G_f32	78.7373962
CMM388NTCEnableTimer_mS_M_u32	436321280
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2381413376
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	61819
CMMNodeAbsentTimer_mS_M_u32	3555838976
CONSANGLECPKSigInvalidCount_Cnt_M_u16	7644
CONSANGLECPKSigValidCount_Cnt_M_u16	14446
CONSANGLECPK_Cnt_M_u16	12593
CONSANGLECPK_HwDeg_M_f32	130.973999
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	12593
CPKVehicleSpeedMsgTimer_mS_M_u32	425094144
CPKVehicleSpeedValidCount_Cnt_M_u16	56655

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	6297
CityParkInputInvalidCount_Cnt_M_u16	8312
CityParkInputMsgTimer_mS_M_u32	755838208
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	218094592
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	45213
ComputerRazGCTSigInvalidTimer_mS_M_u32	2278554624
ComputerRazGCTSigValidCount_Cnt_M_u16	35734
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	18548
DMDFCTCPKSigValidCount_Cnt_M_u16	31454
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	22876
DMDRELAXECPKSigValidCount_Cnt_M_u16	49054
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	16737
DateInvalidTimer_mS_M_u32	1576279040
DiagMuxOnAbsentTimer_mS_M_u32	2858363904
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3824667648
ESPNTCEnableTimer_mS_M_u32	1229249536
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	38809
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	8
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2046397440
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	37390
EtatMTSigValidCount_Cnt_M_u16	15388
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	15582
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	62704
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20324
ISDAT4V2BSI552MsgTimer_mS_M_u32	3824536576
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	63711
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	41077
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	15388
ISDATBSI3F2MsgTimer_mS_M_u32	1667050496
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	52815
ISDATBSI412MsgLenValidCount_Cnt_M_u16	21909
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	37390
ISDATBSI412MsgTimer_mS_M_u32	64842752
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	48255
ISDATBSI432MsgLenValidCount_Cnt_M_u16	23965
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	6906
ISDATDIRASentFltAcc_Cnt_M_u16	59790
ISDATDIRASentTimer_mS_M_u32	425094144
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	19631
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	33941
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	40819
ISDYN2CMMMsgTimer_mS_M_u32	2310986752
ISDYNAASChkSumInvalidCount_Cnt_M_u16	23451
ISDYNAASChkSumValidCount_Cnt_M_u16	39549
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	4500
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	6292
ISDYNAASMsgLenValidCount_Cnt_M_u16	52910
ISDYNAASMsgTimeValidCount_Cnt_M_u16	23451
ISDYNAASMsgTimer_mS_M_u32	2935864320
ISDYNABRChkSumInvalidCount_Cnt_M_u16	14834
ISDYNABRChkSumValidCount_Cnt_M_u16	34364
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	3866
ISDYNABRMsgCountValidCount_Cnt_M_u16	16188
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	27739
ISDYNABRMsgLenValidCount_Cnt_M_u16	47149
ISDYNABRMsgTimeValidCount_Cnt_M_u16	12593

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	47707
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	15388
ISDYNCMM208MsgTimer_mS_M_u32	1880005632
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	47707
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	12947
ISDYNCMM388MsgTimer_mS_M_u32	136133632
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	20186
ISDYNVOLChkSumValidCount_Cnt_M_u16	52204
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	21618
ISDYNVOLMsgCountValidCount_Cnt_M_u16	10588
ISDYNVOLMsgCount_Cnt_M_u08	4
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	60186
ISDYNVOLMsgLenValidCount_Cnt_M_u16	28556
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	61819
ISDYNVOLMsgTimer_mS_M_u32	684456960
IgnOnTimer_mS_M_u32	1260469248
IgnTimeOff_Sec_M_u32	2881647345
ManVehSpd_Kph_M_f32	170.158295
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	84
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3234016256
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	223
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2549746688
PrevISDATBSI412MsgDLCError_Cnt_M_u08	177
PrevISDATBSI412MsgRxTime_MSec_M_u32	4053040128
PrevISDATBSI432MsgDLCError_Cnt_M_u08	48
PrevISDATBSI432MsgRxTime_MSec_M_u32	1966660608
PrevISDATDIRAMsgTxTime_MSec_M_u32	1193835520
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	225
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1356418048
PrevISDYNAASMsgDLCError_Cnt_M_u08	117
PrevISDYNAASMsgRxTime_MSec_M_u32	3427400704
PrevISDYNABRMsgDLCError_Cnt_M_u08	57
PrevISDYNABRMsgRxTime_MSec_M_u32	1612266496
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	117
PrevISDYNCMM208MsgRxTime_MSec_M_u32	252115968
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	170
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1392237568
PrevISDYNVOLMsgDLCError_Cnt_M_u08	18
PrevISDYNVOLMsgRxTime_MSec_M_u32	2062121984
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3722144768
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	0
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	23186
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	13100
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	28563
VitesseVehicleBVRampValidCount_Cnt_M_u16	46829
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	17115

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	6749
VitesseVehicleBV_Kph_M_f32	339.348999
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	12947
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	25228
VitesseVehiculeRoues_Kph_M_f32	21.0475006
k_AASNTCEnableTimeout_mS_u16	48616
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	10384
k_AASNodeTimeout_mS_u16	36396
k_ABSNodeTimeout_mS_u16	54129
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	19386
k_ANGLEVOLANTSigValidThresh_Cnt_u16	29464
k_AngleVolantInvalidThresh_Cnt_u16	14495
k_AngleVolantValidThresh_Cnt_u16	8312
k_BSI552MsgTimeout_mS_u16	9939
k_BSINTCEnableTimeout_mS_u16	49527
k_BSINodeAbsentDiag_Cnt_str.Threshold	33043
k_BSINodeAbsentDiag_Cnt_str.PStep	12643
k_BSINodeAbsentDiag_Cnt_str.NStep	27671
k_BSINodeAbsentTimeout_mS_u16	16406
k_BSINodeTimeout_mS_u16	6906
k_BattOvHi_Volt_f32	2.12190008
k_BattOvLo_Volt_f32	0.391200006
k_BattUvHi_Volt_f32	3.3915
k_BattUvLo_Volt_f32	19.9221001
k_CAVNTCEnableTimeout_mS_u16	30574
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	44687
k_CAVNodeTimeout_mS_u16	27352
k_CMM388MsgTimeout_mS_u16	61849
k_CMM388NTCEnableTimeout_mS_u16	55189
k_CMMNTCEnableTimeout_mS_u16	14807
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	20104
k_CONSANGLECPKMax_HwDeg_f32	409.196991
k_CONSANGLECPKMin_HwDeg_f32	-734.966919
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	19859
k_CONSANGLECPKSigValidThresh_Cnt_u16	48524
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	62898
k_CPKVehicleSpeedValidThresh_Cnt_u16	24850
k_CityParkInputInvalidThresh_Cnt_u16	49656
k_CityParkInputValidThresh_Cnt_u16	6297
k_ComputerRazGCTSigValidThresh_Cnt_u16	29893
k_CptTemporelSigValidThresh_Cnt_u16	23771
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	1883
k_DMDFCTCPKSigValidThresh_Cnt_u16	37677
k_DMDFCTCPKValidCount_Cnt_u16	30177
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	40819
k_DMDRELAXECPKSigValidThresh_Cnt_u16	25373
k_DMDRelaxeConsistentThresh_Cnt_u16	25763
k_DateValidThresh_Cnt_u16	20324
k_DefaultVehSpd_Kph_f32	79.9825974
k_DiagMuxOnAbsentTimeout_mS_u16	46503
k_EMNodeTimeout_mS_u16	55745
k_ESPNTCEnableTimeout_mS_u16	47245
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	4496
k_EtatMTSigInvalidThresh_Cnt_u16	31833
k_EtatMTSigValidThresh_Cnt_u16	38883
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	38229
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	40771
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	28570
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	17284
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	3290
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	3923

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	19620
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	12162
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	51075
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	2709
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	763
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	57859
k_ISDATDIRASentDiag_Cnt_str.Threshold	2451
k_ISDATDIRASentDiag_Cnt_str.PStep	5266
k_ISDATDIRASentDiag_Cnt_str.NStep	3881
k_ISDATDIRASentTimeout_mS_u16	13550
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	9280
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	47390
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	4505
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	21746
k_ISDYNAASChkSumValidThresh_Cnt_u16	57660
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	43546
k_ISDYNAASMsgCountValidThresh_Cnt_u16	6716
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	39414
k_ISDYNAASMsgLenValidThresh_Cnt_u16	47664
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	1056
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	24665
k_ISDYNABRChkSumValidThresh_Cnt_u16	20139
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	27865
k_ISDYNABRMsgCountValidThresh_Cnt_u16	26331
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	19579
k_ISDYNABRMsgLenValidThresh_Cnt_u16	12953
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	7330
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	9878
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	49296
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	61811
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	23386
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	58396
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	52080
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	39434
k_ISDYNVOLChkSumValidThresh_Cnt_u16	1936
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	286
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	41280
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	56842
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	52504
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	33498
k_IgnOnTimeout_mS_u16	10502
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	131.258499
k_PowerCutVehSpdLowThresh_Kph_f32	146.266296
k_PowerCutVehSpdLowTimeout_mS_u16	65108
k_VBattMaxAAS_Volt_f32	20.4386997
k_VBattMaxBSI_Volt_f32	22.2472
k_VBattMaxCAV_Volt_f32	26.9857998
k_VBattMaxCMM388_Volt_f32	32
k_VBattMaxCMM_Volt_f32	5.59800005
k_VBattMaxESP_Volt_f32	21.5795002
k_VBattMinAAS_Volt_f32	12.9912996
k_VBattMinBSI_Volt_f32	21.5795002
k_VBattMinCAV_Volt_f32	7.71330023
k_VBattMinCMM388_Volt_f32	3.98690009
k_VBattMinCMM_Volt_f32	27.6620998
k_VBattMinESP_Volt_f32	5.59800005
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	8122
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	7408
k_VitesseVehicleBVRampValidThresh_Cnt_u16	28530
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	42732
k_VitesseVehicleBVSigValidThresh_Cnt_u16	658
k_VitesseVehicleBVSpeedPassThresh_kph_f32	339.953094
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	62609
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	40555
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1576279040
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	61949
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2435230720
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	170
target_SrlComInput_Per1_Batt_Volt_f32.value	9.40639973
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2539686912
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	237
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.063242726
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	896220160
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	147
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3937098752
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2856025088
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1008442368
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1749793792
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	206
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4140555264
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	89
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2946235392
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	37
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	73
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	88
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	158
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	185
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	187
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	225
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1098685440
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	114
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	142
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	155
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	192
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	201
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1917729792
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	139
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1326341120
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	52
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4129192960
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	74
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	137
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	156
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	194
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1686899712
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	121
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.40669629
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	860206
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	155.650299
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	7052

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2435230720	2435230720	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2435230720	2435230720	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2435230720	2435230720	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2435230720	2435230720	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2435230720	2435230720	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	12593	12593	✔
CONSANGLECPK_HwDeg_M_f32	130.973999	130.973999 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2435230720	2435230720	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2435230720	2435230720	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2435230720	2435230720	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2435230720	2435230720	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2435230720	2435230720	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2435230720	2435230720	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2435230720	2435230720	✔
ESPNTCEnableTimer_mS_M_u32	2435230720	2435230720	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2435230720	2435230720	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	2435230720	2435230720	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2435230720	2435230720	✔
ElecIntTimer_mS_M_u32[1]	8	8	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2435230720	2435230720	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDATDIRASentFltAcc_Cnt_M_u16	2451	2451	✔
ISDATDIRASentTimer_mS_M_u32	2435230720	2435230720	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2435230720	2435230720	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	4	4	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2435230720	2435230720	✔
IgnOnTimer_mS_M_u32	2435230720	2435230720	✔
IgnTimeOff_Sec_M_u32	2881647345	2881647345	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	152	152	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	896220160	896220160	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	147	147	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3937098752	3937098752	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	180	180	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2856025088	2856025088	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1008442368	1008442368	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1193835520	1193835520	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	206	206	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4140555264	4140555264	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	89	89	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2946235392	2946235392	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	192	192	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1098685440	1098685440	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	201	201	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1917729792	1917729792	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	139	139	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1326341120	1326341120	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	52	52	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4129192960	4129192960	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1686899712	1686899712	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	0	0	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	339.348999	339.348999	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	21.0475006	21.0475006	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	12593	12593	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2881647345	2881647345	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	130.973999	130.973999 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	79.9825974	79.9825974	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.464 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2578480896
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	56960
AASNodeAbsentTimer_mS_M_u32	2921017088
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	17215
ANGLEVOLANTSigValidCount_Cnt_M_u16	7353
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	2801
AngleVolantMsgTimer_mS_M_u32	2578480896
AngleVolantValidCount_Cnt_M_u16	43279
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3365531392
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	758279936
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3204292352
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2246532864
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	51906
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3188203264
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	15386
CAVNodeAbsentTimer_mS_M_u32	306990848
CDD_SrlComVehSpd_Kph_G_f32	518.982971
CMM388NTCEnableTimer_mS_M_u32	3079245568
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3401207552
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	39195
CMMNodeAbsentTimer_mS_M_u32	502882048
CONSANGLECPKSigInvalidCount_Cnt_M_u16	25018
CONSANGLECPKSigValidCount_Cnt_M_u16	1476
CONSANGLECPK_Cnt_M_u16	59259
CONSANGLECPK_HwDeg_M_f32	521.029297
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	59259
CPKVehicleSpeedMsgTimer_mS_M_u32	676036352
CPKVehicleSpeedValidCount_Cnt_M_u16	49097
CityParkInputConsistentCount_Cnt_M_u16	64771
CityParkInputInvalidCount_Cnt_M_u16	29285

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	896220160
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4279185152
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	57460
ComputerRazGCTSigInvalidTimer_mS_M_u32	1998507776
ComputerRazGCTSigValidCount_Cnt_M_u16	55308
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	60017
DMDFCTCPKSigValidCount_Cnt_M_u16	42740
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	57
DMDRELAXECPKSigValidCount_Cnt_M_u16	33075
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	19243
DateInvalidTimer_mS_M_u32	758279936
DiagMuxOnAbsentTimer_mS_M_u32	2284928768
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2246532864
ESPNTCEnableTimer_mS_M_u32	2655006464
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	51841
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	87
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	21
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	4209123072
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	5217
EtatMTSigValidCount_Cnt_M_u16	63991
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	36020
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	22590
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	49506
ISDAT4V2BSI552MsgTimer_mS_M_u32	4260192000
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	6512
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	9838
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	63991
ISDATBSI3F2MsgTimer_mS_M_u32	3577167616
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	43551
ISDATBSI412MsgLenValidCount_Cnt_M_u16	55310
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	5217
ISDATBSI412MsgTimer_mS_M_u32	1152810752
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	18447
ISDATBSI432MsgLenValidCount_Cnt_M_u16	34933
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	23519
ISDATDIRASentFltAcc_Cnt_M_u16	16419
ISDATDIRASentTimer_mS_M_u32	676036352
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	3329
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	43279
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	41332
ISDYN2CMMMsgTimer_mS_M_u32	1154625280
ISDYNAASChkSumInvalidCount_Cnt_M_u16	22394
ISDYNAASChkSumValidCount_Cnt_M_u16	52885
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	48658
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	19217
ISDYNAASMsgLenValidCount_Cnt_M_u16	15491
ISDYNAASMsgTimeValidCount_Cnt_M_u16	22394
ISDYNAASMsgTimer_mS_M_u32	3902115584
ISDYNABRChkSumInvalidCount_Cnt_M_u16	12278
ISDYNABRChkSumValidCount_Cnt_M_u16	7896
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	63741
ISDYNABRMsgCountValidCount_Cnt_M_u16	40024
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	12861
ISDYNABRMsgLenValidCount_Cnt_M_u16	17031
ISDYNABRMsgTimeValidCount_Cnt_M_u16	59259
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	43890
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	2127

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	63991
ISDYNCMM208MsgTimer_mS_M_u32	2162355968
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	43890
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	2127
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	5909
ISDYNCMM388MsgTimer_mS_M_u32	3140947712
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	18112
ISDYNVOLChkSumValidCount_Cnt_M_u16	49994
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	15991
ISDYNVOLMsgCountValidCount_Cnt_M_u16	4986
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	5118
ISDYNVOLMsgLenValidCount_Cnt_M_u16	64104
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	39195
ISDYNVOLMsgTimer_mS_M_u32	2217398016
IgnOnTimer_mS_M_u32	36376320
IgnTimeOff_Sec_M_u32	2314011855
ManVehSpd_Kph_M_f32	526.100525
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	82
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	140
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3573890816
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	144
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1122017024
PrevISDATBSI412MsgDLCError_Cnt_M_u08	211
PrevISDATBSI412MsgRxTime_MSec_M_u32	3956363008
PrevISDATBSI432MsgDLCError_Cnt_M_u08	79
PrevISDATBSI432MsgRxTime_MSec_M_u32	3932434176
PrevISDATDIRAMsgTxTime_MSec_M_u32	991252224
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	215
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2772623104
PrevISDYNAASMsgDLCError_Cnt_M_u08	172
PrevISDYNAASMsgRxTime_MSec_M_u32	296800000
PrevISDYNABRMsgDLCError_Cnt_M_u08	158
PrevISDYNABRMsgRxTime_MSec_M_u32	2739080960
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	140
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2105134848
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	78
PrevISDYNCMM388MsgRxTime_MSec_M_u32	488320768
PrevISDYNVOLMsgDLCError_Cnt_M_u08	197
PrevISDYNVOLMsgRxTime_MSec_M_u32	3822210816
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	784105216
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	655.340027
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	64791
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	34569
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	532
VitesseVehicleBVRampValidCount_Cnt_M_u16	16326
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	65468
VitesseVehicleBVSigValidCount_Cnt_M_u16	11510
VitesseVehicleBV_Kph_M_f32	6.35010004

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	5909
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	6887
VitesseVehiculeRoues_Kph_M_f32	52.3774986
k_AASNTCEnableTimeout_mS_u16	56662
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	26910
k_AASNodeTimeout_mS_u16	30217
k_ABSNodeTimeout_mS_u16	32122
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	18014
k_ANGLEVOLANTSigValidThresh_Cnt_u16	62468
k_AngleVolantInvalidThresh_Cnt_u16	32623
k_AngleVolantValidThresh_Cnt_u16	29285
k_BSI552MsgTimeout_mS_u16	43538
k_BSINTCEnableTimeout_mS_u16	6439
k_BSINodeAbsentDiag_Cnt_str.Threshold	28392
k_BSINodeAbsentDiag_Cnt_str.PStep	49975
k_BSINodeAbsentDiag_Cnt_str.NStep	2138
k_BSINodeAbsentTimeout_mS_u16	22025
k_BSINodeTimeout_mS_u16	23519
k_BattOvHi_Volt_f32	29.3789997
k_BattOvLo_Volt_f32	16.8927002
k_BattUvHi_Volt_f32	14.4617996
k_BattUvLo_Volt_f32	14.0958996
k_CAVNTCEnableTimeout_mS_u16	50563
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	13600
k_CAVNodeTimeout_mS_u16	27334
k_CMM388MsgTimeout_mS_u16	3456
k_CMM388NTCEnableTimeout_mS_u16	19340
k_CMMNTCEnableTimeout_mS_u16	13960
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	18163
k_CONSANGLECPKMax_HwDeg_f32	133.996002
k_CONSANGLECPKMin_HwDeg_f32	-176.634293
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	50709
k_CONSANGLECPKSigValidThresh_Cnt_u16	2535
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	55159
k_CPKVehicleSpeedValidThresh_Cnt_u16	48598
k_CityParkInputInvalidThresh_Cnt_u16	12260
k_CityParkInputValidThresh_Cnt_u16	64771
k_ComputerRazGCTSigValidThresh_Cnt_u16	48574
k_CptTemporelSigValidThresh_Cnt_u16	2364
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	24893
k_DMDFCTCPKSigValidThresh_Cnt_u16	45447
k_DMDFCTCPKValidCount_Cnt_u16	65194
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	41332
k_DMDRELAXECPKSigValidThresh_Cnt_u16	43575
k_DMDRelaxeConsistentThresh_Cnt_u16	15781
k_DateValidThresh_Cnt_u16	49506
k_DefaultVehSpd_Kph_f32	0.859799981
k_DiagMuxOnAbsentTimeout_mS_u16	45593
k_EMNodeTimeout_mS_u16	523
k_ESPNTCEnableTimeout_mS_u16	36646
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	7643
k_EtatMTSigInvalidThresh_Cnt_u16	50369
k_EtatMTSigValidThresh_Cnt_u16	17891
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	17550
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	35460
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	15360
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	3457
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	46399
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	63251
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	27552
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	59078

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	14083
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	60239
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	17885
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	36867
k_ISDATDIRASentDiag_Cnt_str.Threshold	42732
k_ISDATDIRASentDiag_Cnt_str.PStep	3144
k_ISDATDIRASentDiag_Cnt_str.NStep	10267
k_ISDATDIRASentTimeout_mS_u16	12034
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	64844
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	2801
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	46082
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	57078
k_ISDYNAASChkSumValidThresh_Cnt_u16	3544
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	10237
k_ISDYNAASMsgCountValidThresh_Cnt_u16	2904
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	8170
k_ISDYNAASMsgLenValidThresh_Cnt_u16	509
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	24812
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	52803
k_ISDYNABRChkSumValidThresh_Cnt_u16	63245
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	63938
k_ISDYNABRMsgCountValidThresh_Cnt_u16	49020
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	34843
k_ISDYNABRMsgLenValidThresh_Cnt_u16	63873
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	31271
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	43275
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	5980
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	10292
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	29247
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	35769
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	20861
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	62190
k_ISDYNVOLChkSumValidThresh_Cnt_u16	28189
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	57842
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	56780
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	8301
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	14083
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	32512
k_IgnOnTimeout_mS_u16	13818
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	73.5322037
k_PowerCutVehSpdLowThresh_Kph_f32	164.508804
k_PowerCutVehSpdLowTimeout_mS_u16	52242
k_VBattMaxAAS_Volt_f32	16.3894997
k_VBattMaxBSI_Volt_f32	15.9267998
k_VBattMaxCAV_Volt_f32	1.48549998
k_VBattMaxCMM388_Volt_f32	1.56659997
k_VBattMaxCMM_Volt_f32	13.0874004
k_VBattMaxESP_Volt_f32	27.6303997
k_VBattMinAAS_Volt_f32	24.7775993
k_VBattMinBSI_Volt_f32	27.6303997
k_VBattMinCAV_Volt_f32	14.4113998
k_VBattMinCMM388_Volt_f32	5.80350018
k_VBattMinCMM_Volt_f32	23.6910992
k_VBattMinESP_Volt_f32	13.0874004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	29406
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	65276
k_VitesseVehicleBVRampValidThresh_Cnt_u16	60791
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	12874
k_VitesseVehicleBVSigValidThresh_Cnt_u16	25368
k_VitesseVehicleBVSpeedPassThresh_kph_f32	59.0192986
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	60186
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	332
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	758279936
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	61551
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1373290240
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	78

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	2.25679994
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4272758528
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	55
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.326103896
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	102
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3947695872
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1946988288
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	98
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	500977408
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	187
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2428235520
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1957400320
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1907044096
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	22
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	800771840
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	58
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	129
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	164
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	171
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	240
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	139
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1150873344
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	128
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	174
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	176
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	196
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	221
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2158235392
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2464395008
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2251509504
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	132
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	166
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	186
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2771033856
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2874
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.526511967
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	300335
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	181.606705
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	8745

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1373290240	1373290240	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1373290240	1373290240	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1373290240	1373290240	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1373290240	1373290240	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1373290240	1373290240	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	59259	59259	✔
CONSANGLECPK_HwDeg_M_f32	521.029297	521.029297 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1373290240	1373290240	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1373290240	1373290240	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1373290240	1373290240	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1373290240	1373290240	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1373290240	1373290240	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1373290240	1373290240	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1373290240	1373290240	✔
ESPNTCEnableTimer_mS_M_u32	1373290240	1373290240	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1373290240	1373290240	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1373290240	1373290240	✔
EffacDefaultDiagTimer_mS_M_u32[1]	87	87	✔
ElecIntCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	1373290240	1373290240	✔
ElecIntTimer_mS_M_u32[1]	21	21	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1373290240	1373290240	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDATDIRASentFltAcc_Cnt_M_u16	42732	42732	✔
ISDATDIRASentTimer_mS_M_u32	1373290240	1373290240	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1373290240	1373290240	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1373290240	1373290240	✔
IgnOnTimer_mS_M_u32	1373290240	1373290240	✔
IgnTimeOff_Sec_M_u32	2314011855	2314011855	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	102	102	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3947695872	3947695872	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	126	126	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1946988288	1946988288	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	98	98	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	500977408	500977408	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	187	187	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2428235520	2428235520	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	991252224	991252224	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1907044096	1907044096	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	22	22	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	800771840	800771840	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	139	139	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1150873344	1150873344	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	31	31	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2158235392	2158235392	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2464395008	2464395008	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	45	45	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2251509504	2251509504	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2771033856	2771033856	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	655.340027	655.340027	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	6.35010004	6.35010004	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	52.3774986	52.3774986	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	59259	59259	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2314011855	2314011855	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	521.029297	521.029297 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.465 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1531528704
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	28375
AASNodeAbsentTimer_mS_M_u32	1690908160
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	23196
ANGLEVOLANTSigValidCount_Cnt_M_u16	45805
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	60804
AngleVolantMsgTimer_mS_M_u32	1531528704
AngleVolantValidCount_Cnt_M_u16	4523
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2152527360
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1417901568
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	132244992
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2317657600
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	36883
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1422026240
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	41612
CAVNodeAbsentTimer_mS_M_u32	3837122048
CDD_SrlComVehSpd_Kph_G_f32	570.014526
CMM388NTCEnableTimer_mS_M_u32	2046694912
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4083930624
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	40264
CMMNodeAbsentTimer_mS_M_u32	2314118656
CONSANGLECPKSigInvalidCount_Cnt_M_u16	23084
CONSANGLECPKSigValidCount_Cnt_M_u16	37581
CONSANGLECPK_Cnt_M_u16	35240
CONSANGLECPK_HwDeg_M_f32	-93.9639969
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	35240
CPKVehicleSpeedMsgTimer_mS_M_u32	3682092544
CPKVehicleSpeedValidCount_Cnt_M_u16	2758
CityParkInputConsistentCount_Cnt_M_u16	58831
CityParkInputInvalidCount_Cnt_M_u16	57001

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	3947695872
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1106064896
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	14587
ComputerRazGCTSigInvalidTimer_mS_M_u32	540956160
ComputerRazGCTSigValidCount_Cnt_M_u16	47284
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	42629
DMDFCTCPKSigValidCount_Cnt_M_u16	30142
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	35758
DMDRELAXECPKSigValidCount_Cnt_M_u16	60799
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	41433
DateInvalidTimer_mS_M_u32	1417901568
DiagMuxOnAbsentTimer_mS_M_u32	2194081280
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2317657600
ESPNTCEnableTimer_mS_M_u32	1750742528
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	40405
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	707
EffacDefaultDiagTimer_mS_M_u32[1]	1235
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	979
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2251580928
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	5237
EtatMTSigValidCount_Cnt_M_u16	47218
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	16702
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	863
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	24180
ISDAT4V2BSI552MsgTimer_mS_M_u32	3121784320
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	22728
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	9870
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	47218
ISDATBSI3F2MsgTimer_mS_M_u32	867501568
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	29626
ISDATBSI412MsgLenValidCount_Cnt_M_u16	40624
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	5237
ISDATBSI412MsgTimer_mS_M_u32	4063708672
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	24684
ISDATBSI432MsgLenValidCount_Cnt_M_u16	13305
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	38717
ISDATDIRASentFltAcc_Cnt_M_u16	64113
ISDATDIRASentTimer_mS_M_u32	3682092544
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	45334
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	4523
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	19836
ISDYN2CMMMsgTimer_mS_M_u32	1017394688
ISDYNAASChkSumInvalidCount_Cnt_M_u16	27625
ISDYNAASChkSumValidCount_Cnt_M_u16	27483
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	40610
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	4519
ISDYNAASMsgLenValidCount_Cnt_M_u16	528
ISDYNAASMsgTimeValidCount_Cnt_M_u16	27625
ISDYNAASMsgTimer_mS_M_u32	383391232
ISDYNABRChkSumInvalidCount_Cnt_M_u16	34807
ISDYNABRChkSumValidCount_Cnt_M_u16	16401
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	21344
ISDYNABRMsgCountValidCount_Cnt_M_u16	52754
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	46243
ISDYNABRMsgLenValidCount_Cnt_M_u16	43140
ISDYNABRMsgTimeValidCount_Cnt_M_u16	35240
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	57651

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	47218
ISDYNCMM208MsgTimer_mS_M_u32	3144807936
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	57651
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	24473
ISDYNCMM388MsgTimer_mS_M_u32	83203584
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	17178
ISDYNVOLChkSumValidCount_Cnt_M_u16	62011
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	17011
ISDYNVOLMsgCountValidCount_Cnt_M_u16	51244
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	62814
ISDYNVOLMsgLenValidCount_Cnt_M_u16	59103
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	40264
ISDYNVOLMsgTimer_mS_M_u32	689591808
IgnOnTimer_mS_M_u32	1676800
IgnTimeOff_Sec_M_u32	608410667
ManVehSpd_Kph_M_f32	360.861511
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	83
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	82
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3964339712
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	113
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3359172096
PrevISDATBSI412MsgDLCError_Cnt_M_u08	124
PrevISDATBSI412MsgRxTime_MSec_M_u32	2888226304
PrevISDATBSI432MsgDLCError_Cnt_M_u08	26
PrevISDATBSI432MsgRxTime_MSec_M_u32	334378496
PrevISDATDIRAMsgTxTime_MSec_M_u32	3462059520
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	182
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4195493376
PrevISDYNAASMsgDLCError_Cnt_M_u08	134
PrevISDYNAASMsgRxTime_MSec_M_u32	411588096
PrevISDYNABRMsgDLCError_Cnt_M_u08	242
PrevISDYNABRMsgRxTime_MSec_M_u32	2094110208
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	73
PrevISDYNCMM208MsgRxTime_MSec_M_u32	959272448
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	216
PrevISDYNCMM388MsgRxTime_MSec_M_u32	399062528
PrevISDYNVOLMsgDLCError_Cnt_M_u08	108
PrevISDYNVOLMsgRxTime_MSec_M_u32	136566272
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3424994816
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	1.39160001
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	37781
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	47742
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	47262
VitesseVehicleBVRampValidCount_Cnt_M_u16	50247
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	22821
VitesseVehicleBVSigValidCount_Cnt_M_u16	46646
VitesseVehicleBV_Kph_M_f32	643.967407

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	24473
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	39139
VitesseVehiculeRoues_Kph_M_f32	607.156189
k_AASNTCEnableTimeout_mS_u16	54295
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	52606
k_AASNodeTimeout_mS_u16	60798
k_ABSNodeTimeout_mS_u16	20842
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	24959
k_ANGLEVOLANTSigValidThresh_Cnt_u16	60748
k_AngleVolantInvalidThresh_Cnt_u16	46859
k_AngleVolantValidThresh_Cnt_u16	57001
k_BSI552MsgTimeout_mS_u16	22370
k_BSINTCEnableTimeout_mS_u16	19748
k_BSINodeAbsentDiag_Cnt_str.Threshold	13537
k_BSINodeAbsentDiag_Cnt_str.PStep	61147
k_BSINodeAbsentDiag_Cnt_str.NStep	49162
k_BSINodeAbsentTimeout_mS_u16	27708
k_BSINodeTimeout_mS_u16	38717
k_BattOvHi_Volt_f32	22.1350002
k_BattOvLo_Volt_f32	15.1286001
k_BattUvHi_Volt_f32	2.71169996
k_BattUvLo_Volt_f32	18.6312008
k_CAVNTCEnableTimeout_mS_u16	56655
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	20346
k_CAVNodeTimeout_mS_u16	28424
k_CMM388MsgTimeout_mS_u16	57815
k_CMM388NTCEnableTimeout_mS_u16	22451
k_CMMNTCEnableTimeout_mS_u16	24960
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	17599
k_CONSANGLECPKMax_HwDeg_f32	740.085815
k_CONSANGLECPKMin_HwDeg_f32	-359.657013
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	21145
k_CONSANGLECPKSigValidThresh_Cnt_u16	52195
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	308
k_CPKVehicleSpeedValidThresh_Cnt_u16	54421
k_CityParkInputInvalidThresh_Cnt_u16	49197
k_CityParkInputValidThresh_Cnt_u16	58831
k_ComputerRazGCTSigValidThresh_Cnt_u16	9182
k_CptTemporelSigValidThresh_Cnt_u16	13860
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	10147
k_DMDFCTCPKSigValidThresh_Cnt_u16	23428
k_DMDFCTCPKValidCount_Cnt_u16	37979
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	19836
k_DMDRELAXECPKSigValidThresh_Cnt_u16	14325
k_DMDRelaxeConsistentThresh_Cnt_u16	46507
k_DateValidThresh_Cnt_u16	24180
k_DefaultVehSpd_Kph_f32	220.274994
k_DiagMuxOnAbsentTimeout_mS_u16	8654
k_EMNodeTimeout_mS_u16	64825
k_ESPNTCEnableTimeout_mS_u16	55656
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	24583
k_EtatMTSigInvalidThresh_Cnt_u16	46486
k_EtatMTSigValidThresh_Cnt_u16	46832
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	54767
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	55501
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	23768
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	149
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	65051
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	23774
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	31161
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	40198

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	25488
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	52780
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	62273
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	24337
k_ISDATDIRASentDiag_Cnt_str.Threshold	53644
k_ISDATDIRASentDiag_Cnt_str.PStep	28273
k_ISDATDIRASentDiag_Cnt_str.NStep	22576
k_ISDATDIRASentTimeout_mS_u16	47827
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	31542
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	60804
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	56020
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	31479
k_ISDYNAASChkSumValidThresh_Cnt_u16	29457
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	50784
k_ISDYNAASMsgCountValidThresh_Cnt_u16	33042
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	34843
k_ISDYNAASMsgLenValidThresh_Cnt_u16	6562
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	18068
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	30865
k_ISDYNABRChkSumValidThresh_Cnt_u16	8946
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	787
k_ISDYNABRMsgCountValidThresh_Cnt_u16	38564
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	53320
k_ISDYNABRMsgLenValidThresh_Cnt_u16	4309
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	53923
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	24505
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	24579
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	17149
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	52636
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	26093
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	41313
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	38221
k_ISDYNVOLChkSumValidThresh_Cnt_u16	55427
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	23426
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	54069
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	8273
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	12622
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	7578
k_IgnOnTimeout_mS_u16	64553
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	90.7578964
k_PowerCutVehSpdLowThresh_Kph_f32	177.828201
k_PowerCutVehSpdLowTimeout_mS_u16	63459
k_VBattMaxAAS_Volt_f32	4.56659985
k_VBattMaxBSI_Volt_f32	24.066
k_VBattMaxCAV_Volt_f32	2.06680012
k_VBattMaxCMM388_Volt_f32	15.8098001
k_VBattMaxCMM_Volt_f32	25.9454994
k_VBattMaxESP_Volt_f32	25.8547001
k_VBattMinAAS_Volt_f32	21.2646999
k_VBattMinBSI_Volt_f32	25.8547001
k_VBattMinCAV_Volt_f32	31.9636993
k_VBattMinCMM388_Volt_f32	18.1488991
k_VBattMinCMM_Volt_f32	27.7469006
k_VBattMinESP_Volt_f32	25.9454994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	57984
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	45797
k_VitesseVehicleBVRampValidThresh_Cnt_u16	13683
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	42299
k_VitesseVehicleBVSigValidThresh_Cnt_u16	18320
k_VitesseVehicleBVSpeedPassThresh_kph_f32	322.515503
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	38284
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	6069
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1417901568
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60612
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2882176512
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	216

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	19.9615002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1725130240
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	7
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0849110708
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	238
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1286837760
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3103045120
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	33936896
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	803665408
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1251481088
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1511601664
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	8
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1718244864
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	43
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	101
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	208
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3360683520
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	81
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	161
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	163
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	225
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2830013952
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2020587008
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3842037248
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	79
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	93
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	175
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1230693888
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	973
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.54462564
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	602488
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	246.7845
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	60511

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2882176512	2882176512	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2882176512	2882176512	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2882176512	2882176512	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2882176512	2882176512	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2882176512	2882176512	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	35240	35240	✔
CONSANGLECPK_HwDeg_M_f32	-93.9639969	-93.9639969 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2882176512	2882176512	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2882176512	2882176512	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2882176512	2882176512	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2882176512	2882176512	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2882176512	2882176512	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2882176512	2882176512	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2882176512	2882176512	✔
ESPNTCEnableTimer_mS_M_u32	2882176512	2882176512	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2882176512	2882176512	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2882176512	2882176512	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1235	1235	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	2882176512	2882176512	✔
ElecIntTimer_mS_M_u32[1]	979	979	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2882176512	2882176512	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDATDIRASentFltAcc_Cnt_M_u16	53644	53644	✔
ISDATDIRASentTimer_mS_M_u32	2882176512	2882176512	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2882176512	2882176512	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2882176512	2882176512	✔
IgnOnTimer_mS_M_u32	1676800	1676800	✔
IgnTimeOff_Sec_M_u32	608410667	608410667	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	238	238	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1286837760	1286837760	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	143	143	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3103045120	3103045120	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	9	9	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	33936896	33936896	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	99	99	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	803665408	803665408	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3462059520	3462059520	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	219	219	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1511601664	1511601664	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	8	8	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1718244864	1718244864	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	169	169	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3360683520	3360683520	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	225	225	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2830013952	2830013952	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	133	133	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2020587008	2020587008	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	194	194	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3842037248	3842037248	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1230693888	1230693888	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	1.39160001	1.39160001	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	643.967407	643.967407	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	607.156189	607.156189	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	35240	35240	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	608410667	608410667	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-93.9639969	-93.9639969 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.466 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1448800512
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	30127
AASNodeAbsentTimer_mS_M_u32	1704665344
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	25697
ANGLEVOLANTSigValidCount_Cnt_M_u16	44333
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	60840
AngleVolantMsgTimer_mS_M_u32	1448800512
AngleVolantValidCount_Cnt_M_u16	34227
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3524256000
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1332502784
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	4212199680
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4014526720
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	24572
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	913281280
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	62737
CAVNodeAbsentTimer_mS_M_u32	3763683584
CDD_SrlComVehSpd_Kph_G_f32	362.719086
CMM388NTCEnableTimer_mS_M_u32	2440855808
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	204685568
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	53150
CMMNodeAbsentTimer_mS_M_u32	2548748544
CONSANGLECPKSigInvalidCount_Cnt_M_u16	21682
CONSANGLECPKSigValidCount_Cnt_M_u16	15502
CONSANGLECPK_Cnt_M_u16	33789
CONSANGLECPK_HwDeg_M_f32	378.185608
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	33789
CPKVehicleSpeedMsgTimer_mS_M_u32	1372451072
CPKVehicleSpeedValidCount_Cnt_M_u16	650

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	39239
CityParkInputInvalidCount_Cnt_M_u16	41915
CityParkInputMsgTimer_mS_M_u32	1286837760
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1580146944
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	42819
ComputerRazGCTSigInvalidTimer_mS_M_u32	4022059264
ComputerRazGCTSigValidCount_Cnt_M_u16	62616
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	48167
DMDFCTCPKSigValidCount_Cnt_M_u16	16443
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	39211
DMDRELAXECPKSigValidCount_Cnt_M_u16	50551
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	29099
DateInvalidTimer_mS_M_u32	1332502784
DiagMuxOnAbsentTimer_mS_M_u32	115454208
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4014526720
ESPNTCEnableTimer_mS_M_u32	3739754752
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	4022
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	8
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3927544064
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	44822
EtatMTSigValidCount_Cnt_M_u16	50398
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	26492
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	45784
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	56857
ISDAT4V2BSI552MsgTimer_mS_M_u32	2541670656
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	59292
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	40972
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	50398
ISDATBSI3F2MsgTimer_mS_M_u32	739750144
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	12229
ISDATBSI412MsgLenValidCount_Cnt_M_u16	37029
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	44822
ISDATBSI412MsgTimer_mS_M_u32	3381719296
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	5682
ISDATBSI432MsgLenValidCount_Cnt_M_u16	56650
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	6910
ISDATDIRASentFltAcc_Cnt_M_u16	49506
ISDATDIRASentTimer_mS_M_u32	1372451072
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	17843
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	34227
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	25410
ISDYN2CMMMsgTimer_mS_M_u32	168435968
ISDYNAASChkSumInvalidCount_Cnt_M_u16	18041
ISDYNAASChkSumValidCount_Cnt_M_u16	6629
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	31438
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	54208
ISDYNAASMsgLenValidCount_Cnt_M_u16	46148
ISDYNAASMsgTimeValidCount_Cnt_M_u16	18041
ISDYNAASMsgTimer_mS_M_u32	719880448
ISDYNABRChkSumInvalidCount_Cnt_M_u16	463
ISDYNABRChkSumValidCount_Cnt_M_u16	19267
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	11284
ISDYNABRMsgCountValidCount_Cnt_M_u16	36288
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	57677
ISDYNABRMsgLenValidCount_Cnt_M_u16	38761
ISDYNABRMsgTimeValidCount_Cnt_M_u16	33789

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	47707
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	50398
ISDYNCMM208MsgTimer_mS_M_u32	4104184064
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	47707
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	54249
ISDYNCMM388MsgTimer_mS_M_u32	781582592
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	53736
ISDYNVOLChkSumValidCount_Cnt_M_u16	22084
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	8285
ISDYNVOLMsgCountValidCount_Cnt_M_u16	33009
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	27931
ISDYNVOLMsgLenValidCount_Cnt_M_u16	43606
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	53150
ISDYNVOLMsgTimer_mS_M_u32	1160233216
IgnOnTimer_mS_M_u32	3442082048
IgnTimeOff_Sec_M_u32	622270207
ManVehSpd_Kph_M_f32	240.899094
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	84
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	255
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3663048960
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	35
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3591115008
PrevISDATBSI412MsgDLCError_Cnt_M_u08	137
PrevISDATBSI412MsgRxTime_MSec_M_u32	2382512384
PrevISDATBSI432MsgDLCError_Cnt_M_u08	116
PrevISDATBSI432MsgRxTime_MSec_M_u32	741089536
PrevISDATDIRAMsgTxTime_MSec_M_u32	4150673664
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	11
PrevISDYN2CMMMsgRxTime_MSec_M_u32	897601792
PrevISDYNAASMsgDLCError_Cnt_M_u08	172
PrevISDYNAASMsgRxTime_MSec_M_u32	2933768448
PrevISDYNABRMsgDLCError_Cnt_M_u08	158
PrevISDYNABRMsgRxTime_MSec_M_u32	922878208
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	58
PrevISDYNCMM208MsgRxTime_MSec_M_u32	552517888
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	11
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1285234944
PrevISDYNVOLMsgDLCError_Cnt_M_u08	102
PrevISDYNVOLMsgRxTime_MSec_M_u32	2919973120
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1942417664
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	595.151184
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	34294
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	49914
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	31451
VitesseVehicleBVRampValidCount_Cnt_M_u16	2463
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	52422

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	1874
VitesseVehicleBV_Kph_M_f32	594.657898
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	54249
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	22988
VitesseVehiculeRoues_Kph_M_f32	401.277893
k_AASNTCEnableTimeout_mS_u16	8368
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	24122
k_AASNodeTimeout_mS_u16	10746
k_ABSNodeTimeout_mS_u16	36728
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	7929
k_ANGLEVOLANTSigValidThresh_Cnt_u16	48465
k_AngleVolantInvalidThresh_Cnt_u16	7188
k_AngleVolantValidThresh_Cnt_u16	41915
k_BSI552MsgTimeout_mS_u16	55887
k_BSINTCEnableTimeout_mS_u16	12298
k_BSINodeAbsentDiag_Cnt_str.Threshold	33043
k_BSINodeAbsentDiag_Cnt_str.PStep	12643
k_BSINodeAbsentDiag_Cnt_str.NStep	27671
k_BSINodeAbsentTimeout_mS_u16	20864
k_BSINodeTimeout_mS_u16	6910
k_BattOvHi_Volt_f32	21.3785
k_BattOvLo_Volt_f32	13.2936001
k_BattUvHi_Volt_f32	12.1726999
k_BattUvLo_Volt_f32	17.4489994
k_CAVNTCEnableTimeout_mS_u16	49097
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	9799
k_CAVNodeTimeout_mS_u16	34334
k_CMM388MsgTimeout_mS_u16	7343
k_CMM388NTCEnableTimeout_mS_u16	11035
k_CMMNTCEnableTimeout_mS_u16	44404
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	50744
k_CONSANGLECPKMax_HwDeg_f32	507.793488
k_CONSANGLECPKMin_HwDeg_f32	-235.076508
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	64233
k_CONSANGLECPKSigValidThresh_Cnt_u16	49356
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	18136
k_CPKVehicleSpeedValidThresh_Cnt_u16	14644
k_CityParkInputInvalidThresh_Cnt_u16	45357
k_CityParkInputValidThresh_Cnt_u16	39239
k_ComputerRazGCTSigValidThresh_Cnt_u16	24154
k_CptTemporelSigValidThresh_Cnt_u16	18762
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	34893
k_DMDFCTCPKSigValidThresh_Cnt_u16	32361
k_DMDFCTCPKValidCount_Cnt_u16	29476
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	25410
k_DMDRELAXECPKSigValidThresh_Cnt_u16	38294
k_DMDRelaxeConsistentThresh_Cnt_u16	29812
k_DateValidThresh_Cnt_u16	56857
k_DefaultVehSpd_Kph_f32	175.888901
k_DiagMuxOnAbsentTimeout_mS_u16	54155
k_EMNodeTimeout_mS_u16	57227
k_ESPNTCEnableTimeout_mS_u16	49277
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	37984
k_EtatMTSigInvalidThresh_Cnt_u16	46322
k_EtatMTSigValidThresh_Cnt_u16	8870
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	29863
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	60878
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	38956
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	25653
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	36197
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	1113

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	15947
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	5667
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	40134
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	50801
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	47345
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	38595
k_ISDATDIRASentDiag_Cnt_str.Threshold	63911
k_ISDATDIRASentDiag_Cnt_str.PStep	39954
k_ISDATDIRASentDiag_Cnt_str.NStep	1837
k_ISDATDIRASentTimeout_mS_u16	55611
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	5716
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	60840
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	27705
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	10447
k_ISDYNAASChkSumValidThresh_Cnt_u16	45635
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	54036
k_ISDYNAASMsgCountValidThresh_Cnt_u16	29888
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	37219
k_ISDYNAASMsgLenValidThresh_Cnt_u16	13710
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	53625
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	52611
k_ISDYNABRChkSumValidThresh_Cnt_u16	24607
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	1788
k_ISDYNABRMsgCountValidThresh_Cnt_u16	40456
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	13982
k_ISDYNABRMsgLenValidThresh_Cnt_u16	46774
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	42507
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	45450
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	52970
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	58749
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	2913
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	37933
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	15251
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	55052
k_ISDYNVOLChkSumValidThresh_Cnt_u16	61228
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	51887
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	8663
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	64386
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	51786
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	47271
k_IgnOnTimeout_mS_u16	4728
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	42.9402008
k_PowerCutVehSpdLowThresh_Kph_f32	237.729294
k_PowerCutVehSpdLowTimeout_mS_u16	58700
k_VBattMaxAAS_Volt_f32	19.1345997
k_VBattMaxBSI_Volt_f32	5.30240011
k_VBattMaxCAV_Volt_f32	3.26950002
k_VBattMaxCMM388_Volt_f32	19.0816994
k_VBattMaxCMM_Volt_f32	19.5797997
k_VBattMaxESP_Volt_f32	21.2378998
k_VBattMinAAS_Volt_f32	8.45330048
k_VBattMinBSI_Volt_f32	21.2378998
k_VBattMinCAV_Volt_f32	4.55439997
k_VBattMinCMM388_Volt_f32	32
k_VBattMinCMM_Volt_f32	12.3387003
k_VBattMinESP_Volt_f32	19.5797997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	34934
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	47365
k_VitesseVehicleBVRampValidThresh_Cnt_u16	18269
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	15684
k_VitesseVehicleBVSigValidThresh_Cnt_u16	47108
k_VitesseVehicleBVSpeedPassThresh_kph_f32	80.3255997
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	7185
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	18261
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1332502784
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	49346
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	4191629568
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	11
target_SrlComInput_Per1_Batt_Volt_f32.value	16.0797005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2218561792
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	192
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.110221915
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3478913280
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1998102784
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	52
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3362078976
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2873221376
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	128876800
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3316326656
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	233
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3442983168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	11
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	46
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	47
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	95
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	103
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	196
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3322339584
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	60
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	76
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	123
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	153
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	164
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	165
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	214
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	224
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	127
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1735065856
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3836190976
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3413393664
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	48
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	72
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	84
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	88
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	165
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1520832768
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3787
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.674728334
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	616390
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	182.110397
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	9112

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4191629568	4191629568	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	4191629568	4191629568	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	4191629568	4191629568	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4191629568	4191629568	✔
CDD_SrlComVehSpd_Kph_G_f32	240.899094	240.899094	✔
CMM388NTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4191629568	4191629568	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	33789	33789	✔
CONSANGLECPK_HwDeg_M_f32	378.185608	378.185608 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4191629568	4191629568	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	4191629568	4191629568	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4191629568	4191629568	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4191629568	4191629568	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4191629568	4191629568	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4191629568	4191629568	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4191629568	4191629568	✔
ESPNTCEnableTimer_mS_M_u32	4191629568	4191629568	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4191629568	4191629568	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4	4	✔
ElecIntTimer_mS_M_u32[1]	8	8	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	4191629568	4191629568	✔
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	56857	56857	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	50398	50398	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	44822	44822	✔
ISDATBSI412MsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	6910	6910	✔
ISDATBSI432MsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	4191629568	4191629568	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	25410	25410	✔
ISDYN2CMMMsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	18041	18041	✔
ISDYNAASMsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	33789	33789	✔
ISDYNABRMsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	50398	50398	✔
ISDYNCMM208MsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	54249	54249	✔
ISDYNCMM388MsgTimer_mS_M_u32	4191629568	4191629568	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	53150	53150	✔
ISDYNVOLMsgTimer_mS_M_u32	4191629568	4191629568	✔
IgnOnTimer_mS_M_u32	3442082048	3442082048	✔
IgnTimeOff_Sec_M_u32	622270207	622270207	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	170	170	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3478913280	3478913280	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	20	20	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1998102784	1998102784	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	52	52	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3362078976	3362078976	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	241	241	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2873221376	2873221376	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4150673664	4150673664	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3316326656	3316326656	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	233	233	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3442983168	3442983168	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	5	5	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3322339584	3322339584	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	127	127	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1735065856	1735065856	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	223	223	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3836190976	3836190976	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	180	180	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3413393664	3413393664	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1520832768	1520832768	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	595.151184	595.151184	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	594.657898	594.657898	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	401.277893	401.277893	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	33789	33789	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	622270207	622270207	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	378.185608	378.185608 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	240.899094	240.899094	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.467 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	361885696
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	43412
AASNodeAbsentTimer_mS_M_u32	1687248896
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	51068
ANGLEVOLANTSigValidCount_Cnt_M_u16	63449
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	26025
AngleVolantMsgTimer_mS_M_u32	361885696
AngleVolantValidCount_Cnt_M_u16	36873
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3795001344
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2082316288
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	670011392
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3662172160
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	171
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	265555968
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	56302
CAVNodeAbsentTimer_mS_M_u32	81985536
CDD_SrlComVehSpd_Kph_G_f32	121.676697
CMM388NTCEnableTimer_mS_M_u32	2657959936
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2034827264
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	60423
CMMNodeAbsentTimer_mS_M_u32	3898757120
CONSANGLECPKSigInvalidCount_Cnt_M_u16	10634
CONSANGLECPKSigValidCount_Cnt_M_u16	48311
CONSANGLECPK_Cnt_M_u16	25194
CONSANGLECPK_HwDeg_M_f32	641.164795
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	25194
CPKVehicleSpeedMsgTimer_mS_M_u32	2939744256
CPKVehicleSpeedValidCount_Cnt_M_u16	33035
CityParkInputConsistentCount_Cnt_M_u16	42317
CityParkInputInvalidCount_Cnt_M_u16	42736
CityParkInputMsgTimer_mS_M_u32	3478913280
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3402981376
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	25816

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2427420672
ComputerRazGCTSigValidCount_Cnt_M_u16	5978
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	3500
DMDFCTCPKSigValidCount_Cnt_M_u16	44081
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	53534
DMDRELAXECPKSigValidCount_Cnt_M_u16	22267
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	63135
DateInvalidTimer_mS_M_u32	2082316288
DiagMuxOnAbsentTimer_mS_M_u32	2398990336
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3662172160
ESPNTCEnableTimer_mS_M_u32	1823105024
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	26240
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	87
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	21
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	483790848
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	32414
EtatMTSigValidCount_Cnt_M_u16	14343
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	39212
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	473
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	51863
ISDAT4V2BSI552MsgTimer_mS_M_u32	967200768
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	50316
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	13821
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	14343
ISDATBSI3F2MsgTimer_mS_M_u32	2002497536
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	8465
ISDATBSI412MsgLenValidCount_Cnt_M_u16	22834
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	32414
ISDATBSI412MsgTimer_mS_M_u32	334491648
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	26699
ISDATBSI432MsgLenValidCount_Cnt_M_u16	19908
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	24103
ISDATDIRASentFltAcc_Cnt_M_u16	64251
ISDATDIRASentTimer_mS_M_u32	2939744256
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	30024
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	36873
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	17499
ISDYN2CMMMsgTimer_mS_M_u32	4081344512
ISDYNAASChkSumInvalidCount_Cnt_M_u16	57142
ISDYNAASChkSumValidCount_Cnt_M_u16	61363
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	56504
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	48097
ISDYNAASMsgLenValidCount_Cnt_M_u16	1302
ISDYNAASMsgTimeValidCount_Cnt_M_u16	57142
ISDYNAASMsgTimer_mS_M_u32	2183741440
ISDYNABRChkSumInvalidCount_Cnt_M_u16	32435
ISDYNABRChkSumValidCount_Cnt_M_u16	19736
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	23141
ISDYNABRMsgCountValidCount_Cnt_M_u16	49186
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	44985
ISDYNABRMsgLenValidCount_Cnt_M_u16	55334
ISDYNABRMsgTimeValidCount_Cnt_M_u16	25194
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	43890
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	2127
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	14343
ISDYNCMM208MsgTimer_mS_M_u32	4269809664
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	43890
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	2127
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	64871

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	220250112
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	2536
ISDYNVOLChkSumValidCount_Cnt_M_u16	51093
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	14602
ISDYNVOLMsgCountValidCount_Cnt_M_u16	16911
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	8785
ISDYNVOLMsgLenValidCount_Cnt_M_u16	13662
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	60423
ISDYNVOLMsgTimer_mS_M_u32	1080786944
IgnOnTimer_mS_M_u32	2170863616
IgnTimeOff_Sec_M_u32	1357340656
ManVehSpd_Kph_M_f32	109.612999
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	82
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	109
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3835801600
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	120
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1123979264
PrevISDATBSI412MsgDLCError_Cnt_M_u08	184
PrevISDATBSI412MsgRxTime_MSec_M_u32	4024172544
PrevISDATBSI432MsgDLCError_Cnt_M_u08	165
PrevISDATBSI432MsgRxTime_MSec_M_u32	2497601536
PrevISDATDIRAMsgTxTime_MSec_M_u32	1135607808
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	163
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1168232448
PrevISDYNAASMsgDLCError_Cnt_M_u08	136
PrevISDYNAASMsgRxTime_MSec_M_u32	1531543552
PrevISDYNABRMsgDLCError_Cnt_M_u08	21
PrevISDYNABRMsgRxTime_MSec_M_u32	2749153280
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	97
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2299953152
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	111
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2945540096
PrevISDYNVOLMsgDLCError_Cnt_M_u08	24
PrevISDYNVOLMsgRxTime_MSec_M_u32	4089511936
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1833824256
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	249.933197
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	64831
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	12532
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	62096
VitesseVehicleBVRampValidCount_Cnt_M_u16	12549
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	25165
VitesseVehicleBVSigValidCount_Cnt_M_u16	48490
VitesseVehicleBV_Kph_M_f32	33.4874992
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	64871
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	54908
VitesseVehiculeRoues_Kph_M_f32	212.388397
k_AASNTCEnableTimeout_mS_u16	6225
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	57972
k_AASNodeTimeout_mS_u16	64500
k_ABSNodeTimeout_mS_u16	6073
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	10742
k_ANGLEVOLANTSigValidThresh_Cnt_u16	35247
k_AngleVolantInvalidThresh_Cnt_u16	14694
k_AngleVolantValidThresh_Cnt_u16	42736
k_BSI552MsgTimeout_mS_u16	8435
k_BSINTCEnableTimeout_mS_u16	31427
k_BSINodeAbsentDiag_Cnt_str.Threshold	28392
k_BSINodeAbsentDiag_Cnt_str.PStep	49975
k_BSINodeAbsentDiag_Cnt_str.NStep	2138
k_BSINodeAbsentTimeout_mS_u16	39457
k_BSINodeTimeout_mS_u16	24103
k_BattOvHi_Volt_f32	7.83249998
k_BattOvLo_Volt_f32	21.8990993
k_BattUvHi_Volt_f32	10.3766003
k_BattUvLo_Volt_f32	30.4435997
k_CAVNTCEnableTimeout_mS_u16	2758
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	41036
k_CAVNodeTimeout_mS_u16	17734
k_CMM388MsgTimeout_mS_u16	46228
k_CMM388NTCEnableTimeout_mS_u16	14672
k_CMMNTCEnableTimeout_mS_u16	54020
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	16696
k_CONSANGLECPKMax_HwDeg_f32	693.42627
k_CONSANGLECPKMin_HwDeg_f32	-555.667786
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	34919
k_CONSANGLECPKSigValidThresh_Cnt_u16	41340
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	40282
k_CPKVehicleSpeedValidThresh_Cnt_u16	32964
k_CityParkInputInvalidThresh_Cnt_u16	26777
k_CityParkInputValidThresh_Cnt_u16	42317
k_ComputerRazGCTSigValidThresh_Cnt_u16	55378
k_CptTemporelSigValidThresh_Cnt_u16	45635
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	47801
k_DMDFCTCPKSigValidThresh_Cnt_u16	8998
k_DMDFCTCPKValidCount_Cnt_u16	26419
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	17499
k_DMDRELAXECPKSigValidThresh_Cnt_u16	55328
k_DMDRelaxeConsistentThresh_Cnt_u16	13190
k_DateValidThresh_Cnt_u16	51863
k_DefaultVehSpd_Kph_f32	115.469002
k_DiagMuxOnAbsentTimeout_mS_u16	11200
k_EMNodeTimeout_mS_u16	11519
k_ESPNTCEnableTimeout_mS_u16	10666
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	30400
k_EtatMTSigInvalidThresh_Cnt_u16	45386
k_EtatMTSigValidThresh_Cnt_u16	4847
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	4077
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	7989
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	31902
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	62145
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	4594
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	62293
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	37888
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	18233
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	9359
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	27406
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	28239
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	28953
k_ISDATDIRASentDiag_Cnt_str.Threshold	31074

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	34522
k_ISDATDIRASentDiag_Cnt_str.NStep	11395
k_ISDATDIRASentTimeout_mS_u16	43119
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	30310
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	26025
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	5750
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	2483
k_ISDYNAASChkSumValidThresh_Cnt_u16	6168
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	25957
k_ISDYNAASMsgCountValidThresh_Cnt_u16	2850
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	8183
k_ISDYNAASMsgLenValidThresh_Cnt_u16	10552
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	60727
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	17175
k_ISDYNABRChkSumValidThresh_Cnt_u16	54788
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	2987
k_ISDYNABRMsgCountValidThresh_Cnt_u16	20808
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46855
k_ISDYNABRMsgLenValidThresh_Cnt_u16	29056
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	1343
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	51843
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	6050
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	38251
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	53884
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	17113
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	16232
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	1852
k_ISDYNVOLChkSumValidThresh_Cnt_u16	6557
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	22933
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	6492
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	18778
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	55235
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	62189
k_IgnOnTimeout_mS_u16	1272
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	30.8152008
k_PowerCutVehSpdLowThresh_Kph_f32	126.447998
k_PowerCutVehSpdLowTimeout_mS_u16	14973
k_VBattMaxAAS_Volt_f32	19.5709
k_VBattMaxBSI_Volt_f32	26.0694008
k_VBattMaxCAV_Volt_f32	5.25880003
k_VBattMaxCMM388_Volt_f32	17.6991005
k_VBattMaxCMM_Volt_f32	22.4890003
k_VBattMaxESP_Volt_f32	13.3573999
k_VBattMinAAS_Volt_f32	32
k_VBattMinBSI_Volt_f32	13.3573999
k_VBattMinCAV_Volt_f32	25.4775009
k_VBattMinCMM388_Volt_f32	12.6480999
k_VBattMinCMM_Volt_f32	16.7229004
k_VBattMinESP_Volt_f32	22.4890003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	10240
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	45329
k_VitesseVehicleBVRampValidThresh_Cnt_u16	50186
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	4757
k_VitesseVehicleBVSigValidThresh_Cnt_u16	32022
k_VitesseVehicleBVSpeedPassThresh_kph_f32	105.488098
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	26350
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	53219
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2082316288
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	2
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	55763
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1813852160
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	111
target_SrlComInput_Per1_Batt_Volt_f32.value	22.0277004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2590838784
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	140
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	14
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.221261621
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3268329472
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	102293504
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2360541184
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2661097472
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2211921920
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2220974080
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3896213504
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	12
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	71
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	80
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	98
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	194
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	232
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	62
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2723028992
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	27
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	37
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	56
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	94
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	198
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	213
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	103
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4137795584
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3110854656
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	63
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2139488256
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	37
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	49
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	80
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	162
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	201
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2637205504
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3756
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.235563874
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	248901
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	95.5547028
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	11353

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1813852160	1813852160	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
CDD_SrlComVehSpd_Kph_G_f32	109.612999	109.612999	✔
CMM388NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	25194	25194	✔
CONSANGLECPK_HwDeg_M_f32	641.164795	641.164795 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1813852160	1813852160	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1813852160	1813852160	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	1	1	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1813852160	1813852160	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1813852160	1813852160	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1813852160	1813852160	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1813852160	1813852160	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1813852160	1813852160	✔
ESPNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔
EffacDefaultDiagTimer_mS_M_u32[1]	87	87	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	20	20	✔
ElecIntTimer_mS_M_u32[1]	21	21	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1813852160	1813852160	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	51863	51863	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	14343	14343	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	32414	32414	✔
ISDATBSI412MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	24103	24103	✔
ISDATBSI432MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	1813852160	1813852160	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	17499	17499	✔
ISDYN2CMMMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	57142	57142	✔
ISDYNAASMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	25194	25194	✔
ISDYNABRMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	14343	14343	✔
ISDYNCMM208MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	64871	64871	✔
ISDYNCMM388MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	60423	60423	✔
ISDYNVOLMsgTimer_mS_M_u32	1813852160	1813852160	✔
IgnOnTimer_mS_M_u32	2170863616	2170863616	✔
IgnTimeOff_Sec_M_u32	1357340656	1357340656	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	235	235	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3268329472	3268329472	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	200	200	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	102293504	102293504	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2360541184	2360541184	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	39	39	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2661097472	2661097472	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1135607808	1135607808	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	68	68	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2220974080	2220974080	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	141	141	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3896213504	3896213504	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	62	62	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2723028992	2723028992	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	103	103	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4137795584	4137795584	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	100	100	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3110854656	3110854656	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	63	63	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2139488256	2139488256	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2637205504	2637205504	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	249.933197	249.933197	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	33.4874992	33.4874992	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	212.388397	212.388397	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	25194	25194	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1357340656	1357340656	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	641.164795	641.164795 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	109.612999	109.612999	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.468 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1731193344
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	40774
AASNodeAbsentTimer_mS_M_u32	4088060416
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	8306
ANGLEVOLANTSigValidCount_Cnt_M_u16	38199
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	50179
AngleVolantMsgTimer_mS_M_u32	1731193344
AngleVolantValidCount_Cnt_M_u16	20068
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	341481984
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3248036352
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	360352256
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1754876416
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	15129
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	277023232
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	52589
CAVNodeAbsentTimer_mS_M_u32	3213457920
CDD_SrlComVehSpd_Kph_G_f32	499.145111
CMM388NTCEnableTimer_mS_M_u32	1332066816
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1193245184
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	39375
CMMNodeAbsentTimer_mS_M_u32	2005092864
CONSANGLECPKSigInvalidCount_Cnt_M_u16	10478
CONSANGLECPKSigValidCount_Cnt_M_u16	38659
CONSANGLECPK_Cnt_M_u16	8782
CONSANGLECPK_HwDeg_M_f32	92.9587021
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	8782
CPKVehicleSpeedMsgTimer_mS_M_u32	2785995264
CPKVehicleSpeedValidCount_Cnt_M_u16	61192
CityParkInputConsistentCount_Cnt_M_u16	44488
CityParkInputInvalidCount_Cnt_M_u16	3717
CityParkInputMsgTimer_mS_M_u32	640844544
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	739170816
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	54442

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	3183081984
ComputerRazGCTSigValidCount_Cnt_M_u16	63549
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	2849
DMDFCTCPKSigValidCount_Cnt_M_u16	40782
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	18212
DMDRELAXECPKSigValidCount_Cnt_M_u16	48489
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	59051
DateInvalidTimer_mS_M_u32	3248036352
DiagMuxOnAbsentTimer_mS_M_u32	1912187392
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	1754876416
ESPNTCEnableTimer_mS_M_u32	1686886912
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	2448
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	707
EffacDefaultDiagTimer_mS_M_u32[1]	1235
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	979
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1435830784
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	13088
EtatMTSigValidCount_Cnt_M_u16	22865
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	58784
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	54581
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	8420
ISDAT4V2BSI552MsgTimer_mS_M_u32	4075244032
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	32642
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	24058
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	22865
ISDATBSI3F2MsgTimer_mS_M_u32	3444025856
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	31272
ISDATBSI412MsgLenValidCount_Cnt_M_u16	54481
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	13088
ISDATBSI412MsgTimer_mS_M_u32	2289953280
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	38963
ISDATBSI432MsgLenValidCount_Cnt_M_u16	51956
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	35182
ISDATDIRASentFltAcc_Cnt_M_u16	11490
ISDATDIRASentTimer_mS_M_u32	2785995264
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	64540
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	20068
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	3912
ISDYN2CMMMsgTimer_mS_M_u32	2952124928
ISDYNAASChkSumInvalidCount_Cnt_M_u16	20984
ISDYNAASChkSumValidCount_Cnt_M_u16	42972
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	6283
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	25848
ISDYNAASMsgLenValidCount_Cnt_M_u16	31060
ISDYNAASMsgTimeValidCount_Cnt_M_u16	20984
ISDYNAASMsgTimer_mS_M_u32	2969680384
ISDYNABRChkSumInvalidCount_Cnt_M_u16	43100
ISDYNABRChkSumValidCount_Cnt_M_u16	60264
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	48799
ISDYNABRMsgCountValidCount_Cnt_M_u16	5059
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	63637
ISDYNABRMsgLenValidCount_Cnt_M_u16	42474
ISDYNABRMsgTimeValidCount_Cnt_M_u16	8782
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	57651
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	22865
ISDYNCMM208MsgTimer_mS_M_u32	1527749120
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	57651
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	22194

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	531970560
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	15420
ISDYNVOLChkSumValidCount_Cnt_M_u16	10449
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	49519
ISDYNVOLMsgCountValidCount_Cnt_M_u16	5148
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	35817
ISDYNVOLMsgLenValidCount_Cnt_M_u16	30941
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	39375
ISDYNVOLMsgTimer_mS_M_u32	1263925760
IgnOnTimer_mS_M_u32	3591977472
IgnTimeOff_Sec_M_u32	3084387365
ManVehSpd_Kph_M_f32	158.545898
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	83
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	112
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	347974144
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	66
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	553748992
PrevISDATBSI412MsgDLCError_Cnt_M_u08	83
PrevISDATBSI412MsgRxTime_MSec_M_u32	709523968
PrevISDATBSI432MsgDLCError_Cnt_M_u08	0
PrevISDATBSI432MsgRxTime_MSec_M_u32	3999259136
PrevISDATDIRAMsgTxTime_MSec_M_u32	1019116032
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	149
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2327759360
PrevISDYNAASMsgDLCError_Cnt_M_u08	196
PrevISDYNAASMsgRxTime_MSec_M_u32	1831074304
PrevISDYNABRMsgDLCError_Cnt_M_u08	159
PrevISDYNABRMsgRxTime_MSec_M_u32	3427875328
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	138
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1364785664
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	33
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2527779328
PrevISDYNVOLMsgDLCError_Cnt_M_u08	44
PrevISDYNVOLMsgRxTime_MSec_M_u32	1431796224
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3704351232
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	104.901398
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57670
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	13346
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	3
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	26911
VitesseVehicleBVRampValidCount_Cnt_M_u16	7355
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	31179
VitesseVehicleBVSigValidCount_Cnt_M_u16	28496
VitesseVehicleBV_Kph_M_f32	141.293198
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	22194
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	31214
VitesseVehiculeRoues_Kph_M_f32	436.157288
k_AASNTCEnableTimeout_mS_u16	24429
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	44071
k_AASNodeTimeout_mS_u16	22306
k_ABSNodeTimeout_mS_u16	44438
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	57142
k_ANGLEVOLANTSigValidThresh_Cnt_u16	24119
k_AngleVolantInvalidThresh_Cnt_u16	58278
k_AngleVolantValidThresh_Cnt_u16	3717
k_BSI552MsgTimeout_mS_u16	28701
k_BSINTCEnableTimeout_mS_u16	65131
k_BSINodeAbsentDiag_Cnt_str.Threshold	13537
k_BSINodeAbsentDiag_Cnt_str.PStep	61147
k_BSINodeAbsentDiag_Cnt_str.NStep	49162
k_BSINodeAbsentTimeout_mS_u16	23611
k_BSINodeTimeout_mS_u16	35182
k_BattOvHi_Volt_f32	30.5732994
k_BattOvLo_Volt_f32	6.28879976
k_BattUvHi_Volt_f32	24.6515999
k_BattUvLo_Volt_f32	6.38250017
k_CAVNTCEnableTimeout_mS_u16	33035
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	58555
k_CAVNodeTimeout_mS_u16	33418
k_CMM388MsgTimeout_mS_u16	582
k_CMM388NTCEnableTimeout_mS_u16	3298
k_CMMNTCEnableTimeout_mS_u16	49594
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	39562
k_CONSANGLECPKMax_HwDeg_f32	777.060425
k_CONSANGLECPKMin_HwDeg_f32	-510.46051
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	14770
k_CONSANGLECPKSigValidThresh_Cnt_u16	40174
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	29624
k_CPKVehicleSpeedValidThresh_Cnt_u16	36723
k_CityParkInputInvalidThresh_Cnt_u16	20850
k_CityParkInputValidThresh_Cnt_u16	44488
k_ComputerRazGCTSigValidThresh_Cnt_u16	41336
k_CptTemporelSigValidThresh_Cnt_u16	11376
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	23445
k_DMDFCTCPKSigValidThresh_Cnt_u16	18666
k_DMDFCTCPKValidCount_Cnt_u16	5601
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	3912
k_DMDRELAXECPKSigValidThresh_Cnt_u16	17077
k_DMDRelaxeConsistentThresh_Cnt_u16	59723
k_DateValidThresh_Cnt_u16	8420
k_DefaultVehSpd_Kph_f32	49.2775002
k_DiagMuxOnAbsentTimeout_mS_u16	9812
k_EMNodeTimeout_mS_u16	53259
k_ESPNTCEnableTimeout_mS_u16	59657
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	48210
k_EtatMTSigInvalidThresh_Cnt_u16	51115
k_EtatMTSigValidThresh_Cnt_u16	14327
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	13027
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	24051
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	10145
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	42847
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	41367
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	32396
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	43408
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	6161
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	54935
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	4114
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	36570
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	42098
k_ISDATDIRASentDiag_Cnt_str.Threshold	16910

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	7039
k_ISDATDIRASentDiag_Cnt_str.NStep	21916
k_ISDATDIRASentTimeout_mS_u16	32760
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	7207
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	50179
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	7221
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	35676
k_ISDYNAASChkSumValidThresh_Cnt_u16	3688
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	8607
k_ISDYNAASMsgCountValidThresh_Cnt_u16	46787
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	62400
k_ISDYNAASMsgLenValidThresh_Cnt_u16	36486
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	7679
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	22243
k_ISDYNABRChkSumValidThresh_Cnt_u16	49848
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	40473
k_ISDYNABRMsgCountValidThresh_Cnt_u16	53790
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	48335
k_ISDYNABRMsgLenValidThresh_Cnt_u16	27792
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	32205
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	47274
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	3393
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	5201
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	33650
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	14391
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	10941
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	2475
k_ISDYNVOLChkSumValidThresh_Cnt_u16	4244
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	7501
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	47564
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	46012
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	22253
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	31722
k_IgnOnTimeout_mS_u16	21831
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	56.3931999
k_PowerCutVehSpdLowThresh_Kph_f32	101.088501
k_PowerCutVehSpdLowTimeout_mS_u16	29433
k_VBattMaxAAS_Volt_f32	7.79360008
k_VBattMaxBSI_Volt_f32	30.3152008
k_VBattMaxCAV_Volt_f32	18.6553001
k_VBattMaxCMM388_Volt_f32	20.4029007
k_VBattMaxCMM_Volt_f32	11.6271
k_VBattMaxESP_Volt_f32	19.6126003
k_VBattMinAAS_Volt_f32	7.72730017
k_VBattMinBSI_Volt_f32	19.6126003
k_VBattMinCAV_Volt_f32	6.94110012
k_VBattMinCMM388_Volt_f32	4.01179981
k_VBattMinCMM_Volt_f32	25.9258995
k_VBattMinESP_Volt_f32	11.6271
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	60049
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	40362
k_VitesseVehicleBVRampValidThresh_Cnt_u16	42095
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	52177
k_VitesseVehicleBVSigValidThresh_Cnt_u16	60377
k_VitesseVehicleBVSpeedPassThresh_kph_f32	564.963989
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	45165
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	57993
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	3248036352
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	44013
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	68495872
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	33
target_SrlComInput_Per1_Batt_Volt_f32.value	20.2567005
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	400820736
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	52
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.793080807
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	852703744
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	100
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2909690368
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	157
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	98138624
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	247
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3289684480
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1881127424
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2449136128
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2980444672
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	54
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	107
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	117
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	121
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	225
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	231
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3444414976
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	75
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	93
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	105
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	235
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3174971904
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	149
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3008977408
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	169
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1195670016
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	23
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	86
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	87
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	144
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	157
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	199
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2630060544
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	908
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.996816099
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	104379
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	103.548698
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	6448

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	68495872	68495872	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	68495872	68495872	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	68495872	68495872	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	13537	13537	✔
BSINodeAbsentTimer_mS_M_u32	68495872	68495872	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	68495872	68495872	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
CDD_SrlComVehSpd_Kph_G_f32	158.545898	158.545898	✔
CMM388NTCEnableTimer_mS_M_u32	68495872	68495872	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	68495872	68495872	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	8782	8782	✔
CONSANGLECPK_HwDeg_M_f32	92.9587021	92.9587021 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	68495872	68495872	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	68495872	68495872	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	68495872	68495872	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	68495872	68495872	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	68495872	68495872	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	68495872	68495872	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	68495872	68495872	✔
ESPNTCEnableTimer_mS_M_u32	68495872	68495872	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	707	707	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1235	1235	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	97	97	✔
ElecIntTimer_mS_M_u32[1]	979	979	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	68495872	68495872	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	8420	8420	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	22865	22865	✔
ISDATBSI3F2MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	13088	13088	✔
ISDATBSI412MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	35182	35182	✔
ISDATBSI432MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATDIRASentFltAcc_Cnt_M_u16	16910	16910	✔
ISDATDIRASentTimer_mS_M_u32	68495872	68495872	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	3912	3912	✔
ISDYN2CMMMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	20984	20984	✔
ISDYNAASMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	8782	8782	✔
ISDYNABRMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	22865	22865	✔
ISDYNCMM208MsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	22194	22194	✔
ISDYNCMM388MsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	39375	39375	✔
ISDYNVOLMsgTimer_mS_M_u32	68495872	68495872	✔
IgnOnTimer_mS_M_u32	3591977472	3591977472	✔
IgnTimeOff_Sec_M_u32	3084387365	3084387365	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	198	198	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	852703744	852703744	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	100	100	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2909690368	2909690368	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	157	157	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	98138624	98138624	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	247	247	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3289684480	3289684480	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1019116032	1019116032	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	49	49	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2449136128	2449136128	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2980444672	2980444672	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	169	169	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3444414976	3444414976	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3174971904	3174971904	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	149	149	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3008977408	3008977408	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	169	169	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1195670016	1195670016	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2630060544	2630060544	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	104.901398	104.901398	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	3	3	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	141.293198	141.293198	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	436.157288	436.157288	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	8782	8782	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3084387365	3084387365	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	92.9587021	92.9587021 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.469 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2318861568
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	23539
AASNodeAbsentTimer_mS_M_u32	3162912000
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	10862
ANGLEVOLANTSigValidCount_Cnt_M_u16	43488
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	8636
AngleVolantMsgTimer_mS_M_u32	2318861568
AngleVolantValidCount_Cnt_M_u16	61209
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3380016384
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3686495488
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1909925120
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1668998400
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	13945
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1119724800
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	13311
CAVNodeAbsentTimer_mS_M_u32	2607437056
CDD_SrlComVehSpd_Kph_G_f32	194.759094
CMM388NTCEnableTimer_mS_M_u32	2899678464
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3702019328
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	62871
CMMNodeAbsentTimer_mS_M_u32	1589437696
CONSANGLECPKSigInvalidCount_Cnt_M_u16	45050
CONSANGLECPKSigValidCount_Cnt_M_u16	33661
CONSANGLECPK_Cnt_M_u16	52636
CONSANGLECPK_HwDeg_M_f32	765.98407
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	52636
CPKVehicleSpeedMsgTimer_mS_M_u32	161088768
CPKVehicleSpeedValidCount_Cnt_M_u16	33237
CityParkInputConsistentCount_Cnt_M_u16	24813
CityParkInputInvalidCount_Cnt_M_u16	50101
CityParkInputMsgTimer_mS_M_u32	852703744
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2740598016
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	19399

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	47764736
ComputerRazGCTSigValidCount_Cnt_M_u16	38286
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	15841
DMDFCTCPKSigValidCount_Cnt_M_u16	65308
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	65112
DMDRELAXECPKSigValidCount_Cnt_M_u16	31050
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	43715
DateInvalidTimer_mS_M_u32	3686495488
DiagMuxOnAbsentTimer_mS_M_u32	3235497216
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1668998400
ESPNTCEnableTimer_mS_M_u32	769864960
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	29718
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	8
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	998745344
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	65187
EtatMTSigValidCount_Cnt_M_u16	6610
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	49636
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	4327
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	21082
ISDAT4V2BSI552MsgTimer_mS_M_u32	2089870592
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	55039
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	59734
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	6610
ISDATBSI3F2MsgTimer_mS_M_u32	1726989568
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	20492
ISDATBSI412MsgLenValidCount_Cnt_M_u16	44499
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	65187
ISDATBSI412MsgTimer_mS_M_u32	3729589504
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	35435
ISDATBSI432MsgLenValidCount_Cnt_M_u16	49130
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	17404
ISDATDIRASentFltAcc_Cnt_M_u16	10656
ISDATDIRASentTimer_mS_M_u32	161088768
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	63538
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	61209
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	36204
ISDYN2CMMMsgTimer_mS_M_u32	1940206848
ISDYNAASChkSumInvalidCount_Cnt_M_u16	35805
ISDYNAASChkSumValidCount_Cnt_M_u16	59376
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	60580
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	22878
ISDYNAASMsgLenValidCount_Cnt_M_u16	23049
ISDYNAASMsgTimeValidCount_Cnt_M_u16	35805
ISDYNAASMsgTimer_mS_M_u32	4160853248
ISDYNABRChkSumInvalidCount_Cnt_M_u16	28721
ISDYNABRChkSumValidCount_Cnt_M_u16	42188
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	41448
ISDYNABRMsgCountValidCount_Cnt_M_u16	59
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	40197
ISDYNABRMsgLenValidCount_Cnt_M_u16	45768
ISDYNABRMsgTimeValidCount_Cnt_M_u16	52636
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	47707
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	6610
ISDYNCMM208MsgTimer_mS_M_u32	156759296
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	47707
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	36399

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	3655800064
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	11792
ISDYNVOLChkSumValidCount_Cnt_M_u16	34323
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	54007
ISDYNVOLMsgCountValidCount_Cnt_M_u16	22706
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	37131
ISDYNVOLMsgLenValidCount_Cnt_M_u16	26605
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	62871
ISDYNVOLMsgTimer_mS_M_u32	3389314304
IgnOnTimer_mS_M_u32	1186665728
IgnTimeOff_Sec_M_u32	355452766
ManVehSpd_Kph_M_f32	251.916306
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	84
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	132
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3901605120
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	110
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	725755136
PrevISDATBSI412MsgDLCError_Cnt_M_u08	121
PrevISDATBSI412MsgRxTime_MSec_M_u32	2670155008
PrevISDATBSI432MsgDLCError_Cnt_M_u08	239
PrevISDATBSI432MsgRxTime_MSec_M_u32	3764860160
PrevISDATDIRAMsgTxTime_MSec_M_u32	936072448
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	184
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1930061056
PrevISDYNAASMsgDLCError_Cnt_M_u08	243
PrevISDYNAASMsgRxTime_MSec_M_u32	479909120
PrevISDYNABRMsgDLCError_Cnt_M_u08	18
PrevISDYNABRMsgRxTime_MSec_M_u32	1142101248
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	241
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2214319360
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	133
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3548787968
PrevISDYNVOLMsgDLCError_Cnt_M_u08	189
PrevISDYNVOLMsgRxTime_MSec_M_u32	2449495296
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2573403392
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	90.4484024
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	40052
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	57759
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	43241
VitesseVehicleBVRampValidCount_Cnt_M_u16	52180
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	49763
VitesseVehicleBVSigValidCount_Cnt_M_u16	49045
VitesseVehicleBV_Kph_M_f32	614.538391
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	36399
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	57913
VitesseVehiculeRoues_Kph_M_f32	61.962101
k_AASNTCEnableTimeout_mS_u16	21055
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	41424
k_AASNodeTimeout_mS_u16	30879
k_ABSNodeTimeout_mS_u16	27266
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	33122
k_ANGLEVOLANTSigValidThresh_Cnt_u16	53793
k_AngleVolantInvalidThresh_Cnt_u16	48596
k_AngleVolantValidThresh_Cnt_u16	50101
k_BSI552MsgTimeout_mS_u16	31660
k_BSINTCEnableTimeout_mS_u16	14275
k_BSINodeAbsentDiag_Cnt_str.Threshold	33043
k_BSINodeAbsentDiag_Cnt_str.PStep	12643
k_BSINodeAbsentDiag_Cnt_str.NStep	27671
k_BSINodeAbsentTimeout_mS_u16	14612
k_BSINodeTimeout_mS_u16	17404
k_BattOvHi_Volt_f32	23.9379005
k_BattOvLo_Volt_f32	14.3668003
k_BattUvHi_Volt_f32	3.6803
k_BattUvLo_Volt_f32	31.5
k_CAVNTCEnableTimeout_mS_u16	1059
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	42517
k_CAVNodeTimeout_mS_u16	4902
k_CMM388MsgTimeout_mS_u16	13043
k_CMM388NTCEnableTimeout_mS_u16	33567
k_CMMNTCEnableTimeout_mS_u16	61527
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	61541
k_CONSANGLECPKMax_HwDeg_f32	566.379028
k_CONSANGLECPKMin_HwDeg_f32	-748.047729
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	58671
k_CONSANGLECPKSigValidThresh_Cnt_u16	31033
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	64221
k_CPKVehicleSpeedValidThresh_Cnt_u16	64555
k_CityParkInputInvalidThresh_Cnt_u16	19695
k_CityParkInputValidThresh_Cnt_u16	24813
k_ComputerRazGCTSigValidThresh_Cnt_u16	51485
k_CptTemporelSigValidThresh_Cnt_u16	54772
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	29701
k_DMDFCTCPKSigValidThresh_Cnt_u16	51656
k_DMDFCTCPKValidCount_Cnt_u16	50721
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	36204
k_DMDRELAXECPKSigValidThresh_Cnt_u16	28903
k_DMDRelaxeConsistentThresh_Cnt_u16	21797
k_DateValidThresh_Cnt_u16	21082
k_DefaultVehSpd_Kph_f32	240.443893
k_DiagMuxOnAbsentTimeout_mS_u16	22922
k_EMNodeTimeout_mS_u16	28323
k_ESPNTCEnableTimeout_mS_u16	20779
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	43789
k_EtatMTSigInvalidThresh_Cnt_u16	3652
k_EtatMTSigValidThresh_Cnt_u16	47903
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	10588
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	46571
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	38754
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	4968
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	53887
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	53984
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	2644
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	35987
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	24383
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	5200
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	34231
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	51758
k_ISDATDIRASentDiag_Cnt_str.Threshold	32887

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	20123
k_ISDATDIRASentDiag_Cnt_str.NStep	32507
k_ISDATDIRASentTimeout_mS_u16	22877
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	30479
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	8636
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	26535
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	50993
k_ISDYNAASChkSumValidThresh_Cnt_u16	15308
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	30952
k_ISDYNAASMsgCountValidThresh_Cnt_u16	5947
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	7685
k_ISDYNAASMsgLenValidThresh_Cnt_u16	25203
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	45769
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	14875
k_ISDYNABRChkSumValidThresh_Cnt_u16	5214
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	3449
k_ISDYNABRMsgCountValidThresh_Cnt_u16	20267
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	35991
k_ISDYNABRMsgLenValidThresh_Cnt_u16	19222
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	51230
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	42568
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	15041
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	48402
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	366
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	49376
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	20237
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	28035
k_ISDYNVOLChkSumValidThresh_Cnt_u16	50826
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	27871
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	51616
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	60623
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	37118
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	55624
k_IgnOnTimeout_mS_u16	64175
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	217.596802
k_PowerCutVehSpdLowThresh_Kph_f32	155.510803
k_PowerCutVehSpdLowTimeout_mS_u16	18331
k_VBattMaxAAS_Volt_f32	21.7721004
k_VBattMaxBSI_Volt_f32	8.15450001
k_VBattMaxCAV_Volt_f32	10.6821003
k_VBattMaxCMM388_Volt_f32	5.76160002
k_VBattMaxCMM_Volt_f32	27.4158993
k_VBattMaxESP_Volt_f32	16.7045994
k_VBattMinAAS_Volt_f32	13.4308004
k_VBattMinBSI_Volt_f32	16.7045994
k_VBattMinCAV_Volt_f32	22.8470001
k_VBattMinCMM388_Volt_f32	27.8320999
k_VBattMinCMM_Volt_f32	0.729700029
k_VBattMinESP_Volt_f32	27.4158993
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	13265
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	18503
k_VitesseVehicleBVRampValidThresh_Cnt_u16	10743
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	40211
k_VitesseVehicleBVSigValidThresh_Cnt_u16	10938
k_VitesseVehicleBVSpeedPassThresh_kph_f32	336.368713
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	35583
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	12906
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3686495488
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65109
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3632743680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	133
target_SrlComInput_Per1_Batt_Volt_f32.value	5.13940001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4036666624
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	43
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.531221032
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	44
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2559382784
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	4248548608
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	79
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	142234880
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	245
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	575206656
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2997327104
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	111
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	563492096
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3608466688
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	32
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	52
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	53
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	79
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	102
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	109
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	180
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	714994944
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	65
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	172
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	197
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	220
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	228
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1699484928
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	96
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1467659520
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2956547328
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	47
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	77
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	89
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	90
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	138
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	149
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1073489152
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1067
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.651292324
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	494555
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	111.380203
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	7350

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3632743680	3632743680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	52636	52636	✔
CONSANGLECPK_HwDeg_M_f32	765.98407	765.98407 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3632743680	3632743680	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3632743680	3632743680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3632743680	3632743680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3632743680	3632743680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3632743680	3632743680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3632743680	3632743680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3632743680	3632743680	✔
ESPNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4	4	✔
ElecIntTimer_mS_M_u32[1]	8	8	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3632743680	3632743680	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	32887	32887	✔
ISDATDIRASentTimer_mS_M_u32	3632743680	3632743680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3632743680	3632743680	✔
IgnOnTimer_mS_M_u32	3632743680	3632743680	✔
IgnTimeOff_Sec_M_u32	355452766	355452766	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	44	44	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2559382784	2559382784	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	132	132	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4248548608	4248548608	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	79	79	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	142234880	142234880	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	245	245	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	575206656	575206656	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	936072448	936072448	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	111	111	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	563492096	563492096	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3608466688	3608466688	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	3	3	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	714994944	714994944	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	90	90	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1699484928	1699484928	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	96	96	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1467659520	1467659520	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	152	152	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2956547328	2956547328	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1073489152	1073489152	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	90.4484024	90.4484024	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	614.538391	614.538391	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	61.962101	61.962101	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	52636	52636	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	355452766	355452766	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	765.98407	765.98407 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	240.443893	240.443893	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.470 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	830842624
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	9510
AASNodeAbsentTimer_mS_M_u32	567170816
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	11124
ANGLEVOLANTSigValidCount_Cnt_M_u16	15868
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	49463
AngleVolantMsgTimer_mS_M_u32	830842624
AngleVolantValidCount_Cnt_M_u16	39544
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1682249472
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3702363904
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1663485696
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1743292160
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	4055
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1598113536
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	43667
CAVNodeAbsentTimer_mS_M_u32	2765321984
CDD_SrlComVehSpd_Kph_G_f32	609.589783
CMM388NTCEnableTimer_mS_M_u32	3550000896
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	536966912
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	12906
CMMNodeAbsentTimer_mS_M_u32	221939456
CONSANGLECPKSigInvalidCount_Cnt_M_u16	2919
CONSANGLECPKSigValidCount_Cnt_M_u16	37503
CONSANGLECPK_Cnt_M_u16	50582
CONSANGLECPK_HwDeg_M_f32	451.267212
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	50582
CPKVehicleSpeedMsgTimer_mS_M_u32	3825248000
CPKVehicleSpeedValidCount_Cnt_M_u16	22243
CityParkInputConsistentCount_Cnt_M_u16	47852

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	36343
CityParkInputMsgTimer_mS_M_u32	881558528
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1598183168
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	45978
ComputerRazGCTSigInvalidTimer_mS_M_u32	733345536
ComputerRazGCTSigValidCount_Cnt_M_u16	64661
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	47491
DMDFCTCPKSigValidCount_Cnt_M_u16	23571
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	44718
DMDRELAXECPKSigValidCount_Cnt_M_u16	39094
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	33912
DateInvalidTimer_mS_M_u32	3702363904
DiagMuxOnAbsentTimer_mS_M_u32	993945344
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1743292160
ESPNTCEnableTimer_mS_M_u32	3860027136
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	7262
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	87
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	21
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	777733888
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	32216
EtatMTSigValidCount_Cnt_M_u16	27133
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	48289
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	39737
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	31041
ISDAT4V2BSI552MsgTimer_mS_M_u32	967739136
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	27667
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	18592
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	27133
ISDATBSI3F2MsgTimer_mS_M_u32	33842944
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	3979
ISDATBSI412MsgLenValidCount_Cnt_M_u16	4871
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	32216
ISDATBSI412MsgTimer_mS_M_u32	374056704
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	36318
ISDATBSI432MsgLenValidCount_Cnt_M_u16	59090
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	632
ISDATDIRASentFltAcc_Cnt_M_u16	46396
ISDATDIRASentTimer_mS_M_u32	3825248000
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	13532
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	39544
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	64870
ISDYN2CMMMsgTimer_mS_M_u32	702895872
ISDYNAASChkSumInvalidCount_Cnt_M_u16	58464
ISDYNAASChkSumValidCount_Cnt_M_u16	47240
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	64603
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	37610
ISDYNAASMsgLenValidCount_Cnt_M_u16	61546
ISDYNAASMsgTimeValidCount_Cnt_M_u16	58464
ISDYNAASMsgTimer_mS_M_u32	1478801152
ISDYNABRChkSumInvalidCount_Cnt_M_u16	12887
ISDYNABRChkSumValidCount_Cnt_M_u16	58183
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	8899
ISDYNABRMsgCountValidCount_Cnt_M_u16	2859
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	55498
ISDYNABRMsgLenValidCount_Cnt_M_u16	46114
ISDYNABRMsgTimeValidCount_Cnt_M_u16	50582
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	43890

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	2127
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	27133
ISDYNCMM208MsgTimer_mS_M_u32	187569920
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	43890
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	2127
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	8766
ISDYNCMM388MsgTimer_mS_M_u32	2234922752
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	27181
ISDYNVOLChkSumValidCount_Cnt_M_u16	39365
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	59209
ISDYNVOLMsgCountValidCount_Cnt_M_u16	29273
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	43259
ISDYNVOLMsgLenValidCount_Cnt_M_u16	20084
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	12906
ISDYNVOLMsgTimer_mS_M_u32	205649664
IgnOnTimer_mS_M_u32	2024421120
IgnTimeOff_Sec_M_u32	494045880
ManVehSpd_Kph_M_f32	168.978806
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	97
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	144
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3230820096
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	116
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1609156352
PrevISDATBSI412MsgDLCError_Cnt_M_u08	44
PrevISDATBSI412MsgRxTime_MSec_M_u32	2390259456
PrevISDATBSI432MsgDLCError_Cnt_M_u08	39
PrevISDATBSI432MsgRxTime_MSec_M_u32	3434567424
PrevISDATDIRAMsgTxTime_MSec_M_u32	2352772864
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	238
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1072957184
PrevISDYNAASMsgDLCError_Cnt_M_u08	237
PrevISDYNAASMsgRxTime_MSec_M_u32	3817338624
PrevISDYNABRMsgDLCError_Cnt_M_u08	114
PrevISDYNABRMsgRxTime_MSec_M_u32	549598976
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	133
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3991992064
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	224
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4040054528
PrevISDYNVOLMsgDLCError_Cnt_M_u08	71
PrevISDYNVOLMsgRxTime_MSec_M_u32	1075410688
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2584848128
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	132.282196
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57008
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	42160
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	54989
VitesseVehicleBVRampValidCount_Cnt_M_u16	26765
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	2833
VitesseVehicleBVSigValidCount_Cnt_M_u16	35161

Name	Input Value
VitesseVehicleBV_Kph_M_f32	495.712311
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	8766
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	28190
VitesseVehiculeRoues_Kph_M_f32	186.128799
k_AASNTCEnableTimeout_mS_u16	42833
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	15079
k_AASNodeTimeout_mS_u16	62384
k_ABSNodeTimeout_mS_u16	45868
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	38029
k_ANGLEVOLANTSigValidThresh_Cnt_u16	58049
k_AngleVolantInvalidThresh_Cnt_u16	58380
k_AngleVolantValidThresh_Cnt_u16	36343
k_BSI552MsgTimeout_mS_u16	35625
k_BSINTCEnableTimeout_mS_u16	26102
k_BSINodeAbsentDiag_Cnt_str.Threshold	28392
k_BSINodeAbsentDiag_Cnt_str.PStep	49975
k_BSINodeAbsentDiag_Cnt_str.NStep	2138
k_BSINodeAbsentTimeout_mS_u16	21327
k_BSINodeTimeout_mS_u16	632
k_BattOvHi_Volt_f32	17.4053001
k_BattOvLo_Volt_f32	7.62769985
k_BattUvHi_Volt_f32	28.1823006
k_BattUvLo_Volt_f32	28.2677002
k_CAVNTCEnableTimeout_mS_u16	33237
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	40281
k_CAVNodeTimeout_mS_u16	26611
k_CMM388MsgTimeout_mS_u16	46118
k_CMM388NTCEnableTimeout_mS_u16	26034
k_CMMNTCEnableTimeout_mS_u16	4139
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	52650
k_CONSANGLECPKMax_HwDeg_f32	123.3797
k_CONSANGLECPKMin_HwDeg_f32	-318.267395
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	12606
k_CONSANGLECPKSigValidThresh_Cnt_u16	48414
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	47070
k_CPKVehicleSpeedValidThresh_Cnt_u16	46242
k_CityParkInputInvalidThresh_Cnt_u16	9477
k_CityParkInputValidThresh_Cnt_u16	47852
k_ComputerRazGCTSigValidThresh_Cnt_u16	7969
k_CptTemporelSigValidThresh_Cnt_u16	51758
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	26570
k_DMDFCTCPKSigValidThresh_Cnt_u16	33570
k_DMDFCTCPKValidCount_Cnt_u16	23743
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	64870
k_DMDRELAXECPKSigValidThresh_Cnt_u16	54326
k_DMDRelaxeConsistentThresh_Cnt_u16	2660
k_DateValidThresh_Cnt_u16	31041
k_DefaultVehSpd_Kph_f32	154.583099
k_DiagMuxOnAbsentTimeout_mS_u16	24820
k_EMNodeTimeout_mS_u16	26456
k_ESPNTCEnableTimeout_mS_u16	37151
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	40338
k_EtatMTSigInvalidThresh_Cnt_u16	30978
k_EtatMTSigValidThresh_Cnt_u16	25650
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	62037
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	56025
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	11529
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	13252
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	8977
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	51455
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	46351

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	49347
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	10578
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	25066
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	5638
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	56502
k_ISDATDIRASentDiag_Cnt_str.Threshold	58484
k_ISDATDIRASentDiag_Cnt_str.PStep	41555
k_ISDATDIRASentDiag_Cnt_str.NStep	45799
k_ISDATDIRASentTimeout_mS_u16	17635
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	22687
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	49463
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	47995
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	16727
k_ISDYNAASChkSumValidThresh_Cnt_u16	12871
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	45507
k_ISDYNAASMsgCountValidThresh_Cnt_u16	55851
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	28363
k_ISDYNAASMsgLenValidThresh_Cnt_u16	19492
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	2217
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	20112
k_ISDYNABRChkSumValidThresh_Cnt_u16	4712
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	40663
k_ISDYNABRMsgCountValidThresh_Cnt_u16	34207
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	33130
k_ISDYNABRMsgLenValidThresh_Cnt_u16	43870
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	32298
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	22308
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	55272
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	5051
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	47732
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	3324
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	13327
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	28858
k_ISDYNVOLChkSumValidThresh_Cnt_u16	18806
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	33647
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	20155
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	48484
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	31369
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	59295
k_IgnOnTimeout_mS_u16	18246
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	177.958603
k_PowerCutVehSpdLowThresh_Kph_f32	147.185196
k_PowerCutVehSpdLowTimeout_mS_u16	42893
k_VBattMaxAAS_Volt_f32	13.7516003
k_VBattMaxBSI_Volt_f32	4.24329996
k_VBattMaxCAV_Volt_f32	3.85369992
k_VBattMaxCMM388_Volt_f32	31.3696995
k_VBattMaxCMM_Volt_f32	10.1473999
k_VBattMaxESP_Volt_f32	20.1574001
k_VBattMinAAS_Volt_f32	15.9591999
k_VBattMinBSI_Volt_f32	20.1574001
k_VBattMinCAV_Volt_f32	29.7418003
k_VBattMinCMM388_Volt_f32	6.15859985
k_VBattMinCMM_Volt_f32	28.7502003
k_VBattMinESP_Volt_f32	10.1473999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	52081
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	47901
k_VitesseVehicleBVRampValidThresh_Cnt_u16	63049
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	26821
k_VitesseVehicleBVSigValidThresh_Cnt_u16	6945
k_VitesseVehicleBVSpeedPassThresh_kph_f32	111.188797
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	47507
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	62419
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3702363904
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	61417
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1499264000
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	224
target_SrlComInput_Per1_Batt_Volt_f32.value	11.8276997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1141262080
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	159
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.207585633
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2836150016
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	607115008
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4200822528
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	244
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3550942976
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1476048640
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	794711808
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	30537472
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	65
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	139
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	230
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	250
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2795771648
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	23
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	46
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1942173440
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3899053824
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2015000320
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	108
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	213
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2859714304
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3780
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0360774584
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	166403
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	112.509598

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	12546		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	1499264000	1499264000	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	28392	28392	✔
BSINodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
CDD_SrlComVehSpd_Kph_G_f32	168.978806	168.978806	✔
CMM388NTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	50582	50582	✔
CONSANGLECPK_HwDeg_M_f32	451.267212	451.267212 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1499264000	1499264000	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	1499264000	1499264000	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1499264000	1499264000	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1499264000	1499264000	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1499264000	1499264000	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1499264000	1499264000	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	1499264000	1499264000	✔
ESPNTCEnableTimer_mS_M_u32	1499264000	1499264000	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1499264000	1499264000	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	87	87	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	20	20	✔
ElecIntTimer_mS_M_u32[1]	21	21	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1499264000	1499264000	✔
EngOnDLCInvalidCount_Cnt_M_u08	2	2	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	31041	31041	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	27133	27133	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	32216	32216	✔
ISDATBSI412MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	632	632	✔
ISDATBSI432MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDATDIRASentFltAcc_Cnt_M_u16	58484	58484	✔
ISDATDIRASentTimer_mS_M_u32	1499264000	1499264000	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	64870	64870	✔
ISDYN2CMMMsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	58464	58464	✔
ISDYNAASMsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	50582	50582	✔
ISDYNABRMsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	27133	27133	✔
ISDYNCMM208MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	8766	8766	✔
ISDYNCMM388MsgTimer_mS_M_u32	1499264000	1499264000	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	12906	12906	✔
ISDYNVOLMsgTimer_mS_M_u32	1499264000	1499264000	✔
IgnOnTimer_mS_M_u32	2024421120	2024421120	✔
IgnTimeOff_Sec_M_u32	494045880	494045880	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	81	81	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2836150016	2836150016	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	29	29	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	607115008	607115008	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	113	113	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4200822528	4200822528	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	244	244	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3550942976	3550942976	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2352772864	2352772864	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	38	38	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	794711808	794711808	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	38	38	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	30537472	30537472	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	250	250	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2795771648	2795771648	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	135	135	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1942173440	1942173440	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3899053824	3899053824	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	154	154	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2015000320	2015000320	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2859714304	2859714304	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	132.282196	132.282196	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	495.712311	495.712311	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	186.128799	186.128799	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	50582	50582	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	494045880	494045880	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	451.267212	451.267212 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	168.978806	168.978806	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.471 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3127496192
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	392
AASNodeAbsentTimer_mS_M_u32	676314624
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	18588
ANGLEVOLANTSigValidCount_Cnt_M_u16	44484
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	45397
AngleVolantMsgTimer_mS_M_u32	3127496192
AngleVolantValidCount_Cnt_M_u16	46096
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2884337152
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2226257408
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2449894912
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3133222400
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	59251
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	666299904
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	3520
CAVNodeAbsentTimer_mS_M_u32	2613075456
CDD_SrlComVehSpd_Kph_G_f32	89.5624008
CMM388NTCEnableTimer_mS_M_u32	3027279360
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1647730176
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	24570
CMMNodeAbsentTimer_mS_M_u32	2462789120
CONSANGLECPKSigInvalidCount_Cnt_M_u16	58308
CONSANGLECPKSigValidCount_Cnt_M_u16	11067
CONSANGLECPK_Cnt_M_u16	44534
CONSANGLECPK_HwDeg_M_f32	-575.999573
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	44534
CPKVehicleSpeedMsgTimer_mS_M_u32	1324928512
CPKVehicleSpeedValidCount_Cnt_M_u16	4375
CityParkInputConsistentCount_Cnt_M_u16	8884
CityParkInputInvalidCount_Cnt_M_u16	41621
CityParkInputMsgTimer_mS_M_u32	2836150016
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1072938496
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	9772

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2971196928
ComputerRazGCTSigValidCount_Cnt_M_u16	16825
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	20465
DMDFCTCPKSigValidCount_Cnt_M_u16	9473
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	9966
DMDRELAXECPKSigValidCount_Cnt_M_u16	1430
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	64657
DateInvalidTimer_mS_M_u32	2226257408
DiagMuxOnAbsentTimer_mS_M_u32	1883213312
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3133222400
ESPNTCEnableTimer_mS_M_u32	796966400
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	61150
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	707
EffacDefaultDiagTimer_mS_M_u32[1]	1235
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8976
ElecIntTimer_mS_M_u32[1]	15237
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2724785664
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	1711
EtatMTSigValidCount_Cnt_M_u16	20227
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	14358
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	30989
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	1399
ISDAT4V2BSI552MsgTimer_mS_M_u32	3715051008
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	16255
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	22170
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	20227
ISDATBSI3F2MsgTimer_mS_M_u32	3018690048
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	16921
ISDATBSI412MsgLenValidCount_Cnt_M_u16	42084
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	1711
ISDATBSI412MsgTimer_mS_M_u32	2753023488
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	7582
ISDATBSI432MsgLenValidCount_Cnt_M_u16	24450
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	55825
ISDATDIRASentFltAcc_Cnt_M_u16	53701
ISDATDIRASentTimer_mS_M_u32	1324928512
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	63524
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	46096
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	53320
ISDYN2CMMMsgTimer_mS_M_u32	738901504
ISDYNAASChkSumInvalidCount_Cnt_M_u16	11226
ISDYNAASChkSumValidCount_Cnt_M_u16	52257
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	55911
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	28859
ISDYNAASMsgLenValidCount_Cnt_M_u16	54523
ISDYNAASMsgTimeValidCount_Cnt_M_u16	11226
ISDYNAASMsgTimer_mS_M_u32	1456250368
ISDYNABRChkSumInvalidCount_Cnt_M_u16	55156
ISDYNABRChkSumValidCount_Cnt_M_u16	355
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	48305
ISDYNABRMsgCountValidCount_Cnt_M_u16	8248
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	51099
ISDYNABRMsgLenValidCount_Cnt_M_u16	4690
ISDYNABRMsgTimeValidCount_Cnt_M_u16	44534
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	60673
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	47786
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	20227
ISDYNCMM208MsgTimer_mS_M_u32	2603646464
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	60673
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	47786
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	46270

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	4120387072
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	24434
ISDYNVOLChkSumValidCount_Cnt_M_u16	44393
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	24223
ISDYNVOLMsgCountValidCount_Cnt_M_u16	31279
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	64775
ISDYNVOLMsgLenValidCount_Cnt_M_u16	26974
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	24570
ISDYNVOLMsgTimer_mS_M_u32	1064623616
IgnOnTimer_mS_M_u32	3946585600
IgnTimeOff_Sec_M_u32	1970245427
ManVehSpd_Kph_M_f32	546.744385
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	98
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	63
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	809733632
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	148
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1740467712
PrevISDATBSI412MsgDLCError_Cnt_M_u08	240
PrevISDATBSI412MsgRxTime_MSec_M_u32	3000065536
PrevISDATBSI432MsgDLCError_Cnt_M_u08	192
PrevISDATBSI432MsgRxTime_MSec_M_u32	194297344
PrevISDATDIRAMsgTxTime_MSec_M_u32	3380960768
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	222
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3231624704
PrevISDYNAASMsgDLCError_Cnt_M_u08	248
PrevISDYNAASMsgRxTime_MSec_M_u32	1369628160
PrevISDYNABRMsgDLCError_Cnt_M_u08	197
PrevISDYNABRMsgRxTime_MSec_M_u32	1391730176
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	173
PrevISDYNCMM208MsgRxTime_MSec_M_u32	375905792
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	97
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3142565376
PrevISDYNVOLMsgDLCError_Cnt_M_u08	141
PrevISDYNVOLMsgRxTime_MSec_M_u32	1643011584
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2965753344
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	172.911896
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	9577
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	20521
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	61714
VitesseVehicleBVRampValidCount_Cnt_M_u16	47250
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	24005
VitesseVehicleBVSigValidCount_Cnt_M_u16	32685
VitesseVehicleBV_Kph_M_f32	361.971588
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	46270
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	52701
VitesseVehiculeRoues_Kph_M_f32	202.377106
k_AASNTCEnableTimeout_mS_u16	46277
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	20163
k_AASNodeTimeout_mS_u16	25385
k_ABSNodeTimeout_mS_u16	18166
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	34193
k_ANGLEVOLANTSigValidThresh_Cnt_u16	59317
k_AngleVolantInvalidThresh_Cnt_u16	53204
k_AngleVolantValidThresh_Cnt_u16	41621
k_BSI552MsgTimeout_mS_u16	25276
k_BSINTCEnableTimeout_mS_u16	62806
k_BSINodeAbsentDiag_Cnt_str.Threshold	58639
k_BSINodeAbsentDiag_Cnt_str.PStep	1938
k_BSINodeAbsentDiag_Cnt_str.NStep	23529
k_BSINodeAbsentTimeout_mS_u16	23309
k_BSINodeTimeout_mS_u16	55825
k_BattOvHi_Volt_f32	27.4127998
k_BattOvLo_Volt_f32	7.20230007
k_BattUvHi_Volt_f32	14.1884003
k_BattUvLo_Volt_f32	19.6133995
k_CAVNTCEnableTimeout_mS_u16	48891
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	52590
k_CAVNodeTimeout_mS_u16	65056
k_CMM388MsgTimeout_mS_u16	21640
k_CMM388NTCEnableTimeout_mS_u16	28644
k_CMMNTCEnableTimeout_mS_u16	45879
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	57145
k_CONSANGLECPKMax_HwDeg_f32	694.521118
k_CONSANGLECPKMin_HwDeg_f32	-231.827698
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	34750
k_CONSANGLECPKSigValidThresh_Cnt_u16	57565
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	20127
k_CPKVehicleSpeedValidThresh_Cnt_u16	28372
k_CityParkInputInvalidThresh_Cnt_u16	14186
k_CityParkInputValidThresh_Cnt_u16	8884
k_ComputerRazGCTSigValidThresh_Cnt_u16	56917
k_CptTemporelSigValidThresh_Cnt_u16	35312
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	6811
k_DMDFCTCPKSigValidThresh_Cnt_u16	42322
k_DMDFCTCPKValidCount_Cnt_u16	41147
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	53320
k_DMDRELAXECPKSigValidThresh_Cnt_u16	2200
k_DMDRelaxeConsistentThresh_Cnt_u16	40462
k_DateValidThresh_Cnt_u16	1399
k_DefaultVehSpd_Kph_f32	197.730194
k_DiagMuxOnAbsentTimeout_mS_u16	54236
k_EMNodeTimeout_mS_u16	54257
k_ESPNTCEnableTimeout_mS_u16	35356
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	3969
k_EtatMTSigInvalidThresh_Cnt_u16	28531
k_EtatMTSigValidThresh_Cnt_u16	60066
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	15162
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	3693
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	32861
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	60524
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	52039
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	58813
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	44043
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	54703
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	6978
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	10490
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	63846
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	38807
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	53200
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	2012
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	45397
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	31496
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	43636
k_ISDYNAASChkSumValidThresh_Cnt_u16	5219
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	4017
k_ISDYNAASMsgCountValidThresh_Cnt_u16	45880
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	61976
k_ISDYNAASMsgLenValidThresh_Cnt_u16	10701
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	5629
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	65097
k_ISDYNABRChkSumValidThresh_Cnt_u16	36736
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	14963
k_ISDYNABRMsgCountValidThresh_Cnt_u16	8923
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	29434
k_ISDYNABRMsgLenValidThresh_Cnt_u16	16862
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	9530
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	35853
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	40194
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	61192
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	39836
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	16580
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	4173
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	39564
k_ISDYNVOLChkSumValidThresh_Cnt_u16	32023
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	15787
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	36615
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	30731
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	19807
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	45661
k_IgnOnTimeout_mS_u16	18152
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	168.103699
k_PowerCutVehSpdLowThresh_Kph_f32	108.424004
k_PowerCutVehSpdLowTimeout_mS_u16	42001
k_VBattMaxAAS_Volt_f32	11.2720003
k_VBattMaxBSI_Volt_f32	2.22059989
k_VBattMaxCAV_Volt_f32	21.5974007
k_VBattMaxCMM388_Volt_f32	29.3481998
k_VBattMaxCMM_Volt_f32	21.1823006
k_VBattMaxESP_Volt_f32	29.5338001
k_VBattMinAAS_Volt_f32	4.23019981
k_VBattMinBSI_Volt_f32	29.5338001
k_VBattMinCAV_Volt_f32	3.32669997
k_VBattMinCMM388_Volt_f32	11.7502003
k_VBattMinCMM_Volt_f32	22.7047005
k_VBattMinESP_Volt_f32	21.1823006
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	30566
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	54562
k_VitesseVehicleBVRampValidThresh_Cnt_u16	12703
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	16489
k_VitesseVehicleBVSigValidThresh_Cnt_u16	5653
k_VitesseVehicleBVSpeedPassThresh_kph_f32	306.056305
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	57536
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	44736
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2226257408
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	37067
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2354571008
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	97
target_SrlComInput_Per1_Batt_Volt_f32.value	26.0769997
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3446140416
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	78
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.190272257
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	54
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1645616640
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	71
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2267758080
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	2
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3675282944
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1707441664
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	793419264
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	134
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1067433472
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	60
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2663702016
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	124
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	137
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	182
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	219
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	223
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	237
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	550403584
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	100
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	162
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	232
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	242
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	244
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2649824768
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	244
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3599121920
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4260060672
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	30
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	150
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	191
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	807366144
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1972
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.570788622
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	468645
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	180.700699
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	63091

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2354571008	2354571008	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	45399	45399	✔
AngleVolantMsgTimer_mS_M_u32	2354571008	2354571008	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2354571008	2354571008	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2354571008	2354571008	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2354571008	2354571008	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	44534	44534	✔
CONSANGLECPK_HwDeg_M_f32	-575.999573	-575.999573 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	44534	44534	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1324928512	1324928512	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	4375	4375	✔
CityParkInputConsistentCount_Cnt_M_u16	8884	8884	✔
CityParkInputInvalidCount_Cnt_M_u16	41621	41621	✔
CityParkInputMsgTimer_mS_M_u32	2354571008	2354571008	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2354571008	2354571008	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2354571008	2354571008	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2354571008	2354571008	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2354571008	2354571008	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2354571008	2354571008	✔
ESPNTCEnableTimer_mS_M_u32	2354571008	2354571008	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2354571008	2354571008	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	707	707	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1235	1235	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	8976	8976	✔
ElecIntTimer_mS_M_u32[1]	15237	15237	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2354571008	2354571008	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11170	11170	✔
ISDATDIRASentTimer_mS_M_u32	2354571008	2354571008	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2354571008	2354571008	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2354571008	2354571008	✔
IgnOnTimer_mS_M_u32	2354571008	2354571008	✔
IgnTimeOff_Sec_M_u32	1970245427	1970245427	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	54	54	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1645616640	1645616640	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	71	71	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2267758080	2267758080	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	2	2	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3675282944	3675282944	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	113	113	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1707441664	1707441664	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3380960768	3380960768	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	134	134	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1067433472	1067433472	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	60	60	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2663702016	2663702016	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	144	144	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	550403584	550403584	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	48	48	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2649824768	2649824768	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	244	244	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3599121920	3599121920	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	35	35	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4260060672	4260060672	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	807366144	807366144	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	172.911896	172.911896	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	361.971588	361.971588	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	202.377106	202.377106	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	44534	44534	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1970245427	1970245427	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-575.999573	-575.999573 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	197.730194	197.730194	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.472 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1828056320
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	36098
AASNodeAbsentTimer_mS_M_u32	1249058048
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	61068
ANGLEVOLANTSigValidCount_Cnt_M_u16	63197
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	12651
AngleVolantMsgTimer_mS_M_u32	1828056320
AngleVolantValidCount_Cnt_M_u16	18508
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1755045120
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1714445568
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3486125312
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	495308032
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	29815
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3275787520
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	12226
CAVNodeAbsentTimer_mS_M_u32	1393245440
CDD_SrlComVehSpd_Kph_G_f32	584.309814
CMM388NTCEnableTimer_mS_M_u32	3367927040
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	688471296
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	48320
CMMNodeAbsentTimer_mS_M_u32	3557281024
CONSANGLECPKSigInvalidCount_Cnt_M_u16	41681
CONSANGLECPKSigValidCount_Cnt_M_u16	6450
CONSANGLECPK_Cnt_M_u16	7601
CONSANGLECPK_HwDeg_M_f32	183.107895
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	7601
CPKVehicleSpeedMsgTimer_mS_M_u32	356052224
CPKVehicleSpeedValidCount_Cnt_M_u16	38599

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	4768
CityParkInputInvalidCount_Cnt_M_u16	59600
CityParkInputMsgTimer_mS_M_u32	2038448640
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2848398592
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	38230
ComputerRazGCTSigInvalidTimer_mS_M_u32	973716736
ComputerRazGCTSigValidCount_Cnt_M_u16	34017
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	35452
DMDFCTCPKSigValidCount_Cnt_M_u16	31124
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	20150
DMDRELAXECPKSigValidCount_Cnt_M_u16	647
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	39994
DateInvalidTimer_mS_M_u32	1714445568
DiagMuxOnAbsentTimer_mS_M_u32	1712368896
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	495308032
ESPNTCEnableTimer_mS_M_u32	3404733696
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	55197
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	1100
ElecIntTimer_mS_M_u32[1]	1152
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	877300992
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	18356
EtatMTSigValidCount_Cnt_M_u16	7489
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	251
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	41692
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	41362
ISDAT4V2BSI552MsgTimer_mS_M_u32	3395013888
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	48732
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	60433
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	7489
ISDATBSI3F2MsgTimer_mS_M_u32	3219565824
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	29425
ISDATBSI412MsgLenValidCount_Cnt_M_u16	534
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	18356
ISDATBSI412MsgTimer_mS_M_u32	885779712
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	35348
ISDATBSI432MsgLenValidCount_Cnt_M_u16	48113
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	4831
ISDATDIRASentFltAcc_Cnt_M_u16	771
ISDATDIRASentTimer_mS_M_u32	356052224
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	19463
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	18508
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	999
ISDYN2CMMMsgTimer_mS_M_u32	3690077440
ISDYNAASChkSumInvalidCount_Cnt_M_u16	51500
ISDYNAASChkSumValidCount_Cnt_M_u16	12829
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	12215
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	22401
ISDYNAASMsgLenValidCount_Cnt_M_u16	7178
ISDYNAASMsgTimeValidCount_Cnt_M_u16	51500
ISDYNAASMsgTimer_mS_M_u32	3681189120
ISDYNABRChkSumInvalidCount_Cnt_M_u16	23452
ISDYNABRChkSumValidCount_Cnt_M_u16	14869
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	39191
ISDYNABRMsgCountValidCount_Cnt_M_u16	44104
ISDYNABRMsgCount_Cnt_M_u08	4
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	43452
ISDYNABRMsgLenValidCount_Cnt_M_u16	2653
ISDYNABRMsgTimeValidCount_Cnt_M_u16	7601

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	58010
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	35167
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	7489
ISDYNCMM208MsgTimer_mS_M_u32	773643520
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	58010
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	35167
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	15138
ISDYNCMM388MsgTimer_mS_M_u32	3326082304
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	54439
ISDYNVOLChkSumValidCount_Cnt_M_u16	8072
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	13138
ISDYNVOLMsgCountValidCount_Cnt_M_u16	14058
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	6834
ISDYNVOLMsgLenValidCount_Cnt_M_u16	4210
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	48320
ISDYNVOLMsgTimer_mS_M_u32	1219869952
IgnOnTimer_mS_M_u32	1804860672
IgnTimeOff_Sec_M_u32	3055494451
ManVehSpd_Kph_M_f32	161.210007
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	102
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	196
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1917103360
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	9
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3205827840
PrevISDATBSI412MsgDLCError_Cnt_M_u08	94
PrevISDATBSI412MsgRxTime_MSec_M_u32	1105739008
PrevISDATBSI432MsgDLCError_Cnt_M_u08	153
PrevISDATBSI432MsgRxTime_MSec_M_u32	1945378048
PrevISDATDIRAMsgTxTime_MSec_M_u32	3305913600
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	45
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2588232960
PrevISDYNAASMsgDLCError_Cnt_M_u08	37
PrevISDYNAASMsgRxTime_MSec_M_u32	2668346624
PrevISDYNABRMsgDLCError_Cnt_M_u08	194
PrevISDYNABRMsgRxTime_MSec_M_u32	1475083520
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	254
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3154951424
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	87
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3245546752
PrevISDYNVOLMsgDLCError_Cnt_M_u08	85
PrevISDYNVOLMsgRxTime_MSec_M_u32	3445701888
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3282169088
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	312.869507
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	28247
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	51040
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	53484
VitesseVehicleBVRampValidCount_Cnt_M_u16	24501
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	36001

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	27314
VitesseVehicleBV_Kph_M_f32	117.7257
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	15138
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	53002
VitesseVehiculeRoues_Kph_M_f32	645.6026
k_AASNTCEnableTimeout_mS_u16	21300
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	60515
k_AASNodeTimeout_mS_u16	48736
k_ABSNodeTimeout_mS_u16	62653
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	23147
k_ANGLEVOLANTSigValidThresh_Cnt_u16	61320
k_AngleVolantInvalidThresh_Cnt_u16	34331
k_AngleVolantValidThresh_Cnt_u16	59600
k_BSI552MsgTimeout_mS_u16	27485
k_BSINTCEnableTimeout_mS_u16	9836
k_BSINodeAbsentDiag_Cnt_str.Threshold	2544
k_BSINodeAbsentDiag_Cnt_str.PStep	17063
k_BSINodeAbsentDiag_Cnt_str.NStep	13794
k_BSINodeAbsentTimeout_mS_u16	30659
k_BSINodeTimeout_mS_u16	4831
k_BattOvHi_Volt_f32	11.8183002
k_BattOvLo_Volt_f32	20.7693996
k_BattUvHi_Volt_f32	31.0132999
k_BattUvLo_Volt_f32	0.142199993
k_CAVNTCEnableTimeout_mS_u16	60414
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	54680
k_CAVNodeTimeout_mS_u16	52605
k_CMM388MsgTimeout_mS_u16	50178
k_CMM388NTCEnableTimeout_mS_u16	64430
k_CMMNTCEnableTimeout_mS_u16	18100
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	33974
k_CONSANGLECPKMax_HwDeg_f32	651.597107
k_CONSANGLECPKMin_HwDeg_f32	-62.2308998
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	61986
k_CONSANGLECPKSigValidThresh_Cnt_u16	50698
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	30046
k_CPKVehicleSpeedValidThresh_Cnt_u16	6512
k_CityParkInputInvalidThresh_Cnt_u16	32026
k_CityParkInputValidThresh_Cnt_u16	4768
k_ComputerRazGCTSigValidThresh_Cnt_u16	45370
k_CptTemporelSigValidThresh_Cnt_u16	59759
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	57532
k_DMDFCTCPKSigValidThresh_Cnt_u16	33117
k_DMDFCTCPKValidCount_Cnt_u16	13599
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	999
k_DMDRELAXECPKSigValidThresh_Cnt_u16	48447
k_DMDRelaxeConsistentThresh_Cnt_u16	5693
k_DateValidThresh_Cnt_u16	41362
k_DefaultVehSpd_Kph_f32	21.4552994
k_DiagMuxOnAbsentTimeout_mS_u16	7263
k_EMNodeTimeout_mS_u16	44058
k_ESPNTCEnableTimeout_mS_u16	21614
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	20574
k_EtatMTSigInvalidThresh_Cnt_u16	32911
k_EtatMTSigValidThresh_Cnt_u16	16200
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	31293
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	64809
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	57141
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	40293
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	12250
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	60997

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	23709
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	37690
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	38760
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	43237
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	12202
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	18715
k_ISDATDIRASentDiag_Cnt_str.Threshold	2435
k_ISDATDIRASentDiag_Cnt_str.PStep	9638
k_ISDATDIRASentDiag_Cnt_str.NStep	54621
k_ISDATDIRASentTimeout_mS_u16	52296
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	39836
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	12651
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	5226
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	4764
k_ISDYNAASChkSumValidThresh_Cnt_u16	12565
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	53271
k_ISDYNAASMsgCountValidThresh_Cnt_u16	9032
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	57840
k_ISDYNAASMsgLenValidThresh_Cnt_u16	180
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	41264
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	23186
k_ISDYNABRChkSumValidThresh_Cnt_u16	53171
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	43895
k_ISDYNABRMsgCountValidThresh_Cnt_u16	7688
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46016
k_ISDYNABRMsgLenValidThresh_Cnt_u16	3741
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	51675
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	53419
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	56262
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	58803
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	9612
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	28125
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	9000
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	63944
k_ISDYNVOLChkSumValidThresh_Cnt_u16	52269
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	36614
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	38761
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	56672
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	56301
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	31552
k_IgnOnTimeout_mS_u16	36468
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	253.186203
k_PowerCutVehSpdLowThresh_Kph_f32	11.3502998
k_PowerCutVehSpdLowTimeout_mS_u16	7696
k_VBattMaxAAS_Volt_f32	9.18109989
k_VBattMaxBSI_Volt_f32	13.7009001
k_VBattMaxCAV_Volt_f32	11.4197998
k_VBattMaxCMM388_Volt_f32	20.8985004
k_VBattMaxCMM_Volt_f32	17.3264999
k_VBattMaxESP_Volt_f32	28.9673004
k_VBattMinAAS_Volt_f32	18.3539009
k_VBattMinBSI_Volt_f32	28.9673004
k_VBattMinCAV_Volt_f32	4.0381999
k_VBattMinCMM388_Volt_f32	27.4186993
k_VBattMinCMM_Volt_f32	16.1464996
k_VBattMinESP_Volt_f32	17.3264999
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	33694
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	10098
k_VitesseVehicleBVRampValidThresh_Cnt_u16	59986
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	38536
k_VitesseVehicleBVSigValidThresh_Cnt_u16	8589
k_VitesseVehicleBVSpeedPassThresh_kph_f32	558.48938
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	59074
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	18955
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1714445568
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8524
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	87
target_SrlComInput_Per1_Batt_Volt_f32.value	26.9025002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3493694720
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	17
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0152123319
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2728787200
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	232
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	639147264
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	199
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2048605440
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	42
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	112057600
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	869301504
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1770200320
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	128
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	264617216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	45
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	134
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	183
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	190
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2971852032
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	45
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	146
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	210
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	252
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1841626368
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	186
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1857527040
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3816704
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	66
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	82
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	151
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	839847168
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3481
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.822067678
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	60630
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	32.3837013
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	51673

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	7601	7601	✔
CONSANGLECPK_HwDeg_M_f32	183.107895	183.107895 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1713429248	1713429248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1100	1100	✔
ElecIntTimer_mS_M_u32[1]	1152	1152	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	2435	2435	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	4	4	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	1713429248	1713429248	✔
IgnTimeOff_Sec_M_u32	3055494451	3055494451	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	38	38	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2728787200	2728787200	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	232	232	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	639147264	639147264	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	199	199	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2048605440	2048605440	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	42	42	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	112057600	112057600	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3305913600	3305913600	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	31	31	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1770200320	1770200320	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	128	128	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	264617216	264617216	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	51	51	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2971852032	2971852032	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	91	91	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1841626368	1841626368	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	186	186	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1857527040	1857527040	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	246	246	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3816704	3816704	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	839847168	839847168	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	312.869507	312.869507	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	117.7257	117.7257	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	645.6026	645.6026	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	7601	7601	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3055494451	3055494451	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	183.107895	183.107895 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.473 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	145816576
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	31371
AASNodeAbsentTimer_mS_M_u32	553217024
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	40939
ANGLEVOLANTSigValidCount_Cnt_M_u16	58809
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	29008
AngleVolantMsgTimer_mS_M_u32	145816576
AngleVolantValidCount_Cnt_M_u16	63278
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1501506560
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1388424192
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3635715072
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2390842368
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	31274
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4166065152
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	15051
CAVNodeAbsentTimer_mS_M_u32	263261184
CDD_SrlComVehSpd_Kph_G_f32	284.860809
CMM388NTCEnableTimer_mS_M_u32	2341948416
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	95882240
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	14225
CMMNodeAbsentTimer_mS_M_u32	4076559360
CONSANGLECPKSigInvalidCount_Cnt_M_u16	34333
CONSANGLECPKSigValidCount_Cnt_M_u16	49595
CONSANGLECPK_Cnt_M_u16	28734
CONSANGLECPK_HwDeg_M_f32	561.372375
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	28734
CPKVehicleSpeedMsgTimer_mS_M_u32	3689413632
CPKVehicleSpeedValidCount_Cnt_M_u16	23237
CityParkInputConsistentCount_Cnt_M_u16	59442

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	30369
CityParkInputMsgTimer_mS_M_u32	2728787200
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1392339968
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	45455
ComputerRazGCTSigInvalidTimer_mS_M_u32	1958054912
ComputerRazGCTSigValidCount_Cnt_M_u16	54639
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	16797
DMDFCTCPKSigValidCount_Cnt_M_u16	62227
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	42861
DMDRELAXECPKSigValidCount_Cnt_M_u16	60091
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	32226
DateInvalidTimer_mS_M_u32	1388424192
DiagMuxOnAbsentTimer_mS_M_u32	4167089152
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2390842368
ESPNTCEnableTimer_mS_M_u32	3548539904
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	30139
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	87
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	2050
ElecIntTimer_mS_M_u32[1]	6072
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1295195136
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	47028
EtatMTSigValidCount_Cnt_M_u16	34254
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	37791
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	19645
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	62233
ISDAT4V2BSI552MsgTimer_mS_M_u32	1610570752
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	19260
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	45278
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	34254
ISDATBSI3F2MsgTimer_mS_M_u32	3269377024
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	4733
ISDATBSI412MsgLenValidCount_Cnt_M_u16	5071
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	47028
ISDATBSI412MsgTimer_mS_M_u32	2301557760
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	8085
ISDATBSI432MsgLenValidCount_Cnt_M_u16	6335
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	17780
ISDATDIRASentFltAcc_Cnt_M_u16	1288
ISDATDIRASentTimer_mS_M_u32	3689413632
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	48444
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	63278
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	16732
ISDYN2CMMMsgTimer_mS_M_u32	679242752
ISDYNAASChkSumInvalidCount_Cnt_M_u16	60941
ISDYNAASChkSumValidCount_Cnt_M_u16	37371
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	44269
ISDYNAASMsgCount_Cnt_M_u08	1
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	32654
ISDYNAASMsgLenValidCount_Cnt_M_u16	28852
ISDYNAASMsgTimeValidCount_Cnt_M_u16	60941
ISDYNAASMsgTimer_mS_M_u32	59984896
ISDYNABRChkSumInvalidCount_Cnt_M_u16	61500
ISDYNABRChkSumValidCount_Cnt_M_u16	21394
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	59980
ISDYNABRMsgCountValidCount_Cnt_M_u16	36730
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	56668
ISDYNABRMsgLenValidCount_Cnt_M_u16	23098
ISDYNABRMsgTimeValidCount_Cnt_M_u16	28734
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	19611

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	10508
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	34254
ISDYNCMM208MsgTimer_mS_M_u32	1291594752
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	19611
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	10508
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	63148
ISDYNCMM388MsgTimer_mS_M_u32	2031275008
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	51355
ISDYNVOLChkSumValidCount_Cnt_M_u16	34489
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	7963
ISDYNVOLMsgCountValidCount_Cnt_M_u16	37649
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	16508
ISDYNVOLMsgLenValidCount_Cnt_M_u16	32250
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	14225
ISDYNVOLMsgTimer_mS_M_u32	4172385280
IgnOnTimer_mS_M_u32	3642149888
IgnTimeOff_Sec_M_u32	2206359365
ManVehSpd_Kph_M_f32	653.615784
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	103
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2747579392
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	59
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	4141063168
PrevISDATBSI412MsgDLCError_Cnt_M_u08	178
PrevISDATBSI412MsgRxTime_MSec_M_u32	4145679360
PrevISDATBSI432MsgDLCError_Cnt_M_u08	186
PrevISDATBSI432MsgRxTime_MSec_M_u32	3900075008
PrevISDATDIRAMsgTxTime_MSec_M_u32	4256041984
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	160
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1984093184
PrevISDYNAASMsgDLCError_Cnt_M_u08	238
PrevISDYNAASMsgRxTime_MSec_M_u32	3450833920
PrevISDYNABRMsgDLCError_Cnt_M_u08	92
PrevISDYNABRMsgRxTime_MSec_M_u32	1947126784
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	201
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3131870208
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	38
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3153685504
PrevISDYNVOLMsgDLCError_Cnt_M_u08	67
PrevISDYNVOLMsgRxTime_MSec_M_u32	2024737792
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3031235584
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	530.01178
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	4876
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	18098
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	32589
VitesseVehicleBVRampValidCount_Cnt_M_u16	4531
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	22956
VitesseVehicleBVSigValidCount_Cnt_M_u16	7738

Name	Input Value
VitesseVehicleBV_Kph_M_f32	446.284302
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	63148
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	63922
VitesseVehiculeRoues_Kph_M_f32	286.859985
k_AASNTCEnableTimeout_mS_u16	39861
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	9961
k_AASNodeTimeout_mS_u16	25010
k_ABSNodeTimeout_mS_u16	18138
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	51856
k_ANGLEVOLANTSigValidThresh_Cnt_u16	39418
k_AngleVolantInvalidThresh_Cnt_u16	57921
k_AngleVolantValidThresh_Cnt_u16	30369
k_BSI552MsgTimeout_mS_u16	12473
k_BSINTCEnableTimeout_mS_u16	43661
k_BSINodeAbsentDiag_Cnt_str.Threshold	43032
k_BSINodeAbsentDiag_Cnt_str.PStep	7476
k_BSINodeAbsentDiag_Cnt_str.NStep	29379
k_BSINodeAbsentTimeout_mS_u16	65096
k_BSINodeTimeout_mS_u16	17780
k_BattOvHi_Volt_f32	14.5422001
k_BattOvLo_Volt_f32	10.5086002
k_BattUvHi_Volt_f32	8.05580044
k_BattUvLo_Volt_f32	17.2290993
k_CAVNTCEnableTimeout_mS_u16	42263
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	8521
k_CAVNodeTimeout_mS_u16	46617
k_CMM388MsgTimeout_mS_u16	54667
k_CMM388NTCEnableTimeout_mS_u16	56967
k_CMMNTCEnableTimeout_mS_u16	4660
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	34990
k_CONSANGLECPKMax_HwDeg_f32	527.242676
k_CONSANGLECPKMin_HwDeg_f32	-552.711792
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	53676
k_CONSANGLECPKSigValidThresh_Cnt_u16	5298
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	46264
k_CPKVehicleSpeedValidThresh_Cnt_u16	56064
k_CityParkInputInvalidThresh_Cnt_u16	962
k_CityParkInputValidThresh_Cnt_u16	59442
k_ComputerRazGCTSigValidThresh_Cnt_u16	27298
k_CptTemporelSigValidThresh_Cnt_u16	45252
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	14428
k_DMDFCTCPKSigValidThresh_Cnt_u16	62778
k_DMDFCTCPKValidCount_Cnt_u16	55346
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	16732
k_DMDRELAXECPKSigValidThresh_Cnt_u16	37906
k_DMDRelaxeConsistentThresh_Cnt_u16	280
k_DateValidThresh_Cnt_u16	62233
k_DefaultVehSpd_Kph_f32	209.707504
k_DiagMuxOnAbsentTimeout_mS_u16	44084
k_EMNodeTimeout_mS_u16	52802
k_ESPNTCEnableTimeout_mS_u16	31943
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	50614
k_EtatMTSigInvalidThresh_Cnt_u16	3427
k_EtatMTSigValidThresh_Cnt_u16	53241
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	57883
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	10260
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	5747
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	4641
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	18819
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	61569
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	3066

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	63204
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	18329
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	40610
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	14612
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	50433
k_ISDATDIRASentDiag_Cnt_str.Threshold	50189
k_ISDATDIRASentDiag_Cnt_str.PStep	7148
k_ISDATDIRASentDiag_Cnt_str.NStep	24623
k_ISDATDIRASentTimeout_mS_u16	20024
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	4478
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	29008
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	11475
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	52028
k_ISDYNAASChkSumValidThresh_Cnt_u16	28306
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	17740
k_ISDYNAASMsgCountValidThresh_Cnt_u16	10874
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	44352
k_ISDYNAASMsgLenValidThresh_Cnt_u16	60086
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	9474
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	41690
k_ISDYNABRChkSumValidThresh_Cnt_u16	57912
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	54570
k_ISDYNABRMsgCountValidThresh_Cnt_u16	56376
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	21137
k_ISDYNABRMsgLenValidThresh_Cnt_u16	53435
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	58559
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	15376
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	27646
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	63417
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	64235
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	32953
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	10137
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	39416
k_ISDYNVOLChkSumValidThresh_Cnt_u16	53642
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	13184
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	35734
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	42672
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	63946
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	40463
k_IgnOnTimeout_mS_u16	35828
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	111.014603
k_PowerCutVehSpdLowThresh_Kph_f32	108.5224
k_PowerCutVehSpdLowTimeout_mS_u16	43809
k_VBattMaxAAS_Volt_f32	30.7318993
k_VBattMaxBSI_Volt_f32	14.1429996
k_VBattMaxCAV_Volt_f32	28.6240997
k_VBattMaxCMM388_Volt_f32	26.0337009
k_VBattMaxCMM_Volt_f32	8.48709965
k_VBattMaxESP_Volt_f32	2.92309999
k_VBattMinAAS_Volt_f32	27.8022003
k_VBattMinBSI_Volt_f32	2.92309999
k_VBattMinCAV_Volt_f32	19.6702003
k_VBattMinCMM388_Volt_f32	20.7495995
k_VBattMinCMM_Volt_f32	28.3658009
k_VBattMinESP_Volt_f32	8.48709965
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	57720
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	25786
k_VitesseVehicleBVRampValidThresh_Cnt_u16	64027
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	8633
k_VitesseVehicleBVSigValidThresh_Cnt_u16	44907
k_VitesseVehicleBVSpeedPassThresh_kph_f32	186.058899
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	5579
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	10929
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1388424192
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	33485
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	38
target_SrlComInput_Per1_Batt_Volt_f32.value	9.42669964
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	89791488
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	145
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.251980603
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4225813504
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	170
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	67693568
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3665890304
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1195977728
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	308366336
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	63532032
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	225
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3816918016
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	25
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	63
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	167
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	250
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1542073344
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	48
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	218
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	29
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3598961664
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1714154496
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2216954880
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	43
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	204
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	98933760
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2570
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.316091031
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	877008
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	195.672104

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	34950		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	29010	29010	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1501506560	1501506560	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	1388424192	1388424192	✔
BSI412NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2390842368	2390842368	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	14225	14225	✔
CMMNodeAbsentTimer_mS_M_u32	63532032	63532032	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	28734	28734	✔
CONSANGLECPK_HwDeg_M_f32	561.372375	561.372375 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	28734	28734	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3689413632	3689413632	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	23237	23237	✔
CityParkInputConsistentCount_Cnt_M_u16	59442	59442	✔
CityParkInputInvalidCount_Cnt_M_u16	30369	30369	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1392339968	1392339968	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1958054912	1958054912	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2390842368	2390842368	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	87	87	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	1713429248	1713429248	✔
ElecIntTimer_mS_M_u32[1]	6072	6072	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	37792	37792	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4225813504	4225813504	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	19260	19260	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3269377024	3269377024	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	4733	4733	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3665890304	3665890304	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	50189	50189	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	1	1	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	3642149888	3642149888	✔
IgnTimeOff_Sec_M_u32	2206359365	2206359365	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	126	126	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4225813504	4225813504	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	170	170	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	67693568	67693568	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	192	192	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3665890304	3665890304	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	137	137	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1195977728	1195977728	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4256041984	4256041984	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	81	81	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	63532032	63532032	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	225	225	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3816918016	3816918016	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	132	132	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1542073344	1542073344	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	29	29	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3598961664	3598961664	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	113	113	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1714154496	1714154496	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	110	110	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2216954880	2216954880	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	98933760	98933760	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	530.01178	530.01178	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	446.284302	446.284302	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	286.859985	286.859985	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	28734	28734	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2206359365	2206359365	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	561.372375	561.372375 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	209.707504	209.707504	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	5	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	10	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	10	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.474 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3997900544
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	23131
AASNodeAbsentTimer_mS_M_u32	1722666752
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	33114
ANGLEVOLANTSigValidCount_Cnt_M_u16	51084
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	40268
AngleVolantMsgTimer_mS_M_u32	3997900544
AngleVolantValidCount_Cnt_M_u16	18170
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3540815616
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	3001356032
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	4159192832
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2956066560
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	1117
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1194508032
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	10820
CAVNodeAbsentTimer_mS_M_u32	1496248064
CDD_SrlComVehSpd_Kph_G_f32	165.5215
CMM388NTCEnableTimer_mS_M_u32	311176960
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3969707776
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	6430
CMMNodeAbsentTimer_mS_M_u32	2906914560
CONSANGLECPKSigInvalidCount_Cnt_M_u16	63412
CONSANGLECPKSigValidCount_Cnt_M_u16	12407
CONSANGLECPK_Cnt_M_u16	49070

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CONSANGLECPK_HwDeg_M_f32	-82.5762024
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	49070
CPKVehicleSpeedMsgTimer_mS_M_u32	3563462400
CPKVehicleSpeedValidCount_Cnt_M_u16	11432
CityParkInputConsistentCount_Cnt_M_u16	44270
CityParkInputInvalidCount_Cnt_M_u16	48880
CityParkInputMsgTimer_mS_M_u32	2410306560
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1235341056
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	28239
ComputerRazGCTSigInvalidTimer_mS_M_u32	1648455424
ComputerRazGCTSigValidCount_Cnt_M_u16	47735
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	9468
DMDFCTCPKSigValidCount_Cnt_M_u16	49718
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	18260
DMDRELAXECPKSigValidCount_Cnt_M_u16	62726
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	30629
DateInvalidTimer_mS_M_u32	3001356032
DiagMuxOnAbsentTimer_mS_M_u32	2880167680
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	2956066560
ESPNTCEnableTimer_mS_M_u32	3746746112
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	54588
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	579
EffacDefaultDiagTimer_mS_M_u32[1]	990
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	5
ElecIntTimer_mS_M_u32[1]	57
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3171729152
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	23300
EtatMTSigValidCount_Cnt_M_u16	33618
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	11182
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	19441
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	47012
ISDAT4V2BSI552MsgTimer_mS_M_u32	2671247104
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	61891
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	9593
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	33618
ISDATBSI3F2MsgTimer_mS_M_u32	4021411584
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	60306
ISDATBSI412MsgLenValidCount_Cnt_M_u16	55352
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	23300
ISDATBSI412MsgTimer_mS_M_u32	2421235456
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	23058
ISDATBSI432MsgLenValidCount_Cnt_M_u16	42288
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	25225
ISDATDIRASentFltAcc_Cnt_M_u16	57549
ISDATDIRASentTimer_mS_M_u32	3563462400
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	7220
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	18170
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	38783
ISDYN2CMMMsgTimer_mS_M_u32	719638272
ISDYNAASChkSumInvalidCount_Cnt_M_u16	56405
ISDYNAASChkSumValidCount_Cnt_M_u16	20519
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	6013
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	1723
ISDYNAASMsgLenValidCount_Cnt_M_u16	28901
ISDYNAASMsgTimeValidCount_Cnt_M_u16	56405
ISDYNAASMsgTimer_mS_M_u32	2979540736
ISDYNABRChkSumInvalidCount_Cnt_M_u16	33728
ISDYNABRChkSumValidCount_Cnt_M_u16	50011
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	31064

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNABRMsgCountValidCount_Cnt_M_u16	47466
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	17335
ISDYNABRMsgLenValidCount_Cnt_M_u16	35002
ISDYNABRMsgTimeValidCount_Cnt_M_u16	49070
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	34458
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	31022
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	33618
ISDYNCMM208MsgTimer_mS_M_u32	3721760512
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	34458
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	31022
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	11264
ISDYNCMM388MsgTimer_mS_M_u32	2985930496
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	54202
ISDYNVOLChkSumValidCount_Cnt_M_u16	9469
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	61442
ISDYNVOLMsgCountValidCount_Cnt_M_u16	58812
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	41785
ISDYNVOLMsgLenValidCount_Cnt_M_u16	36443
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	6430
ISDYNVOLMsgTimer_mS_M_u32	3712839424
IgnOnTimer_mS_M_u32	2330832640
IgnTimeOff_Sec_M_u32	1059447798
ManVehSpd_Kph_M_f32	75.1334
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	104
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	186
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3128942336
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	54
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3880468224
PrevISDATBSI412MsgDLCError_Cnt_M_u08	59
PrevISDATBSI412MsgRxTime_MSec_M_u32	2872307456
PrevISDATBSI432MsgDLCError_Cnt_M_u08	33
PrevISDATBSI432MsgRxTime_MSec_M_u32	4118204160
PrevISDATDIRAMsgTxTime_MSec_M_u32	343404288
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	241
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1716354816
PrevISDYNAASMsgDLCError_Cnt_M_u08	94
PrevISDYNAASMsgRxTime_MSec_M_u32	2714988288
PrevISDYNABRMsgDLCError_Cnt_M_u08	204
PrevISDYNABRMsgRxTime_MSec_M_u32	2282073856
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	14
PrevISDYNCMM208MsgRxTime_MSec_M_u32	538734336
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	77
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1437454080
PrevISDYNVOLMsgDLCError_Cnt_M_u08	122
PrevISDYNVOLMsgRxTime_MSec_M_u32	1639247616
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4049018624
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	523.861511
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	12225
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	29291
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1

Name	Input Value
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	31038
VitesseVehicleBVRampValidCount_Cnt_M_u16	53160
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	16983
VitesseVehicleBVSigValidCount_Cnt_M_u16	15433
VitesseVehicleBV_Kph_M_f32	217.251205
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	11264
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	6282
VitesseVehiculeRoues_Kph_M_f32	248.376404
k_AASNTCEnableTimeout_mS_u16	11529
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	12425
k_AASNodeTimeout_mS_u16	57707
k_ABSNodeTimeout_mS_u16	60037
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	8673
k_ANGLEVOLANTSigValidThresh_Cnt_u16	64063
k_AngleVolantInvalidThresh_Cnt_u16	42282
k_AngleVolantValidThresh_Cnt_u16	48880
k_BSI552MsgTimeout_mS_u16	10037
k_BSINTCEnableTimeout_mS_u16	34602
k_BSINodeAbsentDiag_Cnt_str.Threshold	40733
k_BSINodeAbsentDiag_Cnt_str.PStep	14806
k_BSINodeAbsentDiag_Cnt_str.NStep	6466
k_BSINodeAbsentTimeout_mS_u16	17508
k_BSINodeTimeout_mS_u16	25225
k_BattOvHi_Volt_f32	6.21140003
k_BattOvLo_Volt_f32	13.5099001
k_BattUvHi_Volt_f32	22.8500004
k_BattUvLo_Volt_f32	21.3057995
k_CAVNTCEnableTimeout_mS_u16	58638
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	6730
k_CAVNodeTimeout_mS_u16	28352
k_CMM388MsgTimeout_mS_u16	2395
k_CMM388NTCEnableTimeout_mS_u16	13671
k_CMMNTCEnableTimeout_mS_u16	27355
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	12950
k_CONSANGLECPKMax_HwDeg_f32	607.947083
k_CONSANGLECPKMin_HwDeg_f32	-591.318604
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	23296
k_CONSANGLECPKSigValidThresh_Cnt_u16	34698
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	40409
k_CPKVehicleSpeedValidThresh_Cnt_u16	44233
k_CityParkInputInvalidThresh_Cnt_u16	7854
k_CityParkInputValidThresh_Cnt_u16	44270
k_ComputerRazGCTSigValidThresh_Cnt_u16	41233
k_CptTemporelSigValidThresh_Cnt_u16	21319
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	62135
k_DMDFCTCPKSigValidThresh_Cnt_u16	30650
k_DMDFCTCPKValidCount_Cnt_u16	23621
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	38783
k_DMDRELAXECPKSigValidThresh_Cnt_u16	8441
k_DMDRelaxeConsistentThresh_Cnt_u16	3943
k_DateValidThresh_Cnt_u16	47012
k_DefaultVehSpd_Kph_f32	76.0263977
k_DiagMuxOnAbsentTimeout_mS_u16	7500
k_EMNodeTimeout_mS_u16	56965
k_ESPNTCEnableTimeout_mS_u16	60240
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	44414
k_EtatMTSigInvalidThresh_Cnt_u16	10251
k_EtatMTSigValidThresh_Cnt_u16	39398
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	43120

Name	Input Value
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	41247
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	12395
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	35924
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	15050
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	51846
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	58403
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	18945
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	56070
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	1410
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	11976
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	27797
k_ISDATDIRASentDiag_Cnt_str.Threshold	13378
k_ISDATDIRASentDiag_Cnt_str.PStep	37990
k_ISDATDIRASentDiag_Cnt_str.NStep	48989
k_ISDATDIRASentTimeout_mS_u16	61644
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	44126
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	40268
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	50732
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	45760
k_ISDYNAASChkSumValidThresh_Cnt_u16	12891
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	10328
k_ISDYNAASMsgCountValidThresh_Cnt_u16	43114
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	34228
k_ISDYNAASMsgLenValidThresh_Cnt_u16	32607
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	2855
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	22205
k_ISDYNABRChkSumValidThresh_Cnt_u16	62528
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	45917
k_ISDYNABRMsgCountValidThresh_Cnt_u16	34255
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	34846
k_ISDYNABRMsgLenValidThresh_Cnt_u16	33852
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	32762
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	60853
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	15695
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	37654
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	12378
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	46732
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	64008
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	15841
k_ISDYNVOLChkSumValidThresh_Cnt_u16	38855
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	33581
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	5199
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	21776
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	11870
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	34882
k_IgnOnTimeout_mS_u16	61165
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	170.5112
k_PowerCutVehSpdLowThresh_Kph_f32	14.4877996
k_PowerCutVehSpdLowTimeout_mS_u16	453
k_VBattMaxAAS_Volt_f32	24.4354
k_VBattMaxBSI_Volt_f32	31.4895992
k_VBattMaxCAV_Volt_f32	26.2689991
k_VBattMaxCMM388_Volt_f32	23.0389004
k_VBattMaxCMM_Volt_f32	24.8232994
k_VBattMaxESP_Volt_f32	1.44760001
k_VBattMinAAS_Volt_f32	0.947399974
k_VBattMinBSI_Volt_f32	1.44760001
k_VBattMinCAV_Volt_f32	13.7642002
k_VBattMinCMM388_Volt_f32	5.45429993
k_VBattMinCMM_Volt_f32	10.7695999
k_VBattMinESP_Volt_f32	24.8232994
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	18160
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	18886
k_VitesseVehicleBVRampValidThresh_Cnt_u16	7938
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	5117
k_VitesseVehicleBVSigValidThresh_Cnt_u16	45955
k_VitesseVehicleBVSpeedPassThresh_kph_f32	586.312927
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	22852
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	51246
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3001356032
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	13090
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	77
target_SrlComInput_Per1_Batt_Volt_f32.value	28.3244991
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1347927808
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	170
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.95991385
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	23
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1091546880
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	19
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1650413312
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	213839616
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	81
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3895365376
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2628660992
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3527266048
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	819818240
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	58
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	129
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	164
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	171
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	240
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2425065216
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	128
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	174
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	176
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	196
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	221
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	333885184
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	146
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2125876992
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	237
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	848686848
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	132
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	166
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	186
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1519730432
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	524
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.543216407
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	483388
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	69.9918976
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	14803

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	40270	40270	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	49070	49070	✔
CONSANGLECPK_HwDeg_M_f32	-82.5762024	-82.5762024 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	49070	49070	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3563462400	3563462400	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	11432	11432	✔
CityParkInputConsistentCount_Cnt_M_u16	44270	44270	✔
CityParkInputInvalidCount_Cnt_M_u16	48880	48880	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1713429248	1713429248	✔
EffacDefaultDiagTimer_mS_M_u32[1]	990	990	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1713429248	1713429248	✔
ElecIntTimer_mS_M_u32[1]	57	57	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	13378	13378	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
IgnOnTimer_mS_M_u32	2330832640	2330832640	✔
IgnTimeOff_Sec_M_u32	1059447798	1059447798	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	23	23	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1091546880	1091546880	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	19	19	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1650413312	1650413312	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	67	67	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	213839616	213839616	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	81	81	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3895365376	3895365376	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	343404288	343404288	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3527266048	3527266048	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	57	57	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	819818240	819818240	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	117	117	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2425065216	2425065216	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	45	45	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	333885184	333885184	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	146	146	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2125876992	2125876992	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	237	237	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	848686848	848686848	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1519730432	1519730432	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	523.861511	523.861511	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	217.251205	217.251205	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	248.376404	248.376404	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	49070	49070	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1059447798	1059447798	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-82.5762024	-82.5762024 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	76.0263977	76.0263977	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.475 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2415486464
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	11719
AASNodeAbsentTimer_mS_M_u32	1301370368
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	53964
ANGLEVOLANTSigValidCount_Cnt_M_u16	50421
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	26868
AngleVolantMsgTimer_mS_M_u32	2415486464
AngleVolantValidCount_Cnt_M_u16	43628
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	4084536832
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1441502720
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3483502080
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	4257531392
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	5571
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	734168576
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	19084
CAVNodeAbsentTimer_mS_M_u32	1653470720
CDD_SrlComVehSpd_Kph_G_f32	529.234802
CMM388NTCEnableTimer_mS_M_u32	997602816
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3762550272
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	61376
CMMNodeAbsentTimer_mS_M_u32	3465463296
CONSANGLECPKSigInvalidCount_Cnt_M_u16	19132
CONSANGLECPKSigValidCount_Cnt_M_u16	42293
CONSANGLECPK_Cnt_M_u16	37776
CONSANGLECPK_HwDeg_M_f32	-121.591003
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37776
CPKVehicleSpeedMsgTimer_mS_M_u32	162031104
CPKVehicleSpeedValidCount_Cnt_M_u16	19111

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	18576
CityParkInputInvalidCount_Cnt_M_u16	60297
CityParkInputMsgTimer_mS_M_u32	1091546880
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1958041088
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	49643
ComputerRazGCTSigInvalidTimer_mS_M_u32	2975233536
ComputerRazGCTSigValidCount_Cnt_M_u16	33781
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	59749
DMDFCTCPKSigValidCount_Cnt_M_u16	63094
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	59614
DMDRELAXECPKSigValidCount_Cnt_M_u16	42119
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	52969
DateInvalidTimer_mS_M_u32	1441502720
DiagMuxOnAbsentTimer_mS_M_u32	3403097600
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4257531392
ESPNTCEnableTimer_mS_M_u32	3080869376
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	12325
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	101
EffacDefaultDiagTimer_mS_M_u32[1]	105
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	979
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2989786624
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	37645
EtatMTSigValidCount_Cnt_M_u16	20194
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	5838
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	47815
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	20012
ISDAT4V2BSI552MsgTimer_mS_M_u32	3367159296
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	57936
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	7150
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	20194
ISDATBSI3F2MsgTimer_mS_M_u32	2529502720
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	16867
ISDATBSI412MsgLenValidCount_Cnt_M_u16	4272
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	37645
ISDATBSI412MsgTimer_mS_M_u32	1105683968
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	64740
ISDATBSI432MsgLenValidCount_Cnt_M_u16	36937
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	62909
ISDATDIRASentFltAcc_Cnt_M_u16	35569
ISDATDIRASentTimer_mS_M_u32	162031104
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	5630
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	43628
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	24028
ISDYN2CMMMsgTimer_mS_M_u32	2632734208
ISDYNAASChkSumInvalidCount_Cnt_M_u16	4057
ISDYNAASChkSumValidCount_Cnt_M_u16	63779
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	1251
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	20775
ISDYNAASMsgLenValidCount_Cnt_M_u16	46952
ISDYNAASMsgTimeValidCount_Cnt_M_u16	4057
ISDYNAASMsgTimer_mS_M_u32	2387752448
ISDYNABRChkSumInvalidCount_Cnt_M_u16	32535
ISDYNABRChkSumValidCount_Cnt_M_u16	9481
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	1232
ISDYNABRMsgCountValidCount_Cnt_M_u16	35162
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	12979
ISDYNABRMsgLenValidCount_Cnt_M_u16	26732
ISDYNABRMsgTimeValidCount_Cnt_M_u16	37776

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	47302
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	47819
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	20194
ISDYNCMM208MsgTimer_mS_M_u32	924456448
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	47302
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	47819
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	37722
ISDYNCMM388MsgTimer_mS_M_u32	4079859200
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	20138
ISDYNVOLChkSumValidCount_Cnt_M_u16	24483
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	8275
ISDYNVOLMsgCountValidCount_Cnt_M_u16	9188
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	64046
ISDYNVOLMsgLenValidCount_Cnt_M_u16	48520
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	61376
ISDYNVOLMsgTimer_mS_M_u32	1882355200
IgnOnTimer_mS_M_u32	944879104
IgnTimeOff_Sec_M_u32	2611568680
ManVehSpd_Kph_M_f32	530.556213
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	105
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	60
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3998950912
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	81
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1299777024
PrevISDATBSI412MsgDLCError_Cnt_M_u08	215
PrevISDATBSI412MsgRxTime_MSec_M_u32	3229545984
PrevISDATBSI432MsgDLCError_Cnt_M_u08	248
PrevISDATBSI432MsgRxTime_MSec_M_u32	87447040
PrevISDATDIRAMsgTxTime_MSec_M_u32	2494756352
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	184
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2842838528
PrevISDYNAASMsgDLCError_Cnt_M_u08	225
PrevISDYNAASMsgRxTime_MSec_M_u32	3131078144
PrevISDYNABRMsgDLCError_Cnt_M_u08	59
PrevISDYNABRMsgRxTime_MSec_M_u32	2701768192
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	150
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2747627008
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	110
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2157008384
PrevISDYNVOLMsgDLCError_Cnt_M_u08	127
PrevISDYNVOLMsgRxTime_MSec_M_u32	3774608896
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3067438592
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	566.916077
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	28181
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	19158
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	50590
VitesseVehicleBVRampValidCount_Cnt_M_u16	26399
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	50133

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	39614
VitesseVehicleBV_Kph_M_f32	550.949707
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	37722
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	62075
VitesseVehiculeRoues_Kph_M_f32	394.760315
k_AASNTCEnableTimeout_mS_u16	30591
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	59839
k_AASNodeTimeout_mS_u16	64982
k_ABSNodeTimeout_mS_u16	64714
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	41335
k_ANGLEVOLANTSigValidThresh_Cnt_u16	36124
k_AngleVolantInvalidThresh_Cnt_u16	63579
k_AngleVolantValidThresh_Cnt_u16	60297
k_BSI552MsgTimeout_mS_u16	12922
k_BSINTCEnableTimeout_mS_u16	54684
k_BSINodeAbsentDiag_Cnt_str.Threshold	37565
k_BSINodeAbsentDiag_Cnt_str.PStep	6355
k_BSINodeAbsentDiag_Cnt_str.NStep	41166
k_BSINodeAbsentTimeout_mS_u16	54188
k_BSINodeTimeout_mS_u16	62909
k_BattOvHi_Volt_f32	20.8616009
k_BattOvLo_Volt_f32	31.5
k_BattUvHi_Volt_f32	12.3958998
k_BattUvLo_Volt_f32	27.7877007
k_CAVNTCEnableTimeout_mS_u16	28975
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	4730
k_CAVNodeTimeout_mS_u16	5528
k_CMM388MsgTimeout_mS_u16	8391
k_CMM388NTCEnableTimeout_mS_u16	52387
k_CMMNTCEnableTimeout_mS_u16	55048
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	54359
k_CONSANGLECPKMax_HwDeg_f32	253.297104
k_CONSANGLECPKMin_HwDeg_f32	-621.164673
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	1626
k_CONSANGLECPKSigValidThresh_Cnt_u16	42363
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	140
k_CPKVehicleSpeedValidThresh_Cnt_u16	39486
k_CityParkInputInvalidThresh_Cnt_u16	58957
k_CityParkInputValidThresh_Cnt_u16	18576
k_ComputerRazGCTSigValidThresh_Cnt_u16	35942
k_CptTemporelSigValidThresh_Cnt_u16	19076
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	9651
k_DMDFCTCPKSigValidThresh_Cnt_u16	39788
k_DMDFCTCPKValidCount_Cnt_u16	44555
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	24028
k_DMDRELAXECPKSigValidThresh_Cnt_u16	42541
k_DMDRelaxeConsistentThresh_Cnt_u16	4835
k_DateValidThresh_Cnt_u16	20012
k_DefaultVehSpd_Kph_f32	109.275497
k_DiagMuxOnAbsentTimeout_mS_u16	29366
k_EMNodeTimeout_mS_u16	6729
k_ESPNTCEnableTimeout_mS_u16	14184
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	927
k_EtatMTSigInvalidThresh_Cnt_u16	32310
k_EtatMTSigValidThresh_Cnt_u16	36200
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	64711
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	51069
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	61977
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	38557
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	24571
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	29959

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	58033
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	9686
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	18952
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	4628
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	43778
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	56281
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	26611
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	32894
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	26868
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	5844
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	61975
k_ISDYNAASChkSumValidThresh_Cnt_u16	55305
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	63440
k_ISDYNAASMsgCountValidThresh_Cnt_u16	48218
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	18747
k_ISDYNAASMsgLenValidThresh_Cnt_u16	62458
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	64100
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	37281
k_ISDYNABRChkSumValidThresh_Cnt_u16	48602
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	2243
k_ISDYNABRMsgCountValidThresh_Cnt_u16	22060
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	41664
k_ISDYNABRMsgLenValidThresh_Cnt_u16	8997
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	54187
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	1081
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	32940
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	21717
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	50636
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	63477
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	39489
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	18166
k_ISDYNVOLChkSumValidThresh_Cnt_u16	52739
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	10834
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	557
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	54505
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	32190
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	54354
k_IgnOnTimeout_mS_u16	25554
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	234.320908
k_PowerCutVehSpdLowThresh_Kph_f32	38.391201
k_PowerCutVehSpdLowTimeout_mS_u16	59723
k_VBattMaxAAS_Volt_f32	28.1886997
k_VBattMaxBSI_Volt_f32	0.387499988
k_VBattMaxCAV_Volt_f32	20.8509007
k_VBattMaxCMM388_Volt_f32	19.7777004
k_VBattMaxCMM_Volt_f32	21.9978008
k_VBattMaxESP_Volt_f32	16.0377007
k_VBattMinAAS_Volt_f32	4.3901
k_VBattMinBSI_Volt_f32	16.0377007
k_VBattMinCAV_Volt_f32	23.9151993
k_VBattMinCMM388_Volt_f32	17.4561005
k_VBattMinCMM_Volt_f32	27.6462002
k_VBattMinESP_Volt_f32	21.9978008
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	30920
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	50437
k_VitesseVehicleBVRampValidThresh_Cnt_u16	37715
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	37539
k_VitesseVehicleBVSigValidThresh_Cnt_u16	51409
k_VitesseVehicleBVSpeedPassThresh_kph_f32	346.873199
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	48524
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	5517
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1441502720
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	54592
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1236548
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	110
target_SrlComInput_Per1_Batt_Volt_f32.value	4.07089996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3830679040
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	65
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.194125488
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	143
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	501986816
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	8181248
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	151
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2279470592
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	19
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3155105280
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2769303040
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1256281600
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	207
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3045225984
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	43
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	101
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	208
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1995970048
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	81
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	161
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	163
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	105
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3244733952
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	96
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3346519552
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	183
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	844690944
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	79
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	93
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	175
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2610628096
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3979
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.927481115
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	644414
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	152.128799
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	6111

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1236548	1236548	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	26870	26870	✔
AngleVolantMsgTimer_mS_M_u32	1236548	1236548	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1236548	1236548	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	37776	37776	✔
CONSANGLECPK_HwDeg_M_f32	-121.591003	-121.591003 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37776	37776	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	162031104	162031104	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	19111	19111	✔
CityParkInputConsistentCount_Cnt_M_u16	18576	18576	✔
CityParkInputInvalidCount_Cnt_M_u16	60297	60297	✔
CityParkInputMsgTimer_mS_M_u32	1236548	1236548	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1236548	1236548	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1236548	1236548	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1236548	1236548	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1236548	1236548	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1236548	1236548	✔
ESPNTCEnableTimer_mS_M_u32	1236548	1236548	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	101	101	✔
EffacDefaultDiagTimer_mS_M_u32[1]	105	105	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	1236548	1236548	✔
ElecIntTimer_mS_M_u32[1]	979	979	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1236548	1236548	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATDIRASentFltAcc_Cnt_M_u16	41895	41895	✔
ISDATDIRASentTimer_mS_M_u32	1236548	1236548	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1236548	1236548	✔
IgnOnTimer_mS_M_u32	1236548	1236548	✔
IgnTimeOff_Sec_M_u32	2611568680	2611568680	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	143	143	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	501986816	501986816	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	195	195	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	8181248	8181248	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	151	151	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2279470592	2279470592	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	19	19	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3155105280	3155105280	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2494756352	2494756352	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	39	39	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1256281600	1256281600	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	207	207	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3045225984	3045225984	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	91	91	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1995970048	1995970048	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	105	105	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3244733952	3244733952	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	96	96	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3346519552	3346519552	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	183	183	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	844690944	844690944	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2610628096	2610628096	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	566.916077	566.916077	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	550.949707	550.949707	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	394.760315	394.760315	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	37776	37776	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2611568680	2611568680	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-121.591003	-121.591003 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.476 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3649611008
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	28805
AASNodeAbsentTimer_mS_M_u32	4178564352
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	26431
ANGLEVOLANTSigValidCount_Cnt_M_u16	48810
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	18638
AngleVolantMsgTimer_mS_M_u32	3649611008
AngleVolantValidCount_Cnt_M_u16	33594
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	752915712
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	946148608
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1761133824
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3036448000
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	41674
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3223274752
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	20065
CAVNodeAbsentTimer_mS_M_u32	2579756288
CDD_SrlComVehSpd_Kph_G_f32	552.6698
CMM388NTCEnableTimer_mS_M_u32	4199494912
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2114057472
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	40977
CMMNodeAbsentTimer_mS_M_u32	1295942912
CONSANGLECPKSigInvalidCount_Cnt_M_u16	10668
CONSANGLECPKSigValidCount_Cnt_M_u16	48423
CONSANGLECPK_Cnt_M_u16	6342
CONSANGLECPK_HwDeg_M_f32	-407.966614
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	6342
CPKVehicleSpeedMsgTimer_mS_M_u32	2221647104
CPKVehicleSpeedValidCount_Cnt_M_u16	34211
CityParkInputConsistentCount_Cnt_M_u16	14094
CityParkInputInvalidCount_Cnt_M_u16	40311
CityParkInputMsgTimer_mS_M_u32	3482671616
CityParkInputValidCount_Cnt_M_u16	6

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2716062976
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	41561
ComputerRazGCTSigInvalidTimer_mS_M_u32	3144840448
ComputerRazGCTSigValidCount_Cnt_M_u16	14895
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	54691
DMDFCTCPKSigValidCount_Cnt_M_u16	49877
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56361
DMDRELAXECPKSigValidCount_Cnt_M_u16	61204
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	46837
DateInvalidTimer_mS_M_u32	946148608
DiagMuxOnAbsentTimer_mS_M_u32	738944256
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3036448000
ESPNTCEnableTimer_mS_M_u32	518837504
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	25735
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	707
EffacDefaultDiagTimer_mS_M_u32[1]	1235
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	979
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	166282496
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	18109
EtatMTSigValidCount_Cnt_M_u16	40932
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	56470
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	43921
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	47379
ISDAT4V2BSI552MsgTimer_mS_M_u32	2903672064
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	32073
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	4504
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	40932
ISDATBSI3F2MsgTimer_mS_M_u32	824272128
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	21110
ISDATBSI412MsgLenValidCount_Cnt_M_u16	2613
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	18109
ISDATBSI412MsgTimer_mS_M_u32	2359207168
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	63205
ISDATBSI432MsgLenValidCount_Cnt_M_u16	62043
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	8926
ISDATDIRASentFltAcc_Cnt_M_u16	37506
ISDATDIRASentTimer_mS_M_u32	2221647104
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	57948
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	33594
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	5294
ISDYN2CMMMsgTimer_mS_M_u32	1101976832
ISDYNAASChkSumInvalidCount_Cnt_M_u16	16751
ISDYNAASChkSumValidCount_Cnt_M_u16	34169
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	28741
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	42304
ISDYNAASMsgLenValidCount_Cnt_M_u16	43490
ISDYNAASMsgTimeValidCount_Cnt_M_u16	16751
ISDYNAASMsgTimer_mS_M_u32	2205889792
ISDYNABRChkSumInvalidCount_Cnt_M_u16	61235
ISDYNABRChkSumValidCount_Cnt_M_u16	16326
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	34554
ISDYNABRMsgCountValidCount_Cnt_M_u16	27972
ISDYNABRMsgCount_Cnt_M_u08	13
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	50743
ISDYNABRMsgLenValidCount_Cnt_M_u16	15346
ISDYNABRMsgTimeValidCount_Cnt_M_u16	6342
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	57651
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	40932
ISDYNCMM208MsgTimer_mS_M_u32	1531024640

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	57651
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	336
ISDYNCMM388MsgTimer_mS_M_u32	2904601856
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	1730
ISDYNVOLChkSumValidCount_Cnt_M_u16	24253
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	18873
ISDYNVOLMsgCountValidCount_Cnt_M_u16	15211
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	53756
ISDYNVOLMsgLenValidCount_Cnt_M_u16	22743
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	40977
ISDYNVOLMsgTimer_mS_M_u32	3231610112
IgnOnTimer_mS_M_u32	3690247424
IgnTimeOff_Sec_M_u32	2736607532
ManVehSpd_Kph_M_f32	577.058105
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	106
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	187
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3317654784
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	4
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1105446144
PrevISDATBSI412MsgDLCError_Cnt_M_u08	30
PrevISDATBSI412MsgRxTime_MSec_M_u32	3254842624
PrevISDATBSI432MsgDLCError_Cnt_M_u08	10
PrevISDATBSI432MsgRxTime_MSec_M_u32	191943936
PrevISDATDIRAMsgTxTime_MSec_M_u32	1688532224
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	107
PrevISDYN2CMMMsgRxTime_MSec_M_u32	223085824
PrevISDYNAASMsgDLCError_Cnt_M_u08	158
PrevISDYNAASMsgRxTime_MSec_M_u32	2989782272
PrevISDYNABRMsgDLCError_Cnt_M_u08	132
PrevISDYNABRMsgRxTime_MSec_M_u32	3578574080
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	151
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3356849408
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	114
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2416956672
PrevISDYNVOLMsgDLCError_Cnt_M_u08	217
PrevISDYNVOLMsgRxTime_MSec_M_u32	794424576
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	649372928
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	56.7342987
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	51030
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	20600
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	58443
VitesseVehicleBVRampValidCount_Cnt_M_u16	43821
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	53172
VitesseVehicleBVSigValidCount_Cnt_M_u16	1247
VitesseVehicleBV_Kph_M_f32	211.312607
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	336
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	18771

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	280.945313
k_AASNTCEnableTimeout_mS_u16	59625
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	25457
k_AASNodeTimeout_mS_u16	26488
k_ABSNodeTimeout_mS_u16	53444
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	47964
k_ANGLEVOLANTSigValidThresh_Cnt_u16	61970
k_AngleVolantInvalidThresh_Cnt_u16	37189
k_AngleVolantValidThresh_Cnt_u16	40311
k_BSI552MsgTimeout_mS_u16	63046
k_BSINTCEnableTimeout_mS_u16	41021
k_BSINodeAbsentDiag_Cnt_str.Threshold	13537
k_BSINodeAbsentDiag_Cnt_str.PStep	61147
k_BSINodeAbsentDiag_Cnt_str.NStep	49162
k_BSINodeAbsentTimeout_mS_u16	23590
k_BSINodeTimeout_mS_u16	8926
k_BattOvHi_Volt_f32	6.66909981
k_BattOvLo_Volt_f32	30.8794003
k_BattUvHi_Volt_f32	29.3295994
k_BattUvLo_Volt_f32	19.1012001
k_CAVNTCEnableTimeout_mS_u16	47333
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	8055
k_CAVNodeTimeout_mS_u16	51928
k_CMM388MsgTimeout_mS_u16	51077
k_CMM388NTCEnableTimeout_mS_u16	54705
k_CMMNTCEnableTimeout_mS_u16	37537
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	5503
k_CONSANGLECPKMax_HwDeg_f32	395.7453
k_CONSANGLECPKMin_HwDeg_f32	-308.620514
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	55376
k_CONSANGLECPKSigValidThresh_Cnt_u16	24659
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	3254
k_CPKVehicleSpeedValidThresh_Cnt_u16	4117
k_CityParkInputInvalidThresh_Cnt_u16	12017
k_CityParkInputValidThresh_Cnt_u16	14094
k_ComputerRazGCTSigValidThresh_Cnt_u16	49767
k_CptTemporelSigValidThresh_Cnt_u16	37174
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	7479
k_DMDFCTCPKSigValidThresh_Cnt_u16	54002
k_DMDFCTCPKValidCount_Cnt_u16	46706
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	5294
k_DMDRELAXECPKSigValidThresh_Cnt_u16	50208
k_DMDRelaxeConsistentThresh_Cnt_u16	52062
k_DateValidThresh_Cnt_u16	47379
k_DefaultVehSpd_Kph_f32	223.825302
k_DiagMuxOnAbsentTimeout_mS_u16	16308
k_EMNodeTimeout_mS_u16	43733
k_ESPNTCEnableTimeout_mS_u16	43405
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	54311
k_EtatMTSigInvalidThresh_Cnt_u16	45254
k_EtatMTSigValidThresh_Cnt_u16	6553
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	48309
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	30524
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	32259
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	56370
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	64833
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	38730
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	22862
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	33156
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	36281
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	20858

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	44248
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	35511
k_ISDATDIRASentDiag_Cnt_str.Threshold	12314
k_ISDATDIRASentDiag_Cnt_str.PStep	25984
k_ISDATDIRASentDiag_Cnt_str.NStep	21340
k_ISDATDIRASentTimeout_mS_u16	5727
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	42520
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	18638
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	1545
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	50739
k_ISDYNAASChkSumValidThresh_Cnt_u16	22214
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	56826
k_ISDYNAASMsgCountValidThresh_Cnt_u16	1092
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	57095
k_ISDYNAASMsgLenValidThresh_Cnt_u16	37708
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	54970
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	16973
k_ISDYNABRChkSumValidThresh_Cnt_u16	48264
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	63946
k_ISDYNABRMsgCountValidThresh_Cnt_u16	45941
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46865
k_ISDYNABRMsgLenValidThresh_Cnt_u16	48007
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	65512
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	4906
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	60843
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	16235
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	48703
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	21930
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	9423
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	32109
k_ISDYNVOLChkSumValidThresh_Cnt_u16	20588
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	61392
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	9882
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	62185
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	21776
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	23297
k_IgnOnTimeout_mS_u16	18585
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	102.290604
k_PowerCutVehSpdLowThresh_Kph_f32	201.204697
k_PowerCutVehSpdLowTimeout_mS_u16	54341
k_VBattMaxAAS_Volt_f32	9.47850037
k_VBattMaxBSI_Volt_f32	14.1414003
k_VBattMaxCAV_Volt_f32	31.4006004
k_VBattMaxCMM388_Volt_f32	5.05749989
k_VBattMaxCMM_Volt_f32	32
k_VBattMaxESP_Volt_f32	7.98409986
k_VBattMinAAS_Volt_f32	3.7112999
k_VBattMinBSI_Volt_f32	7.98409986
k_VBattMinCAV_Volt_f32	25.7723999
k_VBattMinCMM388_Volt_f32	0.569299996
k_VBattMinCMM_Volt_f32	23.4461994
k_VBattMinESP_Volt_f32	32
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	49114
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	9801
k_VitesseVehicleBVRampValidThresh_Cnt_u16	8377
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	62909
k_VitesseVehicleBVSigValidThresh_Cnt_u16	3419
k_VitesseVehicleBVSpeedPassThresh_kph_f32	43.7881012
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	9569
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	45251
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	946148608
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2646119936
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	114
target_SrlComInput_Per1_Batt_Volt_f32.value	28.8589001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1652311296
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	35
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.656749189
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	28
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4073108736
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1233474816
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1859384576
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	119
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3400701184
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3307287808
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	198
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3323974912
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	145
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	900625664
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	32
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	52
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	53
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	79
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	102
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	109
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	180
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	38
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	327652608
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	65
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	136
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	171
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	172
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	197
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	220
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	228
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	139
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3775247616
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	175
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2235847936
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3088250112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	47
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	77
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	89
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	90
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	138
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	149
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3214787840
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1753
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.55577153
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	995723
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	187.230301
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	25752

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2646119936	2646119936	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2646119936	2646119936	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	2646119936	2646119936	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2646119936	2646119936	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2646119936	2646119936	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2646119936	2646119936	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2646119936	2646119936	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	13537	13537	✔
BSINodeAbsentTimer_mS_M_u32	2646119936	2646119936	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2646119936	2646119936	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2646119936	2646119936	✔
CDD_SrlComVehSpd_Kph_G_f32	577.058105	577.058105	✔
CMM388NTCEnableTimer_mS_M_u32	2646119936	2646119936	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2646119936	2646119936	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2646119936	2646119936	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	6342	6342	✔
CONSANGLECPK_HwDeg_M_f32	-407.966614	-407.966614 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2646119936	2646119936	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	2646119936	2646119936	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2646119936	2646119936	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2646119936	2646119936	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2646119936	2646119936	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2646119936	2646119936	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	2646119936	2646119936	✔
ESPNTCEnableTimer_mS_M_u32	2646119936	2646119936	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2646119936	2646119936	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	707	707	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1235	1235	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	97	97	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	979	979	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2646119936	2646119936	✔
EngOnDLCInvalidCount_Cnt_M_u08	0	0	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	47379	47379	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2646119936	2646119936	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	40932	40932	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2646119936	2646119936	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	18109	18109	✔
ISDATBSI412MsgTimer_mS_M_u32	2646119936	2646119936	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	8926	8926	✔
ISDATBSI432MsgTimer_mS_M_u32	2646119936	2646119936	✔
ISDATDIRASentFltAcc_Cnt_M_u16	12314	12314	✔
ISDATDIRASentTimer_mS_M_u32	2646119936	2646119936	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	5294	5294	✔
ISDYN2CMMMsgTimer_mS_M_u32	2646119936	2646119936	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	16751	16751	✔
ISDYNAASMsgTimer_mS_M_u32	2646119936	2646119936	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	13	13	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	6342	6342	✔
ISDYNABRMsgTimer_mS_M_u32	2646119936	2646119936	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	40932	40932	✔
ISDYNCMM208MsgTimer_mS_M_u32	2646119936	2646119936	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	336	336	✔
ISDYNCMM388MsgTimer_mS_M_u32	2646119936	2646119936	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	40977	40977	✔
ISDYNVOLMsgTimer_mS_M_u32	2646119936	2646119936	✔
IgnOnTimer_mS_M_u32	3690247424	3690247424	✔
IgnTimeOff_Sec_M_u32	2736607532	2736607532	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	28	28	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4073108736	4073108736	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	210	210	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1233474816	1233474816	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	35	35	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1859384576	1859384576	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	119	119	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3400701184	3400701184	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1688532224	1688532224	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	198	198	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3323974912	3323974912	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	145	145	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	900625664	900625664	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	38	38	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	327652608	327652608	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	139	139	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3775247616	3775247616	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	175	175	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2235847936	2235847936	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	46	46	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3088250112	3088250112	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3214787840	3214787840	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	56.7342987	56.7342987	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	211.312607	211.312607	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	280.945313	280.945313	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	6342	6342	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2736607532	2736607532	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-407.966614	-407.966614 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	577.058105	577.058105	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.477 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2480460800
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	24803
AASNodeAbsentTimer_mS_M_u32	2382578688
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	34483
ANGLEVOLANTSigValidCount_Cnt_M_u16	50995
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	15368
AngleVolantMsgTimer_mS_M_u32	2480460800
AngleVolantValidCount_Cnt_M_u16	34626
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	630260736
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3036906496
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1309176832
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	687682560
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	49170
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	43316224
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	57294
CAVNodeAbsentTimer_mS_M_u32	610722816
CDD_SrlComVehSpd_Kph_G_f32	156.407394
CMM388NTCEnableTimer_mS_M_u32	1069884416
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4021085184
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	54911
CMMNodeAbsentTimer_mS_M_u32	3895931904
CONSANGLECPKSigInvalidCount_Cnt_M_u16	57965
CONSANGLECPKSigValidCount_Cnt_M_u16	44733
CONSANGLECPK_Cnt_M_u16	55264
CONSANGLECPK_HwDeg_M_f32	-343.037689
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	55264
CPKVehicleSpeedMsgTimer_mS_M_u32	3744453632
CPKVehicleSpeedValidCount_Cnt_M_u16	46607
CityParkInputConsistentCount_Cnt_M_u16	48070
CityParkInputInvalidCount_Cnt_M_u16	31117
CityParkInputMsgTimer_mS_M_u32	4073108736
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3817292800
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	7015

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	2572903424
ComputerRazGCTSigValidCount_Cnt_M_u16	30307
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	33033
DMDFCTCPKSigValidCount_Cnt_M_u16	8241
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	20469
DMDRELAXECPKSigValidCount_Cnt_M_u16	24053
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	40594
DateInvalidTimer_mS_M_u32	3036906496
DiagMuxOnAbsentTimer_mS_M_u32	391156736
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	687682560
ESPNTCEnableTimer_mS_M_u32	3496756224
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	65499
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	8
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3442930688
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	58234
EtatMTSigValidCount_Cnt_M_u16	3782
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	61871
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	2943
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	46455
ISDAT4V2BSI552MsgTimer_mS_M_u32	414921728
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	51030
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	57642
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	3782
ISDATBSI3F2MsgTimer_mS_M_u32	3759051776
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	36047
ISDATBSI412MsgLenValidCount_Cnt_M_u16	64594
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	58234
ISDATBSI412MsgTimer_mS_M_u32	1385616384
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	8707
ISDATBSI432MsgLenValidCount_Cnt_M_u16	42591
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	38487
ISDATDIRASentFltAcc_Cnt_M_u16	55147
ISDATDIRASentTimer_mS_M_u32	3744453632
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	21278
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	34626
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	45032
ISDYN2CMMMsgTimer_mS_M_u32	4029039616
ISDYNAASChkSumInvalidCount_Cnt_M_u16	5669
ISDYNAASChkSumValidCount_Cnt_M_u16	4293
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	44065
ISDYNAASMsgCount_Cnt_M_u08	7
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	5937
ISDYNAASMsgLenValidCount_Cnt_M_u16	12297
ISDYNAASMsgTimeValidCount_Cnt_M_u16	5669
ISDYNAASMsgTimer_mS_M_u32	1413555200
ISDYNABRChkSumInvalidCount_Cnt_M_u16	5720
ISDYNABRChkSumValidCount_Cnt_M_u16	2912
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	12676
ISDYNABRMsgCountValidCount_Cnt_M_u16	17764
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	63692
ISDYNABRMsgLenValidCount_Cnt_M_u16	7772
ISDYNABRMsgTimeValidCount_Cnt_M_u16	55264
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	47707
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	3782
ISDYNCMM208MsgTimer_mS_M_u32	1584268288
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	47707
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	58624

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1297130496
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	9003
ISDYNVOLChkSumValidCount_Cnt_M_u16	41467
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	64711
ISDYNVOLMsgCountValidCount_Cnt_M_u16	36463
ISDYNVOLMsgCount_Cnt_M_u08	0
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	52092
ISDYNVOLMsgLenValidCount_Cnt_M_u16	15788
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	54911
ISDYNVOLMsgTimer_mS_M_u32	970417152
IgnOnTimer_mS_M_u32	282371072
IgnTimeOff_Sec_M_u32	3173906817
ManVehSpd_Kph_M_f32	269.761108
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	107
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	233
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	439653376
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	81
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	793211904
PrevISDATBSI412MsgDLCError_Cnt_M_u08	13
PrevISDATBSI412MsgRxTime_MSec_M_u32	3752846336
PrevISDATBSI432MsgDLCError_Cnt_M_u08	143
PrevISDATBSI432MsgRxTime_MSec_M_u32	450905088
PrevISDATDIRAMsgTxTime_MSec_M_u32	2277762048
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	207
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3188634624
PrevISDYNAASMsgDLCError_Cnt_M_u08	3
PrevISDYNAASMsgRxTime_MSec_M_u32	1024812032
PrevISDYNABRMsgDLCError_Cnt_M_u08	158
PrevISDYNABRMsgRxTime_MSec_M_u32	2228003840
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	134
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3211944960
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	174
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3372434432
PrevISDYNVOLMsgDLCError_Cnt_M_u08	8
PrevISDYNVOLMsgRxTime_MSec_M_u32	1000662016
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1549063168
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	254.619095
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	35055
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	5191
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	17936
VitesseVehicleBVRampValidCount_Cnt_M_u16	6184
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	24916
VitesseVehicleBVSigValidCount_Cnt_M_u16	2196
VitesseVehicleBV_Kph_M_f32	188.277496
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	58624
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	46008
VitesseVehiculeRoues_Kph_M_f32	131.927094
k_AASNTCEnableTimeout_mS_u16	45943
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	33437
k_AASNodeTimeout_mS_u16	53063
k_ABSNodeTimeout_mS_u16	21414
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	28830
k_ANGLEVOLANTSigValidThresh_Cnt_u16	17210
k_AngleVolantInvalidThresh_Cnt_u16	61857
k_AngleVolantValidThresh_Cnt_u16	31117
k_BSI552MsgTimeout_mS_u16	14559
k_BSINTCEnableTimeout_mS_u16	34299
k_BSINodeAbsentDiag_Cnt_str.Threshold	33043
k_BSINodeAbsentDiag_Cnt_str.PStep	12643
k_BSINodeAbsentDiag_Cnt_str.NStep	27671
k_BSINodeAbsentTimeout_mS_u16	25088
k_BSINodeTimeout_mS_u16	38487
k_BattOvHi_Volt_f32	22.9915009
k_BattOvLo_Volt_f32	14.8209
k_BattUvHi_Volt_f32	12.2025003
k_BattUvLo_Volt_f32	21.4006004
k_CAVNTCEnableTimeout_mS_u16	24387
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	17548
k_CAVNodeTimeout_mS_u16	44777
k_CMM388MsgTimeout_mS_u16	23523
k_CMM388NTCEnableTimeout_mS_u16	57695
k_CMMNTCEnableTimeout_mS_u16	59214
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	65332
k_CONSANGLECPKMax_HwDeg_f32	565.280273
k_CONSANGLECPKMin_HwDeg_f32	-616.27948
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	24576
k_CONSANGLECPKSigValidThresh_Cnt_u16	28344
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	22413
k_CPKVehicleSpeedValidThresh_Cnt_u16	36850
k_CityParkInputInvalidThresh_Cnt_u16	53022
k_CityParkInputValidThresh_Cnt_u16	48070
k_ComputerRazGCTSigValidThresh_Cnt_u16	61436
k_CptTemporelSigValidThresh_Cnt_u16	23120
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	62412
k_DMDFCTCPKSigValidThresh_Cnt_u16	22876
k_DMDFCTCPKValidCount_Cnt_u16	9498
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	45032
k_DMDRELAXECPKSigValidThresh_Cnt_u16	2128
k_DMDRelaxeConsistentThresh_Cnt_u16	27286
k_DateValidThresh_Cnt_u16	46455
k_DefaultVehSpd_Kph_f32	115.472504
k_DiagMuxOnAbsentTimeout_mS_u16	39702
k_EMNodeTimeout_mS_u16	17138
k_ESPNTCEnableTimeout_mS_u16	32330
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	25404
k_EtatMTSigInvalidThresh_Cnt_u16	56735
k_EtatMTSigValidThresh_Cnt_u16	35303
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	912
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	35516
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	64231
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	36507
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	559
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	3667
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	57032
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	56548
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	44423
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	64964
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	616
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	30987
k_ISDATDIRASentDiag_Cnt_str.Threshold	53628

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	31362
k_ISDATDIRASentDiag_Cnt_str.NStep	51301
k_ISDATDIRASentTimeout_mS_u16	20692
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	60136
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	15368
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	22742
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	37208
k_ISDYNAASChkSumValidThresh_Cnt_u16	50784
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	11396
k_ISDYNAASMsgCountValidThresh_Cnt_u16	32868
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	38620
k_ISDYNAASMsgLenValidThresh_Cnt_u16	39883
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	13634
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	23690
k_ISDYNABRChkSumValidThresh_Cnt_u16	29850
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	47890
k_ISDYNABRMsgCountValidThresh_Cnt_u16	54482
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	37247
k_ISDYNABRMsgLenValidThresh_Cnt_u16	64219
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	31609
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	62835
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	53040
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	54126
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	33203
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	563
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	17285
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	42986
k_ISDYNVOLChkSumValidThresh_Cnt_u16	50605
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	49664
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	42724
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	36598
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	40770
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	1965
k_IgnOnTimeout_mS_u16	63078
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	36.5764999
k_PowerCutVehSpdLowThresh_Kph_f32	35.834301
k_PowerCutVehSpdLowTimeout_mS_u16	24931
k_VBattMaxAAS_Volt_f32	21.7022991
k_VBattMaxBSI_Volt_f32	19.1219997
k_VBattMaxCAV_Volt_f32	2.82570004
k_VBattMaxCMM388_Volt_f32	23.1382999
k_VBattMaxCMM_Volt_f32	17.9354
k_VBattMaxESP_Volt_f32	29.8915997
k_VBattMinAAS_Volt_f32	27.4990005
k_VBattMinBSI_Volt_f32	29.8915997
k_VBattMinCAV_Volt_f32	18.5179996
k_VBattMinCMM388_Volt_f32	14.7854996
k_VBattMinCMM_Volt_f32	24.1107998
k_VBattMinESP_Volt_f32	17.9354
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	9634
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	18710
k_VitesseVehicleBVRampValidThresh_Cnt_u16	30663
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	56571
k_VitesseVehicleBVSigValidThresh_Cnt_u16	44255
k_VitesseVehicleBVSpeedPassThresh_kph_f32	91.5561981
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	23246
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	57190
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3036906496
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	810352896
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	174
target_SrlComInput_Per1_Batt_Volt_f32.value	7.66680002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3481138176
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	245
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	3
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.410931081
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	14
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2489230336
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1386398720
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	124
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3845579776
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	337314816
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2806981632
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	189
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1725121536
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	61
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	447177728
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	118
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	154
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	169
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	181
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	200
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	238
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	239
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	44
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3449553920
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	63
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	195
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	205
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	205
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	223
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2241963008
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1533395968
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	25
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3313099776
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	123
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	138
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	155
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	208
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	218
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	235
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	237
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	504984576
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3418
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0150569864
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	1
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	556903
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	92.0074005
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	14633

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	810352896	810352896	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	810352896	810352896	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	0	0	✔
AngleVolantMsgTimer_mS_M_u32	810352896	810352896	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	810352896	810352896	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	810352896	810352896	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	810352896	810352896	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	810352896	810352896	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	33043	33043	✔
BSINodeAbsentTimer_mS_M_u32	810352896	810352896	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	810352896	810352896	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	810352896	810352896	✔
CDD_SrlComVehSpd_Kph_G_f32	269.761108	269.761108	✔
CMM388NTCEnableTimer_mS_M_u32	810352896	810352896	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	810352896	810352896	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	810352896	810352896	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	55264	55264	✔
CONSANGLECPK_HwDeg_M_f32	-343.037689	-343.037689 ± 0.0125	✔
CPKOK_Cnt_M_lgc	1	1	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	810352896	810352896	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	0	0	✔
CityParkInputMsgTimer_mS_M_u32	810352896	810352896	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	810352896	810352896	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	810352896	810352896	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	810352896	810352896	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	810352896	810352896	✔
DiagOn_Cnt_M_lgc	1	1	✔
DmdDelestDATimer_mS_M_u32	810352896	810352896	✔
ESPNTCEnableTimer_mS_M_u32	810352896	810352896	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	810352896	810352896	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4	4	✔
ElecIntTimer_mS_M_u32[1]	8	8	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	810352896	810352896	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	46455	46455	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	810352896	810352896	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	3782	3782	✔
ISDATBSI3F2MsgTimer_mS_M_u32	810352896	810352896	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	58234	58234	✔
ISDATBSI412MsgTimer_mS_M_u32	810352896	810352896	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	38487	38487	✔
ISDATBSI432MsgTimer_mS_M_u32	810352896	810352896	✔
ISDATDIRASentFltAcc_Cnt_M_u16	53628	53628	✔
ISDATDIRASentTimer_mS_M_u32	810352896	810352896	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	45032	45032	✔
ISDYN2CMMMsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	7	7	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	5669	5669	✔
ISDYNAASMsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	55264	55264	✔
ISDYNABRMsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	3782	3782	✔
ISDYNCMM208MsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	58624	58624	✔
ISDYNCMM388MsgTimer_mS_M_u32	810352896	810352896	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	0	0	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	54911	54911	✔
ISDYNVOLMsgTimer_mS_M_u32	810352896	810352896	✔
IgnOnTimer_mS_M_u32	282371072	282371072	✔
IgnTimeOff_Sec_M_u32	3173906817	3173906817	✔
Msg348Valid_Cnt_M_lgc	1	1	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2489230336	2489230336	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	141	141	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1386398720	1386398720	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	124	124	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3845579776	3845579776	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	164	164	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	337314816	337314816	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2277762048	2277762048	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	189	189	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1725121536	1725121536	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	61	61	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	447177728	447177728	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	44	44	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3449553920	3449553920	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	123	123	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2241963008	2241963008	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	178	178	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1533395968	1533395968	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	25	25	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3313099776	3313099776	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	504984576	504984576	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	254.619095	254.619095	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	1	1	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	188.277496	188.277496	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	131.927094	131.927094	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	55264	55264	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3173906817	3173906817	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-343.037689	-343.037689 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	269.761108	269.761108	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔

Test Step 1.478 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	610551552
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	1860
AASNodeAbsentTimer_mS_M_u32	732231424
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	30675
ANGLEVOLANTSigValidCount_Cnt_M_u16	57875
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	18901
AngleVolantMsgTimer_mS_M_u32	610551552
AngleVolantValidCount_Cnt_M_u16	30887
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3422271232
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	128202496
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3159713536
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4000786176
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	1974
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1890576128
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	16641
CAVNodeAbsentTimer_mS_M_u32	4277802752
CDD_SrlComVehSpd_Kph_G_f32	161.947693
CMM388NTCEnableTimer_mS_M_u32	4125054720
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	891819776
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	39345
CMMNodeAbsentTimer_mS_M_u32	415835904
CONSANGLECPKSigInvalidCount_Cnt_M_u16	31654
CONSANGLECPKSigValidCount_Cnt_M_u16	33398
CONSANGLECPK_Cnt_M_u16	21261
CONSANGLECPK_HwDeg_M_f32	-108.035004
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21261
CPKVehicleSpeedMsgTimer_mS_M_u32	1583302400
CPKVehicleSpeedValidCount_Cnt_M_u16	27175
CityParkInputConsistentCount_Cnt_M_u16	60187
CityParkInputInvalidCount_Cnt_M_u16	57029
CityParkInputMsgTimer_mS_M_u32	2489230336
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	991491840
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	59320

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ComputerRazGCTSigInvalidTimer_mS_M_u32	303863552
ComputerRazGCTSigValidCount_Cnt_M_u16	28484
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	47185
DMDFCTCPKSigValidCount_Cnt_M_u16	42649
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	41997
DMDRELAXECPKSigValidCount_Cnt_M_u16	42445
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	6967
DateInvalidTimer_mS_M_u32	128202496
DiagMuxOnAbsentTimer_mS_M_u32	687671040
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	4000786176
ESPNTCEnableTimer_mS_M_u32	1214904064
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	47453
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	87
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	21
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	415885056
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	28607
EtatMTSigValidCount_Cnt_M_u16	18843
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	54752
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	62512
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	32455
ISDAT4V2BSI552MsgTimer_mS_M_u32	2537367296
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	11690
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	23534
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	18843
ISDATBSI3F2MsgTimer_mS_M_u32	1187186432
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	3649
ISDATBSI412MsgLenValidCount_Cnt_M_u16	64373
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	28607
ISDATBSI412MsgTimer_mS_M_u32	1613383424
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	50981
ISDATBSI432MsgLenValidCount_Cnt_M_u16	54737
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	33126
ISDATDIRASentFltAcc_Cnt_M_u16	3626
ISDATDIRASentTimer_mS_M_u32	1583302400
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	22867
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	30887
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	26548
ISDYN2CMMMsgTimer_mS_M_u32	1362884352
ISDYNAASChkSumInvalidCount_Cnt_M_u16	28542
ISDYNAASChkSumValidCount_Cnt_M_u16	11102
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	17930
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	59096
ISDYNAASMsgLenValidCount_Cnt_M_u16	10257
ISDYNAASMsgTimeValidCount_Cnt_M_u16	28542
ISDYNAASMsgTimer_mS_M_u32	2825606912
ISDYNABRChkSumInvalidCount_Cnt_M_u16	21094
ISDYNABRChkSumValidCount_Cnt_M_u16	48910
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	22881
ISDYNABRMsgCountValidCount_Cnt_M_u16	51585
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	29833
ISDYNABRMsgLenValidCount_Cnt_M_u16	28569
ISDYNABRMsgTimeValidCount_Cnt_M_u16	21261
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	43890
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	2127
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	18843
ISDYNCMM208MsgTimer_mS_M_u32	3580147456
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	43890
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	2127
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	55149

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgTimer_mS_M_u32	1530713856
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	12652
ISDYNVOLChkSumValidCount_Cnt_M_u16	8380
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	48407
ISDYNVOLMsgCountValidCount_Cnt_M_u16	54239
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	6778
ISDYNVOLMsgLenValidCount_Cnt_M_u16	44970
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	39345
ISDYNVOLMsgTimer_mS_M_u32	547919616
IgnOnTimer_mS_M_u32	548460288
IgnTimeOff_Sec_M_u32	1731174213
ManVehSpd_Kph_M_f32	575.011292
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	108
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	45
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2958100224
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	41
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3566757632
PrevISDATBSI412MsgDLCError_Cnt_M_u08	225
PrevISDATBSI412MsgRxTime_MSec_M_u32	824121088
PrevISDATBSI432MsgDLCError_Cnt_M_u08	132
PrevISDATBSI432MsgRxTime_MSec_M_u32	957216512
PrevISDATDIRAMsgTxTime_MSec_M_u32	2296583936
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	156
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1430431488
PrevISDYNAASMsgDLCError_Cnt_M_u08	152
PrevISDYNAASMsgRxTime_MSec_M_u32	2398000896
PrevISDYNABRMsgDLCError_Cnt_M_u08	223
PrevISDYNABRMsgRxTime_MSec_M_u32	2764625664
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	198
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3151468288
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	36
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2057631488
PrevISDYNVOLMsgDLCError_Cnt_M_u08	106
PrevISDYNVOLMsgRxTime_MSec_M_u32	826283776
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3136308992
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	98.0572968
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	2462
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	62295
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	38459
VitesseVehicleBVRampValidCount_Cnt_M_u16	43956
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	44016
VitesseVehicleBVSigValidCount_Cnt_M_u16	57840
VitesseVehicleBV_Kph_M_f32	417.581909
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	55149
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	30469
VitesseVehiculeRoues_Kph_M_f32	128.9897
k_AASNTCEnableTimeout_mS_u16	56392
k_AASNodeAbsentDiag_Cnt_str.Threshold	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	45718
k_AASNodeTimeout_mS_u16	49751
k_ABSNodeTimeout_mS_u16	62586
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	1876
k_ANGLEVOLANTSigValidThresh_Cnt_u16	11072
k_AngleVolantInvalidThresh_Cnt_u16	31755
k_AngleVolantValidThresh_Cnt_u16	57029
k_BSI552MsgTimeout_mS_u16	17296
k_BSINTCEnableTimeout_mS_u16	31549
k_BSINodeAbsentDiag_Cnt_str.Threshold	28392
k_BSINodeAbsentDiag_Cnt_str.PStep	49975
k_BSINodeAbsentDiag_Cnt_str.NStep	2138
k_BSINodeAbsentTimeout_mS_u16	47085
k_BSINodeTimeout_mS_u16	33126
k_BattOvHi_Volt_f32	5.31629992
k_BattOvLo_Volt_f32	31.4466
k_BattUvHi_Volt_f32	28.6061001
k_BattUvLo_Volt_f32	0.472200006
k_CAVNTCEnableTimeout_mS_u16	34211
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	35527
k_CAVNodeTimeout_mS_u16	1586
k_CMM388MsgTimeout_mS_u16	5700
k_CMM388NTCEnableTimeout_mS_u16	30160
k_CMMNTCEnableTimeout_mS_u16	44482
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	33937
k_CONSANGLECPKMax_HwDeg_f32	274.758301
k_CONSANGLECPKMin_HwDeg_f32	-338.590515
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	26221
k_CONSANGLECPKSigValidThresh_Cnt_u16	17925
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	49541
k_CPKVehicleSpeedValidThresh_Cnt_u16	20696
k_CityParkInputInvalidThresh_Cnt_u16	49172
k_CityParkInputValidThresh_Cnt_u16	60187
k_ComputerRazGCTSigValidThresh_Cnt_u16	52152
k_CptTemporelSigValidThresh_Cnt_u16	2172
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	33673
k_DMDFCTCPKSigValidThresh_Cnt_u16	48793
k_DMDFCTCPKValidCount_Cnt_u16	63646
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	26548
k_DMDRELAXECPKSigValidThresh_Cnt_u16	10812
k_DMDRelaxeConsistentThresh_Cnt_u16	39786
k_DateValidThresh_Cnt_u16	32455
k_DefaultVehSpd_Kph_f32	174.015198
k_DiagMuxOnAbsentTimeout_mS_u16	24939
k_EMNodeTimeout_mS_u16	44567
k_ESPNTCEnableTimeout_mS_u16	21901
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	30841
k_EtatMTSigInvalidThresh_Cnt_u16	55441
k_EtatMTSigValidThresh_Cnt_u16	8057
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	35196
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	53176
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	61880
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	11227
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	19679
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	39349
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	58582
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	34370
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	13465
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	29025
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	7989
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	35468
k_ISDATDIRASentDiag_Cnt_str.Threshold	1905

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATDIRASentDiag_Cnt_str.PStep	4278
k_ISDATDIRASentDiag_Cnt_str.NStep	49319
k_ISDATDIRASentTimeout_mS_u16	37618
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	59637
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	18901
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	62953
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	57702
k_ISDYNAASChkSumValidThresh_Cnt_u16	36366
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	26721
k_ISDYNAASMsgCountValidThresh_Cnt_u16	6273
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	57562
k_ISDYNAASMsgLenValidThresh_Cnt_u16	27851
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	29992
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	49487
k_ISDYNABRChkSumValidThresh_Cnt_u16	58591
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	5814
k_ISDYNABRMsgCountValidThresh_Cnt_u16	62774
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	26801
k_ISDYNABRMsgLenValidThresh_Cnt_u16	51293
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	23873
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	54290
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	2846
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	4578
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	34515
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	12563
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	24797
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	59632
k_ISDYNVOLChkSumValidThresh_Cnt_u16	52068
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	18158
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	64642
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	23883
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	34855
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	57381
k_IgnOnTimeout_mS_u16	60796
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	205.203201
k_PowerCutVehSpdLowThresh_Kph_f32	87.4298019
k_PowerCutVehSpdLowTimeout_mS_u16	33412
k_VBattMaxAAS_Volt_f32	23.8941994
k_VBattMaxBSI_Volt_f32	30.4106007
k_VBattMaxCAV_Volt_f32	5.85510015
k_VBattMaxCMM388_Volt_f32	22.0676003
k_VBattMaxCMM_Volt_f32	7.99550009
k_VBattMaxESP_Volt_f32	21.2080994
k_VBattMinAAS_Volt_f32	8.01869965
k_VBattMinBSI_Volt_f32	21.2080994
k_VBattMinCAV_Volt_f32	28.3554001
k_VBattMinCMM388_Volt_f32	13.5780001
k_VBattMinCMM_Volt_f32	15.7340002
k_VBattMinESP_Volt_f32	7.99550009
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	41159
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	12844
k_VitesseVehicleBVRampValidThresh_Cnt_u16	19479
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	28604
k_VitesseVehicleBVSigValidThresh_Cnt_u16	48080
k_VitesseVehicleBVSpeedPassThresh_kph_f32	536.610291
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	53249
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	52730
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	128202496
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8524
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2751184896
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	36
target_SrlComInput_Per1_Batt_Volt_f32.value	22.4284992
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3992250112
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	63
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.175803542
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1041422080
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3150345984
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	17
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4236908288
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	50
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2824713984
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1732335360
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3778344704
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	176
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3191379712
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	65
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	66
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	91
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	139
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	230
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3218781952
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	21
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	23
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	46
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	72
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	201
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	111
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	910808832
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	228
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1836939008
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	7
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	666965760
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	11
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	103
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	108
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	213
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3491915520
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3994
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.523333132
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	397786
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	132.160507
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	24816

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	610551552	610551552	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2751184896	2751184896	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	18903	18903	✔
AngleVolantMsgTimer_mS_M_u32	2751184896	2751184896	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3422271232	3422271232	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI412NTCEnableTimer_mS_M_u32	128202496	128202496	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3159713536	3159713536	✔
BSI432NTCsEnabled_Cnt_M_lgc	1	1	✔
BSI552NTCEnableTimer_mS_M_u32	4000786176	4000786176	✔
BSI552NTCsEnabled_Cnt_M_lgc	1	1	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2751184896	2751184896	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2751184896	2751184896	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	39345	39345	✔
CMMNodeAbsentTimer_mS_M_u32	3778344704	3778344704	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	21261	21261	✔
CONSANGLECPK_HwDeg_M_f32	-108.035004	-108.035004 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	21261	21261	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1583302400	1583302400	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	27175	27175	✔
CityParkInputConsistentCount_Cnt_M_u16	60187	60187	✔
CityParkInputInvalidCount_Cnt_M_u16	57029	57029	✔
CityParkInputMsgTimer_mS_M_u32	2751184896	2751184896	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2751184896	2751184896	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2751184896	2751184896	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	128202496	128202496	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2751184896	2751184896	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4000786176	4000786176	✔
ESPNTCEnableTimer_mS_M_u32	2751184896	2751184896	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2751184896	2751184896	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2751184896	2751184896	✔
EffacDefaultDiagTimer_mS_M_u32[1]	87	87	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2751184896	2751184896	✔
ElecIntTimer_mS_M_u32[1]	21	21	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2751184896	2751184896	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	54752	54752	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1041422080	1041422080	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	11690	11690	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1187186432	1187186432	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	50981	50981	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2824713984	2824713984	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1905	1905	✔
ISDATDIRASentTimer_mS_M_u32	2751184896	2751184896	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2751184896	2751184896	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2751184896	2751184896	✔
IgnOnTimer_mS_M_u32	548460288	548460288	✔
IgnTimeOff_Sec_M_u32	1731174213	1731174213	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	235	235	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1041422080	1041422080	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	135	135	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3150345984	3150345984	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	17	17	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4236908288	4236908288	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	50	50	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2824713984	2824713984	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2296583936	2296583936	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	218	218	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3778344704	3778344704	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	176	176	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3191379712	3191379712	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	221	221	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3218781952	3218781952	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	111	111	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	910808832	910808832	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	228	228	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1836939008	1836939008	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	7	7	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	666965760	666965760	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3491915520	3491915520	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	98.0572968	98.0572968	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	417.581909	417.581909	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	128.9897	128.9897	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	21261	21261	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1731174213	1731174213	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-108.035004	-108.035004 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	174.015198	174.015198	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔
NTC	0x0138	0x0138	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔
NTC	0x0160	0x0160	✔
Param	0x00	0x00	✔
Status	0x01	0x01	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	7	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
NodeAbsentNTCProcessing	1	NodeAbsentNTCProcessing	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	11	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	11	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
MissingMessageNTCProcessing	1	MissingMessageNTCProcessing	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
MixedTimeValidityNTCProcessing	1	MixedTimeValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
ValidityNTCProcessing	1	ValidityNTCProcessing	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_SetNTCStatus	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.479 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	609086976
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	40364
AASNodeAbsentTimer_mS_M_u32	759946752
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	42496
ANGLEVOLANTSigValidCount_Cnt_M_u16	58368
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	23033
AngleVolantMsgTimer_mS_M_u32	609086976
AngleVolantValidCount_Cnt_M_u16	39940
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	390569472
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2790137344
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	150638080
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	697650688
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	16983
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	1978338816
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	52469
CAVNodeAbsentTimer_mS_M_u32	4023156224
CDD_SrlComVehSpd_Kph_G_f32	372.345886
CMM388NTCEnableTimer_mS_M_u32	807190016
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2235727360
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	3238
CMMNodeAbsentTimer_mS_M_u32	1923042816
CONSANGLECPKSigInvalidCount_Cnt_M_u16	21896
CONSANGLECPKSigValidCount_Cnt_M_u16	64984

Name	Input Value
CONSANGLECPK_Cnt_M_u16	43027
CONSANGLECPK_HwDeg_M_f32	-638.973999
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43027
CPKVehicleSpeedMsgTimer_mS_M_u32	576515584
CPKVehicleSpeedValidCount_Cnt_M_u16	60876
CityParkInputConsistentCount_Cnt_M_u16	5288
CityParkInputInvalidCount_Cnt_M_u16	45737
CityParkInputMsgTimer_mS_M_u32	0
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3471826432
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	52304
ComputerRazGCTSigInvalidTimer_mS_M_u32	1617231360
ComputerRazGCTSigValidCount_Cnt_M_u16	27693
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	22021
DMDFCTCPKSigValidCount_Cnt_M_u16	10221
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	35154
DMDRELAXECPKSigValidCount_Cnt_M_u16	210
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	64213
DateInvalidTimer_mS_M_u32	2790137344
DiagMuxOnAbsentTimer_mS_M_u32	1770237440
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	697650688
ESPNTCEnableTimer_mS_M_u32	721214976
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	55906
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	8
EffacDefaultDiagTimer_mS_M_u32[1]	9
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	202
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1704791552
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	37755
EtatMTSigValidCount_Cnt_M_u16	62119
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	44762
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	4266
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	55139
ISDAT4V2BSI552MsgTimer_mS_M_u32	3343076864
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	7483
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	7982
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	62119
ISDATBSI3F2MsgTimer_mS_M_u32	2821828096
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	59509
ISDATBSI412MsgLenValidCount_Cnt_M_u16	28057
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	37755
ISDATBSI412MsgTimer_mS_M_u32	150728192
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	21578
ISDATBSI432MsgLenValidCount_Cnt_M_u16	21766
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	57286
ISDATDIRASentFltAcc_Cnt_M_u16	18810
ISDATDIRASentTimer_mS_M_u32	576515584
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	11585
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	39940
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	37852
ISDYN2CMMMsgTimer_mS_M_u32	3632717312
ISDYNAASChkSumInvalidCount_Cnt_M_u16	52478
ISDYNAASChkSumValidCount_Cnt_M_u16	38429
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	32731
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	63344
ISDYNAASMsgLenValidCount_Cnt_M_u16	36999
ISDYNAASMsgTimeValidCount_Cnt_M_u16	52478
ISDYNAASMsgTimer_mS_M_u32	1215872512
ISDYNABRChkSumInvalidCount_Cnt_M_u16	31176
ISDYNABRChkSumValidCount_Cnt_M_u16	20623

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	23381
ISDYNABRMsgCountValidCount_Cnt_M_u16	1972
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	46815
ISDYNABRMsgLenValidCount_Cnt_M_u16	33391
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43027
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	58343
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	33345
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	62119
ISDYNCMM208MsgTimer_mS_M_u32	3742146048
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	58343
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	33345
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	6066
ISDYNCMM388MsgTimer_mS_M_u32	1443118592
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	52278
ISDYNVOLChkSumValidCount_Cnt_M_u16	47878
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	57267
ISDYNVOLMsgCountValidCount_Cnt_M_u16	14363
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	27403
ISDYNVOLMsgLenValidCount_Cnt_M_u16	59450
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	3238
ISDYNVOLMsgTimer_mS_M_u32	1690369536
IgnOnTimer_mS_M_u32	3584572928
IgnTimeOff_Sec_M_u32	3067669271
ManVehSpd_Kph_M_f32	155.481506
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	109
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	232
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	596094464
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	86
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2352057856
PrevISDATBSI412MsgDLCError_Cnt_M_u08	114
PrevISDATBSI412MsgRxTime_MSec_M_u32	761101824
PrevISDATBSI432MsgDLCError_Cnt_M_u08	12
PrevISDATBSI432MsgRxTime_MSec_M_u32	3910196736
PrevISDATDIRAMsgTxTime_MSec_M_u32	907116032
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	54
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2201144832
PrevISDYNAASMsgDLCError_Cnt_M_u08	122
PrevISDYNAASMsgRxTime_MSec_M_u32	2985229824
PrevISDYNABRMsgDLCError_Cnt_M_u08	97
PrevISDYNABRMsgRxTime_MSec_M_u32	2841656832
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	204
PrevISDYNCMM208MsgRxTime_MSec_M_u32	255065600
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	56
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1078713856
PrevISDYNVOLMsgDLCError_Cnt_M_u08	101
PrevISDYNVOLMsgRxTime_MSec_M_u32	4042948096
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2427055616
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	528.123474
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	10014
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	50869
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VehSpdSync_Cnt_M_Igc	0
VehTimeValid_Cnt_M_Igc	0
VehicleSpeedValid_Cnt_M_Igc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	13639
VitesseVehicleBVRampValidCount_Cnt_M_u16	20894
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	48553
VitesseVehicleBVSigValidCount_Cnt_M_u16	39017
VitesseVehicleBV_Kph_M_f32	520.729919
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	6066
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	5545
VitesseVehiculeRoues_Kph_M_f32	134.076401
k_AASNTCEnableTimeout_mS_u16	47202
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	27191
k_AASNodeTimeout_mS_u16	22965
k_ABSNodeTimeout_mS_u16	34186
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	4029
k_ANGLEVOLANTSigValidThresh_Cnt_u16	53433
k_AngleVolantInvalidThresh_Cnt_u16	51800
k_AngleVolantValidThresh_Cnt_u16	45737
k_BSI552MsgTimeout_mS_u16	39944
k_BSINTCEnableTimeout_mS_u16	38914
k_BSINodeAbsentDiag_Cnt_str.Threshold	33175
k_BSINodeAbsentDiag_Cnt_str.PStep	57513
k_BSINodeAbsentDiag_Cnt_str.NStep	17487
k_BSINodeAbsentTimeout_mS_u16	28593
k_BSINodeTimeout_mS_u16	57286
k_BattOvHi_Volt_f32	27.4346008
k_BattOvLo_Volt_f32	9.18789959
k_BattUvHi_Volt_f32	17.2968006
k_BattUvLo_Volt_f32	5.81720018
k_CAVNTCEnableTimeout_mS_u16	46607
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	34723
k_CAVNodeTimeout_mS_u16	58852
k_CMM388MsgTimeout_mS_u16	28844
k_CMM388NTCEnableTimeout_mS_u16	33288
k_CMMNTCEnableTimeout_mS_u16	64755
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	7429
k_CONSANGLECPKMax_HwDeg_f32	443.262207
k_CONSANGLECPKMin_HwDeg_f32	-65.6063004
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	27314
k_CONSANGLECPKSigValidThresh_Cnt_u16	43177
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	37931
k_CPKVehicleSpeedValidThresh_Cnt_u16	15536
k_CityParkInputInvalidThresh_Cnt_u16	26814
k_CityParkInputValidThresh_Cnt_u16	5288
k_ComputerRazGCTSigValidThresh_Cnt_u16	64273
k_CptTemporelSigValidThresh_Cnt_u16	53636
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	35295
k_DMDFCTCPKSigValidThresh_Cnt_u16	38255
k_DMDFCTCPKValidCount_Cnt_u16	3999
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	37852
k_DMDRELAXECPKSigValidThresh_Cnt_u16	59652
k_DMDRelaxeConsistentThresh_Cnt_u16	52602
k_DateValidThresh_Cnt_u16	55139
k_DefaultVehSpd_Kph_f32	13.9337997
k_DiagMuxOnAbsentTimeout_mS_u16	29945
k_EMNodeTimeout_mS_u16	49717
k_ESPNTCEnableTimeout_mS_u16	48977
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	57677
k_EtatMTSigInvalidThresh_Cnt_u16	21319
k_EtatMTSigValidThresh_Cnt_u16	39758

Name	Input Value
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	55366
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	29265
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	46289
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	9896
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	20571
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	5657
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	65335
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	18355
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	56302
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	40215
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	24666
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	45203
k_ISDATDIRASentDiag_Cnt_str.Threshold	6549
k_ISDATDIRASentDiag_Cnt_str.PStep	63930
k_ISDATDIRASentDiag_Cnt_str.NStep	24627
k_ISDATDIRASentTimeout_mS_u16	59428
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	31064
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	23033
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	20029
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	52424
k_ISDYNAASChkSumValidThresh_Cnt_u16	58255
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	11861
k_ISDYNAASMsgCountValidThresh_Cnt_u16	6836
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	40556
k_ISDYNAASMsgLenValidThresh_Cnt_u16	10841
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	37633
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	26765
k_ISDYNABRChkSumValidThresh_Cnt_u16	47773
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	5463
k_ISDYNABRMsgCountValidThresh_Cnt_u16	63127
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	40870
k_ISDYNABRMsgLenValidThresh_Cnt_u16	44386
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	43638
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	38850
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	42462
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	22292
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	30976
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	63232
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	35937
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	54376
k_ISDYNVOLChkSumValidThresh_Cnt_u16	31180
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	46511
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	26675
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	64215
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	26371
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	43849
k_IgnOnTimeout_mS_u16	63172
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	24.8698006
k_PowerCutVehSpdLowThresh_Kph_f32	226.190201
k_PowerCutVehSpdLowTimeout_mS_u16	46510
k_VBattMaxAAS_Volt_f32	30.6664009
k_VBattMaxBSI_Volt_f32	14.7910995
k_VBattMaxCAV_Volt_f32	11.7904997
k_VBattMaxCMM388_Volt_f32	28.7017002
k_VBattMaxCMM_Volt_f32	27.9599991
k_VBattMaxESP_Volt_f32	6.079
k_VBattMinAAS_Volt_f32	7.74900007
k_VBattMinBSI_Volt_f32	6.079
k_VBattMinCAV_Volt_f32	32
k_VBattMinCMM388_Volt_f32	22.8139992
k_VBattMinCMM_Volt_f32	24.9505005
k_VBattMinESP_Volt_f32	27.9599991
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	6626
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	29302
k_VitesseVehicleBVRampValidThresh_Cnt_u16	12979
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	52742
k_VitesseVehicleBVSigValidThresh_Cnt_u16	46729
k_VitesseVehicleBVSpeedPassThresh_kph_f32	20.7115002
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	8181
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	33484
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2790137344

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	55763
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	56
target_SrlComInput_Per1_Batt_Volt_f32.value	26.5867996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1377570304
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	16
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0840601325
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2239905280
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	13
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3806813696
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	101
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	924614144
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	56
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2317458944
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3824598528
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1285283328
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	224
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3423665664
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	124
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	137
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	182
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	219
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	223
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	237
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2007670272
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	100
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	162
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	179
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	232
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	242
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	244
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	58
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	954023424
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	146
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1774345728
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1366785536
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	18
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	30
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	70
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	150
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	174
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	191
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1100189184
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2887
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0208821166
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1024896
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	220.248001
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	59688

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	43027	43027	✔
CONSANGLECPK_HwDeg_M_f32	-638.973999	-638.973999 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1713429248	1713429248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1713429248	1713429248	✔
EffacDefaultDiagTimer_mS_M_u32[1]	9	9	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1713429248	1713429248	✔
ElecIntTimer_mS_M_u32[1]	202	202	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	6549	6549	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	1713429248	1713429248	✔
IgnTimeOff_Sec_M_u32	3067669271	3067669271	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2239905280	2239905280	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	13	13	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3806813696	3806813696	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	101	101	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	924614144	924614144	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	56	56	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2317458944	2317458944	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	907116032	907116032	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1285283328	1285283328	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	224	224	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3423665664	3423665664	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	106	106	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2007670272	2007670272	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	58	58	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	954023424	954023424	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	146	146	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1774345728	1774345728	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	30	30	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1366785536	1366785536	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1100189184	1100189184	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	528.123474	528.123474	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	520.729919	520.729919	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	134.076401	134.076401	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	43027	43027	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3067669271	3067669271	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-638.973999	-638.973999 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.480 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1072494848
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	28113
AASNodeAbsentTimer_mS_M_u32	3367184640
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	18131
ANGLEVOLANTSigValidCount_Cnt_M_u16	5781
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	44266
AngleVolantMsgTimer_mS_M_u32	1072494848
AngleVolantValidCount_Cnt_M_u16	31561
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2847926528
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	917268736
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2355566848
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	93772032
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	36302
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2811599104
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	19063
CAVNodeAbsentTimer_mS_M_u32	3417393408
CDD_SrlComVehSpd_Kph_G_f32	495.838196
CMM388NTCEnableTimer_mS_M_u32	2613086464
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1666140416
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	44578
CMMNodeAbsentTimer_mS_M_u32	3531135232
CONSANGLECPKSigInvalidCount_Cnt_M_u16	1852
CONSANGLECPKSigValidCount_Cnt_M_u16	55310
CONSANGLECPK_Cnt_M_u16	34141
CONSANGLECPK_HwDeg_M_f32	724.323608
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	34141
CPKVehicleSpeedMsgTimer_mS_M_u32	1103100160
CPKVehicleSpeedValidCount_Cnt_M_u16	13080
CityParkInputConsistentCount_Cnt_M_u16	41309

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	23641
CityParkInputMsgTimer_mS_M_u32	4294967295
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1942432000
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	29157
ComputerRazGCTSigInvalidTimer_mS_M_u32	2078787840
ComputerRazGCTSigValidCount_Cnt_M_u16	61134
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	57925
DMDFCTCPKSigValidCount_Cnt_M_u16	38479
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	25821
DMDRELAXECPKSigValidCount_Cnt_M_u16	34847
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	35669
DateInvalidTimer_mS_M_u32	917268736
DiagMuxOnAbsentTimer_mS_M_u32	2001451264
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	93772032
ESPNTCEnableTimer_mS_M_u32	3550488832
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	48816
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	11
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	89
ElecIntTimer_mS_M_u32[1]	900
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	545233152
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	65186
EtatMTSigValidCount_Cnt_M_u16	6880
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	49990
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	26520
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	57325
ISDAT4V2BSI552MsgTimer_mS_M_u32	1686952192
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	5860
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	27338
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	6880
ISDATBSI3F2MsgTimer_mS_M_u32	4081170688
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	28213
ISDATBSI412MsgLenValidCount_Cnt_M_u16	63627
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	65186
ISDATBSI412MsgTimer_mS_M_u32	3387095296
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	26422
ISDATBSI432MsgLenValidCount_Cnt_M_u16	57028
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	38404
ISDATDIRASentFltAcc_Cnt_M_u16	10472
ISDATDIRASentTimer_mS_M_u32	1103100160
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	11731
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	31561
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	17600
ISDYN2CMMMsgTimer_mS_M_u32	1929521408
ISDYNAASChkSumInvalidCount_Cnt_M_u16	42971
ISDYNAASChkSumValidCount_Cnt_M_u16	22077
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	60356
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	30470
ISDYNAASMsgLenValidCount_Cnt_M_u16	38272
ISDYNAASMsgTimeValidCount_Cnt_M_u16	42971
ISDYNAASMsgTimer_mS_M_u32	3266087168
ISDYNABRChkSumInvalidCount_Cnt_M_u16	41213
ISDYNABRChkSumValidCount_Cnt_M_u16	50791
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	6358
ISDYNABRMsgCountValidCount_Cnt_M_u16	7544
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	65335
ISDYNABRMsgLenValidCount_Cnt_M_u16	26185
ISDYNABRMsgTimeValidCount_Cnt_M_u16	34141
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	62744

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	11722
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	6880
ISDYNCMM208MsgTimer_mS_M_u32	2792417536
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	62744
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	11722
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	16447
ISDYNCMM388MsgTimer_mS_M_u32	671746304
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	56114
ISDYNVOLChkSumValidCount_Cnt_M_u16	55428
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	32059
ISDYNVOLMsgCountValidCount_Cnt_M_u16	40389
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	61621
ISDYNVOLMsgLenValidCount_Cnt_M_u16	49894
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	44578
ISDYNVOLMsgTimer_mS_M_u32	3738421504
IgnOnTimer_mS_M_u32	958269696
IgnTimeOff_Sec_M_u32	2260233357
ManVehSpd_Kph_M_f32	48.4720993
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	110
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	81
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1497348352
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	225
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2663520512
PrevISDATBSI412MsgDLCError_Cnt_M_u08	194
PrevISDATBSI412MsgRxTime_MSec_M_u32	2533247232
PrevISDATBSI432MsgDLCError_Cnt_M_u08	108
PrevISDATBSI432MsgRxTime_MSec_M_u32	3915655424
PrevISDATDIRAMsgTxTime_MSec_M_u32	1289898240
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	151
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1321097472
PrevISDYNAASMsgDLCError_Cnt_M_u08	38
PrevISDYNAASMsgRxTime_MSec_M_u32	793364736
PrevISDYNABRMsgDLCError_Cnt_M_u08	62
PrevISDYNABRMsgRxTime_MSec_M_u32	2650147072
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	155
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1803208960
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	200
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2410883328
PrevISDYNVOLMsgDLCError_Cnt_M_u08	63
PrevISDYNVOLMsgRxTime_MSec_M_u32	2574592
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1792604416
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	136.186203
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	8188
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	10998
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	55681
VitesseVehicleBVRampValidCount_Cnt_M_u16	28219
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	58328
VitesseVehicleBVSigValidCount_Cnt_M_u16	56666

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBV_Kph_M_f32	586.526123
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	16447
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	45080
VitesseVehiculeRoues_Kph_M_f32	253.0569
k_AASNTCEnableTimeout_mS_u16	20592
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	40112
k_AASNodeTimeout_mS_u16	29174
k_ABSNodeTimeout_mS_u16	42934
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	49373
k_ANGLEVOLANTSigValidThresh_Cnt_u16	63403
k_AngleVolantInvalidThresh_Cnt_u16	18126
k_AngleVolantValidThresh_Cnt_u16	23641
k_BSI552MsgTimeout_mS_u16	22779
k_BSINTCEnableTimeout_mS_u16	31758
k_BSINodeAbsentDiag_Cnt_str.Threshold	13192
k_BSINodeAbsentDiag_Cnt_str.PStep	45714
k_BSINodeAbsentDiag_Cnt_str.NStep	29664
k_BSINodeAbsentTimeout_mS_u16	19394
k_BSINodeTimeout_mS_u16	38404
k_BattOvHi_Volt_f32	27.3948994
k_BattOvLo_Volt_f32	31.5
k_BattUvHi_Volt_f32	8.61400032
k_BattUvLo_Volt_f32	5.69689989
k_CAVNTCEnableTimeout_mS_u16	27175
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	21101
k_CAVNodeTimeout_mS_u16	50728
k_CMM388MsgTimeout_mS_u16	62673
k_CMM388NTCEnableTimeout_mS_u16	12477
k_CMMNTCEnableTimeout_mS_u16	22460
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	2564
k_CONSANGLECPKMax_HwDeg_f32	631.374329
k_CONSANGLECPKMin_HwDeg_f32	-151.274994
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	18239
k_CONSANGLECPKSigValidThresh_Cnt_u16	63256
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	6804
k_CPKVehicleSpeedValidThresh_Cnt_u16	7556
k_CityParkInputInvalidThresh_Cnt_u16	11291
k_CityParkInputValidThresh_Cnt_u16	41309
k_ComputerRazGCTSigValidThresh_Cnt_u16	21858
k_CptTemporelSigValidThresh_Cnt_u16	11208
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	34359
k_DMDFCTCPKSigValidThresh_Cnt_u16	11593
k_DMDFCTCPKValidCount_Cnt_u16	17910
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	17600
k_DMDRELAXECPKSigValidThresh_Cnt_u16	28426
k_DMDRelaxeConsistentThresh_Cnt_u16	6568
k_DateValidThresh_Cnt_u16	57325
k_DefaultVehSpd_Kph_f32	239.537506
k_DiagMuxOnAbsentTimeout_mS_u16	13995
k_EMNodeTimeout_mS_u16	46389
k_ESPNTCEnableTimeout_mS_u16	58211
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	56620
k_EtatMTSigInvalidThresh_Cnt_u16	53376
k_EtatMTSigValidThresh_Cnt_u16	41514
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	31299
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	26080
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	42210
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	61085
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	52035
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	30025
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	23151

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	64189
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	24650
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	46673
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	1607
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	24283
k_ISDATDIRASentDiag_Cnt_str.Threshold	1170
k_ISDATDIRASentDiag_Cnt_str.PStep	4955
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	50665
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	22668
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	44266
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	59039
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	43005
k_ISDYNAASChkSumValidThresh_Cnt_u16	3431
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	40918
k_ISDYNAASMsgCountValidThresh_Cnt_u16	58488
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	49937
k_ISDYNAASMsgLenValidThresh_Cnt_u16	36874
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	53459
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	8749
k_ISDYNABRChkSumValidThresh_Cnt_u16	62911
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	5326
k_ISDYNABRMsgCountValidThresh_Cnt_u16	64208
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	62754
k_ISDYNABRMsgLenValidThresh_Cnt_u16	17840
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	6963
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	24080
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	6650
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	46553
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	52691
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	56725
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	44849
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	13916
k_ISDYNVOLChkSumValidThresh_Cnt_u16	24562
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	41161
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	3963
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	14478
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	11724
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	31803
k_IgnOnTimeout_mS_u16	16200
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	149.229401
k_PowerCutVehSpdLowThresh_Kph_f32	1.26839995
k_PowerCutVehSpdLowTimeout_mS_u16	34956
k_VBattMaxAAS_Volt_f32	9.49380016
k_VBattMaxBSI_Volt_f32	13.0981998
k_VBattMaxCAV_Volt_f32	21.1009007
k_VBattMaxCMM388_Volt_f32	4.72079992
k_VBattMaxCMM_Volt_f32	3.81999993
k_VBattMaxESP_Volt_f32	16.1924992
k_VBattMinAAS_Volt_f32	25.8778
k_VBattMinBSI_Volt_f32	16.1924992
k_VBattMinCAV_Volt_f32	23.9920006
k_VBattMinCMM388_Volt_f32	17.4531002
k_VBattMinCMM_Volt_f32	18.2301998
k_VBattMinESP_Volt_f32	3.81999993
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	7918
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	61171
k_VitesseVehicleBVRampValidThresh_Cnt_u16	33851
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	40836
k_VitesseVehicleBVSigValidThresh_Cnt_u16	32698
k_VitesseVehicleBVSpeedPassThresh_kph_f32	546.361816
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	20855
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	4785
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	917268736
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	200
target_SrlComInput_Per1_Batt_Volt_f32.value	2.78189993
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	386046208
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	193
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.148090169
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	294652160
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	78
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1977657600
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	901859584
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	959572224
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1748142336
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	32
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2864916736
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	227
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3907242240
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	59
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	85
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	92
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	128
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	176
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	184
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	201
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3566659840
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	49
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	141
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	157
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	177
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	204
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	227
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	234
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	24
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	595527936
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	235
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	223324416
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	102
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	313542912
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	61
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	97
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	122
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	145
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	153
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	169
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	246
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2258376960
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3813
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.718048275
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	309957
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	146.344894

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	33246		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	34141	34141	✔
CONSANGLECPK_HwDeg_M_f32	724.323608	724.323608 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1713429248	1713429248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1713429248	1713429248	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	11	11	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1713429248	1713429248	✔
ElecIntTimer_mS_M_u32[1]	900	900	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1170	1170	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	1713429248	1713429248	✔
IgnTimeOff_Sec_M_u32	2260233357	2260233357	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	33	33	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	294652160	294652160	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	78	78	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1977657600	1977657600	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	99	99	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	901859584	901859584	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	72	72	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	959572224	959572224	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1289898240	1289898240	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	32	32	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2864916736	2864916736	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	227	227	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3907242240	3907242240	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3566659840	3566659840	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	24	24	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	595527936	595527936	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	235	235	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	223324416	223324416	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	102	102	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	313542912	313542912	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2258376960	2258376960	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	136.186203	136.186203	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	586.526123	586.526123	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	253.0569	253.0569	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	34141	34141	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2260233357	2260233357	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	724.323608	724.323608 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	239.537506	239.537506	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.481 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	184276992
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	45902
AASNodeAbsentTimer_mS_M_u32	2238269440
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	21062
ANGLEVOLANTSigValidCount_Cnt_M_u16	17857
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	39427
AngleVolantMsgTimer_mS_M_u32	184276992
AngleVolantValidCount_Cnt_M_u16	29031
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	88279040
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2961016832
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	906852352
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	964573184
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	10581
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3196188672
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	56795
CAVNodeAbsentTimer_mS_M_u32	2632902656
CDD_SrlComVehSpd_Kph_G_f32	117.469498
CMM388NTCEnableTimer_mS_M_u32	2042701824
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3457476608
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	19099
CMMNodeAbsentTimer_mS_M_u32	3671603200
CONSANGLECPKSigInvalidCount_Cnt_M_u16	41996
CONSANGLECPKSigValidCount_Cnt_M_u16	54359
CONSANGLECPK_Cnt_M_u16	51306
CONSANGLECPK_HwDeg_M_f32	-433.072998
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	51306
CPKVehicleSpeedMsgTimer_mS_M_u32	293787648
CPKVehicleSpeedValidCount_Cnt_M_u16	57984
CityParkInputConsistentCount_Cnt_M_u16	20267

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	24374
CityParkInputMsgTimer_mS_M_u32	294652160
CityParkInputValidCount_Cnt_M_u16	10
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3559737344
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	63250
ComputerRazGCTSigInvalidTimer_mS_M_u32	2253088768
ComputerRazGCTSigValidCount_Cnt_M_u16	27352
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	32114
DMDFCTCPKSigValidCount_Cnt_M_u16	58389
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	41000
DMDRELAXECPKSigValidCount_Cnt_M_u16	39203
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	48065
DateInvalidTimer_mS_M_u32	2961016832
DiagMuxOnAbsentTimer_mS_M_u32	1340053504
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	964573184
ESPNTCEnableTimer_mS_M_u32	1487030272
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	43954
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	20
EffacDefaultDiagTimer_mS_M_u32[1]	21
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	750
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2076440576
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	43546
EtatMTSigValidCount_Cnt_M_u16	43041
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	6126
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	52665
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	65339
ISDAT4V2BSI552MsgTimer_mS_M_u32	1956395008
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	16596
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	14307
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	43041
ISDATBSI3F2MsgTimer_mS_M_u32	872257536
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	4065
ISDATBSI412MsgLenValidCount_Cnt_M_u16	9119
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	43546
ISDATBSI412MsgTimer_mS_M_u32	3306805248
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	28511
ISDATBSI432MsgLenValidCount_Cnt_M_u16	39798
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	28468
ISDATDIRASentFltAcc_Cnt_M_u16	18056
ISDATDIRASentTimer_mS_M_u32	293787648
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	9992
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	29031
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	513
ISDYN2CMMMsgTimer_mS_M_u32	2189182976
ISDYNAASChkSumInvalidCount_Cnt_M_u16	44336
ISDYNAASChkSumValidCount_Cnt_M_u16	33995
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	52214
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	21550
ISDYNAASMsgLenValidCount_Cnt_M_u16	15233
ISDYNAASMsgTimeValidCount_Cnt_M_u16	44336
ISDYNAASMsgTimer_mS_M_u32	3036489728
ISDYNABRChkSumInvalidCount_Cnt_M_u16	49993
ISDYNABRChkSumValidCount_Cnt_M_u16	21964
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	1599
ISDYNABRMsgCountValidCount_Cnt_M_u16	56090
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	26651
ISDYNABRMsgLenValidCount_Cnt_M_u16	54694
ISDYNABRMsgTimeValidCount_Cnt_M_u16	51306
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	61330

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	2619
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	43041
ISDYNCMM208MsgTimer_mS_M_u32	321914880
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	61330
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	2619
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	31365
ISDYNCMM388MsgTimer_mS_M_u32	3672418304
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	32810
ISDYNVOLChkSumValidCount_Cnt_M_u16	10997
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	1168
ISDYNVOLMsgCountValidCount_Cnt_M_u16	9651
ISDYNVOLMsgCount_Cnt_M_u08	14
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	27043
ISDYNVOLMsgLenValidCount_Cnt_M_u16	5582
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	19099
ISDYNVOLMsgTimer_mS_M_u32	226977792
IgnOnTimer_mS_M_u32	4155025408
IgnTimeOff_Sec_M_u32	2840162323
ManVehSpd_Kph_M_f32	159.065903
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	111
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	185
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2047055872
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	121
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	721188864
PrevISDATBSI412MsgDLCError_Cnt_M_u08	53
PrevISDATBSI412MsgRxTime_MSec_M_u32	2936530944
PrevISDATBSI432MsgDLCError_Cnt_M_u08	217
PrevISDATBSI432MsgRxTime_MSec_M_u32	659965952
PrevISDATDIRAMsgTxTime_MSec_M_u32	492562432
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	88
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1544009728
PrevISDYNAASMsgDLCError_Cnt_M_u08	156
PrevISDYNAASMsgRxTime_MSec_M_u32	1948608512
PrevISDYNABRMsgDLCError_Cnt_M_u08	239
PrevISDYNABRMsgRxTime_MSec_M_u32	690006016
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	248
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3281152000
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	36
PrevISDYNCMM388MsgRxTime_MSec_M_u32	812206080
PrevISDYNVOLMsgDLCError_Cnt_M_u08	191
PrevISDYNVOLMsgRxTime_MSec_M_u32	1468852224
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	976738304
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	217.043106
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	45388
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	54047
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	55485
VitesseVehicleBVRampValidCount_Cnt_M_u16	23888
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	53047
VitesseVehicleBVSigValidCount_Cnt_M_u16	17778

Name	Input Value
VitesseVehicleBV_Kph_M_f32	206.905502
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	31365
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	60856
VitesseVehiculeRoues_Kph_M_f32	436.882599
k_AASNTCEnableTimeout_mS_u16	29489
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	26930
k_AASNodeTimeout_mS_u16	65055
k_ABSNodeTimeout_mS_u16	12575
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	48746
k_ANGLEVOLANTSigValidThresh_Cnt_u16	44225
k_AngleVolantInvalidThresh_Cnt_u16	2904
k_AngleVolantValidThresh_Cnt_u16	24374
k_BSI552MsgTimeout_mS_u16	16143
k_BSINTCEnableTimeout_mS_u16	37079
k_BSINodeAbsentDiag_Cnt_str.Threshold	60865
k_BSINodeAbsentDiag_Cnt_str.PStep	39907
k_BSINodeAbsentDiag_Cnt_str.NStep	37690
k_BSINodeAbsentTimeout_mS_u16	7547
k_BSINodeTimeout_mS_u16	28468
k_BattOvHi_Volt_f32	5.2874999
k_BattOvLo_Volt_f32	13.6599998
k_BattUvHi_Volt_f32	14.2129002
k_BattUvLo_Volt_f32	5.0321002
k_CAVNTCEnableTimeout_mS_u16	60876
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	7673
k_CAVNodeTimeout_mS_u16	5960
k_CMM388MsgTimeout_mS_u16	7758
k_CMM388NTCEnableTimeout_mS_u16	6794
k_CMMNTCEnableTimeout_mS_u16	56908
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	36852
k_CONSANGLECPKMax_HwDeg_f32	670.854187
k_CONSANGLECPKMin_HwDeg_f32	-190.433197
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	25989
k_CONSANGLECPKSigValidThresh_Cnt_u16	6328
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	64581
k_CPKVehicleSpeedValidThresh_Cnt_u16	65012
k_CityParkInputInvalidThresh_Cnt_u16	6639
k_CityParkInputValidThresh_Cnt_u16	20267
k_ComputerRazGCTSigValidThresh_Cnt_u16	64858
k_CptTemporelSigValidThresh_Cnt_u16	27881
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	54043
k_DMDFCTCPKSigValidThresh_Cnt_u16	32934
k_DMDFCTCPKValidCount_Cnt_u16	41181
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	513
k_DMDRELAXECPKSigValidThresh_Cnt_u16	1508
k_DMDRelaxeConsistentThresh_Cnt_u16	65034
k_DateValidThresh_Cnt_u16	65339
k_DefaultVehSpd_Kph_f32	182.6483
k_DiagMuxOnAbsentTimeout_mS_u16	27776
k_EMNodeTimeout_mS_u16	48673
k_ESPNTCEnableTimeout_mS_u16	49943
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	46716
k_EtatMTSigInvalidThresh_Cnt_u16	192
k_EtatMTSigValidThresh_Cnt_u16	36483
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	22840
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	26911
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	39068
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	56745
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	14968
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	19109
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	47540

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	27531
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	54307
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	1422
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	18541
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	25329
k_ISDATDIRASentDiag_Cnt_str.Threshold	47720
k_ISDATDIRASentDiag_Cnt_str.PStep	17950
k_ISDATDIRASentDiag_Cnt_str.NStep	21543
k_ISDATDIRASentTimeout_mS_u16	1157
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	31198
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	39427
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	43363
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	44617
k_ISDYNAASChkSumValidThresh_Cnt_u16	32972
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	28991
k_ISDYNAASMsgCountValidThresh_Cnt_u16	34330
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	44301
k_ISDYNAASMsgLenValidThresh_Cnt_u16	62435
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	49481
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	22329
k_ISDYNABRChkSumValidThresh_Cnt_u16	32580
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	37973
k_ISDYNABRMsgCountValidThresh_Cnt_u16	17680
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	30107
k_ISDYNABRMsgLenValidThresh_Cnt_u16	5810
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	12263
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	18192
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	24722
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	32374
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	48454
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	61633
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	50862
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	4972
k_ISDYNVOLChkSumValidThresh_Cnt_u16	18794
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	43367
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	51856
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	44118
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	8029
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	57937
k_IgnOnTimeout_mS_u16	43176
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	114.072601
k_PowerCutVehSpdLowThresh_Kph_f32	213.955399
k_PowerCutVehSpdLowTimeout_mS_u16	15069
k_VBattMaxAAS_Volt_f32	24.0170994
k_VBattMaxBSI_Volt_f32	13.2683001
k_VBattMaxCAV_Volt_f32	25.2574005
k_VBattMaxCMM388_Volt_f32	4.33710003
k_VBattMaxCMM_Volt_f32	16.4172993
k_VBattMaxESP_Volt_f32	7.11140013
k_VBattMinAAS_Volt_f32	32
k_VBattMinBSI_Volt_f32	7.11140013
k_VBattMinCAV_Volt_f32	19.0009003
k_VBattMinCMM388_Volt_f32	13.9321003
k_VBattMinCMM_Volt_f32	23.0412998
k_VBattMinESP_Volt_f32	16.4172993
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	11960
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	12647
k_VitesseVehicleBVRampValidThresh_Cnt_u16	61328
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	54773
k_VitesseVehicleBVSigValidThresh_Cnt_u16	26644
k_VitesseVehicleBVSpeedPassThresh_kph_f32	353.677795
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	51419
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	51182
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2961016832
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52496
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	36
target_SrlComInput_Per1_Batt_Volt_f32.value	26.1868992
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1681586176
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	178
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.967899442
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	154
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3058870272
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	333498368
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	231
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2663311360
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	35
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2666334208
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1550526464
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	523847680
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	145
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	794257408
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	57
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	82
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	93
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	152
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	161
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	179
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	193
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2696808448
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	23
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	108
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	118
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	135
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	137
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	175
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4236617728
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	33
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3381905408
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2213668864
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	50
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	120
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	129
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	130
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	148
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	161
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	243
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1533966336
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3917
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.576925635
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	177678
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	164.976196

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	37798		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	39427	39427	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	51306	51306	✔
CONSANGLECPK_HwDeg_M_f32	-433.072998	-433.072998 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	51306	51306	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	293787648	293787648	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	57984	57984	✔
CityParkInputConsistentCount_Cnt_M_u16	20267	20267	✔
CityParkInputInvalidCount_Cnt_M_u16	24374	24374	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	20	20	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	21	21	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1713429248	1713429248	✔
ElecIntTimer_mS_M_u32[1]	750	750	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	47720	47720	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	14	14	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	4155025408	4155025408	✔
IgnTimeOff_Sec_M_u32	2840162323	2840162323	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	154	154	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3058870272	3058870272	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	123	123	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	333498368	333498368	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	231	231	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2663311360	2663311360	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	35	35	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2666334208	2666334208	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	492562432	492562432	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	48	48	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	523847680	523847680	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	145	145	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	794257408	794257408	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	144	144	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2696808448	2696808448	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	48	48	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4236617728	4236617728	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	33	33	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3381905408	3381905408	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	92	92	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2213668864	2213668864	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1533966336	1533966336	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	217.043106	217.043106	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	206.905502	206.905502	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	436.882599	436.882599	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	51306	51306	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2840162323	2840162323	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-433.072998	-433.072998 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	182.6483	182.6483	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.482 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	736000
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	28947
AASNodeAbsentTimer_mS_M_u32	1384311552
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	5674
ANGLEVOLANTSigValidCount_Cnt_M_u16	4985
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	53492
AngleVolantMsgTimer_mS_M_u32	736000
AngleVolantValidCount_Cnt_M_u16	33608
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1777707776
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1917201152
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1297505024
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	4127464192
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	36093
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	637065984
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	45034
CAVNodeAbsentTimer_mS_M_u32	2859600640
CDD_SrlComVehSpd_Kph_G_f32	414.80481
CMM388NTCEnableTimer_mS_M_u32	754666240
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	788531968
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	41581
CMMNodeAbsentTimer_mS_M_u32	4193655552
CONSANGLECPKSigInvalidCount_Cnt_M_u16	26584
CONSANGLECPKSigValidCount_Cnt_M_u16	61112
CONSANGLECPK_Cnt_M_u16	7807
CONSANGLECPK_HwDeg_M_f32	-2.18460011
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	7807
CPKVehicleSpeedMsgTimer_mS_M_u32	3363191552
CPKVehicleSpeedValidCount_Cnt_M_u16	34403
CityParkInputConsistentCount_Cnt_M_u16	63996

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	1754
CityParkInputMsgTimer_mS_M_u32	3058870272
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1983310592
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	46535
ComputerRazGCTSigInvalidTimer_mS_M_u32	6064896
ComputerRazGCTSigValidCount_Cnt_M_u16	39669
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	39974
DMDFCTCPKSigValidCount_Cnt_M_u16	57341
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	13444
DMDRELAXECPKSigValidCount_Cnt_M_u16	8531
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	13497
DateInvalidTimer_mS_M_u32	1917201152
DiagMuxOnAbsentTimer_mS_M_u32	1885338368
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4127464192
ESPNTCEnableTimer_mS_M_u32	4242008832
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	50920
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	99
EffacDefaultDiagTimer_mS_M_u32[1]	759
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	45
ElecIntTimer_mS_M_u32[1]	100
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	1983044352
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	37103
EtatMTSigValidCount_Cnt_M_u16	40602
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	5170
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	2706
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	42635
ISDAT4V2BSI552MsgTimer_mS_M_u32	1017780992
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	11840
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	28883
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	40602
ISDATBSI3F2MsgTimer_mS_M_u32	3154508544
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	16923
ISDATBSI412MsgLenValidCount_Cnt_M_u16	61086
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	37103
ISDATBSI412MsgTimer_mS_M_u32	3383835392
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	17441
ISDATBSI432MsgLenValidCount_Cnt_M_u16	1948
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	40927
ISDATDIRASentFltAcc_Cnt_M_u16	27107
ISDATDIRASentTimer_mS_M_u32	3363191552
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	64165
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	33608
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	2681
ISDYN2CMMMsgTimer_mS_M_u32	1732897536
ISDYNAASChkSumInvalidCount_Cnt_M_u16	35693
ISDYNAASChkSumValidCount_Cnt_M_u16	23644
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	28571
ISDYNAASMsgCount_Cnt_M_u08	2
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	22769
ISDYNAASMsgLenValidCount_Cnt_M_u16	55993
ISDYNAASMsgTimeValidCount_Cnt_M_u16	35693
ISDYNAASMsgTimer_mS_M_u32	1799834368
ISDYNABRChkSumInvalidCount_Cnt_M_u16	17571
ISDYNABRChkSumValidCount_Cnt_M_u16	34010
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	31808
ISDYNABRMsgCountValidCount_Cnt_M_u16	21871
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	6059
ISDYNABRMsgLenValidCount_Cnt_M_u16	59083
ISDYNABRMsgTimeValidCount_Cnt_M_u16	7807
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	42495

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	1987
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	40602
ISDYNCMM208MsgTimer_mS_M_u32	875473664
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	42495
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	1987
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	24558
ISDYNCMM388MsgTimer_mS_M_u32	4153461504
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	52094
ISDYNVOLChkSumValidCount_Cnt_M_u16	58078
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	65228
ISDYNVOLMsgCountValidCount_Cnt_M_u16	4899
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	37141
ISDYNVOLMsgLenValidCount_Cnt_M_u16	9300
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	41581
ISDYNVOLMsgTimer_mS_M_u32	1520995072
IgnOnTimer_mS_M_u32	2974075648
IgnTimeOff_Sec_M_u32	2447020753
ManVehSpd_Kph_M_f32	253.480804
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	112
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	12
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	69
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2180250368
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	183
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3934870272
PrevISDATBSI412MsgDLCError_Cnt_M_u08	100
PrevISDATBSI412MsgRxTime_MSec_M_u32	405211904
PrevISDATBSI432MsgDLCError_Cnt_M_u08	154
PrevISDATBSI432MsgRxTime_MSec_M_u32	1622928128
PrevISDATDIRAMsgTxTime_MSec_M_u32	489360128
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	22
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2489817856
PrevISDYNAASMsgDLCError_Cnt_M_u08	120
PrevISDYNAASMsgRxTime_MSec_M_u32	516852480
PrevISDYNABRMsgDLCError_Cnt_M_u08	177
PrevISDYNABRMsgRxTime_MSec_M_u32	4242328320
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	54
PrevISDYNCMM208MsgRxTime_MSec_M_u32	612862720
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	159
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1367534336
PrevISDYNVOLMsgDLCError_Cnt_M_u08	198
PrevISDYNVOLMsgRxTime_MSec_M_u32	1922566912
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1649883904
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	428.870789
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	14743
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	3039
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	51012
VitesseVehicleBVRampValidCount_Cnt_M_u16	29004
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	41815
VitesseVehicleBVSigValidCount_Cnt_M_u16	6246

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBV_Kph_M_f32	374.677399
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	24558
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	48661
VitesseVehiculeRoues_Kph_M_f32	27.0170002
k_AASNTCEnableTimeout_mS_u16	64042
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	34791
k_AASNodeTimeout_mS_u16	35551
k_ABSNodeTimeout_mS_u16	29983
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	17152
k_ANGLEVOLANTSigValidThresh_Cnt_u16	49083
k_AngleVolantInvalidThresh_Cnt_u16	49142
k_AngleVolantValidThresh_Cnt_u16	1754
k_BSI552MsgTimeout_mS_u16	58896
k_BSINTCEnableTimeout_mS_u16	49081
k_BSINodeAbsentDiag_Cnt_str.Threshold	32498
k_BSINodeAbsentDiag_Cnt_str.PStep	62155
k_BSINodeAbsentDiag_Cnt_str.NStep	23303
k_BSINodeAbsentTimeout_mS_u16	9868
k_BSINodeTimeout_mS_u16	40927
k_BattOvHi_Volt_f32	30.6334991
k_BattOvLo_Volt_f32	6.62669992
k_BattUvHi_Volt_f32	16.1081009
k_BattUvLo_Volt_f32	31.5
k_CAVNTCEnableTimeout_mS_u16	13080
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	59280
k_CAVNodeTimeout_mS_u16	65060
k_CMM388MsgTimeout_mS_u16	12307
k_CMM388NTCEnableTimeout_mS_u16	11103
k_CMMNTCEnableTimeout_mS_u16	13784
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	51041
k_CONSANGLECPKMax_HwDeg_f32	58.9030991
k_CONSANGLECPKMin_HwDeg_f32	-209.528702
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	40686
k_CONSANGLECPKSigValidThresh_Cnt_u16	15637
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	43117
k_CPKVehicleSpeedValidThresh_Cnt_u16	33762
k_CityParkInputInvalidThresh_Cnt_u16	22705
k_CityParkInputValidThresh_Cnt_u16	63996
k_ComputerRazGCTSigValidThresh_Cnt_u16	37038
k_CptTemporelSigValidThresh_Cnt_u16	27073
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	54955
k_DMDFCTCPKSigValidThresh_Cnt_u16	58827
k_DMDFCTCPKValidCount_Cnt_u16	18021
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	2681
k_DMDRELAXECPKSigValidThresh_Cnt_u16	30352
k_DMDRelaxeConsistentThresh_Cnt_u16	42526
k_DateValidThresh_Cnt_u16	42635
k_DefaultVehSpd_Kph_f32	205.550201
k_DiagMuxOnAbsentTimeout_mS_u16	2621
k_EMNodeTimeout_mS_u16	44441
k_ESPNTCEnableTimeout_mS_u16	61494
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	29641
k_EtatMTSigInvalidThresh_Cnt_u16	10302
k_EtatMTSigValidThresh_Cnt_u16	30389
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	7572
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	30111
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	8617
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	60353
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	64788
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	41423
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	63778

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	11101
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	9685
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	63251
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	38454
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	55786
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	28911
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	35107
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	53492
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	27986
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	33699
k_ISDYNAASChkSumValidThresh_Cnt_u16	986
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	15168
k_ISDYNAASMsgCountValidThresh_Cnt_u16	21615
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	38743
k_ISDYNAASMsgLenValidThresh_Cnt_u16	47507
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	41507
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	16977
k_ISDYNABRChkSumValidThresh_Cnt_u16	57841
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	19453
k_ISDYNABRMsgCountValidThresh_Cnt_u16	4492
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	8557
k_ISDYNABRMsgLenValidThresh_Cnt_u16	34280
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	27911
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	34891
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	21512
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	9690
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	54570
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	4729
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	45170
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	9082
k_ISDYNVOLChkSumValidThresh_Cnt_u16	26941
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	57801
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	13966
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	31291
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	10470
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	54601
k_IgnOnTimeout_mS_u16	21446
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	149.777298
k_PowerCutVehSpdLowThresh_Kph_f32	114.128799
k_PowerCutVehSpdLowTimeout_mS_u16	21286
k_VBattMaxAAS_Volt_f32	18.1180992
k_VBattMaxBSI_Volt_f32	17.1709995
k_VBattMaxCAV_Volt_f32	5.2125001
k_VBattMaxCMM388_Volt_f32	14.1549997
k_VBattMaxCMM_Volt_f32	15.7806997
k_VBattMaxESP_Volt_f32	26.2637005
k_VBattMinAAS_Volt_f32	14.9474001
k_VBattMinBSI_Volt_f32	26.2637005
k_VBattMinCAV_Volt_f32	16.7311001
k_VBattMinCMM388_Volt_f32	6.99420023
k_VBattMinCMM_Volt_f32	11.3451996
k_VBattMinESP_Volt_f32	15.7806997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	21141
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	62025
k_VitesseVehicleBVRampValidThresh_Cnt_u16	15820
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	57822
k_VitesseVehicleBVSigValidThresh_Cnt_u16	37697
k_VitesseVehicleBVSpeedPassThresh_kph_f32	511.862793
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	61162
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	10610
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1917201152
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8524
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1236548
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	159
target_SrlComInput_Per1_Batt_Volt_f32.value	26.0013008
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1489885952
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	135
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.885410964
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	185
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2638662400
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	212
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3843844864
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	147
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3842116352
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3304565504
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2902280960
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	56
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3306351360
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	23
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	892898048
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	145
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	157
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	234
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	235
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	92
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1132768000
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	79
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	113
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	121
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	167
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	190
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	191
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	216
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	130
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1454230272
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1342401280
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	191
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3244886784
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	126
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	134
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	179
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	182
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	202
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	203
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	227
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2704497408
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2446
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.183540046
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	379025
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	126.316597

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	31369		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1236548	1236548	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	53492	53492	✔
AngleVolantMsgTimer_mS_M_u32	1236548	1236548	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1236548	1236548	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	7807	7807	✔
CONSANGLECPK_HwDeg_M_f32	-2.18460011	-2.18460011 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	7807	7807	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3363191552	3363191552	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	34403	34403	✔
CityParkInputConsistentCount_Cnt_M_u16	63996	63996	✔
CityParkInputInvalidCount_Cnt_M_u16	1756	1756	✔
CityParkInputMsgTimer_mS_M_u32	1236548	1236548	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1236548	1236548	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1236548	1236548	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1236548	1236548	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1236548	1236548	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1236548	1236548	✔
ESPNTCEnableTimer_mS_M_u32	1236548	1236548	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1236548	1236548	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	759	759	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1236548	1236548	✔
ElecIntTimer_mS_M_u32[1]	100	100	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1236548	1236548	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATDIRASentFltAcc_Cnt_M_u16	41895	41895	✔
ISDATDIRASentTimer_mS_M_u32	1236548	1236548	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	2	2	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1236548	1236548	✔
IgnOnTimer_mS_M_u32	1236548	1236548	✔
IgnTimeOff_Sec_M_u32	2447020753	2447020753	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	12	12	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	185	185	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2638662400	2638662400	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	212	212	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3843844864	3843844864	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	147	147	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3842116352	3842116352	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	30	30	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3304565504	3304565504	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	489360128	489360128	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	56	56	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3306351360	3306351360	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	23	23	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	892898048	892898048	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	92	92	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1132768000	1132768000	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	130	130	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1454230272	1454230272	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	110	110	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1342401280	1342401280	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	191	191	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3244886784	3244886784	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2704497408	2704497408	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	428.870789	428.870789	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	374.677399	374.677399	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	27.0170002	27.0170002	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	7807	7807	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2447020753	2447020753	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-2.18460011	-2.18460011 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	205.550201	205.550201	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.483 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	237572608
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	32015
AASNodeAbsentTimer_mS_M_u32	3514958336
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	1996
ANGLEVOLANTSigValidCount_Cnt_M_u16	34974
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	8556
AngleVolantMsgTimer_mS_M_u32	237572608
AngleVolantValidCount_Cnt_M_u16	24817
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3324625408
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2402828800
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3133649408
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2814276096
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	44883
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3672125952
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	34058
CAVNodeAbsentTimer_mS_M_u32	3996426752
CDD_SrlComVehSpd_Kph_G_f32	26.0702991
CMM388NTCEnableTimer_mS_M_u32	463004160
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	411738624
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	834
CMMNodeAbsentTimer_mS_M_u32	3823661568
CONSANGLECPKSigInvalidCount_Cnt_M_u16	15807
CONSANGLECPKSigValidCount_Cnt_M_u16	25058
CONSANGLECPK_Cnt_M_u16	44685
CONSANGLECPK_HwDeg_M_f32	-73.5083008
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	44685
CPKVehicleSpeedMsgTimer_mS_M_u32	552079872
CPKVehicleSpeedValidCount_Cnt_M_u16	62566
CityParkInputConsistentCount_Cnt_M_u16	52437

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	61242
CityParkInputMsgTimer_mS_M_u32	2638662400
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	912654848
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	32499
ComputerRazGCTSigInvalidTimer_mS_M_u32	3061129728
ComputerRazGCTSigValidCount_Cnt_M_u16	3562
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	24406
DMDFCTCPKSigValidCount_Cnt_M_u16	11409
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	38078
DMDRELAXECPKSigValidCount_Cnt_M_u16	18192
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	39708
DateInvalidTimer_mS_M_u32	2402828800
DiagMuxOnAbsentTimer_mS_M_u32	2806272
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2814276096
ESPNTCEnableTimer_mS_M_u32	1719861760
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	48785
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1121
EffacDefaultDiagTimer_mS_M_u32[1]	2235
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	66
ElecIntTimer_mS_M_u32[1]	80
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	1379021312
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	4284
EtatMTSigValidCount_Cnt_M_u16	53370
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	8369
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	63060
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	37095
ISDAT4V2BSI552MsgTimer_mS_M_u32	3956044288
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	5193
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	54607
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	53370
ISDATBSI3F2MsgTimer_mS_M_u32	892916224
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	21943
ISDATBSI412MsgLenValidCount_Cnt_M_u16	39150
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	4284
ISDATBSI412MsgTimer_mS_M_u32	3375829504
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	60966
ISDATBSI432MsgLenValidCount_Cnt_M_u16	52341
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	51499
ISDATDIRASentFltAcc_Cnt_M_u16	31519
ISDATDIRASentTimer_mS_M_u32	552079872
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	12827
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	24817
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	8285
ISDYN2CMMMsgTimer_mS_M_u32	1865220608
ISDYNAASChkSumInvalidCount_Cnt_M_u16	5633
ISDYNAASChkSumValidCount_Cnt_M_u16	39924
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	43000
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	26101
ISDYNAASMsgLenValidCount_Cnt_M_u16	14687
ISDYNAASMsgTimeValidCount_Cnt_M_u16	5633
ISDYNAASMsgTimer_mS_M_u32	2427773440
ISDYNABRChkSumInvalidCount_Cnt_M_u16	63457
ISDYNABRChkSumValidCount_Cnt_M_u16	20475
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	20360
ISDYNABRMsgCountValidCount_Cnt_M_u16	48315
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	14918
ISDYNABRMsgLenValidCount_Cnt_M_u16	34217
ISDYNABRMsgTimeValidCount_Cnt_M_u16	44685
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	292

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	50841
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	53370
ISDYNCMM208MsgTimer_mS_M_u32	2340340224
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	292
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	50841
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	58111
ISDYNCMM388MsgTimer_mS_M_u32	4057489920
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	10957
ISDYNVOLChkSumValidCount_Cnt_M_u16	40304
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	20324
ISDYNVOLMsgCountValidCount_Cnt_M_u16	43807
ISDYNVOLMsgCount_Cnt_M_u08	9
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	21514
ISDYNVOLMsgLenValidCount_Cnt_M_u16	54028
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	834
ISDYNVOLMsgTimer_mS_M_u32	3616612864
IgnOnTimer_mS_M_u32	2495373824
IgnTimeOff_Sec_M_u32	2572574475
ManVehSpd_Kph_M_f32	619.645874
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	113
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	69
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	460247552
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	222
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1865331200
PrevISDATBSI412MsgDLCError_Cnt_M_u08	50
PrevISDATBSI412MsgRxTime_MSec_M_u32	3105202688
PrevISDATBSI432MsgDLCError_Cnt_M_u08	44
PrevISDATBSI432MsgRxTime_MSec_M_u32	3403088384
PrevISDATDIRAMsgTxTime_MSec_M_u32	3121193472
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	201
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3130257920
PrevISDYNAASMsgDLCError_Cnt_M_u08	31
PrevISDYNAASMsgRxTime_MSec_M_u32	2736726528
PrevISDYNABRMsgDLCError_Cnt_M_u08	219
PrevISDYNABRMsgRxTime_MSec_M_u32	301228544
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	107
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3052675584
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	113
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3565289984
PrevISDYNVOLMsgDLCError_Cnt_M_u08	13
PrevISDYNVOLMsgRxTime_MSec_M_u32	2915213824
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	390402560
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	358.191193
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	56323
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	48621
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	9980
VitesseVehicleBVRampValidCount_Cnt_M_u16	33190
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	21573
VitesseVehicleBVSigValidCount_Cnt_M_u16	28119

Name	Input Value
VitesseVehicleBV_Kph_M_f32	118.250397
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	58111
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	41290
VitesseVehiculeRoues_Kph_M_f32	134.418304
k_AASNTCEnableTimeout_mS_u16	34700
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	36628
k_AASNodeTimeout_mS_u16	16621
k_ABSNodeTimeout_mS_u16	63595
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	11657
k_ANGLEVOLANTSigValidThresh_Cnt_u16	57368
k_AngleVolantInvalidThresh_Cnt_u16	35687
k_AngleVolantValidThresh_Cnt_u16	61242
k_BSI552MsgTimeout_mS_u16	54617
k_BSINTCEnableTimeout_mS_u16	56158
k_BSINodeAbsentDiag_Cnt_str.Threshold	64457
k_BSINodeAbsentDiag_Cnt_str.PStep	9601
k_BSINodeAbsentDiag_Cnt_str.NStep	524
k_BSINodeAbsentTimeout_mS_u16	32932
k_BSINodeTimeout_mS_u16	51499
k_BattOvHi_Volt_f32	10.4924002
k_BattOvLo_Volt_f32	14.1803999
k_BattUvHi_Volt_f32	17.3157005
k_BattUvLo_Volt_f32	1.90999997
k_CAVNTCEnableTimeout_mS_u16	57984
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	63000
k_CAVNodeTimeout_mS_u16	43739
k_CMM388MsgTimeout_mS_u16	16399
k_CMM388NTCEnableTimeout_mS_u16	32299
k_CMMNTCEnableTimeout_mS_u16	23937
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	46438
k_CONSANGLECPKMax_HwDeg_f32	202.478607
k_CONSANGLECPKMin_HwDeg_f32	-572.344177
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	9727
k_CONSANGLECPKSigValidThresh_Cnt_u16	9290
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	41027
k_CPKVehicleSpeedValidThresh_Cnt_u16	27746
k_CityParkInputInvalidThresh_Cnt_u16	29623
k_CityParkInputValidThresh_Cnt_u16	52437
k_ComputerRazGCTSigValidThresh_Cnt_u16	9471
k_CptTemporelSigValidThresh_Cnt_u16	8837
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	64838
k_DMDFCTCPKSigValidThresh_Cnt_u16	34985
k_DMDFCTCPKValidCount_Cnt_u16	8987
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	8285
k_DMDRELAXECPKSigValidThresh_Cnt_u16	29912
k_DMDRelaxeConsistentThresh_Cnt_u16	40494
k_DateValidThresh_Cnt_u16	37095
k_DefaultVehSpd_Kph_f32	52.1413994
k_DiagMuxOnAbsentTimeout_mS_u16	25427
k_EMNodeTimeout_mS_u16	45180
k_ESPNTCEnableTimeout_mS_u16	62502
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	20526
k_EtatMTSigInvalidThresh_Cnt_u16	30992
k_EtatMTSigValidThresh_Cnt_u16	42602
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	40142
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	64877
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	18894
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	8134
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	29836
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	1691
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	4899

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	42290
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	6410
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	29905
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	24615
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	56138
k_ISDATDIRASentDiag_Cnt_str.Threshold	6549
k_ISDATDIRASentDiag_Cnt_str.PStep	63930
k_ISDATDIRASentDiag_Cnt_str.NStep	24627
k_ISDATDIRASentTimeout_mS_u16	41725
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	61855
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	8556
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	60626
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	15073
k_ISDYNAASChkSumValidThresh_Cnt_u16	54011
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	4744
k_ISDYNAASMsgCountValidThresh_Cnt_u16	49083
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	53189
k_ISDYNAASMsgLenValidThresh_Cnt_u16	34001
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	55520
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	53844
k_ISDYNABRChkSumValidThresh_Cnt_u16	44087
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	29267
k_ISDYNABRMsgCountValidThresh_Cnt_u16	39525
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	34370
k_ISDYNABRMsgLenValidThresh_Cnt_u16	33169
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	13300
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	49127
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	5104
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	7164
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	51916
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	35742
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	21106
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	60826
k_ISDYNVOLChkSumValidThresh_Cnt_u16	25873
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	12782
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	2783
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	34008
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	24982
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	31917
k_IgnOnTimeout_mS_u16	36022
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	235.960205
k_PowerCutVehSpdLowThresh_Kph_f32	62.9054985
k_PowerCutVehSpdLowTimeout_mS_u16	27800
k_VBattMaxAAS_Volt_f32	19.7401009
k_VBattMaxBSI_Volt_f32	23.1615009
k_VBattMaxCAV_Volt_f32	20.0104008
k_VBattMaxCMM388_Volt_f32	22.6382008
k_VBattMaxCMM_Volt_f32	3.16219997
k_VBattMaxESP_Volt_f32	24.0172005
k_VBattMinAAS_Volt_f32	24.1926003
k_VBattMinBSI_Volt_f32	24.0172005
k_VBattMinCAV_Volt_f32	7.20760012
k_VBattMinCMM388_Volt_f32	12.2482996
k_VBattMinCMM_Volt_f32	3.15939999
k_VBattMinESP_Volt_f32	3.16219997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	56649
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	1775
k_VitesseVehicleBVRampValidThresh_Cnt_u16	37476
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	41072
k_VitesseVehicleBVSigValidThresh_Cnt_u16	21766
k_VitesseVehicleBVSpeedPassThresh_kph_f32	599.54718
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	51210
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	28980
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2402828800
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	55763
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1813852160
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	113
target_SrlComInput_Per1_Batt_Volt_f32.value	6.47020006
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3596694016
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	2
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.714429975
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	171
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1488347648
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	25
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1605730816
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2122621440
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	121
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1025753600
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	596828672
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3117548032
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	201
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2279678464
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	50
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	67
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	68
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	132
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	188
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	198
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	202
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	244
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	50
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	897368576
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	51
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	92
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	106
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	186
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2290180608
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2063630848
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1162846720
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	24
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	36
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	86
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	104
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	157
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	167
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	170
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1932571136
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2158
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.738950849
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	130754
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	174.5923

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	24877		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1813852160	1813852160	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	44685	44685	✔
CONSANGLECPK_HwDeg_M_f32	-73.5083008	-73.5083008 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1813852160	1813852160	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1813852160	1813852160	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1813852160	1813852160	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1813852160	1813852160	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1813852160	1813852160	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1813852160	1813852160	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1813852160	1813852160	✔
ESPNTCEnableTimer_mS_M_u32	1813852160	1813852160	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1813852160	1813852160	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1121	1121	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	2235	2235	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1813852160	1813852160	✔
ElecIntTimer_mS_M_u32[1]	80	80	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1813852160	1813852160	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDATDIRASentFltAcc_Cnt_M_u16	6549	6549	✔
ISDATDIRASentTimer_mS_M_u32	1813852160	1813852160	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1813852160	1813852160	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	9	9	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1813852160	1813852160	✔
IgnOnTimer_mS_M_u32	2495373824	2495373824	✔
IgnTimeOff_Sec_M_u32	2572574475	2572574475	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	171	171	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1488347648	1488347648	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	25	25	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1605730816	1605730816	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2122621440	2122621440	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	121	121	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1025753600	1025753600	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3121193472	3121193472	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	104	104	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3117548032	3117548032	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	201	201	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2279678464	2279678464	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	50	50	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	897368576	897368576	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	173	173	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2290180608	2290180608	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	167	167	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2063630848	2063630848	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	180	180	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1162846720	1162846720	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1932571136	1932571136	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	358.191193	358.191193	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	118.250397	118.250397	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	134.418304	134.418304	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	44685	44685	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2572574475	2572574475	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-73.5083008	-73.5083008 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.484 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1273728256
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	47416
AASNodeAbsentTimer_mS_M_u32	3516972288
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	43778
ANGLEVOLANTSigValidCount_Cnt_M_u16	48715
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	32801
AngleVolantMsgTimer_mS_M_u32	1273728256
AngleVolantValidCount_Cnt_M_u16	48657
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1118403840
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1098775808
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2291117312
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	212561152
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	36973
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	709242112
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	21448
CAVNodeAbsentTimer_mS_M_u32	235461888
CDD_SrlComVehSpd_Kph_G_f32	461.863312
CMM388NTCEnableTimer_mS_M_u32	1725701376
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1728503040
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	55262
CMMNodeAbsentTimer_mS_M_u32	2150460672
CONSANGLECPKSigInvalidCount_Cnt_M_u16	34855
CONSANGLECPKSigValidCount_Cnt_M_u16	61823
CONSANGLECPK_Cnt_M_u16	30590
CONSANGLECPK_HwDeg_M_f32	-108.874001
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	30590
CPKVehicleSpeedMsgTimer_mS_M_u32	3484323072
CPKVehicleSpeedValidCount_Cnt_M_u16	19801
CityParkInputConsistentCount_Cnt_M_u16	2661

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	51253
CityParkInputMsgTimer_mS_M_u32	1488347648
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	854899968
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	17292
ComputerRazGCTSigInvalidTimer_mS_M_u32	1464294656
ComputerRazGCTSigValidCount_Cnt_M_u16	56102
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	59361
DMDFCTCPKSigValidCount_Cnt_M_u16	46578
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	19500
DMDRELAXECPKSigValidCount_Cnt_M_u16	51957
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	9232
DateInvalidTimer_mS_M_u32	1098775808
DiagMuxOnAbsentTimer_mS_M_u32	2900774144
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	212561152
ESPNTCEnableTimer_mS_M_u32	1453178112
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	11186
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	41
EffacDefaultDiagTimer_mS_M_u32[1]	46
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	101
ElecIntTimer_mS_M_u32[1]	107
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2354064640
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	9330
EtatMTSigValidCount_Cnt_M_u16	10999
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	10065
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	31785
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	24816
ISDAT4V2BSI552MsgTimer_mS_M_u32	4169231616
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	34634
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	43510
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	10999
ISDATBSI3F2MsgTimer_mS_M_u32	3317452032
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	19455
ISDATBSI412MsgLenValidCount_Cnt_M_u16	43036
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	9330
ISDATBSI412MsgTimer_mS_M_u32	3535899904
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	42802
ISDATBSI432MsgLenValidCount_Cnt_M_u16	37382
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	19301
ISDATDIRASentFltAcc_Cnt_M_u16	1417
ISDATDIRASentTimer_mS_M_u32	3484323072
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	42196
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	48657
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	32972
ISDYN2CMMMsgTimer_mS_M_u32	1688190208
ISDYNAASChkSumInvalidCount_Cnt_M_u16	13922
ISDYNAASChkSumValidCount_Cnt_M_u16	47690
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	50428
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	7431
ISDYNAASMsgLenValidCount_Cnt_M_u16	39047
ISDYNAASMsgTimeValidCount_Cnt_M_u16	13922
ISDYNAASMsgTimer_mS_M_u32	2005409024
ISDYNABRChkSumInvalidCount_Cnt_M_u16	26690
ISDYNABRChkSumValidCount_Cnt_M_u16	5555
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	26061
ISDYNABRMsgCountValidCount_Cnt_M_u16	13301
ISDYNABRMsgCount_Cnt_M_u08	0
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	28306
ISDYNABRMsgLenValidCount_Cnt_M_u16	25130
ISDYNABRMsgTimeValidCount_Cnt_M_u16	30590
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	9330

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	5075
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	10999
ISDYNCMM208MsgTimer_mS_M_u32	2259320064
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	9330
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	5075
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	61415
ISDYNCMM388MsgTimer_mS_M_u32	1109236992
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	30973
ISDYNVOLChkSumValidCount_Cnt_M_u16	63189
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	53175
ISDYNVOLMsgCountValidCount_Cnt_M_u16	62024
ISDYNVOLMsgCount_Cnt_M_u08	15
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	36679
ISDYNVOLMsgLenValidCount_Cnt_M_u16	26624
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	55262
ISDYNVOLMsgTimer_mS_M_u32	1676893440
IgnOnTimer_mS_M_u32	3916537088
IgnTimeOff_Sec_M_u32	2769603271
ManVehSpd_Kph_M_f32	321.345306
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	114
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	141
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1796885760
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	248
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3344608512
PrevISDATBSI412MsgDLCError_Cnt_M_u08	234
PrevISDATBSI412MsgRxTime_MSec_M_u32	1902501120
PrevISDATBSI432MsgDLCError_Cnt_M_u08	41
PrevISDATBSI432MsgRxTime_MSec_M_u32	2040642816
PrevISDATDIRAMsgTxTime_MSec_M_u32	1049222400
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	28
PrevISDYN2CMMMsgRxTime_MSec_M_u32	170585344
PrevISDYNAASMsgDLCError_Cnt_M_u08	169
PrevISDYNAASMsgRxTime_MSec_M_u32	3108592896
PrevISDYNABRMsgDLCError_Cnt_M_u08	61
PrevISDYNABRMsgRxTime_MSec_M_u32	1372167424
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	44
PrevISDYNCMM208MsgRxTime_MSec_M_u32	348806400
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	100
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3365977344
PrevISDYNVOLMsgDLCError_Cnt_M_u08	80
PrevISDYNVOLMsgRxTime_MSec_M_u32	2271141120
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2694286592
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	311.563812
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	29405
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	49885
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	46578
VitesseVehicleBVRampValidCount_Cnt_M_u16	39858
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	59799
VitesseVehicleBVSigValidCount_Cnt_M_u16	12960

Name	Input Value
VitesseVehicleBV_Kph_M_f32	269.929199
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	61415
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	10952
VitesseVehiculeRoues_Kph_M_f32	20.1650009
k_AASNTCEnableTimeout_mS_u16	43137
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	32680
k_AASNodeTimeout_mS_u16	14813
k_ABSNodeTimeout_mS_u16	45218
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	13577
k_ANGLEVOLANTSigValidThresh_Cnt_u16	41757
k_AngleVolantInvalidThresh_Cnt_u16	40240
k_AngleVolantValidThresh_Cnt_u16	51253
k_BSI552MsgTimeout_mS_u16	35483
k_BSINTCEnableTimeout_mS_u16	49034
k_BSINodeAbsentDiag_Cnt_str.Threshold	41984
k_BSINodeAbsentDiag_Cnt_str.PStep	38683
k_BSINodeAbsentDiag_Cnt_str.NStep	49594
k_BSINodeAbsentTimeout_mS_u16	17017
k_BSINodeTimeout_mS_u16	19301
k_BattOvHi_Volt_f32	6.81829977
k_BattOvLo_Volt_f32	5.75209999
k_BattUvHi_Volt_f32	31.5
k_BattUvLo_Volt_f32	9.49190044
k_CAVNTCEnableTimeout_mS_u16	34403
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	47262
k_CAVNodeTimeout_mS_u16	45267
k_CMM388MsgTimeout_mS_u16	28728
k_CMM388NTCEnableTimeout_mS_u16	9700
k_CMMNTCEnableTimeout_mS_u16	35746
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	24180
k_CONSANGLECPKMax_HwDeg_f32	309.023285
k_CONSANGLECPKMin_HwDeg_f32	-420.1539
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	9959
k_CONSANGLECPKSigValidThresh_Cnt_u16	41416
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	62427
k_CPKVehicleSpeedValidThresh_Cnt_u16	29694
k_CityParkInputInvalidThresh_Cnt_u16	52416
k_CityParkInputValidThresh_Cnt_u16	2661
k_ComputerRazGCTSigValidThresh_Cnt_u16	44328
k_CptTemporelSigValidThresh_Cnt_u16	6740
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	9618
k_DMDFCTCPKSigValidThresh_Cnt_u16	22826
k_DMDFCTCPKValidCount_Cnt_u16	21781
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	32972
k_DMDRELAXECPKSigValidThresh_Cnt_u16	47389
k_DMDRelaxeConsistentThresh_Cnt_u16	5403
k_DateValidThresh_Cnt_u16	24816
k_DefaultVehSpd_Kph_f32	46.4771996
k_DiagMuxOnAbsentTimeout_mS_u16	61740
k_EMNodeTimeout_mS_u16	25584
k_ESPNTCEnableTimeout_mS_u16	30324
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	44572
k_EtatMTSigInvalidThresh_Cnt_u16	24757
k_EtatMTSigValidThresh_Cnt_u16	36454
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	59962
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	36383
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	46970
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	39123
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	63
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	51539
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	27707

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	15311
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	46726
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	13490
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	6255
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	54344
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	55022
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	9545
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	32801
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	15472
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	40770
k_ISDYNAASChkSumValidThresh_Cnt_u16	36019
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	7373
k_ISDYNAASMsgCountValidThresh_Cnt_u16	10997
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	28822
k_ISDYNAASMsgLenValidThresh_Cnt_u16	65073
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	55493
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	24168
k_ISDYNABRChkSumValidThresh_Cnt_u16	42624
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	18285
k_ISDYNABRMsgCountValidThresh_Cnt_u16	25846
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	20190
k_ISDYNABRMsgLenValidThresh_Cnt_u16	58034
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	37961
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	22321
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	13652
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	42160
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	25090
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	46411
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	32397
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	53334
k_ISDYNVOLChkSumValidThresh_Cnt_u16	36787
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	34203
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	29959
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	14366
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	59299
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	13726
k_IgnOnTimeout_mS_u16	25346
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	213.520706
k_PowerCutVehSpdLowThresh_Kph_f32	36.6847992
k_PowerCutVehSpdLowTimeout_mS_u16	10589
k_VBattMaxAAS_Volt_f32	3.28640008
k_VBattMaxBSI_Volt_f32	24.2821007
k_VBattMaxCAV_Volt_f32	18.8146
k_VBattMaxCMM388_Volt_f32	21.566
k_VBattMaxCMM_Volt_f32	24.7896996
k_VBattMaxESP_Volt_f32	3.31369996
k_VBattMinAAS_Volt_f32	5.10760021
k_VBattMinBSI_Volt_f32	3.31369996
k_VBattMinCAV_Volt_f32	24.9641991
k_VBattMinCMM388_Volt_f32	16.3516998
k_VBattMinCMM_Volt_f32	31.7269001
k_VBattMinESP_Volt_f32	24.7896996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	35403
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	62232
k_VitesseVehicleBVRampValidThresh_Cnt_u16	1719
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	60885
k_VitesseVehicleBVSigValidThresh_Cnt_u16	30162
k_VitesseVehicleBVSpeedPassThresh_kph_f32	85.5194016
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	35528
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	34056
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1098775808
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	44013
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	68495872
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	100
target_SrlComInput_Per1_Batt_Volt_f32.value	3.32710004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2076388608
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	208
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.659334958
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	18
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	92511488
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	140
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1426472192
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2635652352
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	182
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1169915136
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3069058304
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1487977728
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2466471168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	29
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	45
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	133
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	134
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	183
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	190
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	47
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	11566336
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	45
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	53
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	70
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	146
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	210
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	217
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	252
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	248
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1646435584
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	208
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4012195072
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	884464896
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	66
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	82
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	102
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	151
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	158
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	171
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1129622784
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1165
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.807029188
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	559426
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	24.8745003

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	2911		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	68495872	68495872	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	32803	32803	✔
AngleVolantMsgTimer_mS_M_u32	68495872	68495872	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	68495872	68495872	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	68495872	68495872	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	68495872	68495872	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	68495872	68495872	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	68495872	68495872	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	30590	30590	✔
CONSANGLECPK_HwDeg_M_f32	-108.874001	-108.874001 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	30590	30590	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3484323072	3484323072	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	19801	19801	✔
CityParkInputConsistentCount_Cnt_M_u16	2661	2661	✔
CityParkInputInvalidCount_Cnt_M_u16	51255	51255	✔
CityParkInputMsgTimer_mS_M_u32	68495872	68495872	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	68495872	68495872	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	68495872	68495872	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	68495872	68495872	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	68495872	68495872	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	68495872	68495872	✔
ESPNTCEnableTimer_mS_M_u32	68495872	68495872	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	68495872	68495872	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	68495872	68495872	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	46	46	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	68495872	68495872	✔
ElecIntTimer_mS_M_u32[1]	107	107	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	68495872	68495872	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	68495872	68495872	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11170	11170	✔
ISDATDIRASentTimer_mS_M_u32	68495872	68495872	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	0	0	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	68495872	68495872	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	15	15	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	68495872	68495872	✔
IgnOnTimer_mS_M_u32	3916537088	3916537088	✔
IgnTimeOff_Sec_M_u32	2769603271	2769603271	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	15	15	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	18	18	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	92511488	92511488	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	140	140	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1426472192	1426472192	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	75	75	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2635652352	2635652352	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	182	182	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1169915136	1169915136	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1049222400	1049222400	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	51	51	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1487977728	1487977728	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2466471168	2466471168	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	47	47	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	11566336	11566336	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	248	248	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1646435584	1646435584	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	208	208	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4012195072	4012195072	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	172	172	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	884464896	884464896	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1129622784	1129622784	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	311.563812	311.563812	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	269.929199	269.929199	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	20.1650009	20.1650009	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	30590	30590	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2769603271	2769603271	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-108.874001	-108.874001 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.485 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3394247680
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	21610
AASNodeAbsentTimer_mS_M_u32	3387984896
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	51467
ANGLEVOLANTSigValidCount_Cnt_M_u16	52721
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	58287
AngleVolantMsgTimer_mS_M_u32	3394247680
AngleVolantValidCount_Cnt_M_u16	13405
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2312522752
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2136525824
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1289993216
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	3750788096
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	33994
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1639988224
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	27962
CAVNodeAbsentTimer_mS_M_u32	1563962368
CDD_SrlComVehSpd_Kph_G_f32	320.184814
CMM388NTCEnableTimer_mS_M_u32	2948492288
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	3393072128
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	58552
CMMNodeAbsentTimer_mS_M_u32	218790912
CONSANGLECPKSigInvalidCount_Cnt_M_u16	46236
CONSANGLECPKSigValidCount_Cnt_M_u16	63314
CONSANGLECPK_Cnt_M_u16	8533
CONSANGLECPK_HwDeg_M_f32	-132.828506
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	8533
CPKVehicleSpeedMsgTimer_mS_M_u32	185015296
CPKVehicleSpeedValidCount_Cnt_M_u16	18829
CityParkInputConsistentCount_Cnt_M_u16	40801
CityParkInputInvalidCount_Cnt_M_u16	63216

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	92511488
CityParkInputValidCount_Cnt_M_u16	1
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4126444544
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	1390
ComputerRazGCTSigInvalidTimer_mS_M_u32	2608638976
ComputerRazGCTSigValidCount_Cnt_M_u16	28958
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	18412
DMDFCTCPKSigValidCount_Cnt_M_u16	15482
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	3469
DMDRELAXECPKSigValidCount_Cnt_M_u16	53235
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	50401
DateInvalidTimer_mS_M_u32	2136525824
DiagMuxOnAbsentTimer_mS_M_u32	39836672
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	3750788096
ESPNTCEnableTimer_mS_M_u32	1861848064
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	22522
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	3
EffacDefaultDiagTimer_mS_M_u32[1]	6
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	99
ElecIntTimer_mS_M_u32[1]	1001
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3819060224
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	40955
EtatMTSigValidCount_Cnt_M_u16	47917
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	65310
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	32596
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0
ISDAT4V2BSI552MsgTimer_mS_M_u32	4094589952
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	12020
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	38317
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	47917
ISDATBSI3F2MsgTimer_mS_M_u32	2413681664
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	17876
ISDATBSI412MsgLenValidCount_Cnt_M_u16	49214
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	40955
ISDATBSI412MsgTimer_mS_M_u32	231611392
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	50876
ISDATBSI432MsgLenValidCount_Cnt_M_u16	29950
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	14947
ISDATDIRASentFltAcc_Cnt_M_u16	39927
ISDATDIRASentTimer_mS_M_u32	185015296
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	29011
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	13405
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	59691
ISDYN2CMMMsgTimer_mS_M_u32	3438513152
ISDYNAASChkSumInvalidCount_Cnt_M_u16	1260
ISDYNAASChkSumValidCount_Cnt_M_u16	14322
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	35740
ISDYNAASMsgCount_Cnt_M_u08	5
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	52605
ISDYNAASMsgLenValidCount_Cnt_M_u16	31163
ISDYNAASMsgTimeValidCount_Cnt_M_u16	1260
ISDYNAASMsgTimer_mS_M_u32	767192064
ISDYNABRChkSumInvalidCount_Cnt_M_u16	59595
ISDYNABRChkSumValidCount_Cnt_M_u16	48953
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	58027
ISDYNABRMsgCountValidCount_Cnt_M_u16	14065
ISDYNABRMsgCount_Cnt_M_u08	6
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	27995
ISDYNABRMsgLenValidCount_Cnt_M_u16	4433
ISDYNABRMsgTimeValidCount_Cnt_M_u16	8533
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	3155
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	32495

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	47917
ISDYNCMM208MsgTimer_mS_M_u32	30624768
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	3155
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	32495
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	30427
ISDYNCMM388MsgTimer_mS_M_u32	66710528
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	47642
ISDYNVOLChkSumValidCount_Cnt_M_u16	48976
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	26730
ISDYNVOLMsgCountValidCount_Cnt_M_u16	24440
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	49467
ISDYNVOLMsgLenValidCount_Cnt_M_u16	13777
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	58552
ISDYNVOLMsgTimer_mS_M_u32	628665344
IgnOnTimer_mS_M_u32	1576922112
IgnTimeOff_Sec_M_u32	1850943999
ManVehSpd_Kph_M_f32	415.491486
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	115
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	82
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2546195456
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	107
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2088942592
PrevISDATBSI412MsgDLCError_Cnt_M_u08	206
PrevISDATBSI412MsgRxTime_MSec_M_u32	3877710848
PrevISDATBSI432MsgDLCError_Cnt_M_u08	137
PrevISDATBSI432MsgRxTime_MSec_M_u32	367889408
PrevISDATDIRAMsgTxTime_MSec_M_u32	263531520
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	81
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1158806528
PrevISDYNAASMsgDLCError_Cnt_M_u08	254
PrevISDYNAASMsgRxTime_MSec_M_u32	4252412928
PrevISDYNABRMsgDLCError_Cnt_M_u08	233
PrevISDYNABRMsgRxTime_MSec_M_u32	2230709248
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	59
PrevISDYNCMM208MsgRxTime_MSec_M_u32	787721216
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	191
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3840969728
PrevISDYNVOLMsgDLCError_Cnt_M_u08	175
PrevISDYNVOLMsgRxTime_MSec_M_u32	3375770624
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2085362688
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	201.913193
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	41979
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	53945
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	28348
VitesseVehicleBVRampValidCount_Cnt_M_u16	56378
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	41292
VitesseVehicleBVSigValidCount_Cnt_M_u16	1266
VitesseVehicleBV_Kph_M_f32	642.168091

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	30427
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	25849
VitesseVehiculeRoues_Kph_M_f32	26.2220993
k_AASNTCEnableTimeout_mS_u16	23116
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	2968
k_AASNodeTimeout_mS_u16	28089
k_ABSNodeTimeout_mS_u16	12713
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	14647
k_ANGLEVOLANTSigValidThresh_Cnt_u16	23993
k_AngleVolantInvalidThresh_Cnt_u16	31616
k_AngleVolantValidThresh_Cnt_u16	63216
k_BSI552MsgTimeout_mS_u16	20864
k_BSINTCEnableTimeout_mS_u16	56756
k_BSINodeAbsentDiag_Cnt_str.Threshold	16167
k_BSINodeAbsentDiag_Cnt_str.PStep	5399
k_BSINodeAbsentDiag_Cnt_str.NStep	21627
k_BSINodeAbsentTimeout_mS_u16	64679
k_BSINodeTimeout_mS_u16	14947
k_BattOvHi_Volt_f32	29.3516998
k_BattOvLo_Volt_f32	2.55769992
k_BattUvHi_Volt_f32	14.2086
k_BattUvLo_Volt_f32	25.552
k_CAVNTCEnableTimeout_mS_u16	62566
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	5816
k_CAVNodeTimeout_mS_u16	60056
k_CMM388MsgTimeout_mS_u16	12138
k_CMM388NTCEnableTimeout_mS_u16	48742
k_CMMNTCEnableTimeout_mS_u16	33260
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	31221
k_CONSANGLECPKMax_HwDeg_f32	281.263092
k_CONSANGLECPKMin_HwDeg_f32	-69.2686996
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	53723
k_CONSANGLECPKSigValidThresh_Cnt_u16	65529
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	47039
k_CPKVehicleSpeedValidThresh_Cnt_u16	35287
k_CityParkInputInvalidThresh_Cnt_u16	13137
k_CityParkInputValidThresh_Cnt_u16	40801
k_ComputerRazGCTSigValidThresh_Cnt_u16	46426
k_CptTemporelSigValidThresh_Cnt_u16	15507
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	18523
k_DMDFCTCPKSigValidThresh_Cnt_u16	11345
k_DMDFCTCPKValidCount_Cnt_u16	54994
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	59691
k_DMDRELAXECPKSigValidThresh_Cnt_u16	40697
k_DMDRelaxeConsistentThresh_Cnt_u16	767
k_DateValidThresh_Cnt_u16	45952
k_DefaultVehSpd_Kph_f32	37.1414986
k_DiagMuxOnAbsentTimeout_mS_u16	60491
k_EMNodeTimeout_mS_u16	34113
k_ESPNTCEnableTimeout_mS_u16	46390
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	11005
k_EtatMTSigInvalidThresh_Cnt_u16	35698
k_EtatMTSigValidThresh_Cnt_u16	57632
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	4258
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	54196
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	11298
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	24153
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	63186
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	7640
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	56225
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	56227

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	59584
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	47545
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	7491
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	25080
k_ISDATDIRASentDiag_Cnt_str.Threshold	25239
k_ISDATDIRASentDiag_Cnt_str.PStep	16638
k_ISDATDIRASentDiag_Cnt_str.NStep	16248
k_ISDATDIRASentTimeout_mS_u16	19655
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	45813
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58287
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	21314
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	17355
k_ISDYNAASChkSumValidThresh_Cnt_u16	23097
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	48555
k_ISDYNAASMsgCountValidThresh_Cnt_u16	20977
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	8143
k_ISDYNAASMsgLenValidThresh_Cnt_u16	28861
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	23745
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	30169
k_ISDYNABRChkSumValidThresh_Cnt_u16	7247
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	24522
k_ISDYNABRMsgCountValidThresh_Cnt_u16	17904
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	32696
k_ISDYNABRMsgLenValidThresh_Cnt_u16	13050
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	50167
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	18175
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7637
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	14656
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	41995
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	59633
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	13288
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	54479
k_ISDYNVOLChkSumValidThresh_Cnt_u16	9593
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	11839
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	61757
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	5367
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	13609
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	28022
k_IgnOnTimeout_mS_u16	52427
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	196.5112
k_PowerCutVehSpdLowThresh_Kph_f32	255
k_PowerCutVehSpdLowTimeout_mS_u16	18360
k_VBattMaxAAS_Volt_f32	2.84739995
k_VBattMaxBSI_Volt_f32	11.0811005
k_VBattMaxCAV_Volt_f32	6.24639988
k_VBattMaxCMM388_Volt_f32	32
k_VBattMaxCMM_Volt_f32	23.0289001
k_VBattMaxESP_Volt_f32	30.1903
k_VBattMinAAS_Volt_f32	17.8477993
k_VBattMinBSI_Volt_f32	30.1903
k_VBattMinCAV_Volt_f32	18.5739994
k_VBattMinCMM388_Volt_f32	24.8822002
k_VBattMinCMM_Volt_f32	14.4314003
k_VBattMinESP_Volt_f32	23.0289001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	3055
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	8265
k_VitesseVehicleBVRampValidThresh_Cnt_u16	50026
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	55888
k_VitesseVehicleBVSigValidThresh_Cnt_u16	20762
k_VitesseVehicleBVSpeedPassThresh_kph_f32	42.3154984
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	51258
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	63544
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2136525824
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65109
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3632743680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	191

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	19.9652996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2705931264
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	20
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	0
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.947707832
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3519540224
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	221
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3049262080
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	147
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4027067392
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	132
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1218464768
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2273864704
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1958775808
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3628641280
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	23
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	25
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	63
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	167
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	199
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	250
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	252
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	734088192
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	48
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	61
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	144
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	182
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	206
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	218
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	36
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4159368192
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	79
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	593693696
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	172
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1697328128
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	33
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	43
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	62
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	100
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	204
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	219
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1888795648
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	803
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.286005735
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	772562
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	88.6998978
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	25205

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	58287	58287	✔
AngleVolantMsgTimer_mS_M_u32	3632743680	3632743680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	8533	8533	✔
CONSANGLECPK_HwDeg_M_f32	-132.828506	-132.828506 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	8533	8533	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	185015296	185015296	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	18829	18829	✔
CityParkInputConsistentCount_Cnt_M_u16	40801	40801	✔
CityParkInputInvalidCount_Cnt_M_u16	63216	63216	✔
CityParkInputMsgTimer_mS_M_u32	3632743680	3632743680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3632743680	3632743680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3632743680	3632743680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3632743680	3632743680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3632743680	3632743680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3632743680	3632743680	✔
ESPNTCEnableTimer_mS_M_u32	3632743680	3632743680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3632743680	3632743680	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3632743680	3632743680	✔
EffacDefaultDiagTimer_mS_M_u32[1]	6	6	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	3632743680	3632743680	✔
ElecIntTimer_mS_M_u32[1]	1001	1001	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3632743680	3632743680	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	25239	25239	✔
ISDATDIRASentTimer_mS_M_u32	3632743680	3632743680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	5	5	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	6	6	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3632743680	3632743680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3632743680	3632743680	✔
IgnOnTimer_mS_M_u32	1576922112	1576922112	✔
IgnTimeOff_Sec_M_u32	1850943999	1850943999	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	153	153	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3519540224	3519540224	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	221	221	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3049262080	3049262080	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	147	147	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4027067392	4027067392	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	132	132	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1218464768	1218464768	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	263531520	263531520	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	51	51	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1958775808	1958775808	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	131	131	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3628641280	3628641280	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	45	45	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	734088192	734088192	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	36	36	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4159368192	4159368192	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	79	79	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	593693696	593693696	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	172	172	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1697328128	1697328128	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1888795648	1888795648	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	201.913193	201.913193	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	642.168091	642.168091	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	26.2220993	26.2220993	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	8533	8533	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1850943999	1850943999	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-132.828506	-132.828506 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.486 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1478389504
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	17358
AASNodeAbsentTimer_mS_M_u32	2801606400
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	2029
ANGLEVOLANTSigValidCount_Cnt_M_u16	15611
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	59903
AngleVolantMsgTimer_mS_M_u32	1478389504
AngleVolantValidCount_Cnt_M_u16	55413
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	776724224
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2009358080
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	652447488
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	299716352
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	37040
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	4199419648
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	16352
CAVNodeAbsentTimer_mS_M_u32	329662208
CDD_SrlComVehSpd_Kph_G_f32	324.712311
CMM388NTCEnableTimer_mS_M_u32	85163776
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1687437056
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	52773
CMMNodeAbsentTimer_mS_M_u32	4050603776
CONSANGLECPKSigInvalidCount_Cnt_M_u16	48184
CONSANGLECPKSigValidCount_Cnt_M_u16	30678
CONSANGLECPK_Cnt_M_u16	50637
CONSANGLECPK_HwDeg_M_f32	-158.622696
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	50637
CPKVehicleSpeedMsgTimer_mS_M_u32	838430464
CPKVehicleSpeedValidCount_Cnt_M_u16	28622
CityParkInputConsistentCount_Cnt_M_u16	42857

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	60859
CityParkInputMsgTimer_mS_M_u32	3519540224
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	854662912
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	16578
ComputerRazGCTSigInvalidTimer_mS_M_u32	181976832
ComputerRazGCTSigValidCount_Cnt_M_u16	26162
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	60103
DMDFCTCPKSigValidCount_Cnt_M_u16	61661
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	49767
DMDRELAXECPKSigValidCount_Cnt_M_u16	48885
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	57193
DateInvalidTimer_mS_M_u32	2009358080
DiagMuxOnAbsentTimer_mS_M_u32	2666475264
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	299716352
ESPNTCEnableTimer_mS_M_u32	467803904
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	10271
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	9
EffacDefaultDiagTimer_mS_M_u32[1]	81
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	8
ElecIntTimer_mS_M_u32[1]	11
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2091388672
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	47451
EtatMTSigValidCount_Cnt_M_u16	56197
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	25778
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	26576
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	65535
ISDAT4V2BSI552MsgTimer_mS_M_u32	1281576704
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	58866
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	17796
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	56197
ISDATBSI3F2MsgTimer_mS_M_u32	1853173504
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	29265
ISDATBSI412MsgLenValidCount_Cnt_M_u16	22228
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	47451
ISDATBSI412MsgTimer_mS_M_u32	94662400
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	14361
ISDATBSI432MsgLenValidCount_Cnt_M_u16	57619
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	48229
ISDATDIRASentFltAcc_Cnt_M_u16	59305
ISDATDIRASentTimer_mS_M_u32	838430464
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	19923
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	55413
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	49930
ISDYN2CMMMsgTimer_mS_M_u32	1777606400
ISDYNAASChkSumInvalidCount_Cnt_M_u16	47688
ISDYNAASChkSumValidCount_Cnt_M_u16	58615
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	36536
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	60183
ISDYNAASMsgLenValidCount_Cnt_M_u16	35357
ISDYNAASMsgTimeValidCount_Cnt_M_u16	47688
ISDYNAASMsgTimer_mS_M_u32	2065661696
ISDYNABRChkSumInvalidCount_Cnt_M_u16	41516
ISDYNABRChkSumValidCount_Cnt_M_u16	33442
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	56587
ISDYNABRMsgCountValidCount_Cnt_M_u16	41978
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	19963
ISDYNABRMsgLenValidCount_Cnt_M_u16	58841
ISDYNABRMsgTimeValidCount_Cnt_M_u16	50637
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	36685

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	30008
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	56197
ISDYNCMM208MsgTimer_mS_M_u32	4199866112
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	36685
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	30008
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	35067
ISDYNCMM388MsgTimer_mS_M_u32	1449197312
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	9150
ISDYNVOLChkSumValidCount_Cnt_M_u16	38876
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	333
ISDYNVOLMsgCountValidCount_Cnt_M_u16	65507
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	12380
ISDYNVOLMsgLenValidCount_Cnt_M_u16	54874
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	52773
ISDYNVOLMsgTimer_mS_M_u32	1558494976
IgnOnTimer_mS_M_u32	1481965312
IgnTimeOff_Sec_M_u32	1409149472
ManVehSpd_Kph_M_f32	361.193604
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	116
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	219
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1858285312
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	122
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3557199616
PrevISDATBSI412MsgDLCError_Cnt_M_u08	173
PrevISDATBSI412MsgRxTime_MSec_M_u32	1508589312
PrevISDATBSI432MsgDLCError_Cnt_M_u08	21
PrevISDATBSI432MsgRxTime_MSec_M_u32	4144373504
PrevISDATDIRAMsgTxTime_MSec_M_u32	808402688
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	214
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3344486144
PrevISDYNAASMsgDLCError_Cnt_M_u08	206
PrevISDYNAASMsgRxTime_MSec_M_u32	1290452736
PrevISDYNABRMsgDLCError_Cnt_M_u08	28
PrevISDYNABRMsgRxTime_MSec_M_u32	3278700288
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	200
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3967008512
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	190
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1442651904
PrevISDYNVOLMsgDLCError_Cnt_M_u08	204
PrevISDYNVOLMsgRxTime_MSec_M_u32	1202470656
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	841641728
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	418.016602
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	57245
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	63267
VVHTYPE1Count_Cnt_M_u08	6
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	50010
VitesseVehicleBVRampValidCount_Cnt_M_u16	7840
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	49962
VitesseVehicleBVSigValidCount_Cnt_M_u16	56312

Name	Input Value
VitesseVehicleBV_Kph_M_f32	120.219498
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	35067
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	57953
VitesseVehiculeRoues_Kph_M_f32	156.712708
k_AASNTCEnableTimeout_mS_u16	46824
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	65220
k_AASNodeTimeout_mS_u16	9763
k_ABSNodeTimeout_mS_u16	24976
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	36008
k_ANGLEVOLANTSigValidThresh_Cnt_u16	53986
k_AngleVolantInvalidThresh_Cnt_u16	21901
k_AngleVolantValidThresh_Cnt_u16	60859
k_BSI552MsgTimeout_mS_u16	63692
k_BSINTCEnableTimeout_mS_u16	54065
k_BSINodeAbsentDiag_Cnt_str.Threshold	57935
k_BSINodeAbsentDiag_Cnt_str.PStep	21184
k_BSINodeAbsentDiag_Cnt_str.NStep	22229
k_BSINodeAbsentTimeout_mS_u16	32535
k_BSINodeTimeout_mS_u16	48229
k_BattOvHi_Volt_f32	14.5621996
k_BattOvLo_Volt_f32	22.4221001
k_BattUvHi_Volt_f32	12.3205004
k_BattUvLo_Volt_f32	13.2974997
k_CAVNTCEnableTimeout_mS_u16	19801
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	47974
k_CAVNodeTimeout_mS_u16	2628
k_CMM388MsgTimeout_mS_u16	45774
k_CMM388NTCEnableTimeout_mS_u16	62938
k_CMMNTCEnableTimeout_mS_u16	52490
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	37741
k_CONSANGLECPKMax_HwDeg_f32	25.8593006
k_CONSANGLECPKMin_HwDeg_f32	-664.354919
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	30715
k_CONSANGLECPKSigValidThresh_Cnt_u16	4449
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	57361
k_CPKVehicleSpeedValidThresh_Cnt_u16	29256
k_CityParkInputInvalidThresh_Cnt_u16	23194
k_CityParkInputValidThresh_Cnt_u16	42857
k_ComputerRazGCTSigValidThresh_Cnt_u16	27328
k_CptTemporelSigValidThresh_Cnt_u16	26834
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	48379
k_DMDFCTCPKSigValidThresh_Cnt_u16	38105
k_DMDFCTCPKValidCount_Cnt_u16	47768
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	49930
k_DMDRELAXECPKSigValidThresh_Cnt_u16	34144
k_DMDRelaxeConsistentThresh_Cnt_u16	61774
k_DateValidThresh_Cnt_u16	9163
k_DefaultVehSpd_Kph_f32	64.1330032
k_DiagMuxOnAbsentTimeout_mS_u16	48363
k_EMNodeTimeout_mS_u16	7753
k_ESPNTCEnableTimeout_mS_u16	22508
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	41045
k_EtatMTSigInvalidThresh_Cnt_u16	5687
k_EtatMTSigValidThresh_Cnt_u16	30957
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	8552
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	52210
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	17702
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	11203
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	62997
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	64069
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	52586

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	33060
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	57869
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	36001
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	13763
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	65253
k_ISDATDIRASentDiag_Cnt_str.Threshold	19232
k_ISDATDIRASentDiag_Cnt_str.PStep	3193
k_ISDATDIRASentDiag_Cnt_str.NStep	10166
k_ISDATDIRASentTimeout_mS_u16	26168
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	16366
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	59903
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	44488
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	37164
k_ISDYNAASChkSumValidThresh_Cnt_u16	45474
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	19467
k_ISDYNAASMsgCountValidThresh_Cnt_u16	21242
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	3360
k_ISDYNAASMsgLenValidThresh_Cnt_u16	11543
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	62922
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	44161
k_ISDYNABRChkSumValidThresh_Cnt_u16	15583
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	65456
k_ISDYNABRMsgCountValidThresh_Cnt_u16	37118
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	64805
k_ISDYNABRMsgLenValidThresh_Cnt_u16	38687
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	62185
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	1681
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	11854
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	40846
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	30445
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	60411
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	5843
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	29024
k_ISDYNVOLChkSumValidThresh_Cnt_u16	54051
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	63824
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	64662
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	19047
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	23953
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	19945
k_IgnOnTimeout_mS_u16	31084
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	164.5242
k_PowerCutVehSpdLowThresh_Kph_f32	125.000702
k_PowerCutVehSpdLowTimeout_mS_u16	40612
k_VBattMaxAAS_Volt_f32	11.2524004
k_VBattMaxBSI_Volt_f32	3.88919997
k_VBattMaxCAV_Volt_f32	16.1051998
k_VBattMaxCMM388_Volt_f32	1.29369998
k_VBattMaxCMM_Volt_f32	26.6336002
k_VBattMaxESP_Volt_f32	11.9490995
k_VBattMinAAS_Volt_f32	3.85949993
k_VBattMinBSI_Volt_f32	11.9490995
k_VBattMinCAV_Volt_f32	18.7931995
k_VBattMinCMM388_Volt_f32	25.4566002
k_VBattMinCMM_Volt_f32	15.7845001
k_VBattMinESP_Volt_f32	26.6336002
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	40192
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	29618
k_VitesseVehicleBVRampValidThresh_Cnt_u16	61517
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	18140
k_VitesseVehicleBVSigValidThresh_Cnt_u16	46654
k_VitesseVehicleBVSpeedPassThresh_kph_f32	128.3022
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	12000
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	17062
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2009358080
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60393
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1305159680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	190
target_SrlComInput_Per1_Batt_Volt_f32.value	2.42370009
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2679312128
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	241
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.447082847
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2767650560
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2173607680
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2604023552
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2582503168
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	632651520
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	188
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3868008192
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	247
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2222243584
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	9
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	35
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	55
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	146
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	147
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	172
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	220
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	1
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3028999936
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	14
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	26
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	34
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	102
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	127
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	153
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	45
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2123235072
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2225446656
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	164
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2278375168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	38
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	45
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	92
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	115
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	140
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	189
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3218116352
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1632
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.914798498
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	204458
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	205.207993

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	3119		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	59903	59903	✔
AngleVolantMsgTimer_mS_M_u32	1305159680	1305159680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	50637	50637	✔
CONSANGLECPK_HwDeg_M_f32	-158.622696	-158.622696 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	50637	50637	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	838430464	838430464	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	28622	28622	✔
CityParkInputConsistentCount_Cnt_M_u16	42857	42857	✔
CityParkInputInvalidCount_Cnt_M_u16	60859	60859	✔
CityParkInputMsgTimer_mS_M_u32	1305159680	1305159680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1305159680	1305159680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1305159680	1305159680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1305159680	1305159680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1305159680	1305159680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1305159680	1305159680	✔
ESPNTCEnableTimer_mS_M_u32	1305159680	1305159680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1305159680	1305159680	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	9	9	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	81	81	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1305159680	1305159680	✔
ElecIntTimer_mS_M_u32[1]	11	11	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1305159680	1305159680	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	19232	19232	✔
ISDATDIRASentTimer_mS_M_u32	1305159680	1305159680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1305159680	1305159680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1305159680	1305159680	✔
IgnOnTimer_mS_M_u32	1481965312	1481965312	✔
IgnTimeOff_Sec_M_u32	1409149472	1409149472	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	129	129	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2767650560	2767650560	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	158	158	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2173607680	2173607680	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	164	164	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2604023552	2604023552	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	59	59	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2582503168	2582503168	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	808402688	808402688	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	188	188	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3868008192	3868008192	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	247	247	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2222243584	2222243584	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	1	1	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3028999936	3028999936	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	45	45	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2123235072	2123235072	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2225446656	2225446656	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	164	164	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2278375168	2278375168	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3218116352	3218116352	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	418.016602	418.016602	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	6	6	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	120.219498	120.219498	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	156.712708	156.712708	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	50637	50637	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1409149472	1409149472	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-158.622696	-158.622696 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStart	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.487 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2210362880
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	8877
AASNodeAbsentTimer_mS_M_u32	2917361152
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	28754
ANGLEVOLANTSigValidCount_Cnt_M_u16	1511
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	13338
AngleVolantMsgTimer_mS_M_u32	2210362880
AngleVolantValidCount_Cnt_M_u16	51002
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3270977024
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1754113536
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	334501376
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	1778570752
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	41481
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1672517120
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	23290
CAVNodeAbsentTimer_mS_M_u32	4100457984
CDD_SrlComVehSpd_Kph_G_f32	218.952194
CMM388NTCEnableTimer_mS_M_u32	1696613888
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	966657536
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	53738
CMMNodeAbsentTimer_mS_M_u32	2471286272
CONSANGLECPKSigInvalidCount_Cnt_M_u16	61042
CONSANGLECPKSigValidCount_Cnt_M_u16	12375
CONSANGLECPK_Cnt_M_u16	57970
CONSANGLECPK_HwDeg_M_f32	114.170601
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	57970
CPKVehicleSpeedMsgTimer_mS_M_u32	573470208
CPKVehicleSpeedValidCount_Cnt_M_u16	7286

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	10846
CityParkInputInvalidCount_Cnt_M_u16	28775
CityParkInputMsgTimer_mS_M_u32	2767650560
CityParkInputValidCount_Cnt_M_u16	3
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3657917952
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	64465
ComputerRazGCTSigInvalidTimer_mS_M_u32	4174415360
ComputerRazGCTSigValidCount_Cnt_M_u16	20995
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	43331
DMDFCTCPKSigValidCount_Cnt_M_u16	60352
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	43236
DMDRELAXECPKSigValidCount_Cnt_M_u16	59385
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	35039
DateInvalidTimer_mS_M_u32	1754113536
DiagMuxOnAbsentTimer_mS_M_u32	3796710912
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1778570752
ESPNTCEnableTimer_mS_M_u32	590636544
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	43195
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	10
EffacDefaultDiagTimer_mS_M_u32[1]	20
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	7
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3298989568
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	47431
EtatMTSigValidCount_Cnt_M_u16	63368
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	23812
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	51305
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	35574
ISDAT4V2BSI552MsgTimer_mS_M_u32	1383126528
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	42754
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	52492
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	63368
ISDATBSI3F2MsgTimer_mS_M_u32	196818432
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	36581
ISDATBSI412MsgLenValidCount_Cnt_M_u16	58910
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	47431
ISDATBSI412MsgTimer_mS_M_u32	321746432
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	25614
ISDATBSI432MsgLenValidCount_Cnt_M_u16	19935
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	14699
ISDATDIRASentFltAcc_Cnt_M_u16	51103
ISDATDIRASentTimer_mS_M_u32	573470208
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	57952
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	51002
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	60538
ISDYN2CMMMsgTimer_mS_M_u32	16672256
ISDYNAASChkSumInvalidCount_Cnt_M_u16	10047
ISDYNAASChkSumValidCount_Cnt_M_u16	23541
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	28785
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	62805
ISDYNAASMsgLenValidCount_Cnt_M_u16	11523
ISDYNAASMsgTimeValidCount_Cnt_M_u16	10047
ISDYNAASMsgTimer_mS_M_u32	855393792
ISDYNABRChkSumInvalidCount_Cnt_M_u16	46357
ISDYNABRChkSumValidCount_Cnt_M_u16	59507
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	35574
ISDYNABRMsgCountValidCount_Cnt_M_u16	60140
ISDYNABRMsgCount_Cnt_M_u08	5
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	1321
ISDYNABRMsgLenValidCount_Cnt_M_u16	45646
ISDYNABRMsgTimeValidCount_Cnt_M_u16	57970

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	50825
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	23433
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	63368
ISDYNCMM208MsgTimer_mS_M_u32	3269207552
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	50825
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	23433
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	19880
ISDYNCMM388MsgTimer_mS_M_u32	2268579328
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	20448
ISDYNVOLChkSumValidCount_Cnt_M_u16	26693
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	64945
ISDYNVOLMsgCountValidCount_Cnt_M_u16	22190
ISDYNVOLMsgCount_Cnt_M_u08	1
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	50180
ISDYNVOLMsgLenValidCount_Cnt_M_u16	50890
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	53738
ISDYNVOLMsgTimer_mS_M_u32	850167296
IgnOnTimer_mS_M_u32	1364968960
IgnTimeOff_Sec_M_u32	2573371081
ManVehSpd_Kph_M_f32	454.984009
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	117
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	1
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	170
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3268490752
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	6
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1485248000
PrevISDATBSI412MsgDLCError_Cnt_M_u08	98
PrevISDATBSI412MsgRxTime_MSec_M_u32	1972962816
PrevISDATBSI432MsgDLCError_Cnt_M_u08	93
PrevISDATBSI432MsgRxTime_MSec_M_u32	566781440
PrevISDATDIRAMsgTxTime_MSec_M_u32	46990848
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	204
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2542818816
PrevISDYNAASMsgDLCError_Cnt_M_u08	226
PrevISDYNAASMsgRxTime_MSec_M_u32	4204430848
PrevISDYNABRMsgDLCError_Cnt_M_u08	205
PrevISDYNABRMsgRxTime_MSec_M_u32	1880344064
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	233
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2147452416
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	123
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2699257344
PrevISDYNVOLMsgDLCError_Cnt_M_u08	186
PrevISDYNVOLMsgRxTime_MSec_M_u32	4032169472
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	630945280
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	67.2305984
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	44995
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	32241
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	14476
VitesseVehicleBVRampValidCount_Cnt_M_u16	15226
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	29339

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	23792
VitesseVehicleBV_Kph_M_f32	517.079773
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	19880
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	54837
VitesseVehiculeRoues_Kph_M_f32	590.913818
k_AASNTCEnableTimeout_mS_u16	15137
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	20557
k_AASNodeTimeout_mS_u16	61681
k_ABSNodeTimeout_mS_u16	43240
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	25185
k_ANGLEVOLANTSigValidThresh_Cnt_u16	29810
k_AngleVolantInvalidThresh_Cnt_u16	22641
k_AngleVolantValidThresh_Cnt_u16	28775
k_BSI552MsgTimeout_mS_u16	65268
k_BSINTCEnableTimeout_mS_u16	62150
k_BSINodeAbsentDiag_Cnt_str.Threshold	2821
k_BSINodeAbsentDiag_Cnt_str.PStep	58097
k_BSINodeAbsentDiag_Cnt_str.NStep	36849
k_BSINodeAbsentTimeout_mS_u16	54482
k_BSINodeTimeout_mS_u16	14699
k_BattOvHi_Volt_f32	28.4678993
k_BattOvLo_Volt_f32	27.4540997
k_BattUvHi_Volt_f32	15.7056999
k_BattUvLo_Volt_f32	5.25260019
k_CAVNTCEnableTimeout_mS_u16	18829
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	32872
k_CAVNodeTimeout_mS_u16	13390
k_CMM388MsgTimeout_mS_u16	54701
k_CMM388NTCEnableTimeout_mS_u16	15497
k_CMMNTCEnableTimeout_mS_u16	20922
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	62225
k_CONSANGLECPKMax_HwDeg_f32	197.311203
k_CONSANGLECPKMin_HwDeg_f32	-300.617401
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	32936
k_CONSANGLECPKSigValidThresh_Cnt_u16	18741
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	64295
k_CPKVehicleSpeedValidThresh_Cnt_u16	11008
k_CityParkInputInvalidThresh_Cnt_u16	50123
k_CityParkInputValidThresh_Cnt_u16	10846
k_ComputerRazGCTSigValidThresh_Cnt_u16	53400
k_CptTemporelSigValidThresh_Cnt_u16	6946
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	47145
k_DMDFCTCPKSigValidThresh_Cnt_u16	42318
k_DMDFCTCPKValidCount_Cnt_u16	50257
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	60538
k_DMDRELAXECPKSigValidThresh_Cnt_u16	64055
k_DMDRelaxeConsistentThresh_Cnt_u16	61037
k_DateValidThresh_Cnt_u16	35574
k_DefaultVehSpd_Kph_f32	226.205399
k_DiagMuxOnAbsentTimeout_mS_u16	62744
k_EMNodeTimeout_mS_u16	19519
k_ESPNTCEnableTimeout_mS_u16	17110
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	27737
k_EtatMTSigInvalidThresh_Cnt_u16	17652
k_EtatMTSigValidThresh_Cnt_u16	61842
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	21282
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	30787
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	34087
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	22927
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	16217
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	50953

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	10267
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	61868
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	13874
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	56822
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	26448
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	17963
k_ISDATDIRASentDiag_Cnt_str.Threshold	47720
k_ISDATDIRASentDiag_Cnt_str.PStep	17950
k_ISDATDIRASentDiag_Cnt_str.NStep	21543
k_ISDATDIRASentTimeout_mS_u16	39153
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	59152
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	13338
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	45378
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	59413
k_ISDYNAASChkSumValidThresh_Cnt_u16	23411
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	15862
k_ISDYNAASMsgCountValidThresh_Cnt_u16	56812
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	17465
k_ISDYNAASMsgLenValidThresh_Cnt_u16	44053
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	43962
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	33175
k_ISDYNABRChkSumValidThresh_Cnt_u16	17724
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	21769
k_ISDYNABRMsgCountValidThresh_Cnt_u16	54750
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	17642
k_ISDYNABRMsgLenValidThresh_Cnt_u16	23483
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	7197
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	2791
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	36590
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	61616
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	9042
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	63719
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	21791
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	36280
k_ISDYNVOLChkSumValidThresh_Cnt_u16	27953
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	14632
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	19095
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	13859
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	41316
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	1180
k_IgnOnTimeout_mS_u16	42388
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	237.532104
k_PowerCutVehSpdLowThresh_Kph_f32	204.102402
k_PowerCutVehSpdLowTimeout_mS_u16	29677
k_VBattMaxAAS_Volt_f32	28.7113991
k_VBattMaxBSI_Volt_f32	31.7873001
k_VBattMaxCAV_Volt_f32	2.00349998
k_VBattMaxCMM388_Volt_f32	23.2994995
k_VBattMaxCMM_Volt_f32	18.7903004
k_VBattMaxESP_Volt_f32	9.44439983
k_VBattMinAAS_Volt_f32	4.06479979
k_VBattMinBSI_Volt_f32	9.44439983
k_VBattMinCAV_Volt_f32	6.92679977
k_VBattMinCMM388_Volt_f32	9.1729002
k_VBattMinCMM_Volt_f32	29.2625999
k_VBattMinESP_Volt_f32	18.7903004
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	38874
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	55427
k_VitesseVehicleBVRampValidThresh_Cnt_u16	12465
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	23365
k_VitesseVehicleBVSigValidThresh_Cnt_u16	37343
k_VitesseVehicleBVSpeedPassThresh_kph_f32	616.536377
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	36346
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	26472
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1754113536
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	2073
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1490897664
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	123
target_SrlComInput_Per1_Batt_Volt_f32.value	19.9293995
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1199674880
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	76
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.0268030744
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1937098240
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1143924224
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2646083072
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	168
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2282825216
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	188368384
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	112
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	791897600
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	71
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	4227630592
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	44
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	62
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	74
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	114
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	195
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	205
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	218
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	9
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3963233792
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	4
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	57
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	71
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	175
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	181
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	193
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	89
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	45139456
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1458169344
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	195
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4092790272
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	16
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	31
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	81
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	83
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	111
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	173
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	187
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	231
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1026102784
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3685
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.220257074
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	1032573
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	195.730606
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	61965

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1490897664	1490897664	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1490897664	1490897664	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1490897664	1490897664	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1490897664	1490897664	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1490897664	1490897664	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	57970	57970	✔
CONSANGLECPK_HwDeg_M_f32	114.170601	114.170601 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1490897664	1490897664	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1490897664	1490897664	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1490897664	1490897664	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1490897664	1490897664	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1490897664	1490897664	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1490897664	1490897664	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1490897664	1490897664	✔
ESPNTCEnableTimer_mS_M_u32	1490897664	1490897664	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1490897664	1490897664	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	10	10	✔
EffacDefaultDiagTimer_mS_M_u32[1]	20	20	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	1490897664	1490897664	✔
ElecIntTimer_mS_M_u32[1]	7	7	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1490897664	1490897664	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDATDIRASentFltAcc_Cnt_M_u16	47720	47720	✔
ISDATDIRASentTimer_mS_M_u32	1490897664	1490897664	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	5	5	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1490897664	1490897664	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	1	1	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1490897664	1490897664	✔
IgnOnTimer_mS_M_u32	1490897664	1490897664	✔
IgnTimeOff_Sec_M_u32	2573371081	2573371081	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	1	1	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	67	67	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1937098240	1937098240	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	51	51	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1143924224	1143924224	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	167	167	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2646083072	2646083072	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	168	168	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2282825216	2282825216	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	46990848	46990848	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	112	112	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	791897600	791897600	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	71	71	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	4227630592	4227630592	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	9	9	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3963233792	3963233792	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	89	89	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	45139456	45139456	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	108	108	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1458169344	1458169344	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	195	195	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4092790272	4092790272	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1026102784	1026102784	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	67.2305984	67.2305984	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	517.079773	517.079773	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	590.913818	590.913818	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	57970	57970	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2573371081	2573371081	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	114.170601	114.170601 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.488 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2981650688
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	44780
AASNodeAbsentTimer_mS_M_u32	4010578176
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	63487
ANGLEVOLANTSigValidCount_Cnt_M_u16	39167
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	28325
AngleVolantMsgTimer_mS_M_u32	2981650688
AngleVolantValidCount_Cnt_M_u16	39368
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2932953344
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	940429568
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	195461376
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3295559936
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	65242
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	3194290432
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	32903
CAVNodeAbsentTimer_mS_M_u32	1979625728
CDD_SrlComVehSpd_Kph_G_f32	279.489197
CMM388NTCEnableTimer_mS_M_u32	1423307008
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4267487488
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	46711
CMMNodeAbsentTimer_mS_M_u32	4035985664
CONSANGLECPKSigInvalidCount_Cnt_M_u16	44192
CONSANGLECPKSigValidCount_Cnt_M_u16	34991
CONSANGLECPK_Cnt_M_u16	40542
CONSANGLECPK_HwDeg_M_f32	563.245605
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	40542
CPKVehicleSpeedMsgTimer_mS_M_u32	1382768896
CPKVehicleSpeedValidCount_Cnt_M_u16	26683
CityParkInputConsistentCount_Cnt_M_u16	92
CityParkInputInvalidCount_Cnt_M_u16	58176
CityParkInputMsgTimer_mS_M_u32	1937098240
CityParkInputValidCount_Cnt_M_u16	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4204826880
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	45952
ComputerRazGCTSigInvalidTimer_mS_M_u32	2865049856
ComputerRazGCTSigValidCount_Cnt_M_u16	23917
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	43180
DMDFCTCPKSigValidCount_Cnt_M_u16	58100
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	5705
DMDRELAXECPKSigValidCount_Cnt_M_u16	47817
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	53593
DateInvalidTimer_mS_M_u32	940429568
DiagMuxOnAbsentTimer_mS_M_u32	4245627136
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3295559936
ESPNTCEnableTimer_mS_M_u32	320442624
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	33731
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	707
EffacDefaultDiagTimer_mS_M_u32[1]	1235
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	979
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	3817799936
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	1376
EtatMTSigValidCount_Cnt_M_u16	23643
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	10474
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	34937
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	23890
ISDAT4V2BSI552MsgTimer_mS_M_u32	1126449408
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	57774
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	41297
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	23643
ISDATBSI3F2MsgTimer_mS_M_u32	3099926784
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	33543
ISDATBSI412MsgLenValidCount_Cnt_M_u16	28443
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	1376
ISDATBSI412MsgTimer_mS_M_u32	997089536
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	36875
ISDATBSI432MsgLenValidCount_Cnt_M_u16	9303
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	59700
ISDATDIRASentFltAcc_Cnt_M_u16	3736
ISDATDIRASentTimer_mS_M_u32	1382768896
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	54932
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	39368
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	31495
ISDYN2CMMMsgTimer_mS_M_u32	565940480
ISDYNAASChkSumInvalidCount_Cnt_M_u16	26934
ISDYNAASChkSumValidCount_Cnt_M_u16	44246
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	14883
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	56694
ISDYNAASMsgLenValidCount_Cnt_M_u16	63533
ISDYNAASMsgTimeValidCount_Cnt_M_u16	26934
ISDYNAASMsgTimer_mS_M_u32	1531048192
ISDYNABRChkSumInvalidCount_Cnt_M_u16	61237
ISDYNABRChkSumValidCount_Cnt_M_u16	55004
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	55825
ISDYNABRMsgCountValidCount_Cnt_M_u16	39921
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	1147
ISDYNABRMsgLenValidCount_Cnt_M_u16	40650
ISDYNABRMsgTimeValidCount_Cnt_M_u16	40542
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	57651
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	23643
ISDYNCMM208MsgTimer_mS_M_u32	2200064256

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	57651
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	15998
ISDYNCMM388MsgTimer_mS_M_u32	2895081728
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	49238
ISDYNVOLChkSumValidCount_Cnt_M_u16	6373
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	58210
ISDYNVOLMsgCountValidCount_Cnt_M_u16	55850
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	38376
ISDYNVOLMsgLenValidCount_Cnt_M_u16	44888
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	46711
ISDYNVOLMsgTimer_mS_M_u32	1831940352
IgnOnTimer_mS_M_u32	3726864640
IgnTimeOff_Sec_M_u32	0
ManVehSpd_Kph_M_f32	503.986298
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	118
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	45
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1803755776
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	107
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1507950848
PrevISDATBSI412MsgDLCError_Cnt_M_u08	124
PrevISDATBSI412MsgRxTime_MSec_M_u32	4134252800
PrevISDATBSI432MsgDLCError_Cnt_M_u08	239
PrevISDATBSI432MsgRxTime_MSec_M_u32	1734185216
PrevISDATDIRAMsgTxTime_MSec_M_u32	516927744
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	143
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1371914496
PrevISDYNAASMsgDLCError_Cnt_M_u08	77
PrevISDYNAASMsgRxTime_MSec_M_u32	1298608384
PrevISDYNABRMsgDLCError_Cnt_M_u08	18
PrevISDYNABRMsgRxTime_MSec_M_u32	1643868416
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	92
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2436378880
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	69
PrevISDYNCMM388MsgRxTime_MSec_M_u32	369922304
PrevISDYNVOLMsgDLCError_Cnt_M_u08	80
PrevISDYNVOLMsgRxTime_MSec_M_u32	3124015360
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1009017088
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	350.07959
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	58924
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	15715
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	0
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	45009
VitesseVehicleBVRampValidCount_Cnt_M_u16	26824
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	21796
VitesseVehicleBVSigValidCount_Cnt_M_u16	63460
VitesseVehicleBV_Kph_M_f32	331.158905
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	15998
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	59030

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	216.055801
k_AASNTCEnableTimeout_mS_u16	4177
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	2703
k_AASNodeTimeout_mS_u16	58467
k_ABSNodeTimeout_mS_u16	32189
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	41234
k_ANGLEVOLANTSigValidThresh_Cnt_u16	48286
k_AngleVolantInvalidThresh_Cnt_u16	52385
k_AngleVolantValidThresh_Cnt_u16	58176
k_BSI552MsgTimeout_mS_u16	10329
k_BSINTCEnableTimeout_mS_u16	50147
k_BSINodeAbsentDiag_Cnt_str.Threshold	13537
k_BSINodeAbsentDiag_Cnt_str.PStep	61147
k_BSINodeAbsentDiag_Cnt_str.NStep	49162
k_BSINodeAbsentTimeout_mS_u16	27773
k_BSINodeTimeout_mS_u16	59700
k_BattOvHi_Volt_f32	19.2329006
k_BattOvLo_Volt_f32	19.5764999
k_BattUvHi_Volt_f32	18.4813995
k_BattUvLo_Volt_f32	7.4066
k_CAVNTCEnableTimeout_mS_u16	28622
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	18493
k_CAVNodeTimeout_mS_u16	19212
k_CMM388MsgTimeout_mS_u16	38380
k_CMM388NTCEnableTimeout_mS_u16	53592
k_CMMNTCEnableTimeout_mS_u16	49542
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	2
k_CONSANGLECPKMax_HwDeg_f32	51.6711998
k_CONSANGLECPKMin_HwDeg_f32	-104.829102
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	42366
k_CONSANGLECPKSigValidThresh_Cnt_u16	36246
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	7617
k_CPKVehicleSpeedValidThresh_Cnt_u16	55990
k_CityParkInputInvalidThresh_Cnt_u16	6931
k_CityParkInputValidThresh_Cnt_u16	92
k_ComputerRazGCTSigValidThresh_Cnt_u16	15596
k_CptTemporelSigValidThresh_Cnt_u16	36623
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	60283
k_DMDFCTCPKSigValidThresh_Cnt_u16	50634
k_DMDFCTCPKValidCount_Cnt_u16	47106
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	31495
k_DMDRELAXECPKSigValidThresh_Cnt_u16	21391
k_DMDRelaxeConsistentThresh_Cnt_u16	52973
k_DateValidThresh_Cnt_u16	23890
k_DefaultVehSpd_Kph_f32	82.847702
k_DiagMuxOnAbsentTimeout_mS_u16	32364
k_EMNodeTimeout_mS_u16	1849
k_ESPNTCEnableTimeout_mS_u16	14579
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	46122
k_EtatMTSigInvalidThresh_Cnt_u16	31640
k_EtatMTSigValidThresh_Cnt_u16	63359
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	49616
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	58412
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	21505
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	15879
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	48746
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	27291
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	47076
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	44272
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	43423
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	48082

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	37254
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	17972
k_ISDATDIRASentDiag_Cnt_str.Threshold	52110
k_ISDATDIRASentDiag_Cnt_str.PStep	20589
k_ISDATDIRASentDiag_Cnt_str.NStep	35392
k_ISDATDIRASentTimeout_mS_u16	45985
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	14213
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	28325
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	40367
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	22069
k_ISDYNAASChkSumValidThresh_Cnt_u16	32220
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	49425
k_ISDYNAASMsgCountValidThresh_Cnt_u16	49905
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	53705
k_ISDYNAASMsgLenValidThresh_Cnt_u16	17143
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	14022
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	50993
k_ISDYNABRChkSumValidThresh_Cnt_u16	7680
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	58842
k_ISDYNABRMsgCountValidThresh_Cnt_u16	50458
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	23927
k_ISDYNABRMsgLenValidThresh_Cnt_u16	27331
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	44637
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	25792
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	59116
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	41254
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	57087
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	49151
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	5400
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	37518
k_ISDYNVOLChkSumValidThresh_Cnt_u16	58850
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	50812
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	16496
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	65228
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	52935
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	2144
k_IgnOnTimeout_mS_u16	47866
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	135.367706
k_PowerCutVehSpdLowThresh_Kph_f32	179.656799
k_PowerCutVehSpdLowTimeout_mS_u16	38381
k_VBattMaxAAS_Volt_f32	19.4997997
k_VBattMaxBSI_Volt_f32	1.31299996
k_VBattMaxCAV_Volt_f32	4.07180023
k_VBattMaxCMM388_Volt_f32	9.59980011
k_VBattMaxCMM_Volt_f32	6.59520006
k_VBattMaxESP_Volt_f32	29.8311005
k_VBattMinAAS_Volt_f32	2.9151001
k_VBattMinBSI_Volt_f32	29.8311005
k_VBattMinCAV_Volt_f32	16.3398991
k_VBattMinCMM388_Volt_f32	8.89260006
k_VBattMinCMM_Volt_f32	8.40380001
k_VBattMinESP_Volt_f32	6.59520006
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	52519
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	48363
k_VitesseVehicleBVRampValidThresh_Cnt_u16	19042
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	16357
k_VitesseVehicleBVSigValidThresh_Cnt_u16	3545
k_VitesseVehicleBVSpeedPassThresh_kph_f32	318.014893
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	59271
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	7422
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	940429568
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	21877
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2683494912
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	69
target_SrlComInput_Per1_Batt_Volt_f32.value	14.7699003
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2532442368
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	151
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.686177611
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	192
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1607823616
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	30
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3123319040
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	46
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3121524992
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	216
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1199788288
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1250423040
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	152
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2870776064
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	126
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1363226880
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	34
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	140
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	166
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	189
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	197
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	209
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	214
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	153
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4278735104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	2
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	3
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	29
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	52
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	59
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	130
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	222
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1579446528
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	771297536
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	133
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1667084544
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	71
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	135
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	142
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	177
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	226
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	234
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3019604224
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3789
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.253303319
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	540931
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	20.0221996
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	51022

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2683494912	2683494912	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	28327	28327	✔
AngleVolantMsgTimer_mS_M_u32	2683494912	2683494912	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	40542	40542	✔
CONSANGLECPK_HwDeg_M_f32	563.245605	563.245605 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	40542	40542	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1382768896	1382768896	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	26683	26683	✔
CityParkInputConsistentCount_Cnt_M_u16	92	92	✔
CityParkInputInvalidCount_Cnt_M_u16	58176	58176	✔
CityParkInputMsgTimer_mS_M_u32	2683494912	2683494912	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2683494912	2683494912	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2683494912	2683494912	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2683494912	2683494912	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2683494912	2683494912	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2683494912	2683494912	✔
ESPNTCEnableTimer_mS_M_u32	2683494912	2683494912	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2683494912	2683494912	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2683494912	2683494912	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1235	1235	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	2683494912	2683494912	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	979	979	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2683494912	2683494912	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDATDIRASentFltAcc_Cnt_M_u16	52110	52110	✔
ISDATDIRASentTimer_mS_M_u32	2683494912	2683494912	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2683494912	2683494912	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2683494912	2683494912	✔
IgnOnTimer_mS_M_u32	3726864640	3726864640	✔
IgnTimeOff_Sec_M_u32	0	0	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	192	192	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1607823616	1607823616	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	30	30	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3123319040	3123319040	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	46	46	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3121524992	3121524992	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	216	216	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1199788288	1199788288	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	516927744	516927744	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	152	152	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2870776064	2870776064	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	126	126	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1363226880	1363226880	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	153	153	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4278735104	4278735104	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1579446528	1579446528	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	31	31	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	771297536	771297536	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	133	133	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1667084544	1667084544	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3019604224	3019604224	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	350.07959	350.07959	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	0	0	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	331.158905	331.158905	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	216.055801	216.055801	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	40542	40542	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	0	0	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	563.245605	563.245605 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	82.847702	82.847702	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.489 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2235146240
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	65436
AASNodeAbsentTimer_mS_M_u32	2583498752
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	36452
ANGLEVOLANTSigValidCount_Cnt_M_u16	34341
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	58481
AngleVolantMsgTimer_mS_M_u32	2235146240
AngleVolantValidCount_Cnt_M_u16	46473
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1571737600
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1408847872
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	1475297280
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4237819904
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	42451
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	1504952320
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	6989
CAVNodeAbsentTimer_mS_M_u32	4121341952
CDD_SrlComVehSpd_Kph_G_f32	498.916809
CMM388NTCEnableTimer_mS_M_u32	3324047360
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1418506240
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	43322
CMMNodeAbsentTimer_mS_M_u32	2150760448
CONSANGLECPKSigInvalidCount_Cnt_M_u16	58242
CONSANGLECPKSigValidCount_Cnt_M_u16	27155
CONSANGLECPK_Cnt_M_u16	42246
CONSANGLECPK_HwDeg_M_f32	779.593201
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	42246
CPKVehicleSpeedMsgTimer_mS_M_u32	790667264
CPKVehicleSpeedValidCount_Cnt_M_u16	32696
CityParkInputConsistentCount_Cnt_M_u16	53709
CityParkInputInvalidCount_Cnt_M_u16	2592

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	1607823616
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3342929920
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	16864
ComputerRazGCTSigInvalidTimer_mS_M_u32	2438148096
ComputerRazGCTSigValidCount_Cnt_M_u16	16026
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	27100
DMDFCTCPKSigValidCount_Cnt_M_u16	46533
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56198
DMDRELAXECPKSigValidCount_Cnt_M_u16	51399
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	39255
DateInvalidTimer_mS_M_u32	1408847872
DiagMuxOnAbsentTimer_mS_M_u32	1848991744
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4237819904
ESPNTCEnableTimer_mS_M_u32	2715160576
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	19479
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	8
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	305512448
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	44418
EtatMTSigValidCount_Cnt_M_u16	29519
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	5796
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	4789
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	16043
ISDAT4V2BSI552MsgTimer_mS_M_u32	3631611904
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	10264
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	21485
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	29519
ISDATBSI3F2MsgTimer_mS_M_u32	2467520512
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	14604
ISDATBSI412MsgLenValidCount_Cnt_M_u16	40849
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	44418
ISDATBSI412MsgTimer_mS_M_u32	1075290112
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	27774
ISDATBSI432MsgLenValidCount_Cnt_M_u16	47707
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	54598
ISDATDIRASentFltAcc_Cnt_M_u16	62746
ISDATDIRASentTimer_mS_M_u32	790667264
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	21604
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	46473
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	7883
ISDYN2CMMMsgTimer_mS_M_u32	2112884736
ISDYNAASChkSumInvalidCount_Cnt_M_u16	30910
ISDYNAASChkSumValidCount_Cnt_M_u16	2207
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	120
ISDYNAASMsgCount_Cnt_M_u08	12
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	32896
ISDYNAASMsgLenValidCount_Cnt_M_u16	60185
ISDYNAASMsgTimeValidCount_Cnt_M_u16	30910
ISDYNAASMsgTimer_mS_M_u32	1658646528
ISDYNABRChkSumInvalidCount_Cnt_M_u16	22595
ISDYNABRChkSumValidCount_Cnt_M_u16	7179
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	21037
ISDYNABRMsgCountValidCount_Cnt_M_u16	26446
ISDYNABRMsgCount_Cnt_M_u08	9
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	2033
ISDYNABRMsgLenValidCount_Cnt_M_u16	21442
ISDYNABRMsgTimeValidCount_Cnt_M_u16	42246
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	47707

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	29519
ISDYNCMM208MsgTimer_mS_M_u32	1690030080
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	47707
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	8039
ISDYNCMM388MsgTimer_mS_M_u32	2230611968
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	96
ISDYNVOLChkSumValidCount_Cnt_M_u16	4465
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	4538
ISDYNVOLMsgCountValidCount_Cnt_M_u16	10275
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	59816
ISDYNVOLMsgLenValidCount_Cnt_M_u16	14361
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	43322
ISDYNVOLMsgTimer_mS_M_u32	4195299328
IgnOnTimer_mS_M_u32	1077440512
IgnTimeOff_Sec_M_u32	3185135999
ManVehSpd_Kph_M_f32	309.348114
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	119
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	71
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4074332160
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	149
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	423510016
PrevISDATBSI412MsgDLCError_Cnt_M_u08	241
PrevISDATBSI412MsgRxTime_MSec_M_u32	1751101440
PrevISDATBSI432MsgDLCError_Cnt_M_u08	102
PrevISDATBSI432MsgRxTime_MSec_M_u32	3037335552
PrevISDATDIRAMsgTxTime_MSec_M_u32	2134093824
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	202
PrevISDYN2CMMMsgRxTime_MSec_M_u32	311525376
PrevISDYNAASMsgDLCError_Cnt_M_u08	137
PrevISDYNAASMsgRxTime_MSec_M_u32	2976722944
PrevISDYNABRMsgDLCError_Cnt_M_u08	170
PrevISDYNABRMsgRxTime_MSec_M_u32	347107328
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	236
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1778003968
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	82
PrevISDYNCMM388MsgRxTime_MSec_M_u32	620564480
PrevISDYNVOLMsgDLCError_Cnt_M_u08	220
PrevISDYNVOLMsgRxTime_MSec_M_u32	2164568064
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2515902464
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	128.188293
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	48734
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	29559
VVHTYPE1Count_Cnt_M_u08	0
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	13679
VitesseVehicleBVRampValidCount_Cnt_M_u16	50504
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	19189
VitesseVehicleBVSigValidCount_Cnt_M_u16	15734
VitesseVehicleBV_Kph_M_f32	131.110107

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	8039
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	25056
VitesseVehiculeRoues_Kph_M_f32	157.2229
k_AASNTCEnableTimeout_mS_u16	56109
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	16180
k_AASNodeTimeout_mS_u16	32375
k_ABSNodeTimeout_mS_u16	28329
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	5481
k_ANGLEVOLANTSigValidThresh_Cnt_u16	52614
k_AngleVolantInvalidThresh_Cnt_u16	27005
k_AngleVolantValidThresh_Cnt_u16	2592
k_BSI552MsgTimeout_mS_u16	26775
k_BSINTCEnableTimeout_mS_u16	12534
k_BSINodeAbsentDiag_Cnt_str.Threshold	33043
k_BSINodeAbsentDiag_Cnt_str.PStep	12643
k_BSINodeAbsentDiag_Cnt_str.NStep	27671
k_BSINodeAbsentTimeout_mS_u16	19177
k_BSINodeTimeout_mS_u16	54598
k_BattOvHi_Volt_f32	28.7101994
k_BattOvLo_Volt_f32	3.27259994
k_BattUvHi_Volt_f32	18.0788994
k_BattUvLo_Volt_f32	16.1056995
k_CAVNTCEnableTimeout_mS_u16	7286
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	7211
k_CAVNodeTimeout_mS_u16	47166
k_CMM388MsgTimeout_mS_u16	19100
k_CMM388NTCEnableTimeout_mS_u16	18520
k_CMMNTCEnableTimeout_mS_u16	59536
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	50588
k_CONSANGLECPKMax_HwDeg_f32	505.132202
k_CONSANGLECPKMin_HwDeg_f32	-306.508514
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	60007
k_CONSANGLECPKSigValidThresh_Cnt_u16	27872
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	51805
k_CPKVehicleSpeedValidThresh_Cnt_u16	44543
k_CityParkInputInvalidThresh_Cnt_u16	52393
k_CityParkInputValidThresh_Cnt_u16	53709
k_ComputerRazGCTSigValidThresh_Cnt_u16	36446
k_CptTemporelSigValidThresh_Cnt_u16	691
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	21233
k_DMDFCTCPKSigValidThresh_Cnt_u16	57026
k_DMDFCTCPKValidCount_Cnt_u16	6747
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	7883
k_DMDRELAXECPKSigValidThresh_Cnt_u16	36852
k_DMDRelaxeConsistentThresh_Cnt_u16	5594
k_DateValidThresh_Cnt_u16	16043
k_DefaultVehSpd_Kph_f32	108.342796
k_DiagMuxOnAbsentTimeout_mS_u16	48348
k_EMNodeTimeout_mS_u16	30647
k_ESPNTCEnableTimeout_mS_u16	41481
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	18724
k_EtatMTSigInvalidThresh_Cnt_u16	65306
k_EtatMTSigValidThresh_Cnt_u16	1570
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	55856
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	48605
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	43742
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	46861
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	41122
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	53840
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	39155
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	50320

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	28610
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	7338
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	17999
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	13445
k_ISDATDIRASentDiag_Cnt_str.Threshold	26593
k_ISDATDIRASentDiag_Cnt_str.PStep	61445
k_ISDATDIRASentDiag_Cnt_str.NStep	10573
k_ISDATDIRASentTimeout_mS_u16	47871
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	58514
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	58481
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	25557
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	9027
k_ISDYNAASChkSumValidThresh_Cnt_u16	9995
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	40237
k_ISDYNAASMsgCountValidThresh_Cnt_u16	62030
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	135
k_ISDYNAASMsgLenValidThresh_Cnt_u16	45755
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	65294
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	6095
k_ISDYNABRChkSumValidThresh_Cnt_u16	11808
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	61651
k_ISDYNABRMsgCountValidThresh_Cnt_u16	11732
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46138
k_ISDYNABRMsgLenValidThresh_Cnt_u16	38679
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	15883
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	37538
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	57693
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	5166
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	55652
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	4389
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	54424
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	58999
k_ISDYNVOLChkSumValidThresh_Cnt_u16	5948
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	42988
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	12111
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	28990
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	52235
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	62849
k_IgnOnTimeout_mS_u16	7475
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	203.2827
k_PowerCutVehSpdLowThresh_Kph_f32	238.415497
k_PowerCutVehSpdLowTimeout_mS_u16	47705
k_VBattMaxAAS_Volt_f32	31.0755997
k_VBattMaxBSI_Volt_f32	13.5129004
k_VBattMaxCAV_Volt_f32	1.01489997
k_VBattMaxCMM388_Volt_f32	7.18300009
k_VBattMaxCMM_Volt_f32	32
k_VBattMaxESP_Volt_f32	10.4911003
k_VBattMinAAS_Volt_f32	22.4030991
k_VBattMinBSI_Volt_f32	10.4911003
k_VBattMinCAV_Volt_f32	15.0963001
k_VBattMinCMM388_Volt_f32	6.56519985
k_VBattMinCMM_Volt_f32	26.6909008
k_VBattMinESP_Volt_f32	32
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	11180
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	18209
k_VitesseVehicleBVRampValidThresh_Cnt_u16	56506
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	40049
k_VitesseVehicleBVSigValidThresh_Cnt_u16	56662
k_VitesseVehicleBVSpeedPassThresh_kph_f32	627.544495
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	58957
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	166
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1408847872
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	82

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	30.1760006
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1141686272
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	23
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.460389018
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	108
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	52588544
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	203
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2393149440
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	85
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1769385984
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	83
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	3684225024
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	755691520
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	200
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2781679616
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	207
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2380214272
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	32
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	70
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	163
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	165
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	174
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	192
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	151638016
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	68
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	104
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	119
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	131
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	150
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	188
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	189
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	216
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	70610944
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	196
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	792170496
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1770631168
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	68
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	107
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	131
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	143
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	201
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	210
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	229
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	242
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4075831296
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3988
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.586493015
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	4597
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	247.569107
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	8952

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	58481	58481	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	42246	42246	✔
CONSANGLECPK_HwDeg_M_f32	779.593201	779.593201 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	42246	42246	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	790667264	790667264	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	32696	32696	✔
CityParkInputConsistentCount_Cnt_M_u16	53709	53709	✔
CityParkInputInvalidCount_Cnt_M_u16	2594	2594	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	4	4	✔
ElecIntTimer_mS_M_u32[1]	8	8	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	26593	26593	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	12	12	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	9	9	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	1077440512	1077440512	✔
IgnTimeOff_Sec_M_u32	3185135999	3185135999	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	108	108	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	52588544	52588544	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	203	203	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2393149440	2393149440	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	85	85	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1769385984	1769385984	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	83	83	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	3684225024	3684225024	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2134093824	2134093824	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	200	200	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2781679616	2781679616	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	207	207	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2380214272	2380214272	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	99	99	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	151638016	151638016	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	37	37	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	70610944	70610944	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	196	196	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	792170496	792170496	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	77	77	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1770631168	1770631168	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4075831296	4075831296	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	128.188293	128.188293	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	0	0	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	131.110107	131.110107	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	157.2229	157.2229	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	42246	42246	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3185135999	3185135999	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	779.593201	779.593201 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.490 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2725372672
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	56650
AASNodeAbsentTimer_mS_M_u32	4259812096
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	62192
ANGLEVOLANTSigValidCount_Cnt_M_u16	31598
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	49867
AngleVolantMsgTimer_mS_M_u32	2725372672
AngleVolantValidCount_Cnt_M_u16	22531
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2849133312
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	284349184
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2295399168
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	769049344
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	10403
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	897811200
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	55477
CAVNodeAbsentTimer_mS_M_u32	426423040
CDD_SrlComVehSpd_Kph_G_f32	401.431396
CMM388NTCEnableTimer_mS_M_u32	1627124480
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	347648768
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	40877
CMMNodeAbsentTimer_mS_M_u32	2332607232
CONSANGLECPKSigInvalidCount_Cnt_M_u16	39575
CONSANGLECPKSigValidCount_Cnt_M_u16	46756
CONSANGLECPK_Cnt_M_u16	37323
CONSANGLECPK_HwDeg_M_f32	-364.979492
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37323
CPKVehicleSpeedMsgTimer_mS_M_u32	12378880
CPKVehicleSpeedValidCount_Cnt_M_u16	30939
CityParkInputConsistentCount_Cnt_M_u16	4919
CityParkInputInvalidCount_Cnt_M_u16	51005

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	52588544
CityParkInputValidCount_Cnt_M_u16	2
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2249954048
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	9854
ComputerRazGCTSigInvalidTimer_mS_M_u32	2556769024
ComputerRazGCTSigValidCount_Cnt_M_u16	16592
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	38921
DMDFCTCPKSigValidCount_Cnt_M_u16	50190
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	5002
DMDRELAXECPKSigValidCount_Cnt_M_u16	48008
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	3352
DateInvalidTimer_mS_M_u32	284349184
DiagMuxOnAbsentTimer_mS_M_u32	2256446208
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	769049344
ESPNTCEnableTimer_mS_M_u32	2321322752
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	38615
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	87
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	21
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2482864896
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	49112
EtatMTSigValidCount_Cnt_M_u16	3633
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	2353
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	50366
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	16732
ISDAT4V2BSI552MsgTimer_mS_M_u32	2453455616
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	8597
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	24022
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	3633
ISDATBSI3F2MsgTimer_mS_M_u32	266642176
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	4024
ISDATBSI412MsgLenValidCount_Cnt_M_u16	23529
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	49112
ISDATBSI412MsgTimer_mS_M_u32	1775756032
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	26081
ISDATBSI432MsgLenValidCount_Cnt_M_u16	23563
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	52938
ISDATDIRASentFltAcc_Cnt_M_u16	48974
ISDATDIRASentTimer_mS_M_u32	12378880
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	31665
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	22531
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	62780
ISDYN2CMMMsgTimer_mS_M_u32	3725497088
ISDYNAASChkSumInvalidCount_Cnt_M_u16	31204
ISDYNAASChkSumValidCount_Cnt_M_u16	47617
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	62262
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	13596
ISDYNAASMsgLenValidCount_Cnt_M_u16	50449
ISDYNAASMsgTimeValidCount_Cnt_M_u16	31204
ISDYNAASMsgTimer_mS_M_u32	2059924224
ISDYNABRChkSumInvalidCount_Cnt_M_u16	34517
ISDYNABRChkSumValidCount_Cnt_M_u16	52026
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	27031
ISDYNABRMsgCountValidCount_Cnt_M_u16	6644
ISDYNABRMsgCount_Cnt_M_u08	3
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	43338
ISDYNABRMsgLenValidCount_Cnt_M_u16	30103
ISDYNABRMsgTimeValidCount_Cnt_M_u16	37323
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	43890
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	2127

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	3633
ISDYNCMM208MsgTimer_mS_M_u32	145445632
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	43890
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	2127
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	4713
ISDYNCMM388MsgTimer_mS_M_u32	3531698944
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	15357
ISDYNVOLChkSumValidCount_Cnt_M_u16	47242
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	39023
ISDYNVOLMsgCountValidCount_Cnt_M_u16	25844
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	16932
ISDYNVOLMsgLenValidCount_Cnt_M_u16	34449
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	40877
ISDYNVOLMsgTimer_mS_M_u32	1311847168
IgnOnTimer_mS_M_u32	2964681472
IgnTimeOff_Sec_M_u32	2420941020
ManVehSpd_Kph_M_f32	174.709702
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	120
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	190
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2291311360
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	190
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1088684800
PrevISDATBSI412MsgDLCError_Cnt_M_u08	251
PrevISDATBSI412MsgRxTime_MSec_M_u32	3846157056
PrevISDATBSI432MsgDLCError_Cnt_M_u08	44
PrevISDATBSI432MsgRxTime_MSec_M_u32	549491456
PrevISDATDIRAMsgTxTime_MSec_M_u32	4039357184
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	58
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2984919808
PrevISDYNAASMsgDLCError_Cnt_M_u08	18
PrevISDYNAASMsgRxTime_MSec_M_u32	538391296
PrevISDYNABRMsgDLCError_Cnt_M_u08	90
PrevISDYNABRMsgRxTime_MSec_M_u32	323842816
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	52
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1785737984
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	155
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1558680320
PrevISDYNVOLMsgDLCError_Cnt_M_u08	1
PrevISDYNVOLMsgRxTime_MSec_M_u32	1867559680
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1614668544
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	21.4689999
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	29570
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	9207
VVHTYPE1Count_Cnt_M_u08	1
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	37455
VitesseVehicleBVRampValidCount_Cnt_M_u16	45700
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	16701
VitesseVehicleBVSigValidCount_Cnt_M_u16	55675
VitesseVehicleBV_Kph_M_f32	174.224594

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	4713
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	39614
VitesseVehiculeRoues_Kph_M_f32	397.1362
k_AASNTCEnableTimeout_mS_u16	19286
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	9986
k_AASNodeTimeout_mS_u16	759
k_ABSNodeTimeout_mS_u16	64930
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	55072
k_ANGLEVOLANTSigValidThresh_Cnt_u16	36490
k_AngleVolantInvalidThresh_Cnt_u16	22181
k_AngleVolantValidThresh_Cnt_u16	51005
k_BSI552MsgTimeout_mS_u16	8857
k_BSINTCEnableTimeout_mS_u16	63609
k_BSINodeAbsentDiag_Cnt_str.Threshold	28392
k_BSINodeAbsentDiag_Cnt_str.PStep	49975
k_BSINodeAbsentDiag_Cnt_str.NStep	2138
k_BSINodeAbsentTimeout_mS_u16	28515
k_BSINodeTimeout_mS_u16	52938
k_BattOvHi_Volt_f32	12.3050003
k_BattOvLo_Volt_f32	31.5
k_BattUvHi_Volt_f32	17.8560009
k_BattUvLo_Volt_f32	31.5
k_CAVNTCEnableTimeout_mS_u16	26683
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	52763
k_CAVNodeTimeout_mS_u16	3171
k_CMM388MsgTimeout_mS_u16	64586
k_CMM388NTCEnableTimeout_mS_u16	62230
k_CMMNTCEnableTimeout_mS_u16	49197
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	24458
k_CONSANGLECPKMax_HwDeg_f32	413.06369
k_CONSANGLECPKMin_HwDeg_f32	-321.589386
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	45417
k_CONSANGLECPKSigValidThresh_Cnt_u16	31166
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	14149
k_CPKVehicleSpeedValidThresh_Cnt_u16	15583
k_CityParkInputInvalidThresh_Cnt_u16	16803
k_CityParkInputValidThresh_Cnt_u16	4919
k_ComputerRazGCTSigValidThresh_Cnt_u16	34499
k_CptTemporelSigValidThresh_Cnt_u16	59780
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	51274
k_DMDFCTCPKSigValidThresh_Cnt_u16	54423
k_DMDFCTCPKValidCount_Cnt_u16	60171
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	62780
k_DMDRELAXECPKSigValidThresh_Cnt_u16	45441
k_DMDRelaxeConsistentThresh_Cnt_u16	14287
k_DateValidThresh_Cnt_u16	16732
k_DefaultVehSpd_Kph_f32	141.591797
k_DiagMuxOnAbsentTimeout_mS_u16	8777
k_EMNodeTimeout_mS_u16	61944
k_ESPNTCEnableTimeout_mS_u16	13441
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	62706
k_EtatMTSigInvalidThresh_Cnt_u16	44624
k_EtatMTSigValidThresh_Cnt_u16	10485
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	5068
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	34949
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	3076
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	34998
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	35767
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	21484
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	62594
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	20844

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	27669
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	47839
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	15793
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	20047
k_ISDATDIRASentDiag_Cnt_str.Threshold	40598
k_ISDATDIRASentDiag_Cnt_str.PStep	346
k_ISDATDIRASentDiag_Cnt_str.NStep	15969
k_ISDATDIRASentTimeout_mS_u16	20129
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	45608
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	49867
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	7965
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	9685
k_ISDYNAASChkSumValidThresh_Cnt_u16	43578
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	34967
k_ISDYNAASMsgCountValidThresh_Cnt_u16	30964
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	40457
k_ISDYNAASMsgLenValidThresh_Cnt_u16	30251
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	6642
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	29104
k_ISDYNABRChkSumValidThresh_Cnt_u16	56957
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	18339
k_ISDYNABRMsgCountValidThresh_Cnt_u16	97
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	32429
k_ISDYNABRMsgLenValidThresh_Cnt_u16	46551
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	27580
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	1718
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	39621
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	56786
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	4592
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	55918
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	18389
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	29559
k_ISDYNVOLChkSumValidThresh_Cnt_u16	24808
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	5976
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	41326
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	25764
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	62461
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	62682
k_IgnOnTimeout_mS_u16	48963
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	123.272003
k_PowerCutVehSpdLowThresh_Kph_f32	25.8736
k_PowerCutVehSpdLowTimeout_mS_u16	24018
k_VBattMaxAAS_Volt_f32	1.21249998
k_VBattMaxBSI_Volt_f32	6.26959991
k_VBattMaxCAV_Volt_f32	23.4288998
k_VBattMaxCMM388_Volt_f32	2.66849995
k_VBattMaxCMM_Volt_f32	8.04769993
k_VBattMaxESP_Volt_f32	31.7385006
k_VBattMinAAS_Volt_f32	4.51030016
k_VBattMinBSI_Volt_f32	31.7385006
k_VBattMinCAV_Volt_f32	26.5272999
k_VBattMinCMM388_Volt_f32	12.7398996
k_VBattMinCMM_Volt_f32	28.3852997
k_VBattMinESP_Volt_f32	8.04769993
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	50394
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	45627
k_VitesseVehicleBVRampValidThresh_Cnt_u16	14191
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	6026
k_VitesseVehicleBVSigValidThresh_Cnt_u16	21660
k_VitesseVehicleBVSpeedPassThresh_kph_f32	595.61438
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	30645
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	63594
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	284349184
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8816
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3873991680
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	155

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	6.17439985
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	444105472
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	33
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.827499449
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	179
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2415358720
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	39
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	502338304
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	89
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4261065472
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	113
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1477726976
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1413346048
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	243
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	444044032
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	173
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3535876864
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	42
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	60
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	170
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	178
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	224
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	226
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	68
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3552662272
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	16
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	41
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	89
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	134
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	180
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	194
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	147
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2562618112
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	72
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1211634432
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	124
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	163689216
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	27
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	52
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	78
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	192
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	195
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	207
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	215
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	4224582400
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3405
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.747774839
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	682982
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	127.662903
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	11700

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	49867	49867	✔
AngleVolantMsgTimer_mS_M_u32	3873991680	3873991680	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	37323	37323	✔
CONSANGLECPK_HwDeg_M_f32	-364.979492	-364.979492 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	37323	37323	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	12378880	12378880	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	30939	30939	✔
CityParkInputConsistentCount_Cnt_M_u16	4919	4919	✔
CityParkInputInvalidCount_Cnt_M_u16	51005	51005	✔
CityParkInputMsgTimer_mS_M_u32	3873991680	3873991680	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3873991680	3873991680	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3873991680	3873991680	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3873991680	3873991680	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3873991680	3873991680	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3873991680	3873991680	✔
ESPNTCEnableTimer_mS_M_u32	3873991680	3873991680	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3873991680	3873991680	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3873991680	3873991680	✔
EffacDefaultDiagTimer_mS_M_u32[1]	87	87	✔
ElecIntCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	3873991680	3873991680	✔
ElecIntTimer_mS_M_u32[1]	21	21	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3873991680	3873991680	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDATDIRASentFltAcc_Cnt_M_u16	40598	40598	✔
ISDATDIRASentTimer_mS_M_u32	3873991680	3873991680	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	3	3	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3873991680	3873991680	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3873991680	3873991680	✔
IgnOnTimer_mS_M_u32	2964681472	2964681472	✔
IgnTimeOff_Sec_M_u32	2420941020	2420941020	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	179	179	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2415358720	2415358720	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	39	39	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	502338304	502338304	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	89	89	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4261065472	4261065472	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	113	113	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1477726976	1477726976	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4039357184	4039357184	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	243	243	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	444044032	444044032	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	173	173	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3535876864	3535876864	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	68	68	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3552662272	3552662272	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	147	147	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2562618112	2562618112	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	72	72	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1211634432	1211634432	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	124	124	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	163689216	163689216	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4224582400	4224582400	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	21.4689999	21.4689999	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	1	1	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	174.224594	174.224594	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	397.1362	397.1362	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	37323	37323	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2420941020	2420941020	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-364.979492	-364.979492 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.491 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1939151360
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	50443
AASNodeAbsentTimer_mS_M_u32	2482244096
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	15896
ANGLEVOLANTSigValidCount_Cnt_M_u16	21856
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	22664
AngleVolantMsgTimer_mS_M_u32	1939151360
AngleVolantValidCount_Cnt_M_u16	32609
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2872297984
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2547141120
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2767698432
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	4242962944
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	10495
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2296396288
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	59210
CAVNodeAbsentTimer_mS_M_u32	3052055040
CDD_SrlComVehSpd_Kph_G_f32	283.154388
CMM388NTCEnableTimer_mS_M_u32	3023497728
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2080418304
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	16416
CMMNodeAbsentTimer_mS_M_u32	760248832
CONSANGLECPKSigInvalidCount_Cnt_M_u16	21027
CONSANGLECPKSigValidCount_Cnt_M_u16	61116
CONSANGLECPK_Cnt_M_u16	47431
CONSANGLECPK_HwDeg_M_f32	-225.234406
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	47431
CPKVehicleSpeedMsgTimer_mS_M_u32	1152653824
CPKVehicleSpeedValidCount_Cnt_M_u16	16031
CityParkInputConsistentCount_Cnt_M_u16	7621
CityParkInputInvalidCount_Cnt_M_u16	60082

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	2415358720
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3411544576
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	47471
ComputerRazGCTSigInvalidTimer_mS_M_u32	1123756544
ComputerRazGCTSigValidCount_Cnt_M_u16	14586
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	43086
DMDFCTCPKSigValidCount_Cnt_M_u16	62719
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	50250
DMDRELAXECPKSigValidCount_Cnt_M_u16	32018
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	16032
DateInvalidTimer_mS_M_u32	2547141120
DiagMuxOnAbsentTimer_mS_M_u32	3933133312
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	4242962944
ESPNTCEnableTimer_mS_M_u32	43321856
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	47973
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	707
EffacDefaultDiagTimer_mS_M_u32[1]	1235
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	979
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3581032960
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	22690
EtatMTSigValidCount_Cnt_M_u16	36438
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	61013
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	44142
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	13589
ISDAT4V2BSI552MsgTimer_mS_M_u32	3887364608
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	48875
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	51943
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	36438
ISDATBSI3F2MsgTimer_mS_M_u32	1715264000
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	37249
ISDATBSI412MsgLenValidCount_Cnt_M_u16	11694
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	22690
ISDATBSI412MsgTimer_mS_M_u32	895687168
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	48516
ISDATBSI432MsgLenValidCount_Cnt_M_u16	15305
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	39179
ISDATDIRASentFltAcc_Cnt_M_u16	55167
ISDATDIRASentTimer_mS_M_u32	1152653824
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	5013
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	32609
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	7349
ISDYN2CMMMsgTimer_mS_M_u32	1333725696
ISDYNAASChkSumInvalidCount_Cnt_M_u16	55101
ISDYNAASChkSumValidCount_Cnt_M_u16	18342
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	14792
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	11797
ISDYNAASMsgLenValidCount_Cnt_M_u16	3829
ISDYNAASMsgTimeValidCount_Cnt_M_u16	55101
ISDYNAASMsgTimer_mS_M_u32	2530404864
ISDYNABRChkSumInvalidCount_Cnt_M_u16	44521
ISDYNABRChkSumValidCount_Cnt_M_u16	12665
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	37924
ISDYNABRMsgCountValidCount_Cnt_M_u16	46029
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	45578
ISDYNABRMsgLenValidCount_Cnt_M_u16	15843
ISDYNABRMsgTimeValidCount_Cnt_M_u16	47431
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	57651

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	36438
ISDYNCMM208MsgTimer_mS_M_u32	849922560
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	57651
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	26671
ISDYNCMM388MsgTimer_mS_M_u32	1436969472
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	34289
ISDYNVOLChkSumValidCount_Cnt_M_u16	266
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	48924
ISDYNVOLMsgCountValidCount_Cnt_M_u16	10829
ISDYNVOLMsgCount_Cnt_M_u08	3
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	11646
ISDYNVOLMsgLenValidCount_Cnt_M_u16	53494
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	16416
ISDYNVOLMsgTimer_mS_M_u32	1368861184
IgnOnTimer_mS_M_u32	2332715520
IgnTimeOff_Sec_M_u32	2180654963
ManVehSpd_Kph_M_f32	67.9023972
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	118
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	6
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	247
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	875747840
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	62
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2294200832
PrevISDATBSI412MsgDLCError_Cnt_M_u08	145
PrevISDATBSI412MsgRxTime_MSec_M_u32	3865815552
PrevISDATBSI432MsgDLCError_Cnt_M_u08	76
PrevISDATBSI432MsgRxTime_MSec_M_u32	3479767552
PrevISDATDIRAMsgTxTime_MSec_M_u32	3554650624
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	114
PrevISDYN2CMMMsgRxTime_MSec_M_u32	514587136
PrevISDYNAASMsgDLCError_Cnt_M_u08	173
PrevISDYNAASMsgRxTime_MSec_M_u32	4091881984
PrevISDYNABRMsgDLCError_Cnt_M_u08	213
PrevISDYNABRMsgRxTime_MSec_M_u32	3275909632
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	103
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3101305344
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	94
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1995704832
PrevISDYNVOLMsgDLCError_Cnt_M_u08	42
PrevISDYNVOLMsgRxTime_MSec_M_u32	3426265600
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1781602816
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	648.76532
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	35555
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	2627
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	41596
VitesseVehicleBVRampValidCount_Cnt_M_u16	53916
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	50993
VitesseVehicleBVSigValidCount_Cnt_M_u16	44857
VitesseVehicleBV_Kph_M_f32	362.275085

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	26671
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	57328
VitesseVehiculeRoues_Kph_M_f32	102.470901
k_AASNTCEnableTimeout_mS_u16	30886
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	52836
k_AASNodeTimeout_mS_u16	27971
k_ABSNodeTimeout_mS_u16	7043
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	9671
k_ANGLEVOLANTSigValidThresh_Cnt_u16	24652
k_AngleVolantInvalidThresh_Cnt_u16	13307
k_AngleVolantValidThresh_Cnt_u16	60082
k_BSI552MsgTimeout_mS_u16	29791
k_BSINTCEnableTimeout_mS_u16	26044
k_BSINodeAbsentDiag_Cnt_str.Threshold	13537
k_BSINodeAbsentDiag_Cnt_str.PStep	61147
k_BSINodeAbsentDiag_Cnt_str.NStep	49162
k_BSINodeAbsentTimeout_mS_u16	45760
k_BSINodeTimeout_mS_u16	39179
k_BattOvHi_Volt_f32	23.4088993
k_BattOvLo_Volt_f32	5.1487999
k_BattUvHi_Volt_f32	20.7840996
k_BattUvLo_Volt_f32	19.4652004
k_CAVNTCEnableTimeout_mS_u16	32696
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	7960
k_CAVNodeTimeout_mS_u16	11455
k_CMM388MsgTimeout_mS_u16	26635
k_CMM388NTCEnableTimeout_mS_u16	45991
k_CMMNTCEnableTimeout_mS_u16	17187
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	49548
k_CONSANGLECPKMax_HwDeg_f32	740.512817
k_CONSANGLECPKMin_HwDeg_f32	-26.8022003
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	35631
k_CONSANGLECPKSigValidThresh_Cnt_u16	17136
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	34905
k_CPKVehicleSpeedValidThresh_Cnt_u16	26124
k_CityParkInputInvalidThresh_Cnt_u16	13695
k_CityParkInputValidThresh_Cnt_u16	7621
k_ComputerRazGCTSigValidThresh_Cnt_u16	51041
k_CptTemporelSigValidThresh_Cnt_u16	24541
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	21770
k_DMDFCTCPKSigValidThresh_Cnt_u16	8419
k_DMDFCTCPKValidCount_Cnt_u16	33223
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	7349
k_DMDRELAXECPKSigValidThresh_Cnt_u16	47270
k_DMDRelaxeConsistentThresh_Cnt_u16	56764
k_DateValidThresh_Cnt_u16	13589
k_DefaultVehSpd_Kph_f32	208.641495
k_DiagMuxOnAbsentTimeout_mS_u16	32717
k_EMNodeTimeout_mS_u16	4096
k_ESPNTCEnableTimeout_mS_u16	998
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	41300
k_EtatMTSigInvalidThresh_Cnt_u16	58232
k_EtatMTSigValidThresh_Cnt_u16	50248
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	52932
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	4441
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	42846
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	19848
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	1348
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	38117
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	54689
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	8102

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	31464
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	36363
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	1623
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	17084
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	34437
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	47921
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	22664
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	46098
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	53481
k_ISDYNAASChkSumValidThresh_Cnt_u16	38009
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	14116
k_ISDYNAASMsgCountValidThresh_Cnt_u16	38605
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	14413
k_ISDYNAASMsgLenValidThresh_Cnt_u16	58279
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	24084
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	28888
k_ISDYNABRChkSumValidThresh_Cnt_u16	6961
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	52223
k_ISDYNABRMsgCountValidThresh_Cnt_u16	21127
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	41760
k_ISDYNABRMsgLenValidThresh_Cnt_u16	24165
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	15478
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	41287
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	25690
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	2226
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	57624
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	14432
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	51434
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	8772
k_ISDYNVOLChkSumValidThresh_Cnt_u16	55985
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	32226
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	32477
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	39486
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	3314
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	37531
k_IgnOnTimeout_mS_u16	28384
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	232.100998
k_PowerCutVehSpdLowThresh_Kph_f32	244.296295
k_PowerCutVehSpdLowTimeout_mS_u16	12594
k_VBattMaxAAS_Volt_f32	8.14659977
k_VBattMaxBSI_Volt_f32	3.86789989
k_VBattMaxCAV_Volt_f32	13.3949003
k_VBattMaxCMM388_Volt_f32	16.4435997
k_VBattMaxCMM_Volt_f32	17.6763
k_VBattMaxESP_Volt_f32	10.2514
k_VBattMinAAS_Volt_f32	0.412499994
k_VBattMinBSI_Volt_f32	10.2514
k_VBattMinCAV_Volt_f32	0.0714000016
k_VBattMinCMM388_Volt_f32	27.5760994
k_VBattMinCMM_Volt_f32	16.5727005
k_VBattMinESP_Volt_f32	17.6763
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	51995
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	17335
k_VitesseVehicleBVRampValidThresh_Cnt_u16	57884
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	58378
k_VitesseVehicleBVSigValidThresh_Cnt_u16	11670
k_VitesseVehicleBVSpeedPassThresh_kph_f32	585.766907
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	2634
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	6378
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2547141120
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	56852
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	2274721536
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	94

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	9.52880001
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3993057792
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	89
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.747498631
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	236
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1967417856
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	222
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	970426880
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1211804160
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	93
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	678283776
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1651567104
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2118388224
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	147
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	65481216
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	27
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	69
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	131
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	148
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	149
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	211
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	213
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2842085888
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	73
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	87
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	132
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	169
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	173
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	187
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	199
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	239
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	921659904
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	86
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2533526016
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	15051264
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	99
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	105
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	117
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	181
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	185
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	238
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	248
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2147531264
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2944
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.470800281
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	30788
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	63.1783981
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	42061

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	22664	22664	✔
AngleVolantMsgTimer_mS_M_u32	2274721536	2274721536	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	47431	47431	✔
CONSANGLECPK_HwDeg_M_f32	-225.234406	-225.234406 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	47431	47431	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1152653824	1152653824	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	16031	16031	✔
CityParkInputConsistentCount_Cnt_M_u16	7621	7621	✔
CityParkInputInvalidCount_Cnt_M_u16	60082	60082	✔
CityParkInputMsgTimer_mS_M_u32	2274721536	2274721536	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2274721536	2274721536	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2274721536	2274721536	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2274721536	2274721536	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2274721536	2274721536	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2274721536	2274721536	✔
ESPNTCEnableTimer_mS_M_u32	2274721536	2274721536	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2274721536	2274721536	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	2274721536	2274721536	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1235	1235	✔
ElecIntCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	2274721536	2274721536	✔
ElecIntTimer_mS_M_u32[1]	979	979	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	2274721536	2274721536	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDATDIRASentFltAcc_Cnt_M_u16	41895	41895	✔
ISDATDIRASentTimer_mS_M_u32	2274721536	2274721536	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2274721536	2274721536	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	3	3	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2274721536	2274721536	✔
IgnOnTimer_mS_M_u32	2274721536	2274721536	✔
IgnTimeOff_Sec_M_u32	2180654963	2180654963	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	6	6	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	236	236	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1967417856	1967417856	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	222	222	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	970426880	970426880	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	215	215	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1211804160	1211804160	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	93	93	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	678283776	678283776	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3554650624	3554650624	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	51	51	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2118388224	2118388224	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	147	147	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	65481216	65481216	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	215	215	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2842085888	2842085888	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	921659904	921659904	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	86	86	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2533526016	2533526016	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	74	74	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	15051264	15051264	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2147531264	2147531264	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	648.76532	648.76532	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	362.275085	362.275085	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	102.470901	102.470901	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	47431	47431	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2180654963	2180654963	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-225.234406	-225.234406 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	208.641495	208.641495	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.492 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3049747712
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	47971
AASNodeAbsentTimer_mS_M_u32	3161105664
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	8766
ANGLEVOLANTSigValidCount_Cnt_M_u16	51749
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	13548
AngleVolantMsgTimer_mS_M_u32	3049747712
AngleVolantValidCount_Cnt_M_u16	3297
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	631989504
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	4191151360
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1948226816
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2538820864
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	48521
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	174462208
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	5928
CAVNodeAbsentTimer_mS_M_u32	4177970432
CDD_SrlComVehSpd_Kph_G_f32	24.2289009
CMM388NTCEnableTimer_mS_M_u32	2132935936
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	2126824704
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	868
CMMNodeAbsentTimer_mS_M_u32	773149952
CONSANGLECPKSigInvalidCount_Cnt_M_u16	50459
CONSANGLECPKSigValidCount_Cnt_M_u16	7441
CONSANGLECPK_Cnt_M_u16	43376
CONSANGLECPK_HwDeg_M_f32	164.136795
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	43376
CPKVehicleSpeedMsgTimer_mS_M_u32	2120905984
CPKVehicleSpeedValidCount_Cnt_M_u16	35280
CityParkInputConsistentCount_Cnt_M_u16	49589
CityParkInputInvalidCount_Cnt_M_u16	40941
CityParkInputMsgTimer_mS_M_u32	1967417856
CityParkInputValidCount_Cnt_M_u16	7

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2789123328
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	28215
ComputerRazGCTSigInvalidTimer_mS_M_u32	869614848
ComputerRazGCTSigValidCount_Cnt_M_u16	33814
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	55065
DMDFCTCPKSigValidCount_Cnt_M_u16	32456
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	55208
DMDRELAXECPKSigValidCount_Cnt_M_u16	39695
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	13220
DateInvalidTimer_mS_M_u32	4191151360
DiagMuxOnAbsentTimer_mS_M_u32	3896128768
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2538820864
ESPNTCEnableTimer_mS_M_u32	881304832
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	28502
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	8
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3970962688
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	20192
EtatMTSigValidCount_Cnt_M_u16	19330
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	14469
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	11259
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	38534
ISDAT4V2BSI552MsgTimer_mS_M_u32	2397656320
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	31108
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	4942
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	19330
ISDATBSI3F2MsgTimer_mS_M_u32	751842560
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	10945
ISDATBSI412MsgLenValidCount_Cnt_M_u16	54268
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	20192
ISDATBSI412MsgTimer_mS_M_u32	677213440
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	6968
ISDATBSI432MsgLenValidCount_Cnt_M_u16	32298
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	17893
ISDATDIRASentFltAcc_Cnt_M_u16	23177
ISDATDIRASentTimer_mS_M_u32	2120905984
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	21126
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	3297
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	54756
ISDYN2CMMMsgTimer_mS_M_u32	1976149248
ISDYNAASChkSumInvalidCount_Cnt_M_u16	52429
ISDYNAASChkSumValidCount_Cnt_M_u16	59732
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	14764
ISDYNAASMsgCount_Cnt_M_u08	13
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	11975
ISDYNAASMsgLenValidCount_Cnt_M_u16	55781
ISDYNAASMsgTimeValidCount_Cnt_M_u16	52429
ISDYNAASMsgTimer_mS_M_u32	1196295424
ISDYNABRChkSumInvalidCount_Cnt_M_u16	20554
ISDYNABRChkSumValidCount_Cnt_M_u16	54105
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	61976
ISDYNABRMsgCountValidCount_Cnt_M_u16	223
ISDYNABRMsgCount_Cnt_M_u08	15
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	358
ISDYNABRMsgLenValidCount_Cnt_M_u16	35740
ISDYNABRMsgTimeValidCount_Cnt_M_u16	43376
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	47707
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	19330
ISDYNCMM208MsgTimer_mS_M_u32	2739692800

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	47707
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	2679
ISDYNCMM388MsgTimer_mS_M_u32	3100869888
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	57777
ISDYNVOLChkSumValidCount_Cnt_M_u16	40487
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	19119
ISDYNVOLMsgCountValidCount_Cnt_M_u16	38622
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	48395
ISDYNVOLMsgLenValidCount_Cnt_M_u16	32866
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	868
ISDYNVOLMsgTimer_mS_M_u32	2013349120
IgnOnTimer_mS_M_u32	2829550848
IgnTimeOff_Sec_M_u32	488058425
ManVehSpd_Kph_M_f32	74.5358963
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	119
PrevDMDFCTCPK_Cnt_M_u08	1
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	159
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	451818752
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	250
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2764739840
PrevISDATBSI412MsgDLCError_Cnt_M_u08	223
PrevISDATBSI412MsgRxTime_MSec_M_u32	2877539584
PrevISDATBSI432MsgDLCError_Cnt_M_u08	204
PrevISDATBSI432MsgRxTime_MSec_M_u32	504079616
PrevISDATDIRAMsgTxTime_MSec_M_u32	3005728000
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	100
PrevISDYN2CMMMsgRxTime_MSec_M_u32	671274240
PrevISDYNAASMsgDLCError_Cnt_M_u08	103
PrevISDYNAASMsgRxTime_MSec_M_u32	1226261760
PrevISDYNABRMsgDLCError_Cnt_M_u08	239
PrevISDYNABRMsgRxTime_MSec_M_u32	3758064896
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	220
PrevISDYNCMM208MsgRxTime_MSec_M_u32	238568704
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	108
PrevISDYNCMM388MsgRxTime_MSec_M_u32	325756160
PrevISDYNVOLMsgDLCError_Cnt_M_u08	19
PrevISDYNVOLMsgRxTime_MSec_M_u32	1847379200
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1106474240
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	593.884399
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	53341
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	40955
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	11666
VitesseVehicleBVRampValidCount_Cnt_M_u16	60144
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	10995
VitesseVehicleBVSigValidCount_Cnt_M_u16	24730
VitesseVehicleBV_Kph_M_f32	281.685791
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	2679
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	28918

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	490.646515
k_AASNTCEnableTimeout_mS_u16	42835
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	60376
k_AASNodeTimeout_mS_u16	30459
k_ABSNodeTimeout_mS_u16	37242
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	44655
k_ANGLEVOLANTSigValidThresh_Cnt_u16	56481
k_AngleVolantInvalidThresh_Cnt_u16	56724
k_AngleVolantValidThresh_Cnt_u16	40941
k_BSI552MsgTimeout_mS_u16	12201
k_BSINTCEnableTimeout_mS_u16	656
k_BSINodeAbsentDiag_Cnt_str.Threshold	33043
k_BSINodeAbsentDiag_Cnt_str.PStep	12643
k_BSINodeAbsentDiag_Cnt_str.NStep	27671
k_BSINodeAbsentTimeout_mS_u16	1604
k_BSINodeTimeout_mS_u16	17893
k_BattOvHi_Volt_f32	13.0261002
k_BattOvLo_Volt_f32	11.7882996
k_BattUvHi_Volt_f32	11.3155003
k_BattUvLo_Volt_f32	23.1116009
k_CAVNTCEnableTimeout_mS_u16	30939
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	10174
k_CAVNodeTimeout_mS_u16	42311
k_CMM388MsgTimeout_mS_u16	53859
k_CMM388NTCEnableTimeout_mS_u16	24463
k_CMMNTCEnableTimeout_mS_u16	52444
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	15394
k_CONSANGLECPKMax_HwDeg_f32	531.872192
k_CONSANGLECPKMin_HwDeg_f32	-732.359619
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	41335
k_CONSANGLECPKSigValidThresh_Cnt_u16	18422
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	64953
k_CPKVehicleSpeedValidThresh_Cnt_u16	39200
k_CityParkInputInvalidThresh_Cnt_u16	37256
k_CityParkInputValidThresh_Cnt_u16	49589
k_ComputerRazGCTSigValidThresh_Cnt_u16	47138
k_CptTemporelSigValidThresh_Cnt_u16	44140
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	6246
k_DMDFCTCPKSigValidThresh_Cnt_u16	58012
k_DMDFCTCPKValidCount_Cnt_u16	54065
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	54756
k_DMDRELAXECPKSigValidThresh_Cnt_u16	36819
k_DMDRelaxeConsistentThresh_Cnt_u16	63633
k_DateValidThresh_Cnt_u16	38534
k_DefaultVehSpd_Kph_f32	67.1018982
k_DiagMuxOnAbsentTimeout_mS_u16	60894
k_EMNodeTimeout_mS_u16	16260
k_ESPNTCEnableTimeout_mS_u16	12628
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	48330
k_EtatMTSigInvalidThresh_Cnt_u16	43933
k_EtatMTSigValidThresh_Cnt_u16	5868
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	38520
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	60539
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	51434
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	33197
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	6199
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	45205
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	34529
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	34451
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	29452
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	15140

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	53247
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	53266
k_ISDATDIRASentDiag_Cnt_str.Threshold	1170
k_ISDATDIRASentDiag_Cnt_str.PStep	4955
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	13942
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	31411
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	13548
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	53456
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	59210
k_ISDYNAASChkSumValidThresh_Cnt_u16	43609
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	2328
k_ISDYNAASMsgCountValidThresh_Cnt_u16	22495
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	16670
k_ISDYNAASMsgLenValidThresh_Cnt_u16	41935
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	841
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	31996
k_ISDYNABRChkSumValidThresh_Cnt_u16	43954
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	54409
k_ISDYNABRMsgCountValidThresh_Cnt_u16	11952
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	55908
k_ISDYNABRMsgLenValidThresh_Cnt_u16	34390
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	60643
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	7473
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	22070
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	8366
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	14654
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	8485
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	58693
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	17528
k_ISDYNVOLChkSumValidThresh_Cnt_u16	39155
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	23519
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	31533
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	64012
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	16302
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	5620
k_IgnOnTimeout_mS_u16	52900
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	91.2235031
k_PowerCutVehSpdLowThresh_Kph_f32	126.637497
k_PowerCutVehSpdLowTimeout_mS_u16	44463
k_VBattMaxAAS_Volt_f32	10.4970999
k_VBattMaxBSI_Volt_f32	23.6557007
k_VBattMaxCAV_Volt_f32	10.0600004
k_VBattMaxCMM388_Volt_f32	13.6110001
k_VBattMaxCMM_Volt_f32	23.8027992
k_VBattMaxESP_Volt_f32	20.1348991
k_VBattMinAAS_Volt_f32	27.2220001
k_VBattMinBSI_Volt_f32	20.1348991
k_VBattMinCAV_Volt_f32	29.1152992
k_VBattMinCMM388_Volt_f32	21.1735001
k_VBattMinCMM_Volt_f32	12.3858004
k_VBattMinESP_Volt_f32	23.8027992
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	29429
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	18144
k_VitesseVehicleBVRampValidThresh_Cnt_u16	57775
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	62759
k_VitesseVehicleBVSigValidThresh_Cnt_u16	5698
k_VitesseVehicleBVSpeedPassThresh_kph_f32	398.946503
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	44584
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	53254
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	4191151360
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	42709
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1704609280
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	108
target_SrlComInput_Per1_Batt_Volt_f32.value	19.4169006
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2667779328
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	222
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.73287046
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	75
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1375307008
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3099600128
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	242
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2182530304
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	244
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	368928000
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3698590976
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	91
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1031447808
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	144
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2702263552
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	18
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	110
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	126
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	173
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	203
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	214
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	215
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	171
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3071436032
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	9
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	42
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	78
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	126
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	134
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	151
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	227
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	2029552896
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	222242048
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	5
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3289761024
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	55
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	147
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	163
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	183
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	184
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	209
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	232
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	239
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1191482624
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1260
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.738833606
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	32293
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	41.2412987
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	44063

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1704609280	1704609280	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1704609280	1704609280	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	43376	43376	✔
CONSANGLECPK_HwDeg_M_f32	164.136795	164.136795 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1704609280	1704609280	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1704609280	1704609280	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1704609280	1704609280	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1704609280	1704609280	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1704609280	1704609280	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1704609280	1704609280	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1704609280	1704609280	✔
ESPNTCEnableTimer_mS_M_u32	1704609280	1704609280	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1704609280	1704609280	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	1704609280	1704609280	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	8	8	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1704609280	1704609280	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1170	1170	✔
ISDATDIRASentTimer_mS_M_u32	1704609280	1704609280	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	13	13	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	15	15	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1704609280	1704609280	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1704609280	1704609280	✔
IgnOnTimer_mS_M_u32	1704609280	1704609280	✔
IgnTimeOff_Sec_M_u32	488058425	488058425	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	1	1	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	75	75	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1375307008	1375307008	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	135	135	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3099600128	3099600128	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	242	242	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2182530304	2182530304	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	244	244	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	368928000	368928000	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3005728000	3005728000	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	91	91	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1031447808	1031447808	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	144	144	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2702263552	2702263552	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	171	171	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3071436032	3071436032	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	3	3	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2029552896	2029552896	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	141	141	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	222242048	222242048	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	5	5	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3289761024	3289761024	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1191482624	1191482624	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	593.884399	593.884399	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	281.685791	281.685791	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	490.646515	490.646515	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	43376	43376	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	488058425	488058425	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	164.136795	164.136795 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.493 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1046242304
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	16262
AASNodeAbsentTimer_mS_M_u32	4080194560
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	38135
ANGLEVOLANTSigValidCount_Cnt_M_u16	54275
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	14059
AngleVolantMsgTimer_mS_M_u32	1046242304
AngleVolantValidCount_Cnt_M_u16	51598
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2859504640
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1610814464
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	198444032
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	557368320
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	44822
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2197849088
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	58554
CAVNodeAbsentTimer_mS_M_u32	1440642048
CDD_SrlComVehSpd_Kph_G_f32	304.063507
CMM388NTCEnableTimer_mS_M_u32	1082962944
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1017410560
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	15302
CMMNodeAbsentTimer_mS_M_u32	3841115136
CONSANGLECPKSigInvalidCount_Cnt_M_u16	3937
CONSANGLECPKSigValidCount_Cnt_M_u16	32317
CONSANGLECPK_Cnt_M_u16	5408
CONSANGLECPK_HwDeg_M_f32	375.14151
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	5408
CPKVehicleSpeedMsgTimer_mS_M_u32	812868608
CPKVehicleSpeedValidCount_Cnt_M_u16	49863
CityParkInputConsistentCount_Cnt_M_u16	64274
CityParkInputInvalidCount_Cnt_M_u16	37225
CityParkInputMsgTimer_mS_M_u32	1375307008
CityParkInputValidCount_Cnt_M_u16	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2243351552
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	30474
ComputerRazGCTSigInvalidTimer_mS_M_u32	4285723648
ComputerRazGCTSigValidCount_Cnt_M_u16	30703
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	39909
DMDFCTCPKSigValidCount_Cnt_M_u16	64409
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	40121
DMDRELAXECPKSigValidCount_Cnt_M_u16	35141
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	10182
DateInvalidTimer_mS_M_u32	1610814464
DiagMuxOnAbsentTimer_mS_M_u32	3791922176
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	557368320
ESPNTCEnableTimer_mS_M_u32	1054594048
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	24238
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	87
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	21
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2216854528
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	39505
EtatMTSigValidCount_Cnt_M_u16	52009
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	56611
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	31103
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	11359
ISDAT4V2BSI552MsgTimer_mS_M_u32	309773312
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	486
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	64326
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	52009
ISDATBSI3F2MsgTimer_mS_M_u32	3963757568
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	29486
ISDATBSI412MsgLenValidCount_Cnt_M_u16	65086
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	39505
ISDATBSI412MsgTimer_mS_M_u32	3197789184
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	17482
ISDATBSI432MsgLenValidCount_Cnt_M_u16	33330
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	35971
ISDATDIRASentFltAcc_Cnt_M_u16	56983
ISDATDIRASentTimer_mS_M_u32	812868608
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	61918
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	51598
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	35716
ISDYN2CMMMsgTimer_mS_M_u32	51762176
ISDYNAASChkSumInvalidCount_Cnt_M_u16	13128
ISDYNAASChkSumValidCount_Cnt_M_u16	38004
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	12077
ISDYNAASMsgCount_Cnt_M_u08	3
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	55773
ISDYNAASMsgLenValidCount_Cnt_M_u16	61249
ISDYNAASMsgTimeValidCount_Cnt_M_u16	13128
ISDYNAASMsgTimer_mS_M_u32	2550707200
ISDYNABRChkSumInvalidCount_Cnt_M_u16	37459
ISDYNABRChkSumValidCount_Cnt_M_u16	57319
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	44903
ISDYNABRMsgCountValidCount_Cnt_M_u16	14803
ISDYNABRMsgCount_Cnt_M_u08	11
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	18048
ISDYNABRMsgLenValidCount_Cnt_M_u16	7836
ISDYNABRMsgTimeValidCount_Cnt_M_u16	5408
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	43890
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	2127
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	52009
ISDYNCMM208MsgTimer_mS_M_u32	4119696384

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	43890
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	2127
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	43212
ISDYNCMM388MsgTimer_mS_M_u32	964178944
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	37279
ISDYNVOLChkSumValidCount_Cnt_M_u16	54011
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	6435
ISDYNVOLMsgCountValidCount_Cnt_M_u16	35671
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	35215
ISDYNVOLMsgLenValidCount_Cnt_M_u16	13899
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	15302
ISDYNVOLMsgTimer_mS_M_u32	3807310848
IgnOnTimer_mS_M_u32	3120313344
IgnTimeOff_Sec_M_u32	1549240684
ManVehSpd_Kph_M_f32	626.809814
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	120
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	13
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	30
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	434643968
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	128
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3855811584
PrevISDATBSI412MsgDLCError_Cnt_M_u08	55
PrevISDATBSI412MsgRxTime_MSec_M_u32	1919382528
PrevISDATBSI432MsgDLCError_Cnt_M_u08	25
PrevISDATBSI432MsgRxTime_MSec_M_u32	2454705152
PrevISDATDIRAMsgTxTime_MSec_M_u32	3950736384
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	51
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2368357376
PrevISDYNAASMsgDLCError_Cnt_M_u08	8
PrevISDYNAASMsgRxTime_MSec_M_u32	1202516992
PrevISDYNABRMsgDLCError_Cnt_M_u08	108
PrevISDYNABRMsgRxTime_MSec_M_u32	1945383936
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	198
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3158963200
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	175
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3996308480
PrevISDYNVOLMsgDLCError_Cnt_M_u08	152
PrevISDYNVOLMsgRxTime_MSec_M_u32	3466359808
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1238918144
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	159.031998
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	52507
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	29951
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	51580
VitesseVehicleBVRampValidCount_Cnt_M_u16	43040
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	36568
VitesseVehicleBVSigValidCount_Cnt_M_u16	9380
VitesseVehicleBV_Kph_M_f32	16.2563
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	43212
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	3087

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	444.389313
k_AASNTCEnableTimeout_mS_u16	26487
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	51369
k_AASNodeTimeout_mS_u16	61439
k_ABSNodeTimeout_mS_u16	12482
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	9893
k_ANGLEVOLANTSigValidThresh_Cnt_u16	717
k_AngleVolantInvalidThresh_Cnt_u16	35828
k_AngleVolantValidThresh_Cnt_u16	37225
k_BSI552MsgTimeout_mS_u16	23542
k_BSINTCEnableTimeout_mS_u16	60994
k_BSINodeAbsentDiag_Cnt_str.Threshold	28392
k_BSINodeAbsentDiag_Cnt_str.PStep	49975
k_BSINodeAbsentDiag_Cnt_str.NStep	2138
k_BSINodeAbsentTimeout_mS_u16	8931
k_BSINodeTimeout_mS_u16	35971
k_BattOvHi_Volt_f32	22.1065998
k_BattOvLo_Volt_f32	31.3742008
k_BattUvHi_Volt_f32	23.4932003
k_BattUvLo_Volt_f32	29.5869007
k_CAVNTCEnableTimeout_mS_u16	16031
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	35576
k_CAVNodeTimeout_mS_u16	7901
k_CMM388MsgTimeout_mS_u16	64134
k_CMM388NTCEnableTimeout_mS_u16	770
k_CMMNTCEnableTimeout_mS_u16	26590
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	23179
k_CONSANGLECPKMax_HwDeg_f32	740.361328
k_CONSANGLECPKMin_HwDeg_f32	-372.412903
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	58316
k_CONSANGLECPKSigValidThresh_Cnt_u16	34575
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	54213
k_CPKVehicleSpeedValidThresh_Cnt_u16	25617
k_CityParkInputInvalidThresh_Cnt_u16	18073
k_CityParkInputValidThresh_Cnt_u16	64274
k_ComputerRazGCTSigValidThresh_Cnt_u16	15884
k_CptTemporelSigValidThresh_Cnt_u16	10220
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	384
k_DMDFCTCPKSigValidThresh_Cnt_u16	6556
k_DMDFCTCPKValidCount_Cnt_u16	3614
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	35716
k_DMDRELAXECPKSigValidThresh_Cnt_u16	46200
k_DMDRelaxeConsistentThresh_Cnt_u16	62014
k_DateValidThresh_Cnt_u16	11359
k_DefaultVehSpd_Kph_f32	168.892593
k_DiagMuxOnAbsentTimeout_mS_u16	32726
k_EMNodeTimeout_mS_u16	33830
k_ESPNTCEnableTimeout_mS_u16	17974
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	30867
k_EtatMTSigInvalidThresh_Cnt_u16	35930
k_EtatMTSigValidThresh_Cnt_u16	8494
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	50568
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	27200
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	63859
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	52587
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	53387
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	12722
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	58703
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	19703
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	36046
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	12292

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	30772
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	22586
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	36815
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	7255
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	14059
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	22466
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	52563
k_ISDYNAASChkSumValidThresh_Cnt_u16	23271
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	27239
k_ISDYNAASMsgCountValidThresh_Cnt_u16	13523
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	4055
k_ISDYNAASMsgLenValidThresh_Cnt_u16	47491
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	11989
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	43966
k_ISDYNABRChkSumValidThresh_Cnt_u16	38490
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	27158
k_ISDYNABRMsgCountValidThresh_Cnt_u16	37474
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	46790
k_ISDYNABRMsgLenValidThresh_Cnt_u16	6574
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	58313
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	13983
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	1231
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	32486
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	20471
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	52995
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	8545
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	49673
k_ISDYNVOLChkSumValidThresh_Cnt_u16	19289
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	64787
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	14443
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	18637
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	40613
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	58901
k_IgnOnTimeout_mS_u16	54149
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	69.0279007
k_PowerCutVehSpdLowThresh_Kph_f32	2.78570008
k_PowerCutVehSpdLowTimeout_mS_u16	50275
k_VBattMaxAAS_Volt_f32	14.4249001
k_VBattMaxBSI_Volt_f32	6.98239994
k_VBattMaxCAV_Volt_f32	2.81340003
k_VBattMaxCMM388_Volt_f32	20.0685005
k_VBattMaxCMM_Volt_f32	13.8242998
k_VBattMaxESP_Volt_f32	3.65490007
k_VBattMinAAS_Volt_f32	16.6828003
k_VBattMinBSI_Volt_f32	3.65490007
k_VBattMinCAV_Volt_f32	8.39260006
k_VBattMinCMM388_Volt_f32	6.50110006
k_VBattMinCMM_Volt_f32	26.2577
k_VBattMinESP_Volt_f32	13.8242998
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	48017
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	34449
k_VitesseVehicleBVRampValidThresh_Cnt_u16	21539
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	52731
k_VitesseVehicleBVSigValidThresh_Cnt_u16	29035
k_VitesseVehicleBVSpeedPassThresh_kph_f32	582.965576
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	8122
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	53470
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1610814464
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	2445
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	3144151296
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	175
target_SrlComInput_Per1_Batt_Volt_f32.value	7.89909983
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2032763904
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	51
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	6
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.230020732
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	129
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2248553472
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	142
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	875713536
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	79
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4205736960
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2709165056
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	4036408320
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	157
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2952975360
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	0
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2814309376
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	77
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	87
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	104
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	106
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	144
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	248
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	253
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1379636224
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	7
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	31
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	43
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	101
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	111
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	129
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	142
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	225
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3439932416
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	57
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	4071969792
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	210
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	4038161408
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	29
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	44
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	56
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	75
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	113
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	114
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	141
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	249
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1730479104
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	141
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.843542039
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	904399
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	97.2244034
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	49621

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	3144151296	3144151296	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	5408	5408	✔
CONSANGLECPK_HwDeg_M_f32	375.14151	375.14151 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3144151296	3144151296	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	3144151296	3144151296	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3144151296	3144151296	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3144151296	3144151296	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3144151296	3144151296	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3144151296	3144151296	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3144151296	3144151296	✔
ESPNTCEnableTimer_mS_M_u32	3144151296	3144151296	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3144151296	3144151296	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔
EffacDefaultDiagTimer_mS_M_u32[1]	87	87	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3144151296	3144151296	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	21	21	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3144151296	3144151296	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11170	11170	✔
ISDATDIRASentTimer_mS_M_u32	3144151296	3144151296	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	3	3	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	11	11	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3144151296	3144151296	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3144151296	3144151296	✔
IgnOnTimer_mS_M_u32	3120313344	3120313344	✔
IgnTimeOff_Sec_M_u32	1549240684	1549240684	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	13	13	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	129	129	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2248553472	2248553472	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	142	142	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	875713536	875713536	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	79	79	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4205736960	4205736960	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	141	141	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2709165056	2709165056	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3950736384	3950736384	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	157	157	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2952975360	2952975360	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	0	0	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2814309376	2814309376	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	253	253	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1379636224	1379636224	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3439932416	3439932416	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	57	57	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4071969792	4071969792	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	210	210	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	4038161408	4038161408	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1730479104	1730479104	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	159.031998	159.031998	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	16.2563	16.2563	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	444.389313	444.389313	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	5408	5408	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1549240684	1549240684	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	375.14151	375.14151 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.494 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1729730304
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	11674
AASNodeAbsentTimer_mS_M_u32	3998631680
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	36680
ANGLEVOLANTSigValidCount_Cnt_M_u16	11748
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	7019
AngleVolantMsgTimer_mS_M_u32	1729730304
AngleVolantValidCount_Cnt_M_u16	5124
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	4020045568
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	954566400
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3845306112
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	671381248
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	31979
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3517789952
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	5247
CAVNodeAbsentTimer_mS_M_u32	2094229248
CDD_SrlComVehSpd_Kph_G_f32	93.9393005
CMM388NTCEnableTimer_mS_M_u32	1170777856
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1619093248
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	48154
CMMNodeAbsentTimer_mS_M_u32	1154905856
CONSANGLECPKSigInvalidCount_Cnt_M_u16	63243
CONSANGLECPKSigValidCount_Cnt_M_u16	17975
CONSANGLECPK_Cnt_M_u16	52622
CONSANGLECPK_HwDeg_M_f32	-200.040207
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	52622
CPKVehicleSpeedMsgTimer_mS_M_u32	2899613440
CPKVehicleSpeedValidCount_Cnt_M_u16	63551
CityParkInputConsistentCount_Cnt_M_u16	36728

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	14706
CityParkInputMsgTimer_mS_M_u32	2248553472
CityParkInputValidCount_Cnt_M_u16	0
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1187661568
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	38670
ComputerRazGCTSigInvalidTimer_mS_M_u32	1914038016
ComputerRazGCTSigValidCount_Cnt_M_u16	52449
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	2558
DMDFCTCPKSigValidCount_Cnt_M_u16	59043
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	2
DMDRELAXECPKSigValidCount_Cnt_M_u16	38430
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	33244
DateInvalidTimer_mS_M_u32	954566400
DiagMuxOnAbsentTimer_mS_M_u32	3408025344
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	671381248
ESPNTCEnableTimer_mS_M_u32	4015736576
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	7970
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	707
EffacDefaultDiagTimer_mS_M_u32[1]	1235
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	979
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3594991360
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	56696
EtatMTSigValidCount_Cnt_M_u16	54961
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	5573
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	56433
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	60497
ISDAT4V2BSI552MsgTimer_mS_M_u32	3427432192
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	61499
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	45019
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	54961
ISDATBSI3F2MsgTimer_mS_M_u32	610817792
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	3427
ISDATBSI412MsgLenValidCount_Cnt_M_u16	55283
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	56696
ISDATBSI412MsgTimer_mS_M_u32	1583322880
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	45710
ISDATBSI432MsgLenValidCount_Cnt_M_u16	50326
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	33060
ISDATDIRASentFltAcc_Cnt_M_u16	56040
ISDATDIRASentTimer_mS_M_u32	2899613440
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	44884
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	5124
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	30497
ISDYN2CMMMsgTimer_mS_M_u32	179128064
ISDYNAASChkSumInvalidCount_Cnt_M_u16	55892
ISDYNAASChkSumValidCount_Cnt_M_u16	37520
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	7975
ISDYNAASMsgCount_Cnt_M_u08	8
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	33046
ISDYNAASMsgLenValidCount_Cnt_M_u16	64682
ISDYNAASMsgTimeValidCount_Cnt_M_u16	55892
ISDYNAASMsgTimer_mS_M_u32	794076928
ISDYNABRChkSumInvalidCount_Cnt_M_u16	179
ISDYNABRChkSumValidCount_Cnt_M_u16	37815
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	41463
ISDYNABRMsgCountValidCount_Cnt_M_u16	56947
ISDYNABRMsgCount_Cnt_M_u08	2
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	36270
ISDYNABRMsgLenValidCount_Cnt_M_u16	41242
ISDYNABRMsgTimeValidCount_Cnt_M_u16	52622
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	41058

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	57651
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	54961
ISDYNCMM208MsgTimer_mS_M_u32	3259369216
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	57651
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	61002
ISDYNCMM388MsgTimer_mS_M_u32	1762010880
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	59473
ISDYNVOLChkSumValidCount_Cnt_M_u16	49149
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	2628
ISDYNVOLMsgCountValidCount_Cnt_M_u16	44905
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	25215
ISDYNVOLMsgLenValidCount_Cnt_M_u16	30732
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	48154
ISDYNVOLMsgTimer_mS_M_u32	3080840960
IgnOnTimer_mS_M_u32	4151977728
IgnTimeOff_Sec_M_u32	3049888972
ManVehSpd_Kph_M_f32	330.058685
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	118
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	7
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	240
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3010877184
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	111
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	322287360
PrevISDATBSI412MsgDLCError_Cnt_M_u08	19
PrevISDATBSI412MsgRxTime_MSec_M_u32	2335729408
PrevISDATBSI432MsgDLCError_Cnt_M_u08	120
PrevISDATBSI432MsgRxTime_MSec_M_u32	3305064192
PrevISDATDIRAMsgTxTime_MSec_M_u32	1878812416
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	132
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2318399232
PrevISDYNAASMsgDLCError_Cnt_M_u08	110
PrevISDYNAASMsgRxTime_MSec_M_u32	23586560
PrevISDYNABRMsgDLCError_Cnt_M_u08	72
PrevISDYNABRMsgRxTime_MSec_M_u32	2844927744
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	217
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1469114112
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	81
PrevISDYNCMM388MsgRxTime_MSec_M_u32	4250289920
PrevISDYNVOLMsgDLCError_Cnt_M_u08	253
PrevISDYNVOLMsgRxTime_MSec_M_u32	2325309184
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	883267328
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	431.60849
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	8028
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	58224
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	5
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	60985
VitesseVehicleBVRampValidCount_Cnt_M_u16	3597
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	26021
VitesseVehicleBVSigValidCount_Cnt_M_u16	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBV_Kph_M_f32	160.010406
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	61002
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	62
VitesseVehiculeRoues_Kph_M_f32	304.945587
k_AASNTCEnableTimeout_mS_u16	62089
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	17075
k_AASNodeTimeout_mS_u16	29296
k_ABSNodeTimeout_mS_u16	65383
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	14205
k_ANGLEVOLANTSigValidThresh_Cnt_u16	28357
k_AngleVolantInvalidThresh_Cnt_u16	12112
k_AngleVolantValidThresh_Cnt_u16	14706
k_BSI552MsgTimeout_mS_u16	27785
k_BSINTCEnableTimeout_mS_u16	38054
k_BSINodeAbsentDiag_Cnt_str.Threshold	13537
k_BSINodeAbsentDiag_Cnt_str.PStep	61147
k_BSINodeAbsentDiag_Cnt_str.NStep	49162
k_BSINodeAbsentTimeout_mS_u16	14211
k_BSINodeTimeout_mS_u16	33060
k_BattOvHi_Volt_f32	18.4130001
k_BattOvLo_Volt_f32	6.44740009
k_BattUvHi_Volt_f32	25.4885006
k_BattUvLo_Volt_f32	12.7615004
k_CAVNTCEnableTimeout_mS_u16	35280
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	39365
k_CAVNodeTimeout_mS_u16	47255
k_CMM388MsgTimeout_mS_u16	64666
k_CMM388NTCEnableTimeout_mS_u16	54054
k_CMMNTCEnableTimeout_mS_u16	40531
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	1226
k_CONSANGLECPKMax_HwDeg_f32	342.129486
k_CONSANGLECPKMin_HwDeg_f32	-331.138611
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	15690
k_CONSANGLECPKSigValidThresh_Cnt_u16	36670
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	24350
k_CPKVehicleSpeedValidThresh_Cnt_u16	34490
k_CityParkInputInvalidThresh_Cnt_u16	31713
k_CityParkInputValidThresh_Cnt_u16	36728
k_ComputerRazGCTSigValidThresh_Cnt_u16	21449
k_CptTemporelSigValidThresh_Cnt_u16	16873
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	23726
k_DMDFCTCPKSigValidThresh_Cnt_u16	45082
k_DMDFCTCPKValidCount_Cnt_u16	32723
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	30497
k_DMDRELAXECPKSigValidThresh_Cnt_u16	63494
k_DMDRelaxeConsistentThresh_Cnt_u16	54964
k_DateValidThresh_Cnt_u16	60497
k_DefaultVehSpd_Kph_f32	240.0047
k_DiagMuxOnAbsentTimeout_mS_u16	58732
k_EMNodeTimeout_mS_u16	60604
k_ESPNTCEnableTimeout_mS_u16	57355
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	51890
k_EtatMTSigInvalidThresh_Cnt_u16	61086
k_EtatMTSigValidThresh_Cnt_u16	44002
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	21973
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	29549
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	22613
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	57772
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	33804
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	57815
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	9087

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	47175
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	59650
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	3298
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	8210
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	57150
k_ISDATDIRASentDiag_Cnt_str.Threshold	24699
k_ISDATDIRASentDiag_Cnt_str.PStep	10108
k_ISDATDIRASentDiag_Cnt_str.NStep	32066
k_ISDATDIRASentTimeout_mS_u16	63551
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	18151
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	7019
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	56167
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	20403
k_ISDYNAASChkSumValidThresh_Cnt_u16	8887
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	28919
k_ISDYNAASMsgCountValidThresh_Cnt_u16	60787
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	38951
k_ISDYNAASMsgLenValidThresh_Cnt_u16	9700
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	2733
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	54772
k_ISDYNABRChkSumValidThresh_Cnt_u16	45536
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	19435
k_ISDYNABRMsgCountValidThresh_Cnt_u16	11975
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	19226
k_ISDYNABRMsgLenValidThresh_Cnt_u16	60962
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	38546
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	62160
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	7296
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	8635
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	24136
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	15588
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	27018
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	19666
k_ISDYNVOLChkSumValidThresh_Cnt_u16	7330
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	6131
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	39467
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	49668
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	19517
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	5935
k_IgnOnTimeout_mS_u16	2142
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	110.098999
k_PowerCutVehSpdLowThresh_Kph_f32	188.8255
k_PowerCutVehSpdLowTimeout_mS_u16	35781
k_VBattMaxAAS_Volt_f32	25.3913994
k_VBattMaxBSI_Volt_f32	17.6193008
k_VBattMaxCAV_Volt_f32	32
k_VBattMaxCMM388_Volt_f32	29.5046005
k_VBattMaxCMM_Volt_f32	8.2439003
k_VBattMaxESP_Volt_f32	3.27069998
k_VBattMinAAS_Volt_f32	26.3199997
k_VBattMinBSI_Volt_f32	3.27069998
k_VBattMinCAV_Volt_f32	26.0216007
k_VBattMinCMM388_Volt_f32	9.8465004
k_VBattMinCMM_Volt_f32	3.39599991
k_VBattMinESP_Volt_f32	8.2439003
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	53561
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	39929
k_VitesseVehicleBVRampValidThresh_Cnt_u16	22852
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	52989
k_VitesseVehicleBVSigValidThresh_Cnt_u16	53357
k_VitesseVehicleBVSpeedPassThresh_kph_f32	298.7883
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	25471
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	3027
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	954566400
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	39539
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1516957696
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	81
target_SrlComInput_Per1_Batt_Volt_f32.value	10.0131998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	3543283456
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	55
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	7
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.578674674
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	995895040
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	37
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2304231168
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3462620928
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2994669312
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3718948608
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	4159063808
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2838619904
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	48
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	83
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	90
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	136
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	159
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	228
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	233
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	253
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	79
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3829139200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	93
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	95
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	107
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	115
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	166
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	183
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	185
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	208
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	166
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	844310272
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	241
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	432981760
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3092932352
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	14
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	58
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	85
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	105
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	119
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	196
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	197
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	221
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1463793408
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2134
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.94697088
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	616410
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	134.759399

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	43310		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	7021	7021	✔
AngleVolantMsgTimer_mS_M_u32	1516957696	1516957696	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	52622	52622	✔
CONSANGLECPK_HwDeg_M_f32	-200.040207	-200.040207 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	52622	52622	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2899613440	2899613440	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	63551	63551	✔
CityParkInputConsistentCount_Cnt_M_u16	36728	36728	✔
CityParkInputInvalidCount_Cnt_M_u16	14708	14708	✔
CityParkInputMsgTimer_mS_M_u32	1516957696	1516957696	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1516957696	1516957696	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1516957696	1516957696	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1516957696	1516957696	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1516957696	1516957696	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1516957696	1516957696	✔
ESPNTCEnableTimer_mS_M_u32	1516957696	1516957696	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1516957696	1516957696	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1516957696	1516957696	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	1235	1235	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	1516957696	1516957696	✔
ElecIntTimer_mS_M_u32[1]	979	979	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1516957696	1516957696	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDATDIRASentFltAcc_Cnt_M_u16	24699	24699	✔
ISDATDIRASentTimer_mS_M_u32	1516957696	1516957696	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	8	8	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	2	2	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1516957696	1516957696	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1516957696	1516957696	✔
IgnOnTimer_mS_M_u32	1516957696	1516957696	✔
IgnTimeOff_Sec_M_u32	3049888972	3049888972	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	148	148	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	995895040	995895040	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	37	37	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2304231168	2304231168	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3462620928	3462620928	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	90	90	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2994669312	2994669312	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1878812416	1878812416	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	90	90	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4159063808	4159063808	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2838619904	2838619904	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	79	79	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3829139200	3829139200	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	166	166	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	844310272	844310272	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	241	241	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	432981760	432981760	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	31	31	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3092932352	3092932352	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1463793408	1463793408	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	431.60849	431.60849	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	5	5	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	160.010406	160.010406	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	304.945587	304.945587	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	52622	52622	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	3049888972	3049888972	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-200.040207	-200.040207 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.495 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	2507013632
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	58348
AASNodeAbsentTimer_mS_M_u32	242740736
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	39136
ANGLEVOLANTSigValidCount_Cnt_M_u16	43468
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	40569
AngleVolantMsgTimer_mS_M_u32	2507013632
AngleVolantValidCount_Cnt_M_u16	41772
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	2510532096
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2076847616
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1738710528
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	372071936
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	7159
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	2889031168
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	43965
CAVNodeAbsentTimer_mS_M_u32	1065389568
CDD_SrlComVehSpd_Kph_G_f32	107.831596
CMM388NTCEnableTimer_mS_M_u32	1235275264
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	3430321664
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	44714
CMMNodeAbsentTimer_mS_M_u32	2276941312
CONSANGLECPKSigInvalidCount_Cnt_M_u16	56472
CONSANGLECPKSigValidCount_Cnt_M_u16	7124
CONSANGLECPK_Cnt_M_u16	41423
CONSANGLECPK_HwDeg_M_f32	-306.554993
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	41423
CPKVehicleSpeedMsgTimer_mS_M_u32	1883045376
CPKVehicleSpeedValidCount_Cnt_M_u16	9925
CityParkInputConsistentCount_Cnt_M_u16	208
CityParkInputInvalidCount_Cnt_M_u16	48097

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	995895040
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3575377408
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	30608
ComputerRazGCTSigInvalidTimer_mS_M_u32	2310606336
ComputerRazGCTSigValidCount_Cnt_M_u16	11413
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	31293
DMDFCTCPKSigValidCount_Cnt_M_u16	61713
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	44722
DMDRELAXECPKSigValidCount_Cnt_M_u16	55582
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	49189
DateInvalidTimer_mS_M_u32	2076847616
DiagMuxOnAbsentTimer_mS_M_u32	2085862912
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	372071936
ESPNTCEnableTimer_mS_M_u32	1600712192
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	8786
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	8
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	2254773760
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	37776
EtatMTSigValidCount_Cnt_M_u16	1191
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	59498
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	49446
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	6151
ISDAT4V2BSI552MsgTimer_mS_M_u32	3243990528
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	32455
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	15526
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	1191
ISDATBSI3F2MsgTimer_mS_M_u32	142720512
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	54353
ISDATBSI412MsgLenValidCount_Cnt_M_u16	12641
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	37776
ISDATBSI412MsgTimer_mS_M_u32	1201405440
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	39758
ISDATBSI432MsgLenValidCount_Cnt_M_u16	502
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	14798
ISDATDIRASentFltAcc_Cnt_M_u16	15490
ISDATDIRASentTimer_mS_M_u32	1883045376
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	38013
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	41772
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	32468
ISDYN2CMMMsgTimer_mS_M_u32	3581079040
ISDYNAASChkSumInvalidCount_Cnt_M_u16	17854
ISDYNAASChkSumValidCount_Cnt_M_u16	35273
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	52675
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	33272
ISDYNAASMsgLenValidCount_Cnt_M_u16	56315
ISDYNAASMsgTimeValidCount_Cnt_M_u16	17854
ISDYNAASMsgTimer_mS_M_u32	3170684416
ISDYNABRChkSumInvalidCount_Cnt_M_u16	2080
ISDYNABRChkSumValidCount_Cnt_M_u16	56275
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	15061
ISDYNABRMsgCountValidCount_Cnt_M_u16	61984
ISDYNABRMsgCount_Cnt_M_u08	8
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	25775
ISDYNABRMsgLenValidCount_Cnt_M_u16	22315
ISDYNABRMsgTimeValidCount_Cnt_M_u16	41423
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	47707

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	1191
ISDYNCMM208MsgTimer_mS_M_u32	27831808
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	47707
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	44122
ISDYNCMM388MsgTimer_mS_M_u32	3051900416
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	41158
ISDYNVOLChkSumValidCount_Cnt_M_u16	18050
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	4459
ISDYNVOLMsgCountValidCount_Cnt_M_u16	11967
ISDYNVOLMsgCount_Cnt_M_u08	12
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	3131
ISDYNVOLMsgLenValidCount_Cnt_M_u16	30806
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	44714
ISDYNVOLMsgTimer_mS_M_u32	3910471168
IgnOnTimer_mS_M_u32	3666628096
IgnTimeOff_Sec_M_u32	221967916
ManVehSpd_Kph_M_f32	380.778503
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	119
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	120
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	324517376
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	15
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2845416960
PrevISDATBSI412MsgDLCError_Cnt_M_u08	196
PrevISDATBSI412MsgRxTime_MSec_M_u32	3897658880
PrevISDATBSI432MsgDLCError_Cnt_M_u08	123
PrevISDATBSI432MsgRxTime_MSec_M_u32	1853681152
PrevISDATDIRAMsgTxTime_MSec_M_u32	1241878016
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	72
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4255833600
PrevISDYNAASMsgDLCError_Cnt_M_u08	82
PrevISDYNAASMsgRxTime_MSec_M_u32	2747469312
PrevISDYNABRMsgDLCError_Cnt_M_u08	174
PrevISDYNABRMsgRxTime_MSec_M_u32	608456192
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	28
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2236091904
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	24
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3782733312
PrevISDYNVOLMsgDLCError_Cnt_M_u08	230
PrevISDYNVOLMsgRxTime_MSec_M_u32	2922286592
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1556741632
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	43.4403992
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	16166
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	49065
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	6
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	34447
VitesseVehicleBVRampValidCount_Cnt_M_u16	62418
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	51657
VitesseVehicleBVSigValidCount_Cnt_M_u16	59253
VitesseVehicleBV_Kph_M_f32	332.649689

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	44122
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	49982
VitesseVehiculeRoues_Kph_M_f32	204.221695
k_AASNTCEnableTimeout_mS_u16	57054
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	37663
k_AASNodeTimeout_mS_u16	4777
k_ABSNodeTimeout_mS_u16	32258
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	34945
k_ANGLEVOLANTSigValidThresh_Cnt_u16	32617
k_AngleVolantInvalidThresh_Cnt_u16	10696
k_AngleVolantValidThresh_Cnt_u16	48097
k_BSI552MsgTimeout_mS_u16	27229
k_BSINTCEnableTimeout_mS_u16	21766
k_BSINodeAbsentDiag_Cnt_str.Threshold	33043
k_BSINodeAbsentDiag_Cnt_str.PStep	12643
k_BSINodeAbsentDiag_Cnt_str.NStep	27671
k_BSINodeAbsentTimeout_mS_u16	43569
k_BSINodeTimeout_mS_u16	14798
k_BattOvHi_Volt_f32	21.8190002
k_BattOvLo_Volt_f32	10.2035999
k_BattUvHi_Volt_f32	31.5
k_BattUvLo_Volt_f32	20.9048004
k_CAVNTCEnableTimeout_mS_u16	49863
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	46059
k_CAVNodeTimeout_mS_u16	51188
k_CMM388MsgTimeout_mS_u16	30444
k_CMM388NTCEnableTimeout_mS_u16	9032
k_CMMNTCEnableTimeout_mS_u16	54399
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	58778
k_CONSANGLECPKMax_HwDeg_f32	25.3059006
k_CONSANGLECPKMin_HwDeg_f32	-743.117371
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	48986
k_CONSANGLECPKSigValidThresh_Cnt_u16	5694
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	33951
k_CPKVehicleSpeedValidThresh_Cnt_u16	33868
k_CityParkInputInvalidThresh_Cnt_u16	52886
k_CityParkInputValidThresh_Cnt_u16	208
k_ComputerRazGCTSigValidThresh_Cnt_u16	3101
k_CptTemporelSigValidThresh_Cnt_u16	15996
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	63407
k_DMDFCTCPKSigValidThresh_Cnt_u16	10795
k_DMDFCTCPKValidCount_Cnt_u16	45887
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	32468
k_DMDRELAXECPKSigValidThresh_Cnt_u16	2280
k_DMDRelaxeConsistentThresh_Cnt_u16	42206
k_DateValidThresh_Cnt_u16	6151
k_DefaultVehSpd_Kph_f32	161.215302
k_DiagMuxOnAbsentTimeout_mS_u16	21045
k_EMNodeTimeout_mS_u16	65413
k_ESPNTCEnableTimeout_mS_u16	31001
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	13282
k_EtatMTSigInvalidThresh_Cnt_u16	43615
k_EtatMTSigValidThresh_Cnt_u16	65362
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	15482
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	49265
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	23097
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	44660
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	50195
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	9973
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	19579
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	10979

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	51186
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	13267
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	14082
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	56255
k_ISDATDIRASentDiag_Cnt_str.Threshold	55184
k_ISDATDIRASentDiag_Cnt_str.PStep	37963
k_ISDATDIRASentDiag_Cnt_str.NStep	46267
k_ISDATDIRASentTimeout_mS_u16	20860
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	35012
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	40569
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	63237
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	6944
k_ISDYNAASChkSumValidThresh_Cnt_u16	11987
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	52693
k_ISDYNAASMsgCountValidThresh_Cnt_u16	50464
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	4548
k_ISDYNAASMsgLenValidThresh_Cnt_u16	51277
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	19377
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	9181
k_ISDYNABRChkSumValidThresh_Cnt_u16	48345
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	44791
k_ISDYNABRMsgCountValidThresh_Cnt_u16	62243
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	426
k_ISDYNABRMsgLenValidThresh_Cnt_u16	46418
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	42946
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	38090
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	23290
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	61640
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	11232
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	31948
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	35737
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	37380
k_ISDYNVOLChkSumValidThresh_Cnt_u16	57172
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	48095
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	39031
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	5612
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	54275
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	36717
k_IgnOnTimeout_mS_u16	36704
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	47.4325981
k_PowerCutVehSpdLowThresh_Kph_f32	171.252899
k_PowerCutVehSpdLowTimeout_mS_u16	810
k_VBattMaxAAS_Volt_f32	21.1797009
k_VBattMaxBSI_Volt_f32	2.79480004
k_VBattMaxCAV_Volt_f32	14.0644999
k_VBattMaxCMM388_Volt_f32	11.7082996
k_VBattMaxCMM_Volt_f32	30.4696007
k_VBattMaxESP_Volt_f32	19.8337002
k_VBattMinAAS_Volt_f32	28.2873993
k_VBattMinBSI_Volt_f32	19.8337002
k_VBattMinCAV_Volt_f32	5.6894002
k_VBattMinCMM388_Volt_f32	20.7637005
k_VBattMinCMM_Volt_f32	13.6571999
k_VBattMinESP_Volt_f32	30.4696007
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	45518
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	52814
k_VitesseVehicleBVRampValidThresh_Cnt_u16	9323
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	6530
k_VitesseVehicleBVSigValidThresh_Cnt_u16	20977
k_VitesseVehicleBVSpeedPassThresh_kph_f32	306.659088
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	48829
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	37504
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2076847616
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	60573
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	1277031168
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	24

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	2.98920012
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4221836800
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	18
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	13
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.212266684
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	40
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	384192000
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	74
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	594767360
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2328923648
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	27
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1425911296
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2314915328
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	135
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	835186176
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	43
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1415908864
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	30
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	43
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	61
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	125
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	143
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	155
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	195
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4089884160
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	0
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	17
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	18
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	82
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	138
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	148
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	152
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	194
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3456192000
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	131
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	235826688
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	15
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1760267776
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	94
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	97
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	112
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	124
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	164
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2239471104
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1075
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.725078583
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	254050
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	157.701401
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	27056

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1277031168	1277031168	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	41423	41423	✔
CONSANGLECPK_HwDeg_M_f32	-306.554993	-306.554993 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1277031168	1277031168	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1277031168	1277031168	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1277031168	1277031168	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1277031168	1277031168	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1277031168	1277031168	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1277031168	1277031168	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1277031168	1277031168	✔
ESPNTCEnableTimer_mS_M_u32	1277031168	1277031168	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1277031168	1277031168	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	1277031168	1277031168	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	1277031168	1277031168	✔
ElecIntTimer_mS_M_u32[1]	8	8	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1277031168	1277031168	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDATDIRASentFltAcc_Cnt_M_u16	55184	55184	✔
ISDATDIRASentTimer_mS_M_u32	1277031168	1277031168	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	8	8	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1277031168	1277031168	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	12	12	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1277031168	1277031168	✔
IgnOnTimer_mS_M_u32	3666628096	3666628096	✔
IgnTimeOff_Sec_M_u32	221967916	221967916	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	40	40	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	384192000	384192000	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	74	74	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	594767360	594767360	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	67	67	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2328923648	2328923648	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	27	27	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1425911296	1425911296	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1241878016	1241878016	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	135	135	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	835186176	835186176	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	43	43	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1415908864	1415908864	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	110	110	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4089884160	4089884160	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	141	141	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3456192000	3456192000	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	131	131	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	235826688	235826688	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	15	15	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1760267776	1760267776	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2239471104	2239471104	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	43.4403992	43.4403992	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	6	6	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	332.649689	332.649689	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	204.221695	204.221695	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	41423	41423	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	221967916	221967916	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-306.554993	-306.554993 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.496 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	194799616
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	12814
AASNodeAbsentTimer_mS_M_u32	1450563584
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	58023
ANGLEVOLANTSigValidCount_Cnt_M_u16	8302
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	2307
AngleVolantMsgTimer_mS_M_u32	194799616
AngleVolantValidCount_Cnt_M_u16	63568
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	3707738112
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2556041216
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3497396224
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1364641792
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	54902
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3985278976
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	63844
CAVNodeAbsentTimer_mS_M_u32	2428729344
CDD_SrlComVehSpd_Kph_G_f32	460.907898
CMM388NTCEnableTimer_mS_M_u32	98940928
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1969846272
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	41791
CMMNodeAbsentTimer_mS_M_u32	1597032448
CONSANGLECPKSigInvalidCount_Cnt_M_u16	59933
CONSANGLECPKSigValidCount_Cnt_M_u16	18612
CONSANGLECPK_Cnt_M_u16	63111
CONSANGLECPK_HwDeg_M_f32	451.958099
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	63111
CPKVehicleSpeedMsgTimer_mS_M_u32	3571673088
CPKVehicleSpeedValidCount_Cnt_M_u16	56766

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	58132
CityParkInputInvalidCount_Cnt_M_u16	30895
CityParkInputMsgTimer_mS_M_u32	3248740608
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4063877120
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	722
ComputerRazGCTSigInvalidTimer_mS_M_u32	549451776
ComputerRazGCTSigValidCount_Cnt_M_u16	29953
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	35307
DMDFCTCPKSigValidCount_Cnt_M_u16	40154
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	63241
DMDRELAXECPKSigValidCount_Cnt_M_u16	6736
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	12818
DateInvalidTimer_mS_M_u32	2556041216
DiagMuxOnAbsentTimer_mS_M_u32	2142251008
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1364641792
ESPNTCEnableTimer_mS_M_u32	384751616
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	47522
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	707
EffacDefaultDiagTimer_mS_M_u32[1]	1235
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	97
ElecIntTimer_mS_M_u32[1]	979
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3914106880
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	53582
EtatMTSigValidCount_Cnt_M_u16	20641
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	42111
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	26774
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	60288
ISDAT4V2BSI552MsgTimer_mS_M_u32	99928064
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	38209
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	1948
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	20641
ISDATBSI3F2MsgTimer_mS_M_u32	491661312
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	49437
ISDATBSI412MsgLenValidCount_Cnt_M_u16	19496
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	53582
ISDATBSI412MsgTimer_mS_M_u32	4282017792
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	38147
ISDATBSI432MsgLenValidCount_Cnt_M_u16	13926
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	57341
ISDATDIRASentFltAcc_Cnt_M_u16	6225
ISDATDIRASentTimer_mS_M_u32	3571673088
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	11941
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	63568
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	2874
ISDYN2CMMMsgTimer_mS_M_u32	1296619520
ISDYNAASChkSumInvalidCount_Cnt_M_u16	62064
ISDYNAASChkSumValidCount_Cnt_M_u16	64599
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	53151
ISDYNAASMsgCount_Cnt_M_u08	15
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	31095
ISDYNAASMsgLenValidCount_Cnt_M_u16	2326
ISDYNAASMsgTimeValidCount_Cnt_M_u16	62064
ISDYNAASMsgTimer_mS_M_u32	1948366848
ISDYNABRChkSumInvalidCount_Cnt_M_u16	35553
ISDYNABRChkSumValidCount_Cnt_M_u16	57776
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	59455
ISDYNABRMsgCountValidCount_Cnt_M_u16	65382
ISDYNABRMsgCount_Cnt_M_u08	1
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	2796
ISDYNABRMsgLenValidCount_Cnt_M_u16	46787
ISDYNABRMsgTimeValidCount_Cnt_M_u16	63111

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	57651
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	20641
ISDYNCMM208MsgTimer_mS_M_u32	2972489728
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	41058
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	57651
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	64238
ISDYNCMM388MsgTimer_mS_M_u32	3764992000
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	32699
ISDYNVOLChkSumValidCount_Cnt_M_u16	30930
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	35465
ISDYNVOLMsgCountValidCount_Cnt_M_u16	30712
ISDYNVOLMsgCount_Cnt_M_u08	10
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	39635
ISDYNVOLMsgLenValidCount_Cnt_M_u16	36170
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	41791
ISDYNVOLMsgTimer_mS_M_u32	3673946112
IgnOnTimer_mS_M_u32	3391961088
IgnTimeOff_Sec_M_u32	401958722
ManVehSpd_Kph_M_f32	234.384003
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	118
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	4
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	15
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1859397632
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	157
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2049247232
PrevISDATBSI412MsgDLCError_Cnt_M_u08	127
PrevISDATBSI412MsgRxTime_MSec_M_u32	1746696192
PrevISDATBSI432MsgDLCError_Cnt_M_u08	236
PrevISDATBSI432MsgRxTime_MSec_M_u32	3198343168
PrevISDATDIRAMsgTxTime_MSec_M_u32	4151343104
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	30
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1891649536
PrevISDYNAASMsgDLCError_Cnt_M_u08	123
PrevISDYNAASMsgRxTime_MSec_M_u32	454686720
PrevISDYNABRMsgDLCError_Cnt_M_u08	78
PrevISDYNABRMsgRxTime_MSec_M_u32	564475904
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	105
PrevISDYNCMM208MsgRxTime_MSec_M_u32	281475072
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	106
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3245725696
PrevISDYNVOLMsgDLCError_Cnt_M_u08	73
PrevISDYNVOLMsgRxTime_MSec_M_u32	618756096
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1842898944
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	547.98291
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	53269
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	47668
VVHTYPE1Count_Cnt_M_u08	8
VVHTYPE2Count_Cnt_M_u08	9
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	64198
VitesseVehicleBVRampValidCount_Cnt_M_u16	14245
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	17112

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	62303
VitesseVehicleBV_Kph_M_f32	253.741104
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	64238
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	11884
VitesseVehiculeRoues_Kph_M_f32	18.3033009
k_AASNTCEnableTimeout_mS_u16	13326
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	8155
k_AASNodeTimeout_mS_u16	42292
k_ABSNodeTimeout_mS_u16	46040
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	41934
k_ANGLEVOLANTSigValidThresh_Cnt_u16	22385
k_AngleVolantInvalidThresh_Cnt_u16	60616
k_AngleVolantValidThresh_Cnt_u16	30895
k_BSI552MsgTimeout_mS_u16	42627
k_BSINTCEnableTimeout_mS_u16	56443
k_BSINodeAbsentDiag_Cnt_str.Threshold	13537
k_BSINodeAbsentDiag_Cnt_str.PStep	61147
k_BSINodeAbsentDiag_Cnt_str.NStep	49162
k_BSINodeAbsentTimeout_mS_u16	12923
k_BSINodeTimeout_mS_u16	57341
k_BattOvHi_Volt_f32	8.3842001
k_BattOvLo_Volt_f32	23.6261005
k_BattUvHi_Volt_f32	12.2831001
k_BattUvLo_Volt_f32	3.52090001
k_CAVNTCEnableTimeout_mS_u16	9925
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	62210
k_CAVNodeTimeout_mS_u16	36953
k_CMM388MsgTimeout_mS_u16	23822
k_CMM388NTCEnableTimeout_mS_u16	52298
k_CMMNTCEnableTimeout_mS_u16	22713
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	50088
k_CONSANGLECPKMax_HwDeg_f32	53.0777016
k_CONSANGLECPKMin_HwDeg_f32	-117.8274
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	42478
k_CONSANGLECPKSigValidThresh_Cnt_u16	6508
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	38618
k_CPKVehicleSpeedValidThresh_Cnt_u16	59632
k_CityParkInputInvalidThresh_Cnt_u16	29959
k_CityParkInputValidThresh_Cnt_u16	58132
k_ComputerRazGCTSigValidThresh_Cnt_u16	32071
k_CptTemporelSigValidThresh_Cnt_u16	2082
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	13804
k_DMDFCTCPKSigValidThresh_Cnt_u16	8643
k_DMDFCTCPKValidCount_Cnt_u16	26622
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	2874
k_DMDRELAXECPKSigValidThresh_Cnt_u16	52073
k_DMDRelaxeConsistentThresh_Cnt_u16	14095
k_DateValidThresh_Cnt_u16	60288
k_DefaultVehSpd_Kph_f32	42.6818008
k_DiagMuxOnAbsentTimeout_mS_u16	39453
k_EMNodeTimeout_mS_u16	27762
k_ESPNTCEnableTimeout_mS_u16	37280
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	50224
k_EtatMTSigInvalidThresh_Cnt_u16	55064
k_EtatMTSigValidThresh_Cnt_u16	47399
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	1421
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	11968
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	44997
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	35414
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	4721
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	18657

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	6040
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	61115
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	50887
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	47275
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	6870
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	52733
k_ISDATDIRASentDiag_Cnt_str.Threshold	5639
k_ISDATDIRASentDiag_Cnt_str.PStep	36987
k_ISDATDIRASentDiag_Cnt_str.NStep	30451
k_ISDATDIRASentTimeout_mS_u16	32541
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	60202
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	2307
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	57068
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	13793
k_ISDYNAASChkSumValidThresh_Cnt_u16	52400
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	4927
k_ISDYNAASMsgCountValidThresh_Cnt_u16	27238
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	33189
k_ISDYNAASMsgLenValidThresh_Cnt_u16	43000
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	50681
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	29578
k_ISDYNABRChkSumValidThresh_Cnt_u16	63969
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	374
k_ISDYNABRMsgCountValidThresh_Cnt_u16	3197
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	36415
k_ISDYNABRMsgLenValidThresh_Cnt_u16	58530
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	65044
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	29401
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	9486
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	3147
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	3495
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	35694
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	34343
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	9320
k_ISDYNVOLChkSumValidThresh_Cnt_u16	8627
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	26519
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	9076
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	50826
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	64221
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	36374
k_IgnOnTimeout_mS_u16	27812
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	195.637299
k_PowerCutVehSpdLowThresh_Kph_f32	110.020103
k_PowerCutVehSpdLowTimeout_mS_u16	23226
k_VBattMaxAAS_Volt_f32	13.7250004
k_VBattMaxBSI_Volt_f32	21.6394997
k_VBattMaxCAV_Volt_f32	1.18649995
k_VBattMaxCMM388_Volt_f32	13.1091003
k_VBattMaxCMM_Volt_f32	31.5921993
k_VBattMaxESP_Volt_f32	3.86689997
k_VBattMinAAS_Volt_f32	24.7782001
k_VBattMinBSI_Volt_f32	3.86689997
k_VBattMinCAV_Volt_f32	25.5189991
k_VBattMinCMM388_Volt_f32	21.0664997
k_VBattMinCMM_Volt_f32	8.86390018
k_VBattMinESP_Volt_f32	31.5921993
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	27780
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	12927
k_VitesseVehicleBVRampValidThresh_Cnt_u16	13705
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	58322
k_VitesseVehicleBVSigValidThresh_Cnt_u16	9533
k_VitesseVehicleBVSpeedPassThresh_kph_f32	482.595886
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	42084
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	31683
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2556041216
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	38041
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	0
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	106
target_SrlComInput_Per1_Batt_Volt_f32.value	30.6207008
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2692974592
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	39
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.976521909
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2035759104
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	98
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1062033408
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	184
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3063117824
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	657037312
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3641686016
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	217
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	340121600
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	550238208
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	31
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	113
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	151
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	176
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	246
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	255
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	255
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	251
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1681561600
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	13
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	117
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	149
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	200
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	202
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	212
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	229
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	231
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	162
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3779737600
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	90
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1992316928
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	223
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2105964544
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	35
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	149
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	188
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	224
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	85395456
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3803
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.243655264
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	610964
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	152.556503
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	24303

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	0	0	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	0	0	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2309	2309	✔
AngleVolantMsgTimer_mS_M_u32	0	0	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	0	0	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	0	0	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	0	0	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	0	0	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	0	0	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	0	0	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	0	0	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	0	0	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	0	0	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	0	0	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	63111	63111	✔
CONSANGLECPK_HwDeg_M_f32	451.958099	451.958099 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	63111	63111	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3571673088	3571673088	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	56766	56766	✔
CityParkInputConsistentCount_Cnt_M_u16	58132	58132	✔
CityParkInputInvalidCount_Cnt_M_u16	30895	30895	✔
CityParkInputMsgTimer_mS_M_u32	0	0	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	0	0	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	0	0	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	0	0	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	0	0	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	0	0	✔
ESPNTCEnableTimer_mS_M_u32	0	0	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	0	0	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1235	1235	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	0	0	✔
ElecIntTimer_mS_M_u32[1]	979	979	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	0	0	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	0	0	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	0	0	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	0	0	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	0	0	✔
ISDATDIRASentFltAcc_Cnt_M_u16	5639	5639	✔
ISDATDIRASentTimer_mS_M_u32	0	0	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	0	0	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	15	15	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	0	0	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	1	1	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	0	0	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	0	0	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	0	0	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	10	10	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	0	0	✔
IgnOnTimer_mS_M_u32	3391961088	3391961088	✔
IgnTimeOff_Sec_M_u32	401958722	401958722	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	4	4	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	26	26	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2035759104	2035759104	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	98	98	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1062033408	1062033408	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	184	184	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3063117824	3063117824	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	99	99	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	657037312	657037312	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4151343104	4151343104	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	217	217	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	340121600	340121600	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	51	51	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	550238208	550238208	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	251	251	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1681561600	1681561600	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	162	162	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3779737600	3779737600	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	90	90	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1992316928	1992316928	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	223	223	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2105964544	2105964544	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	85395456	85395456	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	547.98291	547.98291	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	8	8	✔
VVHTYPE2Count_Cnt_M_u08	9	9	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	253.741104	253.741104	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	18.3033009	18.3033009	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	63111	63111	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	401958722	401958722	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	451.958099	451.958099 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.497 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4100557568
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	27410
AASNodeAbsentTimer_mS_M_u32	2241673984
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	23368
ANGLEVOLANTSigValidCount_Cnt_M_u16	43443
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	64051
AngleVolantMsgTimer_mS_M_u32	4100557568
AngleVolantValidCount_Cnt_M_u16	1230
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	1224735488
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2700114688
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2489101056
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2226809600
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	31707
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	790571776
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	62353
CAVNodeAbsentTimer_mS_M_u32	2503236352
CDD_SrlComVehSpd_Kph_G_f32	220.9384
CMM388NTCEnableTimer_mS_M_u32	2395839232
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	4282538752
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	40639
CMMNodeAbsentTimer_mS_M_u32	1126984448
CONSANGLECPKSigInvalidCount_Cnt_M_u16	19431
CONSANGLECPKSigValidCount_Cnt_M_u16	30690
CONSANGLECPK_Cnt_M_u16	31337
CONSANGLECPK_HwDeg_M_f32	502.832703
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	31337
CPKVehicleSpeedMsgTimer_mS_M_u32	1955891968
CPKVehicleSpeedValidCount_Cnt_M_u16	40172
CityParkInputConsistentCount_Cnt_M_u16	21634
CityParkInputInvalidCount_Cnt_M_u16	4272
CityParkInputMsgTimer_mS_M_u32	2035759104
CityParkInputValidCount_Cnt_M_u16	10

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3260103424
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	2246
ComputerRazGCTSigInvalidTimer_mS_M_u32	2000608000
ComputerRazGCTSigValidCount_Cnt_M_u16	37563
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	52476
DMDFCTCPKSigValidCount_Cnt_M_u16	15344
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	9762
DMDRELAXECPKSigValidCount_Cnt_M_u16	50189
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	34824
DateInvalidTimer_mS_M_u32	2700114688
DiagMuxOnAbsentTimer_mS_M_u32	2536393472
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2226809600
ESPNTCEnableTimer_mS_M_u32	1748122368
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	54102
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	88
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	8
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3285789440
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	24977
EtatMTSigValidCount_Cnt_M_u16	7001
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	9409
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	8252
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	26622
ISDAT4V2BSI552MsgTimer_mS_M_u32	1591765760
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	22330
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	22505
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	7001
ISDATBSI3F2MsgTimer_mS_M_u32	3058977536
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	38053
ISDATBSI412MsgLenValidCount_Cnt_M_u16	2885
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	24977
ISDATBSI412MsgTimer_mS_M_u32	294619904
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	55667
ISDATBSI432MsgLenValidCount_Cnt_M_u16	27914
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	58310
ISDATDIRASentFltAcc_Cnt_M_u16	35530
ISDATDIRASentTimer_mS_M_u32	1955891968
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	51727
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	1230
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	17679
ISDYN2CMMMsgTimer_mS_M_u32	2904832768
ISDYNAASChkSumInvalidCount_Cnt_M_u16	12780
ISDYNAASChkSumValidCount_Cnt_M_u16	39927
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	31457
ISDYNAASMsgCount_Cnt_M_u08	14
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	32600
ISDYNAASMsgLenValidCount_Cnt_M_u16	14395
ISDYNAASMsgTimeValidCount_Cnt_M_u16	12780
ISDYNAASMsgTimer_mS_M_u32	874093312
ISDYNABRChkSumInvalidCount_Cnt_M_u16	50201
ISDYNABRChkSumValidCount_Cnt_M_u16	59244
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	19583
ISDYNABRMsgCountValidCount_Cnt_M_u16	36554
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	58746
ISDYNABRMsgLenValidCount_Cnt_M_u16	10677
ISDYNABRMsgTimeValidCount_Cnt_M_u16	31337
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	47707
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	7001
ISDYNCMM208MsgTimer_mS_M_u32	3229154048

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	11023
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	47707
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	62708
ISDYNCMM388MsgTimer_mS_M_u32	1833114368
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	33549
ISDYNVOLChkSumValidCount_Cnt_M_u16	57224
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	49954
ISDYNVOLMsgCountValidCount_Cnt_M_u16	41622
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	13251
ISDYNVOLMsgLenValidCount_Cnt_M_u16	9246
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	40639
ISDYNVOLMsgTimer_mS_M_u32	948624128
IgnOnTimer_mS_M_u32	3220642560
IgnTimeOff_Sec_M_u32	2075624666
ManVehSpd_Kph_M_f32	2.52920008
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	119
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	8
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	91
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1505905408
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	208
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	323988224
PrevISDATBSI412MsgDLCError_Cnt_M_u08	238
PrevISDATBSI412MsgRxTime_MSec_M_u32	3005831936
PrevISDATBSI432MsgDLCError_Cnt_M_u08	168
PrevISDATBSI432MsgRxTime_MSec_M_u32	1091975936
PrevISDATDIRAMsgTxTime_MSec_M_u32	1429035776
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	139
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2893933312
PrevISDYNAASMsgDLCError_Cnt_M_u08	114
PrevISDYNAASMsgRxTime_MSec_M_u32	1882249984
PrevISDYNABRMsgDLCError_Cnt_M_u08	26
PrevISDYNABRMsgRxTime_MSec_M_u32	2576292608
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	106
PrevISDYNCMM208MsgRxTime_MSec_M_u32	2200558336
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	178
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1151154944
PrevISDYNVOLMsgDLCError_Cnt_M_u08	31
PrevISDYNVOLMsgRxTime_MSec_M_u32	3503971072
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3182791424
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	600.67041
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	29566
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	7393
VVHTYPE1Count_Cnt_M_u08	5
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	63339
VitesseVehicleBVRampValidCount_Cnt_M_u16	43150
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	16053
VitesseVehicleBVSigValidCount_Cnt_M_u16	13536
VitesseVehicleBV_Kph_M_f32	578.364624
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	62708
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	16951

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	232.226501
k_AASNTCEnableTimeout_mS_u16	40404
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	31277
k_AASNodeTimeout_mS_u16	23521
k_ABSNodeTimeout_mS_u16	17205
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	39186
k_ANGLEVOLANTSigValidThresh_Cnt_u16	62953
k_AngleVolantInvalidThresh_Cnt_u16	20964
k_AngleVolantValidThresh_Cnt_u16	4272
k_BSI552MsgTimeout_mS_u16	62962
k_BSINTCEnableTimeout_mS_u16	58123
k_BSINodeAbsentDiag_Cnt_str.Threshold	33043
k_BSINodeAbsentDiag_Cnt_str.PStep	12643
k_BSINodeAbsentDiag_Cnt_str.NStep	27671
k_BSINodeAbsentTimeout_mS_u16	24011
k_BSINodeTimeout_mS_u16	58310
k_BattOvHi_Volt_f32	22.1368008
k_BattOvLo_Volt_f32	24.2406006
k_BattUvHi_Volt_f32	10.5035
k_BattUvLo_Volt_f32	31.5
k_CAVNTCEnableTimeout_mS_u16	56942
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	65207
k_CAVNodeTimeout_mS_u16	18739
k_CMM388MsgTimeout_mS_u16	59922
k_CMM388NTCEnableTimeout_mS_u16	35934
k_CMMNTCEnableTimeout_mS_u16	60626
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	29315
k_CONSANGLECPKMax_HwDeg_f32	710.987488
k_CONSANGLECPKMin_HwDeg_f32	-701.153625
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	62452
k_CONSANGLECPKSigValidThresh_Cnt_u16	33079
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	40687
k_CPKVehicleSpeedValidThresh_Cnt_u16	10540
k_CityParkInputInvalidThresh_Cnt_u16	7591
k_CityParkInputValidThresh_Cnt_u16	21634
k_ComputerRazGCTSigValidThresh_Cnt_u16	14120
k_CptTemporelSigValidThresh_Cnt_u16	61015
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	25722
k_DMDFCTCPKSigValidThresh_Cnt_u16	59573
k_DMDFCTCPKValidCount_Cnt_u16	59203
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	17679
k_DMDRELAXECPKSigValidThresh_Cnt_u16	44099
k_DMDRelaxeConsistentThresh_Cnt_u16	33105
k_DateValidThresh_Cnt_u16	26622
k_DefaultVehSpd_Kph_f32	7.69990015
k_DiagMuxOnAbsentTimeout_mS_u16	26535
k_EMNodeTimeout_mS_u16	22760
k_ESPNTCEnableTimeout_mS_u16	6877
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	37099
k_EtatMTSigInvalidThresh_Cnt_u16	31604
k_EtatMTSigValidThresh_Cnt_u16	64775
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	57046
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	6909
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	62063
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	3067
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	52074
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	3417
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	58804
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	55307
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	21543
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	50173

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	13628
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	16133
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	55141
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	56190
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	64051
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	25337
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	49945
k_ISDYNAASChkSumValidThresh_Cnt_u16	9836
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	52095
k_ISDYNAASMsgCountValidThresh_Cnt_u16	19914
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	61389
k_ISDYNAASMsgLenValidThresh_Cnt_u16	25493
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	51793
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	41888
k_ISDYNABRChkSumValidThresh_Cnt_u16	22619
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	64219
k_ISDYNABRMsgCountValidThresh_Cnt_u16	57734
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	56767
k_ISDYNABRMsgLenValidThresh_Cnt_u16	21078
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	10433
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	39730
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	27858
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	17052
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	55880
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	26803
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	51272
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	22212
k_ISDYNVOLChkSumValidThresh_Cnt_u16	30372
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	56695
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	12832
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	29149
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	3237
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	22588
k_IgnOnTimeout_mS_u16	28176
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	87.3331985
k_PowerCutVehSpdLowThresh_Kph_f32	96.1847
k_PowerCutVehSpdLowTimeout_mS_u16	55760
k_VBattMaxAAS_Volt_f32	18.8624001
k_VBattMaxBSI_Volt_f32	32
k_VBattMaxCAV_Volt_f32	28.7310009
k_VBattMaxCMM388_Volt_f32	9.26980019
k_VBattMaxCMM_Volt_f32	14.3739996
k_VBattMaxESP_Volt_f32	28.5529003
k_VBattMinAAS_Volt_f32	15.5768995
k_VBattMinBSI_Volt_f32	28.5529003
k_VBattMinCAV_Volt_f32	20.6700001
k_VBattMinCMM388_Volt_f32	13.2090998
k_VBattMinCMM_Volt_f32	5.18300009
k_VBattMinESP_Volt_f32	14.3739996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	16240
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	50495
k_VitesseVehicleBVRampValidThresh_Cnt_u16	49698
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	40584
k_VitesseVehicleBVSigValidThresh_Cnt_u16	29191
k_VitesseVehicleBVSpeedPassThresh_kph_f32	510.3237
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	62097
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	54324
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	2700114688
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	52138
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	4294967295
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	178
target_SrlComInput_Per1_Batt_Volt_f32.value	23.4808998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	976497408
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	142
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.573455751
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	239
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3665369856
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	118
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	2299968256
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	22
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1673812736
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	246
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2457991936
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1028627200
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	21
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	2351774464
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	165
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2803555072
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	3
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	49
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	51
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	72
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	73
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	96
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	123
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	251
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	178
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1599011584
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	5
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	96
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	97
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	122
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	170
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	207
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	215
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	226
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	782244608
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	27
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1857927936
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	44
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2599115520
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	17
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	20
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	32
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	40
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	91
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	108
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	109
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	133
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3128535808
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2916
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.10775204
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	448834
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	105.8256
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	44784

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	4294967295	4294967295	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	4294967295	4294967295	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	4294967295	4294967295	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	4294967295	4294967295	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	4294967295	4294967295	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	4294967295	4294967295	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	31337	31337	✔
CONSANGLECPK_HwDeg_M_f32	502.832703	502.832703 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	4294967295	4294967295	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	4294967295	4294967295	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	4294967295	4294967295	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	4294967295	4294967295	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	4294967295	4294967295	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	4294967295	4294967295	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	4294967295	4294967295	✔
ESPNTCEnableTimer_mS_M_u32	4294967295	4294967295	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	4294967295	4294967295	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔
EffacDefaultDiagTimer_mS_M_u32[1]	88	88	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	4294967295	4294967295	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	8	8	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	4294967295	4294967295	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDATDIRASentFltAcc_Cnt_M_u16	41895	41895	✔
ISDATDIRASentTimer_mS_M_u32	4294967295	4294967295	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	14	14	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	4294967295	4294967295	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	4294967295	4294967295	✔
IgnOnTimer_mS_M_u32	4294967295	4294967295	✔
IgnTimeOff_Sec_M_u32	2075624666	2075624666	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	8	8	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	239	239	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3665369856	3665369856	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	118	118	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2299968256	2299968256	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	22	22	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1673812736	1673812736	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	246	246	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2457991936	2457991936	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1429035776	1429035776	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	21	21	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2351774464	2351774464	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	165	165	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2803555072	2803555072	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	178	178	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1599011584	1599011584	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	226	226	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	782244608	782244608	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	27	27	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1857927936	1857927936	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	44	44	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2599115520	2599115520	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3128535808	3128535808	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	600.67041	600.67041	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	5	5	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	578.364624	578.364624	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	232.226501	232.226501	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	31337	31337	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2075624666	2075624666	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	502.832703	502.832703 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	7.69990015	7.69990015	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.498 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1313743360
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	11348
AASNodeAbsentTimer_mS_M_u32	1165169152
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	21937
ANGLEVOLANTSigValidCount_Cnt_M_u16	21295
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	17137
AngleVolantMsgTimer_mS_M_u32	1313743360
AngleVolantValidCount_Cnt_M_u16	39326
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	4132098560
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	1350128128
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	2733949440
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	2027651584
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	65528
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4239213056
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	63319
CAVNodeAbsentTimer_mS_M_u32	3677204992
CDD_SrlComVehSpd_Kph_G_f32	67.3424988
CMM388NTCEnableTimer_mS_M_u32	3814846976
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	1426305536
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	64395
CMMNodeAbsentTimer_mS_M_u32	2240119296
CONSANGLECPKSigInvalidCount_Cnt_M_u16	28372
CONSANGLECPKSigValidCount_Cnt_M_u16	5027
CONSANGLECPK_Cnt_M_u16	59406
CONSANGLECPK_HwDeg_M_f32	-141.891098
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	59406
CPKVehicleSpeedMsgTimer_mS_M_u32	969744896
CPKVehicleSpeedValidCount_Cnt_M_u16	38924

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	31362
CityParkInputInvalidCount_Cnt_M_u16	52984
CityParkInputMsgTimer_mS_M_u32	3665369856
CityParkInputValidCount_Cnt_M_u16	4
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1599541760
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	9016
ComputerRazGCTSigInvalidTimer_mS_M_u32	2131636736
ComputerRazGCTSigValidCount_Cnt_M_u16	58327
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	51732
DMDFCTCPKSigValidCount_Cnt_M_u16	34298
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56611
DMDRELAXECPKSigValidCount_Cnt_M_u16	60449
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	32369
DateInvalidTimer_mS_M_u32	1350128128
DiagMuxOnAbsentTimer_mS_M_u32	1761600000
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2027651584
ESPNTCEnableTimer_mS_M_u32	833884672
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	63110
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	37
EffacDefaultDiagTimer_mS_M_u32[1]	87
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	20
ElecIntTimer_mS_M_u32[1]	21
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2793357824
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	52245
EtatMTSigValidCount_Cnt_M_u16	63359
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	52294
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	661
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	47568
ISDAT4V2BSI552MsgTimer_mS_M_u32	40468992
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	9882
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	7501
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	63359
ISDATBSI3F2MsgTimer_mS_M_u32	596500992
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	11096
ISDATBSI412MsgLenValidCount_Cnt_M_u16	32827
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	52245
ISDATBSI412MsgTimer_mS_M_u32	249307648
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	7023
ISDATBSI432MsgLenValidCount_Cnt_M_u16	63850
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	15032
ISDATDIRASentFltAcc_Cnt_M_u16	21932
ISDATDIRASentTimer_mS_M_u32	969744896
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	4380
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	39326
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	28123
ISDYN2CMMMsgTimer_mS_M_u32	2866680320
ISDYNAASChkSumInvalidCount_Cnt_M_u16	49094
ISDYNAASChkSumValidCount_Cnt_M_u16	60005
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	17253
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	12290
ISDYNAASMsgLenValidCount_Cnt_M_u16	52760
ISDYNAASMsgTimeValidCount_Cnt_M_u16	49094
ISDYNAASMsgTimer_mS_M_u32	595456512
ISDYNABRChkSumInvalidCount_Cnt_M_u16	63166
ISDYNABRChkSumValidCount_Cnt_M_u16	5508
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	31757
ISDYNABRMsgCountValidCount_Cnt_M_u16	7660
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	44571
ISDYNABRMsgLenValidCount_Cnt_M_u16	2602
ISDYNABRMsgTimeValidCount_Cnt_M_u16	59406

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	43890
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	2127
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	63359
ISDYNCMM208MsgTimer_mS_M_u32	3017789952
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	43890
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	2127
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	57644
ISDYNCMM388MsgTimer_mS_M_u32	4261507584
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	57698
ISDYNVOLChkSumValidCount_Cnt_M_u16	62641
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	65442
ISDYNVOLMsgCountValidCount_Cnt_M_u16	27144
ISDYNVOLMsgCount_Cnt_M_u08	11
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	51519
ISDYNVOLMsgLenValidCount_Cnt_M_u16	41197
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	64395
ISDYNVOLMsgTimer_mS_M_u32	1797927424
IgnOnTimer_mS_M_u32	3588583936
IgnTimeOff_Sec_M_u32	1263695408
ManVehSpd_Kph_M_f32	134.812607
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	0
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	120
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	194
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1900274176
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	255
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2988163584
PrevISDATBSI412MsgDLCError_Cnt_M_u08	98
PrevISDATBSI412MsgRxTime_MSec_M_u32	2504962560
PrevISDATBSI432MsgDLCError_Cnt_M_u08	47
PrevISDATBSI432MsgRxTime_MSec_M_u32	923275776
PrevISDATDIRAMsgTxTime_MSec_M_u32	3208819200
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	24
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1871774208
PrevISDYNAASMsgDLCError_Cnt_M_u08	110
PrevISDYNAASMsgRxTime_MSec_M_u32	3694670336
PrevISDYNABRMsgDLCError_Cnt_M_u08	13
PrevISDYNABRMsgRxTime_MSec_M_u32	2837279232
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	63
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3343725056
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	132
PrevISDYNCMM388MsgRxTime_MSec_M_u32	141758976
PrevISDYNVOLMsgDLCError_Cnt_M_u08	33
PrevISDYNVOLMsgRxTime_MSec_M_u32	1077654016
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	577380864
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	286.975403
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	27536
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	14374
VVHTYPE1Count_Cnt_M_u08	7
VVHTYPE2Count_Cnt_M_u08	8
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	54217
VitesseVehicleBVRampValidCount_Cnt_M_u16	35103
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	40810

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	42408
VitesseVehicleBV_Kph_M_f32	443.626801
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	57644
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	16931
VitesseVehiculeRoues_Kph_M_f32	45.0153999
k_AASNTCEnableTimeout_mS_u16	59853
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	30081
k_AASNodeTimeout_mS_u16	31526
k_ABSNodeTimeout_mS_u16	35689
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	6290
k_ANGLEVOLANTSigValidThresh_Cnt_u16	39629
k_AngleVolantInvalidThresh_Cnt_u16	13020
k_AngleVolantValidThresh_Cnt_u16	52984
k_BSI552MsgTimeout_mS_u16	54002
k_BSINTCEnableTimeout_mS_u16	24231
k_BSINodeAbsentDiag_Cnt_str.Threshold	28392
k_BSINodeAbsentDiag_Cnt_str.PStep	49975
k_BSINodeAbsentDiag_Cnt_str.NStep	2138
k_BSINodeAbsentTimeout_mS_u16	30761
k_BSINodeTimeout_mS_u16	15032
k_BattOvHi_Volt_f32	1.10239995
k_BattOvLo_Volt_f32	13.802
k_BattUvHi_Volt_f32	3.31170011
k_BattUvLo_Volt_f32	20.1103992
k_CAVNTCEnableTimeout_mS_u16	56766
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	60901
k_CAVNodeTimeout_mS_u16	42736
k_CMM388MsgTimeout_mS_u16	44884
k_CMM388NTCEnableTimeout_mS_u16	63600
k_CMMNTCEnableTimeout_mS_u16	50642
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	57663
k_CONSANGLECPKMax_HwDeg_f32	287.960785
k_CONSANGLECPKMin_HwDeg_f32	-619.04657
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	58412
k_CONSANGLECPKSigValidThresh_Cnt_u16	34083
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	27132
k_CPKVehicleSpeedValidThresh_Cnt_u16	18883
k_CityParkInputInvalidThresh_Cnt_u16	41492
k_CityParkInputValidThresh_Cnt_u16	31362
k_ComputerRazGCTSigValidThresh_Cnt_u16	48848
k_CptTemporelSigValidThresh_Cnt_u16	37379
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	12571
k_DMDFCTCPKSigValidThresh_Cnt_u16	52522
k_DMDFCTCPKValidCount_Cnt_u16	24000
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	28123
k_DMDRELAXECPKSigValidThresh_Cnt_u16	16641
k_DMDRelaxeConsistentThresh_Cnt_u16	31191
k_DateValidThresh_Cnt_u16	47568
k_DefaultVehSpd_Kph_f32	194.942398
k_DiagMuxOnAbsentTimeout_mS_u16	38996
k_EMNodeTimeout_mS_u16	35793
k_ESPNTCEnableTimeout_mS_u16	45427
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	9735
k_EtatMTSigInvalidThresh_Cnt_u16	64685
k_EtatMTSigValidThresh_Cnt_u16	179
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	1607
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	10898
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	38075
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	19543
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	1738
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	37180

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	15020
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	64615
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	31571
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	23378
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	16468
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	47419
k_ISDATDIRASentDiag_Cnt_str.Threshold	1170
k_ISDATDIRASentDiag_Cnt_str.PStep	4955
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	60634
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	2000
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	17137
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	18719
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	63934
k_ISDYNAASChkSumValidThresh_Cnt_u16	22660
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	65293
k_ISDYNAASMsgCountValidThresh_Cnt_u16	57580
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	17314
k_ISDYNAASMsgLenValidThresh_Cnt_u16	13322
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	48533
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	35753
k_ISDYNABRChkSumValidThresh_Cnt_u16	38456
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	33528
k_ISDYNABRMsgCountValidThresh_Cnt_u16	47030
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	16011
k_ISDYNABRMsgLenValidThresh_Cnt_u16	31110
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	36357
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	50292
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	38609
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	29429
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	55473
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	5679
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	2096
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	8443
k_ISDYNVOLChkSumValidThresh_Cnt_u16	31262
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	39971
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	1384
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	52017
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	21403
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	24854
k_IgnOnTimeout_mS_u16	2839
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	132.542496
k_PowerCutVehSpdLowThresh_Kph_f32	81.9878006
k_PowerCutVehSpdLowTimeout_mS_u16	9689
k_VBattMaxAAS_Volt_f32	8.90250015
k_VBattMaxBSI_Volt_f32	23.5426998
k_VBattMaxCAV_Volt_f32	29.5379009
k_VBattMaxCMM388_Volt_f32	6.00169992
k_VBattMaxCMM_Volt_f32	7.02790022
k_VBattMaxESP_Volt_f32	6.48239994
k_VBattMinAAS_Volt_f32	28.1368999
k_VBattMinBSI_Volt_f32	6.48239994
k_VBattMinCAV_Volt_f32	23.9115009
k_VBattMinCMM388_Volt_f32	9.7493
k_VBattMinCMM_Volt_f32	2.72889996
k_VBattMinESP_Volt_f32	7.02790022
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	9210
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	2892
k_VitesseVehicleBVRampValidThresh_Cnt_u16	674
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	47025
k_VitesseVehicleBVSigValidThresh_Cnt_u16	30195
k_VitesseVehicleBVSpeedPassThresh_kph_f32	104.8591
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	64087
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	7725
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	1350128128
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65036
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	163190528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	132
target_SrlComInput_Per1_Batt_Volt_f32.value	13.6875
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1869496832
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	186
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	1
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.213709176
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	232
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	241136128
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	48
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	17207808
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	112
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2944250368
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	47
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2714030592
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1608249856
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	77
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1908609536
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	188
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1601843712
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	26
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	36
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	38
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	150
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	162
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	212
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	229
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	110
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	2942161408
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	12
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	24
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	64
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	145
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	154
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	168
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	186
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	250
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	106
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1844081152
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2886832640
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	137
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1711845888
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	6
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	63
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	73
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	76
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	118
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	180
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	198
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	198
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3835544064
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1587
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.601339877
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	979523
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	153.315201
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	314

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	163190528	163190528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	17137	17137	✔
AngleVolantMsgTimer_mS_M_u32	163190528	163190528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	163190528	163190528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	163190528	163190528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	163190528	163190528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	59406	59406	✔
CONSANGLECPK_HwDeg_M_f32	-141.891098	-141.891098 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	59406	59406	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	969744896	969744896	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	38924	38924	✔
CityParkInputConsistentCount_Cnt_M_u16	31362	31362	✔
CityParkInputInvalidCount_Cnt_M_u16	52984	52984	✔
CityParkInputMsgTimer_mS_M_u32	163190528	163190528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	163190528	163190528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	163190528	163190528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	163190528	163190528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	163190528	163190528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	163190528	163190528	✔
ESPNTCEnableTimer_mS_M_u32	163190528	163190528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	163190528	163190528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	37	37	✔
EffacDefaultDiagTimer_mS_M_u32[1]	87	87	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	163190528	163190528	✔
ElecIntTimer_mS_M_u32[1]	21	21	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	163190528	163190528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	163190528	163190528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	1170	1170	✔
ISDATDIRASentTimer_mS_M_u32	163190528	163190528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	163190528	163190528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	11	11	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	163190528	163190528	✔
IgnOnTimer_mS_M_u32	3588583936	3588583936	✔
IgnTimeOff_Sec_M_u32	1263695408	1263695408	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	1	1	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	1	1	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	232	232	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	241136128	241136128	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	48	48	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	17207808	17207808	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	112	112	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2944250368	2944250368	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	47	47	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2714030592	2714030592	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3208819200	3208819200	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	77	77	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1908609536	1908609536	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	188	188	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1601843712	1601843712	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	110	110	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	2942161408	2942161408	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	106	106	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1844081152	1844081152	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	158	158	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2886832640	2886832640	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	137	137	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1711845888	1711845888	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3835544064	3835544064	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	286.975403	286.975403	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	7	7	✔
VVHTYPE2Count_Cnt_M_u08	8	8	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	443.626801	443.626801	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	45.0153999	45.0153999	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	59406	59406	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1263695408	1263695408	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-141.891098	-141.891098 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.499 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	867982592
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	54184
AASNodeAbsentTimer_mS_M_u32	1309510912
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	27027
ANGLEVOLANTSigValidCount_Cnt_M_u16	46808
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	17361
AngleVolantMsgTimer_mS_M_u32	867982592
AngleVolantValidCount_Cnt_M_u16	56394
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1250315520
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	368758016
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	2554887424
BSI432NTCsEnabled_Cnt_M_lgc	1
BSI552NTCEnableTimer_mS_M_u32	563363072
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	18110
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	220134656
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	17696
CAVNodeAbsentTimer_mS_M_u32	1063103744
CDD_SrlComVehSpd_Kph_G_f32	646.346802
CMM388NTCEnableTimer_mS_M_u32	1203825920
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2849746176
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	10050
CMMNodeAbsentTimer_mS_M_u32	597048576
CONSANGLECPKSigInvalidCount_Cnt_M_u16	23848
CONSANGLECPKSigValidCount_Cnt_M_u16	62588
CONSANGLECPK_Cnt_M_u16	58171
CONSANGLECPK_HwDeg_M_f32	439.267487
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	58171
CPKVehicleSpeedMsgTimer_mS_M_u32	759127296
CPKVehicleSpeedValidCount_Cnt_M_u16	44201
CityParkInputConsistentCount_Cnt_M_u16	51614

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	12606
CityParkInputMsgTimer_mS_M_u32	241136128
CityParkInputValidCount_Cnt_M_u16	6
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2422312192
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	32508
ComputerRazGCTSigInvalidTimer_mS_M_u32	1975266560
ComputerRazGCTSigValidCount_Cnt_M_u16	8607
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	45034
DMDFCTCPKSigValidCount_Cnt_M_u16	25079
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	6973
DMDRELAXECPKSigValidCount_Cnt_M_u16	13314
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	57937
DateInvalidTimer_mS_M_u32	368758016
DiagMuxOnAbsentTimer_mS_M_u32	3668385024
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	563363072
ESPNTCEnableTimer_mS_M_u32	3444215040
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	27667
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	65535
EffacDefaultDiagTimer_mS_M_u32[1]	95535
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	89
ElecIntTimer_mS_M_u32[1]	901
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	3618176256
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	27303
EtatMTSigValidCount_Cnt_M_u16	56871
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	36050
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	28582
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	40565
ISDAT4V2BSI552MsgTimer_mS_M_u32	1021984000
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	43159
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	55871
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	56871
ISDATBSI3F2MsgTimer_mS_M_u32	1660755200
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	25436
ISDATBSI412MsgLenValidCount_Cnt_M_u16	14964
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	27303
ISDATBSI412MsgTimer_mS_M_u32	2853330176
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	22422
ISDATBSI432MsgLenValidCount_Cnt_M_u16	62311
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	16125
ISDATDIRASentFltAcc_Cnt_M_u16	48673
ISDATDIRASentTimer_mS_M_u32	759127296
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	8209
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	56394
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	41109
ISDYN2CMMMsgTimer_mS_M_u32	2311884032
ISDYNAASChkSumInvalidCount_Cnt_M_u16	24914
ISDYNAASChkSumValidCount_Cnt_M_u16	42807
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	47861
ISDYNAASMsgCount_Cnt_M_u08	4
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	1823
ISDYNAASMsgLenValidCount_Cnt_M_u16	53916
ISDYNAASMsgTimeValidCount_Cnt_M_u16	24914
ISDYNAASMsgTimer_mS_M_u32	4151110912
ISDYNABRChkSumInvalidCount_Cnt_M_u16	62443
ISDYNABRChkSumValidCount_Cnt_M_u16	64855
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	2173
ISDYNABRMsgCountValidCount_Cnt_M_u16	59554
ISDYNABRMsgCount_Cnt_M_u08	14
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	31571
ISDYNABRMsgLenValidCount_Cnt_M_u16	60647
ISDYNABRMsgTimeValidCount_Cnt_M_u16	58171
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	27534

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	52876
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	56871
ISDYNCMM208MsgTimer_mS_M_u32	2781302016
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	27534
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	52876
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	48544
ISDYNCMM388MsgTimer_mS_M_u32	3588386048
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	48510
ISDYNVOLChkSumValidCount_Cnt_M_u16	2386
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	51008
ISDYNVOLMsgCountValidCount_Cnt_M_u16	28109
ISDYNVOLMsgCount_Cnt_M_u08	8
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	6120
ISDYNVOLMsgLenValidCount_Cnt_M_u16	38557
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	10050
ISDYNVOLMsgTimer_mS_M_u32	560475392
IgnOnTimer_mS_M_u32	3728108800
IgnTimeOff_Sec_M_u32	1224898457
ManVehSpd_Kph_M_f32	238.189301
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	118
PrevDMDFCTCPK_Cnt_M_u08	0
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	0
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	221
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3520797952
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	78
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3335748864
PrevISDATBSI412MsgDLCError_Cnt_M_u08	243
PrevISDATBSI412MsgRxTime_MSec_M_u32	3573198080
PrevISDATBSI432MsgDLCError_Cnt_M_u08	153
PrevISDATBSI432MsgRxTime_MSec_M_u32	223251712
PrevISDATDIRAMsgTxTime_MSec_M_u32	656321792
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	39
PrevISDYN2CMMMsgRxTime_MSec_M_u32	4084448512
PrevISDYNAASMsgDLCError_Cnt_M_u08	3
PrevISDYNAASMsgRxTime_MSec_M_u32	2252221696
PrevISDYNABRMsgDLCError_Cnt_M_u08	96
PrevISDYNABRMsgRxTime_MSec_M_u32	1150184704
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	106
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1493118208
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	65
PrevISDYNCMM388MsgRxTime_MSec_M_u32	84774144
PrevISDYNVOLMsgDLCError_Cnt_M_u08	190
PrevISDYNVOLMsgRxTime_MSec_M_u32	3358829824
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	661150976
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	505.341309
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	4
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	3189
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	19570
VVHTYPE1Count_Cnt_M_u08	3
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	63434
VitesseVehicleBVRampValidCount_Cnt_M_u16	32135
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	45160
VitesseVehicleBVSigValidCount_Cnt_M_u16	58221

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBV_Kph_M_f32	422.525085
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	48544
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	49277
VitesseVehiculeRoues_Kph_M_f32	22.3764
k_AASNTCEnableTimeout_mS_u16	39422
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	38049
k_AASNodeTimeout_mS_u16	33650
k_ABSNodeTimeout_mS_u16	65515
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	44077
k_ANGLEVOLANTSigValidThresh_Cnt_u16	23358
k_AngleVolantInvalidThresh_Cnt_u16	36625
k_AngleVolantValidThresh_Cnt_u16	12606
k_BSI552MsgTimeout_mS_u16	2576
k_BSINTCEnableTimeout_mS_u16	28142
k_BSINodeAbsentDiag_Cnt_str.Threshold	22869
k_BSINodeAbsentDiag_Cnt_str.PStep	39892
k_BSINodeAbsentDiag_Cnt_str.NStep	53974
k_BSINodeAbsentTimeout_mS_u16	33833
k_BSINodeTimeout_mS_u16	16125
k_BattOvHi_Volt_f32	9.62959957
k_BattOvLo_Volt_f32	11.9969997
k_BattUvHi_Volt_f32	3.57279992
k_BattUvLo_Volt_f32	4.6880002
k_CAVNTCEnableTimeout_mS_u16	40172
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	6518
k_CAVNodeTimeout_mS_u16	9428
k_CMM388MsgTimeout_mS_u16	19112
k_CMM388NTCEnableTimeout_mS_u16	57172
k_CMMNTCEnableTimeout_mS_u16	43759
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	21289
k_CONSANGLECPKMax_HwDeg_f32	175.370605
k_CONSANGLECPKMin_HwDeg_f32	-401.315186
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	46240
k_CONSANGLECPKSigValidThresh_Cnt_u16	63357
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	36592
k_CPKVehicleSpeedValidThresh_Cnt_u16	29723
k_CityParkInputInvalidThresh_Cnt_u16	51689
k_CityParkInputValidThresh_Cnt_u16	51614
k_ComputerRazGCTSigValidThresh_Cnt_u16	14325
k_CptTemporelSigValidThresh_Cnt_u16	54301
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	62035
k_DMDFCTCPKSigValidThresh_Cnt_u16	41959
k_DMDFCTCPKValidCount_Cnt_u16	19814
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	41109
k_DMDRELAXECPKSigValidThresh_Cnt_u16	3298
k_DMDRelaxeConsistentThresh_Cnt_u16	14944
k_DateValidThresh_Cnt_u16	40565
k_DefaultVehSpd_Kph_f32	202.324203
k_DiagMuxOnAbsentTimeout_mS_u16	27241
k_EMNodeTimeout_mS_u16	14897
k_ESPNTCEnableTimeout_mS_u16	34508
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	42193
k_EtatMTSigInvalidThresh_Cnt_u16	24094
k_EtatMTSigValidThresh_Cnt_u16	47050
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	42511
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	44784
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	40691
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	27488
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	20936
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	49584
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	11743

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	7792
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	51178
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	39279
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	16424
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	4789
k_ISDATDIRASentDiag_Cnt_str.Threshold	11170
k_ISDATDIRASentDiag_Cnt_str.PStep	19555
k_ISDATDIRASentDiag_Cnt_str.NStep	5240
k_ISDATDIRASentTimeout_mS_u16	33175
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	47862
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	17361
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	28616
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	60139
k_ISDYNAASChkSumValidThresh_Cnt_u16	13399
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	32637
k_ISDYNAASMsgCountValidThresh_Cnt_u16	40866
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	40255
k_ISDYNAASMsgLenValidThresh_Cnt_u16	59590
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	4838
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	39593
k_ISDYNABRChkSumValidThresh_Cnt_u16	189
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	48574
k_ISDYNABRMsgCountValidThresh_Cnt_u16	25923
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	24130
k_ISDYNABRMsgLenValidThresh_Cnt_u16	58131
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	56918
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	37321
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	17649
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	38917
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	57491
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	28120
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	26006
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	52851
k_ISDYNVOLChkSumValidThresh_Cnt_u16	39115
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	12092
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	48555
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	56659
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	14803
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	16547
k_IgnOnTimeout_mS_u16	32799
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	116.023903
k_PowerCutVehSpdLowThresh_Kph_f32	83.6878967
k_PowerCutVehSpdLowTimeout_mS_u16	5594
k_VBattMaxAAS_Volt_f32	28.6128998
k_VBattMaxBSI_Volt_f32	20.0769997
k_VBattMaxCAV_Volt_f32	13.9829998
k_VBattMaxCMM388_Volt_f32	0.351200014
k_VBattMaxCMM_Volt_f32	14.2560997
k_VBattMaxESP_Volt_f32	21.9188995
k_VBattMinAAS_Volt_f32	8.77579975
k_VBattMinBSI_Volt_f32	21.9188995
k_VBattMinCAV_Volt_f32	21.2907009
k_VBattMinCMM388_Volt_f32	8.41230011
k_VBattMinCMM_Volt_f32	23.7693005
k_VBattMinESP_Volt_f32	14.2560997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	36472
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	28225
k_VitesseVehicleBVRampValidThresh_Cnt_u16	48704
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	49234
k_VitesseVehicleBVSigValidThresh_Cnt_u16	56139
k_VitesseVehicleBVSpeedPassThresh_kph_f32	442.140106
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	15392
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	30301
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	368758016
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	0
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	65
target_SrlComInput_Per1_Batt_Volt_f32.value	14.7063999
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	4175166720
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	66
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	2
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.959504187
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	194
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	2630380800
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	79
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3377663232
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	53
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	40742144
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	220
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2954382592
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	978513152
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	10
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	152931584
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	98
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2222468352
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	28
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	40
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	191
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	207
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	227
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	254
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	197
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	726486272
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	90
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	116
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	123
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	139
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	147
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	159
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	164
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	240
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	41
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	1780968704
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	244
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3023179008
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	215
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3402411264
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	8
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	9
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	34
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	57
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	136
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	160
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	176
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3075308800
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	3271
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.167670533
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	668729
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	80.9558029

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	29559		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	17362	17362	✔
AngleVolantMsgTimer_mS_M_u32	3402411264	3402411264	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	58171	58171	✔
CONSANGLECPK_HwDeg_M_f32	439.267487	439.267487 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	58171	58171	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	759127296	759127296	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	44201	44201	✔
CityParkInputConsistentCount_Cnt_M_u16	51614	51614	✔
CityParkInputInvalidCount_Cnt_M_u16	12607	12607	✔
CityParkInputMsgTimer_mS_M_u32	2222468352	2222468352	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	3251510528	3251510528	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	95535	95535	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	3251510528	3251510528	✔
ElecIntTimer_mS_M_u32[1]	901	901	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	3618176256	3618176256	✔
EngOnDLCInvalidCount_Cnt_M_u08	3	3	✔
EngOn_Cnt_M_lgc	1	1	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	11170	11170	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	4	4	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	14	14	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	8	8	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	3728108800	3728108800	✔
IgnTimeOff_Sec_M_u32	1224898457	1224898457	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	0	0	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	0	0	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	194	194	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2630380800	2630380800	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	79	79	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3377663232	3377663232	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	53	53	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	40742144	40742144	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	220	220	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2954382592	2954382592	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	656321792	656321792	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	10	10	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	152931584	152931584	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	98	98	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2222468352	2222468352	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	197	197	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	726486272	726486272	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	41	41	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1780968704	1780968704	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	244	244	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3023179008	3023179008	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	215	215	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3402411264	3402411264	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3075308800	3075308800	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	505.341309	505.341309	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	3	3	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	422.525085	422.525085	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	22.3764	22.3764	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	58171	58171	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	1224898457	1224898457	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	439.267487	439.267487 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.500 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	438152192
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	35928
AASNodeAbsentTimer_mS_M_u32	3421117440
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	38040
ANGLEVOLANTSigValidCount_Cnt_M_u16	56202
APARequest_Cnt_M_lgc	0
AngleVolantInvalidCount_Cnt_M_u16	8157
AngleVolantMsgTimer_mS_M_u32	438152192
AngleVolantValidCount_Cnt_M_u16	33011
AngleVolantValid_Cnt_M_lgc	0
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	0
BSI3F2NTCEnableTimer_mS_M_u32	2843728896
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	3106036736
BSI412NTCsEnabled_Cnt_M_lgc	0
BSI432NTCEnableTimer_mS_M_u32	3304672256
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	135662592
BSI552NTCsEnabled_Cnt_M_lgc	0
BSINodeAbsentFltAcc_Cnt_M_u16	26903
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	3765816320
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	49263
CAVNodeAbsentTimer_mS_M_u32	3766074368
CDD_SrlComVehSpd_Kph_G_f32	154.513107
CMM388NTCEnableTimer_mS_M_u32	1682963456
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	419412992
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	19913
CMMNodeAbsentTimer_mS_M_u32	2316307456
CONSANGLECPKSigInvalidCount_Cnt_M_u16	64730
CONSANGLECPKSigValidCount_Cnt_M_u16	42396
CONSANGLECPK_Cnt_M_u16	38239
CONSANGLECPK_HwDeg_M_f32	315.767487
CPKOK_Cnt_M_lgc	1
CPKVehicleSpeedInvalidCount_Cnt_M_u16	38239
CPKVehicleSpeedMsgTimer_mS_M_u32	4187270144
CPKVehicleSpeedValidCount_Cnt_M_u16	19679
CityParkInputConsistentCount_Cnt_M_u16	2295

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputInvalidCount_Cnt_M_u16	41750
CityParkInputMsgTimer_mS_M_u32	2630380800
CityParkInputValidCount_Cnt_M_u16	8
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1424890880
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	55900
ComputerRazGCTSigInvalidTimer_mS_M_u32	3613277184
ComputerRazGCTSigValidCount_Cnt_M_u16	17652
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	55058
DMDFCTCPKSigValidCount_Cnt_M_u16	4012
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	42906
DMDRELAXECPKSigValidCount_Cnt_M_u16	35852
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	20831
DateInvalidTimer_mS_M_u32	3106036736
DiagMuxOnAbsentTimer_mS_M_u32	1079864320
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	135662592
ESPNTCEnableTimer_mS_M_u32	2184387584
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	56855
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	579
EffacDefaultDiagTimer_mS_M_u32[1]	989
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	4
ElecIntTimer_mS_M_u32[1]	751
ElectronicIntegrationCmd_Cnt_M_lgc	0
EngOnAbsentTimer_mS_M_u32	685231104
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	25757
EtatMTSigValidCount_Cnt_M_u16	10459
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	38364
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	23582
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	53810
ISDAT4V2BSI552MsgTimer_mS_M_u32	2383678464
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	49741
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	60435
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	10459
ISDATBSI3F2MsgTimer_mS_M_u32	2136697856
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	14077
ISDATBSI412MsgLenValidCount_Cnt_M_u16	12403
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	25757
ISDATBSI412MsgTimer_mS_M_u32	2400955392
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	3277
ISDATBSI432MsgLenValidCount_Cnt_M_u16	38939
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	34520
ISDATDIRASentFltAcc_Cnt_M_u16	39276
ISDATDIRASentTimer_mS_M_u32	4187270144
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	46813
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	33011
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	28945
ISDYN2CMMMsgTimer_mS_M_u32	3568114688
ISDYNAASChkSumInvalidCount_Cnt_M_u16	2906
ISDYNAASChkSumValidCount_Cnt_M_u16	59500
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	20722
ISDYNAASMsgCount_Cnt_M_u08	11
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	13938
ISDYNAASMsgLenValidCount_Cnt_M_u16	58044
ISDYNAASMsgTimeValidCount_Cnt_M_u16	2906
ISDYNAASMsgTimer_mS_M_u32	88865792
ISDYNABRChkSumInvalidCount_Cnt_M_u16	44305
ISDYNABRChkSumValidCount_Cnt_M_u16	24458
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	33241
ISDYNABRMsgCountValidCount_Cnt_M_u16	36907
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	3673
ISDYNABRMsgLenValidCount_Cnt_M_u16	10331
ISDYNABRMsgTimeValidCount_Cnt_M_u16	38239
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	52286

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	21510
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	10459
ISDYNCMM208MsgTimer_mS_M_u32	3686587392
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	52286
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	21510
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	46321
ISDYNCMM388MsgTimer_mS_M_u32	535526400
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	46040
ISDYNVOLChkSumValidCount_Cnt_M_u16	16154
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	26896
ISDYNVOLMsgCountValidCount_Cnt_M_u16	50218
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	28312
ISDYNVOLMsgLenValidCount_Cnt_M_u16	57658
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	19913
ISDYNVOLMsgTimer_mS_M_u32	2220506112
IgnOnTimer_mS_M_u32	1458535424
IgnTimeOff_Sec_M_u32	603132488
ManVehSpd_Kph_M_f32	27.2073002
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	119
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	9
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	717319168
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	66
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	626543616
PrevISDATBSI412MsgDLCError_Cnt_M_u08	235
PrevISDATBSI412MsgRxTime_MSec_M_u32	3550657536
PrevISDATBSI432MsgDLCError_Cnt_M_u08	209
PrevISDATBSI432MsgRxTime_MSec_M_u32	3525778432
PrevISDATDIRAMsgTxTime_MSec_M_u32	1832303616
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	70
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1886882816
PrevISDYNAASMsgDLCError_Cnt_M_u08	25
PrevISDYNAASMsgRxTime_MSec_M_u32	769145856
PrevISDYNABRMsgDLCError_Cnt_M_u08	87
PrevISDYNABRMsgRxTime_MSec_M_u32	2212985856
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	90
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4187307008
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	224
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2800360448
PrevISDYNVOLMsgDLCError_Cnt_M_u08	108
PrevISDYNVOLMsgRxTime_MSec_M_u32	502774784
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	4011437056
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	336.529785
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	1
StartupTimeCalculated_Cnt_M_lgc	0
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	65136
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	19770
VVHTYPE1Count_Cnt_M_u08	9
VVHTYPE2Count_Cnt_M_u08	1
ValidEngineStatusCount_Cnt_M_u08	2
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	0
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	53361
VitesseVehicleBVRampValidCount_Cnt_M_u16	19963
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	21529
VitesseVehicleBVSigValidCount_Cnt_M_u16	59851

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBV_Kph_M_f32	79.9041977
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	46321
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	15131
VitesseVehiculeRoues_Kph_M_f32	161.239304
k_AASNTCEnableTimeout_mS_u16	15638
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	29678
k_AASNodeTimeout_mS_u16	43066
k_ABSNodeTimeout_mS_u16	11023
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	11016
k_ANGLEVOLANTSigValidThresh_Cnt_u16	31894
k_AngleVolantInvalidThresh_Cnt_u16	60701
k_AngleVolantValidThresh_Cnt_u16	41750
k_BSI552MsgTimeout_mS_u16	27234
k_BSINTCEnableTimeout_mS_u16	10693
k_BSINodeAbsentDiag_Cnt_str.Threshold	37994
k_BSINodeAbsentDiag_Cnt_str.PStep	3118
k_BSINodeAbsentDiag_Cnt_str.NStep	46694
k_BSINodeAbsentTimeout_mS_u16	48853
k_BSINodeTimeout_mS_u16	34520
k_BattOvHi_Volt_f32	31.5
k_BattOvLo_Volt_f32	0.993399978
k_BattUvHi_Volt_f32	15.9510002
k_BattUvLo_Volt_f32	20.5718994
k_CAVNTCEnableTimeout_mS_u16	38924
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	7021
k_CAVNodeTimeout_mS_u16	21974
k_CMM388MsgTimeout_mS_u16	10072
k_CMM388NTCEnableTimeout_mS_u16	6484
k_CMMNTCEnableTimeout_mS_u16	6981
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	13079
k_CONSANGLECPKMax_HwDeg_f32	313.839294
k_CONSANGLECPKMin_HwDeg_f32	-542.979187
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	53233
k_CONSANGLECPKSigValidThresh_Cnt_u16	38427
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	64960
k_CPKVehicleSpeedValidThresh_Cnt_u16	49344
k_CityParkInputInvalidThresh_Cnt_u16	41751
k_CityParkInputValidThresh_Cnt_u16	2295
k_ComputerRazGCTSigValidThresh_Cnt_u16	3123
k_CptTemporelSigValidThresh_Cnt_u16	63097
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	43353
k_DMDFCTCPKSigValidThresh_Cnt_u16	859
k_DMDFCTCPKValidCount_Cnt_u16	62751
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	28945
k_DMDRELAXECPKSigValidThresh_Cnt_u16	31467
k_DMDRelaxeConsistentThresh_Cnt_u16	27249
k_DateValidThresh_Cnt_u16	53810
k_DefaultVehSpd_Kph_f32	120.8508
k_DiagMuxOnAbsentTimeout_mS_u16	14293
k_EMNodeTimeout_mS_u16	51647
k_ESPNTCEnableTimeout_mS_u16	43883
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	56863
k_EtatMTSigInvalidThresh_Cnt_u16	64120
k_EtatMTSigValidThresh_Cnt_u16	48177
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	62563
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	30849
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	7416
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	56818
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	59768
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	27649
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	60914

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	31488
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	3025
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	17091
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	19801
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	7666
k_ISDATDIRASentDiag_Cnt_str.Threshold	37951
k_ISDATDIRASentDiag_Cnt_str.PStep	62140
k_ISDATDIRASentDiag_Cnt_str.NStep	43836
k_ISDATDIRASentTimeout_mS_u16	46093
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	26927
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	8157
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	57463
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	51217
k_ISDYNAASChkSumValidThresh_Cnt_u16	47754
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	7385
k_ISDYNAASMsgCountValidThresh_Cnt_u16	27435
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	277
k_ISDYNAASMsgLenValidThresh_Cnt_u16	51262
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	62878
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	34903
k_ISDYNABRChkSumValidThresh_Cnt_u16	50393
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	1047
k_ISDYNABRMsgCountValidThresh_Cnt_u16	15433
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	43209
k_ISDYNABRMsgLenValidThresh_Cnt_u16	30999
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	56592
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	48756
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	9790
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	30337
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	12184
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	46730
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	26126
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	4536
k_ISDYNVOLChkSumValidThresh_Cnt_u16	12654
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	30876
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	28302
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	48281
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	50647
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	9128
k_IgnOnTimeout_mS_u16	44212
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	176.251602
k_PowerCutVehSpdLowThresh_Kph_f32	57.2594986
k_PowerCutVehSpdLowTimeout_mS_u16	14722
k_VBattMaxAAS_Volt_f32	14.4275999
k_VBattMaxBSI_Volt_f32	32
k_VBattMaxCAV_Volt_f32	15.4881001
k_VBattMaxCMM388_Volt_f32	12.1042004
k_VBattMaxCMM_Volt_f32	18.4393997
k_VBattMaxESP_Volt_f32	10.3718004
k_VBattMinAAS_Volt_f32	26.3402996
k_VBattMinBSI_Volt_f32	10.3718004
k_VBattMinCAV_Volt_f32	22.2787991
k_VBattMinCMM388_Volt_f32	29.0100002
k_VBattMinCMM_Volt_f32	0.0511000007
k_VBattMinESP_Volt_f32	18.4393997
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	30377
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	5647
k_VitesseVehicleBVRampValidThresh_Cnt_u16	33808
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	6682
k_VitesseVehicleBVSigValidThresh_Cnt_u16	51184
k_VitesseVehicleBVSpeedPassThresh_kph_f32	385.764008
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	56175
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	15225
target_Pim_ElecIntData	1
target_Pim_ShutdownTimeData.Time_Sec_u32	3106036736
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	0
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	65535
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1713429248
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	224
target_SrlComInput_Per1_Batt_Volt_f32.value	14.7336998
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	0
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	1363069952
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	245
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	0
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	9
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.360178292
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	80
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3812195328
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	122
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1343855616
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	3611933696
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1086970880
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1419377664
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	20
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3669629952
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	31
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2603236352
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	37
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	73
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	88
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	158
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	168
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	185
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	187
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	225
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	148
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3811236864
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	20
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	112
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	114
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	124
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	142
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	155
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	192
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	238
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3072097280
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	202
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	3413941248
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	51
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3123493888
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	42
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	74
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	125
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	127
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	137
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	154
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	156
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	194
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3152694272
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1475
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.197724476
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	128369
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	199.705994

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value		
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	20842		
Name	**Actual Value**	**Expected Value**	**Result**
AASNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	1713429248	1713429248	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	0	0	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	0	0	✔
BSI3F2NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	38239	38239	✔
CONSANGLECPK_HwDeg_M_f32	315.767487	315.767487 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1713429248	1713429248	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	1713429248	1713429248	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1713429248	1713429248	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1713429248	1713429248	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCEnableTimer_mS_M_u32	1713429248	1713429248	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	579	579	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[1]	989	989	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	1713429248	1713429248	✔
ElecIntTimer_mS_M_u32[1]	751	751	✔
ElectronicIntegrationCmd_Cnt_M_lgc	0	0	✔
EngOnAbsentTimer_mS_M_u32	1713429248	1713429248	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDATDIRASentFltAcc_Cnt_M_u16	37951	37951	✔
ISDATDIRASentTimer_mS_M_u32	1713429248	1713429248	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	11	11	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1713429248	1713429248	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1713429248	1713429248	✔
IgnOnTimer_mS_M_u32	1458535424	1458535424	✔
IgnTimeOff_Sec_M_u32	603132488	603132488	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	80	80	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3812195328	3812195328	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	122	122	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1343855616	1343855616	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	3611933696	3611933696	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	59	59	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1086970880	1086970880	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	1832303616	1832303616	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	20	20	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3669629952	3669629952	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	31	31	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2603236352	2603236352	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	148	148	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3811236864	3811236864	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	88	88	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3072097280	3072097280	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	202	202	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3413941248	3413941248	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	51	51	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3123493888	3123493888	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3152694272	3152694272	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	336.529785	336.529785	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	0	0	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	9	9	✔
VVHTYPE2Count_Cnt_M_u08	1	1	✔
ValidEngineStatusCount_Cnt_M_u08	2	2	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	79.9041977	79.9041977	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	161.239304	161.239304	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	38239	38239	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	603132488	603132488	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	315.767487	315.767487 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	120.8508	120.8508	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

Test Step Call Trace ✔

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	Rte_Call_Ap_SrlComInput_ElecInt_WriteBlock	1	✔
Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	Rte_Call_Ap_SrlComInput_SrlComDriver_SCom_ElecIntStop	1	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.501 (Repeat Count = 1) ✔

Name	Input Value
AASNTCEnableTimer_mS_M_u32	1391836928
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	1606
AASNodeAbsentTimer_mS_M_u32	995127040
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	36740
ANGLEVOLANTSigValidCount_Cnt_M_u16	11886
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	40887
AngleVolantMsgTimer_mS_M_u32	1391836928
AngleVolantValidCount_Cnt_M_u16	64756
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	697249536
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	2762452736
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	3370311424
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	1653382912
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	52743
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	141385472
CAVNTCsEnabled_Cnt_M_lgc	0
CAVNodeAbsentFltAcc_Cnt_M_u16	53375
CAVNodeAbsentTimer_mS_M_u32	1143049984
CDD_SrlComVehSpd_Kph_G_f32	314.730499
CMM388NTCEnableTimer_mS_M_u32	3785281280
CMM388NTCsEnabled_Cnt_M_lgc	1
CMMNTCEnableTimer_mS_M_u32	848269056
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	36144
CMMNodeAbsentTimer_mS_M_u32	1151246080
CONSANGLECPKSigInvalidCount_Cnt_M_u16	36287
CONSANGLECPKSigValidCount_Cnt_M_u16	18233
CONSANGLECPK_Cnt_M_u16	17392
CONSANGLECPK_HwDeg_M_f32	21.5275993
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17392
CPKVehicleSpeedMsgTimer_mS_M_u32	1351663360
CPKVehicleSpeedValidCount_Cnt_M_u16	536

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputConsistentCount_Cnt_M_u16	29928
CityParkInputInvalidCount_Cnt_M_u16	13195
CityParkInputMsgTimer_mS_M_u32	3812195328
CityParkInputValidCount_Cnt_M_u16	7
ClearDTCs_Cnt_M_lgc	0
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2957274880
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	11322
ComputerRazGCTSigInvalidTimer_mS_M_u32	2440302336
ComputerRazGCTSigValidCount_Cnt_M_u16	62705
CountEtatMT_Cnt_M_u08	1
DMDFCTCPKSigInvalidCount_Cnt_M_u16	34711
DMDFCTCPKSigValidCount_Cnt_M_u16	61833
DMDFCTCPK_Cnt_M_u08	3
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	56958
DMDRELAXECPKSigValidCount_Cnt_M_u16	42216
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	58416
DateInvalidTimer_mS_M_u32	2762452736
DiagMuxOnAbsentTimer_mS_M_u32	2402713344
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	1653382912
ESPNTCEnableTimer_mS_M_u32	2088070912
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	49158
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	1000
EffacDefaultDiagTimer_mS_M_u32[1]	2000
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	45
ElecIntTimer_mS_M_u32[1]	101
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	927424256
EngOnDLCInvalidCount_Cnt_M_u08	3
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	42423
EtatMTSigValidCount_Cnt_M_u16	64701
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	19129
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	43955
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	16887
ISDAT4V2BSI552MsgTimer_mS_M_u32	1217568512
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	17957
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	35988
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	64701
ISDATBSI3F2MsgTimer_mS_M_u32	1245478656
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	63765
ISDATBSI412MsgLenValidCount_Cnt_M_u16	36979
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	42423
ISDATBSI412MsgTimer_mS_M_u32	1811660544
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	24612
ISDATBSI432MsgLenValidCount_Cnt_M_u16	41466
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	24900
ISDATDIRASentFltAcc_Cnt_M_u16	31112
ISDATDIRASentTimer_mS_M_u32	1351663360
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	22390
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	64756
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	30106
ISDYN2CMMMsgTimer_mS_M_u32	3976687360
ISDYNAASChkSumInvalidCount_Cnt_M_u16	4416
ISDYNAASChkSumValidCount_Cnt_M_u16	28106
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	18679
ISDYNAASMsgCount_Cnt_M_u08	9
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	14966
ISDYNAASMsgLenValidCount_Cnt_M_u16	2392
ISDYNAASMsgTimeValidCount_Cnt_M_u16	4416
ISDYNAASMsgTimer_mS_M_u32	4004171520
ISDYNABRChkSumInvalidCount_Cnt_M_u16	8091
ISDYNABRChkSumValidCount_Cnt_M_u16	39917
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	27075
ISDYNABRMsgCountValidCount_Cnt_M_u16	12941
ISDYNABRMsgCount_Cnt_M_u08	10
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	5442
ISDYNABRMsgLenValidCount_Cnt_M_u16	31484
ISDYNABRMsgTimeValidCount_Cnt_M_u16	17392

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	36812
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	58931
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	64701
ISDYNCMM208MsgTimer_mS_M_u32	3336056576
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	36812
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	58931
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	55546
ISDYNCMM388MsgTimer_mS_M_u32	2093764352
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	57541
ISDYNVOLChkSumValidCount_Cnt_M_u16	62143
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	18845
ISDYNVOLMsgCountValidCount_Cnt_M_u16	19471
ISDYNVOLMsgCount_Cnt_M_u08	7
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	21123
ISDYNVOLMsgLenValidCount_Cnt_M_u16	11870
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	36144
ISDYNVOLMsgTimer_mS_M_u32	2055212800
IgnOnTimer_mS_M_u32	3888140032
IgnTimeOff_Sec_M_u32	502409863
ManVehSpd_Kph_M_f32	157.602798
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	120
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	2
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	10
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	191
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1611300608
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	112
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3821395712
PrevISDATBSI412MsgDLCError_Cnt_M_u08	175
PrevISDATBSI412MsgRxTime_MSec_M_u32	1319538432
PrevISDATBSI432MsgDLCError_Cnt_M_u08	119
PrevISDATBSI432MsgRxTime_MSec_M_u32	1553559296
PrevISDATDIRAMsgTxTime_MSec_M_u32	3521810176
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	176
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2405965568
PrevISDYNAASMsgDLCError_Cnt_M_u08	9
PrevISDYNAASMsgRxTime_MSec_M_u32	4127592192
PrevISDYNABRMsgDLCError_Cnt_M_u08	78
PrevISDYNABRMsgRxTime_MSec_M_u32	1087917824
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	228
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3335458560
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	56
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2857398016
PrevISDYNVOLMsgDLCError_Cnt_M_u08	127
PrevISDYNVOLMsgRxTime_MSec_M_u32	61312768
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3288448768
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	491.679688
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	2
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	23164
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	16862
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	2
ValidEngineStatusCount_Cnt_M_u08	0
VehSpdControl_Cnt_M_lgc	0
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	1
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	10361
VitesseVehicleBVRampValidCount_Cnt_M_u16	33691
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	38145

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehicleBVSigValidCount_Cnt_M_u16	18347
VitesseVehicleBV_Kph_M_f32	151.419205
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	55546
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	39485
VitesseVehiculeRoues_Kph_M_f32	639.386475
k_AASNTCEnableTimeout_mS_u16	59595
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	53251
k_AASNodeTimeout_mS_u16	12510
k_ABSNodeTimeout_mS_u16	49056
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	45427
k_ANGLEVOLANTSigValidThresh_Cnt_u16	41097
k_AngleVolantInvalidThresh_Cnt_u16	10996
k_AngleVolantValidThresh_Cnt_u16	13195
k_BSI552MsgTimeout_mS_u16	59496
k_BSINTCEnableTimeout_mS_u16	59708
k_BSINodeAbsentDiag_Cnt_str.Threshold	33477
k_BSINodeAbsentDiag_Cnt_str.PStep	23995
k_BSINodeAbsentDiag_Cnt_str.NStep	29012
k_BSINodeAbsentTimeout_mS_u16	41679
k_BSINodeTimeout_mS_u16	24900
k_BattOvHi_Volt_f32	5.90320015
k_BattOvLo_Volt_f32	8.10379982
k_BattUvHi_Volt_f32	26.6756992
k_BattUvLo_Volt_f32	21.4141998
k_CAVNTCEnableTimeout_mS_u16	44201
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	14213
k_CAVNodeTimeout_mS_u16	29387
k_CMM388MsgTimeout_mS_u16	13638
k_CMM388NTCEnableTimeout_mS_u16	20306
k_CMMNTCEnableTimeout_mS_u16	6973
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	41545
k_CONSANGLECPKMax_HwDeg_f32	252.276306
k_CONSANGLECPKMin_HwDeg_f32	-334.640411
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	34810
k_CONSANGLECPKSigValidThresh_Cnt_u16	35133
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	51276
k_CPKVehicleSpeedValidThresh_Cnt_u16	10188
k_CityParkInputInvalidThresh_Cnt_u16	54665
k_CityParkInputValidThresh_Cnt_u16	29928
k_ComputerRazGCTSigValidThresh_Cnt_u16	32883
k_CptTemporelSigValidThresh_Cnt_u16	34146
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	17474
k_DMDFCTCPKSigValidThresh_Cnt_u16	59900
k_DMDFCTCPKValidCount_Cnt_u16	18927
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	30106
k_DMDRELAXECPKSigValidThresh_Cnt_u16	27596
k_DMDRelaxeConsistentThresh_Cnt_u16	13626
k_DateValidThresh_Cnt_u16	16887
k_DefaultVehSpd_Kph_f32	207.255402
k_DiagMuxOnAbsentTimeout_mS_u16	46222
k_EMNodeTimeout_mS_u16	64272
k_ESPNTCEnableTimeout_mS_u16	65419
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	49457
k_EtatMTSigInvalidThresh_Cnt_u16	37734
k_EtatMTSigValidThresh_Cnt_u16	57848
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	12387
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	51145
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	31973
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	50998
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	26725
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	27145

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	37045
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	52555
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	29464
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	52164
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	44994
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	25912
k_ISDATDIRASentDiag_Cnt_str.Threshold	3858
k_ISDATDIRASentDiag_Cnt_str.PStep	45405
k_ISDATDIRASentDiag_Cnt_str.NStep	21916
k_ISDATDIRASentTimeout_mS_u16	64167
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	46977
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	40887
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	36967
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	52891
k_ISDYNAASChkSumValidThresh_Cnt_u16	35565
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	39107
k_ISDYNAASMsgCountValidThresh_Cnt_u16	41357
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	13199
k_ISDYNAASMsgLenValidThresh_Cnt_u16	57554
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	21873
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	8008
k_ISDYNABRChkSumValidThresh_Cnt_u16	7554
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	64775
k_ISDYNABRMsgCountValidThresh_Cnt_u16	51249
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	31792
k_ISDYNABRMsgLenValidThresh_Cnt_u16	61190
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	49628
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	10864
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	28498
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	41481
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	48772
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	40302
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	51875
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	5348
k_ISDYNVOLChkSumValidThresh_Cnt_u16	14722
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	17527
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	32481
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	36291
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	5577
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	42389
k_IgnOnTimeout_mS_u16	13296
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	139.552704
k_PowerCutVehSpdLowThresh_Kph_f32	120.529297
k_PowerCutVehSpdLowTimeout_mS_u16	41863
k_VBattMaxAAS_Volt_f32	10.8331003
k_VBattMaxBSI_Volt_f32	9.93529987
k_VBattMaxCAV_Volt_f32	4.13880014
k_VBattMaxCMM388_Volt_f32	15.1286001
k_VBattMaxCMM_Volt_f32	16.9734001
k_VBattMaxESP_Volt_f32	29.4136009
k_VBattMinAAS_Volt_f32	18.8908005
k_VBattMinBSI_Volt_f32	29.4136009
k_VBattMinCAV_Volt_f32	29.625
k_VBattMinCMM388_Volt_f32	6.14449978
k_VBattMinCMM_Volt_f32	8.68420029
k_VBattMinESP_Volt_f32	16.9734001
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	63251
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	23713
k_VitesseVehicleBVRampValidThresh_Cnt_u16	63645
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	25023
k_VitesseVehicleBVSigValidThresh_Cnt_u16	23549
k_VitesseVehicleBVSpeedPassThresh_kph_f32	108.746101
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	32639
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	13089
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2762452736
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	1
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	8524
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	1236548
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	56
target_SrlComInput_Per1_Batt_Volt_f32.value	27.3999996
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	437411584
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	169
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	0
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	15
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.554013073
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	7
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	3940699904
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	16
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	3435261696
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	181
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	2679213824
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	160
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	196161280
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	3099643648
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	228
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	1323331328
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	141
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	1980763904
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	58
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	129
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	164
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	171
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	217
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	240
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	241
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	88
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	3901632256
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	10
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	120
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	128
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	174
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	176
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	196
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	221
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	247
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	59
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3141095168
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	109
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2795040512
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	252
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	1124634368
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	21
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	22
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	46
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	95
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	132
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	139
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	166
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	186
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3893354240
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2055
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	1
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.912135124
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	425533
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	58.4397011
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	51598

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	1236548	1236548	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	40887	40887	✔
AngleVolantMsgTimer_mS_M_u32	1236548	1236548	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	1236548	1236548	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	1236548	1236548	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	1236548	1236548	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	17392	17392	✔
CONSANGLECPK_HwDeg_M_f32	21.5275993	21.5275993 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	17392	17392	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	1351663360	1351663360	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	536	536	✔
CityParkInputConsistentCount_Cnt_M_u16	29928	29928	✔
CityParkInputInvalidCount_Cnt_M_u16	13197	13197	✔
CityParkInputMsgTimer_mS_M_u32	1236548	1236548	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	1236548	1236548	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	1236548	1236548	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	3	3	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	1236548	1236548	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	1236548	1236548	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	1236548	1236548	✔
ESPNTCEnableTimer_mS_M_u32	1236548	1236548	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	1236548	1236548	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
EffacDefaultDiagTimer_mS_M_u32[0]	1000	1000	✔
EffacDefaultDiagTimer_mS_M_u32[1]	2000	2000	✔
ElecIntCount_Cnt_M_u08	0	0	✔
ElecIntTimer_mS_M_u32[0]	45	45	✔
ElecIntTimer_mS_M_u32[1]	101	101	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	1236548	1236548	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	1236548	1236548	✔
ISDATDIRASentFltAcc_Cnt_M_u16	3858	3858	✔
ISDATDIRASentTimer_mS_M_u32	1236548	1236548	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	9	9	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	10	10	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	1236548	1236548	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	7	7	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	1236548	1236548	✔
IgnOnTimer_mS_M_u32	3888140032	3888140032	✔
IgnTimeOff_Sec_M_u32	502409863	502409863	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	2	2	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	10	10	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	7	7	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3940699904	3940699904	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	16	16	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	3435261696	3435261696	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	181	181	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	2679213824	2679213824	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	160	160	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	196161280	196161280	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3521810176	3521810176	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	228	228	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1323331328	1323331328	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	141	141	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	1980763904	1980763904	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	88	88	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	3901632256	3901632256	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	59	59	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3141095168	3141095168	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	109	109	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2795040512	2795040512	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	252	252	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	1124634368	1124634368	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3893354240	3893354240	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	491.679688	491.679688	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	2	2	✔
ValidEngineStatusCount_Cnt_M_u08	0	0	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	1	1	✔
VehicleSpeedValid_Cnt_M_lgc	0	0	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	151.419205	151.419205	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	639.386475	639.386475	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	17392	17392	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	3	3	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	502409863	502409863	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	21.5275993	21.5275993 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	207.255402	207.255402	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	2	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	12	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.502 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	3564733952
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	40072
AASNodeAbsentTimer_mS_M_u32	573142528
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	6860
ANGLEVOLANTSigValidCount_Cnt_M_u16	58061
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	54325
AngleVolantMsgTimer_mS_M_u32	3564733952
AngleVolantValidCount_Cnt_M_u16	15100
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3261937152
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	1394849280
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	254944768
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	422897152
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	11075
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	2593302016
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	2652
CAVNodeAbsentTimer_mS_M_u32	875959808
CDD_SrlComVehSpd_Kph_G_f32	457.208496
CMM388NTCEnableTimer_mS_M_u32	3770570240
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2699826688
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	42504
CMMNodeAbsentTimer_mS_M_u32	989783552
CONSANGLECPKSigInvalidCount_Cnt_M_u16	31516
CONSANGLECPKSigValidCount_Cnt_M_u16	13165
CONSANGLECPK_Cnt_M_u16	55624
CONSANGLECPK_HwDeg_M_f32	-321.095703
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	55624
CPKVehicleSpeedMsgTimer_mS_M_u32	128484864
CPKVehicleSpeedValidCount_Cnt_M_u16	37081
CityParkInputConsistentCount_Cnt_M_u16	41760
CityParkInputInvalidCount_Cnt_M_u16	49209
CityParkInputMsgTimer_mS_M_u32	3940699904
CityParkInputValidCount_Cnt_M_u16	5

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2471327232
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	64172
ComputerRazGCTSigInvalidTimer_mS_M_u32	3057554944
ComputerRazGCTSigValidCount_Cnt_M_u16	34565
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	62485
DMDFCTCPKSigValidCount_Cnt_M_u16	31486
DMDFCTCPK_Cnt_M_u08	1
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	38366
DMDRELAXECPKSigValidCount_Cnt_M_u16	59231
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	31689
DateInvalidTimer_mS_M_u32	1394849280
DiagMuxOnAbsentTimer_mS_M_u32	314000896
DiagOn_Cnt_M_lgc	1
DmdDelestDATimer_mS_M_u32	422897152
ESPNTCEnableTimer_mS_M_u32	851080704
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	25157
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	2500
EffacDefaultDiagTimer_mS_M_u32[1]	3500
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	66
ElecIntTimer_mS_M_u32[1]	81
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	4127499776
EngOnDLCInvalidCount_Cnt_M_u08	1
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	17781
EtatMTSigValidCount_Cnt_M_u16	21795
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	44078
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	28159
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	49588
ISDAT4V2BSI552MsgTimer_mS_M_u32	4280477184
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	14248
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	6430
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	21795
ISDATBSI3F2MsgTimer_mS_M_u32	2040874496
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	60379
ISDATBSI412MsgLenValidCount_Cnt_M_u16	39552
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	17781
ISDATBSI412MsgTimer_mS_M_u32	560432640
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	64812
ISDATBSI432MsgLenValidCount_Cnt_M_u16	35945
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	44045
ISDATDIRASentFltAcc_Cnt_M_u16	29505
ISDATDIRASentTimer_mS_M_u32	128484864
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	14006
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	15100
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	62988
ISDYN2CMMMsgTimer_mS_M_u32	2835641856
ISDYNAASChkSumInvalidCount_Cnt_M_u16	58266
ISDYNAASChkSumValidCount_Cnt_M_u16	62139
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	8947
ISDYNAASMsgCount_Cnt_M_u08	6
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	26743
ISDYNAASMsgLenValidCount_Cnt_M_u16	32913
ISDYNAASMsgTimeValidCount_Cnt_M_u16	58266
ISDYNAASMsgTimer_mS_M_u32	3919205888
ISDYNABRChkSumInvalidCount_Cnt_M_u16	56839
ISDYNABRChkSumValidCount_Cnt_M_u16	44497
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	42513
ISDYNABRMsgCountValidCount_Cnt_M_u16	28786
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	45203
ISDYNABRMsgLenValidCount_Cnt_M_u16	25636
ISDYNABRMsgTimeValidCount_Cnt_M_u16	55624
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	1101
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	14297
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	21795
ISDYNCMM208MsgTimer_mS_M_u32	1318204928

Name	Input Value
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	1101
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	14297
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	16106
ISDYNCMM388MsgTimer_mS_M_u32	2771768832
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	6666
ISDYNVOLChkSumValidCount_Cnt_M_u16	51419
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	17923
ISDYNVOLMsgCountValidCount_Cnt_M_u16	876
ISDYNVOLMsgCount_Cnt_M_u08	6
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	57038
ISDYNVOLMsgLenValidCount_Cnt_M_u16	45056
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	42504
ISDYNVOLMsgTimer_mS_M_u32	723162624
IgnOnTimer_mS_M_u32	878302720
IgnTimeOff_Sec_M_u32	133296329
ManVehSpd_Kph_M_f32	576.706299
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	0
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	3
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	2
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	222
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4030416384
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	181
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	176760320
PrevISDATBSI412MsgDLCError_Cnt_M_u08	77
PrevISDATBSI412MsgRxTime_MSec_M_u32	1755780608
PrevISDATBSI432MsgDLCError_Cnt_M_u08	137
PrevISDATBSI432MsgRxTime_MSec_M_u32	575567360
PrevISDATDIRAMsgTxTime_MSec_M_u32	4007335424
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	13
PrevISDYN2CMMMsgRxTime_MSec_M_u32	1621255680
PrevISDYNAASMsgDLCError_Cnt_M_u08	147
PrevISDYNAASMsgRxTime_MSec_M_u32	1351128576
PrevISDYNABRMsgDLCError_Cnt_M_u08	200
PrevISDYNABRMsgRxTime_MSec_M_u32	2299647488
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	39
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1110283776
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	129
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3576264192
PrevISDYNVOLMsgDLCError_Cnt_M_u08	226
PrevISDYNVOLMsgRxTime_MSec_M_u32	2376340992
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2975172096
PrevModeDiag_Cnt_M_u08	0
PrevSrlComVehSpd_Kph_M_f32	382.72229
PrevVitesseVehicleBVValid_Cnt_M_lgc	1
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	41061
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	28415
VVHTYPE1Count_Cnt_M_u08	4
VVHTYPE2Count_Cnt_M_u08	4
ValidEngineStatusCount_Cnt_M_u08	3
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	1
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	27246
VitesseVehicleBVRampValidCount_Cnt_M_u16	56776
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	15957
VitesseVehicleBVSigValidCount_Cnt_M_u16	51990
VitesseVehicleBV_Kph_M_f32	139.536697
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	16106
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	65507

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRoues_Kph_M_f32	417.75589
k_AASNTCEnableTimeout_mS_u16	5815
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	48591
k_AASNodeTimeout_mS_u16	41471
k_ABSNodeTimeout_mS_u16	45050
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	1343
k_ANGLEVOLANTSigValidThresh_Cnt_u16	36028
k_AngleVolantInvalidThresh_Cnt_u16	22907
k_AngleVolantValidThresh_Cnt_u16	49209
k_BSI552MsgTimeout_mS_u16	33122
k_BSINTCEnableTimeout_mS_u16	49636
k_BSINodeAbsentDiag_Cnt_str.Threshold	18657
k_BSINodeAbsentDiag_Cnt_str.PStep	61761
k_BSINodeAbsentDiag_Cnt_str.NStep	32693
k_BSINodeAbsentTimeout_mS_u16	10989
k_BSINodeTimeout_mS_u16	44045
k_BattOvHi_Volt_f32	24.1345997
k_BattOvLo_Volt_f32	29.9426003
k_BattUvHi_Volt_f32	11.3922997
k_BattUvLo_Volt_f32	1.37360001
k_CAVNTCEnableTimeout_mS_u16	19679
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	27978
k_CAVNodeTimeout_mS_u16	64504
k_CMM388MsgTimeout_mS_u16	3976
k_CMM388NTCEnableTimeout_mS_u16	61796
k_CMMNTCEnableTimeout_mS_u16	6240
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	6079
k_CONSANGLECPKMax_HwDeg_f32	107.623703
k_CONSANGLECPKMin_HwDeg_f32	-358.51001
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	12778
k_CONSANGLECPKSigValidThresh_Cnt_u16	13027
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	5045
k_CPKVehicleSpeedValidThresh_Cnt_u16	64438
k_CityParkInputInvalidThresh_Cnt_u16	62525
k_CityParkInputValidThresh_Cnt_u16	41760
k_ComputerRazGCTSigValidThresh_Cnt_u16	16574
k_CptTemporelSigValidThresh_Cnt_u16	59060
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	9107
k_DMDFCTCPKSigValidThresh_Cnt_u16	5924
k_DMDFCTCPKValidCount_Cnt_u16	22411
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	62988
k_DMDRELAXECPKSigValidThresh_Cnt_u16	55349
k_DMDRelaxeConsistentThresh_Cnt_u16	46059
k_DateValidThresh_Cnt_u16	49588
k_DefaultVehSpd_Kph_f32	150.088501
k_DiagMuxOnAbsentTimeout_mS_u16	32622
k_EMNodeTimeout_mS_u16	46889
k_ESPNTCEnableTimeout_mS_u16	44344
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	23303
k_EtatMTSigInvalidThresh_Cnt_u16	28326
k_EtatMTSigValidThresh_Cnt_u16	51120
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	63344
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	50685
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	48937
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	14453
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	2475
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	26879
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	61305
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	36470
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	37968
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	37324

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	55954
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	17521
k_ISDATDIRASentDiag_Cnt_str.Threshold	12438
k_ISDATDIRASentDiag_Cnt_str.PStep	4214
k_ISDATDIRASentDiag_Cnt_str.NStep	47738
k_ISDATDIRASentTimeout_mS_u16	31971
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	45462
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	54325
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	27300
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	53511
k_ISDYNAASChkSumValidThresh_Cnt_u16	57553
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	6417
k_ISDYNAASMsgCountValidThresh_Cnt_u16	9074
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	29227
k_ISDYNAASMsgLenValidThresh_Cnt_u16	25123
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	3588
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	10881
k_ISDYNABRChkSumValidThresh_Cnt_u16	5266
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	40515
k_ISDYNABRMsgCountValidThresh_Cnt_u16	57732
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	55560
k_ISDYNABRMsgLenValidThresh_Cnt_u16	54597
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	24707
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	137
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	48420
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	47742
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	36300
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	38349
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	23281
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	37998
k_ISDYNVOLChkSumValidThresh_Cnt_u16	39763
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	55538
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	54517
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	48465
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	14847
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	36570
k_IgnOnTimeout_mS_u16	26442
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	57.6963997
k_PowerCutVehSpdLowThresh_Kph_f32	218.766693
k_PowerCutVehSpdLowTimeout_mS_u16	54915
k_VBattMaxAAS_Volt_f32	26.0053997
k_VBattMaxBSI_Volt_f32	30.3099995
k_VBattMaxCAV_Volt_f32	23.6264992
k_VBattMaxCMM388_Volt_f32	21.1434002
k_VBattMaxCMM_Volt_f32	19.0571995
k_VBattMaxESP_Volt_f32	17.0247002
k_VBattMinAAS_Volt_f32	2.44449997
k_VBattMinBSI_Volt_f32	17.0247002
k_VBattMinCAV_Volt_f32	7.59250021
k_VBattMinCMM388_Volt_f32	21.8953991
k_VBattMinCMM_Volt_f32	3.28699994
k_VBattMinESP_Volt_f32	19.0571995
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	47840
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	48885
k_VitesseVehicleBVRampValidThresh_Cnt_u16	14595
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	31707
k_VitesseVehicleBVSigValidThresh_Cnt_u16	33249
k_VitesseVehicleBVSpeedPassThresh_kph_f32	268.196899
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	64860
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	26422
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	1394849280
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	33485
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	242062592
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	129
target_SrlComInput_Per1_Batt_Volt_f32.value	13.1569004
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	967026176
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	22
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	1
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	12
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.400892586
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	176
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	854840832
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	254
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	332723712
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	180
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	1636177408
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	219
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	604452352
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	1666733568
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	156
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	662271488
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2020251136
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	43
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	56
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	101
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	142
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	156
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	206
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	208
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	236
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	101
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	1097872896
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	19
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	81
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	98
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	99
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	161
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	163
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	219
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	233
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	50
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	3723417088
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	3
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	2723149312
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	252
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	2474710528
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	69
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	79
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	93
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	110
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	175
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	193
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	205
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	245
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	2779457024
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2109
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	0
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.900920391
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	597064
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	1
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	77.2854996
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	6959

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	242062592	242062592	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	242062592	242062592	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	242062592	242062592	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	242062592	242062592	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	242062592	242062592	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	242062592	242062592	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	242062592	242062592	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	0	0	✔
BSINodeAbsentTimer_mS_M_u32	242062592	242062592	✔
BattOk_Cnt_M_lgc	1	1	✔
CAVNTCEnableTimer_mS_M_u32	242062592	242062592	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	242062592	242062592	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	242062592	242062592	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	242062592	242062592	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	242062592	242062592	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	55624	55624	✔
CONSANGLECPK_HwDeg_M_f32	-321.095703	-321.095703 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	242062592	242062592	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	242062592	242062592	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	242062592	242062592	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	242062592	242062592	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	1	1	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	242062592	242062592	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	242062592	242062592	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	242062592	242062592	✔
ESPNTCEnableTimer_mS_M_u32	242062592	242062592	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	242062592	242062592	✔
EffacDefaultDiagCount_Cnt_M_u08	1	1	✔
EffacDefaultDiagTimer_mS_M_u32[0]	242062592	242062592	✔
EffacDefaultDiagTimer_mS_M_u32[1]	3500	3500	✔
ElecIntCount_Cnt_M_u08	1	1	✔
ElecIntTimer_mS_M_u32[0]	242062592	242062592	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[1]	81	81	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	242062592	242062592	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	242062592	242062592	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	242062592	242062592	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	242062592	242062592	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	242062592	242062592	✔
ISDATDIRASentFltAcc_Cnt_M_u16	12438	12438	✔
ISDATDIRASentTimer_mS_M_u32	242062592	242062592	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	242062592	242062592	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	6	6	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	242062592	242062592	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	242062592	242062592	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	242062592	242062592	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	242062592	242062592	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	6	6	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	242062592	242062592	✔
IgnOnTimer_mS_M_u32	242062592	242062592	✔
IgnTimeOff_Sec_M_u32	133296329	133296329	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	3	3	✔
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevEtatMT_Cnt_M_u08	2	2	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	176	176	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	854840832	854840832	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	254	254	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	332723712	332723712	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	180	180	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	1636177408	1636177408	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	219	219	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	604452352	604452352	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	4007335424	4007335424	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	156	156	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	662271488	662271488	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	69	69	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2020251136	2020251136	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	101	101	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	1097872896	1097872896	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	50	50	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	3723417088	3723417088	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	3	3	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	2723149312	2723149312	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	252	252	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	2474710528	2474710528	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	2779457024	2779457024	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	382.72229	382.72229	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	1	1	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	4	4	✔
VVHTYPE2Count_Cnt_M_u08	4	4	✔
ValidEngineStatusCount_Cnt_M_u08	3	3	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	139.536697	139.536697	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	417.75589	417.75589	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	55624	55624	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	1	1	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	133296329	133296329	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-321.095703	-321.095703 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.503 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4224332032
AASNTCsEnabled_Cnt_M_lgc	0
AASNodeAbsentFltAcc_Cnt_M_u16	64926
AASNodeAbsentTimer_mS_M_u32	4269433088
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	13521
ANGLEVOLANTSigValidCount_Cnt_M_u16	61068
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	19095
AngleVolantMsgTimer_mS_M_u32	4224332032
AngleVolantValidCount_Cnt_M_u16	39618
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	3702464768
BSI3F2NTCsEnabled_Cnt_M_lgc	1
BSI412NTCEnableTimer_mS_M_u32	613130496
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	1981829376
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	3541569792
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	40812
BattOk_Cnt_M_lgc	1
CAVNTCEnableTimer_mS_M_u32	4127117568
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	20128
CAVNodeAbsentTimer_mS_M_u32	1121222912
CDD_SrlComVehSpd_Kph_G_f32	252.466995
CMM388NTCEnableTimer_mS_M_u32	2923151616
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	1420984576
CMMNTCsEnabled_Cnt_M_lgc	0
CMMNodeAbsentFltAcc_Cnt_M_u16	1629
CMMNodeAbsentTimer_mS_M_u32	364515584
CONSANGLECPKSigInvalidCount_Cnt_M_u16	737
CONSANGLECPKSigValidCount_Cnt_M_u16	11181
CONSANGLECPK_Cnt_M_u16	26140
CONSANGLECPK_HwDeg_M_f32	-7.50899982
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	26140
CPKVehicleSpeedMsgTimer_mS_M_u32	3728552192
CPKVehicleSpeedValidCount_Cnt_M_u16	0
CityParkInputConsistentCount_Cnt_M_u16	62038
CityParkInputInvalidCount_Cnt_M_u16	36874

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	854840832
CityParkInputValidCount_Cnt_M_u16	5
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	990798080
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	29490
ComputerRazGCTSigInvalidTimer_mS_M_u32	2126184704
ComputerRazGCTSigValidCount_Cnt_M_u16	6823
CountEtatMT_Cnt_M_u08	2
DMDFCTCPKSigInvalidCount_Cnt_M_u16	25718
DMDFCTCPKSigValidCount_Cnt_M_u16	33146
DMDFCTCPK_Cnt_M_u08	2
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	35739
DMDRELAXECPKSigValidCount_Cnt_M_u16	43222
DMDRELAXECPK_Cnt_M_u08	1
DMDRelaxeConsistentCount_Cnt_M_u16	62682
DateInvalidTimer_mS_M_u32	613130496
DiagMuxOnAbsentTimer_mS_M_u32	1745940736
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	3541569792
ESPNTCEnableTimer_mS_M_u32	1355243776
ESPNTCsEnabled_Cnt_M_lgc	1
ESPNodeAbsentFltAcc_Cnt_M_u16	54117
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	979
EffacDefaultDiagTimer_mS_M_u32[1]	1085
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	101
ElecIntTimer_mS_M_u32[1]	108
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	732483840
EngOnDLCInvalidCount_Cnt_M_u08	0
EngOn_Cnt_M_lgc	1
EtatMTSigInvalidCount_Cnt_M_u16	27926
EtatMTSigValidCount_Cnt_M_u16	65485
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	14251
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	17399
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	1368
ISDAT4V2BSI552MsgTimer_mS_M_u32	1498288384
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	7163
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	22875
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	65485
ISDATBSI3F2MsgTimer_mS_M_u32	1799811328
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	39013
ISDATBSI412MsgLenValidCount_Cnt_M_u16	11828
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	27926
ISDATBSI412MsgTimer_mS_M_u32	1291858176
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	37105
ISDATBSI432MsgLenValidCount_Cnt_M_u16	58617
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	28045
ISDATDIRASentFltAcc_Cnt_M_u16	59377
ISDATDIRASentTimer_mS_M_u32	3728552192
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	34258
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	39618
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	64145
ISDYN2CMMMsgTimer_mS_M_u32	2515099904
ISDYNAASChkSumInvalidCount_Cnt_M_u16	61544
ISDYNAASChkSumValidCount_Cnt_M_u16	21700
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	32477
ISDYNAASMsgCount_Cnt_M_u08	0
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	24655
ISDYNAASMsgLenValidCount_Cnt_M_u16	35267
ISDYNAASMsgTimeValidCount_Cnt_M_u16	61544
ISDYNAASMsgTimer_mS_M_u32	61325568
ISDYNABRChkSumInvalidCount_Cnt_M_u16	37023
ISDYNABRChkSumValidCount_Cnt_M_u16	21250
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	17667
ISDYNABRMsgCountValidCount_Cnt_M_u16	30623
ISDYNABRMsgCount_Cnt_M_u08	7
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	65148
ISDYNABRMsgLenValidCount_Cnt_M_u16	13704
ISDYNABRMsgTimeValidCount_Cnt_M_u16	26140
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	6470
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	55906

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	65485
ISDYNCMM208MsgTimer_mS_M_u32	205529344
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	6470
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	55906
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	50936
ISDYNCMM388MsgTimer_mS_M_u32	2664775936
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	24087
ISDYNVOLChkSumValidCount_Cnt_M_u16	41827
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	42668
ISDYNVOLMsgCountValidCount_Cnt_M_u16	8240
ISDYNVOLMsgCount_Cnt_M_u08	5
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	49610
ISDYNVOLMsgLenValidCount_Cnt_M_u16	8182
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	1629
ISDYNVOLMsgTimer_mS_M_u32	2418475264
IgnOnTimer_mS_M_u32	2171158784
IgnTimeOff_Sec_M_u32	666558158
ManVehSpd_Kph_M_f32	293.289795
Msg348Valid_Cnt_M_lgc	0
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	1
NetOn_Cnt_M_lgc	1
NtWrapC_Dem_ClearDTC()	255
PrevDMDFCTCPK_Cnt_M_u08	3
PrevDMDRELAXECPK_Cnt_M_u08	0
PrevDiagIntegraElec_Cnt_M_u08	1
PrevEtatMT_Cnt_M_u08	14
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	235
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	3750031616
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	171
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	2686144768
PrevISDATBSI412MsgDLCError_Cnt_M_u08	230
PrevISDATBSI412MsgRxTime_MSec_M_u32	2843836672
PrevISDATBSI432MsgDLCError_Cnt_M_u08	120
PrevISDATBSI432MsgRxTime_MSec_M_u32	3523961088
PrevISDATDIRAMsgTxTime_MSec_M_u32	3873800448
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	85
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2463076608
PrevISDYNAASMsgDLCError_Cnt_M_u08	23
PrevISDYNAASMsgRxTime_MSec_M_u32	1474101504
PrevISDYNABRMsgDLCError_Cnt_M_u08	108
PrevISDYNABRMsgRxTime_MSec_M_u32	1665220864
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	240
PrevISDYNCMM208MsgRxTime_MSec_M_u32	1458438400
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	226
PrevISDYNCMM388MsgRxTime_MSec_M_u32	3850002688
PrevISDYNVOLMsgDLCError_Cnt_M_u08	21
PrevISDYNVOLMsgRxTime_MSec_M_u32	1854570752
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3577098496
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	419.521393
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	1
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	0
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	61573
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	63097
VVHTYPE1Count_Cnt_M_u08	10
VVHTYPE2Count_Cnt_M_u08	7
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	63082
VitesseVehicleBVRampValidCount_Cnt_M_u16	3614
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	11830
VitesseVehicleBVSigValidCount_Cnt_M_u16	39345
VitesseVehicleBV_Kph_M_f32	346.600098

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	50936
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	30156
VitesseVehiculeRoues_Kph_M_f32	192.638901
k_AASNTCEnableTimeout_mS_u16	10703
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	7753
k_AASNodeTimeout_mS_u16	23929
k_ABSNodeTimeout_mS_u16	1223
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	33976
k_ANGLEVOLANTSigValidThresh_Cnt_u16	61440
k_AngleVolantInvalidThresh_Cnt_u16	17859
k_AngleVolantValidThresh_Cnt_u16	36874
k_BSI552MsgTimeout_mS_u16	44367
k_BSINTCEnableTimeout_mS_u16	8905
k_BSINodeAbsentDiag_Cnt_str.Threshold	62218
k_BSINodeAbsentDiag_Cnt_str.PStep	20010
k_BSINodeAbsentDiag_Cnt_str.NStep	18190
k_BSINodeAbsentTimeout_mS_u16	9839
k_BSINodeTimeout_mS_u16	28045
k_BattOvHi_Volt_f32	25.6627998
k_BattOvLo_Volt_f32	3.50990009
k_BattUvHi_Volt_f32	12.6643
k_BattUvLo_Volt_f32	22.6299
k_CAVNTCEnableTimeout_mS_u16	536
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	24022
k_CAVNodeTimeout_mS_u16	61517
k_CMM388MsgTimeout_mS_u16	42142
k_CMM388NTCEnableTimeout_mS_u16	28426
k_CMMNTCEnableTimeout_mS_u16	22995
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	40504
k_CONSANGLECPKMax_HwDeg_f32	114.043098
k_CONSANGLECPKMin_HwDeg_f32	-381.904297
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	60920
k_CONSANGLECPKSigValidThresh_Cnt_u16	56524
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	24663
k_CPKVehicleSpeedValidThresh_Cnt_u16	38100
k_CityParkInputInvalidThresh_Cnt_u16	42493
k_CityParkInputValidThresh_Cnt_u16	62038
k_ComputerRazGCTSigValidThresh_Cnt_u16	55481
k_CptTemporelSigValidThresh_Cnt_u16	51353
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	42364
k_DMDFCTCPKSigValidThresh_Cnt_u16	7304
k_DMDFCTCPKValidCount_Cnt_u16	14996
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	64145
k_DMDRELAXECPKSigValidThresh_Cnt_u16	1493
k_DMDRelaxeConsistentThresh_Cnt_u16	51891
k_DateValidThresh_Cnt_u16	1368
k_DefaultVehSpd_Kph_f32	19.4484997
k_DiagMuxOnAbsentTimeout_mS_u16	35754
k_EMNodeTimeout_mS_u16	49850
k_ESPNTCEnableTimeout_mS_u16	54796
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	62560
k_EtatMTSigInvalidThresh_Cnt_u16	6850
k_EtatMTSigValidThresh_Cnt_u16	16741
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	24870
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	14142
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	571
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	36244
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	64436
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	45305
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	11786
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	21202

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	23429
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	19600
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	37888
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	47010
k_ISDATDIRASentDiag_Cnt_str.Threshold	1559
k_ISDATDIRASentDiag_Cnt_str.PStep	4663
k_ISDATDIRASentDiag_Cnt_str.NStep	20460
k_ISDATDIRASentTimeout_mS_u16	9227
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	17459
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	19095
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	19912
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	47007
k_ISDYNAASChkSumValidThresh_Cnt_u16	47618
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	60419
k_ISDYNAASMsgCountValidThresh_Cnt_u16	24223
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	25651
k_ISDYNAASMsgLenValidThresh_Cnt_u16	44301
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	35880
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	51378
k_ISDYNABRChkSumValidThresh_Cnt_u16	23614
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	18028
k_ISDYNABRMsgCountValidThresh_Cnt_u16	36455
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	27997
k_ISDYNABRMsgLenValidThresh_Cnt_u16	31333
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	52586
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	24601
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	34954
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	53244
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	56273
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	54668
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	40930
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	43692
k_ISDYNVOLChkSumValidThresh_Cnt_u16	14267
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	25438
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	28054
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	30082
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	49465
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	46566
k_IgnOnTimeout_mS_u16	41496
k_JDD2010Selected_Cnt_lgc	1
k_PowerCutVehSpdHighThresh_Kph_f32	159.124802
k_PowerCutVehSpdLowThresh_Kph_f32	131.913803
k_PowerCutVehSpdLowTimeout_mS_u16	6763
k_VBattMaxAAS_Volt_f32	6.50939989
k_VBattMaxBSI_Volt_f32	21.7616997
k_VBattMaxCAV_Volt_f32	15.0318003
k_VBattMaxCMM388_Volt_f32	30.0223007
k_VBattMaxCMM_Volt_f32	25.9361
k_VBattMaxESP_Volt_f32	25.1692009
k_VBattMinAAS_Volt_f32	9.35529995
k_VBattMinBSI_Volt_f32	25.1692009
k_VBattMinCAV_Volt_f32	13.8593998
k_VBattMinCMM388_Volt_f32	7.36679983
k_VBattMinCMM_Volt_f32	30.1597004
k_VBattMinESP_Volt_f32	25.9361
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	53333
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	9685
k_VitesseVehicleBVRampValidThresh_Cnt_u16	52652
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	35427
k_VitesseVehicleBVSigValidThresh_Cnt_u16	39443
k_VitesseVehicleBVSpeedPassThresh_kph_f32	615.036499
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	30112
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	43476
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	613130496
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	13090
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentT	2006148864
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	226

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	22.6184006
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	1
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2630603008
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	99
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	1
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	1
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	0
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	10
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.51365447
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	117
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	1838891264
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	89
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	930603264
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	67
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	4209279232
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	26
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	2682331392
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	1
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	242073856
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	49
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	780820736
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	65
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	3895918848
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	4
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	11
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	46
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	47
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	95
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	103
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	120
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	196
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	96
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	732307712
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	60
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	76
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	123
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	153
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	164
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	165
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	214
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	224
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	158
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	413810944
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	247
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	939974912
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	22
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	284393728
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	15
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	41
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	48
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	64
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	72
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	84
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	88
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	165
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	3602206976
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	2876
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	0
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.0762358829
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	0
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	96087
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	3.60739994
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	10279

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	1	1	✔
AngleVolantInvalidCount_Cnt_M_u16	2	2	✔
AngleVolantMsgTimer_mS_M_u32	2006148864	2006148864	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	62218	62218	✔
BSINodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	26140	26140	✔
CONSANGLECPK_HwDeg_M_f32	-7.50899982	-7.50899982 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	0	0	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	2006148864	2006148864	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	0	0	✔
CityParkInputInvalidCount_Cnt_M_u16	2	2	✔
CityParkInputMsgTimer_mS_M_u32	2006148864	2006148864	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	2006148864	2006148864	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	2	2	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	1	1	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	2006148864	2006148864	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCEnableTimer_mS_M_u32	2006148864	2006148864	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	979	979	✔
EffacDefaultDiagTimer_mS_M_u32[1]	1085	1085	✔
ElecIntCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	2006148864	2006148864	✔
ElecIntTimer_mS_M_u32[1]	108	108	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	2006148864	2006148864	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	2006148864	2006148864	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	0	0	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	7	7	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	2006148864	2006148864	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	5	5	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	2006148864	2006148864	✔
IgnOnTimer_mS_M_u32	2006148864	2006148864	✔
IgnTimeOff_Sec_M_u32	666558158	666558158	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	3	3	✔
PrevDMDRELAXECPK_Cnt_M_u08	0	0	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	1	1	✔
PrevEtatMT_Cnt_M_u08	14	14	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	117	117	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	1838891264	1838891264	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	89	89	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	930603264	930603264	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	67	67	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	4209279232	4209279232	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	26	26	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	2682331392	2682331392	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	3873800448	3873800448	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	49	49	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	780820736	780820736	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	65	65	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	3895918848	3895918848	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	96	96	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	732307712	732307712	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	158	158	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	413810944	413810944	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	247	247	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	939974912	939974912	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	22	22	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	284393728	284393728	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	3602206976	3602206976	✔
PrevModeDiag_Cnt_M_u08	0	0	✔
PrevSrlComVehSpd_Kph_M_f32	419.521393	419.521393	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	10	10	✔
VVHTYPE2Count_Cnt_M_u08	7	7	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	346.600098	346.600098	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	192.638901	192.638901	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	26140	26140	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	2	2	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	666558158	666558158	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	-7.50899982	-7.50899982 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔

Test Step 1.504 (Repeat Count = 1)

Name	Input Value
AASNTCEnableTimer_mS_M_u32	4064555008
AASNTCsEnabled_Cnt_M_lgc	1
AASNodeAbsentFltAcc_Cnt_M_u16	57030
AASNodeAbsentTimer_mS_M_u32	653500416
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	9007
ANGLEVOLANTSigValidCount_Cnt_M_u16	49340
APARequest_Cnt_M_lgc	1
AngleVolantInvalidCount_Cnt_M_u16	7131
AngleVolantMsgTimer_mS_M_u32	4064555008
AngleVolantValidCount_Cnt_M_u16	40411
AngleVolantValid_Cnt_M_lgc	1
AngleVolant_HwDeg_M_f32	0
ApaRelaxReq_Cnt_M_lgc	1
BSI3F2NTCEnableTimer_mS_M_u32	1330995200
BSI3F2NTCsEnabled_Cnt_M_lgc	0
BSI412NTCEnableTimer_mS_M_u32	2311053312
BSI412NTCsEnabled_Cnt_M_lgc	1
BSI432NTCEnableTimer_mS_M_u32	63033344
BSI432NTCsEnabled_Cnt_M_lgc	0
BSI552NTCEnableTimer_mS_M_u32	2077921280
BSI552NTCsEnabled_Cnt_M_lgc	1
BSINodeAbsentFltAcc_Cnt_M_u16	3934
BattOk_Cnt_M_lgc	0
CAVNTCEnableTimer_mS_M_u32	505827328
CAVNTCsEnabled_Cnt_M_lgc	1
CAVNodeAbsentFltAcc_Cnt_M_u16	7232
CAVNodeAbsentTimer_mS_M_u32	3932504064
CDD_SrlComVehSpd_Kph_G_f32	485.762787
CMM388NTCEnableTimer_mS_M_u32	1429176320
CMM388NTCsEnabled_Cnt_M_lgc	0
CMMNTCEnableTimer_mS_M_u32	2899001344
CMMNTCsEnabled_Cnt_M_lgc	1
CMMNodeAbsentFltAcc_Cnt_M_u16	21705
CMMNodeAbsentTimer_mS_M_u32	3153367040
CONSANGLECPKSigInvalidCount_Cnt_M_u16	60412
CONSANGLECPKSigValidCount_Cnt_M_u16	31833
CONSANGLECPK_Cnt_M_u16	18700
CONSANGLECPK_HwDeg_M_f32	316.518188
CPKOK_Cnt_M_lgc	0
CPKVehicleSpeedInvalidCount_Cnt_M_u16	18700
CPKVehicleSpeedMsgTimer_mS_M_u32	3605737472
CPKVehicleSpeedValidCount_Cnt_M_u16	0
CityParkInputConsistentCount_Cnt_M_u16	59167
CityParkInputInvalidCount_Cnt_M_u16	12035

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
CityParkInputMsgTimer_mS_M_u32	1838891264
CityParkInputValidCount_Cnt_M_u16	9
ClearDTCs_Cnt_M_lgc	1
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3241648128
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	52746
ComputerRazGCTSigInvalidTimer_mS_M_u32	4038180864
ComputerRazGCTSigValidCount_Cnt_M_u16	61996
CountEtatMT_Cnt_M_u08	0
DMDFCTCPKSigInvalidCount_Cnt_M_u16	25023
DMDFCTCPKSigValidCount_Cnt_M_u16	62836
DMDFCTCPK_Cnt_M_u08	0
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	50897
DMDRELAXECPKSigValidCount_Cnt_M_u16	14814
DMDRELAXECPK_Cnt_M_u08	0
DMDRelaxeConsistentCount_Cnt_M_u16	14865
DateInvalidTimer_mS_M_u32	2311053312
DiagMuxOnAbsentTimer_mS_M_u32	946860032
DiagOn_Cnt_M_lgc	0
DmdDelestDATimer_mS_M_u32	2077921280
ESPNTCEnableTimer_mS_M_u32	2752290816
ESPNTCsEnabled_Cnt_M_lgc	0
ESPNodeAbsentFltAcc_Cnt_M_u16	59506
EffacDefaultDiagCount_Cnt_M_u08	0
EffacDefaultDiagTimer_mS_M_u32[0]	6
EffacDefaultDiagTimer_mS_M_u32[1]	16
ElecIntCount_Cnt_M_u08	0
ElecIntTimer_mS_M_u32[0]	99
ElecIntTimer_mS_M_u32[1]	1002
ElectronicIntegrationCmd_Cnt_M_lgc	1
EngOnAbsentTimer_mS_M_u32	2770882560
EngOnDLCInvalidCount_Cnt_M_u08	2
EngOn_Cnt_M_lgc	0
EtatMTSigInvalidCount_Cnt_M_u16	20896
EtatMTSigValidCount_Cnt_M_u16	21561
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	62878
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	56187
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	25050
ISDAT4V2BSI552MsgTimer_mS_M_u32	1094225920
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	46191
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	22288
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	21561
ISDATBSI3F2MsgTimer_mS_M_u32	2261643264
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	29747
ISDATBSI412MsgLenValidCount_Cnt_M_u16	52612
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	20896
ISDATBSI412MsgTimer_mS_M_u32	1453469696
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	1293
ISDATBSI432MsgLenValidCount_Cnt_M_u16	950
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	45945
ISDATDIRASentFltAcc_Cnt_M_u16	54349
ISDATDIRASentTimer_mS_M_u32	3605737472
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	16874
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	40411
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	52078
ISDYN2CMMMsgTimer_mS_M_u32	3701907456
ISDYNAASChkSumInvalidCount_Cnt_M_u16	44648
ISDYNAASChkSumValidCount_Cnt_M_u16	52245
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	7562
ISDYNAASMsgCount_Cnt_M_u08	10
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	25395
ISDYNAASMsgLenValidCount_Cnt_M_u16	37272
ISDYNAASMsgTimeValidCount_Cnt_M_u16	44648
ISDYNAASMsgTimer_mS_M_u32	82542592
ISDYNABRChkSumInvalidCount_Cnt_M_u16	8005
ISDYNABRChkSumValidCount_Cnt_M_u16	17114
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	56471
ISDYNABRMsgCountValidCount_Cnt_M_u16	36740
ISDYNABRMsgCount_Cnt_M_u08	12
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	9515
ISDYNABRMsgLenValidCount_Cnt_M_u16	35528
ISDYNABRMsgTimeValidCount_Cnt_M_u16	18700
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	29414
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	7250

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	21561
ISDYNCMM208MsgTimer_mS_M_u32	1151492096
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	29414
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	7250
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	28985
ISDYNCMM388MsgTimer_mS_M_u32	3378708480
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	12890
ISDYNVOLChkSumValidCount_Cnt_M_u16	27959
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	62237
ISDYNVOLMsgCountValidCount_Cnt_M_u16	29010
ISDYNVOLMsgCount_Cnt_M_u08	13
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	61763
ISDYNVOLMsgLenValidCount_Cnt_M_u16	24960
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	21705
ISDYNVOLMsgTimer_mS_M_u32	1819131904
IgnOnTimer_mS_M_u32	1906769920
IgnTimeOff_Sec_M_u32	2182505990
ManVehSpd_Kph_M_f32	478.025604
Msg348Valid_Cnt_M_lgc	1
Msg432Valid_Cnt_M_lgc	1
Msg552Valid_Cnt_M_lgc	0
NetOn_Cnt_M_lgc	0
NtWrapC_Dem_ClearDTC()	120
PrevDMDFCTCPK_Cnt_M_u08	2
PrevDMDRELAXECPK_Cnt_M_u08	1
PrevDiagIntegraElec_Cnt_M_u08	0
PrevEtatMT_Cnt_M_u08	5
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	246
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	2719215616
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	240
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	835768320
PrevISDATBSI412MsgDLCError_Cnt_M_u08	44
PrevISDATBSI412MsgRxTime_MSec_M_u32	2858303488
PrevISDATBSI432MsgDLCError_Cnt_M_u08	166
PrevISDATBSI432MsgRxTime_MSec_M_u32	809541632
PrevISDATDIRAMsgTxTime_MSec_M_u32	2184331264
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	209
PrevISDYN2CMMMsgRxTime_MSec_M_u32	2058620928
PrevISDYNAASMsgDLCError_Cnt_M_u08	149
PrevISDYNAASMsgRxTime_MSec_M_u32	1833680896
PrevISDYNABRMsgDLCError_Cnt_M_u08	184
PrevISDYNABRMsgRxTime_MSec_M_u32	740229120
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	76
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4095262720
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	119
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1911791616
PrevISDYNVOLMsgDLCError_Cnt_M_u08	218
PrevISDYNVOLMsgRxTime_MSec_M_u32	3208855552
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	369111040
PrevModeDiag_Cnt_M_u08	1
PrevSrlComVehSpd_Kph_M_f32	153.812195
PrevVitesseVehicleBVValid_Cnt_M_lgc	0
ResetTimers_Cnt_M_lgc	0
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET(signal)	target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComInput	target_Rte_Inst_Ap_SrlComInput
Rte_Mode_Ap_SrlComInput_SystemState_Mode()	3
StartupTimeCalculated_Cnt_M_lgc	1
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	2705
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	41846
VVHTYPE1Count_Cnt_M_u08	2
VVHTYPE2Count_Cnt_M_u08	10
ValidEngineStatusCount_Cnt_M_u08	1
VehSpdControl_Cnt_M_lgc	1
VehSpdSync_Cnt_M_lgc	0
VehTimeValid_Cnt_M_lgc	0
VehicleSpeedValid_Cnt_M_lgc	1
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	52450
VitesseVehicleBVRampValidCount_Cnt_M_u16	12423
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	2816
VitesseVehicleBVSigValidCount_Cnt_M_u16	37709
VitesseVehicleBV_Kph_M_f32	154.650894

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	28985
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	36734
VitesseVehiculeRoues_Kph_M_f32	543.46521
k_AASNTCEnableTimeout_mS_u16	35315
k_AASNodeAbsentDiag_Cnt_str.Threshold	0
k_AASNodeAbsentDiag_Cnt_str.PStep	0
k_AASNodeAbsentDiag_Cnt_str.NStep	0
k_AASNodeAbsentTimeout_mS_u16	61254
k_AASNodeTimeout_mS_u16	28278
k_ABSNodeTimeout_mS_u16	1228
k_ANGLEVOLANTSigInvalidThresh_Cnt_u16	1464
k_ANGLEVOLANTSigValidThresh_Cnt_u16	48801
k_AngleVolantInvalidThresh_Cnt_u16	35160
k_AngleVolantValidThresh_Cnt_u16	12035
k_BSI552MsgTimeout_mS_u16	46325
k_BSINTCEnableTimeout_mS_u16	44933
k_BSINodeAbsentDiag_Cnt_str.Threshold	61209
k_BSINodeAbsentDiag_Cnt_str.PStep	57594
k_BSINodeAbsentDiag_Cnt_str.NStep	2446
k_BSINodeAbsentTimeout_mS_u16	59475
k_BSINodeTimeout_mS_u16	45945
k_BattOvHi_Volt_f32	29.1299992
k_BattOvLo_Volt_f32	12.2756004
k_BattUvHi_Volt_f32	26.8022995
k_BattUvLo_Volt_f32	24.6763
k_CAVNTCEnableTimeout_mS_u16	37081
k_CAVNodeAbsentDiag_Cnt_str.Threshold	0
k_CAVNodeAbsentDiag_Cnt_str.PStep	0
k_CAVNodeAbsentDiag_Cnt_str.NStep	0
k_CAVNodeAbsentTimeout_mS_u16	18078
k_CAVNodeTimeout_mS_u16	54200
k_CMM388MsgTimeout_mS_u16	59846
k_CMM388NTCEnableTimeout_mS_u16	14978
k_CMMNTCEnableTimeout_mS_u16	23271
k_CMMNodeAbsentDiag_Cnt_str.Threshold	0
k_CMMNodeAbsentDiag_Cnt_str.PStep	0
k_CMMNodeAbsentDiag_Cnt_str.NStep	0
k_CMMNodeAbsentTimeout_mS_u16	50746
k_CONSANGLECPKMax_HwDeg_f32	157.087708
k_CONSANGLECPKMin_HwDeg_f32	-466.024292
k_CONSANGLECPKSigInvalidThresh_Cnt_u16	64569
k_CONSANGLECPKSigValidThresh_Cnt_u16	23166
k_CPKVehicleSpeedInvalidThresh_Cnt_u16	24028
k_CPKVehicleSpeedValidThresh_Cnt_u16	64230
k_CityParkInputInvalidThresh_Cnt_u16	55083
k_CityParkInputValidThresh_Cnt_u16	59167
k_ComputerRazGCTSigValidThresh_Cnt_u16	63029
k_CptTemporelSigValidThresh_Cnt_u16	33110
k_DMDFCTCPKSigInvalidThresh_Cnt_u16	12331
k_DMDFCTCPKSigValidThresh_Cnt_u16	54728
k_DMDFCTCPKValidCount_Cnt_u16	56806
k_DMDRELAXECPKSigInvalidThresh_Cnt_u16	52078
k_DMDRELAXECPKSigValidThresh_Cnt_u16	37987
k_DMDRelaxeConsistentThresh_Cnt_u16	15817
k_DateValidThresh_Cnt_u16	25050
k_DefaultVehSpd_Kph_f32	149.790298
k_DiagMuxOnAbsentTimeout_mS_u16	36962
k_EMNodeTimeout_mS_u16	20593
k_ESPNTCEnableTimeout_mS_u16	13820
k_ESPNodeAbsentDiag_Cnt_str.Threshold	0
k_ESPNodeAbsentDiag_Cnt_str.PStep	0
k_ESPNodeAbsentDiag_Cnt_str.NStep	0
k_ESPNodeAbsentTimeout_mS_u16	25538
k_EtatMTSigInvalidThresh_Cnt_u16	52444
k_EtatMTSigValidThresh_Cnt_u16	50097
k_ISDAT4V2BSI552MsgLenInvalidThresh_Cnt_u16	22383
k_ISDAT4V2BSI552MsgLenValidThresh_Cnt_u16	4072
k_ISDAT4V2BSI552MsgTimeValidThresh_Cnt_u16	35696
k_ISDATBSI3F2MsgLenInvalidThresh_Cnt_u16	932
k_ISDATBSI3F2MsgLenValidThresh_Cnt_u16	5125
k_ISDATBSI3F2MsgTimeValidThresh_Cnt_u16	31351
k_ISDATBSI412MsgLenInvalidThresh_Cnt_u16	53698
k_ISDATBSI412MsgLenValidThresh_Cnt_u16	24107

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
k_ISDATBSI412MsgTimeValidThresh_Cnt_u16	62801
k_ISDATBSI432MsgLenInvalidThresh_Cnt_u16	26032
k_ISDATBSI432MsgLenValidThresh_Cnt_u16	10785
k_ISDATBSI432MsgTimeValidThresh_Cnt_u16	39803
k_ISDATDIRASentDiag_Cnt_str.Threshold	41895
k_ISDATDIRASentDiag_Cnt_str.PStep	28944
k_ISDATDIRASentDiag_Cnt_str.NStep	50011
k_ISDATDIRASentTimeout_mS_u16	5377
k_ISDYN2CMMMsgLenInvalidThresh_Cnt_u16	31176
k_ISDYN2CMMMsgLenValidThresh_Cnt_u16	7131
k_ISDYN2CMMMsgTimeValidThresh_Cnt_u16	48840
k_ISDYNAASChkSumInvalidThresh_Cnt_u16	43589
k_ISDYNAASChkSumValidThresh_Cnt_u16	3546
k_ISDYNAASMsgCountInvalidThresh_Cnt_u16	59287
k_ISDYNAASMsgCountValidThresh_Cnt_u16	55940
k_ISDYNAASMsgLenInvalidThresh_Cnt_u16	62601
k_ISDYNAASMsgLenValidThresh_Cnt_u16	53178
k_ISDYNAASMsgTimeValidThresh_Cnt_u16	35369
k_ISDYNABRChkSumInvalidThresh_Cnt_u16	7817
k_ISDYNABRChkSumValidThresh_Cnt_u16	28326
k_ISDYNABRMsgCountInvalidThresh_Cnt_u16	6750
k_ISDYNABRMsgCountValidThresh_Cnt_u16	3371
k_ISDYNABRMsgLenInvalidThresh_Cnt_u16	8137
k_ISDYNABRMsgLenValidThresh_Cnt_u16	62322
k_ISDYNABRMsgTimeValidThresh_Cnt_u16	7202
k_ISDYNCMM208MsgLenInvalidThresh_Cnt_u16	3029
k_ISDYNCMM208MsgLenValidThresh_Cnt_u16	30660
k_ISDYNCMM208MsgTimeValidThresh_Cnt_u16	58093
k_ISDYNCMM388MsgLenInvalidThresh_Cnt_u16	11823
k_ISDYNCMM388MsgLenValidThresh_Cnt_u16	3004
k_ISDYNCMM388MsgTimeValidThresh_Cnt_u16	24443
k_ISDYNVOLChkSumInvalidThresh_Cnt_u16	6494
k_ISDYNVOLChkSumValidThresh_Cnt_u16	36079
k_ISDYNVOLMsgCountInvalidThresh_Cnt_u16	23687
k_ISDYNVOLMsgCountValidThresh_Cnt_u16	17182
k_ISDYNVOLMsgLenInvalidThresh_Cnt_u16	59484
k_ISDYNVOLMsgLenValidThresh_Cnt_u16	49141
k_ISDYNVOLMsgTimeValidThresh_Cnt_u16	2096
k_IgnOnTimeout_mS_u16	58138
k_JDD2010Selected_Cnt_lgc	0
k_PowerCutVehSpdHighThresh_Kph_f32	143.261505
k_PowerCutVehSpdLowThresh_Kph_f32	136.894302
k_PowerCutVehSpdLowTimeout_mS_u16	10271
k_VBattMaxAAS_Volt_f32	1.3721
k_VBattMaxBSI_Volt_f32	3.1171
k_VBattMaxCAV_Volt_f32	4.64769983
k_VBattMaxCMM388_Volt_f32	3.0532999
k_VBattMaxCMM_Volt_f32	13.3458996
k_VBattMaxESP_Volt_f32	3.23939991
k_VBattMinAAS_Volt_f32	31.3451996
k_VBattMinBSI_Volt_f32	3.23939991
k_VBattMinCAV_Volt_f32	23.9881001
k_VBattMinCMM388_Volt_f32	0.217800006
k_VBattMinCMM_Volt_f32	30.9360008
k_VBattMinESP_Volt_f32	13.3458996
k_VITESSEROTVOLANTSigInvalidThresh_Cnt_u16	56674
k_VITESSEROTVOLANTSigValidThresh_Cnt_u16	47011
k_VitesseVehicleBVRampValidThresh_Cnt_u16	32285
k_VitesseVehicleBVSigInvalidThresh_Cnt_u16	47159
k_VitesseVehicleBVSigValidThresh_Cnt_u16	9192
k_VitesseVehicleBVSpeedPassThresh_kph_f32	11.4502001
k_VitesseVehiculeRouesSigInvalidThresh_Cnt_u16	42816
k_VitesseVehiculeRouesSigValidThresh_Cnt_u16	46437
target_Pim_ElecIntData	0
target_Pim_ShutdownTimeData.Time_Sec_u32	2311053312
target_Pim_ShutdownTimeData.Valid_Cnt_lgc	1
target_Pim_VVHTYPEData	0
target_Rte_Call_Ap_SrlComInput_EpsEn_OP_GET_signal	0
target_Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16_Elaps	14237
target_Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32_Current1	3251510528
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APAAuthn_Cnt_lgc	target_SrlComInput_Per1_APAAuthn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_APARequest_Cnt_lgc	target_SrlComInput_Per1_APARequest_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AngleVolant_HwDeg_f32	target_SrlComInput_Per1_AngleVolant_HwDeg_f32

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_AnneeEcoule_Cnt_u08	target_SrlComInput_Per1_AnneeEcoule_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ApaRelaxReq_Cnt_lgc	target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BSIDataMissing_Cnt_lgc	target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_Batt_Volt_f32	target_SrlComInput_Per1_Batt_Volt_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_BusOff_Cnt_lgc	target_SrlComInput_Per1_BusOff_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CAVHCSelected_Cnt_lgc	target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CMMDataMissing_Cnt_lgc	target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CONSANGLECPK_Cnt_u16	target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CPKOK_Cnt_lgc	target_SrlComInput_Per1_CPKOK_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CTermActive_Cnt_lgc	target_SrlComInput_Per1_CTermActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CityParkSelected_Cnt_lgc	target_SrlComInput_Per1_CityParkSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_CompteurTemporelVehicule_C	target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ComputerRazGCT_Cnt_u08	target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DMDFCTCPK_Cnt_u08	target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DefaultVehSpd_Cnt_lgc	target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagIntegraElec_Cnt_u08	target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagMuxOn_Cnt_u08	target_SrlComInput_Per1_DiagMuxOn_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lg	target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_DmdDelestDA_Cnt_u08	target_SrlComInput_Per1_DmdDelestDA_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EffacDefaultDiag_Cnt_u08	target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ElectronicIntegration_Cnt_lgc	target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EngOn_Cnt_lgc	target_SrlComInput_Per1_EngOn_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_EtatMT_Cnt_u08	target_SrlComInput_Per1_EtatMT_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_HandwheelAuthority_Uls_f32	target_SrlComInput_Per1_HandwheelAuthority_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgDLCErr	target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_	target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI412MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgDLCError_C	target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATBSI432MsgRxTime_MS	target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxInProgress_	target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec	target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgDLCError_C	target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYN2CMMMsgRxTime_MS	target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNAASMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNABRMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgDLCError	target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM208MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgDLCError_	target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNCMM388MsgRxTime_M	target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_	target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec	target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08	target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ISINTEELECTRONBSIMsgRx	target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_IgnTimeOff_Cnt_u32	target_SrlComInput_Per1_IgnTimeOff_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_JourEcoule_Cnt_u16	target_SrlComInput_Per1_JourEcoule_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_LXASelected_Cnt_lgc	target_SrlComInput_Per1_LXASelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_MarcheARBVM_Cnt_u08	target_SrlComInput_Per1_MarcheARBVM_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ModeDiag_Cnt_u08	target_SrlComInput_Per1_ModeDiag_Cnt_u08
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_OutputRampMult_Uls_f32	target_SrlComInput_Per1_OutputRampMult_Uls_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32	target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ReverseGearEngaged_Cnt_lg	target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lg	target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_STTdSelected_Cnt_lgc	target_SrlComInput_Per1_STTdSelected_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SecondeEcoulee_Cnt_u32	target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SerialComAngleValid_Cnt_lgc	target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc	target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_SrlComVehSpd_Kph_f32	target_SrlComInput_Per1_SrlComVehSpd_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_ValidEngineStatus_Cnt_lgc	target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehTimeValid_Cnt_lgc	target_SrlComInput_Per1_VehTimeValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc	target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VehicleSpeed_Kph_f32	target_SrlComInput_Per1_VehicleSpeed_Kph_f32
target_Rte_Inst_Ap_SrlComInput.SrlComInput_Per1_VitesseVehicleBV_Cnt_u16	target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16
target_Rte_Inst_Ap_SrlComInput.Pim_ElecIntData	target_Pim_ElecIntData
target_Rte_Inst_Ap_SrlComInput.Pim_ShutdownTimeData	target_Pim_ShutdownTimeData
target_Rte_Inst_Ap_SrlComInput.Pim_VVHTYPEData	target_Pim_VVHTYPEData
target_SrlComInput_Per1_AnneeEcoule_Cnt_u08.value	119

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Input Value
target_SrlComInput_Per1_Batt_Volt_f32.value	12.0367002
target_SrlComInput_Per1_BusOff_Cnt_lgc.value	0
target_SrlComInput_Per1_CAVHCSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CTermActive_Cnt_lgc.value	1
target_SrlComInput_Per1_CityParkSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_CompteurTemporelVehicule_Cnt_u32.value	2646560768
target_SrlComInput_Per1_ComputerRazGCT_Cnt_u08.value	46
target_SrlComInput_Per1_DefaultVehSpd_Cnt_lgc.value	1
target_SrlComInput_Per1_DiagIntegraElec_Cnt_u08.value	0
target_SrlComInput_Per1_DiagMuxOn_Cnt_u08.value	1
target_SrlComInput_Per1_DiagRmpToZeroActive_Cnt_lgc.value	0
target_SrlComInput_Per1_DmdDelestDA_Cnt_u08.value	1
target_SrlComInput_Per1_EffacDefaultDiag_Cnt_u08.value	0
target_SrlComInput_Per1_EtatMT_Cnt_u08.value	5
target_SrlComInput_Per1_HandwheelAuthority_Uls_f32.value	0.975692391
target_SrlComInput_Per1_ISDAT4V2BSI552MsgDLCError_Cnt_u08.value	87
target_SrlComInput_Per1_ISDAT4V2BSI552MsgRxTime_MSec_u32.value	4111532032
target_SrlComInput_Per1_ISDATBSI3F2MsgDLCError_Cnt_u08.value	69
target_SrlComInput_Per1_ISDATBSI3F2MsgRxTime_MSec_u32.value	1375412224
target_SrlComInput_Per1_ISDATBSI412MsgDLCError_Cnt_u08.value	99
target_SrlComInput_Per1_ISDATBSI412MsgRxTime_MSec_u32.value	37044224
target_SrlComInput_Per1_ISDATBSI432MsgDLCError_Cnt_u08.value	248
target_SrlComInput_Per1_ISDATBSI432MsgRxTime_MSec_u32.value	1304387584
target_SrlComInput_Per1_ISDATDIRAMsgTxInProgress_Cnt_lgc.value	0
target_SrlComInput_Per1_ISDATDIRAMsgTxTime_MSec_u32.value	2090434560
target_SrlComInput_Per1_ISDYN2CMMMsgDLCError_Cnt_u08.value	167
target_SrlComInput_Per1_ISDYN2CMMMsgRxTime_MSec_u32.value	3603144704
target_SrlComInput_Per1_ISDYNAASMsgDLCError_Cnt_u08.value	82
target_SrlComInput_Per1_ISDYNAASMsgRxTime_MSec_u32.value	2755510272
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[0]	1
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[1]	12
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[2]	71
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[3]	80
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[4]	98
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[5]	112
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[6]	194
target_SrlComInput_Per1_ISDYNAASMsg_Cnt_u08.value[7]	232
target_SrlComInput_Per1_ISDYNABRMsgDLCError_Cnt_u08.value	123
target_SrlComInput_Per1_ISDYNABRMsgRxTime_MSec_u32.value	4268777472
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[0]	27
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[1]	37
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[2]	54
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[3]	56
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[4]	94
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[5]	198
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[6]	213
target_SrlComInput_Per1_ISDYNABRMsg_Cnt_u08.value[7]	230
target_SrlComInput_Per1_ISDYNCMM208MsgDLCError_Cnt_u08.value	218
target_SrlComInput_Per1_ISDYNCMM208MsgRxTime_MSec_u32.value	4024696832
target_SrlComInput_Per1_ISDYNCMM388MsgDLCError_Cnt_u08.value	104
target_SrlComInput_Per1_ISDYNCMM388MsgRxTime_MSec_u32.value	1280188416
target_SrlComInput_Per1_ISDYNVOLMsgDLCError_Cnt_u08.value	229
target_SrlComInput_Per1_ISDYNVOLMsgRxTime_MSec_u32.value	3154657280
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[0]	37
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[1]	39
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[2]	49
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[3]	67
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[4]	80
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[5]	116
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[6]	162
target_SrlComInput_Per1_ISDYNVOLMsg_Cnt_u08.value[7]	201
target_SrlComInput_Per1_ISINTEELECTRONBSIMsgRxTime_MSec_u32.value	1979895808
target_SrlComInput_Per1_JourEcoule_Cnt_u16.value	1152
target_SrlComInput_Per1_LXASelected_Cnt_lgc.value	1
target_SrlComInput_Per1_MarcheARBVM_Cnt_u08.value	0
target_SrlComInput_Per1_ModeDiag_Cnt_u08.value	1
target_SrlComInput_Per1_OutputRampMult_Uls_f32.value	0.962102652
target_SrlComInput_Per1_RxMsgsSrlComSvcDft_Cnt_lgc.value	0
target_SrlComInput_Per1_STTdSelected_Cnt_lgc.value	1
target_SrlComInput_Per1_SecondeEcoulee_Cnt_u32.value	870893
target_SrlComInput_Per1_SrlComHwTrqValid_Cnt_lgc.value	0
target_SrlComInput_Per1_VehicleSpeed_Kph_f32.value	132.063507
target_SrlComInput_Per1_VitesseVehicleBV_Cnt_u16.value	27563

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
AASNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
AASNTCsEnabled_Cnt_M_lgc	0	0	✔
AASNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
AASNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
ANGLEVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
ANGLEVOLANTSigValidCount_Cnt_M_u16	0	0	✔
APARequest_Cnt_M_lgc	0	0	✔
AngleVolantInvalidCount_Cnt_M_u16	7133	7133	✔
AngleVolantMsgTimer_mS_M_u32	3251510528	3251510528	✔
AngleVolantValidCount_Cnt_M_u16	0	0	✔
AngleVolantValid_Cnt_M_lgc	1	1	✔
AngleVolant_HwDeg_M_f32	0	0	✔
ApaRelaxReq_Cnt_M_lgc	1	1	✔
BSI3F2NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI3F2NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI412NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI412NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI432NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI432NTCsEnabled_Cnt_M_lgc	0	0	✔
BSI552NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
BSI552NTCsEnabled_Cnt_M_lgc	0	0	✔
BSINodeAbsentFltAcc_Cnt_M_u16	61209	61209	✔
BSINodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
BattOk_Cnt_M_lgc	0	0	✔
CAVNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CAVNTCsEnabled_Cnt_M_lgc	0	0	✔
CAVNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CAVNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CDD_SrlComVehSpd_Kph_G_f32	0	0	✔
CMM388NTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMM388NTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
CMMNTCsEnabled_Cnt_M_lgc	0	0	✔
CMMNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
CMMNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
CONSANGLECPKSigInvalidCount_Cnt_M_u16	0	0	✔
CONSANGLECPKSigValidCount_Cnt_M_u16	0	0	✔
CONSANGLECPK_Cnt_M_u16	18700	18700	✔
CONSANGLECPK_HwDeg_M_f32	316.518188	316.518188 ± 0.0125	✔
CPKOK_Cnt_M_lgc	0	0	✔
CPKVehicleSpeedInvalidCount_Cnt_M_u16	18700	18700	✔
CPKVehicleSpeedMsgTimer_mS_M_u32	3605737472	3605737472	✔
CPKVehicleSpeedValidCount_Cnt_M_u16	0	0	✔
CityParkInputConsistentCount_Cnt_M_u16	59167	59167	✔
CityParkInputInvalidCount_Cnt_M_u16	12037	12037	✔
CityParkInputMsgTimer_mS_M_u32	3251510528	3251510528	✔
CityParkInputValidCount_Cnt_M_u16	0	0	✔
ClearDTCs_Cnt_M_lgc	0	0	✔
CompteurTemporelVehiculeSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
CompteurTemporelVehiculeSigValidCount_Cnt_M_u16	0	0	✔
ComputerRazGCTSigInvalidTimer_mS_M_u32	3251510528	3251510528	✔
ComputerRazGCTSigValidCount_Cnt_M_u16	0	0	✔
CountEtatMT_Cnt_M_u08	0	0	✔
DMDFCTCPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDFCTCPKSigValidCount_Cnt_M_u16	0	0	✔
DMDFCTCPK_Cnt_M_u08	0	0	✔
DMDRELAXECPKSigInvalidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPKSigValidCount_Cnt_M_u16	0	0	✔
DMDRELAXECPK_Cnt_M_u08	0	0	✔
DMDRelaxeConsistentCount_Cnt_M_u16	0	0	✔
DateInvalidTimer_mS_M_u32	3251510528	3251510528	✔
DateValidCount_Cnt_M_u16	0	0	✔
DiagMuxOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
DiagOn_Cnt_M_lgc	0	0	✔
DmdDelestDATimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCEnableTimer_mS_M_u32	3251510528	3251510528	✔
ESPNTCsEnabled_Cnt_M_lgc	0	0	✔
ESPNodeAbsentFltAcc_Cnt_M_u16	0	0	✔
ESPNodeAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EffacDefaultDiagCount_Cnt_M_u08	0	0	✔
EffacDefaultDiagTimer_mS_M_u32[0]	6	6	✔
EffacDefaultDiagTimer_mS_M_u32[1]	16	16	✔
ElecIntCount_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
ElecIntTimer_mS_M_u32[0]	3251510528	3251510528	✔
ElecIntTimer_mS_M_u32[1]	1002	1002	✔
ElectronicIntegrationCmd_Cnt_M_lgc	1	1	✔
EngOnAbsentTimer_mS_M_u32	3251510528	3251510528	✔
EngOnDLCInvalidCount_Cnt_M_u08	1	1	✔
EngOn_Cnt_M_lgc	0	0	✔
EtatMTSigInvalidCount_Cnt_M_u16	0	0	✔
EtatMTSigValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDAT4V2BSI552MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI3F2MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI3F2MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI412MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI412MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATBSI432MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDATBSI432MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDATDIRASentFltAcc_Cnt_M_u16	0	0	✔
ISDATDIRASentTimer_mS_M_u32	3251510528	3251510528	✔
ISDYN2CMMMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYN2CMMMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNAASChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgCount_Cnt_M_u08	10	10	✔
ISDYNAASMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNAASMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNABRChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgCount_Cnt_M_u08	12	12	✔
ISDYNABRMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNABRMsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM208MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM208MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNCMM388MsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNCMM388MsgTimer_mS_M_u32	3251510528	3251510528	✔
ISDYNVOLChkSumInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLChkSumValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCountValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgCount_Cnt_M_u08	13	13	✔
ISDYNVOLMsgLenInvalidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgLenValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimeValidCount_Cnt_M_u16	0	0	✔
ISDYNVOLMsgTimer_mS_M_u32	3251510528	3251510528	✔
IgnOnTimer_mS_M_u32	3251510528	3251510528	✔
IgnTimeOff_Sec_M_u32	2182505990	2182505990	✔
Msg348Valid_Cnt_M_lgc	0	0	✔
Msg432Valid_Cnt_M_lgc	0	0	✔
Msg552Valid_Cnt_M_lgc	0	0	✔
NetOn_Cnt_M_lgc	0	0	✔
PrevDMDFCTCPK_Cnt_M_u08	2	2	✔
PrevDMDRELAXECPK_Cnt_M_u08	1	1	✔

TEST DETAILS REPORT

SrlComInput_Per1

2016-09-20, 18:12:56+0530

Name	Actual Value	Expected Value	Result
PrevDiagIntegraElec_Cnt_M_u08	0	0	✔
PrevEtatMT_Cnt_M_u08	5	5	✔
PrevISDAT4V2BSI552MsgDLCError_Cnt_M_u08	87	87	✔
PrevISDAT4V2BSI552MsgRxTime_MSec_M_u32	4111532032	4111532032	✔
PrevISDATBSI3F2MsgDLCError_Cnt_M_u08	69	69	✔
PrevISDATBSI3F2MsgRxTime_MSec_M_u32	1375412224	1375412224	✔
PrevISDATBSI412MsgDLCError_Cnt_M_u08	99	99	✔
PrevISDATBSI412MsgRxTime_MSec_M_u32	37044224	37044224	✔
PrevISDATBSI432MsgDLCError_Cnt_M_u08	248	248	✔
PrevISDATBSI432MsgRxTime_MSec_M_u32	1304387584	1304387584	✔
PrevISDATDIRAMsgTxTime_MSec_M_u32	2184331264	2184331264	✔
PrevISDYN2CMMMsgDLCError_Cnt_M_u08	167	167	✔
PrevISDYN2CMMMsgRxTime_MSec_M_u32	3603144704	3603144704	✔
PrevISDYNAASMsgDLCError_Cnt_M_u08	82	82	✔
PrevISDYNAASMsgRxTime_MSec_M_u32	2755510272	2755510272	✔
PrevISDYNABRMsgDLCError_Cnt_M_u08	123	123	✔
PrevISDYNABRMsgRxTime_MSec_M_u32	4268777472	4268777472	✔
PrevISDYNCMM208MsgDLCError_Cnt_M_u08	218	218	✔
PrevISDYNCMM208MsgRxTime_MSec_M_u32	4024696832	4024696832	✔
PrevISDYNCMM388MsgDLCError_Cnt_M_u08	104	104	✔
PrevISDYNCMM388MsgRxTime_MSec_M_u32	1280188416	1280188416	✔
PrevISDYNVOLMsgDLCError_Cnt_M_u08	229	229	✔
PrevISDYNVOLMsgRxTime_MSec_M_u32	3154657280	3154657280	✔
PrevISINTEELECTRONBSIMsgRxTime_MSec_M_u32	1979895808	1979895808	✔
PrevModeDiag_Cnt_M_u08	1	1	✔
PrevSrlComVehSpd_Kph_M_f32	153.812195	153.812195	✔
PrevVitesseVehicleBVValid_Cnt_M_lgc	0	0	✔
ResetTimers_Cnt_M_lgc	0	0	✔
StartupTimeCalculated_Cnt_M_lgc	1	1	✔
VITESSEROTVOLANTSigInvalidCount_Cnt_M_u16	0	0	✔
VITESSEROTVOLANTSigValidCount_Cnt_M_u16	0	0	✔
VVHTYPE1Count_Cnt_M_u08	2	2	✔
VVHTYPE2Count_Cnt_M_u08	10	10	✔
ValidEngineStatusCount_Cnt_M_u08	1	1	✔
VehSpdSync_Cnt_M_lgc	0	0	✔
VehTimeValid_Cnt_M_lgc	0	0	✔
VehicleSpeedValid_Cnt_M_lgc	1	1	✔
VitesseVehicleBVRampInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVRampValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBVSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehicleBV_Kph_M_f32	154.650894	154.650894	✔
VitesseVehiculeRouesSigInvalidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRouesSigValidCount_Cnt_M_u16	0	0	✔
VitesseVehiculeRoues_Kph_M_f32	543.46521	543.46521	✔
target_SrlComInput_Per1_APAAuthn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_APARequest_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_AngleVolant_HwDeg_f32.value	0	0	✔
target_SrlComInput_Per1_ApaRelaxReq_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_BSIDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CMMDataMissing_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_CONSANGLECPK_Cnt_u16.value	18700	18700	✔
target_SrlComInput_Per1_CPKOK_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_DMDFCTCPK_Cnt_u08.value	0	0	✔
target_SrlComInput_Per1_ElectronicIntegration_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_EngOn_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_IgnTimeOff_Cnt_u32.value	2182505990	2182505990	✔
target_SrlComInput_Per1_PosSrvoHwAngle_HwDeg_f32.value	316.518188	316.518188 ± 0.0125	✔
target_SrlComInput_Per1_ReverseGearEngaged_Cnt_lgc.value	1	1	✔
target_SrlComInput_Per1_SerialComAngleValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_SrlComVehSpd_Kph_f32.value	0	0	✔
target_SrlComInput_Per1_ValidEngineStatus_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehTimeValid_Cnt_lgc.value	0	0	✔
target_SrlComInput_Per1_VehicleSpeedValid_Cnt_lgc.value	1	1	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	Rte_Mode_Ap_SrlComInput_SystemState_Mode	1	✔
Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	Rte_Call_Ap_SrlComInput_EpsEn_OP_GET	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComInput_SystemTime_GetSystemTime_mS_u32	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
ResetFltAcc	1	ResetFltAcc	1	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
NtWrapC_Dem_ClearDTC	1	NtWrapC_Dem_ClearDTC	1	✔
Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	Rte_Call_Ap_SrlComInput_SystemTime_DtrmnElapsedTime_mS_u16	6	✔
Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	Rte_Call_Ap_SrlComInput_NxtrDiagMgr_GetNTCFailed	22	✔